

# Levee and Floodwall Observation Sheet

**Report location of Incident (GPS location preferred, levee station is a second choice)**

Limit a single observation record to conditions that are uniform along the levee or floodwall.

Location (parish, area) in which incident is occurring: Orleans Parish, East Bank Lakefront, Map ID L51

**A. Type of Structure:** Levee X, Levee with I-Wall (capped) \_\_\_\_, Levee with T-Wall \_\_\_\_,  
Levee with Sheetpile (uncapped) \_\_\_\_, Other: \_\_

**B. GPS Coordinates**

Location of observation using GPS unit:

Start of problem: N 90° 05' 7.9" W 030° 01' 35.6"

End of problem:

Length of damage: 20'

**C. Photo Numbers:** PHOTO ATTACHED

**D. Report Category of Severity of Scour Damage**

*Select one*

- 
- 
- 

Class	Descriptor	Description of Scour
I	Light	Scour from crown 2 feet down slope
II	Heavy	Scour from crown to ground surface
III	Breach	Scour below ground surface

Comments: Scour – width: 3 ft and depth: 1 ft.

**E. Condition of Floodwall:** I-Wall \_\_\_\_ T-Wall \_\_ Sheetpile Wall (uncapped) \_\_

**Other:** \_\_ - (select most appropriate category)

*Select one*

- 
- 
- 
- 

Description
Rotated I-wall
Scour adjacent to wall
Breached wall
Other: _____

Comments: \_

**F. Date and Time of Observation** Date: \_\_ Time: \_\_\_\_\_

**G. Name of person making observation:**

**H. Sketches/Diagrams**

