

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification: Machinery		3. Date/Time of Accident: 01/21/2013 11:50 AM		4. Date/Time of Death: 01/21/2013 03:05 PM		5. Fatal Case No: 2					
6. Mine Information :													
a) Mining Company Name: Lhoist North America of Arizona Inc.			b) Mine Name: Apex Quarry and Plant			c) Parent of Mining Company: Lhoist Group							
7. Mine Location :		a) City: N Las Vegas		b) County: Clark		c) State: NV		8. Mine ID Number: 26-00081		9. Union: NO			
10. Primary Mineral Mined: LIME, N.E.C.			11. Number of Mine Employees:		a) Total: 128	b) Underground: 0	c) Open Pit/Quarry: 64		d) Mill/Prep Plant: 34	e) Other: 30			
12. Contractor Name:						13. Union:		14. Contractor ID Number:					
15. Contractor Address:													
a) City:		b) County:			c) State:			d) Zip Code:					
16. Number of Contractor Employees:													
a) Total:		b) Underground:		c) Open Pit/Quarry:		d) Mill/Prep Plant:		e) Other:					
17. Number of Persons in Mine at Time of Accident:						18. Number of Persons Unaccounted For:							
a) Mine Employees: 47		b) Contractor Employees: 0				a) Mine Employees: 0		b) Contractor Employees: 0					
19) Location of Accident									20. Mining Height:				
<input type="checkbox"/> 01-Underground	<input type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input checked="" type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		Feet Inches				
<input type="checkbox"/> 02-Surface at Underground	<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility								
21. Nonfatal Injuries: 0		22. Fatal Injuries: 1											
23. Victim Information :													
a) Name: Kenneth Korakis				b) Age: 54									
c) Regular Job Title: Mechanic				d) Activity at Time of Accident: Maintenance				<input checked="" type="checkbox"/> Mine Employee					
24. Experience :													
Years Weeks Days			Years Weeks Days			Years Weeks Days			Years Weeks Days				
a) Total:		6 7 4		b) at the mine:		6 7 4		c) at activity (23d):		6 7 4		d) with Contractor:	
25. Autopsy Performed: If Yes, Location YES Clark County, NV						26. Mine Telephone No.: (702) 643-7702							

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The victim went to the Kiln #2 pre-heat deck to repair a leaking hydraulic cylinder that activates the pusher arm on the southeast side of the kiln. He was found under the cylinder.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer:				29. Model:					
30. District: M7000 Western		32. Field Office: Henderson NV				33. Event Number: 1137960			
34. Accident Investigator: Jerry D. Hulsey				35. MSHA Person Notified: Bart T. Wrobel		Date: 01/21/2013		Time: 12:30 P	
36. Type of Report: Amended		37. Name of Preparer and Date Prepared: Mike Hancher <i>MH</i>				Date: 01/22/2013			
38. Reason For Amendment: Items: 24 a, b, c									