

The Metal-Nonmetal Monitor

2008 Fatal Accidents



As of - Friday, May 22, 2009

No	Acc Date	St	Contractor	Class	Mine Type	Mine Status	Mineral	Equip or Location	Occupation	Employees	Age	Mining Exp (yr . mo)	Job Exp (yr . mo)	PPE Involved	Training Rec'd
1	1/21/2008	CA	Yes	Fall of Person	ML	F	Cement	Bulk Truck Driver	Bulk Truck Driver	205	58	3.7	1.11	Yes	Yes
2	1/25/2008	MO	No	Handling Material	ML	F	Lime	Shoveling	Mechanic	38	36	1.11	0.3	No	Yes
3	1/26/2008	NV	No	Powered Haulage	UG	F	Gold	Walking	Equipment Operator	40	43	8.4	2.4	No	Yes
4	1/23/2008	KS	No	Other	DR	I	Sand & Gravel	Maintenance	Dredge Operator/Pumper	2	64	24	24	Yes	Yes
5	2/25/2008	WI	Yes	Machinery	QU	I	Sand & Gravel	Operating Excavator	Manager	6	62	28	28	No	Yes
6	4/21/2008	NV	No	Fall of Back	UG	F	Gold	Repairing Bolter	Mechanic	36	28	1.11	1.11	No	Yes
7	4/24/2008	IA	No	Powered Haulage	UG	F	Industrial Sand	Checking Roof	Laborer	70	48	0.7	0.7	No	Yes
8	5/3/2008	KY	No	Machinery	QU	F	Sand & Gravel	Operating Excavator	Co-owner	9	51	0.1	0.1	No	No
9	5/22/2008	TX	No	Fall of Person	QU	F	Crushed Stone	Feeding Crusher	Equipment Operator	10	46	0.2	0.2	No	Yes
10	5/27/2008	CA	No	Powered Haulage	QU	F	Crushed Stone	Driving Haul Truck	Truck Driver	47	52	1.11	1.11	Yes	Yes
11	5/31/2008	NY	No	Fall of Back	UG	F	Lead-Zinc	Drilling at Face	Driller	223	40	2	2	No	Yes
12	8/6/2008	NM	No	Electrical	UG	F	Potash	Open/Close Valve	Shift Foreman	306	38	15	15	No	Yes
13	8/15/2008	AZ	No	Electrical	QU	F	Copper	Check Light Ballast	Electrician Apprentice	790	41	14	1.3	No	Yes
14	8/18/2008	PA	Yes	Machinery	UG	F	Crushed Stone	Place Counterweight	Mechanic/Welder	47	28	8.2	6.2	No	Yes
15	9/1/2008	AZ	Yes	Fall of Person	QU	F	Copper	Splicing Belt	Consultant	3500	67	46	46	Yes	Yes
16	10/1/2008	TX	No	Powered Haulage	DR	F	Sand & Gravel	Driving Vehicle	Loader Operator	12	38	3	0.8	No	Yes
17	10/7/2008	PA	No	Falling Material	QU	F	Crushed Stone	Surge Tunnel	Lead Man	19	56	18.8	18.8	No	Yes
18	10/9/2008	NV	No	Falling Material	QU	F	Gold	Dismantling Rack	Welder	1294	56	21.2	18.4	No	Yes
19	10/11/2008	MO	No	Fall of Person	ML	F	Cement	Loading Barge	Cement Handler	152	67	3.3	3.3	Yes	Yes
20	10/17/2008	GA	No	Fall of Back	UG	F	Marble	Scaling Back	Scaler Operator	24	45	8.2	4.8	No	Yes
21	10/29/2008	UT	Yes	Falling Material	ML	F	Copper	Unloading Pipe	Delivery Truck Driver	355	81	55	55	No	Yes
22	11/17/2008	IA	No	Powered Haulage	UG	F	Crushed Stone	Repairing Gate Post	Mechanic	14	67	36	30	No	Yes
23	2/29/2008	TX	Yes	Fall of Person	QU	F	Crushed Stone	Walking Down Steps	Truck Driver	11	58	30	30	No	Yes

Mine Types: UG - Underground, OP - Open Pit, QU - Quarry, SG - Sand & Gravel, ML - Mill, DR - Dredge
 Mine Status: F - Full Time, I - Intermittent, N - Nonproducing, P - Closed

Red Block Indicates Link to Fatalgram with subsequent link to Fatal Investigation Report *ND - Not Determined as Fatal Investigation Report has not been completed.