


BMAR REPORT AND PROJECTS PLAN
MARINE CORPS BASE
CAMP LEJEUNE, NORTH CAROLINA
FY-79

FY 79

TYPE A ANNUAL INSPECTION SUMMARY
MARINE CORPS AIR STATION (HELICOPTER)
NEW RIVER, NORTH CAROLINA

Type A Annual Inspection Summary (Unfunded Facilities Deficiencies)


| 1. Activity Marine Corps Air Station (H) New River, North Carolina | 2. Current <input checked="" type="checkbox"/> Projected <input type="checkbox"/> | 3. Less Housing <input checked="" type="checkbox"/> Housing <input type="checkbox"/> | 4. For Period 30 Sep Ending FY 79 | | | 5. Sheet 2 of 7 | |
|--------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------|-----------------------------------------|-------------------|------------------------------|-----------------------|--|
| 6 | 7 | 8 | 9 | 10 | 11 | 12 | |
| Description | Category Code | Deficiency Code | Unfunded Cost | Validation Rating | Number of Previous Summaries | Line No. | |
| BACHELOR HOUSING MESS FACILITIES | | | | | | | |
| Structural, mechanical repairs, interior paint, AS-226 | 722 | 1 | \$ 169.0 | | 3 | 12 | |
| COMMUNITY FACILITIES - MORALE, WELFARE AND RECREATION, INTERIOR | | | | | | | |
| Structural, mechanical repairs, reroof, replace floor, AS-202 | 740 | 1 | 93.6 | | 7 | 13 | |
| Structural repairs, replace air conditioning, AS-208 | 740 | 1 | 45.0 | | 2 | 14 | |
| ROADS | | | | | | | |
| Resurface various roads | 851 | 1 | 60.2 | | 2 | 15 | |
| SIDEWALKS AND OTHER PAVEMENT | | | | | | | |
| Repair various parking areas | 852 | 1 | 260.3 | | 6 | 16 | |
| FENCES, GATES, GUARD TOWERS AND SHELTERS | | | | | | | |
| Replace security fence, MCOLF, Oak Grove | 872 | 1 | 120.2 | | 4 | 17 | |
| FIRE AND OTHER ALARM SYSTEMS | | | | | | | |
| Replace fire alarm system | 880 | 1 | 132.4 | | 4 | 18 | |
| Subtotal | | | \$2,697.6 | | | | |
| <u>MCAS(H) CODE II</u> | | | | | | | |
| AIRFIELD PAVEMENTS - OTHER | | | | | | | |
| Mechanical repairs AS-513 | 116 | 2 | 6.0 | | 0 | 19 | |



Type A Annual Inspection Summary (Unfunded Facilities Deficiencies)

| | | | | |
|--------------------------------------------------------------------------|--------------------------------------|---------------------------------------|-----------------------------------------|-----------------------|
| 1. Activity Marine Corps Air Station (H) New River, North Carolina | 2. Current - X Projected _____ | 3. Less Housing X Housing _____ | 4. For Period 30 Sep Ending FY 79 | 5. Sheet 1 of 7 |
|--------------------------------------------------------------------------|--------------------------------------|---------------------------------------|-----------------------------------------|-----------------------|

| 6 Description | 7 Category Code | 8 Deficiency Code | 9 Unfunded Cost | 10 Validation Rating | 11 Number of Previous Summaries | 12 Line No. |
|----------------------------------------------------------------------------------------------------------------|--------------------|----------------------|--------------------|-------------------------|------------------------------------|----------------|
| AIRFIELD PAVEMENTS - RUNWAYS Resurface runways and taxiways at MCOLF, Oak Grove | 111 | 1 | \$ 757.0 | | 9 | 1 |
| Repairs, resealing joints, and restriping of taxiway parking, MCAS(H), New River | 111 | 1 | 147.3 | | 0 | 2 |
| Resurface runways 18 - 36 MCAS(H), New River | 111 | 1 | 162.4 | | 0 | 3 |
| Correct substandard base course and subgrade taxiway "B", MCAS(H), New River | 111 | 1 | 50.0 | | 1 | 4 |
| Miscellaneous repairs, resurfacing, slurry seal and stripe taxiways, MCAS(H), New River | 111 | 1 | 109.1 | | 0 | 5 |
| OPERATING FUEL STORAGE Replace fuel tanks AS-526 and AS-527 | 124 | 1 | 80.0 | | 1 | 6 |
| MAINTENANCE AIRCRAFT - SPARES Replace roof, structural, mechanical repairs and interior paint hangar AS-504 | 211 | 1 | 242.0 | | 2 | 7 |
| Structural repairs, interior and exterior paint hangar AS-4100 | 211 | 1 | 68.0 | | 1 | 8 |
| Structural repairs, exterior paint AS-4106 | 211 | 1 | 42.3 | | 1 | 9 |
| Structural, mechanical repairs, interior paint AS-515 | 211 | 1 | 91.0 | | 1 | 10 |
| Replace roof, structural, mechanical repairs, exterior paint AS-518 | 211 | 1 | 67.8 | | 1 | 11 |




Type A Annual Inspection Summary (Unfunded Facilities Deficiencies)

| 1. Activity Marine Corps Air Station(H) New River, North Carolina | 2. Current - X Projected _____ | 3. Less Housing X Housing _____ | 4. For Period 30 Sep Ending FY 79 | | | 5. Sheet 3 of 7 | |
|---------------------------------------------------------------------------------------------------------------------|--------------------------------------|---------------------------------------|-----------------------------------------|------------------------------|------------------------------------|-----------------------|--|
| 6 Description | 7 Category Code | 8 Defi- ciency Code | 9 Unfunded Cost | 10 Vali- dation Rating | 11 Number of Previous Summaries | 12 Line No. | |
| AIRCRAFT FUELING/DISPENSING FACILITY Mechanical repairs AS-145 | 121 | 2 | \$ 1.6 | | 0 | 20 | |
| MARINE FUEL DISPENSING Electrical repairs, AS-2804 | 122 | 2 | .4 | | 0 | 21 | |
| LAND VEHICLE FUELING/DISPENSING FACILITIES Interior paint AS-143 | 123 | 2 | .6 | | 6 | 22 | |
| OPERATING FUEL STORAGE Structural repairs AS-141 | 124 | 2 | .4 | | 0 | 23 | |
| POL PIPELINE (TWO BUILDINGS) Interior and exterior paint AS-144 and AS-509 | 125 | 2 | .5 | | 6 | 24 | |
| COMMUNICATIONS BUILDINGS Roof replacement, interior paint AS-224 | 131 | 2 | 3.6 | | 4 | 25 | |
| NAVIGATION AND TRAFFIC AIDS BUILDINGS (THREE BUILDINGS) Structural repair, paint AS-805, AS-3000 and AS-3620 | 133 | 2 | 2.8 | | 5 | 26 | |
| OPERATIONAL BUILDINGS (THREE BUILDINGS) Structural, mechanical repairs and painting AS-502, AS-571 and AS-843 | 141 | 2 | 7.4 | | 6 | 27 | |
| Structural repairs, painting AS-816 | 143 | 2 | 7.6 | | 0 | 28 | |
| SMALL CRAFT BERTHING Structural repairs AS-846 | 155 | 2 | .9 | | 1 | 29 | |

Type A Annual Inspection Summary (Unfunded Facilities Deficiencies)

| | | | | | | |
|--------------------------------------------------------------------------|-----------------------------------|------------------------------------|--------------------------------------|--|--|--------------------|
| 1. Activity Marine Corps Air Station (H) New River, North Carolina | 2. Current - X Projected _____ | 3. Less Housing X Housing _____ | 4. For Period 30 Sep Ending FY 79 | | | 5. Sheet # of 7 |
|--------------------------------------------------------------------------|-----------------------------------|------------------------------------|--------------------------------------|--|--|--------------------|


| 6 Description | 7 Category Code | 8 Deficiency Code | 9 Unfunded Cost | 10 Validation Rating | 11 Number of Previous Summaries | 12 Line No. |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------|----------------------|--------------------|-------------------------|------------------------------------|----------------|
| MARINE IMPROVEMENTS Structural repairs AS-720 | 164 | 2 | \$.4 | | 1 | 30 |
| TRAINING BUILDINGS (FOUR BUILDINGS) Structural, electrical repairs, painting AS-222, AS-312, AS-3515 and AS-4120 | 171 | 2 | 4.8 | | 4 | 31 |
| TRAINING FACILITIES OTHER THAN BUILDINGS Structural repairs, AS-3617 | 179 | 2 | .3 | | 0 | 32 |
| MAINTENANCE AIRCRAFT SPARES (TWO BUILDINGS) Structural, electrical, mechanical repairs, painting AS-585 and AS-840 | 211 | 2 | 6.5 | | 6 | 33 |
| MAINTENANCE TANK - AUTOMOTIVE (ELEVEN BUILDINGS) Structural, mechanical, electrical repairs, painting, AS-112, AS-113, AS-114, AS-116, AS-117, AS-118, AS-119, AS-153, AS-150, AS-181 and AS-3504 | 214 | 2 | 38.4 | | 5 | 34 |
| MAINTENANCE - ELECTRONIC/COMMUNICATIONS EQUIPMENT Structural, mechanical repairs, painting AS-849 | 217 | 2 | 9.8 | | 7 | 35 |
| MAINTENANCE - PUBLIC WORKS REPAIR AND OPERATIONS (THREE BUILDINGS) Structural, mechanical repairs, painting AS-122, AS-124 and AS-522 | 219 | 2 | 16.1 | | 7 | 36 |
| RESEARCH, DEVELOPMENT, TEST, AND EVALUATION BUILDINGS Structural repairs, painting AS-580 | 310 | 2 | 1.0 | | 8 | 37 |



Type A Annual Inspection Summary (Unfunded Facilities Deficiencies)


| | | | | |
|----------------------------------------------------------------------|-----------------------------------------|-------------------------------------------|--------------------------------------|--------------------|
| 1. Activity Marine Corps Air Station New River, North Carolina | 2. Current <u>-X</u> Projected _____ | 3. Less Housing <u>X</u> Housing _____ | 4. For Period 30 Sep Ending FY 79 | 5. Sheet 5 of 7 |
|----------------------------------------------------------------------|-----------------------------------------|-------------------------------------------|--------------------------------------|--------------------|

| 6 Description | 7 Category Code | 8 Deficiency Code | 9 Unfunded Cost | 10 Validation Rating | 11 Number of Previous Summaries | 12 Line No. |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------|----------------------|--------------------|-------------------------|------------------------------------|----------------|
| GENERAL SUPPLY STORAGE/SUPPLY OPERATIONS BUILDINGS (TWENTY-THREE BUILDINGS) Structural, mechanical, electrical repairs, painting AS-12, AS-128, AS-130, AS-218, AS-416, AS-424, AS-581, AS-582, AS-583, AS-587, AS-588, AS-590, AS-593, AS-594, AS-595, AS-810, AS-812, AS-813, AS-815, AS-865, AS-873, AS-4110 and AS-4127 | 441 | 2 | \$ 48.5 | | 5 | 38 |
| DISPENSARIES Structural, electrical, mechanical repairs AS-302 | 550 | 2 | .9 | | 7 | 39 |
| ADMINISTRATIVE BUILDINGS (TWELVE BUILDINGS) Structural, electrical, mechanical repairs, painting AS-216, AS-217, AS-425, AS-586, AS-589, AS-804, AS-814, AS-818, AS-820, AS-822, AS-8502 and AS-4122 | 610 | 2 | 68.9 | | 6 | 40 |
| OTHER ADMINISTRATIVE FACILITIES (FOUR BUILDINGS) Structural repairs, painting AS-821, AS-829, AS-842 and AS-4123 | 690 | 2 | 1.0 | | 1 | 41 |
| TROOP HOUSING - BACHELOR EM BARRACKS (ELEVEN BUILDINGS) Structural, electrical, mechanical repairs, painting AS-211, AS-212, AS-213, AS-214, AS-215, AS-702, AS-704, AS-4010, AS-4015, AS-4020 and AS-4025 | 721 | 2 | 127.2 | | 5 | 42 |
| BACHELOR HOUSING - MESS FACILITIES Structural, electrical, mechanical repairs AS-4012 | 722 | 2 | 10.0 | | 4 | 43 |
| BACHELOR HOUSING -DETACHED FACILITIES (TWO BUILDINGS) Structural repairs AS-6040 and AS-6045 | 723 | 2 | .3 | | 1 | 44 |



Type A Annual Inspection Summary (Unfunded Facilities Deficiencies)

| 1. Activity Marine Corps Air Station(H) New River, North Carolina | 2. Current - <u>X</u> Projected _____ | 3. Less Housing <u>X</u> Housing _____ | 4. For Period 30 Sep Ending FY 79 | | | 5. Sheet 6 of 7 | |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------|----------------------------------------------|-----------------------------------------|-------------------|------------------------------|-----------------------|--|
| 6 | 7 | 8 | 9 | 10 | 11 | 12 | |
| Description | Category Code | Deficiency Code | Unfunded Cost | Validation Rating | Number of Previous Summaries | Line No. | |
| BACHELOR HOUSING - OFFICERS QUARTERS Structural repairs AS-710 | 724 | 2 | \$ 1.2 | | 3 | 45 | |
| COMMUNITY FACILITIES - PERSONNEL SUPPORT AND SERVICES (THREE BUILDINGS) Structural repairs, painting AS-133, AS-536 and AS-2860 | 730 | 2 | 1.0 | | 4 | 46 | |
| COMMUNITY FACILITIES - MORALE, WELFARE AND RECREATION - INTERIOR (SEVENTEEN BUILDINGS) Roof, structural, electrical, mechanical repairs, painting AS-205, AS-231, AS-232, AS-233, AS-234, AS-236, AS-240, AS-299, AS-410, AS-413, AS-414, AS-608, AS-708, AS-710, AS-832, AS-901 and AS-2800. | 740 | 2 | 61.9 | | 5 | 47 | |
| COMMUNITY FACILITIES - MORALE, WELFARE, AND RECREATIONAL - EXTERIOR (SEVEN BUILDINGS) Structural, electrical repairs, painting AS-207, AS-246, AS-252, AS-254, AS700, AS-2803 and AS-2850 | 750 | 2 | 29.4 | | 5 | 48 | |
| ELECTRIC POWER - TRANSMISSION AND DISTRIBUTION LINES (STRUCTURES) (SIX BUILDINGS) Roof, structural repairs, painting AS-101, AS-227, AS-311, AS-819, AS-841 and AS-3605 | 812 | 2 | 1.8 | | 3 | 49 | |
| HEAT - SOURCE (TWO BUILDINGS) Roof, structural repairs, painting AS-703 and AS-833 | 821 | 2 | 9.4 | | 5 | 50 | |
| REFRIGERATION/AIR CONDITIONING Structural, mechanical repairs AS-225 | 826 | 2 | 2.3 | | 0 | 51 | |




Type A Annual Inspection Summary (Unfunded Facilities Deficiencies)


| | | | | |
|--------------------------------------------------------------------------|----------------------------------------------------|-------------------------------------------------------|--------------------------------------|--------------------|
| 1. Activity Marine Corps Air Station (H) New River, North Carolina | 2. Current <u> X </u> Projected <u> </u> | 3. Less Housing <u> X </u> Housing <u> </u> | 4. For Period 30 Sep Ending FY 79 | 5. Sheet 7 of 7 |
|--------------------------------------------------------------------------|----------------------------------------------------|-------------------------------------------------------|--------------------------------------|--------------------|

| | | | | | | |
|-------------|---------------|-----------------|---------------|-------------------|------------------------------|----------|
| 6 | 7 | 8 | 9 | 10 | 11 | 12 |
| Description | Category Code | Deficiency Code | Unfunded Cost | Validation Rating | Number of Previous Summaries | Line No. |

| | | | | | | |
|------------------------------------------------------------------------------------------------------------------------------------------|-----|---|----------|--|---|----|
| SEWAGE AND INDUSTRIAL WASTE COLLECTION Structural repairs, painting AS-850 | 832 | 2 | \$ 1.1 | | 6 | 52 |
| REFUSE/GARBAGE Roof, structural repairs, painting AS-209 | 833 | 2 | .4 | | 1 | 53 |
| POTABLE WATER SUPPLY TREATMENT AND STORAGE (FOUR BUILDINGS) Structural repairs, roof, painting AS-203, AS-1002, AS-3506 and AS-650 | 841 | 2 | 2.1 | | 3 | 54 |
| WATER DISTRIBUTION SYSTEM POTABLE (FOUR BUILDINGS) Structural repairs, painting AS-506, AS-514, AS-4102 and AS-4105 | 842 | 2 | 1.5 | | 4 | 55 |
| Code II Total | | | \$ 478.0 | | | |



TYPE A ANNUAL INSPECTION SUMMARY
MARINE CORPS BASE
CAMP LEJEUNE, NORTH CAROLINA



Type A Annual Inspection Summary (Unfunded Facilities Deficiencies)

| 1. Activity Marine Corps Base Camp Lejeune, North Carolina | 2. Current <u>- X</u> Projected <u> </u> | 3. Less Housing <u>X</u> Housing <u> </u> | 4. For Period 30 Sept Ending FY 79 | | | 5. Sheet 1 of 18 | |
|------------------------------------------------------------------------------|-----------------------------------------------------|------------------------------------------------------|------------------------------------------|-------------------|------------------------------|------------------------|--|
| 6 | 7 | 8 | 9 | 10 | 11 | 12 | |
| Description | Category Code | Deficiency Code | Unfunded Cost | Validation Rating | Number of Previous Summaries | Line No. | |
| COMMUNICATIONS AND CONTROL LINES | | | | | | | |
| Replace cable No. 30 from Terminal 239 to cross connect house 247 | 135 | 1 | \$ 89.6 | | 4 | 1 | |
| Replace cable No. 3 from cross connect house 172 to building TC-755 | 135 | 1 | 240.0 | | 5 | 2 | |
| TRAINING FACILITIES OTHER THAN BUILDINGS | | | | | | | |
| Repair tracks vehicular trails | 179 | 1 | 150.0 | | 4 | 3 | |
| TRAINING BUILDINGS | | | | | | | |
| Structural repairs, replace roof, interior and exterior, paint, building A-3 | 213 | 1 | 207.0 | | 3 | 4 | |
| Structural repair, replace roof and exterior paint, building 1202 | 219 | 1 | 79.6 | | 4 | 5 | |
| Structural, electrical, mechanical repairs, building 1300 | 431 | 1 | 77.2 | | 2 | 6 | |
| Replace roof, building 1012 | 441 | 1 | 84.2 | | 1 | 7 | |
| Replace roof, building 1118 | 441 | 1 | 84.2 | | 1 | 8 | |
| Replace roof, building 1317 | 441 | 1 | 84.2 | | 1 | 9 | |
| TROOP HOUSING - BACHELOR EM BARRACKS | | | | | | | |
| Replace ceramic tile in heads of G barracks, Camp Geiger (48 heads) | 721 | 1 | 136.4 | | 0 | 10 | |


Type A Annual Inspection Summary (Unfunded Facilities Deficiencies)

| 1. Activity Marine Corps Base Camp Lejeune, North Carolina | 2. Current - X Projected _____ | 3. Less Housing X Housing _____ | 4. For Period 30 Sept Ending FY 79 | | | 5. Sheet 2 of 18 | |
|----------------------------------------------------------------------------------------------|--------------------------------------|---------------------------------------|---------------------------------------|---------------------------|------------------------------------|------------------------|--|
| 6 | 7 | 8 | 9 | 10 | 11 | 12 | |
| Description | Category Code | Defi- ciency Code | Unfunded Cost | Vali- dation Rating | Number of Previous Summaries | Line No. | |
| Roof replacement, structural repairs and exterior paint building 1209 | 722 | 1 | \$ 46.0 | | 0 | 11 | |
| Structural repairs, replace roof, and interior and exterior paint building RR-3 | 722 | 1 | 71.2 | | 2 | 12 | |
| Structural repairs, interior and exterior paint and replace roof, building BB-45 | 724 | 1 | 29.2 | | 1 | 13 | |
| Structural repairs, interior and exterior painting and replace roofs buildings 1212 and 1500 | 730 | 1 | 256.0 | | 7 | 14 | |
| Correct electrical overload, building 84 | 740 | 1 | 41.6 | | 1 | 15 | |
| Structural repairs, replace gym floor, building 115 | 740 | 1 | 29.5 | | 6 | 16 | |
| Structural, mechanical repairs, replace gym floor, building 300 | 740 | 1 | 29.4 | | 6 | 17 | |
| Structural, mechanical, replace roof and exterior paint, building 322 | 740 | 1 | 30.0 | | 2 | 18 | |
| Structural, mechanical, electrical repairs, replace gym floor, exterior paint, building 401 | 740 | 1 | 40.2 | | 6 | 19 | |
| Structural repairs, interior and exterior painting, building 500 | 740 | 1 | 43.1 | | 6 | 20 | |
| Structural repairs, replace roof, interior and exterior painting, building 730 | 740 | 1 | 59.2 | | 2 | 21 | |

Type A Annual Inspection Summary (Unfunded Facilities Deficiencies)

| | | | | |
|------------------------------------------------------------------|----------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|---------------------------------------|---------------------|
| 1. Activity Marine Corps Base Camp Lejeune, North Carolina | 2. Current <input checked="" type="checkbox"/> X Projected <input type="checkbox"/> | 3. Less Housing <input checked="" type="checkbox"/> X Housing <input type="checkbox"/> | 4. For Period 30 Sept Ending FY 79 | 5. Sheet 3 of 18 |
|------------------------------------------------------------------|----------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|---------------------------------------|---------------------|

| 6 Description | 7 Category Code | 8 Deficiency Code | 9 Unfunded Cost | 10 Validation Rating | 11 Number of Previous Summaries | 12 Line No. |
|-------------------------------------------------------------------------------------------------------------------------|--------------------|----------------------|--------------------|-------------------------|------------------------------------|----------------|
| Structural repairs, roof replacement, interior and exterior paint, building 1200 | 740 | 1 | \$ 68.7 | | 4 | 22 |
| Structural, electrical, mechanical repairs building BB-2 | 740 | 1 | 28.8 | | 1 | 23 |
| Structural, mechanical repairs, replace gym floor, interior paint, building RR-8 | 740 | 1 | 53.4 | | 6 | 24 |
| COMMUNITY FACILITIES - MORALE, WELFARE, AND RECREATION, INTERIOR Modifications to heating/cooling system building 89 | 740 | 1 | 313.0 | | 0 | 25 |
| ELECTRIC POWER - TRANSMISSION AND DISTRIBUTION LINES Repair distribution lines, basewide | 812 | 1 | 64.5 | | 5 | 26 |
| Repair poles, crossarms, and miscellaneous electrical distribution repairs, Camp Geiger Area | 812 | 1 | 60.3 | | 0 | 27 |
| HEAT, STEAM - SOURCE Replace secondary and primary conductors, transformers and related switchgear, building 1700 | 821 | 1 | 400.0 | | 1 | 28 |
| Repairs to boiler refractory and burner cones, buildings 2615, BB-9 and RR-15 | 821 | 1 | 80.0 | | 0 | 29 |
| Replace area steam flow recorders, building 1700 | 821 | 1 | 35.0 | | 0 | 30 |



Type A Annual Inspection Summary (Unfunded Facilities Deficiencies)

| 1. Activity Marine Corps Base Camp Lejeune, North Carolina | 2. Current - <input checked="" type="checkbox"/> X Projected <input type="checkbox"/> | 3. Less Housing <input checked="" type="checkbox"/> X Housing <input type="checkbox"/> | 4. For Period 30 Sep Ending FY 79 | | | 5. Sheet 4 of 18 | |
|--------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------|-----------------------------------------|-------------------|------------------------------|------------------------|--|
| 6 | 7 | 8 | 9 | 10 | 11 | 12 | |
| Description | Category Code | Deficiency Code | Unfunded Cost | Validation Rating | Number of Previous Summaries | Line No. | |
| HEAT, TRANSMISSION AND DISTRIBUTION LINES | | | | | | | |
| Replace steam and condensate lines 300 Area Hadnot Point | 822 | 1 | \$ 749.2 | | 0 | 31 | |
| Replace steam and condensate lines 100 Area Hadnot Point | 822 | 1 | 552.0 | | 0 | 32 | |
| Replace steam and condensate lines 200 Area Hadnot Point | 822 | 1 | 531.4 | | 0 | 33 | |
| Replace steam and condensate lines, Areas 900, 1000, 1100, 1200, 1300, 1400, 1500, 1600 and 1700 | 822 | 1 | 1,381.5 | | 2 | 34 | |
| Replace condensate line from manhole S-11 to building 1700 | 822 | 1 | 161.7 | | 0 | 35 | |
| Replace condensate lines, Camp Johnson | 822 | 1 | 208.0 | | 0 | 36 | |
| Replace condensate line from manhole 159 to S-11 underground | 822 | 1 | 454.9 | | 2 | 37 | |
| Replace steam and condensate lines, Rifle Range | 822 | 1 | 212.3 | | 2 | 38 | |
| Repair steam line insulation French Creek feeder | 822 | 1 | 304.0 | | 1 | 39 | |
| POTABLE WATER - SUPPLY, TREATMENT AND STORAGE | | | | | | | |
| Replace water wells HP-625 and TC-202 | 841 | 1 | 90.0 | | 1 | 40 | |
| Replace water wells TT-53 and M-243 | 841 | 1 | 90.0 | | 0 | 41 | |
| Replace water softening equipment and filters, building M-178 | 841 | 1 | 250.0 | | 0 | 42 | |

Type A Annual Inspection Summary (Unfunded Facilities Deficiencies)

| | | | | |
|------------------------------------------------------------------|------------------------------------------|-------------------------------------------|---------------------------------------|---------------------|
| 1. Activity Marine Corps Base Camp Lejeune, North Carolina | 2. Current - <u>X</u> Projected _____ | 3. Less Housing <u>X</u> Housing _____ | 4. For Period 30 Sept Ending FY 79 | 5. Sheet 5 of 18 |
|------------------------------------------------------------------|------------------------------------------|-------------------------------------------|---------------------------------------|---------------------|


| 6 Description | 7 Category Code | 8 Deficiency Code | 9 Unfunded Cost | 10 Validation Rating | 11 Number of Previous Summaries | 12 Line No. |
|---------------------------------------------------------------------------------|--------------------|----------------------|--------------------|-------------------------|------------------------------------|----------------|
| Replace lime slaking and agitating equipment, building 20 | 841 | 1 | \$ 176.0 | | 1 | 43 |
| Replace boiler number 54, building BB-9 | 841 | 1 | 70.0 | | 0 | 44 |
| Replace lime mixing equipment and tanks, TT-38 | 841 | 1 | 151.9 | | 4 | 45 |
| Replace boiler number 9, building PP-2615 | 841 | 1 | 70.0 | | 0 | 46 |
| Restore cathodic protection in water storage tanks, basewide | 841 | 1 | 54.0 | | 3 | 47 |
| Repair and paint water tank SBA-108 | 841 | 1 | 32.0 | | 0 | 48 |
| ROADS | | | | | | |
| Replace bridges with culverts S-858, S-859, S-860, S-861, S-862, S-863, SBA-148 | 851 | 1 | 186.5 | | 0 | 49 |
| Resurface roads, Camp Johnson | 851 | 1 | 227.3 | | 2 | 50 |
| Resurface roads, Camp Geiger | 851 | 1 | 95.5 | | 2 | 51 |
| Resurface roads, Rifle Range | 851 | 1 | 76.0 | | 2 | 52 |
| Resurface roads, Courthouse Bay | 851 | 1 | 83.6 | | 2 | 53 |
| Resurface roads, basewide | 851 | 1 | 637.3 | | 2 | 54 |
| Resurface roads, Industrial Area | 851 | 1 | 120.4 | | 2 | 55 |

Type A Annual Inspection Summary (Unfunded Facilities Deficiencies)

| | | | | |
|------------------------------------------------------------------|--------------------------------------------|----------------------------------------------|-----------------------------------------|------------------------|
| 1. Activity Marine Corps Base Camp Lejeune, North Carolina | 2. Current <u>-X</u> Projected _____ | 3. Less Housing <u>X</u> Housing _____ | 4. For Period 30 Sep Ending FY 79 | 5. Sheet 6 of 18 |
|------------------------------------------------------------------|--------------------------------------------|----------------------------------------------|-----------------------------------------|------------------------|


| | | | | | | |
|-------------|---------------|-----------------|---------------|-------------------|------------------------------|----------|
| 6 | 7 | 8 | 9 | 10 | 11 | 12 |
| Description | Category Code | Deficiency Code | Unfunded Cost | Validation Rating | Number of Previous Summaries | Line No. |

| | | | | | | |
|--------------------------------------------------|-----|---|------------|--|---|----|
| SIDEWALKS AND OTHER PAVEMENTS | | | | | | |
| Repair sidewalks, basewide | 851 | 1 | \$ 26.0 | | 7 | 56 |
| Repair parking lots, various locations, basewide | 851 | 1 | 252.0 | | 7 | 57 |
| GROUNDS - DRAINAGE | | | | | | |
| Repairs to drainage ditches, basewide | 871 | 1 | 323.6 | | 5 | 58 |
| Repairs to security fences, basewide | 872 | 1 | 165.0 | | 3 | 59 |
| Code I Subtotal | | | \$10,743.6 | | | |



Type A Annual Inspection Summary (Unfunded Facilities Deficiencies)

| 1. Activity Marine Corps Base Camp Lejeune, North Carolina | 2. Current - <input checked="" type="checkbox"/> Projected _____ | 3. Less Housing <input checked="" type="checkbox"/> Housing _____ | 4. For Period 30 Sep Ending FY 79 | | 5. Sheet 7 of 18 | |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------|----------------------------------------------------------------------|--------------------------------------|-------------------|------------------------------|----------|
| 6 | 7 | 8 | 9 | 10 | 11 | 12 |
| Description | Category Code | Deficiency Code | Unfunded Cost | Validation Rating | Number of Previous Summaries | Line No. |
| LAND VEHICLE FUELING/DISPENSING FACILITIES Structural, mechanical repairs, painting building 1002 | 123 | 2 | \$ 2.2 | | 6 | 60 |
| POL PIPELINE (TWO BUILDINGS) Structural repairs, painting, buildings 1004 and 1706 | 125 | 2 | .6 | | 6 | 61 |
| OTHER LIQUID FUELING AND DISPENSING Structural, mechanical repairs, building TC-362 | 126 | 2 | 1.3 | | 0 | 62 |
| COMMUNICATIONS - BUILDINGS (FOURTEEN BUILDINGS) Structural, electrical repairs, reroofing, painting buildings 24, 26, 1104, M-167, BB-69, PT-5, TC-724, TC-725, TC-734, TP-450, VL-172 | 131 | 2 | 32.9 | | 3 | 63 |
| COMMUNICATIONS AND CONTROL LINES Replacement of cable 214 and aerial cable 1701 with direct burial cable from TP-450 to Highway 24 | 135 | 2 | 9.5 | | 0 | 64 |
| OPERATIONAL BUILDINGS Structural, mechanical repairs, painting building 54 | 141 | 2 | 7.5 | | 6 | 65 |
| Structural, electrical repairs, reroofing, painting (twenty-six buildings) 126, 218, 244, 335, 402, 413, 440, 743, 744, 752, 807, 814, 828, 856, 857, 874, 919, G-480, M-308, BB-6, FC-301, FC-302, RR-70, SH-7, VL-100 and FAD-1 | 143 | 2 | 59.9. | | 6 | 66 |




Type A Annual Inspection Summary (Unfunded Facilities Deficiencies)

| 1. Activity | 2. Current - X Projected | 3. Less Housing X Housing | 4. For Period 30 Sep Ending FY 79 | | | 5. Sheet 8 of 18 | |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|------------------------------|--------------------------------------|-------------------------|------------------------------------|---------------------|--|
| Marine Corps Base Camp Lejeune, North Carolina 6 | | | | | | | |
| Description | 7 Category Code | 8 Deficiency Code | 9 Unfunded Cost | 10 Validation Rating | 11 Number of Previous Summaries | 12 Line No. | |
| TRAINING BUILDINGS (ONE HUNDRED FOUR BUILDINGS) Structural, electrical, mechanical repairs, reroofing, painting buildings 64, 222, 229, 230, 306, 337, 338, 344, 408, 443, 451 512, 531, 538, 539, 883, 1308, 1318, 1319; M-101, M-102, M-104, M-113, M-119, M-121, M-122, M-123, M-124, M-125, M-127, M-126, M-132, M-202, M-203, M-214, M-219, M-255, M-307, M-324, M-326, M-327, M-403, M-405, M-406, M-407, M-409, M-411, M-412, M-413, M-416, M-420, M-422, M-513, M-520, M-620, BB-32, BB-34, BB-49, BB-50, BB-52, BB-68, BB-71, BB-73, BB-80, BB-82, BB-84, BB-89, BB-90, BB-91, BB-92, BB-93, BB-95, BB-100, BB-138, BB-174, BB-175, BB-176, BB-223, ES-101, ES-200, FC-312, RR-53, RR-253, SM-329, TC-174, TC-179, TC-650, TC-723, TC-1017, TC-1024, TC-1025, TC-1036, TC-1037, TC-1038, TC-1062, TC-1120, TC-1143, TP-455, TP-456, SBB-76, SBB-161, SBB-183, SBB-226 and SBB-227 | 171 | 2 | \$ 232.3 | | 4 | 67 | |
| TRAINING FACILITIES - OTHER THAN BUILDING (THIRTY-FOUR BUILDINGS) Structural, electrical, mechanical repairs, reroofing, painting buildings 236, M-139, S-942, SK-5A, SK-11A, SM-6A, SM-180, SM-196, SM-262, SBA-158, SBB-217, SFC-700, SRR-19A, SRR-64, SRR-65, SRR-66, STC-299, STC-367, STC-644, STC-651, STC-1204, STC-1205, STC-1206, STC-1213, STC-1219, STC-1222, STC-1223, STC-1226, STP-454, SVL-128, SVL-142, SVL-175, SVL-177 and SVL-180 | 179 | 2 | 44.1 | | 4 | 68 | |
| MAINTENANCE - SHIPS, SPARES Structural repairs, reroofing, painting building A-2 | 213 | 2 | 19.3 | | 2 | 69 | |

Type A Annual Inspection Summary (Unfunded Facilities Deficiencies)

| 1. Activity Marine Corps Base Camp Lejeune, North Carolina 6 | 2. Current - X Projected _____ | 3. Less Housing X Housing _____ | 4. For Period 30 Sep Ending FY 79 | | | | 5. Sheet 9 of 18 |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|---------------------------------------|--------------------------------------|---------------------------------|------------------------------------------|-------------------|------------------------|
| Description | 7 Category Code | 8 Defi- ciency Code | 9 Unfunded Cost | 10 Vali- dation Rating | 11 Number of Previous Summaries | 12 Line No. | |
| MAINTENANCE - TANK, AUTOMOTIVE (FIFTY-FOUR BUILDINGS) Structural, electrical, mechanical repairs, reroofing, painting buildings 739, 746, 901, 908, 913, 1018, 1205, 1206, 1405, 1406, 1502, 1503, 1504, 1505, 1506, 1601, 1604, 1605, 1607, 1711, 1739, 1750, 1755, 1760, 1809, 1817, 1820, 1822, 1841, A-11, S-938, S-1050, BA-130, FC-100, GP-1, GP-21, SA-26, SA-29, SA-34, SA-36, SH-13, SM-173, TC-771, TC-773, TC-774, TC-863, TC-864, TC-952, SBB-169, SFC-205, SGP-15, SGP-17, SRR-80 and STC-777 | 214 | 2 | \$ 249.9 | | 3 | 70 | |
| MAINTENANCE - WEAPONS, SPARES Structural repairs, building 1780 | 215 | 2 | .5 | | 0 | 71 | |
| MAINTENANCE - AMMUNITION, EXPLOSIVES, TOXICS Structural repairs, painting, building SH-8 | 216 | 2 | 6.6 | | 0 | 72 | |
| MAINTENANCE - ELECTRONICS/COMMUNICATIONS (FOURTEEN BUILDINGS) Structural repairs, reroofing, painting, buildings 134, 234, 307, 329, 414, 439, 442, 444, 505, 532, 816, 1309, 1603 and 1707 | 217 | 2 | 56.5 | | 7 | 73 | |
| MAINTENANCE - FACILITIES, MISCELLANEOUS ITEMS/EQUIPMENT (EIGHT BUILDINGS) Structural, electrical, mechanical repairs, reroofing, painting buildings 902, 910, 1022, 1310, 1808, A-13, BB-51 and FC-200 | 218 | 2 | 53.6 | | 6 | 74 | |
| MAINTENANCE - PUBLIC WORKS REPAIR AND OPERATIONS (TWENTY-SIX BUILDINGS) Structural, electrical, mechanical repairs, reroofing, painting buildings 42, 45, 539, 780, 866, 939, 1102, | | | | | | | |



Type A Annual Inspection Summary (Unfunded Facilities Deficiencies)

| 1. Activity | 2. Current - X Projected _____ | 3. Less Housing X Housing _____ | 4. For Period 30 Sep Ending FY 79 | | | | 5. Sheet 10 of 18 | |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------|------------------------------------|--------------------------------------|-------------------|------------------------------|----------|----------------------|----|
| Marine Corps Base Camp Lejeune, North Carolina 6 | | | 7 | 8 | 9 | 10 | 11 | 12 |
| Description | Category Code | Deficiency Code | Unfunded Cost | Validation Rating | Number of Previous Summaries | Line No. | | |
| 1105, 1114, 1202, 1302, 1304, 1919, 1966, M-103, M-135, M-158, M-323, RR-13, TC-715, TC-832, TT-41, TT-49, LCH-4023, LCH-4027 and STT-50 | 219 | 2 | \$ 59.0 | | 7 | 75 | | |
| PRODUCTION - MAINTENANCE - REPAIR AND OPERATIONS OF INSTALLATION (THREE BUILDINGS) Structural repairs, painting buildings 80, 1111 and 1115 | 229 | 2 | 6.0 | | 4 | 76 | | |
| RESEARCH - DEVELOPMENT, TEST AND EVALUATION (FIVE BUILDINGS) Electrical repairs, reroofing, painting buildings 813, PT-6, PT-9, PT-25 and PT-37 | 310 | 2 | 8.0 | | 8 | 77 | | |
| AMMUNITION STORAGE DEPOT AND INSTALLATION (SEVENTY-TWO BUILDINGS) Structural repairs, reroofing, painting, buildings FAD-6, FAD-7, FAS-8, FAS-9, FAD-10, FAD-11, FAD-12, FAD-13, FAD-14, FAD-15, FAD-16, FAD-17, SBA-136, SBA-137, SFA-1, SFA-2, SFA-3, SFA-4, SFA-5, SFA-6, SFD-1, STA-7, SFA-8, SFD-2, SFD-3, SFD-4, SFD-5, SFD-6, SFD-7, SFD-8, SFD-9, SFD-10, SFD-11, SFD-12, SFD-13, SFD-14, SHE-1, SHE-2, SHE-3, SHE-4, SHE-5, SHE-6, SHE-7, SHE-8, SHE-9, SHE-10, SHE-11, SRR-241, SRR-252, SSA-1, SSA-2, SSA-4, SSA-5, SSA-6, SSA-7, SSA-8, SSA-9, SSH-1, SSH-2, SSH-3, SSH-4, SSH-5, SSH-6, STC-130, SVL-14, SVL-16, SVL-17, SVL-18, SVL-19, SVL-20, SVL-21, SVL-22 | 421 | 2 | 45.8 | | 9 | 78 | | |
| GENERAL SUPPLY STORAGE/SUPPLY OPERATIONS BUILDINGS Structural, electrical, mechanical, reroofing, painting, (Two hundred seventy-one Buildings) 11, 14A, 25A, 100, 103, 107, 113, 116, 117A, 130, 131, 132, 133, 200, 203A, 206, 210, 215, 231, 232, 302A, 303, 310, 319, 328, 332, | | | | | | | | |

Type Annual Inspection Summary (Unfunded Facilities Deficiencies)

| | | | | |
|------------------------------------------------------------------|---------------------------------------------|----------------------------------------------|-----------------------------------------|-------------------------|
| 1. Activity Marine Corps Base Camp Lejeune, North Carolina | 2. Current - <u>X</u> Projected _____ | 3. Less Housing <u>X</u> Housing _____ | 4. For Period 30 Sep Ending FY 79 | 5. Sheet 11 of 18 |
|------------------------------------------------------------------|---------------------------------------------|----------------------------------------------|-----------------------------------------|-------------------------|

| | | | | | | |
|------------------|--------------------|----------------------|--------------------|-------------------------|------------------------------------|----------------|
| 6 Description | 7 Category Code | 8 Deficiency Code | 9 Unfunded Cost | 10 Validation Rating | 11 Number of Previous Summaries | 12 Line No. |
|------------------|--------------------|----------------------|--------------------|-------------------------|------------------------------------|----------------|

334, 341, 343, 405, 418, 428, 431, 432, 433, 434, 435,
 436, 441, 445, 504, 509, 513, 525, 528, 529, 533, 534, 548,
 571, 702, 729, 738, 747, 752B, 801, 900, 903, 904, 905, 906,
 907, 909, 914, 915, 916, 926, 927, 928, 943, 1011, 1013, 1014,
 1053, 1101, 1108, 1116, 1117, 1201, 1203, 1211, 1301, 1305,
 1311, 1312, 1316, 1401, 1419, 1501, 1606, 1705, 1709, 1710,
 1730, 1731, 1737, 1738, 1757, 1800, 1801, 1802, 1810, 1816,
 1819, 1824, 1826, 1829, 1831, 1833, 1835, 1847, 1849, 1903,
 1916, 1932, 1975, 1999, 2629, A-1, A-8, A-9, A-10, A-12,
 A-14, A-37, M-112, M-133, M-151, M-166, M-182, M-184, M-259,
 M-301, M-314, M-319, M-330, M-402, M-408, M-415, M-501, M-506,
 M-512, M-606, M-689, BA-128, BB-31, BB-83, BB-88, BB-166,
 BB-172, BB-224, BB-225, BB-228, BB-231, BB-232, BB-233, BB-234,
 CG-23, CG-28, ES-139, FC-101, FC-102, FC-206, FC-207, FC-208,
 GP-2, GP-3, GP-4, GP-5, GP-7, GP-8, GP-9, GP-12, GP-13, GP-20,
 HP-28, PT-42, RR-14, RR-16, RR-19, RR-30, RR-33, RR-36, RR-48,
 RR-50, RR-62, RR-238, RR-240, RR-247, RR-248, RR-254, RR-260,
 SH-9, SH-11, TC-98, TC-180, TC-185, TC-309, TC-322, TC-341,
 TC-342, TC-460, TC-462, TC-470, TC-471, TC-473, TC-474, TC-560,
 TC-562, TC-569, TC-572, TC-608, TC-611, TC-628, TC-630, TC-720,
 TC-721, TC-722, TC-731, TC-760, TC-761, TC-762, TC-775, TC-820,
 TC-821, TC-822, TC-823, TC-824, TC-825, TC-830, TC-831, TC-833,
 TC-834, TC-835, TC-860, TC-861, TC-862, TC-940, TC-942, TC-1020,
 TC-1021, TC-1022, TC-1023, TC-1030, TC-1031, TC-1032, TC-1033,
 TC-1034, TC-1035, TC-1053, TC-1055, TC-1056, TC-1057, TC-1058,
 TP-448, TP-449, TP-451, VL-25, VL-141, VL-166, VL-169, FAD-2,
 FAD-3, LCH-4029, SBB-140, SBB-170, SBB-213, SBB-238, STC-346,
 STC-629, USO-2

441

2

597.3

5


79

LABORATORIES AND CLINICS
 Structural, mechanical repairs and painting buildings

Type A Annual Inspection Summary (Unfunded Facilities Deficiencies)

| | | | | |
|------------------------------------------------------------------|------------------------------------------|-------------------------------------------|--------------------------------------|------------------------------------|
| 1. Activity Marine Corps Base Camp Lejeune, North Carolina | 2. Current <u>- X</u> Projected _____ | 3. Less Housing <u>X</u> Housing _____ | 4. For Period 30 Sep Ending FY 79 | 5. Sheet <u>12</u> of <u>18</u> |
|------------------------------------------------------------------|------------------------------------------|-------------------------------------------|--------------------------------------|------------------------------------|

| 6 Description | 7 Category Code | 8 Deficiency Code | 9 Unfunded Cost | 10 Validation Rating | 11 Number of Previous Summaries | 12 Line No. |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------|----------------------|--------------------|-------------------------|------------------------------------|----------------|
| 36 and 35 | 530 | 2 | \$ 36.4 | | 4 | 80 |
| DISPENSARIES (EIGHT BUILDINGS) Structural, electrical, mechanical repairs, painting buildings 15, 119, 221, 324, 421, 520, G-770 and BB-10 | 550 | 2 | 25.6 | | 7 | 81 |
| ADMINISTRATIVE BUILDINGS (ONE HUNDRED THIRTY-NINE BUILDINGS) Structural, electrical, mechanical repairs, reroofing, painting, buildings 1, 2, 3B, 7, 13, 14, 24, 27, 33, 50, 59, 61, 66, 114, 117, 121, 123, 127, 203, 207, 214, 216, 219, 223, 233, 248, 302, 304, 311, 314, 315, 317, 320, 331, 333, 336, 339, 340, 342, 400, 416, 419, 423, 429, 430, 437, 438, 501, 516, 518, 518A, 522, 526, 535, 536, 537, 800, 827, 854, 896, 1005, 1020, 1021, 1100, 1403, 1404, 1407, 1409, 1410, 1509, 1722, 1811, 1812, 1944, G-520, G-530, G-540, G-550, M-105, M-131, M-144, M-200, M-201, M-215, M-401, M-414, M-418, M-514, M-521, M-601, M-603, M-611, M-612, M-613, BB-5, BB-15, BB-28, BB-37, BB-38, BB-86, BB-208, CG-1, FC-201, RR-11, RR-12, RR-17, RR-20, RR-22, RR-24, TC-704, TC-705, TC-706, TC-716, TC-717, TC-718, TC-719, TC-726, TC-727, TC-728, TC-729, TC-736, TC-737, TC-739, TC-745, TC-750, TC-751, TC-752, TC-753, TC-754, TC-805, TC-809, TC-854, TC-1048, TC-1049, TC-1060, TC-1110, TT-45, LCH-4002, LCH-4014E, | 610 | 2 | 314.6 | | | 82 |
| TROOP HOUSING - BACHELOR EM BARRACKS (ONE HUNDRED FIFTY BUILDINGS) Structural, electrical, mechanical repairs, reroofing, painting buildings 6, 8, 10, 12, 58, 60, 101, 102, 104, 105, 108, 109, 111, 112, 118, 202, 204, 205, 208, 209, 212, 217, 220, 308, 309, 312, 313, 316, 318, 321, 323, 326, 327, 404, | | | | | | |



Type A Annual Inspection Summary (Unfunded Facilities Deficiencies)

| | | | | |
|------------------------------------------------------------------|-----------------------------------|------------------------------------|--------------------------------------|----------------------|
| 1. Activity Marine Corps Base Camp Lejeune, North Carolina | 2. Current - X Projected _____ | 3. Less Housing X Housing _____ | 4. For Period 30 Sep Ending FY 79 | 5. Sheet 14 of 18 |
|------------------------------------------------------------------|-----------------------------------|------------------------------------|--------------------------------------|----------------------|

| 6 | 7 | 8 | 9 | 10 | 11 | 12 |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-----------------|---------------|-------------------|------------------------------|----------|
| Description | Category Code | Deficiency Code | Unfunded Cost | Validation Rating | Number of Previous Summaries | Line No. |
| 406, 407, 409, 410, 412, 415, 417, 420, 422, 426, 427, 502, 503, 506, 507, 510, 511, 514, 517, 519, 523, 527, 1042, G-521, G-522, G-523, G-524, G-531, G-532, G-533, G-534, G-541, G-542, G-543, G-544, G-551, G-552, G-553, G-554, M-128, M-130, M-211, M-212, M-213, M-217, M-218, M-221, M-222, M-223, M-224, M-225, M-226, M-227, M-228, M-229, M-303, M-305, M-311, M-313, M-316, M-318, M-503, M-504, M-507, M-509, M-511, M-516, M-518, M-604, M-607, M-609, M-614, M-616, M-621, M-622, BA-102, BA-104, BA-105, BB-250, BB-255, FC-304, FC-305, FC-306, FC-309, FC-310, FC-311, HP-301, RR-1, RR-2, RR-4, RR-5, TC-804, TC-806, TC-807, TC-808, TC-1003, TC-1004, TC-1005, TC-1006, TC-1007, TC-1008, TC-1009, TC-1018, TC-1019, TC-1026, TC-1027, TC-1028, TC-1039, TC-1046, TC-1047, TC-1064, TC-1065, TC-1066, TC-1131, TC-1132, and TC-1142 | 721 | 2 | \$ 734.8 | | 0 | 83 |
| BACHELOR HOUSING - MESS FACILITIES (SIXTEEN BUILDINGS) Structural, electrical, mechanical repairs, painting Buildings 9, 106, 122, 211, 226, 325, 411, 424, 508, 521, G-640, M-424, BA-103, BB-7, FC-303 and FC-420 | 722 | 2 | 44.9 | | 4 | 84 |
| BACHELOR - HOUSING - DETACHED FACILITIES (FORTY-EIGHT BUILDINGS) Structural, electrical, mechanical repairs, reroofing, painting, Buildings 30, 550, 924, 1814, M-205, M-206, M-207, M-208, M-209, M-210, M-315, M-419, M-502, M-619, BB-96, BB-98, BB-151, GP-14, RR-26, RR-27, RR-28, RR-29, RR-31, RR-32, RR-34, RR-35, RR-37, TC-812, TC-850, TC-851, TC-865, TC-1010, TC-1012, TC-1013, TC-1015, TC-1016, TC-1029, TC-1040, TC-1041, TC-1042, TC-1044, TC-1045, TC-1050, TC-1051, TC-1052, TC-1054, TC-1140, TC-1141 | 723 | 2 | 62.2 | | 3 | 85 |

Type A Annual Inspection Summary (Unfunded Facilities Deficiencies)

| 1. Activity Marine Corps Base Camp Lejeune, North Carolina | 2. Current - X Projected _____ | 3. Less Housing X Housing _____ | 4. For Period 30 Sep Ending FY 79 | | | 5. Sheet 15 of 18 | |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|---------------------------------------|-----------------------------------------|-------------------------|------------------------------------|-------------------------|--|
| 6 Description | 7 Category Code | 8 Deficiency Code | 9 Unfunded Cost | 10 Validation Rating | 11 Number of Previous Summaries | 12 Line No. | |
| BACHELOR - HOUSING - OFFICERS QUARTERS (SEVENTEEN BUILDINGS) Structural, electrical, mechanical repairs, reroofing, painting, Buildings 2604, 2605, 2607, 2609, 2611, 2613, 2617, M-231, M-232, M-233, RR-9, TC-1067, TC-1068, TC-1069, TC-1160, TC-1161, TC-1162 | 724 | 2 | \$ 17.9 | | 5 | 86 | |
| COMMUNITY FACILITIES - PERSONNEL SUPPORT AND SERVICES (FORTY-TWO BUILDINGS) Structural, electrical, mechanical repairs, reroofing, painting, Buildings 3, 18, 35, 235, 812, 1041, 1047, 1208, 1400, 1963, 1964, 1965, 1969, 1982, 1984, 2600, A-15, A-20, A-33, M-169, M-302, M-325, S-1741, BB-8, BB-136, PT-33, RR-6, RR-78, SD-46, SH-8A, SH-12, TC-306, TC-701, TC-732, TC-733, TT-57, LCH-4000, LCH-4022, SFC-321, SFC-322, SPT-32, SSH-10 | 730 | 2 | 87.3 | | | 87 | |
| COMMUNITY FACILITIES - MORALE, WELFARE, AND RECREATION, - INTERIOR (ONE HUNDRED TWENTY BUILDINGS) Structural, electrical, mechanical repairs, reroofing, painting, Buildings 4, 4A, 16, 17, 19, 25, 31, 37, 39, 41, 43, 62, 63, 84, 87, 89, 125, 125A, 129, 145, 201, 225, 225A, 251, 253, 322A, 330, 403, 403A, 425, 425A, 457, 524, 524A, 600, 712, 728, 751, 826, 895, 897, 898, 1006, 1015, 1103, 1106, 1113, 1120, 1402, 1413, 1610, 1611, 1612, 1613, 1614, 1615, 1728, 1765, 1909, 1945, 1985, 2601, 2615, 2625, 2626, 2627, 2628, A-25, E-1, G-560, M-100, M-129, M-124, M-171, M-238, M-239, M-240, M-321, M-602, BB-3, BB-3A, BB-16, BB-30, BB-36, BB-46, BB-54, BB-177, BB-210, GP-10, PT-4, PT-30, RR-8, RR-10, RR-49, RR-51, SA-28, SM-183, TC-200, TC-614, TC-900, TC-910, TC-912, TC-1130, TT-44, TT-2453, TT-2455, TT-2457, TT-2463, TT-2465, TT-2469, TT-2471, TT-2473, TT-2475, LCH-4014, LCH-4014D, LCH-4015, LCH-4025, SBB-94, SBB-229, USC-1 | 740 | 2 | 517.3 | | | 88 | |


Type A Annual Inspection Summary (Unfunded Facilities Deficiencies)

| | | | | | | |
|------------------------------------------------------------------|-----------------------------------|------------------------------------|--------------------------------------|--|--|----------------------|
| 1. Activity Marine Corps Base Camp Lejeune, North Carolina | 2. Current - X Projected _____ | 3. Less Housing X Housing _____ | 4. For Period 30 Sep Ending FY 79 | | | 5. Sheet 16 of 18 |
|------------------------------------------------------------------|-----------------------------------|------------------------------------|--------------------------------------|--|--|----------------------|

| | | | | | | |
|---|---|---|---|----|----|----|
| 6 | 7 | 8 | 9 | 10 | 11 | 12 |
|---|---|---|---|----|----|----|

| Description | Category Code | Deficiency Code | Unfunded Cost | Validation Rating | Number of Previous Summaries | Line No. |
|-------------|---------------|-----------------|---------------|-------------------|------------------------------|----------|
|-------------|---------------|-----------------|---------------|-------------------|------------------------------|----------|

| | | | | | | |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|---|--------|--|---|----|
| COMMUNITY FACILITIES - MORALE, WELFARE AND RECREATION, EXTERIOR (THIRTEEN BUILDINGS) Structural repairs, reroofing, painting, Buildings SD-9, SM-175, SM-189, SM-190, SM-245, SM-246, SM-247, SM-248, SBB-59, SRR-71, SRR-101, STC-856 and STC-866 | 750 | 2 | \$ 7.9 | | 3 | 89 |
| ELECTRIC POWER, SOURCE (FIVE BUILDINGS) Structural repairs, reroofing, painting, buildings 353, BB-193, BB-216, FC-209 and SFC-106 | 750 | 2 | 2.8 | | 1 | 90 |
| ELECTRIC POWER - TRANSMISSION AND DISTRIBUTION LINES (THREE BUILDINGS) Structural repairs, reroofing, painting, Buildings 884, H-35 and H-70 | 812 | 2 | .4 | | 3 | 91 |
| HEAT; STEAM - SOURCE (EIGHT BUILDINGS) Structural repairs, reroofing, painting, Buildings 740, 779, 1700, M-170, M-230, M-625, BB-9 and RR-15 | 821 | 2 | 53.5 | | 9 | 92 |
| HEAT, GAS - SOURCE Structural repairs, reroofing, painting, Buildings 803 and 804 | 823 | 2 | 2.9 | | 1 | 93 |
| SEWAGE AND INDUSTRIAL WASTE, TREATMENT AND DISPOSAL (SEVENTEEN BUILDINGS) Structural repairs, reroofing, painting, Buildings 22, 32, 683, 765, M-136, M-137, M-138, BB-4, SM-331, TC-563, TT-35, TT-56, SBB-67, SRR-67, SRR-93, STC-636, STC-637 | 831 | 2 | 17.3 | | 6 | 94 |
| SEWAGE AND INDUSTRIAL WASTE COLLECTION (TEN BUILDINGS) Structural repairs, reroofing, painting, Buildings 21, 34, 46, 672, RR-52, TT-36, SEA-160, STT-32, STT-34, LSCH-4005 | 832 | 2 | 5.6 | | 6 | 95 |




Type A Annual Inspection Summary (Unfunded Facilities Deficiencies)

| 1. Activity Marine Corps Base Camp Lejeune, North Carolina | 2. Current - X Projected _____ | 3. Less Housing X Housing _____ | 4. For Period 30 Sep Ending FY 79 | | | | 5. Sheet 17 of 18 |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------|------------------------------------|--------------------------------------|-----------------------|----------------------------------|--------------|----------------------|
| 6. Description | 7. Category Code | 8. Deficiency Code | 9. Unfunded Cost | 10. Validation Rating | 11. Number of Previous Summaries | 12. Line No. | |
| REPOSE - GARBAGE (FOUR BUILDINGS) Structural repairs, reroofing, painting, Buildings M-101A, M-256, M-426 and FC-19 | 833 | 2 | \$ 3.8 | | 1 | 96 | |
| POTABLE WATER SUPPLY, TREATMENT AND STORAGE (FIFTY-SEVEN BUILDINGS) Structural repairs, reroofing, painting, Buildings 20, 38, 601, 602, 603, 606, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 619, 620, 621, 625, 626, 630, 633, 634, 635, 636, 762, A-5, M-142, M-143, M-168, M-178, M-243, BB-44, BB-190, RR-47, TC-100, TC-104, TC-202, TC-502, TC-504, TC-600, TC-604, TC-700, TC-901, TC-1000, TT-26, TT-38, TT-52, TT-53, SBA-151, SBB-25, SRR-44, STC-503, STC-606, STC-619, STC-1070. | 841 | 2 | 67.8 | | 8 | 97 | |
| WATER - DISTRIBUTION SYSTEM POTABLE (EIGHT BUILDINGS) Structural repairs, reroofing, painting, Buildings 741, 742, A-4, D-39, TC-501, LCH-4006, LCH-4007, STT-39A | 842 | 2 | 2.9 | | 4 | 98 | |
| ROADS AND VEHICULAR STRUCTURES (FOUR STRUCTURES) Structural repairs, painting, structures SBA-129, STC-617, STC-1220 and SVL-126 | 851 | 2 | 54.4 | | 1 | 99 | |
| Repair road shoulders, basewide | 851 | 2 | 139.2 | | 2 | 100 | |
| MISCELLANEOUS FACILITIES Structural, electrical, mechanical repairs, reroofing, painting, Building 1702 | 890 | 2 | 11.4 | | 0 | 101 | |
| Code II Total | | | \$ 3,703.7 | | | | |

Type A Inspection Summary (Unfunded Facilities Deficiencies)

| | | | | |
|----------------------------------------------------------------|--------------------------------------|---------------------------------------|-----------------------------------------|-------------------------|
| Community Marine Corps Base Camp Lejeune, North Carolina | 2. Current - X Projected _____ | 3. Less Housing X Housing _____ | 4. For Period 30 Sep Ending FY 79 | 5. Sheet 18 of 18 |
|----------------------------------------------------------------|--------------------------------------|---------------------------------------|-----------------------------------------|-------------------------|

| 6 | 7 | 8 | 9 | 10 | 11 | 12 |
|---------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-----------------|-------------------|-------------------|------------------------------|----------|
| Description | Category Code | Deficiency Code | Unfunded Cost | Validation Rating | Number of Previous Summaries | Line No. |
| CODE III | | | | | | |
| OPERATIONAL - BUILDINGS (THREE BUILDINGS) Demolition of buildings 857, RR-70 and SM-6A | 141 | 3 | \$ 7.0 | | 1 | 102 |
| TRAINING FACILITIES OTHER THAN BUILDINGS (SIX BUILDINGS) Demolition of training courses S-454, RNGM-109, RNGM-122, SOC-1C, SVL-130 and SVL-178 | 179 | 3 | 3.2 | | 1 | 103 |
| BACHELOR HOUSING - DETACHED FACILITIES (THREE BUILDINGS) Demolition of mess shelters, SVL-158, SVL-159 and SVL-163 | 723 | 3 | 6.3 | | 1 | 104 |
| SEWAGE AND INDUSTRIAL WASTE - COLLECTION Demolition of sewage lift station CG-22 | 832 | 3 | .8 | | 1 | 105 |
| Subtotal | | | 17.3 | | | |
| <u>MARINE CORPS BASE</u> | | | | | | |
| Code I | | | \$10,743.6 | | | |
| Code II | | | 3,703.7 | | | |
| Code III | | | 17.3 | | | |
| Total | | | <u>\$14,464.6</u> | | | |
| <u>MARINE CORPS AIR STATION(H)</u> | | | | | | |
| Code I | | | \$ 2,697.6 | | | |
| Code II | | | 478.0 | | | |
| Total | | | <u>\$3,175.6</u> | | | |



WKREPTBR

BMAR REPORT AND PROJECTS -PLAN
MARINE CORPS BASE
CAMP LEJEUNE, NORTH CAROLINA
FY-80



BMAR REPORT AND PROJECTS PLAN (BACKLOG OF MAINTENANCE AND REPAIR)

| | | | | |
|------------------------------------------------------------------|-------------------------------|----------------------------------|-------------------------------------|-----------------------------------|
| 1. ACTIVITY Marine Corps Base Camp Lejeune, North Carolina | 2. CURRENT PROJECTED <u>X</u> | 3. LESS HOUSING HOUSING <u>X</u> | 4. FOR PERIOD ENDING 30 Sep 1980 | 5. SHEET <u>1</u> OF <u>14</u> |
|------------------------------------------------------------------|-------------------------------|----------------------------------|-------------------------------------|-----------------------------------|

| DESCRIPTION | CATEGORY CODE | DEFICIENCY CODE | UNFUNDED COST | VALIDATION RATING | NUMBER OF PREVIOUS SUMMARIES | LINE NO. |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-----------------|---------------|-------------------|------------------------------|----------|
| CODE I | | | | | | |
| STRUCTURAL REPAIRS, BUILDING SA-21 | 122 | 1 | .6 | | 1 | 1 |
| LAND VEHICLE FUELING/DISPENSING FACILITIES Structural, mechanical repairs, painting Buildings 1002 & S-1843 | 123 | 1 | 1.5 | | 8 | 2 |
| POL PIPELINE Structural repairs, painting, Buildings 1004 and 1706 | 125 | 1 | 1.0 | | 8 | 3 |
| OTHER LIQUID FUELING AND DISPENSING Structural, mechanical repairs, Building TC-362 | 126 | 1 | 4.8 | | 2 | 4 |
| COMMUNICATIONS - BUILDINGS Structural, electrical repairs, reroofing, painting, Buildings 26, 1104, M-167, BB-69, PT-5, TC-734, TC-735, TC-1059 and TC-1119 | 131 | 1 | 26.9 | | 5 | 5 |
| COMMUNICATIONS - OTHER THAN BUILDINGS Painting - S-99 | 132 | 1 | .8 | | 0 | 6 |
| OPERATIONAL BUILDINGS Structural, mechanical repairs, painting Building 54 | 141 | 1 | 29.7 | | 8 | 7 |
| STRUCTURAL, ELECTRICAL REPAIRS, REROOFING, PAINTING Buildings 126, 218, 244, 335, 402, 413, 440, 743, 744, 752, 807, 814, 828, 857, 874, 919, G-480, M-308, FC-301, FC-302, S-752A and BB-6 | 143 | 1 | 52.2 | | 8 | 8 |
| TRAINING BUILDINGS Structural, electrical, mechanical repairs, reroofing, painting Buildings 222, 229, 230, 306, 337, 338, 344, 408, 443, 451, 512, 538, 539, 883, 934, 935, 1308, M-104, M-119, M-124, M-255, M-307, M-324, M-327, M-420, M-520, M-620, BB-32, BB-34, BB-49, BB-50, BB-52, BB-71, BB-73, BB-84, BB-89, BB-91, BB-92, BB-95, BB-138, BB-174, BB-175, BB-176, BB-214, BB-222, BB-223, ES-101, ES-200, FC-312, RR-53, SM-329, TC-174, TC-179, TC-650, TC-1060, TC-1120, | | | | | | |



BMAR REPORT AND PROJECTS PLAN (BACKLOG OF MAINTENANCE AND REPAIR)

| | | | | |
|-------------------------------------------------------------------|-----------------------------------|--------------------------------------|-------------------------------------|--------------------------------------|
| 1. ACTIVITY Marine Corps Base, Camp Lejeune, North Carolina | 2. CURRENT PROJECTED <u> X </u> | 3. LESS HOUSING HOUSING <u> X </u> | 4. FOR PERIOD ENDING 30 Sep 1980 | 5. SHEET <u> 2 </u> OF <u> 14 </u> |
|-------------------------------------------------------------------|-----------------------------------|--------------------------------------|-------------------------------------|--------------------------------------|

| DESCRIPTION | CATEGORY CODE | DEFICIENCY CODE | UNFUNDED COST | VALIDATION RATING | NUMBER OF PREVIOUS SUMMARIES | LINE NO. |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-----------------|---------------|-------------------|------------------------------|----------|
| TC-1143, TP-455, TP-456, SBB-76, SBB-161, SBB-183, SBB-226 and SBB-227 | 171 | 1 | 181.9 | | 6 | 9 |
| TRAINING FACILITIES - OTHER THAN BUILDING Structural, electrical, mechanical repairs, reroofing, painting Buildings 236, 540, M-139, S-160, S-165, S-247, S-250, S-352, S-461, S-557, S-770, S-772, S-773, S-774, S-850, S-877, S-942, SK-5A, SK-11A, SM-180, SM-262, SBB-217, SFC-700, SRR-19A, SRR-64, SRR-65, SRR-66, SRR-245, STC-299, StC-367, STC-644, STC-1204, STC-1205, STC-1206, STC-1213, STC-1219, STC-1222, STC-1223, STC-1226, STP-454, SVL-128, SVL-142, SVL-175, SVL-177, SVL-180 | 179 | 1 | 90.5 | | 6 | 10 |
| INTERIOR PAINT, FC-260 | 211 | 1 | 1.4 | | 1 | 11 |
| MAINTENANCE - SHIPS, SPARES Structural repairs, reroofing, painting, Buildings A-2 and A-3 | 213 | 1 | 28.1 | | 4 | 12 |
| MAINTENANCE - TANK, AUTOMOTIVE Structural, electrical, mechanical repairs, reroofing, painting Buildings 739, 746, 901, 908, 913, 1018, 1205, 1206, 1405, 1406, 1502, 1503, 1504, 1505, 1506, 1604, 1605, 1607, 1711, 1739, 1750, 1755, 1760, 1809, 1815, 1817, 1820, 1822, 1823, 1827, 1828, 1832, 1841, A-11, S-921, S-925, S-929, S-937, S-938, S-1050, S-1123, S-1213, S-1416, S-1418, S-1507, S-1616, S-1729, S-1758, S-1805, S-1807, FC-100, GP-1, GP-21, SA-26, SA-29, SH-13, SM-258, TC-474, TC-771, TC-773, TC-774, TC-864, TC-942, TC-952, SBB-169, SFC-205, SGP-15, SRR-80, STC-777, SGP-17 | 214 | 1 | 345.6 | | 5 | 13 |
| MAINTENANCE - WEAPONS, SPARES Structural repairs, Building 1780 | 215 | 1 | 1.0 | | 2 | 14 |



BMAR REPORT AND PROJECTS PLAN (BACKLOG OF MAINTENANCE AND REPAIR)

| | | | | |
|------------------------------------------------------------------|---------------------------------|------------------------------------|-------------------------------------|------------------------------------|
| 1. ACTIVITY Marine Corps Base Camp Lejeune, North Carolina | 2. CURRENT PROJECTED <u> X </u> | 3. LESS HOUSING HOUSING <u> X </u> | 4. FOR PERIOD ENDING 30 Sep 1980 | 5. SHEET <u> 3 </u> OF <u> 14 </u> |
|------------------------------------------------------------------|---------------------------------|------------------------------------|-------------------------------------|------------------------------------|

| DESCRIPTION | CATEGORY CODE | DEFI- CIENCY CODE | UNFUNDED COST | VALI- DATION RATING | NUMBER OF PREVIOUS SUMMARIES | LINE NO. |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-------------------|---------------|---------------------|------------------------------|----------|
| MAINTENANCE - ELECTRONICS/COMMUNICATIONS Structural repairs, reroofing, painting, Buildings 134, 234, 307, 329, 439, 442, 444, 505, 532, 599, 816, 1309, 1602, 1603 and 1707 | 217 | 1 | 97.5 | | 9 | 15 |
| MAINTENANCE - FACILITIES, MISCELLANEOUS ITEMS/EQUIPMENT Structural, electrical, mechanical repairs, reroofing, painting, Buildings 902, 910, 1022, 1310, 1804, 1808, 1842, A-13, S-1215, BB-51, FC-200 | 218 | 1 | 80.8 | | 8 | 16 |
| MAINTENANCE - PUBLIC WORKS REPAIR AND OPERATIONS Structural, electrical, mechanical repairs, reroofing, painting Buildings 42, 45, 559, 780, 866, 940, 1102, 1105, 1114, 1302, 1304, 1919, 1966, M-103, S-1051, PT-37, RR-13, TC-823, TC-825, TC-832, TT-49, STT-50 | 219 | 1 | 46.3 | | 9 | 17 |
| PRODUCTION - MAINTENANCE - REPAIR AND OPERATIONS OF INSTALLATION Structural repairs, painting, Buildings 80, 1111, 1115 | 229 | 1 | 2.0 | | 6 | 18 |
| RESEARCH - DEVELOPMENT, TEST AND EVALUATION Electrical repairs, reroofing, painting, Building 813 | 310 | 1 | 2.4 | | 10 | 19 |
| AMMUNITION STORAGE DEPOT AND INSTALLATION Structural repairs, reroofing, painting, Buildings FAD-6, FAD-7, FAD-8, FAD-9, FAD-10, FAD-11, FAD-12, FAD-13, FAD-14, FAD-15, FAD-16, FAD-17, SHE-1, SHE-2, SHE-3, SHE-4, SHE-5, SHE-6, SHE-7, SHE-8, SHE-9, SHE-10, SHE-11, SRR-241, SRR-242, SSA-2, SSH-4, SSH-5, SSH-6, STC-130, SVL-14, SVL-16, SVL-17, SVL-18, SVL-19, SVL-20, SVL-21, SVL-22 | 421 | 1 | 51.2 | | 11 | 20 |
| GENERAL SUPPLY STORAGE/SUPPLY OPERATIONS BUILDINGS Structural, electrical, mechanical, reroofing, painting Buildings 11, 25A, 100, 107, 116, 130, 131, 132, 200, 206, 210, 215, 231, 232, 303, 310, 319, 332, 334, 341, 428, 431, 432, 434, 435, 436, 441, 445, 504, 509, 528, 534, 548, 571, 702, 729, 738, M-259, M-301, M-314, M-319, M-380, M-408, M-501, M-506, M-512, S-869, S-870, S-893, S-932, S-1124, TC-722, TC-760, TC-762, TC-820, TC-821 | | | | | | |



BMAR REPORT AND PROJECTS PLAN (BACKLOG OF MAINTENANCE AND REPAIR)

| | | | | |
|---------------------------------------------------------------|------------------------------------------|---------------------------------------------|----------------------------------------|---------------------|
| 1. ACTIVITY Marine Corps Base Camp Lejeune, North Carolina | 2. CURRENT <u> X </u> PROJECTED _____ | 3. LESS HOUSING <u> X </u> HOUSING _____ | 4. FOR PERIOD ENDING 30 Sep 1980 | 5. SHEET 4 OF 14 |
|---------------------------------------------------------------|------------------------------------------|---------------------------------------------|----------------------------------------|---------------------|

| DESCRIPTION | CATEGORY CODE | DEFI- CIENCY CODE | UNFUNDED COST | VALI- DATION RATING | NUMBER OF PREVIOUS SUMMARIES | LINE NO. |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------|-------------------------|------------------|---------------------------|------------------------------------|-------------|
| 747, 752B, 801, 853, 899, 903, 904, 905, 906, 907, 909, 914, 915, 916, 926, 927, 928, 943, 1011, 1012, 1013, 1014, 1052, 1053, 1101, 1108, 1116, 1117, 1118, 1201, 1203, 1211, 1212, 1301, 1303, 1305, 1311, 1312, 1316, 1317, 1401, 1501, 1606, 1703, 1704, 1705, 1710, 1737, 1757, 1800, 1801, 1802, 1810, 1812, 1816, 1819, 1824, 1826, 1829, 1831, 1833, 1835, 1847, 1903, 1932, 1999, 2629, A-1, A-8, A-9, A-10, A-12, A-14, A-37, M-184, BB-31, BB-83, BB-88, BB-137, BB-189, BB-224, BB-225, BB-228, BB-231, BB-232, ES-139, FC-101, FC-102, FC-206, FC-207, FC-208, GP-12, PT-4, PT-6, PT-36, PT-42, RR-14, RR-19, RR-30, RR-33, RR-36, RR-48, RR-50, RR-62, RR-238, TC-98, TC-309, TC-322, TC-341, TC-342, TC-460, TC-462, TC-470, TC-473, TC-608, TC-611, TC-628, TC-630, TC-822, TC-723, TC-724, TC-725, TC-835, TC-860, TC-940, TC-1049, TC-1051, TC-1053, TC-1055, TC-1057, TP-448, VL-25, VL-141, VL-169, FAD-3, SBB-140, SBB-170, SBB-213, SBB-238, STC-346, STC-629, US0-2 | 441 | 1 | 663.8 | | 7 | 21 |
| LABORATORIES AND CLINICS Structural, mechanical repairs and painting; Buildings 36, 65, TT-2451 | 530 | 1 | 13.0 | | 6 | 22 |
| DENTAL CLINICS Electrical repairs - Building 460 | 540 | 1 | 1.1 | | 0 | 23 |
| DISPENSARIES Structural, electrical, mechanical repairs, painting, buildings 15, 119, 221, 324, 421, 520, G-540, G-550, G-770, BB-10, FC-313 | 550 | 1 | 54.0 | | 9 | 24 |
| ADMINISTRATIVE BUILDINGS Structural, electrical, mechanical repairs, reroofing, painting Buildings 1, 2, 3B, 7, 13, 14, 27, 33, 50, 59, 61, 66, 101, 102, 111, 114, 117, 121, 123, 127, 207, 214, 216, 219, 223, 248, 302, 304, 311, 314, 315, 317, 320, 331, 333, 336, 339, 340, 342, 400, 416, 419, 423, 429, 430, 437, 438, 501, 516, 518, 522, 526, 535, 536, 537, 800, 827, 854, 1005, 1020, 1021, 1100, 1403, 1404, 1407, 1409, 1410, 1509, 1811, 1944, G-520, G-530, M-105, M-144, M-200, M-401, M-402, M-414, M-418, M-521, M-603, M-606, BB-5, | | | | | | |



BMAR REPORT AND PROJECTS PLAN (BACKLOG OF MAINTENANCE AND REPAIR)

| | | | | |
|-------------------------------------------------------------------|--------------------------------------------------------|-----------------------------------------------------------|----------------------------------------|---------------------|
| 1. ACTIVITY Marine Corps Base, Camp Lejeune, North Carolina | 2. CURRENT <u> X </u> PROJECTED <u> </u> | 3. LESS HOUSING <u> X </u> HOUSING <u> </u> | 4. FOR PERIOD ENDING 30 Sep 1980 | 5. SHEET 5 OF 14 |
|-------------------------------------------------------------------|--------------------------------------------------------|-----------------------------------------------------------|----------------------------------------|---------------------|

| DESCRIPTION | CATEGORY CODE | DEFI- CIENCY CODE | UNFUNDED COST | VALI- DATION RATING | NUMBER OF PREVIOUS SUMMARIES | LINE NO. |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-------------------|---------------|---------------------|------------------------------|----------|
| BB-28, BB-38, BB-86, BB-208, CG-1, FC-201, FC-300, FC-400, RR-11, RR-12, RR-17, RR-20, RR-22, RR-24, TC-704, TC-840, TC-845, TC-854, TC-1056, TC-1061, TC-1063, TC-1110, TT-42, LCH-4002, LCH-4014E | 610 | 1 | 454.0 | | 8 | 25 |
| OTHER ADMINISTRATIVE FACILITIES Structural repairs and paint - Buildings S-355, SBB-28A, SFC-319, STC-307A | 690 | 1 | .3 | | 0 | 26 |
| TROOP HOUSING - BACHELOR EM BARRACKS Structural, electrical, mechanical repairs, reroofing, painting Buildings 6, 8, 10, 12, 58, 60, 67, 202, 204, 205, 208, 209, 212, 213, 217, 220, 224, 227, 308, 309, 312, 313, 316, 318, 321, 323, 327, 404, 406, 407, 409, 410, 412, 415, 417, 420, 422, 426, 427, 502, 503, 506, 507, 510, 511, 514, 517, 519, 523, 527, 1042, G-521, G-522, G-523, G-523, G-531, G-532, G-533, G-534, G-541, G-542, G-543, G-544, G-551, G-552, G-553, G-554, M-128, M-130, M-211, M-217, M-221, M-222, M-226, M-227, M-228, M-229, M-234, M-235, M-236, M-303, M-305, M-309, M-311, M-316, M-318, M-416, M-503, M-504, M-507, M-509, M-511, M-514, M-516, M-518, M-522, M-604, M-607, BB-250, BB-255, FC-304, FC-305, FC-306, FC-309, FC-310, FC-311, M-614, M-621, BA-105, BB-11, BB-12, BB-13, BB-14, FC-311, FC-411, FC-412, FC-413, FC-414, FC-415, FC-416, HP-51, HP-53, HP-55, HP-301, RR-1, RR-2, RR-4, RR-5, TC-804, TC-808, TC-1004, TC-1009, TC-1064, TC-1065 | 721 | 1 | 1555.4 | | 3 | 27 |
| BACHELOR HOUSING - MESS FACILITIES Structural, electrical, mechanical repairs, painting, Buildings 9, 106, 122, 211, 226, 325, 411, 424, 508, 512, 521, 1209, G-640, M-424, BB-7, FC-303, FC-420 | 722 | 1 | 88.3 | | 6 | 28 |
| BACHELOR - HOUSING - DETACHED FACILITIES Structural, electrical, mechanical repairs, reroofing, painting Buildings 30, 550, 572, 821, 924, 1814, M-205, M-206, M-208, M-209, M-315, M-502, M-619, BB-151, GP-14, RR-26, RR-27, RR-28, | | | | | | |



BMAR REPORT AND PROJECTS PLAN (BACKLOG OF MAINTENANCE AND REPAIR)

| | | | | |
|------------------------------------------------------------------|-----------------------------------|--------------------------------------|-------------------------------------|----------------------------------------|
| 1. ACTIVITY Marine Corps Base Camp Lejeune, North Carolina | 2. CURRENT PROJECTED <u> X </u> | 3. LESS HOUSING HOUSING <u> X </u> | 4. FOR PERIOD ENDING 30 Sep 1980 | 5. SHEET <u> 6 </u> OF <u> 14 </u> |
|------------------------------------------------------------------|-----------------------------------|--------------------------------------|-------------------------------------|----------------------------------------|

| DESCRIPTION | CATEGORY CODE | DEFI- CIENCY CODE | UNFUNDED COST | VALI- DATION RATING | NUMBER OF PREVIOUS SUMMARIES | LINE NO. |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-------------------|---------------|---------------------|------------------------------|----------|
| RR-29, RR-31, RR-32, RR-34, RR-35, RR-37, TC-810, TC-814, TC-815, TC-841, TC-842, TC-844, TC-845, TC-850, TC-851, TC-865, TC-1015, TC-1040, TC-1041, TC-1042, TC-1044, TC-1045, TC-1050, TC-1140, TC-1141, TC-812 | 723 | 1 | 75.4 | | 5 | 29 |
| BACHELOR - HOUSING - OFFICERS QUARTERS Structural, electrical, mechanical repairs, reroofing, painting Buildings 2602, 2604, 2605, 2607, 2609, 2611, 2613, 2617, RR-9, TC-1067, BB-45, TC-1068, TC-1069, TC-1160, TC-1161, TC-1162 | 724 | 1 | 79.1 | | 7 | 30 |
| COMMUNITY FACILITIES - PERSONNEL SUPPORT AND SERVICES Structural, electrical, mechanical repairs, reroofing, painting Buildings 3, 18, 235, 812, 1041, 1047, 1054, 1208, 1400, 1963, 1964, 1965, 1969, 1984, 2600, A-15, A-20, M-325, S-894, S-1851, BB-8, BB-136, CR-115, CR-117, RR-6, RR-78, SD-46, SH-8A, SH-12, TC-306, TC-701, TC-732, TC-733, TC-834, TT-57, LCH-4000, LCH-4022, SBB-230, SBB-299, SFC-321, SFC-322, SSH-10 | 730 | 1 | 78.7 | | 7 | 31 |
| COMMUNITY FACILITIES - MORALE, WELFARE AND RECREATION - INTERIOR Structural, electrical, mechanical repairs, reroofing, painting Buildings 4, 31, 37, 41, 43, 62, 63, 64, 84, 89, 115, 125, 129, 145, 225, 225A, 251, 253, 300, 322, 322A, 403, 425, 500, 524, 712, 728, 826, 895, 897, 898, 1010, 1015, 1103, 1106, 1107, 1113, 1120, 1200, 1207, 1413, 1610, 1611, 1612, 1613, 1614, 1615, 1728, 1765, 1770, 1909, 1915, 1945, 1985, 1987, 2601, 2603, 2615, 2624, 2625, 2626, 2627, 2628, A-25, E-1, G-560, M-129, M-134, M-171, M-602, BB-3, BB-16, BB-30, BB-36, BB-46, S-1972, S-1973, S-1981, BB-2, BB-54, BB-177, BB-210, CG-505, FC-318, GP-10, PT-30, RR-10, RR-49, RR-51, RR-72, SA-28, TC-614, TC-900, TC-910, TC-775, TC-830, TC-833, TC-1062, TT-44, TT-2453, TT-2455, TT-2457, TT-2477, LCH-4014, LCH-4014A, LCH-4014D, LCH-4015, SBB-94, SBB-229, USO-1 TT-2467 | 740 | 1 | 511.9 | | 7 | 32 |
| COMMUNITY FACILITIES - MORALE, WELFARE AND RECREATION, EXTERIOR Structural repairs, reroofing, painting, Buildings S-90, S-162, S-446, S-541, S-1718, S-1726, S-1734, S-1940, S-1970, S-1977, | | | | | | |



BMAR REPORT AND PROJECTS PLAN (BACKLOG OF MAINTENANCE AND REPAIR)

| | | | | | |
|-------------|----------------------------------------------------|-----------------------------------|--------------------------------------|-------------------------------------|--------------------------------------|
| 1. ACTIVITY | Marine Corps Base, Camp Lejeune, North Carolina | 2. CURRENT PROJECTED <u> X </u> | 3. LESS HOUSING HOUSING <u> X </u> | 4. FOR PERIOD ENDING 30 Sep 1980 | 5. SHEET <u> 7 </u> OF <u> 14 </u> |
|-------------|----------------------------------------------------|-----------------------------------|--------------------------------------|-------------------------------------|--------------------------------------|

| DESCRIPTION | CATEGORY CODE | DEFI- CIENCY CODE | UNFUNDED COST | VALI- DATION RATING | NUMBER OF PREVIOUS SUMMARIES | LINE NO. |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-------------------|---------------|---------------------|------------------------------|----------|
| SM-189, SM-265, SBB-59, SBB-60, SRR-57, SRR-101, STC-856, STC-866, SRR-58 | 750 | 1 | 33.3 | | 5 | 33 |
| ELECTRIC POWER, SOURCE Structural repairs, reroofing, painting, Buildings 353, BB-193, FC-209, SFC-106 | 811 | 1 | 5.2 | | 3 | 34 |
| ELECTRIC POWER - TRANSMISSION AND DISTRIBUTION LINES Structural repairs, reroofing, painting, Building 884 | 812 | 1 | .1 | | 5 | 35 |
| HEAT - STEAM - SOURCE Structural repairs, reroofing, painting, Buildings 779, 1700, M-170, M-230, M-625, BB-9, RR-15, G-650, S-781, S-1009, FC-202, | 821 | 1 | 70.9 | | 11 | 36 |
| EXTERIOR PAINT - Building M-237 | 822 | 1 | 1.4 | | 1 | 37 |
| HEAT - GAS, SOURCE Structural repairs, reroofing, painting, Buildings 803, 804, S-888, S-889, S-890, S-891 | 823 | 1 | 3.5 | | 3 | 38 |
| SEWAGE AND INDUSTRIAL WASTE, TREATMENT AND DISPOSAL Structural repairs, reroofing, painting, Buildings 22, 32, 683, 765, M-137, S-717, S-764, RR-38, TC-563, TT-35, SBB-67, SRR-67, SRR-93, STC-636, STC-637 | 831 | 1 | 22.2 | | 8 | 39 |
| SEWAGE AND INDUSTRIAL WASTE COLLECTION Structural repairs, reroofing, painting, Buildings RR-52, TT-36, STT-32, STT-34, 680, S-47, S-47A, S-2633, FC-203 | 832 | 1 | 6.9 | | 8 | 40 |
| REFUSE - GARBAGE Structural repairs, reroofing, painting, Buildings M-256, M-426, FC-19 | 833 | 1 | 2.0 | | 3 | 41 |



BMAR REPORT AND PROJECTS PLAN (BACKLOG OF MAINTENANCE AND REPAIR)

1. ACTIVITY Marine Corps Base
Camp Lejeune, North Carolina

2. CURRENT X
PROJECTED

3. LESS HOUSING X
HOUSING

4. FOR PERIOD
ENDING
30 Sep 1980

5. SHEET
8 OF 14

| DESCRIPTION | CATEGORY CODE | DEFI- CIENCY CODE | UNFUNDED COST | VALI- DATION RATING | NUMBER OF PREVIOUS SUMMITTES | LINE NO. |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-------------------|---------------|---------------------|------------------------------|----------|
| POTABLE WATER SUPPLY, TREATMENT AND STORAGE Structural repairs, reroofing, painting, Buildings 38, 601, 602, 603, 606, 608, 609, 610, 611, 612, 613, 614, 615, 616, 620, 621, 625, 626, 630, 633, 634, 635, 636, 762, A-5, M-142, M-243, BB-43, BB-44, BB-190, RR-45, RR-47, TC-100, TC-104, TC-202, TC-604, TC-901, TC-1000, TC-1001, TT-26, TT-31, TT-38, TT-52, TT-53, STC-503, STC-1251, STC-1254, STC-1255, STC-1256 | 841 | 1 | 71.0 | | 10 | 42 |
| WATER DISTRIBUTION SYSTEM POTABLE Structural repairs, reroofing, painting, Buildings 741, 742, A-4, D-39, S-5263, S-5781, TC-501, LCH-4006, LCH-4007, STT-39A | 842 | 1 | 2.0 | | 6 | 43 |
| ROADS AND VEHICULAR STRUCTURES Structural repairs, painting, Structures STC-1220, SVL-126, S-750, S-787, S-788, S-852, S-864, S-865, S-872, S-885, S-1007, S-1959 | 851 | 1 | 27.2 | | 3 | 44 |
| SIDEWALKS AND OTHER PAVEMENTS Repairs, S-455 and S-555 | 852 | 1 | 1.4 | | 0 | 45 |
| FENCING Repairs, S-1048 and S-1049 | 872 | 1 | 2.9 | | 0 | 46 |
| MISCELLANEOUS FACILITIES Structural, electrical, mechanical repairs, reroofing, painting Buildings 1702, 1414, S-94, S-96, S-1210, S-1415 | 890 | 1 | 4.9 | | 2 | 47 |



BMAR REPORT AND PROJECTS PLAN (BACKLOG OF MAINTENANCE AND REPAIR)

| | | | | |
|---------------------------------------------------------------|-----------------------------------|--------------------------------------|-------------------------------------|--------------------------------------|
| 1. ACTIVITY Marine Corps Base Camp Lejeune, North Carolina | 2. CURRENT PROJECTED <u> X </u> | 3. LESS HOUSING HOUSING <u> X </u> | 4. FOR PERIOD ENDING 30 Sep 1980 | 5. SHEET <u> 9 </u> OF <u> 14 </u> |
|---------------------------------------------------------------|-----------------------------------|--------------------------------------|-------------------------------------|--------------------------------------|

| DESCRIPTION | CATEGORY CODE | DEFI- CIENCY CODE | UNFUNDED COST | VALI- DATION RATING | NUMBER OF PREVIOUS SUMMARIES | LINE NO. |
|--------------------------------------------------------|---------------|-------------------|---------------|---------------------|------------------------------|----------|
| CODE II | | | | | | |
| REPAIR PETROLEUM FACILITIES | 123 | 2 | 557.3 | | 0 | 48 |
| REPLACE AERIAL CABLE 216 FROM R-1 TO RP-2 (LE106M) | 135 | 2 | 100.5 | | 1 | 49 |
| REPAIR STREAM CROSSINGS, TANK TRAILS | 179 | 2 | 260.0 | | 0 | 50 |
| STRUCTURAL, MECHANICAL REPAIRS, Building 1300 (LE029M) | 431 | 2 | 106.0 | | 4 | 51 |
| REPAIR VENTILATION SYSTEMS, Buildings BB-250, BB-255 | 721 | 2 | 51.0 | | 0 | 52 |
| REPLACE ROOF, Building 1500 (LE115M) | 730 | 2 | 121.5 | | 1 | 53 |
| REPLACE GYM FLOOR, Building 115 | 740 | 2 | 35.8 | | 1 | 54 |
| REPLACE GYM FLOOR, Building 300 | 740 | 2 | 35.8 | | 1 | 55 |
| REPLACE GYM FLOOR, BUILDING 401 | 740 | 2 | 35.8 | | 1 | 56 |
| REPLACE GYM FLOOR, BUILDING 500 | 740 | 2 | 35.8 | | 1 | 57 |
| REPLACE GYM FLOOR, BUILDING BB-2 | 740 | 2 | 35.8 | | 1 | 58 |
| REPLACE GYM FLOOR, BUILDING RR-8 | 740 | 2 | 35.8 | | 1 | 59 |
| STRUCTURAL REPAIRS, REROOF, Building 751 | 740 | 2 | 71.0 | | 0 | 60 |
| REPAIRS TO MARINA, Building 31 | 740 | 2 | 84.0 | | 0 | 61 |
| REPAIRS TO THEATER, Building TC-900 | 740 | 2 | 55.0 | | 0 | 62 |
| REPAIRS TO BUILDING 1006 | 740 | 2 | 90.5 | | 0 | 63 |
| REPLACE STEAM VALVES, Building 1700 | 821 | 2 | 90.0 | | 0 | 64 |



BMAR REPORT AND PROJECTS PLAN (BACKLOG OF MAINTENANCE AND REPAIR)

| | | | | |
|------------------------------------------------------------------|----------------------------------------|-------------------------------------------|----------------------------------------|----------------------|
| 1. ACTIVITY Marine Corps Base Camp Lejeune, North Carolina | 2. CURRENT <u>X</u> PROJECTED _____ | 3. LESS HOUSING <u>X</u> HOUSING _____ | 4. FOR PERIOD ENDING 30 Sep 1980 | 5. SHEET 10 OF 14 |
|------------------------------------------------------------------|----------------------------------------|-------------------------------------------|----------------------------------------|----------------------|

| DESCRIPTION | CATEGORY CODE | DEFI- CIENCY CODE | UNFUNDED COST | VALI- DATION RATING | NUMBER OF PREVIOUS SUMMARIES | LINE NO. |
|------------------------------------------------------------------------------------------|------------------|-------------------------|------------------|---------------------------|------------------------------------|-------------|
| REPLACE BOILER NUMBER 55, Building BB-9 | 821 | 2 | 200.0 | | 0 | 65 |
| REPLACE BOILER NUMBER 46, Building RR-15 | 821 | 2 | 200.0 | | 0 | 66 |
| REPLACE BOILER NUMBER 47, Building RR-15 | 821 | 2 | 200.0 | | 0 | 67 |
| REPLACE BOILER NUMBER 10, Building 2615 | 821 | 2 | 200.0 | | 0 | 68 |
| REPLACE ELECTRIC SERVICE, TRANSFORMERS AND SWITCH EQUIPMENT Building 1700 (LE008M) | 821 | 2 | 530.0 | | 4 | 69 |
| REPLACE CASING - BOILER NUMBER 5, Building 1700 | 821 | 2 | 52.7 | | 1 | 70 |
| REPLACE BOILER NUMBER 9, Building 2615 (LE012M) | 821 | 2 | 116.3 | | 2 | 71 |
| REPLACE BURNER EYE AND FRONT WALL REFRACTORY, BOILERS 1,2,3,4, Building 1700 (LE101M) | 821 | 2 | 120.0 | | 1 | 72 |
| REPLACE ROOF, MISCELLANEOUS REPAIRS, Building G-650 (LE102M) | 821 | 2 | 62.5 | | 1 | 73 |
| REPLACE CONDENSATE TANK (INCLUDE CONDENSATE POLISHERS) Building 1708 (LE107M) | 821 | 2 | 167.2 | | 1 | 74 |
| REPLACE CONDENSATE LINES, INDUSTRIAL AREA (LE017M) | 822 | 2 | 832.2 | | 4 | 75 |
| REINSULATE STEAM LINES, INDUSTRIAL AREA (LE108M) | 822 | 2 | 110.9 | | 1 | 76 |
| REPLACE CONDENSATE LINES, CAMP JOHNSON (LE028M) | 822 | 2 | 175.3 | | 2 | 77 |
| REPLACE UNDERGROUND CONDENSATE LINE, MH-159 TO MH-S-11 (LE011M) | 822 | 2 | 499.9 | | 4 | 78 |
| REPLACE CONDENSATE LINE FROM S-11 TO BUILDING 1700 (LE016M) | 822 | 2 | 205.4 | | 2 | 79 |
| REPLACE STEAM AND CONDENSATE LINES, RIFLE RANGE (LE010M) | 822 | 2 | 234.0 | | 4 | 80 |



BMAR REPORT AND PROJECTS PLAN (BACKLOG OF MAINTENANCE AND REPAIR)

| | | | | |
|------------------------------------------------------------------|-----------------------------------|--------------------------------------|-------------------------------------|----------------------|
| 1. ACTIVITY Marine Corps Base Camp Lejeune, North Carolina | 2. CURRENT PROJECTED <u> x </u> | 3. LESS HOUSING HOUSING <u> x </u> | 4. FOR PERIOD ENDING 30 Sep 1980 | 5. SHEET 11 OF 14 |
|------------------------------------------------------------------|-----------------------------------|--------------------------------------|-------------------------------------|----------------------|

| DESCRIPTION | CATEGORY CODE | DEFI- CIENCY CODE | UNFUNDED COST | VALI- DATION RATING | NUMBER OF PREVIOUS SUMMARIES | LINE NO. |
|----------------------------------------------------------------------------------------|---------------|-------------------|---------------|---------------------|------------------------------|----------|
| REPLACE 25" COMMUNUTORS IN INFLUENT LINE, SEWAGE PLANT, Building 22 (LE109M) | 831 | 2 | 33.0 | | 1 | 81 |
| REPLACE MECHANICAL EQUIPMENT AND TANKS, Buildings 22, TT-35 | 831 | 2 | 120.0 | | 0 | 82 |
| REPLACE LIFT STATION, Building TT-35 | 831 | 2 | 115.0 | | 0 | 83 |
| REPLACE CHLORINE CONTACT CHAMBER, Building 683 | 831 | 2 | 50.0 | | 0 | 84 |
| REPLACE LIME MIXING EQUIPMENT AND TANKS, Building TT-38 (LE110M) | 841 | 2 | 226.4 | | 6 | 85 |
| REPLACE WATER WELLS, Buildings 611, 614, 621, 627, 638, 639, RR-227, LCH-4006 (LE103M) | 841 | 2 | 640.0 | | 1 | 86 |
| REPLACE SPIRACTORS AND PIPING, Building 20 | 841 | 2 | 400.0 | | 8 | 87 |
| REPLACE WATER WELLS, Buildings 601, 610, M-168, BB-43 | 841 | 2 | 200.0 | | 0 | 88 |
| REPAIR WATER FILTERS AND EQUIPMENT, Building RR-85 | 841 | 2 | 75.0 | | 0 | 89 |
| REPAIR SIDEWALKS, BASEWIDE (LE111M) | 851 | 2 | 199.1 | | 9 | 90 |
| REPAIR DRIVEWAYS, DINING FACILITIES (12 BUILDINGS) | 851 | 2 | 135.0 | | 0 | 91 |
| REPAIR SIDEWALKS, CAMP GEIGER | 851 | 2 | 164.0 | | 0 | 92 |
| REPAIR PARKING LOTS, VARIOUS LOCATIONS, BASEWIDE (LE112M) | 851 | 2 | 819.8 | | 9 | 93 |
| REPAIRS TO SECURITY FENCES, BASEWIDE (LE114M) | 872 | 2 | 291.7 | | 5 | 94 |
| REPLACE STEAM FLOW RECORDERS, Building 1700 (LE015M) | 821 | 2 | 50.6 | | 2 | 95 |



BMAR REPORT AND PROJECTS PLAN (BACKLOG OF MAINTENANCE AND REPAIR)

1. ACTIVITY Marine Corps Base,
Camp Lejeune, North Carolina


2. CURRENT x
PROJECTED

3. LESS HOUSING x
HOUSING

4. FOR PERIOD
ENDING
30 Sep 1980

5. SHEET
12 OF 14

| DESCRIPTION | CATEGORY CODE | DEFI- CIENCY CODE | UNFUNDED COST | VALI- DATION RATING | NUMBER OF PREVIOUS SUMMARIES | LINE NO. |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-------------------|---------------|---------------------|------------------------------|----------|
| CODE III | | | | | | |
| HELICOPTER LANDING PAD, Buildings SLZ-7 and SLZ-14 | 111 | 3 | .4 | | 1 | 96 |
| TRAINING BUILDING, RR-70 | 171 | 3 | .3 | | 1 | 97 |
| TRAINING FACILITIES OTHER THAN BUILDINGS, SOC-1C, SOC-21C, ST-10, SPT-34, STC-1204, STC-1205, STC-1206, STC-1223, STC-1224, SVL-130, SVL-178, SRR-250, TFM-107, TFM-118, RNGK-206, RNGK-209, RNGM-013, RNGM-109, RNGM-122, RNGM-207 | 179 | 3 | 7.5 | | 1 | 98 |
| MAINTENANCE - TANK, AUTOMOTIVE SGP-16 SM-258 | 214 | 3 | 2.0 | | 1 | 99 |
| MAINTENANCE - PUBLIC WORKS REPAIR AND OPERATIONS, TC-365 | 219 | 3 | .8 | | 1 | 100 |
| GENERAL SUPPLY STORAGE/OPERATIONS, Buildings 1848, 1986, CG-23, GP-6, TC-471 | 441 | 3 | 5.5 | | 1 | 101 |
| BACHELOR HOUSING - DETACHED FACILITIES SVL-158, SVL-159, SVL-163.. | 723 | 3 | .9 | | 1 | 102 |
| COMMUNITY FACILITIES - MORALE, WELFARE AND RECREATION TC-343 | 740 | 3 | .5 | | 1 | 103 |
| COMMUNITY FACILITIES - MORALE, WELFARE AND RECREATION, EXTERIOR SCG-27, SD-43 | 750 | 3 | 1.0 | | 1 | 104 |
| HEAT, SOURCE D-24 | 821 | 3 | .8 | | 1 | 105 |
| SEWAGE AND INDUSTRIAL WASTE - COLLECTION CG-22 | 832 | 3 | .8 | | 1 | 106 |



BMAR REPORT AND PROJECTS PLAN (BACKLOG OF MAINTENANCE AND REPAIR)

| | | | | |
|-------------------------------------------------------------------|----------------------------------------------------|-------------------------------------------------------|----------------------------------------|----------------------|
| 1. ACTIVITY Marine Corps Base, Camp Lejeune, North Carolina | 2. CURRENT <u> X </u> PROJECTED <u> </u> | 3. LESS HOUSING <u> X </u> HOUSING <u> </u> | 4. FOR PERIOD ENDING 30 Sep 1980 | 5. SHEET 13 OF 14 |
|-------------------------------------------------------------------|----------------------------------------------------|-------------------------------------------------------|----------------------------------------|----------------------|

| DESCRIPTION | CATEGORY CODE | DEFI- CIENCY CODE | UNFUNDED COST | VALI- DATION RATING | NUMBER OF PREVIOUS SUMMARIES | LINE NO. |
|-------------------------------------------------|------------------|-------------------------|------------------|---------------------------|------------------------------------|-------------|
| <u>PROJECTS PLANS (FY-81)</u> | | | | | | |
| REROOF BUILDING 1202 (LE104M) | 219 | 2 | 127.7 | | 1 | 1 |
| REROOF BUILDING 1200 (LE116M) | 740 | 2 | 132.1 | | 1 | 2 |
| <u>PROJECTS PLANS (FY-83)</u> | | | | | | |
| RETUBE BOILER NUMBER 85, Building G-650 | 821 | 2 | 65.4 | | 0 | 1 |
| RETUBE BOILERS NUMBER 83 AND 84, Building G-650 | 821 | 2 | 130.8 | | 0 | 2 |
| REPAIR RAILROAD SYSTEM | 860 | 2 | 500.0 | | 0 | 3 |



BMAR REPORT AND PROJECTS PLAN (BACKLOG OF MAINTENANCE AND REPAIR)

1. ACTIVITY Marine Corps Base,
Camp Lejeune, North Carolina


2. CURRENT X
PROJECTED _____

3. LESS HOUSING X
HOUSING _____

4. FOR PERIOD
ENDING
30 Sep 1980

5. SHEET
 14 OF 14

| DESCRIPTION | CATEGORY CODE | DEFI- CIENCY CODE | UNFUNDED COST | VALI- DATION RATING | NUMBER OF PREVIOUS SUMMARIES | LINE NO. |
|--------------------------------------|------------------|-------------------------|------------------|---------------------------|------------------------------------|-------------|
| <u>MARINE CORPS BASE FY-80 BEMAR</u> | | | | | | |
| CODE I \$ 4,876,100 | | | | | | |
| CODE II \$ 9,227,600 | | | | | | |
| CODE III \$ 20,500 | | | | | | |
| Total \$14,049,200 | | | | | | |
| FY-81 Projects Plan 259,800 | | | | | | |
| FY-83 Projects Plan 696,200 | | | | | | |



BMAR REPORT AND PROJECTS PLAN
MARINE CORPS AIR STATION (HELICOPTER)
NEW RIVER, NORTH CAROLINA
FY-80



BMAR REPORT AND PROJECTS PLAN (BACKLOG OF MAINTENANCE AND REPAIR)

1. ACTIVITY Marine Corps Air Station (H)
New River, North Carolina


2. CURRENT X
PROJECTED

3. LESS HOUSING X
HOUSING

4. FOR PERIOD
ENDING
30 Sep 1980

5. SHEET
 1 OF 7

| DESCRIPTION | CATEGORY CODE | DEFI- CIENCY CODE | UNFUNDED COST | VALI- DATION RATING | NUMBER OF PREVIOUS SUMMARIES | LINE NO. |
|---------------------------------------------------------------------------------------------|---------------|-------------------|---------------|---------------------|------------------------------|----------|
| CODE I | | | | | | |
| AIRFIELD PAVEMENTS, OTHER Structural, mechanical repairs, paint AS-513, AS-900 | 116 | 1 | 9.5 | | 2 | 1 |
| AIRFIELD FUELING/DISPENSING FACILITY Mechanical repairs, AS-145 | 121 | 1 | 1.6 | | 2 | 2 |
| MARINE FUEL DISPENSING Electrical repairs, AS-2804 | 122 | 1 | .4 | | 2 | 3 |
| LAND VEHICLE FUELING/DISPENSING FACILITIES Interior paint, AS-143 | 123 | 1 | .6 | | 8 | 4 |
| OPERATING FUEL STORAGE Structural repairs, AS-141 | 124 | 1 | .4 | | 2 | 5 |
| POL PIPELINE Structural repairs, paint AS-144, AS-509, AS-4155 | 125 | 1 | .7 | | 8 | 6 |
| COMMUNICATIONS BUILDINGS Roof replacement, interior paint AS-224 | 131 | 1 | 1.2 | | 6 | 7 |
| NAVIGATION AND TRAFFIC AIDS BUILDINGS Structural repairs, paint AS-805, AS-3000, AS-3620 | 133 | 1 | 3.7 | | 6 | 8 |
| NAVIGATION AND TRAFFIC AIDS - OTHER THAN BUILDINGS Repair and paint, AS-3602, AS-3604 | 134 | 1 | .6 | | 0 | 9 |
| OPERATIONAL BUILDINGS Structural, mechanical repairs, paint AS-502, AS-571, AS-843 | 141 | 1 | 20.2 | | 6 | 10 |
| STRUCTURAL REPAIRS AS-2802 | 154 | 1 | 4.1 | | 1 | 11 |
| SMALL CRAFT BERTHING Structural repairs, AS-846 | 155 | 1 | 1.7 | | 3 | 12 |



BMAR REPORT AND PROJECTS PLAN (BACKLOG OF MAINTENANCE AND REPAIR)

| | | | | |
|--------------------------------------------------------------------------|-----------------------------------|--------------------------------------|-------------------------------------|---------------------------------------|
| 1. ACTIVITY Marine Corps Air Station (H) New River, North Carolina | 2. CURRENT PROJECTED <u> X </u> | 3. LESS HOUSING HOUSING <u> X </u> | 4. FOR PERIOD ENDING 30 Sep 1980 | 5. SHEET <u> 2 </u> OF <u> 7 </u> |
|--------------------------------------------------------------------------|-----------------------------------|--------------------------------------|-------------------------------------|---------------------------------------|


| DESCRIPTION | CATEGORY CODE | DEFI- CIENCY CODE | UNFUNDED COST | VALI- DATION RATING | NUMBER OF PREVIOUS SUMMARIES | LINE NO. |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-------------------|---------------|---------------------|------------------------------|----------|
| MARINE IMPROVEMENTS Structural repairs, AS-720 | 164 | 1 | 1.8 | | 3 | 13 |
| TRAINING BUILDINGS Structural, electrical repairs, paint, AS-222, AS-312, AS-3515, AS-4120 | 171 | 1 | 15.8 | | 6 | 14 |
| TRAINING FACILITIES OTHER THAN BUILDINGS Structural repairs, AS-3617 | 179 | 1 | .3 | | 2 | 15 |
| MAINTENANCE AIRCRAFT SPARES Structural, electrical, mechanical repairs, reroof, paint, AS-504, AS-515, AS-518, AS-537, AS-585, AS-4100, AS-4106 | 211 | 1 | 197.3 | | 8 | 16 |
| MAINTENANCE TANK - AUTOMOTIVE Structural, electrical, mechanical repairs, reroof, paint, AS-109, AS-112, AS-113, AS-114, AS-117, AS-118, AS-119, AS-153, AS-156, AS-181, AS-3504 | 214 | 1 | 29.5 | | 7 | 17 |
| MAINTENANCE - ELECTRONIC/COMMUNICATIONS EQUIPMENT Structural, mechanical repairs, paint AS-849 | 217 | 1 | 6.5 | | 9 | 18 |
| MAINTENANCE - PROCURED ITEMS/EQUIPMENT Structural, electrical repairs, paint, AS-587 | 218 | 1 | 1.2 | | 0 | 19 |
| MAINTENANCE - PUBLIC WORKS REPAIR AND OPERATION Structural, electrical, mechanical repairs, paint AS-121, AS-122, AS-124, AS-520, AS-522 | 219 | 1 | 26.6 | | 9 | 20 |
| RESEARCH, DEVELOPMENT, TEST AND EVALUATION BUILDINGS Structural repairs, paint, AS-580 | 310 | 1 | 1.0 | | 10 | 21 |



BMAR REPORT AND PROJECTS PLAN (BACKLOG OF MAINTENANCE AND REPAIR)

| | | | | |
|-----------------------------------------------------------------------|------------------------------------------|---------------------------------------------|----------------------------------------|--------------------------------------|
| 1. ACTIVITY Marine Corps Air Station (H) New River, North Carolina | 2. CURRENT <u> X </u> PROJECTED _____ | 3. LESS HOUSING <u> X </u> HOUSING _____ | 4. FOR PERIOD ENDING 30 Sep 1980 | 5. SHEET <u> 3 </u> OF <u> 7 </u> |
|-----------------------------------------------------------------------|------------------------------------------|---------------------------------------------|----------------------------------------|--------------------------------------|

| DESCRIPTION | CATEGORY CODE | DEFI- CIENCY CODE | UNFUNDED COST | VALI- DATION RATING | NUMBER OF PREVIOUS SUMMARIES | LINE NO. |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-------------------|---------------|---------------------|------------------------------|----------|
| GENERAL SUPPLY STORAGE/SUPPLY OPERATIONS BUILDINGS Structural, electrical, mechanical repairs, reroof, paint AS-12, AS-116, AS-128, AS-130, AS-218, AS-416, AS-424, AS-516, AS-521, AS-530, AS-544, AS-572, AS-581, AS-582, AS-583, AS-584, AS-588, AS-590, AS-591, AS-600, AS-810, AS-816, AS-873, AS-3525, AS-4103, AS-4110, AS-4124, AS-4127, AS-4137 | 441 | 1 | 67.6 | | 7 | 22 |
| DISPENSARIES Structural, electrical, mechanical repairs, AS-302 | 550 | 1 | .7 | | 9 | 23 |
| ADMINISTRATIVE BUILDINGS Structural, electrical, mechanical repairs, reroof, paint AS-216, AS-217, AS-425, AS-586, AS-589, AS-804, AS-814, AS-815, AS-822, AS-3502, AS-4122 | 610 | 1 | 70.3 | | 8 | 24 |
| OTHER ADMINISTRATIVE FACILITIES Structural repairs, paint, AS-821, AS-829, AS-4123 | 690 | 1 | .5 | | 3 | 25 |
| TROOP HOUSING, BACHELOR EM BARRACKS Structural, electrical, mechanical repairs, paint AS-211, AS- 212, AS-213, AS-214, AS-215, AS-702, AS-704, AS-4010, AS-4015, AS-4020, AS-4025 | 721 | 1 | 84.0 | | 7 | 26 |
| BACHELOR HOUSING - MESS FACILITIES Structural, electrical, mechanical repairs, AS-4012 | 722 | 1 | 10.0 | | 6 | 27 |
| BACHELOR HOUSING - DETACHED FACILITIES Structural repairs, AS-6045, AS-6044 | 723 | 1 | .3 | | 3 | 28 |
| BACHELOR HOUSING - OFFICERS QUARTERS Structural repairs, AS-705 | 724 | 1 | 1.2 | | 5 | 29 |
| COMMUNITY FACILITIES - PERSONNEL SUPPORT AND SERVICES Structural repairs, paint, AS-133, AS-536, AS-2860 | 730 | 1 | 1.1 | | 6 | 30 |



BMAR REPORT AND PROJECTS PLAN (BACKLOG OF MAINTENANCE AND REPAIR)

| | | | | |
|-----------------------------------------------------------------------|----------------------------------------------------|-------------------------------------------------------|----------------------------------------|------------------------------------------|
| 1. ACTIVITY Marine Corps Air Station (H) New River, North Carolina | 2. CURRENT <u> X </u> PROJECTED <u> </u> | 3. LESS HOUSING <u> X </u> HOUSING <u> </u> | 4. FOR PERIOD ENDING 30 Sep 1980 | 5. SHEET <u> 4 </u> OF <u> 7 </u> |
|-----------------------------------------------------------------------|----------------------------------------------------|-------------------------------------------------------|----------------------------------------|------------------------------------------|

| DESCRIPTION | CATEGORY CODE | DEFI- CIENCY CODE | UNFUNDED COST | VALI- DATION RATING | NUMBER OF PREVIOUS SUMMARIES | LINE NO. |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------|-------------------------|------------------|---------------------------|------------------------------------|-------------|
| COMMUNITY FACILITIES - MORALE, WELFARE, RECREATION, INTERIOR Structural, electrical, mechanical repairs, reroof, paint AS-201, AS-205, AS-208, AS-231, AS-232, AS-233, AS-234, AS-236, AS-240, AS-299, AS-402, AS-410, AS-413, AS-414, AS-608, AS-708, AS-832, AS-901, AS-2800, AS-4126 | 740 | 1 | 85.1 | | 6 | 31 |
| COMMUNITY FACILITIES, MORALE, WELFARE, RECREATION, EXTERIOR Structural, electrical repairs, paint AS-207, AS-246, AS-252, AS-2850 | 750 | 1 | 28.3 | | 6 | 32 |
| ELECTRIC POWER - TRANSMISSION AND DISTRIBUTION LINES Structural repairs, paint AS-227, AS-311, AS-819, AS-841, AS- 3605 | 812 | 1 | 1.3 | | 5 | 33 |
| HEAT - SOURCE Structural repairs AS-703, AS-4151 | 821 | 1 | 4.7 | | 7 | 34 |
| REFRIGERATION/AIR CONDITIONING Structural, mechanical repairs AS-225 | 826 | 1 | .3 | | 2 | 35 |
| SEWAGE AND INDUSTRIAL WASTE COLLECTION Structural repairs, paint AS-850, AS-2001 | 832 | 1 | 1.7 | | 8 | 36 |
| REFUSE/GARBAGE Structural repair, paint AS-209 | 833 | 1 | .3 | | 3 | 37 |
| POTABLE WATER SUPPLY TREATMENT AND STORAGE Structural repair, paint AS-110, AS-1002, AS-3506, AS-4130, AS-4140, AS-5001, AS-5009 | 841 | 1 | 11.8 | | 5 | 38 |
| WATER DISTRIBUTION SYSTEM POTABLE Structural repair, paint AS-506, AS-514, AS-2003, AS-4102, AS-4105 | 842 | 1 | 3.5 | | 6 | 39 |
| STRUCTURAL REPAIR AS-129 | 890 | 1 | .1 | | 1 | 40 |



BMAR REPORT AND PROJECTS PLAN (BACKLOG OF MAINTENANCE AND REPAIR)

1. ACTIVITY Marine Corps Air Station (H)
New River, North Carolina


2. CURRENT PROJECTED X

3. LESS HOUSING HOUSING X

4. FOR PERIOD ENDING
30 Sep 1980

5. SHEET 5 OF 7


| DESCRIPTION | CATEGORY CODE | DEFI-CIENCY CODE | UNFUNDED COST | VALI-DATION RATING | NUMBER OF PREVIOUS SUMMARIES | LINE NO. |
|----------------------------------------------------------|---------------|------------------|---------------|--------------------|------------------------------|----------|
| CODE II | | | | | | |
| REPAIRS TO AIRCRAFT PARKING, MCAS(H), NEW RIVER (NR005M) | 111 | 2 | 159.5 | | 2 | 41 |
| RESURFACE RUNWAY 18-36, MCAS(H), NEW RIVER (NR003M) | 111 | 2 | 370.5 | | 2 | 42 |
| REPAIRS TO TAXIWAYS, MCAS(H), NEW RIVER (NR004M) | 111 | 2 | 140.4 | | 2 | 43 |
| REPAIRS TO RUNWAY 5-23 (NR101M) | 111 | 2 | 168.4 | | 1 | 44 |
| REPAIR AIRCRAFT WASHING FACILITIES | 116 | 2 | 80.0 | | 0 | 45 |
| REPAIR PETROLEUM FACILITIES | 123 | 2 | 98.1 | | 0 | 46 |
| REPAIR AIRFIELD LIGHTING (NR106M) | 130 | 2 | 230.0 | | 1 | 47 |
| REROOF BUILDING AS-4108 (NR102M) | 211 | 2 | 41.7 | | 1 | 48 |
| REPAIRS TO BALLFIELD LIGHTING, AS-246 (NR104M) | 750 | 2 | 68.1 | | 1 | 49 |
| RESURFACE VARIOUS ROADS (NR106M) | 851 | 2 | 30.9 | | 4 | 50 |
| REPAIR PARKING AREAS (NR105M) | 852 | 2 | 268.5 | | 8 | 51 |
| REPLACE SECURITY FENCE, OAK GROVE | 872 | 2 | 120.2 | | 1 | 52 |
| REPLACE FIRE ALARM SYSTEM (NR008M) | 880 | 2 | 260.0 | | 5 | 53 |
| REPLACE BOILER CASINGS, AS-4151 | 821 | 2 | 158.0 | | 1 | 54 |



BMAR REPORT AND PROJECTS PLAN (BACKLOG OF MAINTENANCE AND REPAIR)

| | | | | |
|-----------------------------------------------------------------------|-----------------------------------|--------------------------------------|-------------------------------------|---------------------------------------|
| 1. ACTIVITY Marine Corps Air Station (H) New River, North Carolina | 2. CURRENT PROJECTED <u> X </u> | 3. LESS HOUSING HOUSING <u> X </u> | 4. FOR PERIOD ENDING 30 Sep 1980 | 5. SHEET <u> 6 </u> OF <u> 7 </u> |
|-----------------------------------------------------------------------|-----------------------------------|--------------------------------------|-------------------------------------|---------------------------------------|

| DESCRIPTION | CATEGORY CODE | DEFI-CIENCY CODE | UNFUNDED COST | VALI-DATION RATING | NUMBER OF PREVIOUS SUMMARIES | LINE NO. |
|-------------------------------------------------------------|---------------|------------------|---------------|--------------------|------------------------------|----------|
| CODE III | | | | | | |
| NAVIGATION AND TRAFFIC AIDS OTHER THAN BUILDINGS, AS-3514 | 134 | 3 | .8 | | 1 | 55 |
| GENERAL SUPPLY STORAGE/OPERATIONS BUILDINGS, AS-808, AS-873 | 441 | 3 | 1.0 | | 1 | 56 |
| <u>PROJECTS PLAN</u> | | | | | | |
| REPLACE RAPID REFUEL SUPPLY LINE | 824 | | 80.0 | | 0 | 1 |



BMAR REPORT AND PROJECTS PLAN (BACKLOG OF MAINTENANCE AND REPAIR)

| | | | | |
|-----------------------------------------------------------------------|-------------------------------------|----------------------------------------|----------------------------|-------------------------------|
| 1. ACTIVITY Marine Corps Air Station (H) New River, North Carolina | 2. CURRENT PROJECTED _____ _____ | 3. LESS HOUSING HOUSING _____ _____ | 4. FOR PERIOD ENDING _____ | 5. SHEET <u>7</u> OF <u>7</u> |
|-----------------------------------------------------------------------|-------------------------------------|----------------------------------------|----------------------------|-------------------------------|

| DESCRIPTION | CATEGORY CODE | DEFI- CIENCY CODE | UNFUNDED COST | VALI- DATION RATING | NUMBER OF PREVIOUS SUMMARIES | LINE NO. |
|---------------------|---------------|-------------------|---------------|---------------------|------------------------------|----------|
| FY 80 BEMAR | | | | | | |
| CODE I | | | \$ 697,600 | | | |
| CODE II | | | \$2,194,300 | | | |
| CODE III | | | \$ 1,800 | | | |
| Total | | | \$2,475,700 | | | |
| | | | | | | |
| FY 85 Projects Plan | | | 80,000 | | | |

