

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
JB7 819 101 146	4/14/67	221	Install sink, electric outlet and elect water heater, connect hot and cold water to sink
JB7 819 101 152	4/7/67	128	Cut and remove trees (5) as noted on Mr. Hawkins report
AA023 0313 23**Tg	2/27/70	443	Install elect water heater and utility sink, more kiln from 825 to 855 rm 107
AA023 0314 2324T	9/5/69	168	Misc. maint and repairs to plumbing and heating systems
AA023 0326 23XXT	3/6/70		Emergency repair to leak under building
AA123 0349 2327T		715	Furnish 250 tons of shellrock for parking lot south side of Bldg 855.
AA 0358 2318T	6/30/71	329	Replace coil in air handling unit
AA123 0359 2318T	6/30/71	57	PM air conditioning monthly
AA2 23 0321 2318T	10/29/71	113	July Aug, Sept, Oct P.M. air conditioning monthly
AA223 0331 23XXT	8/6/71	463	Cut and remove six trees, cut stumps below ground, back fill and dress-up area
AA223 9238 23XXT	3/24/72	712	Install window air conditioners in schools 1943 to 4003, 825-855
AA223 9247 23XXT	6/30/72		Inspect and repair heaters, shop 16 to notify Mr Hinton and Mr. Taylor when work is to start, inspectors will assist in work.
AA223 9247 2318T		67	Quarterly P. April to June on central air cond.
AA223 9266 2318T	6/30/72	1,419	Replace compressor on air conditioner
AA223 9267 23XXT	5/12/72	853	Relocate central air-conditioner compressor from roof to ground level
223 9272 23020	1/2/73	400	Repairs to automatic controls heating system
1776	10-25-74	484	Repair roof over office
1731	7-26-74	747	Rebuild 39 V. Blinds
1716		147	PM A/C
1805	2-9-73	313	Rpl v bluts + motor mounts
1735	11-3-72	120	PM A/C
1827	12-28-73	140	Install duplex receptacle

