

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
HQ8CMOPH 502	2/2/68	907	Self-help landscaping of new schools
AA923 ** 15123	4/11/69	303	Install anteaenna to auditorium in bldg
AA923** 15140	6/27/69	143	Perform preventive maintenance to Johnson service system in Berkely manor
AA923 ** 15142	6/27/69	289	Replace warm air limit controls and install protective covers outside Wings A, B, C, D, E, and F.
AA023 0307 2319T	1/2/70	143	Perform preventive maintenance to Johnson service system
AA023 0321 2319T	3/27/70	143	Perform preventive maintenance to Johnson service controls
AA023 0323 2319T	12/31/70	151	Perform recurring maintenance to Johnson service control system
AA123 0333 2319T	4/2/71	151	Perform recurring maintenance to Johnson service control system
AA123 0340 2319T	6/30/71	155	Perform recurring maintenance to Johnson service system
AA123 0351 2316T	4/9/71	538	Install (4) 96" 2 tube florescent lights in (2) sections of auditorium for temporary classrooms
AA123 0362 23XXT	6/4/71	461	Install air conditioner in library at school bldg
AA123 0363 23XXT	6/8/71	838	Spread fill dirt, clean-out swales, haul and spread top-soil, fertilize and reseed bare areas
AA123 0368 2317T	6/30/71		Furnish temporary service and remove bad transformer
AA223 0320 2319T	10/1/71	329	Perform recurring maintenance to Johnson service control system
AA223 0326 2317T	6/23/72		Repair and reinstall transformers feeding school
AA223 0323 2319T	12/30/71	329	Perform recurring maint to Johnson service systems
AA223 0366 2318T	3/31/72	333	Perform recurring maintenance to Johnson service control system
AA2 23 0381 2320T	1/21/72	007	Fabricate and install 8 steel columns 4 in cafeteria
AA223 9225 2318T	4/28/72	333	Perform recurring maintenance to Johnson service controls systems
AA223 7243 23XXT	2/11/72		Dig out, check cause of sink hole and make necessary repairs under window of reading room
AA223 9600 2317T	4/28/72	1,131	Install pole and two mercury vapor lights on each in (2) playground areas
<i>+598</i>	<i>9-24-80</i>	<i>179</i>	<i>P.M. Colored water test</i>
<i>+560</i>	<i>8-15-79</i>	<i>1986</i>	<i>Art grass around dep school - on playing field</i>

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
1790	2-28-75	294	Cut opening for door jamb, install & paint
1785	12-20-74	162	Cut trees, remove stumps
1763	11-8-74	99	Install 6" plug mold
1759	11-15-74	142	Install 2 fluorescent lites
1744	7-19-74	432	Recurring maint to control system
1719	5-31-74	272	Extend 4" clean out plugs from under bldg to floor level
1712	7-1-74	406	Recurring maint to Johnson service control sys
1860	4-19-74	192	Replace cable on flag pole
1810	12-14-73	528	Fix leak in roof and leak damage boiler room
1809	2-22-74	996	Install 6 receptacles for A/C
1776	10-5-73	168	Dig holes and set playground equip
1712	7-2-73	367	Recurring maint to Johnson service controls
1721	7-10-73	379	" " " " " "
1837	6-29-73	350	" " " " " "
1805	2-9-73	313	Replace V belts and motor mounts
1785	3-28-73	350	Recurring maint to Johnson Service Controls
1739	7-13-72	191	Replace V belts and motor mounts
1736	7-12-72	350	Recurring maint to Johnson Service Controls
1761	1-9-76	300	repl. circulating pump in Wing A.
1798	3-28-75		O/E rep roof leaks
1765	7-12-77	531	Repl. A/C compressor
1739	12-29-77	934	Repair & clean out catch basins & storm drain
1749	1-30-78	63	Remove old light fixtures & install new
1733	11-11-77	509	Inst. floor lights, switches, and duplex recept. in P.E. Office
1768	7-10-78	443	Replace A/C compressor
1718	9-27-78	1997	For Johnson Control system

39

UPDATED BLDGS METER REQUIREMENTS

BLDG #	ELECTRICAL	WATER	STEAM
4		X	
1402		X	
1010	(DELETE)	ACCOMPLISHED ON PROJ LE614R	85-6419
TT-2465		X	
TC-611	(DELETE)	ACCOMPLISHED ON PROJ LE614R	85-6419
TC-832	X		
LCH-4014C		X	
1015		X	
FC-313	X		
421	(DELETE)	FROM PROJECT	
1300	(DELETE)	FROM PROJECT	
TT-48		X	
TT-60		X	
1943		X	
40		X	
5400		X	
825		X	
TC-1500		X	
1200		X	
1401		X	X
AS-710		X	
TT-2475	X		
TT-44	X		
TT-2451	X		
2600	X		
1919	X		
AS-2800	X		
LCH-4025	X		
LCH-4000	X		
LCH-4007	X		
LCH-4005	X		
LCH-4009	X		
AS-1001	X		
AS-2001	X		
TT-38	X		
TT-35	X		
* 623	X		
* 607	X		
* 622	X		

Encl (1)

