

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
2349		863	make 287 keep for 107 clocks
4842	6-29-73	600	repl motor & oil pump.
3520	11/9/76	/	Rpl sump pump line
3300	1-12-79	900	Rpl heat exchanger
3255	4-6-79	280	Rpl missing grilles and register patch small hole in plaster
3040	12/4/79	1141	Job/uninstall venetian blinds
4677	8-30-79	1571	Repl venetian blinds complete
3703	6-22-79	726	Repl tube bundle in HOT WATER Storage Tank
4724	Comp	594	Job 12 return air grille
3465	Comp	/	Rep to A/c compressor (4)
3664	9-24-85	287	rpl. V-Blinds
3109	Comp	1038	Repr. elect. switches
3381	4-30-82	3485	repr. A/c
3382	Comp.	2215	rebuild a/c compressor
4321	4-22-83	1034	Replace condensate pump
3075	Comp	1138	Rebuild steam traps
3733	7-10-84	8580	INST AUTOMATIC CHEMICAL FEEDS
4505	3-28-85	2629	PREPARE DRIVEWAY AREA Landscaping
3231	3-28-85	716	REPI MAIN HOT WATER Htg Syst Piping
<del>3733</del>	<del>4-20-84</del>		
3315	11-15-91	1320	RPLC 575 LF RUBBER BASE BOARD + 2 EA FLOOR REGISTERS +
3726	5-20-96	751	MISC ELEC REPS. CYCLIC MAINT pump 8/23/88
✓3810	4-18-97	3577	RPLC HEAT EXCHANGER Merged 9-21-01
4257		4488	RPLC PUMP
CLM1		26,271	F.V 02-167982 TAPL Dealing Tower

