BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD MCBCL 11011/3
TC-611					

JOB ORDER NO	DATE ~~COMPLETED~~ signed	COST	DESCRIPTION
4702	2-7-75	96	Repair broken water main near TC-611
0207	7-1-77	106	Provide water tap for MCX
Cont # 79-2665	6-80	—	Ext. Paint
1219	Comp	—	Install head facilities
4730	Comp	4799	Make ext. repr before contract pt.
3446	Comp	1005	Repr water line to bldg

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION