BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD MCBCL 11011/3
M-244					

JOB ORDER NO	DATE ~~COMPLETED~~ signed	COST	DESCRIPTION
4145	11-9-73	853	Repair well pump
4177	6-1-73	1211	Pull check & Repair well pump
3195	Cancel 2-1-74	2940	Replace well pump
3985	6-29-73	102	Repair well pump
3540	10-8-71	186	Repair/Paint ext

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION