BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
0070	8-17-79	376	Install 115 volt outlet
3826	6-1-79	2663	Replc. damaged fuel pump
1115	4-13-79	712	Install hot water heater in machine shop
4874	10-24-80	60	Rpr gate & fence
4784	11-14-80	832	Remove shell stone etc and fittings for vacuum cooler
3175	11-7-80	57	Assist fire dept to test & flush sprinkler system
3395	3-27-81	185	Install U-line snap plugs in battery shop
1202	8-14-81	200	Extent wall to provide security
5189	3-19-82	934	Rpr. Hydralic lift
1220	11-18-83	2318	Refl Exhaust System
4557	11-18-83	633	Repair Grease Pump
1305	8-3-84	620	Troop Training Project Fabricate Ceiling For Security Room
0052	5-17-85	188	Rpr Bishman Mod # 931 A Truck Tire Changer PA# 213041
2196	9-25-85	577	Install elt to East Ext Side of Bldg
3163	Compl	5053	Rpr Roof Flashing around Parapet Walls & around A/H units 10-5-84
3198	10-3-84	5053	REPR ROOF FLASHING around PARAPET WALLS

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION