BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD
RR-34					MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
4582	8-1-80	522	Rpr sewer drain line
3968	5-29-81	484	Rpr. underground water main
3968	Comp	484	Rpl 60' of water line
4351	10-23-81	769	Ext Rprs. before paint
5242	5-25-84	1343	make misc Plumbing Repairs

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
4352	12-25-81	342	EXT Rpr. before paint
5242	5-25-84	1343	make Misc. Plumbing Repairs
3017	12-23-83	823	Replace 2" Water Line Vicinity RR 35

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION

| BLDG NO | INT. PAINT SQ FT | | EXT. PAINT SQ FT | ROOF SQ FT | CONDEN. LINES LIN FT | FACILITY HISTORY RECORD |
| RR-36 | | | | | | MCBCL 11011/3 |

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
3104	12-1-72	478	Repair & Paint
125-577-198 5-1567		97	Paint ext trim
3131	5-20-83	2017	Replace two doors + jambs
3018	10-5-83	456	Rpl the Exist & deteriorated Galvanize water line Leaking

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION