

BLDG NO
M-607INT. PAINT SQ FT
18000 sfEXT. PAINT SQ FT
1300 sf 41 windows

ROOF SQ FT

CONDEN. LINES LIN FT

FACILITY HISTORY RECORD
MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED signed	COST	DESCRIPTION
023-03014-82	1/31/63	E 738	Renovation
023-03196-82	4/2/63	E 284	Renovate and paint exterior
CONTRACT	C 9/25/63		Waterproofed
AAO-83-4049	3/9/70	717	replace repair ceramic tile & plaster self help
3182	1-2-72	3659	Repair & paint ext
41954	6-6-74	609	Paint int
3334	1-27-75	1185	Self help tile decks
4501	1-24-75	1471	Repair & paint
4826	1/26/76	1041	issue material
3080	9-21-79	2482	Unit Repair Paint Int Complete 2 Coats
5182	4-30-82	5727	Rpl. steam coils in A/H units
5181	1-7-82	676	" Hot water heating coils
3408	6-18-82	6295	INT. Rprs paint
3324	Comp	2462	Rpl steam coils in Air Handling Units
3394	Comp	3692	Rpl steam coils in Air Handling Units
3576	1-18-83	976	Remove steam condensate
4504	4-20-83	3584	Repair & Replace sewer doors & lights
3448	6-15-84	1002	Repair Plaster & Paint
3823	Comp	2366	Repl Return air Grilles
4037	Comp	2276	Start up & Check out & make repairs to (46) Central Units
4096	Comp	1913	Repl missing & Damaged Window Screens
4113	Comp	1954	Repl missing & Damaged Window Screens
4432	Comp	941	Repl Thermometers & Thermometer Sockets
5016	Comp	16400	Perform cyclic maint
6018	Comp	1065	Repl missing & Damaged window Screens

