8.4 REGULATORY INSPECTION SUMMARY

Date: 03/14/02						
To: (Plant Mgr.) Earl Deskins						
Regulatory Inspection Summary						
Facility Inspected Kingston Fossil Plant						
2. Date of Inspection & duration 03/08/02						
Purpose of Inspection (routine compliance, NOV follow-up, permit renewa Routine Compliance	l)					
4. Media covered during inspection Solid Waste (Ash Pond and Dikes)						
5. Name of Inspector & Agency Rick Brown, TDEC, Div. of Solid Waste Management						
Facility personnel participating or contacted during inspection James Settles, HED						
7. Observations or problem identified by inspector <u>Comments from inspector - Fill is progressing according to plans. They are now on the third level. The outer berm is covered with soil and will be seeded in the next few weeks. Observed one washout in lower level berm that will need to be repaired.</u>						
·						
8. Samples collected No						
9. Records Reviewed No						
40 D C :						
10. Deficiencies No						
Submitted by: Linda Campbell						
cc: Mgr., ENV AFF 3/14/62						

NOTE: This summary is to be provided to the facility manager and faxed or e-mailed to ENV AFF (751-7011) by the close of business on the day following the inspection. (See Section 6.2.6)





TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION DIVISION OF SOLID WASTE MANAGEMENT SOLID WASTE DISPOSAL FACILITY EVALUATION

NAME OF SITE	<u> </u>		REGISTRAT	ION NUMBER	401	BATE 3/8/2/02
TVA Kingston Power Plant	Coal Ach	Murstill	IDL	73-103-0	044	
I I CICA HON (MYWRIAN)				PURPOSE Comple	ete () Foll	
TVA Knasta Rvor Plant property	aft Hillhury	10 west of	KU YA JON /NY	() Compla		
OWNERIOPERATOR JUNE TEMPERATOR	control (Tames	Settles		() CLASS 1 () CLASS III	CLASS II
DIMA I JEMARGE VALLEY MUTAVITY	V1	<u>√ω // ως</u> V2	1119		() COASS III	V1 V2
		42			4 0000	*
Inadequate vector control	8010			improperly manage		
Access not limited to operating hours	8020			te leachate collection -	n 8340	
Inadequate artificial or natural barrier Inadequate information signs	8030 <u> </u>	_	syster	observed at the site		
Unsatisfactory access road(s)/parking	9040		1	entering runoff	8360	
area(s)	8050			entering a water	0020	
Certified personnel not present			cours	-	8370	
during operating hours	8060		1	te gas migration con		
Unapproved salvaging of waste	8070		system	-	8380	
Evidence of open burning	8080			te maintenance of ga	as	
Inadequate fire protection	8090			tion control system	8390	
Unsatisfactory litter control	8110			for explosions or		
Inadequate employee facilities	8120		uncon	trolled fires	8420	
No communication devices	8130		Waste no	t confined to a		
Inadequate operating equipment	8140		manag	geable area	8430	
Unavailability of backup equipment	8150		Improper	spreading of waste	8440	
Unavailability of cover material	8160			compacting of waste		
Inadequate maintenance of				ctory initial cover	8460	
runon/runoff system(s)	8170		Unsatisfa	ctory intermediate		
Inadequate erosion control	8180	_	cover		8470	
inadequate dust control	8190	-		ctory final cover	8480	
Unauthorized waste accepted	8210			pooling of water	8490	
Unapproved special waste accepted	8220		Unsatisfa	ctory stabilization of		
Tires improperly handled	8230		cover		8510	
Medical waste improperly handled	8240			of waste into water	8520	
Dead animals improperly handled	8250			ctory records or repo		
Washout of solid waste	8270			ater monitoring syste		
No permanent benchmark	8280			erly maintained	8540	
Inadequate random inspection	0000		1 '	does not correspond		
program Mishandling of special waste	8290			ngineering plans	8570	
Buffer zone standard violated	8300			does not correspond		
Inadequate maintenance of leachate	8310			ermit condition(s)	8580	
	0000			ans, operating manu		
management system	8320		not ava		8590	
			No operati	ing scales	8610	
COMMENTS: Fill is amount	resting a	neadi	24 1	ylansi	7700 0	اريهم مس
	essing u	TXOVOLT.	M M		7.7	re now
on the Third les	res.	Le 04	Her by	mr. 12 Co	verou	12 501/
and will be seed	ed D	De	next	For will	KC B	served
one washout in lower sevel been treat will need to be						
all a words						
To part to						
<i>U</i>						
S55000 A	7			-0-10		
PERSON INTERVIEWED (Signature) INSPECTED BY (Signature) (Signature)						
TITLE FAMILY Engineer						
TIME OF OVERLAND AND AND AND AND AND AND AND AND AND						
Distribution: Facility - White Field Office - Canary Central Office - XC						
Cistibuton. I a				Central Childe -	710	

CN_07R1 (RAV 7_QR)

RDAs 2202 and 2499TOTAL P.01

TVA-00029269