REPORT OF CHANNEL CONDITIONS 100 TO 400 FEET WIDE

Page 1 of 1 Date 6/22/2015

| To: Navigation Interests | From: | U.S. Army Corps of Engineers - Charleston | | | | | |
|--|-------------------|---|---------|-----------------------|--------------------|---------------|--------------------|
| | | 69A Hagood Avenue | | | | | |
| | | Charleston. SC 29403 | | | | | |
| RIVER/HARBOR NAME AND STATE | | | | | MINIMU | JM DEPTHS | IN EACH |
| ASHLEY RIVER | | | | | 1/4 W | IDTH OF CHA | ANNEL |
| SOUTH CAROLINA | | | | ENTERING FROM SEAWARD | | | |
| NAME OF CHANNEL | DATE OF SURVEY | AUTHORIZED PROJECT | | | LEFT | | RIGHT |
| | | WIDTH LENG | LENGTH | STH DEPTH | OUTSIDE QUARTER | MIDDLE | OUTSIDE QUARTER |
| | | (feet) | (miles) | (feet) | (feet) | HALF (feet) | |
| Ashley River Reach 1 | | 600 | | | , | , , | , |
| 0+00 to 546+82 | 06-15-2015 | | 10.30 | 30.0 | 14.7 | 14.4 | 8.4 |
| 0.00.00.10.02 | 00 13 2013 | 300 | 10.50 | 30.0 | 11.7 | 1 11 1 | 0.1 |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| 1. All depths refer to local mean lower low water (MLLW) | | | | | | | |

^{2.} The information shown represents the results of surveys made on the dates indicated and reflects the general conditions at that time

^{3.} The right and left sides of the channel refer to travel in the general direction when entering from seaward

^{4.} Only minimum depths based on survey lines depicted