## REPORT OF CHANNEL CONDITIONS 400 FEET WIDE OR GREATER

(ER 1130-2-306)

 PAGE
 1
 OF
 1

 DATE
 July 29, 2011

TO: The Record

FROM:

U.S. Army Corps of Engineers

26 Federal Plaza, ATTN: CENAN-OP-ST

New York, NY 10278-0090

RIVER/HARBOR NAME AND STATE:

Tarrytown Harbor, New York

MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHO WIDTH (feet)	RIZED PRO LENGTH (nmiles)	DEPTH (feet)	LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
Reach A (South Channel): Begins at Green Can #1, Ends at Green Can #5.	Map 26 Page 2 of 2; 06-07 June 2011	150	0.34	12	7.9	8.3	8.0
Reach B (Wharf): Begins at Green Can #5, Ends approximately 300 feet seaward of Red Nun #4.	Map 26 Pg 1 thru 2 of 2 ; 06-07 June 2011	250	0.38	12	5.9	6.2	5.1
Reach C (North Channel): Begins approximately 300 feet seaward of Red Nun #4, Ends approximately 700 feet seaward of Green Can #3.	Map 26 Page 1 of 2; 06-07 June 2011	150	0.28	12	7.0	7.0	6.4

## REMARKS:

- All depths in Mean Low Water (MLW)
- · Channel length is in nautical miles.

## MAIN SHIP CHANNEL:

- Reach A Slight shoaling has occurred throughout the width of the channel from Green Can #3 to Green Can #5.
- Reach B Between 400 and 600 feet of Red Nun #4, shoaling exists along the entire width of the channel.
   Shoaling also exists along the jetty wall, between 600 to 800 feet landward from Red Nun #6.
- Reach C Shoaling exists throughout the right outside quarter, adjacent to the jetty wall. Shoaling can also be seen on the left outside quarter from Red Nun #4 to roughly 300 feet landward.