

May 23, 2011

Pipeline and Hazardous Materials Safety Administration Central Region 901 Locust Street, Suite 462 Kansas City, MO 64106-2641

- Attention: Mr. David Barrett Director, Central Region
- Re: Notice of Probable Violation and Proposed Civil Penalty Guardian Pipeline Company CPF 3-2011-1007

Dear Mr. Barrett:

In response to the Notice of Probable Violation and Proposed Civil Penalty CPF 3-2011-1007 dated April 25, 2011, Guardian Pipeline Company (GPL) submits the following regarding the issues brought forth from the inspection of GPL records and facilities of Guardian Pipeline at Channahon, Illinois, during April 26-30, 2010.

The Pipeline and Hazardous Materials Safety Administration (PHMSA) issued a Notice of Probable Violation for two items with preliminary assessed civil penalties as noted below.

 §192.709 (c) Transmission lines: record Keeping. A record of each patrol, survey, inspection, and test required by subparts L and M of this part must be retained for at least 5 years or until the next patrol, survey, inspection, or test is complete, which is longer.

§192.625 Odorization of gas.

§192.625 (f) Each operator shall conduct periodic sampling of combustible gases to assure the proper concentration of odorant.

Guardian was unable to produce annual inspection records for the inspection and testing of the domestic odorizer at the Channahon, IL compressor station for the calendar years 2007, 2008, and 2009.

Guardians' operating procedure, OKSop3.080.402 – "Odorization of Gas", specifies that odorizers be sampled and tested once each calendar year. A record of the inspection and testing is required per the requirements of §192.709 (c).

Proposed Civil Penalty \$17,600

ONEOK Partners, L.P. 100 West Fifth Street Tulsa, OK 74103 www.oneokpartners.com

GPL NOPV Response:

As discussed during the audit, GPL was unable to locate the 2007, 2008, and 2009, D7i records for the inspection and testing of the domestic odorizer at the GPL, Channahon Station. The odorizer was inspected and tested on May 6, 2010, and was properly working. GPL has since closed out the open work order records for the odorization inspection and maintenance tasks for 2008 and 2009. It appears no work order task was generated for 2007 since Guardian was in transition to our computerized maintenance system D7i. The open work order requests did not deal with fixes to the proper functioning of the odorization equipment so there is a reasonable basis for concluding that the equipment was in proper working order during the years inspection documentation is missing. Discussion has been held with the team members of the importance of performing the work according to the procedure and closing the work order tasks, including those dealing with inspection and documentation of same, within the required timeframe. The testing and inspection records for May 6, 2010, are attached for reference.

 §192.709 (c) Transmission lines: record Keeping. A record of each patrol, survey, inspection, and test required by subparts L and M of this part must be retained for at least 5 years or until the next patrol, survey, inspection, or test is complete, which is longer.

§192.731 Compressor stations: Inspection and testing of relief devices.

§192.731 (c). Each remote control shutdown device must be inspected and tested at intervals not exceeding 15 months, but at least once each calendar year, to determine that it functions properly.

Guardian could not produce required records for the annual inspection and testing of the discharge pressure transmitter located at the Channahon IL compressor station for calendar years 2007, 2008, and 2009.

Guardian's operating procedure, OKSops3.030.301 – "Remote Control Shutdown Devices, Inspection, Maintenance, and Calibration", specifies annual testing and calibration of station shutdown instrumentation and devices. At the Channahon, IL compressor station the discharge pressure transmitters serve as primary shutdown device that requires a record of such testing and calibration per §192.731 (c).

Proposed Civil Penalty \$17,600

GPL NOPV Response:

During the audit, GPL produced records for the annual inspection and testing of the discharge pressure transmitter located at the Channahon IL compressor station for calendar years 2008, and 2009. The testing and calibration record could not be found for 2007 but GPL believes that the inspection and testing was in fact completed. It appears the record was lost due to employee changes and transition to the computerized maintenance system D7i.

The fact that the testing and calibration records for 2008 and 2009 for the pressure transmitter were provided should remove these years from the penalty calculation. We ask that the fact that the 2007 records on the pressure transmitter were lost but that this is a

recordkeeping rather than substantive violation result in mitigation of the proposed penalties. We ask that the recordkeeping issues associated with the odorization records at the plant be considered in light of the 2010 records showing proper operation and that this issue also be subject to mitigation of the proposed penalties.

We hope you will find the responses and information provided sufficient to warrant mitigation of the civil penalties and to assure you that we are taking responsibility for these deficiencies and steps to prevent reoccurrence. If you require any additional information or clarification to this response letter, please contact Mark Mickelberg, Senior Pipeline Safety Engineer, at 1-651-994-0332 Ext 1225.

Very truly yours,

Mubel E welco

Mr. Michel E. Nelson Senior Vice President, Natural Gas Pipeline Operations

/ork Order	189875	80.402-TEST ODORIZATION OF GAS ANNUALLY	Scheduled Start Scheduled End Date Status	09/01/2008 09/30/2008 RELEASED
arent WO epartment	GUARDIAN		WO Туре	DOT
eparament	GUARDIAN		Assigned To	OKE10880 - WILBURN, MARK
M Schedule	80.402B		Reported By	·····
orm Number:	80.402-TEST	DOORIZATION OF GAS ANNUALLY	Assigned By Multiple Equipment	
tandard WO			Date Started	6-25-10
erformed Every:	1 Years		Date Completed	6-21-10
ieter Interval:			Time Completed	

	Comment: odor	ilation pomp	in mid al	hree ke	ad and	accentra	<u>ia</u>
lanufacturer lodel erial Number	900 l	condition.	Mercaptain	Ì\$	rembing	Jonestic	sources,
ocation		and the statistic ends of the statistic statistics and the MASS		ax	5 Juli	Э	ತ್ರೇಕೆ ಪ್ರಶಸ್ತಿ ಪ್ರಧಾನ ಮಹುದನ
		WO/PM C	omments		Current		

FACILITY-GPL JOLIET COMPRESSOR STATION

5.3. CONDUCT PERIODIC SAMPLING AND TESTING OF ALL ODORIZED GAS TO ASSURE THE PROPER CONCENTRATION OF ODORANT IS PRESENT.

5.3.1. SELECT SAMPLING SITES TO PROVIDE MAXIMUM ASSURANCE THAT ALL GAS WITHIN THE PIPING SYSTEM CONTAINS THE REQUIRED ODORANT CONCENTRATIONS. THE NUMBER OF SITES SELECTED DEPENDS UPON THE SIZE AND CONFIGURATION OF THE SYSTEM, LOCATION OF ODORIZATION STATIONS, AND LOCATIONS THAT MAY CONTAIN LOW ODORANT LEVELS. THE LOCATION OF SAMPLING SHOULD BE DISTANT FROM ANY GAS BEING VENTED AND THE ODORIZER.

5.3.2, SAMPLE AND TEST AT LEAST ONCE EACH CALENDAR YEAR.

10043

quipment

5.3.3. USE AN MSA UNIVERSAL TESTER, HEATH ODORATOR OR EQUIVALENT TESTING DEVICE TO DETERMINE ODOR LEVELS. ADJUST INJECTION RATES AS NECESSARY.

5.3.4. ASSURE THAT THE GAS IS ODORIZED SO THAT IT IS READILY DETECTABLE BY A PERSON WITH A NORMAL SENSE OF SMELL AT THE FOLLOWING CONCENTRATION.

5.3.4.1. FOR ALL OTHER FACILITIES THE GAS IN AIR IS NO MORE THAN ONE-FIFTH THE LOWER EXPLOSIVE LIMIT.

5.3.5. DOCUMENT EACH TEST INCLUDING THE FOLLOWING INFORMATION.

5.3.5.1. TEST SITE LOCATION: GUARDIAN Kitchen

5.3.5.2. DATE OF TEST: 8-29-108

5.3.5.3. PERSON CONDUCTING THE TEST: Justa Malaney

5.3.5.4. UNIQUE IDENTIFICATION OF TEST INSTRUMENT: Bacharach Part # 5110-0200

5.3.5.5. RESULTS OF TEST, PERCENT GAS IN AIR: 100 %

Tested on RKI GX 2003 ges detatol is calibrated.

• · · · · · · ·

COMMENTS: Essential for this type of reading to be based on first sailt cally due to imped fortigue with ones office tary senses with continued exposure to odor. J.M.

.

.

· · · · ·

/ork Order	215575	80.402-TEST ODORIZATION OF C	GAS ANNUALLY Scheduled Start Scheduled End Date Status	09/01/2009 e 09/30/2009 RELEASED
arent WO epartment	GUARDIAN		WO Туре	DOT
	GUARDIAN		Assigned To	OKE11356 - FOX, JIM
M Schedule orm Number:	80.402B 80.402-TEST	FODORIZATION OF GAS ANNUALLY	Reported By Assigned By Multiple Equipment	107, 514
tandard WO			Date Started	6-24-10
erformed Every:	1 Years		Date Completed	6-27-10
ieter Interval:			Time Completed	
quipment	10043		FACILITY-GPL JOLIET COMPRESSOR STATIC	N

Con Ianufacturer Iodel erial Number ocation	good operating condition.
	WO/PM Comments

5.3. CONDUCT PERIODIC SAMPLING AND TESTING OF ALL ODORIZED GAS TO ASSURE THE PROPER CONCENTRATION OF ODORANT IS PRESENT.

5.3.1. SELECT SAMPLING SITES TO PROVIDE MAXIMUM ASSURANCE THAT ALL GAS WITHIN THE PIPING SYSTEM CONTAINS THE REQUIRED ODORANT CONCENTRATIONS. THE NUMBER OF SITES SELECTED DEPENDS UPON THE SIZE AND CONFIGURATION OF THE SYSTEM, LOCATION OF ODORIZATION STATIONS, AND LOCATIONS THAT MAY CONTAIN LOW ODORANT LEVELS. THE LOCATION OF SAMPLING SHOULD BE DISTANT FROM ANY GAS BEING VENTED AND THE ODORIZER.

5.3.2. SAMPLE AND TEST AT LEAST ONCE EACH CALENDAR YEAR.

5.3.3. USE AN MSA UNIVERSAL TESTER, HEATH ODORATOR OR EQUIVALENT TESTING DEVICE TO DETERMINE ODOR LEVELS. ADJUST INJECTION RATES AS NECESSARY.

5.3.4. ASSURE THAT THE GAS IS ODORIZED SO THAT IT IS READILY DETECTABLE BY A PERSON WITH A NORMAL SENSE OF SMELL AT THE FOLLOWING CONCENTRATION.

5.3.4.1. FOR ALL OTHER FACILITIES THE GAS IN AIR IS NO MORE THAN ONE-FIFTH THE LOWER EXPLOSIVE LIMIT.

5.3.5. DOCUMENT EACH TEST INCLUDING THE FOLLOWING INFORMATION.

5.3.5.1. TEST SITE LOCATION: Crunching I Change how
5.3.5.2. DATE OF TEST: 6/21/20/0
5.3.5.3. PERSON CONDUCTING THE TEST: Jostin Whyleney
5.3.5.4. UNIQUE IDENTIFICATION OF TEST INSTRUMENT: BACAMACH PART # 5110-0200
5.3.5.5. RESULTS OF TEST, PERCENT GAS IN AIR: 1017 - 315 de fected
ow RKI Engle Letector.
Standard Concentration is barely-readily defectable

так кала полого ст. 19. у толи полобили и кала ст. по толиторионала на селото сило ст. Ст. так се 19. формини полов ма и к. по типотити

COMMENTS: As described on page 3 of Bacharach adorometer instructions. J.M.

· · ' ·

conservative and the second second

. .

Work Order	208910 30.301-4A,5F,G,I-TEST REMOTE SHUTDOWN DEVICES ANNU	ALLY Scheduled Start Scheduled End Date Status	06/05/2009 RELEASED
Parent WO Department	GUARDIAN GUARDIAN		DOT OKE11356 - FOX, JIM
PM Schedule	30.301-4A,5F,G,I 30.301-4A,5F,G,I-TEST REMOTE SHUTDOWN DEVICES ANNUALLY	Requested By Assigned By Multiple Equipment	No
itandard WO		Date Started	
erformed Every:	1 Years	Date Completed	7/22/09 7/22/09
Meter interval:		Time Completed	and the second second
quipment lanufacturer lodel erial Number ocation	59153 (GPL) STATION HIGH Comment: <u>のに</u>	1 PRESSURE SHUTDOWN	
IF A TEST IS INTEN OR MIGHT CAUSE TEST THE DEVICE OUTPUT RESPONS	WO/PM Comments IDED. ISOLATE ITEMS SUCH AS DUMP VALVES, WHICH, IF OPERATED, W AN UNWANTED SHUTDOWN OF EQUIPMENT, CLEAN, REPAIR OR REPL BY INTRODUCING AN INPUT SIGNAL OR SIMULATED CONDITION THAT SE THAT WILL SHUTDOWN OR ISOLATE EQUIPMENT OR CAUSE OPERAT ACTIVATION BY THE DEVICE IS NOT A REQUIREMENT	ILL CAUSE UNNECESSARY W. ACE PARTS AS REQUIRED. CAUSES THE DEVICE TO ACT	ASTE OF GAS OR CHEMICAL
IF A TEST IS INTEN OR MIGHT CAUSE TEST THE DEVICE OUTPUT RESPONS	IDED. ISOLATE ITEMS SUCH AS DUMP VALVES, WHICH, IF OPERATED, W AN UNWANTED SHUTDOWN OF EQUIPMENT. CLEAN, REPAIR OR REPL BY INTRODUCING AN INPUT SIGNAL OR SIMULATED CONDITION THAT	ILL CAUSE UNNECESSARY W. ACE PARTS AS REQUIRED. CAUSES THE DEVICE TO ACT	ASTE OF GAS OR CHEMICAL
IF A TEST IS INTEN OR MIGHT CAUSE TEST THE DEVICE OUTPUT RESPONS	IDED. ISOLATE ITEMS SUCH AS DUMP VALVES, WHICH, IF OPERATED, W AN UNWANTED SHUTDOWN OF EQUIPMENT. CLEAN, REPAIR OR REPL BY INTRODUCING AN INPUT SIGNAL OR SIMULATED CONDITION THAT SE THAT WILL SHUTDOWN OR ISOLATE EQUIPMENT OR CAUSE OPERAT	ILL CAUSE UNNECESSARY W. ACE PARTS AS REQUIRED. CAUSES THE DEVICE TO ACT	ASTE OF GAS OR CHEMICAL
IF A TEST IS INTEN OR MIGHT CAUSE TEST THE DEVICE OUTPUT RESPONS	IDED. ISOLATE ITEMS SUCH AS DUMP VALVES, WHICH, IF OPERATED, W AN UNWANTED SHUTDOWN OF EQUIPMENT. CLEAN, REPAIR OR REPL BY INTRODUCING AN INPUT SIGNAL OR SIMULATED CONDITION THAT SE THAT WILL SHUTDOWN OR ISOLATE EQUIPMENT OR CAUSE OPERAT	ILL CAUSE UNNECESSARY W. ACE PARTS AS REQUIRED. CAUSES THE DEVICE TO ACT	ASTE OF GAS OR CHEMICAL
IF A TEST IS INTEN OR MIGHT CAUSE TEST THE DEVICE OUTPUT RESPONS	IDED. ISOLATE ITEMS SUCH AS DUMP VALVES, WHICH, IF OPERATED, W AN UNWANTED SHUTDOWN OF EQUIPMENT. CLEAN, REPAIR OR REPL BY INTRODUCING AN INPUT SIGNAL OR SIMULATED CONDITION THAT SE THAT WILL SHUTDOWN OR ISOLATE EQUIPMENT OR CAUSE OPERAT	ILL CAUSE UNNECESSARY W. ACE PARTS AS REQUIRED. CAUSES THE DEVICE TO ACT	ASTE OF GAS OR CHEMICAL
IF A TEST IS INTEN OR MIGHT CAUSE TEST THE DEVICE OUTPUT RESPONS	IDED. ISOLATE ITEMS SUCH AS DUMP VALVES, WHICH, IF OPERATED, W AN UNWANTED SHUTDOWN OF EQUIPMENT. CLEAN, REPAIR OR REPL BY INTRODUCING AN INPUT SIGNAL OR SIMULATED CONDITION THAT SE THAT WILL SHUTDOWN OR ISOLATE EQUIPMENT OR CAUSE OPERAT	ILL CAUSE UNNECESSARY W. ACE PARTS AS REQUIRED. CAUSES THE DEVICE TO ACT	ASTE OF GAS OR CHEMICAL
IF A TEST IS INTEN OR MIGHT CAUSE TEST THE DEVICE OUTPUT RESPONS	IDED. ISOLATE ITEMS SUCH AS DUMP VALVES, WHICH, IF OPERATED, W AN UNWANTED SHUTDOWN OF EQUIPMENT. CLEAN, REPAIR OR REPL BY INTRODUCING AN INPUT SIGNAL OR SIMULATED CONDITION THAT SE THAT WILL SHUTDOWN OR ISOLATE EQUIPMENT OR CAUSE OPERAT	ILL CAUSE UNNECESSARY W. ACE PARTS AS REQUIRED. CAUSES THE DEVICE TO ACT	ASTE OF GAS OR CHEMICAL

Work Order 193517 30.301-4A.3F.G.1-TEST REMOTE SNUTDOWN DEVICES ANNUALLY Scheduled Start 06/05/2008 Parent WO Department GUARDIAN Wolf Wolf Wolf Wolf Wolf Wolf Wolf Wolf		\bullet	Print Work Order Custom	\bullet	
Department GUARDIAN Asigned To OKE10880 - W Schedule 30.301-4A,SF,G,I WILBURN, MARK Requested By 30.301-4A,SF,G,I 30.301-4A,SF,G,I Requested By Standard WO Standard WO Date Started Wilburn Performed Every: 1 Years Date Completed 7-8-08 Meter Interval: Time Completed ##@ Equipment 59153 STATION HIGH PRESSURE SHUTDOWN Serial Number Comments ##@ Model Serial Number SolotATE ITEMS SUCH AS DUMP VALVES, WHICH, IF OPERATED, WILL CAUSE UNNECESSARY WASTE OF GAS OR CHEMI OR MIGHT CAUSE AN UNWANTED SHUTDOWN OF EQUIPMENT. CLEAN, REPAIR OR REPLACE PARTS AS REQUIRED. WORFM Comments IF A TEST IS INTENDED, ISOLATE ITEMS SUCH AS DUMP VALVES, WHICH, IF OPERATED, WILL CAUSE UNNECESSARY WASTE OF GAS OR CHEMI OR MIGHT CAUSE AN UNWANTED SHUTDOWN OF EQUIPMENT. CLEAN, REPAIR OR REPLACE PARTS AS REQUIRED. TEST THE DEVICE BY INTRODUCING AN INPUT SIGNAL OR SIMULATED CONDITION THAT CAUSES THE DEVICE TO ACTIVATE, PRODUCING AN OUTPUT RESPONSE THAT WILL SHUTDOWN OR ISOLATE EQUIPMENT OR CAUSE OPERATION OF VALVES OR EQUIPMENT. ACTUAL EQUIPMENT				Scheduled End Date	2
30.301-4A,5F,G,I-TEST REMOTE SHUTDOWN DEVICES ANNUALLY Form Number: Standard WO Performed Every: 1 Years Meter Interval: Equipment 59153 Comment: Manufacturer Model Serial Number Location IF A TEST IS INTENDED, ISOLATE ITEMS SUCH AS DUMP VALVES, WHICH, IF OPERATED, WILL CAUSE UNNECESSARY WASTE OF GAS OR CHEMI OR MIGHT CAUSE AN UNWANTED SHUTDOWN OF EQUIPMENT. CLEAN, REPAIR OR REPLACE PARTS AS REQUIRED. TEST THE DEVICE BY INTRODUCING AN INPUT SIGNAL OR SIMULATED CONDITION THAT CAUSES THE DEVICE TO ACTIVATE, PRODUCING AN OUTPUT RESPONSE THAT WILL SHUTDOWN OR ISOLATE EQUIPMENT OR CAUSE OPERATION OF VALVES OR EQUIPMENT. ACTUAL EQUIPMENT. ACTUAL EQUIPMENT. ACTUAL EQUIPMENT. ACTUAL EQUIPMENT. ACTUAL EQUIPMENT OR CAUSE OPERATION OF VALVES OR EQUIPMENT. ACTUAL EQUIPMENT OR CAUSE OPERATION OF VALVES OR EQUIPMENT. ACTUAL EQUIPMENT					OKE10880 -
Performed Every: 1 Years Performed Every: 1 Years Meter Interval: Equipment 59153 STATION HIGH PRESSURE SHUTDOWN Comment: Manufacturer Model Serial Number Location IF A TEST IS INTENDED, ISOLATE ITEMS SUCH AS DUMP VALVES, WHICH, IF OPERATED, WILL CAUSE UNNECESSARY WASTE OF GAS OR CHEMI OR MIGHT CAUSE AN UNWANTED SHUTDOWN OF EQUIPMENT. CLEAN, REPAIR OR REPLACE PARTS AS REQUIRED. TEST THE DEVICE BY INTRODUCING AN INPUT SIGNAL OR SIMULATED CONDITION THAT CAUSES THE DEVICE TO ACTIVATE, PRODUCING AN OUTPUT RESPONSE THAT WILL SHUTDOWN OR ISOLATE EQUIPMENT OR CAUSE OPERATION OF VALVES OR EQUIPMENT. ACTUAL EQUIPMENT	Form Number:		TE SHUTDOWN DEVICES ANNUALLY	Assigned By	Νο
Meter Interval: Time Completed // 3 - 0/3 Equipment 59153 STATION HIGH PRESSURE SHUTDOWN Comment: Manufacturer Model Serial Number Location WO/FM Comments IF A TEST IS INTENDED, ISOLATE ITEMS SUCH AS DUMP VALVES, WHICH, IF OPERATED, WILL CAUSE UNNECESSARY WASTE OF GAS OR CHEMI OR MIGHT CAUSE AN UNWANTED SHUTDOWN OF EQUIPMENT. CLEAN, REPAIR OR REPLACE PARTS AS REQUIRED. TEST THE DEVICE BY INTRODUCING AN INPUT SIGNAL OR SIMULATED CONDITION THAT CAUSES THE DEVICE TO ACTIVATE, PRODUCING AN OUTPUT RESPONSE THAT WILL SHUTDOWN OR ISOLATE EQUIPMENT OR CAUSE OPERATION OF VALVES OR EQUIPMENT. ACTUAL EQUIPMENT		1 Maara			-8-08
Equipment 59153 STATION HIGH PRESSURE SHUTDOWN Comment:	_	i feats		-	7-8-08 1410
Model Serial Number Location IF A TEST IS INTENDED, ISOLATE ITEMS SUCH AS DUMP VALVES, WHICH, IF OPERATED, WILL CAUSE UNNECESSARY WASTE OF GAS OR CHEMI OR MIGHT CAUSE AN UNWANTED SHUTDOWN OF EQUIPMENT. CLEAN, REPAIR OR REPLACE PARTS AS REQUIRED. TEST THE DEVICE BY INTRODUCING AN INPUT SIGNAL OR SIMULATED CONDITION THAT CAUSES THE DEVICE TO ACTIVATE, PRODUCING AN OUTPUT RESPONSE THAT WILL SHUTDOWN OR ISOLATE EQUIPMENT OR CAUSE OPERATION OF VALVES OR EQUIPMENT. ACTUAL EQUIPMENT			STATION HIGH		
IF A TEST IS INTENDED, ISOLATE ITEMS SUCH AS DUMP VALVES, WHICH, IF OPERATED, WILL CAUSE UNNECESSARY WASTE OF GAS OR CHEMI OR MIGHT CAUSE AN UNWANTED SHUTDOWN OF EQUIPMENT. CLEAN, REPAIR OR REPLACE PARTS AS REQUIRED. TEST THE DEVICE BY INTRODUCING AN INPUT SIGNAL OR SIMULATED CONDITION THAT CAUSES THE DEVICE TO ACTIVATE, PRODUCING AN OUTPUT RESPONSE THAT WILL SHUTDOWN OR ISOLATE EQUIPMENT OR CAUSE OPERATION OF VALVES OR EQUIPMENT. ACTUAL EQUIPMENT	Model Serial Number				