

July 2010 Construction Photos



Setting up dewatering for canal on the east side of Red Bank Creek.




Driving sheet piles near the existing Tehama-Colusa & Tehama-Corning Canal settling basin.

July 2010 Construction Photos



Driving sheet piles towards the settling basin.



Excavating out the canal on the east side of Red Bank Creek.

July 2010 Construction Photos



More excavating out the canal on the east side of Red Bank Creek.



Driving sheet pile inside the settling basin.

July 2010 Construction Photos



Cofferdam of sheet piles for the connection to the existing settling basin of the Tehama-Colusa Canal.



Balfour Beatty mobilizing onsite.