

May 2012 Construction Photos



Subcontractor FD Thomas coating the roof hatches to match building roof color



Subcontractor Central Sierra Electric installing the Arc Flash plenum ducting.

May 2012 Construction Photos



Start of pump test water flow in canal transition.



Pump and Motor #9 monitoring equipment and data collection

May 2012 Construction Photos



Subcontractor Central Sierra landing conductors in electrical distribution panel DCA.



Subcontractor Central Sierra drilling holes for the exterior lights on the downstream side of the control building.

May 2012 Construction Photos



Balfour Beatty laborer making concrete repairs at the afterbay wall and canal transition sheet pile wall.



Subcontractor Meyers Earth Work constructing drainage ditch along the switchyard access road