

Fontenelle Dam & Powerplant – Sept. 2010



RECLAMATION



RECLAMATION



RECLAMATION

April 28, 2009



RECLAMATION

May 4, 2009



RECLAMATION

May 11, 2009



RECLAMATION



bladder dams
small
large

6-inch discharge lines

3 floating pumps
10-inch discharge

3 submersible pumps
6-inch discharge

dentates


boat

chute blocks

RECLAMATION



RECLAMATION




RECLAMATION




RECLAMATION



RECLAMATION





4 sump pumps

2 of 3 submersible pumps

cobble and gravel

Estimated 400 gpm flow
from the drain exiting chute
block #2.

chute block #2

RECLAMATION



RECLAMATION



1967



1967



1967

RECLAMATION





RECLAMATION



RECLAMATION




RECLAMATION



RECLAMATION



RECLAMATION



RECLAMATION



RECLAMATION



RECLAMATION



RECLAMATION