

Hanford Site Waste Management Units Report

Prepared for the U.S. Department of Energy
Assistant Secretary for Environmental Management

Contractor for the U.S. Department of Energy
under Contract DE-AC06-08RL14788



**P.O. Box 1600
Richland, Washington 99352**

Hanford Site Waste Management Units Report

Document Type: RPT

J. P. Shearer
CH2M HILL Plateau Remediation Company

Date Published
February 2016

Prepared for the U.S. Department of Energy
Assistant Secretary for Environmental Management

Contractor for the U.S. Department of Energy
under Contract DE-AC06-08RL14788


P.O. Box 1600
Richland, Washington 99352

APPROVED

By Ashley Jenkins at 2:39 pm, Feb 17, 2016

Release Approval

Date

Approved for Public Release;
Further Dissemination Unlimited

TRADEMARK DISCLAIMER

Reference herein to any specific commercial product, process, or service by tradename, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof or its contractors or subcontractors.

This report has been reproduced from the best available copy.

Printed in the United States of America

TABLE OF CONTENTS

INTRODUCTION	1
OPERABLE UNIT:	
100-BC-1.....	3
100-BC-2.....	79
100-DR-1.....	122
100-DR-2.....	279
100-FR-1.....	320
100-FR-2.....	431
100-HR-1.....	447
100-HR-2.....	522
100-IU-1.....	541
100-IU-2.....	545
100-IU-3.....	621
100-IU-4.....	625
100-IU-5.....	626
100-IU-6.....	627
100-KR-1.....	696
100-KR-2.....	714
100-NR-1.....	819
200-BC-1.....	986
200-CB-1.....	1005
200-CP-1.....	1014
200-CR-1.....	1026
200-CU-1.....	1031
200-CW-1.....	1036
200-CW-3.....	1045
200-CW-5.....	1060
200-DV-1.....	1065
200-EA-1.....	1096
200-IS-1.....	1166
200-OA-1.....	1214
200-PW-1.....	1264
200-PW-3.....	1269
200-PW-6.....	1273
200-SW-1.....	1276
200-SW-2.....	1278

200-WA-1	1293
300-FF-1	1376
300-FF-2	1411
1100-EM-1	1567
1100-EM-2	1572
1100-EM-3	1576
1100-IU-1	1580
WMA A/AX	1586
WMA B/BX/BY	1603
WMA C	1647
WMA S/SX	1667
WMA T	1689
WMA TX/TY	1702
WMA U	1724
Not Applicable	1745
TBD	2439

INTRODUCTION

SCOPE AND PURPOSE

The Hanford Site Waste Management Units Report (HSWMUR) has been created to meet the requirements of the Tri-Party Agreement (TPA) Action Plan, Section 3.5, which states: “The Hanford Site Waste Management Units Report shall be generated, in a format agreed upon by the Parties, as a calendar year report and issued annually by the DOE by the end of February of each year, and posted electronically for regulator and public access. This report shall reflect all changes made in waste management unit status during the previous year.”

This February 2016 version of the HSWMUR contains a comprehensive inventory of the 3455 sites and 581 subsites in the Waste Information Data System (WIDS). The information for each site contains a description of each unit and the waste it contains, where applicable. The WIDS database provides additional information concerning the sites contained in this report and is maintained with daily changes to these sites.

DEFINITIONS

The HSWMUR shows the classification and reclassification designations for each site. These designations are based on definitions in TPA procedure TPA-MP-14. Simplified definitions are provided below. Full definitions can be found in the procedure which is available at the following URL: <http://www.hanford.gov/files.cfm/TPA-MP14.pdf>.

Classification designations are as follows:

- Accepted – The site has been evaluated and found to be a waste management unit. For sites added to WIDS since February 2, 2007, the approval date for TPA-MP-14 Rev. 1, this evaluation has also been approved by the appropriate regulatory agency. Sites added prior to February 2, 2007 were classified as Accepted based only on a contractor review.
- Accepted (Proposed) – The site has been evaluated and tentatively identified as being a waste management unit, but this evaluation has not yet been approved by the appropriate regulatory agency.
- Rejected – The site has been evaluated and found not to be a waste management unit. This evaluation has been approved by the appropriate regulatory agency.
- Rejected (Proposed) – The site has been evaluated and tentatively identified as not being a waste management unit, but this evaluation has not yet been approved by the appropriate regulatory agency.
- Discovery - The site has not yet had the evaluation completed.

Reclassification designations are as follows:

- Interim No Action – The site does not require any action based on an assessment of quantitative data (e.g. analytical samples) against the cleanup standards specified in an Interim Action Record of Decision.
- Final No Action – The site does not require any action based on an assessment of quantitative data (e.g. analytical samples) against the cleanup standards specified in a Final Record of Decision.
- Interim Closed Out – The site meets cleanup standards specified in an Interim Action Record of Decision.
- Final Closed Out – The site meets cleanup standards specified in a Final Record of Decision.
- Closed Out – The site meets other applicable cleanup standards or closure requirements.
- RCRA Postclosure – The site is a TSD unit that has been closed with waste in place and postclosure care, including monitoring and institutional controls, is being implemented.
- Rejected – The site does not require remediation based on qualitative information such as a review of historical records, photographs, drawings, walkdowns, ground penetrating radar scans, radiation surveys, and shallow test pits
- Consolidated – The site will be dispositioned as part of another WIDS site.
- Deleted from NPL – The site is deleted from the National Priorities List or included in a final action published in the Federal Register.
- None – The site has not been reclassified.

ORGANIZATION

The waste management units at the Hanford Site are grouped into operable units (OUs) or waste management areas (WMAs). The groupings may be based on geographic location, types of waste received, and/or the ability to achieve economies of scale during remediation. Sites flagged as TBD (To Be Determined) haven't been assigned to an OU or WMA. Sites flagged as Not Applicable do not fit the criteria to be assigned to an OU or WMA. The HSWMUR organization is based on the waste site grouping within the operable units and waste management areas.

100-BC-1

Code: 100-B-2 **Classification:** Accepted
Names: 100-B-2; 181-B Backwash Trench; Backwash Trench; Miscellaneous Stream #73; Undocumented Liquid Waste Site **Reclassification** Interim No Action (11/18/2004)
Type: Trench **Start Date:** 1/1/1975
Status: Inactive **End Date:**

Description: The waste site has been evaluated and reclassified to No Action. It was a trench that was constructed to receive backwash filter backflush from the 181-B Pumphouse. The trench was fed by a single 30 centimeter (12 inch) pipeline that originated at the backwash filter. The pipe was approximately 0.9 meters (3 feet) below grade. It entered the trench from the west.

Location: The site was located east of the 181-B pumphouse and outside the exclusion area perimeter fence.

Related Sites/ Structures: The site is related to the 181-B Pumphouse.

Process Description: The trench was constructed to receive backwash filter backflush from the 181-B Pumphouse. Before construction of the trench, the backflush water was returned directly to the Columbia River.

Waste Type: Water

Waste Description: The site received river screen backwash water effluent.

Closure Info: Interim (11/18/2004): WIDS Reclassification form 2004-101 states the site received river water after it was filtered through the backwash filter screen. No hazardous or radioactive contaminants were included in the filter backwash process. The waste site was Reclassified to No Action.

Code: 100-B-3 **Classification:** Accepted
Names: 100-B-3; Hot Thimble Burial Ground; Undocumented Solid Waste Site **Reclassification** Interim No Action (4/2/2003)
Type: Burial Ground **Start Date:** 1/1/1952
Status: Inactive **End Date:**

Description: The waste site has been evaluated in the Calculation Brief for the 100-B-3 Hot Thimble Burial Ground (0100B-CA-V-0116) and reclassified with a Waste Site Reclassification form to No Action. It was a vertically buried structure that was removed prior to 1956.

Location: The site was located south of the 105-B Reactor and west of the southwest corner of the 115-B Building.

Waste Type: Equipment

Waste Description: A highly contaminated vertical thimble was removed from the 105-B Reactor Building in 1952 and temporarily buried in a trench. The thimble was later removed and taken to another burial ground. Radioactive contaminants may remain in the trench.

Closure Info: Interim (4/2/2003): The vertical thimble that was placed at this site in 1952 was removed prior

to 1956. Based on process knowledge, the radionuclides that are associated with vertical thimbles are Mn-54, Co-60, and Zn-65. These are the contaminants of concern that would have been the residual contamination remaining in the excavation after removal of the thimble. They would have decayed away in the 51 years (approximately 10 half-lives, for Co-60, the longest-lived of the three) since burial. A 2003 geophysical survey of the area shows no evidence of the thimble remaining.

The 100-B-3 Hot Thimble Burial Ground requires no further action to meet the cleanup standards specified in the Interim Action Record of Decision for the 100-BC-1 100-BC-2, 100-DR-1, 100-DR-2, 100-FR-1, 100-FR-2, 100-HR-1, 100-HR-2, 100-KR-1, 100-KR-2, 100-IU-2, 100-IU-6, and 200-CW-3 Operable Units, (Remaining Sites ROD).

The calculation brief was based on a review of historical data and facility information, no sampling was necessary to confirm the status of this site because original documentation explained that the vertical thimble was buried in 1952 and removed prior to 1956. Also that the contamination remaining in the excavation (where the thimble was removed) were short-lived radionuclides, all with half-lives of less than 5.27 years. After 10 half-lives have elapsed, a radionuclide is considered to have decayed away. A geophysical survey over a larger area showed no evidence of a remaining buried thimble nor the conclusive location of an old burial site. Thus, while a possible location for the burial site can be estimated from old photographs, the actual location is unknown. Test pit results, even if the correct location was sampled, would prove inconclusive since the thimble has been removed and the short-lived radionuclides have decayed.

The calculation brief demonstrated that, based on a preponderance of the information, the 100-B-3 Buried Thimble Site no longer exists. No concentrations of the potential contaminants of concern for this site could remain above the RAGS established in the approved ROD and Remedial Design Report/Remedial Action Work Plan for the 100 Area, RDR/RAWP due to decay of the short-lived radionuclides. These results also indicate that the site will support future land uses that can be represented (or bounded) by a rural-residential scenario, and that the site poses no threat to groundwater or the Columbia River.

Code:	100-B-5	Classification:	Accepted
Names:	100-B-5; 105-B Effluent Vent Trench; 116-B-9; Effluent Vent Disposal Trench	Reclassification	Interim Closed Out (9/11/2003)
Type:	Trench	Start Date:	1/1/1954
Status:	Inactive	End Date:	1/1/1956
Description:	The site has been remediated and closed out. The waste site was the result of leakage that occurred at a junction box [probably at the 0.61 meter (2-foot) vent pipe], where the 1.4 meter (54-inch) 100-B Reactor cross tie pipeline effluent joined the 1.7 meter (66-inch) 100-C Reactor pipeline effluent, resulting in contamination of the area (Dorian and Richards).		
Location:	The site was believed to be located east of the 105-B Reactor Building, west of the 100-C Reactor effluent pipeline, north of the 100-B Reactor effluent cross tie pipeline, and north of the junction box where the east-west 100-B effluent pipeline joined the north-south 100-C effluent pipeline. The site location was identified as site number 23 on site drawing H-1-4049.		
Related Sites/ Structures:	Associated sites include the 100-C-6 and 100-B-8 Reactor Cooling Water Effluent Underground Pipelines.		
Process Description:	The junction box (part of site 100-C-6, 100-C Reactor Cooling Water Effluent Underground Pipelines, but pertinent to this site) was a concrete structure that was 5.6 meters (18.5 feet) long by 5.6 meters (18.5 feet) wide by 8.2 meters (27 feet) deep. The outer walls of the structure		

were 0.46 meters (1.5 feet) thick. Two sides of the structure were double-walled providing the structure with two chambers. The 1.4-meter (54-inch) 100-B Reactor cross tie pipeline (invert) entered from the west through a double concrete wall, while the 1.7-meter (66-inch) 100-C Reactor pipeline (invert) entered the structure from the south through a single concrete wall. A single 1.7-meter (66-inch) pipeline exited the structure to the north through the double walled portion of the structure. The interior of the structure was accessible via metal ladder rungs. The original structure had a 0.61-meter (2-foot) vent pipe. The vent pipe was located approximately 2.35 meters (7.7 feet) southwest of the southwest corner of the junction box. The vent was above grade 1.4 meters (4.6 feet) and had a valve on the top. A new 0.31-meter (12-inch) vent pipe was added later. The vent pipe was located approximately 2.3 meters (7.5 feet) south and 1.8 meters (6 feet) east of the southwest corner of the junction box. The vent was above grade approximately 1 meter (3.3 feet) (pipe + valve handle) and had a valve handle on the top. The effluent flowed out of the junction box via the 1.7-meter (66-inch) pipeline and downhill (gravity flow since there was no pump station at 100-B) to the retention basins. On the 100-C effluent pipeline north of the junction box about 80 meters (262 feet) was an inspection manhole. The manhole (riser) was marked "Confined Space 063" and "Fixed Contamination Area FCA-B-0003".

Waste Type: Process Effluent

Waste Description: The waste was process effluent contaminated soil. Sample numbers (Dorian and Richards) and depths were: B - 4.6, 6.1, 8.4 meters (15, 20, 27.5 feet); C - 3.05 meters (10 feet); D - 4.6, 6.1, 8.4 meters (15, 20, 27.5 feet); E - 4.6, 5.3, 7.6 meters (15, 17.5, 25 feet); F - 4.6, 6.1, 8.4 meters (15, 20, 27.5 feet); H - 6.1 meters (20 feet). Samples were analyzed for plutonium-238, plutonium-239/240, strontium-90, hydrogen-3, europium-152, cobalt-60, europium-154, cesium-234, cesium-137, europium-155, and uranium.

Closure Info: Interim: Remedial action at the 100-B-5 site was conducted in May 2003. Excavation of the 100-B-5 site involved removing the overburden materials, removing sections of the 100-C-6 and 100-B-8 Reactor effluent pipelines, removing a pipeline junction box, and removing contaminated soil. Contaminated materials including the pipeline sections and concrete junction box were disposed of at the ERDF. Cleanup demonstration of the reactor effluent pipelines will be included in a future CVP and will reference this CVP for the small section of pipelines remediated With the 100-B-5 site.

Remedial action objectives (RAOs) and goals (RAGs) for the site were documented in the Interim Action Record of Decision for the 100-BC-1, 100-BC-2, 100-DR-1, 100-DR-2, 100-FR-1, 100-FR-2, 100 HR-1, 100 HR-2, 100-KR-1, 100-KR-2, 100-IU-2, 100-IU-6, and 200-CW-3 Operable Units (ROD) and the Remedial Design Report/Remedial Action Work Plan for the 100 Area (RDR/RAWP). Excavation was driven by remedial action objectives for direct exposure, protection of groundwater, and protection of the Columbia River.

At the completion of the remedial action, the total excavation was approximately 4,450 square meters (47,900 square feet) in area with a maximum depth of 8.5 meters (27.9 feet) below ground surface. Approximately 16,320 metric tons (17,950 tons) of material from the site were disposed of at the Environmental Restoration Disposal Facility. In addition to the 100-B-5 site, the portions of the 100 B-8 and 100-C-6 Reactor cooling water effluent pipelines beneath the site were remediated with the 100-B-5 site. Cleanup verification of the rest of the adjacent large pipeline sites (100-C-6 and 100-B-8) will be included in the CVPs for those sites.

The CVP has demonstrated that remedial action at the site has met the RAOs and corresponding RAGs established in the ROD and RDR/RAWP. The remaining soils at the site have been sampled, analyzed, and modeled. The results of this effort indicated that the material from the site containing COCs at concentrations exceeding RAGs have been excavated and disposed at the ERDF. These results also indicate that residual concentrations in the shallow zone will support future land uses that can be represented (or bounded) by a rural-residential scenario and

that residual concentrations throughout the site do not pose a threat to groundwater or the Columbia River.

Code:	100-B-8	Classification:	Accepted
Names:	100-B-8; 100-B Reactor Cooling Water Effluent Underground Pipelines	Reclassification	Interim Closed Out (4/20/2004)
Type:	Radioactive Process Sewer	Start Date:	1/1/1944
Status:	Inactive	End Date:	1/1/1968

Description: 100-B-8 was divided into two subsites. Both subsites have been remediated and Interim Closed Out, therefore the parent site is also considered Interim Closed Out. The waste site is comprised of the underground 100-B Reactor cooling water effluent pipelines. Subsite 1 was the effluent lines south of 105-B. Subsite 2 was the effluent lines north of 105-B. The waste site included the effluent pipelines that transported 118-B-8 (105-B Reactor) cooling water from the reactor core to the 116-B-11 (107-B) Retention Basin, and from the basin to the 116-B-7 (1904-B) outfall structure. This waste site included all associated expansion and valve boxes and excluded the retention basin, outfall structure, and those effluent pipelines that were within the confines of the 105-B Reactor Building or that run from the outfall structure to the bottom of the river. It also excludes all reactor influent pipelines that are upstream (untreated and treated water pipelines) of the 105-B Reactor Building.

Location: The site included of all the underground reactor effluent lines running from the 105-B Reactor Building to the Columbia River. This includes segments between the reactor building and the retention basin, and between the basin and the outfall structure. It excludes the reactor building (and a 7.6 meter [25 foot] buffer zone for the B Reactor Museum), retention basin, and outfall structure, each of which is treated as a unique waste site. Also included are the cross-tie underground lines (one north and one south) that connect the 100-B Reactor effluent system to the 100-C Reactor effluent system (100-C-6).

Related Sites/ Structures: Related structures include the 116-B-11 (107-B) Retention Basin, the 116-B-7 (1904-B) Outfall, the 105-B Reactor, the 100-C-6 Effluent Pipelines, and the 100-B-15 River Pipelines.

Process Description: Effluent water passed from the reactor rear face and gravity flowed through the underground effluent pipelines, junction boxes and diversion boxes to the retention basins where it was held up for a short period of time to allow thermal and radiological cooling before being released through the outfall structure to the Columbia River. During periods of reactor fuel cladding ruptures, some effluent was diverted to an open trench.

Waste Type: Process Effluent

Waste Description: The waste is radioactively contaminated steel piping, concrete, and soil. Reactor cooling water became radioactively contaminated as it passed through the reactor core. Activation products created in the water included calcium-41, chromium-51, and zinc-65. Activation products from the reactor core that were picked up and transported by the cooling water included tritium, carbon-14, cobalt-60, nickel-63, and europium-152/154/155. Fuel element fission products, such as strontium-90, and cesium-137, as well as transuranics such as plutonium-239/240 were introduced into cooling water due to fuel cladding failures. Concentrations of radionuclides in cooling water during normal reactor operations were approximately 0.2 microcuries/liter. Concentrations of radionuclides have built up in rust flakes and scale on the inner surfaces of the pipelines and in sludge in the diversion and junction boxes. Average beta-gamma concentrations for the effluent pipeline scale and junction/diversion boxes were 83,000 and 120,000 picocuries/liter, respectively. Average plutonium-239/240 concentrations were 66 picocuries/gram for the effluent pipeline scale and 720 picocuries/gram for the sludge at the bottom of the diversion and junction boxes. Direct readings of the bottom of the effluent

pipelines averaged approximately 40,000 counts/minute with a Geiger-Mueller probe. Additional chemicals were added to the effluent for purposes of water treatment. These included aluminum sulfate (alum), with excess hydrated calcium oxide, sulfuric acid, chlorine, and sodium dichromate. Water pH was maintained at about 7.5, and the free chlorine residual was approximately 0.2 milligrams/liter.

This Site has the Following SubSites:

Code: 100-B-8:1
Names: 100-B-8:1; 100-B Area South Effluent Pipelines
Code: 100-B-8:2
Names: 100-B-8:2; 100-B Area North Effluent Pipelines

Code: 100-B-8:1	Classification: Accepted
Names: 100-B-8:1; 100-B Area South Effluent Pipelines	Reclassification Interim Closed Out (4/20/2004)
Type: Radioactive Process Sewer	Start Date:
Status: Inactive	End Date:

Description: The subsite has been remediated and Interim Closed Out. The site included the underground 105-B Reactor effluent pipelines running from within 7.5 meters (25 feet) of the reactor building north to B Avenue, including all associated expansion joints and valve boxes. Also included are the cross-tie underground lines that connected the 105-B Reactor effluent system to the 105-C Reactor effluent pipeline system.

Location: Subsite 100-B-8:1 includes the underground effluent pipelines surrounding the 105-B Reactor (excluding a 7.6 meter [25 foot] buffer zone around the reactor foundation), and running north from the reactor to B Avenue, including all associated expansion joints and valve boxes.

Waste Type: Not Specified

Waste Description: The waste is radioactively contaminated steel piping, concrete, and soil.

Closure Info: Interim: At the completion of remedial action, the excavation was approximately 48,260 square meters (519,466 square feet) in area. Approximately 244,656 metric tons (269,742 tons) of material, including soil, debris, and piping were removed from the 100-B/C south pipelines site and disposed of at the Environmental Restoration Disposal Facility. The remaining soils at these sites have been sampled, analyzed, and modeled, while contaminated material has been excavated and disposed at ERDF. These results also indicated that residual concentrations in the shallow zone will support future land uses that can be represented (or bounded) by a rural-residential scenario, and that residual concentrations throughout the site pose no threat to groundwater or the Columbia River. The site was verified to be remediated in accordance with the ROD and may be backfilled.

The SubSite is Part Of:

Code: 100-B-8
Names: 100-B-8; 100-B Reactor Cooling Water Effluent Underground Pipelines

Code: 100-B-8:2	Classification: Accepted
Names: 100-B-8:2; 100-B Area North Effluent Pipelines	Reclassification Interim Closed Out (2/17/2004)
Type: Radioactive Process Sewer	Start Date:
Status: Inactive	End Date:

Description: Cleanup Verification Package 2003-00019 (CVP) documented completion of remedial action for the 100-B/C Effluent Pipeline subsites located north of B Avenue (100-B-8:2, 100-C-6:2, 100-C-6:3, and 100-C-6:4 collectively referred to as the 100-B/C north pipelines site). The 100-B-8:2 subsite portion includes the 105-B Reactor effluent pipelines from B Avenue north to the 116-B-1 Trench, the pipelines from the 116-B-11 Retention Basin to the 116-B-7 Outfall (located just north of pipelines 3 and 4 terminations), and the east-west connecting pipeline from 100-B-8:2 to the diversion box for the 100-C-6 pipelines, which was just south of the 116-C-5 Retention Basin. It also includes the pipeline connecting this diversion box to the 116-C-5 Retention Basin and the northernmost section of pipe 11 that drained into the 116-C-5 Retention Basin; these pipelines were removed and backfilled but not entirely sampled as part of the 116-C-5 remedial action (BHI 1997).

Cleanup verification for pipes 11 and 25 were conducted as part of CVP-2003-00019. Drawings identifying previous sampling locations were used to ensure that pipe 11 and pipe 25 corridors were excavated to below clean backfill elevations prior to verification sampling.

Location: These pipelines were north of the 105-B Reactor, north of B Avenue to the outfall structure.

Waste Type: Not Specified

Waste Description: The waste is radioactively contaminated steel piping, concrete, and soil.

Closure Info: Interim: Remedial action at the 100-B/C north pipelines site began on February 26, 2001. Excavation of the site involved removing the overburden materials, piping, debris, and underlying contaminated soil. Based on field screening overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Contaminated materials were disposed of at ERDF. At the completion of remedial activities at the 100-B/C pipeline waste sites, more than 364 metric tons (400 tons) of concrete and fence posts with associated concrete debris were removed and segregated as part of the 100-B/C Pipeline Remediation Project (100-BC-1/100-BC-2 Operable Units). The majority of the fence posts are associated with security fencing that surrounded many of the pipelines and waste sites. None of the fence material has been known to be contaminated. External radiological surveys indicate that none of the concrete and fence posts show any, signs of radioactive contamination. Radiological release surveys of the fence posts and concrete were performed to allow them to be used as clean backfill. The Environmental Restoration Contractor radiological survey records for 100-B/C remediation between the dates of February 26, 2001 and November 6, 2003, contain survey results for the fencing debris used as backfill. The excavation was completed on February 6, 2003.

Excavation was driven by remedial action objectives for direct exposure, protection of groundwater, and protection of the Columbia River. For the respective points of compliance, remedial action goals (RAGs) were established to identify radionuclide and non-radionuclide contaminants of concern (COCs). Cleanup verification samples including QA/QC samples consisted of 193 shallow zone samples, 104 deep zone samples, 260 overburden samples, and 72 discovery area samples. The final verification samples were collected between August 12, 2002, and concluded on July 24, 2003, and were analyzed for the established contaminants of concern. The sample numbers are too numerous to list, however they are available in appendix A of CVP-2003-00019. At the completion of remedial action, the excavation was approximately 135,000 square meters (443,000 square feet) in area with an average depth of approximately 7.5 meters (25 feet). Approximately 244,656 metric tons (269,742 tons) of material including soil, debris, and piping were removed from the 100 B/C north pipelines site and disposed at the Environmental Restoration Disposal Facility.

The SubSite is Part Of:

Code: 100-B-8
Names: 100-B-8; 100-B Reactor Cooling Water Effluent Underground Pipelines

Code: 100-B-10 **Classification:** Accepted
Names: 100-B-10; 107-B Basin Leak and Warm Springs **Reclassification:** Interim No Action (4/11/2002)
Type: Unplanned Release **Start Date:** 1/1/1949
Status: Inactive **End Date:**

Description: The waste site was evaluated and determined to require No Action. The site is an unknown location along the Columbia River shoreline. It was reported in February 1949 as a warm springs below the 116-B-11 Retention Basin, and was attributed to leaks in the wall of the north basin. This spring no longer exists and the precise location is unknown. The reported spring is assumed to have stopped flowing after the basins were shut down. The groundwater that fed the spring is a separate Operable Unit (100-BC-5).

Location: The springs were observed along the Columbia River below the 100-B Area Retention Basin (116-B-11).

Related Sites/ Structures: The springs were attributed to leaks in the walls of the north basin at 107-B (116-B-11).

Process Description: In 1991 in preparation for a spring sampling study, the entire shoreline of the River in the 100 Areas was searched for springs. Three were found at the 100-BC Area, all upstream (about 700 meters [2,300 feet]) of the estimated location of this spring. No springs were found below the 116-B-11 Retention Basin. The reported spring is assumed to have stopped flowing after the basins were shut down.

Waste Type: Water

Waste Description: A sample of the water showed beta activity of 4E-03 microcuries/liter.

Closure Info: Interim: This was determined to be a No Action site.

This is not a site where wastes have been disposed or spilled, but was the location where groundwater contaminated from the 116-B-11 Retention Basin exited the riverbank in 1949. Previous radiation surveys of the shoreline in 1966 (J.D. Lodge, Radiation Survey of the Columbia River Shoreline Near the Hanford Reactor Areas, BNWL-CC-835) showed no elevated radiation in this area. In 1980 (per PNL-3127) a reading of 125 uR/hour was documented but the actual location was not provided. Only a general location below the retention basin was listed. More detailed tables of the 100-B shoreline radiation readings in PNL-3127 show from 5 to 100 uR/hour. In preparation for a 1991 spring sampling study, the entire shoreline of the River in the 100 Areas was searched for springs. Three were found at the 100-BC Area, all upstream (about 700 meters [2,300 feet]) of the estimated location of this spring. No springs were found at or near the River shoreline below the 116-B-11 Retention Basin.

The 116-B-11 Retention Basin and underlying plumes that led to the river from old spills have been remediated and closed out to the cleanup standards as specified in the Interim Action Record of Decision for the 100-BC-1, 100-DR-1, and 100-HR-1 Operable Units (EPA 1995), and the Remedial Design Report/Remedial Action Work Plan for the 100 Area (DOE-RL 1998). It is expected that since the underlying plumes have been excavated and remediated until they met cleanup criteria, any deeper zones (closer to the river and farther from the source retention basin) would have less remaining contamination. In addition, the groundwater that fed the spring is a separate Operable Unit (100-BC-5); it and associated remaining contaminants

will be addressed as part of that project.

Code: 100-B-11	Classification: Accepted
Names: 100-B-11; 115-B Tank; 115-B/C Caisson Site; 115-B/C Caisson Valve Pit; 115-BC Drywell; 115-BC Sump	Reclassification: Interim No Action (7/15/2004)
Type: Storage Tank	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1969

Description: The site has been evaluated and reclassified to No Action. This caisson was identified during a pre-demolition walk-through of the 115-B/C Gas Recirculation Building and was removed during building demolition. The site had been a steel pipe structure (caisson) about 1.2 meters (4 feet) in diameter and 1.5 meters (5 feet) deep with a bottom and a steel plate placed over the top. The site was self contained without any incoming or outgoing piping. This caisson was identified during a pre-demolition walk-through of the 115-B/C Gas Recirculation Building.

Location: The site was located just east of the 115-B/C Building Dryer Room #1 and approximately 60 meters (197 feet) south-southeast of the 105-B Reactor Building.

Release Description: The releases to the caisson are unknown. Sample results taken of soil from underneath and near the sides of the caisson were below Washington Administrative Code (WAC) limits for chromium.

Related Sites/Structures: The site was probably related to the 115-B/C Gas Recirculation Facility (132-B-5) that was demolished in 1989. The caisson was contaminated with sodium dichromate. Sodium dichromate was not normally used at the 115 B/C Gas Recirculation Facility.

Process Description: The site was a steel pipe structure (caisson) about 1.2 meters (4 ft) in diameter and about 1.7 meters (5.5 ft) deep with a bottom and a steel plate placed over the top. The site was self-contained without any incoming or outgoing piping. Its original purpose is not known, but it was located just outside of Dryer Room #1 of the 115-B/C Facility. This caisson was identified during a pre-demolition walk-through of the 115-B/C Gas Recirculation Building, and was removed during building demolition. The caisson contained sludge and water that was heavily contaminated with chromium, which was removed and disposed of during the demolition of the 115-B/C Building. Contaminated soil was also sampled and removed during excavation of the caisson.

Waste Type: Soil

Waste Description: Originally, the caisson contained a yellowish-colored soil which was sampled for pH and EP toxic metals. Sample results indicated a pH of 8 and 72,500 milligrams/liter of chromium. Additional samples were taken (after caisson removal) from soil directly underneath and around the outside of the caisson. Results from these samples showed chromium levels ranging from 0.08 milligrams/liter to 9.14 milligrams/liter. The caisson contained approximately 0.37 cubic meters (13 cubic feet) of chromate contaminated soil.

Closure Info: Interim: This caisson was identified during a pre-demolition walk-through of the 115-B/C Gas Recirculation Building and was removed during building demolition. The caisson contained sludge and water that was heavily contaminated with chromium, which was removed and disposed of during the 115-B/C Building demolition. The No Action decision for the 100-B-11 site is supported based on reviews of site history, field observations, and characterization results. The maximum detected results from underlying soil samples collected at locations suspected of having the greatest potential for residual contamination levels were shown to meet the cleanup objectives for direct exposure, groundwater protection, and river protection.

Code: 100-B-12 **Classification:** Accepted
Names: 100-B-12; Filter Box Radiological Materials Area (RMA) **Reclassification** Interim Closed Out (5/31/2001)
Type: Storage **Start Date:**
Status: Inactive **End Date:**

Description: The waste site has been Interim Closed Out. The site was a Radiological Materials area (RMA) with four metal boxes containing filters, that rested on shoring that sat on the bare soil. An additional six filter frames, marked as having fixed contamination, rested directly on the soil. The contaminated filter frames were removed and disposed at ERDF.

Location: The site is in the northwest corner of the 100-BC Area, at the approximate coordinates of E56500/N144800.

Waste Type: Equipment

Waste Description: The radiological contamination is fixed on the filter frames.

Closure Info: Interim: All contaminated filter frames have been disposed of at ERDF. Because the filter frames were solid waste, no releases to the soil are expected. A radiation survey was completed at the site after the frames were removed to document that the Radioactive Material Area could be downposted. The survey results met the requirement for downposting an RMA. The waste site Reclassified with a signed form 2001-016.

Code: 100-B-14 **Classification:** Accepted
Names: 100-B-14; 100-B Area Process and Sanitary Sewer Underground Pipelines **Reclassification** Interim Closed Out (3/1/2007)
Type: Process Sewer **Start Date:** 1/1/1944
Status: Inactive **End Date:** 1/1/1969

Description: The waste site encompassed pre-reactor underground process and sanitary pipelines and sewers. The waste was divided into seven subsites. All the subsites have been evaluated and reclassified to either Interim Closed Out or No Action. Therefore, the parent site has been reclassified to Interim Closed Out. The area was revegetated in 2007.

The subsites are:

- Subsite 1 - Main Process Sewer Collection Pipelines
- Subsite 2 - 115-B Sanitary Sewer Pipelines
- Subsite 3 - West Process Sewer Feeder Pipelines from 182-B and 183-B, Subsite 4 - Cooling Water Pipelines and Tunnels from 190-B
- Subsite 5 - Sodium Dichromate and Sodium Silicate Pipelines
- Subsite 6 - Process Sewer Feeder Pipeline from 184-B and 184-B Ash Slurry Line
- Subsite 7 - Process Sewer Feeder Pipelines from 185-B and 190-B.

Location: These pipelines were located mostly north and west of the 105-B Reactor and north of the 183-B Filter House. Most joined to empty into the 116-B-7 Outfall. Others emptied into the 126-B-1 Power House Ash Pit, and the 1607-B2 and 1607-B7 Septic Systems. The sodium dichromate pipeline connected the 108-B Laboratory and the 190-B building, and the treated reactor cooling water ran from the 190-B Facility to the 105-B Reactor.

Related Sites/ Structures: Buildings associated with these pipelines included the 105-B Reactor, 190-B Facility, 108-B Laboratory, 182-B and 183-B Filter Buildings, 184-B Power House, 115-B Filter House, and 1700-Series support buildings.

Process Description: These pipelines carried a variety of non-radioactive waste fluids, product (sodium dichromate), treated cooling water (pre-reactor), and sewage.

Waste Type: Equipment

Waste Description: The waste site consisted of abandoned process and sanitary sewer pipelines, and residual chemicals remaining on the pipes. Chemical additives to the reactor cooling water included aluminum sulfate (alum) with excess hydrated calcium oxide, sulfuric acid, chlorine, and sodium dichromate. Water pH was maintained at about 7.5, the free chlorine residual was approximately 0.2 milligrams/liter, and sodium dichromate was added at a rate of about 2 milligrams/liter. One length of the product piping held undiluted sodium dichromate: the pipe from the 185-B/190-B to the 108-B Building (per drawing M2913, Sheet 5). This pipeline was in use only for a few years, until the sodium dichromate was added to the cooling water at the 185-B Building. (Note: Reference: WHC-SD-EN-TI-169 is for 100-F, and applies equally to 100-B).

This Site has the Following SubSites:

Code: 100-B-14:1
Names: 100-B-14:1; Main Process Sewer Pipelines

Code: 100-B-14:2
Names: 100-B-14:2; Sanitary Sewer Pipelines

Code: 100-B-14:3
Names: 100-B-14:3; West Process Sewer Pipelines from 182-B and 183-B

Code: 100-B-14:4
Names: 100-B-14:4; Cooling Water Pipelines and Tunnels from 190-B

Code: 100-B-14:5
Names: 100-B-14:5; Sodium Dichromate and Sodium Silicate Pipelines

Code: 100-B-14:6
Names: 100-B-14:6; 184-B and 184-B Ash Slurry Line; Powerhouse Pipelines

Code: 100-B-14:7
Names: 100-B-14:7; 185-B and 190-B Sump and Pipelines

Code: 100-B-14:1	Classification: Accepted
Names: 100-B-14:1; Main Process Sewer Pipelines	Reclassification: Interim Closed Out (2/22/2007)
Type: Process Sewer	Start Date:
Status: Inactive	End Date:

Description: The subsite has been remediated and Interim Closed Out. The subsite encompassed the process sewer mainline that provided service to the 105-B, 108-B, 182-B, 183-B, 184-B and 185/190-B facilities and discharging to the 116-B-7 Outfall Structure and some feeder lines. The main process line site consisted of 1270 meters (4166 ft) of pipe ranging from 0.3 m (12 in.) diameter vitrified-clay pipe to 1.82 meter (72 in) diameter reinforced concrete pipe (RCP).

Location: The subsite consisted of the reinforced concrete process sewer main that formerly serviced the 105-B Reactor Building; the 108-B Chemical Pumphouse and Tritium Separation Facility; and 100-B water treatment facilities then discharged to the 116-B-7 Outfall Structure. Vitrified clay

feeder pipelines associated with the 108-B facility were also included in the subsite.

Waste Type: Not Specified

Waste Description: The waste site consists of abandoned process and sanitary sewer pipelines, and residual chemicals remaining on the pipes.

Closure Info: Interim: Remediation of the subsite was performed from January 2005 through April 2006 as part of the 100-B/C Area Remaining Pipes and Sewers remediation. The remediation of the pipelines consisted of the excavation and stockpiling (on-site) of overburden soils presumed to contain no residual contamination above cleanup levels, removal of soils around and approximately 0.3 meters (1 foot) below the pipelines; and disposal of the pipeline and suspect potentially contaminated soil at the Environmental Restoration Disposal Facility (ERDF).

Excavation at the upgradient (southeastern) end of the pipeline near the former 108-B facility was restricted within the shallow zone (less than 4.6 meters [15 feet] below ground surface [bgs]), and extended into the deep zone further downgradient, near the influent of the feeder line associated with the 105-B Reactor Building. The maximum depth of excavation was approximately 7.6 meters (25 feet) bgs, near the outfall of the pipeline at the northern end of the site. Due to co-location and concurrent remediation of differing functional pipeline groups, excavated and disposed material quantities could not be explicitly separated for the subsite. Following a determination that cleanup criteria had been attained, the excavation was backfilled with stockpiled overburden and borrow material. Railroad rails discovered and stockpiled during excavation of the site were also backfilled in the western portion of the excavation.

Initial cleanup verification sampling was conducted concurrently with variance sampling from May 30 to June 19, 2006. Additional verification sampling for carbon-14 in stockpiled overburden material was conducted from September 19 to 29, 2006. All verification samples were submitted to offsite laboratories for analysis using approved U.S. Environmental Protection Agency analytical methods as required per the Sampling and Analysis Plan (SAP). Based on process knowledge and the results of the confirmatory sampling activity for the subsite, this pipeline received radioactive waste stream discharges. Accordingly, the radioactive liquid waste effluent sites cleanup and closeout approach was implemented for the site, as described in the SAP.

The results of verification sampling illustrated that residual contaminant concentrations does not preclude any future uses (as bounded by the rural-residential scenario) and allow for unrestricted use of shallow zone soils (i.e., surface to 4.6 meters [15 feet] deep). The results also demonstrated that residual contaminant concentrations are protective of groundwater and the Columbia River. The acceptability of unrestricted exposure to deep zone portions of this site has not been demonstrated; therefore, institutional controls are required to prevent uncontrolled drilling/excavation into the deep zone.

The SubSite is Part Of:

Code: 100-B-14

Names: 100-B-14; 100-B Area Process and Sanitary Sewer Underground Pipelines

Code: 100-B-14:2

Classification: Accepted

Names: 100-B-14:2; Sanitary Sewer Pipelines

Reclassification: Interim Closed Out (3/21/2007)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This subsite has been remediated and Interim Closed Out. The subsite was further divided into

five service areas.

Service Area 1 is the 108-B and 17-3-B sanitary sewer pipelines and pipelines found during the 100-B-21 remediation.

Service Area 2 is the 1607-B7 sanitary sewer pipelines.

Service Area 3 is the 1700-B Series Support Buildings and 108-B Building were serviced by 15 and 20 centimeter (6 and 8 inch) vitrified clay pipes of various lengths.

Service Area 4 is the 190-B Pumphouse was serviced by 10, 15, and 20 centimeter (4, 6 and 8 inch) vitrified clay sewer pipes of various lengths.

Service Area 5 is the 115-B Gas Recirculation sanitary sewer site consists of approximately 311 meters (1020 feet) of 20 centimeter (8 inch) vitrified clay sewer pipe.

Location: The pipelines in this subsite were located in four areas: east of the 183-B Clearwells; north and east of the 190-B Pumphouse. The pipes exited the 115-B Gas Recirculation Facility and extended north on the east side of the 105-B Reactor. The 108-B Building and 1700-B Series supported buildings located about 150 meters (500 feet) north of the 105-B Reactor.

Waste Type: Not Specified

Waste Description: the waste is the sanitary sewer pipelines, pipeline contents, pipeline debris, and surrounding soils.

Closure Info: Interim: Remediation of the 100-B-14:2 and 1607-B2 waste sites was performed in stages from January 2005 through June 2006. All excavation was restricted within the shallow zone (less than 4.6 meters [15 feet] bgs), with an average depth of approximately 2.5 meters [8 feet] bgs, and a maximum depth of approximately 4 meters [13 feet] bgs at the septic tank. Excavation at the northern portion of the site continued to greater depth due to concurrent remediation of the underlying 100-B-14:1 process sewer. Excavated and disposed material quantities could not be explicitly separated for each site due to co-location and concurrent remediation of differing functional pipeline groups.

Based on the results of confirmatory sampling and previous investigations, it was decided that remedial action was necessary at areas 1, 2, 4, and 5 and that no further action was required at area 3. Area 1 was removed with the remediation of the 100-B-8:1 effluent lines. A decision was also made that remediation was necessary at the 1607-B2 waste site without further investigation based on the confirmatory sampling results for the influent feeder pipelines.

Due to its proximity to the reactor building, the southernmost portion of the 1607-B2 collection line, which formerly serviced the 105-B Reactor Building, was not removed. This portion of the pipeline will be addressed in the 118-B-8, 105-B Reactor waste site.

Site remediation consisted of the removal of the sewer piping, septic tank, and drain field where applicable, as well as adjacent, potentially-contaminated soils for disposal at the Environmental Restoration Disposal Facility (ERDF). Remedial actions were performed so as to not preclude any future uses (as bounded by the rural-residential scenario) and to allow unrestricted use of shallow zone soils [i.e., surface to 4.6 meters (15 feet) deep].

The SubSite is Part Of:

Code: 100-B-14

Names: 100-B-14; 100-B Area Process and Sanitary Sewer Underground Pipelines

Code: 100-B-14:3

Classification: Accepted

Names: 100-B-14:3; West Process Sewer Pipelines from 182-B and 183-B

Reclassification Interim No Action (6/4/2004)

Type: Process Sewer**Start Date:****Status:** Inactive**End Date:**

Description: The subsite has been evaluated and reclassified to No Action. It consisted of the process sewer pipelines that exited from the 182-B reservoir and 183-B water treatment facilities. These process sewer lines were collected into a single 1.67 meter (5.5-foot) reinforced concrete box sewer that fed into the main process sewer collection line serving the 185-B/190-B Pumphouse, 105-B Reactor, and the 108-B Tritium Separation Facility. The basis for separating this subsite from the main process sewer line was that these lines carried effluent from facilities known to be potential sources of radioactive and chemical contaminants.

Location: These pipelines are located north of the 182-B and 183-B facilities, as well as between the 182-B and 183-B buildings, and east of the 183-B Clearwells. The individual pipeline segments are mapped in the WCH Geographic Information System (GIS) database.

Waste Type: Not Specified

Waste Description: The waste includes the pipelines and the contaminated scale contained within them.

Closure Info: Interim: Confirmatory sampling was conducted in October 2003. The sampling approach consisted of collecting three samples of pipe scale material from each of three manholes and one soil sample from below one manhole/pipe. The maximum detected results from the scale and soil samples were used to support waste site reclassification. A summary of the evaluation of the scale and soil sample results were compared against the applicable remedial action goals (RAGs). A focused sampling approach was selected for this site, biased toward worst-case sample locations and locations that were accessible.

The No Action decision for the 100-13-14:3 site is supported based on reviews of site history, field observations, and characterization results. The maximum detected results from pipe scale and underlying/surrounding soil samples collected at locations suspected of having the greatest potential for residual contamination levels were shown to meet the cleanup objectives for direct exposure, groundwater protection, and river protection.

The SubSite is Part Of:

Code: 100-B-14

Names: 100-B-14; 100-B Area Process and Sanitary Sewer Underground Pipelines

Code: 100-B-14:4

Classification: Accepted

Names: 100-B-14:4; Cooling Water Pipelines and Tunnels from 190-B

Reclassification: Interim No Action (9/16/2004)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The subsite has been evaluated and reclassified to No Action. This subsite included the pipes and tunnels from the 190-B Building to the road east of the 105-B Reactor. The 100-B-14:4 pipelines were removed and the tunnels collapsed in 1993 during deactivation and decommissioning of the 190-B pump house. There were twin tunnels at each reactor. The tunnel dimensions varied, but were about 3.3 meters wide by 3.6 meters high (10 ft by 12 ft). They covered a distance of about 140.2 meters (460 ft) from the pumphouses to the reactor. Each tunnel from the 190-C pumphouse held one 20.3 cm (8 in) steam line and three 61 cm (24 in) water pipes. Each tunnel from the 190-B pumphouse and annex held twelve 30.5 cm (12 in), and two 45.7 cm (18 in) pipelines for cooling water to the 105-B Reactor. The pipes from the

edge of the road to the reactor will be included in 118-B-8, as they cannot be removed until the reactor is addressed.

Location: This subsite includes the pipes and tunnels from the 190-B Building to the road east of the 105-B Reactor, and from the edge of the road to the reactor.

Waste Type: Not Specified

Waste Description: The waste includes the pipelines, and their contents (scale, sediment).

Closure Info: Interim (9/16/2004): The 100-B-14:4 pipelines were removed and the tunnels collapsed in 1993 during deactivation and decommissioning of the 190-B pump house. The Cooling Water Pipe Tunnels Site (100-B-14:4) meets the Remedial Action Objectives specified in the Remaining Sites ROD, U.S. Environmental Protection Agency, Region 10, Seattle, Washington. There is no history of radiological contamination associated with the 100-B Reactor cooling water tunnels and no radiological contamination was detected during decommissioning of the tunnels. There were no known process incidents at 105-8 Reactor that would have introduced radiological contamination from the reactor into the tunnels. Additionally, since the 105-B cooling water tunnels had the same source of water as the 105-C cooling water tunnels, the 105-B tunnels are analogous to the 105-C tunnels. Historical sampling indicated that no unacceptable levels of residual hexavalent chromium exist in the 105-C tunnels.

Reclassification form 2004-0008 states the 105-C tunnels have been determined to meet the cleanup criteria, therefore the 100-B-14:4 site also meets the cleanup criteria and the remaining contaminant levels are protective of groundwater and the Columbia River. All samples were less than the criteria of 2.0 mg/kg for protection of groundwater and Columbia River. This result is for the main sample associated with the duplicate soil sample.

The SubSite is Part Of:

Code: 100-B-14

Names: 100-B-14; 100-B Area Process and Sanitary Sewer Underground Pipelines

Code: 100-B-14:5

Classification: Accepted

Names: 100-B-14:5; Sodium Dichromate and Sodium Silicate Pipelines

Reclassification: Interim No Action (6/3/2004)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The subsite has been evaluated and reclassified to No Action. The subsite consisted of the sodium dichromate and sodium silicate product pipelines that transferred product from 108-B Building to 185/190-B facilities.

Location: These pipes exit the northwest side of the 108-B Facility and connected to the north side of the 185-B Facility. The pipes make three 90-degree corners in a step like fashion with north-south and east-west sections. Exact depth below grade is unknown, but is believed to be within 3 meters (10 ft) of the surface.

Process Description: Two 7.6cm (3in.) diameter stainless-steel pipes transferred concentrated sodium dichromate and sodium silicate solutions from the 108-B Building to the 185-B/190-B Pumphouse facility, where they added to filtered cooling water prior to its use in the reactor.

Waste Type: Not Specified

Waste Description: The waste includes the pipelines, and their contents (scale, sediment).

Description:

Closure Info: Interim: The No Action decision for the 100-B-14:5 site is supported based on reviews of site history, field observations, and characterization results. The maximum detected results from soil samples collected underneath the sodium dichromate and sodium silicate product pipelines at locations suspected of having the greatest potential for residual contamination levels were shown to meet the cleanup objectives for direct exposure, groundwater protection, and river protection.

Confirmatory sampling was conducted in October 2003. The original sampling approach consisted of collecting one sample of pipe scale and one soil sample from below each pipe at two sampling locations. Since no scale or sediment was found in the piping at the selected locations, two alternative soil locations along the piping were sampled. The maximum detected results from soil samples were used to support waste site reclassification.

The SubSite is Part Of:

Code: 100-B-14

Names: 100-B-14; 100-B Area Process and Sanitary Sewer Underground Pipelines

Code: 100-B-14:6

Classification: Accepted

Names: 100-B-14:6; 184-B and 184-B Ash Slurry Line; Powerhouse Pipelines

Reclassification: Interim No Action (6/4/2004)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The subsite has been evaluated and reclassified to No Action. This subsite included the process sewer pipelines from the 184-B Powerhouse, flowing north to the ash pit east to the main trunk line (100-B-14:1).

Location: The segments were located on the north and south sides of the powerhouse.

Process Description: Process Sewer Pipelines exited the 184-B Power House and eventually discharged into the main 100-B-14 process sewer pipeline connecting to the 116-B-7 outfall. The underground piping for the 184-B Powerhouse included sanitary (clean) waterlines, a sanitary sewer line and process sewer lines. These pipelines consist of: Sanitary waterline pipelines: These pipelines consist of sanitary water pipelines, filtered water pipelines, and raw and condensor water pipelines. Proceeding from west to east along the south side of the building the pipelines include: 1607-B-3 Sanitary Sewer Pipeline: This piping is a 20.3 cm (8 in) diameter vitrified clay pipe that exited the northwest corner of the 184-B Powerhouse to the 1607-B-3 Septic Tank. 184-B Powerhouse Ash Pipeline: This pipeline is an 20.3 cm (8 in) diameter ashcolite pipe that was used to discharge coal ash that was mixed with raw water and sluiced from the 184-B Powerhouse to the 126 B Ash Pit. 184-B Process Sewer Pipelines: There are four locations where process sewer pipelines exit the 184-B Powerhouse and eventually discharge into the main 100-B-14 Process Sewer Pipeline connecting to the 116-B-7 Outfall. There is also a pipeline that discharges from the powerhouse blow-off tank into the 184-B Process Sewer Pipelines. These pipelines required confirmatory sampling and included: Two pipelines, a 15.2 cm (6 in) diameter vitrified clay pipe and a 20.3 cm (8 in) diameter vitrified clay pipe, both on the left south side of the building, that discharged into a 30.5 cm (12 in) diameter vitrified clay pipe and eventually into the main process sewer line. A 30.5 cm (12 in) diameter steel pipe near the center south side of the building that discharged into a 130.5 cm (2 in) diameter vitrified clay pipe and eventually into the main process sewer line. A 38.1 cm (15 in) diameter vitrified clay pipe on the north side of the building that discharged directly into the main process sewer pipeline.

Waste Type: Not Specified

Waste Description: The waste was the remaining pipelines and any potentially contaminated soil.

Closure Info: Interim: The No Action decision for the 100-B-14:6 site is supported based on reviews of site history, field observations, and characterization results. The maximum detected results from pipe scale and underlying/surrounding soil samples collected at locations suspected of having the greatest potential for residual contamination levels were shown to meet the cleanup objectives for direct exposure, groundwater protection, and river protection.

Confirmatory sampling was conducted in September and October 2003. The maximum detected results from the scale and soil samples were used to support waste site reclassification.

The SubSite is Part Of:

Code: 100-B-14

Names: 100-B-14; 100-B Area Process and Sanitary Sewer Underground Pipelines

Code: 100-B-14:7

Classification: Accepted

Names: 100-B-14:7; 185-B and 190-B Sump and Pipelines

Reclassification: Interim No Action (6/3/2004)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The subsite has been evaluated and reclassified to No Action. This subsite consisted of the pipelines that were used to control the temperature of process water used in association with the 185-B Deaeration Building and the 190-B Pumphouse. The subsite included the sump. The sump was a 14.3 m by 10.4 m by 4.6 m deep (47 ft by 34 ft by 15 ft deep) reinforced concrete reservoir, and was open to the environment. An 80 m (260 ft) long, 61 cm (24 in) diameter cast-iron pipe exited the south side of the 185-B Building and fed the sump. A 10 m (30 ft) long, 76 cm (30 in) diameter cast-iron pipe that exited the south side of the 190-B Pumphouse joined this pipe. The pipe entered the sump on the south side near the west corner at approximately 3 m (9 ft) below ground surface (coordinates N144444.427; E565173.872).

Location: The pipelines were from the south side of the 185-B and 190-B facilities and ended at the sump on the southeast corner of 190-B.

Waste Type: Not Specified

Waste Description: the waste is the pipelines, and their contents, and the 190-B sump.

Closure Info: Interim: The No Action decision for the 100-B-14:7 site is supported based on reviews of site history, field observations, and sampling results. The maximum detected results from pipe scale and underlying/surrounding soil samples collected at locations suspected of having the greatest potential for residual contamination levels were shown to meet the cleanup objectives for direct exposure, groundwater protection, and river protection.

Confirmatory sampling was conducted during October 2003. The contaminants of potential concern (COPCs) were identified based on existing analytical data, historical process information, and historical uses and practices associated with the 185 B/190-B sump and pipeline facilities. The COPCs included inductively coupled plasma (ICP) metals, mercury, and hexavalent chromium. At the location where a 46-centimeter (18-inch) pipe entered the sump, some suspect fibrous insulating material was observed. This fibrous material was sampled for

asbestos analysis. The absence of radionuclide contamination was confirmed using gamma energy analysis (GEA) and gross alpha and gross beta analyses. On this basis, no radionuclide COPCs were identified for this site.

The SubSite is Part Of:

Code: 100-B-14

Names: 100-B-14; 100-B Area Process and Sanitary Sewer Underground Pipelines

Code: 100-B-15

Classification: Accepted

Names: 100-B-15; 100BC River Effluent Pipelines;
100BC River Lines

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This site includes the 100-B/C Area river effluent pipelines (river lines) that extend from each of the three outfalls into the main channel of the Columbia River.

Location: The river lines are located in the Columbia River, adjacent to the 100BC area. The lines extend north into the main channel of the river from three outfall structures located near the river shore.

Related Sites/ Structures: The site is associated with the 116-B-7 (1904-B1 outfall), 132-B-6 (the 1904-B2 outfall), and 132-C-2 (the 1904-C outfall); the 100-B Reactor Cooling Water Effluent Underground Pipelines (100-B-8), the 100 B Area Process and Sanitary Sewer Underground Pipelines (100-B-14), the 100-C Reactor Cooling Water Effluent Underground Pipelines (100-C-6), and the 100-C Area Process and Sanitary Sewer Underground Pipelines (100-C-9); the 107-B Retention Basin (116 B-11), the 107-B Liquid Waste Disposal Trench (116-B-1), the 107-C Retention Basins (116-C-5), and the 107-C Liquid Waste Disposal Trench; and 100-B-24 (the 1904-B1 Spillway), 100-B-25 (the 1904-B2 Spillway), 100-B-26 (and the 1904 C Spillway).

Process Description: The river effluent pipeline from 116-B-7 (1904-B1) provided for the discharge of reactor cooling water and the B Area process sewers until 1955. After that time, it provided only for the discharge of B Area process sewers, and reactor cooling water was rerouted through a new, higher capacity 132-B-6 (1904-B2) pipeline. In 1952 the 1904-C pipelines (and the 132-C-2 outfall) discharged reactor cooling water for the new C Reactor and C Area process sewers. In the event any of the pipelines became plugged or had to be removed from service during operation, the effluent overflowed the effected outfall and entered the river via an attached spillway.

Waste Type: Process Effluent

Waste Description: The waste includes the pipelines and the contaminated scale contained within them. Contaminants of concern/potential concern are based on those for the outfalls themselves. They include americium-241, cesium-137, cobalt-60, europium-152, europium-154, europium-155, nickel-63, plutonium-238, plutonium-239/240, strontium-90, tritium, uranium-234, uranium-235, uranium-238, hexavalent chromium, total chromium, mercury, and lead.

Code: 100-B-16

Classification: Accepted

Names: 100-B-16; Utility Poles and Fixtures Debris Pile

Reclassification: Interim Closed Out (6/29/2005)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site has been remediated and interim closed out. The site consisted of four surface debris

	piles that included unsheathed wire ropes, metal light poles, aluminum utility framing, rubber-insulated wires, ceramic insulators, broken light bulbs, light fixtures, lead bolts, and other wood. Two were known as northern debris piles and two were known as southern debris piles.
Location:	The northern debris pile was situated 80 meters (262 feet) north of Bell Ave and 100 meters (328 feet) west of Beaver Ave. The southern debris pile was directly south of Bell Ave. 90 meters (295 feet) and 95 meters (311 feet) west of Beaver Ave. Both areas were northwest of the 105-B Reactor.
Process Description:	The site consisted of four surface debris piles. Two piles were situated north of Bell Ave, the other two were directly south and across Bell Ave. The surface debris materials were composed of telephone poles (most of which were grouped together) and associated utility debris in piles adjacent to the telephone poles. Associated debris included unsheathed wire ropes, metal light poles, aluminum utility framing, rubber-insulated wires, ceramic insulators, broken light bulbs, light fixtures, lead bolts, and other wood pieces (including pressure-treated lumber).
Waste Type:	Misc. Trash and Debris
Waste Description:	The waste includes creosote-treated wood poles and cross beams, lead-tipped bolts and other debris. A few small boxes were seen that could be transformers. The possible transformers do not seem to be leaking any oil. Other debris included particle board, conduit, light fixtures, wire, insulators, junction boxes, chain link fencing and incandescent light bulbs.
Closure Info:	Interim (6/29/2005): Remedial action activities for the site began November 11, 2004 until November 19, 2004. All of the debris piles were removed, and 639 bank cubic meters (BCM) of pile material was collected, sorted, and disposed of at Environmental Restoration Disposal Facility. Following remediation, verification sampling was conducted on January 25, 2005. Analytical results of the verification samples (J02FN3) collected in sample location 4 exceeded the asbestos criteria. Consequently, additional remediation was warranted for this site. Additional remediation was conducted on March 7, 2005. Approximately 135 BCM of soil was removed. Following remediation, an additional verification sample (J03034) was collected for asbestos analysis on March 7, 2005.

Code:	100-B-18	Classification:	Accepted
Names:	100-B-18; 184-B Powerhouse Debris Pile	Reclassification:	Interim Closed Out (11/30/2007)
Type:	Dumping Area	Start Date:	
Status:	Inactive	End Date:	
Description:	The site consisted of a debris pile containing miscellaneous demolition waste from the decommissioning activities of the 184-B Building and the 184-B Power House.		
Location:	The 184-B surface debris pile was located northwest of the 184-B Power House. The coordinates at the center of the debris site were E 564449.562, N 144962.219.		
Related Sites/ Structures:	Some of the waste (especially corrugated ACM) at this site was similar to waste found at WIDS site 100-B-17, which was approximately 165 meters (541 feet) due north.		
Process Description:	The 105-B Reactor operated between 1944 and 1968, and the 105-C Reactor operated between 1952 and 1969. Constructed in 1944, the coal-fired 184-B Power House provided steam and emergency electrical power for the secondary coolant system located at 181-B. The 184-B Power House also supplied office heat and other heating needs for 100 B/C Area facilities through overhead steam lines that looped through the 100 B/C Area. A small turbine generator in 184-B also supplied emergency electrical power for area building lights and motors. Soon after the 105-B and 105-C Reactors were deactivated in 1969, the 184 B Building and other ancillary facilities were gradually phased out. The 184-B Building was closed in the mid 1970s, and parts of the 184 B Power House and all of the equipment were removed in 1979.		

Demolition and removal of all above ground structures including the stack was complete in 1983, leaving the foundation slabs, footprints, tunnels, pits, and other associated concrete structures at or near grade level. During 1988, the foundation and the other below-grade features, including the salt dissolving pits, were demolished to at least 0.9 meters (3 feet) below grade, backfilled with rubble, and buried in situ. Four 184-B Process Sewer Pipelines exited the 184-B Power House and eventually discharged into the main 100-B-14 process sewer pipeline connecting to the 116-B-7 outfall.

Waste Type: Misc. Trash and Debris

Waste Description: Suspect asbestos-containing materials such as siding, roofing, lagging, and wrapping were interspersed in the debris pile.

Closure Info: Interim: Remediation of the site was begun on June 26, 2007, and July 16, 2007. Because the majority of the material to be disposed was inert demolition debris (e.g., concrete blocks and asphalt rubble), the Environmental Protection Agency (EPA) and the Department of Energy, Richland Operations Office (DOE-RL) agreed that site remediation would be accomplished by selective removal of suspect hazardous items (specifically, light ballasts and tar/mastic material) and potentially impacted. No cleanup action for the non-friable asbestos-containing material (ACM) was required because it did not present a potential release to the environment.

Remediation activities included the removal of 70 BCM (bank cubic meter) of tar/mastic material along with underlying soils. Although expected, no light ballasts were found during remediation. The numerous intact and broken fluorescent light tubes located at the site (approximately 50) were picked up and disposed. No other hazardous debris or stained soil requiring remediation was identified at the site. The asphalt was not removed because it had been used for structural and construction purposes. Therefore, it was excluded from consideration as a dangerous waste based on the Washington Administrative Code (WAC) 173-303-071(3)(e), it is listed as an inert waste in WAC 173-350-990(2)(b), and does not present a significant risk to human health or the environment.

Because the majority of the material was inert demolition debris (e.g., concrete blocks and asphalt rubble), site remediation was accomplished by selective removal of suspect hazardous items (specifically, light ballasts and tar/mastic material) and potentially impacted soils. The asbestos-containing materials present at the site were in a non-friable form and did not present a potential release to the environment. Therefore, no cleanup action was required.

Excavation was performed in June 2007 with removal of additional light tubes in July 2007. Seventy BCM (bank cubic meter) of tar/mastic material along with surrounding contaminated soils were disposal at the Environmental Restoration Disposal Facility (ERDF). Light ballasts were expected at the site, however, none were found. The numerous intact and broken fluorescent light tubes located at the site (approximately 50) were picked up and disposed. Inert debris material was left in-place at the site. No other hazardous debris or stained soil requiring remediation was identified at the site.

Code: 100-B-19

Classification: Accepted

Names: 100-B-19; 100B/C Chemical Contaminated Surface Soil Areas; 100-B/C Stained Soil Sites

Reclassification: Interim Closed Out (1/13/2010)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The waste site has been remediated and Interim Closed Out. Prior to remediation the 100-B-19 waste site consisted of six stained soil locations that were dispersed within the 100-B/C Area. The stained soil was identified during a WCH 2004 orphan sites field visit of the 100-B/C Area.

Three of the locations (SS-100BC-001, SS-100BC-002, and SS-100BC-003) contained reddish-to purple-colored coarse-grained garnet material on the surface. The other three locations (SS-100BC-004, SS-100BC-005, and SS-100BC-006) had yellow-stained surface soil that was ultimately determined to originate from sulfuric acid.

An agreement was made among the Environmental Protection Agency (EPA), the U.S. Department of Energy, Richland Operations Office (DOE-RL), and the Environmental Restoration Contractor Team on May 5, 2005, that a general cleanup action to remove the garnet-like material and yellow-stained soils would occur at each of the six locations. Additionally, one multi-aliquot sample would be collected of the underlying soils at each of the six locations.

- Location:** (SS-100BC-001): Potential garnet material was found on the surface at coordinates E 566706.139, N 145169.459 in the northeast corner of the 100-B/C Area (using handheld GIS equipment).
- (SS-100BC-002): Potential garnet grit-blasting material was visible on the soil surface at coordinates E 564420.28, N 144545.33 about 150 meters (475 feet) west of the southwest corner of the 182-B Reservoir in the 100-B/C Area.
- (SS-100BC-003): Potential garnet grit-blasting material was visible on soil surface at E 565968.41, N 144,046.68 about 32 meters (105 feet) northeast of the north boundary of the 128-C-1 WIDS waste site, which is east of the 105-C Reactor.
- (SS-100BC-004): This surface stained soil area was on the north side of the railroad tracks at E 564802.438, N 144346.781 (centroid). The north area was connected (by a clay pipe culvert under railroad tracks) to a soil stained area on the south side of the railroad tracks at E 564803.312, N 144327.703 (centroid). The pipe culvert was located between the head houses for the 183-B and 183-C Water Treatment Plants. The pipe culvert was about 175 meters (575 feet) west of the northwest corner of the 151-B Substation yard. The combined area was about 28 square meters (296 square feet).
- (SS-100BC-005): This surface stained soil area at E 564803.062, N 144144.156 (centroid) is located 135 meters (443 feet) north and 40 meters (131 feet) east of the 183-C Head House (center). The east-west centerline of the stained surface area runs parallel and about 6.6 meters (22 feet) north of the east-west paved road (center) between the 183-C Water Plant and the 151 B Substation. The total stained area is about 58 square meters (619 square feet). The area between the two locations (i.e., the culvert) is not included in the total area. If soil analyses for potential contaminants of concern for either or both areas indicate cleanup is required, then the culvert area should be included in the cleanup action.
- (SS-100BC-006): There is stained soil in a hole is about 0.7 meters (2 feet) in diameter and about 1.5 meters (5 feet) deep located at E 564804.06, N 144374.71. It is about 7.5 meters (25 feet) north of the east-west paved road (center) that runs between the 183-B Water Plant and the 151-B Substation.

- Process Description:** Garnet grit was commonly used in grit-blasting operations to clean the surface of metal components of rust, paint, or contamination. The garnet is not a hazardous substance, but there is a potential for contamination from the surface material that was cleaned by grit blasting. Analogous waste site information is available for WIDS site 100-K-29, a garnet grit blasting surface soil site in the 100-K Area that was remediated under the Remaining Sites Record of Decision. Yellow stains on soil in this area may be due to spills of concentrated sodium dichromate solution (hexavalent chromium) and/or concentrated sulfuric acid used at the water treatment plants for reactor coolant water cleaning and for corrosion control. These chemicals were received in railroad tank cars and in tanker trucks for off-loading to storage tanks at the 183-B, 185-B, 190-B, 183-C, and 190-C water plant facilities. Chemical spills and leaks to the

surrounding soil are known to have occurred during loading and unloading operations and during equipment maintenance at the 100-K Area and similar problems likely occurred at the 100-B/C water plant facilities.

Analogous hexavalent chromium waste sites include the 100-C-7 hexavalent chromium waste site for the sodium dichromate equipment area in the 183-C Filter House and surrounding soil. Hexavalent chromium on concrete, steel, and soil was successfully remediated for the 190 C Pump House and Water Tunnels (BHI 1997). Analogous concentrated sulfuric acid waste sites that have been remediated include the 100 K Area sulfuric acid storage tank sites (WIDS waste sites 100-K-30, 100-K-31, 100-K-32, and 100 K-33) associated with the water treatment plant for the 100-K Area. The contaminants of concern for concentrated sulfuric acid are lead and mercury that were present as impurities in the acid.

Waste Type: Chemical Release

Waste Description: The waste is contaminated (stained) soil. Contaminants of potential concern (COPCs) include hexavalent chromium, lead, and mercury for yellow stained sites.

Closure Info: Interim: An agreement was made between the EPA, DOE-RL, and the Environmental Restoration Contractor Team on May 5, 2005, that a general cleanup action to remove the garnet-like material and yellow-stained soils would occur at each of the six 100-B-19 locations. Therefore, confirmatory sampling was not required. The site was included in the Explanation of Significant Differences for the 100 Area Remaining Sites Interim Remedial Action Record of Decision, Hanford Site, Benton County, Washington (EPA 2009) as a waste site for remediation, treatment, and disposal.

All remediation was guided by visual inspection, and, where applicable, X-ray fluorescence (XRF) field measurements. Initial remediation of the 100-B-19 waste site was performed between June and October 2007. Approximately 11,390 metric tons (12,550 US tons) of material was excavated and disposed at the Environmental Restoration Disposal Facility (ERDF) from all locations in the entire waste site. All waste soils were directly loaded out, except at location SS-100BC-004.

In 2009, further remediation was performed at locations SS-100BC-002 and SS-100BC-004 resulting in the removal of approximately 1,150 metric tons (1,270 US tons) of soil. Remediation at location SS-100BC-002 was performed from February to May. Additional material removal revealed a more extensive subsurface lens of garnet mixed with soil, as was previously observed at locations SS-100BC-001 and SS-100BC-003. All visible garnet material was removed over an area of approximately 450 square meters (4,800 ft²) to a maximum depth of approximately 1 meters (3 ft) below original grade. Approximately 650 bank cubic yards (500 bank cubic meters) of soil mixed with garnet grit was excavated and staged north of the site. Loadout of the material was completed in July 2009. A total of 12,540 metric tons (13,820 tons) of material from the six stained soil locations were disposed at ERDF.

Code: 100-B-20	Classification: Accepted
Names: 100-B-20; 1716-B Maintenance Garage Underground Tank	Reclassification: Interim Closed Out (9/27/2006)
Type: Maintenance Shop	Start Date:
Status: Inactive	End Date:
Description: The site has been remediated and Interim Closed Out. The site consisted of an underground gas and/or oil tanks near the garage. The garage was used for maintenance of 100-B area vehicles. The facility and tanks have been removed.	

- Location:** The site was located approximately 300 meters (984 feet) northwest of the 105-B Reactor Building on the south side of B Avenue.
- Process Description:** The 1716-B Maintenance Shop was built in 1944 and provided automotive repair and light vehicle maintenance and lubrication service for 100-B/C Area vehicles until deactivation of B Reactor in 1968. Drawing H-1-10983 identified the building as a Bus Garage. Whalen noted the "lubrication of vehicles was accomplished from a grease pit dug in a high-bay area of the garage". Drawing HW-71669 references Drawing H-1-5055, Lube. Pit Lte. Electrical, which shows that 1716-D and 1716-F had lubrication pits, but there was no reference to one at 1716-B.
- The "L"-shaped 12.2 meter by 16.3 meter (40 foot by 53.5 foot), single-story, wood frame building, which measured approximately 167.2 square meters (1,800 square feet), contained one large rectangular room (high bay) and a small adjoining room (office). Drawing W-71300 shows two service bays that were large enough to accommodate buses. In 1979, the building was declared surplus, the equipment was excessed, and the entire facility was removed by a salvage operator. Removal of the gas and oil tanks nor the associated piping were mentioned.
- Waste Type:** Soil
- Waste Description:** While the records indicate that the underground gasoline tank was removed and no contamination was found in soil samples, no documentation of when the oil storage tank was removed could be found. Additional potential contamination sources include the former grease pit, lubricating fluids, battery acid in the high bay area, and asbestos shake siding. Contaminants of potential concern (COPCs) would include total petroleum hydrocarbons (TPH) and polychlorinated biphenyls (PCBs).
- Closure Info:** Interim: The site was evaluated through field observations and focused sampling and analysis to determine if hazardous contaminants were present at the site. One test trench, in the most likely location of the underground oil storage tank (UST), was excavated in sample area 1. The UST was discovered within the excavation trench at an approximate depth of 1.7 to 1.8 meters (5.5 to 6.0 feet). The tank consisted of two separate compartments, each of which contained waste material. The larger compartment had an approximate capacity of 946 to 1136 liters (250 to 300 gallons) and contained 189 to 227 Liters (50 to 60 gallon) of sludge. The smaller compartment had an approximate capacity of 379 to 568 Liters (100 to 150 gallons) and contained 19 to 38 Liters (5 to 10 gallons) of a soil/water/diesel mixture. After removal of the UST, the remaining soils underlying the tank footprint were sampled. A total of five samples were collected at the UST excavation (sample area 1) and consisted of a soil sample from underneath the tank, two soil samples from the excavation sidewalls, one duplicate and one blank. An additional soil sample (sample area 2) was collected at the 100-B-20 waste site from subsurface stained soils. The excavation was backfilled upon completion of sampling with clean soil from the 100-B Area borrow pit.
- The UST was unable to be sampled in place and was removed to gain access to the internal contents. A composite sample was collected from the material in the two compartments and analyzed for waste characterization purposes. According to remedial field notes the tank contents were removed, and the empty tank and waste contents were placed into a B-25 box. In addition to the tank removal, approximately 0.3 meters (1 foot) of soil was excavated from the location underlying the UST and placed into a second B-25 box. The contents of the B-25 boxes will be managed and disposed of separately in accordance with the Washington State Department of Ecology "Dangerous Waste Regulations" (Washington Administrative Code [WAC] 173-303) and as according to CERCLA requirements, the waste will be disposed at the Environmental Restoration Disposal Facility.
- The depth of the oil tank was approximately 1.8 meters (6.0 feet) and the soils collected underlying the tank were at a depth of 2.1 meters (6.9 feet). The sample results at the

boundaries of the excavation indicated that the remedial action objectives for the site have been met. No further excavation is required.

Code: 100-B-21 **Classification:** Accepted
Names: 100-B-21; 100-B/C Miscellaneous Pipelines **Reclassification** Interim Closed Out (2/9/2010)
Type: Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: All of the subsites have been evaluated and reclassified. The waste site included 21 pipeline segments. They consisted of a variety of underground pipelines that were discovered during removal of other 100-B/C Reactor effluent pipelines and soil sites. The pipeline segments did not belong to previously established waste sites. They have been grouped together based on the type of pipeline and potential closeout pathways for each. The waste site was split into four subsites.

Location: The multiple locations were described in terms of easting (E), northing (N), and elevation (meters). Elevations are NAVD88.

Process Description: The pipelines in this waste site were discovered during the removal of other effluent pipelines and soil sites. As pipeline removal progressed, an effort was made to photograph, accurately locate (at least the exposed end), and in some cases perform limited chemical and radiological investigations of the pipelines. Many of the pipelines were not identified on drawings. Some of the pipelines were included in other waste sites, thus, gaps exist in the numbering of the pipelines included in this waste site. Large-diameter pipeline generally means pipeline greater than 50.8 centimeters (20 inches).

Waste Type: Process Effluent

Waste Description: Contaminants of Potential Concern are listed only for sites known to have contaminants. (DS-100BC-002) Contaminants of potential concern are asbestos, semivolatile organic analytes, phenanthrene, fluoranthene, pyrene, benzo (a, b, and k) anthracene, chrysene, mercury, and lead. (DS-100BC-016) The potential contaminants of concern are asbestos, lead, and arsenic. (DS-100BC-019) The potential contaminants of concern are americium-241, and asbestos. (DS-100BC-022) The potential contaminants of concern include asbestos.

This Site has the Following SubSites:

Code: 100-B-21:1

Names: 100-B-21:1; Steel Pipeline Segment

Code: 100-B-21:2

Names: 100-B-21:2; Asbestos/Tar Wrapped Pipeline

Code: 100-B-21:3

Names: 100-B-21:3; Asbestos Wrapped Steel Pipeline

Code: 100-B-21:4

Names: 100-B-21:4; Pipeline from the 105-C Reactor East to 116-C-2B Sump

Code: 100-B-21:1 **Classification:** Accepted
Names: 100-B-21:1; Steel Pipeline Segment **Reclassification** Interim No Action (2/14/2006)
Type: Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The two pipeline segments in this subsite have been evaluated and reclassified to No Action. The evaluation of these pipelines included site histories, analytical data, process knowledge, and field observations based on field screening, and laboratory data. In June 2007, during remedial activities, it was discovered that the DS-100BC-019 pipeline and DS-100BC-016 pipeline were connected. Therefore, the DS-100BC-016 pipeline was incorporated with segment DS-100BC-019 that is part of the 100-B-21:3 subsite. Both DS-100BC-016 and DS-100BC-019 pipeline segments were removed.

The DS-100BC-016 pipeline segment consisted of a 20-centimeter (8-inch) diameter, east-west-running steel pipe found during excavation of waste site 100-C-6, the 100-C Reactor effluent underground pipelines. The pipe had an asbestos-containing tar-based spiral wrap. The pipeline segment that crossed the excavation of the 100-C-6 pipelines was removed. The pipeline was left in place at coordinates E565473, N144463.

The DS-100BC-022 pipeline segment consisted of a 2.5-centimeter (1-inch) diameter pipeline discovered during the remediation of the 100-C-3 site. The pipeline was documented in an area to the southeast of the 105-C Reactor near the former location of the 119-C sample building. The pipeline connected to a larger 10.2-centimeter (4-inch) pipeline south of where the smaller section of pipeline was discovered. The larger pipeline was a water supply line, and no contaminants of potential concern were identified beyond the asbestos commonly found in the wrapping on this type of pipe. The small pipeline was considered analogous to the larger pipeline.

Location: The pipeline crosses along the east edge of 100-C-3. Coordinates are E 565396, N143951. The elevation is about 1.5 m (5 ft) below grade.

Waste Type: Not Specified

Waste Description: The waste is piping and potentially contaminated soil.

Closure Info: Interim (2/14/2006): NOTE: In June 2007, during remedial activities, it was discovered that the DS-100BC-019 pipeline and DS-100BC-016 pipeline were connected. Therefore, the DS-100BC-016 pipeline segment was incorporated into the 100-B-21:3 subsite and both pipeline segments were removed. The DS-100BC-016 pipeline, mapped at Washington State Plane coordinates N 14463, E 565473, had been investigated separately and reclassified to No Action in the 100-B-21:1 subsite in 2006.

DS-100BC-016 : Approximately 50 meters (164 feet) of the pipeline was disposed at the Environmental Restoration Disposal Facility. The potential contaminants of concern were asbestos, lead, and arsenic. On 9/24/2003, samples J00YH1 (Chemistry) and J00YJ0 (Field Screening) were collected. The pipeline analytical data results detected total chromium (26.4-mg/kg) and lead (48.4 mg/kg) above-background levels and confirmed asbestos (4-8% chrysotile) in the pipe wrap. The total chromium and lead results were above background, but below direct exposure levels. RESidual RADioactivity (RESRAD) analysis illustrated that total chromium and lead will not reach groundwater or the river within 1,000 years. Therefore, they are considered protective of groundwater and the river. The risk associated with asbestos was that of direct exposure to friable asbestos fibers. Because the asbestos on this pipe was suspended in a tar-based compound, it was considered nonfriable. The segment, therefore, does not require further remediation and was recommended for a No Action decision.

DS-100BC-022 : A sample of the pipe wrap was taken in 2003 and tested for asbestos. The analytical result confirmed 3% to 8% chrysotile in the tar wrap on the pipe. The asbestos is in a nonfriable form and does not represent a risk warranting CERCLA action. The pipeline segment, therefore, does not require further remediation and is recommended for a No Action decision.

Evaluation of pipeline segments DS-100BC-016 and DS-100BC-22 used analytical data, process knowledge, and field observations that supports the reclassification to No Action. The evaluation has found this subsite to meet the cleanup objectives for direct exposure, groundwater protection, and river protection.

Soil cleanup levels were established in the interim action ROD based on a limited ecological risk assessment. A baseline risk assessment for the river corridor portion of Hanford began in 2004, which includes a more complete quantitative ecological risk assessment. That baseline risk assessment will be used as part of the final ROD for the site.

The SubSite is Part Of:

Code: 100-B-21

Names: 100-B-21; 100-B/C Miscellaneous Pipelines

Code: 100-B-21:2

Classification: Accepted

Names: 100-B-21:2; Asbestos/Tar Wrapped Pipeline

Reclassification Interim Closed Out (6/16/2008)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The 100-B-21:2 waste site has been remediated and Interim Closed Out. It consisted of the single pipeline segment originally designated as DS-100BC-002. This pipeline segment was described as a 2.5 cm (1-inch) diameter asbestos-wrapped metal pipe protruding 1.5 meters (5 ft) horizontally from the bank of the Columbia River. The northern end of the 100-B-21:2 pipeline, originally discovered at N145362, E565307, was located west of the 116-B-7 outfall structure and north of the 100-BC perimeter road. During remediation the pipeline was determined to extend due south, under the 100-BC perimeter road to the edge of 116-B-11 Retention Basin excavation boundary.

Location: The pipeline is north of the 100-B/C perimeter road and north of the former location of 116-B-11 Retention Basin. The location was measured at 30.5 m (100 ft) east of the 116-B-7 flume east edge and 34 m (111 ft) north of the road. The pipeline was sampled at coordinates E 565307, N 145362, and elevation 132.086 m.

Process Description: The history of the 100-B-21:2 pipeline, prior to its discovery in 2003, is unknown. The pipeline did not appear on the historical construction drawings. The location and orientation of the pipeline suggested that it was associated with the 116-B-11 Retention Basin and discharged to the river embankment. It was smaller than most drain lines, suggesting it was a pressurized water pipe, though the exact purpose remained unknown.

Waste Type: Not Specified

Waste Description: The waste is a small diameter pipeline and potentially contaminated soil.

Closure Info: Interim (6/16/2008): Remediation of the 100-B-21:2 waste site was performed from June 11 through June 18, 2007. The 100B/C perimeter road was closed to allow remediation. Asphalt removed from the road surface was segregated into a stockpile on the adjacent road surface for disposal at the Environmental Restoration Disposal Facility (ERDF). Overburden soils were removed from above the pipeline and placed into two stockpiles on the west side of the excavation. The pipeline, soil in contact with the pipe, and soil 0.3 meters (1 foot) below the pipeline were removed and disposed of at ERDF. A total of approximately 91 metric tons (100 US tons) of material was disposed at ERDF. No anomalies were discovered during the remedial action.

An additional geophysical survey in March 2007 of the 100-B-21:2 pipeline segment was performed using ground penetrating radar with results similar to those found in 2003. The geophysical interpretation identified the pipeline and noted low amplitude anomalies (thought to be large boulders) in the subsurface.

The SubSite is Part Of:

Code: 100-B-21

Names: 100-B-21; 100-B/C Miscellaneous Pipelines

Code: 100-B-21:3

Classification: Accepted

Names: 100-B-21:3; Asbestos Wrapped Steel Pipeline

Reclassification: Interim Closed Out (5/7/2009)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. In 2003, the DS-100BC-019 pipeline was described as a 20 cm (8-in.) diameter steel pipe with an asbestos-containing, tar-based spiral pipeline wrap and mechanical joints. This pipeline protruded from a sidewall of a railroad track bed cut, located just south of the 116-B-15 Percolation Pit, and ran in a north-south direction.

In June 2007, during remedial activities, it was discovered that the DS-100BC-019 pipeline and DS-100BC-016 pipeline were connected. Therefore, the DS-100BC-016 pipeline segment was incorporated into the 100-B-21:3 subsite and both pipeline segments were removed. The DS-100BC-016 pipeline, mapped at Washington State Plane coordinates N 14463, E 565473, had previously been investigated separately and reclassified as No Action in the 100-B-21:1 subsite.

Location: The subsite is directly south of the 116-B-15 waste site. DS-100BC-019 located at Washington State Plane coordinates N 144494, E 565528. DS-100BC-016 located at Washington State Plane coordinates N 14463, E 565473.

Waste Type: Not Specified

Waste Description: The waste is piping and potentially contaminated soil.

Closure Info: Interim: In March 2007, geophysical surveys were performed over the site using ground-penetrating radar (GPR). A linear anomaly that was interpreted to be the target pipeline was oriented north-south and continued to the southern edge of the investigation area where it was obscured by a highly reflective horizon. It was uncertain whether the pipeline continued past the southern boundary of the survey area; however, during remedial activities it was verified that the pipeline extended past the boundary. In September 2007, GPR was used to trace the pipeline from the last exposed point in the excavation; the line was interpreted to bend to the west and extended approximately 60 m (200 ft) to the location of the DS-100BC-016 pipeline.

In June 2007, during remedial activities, it was discovered that the DS-100BC-019 pipeline and DS-100BC-016 pipeline were connected. Therefore, the DS-100BC-016 pipeline was incorporated into the 100-B-21:3 subsite and both pipeline segments were removed. The DS-100BC-016 pipeline, mapped at Washington State Plane coordinates N 14463, E 565473, had previously been investigated separately and reclassified as No Action in the 100-B-21:1 subsite. In June 2007, overburden soils were removed from above the pipeline and placed into two stockpile areas. Remedial activities continued through January 2008, with a total of approximately 850 metric tons (940 US tons) of material being disposed at the Environmental Restoration Disposal Facility. The waste consisted of the DS-100BC-019 and DS-100BC-016

pipelines, soil in contact with the pipelines, and soil 0.3 meter (1 ft) below the pipeline. On June 13, 2007, approximately 40 liters (10 gal) of liquid was released to the soil from the DS-100BC-019 pipeline. Although the liquid was suspected to be dust-suppression water that had been applied during remediation, the impacted soil was placed in a plastic-lined area east of the excavation. The liquid and soil were sampled, and analytical results indicated no contaminants above cleanup level. The soil and plastic liner were disposed at ERDF. The area that contained the staged soil was not included in the verification sampling design due to the fact that it had been lined with plastic prior to placement of soil, and data results indicated that the impacted soil had no contamination above cleanup levels.

The SubSite is Part Of:

Code: 100-B-21

Names: 100-B-21; 100-B/C Miscellaneous Pipelines

Code: 100-B-21:4

Classification: Accepted

Names: 100-B-21:4; Pipeline from the 105-C Reactor East to 116-C-2B Sump

Reclassification: Interim Closed Out (2/9/2010)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The 100-B-21:4 subsite has been remediated and Interim Closed Out. It was previously identified as the DS-100BC-044 discovery pipeline segment. The 20-cm (8-in.) stainless steel, radioactive chemical waste pipeline was at a depth of 6.1 m (20 ft) below ground surface (bgs). The pipeline ran from the northwestern corner of the 105-C Reactor Building, under the 105-C Metal Examination Facility (MEF), and discharged into the 116-C-2B Pluto Crib Pump Station. Although there is documentation of a smaller pipeline exiting the MEF and connecting to the DS-100BC-44 pipeline, this smaller pipeline or residual connection joints were not found during remediation, and they are assumed to have never been present. Drain lines from the MEF to the 116-C-2B sump and other facilities are believed to have been removed during decontamination and decommissioning activities at the 105-C Reactor Building or during field remediation of the 100-C-6:1 process effluent pipelines.

Location: The pipeline ran from the northwestern corner of the 105-C Reactor Building, under the 105-C Metal Examination Facility, and discharged into the 116-C-2B Pluto Crib Pump Station.

Waste Type: Not Specified

Waste Description: The waste is piping and potentially contaminated soil.

Closure Info: Interim: Remedial action at the waste site was performed in April 2009. The site was excavated to a depth of 7.5 meters (25 ft), generating approximately 7,095 bank cubic meters (BCM) (9,280 bank cubic yards [BCY]) of overburden material stockpiled for evaluation for use as clean backfill. The excavation encountered and disposed of approximately 64 meters (210 ft) of 20-cm (8-in.) stainless steel pipeline encased in concrete. Approximately 400 BCM (523 BCY) of debris and soil were sent for disposal at the Environmental Restoration Disposal Facility (ERDF).

The SubSite is Part Of:

Code: 100-B-21

Names: 100-B-21; 100-B/C Miscellaneous Pipelines

Code: 100-B-22

Classification: Accepted

Names: 100-B-22; 100-B Water Treatment Facilities, Pipelines, and Surrounding Soils **Reclassification** Interim Closed Out (3/22/2010)

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: To facilitate remedial activities, the site was divided into two subsites. Subsite 1 consists of the underground transfer piping that interconnected the 100-B Area Water Treatment Facilities and associated soils and was reclassified to No Action. Subsite 2 consisted of the water treatment facility structures (183-B Filter House, 185-B Deaeration Building, 195-B Process Pump House). The facilities associated with 100-B-22:2 were demolished and Subsite 2 was Interim Closed Out. Since both subsites have been reclassified, the parent site is also considered Interim Closed Out.

Location: The water treatment facilities occupied an area approximately 275 meters (900 feet) wide by 365 meters (1200 feet) long and were 91 meters (300 feet) directly west of the 105-B Reactor Building.

The location of each facility include:

The 183-B Filter Plant structures were located along the centerline N144511 and between E564776 and E564846.

The headhouse was located at E564781 N144511.

The 12 flocculation basins were located at E564790 N144511.

The 12 sedimentation basins were located at E564809 N144511.

The filter building was located at E564839 N144511.

Storage tanks were located at E565112 N144511.

The process pump house was located at E565144 N144511.

Release Description: One dichromate release was noted as "a large spill in September 1966" (WHC-MR-0425), but was believed to have occurred on the north side of the 183-C Headhouse (per employee discussion September 2004).

Related Sites/ Structures: 126-B-2 (183-B Clear Water Reservoir), 132-B-1 and 100-B-14 (108-B Chemical Pump House), 105-B Reactor

Process Description: The 100-B Area Water Treatment Facilities were operated from 1944 until 1968, they provided large volumes of high-quality cooling water to the 105-B Reactor. The primary facilities (in the order of the treated water flow) included: 181-B River Pump House or Head House, Flocculation and Sedimentation Basins, Filter Building, 183-B Clear Water Reservoir (126-B-2) and Pump Room; the 185-B Deaeration Facility, the 190-B Process Pump House; and the 108-B Chemical Pump House (132-B-1). Water was removed from the Columbia River by pumps at the 181-B River Pump House and stored temporarily at the 182-B Reservoir. From 182-B, the water was pumped to the 183-B Filter House, where it was treated for use as process cooling water for the B Reactor. Here, chlorine was added to control algae, and sulfuric acid was added to lower the water pH to 7.5 for the coagulation and filtration process. Coagulants included alum, ferric sulfate, and Separan. Following coagulation and settling, the water passed through filters consisting of anthracite coal, sand, and gravel. After filtration, lime was added to raise the pH back to 7.8, and the water was stored temporarily in underground clearwells. The clarified water was next passed through the 185-B Deaeration Plant, where sodium dichromate was added at a rate of 2 parts per million. Until 1950 the sodium dichromate was mixed at the 108-B Chemical Pump House and sent via underground piping to storage tanks inside the 183-B Building. After 1950, sodium dichromate mixing was moved to 183-B. The actual injection points for the sodium dichromate were at the intake header for the storage tanks in the 190-B Process Pump House.

Waste Type: Soil

Waste Description: Fill material placed over potentially contaminated soil and demolished concrete structures. The concrete flocculation and sedimentation basins were collapsed into themselves, and backfilled at least partially with waste material. No record has been found characterizing this waste material, nor has a record been found that any soil samples were taken.

Waste Type: Equipment

Waste Description: Best available information (Sharpe and Linville 2000, Plate 4) indicates that the underground piping connecting the 183-B Filter House and the 185-B/190-B Process Pump House is still in place. The lines are up to 600 meters (1,968 feet) long, and include reinforced concrete, cast iron, and steel pipes up to 137 centimeters (54 inches) in diameter. The paths of the lines are generally north of and parallel to an existing road, N144406; and south of and parallel to an existing road, N144631.

Waste Type: Soil

Waste Description: Contaminants of Potential Concern: Contaminants of potential concern (COPCs) include lead, mercury, hexavalent chromium, and polychlorinated biphenyls (PCBs). Fill material was placed over potentially contaminated soil. Sulfuric acid was added at the 183-B Head house for more than 20 years. Much of the sulfuric acid was known to be contaminated with significant amounts of lead and mercury. The sulfuric acid was unloaded at the facility from two railroad car locations. It is reasonable to assume that, during the early hectic years of operation, some unplanned and unreported spills may have occurred. No record has been found that the soil in the area of the headhouse was sampled and tested for lead and mercury prior to backfilling.

Waste Type: Soil

Waste Description: Two 75,700 liter (20,000 gallon) acid storage tanks, believed to contain concentrated sulfuric acid, were located 12.2 meters (40 feet) south of the south end of the 185-B Deaeration Plant. Acid was unloaded from railroad cars near this location and acid was transferred from these tanks into the Deaeration Plant. The sulfuric acid was contaminated with significant concentrations of lead and mercury. It is prudent to assume unplanned and unreported leaks and spills of this acid may have occurred during the many years of operation of this plant. No records have been found to indicate that soil samples for lead and mercury were taken from this area during or after decommissioning. The tanks were located at E565113, N144451.

Waste Type: Soil

Waste Description: Concrete is located approximately 1 meter (3 feet) below clean fill material. Decommissioning of the 185-B Deaeration Plant, 190-B Process Pump House, and associated pipe tunnels, generally allowed any portion of a structure that was 1 meter (3 feet) below grade to be left in place. Foundation concrete for both buildings, as well as the demolished parts of the tunnels, remain underground, generally within the area bounded by E565103 and E565245, and N144444 and N144584.

This Site has the Following SubSites:

Code: 100-B-22:1

Names: 100-B-22:1; Piping Between 183-B and the 185-B/195-B Building(s)

Code: 100-B-22:2

Names: 100-B-22:2; 183-B Filter House, 185-B Deaeration Building, 195-B Process Pump House and Associated Soils; Water Treatment Facilities and Surrounding Soils

Code: 100-B-22:1

Classification: Accepted

Names: 100-B-22:1; Piping Between 183-B and the 185-B/195-B Building(s)

Reclassification: Interim No Action (9/12/2006)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The pipelines in this subsite were evaluated and determined to require No Action. The subsite consists of the underground transfer piping that interconnected the 100-B Area Water Treatment Facilities and associated soils. The 100-B-22:1 Pipelines and Associated Soils waste site is limited to pipelines that interconnected the 183-B Filter House (including the 126-B-2 Clearwells), the 185-B Deaeration Plant, and the 190-B Process Pumphouse. All of the 100-B-22:1 pipelines are larger than 0.15 meter (6 in.) in diameter and were used for cooling water.

Location: The 100-B-22:1 pipelines are located in the 100-BC-1 Operable Unit in the 100-B/C Area of the Hanford Site, west of the 105-B Reactor.

Process Description: Process knowledge indicated that the pipelines were upstream of facilities where sodium dichromate was added to the process water and of the 105-B Reactor. Also, process knowledge confirms that the chemical additives used to produce the process/cooling water were distributed in smaller volumes than the process water and were transferred in much smaller pipelines. Generally, the chemical transfer lines were 0.08 meters (3in.) or smaller in size. The pipelines, therefore, would not have received discharges containing elevated levels of radionuclides or metals, including lead and hexavalent chromium. Originally, the sodium dichromate was brought into the 185-B/190-B Buildings as a concentrated solution through the sodium dichromate lines (100-B-14:5) that entered on the north side of the building. Cooling water pipelines between the 190-B Building and the 105-B Reactor were part of 100-B-14:4 waste site.

Waste Type: Not Specified

Waste Description: The waste is the underground piping and associated soils.

Closure Info: Interim (9/12/2006): The RSVP indicated that the only additives to the process water in the pipelines came from the 183-B facility. Chemicals added at the 183-B facility included chlorine, sulfuric acid, alum, ferric sulfate, Separan (a coagulant), and lime. Sulfuric acid used for water treatment at the Hanford site, historically had lead and mercury contamination. Where sulfuric acid was spilled or otherwise allowed to collect, lead and mercury have been found above the remedial action goals. These areas were most commonly associated with the transportation and handling of concentrated sulfuric acid. Trace contamination from the sulfuric acid that was added to adjust the pH of the water, would be dilute in the cooling water. There was no evidence to suggest that the pipelines were ever a source of human health risk due to the addition of sulfuric acid.

Considering that the process water routed in the 100-B-22:1 pipelines was relatively clean, the primary risk from pipelines in the area of the 100-B Water Treatment Facilities was identified as the chemical transfer lines. The chemical transfer lines distributed concentrated sodium dichromate solution, sodium silicate solution, and sulfuric acid to buildings in the area.

Examination of excavated trenches as well as historical documents and drawings indicated that all of the pipelines were larger than 0.15 meters (6 inches) in diameter and were used for cooling water, not for the transfer of concentrated chemical solutions. Three small-diameter pipelines, used as chemical transfer lines, were found plumbed into the 183-B and 190-B Buildings. Two of these pipelines, the sodium dichromate and the sodium silicate pipelines connected the 108-B Building to the 185-B/190-B Buildings and are part of sitecode 100-B-14:5. The third small-diameter pipeline was determined to be the sodium dichromate line. designated as the 100-B-28 waste site. Remediation of the 100-B-28 site is expected in 2007.

Three other small-diameter pipelines, used as chemical transfer lines, were found plumbed into the 183-B and 190-B Buildings. Two of these pipelines, the sodium dichromate and the sodium silicate pipelines (100-B-14:5) connected the 108-B Building to the 185-B/190-B Buildings.

The 100-B-14:5 site has been determined to require no action based on confirmatory evaluation. The third small-diameter pipeline has been identified as the sodium dichromate line designated as the 100-B-28 waste site. Remediation of the 100-B-28 site was approved in 2010.

The basis for the No Action determination precluded the need for sampling at this site. Therefore a comparison between soil data and ecological screening levels was not necessary. A baseline risk assessment for the river corridor portion of the Hanford Site began in 2004, which included a more complete quantitative ecological risk assessment. That baseline risk assessment will be used as part of the final closeout decision for this site.

Reclassification evaluations have illustrated that residual soil concentrations support future land uses that can be represented (or bounded) by a rural residential scenario. The evaluations also demonstrated that residual contaminant concentrations support unrestricted future use and that contaminant levels remaining in the soil are protective of groundwater and the Columbia River.

The SubSite is Part Of:

Code: 100-B-22

Names: 100-B-22; 100-B Water Treatment Facilities, Pipelines, and Surrounding Soils

Code: 100-B-22:2

Classification: Accepted

Names: 100-B-22:2; 183-B Filter House, 185-B Deaeration Building, 195-B Process Pump House and Associated Soils; Water Treatment Facilities and Surrounding Soils

Reclassification Interim Closed Out (3/22/2010)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: 100-B-22:2 subsite has been remediated and Interim Closed Out. It consisted of the 183-B Filter House, 185-B Deaeration Plant, and 190-B Process Pumphouse footprints and associated soils. The 183-B clearwells are excluded from this waste site, as they are addressed separately as the 126-B-2 waste site. These facilities were designed to supply, treat, store, and transport cooling water to the 105-B Reactor. The facilities have been decommissioned and demolished to approximately 1 meter (3 ft) below ground surface.

In 2006 and 2009, confirmatory samples were collected from test pits that targeted the entry points for process chemicals into the facilities. Visual investigation and focused sampling was done. Based on confirmatory sample results, it was determined that soil remediation was required only for a small drain line associated with the 183-B headhouse. The remediation was performed in May 2009, by excavating approximately 40 bank cubic meters (50 bank cubic yards) of pipe debris and soil and disposing it at the Environmental Restoration Disposal Facility.

Location: The 185-B/190-B Building was approximately 100 meters (330 feet) west of the 105-B Reactor; the 183-B Building was approximately 400 meters (1/4 mile) west of the Reactor.

Process Description: The 105 B Reactor was a single-pass reactor, so cooling water was not recycled after its initial use. All water had to be treated and conditioned prior to use in the reactor to prevent pipes within the reactor from corroding and to prevent constituents dissolved in the water from precipitating and eventually restricting flow through the aluminum pipelines used for cooling the core of the reactor. Cooling water was pumped from the Columbia River via the 181-B river pumphouse into the 182-B reservoir. From the reservoir, water flowed into the 183-B Treatment Plant where it was treated with chlorine, sulfuric acid, and coagulants such as alum, ferric sulfate, and Separan. After flocculation, particle settling, and filtration, the clarified water

was stored in large underground clearwells. From the clearwells, water flowed to the 185-B Deaeration Plant via the 100-B-22:1 cooling water pipelines. The 185-B Deaeration Plant was never used for deaeration as originally intended. It did, however, contain two 3,785 liters (1,000-gal) storage tanks where concentrated sodium dichromate solution was stored. Originally, the sodium dichromate solution was mixed and piped in from the 108-B Building. In the early 1950's, the sodium dichromate mixing was moved into the 185-B Building. The sodium dichromate solution was added to the cooling water lines at the common wall of the 185-B and 190-B facilities. Cooling water was stored in the 190-B Process Pumphouse in four 6.62 million liters (1.75 million gallons) tanks. Water stored in the 190-B Process Pumphouse was available for use in the 105 B Reactor on an as-needed basis via piping in underground tunnels (100-B-14:4 subsite).

Waste Type: Not Specified

Waste Description: The remaining footprint of these facilities contains inert concrete debris and structural material below 1 meter (3 feet) below ground surface, along with other clean fill used to bring the site to grade. Fill material placed over potentially contaminated soil and demolished concrete structures.

Closure Info: Interim (3/22/2010): In 2006 and 2009, confirmatory sampling was collected from four Test Pits. Visual investigation and focused sampling was done. The samples targeted the entry points for process chemicals into the facilities. Based on confirmatory sample results, it was determined that soil remediation was required only for a small drain line associated with the 183-B headhouse. The drain was located within the railcar park at the 183-B headhouse. The contamination was likely related to spillage and washout collection, rather than a leak in the line. It was excavated in September and November 2006, revealing a 7.6 centimeter (3-in.) cast iron pipe extending approximately 0.6 meters (2 ft) below ground surface (bgs). The pipeline was excavated up to the edge of an exterior concrete pad at the former 183-B headhouse, where it entered the facility. It presumably connected with one of the sumps associated with the 100-B-14:3 Process sewers. Samples were collected from stained soils beneath the former railroad tracks near the drain and from soil underlying the pipeline where it entered the 183-B facility.

Soil staining was observed beneath railroad ties, as previously observed and sampled during confirmatory sampling. Results from confirmatory sampling of this material and sampling analogous staining associated with railroad ties at other 100-B/C locations have demonstrated that no hazardous constituents are present above cleanup levels in these soils. Stained soils and decayed wood material were also observed along the southern side of the concrete footing beneath the drain line. Stained soils and concrete were also observed at the southeastern corner of the excavation. No samples were collected from this material at the time of remediation.

The remediation was performed in May 2009, by excavating approximately 40 bank cubic meters (50 bank cubic yards) of pipe debris and soil and disposing it at the Environmental Restoration Disposal Facility. Remediation proceeded to a maximum depth of approximately 0.9 meters (3 ft) at the eastern end, removing at least 0.3 meters (1 ft) of soil underlying the drain line and soils disturbed during previous confirmatory sampling activities. The 183-B facility foundation was observed to continue beyond the depth of excavation at the eastern end, and a concrete footing is evident beneath the drain line where it enters the facility.

The SubSite is Part Of:

Code: 100-B-22

Names: 100-B-22; 100-B Water Treatment Facilities, Pipelines, and Surrounding Soils

Code: 100-B-24

Classification: Accepted

Names: 100-B-24; 116-B-7 Spillway (Flume)

Reclassification: Interim No Action (9/18/2006)

Type: Outfall**Start Date:****Status:** Inactive**End Date:****Description:** The site has been sampled and found to meet the requirements for reclassification to "No Action". The 100-B-24 Spillway (also referred to as a flume) was constructed of concrete and led from the 116-B-7 outfall structure to the river shoreline. The flume was decommissioned and backfilled in 1979.**Location:** The site was located northwest of 116-B-11 Retention Basin and upstream of the 132-B-6 Outfall. The remaining portion of the spillway is 18 meters (60 feet) downstream of, and parallel to, the river effluent pipeline.**Related Sites/ Structures:** The site was associated with the 100-B-15 River Effluent Pipelines and the 116-B-7 Outfall Structure.**Process Description:** The spillway was an alternate discharge point for the 116-B-7 Outfall Structure. The spillway was to be for an emergency effluent release or if the 100-B-15 river effluent pipelines were blocked, damaged, or undergoing maintenance. There was no corroborated physical or historical evidence that the spillway was ever used.**Waste Type:** Construction Debris**Waste Description:** No evidence has been found that the flume was ever put into service. If it had been used the COPCs for the 100-B-24 spillway would be the same as those for the 116-B-7 outfall structure, which are as follows: americium-241, cobalt-60, cesium-137, europium-152, europium-154, europium-155, tritium, nickel-63, uranium-234, uranium-235, uranium-238, plutonium-238, plutonium-239/240, strontium-90, total chromium, hexavalent chromium, lead, and mercury.**Closure Info:** Interim (9/18/2006): Between July and December of 2001, the 116-B-7 outfall structure was removed and disposed along with the upper portion of the spillway. The remaining concrete spillway structure was partially covered with clean fill down to the normal water level at the river shoreline. The spillway was excavated, sampled, and analyzed for chemicals and radionuclides. The contamination was bound in the concrete structure. It was concluded that remedial action to remove the concrete had the possibility of destabilizing the riverbank. To avoid and minimize the impacts on the river and the local ecosystem of the release of soils and sediments into the river, it was reasonable to conclude that there was a greater risk posed to the river and the local ecosystem by a removal action than was posed by leaving it in its current state.

Code: 100-B-25**Classification:** Accepted**Names:** 100-B-25; 132-B-6 Spillway (Flume)**Reclassification:** Interim Closed Out (1/13/2010)**Type:** Outfall**Start Date:****Status:** Inactive**End Date:****Description:** The site has been remediated and reclassified to Interim Closed Out. The site consisted of a concrete Spillway (also referred to as a flume) that led from the 132-B-6 outfall structure, via a heavy riprap extension on the end of the concrete spillway, to the river shoreline. During decommissioning projects in the 1979, the spillway walls were collapsed and the structure was covered with clean soil.**Location:** The site was located north of the northeast corner of the 116-B-11 (107-B Retention Basin) and downstream of 116-B-7 (the 1904-B1 Outfall).**Related Sites/ Structures:** The site is associated with the 100-B-15 River Effluent Pipelines and the 132-B-6 Outfall Structure.

Process Description: The spillway was an alternate discharge point for the 132-B-6 Outfall Structure. It was planned to be used only if the 100-B-15 river effluent pipelines were blocked, damaged, or undergoing maintenance. There is no corroborated historical information that the spillway was ever used.

Waste Type: Demolition and Inert Waste

Waste Description: Possible chemical and/or radionuclide contamination (see Contaminants of Potential Concern). No evidence has been found that the flume was ever put into service. If it had been used, the COPCs for the 100-B-25 spillway would be the same as those for the 132-B-6 outfall structure, which are as follows: Americium-241, cobalt-60, cesium-137, europium-152, europium-154, europium-155, tritium, nickel-63, uranium-234, uranium-235, uranium-238, plutonium-238, plutonium-239/240, strontium-90, total chromium, hexavalent chromium, lead, and mercury.

Closure Info: Interim: Radiological surveys were performed along the 100-B/C Area shoreline during 2002 and 2003, as part of the 100-B/C pilot study. Gamma readings up to 8,170 counts per minute were observed at the surface in the exposed riprap, portions of the 100-B-25 Overflow Spillway. Based upon this information, the decision was made to include the 100-B-25 overflow spillway for the remove, treat, and dispose process. Excavation of the 132-B-6 Outfall sump in 2001 included removal of the upstream portion of the 100-B-25 spillway that was located within the excavation layback. Remedial action at the 100-B-25 waste site was performed between February 3 and March 14, 2009. Remediation encompassed the removal of a large volume of overburden that had been added in 2001, after the upper portion of the spillway was removed during the 132-B-6 Outfall remediation. The remaining spillway structure was unearthed and removed. Basalt rocks that formed the riprap on the slope to the Columbia River were removed for disposal due to elevated radiological readings.

The site was excavated to a maximum depth of approximately 5 meters (16 ft) below grade, resulting in the removal of approximately 2,682 bank cubic meters (BCM) (3,504 bank cubic yards [BCY]) of material for disposal at the Environmental Restoration Disposal Facility (ERDF). Approximately 4,991 BCM (6,521 BCY) of soil (overburden) was stockpiled for evaluation as clean backfill. Material awaiting disposal in the waste staging piles was removed and disposed at ERDF in July 2009.

Code: 100-B-26

Classification: Accepted

Names: 100-B-26; 132-C-2 Spillway (Flume)

Reclassification: Interim No Action (9/18/2006)

Type: Outfall

Start Date:

Status: Inactive

End Date:

Description: The site has been sampled and found to meet the requirements for reclassification to No Action. The flume was decommissioned and backfilled in 1979. The 100-B-26 Spillway (also referred to as a flume) was constructed of concrete and led from the 132-C-2 outfall structure to the river shoreline. During 2001, the 132-C-2 Outfall Structure was removed and disposed. At the same time, most of the upper portion of the spillway was also removed and disposed.

Location: The site was located just north of 116-B-11 (the 107-B Retention Basin) and downstream of 132-B-6 (the 1904-B2 Outfall). The remaining portion of the spillway was along a centerline from E 565724, N 145498, a minimum of 7 meters (23 feet) due north to E 565724, N 145505. The top half of the remaining spillway was concrete, and the bottom half was heavy riprap.

Related Sites/Structures: The site was associated with 100-B-15 (the 100-B/C River Effluent Pipelines) and 132-C-2 (the 1904-C Outfall Structure).

Process Description: The spillway (also referred to as a flume) was constructed of concrete and led from the 132-C-2 outfall structure, via a heavy riprap extension on the end of the concrete spillway, to the river shoreline. During decommissioning projects in the 1979, the spillway walls were collapsed and

the structure was covered with clean soil.

The upper portion of the spillway was removed in 2001 as part of remediation of the outfall structure, and the remainder of the spillway/riprap was backfilled with clean soil. The spillway was an alternate discharge point for the 132-C-2 Outfall Structure. It was planned to be used as an alternate for effluent only if the 100-B-15 river effluent pipelines were blocked, damaged, or undergoing maintenance. There was no historical information that the spillway was ever used.

Waste Type: Construction Debris

Waste Description: If ever put into service, the COPCs for the 100-B-26 spillway would be the same as those for the 132-C-2 Outfall, which are as follows: Americium-241, cobalt-60, cesium-137, europium-152, europium-154, europium-155, tritium, nickel-63, uranium-234, uranium-235, uranium-238, plutonium-238, plutonium-239/240, strontium-90, total chromium, hexavalent chromium, lead, and mercury.

Closure Info: Interim (9/18/2006): Confirmatory sampling of the waste site was conducted on January 17, 2006. Heavy equipment was used to excavate through the riprap, and the underlying soils were sampled. The sample results indicated that six constituents slightly exceeded remedial action goals for the protection of groundwater and the Columbia River. The contamination is bound to the concrete structure. The residual contaminants within the spillway present little risk to human health and the environment compared to the effect remediating the spillway could have on the Columbia River and its shoreline.

The riprap section of the spillway remains, with the upper portion covered by clean fill. A rudimentary road crosses the otherwise exposed lower riprap section. The site was reclassified to No Action because remediation to remove the riprap and underlying soils presented the possibility of destabilizing the riverbank and disturbing the existing ecosystem.

Code: 100-B-27

Classification: Accepted

Names: 100-B-27; Sodium Dichromate Spill

Reclassification: Interim Closed Out (4/12/2010)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The site has been remediated and Interim Closed Out. It was an unplanned release of sodium dichromate that was discovered while removing the western staging pile associated with the cleanup of the 126-B-3 Coal Pit.

Soil contamination associated with the spill consisted of a fairly narrow, near-vertical plume in the upper vadose zone (to approximately 11 meters [36 ft] below ground surface [bgs]). Below this depth, the plume continued downward in a generally northeasterly direction. Soil contamination was found down to the groundwater table, located approximately 13.5 meters (44 ft) bgs.

Location: The site was located 50 meters (164 ft) west of the former 126-B-3, Coal Pit.

Related Sites/Structures: The site may be related to a temporary receiving and storage warehouse. The Plot Plan for 100-B Area shows a material storage platform on the west end of the receiving warehouse. Initially, sodium dichromate was used in dry form thus, the platform was likely used for material offloading from railroad cars. A railroad spur diverted from the main railroad track north of the material handling platform. It extended east with 305 meters (1000 ft) of track before it rejoined the main track. The site was associated with 126-B-3.

Process Description: The source of contamination was unknown, but may have been related to a temporary receiving and storage warehouse that was located near the northern railroad spur. The warehouse was

likely used for material offloading and storage from the railroad cars. Sodium dichromate was used in dry form at 100-B/C and transported via railroad until about 1955, when receipt of incoming sodium dichromate as a liquid solution began. The 100-B-27 waste site is believed to be associated with spillage and/or dumping of unknown amounts of sodium dichromate.

Waste Type: Chemical Release

Waste Description: The contaminant of potential concern is Cr6. Sample results for J030K6 show greater than 500 mg/kg total chromium (15,000 ug/L chromium by TCLP). Elevated chromium concentrations were also detected in waste characterization samples that were collected from segregated soil (J03CP6 and J03CP7). The waste was soil contaminated with sodium dichromate. The suspected source of the sodium dichromate is consistent with handling and delivery of this material in bagged dry form. Sodium dichromate was delivered in dry form until about 1955 when modifications were made to use liquid sodium dichromate.

Closure Info: Interim (4/12/2010): Initial remediation was performed from June 18 to 20, 2007, with excavation extending to approximately 4.6 meters (15 ft) below ground surface (bgs). Approximately 900 metric tons (1,000 U.S. tons) of contaminated material was removed. Additional characterization showed that contamination extended to groundwater, so a decision was made to postpone remedial action until 2009.

Remediation resumed in February 2009, removing contaminated material until the groundwater table was encountered at approximately 14 meters (46 ft) below ground surface. As remediation proceeded, rising Columbia River levels resulted in groundwater seeping into the excavation at approximately 13.5 m (44 ft) bgs. Excavation activities were completed on June 9, 2009. A total of approximately 10,190 bank cubic meters (BCM) (13,330 bank cubic yards [BCY]) of contaminated soil and 40,180 BCM (52,550 BCY) of overburden/layback soil were excavated. The contaminated soil disposed at the Environmental Restoration Disposal Facility.

Well 199-B5-1 (C7505) was drilled to a depth of 189 feet in January 2010 to assess the depth of contamination.

Code: 100-B-28	Classification: Accepted
Names: 100-B-28; 183-C Headhouse to 183-B Pumphouse Sodium Dichromate Transfer Pipeline	Reclassification: Interim Closed Out (3/22/2010)
Type: Product Piping	Start Date:
Status: Inactive	End Date:

Description: The waste site has been remediated and Interim Closed Out. It consisted of an underground sodium dichromate pipeline from the 183-C Head House to the 183-B Filter Plant/Pump House. The pipeline was originally a soft water supply line from the 184-B Power House to the 183-C Head House.

The 7.6-centimeter (3-inch) steel line for supplying soft water from the 184-B Power House to the 183-C Head House was modified per the drawing (H-1-10350) at a point due east of the 183-B Filter Plant/Pump House in about 1962. The line from the 184-B Power House was blanked and a new line was run to the 183-B Filter Plant to allow use of the southern extent of the 3-inch steel line as a sodium dichromate transfer line from the 183-C Head House to the 183-B Filter Plant.

Location: The northern end of the waste site was located approximately 430 meters (1,410 ft) directly west of the 105-B Reactor. The southern end of the pipeline was 9 meters (28 ft) northwest of the former 183-C Filter Plant. The remaining southern portion of the pipeline is considered within the footprint of the 100-C-7:1 waste site.

Release Description: Concentrated sodium dichromate solution was drained from the "softwater" pipeline (1,2) that was excavated and opened during July-August 2005 at the 100-C-7 waste site (dichromate unplanned release) north of the 183-C Head House. The piping drawing (3) indicates the 7.6-cm (3-in) softwater line was modified in 1962 to serve as a sodium dichromate solution transfer line from the 183-C Head House to the 183-B Filter Plant. The sodium dichromate solution was collected and disposed. The spilled material was contained within the existing 100-C-7 waste site (a sodium dichromate unplanned release waste site).

Related Sites/ Structures: 183-C Head House; 183-C Filter Building/Pump Facility; 184-B Power House

Process Description: Sodium dichromate solids and concentrated solutions were received, stored, and mixed with the reactor cooling water as a corrosion inhibitor for the reactor fuel and piping. Initially, granular sodium dichromate was mixed with water to prepare a 15 Weight Percent solution that was metered into the volute of the primary pumps in the 190-B Pump House to provide a 2 part per million (ppm) concentration of sodium dichromate in the reactor cooling water. Later, the solid sodium dichromate feedstock was replaced with a concentrated (70% by weight) sodium dichromate solution that was metered into the cooling water to produce the 2 ppm concentration of sodium dichromate. The southern section of the soft water line was isolated from the 184-B Power House supply line at a point east of the 183-B Filter Plant and the northern section was blanked. A new pipeline segment was installed to connect the southern section of the pipeline to the 183-B Filter Plant.

Waste Type: Abandoned Chemicals

Waste Description: Concentrated sodium dichromate solution was drained from the converted softwater pipeline (1-3) excavated and opened at the 100-C-7 waste site (dichromate unplanned release) north of the 183-C Head House. The 7.6-cm (3-in) softwater line was modified in 1962 to serve as a sodium dichromate solution transfer line from the 183-C Head House to the 183-B Filter Plant.

Closure Info: Interim: Remedial action at the site was performed from February to April 2009. Remediation included removing and staging overburden material, hot tapping, draining, and collecting the pipeline liquid; size-reducing and removing the pipeline, and removing and staging contaminated material for disposal at the Environmental Restoration Disposal Facility (ERDF). Two sections of pipeline beneath active utility lines were grouted in-place. The potential for pipe leakages beneath these sections could not be addressed while the utilities remain active. Therefore, in agreement with DOE-RL and EPA, these two sections will be administratively removed from the site and placed in a new waste site created to collect components from various waste sites that cannot be remediated while utilities remain active.

The grout-filling campaign for the two sections of pipeline that were left in place was initiated on April 13, 2009, and completed on April 14, 2009. The grout was pumped into the northern section of the 100-B-28 pipeline. This section of pipeline, approximately 26 meters (85 ft) in length, was located beneath an active pipeline supplying water for fire suppression water. During grout addition, approximately 76 liters (20 gal) of sodium dichromate liquid was displaced, collected, and drummed. The second section of pipeline, approximately 26 meters (85 ft) long, ran beneath the export water line located at the southern end of the excavation. Approximately 38 liters (10 gal) of sodium dichromate liquid was displaced during grout addition. It was also collected and drummed.

During the excavation of the southern portion of the site, discolored soil was encountered at the base of the 7.6-cm (3-in.) pipeline. The worst of the discolored material soil was sampled (J18N79) for ICP metals and TCLP metals. Data results showed TCLP values for chromium at 130 mg/L. The material was Land Disposal Restricted requiring treatment for disposal at ERDF. Sampling was not performed on the less-impacted soils. However, it was conceded the material would qualify as LDR material. Approximately 40 BCM (52 BCY) of material required treatment. During removal of contaminated soil and a concrete encasement

surrounding the grout-filled pipeline, a 6.1-meter (20-ft) section sheared off the end. This section was placed into an ERDF container. The remainder of the pipeline was grouted.

Code: 100-B-32	Classification: Accepted
Names: 100-B-32; SCA #1; Soil Contamination Area Associated with Legacy Waste	Reclassification: Interim Closed Out (1/13/2010)
Type: Unplanned Release	Start Date: 1/1/2005
Status: Inactive	End Date: 1/1/2009

Description: The waste site has been remediated and Interim Closed Out. The site had been a Surface Contamination Area (SCA) found on the haul route from the 118-B-1 Burial Ground to the container transfer area. The area was previously posted as an SCA due to multiple locations of elevated radiological activity identified by LARADS. Field instrumentation indicated a location with approximately 3.4 million dpm/100 square centimeters beta/gamma activity at this spot. The hot spot measured approximately 25 square centimeters. The contamination at this location was matrixed with the asphalt and is believed to be a legacy of past practices and operations. Down-posting efforts following completion of remediation and closure activities in the area confirmed an area of significantly elevated radiological activity at the location listed.

No other areas of significant elevated activity were identified along the posted haul route at the locations previously identified based on 2005 LARADS data.

Location: The site was located in 100-B/C Area, south of the 182-B Reservoir, just west of the intersection of Burnett Avenue and Bow Street, and on the southern portion of the roadway surface. The approximate Washington State Plane coordinates are E564738, N144362.

Related Sites/ Structures: 100-B-32 is associated with 118-B-1 Burial Ground.

Waste Type: Soil

Waste Description: The waste is contaminated soil and asphalt. The contaminants of potential concern are radiological contaminants. The source of this material is unknown.

Closure Info: Interim: Remedial action activities were performed on July 28, 2009. Verification sampling at the 100-B-32 waste site occurred on August 10, 2009. Remediation was performed using an excavator to remove asphalt and underlying contaminated material identified by hand-held instrumentation. Verification sampling was performed after the contaminated material was removed.

Code: 100-B-33	Classification: Accepted
Names: 100-B-33; SCA #2; Soil Contamination Area 2 Associated with Legacy Waste	Reclassification: Interim Closed Out (1/13/2010)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The site has been remediated and Interim Closed Out. It was a posted Surface Contaminated Area (SCA). The site was discovered during GPERS surface soil surveys of the north-east quadrant of the 100-BC Area in July - August 2007. The survey showed an area of elevated readings averaging 15,000 cpm over a 150 square meter area with a maximum reading of 93,000 cpm.

Location: The site was located in the north-east quadrant of the 100-B/C Area, north of the railroad tracks

and west of the former 100-C-9:1 pipeline. The approximate Washington State Plane coordinates are E565557.125, N144949.672.

Waste Type: Soil

Waste Description: The waste is contaminated soil. The contaminants of potential concern are radiological contaminants. The source of this material is unknown.

Closure Info: Interim: Remedial action was performed from May to August 2009. Remediation consisted of removing soils with elevated radiological activity identified with field instrumentation. Approximately 310 bank cubic meters (410 bank cubic yards) of contaminated soil was excavated and staged on site before being disposed at the Environmental Restoration Disposal Facility.

Two surface characterization samples were collected in April 2009. A post remediation radiological survey was done in August 2009. Following remediation, verification sampling was conducted in September 2009.

Code: 116-B-1	Classification: Accepted
Names: 116-B-1; Process Effluent Trench; 107-B Liquid Waste Disposal Trench	Reclassification: Interim Closed Out (12/8/1999)
Type: Trench	Start Date: 1/1/1950
Status: Inactive	End Date: 1/1/1968

Description: The site has been remediated and closed out. The 116-B-1 Liquid Waste Disposal Trench was dug to receive effluent routed from 116-B-11 (107-B Retention Basin). The unit ran from southwest to northeast. The site included the 40.6 centimeter (16 inch) diameter steel piping from 116-B-11. Historical documents described the trench as a french drain or an excavation that was partly or completely filled with coarse gravel and had dimensions of 61 meters (200 feet) long by 9.1 meters (30 feet) wide by 4.6 meters (15 feet) deep. A geophysical investigation of 116-B-1 performed in November and December 1996 showed the trench was almost twice as long as indicated by historical information (see Dimensions). The Ground Penetrating Radar (GPR) survey identified a pipeline, labeled #10 in the survey report, entering the trench at its southwest end. No other pipelines were evident. A significant volume of buried debris was present in the northeastern half of the trench.

Location: The site was located east of the 107-B Retention Basin.

Related Sites/Structures: The site was associated with the 107-B Retention Basin and the 107-C Retention Basin.

Waste Type: Misc. Trash and Debris

Waste Description: Geophysical investigation identified a high concentration of subsurface debris in the northeastern half of the trench.

Waste Type: Process Effluent

Waste Description: The site received effluent from the 107-B Retention Basin at times of high activity due to fuel element failures. The fission products of 54 fuel ruptures were routed to this site.

Closure Info: Interim (12/8/1999): Excavation of the 116-B-1 site began on October 6, 1998, by removing the overburden materials and underlying contaminated soil. Based on field screening, overburden materials that were identified as potentially clean were placed in stockpiles for potential use as backfill. Overburden materials that were found to be contaminated were disposed of at ERDF. On January 6, 1999, the excavation had reached the design limit at El. 128.0 m (438 ft). Soils

not meeting direct exposure RAGs based on field screening results were excavated, loaded into shipping containers, and disposed of at ERDF. Cleanup verification sampling began on February 1, 1999, and was finished on February 24, 1999. At the completion of the remedial action and removal of the engineered structure, the excavation area floor was approximately 1,863.3 square meters (20,056 ft or 0.460 acres) at a depth of approximately 4.6 meters (15 ft), and approximately 43,033 metric tons (47,436 tons) of material from the site were disposed of at ERDF. The excavation will be backfilled in the near future to the reference grade of El. 132.5 meters (438 ft). Clean backfill may be taken from the clean overburden pile and other sources of clean material that have been surveyed in accordance with the SAP (DOE-RL 1998a) and that are appropriate for use as backfill. Overburden from 116-B-1, 116-C-5, and pipeline excavation was segregated and sampled for potential use as clean backfill.

The maximum dose rate (all pathways) predicted from the RESRAD dose assessment model is 5 mrem/year in 1999, and decreases to 0.014 mrem/year in 1,000 years, based on samples taken from the excavation walls and floor. Hexavalent chromium is the only non-radionuclide carcinogenic contaminant of concern; the risk value was three orders of magnitude below the individual and cumulative risk limits.

Code:	116-B-2	Classification:	Accepted
Names:	116-B-2; B-Storage Basin Crib; 105-B Storage Basin Trench	Reclassification	Interim Closed Out (2/24/2000)
Type:	Trench	Start Date:	1/1/1946
Status:	Inactive	End Date:	1/1/1946

Description: This site was remediated and closed out on February 24, 2000. It is no longer marked or posted.

The trench was used one time to receive approximately 4E+06 liters (1.1E+06 gallons) of storage basin water that became contaminated when a fuel rod was accidentally cut in half. The trench was backfilled after use with clean dirt.

Location: The 116-B-2 site was located near the center of the 100-B Area, approximately 865 meters (2,838 feet) from the Columbia River and 76 meters (250 feet) northeast of 105-B Storage Basin.

Process Description: The trench was only used once in 1946 to receive contaminated basin water after a fuel element was accidentally cut in half in the 105-B Fuel Storage Basin.

Waste Type: Water

Waste Description: This unit was dug and used once after a fuel element was accidentally cut in half in the 105-B Storage Basin. Basin water was discharged to this unit in an attempt to remove radionuclides from the fuel storage basin cooling water for contamination control.

Closure Info: Interim: Excavation of the 116-B-2 site began on February 17, 1999, by removing the overburden materials and underlying contaminated soil. Based on field screening, materials identified as potentially clean were placed in stockpiles for potential use as backfill. Materials that were found to be contaminated were disposed of at the ERDF. After completion of the initial excavation to design limits, several contaminated areas (i.e., plumes) were discovered. Each of the plumes was excavated and the new surfaces were screened for contamination. On May 20, 1999, the excavation had reached the final limit at El. 138.4 meters (454.2 feet). Cleanup verification sampling began on May 21, 1999, and was finished on June 24, 1999.

At the completion of the remedial action, the excavation floor area was approximately 459 square meters (4,940 square feet) at a depth of approximately 4.9 meters (16 feet), and

approximately 9,393 metric tons (10,354 tons) of material from the site had been disposed of at ERDF.

The excavation was backfilled with clean fill materials to the reference grade of El. 143.3 meters (470.2 feet). Clean backfill may be taken from the clean overburden pile and other sources of clean material that have been verified clean in accordance with the SAP (DOE-RL 1998) and that are appropriate for use as backfill.

The cleanup verification package (CVP) demonstrated that remedial action at the 116-B-2 site has achieved the RAOs and corresponding RAGs established in the approved interim action ROD (EPA 1995) and RDR/RAWP. Materials that contained COCs at concentrations exceeding the RAGs have been excavated and disposed of at the ERDF. The remaining soils have been sampled, analyzed, and modeled to show that residual concentrations will support future land uses that can be represented (or bounded) by a rural-residential scenario. This scenario, described in Section 4.2 of the CVP, assumes multiple exposure pathways (e.g., ingestion, inhalation, direct exposure) for shallow zone soils. (The acceptability of unrestricted direct exposure to deep zone soils has not been demonstrated; therefore, institutional controls to prevent uncontrolled drilling or excavation into the deep zone [i.e., below 4.6 meters (5 feet)] are required.) The verification package also demonstrated that residual COC concentrations pose no threat to groundwater or the Columbia River. Thus, the 116-B-2 site was verified to be remediated and may be backfilled.

Code:	116-B-3	Classification:	Accepted
Names:	116-B-3; 105-B Pluto Crib	Reclassification	Interim Closed Out (2/24/2000)
Type:	Crib	Start Date:	1/1/1951
Status:	Inactive	End Date:	1/1/1952

Description: The 116-B-3 Pluto Crib has been remediated and was closed out on February 24, 2000. It is no longer marked or posted.

This unit was a wooden crib shored with railroad ties, filled with gravel and covered to grade with clean soil. A concrete marker indicates the position of the crib. Clukey (1954) indicates that the crib is a french drain, otherwise defined as a "tile or pipe buried vertically, sometimes gravel-filled". After its use, the crib was reportedly unearthed and shored with wooden ties.

Location: This unit was located within the 105-B Area exclusion fence, about 30 meters (100 feet) east of the 105-B Building and about 847 meters (2,780 feet) from the 100-year flood level of the Columbia River.

Process Description: This pluto crib received 105-B cooling water wastes that had been contaminated by cladding ruptures of fuel elements. Cooling water diversion occurred when a fuel element rupture was detected within a process tube. The water was diverted from the affected process tube through a valve on the rear of the reactor face known as a "pluto valve" and through rubber hose to the crib. The wooden crib was buried so that its upper surface was approximately at grade. A hatch on the upper surface was opened to receive the rubber hose and the crib was allowed to flood.

Waste Type: Water

Waste Description: The site received effluent from reactor tubes containing ruptured fuel elements.

Closure Info: Interim (2/24/2000): Excavation of the 116-B-3 site began on February 17, 1999, by removing the overburden materials and underlying contaminated soil. Based on field screening, materials

identified as potentially clean were placed in stockpiles for potential use as backfill. Cleanup verification sampling began on April 13, 1999, and was finished on May 12, 1999. At the completion of the remedial action, the area of the excavation was approximately 112.38 square meters (1,209.6 square feet) at a maximum depth of approximately 4.6 meters (15 ft).

Approximately 244 metric tons of material from the site were disposed at the ERDF. The excavation was to be backfilled with clean fill materials to the reference grade of El. 143 meters (469 feet).

The remaining soils have been sampled, analyzed, and modeled to show that residual concentrations will support future land uses that can be represented (or bounded) by a rural-residential scenario. The acceptability of unrestricted direct exposure to deep zone soils has not been demonstrated; therefore, institutional controls to prevent uncontrolled drilling or excavation into the deep zone [i.e., below 4.6 meters (15 feet)] are required. The verification package also demonstrated that residual COPC concentrations pose no threat to groundwater or the Columbia River. Thus, the 116-B-3 site has been verified to be remediated and may be backfilled.

Code:	116-B-4	Classification:	Accepted
Names:	116-B-4; 105-B Dummy Decontamination Disposal Crib; 105-B Dummy Decontamination French Drain	Reclassification:	Interim Closed Out (2/24/2000)
Type:	French Drain	Start Date:	1/1/1957
Status:	Inactive	End Date:	1/1/1968
Description:	This site has been remediated and closed out. It is no longer marked or posted.		
	The unit had a graded rock and sand bottom. It was marked with four yellow steel posts and had a curved stainless steel pipe in the center along with a painted concrete marker. The site included a feed pipe that originated at the 105-B Building.		
Location:	The 116-B-4 site was located near the center of the 100-B Area and was approximately 806.6 meters (2,646 feet) from the Columbia River and approximately 21 m (69 ft) south of 116-B-3 Pluto Crib.		
Related Sites/ Structures:	The site was associated with the 105-B Building (118-B-8).		
Process Description:	The 116-B-4 French Drain received spent acid rinse water from the 105-B Dummy Decontamination Facility, which was used for the decontamination of fuel element spacers and other reactor hardware. The french drain was fed by a single, underground stainless steel pipe. Acids were neutralized within the 105-B Dummy Decontamination Facility prior to discharge to the french drain.		
Waste Type:	Process Effluent		
Waste Description:	The site received spent acid and rinse water from the 105-B Dummy (fuel element spacers and reactor hardware) Decontamination Facility.		
Closure Info:	Interim: Initial, partial remediation of the 116-B-4 site was completed under the 100-B/C Demonstration Project. This phase began on July 11, 1995, and was completed on July 28, 1995. Additional contaminated materials (i.e., plumes) were identified during the 100-B/C Demonstration Project, but excavation was deferred until 1999. Deep zone cleanup verification samples were taken from the bottom of the 100-B/C Demonstration Project excavation in July 1995. Sampling and analysis activities were completed in accordance with the applicable		

Sampling and Analysis Plan and Quality Assurance Project Plan in the 100-BC-1 Excavation Demonstration Project Plan (DOE-RL 1995). Remediation began on July 11, 1995, under the 100-B/C Demonstration Project. Excavation of the initial waste site footprint was completed July 28, 1995. Additional contaminated material was identified to the north, south, east, and west.

After discussions with the decision makers, partial excavation of the plumes commenced on September 25, 1995. Excavation for the demonstration project was completed on December 18, 1995. Screening samples collected during excavation were analyzed at the Hanford Environmental Analysis Laboratory, and post-excavation verification samples were analyzed at the offsite Quanterra Laboratory. After verification sampling, the site was backfilled. Excavation to complete the remediation of the 116-8-4 site plumes began on February 17, 1999, by removing the overburden materials and underlying contaminated soil. Based on field screening, materials identified as potentially clean were placed in stockpiles for potential use as backfill. Materials that were found to be contaminated were disposed of at ERDF. On April 4, 1999, the excavation had reached the design limit at El. 138.43 meters (454 ft). Cleanup verification sampling began on April 12, 1999, and was finished on May 6, 1999.

In February 1999, excavation began to complete the remediation of the 116-B-4 site plumes by removing the overburden materials and underlying contaminated soil. On April 4, 1999, the excavation had reached the design limit at El. 138.43 meters (454 feet). Cleanup verification sampling began on April 12, 1999, and was finished on May 6, 1999. The resulting data were used together with the 1995 data to support cleanup verification for the entire site.

At the completion of the remedial action, the excavation area floor was approximately 1,062 square meters (11,433 square feet) at a depth of approximately 4.6 meters (15 feet), and approximately 8,700 metric tons (9,590 tons) of material from the site had been disposed at ERDF.

Code:	116-B-5	Classification:	Accepted
Names:	116-B-5; 116-B-5 Crib; 116-B-5 Trench; 108-B Crib	Reclassification	Interim Closed Out (1/14/1999)
Type:	Crib	Start Date:	1/1/1950
Status:	Inactive	End Date:	1/1/1968
Description:	This waste site has been remediated and Interim Closed Out. The crib structure and its contents have been removed. The crib was constructed of concrete timbers and consisted of 12 rectangular cells in a single row. Each cell was partially filled with sandy gravel and had a separate concrete lid. For cleanup purposes, the cells were identified using the letters "A" through "L", with cell A being the southernmost cell. The crib was fed with a vitrified clay pipe.		
Location:	The crib was located approximately 46 meters (150 feet) north of the 108-B Building site (132-B-1) and east of the 108-B Ventilation Exhaust Stack Burial Ground (132-B-3).		
Waste Type:	Process Effluent		
Waste Description:	The site received liquid tritium wastes from the 108 Building. Only wastes of less than 1 microcuries/cubic centimeter were discharged to this unit.		
Closure Info:	Interim (1/14/1997): In June 1995, the site was excavated as part of the 100-B/C Demonstration Project. Remedial action was accomplished by excavating approximately 300 cubic meters (10,600 cubic feet) of soil from the crib and demolishing the concrete crib structure, leaving an open excavation approximately 34 meters (112 feet) by 8 meters (26 feet) to a 5 meter (16 feet) depth. The soils within and surrounding the crib were sampled and analyzed. The soils from		

cells C and D containing levels of tritium above cleanup standards were taken to the Environmental Restoration Disposal Facility (ERDF). All other soils sampled were within cleanup standards.

Nine boreholes were drilled to a depth of approximately 15 feet. Samples were collected at intervals from the core holes. No radiological or hazardous constituents were found. The overburden samples found no contaminants.

Concrete rubble from the crib structure was taken to the 183-C Clearwell.

A "100 NPL Agreement/Change Control Form" documenting the close out of the 116-B-5 Crib was submitted on January 8, 1997 and signed by the Environmental Protection Agency Project Manager on January 14, 1997. The form also authorized the backfilling of the waste site.

Code:	116-B-6A	Classification:	Accepted
Names:	116-B-6A; 111-B Crib No. 1; 116-B-6-1	Reclassification	Interim Closed Out (5/17/2000)
Type:	Crib	Start Date:	1/1/1951
Status:	Inactive	End Date:	1/1/1968
Description:	This site has been remediated and closed out. An in-situ vitrification treatability test that was conducted in April, 1990.		
Location:	The site was located immediately north of the 111-B Building Site.		
Process Description:	The 116-B-6A Crib received radioactive liquid wastes from equipment decontamination performed in the 111-B Building, as well as from the decontamination of fuel element spacers.		
Waste Type:	Process Effluent		
Waste Description:	The unit received radioactive liquid wastes from equipment decontamination performed in the 111-B Building, as well as from the decontamination of fuel element spacers performed at the 111-B Building Decontamination Station.		
Closure Info:	Interim (5/17/2000): Excavation of the 116-B-6A/116-B-16 site involved removing the overburden materials, the contaminated structure, and underlying contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Materials shown to be contaminated were disposed of at the ERDF. On May 12, 1999, the excavation reached the design limit at El. 141.4 meters (464 ft). Cleanup verification sampling began on May 20, 1999, and was finished on June 18, 1999.		

The cleanup verification package for the 116-B-6A Crib and 116-B-16 Fuel Examination Tank, because of their close proximity to each other and similar contaminants of concern (COCs), were excavated as one remedial action site and are hereinafter referred to as the 116-B-6A/116-B-16 site.

At the completion of the remedial action, the total excavation was approximately 603.5 square meters (6,496 square feet or 0.15 acres) in area with a maximum depth of approximately 4.6 meters (15 feet). Approximately 5,072 metric tons (5,591 tons) of material from the site were disposed of at the Environmental Restoration Disposal Facility. The excavation will be backfilled in the near future (written June 6, 2000) with appropriate materials to the reference grade El. 146 meters (479 feet).

Results of the sampling, laboratory analyses, and data evaluations for the 116-B-6A/116-B-16 site indicate that all remedial action objectives and goals for direct exposure, protection of

ground water, and protection of the Columbia River have been met. However, this site close out includes a deed restriction against drilling or digging into the deep zone soils (below 4.6 m [15 ft] depth).

Code: 116-B-6B	Classification: Accepted
Names: 116-B-6B; 111-B Crib No. 2; 116-B-6-2	Reclassification: Interim Closed Out (2/24/2000)
Type: Crib	Start Date: 1/1/1950
Status: Inactive	End Date: 1/1/1953

Description: This site has been remediated and closed out. The site was commonly known as the 116-B-6B Crib, although it has also been known as 111-B Crib No. 2 and as 116-B-6-2.

Location: The site is located approximately 9.2 meters (30 feet) southeast of the former 111-B Building site.

Related Sites/ Structures: The site was associated with the 111-B Building.

Process Description: The unlined crib received radioactive wastes from equipment decontamination performed in the 111-B decontamination station, as well as liquid wastes from the decontamination of fuel element spacers.

Waste Type: Process Effluent

Waste Description: The site received radioactive wastes from equipment decontamination performed in the 111-B Building as well as liquid wastes from fuel element spacer decontamination.

Closure Info: Interim: The Cleanup Verification Package (CVP-99-00017) demonstrates that remedial action at the 116-B-6B site has achieved the Remedial Action Objectives (RAOs) and corresponding Remedial Action Goals (RAGs) as established in the Interim Action ROD (ROD) (EPA 1995) and the Remedial Design Report/Remedial Action Work Plan for the 100 Area (RDR/RAWP) (DOE-RL 1998).

Excavation of the 116-B-6B site began on March 11, 1999, by removing the materials and underlying contaminated soil. Based on field screening, materials identified as potentially clean were placed in stockpiles for potential use as backfill. On March 12, 1999, the excavation reached the design limits at El. 144.28 meters (473 feet) and cleanup verification sampling was initiated. At the completion of the remedial action, the excavation floor was approximately 25 square meters (270 square feet) at a depth of 3 meters (9.8 feet). A total of approximately 263 metric tons (259 tons) of material were disposed at the Environmental Restoration Disposal Facility (ERDF). The excavation was to be backfilled with clean fill materials to the reference grade of El. 147.3 meters (483 feet).

Code: 116-B-7	Classification: Accepted
Names: 116-B-7; 1904-B1; 1904-B-1 Outfall Structure	Reclassification: Interim Closed Out (7/25/2002)
Type: Outfall	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1972

Description: The site has been remediated and closed out. The outfall was excavated, sampled and backfilled to match the surrounding grade.

Location: The site was located at the top of the river bank, northwest of 116-B-11 (107-B Retention Basin), upstream of 132-B-6 (1904-B-2 Outfall).

Related Sites/ Structures: The site received effluent from the 100B process effluent lines (100-B-8), the 100B process sewer lines (100-B-14), and discharged effluent via the 100BC river effluent pipelines (100-B-15) and flumes (100-B-15:1).

Process Description: Outfalls were open, reinforced concrete structures that directed the water through either the river discharge pipelines or through spillways. The spillways were concrete flumes used when the river pipelines were blocked, damaged or undergoing maintenance.

Cooling water released from the reactor went to a retention basin located between the reactor building and the river. Water retention permitted thermal cooling and decay of short-lived radioisotopes prior to river discharge.

As reactor production increased, the hold-up period decreased. The basins also served to hold up flow of effluent with high radioactive isotope concentrations resulting from fuel element failure. This effluent was isolated and diverted, either by gravity or pumping, to an open pond area or crib. The pond or crib filtered the effluent through the ground. The cooling water discharged into the upper chamber of the concrete outfall structure, flowed through a bar grillwork and fell about 20 feet to the lower chamber of the outfall structure. The cooling water then overflowed from the lower chamber into the discharge pipe to the river.

Waste Type: Process Effluent

Waste Description: The outfall was originally used for both process sewer and reactor cooling water disposal until 1954 when it was used exclusively for process sewer disposal.

Closure Info: Interim (7/25/2002): Remedial action at the B/C Outfall sites began on June 4, 2001. Excavation of the three outfall sites (132-B-6, 116-B -7, and 132-C-2) involved removing the overburden materials and debris, the contaminated structure, and underlying contaminated soil. Overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Contaminated materials were disposed of at the ERDF. Cleanup verification sampling for the deep and shallow zones was done on January 14 and 15, 2002. The final verification samples were submitted to offsite laboratories for analysis using approved EPA analytical methods, as required per the SAP.

The concrete flumes extending from each of the outfall structures are a subsite of the 100-B-15 River Effluent Pipelines waste at and will be closed at later date. Portions of the flumes within the layback area were removed to the extent necessary to facilitate removal of the outfall structures. The effluent pipelines leading to the outfalls were left in place and grouted at the ends. They will be removed as part of the 100-B-8 and 100-C-6 Pipeline remediation.

The cleanup verification package (CVP-2002-00003) for the sites, also referred to as B/C Outfall, has demonstrated that remedial action has met the Remedial Action Objectives (RAOs) and corresponding Remedial Action Goals (RAGs) as established in the approved interim action Interim Action Record of Decision (ROD) (EPA 1999) and Remedial Design Report/Remedial Action Work Plan for the 100 Area (RDR/RAWP) (DOE/RL-96-17 Rev. 3).

Code: 116-B-9	Classification: Accepted
Names: 116-B-9; 104-B-2 French Drain	Reclassification: Interim Closed Out (2/24/2000)
Type: French Drain	Start Date: 1/1/1952
Status: Inactive	End Date: 1/1/1954

Description: The site has been remediated and Interim Closed Out. The site was a french drain that was related to the 104-B-2 Tritium Laboratory (118-B-9). The site included the feed pipeline that originated at the 104-B Building. The drain was not originally apparent from the surface.

-
- Ground Penetrating Radar (GPR) revealed an anomaly consistent with a french drain.
- Location:** The site is located approximately 30 meters (100 feet) east of the 104-B-2 Storage Building (104-B2 Tritium Laboratory), northwest of the 108-B Tritium Separation Facility (132-B-1), and just inside the reactor exclusion area fence.
- Related Sites/ Structures:** The site was associated with the 104-B-2 Building.
- Process Description:** The 104-B-2 building was associated with the P-10 project that involved tritium production. The 104-B-2 Building was used to store casks containing irradiated lithium targets for tritium production and product tritium. The facility contained an inspection laboratory and an annex on the east end that contained air sampling equipment.
- Waste Type:** Process Effluent
- Waste Description:** The site received waste water from the P-10 Storage Building drain. Since the P-10 project involved tritium production, tritium may be a potential contaminant. The drain is not currently posted as being contaminated. An evaluation to determine potential contaminants for the 100 Area SAP resulted in four COPCs: coal-60, cesium-137, europium-152, and strontium-90.
- Closure Info:** Interim (2/24/2000): Excavation of the 116-B-9 site began on March 10, 1999, by removing the overburden materials and underlying contaminated soil. Based on field screening, materials identified as potentially clean were placed in stockpiles for potential use as backfill. On March 11, 1999, the excavation had reached the design limit at El. 139 meters (455.8 feet). Cleanup verification sampling began on March 15, 1999, and was finished on April 23, 1999.

At the completion of the remedial action and removal of the engineered structure, the excavation area was approximately 51.5 square meters (554 square feet or 0.013 acres) at a depth of approximately 2.44 meters (8.0 feet). The excavation will be backfilled with clean fill materials to the reference grade of El. 141.1 meters (462.8 feet). Clean backfill may be taken from the clean overburden pile and other sources of clean material that have been surveyed in accordance with the SAP (DOE-RL 1998) and that are appropriate for use as backfill.

Site remediation was performed in accordance with an Interim Action Record of Decision (ROD) (EPA 1995). The ROD provides the U.S. Department of Energy, Richland Operations Office (RL) the authority and guidelines to conduct this remedial action at the site. The preferred remedy specified in the ROD is excavation and disposal of contaminated materials at the Environmental Restoration Disposal Facility (ERDF). The Remedial Action Objectives (RAOs) were established in the Interim Action ROD (EPA 1995) and are summarized in the Cleanup Verification Package (CVP) along with the corresponding Remedial Action Goals (RAGs). Methods to attain the RAOs are presented in the Remedial Design Report/Remedial Action Work Plan for the 100 Area (RDR/RAWP) (DOE-RL 1998) and are discussed in further detail in the 100 Area Remedial Action Sampling and Analysis Plan (SAP) (DOE-RL 1998). The CVP demonstrates that remedial action at the 116-B-9 site has achieved the RAOs and corresponding RAGs established in the approved interim action ROD (EPA 1995) and the RDR/RAWP (DOE-RL 1998). Materials that contain COCs at concentrations exceeding the RAGs have been excavated and disposed of at the ERDF. The remaining soils have been sampled, analyzed, and modeled to show that residual COC concentrations will support future land uses that can be represented (or bounded) by a rural-residential scenario. This scenario, described in the Cleanup Verification Package (CVP), assumes multiple exposure pathways (e.g., ingestion, inhalation, and direct exposure) for shallow zone soils. The verification package demonstrates that residual COC concentrations pose no threat to groundwater or the Columbia River. Thus, the 116-B-9 site is verified to be remediated in accordance with the ROD.

Code: 116-B-10	Classification: Accepted
Names: 116-B-10; Quench Tank; 108-B Dry Well	Reclassification: Interim Closed Out (2/24/2000)
Type: Injection/Reverse Well	Start Date: 1/1/1950
Status: Inactive	End Date: 1/1/1968

Description: The site was remediated in 1999 and closed out in February 2000. It is no longer marked or posted.

The site was a french drain with a metal manhole type cover and constructed of a 61-centimeter (24-inch) vitrified clay pipe on subsurface concrete slab. It was covered with a plywood cover and clean backfill material. A 3.8-centimeter (1.5-inch) drain line was added in the mid-50s that came from the experimental tube and other hardware decontamination facility. All piping leading into the drain was removed at the time of the 108-B demolition.

Location: The unit is located in the northwest corner of Room 15-C of 108-B Building.

Process Description: The quench tank was used to collect liquid decontamination wastes from the 108-B Tube Examination and Experimental Facility.

Waste Type: Process Effluent

Waste Description: This site received liquid decontamination wastes from the 108-B Tube Examination and Experimental Facility. During the tritium recovery programs, the site also received liquid decontamination wastes from the mask and small tool decontamination station located on the second floor and storm runoff from the fan room roof. The 108-B Building was involved with tritium recovery activities so tritium is a possible contaminant of concern.

Closure Info: Interim: The cleanup verification package (CVP-99-00010) has demonstrated that remedial action at the 116-B-10 site has met the Remedial Action Objectives (RAOs) and corresponding Remedial Action Goals (RAGs) as established in the approved interim action Interim Action Record of Decision (ROD) and Remedial Design Report/Remedial Action Work Plan for the 100 Area (RDR/RAWP).

Excavation of the site began on March 10, 1999. After completion of the initial excavation to design limits, several other contaminated areas (plumes) were discovered and also excavated. For this phase cleanup verification sampling began on May 20, 1999, and was finished on June 22, 1999.

At the completion of the remedial action, the excavation floor was approximately 153 square meters (1650 square feet) at a depth of 2.4 meters (8 feet), and approximately 692 metric tons (763 tons) of material were disposed at the Environmental Restoration and Disposal Facility (ERDF).

The remaining soils have been sampled, analyzed, and modeled to show that residual concentrations will support future land uses that can be represented (or bounded) by a rural-residential scenario. This scenario, described in Section 4.2 of the CVP, assumes multiple exposure pathways (e.g., ingestion, inhalation, direct exposure) for shallow zone soils.

Institutional control (IC) information has been revised as directed by the U. S. DOE letter, 05-AMRC-0078, 1/4/05, following a review of the Institutional Controls (ICs) in the WIDS. For some sites, including this one, both the CVP/reclassification forms and WIDS had indicated that IC restrictions were needed. However, these sites were remediated only with the more restrictive shallow zone criteria; deep zone criteria were not used. Therefore, no institutional controls to prevent uncontrolled drilling or excavation into the deep zone (i.e., below 4.6 m [15 feet]) are required.

Code: 116-B-11	Classification: Accepted
Names: 116-B-11; 116-B-11 Retention Basin; 107-B Retention Basin	Reclassification: Interim Closed Out (12/8/1999)
Type: Retention Basin	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1968

Description: The site has been remediated and closed out. It included the retention basin and the two effluent pipes running parallel to, and adjacent to, the north side of the basins. These pipes were removed as part of the plume removal during the retention basin remedial action.

Location: The 116-B-11 Retention Basin were located near the northern edge of the 100-B Area and is located north of 116-C-5 (107-C Retention Basin).

Related Sites/ Structures: The 116-B-11 Retention Basin is associated with the 105-B Reactor, the 116-B-1 Liquid Waste Disposal Trench, 116-B-7 (1904-B1 Outfall), and the 132-B-6 (1904-B2 Outfall).

Process Description: The 116-B-11 Retention Basin was constructed to hold cooling water effluent from the 105-B Reactor to allow for thermal cooling and radioactive decay prior to release to the Columbia River. This unit was a concrete-lined basin with wooden baffles. The basin was divided lengthwise into two halves designed to operate independently. The floor and walls consist of concrete slabs, their joints were originally closed with neoprene water seals. From the basin floor to approximately 3 meters (10 feet) above the floor, the walls sloped and were approximately 0.1 meter (4 inches) thick. The upper 3 meter (10-foot) sections of the walls were vertical and ranged in thickness from about 1.7 meters (5 feet 8 inches) at the bottom to 0.3 meter (1 foot) at the top. The unit was backfilled with soil to a depth of almost 1.2 meters (4 feet).

Waste Type: Water

Waste Description: This unit received cooling water effluent from the 105-B Reactor for radioactive decay and thermal cooling prior to release to the Columbia River. Total radionuclide inventories in the vicinity of the unit ranged from 5 to over 400 curies. Eighty percent of the total radionuclide inventory is contained within the soil adjacent to the unit. Approximately 10 curies have leached into the concrete floor and walls.

Closure Info: Interim (12/8/1999): Excavation of the 116-B-11 site began on November 26, 1997, to remove overburden materials and underlying contaminated soil. All overburden materials were determined to be contaminated and were disposed of at the ERDF. On October 28, 1998, removal of contaminated soil had reached the design limits at the base of the engineered structure (El. 127.5 m [418.3 ft]). Soils not meeting direct exposure RAGs based on field screening results were excavated, loaded into shipping containers, and disposed of at ERDF. Cleanup verification sampling was conducted on November 19 and 20, 1998, for the deep zone, and on December 8, 1998, for the shallow zone. Contaminated soil associated with the process effluent pipelines was partially removed; the rest remains for final remediation with pipelines and a separate cleanup verification package. The 100-BC process effluent pipelines are scheduled to be removed within the next few years. The 116-B-11 sidewall areas that are adjacent to future pipeline excavation areas were not sampled as part of the cleanup verification effort. These areas will be sampled and verified clean as part of the effluent pipeline remediation efforts. At the completion of the remedial action and removal of the engineered structure, the excavation area was approximately 14,000 square meters (150,696 ft²) at a depth of 5.0 m (16.4 ft), and approximately 165,178 metric tons (182,109 tons) of material from the site were disposed of at the ERDF. The excavation will be backfilled in the near future with clean fill materials to the reference grade of El. 132.5 m (434.7 ft). Backfill will be provided by use of clean source material from an area located near the 116-B-11 site that has been surveyed in accordance with the SAP (DOE-RL 1998a) and that is appropriate for use as backfill.

The site has been excavated and remediated. Results of the sampling, testing, and analyses for the 116-B-11 site cleanup indicate that all remedial action objectives and goals for direct exposure, protection of groundwater, and protection of surface waters (including the Columbia River) have been met.

The material removed from the site (approximately 165,178 metric tons [182,109 tons]) was disposed of in the Environmental Restoration Disposal Facility (ERDF). The excavation will be backfilled with clean material to the reference grade of elevation 132.5 meters (434.7 feet).

Code:	116-B-12	Classification:	Accepted
Names:	116-B-12; 117-B Crib; 117-B Seal Pit Crib	Reclassification	Interim Closed Out (2/24/2000)
Type:	Crib	Start Date:	1/1/1961
Status:	Inactive	End Date:	1/1/1968
Description:	This site has been remediated and closed out. The site was a crib with bottom measurements of 6.1 meters (20 feet) by 15.24 meters (50 feet).		
Location:	The site is located northeast of the 105-B Reactor Building. The site is adjacent to the 118-B-5 Burial Ground.		
Related Sites/ Structures:	The site was associated with the 117-B (132-B-4 Air Filtration Ventilation) Building, which has been demolished.		
Process Description:	The crib received drainage from the confinement system seal pits in the 132-B-4 Air Filtration Ventilation Building.		
Waste Type:	Process Effluent		
Waste Description:	The site received drainage from the confinement system in the 117-B Building seal pits. From process knowledge, the waste site contaminants of concern (COCs) identified in the SAP (DOE-RL 1998) include strontium-90, uranium-238, and hexavalent chromium (Cr+6).		
Closure Info:	Interim (2/24/2000): This site was remediated to meet the cleanup standards and closed out on February 24, 2000. Excavation of the 116-B-12 site began on February 17, 1999, by removing the overburden materials and underlying contaminated soil. Based on field screening, materials identified as potentially clean were placed in stockpiles for potential use as backfill. Materials that were found to be contaminated were disposed of at ERDF. On March 5, 1999, the excavation had reached the design limit at El. 139.93 meters (459.1 feet). Cleanup verification sampling began on March 15, 1999, and was finished on April 13, 1999.		

At the completion of the remedial action, the excavation floor area was approximately 520.8 square meters (5,605.8 square feet or 0.129 acres) at a depth of approximately 4.6 meters (15 feet), and approximately 8,696 metric tons (9,586 tons) of material from the site had been disposed of at ERDF. The excavation will be backfilled in the near future with clean fill materials to the reference grade of El. 144.5 meters (474 feet).

Site remediation was performed in accordance with an Interim Action Record of Decision (ROD) (EPA 1995). The ROD provides the U.S. Department of Energy, Richland Operations Office (RL) the authority and guidelines to conduct this remedial action at the site. The preferred remedy specified in the ROD is excavation and disposal of contaminated materials at the Environmental Restoration Disposal Facility (ERDF). The Remedial Action Objectives (RAOs) were established in the Interim Action ROD (EPA 1995) and are summarized in the Cleanup Verification Package (CVP) along with the corresponding Remedial Action Goals (RAGs). Methods to attain the RAOs are presented in the Remedial Design Report/Remedial

Action Work Plan for the 100 Area (RDR/RAWP) (DOE-RL 1998) and are discussed in further detail in the 100 Area Remedial Action Sampling and Analysis Plan (SAP) (DOE-RL 1998).

The Cleanup Verification Package (CVP) demonstrated that remedial action at the 116-B-12 site has achieved the RAOs and corresponding RAGs established in the approved interim action ROD (EPA 1995) and the RDR/RAWP (DOE-RL 1998). Materials that contain COCs at concentrations exceeding the RAGs have been excavated and disposed of at the ERDF. The remaining soils have been sampled, analyzed, and modeled to show that residual COC concentrations will support future land uses that can be represented (or bounded) by a rural-residential scenario. This scenario, described in the CVP, assumes multiple exposure pathways (e.g., ingestion, inhalation, and direct exposure) for shallow zone soils.

The acceptability of unrestricted direct exposure to deep zone soils has not been demonstrated; therefore, institutional controls to prevent uncontrolled drilling or excavation into the deep zone [i.e., below 4.6 meters (15 feet)] are required. The verification package demonstrates that residual COC concentrations pose no threat to groundwater or the Columbia River. Thus, the 116-B-12 site was verified to be remediated in accordance with the ROD.

Code:	116-B-13	Classification:	Accepted
Names:	116-B-13; 116-B-8; Basin Sludge Burial Pit; 107-B #2 Grave; 107-B South Sludge Trench	Reclassification	Interim Closed Out (7/22/1999)
Type:	Trench	Start Date:	1/1/1952
Status:	Inactive	End Date:	1/1/1952

Description: This site has been remediated, backfilled, and revegetated. It has been closed out.

Location: Historical documentation places the trench south of the southeast corner of the 116-B-11 Retention Basin.

Related Sites/Structures: The site was associated with the 116-B-11 (107-B) Retention Basin.

Process Description: The 116-B-13 Sludge Trench was dug to receive sludge from the bottom of the 107-B Retention Basin (116-B-11).

Waste Type: Sludge

Waste Description: The unit received low-level sludge waste from the bottom of 116-B-11 (107-B Retention Basin). During maintenance clean out operations, sludge was disposed of in the trench. There is no indication from available records that this site directly received any regular and/or high-volume effluent wastes.

Potential contaminants of concern included: americium-241, cobalt-60, cesium-137, europium-152, europium-154, europium-155, plutonium-238, plutonium-239/240, strontium-90, uranium-238, total chromium, hexavalent chromium (Cr+6), mercury, and lead.

Closure Info: Interim (7/22/1999): The cleanup verification package (CVP-1999-00002) has documented that the 116-B-13 site has achieved the remedial action objectives (RAOs) and corresponding remedial action goals (RAGs) as established in the Interim Action Record of Decision (ROD) (EPA 1995) and Remedial Design Report/Remedial Action Work Plan for the 100 Area (RDR/RAWP) (DOE/RL-96-17). 100 Area Remedial Action Sampling and Analysis Plan (SAP) (DOE/RL-96-22).

Excavation of the 116-B-13 site began on August 7, 1998, by removing the overburden materials and underlying contaminated soil. On November 6, 1998, the excavation had reached

the design limits at the base of the engineered structure, elevation 128.2 meters (421 feet) and cleanup verification sampling was initiated.

At the completion of the remedial action, the excavation footprint area was approximately 620 square meters (6,674 square feet) at a depth of 4.3 meters (14 feet), and approximately 6,340 metric tons (6,989 tons) of material from the site were disposed of at the ERDF. The excavation will be backfilled to the reference grade of elevation 132.5 meters (435 feet).

Code:	116-B-14	Classification:	Accepted
Names:	116-B-14; 116-B-2; 107-B #1 Grave; 107-B Liquid Waste Disposal Trench No. 1; 107-B North Sludge Trench	Reclassification	Interim Closed Out (7/22/1999)
Type:	Trench	Start Date:	1/1/1948
Status:	Inactive	End Date:	1/1/1948

Description: The site has been remediated and closed out. The 116-B-14 site appears as an open field covered with cobbles and sparse vegetation.

Location: The 116-B-14 site was located immediately north of 116-B-11 (107-B Retention Basin) and is outside the exclusion area fence that encloses the 116-B-11 and 116-C-5 (107-C Retention Basin). The center line for the trench is believed to be approximately 12 meters (40 feet) north of the exclusion area fenceline. The exact locations of the site boundaries are uncertain.

Related Sites/ Structures: The site was related to 116-B-11 (107-B) Retention Basin.

Waste Type: Sludge

Waste Description: The unit received low-level sludge waste from the bottom of 116-B-11 (107-B Retention Basin). During maintenance clean out operations, sludge was disposed of in the trench. There is no indication from available records that this site directly received any regular and/or high-volume effluent wastes. After its use, the waste site was covered with about 1.8 meters (6 feet) of soil.

Potential contaminants of concern included: americium-241, cobalt-60, cesium-137, europium-152, europium-154, europium-155, plutonium-238, plutonium-239/240, strontium-90, uranium-238, total chromium, hexavalent chromium (Cr+6), mercury, and lead.

Closure Info: Interim (7/22/1999): The cleanup verification package (CVP-1999-00003) has documented that the 116-B-14 site has achieved the remedial action objectives (RAOs) and corresponding remedial action goals (RAGs) as established in the Interim Action Record of Decision (ROD) (EPA 1995) and Remedial Design Report/Remedial Action Work Plan for the 100 Area (RDR/RAWP) (DOE/RL-96-17). 100 Area Remedial Action Sampling and Analysis Plan (SAP) (DOE/RL-96-22). Excavation began on May 27, 1998, and reached the design limits below the base of the engineered structure (elevation 126.5 meters [415 feet]) on September 17, 1998. At the completion of the remedial action, the excavation area floor was approximately 132 square meters (1,422 square feet) at a depth of 6 meters (19.7 feet), and approximately 3,795 metric tons (4,183 tons) of material from the site were disposed of at the ERDF. The excavation will be backfilled to the reference grade of (elevation 132.5 meters [435 feet]). Clean backfill was taken from the clean overburden pile and other sources of clean material (e.g., demolition rubble from the 108-F Building) that have been surveyed in accordance with the Sampling Analysis Plan (DOE/RL-96-22). Institutional control (IC) information has been revised as directed by the U. S. DOE letter, 05-AMRC-0078, 1/4/05, following a review of the Institutional Controls (ICs) in the WIDS. For some sites, including this one, WIDS had shown

IC restrictions but the sites were remediated to shallow zone criteria so that no ICs were required. The ICs for this site have been revised accordingly.

Code: 116-B-15 **Classification:** Accepted
Names: 116-B-15; 105-B Fuel Storage Basin Cleanout Percolation Pit; 105-B Fuel Storage Discharge Pond; 105-B Pond **Reclassification** Interim No Action (12/8/2003)
Type: Pond **Start Date:** 1/1/1984
Status: Inactive **End Date:** 1/1/1985

Description: This site has been evaluated and determined to meet remedial action objectives. The evaluation and sampling results support the reclassification to No Action. The unit was a large, open, excavated pit, rectangular in shape. The site was used from November 1984 to December 1985.

Location: The site was located east of the 105-B Reactor Building.

Related Sites/ Structures: The site received processed water from the 105-B Fuel Storage Basin.

Process Description: During the cleaning of the 105-B Fuel Storage Basin, the radiologically contaminated shielding water was processed through a system that utilized ion exchange columns. Before the water was discharged to this site, composite samples were taken to ensure that radionuclide concentrations were below release criteria.

Waste Type: Water

Waste Description: The unit received processed water from the 105-B Fuel Storage Basin. During the cleaning of this basin, the radiologically contaminated shielding water was processed through a system that utilized ion exchange columns. Before discharging the water to the unit, composite samples were taken to ensure that radionuclide concentrations were below release criteria in Table II of DOE Order 5480.1. No known chemical substances were present in the water; however, chemical analysis during that period was not a standard practice, and there is no evidence that it was performed.

Closure Info: Interim (12/8/2003): This site has been evaluated and determined to meet remedial action objectives. The "No Action" reclassification was supported by a review of the site history, an extensive site evaluation, confirmatory soil sampling and the site reclassification form (control number 2003-052) with a supporting documentation package. The current site soil conditions achieve the remedial action objectives and the corresponding remedial action goals established in the Remedial Design Report/Remedial Action Work Plan for the 100 Area and the Interim Action Record of Decision for the 100-BC-1, 100-BC-2, 100-DR-1, 100-DR-2, 100-FR-1, 100-FR-2, 100-HR-1, 100-HR-2, 100-KR-1, 100-KR-2, 100-IU-2, 100-IU-6, and 100-CW-3 Operable Units.

Residual soil concentrations support future land uses that can be represented (or bounded) by a rural-residential scenario and pose no threat to groundwater or the Columbia River.

Code: 116-B-16 **Classification:** Accepted
Names: 116-B-16; 111-B Fuel Examination Tank **Reclassification** Interim Closed Out (5/17/2000)
Type: Storage Tank **Start Date:**
Status: Inactive **End Date:** 1/1/1968

Description: This site has been remediated and closed out. The unit was a vegetation free, cobble-covered field located within a barricaded area at the former site of the 111-B Building. The floor, foundation, and tank were the only remaining portions of the building. The fuel examination tank was located along the west side of the barricaded area. A curved, capped ventilation pipe extended about 25 centimeters (10 inches) above ground just north and east of the tank location. The barricaded area was surrounded by light duty steel posts with light duty chain and has been posted with "Caution: Underground Radioactive Material" signs. The tank was constructed of concrete. It is believed that the tank was filled with either sand or concrete before the site was abandoned.

Location: The site was located below the northwest corner of the 111-B Metallurgical Examination Building floor, southeast of the 105-B Reactor Building, adjacent to 116-B-6A, and within the 105 B/C Exclusion Area.

Related Sites/ Structures: The site was associated with the 111-B Metallurgical Examination Building.

Process Description: The 116-B-16 Fuel Examination Tank, was a low-level liquid waste disposal site that was operational during the lifetime of the 111-B Metallurgical Examination Building. The tank received liquid wastes from the decontamination of fuel element spacers and other equipment as well as from other 111-B Building activities.

Waste Type: Process Effluent

Waste Description: The unit is believed to have received wastes similar to those identified in 116-B-6A (111-B Crib No. 1); i.e., radioactive waste from equipment decontamination, the 111-B Building, and liquid wastes from fuel element spacer decontamination.

Closure Info: Interim (5/17/2000): Excavation of the 116-B-6A/116-B-16 site involved removing the overburden materials, the contaminated structure, and underlying contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Materials shown to be contaminated were disposed of at the ERDF. On May 12, 1999, the excavation reached the design limit at El. 141.4 meters (464 ft). Cleanup verification sampling began on May 20, 1999, and was finished on June 18, 1999.

The cleanup verification package for the 116-B-6A Crib and 116-B-16 Fuel Examination Tank, because of their close proximity to each other and similar contaminants of concern (COCs), were excavated as one remedial action site and are hereinafter referred to as the 116-B-6A/116-B-16 site.

At the completion of the remedial action, the total excavation was approximately 603.5 square meters (6,496 square feet or 0.15 acres) in area with a maximum depth of approximately 4.6 meters (15 feet). Approximately 5,072 metric tons (5,591 tons) of material from the site were disposed of at the Environmental Restoration Disposal Facility. The excavation will be backfilled in the near future (written June 6, 2000) with appropriate materials to the reference grade El. 146 meters (479 feet).

Results of the sampling, laboratory analyses, and data evaluations for the 116-B-6A/116-B-16 site indicate that all remedial action objectives and goals for direct exposure, protection of ground water, and protection of the Columbia River have been met. However, this site close out includes a deed restriction against drilling or digging into the deep zone soils (below 4.6 m [15 ft] depth).

Code: 118-B-5

Classification: Accepted

Names: 118-B-5; Ball 3X Burial Ground

Reclassification: Interim Closed Out (5/24/2004)

Type: Burial Ground **Start Date:** 1/1/1953

Status: Inactive **End Date:** 1/1/1953

Description: The site has been remediated and Interim Closed Out. The 118-B-5 (Ball 3X) Burial Ground contained one trench, which was covered with 1.5 meters (5 feet) of soil after its use was discontinued. The site appeared as a vegetation free "L" shaped mound of cobbles, about 0.9 meters (3 feet) high, that was surrounded by permanent concrete markers and was outside the reactor exclusion area. The long south side of the burial ground was about 4.6 meters (15 feet) from a section of the reactor exclusion area fence that ran from north to south. Following remediation, authorization to remove the radiological postings was given in October 2012.

Location: The burial ground was located east of the 115-B Gas Recirculation Building. The west side was about 6.1 meters (20 feet) from the fence. The site was posted with signs reading "118-B-5 Ball 3X Burial Grounds".

Process Description: This burial ground received irradiated equipment and metallic wastes removed from the 105-B Reactor during the Ball 3X Project.

Waste Type: Equipment

Waste Description: The unit received 40.00 cubic meters (1410 cubic feet) of highly contaminated metallic wastes, including thimbles and step plugs that were removed from the 100-B Reactor during the performance of work for the Ball 3X project. The Ball 3X project replaced the liquid boron system for emergency reactor control with a system using solid boron-steel and carbon-steel balls. Potential contaminants include: C-14, Co-60, Ni-63.

Closure Info: Interim: The excavation was completed in December 2003. At the completion of the remedial action, the total excavation was approximately 753 square meters (8,101 square feet) in area for the shallow zone and approximately 3,419 square meters (37,783 square feet) in area for the staging pile area, with a burial ground depth of approximately 4.8 meters (15.7 feet). Approximately 5,046 metric tons (5,563 tons) of material from the site were disposed of at the Environmental Restoration Disposal Facility. Excavation during remediation of the site found only miscellaneous debris associated with the Ball 3X Project and lead solids.

Code: 118-B-9 **Classification:** Accepted

Names: 118-B-9; 104-B-1 Tritium Vault and 104-B-2 Tritium Laboratory; 104-B2 Storage Building **Reclassification:** Interim No Action (7/15/2004)

Type: Storage **Start Date:** 1/1/1950

Status: Inactive **End Date:** 1/1/1955

Description: The waste site has been evaluated and Reclassified to No Action. It is a gravel-covered field. The site originally consisted of two concrete masonry facilities identified as 104-B-1 Tritium Vault and 104-B-2 Tritium Laboratory. Both structures were demolished in 1996 and their associated foundations removed to 1 meter (3 feet) below grade. The excavated areas were then backfilled and graded to match the existing terrain.

Location: The site was located in the extreme northwest corner of the 105-B Exclusion Area. The 104-B-2 Product Storage Building was located immediately northwest of the 91.4-meter (300-foot) 108-B Stack. The 104-B-1 Tritium Vault was located due north of the 103-B Building and just outside the fence for 103-B. Both structures have been demolished.

Release Description: There have been no known unplanned releases from these facilities.

Related Sites/ Structures: The two facilities (104-B-1 and 104-B-2) were related to each other (both supported the P-10 Project). The 104-B-2 Facility was related to 108-B, Tritium Separations Facility. The 104-B-2 Facility housed the air sampling equipment for the 108-B Stack. These two facilities were connected through a vent pipe leading from the 108-B Stack to 104-B-2 Tritium Laboratory (annex). Photograph (83E17058CN) 100 Area, 104-B-2, View of the 104-B-2 Tritium Lab from the roof of 108-B, shows the vent line that went from the 104-B-2 Tritium Laboratory to the 108-B, Tritium Separations Facility. A french drain, identified as the 116-B-9 French Drain, was associated with this unit (104-B-2). This site is located at the east end of the 104-B-2 Tritium Laboratory (the end containing the annex that housed the air sampling equipment for the 108-B stack). Drawing H-1-2659 shows a french drain associated with this facility. BHI-00835 states that no evidence of the french drain was found when the team performed the walkthroughs (prior to demolition of 104-B-2) or when the vent line from the storage cells to the 108-F Stack (demolished in the 1980's) was opened and surveyed. No french drain was identified during demolition. Ground Penetrating Radar (GPR) surveys were performed in 1994 and 1996 identified an anomaly consistent with the shape of a french drain. In preparation for sampling the french drain, the site has been located and uncovered. Site 116-B-9 has photo images (#2 and #3) of the exposed french drain. Early WIDS documentation states that the french drain was not visible from the surface.

Process Description: The 104-B-1 Tritium Vault had a concrete foundation and concrete block walls. The 104-B-2 Tritium Laboratory was also a concrete structure with a small steel framed transite sided annex located on the east end. The Tritium Laboratory contained sixty-three (63) special cells recessed in the laboratory floor. These were used to store the vacuum casks which contained the irradiated target elements for the P-10 Project. The 104-B-2 Tritium Laboratory annex housed the air sampling equipment for the 108-B Stack. In the P-10 program, irradiation of lithium-aluminum fuel targets, took place in the 105-B, H and F Reactors. The irradiated fuel targets were put in special vacuum casks and taken to the 104-B-2 Tritium Laboratory where they were put into special storage wells. The vacuum casks were then moved to the 108-B Tritium Separations Facility and charged into a furnace with an inert atmosphere and a stainless steel furnace tube connected to a complex series of glass tubing and flasks fitted with palladium valves. As soon as the furnace was charged, the entire line was pumped down to an extremely high vacuum to remove impurities, and the furnace was out gassed to drive off absorbent gases. At that point, the actual extraction began. The furnace temperature was raised until all of the tritium gas had been driven from the irradiated targets, and the gas was drawn down the glass lines, through palladium valves, and collected in shipping flasks. These shipping flasks were stored in storage racks located on the north and south walls of the 104-B-1 Tritium Vault, prior to use. Prior to demolition, the laboratory had been deactivated, posted as radiologically contaminated, and used to store contaminated reactor refueling components from the 105-B and 105-C Reactors.

Waste Type: Demolition and Inert Waste

Waste Description: Following demolition activities, 0.7646 cubic meters (1 cubic yard) of miscellaneous metal from the two buildings was taken and staged with the 190-C recycle material.

Waste Type: Demolition and Inert Waste

Waste Description: Lead based paint was found on the roof trim, vents, and exterior doors. Following demolition activities, 0.7646 cubic meters (1 cubic yard) of lead base painted wood was disposed to an offsite vendor's container (where other 100-B/C small buildings hazardous waste was temporarily stored). This material was identified as number 200E-96-0015 and was packaged in a Laidlaw box and shipped offsite to Laidlaw Lone Mountain Facility on Manifest A6344 on 12/9/96.

Waste Type: Demolition and Inert Waste

Waste Description: The building was constructed of concrete block and the foundation was concrete. Following demolition activities, 110 cubic meters (144 cubic yards) of concrete rubble was disposed of in the 100-F Clearwell.

Waste Type: Demolition and Inert Waste

Waste Description: The facility (104-B-1) contained asbestos, consisting of caulking around exterior vents. Following demolition activities, 0.92 cubic meters (1.2 cubic yards) of non-friable cement asbestos board (CAB) were put into a dumpster and hauled away. The material was then shipped to Basin Disposal, Pasco for eventual disposal in the RABANCO landfill, Roosevelt, WA. Total asbestos material identified was non-friable Category I: asphalt roofing 55 square meters (592 square feet), non-friable Category II: joint caulking 1.21 square meters (13 square feet), non-friable Category II: transite wall board 63.92 square meters (688 square feet). The total category I was 55 square meters (592 square feet) and Category I was 65.13 square meters (701 square feet).

Waste Type: Equipment

Waste Description: The unit (104-B-2) contained trace amounts of radioactive waste. It was used to store containers of reactor refueling components from 105-B and 105-C Reactors. No liquid contaminants were involved. Bird droppings were also found in small quantities.

Following demolition activities, two 1.2 by 1.2 by 2.44-meter (4 by 4 by 8-foot) plywood burial boxes equivalent to 7.25 cubic meters (9.5 cubic yards) were taken to a burial ground. The burial boxes have numbers 100B-96-0002 and 100B-96-0017 and were shipped on 12/3/96 to burial ground 218-W-5, trench 29.

Closure Info: Interim (6/4/2004): Both structures (104-B-1 and 104-B-2) were demolished in 1996 and their associated foundations removed to 1 meter (3 feet) below grade. The excavated areas were then backfilled and graded to match the existing terrain. Confirmatory sampling was conducted at the 118-B-9 site in September 2003. One of the two judgmentally located sampling locations was in the center of the 104-B-1 Tritium Vault site and the second was below the exhaust vent pipe of 104-B-2 Tritium Laboratory site. The randomly located test pits were dug under the former location of the floor storage cells of the 104-B-2 Tritium Laboratory site. Soil samples were collected from a depth of 1.2 meters (4 ft) below ground surface.

During excavation of the foundations, radiological surveys were done to verify that no residual contamination existed in the footings or soil proximate to the foundations. No contamination was found.

The no action decision for the 118-B-9 site is supported based on reviews of site history, field observations, and characterization results. The maximum detected results from underlying soil samples collected at locations suspected of having the greatest potential for residual contamination levels were shown to meet the cleanup objectives for direct exposure, groundwater protection, and river protection.

Code: 118-B-10

Classification: Accepted

Names: 118-B-10; Ball 3X Storage Vault

Reclassification: Interim Closed Out (5/24/2004)

Type: Storage Tank

Start Date:

Status: Inactive

End Date:

Description: The site has been remediated and Interim Closed Out. Before remediation, the location of this burial ground was marked with a concrete pad and a metal medallion at the ground surface in a gravel field. Following remediation, authorization to remove the radiological postings was given in October 2012.

In November 2001 the site appeared as a vegetation-free area that had been covered with cobbles piled to 0.6 meters (2 feet) above grade. However, this location was wrong. As shown on Drawing H-1-19820 and confirmed by ground-penetrating radar (GPR), the mound of cobble is backfill over a process sewer that was constructed over the ventilation tunnel to 115-B. The pipeline had to be close to the surface because of the tunnel, so it was encased in concrete and covered with 18 inches of backfill.

- Location:** This site was south of the 105-B Reactor. See the photos for the top of this feature that is at ground level.
- Process Description:** The site was a metal tank used to store highly radioactive balls.
- Waste Type:** Equipment
- Waste Description:** The waste is a radioactive metal storage tank used to store radioactive boron balls from the ball 3X system.
- Closure Info:** Interim (5/24/2004): The site was remediated on December 1 and 2, 2003. Excavation included removing the overburden and the burial ground site materials. The average depth of the excavation was 10.5 feet. At the completion of remedial action, the excavation was approximately 137 square meters (1,475 square feet) in area with an average depth of approximately 3.21 meters (10.5 feet). Approximately 266 metric tons (293 tons) of material, including soil and burial ground debris, were removed from the site and disposed of at the Environmental Restoration Disposal Facility.

Code: 120-B-1	Classification: Accepted
Names: 120-B-1; 105-B Battery Acid Sump	Reclassification: Interim Closed Out (9/25/2006)
Type: Sump	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1969

Description: The site has been remediated and interim closed. The sump and underlying soils were removed on June 13, 2006. The site was backfilled with clean soil from the 100-B Area borrow pit.

Location: The site was located west of the 105-B Building, adjacent to the main switchgear room.

Related Sites/Structures: The sump was located on the northwest corner of 118-B-8 (105-B Reactor).

Process Description: The battery acid sump was a standard limestone acid neutralization pit. It was used from approximately 1944 to 1969 to neutralize the spent sulfuric acid from lead cell batteries of emergency power packs and the emergency lighting system. The neutralized battery acid waste (containing calcium sulfate, metal sulfates, and water) was periodically jetted out to the process sewer.

The sump was designed as a concrete box with hinged metal covers. During a site visit it was observed that concrete repairs had been made to each of the four corners. The repairs suggested that the integrity of the structure may have been compromised, creating the potential for leakage to the surrounding soils.

Waste Type: Chemicals

Waste Description: The site contained unknown amounts of sulfuric acid from spillage during use and servicing of an emergency power battery bank inside the 105-B Building. The residual liquid and sludge were analyzed for heavy metals in 1986 using the EP Toxicity Test and chromium was found.

Closure Info: Interim: When the sump was cleaned out in 1986, the residual limestone was removed and both the solution section (south end) and the solids (limestone) section (north end) were flushed with water and jetted out to the process sewer using the sump's water-operated eductor. Both sections of the concrete box were lined with acid-resistant brick including the partition between the two sections. The air and water supply to the sump (air sparger and water eductor) were shut off. The sump contained a 10-centimeter (4-inch) waste inlet pipe from the 105-B Building; it was located in the south wall of the sump about 50.8 centimeters (20 inches) below the metal access doors. The outlet pipe was located near the top of the west wall of the northern section of the sump. The associated inlet and outlet pipes were removed to the boundaries of the remediation footprint and grouted. After verification samples were collected, the excavation was backfilled.

In support of confirmatory sampling, the sump was opened in March 2003. Standing water was observed in both sections of the sump. Due to the presence of corrosive water in the sump and the results of confirmatory sampling, it was determined that remedial action was necessary. On June 1, 2006, the standing water present in the sump (approximately 6,400 liters [1,700 gal]) was treated with lime to adjust the pH and removed. On June 13, 2006, the remainder of the site (consisting of the sump structure) was excavated and removed along with a small volume of soil directly in contact with the sump. The site was excavated to a maximum depth of 3.0 meters (10 ft) below ground surface in order to preclude any potential impact to the integrity of the 105-B Building walls and nearby transformer pad. The pipelines were removed to the extent of the excavation boundaries and grouted prior to backfilling. The site was backfilled immediately following the verification sampling with clean backfill material from the 100-B Area borrow pit. Approximately 32 bank cubic meters (42 bank cubic yards) of material was excavated and disposed at the Environmental Restoration Disposal Facility.

The inlet and outlet pipelines associated with the sump were sampled but were not included as part of the closeout for the 120-B-1 waste site. The inlet and outlet pipelines were grouted and are included as a subsite within the 118-B-8, 105-B Reactor Building waste site.

Code: 126-B-2	Classification: Accepted
Names: 126-B-2; 183-B Clearwells	Reclassification: Interim No Action (3/20/2007)
Type: Dumping Area	Start Date:
Status: Inactive	End Date:
Description: The site has been evaluated and reclassified to No Action. The site consisted of two underground concrete reservoirs, or clearwells, separated in the center by the remains of a demolished pump room. A concrete piping structure was located above ground at the southeast corner of the clearwell site.	
Location: The site was located approximately 430 meters (1,410 feet) directly west of the 105-B Reactor Facility and southeast of the 182-B Retention Basin.	
Related Sites/ Structures: This unit was part of the 100-B Water Treatment Facility.	
Process Description: This site was part of the 100-B Water Treatment Facility. River water stored in the 182-B Retention Basin was transferred sequentially to the 183-B Head House for chemical additions, then to flocculation and sedimentation basins, through anthracite filters, and finally into the clearwells. The 183-B Filter Pump House then fed most of the stored potable water to the 185/190 B facilities, which provided final treatment and storage before use as cooling water for the 105-B Reactor. The pump room was constructed of concrete and was approximately 6.7 meters (22 feet) below grade. The remaining portion of the pump house contained debris from the demolition of the above-ground portion and was believed to include steel, concrete, and	

asbestos-containing siding (transite). The clearwells were each 1.9E+7 liter (5E+6 gallon) concrete rectangular boxes, with flat concrete roofs. The concrete roofs were surmounted by an above-grade water-resistant roof, which may have been made of asbestos-containing materials in asphalt-saturated board, covered by tarred felt. Water stored in the 183-B Clearwells would have contained additives from the flocculation and sedimentation steps that occurred at the 183-B facility. Chlorine, sulfuric acid, alum, ferric sulfate, Sepran O 1 (a coagulant), and lime were used in the treatment process. After the filtration step, the additives and any trace contamination from the additives would have been very dilute in the treated water. The Clearwells were upstream of sodium dichromate additions and of the 105-B Reactor. There was no evidence to suggest that the water stored in the clearwells ever contained sufficient quantities of radionuclide or no radionuclide hazardous chemicals to present a human health risk.

Waste Type: Demolition and Inert Waste

Waste Description: No waste was deposited at the clearwells in the past. However, this unit is scheduled for future use as a disposal site for demolition and inert solid waste after the 126-B-3 Coal Pit and demolition landfill is closed. The remaining portion of the pumphouse currently contains waste from the demolition of the above ground portion. These wastes were believed to include steel, concrete, and asbestos transite.

Closure Info: Interim: On September 15, 2005, a meeting among the Washington Closure Hanford (WCH) Field Remediation Closure Project, the U.S. Environmental Protection Agency (EPA), and the U.S. Department of Energy, Richland Operations Office (DOE-RL) was conducted to discuss a path forward for the 126-B-2 Clearwells and the 100-B-22, 100-B Water Treatment Facilities and Surrounding Soils. Background information presented to facilitate the discussion included a description of the water treatment facilities, the 126-B-2 Clearwells, and current information from the 100-B-14 excavations occurring in the area. The status of pipelines in the immediate area of the 126-B-2, 183-B Clearwells was also presented. The parties agreed all of the pipelines in the area were part 100-B-14, 100-B-28 or 100-B-22:1 and not part of the 126-B-2 Clearwells waste site.

It was further discussed that under the original and final configurations of the water treatment facilities, sodium dichromate was added to the process water downstream of the Clearwells in the 190-B facility. The 100-B-28 pipeline appeared to have transferred sodium dichromate solution from the 100-C Area to the 183-B Pumphouse. If sodium dichromate had been added to the process at the pumphouse, it would have been pumped to the 190-B facility for storage. Therefore, water in the Clearwells would not have been expected to contain hexavalent chromium or radionuclides, even at low concentrations. A baseline risk assessment for the river corridor portion of the Hanford Site began in 2004, which included a comprehensive ecological risk assessment. That baseline risk assessment will be used as part of the final closeout decision for this site.

Code: 126-B-3	Classification: Accepted
Names: 126-B-3; 184-B Coal Pit	Reclassification: Interim Closed Out (8/8/2006)
Type: Dumping Area	Start Date: 1/1/1943
Status: Inactive	End Date: 1/1/1968

Description: The site has been remediated and Interim Closed Out. The site consisted of a pit originally excavated to store coal for use in the 184-B powerhouse from 1943 through 1968. After coal storage was discontinued, the site was used as a demolition landfill.

Location: The site was located just west of the 184-B Power House (demolished) and northeast of the 182-B Pump House and Reservoir.

Related Sites/ Structures: The site was associated with the 184-B Power House and 100-B-27 Chromium-contaminated Soil.

Process Description: The site was used for coal storage from 1943 to 1968. Beginning in the early to mid 1970's, the site was used as a dumping area (burial ground) for demolished 100B/C Area facilities. The decommissioning of the 108-B building was completed in May 1985. All the above-grade portions of the building were demolished to a minimum of 3 meters (10 feet) below grade. The clean rubble and debris were disposed in the 184-B Coal Pit.

Waste Type: Demolition and Inert Waste

Waste Description: This unit contains waste from demolished 100-B Facilities. These include released portions of 108-B, 117-B, 117-C, 115-BC, and 184-B. This unit is likely to contain lead acid batteries. There are aluminum filter frames from the 117-B and 117-C Facilities on the surface on the south side. Steel staircases and ladders have been deposited on the surface on the northeast side of the site.

Closure Info: Interim: Initial remediation of the burn pit area was performed from September 4 to September 17, 2003; removing approximately 43,100 bank cubic meters (56,400 bank cubic yards) of material. The remediation consisted of the removal of suspect hazardous material and impacted soils within the disposal pit to depths of up to 7 meters (23 feet). Material removed included batteries, lead bricks, rubber gaskets, a compressor, metal scrap, concrete rubble, miscellaneous asbestos-containing material, ash, and contaminated soil.

After this remediation, an area of chromium-contaminated soil was identified in the northern portion of the western staging area. It was unrelated to waste staging or historical disposal activities at the site. This area was classified as a discovery site and designated as the 100-B-27 Chromium-Contaminated Soil waste site and was not considered within the closeout documentation of the 126-B-3 waste site.

Following the removal of an additional 4,640 bank cubic meters (6,060 bank cubic yards) of material, including a suspect drywell discovered within the staging pile footprint, the additional removal brought the total material removed to approximately 47,740 bank cubic meters (62,440 bank cubic yards) of soil and debris disposed at the ERDF.

Code: 128-B-2	Classification: Accepted
Names: 128-B-2; 100-B Burn Pit #2	Reclassification: Interim Closed Out (12/21/2005)
Type: Burn Pit	Start Date: 1/1/1948
Status: Inactive	End Date: 1/1/1968

Description: The site has been remediated and Interim Closed Out. The site covered a large area, covered in places with gravel and vegetation.

Location: The site was located east of the northeast corner of the 100-B Area, north of Route 1. The site was on the north side of an east-west dirt road that connects to Route 1.

Waste Type: Misc. Trash and Debris

Waste Description: The site received nonradioactive, combustible materials. Old paint cans and sandblast sand can still be seen at the site. Office waste, paint waste, chemicals, and solvent were burned at this site. It appears that clean fill material has been added to the site, indicating that the site may have also been used as a solid waste landfill.

Closure Info: Interim: The 128-B-2 Burn Pit also referred to as 100-B Burn Pit #2, was historically used for the disposal of combustible and noncombustible waste. The operational use of the Burn Pit was

not completely known it was used as a burn pit for office and paint wastes, chemicals, and solvents. Landfilled noncombustible material, including concrete and metallic debris, was also discovered during remediation of the site. The presence of garnet sand also suggests that sandblasting activities may have been performed at this site.

Remedial action of the 128-B-2 site was initiated in November 2004 and continued through April 2005, with 5,627 bank cubic meters (7,360 bank cubic yards) of material excavated and disposed at the Environmental Restoration Disposal Facility (ERDF). Scrap metal, wood debris, tar paper, copper wire, plastic pipe, colored sand (believed to be garnet or other sandblasting abrasive), concrete rubble, cyclone fencing, barbed wire, bricks, vitrified clay pipe tiles, fence posts, potentially contaminated soil, and other miscellaneous materials were removed. Excavated materials were sorted and segregated based on visual inspection and site location and staged onsite for transport to the ERDF. The site was excavated to a maximum depth of 3.5 meters (11.5 ft) at areas of buried foreign material. Surficial soils surrounding the primary excavations were also removed to a depth of 0.30 to 0.45 meters (1 to 1.5 ft) due to the presence of visible surficial foreign material.

Code:	128-B-3	Classification:	Accepted
Names:	128-B-3; 128-B-3 Burning Pit Site; 128-B-3 Coal Ash and Demolition Waste Site; 600-57; 100-B Dump Site	Reclassification	Interim Closed Out (11/17/2006)
Type:	Burn Pit	Start Date:	1/1/1944
Status:	Inactive	End Date:	1/1/1968

Description: The site has been remediated and reclassified to Interim Closed Out. Institutional Controls are to be maintained on the river embankment area to prevent activities that would mobilize residual contaminants to travel to groundwater or the river. Institutional controls will be maintained until such time that the results of a baseline risk assessment can be considered (for a final site remedy, closure).

The 128-B-3 Coal Ash and Demolition Waste Site was an area where dumping and burning of waste material had occurred. The site was visible in a 1968 aerial photo and appeared to have been divided into a construction debris dumping area to the south and a combustible waste burning area to the north. The site was separated into the two sections by an ash covered roadway. At the site's southern edge was an area of vegetation-free gravel, covered with what was described as a "white-colored spray".

Location: This site was northeast of the northeast corner of the 100-B perimeter road on the plateau above the river shoreline.

Waste Type: Misc. Trash and Debris

Waste Description: Coal ash, burning evidence, and demolition rubble can be seen at the surface of the site. A 1952 shop manual was found among the waste.

Closure Info: Interim: The waste site, located immediately adjacent to the Columbia River, was formerly used as a disposal site for the 100-B/C Area. Site history indicates that the site was used for the dumping and burning of miscellaneous wastes, including office waste, paints, solvents, coal ash, and demolition debris.

Remediation of the site was performed from November 2004 to May 2006, consisting of the removal of approximately 21,000 BCM (bank cubic meters) (27,500 BCY [bank cubic yards]) of material from four former disposal pits, the river embankment, and the upland surface to disposal at the Environmental Restoration Disposal Facility. Initial remedial efforts at the

upland area of the site were extended to include the river embankment following the results of geophysical investigation and focused sampling of visible debris at the embankment. Multiple chemical contaminants were detected above action levels in the in-process and waste characterization samples, including metals, hexavalent chromium, polycyclic aromatic hydrocarbons, total petroleum hydrocarbons (TPH), pesticides, and polychlorinated biphenyls.

The verification sample results indicated that the waste removal action achieved compliance with the RAOs and the Remaining Sites ROD, except at the river embankment area. Residual concentrations of metals, TPH, and aroclor-1254 slightly exceeded soil RAGS for protection of groundwater and the Columbia River at this location. However, further remediation activities to remove trace remaining contamination are likely to inflict greater environmental damage than leaving said contamination in place. The results for the entirety of the site show that residual contaminant concentrations do not exceed cleanup levels for direct exposure (i.e., ingestion of the soil). Statistical and judgmental sampling to verify the completeness of remediation was performed, and analytical results for upland areas were shown to meet the cleanup objectives for direct exposure, groundwater protection, and river protection. Analytical results for the remediated river embankment were shown to meet the cleanup objectives for direct exposure and to not significantly exceed soil RAGs for protection of groundwater and the Columbia River.

Accordingly, an interim closure reclassification is supported for the site, with imposition of institutional controls on the river embankment area to prevent activities that would mobilize residual contaminants to travel to groundwater or the river. Institutional controls will be maintained until such time that the results of a baseline risk assessment can be considered (for a final site remedy, closure).

The remainder of the site does not have a deep zone or residual contaminant concentrations that would require any institutional controls. The results of verification sampling show that residual contaminant concentrations do not preclude any future uses (as bounded by the rural-residential scenario) and allow for unrestricted use of shallow zone soils (i.e., surface to 4.6 in [15 ft] deep). The results also demonstrate that residual contaminant concentrations are sufficiently protective of groundwater and the Columbia River to preclude further remedial action.

Code:	132-B-1	Classification:	Accepted
Names:	132-B-1; 108-B Tritium Separation Facility	Reclassification	Interim No Action (3/1/2004)
Type:	Process Unit/Plant	Start Date:	1/1/1944
Status:	Inactive	End Date:	1/1/1975
Description:	The 108-B building has been demolished. The decommissioning was completed in May 1985. This site has been evaluated and determined to meet remedial action objectives. The evaluation and sampling results support the reclassification to No Action. The site is now a flat cobble field.		
Location:	The building was located north of 105-B.		
Related Sites/ Structures:	The 108-B Dry Well was left undisturbed. The drain line to the 108-B Crib was removed to a point south of the entrance road and capped.		
Process Description:	The intended use of this facility was to provide facilities for the mixing and addition of chemicals used in the treatment of the reactor cooling water. Shortly after the reactor began operation, it was determined that the chemical mixing and addition function could be better performed elsewhere in the cooling water supply system. The 108-B Building was then converted to a tritium recovery processing facility and was utilized as such until 1954. After the tritium processing facility was closed down, operational activity was limited to the first floor.		

The tube examination hot cell and laboratory rooms located there were utilized until the early 1970's.

Waste Type: Demolition and Inert Waste

Waste Description: The main radionuclide present at the site is tritium.

Closure Info: Interim: As part of decommissioning activities, hazardous material was removed and properly disposed. Extensive radiological surveys were performed to collect data to evaluate the potential radiological dose to a hypothetical, maximally exposed site resident if the site was released for unrestricted use after the demolition and burial in situ of the facility. The final release survey was completed in early 1985. The results indicated that the facility was ready for demolition. Demolition and site grading were completed in May 1985 using conventional heavy equipment. The rubble was buried under at least 1 meter (3 ft) of clean fill and the site was graded to blend with the natural terrain. All the above-grade portions of the building were demolished to a minimum of 3 meters (10 feet) below grade.

Any residual concentrations will support future land uses that can be represented (or bounded) by a rural-residential scenario, and that based on RESidual RADioactivity (RESRAD) modeling, residual concentrations at the site pose no threat to groundwater or the Columbia River.

Code: 132-B-3

Classification: Accepted

Names: 132-B-3; Ventilation Exhaust Stack Site; 108-B Tritium Pilot Facility; 108-B Ventilation Exhaust Stack Site

Reclassification: Interim No Action (12/8/2003)

Type: Burial Ground

Start Date:

Status: Inactive

End Date:

Description: The stack was demolished with explosives on September 9, 1983. This site has been evaluated and determined to meet remedial action objectives. The evaluation supports reclassification to No Action.

The site consisted of a trench, which was used to bury low-level contaminated rubble from the demolition of the 108-B Ventilation Exhaust Stack, also known as the 108-B Tritium Pilot Facility Ventilation Exhaust Stack. The trench was 9.1 meters (30 feet) wide, 5.5 meters (18 feet) deep, and 76 meters (250 feet) long. The stack foundation was found to be free of contamination. It was destroyed separately, buried in place and covered with clean fill material. Although it was on the opposite side of the road, it was considered to be part of this site.

Location: The burial trench was north of 105-B, west of 108-B Crib, across the road from the stack foundation site.

Waste Type: Demolition and Inert Waste

Waste Description: The 91-meter (300-foot) stack was demolished in 1983 and buried at this site. The stack was built of reinforced concrete and had a stainless steel liner. The total radionuclide inventory of the buried stack rubble is 21 millicuries.

Closure Info: Interim: Prior to demolition, surveys were conducted in the void beneath the liner and in the area inside the stack from the bottom of the liner to the 16 foot level. After removal of a layer of dust and dirt from an area around the liner floor drain, direct beta-gamma readings were ≤ 100 cpm/probe area inside the stack up to the 16 foot level. Alpha radiation was not detected with portable survey instruments. To determine the depth of penetration, concrete

cores were collected from the inner stack surface to a depth of 3/8 inches at the 32-ft and 64-ft levels and submitted for analysis. The stack was demolished with explosives on September 9, 1983, under the allowable residual contamination level (ARCL) method in conjunction with in-situ decommissioning for permanent disposal. A valve and a drain line had been removed by the time the stack was demolished. Some rubble from the stack fell across the perimeter road and was pushed into the 132-B-3 Trench with heavy earth moving equipment. Most of the rubble, however, fell directly into the trench. After the stack was destroyed and buried, the foundation was demolished in place. The entire area was covered with clean fill material. The uncontaminated stack foundation was demolished separately in place.

Code: 132-B-4	Classification: Accepted
Names: 132-B-4; 117-B Filter Building	Reclassification: Interim No Action (4/2/2003)
Type: Process Unit/Plant	Start Date: 1/1/1961
Status: Inactive	End Date: 1/1/1968

Description: The site has been evaluated and determined to require No Action. Historical data compiled for the Calculation Brief 0100B-CA-V0128 was of sufficient quality and quantity to support reclassification of the waste site to No Action. The 117-B building was demolished in two phases, beginning in 1985 and continuing through 1988. The ventilation exhaust filter building housed blowers and particulate filters used to treat the ventilation exhausted from the B Reactor Building. Included in this site were the 117-B Building, the intake ventilation duct from the 105-D Reactor Building, and the exhaust ventilation ducts to the 116-B Reactor Exhaust Stack.

Location: The site was located south of the 105-B Reactor, southwest of the 116-B Stack (132-B-2).

Related Sites/Structures: The site was associated with the 105-B Reactor (118-B-8), the 116-B Stack (132-B-2), the 119-B Sample Building, and the 117-B Seal Pit Crib (116-B-12).

Process Description: The building and below grade duct work were made of reinforced concrete, 0.3 to 0.6 meters (1 to 2 feet) thick; above grade ducts were constructed of 10 gauge black steel. The building was 16.76 meters (55 feet) long, 7.01 meters (23 feet) wide, and 11.0 meters (36 feet) high with 2.4 meters (8 feet) above grade. A soil berm was built up around the building from grade level to the top of the structure.

The building was divided into two large filter cells with a smaller operating area between them. The filter cells each held six filter frames (two wide and three deep). The filter frames were designed to hold twenty-eight filters that were 0.6 meters (2 feet) square by 0.3 meters (1 foot) thick. There were spaces between the frames to allow access for filter maintenance.

The operating area between the two cells was divided into two levels. The upper level, called the access gallery had ten doors that lead from it. Four doors opened into each of the filter cells and the two other doors provided access to the intake and exhaust ducts. The operating gallery was located below the access gallery. A sump was located at each end of the operating gallery to collect incidental drainage from above. A large open area extended the full length of the structure above the access gallery and the filter cells. It ranged in height between 2.5 and 2.4 meters (8.1 and 7.8 feet) due to the structure's sloping roof. The space provided access to the cement cover blocks that were positioned over each of the filter frames.

Before the filter building was used, unfiltered ventilation was exhausted directly from the reactor to the atmosphere. The reactor confinement system diverted the exhaust just before the stack and routed it to the filter building where it passed through a series of filters. The filtered exhaust was then routed back to the ventilation exhaust stack where it was discharged to the atmosphere. Sealwells within the filter building provided the ability to direct the exhaust into one or both of the filter cells.

Waste Type: Demolition and Inert Waste

Waste Description: The site contained radiologically contaminated debris. Total radionuclide inventory in this unit was estimated to be 92 nanocuries. The radionuclides comprising this inventory were tritium, carbon-14, cesium-137, strontium-90, and plutonium-239/240. Of these radionuclides, strontium-90 was the most restrictive in the allowable residual contamination level (ARCL) calculations. Cobalt-60, europium-152, europium-153, and europium-155 were not identified in any of the samples analyzed.

Closure Info: Interim (4/2/2003): Reclassification form 2003-10 and the attached Calculation Brief document the reclassification to No Action. The 117-B Filter Building and associated below-grade ductwork were demolished in two phases beginning in March 1985 and continuing through January 1988. Phase I included work necessary prior to demolition activities and included extensive radiological surveying and sampling, the removal of assorted equipment (e.g., HEPA filters) for disposal in the 200 West Area burial grounds, and decontamination and/or fixing contamination. As part of Phase I activities, a calculation methodology known as Allowable Residual Contamination Level (ARCL) was used to evaluate the potential radiological dose to a hypothetical, maximally exposed site resident if the site were released for unrestricted use after the demolition and burial in situ of the facility. The ARCL calculations were prepared in accordance with Allowable Residual Contamination Levels for Decommissioning Facilities in the 100 Areas of the Hanford Site (UNC 1983) and authorized by the U.S. Department of Energy, Richland Operations Office. The radionuclide inventories in the 117-B Filter Building and the inlet/outlet ducts were determined from radiological surveys, isotopic analyses, and from previously collected data that are discussed in UNC (1978).

Paint and concrete samples were collected and analyzed for Cobalt-60, Cesium-137, Europium 152 and 154, 155. Selected samples were analyzed for gross alpha, Tritium, Sr-90 and carbon-14.

Code: 132-B-5	Classification: Accepted
Names: 132-B-5; 115-B/C Gas Recirculation Facility	Reclassification: Interim No Action (1/5/2004)
Type: Process Unit/Plant	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1968

Description: The building was demolished in 1989. This waste site has been evaluated and determined to meet remedial action objectives. The evaluation supports reclassification to "No Action".

The waste site was a single-story reinforced concrete structure with a basement. It was 6.1 meters (20 feet) above and 3.4 meters (11 feet) below grade, and the width ranged from 22 meters (72 feet) to 30 meters (98 feet). It included vacuum and pressure seal pit and tunnels.

Location: The site was located south of 105-B.

Related Sites/ Structures: 100-B-11, 115-B/C Caisson Site

Waste Type: Demolition and Inert Waste

Waste Description: The resident radionuclides are tritium, carbon-14, cobalt-60, strontium-90, cesium-137, europium-152, and plutonium-239.

Closure Info: Interim: As part of Phase I Decommissioning activities, a calculation methodology known as "allowable residual contamination level" (ARCL) was used to evaluate the potential radiological dose to a hypothetical, maximally exposed site resident, if the site was released for unrestricted use after the demolition and burial in situ of the facility. The ARCL calculation

results indicated that the facility was ready for demolition activities. The Phase I demolition and grading were performed using conventional heavy equipment and completed in 1989. The above-grade structure was demolished to within a foot or two of the protective concrete cap (added during Phase I) on the process cell floors. The rubble and remaining clean equipment were removed for disposal in the area landfill. The at- and below-grade structure (floor slabs, foundation walls, footing pedestal, tunnel roof and walls, and piping) was demolished to at least 1 m (3.3 ft) below grade, and the resulting rubble was placed in the basement for in situ disposal. The area was backfilled to grade with clean fill material from a nearby borrow pit at the Hanford Site. The project decommissioned in situ the tunnel from the 115-B/C Building north for approximately 15.2 meters (50 ft). Tunnel demolition was restricted due to a suspected burial site of radioactive waste (100-B-11) located directly over the tunnel about 28.9 meters (75 ft) north of the 115-B/C Building. The 115-B/C Building below grade piping connecting the gas facility with the 105-B and 105-C reactors are internally contaminated. In general, the levels of radiation are relatively low, less than 1 mR/hr. Ten pipeline samples were taken from each of the "B" and "C" pipeline loops and were radiologically characterized.

Code:	132-B-6	Classification:	Accepted
Names:	132-B-6; 1904-B2; 1904-B-2 Outfall Structure Site; 116-B-8	Reclassification	Interim Closed Out (7/25/2002)
Type:	Outfall	Start Date:	1/1/1954
Status:	Inactive	End Date:	1/1/1968

Description: The site has been remediated and closed out. A dirt road leading to the site is crossed by a vegetation-free outfall structure wall that was left intact when the structure was backfilled to grade.

Location: The site is located north of the northeast corner of 116-B-11 (107-B Retention Basin) bank, directly north of the east end of 116-B-11 (107-B Retention Basin), and downstream of 116-B-7 (1904-B1 Outfall Structure), at the top of the riverbank.

Related Sites/ Structures: The site received effluent from the 100-B process effluent lines (100-B-8), the 100-B process sewer lines (100-B-14), and discharged effluent via the 100-BC river effluent pipelines (100-B-15) and flumes (100-B-15:1).

Waste Type: Process Effluent

Waste Description: The unit received and discharged reactor coolant effluent wastes to the river. The 1904-B2 Outfall received cooling water and process drainage from B Reactor and discharged through a 168-centimeter (66-inch) effluent line (100-B-15) to the middle of the Columbia River. A 1992 report states, "surface contamination is known to be present at the 132-B-6 spillway." Other documents reviewed provided no information about wastes or contamination.

Closure Info: Interim (7/25/2002): Remedial action at the B/C Outfall sites began on June 4, 2001. Excavation of the three outfall sites (132-B-6, 116-B -7, and 132-C-2) involved removing the overburden materials and debris, the contaminated structure, and underlying contaminated soil. Overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Contaminated materials were disposed of at the ERDF. Cleanup verification sampling for the deep and shallow zones was done on January 14 and 15, 2002. The final verification samples were submitted to offsite laboratories for analysis using approved EPA analytical methods, as required per the SAP.

The concrete flumes extending from each of the outfall structures are a subsite of the 100-B-15 River Effluent Pipelines waste at and will be closed at later date. Portions of the flumes within the layback area were removed to the extent necessary to facilitate removal of the outfall

structures. The effluent pipelines leading to the outfalls were left in place and grouted at the ends. They will be removed as part of the 100-B-8 and 100-C-6 Pipeline remediation.

The cleanup verification package (CVP-2002-00003) for the sites, also referred to as B/C Outfall, has demonstrated that remedial action has met the Remedial Action Objectives (RAOs) and corresponding Remedial Action Goals (RAGs) as established in the approved interim action Interim Action Record of Decision (ROD) (EPA 1999) and Remedial Design Report/Remedial Action Work Plan for the 100 Area (RDR/RAWP) (DOE/RL-96-17 Rev. 3).

Code:	1607-B1	Classification:	Accepted
Names:	1607-B1; 1607-B1 Sanitary Sewer System; 1607-B1 Septic Tank System; 124-B-1	Reclassification	Interim No Action (8/30/2007)
Type:	Septic Tank	Start Date:	1/1/1944
Status:	Inactive	End Date:	1/1/1960
Description:	<p>The waste site has been evaluated and reclassified to No Action. It included a septic tank, tile field, and associated pipelines from the 1701-B badge house, the 1720-B patrol building, the 1709-B Fire headquarters, and the change rooms. The septic tank, drain field and piping were removed in 2007.</p> <p>The site appeared as a vegetation and gravel covered area that is raised about 1.2 meters (4 feet) above the surrounding terrain. The septic tank was clearly marked on historical drawings in the location of the raised mound.</p>		
Location:	The site was located north of the 1720-B Building site near the entrance to the 100 B/C Area.		
Related Sites/Structures:	The site received effluent from the change rooms, 1701-B Badgehouse, 1720-B patrol building, 1709-B Fire Station Headquarters.		
Process Description:	The septic tank was constructed of reinforced concrete and had a 125 person capacity (132 liters [35 gallons] per capita) or approximately 16,504 Liters with an average detention period of 24 hours. The walls and floor were 25 centimeters (10 inches) thick. The tile field was constructed of 10-centimeter (4-inch) vitrified pipe, concrete pipe or drain tile with a minimum of 2.4 meters (8 linear feet) per capita. The laterals were open-jointed and spaced 2.4 meters (8 feet) apart.		
Waste Type:	Sanitary Sewage		
Waste Description:	According to documentation, the site received unknown amounts of sanitary sewage from the 1701-B Badgehouse (security checkpoint), the 1709-B Fire Station, the 1720-B Patrol Change Room, and offices.		
Closure Info:	Interim (8/30/2007): Excavation and confirmatory sampling at the site was conducted on May 21, 2007. Excavation began with a test pit at the suspected location of the septic tank. The septic tank was encountered less than 0.3 meters (1 foot) below ground surface (bgs). The top of the tank was found to have been entirely removed and the tank contained mostly soil backfill with small quantities of miscellaneous, nonhazardous debris (i.e., bollards, concrete debris, rebar, and VCP pieces). A single sample was collected from the bottom of the tank which was reached at 3.4 meters (11 feet) bgs. Excavation at the drain field revealed vitrified clay pipe containing no sediment. The rest of the samples consisted of soil underlying the tank, soil underlying pipelines, and the soil underlying the drain field.		

Code:	1607-B2	Classification:	Accepted
--------------	---------	------------------------	----------

Names: 1607-B2; 1607-B2 Sanitary Sewer System; 1607-B2 Septic Tank System; 124-B-2 **Reclassification** Interim Closed Out (3/13/2007)

Type: Septic Tank **Start Date:** 1/1/1944

Status: Inactive **End Date:**

Description: The site has been remediated and Interim Closed Out. The site included a septic tank and drain field. The site was divided into subsite 1 - Septic drain field and subsite 2- the septic tank and pipeline.

Location: The septic tank was located 390 meters (1280 feet) north of the 105-B Building. The drain field was located 240 meters (787.4 feet) northwest of the septic tank.

Related Sites/ Structures: The septic tank received sanitary sewage effluent from the 105-B Reactor Building, the 190-B Pumphouse and the 100-B Area office buildings. The office buildings have been removed.

Process Description: The septic tank system received effluent from the 100-B/C Area office buildings, 105-B Reactor Building, and the 190-B Pumphouse. The septic tank had a capacity of 59,620.24 liters (15,750 gallons). The system had the potential to support 450 persons assuming input of 132.5 liters (35 gallons) per capita per day and a one day retention period.

Waste Type: Sanitary Sewage

Waste Description: This unit received sanitary sewage from the 100 B/C Area office buildings, the 105-B Reactor Building, and the 190-B Pumphouse. All office buildings have been removed; however, the sewer lines to the respective buildings remained in place.

Closure Info: Interim: Remediation of the 100-B-14:2 and 1607-B2 waste sites was performed in stages from January 2005 through June 2006. All excavation was restricted within the shallow zone (less than 4.6 meters [15 feet] bgs), with an average depth of approximately 2.5 meters [8 feet] bgs, and a maximum depth of approximately 4 meters [13 feet] bgs at the septic tank. Excavation at the northern portion of the site continued to greater depth due to concurrent remediation of the underlying 100-B-14:1 process sewer. Excavated and disposed material quantities could not be explicitly separated for each site due to co-location and concurrent remediation of differing functional pipeline groups.

Based on the results of confirmatory sampling and previous investigations, it was decided that remedial action was necessary at areas 1, 2, 4, and 5 and that no further action was required at area 3. Area 1 was removed with the remediation of the 100-B-8:1 effluent lines. A decision was also made that remediation was necessary at the 1607-B2 waste site without further investigation based on the confirmatory sampling results for the influent feeder pipelines.

Due to its proximity to the reactor building, the southernmost portion of the 1607-B2 collection line, which formerly serviced the 105-B Reactor Building, was not removed. This portion of the pipeline will be addressed in the 118-B-8, 105-B Reactor waste site.

Site remediation consisted of the removal of the sewer piping, septic tank, and drain field where applicable, as well as adjacent, potentially-contaminated soils for disposal at the Environmental Restoration Disposal Facility (ERDF). Remedial actions were performed so as to not preclude any future uses (as bounded by the rural-residential scenario) and to allow unrestricted use of shallow zone soils [i.e., surface to 4.6 meters (15 feet) deep].

This Site has the Following SubSites:

Code: 1607-B2:1

Names: 1607-B2:1; 1607-B2 Drain Field

Code: 1607-B2:2
Names: 1607-B2:2; 1607-B2 Septic Tank and Pipeline

Code: 1607-B2:1 **Classification:** Accepted
Names: 1607-B2:1; 1607-B2 Drain Field **Reclassification** Interim Closed Out (3/13/2007)
Type: Septic Tank **Start Date:**
Status: Inactive **End Date:**

Description: A historical drawing states that the drain field was "to be located in field" near the septic tank, but does not show exact location. The drain field is constructed of 10-centimeter (4-inch) vitrified pipe, concrete pipe, or drain tile with a total of 1097.3 meters (3600 linear feet) of piping (2.4 meters [8 linear feet] per capita). The laterals are open-jointed and spaced 2.4 meter (8 feet) apart. The drain field was a vegetation-covered area surrounded with light-duty steel posts and light-duty barricade chain. During the March 2000 field visit, it was noted that some of the barricade has fallen. The site was identified with "Drain Field" signs.

Location: The drain field is located 240 meters (787 feet) northwest of the septic tank.

The SubSite is Part Of:

Code: 1607-B2
Names: 1607-B2; 1607-B2 Sanitary Sewer System; 1607-B2 Septic Tank System; 124-B-2

Code: 1607-B2:2 **Classification:** Accepted
Names: 1607-B2:2; 1607-B2 Septic Tank and Pipeline **Reclassification** Interim Closed Out (3/13/2007)
Type: Septic Tank **Start Date:**
Status: Inactive **End Date:**

Description: The septic tank had a capacity of 59,620.24 liters (15,750 gallons). The system could support 450 persons assuming input of 132.5 liters (35 gallons) per capita per day and a one day retention period. The septic tank was constructed of reinforced concrete. The walls and floor are 25 centimeters (10 inches) thick. During the March 2000 field visit, it was observed that the top of the septic tank was at grade level except on the north side, where it was above grade. In many areas the edges of the concrete were obscured by soil and vegetation. There were three manholes in the top of the tank covered by metal covers with handles. The septic tank was surrounded by six black and yellow striped posts, each about 0.9 meter (3 feet) high, and a light-duty barricade chain. The site was identified with a blue and white "Septic Tank" sign.

Location: The septic tank was located 390 meters (1280 feet) north of the 105-B Building.

The SubSite is Part Of:

Code: 1607-B2
Names: 1607-B2; 1607-B2 Sanitary Sewer System; 1607-B2 Septic Tank System; 124-B-2

Code: 1607-B5 **Classification:** Accepted
Names: 1607-B5; 1607-B5 Septic Tank System; 124-B-4; **Reclassification** None
1607-B4; 1607-B4 Sanitary Sewer System; 1607-B4 Septic Tank System
Type: Septic Tank **Start Date:** 1/1/1944

Status: Inactive**End Date:**

Description: The septic tank can be identified by a 20 centimeter (8 inch) capped steel vent pipe. The cap is stamped with the words septic tank. It is surrounded by a vegetation-free graveled parking lot. The pipe extends above grade about 0.76 meters (2.5 feet). The drain field runs southeast of the tank. The residue in the tank was sampled in January 2001. Elevated levels of cesium resulted in the tank being posted with Underground Radioactive Material signs. The tank was not backfilled. In 2007, analysis of additional samples of tank contents found no radiological constituents above background in either the liquid or sludge waste in the tank. For this reason, the site was down posted from URMA status. HEIS numbers for the 2007 sampling effort are: liquid--J14XJ3, J14XJ4, J14XJ5, and J14XJ6; sludge--J14XH9, J14XJ0, J14XJ1, and J14XJ2.

Location: The site is located southeast of the 181-B/C Pump House.

Related Sites/ Structures: The site is associated with the 181-B pump house building.

Process Description: The unit received sanitary sewage from the 181 B/C Pumphouse.

Waste Type: Sanitary Sewage

Waste Description: This unit received sanitary sewage from 181-B/C River Pumphouse. The flow rate to the unit was estimated at approximately 35 gal/day (130 L/day). In January 2001, the tank was sampled and analyzed for radionuclides. All radionuclides were undetected except for cesium-137, which was 38.3 picocuries per liter and gross beta, which was 1.8 picocuries per liter.

Code: 1607-B7**Classification:** Accepted**Names:** 1607-B7; 1607-B7 Sanitary Sewer System; 1607-B7 Septic Tank System; 124-C-1**Reclassification:** Interim Closed Out (7/27/2003)**Type:** Septic Tank**Start Date:** 1/1/1944**Status:** Inactive**End Date:** 1/1/1969

Description: The site has been remediated and interim closed out. The waste site consisted of a septic tank and drain field. The tank was constructed of reinforced concrete with a brick manhole access. The drain field was located due east of the tank.

Location: The unit was located northeast of the 183-B Filter Plant.

Related Sites/ Structures: The 183-B water treatment facility discharged effluent to the septic system via the 100-B-14 pipeline.

Process Description: The tank walls were 20 centimeters (8 inches) thick, the floor was 15 centimeters (6 inches) thick, and 2.5 meters (8 feet 3 inches) deep. It had a 12-person capacity (130 liters [35 gallons] per capita) with an average detention period of 24 hours. The drain field was constructed of 10-centimeter (4-inch) vitrified pipe, concrete pipe, or drain tile with a minimum of 2.4 meter (8 linear feet) per capita. The laterals were open jointed and spaced about 2.4 meters (8 feet) apart.

Waste Type: Sanitary Sewage

Waste Description: This unit received an unknown amount of sanitary sewage from 183-B Water Treatment Plant.

Closure Info: Interim (7/27/2003): Remedial action at the 1607-B7 site was conducted in March 2003. Excavation of the site involved removing the overburden materials, the septic system (tank and drain field), and underlying contaminated soil. Contaminated materials including the septic tank

and drain field piping were disposed of at the ERDF.

Remedial action objectives and goals for the 1607-B7 site were established by the U.S. Environmental Protection Agency (EPA) and the U.S. Department of Energy, Richland Operations Office, in concurrence with the Washington State Department of Ecology. These goals and objectives are documented in the Interim Action Record of Decision for the 100-BC-1, 100-BC-2, 100-DR-1, 100-DR-2, 100-FR-1, 100-FR-2, 100-HR-1, 100-HR-2, 100-KR-1, 100-KR-2, 100-IU-2, 100-IU-6, and 200-CW-3 Operable Units (ROD) (EPA 1999) and the Remedial Design Report/Remedial Action Work Plan for the 100 Area (DOE/RL-96-17).

The selected remedial action for the 1607-B7 site included (1) excavating the site to the extent required to meet specified soil cleanup levels, (2) disposing of contaminated excavation materials at the Environmental Restoration Disposal Facility at the 200 Areas of the Hanford Site, and (3) backfilling the site with clean soil to average adjacent grade elevation. Excavation was driven by remedial action objectives for direct exposure, protection of groundwater, and protection of the Columbia River.

Waste site COPCs for the 1607-B7 site were identified through process knowledge and analogous site data and are included in the Data Quality Objectives Summary Report for 100/300 Area Remaining Sites Analytical Sampling Effort (BHI 2003). From BHI (2003), the COPCs for this site consist of metals, pesticides, polychlorinated biphenyls (PCBs), and semivolatile organic compounds (SVOCs). Additional COPCs for this site included at the request of the regulatory agency are radionuclides (gross alpha, gross beta, and gamma emitters) and hexavalent chromium. Gross alpha and gross beta analyses were conducted for screening purposes.

At the completion of the remedial action, the total excavation was approximately 369 square meters (3,709 square feet) in area with a depth of 3.5 meters (11.5 feet). Approximately 198 metric tons (218 tons) of material from the site were disposed of at the Environmental Restoration Disposal Facility. The septic system inlet pipe was partially removed, see map and co-ordinates in the Cleanup Verification Package (CVP) for a more precise location. The remainder of the pipeline (100-B-14) from the 183-B water treatment facility will be dispositioned with the other pipelines in that site.

Results of the sampling, laboratory analyses, and data evaluations for the 1607-B7 site indicate that all remedial action objectives and goals for direct exposure, protection of groundwater, and protection of the Columbia River have been met.

Code: 116-C-1	Classification: Accepted
Names: 116-C-1; 107-C Liquid Waste Disposal Trench	Reclassification: Interim Closed Out (1/21/1999)
Type: Trench	Start Date: 1/1/1952
Status: Inactive	End Date: 1/1/1968
Description:	This site has been remediated and Interim Closed Out. It has been backfilled and revegetated. The remediation of the 116-C-1 trench began with the 100 B/C Demonstration Project in 1996. The final remediation project occurred in three stages; removing and disposing of the engineered structure, excavation and disposal of eight contaminated soil plumes and a characterization test pit. The final remediation project was completed in January 1998.
Location:	116-C-1 was located northeast of the 116-C-5 retention Basins approximately 253 meters (830 feet) from the 100-year flood level of the Columbia River.

Release Description: The 116-C-1 Trench received 700 million liters (184 million gallons) of contaminated cooling water from the 100-B/C Area Retention Basins. The site continued to receive contaminated cooling water until reactor operations ceased in 1968. An additional 40 billion liters (more than 10 billion gallons) of high-temperature reactor cooling water was discharged to the site during a 150 day infiltration test in 1967.

Related Sites/ Structures: The site was associated with 116-C-5 (107-C Retention Basins).

Process Description: The 116-C-1 site was constructed in 1952. The 16 meter long, 32 meter wide, 5 meter deep (548 ft long, 105 ft wide, 16.4 ft deep) trench was an unlined process effluent disposal trench that received 700 million liters (184 million gallons) of contaminated cooling water from the 100-B/C Area Retention Basins after ruptured fuel elements were detected in the reactors. The 116-C-1 site continued to receive contaminated cooling water until reactor operations ceased in 1968. An additional 40 billion liters (more than 10 billion gallons) of high-temperature reactor cooling water was discharged to the site during a 150 day infiltration test in 1967. This test likely influenced the distribution of contaminants beneath the site.

Influent water was transferred to the trench via two, 107 centimeters (42 inches) steel pipes leading from the 168 centimeters (66 inches) outfall pipelines that connected the 116-C-5 Retention Basins to the river. Two additional 61 centimeters (24 inches) pipes discharged influent water to the site. The contaminated water discharged to the site soils continued from 1952 to 1968. After operations ceased in 1968, the site was decommissioned as part of the Radiation Area Remedial Action (RARA) Program. The RARA activities at the 116-C-1 site included the placement of at least 1.5 meters (4.9 feet) of fill material (shielding) over the entire base of the trench to stabilize the exposed contaminated surfaces of the engineered structure.

Waste Type: Process Effluent

Waste Description: The site received effluent overflow from 116-C-5 (107-C Retention Basin) during reactor outages due to ruptured fuel elements. Beginning in 1955, this site also served 116-B-11 (107-B Retention Basin). The trench was used in 1967 for an infiltration test in which the total cooling water volume from B-Reactor was disposed in the trench. During the test, an estimated 4.4E+10 liters (1.17E+10 gallons) of effluent water were released. From process knowledge, the waste site contaminants of concern (COCs) identified are: Americium-241, Cobalt-60, Cesium-137, Europium-152, -154, -155, Nickel-63, Plutonium-238, -239/240, Strontium-90, Uranium-238, Total Chromium, Hexavalent chromium, Mercury, and Lead.

Closure Info: Interim (1/21/1999): The 116-C-1 site cleanup activities began with the 100-B/C Demonstration Project in 1966. The purpose of the 100-B/C Demonstration Project was to initiate a limited remedial action in the 100 areas to address uncertainties in remedial design and planning. An area measuring 38 by 38 meters (124 by 124 ft) in the southwest corner of the 116-C-1 trench was excavated in 1996.

The final remediation project occurred in three phases. The excavation and disposal of the engineered structure began on July 15, 1996 and was completed on November 15, 1996. The second phase addressed eight contaminated soil plumes. The plumes extended beyond the engineered structure and were identified during the subsequent field screening and sampling efforts. The excavation and disposal of the plume areas began on April 23, 1997 and were completed on October 28, 1997. After the soil plume excavation was completed, the third phase began. The third phase excavated a test pit down to groundwater to further characterize the subsurface. The test pit was centered at an area of elevated radiological activity near the 116-C-1 inlet pipes. The test pit effort began on December 15, 1997, and was completed on January 15, 1998. Soil samples were taken from each quadrant of the test pit and composited for each of the eight 1 meter (3 ft) test pit lifts. When the final test pit samples were obtained, 1 meter of clean native soil from identified borrow pits to the south was placed in the bottom of the pit. Backfill of the test pit occurred in approximately the same sequence as when the soils were

removed using the stockpiled materials.

At the completion of the remediation project, the excavation footprint was approximately 11,116 square meters with a depth of 5 meters (16.4 ft). Approximately 97,515 metric tons of material was disposed at ERDF. The influent pipelines will be addressed in a separate remediation project.

Code:	116-C-5	Classification:	Accepted
Names:	116-C-5; 116-C-5 Retention Basins; 107-C Retention Basins	Reclassification	Interim Closed Out (12/8/1999)
Type:	Retention Basin	Start Date:	1/1/1952
Status:	Inactive	End Date:	1/1/1969
Description:	The site has been remediated, backfilled, and revegetated.		
Location:	The 116-C-5 Retention Basins were located approximately 1,040 meters (3,400 feet) north of the 105-C Reactor and southeast of 116-B-11 (107-B Retention Basin).		
Related Sites/ Structures:	The 116-C-5 Retention Basins are associated with the 105-C Reactor, 105-B Reactor, 116-C-1 Liquid Waste Disposal Trench, 132-B-6 (1904-B2) Outfall, and the 132-C-2 (1904-C) Outfall.		
Process Description:	The 116-C-5 Retention Basins were constructed to hold cooling water effluent from the 105-C Reactor to allow for thermal cooling and radioactive decay prior to release to the Columbia River. When in operation, the retention basins were two circular, 3.8E+07 liter (1.0E+07 gallon), open-topped tanks. Each tank had a diameter of 100 meters (330 feet), a depth of 4.9 meters (16 feet), and had internal baffles to prevent water from channeling across the tanks into the discharge lines. The tanks were constructed of welded carbon steel and were set on a reinforced concrete foundation with a crushed rock subfloor.		
Waste Type:	Process Effluent		
Waste Description:	The basins received cooling water effluent from the 105-B and 105-C Reactors for radioactive decays and thermal cooling prior to release to the Columbia River. The total radionuclide inventories in the vicinity of the basins ranged from 5 to over 400 curies. Eighty percent of the total radionuclide inventory is contained within the soil adjacent to the basins. Approximately 10 curies leached into the basins' floors and walls.		
Closure Info:	Interim (12/8/1999): The site has been excavated, remediated, and closed out. The material removed from the site was disposed of in the Environmental Restoration Disposal Facility (ERDF). Excavation of the 116-C-5 site began on September 21, 1996, by removing the overburden materials and underlying contaminated soil. Based on field screening, overburden materials that were identified as potentially clean were placed in stockpiles for potential use as backfill. Overburden materials that were found to be contaminated were disposed of at ERDF. On March 21, 1998, the excavation had reached the design limit at El. 129 meters (423 ft). Soils not meeting direct exposure RAGs based on field screening results were excavated, loaded into shipping containers, and disposed of at ERDF. Cleanup verification sampling began on August 18, 1998, and was finished on January 20, 1999 (as stated, the adjacent pipeline areas will be addressed at a later date). Contaminated soil associated with the process effluent pipelines was partially removed; the rest remains for final remediation with pipelines and a separate cleanup verification package. The 100-BC process effluent pipelines are scheduled to be removed within the next few years. The 11 6-C-5 sidewall areas that are adjacent to future pipeline excavation areas were not sampled as part of this cleanup verification effort. These areas will be sampled and verified clean as part of the effluent pipeline remediation efforts.		

In accordance with the Interim Action Record of Decision and Remedial Design

Report/Remedial Action Work Plan, a rural residential exposure scenario was assumed in calculating cleanup levels. Results of the sampling, testing, and analyses for the 116-C-5 site cleanup indicate that all remedial action objectives and goals for direct exposure, protection of groundwater, and protection of surface waters (including the Columbia River) have been met.

At the completion of the remedial action, the excavation floor area was approximately 26,000 square meters (6.4 acres) at a depth of 4.6 meters (15 feet), and approximately 224,709 metric tons (246,695 tons) of material from the site, including pipelines within the excavation footprint, were disposed of at the ERDF. The excavation is to be backfilled to the reference grade of 133.5 meters (438 feet).

Code: 132-C-2	Classification: Accepted
Names: 132-C-2; 1904-C Outfall; 116-C-4	Reclassification: Interim Closed Out (7/25/2002)
Type: Outfall	Start Date:
Status: Inactive	End Date:

Description: The site has been remediated and closed out.

Location: The site was located just north of the 116-B-11 (107-B Retention Basin) and downstream of 116-B-7 (1904-B1 Outfall) and 132-B-6 (1904-B2 Outfall).

Related Sites/ Structures: The site received effluent from the 100-C process effluent lines (100-C-6) and discharged effluent via the 132-C-2 Outfall, 100B/C river effluent pipelines (100-B-15) and/or flumes (100-B-26).

Waste Type: Process Effluent

Waste Description:

Closure Info: Interim (7/25/2002): Remedial action at the B/C Outfall sites began on June 4, 2001. Excavation of the three outfall sites (132-B-6, 116-B -7, and 132-C-2) involved removing the overburden materials and debris, the contaminated structure, and underlying contaminated soil. Overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Contaminated materials were disposed of at the ERDF. Cleanup verification sampling for the deep and shallow zones was done on January 14 and 15, 2002. The final verification samples were submitted to offsite laboratories for analysis using approved EPA analytical methods, as required per the SAP.

The concrete flumes extending from each of the outfall structures are a subsite of the 100-B-15 River Effluent Pipelines waste at and will be closed at later date. Portions of the flumes within the layback area were removed to the extent necessary to facilitate removal of the outfall structures. The effluent pipelines leading to the outfalls were left in place and grouted at the ends. They will be removed as part of the 100-B-8 and 100-C-6 Pipeline remediation.

The cleanup verification package (CVP-2002-00003) for the sites, also referred to as B/C Outfall, has demonstrated that remedial action has met the Remedial Action Objectives (RAOs) and corresponding Remedial Action Goals (RAGs) as established in the approved interim action Interim Action Record of Decision (ROD) (EPA 1999) and Remedial Design Report/Remedial Action Work Plan for the 100 Area (RDR/RAWP) (DOE/RL-96-17 Rev. 3).

Code: 600-230	Classification: Accepted
Names: 600-230; RCRA General Inspection 200WFY97	Reclassification: Interim No Action (5/25/2006)

Item #4 Historic Disposal Site

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site has been evaluated and reclassified to "No Action". The site consisted of an area of household debris typical of items found at pre-Manhattan Project farm sites.

Location: The site was located on the right bank of the Columbia River (facing downstream) between 100B Area and 100K Area, approximately 1/3 mile west of the old Hanford Irrigation Project Pumphouse and approximately 40 yards from the river.

Process Description: The area appeared to have been used as a dumping area for domestic waste before the Manhattan Project.

Waste Type: Batteries

Waste Description: Miscellaneous household garbage including, one C cell battery was found.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: Empty food cans, paint cans, buckets and glass.

Closure Info: Interim (5/25/2006): The waste site was evaluated and reclassified to No Action with correspondences attached to the signed WIDS Reclassification form 2006-041.

100-BC-2

Code: 100-B-1 **Classification:** Accepted
Names: 100-B-1; Laydown Yard; Surface Chemical and Solid Waste Dumping Area **Reclassification:** Interim Closed Out (4/26/2006)
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The site has been remediated and Interim Closed Out. It was an old laydown yard and adjacent dumping area. Miscellaneous debris was scattered in the southern area of the site. There were many areas of stressed vegetation and discolored soil.

In February 2003, the northwest portion was being used as a soil staging area. It was removed from the 100-B-1 site description, reducing the size of the site.

Location: The site was located east of the 105-C Building. The export water line ran through the center of the area. Some debris and stressed vegetation was identified north of the export water line and some debris and stressed vegetation was found south of the export water line.

Process Description: The 100-B Technical Baseline Report describes two areas located east of 105-C. One area is described as "Undocumented Solid Waste Site: Laydown Yard". The laydown yard contains miscellaneous items such as wood, power poles, light fixtures, wire, broken glass, broken transite and plexiglass filter columns. The other is described as Undocumented Solid and Liquid Waste Site: Surface Chemical Dumping Area". The chemical dump area, located 100 meters (300 feet) northeast of the laydown yard, contains areas of distressed vegetation and oil contaminated soil. Both areas were combined into WIDS site code 100-B-1.

Waste Type: Misc. Trash and Debris

Waste Description: The solid waste at the site consists of miscellaneous debris such as wooden power poles, lighting fixtures, coils of wire, broken glass, small amounts of broken transite, a bottle of hand cream, and four 20-centimeter (8-inch) Plexiglas filter columns.

Waste Type: Oil

Waste Description: Petroleum contaminated soil was also noted and verified with field screening tests. Areas of soil appear to be discolored by oil. A field screening test on the soil with ENSYS Petro and Polyaromatic Hydrocarbons (PAH) kits indicated petroleum contamination. The Petro results were greater than 10 parts per million and less 100 parts per million total petroleum hydrocarbons (TPH). The PAH results were greater than 1 part per million and less than 10 parts per million polyaromatic hydrocarbons.

Closure Info: Interim (4/26/2006): Remedial action began on June 9, 2003, with three additional excavations throughout 2005 due to elevated total petroleum hydrocarbon concentrations. Five Sample Areas were identified. Sample collection was done in Test Pits.

Remedial actions were performed so as to not preclude any future uses (as bounded by the rural-residential scenario) and to allow unrestricted use of shallow zone soils (i.e., surface to 4.6 meters [15 feet] deep). Because of the presence of TPH, pesticides, SVOCs, and PCBs at concentrations exceeding RAGs and visual observations of debris during confirmatory sampling. From 2003 through 2005, approximately 51,099 metric tons (56,327 US tons) of material was removed for disposal at ERDF. The site was excavated to a maximum depth of 3.7 to 4 meters (12 to 13 feet) below ground surface.

Code: 100-B-23 **Classification:** Accepted

Names: 100-B-23; 100-B/C Surface Debris **Reclassification** Interim Closed Out (6/16/2008)
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The site consisted of various sizes and forms of scattered surface debris in the 100-B/C Area which has been identified as CERCLA waste or potentially dangerous under Washington Administrative Code (WAC) regulations.

Location: The surface debris included in this site was scattered over the 100 B/C Area. A GPS was used to record the location of field observations.

Process Description: A field walk-down of the 100-B/C Area was conducted during July and August 2004 as a final closure screening activity. Scattered surface debris that was created during the construction, operating, decontamination and decommissioning (D), and remedial action (RA) activities at the 100-B/C Area was identified as potentially dangerous/CERCLA waste. The locations of the debris were recorded using Global Positioning System (GPS) technology and a description was entered into a field logbook. For some features, additional information was obtained using digital photography. Subsequent evaluation of the collected data yielded 4 generic groupings of wastes: asbestos-containing material, lead, oil and oil filters, and treated wood.

The field walk-down of the 100-B/C Area did not include the 30-meter by 30-meter grids where cleanup activities were being conducted or within posted areas. The field walk-down was limited to observations; no sampling was conducted. Observations of potential physical hazards, cultural artifacts, and nonhazardous, nondangerous solid waste were GPSd and noted in a logbook. A spreadsheet was created listing the coordinates of the debris that had been observed. The spreadsheet is in the WIDS library file.

Waste Type: Oil

Waste Description: Oil from automobile oil filters on soil surface; scattered oil filters.

Waste Type: Misc. Trash and Debris

Waste Description: The treated wood locations are isolated; that is, not within existing or abandoned railroad beds or utility laydown yards. These locations contain one or more horizontal railroad ties, posts, or poles imbedded or resting on the surface, more or less weathered. The locations do not include posts, poles, plywood, or other wood materials that does not appear to have been a treated wood.

Waste Type: Misc. Trash and Debris

Waste Description: Pieces of lead sheet.

Waste Type: Asbestos (non-friable)

Waste Description: Contaminants of potential concern (COPCs) include asbestos, lead, oil, and creosote. Debris is scattered across the 100-B/C area.

Closure Info: Interim (6/16/2008): A meeting between the U.S. Environmental Protection Agency (EPA), the U.S. Department of Energy, Richland Operations Office (DOE-RL), and the Environmental Restoration Contractor (ERC) Team was held on May 5, 2005, to determine a path forward for the 100-B-23 waste site. EPA and DOE-RL agreed that a general cleanup action would occur at the 100-B-23 waste site to remove the friable ACM, oil filters, oil-stained soil, lead debris, and treated wood debris.

Remediation of the 100-B-23 waste site was performed in accordance with the site-specific remediation approach as outlined in the work instruction and the site specific soil-sampling

documents. The design consisted of the removal of suspect hazardous material identified at the surface of the site (friable ACM, lead sheeting and batteries, oil filters, and treated wood) along with any associated stained soils. Verification sampling of underlying stained soils was performed concurrently with the cleanup action to support waste site closure. Two locations contained friable asbestos. All nonfriable ACM material and most of the inert wood material was left in-place at the site. The nonfriable ACM and inert wood material did not present a potential release to the environment, therefore, no cleanup action was required for these items.

Remediation and verification sampling of the site was performed between June 2007 and February 2008. Evaluation of the collected information for the surface debris features yielded four generic waste groupings: asbestos-containing material (ACM), lead debris, oil and oil filters, and treated wood. The various forms of scattered surface debris are believed to be created during the construction, operating, decontamination and decommissioning, at the 100-B/C Area.

No geophysical survey was performed because the position and character of debris was well established by visual reconnaissance.

A total of approximately 680 metric tons (750 US tons) of debris and stained soils were removed from the site and disposed at the Environmental Restoration Disposal Facility.

The results of verification sampling show that residual contaminant concentrations do not preclude any future uses (as bounded by the rural-residential scenario) and allow for unrestricted use of shallow-zone soils (i.e., surface to 4.6 meters [15 feet] deep). The verification sampling results supported a reclassification to Interim Closed Out. The results also demonstrated that residual contaminant concentrations were protective of groundwater and the Columbia River. Site contamination did not extend into the deep-zone soils; therefore, institutional controls to prevent uncontrolled drilling or excavation into the deep zone were not required.

Code:	100-B-31	Classification:	Accepted
Names:	100-B-31; Garnet Sand Located at 183-C Clearwell Pads	Reclassification	Interim Closed Out (1/13/2010)
Type:	Unplanned Release	Start Date:	
Status:	Inactive	End Date:	
Description:	The site has been remediated and Interim Closed Out. It consisted of scattered garnet sands on the 183-C Clearwell concrete pads and the surrounding soils.		
Location:	The site was located south of Bells Street and east of Tank Avenue in south central 100-B/C Area. The center of the site was located at Washington State Plane coordinates E565072.91/N144009.16.		
Process Description:	The exact process that caused the garnet sand to be located at this site is unknown. However, garnet sand (grit) was used in sandblasting operations throughout the Hanford site.		
Waste Type:	Chemicals		
Waste Description:	The waste is garnet sand mixed with the material that was sandblasted. Confirmatory sampling is needed to determine if there are any contaminants of potential concern.		
Closure Info:	Interim: The 100-B-31 waste site was an area of scattered garnet sand on the 183-C Clearwell concrete pads and surrounding soils. The garnet sand was suspected to be the result of sandblasting operations at the former clearwell tanks. The site has been remediated with		

shallow scraping and does not require backfill. The site measured 134 meters (440 ft) in length by 122 meters (400 ft) in width, for a total area of 16,400 square meters (176,000 sq ft).

Remedial action at the site was performed from May to July 2009. Remediation included scraping along the edge of the clearwell pads and removal of garnet sand, asphalt, and contaminated soil from the area. In total, approximately 2,330 bank cubic meters (3,050 bank cubic yards) of contaminated material was removed from the site. This material, composed of garnet sand, soil, and asphalt, was stockpiled on the northeastern and southeastern tank pads before being disposed at the Environmental Restoration Disposal Facility.

Code:	118-B-1	Classification:	Accepted
Names:	118-B-1; Ext. to BG No. 1; Operations Solid Waste Burial Ground; 105-B Burial Ground; 105-B Solid Waste Burial Ground; 108-B Burial Ground	Reclassification	Interim Closed Out (1/9/2008)
Type:	Burial Ground	Start Date:	1/1/1944
Status:	Inactive	End Date:	1/1/1973

Description: The waste site has been remediated and Interim Closed Out. It had been a solid waste disposal site containing more than twenty trenches. It has been backfilled and the surface is free of vegetation.

Location: The site was located 914 meters (3,000 feet) due west of the 105-C Reactor Building.

Process Description: This waste site operated from 1944 to 1973, receiving general radioactive and non-radioactive wastes from the 105-B and 105-N Reactors, construction wastes from modification of the 105-B Reactor Building, and process wastes from the P-10 Tritium Separation Project. The original burial ground contained six to eight trenches that ran in a east-west direction, receiving general reactor waste from the B Reactor which included: aluminum tubes, lead bricks, thermocouples, vertical and horizontal aluminum thimbles, stainless-steel gun barrels and expendables (e.g., plastic, wood, and cardboard). It was expanded over time to include more than 20 trenches.

Spline silos were also constructed at the burial ground, which were vertical metal culverts, 3 to 3.7 meters (10 to 12 feet) in diameter, built presumably to receive reactor poison splines and other metal wastes. One extension to the south side of the original burial ground was known as the 108-B Solid Waste Burial Ground, measuring 46 meters (150 feet) long by 73 meters (240 feet) wide by 6.1 meters (20 feet) deep. The burial ground contained three trenches oriented from east to west. This burial ground received contaminated tritium pots, irradiated process tubing (in 1952), contaminated fuel spacers (perfs), solid tritium wastes, and high-level liquid tritium wastes that were sealed in a 7.6-centimeter (3-inch)-diameter iron pipe. The second extension to the burial ground was added in 1956 and was referred to as the "extension to Burial Ground No. 1." It measured 61 meters (200 feet) long by 15 meters (50 feet) wide and ran in a north-south direction, adjacent to and at the midpoint of the original burial ground's west side. This extension contained two trenches that ran in a north-south direction and was used for the burial of contaminated yokes from B Reactor. The third extension was added to the north side of the original burial ground in the mid 1960s and measured 106 meters (350 feet) long by 91 meters (300 feet) wide, with trenches running in an east-west direction. Historical data on the contents of these trenches are not as detailed as with earlier extensions but are presumed to include "general" reactor and construction waste from modifications to B Reactor.

During remediation, it was discovered that 2 of the 23 trenches had not been used for waste disposal.

Waste materials from the Tritium Separation (P-10) Project were also buried here, including lithium-aluminum alloy, lead, mercury, aluminum cladding, and palladium.

Waste Type: Equipment

Waste Description: The burial ground received general reactor waste from the 105B and 105N reactors, including the following: aluminum tubes, irradiated facilities, thermocouples, vertical and horizontal aluminum thimbles, stainless steel gun barrels, wastes from operation of the P-10 tritium separation project, and expendables such as plastic, wood, and cardboard. Waste materials were typically buried 6.1 meters (20 feet) below grade and were covered with a minimum of 1.2 meters (4 feet) of clean soil; actual soil cover ranged from 0.6 meters (2 feet) to greater than 4.3 meters (14 feet). Potential Contaminants include Ag-108m, C-14, Co-60, Cs-137, Eu-152, Eu-154, Eu-155, H-3, Ni-59, Ni-63, Sr-90, cadmium, Cr+6, lead, mercury, boron, graphite, PCBs, SVOAs, TPH, and VOAs. Permanent concrete markers surrounded the site, and "Caution: Underground Radioactive Material" signs were posted. Blue and green ground penetrating radar survey stakes had been placed around the perimeter and in lines crossing the site. A 12 by 4.6-meter (40 by 15-foot), vegetation-free, cobble-covered portion about 46 meters (50 yards) north of the southeast corner is bounded by steel posts and light-duty barricade chain; warning signs are posted on that section.

Closure Info: Interim: In late 1994 and early 1995, this burial ground was used for a treatability investigation. A total of 1,530 cubic meters (2,000 cubic yards) of waste was excavated, sorted, characterized and reburied. The overall lateral footprint of the burial ground prior to remediation was approximately 225 meters by 90 meters (740 feet by 300 feet).

The Remedial Action began on February 2, 2004 with overburden removal. Approximately 20,000 bank cubic meters (BCM) [26,200 bank cubic yards (BCY)] of overburden material was removed before beginning excavation. During remediation, it was discovered that 2 of the 23 trenches had not been used for waste disposal. The burial ground also consisted of several spline silos constructed from 3 to 3.7 meter (10 to 12 foot) diameter metal culvert piping and 3 spacer pits shored with railroad ties. Sorting of the burial ground contents began on March 16, 2004. Approximately 1,500 anomalous items were discovered during excavation and sorting operations. Approximately 1,000 of the items were tubes used for packaging and disposal of tritium gas. Approximately 350 were barium desiccant tubes, 81 were tubes used for packaging and disposal of mercury, approximately 50 were glass/plastic bottles, and approximately 70 were unique anomalous containers or solids.

Suspect spent nuclear fuel (SNF) was discovered on September 15, 2004. Remedial activities suspended until the Authorization Basis could be assessed and revised to address spent nuclear fuel (SNF). The suspect SNF was staged in two bunkers within the 118-B-1 waste staging pile area. Six pieces of confirmed SNF and two fractional pieces were identified following characterization. This material was transferred to the 100-K fuel storage basins for interim storage prior to final packaging and disposal. Load-out operations resumed on April 11, 2005 for previously sorted and segregated material. All remedial activities (excavation, sorting, and load-out) resumed on August 24, 2005. The remediation was completed on June 7, 2007, with the exception of characterization and dispositioning of the SNF and approximately 100 remaining anomalous containers.

Over 120,000 metric tons (132,300 tons) of debris and contaminated soil from the Burial Ground was removed and disposed at ERDF. At the conclusion of remediation activities, the excavated area was approximately 10 meters (33 feet) at its deepest, with a lateral footprint of approximately 21,600 square meters (5.3 acres). Approximately 136,000 square meters (33.6 acres) in total at the site were disturbed, including stockpiles and waste sorting and staging areas.

Code: 118-B-2	Classification: Accepted
Names: 118-B-2; Construction Burial Ground No. 1; Minor Construction Burial Ground No. 1	Reclassification Interim Closed Out (4/5/2005)
Type: Burial Ground	Start Date: 1/1/1952
Status: Inactive	End Date: 1/1/1956

Description: The site has been remediated and Interim Closed Out. The unit was a burial ground containing a trench that ran east and west. Characterization data found that the 118-B-2 Burial Ground was located within the mapped boundaries of the 118-B-3 Burial Ground. Therefore, the two waste sites were combined in closure documentation and collectively referred to as the 118-B-3 Burial Ground. Following remediation, authorization to remove the radiological postings was given in October 2012.

Location: Site characterization data collected in 2001 and 2002 indicated the trench may have actually been within the 118-B-3 Burial Ground. The site was originally thought to be located approximately 128 meters (420 feet) east of the 105-B Building and immediately west of the 118-B-3 Burial Ground.

Related Sites/ Structures: Received waste from the 107-B Basin repairs and from the 115-B Gas Recirculation Facility alterations.

Process Description: This burial ground received dry waste from the 107-B Basin repairs and from the 115-B Gas Recirculation Facility alterations. Operation of the unit began in 1952 and ended in the Summer of 1956.

Waste Type: Construction Debris

Waste Description: The unit was used for disposal of 100 cubic meters (131 cubic yards) of dry waste from the 107-B Basin repairs and waste from the 115-B Gas Recirculation Facility alterations. Potential Contaminants are: Co-60, Cs-137, Eu-152, Eu-154, Eu-155, Sr-90, chromium, Cr+6, lead, mercury, PCBs.

Closure Info: Interim: Results of geophysical investigations and test pit excavations conducted in 2001 and 2002 indicated that the 118-B-2 Burial Ground was located within the mapped boundaries of the 118-B-3 Burial Ground. Therefore, the two waste sites were combined in closure documentation and collectively referred to as the 118-B-3 Burial Ground.

Remedial action activities occurred between April 19, 2004 and June 24, 2004. At the completion of remedial action, the excavation was 4,803.8 square meters (51,708 square feet) in area with an average depth of less than 4.6 meters (15 feet). Approximately 9,525 metric tons (10,500 tons) of material, including soil and burial ground debris, were removed from the burial ground and disposed of at the ERDF. Results of the sampling, laboratory analyses, and data evaluations for the site indicate that all remedial action objectives and goals for direct exposure, protection of groundwater, and protection of the Columbia River have been met.

Code: 118-B-3	Classification: Accepted
Names: 118-B-3; Construction Burial Ground No. 2	Reclassification Interim Closed Out (4/5/2005)
Type: Burial Ground	Start Date: 1/1/1956
Status: Inactive	End Date: 1/1/1960

Description: The site has been remediated and Interim Closed Out. The unit contained many trenches running east and west. Characterization data found that the 118-B-2 Burial Ground was located within the mapped boundaries of the 118-B-3 Burial Ground. Therefore, the two waste sites

were combined in closure documentation and collectively referred to as the 118-B-3 Burial Ground. Following remediation, authorization to remove the radiological postings was given in October 2012.

Location: This unit was located approximately 160 meters (525 feet) northeast of the 105-B Building and directly east of 118-B-2.

Process Description: The burial ground was in operation from the summer of 1956 until 1960 and was used for disposal of solid waste from effluent pipeline modifications and for disposal of reactor-generated solid waste during various modification programs.

Waste Type: Construction Debris

Waste Description: The unit was used for the disposal of solid waste from the effluent line modification and for disposal of reactor-generated solid waste during various modification programs. Potential contaminants include: Co-60, Cs-137, Eu-152, Eu-154, Eu-155, Ni-63, Pu-238, Pu-239/240, Sr-90, chromium, lead, mercury, PCBs.

Closure Info: Interim: Results of geophysical investigations and test pit excavations conducted in 2001 and 2002 indicated that the 118-B-2 Burial Ground was located within the mapped boundaries of the 118-B-3 Burial Ground. Therefore, the two waste sites were combined in closure documentation and collectively referred to as the 118-B-3 Burial Ground.

Remedial action activities occurred between April 19, 2004 and June 24, 2004. At the completion of remedial action, the excavation was 4,803.8 square meters (51,708 square feet) in area with an average depth of less than 4.6 meters (15 feet). Approximately 9,525 metric tons (10,500 tons) of material, including soil and burial ground debris, were removed from the burial ground and disposed of at the ERDF. Results of the sampling, laboratory analyses, and data evaluations for the site indicate that all remedial action objectives and goals for direct exposure, protection of groundwater, and protection of the Columbia River have been met.

Code:	118-B-4	Classification:	Accepted
Names:	118-B-4; 105-B Dummy Burial Ground; 105-B Spacer Burial Ground	Reclassification	Interim Closed Out (5/24/2004)
Type:	Burial Ground	Start Date:	1/1/1956
Status:	Inactive	End Date:	1/1/1958
Description:	The site has been remediated and Interim Closed Out. The waste site consisted of six dummy storage pits installed vertically below ground. The pits were constructed of metal culverts 4.6 meters (15 feet) deep and 1.8 meters (6 feet) in diameter. During remediation, five wood and three metal caissons containing metallic debris were found. Following remediation, authorization to remove the radiological postings was given in October 2012.		
Location:	The site was located 91 meters (300 feet) northeast of the 105-B Reactor Building within the 105-B exclusion area fence.		
Process Description:	This site received irradiated aluminum fuel spacers from the 105-B Reactor.		
Waste Type:	Equipment		
Waste Description:	The unit was used for disposal of fuel spacers dummies. Potential contaminants included: Co-60, Cr+6.		
Closure Info:	Interim: During excavation of the burial ground, five wood and three metal caissons containing metallic debris were found. The caissons contained aluminum fuel spacers, splines, and lead-		

cadmium "poison pieces" used during operation of the 105-B Reactor. The pieces were found to be intact, which substantially reduced the leachability potential of the slugs. This observation and conclusion was further supported by waste profiling. Designation of the waste form determined they were fully encapsulated by the aluminum jacket. Therefore, the waste did not technically require macro encapsulation treatment for disposal at ERDF. At the completion of remedial action, the excavation was approximately 531.5 square meters (5,721 square feet) in area with an average depth of approximately 3.9 meters (13 feet). Approximately 3,171 metric tons (3,495 tons) of material, including soil and burial ground debris, were removed from the site and disposed of at ERDF.

Code:	118-B-6	Classification:	Accepted
Names:	118-B-6; 108-B Solid Waste Burial Ground; 108-B Solid Waste Burial Ground No. 2	Reclassification	Interim Closed Out (6/8/2006)
Type:	Burial Ground	Start Date:	1/1/1950
Status:	Inactive	End Date:	1/1/1953

Description: The site has been remediated and Interim Closed Out. The site has been excavated, backfilled and leveled to grade. The unit consisted of two concrete caissons (pipes). They were constructed of 5.5 meters (18 feet) long by 1.8 meters (6 feet) in diameter pipes that were buried vertically in the ground and capped with a concrete pad. The concrete pad had two pear-shaped steel lids that provided access to the caissons. Following remediation, authorization to remove the radiological postings was given in October 2012.

Location: This site was located approximately 107 meters (350 feet) northeast of the B Reactor.

Process Description: This site was used for disposal of wastes from the "metal line" of the P-10 Tritium Separation Project. At the time of remediation, one of the vertical caissons was filled with waste and capped and the other was partially filled with waste. Both were capped by a concrete pad. The pad measured about 4.6 by 3.0 meters (15 by 10 feet) with two pear-shaped steel lids that provided access to the caissons' burial chambers.

Waste Type: Equipment

Waste Description: The unit received the following types and amounts of wastes: 26,500 kilograms (58,500 pounds) of spent lithium-aluminum alloy, 21,300 kilograms (47,000 pounds) of lead from pots, 45 kilograms (100 pounds) of mercury from manometers and Toepler pumps, 1,720 kilograms (3,800 pounds) of aluminum cladding, and 1,360 kilograms (3,000 pounds) of palladium. Additionally, it contains a total of 21,200 kilograms (23.4 tons) of wastes generated as a result of the P-10 tritium production project in the 108-B Facility. Potential contaminants include: H-3, lead, mercury.

Closure Info: Interim (6/8/2006): Remedial action at the site began in November 2004. Excavation of the site involved removing the uncontaminated overburden, caissons, concrete pad, buried materials, and underlying contaminated soil. Although the majority of the excavation was completed by December 2004, leach tests done on soil samples taken from the bottom of the excavation showed levels of tritium that required an additional 1.5 meters (5 feet) of soil removal. This additional excavation was completed in June 2005.

One of the concrete caissons was filled with waste and capped, while the other was partially filled with waste, covered with a thin layer of concrete, and left for future use. A test pit was dug at the bottom of the 18 foot excavation. Tritium samples were collected at depths of 21 feet, 27 feet and 31 feet below ground surface.

At the conclusion of excavation activities, the elevation of the bottom of the excavation was at

136 meters (446 feet). The excavation was approximately 885 square meters (9,523 square feet) in area with a depth of approximately 7 meters (23 feet). Nearly 577 metric tons (636 tons) of contaminated material was disposed at ERDF.

Code: 1607-B8	Classification: Accepted
Names: 1607-B8; 1607-B8 Sanitary Sewer System; 1607-B8 Septic Tank System; Septic Tank & Disposal Field for 190-C Pumphouse; 124-C-2	Reclassification Interim Closed Out (7/29/2003)
Type: Septic Tank	Start Date: 1/1/1951
Status: Inactive	End Date: 1/1/1969

Description: The site has been remediated and interim closed out. The site consisted of a septic tank and tile field. The vertical tank was constructed of steel and had a 1,325-liter (350-gallon) capacity. The tile field was oriented north-south and was located to the south of the septic tank. The tile field was constructed of 20-centimeter (8-inch) vitrified clay pipe laid with open joints.

Location: The site was located east of the southeast corner of the 190-C Process Pumphouse.

Related Sites/Structures: The 190-C Pumphouse discharged sanitary effluent via the 100-C-9 pipeline to the septic system.

Waste Type: Sanitary Sewage

Waste Description: This unit received an unknown quantity of sanitary sewage from the 190-C Pumphouse.

Closure Info: Interim (7/29/2003): The Cleanup Verification Package (CVP-2003-05) has documented that the site meets the remedial action objectives (RAOs) and remedial action goals (RAGs) for the site as established in the Interim Action Record of Decision for the 100-BC-1, 100-BC-2, 100-DR-1, 100-DR-2, 100-FR-1, 100-FR-2, 100-HR-1, 100-HR-2, 100-KR-1, 100-KR-2, 100-IU-2, 100-IU-6, and 200-CW-3 Operable Units (ROD) and the Remedial Design Report/Remedial Action Work Plan for the 100 Area (RDR/RAWP).

At the completion of remedial action, the total excavation was approximately 255 square meters (2,740 square feet) in area with a depth of 2.5 meters (8.2 feet). Approximately 361 metric tons (397 tons) of site materials were disposed at the Environmental Restoration Disposal Facility. The septic system inlet pipe was removed to the extent of the site excavation. The approximately 12 meters of remaining pipeline between the 190-C Pump House and the 1607-B8 site has been included in the 100-C-9 pipeline site and will be dispositioned with the other pipelines in that site. At the conclusion of excavation activities, the bottom elevation of the excavation was at 143.7 meters (471.3 feet). The excavation was approximately 255 square meters (2,740 square feet) in area with a depth of approximately 2.5 meters (8.2 feet).

The remaining soils at the site have been sampled, analyzed, and modeled. The results of this effort indicated that the materials from the site containing contaminants at concentrations exceeding RAGs have been excavated and disposed at the ERDF. These results also indicated that residual concentrations will support future land uses that can be represented (or bounded) by a rural-residential scenario, and that residual concentrations throughout the site pose no threat to groundwater or the Columbia River. The 1607-B8 site is verified to be remediated in accordance with the ROD and may be backfilled.

Code: 1607-B9	Classification: Accepted
Names: 1607-B9; 1607-B9 Sanitary Sewer System; 1607-	Reclassification Interim Closed Out (8/28/2003)

B9 Septic Tank System; 124-C-3

Type: Septic Tank**Start Date:****Status:** Inactive**End Date:****Description:** The site has been remediated and interim closed out. The site was a septic tank and tile field.**Location:** The unit was located south of the 118-C-1 Burial Ground, southeast of the 105-C Reactor building and north of the perimeter road.**Related Sites/ Structures:** The site received sanitary sewer effluent from the 105 C reactor via an influent pipeline (100-C-9).**Process Description:** Effluent from the tank was routed a short distance (about 16 meters [52 feet]) through a pipeline to the tile field. The tile field located southeast of the tank was constructed of 20-centimeters (8-inches)-diameter vitrified clay pipe laid with open joints. The 20-centimeters (8-inches)-diameter pipeline between the reactor building and the septic tank was part of the 100-C-9 pipelines site. A small portion of the pipeline was removed with the 1607-B9 site. The remainder of the septic tank influent pipeline will be dispositioned with other pipelines included in the 100-C-9 pipelines site. The tank had a 9,085-liter (2,400-gallon) capacity.**Waste Type:** Sanitary Sewage**Waste Description:** This unit received an unknown amount of sanitary sewage from the 105-C Reactor Building.**Closure Info:** Interim (8/23/2003): Remedial action at the 1607-89 site was conducted in April and May 2003. Excavation of the site involved removing the overburden materials, septic system (septic tank, effluent pipeline, and tile drain field), and underlying contaminated soil. Contaminated materials including the septic tank, piping, and drain field piping were disposed of at the ERDF. The 1607-B9 Septic System inlet pipeline was removed to the extent of the site excavation. The remainder of the pipeline will be addressed with the 100-C-9 pipelines.

The Cleanup Verification Package (CVP-2003-06) has documented that the site meets the remedial action objectives (RAOs) and remedial action goals (RAGs) for the site as established in the Interim Action Record of Decision for the 100-BC-1, 100-BC-2, 100-DR-1, 100-DR-2, 100-FR-1, 100-FR-2, 100-HR-1, 100-HR-2, 100-KR-1, 100-KR-2, 100-IU-2, 100-IU-6, and 200-CW-3 Operable Units (ROD) and the Remedial Design Report/Remedial Action Work Plan for the 100 Area (RDR/RAWP).

At the completion of the remedial action, the total excavation was approximately 1,773 square meters (19,084 square feet) in area with a depth of 3.5 meters (11.5 feet). Approximately 3,060 metric tons (3,370 tons) of material from the site were disposed at the Environmental Restoration Disposal Facility.

The CVP demonstrated that remedial action has achieved the RAOs and corresponding RAGs established in the ROD and RDR/RAWP. The remaining soils have been sampled, analyzed, and modeled. The results of this effort indicated that the materials, containing COCs at concentrations exceeding RAGs, have been excavated and disposed at the ERDF. These results also indicated that residual concentrations will support future land uses that can be represented (or bounded) by a rural-residential scenario, and that residual concentrations throughout the site do not pose a threat to groundwater or the Columbia River. As stated in CVP-2003-00006, the site was verified to be remediated in accordance with the ROD and may be backfilled.

Code: 1607-B10**Classification:** Accepted**Names:** 1607-B10; 1607-B10 Septic Tank System;**Reclassification:** Interim Closed Out (7/29/2003)

Sewage Disposal Field

Type: Septic Tank **Start Date:** 1/1/1952

Status: Inactive **End Date:** 1/1/1969

Description: The site has been remediated and interim closed out. The site consisted of a septic tank and tile field. A steel pipe riser 20 centimeters (8 inches) in diameter and 84 centimeters (33 inches) above grade marked the location of the tank.

Location: The unit was located south of the former site of the 183-C Head House and east of the road that passed the 183-C Water Plant in a north/south direction.

Related Sites/ Structures: The 183-C Head House discharged sanitary effluent to the septic system via the 100-C-9 pipeline.

Waste Type: Sanitary Sewage

Waste Description: The unit received only sanitary sewer wastes from the headhouse of the 183-C Water Treatment Plant. There were no known discharges of hazardous chemicals or radionuclides.

Closure Info: Interim: At the completion of the remedial action, the total excavation was approximately 178 square meters (1,915 square feet) in area with a depth of 2.5 meters (8.2 feet) and the bottom elevation of the excavation was 145.0 meters (475.6 feet). Approximately 328 metric tons (361 tons) of material from the site were disposed of at the Environmental Restoration Disposal Facility. The 1607-B10 septic system inlet pipe was removed to the extent of the site excavation. The remainder of the pipeline between the 183-C Head House and the 1607-B10 site is included in the 100-C-9 pipelines site and will be dispositioned with the other pipelines in that site.

Remedial action objectives and goals for the 1607-B10 site were established by the U.S. Environmental Protection Agency (EPA) and the U.S. Department of Energy, Richland Operations Office, in concurrence with the Washington State Department of Ecology. These goals and objectives are documented in the Interim Action Record of Decision for the 100-BC-1, 100-BC-2, 100-DR-1, 100-DR-2, 100-FR-1, 100-FR-2, 100-HR-1, 100-HR-2, 100-KR-1, 100-KR-2, 100-IU-2, 100-IU-6, and 200-CW-3 Operable Units (ROD) (EPA 1999) and the Remedial Design Report/Remedial Action Work Plan for the 100 Area (DOE-RL-96-17).

The selected remedial action for the 1607-B10 site included (1) excavating the site to the extent required to meet specified soil cleanup levels, (2) disposing of contaminated excavation materials at the Environmental Restoration Disposal Facility at the 200 Areas of the Hanford Site, and (3) backfilling the site with clean soil to the average adjacent grade elevation. Excavation was driven by remedial action objectives for direct exposure, protection of groundwater, and protection of the Columbia River. For the respective points of compliance, remedial action goals (RAGs) were established to identify radionuclide and no radionuclide contaminants of potential concern (COPCs).

The CVP demonstrates that remedial action at the 1607-B10 site has achieved the RAOs and corresponding RAGs established in the ROD and RDR/RAWP. The remaining soils at the 1607-B10 site have been sampled, analyzed, and modeled. The results of this effort indicate that the materials from the 1607-B10 site containing COCs at concentrations exceeding RAGs have been excavated and disposed of at the ERDF. These results also indicate that residual concentrations will support future land uses that can be represented (or bounded) by a rural-residential scenario, and that residual concentrations throughout the site pose no threat to groundwater or the Columbia River. The 1607-B10 site is verified to be remediated in accordance with the ROD and may be backfilled.

Code: 1607-B11	Classification: Accepted
Names: 1607-B11; 1607-B11 Septic Tank System	Reclassification: Interim Closed Out (7/29/2003)
Type: Septic Tank	Start Date: 1/1/1952
Status: Inactive	End Date: 1/1/1969

Description: The site has been remediated and interim closed out. Remedial action at the 1607-B11 site was conducted in March 2003. Excavation of the site involved removing the overburden materials, septic system (septic tank and drain field), and underlying contaminated soil. Contaminated materials including the septic tank and drain field piping were disposed of at the ERDF. The site consisted of a septic tank and drain field.

Location: The unit was located north of the 183-C Filter Building site, west of the 183-C Filter Building site entrance road. The drain field was located northwest of the tank.

Related Sites/ Structures: The septic system was associated with the 183-C Filter Building, Pump Room and 100-C-9 pipeline site.

Process Description: A steel riser 20 centimeters (8 inches) in diameter and 46 centimeters (18 inches) above grade marked the location of the tank. The vertical tank was constructed of steel and had a capacity of 1,325 liters (350 gallons).

Waste Type: Sanitary Sewage

Waste Description: There were no known discharges of hazardous chemicals or radionuclides into the unit. The unit received only sanitary sewer wastes from the 183-C Filter Building & Pump Room (183-C Water Treatment Plant).

Closure Info: Interim: Remedial action at the 1607-B11 site was conducted in March 2003. Excavation of the site involved removing the overburden materials, septic system (septic tank and drain field), and underlying contaminated soil. Contaminated materials including the septic tank and drain field piping were disposed of at the ERDF.

Remedial action objectives and goals for the 1607-B11 site were established by the U.S. Environmental Protection Agency (EPA) and the U.S. Department of Energy, Richland Operations Office, in concurrence with the Washington State Department of Ecology. These goals and objectives are documented in the Interim Action Record of Decision for the 100-BC-1, 100-BC-2, 100-DR-1, 100-DR-2, 100-FR-1, 100-FR-2, 100-HR-1, 100-HR-2, 100-KR-1, 100-KR-2, 100-IU-2, 100-IU-6, and 200-CW-3 Operable Units (ROD) (EPA 1999) and the Remedial Design Report/Remedial Action Work Plan for the 100 Area (DOE-RL-96-17).

The selected remedial action for the 1607-B11 site included (1) excavating the site to the extent required to meet specified soil cleanup levels, (2) disposing of contaminated excavation materials at the Environmental Restoration Disposal Facility at the 200 Areas of the Hanford Site, and (3) backfilling the site with clean soil to the average adjacent grade elevation. Excavation was driven by remedial action objectives for direct exposure, protection of groundwater, and protection of the Columbia River. For the respective points of compliance, remedial action goals (RAGs) were established to identify radionuclide and no radionuclide contaminants of potential concern (COPCs).

Waste site COPCs for the 1607-B11 site were identified through process knowledge and analogous site data and are included in the Data Quality Objectives Summary Report for 100/300 Area Remaining Sites Analytical Sampling Effort (BHI 01249). The COPCs for this site consisted of metals, pesticides, polychlorinated biphenyls (PCBs), and semivolatile organic compounds (SVOCs). Additional COPCs for this site included at the request of the regulatory agency are radionuclides (gross alpha, gross beta, and gamma emitters) and hexavalent chromium. Gross alpha and gross beta analyses were conducted for screening purposes.

Of the metals analyzed for (arsenic, barium, cadmium, total chromium, lead, mercury, selenium, and silver), only lead was detected at levels greater than Hanford Site or Washington State background. Because concentrations of lead in soil were greater than background, it is included as a cleanup verification contaminant of concern (COC) for the 1607-B11 site. Because the other metals were not detected above soil background concentrations, they were not included as site COCs.

None of the 21 pesticides, 7 PCB Aroclors, or 64 SVOCs (with the exception of bis[2-ethylhexyl]phthalate) analyzed for were detected in cleanup verification samples at concentrations greater than the analytical method practical quantitation limits (PQLs). Bis[2-ethylhexyl]phthalate is included as a cleanup verification COC because of the detections above the analytical method PQL. None of the other pesticides, PCBs, or SVOCs were detected at concentrations greater than the analytical method PQL and are therefore not included as site COCs. These analyses were performed using the EPA SW-846 Methods 8081 for pesticides, 8082 for PCBs, and 8270 for SVOCs (EPA, 1986). With the exception of the SVOC analysis for one verification sample, the analyses met the specified detection limits included in the 100 Area Remedial Action Sampling and Analysis Plan (DOE-RL-96-22) or the Data Quality Objectives Summary Report for 100/300 Area Remaining Sites Analytical Sampling Effort (BHI 01249) (Appendix B has additional discussion). The PCB, pesticide, and SVOC results are included in Appendix A of BHI 01249.

With the exception of cesium-137 in one sample, none of the radionuclides analyzed for were detected at concentrations greater than the analytical method minimum detectable activity or greater than Hanford Site background for naturally occurring radionuclides. The radionuclide analyses met the radionuclide detection limits specified in SAP or are well below cleanup criteria. Cleanup verification sample results for cesium-137, cobalt-60, europium 152, europium 154, and europium 155 are included in Appendix A of the CVP and are included as cleanup verification COCs for the 1607-B11 site. These radionuclides were included as COCs because they are common COCs for liquid waste sites throughout the 100 Area.

Hexavalent chromium was not detected in the 1607-B11 cleanup verification samples at concentrations greater than the analytical method PQL. Hexavalent chromium was detected in the split sample used for quality assurance purposes at a concentration of 0.38 mg/kg, well below applicable cleanup criteria. Because hexavalent chromium is a common contaminant for 100 Area liquid waste sites, it is included as a cleanup verification COC for the 1607-B11 site. Hexavalent chromium was analyzed for using the EPA SW-846 Method 7196 (EPA, 1986). Hexavalent chromium cleanup verification results are included in Appendix A of the CVP.

For the various reasons given above, lead, bis(2-ethylhexyl)phthalate, hexavalent chromium, and the individual radionuclides (cesium-137, cobalt-60, europium 152, europium 154, and europium 155) are carried throughout the CVP as COCs for the 1607-B11 site. The final 1607-B11 cleanup verification COCs include: cesium-137, cobalt-60, europium-152, europium-154, europium-155, lead, hexavalent chromium, bis(2-ethylhexyl)phthalate.

At the completion of the remedial action, the total excavation was approximately 136 square meters (1,460 square feet) in area with approximate depth of 3.0 meters (9.8 feet). Approximately 131 metric tons (144 tons) of material from the site were disposed of at the Environmental Restoration Disposal Facility (ERDF). The 1607-B11 septic system inlet pipeline was removed to the extent of the site excavation. The remainder of the pipeline is included in the 100-C-9 pipelines site and will be dispositioned with it.

The CVP demonstrates that remedial action at the 1607-B11 site has achieved the RAOs and corresponding RAGs established in the ROD and RDR/RAWP. The remaining soils at the 1607-B11 site have been sampled, analyzed, and modeled. The results of this effort indicate that the

materials from the 1607-B11 site containing COCs at concentrations exceeding RAGs have been excavated and disposed of at the ERDF. These results also indicate that residual concentrations will support future land uses that can be represented (or bounded) by a rural-residential scenario and that residual concentrations throughout the site do not pose a threat to groundwater or the Columbia River. The 1607-B11 site is verified to be remediated in accordance with the ROD and may be backfilled.

Code:	100-C-3	Classification:	Accepted
Names:	100-C-3; 119-C French Drain; 119-C Sample Building French Drain	Reclassification	Interim Closed Out (7/28/2003)
Type:	French Drain	Start Date:	1/1/1960
Status:	Inactive	End Date:	
Description:	The site has been remediated and interim closed out. The french drain and surrounding soil were excavated and disposed at ERDF. The 100-C-3 French Drain was a 0.61 meter (2 ft) diameter gravel-filled pit that received effluent from the 119 C Sample Building.		
Location:	The site was located east of the 105-C Building.		
Related Sites/ Structures:	The 119-C Sample Building discharged effluent to this site.		
Process Description:	The 100-C-3 French Drain was a 0.61 meter (2 ft) diameter gravel-filled pit that received effluent from the 119 C Sample Building. The 119-C Sample Building was built in 1960 and contained water-cooled air sample monitoring equipment. Effluent from the sampling equipment, the building's swamp cooler, and possibly janitorial waste would have been disposed to the 100-C-3 French Drain.		
Waste Type:	Water		
Waste Description:	The 119-C Sample Building was built in 1960 and contained "water cooled" air sample monitoring equipment. Effluent from the sampling equipment, the building's swamp cooler, and janitorial waste would have been disposed to this drain.		
Closure Info:	Interim (7/28/2003): The french drain and surrounding soil were excavated and disposed at ERDF.		

Remedial action objectives and goals for the 100-C-3 site were established by the U.S. Environmental Protection Agency (EPA) and the U.S. Department of Energy, Richland Operations Office, in concurrence with the Washington State Department of Ecology. These goals and objectives are documented in the Interim Action Record of Decision for the 100-BC-1, 100-BC-2, 100-DR-1, 100-DR-2, 100-FR-1, 100-FR-2, 100-HR-1, 100-HR-2, 100-KR-1, 100-KR-2, 100-IU-2, 100-IU-6, and 200-CW-3 Operable Units (ROD) (EPA 1999) and the Remedial Design Report/Remedial Action Work Plan for the 100 Area (DOE/RL-96-17).

The selected remedial action for the 100-C-3 site included (1) excavating the site to the extent required to meet specified soil cleanup levels, (2) disposing of contaminated excavation materials at the Environmental Restoration Disposal Facility at the 200 Areas of the Hanford Site, and (3) backfilling the site with clean soil to average adjacent grade elevation. Excavation was driven by remedial action objectives for direct exposure, protection of groundwater, and protection of the Columbia River. For the respective points of compliance, remedial action goals (RAGs) were established to identify contaminants of potential concern (COPCs). Because none of the metals were detected in the cleanup verification samples above soil background concentrations, they were not included as site contaminants of concern (COCs). Verification sample results and soil background concentrations for metals are included in appendix A of the

CVP.

Although low levels of methylene chloride, acetone, and toluene were detected, their presence have been attributed to laboratory-introduced contamination and are not considered waste site contaminants or COCs for cleanup verification. Hexavalent chromium, a common contaminant for the 100 Area liquid waste sites, and the individual radionuclides (cesium-137, cobalt 60, europium 152, europium 154, and europium 155) are included as cleanup verification COCs.

At the completion of remedial action, the total excavation was approximately 94 square meters (1,011 square feet) in area with a depth of approximately 3 meters (9.8 feet). Approximately 49 metric tons (54 tons) of material from the site were disposed of at the Environmental Restoration Disposal Facility (ERDF).

The CVP demonstrates that remedial action at the site has achieved the RAOs and corresponding RAGs established in the ROD and RDR/RAWP. The remaining soils at the site have been sampled, analyzed, and modeled. The results of this effort indicate that the materials containing contaminants at concentrations exceeding RAGs have been excavated and disposed of at the ERDF. These results also indicate that residual concentrations will support future land uses that can be represented (or bounded) by a rural-residential scenario and that residual concentrations throughout the site do not pose a threat to groundwater or the Columbia River. As stated in CVP 2003-00009 the site has been verified to be remediated in accordance with the ROD and may be backfilled.

Code:	100-C-6	Classification:	Accepted
Names:	100-C-6; 100-C Reactor Cooling Water Effluent Underground Pipelines	Reclassification	Interim Closed Out (9/19/2011)
Type:	Radioactive Process Sewer	Start Date:	1/1/1952
Status:	Inactive	End Date:	1/1/1969
Description:	The site includes the underground 105-C Reactor cooling water effluent pipelines. These include those effluent pipelines that transported 105-C Reactor cooling water from the reactor to the 116-C-5 (107-C Retention Basin), and from the basin to the 132-B-6 and 132-C-2 Outfall Structures and/or to the 116-C-1 Liquid Waste Disposal Trench. This waste site includes all associated expansion and valve boxes and excludes the retention basin (separate site), outfall structures (separate sites), and those effluent pipelines that are within the confines of the 105-C Reactor Building or that run from the outfall structures to the bottom of the river. It also excludes all reactor influent pipelines that are upstream of the reactor building.		
Location:	The site is the location of all underground reactor effluent lines running from the 105-C Reactor Building to the Columbia River. This includes segments between the reactor building and the retention basin, and between the basin and the outfall structures. Also included are the underground lines that run from the retention basin to the 116-C-1 Trench. It excludes the reactor building (and a 1.5 meter [5 foot] buffer), retention basin, and outfall structures, each of which is treated as a unique waste site.		
Related Sites/ Structures:	Related structures include the 116-C-5 Retention Basin, the 132-B-6 and 132-C-2 Outfalls, the 116-C-1 Trench, the 105-C Reactor, the 100-B-8 Effluent Pipelines, and the 100-B-15 River Pipelines.		
Process Description:	Effluent water passed from the reactor rear face and gravity flowed through the underground effluent lines, junction boxes and diversion boxes to the retention basins where it was held up for a short period of time to allow thermal and radiological cooling before being released through the outfall structure to the Columbia River. During periods of reactor fuel cladding ruptures, some effluent was diverted to an open trench.		

Waste Type: Process Effluent

Waste Description: The waste was contaminated steel piping, concrete, and soil. Reactor cooling water became radioactively contaminated as it passed through the reactor core. Activation products created in the water included calcium-41, chromium-51, and zinc-65. Activation products from the reactor core that were picked up and transported by the cooling water included tritium, carbon-14, cobalt-60, nickel-63, and europium-152/154/155. Fuel element fission products such as strontium-90, and cesium-137, as well as transuranics such as plutonium-239/240 were introduced into cooling water due to fuel cladding failures. Concentrations of radionuclides in cooling water during normal reactor operations were approximately (0.2 microcuries/liter). Concentrations of radionuclides have built up in rust flakes and scale on the inner surfaces of the pipelines and in sludge in the diversion and junction boxes. Average beta-gamma concentrations for the effluent line scale and junction/diversion boxes are 83,000 and 120,000 picocuries/liter, respectively. Average plutonium-239/240 concentrations are 66 picocuries/gram for the effluent line scale and 720 picocuries/gram for the sludge at the bottom of the diversion and junction boxes. Direct readings of the bottom of the effluent lines averaged approximately 40,000 counts/minute with a Geiger-Mueller probe. Additional chemicals were added to the effluent for purposes of water treatment. These included aluminum sulfate (alum), with excess hydrated calcium oxide, sulfuric acid, chlorine, and sodium dichromate. Water pH was maintained at about 7.5, and the free chlorine residual was approximately 0.2 milligrams/liter. The waste is any remaining process effluent and the contaminated pipelines.

This Site has the Following SubSites:

Code: 100-C-6:1

Names: 100-C-6:1; 100-C Area South Effluent Pipelines

Code: 100-C-6:2

Names: 100-C-6:2; 100-C Area North Effluent Pipelines

Code: 100-C-6:3

Names: 100-C-6:3; 100-C Retention Basin to Outfalls Effluent Pipelines

Code: 100-C-6:4

Names: 100-C-6:4; B/C Pipelines Discovery Areas

Code: 100-C-6:5

Names: 100-C-6:5; Pipelines Sections Under Export Water Line (transferred to 100-B-34)

Code: 100-C-6:1

Classification: Accepted

Names: 100-C-6:1; 100-C Area South Effluent Pipelines

Reclassification: Interim Closed Out (4/20/2004)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This subsite included the underground reactor effluent pipelines surrounding the 118-C-3:1 (105-C Reactor) to within 1.5 meters (5 feet) of the reactor foundation, and running north from the reactor to B Avenue. This subsite excluded two 110 foot sections of pipeline that passed beneath the Export Water Line, see 100-C-6:5.

The Cleanup Verification Package 2003-00022 (CVP), documented completion of remedial action for the 100-C-6:1 subsite. Also included are the cross-tie underground lines that connected the 105-B Reactor effluent system to the 105-C Reactor effluent pipeline system. Sites that are excluded from the CVP are the associated retention basin and outfall structure, which was treated as unique waste sites. The 105-C Reactor effluent pipeline subsites (100-C-

6:2, 100-C-6:3, 100-C-6:4) were located north of B Avenue and addressed in a separate CVP.
Location: The site includes the underground pipelines from the 105-C Reactor to B Avenue.

Waste Type: Not Specified

Waste Description: The waste is radioactively contaminated steel piping, concrete, and soil.

Closure Info: Interim: At the completion of remedial action, the excavation was approximately 48,260 square meters (519,466 square feet) in area. Approximately 244,656 metric tons (269,742 tons) of material, including soil, debris, and piping were removed from the 100-B/C south pipelines site and disposed of at the Environmental Restoration Disposal Facility. The remaining soils at these sites have been sampled, analyzed, and modeled, while contaminated material has been excavated and disposed at ERDF. These results also indicated that residual concentrations in the shallow zone will support future land uses that can be represented (or bounded) by a rural-residential scenario, and that residual concentrations throughout the site pose no threat to groundwater or the Columbia River. The site was verified to be remediated in accordance with the ROD and may be backfilled.

The SubSite is Part Of:

Code: 100-C-6

Names: 100-C-6; 100-C Reactor Cooling Water Effluent Underground Pipelines

Code: 100-C-6:2

Classification: Accepted

Names: 100-C-6:2; 100-C Area North Effluent Pipelines

Reclassification: Interim Closed Out (2/17/2004)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: Cleanup Verification Package 2003-00019 (CVP) documented completion of remedial action for the 100-B/C Effluent Pipeline subsites located north of B Avenue (100-B-8:2, 100-C-6:2, 100-C-6:3, and 100-C-6:4 collectively referred to as the 100-B/C north pipelines site). The 100-C-6:2 subsite included the 105-C Reactor effluent pipelines from B Avenue north to the 116-C-5 Retention Basin, and included the diversion box just south of the 116-C-5 Retention Basin.

Location: These pipelines were north of the 105-C Reactor, north of B Avenue, to the 116-C-5 Retention Basin, and the diversion box is located just south of the 116-C-5 Retention Basin.

Waste Type: Not Specified

Waste Description: The waste is radioactively contaminated steel piping, concrete, and soil.

Closure Info: Interim: Remedial action at the 100-B/C north pipelines site began on February 26, 2001. Excavation of the site involved removing the overburden materials, piping, debris, and underlying contaminated soil. Based on field screening overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Contaminated materials were disposed of at ERDF. At the completion of remedial activities at the 100-B/C pipeline waste sites, more than 364 metric tons (400 tons) of concrete and fence posts with associated concrete debris were removed and segregated as part of the 100-B/C Pipeline Remediation Project (100-BC-1/100-BC-2 Operable Units). The majority of the fence posts are associated with security fencing that surrounded many of the pipelines and waste sites. None of the fence material has been known to be contaminated. External radiological surveys indicate that none of the concrete and fence posts show any signs of radioactive contamination. Radiological release surveys of the fence posts and concrete were performed to allow them to be used as clean

backfill. The Environmental Restoration Contractor radiological survey records for 100-B/C remediation between the dates of February 26, 2001 and November 6, 2003, contain survey results for the fencing debris used as backfill. The excavation was completed on February 6, 2003.

Excavation was driven by remedial action objectives for direct exposure, protection of groundwater, and protection of the Columbia River. For the respective points of compliance, remedial action goals (RAGs) were established to identify radionuclide and non-radionuclide contaminants of concern (COCs). Cleanup verification samples including QA/QC samples consisted of 193 shallow zone samples, 104 deep zone samples, 260 overburden samples, and 72 discovery area samples. The final verification samples were collected between August 12, 2002, and concluded on July 24, 2003, and were analyzed for the established contaminants of concern. The sample numbers are too numerous to list, however they are available in appendix A of CVP-2003-00019. At the completion of remedial action, the excavation was approximately 135,000 square meters (443,000 square feet) in area with an average depth of approximately 7.5 meters (25 feet). Approximately 244,656 metric tons (269,742 tons) of material including soil, debris, and piping were removed from the 100 B/C north pipelines site and disposed at the Environmental Restoration Disposal Facility.

The SubSite is Part Of:

Code: 100-C-6

Names: 100-C-6; 100-C Reactor Cooling Water Effluent Underground Pipelines

Code: 100-C-6:3

Classification: Accepted

Names: 100-C-6:3; 100-C Retention Basin to Outfalls Effluent Pipelines

Reclassification: Interim Closed Out (2/17/2004)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: Cleanup Verification Package 2003-00019 (CVP) documented completion of remedial action for the 100-B/C Effluent Pipeline subsites located north of B Avenue (100-B-8:2, 100-C-6:2, 100-C-6:3, and 100-C-6:4 collectively referred to as the 100-B/C north pipelines site). The 100-C-6:3 subsite included the 105-C underground effluent pipelines that ran between the 116-C-5 Retention Basin, 116-C-1 Trench, 132-B-6 Outfall, and 132 C 2 Outfall, and between the 116-B-11 Retention Basin and 116-B-1 Trench. Also included are the westernmost pipelines from the 116-C-5 Retention Basin to the junction box south of 116-C-5, and the pipeline on the north side of 116-C-5 that ran to the junction box immediately north of the eastern basin. One section of this subsite, (pipeline segment 16) was removed and backfilled but not entirely sampled as part of the 116-C-5 remedial action (BHI 1997). Pipeline Section 16 was sampled for cleanup verification with this subsite.

Location: 100-C-6:3 subsite included the 105-C underground effluent pipelines that ran between the 116-C-5 Retention Basin, 116-C-1 Trench, 132-B-6 Outfall, and 132 C 2 Outfall, and between the 116-B-11 Retention Basin and 116-B-1 Trench. Also included are the westernmost pipelines from the 116-C-5 Retention Basin to the junction box south of 116-C-5, and the pipeline on the north side of 116-C-5 that ran to the junction box immediately north of the eastern basin.

Waste Type: Not Specified

Waste Description: The waste is radioactively contaminated steel piping, concrete, and soil.

Closure Info: Interim: Remedial action at the 100-B/C north pipelines site began on February 26, 2001. Excavation of the site involved removing the overburden materials, piping, debris, and

underlying contaminated soil. Based on field screening overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Contaminated materials were disposed of at ERDF. At the completion of remedial activities at the 100-B/C pipeline waste sites, more than 364 metric tons (400 tons) of concrete and fence posts with associated concrete debris were removed and segregated as part of the 100-B/C Pipeline Remediation Project (100-BC-1/100-BC-2 Operable Units). The majority of the fence posts are associated with security fencing that surrounded many of the pipelines and waste sites. None of the fence material has been known to be contaminated. External radiological surveys indicate that none of the concrete and fence posts show any, signs of radioactive contamination. Radiological release surveys of the fence posts and concrete were performed to allow them to be used as clean backfill. The Environmental Restoration Contractor radiological survey records for 100-B/C remediation between the dates of February 26, 2001 and November 6, 2003, contain survey results for the fencing debris used as backfill. The excavation was completed on February 6, 2003.

Excavation was driven by remedial action objectives for direct exposure, protection of groundwater, and protection of the Columbia River. For the respective points of compliance, remedial action goals (RAGs) were established to identify radionuclide and non-radionuclide contaminants of concern (COCs). Cleanup verification samples including QA/QC samples consisted of 193 shallow zone samples, 104 deep zone samples, 260 overburden samples, and 72 discovery area samples. The final verification samples were collected between August 12, 2002, and concluded on July 24, 2003, and were analyzed for the established contaminants of concern. The sample numbers are too numerous to list, however they are available in appendix A of CVP-2003-00019. At the completion of remedial action, the excavation was approximately 135,000 square meters (443,000 square feet) in area with an average depth of approximately 7.5 meters (25 feet). Approximately 244,656 metric tons (269,742 tons) of material including soil, debris, and piping were removed from the 100 B/C north pipelines site and disposed at the Environmental Restoration Disposal Facility.

The SubSite is Part Of:

Code: 100-C-6

Names: 100-C-6; 100-C Reactor Cooling Water Effluent Underground Pipelines

Code: 100-C-6:4

Classification: Accepted

Names: 100-C-6:4; B/C Pipelines Discovery Areas

Reclassification: Interim Closed Out (2/17/2004)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: Cleanup Verification Package 2003-00019 (CVP) documented completion of remedial action for the 100-B/C Effluent Pipeline subsites located north of B Avenue (100-B-8:2, 100-C-6:2, 100-C-6:3, and 100-C-6:4, collectively referred to as the 100-B/C north pipelines site). This CVP also included eleven areas discovered to have radiological contamination above background, called "discovery areas." They are collectively identified as subsite 100-C-6:4.

Some areas were identified prior to commencement of the 100-B/C pipeline remediation activities, while others were found during the pipeline remediation process. The source of contamination for these areas has not been established, although the adjacent effluent piping and the 116-C-5 Retention Basins are suspected sources.

Location: These eleven pipeline segments are about 650 meters (2,145 feet) north-northeast of the 105-B Reactor, surrounding the 107-C and 107-B Retention basins.

Waste Type: Not Specified

Waste Description: The waste is radioactively contaminated steel piping, concrete, and soil.

Description:

Closure Info: Interim: Remedial action at the 100-B/C north pipelines site began on February 26, 2001. Excavation of the site involved removing the overburden materials, piping, debris, and underlying contaminated soil. Based on field screening overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Contaminated materials were disposed of at ERDF. At the completion of remedial activities at the 100-B/C pipeline waste sites, more than 364 metric tons (400 tons) of concrete and fence posts with associated concrete debris were removed and segregated as part of the 100-B/C Pipeline Remediation Project (100-BC-1/100-BC-2 Operable Units). The majority of the fence posts are associated with security fencing that surrounded many of the pipelines and waste sites. None of the fence material has been known to be contaminated. External radiological surveys indicate that none of the concrete and fence posts show any, signs of radioactive contamination. Radiological release surveys of the fence posts and concrete were performed to allow them to be used as clean backfill. The Environmental Restoration Contractor radiological survey records for 100-B/C remediation between the dates of February 26, 2001 and November 6, 2003, contain survey results for the fencing debris used as backfill. The excavation was completed on February 6, 2003.

Excavation was driven by remedial action objectives for direct exposure, protection of groundwater, and protection of the Columbia River. For the respective points of compliance, remedial action goals (RAGs) were established to identify radionuclide and non-radionuclide contaminants of concern (COCs). Cleanup verification samples including QA/QC samples consisted of 193 shallow zone samples, 104 deep zone samples, 260 overburden samples, and 72 discovery area samples. The final verification samples were collected between August 12, 2002, and concluded on July 24, 2003, and were analyzed for the established contaminants of concern. The sample numbers are too numerous to list, however they are available in appendix A of CVP-2003-00019. At the completion of remedial action, the excavation was approximately 135,000 square meters (443,000 square feet) in area with an average depth of approximately 7.5 meters (25 feet). Approximately 244,656 metric tons (269,742 tons) of material including soil, debris, and piping were removed from the 100 B/C north pipelines site and disposed at the Environmental Restoration Disposal Facility.

The SubSite is Part Of:

Code: 100-C-6

Names: 100-C-6; 100-C Reactor Cooling Water Effluent Underground Pipelines

Code: 100-C-6:5

Classification: Not Accepted

Names: 100-C-6:5; Pipelines Sections Under Export Water Line (transferred to 100-B-34)

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This waste site is two sections of pipe, approximately 110 feet long, that crossed under the active Export Water line. The line segments were left in place so as not to undermine the active 42 inch export water line that passes above these effluent lines. For remediation purposes, these sections of piping were transferred to waste site 100-B-34.

Location: These sections are north of the 105-C reactor.

Related Sites/ Structures: This section of pipe was previously associated with 100-C-6:1.

Process Description: Because these sections of pipe are being transferred to waste site 100-B-34 for remediation, this subsite is being Classified to Not Accepted - per E:Mail from WCH Leonard Habel.

Waste Type: Not Specified

Waste Description: The waste is radioactively contaminated steel piping, concrete, and soil.

The SubSite is Part Of:

Code: 100-C-6

Names: 100-C-6; 100-C Reactor Cooling Water Effluent Underground Pipelines

Code: 100-C-7

Classification: Accepted

Names: 100-C-7; 183-C Filter Building /Pumproom Facility Foundation and Demolition Waste; 183-C Monolith

Reclassification: Interim Closed Out (3/11/2014)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The 100-C-7 main site and subsite have been remediated and Interim Closed Out. The concrete foundation and contaminated soil that remained after the 1997 building demolition has been remediated and Interim Closed Out. The 100-C-7 waste site Reclassification status was updated in March 2014, when the stained soil (100-C-7 Subsite 1) remediation was completed. The 100-C-7 waste site is the residual sodium dichromate contamination associated with concrete that was left in place after the 1997 decommissioning and demolition of the 183-C Filter Building/Pumproom. The building foundation had been backfilled and graded to match the surrounding terrain. An area of yellow stained soil was observed near the sedimentation basins and became 100-C-7 Subsite 1.

Location: The foundation of the 183-C pump room was located in the southwestern portion of the 100B/C Area, 340 meters (1,115 feet) west of the 105-C Reactor Building, between the 183-C Sedimentation Basins and the four 183-C Clearwell Tank Pads.

Related Sites/ Structures: The 183-C Filter Building /Pump room Facility Foundation is associated with the yellow stained soil documented in 100-C-7:1.

Process Description: The 183 Filter Building/Pump Room Facility received water from the 183-C Sedimentation Basins and sent treated water to the 183-C Clearwells where it was stored for the 190-C Process Pump House.

One of the purposes of the 183-C Pump room was to treat the cooling water with sodium dichromate, a rust inhibitor, prior to storage in the four exterior 1.89E+07-liter (5E+06-gallon) tanks (183-C Clearwells). Water was drawn from the 183-C Filter Building clearwells and injected with sodium dichromate in the pump room prior to being pumped to the four, large tanks for storage. During past practices, the sodium dichromate was stored, mixed, and spilled in various locations throughout the building.

Waste Type: Chemicals

Waste Description: The concrete foundation located in the 183-C Pumproom is contaminated with sodium dichromate. Characterization data showed the contamination at the worst location to be 20 centimeters (8 inches) deep, half the thickness of the floor. Therefore, assuming the contamination averaged a depth of 15 centimeters (6 inches) throughout and covered a total area of 93 square meters (1000 square feet), a quantity of 14 cubic meters (500 cubic feet) was calculated.

-
- Waste Type:** Demolition and Inert Waste
- Waste Description:** The 183-C Filter Building foundation and clearwells were filled with demolition and inert waste materials and leveled to grade.
- Waste Type:** Asbestos (friable)
- Waste Description:** An underground asbestos wrapped steam line was encountered during the foundation demolition along the north clearwell. Due to the length and location of the steam line, the small area uncovered during the excavation work was not remediated. The pipe was wrapped in plastic, marked with "DANGER ASBESTOS HAZARD" tape, and covered again with soil.
- Closure Info:** Interim: Note: The contaminated concrete and 66,387 BCM of contaminated soil has been removed. The 100-C-7 waste site Reclassification status was updated when the 100-C-7 Subsite 1 remediation was completed. The Reclassification form for 100-C-7 Subsite 1 was approved on 3/11/2014.

During a previous 1996 remediation activity, the 183-C Filter Building Pump Room Facility was demolished. The remediation phase included the removal of asbestos lagged pipes located throughout the facility, hazardous materials, pumping equipment, valves, transit siding and roofing, and the structural steel. Demolition of the concrete structures below grade occurred during the steel removal activities. Once the complex was cleared of all the structural steel, the remaining concrete slab contaminated with sodium dichromate was removed and disposed offsite. All foundations and below-grade structures were demolished to a minimum of 1 meter (3 feet) below grade and backfilled. Structures deeper than 1 meter (3 feet), including those contaminated with sodium dichromate and an asbestos steam line remained in place. The amount of contaminated concrete was significantly more than what was originally estimated. Characterization data showed sodium dichromate contamination penetrating up to 20 cm (8 in.) into the concrete floor. As efforts were initiated on chiseling up the concrete, it became evident that there was no simple method to control the depth of concrete removal. The contaminated concrete was stabilized with a plastic barrier and a soil layer.

In 2004, the excavation of the concrete and contaminated soil beneath the concrete was completed to a depth of 4.6 meters (15 ft). In-process sampling indicated residual chromium contamination. Remedial activities were discontinued when yellow stained soil, due to sodium dichromate contamination, was observed beneath a north-south trending steam line. A test pit was excavated and sampled to a depth of 10 meters (33 ft). Total chromium contamination of 1,230 mg/kg and hexavalent chromium of 1620 mg/kg were present at the 33 foot level and extended beyond the waste site boundary. In 2007, a borehole (C4947) was drilled to evaluate the vertical extent of the contamination. Analytical results from the borehole showed a maximum concentration of 310 mg/kg total chromium at a depth of 10.7 meters (35 ft) below ground surface. It was determined that the contamination below 4.6 meters (15 ft) needed to be remediated to protect the 100-B/C Area groundwater. This contamination will be addressed in 100-C-7:1.

Demolition of reinforced concrete substructures associated with the 183-C Headhouse, 183-C Sedimentation Basins, 183-C Filter Building, and 183-C Clearwell pads began on June 8, 2010. Demolition of concrete foundations included shearing pipes and rebar and staging concrete rubble to the designated staging areas. Following subsurface concrete demolition, remedial activities to remove contaminated soil and portions of an inactive pipeline resumed on January 27, 2011. The 100-C-7 excavation was extended to a depth of approximately 17 meters (55 ft) bgs, and in-process sampling was performed. In-process sample results identified hexavalent chromium above cleanup levels at this depth. On June 20, 2011, a pothole was excavated to a depth of 22 meters (72 ft) bgs. Visual observations of discolored soil, elevated x-ray fluorescence (XRF) readings for total chromium and in-process sample results showed hexavalent chromium at concentrations exceeding cleanup criteria. The excavation continued

until groundwater was encountered at a depth of approximately 26 meters (85.3 ft) bgs. The remedial design was revised to encompass additional remediation of the 100-C-7 waste site to the north, based on the presence of chromium contamination at a depth of 22 meters (72 ft) that appeared to be trending to the northeast.

The 100-C-7 site remediation was completed on December 13, 2011. Approximately 73,780 bank cubic meters (BCM) (96,501 bank cubic yards [BCY]) of concrete and building slab rubble was transported to U-Canyon, located in the 200 West Area. Approximately 66,387 BCM (86,831 BCY) of contaminated soil was excavated for disposal to Environmental Restoration Disposal Facility (ERDF). 285,660 BCM (373,629 BCY) of overburden/layback soil was stockpiled at the 100-C-7 waste site for use as backfill material.

This Site has the Following SubSites:

Code: 100-C-7:1

Names: 100-C-7:1; Yellow Stained Soil/183-C Water Treatment Facility Head House

Code: 100-C-7:1

Classification: Accepted

Names: 100-C-7:1; Yellow Stained Soil/183-C Water Treatment Facility Head House

Reclassification: Interim Closed Out (3/11/2014)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. It was the 183-C area of stained soil. It was a large area (approximately 6600 sq meters) of soil that was mostly free of vegetation. The yellow stained soil was located between the railroad tracks on the west side of 183-C. The stained soil was observed in early April 2002. Discussions with project personnel concerning the past use of this area indicate that the appearance of the stain is consistent with sodium dichromate. It is unclear how the Sodium Dichromate was transferred from the Head House, located west of the sedimentation basins, to the Pump Room Facility, located east of the basins. The stained area may be a result of this transfer process.

Location: The stained soil was located adjacent to the northwest corner of the 183-C Sedimentation Basins. The 183-C head house is located 557 meters (1,828 feet) west of the 105-C Reactor Building.

Process Description: It is believed that a railroad spur was used to deliver water treatment supplies to the 183-C Head House. One of these chemicals was sodium dichromate, a corrosion inhibitor, used to treat the reactor cooling water. The Final Decommissioning Report for the 183-C Filter Building/Pump Room Facility (BHI-01005) states that the sodium dichromate was stored, mixed and spilled in various locations throughout the 183-C Pump Room Facility where it was then pumped into the four large exterior tanks and stored for the 190-C Process Pump House.

Waste Type: Soil

Waste Description: The waste is contaminated concrete and stained soils.

Closure Info: Interim (3/11/2014): The 183-C Filter building and pump room were demolished in 1996. Characterization data showed sodium dichromate contamination penetrating up to 20 cm (8 in.) into the concrete floor. As efforts were initiated on chiseling up the concrete, it became evident that there was no simple method to control the depth of concrete removal. It was determined that continued removal of the sodium dichromate-contaminated concrete was not cost efficient using the available resources and additional removal would occur during remediation of 100-B/C waste sites. In order to stabilize the remaining contaminated concrete (known as the

monolith) in a manner that would not hinder future cleanup activities, the contaminated concrete was covered with a plastic barrier and then a soil layer. In 2002, an area of yellow soil was observed and added as a subsite (100-C-7:1) to the 100-C-7 waste site. A sample analyzed in 2003 found total chrome and hexavalent chrome present.

Remedial action at the 100-C-7:1 subsite was initiated in December 2004 with excavation of the stained soil area located north of the 183-C Head House to a depth of approximately 3.5 meters (11.5 ft). Excavation adjacent to the north side of the 183-C Head House, where the outdoor chemical storage tanks were once located, proceeded to a depth of 4.6 meters (15 ft) where in-process sampling indicated residual chromium contamination exceeding cleanup criteria. Chromium staining was also observed on the outside foundation wall of the 183-C Sedimentation Basins exposed in the east sidewall of the excavation. Following initial remediation of the 100-C-7 waste site, it was determined that total chromium and hexavalent chromium were present in the subsurface soil beyond the boundaries of the remediation excavations at both the 100-C-7:1 and 100-C-7 monolith waste sites at concentrations exceeding the remedial action objectives and goals. Several potholes and boreholes were excavated at 100-C-7:1 to evaluate the distribution of sodium dichromate contamination. The initial pothole in April 2005 showed residual soil contamination present at 10 meters (33 ft) below ground surface (bgs). In 2009, it was determined that the hexavalent chromium in the vadose zone below 4.6 meters (15 ft) would need to be remediated in order to protect groundwater in the 100-B/C Area.

Demolition of reinforced concrete substructures associated with the 183-C Head House, 183-C Sedimentation Basins, 183-C Filter Building, and 183-C Clearwell pads in the vicinity of the 100-C-7 and 100-C-7:1 waste sites began on June 8, 2010. Demolition of concrete foundations included shearing pipes and rebar and staging concrete rubble to the designated staging areas. Following subsurface concrete demolition, remedial activities to remove contaminated soil and portions of inactive pipeline resumed on January 27, 2011. Remediation of the 100-C-7:1 subsite included removal and disposal of the inactive section of the relocated export water line, a segment of fire water piping, and the segment of 7.6-cm (3 inch) sodium dichromate pipeline from beneath the export water line crossing.

Approximately 45,000 bank cubic meters (BCM) (58,858 bank cubic yards [BCY]) of concrete and building slab rubble was transported to the U Canyon (in the 200 West Area) to be used as fill. By March 2012, approximately 261,414 BCM (341,917 BCY) of contaminated soil was excavated for disposal to the Environmental Restoration Disposal Facility (ERDF) and 373,403 BCM (488,393 BCY) of overburden/layback soil was excavated and stockpiled at the 100-C-7:1 waste site for use as backfill material. No anomalies were encountered. There are no radiological constituents associated with this site.

The SubSite is Part Of:

Code: 100-C-7

Names: 100-C-7; 183-C Filter Building /Pumproom Facility Foundation and Demolition Waste; 183-C Monolith

Code: 100-C-9

Classification: Accepted

Names: 100-C-9; 100-C Area Process and Sanitary Sewer Underground Pipelines

Reclassification: Interim Closed Out (7/11/2007)

Type: Process Sewer

Start Date: 1/1/1952

Status: Inactive

End Date: 1/1/1969

Description: This site was divided into four subsites. All of the subsites have been reclassified to Interim Closed Out or No Action. Therefore, the parent site is considered Interim Closed Out. It

consisted of approximately 3,000 meters (9,842.5 feet) of miscellaneous underground pipelines in 100-C Area. Subsite 1 is the main process sewers associated with the 105-C Reactor operations, Subsite 2 is the sanitary sewer feeder pipelines to four septic systems (1607-B8, 1607-B9, 1607-B10), Subsite 3 is the 183-C Clearwell pipelines, and Subsite 4 is the 100-C cooling water transfer lines and tunnels.

Location: The pipelines came from the 183-C Head House, Sedimentation/Filter Building, and Clearwells, the 190-C Pump House, and joined to form the 2,143-meter (7,032-foot) long concrete flume. The flume contained two side-by-side 4 foot by 6 foot (1.2 meter by 1.8 meter) process sewers that eventually drained at the 132-C-2 Outfall Structure.

Related Sites/ Structures: The buildings that discharged to the process and septic sewers are the 183-C Facilities and 190-C Pump House discharged to 1607-B8; the 105-C Reactor discharged to the 1607-B9 Septic system pipeline, and the 190-C Pump House connected to the 105-C Reactor through the treated cooling water pipelines.

Process Description: These pipelines carried a variety of non-radioactive waste fluids, treated cooling water (pre-reactor), and septage. This site did not include the clean water pipelines, pipelines otherwise identified with septic systems, or the main reactor effluent pipelines (100-C-6).

Waste Type: Equipment

Waste Description: The subsite consisted of the non-radioactively contaminated process and septic sewer pipelines associated with the 105-C Reactor operations. The 1607-B9 septic system serviced the 105-C Reactor and thus may be radioactively contaminated. Any contamination associated with these pipelines was expected to be in residual amounts.

Chemical additives to the reactor cooling water included aluminum sulfate (alum) with excess hydrated calcium oxide, sulfuric acid, chlorine, and sodium dichromate. Water pH was maintained at about 7.5, the free chlorine residual was approximately 0.2 milligrams/liter, and sodium dichromate was added at a rate of about 2 milligrams/liter. (Note: Reference: WHC-SD-EN-TI-169 is for 100-F, and applies equally to 100-C).

This Site has the Following SubSites:

Code: 100-C-9:1

Names: 100-C-9:1; 100-C Main Process Sewer Collection Line

Code: 100-C-9:2

Names: 100-C-9:2; 100-C Sanitary Sewer Lines

Code: 100-C-9:3

Names: 100-C-9:3; 183-C Clearwell Pipelines

Code: 100-C-9:4

Names: 100-C-9:4; 100-C Cooling Water Transfer Pipelines and Tunnels

Code: 100-C-9:1

Classification: Accepted

Names: 100-C-9:1; 100-C Main Process Sewer Collection Line

Reclassification: Interim Closed Out (6/6/2007)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. It included pipelines from the 183-C and 190-C facilities that fed into the main process sewer which consisted of a dual 1.2-meter by 1.8-meter (48-inch by 72-inch)-reinforced concrete box sewer that shared a central dividing

wall. The dual reinforced concrete box sewers were often referred to as the twin box culvert. The deep zone portion of the southern twin box culvert and sump were left in place. Given the construction sequence, leaks from the cold joints could have developed at any point along the length of the structure between the floor and walls.

Location: The main process sewer began down-gradient from the 183-C sedimentation basins and was oriented east-west, running to the north of the 100-C Area water treatment and pump house facilities. Multiple feeder pipes of various sizes from the 183-C and 190-C facilities discharged into the twin box culvert. The intended purpose of these pipelines was to handle diluted, nonhazardous process wastes and storm water. Sanitary wastes were handled separately via multiple septic systems. North of the 105-C Reactor Building, the twin box culvert changed orientation to approximately north-south and ran north to the former 132-C-2 outfall.

Process Description: A process sewer sump existed approximately 4.6 meters (14 ft) north of the northeast corner of the facility. The basement trench fed this sump, which overflowed into the 100-B/C process sewer system. Before building demolition, the access from the 190-C basement trench was closed and barricaded to prevent subsidence activities into the sump. No demolition activities were associated beyond the barricade, as the sump was outside of the 190-C foundation. It was approximately 3.7 meters (12 ft) below grade. The grade-level manhole cover and concrete pad allowing access to the sump were left intact after site grading and are visible at the site.

Waste Type: Not Specified

Waste Description: Potentially contaminated pipeline (and contents), concrete, and underlying/associated soils.

Closure Info: Interim: Remedial action was divided into a northern and a southern section due to the length of the required excavation of approximately 1875 meters (6150 feet).

The entire northern section along with a minimum of 0.3 meters (1 foot) of underlying soil was excavated between November 22, 2004, and February 2005. Approximately 14,639 metric tons (16,137 U.S. tons) of contaminated soil and concrete were disposed at the Environmental Restoration Disposal Facility. Verification sampling of the northern excavation was performed on August 23, 2005.

The southern portion consisted of a deep zone [i.e., more than 4.6 meters (15 feet) deep] section of the twin box culvert and a shallow zone which included a section of the twin box culvert and the feeder lines from the 100-C water treatment facilities. Remediation of the southern portion shallow zone began in December 2004, and was completed on April 19, 2006. Approximately 5,851 metric tons (6,450 U.S. tons) of contaminated soil and concrete were removed for disposal at ERDF. The deep zone portion of the southern twin box culvert was left in place.

The SubSite is Part Of:

Code: 100-C-9

Names: 100-C-9; 100-C Area Process and Sanitary Sewer Underground Pipelines

Code: 100-C-9:2

Classification: Accepted

Names: 100-C-9:2; 100-C Sanitary Sewer Lines

Reclassification: Interim Closed Out (7/11/2007)

Type: Sanitary Sewer

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. It consisted of the feeder pipelines for the former 1607-B8, 1607-B9, 1607-B 10, and 1607-B 11 septic systems (septic tank and drain field). All four of the septic systems and underlying contaminated soils were removed between

	March and May 2003, leaving the feeder pipelines in place.
Location:	Theses pipelines came from the 183-C, 190-C, and west side (pre-process side) of the 105-C Reactor buildings.
Waste Type:	Not Specified
Waste Description:	Potentially contaminated pipeline (and contents), concrete, and underlying/associated soils.
Closure Info:	<p>Interim: Remedial action associated with each of the four feeder pipelines began in early 2005 and concluded on September 29, 2006. A total of approximately 3,701 metric tons (4,080 U.S. tons) of contaminated material was disposed at ERDF. Statistical and focused sampling to verify the completeness of remediation was performed, and analytical results were shown to meet the cleanup objectives for direct exposure, groundwater protection, and river protection. A summary of the remediation for each of the four septic system pipelines follows:</p> <p>The pipeline from the 1607-B8 septic system was removed between March 23, 2005 and April 13, 2005. The site was excavated 2 meters (6.6 feet) below grade. A total of 266 metric tons (293 U.S. tons) of contaminated material was disposed at ERDF. The resulting trench was approximately 9 meters (29.5 feet) in length by 3.5 meters (11.5 feet) wide.</p> <p>Remediation of the 1607-B9 pipeline began on May 23, 2005 through July 11, 2005. The site was excavated to 3.5 meters (11.5 feet) below grade, removing a total of 2,626 metric tons (2,895 U.S. tons) of contaminated material that was disposed at ERDF. An additional 310 metric tons (342 U.S. tons) was removed on September 29, 2006, following detection of strontium-90 above the cleanup criterion in one verification sample.</p> <p>During excavation of the pipeline on May 25, 2005, an anomaly consisting of reddish-brown material was discovered after a concrete structure was removed. Radiological readings were all at background levels. A sample (J03701) of the material was collected and analyzed for total metals, leachable metals (toxicity characteristic leaching procedure [TCLP]), and semivolatile organic compounds (SVOCs) to support waste characterization and disposal. There were no significant metal or SVOC concentrations associated with this anomaly. The COPCs for the pipeline were identified through process knowledge and analogous site data and consisted of inductively coupled plasma (ICP) metals, hexavalent chromium, pesticides, polychlorinated biphenyls (PCBs), and semivolatile organic compounds. Radiological screening was also performed using gross alpha, gross beta, and gamma energy analyses.</p> <p>The 1607-B 10 pipeline was removed by March 2005. A total of approximately 9 meters (29.5 feet) of sanitary sewer pipeline and an estimated 45 metric tons (50 U.S. tons) of contaminated material was removed and sent to ERDF. The resulting trench was approximately 9 meters (29.5 feet) in length by 3.5 meters (11.5 feet) wide.</p> <p>The 1607-B-11 pipeline was co-located and remediated with the subsite 100-C-9:1, (100-C main process sewer collection pipelines). The 100-C-9:1 process sewer pipeline was excavated to at least 4 meters (13 feet) below grade, which concurrently removed the 1607-B 11 sanitary sewer pipeline that was approximately 1.2 meters (4 feet) below grade. The remediation activities were completed by April 2006, removing approximately 40 meters (131 feet) of the sanitary sewer pipeline and an estimated 454 metric tons (500 U.S. tons) of contaminated material was removed and sent to ERDF.</p> <p>Soil cleanup levels were established in the Remaining Sites ROD based on a limited ecological risk assessment. Although not required by the Remaining Sites ROD, a comparison against ecological risk screening levels was made for the site contaminants of concern (COC), contaminants of potential concern (COPC), and other constituents. Ecological screening levels</p>

were exceeded for antimony, boron, cadmium, total chromium, copper, lead, mercury, vanadium, and zinc. Exceedance of screening values does not necessarily indicate the existence of risk to ecological receptors. Residual concentrations of antimony, cadmium, total chromium, copper, lead, mercury, vanadium, and zinc were within the range of Hanford Site background levels, and boron concentrations were consistent with those seen elsewhere at the Hanford Site (no established background value is available). Concentrations of chromium, copper, lead, mercury, and zinc were within the range of Hanford Site background levels. All exceedances of screening values at the subsite will be evaluated in the context of additional lines of evidence for ecological effects following a baseline risk assessment for the river corridor portion of the Hanford Site, which will include a more complete quantitative ecological risk assessment. That baseline risk assessment will be used to support the final closeout decision for the 100-C-9 site.

The SubSite is Part Of:

Code: 100-C-9

Names: 100-C-9; 100-C Area Process and Sanitary Sewer Underground Pipelines

Code: 100-C-9:3

Classification: Accepted

Names: 100-C-9:3; 183-C Clearwell Pipelines

Reclassification Interim No Action (6/3/2004)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This subsite was evaluated and reclassified to No Action. It consisted of the process sewer pipelines that surrounded and drained from the 183-C Clearwells. The clearwell drains ran from circular aboveground steel tanks and connected to cast-iron process sewers surrounding the tanks. The cast-iron process sewers eventually drained to the main twin box process sewers that connected to the 190-C Facility. The basis for separating this site from the other 100-C-9 sites is that these process sewer lines were isolated from facilities known to be potential sources of radioactive and chemical contaminants. The clearwells were used to store treated cooling water for the 105-C reactor. Chromium was added to the treated water at concentrations between 2-4 ppm (parts per million) as a corrosion inhibitor. The primary contaminant of concern was hexavalent chromium.

Location: This subsite was located west of the 105-C Reactor building.

Waste Type: Not Specified

Waste Description: Potentially contaminated pipeline (and contents), concrete, and underlying/associated soils.

Closure Info: Interim: The No Action decision for the 100-C-9:3 site (a deep zone site) is supported based on reviews of site history, field observations, and characterization results. The maximum detected results from pipe scale and underlying/surrounding soil samples collected at locations suspected of having the greatest potential for residual contamination levels were shown to meet the cleanup objectives for direct exposure, groundwater protection, and river protection.

The SubSite is Part Of:

Code: 100-C-9

Names: 100-C-9; 100-C Area Process and Sanitary Sewer Underground Pipelines

Code: 100-C-9:4

Classification: Accepted

Names: 100-C-9:4; 100-C Cooling Water Transfer Pipelines and Tunnels

Reclassification Interim No Action (6/3/2004)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This subsite has been evaluated and reclassified to No Action. The site consisted of the cooling water transfer lines located in tunnels between the 190-C Pump House and the 105-C Reactor building. Six 0.6 meter (24 inch) steel pipes located in two tunnels transferred treated cooling water from the 190-C Pump House to the 105-C Reactor. The portions of the tunnels from the 190-C building to just west of the Ventilation house of each tunnel were removed with D of the 190-C Building. Radiological contamination may also have existed as contaminated biological waste products (i.e. bat guano).

Location: This subsite includes the Cooling Water transfer lines located in tunnels between the 190-C Pump House and the 105-C Reactor building.

Waste Type: Not Specified

Waste Description: The waste is the feedwater pipelines and their contents.

Closure Info: Interim: The scope of the confirmatory sampling effort consisted of the cooling water pipes and tunnels to the reactor. Sampling efforts were conducted only on the pipes. Previous sampling and survey data associated with decontamination and decommissioning (D & D) activities at the 105-C cooling water pipe tunnels was used to evaluate the tunnels and soil. This data, as well as a focused sampling approach at the analogous 100-B-14:4 site, were used to confirm current site conditions. The analogous, focused sampling data, previous tunnel sampling and survey data, and previous soil sampling beneath the tunnels was used to make decisions for reclassifying the site in accordance with the TPA-MP-14 (RL-TPA-90-0001) process. The confirmatory sampling results for pipe scale at an analogous site, previous sampling and surveying data associated with the concrete floor of the tunnels, and previous soil sampling from beneath the tunnels, support a no action reclassification of the 100-C-9:4 site.

The confirmatory sampling results for pipe scale at an analogous site, previous sampling and surveying data associated with the concrete floor of the tunnels, and previous soil sampling from beneath the tunnels, support a No Action reclassification of the 100-C-9:4 site.

The western end of the tunnels was removed from the 190-C Pump House to within approximately 18 meters (60 ft) of the tunnel ventilation structures during pump house demolition activities in 1996 and 1997. All of the water pipes in the remaining tunnel structures were cut and capped, and the western tunnel end was sealed with wood beams, railroad ties, angle iron, and foam sealant. During the 1996 through 1998 105-C Reactor interim safe storage activities, the eastern-most end of the tunnels was removed from the reactor building to approximately 3 meters (10 ft) from the west edge of the reactor building and backfilled with clean soil. Approximately 121 meters (400 ft) of open tunnel and piping remain in place.

The no action decision for the 100-C-9:4 site is supported based on reviews of site history, field observations and characterization results from an analogous site, and previous investigations performed at the site during D&D activities. The maximum detected results from pipe scale at analogous locations suspected of having the greatest potential for residual contamination levels were shown to meet the cleanup objectives for direct exposure, groundwater protection, and river protection. It should be noted, however, that given the demonstrated maximum residual concentration of hexavalent chromium in the feedwater pipes, institutional controls are required to prevent an inhalation exposure pathway.

The SubSite is Part Of:

Code: 100-C-9
Names: 100-C-9; 100-C Area Process and Sanitary Sewer Underground Pipelines

Code: 116-C-2A **Classification:** Accepted
Names: 116-C-2A; 105-C Crib; 105-C Pluto Crib; 116-C-2 **Reclassification** Interim Closed Out (3/15/2000)
Type: Crib **Start Date:** 1/1/1952
Status: Inactive **End Date:** 1/1/1969

Description: This site has been remediated and Interim Closed Out. The crib was covered over by concrete roof slabs. A 20-centimeter (8-inch) well casing extended through the crib and extended 36 meters (118 feet) below grade.

Location: The crib was located 275 feet east of the northeast corner of the 105-C Building.

Process Description: The pluto crib was constructed of concrete ties that were notched and stacked in a log cabin formation. Walls of concrete ties were constructed to divide the crib into twelve sections. Spaces between the ties were filled with sand. It measured 6.8 meters (22 ft) by 4.7 meters (15 ft) and was 5.1 meters (17 ft) deep.

The pluto crib was used for disposal for reactor cooling water after fuel cladding failures. This was the largest of the 100 Area Pluto Cribs and was unique in that effluents passed through a settling tank and sand filter before being discharged to the crib. A 20-centimeter (8-inch) schedule 40 stainless steel pipe ran from the 105-C Reactor Building to the 116-C-2B Pump Station. From the pump station, waste flowed through a 10-centimeter (4-inch) clay vitrified pipe that led to the 116-C-2C Sand Filter. The pipe was around 1.2 meters (4 feet) below grade at its junction with the pump station and 0.9 meters (3 feet) below grade at its junction with the sand filter. A 20-centimeter (8-inch) clay vitrified pipe, located approximately 6.1 meters (20 feet) below grade, similarly led from the sand filter to the Pluto crib. The sand filter and Pluto Crib were 12.6 meters (41.5 feet) apart. Wastes were drained by gravity from the sand filter to the Pluto Crib. After decommissioning, the crib and a surrounding depression were filled to grade with gravel and sand.

Waste Type: Process Effluent

Waste Description: This unit was initially used for the disposal of reactor cooling effluent after fuel cladding failures. Unknown additional quantities of contaminated wastes included wash water from the decontamination of dummy fuel elements on the 105-C wash pad, contaminated water received from the 105-C Metal Examination Facility, and liquid wastes received from the 105-C Reactor rear face. Potential contaminants of concern include americium-241, plutonium-238/239/240, cobalt-60, cesium-137 and strontium-90. Reports vary as to the amounts of different chemicals disposed of at the Pluto Crib site. Two reports state that the crib contained 500 kilograms (1,100 pounds) of sodium dichromate, 1,000 kilograms (2,200 pounds) of sodium oxalate, and 1,000 kilograms (2,200 pounds) of sodium sulfamate. Another report, states that the crib contained 990 kilograms (2,180 pounds) of sodium dichromate, 2,100 kilograms (4,630 pounds) of sodium oxalate, and 6,600 kilograms (14,550 pounds) of sodium sulfamate. Sodium hydroxide and nitric acid were also believed to be disposed at the site. The total waste volume is listed as 7.5E+06 liters (1.98E+06 gallons).

Closure Info: Interim (3/15/2000): The cleanup verification package (CVP-99-00019) for the 116-C-2A Pluto Crib, 116-C-2B Pump Station and 116-C-2C Sand Filter were combined into a single remediation area and collectively referred to as the 116-C-2ABC site. The overburden was removed from the 116-C-2ABC, 116-B-2, 116-B-3, 116-B-4, 116-B-9 and 116-B-12 waste sites located in the 100-BC-1 and 100-BC-2 Operable units. Excavation of the 116-C-2ABC site began on March 3, 1999, by removing the overburden materials, contaminated structures,

and underlying contaminated soil. Based on field screening, materials identified as potentially clean were placed in stockpiles for potential use as backfill. Materials that were found to be contaminated have been disposed of at ERDF. On May 7, 1999, the excavation had reached the design limit at El. 141.36 meters (464 ft), a depth of 9.15 meters (30 feet). Cleanup verification sampling began on May 17, 1999, and was finished on July 1, 1999.

At the completion of the remedial action, the area of the excavation was approximately 2,516 square meters (27,728 square feet) at a maximum depth of approximately 9.15 meters (30 feet). Approximately 15,939 metric tons (17,570 tons) of material were disposed of at ERDF. Approximately 2,000 cubic meters (70,629 cubic feet) of overburden was set aside from the 116-C-2ABC site as potentially clean. The excavation will be backfilled with clean fill materials to the reference grade of El. 150.5 meters (494 feet).

The posted URMA at 100 B/C Area, located south of B Ave. was removed in 2014. The waste sites in this area were released under an approved interim or final Record of Decision. (CCN 176577)

Code:	116-C-2B	Classification:	Accepted
Names:	116-C-2B; 116-C-2B Pump Station; 105-C Pluto Crib Pump Station; 116-C-2-1	Reclassification	Interim Closed Out (3/15/2000)
Type:	Pump Station	Start Date:	1/1/1952
Status:	Inactive	End Date:	1/1/1969

Description: This site has been remediated and Interim Closed Out. It was a rectangular shaped, concrete sump. A diamond-plate steel access hole cover was located in the northwest corner, and a vent was located at the east end. The site included all underground pipelines between the 105-C Reactor and the 116-C-2C Sand Filter.

Location: The site was located northwest of the 116-C-2C Sand Filter.

Related Sites/ Structures: The associated structures were the 116-C-2A Pluto Crib, 116-C-2C Sand Filter, and the 105-C Reactor.

Waste Type: Process Effluent

Waste Description: The unit received waste from the 105-C Reactor and pumped it into the 116-C-2C (105-C Pluto Crib Sand Filter).

Closure Info: Interim (3/15/2000): The cleanup verification package (CVP-99-00019) for the 116-C-2A Pluto Crib, 116-C-2B Pump Station and 116-C-2C Sand Filter were combined into a single remediation area and collectively referred to as the 116-C-2ABC site. The overburden was removed from the 116-C-2ABC, 116-B-2, 116-B-3, 116-B-4, 116-B-9 and 116-B-12 waste sites located in the 100-BC-1 and 100-BC-2 Operable units. Excavation of the 116-C-2ABC site began on March 3, 1999, by removing the overburden materials, contaminated structures, and underlying contaminated soil. Based on field screening, materials identified as potentially clean were placed in stockpiles for potential use as backfill. Materials that were found to be contaminated have been disposed of at ERDF. On May 7, 1999, the excavation had reached the design limit at El. 141.36 meters (464 ft), a depth of 9.15 meters (30 feet). Cleanup verification sampling began on May 17, 1999, and was finished on July 1, 1999.

At the completion of the remedial action, the area of the excavation was approximately 2,516 square meters (27,728 square feet) at a maximum depth of approximately 9.15 meters (30 feet). Approximately 15,939 metric tons (17,570 tons) of material were disposed of at ERDF. Approximately 2,000 cubic meters (70,629 cubic feet) of overburden was set aside from the

116-C-2ABC site as potentially clean. The excavation will be backfilled with clean fill materials to the reference grade of El. 150.5 meters (494 feet).

The posted URMA at 100 B/C Area, located south of B Ave. was removed in 2014. The waste sites in this area were released under an approved interim or final Record of Decision. (CCN 176577)

Code:	116-C-2C	Classification:	Accepted
Names:	116-C-2C; 116-C-8; 105-C Pluto Crib Sand Filter; 116-C-2-2	Reclassification	Interim Closed Out (3/15/2000)
Type:	Sand Filter	Start Date:	1/1/1952
Status:	Inactive	End Date:	1/1/1969
Description:	This site has been remediated and Interim Closed Out. The structure was an open-bottom concrete box placed in a sand and gravel pit. It was covered with concrete shielding slabs. The site included the underground pipelines from the 105-C Pluto Crib Sand Filter to the 116-C-2A Pluto Crib.		
Location:	The site is located west of the 116-C-2A (105-C Pluto Crib). The crib was located 275 feet east of the northeast corner of the 105-C Building.		
Related Sites/ Structures:	This unit was associated with 116-C-2A (105-C Pluto Crib) and 116-C-2B (105-C Pluto Crib Pump Station).		
Process Description:	Contaminated water was spread over the surface of the sand filter media by distribution trays. The effluent passed through this filter prior to being discharged to the soil column of the 116-C-2 Crib.		
Waste Type:	Process Effluent		
Waste Description:	The 105-C Pluto crib sand filter was sampled and surveyed between 2/6/76 and 4/5/76. Based on sample results, the sand filter contains an estimated radioactive inventory of 260 curies (Table 3.4-9, page 3-30, UNI-946) in 90,000 cubic feet of soil (about 6,100,000 Kg). Beta-gamma concentrations in the sand filter averaged 42,000 pCi/g with a maximum value reported of 7,300,000 pCi/g in a sample taken from an inlet distribution tray. Radioactivity in this sample was primarily due to cobalt-60 although high levels of strontium-90 (29,000 pCi/g) and cesium-137 (140,000 pCi/g) were present as well. This sample also contained 1,500 pCi/g plutonium-239/240. The average concentration of plutonium-239/40 in the sand filter was reported to be about 20 pCi/g for the entire mass of potentially contaminated soil column. Sample analyses for the sand filter are presented in Table 3.4-7 (page 3-28, UNI-946) by Dorian and Richards. The site may have received contaminated wastes from the decontamination of dummy fuel elements on the wash pad. Americium-241 is another potential contaminant of concern.		
Closure Info:	Interim (3/15/2000): The cleanup verification package (CVP-99-00019) for the 116-C-2A Pluto Crib, 116-C-2B Pump Station and 116-C-2C Sand Filter were combined into a single remediation area and collectively referred to as the 116-C-2ABC site. The overburden was removed from the 116-C-2ABC, 116-B-2, 116-B-3, 116-B-4, 116-B-9 and 116-B-12 waste sites located in the 100-BC-1 and 100-BC-2 Operable units. Excavation of the 116-C-2ABC site began on March 3, 1999, by removing the overburden materials, contaminated structures, and underlying contaminated soil. Based on field screening, materials identified as potentially clean were placed in stockpiles for potential use as backfill. Materials that were found to be contaminated have been disposed of at ERDF. On May 7, 1999, the excavation had reached the design limit at El. 141.36 meters (464 ft), a depth of 9.15 meters (30 feet). Cleanup verification sampling began on May 17, 1999, and was finished on July 1, 1999.		

At the completion of the remedial action, the area of the excavation was approximately 2,516 square meters (27,728 square feet) at a maximum depth of approximately 9.15 meters (30 feet). Approximately 15,939 metric tons (17,570 tons) of material were disposed of at ERDF. Approximately 2,000 cubic meters (70,629 cubic feet) of overburden was set aside from the 116-C-2ABC site as potentially clean. The excavation will be backfilled with clean fill materials to the reference grade of El. 150.5 meters (494 feet).

The posted URMA at 100 B/C Area, located south of B Ave. was removed in 2014. The waste sites in this area were released under an approved interim or final Record of Decision. (CCN 176577)

Code: 116-C-3	Classification: Accepted
Names: 116-C-3; 105-C Chemical Waste Tanks	Reclassification: Interim Closed Out (1/31/2008)
Type: Storage Tank	Start Date: 1/1/1964
Status: Inactive	End Date: 1/1/1969

Description: The site has been remediated and Interim Closed Out. It has been backfilled, and revegetated. Before remediation the site consisted of two below-grade chemical waste storage tanks, designed to receive and store chemical waste from the 105-C Reactor Metals Examination Facility (MEF) de-jacketing process. Each of the waste tanks was approximately 3.5 meters (11.5 ft) in diameter and approximately 10.9 meters (36 ft) in length, with a nominal capacity of 102,200 L (27,000 gal). The long axis of each tank was oriented east-west on a horizontal plane, with one tank located north of the other. The crests of the tanks were located approximately 3.4 meters (11 ft) below existing grade, with centerlines spaced approximately 6.2 meters (20 ft) apart.

Location: The site was located approximately 100 meters (330 ft) northeast of the 105-C Reactor safe storage enclosure, just outside the exclusion area fence.

Related Sites/Structures: The site is associated with the 105-C Reactor Building and pipeline site 100-C-6:1.

Process Description: The tanks were originally installed to receive liquid wastes from the 105-C Metal Examination Facility (MEF), which was part of the 105-C Reactor Building, and was used to examine and test irradiated fuel elements. Examination included chemical de-jacketing of the fuel slugs. The process consisted of two cycles of immersing the fuel slugs in a 50% sodium hydroxide solution, draining the resulting solution, and rinsing the de-jacketed slugs with water. The slugs were then cleaned with a 10% nitric acid solution, followed with multiple water rinses.

Waste was discharged to the tanks from the 105-C MEF via a 5-cm (2-in.) stainless-steel pipeline connected to top-feed distribution piping at the tanks. This discharge line was included in the 100-C-6:1 subsite (known as Pipeline 31). The pipeline was removed up to a point immediately upstream of the discharge to the southern 116-C-3 tank. Multiple additional small-diameter pipelines were also connected to the tops of the tanks, including vent risers, overflow lines, and conduits for the cathodic protection system used for corrosion control.

Closure Info: Interim: The chemical tanks were installed in 1955. Conflicting reports described their usage. One report indicated the tanks were potentially unused. However, remediation of the influent pipeline and confirmatory evaluation of the waste site in 2003 confirmed that the site had received radiological waste. Subsequent additional characterization was done in 2004 that indicated that the southern tank was approximately one-third full of mixed waste consistent with the 105-C Reactor Metals Examination Facility (MEF) de-jacketing process. The north tank was found to contain only a small volume of suspect condensate or residual water from

pressure testing. No significant radiological activity or metals concentrations were detected in the north tank.

Remediation of the waste site was performed from February through December 2007. The overburden and surrounding soils were removed to provide a sub-grade staging and operations area for waste treatment activities. During excavation, a small volume of radiologically contaminated soil was encountered beneath the influent pipelines near the southern tank, and staged onsite in the waste staging pile area before disposal at the Environmental Restoration Disposal Facility (ERDF). A concrete pad, unrelated to the 116-C-3 waste site, was also partially demolished and removed from the northeastern corner of the operations area. Systematic global positioning system environmental radiological surveys (GPERS) were performed across each 1 meter (3 ft) lift of stockpiled overburden soil. No significant radiological activity was detected.

Site remediation consisted of the removal and stockpiling of overburden material, followed by a proof-of-principle demonstration of the empty northern tank. A treatment and remediation process was planned for the southern tank. Subsequently, the contents of the southern tank was treated using chemical treatment to address the corrosivity characteristic of the waste and reduce hexavalent chromium to trivalent chromium. A physical treatment using in situ grout stabilization was applied to the southern tank. Verification sampling indicated that requirements had been met, and the treated tank was demolished and removed, along with approximately 1.5 meters (5 ft) of underlying soil.

Treated material, demolition rubble, and approximately 1 meters (3 ft) of soil underlying the tank was removed for disposal at ERDF. Initial soil samples from the tank footprint indicated residual hexavalent chromium concentrations above soil remedial action goals (RAGs) and elevated residual radiological activity. Therefore, an additional 0.7 meters (2 ft) of soil was removed from the southern tank footprint and disposed at ERDF. Excavation at the site extended to a maximum depth of approximately 8.5 meters (28 ft) below ground surface (bgs). The footprints of the remediated waste tanks were entirely in the deep zone (greater than 4.6 m [15 ft] bgs). Approximately 3,767 metric tons (4,152 U.S. tons) of treated waste, debris, and soil was removed from the site and disposed at ERDF. Following verification of attainment of cleanup criteria, the site was backfilled and revegetated.

Code: 116-C-6	Classification: Accepted
Names: 116-C-6; 105-C Fuel Storage Basin Cleanout Percolation Pit; 105-C Pond	Reclassification: Interim Closed Out (12/8/2003)
Type: Process Pit	Start Date: 1/1/1984
Status: Inactive	End Date: 1/1/1985
Description:	The site has been evaluated and determined to meet remedial action objectives and supports reclassification to interim closed out. The site was an unlined, L-shaped open excavated pit. Soil was excavated from the center and used as a berm around its perimeter.
Location:	The site was located east of the 105-C Reactor Building, east of the reactor exclusion fence.
Related Sites/ Structures:	The site was related to the 105-C Fuel Storage Basin.
Process Description:	The pit was constructed to receive liquid from the clean out of the 105-C Fuel Storage Basin. The radiologically contaminated shielding water in the basin was processed through an ion exchange column and filter system. After being sampled to determine if the radioactivity was below release criteria, the water was discharged to the pit. Chemical analysis for hazardous substances was not a standard practice and there was no evidence that it was performed. The

water percolated into the soil as fast as it was discharged to the site.

Waste Type: Water

Waste Description: This unit received water from the 105-C Fuel Storage Basin cleanout. Before being discharged to the pit, the radiologically contaminated shielding water in the basin was processed through ion exchange columns. Composite samples were taken to ensure that radionuclide concentrations were below release criteria in Table II of DOE Order 5480.1. No known hazardous substances were present in the water; however chemical analysis during that period was not a standard practice, and there is no evidence that any chemical analyses were performed.

Closure Info: Interim: In 2003 the waste site evaluation 0100B-CA-V0121, Rev. 4 demonstrated that information (which included previous sample results, a 2003 field walkdown (site evaluation), and historical data) supported reclassification to "interim closed out" of the 116-C-6 site. The site soil conditions have achieved the remedial action objectives and the corresponding remedial action goals established in the Remedial Design Report/Remedial Action Work Plan for the 100 Area (DOE-RL 2002) and the Interim Action Record of Decision for the 100-BC-1, 100-BC-2, 100-DR-1, 100-DR-2, 100-FR-1, 100-FR-2, 100-HR-1, 100-HR-2, 100-KR-1, 100-KR-2, 100-IU-2, 100-IU-6, and 200-CW-3 Operable Units (EPA 1999).

Cleanup verification samples collected, from four test pits in March 2003. The samples were analyzed by offsite contract laboratories using U.S. Environmental Protection Agency approved analytical methods. Sample results from test pit #3 had elevated levels of cesium-137. Per agreement with the EPA, the area of the hot spot was excavated and contaminated soil removed and disposed of at the Environmental Restoration Disposal Facility. After remediation, a confirmatory sample was collected to verify cleanup levels had been met.

Residual soil concentrations support future land uses that can be represented (or bounded) by a rural residential scenario and pose no threat to groundwater or the Columbia River.

Code:	118-C-1	Classification:	Accepted
Names:	118-C-1; 118-C-1 Burial Ground; 105-C Burial Ground; 105-C Solid Waste Burial Ground	Reclassification	Interim Closed Out (7/19/2007)
Type:	Burial Ground	Start Date:	1/1/1953
Status:	Inactive	End Date:	1/1/1969
Description:	The site has been remediated and Interim Closed Out. It was a burial ground that contained six small engineered disposal structures (rectangular pits with reinforced side walls) and several trenches running north and south. A total of ten trenches were identified during remediation. The site boundaries were permanently marked with concrete posts numbered C-70-1 through C-70-20.		
Location:	The site was located approximately 152 meters (500 feet) southeast of the 105-C Building.		
Process Description:	This site was the primary burial ground for general wastes from the operation of the 105-C Reactor. It received radioactively contaminated process tubes, aluminum fuel spacers, control rods, reactor hardware, and soft wastes. Some Spent Nuclear Fuel was found during remediation.		
Waste Type:	Equipment		
Waste Description:	The unit was used for miscellaneous solid waste from 105-C Building that included process tubes, aluminum spacers, control rods, soft waste, and reactor hardware. The C Area Land Burial log (1962-1965) identified waste as trash, poison splines, dummies, hot laundry, fan		

filters, irradiated boron balls, ceramic samples, thimbles, gun barrels, and hoses. The Burial Ground ROD reported that an estimate of the waste was 86 metric tons (94.8 tons) of boron, 1.1 metric tons (1.2 tons) of graphite, 0.51 metric tons (0.56 tons) of lead, 21.6 metric tons (23.8 tons) of lead/cadmium, and 96 metric tons (105.9 tons) of other materials. Potential contaminants include: Ag-108m, C-14, Co-60, Cs-137, Eu-152, Eu-154, Eu-155, H-3, Ni-59, Ni-63, Sr-90, Ba-133, Ca-41, cadmium, Cr+6, lead, boron, mercury, PCBs, SVOAs, TPH, and VOAs.

Closure Info: Interim: Remedial action began on February 2, 2004 and was completed on May 27, 2006. Excavation of the ten trenches, (eight oriented in a north-south direction and the other two oriented east to west) involved removing the uncontaminated overburden, the buried contaminated debris, and the underlying contaminated soil. Visual observations of the buried waste confirmed that the following items had been disposed in the Burial Ground during its operation: several thousand perforated and non-perforated spacers, piping and tubing, vertical control rods, sheet metal, boron balls, boron ball vacuums, bismuth, paint, high-dose piping, wax, casks, tar, tar paper, miscellaneous metal, mercury tubes, lead items, reactor parts and hardware, Spent Nuclear Fuel (SNF), hydraulic hoses and parts, degraded drums, glassware, concrete, electrical components, and other miscellaneous debris.

During remedial excavation and sorting, Spent Nuclear Fuel (SNF) was discovered on September 27, 2004. All remedial activities were suspended until the Authorization Basis could be properly assessed and revised to include the SNF. Load-out operations were re-established on April 11, 2005, for previously sorted and segregated material. All remedial activities (excavation, sorting, and load-out) resumed on October 25, 2005 and were completed on May 27, 2006. Over 75,300 metric tons (83,000 tons) of waste and contaminated soil from the Burial Ground was disposed at the Environmental Restoration Disposal Facility (ERDF). The Spent Nuclear Fuel was transferred to the 100-K Basins for interim storage prior to final packaging and disposal. ERDF and approximately 9,300 bank cubic meters (BCM) of overburden soil was removed for subsequent backfill. At the conclusion of excavation activities, the elevation at the deepest part of the remedial excavation was 146 meters (480 feet) above sea level. The remediation excavation footprint was approximately 20,500 square meters (220,600 square feet) in area with a maximum depth of approximately 5 meters (17 feet).

Code:	118-C-2	Classification:	Accepted
Names:	118-C-2; Ball 3X Storage Tank; 105-C Ball Storage Tank	Reclassification	Interim Closed Out (7/30/2004)
Type:	Storage Tank	Start Date:	1/1/1969
Status:	Inactive	End Date:	1/1/1969
Description:	The site has been remediated and interim closed out. The waste site had been an underground storage tank.		
Location:	The site was located approximately 6 meters (20 feet) directly north of the northeast corner of the 105-C Reactor Building (original footprint).		
Process Description:	Operation of this waste site began in 1969, coinciding with the Ball 3X Project work. The project operation ended that same year. During Ball 3X Project work with a prototype-contaminated ball sorter, the tank received highly radioactive, irradiated, nickel-plated boron-steel and carbon-steel balls. The tank served as temporary storage until the balls decayed radiologically before being transferred to a solid waste burial ground. The storage box had a slope with vents at each end. One vent was used to put the balls into the tank and the other was used to remove them, following a decay period. Approximately 9,070 kilograms (20,000 pounds) of highly radioactive balls remained in the storage tank. Approximately 70% of the balls remaining are boron-steel and 30% are carbon-steel.		

Waste Type: Equipment

Waste Description: During Ball 3X project work with a prototype contaminated ball sorter, the tank received highly radioactive, irradiated, nickel-plated boron steel and carbon steel balls for temporary storage so that they would decay radiologically before burial. Approximately 9,070 kilograms (20,000 pounds) of highly activated balls remain in the storage tank. Seventy percent of the balls remaining are boron steel, and thirty percent are carbon steel. A 1987 evaluation of the tank waste estimated that 80 curies of cobalt-60 and 1.6 curies of nickel-63 are present. Potential contaminants include: Co-60, Ni-63, Sr-90, Cs-137, Eu-152, Eu-154, U-238, Pu-238, Pu-239/240, chromium, lead, mercury.

Closure Info: Interim (7/30/2004): Remedial action began on November 10, 2003. Excavation of the site involved removing the overburden materials, debris, and underlying contaminated soil. Both the collection tank and loose boron balls exposed during the excavation were removed. The tank was a light gage stainless steel tank installed about two feet below grade, about 8 feet long x 8 feet deep and 4 feet wide (long rectangular box) with two 4 inch diameter riser pipes in the top of the tank that were about 4 feet apart and protruded 2 feet above ground. The box tank was installed at a slight slope, possibly to allow the 1-centimeter (0.39 inch) diameter nickel-plated 1 weight % borated stainless steel balls to roll to one end. The field staff reported that the light gage stainless steel box tank was about half full of the 3/8-inch diameter metal balls. The tank was flattened, crumpled up and hauled off with the soil waste to ERDF. There was no external piping to or from the tank. There was no exposed piping removed during the excavation. All contaminated materials were disposed of at the ERDF.

At the completion of remedial action on December 3, 2002, the site excavation was approximately 123.8 square meters (1,333 square feet) in area, while the former staging pile area was approximately 166.1 square meters (1,787 square feet). The excavation had an average depth of approximately 3.1 meters (10.3 feet). Approximately 420 metric tons (463 tons) of material, including soil and debris, were removed from the 118-C-2 Burial Ground site and transferred to ERDF for disposal. Both the collection tank and loose boron balls exposed during the excavation were removed and transferred to ERDF. There was no piping associated with this remediation.

Code: 118-C-4	Classification: Accepted
Names: 118-C-4; 105-C Horizontal Control Rod Storage Cave	Reclassification: Interim Closed Out (9/11/2003)
Type: Storage	Start Date: 1/1/1950
Status: Inactive	End Date: 1/1/1969

Description: The site has been remediated and interim closed out. The site consisted of two steel-plate tunnels covered with 1.2-meters (4-foot) of soil, gravel and asphalt emulsion. The two tunnels were grouted onto a concrete floor that had three equally spaced 0.6-meter (2-foot) diameter by 0.6-meter (2-foot) deep french drains beneath the centerline of the long axis of the structure. The french drains removed water runoff that could collect between the tunnels in the earth shielding.

Location: The site was located south of the 105-C Reactor Building, within the 105-C exclusion area fence.

Related Sites/Structures: The site was associated with the operation of the 105-C Reactor.

Process Description: The tunnels were used for temporary storage of control rods, and possibly miscellaneous equipment, to allow radioactive decay prior to disposal. Three french drains were located along

the center of the structure floor for the removal of precipitation runoff that could potentially percolate and collect between the tunnels.

Waste Type: Equipment

Waste Description: The tunnel was used for temporary storage for radioactive decay pending subsequent disposal. Some miscellaneous components are currently in the rod cave. The radiation reading at the entrance to the tunnel with the door open was once documented to be 5 millirads/hour.

Closure Info: Interim: The rod cave was demolished as part of decontamination and decommissioning activities in March 2003. The cleanup verification package (CVP) documents completion of remedial action for the soil beneath the former 118-C-4 Horizontal Control Rod Cave. The 118-C-4 waste site consisted of the soils underlying the former 118-C-4, 105-C Horizontal Control Rod Cave (rod cave) building.

Field screening was used to guide the excavation to quickly assess the presence and level of contamination. Field screening for the 118-C-4 site included using a radiological data mapping system survey. The radiological mapping survey was performed over more than 50% of the site excavation surface area. Final cleanup verification samples were collected following variance sampling. Cleanup verification sampling was conducted on May 15, 2003. Each verification sample was a composite formed by combining soil collected at four randomly selected nodes within each sampling area. The final verification samples were submitted to offsite laboratories for analysis using approved EPA analytical methods, as required per the Sampling and Analysis Plan (SAP) (DOE/RL-96-22). The sample design methodology and sample location figure is presented in the calculation briefs for variance analysis and sample design.

Remedial action objectives and goals from the Interim Action Record of Decision for the 100-BC-1, 100-DR-1, and 100-HR-1 Operable Units (ROD) (EPA, 1995) are used for the 118-C-4 site. Although the 118-C-4 site is not identified in the ROD, the remedial action objectives and goals documented in the ROD, and in the Remedial Design Report/Remedial Action Work Plan for the 100 Area (DOE/RL-96-17), are designated for the 118-C-4 site in the Approved Action Memorandum for the 100 B/C Area Ancillary Facilities and the 108-F Building Removal Action (EPA, 1997 CCN 042276). The remedial action goals and objectives were established by the U.S. Environmental Protection Agency (EPA) and the U.S. Department of Energy, Richland Operations Office, in concurrence with the Washington State Department of Ecology.

The selected remedial action for the 118-C-4 site included (1) excavating the site to the extent required to meet specified soil cleanup levels, (2) disposing of contaminated excavation materials at the Environmental Restoration Disposal Facility near the 200 Areas of the Hanford Site, and (3) backfilling the site with clean soil to average adjacent grade elevation. Excavation was driven by remedial action objectives for direct exposure, protection of groundwater, and protection of the Columbia River. For the respective points of compliance, remedial action goals (RAGs) were established to identify radionuclide and nonradionuclide contaminants of concern (COCs) and contaminants of potential concern (COPCs).

Site excavation and waste disposal are complete, and the exposed surfaces have been sampled and analyzed to verify attainment of the RAGs. At the completion of the remedial action, the total excavation was approximately 122 square meters (1,310 square feet) in area with an approximate depth of 0.85 meters (2.8 feet). Approximately 453 metric tons (500 tons) of material from the site were disposed of at the Environmental Restoration Disposal Facility.

Results of the sampling, laboratory analyses, and data evaluations for the 118-C-4 site indicate that all remedial action objectives and goals for direct exposure, protection of groundwater, and protection of the Columbia River have been met.

CVP-2003-00015 demonstrates that remedial action at the 118-C-4 site has achieved the RAOs

and corresponding RAGs established in the ROD and RDR/RAWP. The remaining soils at the 118-C-4 site have been sampled, analyzed, and modeled. The results of this effort indicate that the materials from the 118-C-4 site containing Contaminates of Concerns at concentrations exceeding RAGs have been excavated and disposed of at the ERDF. These results also indicate that residual concentrations will support future land uses that can be represented (or bounded) by a rural-residential scenario and that residual concentrations throughout the site are protective of groundwater and the Columbia River. The 118-C-4 site is verified to be remediated in accordance with the RAOs and RAGs of the ROD and may be backfilled.

Code:	128-C-1	Classification:	Accepted
Names:	128-C-1; 100-C Burning Pit	Reclassification	Interim Closed Out (8/10/2005)
Type:	Burn Pit	Start Date:	
Status:	Inactive	End Date:	
Description:	The site has been remediated and Interim Closed Out. It was a vegetation and ash-covered field strewn with pieces of green, clear, and bright blue glass; small glass bottles, rusted cans, auto parts, assorted scrap metal, chunks of concrete and pieces of asbestos transite.		
Location:	The site was located east of the 105-C Reactor Building and west of the eastern leg of the 100-B/C perimeter road. It was bounded on the north by an export water line and on the east by the export water line soil berm.		
Waste Type:	Misc. Trash and Debris		
Waste Description:	The burning pit received combustible materials such as office wastes, paint wastes, vegetation, and chemical solvents. Large metal items such as hardware, machinery, and other noncontaminated equipment were also deposited at the site.		
Closure Info:	Interim (8/10/2005): Remedial action at the 128-C-1 site was initiated on September 16, 2004, and completed on November 9, 2004. Approximately 8,750 bank cubic meters (11,440 bank cubic yards) were excavated for disposal, including contaminated ash and soil, concrete, tar, mastic, and asbestos containing material (e.g., transite). All excavated material was disposed of at the Environmental Restoration Disposal Facility. A yellow-brown suspect soil material containing chromium and lead was identified and removed during excavation as well as a suspect garnet material contaminated with chromium and likely used for abrasive decontamination activities. No residual anomalous features were noted during a post remediation site inspection performed on November 16, 2004.		

Based on the Work Instruction for Verification Sampling of the Waste Site 128-C-1, Burn Pit Waste Site, statistical sampling was required for this site because the spatial distribution of potential residual soil contamination over the study area (site) was uncertain. The results of verification sampling show that residual contaminant concentrations do not preclude any future uses (as bounded by the rural residential scenario) and allow for unrestricted use of shallow zone soils (i.e., surface to 4.6 meters [15 feet] deep). The results also demonstrate that residual contaminant concentrations are protective of groundwater and the Columbia River. This site does not have a deep zone.

Code:	132-C-1	Classification:	Accepted
Names:	132-C-1; 105-C Reactor Stack Site; 116-C Reactor Exhaust Stack Site	Reclassification	Interim No Action (9/11/2003)
Type:	Burial Ground	Start Date:	1/1/1952
Status:	Inactive	End Date:	1/1/1969

Description: The site has been evaluated and reclassified to "No Action". The stack was demolished with explosives in September 1983. The rubble was pushed into a trench. This waste site is the area that contains the buried rubble from the 105-C Reactor Stack. The stack was 5.1 meters (16.6 feet) in diameter and 61 meters (200 feet) high. It operated from 1952 through 1969, exhausting confinement air from the work areas in the reactor. The area currently appears as a vegetation-free, cobble-covered field adjacent to the 100-C Reactor. It is no longer marked or posted.

Related Sites/ Structures: Air was exhausted from the 105-C Reactor Building and the 117-C Filter Building.

Process Description: Exhaust air flowed through concrete ducts from the 105-C Building directly out the exhaust stack. Following completion of the confinement project in the 1950's, the air was diverted via underground, reinforced concrete ducts to the 117-C Filter Building. After flowing through the filters, the air went through below-grade and above-grade concrete ducts into the exhaust stack.

Waste Type: Demolition and Inert Waste

Waste Description: Sampling of the stack inlet was performed in 1976, using standard smear techniques. Low-level beta and gamma radiation was detected in the stack. It was estimated that the interior of the unit contained approximately 2.8 millicuries of radioactive materials. At the time of demolition (1983), the interior of the reactor stack contained approximately 2 millicuries of radioactive materials.

Closure Info: Interim: Reclassification form 2003-26 and attached supporting information document the site reclassification to No Action.

The stack and foundation were demolished with explosives in September 1983. Rubble from the stack foundation was pushed into the trench using heavy equipment. The remainder of the stack was buried in place. The trench containing the stack rubble and the foundation base were covered with clean fill to a depth of at least 1 meter (3.3 ft). The area was graded to conform with the natural area topography. Five concrete core samples were collected from the stack to establish the radionuclide inventory and depth of contaminant penetration. Core samples were collected at elevations above, below, and approximately equal to the inlet duct. The contamination in the concrete was only in a thin layer of the concrete.

It was determined that excavating the trench for more information presented a greater risk than No Action.

An evaluation of the historical data and RESRAD models supports no action interim closure of the 132-C-1 site.

Code: 132-C-3	Classification: Accepted
Names: 132-C-3; 117-C Filter Building	Reclassification: Interim No Action (9/11/2003)
Type: Process Unit/Plant	Start Date: 1/1/1961
Status: Inactive	End Date: 1/1/1969

Description: The waste site has been evaluated and reclassified to "No Action". Facility demolition and site grading were performed in October and November 1988. The site now resembles a gravel parking lot.

Location: The site was located east of the southeast corner of the 105-C Reactor Building.

Related Sites/ Structures: The building received exhaust fan discharge through an inlet duct from the 105-C Reactor Building and discharged the filtered air through a discharge duct and out the 116-C Stack.

Process Description: The 117-C building was a reinforced concrete structure that was 10.7 meters (35 feet) high, and was constructed such that approximately 8.2 meters (27 feet) was below-grade, and 2.4 meters (8 feet) was above grade. The maximum thickness of the walls and floors was 0.6 meters (2 feet), while the majority was 0.3 meters (1 foot) thick or less. The ducts were made of reinforced concrete with a maximum wall thickness of 30 centimeters (12 inches). The inlet tunnel was approximately 12 meters (40 feet) long, and the exhaust tunnel was approximately 18 meters (60 feet) long.

Waste Type: Demolition and Inert Waste

Waste Description: Total radionuclide inventory in this unit is estimated to be 0.84 millicuries. The radionuclides comprising this inventory are tritium, carbon-14, cobalt-60, cesium-137, strontium-90, europium-154, plutonium-152, and plutonium-239/240. Of these radionuclides, strontium-90 is the most restrictive in the Allowable Residual Contamination Level (ARCL) calculations.

Closure Info: Interim (9/11/2003): The 117-C Filter Building and associated below-grade ductwork were decommissioned and demolished in two phases. Phase I decommissioning work was completed in 1984, including extensive radiological characterization, removal of contaminated equipment, and decontamination. Low-level radioactive waste (e.g., HEPA filters, pumps, frames) removed from the facility was packaged and shipped to the 200 West Area burial grounds for disposal. No asbestos, mercury, or any other nonradioactive hazardous materials were found in the 117-C Facility. Following equipment removal, decontamination consisted mainly of using Masslin cloth to wipe down the vinyl-based coating on the exposed surfaces and, in some cases, by application of a sweeping compound and vacuum cleaner. As part of Phase I activities, a calculation methodology known as "allowable residual contamination level" (ARCL) was used to evaluate the potential radiological dose to a hypothetical, maximally exposed site resident if the site was released for unrestricted use after the demolition and burial in situ of the facility. The ARCL calculation results indicated that the facility was ready for Phase II (demolition) activities. Demolition and site grading were performed in October and November 1988 using conventional heavy equipment. The rubble was buried under at least 1 meter (3 ft) of clean fill, except for rubble from the seal pits, which was buried beneath clean fill at a minimum of 5 meters (16.4 ft) deep.

Using the greatest activities from the pre-demolition characterization data to represent residual contamination levels over 100% of the inner surface area of the former facility, RESidual RADioactivity (RESRAD) modeling was performed in 2003 to support the previous decision to demolish and bury the facility in place. The RESRAD modeling accounts for radioactive decay from 1988 (the year of building demolition) to 2003, and conservatively predicts that the site achieves the dose limits and risk objectives for rural residential land use, groundwater protection, and river protection.

Code: 600-232

Classification: Accepted

Names: 600-232; 100B Electrical Laydown Area

Reclassification: Interim Closed Out (1/27/2005)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site has been remediated and Interim Closed Out. The area has been returned to its natural appearance.

Location: The site was located approximately 200 meters south of 105-C Reactor Building and north of Route 6. The railroad tracks run east-west through the site.

Waste Type: Chemicals

Waste Description: Tar

Waste Type: Equipment

Waste Description: The treated wood ends of the utility poles are categorized as dangerous waste. The site also contained various electrical utility materials such as steel cable, aluminum high-voltage wire, aluminum beams, aluminum poles, and insulators.

Waste Type: Equipment

Waste Description: The aluminum wire beams and poles are potentially recyclable.

Closure Info: Interim (1/27/2005): A cleanup action was initiated on February 19, 2004. Visual observation of the wooden poles indicated that the poles were treated throughout; therefore, the poles were size reduced and removed for disposal to the Environmental Restoration Disposal Facility (ERDF). A layer of soil underlying the poles and in areas with visible tar was excavated and disposed due to the presence of TPH associated with the tar. Remedial action efforts included flagging the visible tar areas and removing the tar by excavating a layer of soil. In areas where the poles appeared to have been treated, a 30 centimeter (12 inch) layer of soil was removed. Where there were isolated, scattered small tar droppings, approximately 8 centimeters (3 inches) of soil was removed. The cleanup action also included a very small area to the east of the 50 x 50 meters (164 x 164 feet) area that contained similar surface contamination. From March 5 through April 16, 2004, a total of 9,005 metric tons (9,905 tons) of debris were sent to the ERDF for disposal. After the debris, tar, and soil were removed, verification samples were collected.

Code: 600-233 **Classification:** Accepted

Names: 600-233; Vertical Pipe Near 100B Electrical Laydown Area **Reclassification:** Interim Closed Out (12/8/2005)

Type: Product Piping **Start Date:**

Status: Inactive **End Date:**

Description: The site has been remediated and Interim Closed Out. Originally the site consisted of one vertical pipe extending 1.5 meters (4.9 feet) from the ground. During remedial activities two small pipes were discovered and added to the site, for a total of three. The area has been revegetated with grasses and native shrubs.

Location: The site was located approximately 250 meters (820 feet) southeast of the 105-C Reactor Building and just north of the railroad tracks, inside the 600-232 waste site.

Waste Type: Equipment

Waste Description: Steel pipelines.

Closure Info: Interim (12/8/2005): Remediation of the waste site consisted of the removal of the 0.064-meter (2.5-inch) steel pipeline via excavation of a 23-meter (75-foot)-long by 0.5-meter (1.6-foot)-deep trench. The eastern end of the pipeline was discovered to terminate with a pipe cap, and the pipeline was removed for disposal at the Environmental Restoration Disposal Facility. No radiation was detected above background levels during excavation, and no staining or anomalous materials were observed. During remedial activities and exploratory excavations, a 0.025-meter (1-inch) pipe segment and a 0.019-meter (0.75-inch) steel pipe were also discovered in the site vicinity, generally laying perpendicular to the 0.064-meter (2.5-inch) pipe. These discovered pipelines contained residual liquids that were drained and characterized

for disposal and subsequently determined to have been used for diesel fuel supply unrelated to the vertical pipe. It was decided that the discovery pipelines posed no adverse risk to human health or the environment and could be abandoned in place.

100-DR-1

Code:	100-D-1	Classification:	Accepted
Names:	100-D-1; Contaminated Drain; Contaminated Storm Drain	Reclassification	Interim Closed Out (1/27/2011)
Type:	Process Sewer	Start Date:	
Status:	Inactive	End Date:	
Description:	The site has been remediated and Interim Closed Out. It was a below grade cement junction box, with inside dimensions of 96.5 by 68.6 centimeters (38 by 27 inches) with a 30.5-centimeter (12-inch) culvert entering from the south side and running towards the south side of the Patrol Road. It had been covered with a 0.9 by 1.1-meter (3 by 3.5-foot) steel cover. The interior of the junction box and pipes were dry and showed no indication of being active. It had been posted with Radiological Contamination Area and Confined Space signs.		
Location:	The site was located in the 100-D Area approximately 50 meters (165 feet) northwest of the northwest corner of the 107-D Retention Basin (site code 116-D-7) and north of the Patrol Road between the 1904-D and 1904-DR Outfall Structures.		
Release Description:	The drain probably became contaminated by effluent water leakage from the nearby 116-D-7 retention basins (WHC-SD-EN-TI-181).		
Related Sites/ Structures:	The site is associated with the 1904-D Outfall Structure and the 116-D-7 Retention Basins.		
Process Description:	The Patrol Road south of the site shows evidence of an area of pavement which was removed and replaced at one time, suggesting that the site may have been used for drainage for the low area south of the Patrol Road. Drawing H-1-8548-DR shows a 30.5-centimeter (12-inch) drain pipe in this location. On the west side of the junction box, a 23-centimeter (9-inch) pipe runs toward the 1904-D Outfall Structure. Site evaluation concluded that the junction box collected runoff and spillage from a culvert under Patrol Road and the Patrol Road ditch, and discharged the collected liquid to a drainage pipe. The drainage pipe led from the junction box to the river, according to the 100-D Area Technical Baseline Report (WHC-SD-EN-TI-181). Operational dates for this site were unknown, but the associated drainage system appeared to have been at least partially removed or abandoned. Leaks were known to have been common from the nearby 116-D-7 (107-D) and 116-DR-9 (107-DR) retention basins, likely resulting in contaminant introduction to the 100-D-1 Contaminated Storm Drain.		
Waste Type:	Process Effluent		
Waste Description:	Leakage of the nearby retention basins and effluent discharge lines may have accumulated in a low area located between the 107-D Retention Basin (116-D-7) and the Patrol Road. The area was drained through a culvert which ran under the Patrol Road to this junction box and then through a 23-centimeter (9-inch) pipe to the 1904-D Outfall. Potential contaminants include Co-60, Cs-137, Cs-137, Eu-152, Eu-154, Eu-155, H-3, Pu-238, 239 and 241, Am-241, Sr-90, U-238, arsenic, chromium, cadmium, lead and sulfates.		
Closure Info:	Interim: Remedial action was performed on April 15, 2009, to remove the diversion box located at the eastern end of the waste site. Remedial action resumed on January 5, 2010 and continued through January 11, 2010 to remove the associated pipelines. Remediation removed all pipes that were associated with the junction box; however, the portion of pipe that was removed did not extend to the river. Process history indicates a portion of the pipe was previously removed; the portion of the pipe that was there appears to lead to the 100-D-65 site, a spillway that does lead to the river shoreline. The two sites were not connected and the potential association could not be confirmed. A section of pipeline associated with 100-D-65 waste site was uncovered during remediation of the 100-D-1 waste site. The 100-D-65 pipeline was left in place and is		

located at the western end of the 100-D-1 waste site excavation. It has been assigned to the 100-D-105 waste site.

A total of approximately 495 bank cubic meters (647 bank cubic yards) of soil and debris were removed and directly loaded for disposal at Environmental Restoration Disposal Facility (ERDF).

Code: 100-D-2	Classification: Accepted
Names: 100-D-2; Lead Sheeting; Solid Waste Site	Reclassification: Interim Closed Out (3/19/2008)
Type: Foundation	Start Date:
Status: Inactive	End Date:

Description: The waste site has been remediated and Interim Closed Out. The site appeared as a small lead sheet covering a concrete pad. It was not marked or posted.

Location: The unit was located southwest of the 185-D Building about 16 meters (52 feet) north of an east/west roadway and 16 meters (52 feet) west of the access road to the west side of the 185 Building.

Process Description: The history of this site is unknown. The 100-D Area Technical Baseline Report refers to this site as an undocumented solid waste site, lead sheeting. The report indicates that the purpose could not be determined by documentation. A review of aerial photographs, of the 100-D Area from 1943 through 19766, show that the 151-D electrical substation and the overhead steam lines were in the vicinity of the 100-D-2 waste site. According to a 1944 drawing of temporary construction facilities in 100-D Area (HEW 1944), a temporary railroad was also located near this site. However, nothing conclusive was found to indicate the purpose of the lead sheet covering the concrete. Lead sheets previously encountered at other areas of the Hanford Site were used as shielding for penetrating radiation or for corrosion protection (i.e., as barriers below sulfuric acid tanks and pumps).

Waste Type: Construction Debris

Waste Description:

Closure Info: Interim: Remediation of the waste site was performed on April 12, 2007. The lead sheet, which was approximately 0.64 centimeters (0.25 inches) thick, was removed and placed in a drum for later treatment and disposal to the Environmental Restoration Disposal Facility (ERDF). The soil surrounding the concrete pad was moved aside to expose the concrete pad for inspection. The concrete was determined to be solid to at least a depth of 0.6 meters (2 feet).

The 100 Area Remedial Action Sampling and Analysis Plan (SAP) specified lead as the contaminant of potential concern (COPC) for the site. Although not COPCs, the expanded list of inductively coupled plasma metals was analyzed and included arsenic, antimony, barium, beryllium, boron, cadmium, total chromium, cobalt, copper, manganese, molybdenum, nickel, phosphorous, selenium, silver, strontium, tin, uranium, vanadium, and zinc. Due to the potential of handling sulfuric acid, mercury and soil pH were also analyzed. Hexavalent chromium was included as a COPC for verification sampling because of its presence as a contaminant in groundwater and the proximity of the site to historical sodium dichromate handling facilities in the 100-D Area.

Verification soil sampling was performed on October 8, 2007, with one soil sample collected adjacent to each side of the concrete pad. Each sample consisted of 20 aliquots of soil distributed across the surface (0 to 0.15 meters [0 to 6 inches]) below the existing ground

surface, combined into one sample representative of each of the four sides. The analytical results indicated the presence of lead up to 578 milligrams/kilogram, exceeding the direct exposure cleanup criteria. Additionally, a sample chipped from the surface of the concrete exhibited lead at a concentration of 32,900 milligrams/kilogram. Therefore, additional excavation to remove the concrete pad and surrounding soil was performed on October 15, 2007. Approximately a total of 216 metric tons (239 US tons) of soil and concrete were excavated and disposed of at ERDF.

Following the October 15th excavation, a second set of verification samples were collected on October 17, 2007, to determine if the remedial action was adequate to support site closure. The analytical results of this sampling indicated that the waste removal action achieved compliance with the RAOs and RAGs. The results of the verification sampling were used to make reclassification decisions in accordance with the TPA-MP-14 procedure in the Tri-Party Agreement Handbook Management Procedures.

The results of verification sampling show that residual contaminant concentrations do not preclude any future uses (as bounded by the rural-residential scenario) and allow for unrestricted use of shallow-zone soils (i.e., surface to 4.6 meters [15 feet] deep). The results also demonstrated that residual contaminant concentrations were protective of groundwater and the Columbia River.

Code:	100-D-3	Classification:	Accepted
Names:	100-D-3; Silica Gel; Solid Waste Burial Ground	Reclassification	Interim No Action (3/12/2009)
Type:	Burial Ground	Start Date:	
Status:	Inactive	End Date:	
Description:	The site has been reclassified to No Action. It was a suspected burial trench that would have received contaminated silica gel from the drying towers in the 115-D/DR building. The site has been surface stabilized and resembles a gravel parking lot.		
Location:	The site is located east/northeast of the south end of the 115-D/DR Building site.		
Process Description:	The site was used to contain contaminated silica gel removed from the drying towers in 115-D. Inert gas (helium and/or carbon dioxide) was circulated through the 105-D Reactor for the purpose of removing moisture. The gas circulation system was housed in the 115-D Building and consisted of blowers, silica gel drying towers, and filters. Silica gel is a granular material made from sodium silicate. It was used as a desiccant to reduce the humidity of the reactor gas and was regenerated by condensing the moisture. The moisture-absorbing efficiency of the silica gel was reduced as the material aged and eventually required removal from the gas circulation system.		
Waste Type:	Abandoned Chemicals		
Waste Description:	The site contains contaminated silica gel removed from drying towers in the 115-D/DR Building.		
Closure Info:	Interim: The supporting information attached to Reclassification form 2008-017 states the exact location of the waste site was not clear. Three locations characteristic of disturbed soil were identified in the vicinity of the reported silica gel burial ground. The suspected primary location for the silica gel burial ground was excavated during remediation of the 116-D-2/116-D-2A waste site. The presence or absence of the silica gel at this location would have been difficult to discern, because the physical characteristics of the silica gel waste resemble soil (dark brown silicate material) and the silica gel will have been expected to have decomposed after more than 40 years in contact with soil moisture.		

Two alternative locations based on geophysical survey data were excavated. Excavation of the two potential locations for the 100-D-3 waste site was completed on October 9, 2007. Both sites were excavated to approximately 4.5 meters (15 ft) below ground surface. No evidence of waste was encountered at either location. The sites were backfilled a few days later to eliminate the safety hazard of an open excavation. Neither location contained evidence of silica gel. Soil samples collected within the excavation did not detect carbon-14 or tritium above the minimum detectable activity (MDA).

Two test pits were excavated on November 5, 2008 to collect verification samples based, on consultation with the Washington Department of Ecology. No radiological contamination was detected during field excavation. Soil samples were collected at four different depths from the center of each of the two potential locations and analyzed for carbon-14 and tritium. Carbon-14 and tritium were not detected above the MDA in any of the soil samples. Therefore, this site has been reclassified to No Action.

Code:	100-D-4	Classification:	Accepted
Names:	100-D-4; 107-D5; 107-D-5; 107-DR Sludge Trench #5; Sludge Trench #5	Reclassification	Interim Closed Out (3/25/1999)
Type:	Trench	Start Date:	1/1/1955
Status:	Inactive	End Date:	

Description: The site has been remediated. The 100-D-4 site was constructed in 1953. This pit and two other identified sludge pits were associated with maintenance cleanout of the 116-DR-9 Liquid Effluent Retention Basin, which was constructed in the late 1940s. The 116-DR-9 Liquid Effluent Retention Basin was used to hold reactor effluent water for a brief period of time, allowing radioactive decay and thermal cooling to occur before the water was discharged to the Columbia River. The sludge pits were built for disposal of sludge removed from the bottom of the effluent retention basin to enable periodic maintenance and repairs to the basin during operation of the 100-D and 100-DR Reactors. There is no indication from available records that this sludge pit directly received any regular and/or high-volume liquid effluent wastes.

The sludge pit consisted of an unlined excavation approximately 630 square meter (6,779 square feet) bottom dimension with moderately sloped side walls. This pit extended to a depth of about 3 meters (10 ft) below grade, and was surrounded by native sandy gravel soils at the base and side walls of the excavation. After shutdown of the 100-D and 100-DR Reactors in the 1970s, subsequent decommissioning of the effluent retention basin and associated sludge pits (as part of the Radiation Area Remedial Action Program) included placement of approximately 2 meters (6 ft) of materials inside the sludge pit. The materials consisted primarily of soil with some miscellaneous debris from the effluent basin and surrounding area. This sequence of material placement was followed by placement of approximately 1 meter (3 ft) of clean soil cover for interim radiological, health, and safety protection purposes. The materials previously placed over the engineered pit structure (original pit excavation) are identified collectively as overburden materials.

Location: The site is located on the east side of the 107-DR Retention Basin, at the southeast corner.

Process Description: In the Spring of 1953, sludge was removed from the bottom of the 107-DR Retention Basin (116-DR-9) to facilitate repairs. The sludge was deposited in this and other nearby excavated trenches.

Waste Type: Sludge

Waste Description: The site received radioactively contaminated sludge from the bottom of the 107-DR Retention Basin. From process knowledge, the waste site contaminants of concern (COCs) identified in the SAP include the following (DOE-RL 1998a): Americium-241, Cobalt-60, Cesium-137, Europium-152, Europium-154, Europium-155, Plutonium-238, Plutonium-239/240, Strontium-90, Hexavalent chromium, and Polychlorinated biphenyls (PCBs).

Closure Info: Interim: Excavation of the 100-D-4 site began on March 18, 1997, by removing the overburden materials and underlying contaminated soil. Based on field screening, overburden materials that were identified as potentially clean were placed in stockpiles for potential use as backfill. Soil and overburden material that were found to be contaminated were disposed of at the ERDF. On March 27, 1997, the excavation had reached the design limits at the base of the engineered structure (El. 135.0 m [443 ft]) and closeout sampling was initiated.

At the completion of the remedial action, the excavation area was approximately 630 square meters (6,779 square feet) at a depth of 2.9 m (9.5 ft), and approximately 1,678 metric tons (1,850 tons) of material from the site were disposed of at the ERDF. The excavation will be backfilled in the near future with clean fill materials to the reference grade of El. 135 m (443 ft). Clean backfill will be taken from overburden and Borrow Pit 21, which is located due south of the 100-D-4 site. The material in the borrow pit has been surveyed in accordance with the SAP (DOE-RL 1998a) and is appropriate for use as backfill. The overburden soil is also appropriate for use as backfill.

Code: 100-D-5	Classification: Accepted
Names: 100-D-5; Undocumented Solid Waste Site; Undocumented Solid Waste Site Near 103-D; Waste Site Near 103-D	Reclassification: Interim Closed Out (4/23/2001)
Type: Burial Ground	Start Date: 1/1/1950
Status: Inactive	End Date: 1/1/1950

Description: The site has been remediated and Interim Closed Out along with 100-D-6, 100-D-48:3 and 100-D-49:3. The waste site was a below grade, concrete structure. The top surface was made up of removable concrete panels. Debris found inside the structure during remediation included pieces of steel, wood, concrete and soil.

Location: The site is located adjacent to the east side of the 103-D Building, north of the 105-D Building.

Related Sites/ Structures: The site is associated with 105-D and 105-DR.

Process Description: The effluent water lines from 105-D and 105-DR join inside a concrete junction box located within the reactor exclusion area at a point north of 105-D and east of 103-D. At the completion of the underground line tie-in phase in 1950, contaminated soil and pipes were also placed in the excavation and buried. Later the steel effluent pipes were replaced with reinforced concrete piping and the junction box was no longer needed.

Waste Type: Demolition and Inert Waste

Waste Description: The waste included reactor cooling water discharge, and debris generated in a 1950 modification. The contaminated soil and debris were removed and taken to ERDF along with 100-D, Group 3 waste site remediation (100-D-48:3, 100-D-49:3, and 100-D-6).

Closure Info: Interim (4/23/2001): The 100-D-48:3, 100-D-49:3, 100-D-5 and 100-D-6 waste sites were remediated together. The CVP document refers to the group of waste sites as the 100-D-48:3/49:3 pipelines site. Remedial action began on October 28, 1999. Excavation of the sites involved removing the overburden materials, the contaminated structure, and underlying

contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Materials that were found to be contaminated were disposed of at ERDF. On July 24, 2000, the excavation was completed. The excavation design depth generally corresponded with the invert elevation of the pipelines.

At the completion of remedial action and removal of the engineered structure, the excavation was approximately 24,574 square meters (264,517 square feet) in area with a maximum depth of approximately 5.7 meters (18.7 feet). Approximately 55,561 metric tons (61,245 tons) of material from the 100-D-48:4 and 100-D-48:3/49:3 pipeline sites disposed of at ERDF. The excavation was backfilled with appropriate materials to match the surrounding surface grade (average elevation of 143.7 meters [471 feet]).

Code:	100-D-6	Classification:	Accepted
Names:	100-D-6; 118-D-4D; Burial Ground 4D; Buried VSR Thimble; Minor Construction Burial Ground #1	Reclassification	Interim Closed Out (4/23/2001)
Type:	Burial Ground	Start Date:	1/1/1953
Status:	Inactive	End Date:	1/1/1953

Description: The site has been remediated and Interim Closed Out along with 100-D-5 structure, 100-D-48:3 and 100-D-49:3 pipelines. The burial grounds were believed to contain solid waste from reactor system upgrades, but later relocated. The 100-D-48:3 and 100-D-49:3 pipelines were installed through this location. No solid waste was documented during the pipeline excavation.

Location: The solid waste burial ground site was located about 300 meters (1000 feet) east of the 105-D Reactor Building, outside the reactor security fence and south of the railroad spur that services the 100-D Area.

Process Description: The burial ground received contaminated thimbles and other solid reactor materials related to the Ball 3X installation project in 1953. It is believed the material was relocated to another burial ground. Two 152 centimeter (60 inch) reactor effluent lines were installed through this location.

Waste Type: Equipment

Waste Description: The burial ground contains contaminated thimbles, radioactive guides and miscellaneous waste removed from the 105-D Reactor during Ball 3X outage. The thimbles were made of aluminum, similar to that used for process tubes. Isotopic analysis of process tubes indicated the presence of manganese-54 and cobalt-60. The thimbles are expected to have similar composition. When buried, the thimbles' exterior surfaces would have been contaminated with activated graphite products and any remaining potassium borate solution from within the thimble tubes.

Closure Info: Interim (4/23/2001): The 100-D-48:3, 100-D-49:3, 100-D-5 and 100-D-6 waste sites were remediated together. The CVP document refers to the group of waste sites as the 100-D-48:3/49:3 pipelines site. Remedial action began on October 28, 1999. Excavation of the sites involved removing the overburden materials, the contaminated structure, and underlying contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Materials that were found to be contaminated were disposed of at ERDF. On July 24, 2000, the excavation was completed. The excavation design depth generally corresponded with the invert elevation of the pipelines.

At the completion of remedial action and removal of the engineered structure, the excavation was approximately 24,574 square meters (264,517 square feet) in area with a maximum depth

of approximately 5.7 meters (18.7 feet). Approximately 55,561 metric tons (61,245 tons) of material from the 100-D-48:4 and 100-D-48:3/49:3 pipeline sites disposed of at ERDF. The excavation was backfilled with appropriate materials to match the surrounding surface grade (average elevation of 143.7 meters [471 feet]).

Code:	100-D-7	Classification:	Accepted
Names:	100-D-7; Undocumented Solid Waste Site	Reclassification	Interim Closed Out (10/10/2011)
Type:	Dumping Area	Start Date:	
Status:	Inactive	End Date:	
Description:	The waste site has been remediated and Interim Closed Out. It contained a variety of debris such as broken concrete, brick, vitrified clay pipe, wood, rebar, various types of metal, lathe turnings, empty oil, solvent, paint cans, tar, and a white substance in two localized areas. The site appeared to have additional debris buried under the surface and there is evidence of disturbance from heavy equipment. Several areas of stressed vegetation and two areas of subsidence were also observed.		
Location:	The site was located northeast of the 128-D-2 Burn Pit and approximately 700 meters (2,300 feet) northeast of the 105-D Reactor Building.		
Process Description:	This site received solid wastes related to the construction and/or operation of the 100-D Area.		
Waste Type:	Misc. Trash and Debris		
Waste Description:	Wastes include vitrified clay pipe, concrete, empty metal containers, glass, metal and wooden debris.		
Closure Info:	Interim (10/10/2011): Remediation at the 100-D-7 waste site was performed between December 22, 2009 and March 6, 2010. Because the 100-D-7 site was a debris site, the excavation focused on the areas identified by geophysics; however, the excavation extent was conducted as necessary to remove waste and debris and remove contaminated soil. The drawings, visual observations radiological surveys, and collection of in process soil samples guided the extent of excavation during remediation. Approximately 24,120 bank cubic meters (31,548 bank cubic yards) of contaminated soil and debris were removed from the 100-D-7 waste site. The soil and debris were staged in a staging pile to the southeast of the 100-D-7 waste site before being loaded for disposal at the Environmental Restoration Disposal Facility (ERDF). The staging area includes a smaller area where topsoil from the waste sites was placed for use on top of the backfill to support successful revegetation as required by the ecological review for the 128-D-2 and 100-D-7 waste sites. All staged waste has been disposed to the ERDF. The staging area was then scraped to remove surface contaminated soil, which was disposed to the ERDF. Only a portion of the 100-D-7 waste site within the WIDS boundary required remediation. An agreement with the Washington State Department of Ecology (Ecology) that the areas within the WIDS boundary where remediation was not performed would become a separate decision unit subject to additional sampling for closeout of the site (WCH 2009c). Eight anomalies were initially identified during the remediation at the 100-D-7 waste site. These consisted of three 3.8-L (1-gal) bottles containing liquid (anomalies 100D-AN-10-001, 100D-AN-10-002, and 100D-AN-10-010); three areas of uncontained solid material: white powder (anomaly 100D-AN-09-082), a pink solid (anomaly 100D-AN-10-003), and a yellow/brown solid (anomaly 100D-AN-10-004). The remaining two anomalies are identified as grease and a metal cylinder (anomalies 100D-AN-10-006 and 100D-AN-10-008). The solid materials were sampled and characterized prior to removal and shipment to ERDF. Anomaly 100D-AN-09-082 was determined by the project engineer to be the same material as anomaly 100D-AN-09-065, so no sample was required for characterization. Anomalies 100D-AN-10-001, 100D-AN-10-002,		

100D-AN-10-010, and 100D-AN-10-008 were overpacked and transferred to the 118-D-3:2 waste site anomaly characterization area.

Code: 100-D-8	Classification: Accepted
Names: 100-D-8; 105-DR Process Sewer Outfall Site; 1907-DR; Undocumented Liquid Waste Site	Reclassification: Interim Closed Out (8/2/2012)
Type: Outfall	Start Date: 1/1/1949
Status: Inactive	End Date: 1/1/1968

Description: The waste site has been remediated and Interim Closed Out. The outfall structure was demolished, leveled, and covered to blend with the riverbank appearance in 1978. The 100-D-8 waste site consists of two components: an upland segment located above the Columbia River ordinary high water mark (OHWM) and a shoreline segment located below the OHWM and above the ordinary low water mark (OLWM).

Location: The site was located upstream of the 181-D Pumphouse on the Columbia River bank.

Process Description: The outfall was constructed in 1949 as a spillway for an emergency discharge for the DR Reactor. It consisted of a 1.8-meter (72-inch) diameter, reinforced concrete pipe. The pipe discharged into a concrete box flume that spilled onto a grouted riprap surface and extended about 13.1 meters (43 feet) beyond the low-water level of the Columbia River. In 1950 it was modified to increase the discharge flow capacity. Historical records indicate the outfall ceased operation in 1968 and was idle until 1978, when it was demolished.

A previously unidentified pipeline encountered during the remedial action excavation was placed in sitecode 100-D-105 for dispositioning.

Waste Type: Water

Waste Description: The outfall was used to discharge waste water from the 183-DR and 190-DR Water Treatment Facilities. Effluents included filter backwash effluent, storm runoff, and chemical discharges resulting from spills or releases relating to water treatment facilities. There is a potential for radioactive contamination from the 100-D Area Cask Pad storm drains.

Closure Info: Interim (8/2/2012): The 100-D-8 waste site consists of two components: an upland segment located above the Columbia River ordinary high water mark (OHWM) and a shoreline segment located below the OHWM and above the ordinary low water mark (OLWM). Confirmatory sampling of the 100-D-8 outfall was not practical due to its location on the embankment of the Columbia River. Because the 100-D-8 outfall was supplied by the 100-D-50 pipelines, the remedial action decision for the waste site was based upon the results of confirmatory sampling of 100-D-50:1, the pipelines that connected directly to the outfall. Because the spillway extended into the Columbia River, the ordinary high water mark (OHWM) was used to partition the remediation of the waste site into an upland segment, located above the OHWM, and a shoreline segment, located below the OHWM.

Remediation of the upland segment of the 100-D-8 waste site was performed from September 29, 2010 through February 17, 2011. In late March 2011, additional soil was removed at the base of the excavation in the area where four in-process soil samples indicated residual contamination exceeding cleanup criteria. On May 18, 2011, high Columbia River flows resulted in river water entering the excavation and presenting a potential fish-stranding hazard to juvenile fish. With Ecology approval, fill material was temporarily placed into the low areas of the excavation until such time that river flows were sufficiently low to resume excavation. In early December 2011, this fill material was removed and the remediation completed. Approximately 118,440 metric tons (52,253 bank cubic meters) of material was excavated,

stockpiled. Approximately 80% was used as backfill material. 21,625 metric tons was disposed at the Environmental Restoration Disposal Facility (ERDF). Approximately 741 metric tons (1,680 bank cubic meters) of material was removed from the shoreline area and disposed at ERDF.

During excavation, one anomaly, a metal box, was discovered at Washington State Plane coordinates N 151596.7, E 572626.3. The anomaly was moved out of the excavation to an area reserved for characterization of the anomaly.

Code: 100-D-9	Classification: Accepted
Names: 100-D-9; 184DA; 184-DA Boiler Oil Tank	Reclassification: Interim Closed Out (8/10/2006)
Type: Storage Tank	Start Date:
Status: Inactive	End Date:

Description: The site has been remediated and Interim Closed Out. A test trench, measuring approximately 10 meters (23.8 feet) long and up to approximately 3.7 meters (12.1 feet) deep (to native soil), was excavated through the former fuel oil tank location. The test excavation confirms that the large (25,000 gallon) tank was previously removed. The waste site consisted of an underground fuel storage tank that was believed to have been removed during general demolition efforts of the 100-D/DR area during 1985 and 1986. It now appears as a cobble-covered field with vegetation on the surface. The elevation at the top of the tank was 141 meters (464.0 feet) and was covered by at least 0.6 meters (2 feet) of overburden.

Location: The tank was located in the 100-D Area, near the northwest corner of the 184-DA Boiler House. It was 55 meters (180 feet) south of Palouse Street and 165 meters (540 feet) east of Puget Avenue.

Related Sites/ Structures: The site is associated with 100-D-97.

Process Description: The tank held fuel oil for the 184-DA Boiler House. It had a capacity of 94,600 liters (25,000 gallons). The fuel tank was installed in 1967 or 1968 to hold oil that fueled the boilers in the 184-DA Steam Generating Building (Boiler House). It was known as the K1-2-1 tank.

Waste Type: Equipment

Waste Description:

Closure Info: Interim: In 1994, a test trench, measuring approximately 10 meters (23.8 feet) long and up to approximately 3.7 meters (12.1 feet) deep (to native soil), was excavated through the former fuel oil tank location. Concrete, metal and wood debris was encountered while digging. The excavation confirms that the tank had been previously removed. Six soil gas probes had been installed around the tank in 1991. No COC/COPCs were detected above the RAGs during confirmatory sampling.

A geophysical survey was performed at the site in October 2005. Ground-penetrating radar, EM31 electromagnetic surveys, and magnetic gradiometer surveys were performed over an extended area surrounding the former tank location. Several linear anomalies were interpreted within the survey area, all trending roughly east-west. The former tank location appeared to be in the "disturbed" area that was near the center of the survey area. Small, relatively subtle geophysical anomalies were noted within this disturbed area, more typical of small debris or metal, but there was clearly no evidence of a large tank the size of 94,600 Liters (25,000 gallons) demonstrated in the scans. The sample results demonstrated that residual contaminant concentrations support unrestricted future use of shallow zone soil (i.e., surface to 4.6 meters

[15 feet]) and contaminant levels remaining in the soil are protective of groundwater and the Columbia River.

Code: 100-D-18 **Classification:** Accepted

Names: 100-D-18; 107-D Sludge Trench #4; 107-D4; **Reclassification** Interim Closed Out (9/26/2000)
107-D-4; Sludge Trench #4

Type: Trench **Start Date:** 1/1/1953

Status: Inactive **End Date:** 1/1/1953

Description: This site has been remediated and was Interim Closed Out on September 26, 2000. It is no longer posted. The trench was excavated in 1953 during repair activities at the 107-D basin. Contaminated sludge from the bottom of the basin were placed into the trench.

Location: The site was located north of and adjacent to the western half of the 107-D Retention Basin (116-D-7), and was directly over the 100-DR Group 2 pipelines.

Related Sites/ Structures: This site was associated with the 116-D-7 Retention Basin.

Process Description: In the spring of 1953, sludge was removed from the bottom of the 107-D Retention Basin (116-D-7) to facilitate repairs. The sludge was deposited in this and other nearby trenches.

Waste Type: Sludge

Waste Description: The site received contaminated sludge from the bottom of the 107-D Retention Basin (116-D-7).

Closure Info: Interim: Excavation of the site involved removing the overburden materials, and underlying contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Materials found to be contaminated were disposed of at Environmental Restoration Disposal Facility (ERDF).

Remedial action at this site began on September 8, 1997 and ended on December 3, 1998 when the excavation reached the design limit at El. 127.8 meters (420.3 feet). During that time, the shallow zone sidewalls were lost to other nearby remedial activities, leaving only the floor of the excavation for the site. At the completion of remedial action, the excavation area was approximately 344.3 square meters (3,706 square feet) with a maximum depth of approximately 6.6 meters (21.7 feet). Approximately 8,700 metric tons (9,592 tons) of material from the site were disposed of at ERDF. Clean backfill was taken from the clean stockpile and from other sources of clean material that have been surveyed in accordance with the SAP and that are appropriate for use as backfill.

Code: 100-D-19 **Classification:** Accepted

Names: 100-D-19; 107-D Sludge Trench #6; Sludge **Reclassification** Interim Closed Out (3/26/2001)
Trench #6

Type: Trench **Start Date:** 1/1/1953

Status: Inactive **End Date:** 1/1/1953

Description: This site has been remediated and Interim Closed Out. It was a trench dug for disposal of sludge from the bottom of the 107-D Retention Basin. The waste was covered by about 1.8 meters (6 feet) of clean fill.

Location: The site was located north of the eastern half of the 107-D Retention Basin (116-D-7).

Process Description: HW-46715 documents that in the Spring of 1953 sludge was removed from the bottom of the 107-D Retention Basin (116-D-7) to facilitate repairs. The sludge was deposited in this and other nearby trenches.

Waste Type: Sludge

Waste Description: The site received radioactively contaminated sludge from the bottom of the 107-D Retention Basin.

Closure Info: Interim: Waste sites 100-D-48:1, 100-D-49:1, 100-D-19 and UPR-100-D-4 were co-located and remediated together. The CVP document referred to the four, combined waste sites as the 100-D-48:1/49:1 Pipeline site. Remedial action at the 100-D-48:1/49:1 Pipelines site began on December 28, 1998. Excavation of the site involved removing the overburden materials, the contaminated structure, and underlying contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Materials that were found to be contaminated were disposed of at ERDF. On July 24, 2000, the excavation reached the design limit. Because remediation of the 100-D-48:1/49:1 Pipelines site required moving an active overhead power line, site remedial action and sampling were conducted in two phases. These separate phases are reflected by the long time period between the start and finish dates for excavation.

The excavation design depth generally corresponded with the invert elevation of the pipelines. At the completion of remedial action and removal of the engineered structure, the excavation was approximately 15,504 square meters (166,800 square feet) in area with a maximum depth of approximately 6.0 meters (20 feet) below ground surface. Approximately 107,266 metric tons (118,241 tons) of material from the D Area pipelines site have been disposed of at the ERDF through July 2000. Cleanup verification sampling began on April 3, 2000, and was finished on August 8, 2000. The ground surface in the vicinity of the site varies with an average elevation of approximately 134.4 meters (441 feet).

Code: 100-D-20	Classification: Accepted
Names: 100-D-20; 107-D Sludge Trench #3; 107-D3; 107-D-3; Sludge Trench #3	Reclassification: Interim Closed Out (3/25/1999)
Type: Trench	Start Date: 1/1/1953
Status: Inactive	End Date: 1/1/1953

Description: This site has been remediated and interim closed out.

The 100-D-20 Sludge Pit was constructed in 1953. This pit and two other identified sludge pits were associated with maintenance clean out of the 116-D-7 Retention Basin, which was constructed in the late 1940s. The 116-D-7 Retention Basin was used to hold reactor effluent water for a brief period of time, allowing radioactive decay and thermal cooling to occur before the water discharged to the Columbia River. The sludge pits were built for disposal of sludge removed from the bottom of the effluent retention basin to enable periodic maintenance and repairs to the basin during operation of the 100-D and 100-DR Reactors. There is no indication from available records that this sludge pit directly received any regular and/or high-volume liquid effluent wastes.

The sludge pit consisted of an approximate 575 square meter (6,189 square feet) unlined excavation (bottom dimension) with moderately sloped side walls, extended to a depth of about 2.1 meters (7 feet) below grade, and the pit was surrounded by native sandy gravel soils at the base and side walls of the excavation. After shutdown of the 100-D and 100-DR Reactors in the 1970s, subsequent decommissioning of the effluent retention basin and associated sludge pits

(as part of the Radiation Area Remedial Action Program) included placement of approximately 2 meters (7 feet) of material within the sludge pit, which consisted primarily of soil with some miscellaneous debris material from the effluent basin and surrounding area. This sequence of material placement was followed by placement of approximately 1 meter (3 feet) of clean soil cover for interim radiological, health, and safety protection purposes. The materials previously placed over the engineered pit structure (original pit excavation) are identified collectively as overburden materials. A Geophysical Survey was done in 1996 that identified this trench as a disturbed zone that may also contain buried construction debris.

Location: The trench was outside of the south perimeter of 107-D. Refer to Hanford Drawing H-1-4046.

Process Description: In the Spring of 1953 sludge was removed from the bottom of the 107-D Retention Basin (116-D-7) to facilitate repairs. The sludge was deposited in this and other nearby trenches.

Waste Type: Sludge

Waste Description: The site received radioactively contaminated sludge from the bottom of the 107-D Retention Basin. From process knowledge, the waste site contaminants of concern (COCs) identified in the SAP include the following: americium-241, cobalt-60, cesium-137, europium-152, europium-154, europium-155, plutonium-238, plutonium-239/240, strontium-90, hexavalent chromium, and polychlorinated biphenyls.

Closure Info: Interim: Excavation of the 100-D-20 (107-D3) Sludge Pit began on July 30, 1997, by removing the overburden materials and underlying contaminated soil. Based on field screening, all overburden materials were found to be contaminated and were disposed of at the Environmental Restoration Disposal Facility (ERDF). On August 1, 1997, the excavation had reached the design limits at the base of the engineered structure (El. 132.3 meters [434 feet]) and closeout sampling was initiated.

At the completion of the remedial action, the excavation area was approximately 575 square meters (6,189 square feet) at a depth of 2.1 meters (7 feet). Approximately 9,710 metric tons (10,700 tons) of material from the site were disposed of at the ERDF. The excavation will be backfilled in the near future with clean fill materials to the reference grade of El. 134.4 meters (441 feet). Clean backfill will be taken from Borrow Pit 21, which is located due south of the 100-D-20 site. The material in the borrow pit has been surveyed in accordance with the 100 Area Remedial Action Sampling and Analysis Plan (SAP) (DOE/RL -96-22) and is appropriate for use as backfill.

Code: 100-D-21	Classification: Accepted
Names: 100-D-21; 107-D2; 107-D-2; 107-DR Sludge Trench #2; Sludge Trench #2	Reclassification: Interim Closed Out (3/25/1999)
Type: Trench	Start Date: 1/1/1953
Status: Inactive	End Date: 1/1/1953

Description: This waste site has been remediated. The 100-D-21 Sludge Pit was constructed in 1953. This pit and two other identified sludge pits were associated with maintenance cleanout of the 116-D-7 Retention Basin, which was constructed in the late 1940s. The 116-D-7 Retention Basin was used to hold reactor effluent water for a brief period of time, allowing radioactive decay and thermal cooling to occur before the water was discharged to the Columbia River. The sludge pits were excavated for disposal of sludge removed from the bottom of the effluent retention basin to enable periodic maintenance and repairs to the basin during operation of the 100-D and 100-DR Reactors. There is no indication from available records that this sludge pit directly received waste on a regular basis or receive a large volume liquid effluent waste.

The sludge pit consisted of an approximate 891 square meter (9,591 square foot) unlined excavation (bottom dimension), with moderately sloped side walls extending to a depth of about 3 meters (10 feet) below grade. The pit was surrounded by native sandy gravel soils at the base and side walls of the excavation. After shutdown of the 100-D and 100-DR Reactors in the 1970s, subsequent decommissioning of the effluent retention basin and associated sludge pits (as part of the Radiation Area Remedial Action Program) included placement of approximately 2 meters (7 feet) of material inside the sludge pit. The materials consisted primarily of soil with some miscellaneous debris material obtained from the effluent basin and surrounding area. After the material was placed into the trench, of approximately 1 meters (3 feet) of clean soil cover was added for interim radiological, health, and safety protection purposes. The waste was later covered with about 1.8 meters (6 feet) of clean fill and marked with an above-ground concrete marker. The soil and material previously placed over the engineered pit structure (original pit excavation) are identified collectively as overburden materials.

Location: The waste site was north of the 100-D reactors, outside the west perimeter of the 107-DR Basin (116-DR-9).

Process Description: In the Spring of 1953 sludge was removed from the bottom of the 107-DR Retention Basin (116-DR-9) to facilitate repairs. The sludge was deposited in this and other nearby trenches.

Waste Type: Sludge

Waste Description: The site received radioactively contaminated sludge from the 107-DR Retention Basin. From process knowledge, the waste site contaminants of concern (COCs) identified in the SAP include the following (DOE/RL-96-22): Americium-241, Cobalt-60, Cesium-137, Europium-152, Europium-154, Europium-155, Plutonium-238, Plutonium-239/240, Strontium-90, Hexavalent chromium, and Polychlorinated biphenyls (PCBs).

Closure Info: Interim: Excavation of the 100-D-21 Sludge Pit (elevation 135.0 meters [443 feet]) began on December 31, 1997, by removing the overburden materials and contaminated soil. Based on field screening, all overburden materials were found to be contaminated and were disposed of at the Environmental Restoration Disposal Facility (ERDF). On January 8, 1998, the excavation had reached the design limits at the base of the engineered structure (El. 131.9 meters [433 feet]) and closeout sampling was initiated. Elevated levels of PCBs were found at this elevation (El. 131.9 meters [433 feet]) and excavation was continued. On March 17, 1998, the final excavation was completed at El. 130.5 meters (428 feet). For the exposed surface excavation, initial confirmation sampling and testing using GEA began on April 29, 1998, to determine the number of final verification samples at the base of the engineered structure. Verification sampling and testing were completed on May 21, 1998 (El. 130.5 meters [14.8 feet]).

At the completion of the remedial action, the excavation area was approximately 891 square meters (9,591 square feet) at a depth of 4.5 meters (14.8 feet). Approximately 9,943 metric tons (10,957 tons) of contaminated soil were disposed at the ERDF. The excavation will be backfilled to the reference grade of El. 135 meters (443 feet). Clean backfill was taken from Borrow Pit 21. The material in the borrow pit was surveyed in accordance with the 100 Area Remedial Action Sampling and Analysis Plan (SAP) (DOE/RL-96-22) and determined to be appropriate for use as backfill.

Code: 100-D-22	Classification: Accepted
Names: 100-D-22; 107-D1; 107-D-1; 107-DR Sludge Trench #1; Sludge Trench #1	Reclassification: Interim Closed Out (3/25/1999)
Type: Trench	Start Date: 1/1/1953
Status: Inactive	End Date: 1/1/1953

Description: The site has been remediated and interim closed out.

Location: The site is outside the east perimeter of the 107-DR Basin.

**Related Sites/
Structures:** The site was associated with the 116-DR-9 Basin.

**Process
Description:** The 100-D-22 Sludge Pit was constructed in 1953. This pit and two other identified sludge pits were associated with maintenance cleanout of the 116-DR-9 Retention Basin, which was constructed in the late 1940s. The 116-DR-9 Retention Basin was used to hold reactor effluent water for a brief period of time, allowing radioactive decay and thermal cooling to occur before the water was discharged to the Columbia River. The sludge pits were excavated for disposal of sludge removed from the bottom of the effluent retention basin to enable periodic maintenance and repairs to the basin during operation of the 100-D and 100-DR Reactors. There is no indication from available records that this sludge pit directly received any regular discharge or high volumes of liquid effluent wastes.

The sludge pit consisted of an approximate 340 square meter (3,658 square feet) unlined excavation (bottom dimension) with moderately sloped side walls, extended to a depth of about 3 meters (10 feet) below grade, and the pit was surrounded by native sandy gravel soils at the base and side walls of the excavation. After shutdown of the 100-D and 100-DR Reactors in the 1970s, subsequent decommissioning of the effluent retention basin and associated sludge pits (as part of the Radiation Area Remedial Action Program) included placement of approximately 2 meters (7 feet) of material inside the sludge pit, which consisted primarily of soil with some miscellaneous debris materials from the effluent basin and surrounding area. The material was covered with approximately 1 meter (3 feet) of clean soil cover for interim radiological, health, and safety protection purposes. The materials previously placed over the engineered pit structure (original pit excavation) are identified collectively as overburden materials.

The site is outside the east perimeter of the 107-DR Basin. Sludge was removed from the bottom of the 107-DR Basin in the spring of 1953 and buried in a nearby trench. The waste was later covered with about 1.8 meters (6 feet) of clean fill and marked with an above-ground concrete marker. The Technical Baseline Report (Carpenter, 1993) says more than one sludge trench was placed in this area. Refer to Hanford Drawing H-1-4046. A Geophysical Survey was done in 1996 that identified the trench as a disturbed zone and contains what appears to be construction debris.

Waste Type: Sludge

**Waste
Description:** The site received radioactively contaminated sludge from the 107-DR Retention Basin. From process knowledge, the waste site contaminants of concern (COCs) identified in the SAP include the following: Americium-241, Cobalt-60, Cesium-137, Europium-152, Europium-154, Europium-155, Plutonium-238, Plutonium-239/240, Strontium-90, Hexavalent chromium, and Polychlorinated biphenyls (PCBs). A small volume of debris containing lead was encountered during remedial action, which was subsequently transported, treated, and disposed of at the ERDF. Because of the presence of lead-containing debris, lead was included as a COC per regulator request.

Closure Info: Interim (3/25/1999): Excavation of the 100-D-22 Sludge Pit began on March 14, 1997, by removing the overburden materials and underlying contaminated soil. Based on field screening, all overburden materials were found to be contaminated and were disposed of at the Environmental Restoration Disposal Facility (ERDF). On March 25, 1997, the excavation had reached the design limits at the base of the engineered structure [elevation 132.4 meters (434 feet)], and closeout sampling was initiated. Because of the presence of polychlorinated biphenyls (PCBs) at that depth, the excavation was extended to 4.8 meters (16 feet) below grade [elevation 130.2 meters (427 feet)] on November 11, 1997, to remove residual PCB contamination. Closeout sampling for PCBs was initiated at this depth.

Waste materials that were excavated, loaded into shipping containers, and disposed of at the ERDF consisted of soils not meeting direct exposure Remedial Action Goals (RAGs) based on field screening results. This included overburden material removed from the southeast portion of the excavation (to construct an equipment access ramp). For the exposed surface of the excavation, initial confirmation sampling and testing using GEA began on June 25, 1997, to determine the number of final verification samples at the base of the engineered structure [elevation 132.4 meters (434 feet)].

At the completion of the remedial action, the bottom of the excavation was approximately 340 square meters (3,658 square feet) at a depth of 4.8 meters (16 feet), and approximately 9,710 metric tons (4,960 loose cubic meters) of material from the site were disposed of at the ERDF. Upon regulatory approval, the excavation will be backfilled with clean fill materials to the reference grade of elevation 135 meters (443 feet). Clean backfill will be taken from Borrow Pit 21 (Gravel Pit 21). The material in the borrow pit was surveyed in accordance with the Sampling and Analysis Plan (SAP) (DOE/RL-96-22) and determined to be appropriate for use as backfill.

Code:	100-D-24	Classification:	Accepted
Names:	100-D-24; 119-D Sample Building Drywell	Reclassification	Interim No Action (9/19/2006)
Type:	French Drain	Start Date:	1/1/1959
Status:	Inactive	End Date:	
Description:	The site has been evaluated and determined to require No Action. It consisted of a drywell that received drainage from a floor drain in the 119-D Sample Building. The sample building has been demolished and the surrounding area has been graded.		
Location:	The drywell was located south of the 119-D Sample Building, between the intake and exhaust ducts for the 117-D Filter Building.		
Related Sites/ Structures:	The drywell was associated with the 119-D Sample Building.		
Process Description:	The 119-D Sample Building was situated over the intake and exhaust ducts to the 117-D Filter Building and was used to sample effluent gases and particulates. The drywell was connected to the 119-D Sample Building by a 5-centimeter (2-inch) drainage pipe buried at least 0.9 meters (3 feet) below grade. A 1.9-centimeter (3/4-inch) drain line from the building's evaporative cooler connected into the 5-centimeter (2-inch) drain line near the southern edge of the building.		
Waste Type:	Process Effluent		
Waste Description:	The drywell received effluent from the building's evaporative cooler. It was likely that the floor drain also received sample waste and janitorial waste since the building had no other drains or connections to the process sewer system.		
Closure Info:	Interim: Per discussion with the Washington Department of Ecology and review of historical drawings, the coordinates for the drywell were determined to be incorrect. Accordingly, one test pit was excavated at the drywell location shown on historic drawings. The drywell was not identified in the test pit area. The excavation proceeded to 3 meters (10 feet) below ground surface (bgs), at the suspected location of the former base of the drywell. One soil grab sample was collected at 2.4 meters (8 feet) bgs, and another grab sample was collected at 3 meters (10 feet) bgs. The drywell could not be located, so soil samples were collected at the location of the former drywell. It was presumed the dry well had been removed at the time of 119-D building decommissioning and demolition activities.		

Code: 100-D-25 **Classification:** Accepted
Names: 100-D-25; Unplanned Release - 116-DR-9 (107-DR) Retention Basin Leaks **Reclassification:** Interim Closed Out (1/6/2000)
Type: Unplanned Release **Start Date:** 1/1/1951
Status: Inactive **End Date:**

Description: This unplanned release site was remediated with the 116-DR-9 Retention Basin and Interim Closed Out. It was done under the provisions of the Interim Action Record of Decision for "proximity sites." Leakage from the 107-DR Basin was confined at the south end and beneath the basin. The contamination could not be separately distinguished in the gravel retention basin area.

Location: The release was located in the soil beneath the 107-DR Retention Basin.

Release Description: The release involved leakage from the 107-DR Basin.

Related Sites/Structures: The leak was associated with 116-DR-9 (the 107-DR Retention Basin).

Process Description: The basin had a history of leaking and underwent repairs in 1951. Waste site 100-D-25 documents leakage beneath the basin and outside the south end of the basin where the neoprene seals in the concrete floor failed and the pipes pulled away from the basin walls at the retention basin inlet. The contamination could not be distinguished from other contaminated soil.

Waste Type: Water

Waste Description: Radioactively contaminated effluent was released to the site.

Closure Info: Interim: The 116-DR-9 retention basin received cooling water effluent from the 105-DR Reactor from 1950 until 1965. After the 105-D Reactor was deactivated in 1965, the basin remained active until 1967 as part of the 105-D Reactor effluent system. Leakage occurred as unplanned releases in 1951 beneath the basin and outside the south end of the basin when seals in the concrete floor of the basin failed and the pipes pulled away from the basin walls at the retention basin inlet. The basin had a history of leaking and underwent repairs in 1951. Waste site 100-D-25 documents leakage beneath the basin and outside the south end of the basin where the neoprene seals in the concrete floor failed and the pipes pulled away from the basin walls at the retention basin inlet. The contamination could not be distinguished from other contaminated soil. It was remediated with the 116-DR-9 Retention Basin under the provisions for "proximity sites."

Excavation began on October 21, 1997, by removing the overburden materials and underlying contaminated soil. Overburden materials, which were contaminated, were disposed at the ERDF. On December 28, 1998, the excavation had reached the design limits below the base of the engineered structure (El. 130.25 m [427.35 ft]) and cleanup verification sampling was initiated. At the completion of the remedial action, the excavation area floor was approximately 16,352 square meters (176,013 sq ft) at a depth of 4.75 meters (15.6 ft), and approximately 201,519 metric tons (222,122 tons) of material from the site were disposed of at the ERDF. The excavation will be backfilled in the near future with clean fill materials to the reference grade of El. 135.0 meters (443 ft).

Contaminated soil associated with the process effluent pipelines was not removed completely, but deferred for final remediation with the pipeline waste sites. The 116-DR-9 sidewall areas that are adjacent to future pipeline excavation areas were not sampled as part of the basin cleanup verification effort. These areas will be sampled and verified clean as part of the effluent

pipeline remediation efforts.

Code: 100-D-29	Classification: Accepted
Names: 100-D-29; Effluent Line Leak #2	Reclassification: Interim Closed Out (3/25/2010)
Type: Unplanned Release	Start Date: 1/1/1951
Status: Inactive	End Date:

Description: The waste site is a release from the 107-DR Retention Basin. It is possible that the location of the 100-D-29 waste site is documented in WIDS and SIS may not be the actual trench location. The location description was developed using historical sketches and a 1954 photograph. Contamination associated with the release shown in this photograph may have had some portion removed during remediation of the 107-DR Retention Basin (CVP-99-00006). As a result of this new information, a discovery site, 100-D-102, was created in WIDS.

In 1952, the trench was covered by about 1.2 meters (4 ft) of clean fill material upon completion of the basin repair. A portion of the contaminated soils from this leak was used as fill around the pipeline anchor blocks south of the basin. All contaminated soil was then covered by 0.61 meters (2 ft) of soil. Contaminated soil associated with the pipeline anchor blocks would have been removed with the 100-D-49, 100-DR Effluent Cooling Water Pipelines.

Location: The site was located southwest of the 107-DR Basin and southeast of the 107-D Retention Basin. The site is centered at Washington State Plane coordinates, E573832.364, N152132.5.

Release Description: In 1951, extensive leakage of effluent water was detected above ground about 46 meters (105 feet) southeast of the 107-D Basin. A maximum dose rate of 50 millirads/hour was observed at the surface. Two excavations were made to investigate the leakage, but the effluent continued to seep to the surface. In the fall of 1952, there was extensive leakage of effluent water at the inlet end of the 107-DR retention basin (116-DR-9) that was caused by the pipes pulling loose from the basin wall from thermal expansion and contraction of the steel pipelines and the concrete basin wall. In order to repair the leak, a trench was dug to receive the leaked effluent so that repairs could be made. This trench formed a "dogleg" adjacent to the southwest corner of the basin towards the southeast end of the 107-D Retention Basin. (UNI-946).

Related Sites/Structures: The site was related to the 107-DR Retention Basin and 100-D-102.

Process Description: The site was a planned release to allow for the repair of the 107-DR Retention Basin.

Waste Type: Soil

Waste Description: Contaminants of potential concern (COPCs) include: Co-60, Cs-134, Cs-137, Eu-152, Eu-154, Eu-155, H-3. The waste is contaminated soil from a temporarily constructed drainage trench. In the fall of 1952, readings up to 100 mRad/hr were detected at the surface of the mud leaking from the retention basin. The source is radioactive process effluent from the 107-D Retention Basin.

Closure Info: Interim: Remedial activities at the 100-D-29 waste site began on March 7, 2008, and were completed on March 28, 2008. The excavation was approximately 4.6 meters (15 ft) deep and 30 meters (100 ft) long with variable width. Approximately 5,200 bank cubic meters (BCM) (6,800 bank cubic yards [BCY]) of soil was excavated and stockpiled adjacent to the site. Historical information indicated that residual radiological contamination associated with the 100-D-29 waste site would be expected to be encountered at approximately 1.2 meters (4 feet) below ground surface (bgs) because the trench that formed the site had been backfilled with 1.2 meters (4 feet) of soil. However, no field detectable contamination was encountered during

excavation to this depth. The excavation was extended to a depth of 4.6 meters (15 feet), but still no radiological contamination was detected. A limited amount of concrete and pipe debris was encountered during excavation; this was loaded directly into a container for disposal at the ERDF. The concrete and pipeline were likely remnants of a north-south fire protection pipeline and associated valve box in the area. Historic drawings show north-south and east-west 15.20-cm (6-in.) fire protection pipelines (included in the 100-D-63 waste site) in the area.

Based on field observations, in combination with hand-held radiological surveys that indicate the absence of detectable contamination associated with a retention basin leak, it is suspected that the contaminated soil associated with the 100-D-29 site was removed in the fall of 1952 and used as backfill for the anchor blocks at the 107-DR Retention Basin inlet.

Code:	100-D-30	Classification:	Accepted
Names:	100-D-30; 185-D; 185-D Sodium Dichromate Trench & Sump; 189-D Decontamination & Demolition Project; 190-D Sodium Dichromate Soil Contamination	Reclassification	Interim Closed Out (6/3/2015)
Type:	Unplanned Release	Start Date:	1/1/1945
Status:	Inactive	End Date:	1/1/1967
Description:	The waste site has been remediated and Interim Closed Out. It was sodium dichromate contaminated soil. The site was discovered during the 185-D/189-D Subgrade Decontamination and Demolition Project. Sodium dichromate contamination was discovered in the soil along the entire length of the sodium dichromate trench of 185-D. The contamination was visually identified on concrete surfaces and on large cobbles in the soil by the yellow film on the surface. Photographs were taken during demolition of the subgrade structures and show the contaminated soil and structures.		
Location:	The site was located in 100-D Area, between the 105-D Building and the 183-D Building.		
Release Description:	Sodium dichromate solutions were released from cracks or expansion joints in the "chromate trench" which extended the length of the 185-D Building.		
Related Sites/ Structures:	The site was related to 100-D-104, 190-D, 185-D, 189-D and 105-D process piping.		
Process Description:	The process water flowed from the 185-D Building into the refrigeration room of the 189-D Building where it was chilled and pumped into either or both of the two center storage tanks in the 190-D Building. Four large 6.62E+06-liter (1.75E+06-gallon) steel storage tanks were provided in the 190-D High Bay to supply water to the coolant pumps for the reactor. The water in the tanks was treated with sodium dichromate to inhibit corrosion in the reactor process tubes. The 185-D Building contained sodium dichromate mixing tanks and a pipe trench to convey sodium dichromate solutions to be added to the large 190-D Storage Tanks.		
Waste Type:	Chemical Release		
Waste Description:	Sodium dichromate contamination is in the soil.		
Closure Info:	Interim (6/3/2015): Initial remediation of the 100-D-30 waste site was performed from June 2006 through May 2007. Approximately 7,000 cubic meters (9,160 cubic yards) of stained soil, stained concrete, and construction debris were excavated, stockpiled next to the trench, and later disposed to the Environmental Restoration Disposal Facility (ERDF). Waste characterization and in-process samples were collected, as necessary, to support waste designation and to assist in guiding the excavation. Stained concrete observed at the site was		

sampled (J12XP5) to support waste designation. The depth of this excavation was approximately 3.5 meters (12 ft) below ground surface. During the 100-D-30 waste site excavation, pieces of vitrified clay pipe were encountered at the southwestern corner of the 100-D-30 site.

On December 20, 2007, additional soil removal was performed in this southwestern area of the 100-D-30 waste site to a depth of approximately 3 meters (10 ft) below grade. Yellow staining was observed after this further excavation. Four judgmental in-process soil samples were collected in this area (J163Y2, J163Y3, J163Y4, and J163Y5) with one sample (J163Y2) having 20.6 mg/kg of hexavalent chromium. On March 4, 2008, additional excavation was performed to open up the area for further evaluation. As the excavation progressed deeper, the soil became more stained. Excavation continued on March 5, 2008, to a depth of 6 meters (20 ft). The excavation was halted at this depth because any deeper would require an engineering design. In the center of the excavation, an area approximately 3 sq. meters (30 sq. ft) was observed with yellow and brown staining.

From January through February 2009, and June 2009, five investigation boreholes were drilled at the 100-D-30 waste site to support evaluation of the vertical distribution of chromium contamination in the vadose zone below the waste site. Soil samples were collected at discrete depth intervals and analyzed for chromium (total) and hexavalent chromium. Chromium contamination was observed at depth in the vadose zone directly below the french drain location (C6450), indicating probable transport of contamination associated with releases from the french drain and the outdoor sodium dichromate storage tank. Based on historical information, field observations, and sample results, it appeared that the residual contamination identified in the southwestern corner of the 100-D-30 waste site was associated with the acid neutralization french drain, sulfuric acid tank, and sodium dichromate tank that were located outside of the 190-D Complex. Therefore, it was decided to identify this location as a discovery site, 100-D-104, for further remediation because it was not associated with the 185-D Building sodium dichromate trench that was the source of the chromium contamination identified as the 100-D-30 waste site. Based on the concentrations of hexavalent chromium found at depth in the boreholes, a decision was made to perform additional remediation of the 100-D-30 waste site and to combine this remediation with the 100-D-104 waste site remediation.

Additional remediation was performed from October 2011 through March 2012, to a depth of approximately 15.2 meters (50 ft) below surface grade and was identified as the Tier II excavation. A Tier III excavation design was developed for continuing the remediation of these sites to an approximate depth of 24 meters (78.7 ft) below surface grade, with the bottom of the excavations at an elevation of approximately 119 meters (390.4 ft) above mean sea level, the estimated elevation of groundwater. The Tier III excavation began in February 2013 and excavation to groundwater was completed in March 2014. Due to the depth and size of these excavations, considerable layback and overburden soil was removed and stockpiled for use as clean backfill or was placed into previously remediated waste sites (120-D-1, 100-D-73, and 100-D-76). Overburden/layback material was also placed in the south portion of the decommissioned 183-D clearwell.

An agreement with Ecology allowed use of clean concrete and steel debris encountered during remediation to be used as backfill for a portion of the 100-D-30/100-D-104 waste sites. The agreement specified that the excavation would be backfilled with soil approximately 3 meters (10 ft) above groundwater. Clean concrete and steel debris could be placed over the soil to an elevation that would be no closer than 6.1 meter (20 ft) from the backfilled surface grade for the waste sites.

In accordance with this evaluation, the verification sampling results support a reclassification of the 100-D-30 and 100-D-104 waste sites to Interim Closed Out. Contamination above direct exposure levels was not observed in the shallow zone soils and is concluded to not exist in deep

zone soils. Institutional controls to prevent uncontrolled drilling or excavation into the deep zone of the sites are not required.

Code:	100-D-31	Classification:	Accepted
Names:	100-D-31; 100-D Water Treatment Facilities Underground Pipelines	Reclassification	Interim Closed Out (5/28/2015)
Type:	Process Sewer	Start Date:	1/1/1944
Status:	Inactive	End Date:	1/1/1994

Description: All of the subsites have been remediated and Interim Closed Out, so the parent site is also Interim Closed Out. It encompassed the underground pipelines that transported pre-reactor, non radioactive cooling water and process sewer waste streams from water treatment, reactor, and laboratory facilities. The waste site was divided into twelve subsites. All of these underground pipelines are pre-reactor (pre-irradiation) disposal and supply lines, except for the septic sewer lines that fed the 1607-D2 septic tank. All the underground process sewer and drainage piping from water treatment facilities to the 116-D-5 Outfall Structure were part of this site. The site also included the feed pipelines from the 117-DR Filter Building and the 105-DR Reactor to the 100-D-13 septic system.

Excluded from this site are the process sewer system that were constructed specifically for the 100-DR Reactor facilities, chemical supply, or underground effluent pipelines designed to dispose of radionuclide contaminated effluents and pipelines within buildings. These systems were addressed as separate WIDS sites. This site does not include the 120-D-1 Ponds, used for process sewer discharge from 1977 to 1994 or the 116-D-5 Outfall Structure and river pipelines. This site also does not include raw river water, potable water, or fire system water pipelines, or the sodium dichromate underground supply pipelines (100-D-56).

Location: The pipelines were located in the 100-D Area near the 182-D reservoir and 183-D filter building. The system is a network of underground piping that extends from water treatment facilities, the 184-D Powerhouse, 1700-D Series Buildings, and 105-D Reactor to the 116-D-5 Outfall and septic tank 1607-D2. These pipelines run from the 182-D Reservoir, the 183-D Basins, Filters and Clearwells, the 185-D, 183-DR, and 189-D/190-D Complex, the 105-D Reactor and the 1700-D Series Buildings. The individual subsites contain the pipeline descriptions and associated structures.

Related Sites/ Structures: The process sewer received effluent from the following facilities: 182-D, 183-D, 183-DR, 184-D, 185-D 186-D, 189-D, 190-D, 105-D, and 107-D. It is also associated with the 100-D-72; 183-D Acid Facility and underground lines.

Process Description: Water was taken from the Columbia River and treated extensively to purify it prior to use as reactor cooling water. The cooling water was used in a single pass operation and once through the reactor cores became irradiated reactor effluent. The non-radioactive overflows, process cooling waste streams, filter backwashes, and floor drains in non-radioactive areas became process sewer wastes. The 107-D Retention Basin discharged to the process sewer pipeline just prior to the 116-D-5 Outfall Structure.

Waste Type: Water

Waste Description: The waste consists of steel piping, concrete, and soil (if contaminants are present). The water supply and process sewer drain pipelines at the 100-D Area provided for the supply and disposal of non-radioactive streams generated in water treatment and water treatment laboratories facilities and powerhouse operations. Known chemical additions to reactor cooling water included aluminum sulfate (alum) with excess hydrated calcium oxide, sulfuric acid, chlorine, and sodium dichromate. Water pH was maintained near 7.5, free chlorine residual at about 0.2 milligrams per liter, and sodium dichromate was added at a rate of about 2 milligrams

per liter. The sodium dichromate product pipelines would have much greater concentrations. Sodium chloride was also used to regenerate water softeners in both water treatment and powerhouse operations.

The process sewer system connected to the 116-D-5 (1904-D Outfall) at the Columbia River shoreline. (The outfall and the pipelines that carried the process sewer and reactor effluent to the center bottom of the river are addressed by separate Waste Information Data System [WIDS] entries.) Specific chemicals and potential radionuclide content is currently unknown. However, minor amounts of radionuclide, chemical, and mercury contamination may be present in process sewer lines from the 185-D and 189-D/190-D complex as a result of laboratories once located in these now demolished facilities.

This Site has the Following SubSites:

Code: 100-D-31:1
Names: 100-D-31:1; 1607-D2 Septic Sewer Pipeline

Code: 100-D-31:2
Names: 100-D-31:2; 1700-D Series Buildings Septic Sewer Pipelines

Code: 100-D-31:3
Names: 100-D-31:3; 105-D Sewer Pipelines

Code: 100-D-31:4
Names: 100-D-31:4; 190-D Sewer Pipelines

Code: 100-D-31:5
Names: 100-D-31:5; 188-D Ash Disposal Pipeline

Code: 100-D-31:6
Names: 100-D-31:6; 184-D Powerhouse Sewer Pipelines

Code: 100-D-31:7
Names: 100-D-31:7; 116-D-5 and D-Pond Sewer Pipeline

Code: 100-D-31:8
Names: 100-D-31:8; 183-D and 186-D Northern Sewer Pipelines

Code: 100-D-31:9
Names: 100-D-31:9; 183-D and 186-D Process Sewer Pipelines

Code: 100-D-31:10
Names: 100-D-31:10; 182-D North Septic Sewer Pipeline

Code: 100-D-31:11
Names: 100-D-31:11; 182-D and 183-D Sewer Pipelines

Code: 100-D-31:12
Names: 100-D-31:12; 183-D West Process Sewer Pipelines

Code: 100-D-31:1	Classification: Accepted
Names: 100-D-31:1; 1607-D2 Septic Sewer Pipeline	Reclassification: Interim Closed Out (10/7/2010)
Type: Process Sewer	Start Date:
Status: Inactive	End Date:

Description: Subsite one has been remediated. It consisted of approximately 390 meters (1,280 ft) long, 8 inch diameter segment of vitrified clay pipe (VCP) and was located to the northwest of the 105-

D Reactor. The pipelines fed into the 1607-D2:3 portion of the 1607-D2 sanitary sewer system, which was the main sanitary sewer servicing the 100-D Area. It transported sewage from manhole S-21D north to manhole S-25D. This system of sewers was active from 1944 to 1994 and received effluent from the 1700-D, 1704-D, 1707-D, 1707-DA, 1708-D, 1713-D, 1716-D, 1717-D, 1718-D, 1719-D, 1722-D, 182-D, 183-D, 184-D, 185-D, 186-D, 189-D, 190-D, and 108-D Buildings.

Several miscellaneous pipelines crossing over the subsites were encountered during excavation, however, none were connected. All of these pipelines will be addressed separately.

Location: The 100-D-31:1, 1607-D2 septic sewer pipeline subsite is located northwest of the 105-D Reactor in the 100 DR-1 Operable Unit. The 100-D-31:1 waste site addresses a portion of the 1607-D2 septic sewer pipeline that transported sewage from manhole S-21D north to manhole S-25D.

Process Description: The 100-D-31:1 waste site addresses a portion of the 1607-D2 septic sewer pipeline that transported sewage from manhole S-21D north to manhole S-25D. The 1607-D2 septic system received waste from the 1700-D, 1704-D, 1707-D, 1707-DA, 1708-D, 1713-D, 1716-D, 1717-D, 1718-D, 1719-D, 1722-D, 182-D, 183-D, 184-D, 185-D, 186-D, 189-D, 190-D, and 108-D buildings. The 100-D-3 1:1 pipeline transported sewage from all these buildings.

Waste Type: Not Specified

Waste Description: The waste consists of steel piping, concrete, and soil.

Closure Info: Interim: Remedial action was performed between June 18, 2007 and July 17, 2008. The final excavation depths for 100-D-31:1 and 100-D-31:2 were approximately 5 meters (16 ft) and 3 meters (9 ft), respectively. The excavation resulted in approximately 2,512 bank cubic meters (BCM) (3,287 bank cubic yards [BCY]) of material removed for disposal at the Environmental Restoration Disposal Facility, including 756 m (2,480 ft) of pipe.

Analytical results show that residual contaminant concentrations support future land uses that can be represented (or bounded) by a rural-residential scenario. The results also demonstrate that residual contaminant concentrations support unrestricted future use of shallow zone soil (i.e., surface to 4.6 m [15 ft]) and contaminant levels remaining in the soil are protective of groundwater and the Columbia River.

Several miscellaneous pipes crossing over the 100-D-31:1 and 100-D-31:2 pipelines were encountered during excavation. None of the crossing pipelines were connected to the 100-D-31:1 or 100-D-31:2 pipelines. Most of these pipelines are associated with the 100-D-63 clean water pipelines and will be addressed with that site. Four pipelines were not previously identified. These four pipelines were added into 100-D-105 for dispositioning.

The SubSite is Part Of:

Code: 100-D-31

Names: 100-D-31; 100-D Water Treatment Facilities Underground Pipelines

Code: 100-D-31:2

Classification: Accepted

Names: 100-D-31:2; 1700-D Series Buildings Septic Sewer Pipelines

Reclassification: Interim Closed Out (10/7/2010)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: Subsite two has been remediated. It consisted of multiple segments of 8 in. diameter VCP, totaling approximately 365 m (1,200 ft) in length. This pipeline segment was located between manholes S-19D and S-21D, where it connected with the 100-D-31:1 pipeline. The pipelines from the following 1700-D Buildings were connected to the 100-D-31:2 pipelines: 1704-D, 1707-D, 1707-DA, 1713-DD, 1717-D, 1719-D, and 1722-D. Another portion of the pipeline was located east of manhole S-21D and serviced the 108-D Building.

For specific remedial information see subsite 1.

Process Description: The 100-D-3 1:2 waste site is the 1700-D Series Buildings septic sewer pipelines. This pipeline segment is located between manholes S-19D and S-21D, where it connected with the 100-D-31:1 pipeline. The 1700-D Series Buildings were non-radiological offices, shops, change rooms, and equipment storage. The septic sewer pipelines from the following 1700-D Buildings were connected to the 100-D-31:2 pipeline: 1704-D, 1707-D, 1707-DA, 1713-DD, 1717-D, 1719-D, and 1722-D. Another portion of the 100-D-31:2 septic sewer pipeline was located east of manhole S-21D and serviced the 108-D Building.

Waste Type: Not Specified

Waste Description: The waste consists of steel piping, concrete, and soil.

Closure Info: Interim: Remedial action was performed between June 18, 2007 and July 17, 2008. The final excavation depths for 100-D-31:1 and 100-D-31:2 were approximately 5 meters (16 ft) and 3 meters (9 ft), respectively. The excavation resulted in approximately 2,512 bank cubic meters (BCM) (3,287 bank cubic yards [BCY]) of material removed for disposal at the Environmental Restoration Disposal Facility, including 756 m (2,480 ft) of pipe.

Analytical results show that residual contaminant concentrations support future land uses that can be represented (or bounded) by a rural-residential scenario. The results also demonstrate that residual contaminant concentrations support unrestricted future use of shallow zone soil (i.e., surface to 4.6 m [15 ft]) and contaminant levels remaining in the soil are protective of groundwater and the Columbia River.

Several miscellaneous pipes crossing over the 100-D-31:1 and 100-D-31:2 pipelines were encountered during excavation. None of the crossing pipelines were connected to the 100-D-31:1 or 100-D-31:2 pipelines. Most of these pipelines are associated with the 100-D-63 clean water pipelines and will be addressed with that site. Four pipelines were not previously identified. These four pipelines were added into 100-D-105 for dispositioning.

The SubSite is Part Of:

Code: 100-D-31

Names: 100-D-31; 100-D Water Treatment Facilities Underground Pipelines

Code: 100-D-31:3

Classification: Accepted

Names: 100-D-31:3; 105-D Sewer Pipelines

Reclassification: Interim Closed Out (8/10/2011)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This subsite has been remediated and Interim Closed Out. It included three process and septic sewer lines, one from the northwest corner and the other from the west side of the 105-D Reactor building. The pipelines ran west and northwest respectively to a 91.44 cm (36 in) line which led in to the 205.74 cm (6 ft 9 in) square line that connected to the 116-D-5 outfall. Also included were the vitrified clay sewer lines from the 108-D and 1728-D facilities that joined

with the 20 cm (8 in) vitrified clay sewer pipe that is part of 100-D-31:1.

Location: The 105-D sewer pipelines transported waste from the 105-D Reactor north to manhole S-21D. The subsite also included pipelines that transported waste east from manhole S-13D toward the 1607-D2 septic tank. The 100-D-31:3 subsite includes the septic sewer pipelines exiting the northwest and east sides of the 108-D Building, and the septic sewer pipeline under the 1728-D Building.

Process Description: The 100-D-31:3 and 100-D-31:4 process sewer pipelines actively transported process and septic sewer waste beginning in 1944 and continuing through 1994. During reactor operations from 1944 through 1967, the nonradioactive overflows, process cooling waste streams, filter backwashes, and floor drainage in nonradioactive areas became process sewer wastes that flowed through these pipelines.

Waste Type: Not Specified

Waste Description: The waste consists of steel piping, concrete, and soil.

Closure Info: Interim: Remedial action at the 100-D-31:3 pipeline subsite was performed between May 19 and December 30, 2008. Excavation continued until all debris and contamination associated with the pipeline structure had been removed. The site was excavated to depths ranging from approximately 2.8 to 3.5 meters (9.1 to 11.3 ft), resulting in approximately 7,687 bank cubic meters (BCM) (10,070 bank cubic yards [BCY]) of soil and piping/debris being removed for disposal at the Environmental Restoration Disposal Facility (ERDF). In addition, approximately 785 linear meters (2,576 linear ft) of pipe were removed. This piping was sorted within the excavation and direct loaded for disposal at ERDF.

In July 2008, during the 100-D-31:3 remedial excavation, a 55 gallon metal drum was uncovered. The drum was confirmed to be empty and managed as non-hazardous waste.

Several pipelines not previously identified were found during the excavation. They were added to 100-D-105 for dispositioning.

The SubSite is Part Of:

Code: 100-D-31

Names: 100-D-31; 100-D Water Treatment Facilities Underground Pipelines

Code: 100-D-31:4

Classification: Accepted

Names: 100-D-31:4; 190-D Sewer Pipelines

Reclassification: Interim Closed Out (8/15/2011)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. The pipelines in this subsite and the buildings they serviced are:

185-D Development lab - A 121.94 cm (48 in) process sewer line exited the north side, connecting to a line heading west to a 205.74 cm (6 ft 9 in) line to the 116-D-5 outfall. Also, a 15 cm (6 in) vitrified clay pipe (VCP) sewer exited the north side and joined with an east-west 20 cm (8 in) VCP (W-71477).

186-D - A 30.48 cm (12 in) process sewer line exited the northeast corner, heading east to the 205.74 cm (6 ft 9 in) line to the 116-D-5 outfall. Also, a 15 cm (6 in) vitrified clay pipe (VCP) sewer exited the north side and joined with an east-west 20 cm (8 in) VCP.

189-D - A 137 cm (54 in) process sewer line exited the north side and joined with an east-west 205.74 cm (6 ft 9 in) line to the 116-D-5 outfall (W-71477).

190-D High Bay - A 45.7 cm (18 in) process sewer line exited the north side to a 91.4 cm (36 in) line, which headed west to the 205.74 cm (6 ft 9 in) line to the 116-D-5 outfall, and a 76.2 cm (30 in) process sewer line exited the north side to a 91.4 cm (36 in) line, which headed west to the 205.74 cm (6 ft 9 in) line to the 116-D-5 Outfall. Three other lines exited the east side of the 190-D Building, a 10 cm (4 in) cast iron, a 15 cm (6 in) cast iron, and a 15 cm (6 in) VCP, which all joined into a 15 cm (6 in) VCP that headed north to the west side of the 1728D Building location (M-1904-D, Sheet 5, W-71477).

Location: The pipelines were located on the north side of the 105-D Reactor. The 190-D sewer pipelines are bound by manholes S-13D and P-9D to the east and manholes S-11D and P-13D to the west. The pipelines included in this subsite transported process sewer waste from the northeast corner of the 186-D Building and the north side of the 190-D Building toward the 116-D-5 outfall. The pipelines also transported the septic sewer waste from the 185-D, 186-D, and 190-D Buildings.

Related Sites/ Structures: The 100-D-31:4 subsite pipelines also intersect with pipelines from 100-D-31:8 and 100-D-31:9 at junction box P-13D and manhole S-11D, respectively.

Process Description: The 100-D-31:3 and 100-D-31:4 process sewer pipelines actively transported process and septic sewer waste beginning in 1944 and continuing through 1994. During reactor operations from 1944 through 1967, the nonradioactive overflows, process cooling waste streams, filter backwashes, and floor drainage in nonradioactive areas became process sewer wastes that flowed through these pipelines.

Waste Type: Not Specified

Waste Description: The waste consists of steel piping, concrete, and soil.

Closure Info: Interim: Remedial action at the 100-D-31:4 pipeline subsite was performed between September 26, 2008 and December 10, 2009. Excavation continued until all debris and contamination associated with the pipeline structure had been removed. The site was excavated to depths ranging from approximately 3.8 to 4.8 meters (13 to 16 ft), resulting in approximately 9,883 BCM (12,926 BCY) of soil and piping/debris being removed for disposal at ERDF. In addition, approximately 636 linear meters (2,087 linear ft) of pipe were removed. This piping was sorted within the excavation and direct loaded for disposal at ERDF.

During the remediation of the 100-D-31:4 pipeline subsite, it was determined that construction of a land bridge spanning a portion of the open excavated waste site trench was needed to support both existing and future pump-and-treat lines prior to cleanup verification statistical sampling. Three focused samples were collected within 1 meter (3.3 ft) of either side of the pipeline along the center line of the bottom of the 100-D-31:4 excavation. No results from focused sampling within the area of the then proposed land bridge were above shallow zone remedial action goals (RAGs). The Washington State Department of Ecology approved construction of the land bridge in a regulatory agreement titled "Soil Bridges at 100-D-31:4 and 100-D-31:8" (Ecology 2009). The 100-D-31:4 land bridge was constructed on November 16, 2009.

The SubSite is Part Of:

Code: 100-D-31

Names: 100-D-31; 100-D Water Treatment Facilities Underground Pipelines

Code: 100-D-31:5 **Classification:** Accepted
Names: 100-D-31:5; 188-D Ash Disposal Pipeline **Reclassification** Interim Closed Out (10/22/2009)
Type: Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The waste site has been remediated and Interim Closed Out. It was a 133 meter (370 foot) long, 20 centimeter (8 inch) diameter, underground ashcolite pipeline. The pipeline was located in a north-south orientation between the former 184-D Powerhouse and the 188-D Ash Disposal Basin. From the powerhouse, the 100-D-31:5 pipeline carried a slurry of coal ash and raw river water. The slurry was transported to the ash disposal basin (126-D-1 waste site).

Location: The pipeline was located in a north-south orientation between the former 184-D Powerhouse and the 188-D Ash Disposal Basin.

Waste Type: Not Specified

Waste Description: The waste consists of steel piping, concrete, and soil.

Closure Info: Interim (10/22/2009): Remedial action at the 100-D-3 1:5 site was performed between October 29, 2007, and January 9, 2008. There were no anomalies or stained soil discovered during remediation. Coal ash is present throughout the site, however, no ash or sediment was found to be present in the pipeline. The 100-D-31:5 site was excavated to between 1.2 meters (4 ft) and 1.7 meters (5.5 ft) below grade. Approximately 852 bank cubic meters (BCM) (1,114 bank cubic yards [BCY]) of soil (overburden) was removed and stockpiled for evaluation for use as clean backfill. Approximately 94 BCM (123 BCY) of material was disposed at the Environmental Restoration Disposal Facility, including removal of the pipeline.

No anomalies or stained soil were discovered during remediation. Ash is present throughout the site. No ash or sediment was found to be present in the pipeline.

The SubSite is Part Of:

Code: 100-D-31
Names: 100-D-31; 100-D Water Treatment Facilities Underground Pipelines

Code: 100-D-31:6 **Classification:** Accepted
Names: 100-D-31:6; 184-D Powerhouse Sewer Pipelines **Reclassification** Interim Closed Out (8/24/2009)
Type: Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The 100-D-3 1:6 subsite is the part 100-D water treatment facilities underground pipelines associated with the 184-D Powerhouse. It included a total of four pipeline segments, two on the north side and two on the south side of the 184-D Powerhouse.

Location: The 100-D-31:6 subsite is located northwest of the 105-D Reactor.

Waste Type: Not Specified

Waste Description: The waste consists of steel piping, concrete, and soil.

Closure Info: Interim: Remedial action at the subsite was performed between November 1, 2007 and March 5, 2008. The site was excavated between 1.5 meters (5 ft) and 3.3 meters (7.5 ft) below grade resulting in approximately 371 bank cubic meters (BCM) (485 bank cubic yards [BCY]) of

material removed for disposal at the Environmental Restoration Disposal Facility, including approximately 329 meters (1,079 ft) of vitreous clay pipe encased in concrete and 30 meters (98 ft) of steel pipe. Approximately 2,440 BCM (3,192 BCY) of soil (overburden) was removed and stockpiled for evaluation as clean backfill. No anomalies or stained soil were discovered during remediation; however, coal ash and asphalt is present throughout the site. Several miscellaneous pipes crossing over the 100-D-31:6 pipeline were encountered during excavation.

The SubSite is Part Of:

Code: 100-D-31

Names: 100-D-31; 100-D Water Treatment Facilities Underground Pipelines

Code: 100-D-31:7

Classification: Accepted

Names: 100-D-31:7; 116-D-5 and D-Pond Sewer Pipeline **Reclassification** Interim Closed Out (10/14/2010)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This subsite has been remediated and Interim Closed Out. Subsite 7 consisted of pipelines that transported process and septic sewer waste from 1944 to 1994. This subsite is a 2-meter (6-foot, 9-inch) square pipeline that collected sewer wastes from smaller pipelines and fed into the 116-D-5 Outfall. The pipeline was approximately 480 meters (1,574.9 feet) long. The 116-D-5 and D-Pond sewer pipeline transported process waste from junction box P-13D north to the 116-D-5 outfall. It also includes the vitrified clay pipe transporting septic sewer waste from manhole S-19D to manhole S-18D.

Location: The 100-D-31:7 was a north-south oriented pipeline located north-northwest of the 105-D Reactor.

Waste Type: Not Specified

Waste Description: The waste consists of steel piping, concrete, and soil.

Closure Info: Interim: Remedial action at the subsite began on November 5, 2007, and continued through December 9, 2009. The site was excavated to depths between 12 meters (40 ft) and 16 meters (53 ft) below grade, resulting in approximately 17,684 bank cubic meters (BCM) (23,130 bank cubic yards [BCY]) of material removed for disposal at the Environmental Restoration Disposal Facility, including approximately 480 meters (1,574.9 ft) of pipe.

An intact 946.3-L (250-gal) motor oil storage tank was found within the layback of the subsite approximately 12 meters (36 ft) west of the demolished 1716-D Building. The tank was identified as being associated with the 130-D-1, 1716 Gasoline Storage Tank waste site. While relocating the tank from the excavation layback, approximately 95 L (25 gal) of oily fluid spilled onto a polyethylene-lined containment area set up adjacent to the tank. No oily fluid was released to the soil. The oily fluid was sampled for waste designation, and the remaining fluid was absorbed using soil from the surrounding area. The soil underneath the tank was inspected and it was determined that no leaks had occurred from the pipe that was previously attached to the tank. All piping associated with the 130-D-1 waste site that was present within the 100-D-31:7 excavation was removed. The remaining soil will be assessed during remediation and closeout verification of the 130-D-1 waste site.

The SubSite is Part Of:

Code: 100-D-31

Names: 100-D-31; 100-D Water Treatment Facilities Underground Pipelines

Code: 100-D-31:8 **Classification:** Accepted
Names: 100-D-31:8; 183-D and 186-D Northern Sewer Pipelines **Reclassification** Interim Closed Out (10/18/2011)
Type: Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The 100-D-31:8 subsite has been remediated and Interim Closed Out. The pipeline subsite is made up of piping from two different sewer systems (sanitary and process sewers).

The following segment is part of the process sewer:

A 121.94 cm (48 in) reinforced concrete process sewer line exited the north side of the 183-D filter Plant connecting to a 144.2 cm (4 ft 9 in) concrete box pipe, connecting to a 167.54 cm (5 ft 6 in) concrete box pipeline, to the 205.74 cm (6 ft 9 in) line (100-D-31:7) to the 116-D-5 outfall (W-72688).

The following segment is part of the sanitary sewer:

A 20 cm (8 in) vitrified clay pipeline north of the 183-D filter plant and extending to above the northwest side of the 186-D Building and connecting to the 100-D-31:4 pipeline (W-72688).

Location: The 183-D and 186-D northern sewer pipelines were vitrified clay pipelines and reinforced concrete pipelines exiting the north side of the 183-D Building, as well as an east-west trending reinforced concrete pipeline segment from junction box P-3D to junction box P-13D.

Process Description: The process sewer received raw water drained from the 182-D and 183-D Buildings (also see 100-D-31:11). It also received waste water (backwash) and overflow from the 183-D Filter Building. The sanitary sewer received septic waste from the lavatories in the 182-D Pump House and 183-D Headhouse. The 100-D-31:8 pipelines received waste water from the north side of the 182-D and 183-D Buildings via the 100-D-31:11 pipelines at junction box P-3D and at a second connection along the same pipeline approximately 23 meters (75 ft) to the south. The 100-D-31:8 pipelines also received waste water from the 186-D Building where it connected to the 100-D-31:9 pipelines at manhole S-10D and at a second connection approximately 18 meters (59 ft) to the east along the same pipeline. The waste water was then transferred to the 100-D-31:4 and 100-D-31:7 pipeline segments at junction box P-13D and manhole S-11D.

Waste Type: Not Specified

Waste Description: The waste consists of steel piping, concrete, and soil.

Closure Info: Interim (10/18/2011): Remedial action at the 100-D-31:8 subsite was performed between August 27, 2009, and May 19, 2010. The final excavation depth for 100-D-31:8 was approximately 9 meters (30 ft). The excavation resulted in approximately 5,732 bank cubic meters (BCM) (7,509 bank cubic yards [BCY]) of material removed for disposal at the Environmental Restoration Disposal Facility (ERDF). Additionally, approximately 535 meters (1,755 ft) of pipe were removed and disposed at the ERDF. Approximately 61,330 BCM (80,432 BCY) of soil (overburden) was removed and stockpiled for evaluation for use as clean backfill. It was determined that construction of a land bridge spanning a portion of the open excavated waste site trench was needed to support both existing and future pump-and-treat lines prior to conducting cleanup verification sampling. Demolition of the 1902-D water tank in January 2010 resulted in a rust stained area outside the north end of the 100-D-31:8 waste site footprint. This area was sampled (J19KJ9) for characterization and the impacted surface soils were disposed of at ERDF.

Remedial action at the 100-D-31:9 subsite was performed between July 15, 2009, and April 21, 2010. The final excavation depth for 100-D-31:9 was approximately 7 meters (23 ft). The excavation resulted in approximately 11,485 BCM (15,045 BCY) of material removed for disposal at the ERDF. Additionally, approximately 705 meters (2,313 ft) of pipe were removed and disposed of at the ERDF. Approximately 44,310 BCM (57,957 BCY) of soil (overburden) was removed and stockpiled for evaluation for use as clean backfill.

Remedial action at the 100-D-31:10 subsite was performed between December 29, 2009, and January 27, 2010. The final excavation depth for 100-D-31:10 was approximately 3 meters (10 ft). The excavation resulted in approximately 208 BCM (272 BCY) of material removed for disposal at the ERDF. Additionally, approximately 128 meters (420 ft) of pipe were removed and disposed of at the ERDF. Approximately 1,544 BCM (2,019 BCY) of soil (overburden) was removed and stockpiled for evaluation for use as clean backfill. A section of the 100-D-31:10 pipeline subsite is located adjacent to the active 199-D5-33 groundwater monitoring well. To maintain structural integrity of the well, a section of the 100-D-31:10 pipeline subsite was left in place, resulting in a small land bridge measuring 11 meters (36 ft) wide across the pipeline excavation.

On February 22, 2010, confirmatory sampling was being conducted at 100-D-63, test pit 16. While backfilling the test pit, a piece of concrete fell out of the backhoe bucket and struck one of the two pipes in the bottom of the excavation, causing it to leak water. Approximately 37,854 liters (10,000 gal) of raw water was released due to this pipeline not being properly valved off from the export water line. It was unclear whether the leaking water was contaminated. Therefore, Ecology agreed to allow the released raw water to be pumped to the 100-D-31:9 open excavation. In the course of isolating and draining the export water pipeline to repair the leak, and waiting for approval to pump the water into the 182-D Reservoir, approximately 7,571 liters (2,000 gal) of water was pumped from the export water line to the 100-D-31:8 subsite. On March 2, 2010, in-process samples were collected from inside the water release footprints within the 100-D-31:8 and 100-D-31:9 open excavations. On March 4, 2010, an in-process soil sample (J19L76) was collected from outside the water release footprint in 100-D-31:9. Based on results of these in-process samples, the soil from within the water release footprints was placed in the associated overburden stockpiles. These in-process sample results were not used for determining the interim closure.

The SubSite is Part Of:

Code: 100-D-31

Names: 100-D-31; 100-D Water Treatment Facilities Underground Pipelines

Code: 100-D-31:9

Classification: Accepted

Names: 100-D-31:9; 183-D and 186-D Process Sewer Pipelines

Reclassification: Interim Closed Out (10/18/2011)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The 100-D-31:9 subsite has been remediated and Interim Closed Out. The pipeline subsite is made up of piping from two different sewer systems (sanitary and process sewers).

The segments following are part of the process sewer:

A 106.7 cm (42 in) process sewer line exiting the east side of the 183-D Building to junction P-6D, connecting to a 114.3 cm (3 ft 9 in) pipe (100-D-31:8) that runs north to a 167.54 cm (5 ft 6 in) line, east to the 205.74 cm (6 ft 9 in) line (100-D-31:7) to the 116-D-5 outfall (W-72883, W-

72688, W-72689). Two concrete process sewer pipes running north-south between the 183-D and 186-D buildings, joining together to a 114 cm (45 in) reinforced concrete box pipe between the buildings (M-1904-D, Sheet 5).

The following segments are part of the sanitary sewer:

A 20 cm (8 in) vitrified clay pipeline that exited the east side of the 183-D building and turned north to connect to the 100-D-31:8 pipeline (W-72883). Two 15 cm (6 in) vitrified clay pipelines that exited the west side of the 186-D Building and connected to the 20 cm (8 in) main sanitary sewer trunkline (W-71788).

Location: The 183-D and 186-D process sewer pipelines extend from the intersection with the reinforced concrete pipe (RCP) exiting the east side of the 183-D Building to manhole S-10D, and comprise the vitrified clay pipe and RCP pipelines from the east side of the 183-D Building and the west side of the 186-D Building.

Process Description: The process sewer received waste water from floor drains and sumps in the 183-D Pump House and drainage from the 186-D Waste Acid Reservoir (120-D-2). A portion of the process sewer was the main trunk line that was downstream from the 100-D-50:7 pipeline. The sanitary sewer received septic waste from the lavatories in the 183-D Pump House and 186-D Demineralization Plant. The 100-D-31:9 pipelines consist of the 183-D and 186-D Buildings process sewer. These pipelines exit the buildings at various locations, including a 24 inch diameter vitrified clay pipe (VCP) and a 54 inch diameter concrete pipe, which are continuations of the 100-D-50:7, 183DR Head House Floor Drain and Catch Basins Pipelines, and connect to the 100-D-31:8 pipelines at manhole S-10D and a second connection approximately 18 meters (59 ft) to the east along the same pipeline.

Waste Type: Not Specified

Waste Description: The waste consists of steel piping, concrete, and soil.

Closure Info: Interim (10/18/2011): Remedial action at the 100-D-31:8 subsite was performed between August 27, 2009, and May 19, 2010. The final excavation depth for 100-D-31:8 was approximately 9 meters (30 ft). The excavation resulted in approximately 5,732 bank cubic meters (BCM) (7,509 bank cubic yards [BCY]) of material removed for disposal at the Environmental Restoration Disposal Facility (ERDF). Additionally, approximately 535 meters (1,755 ft) of pipe were removed and disposed at the ERDF. Approximately 61,330 BCM (80,432 BCY) of soil (overburden) was removed and stockpiled for evaluation for use as clean backfill. It was determined that construction of a land bridge spanning a portion of the open excavated waste site trench was needed to support both existing and future pump-and-treat lines prior to conducting cleanup verification sampling. Demolition of the 1902-D water tank in January 2010 resulted in a rust stained area outside the north end of the 100-D-31:8 waste site footprint. This area was sampled (J19KJ9) for characterization and the impacted surface soils were disposed of at ERDF.

Remedial action at the 100-D-31:9 subsite was performed between July 15, 2009, and April 21, 2010. The final excavation depth for 100-D-31:9 was approximately 7 meters (23 ft). The excavation resulted in approximately 11,485 BCM (15,045 BCY) of material removed for disposal at the ERDF. Additionally, approximately 705 meters (2,313 ft) of pipe were removed and disposed of at the ERDF. Approximately 44,310 BCM (57,957 BCY) of soil (overburden) was removed and stockpiled for evaluation for use as clean backfill.

Remedial action at the 100-D-31:10 subsite was performed between December 29, 2009, and January 27, 2010. The final excavation depth for 100-D-31:10 was approximately 3 meters (10 ft). The excavation resulted in approximately 208 BCM (272 BCY) of material removed for disposal at the ERDF. Additionally, approximately 128 meters (420 ft) of pipe were removed

and disposed of at the ERDF. Approximately 1,544 BCM (2,019 BCY) of soil (overburden) was removed and stockpiled for evaluation for use as clean backfill. A section of the 100-D-31:10 pipeline subsite is located adjacent to the active 199-D5-33 groundwater monitoring well. To maintain structural integrity of the well, a section of the 100-D-31:10 pipeline subsite was left in place, resulting in a small land bridge measuring 11 meters (36 ft) wide across the pipeline excavation.

On February 22, 2010, confirmatory sampling was being conducted at 100-D-63, test pit 16. While backfilling the test pit, a piece of concrete fell out of the backhoe bucket and struck one of the two pipes in the bottom of the excavation, causing it to leak water. Approximately 37,854 liters (10,000 gal) of raw water was released due to this pipeline not being properly valved off from the export water line. It was unclear whether the leaking water was contaminated. Therefore, Ecology agreed to allow the released raw water to be pumped to the 100-D-31:9 open excavation. In the course of isolating and draining the export water pipeline to repair the leak, and waiting for approval to pump the water into the 182-D Reservoir, approximately 7,571 liters (2,000 gal) of water was pumped from the export water line to the 100-D-31:8 subsite. On March 2, 2010, in-process samples were collected from inside the water release footprints within the 100-D-31:8 and 100-D-31:9 open excavations. On March 4, 2010, an in-process soil sample (J19L76) was collected from outside the water release footprint in 100-D-31:9. Based on results of these in-process samples, the soil from within the water release footprints was placed in the associated overburden stockpiles. These in-process sample results were not used for determining the interim closure.

The SubSite is Part Of:

Code: 100-D-31

Names: 100-D-31; 100-D Water Treatment Facilities Underground Pipelines

Code: 100-D-31:10

Classification: Accepted

Names: 100-D-31:10; 182-D North Septic Sewer Pipeline **Reclassification** Interim Closed Out (10/18/2011)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This subsite has been remediated and Interim Closed Out. It was a 20 cm (8 in) vitrified clay process sewer pipeline, about 144 meters long.

Location: The pipeline exited the northwest corner of the 182-D Building, turns east and continues on the north side of the 182 Building, and ends at manhole P-20D.

Process Description: The process sewer receives drainage from the 182-D Inlet House No. 1. The structure contains the main level control cone valves for the inlet pipes to the reservoir. The second floor contains the chlorinating equipment for treating the incoming water (HAN-10970, Volume 3). The 100-D-31:10 pipelines consist of the 182-D Building septic sewer. These pipelines exit the building at various locations and connect to the 100-D-31:11 pipelines at manhole P-20D. The 100-D-31:11 pipelines transported the waste water to the 100-D-31:8 pipelines at the junction box P-3D and a second connection along the same pipeline approximately 23 meters (75 ft) to the south.

Waste Type: Not Specified

Waste Description: The waste consists of steel piping, concrete, and soil.

Closure Info: Interim (10/18/2011): Remedial action at the 100-D-31:8 subsite was performed between August 27, 2009, and May 19, 2010. The final excavation depth for 100-D-31:8 was

approximately 9 meters (30 ft). The excavation resulted in approximately 5,732 bank cubic meters (BCM) (7,509 bank cubic yards [BCY]) of material removed for disposal at the Environmental Restoration Disposal Facility (ERDF). Additionally, approximately 535 meters (1,755 ft) of pipe were removed and disposed at the ERDF. Approximately 61,330 BCM (80,432 BCY) of soil (overburden) was removed and stockpiled for evaluation for use as clean backfill. It was determined that construction of a land bridge spanning a portion of the open excavated waste site trench was needed to support both existing and future pump-and-treat lines prior to conducting cleanup verification sampling. Demolition of the 1902-D water tank in January 2010 resulted in a rust stained area outside the north end of the 100-D-31:8 waste site footprint. This area was sampled (J19KJ9) for characterization and the impacted surface soils were disposed of at ERDF.

Remedial action at the 100-D-31:9 subsite was performed between July 15, 2009, and April 21, 2010. The final excavation depth for 100-D-31:9 was approximately 7 meters (23 ft). The excavation resulted in approximately 11,485 BCM (15,045 BCY) of material removed for disposal at the ERDF. Additionally, approximately 705 meters (2,313 ft) of pipe were removed and disposed of at the ERDF. Approximately 44,310 BCM (57,957 BCY) of soil (overburden) was removed and stockpiled for evaluation for use as clean backfill.

Remedial action at the 100-D-31:10 subsite was performed between December 29, 2009, and January 27, 2010. The final excavation depth for 100-D-31:10 was approximately 3 meters (10 ft). The excavation resulted in approximately 208 BCM (272 BCY) of material removed for disposal at the ERDF. Additionally, approximately 128 meters (420 ft) of pipe were removed and disposed of at the ERDF. Approximately 1,544 BCM (2,019 BCY) of soil (overburden) was removed and stockpiled for evaluation for use as clean backfill. A section of the 100-D-31:10 pipeline subsite is located adjacent to the active 199-D5-33 groundwater monitoring well. To maintain structural integrity of the well, a section of the 100-D-31:10 pipeline subsite was left in place, resulting in a small land bridge measuring 11 meters (36 ft) wide across the pipeline excavation.

On February 22, 2010, confirmatory sampling was being conducted at 100-D-63, test pit 16. While backfilling the test pit, a piece of concrete fell out of the backhoe bucket and struck one of the two pipes in the bottom of the excavation, causing it to leak water. Approximately 37,854 liters (10,000 gal) of raw water was released due to this pipeline not being properly valved off from the export water line. It was unclear whether the leaking water was contaminated. Therefore, Ecology agreed to allow the released raw water to be pumped to the 100-D-31:9 open excavation. In the course of isolating and draining the export water pipeline to repair the leak, and waiting for approval to pump the water into the 182-D Reservoir, approximately 7,571 liters (2,000 gal) of water was pumped from the export water line to the 100-D-31:8 subsite. On March 2, 2010, in-process samples were collected from inside the water release footprints within the 100-D-31:8 and 100-D-31:9 open excavations. On March 4, 2010, an in-process soil sample (J19L76) was collected from outside the water release footprint in 100-D-31:9. Based on results of these in-process samples, the soil from within the water release footprints was placed in the associated overburden stockpiles. These in-process sample results were not used for determining the interim closure.

The SubSite is Part Of:

Code: 100-D-31

Names: 100-D-31; 100-D Water Treatment Facilities Underground Pipelines

Code: 100-D-31:11

Classification: Accepted

Names: 100-D-31:11; 182-D and 183-D Sewer Pipelines

Reclassification Interim Closed Out (5/28/2015)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: 100-D-31:11 was remediated and Interim Closed Out with the 100-D-72 waste site. The subsite included piping from sanitary and process sewers. The subsite included short sections of the pipes that exited the 182-D and 183-D facilities, but were left in place because of difficulty in excavating too close to the foundation walls. The process sewer segments added to this subsite include:

A 91.4 cm (36 inch) line that exited northeast side of the 182-D Reservoir and extended east to the 121.9 cm (48 inch) process sewer line, ending up at the 116-D-5 outfall (W-71520).

A 106.7 cm (42 inch) process sewer line exits the east corner of the building to the 121.9 cm (48 in) line heading to the 116-D-5 outfall (W-72845).

A 20 cm (8 inch) vitrified clay sewer pipe exits the northeast corner of the 182-D building and connects to the 91.4 cm (36 in) line mentioned above (W-72835).

A 45.5 cm (18 inch) vitrified clay pipe exited the west side of 183-D and connected to the 121.9 cm (48 in) north-south concrete pipe between the 182-D and 183-D Buildings.

Some sanitary sewer segments added to this subsite. They include a 15 cm (6 inch) vitrified clay sewer pipe that exited the east side of the 182-D building and joined with the 20 cm (8 inch) vitrified clay pipe located between the 182-D and 183-D buildings (H-1-26378).

Location: The 182-D and 183-D sewer pipelines transported process sewer and septic sewer waste from the east side of the 182-D building and the west side of the 183-D Building. The subsite is bounded to the south by the concrete manhole, and it is bounded at the north end by junction box P-3D. Additional short segments, transferred from other subsites, are connected to the 183-D and 182-D Buildings.

Related Sites/ Structures: The pipelines are associated with the 100-D-72; 183D Acid Facility.

Process Description: The process sewer received raw water drained from the suction wells in the 182-D Pump House; raw water from the 182-D Reservoir overflow and drainage from the 182-D Inlet House No. 1 (100-D-31:10). The sanitary sewer received septic waste from the lavatories in the 182-D Pump House and 183-D Headhouse.

Waste Type: Not Specified

Waste Description: The waste consists of steel piping, concrete, and soil.

Closure Info: Interim (5/28/2015): Remediation of the 100-D-72 waste site was conducted concurrently with the 100-D-31:11 and 100-D-31:12 waste sites. Excavation of these waste sites began on December 3, 2013, and was completed on February 26, 2014. Approximately 10,585 bank cubic meters (13,845 bank cubic yards) of soil, piping debris, steel, concrete, and vitrified clay pipe were disposed to the Environmental Restoration Disposal Facility (ERDF). The depth of the resulting excavation varied from 2.7 meters (8.9 ft) to approximately 5.7 meters (18.7 ft) below ground surface. The remaining below grade structure of the previously addressed 100-D-59, French Drain was completely removed during this remedial action. No anomalies were observed. Overburden was staged to the east of the excavation in the area of the former 183-D Filter Building. Potentially contaminated soils were staged to the southwest of the excavation in a multiple waste site staging pile area (SPA).

The area south of Paddock St (part of 100-D-72) was backfilled in March 2014 to provide access for well drilling activities in this area.

A portion of the 100-D-72 pipeline site was removed during excavation of the 100-D-100 hexavalent chromium stained soil site. The 100-D-100 site excavation removed the entire vadose zone and is approximately 26 meters (85 ft) deep. Because the 100-D-100 excavation is

much deeper than the 100-D-72 pipeline, verification sampling and further evaluation of the 100-D-72 waste site in the area of the 100-D-100 excavation was determined to be unwarranted.

The SubSite is Part Of:

Code: 100-D-31

Names: 100-D-31; 100-D Water Treatment Facilities Underground Pipelines

Code: 100-D-31:12

Classification: Accepted

Names: 100-D-31:12; 183-D West Process Sewer Pipelines

Reclassification Interim Closed Out (5/28/2015)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: Subsite 12 was remediated and Interim Closed Out with waste site 100-D-72. It was the 183-D west side process sewer pipelines that transported treated cooling water from eight process sewer pipelines exiting the west side of the 183-D Building. The pipeline subsite was bounded on the north end by junction box P-2D.

Location: These pipeline segments were located between the west side of the 183-D Building and the junction box P-2D to the north.

Related Sites/ Structures: The pipelines are associated with the 100-D-72; 18D Acid Facility.

Process Description: The 100-H-31:12 process sewer pipelines transported treated cooling water from eight process sewer pipelines that exiting the west side of the 183-D Building.

Waste Type: Not Specified

Waste Description: The waste consists of steel piping, concrete, and soil.

Closure Info: Interim (5/28/2015): Remediation of the 100-D-72 waste site was conducted concurrently with the 100-D-31:11 and 100-D-31:12 waste sites. Excavation of these waste sites began on December 3, 2013, and was completed on February 26, 2014. Approximately 10,585 bank cubic meters (13,845 bank cubic yards) of soil, piping debris, steel, concrete, and vitrified clay pipe were disposed to the Environmental Restoration Disposal Facility (ERDF). The depth of the resulting excavation varied from 2.7 meters (8.9 ft) to approximately 5.7 meters (18.7 ft) below ground surface. The remaining below grade structure of the previously addressed 100-D-59, French Drain was completely removed during this remedial action. No anomalies were observed. Overburden was staged to the east of the excavation in the area of the former 183-D Filter Building. Potentially contaminated soils were staged to the southwest of the excavation in a multiple waste site staging pile area (SPA).

The area south of Paddock St (part of 100-D-72) was backfilled in March 2014 to provide access for well drilling activities in this area.

A portion of the 100-D-72 pipeline site was removed during excavation of the 100-D-100 hexavalent chromium stained soil site. The 100-D-100 site excavation removed the entire vadose zone and is approximately 26 meters (85 ft) deep. Because the 100-D-100 excavation is much deeper than the 100-D-72 pipeline, verification sampling and further evaluation of the 100-D-72 waste site in the area of the 100-D-100 excavation was determined to be unwarranted.

The SubSite is Part Of:

Code: 100-D-31
Names: 100-D-31; 100-D Water Treatment Facilities Underground Pipelines

Code: 100-D-32 **Classification:** Accepted
Names: 100-D-32; Minor Construction Burial Ground #6 **Reclassification:** Interim Closed Out (12/10/2009)
Type: Burial Ground **Start Date:** 1/1/1956
Status: Inactive **End Date:**

Description: The site has been remediated and reclassified to Interim Closed Out. It consisted of a small 3.0-meter (10-foot) by 3.0-meter (10-foot) burial ground. Only a small amount of concrete debris was unearthed in the northwest corner of the site.

Location: The site was approximately 150 meters (500 feet) southeast of the 105-D Reactor Building and 25 meters (82 feet) north of the railroad tracks (north of 118-D-3 Burial Ground).

Process Description: The trench was excavated in the Fall of 1956. HW-46715 states the site will be used for disposal of contaminated material and equipment. It has been assumed that the site was used as planned.

Waste Type: Equipment

Waste Description: The burial ground was excavated to receive contaminated reactor and effluent system equipment. Potential contaminants include: Co-60, Ni-63, No-59, Sm-151, Pd-107, Sr-90, Ag-108, Am-241, Ba-133, C-14, H-3, Cs-137, Eu-152 and 154, Pu-238, 239 and 241, Ca-41, Cd-113, Kr-85, U-238, Tc-99, Zr-93, chromium, lead and mercury.

Closure Info: Interim: Remedial action began on August 28, 2007, with the removal of 375 bank cubic meters (BCM) (490 bank cubic yards [BCY]) of overburden material. The overburden was stockpiled east of the burial ground. Excavation continued through September 5, 2007, to a remedial design depth of approximately 3 meters (10 ft), resulting in approximately 600 BCM (785 BCY) of material removed for disposal at ERDF. Only a small amount of concrete debris was unearthed in the northwest corner of the site.

Because only a small amount of concrete debris was encountered during excavation, the floor of the excavation had not reached beyond the limit of disturbed soil, and the uncertainty of the depth of the burial ground, an additional exploratory excavation was completed on July 31, 2008. The burial ground excavation was expanded to verify that no waste was present below the 3 meter (10 ft) remedial design limit. The exploratory excavation was performed to a depth of 6 meters (20 ft), with native soil encountered at a depth of approximately 5 meters (17 ft) below surface grade. An additional 525 BCM (687 BCY) of soil was removed from the side slopes and excavation floor and placed on the overburden stockpile.

During remedial excavation only a minor amount of concrete debris was unearthed in the northwest corner of the 100-D-32 Burial Ground. No spent nuclear fuel, anomalous material (containers, stained soils, or other waste forms), or other waste indicative of the disposal of contaminated material or equipment were discovered. It is likely that the 100-D-32 Burial Ground was never used (as reported in Heid, 1956). It may have been excavated and discussed in the context of potential future use (i.e., "will be used").

A previously unidentified pipeline encountered during the remedial action excavation that was added into site 100-D-105 for dispositioning.

Code: 100-D-42 **Classification:** Accepted

Names: 100-D-42; Buried VSR Thimble Site	Reclassification Interim Closed Out (5/13/2010)
Type: Burial Ground	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1955

Description: The waste site has been remediated and Interim Closed Out. It was a solid waste burial ground. The 100-D-42, 100-D-43, and 100-D-45 waste sites were located in the same area and were remediated as one decision unit. The burial ground was in very close proximity to the (exhumed) 152-centimeter (60-inch) effluent lines. Following remediation activities, the project was authorized to remove radiological postings.

Location: The site is located east of the 100-D Reactor Building, outside the reactor security fence and south of the railroad spur that services 100-D.

Waste Type: Equipment

Waste Description: The waste is a buried Vertical Safety Rod (VSR) thimble. The VSR thimbles were made of aluminum similar to that used in the process tubes and should contain similar isotopic composition. Sampling of process tubes was conducted in March 1967. The radionuclide levels, when decay corrected by Dorian and Richards to March 1977, were 5.9E+03 picocuries of manganese-54 per gram of aluminum and 2.5E+07 picocuries of cobalt-60 per gram of aluminum. When buried, the thimble's exterior surfaces would also have been contaminated with activated graphite products and potassium borate.

Closure Info: Interim: The 100-D-42, 100-D-43, and 100-D-45 waste sites were located in the same area and were remediated as one decision unit. Remedial action at the sites began on September 6, 2007, and was completed on April 22, 2008. Contaminated soil and debris were excavated and removed from the burial grounds for shipment to ERDF. Field observations during excavation indicated the presence of VSR thimbles in two of the three burial grounds. Only concrete debris and plastic sheeting were found to be present in the 100-D-42 Burial Ground. The 100-D-43 Burial Ground contained VSR thimbles and other reactor hardware. Mastic, aluminum pipe, VSR thimbles, reactor hardware, and a drum containing rags were found in the 100-D-45 Burial Ground. Due to the close proximity to each other and the type of debris encountered during excavation, the three sites were included in one CVP and interim closed out as one decision unit.

Remedial action at the 100-D-45 Burial Ground began on September 6, 2007, with the removal of 930 bank cubic meters (BCM) (1,216 bank cubic yards [BCY]) of overburden material. Excavation began on September 11, 2007 and continued through July 23, 2008 to a depth of approximately 7 meters (23 ft) resulting in approximately 2,605 BCM (3,407 BCY) of contaminated soil and debris removed for disposal at ERDF. Remedial action at the 100-D-43 Burial Ground began on September 10, 2007, with the removal of 165 BCM (216 BCY) of overburden material. Excavation began on September 25, 2007 and continued through October 10, 2007, to a depth of approximately 5 meters (16 ft), resulting in approximately 803 BCM (1,050 BCY) of contaminated soil and debris removed for disposal at ERDF. Remedial action at the 100-D-42 Burial Ground began on April 22, 2008, with the removal of 495 BCM (647 BCY) of overburden material. Excavation of the burial ground was initiated on April 25, 2008 and continued through May 13, 2008, to a depth of approximately 5 meters (16 ft), resulting in approximately 530 BCM (693 BCY) of contaminated soil and debris removed for disposal at ERDF.

A geophysical survey was conducted in June 2004 at the 100-D-42, 100-D-43, and 100-D-45 Burial Ground locations, and an additional survey was conducted at the 100-D-45 Burial Ground location in September 2004. No notable features with the characteristics of an excavated area or buried debris were detected at the documented location of the 100-D-42 site. Immediately to the south of the 100-D-42 Burial Ground was an area with distinct excavation boundaries and notable concentrations of anomalies with the characteristics of buried debris.

This area correlates more closely with the documented locations of the 100-D-43 and 100-D-45 Burial Grounds. One anomaly was encountered in the 100-D-43 Burial Ground. A 57 liter (15 gal) metal container partially filled with liquid was found during excavation. The container was found to have been breached and the contained liquid is suspected to have been water used for dust suppression during excavation activities. No suspect spent nuclear fuel was present in the burial grounds.

The excavation area has a maximum depth of approximately 7 meters (23 ft). However, the entire excavation area is considered one decision unit and meets the more restrictive shallow zone cleanup criteria.

Code:	100-D-45	Classification:	Accepted
Names:	100-D-45; 118-D-4B; Burial Ground 4B; Buried VSR Thimble Site	Reclassification	Interim Closed Out (5/13/2010)
Type:	Burial Ground	Start Date:	
Status:	Inactive	End Date:	
Description:	The waste site has been remediated and Interim Closed Out. It was a solid waste burial ground. The 100-D-42, 100-D-43, and 100-D-45 waste sites were located in the same area and were remediated as one decision unit. The burial ground was in very close proximity to the (exhumed) 152-centimeter (60-inch) effluent lines. Following remediation activities, the project was authorized to remove radiological postings.		
Location:	The site is located east of the 105-D Reactor Building, outside the security fence and south of the railroad spur that services 100-D.		
Waste Type:	Equipment		
Waste Description:	The waste is a buried Vertical Safety Rod (VSR) thimble. The VSR thimbles were made of aluminum similar to that used in the process tubes and should contain similar isotopic composition. Sampling of process tubes was conducted in March 1967. The radionuclide levels, when decay corrected by Dorian and Richards to March 1977, were 5.9E+03 picocuries of manganese-54 per gram of aluminum and 2.5E+07 picocuries of cobalt-60 per gram of aluminum. When buried, the thimble's exterior surfaces would also have been contaminated with activated graphite products and potassium borate. Potential contamination includes: Co-60, Ni-63.		
Closure Info:	Interim: The 100-D-42, 100-D-43, and 100-D-45 waste sites were located in the same area and were remediated as one decision unit. Remedial action at the sites began on September 6, 2007, and was completed on April 22, 2008. Contaminated soil and debris were excavated and removed from the burial grounds for shipment to ERDF. Field observations during excavation indicated the presence of VSR thimbles in two of the three burial grounds. Only concrete debris and plastic sheeting were found to be present in the 100-D-42 Burial Ground. The 100-D-43 Burial Ground contained VSR thimbles and other reactor hardware. Mastic, aluminum pipe, VSR thimbles, reactor hardware, and a drum containing rags were found in the 100-D-45 Burial Ground. Due to the close proximity to each other and the type of debris encountered during excavation, the three sites were included in one CVP and interim closed out as one decision unit.		
	Remedial action at the 100-D-45 Burial Ground began on September 6, 2007, with the removal of 930 bank cubic meters (BCM) (1,216 bank cubic yards [BCY]) of overburden material. Excavation began on September 11, 2007 and continued through July 23, 2008 to a depth of approximately 7 meters (23 ft) resulting in approximately 2,605 BCM (3,407 BCY) of contaminated soil and debris removed for disposal at ERDF. Remedial action at the 100-D-43 Burial Ground began on September 10, 2007, with the removal of 165 BCM (216 BCY) of		

overburden material. Excavation began on September 25, 2007 and continued through October 10, 2007, to a depth of approximately 5 meters (16 ft), resulting in approximately 803 BCM (1,050 BCY) of contaminated soil and debris removed for disposal at ERDF. Remedial action at the 100-D-42 Burial Ground began on April 22, 2008, with the removal of 495 BCM (647 BCY) of overburden material. Excavation of the burial ground was initiated on April 25, 2008 and continued through May 13, 2008, to a depth of approximately 5 meters (16 ft), resulting in approximately 530 BCM (693 BCY) of contaminated soil and debris removed for disposal at ERDF.

A geophysical survey was conducted in June 2004 at the 100-D-42, 100-D-43, and 100-D-45 Burial Ground locations, and an additional survey was conducted at the 100-D-45 Burial Ground location in September 2004. No notable features with the characteristics of an excavated area or buried debris were detected at the documented location of the 100-D-42 site. Immediately to the south of the 100-D-42 Burial Ground was an area with distinct excavation boundaries and notable concentrations of anomalies with the characteristics of buried debris. This area correlates more closely with the documented locations of the 100-D-43 and 100-D-45 Burial Grounds. One anomaly was encountered in the 100-D-43 Burial Ground. A 57 liter (15 gal) metal container partially filled with liquid was found during excavation. The container was found to have been breached and the contained liquid is suspected to have been water used for dust suppression during excavation activities. No suspect spent nuclear fuel was present in the burial grounds.

The excavation area has a maximum depth of approximately 7 meters (23 ft). However, the entire excavation area is considered one decision unit and meets the more restrictive shallow zone cleanup criteria.

Code: 100-D-48	Classification: Accepted
Names: 100-D-48; 100-D Reactor Cooling Water Effluent Underground Pipelines	Reclassification: Interim Closed Out (4/23/2001)
Type: Radioactive Process Sewer	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1967

Description: All four subsites have been remediated and Interim Closed Out. Therefore, the parent site is also considered to be Interim Closed Out.

The 100-D-48 site includes those underground pipelines that transported radioactive treated and untreated waste water from the 105-D Reactor Building to the 116-D-7 (107-D) Retention Basin and the 116-D-5 Outfall. The included pipeline components are listed below.

There are many small drain pipelines that leave from the east and south sides of the 105-D Reactor Building and terminate at the 132-D-3 (1608-D) Building site. The pipelines that ran from the 105-D Reactor and the 132-D-3 (1608-D) Building to either the 116-D-1A Trench or 116-D-1B Trench or connected to the main cooling water effluent pipelines are part of this waste site.

The main cooling water effluent pipeline is a large 1.5-meter (60-inch) diameter reinforced concrete pipeline that exited the 105-D Reactor Building on the north side and continued north to the 116-D-7 (107-D) Retention Basin. A map in the Dorian and Richards document, UNI-946, indicates that some sections of the pipeline were replaced at least once (as does M-1904-D Sheet 8). The second (replacement) pipeline began at a junction box south of the 116-D-7 (107-D) Retention Basin and ran parallel to the original pipeline up to the 116-D-7 (107-D) Retention Basin. A portion of the steel replacement pipeline remained in place, above grade, at the retention basin, covered with a soil berm, visually indicating the location of the pipeline.

This pipeline system also included a 1.5-meter (60-inch) diameter by 1.3-centimeter (0.5-inch) thick wall, carbon steel cross-tie pipeline to the 105-DR Reactor effluent pipelines that were adjacent to the 103-D Building and connected at a junction box to the west 100-DR Reactor Cooling Water Effluent Pipeline (SiteCode 100-D-49).

This site includes a single pipeline that runs from the west end of the 116-D-7 (107-D) Retention Basin to the 116-DR-1 Trench and 116-DR-2 Trench and two pipelines from the west end of the 116-D-7 (107-D) Retention Basin to the 116-D-5 Outfall.

Because of their length, these pipelines have been broken into four subsites: 100-D-48:1, the pipelines from 116-D-7 to the outfalls; 100-D-48:2, the pipelines from D Avenue to 116-D-7; 100-D-48:3, the pipelines from D Avenue to the 105-D Reactor; and 100-D-48:4, the small cooling water effluent pipelines at the 105-D Reactor.

The site does not include the facilities where the pipelines terminate, or the pipelines (100-D-60) from the 116-D-5 Outfall to the bottom center of the Columbia River. The pipelines associated with (100-D-49) 100-DR Reactor Cooling Water Effluent Underground Pipelines or (100-D-50) 100-DR Reactor Process Sewer Underground Pipelines [pipelines that transported nonradioactive treated and untreated waste water from the 183-DR, 183-DR Clearwell area and the 105-DR Reactor Buildings to the 100-D-8 (1907-DR) Outfall] are not included in this site.

Location: The underground pipelines ran in a north-south direction north of the 105-D Reactor, to the 116-D-7 Retention Basin, terminating at the 116-D-5 Outfall. Pipeline descriptions for this waste site and associated structures are as follows.

105-D Reactor:

- a 20 centimeter (8 inch) vent pipe exits the north side and extends to a junction box in the cross-tie pipeline
- a 15 centimeter (6 inch) line and a 20.32 centimeter (8 inch) line exit the northeast corner to a 76 centimeter (30 inch) pipe, to a diversion box for the 116-D-1A trench
- a 30 centimeter (12 inch) effluent line exits the northeast corner and runs to the 152.4 centimeter (60 inch) DR effluent mainline to 116-DR-9
- a 41 centimeter (16 inch) effluent pipe exits the east side and runs to a junction box, then to 116-D-1A
- a 66 centimeter (26 inch) effluent line exits the south side and runs to a 76.2 centimeter (30 inch) line
- a 152 centimeter (60 inch) main line runs to the 116-D-7 Retention Basin from the north side. A new main line was made just east of the original, crossing the original line approximately 160 meters (530 feet) south of the basin
- a 152 centimeter (60 inch) cross-tie line connects the D and DR effluent lines, approximately 75 meters (250 feet) north of the 105-D Reactor.

1608-D Waste Water Pump House:

- a 15 centimeter (6 inch) waste pipe exits the south side and proceeds east to the 116-D-1A Trench
- a 61 centimeter (24 inch) pipe exits the east side, then runs north to the new 168 centimeter (66 inch) effluent line to 116-D-7
- a 66 centimeter (26 inch) line exits the east side and continues to the southeast corner of the 105-D Reactor.

107-D Retention Basin:

- a 107 centimeter (42 inch) bypass line flows from the north west corner east to the 116-DR-

1&2 Trench

- a 107 centimeter (42 inch) line flows out the west end to the 116-D-5 Outfall
 - a 152 centimeter (60 inch) bypasses the before-mentioned 107 centimeter (42 inch) line, and flows northwest intersecting the 152 centimeter (60 inch) line coming from the DR retention basin.

Related Sites/ Structures: The associated structures are the 105-D Reactor Building, 132-D-3 (1608-D), the 116-D-7 Retention Basin and the 116-D-5 Outfall. Other related sites are the 116-D-1A, 116-D-1B Trenches, and 116-DR-1, 116-DR-2 Trenches, 100-D-85 (105D Reactor Effluent Pipelines), 100-D-49 (100-DR Reactor Cooling Water Effluent Underground Pipelines).

Process Description: The pipelines were used to dispose of radioactive cooling and waste water from the reactor facility. One large main effluent pipelines drained cooling water from the 105-D Reactor. The small effluent pipelines that drained process waste from the sides (east and south) of the 105-D were joined into a single pipeline that ran to the 1608-D Building (Waste Water Pumping Station or Process Lift Station). The 1608-D Building was a rectangular shaped, two-story, reinforced concrete structure that was half below grade elevation. The purpose of this facility was to pump process effluent to the main effluent pipeline.

Waste Type: Process Effluent

Waste Description: The waste is contaminated steel piping, concrete, and soil. Chemical additives to reactor cooling water included aluminum sulfate (alum) with excess hydrated calcium oxide, sulfuric acid, chlorine, diatomaceous earth (a scouring agent), and sodium dichromate. Water pH was maintained at about 7.5, and free chlorine residual was about 0.2 milligrams per liter. Radionuclides discovered at the retention basin during sampling by Dorian and Richards (1978) included the following: plutonium-238, cesium-134, plutonium 239/240, cesium-137, strontium-90, hydrogen-3, uranium, europium-152, europium-154, europium-155, nickel-63, cobalt-60, and carbon-14.

This Site has the Following SubSites:

Code: 100-D-48:1

Names: 100-D-48:1; North Pipelines from 116-D-7 to the Outfalls

Code: 100-D-48:2

Names: 100-D-48:2; West Pipelines from D Avenue to 116-D-7

Code: 100-D-48:3

Names: 100-D-48:3; Effluent Pipelines from D Avenue to 105-D Reactor

Code: 100-D-48:4

Names: 100-D-48:4; Small Cooling Water Effluent Pipelines at 105-D Reactor

Code: 100-D-48:1

Classification: Accepted

Names: 100-D-48:1; North Pipelines from 116-D-7 to the Outfalls

Reclassification: Interim Closed Out (3/19/2001)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This subsite has been remediated and Interim Closed Out. The 100-D-48:1 pipeline sections were located north of the 116-D-7 Retention Basin and went to the 116-D-7 (1904-D Outfall). Pipeline components consisted of a 106.7 cm (42 in) reinforced concrete pipeline (RCP) from the retention basin to the outfall structure, a 106.7 cm (42 in) bypass pipeline, a 152.4 cm (60 in) steel pipeline, and a crosstie pipeline from the 106.7 cm (42 in) Reinforced Concrete Pipe to the 152.4 cm (60 in) steel pipeline. These pipelines have been removed.

Location: Generally, the underground pipelines ran in a north-south direction north of the 105-D Reactor, went to the 116-D-7 Retention Basin, and ended at the 116-D-5 Outfall. Pipeline descriptions include:

107-D Retention Basin:

- a 107 centimeter (42 inch) bypass line flows from the north west corner east to the 116-DR-1&2 Trench
- a 107 centimeter (42 inch) line flows out the west end to the 116-D-5 Outfall
- a 152 centimeter (60 inch) bypasses the before-mentioned 107 centimeter (42 inch) line, and flows northwest intersecting the 152 centimeter (60 inch) line coming from the DR retention basin.

Waste Type: Not Specified

Waste Description: The waste was contaminated steel piping, concrete, and soil.

Closure Info: Interim: Waste sites 100-D-48:1, 100-D-49:1, 100-D-19 and UPR-100-D-4 were co-located and remediated together. The CVP document referred to the four, combined waste sites as the 100-D-48:1/49:1 Pipeline site. Remedial action at the 100-D-48:1/49:1 Pipelines site began on December 28, 1998. Excavation of the site involved removing the overburden materials, the contaminated structure, and underlying contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Materials that were found to be contaminated were disposed of at ERDF. On July 24, 2000, the excavation reached the design limit. Because remediation of the 100-D-48:1/49:1 Pipelines site required moving an active overhead power line, site remedial action and sampling were conducted in two phases. These separate phases are reflected by the long time period between the start and finish dates for excavation.

The excavation design depth generally corresponded with the invert elevation of the pipelines. At the completion of remedial action and removal of the engineered structure, the excavation was approximately 15,504 square meters (166,800 square feet) in area with a maximum depth of approximately 6.0 meters (20 feet) below ground surface. Approximately 107,266 metric tons (118,241 tons) of material from the D Area pipelines site have been disposed of at the ERDF through July 2000. Cleanup verification sampling began on April 3, 2000, and was finished on August 8, 2000. The ground surface in the vicinity of the site varies with an average elevation of approximately 134.4 meters (441 feet).

The SubSite is Part Of:

Code: 100-D-48

Names: 100-D-48; 100-D Reactor Cooling Water Effluent Underground Pipelines

Code: 100-D-48:2

Classification: Accepted

Names: 100-D-48:2; West Pipelines from D Avenue to 116-D-7

Reclassification: Interim Closed Out (9/26/2000)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This subsite of pipelines has been remediated and Interim Closed Out. It consisted of two parallel pipelines that ran from D Avenue to the 116-D-7 Retention Basin. The most western pipeline was a 152.4 cm (60 in) reinforced concrete pipeline (RCP). The other pipeline was a 152.4 cm (60 in) steel pipeline that connected to a junction box (approximately 237 meters (777

ft) south of the 116-D-7 Retention Basin). Inside the junction box, a new 152.4 cm (60 in) pipeline was added. This pipeline continued north to the 116-D-7 Retention Basin.

Location: This segment ran north from D Avenue to the 116-D-7 Retention Basin.

Waste Type: Not Specified

Waste Description: The waste was contaminated steel piping, concrete, and soil.

Closure Info: Interim (9/26/2000): Remediation at the 100-D-48:2 and 100-D-49:2 pipelines and the associated releases UPR-100-D-2 and UPR-100-D-3 were remediated together. Remedial activities began in July 1997. Excavation of the waste sites involved removing the overburden material, contaminated structures, and underlying contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Excavated material found to be contaminated was disposed of at the ERDF. In August 1999, the excavation reached the design limit. The excavation design depth generally corresponded with the invert elevation of the pipelines. Because of the length of the pipeline site, the top-of-excavation elevation ranges from 138 meters (453 feet) near the retention basins to 143 meters (469 feet) near D Avenue.

At the completion of remedial action and removal of the engineered structure, the excavation was approximately 20,475 square meters (220,280 square feet) in area with a maximum depth of approximately 6 meters (20 feet) below ground surface. During the time of excavation and waste disposal (December 1998 through September 1999) approximately 57,106 metric tons (62,960 tons) of material from 100-DR-1 Operable Unit pipelines were disposed of at the ERDF.

The SubSite is Part Of:

Code: 100-D-48

Names: 100-D-48; 100-D Reactor Cooling Water Effluent Underground Pipelines

Code: 100-D-48:3

Classification: Accepted

Names: 100-D-48:3; Effluent Pipelines from D Avenue to 105-D Reactor

Reclassification: Interim Closed Out (4/23/2001)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This subsite has been remediated and Interim Closed Out. The subsite is the section of the 105-D Reactor cooling water effluent pipelines, extending south from D Avenue to about 1.5 meters (5 feet) from the wall of the reactor foundation. The subsite includes a 1.5 meter (60 inch) diameter reinforced concrete pipeline extending south from D Avenue to about 1.5 meters (5 feet) from the wall of the reactor foundation, a parallel 2 meter (66 inch) steel pipe that extends south from D Avenue to an east-west trending cross-tie line to 100-D-49:3, a 1.5 meter (60 inch) steel east-west trending cross-tie line connecting these subsite pipelines to 100-D-49:3 and two 20 centimeter (8 inch) steel lines ending south from the cross-tie to about 1.5 meters (5 feet) from the wall of the reactor foundation. The Decontamination and Decommissioning project is responsible for the remaining stub as part of the foundation removal.

Location: These pipelines extend south from D Avenue to about 1.5 meters (5 feet) from the wall of the reactor foundation. The site is located near the center of the 100-D/DR Area and is approximately 750 meters (2,461 feet) from the Columbia River at the nearest location.

Process Description: The pipelines were used to dispose of large quantities of radioactive cooling and waste water from the 105-D Reactor facility to the 116-D-7 (107-D) Retention Basin.

Waste Type: Not Specified

Waste Description: The waste was contaminated steel piping, concrete, and soil.

Closure Info: Interim (4/23/2001): The 100-D-48:3, 100-D-49:3, 100-D-5 and 100-D-6 waste sites were remediated together. The CVP document refers to the group of waste sites as the 100-D-48:3/49:3 pipelines site. Remedial action began on October 28, 1999. Excavation of the sites involved removing the overburden materials, the contaminated structure, and underlying contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Materials that were found to be contaminated were disposed of at ERDF. On July 24, 2000, the excavation was completed. The excavation design depth generally corresponded with the invert elevation of the pipelines.

At the completion of remedial action and removal of the engineered structure, the excavation was approximately 24,574 square meters (264,517 square feet) in area with a maximum depth of approximately 5.7 meters (18.7 feet). Approximately 55,561 metric tons (61,245 tons) of material from the 100-D-48:4 and 100-D-48:3/49:3 pipeline sites disposed of at ERDF. The excavation was backfilled with appropriate materials to match the surrounding surface grade (average elevation of 143.7 meters [471 feet]).

The SubSite is Part Of:

Code: 100-D-48

Names: 100-D-48; 100-D Reactor Cooling Water Effluent Underground Pipelines

Code: 100-D-48:4

Classification: Accepted

Names: 100-D-48:4; Small Cooling Water Effluent Pipelines at 105-D Reactor

Reclassification: Interim Closed Out (4/23/2001)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This subsite has been remediated and reclassified to Interim Closed Out. It included multiple small drain pipelines that exit from the east and south sides of the 105-D Reactor Building and terminate at the 132-D-3 (1608-D) Building site. The pipelines that ran from the 105-D Reactor and the 132-D-3 (1608-D) Building to either the 116-D-1A Trench and 116-D-1B Trench or connected to the main cooling water effluent pipelines are also part of this subsite. The pipelines were removed up to 4.9 meters (16 ft) from the 105-D and 1608-D Building exterior walls.

Location: These pipelines are on the north, east, and south sides of the 105-D Reactor.

Process Description: The pipelines were used to dispose of radioactive cooling and waste water from the reactor facility. One large main effluent pipeline drained cooling water from the 105-D Reactor. The small effluent pipelines that drained process waste from the sides (east and south) of the 105-D Reactor were joined into a single pipeline that ran to the 1608-D Building (Waste Water Pumping Station or Process Lift Station). The 1608-D Building was a rectangular-shaped, two-story reinforced concrete structure that was half below grade. The purpose of the 1608-D facility was to pump process effluent to the main effluent pipeline. The pipelines were removed up to 4.9 meters (16 ft) from the 105-D and 1608-D Building exterior walls.

Waste Type: Not Specified

Waste Description: The waste was contaminated steel piping, concrete, and soil.

Closure Info: Interim (4/23/2001): The pipelines were used to dispose of radioactive cooling and waste water from the reactor facility. One large main effluent pipeline drained cooling water from the 105-D Reactor. The small effluent pipelines that drained process waste from the sides (east and south) of the 105-D Reactor were joined into a single pipeline that ran to the 1608-D Building (Waste Water Pumping Station or Process Lift Station). The 1608-D Building was a rectangular-shaped, two-story reinforced concrete structure that was half below grade. The purpose of the 1608-D facility was to pump process effluent to the main effluent pipeline. The pipelines were removed up to 4.9 meters (16 ft) from the 105-D and 1608-D Building exterior walls.

Remedial action at the 100-D-48:4 site began on October 28, 1999. Excavation of the site involved removing the overburden materials, the contaminated structure, and underlying contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Materials that were found to be contaminated were disposed of at ERDF. On July 24, 2000, the excavation reached the design limit at El. 136 meters (446 feet).

At the completion of remedial action and removal of the engineered structure, the excavation was approximately 3,291 square meters (35,420 square feet) in area with a maximum depth of approximately 7 meters (23 feet). Approximately 27,738 metric tons (30,576 tons) of material from the site were disposed of at ERDF. Cleanup verification sampling began on September 11, 2000, and was completed on October 18, 2000. The excavation is to be backfilled with appropriate materials to the reference grade of El. 143 meters (469 feet).

Part of the 100-D-48:4 pipeline beneath reactor room 210 was deferred for remedial action with the 118-D-6:4 subsite (105-D Fuel Storage Basin Side Slopes - see CVP-2005-00003).

The SubSite is Part Of:

Code: 100-D-48

Names: 100-D-48; 100-D Reactor Cooling Water Effluent Underground Pipelines

Code: 100-D-49

Classification: Accepted

Names: 100-D-49; 100-DR Reactor Cooling Water Effluent Underground Pipelines

Reclassification: Interim Closed Out (1/15/2004)

Type: Radioactive Process Sewer

Start Date: 1/1/1950

Status: Inactive

End Date: 1/1/1967

Description: The four subsites associated with this site have been remediated and Interim Closed Out. The total waste site included the underground pipelines that transported radioactive, treated and untreated, waste water from the 105-DR Reactor Building, and the 132-DR-1 (1608-DR) Building to the 116-DR-9 (107-DR) (107-DR) Retention Basin and both of the 116-D-5 and 116-DR-5 Outfalls. The pipeline components included in this waste site are listed below.

There are many small drain pipelines that originated on the east side of the 105-DR Reactor Building and terminated at the 132-DR-1 (1608-DR) Building site. The drain pipelines that ran from the 132-DR-1 (1608-DR) to either the 116-DR-6 Trench or connected to the main cooling water effluent pipelines are part of this waste site.

The main cooling water effluent pipelines were two large 1.5-meter (60-inch) diameter by 1.3-centimeter (0.5-inch) thick wall carbon steel pipelines. The east pipeline exited the 105-DR Reactor Building on the south side and ran due east and then turned northeast to a point 75 meters (210 feet) east of the original exclusion fence. The pipeline then ran north to the 116-DR-9 (107-DR) Retention Basin. The west pipeline exited the 105-DR Reactor Building on the

north side and turned northeast to a point 55 meters (154 feet) east of the original exclusion fence. The pipeline then turned north to the 116-DR-9 (107-DR) Retention Basin. The pipelines ran parallel to each other and were approximately 25 meters (70 feet) apart.

This site also includes the discharge pipelines from the 116-DR-9 (107-DR) Retention Basin to the 116-DR-1 and 116-DR-2 Trench and both 116-D-5 and 116-DR-5 Outfalls. At the outlet of the 116-DR-9 (107-DR) Retention Basin, two 1.5-meter (60-inch) carbon steel pipelines are combined into a single 1.5-meter (60-inch) pipeline at a junction box. This pipeline then runs to the outfall structure. The outfall discharge pipeline is a 1.7-meter (66-inch) carbon steel pipeline that continues to the center of the Columbia River.

Because of its length, this site has been broken into four subsites: 100-D-49:1, the pipelines from 116-DR-9 to the Outfalls; 100-D-49:2, the pipelines from D Avenue to 116-DR-9; 100-D-49:3, the pipelines from D Avenue to the 105-D Reactor; and 100-D-49:4 the effluent pipelines within 60 meters of the reactor.

The facilities where these pipelines terminate are not included as part of this site.

The following pipelines are not included as part of this site (included as part of 100-D-48): Opposite the 105-D Reactor Building, the west 105-DR Reactor effluent pipeline is cross-tied to the 105-D Reactor 1.5-meter (60-inch) effluent pipeline by a 1.5-meter (60-inch) diameter by 1.3-centimeter (0.5-inch) thick wall, carbon steel pipeline. The underground pipelines (100-D-50) that transported nonradioactive treated and untreated waste water from the 183-DR, 183-DR Clearwell area, and the 105-DR Reactor Buildings to the 100-D-8 (1907-DR) outfall are not included in this site.

Location: The pipelines ran in a north-south direction east of the 100-D Reactors. Several expansion boxes are apparent at the ground surface along the length of the pipelines. Pipeline descriptions and associated structures are as follows.

105-DR Reactor:

- a 20.32 centimeter (8 inch) effluent line exits the south side and runs to the east side of 1608-DR
- a 45.72 centimeter (18 inch) effluent line exits the south side and also runs to the east side of 1608-DR
- two 152.4 centimeter (60 inch) effluent pipe exit the northeast side and run to the 116-DR-9 Retention Basin

116-DR-9 Retention Basin:

- two 152.4 centimeter (60 inch) lines exit the north end and flow, parallel, west to the 116-D-5 Outfall.
- a 152.4 centimeter (60 inch) bypass line intersects the southern DR basin to the outfall effluent line, and flows north to the 116-DR-5 Outfall.
- a 10.16 centimeter (4 inch) line exits the south end and flows into the 100-D-4 Trench.
- two 30.48 centimeter (12 inch) lines flow east from the north end into the 116-DR-1&2 Trench.

Related Sites/ Structures: The associated structures are the 105-DR Building, the 132-DR-1 (1608-DR), the 116-DR-9 (107-DR) Retention Basin, the 116-D-5 Outfall and 116-DR-5 Outfall. Other related sites are the 116-DR-1, 116-DR-2 and 116-DR-6 Trenches, 100-D-85 (105D Reactor Effluent Pipelines) and 100-D-48 (100-D Reactor Cooling Water Effluent Underground Pipelines).

Process Description: The pipelines were used to dispose of radioactive cooling and waste water from the reactor facility. Two large main effluent pipelines drained cooling water from the 105-DR Reactor.

The small effluent pipelines that drained process waste from the sides (east and south) of the 105-DR were joined into a single pipeline that ran to the 132-DR-1 ([1608-DR Building] Waste Water Pumping Station or Process Lift Station). The 132-DR-1 (1608-DR) Building was a rectangular shaped, two-story, reinforced concrete structure that was half below grade elevation. The purpose of this facility was to pump process effluent to the main effluent pipeline.

Waste Type: Process Effluent

Waste Description: The waste is contaminated steel piping, concrete, and soil. Chemical additives to reactor cooling water included aluminum sulfate (alum) with excess hydrated calcium oxide, sulfuric acid, chlorine, diatomaceous earth (a scouring agent), and sodium dichromate. Water pH was maintained at about 7.5, and free chlorine residual was about 0.2 milligrams per liter. Radionuclides discovered at the retention basin during sampling by Dorian and Richards (1978) for UNI-946, included: plutonium-238, cesium-134, plutonium 239/240, cesium-137, strontium-90, hydrogen-3, uranium, europium-152, europium-154, europium-155, nickel-63, cobalt-60, and carbon-14.

This Site has the Following SubSites:

Code: 100-D-49:1

Names: 100-D-49:1; North Pipelines from 116-DR-9 to the Outfalls

Code: 100-D-49:2

Names: 100-D-49:2; East Pipelines from D Avenue to 116-DR-9

Code: 100-D-49:3

Names: 100-D-49:3; Effluent Pipelines from D Avenue to About 60 Meters from the 105-DR Reactor

Code: 100-D-49:4

Names: 100-D-49:4; 100-DR Effluent Pipelines Within About 60 Meters of the Reactor

Code: 100-D-49:1

Classification: Accepted

Names: 100-D-49:1; North Pipelines from 116-DR-9 to the Outfalls

Reclassification: Interim Closed Out (3/26/2001)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This subsite has been remediated and Interim Closed Out. The 100-D-49:1 pipeline sections were located north of the 116-D-7 Retention Basin and went to the 116-D-5 (1904-D Outfall). Pipeline components consisted of a 1.5 meter (60 inch) steel pipeline, part of another 1.5 meter (60 inch) steel pipeline coming from the 116-DR-9 Retention Basin, up to its connection with the 1.5 meter (60 inch) steel pipeline associated with the 116-D-7 Retention Basin, and part of a 1.1 meter (42 inch) bypass pipeline (up to the northeast end of 116-D-7).

Location: These pipelines were north of the 107-D and 107-DR Retention Basins, extending to the 1904-D and 1904-DR Outfalls.

Process Description: These pipelines drained radioactive cooling water from the retention basins to the 1904-D and 1904-DR Outfalls structures.

Waste Type: Not Specified

Waste Description: The waste was contaminated steel piping, concrete, and soil.

Closure Info: Interim: Waste sites 100-D-48:1, 100-D-49:1, 100-D-19 and UPR-100-D-4 were co-located and

remediated together. The CVP document referred to the four, combined waste sites as the 100-D-48:1/49:1 Pipeline site. Remedial action at the 100-D-48:1/49:1 Pipelines site began on December 28, 1998. Excavation of the site involved removing the overburden materials, the contaminated structure, and underlying contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Materials that were found to be contaminated were disposed of at ERDF. On July 24, 2000, the excavation reached the design limit. Because remediation of the 100-D-48:1/49:1 Pipelines site required moving an active overhead power line, site remedial action and sampling were conducted in two phases. These separate phases are reflected by the long time period between the start and finish dates for excavation.

The excavation design depth generally corresponded with the invert elevation of the pipelines. At the completion of remedial action and removal of the engineered structure, the excavation was approximately 15,504 square meters (166,800 square feet) in area with a maximum depth of approximately 6.0 meters (20 feet) below ground surface. Approximately 107,266 metric tons (118,241 tons) of material from the D Area pipelines site have been disposed of at the ERDF through July 2000. Cleanup verification sampling began on April 3, 2000, and was finished on August 8, 2000. The ground surface in the vicinity of the site varies with an average elevation of approximately 134.4 meters (441 feet).

The SubSite is Part Of:

Code: 100-D-49

Names: 100-D-49; 100-DR Reactor Cooling Water Effluent Underground Pipelines

Code: 100-D-49:2

Classification: Accepted

Names: 100-D-49:2; East Pipelines from D Avenue to 116-DR-9

Reclassification: Interim Closed Out (9/26/2000)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This subsite has been remediated and Interim Closed Out. It consisted of a section of two parallel pipelines that ran from D Avenue to 116-DR-9 Retention Basin. The two pipelines were constructed of 1.5 meter (5 ft) diameter by 1.3 cm (0.5 in.) thick carbon steel with welded joints. The two parallel pipelines were about 25 meters (66 ft) apart.

Location: This section of two parallel pipelines ran from D Avenue to the 116-DR-9 Retention Basin.

Waste Type: Not Specified

Waste Description: The waste was contaminated steel piping, concrete, and soil.

Closure Info: Interim (9/26/2000): Remediation at the 100-D-48:2 and 100-D-49:2 pipelines and the associated releases UPR-100-D-2 and UPR-100-D-3 were remediated together. Remedial activities began in July 1997. Excavation of the waste sites involved removing the overburden material, contaminated structures, and underlying contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Excavated material found to be contaminated was disposed of at the ERDF. In August 1999, the excavation reached the design limit. The excavation design depth generally corresponded with the invert elevation of the pipelines. Because of the length of the pipeline site, the top-of-excavation elevation ranges from 138 meters (453 feet) near the retention basins to 143 meters (469 feet) near D Avenue.

At the completion of remedial action and removal of the engineered structure, the excavation

was approximately 20,475 square meters (220,280 square feet) in area with a maximum depth of approximately 6 meters (20 feet) below ground surface. During the time of excavation and waste disposal (December 1998 through September 1999) approximately 57,106 metric tons (62,960 tons) of material from 100-DR-1 Operable Unit pipelines were disposed of at the ERDF.

The SubSite is Part Of:

Code: 100-D-49

Names: 100-D-49; 100-DR Reactor Cooling Water Effluent Underground Pipelines

Code: 100-D-49:3

Classification: Accepted

Names: 100-D-49:3; Effluent Pipelines from D Avenue to About 60 Meters from the 105-DR Reactor

Reclassification: Interim Closed Out (4/23/2001)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This subsite has been remediated and Interim Closed Out. It extends south from D Avenue to about 60 meters (200 feet) from the wall of the reactor foundation. The east lines are longer and the west lines are shorter. The two parallel pipelines were constructed of 1.5 meter (5 ft) diameter carbon steel with welded joints. The Decontamination and Decommissioning project is responsible for the remaining pipelines as part of the foundation removal.

Location: These pipelines run from the 105-DR Reactor to D Avenue.

Waste Type: Not Specified

Waste Description: The waste was contaminated steel piping, concrete, and soil.

Closure Info: Interim (4/23/2001): The 100-D-48:3, 100-D-49:3, 100-D-5 and 100-D-6 waste sites were remediated together. The CVP document refers to the group of waste sites as the 100-D-48:3/49:3 pipelines site. Remedial action began on October 28, 1999. Excavation of the sites involved removing the overburden materials, the contaminated structure, and underlying contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Materials that were found to be contaminated were disposed of at ERDF. On July 24, 2000, the excavation was completed. The excavation design depth generally corresponded with the invert elevation of the pipelines.

At the completion of remedial action and removal of the engineered structure, the excavation was approximately 24,574 square meters (264,517 square feet) in area with a maximum depth of approximately 5.7 meters (18.7 feet). Approximately 55,561 metric tons (61,245 tons) of material from the 100-D-48:4 and 100-D-48:3/49:3 pipeline sites disposed of at ERDF. The excavation was backfilled with appropriate materials to match the surrounding surface grade (average elevation of 143.7 meters [471 feet]).

The SubSite is Part Of:

Code: 100-D-49

Names: 100-D-49; 100-DR Reactor Cooling Water Effluent Underground Pipelines

Code: 100-D-49:4

Classification: Accepted

Names: 100-D-49:4; 100-DR Effluent Pipelines Within About 60 Meters of the Reactor

Reclassification: Interim Closed Out (1/15/2004)

Type: Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:**

Description: This subsite has been remediated and Interim Closed Out. The sections of the effluent pipelines were transferred from the Remedial Action (RA) group to Decontamination and Decommissioning (D&D) to allow D&D to continue their stabilization work on the DR Reactor. The subsite includes the smaller effluent pipelines near the 132-DR-1 Pumping Station and the large 1.5 meter (60 inch) main effluent steel pipelines (two adjacent pipes) extending from the reactor. The eastern main effluent pipe section is about 67 meters (220 feet) long. The northern section is about 35 meters (115 feet) long.

Location: These pipelines are on the north, northeast and east sides of the 105-DR Reactor.

Process Description: The effluent pipelines were used to dispose of large quantities of radioactive cooling and waste water from the 105-DR Reactor facility to the 116-DR-9 (107-DR) Retention Basin.

Waste Type: Not Specified

Waste Description: The waste was contaminated steel piping, concrete, and soil.

Closure Info: Interim (1/15/2004): The Cleanup verification package CVP-2003-00016 documents completion of removal action for 118-DR-2:2 Below Grade Structures and Underlying soils and the 100-D-49:4 pipeline in support of the 105-DR Reactor Interim Safe Storage Project. The 100-D-49:4 region consisted of the north effluent pipe tunnel, which had been removed. The soil beneath the floor and the side slopes were sampled for cleanup verification purposes. A portion of the 100-D-49:3 pipelines, located adjacent to the 105-D building, were also part of this remedial activity. The remedial activity was divided into five Zones, the north effluent pipeline and three decontamination areas. The three decontamination areas were also part of this remediation.

Removal and disposal activities at the 105-DR site began in September 1998 and concluded through September 2001. Excavation of the site involved removing the overburden materials, building structure, debris, and underlying contaminated soil. The 105-DR D&D activities resulted in removal of above-grade structures and below-grade structures outside of the 105-DR Reactor core shield walls, to 1 meter (3 ft) below surrounding grade, with the exception of the Fuel Storage Basin (FSB). The FSB structure was removed to 4.6 meters (15 ft) below the surrounding grade.

Sample results from the northwest and south decontamination areas resulted in additional excavation of these areas.

An individual calculation of contaminated material removed for cleanup of the pipeline area was not provided in the CVP. A total of approximately 7,220 cubic meters (25,500 cubic feet) of contaminated materials were disposed at the ERDF. The results of this effort indicated that the materials from the site containing COCs at concentrations exceeding RAGs have been excavated and disposed at the ERDF.

The SubSite is Part Of:

Code: 100-D-49

Names: 100-D-49; 100-DR Reactor Cooling Water Effluent Underground Pipelines

Code: 100-D-50

Classification: Accepted

Names: 100-D-50; 100-DR Water Treatment Facilities
Underground Pipelines

Reclassification: None

Type: Process Sewer **Start Date:** 1/1/1950

Status: Inactive **End Date:** 1/1/1965

Description: The waste site is the underground pipelines associated with the pre-reactor cooling water, process waste water and sanitary water. The waste site was divided into ten subsites. The pipelines transported nonradioactive treated and untreated waste water from the 183-DR, 183-DR Clearwell area, and the 105-DR Reactor Buildings to the 100-D-8 (1907-DR) Outfall.

Subsite descriptions are as follows:

- Subsite 1- Emergency Discharge Pipelines
- Subsite 2- Reactor Cooling Water Pipelines
- Subsite 3- Reactor Cooling Water Pipelines
- Subsite 4- Gas Recirculation Pipelines
- Subsite 5- 183-DR Sedimentation Basin Drain Pipelines
- Subsite 6- 183-DR Clearwell Drain Pipelines
- Subsite 7- 183-DR Head House Floor Drain and Catch Basin Pipelines
- Subsite 8- 117-DR Condensate Drain Lines
- Subsite 9 - 1607-DR3 Sanitary Sewer Pipelines
- Subsite 10 - Construction Camp Potable Water Supply Drain Lines

Location: The pipelines run in an east-west direction with north-south lines connecting to the individual facilities. Several manhole access points are located along the length of the system.

Related Sites/Structures: The site is associated with the 116-D-8 Cask Storage Pad, 183-DR, the 183-DR Clearwell Area, the 105-DR Reactor Buildings, and the 1907-DR Outfall (100-D-8).

Process Description: This site was used to dispose of nonradioactive waste water from water treatment facilities associated with the 100-DR Reactor. These pipelines discharged to the 100-D-8 (1907-DR) Outfall just upstream of the 181-D Building. The 100-D-8 (1907-DR) Outfall and the facilities connected to this system are not addressed by this site, nor are the 100-D-56 sodium dichromate pipelines.

Waste Type: Water

Waste Description: The waste is steel pipelines, concrete, and soil (if contaminants are present). Chemical additives to reactor cooling water included aluminum sulfate (alum) with excess hydrated calcium oxide, sulfuric acid, chlorine, and sodium dichromate. Water pH was maintained at about 7.5, free chlorine residual was about 0.2 milligrams/liter, and sodium dichromate was added at a rate of about 2 milligrams per liter. Water and chemical storage tank overflows and other drains discharged to this disposal system. Drawings indicate that it also received storm drainage from the 183-DR Tank Clearwell Basin. Sodium dichromate was used to treat reactor cooling water to assist in the control of process tube corrosion. Sodium dichromate storage tanks may have discharged to this system and potentially act as a source of elevated chromium found in the 100-D groundwater. However, unless there was a deliberate discharge of sodium dichromate to the system, only very dilute discharges would have occurred.

This Site has the Following SubSites:

Code: 100-D-50:1

Names: 100-D-50:1; Emergency Discharge Pipeline

Code: 100-D-50:2

Names: 100-D-50:2; Reactor Cooling Water Pipelines from 190-DR Pumphouse

Code: 100-D-50:3

Names: 100-D-50:3; Reactor Cooling Water Pipelines from 190-D High Bay

Code: 100-D-50:4
Names: 100-D-50:4; Gas Recirculation Pipelines (Unused)

Code: 100-D-50:5
Names: 100-D-50:5; 183-DR Sedimentation Basin Drain Pipelines

Code: 100-D-50:6
Names: 100-D-50:6; 183-DR Clearwell Drain Pipelines

Code: 100-D-50:7
Names: 100-D-50:7; 183-DR Head House Floor Drain and Catch Basins Pipelines

Code: 100-D-50:8
Names: 100-D-50:8; 117-DR Condensate Drain Pipelines

Code: 100-D-50:9
Names: 100-D-50:9; 1607-DR3 Sanitary Sewer Pipelines

Code: 100-D-50:10
Names: 100-D-50:10; Construction Camp Potable Water Supply Pipelines

Code: 100-D-50:1 **Classification:** Accepted
Names: 100-D-50:1; Emergency Discharge Pipeline **Reclassification** Interim Closed Out (3/22/2013)
Type: Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The 100-D-50:1 subsite has been remediated and Interim Closed Out. It encompassed the process and storm sewer collection main for the southern portion of the 100-D/DR Area. It was also intended to serve as an emergency discharge pipeline for the 105-DR reactor. The 100-D-50:1 pipeline included approximately 1,550 meters (5,100 ft) of reinforced concrete pipeline. The line began as a 1.07 meter (42 in) pipeline in the 105-DR Reactor Building footprint. It transitioned to a 1.37 meter (54 in) pipeline upstream of the 183-DR clearwell process sewer (100-D-50:6 subsite) influent manhole (MH T-2a). It increased to a 1.83 meter (72-in.) pipeline upstream of the 183-DR sedimentation basin process sewer (100-D-50:5 subsite) influent manhole (MH T-3). The pipeline terminated at the 100-D-8 outfall. The 100-D-8, 105-DR Process Sewer Outfall Site was remediated in 2011, and the waste site was reclassified to Interim Closed Out on August 2, 2012.

Location: The 100-D-50:1 Emergency Discharge Pipeline traveled from the west side of the 105-DR Reactor, south of the 183-DR Clearwells, and ultimately ended at the 100-D-8 Outfall. The pipeline invert was located 7 to 9.5 meters (23 to 31 ft) below grade, sloping down towards the point of discharge.

Related Sites/ Structures: The pipeline was associated with 105-DR and the 100-D-8 outfall structure.

Process Description: In addition to servicing the 105-DR Reactor Building, the 100-D-50:1 pipeline received discharges from the process and storm sewers associated with the 100-DR water treatment facilities (addressed as the 100-D-50:5 and 100-D-50:6 subsites). These facilities used physical and chemical treatment to condition raw water for reactor use. Chemical addition included sulfuric acid, lime, chlorine, commercial coagulants containing primarily ferrous sulfate or alum, sodium silicate, and sodium dichromate. Discharges to the process sewers presumably consisted primarily of stormwater runoff, backwash water, and underflow drainage from the water treatment units. However, discharges of concentrated chemical products to these sewers likely also occurred.

Waste Type: Not Specified

Waste Description: The waste was contaminated steel piping, concrete, and soil.

Closure Info: Interim (3/22/2013): Confirmatory sampling at the 100-D-50:1 subsite was performed in four test pits from December 2005 to January 2006, and again in April 2006, to collect data to support a determination if remedial action would be required at the subsite. The test pits were adjacent to manholes MH T-6, T-2a, T-3 and T-1. Based on the confirmatory sampling, it was recommended that the pipeline be remediated downgradient from manhole MH T-2a (aka Service Area 2).

Remediation of Service Area 2 of the 100-D-50:1 emergency discharge pipeline was performed from February 14 through March 6, 2012. The excavation extended to a depth of 7.5 meters (25 ft) below ground surface along the length of the pipeline. Approximately 17,000 bank cubic meters (22,000 bank cubic yards) of overburden material was placed in five stockpiles. Approximately 1,350 BCM (1,800 BCY) of potentially contaminated soil, concrete, and piping was excavated and stockpiled in one Spoil Pile Area (SPA) east of the excavation and one SPA to the south of the excavation and later disposed at the Environmental Restoration Disposal Facility. No anomalous materials were encountered during the excavation.

The SubSite is Part Of:

Code: 100-D-50

Names: 100-D-50; 100-DR Water Treatment Facilities Underground Pipelines

Code: 100-D-50:2

Classification: Accepted

Names: 100-D-50:2; Reactor Cooling Water Pipelines from 190-DR Pumphouse

Reclassification: None

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The 100-D-50:2 subsite consists of the residual process cooling water supply lines between the 183-DR clearwells and the 105 DR Reactor Building.

The administrative boundaries for the 100-D-50:2 pipelines encompass those process supply lines from the points of discharge at the former 183-DR clearwells to the boundaries of demolition of the 190-DR Pumphouse and from the points of discharge from the 190-DR valve houses to the boundaries of interim safe storage activities at the 105-DR Reactor Building. The pipelines formerly connecting these two groups have been removed as part of decommissioning and demolition of the 190-DR facility. Residual supply piping within the boundaries of the interim safe storage project has been encased in concrete.

The process lines upstream of the former 190-DR Pumphouse consist of four 0.61-m (24-in.) subsurface steel pipelines. Downstream of the 190-DR facility, these pipelines are housed in two separate tunnels that converge upstream of the 105-DR Reactor Building. Several small diameter water lines are also located in the pipe tunnels, including raw water, filtered water, fire protection water, and potential dichromate-treated process water piping. Raw water, fire protection water piping, and filtered water piping are expected to be part of the 100-D/DR clean water/service water pipelines (100-D-63 waste site). This functional pipeline group has been rejected from consideration as a WIDS site based on process knowledge at other production reactor areas (100-B-7, 100-C-5, 100-H-35, and 100-K-59), but potential process water lines (i.e., the lines labeled "SOUTH RISER," "NORTH RISER," "SOUTH PROCESS WATER," and "NORTH PROCESS WATER") will be considered as part of the 100-D-50:2 subsite.

Location: The 100-D-50:2 pipelines are located between the former 183-DR Clearwells and 190-DR Pumphouse and the former 190-DR Pumphouse and 105-DR Reactor Building. The pipelines downstream of the former 190-DR facility are located within subsurface pipe tunnels.

Waste Type: Not Specified

Waste Description: The waste is any potentially contaminated pipelines.

The SubSite is Part Of:

Code: 100-D-50

Names: 100-D-50; 100-DR Water Treatment Facilities Underground Pipelines

Code: 100-D-50:3	Classification: Accepted
Names: 100-D-50:3; Reactor Cooling Water Pipelines from 190-D High Bay	Reclassification: Rejected (9/26/2012)
Type: Process Sewer	Start Date: 5/1/1950
Status: Inactive	End Date: 7/1/1950

Description: This subsite has been evaluated and reclassified to Rejected on form 2012-067. It consists of steel piping, within a subsurface concrete pipe tunnel, designed to deliver treated cooling water from the 190-D High Bay to the 105-DR Reactor. The pipelines were used only during startup testing between May and July 1950. The pipeline tunnels provide habitat for maternal colonies of bats. There is also evidence of pigeon roosting and nesting.

Location: These pipelines extend southeast from the 190-D Building Annex to the 105-DR Reactor.

Process Description: These pipeline were designed to carry clean, treated (with sodium dichromate) water from the 190-D pump house to the 105-DR Reactor. The pipelines were used only during startup testing between May and July 1950 (HW-17971, HW-18473).

The SubSite is Part Of:

Code: 100-D-50

Names: 100-D-50; 100-DR Water Treatment Facilities Underground Pipelines

Code: 100-D-50:4	Classification: Accepted
Names: 100-D-50:4; Gas Recirculation Pipelines (Unused)	Reclassification: Interim Closed Out (8/2/2012)
Type: Process Sewer	Start Date: 1/1/1950
Status: Inactive	End Date: 1/1/1964

Description: The waste site has been remediated and Interim Closed Out. The subsite consisted of the steel piping inside the subsurface tunnel between the former 115-D Gas Recirculation Facility and the 105-DR Reactor. The 100-D-50:4 subsite was composed of two 0.41 meter (16 in.) diameter, steel pipelines with a combined length of approximately 270 meter (900 ft). These pipelines presently exist within the collapsed subsurface tunnel between the former 115-D/DR Gas Recirculation Facility and the 105-DR Reactor. Characterization of analogous pipelines in the gas recirculation wing of the 105-H Reactor revealed the accumulation of oil sludge containing multiple radionuclides at levels above remedial action goals (RAGS).

In a 4/19/2005 Remove, Treat, and Dispose Report, based on a review of historical site

information and analogous analytical data, it was cited that this subsite contained hazardous constituents at levels in exceedance of RAGs. Remedial action was recommended for this site in accordance with the ROD (EPA, 1999).

Location: The 100-D-50:4 subsite is south of the former 115-D/DR facility, between the 105-D and 105-DR Reactors.

Process Description: Operational use of the 105-DR Reactor equipment and 100-D-50:4 pipelines began in 1950 and ceased in 1964. The 115-D/DR facility was decommissioned in 1985 and 1986. The 100-D-50:4 pipelines were buried in situ (with a portion of the demolition rubble from the 115-D/DR facility) when the pipeline tunnel roofs were collapsed into the tunnels.

Waste Type: Not Specified

Waste Description: The waste is the pipelines and any contaminated soil associated with this site.

Closure Info: Interim (8/2/2012): Remediation of the 100-D-50:4 gas recirculation pipelines and tunnels was performed from May 5, 2011, through July 12, 2011. The excavation extended to a depth of 3.5 meters (11.5 ft) below ground surface. Approximately 370 cubic meters (13,000 cu. ft.) of contaminated soil, concrete, and piping was excavated and loaded for disposal at the Environmental Restoration Disposal Facility (ERDF). The excavation was approximately 3.5 meters (11.5 feet) deep. No anomalous materials were encountered during the excavation. Waste material was stockpiled in a staging pile area east of the excavation prior to disposal at ERDF. No overburden material was associated with the subsite.

The SubSite is Part Of:

Code: 100-D-50

Names: 100-D-50; 100-DR Water Treatment Facilities Underground Pipelines

Code: 100-D-50:5

Classification: Accepted

Names: 100-D-50:5; 183-DR Sedimentation Basin Drain Pipelines

Reclassification: Interim No Action (11/6/2007)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The subsite has been evaluated and determined to require No Action. It encompassed the southern process sewers for the 183-DR coagulation and sedimentation basins, The subsite consisted of approximately 200 meters (650 feet) of pipeline: three 0.15-meters (6-inches) drain lines immediately south of the former 183-DR coagulation and sedimentation basins, which discharged to a 0.30-meter (12-inch) reinforced concrete collection line, trending generally north-south. A 0.30-meter (12-inch) feeder line also connected a runoff collection drain (catch basin U) to the collection line.

Located on the southern side of the 183-DR facility, these sewers were designed to provide underflow drainage for the 183-DR coagulation and sedimentation basins and possibly overflow drainage as well. Several surface runoff collection drains for the area south of the 183-DR facility also discharged to this sewer. The subsite process sewers discharged to the 100-D-50:1 process sewer collection line, which ultimately discharged to the Columbia River at the 100-D-8 outfall. Additional drainage for the 183-DR basins was also provided by higher capacity process sewers on the northern side of the 183-DR facility (100-D-50:7 subsite).

Location: The 100-D-50:5 process sewers are on the south side of the 183-DR facility.

Process Description: As part of the coolant water treatment facilities for the 105-DR Reactor, the 183-DR coagulation and sedimentation basins used physical and chemical treatment to condition raw river water for reactor use. The chemicals added at the 183-DR coagulation basins or at the upstream 183-DR Headhouse included: sulfuric acid, lime chlorine, and commercial coagulants containing primarily ferrous sulfate or alum. Sodium dichromate was also added to cooling water as a corrosion inhibitor, but was injected downstream of the sedimentation basins.

Waste Type: Not Specified

Waste Description: The waste is the pipelines, pipeline sediments, and any contaminated soil associated with this site.

Closure Info: Interim: Confirmatory samples were collected from test pits in November and December 2005. The analytical results from the subsite pipe sediment and underlying soil samples were shown to meet the remedial action objectives for direct exposure, groundwater protection, and river protection.

The SubSite is Part Of:

Code: 100-D-50

Names: 100-D-50; 100-DR Water Treatment Facilities Underground Pipelines

Code: 100-D-50:6

Classification: Accepted

Names: 100-D-50:6; 183-DR Clearwell Drain Pipelines

Reclassification: Interim Closed Out (6/11/2013)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This subsite has been remediated and Interim Closed Out. The site included three functional groups of piping at the 183-DR Clearwells: (1) process sewers that provided underflow and overflow drainage for the 183-DR Clearwells and drainage for proximate runoff catch basins, (2) process supply lines from the 183-DR Filter Building, and (3) drainage lines for the 190-DR Pumphouse tunnel floor drains. The 100-D-50:6 subsite and remedial action recommendation was expanded to include the circular, concrete clearwell pads.

Location: This site is directly east of the 183-DR Water Treatment Facility (demolished) and west of 190-DR. It is southwest of the 105-DR Reactor Building.

Process Description: The 183-DR Clearwells were part of the coolant water treatment facilities. The function of these facilities was to provide storage and chemical contact time for river water conditioned for use in reactor cooling. The chemicals added upstream of the clearwells included sulfuric acid, lime, chlorine, and commercial coagulants including ferrous sulfate, alum, or polymeric flocculants to coagulate suspended solids in the water before filtration.

Waste Type: Not Specified

Waste Description: The waste includes piping, concrete pads and surrounding contaminated soils.

Closure Info: Interim (6/11/2013): Remediation of the 100-D-50:6 subsite was performed from March 11, 2011, through May 28, 2012, to a depth of approximately 9 meters (30 ft). Approximately 49,975 bank cubic meters (BCM) (65,365 bank cubic yards [BCY]) of contaminated soil, concrete, and piping was excavated for disposal at the Environmental Restoration Disposal Facility (ERDF). A majority of the waste was direct loaded for shipment to Environmental Restoration Disposal Facility (ERDF). However, a portion of the waste was stockpiled separately, prior to shipment and disposal at ERDF. Approximately 31,400 BCM (41,070 BCY) of soil (overburden) was removed and stockpiled for evaluation for use as clean backfill.

Additional remediation was conducted from January 21 through 24, 2013. Approximately 180 BCM (235 BCY) of additional soil was removed from the Pipe 4 location within the excavation area on January 21 and 22, 2013, and disposed at ERDF. Approximately 100 BCM (131 BCY) of contaminated soil was removed from the Staging Pile Area (SPA) 8 location on January 24, 2013, and placed into the deep zone of the 100-D-50:6 excavation with regulatory concurrence. The removal of extra material from these two locations did not change the original boundary for either decision unit and the original sample locations were utilized. A sample in the overburden decision unit (OB-8) also exceeded RAGs for PAH, but soil from this location was placed in the deep zone at least 4.6 meters (15 ft) below ground surface within the 100-D-50:6 excavation during site backfill and therefore does not require additional remediation. The vadose zone underlying the excavation is approximately 15 meters (50 ft).

Additionally, approximately 58,674 liters (15,500 gal) of water from inside the pipelines was removed and disposed at the Effluent Treatment Facility (ETF) in 200 East Area.

The SubSite is Part Of:

Code: 100-D-50

Names: 100-D-50; 100-DR Water Treatment Facilities Underground Pipelines

Code: 100-D-50:7

Classification: Accepted

Names: 100-D-50:7; 183-DR Head House Floor Drain and Catch Basins Pipelines

Reclassification Interim Closed Out (5/8/2014)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The subsite was remediated and Interim Closed Out. It included the pipelines that provided drainage for the 183-DR Coagulation Basins, floor drains and catch basins at the 183-DR Head House, and mixing tanks in the vicinity of the 186-D Waste Acid Reservoir. These pipelines ultimately discharged to the 100-D Area process sewer systems.

The sewers for the 183-DR Head House floor drains, 183-DR Coagulation and Sedimentation Basins, and nearby catch basins included 82 meters (269 ft) of 0.20 meter (8 in.) vitrified clay pipe (VCP), 40 meters (131 ft) of 0.25 meter (10 in.) VCP, 36 meters (118 ft) of 0.51-m (20-in.) cast iron pipe, 158 meters (518 ft) of 0.69 meter (27 in.) reinforced concrete pipe (RCP), 332 meters (1,089 ft) of 1.37 meter (54 in.) reinforced concrete pipe (RCP). The piping for the 186-D Mixing Tank process sewer included 90 meters (295 ft) of 0.61 meter (24 in.) VCP.

Location: These pipelines extend from the 183-DR Head House northward to the 186-D Building.

Waste Type: Not Specified

Waste Description: The waste is any potentially contaminated pipelines.

Closure Info: Interim (5/8/2014): Confirmatory sampling of the 100-D-50:7 subsite was performed from November 9 to December 28, 2005.

The 100-D-50:7 excavation boundary had an excavation depth of approximately 7 meters (23 ft). During remediation of the 100-D-50:7 subsite, all of the pipeline was remediated except for the portion of Service Area 3 in which a 7 meters (23 ft) section of pipe was left in place beneath the 183-DR foundation. Clean overburden was removed and stockpiled. The stockpiles consisted of mixed cobble and fine- to coarse-grained soils. Also observed was a large amount of coarse-grained black soils. Between August 8, 2011, and April 25, 2013, approximately

5,700 BCM of soil was excavated and sent to the ERDF and 5,300 BCM of overburden soil was excavated from the 100-D-50:7 subsite to the 100-D-50:7 stockpiles to be used as clean backfill material. No anomalies were found during this time.

Three other excavations overlapped the 100-D-50:7 subsite excavation. The north 27 meters (89 ft) of the 100-D-50:7 subsite was removed during the 100-D-31:9 subsite excavation. All verification samples taken in this area attained remedial action objectives (RAOs) per the 100-D-31:9 Remaining Sites Verification Package (RSVP). The southern end of 100-D-50:7 subsite pipeline was remediated during the excavation of 100-D-62, 100-D-77, and 100-D-83:1. A majority of the 100-D-50:7 subsite pipeline and underlying soil was within the 100-D-100 waste site boundary and was removed with the 100-D-100 excavation. Seven meters (23 ft) of pipe was left in place beneath the 183-DR foundation.

The SubSite is Part Of:

Code: 100-D-50

Names: 100-D-50; 100-DR Water Treatment Facilities Underground Pipelines

Code: 100-D-50:8

Classification: Accepted

Names: 100-D-50:8; 117-DR Condensate Drain Pipelines

Reclassification: Interim Closed Out (1/2/2013)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The 100-D-50:8 subsite has been remediated and Interim Closed Out. It was a 10 centimeter (4 in) diameter, nonfriable asbestos cement distribution pipe that connected the 117-DR Filter Building to the 116-DR-8 Seal Pit Crib. The distribution pipe had a total length of 83 meters (272 ft) and operated independently from all other pipelines. The distribution pipe received radioactive process effluent from the 117-DR HEPA Filter Building.

Location: The 117-DR Filter Building was located south of the 105-DR Reactor Building. The pipeline and crib are located south of 117-DR Filter Building.

Process Description: Although the 100-D-50 pipelines generally did not transport radioactive liquids, this distribution pipe received radioactive process effluent from the 117-DR HEPA Filter Building. The 117-DR HEPA Filter Building, which was later used for the 105-DR Large Sodium Fire Facility (LSFF), was demolished in 2004, and the 116-DR-8 Seal Pit Crib was filled with gravel and covered with clean soil. The distribution pipe was used from 1960 to 1964 in support of reactor operations. It transferred water that collected in the seal pits as part of the exhaust filter system at the 117-DR HEPA Filter Building to the 116-DR-8 Crib. The distribution pipe was then used from 1972 through 1986 in support of the 105-DR LSFF. The LSFF was subject to the regulatory requirements for the storage and treatment of dangerous waste and was included in the Hanford Facility Dangerous Waste Part A Permit Application (DOE-RL 1998). The LSFF was divided into seven areas according to use and deposition of reaction by-products for closure evaluation as described in the 105-DR Large Sodium Fire Facility Closure Plan. Area 6 consisted of the 116-DR-8 Crib and the connecting distribution pipe. In 1996, the Washington State Department of Ecology (Ecology) identified that Area 6 was believed not to have received dangerous waste and was considered closed for the purposes of WAC 173-303.

Waste Type: Not Specified

Waste Description: The waste is potentially contaminated piping and soil.

Closure Info: Interim (1/2/2013): Geophysical survey results, process knowledge, historical drawings, and site visit information were used to develop confirmatory sampling designs for the 100-D-50:8

and 116-DR-8 waste sites.

The sample designs included collection of samples from the pipeline at the point of discharge to the crib and at an upstream bend and collection of soil samples from beneath the pipeline and crib. Excavation at the bend in the 100-D-50:8 pipeline located a concrete thrust block and the intact pipeline at approximately 0.9 meters (3.5 ft) below ground surface (bgs). The pipeline was breached at the downstream side of the thrust block, and minimal visible scale was noted in the lower third of the pipeline.

Remediation of the 100-D-50:8 waste subsite was performed on April 11 and 12, 2012. The excavation extended to a depth of 3.3 meters (10 ft) bgs. Approximately 720 bank cubic meters (BCM) (941.7 bank cubic yards [BCY]) of contaminated soil, concrete, and piping was excavated and staged in a stockpile area before disposal at the Environmental Restoration Disposal Facility (ERDF). Approximately 70 meters (230 ft) of pipe was also removed during remediation and disposed at the ERDF. The remaining portion of the 100-D-50:8 pipeline (approximately 13 meters [42 ft]) was removed during remediation activities of the 116-DR-8 waste site. During the 100-D-50:8 excavation, two additional pipeline segments from the 100-D-63, 100-D/DR Service Water Pipeline were discovered. One of the two segments was removed, because it was impeding the 100-D-50:8 remediation campaign, and one segment was left in place. A post-excavation civil survey was completed on April 24, 2012. In June and July 2008, a portion of the 100-D-50:8 pipelines was removed during the 116-DR-8 excavation. This area underwent verification sampling as part of the 116-DR-8 waste site.

The SubSite is Part Of:

Code: 100-D-50

Names: 100-D-50; 100-DR Water Treatment Facilities Underground Pipelines

Code: 100-D-50:9

Classification: Accepted

Names: 100-D-50:9; 1607-DR3 Sanitary Sewer Pipelines

Reclassification: Interim Closed Out (1/17/2013)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The 100-D-50:9 site has been remediated and Interim Closed Out. It encompassed two functional pipeline groups: (1) the overflow drain line and (2) the residual sanitary sewer lines. The overflow drain line began north of the 105-DR Reactor Building, traveled south along the western side of the building, and turned west to join the sanitary sewage system. The sanitary sewer cut across the southeast corner of the 116-D-8 cask storage pad and was accessible through a manhole set in the concrete pad. For remediation purposes, the subsite was divided into two Service Areas. Confirmatory sample results determined Service Area 1 met the remedial action objectives. Confirmatory sample results determined Service Area 2 required remediation.

The Hanford Site Waste Management Units Report (DOE/RL-88-30) stated the pad was designed with a drain to facilitate pad decontamination and rain runoff, and the drain discharged into the 105-DR sewer (100-D-50:9). The residual sanitary sewer lines are located south and southeast of the 105-DR Reactor Building. Both pipeline functional groups discharged into the 100-D-13 septic tank. Although sections of the former sewer system have been removed under past Group 3 remedial efforts for coexistent sites (the 116-DR-6 Liquid Disposal Trench and the 100-D-48 Reactor Cooling Water Effluent Underground Pipelines), excavations for confirmatory sampling established that portions of the 100-D-50:9 pipelines still remain.

During remediation of 118-D-5 Burial Ground (CVP-2009-00008) a concrete junction vault

located in the southern portion of the burial ground was opened prior to the start of the burial ground excavation and found to contain a breached 15-cm (6-in.) vitrified clay pipe. The pipeline was part of the 100-D-50:9, 1607-DR-3 Sanitary Sewer. The concrete junction vault and pipe located within the excavation were removed for disposal to ERDF.

Location: The overflow drain line (1) was located north of the 105-DR Reactor Building and ran south along the western side of the building, and then turned west to join the sanitary sewage system. The residual sanitary sewer lines (2) were located in the south and southeast sides of the 105-DR Reactor Building.

Process Description: 100-D-50:9 encompassed two functional pipeline groups: (1) the overflow drain line and (2) the residual sanitary sewer lines. Both functional groups discharged to the 100-D-13 septic tank.

Waste Type: Not Specified

Waste Description: The waste is the pipelines, pipeline sediments, and any contaminated soil associated with this site.

Closure Info: Interim (1/17/2013): A stratified sampling strategy was employed to address the 100-D-50:9 subsite as two Service Areas. These Service Areas were determined based on the principles of hydraulics and the potential impact of different waste loading across the system. Service Area 1 was the piping near the 105-DR reactor building. Service Area 2 was located east and southeast of 105-DR reactor. The confirmatory sample design included the excavation of three test pits along the 100-D-50:9 pipelines in order to access the pipe sediment and underlying soil. Two of the test pits were located within Service Area 2. Each test pit was excavated at an unlabeled manhole associated with the pipelines. Confirmatory samples were collected on November 7, 2005. Excavations within the two Service Areas confirmed that portions of the former construction camp sewer lines and elevated water tank drain line still remain. The results of the confirmatory sampling determined that Service Area 1 did not require remedial action because it achieved the established remedial action objectives. The confirmatory samples collected in Service Area 2 exceeded the remedial action levels for mercury and hexavalent chromium, pesticides, SVOCs, aroclor-1260, and cesium-137. A remedial action was planned for Service Area 2.

The 100-D-50:9 subsite (Service Area 2), was remediated between January 25 and March 30, 2011. Approximately 1,800 bank cubic meters (BCM) (2,354 bank cubic yards [BCY]) of overburden material was stockpiled and sampled for use as clean backfill material. Approximately 287 linear meters (942 linear feet) of pipeline was removed from the 100-D-50:9 subsite, resulting in approximately 565 BCM (739 BCY) of soil and piping removed and staged in a staging pile area for subsequent disposal at the Environmental Restoration Disposal Facility. Final loadout of material was completed in June 2011. The deepest part of the excavation extended to approximately 4 meters (13 ft) below ground surface. No anomalous materials were encountered during the remedial action activities.

The SubSite is Part Of:

Code: 100-D-50

Names: 100-D-50; 100-DR Water Treatment Facilities Underground Pipelines

Code: 100-D-50:10

Classification: Accepted

Names: 100-D-50:10; Construction Camp Potable Water Supply Pipelines

Reclassification: Interim No Action (6/29/2005)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This subsite has been evaluated and determined to require No Action. It consists of the residual cast iron pipelines used to supply potable water to the temporary construction camp southeast of the 105-DR Reactor. The exact operational period of the subsite is uncertain, but is believed to be limited to 1947 to 1949 when the construction camp was in use. The system was supplied with water via the fire protection loop piping, which in turn was supplied by the 100-D Area water treatment train at a point prior to any chemical treatment. The subsite is composed of approximately 680 meters (2,220 ft) of 0.15-meter (6-in.) cast iron pipe around the northern, eastern, and southeastern sides of the 105-DR Reactor. Portions of the former supply system were removed under past Group 3 remedial efforts for coexistent sites (the 116-DR-6 Liquid Disposal Trench and the 100-D-48 Reactor Cooling Water Effluent Underground Pipelines). No evidence has been located to suggest that operation of these sites impacted the 100-D-50:10 pipelines beyond the boundaries of previous remedial efforts.

Location: These pipelines are on the north, east, and south sides of the 105-DR Reactor.

Closure Info: Interim: The pipelines provided potable water to the temporary construction camp, located southeast of the 105-DR reactor. The 100 Area Remedial Action Sampling and Analysis Plan identifies contaminants of potential concern (COCs) for the 100-D-50 pipelines, but they were not applicable to this subsite due to the operational history of the pipelines. Process knowledge provides no basis for the introduction of any hazardous or dangerous wastes to these pipelines. Therefore, no further evaluation or confirmatory sampling was necessary for this subsite.

The SubSite is Part Of:

Code: 100-D-50

Names: 100-D-50; 100-DR Water Treatment Facilities Underground Pipelines

Code: 100-D-52

Classification: Accepted

Names: 100-D-52; 105-D Downcomer Insulation Space Dry Well

Reclassification: Interim Closed Out (11/8/2000)

Type: French Drain

Start Date: 1/1/1955

Status: Inactive

End Date:

Description: This site has been remediated and Interim Closed Out. The waste site consisted of a french drain (dry well). The 1 meter (3 foot) diameter dry well was filled with 2.2 meters (5 feet) of 2.5 to 5-centimeter (1 to 2-inch) gravel from the bottom at 6.9 meters (22 feet) below grade to the top at 5.2 meters (17 feet) below grade. The dry well was fed by a 10.2-centimeter (4-inch) steel drain pipe from Room 38A that entered the dry well at 5.8 meters (19 feet) below grade. The drain line discharged into the annulus between a vertical 25.4-centimeter (10-inch) diameter distributor pipe and vertical 10.2-centimeter (4-inch) diameter radiation monitor housing pipe in the center of the dry well. The monitor was used to ensure detection of radiation in the water (condensate or cooling water leakage) from Room 38A. (Room 38A of the 105-D Building is the concrete enclosure for the 105-D Downcomer.) The concentric distributor pipe and radiation monitoring housing pipe ended 30 centimeters (1 foot) above the bottom of the dry well. The radiation monitor pipe extended about 0.6 meters (2 feet) above grade with a valve on the upper end.

Location: The site was located next to the 105-D Reactor Building at Washington Coordinate System (WCS83S) Easting 573797.076, Northing 151625.344.

Related Sites/ Structures: The site was related to 105-D Reactor Building Room 38A.

Process Description: This drywell was installed in 1955 to drain non-contaminated condensate water and contaminated cooling water from the space between the 100-D Reactor process effluent

downcomer and the reactor wall. The contaminated cooling water resulted from potential leakage from the downcomer (a metal baffled structure through which collected reactor cooling water cascaded prior to entry into the effluent discharge line). This site also contained a pipe providing access for radiation monitoring that extended from the bottom of the drywell to just above grade.

Waste Type: Water

Waste Description: No record could be found that indicated any radiological or chemical contamination data. Based on available information it was assumed that contamination would be limited to those radionuclides found in reactor effluent water that potentially leaked from the metal downcomer and collected nonradioactive condensate water. The COPCs for the remedial action were developed in the Sampling and Analysis Plan.

Closure Info: Interim (11/8/2000): Remedial action began on January 4, 2000. The excavation involved removing the overburden materials, the contaminated structure, and underlying contaminated soil. Contaminated materials were disposed at ERDF. On February 25, 2000, the excavation reached the design limit at elevation 134.9 meters (443 feet).

At the completion of remedial action the excavation was approximately 415 square meters (4,467 square feet) in area with a maximum depth of approximately 7.6 meters (25 feet). Approximately 199 metric tons (219 tons) of material from the site were disposed at ERDF. The excavation will be backfilled with appropriate materials to the reference grade of elevation 142.5 meters (468 feet).

Code: 100-D-56 **Classification:** Accepted

Names: 100-D-56; 100-D Area Sodium Dichromate Underground Supply Lines **Reclassification:** Interim Closed Out (4/5/2012)

Type: Product Piping **Start Date:**

Status: Inactive **End Date:**

Description: Both subsites have been Interim Closed Out, so 100-D-56 is also Interim Closed Out. The site consisted of two abandoned 7.6-centimeter (3-inch) underground sodium dichromate supply lines that transported concentrated liquid sodium dichromate between the 108-D, 185-D, 189-D, 190-D, 183-DR, and the 100-D Sodium Dichromate Transfer Station. The sodium dichromate and sodium silicate supply lines exited the 185-D/190-D Building complex running parallel to each other. One set (100-D-56:1) traveled north and east to the 108-D Building, and one set (100-D-56:2) traveled south and west to the vicinity of the 100-D-12 Sodium Dichromate Pumping Station. The 100-D-56:2 chemical supply lines continued west from the vicinity of the 100-D-12 Sodium Dichromate Pumping Station and then turn south to the 183-DR Building.

Location: The underground lines run between the former 108-D, 185-D, 189-D, 190-D, 183-DR Buildings, and the 100-D Sodium Dichromate Transfer Station. The north pipeline exited the north side the 190-D Pump Room and flowed to the west side of 108-D. 183-D Filter Plant - 7.62 centimeter (3 inch) line exits west side and flows south to near the 100-D-12 pump station 183-DR - Two 7.62 centimeter (3 inch) lines exit the west side of 183-DR Head House and flow east to 185-D.

Related Sites/ Structures: Portions of these lines are co-located with the lines in the 100-D-92 encasement.

Process Description: The heat generated during reactor operation was removed by pumping cooling water continuously through the reactors. Cooling water was pumped from the Columbia River at the 181-D River Pump House. The water was purified and treated in the 182-D Reservoir and

Pump House and in the 183-D Filter Building, deaerated in the 185-D Plant, and then cooled in the 189-D Refrigeration Building. Water then flowed into the 190-D Process Pump House and was delivered to the front risers of the reactor building. Water treatment chemicals were added to prevent excessive corrosion of the slugs or process tubes, excessive film formation on the slugs and tubes, and excessive effluent water radioactivity. Aluminum sulfate, ferric sulfate, sodium silicate, sulfuric acid, chlorine, lime, sodium dichromate, and diatomaceous earth were stored, mixed, and used in the water treatment process.

The 100-D-56 supply lines transported sodium silicate and sodium dichromate solutions. Sodium silicate was used as a coagulation aid to increase the rate of flocculent formulation and to produce a flocculent with stronger filtering characteristics. Sodium silicate was also used to minimize the radionuclides reaching the Columbia River in the reactor effluent water. Sodium dichromate was commonly used as a corrosion inhibitor in reactor coolant solutions. The chemicals were unloaded from railcars in either bags or barrels. Sodium dichromate was received in crystalline form, dissolved in water, and diluted to a 10% to 15% dichromate solution then transferred to feed tanks in the 105-D and 185-D Buildings. Sufficient sodium dichromate was added to reactor cooling water so that the instantaneous concentration was 2.0 ppm as required by the reactor cooling water specifications. Sodium dichromate was pumped from the 108-D Building through two different pipelines. One 7.6 cm (3 in.) diameter overhead pipeline connected to the 105-D Reactor. The other sodium dichromate pipeline was a below grade 7.6 cm (3 in.) diameter pipeline that exited the 108-D Building on the west side in combination with a parallel 7.6 cm (3 in.) diameter pipeline that transferred sodium silicate to the north side of the 185-D Building. These mixed solutions were injected into the process water systems at the 105-D Reactor and 185-D Building.

When the transfer of the sodium dichromate system from the 108-D Building to the 185-D Building was completed, the use of dry material handling was replaced with use of concentrated liquid sodium dichromate that was delivered by railcar and truck to an unloading facility/pumping station (100-D-12). The sodium dichromate pumping station was located south of the 183-D Building, next to the railroad tracks. A 7.6 cm (3 inch) diameter underground line provided the means to pump stock solution to storage tanks in the 185-D Building.

Waste Type: Equipment

Waste Description: The waste is abandoned 7.6-centimeter (3-inch) pipe contaminated with sodium dichromate.

This Site has the Following SubSites:

Code: 100-D-56:1

Names: 100-D-56:1; North Portion of the 100-D Area Sodium Dichromate Underground Supply Lines

Code: 100-D-56:2

Names: 100-D-56:2; South Portion of the 100-D Area Sodium Dichromate Underground Supply Lines

Code: 100-D-56:1

Classification: Accepted

Names: 100-D-56:1; North Portion of the 100-D Area Sodium Dichromate Underground Supply Lines

Reclassification: Interim Closed Out (4/5/2012)

Type: Product Piping

Start Date:

Status: Inactive

End Date:

Description: This subsite has been reclassified to Interim Closed Out. The 100-D-56 site consisted of two abandoned 7.6 cm (3 in) underground pipelines that transported sodium silicate and sodium dichromate liquids between the 108-D, 190-D, 185-D, and 189-D facilities; the 100-D-12

Sodium Dichromate Pumping Station; and the 183-DR Building. The sodium dichromate and sodium silicate supply lines exited the 185-D/190-D Building complex running parallel to each other. One set (100-D-56:1) traveled north and east to the 108-D Building, and one set (100-D-56:2) traveled south and west to the vicinity of the 100-D-12 Sodium Dichromate Pumping Station. The 100-D-56:2 chemical supply lines continued west from the vicinity of the 100-D-12 Sodium Dichromate Pumping Station and then turn south to the 183-DR Building.

100-D-56:1 site addresses the northern portion of the pipeline. The pipelines exiting the north side of the 185-D Building were used during the initial dry material handling operations. The pipeline ran from 190-D to 108-D. The total length was approximately 272 meters (892 feet).

Location: The northern portion of the 100-D-56 pipeline ran from the 108-D Building to the 185-D Building. The 108-D Building was located north of the 105-D Reactor and east of the 1709-D Building. The 185-D Building was located west of the 105-D Reactor.

Process Description: The 100-D-56 supply lines transported sodium silicate and sodium dichromate solutions. Sodium silicate was used as a coagulation aid to increase the rate of flocculent formulation and to produce a flocculent with stronger filtering characteristics. Sodium silicate was also used to minimize the radionuclides reaching the Columbia River in the reactor effluent water. Sodium dichromate was commonly used as a corrosion inhibitor in reactor coolant solutions. The chemicals were unloaded from railcars in either bags or barrels. Sodium dichromate was received in crystalline form, dissolved in water, and diluted to a 10% to 15% dichromate solution then transferred to feed tanks in the 105-D and 185-D Buildings. Sufficient sodium dichromate was added to reactor cooling water so that the instantaneous concentration was 2.0 ppm as required by the reactor cooling water specifications. Sodium dichromate was pumped from the 108-D Building through two different pipelines. One 7.6 cm (3 in.) diameter overhead pipeline connected to the 105-D Reactor. The other sodium dichromate pipeline was a below grade 7.6 cm (3 in.) diameter pipeline that exited the 108-D Building on the west side in combination with a parallel 7.6 cm (3 in.) diameter pipeline that transferred sodium silicate to the north side of the 185-D Building. These mixed solutions were injected into the process water systems at the 105-D Reactor and 185-D Building.

Waste Type: Not Specified

Waste Description: The waste is potentially contaminated equipment (pipelines) and any contaminated soil associated with the pipeline.

Closure Info: Interim (4/5/2012): Remediation of the 100-D-56 waste site was initiated in June 2006. Remediation activities consisted of removal and stockpiling of overburden soil to expose the pipelines; tapping, draining, and collection of the pipeline contents; removal and size reduction of the pipelines; and excavation and removal of approximately 0.3 meters (1 ft) of soil directly below the pipelines, including stained and contaminated soil that was identified during remediation. Field portable x-ray fluorescence (XRF) instrumentation was used to evaluate residual soil contamination and guide the excavation. Areas of discolored soil were sampled as necessary to support waste characterization, supplement field XRF measurements, and assist in guiding the excavation. The laboratory results for these samples are provided in Appendix B. Stained soil and suspect contaminated soil was staged on plastic until transported to the Environmental Restoration Disposal Facility (ERDF) for disposal. In addition, an approximate 0.3 meters (1 ft) layer of soil below the pipeline was removed for disposal. The low points of the pipes were tapped. The high points were raised to allow draining and collection of pipe contents and the process was repeated with drained pipeline segments cut and removed until the low points in the pipelines were reached.

Excavation of the north portion of the 100-D-56 pipelines (100-D-56:1) was initiated on December 18, 2006 and completed on January 10, 2007. Approximately 1,885 bank cubic meters (BCM) of soil and pipeline debris was excavated and disposed of at ERDF. Approximately 1,500 L (400 gal) of liquid were drained and collected from the northern

pipelines for disposition at the Effluent Treatment Facility. Stained soil and suspect contaminated soil was placed on plastic until it could be shipped to ERDF. In addition, an approximate 0.3 meters (1 ft) layer of soil below the pipeline was removed for disposal. Overburden soil removed from above the pipelines was placed in stockpiles and was sampled to verify its acceptance for use as clean backfill.

The north 100-D-56 pipelines did not contain sodium dichromate as was found for the south pipelines. However, sodium silicate liquids were present in the north pipes. The pipes were observed to have significant buildup of interior scale and the exterior was highly corroded in some locations. The differences observed between the south pipelines and the north pipelines likely relate to activities associated with the transfer of the sodium dichromate system from the 108-D Building to the 185-D Building when the use of dry sodium dichromate was replaced with the use of liquid sodium dichromate. It is also probable that the northern lines were completely flushed and not used after the aforementioned change in the sodium dichromate mixing process.

The SubSite is Part Of:

Code: 100-D-56

Names: 100-D-56; 100-D Area Sodium Dichromate Underground Supply Lines

Code: 100-D-56:2

Classification: Accepted

Names: 100-D-56:2; South Portion of the 100-D Area Sodium Dichromate Underground Supply Lines

Reclassification: Interim Closed Out (1/23/2012)

Type: Product Piping

Start Date:

Status: Inactive

End Date:

Description: The 100-D-56:2 subsite has been remediated and interim Closed out. It consisted of two abandoned 7.6 cm (3 in) underground pipelines that transported sodium silicate and sodium dichromate liquids between the 108-D, 190-D, 185-D, and 189-D facilities, the 100-D-12 Sodium Dichromate Pumping Station and the 183-DR Building. 100-D-56:2 extended south and west to the vicinity of the 100-D-12 Sodium Dichromate Pumping Station. The 100-D-56:2 chemical supply lines continued west from the vicinity of the 100-D-12 Sodium Dichromate Pumping Station and then turned south to the 183-DR Building.

100-D-56:2 subsite addressed the southern portion of the pipeline. The pipelines exited the south side of the 185-D Building to 100-D-12 and continued to the 183-DR building. This pipeline continued to be used after the transition to concentrated liquid sodium dichromate. The pipeline measured a total of 788 meters (2,585 feet).

Location: The southern portion of the 100-D-56 pipeline ran from the 185-D Building to the 183-DR Head House. The 185-D Building was located west of the 105-D Reactor. The 183-DR Head House is located west of the 190-DR Building.

Related Sites/Structures: A 20 meter (65.6 ft) section of the 100-D-56:2 pipelines, located at the entrance into the 183-DR Head House, and the 183-DR Filter Building sample room were also remediated with 100-D-77. Loadout of waste material with subsequent disposal at ERDF was conducted between July 13 and October 18, 2011.

Waste Type: Not Specified

Waste Description: The waste is abandoned 7.6 cm (3 in) pipe contaminated with sodium dichromate.

Closure Info: Interim (1/23/2012): Remediation of the 100-D-56 waste site was initiated on June 13, 2006.

Remediation activities consisted of removal and stockpiling of overburden soil to expose the pipelines; tapping, draining, and collection of the pipeline contents; and removal and size reduction of the pipelines, including stained soil and contaminated soil identified during remediation. Remediation of the south portion of the 100-D-56 pipelines (100-D-56:2) began on June 13, 2006, and was completed on February 7, 2007. The 100-D-56:2 excavation removed all the chemical supply piping and contaminated soil. However, a 20 meter (65.6-ft) section of concrete encasement that entered the demolished 183-DR Headhouse was left in place. The concrete encasement became part of the 183-DR Headhouse waste site (100-D-77). A 6.1 meter (20 ft) section of 100-D-56:2 was remediated with 100-D-77.

During excavation at the southernmost section of the south portion of the 100-D-56:2 pipelines, approximately 60 meters (197 ft) west of the 183-DR Headhouse, the pipelines were breached and released about 114 liters (30 gal) of a reddish brown liquid from one pipe and a pale green liquid from the other. A second pipeline breach resulting in another release of liquids. It was presumed that the entire section of the 100-D-56 pipelines south of Paddock Street contained liquids, and remediation of the pipelines was suspended. The pipelines were tapped and drained. Samples of liquid from each pipeline were collected for laboratory analysis to support waste disposition. Approximately 3,123 liters (825 gal) of chromium-contaminated liquids were collected from the south pipelines and sent offsite for treatment and disposal.

Following site remediation, verification sampling of the overburden soil stockpiles and soil within the excavation footprint was conducted on March 9 through March 11, 2009. The overburden soil above the pipelines at this location had visible chromium staining. On June 15, 2011, additional soil was removed within Area F (where the second pipeline release occurred). Verification samples were recollected from that location.

Note: The use of dry material handling was replaced with use of concentrated liquid sodium dichromate that was delivered by railcar and truck to an unloading facility/pumping station (100-D-12). The sodium dichromate pumping station was located south of the 183-D Building, next to the railroad tracks. A 7.6 cm (3 inch) diameter underground line provided the means to pump stock solution to storage tanks in the 185-D Building. This pipeline is identified with the 100-D-56:2 pipelines in the south portion of the sodium dichromate pipelines and was removed as part of the 100-D-56:2 remediation and the 100-D-12 remediation.

The SubSite is Part Of:

Code: 100-D-56

Names: 100-D-56; 100-D Area Sodium Dichromate Underground Supply Lines

Code: 100-D-60

Classification: Accepted

Names: 100-D-60; 100D River Lines; 100D/DR River Effluent Pipelines

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This site includes the river effluent pipelines (river lines) that extend from the two outfalls in the 100D/DR area into the main channel of the Columbia River.

Location: The river effluent pipelines extend from the discharge (river side) face of their respective outfall structure.

The river lines are located in the Columbia River, adjacent to the 100-D/DR area. The lines extend northwest from two outfall structures located near the river shore, through D Island, into the main channel of the river.

Related Sites/ Structures:	The site is associated with the 116-D-5 (1904-D outfall), 100-D-65 Spillway, the 116-DR-5 (1904-DR outfall), 100-D-66 Spillway, 100-D-48 (the 100D process effluent lines), 100-D-49 (the 100DR process sewer lines), and the 100-D-31 (100D water treatment facilities underground pipelines).
Process Description:	Reactor cooling water and process sewer wastes were collected and temporarily stored in the 107-D and 107-DR Retention Basins before being pumped to the river via the 116-D-5 and 116-DR-5 outfall structures and associated river effluent pipelines.
	The river pipeline extends from the 116-D-5 (1904-D Outfall) via two buried 107-centimeter (42-inch) diameter reinforced concrete/steel pipes. The steel pipes have a 1.3-centimeter (1/2-inch) thick wall. The pipe extends approximately 400 meters (1300 feet) into the river, passing through D Island. The pipelines are buried along their entire run to a depth of 0.6 meters (2 feet) to 2.1 meters (7 feet). The outlets are not exposed on the river bed.
	The river pipeline extends from the 116-DR-5 (1904-DR Outfall) via a buried 168-centimeter (66-inch) diameter carbon steel pipe with a 1.3-centimeter (1/2-inch) thick wall pipe. The line also extends approximately 400 meters (1300 feet) into the river, passing through D Island (100-D-67, D Island Contamination). The pipeline is buried along its entire run to a depth of 0.6 meters (2 feet) to 1.8 meters (6 feet). The DR outlet is exposed on the river bed.
Waste Type:	Equipment
Waste Description:	The waste includes the pipelines and the contaminated scale contained within them. The contaminants of potential concern are based on those for the outfalls themselves. The contaminants of concern for all D/DR river effluent pipelines include C-14, Cs-137, Sr-90, U-235, -238, and Pu-239/240.

Code:	100-D-61	Classification:	Accepted
Names:	100-D-61; Utility Pole and Fixture Debris Piles	Reclassification	Interim Closed Out (10/22/2009)
Type:	Dumping Area	Start Date:	
Status:	Inactive	End Date:	
Description:	The site consisted of debris piles containing utility poles, lead-tipped bolts, railroad ties, light fixtures, scrap wire and cable, scrap construction wood, and other miscellaneous debris from tearing down electrical utility poles. The exact history of the site was unknown.		
Location:	The site was located northwest of the 105-D Reactor on the northern side of Palouse Street, occupying a surface area of approximately 500 square meters (5,400 sq. ft.). The coordinates as reported by Ron Del Mar are N152838, E573481, northeast of the 183-D Filter Plant.		
Related Sites/ Structures:	Underlying the debris pile was a segment of 100-D-31:6 pipeline.		
Waste Type:	Misc. Trash and Debris		
Waste Description:	The waste includes creosote-treated wood poles and cross beams, wood pallets, metal debris, lead-tipped bolts and other debris.		
Closure Info:	Interim: Initial remediation of the waste site was performed from November 12, 2007, through January 24, 2008. Approximately 270 metric tons (300 U.S. tons) of surface debris and soil was removed including utility poles, railroad ties, light fixtures, scrap wire and cable, scrap construction wood, and other miscellaneous debris. The soil within the waste site footprint was excavated to a depth of 0.3 meter (1 ft) below ground surface (bgs), resulting in 100 bank cubic meters (BCM) (130 bank cubic yards [BCY]) of soil being disposed at the Environmental		

Restoration Disposal Facility (ERDF). The analytical results indicated residual contamination exceeding cleanup criteria in the southern portion of the waste site. Further (Phase II) remediation was conducted at the location on October 13, 2008. The soil within the Phase II waste site footprint was excavated to a depth of 1 meter (3 ft) bgs. The resulting 50 BCM (65 BCY) of soil was disposed at ERDF.

A global positioning survey was used to delineate the boundaries of the excavation footprint for the purpose of the verification sampling design. The site footprint was located above a section of vitrified clay sewer pipeline associated with the 100-D-31:6 waste site. Subsequent to the initial 100-D-61 excavation, the 100-D-31:6 pipeline was removed. The area associated with the 100-D-31:6 remediation trench was excavated to a depth of 1.5 meters (5 ft) below grade.

Code:	100-D-63	Classification:	Accepted
Names:	100-D-63; 100-D/DR Clean Water Pipelines; 100-D/DR Service Water Pipelines	Reclassification	Interim No Action (4/10/2013)
Type:	Product Piping	Start Date:	
Status:	Active	End Date:	
Description:	The waste site has been evaluated and determined to require No Action. It is comprised of the service water pipelines upstream of the 100-D and 100-DR reactors that were not treated with hexavalent chromium. The service water pipelines are those that were used to transport raw water (RW), filtered water (FW), sanitary water (SW), and condenser return water (CW). The 100-D-63 waste site also includes pipelines associated with the Plenum Filling Experiment (PFE) that were designed, but never built.		
Location:	These pipelines were located in the 100-D Area within 100-DR-1 and 100-DR-2 Operable Units.		
Related Sites/Structures:	The structures related to this site were the 184-D Boiler House, 182-D Pump House, 190-D and 190-D Annex Pump Houses, 190-DR and 190-DR Annex Pump Houses, 105-D and 105-DR Reactor Buildings, and the 187-D and 187-DR elevated water tanks adjacent to the Reactor Buildings. Related WIDS sites include: 100-D-63, 100-D/DR Service Water Pipelines, 100-D/DR Clean Water Pipelines, 100-D-31, 100-D Water Treatment Facilities Underground Pipelines (See Subsites), 100-D-77, DR Reactor Water Treatment Facility, Acid Facility, 183-DR Head House, 183-DR Filter Building, Sodium Dichromate Systems, 183-DR Flocculation Basins, 183-DR Sedimentation Basins.		
Process Description:	An enormous quantity of service water (i.e., 243 million gallons per day in June 1960) was required to support the 105-D/DR Reactors and the many supporting facilities in the 100-D/DR Area. Reactor cooling was the single largest use of the water accounting for more than 94% by volume. The majority of the remaining water use was allocated to the steam turbines as condenser water and filter backwash. Less than 1% of the water demand was used by the power house, fire and sanitary supply, and miscellaneous industrial operations.		

Raw water originating from the Columbia River was pumped from the 181-D River Pump House to the 182-D Reservoir and Pump House and the 183-DR filter plant.

The pipelines were designed to supply raw river water from the 181-D River Pump House, treated and filtered at the 183-D Filter Plant to 100-D Area facilities, including the 184-D Boiler House, 182-D Pump House, 190-D and 190-D Annex Pump Houses, 190-DR and 190-DR Annex Pump Houses, 105-D and 105-DR Reactor Buildings, and the 187-D and 187-DR elevated water tanks adjacent to the 105-D and 105-DR Reactor Buildings. The 183-D and DR Filter Plants were used to remove suspended fine solids from river water using chemical flocculation and pH additives, sedimentation basins, and sand/coal bed filters for the physical

and chemical treatment of river water to provide solids-free water suitable for reactor cooling, producing steam, and to supply the ancillary water uses within the 100-D and 100-DR Areas, e.g. water makeup, fire water, emergency cooling water (high towers), etc.

Prior to 1956 - 1957, the 182-D reservoir was used as the principal water supply source for the 183-D filter plants. Following implementation of Project CG-558, the purpose of the reservoir was to provide reserve (emergency) water for reactor cooling, condenser water for the steam condensers, and raw water (export water) to the 200 Areas. The 182-D Reservoir consists of a rectangular, sloped, reinforced concrete basin. The reservoir was divided into two sections by a 25.4 centimeters (10 inches) reinforced concrete wall running parallel to the short dimension of the structure. The inlet section of the reservoir, known as the reserve section, held 56.8 million liters (15 million gallons) of water, while the other, or working section, holds 37.9 million liters (10 million gallons).

The Columbia River water was filtered and chemically treated to prevent filming in the reactor process tubes. Alum, sulfuric acid and chlorine were proportioned in the 183-D Head House (component of the 183-D Filter Plant). Raw bauxite was stored in bunkers in the 183-D Filter Building Head House and flowed to a proportional dry chemical feeder which supplied bauxite at the required rate. From the conveyor belt of the proportional feeders, the bauxite fell into a lead-lined mixing chamber together with sulfuric acid and water.

The sulfuric acid was used to control the pH of the water. The reaction of the bauxite and diluted sulfuric acid formed a solution of alum and excess diluted sulfuric acid. Chlorine was added at this point for algae control in the settling basins. There were two flocculators in series for each settling basin in the 183-D Filter Plant. The purpose of the settling basins was to allow heavier particulate matter to settle out of the water before entering the filters. The filter media consisted of 0.31 meters (12 inches) of graded gravel, 0.15 meters (6 inches) of sand, and 0.61 meters (24 inches) of crushed and graded anthracite coal. Water entered the gullet from the influent flume through an influent valve and flowed to both halves of the filter through port openings. An organic polyelectrolyte filter aid to improve filter efficiency was added to the water in the gullet to improve water quality.

The filtered water collected in the false bottom below the filter and flowed through effluent piping to the effluent flumes. Valves controlled the amount of water passing through the effluent flumes and into the 183-D Clearwells (still within the 183-D Filter Building). The 183-D pump room was the primary supply point for filtered water for the entire production reactor plant. The eastern most clearwell provided the filtered water for power house water, fire and sanitary water (chlorinated before delivery), and for emergency filtered water. Separate pumps and clearwells provided water for the primary reactor cooling water.

Filter backwashing was supplied from the clearwells by backwash pumps located in the 183-D Filter Building Pump Room. Backwash water entered the filter collection area, flowed upward through the filter media into the gullet and through a waste valve into a sewer. The backwash water for the 183-DR filters was supplied from the 183-D Pump Room via a 0.76 meters (30 inches) cross-tie pipeline to the 183-DR Pipe Gallery. There was no equivalent to the 183-D Filter Plant Clearwells at 183-DR Filter Plant. This same pipeline was also used to supplement the 183-DR water requirements.

The 183-D and 183-DR Filter Plant Pump Rooms were the primary supply points for filtered water for each reactor area and the associated limited area (outside the reactor exclusion area). For the primary reactor cooling system, pumps were provided to transfer water to the 190-D and 190-DR Storage Tanks via 0.91 meter (36 inch) and 0.41 meter (16 inch) pipelines, backwash water for the filters and filtered water for the emergency high tanks. The pumps that supplied the four 1,135,624 Liter (300,000 gallon) high tanks (two at 105-D and two at 105-DR) also provided filtered water for cooling the primary coolant pumps and motors, filter

controls and service, reactor thermal loop and control rod cooling. Pumps at 183-D Filter Plant were provided to supply the power house water, fire and sanitary water and for additional emergency filtered water. Four pumps at the 183-D Filter Plant were connected to the combined sanitary and fire protection system.

For the 184-D Power House, boiler feed water was provided from four sources of supply, the first three from the 183-D Filter Plant Pump Room and a last ditch source of raw water from the 182-D Reservoir. At the 184-D Power House, three Zeolite water softeners were used to soften the filtered water. In the 184-D, boiler water treatment chemicals, sodium sulfite and tri-sodium phosphate, were used to reduce scale. In the event of total failure of the electric power to the Hanford Site, a secondary power source was available. It was independent of the electrical or primary source, and was capable of providing adequate cooling water to the reactor until the primary system could be re-established.

Waste Type: Not Specified

Waste Description: The pipelines were associated with the raw water, filtered water, sanitary water, and fire water systems in the 100-D Area. Chemical treatment included pH adjustment (with sulfuric acid or lime), chlorination for algae control, the addition of flocculants, (primarily alum prepared at the 183-D Filter Plant (Head House component) with bauxite and sulfuric acid), and a commercial organic polymer flocculation/filtration aid. This site also includes the potable and fire water pipelines that was delivered to the 1700 (site service buildings) series buildings. Contaminants of potential concern include potential radiological contaminants.

Closure Info: Interim (4/10/2013): Confirmatory sampling was initiated on January 26, 2010 and completed on March 15, 2010. The samples were collected from the soil in test pits and from inside the exposed pipes. Eighteen test pits were planned for excavation and sampling. However, due to field constraints, one test pit was not excavated. Two test pits (TP1 and TP2) were excavated, but not sampled. They were connected to active water lines.

Code: 100-D-65	Classification: Accepted
Names: 100-D-65; 116-D-5 Outfall Spillway; 1904D Spillway; 100-D-60:1 Flume	Reclassification: Interim Closed Out (1/9/2013)
Type: Outfall	Start Date:
Status: Inactive	End Date:
Description: The waste site has been remediated and Interim Closed Out. It consisted of a concrete spillway (a.k.a. flume) that served as an alternate discharge point for the 1904-D Outfall Structure. The 100-D-65 spillway waste site consisted of two components; an upland segment located above the Columbia River ordinary high water mark (OHWM) and a shoreline segment located below the OHWM and above the ordinary low water mark (OLWM).	
Location: The site was located northwest of 116-D-7 (the 107-D Retention Basin) and upstream of 116-DR-5 (the 1904 DR Outfall Structure). There was an engineered erosion barrier of heavy riprap beginning at the discharge end and extending for an additional 6 meters (20 feet).	
Related Sites/Structures: The site is associated with 100-D-60 (the 100-D River Effluent Pipelines) and 116-D-5 (the 1904-D Outfall Structure).	
Process Description: The spillway was an alternate discharge point for the 1904-D Outfall Structure. It was planned to be used only if the 100-D-60 river effluent pipelines were blocked, damaged, or undergoing maintenance. Due to the presence of beta/gamma radioactivity discovered during confirmatory sampling collected in January 2005, it is believed the spillway had been previously used.	
Waste Type: Construction Debris	

Waste Description: No evidence has been found that the spillway was ever put into service, the COPCs for the 100-D-65 spillway would be the same as those for the 116-D-5 outfall structure. The contaminants of concern include carbon-14, cesium-137, strontium-90, uranium-235/238, and plutonium-239/240.

Closure Info: Interim (1/9/2013): Because the 100-D-65 spillway extended into the Columbia River, the waste site consisted of two components: an upland segment located above the Columbia River ordinary high water mark (OHWM) and a shoreline segment located below the OHWM and above the ordinary low water mark (OLWM). Remediation of the upland segment of the outfall was performed September 1 through September 15, 2011. Approximately 468 bulk cubic meters of material was excavated, stockpiled, and later disposed at the Environmental Restoration Disposal Facility (ERDF). Remediation, verification sampling, and backfill of the below OHWM segment of the waste site was performed November 11 through November 13, 2011, during low river flow. Approximately 336 bulk cubic meters of material was removed from the shoreline area and disposed at ERDF. The portion of the concrete spillway remaining below water on the day of excavation was left in place. A sample of concrete exposed just above the water was collected.

A post-excavation Global Positioning Environmental Radiological Surveyor (GPERS) survey of the excavation was conducted on September 27, 2011. A hand-held sodium iodide survey was performed on December 20, 2011, for a portion of the remediation that was not surveyed using GPERS.

Code: 100-D-66	Classification: Accepted
Names: 100-D-66; 116-DR-5 Outfall; 1904-DR Spillway; 100-D-60:1 Flume	Reclassification: Interim Closed Out (1/17/2013)
Type: Outfall	Start Date:
Status: Inactive	End Date:

Description: The waste site has been remediated and Interim Closed Out. It consisted of a concrete spillway (also referred to as a flume). The majority of the spillway was demolished in 1978. It consisted of two components: an upland segment located above the Columbia River ordinary high water mark (OHWM) and a shoreline segment located below the OHWM and above the ordinary low water mark (OLWM).

Location: The site is located northwest of 116-D-7 (the 107-D Retention Basin) and downstream of 116-D-5 (the 1904-D Outfall Structure).

Related Sites/ Structures: The site is associated with the 100-D-60 River Effluent Pipelines and the 116-DR-5 Outfall Structure.

Process Description: The spillway was an alternate discharge point for the 116-DR-5 Outfall Structure. It was planned to be used only if the 100-D-60 river effluent pipelines were blocked, damaged, or undergoing maintenance. Due to the presence of beta/gamma-emitting radionuclides discovered during confirmatory sampling in January 2006, it is believed that the spillway had been used previously. Originally the spillway exited the east side of the 116-DR-5 outfall structure, made a rounding 90-degree turn, and continued to the river shoreline.

Waste Type: Construction Debris

Waste Description: No evidence has been found that the spillway was ever put into service, the COPCs for the 100-D-66 spillway would be the same as those for the 116-DR-5 outfall structure. The contaminants of concern include carbon-14, cesium-137, strontium-90, uranium-235/238, and plutonium-239/240.

Closure Info: Interim (1/17/2013): Because the 100-D-66 spillway extended into the Columbia River, the waste site consisted of two components: an upland segment located above the Columbia River ordinary high water mark (OHWM) and a shoreline segment located below the OHWM and above the ordinary low water mark (OLWM).

Remediation of the upland segment of the spillway was initiated on June 15, 2011 and completed on May 1, 2012. Remediation of the portion of the 100-D-66 waste site located below the OHWM, was performed November 18 through November 20, 2011, during low Columbia River flows. Approximately 3,400 bulk cubic meters of material was removed for disposal at the Environmental Restoration Disposal Facility (ERDF).

A post-excavation Global Positioning Environmental Radiological Surveyor (GPERS) survey of the excavation was conducted on May 2, 2012.

Code: 100-D-67	Classification: Accepted
Names: 100-D-67; D Island; D Island Contamination	Reclassification: Interim No Action (4/1/2014)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The site has been evaluated and determined to require No Action. It consists of contamination spreading from vent risers attached to the buried river effluent pipelines (100-D-60).

Location: D Island is a tapered, 213 meter (700 foot) wide island, located approximately 183 meters (600 feet) from the shoreline, directly across from the D and DR outfalls.

Related Sites/ Structures: This site is associated with 100D River Effluent Pipelines (100-D-60), 100-DR Outfall Structure, (116-DR-5) and the 1904-D Outfall Structure (116-D-5).

Process Description: The island received contamination from the 116-D-5 and 116-DR-5 Outfall Structures via vented river effluent pipelines during operation of 100D/DR Area.

Closure Info: Interim: A 1978 radiological survey identified specks of Cobalt-60 on the surface of D Island. In 1982 and 1990, aerial radiological surveys found the contamination levels were steadily decreasing. In 1992, a radiological survey using the Ultrasonic Ranging Data System (USRADS) found 67,000 data points representing elevated readings. Some specks were removed. In 1994, 40 vent pipe risers were cut off and sealed. In 1994, the Washington State Department of Health concluded the risk related to the specks did not justify further activity to locate and remove the specks.

The Cobalt-60 has gone through almost 4 half-lives of decay since this evaluation in 1992, decaying to approximately 8% of its 1992 activity in the year 2011.

The results of the evaluation indicate that the residual concentrations of radionuclide contaminants of concern/contaminants of potential concern at this waste site do not preclude any future land uses (as bounded by a recreational scenario). The 100-D-67 nonradionuclide concentrations are within the determined value ranges for the Columbia River riparian zone and do not represent contamination of riparian zone soils. Additionally, the dose rate and carcinogenic risk of radionuclide contaminants for the 100-D-67 waste site are less than the human-health risk criteria. This evaluation supports a reclassification of the 100-D-67 waste site to No Action.

The 100-D-67 waste site is not included in any decision document (record of decision or explanation of significant differences). This waste site will be dispositioned as a plug-in site in accordance with the Explanation of Significant Differences for the 100 Area Remaining Sites

Interim Remedial Action Record of Decision, Hanford Site, Benton County, Washington (ESD) (EPA 2009). Per the ESD (EPA 2009), plug-in sites will be documented in the Administrative Record, and an annual fact sheet will be published by the U.S. Department of Energy identifying sites that have been added to the Remaining Sites ROD.

Code: 100-D-69 **Classification:** Accepted

Names: 100-D-69; Sodium Dichromate Found Near Pacific Avenue and Paddock Street **Reclassification:** Interim Closed Out (4/2/2015)

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The site has been remediated and Interim Closed Out. It consisted of a stained concrete foundation and potentially contaminated soil. Pieces of green crushed concrete were present. The crushed concrete was likely remnants from the demolition of the 190-D structure.

Location: The site is located in a parking lot southwest of the intersection of Pacific Avenue and Paddock Street (the "T" intersection southwest of 105-D Reactor and northeast of the 151-D Substation). The center of the site is estimated at E573695.26, N151358.74.

Related Sites/ Structures: The site may have been related to the decommissioning of the 190-D Complex in 1996.

Process Description: During early 100-D water plant demolition activities, concrete debris was crushed and spread in-lieu of gravel fill. Adjacent areas have been covered with gravel as part of field remediation's parking lot construction activities. Likely, the material has been there for approximately 10 years. Gravel covered areas are not characterized.

Waste Type: Chemical Release

Waste Description: The waste is sodium dichromate contaminated concrete. Sodium dichromate was the only contaminant of potential concern.

Closure Info: Interim (4/2/2015): Confirmatory sampling was performed at the 100-D-69 waste site on June 7, 2012. The confirmatory samples were collected from six shallow (0.3 meters [1 ft] deep) test pits.

Remediation of the 100-D-69 waste site was conducted on March 24, 2014. Approximately 250 bank cubic meters (327 bank cubic yards) of gravel, crushed concrete, and soil was removed from the 0.91 meters (3.0 ft) deep excavation and placed in a staging pile area for disposal to the ERDF. The disposal of the staging pile area to ERDF was completed in July 2014. No overburden piles were associated with this excavation. There were no observed anomalies.

Code: 100-D-70 **Classification:** Accepted

Names: 100-D-70; 184-DA Steam Generating Plant Dry Well **Reclassification:** Interim No Action (7/7/2011)

Type: French Drain **Start Date:**

Status: Inactive **End Date:**

Description: The waste site consists of a 122 centimeter (48 inches) diameter drywell located on the south side of the 184-DA Building. It received steam separator discharge from equipment within the former 184-DA (demolished) Building. The pipeline from the building to the dry well is part of site 100-D-88. Confirmatory sampling results supported a reclassification of the 100-D-70

waste site to No Action.

Location: The drywell is on the south west side of the former 184DA Building. The 184DA building was located just south of the 1719D First Aid Station, southeast of the 1716D Gas Station, and north of the 189D building.

Related Sites/ Structures: The site was associated with the 184-DA Building and 100-D-88.

Process Description: The 184DA Building was a metal building constructed in 1968 and was designed as a steam generating facility. The facility contained a steam generator, fuel oil storage tank, fuel oil pump, deaerator, water softener, chemical treatment, fuel tank, steam separator, heater, diesel generator, liquid level gauges, and steam flow meter. One fuel tank (100-D-9) was located near the northwest corner of the building and has been removed. The other fuel tank was located near the southeast corner of the building. GPR was conducted in the southeast corner of the building and could not confirm if the tank was present.

Closure Info: Interim: Confirmatory sampling results supported a reclassification of the 100-D-70 waste site to No Action. Based on confirmatory sampling at the 100-D-70 waste site, remedial action was determined to be unnecessary, and the confirmatory sampling data has been used to document this waste site for reclassification as a No Action site. This site was not remediated.

Code: 100-D-71	Classification: Accepted
Names: 100-D-71; Vertical Safety Rod Tower Components	Reclassification: Interim Closed Out (9/3/2013)
Type: Laboratory	Start Date: 1/1/1957
Status: Inactive	End Date: 1/1/1985

Description: The waste site has been remediated and Interim Closed Out. The waste site consisted of the remaining components of the 195-D vertical safety rod tower, that was demolished in 1995. The remaining components included a 1.2 meter (4 foot) diameter by 2.2 meter (7 foot) deep concrete drywell, a below grade pit that is approximately 30.5 centimeters (12 inches) square, a 7.6 centimeter (3 inch) diameter underground cast iron process waste pipe, originating at the bottom of the tower's elevator shaft, and any potentially contaminated soil. The cast iron pipe extended underground from the pit, to the west, about 12 meters (39 feet) to the drywell. Wastes generated in the tower collected in the floor of the pit located at the bottom of the tower's elevator and which drained to the drywell.

Location: The site was approximately 23 meters (75 feet) southwest of the 189-D building. The french drain was centered at coordinates E573542.5, N151538.6. The pit was centered at coordinates E573558.9, N151541.4.

Related Sites/ Structures: This site relates to the 195-D VSR Tower. The tower was a stand-alone test facility. The remediation was associated with 100-D-104.

Process Description: Constructed in 1957 (Project CA-548), the structure (195-D) was a steel tower built in 100-D to replace the original wooden VSR at White Bluffs. It was constructed of corrugated steel wall over steel framing and sat on a 1 meter (3 feet) thick underground octagonal shaped concrete base. Its construction coincided with major upgrades and expansions of the pumping and piping systems of the Hanford reactors to allow increased power levels. At the time these power level increases were proposed, an intensive review was performed of all of the safety and control equipment associated with the eight reactors.

During fiscal year 1957, 5.33 million dollars was allocated for vertical safety rod (VSR) improvements on existing reactors. These improvements were directed specifically towards

decreasing the insertion time of the VSRs in order to eliminate the possibility of the slug jacket melting on loss of cooling water with existing power levels and VSRs. One major hurdle before the improved safety rods could be used was the effect of accelerating a rod into a graphite channel filled with 3X balls. Tests with an unaccelerated VSR falling on a column of balls showed extensive damage to the graphite. Accelerated rods would have up to four times the energy of a free falling rod indicating that even more extensive graphite damage might result.

A second major development problem was graphite growth in the 100-B, D, and F reactors that distorted some safety rod channels to the point where flexible rods were required. A method had to be found for accelerating rods into these distorted channels before the design of new safety rods could be completed. The only adequate method of obtaining the required information was building a full-scale mock-up of a VSR test facility. Thus, Project CA-548, was created to replace the old VSR tower located at White Bluffs.

The Ball 3X systems were investigated in 1959 and in-pile ball removal equipment was designed and tested in the 195-D building. By the late 1960s, the N Reactor was experiencing multiple problems with the Ball 3X system. During N Reactor's next 15 years of operation, tests were conducted to evaluate various aspects of ball mechanics and operation and of the issues and difficulties raised by graphite distortion effects on the ball channels. The testing in this tower helped establish criteria for the ball system upgrade that actually occurred in 1984. Following these tests, very little work was done in the building.

Waste Type: Oil

Waste Description: Potential contaminants of concern (COPCs) would include oils and PCBs. No testing with radiological materials was known to have occurred in the tower. A transformer bearing PCB oil was located inside the tower on the ground floor. Industrial chemicals and lubricating oils were used in the building. It is not known what, if any, dangerous or hazardous chemical wastes may have been discharged to the dry well.

Closure Info: Interim (9/3/2013): The 195-D VSR facility was removed to a depth of approximately 1 meters (3 ft) by the D&D Project in 1995. The remaining components of the facility (the drywell, pipeline, and elevator pit) define the 100-D-71 waste site. The remaining components were located inside the 100-D-104 excavation. They were removed with the Tier II remediation of the 100-D-104, Unplanned Release Near 185-D Sodium Dichromate Storage Tanks and Acid Neutralization French Drain waste site. Upon completion of the 100-D-104 waste site remediation, approximately 7 meters (23 ft) of soil below the base of the lowest elevation for the 100-D-71 waste site will have been removed. No evidence of soil staining related to the 100-D-71 waste site location was observed within the footprint of the 100-D-104 waste site excavation, indicating that adequate remediation has been performed for the 100-D-71 waste site.

The basis for interim closure of the 100-D-71 waste site is supported by historical operational information, field observations, and the excavation depth. The 100-D-71 waste site has been remediated as part of the remediation of the 100-D-104 waste site. The site does not pose a risk to human health or the environment and will support future unrestricted land uses that can be represented (or bounded) by a rural-residential scenario.

Code: 100-D-72

Classification: Accepted

Names: 100-D-72; 183D Acid Facility

Reclassification: Interim Closed Out (5/28/2015)

Type: Process Unit/Plant

Start Date:

Status: Inactive

End Date:

Description: The waste site was remediated and Interim Closed Out. It was comprised of the 183-D acid

addition facility. It included a concrete trench that protected the service piping (air, steam, filtered water, lime slurry, sulfuric acid) and drained acid waste to the neutralization pit. The underground piping contained in the trench are part of this waste site. The site also includes a dry well, two sumps (exterior to the trench), two storm drains, a storm sewer and an acid/silica supply line. Pipeline segment 93 was remediated with 100-D-72. The filtered water line was assigned to 100-D-63.

Location: The site was south of the 183-D Head House, east of the railroad car spot and on the west side of the flocculation basins.

Release Description: All activities associated with this waste site are related to the unloading, storage and use of acid to support water treatment in the 183-D Head House.

Related Sites/Structures: The site was associated with the 183-D Head House, flocculation basins and the 100-D-31 water treatment facilities underground pipelines.

Process Description: All components were associated with the storage and flow of sulfuric acid to the 183-D Head House where it was added for water treatment. The 183-D Head House was designed to treat raw river water before it entered the reactor. Chemicals were added to the river water in the head house. The head house was used for the storage, preparation, and addition of alum, sulfuric acid, and chlorine for water treatment. Alum was used as a flocculating agent and the excess sulfuric acid was used to control the acidity of the water. Bauxite was stored in bunkers on the third floor and used at a required rate. Chlorine was added to control algae. Concentrated sulfuric acid was received by railroad car and stored in the outside acid storage tanks. It was pumped from the storage tank to the head tank through black iron pipelines. The building also contained a laboratory, restrooms, janitor's room, electrical switchgear room, and locker room. As of August 2006, the 183-D Head House was inactive, but still intact. It was later demolished.

Waste Type: Soil

Waste Description: Contaminants of potential concern (COPCs) include lead and mercury. Sulfuric acid used at the head house may have contaminated impurities, such as lead and mercury. The trench exits the south side of the 183-D Head House and continues toward the two sulfuric acid storage tanks. The trench is 0.76 m (2 ft 6 in) wide and depending on the location contains different piping. From the south side of the 183-D Building to the sulfuric acid pumps, the trench contains a 2.5 cm (1 in) steam line, a 5 cm (2 in) filtered water line, a 5 cm (2 in) lime slurry line and a 1.9 cm (0.75 in) air line. From the sulfuric acid pumps to the two sulfuric acid storage tanks, the trench contains 1 steam line, a 5 cm (2 in) lime slurry line, a 5 cm (2 in) sulfuric acid line that goes to the storage tank, a 5 cm (2 in) sulfuric acid line that goes to the head tank, and 2-5 cm (2 in) PVC storage tank drains in the bottom of the trench.

Closure Info: Interim (5/28/2015): Remediation of the 100-D-72 waste site was conducted concurrently with the 100-D-31:11 and 100-D-31:12 waste sites. Excavation of these waste sites began on December 3, 2013, and was completed on February 26, 2014. Approximately 10,585 bank cubic meters (13,845 bank cubic yards) of soil, piping debris, steel, concrete, and vitrified clay pipe were disposed to the Environmental Restoration Disposal Facility (ERDF). The depth of the resulting excavation varied from 2.7 meters (8.9 ft) to approximately 5.7 meters (18.7 ft) below ground surface. The remaining below grade structure of the previously addressed 100-D-59, French Drain was completely removed during this remedial action. No anomalies were observed. Overburden was staged to the east of the excavation in the area of the former 183-D Filter Building. Potentially contaminated soils were staged to the southwest of the excavation in a multiple waste site staging pile area (SPA).

The area south of Paddock St (part of 100-D-72) was backfilled in March 2014 to provide access for well drilling activities in this area.

A portion of the 100-D-72 pipeline site was removed during excavation of the 100-D-100 hexavalent chromium stained soil site. The 100-D-100 site excavation removed the entire

vadose zone and is approximately 26 meters (85 ft) deep. Because the 100-D-100 excavation is much deeper than the 100-D-72 pipeline, verification sampling and further evaluation of the 100-D-72 waste site in the area of the 100-D-100 excavation was determined to be unwarranted.

Code:	100-D-73	Classification:	Accepted
Names:	100-D-73; 108-D Chemical Pump House	Reclassification	Interim Closed Out (1/28/2013)
Type:	Process Unit/Plant	Start Date:	
Status:	Inactive	End Date:	
Description:	The site has been remediated and Interim Closed Out. It was the soil and possibly the demolition debris under the former 108-D Building. It was identified as part of the Orphan research for sodium dichromate investigation conducted for the D/DR Reactor area. The 108-D Building was demolished in 1987 and the rubble disposed in the 126-D-2 (184-D) coal pit, inert landfill.		
Location:	The 108-D Building was located north of the 105-D Reactor and east of the 1709-D Building.		
Release Description:	A mixing tank may have discharged high concentrations of sodium dichromate into the soil. It was reported that "several sodium dichromate storage tanks associated with the water treatment facilities overflowed or drained into the process sewer and outfall. Monitoring wells near the 108-D Building indicate that up gradient well 199-D5-15 contained chromium concentrations higher than the down gradient well 199-D5-14. Suggesting sodium dichromate may have originated from this area.		
Related Sites/ Structures:	A total of eight pipelines were associated with the 108-D Building. The 108-D Building was associated with the two sodium dichromate lines (100-D-56) that exited the west side of the facility and extended to the 185-D Building. It is also associated with a 7.6 centimeter (3 inches) diameter overhead sodium dichromate line that extended from the 108-D to the 105-D Reactor (removed). There are also two pipelines (100-D-63) that exit the northwest corner of the facility. Three pipelines are associated with 100-D-31. Structures associated with the sodium dichromate system included the 185-D, 190-D Pump Room and sodium dichromate tank and the 183-DR Head House.		
Process Description:	From about 1944 until 1950, the receiving, mixing, and transfer of sodium dichromate were conducted in the 108-D Building. The 108-D facility received, stored, and prepared various chemicals for the preparation of solution concentrations. Chemicals were unloaded from railcars at the weather-proof unloading railroad car spot in either bags or barrels (Spec. HW-2036). The method utilized for the mixing of sodium dichromate chemicals in the 108-D Building was referred to as the "batch method" that consisted of dichromate in crystalline form. The crystalline material was dissolved in water and diluted to a 10% to 15% dichromate solution, mixed, and transferred to feed tanks in the 105-D and 185-D Buildings. Although the total quantity of material used in the facility is unknown, some indication is available; for example, from January 29 through February 25, 1945, 8,960 kilograms (19,736 pounds) were mixed into solution (HW-7-1388 Del). Required additives were prepared in batches and emptied into the conical mix tank (HAN-10970). Water was added and a 10% concentration of sodium dichromate solution was prepared and pumped by two transfer pumps to one of two solution feed tanks located near the #1 deaerator on the mezzanine floor in the 185-D Building. Each tank in the 185-D Building had a 3,800 Liter (1,000 gallon) capacity and dimensions of 1.6 meters by 2.4 meters (5 feet 4 inches by 8 feet) (Spec. 2017). From the tanks, sodium dichromate was added to the process water at the exit side of the deaerators in the 190-D Building. The above grade structures of the 185-D and 190-D Buildings have been demolished. Mixed sodium dichromate was pumped from the 108-D Building through two different pipelines. One overhead pipeline connected to the 105-D Reactor and the other below grade to the 185-D Building (W-74552). Pumps in the 108-D Building transferred sodium dichromate to the 105-D Reactor through a 7.6 centimeter (3 inches) diameter overhead		

pipeline to the valve pit extension into a storage tank located in the acid mixing area (Spec. HW-2036 and W-73176). The second pipeline was a 7.6-centimeter (3 inches) diameter sodium dichromate pipeline (100-D-56) that extended from the west side of the 108-D Building to the north side of the 185-D Building. Mixed solutions were injected into the process water systems in the 105-D and 185-D Buildings (Spec. HW-2036). These pipelines were active until about 1950 when the mixing facility was relocated to the 185-D Building as part of Project C-396 (H-1-2901). Research suggests that the mixing of sodium dichromate into solution in the 108-D Building and associated pipelines was discontinued in 1950. Previous investigations stated that sodium dichromate storage tanks were located on the west side of the 108-D Building. Historical research indicates that no sodium dichromate storage tanks ever existed outside the west side of the 108-D Building. The only tanks located on the west sides of the facility were two sulfuric acid tanks and two sodium silicate tanks.

Waste Type: Chemicals

Waste Description: The waste is potentially contaminated soil because of the releases from the 108-D Building. There is a potential for sodium dichromate, oxalic acid, sodium silicate, and radionuclides under the existing below grade footprint of the 108-D Building. Soil samples collected in 1994 indicate the presence of radionuclide contamination that may include Carbon-14, Potassium K-40, radium Ra-226, Thorium-228, and Thorium-232 (DOE/RL-93-29). The possibility also exists for sodium dichromate. It is not known what would cause the presence of radionuclide contamination.

Closure Info: Interim (1/28/2013): 100-D-76 confirmatory sampling was done in September 2008. A layer of red gravel was found 1.2 meters (4 ft) below the surface. Total chromium was detected in the samples.

The 100-D-73 and 100-D-76 waste sites were remediated between June 8 and 16, 2011. The maximum excavation depth at the 100-D-76 french drain location extended to approximately 5.5 meters (18.0 ft) below ground surface. Approximately 2,171 bank cubic meters (2,840 bank cubic yards) and 182 bank cubic meters (238 bank cubic yards) of soil and debris were excavated from the 100-D-73 and 100-D-76 waste sites, respectively. Debris included concrete chunks, rebar, lumber, miscellaneous metal wire, and ropes. The total resulted in 2,353 bank cubic meters (3,078 bank cubic yards) of excavated materials removed and staged for disposal at the Environmental Restoration Disposal Facility.

Code: 100-D-74

Classification: Accepted

Names: 100-D-74; Drywell Well

Reclassification: Interim No Action (6/15/2011)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The site is a drywell adjacent to the 105-D Reactor. Following remedial activities, radiological postings were removed per WCH Interoffice Memorandum #179974, dated July 13, 2015.

Location: The drywell is located north of the northwest side of original 105D Reactor footprint. The coordinates of the dry well are E 573744.2, N 151316.3.

Related Sites/ Structures: The site is associated with the 105-DR Reactor.

Process Description: Drawing H-1-8522-DR, indicates the purpose of the dry well was to receive steam condensate from the heaters inside the 105-DR Building. In conjunction with the dry well is a flash tank (flash steam to condensate) and a 5.1 cm (2 in) line to the dry well. Although the drawing is not clear, it also appears that some floor drains were connected also. Steam heating is a non-contact system isolated from radiological contaminated portions of the facility. The entire

building was a negative draft system vented through the 117-D Filter Building eliminating the possibility of radiological contamination in this part of the building.

Waste Type: Steam Condensate

Waste Description: The site received steam condensate from the heating units inside the 105-DR Reactor.

Closure Info: Interim: Confirmatory sampling was performed in August 2010. The results indicated that the waste site achieved compliance with the remedial action objectives (RAOs) and remedial action goals (RAGs) for the 100-D-74 waste site, and remediation was not necessary.

Code: 100-D-75

Classification: Accepted

Names: 100-D-75; 151-D Primary Electrical Substation; 152-C1-D & 152-E1-D Secondary Electrical Substations

Reclassification: Interim Closed Out (6/17/2015)

Type: Electrical Substation

Start Date:

Status: Inactive

End Date:

Description: The waste site had been divided into three subsites. All of the subsites have been addressed, so the parent site has been reclassified to Interim Closed Out. The area within the fence contained the 151-D Primary Substation, and two Secondary Electrical Substations (152-C1-D and 152-E1-D). Electrical substations often had leaks and spills of PCBs from the electrical transformers, circuit breakers, and transfer systems during the early years of operation that went unreported. An analogous site, the 151-H Primary Substation (100-H-24) was remediated in 2000, by removing and disposing of more than 21,000 tons of PCB-contaminated material. All three substations are inactive (not providing any electrical power to D Area), although live 230KV power lines will be routed across the 151-D switchyard for the foreseeable future.

The site was divided into three subsites as follows:

100-D-75:1, 151-D Primary Electrical Substation. This subsite was remediated and Interim Closed Out.

100-D-75:2, 152-E1-D Secondary Electrical Substation, Substation C4-S1. This subsite was determined to require No Action.

100-D-75:3, 152-C1-D Secondary Electrical Substation. This subsite was determined to require No Action.

Location: The 151-D Building and associated switchyard are located approximately 350 meters (107 ft) southwest of the 105-D Reactor building and 235 meters (72 ft) northwest of the 105-DR Reactor building, with the center point of the yard at coordinates N151328 E573542. The 152-C1-D Secondary Electrical Substation, centered at coordinates N151584 E573369, is near the 183-D Filter Building. The 152-E1-D Secondary Electrical Substation, centered at coordinates N151692.84 E572833.69, is near the 181-D Pump House.

Release Description: The only significant reported release of transformer oil was in 1995 in the 151-D switchyard. The site was remediated, and reclassified to Closed Out. See WIDS General Summary Report 100-D-27 for details.

Related Sites/Structures: The 151-D Primary Substation distributed 13.8KV power to transformers located at the 181-D River Pump House, 182 Head Houses, 183 Filter Houses, 184-D Power House, 186-D Water Treatment Plant, 190 Pump Houses, and 105-D/DR Reactors, which in turn distributed power to associated facilities. The 151-D Switch House is essentially a one-story building, having a sub-level cable pit equipped with a sump pump. All duct lines originate/terminate at the Switch House. The cable pit is a completely enclosed reinforced concrete pit with floor slab, varying

from 0.3 to 0.4 meters (1 to 1.5 feet) in thickness, and with 0.3 meters (1 foot) thick walls. Switchgear is located on the main floor directly above the cable pit. The overall dimensions of the Switch House are 25 meters by 9.3 meters by 8.7 meters (83 feet by 30.5 feet by 28.5 feet.)

Process Description: The Midway Station fed 230KV power to the 31,250 KVA transformers located in the 151-D switchyard. From these transformers, power was transmitted via overhead and underground cables to secondary and distribution substations located throughout the 100-D/DR Area. Circuit breakers were also in service to support the switchyard operations. PCB-containing oil was transferred, as needed, from a rail tanker on the railroad spur through over ground hoses and piping to transformers and oil circuit breakers in the yard. The smaller transformers at the secondary and distribution substations were also filled via over ground hoses from oil trucks.

Waste Type: Soil

Waste Description: PCB contamination of the soil surrounding the transformer and circuit breaker pads is the primary waste concern. PCB-contaminated soil could also exist along the railroad spur.

This Site has the Following SubSites:

Code: 100-D-75:1

Names: 100-D-75:1; 151-D Primary Electrical Substation

Code: 100-D-75:2

Names: 100-D-75:2; 152-E1-D Secondary Electrical Substation; Substation C4-S1

Code: 100-D-75:3

Names: 100-D-75:3; 152-C1-D Secondary Electrical Substation

Code: 100-D-75:1

Classification: Accepted

Names: 100-D-75:1; 151-D Primary Electrical Substation

Reclassification: Interim Closed Out (6/17/2015)

Type: Electrical Substation

Start Date: 1/1/1944

Status: Inactive

End Date: 1/1/2013

Description: The Primary Substation was remediated and Interim Closed Out. It consisted of a fenced, gravel-bed yard, measuring approximately 165 meters (541 ft) on each side, with the 151-D Switch House on the northern fence line. A railroad spur entered the yard from the east and paralleled the north fence line. Concrete pads of various sizes protrude from the crushed gravel bed throughout the yard that support a variety of electrical equipment, including transformers, circuit breakers, and power line towers and stands.

The 31,250 KVA transformers were originally located at N151338/E573515; and N151338/E573556. Sometime after 1956, a third very large ground transformer was added at N151374/E573516. The circuit breakers were located at N51300/E573494; N151300/E573536 and N151300/E573576.

Location: The 151-D Building and associated switchyard are located approximately 350 meters (107 ft) southwest of the 105-D Reactor building and 235 m (72 ft) northwest of the 105-DR Reactor building, with the center point of the yard at coordinates N151328/E573542.

Related Sites/Structures: The 151-D Primary Substation distributed 13.8KV power to transformers located at the 151-D Switch House, 181-D River Pump House, 182 Head Houses, 183 Filter Houses, 184-D Power House, 186-D Water Treatment Plant, 190 Pump Houses, and 105-D/DR Reactors, which in turn distributed power to associated facilities.

Process Description: The Midway Station fed 230KV power to the 31,250 KVA transformers located in the 151-D switchyard. From these transformers, power was transmitted via overhead and underground

cables to secondary and distribution substations located throughout the 100-D/DR Area. Circuit breakers were also in service to support the switchyard operations. PCB-containing oil was transferred, as needed, from a rail tanker on the railroad spur through over ground hoses and piping to transformers and oil circuit breakers in the yard.

An oil spill from one of the 151-D switchyard transformers was remediated in 1995 (100-D-27). This may not have been the extent of transformer leaks and spills, because such events were not consistently recorded before about 1985. There is some information from power operators that transformer spills and leaks were not uncommon. Therefore, any transformer or circuit breaker pad and surrounding soil may have PCB contamination. Most of the equipment within the substation has already been drained of oil.

According to the Hanford Electrical Utilities craft supervisor, the equipment in the 151D yard is inactive. The only thing energized is the overhead lines going through the yard. Because there is a section of energized 230kV buswork that runs through the substation yard, the yard is off-limits to all, except for qualified system workers.

There are circuit breakers stored in the northeast corner of the switchyard that have been disconnected and drained. These circuit breakers could not have been in use at this location. When in service, the circuit breakers would have to be put on a concrete pad and bolted to the overhead bus. Two smaller transformers were placed in the switchyard from the old, 181D yard (100-D-75:2). Both PCB contaminated transformers were drained on 7/12/2005. This action stopped the 5-year TSCA time requirement. Based on the available aerial photography, it is evident that the two smaller transformers were added to the switchyard sometime between April 2008 and August 2009.

The switch house was used to control the switchyard. There were no processes that indicate any type of contamination to be associated with this structure.

Waste Type: Soil

Waste Description: There may be PCB contaminated soil at these substation sites.

Closure Info: Interim (6/17/2015): Remediation of the 100-D-75:1 subsite was performed between July 7 and October 28, 2014. Approximately 17,039 bank cubic meters (22,286 bank cubic yards) of excavated materials was removed and a small portion was staged prior to disposal at ERDF. The depth of the excavation varies between 1 to 4 meters (3.3 to 13.1 ft) across the subsite. Excavated materials consisted of concrete, rebar, asbestos conduit, steel pipe, wire, and stained soil.

During the 100-D-75:1 subsite remedial activities, oil-stained soils were discovered at several locations throughout the footprint of the 100-D-75:1 subsite. Over 70 in-process samples were collected from this subsite during the course of remediation. In-process sampling was performed when oil-stained soils were encountered and following removal of the stained soils to confirm removal of contaminated materials. Concrete duct banks were encountered in the shallow zone of the 100-D-75:1 excavation. These duct banks contain electrical conduits made of asbestos piping with no other hazardous materials. Per discussion with the Washington State Department of Ecology, the concrete duct banks could be left in place if concrete was free of staining. The decision to leave concrete duct banks in place was based on waste minimization efforts. The field sampling personnel examined the concrete duct banks for staining, and no staining on these concrete structures was identified.

The excavated materials were stockpiled west of the excavation in the approved staging pile area. The staged materials were loaded out on August 14, 2014. Materials excavated from the waste site after this date were direct loaded for disposal at ERDF. No overburden materials

were salvaged from the 100-D-75:1 excavation. No radiation was detected within the 100-D-75:1 excavation area.

The SubSite is Part Of:

Code: 100-D-75

Names: 100-D-75; 151-D Primary Electrical Substation; 152-C1-D & 152-E1-D Secondary Electrical Substations

Code: 100-D-75:2

Classification: Accepted

Names: 100-D-75:2; 152-E1-D Secondary Electrical Substation; Substation C4-S1

Reclassification: Interim No Action (9/30/2014)

Type: Electrical Substation

Start Date:

Status: Inactive

End Date:

Description: The subsite has been evaluated and determined to require No Action. It is a secondary substation that consists of a small fenced area measuring 25 meters (80 ft) by 8 meters (25 ft), with concrete pads for the former transformers and inactive electrical components.

Based on the historical photograph (P-4479), two transformers originally existed behind the power poles. According to the 100-D Area National Code Inspector, two concrete pads are currently located at this secondary substation and suspected to have housed two smaller transformers to provide power for 181D Pump House. The transformers were drained of PCB-containing oil on 7/12/2005. This action stopped the 5-year TSCA time requirement. The transformers have since been removed, but the concrete pads remain. The transformers were moved to the 151-D switchyard (100-D-75:1). Based on the available aerial photography, it appears the two smaller transformers were moved to between April 2008 and August 2009.

Location: The 152-E1-D Secondary Electrical Substation (centered at N151692.84/E572833.69) is located near the 181-D Pump House and the Columbia River.

The 152-E1-D Secondary Electrical Substation is rectangular shaped fenced area.

Process Description: The Midway Station fed 230kV power to the 31,250 KVA transformers located in the 151-D switchyard. From these transformers, power was transmitted via overhead and underground cables to secondary and distribution substations located throughout the 100-D/DR Area. The smaller transformers at the secondary and distribution substations were filled with PCB-containing oil via over ground hoses from oil trucks.

Waste Type: Soil

Waste Description: There may be contaminated soil at these substation sites.

Closure Info: Interim (9/30/2014): Confirmatory sampling was performed at the 100-D-75:2 subsite on May 8, 2014. Confirmatory sampling of the 100-D-75:2 subsite was performed to support evaluation of the site against the RAGs specified in the Remaining Sites ROD (EPA 1999). The analytical results were evaluated against the cleanup criteria specified in the RDR/RAWP (DOE-RL 2009b) to support a No Action or Remedial Action decision.

Based on the historical photograph (P-4479), the two transformers were originally located behind the power poles that remain today. Surface sample SS 1 and SS 2 were collected at this location. No transformer pads were observed at these sample locations. According to the 100-D Area National Code Inspector, two concrete pads that are currently located at this secondary substation are suspected to have housed two smaller transformers. Surface sample locations SS

3 and SS 4 were collected at this location. The transformers have since been removed, but the two concrete pads remain. Two samples of concrete were (CS 5 and CS 6) were scabbled from these pads.

The SubSite is Part Of:

Code: 100-D-75

Names: 100-D-75; 151-D Primary Electrical Substation; 152-C1-D & 152-E1-D Secondary Electrical Substations

Code: 100-D-75:3

Classification: Accepted

Names: 100-D-75:3; 152-C1-D Secondary Electrical Substation

Reclassification: Interim No Action (8/8/2011)

Type: Electrical Substation

Start Date:

Status: Inactive

End Date:

Description: The subsite has been evaluated and determined to require No Action. Three secondary transformers were located at this substation, but have since been removed; leaving the three concrete pads that supported the transformers.

Location: The 152-C1-D Secondary Electrical Substation, centered at coordinates N151584 E573369, is near the 183-D Filter Building and the Columbia River.

The 152-C1-D Secondary Electrical Substation has a rectangular perimeter of 42.3 meters (138.8 ft). Length 8.60 meters (28.22 ft), width 13.6 meters (44.62 ft).

Process Description: The Midway Station fed 230 KV power to the 31,250 KVA transformers located in the 151-D switchyard. From these transformers, power was transmitted via overhead and underground cables to secondary and distribution substations located throughout the 100-D/DR Area. The smaller transformers at the secondary and distribution substations were filled with PCB-containing oil via over ground hoses from oil trucks.

A portion of the 100-D-31:9 pipeline was located directly beneath the 152-C1-D Secondary Electrical Substation. During the remediation of the 100-D-31:9 waste site the three concrete pads at the 152-C1-D Secondary Electrical Substation and portions of the surrounding soil were removed and disposed of at the Environmental Restoration Disposal Facility (ERDF). Additional surrounding soil was collected as part of the overburden for the 100-D-31:9 waste site. The 152-C1-D secondary substation will be addressed using the sample results associated with the 100-D-31:9 closeout sampling.

Waste Type: Soil

Waste Description: There may be PCB contaminated soil and concrete at these substation sites.

Closure Info: Interim: This site was determined to require No Action and was not remediated.

The 100-D-75:3 subsite contained three transformers that had been previously removed. A portion of the 100-D-31:9 pipeline was located directly beneath the 100-D-75:3, Secondary Electrical Substation. During the remediation of the 100-D-31:9 subsite, the three remaining concrete pads at the 100-D-75:3 subsite and portions of the surrounding soil were removed and disposed of at the Environmental Restoration Disposal Facility.

The SubSite is Part Of:

Code: 100-D-75
Names: 100-D-75; 151-D Primary Electrical Substation; 152-C1-D & 152-E1-D Secondary Electrical Substations

Code: 100-D-76 **Classification:** Accepted
Names: 100-D-76; Potential Crib Next to 108D; Potential Former 116-D-3 Crib **Reclassification:** Interim Closed Out (1/28/2013)
Type: Crib **Start Date:** 1/1/1951
Status: Inactive **End Date:** 1/1/1967

Description: The site has been remediated and Interim Closed Out. It was a potential crib, located near the former 108D building. It was identified during a 2008 geophysical investigation as either a french drain or crib. 100-D-76 was determined, through historical research, to be the crib formerly known as 116-D-3.

Location: The site is located just off the edge of southeast corner of the former 108D building.

Related Sites/ Structures: The crib is associated with the 108-D Building, 100-D-73 and a vitrified clay pipe known as 100-D-31:3 that crosses this waste site in a north/south direction. It is also associated with 116-D-3.

Waste Type: Process Effluent

Waste Description: Due to the confusion of the location of the crib, the same historical documentation may apply to waste sites 116-D-3 and 116-D-4. Historical information suggests the crib may have received low level fission product wastes from the contaminated maintenance shop and cask decontamination pad in the 108-D Building. The crib received 0.08180 curies of Cs-134 and 30,000 liters. (7,920 gallons) of liquids. The contaminants of potential concern are assumed to be the same for 116-D-4 that were uranium-238 and hexavalent chromium.

Closure Info: Interim (1/28/2013): 100-D-76 confirmatory sampling was done in September 2008. A layer of red gravel was found 1.2 meters (4 ft) below the surface. Total chromium was detected in the samples.

The 100-D-73 and 100-D-76 waste sites were remediated between June 8 and 16, 2011. The maximum excavation depth at the 100-D-76 french drain location extended to approximately 5.5 meters (18.0 ft) below ground surface. Approximately 2,171 bank cubic meters (2,840 bank cubic yards) and 182 bank cubic meters (238 bank cubic yards) of soil and debris were excavated from the 100-D-73 and 100-D-76 waste sites, respectively. Debris included concrete chunks, rebar, lumber, miscellaneous metal wire, and ropes. The total resulted in 2,353 bank cubic meters (3,078 bank cubic yards) of excavated materials removed and staged for disposal at the Environmental Restoration Disposal Facility.

Code: 100-D-78 **Classification:** Accepted
Names: 100-D-78; 100D Yellow Stained Soils **Reclassification:** Interim Closed Out (8/21/2013)
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The site has been remediated and Interim Closed Out. It consisted of four locations of contaminated soil between the 183-D and 186-D structures. The stained soil was yellow in color, with some white crusty material.

Location: The four patches of yellow-stained soil were located in the area between the 183-D and 186-D

structures. Stain Areas one and two were associated with the acid-proof brick trench that was parallel to the entire length of the west wall of the 186-D Building. Stain Area three was at the southwest corner of the 120-D-2, Waste Acid Reservoir. Stain Area four was located west of Stain Area three, near the southwest corner of the 120-D-2 Waste Acid Reservoir.

Related Sites/ Structures: Related structures included: the 186-D Waste Acid Reservoir waste site 120-D-2, 183-D and the 186-D Buildings.

Process Description: The potentially contaminated soil may have originated from activities associated with the 186-D Building, which was initially constructed as a demineralization plant to remove dissolved calcium, magnesium, and salts through sulfonated coal. However, the building was not used for this purpose. Historical information is very limited for this facility. Although the exact historic use of the facility is unknown, it is believed that it was used for a period of time for storage. The overall dimensions of the building were 204 by 39 by 27 meters (670 feet by 128 feet by 87 feet).

The demineralization plant was a two story structure with a reinforced concrete foundation, reinforced concrete slab floor, steel framework, concrete block superstructure and built-up roofing over precast concrete tile slabs. The ground floor contained two banks of twelve wood mixing tanks located on the east side of the facility. Between the mixing tanks were four wood acid reclaiming tanks and two steel soda reclaiming tanks. Two steel soda dissolving tanks were located at the southern end of the facility. The second floor contained 24 wood tanks along the east wall. The building contained acid tanks, pumps, clearwells and associated equipment. The clearwells were mostly below grade and were located along the east side of the facility with dimensions of 166 by 17 by 9 meters (545 feet by 55 feet by 30 feet). The clearwells and pump building adjoined the 185-D Building. Adjacent to and east of the center portion of the clearwells was a pump house that contained seven stainless steel water pumps.

Along the west wall is an acid-proof brick trench approximately 1.2 meter by 1.8 meters (4 feet deep by 6 feet wide), that extends almost the entire length of the building. The trench empties into the 186-D Waste Acid Reservoir (120-D-2). Approximately 3 meters (10 feet) west of the plant at the south end of the building were six, outside, horizontal sulfuric acid steel tanks.

West of the 186-D Building was the Waste Acid Reservoir (120-D-2) used for the disposal of waste acid from the facility. The Waste Acid Reservoir was constructed of acid proof brick with a 3 ply water proof membrane. Drain pipes were connected to the D-Area process sewer system. It was demolished in 1979 and buried in place.

Waste Type: Soil

Waste Description: The 186-D Waste Acid Reservoir has been identified as a site requiring remediation as stated in the interim ROD for the 100-DR-1, 100-DR-2 Operable Units, so the waste is potentially contaminated soil. Contaminants of Potential Concern indicated by sample data are asbestos, ICP metals, mercury, PCB, herbicide, pesticide, and hexavalent chromium were present.

Closure Info: Interim (8/21/2013): Confirmatory sampling was done in test pits September 2008. Stained areas two and three were partially removed during the remediation of the 120-D-2 waste site.

The above-ground portions of the 186-D Building had been previously removed. Remediation of the 100-D-78 waste site was conducted between April 2 and April 26, 2012, and extended to a depth of 2 meters (6.6 ft) below ground surface. The remove, treat, and dispose (RTD) of stained soil areas one and two consisted of removal of the entire length of the brick acid trench and the entire length of subsurface structure along what had been the west wall of the 186-D Building. Approximately 4,823 BCM of soil, building debris, and acid brick from the acid trench were removed, stockpiled, and then disposed at the Environmental Restoration Disposal Facility (ERDF). The intent of the RTD action was to remove the contents of the acid trench

and any impacted underlying soils. The acid brick trench and the west wall of 186-D structure were removed. However, some remnants of the 186-D structural concrete that was part of the outside wall remained. A small volume of ion-exchange resin found in the acid brick trench was also removed and stockpiled for later disposal at ERDF.

Code: 100-D-80	Classification: Accepted
Names: 100-D-80; 100D Tar Stained Soils & Miscellaneous Debris	Reclassification: Interim Closed Out (3/22/2013)
Type: Dumping Area	Start Date:
Status: Inactive	End Date:

Description: The waste site was divided into two subsites. Both subsites have been reclassified, so the parent site is considered to be Interim Closed Out. The site consisted of four areas that were discovered during the 2006 Orphan Site's Evaluation (OSE) field investigation (EL-1583-6). The areas contained a broken light bulb, tar like material, oil staining and one valve box. 100-D-80:1 is the Tar Stained Soil & Miscellaneous Debris (Areas 1, 2 and 3) and 100-D-80:2 is the Valve Box with Possible Asbestos Insulation (Area 4).

Location: The debris and patches of tar-stained soil in 100-D-80:1 were scattered throughout the 100-D Area.

The 100-D-80:2 valve box was located northwest of the 183-DR Headhouse.

This Site has the Following SubSites:

Code: 100-D-80:1
Names: 100-D-80:1; Tar Stained Soil & Miscellaneous Debris (Areas 1, 2 and 3)
Code: 100-D-80:2
Names: 100-D-80:2; Valve Box with Possible Asbestos Insulation (Area 4)

Code: 100-D-80:1	Classification: Accepted
Names: 100-D-80:1; Tar Stained Soil & Miscellaneous Debris (Areas 1, 2 and 3)	Reclassification: Interim No Action (3/30/2011)
Type: Dumping Area	Start Date:
Status: Inactive	End Date:

Description: 100-D-80:1 has been evaluated and determined to require No Action. The subsite consisted of three areas identified during the 2006 100-D Area Orphan Site Evaluation (OSR-2006-0001). These areas were designated as Area 1, Area 2, and Area 3.

In 2006, Area 1 was described as a single broken light bulb with a metal base, a glass cover and two internal fluorescent-type bulbs located approximately 100 meters (328 ft) south of the 118-D-1 waste site. A site visit on November 4, 2009 found no evidence of the glass debris was found at this location.

In 2006, Area 2 was described as tar-like material with a fiber matrix that appeared to have been dumped (Orphan Site ID# D49). Area 2 was located within the 118-D-3 Burial Ground remedial action sorting cells. In 2009, the material was no longer at this location.

In 2006, Area 3 was described as a tar-and oil-stained area (Orphan Site ID# D65), located approximately 50 m (164 ft) south of the southwest corner of the 182-D Reservoir. In 2009, the

location of Area 3 was vegetated with native grasses. Confirmatory sampling was performed on this portion of the waste site in August 2010.

Location: Area 1 is located approximately 100 m (328 ft) south of the 118-D-1 waste site. Area 1 is centered at coordinates E 573068.8, N 151491.248.

Area 2 is located approximately 260 m (853 ft) southeast of the 100-DR Reactor and 110 m (387 ft) northwest of the 100-D-17 waste site. Area 2 is centered at coordinates E 574022.38, N 151103.16.

Area 3 is located approximately 50 m (164 ft) south of the southwest corner of the 182-D Reservoir. Area 3 is centered at coordinates E 573757.9, N 150857.4.

Waste Type: Soil

Waste Description: The waste is any potentially contaminated soil.

Closure Info: Interim (3/3/2011): Three of the four items discovered in 2006 became 100-D-80:1 and designated as Area 1, Area 2 and Area 3. Remedial investigations were done in 2009.

In 2006, Area 1 was described as a single broken light bulb, a glass cover and two fluorescent type bulbs. In 2009, no glass or light bulbs were found and no samples were collected at this location.

In 2006, Area 2 was described as tar-like material with a fiber matrix. Because this location was within the area used as the 118-D-3 burial ground sorting cell, remnants of the tar-like material were removed during the 118-D-3 remediation activities. No samples were collected at Area 2.

In 2006, Area 3 was described as a tar and oil stained area that measured approximately 1 meter by 2 meters (3 by 7 feet). One shallow soil sample and one duplicate soil sample were collected from Area 3 in 2006. No radiological activity or volatile organic compounds (VOCs) were detected during confirmatory sampling. In 2009, Area 3 was covered by vegetation and no tar or oil staining was visible. In August 2009, additional confirmatory sampling was done at Area 3. The results indicated that environmental contamination was not present, and remedial action was not necessary. The confirmatory sampling data has been used for a No Action determination.

The SubSite is Part Of:

Code: 100-D-80

Names: 100-D-80; 100D Tar Stained Soils & Miscellaneous Debris

Code: 100-D-80:2

Classification: Accepted

Names: 100-D-80:2; Valve Box with Possible Asbestos Insulation (Area 4)

Reclassification: Interim Closed Out (3/22/2013)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: Subsite 2 has been removed and Interim Closed Out. It was a structure believed to be a valve box cover. It was a small wooden structure that contained piping (Orphan Site ID# D76). The valve box cover possibly prevented pipes from freezing during the winter months. A raw water pipeline was known to have existed in the area. The proximity of the valve box to the 91 centimeter (36 in) raw water pipeline would suggest that it is associated with the 100-D-63 pipelines.

Location: This subsite was located south of the 182-D Reservoir and northwest of the 183-DR Head House. Area 4 is centered at coordinates E573111.347, N151295.8. The area dimensions are 1 meter (3 ft) by 1 meter (3 ft).

Waste Type: Not Specified

Waste Description: The waste is potential asbestos containing materials that have been abandoned.

Closure Info: Interim (3/22/2013): The 100-D-80:2 waste site was remediated on January 24, 2013. The wooden structure and contents were removed and disposed at the Environmental Restoration Disposal Facility. The insulation inside of the wooden structure was observed as "fiberglass" insulation rather than friable asbestos. No anomalies were found. Approximately 1.5 bank cubic meters (2.0 bank cubic yards) of soil was removed with the wooden structure resulting in an excavated area measuring approximately 3 by 3 meters (10 by 10 ft) and approximately 0.18 meters (6 in.) deep.

The SubSite is Part Of:

Code: 100-D-80

Names: 100-D-80; 100D Tar Stained Soils & Miscellaneous Debris

Code: 100-D-81

Classification: Accepted

Names: 100-D-81; 100D Burn Areas and Other Stained Areas

Reclassification: Interim Closed Out (3/16/2015)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The waste site has been remediated and Interim Closed Out. Eight soil areas were identified as either stained soil or a burn areas during the 2006 Orphans Sites field walk down.

Area 1 was identified as stained soil #1. The area contains white crusty fragments along with stained soil. The site may have been related to the 107-D Retention Basin. Aerial photos from 1948, 1956 and 1970 did not reveal activity in this location. Area 1 measured approximately 8.6 meters (28.22 feet) x 9.9 meters (32.48 feet).

Area 2 was identified as stained soil #2. The area contained scattered concrete fragments and white crusted areas. Vegetation was not observed growing in the crusted areas. This area may have been related to 100-D-7 and 128-D-2. It is in proximity to the 100-D-7 and 128-D-2 sites that have construction and operations debris on the surface. The 100-D-7 site had a variety of building debris and shop waste along with "a white substance in two localized areas". The 128-D-2 site description stated a "white powder that may be ash" was seen along with concrete and metal debris. The 128-D-2 site also had evidence of surface burning. Area 2 measured approximately 11.3 meters x 20.5 meters (37.07 feet x 67.26 feet).

Area 3 was identified as burned area #1. It was a burned area with native grasses. The area contains evidence of burning. It measured approximately 5.8 meters x 9.3 meters (19.03 feet x 30.51 feet).

Area 4 was potential motor oil contamination. It contained five oil filters with 10-15 bare spots, which appear to be related. The process that caused this area is unknown. The area may have been associated with 118-D-2. Photos from 1943-1989 did not reveal construction or surface disturbance in this area. The site is vegetated with native grasses and rabbit brush. The site is a possible oil changing area. Potential contamination would include oil products. The site is

approximately 10.5 meters by 41 meters.

Area 5 was identified as burn area #2. Evidence of burnt weeds, pieces of wood and metal wire was observed in this location. Photos from this area do not indicate any use during plant construction activities. The area measured approximately 11 meters x 16 meters (36.09 feet x 52.49 feet), has an area of 132.3 square meters (1,424.06 square feet) and a perimeter of 42.8 meters (140.4 feet).

Area 6 was identified as quartz sand #1. It contained quartz sand scattered upon the surface. The site may have been associated with 118-D-2. The area measured 2.4 meters x 2.5 meters (7.87 feet x 8.2 feet). Because quartzite sand has the potential to contain contaminants, it was recorded as a waste site. It was used as a sandblasting material. Photos from 1950 show out buildings that appear to have material in lay down areas surrounding them. The buildings may have been in support of construction of the 183-DR, 190-DR buildings and the 190-DR Clear Wells. A 1956 post construction photo shows a light color spot in the area of concern. The site is vegetated with native grasses and rabbit brush.

Area 7 was identified as quartz sand #2. This site was observed during a field walk down on 4/5/06. Quartz sand was scattered upon the surface that may have been associated with 118-D-2. Photos from 1950 show out buildings in support of the construction of the 183-DR, 190-DR buildings and the 190-DR Clear Wells. These out buildings appear to have material in lay down areas surrounding them. A 1956 post construction photo shows a light color spot in the area of concern. The site is vegetated with native grasses and rabbit brush. Because of the potential for contaminants, quartz sand is recorded as a waste site. The material may have been used for sandblasting. The site measured 2.4 meters x 2.5 meters (7.87 feet x 9.2 feet).

Area 8 was discovered during a field walkdown of the 100 area in 2008. It consisted of multiple stained soil spots, approximately 1 meter (3 feet) in diameter inside an area measuring approximately 50 meters (165 feet). There are about 12 spots in the area and some contain rusted oil filters. The spots are suspected to have been caused by motor oil being dumped to the ground. Area 8 is likely a continuation of Area 4.

Location: The burned and stained areas are scattered throughout the 100-D Area.

Area 1 was located approximately 190 meters (623 feet) east of the 107-D Retention Basin, centered at E 574158.1, N 152282.9.

Area 2 was located approximately 70 meters (230 feet) west to northwest from the 100-D-7 waste site and approximately 100 meters (330 feet) north of the 128-D-2 waste site, centered at E 574220.75, N 152052.

Area 3 was located approximately 70 meters (230 feet) south of the southwest corner of the 182-D reservoir centered at E 573067.2, N 151478.6.

Area 4 was located approximately 300 meters (984 feet) NW of the 118-D-2 waste site, and 20 meters (66 feet) east of the west perimeter road; centered at E572705.8, N151358.6.

Area 5 was located approximately 70 meters (230 feet) west to northwest of the 183-DR Building, centered at coordinates E 573191.688, N 151297.641.

Area 6 was located approximately 130 meters (426 feet) east of the center of the 118-D-2 site with coordinates centered at E 573095.409, N 150937.86.

Area 7 located approximately 130 meters (426 feet) east of the center of the 118-D-2 site. The site was centered at coordinates E 573099.519, N 150916.643.

Area 8 is centered at coordinates E 572696, N 151321. The site is approximately 2 meters southwest of Area 4.

**Release
Description:**

Closure Info: Interim (3/16/2015): According to the remove, treat, dispose (RTD) memo, "100-D-81

Remaining Site for Remedial Action" (WCH 2010), Areas 1, 2, 5, 6, and 7 did not require remediation. Areas 4 and 8 were recommended for RTD without confirmatory sampling based on observations at the sites. Area 3 was recommended for RTD because confirmatory sampling exceeded cleanup levels. Therefore, areas 3, 4, and 8 required remediation.

Remedial action within areas 3, 4, and 8 at the 100-D-81 waste site was performed on July 14, 2014, and July 31, 2014. On July 14, 2014, approximately 1,718 bank cubic meters (BCM) (2,245 bank cubic yards [BCY]) of material were excavated from areas 3, 4, and 8 within the 100-D-81 waste site. This material was staged and loaded out to the Environmental Restoration and Disposal Facility (ERDF) and closed out with the 100-D-72, 100-D-31:11, 100-D-31:12, 100-D-108, and the 100-D-109 waste sites RSVP (WCH 2015). On July 31, 2014, the remaining 14 BCM (18 BCY) of soil was remediated from areas 4 and 8 and loaded out to the ERDF.

Code: 100-D-82	Classification: Accepted
Names: 100-D-82; 100D Garnet Sand Sites	Reclassification: Interim No Action (1/6/2011)
Type: Dumping Area	Start Date:
Status: Inactive	End Date:

Description: The waste site has been evaluated and determined to require No Action. It includes three areas of garnet sand discovered during the WCH Orphan Site's Evaluation field investigation during 2007.

Location: Area 1 is located southeast of the 105-DR Reactor. The site is centered at coordinates E 573909.37, N 151021.07. Area 2 is located just west of the 1716-D Building. It is centered at coordinates E 573516.8, N 151794.9. Area 3 is located northwest of the 105-D Reactor and northeast of the 190-D Building. It is centered at E 573695.229, N 151676.929.

Related Sites/ Structures: Area 1 was associated with 105-DR (Reactor). Area 2 was associated with 1717-D (Maintenance Shop) and 184-D (Power House). Area 3 was associated with 105-D (Reactor) and 190-D (Main Pump House). Also with waste sites 100-D-31:1, 31:2, and 31:7.

Process Description: Garnet sand was recorded as waste sites due to their potential to contain contaminants. Garnet grit was commonly used in sandblasting operations to remove rust, paint, and other contaminants from the surface of metal components. The garnet sand itself is not hazardous.

Waste Type: Soil

Waste Description: Garnet grit was commonly used in grit-blasting operations to clean rust, paint, or contamination from the surface of metal components. The garnet material is not a hazardous substance, but there was a potential for contamination from the surface material that was removed by grit blasting. Contaminants of potential concern include lead, mercury and polychlorinated biphenyls (PCBs).

Closure Info: Interim: A site visit was performed in October 2009. Areas 2 and 3 were observed to have been removed as a part of the 100-D-31:1, 100-D-31:2 and 100-D-31:7 pipelines remediation. Area 1 of 100-D-82 was readily identifiable. It was flat terrain and could be readily accessed for confirmatory sampling. Only Area 1 was addressed by the confirmatory for this waste site.

Confirmatory samples found no radioactivity or volatile organic compounds. Based on the sample results, no remedial action was required.

Code: 100-D-83	Classification: Accepted
-----------------------	---------------------------------

Names: 100-D-83; 100D Treated Water Pipelines **Reclassification** Interim Closed Out (1/7/2015)

Type: Product Piping **Start Date:**

Status: Inactive **End Date:**

Description: The site was divided into five subsites that have all been addressed. Therefore the Parent site is considered to be Interim Closed Out. The site includes 56 additional treated water pipe segments that were not previously identified within an existing waste site. The pipelines supported the pre-reactor non-radioactive cooling water processing facilities. The pipelines were used to transfer chemical products to the water treatment building and treated cooling water to the reactor and laboratory facilities. The additional pipeline segments also include any associated manholes (with associated drains), catch basins, junction boxes, valve control systems or any other below surface related feature.

100-D-83:1 - 183-DR Acid Addition Pipelines has been Interim Closed Out

100-D-83:2 - 183-DR Filter Backwash Connection has been Interim Closed Out

100-D-83:3 - 108-D Acid Addition Facility Pipelines has been Interim Closed Out

100-D-83:4 - Additional Treated Water Pipelines (which has been determined to require No Action)

100-D-83:5 - 186-D Acid Neutralizing System Pipelines has been Interim Closed Out

Location: The treated water pipelines are located adjacent to related facilities (108D, 183D, 186D, 190D, 183DR, and 187-DR).

Related Sites/ Structures: The 108D, 183D, 185D, 186D, 189D, 190D, 183DR, 190DR, annexes, pipe tunnels and associated rail/car unloading spots are associated with this pipeline classification. Associated waste sites include: 100-D-31, 100-D-56, 100-D-77 (DR Reactor Water Treatment Facility, Acid Facility, 183-DR Head House, 183-DR Filter Building, Sodium Dichromate Systems, 183-DR Flocculation Basins, 183-DR Sedimentation Basins) 100-D-73.

Process Description: The 2009 WCH 100-D Area Orphan Site Evaluation identified a number of treated water pipe segments that were not accounted for in other waste sites. Some of the pipe segments connect to (or are extensions of) other waste sites. In some cases the pipe segments have been previously removed by remediation of co-located waste sites. See individual subsites for detailed process descriptions.

This Site has the Following SubSites:

Code: 100-D-83:1

Names: 100-D-83:1; 183-DR Acid Addition Pipelines

Code: 100-D-83:2

Names: 100-D-83:2; 183-DR Filter Backwash Connection

Code: 100-D-83:3

Names: 100-D-83:3; 100-D-83:3 108-D Acid Addition Facility Pipelines

Code: 100-D-83:4

Names: 100-D-83:4; Additional Treated Water Pipelines

Code: 100-D-83:5

Names: 100-D-83:5; 186-D Acid Neutralizing System Pipelines

Code: 100-D-83:1

Classification: Accepted

Names: 100-D-83:1; 183-DR Acid Addition Pipelines

Reclassification Interim Closed Out (10/16/2013)

Type: Product Piping

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. It consisted of thirty five pipeline segments associated with the 100-D-77 (183-DR Acid Facility). It included the low pressure steam, sulfuric acid, and lime slurry lines. The majority of the segments were located within the 100-D-77 acid pipe trench.

Location: The facility was located on the north side of the 183-DR Head House. The majority of the pipeline segments were contained in the acid pipe trench.

Process Description: Sulfuric acid was received by railroad car and stored in two outside aboveground acid storage tanks. The acid was fed by gravity to the 183-DR Head House by maintaining the supply in the Acid Head Tank. The piping between the head tank and the 183-DR Head House was all above grade. Sulfuric Acid was added to the raw water supply before coagulation and filtration to reduce the pH below 7.5 and to aid in the suspension of solids. After filtration, lime was added to the water to raise the pH to between 7.5 and 7.8. Lime slurry was returned to the acid trench for neutralization of the waste acid. The sulfuric acid was reportedly purchased from a mining company and contained mercury and lead.

Waste Type: Not Specified

Waste Description: The waste is the pipelines and any contaminated soil associated with leaks from the pipelines.

Closure Info: Interim (10/16/2013): Remedial action at the 100-D-62 waste site was conducted on May 2 and 3, 2011. A reinforced concrete septic tank, associated concrete piping, and soil were removed as part of the remediation and staged at the Spoil Pile Areas. Approximately 793 bank cubic meters (BCM) (1,037 bank cubic yards [BCY]) of soil and debris was loaded on July 12 and 13, 2011, for disposal at the Environmental Restoration Disposal Facility (ERDF).

Remedial action at the 100-D-77 waste site began on May 3, 2011, and continued through July 13, 2011. The 100-D-83:1 subsite consisted of the pipeline segments associated with the 183-DR Acid Facility. Most of the pipelines were within the 100-D-77 acid trench and were removed during the 100-D-77 waste site remediation. Remediation continued to a depth of approximately 4.5 meters (15 ft) below ground surface (bgs) resulting in approximately 7,103 BCM (9,290 BCY) of contaminated soil and debris that was removed and staged at the staging pile areas (SPAs) prior to loadout and disposal.

The 100-D-83:1 waste site was inside the 100-D-77 site and was fully removed with the 100-D-77 excavation. Verification samples were collected from these three locations on May 29, 2013.

A 20 meter (65.6 ft) section of the 100-D-56:2 pipelines, located at the entrance into the 183-DR Head House, and the 183-DR Filter Building sample room were also remediated with 100-D-77. Loadout of waste material with subsequent disposal at ERDF was conducted between July 13 and October 18, 2011.

At the completion of the remediation, in-process soil samples were collected on July 6 and July 11, 2011, to determine if additional remediation of the waste site was necessary. Mercury was measured above the direct exposure remedial action goals (RAGs) in the in-process sample data. Based on these results, a second tier (Tier 2) of excavation was designed.

The Tier 2 remediation began on December 8, 2011, and continued through January 16, 2012. Approximately 7,126 BCM (9,320 BCY) of contaminated soil and debris were removed from the excavation and moved to the SPAs for loadout and disposal at ERDF. The excavation depth extended a maximum of 9.5 meters (31 ft) bgs. Loadout of the Tier 2 waste material began on December 14, 2011.

The presence of elevated PAH within the excavation area was attributed to cross-contamination of asphalt. Additional remediation of benzo(a)pyrene at location EXC-3 was a result of cross-contamination with asphalt. Additional soil was removed at and around the sample location (EXC-4) with elevated mercury on March 15, 2013. An additional 76 BCM (100 BCY) of contaminated soil and debris were removed from the excavation and staged prior to disposal at ERDF. The area in which additional removal was performed included the FS-1 sample location. Replacement verification samples were collected at the EXC-4 and FS-1 locations on March 15, 2013.

Contaminated soil, concrete, and rebar from previously demolished buildings, piping, and a brick-lined concrete acid trap were among the types of material removed from the excavation. All materials removed from the 100-D-62, 100-D-77, and 100-D-83:1 excavation were staged at five SPAs prior to loadout and disposal at ERDF.

The SubSite is Part Of:

Code: 100-D-83

Names: 100-D-83; 100D Treated Water Pipelines

Code: 100-D-83:2

Classification: Accepted

Names: 100-D-83:2; 183-DR Filter Backwash Connection **Reclassification** Interim Closed Out (1/29/2014)

Type: Product Piping

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. It consisted of the 183-DR water reducing valve pit and three pipeline segments located 20 meters (65.6 feet) northeast of the 183-DR Filter Building. 100-D-83:2 was remediated with 100-D-100.

Location: The subsite was located 20 meters (65.6 feet) northeast of the 183-DR Filter Building and within the 100-D-100 excavation boundary.

Release Description: 100-D-83:2 was remediated with 100-D-100.

Process Description: The backwash water for the 183-DR filters was supplied from the 183-D Pump Room via a 76.2 cm (30 in) carbon steel cross-tie line (100-D-63) to the 183-DR pipe gallery. This line is also used to supplement the 183-DR water requirements including make-up water for the DR Reactor cooling water system (HW-74094, Vol.3). A redundant supply of filtered water was provided via a 40.6 cm (16 in) pipeline (100-D-63) from the 105-D filtered water supply. The two lines, laid parallel to each other, were joined in the water reducing valve pit. The water reducing valve pit had two drain lines (H-1-9660-DR). One was connected to the cross-tie between the backwash and filtered water lines. It received intermittent discharges during pressure surges between the lines. The other drain line collected water in the bottom of the valve pit from leaking valves or pipe repairs. Both drain lines discharged to the process sewer (100-D-50:7).

Waste Type: Not Specified

Waste Description: The waste is the pipeline segments, the valve pit, and any contaminated soil associated with leaks from the pipelines.

Closure Info: Interim (1/29/2014): Hanford construction drawing H-1-9660-DR indicates the base of the valve pit was approximately 15 feet below ground surface. The 100-D-83:2 valve pit was located within the Excavation boundary of the 100-D-100 Stained Soil waste site.

The 100-D-83:2 waste site, including the associated piping and valve pit, were removed during

the Tier III remediation of the 100-D-100 waste site. Approximately 16 meters (52.5 ft) of soil was removed during the 100-D-100 waste site Tier III remediation. Since a significant amount of soil has been removed to a depth well into the deep zone, (more than 4.6 meters (15 ft) below surface grade), there are no direct exposure pathways for the waste site. Field observations during Tier III remediation did not identify any stained soil or other evidence of contamination at the location associated with the 100-83:2 waste site. Therefore, no verification samples are required and the 100-D-83:2 waste site is reclassified as Interim Closed Out.

The SubSite is Part Of:

Code: 100-D-83

Names: 100-D-83; 100D Treated Water Pipelines

Code: 100-D-83:3

Classification: Accepted

Names: 100-D-83:3; 100-D-83:3 108-D Acid Addition Facility Pipelines

Reclassification: Interim Closed Out (1/7/2015)

Type: Product Piping

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. It included the northern segments of a sulfuric acid pipeline (2 in. diameter steel pipe) between the 108-D facility tanks and the 105-D Reactor and a segment of process sewer pipeline (6-in. diameter vitrified clay pipe) located between the 108-D acid neutralization pit and the 100-D-31:3 pipelines.

Location: The 108-D facility (100-D-101) was located approximately 10 meters (32.8 ft) west of the 108-D Chemical Pump House.

Process Description: Sulfuric acid was added to the cooling water upstream of the reactor to lower the pH. The acid was received by railroad tank cars and stored in two above ground storage tanks just west of 108-D. The acid was fed to the 105-D building through a 5.08 cm (2 in) steel pipeline by gravity. The acid neutralization pit was used to balance the pH of the waste acid. The pit drained to the process sewer (100-D-31:3) through a 15.24 cm (6 in) vitrified clay pipe.

Waste Type: Not Specified

Waste Description: The waste is the pipeline segments, the process sewer, and any contaminated soil associated with leaks from the pipelines.

Closure Info: Interim (1/7/2015): Remedial action at the 100-D-83:3 subsite was performed on April 7, 2014. The waste from the site included soil and debris including steel piping, concrete, and brick. A small amount of acid-stained soil was removed in the northern portion of the waste site. Excavation extended to a maximum depth of approximately 2.4 meters (8 ft) bgs.

Approximately 150 bank cubic meters (196 bank cubic yards) of contaminated soil and debris was removed and staged at the staging pile area (SPA). The SPA received waste from the 100-D-83:3 subsite on April 7, 2014. Waste loadout with disposal at the Environmental Restoration Disposal Facility was completed on July 1, 2014. No anomalies were discovered during remediation.

The SubSite is Part Of:

Code: 100-D-83

Names: 100-D-83; 100D Treated Water Pipelines

Code: 100-D-83:4

Classification: Accepted

Names: 100-D-83:4; Additional Treated Water Pipelines **Reclassification** Interim No Action (7/5/2011)

Type: Product Piping **Start Date:**

Status: Inactive **End Date:**

Description: This subsite was evaluated and determined to require No Action. It consists of the remaining treated water pipeline segments that were not addressed by 100-D-83:1, 100-D-83:2, 100-D-83:3 and 100-D-83:5. They include piping associated with the sulfuric acid and sodium silicate supply lines, reused water return lines at the 190-D building and an elevated storage tank drain line south of the 105-DR Reactor Building.

Originally, 100-D-83:4 consisted of four areas of pipelines that were used for treated water and chemical transfer. However, Area 1 will now be addressed with the 100 D 83:5, 186-D Acid Neutralizing System Pipelines. Area 1 consisted of the 18 pipeline segments located west of the 186-D building that are associated with the acid and lime slurry transfer from tanks to the 120 D-2, 186-D Waste Acid Reservoir. A portion of these pipelines, entering the reservoir, were removed during 120-D-2 remediation activities. During confirmatory sampling of the 100 D 83:4 subsite, the pipe tunnels were encountered. It was determined that these segments would be sent to remove, treat, and dispose (RTD). Areas 2, 3, and 4 of the 100 D 83:4 subsite were reclassified to "No Action" on the reclassification form and Remaining Sites Verification package.

Area 2 consisted of 19 pipeline segments located southwest of the 190-D Building that were associated with acid and reused water transfer from the 185-D Deaerating Plant to the underwater test facility. It was known prior to confirmatory sampling that many of these pipelines were removed with previous 100-D-30 remediation activities. As confirmatory sampling was conducted, it became apparent that all of these pipelines had been previously removed. The above ground portion of the 100-D-83:4 pipeline that went south from this location had also been previously removed.

Area 3 consisted of the pipeline segment located at the 187-DR elevated water tank that was associated with transporting untreated emergency cooling water to the 105-DR Reactor in the event that normal flow of cooling water was disrupted.

An additional area of pipelines, which included segments in both the 100-D-83:3 and 100-D-83:4 subsites, was located west of the 108-D Building. It is associated with the sulfuric acid and sodium silicate tanks. Area 4 of the 100 D 83:4 subsite consisted of the pipeline sections that ran from the 108-D tanks towards the 105 D Reactor, but will not be recommended for RTD along with the north-trending 100-D-83:3 pipeline sections, because the pipeline was not located during confirmatory sampling, and is believed to have been removed with the 100-D-31:3 remedial activities.

Location: The sulfuric acid and sodium silicate supply tanks are located just outside the southwest corner of the 190-D Building. Another sulfuric acid line runs between the 108-D Acid Storage Tanks and the 105-D Reactor. The reused water return lines are on the south side of the 190-D Building. The 187-DR elevated storage tank is located on the southeast side of the 105-DR Reactor.

Process 190-D Sulfuric Acid Supply

Description: Sulfuric acid was added to lower the pH of reactor coolant and to prepare activated silica from sodium silicate (HW-34095). The original facility included two acid storage tanks outside the southwest corner of building 190-D that were supplied by piping from a rail car. The acid was later supplied by truck (HW-29542, HW-34095). An acid trench ran from under the two storage tanks to building 185-D where it continued the length of the building. The acid trench has also been referred to as the sodium dichromate trench and was assigned to the 100-D-30 waste site. The original two sulfuric acid storage tanks were relocated to building 183-D in January 1957

(HW-35606, HW-48046). The piping inside the trench was removed during remediation of 100-D-30. A new acid storage tank was installed outside the 185-D building in 1962 as part of the half-reactor test. A 7.6 cm (3 in) acid pipeline was installed between the storage tank and an acid unloading station off the railroad spur just north of the electrical substation 151-D. The test (IP-442-A) which began on January 30, 1963 fed sulfuric acid to lower the pH of the process water for one-half of D Reactor (HW-76398). Two pumps were added to the sulfuric acid storage tank a few months later to permit pH adjustment on the other half of the reactor.

190-D Sodium Silicate Supply

A sodium silicate storage tank was installed in November 1964 south of the 190-D Building not far from the acid storage tanks. The sodium silicate tank was used for another half-reactor test conducted between January 15, 1965 and March 11, 1966 (RL-REA-472 and DUN-1293). Sodium silicate was added to inhibit the formation of film on slug and tube surfaces in the reactor.

190-D Reused Water Return

Filtered water was deaerated before going to the 190-D process water storage tanks or to the refrigeration units (189-D) to remove dissolved oxygen and carbon dioxide (while 186-D was in operation). Steam ejectors exhausted the gases from the deaerators to barometric condensers. The barometric condensers discharged the gases to the atmosphere. Raw water was used to operate the barometric condensers. The raw water (condenser water) was heated in the barometric condensers and emptied into the hotwells below. The condenser water overflowed the condenser hot wells into the reuse water reservoir through a 61 cm (24 in) reused water return line (TNX-PG-4). Hot condenser water was also returned to the storage reservoir (182-D) during the winter through a 50.8 cm (20 in) cast iron pipeline (100-D-63).

108-D Acid Supply Line

Sulfuric acid was added to the cooling water upstream of the reactor to lower the pH. The acid was received by railroad tank cars and stored in two above ground storage tanks just west of 108-D. The acid was fed to the 105-D building through a 5.08 cm (2 in) steel pipeline by gravity. The northern portion of this pipeline is assigned to 100-D-83:3.

105-DR Elevated Storage Tank Drain Line

Two elevated storage tanks (187-DR) with a capacity of 1.14 ML (300,000 G) each were erected to serve 105-DR. Both tanks were located in the vicinity of, and on opposite sides of the 105-DR Building. With the exception of the tank supports, which were cylindrical columns, these installations were the same as the 187-D elevated tanks (HW-24800-34). Both tanks had 7.62 cm (3 in) drain lines that emptied a sump in the floor of the valve pit (W-72733). The tank on the northwest side of 105-DR drained to the process sewer (100-D-50:9). The tank on the southeast side drained to the process sewer (100-D-85:2) on the east side of the reactor. It is this second drain line that has been assigned to 100-D-83:4.

Waste Type: Not Specified

Waste Description: The waste is the contaminated piping, concrete, and soil.

Closure Info: Interim: Confirmatory sampling of the 100-D-83:4 subsite was performed in August 2010. Based on the results, remedial action was determined to be unnecessary. The confirmatory sampling data has been used for reclassification of this site to No Action. The results indicated that the waste site achieved compliance with the remedial action objectives (RAOs) and remedial action goals (RAGs) for subsite, and remediation was not necessary.

The SubSite is Part Of:

Code: 100-D-83
Names: 100-D-83; 100D Treated Water Pipelines

Code: 100-D-83:5
Classification: Accepted
Names: 100-D-83:5; 186-D Acid Neutralizing System Pipelines
Reclassification: Interim Closed Out (6/23/2014)
Type: Product Piping
Start Date:
Status: Inactive
End Date:

Description: The subsite has been remediated and Interim Closed Out. It consisted of two unrelated pipeline areas. It includes the treated water pipeline segments associated with the 186-D Acid Neutralization System (western segments) and the reactor cooling water piping between the 190-D building and the 105-D Reactor (eastern segments).

The lime neutralization plant (186-D Acid Neutralizing System) was located on the southwest side of the 186-D Demineralization Plant. The reactor cooling water piping was housed in two separate tunnels that converge at the 190-D Building upstream of the 105-D Reactor. Several small diameter water lines were also located in the pipe tunnels, including raw water, filtered water, fire protection water, and potential dichromate-treated process water piping.

Location: The lime neutralization plant (186-D Acid Neutralizing System) was located on the southwest side of the 186-D Demineralization Plant. The reactor cooling water piping was located in two tunnels that run between the 190-D Building and the 105-D Reactor.

Related Sites/ Structures: 120-D-2; 186-D Waste Acid Reservoir and the 190-D cooling water process.

Waste Type: Not Specified

Waste Description: The waste is the pipelines and any contaminated soil associated with leaks from the pipelines.

Closure Info: Interim (6/23/2014): The western segments of 100-D-83:5 were originally part of 100-D-83:4. Therefore the confirmatory samples were collected from 100-D-83:4 Test Pit 1 in August 2010 and determined the Remove, Treat, Dispose (RTD) option would be required. The eastern segment was recommended for RTD without confirmatory samples.

Remedial action at the 100-D-83:5 waste site began on April 24, 2013 and continued through June 10, 2013. The waste from the site included residual pipe debris, concrete, soil and debris (including asphalt), building materials, and miscellaneous reactor hardware (unirradiated spacers and perfs). Lead sheeting material was removed from the acid neutralization tanks area. The remnants of the bases of two acid neutralization tanks and one lime storage silo and hopper associated with the demolished 186-D Facility at the south end of the 100-D-83:5 pipeline (western portion) were also removed and disposed. Remediation at the western portion of the 100-D-83:5 waste site at the 186-D acid neutralizing system pipelines extended from 3.5 meters (11.5 ft) bgs to a maximum depth of 8.0 meters (26 ft) bgs. The majority of the pipelines had been previously removed during remediation of adjacent waste sites 100-D-50:7 and 100-D-31:9.

The western pipelines section also included short segments of pipeline located at the northwest corner and east side of 120-D-2. Within the northwest portion of 120-D-2, a segment of 100-D-83:5 extended approximately 8 meters (26 ft) to the south and a second section extended approximately 3 meters (10 ft) north. Post-excavation drawings for the 120-D-2 and 100-D-31:9 waste sites indicated that these pipeline segments had been previously removed. Therefore, no verification sampling was required for the pipe segments in the northwest portion of 120-D-

2. Previous removal of the pipeline segments on the east side of 120-D-2 could not be confirmed. Therefore, a test pit was excavated on September 6, 2013, to determine if the pipes had been removed. A concrete structure was present in the area of the test pit at a depth of approximately 3 meters (10 ft) bgs. This structure had served as a pipe cradle but the pipe had been removed. A test pit was excavated at coordinates N151558.6/E573447.5 to a depth of 3 meters (10 ft) bgs. No pipes were found. A sample (J1TOK9) was collected at the base of the test pit. Per agreement with the Washington State Department of Ecology, no further verification sampling was required for the pipe segments on the east side of 120-D-2.

Remediation at the eastern portion of the 100-D-83:5 waste site between 190-D and 105-D extended to a maximum depth of 6.5 meters (21 ft) bgs. The top of the concrete tunnels had previously been demolished and the tunnels were filled with debris, including pipe debris. The majority of the remaining concrete tunnel structures that contained the 100-D-83:5 pipelines were also removed during remediation. However, a section of one of the tunnels remains due to being located near overhead power lines. Additional safety considerations, including potentially de-energizing the power lines, would have been required for removal of the tunnel. With concurrence with the Washington State Department of Ecology, this section of concrete tunnel was left in place. Portions of the eastern pipelines excavation were within the adjacent 100-D-30 excavation boundary. No indications of contamination were present in the tunnel.

Approximately 1,800 bank cubic meters (BCM) (2,350 bank cubic yards [BCY]) of clean overburden was removed and stockpiled. In total, approximately 12,800 BCM (16,740 BCY) of contaminated soil and debris was removed and placed at the staging pile area (SPA) pending loadout and disposal.

The SubSite is Part Of:

Code: 100-D-83

Names: 100-D-83; 100D Treated Water Pipelines

Code: 100-D-84

Classification: Accepted

Names: 100-D-84; 100D Sanitary Sewer Pipelines

Reclassification: Interim Closed Out (12/16/2014)

Type: Sanitary Sewer

Start Date:

Status: Inactive

End Date:

Description: Both subsites have been reclassified, therefore the Parent site is considered to be Interim Closed Out. The site consists of numerous sanitary sewer pipe segments. It includes underground sanitary sewer connections including associated manholes (and associated drains), catch basins, junction boxes and valve control systems or any other below surface associated feature not previously identified. The sanitary sewer pipelines are service connections supporting ancillary and temporary construction facilities and discharge to associated septic systems. The site was divided into two subsites - 100-D-84:1, Sanitary Sewer Pipelines - Areas 1 and 2 and 100-D-84:2, Sanitary Sewer Pipelines - Areas 3 and 4.

Location: The pipeline segments were observed in various locations throughout the 100-D Area.

Related Sites/ Structures: Ancillary support and temporary construction facilities.

Process Description: The pipelines carried non-radioactive liquid sanitary sewage waste.

Waste Type: Sanitary Sewage

Waste Description: The waste consists of pipelines and any contaminated soil associated with leaks from the pipelines. The contaminants of potential concern (COPCs) are unknown.

This Site has the Following SubSites:

Code: 100-D-84:1

Names: 100-D-84:1; Sanitary Sewer Pipelines - Areas 1 and 2

Code: 100-D-84:2

Names: 100-D-84:2; Sanitary Sewer Pipelines - Areas 3 and 4

Code: 100-D-84:1

Classification: Accepted

Names: 100-D-84:1; Sanitary Sewer Pipelines - Areas 1 and 2

Reclassification: Interim No Action (7/7/2011)

Type: Sanitary Sewer

Start Date:

Status: Inactive

End Date:

Description: Subsite 1 was evaluated and determined to require No Action. It consists of piping from two areas (Areas 1 and 2) as defined in the Confirmatory Work Instruction (0100D-WI-G0092). Area 1 includes 23 pipeline segments south of the 105-DR Reactor Building. Area 2 includes seven pipeline segments northwest of the 105-D Reactor Building.

Location: Area 1 is located approximately 121 meters (400 ft) southeast of the 105-DR Reactor. Area 2 is located approximately 150 meters (500 ft) northwest of the 105-D Reactor.

Related Sites/ Structures: The site was related to ancillary support and temporary construction facilities.

Process Description: The pipelines in Area 1 were the result of temporary construction that was put into place to support 1947 modification of 100-D Area Buildings and facilities and provide a water supply for the existing 105-D Pile Building. At the completion of the construction program, all temporary construction was removed with the exception of the Atkinson-Jones and G.E. Warehouses, a sewage disposal system, and the Atkinson-Jones (A.J.) Superintendent's Building. It is believed that all the Area 1 piping drained to the 100-D-50:9 piping system.

The pipelines in Area 2 were service lines that carried waste from various buildings north of the 105-D reactor to the sanitary sewer main. These buildings included 190-D, 1703-D, 1717-D, 1725-D, 1726-D, 1727-D, 1728-D, and 1729-D. A number of these pipelines were previously removed during remediation of 100-D-31:4 or have been recommended for remove, treat, and dispose (RTD) along with other portions of the 100-D-84:2 subsite.

Waste Type: Not Specified

Waste Description: The waste is the pipelines, pipe contents, and any contaminated soil associated with leaks from the pipelines.

Closure Info: Interim (7/7/2011): Focused samples from four test pit locations were used to evaluate the 100-D-84:1 subsite in August 2010. Based on confirmatory sampling, remedial action was determined to be unnecessary. The analytical results indicated that environmental contamination was not present at this waste site. The residual concentrations of COPCs at this site have met the RAGs and associated RAOs for direct exposure, groundwater protection, and river protection. In accordance with this evaluation, the verification sampling results support a reclassification of the 100-D-84:1 subsite to No Action.

Note: A fifth test pit was to be excavated per the confirmatory sampling plan. However, due to surface obstructions, no sampling was performed at Area 5. Further evaluation of this area

determined that this pipeline connected (on both ends) to the 100-D-31:11 pipelines. Therefore, Area 5 was included in the remedial design for 100-D-31:11.

The SubSite is Part Of:

Code: 100-D-84

Names: 100-D-84; 100D Sanitary Sewer Pipelines

Code: 100-D-84:2

Classification: Accepted

Names: 100-D-84:2; Sanitary Sewer Pipelines - Areas 3 and 4

Reclassification: Interim Closed Out (12/16/2014)

Type: Sanitary Sewer

Start Date:

Status: Inactive

End Date:

Description: Subsite 2 was remediated and Interim Closed Out. It consisted of piping from Areas 3 and 4, as defined in the Confirmatory Work Instruction (0100D-WI-G0092). Area 3 included one pipeline segment, located adjacent to the 107-DR retention basin. Area 4 included one pipeline segment south of the 181-D River Pump House.

Location: Area 3 was located partially within the post-remediation footprint of the 116-DR-9 (107-DR) Retention Basin and protruded approximately 40 meters (132 ft) southwest beyond this waste site. Area 4 was east of the 181-D River Pump House.

Process Description: The pipeline in Area 3 was associated with the 1607-D2 Septic Tank. It carried waste from the septic tank to the drainfield. Most of the pipeline was likely removed in 1950 when the 107-DR Retention Basin was built. The pipeline in Area 4 was the sanitary sewer line that carried waste from the 181-D River Pump House to the 1607-D5 Septic Tank.

Waste Type: Not Specified

Waste Description: The waste is the pipelines, pipe contents, and any contaminated soil associated with leaks from the pipelines.

Closure Info: Interim (12/16/2014): Remedial action at the 100-D-84:2 Area 3 was performed on April 7, 2014. The depth of the remediation extended approximately 3 meters (10 ft) below ground surface resulting in approximately 170 bank cubic meters (222 bank cubic yards) of soil and debris being removed for disposal at the Environmental Restoration Disposal Facility (ERDF). The debris consisted primarily of the vitrified clay pipeline. The waste material was staged prior to loadout to ERDF in a staging pile area (SPA). No overburden soil was stockpiled for use as backfill. No stained soil or anomalous materials were encountered during the remediation.

Due to the 100-D-84:2 Area 4 pipeline segment being located close to an active water line, the Area 4 pipeline segment was closed in place without remediation. Instead, several small potholes, approximately 46 to 61 cm (18 to 24 in.) deep, were excavated by hand to locate the pipeline and collect samples of the pipe contents and the underlying soil. No pipeline was encountered. Therefore, a focused verification soil sample was collected from the pothole location closest to where the pipeline would have entered the drain field.

The SubSite is Part Of:

Code: 100-D-84

Names: 100-D-84; 100D Sanitary Sewer Pipelines

Code: 100-D-85

Classification: Accepted

Names: 100-D-85; 100D Reactor Effluent Pipelines

Reclassification: Interim Closed Out (6/9/2015)

Type: Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:**

Description: The site consists of underground pipelines that transported radioactive treated and untreated waste water from the 105-DR Reactor Building and the 1608-DR (132-DR-1) Building to the 107-DR (116-DR-9) Retention Basin. The pipelines were divided into two subsites containing seventeen pipe segments that were not previously identified. Subsite 1 consists of additional 107-DR Basin Effluent Pipelines. It was evaluated and determined to require No Action. Subsite 2 was remediated and Interim Closed Out. It consisted of additional 105-DR Reactor Effluent Pipelines that were presumed to have been totally removed because they were located within an existing cleanup verification package (CVP) footprint, but were excluded. It also included below grade features associated with the pipeline segments (i.e. manholes, catch basins, junction boxes and valve boxes) not already assigned to any another waste site. Because both subsites have been addressed, the parent site is also being reclassified to Interim Closed Out. Following remedial activities, radiological postings were removed per WCH Interoffice Memorandum #179974, dated July 13, 2015.

Location: The 100-D-85:1 pipeline is located adjacent to the southwest corner of the 107-DR retention basin. The 100-D-85:2 pipelines are located on the east side of the 105-DR reactor.

Related Sites/ Structures: The associated structures include the 105-DR Building, the 132-DR-1 (1608-DR), the 116-DR-9 (107-DR) Retention Basin, the 116-D-5 Outfall and 116-DR-5 Outfall. Other related sites include the 116-DR-1 and 116-DR-2 Trench, the 116-DR-6 Trench, 100-D-48, 100-D Reactor Cooling Water Effluent Underground Pipelines (See Subsites), and 100-D-49, 100-DR Reactor Cooling Water Effluent Underground Pipelines (See Subsites), and 100-D-60, 100D/DR River Effluent Pipelines, 100D River Lines.

Process Description: The pipelines were used to dispose of radioactive cooling and waste water from the reactor facility. Two large main effluent pipelines drained cooling water from the 105-DR Reactor. The small effluent pipelines that drained process waste from the sides (east and south) of the 105-DR were joined into a single pipeline that ran to the 132-DR-1 ([1608-DR Building] Waste Water Pumping Station or Process Lift Station). The building was a rectangular shaped, two-story, reinforced concrete structure that was half below grade elevation. The purpose of this facility was to pump process effluent to the main effluent pipeline. All but one of the pipeline segments are associated with the 105-DR Reactor discharge to the 1608-DR Lift Pump Station (100-D-85:2). The remaining segment (100-D-85:1) connects the two effluent lines (100-D-48:2 and 100-D-49:2) that empty into the 107-D and 107-DR Retention Basins. The reactor effluent pipelines were used to carry reactor cooling water effluent away from the 105-DR Reactor to the 107-DR Retention Basin (116-DR-9), and to the associated outfalls for final discharge to the Columbia River. Contaminated water from building drains in the reactor and piping at elevations below the elevation of the 107-DR Retention Basin flowed by gravity to the 1608-DR Building (132-DR-1) where it was pumped to the 107-DR Retention Basin.

Waste Type: Process Effluent

Waste Description: Waste site contaminants of concern (COCs) identified through process knowledge were identified in the Sampling and Analysis Plan for the 105-F and 105-DR Phase III Below Grade Structures and Underlying Soils (SAP), (DOE/RL-99-35). The 105-DR SAP classified the different areas and structures into affected media that were similar in characteristics and contaminants. The COCs included: americium-241, barium-133, carbon-14, cobalt-60, cesium - 137, europium-152, europium-154, europium-155, nickel-63, plutonium 238, plutonium-239/240, strontium-90, technitium-99, uranium-234, uranium-235, uranium-238, hexavalent chromium, lead, mercury and polychlorinated biphenyls. The waste consisted of contaminated steel piping, concrete, and soil. Chemical additives to reactor cooling water included aluminum sulfate (alum) with excess hydrated calcium oxide, sulfuric acid, chlorine, diatomaceous earth (a scouring agent), and sodium dichromate. Water pH was maintained at about 7.5, and free

chlorine residual was about 0.2 milligrams per liter. Radionuclides discovered at the retention basin during sampling by Dorian and Richards (UNI-946), included: plutonium-238, cesium-134, plutonium 239/240, cesium-137, strontium-90, 155, nickel-63, cobalt-60, and carbon-14. Post Reactor cooling water effluent had anti corrosive chemical additives including pH adjustment and was radioactive.

This Site has the Following SubSites:

Code: 100-D-85:1

Names: 100-D-85:1; Additional 107-DR Effluent Pipeline

Code: 100-D-85:2

Names: 100-D-85:2; Additional 105-DR Reactor Effluent Pipelines

Code: 100-D-85:1

Classification: Accepted

Names: 100-D-85:1; Additional 107-DR Effluent Pipeline **Reclassification** Interim No Action (1/27/2010)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The subsite has been evaluated and determined to require No Action. It consisted of a single pipeline segment identified on one historical drawing, H-1-8348, (HEW 1948); however, it was unknown whether it was ever constructed. The pipeline was believed to be approximately 92 meters (300 ft) in length, buried at approximately 5 meters (16 ft) below ground surface (bgs). It was composed of unknown construction material. If constructed, it was anticipated that the pipe would not have been removed by any previous effluent sewer remedial actions. During excavation of the 100-D-29 waste site, which extended to approximately 4.6 meters (15 ft) bgs into this location, there was no indication of a pipeline.

Location: The pipeline is located adjacent to the southwest corner of the 107-DR retention basin.

Waste Type: Soil

Waste Description: The waste is potentially contaminated soil.

Closure Info: Interim: Confirmatory sampling was performed in August 2010. Undisturbed native soil was encountered at approximately 3 meters (6 ft) bgs. Native black sand was encountered until the base of the test pit excavation ended at 4.9 meters (16 ft) bgs. No pipe was found. Based on field observations and the confirmatory sampling results, remedial action was determined to be unnecessary.

The SubSite is Part Of:

Code: 100-D-85

Names: 100-D-85; 100D Reactor Effluent Pipelines

Code: 100-D-85:2

Classification: Accepted

Names: 100-D-85:2; Additional 105-DR Reactor Effluent Pipelines **Reclassification** Interim Closed Out (6/9/2015)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. The Subsite consisted of sixteen additional reactor effluent pipe segments that were identified during the WCH D Area Orphan

Site Evaluation (OSE). The segments were associated with the 105-DR Reactor that discharged to the 1608-DR Waste Water Pump House. These segments had not been considered part of any existing WIDS site. There was insufficient information to account for their removal during nearby remedial actions. The pipelines consisted of various sizes of cast iron pipe and black steel pipe. The pipe diameters ranged from 3 inches (8 cm) to 18 inches (46 cm).

Location: They are located on the east side of the 105-DR reactor.

Process Description: The pipelines carried process water and steam condensate collected from sumps, floor drains, sinks and steam traps on the eastern half of the 105-DR building. The processes water drained by gravity to the 1608-DR Waste Water Pumping House (132-DR-1) where it was pumped to the main effluent pipeline (100-D-49:3). Many of the 100-D-85:2 pipelines were found to be leaking in 1958 (HW-56911 and HW-57840). Repairs were made and the steam condensate drains were disconnected from the sewers (100-D-85:2) on the north end of the building (HW-58360). Two large main effluent pipelines drained cooling water from the 105-DR Reactor. The small effluent pipelines that drained process waste from the sides (east and south) of the 105-DR Reactor were joined into a single pipeline that ran to the 1608-DR Building.

Waste Type: Not Specified

Waste Description: The waste is contaminated steel piping, concrete, and soil.

Closure Info: Interim (6/9/2015): Remedial action at the 100-D-85:2 subsite began on March 26, 2014. Approximately 13,048 bank cubic meters (17,066 bank cubic yards) of soil and debris were removed resulting in an excavation that is a maximum of 6.5 meters (21.3 ft) below ground surface (bgs). A combination of direct loadout and a staging pile area (SPA) were used to manage the removed material, all of which was ultimately disposed to the Environmental Restoration and Disposal Facility (ERDF). Materials from the SPA area were completely disposed to ERDF by May 6, 2014. Direct loadout from the excavation to ERDF was complete on August 13, 2014. There were no observed anomalies. Materials removed from the 100-D-85:2 excavation included concrete, rebar, and steel pipe. Within the excavation, the partially intact subsurface concrete foundations of several buildings were uncovered and still remain.

The SubSite is Part Of:

Code: 100-D-85

Names: 100-D-85; 100D Reactor Effluent Pipelines

Code: 100-D-86

Classification: Accepted

Names: 100-D-86; 100D Process Sewer Pipelines

Reclassification: Interim Closed Out (6/16/2015)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The site was divided into three subsites. All three subsites have been addressed, so the Parent Site is reclassified to Interim Closed Out. Following remedial activities, radiological postings were removed per WCH Interoffice Memorandum #179974, dated July 13, 2015. The waste site is encompassed 32 process sewer pipeline segments that were not previously identified within an existing WIDS site. Pipelines that were presumed to have been removed in their entirety, because they were located within an existing cleanup verification package (CVP) footprint, were excluded. The waste site includes underground pipelines that transported non-radioactive waste streams from water treatment, reactor, and laboratory facilities. The site includes other below grade features associated with the pipeline segments (i.e. manholes, catch basins, junction boxes and valve boxes) not already assigned to another waste site.

	100-D-86:1 - 105-D Gas Recirculation Pipelines (Interim Closed Out)
	100-D-86:2 - Additional Process Sewer Pipelines (determined to require No Action)
	100-D-86:3 - 105-DR Fan Room Sewer Pipelines (Interim Closed Out)
Location:	The Subsite 1 piping is located in the subsurface tunnel between the former 115-D Gas Recirculation Facility and the 105-D Reactor. The Subsite 2 pipelines are located adjacent to the 105-D, 105-DR and 190-DR facilities. The Subsite 3 pipelines were located on the west side of the 105-DR Fan Room.
Related Sites/ Structures:	The process sewer received effluent from the following facilities: 182-D, 183-D, 183-DR, 184-D, 185-D 186-D, 189-D, 190-D, 105-D, 107-D, 183-DR, the 183-DR Clearwell Area, the 105-DR Reactor Buildings, and the 1907-DR Outfall (100-D-8).
Process Description:	The 100-D Orphan Site Evaluation Report (OSR-2006-0001) identified a number of process sewer pipe segments that were not accounted for in another waste site. These pipe segments were upstream of the reactor effluent discharges and were presumed to carry non-radioactive waste streams from various 100-D/DR Area facilities including the 105-D, 105-DR, 190-D, and 190-DR buildings. The pipelines ultimately discharged to the Columbia River through one of the outfalls (1904-D, 1904-DR and 1907-DR).
Waste Type:	Equipment
Waste Description:	Minor amounts of radionuclide, chemical, and mercury contamination may be present in process sewer lines from the 185-D and 189-D/190-D complex as a result of laboratories once located in these now demolished facilities. The waste consists of steel piping, concrete, and soil (if contaminants are present). The water supply and process sewer drain pipelines at the 100-D and DR Areas provided for the supply and disposal of non-radioactive streams generated in water treatment and water treatment laboratories facilities and powerhouse operations. Known chemical additions to reactor cooling water included aluminum sulfate (alum) with excess hydrated calcium oxide, sulfuric acid, chlorine, and sodium dichromate. Water pH was maintained near 7.5, free chlorine residual at about 0.2 milligrams per liter, and sodium dichromate was added at a rate of about 2 milligrams per liter. Sodium chloride was also used to regenerate water softeners in both water treatment and powerhouse operations.

This Site has the Following SubSites:

Code:	100-D-86:1
Names:	100-D-86:1; 105-D Gas Recirculation Pipelines
Code:	100-D-86:2
Names:	100-D-86:2; Additional Process Sewer Pipelines
Code:	100-D-86:3
Names:	100-D-86:3; 105-DR Fan Room Sewer Pipelines

Code:	100-D-86:1	Classification:	Accepted
Names:	100-D-86:1; 105-D Gas Recirculation Pipelines	Reclassification	Interim Closed Out (6/4/2015)
Type:	Process Sewer	Start Date:	1/1/1943
Status:	Inactive	End Date:	1/1/1967

Description: The Subsite has been remediated and Interim Closed Out. It consisted of the steel gas recirculation piping in the subsurface tunnel between the former 115-D Gas Recirculation Facility and the 105-D Reactor. Features of the subsite included a pipeline described as a 41 cm (16 in) steel pipe that carried reactor atmosphere to and from the 115-D/DR Gas Recirculation Facility. The second feature was a 320 square meter (3,444 sq ft) pipe tunnel between the 115-D/DR Gas Recirculation Facility and the 105-D Reactor. The tunnel was 2.0 meters (6.5 ft) tall,

with the floor being 3.4 meters (11 ft) below the 1st floor of the 115-D/DR Building. It included the vacuum and pressure seal pit, located north of the 1608-D Lift Station.

Location: The Subsite 1 piping is located in the subsurface tunnel between the former 115-D Gas Recirculation Facility and the 105-D Reactor.

**Release
Description:**

**Process
Description:** The gas recirculation pipelines were part of the system that was used to remove radioactive particulates and water from the reactor cover gases. The pipelines were used for the recirculation of helium and carbon dioxide cover gases between the 105-D Reactor Building and the filters and driers in the 115-D/DR Gas Recirculation Facility.

Startup of the 105-D Reactor occurred on December 17, 1944. The 105-D Reactor was provided with an inert, non-radioactive gas environment (reactor atmosphere) to remove moisture and foreign gases. The reactor atmosphere was a mixture of helium and carbon dioxide (HW-74094). The initial and make-up reactor atmosphere was supplied from storage tanks (110-D) located west of 115-D/DR Gas Recirculation Facility. The reactor atmosphere was purified in the 115-D/DR Building and returned to the 105-D Reactor. Parallel, 41 cm (16 in) steel pipes carried the reactor atmosphere to and from the 115-D/DR Building inside an underground reinforced concrete pipe tunnel (W-73950). Connected to, and considered part of the 105-D tunnel, was the vacuum and pressure seal pit. The pit contained two vacuum seal tanks filled with oil (UNI-4281, W-74375). The tunnel also formed part of the 1608-D Lift Station (132-D -3).

The 115-D/DR Recirculation Facility was also used to purify the reactor atmosphere for 105-DR between 1950 and 1964. The piping contained in the 105-DR pipe tunnel was assigned to the 100-D-50:4 waste site. The 115-D/DR Recirculation Facility and the underground pipe tunnels were no longer used after the 105-D Reactor was shut down on June 26, 1967. The 115-D/DR Gas Recirculation Facility and adjoining tunnels were decommissioned by UNC Nuclear Industries in 1985 and 1986 using the Allowable Residual Contamination Levels (ARCL) methodology in conjunction with the in situ decommissioning alternative. The vacuum and pressure seal tanks were removed and disposed of as radioactive waste. The tunnel piping and valves were not removed. The tunnel roof was collapsed from the 115-D/DR Building up to but not including the 1608-D Building. The void was filled with rubble and clean fill. Based on survey data and pre-demolition dose assessment, the tunnel piping/valves met in situ decommissioning criteria (UNI-4281).

Waste Type: Not Specified

**Waste
Description:** The waste consists of steel piping, concrete, and soil (if contaminants are present).

Closure Info: Interim (6/4/2015): The 100-D-86:1 subsite was remediated between March 24 and August 5, 2014. The remediation extended to an approximate maximum depth of 7 meters (23 ft) below ground surface (bgs), resulting in approximately 3,202 bank cubic meters (BCM) (4,188 bank cubic yards [BCY]) of contaminated soil and debris being removed for disposal at the Environmental Restoration Disposal Facility. The debris included steel pipe, concrete, and rebar. All material was direct loaded from the excavation for disposal at the Environmental Restoration Disposal Facility; therefore, no waste staging pile area was generated. Approximately 2,946 BCM (3853 BCY) of overburden material was salvaged from the 100-D-86:1 subsite excavation and stockpiled for use as clean backfill.

A Global Positioning Environmental Radiological Surveyor (GPERS) survey of the overburden pile, conducted in March 2014, detected a radiological hot spot above background. The hot spot was excavated on September 24, 2014.

The SubSite is Part Of:**Code:** 100-D-86**Names:** 100-D-86; 100D Process Sewer Pipelines**Code:** 100-D-86:2**Classification:** Accepted**Names:** 100-D-86:2; Additional Process Sewer Pipelines**Reclassification:** Interim No Action (5/11/2011)**Type:** Process Sewer**Start Date:****Status:** Inactive**End Date:**

Description: Subsite 2 was evaluated and determined to require No Action. It consisted of an additional 13 process sewer pipelines identified on historical drawings during the 100-D Orphan Site Evaluation (OSE). They included piping associated with the 105-D and 190-DR buildings. The 105-DR LSFF pipelines were transferred from the 100-D-86:2 subsite to the 100-D-86:3 subsite, and were recommended for Remove, Treat, and Dispose (RTD).

Location: The Subsite 2 pipelines are located adjacent to the 105-D, 105-DR and 190-DR facilities.

Process Description: The 105-D Building housed a graphite-moderated, water-cooled reactor for the production of weapons grade plutonium. The reactor was located in the process area of the building. Other areas of the building included the control room, fan house, valve pit, work area, storage basin, various offices and equipment storage rooms. Drainage piping was provided throughout the building to carry water from floor drains, steam traps, sumps and trenches to the process sewer (W-71186, W-71617). The process sewer (100-D-31:3) on the west side of 105-D was rerouted when the 190-D Annex was constructed in 1956. A catch basin located outside the northeast corner of the 190-D Annex emptied into the process sewer (100-D-31:3).

190-DR Main Process Water Pump House The 190-DR Building housed pumps that supplied primary cooling water to the 105-DR Reactor (HW-74094 Vol.3).

At 190-DR there were two pump rooms with four pumps in each. The filtered water used for cooling was stored in four large steel storage tanks outside of the 190-DR building. The water was treated with sodium dichromate at the 183-DR Building following filtration prior to entering the storage tanks.

Waste Type: Not Specified

Waste Description: No waste was observed at the site.

Closure Info: Interim: Investigation at the 100-D-86:2 subsite was carried out on November 16 and 17, 2010. Test pits were excavated at six locations. The purpose of each test pit was to determine if process sewer segments associated with the 100-D-86:2 subsite were present in any location.

Test pit 1 (N151287,/E573725) was excavated to a total depth of 6 meters (19 ft) below ground surface (bgs) attempting to access a pipeline associated with the 105-DR Large Sodium Fire Facility (LSFF). Because no pipeline was found in this test pit, an additional test pit was excavated to 6 meters (19 ft) bgs at an alternate location (N151275/ E573725). Because a pipeline was found at the alternate test pit location, the entire Test Pit 1 area was sent to RTD, including the 36 meters (120 ft) of pipeline that extends from this location to the south. Approximately 17 meters (55 ft) of pipeline in the area south of the test pit is in the shallow zone, at a depth of approximately 3 meters (9 ft). The Test Pit 1 area became part of the 100-D-86:3 subsite for RTD.

Test pit 2 (N151189/ E573551) was excavated to a total depth of 1.2 meters (4 ft) bgs,

attempting to access the center of a north-south-trending pipeline shown approximately 15 meters (50 ft) to the east of the 190-DR pump house and west of the valve house test pits 1 and 2 on a temporary drawing. Because the pipeline segment was not found in this test pit, it is concluded that the segment was not present because the pipeline was identified on a temporary piping drawing as being located inside a shallow trench with only 45 cm (18 in.) of sediment covering.

Test pit 3 (N151127/E573543) was excavated to a total depth of 4.6 meters (15 ft) bgs to access the corner of a 20 to 61 cm (8 to 24 inch) steel discharge pipeline. No pipeline was found. It was concluded that the pipeline was removed with demolition of the 190-DR pump house.

Test pit 4 (N151622/E573697) was believed to be the location of a manhole connecting to the 100-D-31:3 subsite. It was planned to be excavated to a maximum depth of 4.6 meters (15 ft) bgs. However, the Test Pit 4 location was determined to be within the excavation boundary of the 100-D-31:4 subsite, which was at a depth of 5.4 meters (18 ft) bgs. Therefore, no excavation was necessary to determine that there was no manhole at this location.

Test pit 5 (N151592/E573698) was excavated to a maximum depth of 4.6 meters (15 ft) bgs, attempting to access a 91 cm (36 in.) diameter manhole associated with the 190-D building annex. Only miscellaneous debris was found during the excavation. The miscellaneous debris included rebar, pieces of concrete, a piece of sheet metal, and a section of conduit. Due to the non-hazardous nature of this debris, the material was backfilled into the test pit when excavation was completed. It was concluded that the manhole and associated piping had been previously removed during demolition of the 190-D building annex.

Test pit 6 (N151036/E573549) was excavated to a maximum depth of 4.6 meters (15 ft) bgs to access a 30 cm (12 in.) diameter drain shown on historical drawings, that to ran north-south and connected with the 100-D-50:1 sewer pipelines. No pipeline was found. It was concluded that this pipeline was never constructed.

The SubSite is Part Of:

Code: 100-D-86

Names: 100-D-86; 100D Process Sewer Pipelines

Code: 100-D-86:3

Classification: Accepted

Names: 100-D-86:3; 105-DR Fan Room Sewer Pipelines

Reclassification: Interim Closed Out (6/16/2015)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The Subsite has been remediated and Interim Closed Out. It consisted of process sewer pipelines that received waste from the 105-DR Fan Room floor drains and condensate. The 105-DR Large Sodium Fire Facility pipelines were transferred from the 100-D-86:2 subsite to the 100-D-86:3 subsite, and are recommended for Remove, Treat, and Dispose (RTD).

Location: Subsite 3 pipelines were located on the west side of the 105-DR Fan Room.

Process Description: The 105-DR Building housed a graphite-moderated, water-cooled reactor for the production of weapons grade plutonium. The fan room housed the main blowers, heaters and air-filters (HAN-10970 Vol. 3). Air was supplied to the 105 Building by two separate supply systems. These supply systems conditioned the air and distributed it to a particular section of the building. The ventilation air supplied to the building spaces outside the confinement zone was exhausted to the atmosphere through roof ventilators. The ventilation air supplied to spaces in the confinement zone was collected by exhaust ducts which discharged into the exhaust tunnel

(HW-74094 Vol. 3). The air in the exhaust tunnel flowed to the exhaust fans in the fan room. At the exhaust fans, the exhaust air became pressurized and was exhausted through an aboveground concrete duct which ran to the base of the 200-foot exhaust stack (116-DR). Originally the ventilation air was released directly to the 116-DR stack. In 1960, air filtering systems (117-DR) were added to minimize the release of radioactive matter (WHC-SD-EN-TI-181).

Waste Type: Not Specified

Waste Description: The waste consists of steel piping, concrete, and soil (if contaminants are present).

Closure Info: Interim (6/16/2015): The 100-D-86:3 subsite confirmatory investigation was performed in November 2010 and one test pit was excavated to a depth of approximately 6 meters (19 ft). No piping was found in the original test pit but a pipe chase was found in an alternative location.

Initial remediation of the 100-D-86:3 waste site was performed on November 14, 2013. Approximately 2,130 bank cubic meters (BCM) (2,786 bank cubic yards [BCY]) of excavated materials were removed and staged in a waste staging pile area (SPA) prior to disposal at the Environmental Restoration Disposal Facility (ERDF). The maximum depth of the waste site excavation was approximately 2 meters (6.6 ft). Excavated materials consisted of soil, gravel, and pipe debris.

During the 100-D-86:3 subsite remedial activities, the end of an 20 centimeter (8 in.) diameter steel pipeline was uncovered on the northern sidewall of the excavation at approximately 2 meters (6.6 ft) bgs. Based on visual observations, the pipe appeared to be intact and took a steep subsurface dive to connect with the Interim Closed Out 100-D-50:1 subsite. The high voltage overhead power line, trending east-west, on the northern side of the excavation precluded the excavation of this pipeline segment during the initial remediation. The entire 100-D-86:3 subsite excavation area was re-excavated between June 26 and July 31, 2014, and again on January 9, 2015 per the 100-D-86:3 Additional Remediation and Resampling agreement. Approximately 740 BCM (809 BCY) of additional material was removed from the 100-D-86:3 excavation area.

For the entire 100-D-86:3 subsite remediation approximately 3,536 BCM (4,612 BCY) of excavated materials were removed from the 100-D-86:3 subsite excavation and disposed at ERDF. No overburden materials were salvaged from the 100-D-86:3 waste site excavation.

The SubSite is Part Of:

Code: 100-D-86

Names: 100-D-86; 100D Process Sewer Pipelines

Code: 100-D-87

Classification: Accepted

Names: 100-D-87; Spill Near Railroad Car Spot

Reclassification: Interim No Action (1/6/2011)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The waste site consists of a suspected unplanned release of liquid near the acid railroad tank car spot. When the spill was photographed in 1945, liquid was present on the surface of the ground north of the railroad car spot on track "B".

The only documentation identifying the spill were construction drawings H-1-281, W-74157 and W71800. The drawings indicate that a 45 centimeters (18 inches) tile is buried in the ground at the car spot. The car spot contained two transfer pumps and two 7.6 centimeters (3

inches) diameter pipelines. The pipelines transported acid to the acid tanks at the 186-D and 185-D Buildings. There were six acid tanks on the west side of the 186-D Building and two on the south side of the 185-D Building.

Location: The railroad car spot was located between the 186-D and 189-D Buildings.

Related Sites/ Structures: The 186-D and 190-D Buildings and waste sites 100-D-63 (clean water pipelines) is about 20 m (65 ft) northeast of 100-D-2 (lead sheet covering a concrete pad).

Process Description: The car spot was used to unload acid that was transported through overhead lines to storage tanks at the 186-D and 190-D Buildings.

Waste Type: Chemical Release

Waste Description: The spill was probably acid associated with the car spot unloading facility. The contaminant of potential concern was acid.

Closure Info: Interim: Confirmatory samples were collected from five test pits ranging in depth from 2 to 10 feet deep.

No staining, anomalies, tiles or linear features were encountered during confirmatory sampling. Analysis was performed to evaluate if contamination associated with the potential spill was present. Field surveys for radiological contamination and volatile organic compounds were also conducted during sampling. Confirmatory sampling indicated that environmental contamination was not present at this waste site. Based on confirmatory sampling at the site, remedial action was determined to be unnecessary.

Code: 100-D-88

Classification: Accepted

Names: 100-D-88; 100D Miscellaneous Pipelines

Reclassification: Interim No Action (5/16/2011)

Type: Product Piping

Start Date:

Status: Inactive

End Date:

Description: The site consists of 27 underground pipeline segments observed during the WCH Orphan Site's Evaluation. The additional pipeline segments include associated manholes (with associated drains), catch basins, junction boxes, valve control systems or any other below surface related feature.

Location: The pipeline segments are located throughout the 100-D Area.

Related Sites/ Structures: The 105DR, 185D, 184DA, 183D, 190D and elevated tank 187-DR1

Process Description: Miscellaneous pipeline segments are associated within unique building processes; boiler fuel delivery systems, elevator shafts, air conditioning systems, railcar/truck delivery spots, equipment drains, storage tanks pressure relief systems, compressor blowdowns and potential contact steam system condensate returns drained to below ground features.

Closure Info: Interim: Focused samples from eight test pit locations were planned to be used to evaluate the 100-D-88 waste site. However, upon preparation for confirmatory sampling, it was determined that test pit 7 could not be excavated, due to the presence of an internet tower in this location. The tower, which includes a base in the location of the french drain, indicates that this drain no longer exists due to the presence of guy wires at approximately 2 to 2.5 m (6 to 8 ft) below ground surface. Therefore, sampling was not necessary to make a No Action decision for this portion of the 100-D-88 waste site. Test pits were excavated at the remaining seven locations of the Pipeline segments of the 100-D-88 waste site to collect samples or verify removal of the associated piping. These seven test pits are adequate to represent the 100-D-88 waste site, as the

absence of a french drain at the test pit 7 location changes the condition of the waste site such that seven sampling locations, instead of eight, are adequate to evaluate the waste site. All radiological and volatile organic vapor readings in the field were less than detectable.

Code:	100-D-90	Classification:	Accepted
Names:	100-D-90; 100-D/DR Out of Service Transformers	Reclassification	Interim No Action (1/6/2011)
Type:	Unplanned Release	Start Date:	
Status:	Inactive	End Date:	
Description:	The site has been evaluated and determined to require No Action. It consists of the soil located below two transformers sitting on railroad ties. The transformers were removed from service in 2003 and drained by the Fluor Electrical Utilities group in July 2005.		
Location:	The transformers had been located 18 meters (60 feet) west of the 183-D Facility next to the paved two lane road. The transformers and railroad ties were removed and staged in the 200 Area laydown yard. Although the waste site had been originally described as an unplanned release, it became apparent through further research that a known release had not occurred.		
Related Sites/ Structures:	These transformers are possibly associated with the 190-DR Building. The transformers were removed from service in 2003 and drained by the Fluor Electrical Utilities group in July 2005.		
Process Description:	There is no process associated with this site. The site is only the staging area for two transformers which may have originated from the 190-DR facility.		
Waste Type:	Soil		
Waste Description:	The transformers contained oil with <499 ppm of PCBs (per Fluor Electrical Utilities). The site has the potential to contain PCBs. However, there was no evidence of staining associated with this site, therefore, there are no contaminants of potential.		
Closure Info:	Interim: The soil exhibited no visible staining, and the transformers and railroad ties had been removed and staged in the 200 Area laydown yard. Although the waste site had been originally described as an unplanned release, it became apparent through further research that no release had occurred.		
	Because analytical documentation on the drained fluid from the transformers was not available, confirmatory sampling was performed in August 2010. The sample results indicated no remediation was required.		
	The transformers had been recorded in WIDS for tracking purposes. Thus, PCBs were determined to be the only COPC for the site, based on professional judgment and other transformer COPCs. PCBs were analyzed for this waste site using EPA Method 8082.		

Code:	100-D-96	Classification:	Accepted
Names:	100-D-96; 100-D/DR Additional French Drains	Reclassification	Interim Closed Out (2/18/2015)
Type:	French Drain	Start Date:	
Status:	Inactive	End Date:	
Description:	Both subsites have been addressed, so the parent site has been reclassified to Interim Closed Out. The waste site originally consisted of seven french drains and two dry wells. They were assigned corresponding numbers FD-1 through FD-9 for identification purposes. All but one		

feature was believed to have received steam condensate from non-radioactive buildings. The source for the ninth feature was determined to be a pressure relief valve. The site was divided into two subsites on November 19, 2012 to accommodate remediation of French Drain #4 (FD-4), separate from the other eight features. The drains in Subsite 1 were evaluated and determined to require No Action. The drain in Subsite 2 (FD-4) was remediated and Interim Closed Out.

Location: The french drains were located throughout the 100-D/DR Area. Refer to the subsites for the locations of specific features.

Process Description: The features were identified during the 100-D Area Orphan Site Evaluation (OSE). The evaluation included reviewing construction drawings, aerial photographs, GIS utility layers, process knowledge and field observations (EL-1583-6). The conclusion of the OSE was that these features were used for the disposal of steam condensate.

Steam was typically used at all facilities for heating purposes. The 184-D Power House boiler facility supplied high pressure steam to all buildings through an above grade pipeline system. The boiler facility utilized clean filtered water from the 183-D filter building. The steam supply was used in a non-contact radial heating system. As a non-contact system the steam remained uncontaminated. The steam transport process utilized a high pressure supply line and a low pressure return or discharge line. It was necessary to bleed both the supply and return lines to prevent condensate build up. The condensate was typical blow off from the above grade piping system into a below grade covered french drain as a safety precaution as illustrated on construction drawing H-1-9644-DR and H-1-15203. Construction drawings H-1-9640-DR thru H-1-9645-DR of the outside steam distribution system indicate steam trap locations (french drains) and typical construction. The size and construction of the french drains diameters varied depending on steam piping size, service capacity pounds per hour, and expected flow rate received.

This Site has the Following SubSites:

Code: 100-D-96:1

Names: 100-D-96:1; 100-D/DR Additional French Drains Group 1

Code: 100-D-96:2

Names: 100-D-96:2; FD-4; 100-D/DR Additional French Drains Group 2

Code: 100-D-96:1

Classification: Accepted

Names: 100-D-96:1; 100-D/DR Additional French Drains Group 1

Reclassification: Interim No Action (1/17/2013)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The french drains in Subsite 1 were evaluated and determined to require No Action. The 100-D-96:1 subsite, includes six french drains, two dry wells, and the underlying soil.

The following are the features associated with this subsite:

FD-1 site is a 0.6 meter (2 ft) concrete french drain that is 5 centimeters (2 in.) above grade. It is filled with cobble.

FD-2 site is a 0.45 meter (1.5 ft) concrete french drain at grade level. It is cobble filled.

FD-3 site is a 0.6 meter (2 ft) concrete french drain at grade level. It is covered with a steel plate with pipe inlet notch.

FD-5 site is a 0.9 meter (3-ft) vitrified clay pipe french drain that is 23 centimeters (9 in.) above

grade. It is filled with cobble.

DW-1 site was a 0.9 meter (3-ft) concrete dry well at grade level covered with a steel plate with pipe inlet notch. It was removed during remediation of the 100-D-31:9 Process Sewer Pipelines subsite in 2009 and 2010. According to drawing H-1-9644-DR, the depth of DW-1 was approximately 3.5 ft (1.1 m). Final depth for the 100-D-31:9 subsite excavation was approximately 7 meters (23 ft).

FD-6 french drain was not located during the discovery site investigation. The french drain was identified and excavated during the remediation of the 100-D-31:8, 183-D and 186-D Northern Sewer Pipelines subsite in 2009 and 2010. The final depth for the 100-D-31:8 subsite excavation was approximately 9 meters (30 ft).

FD-7 site is a 0.45 meter (1.5 ft) french drain. The FD-7 french drain was not located during the discovery site investigation, and it is unknown if the french drain was removed or was covered (DUN 1968, GE 1968).

DW-2 site is a 0.9 meter (3 ft) concrete dry well at grade level covered with a steel plate with a concrete rim. It was determined (H-1-26509 and H-1-9641-DR) to be consistent with the pressure relief valve (PRV) for the high pressure steam supply line to the 151-D annex building. Steam condensate was discharged to DW-2 drywell location.

Location: FD-1 - South of the 151-D Switch Yard at Washington State Plane coordinates E573513.9 N151277.7.

FD-2 - East of the 151-D Switch Yard at Washington State Plane coordinates E573618.03 N151354.5.

FD-3 - Northeast of the 1716-D Maintenance Garage at Washington State Plane coordinates E573551.5 N151801.6.

FD-5 - East of the 181-D River Pump House at Washington State Plane coordinates E572813.3 N151736.1.

DW-1 - East of the 183-D Clear wells at Washington State Plane coordinates E573383.1 N151597.2.

FD-6 site is a 0.6 meters (2-ft) french drain located west of the 184-DA Building at Washington State Plane coordinates E573406.0 N151743.0.

FD-7 - Northwest of the 1716-D Maintenance Garage at Washington State Plane coordinates E573551.0 N151797.0

DW-2 (FD-9) - North of the 151-D Switch Yard at Washington State Plane coordinates E573520.5 N151396.2.

Process Description: Steam was typically used at all facilities for heating purposes. The 184-D Power House boiler facility supplied high pressure steam to all buildings through an above grade pipeline system. The boiler facility utilized clean filtered water from the 183-D filter building. The steam supply was used in a non-contact radial heating system. As a non-contact system the steam remained uncontaminated.

Closure Info: Interim (1/17/2013): Confirmatory sampling of the 100-D-96 french drains was performed on June 6 and 7, 2012. The sample results indicated that french drain FD-4 exceeded the regulatory limit for benzo(a)pyrene. FD-4 became 100-D-96:2, to be addressed separately.

The 100-D-96:1 subsite includes six french drains, two dry wells and the underlying soil. Two of the drain features (FD-6 and DW-1) were removed with process sewer pipeline remediation activities.

The SubSite is Part Of:**Code:** 100-D-96**Names:** 100-D-96; 100-D/DR Additional French Drains**Code:** 100-D-96:2**Classification:** Accepted**Names:** 100-D-96:2; FD-4; 100-D/DR Additional French Drains Group 2**Reclassification** Interim Closed Out (2/18/2015)**Type:** French Drain**Start Date:****Status:** Inactive**End Date:**

Description: The subsite has been remediated and Interim Closed Out. It was a 0.6 meter (24 inches) diameter French Drain that was designated FD-4. It was constructed of concrete, cobble filled, and at grade level. It is believed to have received steam condensate from the non-radioactive 183-D filter building.

Location: FD-4 was approximately 90 meters (295 ft) northeast of the 183-D, Water Treatment Plant at Washington State Plane coordinates E573403.86 N151775.94.

Process Description: Steam was typically used at all facilities for heating purposes. The 184-D Power House boiler facility supplied high pressure steam to all buildings through an above grade pipeline system. The boiler facility utilized clean filtered water from the 183-D filter building. The steam supply was used in a non-contact radial heating system. As a non-contact system the steam remained uncontaminated.

Closure Info: Interim (2/18/2015): Confirmatory sampling of 100-D-96:2 french drain FD-4 was performed on June 7, 2012. The FD-4 french drain was excavated and found to be two sections of reinforced concrete pipe. If stacked together vertically, the two sections of pipe extended to approximately 1.5 meters (5 ft) below ground surface (bgs). The contents of the french drain were primarily rusty cobbles at the top and sandy soil near the bottom. A sample (J1PR51) was collected of sandy soil inside the french drain. A sample (J1PR52) and duplicate (J1PR53) were collected of the underlying soil, at an approximate depth of 2.7 meters (9 ft) bgs. Following sample collection of the underlying soil, the concrete pipe structures were placed sideways at the bottom of the excavation and backfilled with the excavated materials.

Remediation of the 100-D-96:2 subsite was performed on May 13, 2014. Approximately 150 bank cubic meters (196 bank cubic yards) of excavated materials were removed and staged for disposal at the Environmental Restoration Disposal Facility (ERDF). The depth of the waste site excavation was approximately 1.8 meters (6 ft) bgs. Excavated materials consisted of soil, french drain rock, and reinforced concrete pipe. The french drain concrete pipe sections were found at an approximate depth of 1.5 meters (5 ft) bgs during remediation. These concrete pipe sections and an additional 0.3 meters (1 ft) of underlying soil were excavated for disposal at the ERDF. No radiation was detected within the excavation area and no anomalies were found.

The SubSite is Part Of:**Code:** 100-D-96**Names:** 100-D-96; 100-D/DR Additional French Drains**Code:** 100-D-97**Classification:** Accepted**Names:** 100-D-97; 184-DA 500-Gallon Fuel Tank**Reclassification** Interim Closed Out (4/2/2015)**Type:** Storage Tank**Start Date:****Status:** Inactive**End Date:**

Description: The site has been remediated and Interim Closed Out. It consisted of a 500 gallon underground storage tank (UST) associated fuel oil supply (FOS), fuel oil return (FOR) piping [1.27 centimeter (1.5 inch) diameter] and the underlying soil. It had been suspected that these items were removed in 1985/1986, as part of the 100-D/DR general demolition efforts that included a large fuel oil storage tank (see 100-D-9, 184-DA Boiler Oil Tank). However, during confirmatory sampling segments of fuel oil piping were discovered. The 500 gallon fuel oils storage tank (seen on H-1-15206) was not found during the excavation activities.

Location: The 500 gallon tank was located in the 100-D Area, near the southeast corner of the 184-DA Boiler House. It was approximately 1 meter (3 feet) southeast of the 184-DA building.

Related Sites/ Structures: This waste site is associated with the previously remediated 100-D-9 site. 100-D-9 was the underground storage tank supplied fuel oil to the 184 DA Steam Generating Facility and provided steam to the 183-D and other 100-D facilities. The 184-DA Boiler Oil Tank (100-D-9) was near the northwest corner of 184-DA.

Process Description: The UST was a 500 gallon fuel oil tank which supplied fuel to the 184-DA Steam Generating Facility. The 184-DA Building was a metal building constructed about 1968 and was designed as a steam generating facility. The facility contained a steam generator, a large fuel oil storage tank [94,600 Liters (25,000 gallons)], fuel oil pump, deaerator, water softener, chemical treatment, fuel tank, steam separator, heater, diesel generator, liquid level gauges, and steam flow meter. The 500 gallon fuel oil tank was located near the southeast corner of the 184-DA Building. The tank was installed about 1968 under Project No. Dap-515 and buried two feet below grade. The equipment number was K1-7-1. The tank had a 2 inch fill connection and a 2 inch sounding connection. Within the floor of the 184-DA Building were three trenches that contained pipelines used to transport fuel oil and vent lines associated with the fuel oil tanks. In 1973, the building was assigned to Atlantic Richfield Hanford Company (ARHCO), it contained a package boiler which was used to provide steam heat for the occupied facilities in 100-D Area. In case of electrical power outage, the boiler also provided steam for turbine driven pumps used to provide fire and service water to the 100-D facilities. The facility was required to remain in service as long as the area was occupied. It was assumed that the tank was removed during the demolition of the 184-DA Building.

Closure Info: Interim (4/2/2015): Remediation of the 100-D-97 waste site was conducted on February 25, 2014. The remediation extended to approximately 2 meters (6.6 ft) deep, resulting in approximately 70 bank cubic meters (92 bank cubic yards) of soil and piping debris being removed and placed in a staging pile area (SPA). Materials staged in the SPA area were disposed to the Environmental Restoration Disposal Facility on June 26, 2014. The steel piping debris that was removed is thought to be part of the boiler fuel oil piping (see 100-D-9). The 500 gallon fuel tank was not found in the excavation. The soil and debris were later loaded out and disposed at the Environmental Restoration Disposal Facility. There were no anomalies found during the remediation of the 100-D-97 waste site.

Code: 100-D-98	Classification: Accepted
Names: 100-D-98; 152D Substations	Reclassification: None
Type: Electrical Substation	Start Date:
Status: Not Specified	End Date:

Description: The site consists of twenty-one electrical substations and underlying soil. Each of the substations were surrounded by a fence that contained transformers at or near ground level, set on concrete pads (p. 17, WHC-MR-0425). The waste site does not include transformers mounted on electrical poles or the sides of a building. The 153-D, substation adjacent to 107-D, was excluded because it was made of up three small pole mounted transformers.

The site has been divided into three subsites - 100-D-98:1 is two Active 152D Substations. 100-D-98:2 is eighteen Inactive substations located at 152D and 153D. Subsite 2 was evaluated and determined to require No Action. 100-D-98:3 is only the 153-D-5 substation. The Subsite 3 concrete slab and underlying soil were remediated and the subsite was reclassified to Interim Closed Out.

During the Orphan Sites Evaluation (OSE) no staining or evidence of a substation was observed at the mapped locations of the nine former substations. They each had a primary voltage of 13.8 kV and a secondary voltage ranging from 110 V to 230 kV. Each was an open, wooden pole structure surrounded by a picket fence and contained transformers at or near ground level, set on concrete pads. Excluded from the site were an additional six distribution substations known to have been associated with buildings 107-D, 108-D, 115-D, 183-D, 1717-D, and 1720-D. These six could not be located during the OSE field investigation. Each was constructed identical to secondary substations. All had a primary voltage of 2.4 kV, and a secondary voltage ranging from 110 V to 480 V. Information on the exact location of these substations is extremely limited. There was no physical evidence of transformer pads or staining on the ground near the suspect locations. It is assumed that the distribution substations were removed during demolition of the buildings.

- Location:** The substations are located throughout the 100-D/DR Area. Specific locations are defined in the subsite text.
- Related Sites/ Structures:** The 151-D Primary Substation distributed 13.8 kV power to transformers located at the 181-D River Pump House, 182-D Head House, 183-D Filter House, 184-D Power House, 186-D Water Treatment Plant, 190-D Pump House, and 105-D Reactor, which in turn distributed power to associated facilities.
- Process Description:** The Midway Station fed 230 kV power to the 31,250 kVA transformers located in the 151-D switchyard. From these transformers, power was transmitted via overhead and underground cables to secondary and distribution substations located throughout the 100-D Area. The substations had transformers that reduced the voltage to a value suitable for the local distribution system or facility. The transformers contained oil that cooled and insulated the windings. Polychlorinated biphenyls were once widely used in transformer oil due to their heat resistant properties. The transformers were filled with oil using hoses from oil trucks.

The Midway Station, located near the Vernita Bridge, fed 230 kV power to the 31,250 kVA transformers located in the 151-D switchyard. From these transformers, power was transmitted via overhead and underground cables to secondary distribution substations located throughout the 100-D Area. Circuit breakers were also in service to support the switchyard operations. The 151-D Switch House is essentially a one-story building, having a sub-level cable pit equipped with a sump pump. All duct lines originated/terminated at the Switch House. The cable pit is a completely enclosed reinforced concrete pit with floor slab, varying from 0.30 to 0.45 meters (1 to 1.5 feet) in thickness, and with 0.30 meters (1 foot) thick walls. Switchgear is located on the main floor directly above the cable pit. The overall dimensions of the Switch House are 25 meters by 9.3 meters by 8.7 meters (83 feet by 30.5 feet by 28.5 feet). Beneath the switch yard, and throughout the D/DR area there is an extensive subsurface "highway" of electrical conduits, which may still contain lead and/or asbestos wrapped cable inside "Korduct" lining, all surrounded by reinforced concrete. Korduct is believed to be a transite-like material. These concrete monoliths are up to 1.8 meters by 1.8 meters (6 feet wide by 6 feet deep) and up to 152 meters (500 feet) long per segment, and are buried 0.9- 1.5 meters (3-5 feet) below the surface. There are at least 20 major segments in the D/DR area. The segments are connected by mammoth concrete manholes, 2.4 meters by 2.4 meters by 2.4 meters (8 feet by 8 feet by 8 feet high). Each monolith contains up to 2 dozen conduits, each of which may contain 0.6- 12.7 centimeters (2-5 inches) electrical cables.

PCB-containing oil was transferred, as needed, from a rail tanker on the railroad spur through

over ground hoses and piping to transformers and oil circuit breakers in the yard. The smaller transformers at the secondary and distribution substations were also filled via over ground hoses from oil trucks.

Waste Type: Transformer

Waste Description: The two active substations (C4S17 and 152-D1-D) will be evaluated upon termination of operations. There was no documented waste information found during the OSE historical evaluation. There were no contaminants of potential concern assigned to the sites discovered during historical evaluation.

This Site has the Following SubSites:

Code: 100-D-98:1

Names: 100-D-98:1, Active Electrical Substations at 100-D Area

Code: 100-D-98:2

Names: 100-D-98:2; Inactive Electrical Substations at 100-D Area

Code: 100-D-98:3

Names: 100-D-98:3; 153-D-5 Electrical Distribution Substation

Code: 100-D-98:1

Classification: Accepted

Names: 100-D-98:1, Active Electrical Substations at 100-D Area

Reclassification: None

Type: Electrical Substation

Start Date:

Status: Active

End Date:

Description: This site consists of two active (C4-S17 and 152-D1-D) electrical substations and underlying soil.

Location: The C4-S17 Substation is located approximately 990 meters (3245 ft) west of the 105-D Reactor Building, adjacent to the south wall of the 181-D River Pump House (H-1-5100, Sheet 3, H-1-26611). The coordinates for the pads at the substation are N151725.34, E572791.61 and N151722.45 E572788.74.

The 152-D1-D Substation is located immediately east of the 182-D Reservoir and Pump House, approximately 565 meters (1850 ft) west of the 105-D Reactor Building (H-1-222). The coordinates for the substation are N151563.88, E573207.86.

Process Description: The Midway Station fed 230 kV power to the 31,250 KVA transformers located in the 151-D switchyard. From these transformers, power was transmitted via overhead and underground cables to secondary and distribution substations located throughout the 100-D Area. The substations had transformers that reduced the voltage to a value suitable for the local distribution system or facility. The transformers contained oil that cooled and insulated the windings. Polychlorinated biphenyls were once widely used in transformer oil due to their heat resistant properties. The transformers were filled with oil using hoses from oil trucks.

The C4-S17 Substation (152-E2-D) was constructed in 1957 and provided electricity to the 181-D Building. It contained two large transformers as well as additional electrical equipment. The transformers were connected to the 181-D Building switchgear through underground conduits. It was a 13,800/2400 volt, 3750/4687 kV substation that was added to support the additional demand at the 181-D Building after the increase in pumping capacity (p. 29, HW-24800-104 and p. 31, HW-30401).

The 152-D1-D Substation was constructed in 1944 and provided electricity to the 182-D

Building (H-1-26569). It was an open wooden pole structure surrounded by a picket fence and was constructed with one transformer set on a concrete pad (pp. 653, 716 and 717, HAN-10970, Volume 3). The transformer had a capacity of 3000 kV with a primary voltage of 13.8 kV and a secondary voltage of 2.3 kV (W-72007).

The SubSite is Part Of:

Code: 100-D-98

Names: 100-D-98; 152D Substations

Code: 100-D-98:2

Classification: Accepted

Names: 100-D-98:2; Inactive Electrical Substations at 100-D Area

Reclassification: Interim No Action (1/17/2013)

Type: Electrical Substation

Start Date:

Status: Inactive

End Date:

Description: This waste site has been evaluated and determined to require No Action. It consists of 19 inactive electrical substations (secondary and distribution) and underlying soil. Three substations were relocated. The original and the new locations are considered part of this waste site, making a total of 22 substation locations.

Most were an open, wooden pole structure surrounded by a picket fence and contained transformers at or near ground level, set on concrete pads. All substations and all but one concrete pads were removed and demolished with the associated building. Following excavations of these sites, clean soil, non-hazardous debris, and potential asbestos containing material (ACM) were backfilled. This potential ACM would have been buried deeper than 6 inches and covered with compacted non-asbestos containing material.

Substations Associated with 105-D - locations #9a and #9b are within the boundaries of the 118-D-6:4 and 118-D-6:5 waste sites, respectively.

Substations Associated with 108-D - location #10 is located a few feet from the 100-D-73 (108-D pump house) excavation. The 108-D Building was demolished in 1978 and the rubble was disposed of in the 126-D-2 coal pit, inert landfill. It is concluded that all concrete and possible contamination have been removed.

Substations Associated with 115-D - location #11 is located within the boundary of the 132-D-1 waste site.

Substations Associated with 183-D - #12 transformer pad is still visible. It is anticipated that this concrete slab and surrounding soil will be deferred to the Deactivation, Decontamination, Decommissioning, and Demolition (D4) Closure Project and the demolition of the 183-D Building.

Substations Associated with 184-D - The location #1 concrete structure was previously demolished to at least 1 meters (3 ft) below ground surface (bgs). All material was handled, packaged, and transported for disposal in the Hanford central landfill in 1988.

Substations Associated with 185-D - location #3 is located within the boundary of the 100-D-31:9 waste site.

Substations Associated with 186-D - location #2 was part of the 186-D Building. The 186-D foundation, adjacent basins, and pits were demolished in 1979. The basin and pits were filled

and the site leveled to blend with the adjacent area. The structural steel was salvaged and sold as excess material.

Substations Associated with 189-D - location #19 is clean with no visible staining. The 189-D Building would not have been demolished if any contamination or hazardous material was present in the area.

Substations Associated with 190-D - location #4 is within the 132-D-1 waste site boundary. Substation locations #6 and #7 are within the 100-D-31:4 waste site boundary. Associated substation locations #5, #8, and #15 are currently clean with no visible staining. The 190-D facility was demolished in 1995. The 190-D Building would not have been demolished if any contamination or hazardous material was present in the area.

Substations Associated with 1717-D - location #13 was removed with the 1717-D Building in 1980. The 1717-D Building and its concrete foundation were broken up, buried, and the site filled to blend in with the adjacent area. A review of historical and recent photographs shows no evidence of contaminated soil.

Substations Associated with 1720-D - location #14 was removed when the 1720-D Building was demolished in 1966.

Substations Associated with 105-DR - location #16 is currently clean with no visible staining. The main transformer was property of the Hanford Utility Group, which handled its disposal.

Substations Associated with 190-DR - locations #17a, #17b, #18a, and #18b are located within the boundary of the 100-D-28:1 waste site.

Process Description: The Midway Station fed 230 kV power to the 31,250 kV transformers located in the 151-D switchyard. From these transformers, power was transmitted via overhead and underground cables to secondary and distribution substations located throughout the 100-D Area. The substations had transformers that reduced the voltage to a value suitable for the local distribution system or facility. The transformers contained oil that cooled and insulated the windings. Polychlorinated biphenyls were once widely used in transformer oil due to their heat resistant properties. The transformers were filled with oil using hoses from oil trucks.

Closure Info: Interim (1/17/2013): A site-specific sample design for the 100-D-98:2 subsite was developed using information provided from the OSE process, site walkdowns, and historical documentation.

The concrete transformer pad at location #12 still remains. Because of the proximity from the location #12 transformer pad to the 183-D Building was proposed that this pad be removed during demolition of the 183-D Building.

All the other concrete transformer pads and contaminated soils have been removed and no evidence of stained soil was reported. Eleven of the 22 substation locations (#3, #4, #6, #7, #9a, #9b, #11, #17a, #17b, #18a, and #18b) are within other waste site boundaries. These substation locations were either part of the associated waste site remediation during cleanup activities or beneath a staging pile area. Of the remaining 10 substation locations (#1, #2, #5, #8, #10, #13, #14, #15, #16, and #19), five were chosen for test pits. The five chosen substation locations had the least amount of historical documentation and the oldest transformers associated with them. These five substation locations include #1, #2, #5, #13, and #14.

One test pit was dug at each of the chosen locations to a depth of 10 feet.

The SubSite is Part Of:

Code: 100-D-98
Names: 100-D-98; 152D Substations

Code: 100-D-98:3 **Classification:** Accepted
Names: 100-D-98:3; 153-D-5 Electrical Distribution Substation **Reclassification:** Interim Closed Out (4/16/2014)
Type: Electrical Substation **Start Date:**
Status: Inactive **End Date:**

Description: The subsite has been remediated and reclassified to Interim Closed Out. It was concrete slab of the former 153-D-5 electrical transformer. The slab was identified as a stewardship feature during the 100-D Area Orphan Site Evaluation (OSR-2006-0001).

Location: The 153-D-5 Substation was located adjacent to the north side of the 183-D building, approximately 515 meters (1695 ft) west of the 105-D Reactor Building. The coordinates for the substation were N151625.10 E573254.7.

Closure Info: Interim (4/16/2014): The 100-D-98:3 slab was located adjacent to the 183-D building. During the demolition of the 183-D Building in 2013, the 100-D-98:3 subsite concrete slab and underlying soil were excavated to a depth of 1.5 meters (5 ft) below ground surface. The material was disposed at the Environmental Restoration Disposal Facility. No soil staining was observed on the surface or during the removal of the concrete slab and underlying soil. Historical and visual documentation found no sign of stained soil within or around the substations. Confirmatory samples from the 183-D demolition were undetected or detected below Remedial Action Goals.

The area was excavated to a depth greater than the concrete slab. No soil staining was identified before or during the excavation.

The selected action involved (1) evaluating the site using available process information, (2) removing the concrete slab and underlying soil, and (3) proposing the site for reclassification to Interim Closed Out.

The SubSite is Part Of:

Code: 100-D-98
Names: 100-D-98; 152D Substations

Code: 100-D-99 **Classification:** Accepted
Names: 100-D-99; Two Suspect Features Identified by Ground Penetrating Radar **Reclassification:** Interim Closed Out (4/2/2015)
Type: Septic Tank **Start Date:**
Status: Inactive **End Date:**

Description: The site has been remediated and Interim Closed Out. It consisted of two anomalies found in April 2006 during Ground Penetrating Radar surveys being done between the demolished 1716-D Garage and the former 1719-D First aid Station. A potential septic system was identified.

Location: This site is located inside 100 D Area, between the demolished 1716-D Maintenance Garage and the 1719-D First Aid Station.

Related Sites/ Structures: The septic system supported the 1716-D Maintenance Garage and the 1719-D First Aid Station.

Process Description: During construction of the 100-D Hanford Engineer Works, temporary sewer lines and septic tanks were installed for the disposal of non-radioactive liquid sanitary sewage waste. The 1716-D Garage was used for vehicle maintenance and included an exterior gas pump. A below-grade gasoline storage tank was located on the east side of 1716-D, near the gas pump. No septic system was identified on any Hanford drawings between the 1716-D and 1719-D Buildings

Waste Type: Sanitary Sewage

Waste Description: Suspected non-radioactive liquid sanitary sewage waste.

Closure Info: Interim (4/2/2105): Remediation of the 100-D-99 waste site was performed on May 12, 2014, and excavated materials were staged at a staging pile area (SPA). Approximately 383 bank cubic meters (500 bank cubic yards) of excavated materials were staged. On June 25 and June 30, 2014, this material was taken from the SPA and disposed at the Environmental Restoration Disposal Facility. The maximum depth of the waste site excavation was approximately 1.5 meters (5 ft) below ground surface. Excavated materials consisted of soil and concrete debris. No anomalies or staining were encountered.

Code: 100-D-101

Classification: Accepted

Names: 100-D-101; 108-D Acid Pit and Sump; 108-D Car Spot; 108-D Sodium Silicate Sump; 108-D Storage Tanks; Miscellaneous Structures

Reclassification: Interim No Action (6/11/2013)

Type: Sump

Start Date:

Status: Inactive

End Date:

Description: The site has been evaluated and determined to require No Action. It consisted of two sulfuric acid storage tanks, two sodium silicate storage tanks, an acid neutralization pit and sump, a sodium silicate sump, two sets of pumps, and a railroad tank car spot. All of the components were located west of the 108-D Building.

Location: The site was located west of the 108-D building.

Related Sites/Structures: Waste sites in proximity to the 100-D-101 waste site include the 100-D-73, 100-D-76, 100-D-31:3, and 100-D-56:1 waste sites. The 100-D-73 waste site is the 108-D Building which housed the Sodium Dichromate System. The 100-D-76, former 116-D-3 waste site is a crib associated with the 108-D Building. The remedial excavation for these two waste sites is on the south and east sides of the 100-D-101 site. The 100-D-31:3, 105-D sewer pipelines subsite is a sewer pipeline that serviced the 105-D Building. The 100-D-56:1, north portion of 100-D-56 subsite consists of pipelines that conveyed water treatment chemical solutions from the 108-D Building to the 185-D Building. The 100-D-31:3 and 100-D-56:1 remedial excavations border the 100-D-101 waste site on the west.

Process Description: Two elevated sulfuric acid storage tanks were located in the site footprint. Each measured 2.7 by 11.0 meters (9 by 36 ft) and was oriented horizontally, at a height of approximately 5 m off the ground (HAN-10970, HW-75014). A set of wooden stairs allowed workers to reach the top of the tanks (HW-74549). To fill the tanks, two self-priming unloading pumps were situated nearby in a protective shed. The capacity of each pump was 50 gpm and they were run by 440 V electric motors. These storage tanks were removed sometime prior to 1952. The two sulfuric acid tanks were located west of the 108-D building at (E573738.62886, N151772.25873) and (E573738.70631, N151768.65750). The separation between the two tanks was 0.9 meter (3 ft). The pumps for sulfuric acid were located at (E573744.09046, N151775.85017), off the northeast corner of the tanks.

The two chemicals stored near 108-D were sulfuric acid and sodium silicate. Each chemical had

its own set of two large storage tanks. Additionally, each chemical had a set of two pumps for unloading solution out of railroad tank cars at the car spot. An acid neutralization pit/sump was located underneath the acid storage tanks, while another sump was located near the sodium silicate tanks. A car spot and railroad line passed through the site for delivering the solutions.

The sulfuric acid (68-70%), brought in by railroad tank cars, was delivered to the storage tanks. From the storage tanks, a gravity-flow line supplied the 105-D building with acid for controlling the pH of process water. In addition, equipment was set up in the 108-D building for diluting the sulfuric acid. Pumps with suction piping were used to transport acid from the tanks into the 108-D building. Historic photographs indicate that the sulfuric acid tanks were removed before 1952.

The 108-D Acid Neutralization Pit and Sump was located underground beneath the sulfuric acid storage tanks on the west side of the 108-D building. The pit was covered with a removable 1.4 meters (4 ft, 8 in) wooden plank. A 10.1 cm (4 in) overflow pipe was attached to the south end of the pit, which connected to the water treatment process sewer. The northern portion of the pit was separated from the rest by a brick barrier and was used as a sump. Two 5.1 cm (2 in) inlet pipes inside an underground wooden box structure brought acidic solution into the sump. In addition, there were two 10.1 cm (4 in) drain pipes extending from the west ends of the acid tanks, with another 10.1 cm (4 in) drain line originating from the pump shed. Another overflow drain line connected from the center of the tanks. All of these overflow lines connected to the sump portion of the pit. All piping was above ground, except the 5.1 cm (2 in) inlet lines in the wooden box and the sewer drain line. The 108-D Acid Pit was located to the west of the 108-D building, directly underneath the elevated sulfuric acid tanks, at coordinates (E573736.72, N151770.62). It is also in the sidewall of 100-D-31.

A 108-D Acid Neutralization Pit and Sump was located underground beneath the sulfuric acid storage tanks on the west side of the 108-D Building. The pit was covered with a removable 1.4-m (4.6-ft) wooden plank. The Acid Pit consisted of two layers of acid-proof brick. The bottom layer was laid in asphalt, while the top layer was laid in Tegal Vitrabond. Joints were sealed with Vitrabond. The acid pit (excluding the sump portion) had an additional third layer, which was coated with 10.1 cm (4 in) of asphalt (HW-74807). The acid pit was used to safely neutralize acidic solutions. In particular, piping was in place to transfer acid that overflowed or leaked out of the tanks and pumps during the unloading process. Also, by using valves located both near the pumps and near the acid pit, acid could be released directly into the pit. According to drawing HW-74807, only sulfuric acid was supposed to be used in the acid pit.

Two elevated sodium silicate tanks were located just north of the sulfuric acid tanks. Each of these measured 6.1 m (20 ft) in diameter and 4.6 m (15 ft) in height, and had an internal steam heating coil system (HAN-10970, SPEC HW-2036). The tanks were removed prior to 1970 and most of the soil underneath them falls within the cleanup footprint for 100-D-56. According to HAN-10970, the pumps used for unloading sodium silicate from the car spot were identical to those used for the sulfuric acid (50 gpm flow rate). However, SPEC-HW-2036 states instead that there were two 100 gpm pumps. These pumps were also used to transfer sodium silicate into the 108-D building and were housed in a wooden shed with a radiator (SPEC-HW-2036, HW-74550). The tanks were located to the west of the 108-D building and north of the sulfuric acid tanks at (E573737.28065, N151780.51975) and (E573737.28309, N151787.92000). The two tanks were separated by 1.5 meters (5 ft). The sodium silicate pumps were located at (E573744.18968, N151787.46223), east of the northernmost storage tank. Both tanks are partially located in the sidewall of 100-D-56.

Sodium silicate was received in railroad tank cars and moved to the two storage tanks by using the nearby pumps. Those same pumps were then used to transfer the silicate into the 108-D building, where it was diluted with process water. This weaker solution was later transported to 185-D for process water treatment.

Sodium silicate was received in railroad tank cars and moved to the two storage tanks by using the nearby pumps. Those same pumps were then used to transfer the silicate into the 108-D Building, where it was diluted with process water. This weaker solution was later transported to the 185-D Building for process water treatment.

The 108-D Sodium Silicate Sump was built as part of the Alum-Activated Silica Water Treatment Facilities project in 1954. The purpose of the sump was to address the issue of potential spills during the unloading and transfer of sodium silicate solution. However, there is no indication of any drains extending to the sump from the sodium silicate tanks or pumps, so it is not clear how the sump addressed the issue. The sump was located just north of the sodium silicate pumps and drained to the 100-D-31:3 process sewer via a 15 cm (6-in.) vitrified clay pipe. The sump was covered by a steel grating.

The 108-D Sodium Silicate Sump was just north of the sodium silicate pumps, at (E573743.77016, N151790.73936) between the sulfuric acid tanks and the sodium silicate tanks, and was used for unloading liquids. It included a platform for unloading chemicals, stairs to reach the top of railroad tank cars, flexible hoses to unload liquids, and a safety shower (HW-75250).

The 108-D Car Spot was used to unload liquid chemicals for the 108-D building and the nearby storage tanks. Using flexible connecting hoses, sodium silicate solution and sulfuric acid were pumped out of railcars and into the storage tanks. A second car spot, 100-D-73, was used to unload solids and move them into the 108-D building. Among the chemicals transported this way was sodium dichromate.

Waste Type: Soil

Waste Description: Site contaminants of potential concern include mercury, lead, sodium silicate, and sodium dichromate. It is possible that contaminants leaked into the soil during the lifetime of the sulfuric acid storage tanks and the associated components, particularly prior to 1954 when there was no sump. Resulting in potentially high concentrations of heavy metals such as mercury and lead. In addition, during the process of filling the tanks or pumping it into the 108-D building, acid may have spilled into the soil elsewhere in the site footprint. Near the southern portion of the site boundary, sodium dichromate may have been released as it was being unloaded in the nearby car spot, which is included in the adjacent waste site 100-D-73.

Closure Info: Interim (6/11/2013): Confirmatory sampling was performed in three test pits and two test trenches on May 31, June 4 and 5, 2012, and February 27, 2013.

Test Pit 1 (TP1) was excavated at the location of the neutralization pit. All of the piping connecting to the neutralization pit and sump, including the acid neutralization pit was removed with the 100-D-31:3 excavation. The pit structure had been removed during remediation of the adjacent 100-D-31:3 waste site, leaving the TP1 sample location on the side slope of the open excavation. In order to reach the target sample depth of 3 meters (10 ft) below the original grade, the side slope was excavated an additional 0.6 to 0.9 meters (2 to 3 ft) below the existing grade. Wood, brick, and concrete debris were present in the side slope. Yellow-brown stains were seen at sulfuric acid unloading and processing facilities and are characteristic of stains seen at sulfuric acid unloading and processing facilities elsewhere at the Hanford Site. The amount of staining suggested significant anomalous material was intermixed with the soil. The excavation was backfilled.

Test Pit 2 (TP2) was excavated at the suspected location of a silica pump. No structure was found. The excavation proceeded through clean fill material to an approximate depth of 2.4 meters (8 ft), where a few rotten boards were discovered. Below this level was black, gravely sand that was considered to be undisturbed native soil. A sample (J1PPM8) was collected of

this soil. The excavation was backfilled.

Test Pit 3 (TP3) was excavated to a depth of 0.9 meters (3 ft) below ground surface (bgs). No debris was found. A small amount of stained soil was observed. Since the staining was minimal and consistent with that sampled at TP1, no additional samples of the anomalous material were collected. A sample (J1PPM7) was collected of the soil from the bottom of the excavation and the hole was backfilled.

Test Trench 1 (TT1) was excavated in a former concrete pipe trench. The bottom and side walls of the trench were found largely intact. There was no piping or other debris in the soil material that filled the trench. A sample (J1PPN6) was collected of the trench contents (fill material) near the west end. The excavation proceeded to the east inside the trench. Towards the center of the trench, the bottom was up to 1.2 meters (4 ft) bgs. The lower approximately 0.3 m (1 ft) of material in the trench was discolored from the fill material above it. The deeper soil appeared darker, possibly due to a higher organic content. White crystalline material was also mixed with this anomalously colored soil. Samples (J1PPR1 and J1PPT1) were collected of this anomalously colored soil. The excavation proceeded to the eastern end of the trench. A sample (J1PPN7) was collected of the soil fill near the bottom of the trench at the east end. The trench was then backfilled. The confirmatory work instruction called for excavating under the concrete trench and collecting three discrete samples from that location. However, the backhoe was unable to break through the bottom of the concrete trench. The physical constraints of the site did not allow for use of larger equipment. Therefore, a single pothole was excavated outside the trench to access the underlying soil. The pothole was excavated near the center of the north side of the trench to a depth of 2.1 meters (7 ft) bgs. The material appeared to be fill with a small amount of concrete debris and short conduit sections. A sample (J1PPN8) was collected of the soil from the bottom of the pothole. The pothole was backfilled.

Following a review of 100-D-101 waste site physical and procedural constraints and in consultation with Washington State Department of Ecology, it was determined that the two soil samples beneath the concrete trench could be obtained via access through adjacent excavations (100-D-31:3 to the west and 100-D-73/100-D-76 to the east). The samples could be collected by hand means, with shovel excavations from the east and west ends of the trench.

Sampling of the 100-D-101 waste site was resumed on February 27, 2013, when shovel excavations were made to access soil underlying the concrete trench that is located between the former sodium silicate tanks. Two soil samples were collected from the west (J1RFV0) and east (J1RFV1) end of the concrete trench, approximately 2.7 meters (9 ft) bgs, and 1.5-2 ft below the concrete trench.

Test Trench 2 (TT2) was excavated inside an abandoned railroad bed. The railroad ties were still in place at the surface when the excavation was started. These ties were removed and stacked near the excavation. The excavation then proceeded to an approximate depth of 0.3 meter (1 ft). A sample (J1PPP1) was collected from the bottom of the trench at the south end. A sample (J1PPP2) and duplicate (J1PPP3) were collected from the bottom near the north end. The site was left as a shallow excavation, roped, and posted as an exclusion zone pending analytical results.

Code: 100-D-102	Classification: Accepted
Names: 100-D-102; Suspect Effluent Leak Adjacent to 107-DR Basin	Reclassification: Interim No Action (9/26/2012)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The waste site was evaluated and determined to require No Action. The 100-D-102 waste site was identified as a dark area compared to the surrounding terrain in a 1962 aerial photograph. The dark area was suspected to be effluent that leaked to the ground outside of the 107-DR Basin. The feature on the photograph was an irregular shaped, dark feature visible in the aerial photograph (10974-PHOTO) adjacent to 116-DR-9. The surface of the site has been re-graded many times and is no longer discernible from the surrounding area.

Location: The site is located immediately to the southwest corner of 107-DR retention basin.

Release Description: The first known inventory of radioactive releases to the ground in the 100-D/DR area is contained in the January 29, 1953 report titled "Unconfined Underground Radioactive Waste and Contamination" (HW-27337) by H.G. Ruppert. The report identifies five locations near the retention basins. These sites are later assigned the following waste site codes: 100-D-29, 116-DR-1&2, UPR-100-D-2, UPR-100-D-3 and UPR-100-D-4. A memo was issued with corrections to this report on July 16, 1953 (HW-28737). The corrections to the report did not affect any of the releases near the 107-D/DR retention basins.

Another inventory was made in October 1954 (HW-33305). The report listed those facilities that used for disposal of radioactive liquid wastes. It did not contain unplanned radioactive releases (as was done previously in HW-27337). The report listed just two locations (100-D-29 and 116-DR-1&2) near the 107-D/DR retention basins.

The inventory was updated again in May 1956 (HW-43121). It contained six additional disposal facilities from that reported in HW-33305. The new facilities were later assigned the following waste site codes: 100-D-4, 100-D-18, 100-D-19, 100-D-20, 100-D-21 and 100-D-22.

A comprehensive listing of underground radioactive contamination including planned and unplanned releases was issued again in November 1956 (HW-46715). It contained all of the waste sites mentioned previously but did not add any new ones in the vicinity of the 107-D/DR retention basins.

Hanford drawing (H-1-4046) which shows the underground radioactive waste sites in the 100-D/DR Area was revised in June 1964. It shows many (but not all) of the waste sites previously discussed. The drawing depicts two effluent leaks south of 107-DR. One of these is consistent with the location of 100-D-29. The shape and location was used for the remediation design of the 100-D-29 waste site. The other leak identified on the drawing did not correspond to any of the previously reported releases. This location was subsequently assigned to the UPR-100-D-5 waste site.

A report was issued in November 1967, following the deactivation of the 105-D/DR reactors (DUN-3063). This report mentioned the two retention basins and the sludge buried from 107-DR (100-D-22). It did not reveal any new information related to releases near the 107-D/DR retention basins.

Related Sites/ Structures: The waste sites located near and associated with the retention basins include the following WIDS site codes:

100-D-4, Sludge Trench #5, 100-D-18, Sludge Trench #4, 100-D-19, Sludge Trench #6, 100-D-20, Sludge Trench #3, 100-D-21, Sludge Trench #2, 100-D-22, Sludge Trench #1, 100-D-29, Effluent Leak #2, 100-D-48, 100-D Reactor Cooling Water Effluent Underground Pipelines, 100-D-49, 100-D-63, 100-DR Reactor Cooling Water Effluent Underground Pipelines, 116-D-7, 107-D Retention Basin, 116-DR-1&2, 107-DR Liquid Waste Disposal Trench #1, 116-DR-9, 107-DR Retention Basin, UPR-100-D-2, Effluent Line Leak #1, UPR-100-D-3, Effluent Line Leak #3, UPR-100-D-4, 107-D Basin Leaks, UPR-100-D-5, Effluent Line Leak #4 and multiple pipeline sites.

Process Description: The 107-DR retention basin (116-DR-9) received cooling water effluent from the 105-DR Reactor, and reactor floor wastes from the 1608-DR Waste Water Pump House. The cooling water was held in the basin for as long as operating time would permit, allowing the water to thermally cool and for short-lived radionuclides to decay. The water was then discharged to the center of the river via the outfall structures and associated pipelines. The basin experienced several unplanned liquid releases during its lifetime.

The irregular shaped feature visible in the 1962 aerial photograph (10974-PHOTO) is suspected to be an effluent leak. There are several planned and unplanned releases of cooling water effluent reported near the 107-D and 107-DR retention basins. A number of reports published during the operation of the 100-D/DR Area detail the releases. Previously identified releases have been documented as 100-D-4, Sludge Trench #5, 100-D-18, Sludge Trench #4, 100-D-19, Sludge Trench #6, 100-D-20, Sludge Trench #3, 100-D-21, Sludge Trench #2, 100-D-22, Sludge Trench #1, 100-D-29, Effluent Leak #2, 100-D-48, 100-D Reactor Cooling Water Effluent Underground Pipelines, 100-D-49, 100-DR Reactor Cooling Water Effluent Underground Pipelines, 116-D-7, 107-D Retention Basin, 116-DR-1&2, 107-DR Liquid Waste Disposal Trench #1, 116-DR-9, 107-DR Retention Basin, UPR-100-D-2, Effluent Line Leak #1, UPR-100-D-3, Effluent Line Leak #3, UPR-100-D-4, 107-D Basin Leaks, UPR-100-D-5, Effluent Line Leak #4 waste sites. The footprint of the waste site 100-D-102 falls outside the footprints of all the other waste sites previously identified. The original drawings which were used to define the boundary of the waste sites were imprecise. It is possible that the aerial photograph shows the actual footprint of a waste site that was previously identified and located using the less precise historical drawings.

Waste Type: Process Effluent

Waste Description: Contaminants of potential concern (COPCs) include: Co-60, Cs-134, Cs-137, Eu-152, Eu-154, Eu-155, H-3, Pu-238, Pu-239, Pu-241, Sr-90, U-238, Am-241, Sr-90, arsenic, chromium, lead, and zinc and should be the same as those for the 107-D/DR Retention Basins. The waste is contaminated soil from an unplanned release of process effluent.

Closure Info: Interim (9/26/2012): Samples were collected from five test pits on May 30 and 31, 2012, and June 5, 2012. Test pits 1 and 2 were 4.6 meters (15 feet) deep. Test Pit 3 was 1.2 meters (4 feet) deep. Test Pit 4 was 1.8 meters (6 feet) deep. Test Pit 5 was 2 meters (7 feet) deep. Samples were collected from the backhoe bucket of material brought up from the bottom of the excavations. No elevated radiological readings were detected within the pits using field instruments. The excavations were backfilled.

Code: 100-D-103	Classification: Accepted
Names: 100-D-103; Suspected Trench and French Drain from 116-D-8 Cask Pad	Reclassification: Interim No Action (7/18/2013)
Type: French Drain	Start Date:
Status: Inactive	End Date:

Description: The waste site was evaluated and determined to require No Action. The waste site was a suspect feature resembling a trench found on a December 1949 aerial photograph. It appeared to extend south from the 116-D-8 Cask Pad.

Location: The suspect feature is located at approximately E573698/N151250.

Closure Info: Interim (7/18/2013): The December 1993 geophysical survey information was not helpful in identifying the location of the french drain, possibly due to the probable vitrified clay material used for construction of the french drain or due to the fact that french drain may have been removed from the identified location during the decommissioning process of the temporary

airlock building or construction of the 100-D-50:2 pipeline tunnels.

Confirmatory samples of the 100-D-103 waste site were collected on February 22, 2013. A test pit was excavated at the suspected french drain location to investigate the presence of a french drain and to collect appropriate samples. The excavation extended to 3 meters (10 ft) below ground surface (bgs). No french drain or drain components were found. No pipelines or other debris was excavated at this test pit location. The excavation was backfilled with the excavated materials from the test pit.

A test trench was excavated at the location across the suspected trench location. The sloughing of the soils and unstable walls precluded the excavation from extending deeper than 3.7 to 4 meters (12 to 13 ft) bgs. No pipelines, debris, or other anomalies were found within the test trench excavation. Due to the length of the trench, three samples were collected across the test trench floor, at 3.7 to 4 meters (12 to 13 ft) bgs. The excavation was backfilled with the excavated materials from the test trench.

No radioactivity was detected. Confirmatory sample results were evaluated and supported the No Action decision.

Code:	100-D-104	Classification:	Accepted
Names:	100-D-104; Unplanned Release near 185-D Sodium Dichromate Storage Tank and Acid Neutralization French Drain	Reclassification	Interim Closed Out (6/3/2015)
Type:	Unplanned Release	Start Date:	
Status:	Inactive	End Date:	
Description:	The waste site has been remediated and Interim Closed Out. It consisted of stained soil near the former sodium dichromate storage tank and acid french drain, outside of building 185-D. The stain encompassed an area of 910 square meters (9,792 square feet). The site geometry was established by drawing an arbitrary polygon around an existing excavation with a depth of 6.0 meters (19.6 ft) that contained stained soil and elevated concentrations of hexavalent chromium.		
Location:	The centroid of the stain was located at approximately E573586.7 N151521.7.		
Related Sites/ Structures:	The remediation was associated with 100-D-30 and 100-D-71.		
Closure Info:	Interim (6/3/2015): Initial remediation of the 100-D-30 waste site was performed from June 2006 through May 2007. Approximately 7,000 cubic meters (9,160 cubic yards) of stained soil, stained concrete, and construction debris were excavated, stockpiled next to the trench, and later disposed to the Environmental Restoration Disposal Facility (ERDF). Waste characterization and in-process samples were collected, as necessary, to support waste designation and to assist in guiding the excavation. Stained concrete observed at the site was sampled (J12XP5) to support waste designation. The depth of this excavation was approximately 3.5 meters (12 ft) below ground surface. During the 100-D-30 waste site excavation, pieces of vitrified clay pipe were encountered at the southwestern corner of the 100-D-30 site.		

On December 20, 2007, additional soil removal was performed in this southwestern area of the 100-D-30 waste site to a depth of approximately 3 meters (10 ft) below grade. Yellow staining was observed after this further excavation. Four judgmental in-process soil samples were collected in this area (J163Y2, J163Y3, J163Y4, and J163Y5) with one sample (J163Y2) having 20.6 mg/kg of hexavalent chromium. On March 4, 2008, additional excavation was

performed to open up the area for further evaluation. As the excavation progressed deeper, the soil became more stained. Excavation continued on March 5, 2008, to a depth of 6 meters (20 ft). The excavation was halted at this depth because any deeper would require an engineering design. In the center of the excavation, an area approximately 3 sq. meters (30 sq. ft) was observed with yellow and brown staining.

From January through February 2009, and June 2009, five investigation boreholes were drilled at the 100-D-30 waste site to support evaluation of the vertical distribution of chromium contamination in the vadose zone below the waste site. Soil samples were collected at discrete depth intervals and analyzed for chromium (total) and hexavalent chromium. Chromium contamination was observed at depth in the vadose zone directly below the french drain location (C6450), indicating probable transport of contamination associated with releases from the french drain and the outdoor sodium dichromate storage tank. Based on historical information, field observations, and sample results, it appeared that the residual contamination identified in the southwestern corner of the 100-D-30 waste site was associated with the acid neutralization french drain, sulfuric acid tank, and sodium dichromate tank that were located outside of the 190-D Complex. Therefore, it was decided to identify this location as a discovery site, 100-D-104, for further remediation because it was not associated with the 185-D Building sodium dichromate trench that was the source of the chromium contamination identified as the 100-D-30 waste site. Based on the concentrations of hexavalent chromium found at depth in the boreholes, a decision was made to perform additional remediation of the 100-D-30 waste site and to combine this remediation with the 100-D-104 waste site remediation.

Additional remediation was performed from October 2011 through March 2012, to a depth of approximately 15.2 meters (50 ft) below surface grade and was identified as the Tier II excavation. A Tier III excavation design was developed for continuing the remediation of these sites to an approximate depth of 24 meters (78.7 ft) below surface grade, with the bottom of the excavations at an elevation of approximately 119 meters (390.4 ft) above mean sea level, the estimated elevation of groundwater. The Tier III excavation began in February 2013 and excavation to groundwater was completed in March 2014. Due to the depth and size of these excavations, considerable layback and overburden soil was removed and stockpiled for use as clean backfill or was placed into previously remediated waste sites (120-D-1, 100-D-73, and 100-D-76). Overburden/layback material was also placed in the south portion of the decommissioned 183-D clearwell.

An agreement with Ecology allowed use of clean concrete and steel debris encountered during remediation to be used as backfill for a portion of the 100-D-30/100-D-104 waste sites. The agreement specified that the excavation would be backfilled with soil approximately 3 meters (10 ft) above groundwater. Clean concrete and steel debris could be placed over the soil to an elevation that would be no closer than 6.1 meter (20 ft) from the backfilled surface grade for the waste sites.

In accordance with this evaluation, the verification sampling results support a reclassification of the 100-D-30 and 100-D-104 waste sites to Interim Closed Out. Contamination above direct exposure levels was not observed in the shallow zone soils and is concluded to not exist in deep zone soils. Institutional controls to prevent uncontrolled drilling or excavation into the deep zone of the sites are not required.

Code: 116-D-1A	Classification: Accepted
Names: 116-D-1A; 105-D Storage Basin Trench #1	Reclassification: Interim Closed Out (3/5/2001)
Type: Trench	Start Date: 1/1/1947
Status: Inactive	End Date: 1/1/1952

Description:	The site has been remediated and Interim Closed Out.
Location:	The 116-D-1A/116-D-1B site is located within the 100-DR-1 Operable Unit in the 100 Areas of the Hanford Site in southeastern Washington State. The 116-D-1A site is located approximately 30 meters (100 feet) east of the 105-D Reactor Building.
Process Description:	This trench was 40 meters (130 feet) by 3 meters (10 feet) by 1.8 meters (6 feet) deep. It was used from 1947 to 1952 and received contaminated water and sludge from the 118-D-6 Fuel Storage Basin. The 116-D-1B Trench was constructed in 1953 to replace the 116-D-1A Trench. This trench was 30 meters (100 feet) by 3 meters (10 feet) by 5 meters (15 feet) deep and received contaminated water and sludge from the 118-D-6 Fuel Storage Basin from 1953 to 1967. The 100-D-46 site is a burial ground that received radioactive and nonradioactive solid wastes and construction debris generated from various reactor modifications from the 105-D Reactor building after 1967. The 100-D-46 site was co-located with the 116-D-1A and 116-D-1B sites and was remediated along with these sites and their associated plumes.
Waste Type:	Process Effluent
Waste Description:	The site received contaminated water and sludge from 118-D-6 Fuel Storage Basin. Records also show approximately 1,000 kilograms (1.1 tons) of sodium dichromate was disposed in this trench.
Closure Info:	Interim: The 116-D-1A and 116-D-1B Storage Basin Trenches received contaminated water and sludge from the 118-D-6 Fuel Storage Basin. The 100-D-46 Burial Ground received solid waste and construction debris from modifications made to 105-D after 1967 and was co-located with the trenches. The three waste sites were remediated together, with the documentation presented in the same Cleanup Verification Package (CVP-2000-00010). The document referred to the collective three waste sites as the 116-D-1A/116-D-1B site.

The selected remedial action for the 116-D-1A/116-D-1B sites included (1) excavating the site to the extent required to meet specified soil cleanup levels, (2) disposing of contaminated excavation materials at the Environmental Restoration Disposal Facility at the 200 Areas of the Hanford Site, and (3) backfilling the site with clean soil to average adjacent grade elevation. Excavation was driven by remedial action objectives for direct exposure, protection of groundwater, and protection of the Columbia River. For the respective points of compliance, RAGs were established to identify radionuclide and nonradionuclide contaminants of concern (COCs) and contaminants of potential concern (COPCs). Waste site COCs and COPCs identified through process knowledge were listed in the 100 Area Remedial Action Sampling and Analysis Plan (DOE/RL-96-22).

Remedial action at the 116-D-1A/116-D-1B site began on October 21, 1999. Excavation of the site involved removing the overburden materials, the contaminated structure, and underlying contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Materials that were found to be contaminated were disposed of at ERDF. On July 11, 2000, the excavation reached the design limit at El. 138.4 m (454 ft).

At the completion of the remedial action, the total excavation was approximately 2,648 square meters (28,470 square feet) in area with a maximum depth of approximately 4.6 meters (15 feet). Approximately 10,987 metric tons (12,111 tons) of material from the site were disposed of at the Environmental Restoration Disposal Facility (ERDF).

Code:	116-D-1B	Classification:	Accepted
Names:	116-D-1B; 105-D Storage Basin Trench #2	Reclassification:	Interim Closed Out (3/5/2001)
Type:	Trench	Start Date:	1/1/1953

Status: Inactive **End Date:** 1/1/1967

Description: The site has been remediated and Interim Closed Out.

Location: The trench was located approximately 30 meters (100 feet) northeast of the 105-D Reactor.

Process Description: The 116-D-1B Trench was constructed in 1953 to replace the 116-D-1A Trench. This trench was 30 meters (100 feet) by 3 meters (10 feet) by 5 meters (15 feet) deep and received contaminated water and sludge from the 118-D-6 Fuel Storage Basin from 1953 to 1967.

Waste Type: Process Effluent

Waste Description: The site received contaminated water and sludge from 105-D Fuel Storage Basin and liquid waste from the decontamination of fuel spacers and reactor hardware. Records show approximately 700 kilograms (0.8 tons) of sodium dichromate, 2000 kilograms (2.2 tons) of sodium oxalate and 2000 kilograms (2.2 tons) of sodium sulfate were also disposed in this trench.

Closure Info: Interim: The 116-D-1A and 116-D-1B Storage Basin Trenches received contaminated water and sludge from the 118-D-6 Fuel Storage Basin. The 100-D-46 Burial Ground received solid waste and construction debris from modifications made to 105-D after 1967 and was co-located with the trenches. The three waste sites were remediated together, with the documentation presented in the same Cleanup Verification Package (CVP-2000-00010). The document referred to the collective three waste sites as the 116-D-1A/116-D-1B site.

The selected remedial action for the 116-D-1A/116-D-1B sites included (1) excavating the site to the extent required to meet specified soil cleanup levels, (2) disposing of contaminated excavation materials at the Environmental Restoration Disposal Facility at the 200 Areas of the Hanford Site, and (3) backfilling the site with clean soil to average adjacent grade elevation. Excavation was driven by remedial action objectives for direct exposure, protection of groundwater, and protection of the Columbia River. For the respective points of compliance, RAGs were established to identify radionuclide and nonradionuclide contaminants of concern (COCs) and contaminants of potential concern (COPCs). Waste site COCs and COPCs identified through process knowledge were listed in the 100 Area Remedial Action Sampling and Analysis Plan (DOE/RL-96-22).

Remedial action at the 116-D-1A/116-D-1B site began on October 21, 1999. Excavation of the site involved removing the overburden materials, the contaminated structure, and underlying contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Materials that were found to be contaminated were disposed of at ERDF. On July 11, 2000, the excavation reached the design limit at El. 138.4 m (454 ft).

At the completion of the remedial action, the total excavation was approximately 2,648 square meters (28,470 square feet) in area with a maximum depth of approximately 4.6 meters (15 feet). Approximately 10,987 metric tons (12,111 tons) of material from the site were disposed of at the Environmental Restoration Disposal Facility (ERDF).

Code: 116-D-2	Classification: Accepted
Names: 116-D-2; 116-D-2A; 105-D Pluto Crib	Reclassification: Interim Closed Out (10/23/2000)
Type: Crib	Start Date: 1/1/1950
Status: Inactive	End Date: 1/1/1956

Description: This site has been remediated and Interim Closed Out. The crib was a 3 meter (10 feet) by 3

meter (10 feet) crib, 3 meters (10 feet) deep. The unit had been shored with railroad ties and filled with sand. The upper portion of the structure was above grade with a hatch opening that allowed a rubber hose to be inserted and discharge liquid to the crib.

Location: The 116-D-2 site was located approximately 920 meters (3,018 feet) from the Columbia River and about 30.5 meters (100 feet) east of the 115-D/DR Gas Treatment Facility (132-D-1).

Process Description: The 116-D-2 site was used to isolate coolant flow from process tubes containing ruptured fuel elements until the ruptured fuel could be discharged. A pluto valve was installed on the downstream end of the process tube, connecting the tube to a rubber hose. The coolant then flowed through the rubber hose into the crib. An estimated 4,000 liters (1,000 gallons) of liquid wastes were disposed at the 116-D-2 site, and the known hazardous chemical inventory included an estimated 0.004 kilograms (0.009 pounds) of sodium dichromate.

Waste Type: Process Effluent

Waste Description: The site received effluent water from isolated tubes containing ruptured fuel elements.

Closure Info: Interim (10/23/2000): Remedial action at the 116-D-2 site began on November 1, 1999. Excavation of the site involved removing the overburden materials, the contaminated structure, and underlying contaminated soil which were disposed at ERDF. On November 2, 1999, the excavation reached the design limit at El. 137.9 meters (452.4 feet).

At the completion of remedial action, the excavation was approximately 217.9 square meters (2,331.5 square feet) in area with a maximum depth of approximately 4.6 meters (15 feet). Approximately 623.2 metric tons (687 tons) of material from the site were disposed of at ERDF. Cleanup verification sampling was conducted on January 3, 2000. The excavation will be backfilled in the near future with appropriate materials to the reference grade of El. 142.5 meters (467.5 feet).

Code: 116-D-3	Classification: Accepted
Names: 116-D-3; 108-D Crib #1	Reclassification: Interim No Action (1/30/2003)
Type: Crib	Start Date: 1/1/1951
Status: Inactive	End Date: 1/1/1967

Description: Based on excavations, the review of site drawings, and ground penetrating radar, it has been determined that the 116-D-3 Crib is a duplicate number for site 116-D-4. Therefore, No Action was required. Historical research in 2008 found this site to be synonymous with 100-D-76.

Location: This crib is actually a duplicate number for the 116-D-4 Crib.

Related Sites/Structures: See sitecodes 100-D-76 and 116-D-4 for additional information.

Process Description: Crib 116-D-4/116-D-3 received low-level fission product wastes in contaminated wash water from the 108-D Shipping Cask Handling Facility.

Waste Type: Process Effluent

Waste Description: The site (a duplicate number for the 116-D-4 Crib) is a crib containing contaminated soil and rock. The site received low-level fission product wastes in contaminated wash water from the 108-D Shipping Cask Handling Facility.

Closure Info: Interim: The 116-D-3 Crib is actually the same site as the 116-D-4 Crib. Remediation activities at 116-D-4 took place on October 20-21, 1999. Reference drawing H-1-3091 indicates that the

116-D-3 is co-located with 116-D-4 at coordinates N151757, E573832. The possibility of 116-D-3 being a separate site has been investigated through excavation at all historically reported locations. Initial excavation at the contract design coordinates (N151739, E573774) occurred on 10/20/99; however, the excavation showed no engineered structure or contamination (using field instruments). Excavation activities occurred on 11/4/99 at location coordinates N151757, E573768, which is also referenced as a possible location for 116-D-3. No evidence of a structure or contamination (using field instruments) was found. Excavation also occurred on 12/30/99 at coordinates N151725, E573807 and N151731, E573832. No structure or contamination (using field instruments) were found.

Reclassification form 2002-060 form amends a previous reclassification of this site. Originally the site was reclassified as "Rejected" in April 2000. Approval of form 2002-060 reclassified the site to "No Action" to align with remaining sites ROD.

Code: 116-D-4	Classification: Accepted
Names: 116-D-4; 108-D Crib #2	Reclassification: Interim Closed Out (10/23/2000)
Type: Crib	Start Date: 1/1/1951
Status: Inactive	End Date: 1/1/1967

Description: This waste site has been remediated and Interim Closed Out. The site was a 2.4 by 2.4-meter (8 by 8-foot) crib, 5 meters (16 feet) deep. This crib is often referred to as a french drain.

Location: The site is located 65.45 meters (281 feet) directly east of the demolished 108-D Shipping Cask Handling Facility. This location is the southeast corner of the 108-D Building and east of the 108-D wash pad.

Related Sites/Structures: The site is related to the 108-D Shipping Cask Handling Facility and to the maintenance shops and technical laboratory of that facility. 116-D-3 was determined to be a duplicate entry of 116-D-4.

Process Description: The site received low-level fission product wastes in contaminated wash water from the 108-D Shipping Cask Handling Facility maintenance shops and technical laboratory.

Waste Type: Process Effluent

Waste Description: The site was a crib containing contaminated soil and rock. The site received low-level fission product wastes from contaminated maintenance shops in the 108 buildings. Assuming that H-1-3091 represents the correct information, the crib received wash water from the 108-D Shipping Cask Handling Facility.

Closure Info: Interim (10/23/2000): Remedial action began on October 20, 1999. Excavation involved removing the overburden, any engineered structure and the contaminated soil. Based on field screening, excavated materials identified as potentially clean were placed in stockpiles for potential use as backfill. On October, 21, 1999, the excavation reached the design limit at El. 140.7 meters (462 feet).

At the completion of remedial action, the excavation was approximately 137.8 square meters (1,482 square feet) in area with a maximum depth of approximately 2.8 meters (9 feet). The backfill reference grade is El. 143.5 m (471 feet). Backfill will be taken from the clean stockpile and/or from other sources of clean material surveyed in accordance with the SAP and that are appropriate for use as backfill.

Code: 116-D-5	Classification: Accepted
----------------------	---------------------------------

Names: 116-D-5; 1904-D Outfall Structure **Reclassification** Interim Closed Out (8/10/2011)

Type: Outfall **Start Date:** 1/1/1944

Status: Inactive **End Date:** 1/1/1975

Description: The outfall structure has been remediated and Interim Closed Out. It had been an open, reinforced, compartmentalized concrete outfall structure. The outfall structure was demolished, caved into itself and backfilled with soil in 1998. In the spring of 2009, the engineered structure, contaminated debris and soil was removed and disposed in the ERDF facility.

Location: The site is located at the top of river bank, northwest of 116-D-7 (107-D Retention Basin).

Related Sites/ Structures: The site is associated with the 107-D Retention Basin (116-D-7), the 107-DR Retention Basin (116-DR-9), 100D Reactor Cooling Water Effluent Lines (100-D-48), the 100DR Reactor Cooling Water Effluent Lines (100-D-49), the 100D River Effluent Lines (100-D-60) and Flumes (100-D-66).

Process Description: Process sewer wastes, and reactor cooling water collected and temporarily stored in the 116-D-7 and 116-DR-9 retention basins, were pumped to the river via the 116-D-5 outfall structure and associated 100-D-60 river effluent pipelines. The reactor cooling water discharged into the upper chamber of the concrete outfall structure, flowed through a bar grillwork and fell about 6.10 meters (20 feet) to the lower chamber of the outfall structure. Then it overflowed from the lower chamber into the discharge pipe to the river. The discharge pipe to the river (100-D-60) was connected to the side wall of the lower chamber of the outfall structure. The inlet to the discharge pipe from the outfall structure was about 0.10 meters (4 inches) above the floor of the lower chamber. The Outfall Structure was open to the atmosphere which allowed rain and snow to collect in the bottom 4 inches of the lower chamber. Prior to the structure being demolished and caved into itself, the Outfall Structure was enclosed with a chain-link security fence and an aviary exclusion mesh cover.

Waste Type: Construction Debris

Waste Description: This unit received reactor coolant water from the 107-D & 107-DR Retention Basins and waste water from the 100-D Water Support Facilities including 183-D and 190-D. The contaminants of concern include C-14, Cs-137, Sr-90, U-235, -238, and Pu-239/240.

Closure Info: Interim: Remedial action at the 116-D-5 waste site was performed between February 6 and April 1, 2009. Additional remediation was conducted on March 15, 2011 to remove residual contamination identified after the initial round of verification sampling. The site was originally excavated to a depth of approximately 5 meters (16 ft) on the northwestern side of the excavation and 10 meters (33 ft) on the southeastern side of the excavation. The depth of the excavation following additional remediation is approximately 6 meters (20 ft) on the northwestern side and 11 meters (36 ft) on the southeastern side of the excavation. The engineered structure was completely removed. The entire excavation resulted in approximately 2,275 bank cubic meters (2,976 bank cubic yards) of contaminated soil and debris being removed for disposal to the Environmental Restoration Disposal Facility (ERDF). Some of the material removed from the excavation was placed in a staging pile area prior to being loaded out for disposal at ERDF.

Code: 116-D-6 **Classification:** Accepted

Names: 116-D-6; 105-D Cushion Corridor French Drain **Reclassification** Interim Closed Out (11/8/2000)

Type: French Drain **Start Date:** 1/1/1953

Status: Inactive **End Date:** 1/1/1967

Description: This site has been remediated and Interim Closed Out. The waste site was a 1-meter (3.3-foot)

diameter french drain, 1 meter (3.3 feet) deep covered by approximately 1 meter (3.3 feet) of gravel and soil.

Location: The site was located adjacent to the northeast corner of the 105-D Reactor Building, bordered on two sides by the reactor wall and foundation, and on the other two sides by the 100-D-48 cooling water effluent pipelines.

Process Description: The drain received domestic wastewater from the change room and wastewater from the mask decontamination station located in the cushion corridor during reactor operation from 1953 to 1967. Additional decontamination effluents and solvents were also likely disposed into this french drain.

Waste Type: Water

Waste Description: The site received domestic water from the changing room and water from the mask decontamination station. The site may have received chemical decontamination wastes and solvents.

Closure Info: Interim: Because the site was bordered on two sides by the reactor wall and foundation, and on the other two sides by the 100-D-48 cooling water effluent pipelines, shallow soils associated with the 116-D-6 site had previously been excavated and disposed of at the ERDF during the remediation of the 100-D-48 cooling water effluent pipelines. Remedial action at the 116-D-6 site began on October 21, 1999. Excavation of the site involved removing the overburden materials, the contaminated structure, and the underlying deep zone soils. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Materials that were found to be contaminated were disposed of at ERDF.

On January 3, 2000, the excavation reached the design limit at El. 137.9 meters (452 feet). At the completion of remedial action and removal of the engineered structure, the excavation was approximately 10.1 square meters (109 square feet) in area with a maximum depth of approximately 4.6 meters (15 feet). Approximately 200 metric tons (221 tons) of material from the site were disposed of at ERDF. The excavation will be backfilled with appropriate materials to the reference grade of El. 142.5 meters (468 feet).

Code: 116-D-7	Classification: Accepted
Names: 116-D-7; 107-D; 107-D Retention Basin	Reclassification: Interim Closed Out (8/15/2000)
Type: Retention Basin	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1967

Description: The 116-D-7 Retention Basin was an open concrete basin with a vertical concrete baffle constructed lengthwise in the middle of the basin. The floor consisted of concrete slabs, with joints originally closed with neoprene water seals. The walls sloped from the floor to a point 3 meters (10 feet) above the floor level with the remaining wall (approximately 3.0 meters [10 feet]) being vertical. The sloping wall sections were 10 centimeters (4 inches), and the vertical walls were reinforced construction with a minimum thickness of 0.3 meters (1 foot) at the top and 1.75 meters (5.75 feet) at the bottom.

Location: The 116-D-7 site is located near the northern edge of the 100-D Area and is approximately 110 meters (360 feet) from the Columbia River.

Related Sites/ Structures: The retention basin is associated with unplanned release UPR-100-D-4 and four sludge trenches that were excavated adjacent to the 107-D and 107-DR Retention Basins to dispose of sludge that had accumulated at the bottom of the basins. The sludge trenches were excavated in the spring of 1953 to facilitate repair of the retention basins. After use, they were covered with

approximately 1.8 meters (6 feet) of clean soil. In 1955, an additional trench was excavated near the southeast side of the 107-DR Retention Basin to receive effluent from the 107-D and 107-DR systems following an undetermined amount of fuel cladding failures.

Process Description: The 116-D-7 Retention Basin was constructed in 1944 to hold cooling water effluent from the 105-D Reactor for a brief period of time to allow for thermal cooling and decay of short-lived radionuclides prior to release to the Columbia River. The retention basin received reactor cooling water effluent until 1967.

Waste Type: Process Effluent

Waste Description: This site retained cooling water effluent from the 105-D Reactor for radioactive decay and thermal cooling prior to release to the Columbia River. Total radionuclide inventories in the vicinity of the basin ranged from 5 curies to over 400 curies. Seventy percent of the total radionuclide inventory was contained within the soil adjacent to the unit. Approximately 10 curies had leached into the concrete floor and walls.

Closure Info: Interim: Excavation of the 116-D-7 site began on May 1, 1997, and involved removing the overburden materials, the contaminated structure, and underlying contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Materials that were found to be contaminated were disposed of at the ERDF. The excavation design limit elevation was El. 129.85 meters (425.9 feet). However, after the original excavation and sampling, hexavalent chromium concentrations were above the soil RAG for river protection (2.2 milligrams/kilogram). To remediate areas that were above the hexavalent chromium soil RAG for river protection, approximately two-thirds of the floor (deep zone sampling areas A2, B5, C7, C8, and C9) was excavated an additional one meter, to an elevation of El. 128.85 meters (422.6 feet).

The lowest elevation that the excavation extended to was El. 127 meters (417 feet), about 7.4 meters (24.4 feet) below the ground surface (backfill reference El. 134.43 meters [440.9 feet]). The low areas (El. 127 meters [417 feet]) of the site excavation are two relatively small areas near the east and west ends of the site. The remainder of the site, with the exception of the sidewalls, was generally excavated to the design elevation of El. 129.85 meters (425.9 feet).

At the completion of remedial action and removal of the engineered structure, the excavation was approximately 12,940 square meters (139,200 square feet or 3.2 acres). Approximately 177,724 metric tons (195,941 tons) of material from the site were disposed of at ERDF.

The CVP demonstrates that remedial action at the 116-D-7 site achieved the RAOs and corresponding RAGs established in the approved interim action ROD (EPA 1995) and the RDR/RAWP (DOE-RL 1998). Materials that contain COCs at concentrations exceeding the RAGs have been excavated and disposed of at the ERDF. The remaining soils have been sampled, analyzed, and modeled to show that residual COC concentrations will support future land uses that can be represented (or bounded) by a rural-residential scenario. This scenario, described in Section 5.2, assumes multiple exposure pathways (e.g., ingestion, inhalation, and direct exposure) for shallow zone soils.

The acceptability of unrestricted direct exposure to deep zone soils has not been demonstrated; therefore, institutional controls to prevent uncontrolled drilling or excavation into the deep zone [i.e., below 4.6 m (15 ft)] are required. The verification package demonstrates that residual COC concentrations pose no threat to groundwater or the Columbia River. Thus, those areas of the 116-D-7 site represented by the CVP are verified to be remediated in accordance with the ROD.

Code: 116-D-9

Classification: Accepted

Names: 116-D-9; 117-D Crib; 117-D Seal Pit Crib **Reclassification** Interim Closed Out (3/19/2001)

Type: Crib **Start Date:** 1/1/1960

Status: Inactive **End Date:** 1/1/1967

Description: The waste site and associated piping has been excavated and Interim Closed Out. Site remediation began in 1999 and ended in 2000. The waste site included a crib and the pipeline. The crib was filled with gravel and covered to grade with clean soil. The surface was covered with cobbles, and a large steel vent cap was located in the center.

Location: The crib was located 90.7 meters (200 feet) southeast of the 105-D Building.

Related Sites/ Structures: The crib is associated with the 117 Filter Building (site 132-D-2).

Process Description: The 116-D-9 Crib operated from 1960 to 1967. It received stack drainage through a 10-centimeter (4-inch)-diameter pipeline from the confinement system 117 Building seal pits. The 117 Building received exhaust fan discharges from the 105-D Reactor through an inlet duct and released the filtered air through the 132-D-4 exhaust stack. The crib was a 3 meter by 3 meter by 3 meter (10 by 10 by 10 foot) gravel-filled crib with a large steel vent cap extending above the ground surface. It received an estimated 420,000 liters of process effluent drainage from the confinement seal pits located at the 117-D Building. The seal pit effluent entered the 116-D-9 Crib through a 91.4 meter (300-foot) long, 10.2 centimeter (4 inch.) diameter asbestos cement pipe. Sampling in 1978 revealed contamination at the 116-D-9 site was at or below background.

Waste Type: Process Effluent

Waste Description: The site received drainage from the confinement system 117 Building seal pits.

Closure Info: Interim: Remedial action began on October 29, 1999. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Contaminated materials were disposed at ERDF. On August 11, 2000, the excavation reached the design limit at elevation 137.3 meters (447.2 feet).

At the completion of remedial action and removal of the engineered structure, the excavation was approximately 598.4 square meters (6,441 square feet) in area with a maximum depth of approximately 5.5 meters (18 feet). An estimated 100 meters (328 feet) of pipeline was removed. The excavation was backfilled with appropriate materials to the reference grade elevation of 142.5 meters (467 feet). Approximately 7.3 metric tons (8.0 tons) of material was removed and disposed at the Environmental Restoration Disposal Facility (ERDF).

Code: 116-D-10

Classification: Accepted

Names: 116-D-10; 105-D Fuel Storage Basin Cleanout Percolation Pit; 105-D Fuel Storage Discharge Ponds; 105-D Ponds **Reclassification** Interim Closed Out (12/2/2010)

Type: Pond **Start Date:** 7/1/1984

Status: Inactive **End Date:** 9/1/1984

Description: The waste site has been excavated and Interim Closed Out. It consisted of two open excavated pits with a crossover channel connecting them. The west excavation was 10.7 meters (35 feet) long, 6.7 meters (22 feet) wide, and 0.9 meters (3 feet) deep. The east excavation was 15.2 meters (50 feet) long, 7.3 meters (24 feet) wide, and 1.2 meters (4 feet) deep. Both pits had been back filled and graded to resemble the natural terrain.

-
- Location:** The site was located east of the 105-D Reactor Building and just outside of the AC-5-40 permanent markers.
- Related Sites/ Structures:** 105-D Fuel Storage Basin
- Process Description:** The site was used during the 1984 cleanout of the 105-D Fuel Storage Basin (FSB) to dispose of water to the soil. During cleanout of the basin, radiologically contaminated shielding water was processed through ion-exchange columns and retained in holding tanks for analysis before being released to the soil. The water was released to two open excavated pits (ponds) with a connecting channel. The west pond was small and only allowed for the discharge of one holding tank per day, while the east pit was designed to handle an increase in needed capacity. During cleanout of the basin, radiologically contaminated shielding water was processed through ion-exchange columns and released to the ponds. It is reported that no hazardous substances were released with the water; however, chemical analysis was not a standard practice during that period. Additionally, as discussed in Decommissioning of the 105-D Fuel Storage Discharge Ponds Final Radiological Release Report (Beckstrom 1985), "minute quantities of radionuclides in the processed water presented a potential for accumulation of radionuclides in the soil" at the bottom of the ponds. On August 27, 1984, a process equipment failure affected approximately 2,350,000 L (620,000 gal) of water that was processed from the 105-D FSB and introduced very fine particles of sludge into the processed water holdup tanks (Beckstrom 1985). When the previously clean water from the holdup tanks (verified by radiochemical and isotopic analysis) was discharged, the fine sludge particles were also released, allowing radioactive material to enter the soil. Water processing operations were immediately suspended and a detailed radiological survey was performed. Contamination levels ranged from 1 pCi/g to several hundred pCi/g. Equipment was repaired and operations resumed on September 6, 1984. The final tank of processed water was discharged on September 22, 1984. After discharge of the fuel storage basin water was complete, approximately 28 m³ (1,000 ft³) of contaminated soil was removed from the bottom of the ponds and taken to the 200 West Area for burial. Radiological surveys and sampling were then performed to support the completion of contamination removal. The mean alpha and beta-gamma activities were calculated to be less than 1 pCi/g and 17.7 pCi/g, respectively, which met the unrestricted release criteria of less than 1 pCi/g alpha activity and less than 20 pCi/g beta-gamma activity that was applicable at that time. The ponds were then filled to grade with 0.9 to 1.2 m (3 to 4 ft) of clean soil. A 2005 review of the maximum detected isotopic activity levels concluded that residual beta-gamma activity exceeded current remedial action goals (RAGs) in some areas.
- Waste Type:** Water
- Waste Description:** The unit received processed water from the 105-D Fuel Storage Basin. During the cleanout of this basin, the radiologically contaminated shielding water was processed through ion exchange columns. Before discharging the water to the unit, composite samples were taken to ensure that radionuclide concentrations were below release criteria in Table II of DOE Order 5480.1. No known hazardous substances were present in the water, however chemical analysis was not a standard practice during that period and there is no evidence that analyses were performed. It should be noted that water removed from the 1608-D is believed to be comparable to the storage basin water, and EP-TOX testing results for the 1608-D water were negative.
- Closure Info:** Interim: Remedial action was performed from April 24 to May 13, 2008. Approximately 2,700 bank cubic meters (3,500 bank cubic yards) of soil was stockpiled. The excavation was approximately 33 meters (110 ft) long, 25 meters (84 ft) wide, and 5 meters (15 ft) deep. No contaminated soil was found during this remediation, likely because the contamination would have been localized in a very thin layer, located about 1 meter (3 ft) below grade, and would not be readily separated from the surrounding clean soil without using smaller tools than the large scale remediation equipment. Since the excavation reached a depth of 4.6 meters (15 ft), the contaminated soil was certainly blended within the soil stockpile as a result of the
-

excavation and stockpiling. Although no radiological contamination was identified, the staged material was removed to the Environmental Restoration Disposal Facility because of the potential for residual contamination existing within the stockpile. This removal occurred on January 7 through 26, 2009.

Code: 120-D-2	Classification: Accepted
Names: 120-D-2; 186-D Waste Acid Reservoir	Reclassification: Interim Closed Out (7/28/2009)
Type: Surface Impoundment	Start Date:
Status: Inactive	End Date: 1/1/1979

Description: The waste site has been remediated and Interim Closed Out. It consisted of the 186-D waste acid reservoir and associated soils. The above ground 186-D facilities were decommissioned and demolished in 1979. The fate of the lead flashing that was part of the waste acid reservoir was not documented and is assumed to have been disposed in place during demolition. The facilities were removed down to 1 meter (3 ft) below ground surface during demolition. The 120-D-2 reservoir was backfilled and leveled to grade at that time. The waste site was constructed of acid-proof brick, 3-ply waterproof membrane, vitrified pipe, #8 lead flashing, and gunnite. The sides of the reservoir were sloped 2:1 from 1.5 meters (5 feet) below grade level to the bottom. As of June 21, 1991 the site area was covered with gravel and annual weeds. No evidence remained on the surface of the building structure.

Location: The site is located west and south of the center of the 186-D Building.

Related Sites/ Structures: The reservoir drains were connected to the 100-D Area process sewer system. The 186-D Building was originally constructed to be used as a water treatment plant, and the acid waste reservoir was constructed to receive waste acid from processes in the 186-D Building. The 186-D Building was never used as a water treatment plant, however it was used as a warehouse.

Process Description: The 120-D-2, 186-D Waste Acid Reservoir was part of the 186-D demineralization facilities (WHC 1994). The waste acid reservoir was located west and south of center of the 186-D Building. Unique to the 100-D Area, the 186-D Building originally contained demineralization facilities intended as a water treatment system for reactor cooling water. However, research indicates that the facilities were never used as intended. The building apparently was converted to a warehouse. An acid-proof brick-lined trench, running almost the entire length of the 186-D Building, was designed to gather waste acid from the demineralization process and deliver it to the 120-D-2 waste acid reservoir. Acid stored in the reservoir could be transferred to the 186-D acid mixing/neutralization tanks, and subsequently discharged to the 100-D-50:7 segment of the process sewer. Underflow and overflow drains in the waste acid reservoir could also discharge directly to the 100-D-31:9 segment of the process sewer.

Waste Type: Chemicals

Waste Description: This unit was never used for waste acid storage. No records have been found documenting the disposal of waste of any kind in this facility. No written documentation has been found concerning the disposal of the lead flashing that was used in the construction of the waste acid reservoir; however, it is assumed that the lead flashing was disposed in-situ during the demolition of the 186-D Facility.

Closure Info: Interim: The above-ground 186-D facilities were decommissioned and demolished in 1979. The facilities were removed down to 1 meter (3 ft) below ground surface during demolition. The 120-D-2 reservoir was backfilled and leveled to grade at that time. The fate of the lead flashing that was part of the waste acid reservoir was not documented and was assumed to have been disposed in place during demolition.

Remediation of the waste site was performed in May through July 2007. Approximately 3,361

cubic meters (4,396 cubic yds) of stained soil, stained concrete, demolition debris, and lead sheets were excavated and disposed directly to the Environmental Restoration Disposal Facility. Observations during remediation confirmed that the visible yellow stains were present outside of the waste acid reservoir. All of the visibly impacted soils were removed (WCH Logbook, EL-1607-1). The final excavation depth ranged from 3 to 5 meters (10 to 16 feet). Soil pH was monitored during excavation to help direct the extent of the excavation and ensure all of the impacted soils were removed. Piping associated with an overflow and an underflow drain in the northwest corner of the waste acid reservoir was removed from within the footprint of the 120-D-2 remediation. Remaining portions of the drain sewer will be removed with remediation of the 100-D-31:9 pipelines.

Code:	126-D-2	Classification:	Accepted
Names:	126-D-2; 184-D Coal Pit; Inert Landfill	Reclassification:	Interim Closed Out (10/14/2010)
Type:	Inert/Demolition Landfill	Start Date:	1/1/1943
Status:	Inactive	End Date:	1/1/1986
Description:	The waste site has been remediated and Interim Closed Out. It was an excavated pit that was originally used to store coal for the 184-D Power House. Later it used as a demolition and inert waste landfill. This pit was full of debris. It had been covered with about 0.3 meters (1 foot) of pit run backfill material and graded to conform with the natural terrain. Numerous surface depressions were visible, indicating a potential cave-in hazard.		
Location:	The site was located just west of the site of the demolished 184-D Power House, north of the 183-D Water Treatment Facility, and northwest of the 105-D Reactor Building.		
Related Sites/ Structures:	The site was originally associated with the 184-D Power House.		
Process Description:	The site was first used as a coal pit in 1943. Use as a demolition and inert waste landfill began in 1970.		
Waste Type:	Asbestos (friable)		
Waste Description:	Asbestos containing waste has been disposed of at this site.		
Waste Type:	Demolition and Inert Waste		
Waste Description:	The unit contains demolition and inert waste from demolished facilities in and around 100-D. This includes debris from 184-D (including stacks), 108-D, released portions of the 115-D/DR, and 186-D. The site is suspected to contain some radioactively contaminated solid wastes. Potential contaminants include: Chromate, lead, mercury, undetermined organic and inorganic chemicals.		
Waste Type:	Chemicals		
Waste Description:	The site is known to contain paint cans and paint wastes, solvents, acids, dry chemicals, photo chemicals, and herbicide cans.		
Closure Info:	Interim: Initial remedial action at the site began on May 29, 2007, and excavation continued through October 6, 2008. Supplemental remedial action began on October 19, 2009 and excavation continued through March 16, 2010. The debris removed included concrete, steel reinforcing rod, metal pipes, reactor components, drums, various containers, transite material, and a white powdery substance. Approximately 41,873 BCM (54,770 BCY) of soil and debris were removed for disposal to the ERDF.		

Excavation continued to a depth below the base of the original coal pit, at which debris was no longer present. The final depth of the excavation ranged from approximately 3 meters (10 ft) to 5.5 meters (18 ft) in a small portion of the southeast corner of the excavation. The results of verification sampling show that residual contaminant concentrations do not preclude any future uses (as bounded by the rural-residential scenario) and allow for unrestricted use of shallow zone soils.

Code: 128-D-2	Classification: Accepted
Names: 128-D-2; 128-D-2 Burn Pit	Reclassification: Interim Closed Out (9/8/2011)
Type: Burn Pit	Start Date:
Status: Inactive	End Date:

Description: The waste site has been remediated. The site was a large landfill area that showed evidence of surface burning and has no definite boundaries. The site was marked with signs of plant stress, depressions, and berms. Concrete and metallic debris exposed on the surface indicated the possibility that this site was also used as a solid waste landfill. The following items were also noted during the March 31, 1999, visit: rigging equipment, bricks, and unidentified white powder that may be ash, and a north-south running trench. The site has been used as a disposal site for compacted tumbleweeds collected from area fences. Knapweed was noted during the March 1999 walkdown.

Location: The site is located northeast of 105-D and southwest of 100-D-7.

Waste Type: Misc. Trash and Debris

Waste Description: Some pieces of non-contaminated reactor hardware and graphite blocks were found at the site.

Closure Info: Interim: Remediation at the 128-D-2 waste site was performed between July 22, 2009 and January 14, 2010. Approximately 39,570 bank cubic meters (BCM) (51,756 bank cubic yards [BCY]) of contaminated soil and debris were removed from the 128-D-2 waste site. The debris removed from the 128-D-2 waste site consisted of miscellaneous noncombustible debris including concrete, metal, bricks, vitrified clay pipe, and electrical wiring. Although radionuclides cesium-137, potassium-40, thorium-228, thorium-232, radium-226, radium-228, and strontium-90 were detected in confirmatory soil samples at the 128-D-2 waste site, no radiologically contaminated material was discovered during remediation at the 128-D-2 waste site. No indications of previous spills or releases were detected during remediation at the 128-D-2 waste site.

The soil and debris from the 128-D-2 Burn Pit and the 100-D-7 Undocumented Solid Waste Site were staged in a staging pile to the east of the 128-D-2 waste site and southeast of the 100-D-7 waste site before being loaded for disposal at the Environmental Restoration Disposal Facility (ERDF). The staging area includes a smaller area where topsoil from the waste sites was placed for use on top of the backfill to support successful revegetation as required by the ecological review for the 128-D-2 and 100-D-7 waste sites. All staged waste has been disposed to the ERDF. The staging area was then scraped to remove surface contaminated soil, which was disposed to the ERDF. The location of the staging pile was closed out with the 100-D-7 waste site.

Three anomalies were initially identified during the remediation at the 128-D-2 waste site. These consisted of white powder (anomaly 100D-AN-09-060), an area with clumps of yellow sand (anomaly 100D-AN-09-064), and a white solid material (anomaly 100D-AN-09-065). All these materials were sampled and characterized prior to removal and shipment to ERDF, and the sample results are reported in the Work Instruction for Verification Sampling of the 128-D-

2 Burn Pit and the 100-D-7, Undocumented Solid Waste Site. The 100-D-7 waste site is located approximately 700 meters (2300 feet) northeast of the 105 Reactor Building, and immediately northeast of the 128-D-2 Burn Pit.

Code:	130-D-1	Classification:	Accepted
Names:	130-D-1; 1706-D Gasoline Storage Tank; 1716-D Gasoline and Oil Storage Tanks	Reclassification	Interim Closed Out (8/15/2011)
Type:	Storage Tank	Start Date:	1/1/1944
Status:	Inactive	End Date:	1/1/1968

Description: Originally the site consisted of two underground storage tanks. One of the tanks held leaded gasoline and had a capacity of 3,800 L (1,000 gal). The gasoline tank was removed in 1989 as part of the Hanford Site underground storage tank (UST) removal program. It was noted to be empty and heavily deteriorated. The underlying soils were visibly impacted. The other was an oil tank with a capacity of approximately 300 gallons (H-1-5017).

Location: The gasoline tank was located northeast of 190-D and on the east side of the demolished 1716-D Building. The oil tank was located on the west side of the 1716-D Building.

Related Sites/ Structures: The two storage tanks were related to the former 1716-D Garage.

Process Description: From 1944 until 1968, the gasoline tank was used to support vehicle fueling operations at the 1716-D Garage. The oil tank was installed during construction of the lubrication pits in 1953 (HW-27932). The drawing shows two lines from the tank to the 1716-D Building. The text describing the tank in drawing (H-1-5017) is not legible. No other historical information is available about the oil tank. The oil tank was added to the 130-D-1 waste site after it was discovered while excavating the 100-D-31:7 pipeline subsite in 2010. The oil tank was subsequently removed and disposed of at ERDF.

When the garage operations were centralized following deactivation of the 100-D/DR Area, the gasoline tank was emptied of product and filled with water. In 1989, the tank was removed as part of the Hanford Site Underground Storage Tank (UST) removal program and was noted to be devoid of any contents and heavily deteriorated. Underlying soils were visibly impacted, and characterization showed elevated levels of petroleum hydrocarbons. (WHC-N-270) No soil remediation or removal activities were performed, and the excavation was backfilled with clean material. Slightly elevated concentrations of lead were detected in subsequent site characterization activities (DOE/RL-93-29).

The coordinates for the gasoline tank, provided in the Technical Baseline Report, are incorrect per H-1-1520, revision 1. The coordinates would place the gasoline storage tank by the water tower (sanitary water tank 1902-D) approximately 122 m (400 ft) west of the garage and gas station. During the April 1999 site walkdown, no evidence of the site could be found except for some soil gas probes left from the soil gas investigation (WHC-SD-EN-ES-031). The concrete marker mentioned in the Technical Baseline Report could not be found at either the coordinates mentioned in that document or at the site's mapped location. The top of the former gasoline UST is believed to have been located 1.3 to 1.5 m (4 to 5 ft) below ground surface, and soils impacted by past product releases may currently exist up to 3 m (10 ft) of clean overburden.

In June 2004, a geophysical survey was performed at the 130-D-1 site to verify the absence of the underground storage tank (UST) and delineate any residual anomalous subsurface features (CCN 115042). The survey was conducted using ground penetrating radar, electromagnetic induction, and magnetometry. No subsurface anomalous features with the characteristics of a UST were observed. Several subsurface anomalous features were observed during the survey,

including linear anomalies and magnetic anomalies indicative of basalt-rich gravels commonly used for parking areas and roadways.

The project team conducted a site visit in February 2005. The objectives of the visit were as follows: (1) Evaluate the site in consideration of geophysical survey information and historic documentation to assist in the development of an effective environmental strategy, (2) Confirm the waste site boundary, (3) Locate and evaluate surface debris and anomalies that would require removal to allow for reclassification of the waste site, (4) Evaluate access and staging considerations for heavy excavation equipment. The suspected location of the former gasoline tank was identified during the site visit based on the presence of soil gas sampling debris and grid markings from the geophysical survey.

Waste Type: Oil

Waste Description: The two storage tanks were related to the former 1716-D Garage. Contaminants of potential concern (COPCs) include TPH, SVOAs, VOCs, arsenic, barium, chromium, lead, selenium, silver, and polychlorinated biphenyls (PCBs). Radionuclides are not a COPC for this site. Based on a review of historical process information and the results of past characterization, the 130-D-1 site is expected to contain hazardous constituents at levels in exceedance of remedial action goals.

Closure Info: Interim: The gasoline tank was removed in 1989 as part of the Hanford Site underground storage tank (UST) removal program. It was noted to be empty and heavily deteriorated. The underlying soils were visibly impacted. In January 2009, a tank identified as the 1716-D Abandoned Oil Tank was discovered within the layback of the 100-D-31:7 excavation at a depth of approximately 3.3 m (10.8 ft). While moving the tank from the 100-D-31:7 excavation layback, approximately 95 liters (25 gal) of oily fluid was spilled onto a lined containment area, adjacent to the tank. The 1716-D Abandoned Oil Tank and all associated piping within the 100-D-31:7 excavation were removed and disposed at the Environmental Restoration Disposal Facility (ERDF).

Remedial action at the 130-D-1 waste site began on July 21, 2010, and continued through July 26, 2010. Additional remediation was conducted on March 17, 2011, and April 15, 2011, due to residual contamination identified following verification sampling activities. The entire excavation resulted in approximately 780 bank cubic meters (BCM) (1,020 bank cubic yards [BCY]) of soil and debris being removed for disposal at the ERDF. The site was excavated to an approximate depth of 3.5 m (11.5 ft) deep.

Prior to being loaded out for disposal at ERDF, the contaminated soil and debris was staged in a staging pile area on asphalt located east of the 130-D-1 excavation. Following loadout of the waste material, the staging pile area was excavated, removing the asphalt and underlying soil to a depth of approximately 0.5 meter (1.5 ft) below the surface.

Code: 132-D-1	Classification: Accepted
Names: 132-D-1; 115-D/DR Gas Recirculating Facility	Reclassification: Interim Closed Out (12/5/2011)
Type: Process Unit/Plant	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1967

Description: The waste site has been remediated. It consisted of the demolished 115-D/DR Gas Recirculation Facility footprint, debris and pipe tunnels. This remedial action did not include the some portions of the 115-D/DR facility (the seal pit, inlet and outlet ductwork, and tunnels connecting to the 105-D and 105-DR Reactors) that will be included in remedial activities of the 100-D-86:1 and 100-D-50:4. The 115-D/DR Gas Recirculation Facility was a single-story, reinforced concrete structure, 6.1 meters (20 ft) high, with a basement. At ground level, an

operating gallery ran the length of the building and was flanked on either side by cells that contained the gas processing equipment. The cells, including walls, ceilings and floors, were constructed of reinforced concrete slabs with composition surfaces. At right angles to the operating gallery and extending across the full width of the building's end, the fan room was constructed of concrete block and contained the ventilation fan, air compressor, office and locker room.

Location: The was site was located south of the 105-D Reactor Building.

Related Sites/ Structures: The building housed the gas dryers, injection and circulation equipment for the recirculating gas system for both the 105-D and 105-DR Reactors. The vacuum and pressure seal pit, and adjoining tunnels are part of the 100-D-86:1 waste site.

Process Description: The facility was built in 1943 with equipment for 105-D Reactor. The equipment for 105-DR Reactor was added in 1947 and placed in operation in 1950.

Waste Type: Demolition and Inert Waste

Waste Description: The resident radionuclides are tritium, carbon-14, cobalt-60, strontium-90, cesium-137, europium-152, and plutonium-239.

Closure Info: Interim (12/5/2011): Remedial action a began on September 27, 2010. The excavation continued through March 3, 2011, to a depth of approximately 3.6 to 4.5 meters (12.0 to 15.0 ft), resulting in the removal of the 115-D/DR Building engineered structure. This remedial action did not include the some portions of the 115-D/DR facility (the seal pit, inlet and outlet ductwork, and tunnels connecting to the 105-D and 105-DR Reactors) that will be included in remedial activities of the 100-D-86:1 and 100-D-50:4 waste sites.

While removing rebar on the east sidewall of the 132-D-1 waste site, the excavation came into contact with an old asphalt parking lot, resulting in chunks of asphalt breaking off and falling into the excavation. The larger, visible pieces of asphalt was removed from the east side slope and excavation floor. However, there is the possibility of smaller pieces of asphalt being present within the excavation.

Code: 132-D-2	Classification: Accepted
Names: 132-D-2; 117-D Filter Building	Reclassification Interim Closed Out (5/9/2006)
Type: Process Unit/Plant	Start Date: 1/1/1961
Status: Inactive	End Date: 1/1/1967

Description: The building has been remediated and Interim Closed Out. This waste site the 117-D Building, the intake ventilation duct from the 105-D Reactor Building, and the exhaust ventilation ducts to the 116-D Reactor Exhaust Stack. The stack housed blowers and particulate filters used to treat the ventilation exhausted from the 105-D Reactor Building. The building and ducts were demolished in place in 1986 and now resembles a gravel parking lot.

Location: The site was located south of the 105-D Reactor (118-D-6), near the 116-D Stack (132-D-4).

Related Sites/ Structures: The site was associated with the 105-D Reactor (118-D-6), the 116-D Stack (132-D-4), the 119-D Sample Building, and the 117-D Seal Pit Crib (116-D-9).

Process Description: The 117-D Building was constructed as part of the reactor confinement project. Prior to its use, unfiltered ventilation was exhausted directly from the reactor to the atmosphere. The confinement project diverted the exhaust just before the stack and routed it to the filter building where it passed through a series of filters. The filtered exhaust was then routed back to the ventilation exhaust stack where it was discharged to the atmosphere. Sealwells within the filter building provided the ability to direct the exhaust into one or both of the filter cells.

The building was divided into two large filter cells with a smaller operating area between them. The filter cells each held six filter frames (two wide and three deep). The filter frames were designed to hold twenty-eight filters that were 0.6 meters (2 feet) square by 0.3 meters (1 foot) thick. There were spaces between the frames to allow access for filter maintenance. The operating area between the two cells was divided into two levels. The upper level, called the access gallery had ten doors that led from it. Four doors opened into each of the filter cells and the two other doors provided access to the intake and exhaust ducts. The operating gallery was located below the access gallery. A sump was located at each end of the operating gallery to collect incidental drainage from above. A large open area extended the full length of the structure above the access gallery and the filter cells. It ranged in height between 2.5 and 2.4 meters (8.1 and 7.8 feet) due to the structure's sloping roof. The space provided access to the cement cover blocks that were positioned over each of the filter frames.

Waste Type: Demolition and Inert Waste

Waste Description: The site contained radiological contamination from 105-D Reactor ventilation exhaust. Total radionuclide inventory in the 117-D building was estimated to be 3.9E-03 curies. The radionuclides comprising this figure were tritium, carbon-14, cobalt-60, strontium-90, cesium-137, europium-152, and plutonium-239.

Closure Info: Interim: Demolition and site grading were performed in 1986 using conventional heavy equipment, including a crane with a wrecking ball, bulldozer, and trucks. The 117-D building floors were perforated to allow for drainage and the roofs of the inlet and outlet ducts were collapsed. The building and ducts were then backfilled with demolished concrete and clean fill material. Demolition rubble was buried under at least 1 meter (3.3 ft) of clean fill, with rubble from the seal pits buried under at least 5 meters (16 ft) of clean fill, and the site graded to blend with the surrounding terrain.

RESidual RADioactivity (RESRAD) modeling was performed in 2005 to support the previous decision to demolish and bury the building in place. The model used the maximum radiological activities from the pre-demolition characterization data to represent residual contamination levels over 100% of the paint and concrete of the former building. The RESRAD modeling accounts for radioactive decay from 1985 (year of sampling) to 2005, and predicts that the site achieves the dose limits and risk objectives for rural residential land use with institutional controls, groundwater protection, and river protection. Further excavation of the site to collect more information (i.e., samples) was not likely to result in a change to the interim closed out decision because the residual contamination occurred within a thin surface layer of paint on the interior surfaces of the building and would be unlikely to be detected in the deep zone rubble resulting from demolition of the building. A baseline risk assessment for the river corridor portion of The Hanford Site began in 2004, which includes a more complete quantitative ecological risk assessment. That baseline risk assessment will be used as part of the final ROD for this site.

Code: 132-D-3	Classification: Accepted
Names: 132-D-3; 1608-D Effluent Pumping Station; 1608-D Waste Water Pumping Station	Reclassification: Interim Closed Out (5/9/2006)
Type: Pump Station	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1965

Description: The waste site has been remediated and Interim Closed Out. It consisted of the effluent pumping station facility that was decommissioned and demolished in 1986. The area was backfilled to grade and a gravel cover added. It now resembles a gravel parking lot. As documented in the Remaining Sites Verification package RSVP-2005-033, the site meets the

objectives for interim closure.

Location: The unit was located adjacent to the south side of the 105-D Reactor (118-D-6) within the 105-D/DR Exclusion Fence.

Process Description: This unit received water from the 105-D reactor building drains containing trace amounts of low-level radionuclides and decontamination chemicals. Water was pumped from the reactor collection pits into the reactor effluent lines near the reactor building and became part of the 107-D effluent (116-D-7) that was discharged to the Columbia River.

Waste Type: Process Effluent

Waste Description: This unit received water from reactor building drains containing trace amounts of low-level radionuclides and decontamination chemicals. Radionuclides were primarily miscellaneous fission and activation products. The decontamination chemicals consisted of sodium fluoride, oxalic acid, and citric acid.

Waste Type: Demolition and Inert Waste

Waste Description:

Closure Info: Interim: Decommissioning was performed in two phases. Phase 1 consisted of water removal (910 liters [240 gallons]), asbestos removal/disposal (1.1 cubic meters [40 cubic feet]), and pump and piping removal, and was completed April 4, 1986. Phase 2 consisted of in situ demolition and site grading and was completed January 6, 1987. The facility was covered with 1 meter (3.3 feet) of soil. The waste was transported to the 200 Area for disposal.

Demolition and site grading were performed in 1986 using conventional heavy equipment. The structure was demolished to at least 1 meter (3.3 feet) below grade and the rubble buried in situ under at least 1 meter (3.3 feet) of clean fill. The site was released for unrestricted use based on the post-decontamination characterization results and the Dose Assessment of In Situ Burial of the 1608-D Lift Station.

Soil cleanup levels were established in the interim action ROD based on a limited ecological risk assessment. A baseline risk assessment for the river corridor portion of Hanford began in 2004, which includes a more complete quantitative ecological risk assessment. That baseline risk assessment will be used as part of the final ROD for this site. Using the maximum radiological activities from the 1986, pre-demolition characterization data to represent residual contamination levels throughout all the residual concrete of the former building, RESidual RADioactivity (RESRAD) modeling was performed in 2005 to support the previous decision to demolish and bury the building in place.

Code: 1607-D2	Classification: Accepted
Names: 1607-D2; 1607-D2 Sanitary Sewer System; 1607-D2 Septic Tank; 1607-D2 Septic Tank and Associated Drain Fields; 124-D-2	Reclassification: Interim Closed Out (1/13/2015)
Type: Septic Tank	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1996

Description: The 1607-D2 Septic System was divided into five subsites: The 1607-D2:1 Abandoned Tile Field; 1607-D2:2 Replacement Tile Field, 1607-D2:3 Septic Pipelines, 1607-D2:4 Septic Tank, and 1607-D2:5 Inlet Pipe to Replacement System Tile Field. This site was broken into subsites to allow for close out of each part as remediation progressed in the area. All five subsites have been remediated and Interim Closed Out. Therefore, the parent site is also considered to be

Interim Closed Out.

Location: The septic tank was located approximately 30 meters (100 feet) southeast of the 116-D-7 Retention Basin. The original tile field (abandoned in 1950) was near the east side of the 116-DR-9 Liquid Effluent Retention Basin facility and approximately 91.5 meters (300 feet) northeast of the 1607-D2 Septic Tank. The replacement tile field is located approximately 244 meters (800 feet) north of the septic tank, north of the perimeter road.

Related Sites/ Structures: The site serviced the 189-D (Storage Yard and Mechanical Development Laboratory), the 185-D (Thermal Hydraulics Laboratory), the 182-D (Reservoir and Pump House), the 183-D (Water Filter Plant), the 1700-D Administration and Services, and the 105-D Reactor Building. The 100-D-31:1 waste site addressed a portion of the 1607-D2 septic sewer pipeline that transported sewage from manhole S-21D north to manhole S-25D.

Waste Type: Sanitary Sewage

Waste Description: This unit received sanitary waste from office, maintenance services, and process water pumping buildings (190-DA, 189-D, 185-D, 182-D, 183-D, 170-D, and 105-D). The flow rate to this unit was estimated at 4,640 liters/day (1,225 gallons/day). There were several clay brick access manholes associated with this septic system located throughout the 100-D Area. Potential contaminants include Eu-152, U-235, U-238, Cs-137, C0-60, chromium, mercury and lead.

This Site has the Following SubSites:

Code: 1607-D2:1

Names: 1607-D2:1; Eastern 1607-D2 Tile Field; Original 1607-D2 Tile Field

Code: 1607-D2:2

Names: 1607-D2:2; Northern Tile Field; Replacement 1607-D2 Tile Field

Code: 1607-D2:3

Names: 1607-D2:3; 1607-D2 Septic Pipelines

Code: 1607-D2:4

Names: 1607-D2:4; 1607-D2 Septic Tank

Code: 1607-D2:5

Names: 1607-D2:5; 1607-D2 Inlet Pipe to Replacement System Tile Field

Code: 1607-D2:1

Classification: Accepted

Names: 1607-D2:1; Eastern 1607-D2 Tile Field; Original 1607-D2 Tile Field

Reclassification: Interim Closed Out (3/25/1999)

Type: Septic Tank

Start Date: 1/1/1944

Status: Inactive

End Date: 1/1/1950

Description: The 1607-D2:1 Abandoned Tile Field is a subsite has been remediated and Interim Closed Out. The tile field consisted of a clay pipe drain field positioned approximately 1 to 2 meters (3.3 to 6.6 feet) below surrounding grade. A thick layer of aggregate and native sandy gravel soils were placed around the clay pipes.

Location: The 1602-D2:1 tile filed was located near the east side of the 116-DR-9 Retention Basin.

Process Description: The 1607-D2:1 tile field was built in 1944. Sewage liquid from the 553 person-capacity 1607-D2 septic tank discharged to the tile field from 1944 to 1950. The septic tank was designed to capture the solids, and decant liquid effluent which was transported to the tile field. Solids and sludge were retained in the 91,500 liter (24,160 gallon) septic tank (the septic tank is subsite 1607-D2:4).

Closure Info: Interim: In 1950 the tile field was partially demolished for the construction of the 116-DR-9 Liquid Effluent Retention Basin. A replacement tile field (subsite 1607-D2:2) was constructed north of the retention basins. The name "abandoned tile field" was assigned to the infrastructure that remained, adjacent to the 116-DR-9 retention basin.

Excavation of the 1607-D2:1 site began on January 8, 1998, by removing the overburden materials, contaminated soil, and the engineered structure (i.e., clay tiles and aggregate). This first excavation effort removed approximately the top 2 meters (6.6 feet) of soil. All overburden material was found to be contaminated based on field screening results and was disposed at the ERDF with other contaminated material. Contamination was encountered at the base of the first excavation (i.e., below the engineered structure elevation) based on field screening results. A second excavation effort was initiated on January 9, 1998, and was completed on February 4, 1998. The site was judged to be clean based on field screening results. Cleanup verification sampling was initiated at the final excavation elevation of 131.6 meters (431.8 feet).

During excavation of the overburden materials, field screening was used to distinguish between potentially clean materials and contaminated materials for disposal at the ERDF. The field screening results indicated that all removed overburden material did not meet direct exposure RAGs. The overburden material was disposed of at the ERDF.

At the completion of the remedial action, the area of the excavation was approximately 1,203 square meters (12,949 square feet) at a depth of 3.4 meters (11 feet), and approximately 10,040 metric tons (11,064 tons) of material from the site were disposed at the ERDF. The excavation will be backfilled in the near future with clean fill materials to the reference grade of El. 135 meters (443 feet). Clean backfill will be taken from Borrow Pit 21, which is located due south of the 1607-D2:1 site. The material in the borrow pit has been surveyed in accordance with the SAP and is appropriate for use as backfill.

The SubSite is Part Of:

Code: 1607-D2

Names: 1607-D2; 1607-D2 Sanitary Sewer System; 1607-D2 Septic Tank; 1607-D2 Septic Tank and Associated Drain Fields; 124-D-2

Code: 1607-D2:2

Classification: Accepted

Names: 1607-D2:2; Northern Tile Field; Replacement 1607-D2 Tile Field

Reclassification: Interim Closed Out (9/16/2010)

Type: Septic Tank

Start Date:

Status: Inactive

End Date:

Description: This subsite has been remediated and Interim Closed Out. The 1607-D2:2 drain field replaced the original drain field in 1950 when the 116-DR-9 Retention Basin was built and placed over a portion of the original drain field.

Related Sites/ Structures: 1607-D2:5 is associated with this site.

Process Description: The replacement drain field serviced buildings in the 100-D Area until 1996, when a new underground septic system was installed to support facilities associated with the 100-D waste sites remediation. Buildings serviced by the replacement drain field included the 189-D Storage Yard and Mechanical Development Laboratory, 185-D Thermal-Hydraulics Laboratory, 182-D Reservoir and Pump House, 183-D Water Filter Plant, 1700-D Administration and Services Building, and the 105-D Reactor Building.

Closure Info: Interim: Remedial action at the subsite began on April 7, 2008, and concluded on April 23,

2008 with approximately 3,471 bank cubic meters of material removed and disposed to ERDF. The excavation was approximately 100 meters (330 ft) long, 60 meters (200 ft) wide, and ranges from 1.8 meters (6 ft) to 3.1 meters (10 ft) deep.

During remediation, the inlet pipeline to the drain field was located in the sidewall of the excavation at Washington State Plane Coordinates N151445/E573808. A review of the excavation footprint for the 1607-D2:3 subsite (CVP-2000-00004) indicated that a portion of the pipeline north of the perimeter road had not been removed. It was also observed that the active 100-D Area Pump-and-Treat Project pipelines run directly over the ground surface in this location. A fifth subsite, 1607-D2:5, was created to accommodate a section of inlet piping to the replacement drain field that could not currently be removed due to overlaying pipelines of a pump and treat system. Remediation of the 1607-D2:5 subsite will occur at a future date.

A geophysical survey was conducted in February 2008 to locate electrical utilities in the vicinity of the 1607-D2:2 Replacement Drain Field. The survey identified surface electrical lines from a nearby pump-and-treat operation. Piping and electrical lines from the pump-and-treat operation precluded the excavation of a section of the inlet piping to the replacement drain field. This small section was administratively placed in to the 1607-D2:5 subsite to ensure the section of pipe will be remediated at a later date. Other than the surface electrical lines, the geophysical investigation did not find anything in the data to indicate other structures or hazards at the 1607-D2:2 subsite. Radiological surveys did not detect any elevated radiological activity.

The SubSite is Part Of:

Code: 1607-D2

Names: 1607-D2; 1607-D2 Sanitary Sewer System; 1607-D2 Septic Tank; 1607-D2 Septic Tank and Associated Drain Fields; 124-D-2

Code: 1607-D2:3

Classification: Accepted

Names: 1607-D2:3; 1607-D2 Septic Pipelines

Reclassification: Interim Closed Out (9/26/2000)

Type: Septic Tank

Start Date:

Status: Inactive

End Date:

Description: This section of the sanitary sewer pipelines has been removed and Interim Closed Out. It ran from Manhole S-250, through the 1607-D2 Septic Tank, and across the D Area North Perimeter Road to the tile field.

Location: The 1607-D2 pipeline site was located in the northern part of the 100-D Area, approximately 30 meters (100 ft) southeast of the 116-D-7 Retention Basin.

Process Description: The 1607-D2 Septic Pipelines were constructed in 1944 as part of the 1607-D2 septic system, which included tile fields and a septic tank. The pipelines were fed by the 189-D Storage Yard and Mechanical Development Laboratory, the 185-D Thermal Hydraulics Laboratory, the 182-D Reservoir and Pump House, the 183-D Water Filter Plant, the 1700-D Administration and Services Building, and the 105-D Reactor Building.

Closure Info: Interim (9/26/2000): Remedial action at the 1607-D2:3 pipeline waste site began on August 20, 1999. Excavation of the site involved removing the overburden materials, the contaminated structure, and the underlying contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Materials that were found to be contaminated were disposed of at the ERDF. On August 30, 1999, the excavation reached the design limit at elevation 131 meters (430 feet).

At the completion of remedial action and removal of the engineered structure, the shallow zone

excavation was approximately 1,780 square meters (19,200 square feet) in area with a maximum depth of approximately 4.6 meters (15 feet). The overburden area was approximately 1,850 square meters (19,900 square feet). The excavation has been backfilled to the reference grade of elevation 136 meters (445 feet). Backfill was taken from the clean stockpile and/or from other sources of clean material surveyed in accordance with the SAP and that are appropriate for use as backfill.

The SubSite is Part Of:

Code: 1607-D2

Names: 1607-D2; 1607-D2 Sanitary Sewer System; 1607-D2 Septic Tank; 1607-D2 Septic Tank and Associated Drain Fields; 124-D-2

Code: 1607-D2:4

Classification: Accepted

Names: 1607-D2:4; 1607-D2 Septic Tank

Reclassification Interim Closed Out (11/23/1999)

Type: Septic Tank

Start Date:

Status: Inactive

End Date:

Description: The 1607-D2:4 Septic Tank subsite has been remediated and Interim Closed Out. It was constructed of reinforced concrete and had a 553 person capacity (130 L [35 gal] per capita). It had an average retention period of 24 hours. Two tile fields were associated with this septic tank and were 4.1 meters (13.5 ft) deep.

Location: The septic tank was located approximately 30 meters (100 ft) southeast of the 116-D-7 Retention Basin.

Process Description: The 1607-D2 Septic Tank was constructed in 1944 and is located approximately 30 meters (100 ft) southeast of the 116-D-7 Retention Basin. The site serviced the 189-D Storage Yard and Mechanical Development Laboratory, the 185-D Thermal Hydraulics Laboratory, the 182-D Reservoir and Pump House, the 183-D Water Filter Plant, the 1700-D Administration and Services, and the 105-D Reactor Building. The 1607-D2 Septic Tank was 4.1 meters (13.5 ft) deep, constructed of reinforced concrete, and had a 553 person capacity (130 L [35 gal] per capita) and an average retention period of 24 hours. Two tile fields were associated with this septic tank. The original tile field was built in 1944 and was located northeast of the septic tank. This tile field was abandoned in 1950 due to the construction of the 116-DR-9 Retention Basin. A replacement tile field was built approximately 60 meters (66 yd) north of the 116-D-7 Retention Basin, north of the perimeter road. The original and replacement the fields are considered subsites of the 1607-D2 Septic System. The original the field has been addressed by a separate remedial action effort and supporting documentation. Remedial action for the replacement tile field is yet to be determined. The system was replaced by a holding tank in 1996.

Closure Info: Interim: Excavation of the 1607-D2 site began on July 17, 1998, by removing the soil surrounding the septic tank and breaking in place the cover and sides of the tank prior to drying and sampling sludge. The 1607-D2 Septic Tank cover, side walls, and excavated soil were found to be contaminated and were disposed of at the ERDF. The sludge was sampled on September 29, 1998, to determine contamination levels. The sludge was tested for free liquids using the paint filter test on October 20, 1998. The second phase of excavation began on October 21, 1998, and was completed on October 27, 1998. Excavated materials were disposed of at the ERDF.

At the completion of the remedial action and removal of the engineered structure, the area of the excavation was approximately 506 square meters (5,449 sq. ft.) at a depth of 4.7 meters (15.4 ft). Approximately 2,041 metric tons (2,250 tons) of material from the site were disposed at the ERDF. The excavation will be backfilled in the near future with clean fill materials to the

reference grade of El. 137 meters (449 ft).

The SubSite is Part Of:

Code: 1607-D2

Names: 1607-D2; 1607-D2 Sanitary Sewer System; 1607-D2 Septic Tank; 1607-D2 Septic Tank and Associated Drain Fields; 124-D-2

Code: 1607-D2:5

Classification: Accepted

Names: 1607-D2:5; 1607-D2 Inlet Pipe to Replacement System Tile Field

Reclassification: Interim Closed Out (1/13/2015)

Type: Septic Tank

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. It consisted of approximately 14 meters (46 feet) of sanitary sewer pipeline extending from a manhole to the replacement tile field. The pipe extended from a point adjacent to a manhole to the D Area North Perimeter Road. It connected into the replacement tile field (1607-D2:2).

Location: The replacement tile field was located approximately 244 meters (800 feet) north of the septic tank, north of the perimeter road.

Related Sites/Structures: This subsite is related to the 1607-D2 Replacement Tile Field (Subsite 1607-D2:2), the 1607-D2 Septic Tank (Subsite 1607-D2:4), and the 1707-D2 Septic Pipelines (Subsite 1607-D2:3).

Process Description: The pipeline was used to pass treated septage to the tile field.

Closure Info: Interim (1/13/2015): Remedial action at the 1607-D2:5 subsite was performed on April 22, 2014. The depth of the excavation extended approximately 1.5 meters (5 ft) below ground surface. Approximately 340 bank cubic meters (445 bank cubic yards) of soil and debris were disposed at the Environmental Restoration Disposal Facility. The waste material was staged prior to loadout to the Environmental Restoration Disposal Facility. A waste staging pile area (SPA) was created. There is no overburden soil stockpile associated with the 1607-D2:5 subsite. No stained soil or anomalous materials were encountered during the remediation.

The SubSite is Part Of:

Code: 1607-D2

Names: 1607-D2; 1607-D2 Sanitary Sewer System; 1607-D2 Septic Tank; 1607-D2 Septic Tank and Associated Drain Fields; 124-D-2

Code: 1607-D4

Classification: Accepted

Names: 1607-D4; 1607-D4 Sanitary Sewer System; 1607-D4 Septic Tank; 1607-D4 Septic Tank and Associated Drain Field; 124-D-4

Reclassification: Interim Closed Out (2/23/2006)

Type: Septic Tank

Start Date: 1/1/1944

Status: Inactive

End Date: 1/1/1968

Description: The site has been remediated and Interim Closed Out. The site consisted of a small septic tank and drain field.

The unit was a septic tank and tile field. The tank was 2.5 meters (8 feet 4 inches) deep, constructed of reinforced concrete, and had a 6-person capacity [130 liters (35 gallons) per

capita] with an average detention period of 24 hours. The walls were 20 centimeters (8 inches) thick, and the floor was 15 centimeters (6 inches) thick. The tile field was constructed of 10-centimeter (4-inch) vitrified pipe, concrete pipe, or drain tile with a minimum of 2.4 meters (8 feet) per capita. The laterals were open jointed and spaced 2.4 meters (8 feet) apart.

Location: The system was located between the 105-D and the 105-DR Reactors.

Related Sites/ Structures: The site serviced the 115-D and 115-DR (Gas Recirculation Buildings).

Process Description: The system received sanitary sewage from the 115-D/DR Gas Recirculation Facility. Historic drawings indicate that the 1607-D4 Septic System consisted of a rectangular prismatic septic tank and tile field. The tank dimensions were 0.6 by 1.2 meters (2 by 4 feet) in plan view and 2.5 meters (8.3 feet) deep. The design waste capacity of the tank was 795 Liters (210 gallons), leaving up to 1.4 meters (4.5 feet) of freeboard/headspace. The tank was constructed of reinforced concrete with 0.2 meters (8-inches)-thick walls and a 0.15-meter (6-inch)-thick floor. Historic piping layouts show the influent to the tank as a 0.15-meter (6 inch) vitrified clay pipe (VCP) running from the southeast corner of the 115-D/DR Building.

Waste Type: Sanitary Sewage

Waste Description: This unit received an unknown amount of sanitary waste from the 115-D Gas Recirculation Building.

Closure Info: Interim (2/23/2006): The 115-D/DR facility was decommissioned in 1985 and 1986, including demolition of above-grade features. The septic system may have been filled in as part of the decommissioning of the facility, or at some other time after its operational lifetime ended in 1968.

A geophysical survey conducted in 1992 and field observations made during a site visit in February 2005 were used to confirm the location of the site. Existing historical information was used to identify the contaminants of potential concern (COPCs) for the system. The COPC list identified in the 100 Area Remedial Action Sampling and Analysis Plan (SAP) included lead, pesticides, and semivolatile organic compounds. Based on further site-specific evaluations of septic systems, polychlorinated biphenyls were also included as COPCs in the work instructions.

Confirmatory sampling of the 1607-D4 Septic System was conducted on July 5, 2005. One test trench was excavated in the area identified as the most likely location of the septic tank. The septic tank was located within the trench and a sample collected from below it. The tank had been backfilled with clean fill unrelated to the operational history of the septic tank. No sludge was available to be sampled from within the septic tank. A sediment sample was also collected from within the VCP pipeline "tee", at 2 meters (6.5 ft) below ground surface. The sample results indicated that the previous waste removal action achieved compliance with the remedial action objectives for the 1607-D4 site.

Examination of the data has led to the conclusion that the site passes the RAGs without further remedial action. In accordance with this evaluation, the confirmatory sampling results support a reclassification of the site to interim closed out. The analytical results from soil and drain field samples were shown to meet the cleanup objectives for direct exposure, groundwater protection, and river protection.

Code: 1607-D5

Classification: Accepted

Names: 1607-D5; 1607-D5 Sanitary Sewer System; 1607-D5 Septic Tank; 1607-D5 Septic Tank and Associated Drain Field; 124-D-5

Reclassification Interim Closed Out (10/10/2011)

Type:	Septic Tank	Start Date:	1/1/1944
Status:	Inactive	End Date:	
Description:	The site resembles a gravel covered parking area. There are no signs designating the septic and tile field areas.		
Location:	The unit was located east of the northeast corner of the 181-D Pumphouse.		
Related Sites/ Structures:	The site received effluent from the 181-D (River Pump House). The influent pipe is assigned to waste site 100-D-84:2.		
Process Description:	The unit consists of a septic and a tile field. The septic was a concrete tank measuring approximately 3 by 5 ft (0.9 by 1.5 m) in plan and 7 ft 10 in (2.4 m) deep, with a metal cover. The septic tank had a 6-person capacity (35 gal [130 L] per capita) with an average detention period of 24 hours. The walls were 8 in (20 cm) thick, and the floor is 6 in (15 cm) thick. The tile field is constructed of 6-in (15 cm) or 8-in (20 cm) vitrified pipe, concrete pipe, or drain tile with a minimum of 8 linear feet (2.4 m) per capita. The laterals were open jointed and spaced 8 ft (2.4 m) apart.		
Waste Type:	Sanitary Sewage		
Waste Description:	This unit received sanitary waste from the 181-D Pumphouse. The flow rate to this unit was estimated at 35 gallons per day (130 Liters per day).		
Closure Info:	Interim (10/10/2011): Remedial action at the 1607-D5 waste site was performed between October 22 and 26, 2010. Excavation continued to a maximum depth of 3.3 m (11 ft) until all contaminated soil and debris associated with the waste site had been removed. The post-excavation civil survey is shown in Figure 3. Approximately 500 bank cubic meters (BCM) (654 bank cubic yards [BCY]) of contaminated soil and debris were removed from the excavation and directly loaded out for disposal at the Environmental Restoration Disposal Facility. The originally planned above cleanup level (ACL) stockpile proved to be in an inaccessible location. A second location was planned for the ACL, but it proved to be easier to direct load the material. Therefore, neither of the potential stockpile locations was used. No overburden material was retained for use as clean backfill.		

Code:	116-DR-1&2	Classification:	Accepted
Names:	116-DR-1&2; 116-DR-2; Emergency Crib Trench; 107-DR Liquid Waste Disposal Trench #1; 107-DR Liquid Waste Disposal Trench #2; 116-DR-1	Reclassification	Interim Closed Out (9/26/2000)
Type:	Trench	Start Date:	1/1/1950
Status:	Inactive	End Date:	1/1/1967
Description:	The site has been remediated and Interim Closed Out. It is no longer marked or posted. The site was constructed as two separate trenches that were later joined together to form a single trench.		
Location:	The site was located east of the northeast corner of 107-DR Retention Basin.		
Process Description:	The site received effluent from the 107-D and 107-DR Retention Basins when cooling water was contaminated due to ruptured fuel elements. The 116-DR-1 and 116-DR-2 Trenches were originally connected by an underground pipe. They were joined together sometime before 1967 by removing the soil between them. The enlarged single trench was used for a four month test in which the total coolant volume was deposited to the soil column.		
Waste Type:	Water		

Waste Description: The site received effluent from the 107-D and 107-DR Retention Basins when cooling water was contaminated due to ruptured fuel elements. In addition to the 4.0E+07 liters (1.06E+07 gallons) of effluent from ruptured fuel elements listed in PNL-6456 (Stenner et al), the site also received 3.87E+08 liters (1.02E+08 gallons) of cooling effluent daily during the four month test. Waste site COCs identified through process knowledge are listed in the 100 Area Remedial Action Sampling and Analysis Plan (DOE-RL 1998a). The COCs identified for this site are: americium-241, cobalt-60, cesium-137, europium-152, europium-154, europium-155, nickel-63, plutonium-238, plutonium-239/240, strontium-90, and hexavalent chromium.

Closure Info: Interim (9/26/2000): Remedial action at the 116-DR-1&2 Trench began on November 25, 1996. Excavation of the site involved removing the overburden materials, the contaminated structure, and underlying contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Materials that were found to be contaminated were disposed of at ERDF. On October 21, 1999, the excavation reached the design limit at elevation 131.1 meters (430.1 feet). At the completion of the remedial action, the total excavation was approximately 9,730 square meters (104,734 square feet) in area with a maximum depth of approximately 5.0 meters (16.4 feet). Approximately 82,768 metric tons (91,236 tons) of material from the site were disposed of at the ERDF.

Code: 116-DR-5	Classification: Accepted
Names: 116-DR-5; 1904-DR; 1904-DR Outfall Structure	Reclassification: Interim Closed Out (1/6/2011)
Type: Outfall	Start Date: 1/1/1956
Status: Inactive	End Date: 1/1/1967

Description: The site has been remediated and Interim Closed Out. It consisted of an open, reinforced, compartmentalized concrete outfall structure that routinely discharged effluent to the Columbia River via the river effluent pipelines (100-D-60). When the river pipelines were blocked, damaged or undergoing maintenance, the flow was diverted to a concrete overflow spillway (flume) (100-D-66).

Location: The site was located at the top of the river bank, north of the northwest corner of 116-D-7 (107-D Retention Basin).

Related Sites/Structures: The site is associated with the D Island Contamination (100-D-67), 107-D Retention Basin (116-D-7), the 107-DR Retention Basin (116-DR-9), 100D Reactor Cooling Water Effluent Lines (100-D-48), the 100DR Reactor Cooling Water Effluent Lines (100-D-49), the 100D River Effluent Lines (100-D-60) and Flumes (100-D-66).

Process Description: Reactor cooling water collected and temporarily stored in the 116-D-7 and 116-DR-9 retention basins, could be pumped to the river via the 116-DR-5 outfall structure and associated river effluent pipeline (100-D-60).

Waste Type: Construction Debris

Waste Description: This unit received reactor coolant from the 107-D and 107-DR Retention Basins. The contaminants of concern include C-14, Cs-137, Sr-90, U-235, -238, and Pu-239/240.

Closure Info: Interim (1/6/2011): Remedial action at the 116-DR-5 outfall waste site began on January 12, 2009, and continued through May 13, 2009. The site was excavated to a maximum depth of approximately 11 meters (36 ft) resulting in approximately 2,613 bank cubic meters (BCM) (3,417 bank cubic yards [BCY]) of soil and debris removed for disposal at the Environmental Restoration Disposal Facility (ERDF). Approximately 1,190 BCM (1,556 BCY) of overburden and layback material was removed and stockpiled for evaluation for use as clean backfill. The excavation extended into the deep zone (greater than 4.6 meters [15 ft] deep); however, the

entire site was closed out using shallow zone criteria (i.e., including consideration of direct contact cleanup levels).

Contaminated soil and debris were excavated and removed from the 116-DR-5 outfall waste site and stockpiled southeast of the excavation for loadout and disposal to ERDF. Field observations during excavation indicated the presence of concrete, rebar, piping, and miscellaneous debris consistent with the outfall structure and manhole. A small, (1 to 2 oz) polyurethane bottle was found during excavation. The bottle was found to be empty; therefore no waste characterization sample was collected. The bottle was disposed at ERDF.

Code:	116-DR-9	Classification:	Accepted
Names:	116-DR-9; 107-DR; 107-DR Retention Basin	Reclassification	Interim Closed Out (1/6/2000)
Type:	Retention Basin	Start Date:	1/1/1950
Status:	Inactive	End Date:	1/1/1967

Description: This site has been remediated and Interim Closed Out. The retention basin was an open concrete structure with a vertical concrete baffle constructed lengthwise in the middle. The floor consisted of concrete slabs whose joints originally closed with neoprene water seals. The walls sloped from the floor to a point 3 meters (10 feet) above the floor level, with the remaining wall (about 3 meters [10 feet]) being vertical. The sloping wall sections were 10 centimeters (4 inches) thick, and the vertical walls were reinforced construction with a minimum thickness of 0.3 meters (1 foot) at the top and 1.75 meters (5.75 feet) at the bottom.

Location: This site was located north of the 105-D Reactor Building.

Related Sites/Structures: The retention basin is associated with unplanned release 100-D-25 and four sludge trenches that were excavated adjacent to the 107-D and 107-DR Retention Basins to dispose of sludge that had accumulated at the bottom of the basins. The sludge trenches were excavated in the spring of 1953 to facilitate repair of the retention basins. After use, they were covered with approximately 1.8 meters (6 feet) of clean soil. In 1955, an additional trench was excavated near the southeast side of the 107-DR Retention Basin to receive effluent from the 107-D and 107-DR systems following an undetermined amount of fuel cladding failures.

Process Description: The 116-DR-9 Retention Basin was constructed in 1950 to hold cooling water effluent from the 105-DR Reactor for a brief period of time to allow for thermal cooling and radioactive decay prior to release to the Columbia River. The retention basin was a rectangular, reinforced-concrete reservoir measuring 183 meters by 83 meters, 6 meters deep (600 ft by 273 ft by 20 ft). It was located immediately east of the 116-D-7 Retention Basin, and approximately 329 meters (1,079 ft) from the 100-year flood level of the Columbia River. The basin was partially above ground and divided into two sections by a vertical concrete baffle that ran the length of the basin. The retention basin received cooling water effluent from the 105-DR Reactor from 1950 until 1965. After the 105-D Reactor was deactivated in 1965, the basin remained active until 1967 as part of the 105-D Reactor effluent system.

Waste Type: Process Effluent

Waste Description: This site received cooling water effluent from the 105-DR Reactor for radioactive decay and thermal cooling prior to release to the Columbia River. Total radionuclide inventories in the vicinity of the basin ranged from 5 curies to over 400 curies. Seventy percent of the total radionuclide inventory is contained within the soil adjacent to the unit. Approximately 10 curies have leached into the concrete floor and walls. The basin was known to have leaked on several occasions.

Closure Info: Interim: The 116-DR-9 retention basin received cooling water effluent from the 105-DR Reactor from 1950 until 1965. After the 105-D Reactor was deactivated in 1965, the basin

remained active until 1967 as part of the 105-D Reactor effluent system. Leakage occurred as unplanned releases in 1951 beneath the basin and outside the south end of the basin when seals in the concrete floor of the basin failed and the pipes pulled away from the basin walls at the retention basin inlet. The basin had a history of leaking and underwent repairs in 1951. Waste site 100-D-25 documents leakage beneath the basin and outside the south end of the basin where the neoprene seals in the concrete floor failed and the pipes pulled away from the basin walls at the retention basin inlet. The contamination could not be distinguished from other contaminated soil. It was remediated with the 116-DR-9 Retention Basin under the provisions for "proximity sites."

Excavation began on October 21, 1997, by removing the overburden materials and underlying contaminated soil. Overburden materials, which were contaminated, were disposed at the ERDF. On December 28, 1998, the excavation had reached the design limits below the base of the engineered structure (El. 130.25 m [427.35 ft]) and cleanup verification sampling was initiated. At the completion of the remedial action, the excavation area floor was approximately 16,352 square meters (176,013 sq ft) at a depth of 4.75 meters (15.6 ft), and approximately 201,519 metric tons (222,122 tons) of material from the site were disposed of at the ERDF. The excavation will be backfilled in the near future with clean fill materials to the reference grade of El. 135.0 meters (443 ft).

Contaminated soil associated with the process effluent pipelines was not removed completely, but deferred for final remediation with the pipeline waste sites. The 116-DR-9 sidewall areas that are adjacent to future pipeline excavation areas were not sampled as part of the basin cleanup verification effort. These areas will be sampled and verified clean as part of the effluent pipeline remediation efforts.

Code: 628-3	Classification: Accepted
Names: 628-3; 628-3 Burn Pit	Reclassification: Interim Closed Out (5/11/2011)
Type: Burn Pit	Start Date:
Status: Inactive	End Date:
Description: The site has been remediated and Interim Closed Out. It was an oval shaped area with a length of 76 meters (250 ft), a width of 12 meters (40 ft), and a depth of 1.2 meters (4 ft). The center of the burn pit was distinguished by a 1.2-inch (4-ft) depression. The waste site showed signs of severe plant stress and soil discoloration, and there was debris consisting of burnt wood, nails, metal pipes, rebar, and glass scattered across the area. The depression shows signs of severe plant stress and soil discoloration. The depression, as well as the area around it, was littered with debris. It appears that at one time tractors bulldozed some of the surrounding soil.	
Location: The unit was located approximately 300 meters (1,000 feet) east of 128-D-2 and approximately 92 meters (300 feet) east of the D Area Perimeter Road.	
Waste Type: Misc. Trash and Debris	
Waste Description: Debris, consisting mostly of burnt wood, nails, metal pipes, rebar, and glass, is scattered over the area. In some spots, the site also contains what looks like friable and nonfriable asbestos. The site could not definitely be found in 1992 surveys of the area.	
Closure Info: Interim: Remedial activities were carried out from March to June 2009. The excavation depth reached a maximum depth of 4.6 meters (15 ft) near the center of the pit. All contaminated material consisting of: soil, concrete/debris, suspected asbestos-contaminated material, and metal pipe and concrete debris was disposed of at the Environmental Restoration Disposal Facility (ERDF).	

After further review of the post-excavation civil survey and comparison to the geophysical survey the northern excavation boundary was extended. This excavation was completed in January 2010. The additional area of investigation was excavated to 1 meter (3 ft). No debris or indication of previous subsurface disturbance was encountered; therefore, the sample design was not changed to reflect this extended boundary. The geophysical anomalies present in the survey were believed to have been interference from surface debris and/or the basalt layer in this area.

Code: UPR-100-D-1 **Classification:** Accepted

Names: UPR-100-D-1; Oil Soaked Soil **Reclassification:** Interim No Action (4/13/2005)

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The unplanned release was evaluated and determined to require No Action. It was a small depression surrounded by oil contaminated soil. During the March 1999 visit, a buried pipe was observed to the south of the stained soil. In 2005, the area was highly disturbed and soil stained soil was no longer visible.

Location: The site was located approximately 18.3 meters (60 feet) east of the 190-D Building Trampoline Test Facility and 4.6 meters (15 feet) south of the paved road leading to the Trampoline Test Facility.

Release Description: The site contains oil-soaked soil, the source of which could not be determined.

Waste Type: Oil

Waste Description: The source of the oil could not be determined. However, the volume appeared to be small.

Closure Info: Interim: Waste Site Reclassification form 2005-020 states the stained soil was observed to be approximately 0.6 meters (2 ft) in diameter. The source of the staining could not be determined, and the estimated volume was noted as small. The project team performed a site walkdown in February 2005 to locate the site, using the coordinates listed in the WIDS database. The site was supposed to be 18.3 meters (60 ft) east of the 190-D and 1724-D Building Trampoline Test Facilities. The project team discovered that the oil-stained soil was no longer visible, and that the area of the suggested coordinates was in a highly disturbed area. Based on the historical documentation and site walkdown, a reclassification status of No Action has been assigned for the UPR-100-D-1 Oil-Stained Soil site. The site will support future unrestricted land uses that can be represented (or bounded) by a rural-residential scenario and no institutional controls are required.

Code: UPR-100-D-2 **Classification:** Accepted

Names: UPR-100-D-2; Effluent Line Leak #1 **Reclassification:** Interim Closed Out (9/26/2000)

Type: Unplanned Release **Start Date:** 1/1/1951

Status: Inactive **End Date:**

Description: The Unplanned Release was remediated with the source pipelines (100-D-48 100-D Reactor Cooling Water Effluent Underground Pipelines and 100-D-49 100-DR Reactor Cooling Water Effluent Underground Pipelines) and Interim Closed Out on September 26, 2000. UPR-100-D-2 was associated with subsite 100-D-48:2 (West Pipelines from D Avenue to 116-D-7).

Location: The release site was located southeast of the 107-D Basin and west of the 107-DR Basin.

Release Description: In 1951, extensive leakage of effluent water was detected above ground southeast of the 107-D Basin. A maximum dose rate of 50 millirads/hour was observed at the surface. Two excavations were made to investigate the leakage, but the effluent continued to seep to the surface. In 1951, the area was marked with a rope fence and marked as a "Radiation Area" (see Drawing H-1-4046).

Waste Type: Water

Waste Description: The site received radioactively contaminated water from the 107-D/DR Retention Basins.

Closure Info: Interim (9/26/2000): Remediation at the 100-D-48:2 and 100-D-49:2 pipelines and the associated releases UPR-100-D-2 and UPR-100-D-3 were remediated together. Remedial activities began in July 1997. Excavation of the waste sites involved removing the overburden material, contaminated structures, and underlying contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Excavated material found to be contaminated was disposed of at the ERDF. In August 1999, the excavation reached the design limit. The excavation design depth generally corresponded with the invert elevation of the pipelines. Because of the length of the pipeline site, the top-of-excavation elevation ranges from 138 meters (453 feet) near the retention basins to 143 meters (469 feet) near D Avenue.

At the completion of remedial action and removal of the engineered structure, the excavation was approximately 20,475 square meters (220,280 square feet) in area with a maximum depth of approximately 6 meters (20 feet) below ground surface. During the time of excavation and waste disposal (December 1998 through September 1999) approximately 57,106 metric tons (62,960 tons) of material from 100-DR-1 Operable Unit pipelines were disposed of at the ERDF.

Code: UPR-100-D-3	Classification: Accepted
Names: UPR-100-D-3; Effluent Line Leak #3	Reclassification: Interim Closed Out (9/26/2000)
Type: Unplanned Release	Start Date: 1/1/1951
Status: Inactive	End Date:

Description: The Unplanned Release was remediated with the source pipelines (100-D-48 100-D Reactor Cooling Water Effluent Underground Pipelines and 100-D-49 100-DR Reactor Cooling Water Effluent Underground Pipelines) and Interim Closed Out on September 26, 2000.

Location: The unplanned release site was along the south perimeter of the 116-DR-9 (107-DR) Basin.

Release Description: In 1951, extensive leakage of effluent water was caused by pipes pulling loose from the retention basin wall.

Waste Type: Water

Waste Description: The site was soaked with radioactively contaminated reactor cooling water from the 107-DR Basin.

Closure Info: Interim (9/26/2000): Remediation at the 100-D-48:2 and 100-D-49:2 pipelines and the associated releases UPR-100-D-2 and UPR-100-D-3 were remediated together. Remedial activities began in July 1997. Excavation of the waste sites involved removing the overburden material, contaminated structures, and underlying contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Excavated material found to be contaminated was disposed of at the ERDF. In August 1999, the excavation reached the design limit. The excavation design depth generally corresponded with the invert elevation of the pipelines. Because of the length of the pipeline

site, the top-of-excavation elevation ranges from 138 meters (453 feet) near the retention basins to 143 meters (469 feet) near D Avenue.

At the completion of remedial action and removal of the engineered structure, the excavation was approximately 20,475 square meters (220,280 square feet) in area with a maximum depth of approximately 6 meters (20 feet) below ground surface. During the time of excavation and waste disposal (December 1998 through September 1999) approximately 57,106 metric tons (62,960 tons) of material from 100-DR-1 Operable Unit pipelines were disposed of at the ERDF.

Code: UPR-100-D-4	Classification: Accepted
Names: UPR-100-D-4; Unplanned Release: 107-D Basin Leaks	Reclassification: Interim Closed Out (3/26/2001)
Type: Unplanned Release	Start Date: 1/1/1950
Status: Inactive	End Date:

Description: This waste site has been remediated and Interim Closed Out. The waste site represents multiple occurrences of cooling water leaking from the 116-D-7 Retention Basin.

Location: The unplanned release site was located on the north side of the 107-D Basin, between the basin and the river.

Release Description: In 1950, a large effluent leak occurred. The water drained under the road to a section between the road and the perimeter fence. Rad readings of 10,000 counts/minute were detected. No attempt was made at the time to cover the contamination. In 1950, the area was marked with a rope fence and posted with "Radiation Zone" signs. Today the area is not marked or posted.

Related Sites/Structures: UPR-100-D-4 is associated with the 116-D-7 Retention Basin. This UPR site was closed out in conjunction with the 100-D-48:1 and 100-D-49:1 pipelines and the 100-D-19 Sludge Trench.

Waste Type: Water

Waste Description: The site was soaked with radioactively contaminated reactor cooling water effluent.

Closure Info: Interim: Waste sites 100-D-48:1, 100-D-49:1, 100-D-19 and UPR-100-D-4 were co-located and remediated together. The CVP document referred to the four, combined waste sites as the 100-D-48:1/49:1 Pipeline site. Remedial action at the 100-D-48:1/49:1 Pipelines site began on December 28, 1998. Excavation of the site involved removing the overburden materials, the contaminated structure, and underlying contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Materials that were found to be contaminated were disposed of at ERDF. On July 24, 2000, the excavation reached the design limit. Because remediation of the 100-D-48:1/49:1 Pipelines site required moving an active overhead power line, site remedial action and sampling were conducted in two phases. These separate phases are reflected by the long time period between the start and finish dates for excavation.

The excavation design depth generally corresponded with the invert elevation of the pipelines. At the completion of remedial action and removal of the engineered structure, the excavation was approximately 15,504 square meters (166,800 square feet) in area with a maximum depth of approximately 6.0 meters (20 feet) below ground surface. Approximately 107,266 metric tons (118,241 tons) of material from the D Area pipelines site have been disposed of at the ERDF through July 2000. Cleanup verification sampling began on April 3, 2000, and was finished on August 8, 2000. The ground surface in the vicinity of the site varies with an average elevation of approximately 134.4 meters (441 feet).

Code: UPR-100-D-5	Classification: Accepted
Names: UPR-100-D-5; Effluent Line Leak #4	Reclassification: Interim No Action (10/14/2010)
Type: Unplanned Release	Start Date: 1/1/1951
Status: Inactive	End Date:

Description: The waste site has been evaluated and determined to require No Action. It was an event of extensive leakage from the 107-DR retention basin. In 1951, the area was marked with a rope fence and posted as a radiation area. Currently, the area can not be separately distinguished in the gravel retention basin area.

Location: The site is located southeast of 107-DR Basin.

Release Description: In 1951, extensive leakage of effluent was detected above ground southeast of the 107-DR Basin (116-DR-9). A maximum dose rate of 50 millirads/hour was observed at the surface. Two excavations were made to investigate the leakage, but the effluent continued to seep to the surface.

Waste Type: Water

Waste Description: The release consisted of radioactively contaminated effluent from reactor cooling water. Pipeline leaks contaminated the soil around the effluent lines. Potential contaminants include Co-60, Cs-134, Cs-137, Eu-152,154,155; H-3, Pu-238, 239, 240; Am-241, Sr-90 and U-235.

Closure Info: Interim: Remediation occurred between March 7 and April 3, 2008. Approximately 4,485 bank cubic meters (5,586 bank cubic yards) of soil was excavated and stockpiled adjacent to the site. No radiological contamination was detected in the excavated material. Therefore, no soil was taken to the Environmental Restoration Disposal Facility. The excavation is approximately 4.6 meters (15 ft) deep and 30.5 meters (100 ft) long with variable width.

Based on field observations during excavation; the absence of field detectable contamination associated with a retention basin leak and the lack of documentation other than a site location in a historical drawing (GE 1964), it is suspected that an effluent leak may never have occurred. An alternative possibility is that previous remedial actions associated with the 107-D and 107-DR retention basins, sludge trenches, and other effluent leaks may have removed any residual contamination.

100-DR-2

Code: 100-D-12 **Classification:** Accepted
Names: 100-D-12; Sodium Dichromate/Acid Railcar and Truck Unload Station and Associated French Drain; Undocumented Liquid Waste Site **Reclassification:** Interim Closed Out (10/23/2000)
Type: Pump Station **Start Date:**
Status: Inactive **End Date:**

Description: The site has been remediated and was Interim Closed Out on October 23, 2000. It is no longer marked or posted. Before remediation, the site appeared as a small concrete pad with an adjacent, 0.9 meters (3 feet) diameter concrete pipe french drain that supported the flushing and draining of lines that were connected to railroad tank cars.

Location: The 100-D-12 site was located in the 100-D Area next to the 184-D building and the railroad track. It was approximately 710 meters (2,329 feet) from the Columbia River.

Release Description: Spills and hose drainage were routinely discharged to the french drain.

Process Description: Undiluted sodium dichromate and acid solutions were pumped through underground lines to storage tanks located outside the 185-D and 190-DR facilities. Prior to remediation, the site appeared as a small concrete pad enclosed by a curb. The containment area drained to an adjacent concrete pipe french drain that supported the flushing and draining of lines that were connected to railroad tank cars. The majority of the spills and hose drainage were routinely discharged to the french drain. Undiluted volumes of sodium dichromate and acid solutions were spilled directly to the soil column at this location.

Waste Type: Chemical Release

Waste Description: Wastes consisted of sodium dichromate and sulfuric acid.

Closure Info: Interim (10/23/2000): Remedial action at the site began on November 8, 1999 and involved removing the overburden, the contaminated drain structure and the underlying contaminated soil. The activity was completed on April 19, 2000 when the excavation reached the design limit at El. 140.1 meters (460 feet).

At the completion of remedial action and removal of the engineered structure, the excavation was approximately 202.5 square meters (2,180 square feet) in area with a maximum depth of approximately 2.4 meters (7.9 feet). Approximately 34.5 metric tons (38 tons) of contaminated material were disposed at ERDF.

Code: 100-D-13 **Classification:** Accepted
Names: 100-D-13; 100DR Area Sewage Disposal Unit; 124-DR-3; 1607-DR3; Septic Tank D-13; Unnumbered Septic System A **Reclassification:** Interim Closed Out (9/13/2012)
Type: Septic Tank **Start Date:** 1/1/1947
Status: Inactive **End Date:** 1/1/1949

Description: The waste site was evaluated and reclassified to Interim Closed Out. It is a septic system installed for use during the construction of the 105-DR Reactor. The contents of the Imhoff tank were treated, solidified, and then removed and disposed at Environmental Restoration

Disposal Facility. The tank was filled with soil. The entire dosing tank was removed and the area backfilled with soil. All materials were directly loaded for disposal at the ERDF.

The system consisted of an IMHOFF tank, a chlorination house, a dosing tank, a filter bed, and associated piping. The septic tank is surrounded by a steel pipe fence. The filter bed is distinguishable as a rock-filled depression with distribution piping visible on the surface.

Location: The septic tank is approximately 240 meters (800 feet) east-southeast of the of 105-DR, south of the power line road. The filter bed is approximately 120 meters (400 feet) east of the tank on the north side of the road. The pipeline that flows to the tank has been mapped from the 117-DR Building, and surrounds the 105-DR Building, but no connection to the reactor has been found on drawings.

Waste Type: Sanitary Sewage

Waste Description: The tank received sanitary waste from temporary construction facilities at 105-DR. The 100-D Area Technical Baseline Report indicates that the tank also received overflow from the high tanks (water towers) at 105-DR, but no drawings could be found to verify this. The tank may have also received waste from the 105-DR Reactor (see Site Comment), so radioactive contamination may be present.

Closure Info: Interim (9/13/2012): Confirmatory sampling of the 100-D-13 waste site was conducted on July 11 and 12, 2005. The septic tank was discovered to contain residual free liquid and sludge, and appropriate waste characterization samples were collected. Confirmatory samples were collected from surface and underlying soils at the filter bed. On August 18, 2010, an additional pipeline sample was collected in order to characterize the pipeline between the septic tank and dosing tank and to confirm that no contamination was present between the septic tank and the dosing tank. The sample results indicated that the 100-D-13 waste site achieved compliance with the remedial action objectives and goals (RAOs) and RAGs. Therefore remediation was not necessary.

The liquid levels in the septic tank observed on August 18, 2010 were compared to the liquid levels observed during the confirmatory sampling effort in 2005. The liquid level check confirmed that the tank had not leaked any fluids since 2005. The lid of the tank was removed during the efforts to appropriately disposition the residual tank contents. The contents of the tank were treated, solidified, and then removed and disposed at Environmental Restoration Disposal Facility. The septic tank was filled with soil.

The Imhoff tank extended down to 7.3 meters (24 ft) below ground surface. To completely remove the solidified liquids from the tank, the top portion of the tank had to be broken off and removed. An engineered excavation was designed in order to access and appropriately disposition the septic tank. Approximately 885 bank cubic meters (BCM) (1,159 bank cubic yards [BCY]) of solidified liquid and septic tank components were removed from the excavation and staged in the staging pile area before being loaded for disposal at the ERDF.

In January 2011, the smaller dosing tank was uncovered to perform visual observation of the tank contents. The wooden lid was found to be partially deteriorated. Rainwater collection inside the tank was expected. The dosing tank was partially backfilled with soil. It contained a small amount of water in two corners of the tank. On March 14, 2011, the dosing tank was removed and disposed. The dosing tank measured to be approximately 10 feet by 5 feet by 8 feet. The entire dosing tank was removed, resulting in approximately 100 BCM (131 BCY) of dosing tank components, backfill materials and soil. All materials were directly loaded for disposal at the ERDF.

On March 14, 2011, following the removal of the dosing tank, three soil samples were collected from soils underlying the dosing tank.

Code:	100-D-14	Classification:	Accepted
Names:	100-D-14; Unnumbered Septic System (b); Unnumbered Septic Tank #2	Reclassification	Interim Closed Out (10/17/2012)
Type:	Septic Tank	Start Date:	
Status:	Inactive	End Date:	
Description:	The waste site has been remediated and Interim Closed Out. It had been a vegetation-covered field with a small depression that may have indicated the location or presence of the tank. A 10-centimeter (4-inch) cement vent pipe to the drain field was visible.		
Location:	The tank location was located south of the 105-DR Building, outside the 100-D perimeter fence and north of Route 2 North.		
Waste Type:	Sanitary Sewage		
Waste Description:	The unit received sanitary wastes.		
Closure Info:	<p>Interim (10/17/2012): Confirmatory sampling at the 100-D-14 waste site was conducted on January 4, 2006, and July 11, 2007. On January 4, 2006, excavation of a 4 inch vertical concrete pipe, the only feature visible at the surface, showed that the pipe extended approximately 1 meters (3 ft) below ground surface to an elbow connected to a concrete pipeline extending to the east. Approximately 6 meters (20 ft) of this pipeline was excavated. No perforations or other features suggestive of a drain field were discovered. Following this excavation, evidence was discovered that indicated the septic tank location was in a different orientation, farther east of the originally assumed location. Excavation at the suspect septic tank location on July 11, 2007, revealed a suspected influent vitrified clay pipe (VCP) and suspected effluent VCP that was belled at one end (consistent with the configuration for connection to a tank). A gap of approximately 5 meter (16.4 ft) between the two pipes indicated that the septic tank had been removed. Based on the confirmatory data evaluation, residual concentrations of nitrate (as nitrogen), DDE, and DDT exceeded the soil remedial action goals (RAGs) for the protection of groundwater and/or the Columbia River.</p> <p>Remediation of the 100-D-14 waste site was performed from March 28 through March 29, 2012. Approximately 936 bank cubic meters (1,224 bank cubic yards) of excavated materials were removed and stockpiled in a staging pile area west of the excavation prior to disposal at the Environmental Restoration Disposal Facility. The lowest depth of the waste site excavation was approximately 4.6 meters (15 ft) at the location of the former drain field. No septic tank or anomalous materials were encountered during the excavation. No overburden material was associated with the waste site.</p>		

Code:	100-D-15	Classification:	Accepted
Names:	100-D-15; Debris North of 100-D Area Perimeter Road and Debris South of 100-D Perimeter Road Within Gravel Pit #21 (100-D-55); Debris Within Pit 21	Reclassification	Interim Closed Out (9/16/2010)
Type:	Dumping Area	Start Date:	
Status:	Inactive	End Date:	
Description:	100-D-15 has been remediated and Interim Closed Out. The site consisted of two separate areas containing debris. The northern area of the site contained debris consisting of concrete rubble, metallic and asphalt debris, and other inert materials. Potential asbestos-containing materials		

were also found to be present. The southern area of the 100-D-15 waste site was used as a disposal location for sediment that was removed during the cleanout of the 182-D Basin. The sediment was observed to contain clamshells and clumps of asphalt-type sealant used in the 182-D Basin.

Location: There were two solid waste disposal pits containing debris located south of 100-D Area near the perimeter road. One disposal area was located north of the perimeter road and west of the railroad track. The other disposal area was south of the perimeter road, inside Gravel Pit #21 (site code 100-D-55).

Related Sites/ Structures: The site is associated with Gravel Pit #21 (100-D-55).

Process Description: The 100-D Area Technical Baseline Report states that this location contains construction debris consisting of concrete rubble, metallic materials, asphalt material, and broken floor tiles (potentially asbestos-containing). The site was also reportedly used to dispose of empty cans formerly containing oil and cleaning solvents from Army sites located northeast of the 100-D Area.

Waste Type: Construction Debris

Waste Description: The southern pit contains construction debris including concrete, metal, asphalt, and other debris. Asbestos may be present. The exact contents of the debris are unknown. In August 1994, Kaiser Engineers Hanford (KEH) removed sediments from the 182-D River Water Basins and deposited the material in the east end of the pit over part of the existing waste site. This disposal option was chosen rather than the demolition landfill option because the sediment did not meet the demolition landfill acceptance criteria. In a September 1997 memo, it was determined that the material classified as "clean soils or clean dredge soils" as defined in Washington Administrative Code (WAC) 173-304 definition that "Clean soils or clean dredge soils" means soils which are not dangerous waste or problem wastes. This classification excludes material from regulation and requires no specific management or disposal requirements. Therefore, there is no requirement to dispose of the material in any type of permitted landfill.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: The northern pit is assumed to be the older of the two pits. The pit has been reported to have been used as a disposal site for empty cans collected from army sites located northeast of the 100-D Area. Army wastes could include oil cans, solvent cans, and other miscellaneous solid wastes. Asbestos may be present. The exact contents of the debris is unknown.

Closure Info: Interim: The northern area of the site contained debris consisting of concrete rubble, metallic and asphalt debris, and other inert materials. Potential asbestos-containing materials (floor tiles) were also found to be present. The southern area of the 100-D-15 waste site was used as a disposal location for sediment that was removed during the cleanout of the 182-D Basin. The sediment was observed to contain clamshells and clumps of asphalt-type sealant used in the 182-D Basin. Remediation included removing a layer of underlying soil.

Remedial action at the site was performed between October 6 and December 1, 2008. The northern location was excavated to a depth ranging from 2 meters (6.6 ft) to 4 meters (13 ft) below grade. The southern location was excavated to a depth of 3.5 meters (11.5 ft) below grade. Approximately 9,198 bank cubic meters (BCM) (10,059 bank cubic yards [BCY]) of soil and debris were removed from the north area, and 4,003 BCM (4,378 BCY) was removed from the south area. All material was direct loaded for disposal at the Environmental Restoration Disposal Facility. Two pot holes were dug to a depth of 1.2 meters to 1.5 meters (4 to 5 feet) No material was found in the first pot hole, but roofing material was found in the second pot hole. A decision was made to remove this layer of debris.

Code: 100-D-23 **Classification:** Accepted
Names: 100-D-23; 119-DR Sample Building Drywell **Reclassification:** Interim Closed Out (3/4/2004)
Type: French Drain **Start Date:** 1/1/1959
Status: Inactive **End Date:**

Description: The site has been remediated and Interim Closed Out. The site was a drywell that received drainage from a floor drain in the 119-DR Sample Building.

Location: The drywell was located south of the 119-DR Sample Building, between the intake and exhaust ducts for the 117-DR Filter Building.

Related Sites/ Structures: The drywell was associated with the 119-DR Sample Building.

Process Description: The 119-DR Sample Building was situated over the intake and exhaust ducts to the 117-DR Filter Building and was used to sample effluent gases and particulates. The 119-DR Sample Building Drywell was connected to the facility by a 5-centimeter (2-inch) drainage pipe buried at least 0.9 meters (3 feet) below grade. A 1.9-centimeter (3/4-inch) drain line from the building's evaporative cooler connected into the 5-centimeter (2-inch) drain line near the southern edge of the building.

Waste Type: Process Effluent

Waste Description: The drain received effluent from the building's evaporative cooler. It is likely that the drain also received sample waste and janitorial waste since the building had no other drains or connections to the process sewer system.

Closure Info: Interim: Note - The 105-DR reactor operated between 1950 and 1964 for plutonium production. In 1973, the exhaust system portions of the 105-DR reactor were reactivated and re-purposed to support the Large Sodium Fire Facility (LSFF). The LSFF (sitecode 122-DR-1) was a RCRA TSD. Most of the components of the reactor exhaust system have two entries in the WIDS database, one representing the CERCLA (radioactive) contaminants and the other representing the RCRA hazardous chemical contaminants.

The portions of the LSFF TSD that are included in this remedial activity are the 117-DR Exhaust Filter Building (100-D-53/122-DR-1:4), the underground exhaust tunnel (122-DR-1:2), the 119-DR Exhaust sample building (100-D-64), two dry wells (100-D-23 and 100-D-54) and the 116-DR Exhaust Stack (132-DR-2/122-DR-1:5) Four of the seven 122-DR-1 subsites (122-DR-1:1, 122-DR-1:3, 122-DR-1:6 and 122-DR-1:7) were closed out under the 105-DR Large Sodium Fire Facility RCRA Closure Plan (LSFF Closure Plan) are were not discussed in the CVP-2003-00018 Cleanup Verification Package.

The remedial objective for the structures was to remove each structure to a minimum of 0.9 meters (3 feet) below surface grade. In July 2003, remedial/removal action activities removed the 117-DR Exhaust Filter Building (100-D-53/122-DR-1:4), the downstream (post-filter) tunnel and the additional 0.9 meters (3 ft) of the 116-DR Reactor Exhaust Stack (132-DR-2/122-DR-1:5). The aboveground portion of the 132-DR stack had been demolished in 1999.

Large Sodium Fire Facility (LSFF) subsite 122-D-1:2 (underground tunnel between the 105-DR Building) and the 117-DR Exhaust Filter Building were entirely removed. The 315 and 316 exhaust plenums, (aka upper and lower exhaust tunnels) are also associated with the 122-D-1:2 subsite. The upper exhaust tunnel and approximately the top 0.9 meters (3 ft) of the lower exhaust tunnel were removed. The 119-DR Exhaust Stack Sampling Building and two stack sampling building dry wells (100-D-23 and 100-D-64) were also demolished and excavated as part of the remedial/removal action activities in July 2003.

At the completion of the remedial action, the total excavation was approximately 1,010 square meters (10,872 square feet) in area with an approximate depth of 5 meters (16.4 feet). Approximately 14,011 metric tons (15,412 tons) of material from the site were disposed of at the Environmental Restoration Disposal Facility.

Code: 100-D-27 **Classification:** Accepted

Names: 100-D-27; 151-D Substation UPR; A-2 Substation Transformer #A401C Leak **Reclassification:** Closed Out (8/4/2005)

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The site has been reclassified to Closed Out. The site consisted of an unplanned release of less than 100 gallons of PCB oil within the 151-D Substation. The transformer was power washed, the contaminated material was shoveled into seven 208 liter (55 gallon) drums, and the site was backfilled.

Location: The release occurred at the #A401C transformer, located in the 151-D Substation. The substation is west of the 105-DR Reactor and southwest of the 105-D Reactor.

Release Description: During a routine inspection of the 151-D substation, a non-PCB oil leak was discovered. Occurrence report RL--WHC-KHELEC-1995-0013 was issued.

Waste Type: Oil

Waste Description: The release was less than 100 gallons (380 L) of non-PCB mineral oil. According to a transformer inventory, oil in the #A401C transformer contains 42.0 parts per million PCBs.

Closure Info: Final: The oil leak occurred in June 1995. The transformer was power washed, the contaminated material was shoveled into seven 208 liter (55 gallon) drums, and the site was backfilled. The drums were taken to a staging area.

Waste Site Reclassification form 2005-014 states the spill was less than 100 gallons of 42 ppm PCB oil. Therefore, no more than 0.016 kilogram PCB would have been released, significantly less than the CERCLA RQ of 0.45 kilogram (1 pound). The remedial action objectives and remedial action goals in the Remedial Design Report/Remedial Action Work Plan for the 100 Area and the Interim Action Record of Decision for the 100-BC-1, 100-BC-2, 100-DR-1, 100-DR-2, 100-FR-1, 100-FR-2, 100-HR-1, 100-HR-2, 100-KR-1, 100-KR-2, 100-IU-6, and 200-CW-3 Operable Units, Hanford Site, Benton County, Washington (EPA 1999) are therefore not applicable to the 100-D-27 waste site. The site will support future unrestricted land uses that can be represented (or bounded) by a rural-residential scenario and no institutional controls are required.

Code: 100-D-28 **Classification:** Accepted

Names: 100-D-28; 190-DR Building Septic System **Reclassification:** Interim Closed Out (10/11/2011)

Type: Septic Tank **Start Date:**

Status: Inactive **End Date:**

Description: The site consists of two septic systems, the original septic and the replacement. See the subsites for more detail.

Location: The unit is located southwest of the 190-DR Building.

Related Sites/ Structures: 190-DR Building and Annex

Process Description: The system processed and disposed of septage from the 190-DR Main Pump House. The 190 DR Building housed the pumps and related equipment used to supply the 105-DR Reactor with cooling water from the 183 DR Clearwells. Until August 2004, part of this building was also used for the storage of radiological material. A confirmatory radiological survey of the area following removal of the material located no contamination (RSR-105DR-04-0077).

Waste Type: Sanitary Sewage

Waste Description: The system received sanitary wastes.

This Site has the Following SubSites:

Code: 100-D-28:1

Names: 100-D-28:1; Replacement Septic System

Code: 100-D-28:2

Names: 100-D-28:2; Original Septic System

Code: 100-D-28:1

Classification: Accepted

Names: 100-D-28:1; Replacement Septic System

Reclassification: Interim Closed Out (10/11/2011)

Type: Septic Tank

Start Date:

Status: Inactive

End Date:

Description: The 100-D-28:1 subsite has been remediated and Interim Closed Out. It consisted of a septic tank and drain field located approximately 25-meters (82-feet) southwest of the 190-DR Building. The septic system included a 2,730 liters (720-gallons) steel tank and a vitrified clay pipe drain field due west of the septic tank used in association with the 190-DR Building.

The 190-DR Annex constructed in 1955 added approximately 21.3 m (70 ft) to the east side of the 190-DR Building. The 190-DR Annex is approximately 3 m (10 ft) below grade. Photographs from 1955 (see attachment) show the depth and amount of disturbance for the excavation of the annex. It does not appear that this septic tank and tile field could have survived the construction of the 190-DR Annex. Likely a new septic system (100-D-28:1) was installed per drawing H-9923 southwest of the 190-DR as a replacement system.

Location: The septic system was located approximately 25 m (82 ft) southwest of the former 190-DR Building. The drain field is centered at E573491.6, N151105.6 and the septic tank at E573498.7, N151104.8.

Process Description: The system processed and disposed of sewage from the 190-DR Main Process Water Pumphouse.

Waste Type: Not Specified

Waste Description: The waste would be septage from the 190-DR Main Pump House.

Closure Info: Interim (10/11/2011): Remedial action at the 100-D-28:1 subsite was performed between July 27 and August 17, 2010. Additional remediation was conducted on March 17, 2011 due to residual contamination identified following verification sampling activities. The excavation continued to a maximum depth of 5 meters (16 ft) until all contaminated soil and debris associated with the waste site had been removed. Approximately 2,760 bank cubic meters

(BCM) (3,610 bank cubic yards [BCY]) of contaminated soil and debris were removed from the excavation and staged in a staging pile area (SPA) to the north of the excavation before being loaded for disposal at the Environmental Restoration Disposal Facility (ERDF). Approximately 1,275 BCM (1,668 BCY) of overburden material was stockpiled for use as clean backfill. However, verification sampling found unacceptable contaminant concentrations and after additional remediation and resampling, contamination was still present above direct exposure remedial action goal (RAGs); therefore, the entire overburden soil stockpile was loaded out for disposal at the ERDF between April 20 and 21, 2011.

Three miscellaneous pipeline sections were encountered during remediation of the 100-D-28:1 subsite. Two of the pipeline sections found are part of the 100-D-50:6 pipeline subsite and one section is part of the 100-D-63 pipeline site. The 100-D-50:6 and 100-D-63 pipelines will be addressed separately from the 100-D-28:1 subsite.

The debris removed from the 100-D-28:1 subsite consisted of contaminated soil, concrete, and piping associated with the septic tank and drain field. No anomalous material was encountered during excavation.

The SubSite is Part Of:

Code: 100-D-28

Names: 100-D-28; 190-DR Building Septic System

Code: 100-D-28:2

Classification: Accepted

Names: 100-D-28:2; Original Septic System

Reclassification: Rejected (8/1/2005)

Type: Septic Tank

Start Date:

Status: Inactive

End Date:

Description: The 100-D-28:2 site consisted of a septic tank and drain field located approximately 15.2-meters (50-feet) from the northeast side of the original 190-DR Pump House. The tank capacity was 2,839-liters (750-gallons). The 190-DR Annex constructed in 1955 added approximately 21.3-meters (70-feet) to the east side of the 190-DR Building. It does not appear that the 100-D-28:2 septic tank and tile field could have survived the construction of the 190-DR Annex. The 100-D-28:1 septic system was installed per drawing H-9933-DR on the southwest side of the 190-DR Building as a replacement system.

The 190-DR Annex constructed in 1955 added approximately 21.3 meters (70 feet) to the east side of the 190-DR Building. The 190-DR Annex is approximately 3 meters (10 feet) below grade. Photographs from 1955 (see attachment) show the depth and amount of disturbance for the excavation of the annex. It does not appear that this septic tank and tile field could have survived the construction of the 190-DR Annex. Likely a new septic system (100-D-28:1) was installed per drawing H-9923, southwest of the 190-DR as a replacement system.

Based on the historical documentation, the 100-D-28:2 septic system has not existed or been used in over 50 years. A reclassification status of Rejected has been assigned for the 100-D-28:2 septic system. The site achieved the remedial action objectives and the corresponding remedial action goals established in the Remedial Design Report/Remedial Action Work Plan for the 100 Area and the Interim Action Record of Decision for the 100-BC-1, 100-BC-2, 100-DR-1, 100-DR-2, 100-FR-1, 100-FR-2, 100-HR-1, 100-HR-2, 100-KR-1, 100-KR-2, 100-IU-6, and 200-CW-3 Operable Units, Hanford Site, Benton County, Washington. The site will support future unrestricted land uses that can be represented (or bounded) by a rural-residential scenario and no institutional controls are required.

Location: This subsite is located approximately 15.2 m (50 ft) from the northeast side of the original 190-

DR Pump House.

Waste Type: Not Specified

Waste Description: No cleanup was performed at this site.

The SubSite is Part Of:

Code: 100-D-28

Names: 100-D-28; 190-DR Building Septic System

Code: 100-D-43

Classification: Accepted

Names: 100-D-43; 118-D-4C; Burial Ground 4C; Buried VSR Thimble Site

Reclassification: Interim Closed Out (5/13/2010)

Type: Burial Ground

Start Date:

Status: Inactive

End Date:

Description: The waste site has been remediated and Interim Closed Out. It was a solid waste burial ground. The 100-D-42, 100-D-43, and 100-D-45 waste sites were located in the same area and were remediated as one decision unit. The burial ground was in very close proximity to the (exhumed) 152-centimeter (60-inch) effluent lines.

Location: The site is located east of the 105-D Reactor Building, outside the reactor security fence and south of the railroad spur that services 105-D.

Waste Type: Equipment

Waste Description: The waste is a buried Vertical Safety Rod (VSR) thimble. The VSR thimbles were made of aluminum similar to the that used in the process tubes and should contain similar isotopic composition. Sampling of process tubes was conducted in March 1967. The radionuclide levels, when decay corrected by Dorian and Richards to March 1977, were 5.9E+03 picocuries of manganese-54 per gram of aluminum and 2.5E+07 picocuries of cobalt-60 per gram of aluminum. When buried, the thimble's exterior surfaces would also have been contaminated with activated graphite products and potassium borate.

Closure Info: Interim: The 100-D-42, 100-D-43, and 100-D-45 waste sites were located in the same area and were remediated as one decision unit. Remedial action at the sites began on September 6, 2007, and was completed on April 22, 2008. Contaminated soil and debris were excavated and removed from the burial grounds for shipment to ERDF. Field observations during excavation indicated the presence of VSR thimbles in two of the three burial grounds. Only concrete debris and plastic sheeting were found to be present in the 100-D-42 Burial Ground. The 100-D-43 Burial Ground contained VSR thimbles and other reactor hardware. Mastic, aluminum pipe, VSR thimbles, reactor hardware, and a drum containing rags were found in the 100-D-45 Burial Ground. Due to the close proximity to each other and the type of debris encountered during excavation, the three sites were included in one CVP and interim closed out as one decision unit.

Remedial action at the 100-D-45 Burial Ground began on September 6, 2007, with the removal of 930 bank cubic meters (BCM) (1,216 bank cubic yards [BCY]) of overburden material. Excavation began on September 11, 2007 and continued through July 23, 2008 to a depth of approximately 7 meters (23 ft) resulting in approximately 2,605 BCM (3,407 BCY) of contaminated soil and debris removed for disposal at ERDF. Remedial action at the 100-D-43 Burial Ground began on September 10, 2007, with the removal of 165 BCM (216 BCY) of overburden material. Excavation began on September 25, 2007 and continued through October 10, 2007, to a depth of approximately 5 meters (16 ft), resulting in approximately 803 BCM

(1,050 BCY) of contaminated soil and debris removed for disposal at ERDF. Remedial action at the 100-D-42 Burial Ground began on April 22, 2008, with the removal of 495 BCM (647 BCY) of overburden material. Excavation of the burial ground was initiated on April 25, 2008 and continued through May 13, 2008, to a depth of approximately 5 meters (16 ft), resulting in approximately 530 BCM (693 BCY) of contaminated soil and debris removed for disposal at ERDF.

A geophysical survey was conducted in June 2004 at the 100-D-42, 100-D-43, and 100-D-45 Burial Ground locations, and an additional survey was conducted at the 100-D-45 Burial Ground location in September 2004. No notable features with the characteristics of an excavated area or buried debris were detected at the documented location of the 100-D-42 site. Immediately to the south of the 100-D-42 Burial Ground was an area with distinct excavation boundaries and notable concentrations of anomalies with the characteristics of buried debris. This area correlates more closely with the documented locations of the 100-D-43 and 100-D-45 Burial Grounds. One anomaly was encountered in the 100-D-43 Burial Ground. A 57 liter (15 gal) metal container partially filled with liquid was found during excavation. The container was found to have been breached and the contained liquid is suspected to have been water used for dust suppression during excavation activities. No suspect spent nuclear fuel was present in the burial grounds.

The excavation area has a maximum depth of approximately 7 meters (23 ft). However, the entire excavation area is considered one decision unit and meets the more restrictive shallow zone cleanup criteria.

Code:	100-D-46	Classification:	Accepted
Names:	100-D-46; 118-D-4A; Burial Ground 4A	Reclassification	Interim Closed Out (3/1/2001)
Type:	Burial Ground	Start Date:	
Status:	Inactive	End Date:	
Description:	This site has been remediated and Interim Closed Out along with the excavation for the 116-D-1A and 116-D-1B Trenches. The waste site was a 19 by 59-meter (62 by 195-foot) construction burial ground that was co-located with the 116-D-1A and 116-D-1B Trenches. The referenced Hanford drawings refer to the site only as Burial Ground No. 4A.		
Location:	The site was approximately 30 meters (100 feet) east of the 105-D Reactor Building.		
Related Sites/ Structures:	This burial ground received debris from the 105-D Reactor.		
Process Description:	The 100-D-46 site received radioactive and nonradioactive solid wastes and construction debris generated from various reactor modifications from the 105-D Reactor.		
Waste Type:	Construction Debris		
Waste Description:	Potential contaminants include: Co-60, Ni-63.		
Closure Info:	Interim: The 116-D-1A and 116-D-1B Storage Basin Trenches received contaminated water and sludge from the 118-D-6 Fuel Storage Basin. The 100-D-46 Burial Ground received solid waste and construction debris from modifications made to 105-D after 1967 and was co-located with the trenches. The three waste sites were remediated together, with the documentation presented in the same Cleanup Verification Package (CVP-2000-00010). The document referred to the collective three waste sites as the 116-D-1A/116-D-1B site.		

The selected remedial action for the 116-D-1A/116-D-1B sites included (1) excavating the site to the extent required to meet specified soil cleanup levels, (2) disposing of contaminated excavation materials at the Environmental Restoration Disposal Facility at the 200 Areas of the Hanford Site, and (3) backfilling the site with clean soil to average adjacent grade elevation. Excavation was driven by remedial action objectives for direct exposure, protection of groundwater, and protection of the Columbia River. For the respective points of compliance, RAGs were established to identify radionuclide and nonradionuclide contaminants of concern (COCs) and contaminants of potential concern (COPCs). Waste site COCs and COPCs identified through process knowledge were listed in the 100 Area Remedial Action Sampling and Analysis Plan (DOE/RL-96-22).

Remedial action at the 116-D-1A/116-D-1B site began on October 21, 1999. Excavation of the site involved removing the overburden materials, the contaminated structure, and underlying contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Materials that were found to be contaminated were disposed of at ERDF. On July 11, 2000, the excavation reached the design limit at El. 138.4 m (454 ft).

At the completion of the remedial action, the total excavation was approximately 2,648 square meters (28,470 square feet) in area with a maximum depth of approximately 4.6 meters (15 feet). Approximately 10,987 metric tons (12,111 tons) of material from the site were disposed of at the Environmental Restoration Disposal Facility (ERDF).

Code:	100-D-47	Classification:	Accepted
Names:	100-D-47; 118-D-4E; Burial Ground 4E; Construction C.G. 558-Rod Burial	Reclassification	Interim Closed Out (1/15/2010)
Type:	Burial Ground	Start Date:	
Status:	Inactive	End Date:	
Description:	100-D-47 has been remediated and interim Closed Out. It was located within the 118-D-4 cobble field, but was not separately marked. Following remediation activities, the project was authorized to remove radiological postings.		
Location:	The site is located east of the 105-D Reactor Building, outside the reactor exclusion area fence and south of the railroad spur that services the reactor building. The burial ground is west of Burial Ground 4F (118-D-4) and south of Minor Construction Burial Ground #5 Pit (100-D-40) and Trench (100-D-41).		
Process Description:	The site is a burial ground used to dispose of fuel rod waste during project CG-558.		
Waste Type:	Equipment		
Waste Description:	The site is described as a rod burial site. The type and quantity of rods disposed of at this site is not known. Potential contaminates include: C-14, Co-60, Ni-63, H-3, Nb-94, Ni-59, Pd-102, Sm-151, Tc-99, Am-241, Ag-108m, Ba-133, Cs-137, Eu-152 and 154, Pu-238, 239 and 241, Ca-41, Cd-113m, Kr-85, Zr-93, cadmium, lead.		
Closure Info:	Interim: Remedial action began on January 16, 2008, and continued through March 20, 2008. A total of approximately 2,800 bank cubic meters (BCM) (3,660 bank cubic yards [BCY]) of material was removed for disposal at ERDF. Approximately 247 BCM (323 BCY) of overburden and layback was stockpiled for use as clean fill. The material excavated was consistent with the burial of scrap (piping, concrete, valves, etc.) from miscellaneous equipment modifications accomplished during Project CG-558. The horizontal control rods, if present,		

were not distinguishable from the other debris.

Code: 100-D-54	Classification: Accepted
Names: 100-D-54; Drywell Near the Large Sodium Fire Facility Gravel Scrubber	Reclassification Interim Closed Out (3/4/2004)
Type: French Drain	Start Date:
Status: Inactive	End Date:

Description: The site has been remediated and Interim Closed Out. The site was a 56-centimeter (28-inch) drywell. It was constructed of concrete pipe and had a steel cover. When opened during a field visit, the drywell was found to be approximately 1.5 meters (4.9 feet) deep with a 5-centimeter (2-inch) pipe entering it near the bottom on the east side.

Location: The site was located approximately 5.5 meters (18 feet) southwest of the southwest corner of the 119-DR Sample Building.

Related Sites/ Structures: This dry well is associated with waste site 122-DR-1:3 (Large Sodium Fire Facility Gravel Scrubber).

Closure Info: Interim: Note - The 105-DR reactor operated between 1950 and 1964 for plutonium production. In 1973, the exhaust system portions of the 105-DR reactor were reactivated and re-purposed to support the Large Sodium Fire Facility (LSFF). The LSFF (sitecode 122-DR-1) was a RCRA TSD. Most of the components of the reactor exhaust system have two entries in the WIDS database, one representing the CERCLA (radioactive) contaminants and the other representing the RCRA hazardous chemical contaminants.

The portions of the LSFF TSD that are included in this remedial activity are the 117-DR Exhaust Filter Building (100-D-53/122-DR-1:4), the underground exhaust tunnel (122-DR-1:2), the 119-DR Exhaust sample building (100-D-64), two dry wells (100-D-23 and 100-D-54) and the 116-DR Exhaust Stack (132-DR-2/122-DR-1:5) Four of the seven 122-DR-1 subsites (122-DR-1:1, 122-DR-1:3, 122-DR-1:6 and 122-DR-1:7) were closed out under the 105-DR Large Sodium Fire Facility RCRA Closure Plan (LSFF Closure Plan) are were not discussed in the CVP-2003-00018 Cleanup Verification Package.

The remedial objective for the structures was to remove each structure to a minimum of 0.9 meters (3 feet) below surface grade. In July 2003, remedial/removal action activities removed the 117-DR Exhaust Filter Building (100-D-53/122-DR-1:4), the downstream (post-filter) tunnel and the additional 0.9 meters (3 ft) of the 116-DR Reactor Exhaust Stack (132-DR-2/122-DR-1:5). The aboveground portion of the 132-DR stack had been demolished in 1999.

Large Sodium Fire Facility (LSFF) subsite 122-D-1:2 (underground tunnel between the 105-DR Building) and the 117-DR Exhaust Filter Building were entirely removed. The 315 and 316 exhaust plenums, (aka upper and lower exhaust tunnels) are also associated with the 122-D-1:2 subsite. The upper exhaust tunnel and approximately the top 0.9 meters (3 ft) of the lower exhaust tunnel were removed. The 119-DR Exhaust Stack Sampling Building and two stack sampling building dry wells (100-D-23 and 100-D-64) were also demolished and excavated as part of the remedial/removal action activities in July 2003.

At the completion of the remedial action, the total excavation was approximately 1,010 square meters (10,872 square feet) in area with an approximate depth of 5 meters (16.4 feet). Approximately 14,011 metric tons (15,412 tons) of material from the site were disposed of at the Environmental Restoration Disposal Facility.

Code: 100-D-62 **Classification:** Accepted
Names: 100-D-62; 183-DR Headhouse Septic Tank **Reclassification:** Interim Closed Out (10/16/2013)
Type: Septic Tank **Start Date:**
Status: Inactive **End Date:**

Description: The septic system has been remediated and Interim Closed Out. It included the septic tank, drain field and associated piping. It received sanitary sewage from the 183-DR headhouse. The entire 183-DR water treatment facility is a non-radiological area, therefore, the 100-D-62 septic system waste site is not considered radiologically contaminated. This system was designed for the use of 6 people with a 2,271 liter (600 gal) capacity.

Location: The septic system was located about 15.2 meters (50 ft) south of the 183-DR Head House and west of the 183-DR Flocculation Basin. The drain field extended 6.1 meters (20 ft) from the south end of the septic tank.

Related Sites/ Structures: The site was associated with the 183-DR Head House.

Process Description: The 100-D-62 septic system waste site received sanitary sewage from the 183-DR water treatment facility headhouse. The 183-DR water treatment facility was operational from 1952 to 1964, per documentation these facilities were demolished to grade in 1978. The operational period of the septic system is assumed to be the same as the 183-DR facility. The 183-DR water treatment facility filtered and chemically treated raw Columbia River water prior to use to cool components within the 105-DR Reactor. Sulfuric acid, potentially containing impurities such as lead and mercury, was added to raw river water prior to entry into the flocculation basins. Sodium dichromate was added to the water in the filter building to inhibit metal corrosion of reactor components. The 183-DR headhouse served as a receiving, storage, and transfer point for sodium dichromate. Sodium dichromate was received from the 185-D Building into one or more storage tanks located in the equipment room in the northeast corner of the headhouse on the ground floor. The sodium dichromate solution was pumped via an overhead line across the flocculation and sedimentation basins to the eastern end of the filter building. It was then injected into a mixing flume that was located along the eastern side of the building. The 183-DR headhouse was the western most building of the water treatment facility. The building was 34 m by 24 m (110 ft by 80 ft) and supplied an appropriate mixture of chemicals to provide the desired treated water to the reactor. River water entered the headhouse through two 9.1 cm (36 in) diameter steel pipes. The 183-DR headhouse contained inlet control valves, flash mixer chambers, chlorinators, and the ferric sulfate, lime, and silicate storage and feeding equipment used to chemically treat water. The 183-DR headhouse received 10% sodium dichromate solution from the 185-D Building through a 7.6 cm (3 in) diameter pipeline that connected with two tanks, each with a 15,142 L (4,000 gal) capacity. From the storage tanks, two, 1.9 cm (0.75 in) diameter sodium dichromate pipes crossed above the flocculation and sedimentation basins where they entered the sample room and mixing pumps in the filter building.

Waste Type: Sanitary Sewage

Waste Description: The waste is the remaining septic system (tank and piping) and any remaining septage. The Contaminants of potential concern (COPCs) for the 100-D-62 waste site were identified based on existing historical information for the 183-DR water treatment facility and contaminants associated with previously sampled septic systems. The COPCs for the 100-D-62 septic system include constituents associated with the chemicals used in the 183-DR headhouse: chromium, hexavalent chromium, mercury, lead, and anions. Although not COPCs, arsenic, antimony, barium, beryllium, boron, cadmium, cobalt, copper, manganese, molybdenum, nickel, selenium, silver, vanadium, and zinc concentrations will be evaluated by performing the expanded inductively coupled plasma metals analytical list. Based on findings from other septic systems in the 100-D Area, semivolatile organic compounds, pesticides, and polychlorinated biphenyls

are also considered COPCs. Additional COPCs may be identified as part of planning for remedial actions.

Radionuclides are not COPCs for this site. However, the presence of radiological contaminants should be evaluated using field radiological survey instrumentation (capable of detecting alpha, beta, and gamma radiation) during remediation of the septic system. If radiological activity is detected during remediation, the verification sampling work instruction will incorporate specific requirements for radionuclide analysis.

Closure Info: Interim (10/16/2013): Remedial action at the 100-D-62 waste site was conducted on May 2 and 3, 2011. A reinforced concrete septic tank, associated concrete piping, and soil were removed as part of the remediation and staged at the Spoil Pile Areas. Approximately 793 bank cubic meters (BCM) (1,037 bank cubic yards [BCY]) of soil and debris was loaded on July 12 and 13, 2011, for disposal at the Environmental Restoration Disposal Facility (ERDF).

Remedial action at the 100-D-77 waste site began on May 3, 2011, and continued through July 13, 2011. The 100-D-83:1 subsite consisted of the pipeline segments associated with the 183-DR Acid Facility. Most of the pipelines were within the 100-D-77 acid trench and were removed during the 100-D-77 waste site remediation. Remediation continued to a depth of approximately 4.5 meters (15 ft) below ground surface (bgs) resulting in approximately 7,103 BCM (9,290 BCY) of contaminated soil and debris that was removed and staged at the staging pile areas (SPAs) prior to loadout and disposal.

The 100-D-83:1 waste site was inside the 100-D-77 site and was fully removed with the 100-D-77 excavation. Verification samples were collected from these three locations on May 29, 2013.

A 20 meter (65.6 ft) section of the 100-D-56:2 pipelines, located at the entrance into the 183-DR Head House, and the 183-DR Filter Building sample room were also remediated with 100-D-77. Loadout of waste material with subsequent disposal at ERDF was conducted between July 13 and October 18, 2011.

At the completion of the remediation, in-process soil samples were collected on July 6 and July 11, 2011, to determine if additional remediation of the waste site was necessary. Mercury was measured above the direct exposure remedial action goals (RAGs) in the in-process sample data. Based on these results, a second tier (Tier 2) of excavation was designed.

The Tier 2 remediation began on December 8, 2011, and continued through January 16, 2012. Approximately 7,126 BCM (9,320 BCY) of contaminated soil and debris were removed from the excavation and moved to the SPAs for loadout and disposal at ERDF. The excavation depth extended a maximum of 9.5 meters (31 ft) bgs. Loadout of the Tier 2 waste material began on December 14, 2011.

The presence of elevated PAH within the excavation area was attributed to cross-contamination of asphalt. Additional remediation of benzo(a)pyrene at location EXC-3 was a result of cross-contamination with asphalt. Additional soil was removed at and around the sample location (EXC-4) with elevated mercury on March 15, 2013. An additional 76 BCM (100 BCY) of contaminated soil and debris were removed from the excavation and staged prior to disposal at ERDF. The area in which additional removal was performed included the FS-1 sample location. Replacement verification samples were collected at the EXC-4 and FS-1 locations on March 15, 2013.

Contaminated soil, concrete, and rebar from previously demolished buildings, piping, and a brick-lined concrete acid trap were among the types of material removed from the excavation. All materials removed from the 100-D-62, 100-D-77, and 100-D-83:1 excavation were staged at five SPAs prior to loadout and disposal at ERDF.

Code:	100-D-77	Classification:	Accepted
Names:	100-D-77; 183-DR Filter Building; 183-DR Flocculation Basins; 183-DR Head House; 183-DR Sedimentation Basins; Acid Facility; DR Reactor Water Treatment Facility; Sodium Dichromate Systems	Reclassification	Interim Closed Out (10/16/2013)
Type:	Process Unit/Plant	Start Date:	
Status:	Inactive	End Date:	
Description:	<p>The waste site has been remediated and Interim Closed Out. It was the 183-DR Water Treatment Facility. It included the 183-DR filter building, head house, flocculation and sedimentation basins, acid facility and train shed. The entire water treatment system was demolished to grade in 1978. The flocculation and sedimentation basins remain below grade and were demolished in situ.</p> <p>The site includes the sodium dichromate systems that were located within the 183-DR Head House and 183-DR Filter Building, Acid Facility, the six 183-DR Flocculation Basins, and the six 183-DR Sedimentation Basins, all of which were components of the cooling water treatment system to support the 105-DR Reactor.</p>		
Location:	The site is located west of 105-DR, west the remediated 183-DR Clearwells (126-DR-1).		
Related Sites/ Structures:	The 183-DR Head House is on the west side and immediately adjacent to the 183-DR Coagulation Basins. The 183-DR Filter Building is located between the 183-DR Sedimentation Basins and the 190-DR Storage Tanks.		
Process Description:	<p>These components are of interest because they stored, mixed, or processed liquid contaminants of concern, especially sodium dichromate and sulfuric acid (potentially contaminated with lead and mercury). The sedimentation basins and possibly the flocculation basins received demolition debris from the 183-DR area facilities that may have been contaminated. Sodium dichromate was supplied to the 183-DR Head House through a 7.6 centimeter (3 inch) diameter pipeline (100-D-56) that entered the west side of the 183-DR Head House. The 183-DR Head House contained the inlet control valves, flash mixer chamber, chlorinators, ferric sulfate and lime storage, and feeding equipment, silicate and sodium dichromate solution storage and feeding equipment. The 183-DR Head House had its own sodium dichromate storage facility that consisted of two tanks with a 15,200 liter (4,000 gallon) capacity. Sodium dichromate solution was pumped and injected into the process water after the filters in the filter building by the proportioning pumps in the head house. The 183-DR Filter Building also received sodium dichromate from the 183-DR Head House. Two 1.9 centimeter (0.75 inch) diameter sodium dichromate pipelines extended from the mixer in the 183-DR Head House, over the flocculation and sedimentation basins, to the 183-DR Filter Building where it entered the sample room, mixing pumps, and flume. Acid Facility: The Acid Facility was located on the north side of the 183-DR Head House. Sulfuric acid was received by railroad car and stored in two outside above grade acid storage tanks. The acid facility contained two acid storage tanks (No. 1 & 2), two acid pumps, car spot, acid head tank, one drywell, two sumps, acid piping, pipe flume/trench and an acid pit (H-1-5662). The acid pumps were designed to transport sulfuric acid from the railroad cars to the storage tanks and from the storage tanks to the acid head tank (H-1-5663). The GPS coordinates for the acid pumps are E573251, N151223. The railroad car spot was located west of the pipe trench and south of acid storage tank No. 1. Sulfuric acid was unloaded at this location and pumped to either storage tank No. 1 or 2 (H-1-5663). Between the sulfuric acid tanks was a pipe flume/trench that contained seven pipes that included, two 5 centimeter (2 inch) sulfuric acid pipes (100-D-83), a 10 centimeter (4 inch) overflow pipe, a 2.5 centimeter (1 inch) low pressure steam pipe, 3.2 centimeter (1.25 inch) compressed air pipe, 5 centimeter (2 inch) lime slurry pipe, and a 5 centimeter (2 inch) filtered water pipe (H-1-5663).</p>		

From the acid tanks, material was transported through the pipe trench to the acid head tank then to the 183-DR Head House. Each of the other pipes also connected to the northwest wall of the 183-DR Head House (H-1-5662). The acid head tank was located on the east side of the pipe trench and south of acid tank No. 2. A 5 centimeter (2 inch) sulfuric acid line and a 5 centimeter (2 inch) sulfuric acid drain line connected the tank to the pipe trench. Another 5 centimeter (2 inch) pipe connected to the flume/trench between the 183-DR Head House and the flocculation basin (H-1-5663). The GPS coordinates for the acid head tank are E573256, N151222. There is one drywell and two sumps associated with the acid facility. The 31 centimeter (12 inch) diameter drywell was located on the west side of the acid trench and south of acid tank No. 1 (E573251, N151220). There is a sump located on the west side of acid tank No. 1. The sump was a 61 centimeter (24 inch) diameter feature that was installed in 1957 (E573248, N151121). The second sump is west of the pipe trench and the acid pumps. It is 61 centimeter (24 inch) in diameter (H-1-5663) (E573249, N151232). The acid pit was located north of the acid storage tanks. The pipes in the flume/trench drained into the pit (H-1-5663) (E573252, N151239). The former site of the tanks and the unloading and transfer systems have the potential for contaminated soils caused by leaks and spills (potential lead and mercury). Although the facility has been demolished, subsurface contamination may be present. Head House The 183-DR Head House was the western most segment of the water treatment facility. The building contained three floors that included a basement. The basement contained a sump pit. The first floor contained the equipment room, electrical room, control room, chlorinator room, lab, and chlorine room. The top floor contained the chemical feeder (H-1-915). The dimensions were 34 m by 24 meters (110 feet by 80 feet). It was designed to supply the appropriate mixture of chemicals to provide the desired water treatment to the reactor. Chemicals were received by railcar at the train shed located on the west side of the Head House. River water entered the west side of the head house through two 91 centimeter (36 inch) diameter steel pipes. The 183-DR Head House contained the inlet control valves, flash mixer chamber, chlorinators, ferric sulfate and lime storage, and feeding equipment, silicate and sodium dichromate solution storage and feeding equipment used to chemically treat water (HDC-1418). Alum, sulfuric acid, chlorine and sodium dichromate were mixed in the facility. The 183-DR Head House never received sodium dichromate in pure form. It received a 10% sodium dichromate solution from the 185-D Building through a 7.6 centimeter (3 inch) diameter pipeline (100-D-56) that connected with two tanks, each with a 4,000 gallon capacity. From the storage tanks, two 1.9 centimeter (0.75 inch) diameter sodium dichromate pipes crossed above the flocculation and sedimentation basins where the pipes entered the sample room and mixing pumps in the filter building. From the filter building treated water entered the 190-DR Storage Tanks (H-1-9147, H-1-9601, HW-28360, and SK-1-8261). Water treated with sodium dichromate entered the 190-DR Clearwells followed by the 190-DR Pump House and through the pipe tunnels to the 105-DR Reactor. From the reactor, effluent was pumped to the retention basin (116-DR-9) and to the outfalls (100-D-65 and 116-DR-5). Sulfuric acid and sodium dichromate were mixed in the facility. Sulfuric acid was received from the Acid Facility into the head tank. Sodium dichromate was received through the 7.6 centimeter (3 inch) pipelines (100-D-56) from 185-D Building into two storage tanks, located on the ground floor of the Equipment Room in the northeast corner of the head house. Sulfuric acid was added immediately to the river water arriving from the 182-D Reservoir to adjust the pH. With the addition of the sulfuric acid early in the water treatment system, there is a potential for trace amounts of lead and mercury in the flocculation basins, sedimentation basins, and filter buildings. 183-DR Flocculation and Sedimentation Basins The flocculation and sedimentation basins received hundreds of millions of gallons of river water treated with sulfuric acid. The 183-DR flocculation and sedimentation basins were designed to allow heavier particulate matter to settle out of the water before it entered the filter building. The flocculation basins were located between the 183-DR Head House and the sedimentation basins. The flocculation basins contained six chambers, each containing a paddle wheel to mix chemical additives. The six chambers were 112.5 meters (369 feet) wide and 13 meters (43 feet) wide (H-1-9212). Also located in the basins were at least two drywells (H-1-9213 and H-1-9214 sht 2). The sedimentation basins joined the east side of the flocculation basins and also contained six

chambers. There were six sludge hoppers, one for each basin, near the west wall of the sedimentation basins (H-1-9211, H-1-9212, H-1-9216). Combined they were 112.5 meters (369 feet) wide, 58.5 meters (200 feet) long, and at least 5 meters (16 feet deep). The sedimentation basins later received demolition material from the D & D of the head house and the filter building in 1978 (both of which may have had sodium dichromate, mercury, and/or lead contamination). This component of the site is analogous to the 183-B flocculation and sedimentation basins contamination. 183-DR Filter Building The filter building received water treated with sodium dichromate and sulfuric acid. The 183-DR Filter Building was located on the east side of the sedimentation basin. The filter building contained a pipe galley and operating floor. The operating floor contained the ventilation equipment, switchgear room, pump room, and suction header and hot well bay. (H-1-9401). The facility was 171 meters by 15 meters (560 feet by 52 feet) and contained two halves with a gullet between them. The original filters were modified and replaced with 30.48 centimeters (12 inch) of graded gravel, 15 centimeters (6 inch) of sand and 61 centimeters (24 inch) of crushed and graded anthracite coal. Water entered the gullet from the influent flume through an influent valve and flowed to both halves of the filter components through port openings. There were 10 filters in the facility. From the filter building, water entered the 190-DR Clearwells and pumphouse (H-1-9606). After demolition, the facility was disposed of in the 183-DR sedimentation basins.

Waste Type: Demolition and Inert Waste

Waste Description: The waste form would be contaminated soil from leaks and spills during operation, and contaminated fill material from the demolition of the two buildings. Sodium dichromate, lead, and mercury may be present under the site footprint and in the flocculation and sedimentation basins.

Closure Info: Interim (10/16/2013): Remedial action at the 100-D-62 waste site was conducted on May 2 and 3, 2011. A reinforced concrete septic tank, associated concrete piping, and soil were removed as part of the remediation and staged at the Spoil Pile Areas. Approximately 793 bank cubic meters (BCM) (1,037 bank cubic yards [BCY]) of soil and debris was loaded on July 12 and 13, 2011, for disposal at the Environmental Restoration Disposal Facility (ERDF).

Remedial action at the 100-D-77 waste site began on May 3, 2011, and continued through July 13, 2011. The 100-D-83:1 subsite consisted of the pipeline segments associated with the 183-DR Acid Facility. Most of the pipelines were within the 100-D-77 acid trench and were removed during the 100-D-77 waste site remediation. Remediation continued to a depth of approximately 4.5 meters (15 ft) below ground surface (bgs) resulting in approximately 7,103 BCM (9,290 BCY) of contaminated soil and debris that was removed and staged at the staging pile areas (SPAs) prior to loadout and disposal.

The 100-D-83:1 waste site was inside the 100-D-77 site and was fully removed with the 100-D-77 excavation. Verification samples were collected from these three locations on May 29, 2013.

A 20 meter (65.6 ft) section of the 100-D-56:2 pipelines, located at the entrance into the 183-DR Head House, and the 183-DR Filter Building sample room were also remediated with 100-D-77. Loadout of waste material with subsequent disposal at ERDF was conducted between July 13 and October 18, 2011.

At the completion of the remediation, in-process soil samples were collected on July 6 and July 11, 2011, to determine if additional remediation of the waste site was necessary. Mercury was measured above the direct exposure remedial action goals (RAGs) in the in-process sample data. Based on these results, a second tier (Tier 2) of excavation was designed.

The Tier 2 remediation began on December 8, 2011, and continued through January 16, 2012. Approximately 7,126 BCM (9,320 BCY) of contaminated soil and debris were removed from the excavation and moved to the SPAs for loadout and disposal at ERDF. The excavation depth

extended a maximum of 9.5 meters (31 ft) bgs. Loadout of the Tier 2 waste material began on December 14, 2011.

The presence of elevated PAH within the excavation area was attributed to cross-contamination of asphalt. Additional remediation of benzo(a)pyrene at location EXC-3 was a result of cross-contamination with asphalt. Additional soil was removed at and around the sample location (EXC-4) with elevated mercury on March 15, 2013. An additional 76 BCM (100 BCY) of contaminated soil and debris were removed from the excavation and staged prior to disposal at ERDF. The area in which additional removal was performed included the FS-1 sample location. Replacement verification samples were collected at the EXC-4 and FS-1 locations on March 15, 2013.

Contaminated soil, concrete, and rebar from previously demolished buildings, piping, and a brick-lined concrete acid trap were among the types of material removed from the excavation. All materials removed from the 100-D-62, 100-D-77, and 100-D-83:1 excavation were staged at five SPAs prior to loadout and disposal at ERDF.

Code:	100-D-94	Classification:	Accepted
Names:	100-D-94; Dichromate Contaminated Pit Associated with 187-DR	Reclassification	Interim No Action (3/31/2011)
Type:	Depression/Pit (nonspecific)	Start Date:	
Status:	Inactive	End Date:	
Description:	The site was evaluated and determined to require No Action. It consists of an area of yellow material observed inside a pit under the DR water tower. This area was identified during the D Area Orphan Site Evaluation.		
Location:	The site was located directly under the 100-DR water tower, south of the 105-DR Reactor.		
Related Sites/ Structures:	This site is associated with the 187-DR high tower.		
Process Description:	This site served as a valve pit for process water stored in the 187-DR water tower. The water tower provided emergency cooling water to the 105-DR reactor. The reinforced concrete valve pit with a 1.06 meter (3.5 ft) thick floor slab, 0.3 meter (1 ft) thick side walls and 0.76 meter (2.5 ft) thick roof, was located below ground directly beneath the tank. A central riser extended into this pit from the water tank.		
	In August 2010, during confirmatory sampling of 100-D-83:4 in Test Pit 3. Beta and gamma readings up to 6,000 dpm were detected on a piece of broken pipe. The pipe was located approximately 0.3 meters (1 foot) to 2.4 meters (8 feet) below ground surface.		
Waste Type:	Process Effluent		
Waste Description:	Potential Contaminant of Concern, Chromium.		
Closure Info:	Interim (3/31/2011): Based on observations during the site visit, review of historical drawings, process knowledge, and a geophysical survey of the 100-D-94 waste site, confirmatory sampling was performed in August 2010.		
	Two focused soil samples and one duplicate were collected from the excavated test pit and were used to evaluate whether contamination associated with the dichromate contaminated pit was present at the 100-D-94 waste site. The test pit was excavated to 2.0 meters (6.6 ft) below ground surface (bgs). The soil appeared to be fill material consisting of dark gray sandy soil and		

unsorted cobble. The test pit was extended to a depth of 3 meters (9.8 ft) bgs, where a second soil sample was collected. One pipe flange was found loose in the excavation. No other debris or staining was observed. The soil appeared to be fill material at this depth also. No undisturbed native soil was encountered during the excavation. Field surveys for radiological activity and volatile organic compounds were conducted during sampling. No radiological activity or volatile organic compounds were detected.

The confirmatory sampling results indicated that environmental contamination was not present at the 100-D-94 waste site; therefore, remedial action was determined to be unnecessary. The confirmatory sampling data has been used to document this waste site for reclassification as a No Action site.

Code:	100-D-100	Classification:	Accepted
Names:	100-D-100; Sodium Dichromate Near Southern Portion of 100-D-56; Stained soil near 183-DR Railroad Track	Reclassification	Interim Closed Out (8/3/2015)
Type:	Unplanned Release	Start Date:	
Status:	Inactive	End Date:	
Description:	The site has been remediated and Interim Closed Out. It consisted of chromate contaminated stained soil, identified in 2008, located near the former sodium dichromate/ acid railcar and truck unloading station (sitecode 100-D-12). Extensive sampling and excavation occurred between 2008 and 2014.		
Location:	The original area of stained soil was located in an area north of the 183-DR Headhouse and approximately 50 meters (164 feet) south of Paddock Street, adjacent to the remediated 100-D-56 pipeline. The staining was between the 100-D-56 pipelines and the railroad tracks that previously serviced the 183-DR building. The lateral and horizontal extent of contamination has not been defined. The center of the site is located at Washington State Plane coordinates E573351 N151359.		
Related Sites/ Structures:	The nearest structures (including those previously demolished) include the railroad spur leading to the 183-DR building and the sodium dichromate/ acid railcar and truck unloading station (sitecode 100-D-12). The stain was approximately 38 meters (125 feet) south of the 100-D-12 waste site.		
Process Description:	To inhibit corrosion, sodium dichromate was added to the reactor cooling water. Initially the chemical was prepared in the 108-D Chemical Pump House. The concentrated solution was pumped to feed tanks in the 105-D and 185-D Buildings. The preparation of the sodium dichromate feedstock was relocated from the 108-D Chemical Pump House to the 185-D Deaeration Plant in 1950. Two 7.6 centimeter (3 inches) diameter dichromate lines (100-D-56) were installed between the 185-D building and 183-DR building during the 100-DR Water Plant construction. A new spur track was also installed leading to the 183-DR building from the existing railroad tracks south of the 186-D building.		
Waste Type:	Process Effluent		
Waste Description:	The waste consists of hexavalent contaminated soil. The potential contaminant of concern is hexavalent chromium.		
Closure Info:	Interim (8/3/2015): The stained surface soil was identified on April 6, 2008, near the former sodium dichromate/acid railcar and truck unloading station. Five focused soil samples were collected, at that time, to evaluate potential contaminants associated with the stains. Chromium and hexavalent chromium were present in all of the samples. In April 2009, test pits and trenches were excavated and sampled at the 100-D-100 waste site to a depth of 4.6 meters (15		

ft) to evaluate the extent of hexavalent chromium contamination. The results of this sampling indicated that remediation of subsurface soil at the 100-D-100 waste site was necessary. Remediation of the 100-D-100 waste site was initiated in August 2011 and continued through October 2011, to a depth of approximately 16 meters (52.5 ft) below ground surface (bgs). This excavation depth is identified as the 100-D-100 Tier II excavation. Hexavalent chromium contamination exceeding cleanup criteria was present at the base of the Tier II excavation and in portions of the sidewalls of the excavation. Therefore, a Tier III excavation continued to a depth of approximately 26 meters (85.3 ft) bgs. This work was completed in January 2014. After vadose zone remediation was completed in January 2014, elevated levels of hexavalent chromium remained in the soil at the interface of the vadose zone with the unconfined aquifer. An investigation was initiated by the CH2M Hill Plateau Remediation Company to determine the distribution and potential persistence of hexavalent chromium within the aquifer and the aquifer sediment. Four temporary boreholes were drilled at the bottom of the 100-D-100 excavation beginning on April 24, 2014, and were completed on May 12, 2014, to assess the vertical and horizontal distribution of hexavalent chromium remaining in the aquifer. Based upon the results of this investigation, it was decided to remove approximately 3 meters (10 ft) of aquifer sediment from below the seasonal low water table. This additional removal was performed from December 15, 2014, through February 4, 2015. Approximately 15,589 BCM (20,390 BCY) of aquifer sediment was removed, dewatered, and disposed to ERDF.

To evaluate the northeast sidewall where the pipeline valves leaked, thirteen in-process samples were collected at depths of 19.2 to 22.9 meters (63 to 75 ft) bgs

A considerable layback and overburden soil was removed and stockpiled (Approximately 330,000 BCM (431,600 BCY)). Approximately 196,000 bank cubic meters (BCM) (256,360 bank cubic yards [BCY]) of contaminated soil, plus 15,589 BCM (20,390 BCY) of aquifer sediment, was excavated and disposed of at the Environmental Restoration Disposal Facility (ERDF). Approximately 29,000 BCM (37,900 BCY) of this material was treated at ERDF as land disposal restricted for chromium.

Code:	116-D-8	Classification:	Accepted
Names:	116-D-8; 100-D Cask Storage Pad	Reclassification	Interim Closed Out (8/10/2011)
Type:	Storage	Start Date:	1/1/1946
Status:	Inactive	End Date:	1/1/1975
Description:	The site has been remediated and Interim Closed Out. It was a rectangular pad covered with gray grout (shotcrete). The grout-covered concrete pad, including the truck loading pit, degreasing pits, and french drains, was removed in its entirety. It had been surrounded with Underground Radioactive Material signs. It had also been posted with Cave-in Potential signs, but the Cave-in potential signs were removed in November 1999.		
Location:	The site was located on the west side of the 100-DR Reactor, outside the fence.		
Related Sites/ Structures:	The site was associated with 100-D-50:1, 100-D-50:2 and the 1607-DR3 Sanitary Sewer Pipelines that may discharge to the 100-D-50:9 pipeline.		
Process Description:	During the construction of the 105-D Reactor, this site functioned as the foundation and degreasing pits for a temporary airlock to clean and store reactor components before their installation. Subsequently, the concrete pad was modified to provide storage and a decontamination station for shielded casks used for shipping irradiated materials. After the 105-D Reactor was shut down in 1967, the casks and other materials were stored on the pad until general cleanup was performed in 1987. Surface contamination on the pad was stabilized by application of an asphalt fixative.		

The concrete pad had two drains. The drain that handled pad decontamination and rain runoff, discharged into the 105-DR process sewer. The second drain discharged to a french drain, the location of which is unknown; however, an excavation that may be the drain was dug in 1949. There may also be a french drain beneath the loading dock, located on the west side, that provided drainage for storm runoff which is likely to be contaminated. The pad has been stabilized with a sprayed grout material and reinforced with a metal mesh material. There are two structures just south of the pad - one is a red aluminum storage tank and the other appears to be a furnace or shipping cask.

Waste Type: Chemicals

Waste Description: This site contains trace amounts of radionuclides and decontamination chemicals.

Closure Info: Interim (8/10/2011): The grout-covered concrete pad, including the truck loading pit, degreasing pits, and french drains, was removed in its entirety. Remediation was performed from August 19, 2008 through February 8, 2009. Approximately 1,170 bank cubic meters (BCM) (1,530 bank cubic yards [BCY]) of concrete debris, asphalt emulsion, tan fibrous material, black plastic, grout, steel, and soil was removed from the waste site and disposed at the Environmental Restoration Disposal Facility (ERDF). In January 2011 an additional 0.53 BCM (0.69 BCY) of soil was removed from the area at the south degreasing pit. Approximately 1.0 BCM (1.2 BCY) of soil was removed from the south radiological contamination area. This material was also disposed of at ERDF. This is in the ecologically sensitive area associated with the 100-D-50:2 cooling water tunnel. The deepest part of the waste site excavation was approximately 1.5 meters (5 ft) deep at the location of the former degreasing pits.

The 116-D-8 waste site is located above a section of vitrified clay sewer pipeline associated with the 100-D-50:1 waste site. On August 25, 2008, a manhole was discovered during excavation of the 116-D-8 waste site. Based on the coordinate location, it was determined that the manhole was associated with the 100-D-50:1 subsite. The manhole was filled with clean borrow pit soil to eliminate a safety concern and left in place. No further remediation can be conducted at the location with the cesium-137 direct exposure exceedance, without incurring significant adverse impacts to the bat colonies at the 100-D-50:2 pipeline subsite. A study conducted between June 2007 and September 2008 (WCH 2009a) showed that the bats in the 100-D-50:2, Reactor Cooling Water Pipelines (concrete tunnel) from 190-DR Pumphouse subsite use the site as a maternity roost where they give birth and rear their young.

The preferred alternative to eliminate or mitigate impacts to the bat colony is to leave the structure intact and add perimeter fencing and signage to deter human entry. Therefore, institutional controls are required at the location of the cesium-137 contamination south of the 116-D-8 cask storage pad.

A summary of the cleanup evaluation for the soil results against the applicable criteria is presented in Table ES-1. The results of the verification sampling are used to make reclassification decisions for the 116-D-8 waste site in accordance with the Tri-Party Agreement Handbook Management Procedures (DOE-RL 2007).

Code: 118-D-1	Classification: Accepted
Names: 118-D-1; 100-D Burial Ground No. 1	Reclassification: Interim Closed Out (10/10/2011)
Type: Burial Ground	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1967
Description: The waste site has been remediated and Interim Closed Out. It was a burial ground that contained multiple trenches running north and south. The trenches were approximately 90	

meters (300 feet) long by 6 meter (20 feet) wide and 6 meters (20 feet) deep with a 6 meters (20 feet) of space between them. Several trenches were greater than 6 meters (20 feet) deep. A 106 centimeter (42 inch) diameter, reinforced concrete water pipe runs through the northwest corner of the burial ground boundary, but not through any of the waste trenches (see WIDS sitecode 100-D-50).

Location: The unit is located south of the 105-DR Building just outside of the 100-D Perimeter Fence.

Process Description: The burial ground was constructed in 1944 as a solid waste disposal facility used for the disposal of irradiated reactor hardware, including thimbles, dummies, control rods, gun barrels, and other contaminated solid waste. Other waste items included soft waste, desiccant, miscellaneous waste, and thermocouple waste.

Waste Type: Equipment

Waste Description: The unit was used for the disposal of irradiated dummies, thimbles, rods, gun barrels, and other contaminated solid waste. It may contain spent nuclear fuel elements. Potential contaminants include: H-3, C-14, Co-60, Ni-63, Sr-90, Ag-108m, Cs-137, Eu-152, Eu-154, Am-241, Pu-238, 239 and 241, Sm-151, Se-79, Tc-99, U-235 and 238, Kr-85, Zr-93, cadmium, lead, mercury. Historical research identified some specific buried items that include a one ton Aimer track cut into 12 pieces, mattress plate extensions, poison pieces, vertical safety rods, rod guides and tips, shield plugs and contaminated soil.

Closure Info: Interim (10/10/2011): Remedial action at the 118-D-1 Burial Ground began on November 28, 2008, and continued through May 5, 2011. Remedial action activities involved removing and stockpiling the uncontaminated overburden, and removing the buried waste and the underlying contaminated soil for disposal. The maximum depth of excavation was 6.5 meters (21 feet).

Miscellaneous reactor hardware including piping, lead, splines, rods, a thimble head, and drums were excavated. No spent nuclear fuel was found to be present in the burial ground. Some stained soil was noticed during the remedial excavation. Focused samples were collected at these locations.

All waste materials were disposed at the Environmental Restoration Disposal Facility (ERDF).

Code: 118-D-2	Classification: Accepted
Names: 118-D-2; 100-D Burial Ground No. 2	Reclassification: Interim Closed Out (9/27/2012)
Type: Burial Ground	Start Date: 1/1/1949
Status: Inactive	End Date: 1/1/1970

Description: The 118-D-2 waste site included the entire disturbed area visible in historical aerial photographs known as the 100-D Burial Ground No. 2. During remediation, it was split into two subsites: 118-D-2:1, 100-D Burial Ground No. 2 Trenches and Disposal Pits and 118-D-2:2, Anomaly Characterization Area. Both subsites have been remediated and Interim Closed out, so the parent site is also Interim Closed Out. The radiological postings were removed in September 2012.

Location: This unit is located 400 meters (1,312 feet) west-southwest of the 183-DR Headhouse.

Process Description: The waste site was the primary burial ground for the disposal of 105-D Reactor operations waste, including irradiated dummies, splines, rods, thimbles, and gun barrels. The 118-D-2 Burial Ground operated from 1949 to 1970 and was the primary burial ground for the disposal of 105-D Reactor operations waste, including aluminum tubes and spacers; metallic wastes of aluminum, cadmium, and lead; irradiated dummies; splines; vertical safety rods; thimbles; and gun barrels. The burial ground was extended in April 1966 to provide space for the burial of

contaminated solid wastes from the 100-N Area. The burial ground consisted of several trenches running east to west and five pairs of disposal pits. The trenches were said to be 20 meters (66 ft) wide at the surface, 6.1 meters (20 ft) wide at the bottom, and 6.1 meters (20 ft) deep, and were used for the disposal of 105-D Reactor operations waste. The disposal pits were constructed by stacking railroad ties, creating two spaces with interior dimensions of approximately 1.8 by 1.8 meters (6 by 6 ft) that shared a common wall. The structures were built within an excavation reportedly 7.3 meters (24 ft) wide by 7.3 meters (24 ft) deep.

Waste Type: Equipment

Waste Description: The unit was used for miscellaneous contaminated solid waste such as irradiated dummies, splines, vertical safety rods, thimbles, and gun barrels. Waste includes 16,329 kg of aluminum tubes, 36287 kg of aluminum spacers, 89,040 kg of lead poison slugs, 3719 kg of cadmium poison slugs, 5987 kg of aluminum poison slugs, 54 kg of lead and 16,329 kg of miscellaneous metallic waste. This burial ground has the potential to contain spent nuclear fuel rods. Beginning in April 1966, 100-N Area solid wastes were also buried here. A large fire in this burial ground in March 1958. The large volumes of water that were required to extinguish the fire could have potentially washed contaminants into the soil column beneath the burial ground. Potential contaminants include H-3, carbon-14, cobalt-60, Ni-63, Sr-90, Ag-108, Ba-133, Cs-137, Eu-152 and 154, Pu-238, 239 and 241, Ca-41, Cd-113, Kr-85 and Zr-93.

This Site has the Following SubSites:

Code: 118-D-2:1

Names: 118-D-2:1; 100-D Burial Ground No. 2 Trenches and Disposal Pits

Code: 118-D-2:2

Names: 118-D-2:2; Anomaly Characterization Area

Code: 118-D-2:1

Classification: Accepted

Names: 118-D-2:1; 100-D Burial Ground No. 2 Trenches and Disposal Pits

Reclassification: Interim Closed Out (7/11/2012)

Type: Burial Ground

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. The subsite was a burial ground that contained several trenches running east to west and five pairs of disposal pits. The trenches were 20 meters (66 ft) wide at the surface, 6.1 meters (20 ft) wide at the bottom, and 6.1 meters (20 ft) deep. The disposal pits were constructed by stacking railroad ties, creating two spaces with interior dimensions of approximately 1.8 by 1.8 meters (6 by 6 ft) that shared a common wall. The pit structures were built within an excavation measuring 7.3 meters (24 ft) wide by 7.3 meters (24 ft) deep.

Location: The site is located 417 meters (1,368 feet) southwest of the 183-DR Headhouse.

Process Description: The 118-D-2 Burial Ground operated from 1949 to 1970 and was the primary burial ground for the disposal of 105-D Reactor operations waste, including aluminum tubes and spacers; metallic wastes of aluminum, cadmium, and lead; irradiated dummies; splines; vertical safety rods; thimbles; and gun barrels. The burial ground was extended in April 1966 to provide space for the burial of contaminated solid wastes from the 100-N Area. The burial ground consisted of several trenches running east to west and five pairs of disposal pits. The trenches were said to be 20 meters (66 ft) wide at the surface, 6.1 m (20 ft) wide at the bottom, and 6.1 m (20 ft) deep, and were used for the disposal of 105-D Reactor operations waste. The disposal pits were constructed by stacking railroad ties, creating two spaces with interior dimensions of approximately 1.8 by 1.8 meters (6 by 6 ft) that shared a common wall. The structures were

built within an excavation reportedly 7.3 m (24 ft) wide by 7.3 m (24 ft) deep.

In 1953, the 118-D-2 burial ground consisted of one covered trench and one open trench that ran east and west. The waste site was the primary burial ground for the disposal of 105-D Reactor operations waste, including irradiated dummies, splines, rods, thimbles, and gun barrels. Each pair of pits was constructed by stacking railroad ties, creating two spaces with interior dimensions of approximately 1.8 by 1.8 meters (6 by 6 ft) that shared a common wall. The structures were built within an excavation 7.3 meters (24 ft) wide by 7.3 m (24 ft) deep. All were covered with 1.8 meters (6 ft) of soil. It was extended in April of 1966 to provide space for the burial of contaminated solid wastes from N-Area. The waste site was used for miscellaneous contaminated solid waste, irradiated dummies, splines, rods, thimbles, and gun barrels. After April 1966, 100-N Area solid wastes were also buried here. It was reported that there was a large fire in this burial ground sometime around 1960. The large volumes of water that was required to extinguish the fire could have potentially washed contaminants into the soil column beneath the burial ground. The metallic waste disposed in the waste site consists of 16,329 kg of aluminum tubes, 36,287 kg of aluminum spacers, 89,040 kg of lead poison slugs, 3,719 kg of cadmium poison slugs, 54 kg of graphite, 14 kg of desiccant, 5,987 kg of aluminum poison slugs, 816 kg of boron poison splines, 58,966 kg of lead, and 16,329 kg of miscellaneous metallic waste. Radioactively contaminated trash from N Reactor was sent to the Irradiation Processing Department D Reactor's burial trenches. The trash amounted to approximately 14 cubic meters (500 cu ft) per month. It is assumed the trash was delivered to 118-D-2. Three layers of contaminated express car flooring covering a 5 sq ft area were removed. Alpha contamination was maximum 140,000 dpm and the maximum dose rate was 950 mrem/hr. It is assumed the material was delivered to the 118-D-2 burial ground. The cutter wheel of the can cutter in the transfer area was found contaminated to 3,000 dpm of alpha and subsequently discharged, assumed buried in 118-D-2. In February of 1950, sections of thimbles were buried, assumed into 118-D-2. In July of 1950, the can of water used to receive the metal downstream of a ruptured piece of the dummies were buried. The can of water showed 5dpm/L plutonium and 0.284 uc/L of fission product, assumed buried in 118-D-2. In August and November of 1950 a dummy cart full of irradiated dummies and a VSR thimble were buried, assumed to be in 118-D-2. In December of 1950, a contaminated cask containing a ruptured slug from 100-H rolled off a truck onto a road west of the 108-D Building. Contaminated gravel from the road was removed. A can of water into which pieces downstream of ruptured slugs were removed from the storage basin were buried. Water samples showed $1.1E-3$ uc/cc. All material are assumed to be buried in 118-D-2. In 1951, a VSR thimble section with a reading of 5r/hr was momentarily removed from the burial trench. A box containing swabs from a process tube from 105-D were buried. That same year, from the 105-D decontamination vat and two small chips were found during the removal of a tip-off contained dosage rates of 200 and 10r/hr respectively. All material was believed to be buried in 118-D-2. Sections of the effluent line and expansion joints were removed and buried during repair work on the 100-D Reactor effluent lines. The material may have been buried at the waste site. In July 1955, Zirconium tube samples were recovered from the burial ground and are assumed to be from 118-D-2. Dose rates up to 8 rad/hr were encountered while transferring waste from a cave in the Pile Coolant Studies Metallurgy Laboratory to a cask from removal to burial ground, assumed to be 118-D-2.

Closure Info: Interim (7/11/2012): Remediation of the 118-D-2:1 Burial Ground began in February 2009 and continued through May 2011. Approximately 14,524 bank cubic meters (BCM) (18,997 bank cubic yards [BCY]) of overburden soil was removed and stockpiled west of the burial ground for use as clean backfill. Approximately 45,752 BCM (59,842 BCY) of contaminated soil and debris were removed for disposal at ERDF. The remedial design allowed for the construction and use of sorting cells to be located east of the burial ground. However, all excavated materials were sorted within the burial ground and direct loaded for disposal to ERDF. The sorting cells were never constructed. The initial verification sampling conducted in September 2011 indicated contamination remained in the excavation (Trench 7). A recommendation to remove the contaminated soil and resample for all COPCs at the failed sample locations was presented

to Ecology, and a path forward was agreed upon. Additional material was removed in February 2012, resulting in an additional 1,700 BCM (2,223 BCY) of material disposed at ERDF. Field observations during the excavation and sorting of material identified miscellaneous metal debris, piping, lead pigs, and perforated tubes among the types of debris removed from the burial ground excavation. Twelve pieces of suspect spent nuclear fuel (SSNF) were discovered at the 118-D-2:1 Burial Ground subsite. The SSNF was then transferred to the 118-D-3:2 subsite for characterization. Of the 12 pieces of SSNF, 10 were characterized as spent nuclear fuel and 2 were characterized as reactor debris. All waste material has been disposed. Several anomalous items capable of containing liquids or solids were encountered during excavation of the 118-D-2:1 Burial Ground subsite. These items were inspected within the burial ground footprint and were either determined to be empty and loaded out for disposal at the ERDF, or the contents were unknown. The items were moved to the 118-D-2:2 or 118-D-3:2 anomaly characterization area.

The SubSite is Part Of:

Code: 118-D-2

Names: 118-D-2; 100-D Burial Ground No. 2

Code: 118-D-2:2

Classification: Accepted

Names: 118-D-2:2; Anomaly Characterization Area

Reclassification: Interim Closed Out (9/27/2012)

Type: Burial Ground

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. It consisted of remediation support areas located in the northern portion of the 118-D-2 burial ground, where geophysical surveys found no buried waste. The support areas were used for decontamination and staging areas during the 118-D-2 remediation activities.

The six support areas were the (1) Bunker, used to store suspect spent nuclear fuel (SSNF) removed from the 118-D-2 Burial Ground; (2) the Radioactive Materials Area (RMA), used to stage pigs and anomalous items removed from the 118-D-2 Burial Ground; (3) The Carport, used to stage clean equipment; (4) the Radiological (RAD) area, used to examine and process pigs; (5) the Control area, that provided a safety buffer around the RAD area and (6) the Decontamination Pad, where equipment was decontaminated.

Location: The subsite was within the original 118-D-2 waste site, approximately 379 meters (1,243 feet) west-southwest of the 183-DR Headhouse.

Process Description: The anomaly characterization area was used to characterize anomalous materials found in the 118-D-2 Burial Ground during remediation. During remediation, various containers designed to transport radioactive materials were found. The containers were known as pigs. Suspect spent nuclear fuel (SSNF) was also found within the burial ground. The SSNF and pigs required special processing prior to disposal and were staged in the 118-D-2:2 support areas.

Closure Info: Interim (9/27/2012): On June 13, 2011, a 0.3 meter (1 ft) scrape and soil removal was performed at the RAD area, the Bunker, the RMA, and portions of the control area. A 0.9 meter (3 ft) scrape was performed at the decontamination pad. The carport area was covered in plastic and a layer of clean gravel during the scraping activity. June 13, 2011, to determine if elevated radiological activity was present after the initial scrape and removal. The GPERS survey was conducted to include all six of the support. The results found no gamma readings above twice the background level.

Cleanup verification sampling of the site was performed on January 31, 2012. The verification sampling results indicated that a small area in the RMA required additional remediation. On

April 18, 2012, an additional 0.45 meter (1.5 ft) of material was scraped and removed from the southern edge of the RMA. The material removed was disposed to the Environmental Restoration Disposal Facility (ERDF). A total of approximately 543 BCY (415 BCM) of material was disposed to ERDF from the 118-D-2:2 subsite.

None of the pigs or other anomalous materials were found to contain hazardous materials and were disposed to ERDF. The suspect spent nuclear fuel (SSNF) was transferred to the 118-D-3:2, Fuel and Anomaly Characterization Areas site for characterization. The SSNF was ultimately disposed to the 100-K Fuel Storage Basins.

The SubSite is Part Of:

Code: 118-D-2

Names: 118-D-2; 100-D Burial Ground No. 2

Code: 118-D-3

Classification: Accepted

Names: 118-D-3; 100-D Burial Ground No. 3

Reclassification: Interim Closed Out (8/2/2012)

Type: Burial Ground

Start Date: 1/1/1956

Status: Inactive

End Date: 1/1/1973

Description: The waste site has been remediated and Interim Closed Out. The waste site encompassed the 100-D Burial Ground Number 3 which consisted of two subsites. Subsite one included multiple (6 to 8) trenches running east and west. Subsite two was the fuel characterization area and the anomaly characterization area. Both subsites have been remediated and Interim Closed Out, so the parent site is also Interim Closed Out. The radiological postings were removed in September 2012.

Location: The unit is located 106.7 meters (350 feet) east of the 105-DR Building.

Related Sites/ Structures: The site received waste from the 105-DR Reactor and 100-N area solid waste.

Process Description: The burial ground was the primary disposal site for 105-DR Reactor operations waste, including irradiated dummies, splines, rods, thimbles, and gun barrels. The burial ground has the potential to contain spent nuclear fuel elements. The site also contained a burning pit used to dispose of low-level radioactive combustible materials. The eastern boundary was used for the disposal of 100-N solid wastes.

Waste Type: Equipment

Waste Description: The unit contains miscellaneous contaminated solid wastes and irradiated dummies, splines, rods, thimbles, and gun barrels. This burial ground has the potential to contain spent nuclear fuel rods. It was also used for disposal of 100-N solid wastes. Potential contaminants include: H-3, C-14, Co-60, Ni-63, Sr-90, Ag-108m, Cs-137, Eu-152, Eu-154, Kr-85, Zr-93, Cd-113, Se-79, Tc-99, Sm-151, Am-241, Pu-238, 239 and 241, U-235 and 238, Ba-133, cadmium, lead, and mercury.

Waste Type: Equipment

Waste Description: The waste site received 23.8 tons of lead, 97 tons of aluminum, 137.7 tons of Pb/Cd, 1 ton of boron, and 0.06 tons of graphite.

This Site has the Following SubSites:

Code: 118-D-3:1

Names: 118-D-3:1; 100-D Burial Ground No. 3 and Process Cells

Code: 118-D-3:2
Names: 118-D-3:2; Fuel and Anomaly Characterization Areas

Code: 118-D-3:1 **Classification:** Accepted
Names: 118-D-3:1; 100-D Burial Ground No. 3 and **Reclassification** Interim Closed Out (7/11/2012)
 Process Cells
Type: Burial Ground **Start Date:**
Status: Inactive **End Date:**

Description: The subsite has been remediated and Interim Closed Out. It consisted of multiple trenches in the burial ground that were oriented east to west. The trenches were 61 meters (200 ft) long by 6.1 meter (20 ft) wide at the bottom and 6.1 meters (20 ft) deep. The spacing between trenches was not uniform. The subsite also included the process (sorting) cells used to determine the presence of suspect spent nuclear fuel and the north anomaly storage area.

The burial ground was the primary disposal site for 105-DR Reactor operations waste, including irradiated dummies, splines, rods, thimbles, and gun barrels. The burial ground had the potential to contain spent nuclear fuel elements. The site also contained a burn pit used to dispose of low-level radioactive combustible materials. The eastern boundary was used for the disposal of 100-N solid wastes.

Location: The burial ground was located 106.7 meters (350 ft) east of the 105-DR Building. The sorting cells were 137 meters (449 feet) south of the burial ground. The coordinates of centroid of the two sorting cells was N 151139.7, E 573966.5 and N151109.0, E 573967.1. The north anomaly storage area covered a portion of the burial ground along the north side. The centroid of the north anomaly storage area was N 151348.2, E 574047.3.

Closure Info: Interim (7/11/2012): Remedial action at the 118-D-3:1 Burial Ground began in July 2007 and continued through June 2011. Remedial action activities involved removing and stockpiling the uncontaminated overburden and removing the buried waste and the underlying contaminated soil for disposal. Approximately 9,120 bank cubic meters (BCM) (11,929 bank cubic yards [BCY]) of overburden and layback soil were removed from the burial ground and stockpiled for use as clean backfill. Approximately 86,165 BCM (112,700 BCY) of contaminated soil and debris were disposed at the Environmental Restoration Disposal Facility (ERDF). Twenty-five confirmed pieces of spent nuclear fuel were packaged and shipped to the 100 Area KE Basin for disposal. Additional material was removed in January 2011 from the locations exceeding direct exposure RAGs, and those areas were resampled in January 2011. Remedial actions resumed within the burial ground in March 2011 and continued through June 2011. The additional remediation resulted in approximately 19,000 BCM (24,851 BCY) of contaminated soil and debris removed from the burial ground for disposal at ERDF.

Field observations during the excavation and sorting of material identified miscellaneous reactor hardware, including dummies, splines, rods, and piping. Lead pigs, drums, and suspect spent nuclear fuel were also observed within the excavation, and were removed to the anomaly characterization area for further characterization. Three potentially stained soil locations were identified during the remedial activities at the 118-D-3:1 Burial Ground, including two suspect oil-stained locations and one orange stained soil location.

The 118-D-3:1 Burial Ground waste site was divided into seven decision units. The excavation extended approximately 14 meters (46 ft) deep. The burial ground excavation includes both shallow-zone and deep zone decision units.

The SubSite is Part Of:

Code: 118-D-3
Names: 118-D-3; 100-D Burial Ground No. 3

Code: 118-D-3:2 **Classification:** Accepted
Names: 118-D-3:2; Fuel and Anomaly Characterization Areas **Reclassification:** Interim Closed Out (8/2/2012)
Type: Burial Ground **Start Date:**
Status: Inactive **End Date:**

Description: The subsite has been remediated and Interim Closed Out. It included two areas, the fuel characterization area and the anomaly characterization area. The 118-D-3:2 fuel and anomaly characterization area consists of the anomaly staging area, characterization area, suspect spent nuclear fuel (SSNF) bunker area, sodium-potassium alloy (NaK) processing area, and the new bunker area. It was used to investigate suspect spent nuclear fuel and confirm the presence of spent nuclear fuel pieces. The original SSNF bunker area was used to shield and store the NaK and uranium specimens. The new bunker area was a plastic-lined bermed area added to relocate the NaK specimens for the purpose of facilitating scraping of the original bunker. The anomaly characterization area was used to characterize anomalous materials found at 100-D. These materials included irradiated dummies, splines, rods, and spent fuel rods.

Location: The site was located 321 meters (1053 feet) southeast of the 105-DR building.

Closure Info: Interim (8/2/2012): Remedial action at the 118-D-3:2 subsite was performed on January 9, 2012, and February 6, 2012. The subsite was scraped in two stages to a total depth of 0.3 meter (1-ft). The first 0.3 meter (1-ft) scrape incorporated everything inside the area of contamination (AOC) surrounding the 118-D-3:2 subsite except the new bunker area. This allowed in-process samples to be taken at the majority of the site. On February 6, 2012, the new bunker area was moved outside of the AOC to expedite the closure of the 118-D-3:2 subsite. This allowed a second and final scrape to be done on the same day, February 6, 2012, at the original new bunker area location. The material scraped was disposed at the ERDF. Uranium capsules (from NaK test specimens) were shipped to the Central Waste Complex on March 1, 2012. No stained soil was observed.

The SubSite is Part Of:

Code: 118-D-3
Names: 118-D-3; 100-D Burial Ground No. 3

Code: 118-D-4 **Classification:** Accepted
Names: 118-D-4; 118-D-4F; Burial Ground 4F; Construction Burial Ground **Reclassification:** Interim Closed Out (10/14/2010)
Type: Burial Ground **Start Date:** 1/1/1956
Status: Inactive **End Date:** 1/1/1967

Description: The waste site has been remediated and Interim Closed Out. The site surface had been a gravel and cobble field.

Location: The site was located 300 meters (1000 feet) southeast of 105-D Reactor Building and 30 meters (100 feet) south of the 100-D railroad tracks.

Process Description: This irregularly shaped burial ground received construction waste, primarily reactor components and hardware, associated with Project CG-558. Based on historical photograph 3738-Photo, this site (118-D-4F) likely began operations around 1956 instead of 1953. A

geophysical survey detected three distinct trenches.

Waste Type: Equipment

Waste Description: This unit contains contaminated material generated during Project CG-558. The contaminated material consisted mainly of reactor components and hardware. Potential contaminants include: C-14, Co-60, Ni-63, H-3, Nb-94, Ni-59, Pd-102, Sm-151, Tc-99, Am-241, Ag-108m, Ba-133, Cs-137, Eu-152 and 154, Pu-238, 239 and 241, Ca-41, Cd-113m, Kr-85, Zr-93, cadmium, lead.

Closure Info: Interim: Remedial action began on October 10, 2007, with the removal of 5,500 bank cubic meters (BCM) (7,200 bank cubic yards [BCY]) of overburden material. The overburden was stockpiled southeast of the burial ground. Excavation continued through March 20, 2008, to a maximum depth of approximately 6.5 m (21 ft), resulting in approximately 7,067 BCM (9,243 BCY) of waste material removed for disposal at ERDF. Although the excavation extended into the deep zone, the entire excavation area is treated as shallow zone for verification sampling.

The waste encountered consisted of primarily contaminated reactor components and hardware associated with Project CG-558. Field observations during excavation indicated the presence of piping, lead, concrete, steel, reactor hardware, valves, a metal solvent container, and leaded glass. A 19 liter (5 gal) metal solvent container with an unknown amount of liquid was removed from the excavation. In addition, red-stained soil was also observed on the floor of the center excavation. A waste characterization sample was collected of the red-stained soil and showed elevated levels of cadmium, total chromium, and nickel. The soil was excavated and disposed. Focused samples were collected at the location where the metal container and red-stained soil were observed.

The 118-D-4 excavation area had a maximum depth of approximately 6.5 meters (21 ft), which included both shallow zone and deep zone soils. However, the entire excavation area was considered one decision unit, and was closed out using the more restrictive shallow zone cleanup criteria.

Code: 118-D-5	Classification: Accepted
Names: 118-D-5; Ball 3X Burial Ground; Burial Ground 4G; Minor Construction Burial Ground Number 3; Minor Construction Burial Ground Number 5; 118-D-4G	Reclassification: Interim Closed Out (2/1/2010)
Type: Burial Ground	Start Date: 1/1/1954
Status: Inactive	End Date: 1/1/1954

Description: The site has been remediated and Interim Closed Out. The unit consisted of two burial trenches located parallel to each other. Each trench was 12.2 meters (40 feet) long by 6.1 meters (20 feet) wide.

Location: The unit is located 30.5 meters (100 feet) south of the 105-DR Building, just outside the exclusion area fence. Hanford drawings H-1-4046 and H-1-19823 show a discrepancy in the site location.

Process Description: This burial ground received thimbles from the 105-DR Reactor during the Ball 3X Project in 1954.

Waste Type: Equipment

Waste Description: This site received thimbles removed from the 105-DR Reactor during the Ball 3X work in 1954. Potential contaminants include: Co-60, Ni-63, Ag-108, Ba-133, Cs-137, Eu-152 and

154, Pu-238, 239 and 241, Ca-41, Cd-113, Kr-85, Zr-93, cadmium, lead.

Closure Info: Interim (2/1/2010): Remedial action at the 118-D-5 Burial Ground began on June 2, 2008, and continued through August 12, 2008. Approximately 1,943 bank cubic meters (BCM) (2,541 bank cubic yards [BCY]) of overburden material was stockpiled for use as clean fill. Approximately 314 BCM (411 BCY) of soil and debris were removed for disposal to the Environmental Restoration Disposal Facility (ERDF).

The depth of the excavation ranged from 2 meters (6.5 ft) in the easternmost portion of the excavation to 7 meters (23 ft) in the westernmost portion of the excavation. Although defined trenches were not observed on the geophysical data, the debris removed indicates that the 118-D-5 Burial Ground was located and remediated. Concrete, piping, and split tubes (reactor process tubes that were split to allow removal from the reactor core) were among the type of debris removed from the burial ground excavation. No thimbles were identifiable in debris found during the remediation of the burial ground.

A concrete junction vault located in the southern portion of the burial ground was opened prior to the start of the burial ground excavation and found to contain a breached 15-cm (6-in.) vitrified clay pipe. The pipeline is part of the 100-D-50:9, 1607-DR-3 Sanitary Sewer. The concrete junction vault and pipe located within the excavation were removed for disposal to ERDF. A section of the 100-D-50:10, Potable Water Supply Lines subsite, running east-west crosses the north end of the burial ground. The section of pipe within the excavation was removed and disposed. Another 15-cm (6-in.) pipe, part of the 100-D-50:10 Potable Water Supply Lines subsite, was found in the east sidewall of the easternmost excavation. The pipeline remains in place.

Code:	128-D-1	Classification:	Accepted
Names:	128-D-1; 100 D/DR Burning Pit	Reclassification	Interim No Action (4/12/2004)
Type:	Burn Pit	Start Date:	1/1/1944
Status:	Inactive	End Date:	1/1/1967
Description:	The waste site has been evaluated and determined to require No Action. Reviews of historical information demonstrated that this site is a duplicate entry of 128-D-2 and/or 628-3.		
Location:	This site location was indicated as being east of the intersection of the perimeter road and the railroad track that leads to the 184-D Powerhouse, just northeast of 100-D Area. The exact location of the site is unknown.		
Release Description:	An incident report (#180), dated September 29, 1951, states that radioactive material was detected in the burning pit during a routine, monthly survey. The contaminated material was removed and taken to the radioactive burial ground for proper disposal. Judging from the 1956 aerial photo, 628-3 appears to have been the main burning ground in operation at the time.		
Process Description:	The site was originally thought to have been used for the disposal of nonradioactive, combustible materials, such as paint waste, office waste, and chemical solvents.		
Waste Type:	Misc. Trash and Debris		
Waste Description:	The site was used for the disposal of nonradioactive, combustible materials, such as paint waste, office waste, and chemical solvents. The exact location of this waste site is unknown, although evidence of burning and waste materials were found at the site. On September 29, 1951, contaminated materials were found in the burning pit (Radiation incident: Class 1 #180). All contaminated materials were removed to the radioactive burial ground for proper disposal.		
Closure Info:	Interim: A Ground Penetrating Radar scan of the waste site's suspected location was done in		

2003. No underground anomalies were detected.

The location mapped as 128-D-1 and the surrounding area were examined in the field on March 12, 2003. The location, while level where staked, is on a side slope to the perimeter road and is covered with bunchgrasses, cheatgrass, and rabbitbrush. There are no areas of disturbance, old roads, or burned remnant debris in the area.

The lack of physical evidence (aerial photos and on the ground) at the mapped location, the proximity of two other burial pits, and the disconnect between Stenner et al. (1988) and Carpenter (1993) point to the conclusion that 128-D-1 is not a separate third burning pit, but a duplicate for either 128-D-2 or 628-3.

Code:	1607-D1	Classification:	Accepted
Names:	1607-D1; 1607-D1 Sanitary Sewer System; 1607-D1 Septic Tank; 1607-D1 Septic Tank and Associated Drain Field; 124-D-1	Reclassification	Interim Closed Out (5/14/2012)
Type:	Septic Tank	Start Date:	1/1/1944
Status:	Inactive	End Date:	1/1/1965
Description:	The waste site has been remediated and Interim Closed Out. It was a septic tank and associated drain field. The tank was 3.4 meters (11 feet) deep, constructed of reinforced concrete, and has a 125-person capacity (130 liters [35 gallons] per capita) with an average detention period of 24 hours. The walls and floor were 25 centimeters (10 inches) thick. The tile field was constructed of 10-centimeter (4-inch) vitrified pipe, concrete pipe, or drain tile with a minimum of 2.4 meters (8 feet) per capita. The laterals were open jointed and spaced 2.4 meters (8 feet) apart.		
Location:	The 1607-D1 waste site was located in close proximity to the patrol road that bends along the original perimeter fence bordering the site. The septic tank was located at Washington State Plane coordinates N150833, E574534.		
Related Sites/Structures:	The septic system is associated with the 1701-D Badgehouse and the 1709-D Patrol Change Room and Offices.		
Process Description:	The 1607-D1 septic system was one of five systems installed under Hanford Engineering Works in the 100-D Area. The septic system operated from 1944 to around 1965 when the 105-DR Reactor was shut down and received sanitary sewage from 100-D/DR entrance facilities that housed fire and patrol personnel.		
Waste Type:	Sanitary Sewage		
Waste Description:	This unit received an unknown amount of sanitary waste from the 1701-D Badgehouse (security check point) and the 1709-D Patrol Change Room and Offices.		
Closure Info:	Interim (5/14/2012): Remediation of the 1607-D1 waste site occurred from December 16, 2010 to February 4, 2011, and resulted in approximately 3,705 bank cubic meters (4,846 bank cubic yards) of waste materials being removed. The material was stockpiled, southeast of the septic tank, prior to disposal at the Environmental Restoration Disposal Facility. No overburden material was associated with the site. The drain field was excavated to a depth of 2 meters (6.6 ft) below ground surface. It consisted primarily of gray and brown sand, gravel, and sections of vitrified clay pipe. The outlet pipeline north of the waterline was excavated to about 1 to 1.5 meters (3.3 to 5 ft) bgs.		
	An active waterline (100-D-63) runs perpendicular to the waste site and crosses the 1607-D1 outlet pipeline along an existing service road over the site. An estimated 9 meter (30 ft) section of 1607-D1 outlet pipe was left in place to avoid impact to the waterline during excavation.		

Ecology agreed that samples would be taken from within and beneath the pipeline from either side of the waterline to determine if the portion of pipeline left in place met cleanup criteria. However, no material was present inside the pipe during sampling. Therefore, each pair of samples was collected from the bottom (below the pipe), one on the east side and one on the west side.

The septic tank excavation south of the waterline involved demolition of the reinforced concrete tank prior to removal. The septic tank contents, including battery debris, were removed. The reinforced concrete was sheared for removal. The septic tank excavation extended to a depth of 3.5 meters (11.5 ft) bgs. Excavation of the pipeline south of the active waterline included work beneath active power lines. A front-end loader was utilized to excavate this portion of the 1607-D1 pipeline to about 1.5 to 2 meters (5 to 6.6 ft) bgs.

Code: 116-DR-3	Classification: Accepted
Names: 116-DR-3; 105-DR Storage Basin Trench	Reclassification: Interim No Action (9/26/2012)
Type: Trench	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1955

Description: The waste site has been evaluated and determined to require No Action. It is a vegetation-free, cobble and soil-covered field that had been located within a larger area, bounded by permanent concrete markers posted with Underground Radioactive Material warning signs. The trench was estimated to be approximately 15 meters (50 feet) long.

Location: The trench was documented as being located directly south of the 105-DR Building, outside the exclusion fence, approximately 45.7 meters (150 feet) east of the 117-DR Reactor Exhaust Filter Building. The precise waste site location is conflicting and unclear.

Process Description: Water and sludge were pumped through an over ground line from the fuel storage basin to the trench. The trench was backfilled as soon as practical to avoid contamination spreads.

Waste Type: Sludge

Waste Description: The site received contaminated sludge and water removed from 105-DR Fuel Storage Basin.

Closure Info: Interim (9/26/2012): In November 1999, the Environmental Restoration Contractor (ERC) excavated a series of four trenches and two test pits in the 116-DR-3 WIDS site location and surrounding area in an attempt to locate the 116-DR-3 site. Based on field screening, there were no indications of contamination in any of the excavated trenches or test pits. No samples were collected. The depth of the trenches is not given in the documentation, but the trenches are described as shallow. The inference is that the trenches and test pits were likely excavated to a depth of less than 4.6 meters (15 ft) bgs.

In January 2000, an additional test pit was excavated (by Bechtel Hanford, Inc), at another potential location for the 116-DR-3 site. Based on field screening, there were no indications of contamination. Samples were not collected. This test pit was within the excavation of the 118-D-5 Burial Ground waste site. In 2008, the 118-D-5 Burial Ground was excavated and remediated.

In April 2011, confirmatory samples were collected from two, 20 foot deep test pits. Confirmatory sampling was performed, and the analytical results indicate that the residual concentrations of COPCs at this waste site meet the RAOs for direct exposure, groundwater protection, and river protection.

Code: 116-DR-4	Classification: Accepted
Names: 116-DR-4; 105-DR Pluto Crib	Reclassification Interim Closed Out (10/23/2000)
Type: Crib	Start Date: 1/1/1950
Status: Inactive	End Date: 1/1/1956

Description: The crib has been remediated and Interim Closed Out. It is no longer marked or posted.

Location: The crib was located approximately 61 meters (200 feet) southeast of the 105-DR Building and northeast of 116-DR-3.

Process Description: The site received liquid wastes from isolated reactor tubes containing ruptured fuel elements in the 105-DR Fuel Storage Basin. The site may have also received excess "ink" (liquid boron solution) used in the 3X safety system. The samples appeared to have no gravel.

Waste Type: Process Effluent

Waste Description: The site received liquid wastes from isolated tubes containing ruptured fuel elements in the 105-DR Fuel Storage Basin. The site may have also received excess "ink" (liquid boron solution) used in the 3X safety system.

Closure Info: Interim (10/23/2000): Remedial action at the 116-DR-4 site began on November 5, 1999. On November 8, 1999, the excavation reached the design limit at El. 138.2 meters (453.3 feet). During the actual excavation, the crib configuration was found to be a vertical, 20 centimeter (8 in) diameter, perforated feed pipe that emptied to a gravel filled excavation. No wooden structure was present. The feed pipe and portions of the gravel were removed and the excavation was sampled. A contamination plume was identified that required an additional 4.6 meters (15 ft) to be excavated, which was the final excavation depth. The final excavation elevation was El. 137.5 meters (451 feet). The final excavation was completed on January 3, 2000.

At the completion of remedial action and removal of the engineered structure, the excavation was approximately 237.9 square meters (2,560 square feet) in area with a maximum depth of approximately 4.6 meters (15 feet). Approximately 523 metric tons (575 tons) of contaminated material were disposed at ERDF. The excavation was backfilled with appropriate materials to the reference grade of 142 meters (466 feet).

Code: 116-DR-6	Classification: Accepted
Names: 116-DR-6; 1608-DR Liquid Disposal Trench; Wash Pad Liquid Waste Site 3C	Reclassification Interim Closed Out (10/23/2000)
Type: Trench	Start Date: 1/1/1953
Status: Inactive	End Date: 1/1/1965

Description: The site has been remediated and was Interim Closed Out on October 23, 2000. It is no longer marked or posted.

Location: The 116-DR-6 Liquid Disposal Trench was located approximately 37 meters (120 feet) east of 100-DR Reactor and approximately 1,120 meters (3,670 feet) from the Columbia River.

Process Description: The 116-DR-6 Trench received DR Reactor cooling water effluent during upgrade of the reactor emergency shutdown system (Ball 3X upgrade). During reactor shutdown, the trench also received water during maintenance of the cooling water effluent system. In addition, decontamination effluents from the DR fuel storage decontamination pad were routed into the trench. The trench received an estimated 7 million liters (26.5 million gallons) of liquid during its use between 1953 and 1965. The 116-DR-6 Trench has also been described as a crib (subsurface trench) that would sometimes receive effluent volumes great enough to cause

seepage to the surface with drainage across the ground surface to the east. Aerial photographs from the period of trench operation (1953-1965) do not indicate the presence of an open trench in the 116 DR-6 site area. Upon closure in 1965, the area of the 116-DR-6 Trench was covered with about 1.8 meters (6 feet) of soil.

Waste Type: Process Effluent

Waste Description: The site received diverted coolant during the Ball 3X upgrade. It also received diverted water when maintenance was necessary on the effluent system during a reactor shutdown. It is reported that the volume of liquids disposed of at this unit would cause it to overflow, and a solvent odor was present at the site on very hot days.

Closure Info: Interim (10/23/2000): Remedial action at the 116-DR-6 site began in November 2, 1999. Excavation of the site involved removing the overburden materials, the contaminated structure, and underlying contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Materials that were found to be contaminated were disposed of at the ERDF. The excavation design floor elevation was 138.5 meters (454 feet), but because field screening at that depth indicated the presence of radionuclides above the RAGs, an additional meter of soil was removed from the bottom of excavation. The final floor elevation was 137.5 meters (451 feet).

At the completion of remedial action and removal of the engineered structure, the excavation was approximately 485 square meters (5,218 square feet) in area with a maximum depth of approximately 4.8 meters (16 feet). Approximately 2,140 metric tons (2,354 tons) of material from the site were disposed of at the ERDF.

Code: 116-DR-7	Classification: Accepted
Names: 116-DR-7; 105-DR Inkwell Crib	Reclassification: Interim Closed Out (9/26/2000)
Type: Crib	Start Date: 1/1/1953
Status: Inactive	End Date: 1/1/1953

Description: The site was remediated in December 1999 by removing the structure and associated contaminated soil. As of September 2000, the excavation was still open, but was expected to be backfilled in the near future to a grade of elevation 142.0 meters (466 feet).

Location: The site was located south of the 105-DR Building and was approximately 1,100 meters (3,609 ft) from the Columbia River. The site was marked by a single concrete marker and was adjacent to a concrete pad that once supported a storage building.

Process Description: The crib was used to receive the liquid potassium borate solution (called "ink" because it resembles printers ink in color and viscosity) that was drained from the 3X system prior to the Ball 3X system upgrade. The requirements were re-evaluated in 2005. Institutional control (IC) information has been revised as directed by the U. S. DOE letter, 05-AMRC-0078, 1/4/05, following a review of the Institutional Controls (ICs) in the WIDS. For some sites, including this one, both the CVP/reclassification forms and WIDS had indicated that IC restrictions were needed. However, these sites were remediated only with the more restrictive shallow zone criteria; deep zone criteria were not used. Therefore, No Institutional Controls to prevent uncontrolled drilling or excavation into the deep zone (i.e., below 4.6 m [15 feet]) are required.

Waste Type: Process Effluent

Waste Description: Liquid potassium borate solution was drained from the 3X System prior to the Ball 3X System upgrade.

Closure Info: Interim (9/26/2000): Remedial action of this site began on December 7, 1999, and ended on

December 8, 1999. Approximately 59 metric tons (65 tons) of material were disposed at the Environmental Restoration Disposal Facility (ERDF). The excavation reached a final depth of 4.6 meters (15 feet) [at an elevation of 137.2 meters (450 feet)], and had an area of approximately 250.6 square meters (2,697 square feet).

Code:	116-DR-8	Classification:	Accepted
Names:	116-DR-8; 117-DR Crib; 117-DR Seal Pit Crib (CERCLA)	Reclassification	Interim Closed Out (9/20/2010)
Type:	Crib	Start Date:	1/1/1960
Status:	Inactive	End Date:	1/1/1964
Description:	<p>This waste site has been remediated and Interim Closed Out for CERCLA. The 117-DR Seal Pit Crib is documented in WIDS as two separate sites. The first site, 122-DR-1:6 was the portion of the Large Sodium Fire Facility that had been a RCRA TSD. The RCRA permit has been closed for hazardous/dangerous constituents. The second site, 116-DR-8, represents the radioactive constituents remaining at the site that was addressed under CERCLA. Portions of the 100-D-50:8 and 100-D-50:10 pipelines were encountered during remedial activities.</p> <p>Based on the results of the applicable cleanup verification package (CVP or RSVP) documents, authorization was given to remove the Soil Contamination Area and Underground Radioactive Material Area postings from this waste site.</p>		
Location:	The unit is located south of the exclusion area fence and directly east of the 118-DR-1 Burial Ground.		
Related Sites/ Structures:	The site received effluent from the 117-DR HEPA Filter Building seal pits and wash water from the 105-DR Large Sodium Fire Facility.		
Waste Type:	Process Effluent		
Waste Description:	The site received drainage from the 117-DR Building seal pits.		
Closure Info:	<p>Interim: Confirmatory sampling was conducted in July 2005. The sample results indicated several analytes were above regulatory limits. Remedial action at the 116-DR-8 waste site was performed from June 18 through July 24, 2008. Approximately 3,056 bank cubic meters (BCM) (3,997 bank cubic yards [BCY]) of soil overlying the crib was removed and stockpiled as overburden for potential use as clean backfill. The depth of overburden was determined using confirmatory sampling information and construction history for the crib. The site was then further excavated to a depth of approximately 6.8 meters (22 ft) below grade resulting in approximately 1,991 BCM (2,604 BCY) of material that was directly loaded out and disposed at the Environmental Restoration Disposal Facility (ERDF). Portions of the 100-D-50:8 and 100-D-50:10 pipelines, among others, were encountered during remediation.</p>		

Code:	116-DR-10	Classification:	Accepted
Names:	116-DR-10; 105-DR Fuel Storage Basin Cleanout Percolation; 105-DR Fuel Storage Discharge Pond; 105-DR Pond	Reclassification	Interim Closed Out (12/28/2010)
Type:	Pond	Start Date:	1/1/1984
Status:	Inactive	End Date:	1/1/1984
Description:	The waste site has been remediated and interim Closed Out. It was an open pit located in a		

	natural depression. The excavation has been backfilled and graded to match the natural terrain. The original natural depression remains.
Location:	The site is located east and slightly south of the 105-DR Reactor Building, just outside the HPS AC-5-40 permanent markers.
Related Sites/ Structures:	The site is associated with the 105-DR Fuel Storage Basin.
Process Description:	It consisted of an open pit that was excavated in a natural depression and used for disposal of processed water from the 105-DR Fuel Storage Basin cleanout during October and November 1984. The water had been used in the bottom of the fuel storage basin for the process of storing irradiated reactor fuel elements. The processed water was filtered to remove particulate, run through ion-exchange columns to remove colloidal material, and then held in 76,000-L (20,000-gal) batch tanks until sampling verified that radiological release criteria had been met. However, minute quantities of radionuclides remained in the processed water and presented the potential for accumulation of radionuclides at the bottom of the pond. The pit was 24.4 m (80 ft) long and 15.2 m (50 ft) wide with an area of 371.6 m ² (4,000 ft ²). The bottom of the pit was irregular with an average depth of 1.8 to 2.4 m (6 to 8 ft) (Beckstrom 1987).
Waste Type:	Water
Waste Description:	The unit received processed water from the 105-DR Fuel Storage Basin. During the cleanout of this basin, the radiologically contaminated shielding water was processed through a system using ion exchange columns. Before discharging the water to the unit, composite samples were taken to ensure that radionuclide concentrations were below release criteria in Table II of DOE Order 5480.1. Although the water was cleaned to applicable release limits, minute quantities (below release limits) of radionuclides remaining in the water accumulated in the soil at some low points in the floor. No known hazardous substances were present in the water; however, chemical analysis was not a standard practice during that period, and there is no evidence that one was performed. It should be noted that water removed from the 1608-DR is believed to be comparable to the storage basin water, and EP-TOX testing results for the 1608-DR water were negative.
Closure Info:	Interim: Remedial activities at the 116-DR-10 waste site began on November 11, 2008, and concluded on January 7, 2009. The depth ranged from 2.7 meters (9 ft) to 4 meters (13 ft), resulting in approximately 6,000 bank cubic meters (BCM) (7,847 bank cubic yards [BCY]) of soil being removed to the Environmental Restoration Disposal Facility. Approximately 2,462 BCM (3,220 BCY) of overburden material was stockpiled adjacent to the site. The historical information provided in Beckstrom (1987) was used to develop a remediation strategy for the percolation pond. Since the bottom of the pond ranged from 1.8 to 2.4 meters (6 to 8 ft) below surface grade and was then later backfilled to the local terrain, the remediation strategy consisted of removing the surface soil at the site to a depth of approximately 1.2 meters (4 ft) and stockpiling it at the site as overburden soil. The soil from 1.2 m (4 ft) to a depth of approximately 2.7 meters (9 ft) was to be excavated and direct loaded for disposal to the Environmental Restoration Disposal Facility (ERDF) since it delimited the original bottom of the pond that was reported as having residual radiological contamination.

Code:	118-DR-1	Classification:	Accepted
Names:	118-DR-1; 105-DR Gas Loop Burial Ground	Reclassification	Interim Closed Out (6/10/2010)
Type:	Burial Ground	Start Date:	1/1/1963
Status:	Inactive	End Date:	1/1/1964

Description: The waste site has been remediated and Interim Closed Out.

Location: The unit was located 183 meters (600 ft) south of the 105-DR Building.

Process Description: This site was a test loop burial ground and received about 20 cubic meters (26 cubic yards) of irradiated stainless steel assemblies. It was originally a gunnite-lined trench used to perform examination and sectioning of test assemblies, and later received irradiated metal assemblies from the 105-DR gas loop.

Waste Type: Equipment

Waste Description: This unit contains irradiated metal assemblies from the 105-DR Gas Loop.

Closure Info: Interim: Remedial action at the 118-DR-1 Burial Ground began on June 3, 2008, and continued through July 23, 2008. Approximately 1,673 bank cubic meters (BCM) (2,188 bank cubic yards [BCY]) of soil and debris was removed for disposal at ERDF. Approximately 221 BCM (290 BCY) of clean soil was removed from outside of the burial ground excavation footprint and stockpiled west of the burial ground excavation. The excavation area had a maximum depth of approximately 6 meters (20 ft), which included both shallow zone and deep zone soils. Contaminated debris included concrete, piping, metal and drums. The soil was removed during construction of a ramp into the excavation, allowing the excavator equipment access to continue to remove soil and debris at a greater depth. The ramp soil stockpile is not considered overburden; therefore, it was not included in the closeout sample design. This material will be used as backfill material during general backfill of the site.

A geophysical survey was conducted at the 118-DR-1 Burial Ground site in June 2004. The survey identified several geophysical anomalous zones within the survey boundary exhibiting the characteristics of buried debris. One anomalous waste item was encountered in the 118-DR-1 Burial Ground. A breached 208-L (55-gal) drum suspected of containing an undetermined amount of liquid was removed from the sidewall of the excavation. The drum, along with the soil directly below the drum, was placed on a plastic sheet within the burial ground footprint for waste characterization sampling. However, the drum was found to be empty so the soil that was removed with the drum was sampled for waste characterization. No spent nuclear fuel was discovered at the 118-DR-1 Burial Ground.

Code: 126-DR-1	Classification: Accepted
Names: 126-DR-1; 190-DR Clearwell Tank Pit; 100-DR Clearwells	Reclassification: Interim Closed Out (4/23/2009)
Type: Dumping Area	Start Date: 1/1/1975
Status: Inactive	End Date:

Description: The site has been remediated and interim closed out. The waste site was an open excavation area located between the 183-DR and 190-DR that originally contained four 1.42E+07 liter (3.75E+06-gallon) steel water storage tanks. The four tanks were removed in 1979 but the concrete slab foundations remained. The open excavation was used for disposal of demolition debris. The 126-DR-1 waste site was used as demolition waste burial ground between 1975 and 1988. The northwest section of the pit contained approximately 25% of the concrete slab area and a layer of debris waste that was 1.5 to 3 meter (5 to 10 feet) deep and covered with pit run backfill. The southern section of the pit was posted as an asbestos area.

Location: The waste site is located directly east of the site of the demolished 183-DR Water Treatment Facility and west of the demolished 190-DR building. It is west-southwest of the 105-DR Reactor Building.

Related Sites/Structures: The unit is associated with the 183-DR Water Treatment Facility and the 190-DR Main Pump House. Both of these facilities were involved in providing primary coolant water for the 105-

DR Reactor.

Process Description: The tanks were constructed in 1950 and operated until 1964 when the 105-DR Reactor was deactivated. The tanks were most likely dismantled by a salvage operator between 1978 and 1979 when all salvageable material was removed from the 190-D Main Pump Room. After the tanks were removed, the open excavation was used as a dump site for 100-D Area rubble. This site was also suspected of containing hazardous materials, including low-level radioactive waste because of uncontrolled dumping. Other waste that has been observed include paint and solvent cans, oil drums, sodium dichromate crystals, alum, creosote drums, herbicide cans, carbon tetrachloride containers, methanol containers, acetone containers, welding materials, laboratory glassware, furniture, and other solid wastes. The site may contain chromates in both the soil and underground piping because of the use of chromates in water treatment.

Waste Type: Misc. Trash and Debris

Waste Description: The unit contains demolition and inert waste from demolished facilities, including rubble from released portions of the 115-D/DR, and some rubble from 183-DR. In 1989, small amounts of friable asbestos were found scattered throughout the southern sector. The asbestos is believed to be the result of salvage operations during the 1970's. This site may contain chromates in both the soil and underground piping as a result of its association with water treatment. Because of this potential, it is closed to waste disposal. There is potential for chemical and radioactive contamination similar to that found in the 126-D-2 Burial Ground as uncontrolled dumping reportedly occurred at the site, but it is thought to be in much smaller volumes. Potential contaminants include: Chromate, lead, undetermined organic and inorganic chemicals.

Closure Info: Interim: Field work to remediate the 126-DR-1 Waste Site commenced on April 5, 2007, by demarking the excavation boundary. Heavy equipment was used to construct a ramp and prepare the haul road for transportation of the waste out of the area. The site was prepared by leveling the surface and constructing a soil berm around the open face of the waste pile. The soil berm was built to prevent the spread of contamination by rainwater and/or dust suppression water during excavation of the waste. An excavator was the primary piece of equipment used for excavation, sorting, segregation, and load out of waste material. The excavated material was directly loaded into roll-off boxes.

Remediation of the waste site concluded on July 24, 2008, after 23,790 metric tons (26,230 U.S. tons) were removed, transported, and disposed at Environmental Restoration Disposal Facility (ERDF). A radiation detector on the arm of the backhoe was used during excavation of this waste site. There was no evidence of radiation detected during the excavation activities.

The majority of waste was described as construction and demolition debris including concrete rubble, rebar, soil, and rocks. The debris also contained pipe insulation, suspected to contain asbestos; cans of dry paint; empty drums; welding material; laboratory glassware; steel beams; empty process tanks; electrical panels and fuses; actuators; empty cylinders; and structural steel, piping, valves, and duct work. There was no low-level radioactive waste; sodium dichromate crystals; alum; or containers of creosote, herbicide, carbon tetrachloride, or methanol discovered, as stated in the 100 Area Burial Ground ROD. A number of anomalous waste items were identified, characterized, and disposed during the project. The analytical data associated with these items are included in the RSVP. All but one of these items was determined to be inert debris and required no additional treatment prior to disposal at ERDF. The single exception was the discovery of three drums filled with white granular material on June 21, 2007. After treating, the material was spread out in small batches, neutralized with water, then mixed with soil and loaded into a roll-off box. The treated material was sampled (J16VK2) and analyzed prior to disposal at ERDF.

Code: 132-DR-1

Classification: Accepted

Names: 132-DR-1; 1608-DR Effluent Pumping Station; 1608-DR Waste Water Pumping Station **Reclassification** Interim Closed Out (9/22/2005)

Type: Pump Station **Start Date:** 1/1/1950

Status: Inactive **End Date:** 1/1/1964

Description: The site has been remediated and Interim Closed Out. The waste site consisted of an above ground section constructed of concrete block walls, a reinforced concrete floor, and a reinforced concrete roof with a composition surface and a below-grade section, constructed of reinforced concrete. The facility contained an operating level that contained the pumping equipment and an accumulation inlet chamber. The inlet chamber fed three discharge sump chambers. The contaminated liquid wastes were collected in the sumps and pumped to the 107-D/DR Retention Basin via a 41 centimeters (16 inches) diameter pipe.

Location: The pumping station was located adjacent to the northeast corner of the 105-DR Reactor Building within the 105-D/DR Exclusion Area Fence.

Related Sites/ Structures: The site received effluent from the 105-DR Reactor Building (118-DR-2).

Process Description: The facility contained three sumps to collect radioactively contaminated liquid wastes from the 105-DR Reactor Building. The contaminated liquid wastes were collected in the sumps for disposal by pumping to the 107-D/DR Retention Basin via a 41 centimeters (16 inches) diameter pipe.

Waste Type: Water

Waste Description: This site received water from reactor building drains containing trace amounts of low-level radionuclides and decontamination chemicals. Radionuclides were primarily miscellaneous fission and activation products. The decontamination chemicals consisted of sodium fluoride, oxalic acid, and citric acid. Water was pumped from the reactor collection pits into the reactor effluent lines near the reactor building and became part of the 107-DR effluent that was discharged to the Columbia River.

Closure Info: Interim: Decommissioning activities began in July 1987 and were completed on September 30, 1987. Decommissioning consisted of removal and disposal of approximately 3.85 cubic meters (136 cubic feet) of asbestos, the pump equipment and related piping, 4.8E+05 liters (1.27E+05 gallons) of sump water, and fifteen 208-liter (55-gallon) drums of sludge from the sumps. The material was transported to the 200 Area for disposal. The pump station was demolished and the site was leveled and graded. The site was released for unrestricted use based on the post-decontamination characterization results and the Dose Assessment of In Situ Burial of the 1608-DR Lift Station. Consequently, demolition and site grading were performed in 1987 using conventional heavy equipment. The structure was reduced to 5 meters (16.4 feet) below grade using a wrecking ball, the rubble was buried under 5 meters (16.4 feet) of clean fill. The site was graded to blend with the natural terrain.

Prior to demolition in 1987 samples of sludge from the sumps were taken and sent to the Pacific Northwest National Laboratory for analysis. The sludge was designated based on the equivalent concentration of various possible toxic compounds in the sludge. Equivalent concentrations were derived by making "worst-case" assumptions about the form of the various cations in the waste. The sludge did not designate as a hazardous waste. However, the concentrations of lead and phosphate were used to calculate a concentration of lead phosphate (7,300 ppm) that resulted in designating the sludge as a state-only toxic dangerous waste (i.e., extremely hazardous waste) according to Washington State regulations (WAC 173-303). The sludge was also radioactive, giving it the classification of radioactive mixed waste.

After removal of equipment, water, and sludge from the 1608-DR Effluent Pumping Station,

extensive radiological surveys of the floors, ceilings, and walls of the equipment room and sump areas and of the piping left in the facility were performed. At the time of decommissioning of the 1608-DR facility, the allowable residual contamination level (ARCL) calculation determined that the site would contribute less than 1 millirem/year to an overall hectare dose rate and, therefore, no further decontamination to reduce the source term was necessary and the facility could be buried in-situ.

In 2005, RESidual RADioactivity (RESRAD) modeling was performed in accordance with the RDR/RAWP (DOE-RL 2005) to support the interim closure decision. The RESRAD evaluation used the 1987 sampling data adjusted for decay from 1987 to 2005. The highest decayed value for each radionuclide was conservatively used in the RESRAD modeling.

Code: 600-30	Classification: Accepted
Names: 600-30; 100-DR Construction Lay-down Area	Reclassification: Interim Closed Out (8/10/2011)
Type: Dumping Area	Start Date:
Status: Inactive	End Date:

Description: The waste site has been remediated and Interim Closed Out. It was a 4 hectare (10 acre) site covered with scattered construction related debris. Vegetation at the site included grasses and rabbit brush. There were numerous areas that showed signs of plant stress ranging from reduced to no vegetation. There was also evidence of burning throughout the unit.

Location: The site was located approximately 420 meters (1378 feet) east of the junction of Route 2 North and Route 4 North. The northern edge of the site was approximately 12 meters (39 feet) south of Route 2 North. The western edge of the site lies east of a north-south line with the cross country transmission line leading from the 151-D Substation.

Process Description: Based on physical and photograph evidence, it appears to have been a lay-down yard during construction of 105-DR.

Waste Type: Construction Debris

Waste Description: Waste consists of broken sheet asbestos, buckets of tar, steel, galvanized pipe, rebar, angle iron, deteriorated keg of nails, burned and crushed drums, steel plate, chain, wire rope, bolts, metal hinges, shovels, gas and oil cans, welding rod cans, evidence of concrete blocks, metal tubing, and broken shipping boxes.

Closure Info: Interim: Initial remediation was performed in October and November 2008. Remediation consisted of scraping 0.5 to 1 meter (1.6 to 3.3 ft) of soil and debris into piles that were then loaded into Environmental Restoration Disposal Facility (ERDF) containers. Scraping removed the surface debris at the site. At two locations the excavation extended to 1.5 m (4.9 ft) deep to remove additional sub-surface material.

Additional materials discovered during remediation included lead acid batteries and a suspected fire extinguisher. The batteries stacked in two shallow pits were hand removed from the ground, drummed and then disposed at ERDF. There was no indication that the fire extinguisher had leaked hazardous material to the ground, therefore, it was disposed using anomalous media procedures. No other items were discovered during remediation that were considered anomalous. Approximately 7,400 bank cubic meters (BCM) (9,679 bank cubic yards [BCY]) of material were removed and disposed at ERDF.

Following initial remediation, verification sampling performed in August 2009 found a sample result that exceeded the direct exposure RAG for lead at 2,770 mg/kg. A walkdown of the area determined that lead acid debris was widespread. The recommended path forward was to

remediate a 45.7- by 6.1- by 0.6-m (150- by 20- by 2-ft) area, combining the rectangular area and a circular area.

Additional remediation was performed in February and March 2011, which involved scraping 0.5 to 1 meter (1.6 to 3.3 ft) of soil and debris across the northern boundary of the waste site (area 1) and the lead-contaminated area associated with sample locations F-5 and F-6 (area 2). Approximately 3,500 additional BCM (4,578 BCY) of soil was removed for disposal at ERDF.

100-FR-1

Code: 141-C **Classification:** Accepted
Names: 141-C; 141-C Animal Barn; Hog Barn; 100-F **Reclassification** Interim Closed Out (5/24/2006)
 Experimental Animal Farm Large Animal Barn &
 Biology Laboratory
Type: Laboratory **Start Date:** 1/1/1945
Status: Inactive **End Date:** 1/1/1976

Description: The waste site has been remediated and Interim Closed Out. The 141-C Building provided facilities for the long-term housing and care of research animals associated with the Experimental Animal Farm at 100-F Area.

Location: The site was located in the 100-F Experimental Animal Farm area, west of 132-F-2 (144-F Inhalation Laboratory), west of the north end of 107-F Retention Basin, and approximately 500 meters (1640 feet) northeast of the 105-F Reactor Building.

Process Description: Radiological studies on farm animals were conducted at the Experimental Animal Farm from 1945 through 1976. After 1976, the facility was re-located to the 300 Area.

A portion of the radiobiological experiments carried out at 100-F Experimental Animal Farm Area involved the use of large animals. The 141-C Building provided facilities for the long-term housing and care of these research animals. The building was a single L-shaped structure with each wing measuring 35.4 meters (116 feet) by 6.1 meters (20 feet) wide by 2.4 meters (8 feet) high. It was a Butler-type building of all-steel construction and was set on a concrete pad. The animal stalls were of steel construction and each was equipped with feeding and watering facilities.

A common drainage trench served all of the stalls. The 141-C Building included a dry well at its southwest corner that drained a loading dock at the facility's southwest end. It was likely that this dry well received only storm water runoff, but it may have been contaminated by wash water containing radioactive animal waste.

Waste Type: Water

Waste Description: Wash down water may have included the radionuclides used in the animal studies (iodine-131, strontium-90, cesium-137, and plutonium-239).

Closure Info: Interim: In 2004 confirmatory samples were collected from three test trenches. Remediation of the waste site consisted of the removal of soil and debris within the building footprint to a depth of approximately 1 meter (3 feet). Because arsenic, strontium-90, and multiple PAHs were detected above direct exposure RAGs in confirmatory sampling results, approximately 900 bank cubic meters (1,200 bank cubic yards) of soil and debris was excavated and staged onsite before disposal at the Environmental Restoration Disposal Facility (ERDF).

Exploratory trenches were excavated during remedial action efforts to confirm that the sewer lines formerly servicing the building were removed during previous decommissioning and demolition activities. No sewer lines were located by these excavations, and field instrumentation did not detect any beta-gamma or alpha activity above background levels.

Code: 100-F-4 **Classification:** Accepted
Names: 100-F-4; 108-F Building 12-Inch French Drain **Reclassification** Interim Closed Out (7/25/2002)
Type: French Drain **Start Date:**

Status: Inactive**End Date:**

Description: The site has been remediated and closed out. The french drain was constructed of 30-centimeter (12-inch) vitrified clay pipe, or similar material and was filled with gravel. A 1.3-centimeter (0.5-inch) steel pipe entered the drain from the 108-F Building. The drain was visible on Hanford photograph 106669-90-CN. Documentation suggests that the drain was likely removed as part of the layback zone of the 108-F Building excavation.

Location: The site was located adjacent to the southwest wall of the 108-F Building, just west of the building's southwest corner.

Related Sites/ Structures: The site served as a french drain for the 108-F building (site 100-F-36).

Waste Type: Water

Waste Description: The types and quantities of waste the unit received are unknown.

Closure Info: Interim: Site excavation was completed as reported in the 108-F Biological Laboratory D&D Project Closeout Report. The 100-F-4, 100-F-11, 100-F-15, and 100-F-16 french drains were removed during decommissioning and demolition activities and backfilled with clean material. The CVP report documents that the 100-F-4, 100-F-11, 100-F-15, and 100-F-16 french drains have been sampled and analyzed to verify attainment of the RAGs. At the completion of the remedial action, the total excavation was approximately 362.2 square meters (3898.7 square feet) in area with a depth of 4.6 meters (15.0 feet). No material from the sites was disposed of at the Environmental Restoration Disposal Facility as a result of the Remedial Action Project activities described here. Verified clean materials were used as backfill at the completion of the remedial action.

Code: 100-F-7**Classification:** Accepted**Names:** 100-F-7; Underground Fuel Tank - 1705-F Building**Reclassification:** Interim No Action (2/15/2005)**Type:** Storage Tank**Start Date:** 1/1/1948**Status:** Inactive**End Date:**

Description: The waste site has been evaluated and determined to require No Action. It is not distinguishable from the surrounding terrain of vegetation and scattered rocks.

Location: The tank was located north-northwest of the northwest corner of the 107-F Retention Basin fence and north-northeast of the northeast corner of 108-F Building.

Related Sites/ Structures: The tank supplied the oil furnace in the 1705-F Building heater room.

Process Description: The site was an underground fuel tank that supplied the oil furnace in the 1705-F Building Heater Room. The building was decommissioned and demolished in 1975. Debris and asphalt are strewn about the area. The tank's presence could not be confirmed with a metal detector due to multiple underground magnetic anomalies in the area. During an April 1999 visit, a survey grade GPS was used to locate the site based on its mapped coordinates. No evidence of the site could be found at this point.

Closure Info: Interim: The site consisted of an underground fuel tank that supplied the oil furnace in the 1705-F Building heater room. The tank was installed in 1948 and had a capacity of 3,800 Liters (1,000 gallons). When the 1705-F Building and surrounding facilities were demolished in 1975,

no mention was made to indicate the tank was also removed. The presence of the tank could not be confirmed during various site walkdowns or Geophysical surveys.

A site evaluation conducted as part of the Remaining Sites Verification Package attached to the Reclassification Form 2004-124 through field observations and focused sampling and analysis to assess the presence of contaminated media and to determine if the underground fuel tank was still present. One test pit was excavated at the center of the suspected underground fuel tank location, to a depth of 2.4 meters (8 feet), where native soil was encountered. The tank was not present. A soil sample was collected from the bottom of the test pit and submitted for laboratory analysis.

Code:	100-F-9	Classification:	Accepted
Names:	100-F-9; French Drain at East End of 105-F Storage Room (Northeast Corner)	Reclassification	Interim No Action (2/15/2005)
Type:	French Drain	Start Date:	
Status:	Inactive	End Date:	
Description:	The waste site has been evaluated and determined to require No Action. No remnants of this french drain have been identified, indicating that it was likely removed during the 105-F Reactor decommissioning project.		
Location:	The french drain was located adjacent to the northeast corner of the Miscellaneous Storage Room of the 105-F Reactor Building. The Storage Room was the eastern-most portion of the 105-F Reactor Building.		
Related Sites/ Structures:	105-F miscellaneous storage room and the 105-F Reactor.		
Waste Type:	Water		
Waste Description:			
Closure Info:	Interim: Field observations and confirmatory sampling were used to evaluate the site for reclassification. It was believed that the 100-F-9 French Drain received steam condensation via lines from the 105-F miscellaneous storage room building's steam heaters. The storage room facilitated the lunchroom, shower, and locker room and was demolished in 1999 during the 105-F Reactor decommissioning project. Apparently the french drain was removed during that operation.		
	<p>Focused sampling and analysis were used to determine if the french drain had been removed and if hazardous or radiological contaminants were still present. One test pit was excavated to native soil at the WIDS coordinates for the site. No remnants of the french drain were found, indicating that it was likely removed during the 105-F Reactor decommissioning project. No notable anomalies were detected that would suggest the presence of a french drain. However, french drains usually have a very subtle geophysical signature. The abundance of disturbed soil and buried debris from the 105-F Reactor D & D activities could hide an intact drain.</p>		

Code:	100-F-10	Classification:	Accepted
Names:	100-F-10; French Drain at East End of 105-F Storage Room (Southeast Corner)	Reclassification	Final Closed Out (10/28/2015)
Type:	French Drain	Start Date:	

Status: Inactive**End Date:**

Description: The site had been remediated and Interim Closed Out and later Final Closed Out. The french drain was totally removed during the excavation of the 100-F-19:2 pipeline remediation. The waste site consisted of a 91 centimeter (36-inch) concrete pipe buried to an unknown depth. The upper surface was a few inches above grade and was cobble-filled. The unit was fed by one or more 2.5 centimeter (1 inch) steel pipes coming from the 105-F Building. Only one pipe was visible. A 1.9 centimeter (0.75-inch) pipe also entered the top of the drain.

Location: The french drain was outside and adjacent to the southeast corner of the Miscellaneous Storage Room of the 105-F Reactor Building. The Storage Room was the eastern-most portion of the 105-F Reactor Building.

Waste Type: Water

Waste Description:

Closure Info: Interim: (Interim Closed Out) The remediation area was divided into four zones based on process history and structure depth. The 118-F-8:1 Zone 1 was the underlying soils beneath the Fuel Storage Basin. A portion of Zone 1 was later renamed 118-F-8:3. The 118-F-8:1 was re-defined as the other zones (Zones 2, 3, and 4).

Removal and disposal activities at the 105-F site began in 1999 and concluded in December 2003. Excavation of the site involved removing the building structures, debris, and underlying contaminated soil. The 105-F D&D activities resulted in removal of above and below-grade structures outside of the 105-F Reactor core shield walls to a minimum of 0.9 meters (3 ft) below surrounding grade. Approximately 22,132 metric tons (24,345 tons) of contaminated materials were disposed of at ERDF. The equipment decontamination pads were areas where decontamination of equipment occurred during the removal actions and ISS activities. In 2003, approximately 1 meter (3.3 ft) of contaminated soil from equipment decontamination activities was removed and disposed of at ERDF.

Zone 1 was soil beneath the fuel storage basin (FSB), located on the south side of the 105-F Reactor Building. The FSB held treated water and served as an underwater collection, storage and transfer facility for irradiated fuel elements discharged from the reactor. The FSB was approximately 23.8 by 21.6 by 6.4 meters (78 by 71 by 21 ft) deep. Deactivation of the storage basin occurred in 1970. Deactivation was accomplished by pumping the majority of the water from the basin and filling with sand. The Zone 1 Fuel Storage Basin was excavated and removed in 2003. The south and east portions of the FSB excavation are not included in this activity. They were remediated with the adjacent 100-F-19:2 pipeline excavation. Contaminated soil on the western side of the FSB became subsite 118-F-8:4. Remediation of the 118-F-8:4 soil area was deferred to the Remedial Action Project to be completed at a later date (see CVP-2007-00004).

Zone 2 was the valve pit walls. They were removed to a minimum of 0.9 meters (3 ft) below the surrounding surface grade. Because of elevated levels of hexavalent chromium and polychlorinated biphenyls (PCBs) in the valve pit floor, the concrete floor was removed and disposed of at ERDF. The floor of the Zone 2 valve pit was located 4.8 meters (15.8 ft) below surrounding grade. The soils underlying the former floor were sampled and analyzed for hexavalent chromium and PCBs.

Zone 3 included the shallow zone structures (4.6 meters [15 ft] or less below ground surface). It included the solids feed area, the gas recirculation tunnel, the trench under the accumulator room, the east water tunnel, and the flow laboratory basement. The gas recirculation tunnel was removed so that the underlying pipe tunnel (in Zone 4) could be accessed. All of the other

below-grade walls, including ceilings, associated with the Zone 3 structures were removed to a minimum of 0.9 meters (3 ft) below the surrounding grade. Because of elevated levels of hexavalent chromium, the solids feed area concrete floor was removed and disposed of at ERDF. The former floors of the solids feed area and the gas recirculation tunnel were located, at respective depths of 3.4 meters (11 ft) and 4.4 meters (14.5 ft). The floors of the trench under the accumulator room, the east water tunnel, and the flow laboratory are located at the respective depths of 4.4 meters (14.5 ft), 3.8 meters (12.5 ft) and 3 meters (10 ft) below surrounding grade. The soils underlying the former solids feed area floor were sampled and analyzed for hexavalent chromium.

Zone 4 included the deep zone structures. The concrete floors of the Zone 4 structures were within the deep zone (greater than 4.6 meters [15 ft] below ground surface). Zone 4 included the east and west inlet water tunnels, the pipe tunnel, the 315 and 316 exhaust plenums, and the southeast tunnel. All of the concrete ceilings associated with zone 4 structures were removed. All of the Zone 4 walls were removed to a minimum of 0.9 meters (3 ft) below the surrounding surface grade. None of the Zone 4 concrete floors required removal and were left in place. The floors of the east and west inlet water tunnels, the pipe tunnel, the 315 plenum, the 316 plenum, and the southeast tunnel were located at the respective depths of 4.6 meters (15 ft), 5 meters (16.5 ft), 4.9 meters (16 ft), 5 meters (16.5 ft) and 6.1 meters (20 ft) below surrounding grade.

Because the removal of the 100-F-10 French Drain was inadvertently omitted from the 100-F-19:2 pipeline Closeout Verification Package (CVP-2001-00003) report, the activity was included in the 118-F-8:1 and 118-F-8:3 report (CVP-2003-00017) to document the french drain's reclassification to Interim Closed Out. The 100-F-10 French Drain was completely removed during excavation of the 100-F-19:2 pipelines. The cleanup verification sampling results for the 100-F-10 French Drain were included in the CVP-2001-00003 report. 100-F-10 was Final Closed Out in 2015.

Final (10/28/2015): (Final Closed Out) Thirteen 100-F Area waste sites were reclassified to Final Closed out on form 2015-078. They had all previously been classified as Interim Closed Out. The waste sites included on this reclassification form are 100-F-10, 100-F-19 (and subsites 1,2 and 3), 100-F-29, 100-F-34, 116-F-2, 116-F-6, 116-F-9, 116-F-12, subsites 118-F-8:3 and :4, UPR-100-F-1. The Record of Decision (ROD) for the 100-FR-1, 100-FR-2, 100-FR-3, 100-IU-1, 100-IU-2 and 100-IU-6 Operable Units has defined these waste sites as all requiring institutional controls to restrict excavation into the deep zone (greater than 4.6 meters or 15 feet below the ground surface). However, no further remedial actions are required.

Institutional Control Boundaries have been defined to be broadly inclusive of waste site groups. Not all areas within these boundaries contain residual contamination greater than 4.6 meters (15 ft) below ground surface. An image of four Institutional Control Boundaries inside 100F Area was attached to the 2015-078 Reclassification form (and included in the WIDS library).

Code: 100-F-11	Classification: Accepted
Names: 100-F-11; 108-F Building 18-Inch French Drain	Reclassification: Interim Closed Out (7/25/2002)
Type: French Drain	Start Date:
Status: Inactive	End Date:
Description: The site has been remediated and closed out. The french drain was constructed of 46-centimeter (18-inch) concrete pipe of unknown length. The unit had no cover and was filled with gravel. A 2.5-centimeter (1-inch) steel pipeline entered the drain from the 108-F Building. The drain was visible on Hanford photograph 106669-90-CN.	

Documentation suggests that the french drain was likely removed with the layback zone of the

108-F Building.

Location: The unit was adjacent to the southwest corner of the 108-F Building.

Related Sites/ Structures: This site served as a french drain for the 108-F building (site 100-F-36).

Waste Type: Water

Waste Description:

Closure Info: Interim: Site excavation was completed as reported in the 108-F Biological Laboratory D&D Project Closeout Report. The 100-F-4, 100-F-11, 100-F-15, and 100-F-16 french drains were removed during decommissioning and demolition activities and backfilled with clean material. The CVP report documents that the 100-F-4, 100-F-11, 100-F-15, and 100-F-16 french drains have been sampled and analyzed to verify attainment of the RAGs. At the completion of the remedial action, the total excavation was approximately 362.2 square meters (3898.7 square feet) in area with a depth of 4.6 meters (15.0 feet). No material from the sites was disposed of at the Environmental Restoration Disposal Facility as a result of the Remedial Action Project activities described here. Verified clean materials were used as backfill at the completion of the remedial action.

Code: 100-F-12	Classification: Accepted
Names: 100-F-12; 36-Inch French Drain at 105-F Building	Reclassification: Interim No Action (2/15/2005)
Type: French Drain	Start Date:
Status: Inactive	End Date:

Description: The site has been evaluated and determined to require No Action. The area where the french drain was located was a flat, cobble-covered area. The french drain was not visible on the surface due to previous building demolition activities.

Location: The site was located at the northeast corner of the 105-F Reactor Building, adjacent to a steel door marked "Electrical Equipment Room No. 1".

Related Sites/ Structures: The site was associated with the 105-F Reactor Building and sitecode 100-F-61.

Process Description: The site was a French drain, 0.9 meters (3 feet) diameter concrete pipe, buried to an unknown depth. The upper surface of the drain was a few inches above grade and had a steel lid (manhole cover) marked "confined space." The drain was fed by four 19-millimeter (0.75 inch) and one 25-millimeter (1-inch) steel pipes coming from the northeast corner of the 105-F Building. Based on the pipe size it is believed that these pipes may have been steam condensate lines associated with the building's steam heaters.

Waste Type: Water

Waste Description:

Closure Info: Interim: The french drain was not visible on the surface due to previous building demolition activities. A test pit was excavated to locate the french drain. The drain structure was found and soil samples were collected. Stained soil was discovered at a depth of 1 meter (3.3 ft) on the north side of the test pit. It was determined that the stained soil was not part of the french drain and became sitecode 100-F-61.

Although the 100-F-12 french drain was a No Action site, the drain structure was removed with the 100-F-61 soil remediation on February 23, 2011. The removed material was disposed to ERDF. The site backfilled with clean borrow material.

Code: 100-F-16 **Classification:** Accepted

Names: 100-F-16; 108-F Building 30-Inch French Drain **Reclassification** Interim Closed Out (7/25/2002)

Type: French Drain **Start Date:**

Status: Inactive **End Date:**

Description: The site has been remediated and closed out. The french drain was constructed of steel pipe, filled with gravel, and covered with a steel lid. The drain extended 18 centimeters (7 inches) above grade and was 76 centimeters (30 inches) in diameter. Documentation suggests that the drain was likely removed with the layback zone of the 108-F Building excavation.

Location: The drain was next to the south wall of the 108-F Building east loading dock, between the gas cylinder storage shed and the loading dock exit stairs.

Related Sites/ Structures: This site served as a french drain for the 108-F building (site 100-F-36).

Waste Type: Water

Waste Description: The dates of operation and type and quantity of waste are unknown.

Closure Info: Interim: Site excavation was completed as reported in the 108-F Biological Laboratory D&D Project Closeout Report. The 100-F-4, 100-F-11, 100-F-15, and 100-F-16 french drains were removed during decommissioning and demolition activities and backfilled with clean material. The CVP report documents that the 100-F-4, 100-F-11, 100-F-15, and 100-F-16 french drains have been sampled and analyzed to verify attainment of the RAGs. At the completion of the remedial action, the total excavation was approximately 362.2 square meters (3898.7 square feet) in area with a depth of 4.6 meters (15.0 feet). No material from the sites was disposed of at the Environmental Restoration Disposal Facility as a result of the Remedial Action Project activities described here. Verified clean materials were used as backfill at the completion of the remedial action.

Code: 100-F-18 **Classification:** Accepted

Names: 100-F-18; 105-F Condensate Drain Field; **Reclassification** Interim No Action (2/15/2005)
Underground Tank at 105-F Building

Type: Drain/Tile Field **Start Date:**

Status: Inactive **End Date:**

Description: The site has been evaluated and reclassified to No Action. It was likely to have been demolished during the 105-F Reactor Interim Safe Storage Project.

Location: The site was located adjacent to the north wall of the 105-F Reactor supply fan room of the Building, which was the northwest corner of the 105-F Reactor Building.

Related Sites/ Structures: 118-F-8, 105-F Reactor and Fan Room.

Process Description: The site was not visible at the surface, but was identifiable by a 20-centimeter (8-inch) diameter, 91-centimeter (36-inch) long steel pipe welded to what appeared to be the top of a 91-centimeter (36-inch) diameter steel tank. The upper surface of the "tank" was above grade. Liquid was observed through the steel pipe when the site was investigated for the 100-F Technical Baseline Report.

Waste Type: Water

Waste Description:

Closure Info: Interim: The area adjacent to the 105-F fan room was excavated in 1994, during the reactor Interim Safe Storage project. It is assumed the tank was removed at that time.

One test trench was excavated to explore the location specified in the 2/05/04 Geophysical Survey report of a metallic geophysical anomaly. The survey was done to determine if the tank and drain field were present or if they were completely, or partially, removed during decommissioning and demolition activities. No remnants of the tank or drain field were found, indicating that the "tank" and drain field (if present) were likely removed during the 105-F Reactor Interim Safe Storage Project. During the reclassification investigations for the Remaining Sites Verification Package (RSVP) (2004-137) a focused sampling design was implemented on October 22, 2004, in accordance with Work Instruction for 100-F-18 Condensate Drain Field and Underground Tank. The site was investigated through field observations and focused sampling and analysis for the purpose of determining if hazardous or radiological contaminants were present.

No remnants of the tank or drain field were found, indicating that the tank and drain field (if present) were likely removed during the 105-F Reactor Interim Safe Storage Project. One confirmatory soil sample and one field duplicate sample were collected at the native soil interface from the bottom of the test trench.

Code: 100-F-19	Classification: Accepted
Names: 100-F-19; 1904-F Process Sewer; Contaminated Underground Lines; Effluent Water System; 100-F Reactor Cooling Water Effluent Underground Pipelines	Reclassification: Final Closed Out (10/28/2015)
Type: Radioactive Process Sewer	Start Date: 1/1/1945
Status: Inactive	End Date: 1/1/1965

Description: This site included the 100-F Reactor cooling water effluent lines. They were divided into three subsites. All three subsites have been remediated, were Interim Closed Out and later Final Closed Out. Therefore the parent site was also considered to be Interim Closed Out and Final Closed Out. The large effluent lines that ran between the 105-F Reactor Building and the 107-F Retention Basin were underground lines at the western end of the lines and above ground for the remainder. The above ground portions of each line had previously been removed, cut into sections, and placed inside the retention basin.

Subsite 1 contained a pipeline that was constructed of steel (152 centimeters [60 inches] in diameter, 235 meters [770 feet] long) and concrete (182 centimeters [72 inches] in diameter, 280 meters [920 feet] long) from the basin to the 1904-F Outfall Structure.

Subsite 2 consisted of effluent lines that transported 105-F Reactor cooling water from the reactor core to the 107-F Retention Basin (three lines - one measuring 106-centimeters [42-inches] in diameter and 635 meters [2,080 feet] long, a second measuring 152 centimeters [60

inches] in diameter and 283 meters [930 feet] long and the third measuring 105 centimeters [41 inches] in diameter and 238 meters [781 feet] long). The large effluent lines running between the 105-F Reactor Building and the 107-F Retention Basin were underground for the western section of the lines and above ground for the remainder. The above ground portions of each line had previously been removed, cut into sections, and placed in the retention basin. They were covered with a layer of soil.

Subsite 3 consisted of the effluent line that ran from the 105-F Reactor and the 182-F and 183-F Buildings to the 116-F-1 Lewis Canal. It also included all associated expansion and valve boxes, but excluded the retention basin, outfall structure, and those effluent lines that were within the confines of the 105-F Reactor Building. Other excluded lines were all the clean water pipelines that were upstream of the reactor building, all underground lines that were unique to the Experimental Animal Farm, and the smaller reactor effluent lines on the southwest side of the reactor.

Effluent pipe ends were exposed on the east side of the 100-F Area entrance road.

Location: Subsite 100-F-19:1 included the pipelines from the 107-F Retention Basin that extend to the north where they met the 116-F-8 (1904-F) Outfall Structure. These pipelines are in the northeast section of the 100-F Area, near the 146-F biology facilities, the 100-F Retention Basins, and the 100-F Outfalls.

Subsite 100-F-19:2 included the main effluent lines that exited the 105-F Reactor Building, extending to the east and then curving to the north where they discharged to the 107-F Retention Basin. This subsite also included the pipeline that exited the north side of the reactor and extended to the west emptying into the Lewis Canal.

Subsite 100-F-19:3 included pipelines from both the 182-F and 183-F Buildings to the Lewis Canal, and the process sewer line connecting 182-F and 183-F.

Related Sites/ Structures: Related sites include the 105-F Reactor Building, the 1608-F Lift Station, the 107-F Retention Basin (116-F-14), the 1904-F Outfall Structure (116-F-8), the 107-F Liquid Waste Disposal Trench (116-F-2), and the 116-F-1 Lewis Canal. The water treatment pipelines are site 100-F-26, the clean water pipelines are 100-F-41, and pipes associated with the animal farm are 100-F-29.

Process Description: Effluent water passed from the reactor rear face and flowed via gravity through the underground effluent lines, junction boxes and diversion boxes to the retention basins where it was held up for a short period of time to allow thermal and radiological cooling before being released through the outfall structure to the Columbia River. These pipelines carried radioactive effluent from the 100-F Area Retention Basins to the 1904-F and 116-F-16 outfalls and spillways.

During periods of reactor fuel cladding ruptures, some effluent was diverted to an open trench. Cooling of the 105-F Reactor during operation required that a large volume, approximately 380,000 liters/minute (100,000 gallons/minute) of high quality water be continuously supplied to the reactor on a single pass basis. This water was obtained from the Columbia River and, after chemical treatment and filtering in the water treatment plant, was directed through the reactor process tubes. As it passed through the reactor, the cooling water became radioactive to a degree due to irradiation of the remaining impurities and the pick-up of corrosion products from within the piping and process tubes. Upon exiting from the reactor, the coolant was conveyed to the 107-F Retention Basin by gravity flow via a large diameter pipe, the effluent water line. After being retained in the 107-F Retention Basin long enough to permit decay of the short half-life radioactive elements, the water flowed through another large diameter pipe to the 116-F-8 (1904-F) Outfall Structure.

Occasionally during reactor operation, failure of the protective cladding on one of the fuel elements would occur. The reactor coolant would then pick up debris from this failure and, for a limited time, be contaminated with long half-life radionuclides. On these occasions, the effluent would not be permitted to return directly to the river, but would be diverted from the 107-F Retention Basin to the 107-F Liquid Waste Disposal Trench which was located near the retention basin. The trench functioned as a large filter with the highly radioactive particulate matter being retained in the soil below the trench and the purified water eventually finding its way back to the river.

Waste Type: Process Effluent

Waste Description: The waste was radioactively contaminated steel piping, concrete and soil. Reactor cooling water became radioactively contaminated as it passed through the reactor core. Activation products created in the water included calcium-41, chromium-51, and zinc-65. Activation products from the reactor core that were picked up and transported by the cooling water included tritium, carbon-14, cobalt-60, nickel-63, and europium-152/154/155. Fuel element fission products such as strontium-90, and cesium-137, as well as transuranics such as plutonium-239/240 were introduced into cooling water due to fuel cladding failures. Concentrations of radionuclides in cooling water during normal reactor operations were approximately 0.2 microcuries/liter. Concentrations of radionuclides have built up in rust flakes and scale on the inner surfaces of the pipelines and in sludge in the diversion and junction boxes. Average beta-gamma concentrations for the effluent line scale and junction/diversion boxes are 83,000 and 120,000 picocuries/liter, respectively. Average plutonium-239/240 concentrations are 66 picocuries/gram for the effluent line scale and 720 picocuries/gram for the sludge at the bottom of the diversion and junction boxes. Direct readings of the bottom of the effluent lines averaged approximately 40,000 counts/minute with a Geiger-Mueller probe. Additional chemicals were added to the effluent for purposes of water treatment. These included aluminum sulfate (alum), with excess hydrated calcium oxide, sulfuric acid, chlorine, and sodium dichromate. Water pH was maintained at about 7.5, and the free chlorine residual was approximately 0.2 milligrams/liter.

Closure Info: Final (10/28/2015): (Final Closed Out) Thirteen 100-F Area waste sites were reclassified to Final Closed out on form 2015-078. They had all previously been classified as Interim Closed Out. The waste sites included on this reclassification form are 100-F-10, 100-F-19 (and subsites 1,2 and 3), 100-F-29, 100-F-34, 116-F-2, 116-F-6, 116-F-9, 116-F-12, subsites 118-F-8:3 and :4, UPR-100-F-1. The Record of Decision (ROD) for the 100-FR-1, 100-FR-2, 100-FR-3, 100-IU-1, 100-IU-2 and 100-IU-6 Operable Units has defined these waste sites as all requiring institutional controls to restrict excavation into the deep zone (greater than 4.6 meters or 15 feet below the ground surface). However, no further remedial actions are required.

Institutional Control Boundaries have been defined to be broadly inclusive of waste site groups. Not all areas within these boundaries contain residual contamination greater than 4.6 meters (15 ft) below ground surface. An image of four Institutional Control Boundaries inside 100F Area was attached to the 2015-078 Reclassification form (and included in the WIDS library).

This Site has the Following SubSites:

Code: 100-F-19:1

Names: 100-F-19:1; 100-F Reactor Cooling Water Effluent Underground Pipelines (North Group)

Code: 100-F-19:2

Names: 100-F-19:2; 100-F Reactor Cooling Water Effluent Underground Pipelines (South Group)

Code: 100-F-19:3

Names: 100-F-19:3; 100-F Reactor Cooling Water Effluent Underground Pipelines (West Group)

Code: 100-F-19:1

Classification: Accepted

Names: 100-F-19:1; 100-F Reactor Cooling Water Effluent Underground Pipelines (North Group) **Reclassification** Final Closed Out (10/28/2015)

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The 100-F-19:1 has been remediated, Interim Closed Out and later Final Closed Out. The North Pipelines subsite included piping that ran north-northwest from the north side of the 116-F-14 Retention Basin to the 116-F-8 Outfall Structure and also included a second underground effluent pipeline that extended northwest from the 116-F-14 Retention Basin to a junction box and to the 116-F-16 Outfall Structure. The pipelines in this area have been removed including miscellaneous co-located pipelines that were within the excavation boundary.

Location: These pipelines were in the northeast section of the 100-F Area, near the 146-F biology facilities, the 100-F Retention Basins, and the 100-F Outfalls.

Process Description: These pipelines carried radioactive effluent from the 100-F Area Retention Basins to the 1904-F and 116-F-16 outfalls and spillways.

Waste Type: Not Specified

Waste Description: The waste was radioactively contaminated steel piping, concrete and soil.

Closure Info: Interim (5/22/2002): (Interim Closed Out) The 100-F-19:1 North Pipelines, 100-F-19:3 West Pipelines, 100-F-34 Biology Facility French Drain, and the 116-F-12 French Drain were remediated as a group, documented in CVP-2001-00002. The group is referred to as the 100-F-19:1 site. The 100-F-19:1 site remedial action began on August 7, 2001. Excavation of the site involved removing overburden materials, pipelines, french drain structures, and contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Shallow zone excavation occurred both in the vicinity of the 100-F-19:3 West Pipelines and in the vicinity of the 100-F-19:1 North Pipelines, with a maximum depth of 4.6 meters (15 ft). The deep zone excavation occurred in the southern half of the 100-F-19:1 North Pipelines section of the remedial action, with a approximate maximum depth of 5.0 meters (16 ft). The elevation of the bottom of the excavation varied, but averaged approximately 119.6 meters (392.4 ft). At the completion of remedial action in August 2001, the excavation was approximately 25,710 sq. meters (276,740 sq. ft.) in area. Approximately 56,335 metric tons (62,099 tons) of contaminated materials from the site were disposed of at the ERDF.

These sites meet the cleanup standards specified in the Amendment to the Interim Action Record of Decision for the 100-BC-1, 100-DR-1, and Operable Units (ROD). Excavation of the site involved removing overburden materials, pipelines, french drain structures, and contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Shallow zone excavation occurred both in the vicinity of the 100-F-19:3 West Pipelines and in the vicinity of the 100-F-19:1 North Pipelines, with a maximum depth of 4.6 meters (15 ft). The deep zone excavation occurred in the southern half of the 100-F-19:1 North Pipelines section of the remedial action, with a approximate maximum depth of 5.0 m (16 ft). The elevation of the bottom of the excavation varied, but averaged approximately 119.6 m (392.4 ft).

The results showed that the materials from the 100-F-19:3 subsite containing COCs at concentrations exceeding RAGs have been excavated and disposed of. Remedial actions were performed so as to allow rural-residential use of shallow zone soils (i.e., surface to 4.6 meters [15 feet] deep) and to protect groundwater and the Columbia River. All cleanup verification samples for the 100-F-19:3, 100-F-34 and 116-F-12 sites are listed under 100-F-19:1.

Final (10/28/2015): (Final Closed Out) Thirteen 100-F Area waste sites were reclassified to Final Closed out on form 2015-078. They had all previously been classified as Interim Closed Out. The waste sites included on this reclassification form are 100-F-10, 100-F-19 (and subsites 1,2 and 3), 100-F-29, 100-F-34, 116-F-2, 116-F-6, 116-F-9, 116-F-12, subsites 118-F-8:3 and :4, UPR-100-F-1. The Record of Decision (ROD) for the 100-FR-1, 100-FR-2, 100-FR-3, 100-IU-1, 100-IU-2 and 100-IU-6 Operable Units has defined these waste sites as all requiring institutional controls to restrict excavation into the deep zone (greater than 4.6 meters or 15 feet below the ground surface). However, no further remedial actions are required.

Institutional Control Boundaries have been defined to be broadly inclusive of waste site groups. Not all areas within these boundaries contain residual contamination greater than 4.6 meters (15 ft) below ground surface. An image of four Institutional Control Boundaries inside 100F Area was attached to the 2015-078 Reclassification form (and included in the WIDS library).

The SubSite is Part Of:

Code: 100-F-19

Names: 100-F-19; 1904-F Process Sewer; Contaminated Underground Lines; Effluent Water System; 100-F Reactor Cooling Water Effluent Underground Pipelines

Code: 100-F-19:2

Classification: Accepted

Names: 100-F-19:2; 100-F Reactor Cooling Water Effluent Underground Pipelines (South Group)

Reclassification Final Closed Out (10/28/2015)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The 100-F-19:2 Reactor Cooling Water Effluent Pipeline and co-located sites, (116-F-11 Cushion Corridor French Drain, UPR-100-F-1 Sewer Line Leak, and the 100-F-29 Experimental Animal Farm Pipelines), were remediated as a group and Interim Closed Out in CVP-2001-00003. It was later classified as Final Closed Out.

Location: This group of effluent lines exited the reactor building, extended to the east, and to the north where they discharged to the 107-F Retention Basin. A portion of these pipelines were above ground before emptying into the retention basin. Another section of pipe in this subsite ran from the north side of the reactor and emptied into Lewis Canal.

Waste Type: Not Specified

Waste Description: The waste was radioactively contaminated steel piping, concrete and soil.

Closure Info: Interim: (Interim Closed Out) Remedial Action ran from August 2001 until December 2002. The 100-F-19:2 Reactor Cooling Water Effluent Pipeline and co-located sites, (116-F-11 Cushion Corridor French Drain, UPR-100-F-1 Sewer Line Leak, and the 100-F-29 Experimental Animal Farm Pipelines), were remediated as a group and documented in CVP-2001-00003. The group is referred to as the 100-F-19:2 site in the document. The unplanned release was within the footprint of the 100-F-29 pipeline excavation. The elevation of the bottom of the excavation was approximately 124.7 meters (409 ft) upon completion. The excavation area was approximately 19,000 square meters (205,000 sq. ft) with a maximum depth of approximately 5 meters (16 ft) and an average depth of approximately 3.7 meters (13 ft). Removal of the 100-F-29 pipelines near the northwest corner of the 116-F-14 (107-F Retention Basin) required shallower excavation, averaging approximately 1 meter (3 ft) in depth. Little evidence of the 116-F-11 french drain site was found during excavation of the 100-F-19:2 pipelines. The location of the french drain was excavated and sampled to the design elevation 4.6 meters (15 ft).

Remediation included excavation of overburden, piping, debris and contaminated underlying soil. Approximately 39,347 metric tons (43,373 tons) of material including soil, debris and piping were removed and disposed at ERDF.

Final (10/28/2015): (Final Closed Out) Thirteen 100-F Area waste sites were reclassified to Final Closed out on form 2015-078. They had all previously been classified as Interim Closed Out. The waste sites included on this reclassification form are 100-F-10, 100-F-19 (and subsites 1,2 and 3), 100-F-29, 100-F-34, 116-F-2, 116-F-6, 116-F-9, 116-F-12, subsites 118-F-8:3 and :4, UPR-100-F-1. The Record of Decision (ROD) for the 100-FR-1, 100-FR-2, 100-FR-3, 100-IU-1, 100-IU-2 and 100-IU-6 Operable Units has defined these waste sites as all requiring institutional controls to restrict excavation into the deep zone (greater than 4.6 meters or 15 feet below the ground surface). However, no further remedial actions are required.

Institutional Control Boundaries have been defined to be broadly inclusive of waste site groups. Not all areas within these boundaries contain residual contamination greater than 4.6 meters (15 ft) below ground surface. An image of four Institutional Control Boundaries inside 100F Area was attached to the 2015-078 Reclassification form (and included in the WIDS library).

The SubSite is Part Of:

Code: 100-F-19

Names: 100-F-19; 1904-F Process Sewer; Contaminated Underground Lines; Effluent Water System; 100-F Reactor Cooling Water Effluent Underground Pipelines

Code: 100-F-19:3

Classification: Accepted

Names: 100-F-19:3; 100-F Reactor Cooling Water Effluent Underground Pipelines (West Group)

Reclassification: Final Closed Out (10/28/2015)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The 100-F-19:3 West Pipelines subsite was remediated, Interim Closed Out and Later Final Closed Out. It included sections of effluent pipelines located north of the reactor running west from the 182-F Reservoir and the 126-F-12 (183-F) Clearwell to the 116-F-1 Lewis Canal. This subsite also included piping running in a north-south direction between the 182-F Reservoir and the 126-F-12 (183-F) Clearwell.

Location: Subsite 100-F-19:3 included pipelines from both the 182-F and 183-F Buildings to the Lewis Canal, and the process sewer line connecting 182-F and 183-F. These pipelines are in the northern part of the 100-F Area, running from the 182-F Reservoir and 183-F Clearwell to the Lewis Canal.

Waste Type: Not Specified

Waste Description: The waste was radioactively contaminated steel piping, concrete and soil.

Closure Info: Interim (5/22/2002): (Interim Closed Out) The 100-F-19:1 North Pipelines, 100-F-19:3 West Pipelines, 100-F-34 Biology Facility French Drain, and the 116-F-12 French Drain were remediated as a group, documented in CVP-2001-00002. The group is referred to as the 100-F-19:1 site. The 100-F-19:1 site remedial action began on August 7, 2001. Excavation of the site involved removing overburden materials, pipelines, french drain structures, and contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Shallow zone excavation occurred both in the vicinity of the 100-F-19:3 West Pipelines and in the vicinity of the 100-F-19:1 North Pipelines, with a

maximum depth of 4.6 meters (15 ft). The deep zone excavation occurred in the southern half of the 100-F-19:1 North Pipelines section of the remedial action, with a approximate maximum depth of 5.0 meters (16 ft). The elevation of the bottom of the excavation varied, but averaged approximately 119.6 meters (392.4 ft). At the completion of remedial action in August 2001, the excavation was approximately 25,710 sq. meters (276,740 sq. ft.) in area. Approximately 56,335 metric tons (62,099 tons) of contaminated materials from the site were disposed of at the ERDF.

These sites meet the cleanup standards specified in the Amendment to the Interim Action Record of Decision for the 100-BC-1, 100-DR-1, and Operable Units (ROD). Excavation of the site involved removing overburden materials, pipelines, french drain structures, and contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Shallow zone excavation occurred both in the vicinity of the 100-F-19:3 West Pipelines and in the vicinity of the 100-F-19:1 North Pipelines, with a maximum depth of 4.6 meters (15 ft). The deep zone excavation occurred in the southern half of the 100-F-19:1 North Pipelines section of the remedial action, with a approximate maximum depth of 5.0 m (16 ft). The elevation of the bottom of the excavation varied, but averaged approximately 119.6 m (392.4 ft).

The results showed that the materials from the 100-F-19:3 subsite containing COCs at concentrations exceeding RAGs have been excavated and disposed of. Remedial actions were performed so as to allow rural-residential use of shallow zone soils (i.e., surface to 4.6 meters [15 feet] deep) and to protect groundwater and the Columbia River. All cleanup verification samples for the 100-F-19:3, 100-F-34 and 116-F-12 sites are listed under 100-F-19:1.

Final (10/28/2015): (Final Closed Out) Thirteen 100-F Area waste sites were reclassified to Final Closed out on form 2015-078. They had all previously been classified as Interim Closed Out. The waste sites included on this reclassification form are 100-F-10, 100-F-19 (and subsites 1,2 and 3), 100-F-29, 100-F-34, 116-F-2, 116-F-6, 116-F-9, 116-F-12, subsites 118-F-8:3 and :4, UPR-100-F-1. The Record of Decision (ROD) for the 100-FR-1, 100-FR-2, 100-FR-3, 100-IU-1, 100-IU-2 and 100-IU-6 Operable Units has defined these waste sites as all requiring institutional controls to restrict excavation into the deep zone (greater than 4.6 meters or 15 feet below the ground surface). However, no further remedial actions are required.

Institutional Control Boundaries have been defined to be broadly inclusive of waste site groups. Not all areas within these boundaries contain residual contamination greater than 4.6 meters (15 ft) below ground surface. An image of four Institutional Control Boundaries inside 100F Area was attached to the 2015-078 Reclassification form (and included in the WIDS library).

The SubSite is Part Of:

Code: 100-F-19

Names: 100-F-19; 1904-F Process Sewer; Contaminated Underground Lines; Effluent Water System; 100-F Reactor Cooling Water Effluent Underground Pipelines

Code: 100-F-23

Classification: Accepted

Names: 100-F-23; 141-C Drywell; 100-F Experimental Animal Farm Drywell

Reclassification Interim Closed Out (8/14/2003)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The site has been remediated and Interim Closed Out. The site was a drywell (french drain). The 141-C Building included a dry well at its southwest corner that drained a loading dock at the facility's southwest end.

Since the Remaining Sites DQO (BHI-01249) COPC lists were originally established, remediation of contaminated soil associated with the Experimental Animal Farm facilities in the 100-F Area, such as the 116-F-9 Experimental Animal Farm Animal Waste Leaching Trench (CVP-2001-00008), has provided potential contaminant information based on sampling and analysis. Cleanup verification sampling at the 116-F-9 site indicated that the COCs identified in the 100 Area Remedial Action Sampling and Analysis Plan (SAP) (DOE/RL-96-22) (carbon-14, cesium-137, cobalt 60, europium-152, strontium-90, and hexavalent chromium) are appropriate for waste sites associated with Animal Farm activities studying the effects of radiation.

The 100-F-24 French drain is believed to have received liquid wastes from 145-F Animal Monitoring Laboratory. Based on verification sampling results from remediation of the 116-F-9 site, and with concurrence from the regulators, the COCs selected for the 100-F-24 site are the same as those identified in the SAP (DOE/RL-96-22) for the 116-F-9 site (CVP-2001-00008).

Code:	100-F-25	Classification:	Accepted
Names:	100-F-25; 146-FR Drywells	Reclassification	Interim Closed Out (8/14/2003)
Type:	French Drain	Start Date:	1/1/1956
Status:	Inactive	End Date:	1/1/1975

Description: The site has been remediated and Interim Closed Out. The site was a pair of french drains associated with the 146-F and 146-FR Aquatic Biology and Fish Ponds Laboratories, which both housed research on the effects of ionizing radiation on fish. The drywells may have been removed or covered with backfill during site cleanup in 1975. The 146-FR Slab located near the french drains was removed in 1975.

Location: The site was located approximately 75 meters (246 feet) south-southwest of the 116-F-8 Outfall Site and 15 meters (49 feet) east of Well # 1-F5-6. The 100F Area coordinates for the drywells are N80511.5, W29327.9 (center) and N80521.5, W29327.9.

Related Sites/ Structures: The site was related to the 146-FR and 146-F Buildings, both housed research on the effects of ionizing radiation on fish.

Process Description: The french drains are believed to have received liquid wastes from 146-F and 146-FR research laboratories and ponds.

Waste Type: Steam Condensate

Waste Description:

Closure Info: Interim (8/14/2003): The 100-F-25, 146-FR Drywells were a pair of french drains associated with the 146-F and 146-FR Aquatic Biology and Fish Ponds Laboratories, which both housed research on the effects of ionizing radiation on fish. The french drains are believed to have received liquid wastes from 146-F and 146-FR research laboratories and ponds. The UPR-100-F-3 Mercury Spill, is an unplanned release that occurred at the northeast corner of the 146-FR Building. The UPR-100-F-3 waste site falls entirely within the footprint of the 100-F-25 site remedial excavation. These wastes sites consisted of only a shallow zone decision unit.

Remedial actions were conducted on April 12, 2003. At the completion of remedial action, the total excavation was approximately 243 square meters (2,615 square feet) in area with a depth of approximately 4.0 meters (13 feet). Approximately 809 metric tons (892 tons) of material (structures and soil) from the site were disposed at the Environmental Restoration Disposal Facility.

Code: 100-F-26	Classification: Accepted
Names: 100-F-26; 100-F Water Treatment Facility Underground Pipelines	Reclassification: Interim Closed Out (2/13/2012)
Type: Process Sewer	Start Date: 1/1/1945
Status: Inactive	End Date: 1/1/1965

Description: The 100-F-26 waste site was divided into 16 subsites based on intended use of the pipe, expected sources of contamination, and potential remedial actions. All of the subsites were individually evaluated. They were either remediated and Interim Closed Out or designated No Action sites. Therefore the parent site is also considered to be Interim Closed Out.

The 100-F-26 waste site includes the underground process and sanitary sewer pipelines associated with the 100-F Area pre-reactor cooling water treatment facilities. These pipelines include all underground water lines used to transport reactor cooling water between water treatment facilities and the 105-F Reactor Building. This pipeline list also includes all underground lines running between buildings, to drainage facilities, and to the emergency cooling high tanks (water towers). Lines downstream from the reactor building (100-F-19) and the underground pipelines associated with the Experimental Animal Farm (100-F-29 and 100-F-33) and the clean water pipelines (100-F-41) were excluded.

The 16 subsites are as follows:

- 100-F-26:1 North process sewer collection pipelines
- 100-F-26:2 Process water pipelines to the aquatic biology and strontium gardens
- 100-F-26:3 184-F Powerhouse pipelines
- 100-F-26:4 South process pipelines
- 100-F-26:5 190-F bypass pipelines
- 100-F-26:6 190-F Reservoir pipelines
- 100-F-26:7 Sodium dichromate and sodium silicate pipelines
- 100-F-26:8 1607-F1 sanitary sewer pipelines
- 100-F-26:9 1607-F2 sanitary sewer pipelines
- 100-F-26:10 1607-F3 sanitary sewer pipelines
- 100-F-26:11 1607-F4 sanitary sewer pipelines
- 100-F-26:12 1.8-meter (72-in.) main process sewer pipeline
- 100-F-26:13 108-F drain pipelines
- 100-F-26:14 116-F-5 influent pipelines
- 100-F-26:15 Miscellaneous pipelines associated with the 1608-F sump
- 100-F-26:16 Reactor cooling water pipelines.

Location: The location is described as underground lines running from the 181-F River Pumphouse to the 182-F Reservoir, the 183-F Basins and Clearwells, the 184-F Powerhouse, the 190-F Buildings, 108-F Biology Laboratory, and to the 105-F Reactor Building. Also, the drainage lines running from the water treatment buildings to the junction with the 100-F-19 Effluent Pipeline at the Animal Farm are included in this waste site. Septic sewer system pipelines are included only where they are co-located with the other pipelines in this site.

Related Sites/ Structures: Structures associated with 100-F-26 include the 181-F River Pumphouse, the 182-F Settling Basin, the 183-F Basins and Clearwells, the 184-F Powerhouse, the 190-F Water Treatment Building, the 105-F Reactor, 185-F, the 108-F Biology Laboratory, and the several 1700-series support buildings.

Other pipeline sites in the 100-F Area include the Process Effluent Pipelines in site 100-F-19, the Water Treatment Pipelines in site 100-F-26, the river effluent lines are site 100-F-39, the clean water pipelines were 100-F-41, the experimental animal farm pipelines in site 100-F-29

and miscellaneous pipelines in 100-F-44.

Process Description: Reactor cooling water was pumped from the Columbia River, settled and treated to remove minerals, and pumped to the reactor core at a rate of 1.93E+05 liters (51,000 gallons) to 2.69E+05 liters (71,000 gallons) per minute. Historical research indicates that several buildings and waste sites were associated with sodium dichromate use. Originally, from the startup of F-Reactor in 1945 until 1949, the receiving, mixing, and transfer of sodium dichromate and other water treatment chemicals occurred in the 108-F Building, which was constructed to receive and store bulk water treatment chemicals. The chemicals were unloaded from railcars in either bags or barrels. Sufficient sodium dichromate was added to reactor cooling water so that the instantaneous concentration was 2.0 ppm as required by the reactor cooling water specifications.

Waste Type: Water

Waste Description: The waste consists of contaminated pipelines made of various materials (i.e. steel piping, concrete and soil). Chemical additives to the reactor cooling water included aluminum sulfate (alum) with excess hydrated calcium oxide, sulfuric acid, chlorine, and sodium dichromate. Water pH was maintained at about 7.5, and the free chlorine residual was approximately 0.2 milligrams/liter.

This Site has the Following SubSites:

Code: 100-F-26:1

Names: 100-F-26:1; North Process Sewer Collection Pipelines

Code: 100-F-26:2

Names: 100-F-26:2; Process Water Pipelines to the Aquatic Biology and Strontium Gardens

Code: 100-F-26:3

Names: 100-F-26:3; 184-F Powerhouse Pipelines

Code: 100-F-26:4

Names: 100-F-26:4; South Process Pipelines

Code: 100-F-26:5

Names: 100-F-26:5; 190-F Bypass Process Sewer Pipelines

Code: 100-F-26:6

Names: 100-F-26:6; 190-F Reservoir Pipelines

Code: 100-F-26:7

Names: 100-F-26:7; Sodium Dichromate and Sodium Silicate Pipelines

Code: 100-F-26:8

Names: 100-F-26:8; 1607-F1 Sanitary Sewer Pipelines

Code: 100-F-26:9

Names: 100-F-26:9; 1607-F2 Sanitary Sewer Pipelines

Code: 100-F-26:10

Names: 100-F-26:10; 1607-F3 Sanitary Sewer Pipelines

Code: 100-F-26:11

Names: 100-F-26:11; 1607-F4 Sanitary Sewer Pipelines

Code: 100-F-26:12

Names: 100-F-26:12; 72-inch Main Process Sewer Pipeline

Code: 100-F-26:13

Names: 100-F-26:13; 108-F Drain Pipelines

Type: Process Sewer**Start Date:****Status:** Inactive**End Date:**

Description: The subsite was evaluated and determined to be a No Action site. It consisted of a 5.1-centimeter (2-inch) diameter carbon steel pipeline that exited the east side of the 190-F Pumphouse. Drawings indicated it split and conveyed filtered water to both the Aquatic Biology Fish Ponds and the Strontium Gardens. However, field excavation of test pits and exploratory trenches did not reveal the pipeline to the Strontium Gardens, nor did it reveal any indication that the Strontium Gardens pipeline split from the Aquatic Biology pipeline. The Aquatic Biology pipeline was opened and found to contain enough residual scale/sediment for the collection of one sample.

Location: These pipelines ran diagonally across the 100-F Area, from the 190-F Pumphouse northeast to the 146-F biology facilities, and southeast to the Strontium Gardens.

Waste Type: Not Specified

Waste Description: The waste is the pipeline and any contaminated soil that may have occurred because of leaks in the pipeline.

Closure Info: Interim (5/26/2005): Confirmatory sampling of the subsite was conducted from November 17 through 18, 2004. Since no manholes or junction boxes were indicated on site drawings, three test pits were excavated to locate the two 5.1 cm (2 in) process water pipelines that conveyed water to the Aquatic Biology Fish Ponds and the Strontium Gardens. According to historical information, the pipeline split at the location of test pit 1, and one 5.1 cm (2 in) pipe traveled southwest to the Strontium Gardens while the other 5.1 cm (2 in) carbon steel pipe traveled northeast to the Aquatic Biology Fish Ponds. However, excavation of test pits and exploratory trenches at the locations of test pit 1 and test pit 3 did not reveal the pipeline to the Strontium Gardens. They did not reveal any indication that there was a pipeline to the Strontium Gardens that split from the Aquatic Biology pipeline. Further excavation of exploratory test trenches in the vicinity of test pits 1 and 3, between test pits 1 and 3, and between test pit 1 and the 190-F Pumphouse also did not reveal any indication that the Strontium Gardens pipeline split from the Aquatic Biology pipeline, nor that it existed in its presumed location. Consequently, as it could not be located, no confirmatory samples from the Strontium Garden pipeline were collected.

Since the field excavation did not locate a split in the Aquatic Biology pipeline at or in the vicinity of test pit 1, it was determined by the field sampling task lead that test pit 1 was no longer a defensible focused sampling location. Test pit 2 was located at a 90 degree bend in the pipeline. No other pipelines contributed flow upstream or downstream of test pit 2. It was determined that residual contamination at test pit 2 was representative of the residual contamination throughout the pipeline. Therefore, test pit 2 was identified as a defensible worst case focused sampling location for the Aquatic Biology pipeline. Confirmatory samples of the residual scale/sediment in the 5.1 cm (2 in) carbon steel pipe and soil beneath the pipe were collected at the 90 degree elbow in the pipe at test pit 2.

The No Action decision for the 100-F-26:2 subsite is supported based on current reviews of the site history and confirmatory sampling results. The analytical results from soil samples collected were shown to meet the cleanup objectives for direct exposure, groundwater protection, and river protection.

These results indicated that residual soil concentrations support future land uses that can be represented (or bounded) by a rural-residential scenario. The results also demonstrated that residual contaminant concentrations support unrestricted future land uses of shallow zone soil (i.e., surface to 4.6 meters [15 feet]) and that contaminant levels remaining in the soil are protective of groundwater and the Columbia River.

The SubSite is Part Of:**Code:** 100-F-26**Names:** 100-F-26; 100-F Water Treatment Facility Underground Pipelines**Code:** 100-F-26:3**Classification:** Accepted**Names:** 100-F-26:3; 184-F Powerhouse Pipelines**Reclassification** Interim No Action (12/3/2004)**Type:** Process Sewer**Start Date:****Status:** Inactive**End Date:**

Description: The 100-F-26:3 pipeline subsite was evaluated and determined to be a No Action site. The 100-F-26:3 pipeline subsite consisted of a network of process sewer pipelines that serviced the 184-F power house and 188-F ash disposal basin. The 184-F power house was primarily a boiler house, containing four boilers and one small turbine generator for emergency power generation. The 188-F ash disposal basin was an open rectangular-shaped pit used for the disposal of ashes from the 184-F Power House. Ash from the power house was combined with raw river water and pumped directly from the sluice pit in the power house to the ash disposal basin. This subsite was evaluated and reclassified as an analogous site of the 100-B-14:6 subsite (184-B Power House pipelines).

Location: The Subsite location is the network of pipelines running from the 184-F power house to the 188-F ash disposal basin.

Waste Type: Not Specified

Waste Description: The waste was the remaining pipelines and any potentially contaminated soil.

Closure Info: Interim (12/3/2004): The pipeline was determined to require No Action.

The SubSite is Part Of:**Code:** 100-F-26**Names:** 100-F-26; 100-F Water Treatment Facility Underground Pipelines**Code:** 100-F-26:4**Classification:** Accepted**Names:** 100-F-26:4; South Process Pipelines**Reclassification** Interim Closed Out (2/3/2012)**Type:** Process Sewer**Start Date:****Status:** Inactive**End Date:**

Description: This subsite has been remediated and Interim Closed Out. It was a network of process sewer pipelines that received flow from the 105-F Reactor, the 190-F Pumphouse, the 1717-F Combined Shops Buildings and the 108-F Biology Laboratory in the 100-F Areas. The 100-F-26:4 pipelines consisted of sewer lines from the service buildings that flowed north where they connected to the 100-F-26:12 pipeline. The pipelines in 100-F-26:4 were divided into six "service areas" for the confirmatory sampling effort. The service areas were:

Service Area 1 (105-F Reactor Building process sewer) included 39.6 meters (130 ft) of 0.2-meter (8-in.) vitrified clay pipe (VCP) and 62 meters (203 ft) of 0.3 meter (12-in.) VCP.

Service Area 2 (108-F Biology Laboratory process sewer) included 96 meters (315 ft) of 0.15-meter (6-in.) VCP and 32 meters (105 ft) of 0.15-meter (6-in.) cast iron pipe.

Service Area 3 (190-F Pumphouse process sewer) included 21.3 meters (70 ft) of 0.76-meter (30-in.) reinforced concrete pipe (RCP).

Service Area 4 (189-F Refrigeration Building process sewer) included 54.9 meters (180 ft) of 1.4-meter (54-in.) RCP.

Service Area 5 (1717-F Combined Shops Building process sewer) includes 120.4 meters (395 ft) of 0.15-meter (6-in.) VCP.

Service Area 6 (central process sewer collection line) includes 285 meters (935 ft) of 1.5-meter (60-in.) RCP, 53.3 meters (175 ft) of 0.91-meter (36-in.) RCP and 72 meters (236 ft) of 0.3-meter (12-in.) VCP.

Location: The pipelines in this subsite are located in the center of the 100-F Area, east of the 105-F Reactor and the 190-F Pumphouse and west of the 108-F Biology Laboratory and the 1717-F Combined Shops Building.

Process Description: Discharges from the 105-F Reactor Building into the 100-F-26:4 process pipelines are expected to have consisted only of nonradioactive process wastes. The 108-F Building was originally used as a reactor laboratory facility from 1945 to 1950 before being converted to a biology laboratory that operated until 1976. Process chemicals used at this facility were discharged to sewers, sumps, and french drains. The 108-F facility also contained a heavily shielded cobalt-60 source room. The 190-F Pumphouse was used for process water supply with water treatment chemicals, including alum, sulfuric acid, chlorine, and sodium dichromate, historically used at and/or stored near the facility. The 1717-F Combined Shops included a machine shop, carpenter shop, pipe shop, sheet metal shop, electric shop, tool room, six offices, and a restroom. Oils, paints, and solvents were stored and used in the facility.

Waste Type: Not Specified

Waste Description: The waste is potentially contaminated equipment (pipelines) and any contaminated soil associated with the pipeline.

Closure Info: Interim (2/3/2012): The pipelines in 100-F-26:4 were divided into six "service areas" for the confirmatory sampling effort. Samples were collected from ten test pit locations along the pipeline. The test pit excavations began in December 2004. One test pit was dug in each of the Service Areas, but Service Area 2 had two test pits and Service Area 6 had four test pits. The data from the test pit samples defined the areas requiring remedial excavation.

A remedial action requirement was determined for Service Area 2 and the pipeline segment located between test pit 2 and test pit 6 in service area 6 (central process sewer). Remediation of the pipeline segment between test pit 2 and test pit 6 was performed from October 13, 2010 through January 5, 2011. Excavated materials including concrete, asphalt, clay pipe, rebar, and coal ash were staged onsite before disposal at the ERDF. White powder was discovered at Service Area 2 during excavation in February 2007. A soil sample (J14JH1) was collected and analyzed for ICP metals, semivolatile organics, and TPH. The results indicated that the material had elevated concentrations of sodium, silicon, and calcium. The material was excavated less than 4 cubic meters in volume and was properly disposed. No other anomalies or stained soil were discovered during remediation activities.

The site was remediated by removing approximately 540 BCM (706 BCY) of material from February 12 through October 11, 2007, and 304 BCM (400 BCY) from October 13, 2010, through January 5, 2011, for disposal at the ERDF. Statistical and judgmental sampling to verify the completeness of remediation was performed, and analytical results for the two decision units (excavation footprint and overburden stockpiles) were shown to meet the cleanup objectives for direct exposure, groundwater protection, and river protection.

The SubSite is Part Of:**Code:** 100-F-26**Names:** 100-F-26; 100-F Water Treatment Facility Underground Pipelines**Code:** 100-F-26:5**Classification:** Accepted**Names:** 100-F-26:5; 190-F Bypass Process Sewer Pipelines**Reclassification** Interim No Action (7/21/2005)**Type:** Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** The subsite has been evaluated and determined to be a No Action site.

The subsite included the underground pipelines that serviced the 185-F Building and the 190-F Pumphouse Building. They were constructed of 1.2-meter (48-inch) reinforced concrete pipe (RCP) and 0.46-meter (18-inch) vitrified clay pipe (VCP). The effluent discharged to the 100-F-19:3 [100-F Reactor Cooling Water Effluent] underground pipelines that acted as a bypass system to the 116-F-1 (Lewis Canal) site.

Location: The pipeline ran from the 185-F and 190-F Facilities to the south before the pipeline turned west to discharge to one of the 100-F-19:3 [100-F Reactor Cooling Water Effluent Underground Pipelines (West Group)].

Waste Type: Not Specified

Waste Description: The waste includes the pipelines, the contaminated scale and sediment which may be contained within them, and the underlying soils.

Closure Info: Interim (7/21/2005): The subsite included the underground pipelines that serviced the 185-F Building and the 190-F Pumphouse Building, they were composed of 1.2-meter (48-inch) reinforced concrete pipe (RCP) and 0.46-meter (18-inch) vitrified clay pipe (VCP). The historic design flow direction consisted of discharges from the 185-F and 190-F Facilities traveling generally south before the pipeline turned west to discharge to one of the 100-F-19:3 [100-F Reactor Cooling Water Effluent Underground Pipelines (West Group)]. A discrepancy as to the termination point of the 100-F-26:5 pipeline was found, the CVP for the 100-F-19:3 waste site indicated that the 100-F-26:5 pipeline was approximately 63 meters (207 feet) longer at the southwest end of the subsite than was shown on Drawing 0100F-DD-C0189.

For characterization activities this pipeline subsite was divided into three service areas, based on the facilities pipelines serviced prior to confluencing to a general pipeline. One test pit in each service area was excavated to expose either the 1.2-meter (48-in.) RCP (service areas 1 and 3) or the 0.46-meter (18-in.) VCP (service area 2). Sediment or scale samples were collected from inside of the pipes, and soil under the pipes was also collected for analysis. Test pit 1 was excavated to a depth of 4.05 meters (13.3 ft) and was the only test pit where samples were taken from the shallow zone (samples J022P4, J022M5, J022P0, and the duplicate sample J022P1). Test pits 2 and 3 were excavated to depths of 5.8 meters (19 ft) and 7.9 meters (26 ft), respectively.

Mercury levels in test pit 2 (805 milligrams/kilograms) were significantly higher than the direct exposure remedial action goal (RAG) of 24 milligrams/kilograms. However, the sample that contained the high mercury concentration was taken at a depth of 5.5 meters (18 feet) below ground surface in the deep zone, and therefore direct exposure RAGs were not applicable. The results demonstrated that residual contaminant concentrations support future land use that can be represented (or bounded) by the rural-residential scenario. These results also showed that contaminant levels remaining in the soil are protective of groundwater and the Columbia River.

However, because mercury concentrations in deep vadose zone soil exceed direct exposure, institutional controls are required for the 100-F-26:5 waste site to prevent excavation or drilling into the deep vadose zone soils.

The No Action decision for the 100-F-26:5 pipeline subsite is supported based on reviews of the site history, field observations, and the confirmatory investigation and sampling results. The analytical results from the 100-F-26:5 pipeline subsite soil and pipe sediment samples were shown to meet the cleanup objectives for direct exposure, groundwater protection, and river protection with the exception of mercury. Because mercury concentrations in the deep vadose zone soil exceed RAGs, institutional controls are required for the 100-F-26:5 waste site to prevent excavation or drilling into the deep vadose zone.

The SubSite is Part Of:

Code: 100-F-26

Names: 100-F-26; 100-F Water Treatment Facility Underground Pipelines

Code: 100-F-26:6

Classification: Accepted

Names: 100-F-26:6; 190-F Reservoir Pipelines

Reclassification: Interim No Action (12/3/2004)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The subsite was evaluated and determined to be an analogous site of the 100-B-14:7 pipeline site. It was reclassified to No Action. 100-F-26:6 includes cast iron pipe servicing the 190-F Pumphouse Building.

Location: The location is described as underground lines running from the 190-F Building to the 105-F Reactor Building.

Process Description: The subsite received flow via a cast iron pipeline (CIP) with lead joints, from the re-use water reservoir portion of the 190-F Pumphouse. Waste water from the steam jet condensers was collected in the re-use water reservoir and pumped back to the main reservoir (182-F Building) during the winter months to maintain the temperature of the process water.

Closure Info: Interim (12/3/2004): The 100-F-26:6 subsite (190-F re-use water reservoir and pipeline) are analogous to the 100-B-14:7 (190-B Sump and Pipelines) site. They had a similar source of water and supported a similar process. The 190-F Reservoir Pipelines subsite (100-F-26:6) meets the Remedial Action Objectives specified in the Remaining Sites ROD, U.S. Environmental Protection Agency, Region 10, Seattle, Washington. The 190-F re-use water reservoir and pipeline are analogous to the 190-B Sump and Pipelines (100-B-14:7), as they had a similar source of water and supported a similar process. Historical sampling indicated that no unacceptable levels of residual ICP metals, mercury, or hexavalent chromium exist in the 190-B sump or the 100-B-14:7 cast iron pipeline. The 100-F-26:6 pipeline is composed of cast iron pipe (CIP) with lead joints, as was the 100-B-14:7 pipeline. The lead contained in the pipeline does not present a direct exposure risk to human health, and an exposure pathway to groundwater does not exist. There is no history of radiological contamination associated with the 190-F Reservoir Pipelines and no radiological contamination was detected during decommissioning of the 190-F complex. There were no known process incidents at 105-F Reactor that would have introduced radiological contamination from the reactor into the 190-F Reservoir Pipelines. The 100-B-14:7 pipeline subsite has been determined to meet the cleanup criteria, consequently the 100-F-26:6 subsite also meets the cleanup criteria and the remaining contaminant levels are protective of human health, groundwater and the Columbia River.

The lead contained in the pipeline did not present a direct exposure risk to human health, no exposure pathway to groundwater existed. There was no history of radiological contamination

associated with the 190-F Reservoir Pipelines and no radiological contamination was detected during decommissioning of the 190-F complex. There were no known process incidents at 105-F Reactor that would have introduced radiological contamination from the reactor into the 190-F Reservoir Pipelines.

The 100-B-14:7 pipeline subsite was determined to meet the cleanup criteria. Consequently the 100-F-26:6 subsite also has met the cleanup criteria and the remaining contaminant levels were protective of human health, groundwater and the Columbia River. The site has been reclassified to No Action.

The SubSite is Part Of:

Code: 100-F-26

Names: 100-F-26; 100-F Water Treatment Facility Underground Pipelines

Code: 100-F-26:7

Classification: Accepted

Names: 100-F-26:7; Sodium Dichromate and Sodium Silicate Pipelines

Reclassification: Interim Closed Out (2/6/2011)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This subsite has been remediated and Interim Closed Out. The subsite consisted of two parallel, 0.07 meter (3 inch) steel pipelines that conveyed sodium dichromate and sodium silicate, respectively, from the 108-F Chemical Pumping Building to the 190-F Water Treatment Building.

Note from the WIDS Administrator: After the original reclassification form (2005-010) was approved in 2005, a portion of this remaining pipeline subsite was punctured during the 100-F-26:9 overburden removal. Sodium dichromate was still present in the pipeline. Plans were developed to remediate the entire pipeline. The reclassification status listed on the reclassification form was no longer valid, so the reclassification status for this subsite was removed in the WIDS database on 6/10/2010. Reclassification form 2011-088 was issued to track the second remediation activity.

Based on historical information, the sodium silicate pipeline conveyed only chemicals with low inherent toxicity or that readily degrade to compounds of low inherent toxicity. Therefore it is not considered hazardous/dangerous or to present a risk to human health or the environment. Because the sodium silicate pipeline was within 0.8 meters (2 ft) of the sodium dichromate pipeline along their entire lengths, the two were treated as twin pipelines for confirmatory sampling. In 2005, samples were taken of the soil beneath a 90-degree bend in the sodium dichromate pipeline and from a section of the pipe.

Location: The pipelines ran from the 108-F Chemical Pumping Building to the 190-F Water Treatment Building.

Waste Type: Not Specified

Waste Description: The waste is contaminated steel piping and underlying soils.

Closure Info: Interim (2/6/2011): In January 2005, one test pit was excavated and the soil beneath the pipelines was sampled and analyzed. An additional sample was taken from within the sodium dichromate pipeline. The maximum detected results from the soil and pipe sediment/scale were used to support a waste site reclassification to Interim Closed Out in 2005. However, during overburden removal of the 100-F-26:9 pipeline in February 2007, a portion of the 100-F-26:7

pipeline was unearthed and punctured. Approximately 3.75 to 7.5 liters (1 to 2 gal) of liquid from within the pipe spilled to the ground and was quickly contained. Samples taken of this liquid demonstrated that concentrations of total chromium and hexavalent chromium exceeded cleanup criteria. As a result, the original 100-F-26:7 waste subsite reclassification of Interim Closed Out was withdrawn. The pipeline remedy was changed to remove, treat and dispose.

Remedial action of the 100-F-26:7 waste subsite was initiated on January 12, 2011. Remediation activities consisted of removal and stockpiling of overburden soil to expose the pipelines, tapping, draining, and collecting the pipeline contents, removal and size reduction of the pipelines, and excavation of approximately 0.3 meters (1 ft) of soil directly below the pipelines including stained and contaminated soil that was identified during remediation. Two small staging pile areas, that were used for contaminated pipe and soil material, were later loaded out and also disposed at the ERDF.

During excavation, both ends of each pipeline were found to be open. The sodium dichromate pipeline was found to contain approximately 990 liters (300 gal) of liquid, which was emptied into large 954 liter (250 gal) tubs. The liquid in these tubs was then pumped into drums for storage until sampling and disposal could occur. This liquid was sampled on February 15, 2011, and found to exceed cleanup criteria for hexavalent chromium.

The SubSite is Part Of:

Code: 100-F-26

Names: 100-F-26; 100-F Water Treatment Facility Underground Pipelines

Code: 100-F-26:8

Classification: Accepted

Names: 100-F-26:8; 1607-F1 Sanitary Sewer Pipelines

Reclassification: Interim Closed Out (3/14/2008)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This subsite includes the 1607-F1 influent sanitary sewer pipelines. These pipelines were 200 m (660 ft) long and constructed of 8-inch vitrified clay. The pipelines serviced the 1701-F, 1709-F, and 1720-F Buildings.

Location: The 100-F-26:8 sanitary sewer pipelines and 1607-F1 sanitary sewer system waste sites are located within the 100-FR-1 Operable Unit of the Hanford Site, approximately 730 m (2395 ft) south of the 105-F Reactor Building.

Waste Type: Not Specified

Waste Description: The waste is any potentially contaminated pipelines and associated soils.

Closure Info: Interim: Confirmatory sampling was performed at the 1607-F1 septic tank waste site on October 7, 2004. Three sample locations were identified in the work instruction for this site. One sample was collected from soil under the septic tank. Two samples were collected from the septic drain field. No sample of tank contents was collected, as the inside of the tank was previously cleaned and backfilled. At the 1607-F1 septic tank site, contaminants in the drain field and in the soil beneath the septic tank were below the remedial action goals (RAGs).

Confirmatory sampling of the 100-F-26:8 waste site was conducted on January 5, 2005. Samples of the scale inside the pipe and the soil beneath the pipe were collected. A pipe matrix calculation was prepared using the analytical results of the pipe scale sample. An evaluation of the pipe matrix calculations showed that benzo(a)pyrene exceeded the direct exposure RAG. Concentrations of some polychlorinated biphenyl (PCB) congeners, pesticides, and semivolatiles

organic compounds (SVOCs) also exceeded the groundwater and river protection RAGs. These confirmatory sample results indicated that the 100-F-26:8 waste site required remedial action due to benzo(a)pyrene present at levels exceeding remedial action goals for direct exposure.

Remediation of the 1607-F1 and 100-F-26:8 waste sites were performed from January 8 to April 3, 2007. Remedial activities included removal of the septic tank and the associated piping. Both sites were excavated to approximately 3.4 meters (11 feet) below grade resulting in a combined volume of approximately 464 cubic meters (607 cubic yards) of material stockpiled for disposal at the Environmental Restoration Disposal Facility (ERDF). Approximately 266 meters (872 feet) of pipeline were removed during remediation. During pipeline excavation, a french drain was discovered on the west side of the former 1709-F facility. Although this french drain was independent of the pipelines, it was removed.

The SubSite is Part Of:

Code: 100-F-26

Names: 100-F-26; 100-F Water Treatment Facility Underground Pipelines

Code: 100-F-26:9

Classification: Accepted

Names: 100-F-26:9; 1607-F2 Sanitary Sewer Pipelines

Reclassification: Interim Closed Out (10/29/2008)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The 100 F 26:9 subsite consisted of underground pipelines of the 1607-F2 sanitary sewers servicing the 105-F, 108-F, 184-F, 185-F, and 190-F buildings, and the 1700 F administration and service buildings (1704-F, 1707-F, 1707-FA, 1713-F, 1717-F, 1719 F, and 1722-F).

Location: The collection pipelines were located at 105-F, 108-F, 184-F, 185-F, 190-F, 1704-F, 1707-F, 1707-FA, 1713-F, 1717-F, 1719 F, and 1722-F Buildings, and ran to the south and east to the 1607-F2 septic tank.

Waste Type: Not Specified

Waste Description: The waste includes the pipelines and the contaminated scale and sediment which may be contained within them, and any contaminated soil associated with leaks from the pipelines.

Closure Info: Interim: For Confirmatory sampling activities, the waste site was divided into eleven Service Areas. Test pits were dug and sampled at along the pipelines where junction boxes, bends or pipe joints were located. The contaminants found at seven of the service areas (1, 3, 4, 5, 6, 7 and 8) were found to be at concentrations protective of human health, groundwater, and the Columbia River. A remedial action requirement was determined for service areas 2, 9, and 10. Service Area 11 was remediated because it was downstream of service areas 2 and 10. Remediation of Service Areas 2, 9, 10 and 11 of the 100-F-26:9 pipeline subsite was performed from February 8 through October 30, 2007.

Remediation of these service areas was performed from February 8 through October 30, 2007. The site was excavated to a depth of approximately 3.7 meters (12 ft) below grade, resulting in approximately 1,360 bank cubic meters (BCM) (1,780 bank cubic yards [BCY]) of material disposed of at the Environmental Restoration Disposal Facility. Approximately 6,340 BCM (8,290 BCY) of overburden and layback soil was removed and stockpiled for use as clean backfill.

The SubSite is Part Of:

Code: 100-F-26
Names: 100-F-26; 100-F Water Treatment Facility Underground Pipelines

Code: 100-F-26:10 **Classification:** Accepted
Names: 100-F-26:10; 1607-F3 Sanitary Sewer Pipelines **Reclassification:** Interim Closed Out (12/3/2007)
Type: Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The 100-F-26:10 underground pipeline subsite has been remediated and Interim Closed Out. It consisted of underground sanitary sewer pipelines that received effluent from the 182-F, 183-F, and 151-F Buildings and discharged to the 1607-F3 septic system. These pipelines were constructed of 6 and 8-inch vitrified clay.

Location: The pipelines and septic systems were about one-quarter mile northwest and north of the 105-F Reactor.

Waste Type: Not Specified

Waste Description: The waste was contaminated pipelines and associated soils.

Waste Type: Not Specified

Waste Description: The waste was contaminated pipelines and associated soils.

Closure Info: Interim: In preparation for the site remediation, two road crossings were excavated, sampled, and immediately backfilled in January 2007. Remedial action was performed from March 7 through March 12, 2007. The site was excavated between 2.4 meters (8 feet) and 4.3 meters (14 feet) below grade, resulting in approximately 1,900 bank cubic meters (BCM) (2,500 bank cubic yards [BCY]) of material disposed at the Environmental Restoration Disposal Facility, including removal of approximately 600 meters (1,970 feet) of pipeline. Approximately 4,200 BCM (5,500 BCY) of overburden soil was removed and stockpiled for use as clean backfill. Samples were collected at a test pit in each service area from the contents of the junction boxes and from the soil underneath the junction boxes.

The portion of the north-south vitrified clay pipeline (VCP) line that serviced the 182-F Pump Station and a portion of the 183-F Water Treatment Plant VCP line were removed during decommissioning of those buildings, leaving two separate sections of pipeline. The 1607-F3 septic tank, drain field, and associated contaminated soil were removed in September 2005. Remedial action objectives for the 1607-F3 waste site were met after the additional excavation of contaminated soil in 2006 and were addressed in RSVP-2006-047.

The 100-F-26:10 subsite was divided into three decision units for verification sampling. The first decision unit consisted of the excavation footprint of the pipeline, the second decision unit consisted of the overburden stockpiles, and the third decision unit consisted of the pipeline excavations underlying the haul road (road-crossing area) and the overburden stockpiles used to backfill in the road crossings. Statistical and judgmental sampling to verify the completeness of remediation was performed, and analytical results were shown to meet the cleanup objectives for direct exposure, groundwater protection, and river protection.

A 30.1 cm (12 in) diameter pipeline discovered during confirmatory sampling of the 100-F-26:10 test pit #2. It was added to 100-F-44:3 for dispositioning. A 76 centimeter (30-inch) pipe entering the foundation of the 189-F Refrigeration Building was added to 100-F-44:6 for dispositioning.

The SubSite is Part Of:**Code:** 100-F-26**Names:** 100-F-26; 100-F Water Treatment Facility Underground Pipelines**Code:** 100-F-26:11**Classification:** Accepted**Names:** 100-F-26:11; 1607-F4 Sanitary Sewer Pipelines**Reclassification:** Interim No Action (5/26/2005)**Type:** Process Sewer**Start Date:****Status:** Inactive**End Date:**

Description: The subsite was evaluated and determined to be a No Action site. The subsite consisted of a 0.15-meter (6-inch) diameter vitrified clay pipe (VCP) encased in concrete. It received effluent from the 115-F Gas Recirculation Building. The VCP originated at the southwest corner of the 115-F Gas Recirculation Building and carried flow west approximately 53.6 meters (178 feet). The pipeline terminated at the inlet to the 1607-F4 septic tank.

Location: The 100-F-26:11 subsite is located approximately 139 meters (456 feet) west of the 105-F Reactor Building.

Waste Type: Soil**Waste Description:** The waste was the pipeline interior scale and the soil underneath the pipe.

Closure Info: Interim: During excavation of test pit 1, the 0.15-meters (6-in.) VCP was discovered at 1.2 meters (4 ft) below ground surface (bgs) and found to be encased in 0.2 meters (8 in.) of concrete. A section of the VCP was removed by means of a rock hammer (hydraulic hammer attached to an excavator) and samples of the scale sediment inside and soil beneath the pipe were collected. Test pit 2 was excavated to the concrete-encased influent VCP at a depth of 1.2 meters (4 ft) bgs. A section of the VCP was removed via a rock hammer and found to contain no residual sediment in the pipe. A pipe scale sample was scabbled from the VCP. A soil sample from beneath the pipe was also collected. Field radiological surveys and volatile organic constituent field screening were conducted during excavation.

Confirmatory sampling of the subsite was conducted on November 22, 2004, in accordance with the WCH work instructions. A focused sampling approach was selected using the probable worst-case locations for sampling. Confirmatory samples of the 0.15-m (6-in.) influent VCP were collected via excavation of two test pits, one at either end of the pipeline. Samples were taken of the pipeline interior scale and the soil underneath the pipe. Analytical results of pipe scale and underlying soil samples for the subsite were shown to meet the cleanup objectives for direct exposure, groundwater protection, and river protection, excluding the soil sample for lead and the pipe scale sample for aroclor-1260.

The No Action decision for the 100-F-26: 11 subsite is supported based on reviews of the site history and confirmatory sampling results. The analytical results from pipe sediment and underlying soil samples collected were shown to meet the cleanup objectives for direct exposure, groundwater protection, and river protection.

The SubSite is Part Of:**Code:** 100-F-26**Names:** 100-F-26; 100-F Water Treatment Facility Underground Pipelines**Code:** 100-F-26:12**Classification:** Accepted

Names: 100-F-26:12; 72-inch Main Process Sewer Pipeline
Reclassification Interim Closed Out (4/29/2008)

Type: Process Sewer
Start Date:

Status: Inactive
End Date:

Description: This waste site has been remediated and Interim Closed Out. The 100-F-26: 12 underground pipeline subsite consisted of an approximately 308 meters (1,011 ft) long, 1.8 meters (72 in.) diameter, east west-trending reinforced concrete pipe that joined the North Process Sewer Pipelines (100-F-26: 1) and the South Process Pipelines (100-F-26:4) with the 1.8-meter (72-in.) reactor cooling water effluent pipeline (100-F-19).

Location: The 100-F-26:12 pipeline ran for 308 meters (1,011 ft) from west to east about 50 meters north of the 184-F Powerhouse.

Waste Type: Not Specified

Waste Description: The waste was the sewer pipe and surrounding soils.

Closure Info: Interim (4/29/2008): Remediation of the pipeline subsite was performed from January 11 through October 4, 2007. The subsite was excavated between 4.0 meters (13 ft) and 6.0 meters (20 ft) below grade, resulting in approximately 2,900 bank cubic meters (BCM) (3,800 bank cubic yards [BCY]) of material disposed of at the Environmental Restoration Disposal Facility that including removing of approximately 308 meters (1,011 ft) of pipe. Approximately 23,340 BCM (30,530 BCY) of overburden was stockpiled for use as clean backfill.

Radiological field measurements and staining discovered during excavation of the 100-F-19 pipeline in August 2001 indicated that contamination was present within the 100-F-26:12 sewer pipe and its surrounding soils. The site was referred for remedial action without requiring additional confirmatory sampling.

The portion of the pipeline that ran beneath the railroad crossing (near the coal conveyor structure) was encased in concrete to support the additional load. The pipeline encased in concrete was removed. The coal conveyor structure was evaluated and found to be absent of hydraulic systems. The large concrete monolith associated with the coal conveyor was abandoned in place.

The SubSite is Part Of:

Code: 100-F-26

Names: 100-F-26; 100-F Water Treatment Facility Underground Pipelines

Code: 100-F-26:13
Classification: Accepted

Names: 100-F-26:13; 108-F Drain Pipelines
Reclassification Interim Closed Out (3/3/2008)

Type: Process Sewer
Start Date:

Status: Inactive
End Date:

Description: The 100-F-26:13 subsite was remediated and Interim Closed Out. It consisted of one 0.15 meter (6 inch), two 0.2 meter (8 inch), and one 0.31 meter (12 inch) diameter vitrified clay pipe (VCP) segments encased in concrete. The pipelines discharged effluent from the former 108-F Biological Laboratory, which was originally built in 1944 to support treatment of cooling water for use in the 105-F Reactor to the 188-D Ash Disposal Area (126-F-1). In 1949, the 108-F Building was completely remodeled for use in life-science studies to test the effects of radiation and contamination on plant and animal life. In 1999, the 108-F Building was decontaminated,

demolished, and removed; however, the 100-F-26:13 pipeline segments were left in place.

Location: These pipelines were in the south-central part of the 100-F Area, running from the 108-F Building to the 126-F-1 Ash Disposal Pit.

Waste Type: Not Specified

Waste Description: The waste was potentially contaminated pipelines.

Closure Info: Interim: Remediation of this subsite was performed in two stages because a portion of the pipelines were located under the main access road to the 100-F Area. The first stage was performed between February 5 and March 27, 2007, and consisted of excavating and removing all pipeline segments except the portion underlying the main access road. The second stage included excavation and removal of the pipeline segment under the access road and was performed on August 24, 2007.

Approximately 580 bank cubic meters (BCM) [760 bank cubic yards (BCY)] of pipeline material and suspect contaminated adjacent and underlying soils were removed and stockpiled in the staged waste area for later disposal to ERDF. The staged waste area footprint will be addressed with the 100-F-26:9 subsite. Excavation depths at the subsite ranged from 4.3 meters to 5.2 meters (14 feet to 17 feet) below ground surface.

The SubSite is Part Of:

Code: 100-F-26

Names: 100-F-26; 100-F Water Treatment Facility Underground Pipelines

Code: 100-F-26:14

Classification: Accepted

Names: 100-F-26:14; 116-F-5 Influent Pipelines

Reclassification: Interim Closed Out (2/29/2008)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. It consisted of underground pipelines located southwest of the 105-F Building (a 10.2-centimeter (4- inch) influent pipeline that ran from the 105-F Reactor Building to the 116-F-5 ball washer crib, two process pipelines (30.48-centimeter [12- inch] and 15.24- centimeter [6- inch]) that connected to a previously remediated process pipeline (100-F-19:2); and a short 15.24- centimeter [6- inch] cast-iron pipe). These pipelines were associated with the 116-F-5 Ball Washer Crib and remnants of process pipelines on the west side of the 105-F Building.

The 30.48-cm (12 in) process line ran from the 115-F seal pit to the 60.96 cm (24 in) process sewer south of the fuel storage basin (W-73174). The 15.24 cm (6 in) process line received effluent from the tunnel eductor discharge (H-1-70185) and joined with the process line from the 115-F seal pit prior to entering the process sewer. The process sewer was remediated between August 2001 and December 2002 (CVP-2001-00003). The remedial design drawings also show a short 15.24 cm (6 in) cast-iron pipeline off the end of the ball washer influent line near the 105-F Building (0100F-DD-C0032). A possible reference to this pipeline is made on drawing M-1904 F sheet 5. The pipe is referenced by the notation "6 [inch] V.P. BELOW 12 [inch] V.P." with an arrow pointing to the 30.48 cm (12 in.) process line from the 115-F seal pit. No additional historical information is available regarding this pipe.

Location: The 100 F 26:14 pipeline subsite consists of underground pipelines associated with the 116-F-5 Ball Washer Crib and remnants of process pipelines on the west side of the 105-F Buildings. The 100-F-26:14 subsite is an influent pipeline that runs from 118-F-8 (105-F) Reactor Building to 116-F-5 trench.

Related Sites/ Structures: The pipelines are associated with the 116-F-5 crib.

Waste Type: Not Specified

Waste Description: The waste was contaminated pipelines and associated soils.

Closure Info: Interim: Remediation of this subsite was performed from February 1 through April 24, 2007. The excavation cut through the middle of the 118-F-8:4 Fuel Storage Basin area, that had been previously remediated. The total depth of the 118-F-8:4 excavation (8 meters [26 feet] below ground surface) was below the deepest (6 meters [20 feet]) segment of the 100-F-26:14 pipeline. Portions of pipeline that overlapped the 118-F-8:4 site were included in the 118-F-8:4 remediation report. The only pipeline discovered during remediation was a 15.24-cm (6-in.) vitrified clay pipe in a location where the 15.24-cm (6-in.) cast-iron pipe was expected. It was encased in concrete its entire length. The other pipelines are presumed to have been removed during previous remedial actions. There were no anomalies or stained soil discovered during remediation.

Approximately 700 BCM (916 BCY) of contaminated soil was disposed at the Environmental Restoration Disposal Facility and 900 BCM (1,177 BCY) of overburden and layback soil were stockpiled for use as clean backfill.

The SubSite is Part Of:

Code: 100-F-26

Names: 100-F-26; 100-F Water Treatment Facility Underground Pipelines

Code: 100-F-26:15

Classification: Accepted

Names: 100-F-26:15; Miscellaneous Pipelines Associated with 1608-F Sump

Reclassification: Interim Closed Out (3/18/2008)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The 100-F-26:15 waste site includes the remnant portions of underground process effluent and floor drain pipelines that originated at the 105-F Reactor that drained into the 1608-F sump and pumphouse.

Location: The 100-F-26:15 pipelines in the vicinity of the southeast corner of the 105-F Reactor.

Waste Type: Not Specified

Waste Description: The waste was radioactively contaminated piping and associated soils.

Closure Info: Interim: The only pipelines encountered during remediation of the 100-F-26:15 subsite were to the immediate west of the former 132-F-6, 1608-F site. All of the other pipelines included in the 100-F-26:15 subsite are believed to have been removed during previous remediation activities. The 100-F-26:15 subsite was remediated from January 29 through January 31, 2007. Two distinct areas were excavated resulting in disposal of approximately 82 cubic meters (107 cubic yards) of contaminated materials to the Environmental Restoration Disposal Facility. Only 3 of the 16 pipeline segments (numbers 2, 4, and 15 in Table 1 of the RSVP) were found during the excavation. Excavations for the remaining pipeline segments were performed to native soil to verify their previous removal. Eight of the pipeline segments (numbers 7, 8, 9, 10, 11, 12, 14 and 16) were associated with the remediation of the 100-F-19:2, reactor cooling water effluent

pipelines, in 2002 (CVP-2001-00003). The five remaining pipeline segments (numbers 1, 3, 5, 6, and 13) were not found during either of the pipeline removal activities in 2002 or 2007. These were most likely removed during previous demolition activities or historical pipeline replacement projects.

For the five pipeline segments that were not found during either remediation (numbers 1, 3, 5, 6, and 13), excavations at the locations shown on historical drawings were performed until native soil was encountered to verify their previous removal. Additional verification was available for pipeline segments 1 and 6 as these were associated with the 1608-F building. The below grade portion of the 1608-F building was present in the subsurface. It was used as a guide to verify these pipeline segments were no longer present. Excavation was performed next to the 1608-F building for pipeline segments 1 and 6 and continued until the bottom of the structure was reached. This activity verified the pipeline segments were no longer present.

The SubSite is Part Of:

Code: 100-F-26

Names: 100-F-26; 100-F Water Treatment Facility Underground Pipelines

Code: 100-F-26:16

Classification: Accepted

Names: 100-F-26:16; Reactor Cooling Water Pipelines

Reclassification: Interim No Action (1/11/2005)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The 100-F-26:16 subsite has been evaluated and determined to be a No Action site. It consisted of pipelines inside the Cooling Water Pipe Tunnels that ran between the 190-F Pumphouse and the 105-F Reactor. The 100-F-26:16 Reactor Cooling Water Pipelines are analogous to the 100-B-14:4 and 100-C-9:4 105-B and 105-C Cooling Water Pipelines.

Location: The process water tunnels were located due west of the 105-F Reactor (between 190-F and 105-F).

Closure Info: Interim: The process water piping had been contained inside the concrete tunnels. As part of decommissioning activities during 1987, the process water tunnels were filled to grade with clean soil. WHC-EP-0478 indicates the pipelines inside the tunnels were removed and salvaged at the time of decommissioning of the water tunnels.

There was no history of radiological contamination associated with the 100-F Cooling Water Tunnels and no known process incidents at 105-F Reactor that would have introduced contamination from the reactor into the tunnels. Historical sampling of concrete and soil underlying the 105-C Cooling Water Tunnels (BHI-01050) and pipe scale sampling inside the cooling water pipelines at the 100-B Reactor valve pit indicate that residual contamination associated with the 105-B and 105-C Cooling Water Tunnels meets the cleanup criteria.

The 100-F-26:16 105 F Reactor pipelines have been removed, the tunnels have been back-filled, and the analogous sites have been determined to meet the cleanup criteria. A through evaluation the 100-F-26:16 Reactor Cooling Water Pipelines found they are analogous to the 100-B-14:4 105-B Reactor Cooling Water Tunnels and 100-C-9:4 105-C Reactor Cooling Water Tunnels. Per Waste Site Reclassification form 2004-120, the 100-F-26: 16 105 F Reactor pipelines meet the cleanup criteria and the residual contaminant levels are protective of human health, groundwater and the Columbia River and support a Reclassification to No Action.

The SubSite is Part Of:

Code: 100-F-26
Names: 100-F-26; 100-F Water Treatment Facility Underground Pipelines

Code: 100-F-29 **Classification:** Accepted
Names: 100-F-29; 100-F Experimental Animal Farm **Reclassification** Final Closed Out (10/28/2015)
Process Sewer Pipelines
Type: Radioactive Process Sewer **Start Date:** 1/1/1945
Status: Inactive **End Date:** 1/1/1976

Description: The site was remediated, Interim Closed Out and later Final Closed Out. The site consisted of contaminated sewer pipelines that serviced the 100-F Experimental Animal Farm (EAF) facilities.

Location: The location consisted of parts of process sewers (underground pipelines) between various Experimental Animal Farm (EAF) buildings and Junction Box P-24F (H-1-13850).

Related Sites/ Structures: The sewer is associated with UPR-100-F-1. The related structures included all the facilities within the 100-F Area animal farm, such as the 146-FR Aquatic Biology Laboratory, the 141-H Isolation Building, the 141-F Sheep Barn, the 141-N Retention Basin Building, the 141-C Hog Barn, and the Junction Box JB-P-23F. Because the 108-F Biology Laboratory was not near the rest of the animal farm, its pipelines were included with 100-F-26.

Co-located pipeline sites in the 100-F Area included the 100-F-19 Water Treatment Pipelines, 100-F-26 river effluent lines, 100-F-39, clean water pipelines, 100-F-41 experimental animal farm pipelines and the miscellaneous pipelines in 100-F-44.

Process Description: Various Experimental Animal Farm (EAF) research projects yielded liquid waste effluents that were disposed of through the EAF process sewers. Research projects studied the effects of ionizing radiation on living plant and animal organisms. Radioisotopes were introduced to laboratory animals through inhalation, inoculation, ingestion, and absorption. Resulting wastes were flushed down floor drains into the process sewers. Contaminated animal straw bedding was placed over drains to allow drainage into the process sewer. The process sewers also received drainage when animal pens were hosed out to remove contaminated urine and feces and when fish tanks were drained.

Waste Type: Water

Waste Description: The waste is mixed (chemically and radiologically) contaminated piping (concrete, steel and vitrified clay) and contaminated soil. Several radioisotopes were used in varying concentrations. These included iodine-131, strontium-90, cesium-137, and isotopes of plutonium and uranium. All such research generated contaminated urine and feces. Other wastes resulted from cleaning contaminated pens and cages with water.

Closure Info: Interim: (Interim Closed Out) Remedial Action ran from August 2001 until December 2002. The 100-F-19:2 Reactor Cooling Water Effluent Pipeline and co-located sites, (116-F-11 Cushion Corridor French Drain, UPR-100-F-1 Sewer Line Leak, and the 100-F-29 Experimental Animal Farm Pipelines), were remediated as a group and documented in CVP-2001-00003. The group is referred to as the 100-F-19:2 site in the document. The unplanned release was within the footprint of the 100-F-29 pipeline excavation. The elevation of the bottom of the excavation was approximately 124.7 meters (409 ft) upon completion. The excavation area was approximately 19,000 square meters (205,000 sq. ft) with a maximum depth of approximately 5 meters (16 ft) and an average depth of approximately 3.7 meters (13 ft). Removal of the 100-F-29 pipelines near the northwest corner of the 116-F-14 (107-F Retention Basin) required shallower excavation, averaging approximately 1 meter (3 ft) in depth. Little evidence of the 116-F-11 french drain site was found during excavation of the 100-

F-19:2 pipelines. The location of the french drain was excavated and sampled to the design elevation 4.6 meters (15 ft).

Remediation included excavation of overburden, piping, debris and contaminated underlying soil. Approximately 39,347 metric tons (43,373 tons) of material including soil, debris and piping were removed and disposed at ERDF.

Final (10/28/2015): (Final Closed Out) Thirteen 100-F Area waste sites were reclassified to Final Closed out on form 2015-078. They had all previously been classified as Interim Closed Out. The waste sites included on this reclassification form are 100-F-10, 100-F-19 (and subsites 1,2 and 3), 100-F-29, 100-F-34, 116-F-2, 116-F-6, 116-F-9, 116-F-12, subsites 118-F-8:3 and :4, UPR-100-F-1. The Record of Decision (ROD) for the 100-FR-1, 100-FR-2, 100-FR-3, 100-IU-1, 100-IU-2 and 100-IU-6 Operable Units has defined these waste sites as all requiring institutional controls to restrict excavation into the deep zone (greater than 4.6 meters or 15 feet below the ground surface). However, no further remedial actions are required.

Institutional Control Boundaries have been defined to be broadly inclusive of waste site groups. Not all areas within these boundaries contain residual contamination greater than 4.6 meters (15 ft) below ground surface. An image of four Institutional Control Boundaries inside 100F Area was attached to the 2015-078 Reclassification form (and included in the WIDS library).

Code:	100-F-31	Classification:	Accepted
Names:	100-F-31; 144-F Sanitary Sewer System	Reclassification	Interim Closed Out (8/24/2006)
Type:	Septic Tank	Start Date:	
Status:	Inactive	End Date:	1/1/1977
Description:	The site has been remediated and Interim Closed Out The site consisted of a septic tank and drain field. The area has been restored to match the surrounding terrain.		
Location:	The site was located in the 100-F Area within the former Pacific Northwest Laboratory's Experimental Animal Farm site. The 144-F Building was located between the 141-C Animal Barn, Large Animal Barn & Biology Laboratory, Hog Barn Building and the 116-F-14 (107-F Retention Basin) site. The septic system was located directly south of 132-F-2 (144-F Building) and approximately 20 meters (65 feet) west of the 107-F Retention Basin Fence.		
Related Sites/ Structures:	The site received effluent from the 132-F-2 (144-F Particle Exposure Laboratory Building). Pipeline sites in the 100-F Area include the Process Effluent Pipelines in site 100-F-19, the Water Treatment Pipelines in site 100-F-26, the river effluent lines are site 100-F-39, the clean water pipelines were 100-F-41, the experimental animal farm pipelines in site 100-F-29 and miscellaneous pipelines in 100-F-44.		
Process Description:	The septic system was believed to have received both animal and human septic waste from the 132-F-2 (144-F Particle Exposure Laboratory). The 100-F Area included laboratories that performed radiological studies on various species of animals. These laboratories housed animals (mainly dogs) exposed to particulate materials. The 144-F Building was a one-story concrete block building with an office and six laboratories, and included indoor and outdoor animal runs.		
	The 100-F experimental farm was abandoned when Pacific Northwest Laboratory moved its biological studies to the 300 Area and it was believed that the 144-F facility was decommissioned and demolished in 1977, leaving the septic system in place.		
Waste Type:	Sanitary Sewage		

Waste Description: It is unclear from the drawings H-1-14122, Grading Plan Facilities for Radioactive Inhalation Studies and H-1-14123, Plumbing & Details-Facilities for Radioactive Inhalation Studies, whether the site received animal waste as well as human sanitary waste. Since the site serviced the 144-F Building, there is the potential to have received hazardous contaminants.

Closure Info: Interim: Remediation of the 100-F-31 waste site consisted of the removal of the septic tank, drain field, associated piping, and overburden material. Approximately 350 bank cubic meters (460 bank cu yd) of material was excavated and disposed at the Environmental Restoration Disposal Facility (ERDF). The site was excavated to a maximum depth of 3.0 meters (9.8 ft) below ground surface.

Following excavation of the 100-F-31 waste site, verification sampling was performed on February 6, 2006. Analytical results from the verification soil samples indicated that the northern side of the excavation contained residual contamination of aroclor-1248. This residual PCB was detected at a concentration of 7.3 mg/kg, which exceeds the direct exposure RAG (0.5 mg/kg). Additional remediation was performed in April 2006 and the PCB-contaminated soil was removed from the north sidewall of the 100-F-31 excavation footprint. A second set of verification samples were collected on May 17, 2006. These samples were analyzed for PCBs to verify that the subsequent remediation efforts had successfully removed the contamination.

Code: 100-F-33	Classification: Accepted
Names: 100-F-33; 146-F Aquatic Biology Fish Ponds	Reclassification: Interim Closed Out (8/25/2006)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The site has been remediated and Interim Closed Out. The waste site is also referred to as the 146-F Aquatic Biology Fishponds and the fish laboratory. It was designed to conduct tests on fish. The ponds were removed in 1975. There was no visual evidence remains of their original location. The fish ponds were constructed of unlined reinforced concrete. Originally, there were 6 small rectangular ponds. Each pond was divided into two sections. There was also one large circular pond and one large rectangular pond. The waste site is the area where unplanned releases likely occurred from the fish ponds.

Location: The site was located approximately 610 meters (2,000 feet) northwest of the 105-F Reactor Building. Well 199-F5-6 was located just west of the site. The fish ponds were located west of 146-F Aquatic Biology Laboratory, which has been demolished.

Release Description: There was no documented record of an unplanned release from this site. However, due to leakage from the ponds and associated piping and/or splashing from within the ponds, the release of contaminated water to the surrounding environment was likely.

Related Sites/Structures: The site was related to the 146-F Aquatic Biology Fish Ponds laboratory.

Process Description: The studies involved exposing fish to varying concentrations of reactor cooling water effluent to assess possible effects of effluent discharge on aquatic life in the Columbia River. In addition to hatchery troughs, there were six rearing ponds located next to the laboratory. Effluent water was continuously circulated through the troughs at a rate of about 0.2 to 0.3 liters per second (3 to 5 gallons per minute) and was discharged to the Pacific Northwest Laboratory Outfall (116-F-16) via the 147-F Pump House. Testing began in 1945 and was conducted using various mixtures of river and effluent water to determine effects on fish. The effluent water contained a variety of chemicals that included process cooling water, sludge from the water purification area, condenser water, refrigeration cooling water, floor drainage containing radioactive substances and substances that inhibited corrosion, such as materials used for purging the tubes in the pile. From 1947 through 1950, salmon eggs, rainbow trout,

carp, and crayfish were tested under several conditions. Testing included unrefrigerated effluent water, effluent treated with five parts of river water from the 107-F Retention Basin, charcoal filtered and unfiltered river water with 2 parts per million (ppm) dichromate added, pre-pile process water, 5 ppm sodium silicate, and copper sulfate. The testing was designed to determine the accumulation of activity in bone, liver, skin, and the gastrointestinal tract. Some of the feed supplied to the fish was algae and snails. Document HW-20266-RD stated that some of the feed was grown in effluent from the 107-F Retention Basin.

The fish ponds were constructed of unlined reinforced concrete. The configuration of the fish ponds were 6 small rectangular ponds, in a 2 by 3 matrix, one large circular pond located due south of the smaller ponds. Two larger rectangular ponds may have been located between the 6 smaller ponds and the circular pond. There is a note on Drawing H-1-2898 Sheet M-1, Mechanical Plot Plan, Aquatic Biology Laboratory that says that these larger rectangular ponds were not built during 1951-1952 construction. These ponds may never have been constructed. Later drawings show only the six smaller rectangular ponds and the one large circular pond. The six pairs of small rearing ponds were numbered 1 through 12. The structures had outer dimensions of 3.35 meters (11 feet) by 2.90 meters (9.5 feet). Each had a center dividing wall separating it into two halves. If the outer walls and dividing walls were 15 centimeters (6 inches) thick, the dimensions of each half would have been 1.2 meters (4 feet) by 3.0 meters (10 feet) by 0.9 meters (3 feet) which is the size of a liquid waste disposal facility documented in both HW-43121 and HW-33305. Pond 13 was the largest, measuring 16 meters by 2 meters (51 feet by 6 feet). It also contained a circular pond that measured 9 meters (30 feet) in diameter. Drawing H-1-2898, Architectural Plot Plan, Aquatic Biology Laboratory, showed the addition of 3 additional ponds. Hanford Drawing, H-1-2898, Sheet 17, Rectangular Ponds - Aquatic Biology Laboratory shows a pair of the pond structures that were 5.8 meters (19 feet) by 3.5 meters (11.5 feet). Each of the ponds were split lengthwise down the middle by a divider. The divider was removable and did not extend the full length of the pond. The ponds sloped towards the end of the structure containing the drains (2 drains per structure). The depth of the ponds was 0.91 meters (3 feet) sloping to 1 meter (3.3 feet). There was a note on Drawing H-1-2898 Sheet M-1, Mechanical Plot Plan, Aquatic Biology Laboratory that stated these larger rectangular ponds were not built during 1951-1952 construction. These ponds may never have been constructed. Later drawings show only the six smaller rectangular ponds and the one large circular pond. Hanford Drawing H-1-2898, Sheet 18, Circular Pond - Aquatic Biology Laboratory shows the large circular pond to be 9.1 meters (30 feet) in diameter and about 0.87 meters (34 inches) high. The pond slopes to the middle toward a center drain.

Waste Type: Water

Waste Description: If the fish ponds or supporting pipelines had leaked, the waste would contain the same contaminants as the radioactive process effluent. A pipeline containing radioactive process effluent came from the reactor to this site. The waste was the pipelines and contaminated soil. Contaminants of potential concern were Co-60, Ce-137, Eur-152, Eu-154, Eu-155, Pu-238, Pu-239/240, Sr-90, U-234, U-235, Cr6, Hg, Pb, and polycyclic aromatic hydrocarbons (PAHs).

Closure Info: Interim: In 2004, three test trenches were dug and confirmatory samples collected from the trenches. Based on field observations during confirmatory sampling and the results of laboratory analysis of samples collected from trench 1 and trench 2, it was decided that the northern portion of the site required remediation. The confirmatory sample results for the southern portion of the site, collected in the area of the circular fish pond (test pit 3), did not indicate that residual contaminants were present exceeding cleanup criteria. It was decided that this portion of the site did not require remedial action. Site personnel noted that 10 meters (33 ft) of the process sewer leading to the circular pond in the south half of the site appeared to be outside of the excavation. The drain at the head end of this sewer was sampled (J01TF8) as part of 100-F-33 test pit 3. It did not require remedial action.

Remedial action of the northern portion of the site was initiated on August 5, 2005, and

continued through August 8, 2005, with excavation of 2,024 metric tons (2,231 U.S. tons) of material including concrete debris, piping, and soil. Excavated soil and debris were staged at the site until disposal of the materials to the Environmental Restoration Disposal Facility (ERDF) occurred from September 19 to September 21, 2005. Radiological surveys were performed over the excavation and staging pile areas using a mobile sodium iodide detector.

Code: 100-F-34	Classification: Accepted
Names: 100-F-34; Biology Facility French Drain	Reclassification: Final Closed Out (10/28/2015)
Type: French Drain	Start Date:
Status: Inactive	End Date:

Description: The site has been remediated, Interim Closed Out and later Final Closed Out. The french drain was removed during the 100-F Area cooling water effluent pipeline remediation activity in 2002 (see 100-F-19:1).

Location: The drain was located due south of the demolished 1705-F Experimental Gardens. The drain location is noted on Hanford Drawing H-1-13850. There was a label on the drawing stating "Greenhouse and Slab (Removed) June 6, 1975". Behind and between the "o" and the "v" of "Removed" is a small circle that likely indicates the location of the drain.

Related Sites/ Structures: The site is believed to be associated with one of the Biology Facilities that were part of the Experimental Animal Farm.

Process Description: It was not known what purpose this site served. The pipeline that connected the french drain to a facility has not been located on any of the numerous drawings that have been researched for this area.

Closure Info: Interim (5/22/2002): (Interim Closed Out) The 100-F-19:1 North Pipelines, 100-F-19:3 West Pipelines, 100-F-34 Biology Facility French Drain, and the 116-F-12 French Drain were remediated as a group, documented in CVP-2001-00002. The group is referred to as the 100-F-19:1 site. The 100-F-19:1 site remedial action began on August 7, 2001. Excavation of the site involved removing overburden materials, pipelines, french drain structures, and contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Shallow zone excavation occurred both in the vicinity of the 100-F-19:3 West Pipelines and in the vicinity of the 100-F-19:1 North Pipelines, with a maximum depth of 4.6 meters (15 ft). The deep zone excavation occurred in the southern half of the 100-F-19:1 North Pipelines section of the remedial action, with a approximate maximum depth of 5.0 meters (16 ft). The elevation of the bottom of the excavation varied, but averaged approximately 119.6 meters (392.4 ft). At the completion of remedial action in August 2001, the excavation was approximately 25,710 sq. meters (276,740 sq. ft.) in area. Approximately 56,335 metric tons (62,099 tons) of contaminated materials from the site were disposed of at the ERDF.

These sites meet the cleanup standards specified in the Amendment to the Interim Action Record of Decision for the 100-BC-1, 100-DR-1, and Operable Units (ROD). Excavation of the site involved removing overburden materials, pipelines, french drain structures, and contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Shallow zone excavation occurred both in the vicinity of the 100-F-19:3 West Pipelines and in the vicinity of the 100-F-19:1 North Pipelines, with a maximum depth of 4.6 meters (15 ft). The deep zone excavation occurred in the southern half of the 100-F-19:1 North Pipelines section of the remedial action, with a approximate maximum depth of 5.0 m (16 ft). The elevation of the bottom of the excavation varied, but averaged approximately 119.6 m (392.4 ft).

The results showed that the materials from the 100-F-19:3 subsite containing COCs at concentrations exceeding RAGs have been excavated and disposed of. Remedial actions were performed so as to allow rural-residential use of shallow zone soils (i.e., surface to 4.6 meters [15 feet] deep) and to protect groundwater and the Columbia River. All cleanup verification samples for the 100-F-19:3, 100-F-34 and 116-F-12 sites are listed under 100-F-19:1.

Final (10/28/2015): (Final Closed Out) Thirteen 100-F Area waste sites were reclassified to Final Closed out on form 2015-078. They had all previously been classified as Interim Closed Out. The waste sites included on this reclassification form are 100-F-10, 100-F-19 (and subsites 1,2 and 3), 100-F-29, 100-F-34, 116-F-2, 116-F-6, 116-F-9, 116-F-12, subsites 118-F-8:3 and :4, UPR-100-F-1. The Record of Decision (ROD) for the 100-FR-1, 100-FR-2, 100-FR-3, 100-IU-1, 100-IU-2 and 100-IU-6 Operable Units has defined these waste sites as all requiring institutional controls to restrict excavation into the deep zone (greater than 4.6 meters or 15 feet below the ground surface). However, no further remedial actions are required.

Institutional Control Boundaries have been defined to be broadly inclusive of waste site groups. Not all areas within these boundaries contain residual contamination greater than 4.6 meters (15 ft) below ground surface. An image of four Institutional Control Boundaries inside 100F Area was attached to the 2015-078 Reclassification form (and included in the WIDS library).

Code:	100-F-36	Classification:	Accepted
Names:	100-F-36; 108-F Biological Laboratory; 108-F Chemical Pump House	Reclassification	Interim No Action (5/24/2007)
Type:	Laboratory	Start Date:	1/1/1944
Status:	Inactive	End Date:	1/1/1973
Description:	The site has been evaluated and reclassified to No Action. The waste site consisted of the 108-F building that was demolished in August of 1999. Most of the building debris and foundations were removed. All the exposed piping was cut at the edge of the excavation. The pipe trench, sump, and french drain 116-F-15 were removed. All disturbed areas were graded smooth and the facility footprint soils were fixed in place with soil cement.		
Location:	The site was located approximately 100 meters (330 feet) east of the 105-F Reactor Building.		
Related Sites/ Structures:	The initial intended use of the 108-F Building was to provide chemical treatment of the 105-F Reactor cooling water. Site 116-F-15 was a sump with an associated trench in the middle of the building. During excavations and sampling in Winter 2002, the 6 inch (15 centimeter) cast iron pipe at this location had radiation readings of 3000 disintegrations per minute (dpm) alpha and 250,000 dpm beta-gamma. The excavation was closed up without removing any material. French drains on the perimeter of the building included 100-F-4, 100-F-11, 100-F-15, and 100-F-16.		
Process Description:	The 108-F building was constructed in 1944 as part of the original Hanford site construction. It was originally a chemical makeup facility that supported the 105-F reactor. In 1949, the 108-F building was completely remodeled for use in life-science studies for the effects of radiation and contamination on plant and animal life.		

The original 108-F building was a four-story steel frame, concrete block structure with reinforced concrete foundation, and a total floor space of about 1,858 square meters (20,000 square feet). The roof was constructed of concrete tile with a built-up tar and gravel surface. In 1949, and again in 1962, the 108-F building was remodeled, and the floor space increased by the addition of a 1,022 square meter (11,000 square foot) annex. This addition was a three-story concrete block structure adjoining the older building.

The interior of the building contained 39 offices, 47 laboratories, and a heavily shielded cobalt-60 source room, 18 rooms for handling small animals, a large conference room, an administrative section, a library, lunch and locker rooms. Since radioactive materials were used in the work performed within the building, the laboratories and storage rooms were maintained in a controlled status until 1973 when the laboratory activities were phased out and transferred to 300 Area facilities. From 1983 through 1984, the first floor of the 108-F Building was used for office space.

Waste Type: Equipment

Waste Description: The main drain trench and sump were posted as a radiological contamination area. Potential contaminants of concern for this facility were plutonium-238, strontium-90, cobalt-60, and cesium-137.

Waste Type: Equipment

Waste Description: On the first floor there are exposed sheets of lead, approximately 0.64 centimeters (0.25 inches) thick under the wallboard. All paint within the facility is suspected to contain lead.

Waste Type: Oil

Waste Description: Oil in the elevator motor, compressor motors, water coolant system and hoist equipment was suspected to contain polychlorinated biphenyl (PCB) and Resource Conservation and Recovery Act of 1976 (RCRA) metals.

Waste Type: Soil

Waste Description: Friable asbestos insulation, asbestos cement, pipe wrapping and suspected asbestos-containing floor tiles were in the building before demolition. The 108-F closeout report reported contaminants of concern as mercury, PCBs, lead, asbestos, sodium dichromate, and miscellaneous low radiological contamination.

Closure Info: Interim: The 108-F facility became inactive in 1973. From 1977 through 1983, contaminated material was removed from inside the building and disposed in 200 Area burial grounds. The 108-F building was demolished in 1999. The contaminated cast-iron pipe found during the February 2002 excavation was not located during this remedial action. Therefore, an additional test pit was excavated on November 29, 2005, in an attempt to locate the contaminated 15-cm (6-in.) diameter cast-iron pipe. The additional excavation was unsuccessful, and the excavated material was placed back in the pit. Additional efforts in July 2006 to locate the contaminated pipe using a metal detector were also unsuccessful. However, the contaminated 15-cm (6-in.) diameter cast-iron pipe (100-F-26:4) was found during test pitting activities in December 2006. The contaminated pipe is associated with the 100-F-26:4 pipeline site and is not a part of the 116-F-15 sump as previously indicated. Remediation and sampling activities for the 100-F-26:4 pipelines site will be included in a separate verification package.

Remediation of the 116-F-15 waste site was performed on September 26, 2005. It consisted of the removal of approximately 86 metric tons (95 US tons) of material, including concrete debris, piping, and soil being disposed at the Environmental Restoration Disposal Facility. The soil was excavated and field surveyed to a depth of approximately 2.6 meters (8.5 feet).

Following the remediation of 116-F-15, confirmatory sampling at the 100-F-36 waste site was performed on December 5, 2006 and verification sampling of the 116-F-15 waste site was performed on December 12, 2006.

The 100-F-36 waste site was evaluated and confirmatory samples collected. It was determined to require No Action.

Code: 100-F-37

Classification: Accepted

Names: 100-F-37; French Drain Discovered Near Hydrant F-2 **Reclassification** Interim No Action (8/11/2004)

Type: French Drain **Start Date:**

Status: Inactive **End Date:**

Description: The site was evaluated and determined to require No Action. The waste site consisted of an abandoned french drain found while digging an electrical conduit trench. The soil around the drain structure was discolored.

Location: The site was about 235 meters (760 feet) east-northeast of the 100-F Reactor. It was in the northeast corner of the intersection of the F Area perimeter Road and the north-south road that ran on the east side of the 1716-F, 1713-F, 1717-F, and 1707-F facilities.

Waste Type: Soil

Waste Description: The analytical results showed a high level of lead at 214 ppm.

Closure Info: Interim: Sampling of the discolored stained soil associated with the french drain was performed on November 3, 2000 to support disposal of the concrete pipe that was removed during excavation of the electrical conduit trench. The sample was submitted for inductively coupled plasma metals (ICP metals), mercury, and semi-volatile organic analysis (SVOA). Radiological surveys during excavation and sampling did not identify any field detectable radiological activity. Since the site was not associated with historical radiological processes, the sample was not analyzed for radionuclides.

Code: 100-F-38 **Classification:** Accepted

Names: 100-F-38; Yellow Stained Soil Near Hydrant F-2 **Reclassification** Interim Closed Out (3/13/2006)

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The site has been remediated and Interim Closed Out. The waste site consisted of yellow soil discovered during the excavation of a trench for electrical conduit in November 2000. The trench ran diagonally through the parking lot from the subcontractor trailer to Hydrant F-2.

Location: The site was located approximately 235 meters (760 feet) east-northeast of the 100-F Reactor. It was in the northeast corner of the intersection of the F Area perimeter road and the north-south road that ran on the east side of the 1716-F, 1713-F, 1717-F, and 1707-F facilities.

Related Sites/ Structures: A small unidentified structure north of this site can be seen in aerial photos shown in the 100-F Area Technical Baseline Report. The yellow stained soil was found immediately north of Hydrant F-2, and south of the unearthed rust coated rocks and french drain (100-F-37), discovered in the same excavation. Their relationship, however, was not known.

Waste Type: Soil

Waste Description: The stained soil showed high levels of chromium and lead. No radioactivity was detected with field instruments.

Closure Info: Interim: Remedial action occurred in September 15, 2005. Approximately 5.4 metric tons of material was disposed at ERDF. The depth of the excavation was approximately 0.9 meters (3 feet). There were no stockpile areas associated with this site. Verification sampling occurred in November 21, 2005.

Sampling of the yellow soil at the site was performed during November 2000 when the

discolored soil was first encountered while trenching at that location for the placement of underground utilities. At the time of discovery, the yellow soils were assumed to be associated with the disposal or spilling of unused paint. Therefore, inductively coupled plasma (ICP) metals were identified as the potential contaminants associated with the yellow soil. Lead and chromium values were 8850 parts per million (ppm) and 2080 ppm, respectively. The soil was then placed back into the trench and covered.

Although the excavation of the utility trench was not performed within a radiologically controlled area, a radiological control technician was directed to perform a field survey to verify that radiological contamination was not present. Radiological contamination was not detected during this survey.

In August 2004 a remove, treat, and dispose (RTD) report was done to provide documentation to support the remedial action decision for the site, as required by the Sampling and Analysis Plan for the 100 Area Remaining Sites. The 2000 soil sampling results indicated that a remedial action was necessary due to the presence of barium, chromium and lead in concentrations exceeding the Rags. The 100-F-38 waste site is located in a building parking lot, prone to high traffic volumes posing a potential safety hazard. Because of the potential hazard associated with an open excavation in parking lot, three focused verification samples were collected and the excavation backfilled.

Code:	100-F-39	Classification:	Accepted
Names:	100-F-39; 100F River Effluent Pipelines; 100F River Lines	Reclassification	None
Type:	Radioactive Process Sewer	Start Date:	
Status:	Inactive	End Date:	
Description:	This site consists of the river effluent pipelines (river lines) that extend from 1904-F outfall (116-F-8) in the 100F area into the main channel of the Columbia River.		
Location:	The river lines are located in the Columbia River, adjacent to the 100F area. The lines extend north into the main channel of the river from the 1904-F outfall (116-F-8). The river effluent pipelines extend from, and are perpendicular to, the discharge (river side) face of the 116-F-8 outfall structure for 91 meters (300 feet) into the main channel of the river.		
Release Description:	No recorded releases were found.		
Related Sites/Structures:	The site is associated with the 116-F-8 outfall, the process effluent lines (100-F-19), the water treatment facility pipelines (100-F-26), the 107-F Retention Basin (116-F-14), the animal barn (141-C), the 100F Experimental Animal Farm Process Sewer Pipelines (100-F-29), the aquatic biology fish ponds (100-F-33), the PNL outfall (116-F-16), the PNL spillway (100-F-43), and the 100-F-42 spillway. Pipeline sites in the 100-F Area include the Process Effluent Pipelines in site 100-F-19, the Water Treatment Pipelines in site 100-F-26, the river effluent lines are site 100-F-39, the clean water pipelines were 100-F-41, the experimental animal farm pipelines in site 100-F-29 and miscellaneous pipelines in 100-F-44.		
Process Description:	Reactor cooling water was discharged from the 105-F Building through 152 centimeter (60 inch) diameter effluent lines to temporary storage in 116-F-14 (the 107-F Retention Basin), before being pumped to the river via 116-F-8 and two associated 107 centimeter (42 inch) pipelines (100-F-39). In the event the lines became plugged or had to be removed from service during operation, the effluent overflowed the outfall and entered the river via an attached spillway (100-F-42). The two river lines were constructed of 107-centimeter (42-inch) diameter reinforced concrete/steel pipes with 1.3-centimeter (0.5-inch) thick walls. The two parallel lines were originally 91 meters (300 feet long). During a survey in 1994, the pipes		

were found to extend about 24 meters (80 feet) offshore, protruding 1.2 to 2.4 meters (4 to 8 feet) above the riverbed. No buried or exposed pipelines could be found further offshore using geophysical instruments. The pipelines may have been obscured by large pieces of debris or riprap. In 1946, damaged sections of pipe were removed from the river and buried in the riverbank. The broken pipe sections were buried in the riverbank just upstream of the outfall and marked with stakes.

Waste Type: Process Effluent

Waste Description: The waste includes the pipelines and the contaminated scale and sediment which may be contained within them. Contaminants of concern/potential concern are based on those for 116-F-8 Outfall Structure. Contaminants of concern include cobalt-60, europium-152, europium-154, europium-155, and hexavalent chromium. Contaminants of potential concern include carbon-14, cesium-137, nickel-63, and strontium-90.

Code: 100-F-42

Classification: Accepted

Names: 100-F-42; 1904-F Spillway; 100-F-39:1 Flume

Reclassification: Interim Closed Out (9/26/2006)

Type: Outfall

Start Date:

Status: Inactive

End Date:

Description: The site has been remediated and Interim Closed Out. The site consisted of a reinforced concrete spillway (also referred to as a flume). The spillway extended from the 116-F-8 Outfall to the Columbia River shoreline and into the river.

Location: The spillway was located approximately 214 meters (700 feet) north of the 116-F-14 Retention Basin. The upper end of the spillway began at the west face of the outfall and terminated in the river.

Related Sites/ Structures: The site was associated with the 100-F-39, 100-F River Effluent Pipelines, the 116-F-8 Outfall Structure, the 116-F-16 (PNL) Outfall, and 100-F-43 (PNL) Spillway.

Process Description: The spillway was an alternate discharge point for the 116-F-8 Outfall Structure. It was to be used only if the 100-F-39 river effluent pipelines were blocked, damaged, or undergoing maintenance. There was no corroborated physical or historical evidence that the spillway was ever used. The flume was constructed of reinforced concrete and was 4 by 0.6 meters (14 by 2 feet) deep and about 40 meters (130 feet) long. It was an open concrete structure with a flat bottom and two sidewalls. An engineered erosion barrier composed of heavy riprap was constructed at the discharge end of the concrete structure. The spillway was designed to prevent excessive backwater at the 107-F Retention Basin during high water or in the event of a blockage of the outfall lines.

Waste Type: Construction Debris

Waste Description: If ever put into service, the COPCs for the 100-F-42 spillway would be the same as those for the 116-F-8 outfall structure. The contaminants of concern include Cobalt-60, Europium-152/154/155, and hexavalent chromium.

Closure Info: Interim: The 100-F-42 Spillway was administratively separated from the 116-F-8 Outfall for inclusion within the Remaining Sites ROD by agreement among the Tri-Parties. It was subsequently determined that sufficient evidence existed to warrant remedial action during remediation of the 116-F-8 waste site, therefore both waste sites were remediated and evaluated as a single unit.

Remedial action activities at the waste sites were conducted from August 31, 2004, to September 22, 2005. Remediation involved excavation and staging of clean overburden

material and removal of the demolished concrete outfall structure, the concrete spillway structure above the Columbia River ordinary high water mark, and contaminated soil to the extent required to satisfy the RAOs and corresponding RAGs. The residual 100-F-39 effluent pipelines will be sealed with concrete prior to backfill of the remediation footprint. Contaminated materials were disposed at the ERDF. Approximately 1,325 square meters (14,260 square feet) of plan area was excavated, including excavation within the deep zone (greater than 4.6 meters [15 feet] below ground surface) up to 8 meters (26 feet) below ground surface. Approximately 4,900 metric tons (5,400 U.S. tons) of material from the sites was removed and disposed at the ERDF.

Code:	100-F-43	Classification:	Accepted
Names:	100-F-43; 116-F-16 PNL Outfall; Spillway for PNL Outfall; 100-F-39:1	Reclassification	Interim Closed Out (9/14/2006)
Type:	Outfall	Start Date:	
Status:	Inactive	End Date:	
Description:	The site has been remediated and Interim Closed Out. The 100-F-43 spillway (also referred to as a "flume") was constructed of reinforced concrete. It extended from the 116-F-16 Outfall to the Columbia River shoreline and into the river. An engineered erosion barrier composed of heavy riprap was constructed at the discharge end of the concrete structure.		
Location:	The site was located approximately 670 meters (2,200 feet) northeast of the 105-F Reactor Building and about 15 meters (50 feet) upstream of the 116-F-8 Outfall. It was connected to the 116-F-16 PNL outfall face at E580952 N148128, and extends into the river to E580975 N148160.		
Related Sites/ Structures:	The site was associated with 100-F-29 (100-F EAF Process Sewer Pipelines), 100-F-19, 100-F Reactor Cooling Water Effluent Underground Pipelines, Contaminated Underground Lines, Effluent Water System, 1904-F Process Sewer (See Subsites), the 116-F-8 (1904-F) Outfall Structure, the 100-F-42 (1904-F) Spillway, and the 116-F-16 PNL Outfall.		
Process Description:	The 116-F-16 PNL Outfall emptied into the spillway via direct discharge. The spillway was a 4.6-meter (15-foot) wide concrete structure that extended approximately 6.1 meters (20 feet) out from the shoreline and approximately 3.7 meters (12 feet) into the Columbia River. The sides were 46 centimeters (18 inches) high and extended down the length of the structure. The vertical walls of the upper portion had been demolished and covered with soil.		
Waste Type:	Animal Waste		
Waste Description:	The unit received animal sewage, 107-F Retention Basin water from fish studies, and low-level contamination resulting from various 100-F EAF projects. If ever put into service, the COPCs for the 100-F-42 spillway would be the same as those for the 116-F-16 outfall structure, and include Plutonium-239/240, Strontium-90, Cesium-137, Lead, and hexavalent chromium.		
Closure Info:	Interim: The 100-F-43 waste site was administratively separated from the 116-F-16 waste site for future inclusion within the Remaining Sites Record of Decision by agreement among the Tri-Parties. It was subsequently determined that sufficient evidence existed to warrant remedial action of both waste sites as a single unit. All samples collected during remediation are listed under 116-F-16.		

During decommissioning work performed during the 1980's, the portion of the spillway above the river level was demolished and covered with soil. Remedial action activities at the sites were conducted from August 31, 2004, to September 8, 2005. Remediation involved excavation and staging of clean overburden material and removal of the outfall, the concrete spillway structure above the Columbia River ordinary high water mark, and contaminated soil to the

extent required to satisfy the RAOs and corresponding RAGs.

Approximately 384 square meters (4,130 square feet) of plan area was excavated, with all remedial activities restricted to the shallow zone (less than 4.6 meters [15 feet] below ground surface). Approximately 2,090 metric tons (2,300 U.S. tons) of contaminated material was removed from the site and disposed at the ERDF.

Code: 100-F-44	Classification: Accepted
Names: 100-F-44; 100-F Miscellaneous Pipelines (See Subsites)	Reclassification: Interim Closed Out (12/15/2011)
Type: Process Sewer	Start Date:
Status: Inactive	End Date:
Description: All ten subsites have been addressed and reclassified to Rejected, No Action or Interim Closed Out. Therefore, the parent site is considered Interim Closed Out. The waste site consisted of a compilation of pipelines and pipeline segments not previously addressed in any closure documents. Some subsites required remedial action and others were evaluated and determined to require No Action. Some segments were reclassified to Rejected.	
Location: The underground pipeline segments are located throughout the 100-F Area and co-located with those described in waste site 100-F-26 (100-F Water Treatment Facility Underground Pipelines with 16 subsites).	
Related Sites/Structures: Segments of pipelines were identified within the areas of the following buildings: 105-F, 1717-F, 190-F, 1608-F, 141-C, 187-F1 elevated water tower and 189-F.	
Pipeline sites in the 100-F Area include the 100-F-19 Process Effluent Pipelines, the 100-F-26 Water Treatment Pipelines, the 100-F-39 river effluent lines, the 100-F-41 clean water pipelines, the 100-F-29 experimental animal farm pipelines and the 100-F-44 miscellaneous pipelines.	

This Site has the Following SubSites:

Code: 100-F-44:1
Names: 100-F-44:1; Discovery Pipeline Near 182-F Reservoir
Code: 100-F-44:2
Names: 100-F-44:2; Discovery Pipeline Near 108-F Building
Code: 100-F-44:3
Names: 100-F-44:3; 1607-F3 Sewer System Pipeline
Code: 100-F-44:4
Names: 100-F-44:4; Discovery Pipeline in Silica Gel Pit
Code: 100-F-44:5
Names: 100-F-44:5; Process Sewer Pipelines
Code: 100-F-44:6
Names: 100-F-44:6; 189-F Refrigeration Pipeline
Code: 100-F-44:7
Names: 100-F-44:7; 1717-F Blowdown Pipeline
Code: 100-F-44:8
Names: 100-F-44:8; 1717-F Fuel Oil Supply and Return Pipelines

Code: 100-F-44:9
Names: 100-F-44:9; 105-F Process Sewer Pipeline
Code: 100-F-44:10
Names: 100-F-44:10; 141-C Sewer Pipelines; 100-F Experimental Animal Farm Sewer Pipelines

Code: 100-F-44:1 **Classification:** Accepted
Names: 100-F-44:1; Discovery Pipeline Near 182-F Reservoir **Reclassification** Interim No Action (4/26/2007)
Type: Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The 100-F-44:1 pipeline subsite has been evaluated and determined to require No Action. It was discovered during confirmatory sampling at the 100-F-26:1 test pit 5. The test pit contained a junction box with two 76 centimeters (30-inches) reinforced concrete pipes and a previously unidentified 20-centimeter (8-inch) carbon steel pipe. The smaller pipe was just west of the 182-F Reservoir and ran north from the junction box an undetermined distance at a depth of 2.1 meters (7 feet) below the ground surface. The only building in the vicinity was the former 182-FA Pump Test Stand.

The Pump Test Stand was built in 1959 to test new designs for impellers and prototype pumps for future use at the 190 Pumphouse. It was located west of the 182-F reservoir. The pumps, instrument panels and suction piping were housed inside an army surplus prefabricated building. Apparently the project was of a short duration. Therefore sanitary and steam utilities were not constructed. The only underground piping installed from the pump test stand was between the 182-F reservoir and the process sewer. Water from the 182-F reservoir was recirculated through a suppression tank with constant makeup and bleed to control temperature rise.

Location: The pipeline runs north-south and west of the 182-F reservoir. The junction box was sampled at coordinates N148179 E580343 where the pipeline starts, before continuing north for an undetermined distance at a depth of 2.1 meters (7 ft) below ground surface.

Related Sites/ Structures: This subsite is associated with the remediation of 100-F-26:1.

Waste Type: Not Specified

Waste Description: The waste is piping, scale/sediment, concrete, and soil (if contaminants are present).

Closure Info: Interim: The 100-F-44:1 pipeline site was discovered during confirmatory sampling at the 100-F-26:1 test pit 5. The test pit contained a junction box with two 76 centimeters (30-inches) reinforced concrete pipes and a previously unidentified 20-centimeter (8-inch) carbon steel pipe. The smaller pipe was just west of the 182-F Reservoir and ran north from the junction box an undetermined distance at a depth of (7 feet) below the ground surface. The only building in the vicinity was the former 182-FA Pump Test Stand.

The Remaining Site Verification Package for 100-F-26:1 North Process Sewer Collection Pipelines (Attachment to Waste Site Reclassification Form 2005-008) documented that the process sewer that joined the 182-FA discharge pipe at the junction box was sampled as part of confirmatory sampling for the 100-F-26:1 pipelines site. Based on these results, No Action is required for this segment of pipeline. Evaluation of the confirmatory sample results for the 100-F-26:1 satisfied the remedial action objectives and the site was reclassified to "No Action". The water carried by the 100-F-44:1 pipeline was essentially the same water as that carried by the

100-F-26:1 pipeline. Therefore no remedial action for the 100-F-44:1 subsite was needed and it was reclassified on WSRF form 2007-05.

The SubSite is Part Of:

Code: 100-F-44

Names: 100-F-44; 100-F Miscellaneous Pipelines (See Subsites)

Code: 100-F-44:2

Classification: Accepted

Names: 100-F-44:2; Discovery Pipeline Near 108-F Building

Reclassification Interim No Action (5/30/2008)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The subsite has been evaluated and determined to require No Action. The 100-F-44:2 subsite is a 0.05 meter (2-in.) steel pipeline that was discovered in a junction box during confirmatory sampling of the 100-F-26:4 pipeline in December 2004. The 100-F-44:2 pipeline fed into the 100-F-26:4 subsite, the 0.15 meter (6-in.) vitrified clay pipe process sewer pipeline from the 108-F Biology Laboratory at the junction box. Historical and drawing research supports the conclusion that the 100-F-44:2 pipeline is associated with the former 1,140,000 L (300,000-gal) 187-F1 elevated water tower. This information includes the proximity of the junction box location (where the pipeline was discovered) to the 187-F1 elevated water tower and the geophysical results that demonstrate that the pipeline's path is to the water tower.

Location: This pipeline is on the east side of the 187-F1 water tower.

Waste Type: Not Specified

Waste Description: The waste includes the pipelines and any contaminated soil associated with these pipelines.

Closure Info: Interim: Historical and drawing research supports the conclusion that the 100-F-44:2 pipeline is associated with the former 1,140,000 L (300,000-gal) 187-F1 elevated water tower. This information includes the proximity of the junction box location (where the pipeline was discovered) to the 187-F1 elevated water tower and the geophysical results that demonstrate that the pipeline's path is to the water tower.

The geophysical survey of the 100-F-44:2 subsite was conducted in January 2007 using ground-penetrating radar. Two east-westerly trending linears were identified that appear to originate or pass through the former junction box location. The linear that extends to the east is consistent with the location and depth of the 100-F-26:4 pipeline. The linear that extends to the west is consistent with the location and orientation of the pipeline of interest (100-F-44:2). The assumed 100-F-44:2 pipeline linear is interpreted to be between 1 and 1.5 meters (3 and 5 ft) deep.

Confirmatory sampling at the 100-F-44:2 subsite was performed on January 16, 2008. A test pit was excavated beneath the pipe, to a depth of approximately 2 meters (7 feet). The pipe was located and uncovered eastward toward the 100-F-26:4 excavation boundary. The pipe was cut open at coordinates N147618, E580542. No interior pipe sample could be taken because there was no sediment or scale inside the pipe. Confirmatory sampling has shown that the site meets the cleanup objectives for direct exposure, groundwater protection, and river protection. Accordingly, a No Action reclassification is supported for the 100-F-44:2 subsite.

The SubSite is Part Of:

Waste Type: Soil

Waste Description: The waste was pipeline sediment/scale and underlying soil.

Closure Info: Interim: A phased approach was used to evaluate the pipeline and collect samples in support of the sampling objectives. Confirmatory sampling began on February 13, 2008. An exploratory test trench, approximately 5 to 6 meters (15 to 20 ft) long, was excavated. However, the pipe was not found at that location. On February 21, 2008, another trench was dug approximately 6 meters (20 ft) due east of the first trench and of approximately the same length. This time the pipe was found and observed to be approximately 5 cm (2 in.) in diameter and 0.9 m (3 ft) below grade. The pipe length was determined to be 6 meters (20 ft).

The visual evidence indicated this pipe was a piece of electrical conduit debris and not a process pipeline or sewer pipeline. Though the pipe was identified as non-hazardous conduit debris, part of the confirmatory samples planned for the waste site was collected. On February 25, 2008 the pipe was cut and a sample of about 250 milliliters of soil was taken from inside the pipe.

The SubSite is Part Of:

Code: 100-F-44

Names: 100-F-44; 100-F Miscellaneous Pipelines (See Subsites)

Code: 100-F-44:5

Classification: Accepted

Names: 100-F-44:5; Process Sewer Pipelines

Reclassification: Interim No Action (4/22/2009)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The 100-F-44:5 subsite has been evaluated and determined to require No Action. It is a network of reinforced concrete and steel pipelines that received process flow from the 190-F Building and discharged to a 1.07 meter (42-in.) diameter pipeline associated with the 100-F-19:3 reactor cooling water effluent pipelines (CVP-2001-00003), which have been remediated. This pipeline subsite includes reinforced concrete pipe (RCP) and steel pipe consisting of the following:

- Two 0.9 m (36-in.) diameter RCP, 14 m (46-ft) long process sewers
- Two 0.15 m (6-in.) diameter steel, 14 m (46-ft) long process sewers
- One 1.2 m (48 in.) diameter RCP, 38 m (125 ft) long process sewer
- One 0.15 m (6-in.) diameter steel, 25 m (82 ft) long process sewer
- One 1.2 m (48 in.) diameter RCP, unknown length (up to 54 m [177-ft] long) process sewer.

In 1956, an annex was added to the south side of the 190-F Pump House to increase the process water flow throughout the system. It is assumed, based on the 190-F Annex construction photographs and site drawings, that in the process of excavation for the 190-F Annex below-grade pump room, approximately 54 meters (177 ft) of the original 1.2 meters (48 in.) diameter RCP running east to west was removed and replaced with the 1.2 meters (48 in.) diameter RCP that elbows to the south in a path around the 190-F Annex. However, an unknown length of the original pipeline could remain, and therefore has been included in the 100 F-44:5 subsite decision.

Location: It is located directly north of the 105-F Reactor and south of the 190-F Building Annex.

Waste Type: Soil

Waste Description: The waste is potentially contaminated soil.

Description:

Closure Info: Interim (4/22/2009): Confirmatory sampling at the site was conducted on January 17, 2008. Samples of soil underlying the below-grade concrete floor of the pump room that previously contained the 100-F-44:5 pipelines were collected. The two 0.9 meter (36-in.) diameter reinforced concrete pipe, 14 meter (46-ft) long process sewer pipelines were not in the pump room; however, it was confirmed that the location was consistent with the design drawing (H-1-26685). Evidence to that effect included two portals in the south vertical wall and two portals in the north vertical wall. The sampling logbook (WCH EL-1601) documents that the excavator operator confirmed a low spot in the floor that may have indicated a sump between the walls. A section of the floor was rubblized and removed, and the excavator collected soil from beneath the floor location as soil sample material.

One test pit (test pit #1) was excavated at the junction of the 0.15 meter (6-in.) diameter steel pipeline and the 1.2 meter (48-in.) diameter RCP pipeline. The 0.15 meter (6-in.) diameter steel pipeline intersects with the west side of the manhole at 0.91 meter (3 ft) to 2.7 meter (9 ft) bgs, per drawing H-1-26706. According to the sampling logbook, at test pit #1 a square manhole (approximately 1.2 meter (4 ft) on each side) was encountered approximately 0.3 meter (1 ft) bgs. However, the excavation extended to 5 meters (16 ft). This was 2.3 meter (7 ft) below the 0.15 meter (6-in.) diameter steel pipeline anticipated intersection, on the south and west sides of the manhole without intercepting the steel pipeline. As shown in the photographs taken during the excavation, the concrete room at the base of the manhole is visible at approximately 5 meters (16 ft), without evidence of a pipeline or visible point of entry for a pipeline within the concrete side of the manhole. To the south and west of the manhole, the roof of the 190-F cooling water tunnel was encountered at 3 meters (10 ft), and the base of the 190-F cooling water tunnel was encountered at 5 meters (16 ft).

Confirmatory sampling at the 100-F-44:5 site, test pit #2, was performed on January 17, 2008. Field volatile organic compound and radiological surveys were conducted during the sampling. No elevated detections were noted in the logbook. The historical knowledge of the 190-F Annex demolition in 1977 does not include the condition of the below-grade pump rooms following the post-demolition clean up and grading of the site. Therefore, an observational approach was used during excavation of the test pit to identify potential worst-case media for focused sampling. The excavation continued to the below-grade concrete floor surface, approximately 4.0 meter (13 ft) bgs, to expose the contents of the pump room. The two 0.9 meter (36-in.) diameter, 14 meter (46-ft) long pipelines were not in the pump room. However, it was confirmed that the location was consistent with the design drawing.

The SubSite is Part Of:

Code: 100-F-44

Names: 100-F-44; 100-F Miscellaneous Pipelines (See Subsites)

Code: 100-F-44:6

Classification: Accepted

Names: 100-F-44:6; 189-F Refrigeration Pipeline

Reclassification: Rejected (4/30/2007)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The subsite has been evaluated and reclassified as Rejected based on the absence of potential chemical or radionuclide contamination associated with service water pipelines.

The 76 centimeter (30 inch) pipe entering the foundation of the 189-F Refrigeration Building was discovered during excavation of a test pit for confirmatory sampling at the 100-F-26:4 site

on December 17, 2004. The origin of the pipeline was investigated as part of the 100-F Orphan Sites Evaluation task. Initially, the pipeline was thought to be an abandoned 107-centimeter (42-inch)-diameter raw water line for the 189-F Refrigeration Building, associated with 100-F-41 (100-F Service Water Pipelines, 100-F Clean Water Pipelines) and became 100-F-41:2. Because its former use was uncertain, the pipeline was reassigned to 100-F-44 (Miscellaneous Pipelines) and designated 100-F-44:6.

Location: This pipeline ran from the 181-F River Pumphouse to the 189-F Refrigeration Facility in the north-central part of the 100-F Area.

Process Description: The pipe has been identified as a raw water pipeline that supplied water to the condenser units in the 189-F Refrigeration Building. The pipeline also supplied backup raw water to the 182-F and 183-F facilities. The information discovered during the review substantiated the initial finding that the pipeline was the abandoned 107-centimeter (42-inch) raw water line for the 189-F Refrigeration Building. It varied in diameter from 76 centimeters (30 inches) to 107 centimeters (42 inches) and is 908 meters (2,979 feet) in total length, including laterals.

Waste Type: Not Specified

Waste Description: The waste is the old buried pipes from the raw water pipeline system.

The SubSite is Part Of:

Code: 100-F-44

Names: 100-F-44; 100-F Miscellaneous Pipelines (See Subsites)

Code: 100-F-44:7

Classification: Accepted

Names: 100-F-44:7; 1717-F Blowdown Pipeline

Reclassification: Rejected (8/27/2007)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The subsite has been evaluated and reclassified to Rejected. The reclassification was based on the absence of potential chemical or radionuclide contamination within the pipelines.

The subsite was originally thought to be one pipeline. It actually consists of two 10 centimeter (4 in.) diameter cast-iron pipelines, each 27 meters (88 ft) long. The existence of the pipelines was confirmed by geophysical methods. During decommissioning and demolition of the 1717 F Maintenance Shop structure in 1983, short sections of both pipelines had been removed.

The two pipelines had been used to connect the 1717-F auxiliary boiler system to the 1717-F Building Drywell for safety reasons. As a rule the blowdown valve on a boiler was plumbed into a dedicated pipeline or drain. These pipelines discharged into the 100-F-5, 1717-F Building Drywell. Conflicting construction drawings indicated there may be a drain line of identical size and length running in parallel to this line.

Location: The segment consisted of one or two pipelines extending 23 meters (76 feet) from N147757/E580622 to N147757/E580645. The two 10 centimeter (4 inch) diameter pipelines were identified, in historical construction drawings, on the west side of the former 1717-F Maintenance Shop.

Process Description: Both pipelines connected from an auxiliary boiler system in the 1717-F Building to the 100-F-5, 1717-F Building Drywell. Water carried in the pipelines consisted of sanitary (potable) water. The Blowdown pipe served to prevent an explosion if the boiler pressure got too high, hot liquids and vapors would not be able to backflow, and possibly damage other locations or personnel in or around the boiler system. Having a dedicated pipeline also ensured that the

carrying capacity of that pipeline would not become restricted over time due to incidental use. Therefore, each of the boilers in the heating system required a separate dedicated blowdown pipeline.

Steam condensate, from the heating systems serviced by the 1717-F auxiliary boiler system, was not returned to the boiler system for reuse. Therefore, water would not have contained chemical or radiological contaminants from the laboratories or other facilities serviced by the 1717-F auxiliary boiler (heating) system. Only unregulated concentrations of water treatment chemicals, used to produce potable water, would be present in the boiler system and, therefore, in the water carried by the pipelines.

The SubSite is Part Of:

Code: 100-F-44

Names: 100-F-44; 100-F Miscellaneous Pipelines (See Subsites)

Code: 100-F-44:8

Classification: Accepted

Names: 100-F-44:8; 1717-F Fuel Oil Supply and Return Pipelines

Reclassification: Interim Closed Out (12/15/2011)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This subsite has been remediated Interim Closed Out. It was also known as Segment DS-100-F-009 that consisted of two 3.8 centimeter (1.5 inch) diameter black steel pipelines. They extended 36 meters (118 feet) from N147753/E580610 to N147753/E580637 to N147756/E580645. They were fuel oil supply and return pipelines that serviced the three underground fuel oil tanks (WIDS site 100-F-32) and the 1717-F building. Evidence was found that the tanks were offered for sale and photographs showed a disturbance where the tanks were previously located. It is possible these pipelines were removed as part of the tank removal.

Location: These pipelines were located about 240 meters (787 feet) northeast of the 105-F Reactor.

Process Description: The pipelines allowed fuel oil to be supplied to the 1717-F maintenance shop and office buildings.

Waste Type: Not Specified

Waste Description: The waste includes the pipelines and any contaminated soil associated with these pipelines.

Closure Info: Interim (12/15/2011): In 2008, the pipelines were located. Confirmatory sampling determined that liquid with a strong diesel odor was still present in the lines. Remedial action at the 100-F-44:8 pipelines began on October 27, 2010, and continued through January 4, 2011, to a depth of approximately 0.7 meters (2.3 ft) across the entire excavation footprint. Due to the shallow nature of the excavation, no overburden was associated with this site. The excavation resulted in approximately 80 bank cubic meters (BCM) (104.6 bank cubic yards [BCY]) of contaminated soil and debris being removed for disposal at the Environmental Restoration Disposal Facility (ERDF). Approximately 72 meters (238 ft) of 3.81 centimeters (1.5 inch) diameter steel pipe, along with contaminated soil, piping, conduit, wires, concrete, and used personal protective equipment was excavated from this waste site and disposed at the ERDF. Following the verification sample analysis, it was determined that additional remediation was needed due to sample locations that exceeded cleanup criteria. A second remediation was conducted on June 9, 2011, with the removal of 126.4 BCM (165.3 BCY) of contaminated soil. With agreement from the U.S. Environmental Protection Agency (EPA), additional soil was removed from areas that exceeded direct exposure and/or groundwater and river protection

RAGs in the excavation and staging pile area footprint.

The SubSite is Part Of:

Code: 100-F-44

Names: 100-F-44; 100-F Miscellaneous Pipelines (See Subsites)

Code: 100-F-44:9

Classification: Accepted

Names: 100-F-44:9; 105-F Process Sewer Pipeline

Reclassification Interim Closed Out (9/14/2011)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The pipeline has been removed and Interim Closed Out. The pipe segment was a 46 centimeter (18 inch) steel process sewer pipeline approximately 42 meters (140 feet) in length.

Location: The 100-F-44:9 waste site was located in the 100-FR-1 Operable Unit of the Hanford Site. It was east of the former 105-F Reactor Building, within the 105-F Exclusion Area fence line. The pipeline was 42.5 meters (140 feet) long, extending from N147620/E580460 to N147620/E580473 to N147618/E580475, and ending at N147591/E580475.

Related Sites/ Structures: 100-F-44:9 was associated with the 100-F-19:2 cooling water pipeline.

Process Description: The pipeline conveyed effluent from the east side of the 105-F Reactor Building and appeared to discharge to a 1.07-m (42-in.)-diameter pipeline associated with the 100-F-19:2 Reactor cooling water effluent pipelines that have since been remediated.

Waste Type: Not Specified

Waste Description: Possible chemical and/or radionuclide contaminated pipelines and underlying soils.

Closure Info: Interim (9/14/2011): A geophysical survey of the site was conducted in January 2007. The geophysical survey findings agreed with historical documentation for the pipeline that shows a north-south trending, 18-in.-diameter steel pipeline paralleling the 105-F Reactor footprint along the east side. The pipeline turns to the west near the northern side of the reactor. Remedial action at the 100-F-44:9 pipeline subsite began on November 3, 2010, and continued through January 5, 2011, to a depth of approximately 3 meters (10 ft). One staging area was developed during the excavation for storing soil prior to disposal at the ERDF. Contaminated soil, pipe, asphalt, clay pipe, concrete, and rebar were removed from the 100-F-44:9 excavation for shipment and disposal to the ERDF. The post-excavation surveys, conducted on January 10, 2011, identified no residual radioactivity above twice background within the site.

An anomaly was discovered within the excavation of the 100-F-44:9 subsite that appeared to be a large metal valve. A sample of the anomaly not collected after the object was found to be empty. Industrial Hygiene and radiological readings did not detect contamination present within the anomaly.

The SubSite is Part Of:

Code: 100-F-44

Names: 100-F-44; 100-F Miscellaneous Pipelines (See Subsites)

Code: 100-F-44:10

Classification: Accepted

Names: 100-F-44:10; 141-C Sewer Pipelines; 100-F

Reclassification Rejected (10/11/2007)

 Experimental Animal Farm Sewer Pipelines
Type: Process Sewer**Start Date:****Status:** Inactive**End Date:**

Description: The subsite has been evaluated and reclassified to Rejected. The subsite is described as two 20.3-centimeters (8-inch)-diameter sewer pipeline segments exiting the 141-C building. It has been determined through the excavation results that there is no evidence to support the existence of the site. The pipelines were likely removed during earlier demolition activities. The subsite does not pose a risk to human health or the environment and will support future unrestricted land uses that can be represented (or bounded) by a rural-residential scenario, and no institutional controls are required.

Historical review determined that during Decontamination and Decommissioning activities of the 141-C Building (between August and December 1979), the building, concrete pad, foundation and contaminated soils were removed. The only remaining structure was a temporary steel post that marked the location of a 6-inch gate valve. The valve and 36.5 meters (120 feet) of potentially contaminated 20 centimeter (8-inch) steel pipe that extended from the valve to the decommissioned waste lift station (141-N) was capped and abandoned in place.

Documentation in the Cleanup Verification Package-2001-0003 for sites 100-F-19:2, 116-F-11, 100-F-29, and UPR-100-F-1 stated that pipelines were excavated on March 22, 2002 that extended from just east of the former 141-C Building to the former 141-N waste lift station. A geophysical survey was performed in April 2004 to locate and map any buried remains from the demolished 141-C Building. The geophysical survey narrative stated that the entire site appeared to have been disturbed from operational or deactivation activities. There were no obvious anomalous features detected that had the characteristics of remnants of the infrastructure from the original site (e.g., foundation footings, buried debris, pipelines, utilities).

In August 2005 during the 141-C Building remediation, exploratory trenches were dug to confirm that the sewer lines formerly servicing the 141-C Building had been removed during previous deactivation activities. No sewer lines were located by these excavations and field instrumentation did not detect any beta-gamma or alpha activity above background levels. There was no evidence to support the existence of the pipe segments in the vicinity of the 141-C Building.

Location: The waste site was located within the 100-F Experimental Animal Farm area. The subsite consisted of two 20.3-centimeters (8-inch)-diameter sewer pipeline segments exiting the 141-C building. It has been determined through the excavation results that there is no evidence to support the existence of the pipelines.

The SubSite is Part Of:**Code:** 100-F-44**Names:** 100-F-44; 100-F Miscellaneous Pipelines (See Subsites)**Code:** 100-F-45**Classification:** Accepted**Names:** 100-F-45; Buried River Effluent Pipelines**Reclassification:** Interim Closed Out (12/15/2011)**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:**

Description: The waste site was remediated and Interim Closed Out. It consisted of a piece of pipeline that was buried in the river bank after it floated loose from the river effluent pipeline.

Location: The site is located on a steep river bank approximately 10 meters (33 feet) from the Columbia

River, approximately 670 meters (2,200 feet) northeast of the 105-F Reactor Building and about 15 meters (50 feet) upstream from the 116-F-16 PNL Outfall.

Related Sites/ Structures: These suspected pipeline sections are believed to have resulted from the failure of the 100-F-39, 100-F River Effluent Pipelines which are also co-located with 116-F-8 Outfall Structure, and the 100-F-42, 1904-F Spillway/Flume.

Process Description: The 100-F Area process sewers discharged via the 1904-F (116-F-8) Outfall to the Columbia River through two 106 centimeter (42 inch) steel lines (BHI-01141). Soon after the 105-F Reactor started up in 1945, these pipelines began to experience a problem common to all of the early reactors, floating river effluent lines. More than 100 feet of each of these lines were bent and broken. Historical documentation suggested that these broken sections were removed from the river and buried somewhere along the shoreline, although the exact location was not recorded. In 1946, the original pipelines were replaced with much shorter ones, causing confusion over time.

Waste Type: Equipment

Waste Description: Contaminants of concern/potential concern are based on those for the 1904-F outfall (116-F-8). Contaminants of concern include Co-60, Eu-152, Eu-154, Eu-155, and Cr+6. Contaminants of potential concern include C-14, Cs-137, Ni-63, and Sr-90.

Closure Info: Interim (12/15/2011): Remedial action at the 100-F-45 waste site began on March 14, 2011, and continued through March 21, 2011, to a depth of approximately 0.5 to 2.0 meters (1.7 to 6.6 ft). The excavation resulted in approximately 160.0 bank cubic meters (BCM) (208.0 bank cubic yards [BCY]) of contaminated soil and debris being removed, including 15.3 meters (50.0 ft) of the 42 inch diameter steel pipe, for disposal at the Environmental Restoration and Disposal Facility (ERDF). Approximately 217.0 BCM (283.8 BCY) of overburden material was stockpiled southwest of the excavation for use as clean backfill. A small staging pile area was used for contaminated soil and pipe material, which was later loaded out and disposed at the ERDF. No anomalous materials or stained soil were encountered during the excavation.

Upon completion of remedial activities, high river flow caused water seepage into the excavated area. This seepage caused some of the surrounding bank to fall into the finished excavation area. Prior to verification sampling, this soil material was removed at the specified sampling locations.

No elevated radiological readings were detected during the excavation of the 100-F-45 waste site; therefore, no Global Positioning Environmental Radiological Surveyor (GPERS) surveys were conducted.

Code: 100-F-46	Classification: Accepted
Names: 100-F-46; 119-F Stack Sampling French Drain	Reclassification: Interim No Action (8/8/2008)
Type: French Drain	Start Date:
Status: Inactive	End Date:

Description: The site has been evaluated and determined to require No Action. It consisted of the 119-F french drain, a gravel-filled vertical pipe, and the pipeline from the 119-F Stack Sampling Building to the french drain.

Location: The french drain was located about 7.5 meters (25 feet) northwest of the west wall of the 119-F Stack Sampling Building. The influent end of the pipeline was at E580382.2 N147614.2. The pipeline depth was above the top of the 117-F air tunnels such that it was likely removed during the decontamination and decommissioning (D&D) activities for the 117 F Building and air tunnels.

Related Sites/ Structures:	The site was associated with the 118-F-8 Reactor Building 116-F Stack, 119-F Stack Sampling Building, 117-F Filter Building and Air Tunnels.
Process Description:	The 116-F reactor stack exhaust gases were sampled by pulling moist stack offgases through a steam-heated pipe to the 119-F Stack Sampling Building where the gas stream was sampled. The condensate from the stack offgases drained via a 2 inch cast iron pipeline to the 119-F french drain. A 5 centimeter (2 inch) cast iron pipe drained condensate from the 119-F Stack Sampling Building into the french drain. The drain pipeline is included as part of this waste site.
Waste Type:	Equipment
Waste Description:	The site may contain contaminated soil from condensate entering the french drain. The waste includes the french drain and the pipelines. It is likely that these structures no longer exist. However, remediation of these structures is not documented in a cleanup verification package. The condensate from the 116-F stack potentially contained the same contaminants of concern identified for the 116-F stack during the characterization sampling performed for the allowable residual contamination level (ARCL) evaluation completed in 1985. Low levels of tritium-3, carbon-14, strontium-90, cobalt-60, cesium-13, europium-152, and plutonium-239 were reported for the 116-F stack. Potential Contaminants of Concern: Low levels of tritium-3, carbon-14, strontium-90, cobalt-60, cesium-13, europium-152, and plutonium-239 were reported for the 116-F stack.
Closure Info:	Interim (8/8/2008): Both the 100-F-46 French drain and the condensate pipeline were presumed to have been removed during decommissioning and demolition of the 117-F Filter Building (132-F-5) and associated air tunnels in 1983. These structures had been decontaminated, removed to a depth of 1 meter (3 feet) below grade, and backfilled to grade. The confirmatory sampling results supported a reclassification of the site to No Action.

Code:	100-F-47	Classification:	Accepted
Names:	100-F-47; 151-F Substation	Reclassification	Interim Closed Out (12/15/2011)
Type:	Electrical Substation	Start Date:	1/1/1945
Status:	Inactive	End Date:	1/1/1965
Description:	The waste site has been remediated and Interim Closed Out. The substation consisted of a fenced, gravel-bed yard measuring 92.4 meters (303 feet) by 137.2 meters (450 feet), with the 151-F Switch House along the eastern fence line. A railroad spur entered the yard from the south and paralleled the east fence line.		
	The 151-F Substation distributed power to transformers located at the 181-F River Pump House, 182-F Head House, 183-F Filter House, 184-F Power House, 190-F Pump House, and the 105-F Reactor, each of which, in turn, distributed power to associated facilities.		
Location:	The 151-F Building and associated switch yard were located approximately 350 meters (1148 feet) northwest of the 105-F Reactor Building. The 151-F Building was centered along the east fence line of the switch yard.		
Related Sites/ Structures:	The 151-F Building and associated switch yard were located approximately 350 meters (1148 feet) northwest of the 105-F Reactor Building. The 151-F Building was centered along the east fence line of the switch yard.		
Process Description:	The 151-F Substation was fully energized in January 1945 and supplied 13.8 KV electrical power to the 100-F Area.		
	More than 100 concrete footings and pads of various sizes protruded from the crushed gravel bed throughout the yard, supporting a variety of electrical equipment, including two 31,250		

KVA, 220/13.8 KV transformers, one 37.5 KVA transformer, three oil circuit breakers, and several power line towers and stands. Underground concrete-encased "Korduct" ducts connected the switch house with the transformers and oil circuit breakers.

The single-story concrete block switch house was 24.4 meters (80 feet) long by 9.1 meters (30 feet) wide and 3.4 meters (11 feet) high. A 3.4 meter (11 foot) wide by 3.4 meters (11 feet) high by 21.9 meters (72 feet) long reinforced concrete cable pit ran beneath the block house.

Waste Type: Soil

Waste Description: There have been no reported unplanned discharges of oil containing PCBs. Since leak/spill reporting is inconsistent for the entire period of operation of the substation, it is prudent to assume unplanned discharges of oil may have occurred at locations where transformers or oil circuit breakers were positioned, or where the railroad tanker was located. Confirmatory sampling around these locations should be considered. There may be more than 2,744 meters (9,000 feet) of underground electrical cable, generally housed in fiber or transite conduit, and encased in at least 7.6 centimeters (3 inches) of concrete. It is suspected that much of this copper cabling is encased in an asbestos wrap and an outer lead sheath. Also, depending on the extent of unplanned releases, these lines may be contaminated by PCB-containing oil. This same cabling may also still remain in the cable pit of the 151-F Building. Potential Contaminants of Concern: PCBs, lead, and asbestos.

Closure Info: Interim (12/15/2011): Remediation of the 100-F-47 waste site was performed from October 20, 2010, through June 27, 2011, to a depth between 1 and 4.35 meters (3 and 14.3 ft) across the entire excavation footprint. Due to the shallow nature of the contamination, no overburden was associated with this site. Approximately 14,500 cubic meters (19,000 cu. yd.) of contaminated soil, concrete, rebar, wire, steel cable, asphalt, asbestos, wood, steel, porcelain, and glass were removed from the 100-F-47 excavation and were directly loaded for shipment and disposal at the Environmental Restoration Disposal Facility. No anomalous materials were encountered during the excavation. Two small transformers were found during the excavation, and will be characterized for disposal at a later date.

Code: 100-F-48

Classification: Accepted

Names: 100-F-48; 184-F Coal Pit Debris

Reclassification: Interim Closed Out (12/15/2011)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The waste site has been remediated and Interim Closed Out. It consisted of an area of debris that was identified in an aerial photograph and a historical literature search. The debris has been removed and disposed into the Environmental Restoration Disposal Facility.

Location: The coal pit debris is located immediately north of the 184-F Power House site (removed), about 500 meters (1,650 feet) northeast of the 105-F Reactor Building.

Related Sites/ Structures: The associated structures included the 184-F Power House and 184-F Coal Handling Facilities.

Process Description: Inert demolition debris was commonly disposed on site in the large operations support storage facilities such as the coal storage bins and the water treatment and storage basins. The criteria for what was allowed to be disposed on site are not documented but generally are thought to include nonradioactive solid debris such as building materials (e.g., siding, roofing, structural, concrete/concrete block, fencing) removed during demolition of administrative and ancillary support facilities between 1967 and 1990. Some unacceptable solid waste forms such as asbestos-containing siding or roofing were allowed to be disposed.

Closure Info: Interim (12/15/2011): The 100-F-48 waste site anomalies included two deteriorated, leaking drums and a single intact, non-leaking drum. The single intact, non-leaking drum was found to be empty. The two deteriorated, leaking drums were sampled. One drum was found to contain high concentrations of TPH and lead.

Confirmatory sampling failed to meet remedial action objectives. Analytical results from the confirmatory samples indicated that the material in the drum, found in the geophysical anomaly area, exceeded shallow-zone direct exposure Remedial Action Goals (RAGs) for thorium-230, uranium-233/234, uranium-238, and arsenic. The material also exceeded groundwater and river protection RAGs for copper, lead, mercury, and zinc. Based on the confirmatory sampling results, the 100-F-48 waste site was recommended for remediation.

Remediation of the 100-F-48 waste site was performed from September 21, 2010, to January 11, 2011. The coal scrape area was remediated to a depth of approximately 0.3 meters (1 ft), while the main excavation area had a final depth that ranged from approximately 0.2 meters (0.7 ft) to 3.5 meters (11.4 ft). The 100-F-48 waste site excavation resulted in approximately 13,922 BCM (18,209 BCY) of material being removed for disposal at the Environmental Restoration Disposal Facility (ERDF).

Soil and debris from the main excavation area were direct-loaded to ERDF, while material removed from the coal scrape area was staged at the east stockpile area before eventual removal to ERDF. Types of debris uncovered include: concrete, steel pipe, rebar, porcelain, clay pipe, bricks, wire, cable, suspect ACM, and asphalt. No overburden soil stockpiles were associated with the waste site.

Code: 100-F-49	Classification: Accepted
Names: 100-F-49; 1716-F Maintenance Garage Lubrication Pit	Reclassification: Interim Closed Out (12/15/2011)
Type: Foundation	Start Date:
Status: Inactive	End Date:
Description:	The waste site has been remediated and Interim Closed Out. The waste site consisted of components of the 1716-F Maintenance Garage, including the foundation, the lubrication pit, and the contaminated drain(s). The foundation of the former garage building was T-shaped with overall dimensions of approximately 15 by 17 meters (50 by 55 ft).
Location:	The building was located in the northwest corner of the Service Building group approximately 1,101 meters (3,612 feet) north of the 100-FR-2 east-west perimeter road. The building was on the west side of F Avenue, about 13 meters (43 feet) from the road.
Process Description:	The 1716-F facility provided automotive repair, light vehicle maintenance, and lubrication service for the 100 F Area vehicles.
Waste Type:	Soil
Waste Description:	There may have been oil spills in the lubrication pit and battery acid spills in the high bay area. The Geophysical team identified this area as a potential new waste site due to the probable oil spills (polychlorinated biphenyls [PCBs], total petroleum hydrocarbons [TPH]) in the lube pit, potential battery acid in the high bay area, potential unknown pipelines, and the potential asbestos siding debris.
Closure Info:	Interim (12/15/2011): Confirmatory Sampling failed. The results of confirmatory sampling indicated that test trench 1 met all remedial action goals. The results from the remainder of the site indicated contamination with lead and polychlorinated biphenyls (PCBs) above direct

exposure RAGs. In addition, the remainder of the site also exceeded groundwater and river protection RAGs for numerous metals, semivolatile organic analytes, pesticides, and total petroleum hydrocarbons (TPH). In all, 29 different contaminants exceeded groundwater and/or river protection RAGs. Asbestos was also confirmed at the site. Based on these results, the entire 100-F-49 waste site, except for suspect utility lines associated with test trench 1, was recommended for remediation.

The 100-F-49 waste site was remediated between January 11 and April 12, 2011. During the 100-F-49 remedial activities, a steel tank was discovered at Washington State Plane (WSP) coordinates N147891, E 580666. The tank was not expected to be present at this location, and therefore, the excavator had slightly broken into the tank, causing some of the liquid from the tank to spill into the surrounding soils. The spilled liquid from the tank and soil was sampled (J1F1N1) and determined that the tank was used for oil storage purposes. The tank and its location were carefully observed and determined to be the same oil tank that 2008 confirmatory sampling expected to find. The liquid and sludge contents were pumped from the tank prior to its disposal. The steel tank structure, oil saturated soils, and additional underlying soil were removed from the 100-F-49 excavation and disposed at the Environmental Restoration Disposal Facility (ERDF).

Remediation included removal of the 1-in.-diameter steel pipe, 20 cubic meters (21.3 cu. yd.) of concrete, a 1,325-L (350-gal) steel storage tank and approximately 1,325 L (350 gal) of fuel, oil and sludge from the tank. Miscellaneous debris such as concrete and rebar were removed from the excavation and stockpiled adjacent to the site for disposal at the ERDF. The deepest part of the 100-F-49 excavation extended to approximately 2.7 m (8.9 ft). Approximately 2,727 bank cubic meters (3,567 bank cubic yards) of soil and debris was excavated from the 100-F-49 waste site. Roughly half of the materials were stockpiled adjacent to the excavation prior to disposal at the ERDF. The other half of the excavated materials was directly loaded for disposal at the ERDF.

Following the load out of stockpile materials, the staging pile area was scraped to 0.3 meter (1 ft) below ground surface. A very small green/yellow stain was observed at 0.3-meter (1-ft) depth at WSP coordinates N 147943.3, E 580631.1. It was determined that the stain was not caused by the stockpile. The stain was present at this location prior to any 100-F-49 stockpiling activities. The stained soil was sampled (J1FHT7). The sample data of the stained soil indicates that all individual contaminant of potential concern concentrations are below RAGs.

Code:	100-F-51	Classification:	Accepted
Names:	100-F-51; 146-F Fish Laboratory Soil	Reclassification	Interim Closed Out (9/26/2011)
Type:	Unplanned Release	Start Date:	
Status:	Inactive	End Date:	
Description:	The waste site has been remediated and Interim Closed Out. It was the soil under and around the former 146-F Fish Laboratory.		
Location:	The 146-F Fish Laboratory was located approximately 489 meters (1600 feet) northeast of the 105-F Reactor Building, and about 91 meters (300 feet) southwest of the 1904-F Outfall.		
Related Sites/ Structures:	Associated structures included: 116-F-8 (1904-F Outfall), 100-F-57 (190-F Process Water Pump House Debris), 100-F-52 (146-FR Radioecology/Aquatic Biology Laboratory Soil), 116-F14 (107-F Retention Basin).		
Process Description:	The laboratory sat on a curbed, concrete pad, the laboratory was 5 meters (16 feet) wide by 24 meters (80 feet) long. The floor sloped toward a central trough that was 15.8 meters (52 feet) long by 0.4 meters (1.5 feet) wide by 0.2 meters (0.5 feet) deep, which in turn drained out the		

north end of the building and directly east into the 147-F Pump House pit. The laboratory contained ten pairs of elevated, open-top, wooden fish troughs, each 3.7 meters (12 feet) long by 0.3 meters (1 feet) wide by 0.2 meters (0.75 feet) deep, as well as three head tanks and associated piping to the troughs.

River water was pumped to the Fish Laboratory through a 15 centimeter (6 inch) line from the 181-F River Pump House; process water was pumped to the building through a 5 centimeter (2 inch) line from the 190-F Main Process Pump House and Annex; and process effluent was pumped to the facility (where it was cooled before use), via the 148-F Pump House from the 107 F Retention Basin. Spills and overflows from the troughs and head tanks drained to the 147-F Pump House pit, which pumped to the 1904-F Outfall and discharged to the Columbia River.

There were removable wooden walkways between the troughs. In addition, the building contained a process water refrigeration system, fish food bins, refrigerator and freezer, electric heater and swamp cooler, an office, and a bathroom. Immediately to the east of the building were the outdoor rearing ponds and the 149-F Biology Warehouse, and immediately to the south was the 146-FR Radioecology and Aquatic Biology Laboratory that was built in 1952.

Waste Type: Soil

Waste Description: No reports were found of unplanned discharges to the soil from this building. However, because of the open-trough operations within the building it is prudent to assume such discharges may have occurred. A partial geophysical survey of the area recorded mixed subsurface debris that could be a portion of the original foundation. Contaminants of concern/potential concern are based on those for the 1904-F Outfall (116-F-8). Contaminants of concern include cobalt 60, europium 152, europium 154, europium 155, and hexavalent chromium. Contaminants of potential concern include carbon 14, cesium 137, nickel 63, and strontium 90.

Closure Info: Interim (9/26/2011): In November 2007 and February 2008, confirmatory sampling of the 100-F-51 waste site was carried out during the excavation of two test pits, at the north end and southeast corner of the laboratory. Confirmatory sampling results failed to meet remedial action goals (RAGs) and indicated the need for remedial action at the 100-F-51 waste site. Confirmatory sampling was not performed for the 100-F-63 waste site. 100-F-63 was added to the 100-F Area remove, treat, and dispose scope in 2010.

Remedial action at the 100-F-51 and 100-F-63 waste sites began on December 20, 2010, and continued through January 20, 2011. Excavation depth ranged from 0.5 to 1.5 meters (1.6 to 4.9 ft) below ground surface and resulted in approximately 253 bank cubic meters (BCM) (331 bank cubic yards [BCY]) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility. Approximately 330 BCM (432 BCY) of overburden soil was stockpiled to be used as backfill. The 100-F-51 and 100-F-63 waste sites debris included concrete, clay pipe, steel pipe, and asphalt. The verification sampling results support a reclassification of the 100-F-51 and 100-F-63 waste sites to interim closed out.

Code: 100-F-53

Classification: Accepted

Names: 100-F-53; 108-F Septic System

Reclassification: Interim No Action (6/26/2009)

Type: Septic Tank

Start Date:

Status: Inactive

End Date:

Description: The waste site was evaluated and determined to require No Action. The 100-F-53 waste site was created when research of historical information identified an early pre-construction drawing (HEW 1 944b) that depicts what appeared to be an undocumented septic system and drain field. The waste site included the septic drain field, a potential septic tank, and septic

pipelines. The septic system was suspected to be associated with the 108-f Biology Laboratory, due to its proximity to the laboratory facility. The site represented what was thought to be a septic system.

Location: The site was located approximately 190 meters (625 feet) east of the 105-F Reactor Building.

Release Releases unknown.

Description:

Related Sites/ Structures: Any liquid waste discharges to this suspect site would have originated from the 100-F-36 (108-F Chemical Pump House, 108-F Biological Laboratory) site.

Process Description: Gravity drain sewer system, either sanitary or chemical, discharged to the soil column via a drain field.

Waste Type: Soil

Waste Description: The waste potentially consists of the pipelines, the septic tank, the drain field and any contaminated soil around them. Geophysical measurements were inconclusive. No clear evidence was found of a septic tank, a septic line, or a drain field. Since the septic system (if it existed) would have been associated with 108-F Building and the activities within the building (before 1949 and the addition of the biology facilities to 108-F), the contaminants of potential concern may have been hexavalent chromium or mercury.

Closure Info: Interim: Phase I and Phase II confirmatory sampling, the 100-F-53 septic system was determined not to have been associated with the 108-F Biological Laboratory, but instead serviced a temporary construction building. Confirmatory sampling activities determined that the septic tank had previously been removed and sampling results indicate that the residual concentrations of COPCs at this site meet the remedial action objectives for direct exposure, groundwater protection, and river protection.

An aerial photograph P-1888 taken during construction of the 100-F Area showed that the Crafts Office was one of the first buildings constructed in the 100-F Area. This building did not appear on photographs taken during operation of the 100-F Area, indicating it was removed early in the operations time period. Based on the historic aerial photographs, the 100-F Area Plot Plan drawing (Drawing C-3231), and the building description in DuPont (1945), it was concluded that the TC-32 Crafts Office was the Layout building and that this is the building seen in the historic photographs. It follows that the drain field shown on the drawing (and found in the 100-F-53 test trench) serviced this temporary construction building. Thus, the septic tank associated with the 100-F-53 septic system was a wood framed box buried 0.3 m (1 ft) below grade and located somewhere between the drain field and the "Layout" building.

A geophysical survey was performed at the site in August 2005 (Bergstrom and Mitchell 2005) to locate evidence of a septic tank, underground pipelines, and a drain field based on the historical drawing (HEW 1944). Ground-penetrating radar and an electromagnetic induction (EM-61) metal detector were the geophysical methods used for the investigation. The results found no features that would have been characteristic of a typical septic tank. Several linears were detected that could be characteristic of underground pipelines and/or utilities, but the results were inconclusive. Also, scattered anomalies throughout the surveyed area were likely buried remnants from decommissioning of the 108-F Building. It should be noted the geophysical methods used have only a limited capability to detect wood septic tanks and vitrified clay pipes (characteristic of drain fields and sanitary sewer piping).

Based on historical and photographic evidence, including field observations during Phase I and Phase II confirmatory sampling, the 100-F-53 septic system was determined not to have been associated with the 108-F Biological Laboratory, but instead serviced a temporary construction building. Confirmatory sampling activities determined that the septic tank had previously been removed and sampling results indicated that the residual concentrations of COPCs at this site

meet the remedial action objectives for direct exposure, groundwater protection, and river protection. In accordance with this evaluation, the confirmatory sampling results supported a reclassification of the site to No Action.

Code: 100-F-54	Classification: Accepted
Names: 100-F-54; 100-F Animal Farm Pastures	Reclassification: Interim No Action (4/17/2008)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The waste site was evaluated and determined to require No Action. The site consisted of the soil associated with the former pastures for holding contaminated domestic farm animals used in experimental toxicology studies. The site was three pasture areas. Area 1 was a large pasture near the 141-G building. Area 2 was two small pastures (aka 2a located west of 141-G and 2b located north of 141-T). Area 3 was two large pastures, located south of 141-C and 145-G.

Location: A major portion of the animal farm activities were conducted in the segregated complex northeast of the reactor building and near the outfalls. The animal studies were located northeast of the 105-F reactor. There were three general pasture areas associated with the complex. The first was a large, contiguous pasture extending from the 141-G Building north to the perimeter road. The second consisted of two smaller pastures; one adjacent and to the west of the 141-H Building; and the other adjacent and to the north of the 141 T Building. The third consisted of two larger pastures (one for hogs, one for goats) directly south of the 141-C and 145-F Buildings.

Related Sites/ Structures: Dosed animals were housed in the 141-H and 141-F Buildings, which were adjacent to these pastures.

Process Description: There were three general pasture areas associated with the complex. The first was a large, contiguous pasture extending from the 141-G Building north to the perimeter road. The second consisted of two smaller pastures; one adjacent and to the west of the 141-H Building; and the other adjacent and to the north of the 141 T Building. The third consisted of two larger pastures (one for hogs, one for goats) directly south of the 141-C and 145-F Buildings.

The larger pasture was approximately 580 meters squared (6250 square feet) and was centered at the 141-N Building footprint, was approximately 1,500 meters squared (16,100 square feet) and was centered at N147942 E580895 (H-1-13850). The smaller pasture, directly to the east of the N147957 E580927.

Radioactively dosed animals were confined to the buildings until their feces and urine met certain limits, then they were allowed into the pastures. There was concern that the pastures may contain low-level contamination.

Waste Type: Soil

Waste Description: Animals were pastured in these areas, their waste would have discharged to the ground and may have contaminated the soil. Historical documents indicated strontium-90, iodide-131, isotopes of plutonium, cesium-137, and other radioisotopes were used in the animal exposure studies.

Closure Info: Interim: Three general pasture areas were associated with the experimental animal farm complex. Later a few areas were used for stockpiling soil associated with the 100-F Area Remedial Action excavations. These areas were subsequently surveyed and/or sampled to demonstrate no residual radiological activity. Field observations indicated that only two pasture areas remained relatively undisturbed that could potentially be representative of the original pastures, and were available for sampling. One sample area was within a pasture south of the former 141-C and 145-F Buildings. The second sample area was within a pasture north of the

former 141-T Building. Nine soil samples were collected from these areas.

Code: 100-F-55 **Classification:** Accepted
Names: 100-F-55; 1607-F7 Contaminated Ash Layer **Reclassification** Interim Closed Out (12/22/2011)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The waste site has been remediated and Interim Closed Out. The ash layer was discovered during 1607-F7 sampling activities. The site consisted of a black layer of ash approximately 0.3 meters (1 foot) below the ground surface north of the 1607-F7 septic system, near the former 141-M building. The ash was found to be above cleanup limits for hexavalent chrome.

Location: The ash layer was observed in a trench near the 1607-F7 Septic System, approximately 0.3 meters (1 foot) below grade.

Related Sites/ Structures: The ash layer is unrelated to the 1607-F7 Septic System.

Waste Type: Soil

Waste Description: The waste is a contaminated ash layer. The only known contaminant of potential concern is hexavalent chromium.

Closure Info: Interim (12/22/2011): Remedial action at the 100-F-55 waste site was performed from September 16 to October 7, 2010 to a depth of 0.7 meters (2.3 ft). Remedial action at the 100-F-62 waste site was performed from December 2010 to March 2011. The 100-F-62 north pipeline excavation included the removal of the pipelines to the former 1607-F7 septic tank and contained the 100-F-55 waste site excavation. From the north excavation, approximately 2 meters (7 ft) of the 4 inch diameter vitrified clay pipe were removed, and approximately 5 meters (16 ft) of 4 inch diameter steel pipe with lead bells were removed. Verification sample results indicated additional remediation was required. Additional remediation was performed from July 29 to August 9, 2011. The center section of the north excavation was further remediated, and the entire south excavation was further remediated and expanded to the south. The final north excavation depth is 2.3 meters (7.6 ft), and the final south excavation depth is 4.4 meters (14.5 ft). Additional remediation also occurred at the east staging pile area and the northeast quadrant of the south staging pile area.

Code: 100-F-56 **Classification:** Accepted
Names: 100-F-56; 100-F Surface Debris/Stains **Reclassification** Interim Closed Out (12/15/2011)
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The waste site was miscellaneous discarded/abandoned materials across the 100-F Area. The waste site was divided into two subsites, 100-F-56:1, 100-F Garnet Sand Areas and 100-F-56:2, Other 100-F Surface Debris Areas. Both subsites have been remediated, so the parent site is also Interim Closed Out.

Location: The subsite areas were located throughout the 100-F Area.

Related Sites/ Structures: Temporary and permanent 100-F Area facilities removed by remedial action or decontamination/decommissioning activities are listed in the Buildings section of the OSE report for 100-F.

Process Description: Various sizes and forms of hazardous (CERCLA) and/or dangerous (MTCA) surface debris were left during the construction, operation, decontamination and decommissioning (D), and remedial action (RA) activities at the 100-F Area.

Waste Type: Misc. Trash and Debris

Waste Description: The solid waste types addressed here are typically transite, lead battery residues, and treated wood including isolated railroad ties, treated power pole, and wood posts. Railroad ties in railroad beds are not addressed here. The contaminants of potential concern relate to waste characterization for disposal of the debris. There are no significant environmental contaminants of concern for this site since the debris is expected to leave no residue during removal.

This Site has the Following SubSites:

Code: 100-F-56:1

Names: 100-F-56:1; 100-F Garnet Sand Areas

Code: 100-F-56:2

Names: 100-F-56:2; Other 100-F Surface Debris Areas

Code: 100-F-56:1

Classification: Accepted

Names: 100-F-56:1; 100-F Garnet Sand Areas

Reclassification: Interim Closed Out (12/15/2011)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: This subsite has been remediated and Interim Closed Out. The subsite consisted of two garnet sand areas. The first area was described as red garnet sand (sand blasting) with some scattered miscellaneous debris (wood, metal, glass, vitrified clay chunks). The second area was described as stained soil - garnet sandblasting. Soil and debris was removed and disposed into the Environmental Restoration Disposal Facility.

Location: One area was located 200 meters (656 ft) north of the 105-F Reactor Building and the other located was 300 meters (984 ft) south of the 105-F reactor.

Process Description: The exact process that caused the garnet sand to be located at these locations is unknown. However, garnet sand was used in sandblasting operations to clean rust, paint, and contamination from the surface of metal components. The garnet material is not a hazardous substance. However, there is contamination potential due to the paint and other materials removed by sandblasting.

Waste Type: Not Specified

Waste Description: The waste consists of potentially contaminated soil, wood, metal, glass, vitrified clay and garnet sand.

Closure Info: Interim (12/15/2011): Remediation of the 100-F-56:1 waste subsite occurred from March 1 to April 4, 2011. Soil was excavated to a depth of 0.2 meters (9 inches) below ground surface resulting in 440 cubic meters (575 bank cubic yards) of soil and debris being disposed at the ERDF. Following remediation, verification sampling was conducted in July and August 2011. Results showed that a single sample taken from the northern excavation contained contaminant concentrations in excess of the cleanup criteria for hexavalent chromium. Further remediation was performed to excavate an additional meter in depth at that location. A new sample was collected from the original failed location in August 2011. The garnet sand was mixed with soil, therefore, no clean soil in the immediate vicinity was available for backfill.

The SubSite is Part Of:

Code: 100-F-56
Names: 100-F-56; 100-F Surface Debris/Stains

Code: 100-F-56:2 **Classification:** Accepted
Names: 100-F-56:2; Other 100-F Surface Debris Areas **Reclassification:** Interim Closed Out (8/23/2012)
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: This subsite has been remediated and Interim Closed Out. It consisted of twenty locations having stained soil and/or debris across the 100-F Area. Seventeen of the sites were the result of treated wood debris. Two of the sites had oil filters and one site had lead debris. The surface debris was removed.

Location: The debris was located throughout the 100-F Area. The GPS coordinates are provided in the 100-F Orphan Sites Evaluation Report (OSR-2005-0001) and are associated with the 100-F-56:2 waste site in the WCH GIS database using the OSE-ID field.

Waste Type: Not Specified

Waste Description: The waste includes discarded oil filters, lead debris, treated wood debris, and potentially contaminated soils.

Closure Info: Interim: The WCH Field Remediation (FR) project performed remedial action and housekeeping activities at the 100-F Area from July 2005 to March 2008. During these activities, Field Remediation crews found that many of the previously identified 100-F-56 waste site components appeared to have been at other sites that were remediated after the orphan sites evaluation. Thirteen areas did not require any remediation. A total of seven locations containing wood debris (i.e., rail road ties and a wooden utility pole) at the 100-F-56:2 subsite were remediated on March 1 and 2, 2011. Remedial action activities included surface pick up only, generating less than 20 bank cubic meters (26.16 bank cubic yards) of wood debris. This debris was directly loaded for disposal at the Environmental Restoration

The SubSite is Part Of:

Code: 100-F-56
Names: 100-F-56; 100-F Surface Debris/Stains

Code: 100-F-57 **Classification:** Accepted
Names: 100-F-57; 190-F Process Water Pump House Debris **Reclassification:** Interim Closed Out (8/23/2012)
Type: Foundation **Start Date:** 1/1/1945
Status: Inactive **End Date:** 1/1/1965

Description: The waste site was of the remaining, below grade foundation of the demolished 190-F Process Water Pump House. The waste site was split into two subsites in October 2011, to allow separate remediation activities on the eastern and western portions of the waste site. Both subsites have been remediated and Interim Closed Out, so the parent site is also considered Interim Closed Out.

Location: The pump house and annex were directly north of the 105-F Reactor.

Related Sites/Structures: The 190-F Process Water Pump House was associated with the 100-F-36, 108-F Biological Laboratory, the 183-F Filter Plant, the 185-F Water Treatment Plant, the 189-F Refrigeration Building, 126-F-2, 183-F Clearwells and the 105-F Reactor Building.

Process Description: The 100-F Area water treatment facilities were operated from 1945 until 1965 to provide large volumes of high quality cooling water to the 105-B Reactor. The 190-F Process Water Pump House was the final in a series of facilities that treated the raw river water before it was pumped to the 105-F Reactor. The water was transferred to underground clearwells (four 6.6 million L (1.75 million gal) tanks) located in the 190-F Process Water Pump House, where sodium dichromate was added to inhibit corrosion of the 105-F Reactor process tubes. The treated water was temporarily stored in the 190-F Process Water Pump House and pumped to the 105-F Reactor as needed.

Water was pumped from the Columbia River at the 181-F River Pump House and stored temporarily in the 182-F Reservoir. From 182-F, the water was pumped to the 183-F Filter Plant where it was treated for use as process cooling water for the 105-F Reactor. Additives for treatment of the water included chlorine, sulfuric acid (often contaminated with lead and mercury), and coagulants. The treatment process included flocculation and sedimentation process, chemical treatment, and filtration. Following coagulation and settling, the water was filtered, lime was added, and the water stored temporarily in underground clearwells.

The 190-F Process Water Pump House was the last facility in a series of facilities that treated the raw river water. Water arrived at 190-F after a flocculation and sedimentation process, chemical treatment, and filtration. At 190-F, the treated water was temporarily stored in four 6.6 million L (1.75 million gal) tanks (Clearwells), and sodium dichromate was added prior to pumping it through the F Reactor for cooling of the core and fuel. A several thousand gallon sodium dichromate storage tank was located within the facility. The facility shared a common wall on the north with the 185-F Water Treatment Plant, which later became a shop and storage facility. In 1956, an annex was added to the south of the pump house to increase the process water throughout the system. Both the pump house and the annex contained below-grade pump rooms.

Waste Type: Soil

Waste Description: Concrete foundations, demolition debris, and surrounding soil is potentially contaminated by hexavalent chromium.

This Site has the Following SubSites:

Code: 100-F-57:1

Names: 100-F-57:1; Eastern 190-F Process Water Pump House Debris

Code: 100-F-57:2

Names: 100-F-57:2; Western 190-F Process Water Pump House Debris

Code: 100-F-57:1

Classification: Accepted

Names: 100-F-57:1; Eastern 190-F Process Water Pump House Debris

Reclassification: Interim Closed Out (4/10/2012)

Type: Foundation

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. The 100-F-57:1 site consisted of the eastern half of the remaining below-grade pump room facilities and foundation of the 190-F Process Water Pump House.

Location: The 190-F pump house and annex were approximately 100 meters (330 ft) directly north of the 105-F Reactor building.

Closure Info: Interim (4/10/2012): Confirmatory sampling of the 100-F-57 waste site was conducted in 2007.

Results from the confirmatory samples failed to meet the direct-exposure remedial action goal (RAG) for benzo(a)pyrene. The subsequent design and remediation plan called for removal of the pipe cradles at the waste site.

Remediation of the 100-F-57 waste site pipe cradles began December 6, 2010. On December 9, 2010, during exploration for the 100-F-57 northern pipe cradles, discolored (i.e., green-stained) concrete was discovered. High concentrations of hexavalent chromium were noted in the concrete. The discovery of the hexavalent chromium contamination resulted in a design change from the original plan to remediate only the pipe cradles. The waste site was split into two subsites in October 2011, to allow separate remediation activities on the eastern and western portions of the waste site. Remediation of the 100-F-57:1 waste subsite was completed September 7, 2011 and resulted in 2,969 bank cubic meters (BCM) (3,883 bank cubic yards [BCY]) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility. The verification sampling failed to pass the Remedial Action Goal levels. This resulted in an additional 33 BCM (43 BCY) of soil and concrete, which was completed January 31, 2012. A total 3,002 BCM (3,926 BCY) was removed from the 100-F-57:1 waste subsite. Additional verification sampling was conducted at the 100-F-57:1 waste subsite on February 1, 2012.

No overburden material was stockpiled from the 100-F-57:1 waste subsite. The material in the overburden stockpile came from the 100-F-57:2 waste subsite, but was sampled for cleanup verification in conjunction with the 100-F-57:1 waste subsite.

The SubSite is Part Of:

Code: 100-F-57

Names: 100-F-57; 190-F Process Water Pump House Debris

Code: 100-F-57:2

Classification: Accepted

Names: 100-F-57:2; Western 190-F Process Water Pump House Debris

Reclassification: Interim Closed Out (8/23/2012)

Type: Foundation

Start Date:

Status: Inactive

End Date:

Description: The 100-F-57:2 subsite has been remediated and Interim Closed Out. It consisted of the western half of the remaining, below-grade pump room facilities and foundation of the 190-F Process Water Pump House.

Location: The 190-F pump house and annex were directly north of the 105-F Reactor.

Closure Info: Interim (8/23/2012): A discrepancy between the 100-F-57 sample design and the excavation findings resulted in an evaluation that supported a revised trench location, approximately 9 meters (30 ft) south of the original coordinates. Excavation was done at test trench #2 in January 2008. Samples of tar-like material, suspect asbestos found in pipe cradles at test trench #1, scabbled concrete and soil below test trench #2 were collected and analyzed. Based on the confirmatory sampling results, it was determined that remedial action was necessary at this waste site. The excavation exposed concrete slab walls approximately 1 meter (3 ft) apart, with debris filling the area between the walls. The debris was removed to reveal a trench, approximately 1.2 meters (4 ft) below ground surface (bgs), with pipe cradles along the length of the trench. The floor of the pump room was cleared of debris, exposing the pump pads and a grate covering the trench along the north wall. The pump room was examined for the potential location of a sump. It was concluded that no sump was present. Sample material was scabbled from each of the four pieces of concrete brought out of the trench. Soil samples were also collected from below the trench.

The excavation of the 100-F-57 waste site pipe cradles began on October 15, 2010, to collect waste characterization samples. Remediation of the 100-F-57 waste site began on December 6, 2010. On December 9, 2010, during exploration for the 100-F-57 northern pipe cradles, discolored (green-stained) concrete was discovered. The discolored concrete was surveyed using x-ray fluorescence (XRF) and high concentrations of chromium (>900 mg/kg) were detected. The discovery of the high hexavalent chromium concentrations in the in-process soil samples resulted in a design change from the original plan, which had only required remediation of the pipe cradles at the 100-F-57 waste site. October 2011, the project split the site into the 100-F-57:1 and 100-F-57:2 subsites to allow continued remediation of the western portion of the site and to facilitate closure of the eastern portion of the site and the overburden stockpile. The green stain became WIDS site 100-F-65, Green Stained Area Along Railroad Tracks Immediately West of 190-F. It was located approximately 20 meters (66 ft) west of the northwest side of the 190-F Building foundation.

Remediation of 100-F-65 was performed on July 25, 2011. The site was excavated to a depth of 1 meter (3.3 ft) bgs and resulted in approximately 84 BCM (109.9 BCY) of soil being removed and disposed at ERDF.

During the excavation, an underground injection control well was discovered on May 25, 2011 within the 100-F-57:2 subsite (at N147737.93, E580363.59). The underground injection control well was removed and disposed at ERDF. No other anomalies were noted during remediation.

The 100-F-57:2 waste subsite was excavated to groundwater levels in two locations.

Remediation of the 100-F-57:2 waste site was completed on April 9, 2012. The excavation reached a maximum depth of 12.8 meters (42 ft) bgs and resulted in approximately 55,701 BCM (72,854 BCY) of material being removed and disposed at ERDF. The debris included concrete, rebar, steel pipe, transite pipe, miscellaneous steel, wire, steel cable, and non-friable asbestos, unlike the friable asbestos discovered during confirmatory sampling.

The SubSite is Part Of:

Code: 100-F-57

Names: 100-F-57; 190-F Process Water Pump House Debris

Code: 100-F-58

Classification: Accepted

Names: 100-F-58; 100-F Surface Debris Potentially Containing Asbestos

Reclassification Interim Closed Out (5/25/2011)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The waste site consisted of twenty two areas that potentially included asbestos containing material (ACM) discarded or abandoned in the 100-F Area. A total of eight of the twenty two locations identified with potential Asbestos Containing Material (ACM) in the 100-F-58 waste site were remediated on March 2, 2011. Fourteen of the twenty-two 100-F-58 waste site locations did not require remediation.

Location: Twenty two locations have been provided as a table that includes the date found, an identification (ID) number and northing and easting coordinates in Washington State Plane, South Zone.

ID 5 - N147742.1 E580488.0

ID 6 - N147770.2 E581392.2

ID 7 - N146923.3 E580058.8
 ID 8 - N147238.6 E580367.9
 ID 11 - N146961.5 E580063.5
 ID 15 - N146964.1 E580337.8
 ID 16 - N146986.3 E580330.7
 ID 17a - N146961.2 E580298.6
 ID 17b - N147338.6 E580351.3
 ID 18 - N147379.5 E580333.7
 ID 19a - N147369.4 E580340.3
 ID 19b - N147875.0 E580245.6
 ID 20 - N147736.7 E581328.4
 ID 24 - N147300.5 E580055.7
 ID 27 - N147314.3 E580007.0
 ID 58 - N147380.9 E580099.6
 ID 63 - N148633.4 E580239.0
 ID 75 - N147566.7 E580037.8
 ID 78 - N147567.2 E580262.2
 ID 84 - N147621.1 E580087.5

Related Sites/ Structures: Temporary and permanent 100-F Area facilities removed by remedial action or decontamination/decommissioning activities are listed in the Buildings section of the Orphan Sites Evaluation report for 100-F.

Process Description: Surface debris waste (hazardous and/or dangerous) was tabulated for the 100-F Orphan Sites Evaluation (OSE) report to document the field results and guide cleanup. A WIDS submittal (100-F-58) is required pending implementation of a waste control plan for the cleanup of surface debris/stains. Various sizes and forms of hazardous (CERCLA) and/or dangerous (MTCA) surface debris waste materials were left during the construction, operation, decontamination and decommissioning (D&D), and remedial action (RA) activities at the 100-F Area. During fiscal year 2005, a field walkdown of the area was conducted as a site closure screening activity. Surface debris identified as potential dangerous/CERCLA waste was precisely located and recorded using Global Positioning Satellite technology and a field logbook. For some features, additional information was obtained using digital photography. Subsequent evaluation of the collected data yielded four generic groupings of wastes: potentially asbestos containing material, lead, oil filters/oil stains, garnet (sand blasting material), and treated wood.

Originally, there were five categories of waste that were part of 100-F-56. At the request of the Remaining Sites Project, a separate WIDS site (100-F-58) was created for the potential asbestos containing material (ACM). The type of surface debris identified as either hazardous or dangerous waste materials according to CERCLA or MTCA was potentially asbestos containing material (including transite). Whereas this waste was created as a result of either operations or a site cleanup (i.e., D&D) activity, it would seem appropriate to dispose of them at the Environmental Restoration Disposal Facility under a project waste control plan. The concept for handling scattered surface debris under the Investigation Derived Waste (IDW) Strategy was presented at the June 2005 Unit Managers Meeting (UMM) and accepted at the July 2005 UMM meeting for implementation by the RA Project.

Various sizes and forms of hazardous (CERCLA) and/or dangerous (MTCA) surface debris waste materials were left during the construction, operation, decontamination and decommissioning (D&D), and remedial action (RA) activities at the 100-F Area. During fiscal year 2005, a field walkdown of the area was conducted as a site closure screening activity. Surface debris identified as potential dangerous/CERCLA waste was precisely located and recorded using Global Positioning Satellite technology and a field logbook. For some features, additional information was obtained using digital photography. Subsequent evaluation of the

collected data yielded four generic groupings of wastes, including potentially asbestos containing material, lead, oil filters/oil stains, garnet (sand blasting material), and treated wood.

Waste Type: Misc. Trash and Debris

Waste Description: The solid waste consists of scattered debris mainly in the form of transite. The debris is thought to potentially contain asbestos.

Closure Info: Interim (5/25/2011): Remedial action and housekeeping activities occurred from July 2005 through March 2008. Fourteen of the twenty-two 100-F-58 waste site locations did not require remediation. The locations associated with site ID numbers 20 and 75 encompassed small areas with scattered potential ACM where no ACM was visible. It is believed these areas had been scraped during road blading activities or during soil stockpile moving, such that the scattered ACM that had been present was no longer visible. Because there is no human health or environmental threat from the scattered miscellaneous concrete debris, locations that contained cement and/or grout did not require remediation. The cement/grout debris is suspected to be associated with former pre-Hanford farmsteads and is likely residual remnants of former building foundations. Larger accumulations of concrete will be removed via Miscellaneous Restoration.

A total of eight of the twenty two locations identified with potential Asbestos Containing Material (ACM) in the 100-F-58 waste site were remediated on March 2, 2011. Remedial action activities included non-mechanical surface pick-up (picked up by hand) only, generating less than 1 bank cubic meter (1.3 bank cubic yards) of potential ACM that was directly loaded for disposal at the Environmental Restoration Disposal Facility.

Code: 100-F-59

Classification: Accepted

Names: 100-F-59; Riparian Area Contamination
Originating from 128-F-2

Reclassification: None

Type: Burn Pit

Start Date:

Status: Inactive

End Date:

Description: The 100-F-59 is a non-radiological waste site created after the remediation of the 128-F-2 Burn Pit. It is two riparian areas known to contain contaminants above soil remedial action goals (RAGs). The first riparian area is located adjacent to the Columbia River. It was remediated, as part of 128-F-2, to an elevation below the ordinary high water mark (OHWM) of the river. The second riparian area is located below the OHWM, east and southeast of the 128-F-2 waste site. Sediment sampling showed metal contamination in excess of soil RAGs was present. These areas became 100-F-59. During the burn pit remediation, this area was known as Area C. The portion of the 100-F-59 site located outside of the 128-F-2 remediation boundary represents the riparian area with relatively elevated metals concentrations in sediment.

Location: The site is located in the northeast corner of the 100-F Area; approximately 30.5 meters (100 feet) east of the northeast corner of the 100F Area perimeter road which runs along the riverbank and directly east of the 107-F Retention Basin; and along the Columbia Rive, in the nearby riparian area which is occasionally under water.

**Related Sites/
Structures:** 128-F-2 Burning Pit

Process Description: The 128-F-2 Burn Pit was an irregularly shaped depression that was used for incinerating nonradioactive, combustible materials (e.g., vegetation, office waste, paint waste, and chemical solvents). During Hanford Site cleanup operations in the late 1970s, unknown quantities of debris were removed from the burn pit and the site was backfilled (UNI-1488).

Waste Type: Soil

Waste Description: Contaminated soil, The contaminants of concern are ICP metals, mercury, hexavalent chromium, polychlorinated biphenyl (PCBs), and pesticides.

Code: 100-F-60

Classification: Accepted

Names: 100-F-60; Cast Iron Pipe

Reclassification: Interim No Action (3/2/2011)

Type: Product Piping

Start Date:

Status: Inactive

End Date:

Description: The 100-F-60 site was evaluated and determined that No Action was required. It was a 10 centimeter (4 inch) diameter cast iron pipe, buried approximately 1.2 meters (4 feet) below ground surface. Confirmatory sampling for 100-F-60 was performed in September 2010.

Location: This feature is located approximately 75 meters east of the 185-F Building, at coordinates E580556 N147780. It was discovered laying in a northwest direction leading towards a sanitary sewer junction box (100-F-26:9). The junction box was removed during confirmatory sampling of 100-F-26:9 and is no longer present.

Related Sites/ Structures: The 100-F-60 pipe was found while sampling 100-F-26:9.

Closure Info: Interim: Confirmatory sampling for 100-F-60 was performed in September 2010. Two focused samples from the excavated test pit were used to evaluate the 100-F-60 waste site. The cast iron pipe was uncovered 3 meters (9.8 feet) to the northwest of the expected location at coordinates N 147783, E 580552. The pipe was 1.3 meters (4 feet) below ground surface and appeared to be intact. One focused sample was collected from the pipeline contents. There was not enough soil and sediment present inside the pipeline; therefore, the duplicate was collected from the soil underlying the pipeline. Field surveys for radiological contamination and volatile organic compounds (VOCs) were conducted during sampling. No radiological activity or VOCs were detected. Confirmatory sampling determined that environmental contamination was not present at this waste site. Based on confirmatory sampling at the 100-F-60 waste site, remedial action was determined to be unnecessary.

The 100-F-60 waste site has been evaluated in accordance with the 100 Area Remaining Sites ROD and the Remedial Design Report/Remedial Action Work Plan. Confirmatory sampling was performed, and the analytical results indicate that the residual concentrations of COPCs at this site meet the RAGs and associated RAOs for direct exposure, groundwater protection, and river protection. In accordance with this evaluation, the verification sampling results support a reclassification of the 100-F-60 waste site to No Action.

Code: 100-F-61

Classification: Accepted

Names: 100-F-61; Stained Soil near 100-F-12

Reclassification: Interim Closed Out (12/22/2011)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The waste site has been remediated and Interim Closed Out. It consisted of an area of stained soil discovered while excavating the 100-F-12 french drain, near 105-F.

Location: The site was located northeast of the 105-F Reactor, approximately 30 centimeters (12 in.) east of the Electrical Equipment Room Number 1 at (E) 580460, (N) 147631 Washington State Plane.

Related Sites/ Structures: 100-F-61 is associated with 100-F-12.

Closure Info: Interim (12/22/2011): Demolition activities at this location had removed the upper portion of the 100-F-12 french drain. The french drain was then investigated by digging a test pit on October 11, 2004, to determine what structure remained and if the site was contaminated. Wood debris was uncovered just beneath the gravel surface and was identified as pieces of a power pole. A dark stain was uncovered approximately 1 meter (3.3 ft) below ground surface (bgs), along with power pole debris and asphalt. The stained soil was observed outside the red gravel exterior of the french drain and, as a result, was determined to be a discovery site (becoming sitecode 100-F-61) and not associated with the 100-F-12 french drain.

Remediation of the 100-F-61 waste site began February 7, 2011, to remove the stained soil contamination. The stained soil associated with the confirmatory sampling description was located and removed. A layer of coal ash beneath the surface was removed with the excavation. Debris removed from the excavation consisted of asphalt, steel cable, steel conduit, and parts of steel pipe. All waste material was directly loaded for disposal at the Environmental Restoration Disposal Facility (ERDF). No overburden was associated with the waste site. An underground injection chamber associated with the No Action 100-F-12 french drain was removed with the excavation. Through in-process sampling of the excavated area, the 100-F-61 soil contamination was determined to extend north of the original stained soil location toward an active utility pole with overhead power lines. Remediation continued north of the existing excavation during an electrical power outage on March 24, 2011, removing contaminated soil, ash, and associated debris. The excavation was expanded toward the power pole area to the extent possible without affecting the stability of the pole. Due to remaining contamination indicated by in-process samples around the power pole, the decision was made to remove the pole and expand the excavation. The power pole was removed June 22, 2011, and the surrounding contaminated soil was excavated. On August 11, 2011, soil removal targeted the area around the electrical equipment room and extended the excavation on the north side. The final excavation was approximately 3 meters (10 ft) deep.

Code: 100-F-62	Classification: Accepted
Names: 100-F-62; Animal Farm Septic Lines	Reclassification: Interim Closed Out (12/22/2011)
Type: Sanitary Sewer	Start Date:
Status: Inactive	End Date:
Description: The waste site has been remediated and Interim Closed Out. The site included the influent pipes from the 141-M and 144-F 100-F Experimental Animal Farm (EAF) buildings. The 141-M Building vitrified clay pipe connected to the 1607-F7 septic tank and drain field. The 144-F steel pipe influent piping connected to the 100-F-31 septic tank and drain field.	
Location: The Animal Farm (EAF) complex was located approximately 500 meters (0.3 miles) northeast of the 105-F Reactor.	
Related Sites/ Structures: This site is associated with the 1607-F7 septic system and 100-F-31 septic system and the 141-M and 144-F buildings.	
Process Description: The 1607-F7 septic tank and drain field received sanitary sewage from the 141-M Building. The building was constructed in 1949 to provide office space and to serve as a change room for Animal Farm personnel working in the 100F Area. The EAF operations were discontinued in 1976. The 141-M building was also demolished in 1976.	

A sample of the 1607-F7 septic tank contents was collected on October 6, 2004. The results

indicated that the site required remediation. The septic tank and drain field was excavated between August 8 and November 30, 2005. Remediation of the 1607-F7 site was successful and it was reclassified as interim closed out. The post excavation civil survey (0100F-DD-C0309) shows the area excavated to remove the septic tank and drain field. The influent piping was not removed during the 2005 remedial action activities.

The 100-F-31 septic tank and drain field received animal and human septic waste from the 144-F Building. The building was constructed about 1960 as an L-shaped addition to the south end of the 141-F Sheep Barn. It contained an office, several laboratories, and a series of indoor/outdoor kennels. It was used for Pu-239 and Ra-226 inhalation studies first with mice, and then with dogs (BHI-00031). The 144-F facility was decontaminated and removed in 1978.

Samples of the 100-F-31 septic tank contents and stained soil were collected on October 15, 2004. The results indicated that the site required remediation. The septic tank and drain field was excavated in October 2004. Additional excavation was performed on February 6, 2006. Remediation of the 100-F-31 site was successful and it was reclassified as interim closed out. The post excavation civil survey (0100F-DD-C0309) shows the area excavated to remove the septic tank and drain field. The influent piping does not appear to have been removed by the remedial action activities. A portion of the influent piping was removed previously during the Group 4 Remedial Action (100-F-29) as shown in 0100F-DD-C0140. Approximately 13 meters (43 ft) of the influent piping was in an undisturbed area between the two excavations.

Closure Info: Interim (12/22/2011): Remedial action at the 100-F-55 waste site was performed from September 16 to October 7, 2010 to a depth of 0.7 meters (2.3 ft). Remedial action at the 100-F-62 waste site was performed from December 2010 to March 2011. The 100-F-62 north pipeline excavation included the removal of the pipelines to the former 1607-F7 septic tank and contained the 100-F-55 waste site excavation. From the north excavation, approximately 2 meters (7 ft) of the 4 inch diameter vitrified clay pipe were removed, and approximately 5 meters (16 ft) of 4 inch diameter steel pipe with lead bells were removed. Verification sample results indicated additional remediation was required. Additional remediation was performed from July 29 to August 9, 2011. The center section of the north excavation was further remediated, and the entire south excavation was further remediated and expanded to the south. The final north excavation depth is 2.3 meters (7.6 ft), and the final south excavation depth is 4.4 meters (14.5 ft). Additional remediation also occurred at the east staging pile area and the northeast quadrant of the south staging pile area.

Code: 100-F-63	Classification: Accepted
Names: 100-F-63; Animal Farm Radioactive Effluent Lines	Reclassification: Interim Closed Out (9/26/2011)
Type: Radioactive Process Sewer	Start Date:
Status: Inactive	End Date:
Description:	The waste site has been remediated and Interim Closed Out. It included radioactive effluent piping and process sewers at the north end of the Experimental Animal Farm (EAF).
Location:	The EAF complex was located approximately 500 meters (0.3 miles) northeast of the 105-F Reactor.
Related Sites/ Structures:	The pipelines were associated with 146-F, 147-F and 1705-F.
Process Description:	Radioactive effluent was supplied to the EAF beginning in 1945 from the 147-F pump house. The effluent was used to perform studies by exposing fish to varying concentrations of reactor cooling water effluent (BHI-00031). Radioecology experiments also took place at the EAF.

Greenhouses located in the 1705-F Building were used for growing potted plants. Samples of piping and soil were collected at the 146-F Aquatic Biology Fish Ponds site (100-F-33) in September 2004 (118428). The results indicated that the northern portion of the site required remediation. Excavation of contaminated concrete, piping and soil was performed between August 5 and 8, 2005. Remediation of the 100-F-33 was successful and it was reclassified as interim closed out (129492). Portions of the effluent pipelines and process sewer that ran between the 146-F and 147-F buildings appear to be outside of the excavated area. In addition, portions of the process sewer from drains in the 1705-F building appear to be outside the excavated area. Lastly 10 m (33 ft) of the process sewer leading to the circular pond in the south half of the 100-F-33 site appears to be outside of the excavation. The drain at the head end of this sewer was sampled (J01TF8) as part of 100-F-33 test pit 3 and did not require remedial action. It is assumed that this segment was closed in place using the same information. Two other remedial action events took place in the vicinity of the piping. Portions of the piping were likely removed by these activities. Refer to CVP-2001-00002 and CVP-2001-00010 for a description of the cleanup activities.

Closure Info: Interim (9/26/2011): In November 2007 and February 2008, confirmatory sampling of the 100-F-51 waste site was carried out during the excavation of two test pits, at the north end and southeast corner of the laboratory. Confirmatory sampling results failed to meet remedial action goals (RAGs) and indicated the need for remedial action at the 100-F-51 waste site. Confirmatory sampling was not performed for the 100-F-63 waste site. 100-F-63 was added to the 100-F Area remove, treat, and dispose scope in 2010.

Remedial action at the 100-F-51 and 100-F-63 waste sites began on December 20, 2010, and continued through January 20, 2011. Excavation depth ranged from 0.5 to 1.5 meters (1.6 to 4.9 ft) below ground surface and resulted in approximately 253 bank cubic meters (BCM) (331 bank cubic yards [BCY]) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility. Approximately 330 BCM (432 BCY) of overburden soil was stockpiled to be used as backfill. The 100-F-51 and 100-F-63 waste sites debris included concrete, clay pipe, steel pipe, and asphalt. The verification sampling results support a reclassification of the 100-F-51 and 100-F-63 waste sites to interim closed out.

Code: 116-F-1	Classification: Accepted
Names: 116-F-1; Lewis Canal	Reclassification: Interim Closed Out (11/3/2003)
Type: Trench	Start Date: 1/1/1953
Status: Inactive	End Date: 1/1/1965
Description:	The site has been remediated and Interim Closed Out. The waste site was an unlined trench that carried cooling water effluent to the Columbia River.
Location:	The site was located approximately 160 meters (525 feet) west-northwest of the 105-F Building then turned north to the Columbia River.
Release Description:	Contaminated coolant from the reactor front and rear faces were known to have drained into the unit. This included reactor cooling water diverted to the Columbia River via this waste site during the Ball 3X Project in 1953. It also received reactor coolant that was diverted to the trench during reactor process tube chemical scaling activities (i.e., when chemicals were flushed through the process tubes to remove scale that had built up on their inner surfaces and during the H-558 Increased Cooling Water Flow Project and other reactor upgrade projects).
Related Sites/Structures:	The site was related to 105-F, 182-F, 183-F, and 190-F and 189-F Buildings. The pipelines associated with the canal became part of 100-F-19:2 and 100-F-19:3.
Process Description:	The 116-F-1 Trench was commonly known as Lewis Canal. The 105-F Reactor cooling water was diverted to the Columbia River via this trench. The water flowed west from the headwall,

turned northward where it intersected with the Columbia River. Two additional ditches entered the main trench laterally from the east. The north lateral ditch was 194.5 meters (638 feet) long. The south lateral ditch was 219 meters (718 feet) long. Water from the main trench entered the Columbia River without an outfall structure. The water ran across a cobble-covered beach and into the river.

Waste Type: Water

Waste Description: The site received liquid wastes from the 105-F, 182-F, 183-F, and 190-F Buildings and decontamination wastes from the 189-F Building. Reference RHO-CD-827 lists a calculated contaminated soil volume of 2.066E+05 cubic meters (7.3E+06 cubic feet) for the 914-meter (3000-foot) length of Lewis Canal (the length described in most of the documentation for the site). Estimated radionuclide inventories are available in Stenner (1988). Soil sample results are available in Dorian and Richards (1978). The hazardous chemical inventory included sodium dichromate and sulfamic acid. Surface soil and vegetation samples were collected from the areas adjacent to 116-F-1, analyzed for radionuclide concentrations (cobalt-60, strontium-90, cesium-137, plutonium-238, plutonium-239/240), and compared with the results from 1981 through 1986 (Jacques 1986).

Closure Info: Interim: The selected remedial action included (1) excavating the site to the extent required to meet specified soil cleanup levels, (2) disposing of contaminated excavation materials at the Environmental Restoration Disposal Facility (ERDF) at the 200 Areas of the Hanford Site, and (3) backfilling the site with clean soil to average adjacent grade elevation. Excavation was driven by remedial action objectives for direct exposure, protection of groundwater, and protection of the Columbia River.

Remedial action began in June 2002. Excavation involved removing overburden, buried sludge, the contaminated structure and underlying contaminated soil. Two, parallel, lateral ditches did not require remediation and were not excavated. The main excavation was completed in December 2002. An additional small portion was excavated in January 2003. The maximum depth of excavation was 4.5 meters (14.8 feet).

At the completion of remedial action, the total excavation was approximately 24,820 square meters (267,000 square feet) in area with a depth of approximately 4.5 meters (14.8 feet). Approximately 77,696 metric tons (70,634 tons) of material from the site were disposed of at the Environmental Restoration Disposal Facility.

The remedial action at the 116-F-1 site has achieved the RAOs and corresponding RAGs established in the ROD (EPA 1997) and RDR/RAWP (DOE/RL-96-17). The remaining soils at the site have been sampled, analyzed, and modeled. The results of this effort indicate that the materials from the site containing COCs at concentrations exceeding RAGs have been excavated and disposed of at ERDF. These results also indicate that residual concentrations at the site, including overburden, will support future land uses that can be represented (or bounded) by a rural-residential scenario, and are protective of groundwater and the Columbia River. The 116-F-1 site is verified to be remediated in accordance with the ROD (EPA 1997) and may be backfilled.

Code: 116-F-2	Classification: Accepted
Names: 116-F-2; 107-F Liquid Waste Disposal Trench	Reclassification: Final Closed Out (10/28/2015)
Type: Trench	Start Date: 6/4/1948
Status: Inactive	End Date: 1/1/1965

Description: The waste site has been remediated, Interim Closed Out and later Final Closed Out. It was an open liquid waste trench. A 15-centimeter (6-inch), 12-gauge steel distribution pipe ran from

the north end of the 107-F Basin to the north end of the trench. The length of piping inside the trench was unknown since piping was added as the trench was used and later backfilled.

This site was also fed by two emergency bypass ditches that connected the 116-F-2 trench to the effluent line connected to the south end of the 107-F Basin. The first emergency bypass ditch, about 90 meters (295 feet) long, ran from the west center side of the 116-F-2 Trench to the gate valve on the 1.7 meter (5.6 feet) pipeline that ran to the 107-F Basin Inlet Distribution Box at the south end of the 107-F Retention Basin. A second emergency ditch bypass trench connected the 116-F-2 trench to a valve on the 107-centimeter (42-inch) diameter 105-F effluent pipeline. These ditches are also considered to be part of 116-F-2. The trench is shown on Hanford drawings H-1-70185, H-1-1522 and H-1-1540. The liquid waste and bypass trenches are visible in Hanford aerial photo 91062128-8.

- Location:** The site was located approximately 670 meters (2200 feet) east of the 105-F Reactor Building and approximately 60 meters (197 feet) east-southeast of the southeastern corner of 107-F Retention Basin.
- Related Sites/ Structures:** The site was related to the 116-F-14 (107-F) Retention Basin and the 1.7-meter (5.6-foot) diameter pipeline exiting the south end of the Retention Basin and the 100-F-19, 100-F Reactor Cooling Water Effluent Underground Pipelines, Contaminated Underground Lines, Effluent Water System.
- Process Description:** The original trench was excavated June 4-5 1948 and used to dispose of the contaminated reactor effluent from the first Hanford site fuel failure (HW-10284).
- Waste Type:** Process Effluent
- Waste Description:** The site received cooling water effluent from the 107-F Retention Basin during reactor outages due to fuel ruptures. During deactivation of the 105-F Reactor, the unit received overflow water from the 105-F Storage Basin via the retention basin. RHO-CD-827 lists the calculated volume of contaminated soil to be 2.5E+05 cubic meters (9E+06 cubic feet). Radionuclide inventory for 116-F-2 from Stenner (1988) lists, 0.37 curies of tritium, 0.8 curies of cobalt-60, 0.07 curies of strontium-90, 0.76 of cesium-137, 0.007 curies of plutonium-239, and 6.05 curies of europium-152. The site also has a hazardous chemical inventory that includes 60,000 kilograms (1.3E+05 pounds) of sodium dichromate. The results of four soil sample sites in the trench and four samples taken in the connecting ditch can be found in Dorian and Richards (1978).
- Closure Info:** Interim: (Interim Closed Out) Remedial action began on November 22, 2000, and was completed on April 17, 2002. Excavation involved removing the overburden materials and underlying soil. On May 21 through May 29, 2002 cleanup verification samples from the shallow zone, deep zone and overburden were collected and analyzed for the established contaminants of concern.

At the completion of the remedial action, the total excavation was approximately 15,352 square meters (50,367 square feet) in area with a depth of approximately than 4.6 meters (15 feet). Approximately 113,007 metric tons (124,534 tons) of material from the site were disposed at the Environmental Restoration Disposal Facility.

Final (10/28/2015): (Final Closed Out) Thirteen 100-F Area waste sites were reclassified to Final Closed out on form 2015-078. They had all previously been classified as Interim Closed Out. The waste sites included on this reclassification form are 100-F-10, 100-F-19 (and subsites 1,2 and 3), 100-F-29, 100-F-34, 116-F-2, 116-F-6, 116-F-9, 116-F-12, subsites 118-F-8:3 and :4, UPR-100-F-1. The Record of Decision (ROD) for the 100-FR-1, 100-FR-2, 100-FR-3, 100-IU-1, 100-IU-2 and 100-IU-6 Operable Units has defined these waste sites as all requiring institutional controls to restrict excavation into the deep zone (greater than 4.6 meters or 15 feet below the ground surface). However, no further remedial actions are required.

Institutional Control Boundaries have been defined to be broadly inclusive of waste site groups. Not all areas within these boundaries contain residual contamination greater than 4.6 meters (15 ft) below ground surface. An image of four Institutional Control Boundaries inside 100F Area was attached to the 2015-078 Reclassification form (and included in the WIDS library).

Code: 116-F-3	Classification: Accepted
Names: 116-F-3; 105-F Storage Basin Trench	Reclassification: Interim Closed Out (6/16/2003)
Type: Trench	Start Date: 1/1/1947
Status: Inactive	End Date: 1/1/1951

Description: The site has been remediated and Interim Closed Out. The trench had been an east-west oriented open excavation. After deactivation in 1951, the basin was backfilled with soil and cobbles. It was left unmarked and was not visually discernible. No vent pipes or other appurtenances were visible.

Location: The site was located approximately 39.6 meters (130 feet) south of the 105-F Reactor Building.

Related Sites/ Structures: The site is associated with the 105-F reactor and the 105-F fuel storage basin.

Process Description: The trench received reactor cooling water during a 1947 fuel rupture occurrence. In 1951, the trench received sludge from the 105-F fuel storage basin.

Waste Type: Process Effluent

Waste Description: The site received reactor effluent from the 105-F Reactor Building during an early fuel failure outage. In 1951, the site received sludge from the 105-F Storage Basin. During test pit activities in 1993, a buried pipe measuring 150 millimeters (6 inches) in diameter was found buried in the trench at approximately 1.8 meters (6 feet) below surface grade. The pipe was radiologically contaminated reading 500 counts per minute (5000 disintegrations per minute). The contaminants of concern (COC) for this site consist of Europium-152, Europium-154 and Hexavalent chromium.

Closure Info: Interim: Remedial action at the 116-F-3 site began in October 2002. The majority of the excavation was completed in January 2003. However, an additional remedial excavation occurred in February 2003. Excavation of the site involved removing the overburden materials and underlying contaminated soil. Contaminated materials were disposed of at the ERDF. At the conclusion of excavation activities in February 2003, the elevation of the bottom of the excavation was at 121.7 meters (399.3 feet). Site excavation and waste disposal are complete, and the exposed surfaces have been sampled and analyzed to verify attainment of the Remedial Action Goals (RAG). At the completion of the remedial action, the total area of the excavation was approximately 843 square meters (9,074 square feet) with a depth of 4.7 meters (15.4 feet). Approximately 5,205 metric tons (5,738 tons) of material from the site were disposed of at the Environmental Restoration Disposal Facility.

Field screening was used to guide the excavation to quickly assess for the presence and level of contamination. Field screening for the 116-F-3 site included using a radiological data mapping system survey, hand-held sodium iodide (NaI) detectors, and gamma energy analyses. The radiological mapping survey is performed over more than 50% of the site excavation surface area. The hand-held NaI detector is used to screen excavated waste material and to screen for potential excavation wall and floor hot spots. Gamma energy analyses were used to support waste characterization and to corroborate the radiological mapping survey and hand-held sodium iodide (NaI) detector data.

Remedial action objectives and goals for the 116-F-3 site were established by the U.S. Environmental Protection Agency and the U.S. Department of Energy, Richland Operations Office, in concurrence with the Washington State Department of Ecology. These goals and objectives are documented in the Amendment to the Interim Action Record of Decision for the 100-BC-1, 100-DR-1, and 100-HR-1 Operable Units (ROD) (EPA 1997) and the Remedial Design Report/Remedial Action Work Plan for the 100 Area (DOE-RL 2002). The RAGs were developed to support a rural-residential exposure scenario. This scenario involves exposures to soils less than 4.6 meters (15 feet) deep only.

The selected remedial action for the 116-F-3 site included (1) excavating the site to the extent required to meet specified soil cleanup levels, (2) disposing of contaminated excavation materials at the Environmental Restoration Disposal Facility at the 200 Areas of the Hanford Site, and (3) backfilling the site with clean soil to average adjacent grade elevation. Excavation was driven by remedial action objectives for direct exposure, protection of groundwater, and protection of the Columbia River.

Code: 116-F-4	Classification: Accepted
Names: 116-F-4; 105-F Pluto Crib	Reclassification: Interim Closed Out (11/8/2001)
Type: Crib	Start Date: 1/1/1950
Status: Inactive	End Date: 1/1/1952

Description: The waste site has been remediated and Interim Closed Out. The unit consisted of a french drain-type distribution system. A 0.61-meter (2-foot) riser was attached to a bottomless 208-liter (55-gallon) drum that drained into a cobble leach field.

Location: The unit was located approximately 40 meters (130 feet) southwest of the southwestern corner of the 105-F Reactor Building.

Process Description: The 116-F-4 Pluto Crib was an inactive waste site that operated from 1950 to 1952 receiving contaminated reactor cooling water from the 105-F Reactor building. The purpose of the crib was to receive liquid wastes from the 105-F Reactor Building during outages due to fuel ruptures. Cooling water was diverted from the affected tube through a valve known as a "pluto valve" or "pluto cap" and through a rubber hose to the crib. The hose ran above ground from the rear face of the reactor to the crib.

Waste Type: Process Effluent

Waste Description: The site received coolant water from pressure tubes containing ruptured fuel elements. It was estimated that 280 curies of fission products were discharged to the crib during its operation (Dorian and Richards 1978). It was also assumed that the contaminated soil occupied a volume of 6 by 6 by 7.6 meters (20 by 20 by 25 feet).

Closure Info: Interim: The 116-F-4 site was excavated from September to November 1993 during a soil treatability study. Before excavation activities commenced, the vertical extent of contamination was estimated using February 1993 borehole data taken from a location next to the crib riser.

The crib excavation proceeded in 0.6 meter (2-ft) deep increments, or "lifts," over a 6 meter by 6 meter (20 ft by 20 ft) survey/sample grid. Each lift of soil was surveyed using a Geiger-Mueller detector (GM) and portable alpha meter to segregate contamination areas from uncontaminated areas. Excavation at each lift consisted of an initial phase in which uncontaminated soil was removed, followed by a second phase in which contaminated soil was removed. The contaminated soil was transported to a container for storage prior to disposal at ERDF. Overburden materials, identified as potentially clean, were placed in stockpiles for possible use as backfill. On the ninth lift, at a depth of 5.5 meters (18 ft), radiation levels were below

detection limits of the GM survey instruments. Additional in situ monitoring equipment indicated cesium-137 levels just above background in the immediate vicinity of the February 1993 borehole. As a result of an onsite decision by DOE/RL, EPA, and Ecology, a 7.9 meter (26 ft) deep (2.4 meters [8 ft] below bottom of excavation) test pit (Test Pit 1) was excavated at the bottom of the site excavation. An additional test pit (Test Pit 2) was also excavated at the bottom of the site excavation. The elevation of the excavation floor was 123.2 meters (404.2 ft) upon completion, with a maximum depth of approximately 5.5 meters (18 ft). The resulting final excavation yielded 2,980 cubic meters (3,900 cu. yd) of non-contaminated overburden soil and 410 cubic meters (540 cu yd) of contaminated soil. Approximately 700 metric tons (772 tons) of material from the site were disposed of at ERDF.

Cleanup verification sampling was conducted on November 10, 1993 from the bottom of the test pits.

Remedial action objectives and goals for the 116-F-4 site were established by the U.S. Environmental Protection Agency and the Washington State Department of Ecology, in concurrence with the U.S. Department of Energy, Richland Operations Office. These goals and objectives are documented in the Amendment to the Interim Action Record of Decision for the 100-BC-1, 100-DR-1, and 100-HR-1 Operable Units (ROD) (EPA 1997) and the Remedial Design Report/Remedial Action Work Plan for the 100 Area (RDR/RAWP) (DOE-RL 2000).

Code:	116-F-5	Classification:	Accepted
Names:	116-F-5; Ball Washer Crib	Reclassification	Interim Closed Out (8/16/2001)
Type:	Crib	Start Date:	1/1/1954
Status:	Inactive	End Date:	1/1/1964

Description: The site has been remediated and closed out. The 116-F-5 Crib has been fully backfilled and appeared as an unmarked, gravel-covered field. No vent pipes or other appurtenances remain.

The crib was fed by a 76-meter (250 foot) long vitrified clay pipeline that ran from the 105-F Reactor Building, at which point a 10.2-centimeter (4-inch) schedule 40 steel pipe was used. The pipeline was about 1.2 meters (4 feet) below grade. The vitrified clay pipe consisted of 1.2-meter (4-foot) sections. The bell ends were sealed with lead rings. The pipeline ended in a 3 by 3 by 2.7-meter (10 by 10 by 9-foot) excavation filled with cobble. Approximately 36.5 meters (120 feet) of the pipe, from 116-F-5 to the north end of the 116-F-4 excavation, was removed in 1993 during the 100 Area Excavation Treatability Test. The remaining 39.5 meters (130 feet) of pipe is part of site 100-F-26 for remedial action.

Location: The site was located approximately 50 meters (140 feet) southwest of the 105-F Reactor Building.

Related Sites/ Structures: The site was associated with the 105-F Reactor Building ball washer assembly and the 100-F-26:14 Influent Pipeline.

Process Description: The site was used to dispose of liquid decontamination wastes from the 105-F Reactor ball washer assembly. It served to clean and decontaminate small, steel-jacketed boron balls used in the Ball 3X safety system. The ball washer assembly was located in the transfer basin area of the 105-F Reactor Building.

Waste Type: Process Effluent

Waste Description: The site received liquid waste associated with the decontamination of boron steel balls. Contaminants included strontium-90, cesium-137, europium-154, and europium-155. The waste also included nitric acid that was used for decontamination. However, sampling done in

1997 found only cobalt-60 and europium-155 to be above background levels. The Cleanup Verification Package lists the final contaminants of concern (COCs) based on the Sampling and Analysis Plan (DOE/RL-96-22) as cesium-137 and cobalt-60.

Closure Info: Interim: A large test pit was excavated at the 116-F-5 site on July 30, 1997. Field screening and sampling of soil were conducted during excavation. The test pit excavation was an ellipse approximately 6.1 meters by 7.3 meters (20 feet by 24 feet) by 3.4 meters (12 feet) in depth. During test pit excavation, the entire 3-meter (10-foot) by 3-meter (10-foot) by 2.7-meter (9-foot)-deep crib structure (gravels) was excavated, field screened, and sampled. A total of 20 verification samples were collected from four intervals within the test pit on July 30, 1997.

No contaminated materials or soil were encountered.

Code:	116-F-6	Classification:	Accepted
Names:	116-F-6; 1608-F Liquid Waste Disposal Trench; 105-F Cooling Water Trench	Reclassification	Final Closed Out (10/28/2015)
Type:	Trench	Start Date:	1/1/1952
Status:	Inactive	End Date:	1/1/1965

Description: The site has been remediated, Interim Closed Out and later Final Closed Out. The site was an open excavation used to receive reactor cooling water. The waste site was an unlined trench used intermittently to dispose of cooling water while maintenance and repairs were being performed on the effluent system.

Location: The site was located about 55 meters (180 feet) southeast of the southeastern corner of the 105-F Building.

Related Sites/ Structures: The site intermittently received cooling water from the 105-F Reactor Building.

Process Description: The site was used intermittently to dispose of cooling water while maintenance and repairs were being performed on the effluent system.

Dorian and Richards (1978) refer to the 116-F-6 Trench as the "1608-F Liquid Waste Disposal Trench", suggesting that the 1608-F Pumping Station wastes were disposed at this site. Several other documents, including Gano and Hall (1987), Hanford Drawing H-1-15244, and Kiser (1988) also use this nomenclature for 116-F-6. Hanford drawing H-1-70185 shows a "crib" pipe emerging from the east side of 1608-F and angling south toward 116-F-6. A ground penetrating radar (GPR) survey done in 1993 identified a linear anomaly that may represent this pipe.

Waste Type: Process Effluent

Waste Description: The site received water diverted during reactor shutdowns when maintenance was necessary on the effluent system. This practice was used during several reactor upgrades. Contaminants would include, europium-152, cobalt-60, europium-154, cesium-137, and sulfamic acid (3,000 kilograms [6600 pounds]).

Closure Info: Interim: (Interim Closed Out) The selected remedial action for the 116-F-6 site included (1) excavating the site to the extent required to meet specified soil cleanup levels, (2) disposing of contaminated excavation materials at the Environmental Restoration Disposal Facility (ERDF) at the 200 Areas of the Hanford Site, and (3) backfilling the site with clean soil to average adjacent grade elevation. Excavation was driven by remedial action objectives for direct exposure, protection of groundwater, and protection of the Columbia River.

The remedial action began in October 2002. The majority was completed in November 2002,

with a small addition excavation occurring in January 2003. A pipe was encountered on the north part of the excavation. It was removed and disposed at ERDF. At the completion of the remedial action, the total excavation was approximately 5,272 square meters (56,747 feet) in area with a depth of 5.1 meters (17 feet). Approximately 32,156 metric tons (35,446 tons) of material from the site were disposed of at the Environmental Restoration Disposal Facility (ERDF).

Final (10/28/2015): (Final Closed Out) Thirteen 100-F Area waste sites were reclassified to Final Closed out on form 2015-078. They had all previously been classified as Interim Closed Out. The waste sites included on this reclassification form are 100-F-10, 100-F-19 (and subsites 1,2 and 3), 100-F-29, 100-F-34, 116-F-2, 116-F-6, 116-F-9, 116-F-12, subsites 118-F-8:3 and :4, UPR-100-F-1. The Record of Decision (ROD) for the 100-FR-1, 100-FR-2, 100-FR-3, 100-IU-1, 100-IU-2 and 100-IU-6 Operable Units has defined these waste sites as all requiring institutional controls to restrict excavation into the deep zone (greater than 4.6 meters or 15 feet below the ground surface). However, no further remedial actions are required.

Institutional Control Boundaries have been defined to be broadly inclusive of waste site groups. Not all areas within these boundaries contain residual contamination greater than 4.6 meters (15 ft) below ground surface. An image of four Institutional Control Boundaries inside 100F Area was attached to the 2015-078 Reclassification form (and included in the WIDS library).

Code:	116-F-7	Classification:	Accepted
Names:	116-F-7; 116-F-7 Seal Pit Water Crib and Pipeline; 117-F Crib and Pipeline	Reclassification	Interim No Action (11/14/2005)
Type:	Crib	Start Date:	1/1/1960
Status:	Inactive	End Date:	1/1/1965
Description:	The subsite components were evaluated and determined to require No Action. The waste site consisted of the seal pit crib and pipeline.		
Location:	The site was located 137 meters (450 feet) south of the southwestern corner of 105-F Building.		
Related Sites/ Structures:	The site was associated with 132-F-5 (117-F Filter Building) and 116-F-7 Seal Pit Water Crib.		
Process Description:	The crib was used to dispose water collected in exhaust system filter seal pits in the 117-F Ventilation Exhaust Filter Building (132-F-5). The 117-F facility filtered ventilation air from the confinement zone of the 105-F Reactor Building prior to its discharge to the atmosphere through the 105-F Reactor Building Stack.		
Waste Type:	Process Effluent		
Waste Description:	The site received drainage from confinement exhaust system filter seal pits in the 117-F Building.		
	UNI-946 states that boring 7-A appears to have been drilled very close to the center of the crib and a sample was collected at a depth of 3 meters (10 feet). Analysis of this material shows concentrations of 0.032 picocuries/gram for cesium-137, 0.057 picocuries/gram for strontium-90, 0.1 picocuries/gram for plutonium-239/240, and 0.26 picocuries/gram for europium-152.		

This Site has the Following SubSites:

Code: 116-F-7:1
Names: 116-F-7:1; 117-F Crib; 116-F-7 Crib; 116-F-7 Seal Pit Water Crib

Code: 116-F-7:2
Names: 116-F-7:2; 117-F Crib Pipeline; 116-F-7 Crib Pipeline; 116-F-7 Seal Pit Water Crib Pipeline

Code: 116-F-7:1 **Classification:** Accepted
Names: 116-F-7:1; 117-F Crib; 116-F-7 Crib; 116-F-7 Seal Pit Water Crib **Reclassification** Interim No Action (2/15/2005)
Type: Crib **Start Date:**
Status: Inactive **End Date:**

Description: Subsite 1 was evaluated and determined to require No Action. It consisted of the 116-F-7 Seal Pit Water Crib. The crib was marked by a 122 centimeter (48 in) diameter steel vent pipe.

Location: The site was located 137 meters (450 ft) south of the southwestern corner of 105-F Building.

Process Description: The crib was used to dispose water collected in exhaust system filter seal pits in the 117-F Ventilation Exhaust Filter Building (132-F-5). The 117-F facility filtered ventilation air from the confinement zone of the 105-F Reactor Building prior to its discharge to the atmosphere through the 105-F Reactor Building Stack.

Waste Type: Not Specified

Waste Description: The waste would be the crib structure and soil contaminated from the material entering the crib via the pipeline.

Closure Info: Interim: A site evaluation was conducted as part of the Remaining Sites Verification Package (RSVP) attached to the Reclassification Form 2004-128 through field observations and focused sampling and analysis for the purpose of determining if hazardous or radiological contaminants were present. One test pit was excavated to the bottom of the seal pit water crib structure to a depth of 5.8 meters (19 feet). Soil was collected from the pit sample and combined into a composite sample. Four samples were collected at the site on October 12, 2004. A sample of pipe scale from the nonfriable asbestos-cement pipe (subsite 116-F-7:2), a crib soil composite sample, a duplicate sample in the native soil below the gravel, and an equipment blank sample.

Confirmatory sample results found the values of all of the contaminants of potential concern were below remedial action limits. Therefore, nor remedial action was required.

The SubSite is Part Of:

Code: 116-F-7
Names: 116-F-7; 116-F-7 Seal Pit Water Crib and Pipeline; 117-F Crib and Pipeline

Code: 116-F-7:2 **Classification:** Accepted
Names: 116-F-7:2; 117-F Crib Pipeline; 116-F-7 Crib Pipeline; 116-F-7 Seal Pit Water Crib Pipeline **Reclassification** Interim No Action (11/14/2005)
Type: Crib **Start Date:**
Status: Inactive **End Date:**

Description: Subsite 2 was evaluated and determined to require No Action. It consisted of the waste transfer pipeline that originated at the 132-F-5 (117-F Filter Building) and terminated at the 116-F-7 Seal Pit Water Crib.

Location: The pipeline ran south from the 132-F-5 filter building to the 116-F-7:1 seal pit crib.

Process Description: The 10-centimeter (4 inch) diameter, Asbestos-Cement pipeline was used to transfer water from the 132-F-5 (117-F Filter Building) sump pump discharge to the 116-F-7 Seal Water Crib about 168 meters (550 feet) south of the building. The pipeline drained into a perforated distributor pipe in the 116-F-7 crib, a total distance of about 185 meters (607 feet). The vented pipeline was fed from a sump pump and sloped for gravity drain with an average depth of about 1.5 meters (5 feet) below grade.

Waste Type: Not Specified

Waste Description: The waste consists of the piping, and underlying soil.

Closure Info: Interim: The 132-F-5 (117-F Filter Building) was reclassified as "No Action" based on a ResRad evaluation of the Allowable Residual Contamination Level (ARCL) information. The 132-F-5 Filter Building and the 116-F-7 Seal Pit Water Crib and pipeline waste sites have been evaluated and reclassified to "No Action".

The fine soil at the top of the crib soil column had greater sorption capabilities for the contaminants of potential concern than either the 4 inch to 6 inch cobble fill in the crib or the asbestos-cement piping. The 116-F-7 influent pipeline was made of asbestos-cement, which had less surface area than surface soils and did not adsorb ionic contaminants nor filter as effectively as fine soil particles. The soil analyses showed the crib and its internal piping met the cleanup standards. Because the pipeline was composed of the same material as in the crib and was exposed to the same waste stream. Therefore, a reclassification to "No Action" WIDS is appropriate for the pipeline subsite.

The absence of either detectable radiation reading or pipeline scaling indicates a low risk of significant contamination within the pipeline. The influent pipe is deemed to be a lower risk for contamination than within the crib since it has a lower sorptive or filtering capability. As such, the influent pipeline was recommended for reclassification to a "No Action", as a subsite of the 116-F-7 crib. The reclassification form 2005-044 was signed in November 2005.

The SubSite is Part Of:

Code: 116-F-7

Names: 116-F-7; 116-F-7 Seal Pit Water Crib and Pipeline; 117-F Crib and Pipeline

Code: 116-F-8

Classification: Accepted

Names: 116-F-8; 1904-F Outfall Structure

Reclassification: Interim Closed Out (9/25/2006)

Type: Outfall

Start Date: 1/1/1945

Status: Inactive

End Date: 1/1/1965

Description: The site has been remediated and Interim Closed Out. This site consisted of an open-topped, compartmentalized, reinforced concrete outfall structure. A 183 centimeter (72 inch) diameter steel retention basin pipeline entered the south face and two 107 centimeter (42 inch) pipelines exited the north face to the river.

Location: The site was located approximately 214 meters (700 feet) northeast of the 107-F Retention Basin, near the shore of the Columbia River.

Related Sites/Structures: The site was associated with the 116-F-14 (107-F Retention Basin) and the 116-F-16 Pacific Northwest Laboratory (PNL) Outfall Structure. The outfall discharged effluent to the 100-F-39 River Effluent Pipelines and/or 100-F-42 Flume.

Process Description: The outfall was designed as an open concrete structure for discharging reactor effluent cooling water from the 116-F-14 (107-F Retention Basin) to the center of Columbia River via 100-F-39

river pipelines. The outfall was constructed of a reinforced, compartmentalized concrete weir box, with walls extending from 7.6 meters (25 feet) below grade and 0.3 meters (1 foot) above grade. This unit was also connected to the Pacific Northwest Laboratory (PNL) Outfall (116-F-16) by a distribution box. The north effluent discharge consisted of two 107 centimeter (42-inch) diameter pipes. The second was a spillway flume (100-F-42) that ran from the outfall chamber, down the riverbank, and emptied into the river. The flume was constructed of reinforced concrete and was 4 by 0.6 meters (14 by 2 feet) deep and about 40 meters (130 feet) long. The spillway was designed to prevent excessive backwater at the 107-F Retention Basin during high water or in the event of a blockage of the outfall lines. Piping for the 116-F-8 outfall included two 107 centimeter (42 inch)-diameter by 139 meter (455 feet) steel effluent pipelines that exited the northeast side of the outfall and extended into the Columbia River. Two pipelines entered the south side of the outfall from the 107-F Retention Basin. One was a 152 centimeter (60 inch) diameter pipe. The other was a 91 centimeter (36 inch)-diameter pipe.

Waste Type: Construction Debris

Waste Description: Reactor water from the 107-F Basin was piped to the outfall structure that discharged into the Columbia River. The outfall could have also received reactor water that had been diverted for fish studies and other process wastes from the Experimental Animal Farm. Contaminants of concern include cobalt-60, europium-152, europium-154, europium-155, and hexavalent chromium. Other contaminants of potential concern include carbon-14, cesium-137, nickel-63, and strontium-90.

Closure Info: Interim: The 100-F-42 Spillway was administratively separated from the 116-F-8 Outfall for inclusion within the Remaining Sites ROD by agreement among the Tri-Parties. It was subsequently determined that sufficient evidence existed to warrant remedial action during remediation of the 116-F-8 waste site, therefore both waste sites were remediated and evaluated as a single unit.

Remedial action activities at the waste sites were conducted from August 31, 2004, to September 22, 2005. Remediation involved excavation and staging of clean overburden material and removal of the demolished concrete outfall structure, the concrete spillway structure above the Columbia River ordinary high water mark, and contaminated soil to the extent required to satisfy the RAOs and corresponding RAGs. The residual 100-F-39 effluent pipelines will be sealed with concrete prior to backfill of the remediation footprint. Contaminated materials were disposed at the ERDF. Approximately 1,325 square meters (14,260 square feet) of plan area was excavated, including excavation within the deep zone (greater than 4.6 meters [15 feet] below ground surface) up to 8 meters (26 feet) below ground surface. Approximately 4,900 metric tons (5,400 U.S. tons) of material from the sites was removed and disposed at the ERDF.

Code: 116-F-9	Classification: Accepted
Names: 116-F-9; Animal Waste Leaching Trench	Reclassification: Final Closed Out (10/28/2015)
Type: Trench	Start Date: 1/1/1963
Status: Inactive	End Date: 1/1/1976

Description: The site has been remediated, Interim Closed Out and later Final Closed Out. The site was a leaching trench that received waste water from the cleaning of animal pens in the Experimental Animal Farm. The pipelines that originated at the 141-C Building and terminated at the trench are documented in sitecode 100-F-29.

Location: The site was located approximately 46 meters (150 feet) northeast of the 107-F Retention Basin.

Release Description: An unplanned release that occurred in 1955 created what was known as the "basin leak ditch" (see UPR-100-F-2). This release formed a ditch that crossed the animal waste trench site from

west to east.

**Related Sites/
Structures:** The site received wash waste water from the 141-C Animal Barn and the 141-N Animal Waste Collection Facility. Pipelines to the trench are included in site 100-F-29 100 F Experimental Animal Farm Process Sewer Pipelines.

**Process
Description:** During the time that Experimental Animal Farm was active, animal pens housed the animals used for experimental purposes. When the pens were cleaned, waste water containing animal wastes was flushed to the 116-F-9 Animal Waste Leaching Trench.

Waste Type: Soil

**Waste
Description:** Contaminants found during sampling in 1979 included cesium-137, cobalt-60, europium-152, europium-154, europium-155, strontium-90, plutonium-238, plutonium-239/240. The total estimated radioactive inventory (1979) of the 116-F-9 Animal Leach Trench contaminated soil column was 4.1 curies (See Memorandum from V. R. Richards to J. J. Dorian).

Waste Type: Animal Waste

**Waste
Description:** The site received wash waste water from the cleaning of animal pens.

Closure Info: Interim (10/16/2002): (Interim Closed Out) Remedial action objectives and goals for the 116-F-9 site were established by the U.S. Environmental Protection Agency and the Washington State Department of Ecology, in concurrence with the U.S. Department of Energy, Richland Operations Office. These goals and objectives are documented in the Amendment to the Interim Action Record of Decision for the 100-BC-1, 100-DR-1, and 100-HR-1 Operable Units (ROD) (EPA 1997) and the Remedial Design Report/Remedial Action Work Plan for the 100 Area (DOE/RL-96-17).

Remedial action at the 116-F-9 site included (1) excavating the site to the extent required to meet specified soil cleanup levels, (2) disposing of contaminated excavation materials at the Environmental Restoration Disposal Facility (ERDF) at the 200 Areas of the Hanford Site, and (3) backfilling the site with clean soil to average adjacent grade elevation. Excavation was driven by remedial action objectives for direct exposure, protection of groundwater, and protection of the Columbia River.

Remedial action at the 116-F-9 site began on September 4, 2001. Excavation of the site involved removing the overburden materials and underlying contaminated soil. Contaminated materials were disposed of at the ERDF. On March 25, 2002, the excavation was completed. The elevation of the bottom of the excavation was 120.3 meters (394.7 ft) upon completion. The excavation was approximately 5,484 square meters (59,029 sq ft) in area with a depth of approximately 5.7 meters (19 ft). Approximately 49,405 metric tons (54,460 tons) of material from the site were disposed of at ERDF.

Final (10/28/2015): (Final Closed Out) Thirteen 100-F Area waste sites were reclassified to Final Closed out on form 2015-078. They had all previously been classified as Interim Closed Out. The waste sites included on this reclassification form are 100-F-10, 100-F-19 (and subsites 1,2 and 3), 100-F-29, 100-F-34, 116-F-2, 116-F-6, 116-F-9, 116-F-12, subsites 118-F-8:3 and :4, UPR-100-F-1. The Record of Decision (ROD) for the 100-FR-1, 100-FR-2, 100-FR-3, 100-IU-1, 100-IU-2 and 100-IU-6 Operable Units has defined these waste sites as all requiring institutional controls to restrict excavation into the deep zone (greater than 4.6 meters or 15 feet below the ground surface). However, no further remedial actions are required.

Institutional Control Boundaries have been defined to be broadly inclusive of waste site groups. Not all areas within these boundaries contain residual contamination greater than 4.6 meters (15 ft) below ground surface. An image of four Institutional Control Boundaries inside 100F Area was attached to the 2015-078 Reclassification form (and included in the WIDS library).

Code: 116-F-10 **Classification:** Accepted
Names: 116-F-10; 116-F-8; Perf Decontamination Drain; 105 Dummy/Perf Decontamination Crib; 105-F Dummy Decontamination French Drain **Reclassification** Interim Closed Out (6/14/2003)
Type: French Drain **Start Date:** 1/1/1948
Status: Inactive **End Date:** 1/1/1965

Description: The waste site has been remediated and Interim Closed Out. The site consisted of a vitrified clay pipe placed in the ground vertically with approximately 3.0 meters (10 feet) of sand and gravel beneath the tile. The site also included a 10.16-centimeter (4-inch) steel feed pipeline located about 1.2 meters (4 feet) below grade. This pipeline terminated at the "Wash Pad" located in the southeast corner of the 105-F Building fuels storage basin.

Location: The site was located approximately 50 meters (140 feet) south of the 105-F Building.

Related Sites/ Structures: The site was associated with the 105-F Building and 116-F-3.

Process Description: The 116-F-10, 105-F Dummy Decontamination French Drain was used to dispose of decontamination fluids derived from the decontamination of dummy fuel element spacers and other reactor hardware.

Waste Type: Process Effluent

Waste Description: The site received radioactive water rinses and spent nitric acid from the decontamination of fuel element spacers and other reactor hardware, primarily pressure tube caps. In addition, the site received liquid waste containing 2000 kilograms (4400 pounds) of sodium dichromate, 2000 kilograms (4400 pounds) of sodium oxalate, and 2000 kilograms (4400 pounds) of sodium sulfamate. The site may have received other chemicals as well. Known decontamination solutions at 100-F included chromic acid, citric acid, oxalic acid, sulfamic acid, sulfuric acid, and sodium fluoride. Other chemicals, including organic solvents, were also used for some decontamination processes. Three soil borings were drilled in the vicinity of the drain in 1975 (Dorian and Richards 1978). Boring 10-A was drilled next to the tile pipe, and borings 10-B and 10-C were completed approximately 3 meters (10 feet) and 9 meters (30 feet) east of the tile pipe respectively. Samples were collected from these borings at depths ranging from 3.8 to 8.2 meters (12.5 to 27 feet). Analytical results indicated elevated concentrations of cobalt-60 (610 picocuries/gram), europium-152 (250 picocuries/gram), europium-154 (31 picocuries/gram), europium-155 (100 picocuries/gram), and cesium-137 (7.4 picocuries/gram) in boring 10-B. Elevated concentrations were not detected in the samples from borings 10-A and 10-C.

Closure Info: Interim: The selected remedial action for the 116-F-10 site included (1) excavating the site to the extent required to meet specified soil cleanup levels, (2) disposing of contaminated excavation materials at the Environmental Restoration Disposal Facility (ERDF) at the 200 Areas of the Hanford Site, and (3) backfilling the site with clean soil to the average adjacent grade elevation. Excavation was driven by remedial action objectives for direct exposure, protection of groundwater, and protection of the Columbia River.

At the completion of remedial action, the total excavation was approximately 195 square meters (2,100 square feet) in area with a depth of approximately 4.4 meters (14.4 feet). Approximately 848 metric tons (935 tons) of material from the site were disposed of at the Environmental Restoration Disposal Facility.

The site also included a 10-centimeter (4-inch)-diameter steel pipeline that discharged into the

french drain about 1.2 meters (4 feet) below grade. This pipeline originated at the wash pad located in the southeast corner of the 105-F Building Fuel Storage Basin. The pipe ran to the northwest 9 meters (30 feet) and then entered the 116-F-3 excavation. The 10 centimeter (4 inch) diameter steel pipeline was removed without excavation during remediation of the fuel storage basin and the 116-F-10 French Drain and 116-F-3 Storage Basin Trench waste sites. Field screening indicated there was no contamination in the pipeline, and the area was not included in the final cleanup verification sampling design. Because the two associated waste sites (116-F-3 and 116-F-10) were verified clean as shallow zone sites, and the ends of the pipes originally terminated within the boundaries of these excavations, it can be concluded that the short distance between was also clean. This strategy was approved by the regulators.

Code:	116-F-11	Classification:	Accepted
Names:	116-F-11; 105-F Cushion Corridor French Drain	Reclassification	Interim Closed Out (9/15/2003)
Type:	French Drain	Start Date:	1/1/1953
Status:	Inactive	End Date:	1/1/1965
Description:	The site has been remediated and Interim Closed Out. It was a 0.9-meter (3-foot) diameter tile pipe was buried vertically with 2.5 to 5 centimeters (1 to 2 inches) extending above grade. The pipe had a metal lid.		
Location:	The site was located at the southeast corner of the 105-F Reactor Building. It was co-located with the 100-F-19:2 pipelines.		
Related Sites/ Structures:	The french drain was associated with 105-F reactor.		
Process Description:	The cushion corridor french drain received liquid decontamination waste from the cushion corridor area of the reactor. Contaminated liquids were generated when reactor hardware was decontaminated on the concrete floor in the cushion corridor and the decontamination solutions were flushed through a floor-level wall opening drain into the french drain.		
Waste Type:	Process Effluent		
Waste Description:	The site received liquid decontamination wastes from the cushion corridor area when reactor hardware was decontaminated. Boring 105-F-A was completed in this area in 1975 (Dorian and Richards 1978). The boring was drilled to a depth of 2.4 meters (8 feet) before terminating due to a concrete obstruction. A soil sample was collected at a depth of 1.5 meters (5 feet) and radionuclide concentrations varied from 0.01 to 5.6 picocuries per gram. Since this boring is approximately 30 meters (100 feet) away from 116-F-11, these results are not likely to be representative of soils near this waste unit.		
Closure Info:	Interim: (Interim Closed Out) Remedial Action ran from August 2001 until December 2002. The 100-F-19:2 Reactor Cooling Water Effluent Pipeline and co-located sites, (116-F-11 Cushion Corridor French Drain, UPR-100-F-1 Sewer Line Leak, and the 100-F-29 Experimental Animal Farm Pipelines), were remediated as a group and documented in CVP-2001-00003. The group is referred to as the 100-F-19:2 site in the document. The unplanned release was within the footprint of the 100-F-29 pipeline excavation. The elevation of the bottom of the excavation was approximately 124.7 meters (409 ft) upon completion. The excavation area was approximately 19,000 square meters (205,000 sq. ft) with a maximum depth of approximately 5 meters (16 ft) and an average depth of approximately 3.7 meters (13 ft). Removal of the 100-F-29 pipelines near the northwest corner of the 116-F-14 (107-F Retention Basin) required shallower excavation, averaging approximately 1 meter (3 ft) in depth. Little evidence of the 116-F-11 french drain site was found during excavation of the 100-F-19:2 pipelines. The location of the french drain was excavated and sampled to the design elevation 4.6 meters (15 ft).		

Remediation included excavation of overburden, piping, debris and contaminated underlying soil. Approximately 39,347 metric tons (43,373 tons) of material including soil, debris and piping were removed and disposed at ERDF.

Code: 116-F-12	Classification: Accepted
Names: 116-F-12; 148-F French Drain	Reclassification: Final Closed Out (10/28/2015)
Type: French Drain	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1964

Description: The site has been remediated, Interim Closed Out and later Final Closed Out. The drain was excavated during the removal of the 100-F-19:1 effluent pipelines.

Location: The site was located approximately 300 feet (90 meters) north of the northwest corner of the 107-F Retention Basin (116-F-14).

Related Sites/ Structures: The site received pump prime from the 148-F Pump House and Lift Station. The 148-F French Drain was located about 2.4 meters (8 feet) east of the 148-F Pump House.

Process Description: The 116-F-12 French Drain was used to dispose of effluent pump prime recovered from the 148-F Pumphouse.

Waste Type: Water

Waste Description: This drain would have received minimal amounts of leakage or spillage from two pumps located in the facility that were used to supply reactor cooling water to the fish studies facilities. Although Stenner, et al (PNL-6456) states that the site received recovered effluent pump prime, drawings (H-1-459-VOID and H-1-1518) indicate that the site could not have received any effluent except leakage or spillage from maintenance activities on the pumps.

Closure Info: Interim (5/22/2002): (Interim Closed Out) The 100-F-19:1 North Pipelines, 100-F-19:3 West Pipelines, 100-F-34 Biology Facility French Drain, and the 116-F-12 French Drain were remediated as a group, documented in CVP-2001-00002. The group is referred to as the 100-F-19:1 site. The 100-F-19:1 site remedial action began on August 7, 2001. Excavation of the site involved removing overburden materials, pipelines, french drain structures, and contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Shallow zone excavation occurred both in the vicinity of the 100-F-19:3 West Pipelines and in the vicinity of the 100-F-19:1 North Pipelines, with a maximum depth of 4.6 meters (15 ft). The deep zone excavation occurred in the southern half of the 100-F-19:1 North Pipelines section of the remedial action, with a approximate maximum depth of 5.0 meters (16 ft). The elevation of the bottom of the excavation varied, but averaged approximately 119.6 meters (392.4 ft). At the completion of remedial action in August 2001, the excavation was approximately 25,710 sq. meters (276,740 sq. ft.) in area. Approximately 56,335 metric tons (62,099 tons) of contaminated materials from the site were disposed of at the ERDF.

These sites meet the cleanup standards specified in the Amendment to the Interim Action Record of Decision for the 100-BC-1, 100-DR-1, and Operable Units (ROD). Excavation of the site involved removing overburden materials, pipelines, french drain structures, and contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Shallow zone excavation occurred both in the vicinity of the 100-F-19:3 West Pipelines and in the vicinity of the 100-F-19:1 North Pipelines, with a maximum depth of 4.6 meters (15 ft). The deep zone excavation occurred in the southern half of the 100-F-19:1 North Pipelines section of the remedial action, with a approximate maximum depth of 5.0 m (16 ft). The elevation of the bottom of the excavation

varied, but averaged approximately 119.6 m (392.4 ft).

The results showed that the materials from the 100-F-19:3 subsite containing COCs at concentrations exceeding RAGs have been excavated and disposed of. Remedial actions were performed so as to allow rural-residential use of shallow zone soils (i.e., surface to 4.6 meters [15 feet] deep) and to protect groundwater and the Columbia River. All cleanup verification samples for the 100-F-19:3, 100-F-34 and 116-F-12 sites are listed under 100-F-19:1.

Final (10/28/2015): (Final Closed Out) Thirteen 100-F Area waste sites were reclassified to Final Closed out on form 2015-078. They had all previously been classified as Interim Closed Out. The waste sites included on this reclassification form are 100-F-10, 100-F-19 (and subsites 1,2 and 3), 100-F-29, 100-F-34, 116-F-2, 116-F-6, 116-F-9, 116-F-12, subsites 118-F-8:3 and :4, UPR-100-F-1. The Record of Decision (ROD) for the 100-FR-1, 100-FR-2, 100-FR-3, 100-IU-1, 100-IU-2 and 100-IU-6 Operable Units has defined these waste sites as all requiring institutional controls to restrict excavation into the deep zone (greater than 4.6 meters or 15 feet below the ground surface). However, no further remedial actions are required.

Institutional Control Boundaries have been defined to be broadly inclusive of waste site groups. Not all areas within these boundaries contain residual contamination greater than 4.6 meters (15 ft) below ground surface. An image of four Institutional Control Boundaries inside 100F Area was attached to the 2015-078 Reclassification form (and included in the WIDS library).

Code:	116-F-14	Classification:	Accepted
Names:	116-F-14; 107-F; 107-F Retention Basin	Reclassification	Interim Closed Out (7/12/2002)
Type:	Retention Basin	Start Date:	1/1/1945
Status:	Inactive	End Date:	1/1/1965
Description:	The site has been remediated and Interim Closed Out. The retention basin was a rectangular, concrete-lined, open-top reservoir designed to retain reactor cooling water prior to being discharged to the Columbia River. The basin had an estimated capacity of 5.67E+08 liters (1.5E+08 gallons). It was divided into two equal sections by weir walls running lengthwise from inlet to outlet end. Each section was subdivided by a series of wooden baffles. The site was surrounded by sprinklers (Hanford Drawing H-1-14321) installed on the top of the wall to keep the sludge from drying out during those times when effluent was not being discharged to the basin.		
Location:	The site was located approximately 530 meters (1488 feet) east-northeast of the 105-F Reactor Building.		
Release Description:	Numerous instances of retention basin and pipeline leakage occurred during the operation of the basin resulting in areas of soil contamination. The basin leaked at many locations along its walls and bottom. Hanford Drawing H-1-70247 (Retention Basin Leak Repair) shows some of the many types of repairs performed on the basin, including repairs of vertical cracks in the basin walls, removal of spilled concrete, rebuilding of expansion joint and repairs of cracks in the floor of the basin. The largest recorded leak extended roughly 7.6 meters (25 feet) from the foot of the unit wall. The leak, discovered in the summer of 1952, occurred in the effluent lines leading from the basin to the 148-F Pumphouse. Another release of contamination occurred at a large manhole located north of the 107-F basin (identified as P-22F on Hanford Drawing H-1-13850). Effluent overflowed intermittently for an extended period during the early 1950's before it was stopped. In 1955, water overflowed from the basin and contaminated the soils adjacent to the basin and a narrow path between the basin and the Columbia River. This release was identified as UPR-100-F-2. Contamination levels were 20,000 to 60,000 counts per minute with a maximum of 350 millirads/hour. HW-54636 contains information regarding the ground contamination size and shape. At least once during reactor operations, an unknown quantity of		

sludge was removed from the bottom of the basin and buried approximately 30.5 meters (100 feet) southeast of the southeastern corner of the basin. An estimated 1.8E+06 kilograms (2,000 tons) of sludge remained in the retention basin (Dorian and Richards 1978). In 1952, a hole was dug adjacent to the basin inlet pipe to drain the pipe. The hole and associated soil contamination were stabilized by covering it with clean soil, gravel, and cobbles. In 1964, high winds spread contamination when the basin was emptied and dry for maintenance. Known leakage from the 116-F-14 basin appears to have occurred primarily along the south and west sides. Estimates of leakage rates are not well documented, but the presence of a groundwater mound beneath the basin extended as high as 3 meters (10 feet) above the pre-existing water table elevation, suggests that significant leakage had occurred (Dorian and Richards 1978). The extent of these releases were contained within the AC-5-40 permanent Underground Radioactive Material posting.

Related Sites/ Structures: The site was associated with the 105-F Reactor Building, the 100-F-19 pipeline and the 116-F-2 overflow trench.

Process Description: The site was used as a retention basin to hold the discharged reactor water for a brief period of time, allowing radioactive decay and thermal cooling to occur before the water was discharged to the Columbia River. Effluent was discharged to the basin by way of pipelines that were partially underground and partially above ground. The site received essentially all reactor cooling water passing from the reactor to the Columbia River. The total volume has not been estimated, but the flow rate ranged between 1.55E+05 and 2.95E+05 liters (41,000 and 78,000 gallons) per minute. Water flowed from the north end of the basin through a concrete pipeline to the 116-F-8 Outfall. The site is shown on Hanford drawings H-1-1522, M-1600-F, W-73199, W-69714 and Photo 9005316-1cn.

Waste Type: Water

Waste Description: This site received cooling water effluent from the 105-F Reactor for radioactive decay and thermal cooling prior to release to the Columbia River. Seventy percent of the total radionuclide inventory was contained within the soil adjacent to the basin.

Waste Type: Demolition and Inert Waste

Waste Description: This site received cooling water effluent from the 105-F Reactor and held it to allow radioactive decay and thermal cooling prior to releasing the effluent to the Columbia River. Approximately 10 curies of radioactivity had leached into the concrete floor and walls.

Closure Info: Interim: Remedial action began on July 27, 2000. The excavation included removing the overburden, debris and underlying contaminated soil. The majority of the site was completed in September 2001, with additional excavation occurring in October 2001, December 2001 and January 2002.

Site excavation and waste disposal were completed on January 16, 2002, and the exposed surfaces have been sampled and analyzed to verify attainment of the RAGs. At the completion of the remedial action, the total excavation was approximately 20,039 square meters (215,698 sq. ft.) in area with a depth greater than 4.6 meters (15 ft). Approximately 212,015 metric tons (233,707 tons) of material from the site were disposed of at the Environmental Restoration Disposal Facility.

Code: 116-F-15

Classification: Accepted

Names: 116-F-15; 108-F Radiation Crib

Reclassification: Interim Closed Out (5/24/2007)

Type: Sump

Start Date:

Status: Inactive

End Date:

Description: The site has been remediated and Interim Closed Out. The site consisted of 0.9 m by 0.9 m (3 ft by 3-ft) concrete sump near the center of the former 108-F building first floor. The sump system connected to a subgrade (under the building foundation) pipe trench that ran north and south beneath the first floor. The trench was approximately 0.9 meter (3 ft) deep, 0.3 meter (1 ft) wide, and 61 meters (200 ft) long, and drained from both ends into the sump. Many laboratory floor and hood drains were connected to the trench and sump. A 15-cm (6-in.) earthenware pipeline exited the sump and the building to the south. The pipe trench and sump were reportedly removed during D&D activities of the 108-F Biological Laboratory.

Location: The site was located under the excavation of the 108-F Building (site 100-F-36).

Related Sites/Structures: The sump received effluent from the 100-F-36 site glove boxes and floor and hood drains. The sump then emptied into a trench that had the same WIDS site code.

Process Description: The trench drained from both ends into a sump located in approximately the center of the trench. Many laboratory floor and hood drains were connected to the trench and sump. The trench and sump were covered with plywood and posted as radioactive. A 15-centimeter (6-inch) earthenware (vitrified clay) pipeline exited the sump and the building to the south. A continuation drawing (W-2934, sheet 5) that would show the route and destination of the pipeline was no longer available.

Hanford Drawing H-1-2037 showed a 20-centimeter (8-inch) vitrified clay tile pipe that ran south, then east, from the western side of 108-F to the ash pit. Although there was no clear connection between the sump and the pipelines known to run to the ash pit, there was a strong possibility they were interconnected.

Several documents, including Herman, Stenner et al, (1988), Kiser (1988), and Clukey (1954, 1956), discussed sites like this one. If it was a crib, they did not reference as a crib. The noted omission from these documents casts doubt on the existence of this waste site as a crib.

Waste Type: Process Effluent

Waste Description: Prior to 1996, the unit had not been sampled for radiological or chemical contamination. It was known that alpha contamination experiments were conducted in the 108-F Building. The sump was reported to have received liquid wastes from the 108-F Building sinks, glovebox drains, and ventilation hoods. Alpha contamination experiments were conducted at the 108-F Building, therefore the potential for alpha contamination of this waste site exists.

Closure Info: Interim: The 108-F facility became inactive in 1973. From 1977 through 1983, contaminated material was removed from inside the building and disposed in 200 Area burial grounds. The 108-F building was demolished in 1999. The contaminated cast-iron pipe found during the February 2002 excavation was not located during this remedial action. Therefore, an additional test pit was excavated on November 29, 2005, in an attempt to locate the contaminated 15-cm (6-in.) diameter cast-iron pipe. The additional excavation was unsuccessful, and the excavated material was placed back in the pit. Additional efforts in July 2006 to locate the contaminated pipe using a metal detector were also unsuccessful. However, the contaminated 15-cm (6-in.) diameter cast-iron pipe (100-F-26:4) was found during test pitting activities in December 2006. The contaminated pipe is associated with the 100-F-26:4 pipeline site and is not a part of the 116-F-15 sump as previously indicated. Remediation and sampling activities for the 100-F-26:4 pipelines site will be included in a separate verification package.

Remediation of the 116-F-15 waste site was performed on September 26, 2005. It consisted of the removal of approximately 86 metric tons (95 US tons) of material, including concrete debris, piping, and soil being disposed at the Environmental Restoration Disposal Facility. The soil was excavated and field surveyed to a depth of approximately 2.6 meters (8.5 feet).

Following the remediation of 116-F-15, confirmatory sampling at the 100-F-36 waste site was

performed on December 5, 2006 and verification sampling of the 116-F-15 waste site was performed on December 12, 2006.

The 100-F-36 waste site was evaluated and confirmatory samples collected. It was determined to require No Action.

Code:	116-F-16	Classification:	Accepted
Names:	116-F-16; PNL Outfall	Reclassification	Interim Closed Out (9/14/2006)
Type:	Outfall	Start Date:	
Status:	Inactive	End Date:	
Description:	The site has been remediated and Interim Closed Out. This site consisted of an open-topped, compartmentalized, reinforced concrete outfall structure.		
Location:	The site was located approximately 670 meters (2200 feet) northeast of the 105-F Reactor Building and about 15 meters (50 feet) upstream of 116-F-8 outfall.		
Related Sites/ Structures:	The site was associated with 100-F-29 (100-F Experimental Animal Farm Process Sewer Pipelines), 100-F-19, 100-F Reactor Cooling Water Effluent Underground Pipelines, Contaminated Underground Lines, Effluent Water System, 1904-F Process Sewer (See Subsites), the 116-F-8 Outfall Structure, 100-F-43 Flume and 100-F-39 River Lines.		
Process Description:	Animal Sewage and low-level contamination resulting from various Experimental Animal Farm projects, were pumped to the river via the 116-F-16 outfall structure and associated 100-F-43 spillway (flume). The site was a concrete outfall structure that received effluent from the experimental animal farm and aquatic biology laboratory. The Outfall emptied into the 100-F-43 Spillway via direct discharge then into the Columbia River. This unit was connected to the 116-F-8 Outfall Structure by a distribution box. A 183 centimeter (72 inch) diameter pipe extended from the north side of the 107-F Retention Basin, through a diversion box and connected to the south side of the outfall.		
Waste Type:	Construction Debris		
Waste Description:	The unit received animal sewage from various Experimental Animal Farm projects, 107-F Retention Basin water from fish studies, and low-level contamination. The COPCs include Plutonium-239/240, Strontium-90, Cesium-137, Lead, and hexavalent chromium.		
Closure Info:	Interim: The 100-F-43 waste site was administratively separated from the 116-F-16 waste site for future inclusion within the Remaining Sites Record of Decision by agreement among the Tri-Parties. It was subsequently determined that sufficient evidence existed to warrant remedial action of both waste sites as a single unit. All samples collected during remediation are listed under 116-F-16.		

During decommissioning work performed during the 1980's, the portion of the spillway above the river level was demolished and covered with soil. Remedial action activities at the sites were conducted from August 31, 2004, to September 8, 2005. Remediation involved excavation and staging of clean overburden material and removal of the outfall, the concrete spillway structure above the Columbia River ordinary high water mark, and contaminated soil to the extent required to satisfy the RAOs and corresponding RAGs.

Approximately 384 square meters (4,130 square feet) of plan area was excavated, with all remedial activities restricted to the shallow zone (less than 4.6 meters [15 feet] below ground surface). Approximately 2,090 metric tons (2,300 U.S. tons) of contaminated material was removed from the site and disposed at the ERDF.

Code: 126-F-2	Classification: Accepted
Names: 126-F-2; 183-F Clearwells	Reclassification: Interim Closed Out (5/4/2006)
Type: Dumping Area	Start Date: 1/1/1945
Status: Inactive	End Date: 1/1/1965

Description: The waste site has been remediated and Interim Closed Out. It consisted of two covered, reinforced concrete basins (east and west). Originally, the basins were used as part of the cooling water treatment train for the 105-F Reactor from 1944 to 1965. In the late 1970s, the eastern clearwell was used for the disposal of inert debris generated in the demolition of various 100-F Area buildings. Part of the concrete cover on both clearwells had been demolished to permit dumping into the clearwell cavity.

The pump room was reinforced concrete and largely below grade. The above-ground portion of the pump room had been demolished, and the below-ground portion was filled with pump room rubble and backfilled. Approximately 25% of the eastern clearwell basin contained building demolition waste from the 183-F, 185-F, 189-F, 190-F, 115-F and the 108-F buildings.

Location: The site was located north of the 105-F Reactor Building, at the site of the 183-F Water Treatment Facility (demolished).

Related Sites/ Structures: The clearwells were associated with the 183-F Water Treatment Facility.

Process Description: Originally, the basins were used as part of the cooling water treatment train for the 105-F Reactor from 1944 to 1965. The basins had a capacity of about 3.7E+07 liters (1E+07 gallons), they were separated in the center by a pump room. Chemical addition to this point in the treatment train was limited to coagulants (alum and hydrated calcium oxide), pH adjustment (sulfuric acid), and chlorination. Beginning in the 1970's, this site received demolition rubble and inert waste from building demolitions. It received rubble from the 183-F, 190-F, 189-F, 185-F and 171-F buildings.

Waste Type: Demolition and Inert Waste

Waste Description: The unit now contains demolition waste from demolished facilities. This waste includes rubble from the uncontaminated portion of 115-F as well as rubble from such noncontaminated facilities as 183-F, 190-F, 189-F, 185-F, 171-F. The rubble is believed to include asbestos siding tiles from several buildings. The site has been included in the Remaining Sites Record of Decision, and is listed as having "possible low-level radioactive waste."

Closure Info: Interim: Site remediation was performed from July to September 2005 and consisted of the removal of debris within the eastern clearwell structure down to the concrete floor. Radiological surveys and visual inspection of the remediated clearwell structure revealed no residual contamination on the concrete floor or sidewalls and no indication of possible contaminant migration beyond the boundaries of the clearwells. No remediation or investigation was performed at the western clearwell, as no waste materials were disposed there, and the roof of the facility remains intact. Samples of excavated material were collected during remediation to support waste characterization. Following remedial activities, radiological surveys were performed.

Approximately 28,986 metric tons (31,952 U.S. tons) of material was removed and staged at an area adjacent to the clearwells before disposal at the Environmental Restoration Disposal Facility.

Code: 128-F-2	Classification: Accepted
----------------------	---------------------------------

Names: 128-F-2; 100-F Burning Pit **Reclassification** Interim Closed Out (12/1/2008)

Type: Burn Pit **Start Date:** 1/1/1945

Status: Inactive **End Date:** 1/1/1965

Description: The wastes site has been remediated and Interim Closed Out. The burn pit was an irregularly shaped depression that was used for burning wastes. Prior to remediation, the site had been covered and appeared as a flat surface with no sign of the burn pit or its contents. An area appeared to have been filled and leveled in preparation for the installation of well 199-F5-42.

Location: The site was located approximately 30.5 meters (100 feet) east of the northeast corner of the 100-F Area perimeter road which runs along the riverbank. The site is located directly east of the 107-F Retention Basin.

Related Sites/ Structures: An area of residual contamination in Area C remaining after the burn pit remediation was designated as a new site, 100-F-59 Riparian Area Contamination.

Process Description: The 128-F-2, 100-F Burning Pit waste site was an irregularly shaped depression that was used for incinerating nonradioactive, combustible materials (e.g., vegetation, office waste, paint waste, and chemical solvents) from 1945 to 1965.

During Hanford Site cleanup operations in the late 1970s, unknown quantities of debris were removed from the burn pit and the site was backfilled. Historical documentation suggested that multiple burn pits were present at the site, with each pit having the dimensions of 31 by 31 by 3 meters (100 by 100 by 10 ft) deep. According to documentation the waste site was 46 meters (151 ft) by 18 meters (60 ft) and was situated on a steep grade near the shoreline of the Columbia River.

Waste Type: Misc. Trash and Debris

Waste Description: The results of confirmatory sampling were used to determine the COCs and contaminants of potential concern (COPCs) for verification sampling. Metals (including hexavalent chromium and mercury), SVOCs (inclusive of the PAHs detected in confirmatory samples), chlorinated pesticides, TPH, PCBs, and asbestos were considered COCs/COPCs for verification sampling. Additionally, because radiological activity was detected above background levels during confirmatory sampling, laboratory radiological analysis was performed on verification samples to verify the absence of radiological contamination.

Closure Info: Interim: Confirmatory sampling from four test trenches was done in December 2004. Remediation of the site was initially performed August through October 2005, with 21,900 metric tons (24,100 US tons) of material excavated and disposed at the Environmental Restoration Disposal Facility (ERDF). Scrap metal, concrete debris, bottles, laboratory glassware, ash, potentially contaminated soil, asbestos debris, and other miscellaneous materials were removed from the waste site.

Additional debris and ash related to the burn pit waste site was still visible on the Columbia River shoreline beyond the original waste site boundary. Further remediation was conducted in October 2006 that removed material on the riverbank slope. A soil berm was created to protect the area from any water encroachment from the river. In process sample results from October and November 2006 showed residual metal concentrations in the excavated area and soil berm exceeded soil (RAGs). After meeting with the regulatory agency, it was agreed that additional excavation would be conducted on the shoreline below the ordinary high water mark (OHWM). This excavation was completed in February 2007 and was followed by immediate collection of verification samples and gravel stabilization, prior to the onset of higher spring river levels. An agreement with the lead regulatory agency allowed this portion of 128-F-2, along with surrounding sediments with elevated levels of contaminants, to be designated as a new waste site, 100-F-59 (aka Area C).

Excavated materials were sorted and segregated based on visual inspection and location of origin and then staged onsite before disposal at ERDF. Samples of soil and debris were collected as needed to support waste characterization.

On August 19, 2005, soon after the onset of remediation, an area of cultural significance was discovered in the northwestern end of the riverside excavation. The first discovery was a thin concentration of mussel shell and bone fragments in the wall of the excavation. Additional artifacts (subsistence bone, chipped stone tools, knives, several rough stone tools, and trade beads) were discovered on the surface in nearby recently scraped areas on August 22, 2005. During a follow-up inspection on August 29, 2005, a hearth was discovered. The area of cultural significance was excluded from disturbance during remediation activities and was backfilled between February 20 and February 28, 2008.

During the initial 2005 remediation activities, it was observed that debris and ash material extended beyond the excavation design boundaries of the site toward the river shoreline and appeared to be present below the OHWM. Further excavation was delayed until October 2006 to take advantage of lower flows of the Columbia River and avoid impacts to endangered Upper Columbia River (UCR) spring Chinook salmon and steelhead. Remediation continued as Phase II with the excavation of the soil containing debris and ash within the slope extending to the OHWM in October 2006. The remediation proceeded to the shoreline, leaving a low berm to protect against site flooding in the event of higher river stages. Soil samples were collected from the berm to evaluate if it could be left in place or required removal. The data showed individual samples contained levels of hexavalent chromium and lead that exceeded direct exposure RAGs and levels of barium, cadmium, chromium, copper, manganese, mercury, nickel, silver, zinc, PAHs, and PCBs that exceeded the criteria for protection of groundwater and the Columbia River.

Code:	132-F-1	Classification:	Accepted
Names:	132-F-1; 132-F-1 Chronic Feeding Barn; 141-F; 141-F 100-F Experimental Animal Farm Sheep Barn	Reclassification	Interim Closed Out (8/23/2006)
Type:	Laboratory	Start Date:	
Status:	Inactive	End Date:	
Description:	The site has been remediated and Interim Closed Out. The barn has been demolished. When in use, it was an L-shaped concrete block building with a concrete floor and concrete animal pens located both inside and outside of the building. The 141-F building was demolished in 1977.		
Location:	The 141-F (132-F-1) barn site was located in the northeast corner of the 100-F Experimental Animal Farm area. The building site was northwest of the 107-F Retention Basin (116-F-14) and south of the 1904-F Outfall Structure (116-F-8) and the Pacific Northwest Laboratory (PNL) Outfall Structure (116-F-16).		
Related Sites/ Structures:	Drawings indicate that the effluent discharged into the process sewer system (100-F-29) until 1963 then wastewater was diverted to the 116-F-9 Animal Leach Trench.		
Process Description:	Studies involving sheep began in the late 1940's. Up to 1,000 head of sheep were kept in 132-F-1 Barn (141-F) for use in dose studies using iodine-131, strontium-90, plutonium-239, and cesium-137. Most of the work performed involved 20-year lifetime exposure studies. The 141-F Building was one of the main facilities used to house the animals. Animal pens in the building had concrete floors and were connected to the special sewer (100-F-29) for contaminated animal wastes. Contaminated manure and sawdust that could not be shoveled out of the animal pens were washed into the sewer which went to the 141-N Sump. When the sump		

became full, the wastewater was pumped through a screen to the Columbia River via the PNL Outfall (116-F-16). The solids trapped by the screen were dried and sent to the 118-F-5 Sawdust Pit. The Remedial Investigation/Feasibility Study Work Plan for the 100-FR-1 Operable Unit, Hanford Site, Richland, Washington states that wash water from this facility went to the 1607-F6 septic system. A review of Hanford Site historical drawings H-1-13850 (sheets 2 and 3) and M-1904-F (sheet 5) and conditions encountered during remediation of the 132-F-1 site do not indicate piping between the 132-F-1 site and the 1607-F6 septic system. The drawings show that the only outgoing line [a 15 centimeter (6 inch) vitrified clay pipe] from the building discharged into the process sewer system (100-F-29) until 1963, when wastewater was diverted to the 116-F-9 Animal Leach Trench.

Waste Type: Demolition and Inert Waste

Waste Description: Residual strontium-90, cesium-137, and plutonium-239 contamination may remain in any buried debris.

Closure Info: Interim: Confirmatory samples were collected from a test trench in September 2004. Only Strontium-90 was detected above remedial action goals. Low levels of polycyclic aromatic hydrocarbons were detected.

Remedial excavation began August 9, 2005 and continued through August 12, 2005. The concrete foundation, debris and piping were removed to a depth of approximately 1 meter (3 feet). A total of approximately 3,400 bank cubic meters (4,400 bank cubic yards) of soil and debris was excavated and staged onsite before disposal at the Environmental Restoration Disposal Facility. Strontium-90 was detected above remedial action goals in the cast iron piping. After remediation, the site existed as a shallow (approximately 1 meter [3 feet] deep) excavation. Excavation southeast of the former building footprint depth was extended up to 2.4 meters (8 feet) below ground surface (bgs) before native material was encountered, and no debris.

Code: 132-F-3	Classification: Accepted
Names: 132-F-3; 115-F Gas Recirculating Facility	Reclassification: Interim No Action (12/9/2003)
Type: Burial Ground	Start Date: 1/1/1943
Status: Inactive	End Date: 1/1/1965

Description: The site has been evaluated and determined to require No Action. This site was the below grade remaining material from the decommissioning of the 115-F Gas Recirculation Facility. The building was demolished in-situ using Allowable Residual Contamination Level (ARCL) methodology. At present, the site looks like a gravel parking lot that is free of any debris.

Location: The site was located approximately 61 meters (200 feet) due west of 105-F Building.

Process Description: The gas recirculation facility was a single-story concrete building that housed the reactor inert gas processing and recirculation system. The gas system continuously recirculated a large volume of gas at very low pressure. The recirculation cycle included cooling, drying, and filtering of the gas prior to reentry into the reactor. The purpose of the reactor inert gas system was to provide a closed-loop nonreactive gas environment in the graphite core that would remove moisture and gases from the core and serve as a heat transfer medium between the graphite core and the process tubes. The system also served to detect water leaks within the reactor core. When a leak was detected, the gas was routed to the ventilation exhaust system. Filters, gas coolers, blowers, condensers, and silica gel drying towers were located within the 115-F Building. The system was designed to maintain gas pressure in the reactor at a slightly positive value with respect to the ventilation air so that the air could not make contact with the graphite core. Contamination of the 115-F Building occurred on the inside surfaces of ducts,

concrete surfaces, machinery, and filters, as indicated by analysis of smear samples taken from these surfaces. The tunnels that connected the 115-F Building to the 105-F Reactor Building were also radioactively contaminated. When in operation, the site was a single-story, reinforced concrete structure, 6.1 meters (20 feet) high. The unit's dimensions were 51.2 meters (168 feet) long, 29.9 meters (98 feet) wide, with 4.0 meters (13 feet) below grade. An operating gallery extended down the center and was flanked on either side by cells that contained the gas processing equipment. The equipment cell walls and floors were 0.9 meters (3 feet) thick. At right angles to the operating gallery and extending across the full width of the west end was the service section, which contained the ventilation fan, air compressor, office, locker room, etc. A pipe tunnel 11.0 meters (36 feet) wide by 2.4 meters (8 feet) high ran beneath the full length of the building. The main gas lines to and from the 105-F Building entered through this tunnel.

Waste Type: Demolition and Inert Waste

Waste Description: The resident radionuclides are tritium, carbon-14, cobalt-60, strontium-90, cesium-137. Surface smears taken in the facility over a 100-square centimeter (15.5-square inch) area revealed alpha contamination of less than 200 disintegrations per minute (dpm) on all surfaces tested. The maximum direct reading of 15,000 counts per minute (cpm) was recorded in the east end of the piping tunnel that connected the gas recirculation facility to the reactor (Chattin and Powers 1985).

Closure Info: Interim: The 115-F Gas Recirculation Facility decommissioning activities began in July 1984 and were completed in October 1984. The above ground debris and rubble were trucked to the 100-F Clearwell for disposal. The below grade perimeter walls, which extended 4.0 meters (13 feet) below grade, were demolished to 0.9 to 1.2 meters (3 feet to 4 feet) below grade. The remaining walls and piping tunnel were left intact and served as containment for the building rubble. Equipment was removed from the drier/blower cells, packaged, and buried in the 200 West Area Burial Ground. The entire area was covered with clean backfill material. This overburden averaged 1.2 to 1.5 meters (4 to 5 feet) in depth, which exceeded the ARCL requirements of 1 meter (3.3 feet) of clean fill. In addition, grading the final site to be compatible with the surrounding terrain added another 0.9 to 1.2 meters (3 to 4 feet) of clean backfill.

A "No Action" decision is supported based on reviews of the facility information, historical data, and modeling results (ARCL and RESRAD) as summarized below. As part of facility decommissioning activities, contaminated piping and equipment were removed from the facility and shipped to the Hanford 200 Area for disposal. Uncontaminated material and rubble was sent to the 183-F clear wells for disposal. Only the concrete floor surfaces of the facility were contaminated. In these areas, contamination did not penetrate the concrete surface more than 1 cm (0.4 in.). Using conservative inputs (e.g., highest activity sample results, uniform contamination levels over 100% of exposed surfaces), the ARCL and RESRAD outputs indicate that residual contamination levels do not present an unacceptable risk to the maximally exposed individual. In addition, the RESRAD model results indicate that the residual contamination levels are protective of groundwater and the Columbia River. Excavation of the site to collect more information is not cost effective and is not likely to result in a change to the no action interim closure decision for the 132-F-3 site.

Code: 132-F-4	Classification: Accepted
Names: 132-F-4; 132-F-4 Reactor Stack Demolition Site; 116-F Reactor Exhaust Stack; 116-F Reactor Stack	Reclassification: Interim No Action (11/14/2005)
Type: Burial Ground	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1965

- Description:** The site consists of two subsites: one is the 116-F Reactor Stack and Subsite 2 is the stack's octagon-shaped base. Both subsites have been evaluated and determined to require No Action, so the parent site is also considered No Action. The site is a cobble covered field next to the 105-F Reactor Building.
- Location:** The stack was located just west of the 105-F Reactor Building. The stack was demolished into a trench extending west from the stack's original location.
- Related Sites/ Structures:** Following completion of the confinement project in 1960, the air was diverted via underground, reinforced concrete ducts to the 117-F Filter Building. After flowing through the filters, the air went through below-grade and above-grade concrete ducts and into the exhaust stack.
- Process Description:** The stack was used to dispose of confinement air that originated from the work areas in the 105-F Reactor Building. The clean air entered the non-contaminated portions of the reactor building, then through zones with increasing levels of contamination, and finally entered the filter building where air passed through "absolute" (particulate) and "halogen" (activated charcoal) filters. The filtered air then vented through the 61-meter (200-foot) stack and discharged into the atmosphere.
- Waste Type:** Demolition and Inert Waste
- Waste Description:** The estimated radionuclide inventory for the 116-F Stack prior to demolition was 5.0 picocuries/gram. This amount was calculated from the concentration of nuclides over the interior of the stack to a depth of 1 centimeter (0.39 inches). The radionuclides found were tritium, carbon-14, cobalt-60, strontium-90, cesium-137, europium-152, and plutonium-239.

Testing performed on several of the reactor stacks in the 100 Area prior to decommissioning showed that the stacks contained residual quantities of radionuclide materials on their interior surfaces. Standard smear testing performed over a 100-square centimeter (15.5-square inch) area on these surfaces showed the presence of tritium at concentrations of 400 to 13,000 picocuries per square centimeter and carbon-14 at concentrations of 200 to 2.1E+07 picocuries per square centimeter (Dorian and Richards 1978). Beta-gamma activity from other radionuclides was also identified.

This Site has the Following SubSites:

- Code:** 132-F-4:1
Names: 132-F-4:1; 116-F Reactor Stack Demolition Site
- Code:** 132-F-4:2
Names: 132-F-4:2; 116-F Reactor Stack Base Burial

- | | |
|--|--|
| Code: 132-F-4:1 | Classification: Accepted |
| Names: 132-F-4:1; 116-F Reactor Stack Demolition Site | Reclassification: Interim No Action (12/8/2003) |
| Type: Burial Ground | Start Date: |
| Status: Inactive | End Date: |

Description: The demolished 116-F Stack Demolition Site has been evaluated and determined to require No Action. It is the location of the buried rubble from the demolished stack. The stack a reinforced concrete structure, 61 meters (200 feet) high with a base diameter of 5.05 meters (16.58 feet) and a maximum thickness of 0.46 meters (18 inches) at the base. The interior of the unit contained 4.2 microcuries of radioactive materials. The stack was demolished by explosive demolition in 1983 and laid into a trench. It was then was broken into pieces smaller than 1 meter (3 feet) in diameter. All of the loose rubble was pushed into the trench and backfilled. The area was graded to match the surrounding terrain.

Closure Info: Interim: Radiological surveys were done in 1980 and 1983. Characterization concrete samples were collected in 1983. The contamination penetrated only a thin layer of the concrete. Prior to demolition, contaminated sand was vacuumed from the bottom of the stack. The interior of the stack was coated with a substance to adhere any residual contamination to the walls of the stack. The stack was demolished in September 1983 and buried in a trench located between the 117-F Building Site and the 115-F Building Site. The trench was backfilled and covered with a 1 meter (3 foot) layer of soil.

The "No Action" decision is supported based on reviews of the facility information, historical data, and modeling results (ARCL and RESRAD) showing that residual risk is within the bounds established for unrestricted land use. Results used in the ARCL and RESRAD modeling were from the pre-decontamination concrete sample collected at the elevation of the intake duct. The sample elevation was where the highest contaminant levels would be expected and where the highest direct readings were observed during pre-decontamination radiological surveys conducted in 1980. These contaminant levels were modeled over 100% of the inner surface area. Consistent with what would be expected, the contamination did not significantly penetrate the inner concrete surface of the stack. Based on the concrete samples, penetration of contaminants was estimated to be 0.1 to 0.2 cm (0.04 to 0.79 in.), while thickness of the stack wall was up to 46 cm (18 in). Conservative penetration depth of 0.95 cm (0.37 in.) was used to calculate the as-buried contaminated zone thickness. Excavation of the disposal trench to collect more information is not likely to result in a change to the no action interim closure decision for the 132-F-4 site.

The SubSite is Part Of:

Code: 132-F-4

Names: 132-F-4; 132-F-4 Reactor Stack Demolition Site; 116-F Reactor Exhaust Stack; 116-F Reactor Stack

Code: 132-F-4:2

Classification: Accepted

Names: 132-F-4:2; 116-F Reactor Stack Base Burial

Reclassification: Interim No Action (11/14/2005)

Type: Burial Ground

Start Date:

Status: Inactive

End Date:

Description: The subsite has been evaluated and determined to require No Action. Subsite 2 consisted of the (116-F) Reactor Stack Base. The monolithic concrete stack base and foundation included an imbedded stack condensate drain line. The 116-F stack base burial site has a separate waste site boundary about 0.5 meters (1.5 feet) east of 116-F stack burial site. The reclassification of this site was based on the CVP-2005-00003 document for the 105-D Reactor stack base. The two waste sites are analogous.

Closure Info: Interim: The reclassification of this waste site is documented on form 2005-043. This stack base (132-F-4:2) is analogous to the stack base at 105-D reactor. The 132-D-4 (116-D) reactor stack concrete base and foundation including the imbedded cast iron drain line was closed with the 105-D Reactor Cleanup Verification Package (CVP-2005-00003). The analogous decision was based on reviews of the facility information, historical data, and modeling results (ARCL and RESRAD) showing that residual risk is within the bounds established for unrestricted land use. Results used in the ARCL and RESRAD modeling were from the pre-decontamination concrete sample collected at the elevation of the intake duct. The sample elevation was where the highest contaminant levels would be expected and where the highest direct readings were observed during pre-decontamination radiological surveys conducted in 1980. These contaminant levels were modeled over 100% of the inner surface area. Consistent with what would be expected, the contamination did not significantly penetrate the inner concrete surface of the stack. Based on the concrete samples, penetration of contaminants was estimated to be 0.11 to 0.2 cm (0.04 to 0.79 in.), while thickness of the stack wall was up to 46 cm (18 in). Conservative penetration

depth of 0.95 cm (0.37 in.) was used to calculate the as-buried contaminated zone thickness. Excavation of the disposal trench to collect more information is not likely to result in a change to the No Action interim closure decision for the 132-F-4 site.

The 5.6 meters (18.5 feet) diameter octagonal stack base was removed to about 1 meter (3 feet) below grade and extended to 7.2 meters (23.5 feet) below grade. The vertical 15-centimeters (6-inches) cast iron condensate drain pipe in the center of the stack base exited the side of the concrete monolith about 1.6 meters (5.2 feet) below grade. The condensate drain line from the stack base to the 105-F Building process sewer was removed during the demolition activities for the 105-F Reactor below-grade structures.

The stack base included a 15 centimeter (6 inch) diameter cast iron drain pipe in the center of the base that exited the east side of the base at a depth of 1.5 meters (5 feet) below grade. The 15 centimeter (6 inch) cast iron drain pipe ran east from the stack base to the 105-F Building wall a distance of 1.9 meters (6.2 feet) and entered the 105-F Building at a depth of 1.9 meters (6.2 feet) below grade. The external piping and the upper 1 meter (3 feet) of internal piping was removed during the demolition of the 116-F stack and the adjacent 105-F Building walls. About 3.4 meters (11 feet) of cast iron drain pipe remains imbedded in the stack base.

The potential contamination within the imbedded pipeline is deemed negligible since the pipe was a free draining condensate line to the process sewer. The 116-F stack, which was closed with a No Action reclassification, represents the worst-case contamination potential for the drain line. The corresponding 105-D concrete base and foundation, including the imbedded cast iron drain line, was closed with no further action.

The SubSite is Part Of:

Code: 132-F-4

Names: 132-F-4; 132-F-4 Reactor Stack Demolition Site; 116-F Reactor Exhaust Stack; 116-F Reactor Stack

Code: 132-F-5

Classification: Accepted

Names: 132-F-5; 117-F Filter Building

Reclassification: Interim No Action (12/8/2003)

Type: Burial Ground

Start Date: 1/1/1960

Status: Inactive

End Date: 1/1/1965

Description: The site has been evaluated and determined to require No Action. The exhaust filter building housed blowers and particulate and activated carbon filters used to treat the ventilation exhausted from the 105-F Reactor Building. The building was demolished in 1983.

Location: The building was located west of 105-F.

Related Sites/ Structures: The building received exhaust fan discharge through an inlet duct from the 105-F Reactor and discharged the filtered air through a discharge duct and out the 116-F Stack.

Process Description: The ventilation exhaust filter building housed blowers and particulate and activated carbon filters used to treat the ventilation exhausted from the F Reactor Building. The unit and duct work were all made of reinforced concrete, 0.3 to 0.6 meters (1 to 2 feet) thick. The building was 10.7 meters (35 feet) high with 2.4 meters (8 feet) above ground.

Waste Type: Process Effluent

Waste Description: The radionuclides found in the 117-F Building are tritium, carbon-14, cobalt-60, cesium-137, strontium-90, europium-154, and europium-152. During the decommissioning of the facility, surface smears over 100-square centimeter (15.5-square inch) areas in the building revealed beta-gamma contamination of less than 200 counts/minute and alpha contamination less than 500 counts/minute.

Closure Info: Interim: The 117-F Filter Building was released for unrestricted use based on the post-decontamination characterization results cited in a letter from J. J. Dorian with the subject Radiological Criteria for Decontamination and Decommissioning of the Retired 100 Area 117-F Filter Buildings dated May 18, 1983. Consequently, demolition and site grading were performed in November 1983 using conventional heavy equipment. The rubble was buried under at least 1 meter (3 feet) of clean fill and the site was graded to blend with the natural terrain.

RESRAD modeling was performed in 2003 to provide another data point. The RESRAD modeling accounts for radioactive decay from 1983 (the year of building demolition) to 2003, and predicts that none of the contaminants detected in the paint will reach groundwater within 1,000 years. Residual soil concentrations support future land uses that can be represented (or bounded) by a rural-residential scenario and pose no threat to groundwater or the Columbia River based on RESRAD modeling.

Code: 132-F-6	Classification: Accepted
Names: 132-F-6; 132-F-6 Lift Station; 1608-F Effluent Pumping Station; 1608-F Waste Water Pumping Station	Reclassification: Interim No Action (12/8/2003)
Type: Pump Station	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1965

Description: The site has been evaluated and determined to require No Action. The pumping station was demolished in 1987. The area where the demolished facility once stood is currently a cobble covered field.

Location: The site was located near the southeast corner of the 105-F Reactor Building.

Related Sites/Structures: This site was associated with 116-F-6 (1608-F Liquid Waste Disposal Trench) and the 105-F Reactor Building.

Waste Type: Demolition and Inert Waste

Waste Description: Before demolition, this site received water from reactor building drains containing trace amounts of low-level radionuclides and decontamination chemicals (primarily Turco). Radionuclides were primarily miscellaneous activation products, including tritium, carbon-14, cobalt-60, strontium-90, cesium-137, europium-152, and europium-154. The decontamination chemicals consisted of sodium fluoride, oxalic acid, and citric acid. Water was pumped from the reactor collection pits into the reactor effluent lines near the 105-F Reactor Building and became part of the 107-F effluent that was discharged to the Columbia River. During decommissioning of the facility in 1987, a survey of the walls, ceilings, and floor areas of the main floor, pump room, switch gear room, and valve room revealed direct beta-gamma contamination to less than 200 counts/minute (cpm). The maximum contamination levels recorded were for the floor areas of the sumps at 5,000 to 25,000 counts/minute (cpm) direct beta-gamma. During the Dorian and Richards (1978) study in 1975-1976, samples were collected from a soil boring identified as location 132-F-6. Analytical results of material collected in this boring at depths of 7.6 meters (25 feet) and 9 meters (30 feet) revealed elevated concentrations, with a maximum of 92 picocuries/gram for europium-152.

Closure Info: Interim: The 132-F-6 (1608-F) pumping station was demolished in August 1987. The excavation depth was approximately 5 meters (16 feet). 1.6 cubic meters of asbestos was taken to the Hanford Central Landfill. Pumps and piping were shipped to the 200 Area burial grounds for disposal. Approximately 27,500 gallons of residual water was trucked to 1325-N for disposal.

Concrete core samples and scale samples were collected and analyzed.

A "No Action" decision is supported based on reviews of the facility information, historical data, and modeling results (ARCL and RESRAD) and documented on reclassification form 2003-32.

Contaminated material (e.g., asbestos, pumps and associated piping, residual water from sumps, sump sediment, transformer oil) were removed during decommissioning activities and sent to appropriate disposal facilities (e.g., central landfill, 200 Area burial grounds, 1325-N Liquid Waste Disposal Facility, 100-N). The residual contamination exists in a thin concrete layer. Using conservative inputs (e.g., highest activity sample results, Uniform contamination levels over 100% of exposed surfaces), the ARC and RESRAD outputs indicate that residual contamination levels do not present unacceptable risk to the maximally exposed individual. In addition, the RESRAD model results indicate that the residual contamination levels are protective of groundwater and the Columbia River. Excavation of the site to collect more information is not likely to result in a change to the no action interim closure decision for the 132-F-6 site.

Code:	182-F	Classification:	Accepted
Names:	182-F; 182-F Reservoir	Reclassification	Interim Closed Out (9/12/2005)
Type:	Dumping Area	Start Date:	
Status:	Inactive	End Date:	1/1/1977
Description:	The site has been remediated and Interim Closed Out. The 182-F reservoir was used to provide reserve water from the Columbia River for reactor cooling water and raw water for the 100 Area and had a storage capacity of 94.6 million liters (25 million gallons). The reservoir was later used as a landfill for disposal of decontaminated rubble from buildings that were decommissioned in the 100-F Area. In 1997, the site was covered with clean fill.		
Location:	Reservoir was located approximately 400 meters (1,312 feet) due north of the 105-F Reactor Building.		
Related Sites/ Structures:	The site was related to the 183-F Water Treatment Plant, the 126-F-2 (183-F) Clearwells and the 105-F Reactor Building.		
Process Description:	The 182-F Reservoir received raw water from the Columbia River for reactor cooling water and raw water for the 100 Area supply system. The reservoir had a storage capacity of 94.6 million liters (25 million gallons). The reservoir was later used as a landfill for disposal of decontaminated rubble from buildings that were decommissioned in the 100 F Area. In 1997, the site was covered with clean fill.		
Waste Type:	Demolition and Inert Waste		
Waste Description:	This unit received demolition rubble from the 182-F Pumping Station and the 183-F Water Treatment Building and Sedimentation Basins, and debris from other building demolitions. Some of the debris was from 144-F, 144-R, 141-N, 141-P, 141-F, 141-H and 141-L. The unit was covered with fill from adjacent land.		
Closure Info:	Interim: Based on a review of the site historical process information and the results of the geophysical survey, the site appeared to be a disposal area for material that contained hazardous constituents at levels in exceedance of remedial action goals. Based on these determinations, and the implications of sampling a site of this magnitude, remedial action was recommended.		

Excavation of the reservoir began on March 29, 2005, with removal and stockpiling of debris

and soil. Visual observations of soil and debris removed from the southern and eastern portions of the reservoir indicated the presence of inert demolition debris (e.g., concrete, wood, rebar) with a limited amount of lead, asbestos, and some batteries. No hazardous materials other than a limited amount of lead, asbestos, and some batteries were found. Excavation of the western portion of the reservoir revealed essentially soil with no debris. Based on the results of the excavation and discussion with the U.S. Department of Energy and U.S. Environmental Protection Agency, it was decided that excavation would stop and sampling would be performed to support a decision if additional excavation was necessary.

Code:	1607-F2	Classification:	Accepted
Names:	1607-F2; 1607-F2 Sanitary Sewer System; 1607-F2 Septic Tank; 124-F-2	Reclassification	Interim Closed Out (3/11/2003)
Type:	Septic Tank	Start Date:	1/1/1944
Status:	Inactive	End Date:	1/1/1988
Description:	The site has been remediated and Interim Closed Out. It was a septic tank, tile field and associated pipeline. The unit was 4.6 meters (14.9 feet) deep, constructed of reinforced concrete, and had a 522 person capacity (130 liters [35 gallons] per capita) with an average detention period of 24 hours. The walls and floor were 25 centimeters (10 inches) thick. The tile field was constructed of 10-centimeter (4-inch) vitrified pipe, concrete pipe, or drain tile with a minimum of 2.4 meters (8 linear feet) per capita. The laterals were open jointed, spaced 2.4 meters (8 feet) apart. The tile field was irregularly shaped, measuring approximately 90.3 meters (296 feet) by 54.0 meters (177 feet).		
Location:	The septic tank was located approximately 67 meters (220 feet) west and 15 meters (50 feet) south of the 116-F-14 (107-F Retention Basin). The tile field was located approximately 61 meters (200 feet) south of the septic tank, within the 126-F-1 Ash Pit.		
Related Sites/Structures:	This site received effluent from 184-F, 185-F, 190-F, 105-F, 108-F, and the 1700 Administration and Service Buildings.		
Waste Type:	Sanitary Sewage		
Waste Description:	This unit received unknown amounts of sanitary sewage from the 184-F Powerhouse, the 185-F Chemical Treatment Building, the 190-F Pumphouse, the 105-F Reactor Building, the 108-F Building, and the 1700 Administration and Service Buildings. The unit now services the 105-F and 108-F Buildings only. The other buildings have been demolished. Since the site serviced both the 105-F and 108-F Buildings, there is the potential to have received hazardous contaminants. The sludge in the septic tank was measured and sampled as part of the Group 4 Remedial Design Field Investigations. The sludge volume was estimated to be 49,970 liters (13,200 gallons). Sample numbers B0LC76, B0LC77, B0LC78 and B0LC82 were analyzed for metals, volatile organics and semi-volatile organics. Radionuclides were determined by Gamma Spectroscopy. Polyaromatic hydrocarbons were identified as well as elevated levels (above background) of cobalt-60, cesium-137, strontium-90, europium-154/155, radium-226, plutonium-238,239/240 and uranium-234, 235/238. The estimated dose rate from the tank sludge is 157.2 millirem per year.		
Closure Info:	Interim: The selected remedial action for the 1607-F2 site included (1) excavating the site to the extent required to meet specified soil cleanup levels, (2) disposing of contaminated excavation materials at the Environmental Restoration Disposal Facility at the 200 Areas of the Hanford Site, and (3) backfilling the site with clean soil to the average adjacent grade elevation. Excavation was driven by remedial action objectives for direct exposure, protection of groundwater, and protection of the Columbia River.		

During remediation of the 1607-F2 site, in-process sampling and analysis of the sludge in the septic tank, septic system, and tile field (sampling conducted to guide remediation and for waste characterization) indicated that strontium 90, the uranium isotopes, mercury, and arsenic were not COCs for the 1607-F2 site. Therefore, these contaminants are not addressed further in this CVP. In process sampling indicated that strontium-90, the uranium isotopes, and mercury were at levels less than the Hanford Site background (DOE-RL 1996) of 0.18 pCi/g for strontium-90, 1.1 pCi/g for uranium 234, 0.11 pCi/g for uranium-235, 1.1 pCi/g for uranium-238, and 0.33 mg/kg for mercury. Because a large portion of the 1607-F2 drain field was within the footprint of the 126-F-1 Ash Pit and based on agreement between the Tri-Parties, europium-152 was included in the final list CVP COC list for the 1607-F2 site. The COC list for the 126-F-1 Ash Pit is included in the Sampling and Analysis Instruction for Confirmatory Sampling of the Southern Portion of the 126-F-1 Ash Pit.

At the completion of the remedial action, the total excavation was approximately 6,679 square meters (7,988 sq. ft.) in area with a depth of 4.6 meters (15 ft). Waste site cleanup was conservatively evaluated to meet shallow zone criteria. Approximately 35,099 metric tons (38,690 tons) of material from the site were disposed of at the Environmental Restoration Disposal Facility.

Results of the sampling, laboratory analyses, and data evaluations for the 1607-F2 site indicate that all remedial action objectives and goals for direct exposure, protection of groundwater, and protection of the Columbia River have been met.

Code:	1607-F3	Classification:	Accepted
Names:	1607-F3; 1607-F3 Sanitary Sewer System; 1607-F3 Septic Tank; 124-F-3	Reclassification	Interim Closed Out (4/26/2007)
Type:	Septic Tank	Start Date:	1/1/1944
Status:	Inactive	End Date:	1/1/1965
Description:	The site has been remediated and Interim Closed Out. It consisted of a septic tank, drainfield and associated pipeline. It was constructed of reinforced concrete. The walls and floor were 25 centimeters (10 inches) thick.		
Location:	The septic tank was located approximately 183 meters (600 feet) west of the 183-F Water Treatment Plant. The drainfield was approximately 23 meters (75 feet) west of the septic tank.		
Related Sites/ Structures:	The site was related to the 182-F Pump Station, the 183-F Water Treatment Plant, and the 151-F Substation.		
Process Description:	The septic tank had a capacity of 5432.07 liters (1435 gallons). The system could support 41 persons assuming input of 132.49 liters (35 gallons) per capita per day and a one day retention period. The drainfield was constructed of 10-centimeter (4-inch) vitrified pipe, concrete pipe, or drain tile with a total of 100 linear meters (328 linear feet) of piping (2.4 linear meters [8 linear feet] per capita). The 20 centimeter (8 inch) laterals were open jointed and spaced 2.4 meters (8 feet) apart.		
Waste Type:	Sanitary Sewage		
Waste Description:	This unit received an unknown amount of sanitary sewage from the 182-F Pump Station, the 183-F Water Treatment Plant, and the 151-F Substation.		
Closure Info:	Interim: Remediation of the waste site began in September 2005 and consisted of the removal of the septic system, drain field, associated piping, and overburden material. During remediation approximately 2,798 metric tons (US 3,085 tons) of material was excavated, staged onsite, and subsequently disposed of at the Environmental Restoration Disposal Facility,		

(ERDF). Verification sampling of the excavation and staging area footprint was conducted in March 2006 to verify the completeness of remediation. The results indicated that the excavation contained residual arsenic and lead concentrations exceeding cleanup criteria. Additional remediation of the excavation was performed in December 2006 and consisted of removing an additional 3,791 metric tons (4,179 US tons) of material. A second set of verification samples was collected from the excavation and analyzed for arsenic and lead.

Code: 1607-F4	Classification: Accepted
Names: 1607-F4; 1607-F4 Sanitary Sewer System; 1607-F4 Septic Tank; 124-F-4	Reclassification: Interim Closed Out (12/3/2007)
Type: Septic Tank	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1965

Description: The waste site has been remediated and Interim Closed Out. It consisted of a septic tank, drainfield, and associated pipeline. The tank was constructed of reinforced concrete.

Location: The site was located 61 meters (200 feet) west of the 115-F Gas Recirculation Building.

Related Sites/ Structures: This unit received effluent from the 115-F Gas Recirculation Building.

Process Description: The walls of the reinforced concrete septic tank were 20 centimeters (8 inches) thick, and the floor was 15 centimeters (6 inches) thick. It had a capacity of 794.94 liters (210 gallons). The system could support 6 persons assuming input of 132.49 liters (35 gallons) per capita per day and a one day retention period. The drainfield was constructed of 10-centimeter (4-inch) vitrified pipe, concrete pipe, or drain tile with a total of 14.6 linear meters (48 linear feet) of piping (2.4 linear meters [8 linear feet] per capita). The laterals were open jointed and spaced 2.4 meters (8 feet) apart. The system supported the 115-F building.

Waste Type: Sanitary Sewage

Waste Description: This unit received an unknown amount of sanitary sewage from the 115-F Gas Recirculation Building. There is the potential for the site to have received hazardous contaminants from the 115-F Building.

Closure Info: Interim: Confirmatory sampling was conducted on October 6, 2004. During excavation in sample area 1, the septic tank was discovered but was found to have been previously decommissioned and backfilled. The backhoe bucket used in the excavation was too large to enter the opening in the top of the tank. In addition, the septic tank was constructed of reinforced concrete and could not be penetrated with the excavation equipment. As a result, confirmatory samples of material inside the tank were not collected. Instead, a soil sample was collected underneath the septic tank at 2.9 meters (9.5 feet) below ground surface.

Remediation of the waste site was performed from April 3 through April 5, 2007, and included removal of the septic tank, the drain field, and the associated piping. Overburden material and other soils presumed to contain no residual contamination above cleanup levels were stockpiled south of the excavation for post remediation verification sampling. Approximately 707 cubic meters (925 yards) of piping, concrete material, and suspect contaminated adjacent soils were removed and disposed at the Environmental Restoration Disposal Facility. The excavation depth ranged from 2.6 meters (8.5 feet) to 3.2 meters (10 feet).

Code: 1607-F5	Classification: Accepted
Names: 1607-F5; 1607-F5 Sanitary Sewer System; 1607-	Reclassification: Interim Closed Out (9/14/2006)

F5 Septic Tank; 124-F-5

Type: Septic Tank **Start Date:** 1/1/1944

Status: Inactive **End Date:** 1/1/1965

Description: The site has been remediated and Interim Closed Out. The system consisted of a septic tank, drainfield, and associated pipeline.

Location: The site was located approximately 122 meters (400 feet) east of the northeast corner of the old 182-F Reservoir. The drainfield was located just southeast of the septic tank.

Related Sites/ Structures: The site received effluent from the 181-F Pumphouse.

Process Description: The septic tank was constructed of reinforced concrete; the walls are 20 centimeters (8 inches) thick, and the floor was 15 centimeters (6 inches) thick. The septic tank had a capacity of 794.94 liters (210 gallons). The system could support 6 persons assuming input of 132.49 liters (35 gallons) per capita per day and a one day retention period. The drainfield was constructed of 10-centimeter (4-inch) vitrified pipe, concrete pipe, or drain tile with a total of 14.6 linear meters (48 linear feet) of piping (2.4 linear meters [8 linear feet] per capita). The laterals were open jointed and spaced 2.4 meters (8 feet) apart. Piping for the system included a 15 centimeter (6 inch) diameter by 69 meters (225 feet) long vitrified clay pipe that exited the 181-F facility and connected to the northwest side of the septic tank.

Waste Type: Sanitary Sewage

Waste Description: This unit received an unknown amount of sanitary sewage from the 181-F Pumphouse.

Closure Info: Interim: Confirmatory sampling performed in November 2004. It was determined that the waste site required remedial action. However, the influent pipeline connecting the 181-F Pumphouse to the septic tank did not require remedial action. A portion of the piping was removed with the 181-F pump house. The remedial action was conducted on August 30 and 31, 2005, with excavation of 2,250 metric tons (2,480 US tons) of soil and debris, including the septic tank and drain field, being disposed at the Environmental Restoration Disposal Facility. The depth of the excavation was approximately 2.8 meters (9.2 feet).

Code: 1607-F6

Classification: Accepted

Names: 1607-F6; 1607-F6 Sanitary Sewer System; 1607-F6 Septic Tank; 124-F-6

Reclassification: Interim Closed Out (11/8/2001)

Type: Drain/Tile Field **Start Date:** 1/1/1945

Status: Inactive **End Date:** 1/1/1975

Description: The site has been remediated and Interim Closed Out. The 1607-F6 Sanitary Sewer System included two septic old tanks, a new septic tank, a tile field, and pipelines. The old "tanks" were constructed of two 0.91-meter (3-foot) lengths of 91-centimeter (36-inch) concrete pipe connected in series. The pipes were sealed to a wood planking base with asphalt and had wood plank covers. The new tank was constructed of a 1.91-meter (6-foot 3-inch) section of 183-centimeter (72-inch) diameter steel pipe installed vertically with an attached bottom and two layers of tongue and groove planking for the top. The tank is shown on drawing H-1-1518 to have a 61-centimeter (24-inch) by 61-centimeter (24-inch) square access hole at the surface.

Location: The site was located in the Experimental Animal Farm area of the 100F Area. Hanford drawings show the old tanks being located under what was the east side of the 1705-F Building. The new tank is shown to be located 3 meters (6.8 feet) east of 1705-F Building.

The tile field is located 40 meters (112 feet) east of the septic tank.

- Related Sites/ Structures:** Currently no associated structures remain. The site received sanitary sewage from the former 1705-F, 146-F and 146-FR Buildings.
- Process Description:** This septic system operated from 1945 to 1975, receiving sanitary sewage from area buildings. The site is in close proximity to the 100-F-19 Reactor cooling water effluent pipelines, with a portion of the septic system drainfield located directly over one of the large cooling water effluent pipelines.
- Waste Type:** Sanitary Sewage
- Waste Description:** This unit received sanitary sewage from the 146-F and 146-FR Buildings. The amount of waste received is unknown. Since the site serviced both the 146-F and 146-FR Buildings, there is the potential to have received hazardous contaminants.
- Waste Type:** Sanitary Sewage
- Waste Description:** Waste site contaminants of concern (COCs) and contaminants of potential concern (COPCs) identified through process knowledge are listed in the SAP. Because a portion of the septic system drainfield piping was located over the 100-F-19 Reactor cooling water effluent pipelines, the COC/COPC lists for both sites were combined for the CVP. The COCs listed below are attributed to the 100-F-19 Reactor cooling water effluent pipelines, while the COPCs are attributed to the 1607-F6 site. Waste site COCs include: Carbon-14, Cesium-137, Cobalt-60, Europium-152, Europium-154, Europium-155, Nickel-63, Strontium-90. COPCs include: Lead, Polychlorinated biphenyls (PCBs), Semivolatile organic compounds.
- Closure Info:** Interim: Remedial action at the 1607-F6 site began on July 28, 2000. Excavation of the site involved removing the overburden materials, septic system structure (tank and associated influent and drainfield piping), and underlying contaminated soil. On April 25, 2001, the excavation was completed. There was a large gap between the excavation beginning date and completion date because the north-south septic pipeline was excavated at a later date, following the excavation of the septic tank and drain/tile field. The waste site description referred to three septic tanks. However, during remedial excavation of the site, only one tank was encountered and removed. The other two older septic tanks were likely removed and replaced with the newer septic tank during construction of the 1705-F Building. The two older tanks were formerly located under what was the east side of the former 1705-F Building. The animal farm buildings were demolished in 1975. The third and newer tank that was removed during site excavation was located approximately 3 meters (6.8 ft) east of the former 1705-F Building.

The third (and newer) tank was removed during this remedial action. It was located approximately 3 meters (6.8 ft) east of the former 1705-F Building. The drainfield was located east of the septic tank and was located partly over one of the 100-F-19 Reactor cooling water effluent pipelines.

The final excavation and removal of the 1607-F6 site included the removal of one septic tank, the north-south-oriented septic pipeline that served the 146-FR Building, the east-west oriented septic pipeline that served the 146-F Building, the septic system drain/tile field, and underlying contaminated soil. The general average elevation of the bottom of the overall site excavation was at 123.5 meters (405.2 ft) upon completion. The excavation was approximately 5820 square meters (1,908 sq. ft) in area with a maximum depth of approximately 3.5 meters (11.5 ft). Approximately 1,726 metric tons (1,898 tons) of material from the site were disposed of at ERDF.

Code: 1607-F7 **Classification:** Accepted
Names: 1607-F7; 124-F-7; 141-M Building Septic Tank **Reclassification:** Interim Closed Out (10/19/2006)

Type: Septic Tank **Start Date:** 1/1/1945

Status: Inactive **End Date:** 1/1/1975

Description: The site has been remediated and Interim Closed Out. The site consisted of a septic tank, tile field, and interconnecting pipeline located under an area that was historically used for animal grazing (i.e., pasture). The septic tank received sanitary sewage from the former 141-M Building and had a volume of 3,800 Liters (1,000 gallons).

Location: The site was located within the 100-F Experimental Animal Farm area just off the northwest corner of the former 141-M Building and east of the 132-F-1 (The Chronic Feeding Barn) site. A walkway to the former 141-M Building was visible near three living juniper trees located south of the septic tank.

Related Sites/ Structures: There were no associated structures remaining at the site. Before remediation, the site received sanitary sewage from the former 141-M Building and runoff from the pasture use. The barns in the area were used for animals being tested with radioactive substances.

Waste Type: Sanitary Sewage

Waste Description: The site received sanitary sewage from the 141-M Building.

Closure Info: Interim: Confirmatory sampling was done in 2004. No stained soil or suspected asbestos-containing material was encountered during confirmatory sampling activities.

The site excavation began on August 8, 2005, and was completed November 30, 2005. Remediation of the waste site involved layback of overburden and removal of the septic tank, drain field, the interconnecting pipeline, and associated soils around and below those structures. Some of these materials were staged just south of the site before disposal. However, most of the waste was excavated using direct loadout and shipment to the Environmental Restoration Disposal Facility (ERDF). The overall depth of the excavation for the septic tank was approximately 3 meters (10 feet) below ground surface and approximately 1.5 meters (5 feet) below ground surface for the drain field. The excavation depths also included removal of 0.6 meters (2 feet) of soil below these structures. A total of approximately 1,088 metric tons (1,200 US tons) of contaminated material was disposed at ERDF.

Code: UPR-100-F-1 **Classification:** Accepted

Names: UPR-100-F-1; 141 Building Sewer Line Spill; 141-C to 141-M Sewer Line Leak; UN-100-F-1 **Reclassification:** Final Closed Out (10/28/2015)

Type: Unplanned Release **Start Date:** 1/1/1971

Status: Inactive **End Date:**

Description: The site has been remediated and Interim Closed Out. An unplanned release of sewer effluent associated with the Hog Barn occurred on March 13, 1971. The main sewer line became plugged and release approximately 17,000 gallons of contaminated animal pen wash out water to the ground.

Location: The site was located between the 141-C and 141-M Buildings northeast of the 105-F Reactor and west of 116-F-14 (107-F Retention Basin).

Release Description: The release was a spill of wash water containing contaminated animal waste.

Related Sites/ Structures: The site was related to the sewer line from the 141-C to the 141-M Buildings which have since been demolished.

Waste Type: Animal Waste

Waste Description: The spill consisted of wash water used to clean out animal pens. The water contained 4.0E-5 curies of strontium-90 and 1.06E-6 curies plutonium-239.

Closure Info: Interim: (Interim Closed Out) Remedial Action ran from August 2001 until December 2002. The 100-F-19:2 Reactor Cooling Water Effluent Pipeline and co-located sites, (116-F-11 Cushion Corridor French Drain, UPR-100-F-1 Sewer Line Leak, and the 100-F-29 Experimental Animal Farm Pipelines), were remediated as a group and documented in CVP-2001-00003. The group is referred to as the 100-F-19:2 site in the document. The unplanned release was within the footprint of the 100-F-29 pipeline excavation. The elevation of the bottom of the excavation was approximately 124.7 meters (409 ft) upon completion. The excavation area was approximately 19,000 square meters (205,000 sq. ft) with a maximum depth of approximately 5 meters (16 ft) and an average depth of approximately 3.7 meters (13 ft). Removal of the 100-F-29 pipelines near the northwest corner of the 116-F-14 (107-F Retention Basin) required shallower excavation, averaging approximately 1 meter (3 ft) in depth. Little evidence of the 116-F-11 french drain site was found during excavation of the 100-F-19:2 pipelines. The location of the french drain was excavated and sampled to the design elevation 4.6 meters (15 ft).

Remediation included excavation of overburden, piping, debris and contaminated underlying soil. Approximately 39,347 metric tons (43,373 tons) of material including soil, debris and piping were removed and disposed at ERDF.

Final (10/28/2015): (Final Closed Out) Thirteen 100-F Area waste sites were reclassified to Final Closed out on form 2015-078. They had all previously been classified as Interim Closed Out. The waste sites included on this reclassification form are 100-F-10, 100-F-19 (and subsites 1,2 and 3), 100-F-29, 100-F-34, 116-F-2, 116-F-6, 116-F-9, 116-F-12, subsites 118-F-8:3 and :4, UPR-100-F-1. The Record of Decision (ROD) for the 100-FR-1, 100-FR-2, 100-FR-3, 100-IU-1, 100-IU-2 and 100-IU-6 Operable Units has defined these waste sites as all requiring institutional controls to restrict excavation into the deep zone (greater than 4.6 meters or 15 feet below the ground surface). However, no further remedial actions are required.

Institutional Control Boundaries have been defined to be broadly inclusive of waste site groups. Not all areas within these boundaries contain residual contamination greater than 4.6 meters (15 ft) below ground surface. An image of four Institutional Control Boundaries inside 100F Area was attached to the 2015-078 Reclassification form (and included in the WIDS library).

Code: UPR-100-F-2	Classification: Accepted
Names: UPR-100-F-2; 100-F-3; 107-F Basin Leak Ditch; Basin Leak Ditch	Reclassification: Interim Closed Out (4/23/2002)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:
Description: The site has been remediated and Interim Closed Out. Prior to remediation, the ditch resembled a cobble field leading to the river's edge.	
Location: The site ran from the northeast corner of the 107-F Retention Basin to the bank of the Columbia River.	
Related Sites/Structures: The site was associated with the 107-F Retention Basin and the 116-F-9, Animal Waste Leaching Trench.	

Process Description: The Basin Leak Ditch was formed in 1955 following an overflow of the 107-F Retention Basin. The ditch was enlarged by repeated overflows from an effluent manhole located near the north end of the 107-F Retention Basin.

Waste Type: Process Effluent

Waste Description: The waste was radioactive process liquid effluent from the 107-F Retention Basin.

Closure Info: Interim: Site excavation and waste disposal began on February 6, 2001 and were completed on July 28, 2001. The exposed surfaces have been sampled and analyzed to verify attainment of the RAGs.

The maximum excavation depth of 4.2 meters (13.8 ft) occurs in the western portion of the waste site, with a surface elevation of 124.5 meters and a bottom excavation elevation of 120.3 meters. The actual excavation depth throughout the remainder of the site varies, as does the surface elevation. Generally both decrease as the site approaches the river. At the completion of the remedial action, the total excavation was approximately 2,388 square meters (7,834 square feet) in area with a depth greater than 11 meters (36 feet). Approximately 670 metric tons (739 tons) of material from the site were disposed at the Environmental Restoration Disposal Facility (ERDF). Results of the sampling, laboratory analyses, and data evaluations for the UPR-100-F-2 site indicated that all remedial action objectives and goals for direct exposure, protection of groundwater, and protection of the Columbia River have been met.

Code: UPR-100-F-3	Classification: Accepted
Names: UPR-100-F-3; Mercury Spill	Reclassification: Interim Closed Out (8/14/2003)
Type: Unplanned Release	Start Date: 1/1/1977
Status: Inactive	End Date:

Description: The site has been remediated and Interim Closed Out. The site was an unplanned release that occurred at the northeast corner of the demolished 146-FR Fish Laboratory.

Location: The site was located at the northeast corner of the 146-FR Fish Laboratory.

Release Description: In 1977, an unknown quantity of mercury was spilled on the floor in the 146-FR Fish Laboratory and was "squeegeed" across the floor and out the door onto the ground at the northeast corner of the building. The mercury contaminated an area approximately 3.05 meters by 3.05 meters (10 feet by 10 feet). Personnel who remember the incident are unable to specify the volume of mercury, its chemical composition, or the exact area of soil which was contaminated (employee interview).

Related Sites/Structures: The spill was originally in the 146-FR Fish Laboratory then "squeegeed" out the door near the 146-FR Drywells (100-F-25).

Waste Type: Chemical Release

Waste Description: The waste was an unplanned release of mercury. The quantity is unknown.

Closure Info: Interim (8/14/2003): The 100-F-25, 146-FR Drywells were a pair of french drains associated with the 146-F and 146-FR Aquatic Biology and Fish Ponds Laboratories, which both housed research on the effects of ionizing radiation on fish. The french drains are believed to have received liquid wastes from 146-F and 146-FR research laboratories and ponds. The UPR-100-F-3 Mercury Spill, is an unplanned release that occurred at the northeast corner of the 146-FR Building. The UPR-100-F-3 waste site falls entirely within the footprint of the 100-F-25 site

remedial excavation. These wastes sites consisted of only a shallow zone decision unit.

Remedial actions were conducted on April 12, 2003. At the completion of remedial action, the total excavation was approximately 243 square meters (2,615 square feet) in area with a depth of approximately 4.0 meters (13 feet). Approximately 809 metric tons (892 tons) of material (structures and soil) from the site were disposed at the Environmental Restoration Disposal Facility.

100-FR-2

Code: 100-F-2	Classification: Accepted
Names: 100-F-2; PNL Ecological Study Strontium Garden; Strontium Garden	Reclassification: Interim Closed Out (7/25/2002)
Type: Laboratory	Start Date: 1/1/1952
Status: Inactive	End Date: 1/1/1970

Description: The site has been remediated and Interim Closed Out. The site was a garden plot consisting of twelve 1.2 by 3 meter (4 by 10 feet) plots arranged in two rows of six plots each. The area was surrounded on all sides and overhead by a wooden frame with 0.63-centimeter (0.25-inch) screen material attached.

Location: The site was located near the southwest corner of 100F Area, south of well 199-F7-1, and east of the 100-F Perimeter Road (F Avenue).

Related Sites/ Structures: The site was related to the Experimental Animal Farm and radiological experiments conducted by Pacific Northwest Labs (PNL).

Process Description: The site was established to study the behavior of plants grown in soil containing cesium-137 and strontium-90, under controlled conditions of soil tillage, irrigation, cropping and abandonment. Uptake of the radionuclides was measured in alfalfa, barley, radishes, beans, cheatgrass, and tansy mustard. The screened enclosure was designed to exclude mammals and birds, but not insects. Each plot was edged with wooden planks to reduce the transfer of contaminants among the soil plots. An article, written in 1971 by J.F. Cline and W.H. Rickard (published in 1972 in the Health Physics Pergamon Press), describes how the experiments were conducted and indicates the active experiment dates were 1954 -1964. It lists the sample results from the active experiment, collected from 1954 through 1963. Although the plot may have been established in 1952, a total of 180 inches of strontium contaminated irrigation water was used on these plots over the 1954 -1964 time period. This article also states that, in 1970, dry litter and soil samples were collected and analyzed. This seems to be the conclusion of the experiment.

Waste Type: Soil

Waste Description: The waste was contaminated soil. Approximately 39 microcuries of strontium-90 and 120 microcuries of cesium-137 were added to the soil for botany experiments.

Closure Info: Interim: Remedial action at the 100-F-2 site began on December 5, 2001. Excavation of the site involved removing the contaminated structure and underlying contaminated soil. Contaminated materials were disposed of at the ERDF. On January 9, 2002, the excavation was completed. The elevation at the bottom of the excavation was 116.8 meters (383.2 ft) upon completion. The excavation was approximately 373 square meters (4,014 sq. ft) in area with a maximum depth of approximately 1.6 meters (5.2 ft). Approximately 1,269 metric tons (1,399 tons) of material from the site were disposed of at the ERDF.

Code: 100-F-14	Classification: Accepted
Names: 100-F-14; 100-FR-2 Vent Pipe; 100-F Carpenter Shop Waste Site Vent	Reclassification: Interim No Action (3/2/2005)
Type: Storage Tank	Start Date:
Status: Inactive	End Date:

Description: The waste site was evaluated and determined to require No Action. It is a steel vent pipe extending above grade. The above grade pipe was 10 centimeters (4 inches) in diameter with a 180 degree bend at its top. The top points downward at its tip which is fitted with a vent assembly. Steel fence posts surrounded the vent pipe. During a April 1999 visit, several soil gas probes were observed. The area was fairly level with sandy soil and had a moderate cover of grasses. A concrete foundation pad (6 meters x 9 meters [20 ft x 30 ft]) is 13.7 meters (45 ft) east of the site.

Location: The vent was located north of the northeast corner of 118-F-1 Burial Ground and approximately 244 meters (800 feet) southwest of the southwest corner of the 105-F Reactor Building. The unit was 13.7 meters (45 feet) west of a concrete floor pad that remains from a demolished carpenter shop.

Related Sites/ Structures: The site was probably related to the 100-F Carpenter Shop.

Waste Type: Water

Waste Description:

Closure Info: Interim: A site evaluation was conducted as part of the Remaining Sites Verification Package attached to the Reclassification Form 2004-127. Historical data, process knowledge, geophysical survey results, site walkdown observations, and aerial photographs were used to develop a site-specific sample design.

A focused sampling approach was selected for the site, biased towards potential worst-case contaminant locations. Because the site walkdown observations and aerial photographs indicated that the site may have been a decontamination facility, the crib beneath the vent pipe was chosen as the suspected location for the terminus of the drain pipe that discharged liquid effluent from the floor drain.

The evaluation included a focused sampling approach consisting of excavating a test pit into the 3 by 3 meter (10 by 10 feet) subsurface anomaly located beneath the vent pipe. At 0.9 meters (3 feet) below ground surface, a plastic vapor barrier was discovered, followed by the 0.15-meter (6-inch) lateral drain pipe that conveyed effluent from the concrete pad floor drain at 1.2 meters (3.9 feet) below ground surface. The drain pipe appeared to consist of nonfriable asbestos-cement material. A sample of the pipe material was taken.

The rock crib structure was revealed beneath the drain pipe. A sample of the crib material was taken at 1.7 meters (5.6 feet) below ground surface. Native soil was discovered at 2.2 meter (7.2 feet). A representative sample, consisting of 15 aliquots distributed across the bottom of the test pit, was collected. Results of the confirmatory sampling were used to make reclassification decisions for the site in accordance with the TPA-MP-14 (DOE-RL 1998) process.

Code: 100-F-15	Classification: Accepted
Names: 100-F-15; 108-F Building Ventilation French Drain	Reclassification: Interim Closed Out (7/25/2002)
Type: French Drain	Start Date:
Status: Inactive	End Date:

Description: The site has been remediated and Interim Closed Out. The french drain was constructed of concrete, buried to a depth that placed the upper drain surface at grade level. A highly degraded wooden cover was in place over the drain. The bottom of the drain consisted of soil and large

gravel, which supported a five-gallon carboy container. A copper tube connected the exhaust duct from the 108-F third floor, room # 302, to the carboy.

Location: The unit was located next to the east wall of the 108-F Building.

Related Sites/ Structures: This site was associated with the 108-F Building (site 100-F-36).

Waste Type: Water

Waste Description: The drain received condensate that formed inside several large hood ventilation ducts mounted externally on the east wall of the building. Condensate formed during cold weather and ran through 2.5-centimeter (1-inch) stainless steel lines to the drain. The quantity of waste received is not known. A bottle containing 3 gallons of liquid from the 100-F-15 french drain was characterized between 05/07/96 and 08/08/96. A radiological survey of the bottle was conducted using field detection equipment and the resulting readings showed less than detectable. A sample from the liquid was collected and sent to the laboratory for chemical and radiochemistry analysis. The resulting analysis was received on 08/28/96 and indicated the liquid contained above threshold amounts of radiological and hazardous material (i.e., plutonium and chromium). Specifically, the chemical constituents analyzed for were TCLP Metals, Inorganic Ions, and Total Cyanide, and the radiological constituents were GEA, Gross Alpha, Gross Beta, Strontium-90, Isotopic Plutonium, and Total Uranium.

Closure Info: Interim: Site excavation was completed as reported in the 108-F Biological Laboratory D&D Project Closeout Report. The 100-F-4, 100-F-11, 100-F-15, and 100-F-16 french drains were removed during decommissioning and demolition activities and backfilled with clean material. The CVP report documents that the 100-F-4, 100-F-11, 100-F-15, and 100-F-16 french drains have been sampled and analyzed to verify attainment of the RAGs. At the completion of the remedial action, the total excavation was approximately 362.2 square meters (3898.7 square feet) in area with a depth of 4.6 meters (15.0 feet). No material from the sites was disposed of at the Environmental Restoration Disposal Facility as a result of the Remedial Action Project activities described here. Verified clean materials were used as backfill at the completion of the remedial action.

Code: 100-F-20

Classification: Accepted

Names: 100-F-20; PNL Parallel Pits

Reclassification: Interim Closed Out (1/17/2007)

Type: Trench

Start Date: 1/1/1962

Status: Inactive

End Date:

Description: The has been remediated and Interim Closed Out. The site consisted of two earthen pits or trenches, both oriented northeast to southwest. The pits were observed on aerial photographs (#7620 and #6451-5) dated 1962. The photos show the site to be actively in use, with refuse material visible in the pit bottoms. The access roads appear well used, suggesting frequent motor vehicle access to the pit locations.

Prior to remediation, the area was covered with cheat grass and rabbit brush vegetation. Evidence of surface disturbance was visible. Bricks and subsidence were observed at the site, but the exact location of the trenches is not visually discernible from the surface. Blue wooden stakes remain at the site from geophysical surveys. Between March 31, 1995 and April 4, 1995, a radiological survey was conducted over the general area of the Pacific Northwest Laboratory (PNL) parallel pits. Counts as high as 12,000 counts per minute (cpm) were collected over the surface of the site.

Location: The site was located about 30.5 meters (100 feet) west of the eastern 100-F Perimeter Road and immediately north of a dirt road that connects the 100-F Perimeter Road with the main reactor

site access road, running along the southern boundary of the ash pit.

Related Sites/ Structures: The site was thought to have been related to the Experimental Animal Farm.

Process Description: The site was believed to have been used to dispose of both radioactive and nonradioactive material from the experimental animal farm. The Burial Ground ROD reported that the northern trench may have contained non-radioactive animal farm wastes, including hardware, lumber, and soft materials. The southern pit may have received radioactively contaminated animal feces and pen sweepings.

Waste Type: Misc. Trash and Debris

Waste Description: A retired Hanford employee was interviewed in 1995. He clearly remembered delivering waste to the pits. The southern pit may have received radioactively contaminated animal feces (mostly sheep) and pen sweepings, small quantities of animal tissue, and miscellaneous Experimental Animal Farm wastes. The northern pit may have received non-radioactive Experimental Animal Farm wastes including hardware, lumber, and soft materials. Neither of these pits was used as a burn pit. Potential contaminants included: Co-60, Sr-90, Pu-239/240.

Closure Info: Interim: Remedial action began on December 5, 2005, with load out of waste material completed on August 8, 2006. Excavation of the site involved removing demolition debris that contained concrete, metal piping, steel sheeting, and wood. Approximately, 14 small laboratory-type containers were encountered throughout the burial ground. No asbestos-containing material was identified during waste excavation and no areas of the burial ground were identified for focused sampling.

After removal of all debris, radiological field screening was used to determine that excavation activities were complete. At the conclusion of the excavation activities, the remediation footprint was approximately 4.3 meters (14 ft) below the ground surface and at the deepest point the elevation at the bottom of the excavation was 117 meters (384 ft) above sea level. An estimated 11,953 metric tons (13,176 U.S. tons) of material was excavated from the 100-F-20 burial ground and disposed at ERDF

The remaining soils at the site have been sampled, analyzed, and evaluated. The results of this effort indicate that residual concentrations will support future land uses that can be represented (or bounded) by a rural-residential scenario and that residual concentrations throughout the site pose no threat to groundwater or the Columbia River. The site had no deep zone; therefore, no institutional controls were required. The site was verified to be remediated in accordance with the ROD and may be backfilled.

Code: 100-F-35	Classification: Accepted
Names: 100-F-35; Soil Contamination Area Inside the 105-F Exclusion Area	Reclassification: Interim Closed Out (6/16/2003)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:
Description: The site has been remediated and Interim Closed Out. The site had been a posted Soil Contamination Area with no distinguishing features.	
Location: The site was located southwest of the 105-F Reactor Building, inside the Exclusion Area.	
Release Description: An area of contamination was found inside the 105-F Exclusion Area on April 29, 1997. The area was initially found with the Mobile Surface Contamination Monitor (MSCM-II) Tractor (report #MSCMR243). A more detailed survey with an Electra reported 60,000	

disintegrations/minute over an area approximately 3 by 3 meters (10 by 10 feet). A conversation with Steve Demers indicates that the source of contamination was a large container (commercial name "Terra-Store") that had been sitting on this area during the excavation of the 116-F-4 Pluto Crib. The Terra-Store container was filled with contaminated soil from the excavation and then transported to the Environmental Restoration Disposal Facility (ERDF). The 3 by 3-meter (10 by 10-foot) contaminated area is residual contamination from the container of contaminated soil (Terra-Store).

Related Sites/ Structures: The site was associated with 116-F-4 Crib.

Waste Type: Soil

Waste Description: An area of radiologically contaminated soil, reading 60,000 disintegrations/minute was identified within the 105-F Exclusion Area. The ground contamination was the result of a large container placed in this area to hold contaminated soil removed from 116-F-4 Crib. Soil samples from 116-F-4 Crib identified strontium-90 and cesium-137 as the major contaminants.

Closure Info: Interim: Remedial action at the 100-F-35 site began in October 2002 and was completed in December 2002. The excavation was approximately 51.2 square meters (551 square feet) in area with a depth of 0.9 meters (3 feet). Approximately 75.4 metric tons (83 tons) of material from the site were disposed at the Environmental Restoration Disposal Facility (ERDF).

Code: 100-F-50

Classification: Accepted

Names: 100-F-50; Storm Water Run Off Culvert; 100-F Railroad French Drain

Reclassification: Interim No Action (4/15/2008)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The waste site was evaluated and determined to require No Action. It consisted of a circular concrete basin and a steel culvert (pipe). The basin, approximately 1 meter (3 feet) in diameter, collected surface water runoff that drained via a 36-centimeter (14-inch) diameter steel diversion culvert under one of the railroad grades and flowed down an embankment to the flat terrain below.

Location: The concrete retaining wall at the top of the french drain was located about midway between the two sets of track that were about 10 meters (30 feet) apart.

Release Description: Evidence of water erosion on the hillside below the culvert and vegetation in aerial photographs suggested water runoff.

Related Sites/ Structures: The site was associated with railroad tracks and rail cars.

Process Description: The purpose of the French drain and drain pipe was unknown. It appeared to have been installed as a water collector and drain for the land between the two tracks. Aerial photographs during Hanford operations show the presence of an unusually large amount of vegetation below the drain culvert, suggesting that water solutions were discharged. No water piping sources were found on drawings in this area, so it does not appear that rinsing processes were performed at the site. The French drain appeared to be located at a low point in the area between the two railroad tracks. A drain pipe ran east under one set of railroad tracks to discharge from a soil bank above a low area in the adjoining land. There was a line of vegetation below the drain pipe in older photographs, but there was only dead vegetation found during the field walkdown in 2005. Since radioactive solutions were not typically discharged to soil surfaces (to avoid airborne contamination and spreading), it does not appear that any dumping of radioactive solutions was involved at the site. Cask car drainage and flushing was

typically done at the shipping or receiving areas that had process sewers. Chemical dumping was not suspected for this site. There was soil washout on the bank below the culvert east of the railroad tracks. There was evidence of dead vegetation and/or some darkening of the soil in the low area. There was no sign of soil stains that might indicate chemical solution dumping.

Waste Type: Soil

Waste Description: There is evidence of soil erosion below the culvert from the french drain. The concrete ring (french drain) is filled with soil.

Closure Info: Interim: The site evaluation included investigation by confirmatory sampling conducted on November 19, 2007. The contaminants of concern included: hexavalent chromium, gamma-emitting radionuclides (cesium-137, cobalt-60, europium-152, europium-154), and strontium-90. Additionally, based on drainage, the following COPCs were: the expanded list of inductively coupled plasma metals, mercury, semivolatile organic compounds, pesticides, polychlorinated biphenyls, herbicides, total petroleum hydrocarbons, and alpha- and beta-emitting radionuclides. All confirmatory samples were analyzed in accordance with the 100 Area Remedial Action Sampling and Analysis Plan (SAP).

Code: 118-F-1

Classification: Accepted

Names: 118-F-1; Burial Ground No. 1; Minor Construction Burial Ground No. 2; Solid Waste Burial Ground No. 2

Reclassification: Interim Closed Out (12/20/2007)

Type: Burial Ground

Start Date: 1/1/1954

Status: Inactive

End Date: 1/1/1965

Description: The waste site has been remediated and Interim Closed Out. It consisted of a combination of two burial locations formerly called Minor Construction Burial Ground No. 2 and Solid Waste Burial Ground No. 2. The burial ground received radioactive equipment and other miscellaneous wastes from the 100-F Reactor operations. There were three unlined trenches and a pit present at the site. The trenches were oriented north-south and were typically 91 meters (300 feet) long by 6.1 meters (20 feet) wide. The site appeared as a cobble-covered, open field after remediation.

Location: The site was located approximately 300 meters (1000 feet) southwest of the 105-F Reactor Building.

Process Description: The 118-F-1 Burial Ground combined two locations formerly called Minor Construction Burial Ground No. 2 and Solid Waste Burial Ground No. 2. Solid waste from 105-F Reactor Building construction work was put into two holes in 1954 and covered with soil to grade in late 1955 or early 1956. Adjacent to this site, on the south side, a solid waste burial ground was opened in 1955 and extended on two subsequent occasions. Miscellaneous solid waste was buried in the 2 trenches, oriented north and south, and covered to grade with a minimum of 0.6 meters (2 feet) of soil. West of these trenches a number of pits containing irradiated process tubing and dummy elements were similarly covered. A third trench on the east side of the burial ground was used during July and August 1965, for burial of gun barrel tips, steel sleeves, and metal chips removed from the reactor. Filter boxes containing reactor graphite chips were also buried in the trench which was then backfilled to grade with 1.2 meters (4 feet) of soil cover. A pit near the west side of the site was used during the same period for burial of miscellaneous surface contaminated waste and was subsequently backfilled with approximately 1.8 meters (6 feet) of soil cover. The boundary of the burial ground had been marked with posts numbered F-65-1 through F-65-21.

Waste Type: Equipment

Waste Description: This site received radioactive reactor components and hardware (dummy elements, process tubing, etc) and other miscellaneous radioactive solid wastes. Potential contaminants include: Co-60, Sr-90, Pu-239/240.

Closure Info: Interim: Remedial action began on December 27, 2005. All remedial activities (excavation, sorting, and load-out) were completed by June 22, 2007. Wastes encountered in the 118-F-1 Burial Ground included reactor related waste including aluminum fuel spacers, splines, reactor hardware, equipment, piping, graphite dust, sheet metal, concrete, cardboard, wood timbers, other miscellaneous debris, and eight pieces of suspect spent nuclear fuel (SSNF).

The excavation area had a maximum depth of approximately 5.5 meters (18 feet), which included a shallow zone and a deep zone. Approximately 88,800 metric tons (97,900 U.S. tons) of waste and contaminated soil from the site was disposed at ERDF and approximately 13,400 bank cubic meters (BCMs) of soil (overburden/below contaminant level [BCL] stockpile material) was segregated for use as clean backfill material. At the conclusion of excavation activities, the elevation at the deepest part of the remedial excavation was 117 meters (384 feet) above sea level. The remediation excavation was approximately 11,600 square meters (125,000 square feet) in area with a maximum depth of approximately 5.5 meters (18 feet).

Code: 118-F-2	Classification: Accepted
Names: 118-F-2; Burial Ground No. 2; Solid Waste Burial Ground No. 1	Reclassification: Interim Closed Out (2/8/2008)
Type: Burial Ground	Start Date: 1/1/1945
Status: Inactive	End Date: 1/1/1965

Description: The waste site has been remediated and Interim Closed Out. It consisted of a solid waste burial ground that served as the original solid waste disposal site for the 100F Area. It was formerly called Solid Waste Burial Ground No. 1.

Location: The site was located approximately 450 meters (1,475 feet) west-southwest of the 105-F Reactor Building. Prior to remediation the burial ground boundary had been marked by posts numbered F-65-22 through F-65-37.

Process Description: Eight trenches contained miscellaneous solid waste from 105-F and one trench contained solid waste from the biology facilities. According to historical documentation, these trenches were covered to grade prior to 1956. The individual trenches were oriented north and south and were typically 76 meters (250 feet) long by 6.1 meters (20 feet) wide. Several cylindrical sleeves, measuring 5.5 meters (18 feet) long and 1.8 meters (6 feet) in diameter, were used for disposal of animal carcasses and liquid waste from 108-F, and were covered with approximately 1.8 meters (6 feet) of soil in 1955. GPR data from the northern portion of the site indicate considerable disturbed areas which precludes easy and accurate delineation of possible trenches. A 2002 Geophysical Investigation identified nine smaller caissons, measuring one meter (3 feet) in diameter, roughly at grade, on the northwest side of the burial ground. These caissons were located in a mound of soil, approximately 1.5 meters (5 feet) high, running north-south. Uncertainty existed whether these caissons could be the same as the cylindrical sleeves mentioned above because the sleeves measure 1.8 meters (6 feet) in diameter. Additionally, the co-ordinates for the sleeves from HW-33305 (Clukey 1954) places them 90 meters to the west of the caissons.

Waste Type: Equipment

Waste Description: The site contains miscellaneous radioactive solid wastes, reactor components and hardware. Potential contaminants include: Co-60, Ni-63, Sr-90, Cs-137, Eu-152, Eu-154, U-238, Pu-238, Pu-239/240, chromium, lead, mercury.

Waste Type: Animal Waste

Waste Description: The burial ground contains several long metal pipes with wooden lids used to dispose of contaminated animal carcasses.

Closure Info: Interim: Remedial action began on January 17, 2006, and was completed on August 8, 2007. Excavation of the site involved removing the uncontaminated overburden, the buried contaminated debris, and the underlying contaminated soil over an area approximately 14,197 square meters (152,815 square feet). Approximately 4,020 bank cubic meters (BCM) (5,260 bank cubic yards [BCY]) of uncontaminated overburden soil was removed and stockpiled near the excavation for subsequent use as backfill. Approximately 16,100 BCM (21,100 BCY) of waste, including contaminated soil and debris, was disposed at the Environmental Restoration Disposal Facility. At the conclusion of remediation activities, the elevation at the deepest part of the excavation was approximately 117.4 meters (385 feet) above mean sea level with a maximum depth of approximately 4.6 meters (15 feet) below original surrounding ground surface.

Code: 118-F-3

Classification: Accepted

Names: 118-F-3; Burial Ground No. 3; Minor Construction Burial Ground No. 1

Reclassification: Interim Closed Out (12/21/2006)

Type: Burial Ground

Start Date: 1/1/1952

Status: Inactive

End Date: 1/1/1952

Description: The waste site has been remediated and Interim Closed Out. It was a solid waste burial ground that received irradiated reactor parts removed during the Ball 3X project to convert the 100-F Reactor from the liquid 3X to the ball 3X safety systems. The southern half of the burial ground ran in a north-south direction and the northern half angled toward the west forming a dogleg.

Location: The site was located approximately 85 meters (280 feet) southwest of the 105-F Reactor Building, adjacent to the reactor facility fence. The burial ground boundary was permanently marked by posts numbered F-65-38 through F-65-43.

Process Description: This site received irradiated parts from the Ball 3X Project at the 105-F Reactor during 1952. The waste was primarily vertical safety rod (VSR) thimbles and also step plugs. During the project 39 thimbles were removed and buried. Thimbles were described as being 11 meters (35 feet) long, with a diameter of 8.89 centimeters (3.5 inches), and a wall thickness of 0.38 centimeters (0.15 inches). Each weighed about 90 pounds and was made of aluminum. An additional 23 thimbles were replaced for maintenance purposes at an earlier date, it was unclear where these were buried.

Waste Type: Equipment

Waste Description: The site received irradiated reactor parts that were removed during the project to convert the 105-F Reactor from the Liquid 3X to the Ball 3X safety systems. The parts primarily included vertical safety rod thimbles and step plugs. Thirty-eight thimbles were known to have been buried there and possibly as many as 61. The principal radionuclide was short-lived cobalt-60.

Closure Info: Interim: Remedial action began on January 31, 2006 with load out of waste material completed on May 23, 2006. Excavation of the site involved removing metal and concrete debris, including piping, sheet metal, an empty tank structure, a large heat-transfer tower, thimbles, and step plugs. No asbestos-containing material was identified during waste excavation. At the conclusion of excavation activities, the remediation footprint was approximately 3.5 meters (12 feet) below ground surface and the elevation at the bottom of the excavation was 121.5 meters (400 feet) above sea level.

An estimated 4,060 metric tons (4,476 U.S. tons) of contaminated material from the site was disposed at ERDF. In addition, approximately 1,400 cubic meters (49,441 cubic feet) of clean overburden material was excavated from the waste site and stockpiled for potential reuse as backfill.

The interim action ROD, based on a limited ecological risk assessment, established the soil cleanup levels. Although not required by the ROD, a screening comparison against ecological risk screening levels was made for the site COCs, as identified in the RDR/RAWP. The highest exceedance values were observed in the focused sample collected of the black surface ash located north of the site.

Code:	118-F-4	Classification:	Accepted
Names:	118-F-4; 115-F Crib; 115-F Pit	Reclassification	Interim No Action (2/14/2005)
Type:	Crib	Start Date:	1/1/1949
Status:	Inactive	End Date:	1/1/1949
Description:	The waste site has been evaluated and determined to require No Action. It was a small unlined disposal pit/crib. The area appears as an open field covered with cobbles. No vegetation grows on the surface.		
Location:	The site was located approximately 122 meters (400 feet) west-southwest of the 105-F Building, just inside the southwest corner of the 100-F Exclusion Area fence.		
Process Description:	The site was a small, unlined pit constructed to receive silica gel from the 115-F drying towers.		
Waste Type:	Chemicals		
Waste Description:	The site contains 270 kilograms (0.3 tons) of silica gel removed from a gel tower in one of the 115-F dryer rooms.		
Closure Info:	Interim: A site evaluation was conducted in the preparation of the Remaining Sites Verification Package (RSVP). The evaluation consisted of field observations including ground-penetrating radar (GPR) and focused (confirmatory) sampling and analysis for the purpose of determining if hazardous or radiological contaminants were present.		

A stratified sampling design with focused sampling was implemented on October 16, 2004. One test pit and one test trench were excavated. The test pit was excavated to explore the area of the waste site described by WIDS and a linear anomaly identified through GPR believed to be a pipe. The test trench was excavated to explore three other areas identified through GPR as containing a high concentration of subsurface anomalous features near the waste site. At the southern end of the test trench three composite samples were collected from the bottom of the excavations, and one sample was collected from an area of ashy oil-stained surface soil. The results of the confirmation sampling were used to make reclassification decisions for the site in accordance with the TPA-MP-14 (DOE/RL 1998) process.

Code:	118-F-5	Classification:	Accepted
Names:	118-F-5; Battelle Sawdust Pit; PNL Sawdust Pit; PNL Sawdust Respository	Reclassification	Interim Closed Out (5/6/2008)
Type:	Burial Ground	Start Date:	1/1/1954
Status:	Inactive	End Date:	1/1/1975

Description: The waste site has been remediated and Interim Closed Out. It consisted of a single, unlined trench that received radioactive sawdust from the floors of animal pens in the 100F Experimental Animal Farm. The site appeared as a large raised mound. Prior to backfilling, the site consisted of several trenches oriented north and south.

Location: The site was located approximately 305 meters (1000 feet) southeast of the 107-F Retention Basin outside the old perimeter road, and east of the 188-F Ash Disposal Area.

Related Sites/ Structures: The site was associated with the 100F Experimental Animal Farm.

Process Description: According to the Technical Baseline Document, WHC-SD-EN-TI-169, past employees remember that sawdust from the Experimental Animal Farm was placed in boxes or 208-liter (55-gallon) metal drums before burial at this site. The material was transported to the sawdust pit in light trucks and the packaged waste was thrown into the pit by hand. A GPR survey conducted in January 2002, identified a large disturbed area but no evidence of buried containers (boxes or drums).

Waste Type: Animal Waste

Waste Description: The site contains low-level activity sawdust and other solids from floors of dog kennels and swine pens. A facsimile sent from W. D. Richmond to M. R. Schneller on March 31, 1971 contains an estimate that the site had received 15 curies of strontium-90 and 0.3 curies of plutonium-239. The site was active and still receiving waste when the facsimile was sent. The facsimile is included in Appendix D of WHC-EP-0087.

Closure Info: Interim: Remedial action of the 118-F-5 Burial Ground began on November 28, 2005, and was completed on August 29, 2007. Excavation of the site involved removing the uncontaminated overburden and the underlying contaminated soil. Sawdust was evident throughout the area excavated. There was no evidence of containers (i.e., boxes or metal drums) that reportedly been used for disposal of sawdust. A small area (given a field designation of 118-F-5A), northwest of the main 118-F-5 excavation, was also remediated. The area had been identified by the geophysics investigation as a disturbed zone distinct from the larger area. During remediation of this area, no evidence of sawdust or other buried waste was discovered.

Collectively, the sites had approximately 7,100 bank cubic meters (BCM) (9,287 bank cubic yards [BCY]) of uncontaminated overburden soil that would be reused as backfill. A total of approximately 25,500 BCM (33,354 BCY) of contaminated soil was excavated and disposed at the Environmental Restoration Disposal Facility. At the conclusion of remediation activities, the elevation at the deepest part of the excavation was approximately 119.5 meters (392 feet) above mean sea level with a maximum depth of approximately 5.5 meters (18 feet) below ground surface. The remediation excavation covered an area of approximately 7,392 square meters (79,535 square feet).

Code: 118-F-6	Classification: Accepted
Names: 118-F-6; PNL Solid Waste Burial Ground	Reclassification: Interim Closed Out (9/23/2008)
Type: Burial Ground	Start Date: 1/1/1965
Status: Inactive	End Date: 1/1/1973

Description: The waste site has been remediated and Interim Closed Out. It was an unlined burial ground that received animal and laboratory wastes related to the 100F Experimental Animal Farm. A 2002 Geophysical investigation of this burial ground identified six north south trending trenches. Prior to remediation the burial ground was designated by HPS-AC-5-40 concrete markers.

Location: The site was located southwest of the 105-F Reactor Building and adjoined the southern border

of 118-F-1, Minor Construction Burial Ground No. 2, Burial Ground No. 1, Solid Waste Burial Ground No. 2.

- Related Sites/ Structures:** The site was associated with the 118-F-1, Minor Construction Burial Ground No. 2, Burial Ground No. 1, Solid Waste Burial Ground No. 2 and the 100F Experimental Animal Farm.
- Process Description:** The large buried railroad tank cars were used for incineration of animal tissue and carcasses. The carcasses were dropped through a manhole and lime was placed on them to facilitate decomposition. When a tank was full, 1,500 to 1,900 liters (400 to 500 gallons) of fuel oil were added to the tank and ignited. The residual ash was left in a tank after each incineration.
- Waste Type:** Animal Waste
- Waste Description:** This unit contains animal and laboratory wastes including plutonium-238 contaminated animal ash. The site did not receive reactor related waste.
- Closure Info:** Interim: Remedial action at the site began on December 12, 2005, and was completed on December 13, 2007. Remedial action activities involved removing the uncontaminated overburden, the buried contaminated debris, and the underlying contaminated soil. Wastes encountered in the 118-F-6 Burial Ground included a railroad tank car, laboratory equipment and bottles, cylinders and crushed drums, biological and animal wastes and carcasses, and limited reactor hardware. Some of these items contained small amounts of liquids. All liquid mixed waste was sent for off-site treatment and disposal.

Approximately 13,100 bank cubic meters (BCM) of material and contaminated soil was disposed at ERDF. Approximately 12,000 BCM of soil (overburden/layback stockpile material) was segregated for use as clean backfill material. At the conclusion of excavation activities the remediated area was approximately 7,075 square meters (76,155 square feet) with a maximum depth of approximately 6.5 meters (21 feet). The deepest part of the remedial excavation (trench 4) was at an elevation of 115.5 meters (379 feet) above sea level.

All areas identified by geophysical survey as potentially containing debris or waste were excavated. An area north of trench one showed subsurface disturbance in the geophysical survey, however, this portion of the burial ground did not contain waste or contamination. It is likely that it was excavated for the purpose of waste disposal but was never used.

Code:	118-F-7	Classification:	Accepted
Names:	118-F-7; Concrete Box; 100-F Miscellaneous Hardware Storage Vault	Reclassification	Interim Closed Out (10/30/2006)
Type:	Storage	Start Date:	1/1/1945
Status:	Inactive	End Date:	1/1/1965
Description:	The site has been remediated and Interim Closed Out. The site consisted of an inactive solid waste storage vault used for temporary storage of slightly contaminated reactor parts. The majority of the vault was underground.		
Location:	The site was located just south of the 105-F Reactor Building south security fence, west of 116-F-10 and east of the rail line that connected to the 105-F Reactor Building.		
Process Description:	This site was an inactive solid waste storage vault used from 1945 to 1965 for temporary storage of slightly contaminated reactor parts that could be recovered and reused for the 100-F Area reactor operations. The storage vault was a partially buried, light-colored concrete box that extended approximately 46 centimeters (18 inches) above grade. The vault was approximately 23 meters squared (247.5 square feet) and 2.4 meters (8 feet) deep. It was covered with a wooden lid.		

Waste Type: Equipment

Waste Description: This site served as temporary storage for miscellaneous reactor hardware. In 1965, contamination levels within the box were 200 to 300 counts-per-minute. There was some confusion in existing documentation as to whether equipment still remained in the vault. Table 11 of Miller and Wahlen (WHC-EP-0087) reported that 134,700 kilograms (148.3 tons) of lead of 5,600 kilograms (6.2 tons) of cadmium remains in the vault. Appendix A of the same report states that the vault contains only a small amount of radioactive material. DeFord (1993) reports that site personnel believe that the vault was empty.

Closure Info: Interim: The vault was a partially buried concrete box that extended 46 centimeters (18 inches) above grade and was covered with a wooden lid. Underground Radioactive Material signs had been posted on the wooden lid. Remedial action at the site began on January 31, 2006, with load out completed in April 2006. Excavation of the site involved removing the concrete vault structure, the wooden roof structure, and underlying contaminated soil. A single lead/cadmium reactor poison piece, measuring 15 centimeters (6 inches) in length and 3.8 centimeters (1.5 inches) in diameter, was discovered inside the vault during excavation.

At the conclusion of excavation activities, the elevation at the bottom of the excavation was 123 meters (403.5 feet). The excavation area was 138 square meters (1,487 square feet) with an approximate depth of 3.0 meters (9.8 feet). The total of an estimated 104 metric tons (115 U.S. tons) of material was disposed at ERDF.

Code: 120-F-1

Classification: Accepted

Names: 120-F-1; Glass Dump

Reclassification: Interim Closed Out (6/27/2008)

Type: Trench

Start Date:

Status: Inactive

End Date:

Description: The waste site has been remediated and Interim Closed Out. It consisted of two distinct disposal areas, one was a trench that ran east to west filled with fluorescent tubes, incandescent light bulbs, instrument vacuum tubes, small alkaline batteries, chemical bottles and laboratory apparatus. A second area of disturbed soil with plastic debris was located approximately 46 meters (150 feet) to the southeast.

Location: The site was located 275 meters (772 feet) south of 128-F-1, 100-F Burning Pit and south-southeast of the 105-F Reactor.

Process Description: The site was originally described as a single, open trench filled with fluorescent tubes, incandescent light bulbs, instrument vacuum tubes, small alkaline batteries, chemical bottles and laboratory apparatus. A second area of disturbed soil with plastic debris was located approximately 46 meters (150 feet) to the southeast. Due to its proximity, the probable source of the debris found at the 120-F-1 waste site is believed to be the 108-F Building, but the site may have contained debris from other locations within the 100-F Area.

Waste Type: Misc. Trash and Debris

Waste Description: The site is covered with approximately 0.61 meters (2 feet) of fluorescent tubes, incandescent light bulbs, instrument vacuum tubes, and small AAA, C, and D batteries. The site also contains an assortment of chemical bottles, both large and small.

Closure Info: Interim: Remedial action at the 120-F-1 waste site began in September 2007 and was completed in March 2008. Two distinct areas were excavated resulting in disposal of approximately 1,505 bank cubic meters of contaminated materials to the Environmental Restoration Disposal Facility.

On January 21, 2006, prior to remedial activities, an industrial hygiene investigation of the site

was conducted to determine whether beryllium was present in the phosphor material used in the fluorescent tubes dumped at the 120-F-1 waste site. In preparation for remedial action at the site, a standard geophysical investigation was conducted in the vicinity of the glass dump. The second area of debris to the southeast proved to be larger than the glass dump. It contained concrete, wire debris, small drums with heavy oil-type petroleum hydrocarbons, and some stained soil with pesticides (dichlorodiphenyldichloroethylene [DDE] and dichlorodiphenyltrichloroethane [DDT]). The second area was remediated as part of the 120-F-1 Glass Dump Waste Site. When the previously interim-stabilized trench was opened using a front-end loader, it was discovered that the plywood barrier had failed and the fluorescent tubes were crushed. Pieces of the fluorescent tubes and accompanying soils were sampled.

Research indicated that prior to 1949 beryllium was used in the manufacture of fluorescent light bulbs, therefore, the samples were analyzed for metals, including mercury and beryllium. It was determined that the fluorescent tubes were not manufactured with beryllium and that beryllium would not be a health concern during remove, treat, and dispose (RTD). However, mercury and, to a much lesser extent, metals such as manganese, nickel, and cadmium were detected and determined to be possible airborne inhalation hazards.

Code:	126-F-1	Classification:	Accepted
Names:	126-F-1; 184-F Powerhouse Ash Pit; 188-F Ash Disposal Area	Reclassification	Interim Closed Out (9/20/2007)
Type:	Coal Ash Pit	Start Date:	1/1/1944
Status:	Inactive	End Date:	1/1/1965
Description:	The waste site has been remediated and Interim Closed Out. It consisted of an area that had received coal ash from the 100-F Area coal-fired steam plant that operated from 1944 to 1965. Coarse textured bottom ash and boiler slag were evident at the site. The northern portion of the ash pit was delineated with AC-540 concrete markers (approximately 2.4 hectares [6 acres]).		
Location:	The site was located southeast of the 116-F-14, 107-F Retention Basin.		
Related Sites/ Structures:	The site was related to the 184-F Powerhouse.		
Process Description:	The 126-F-1 site was created as a result of disposal of ash from the 184-F coal-fired steam plant that operated between 1944 and 1965. Large amounts of coal ash was sluiced to the ash pit with raw river water through a 20 centimeter (8 inch) ashcolite pipe.		
	The ash pipeline originally terminated at a point between the aboveground reactor cooling water effluent lines that discharged to the 107-F Retention Basins. Leakage of reactor cooling water from the 107-F Retention Basins (116-F-14) flowed into the northern portion of the ash pit causing it to become radiologically contaminated. It was contained with an earthen dike. The coal ash sluice pipe was extended through the dike in the late 1940s to a point farther south, establishing coal ash discharge to the southern portion of the coal ash pit area.		
Waste Type:	Ash		
Waste Description:	Unknown amounts of coal ash from the 184-F Powerhouse were sluiced to this unit with raw river water. The ash has been analyzed using the EP Toxicity Test in accordance with Washington Administrative Code (WAC 173-303), and no hazardous materials were found. This site also received low-level radionuclides from effluent system leakage. Radioactive contamination in excess of 50,000 counts/minute existed in the northwest corner of the pit.		
Closure Info:	Interim: Remedial action at the site began on October 5, 2001. Excavation of the site involved removing the overburden materials and underlying contaminated soil in the northern portion of		

the site only. Based on field screening, overburden materials identified as potentially clean were placed in a stockpile for potential use as backfill.

The excavation of the northern portion of the site was completed on June 17, 2002, it measured approximately 10,689 square meters (115,052 square feet) in area with a maximum depth of approximately 4 meters (13 feet). The average bottom elevation of the excavation was 119.8 meters (393.0 feet). A total of approximately 100,964 metric tons (111,313 tons) of contaminated material was disposed at ERDF.

Portions of the Ash Pit were contaminated by unplanned releases of 105-F Reactor cooling water effluent. The northern portion of the site has been remediated and backfilled with clean soil to adjacent grade elevations. No remedial action was necessary in the southern portion of the 126-F-1 site, but this portion of the site could not be closed out until radioactive decay occurred from the original sampling date in 2001 to 2007 to meet the radiological dose limit of 15 milirem/year above natural background. The reclassification form was signed on 9/20/2007.

Code:	128-F-1	Classification:	Accepted
Names:	128-F-1; 100-F Burning Pit; 100-F Burning Pit No. 1	Reclassification	Interim No Action (12/8/2003)
Type:	Burn Pit	Start Date:	1/1/1945
Status:	Inactive	End Date:	1/1/1965
Description:	The waste site has been evaluated and determined to require No Action. The burn pit was used to dispose of nonradioactive, combustible materials from the 100F Area. The site has been backfilled.		
Location:	The site was located directly east of the 126-F-1 Coal Ash Disposal Pile and west of the 118-F-5 Burial Ground.		
Waste Type:	Misc. Trash and Debris		
Waste Description:	The site was used for the disposal of nonradioactive, combustible materials, such as paint waste, office waste, and chemical solvents.		
Closure Info:	Interim: Based on geophysical survey data and field observations, the site was stratified into two areas for focused sample collection at locations suspected of having the greatest potential for residual contamination. Results from the underlying soil would be used to represent residual contaminant concentrations for cleanup verification. The field activities included excavation of two test trenches in Area 1 and excavation of two test pits in Area 2. During the activities in each area, excavated material was observed for the presence of ash but none was identified. Screening instruments (NaI detector and OVM) were used to focus sample collection towards areas of elevated contamination. No samples were collected in Area 2, because no contamination or debris was observed during excavation activities. Samples collected from Area 1 consisted of 15 soil aliquots that were combined into a single composite for laboratory analysis.		

The remedial decision for the 128-F-1 site is supported based on reviews of site history, field observations, geophysical survey results, and characterization results. Maximum detected results from soil samples collected at locations suspected of having the greatest potential for residual contamination levels were shown to meet the cleanup objectives for direct exposure, groundwater protection, and river protection.

Code:	128-F-3	Classification:	Accepted
--------------	---------	------------------------	----------

Names: 128-F-3; PNL Burn Pit **Reclassification** Interim Closed Out (10/20/2006)

Type: Burn Pit **Start Date:**

Status: Inactive **End Date:**

Description: The waste site has been remediated and Interim Closed Out. The burn pit is believed to have received waste from the Experimental Animal Farm.

Location: The site was located 25 meters (82 feet) south of the dirt access road that passed south of the 126-F-1 Ash Pit and approximately 70 meters (230 feet) west of the southeast corner of the ash pit.

Waste Type: Misc. Trash and Debris

Waste Description: It was not known what was burned at the site. However, Pacific Northwest Laboratory (PNL) and Westinghouse Hanford Company (WHC) employees verified that the site was used for burning. It was assumed the burned material came from the Experimental Animal Farm.

Closure Info: Interim: A geophysical survey was performed in March 2003 and identified an anomalous area devoid of metallic debris. During confirmatory sampling and site evaluation in April 2003 to make a decision as to whether remedial action would be required at the site, two test trenches were excavated. Conclusive evidence of a burn pit could not be located. Additionally, significant matrix interference problems were encountered during analysis of coal ash samples. The surface had a thin layer of coal and coal ash mixed with fine sandy soil. Scraping the surface a few inches revealed black ash or coal dust. Nothing on the soil surface distinguished this site from other coal ash dumping sites found along the dirt road just south of the ash disposal pit.

Remediation was performed on September 20, 2005. It consisted of the removal of coal ash and surrounding soil associated with excavation of the geophysical anomaly. The excavation was also performed to assure no residual debris or ash associated with historical burning was present at the site. During remediation, a limited amount of wood debris and ash associated with burning was found and removed. The excavation proceeded to a depth of approximately 1.1 meters (3.5 feet) within the site boundary. Approximately 690 metric tons (760 US tons) of coal ash, burn ash, debris, and soil was removed to Environmental Restoration Disposal Facility.

The site has been evaluated and remediated in accordance with the Remaining Sites ROD and the RDR/RAWP. Statistical and judgmental sampling to verify the completeness of remediation was performed, and analytical results were shown to meet the cleanup objectives for direct exposure, groundwater protection, and river protection. In accordance with this evaluation, the verification sampling results support a reclassification to interim closed out.

Code: 1607-F1 **Classification:** Accepted

Names: 1607-F1; 1607-F1 Sanitary Sewer System; 1607-F1 Septic Tank; 1607-F1 Septic Tank and Associated Drain Field; 100-F Experimental Animal Farm Septic Tank; 124-F-1 **Reclassification** Interim Closed Out (3/14/2008)

Type: Septic Tank **Start Date:** 1/1/1944

Status: Inactive **End Date:** 1/1/1965

Description: The septic tank, drain field and associated have been remediated and Interim Closed Out. The septic tank was constructed of reinforced concrete. The walls and floor were 25 centimeters (10 inches) thick. The septic tank had a capacity of 16561.18 liters (4375 gallons). The system could support 125 persons assuming input of 130 liters (35 gallons) per capita per day and a

one day retention period. The drain field was constructed of 10-centimeter (4-inch) vitrified pipe, concrete pipe, or drain tile with a total of 304.8 meters (1000 linear feet) of piping (2.4 linear meters [8 linear feet] per capita). The four laterals were open jointed, 38 meters (125 feet) long, and spaced 2.4 meters (8 feet) apart.

Location: The 1607-F1 Septic Tank was located south of the 105-F Reactor Building. The septic tank and drain field are approximately 91.4 meters (300 feet) west of the 1720-F Building.

Related Sites/ Structures: The site was related to 100-F-26:8 Influent pipelines, 1701-F Badge House (security checkpoint), the 1709-F Fire Station, and the 1720-F Administrative Office and change room for security patrol personnel.

Waste Type: Sanitary Sewage

Waste Description: This unit received an unknown amount of sanitary sewage from the 1701-F Badge House (security checkpoint), the 1709-F Fire Station, and the 1720-F Administrative Office and change room for security patrol personnel. Since the site was connected to administrative and support facilities (security and fire protection), the site should not have received hazardous contaminants.

Closure Info: Interim: Confirmatory sampling was performed at the 1607-F1 septic tank waste site on October 7, 2004. Three sample locations were identified in the work instruction for this site. One sample was collected from soil under the septic tank. Two samples were collected from the septic drain field. No sample of tank contents was collected, as the inside of the tank was previously cleaned and backfilled. At the 1607-F1 septic tank site, contaminants in the drain field and in the soil beneath the septic tank were below the remedial action goals (RAGs).

Confirmatory sampling of the 100-F-26:8 waste site was conducted on January 5, 2005. Samples of the scale inside the pipe and the soil beneath the pipe were collected. A pipe matrix calculation was prepared using the analytical results of the pipe scale sample. An evaluation of the pipe matrix calculations showed that benzo(a)pyrene exceeded the direct exposure RAG. Concentrations of some polychlorinated biphenyl (PCB) congeners, pesticides, and semivolatile organic compounds (SVOCs) also exceeded the groundwater and river protection RAGs. These confirmatory sample results indicated that the 100-F-26:8 waste site required remedial action due to benzo(a)pyrene present at levels exceeding remedial action goals for direct exposure.

Remediation of the 1607-F1 and 100-F-26:8 waste sites were performed from January 8 to April 3, 2007. Remedial activities included removal of the septic tank and the associated piping. Both sites were excavated to approximately 3.4 meters (11 feet) below grade resulting in a combined volume of approximately 464 cubic meters (607 cubic yards) of material stockpiled for disposal at the Environmental Restoration Disposal Facility (ERDF). Approximately 266 meters (872 feet) of pipeline were removed during remediation. During pipeline excavation, a french drain was discovered on the west side of the former 1709-F facility. Although this french drain was independent of the pipelines, it was removed.

100-HR-1

Code: 100-H-1 **Classification:** Accepted
Names: 100-H-1; Rod Cave **Reclassification:** Interim Closed Out (3/26/2001)
Type: Storage **Start Date:**
Status: Inactive **End Date:**

Description: This site was a rod cave and has been remediated and closed out. Other rod caves, such as the 105-C Horizontal Control Rod Cave and the 100-K Area Horizontal Control Rod Caves, consisted of sections of metal culvert pipe on a concrete pad with an earthen mound. This rod cave was not as advanced a construction as other rod caves, but was similar in construction. End walls at other rod caves were formed of concrete, but the end walls at this site were made of lead bricks.

Location: The site is located inside the 105-H Exclusion Area west of the railroad tracks, approximately 23 meters (75 feet) southwest of the southwest corner of the 105-H Reactor building.

Process Description: The cave was used during the operation of the 105-H Reactor for temporary storage of irradiated reactor control rods as well as tools used in control rod removal and installation.

Waste Type: Equipment

Waste Description: The site was contaminated from horizontal control rods and possibly other miscellaneous reactor facility components. The ends were constructed from lead bricks.

Closure Info: Interim: Remedial action at the 100-H-21 pipelines site began on October 19, 1999. Excavation of the site involved removing the overburden materials, pipelines (including miscellaneous small pipelines near the reactor building), the 100-H-1 rod cave structure, and underlying contaminated soil (100-H-22). Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Contaminated materials were disposed of at ERDF. Approximately 2,500 lead bricks from the end walls of the rod cave were surveyed for radiological release to allow the lead to be recycled.

On July 21, 2000, the majority of the excavation was completed. Because of elevated lead levels in an area of the site excavation, additional soil was excavated in December 2000. The general average depth of the bottom of the excavation in the deep zone sampling areas was 5.6 meters (18.4 feet) below ground surface. The majority of the site excavation depth was 4.6 meters (15 feet) or less below ground surface, generally corresponding with the former pipeline invert depth. The excavation was approximately 17,629 square meters (189,660 square feet) in area. Approximately 32,725 metric tons (35,998 tons) of material from the site were disposed of at ERDF.

Code: 100-H-3 **Classification:** Accepted
Names: 100-H-3; 1716-H Garage Fuel Tank Site **Reclassification:** Interim Closed Out (6/1/2011)
Type: Storage Tank **Start Date:** 1/1/1949
Status: Inactive **End Date:**

Description: The site may contain one or more underground storage tanks (USTs) from the 1716-H Garage. The garage has been demolished. Some disturbance of the concrete pavement is visible at the site.

Location: The 1716-H Garage was located west of the 107-H Retention Basin (116-H-7) and north of the 1717-H Combined Shops.

Related Sites/ Structures: The tanks supported the 1716-H Garage. The building is also associated with the 100-H-43 waste site.

Closure Info: Interim: The 100-H-3 waste site was remediated between December 21 and 30, 2009. Approximately 894 bank cubic meters (1,170 bank cubic yards) of soil and debris were removed from the site and disposed at the Environmental Restoration Disposal Facility. Remediation included removal of the pump island as well as the fuel supply lines. At the expected location of the tanks, the excavation continued until the approximate depth of 3.5 meters (11.5 ft) was reached. The adjacent french drain and debris at the former tank location were also removed. No soil staining or anomalous hazardous debris was noted during excavation.

Code: 100-H-4	Classification: Accepted
Names: 100-H-4; 1717-H Hot Shop; Contaminated Storage Unit; French Drain	Reclassification: Interim Closed Out (6/1/2011)
Type: Maintenance Shop	Start Date:
Status: Inactive	End Date:

Description: This waste site was remediated along with the 1717-H building. The french drain (FD13) was located northeast of the building footprint. It was excavated to a depth of approximately 4 meters (12 ft).

Location: The 1717-H Maintenance Shop was located west of the 107-H Basins and south of the 1716-H Service Station. The building has been demolished. An employee interview indicates a portion of the shop was used for working on very low-level radioactive materials. Drawing SK-1-7325 identifies two "hot shops." Drawing SK-1-7328 proposed a building addition, also designated as a "hot shop." Drawing P-9343 indicates an existing drywell.

Related Sites/ Structures: This drain is also associated with waste site 100-H-49:3.

Waste Type: Water

Waste Description:

Closure Info: Interim (6/1/2011): Remedial action at the 100-H-4, 1717-H Hot Shop, French Drain, and Contaminated Storage Unit waste site was performed between January 4 and 18, 2010. The excavation resulted in approximately 3,148 bank cubic meters (4,117 bank cubic yards [BCY]) of contaminated soil. All material was direct loaded for disposal at the Environmental Restoration Disposal Facility (ERDF).

The footprint of the 1717-H Building, including the 1717-H Hot Shop and the foundation wall, was excavated to a depth of approximately 1 meter (3 ft) below ground surface. The excavation activities included remediation of former locations of decontamination tanks and exterior exhaust, as per approved excavation design. The french drain located northeast of the building footprint was excavated to a depth of approximately 4 meters (12 ft). A concrete floor trap with metal lid and insulation piece was uncovered and removed. All pieces including the drainpipe were excavated and loaded out in a void-space waste disposal can for grout filling at ERDF. The process sewer line and the sanitary sewer line were completely removed within the 1717-H Building footprint and excavation boundary. Other materials and debris such as concrete and asphalt were excavated and removed from the waste site.

Due to remediation exceeding the excavation design dimensions, two additional features were

uncovered: a 6-in.-diameter cast iron (CI) pipeline running in the east-west direction to the northern side of the 1717-H footprint excavation and a Y-shaped concrete thrust block structure. These two features were left in place. Although not confirmed by historical drawings or historical aerial photographs, it is suspected that the 6 inch diameter cast iron pipeline is part of the 100-H-35, 100-H Clean Water Pipelines, 100-H Service Water Pipelines waste site. However, due to the lack of available historical information, this pipeline will be included with 100-H-56, H-Area Miscellaneous Pipelines. The Y-shaped thrust blocks do not encase any pipelines. These concrete thrust blocks do not appear on any historical drawings or historical aerial photographs.

Code:	100-H-5	Classification:	Accepted
Names:	100-H-5; 107-H Buried Sludge Site; 107-H Grave; 107-H Retention Basin Sludge Burial Site; Sludge Disposal Trench	Reclassification	Interim Closed Out (12/18/2000)
Type:	Burial Ground	Start Date:	1/1/1953
Status:	Inactive	End Date:	

Description: This site has been remediated and Interim Closed Out. The trench was about 100 meters (328 feet) long, 16 meters (52 feet) wide, and 4.6 meters (15 feet) deep.

Location: According to the Technical Baseline Report, the location of the trench was not clear. Several employees were interviewed for information related to the location of this site. They identified several potential locations, including farther north, immediately adjacent to the 107-H Retention Basin or further south and east of the southeast corner of 107-H. (Note the references in the technical baseline report are inverted). In 1997, a Ground Penetrating Radar (GPR) scan was done to establish the location of the trench. The GPR scan placed the trench approximately 52 meters (170 feet) east of the southeast corner of the 116-H-7 Basin, in an area formerly used for orchards. (Washington State Plane Coordinates N152624.63 E578156.95; N152629.13 E578172.30; N152533.16 E578200.42; N152528.66 E578185.06.)

Related Sites/ Structures: The 107-H Retention Basin (116-H-7) is related to this site.

Process Description: The site is a trench that received an unknown quantity of sludge removed from the 107-H Retention Basin during repair work in the Spring of 1953.

Waste Type: Sludge

Waste Description: In 1975, samples of sludge from the basin floor had a maximum Geiger-Mueller (GM) probe reading of 20,000 counts/minute. Samples had an average concentration of 3.1E+04 picocuries/gram beta/gamma and 57 picocuries/gram of plutonium-239/240. The sludge buried in the trench would have similar characteristics.

Closure Info: Interim (12/12/2000): The site was remediated to meet the cleanup standards and Interim Closed Out on December 12, 2000.

Remedial action at the 100-H-5 site began on September 27, 1999. Excavation of the site involved removing the overburden materials, buried sludge and debris, and underlying contaminated soil. Based on field screening overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Contaminated materials were disposed of at the Environmental Restoration Disposal Facility (ERDF). During site excavation, the area where buried sludge and debris were encountered at the south end of the site was not as wide as the estimated footprint of the sludge trench. To avoid unnecessarily excavating and disposing of uncontaminated soil, the excavation at the south end of the site narrowed from the original estimated design site footprint. On April 28, 2000, the excavation was completed.

The elevation of the bottom of the excavation was at 121.4 meters (398.2 feet) upon completion. The surface reference elevation and design backfill elevation are 126.5 meters (415 feet). The excavation was approximately 3,308 square meters (35,589 square feet) in area with a maximum depth of approximately 5.1 meters (16.7 feet). Approximately 23,525 metric tons (25,877 tons) of material from the site were disposed of at ERDF.

The 100-H-5 site has been verified to be remediated in accordance with the ROD amendment.

Code: 100-H-7	Classification: Accepted
Names: 100-H-7; French Drain A	Reclassification: Interim No Action (7/28/2009)
Type: French Drain	Start Date:
Status: Inactive	End Date:
Description: The site has been evaluated and determined to require No Action. It consists of a french drain and an adjoining pipeline. It is a vertical, 76-centimeter (30-inch) diameter vitrified clay pipe with a metal lid. Its upper surface is at grade. A 6.3 centimeter (2.5 inch) steel pipe exits the reactor building at a point in line with the drain, suggesting the possibility of drainage from the 105-H Building to the drain. The drain had no markings.	
Location: The site was located south-southeast of the northeast corner of the 105-H reactor building.	
Related Sites/ Structures: The drain was associated with the 105-H Reactor Building.	
Waste Type: Process Effluent	
Waste Description:	
Closure Info: Interim: Prior to confirmatory sampling activities, it was not known if demolition and decommissioning of the 105-H Reactor Building also removed the 100-H-7 waste site. A geophysical survey was performed for the purpose of obtaining an excavation permit. The results did not detect the french drain, but did show the site to be an area of scattered buried debris and possible buried utilities. During confirmatory sampling activities, the french drain was found intact (minus the metal lid). The drain pipe from the 105-H building was also found in place, connected to the 100-H-7 french drain. No elevated volatile organic compounds or radiological readings were detected. The test pit excavation was approximately 3.7 meters (12 ft) deep.	

Code: 100-H-8	Classification: Accepted
Names: 100-H-8; French Drain B	Reclassification: Interim No Action (12/3/2009)
Type: French Drain	Start Date:
Status: Inactive	End Date:
Description: The site has been evaluated and determined to require No Action. It consisted of as a 91-centimeter (36-inch) diameter concrete pipe with a steel lid. The drain was buried vertically with its upper surface at grade and was filled with gravel to within 20 centimeters (8 inches) of its top. Prior to site evaluation the drain was surrounded by a rope and posts and signs that read "Danger - Keep Out".	
Location: The unit is located east-southeast of the northeast corner of the 105-H Reactor Building.	

Related Sites/ Structures: This site was associated with the 105-H reactor building.

Process Description: During site evaluation, it was determined that this drain was designed and used to collect steam condensate from a former overhead steam line that serviced the emergency cooling water tower located on the northeast side of the 105-H Reactor Building. Sanitary river water was supplied to the 184-H power house, where it was converted to steam by the boiler and carried through aboveground steam lines to the 100-H Area facilities. Boiler water may have been treated with sodium sulfate, trisodium phosphate, and/or chromates.

Waste Type: Process Effluent

Waste Description:

Closure Info: Interim: Confirmatory sampling was performed in November 2008. Excavation of the site revealed the french drain was in place and largely intact. The metal lid was not in place. Inside the french drain were leach rocks that were stained red. There was no fine sediment inside the drain to sample. No elevated VOCs or radiological readings were detected on the french drain contents. Several pipes of various sizes were found during the excavation. None were intact or in service. Based on the location and size of the pipes they were determined to be either water or steam lines. No material was evident in the pipes to sample. No elevated VOCs or radiological readings were detected. The discovered pipes were left in the excavation when it was backfilled.

The vertical concrete pipe comprising the french drain was found to extend to a depth of approximately 3.7 meters (12-ft). Directly below the drain, red stained soil was visible extending to the bottom of the excavation. The red stain also extended horizontally in a thin layer around the sides of the excavation. The color of the stained soil beneath the french drain matched the stain on the rocks within the drain. A primary and duplicate sample was collected of the stained soil directly below the drain. The material present inside the drain consisted of only rock with no fine grained material and therefore was not amenable for sample collection.

Code: 100-H-9	Classification: Accepted
Names: 100-H-9; French Drain C	Reclassification: Interim Closed Out (6/22/2006)
Type: French Drain	Start Date:
Status: Inactive	End Date:

Description: The site has been remediated and Interim Closed Out along with 118-H-6:2 waste site. The waste site consisted of a vertical 61 centimeter (24 inch) diameter concrete pipe with a rusted metal lid. The drain had no markings.

Location: The unit was located east of the northeast corner of the 105-H Reactor Building, adjacent to the north wall.

Related Sites/ Structures: This unit was associated with the 105-H Reactor Building (sitecode 118-H-6).

Waste Type: Process Effluent

Waste Description:

Closure Info: Interim: Removal and disposal activities at the 105-H site (118-H-6:2, 118-H-6:3, 118-H-6:6 subsites) were completed in 2004. D&D activities, in preparation for the construction of

the 105-H Reactor SSE, also resulted in the removal of 100-H-9, 100-H-10, 100-H-11, 100-H-12, 100-H-13, 100-H-14 french drains and the 100-H-31 electrical transformer soil. All materials from the 105-H Reactor ISS Project were demolished and disposed at ERDF. The overburden piles produced during excavation were found to be contaminated. The overburden was deemed unsuitable for use as backfill of the site and was removed to ERDF.

The site was backfilled with clean soil aggregate from the 100-D Area Borrow Pit 21 and graded to match the surrounding terrain. This 105-H D&D activity generated approximately 4,863 bulk containers of low-level contaminated material that were shipped to ERDF, accounting for approximately 73,966 metric tons (81,365 tons).

Per the Sampling and Analysis Plan, the 105 H Reactor ancillary support areas and below-grade structures (118-H-6:2) did not require sampling and analysis because the structures were removed in their entirety and then disposed at the Environmental Restoration Disposal Facility (ERDF). During the D&D activities, an additional evaluation was required to determine if the soils under the Fuel Storage Basin (FSB) floor (118-H-6:3) had achieved the RAGs. The evaluation of the FSB soils and deep zone side-slope soils (118-H-6:6) also evaluated the soils under the 100-H-11, 100-H-12, and 100-H-14 waste sites. Radiological surveys and verification sampling analysis were performed on the FSB underlying soils and deep zone side-slope soils. The data was used with the RESRAD computer model to verify that cleanup criteria were satisfied. Localized contamination was removed in preparation for clean demolition, and a fixative was applied as required. With one exception, no below-grade structures remaining. The exception is a portion of the FSB floor, at its northern end between the two access labyrinths to the D elevator. It was not removed with this activity.

Verification soil samples were collected from soils under the FSB floor. All demolition debris from excavations associated with the activity was sent to ERDF. Final cleanup verification samples for the FSB underlying soils and deep zone side-slope soils were collected following evaluation of field screening for radiological contaminants using global positioning environmental radiological surveyor (GPERS) and laser-assisted ranging and data system (LARADS) surveys. This field screening was performed in order to obtain an initial assessment of attainment of radiological cleanup levels

The remaining soils at the 105-H Reactor site were either been deferred to the Field Remediation Closure Project or have been shown to meet the applicable RAGs through verification sampling, analysis, and RESRAD modeling. All excavated materials generated during the D activities were disposed at ERDF, and the area was backfilled to grade with clean backfill. These results also indicate that residual concentrations in the shallow zone will support future land uses that can be represented (or bounded) by a rural-residential scenario and that residual concentrations throughout the site pose no threat to groundwater or the Columbia River.

The three decontamination pads (118-H-6:5) and the Fuel Storage Basin shallow side-slope soils (118-H-6:4) were deferred to the Field Remediation Closure Project and remediated at a later date.

Code: 100-H-10	Classification: Accepted
Names: 100-H-10; French Drain D	Reclassification: Interim Closed Out (6/22/2006)
Type: French Drain	Start Date:
Status: Inactive	End Date:
Description: The site has been remediated and Interim Closed Out with 118-H-6:2. The unit consisted of a vertically buried 122-centimeter (48-inch) diameter vitrified clay pipe with a steel lid. It was suspected to be a french drain. The unit had no markings.	

Location: The unit was located north of the center point of the 105-H Reactor Building, adjacent to the north wall.

Related Sites/ Structures: The drain was associated with the 105-H Reactor building (sitecode 118-H-6).

Waste Type: Process Effluent

Waste Description:

Closure Info: Interim: Removal and disposal activities at the 105-H site (118-H-6:2, 118-H-6:3, 118-H-6:6 subsites) were completed in 2004. D&D activities, in preparation for the construction of the 105-H Reactor SSE, also resulted in the removal of 100-H-9, 100-H-10, 100-H-11, 100-H-12, 100-H-13, 100-H-14 french drains and the 100-H-31 electrical transformer soil. All materials from the 105-H Reactor ISS Project were demolished and disposed at ERDF. The overburden piles produced during excavation were found to be contaminated. The overburden was deemed unsuitable for use as backfill of the site and was removed to ERDF.

The site was backfilled with clean soil aggregate from the 100-D Area Borrow Pit 21 and graded to match the surrounding terrain. This 105-H D&D activity generated approximately 4,863 bulk containers of low-level contaminated material that were shipped to ERDF, accounting for approximately 73,966 metric tons (81,365 tons).

Per the Sampling and Analysis Plan, the 105 H Reactor ancillary support areas and below-grade structures (118-H-6:2) did not require sampling and analysis because the structures were removed in their entirety and then disposed at the Environmental Restoration Disposal Facility (ERDF). During the D&D activities, an additional evaluation was required to determine if the soils under the Fuel Storage Basin (FSB) floor (118-H-6:3) had achieved the RAGs. The evaluation of the FSB soils and deep zone side-slope soils (118-H-6:6) also evaluated the soils under the 100-H-11, 100-H-12, and 100-H-14 waste sites. Radiological surveys and verification sampling analysis were performed on the FSB underlying soils and deep zone side-slope soils. The data was used with the RESRAD computer model to verify that cleanup criteria were satisfied. Localized contamination was removed in preparation for clean demolition, and a fixative was applied as required. With one exception, no below-grade structures remaining. The exception is a portion of the FSB floor, at its northern end between the two access labyrinths to the D elevator. It was not removed with this activity.

Verification soil samples were collected from soils under the FSB floor. All demolition debris from excavations associated with the activity was sent to ERDF. Final cleanup verification samples for the FSB underlying soils and deep zone side-slope soils were collected following evaluation of field screening for radiological contaminants using global positioning environmental radiological surveyor (GPERS) and laser-assisted ranging and data system (LARADS) surveys. This field screening was performed in order to obtain an initial assessment of attainment of radiological cleanup levels

The remaining soils at the 105-H Reactor site were either been deferred to the Field Remediation Closure Project or have been shown to meet the applicable RAGs through verification sampling, analysis, and RESRAD modeling. All excavated materials generated during the D activities were disposed at ERDF, and the area was backfilled to grade with clean backfill. These results also indicate that residual concentrations in the shallow zone will support future land uses that can be represented (or bounded) by a rural-residential scenario and that residual concentrations throughout the site pose no threat to groundwater or the Columbia River.

The three decontamination pads (118-H-6:5) and the Fuel Storage Basin shallow side-slope soils (118-H-6:4) were deferred to the Field Remediation Closure Project and remediated at a

later date.

Code: 100-H-11	Classification: Accepted
Names: 100-H-11; Expansion Box French Drain; French Drain E	Reclassification: Interim Closed Out (6/22/2006)
Type: French Drain	Start Date:
Status: Inactive	End Date:

Description: The site has been remediated and Interim Closed Out along with 118-H-6:3. The waste site was a french drain that had no markings.

Location: The unit was located next to the west wall of the south wing of the 105-H Reactor Building.

Related Sites/ Structures: The site was associated with the 105-H Reactor Building (sitecode 118-H-6).

Process Description: This unit was a vertical 0.76 meters (30-inch) diameter steel manhole set in concrete that provided access to it. It appeared to be a french drain (drain) located at the bottom of a concrete expansion box in which a 1.52 meters (60-inch) steel effluent line made a 40-degree turn to the southwest. The 100 H-11 french drain provided drainage for any leakage that might have occurred from the effluent line within the expansion box.

Closure Info: Interim: Removal and disposal activities at the 105-H site (118-H-6:2, 118-H-6:3, 118-H-6:6 subsites) were completed in 2004. D&D activities, in preparation for the construction of the 105-H Reactor SSE, also resulted in the removal of 100-H-9, 100-H-10, 100-H-11, 100-H-12, 100-H-13, 100-H-14 french drains and the 100-H-31 electrical transformer soil. All materials from the 105-H Reactor ISS Project were demolished and disposed at ERDF. The overburden piles produced during excavation were found to be contaminated. The overburden was deemed unsuitable for use as backfill of the site and was removed to ERDF.

The site was backfilled with clean soil aggregate from the 100-D Area Borrow Pit 21 and graded to match the surrounding terrain. This 105-H D&D activity generated approximately 4,863 bulk containers of low-level contaminated material that were shipped to ERDF, accounting for approximately 73,966 metric tons (81,365 tons).

Per the Sampling and Analysis Plan, the 105 H Reactor ancillary support areas and below-grade structures (118-H-6:2) did not require sampling and analysis because the structures were removed in their entirety and then disposed at the Environmental Restoration Disposal Facility (ERDF). During the D&D activities, an additional evaluation was required to determine if the soils under the Fuel Storage Basin (FSB) floor (118-H-6:3) had achieved the RAGs. The evaluation of the FSB soils and deep zone side-slope soils (118-H-6:6) also evaluated the soils under the 100-H-11, 100-H-12, and 100-H-14 waste sites. Radiological surveys and verification sampling analysis were performed on the FSB underlying soils and deep zone side-slope soils. The data was used with the RESRAD computer model to verify that cleanup criteria were satisfied. Localized contamination was removed in preparation for clean demolition, and a fixative was applied as required. With one exception, no below-grade structures remaining. The exception is a portion of the FSB floor, at its northern end between the two access labyrinths to the D elevator. It was not removed with this activity.

Verification soil samples were collected from soils under the FSB floor. All demolition debris from excavations associated with the activity was sent to ERDF. Final cleanup verification samples for the FSB underlying soils and deep zone side-slope soils were collected following evaluation of field screening for radiological contaminants using global positioning environmental radiological surveyor (GPERS) and laser-assisted ranging and data system

(LARADS) surveys. This field screening was performed in order to obtain an initial assessment of attainment of radiological cleanup levels

The remaining soils at the 105-H Reactor site were either been deferred to the Field Remediation Closure Project or have been shown to meet the applicable RAGs through verification sampling, analysis, and RESRAD modeling. All excavated materials generated during the D activities were disposed at ERDF, and the area was backfilled to grade with clean backfill. These results also indicate that residual concentrations in the shallow zone will support future land uses that can be represented (or bounded) by a rural-residential scenario and that residual concentrations throughout the site pose no threat to groundwater or the Columbia River.

The three decontamination pads (118-H-6:5) and the Fuel Storage Basin shallow side-slope soils (118-H-6:4) were deferred to the Field Remediation Closure Project and remediated at a later date.

Code:	100-H-12	Classification:	Accepted
Names:	100-H-12; Expansion Box French Drain F and Shielding Lead	Reclassification	Interim Closed Out (6/22/2006)
Type:	French Drain	Start Date:	
Status:	Inactive	End Date:	
Description:	The site has been remediated and Interim Closed Out along with 118-H-6:3. The site consisted of a french drain, accessed through a 0.76-meter (30-inch) vertical steel manhole set in a concrete pad.		
Location:	The site was located in the corner formed by the east wall of the south wing and the south wall of the east wing of the 105-H Reactor Building. The drain was at the bottom of a concrete expansion box.		
Related Sites/ Structures:	The site was associated with the 105-H Reactor Building (sitecode 118-H-6), the radioactive process effluent pipelines and 100-H-11 (Expansion Box drain E).		
Process Description:	The site consisted of a french drain, accessed through a 0.76-meter (30-inch) vertical steel manhole set in a concrete pad. The french drain was located at the bottom of a concrete expansion box, in which a 1.5-meter (60-inch) steel reactor effluent pipeline made a 90-degree turn from south to east. The french drain appeared to have been installed to provide drainage for any leakage that might have occurred in the expansion box. The drain had no markings.		
Waste Type:	Process Effluent		
Waste Description:	The french drain may have received radioactive process effluent.		
Closure Info:	Interim: Removal and disposal activities at the 105-H site (118-H-6:2, 118-H-6:3, 118-H-6:6 subsites) were completed in 2004. D&D activities, in preparation for the construction of the 105-H Reactor SSE, also resulted in the removal of 100-H-9, 100-H-10, 100-H-11, 100-H-12, 100-H-13, 100-H-14 french drains and the 100-H-31 electrical transformer soil. All materials from the 105-H Reactor ISS Project were demolished and disposed at ERDF. The overburden piles produced during excavation were found to be contaminated. The overburden was deemed unsuitable for use as backfill of the site and was removed to ERDF.		
	The site was backfilled with clean soil aggregate from the 100-D Area Borrow Pit 21 and graded to match the surrounding terrain. This 105-H D&D activity generated approximately 4,863 bulk containers of low-level contaminated material that were shipped to ERDF, accounting for approximately 73,966 metric tons (81,365 tons).		

Per the Sampling and Analysis Plan, the 105 H Reactor ancillary support areas and below-grade structures (118-H-6:2) did not require sampling and analysis because the structures were removed in their entirety and then disposed at the Environmental Restoration Disposal Facility (ERDF). During the D&D activities, an additional evaluation was required to determine if the soils under the Fuel Storage Basin (FSB) floor (118-H-6:3) had achieved the RAGs. The evaluation of the FSB soils and deep zone side-slope soils (118-H-6:6) also evaluated the soils under the 100-H-11, 100-H-12, and 100-H-14 waste sites. Radiological surveys and verification sampling analysis were performed on the FSB underlying soils and deep zone side-slope soils. The data was used with the RESRAD computer model to verify that cleanup criteria were satisfied. Localized contamination was removed in preparation for clean demolition, and a fixative was applied as required. With one exception, no below-grade structures remaining. The exception is a portion of the FSB floor, at its northern end between the two access labyrinths to the D elevator. It was not removed with this activity.

Verification soil samples were collected from soils under the FSB floor. All demolition debris from excavations associated with the activity was sent to ERDF. Final cleanup verification samples for the FSB underlying soils and deep zone side-slope soils were collected following evaluation of field screening for radiological contaminants using global positioning environmental radiological surveyor (GPERS) and laser-assisted ranging and data system (LARADS) surveys. This field screening was performed in order to obtain an initial assessment of attainment of radiological cleanup levels

The remaining soils at the 105-H Reactor site were either been deferred to the Field Remediation Closure Project or have been shown to meet the applicable RAGs through verification sampling, analysis, and RESRAD modeling. All excavated materials generated during the D activities were disposed at ERDF, and the area was backfilled to grade with clean backfill. These results also indicate that residual concentrations in the shallow zone will support future land uses that can be represented (or bounded) by a rural-residential scenario and that residual concentrations throughout the site pose no threat to groundwater or the Columbia River.

The three decontamination pads (118-H-6:5) and the Fuel Storage Basin shallow side-slope soils (118-H-6:4) were deferred to the Field Remediation Closure Project and remediated at a later date.

Code:	100-H-13	Classification:	Accepted
Names:	100-H-13; French Drain G	Reclassification	Interim Closed Out (6/22/2006)
Type:	French Drain	Start Date:	
Status:	Inactive	End Date:	
Description:	The site has been remediated and Interim Closed Our with 118-H-6:2. The site consisted of a french drain that was constructed of vitrified clay pipe and covered by two metal lids (the second metal lid positioned 15.2 centimeters [6 inches] below the first).		
Location:	The site was located on the east side of the 105-H Reactor Building, 5.5 meters (18 feet) south of the ramp, and 6.1 meters (20 feet) east of the east wall of the 105-H Reactor Building.		
Related Sites/ Structures:	This unit was associated with the 105-H Reactor Building (sitecode 118-H-6).		
Process Description:	The site had a metal lid with a second metal lid located 15.2 centimeters (6 inches) below the first. A 6.3-centimeter (2.5-inch) stainless steel pipe emerged from the 105-H Reactor Building wall, ran downward to the surface, and disappeared at a point in approximate alignment with the site. An asphalt surface repair mark ran through the asphalt from the point where the		

pipeline entered the ground to the french drain. This suggests the possibility of drainage from the Reactor Building. Hanford Site drawings do not identify this drain or its purpose.

Waste Type: Process Effluent

Waste Description: The site is suspected of having received drainage from the 105-H Reactor Building.

Closure Info: Interim: Removal and disposal activities at the 105-H site (118-H-6:2, 118-H-6:3, 118-H-6:6 subsites) were completed in 2004. D&D activities, in preparation for the construction of the 105-H Reactor SSE, also resulted in the removal of 100-H-9, 100-H-10, 100-H-11, 100-H-12, 100-H-13, 100-H-14 french drains and the 100-H-31 electrical transformer soil. All materials from the 105-H Reactor ISS Project were demolished and disposed at ERDF. The overburden piles produced during excavation were found to be contaminated. The overburden was deemed unsuitable for use as backfill of the site and was removed to ERDF.

The site was backfilled with clean soil aggregate from the 100-D Area Borrow Pit 21 and graded to match the surrounding terrain. This 105-H D&D activity generated approximately 4,863 bulk containers of low-level contaminated material that were shipped to ERDF, accounting for approximately 73,966 metric tons (81,365 tons).

Per the Sampling and Analysis Plan, the 105 H Reactor ancillary support areas and below-grade structures (118-H-6:2) did not require sampling and analysis because the structures were removed in their entirety and then disposed at the Environmental Restoration Disposal Facility (ERDF). During the D&D activities, an additional evaluation was required to determine if the soils under the Fuel Storage Basin (FSB) floor (118-H-6:3) had achieved the RAGs. The evaluation of the FSB soils and deep zone side-slope soils (118-H-6:6) also evaluated the soils under the 100-H-11, 100-H-12, and 100-H-14 waste sites. Radiological surveys and verification sampling analysis were performed on the FSB underlying soils and deep zone side-slope soils. The data was used with the RESRAD computer model to verify that cleanup criteria were satisfied. Localized contamination was removed in preparation for clean demolition, and a fixative was applied as required. With one exception, no below-grade structures remaining. The exception is a portion of the FSB floor, at its northern end between the two access labyrinths to the D elevator. It was not removed with this activity.

Verification soil samples were collected from soils under the FSB floor. All demolition debris from excavations associated with the activity was sent to ERDF. Final cleanup verification samples for the FSB underlying soils and deep zone side-slope soils were collected following evaluation of field screening for radiological contaminants using global positioning environmental radiological surveyor (GPERS) and laser-assisted ranging and data system (LARADS) surveys. This field screening was performed in order to obtain an initial assessment of attainment of radiological cleanup levels

The remaining soils at the 105-H Reactor site were either been deferred to the Field Remediation Closure Project or have been shown to meet the applicable RAGs through verification sampling, analysis, and RESRAD modeling. All excavated materials generated during the D activities were disposed at ERDF, and the area was backfilled to grade with clean backfill. These results also indicate that residual concentrations in the shallow zone will support future land uses that can be represented (or bounded) by a rural-residential scenario and that residual concentrations throughout the site pose no threat to groundwater or the Columbia River.

The three decontamination pads (118-H-6:5) and the Fuel Storage Basin shallow side-slope soils (118-H-6:4) were deferred to the Field Remediation Closure Project and remediated at a later date.

Code: 100-H-14 **Classification:** Accepted
Names: 100-H-14; Surface Contamination Zone H **Reclassification** Interim Closed Out (6/22/2006)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The site has been remediated and Interim Closed Out along with 118-H-6:3. The site consisted of an area of surface contamination located next to the south wall of the 105-H Reactor Building fuel storage basin (FSB). The area had been surface stabilized with 46 to 61 centimeters (18 to 24 inches) of gravel and cobbles.

Location: The site was located inside the exclusion area, on the southeast side of 105-H.

Related Sites/ Structures: The site was associated with the 105-H Reactor Building (sitecode 118-H-6).

Process Description: Drawing P-1758 indicated the room behind the wooden door was a wash pad.

Waste Type: Chemical Release

Waste Description: No documentation has been found to identify the source of the contamination or describe the stabilization activity.

Closure Info: Interim: Removal and disposal activities at the 105-H site (118-H-6:2, 118-H-6:3, 118-H-6:6 subsites) were completed in 2004. D&D activities, in preparation for the construction of the 105-H Reactor SSE, also resulted in the removal of 100-H-9, 100-H-10, 100-H-11, 100-H-12, 100-H-13, 100-H-14 french drains and the 100-H-31 electrical transformer soil. All materials from the 105-H Reactor ISS Project were demolished and disposed at ERDF. The overburden piles produced during excavation were found to be contaminated. The overburden was deemed unsuitable for use as backfill of the site and was removed to ERDF.

The site was backfilled with clean soil aggregate from the 100-D Area Borrow Pit 21 and graded to match the surrounding terrain. This 105-H D&D activity generated approximately 4,863 bulk containers of low-level contaminated material that were shipped to ERDF, accounting for approximately 73,966 metric tons (81,365 tons).

Per the Sampling and Analysis Plan, the 105 H Reactor ancillary support areas and below-grade structures (118-H-6:2) did not require sampling and analysis because the structures were removed in their entirety and then disposed at the Environmental Restoration Disposal Facility (ERDF). During the D&D activities, an additional evaluation was required to determine if the soils under the Fuel Storage Basin (FSB) floor (118-H-6:3) had achieved the RAGs. The evaluation of the FSB soils and deep zone side-slope soils (118-H-6:6) also evaluated the soils under the 100-H-11, 100-H-12, and 100-H-14 waste sites. Radiological surveys and verification sampling analysis were performed on the FSB underlying soils and deep zone side-slope soils. The data was used with the RESRAD computer model to verify that cleanup criteria were satisfied. Localized contamination was removed in preparation for clean demolition, and a fixative was applied as required. With one exception, no below-grade structures remaining. The exception is a portion of the FSB floor, at its northern end between the two access labyrinths to the D elevator. It was not removed with this activity.

Verification soil samples were collected from soils under the FSB floor. All demolition debris from excavations associated with the activity was sent to ERDF. Final cleanup verification samples for the FSB underlying soils and deep zone side-slope soils were collected following evaluation of field screening for radiological contaminants using global positioning environmental radiological surveyor (GPERS) and laser-assisted ranging and data system

(LARADS) surveys. This field screening was performed in order to obtain an initial assessment of attainment of radiological cleanup levels

The remaining soils at the 105-H Reactor site were either been deferred to the Field Remediation Closure Project or have been shown to meet the applicable RAGs through verification sampling, analysis, and RESRAD modeling. All excavated materials generated during the D activities were disposed at ERDF, and the area was backfilled to grade with clean backfill. These results also indicate that residual concentrations in the shallow zone will support future land uses that can be represented (or bounded) by a rural-residential scenario and that residual concentrations throughout the site pose no threat to groundwater or the Columbia River.

The three decontamination pads (118-H-6:5) and the Fuel Storage Basin shallow side-slope soils (118-H-6:4) were deferred to the Field Remediation Closure Project and remediated at a later date.

Code: 100-H-17	Classification: Accepted
Names: 100-H-17; 116-H-2 Trench Overflow	Reclassification: Interim Closed Out (3/1/2001)
Type: Unplanned Release	Start Date: 1/1/1953
Status: Inactive	End Date:

Description: This site has been remediated and closed out.

Location: The site was located in a triangular area bounded by railroad tracks, south of the 116-H-2 Liquid Waste Disposal Trench.

Process Description: In 1953, the 116-H-2 (also known as 1608-H) Liquid Waste Disposal Trench overflowed and flooded the triangular area bounded by the railroad tracks.

Waste Type: Water

Waste Description: The technical baseline report lists 116-H-2 contaminants as including cobalt-60, cesium-134, cesium-137, europium-152, europium-154, europium-155, tritium, plutonium-239, plutonium-240, strontium-90, uranium-235, and uranium-238. Waste site COCs identified through process knowledge were listed in the 100 Area Remedial Action Sampling and Analysis Plan (DOE-RL 1998). The COCs identified for this site in the CVP consist of plutonium-239/240, uranium-238, strontium-90, cesium-137, cobalt-60, europium-152, europium-154, and hexavalent chromium.

Closure Info: Interim: This area is located in an area that, prior to World War II and formation of the Hanford Site, was occupied by fruit tree orchards.

Remedial action at the 100-H-17 sites group (100-H-17, 100-H-30, 100-H-2 and 116-H-2) began on February 2, 2000. The sites were grouped together for remediation because of location and similar contaminants. Excavation of the area involved removing the overburden materials, miscellaneous debris, the contaminated structure, and underlying contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Contaminated materials were disposed of at ERDF. On February 10, 2000, the excavation was completed.

No evidence of buried waste was found during the excavation of the 100-H-2 site.

At the completion of the remedial action, the total excavation was approximately 6,240 square meters (67,170 square feet) in area with a maximum depth of approximately 2.6 meters (8.5 feet). Approximately 19,920 metric tons (21,960 tons) of material from the site were disposed

of at the ERDF.

Code: 100-H-21	Classification: Accepted
Names: 100-H-21; 100-H Reactor Cooling Water Effluent Underground Pipelines	Reclassification: Interim Closed Out (3/19/2001)
Type: Radioactive Process Sewer	Start Date: 1/1/1949
Status: Inactive	End Date: 1/1/1965

Description: This pipeline site has been remediated and was closed out in March 2001. The site was the underground 100-H Reactor cooling water effluent lines. It included the effluent lines that transported 105-H Reactor cooling water from the reactor to the 116-H-7 (107-H) Retention Basin, and from the basin to the 116-H-5 (1904-H) Outfall Structure and/or to the 116-H-1 Trench. This waste site included all associated expansion and valve boxes. It excluded the retention basin, outfall structure, and the effluent lines that are within the confines of the 105-H Reactor Building. It also excluded all reactor influent lines that are upstream of the reactor building. The site also included the pipeline(s) from the 1608-H Waste Water Pumphouse to 116-H-2 (1608-H Liquid Waste Disposal Trench).

Location: The site is the location of all underground reactor effluent lines running from the 105-H Reactor Building to the 1904-H Outfall Structure. This includes segments between the reactor building and the retention basin, and between the basin and the outfall structure. It excludes the reactor building, retention basin, and outfall structure, each of which is treated as a unique waste site. Also included are the underground lines that run from the retention basin to the 116-H-1 Trench (running on the west side of 116-H-7) and from the 1608-H Waste Water Pumphouse to the 116-H-2 Trench.

Related Sites/ Structures: Related structures are the 105-H Reactor, the 1608-H Waste Water Pumphouse, the 116-H-7 (107-H) Retention Basin, the 116-H-1 and 116-H-2 Trenches, and the 116-H-5 (1904-H) Outfall.

Process Description: Effluent water passed from the reactor rear face and flowed via gravity through the underground effluent lines, junction boxes and diversion boxes to the retention basins where it was held up for a short period of time to allow thermal and radiological cooling before being released through the outfall structure to the Columbia River. During periods of reactor fuel cladding ruptures, some effluent was diverted to an open trench.

Waste Type: Process Effluent

Waste Description: The waste was contaminated steel piping, concrete, and soil. Reactor cooling water became radioactively contaminated as it passed through the reactor core. Activation products created in the water included calcium-41, chromium-51, and zinc-65. Activation products from the reactor core that were picked up and transported by the cooling water included tritium, carbon-14, cobalt-60, nickel-63, and europium-152/154/155. Fuel element fission products such as strontium-90, and cesium-137, as well as transuranics such as plutonium-239/240 were introduced into cooling water due to fuel cladding failures. Concentrations of radionuclides in cooling water during normal reactor operations were approximately 0.2 microcuries/liter. Concentrations of radionuclides built up in rust flakes and scale on the inner surfaces of the pipelines and in sludge in the diversion and junction boxes. Average beta-gamma concentrations for the effluent line scale and junction/diversion boxes were 83,000 and 120,000 picocuries/liter, respectively. Average plutonium-239/240 concentrations were 66 picocuries/gram for the effluent line scale and 720 picocuries/gram for the sludge at the bottom of the diversion and junction boxes. Direct readings of the bottom of the effluent lines averaged approximately 40,000 counts/minute with a Geiger-Mueller probe. Chemicals during water treatment included aluminum sulfate (alum), hydrated calcium oxide, sulfuric acid, chlorine, and sodium dichromate. Water pH was maintained at about 7.5, and the free chlorine

residual was approximately 0.2 milligrams/liter. The waste was any remaining process effluent and the contaminated pipelines.

Closure Info: Interim: Remedial action at the 100-H-21 pipelines site began on October 19, 1999. Excavation of the site involved removing the overburden materials, pipelines (including miscellaneous small pipelines near the reactor building), the 100-H-1 rod cave structure, and underlying contaminated soil (100-H-22). Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Contaminated materials were disposed of at ERDF. Approximately 2,500 lead bricks from the end walls of the rod cave were surveyed for radiological release to allow the lead to be recycled.

On July 21, 2000, the majority of the excavation was completed. Because of elevated lead levels in an area of the site excavation, additional soil was excavated in December 2000. The general average depth of the bottom of the excavation in the deep zone sampling areas was 5.6 meters (18.4 feet) below ground surface. The majority of the site excavation depth was 4.6 meters (15 feet) or less below ground surface, generally corresponding with the former pipeline invert depth. The excavation was approximately 17,629 square meters (189,660 square feet) in area. Approximately 32,725 metric tons (35,998 tons) of material from the site were disposed of at ERDF.

Code: 100-H-22	Classification: Accepted
Names: 100-H-22; Soil Contaminated by Effluent Line Leakage	Reclassification: Interim Closed Out (3/19/2001)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The release occurred from the reactor cooling effluent lines. Both the pipelines and the unplanned release to the soil have been remediated and cleaned up.

Location: The 100-H-22 Effluent Pipeline Leakage site is associated with general underground leaks from the cooling water effluent pipelines.

Release Description: Several sources indicate evidence of leaks in the underground 152-centimeter (60-inch) steel reactor cooling effluent lines. Dorian and Richards (UNI-946) indicates backhoe sampling was done in 1971. Excavated soil was less than detection levels with a Geiger-Mueller (GM) probe. UNI-946 documents 1975 characterization studies of the pipeline contents and borehole soil sample results for two holes drilled adjacent to the effluent lines.

Related Sites/Structures: The 107-H Retention Basin, 105-H Reactor, and 100-H-21 Effluent Pipelines are related to this unplanned release.

Waste Type: Process Effluent

Waste Description: Contaminants at the 100-H Area included plutonium, strontium, europium, cobalt, cesium, uranium, nickel, hexavalent chromium, lead, and arsenic.

Closure Info: Interim: Remedial action at the 100-H-21 pipelines site began on October 19, 1999. Excavation of the site involved removing the overburden materials, pipelines (including miscellaneous small pipelines near the reactor building), the 100-H-1 rod cave structure, and underlying contaminated soil (100-H-22). Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Contaminated materials were disposed of at ERDF. Approximately 2,500 lead bricks from the end walls of the rod cave were surveyed for radiological release to allow the lead to be recycled.

On July 21, 2000, the majority of the excavation was completed. Because of elevated lead

levels in an area of the site excavation, additional soil was excavated in December 2000. The general average depth of the bottom of the excavation in the deep zone sampling areas was 5.6 meters (18.4 feet) below ground surface. The majority of the site excavation depth was 4.6 meters (15 feet) or less below ground surface, generally corresponding with the former pipeline invert depth. The excavation was approximately 17,629 square meters (189,660 square feet) in area. Approximately 32,725 metric tons (35,998 tons) of material from the site were disposed of at ERDF.

Code:	100-H-24	Classification:	Accepted
Names:	100-H-24; 100-H-24 Substation; 151-H Electrical Facilities; 151-H Substation	Reclassification	Interim Closed Out (5/9/2001)
Type:	Electrical Substation	Start Date:	1/1/1948
Status:	Inactive	End Date:	1/1/1978

Description: The site has been remediated and closed out. The waste site is the area surrounding the demolished 151-H Substation. It included the 151-H Building and adjacent Switchyard. The former switchyard area had a layer of crushed gravel with several remaining concrete structures that had been used to support electrical equipment. Electrical conduit was observed protruding up from under the ground near the concrete structures. Two manholes appeared to provide access to the main electrical feeder cables that ran from the switchyard to the 151-H Building. These features were removed during the remedial action excavation of the site.

In the area of the former 151-H Building, the southwest corner of the building appears to be protruding through the ground surface and several pieces of rebar were visible to the north. An area of subsidence was also visible near the former northeast corner of the building. An inactive power pole structure exists off the northeast corner of the site. The railroad spur that serviced the switchyard area has been removed. A former chain link fence, that has been cut off and removed just above ground level, surrounds the site. Demolition debris, such as rebar and broken concrete, was observed in the area of the former 151-H Building.

Note: In 1991 soil samples were located at oil stained sites, adjacent to existing concrete transformer foundations. A site visit on 3/20/1996 observed that no oil spills or stains were visible at the site.

Location: The 151-H Substation site was located approximately 200 meters (656 feet) west northwest of the 105-H Reactor Building.

Related Sites/ Structures: The site was related to 100-H Area electrical utilities.

Process Description: Two power transformers at the 151-H Substation provided 13.8 kV (rated at 31,250 kVA) power to two distribution systems that serviced the 100-H Area from 1948 to about 1965.

Waste Type: Demolition and Inert Waste

Waste Description: The 151-H Building was demolished in 1978. The demolition debris was placed in the basement cavity and covered with earth.

Waste Type: Oil

Waste Description: The site contains polychlorinated biphenyls (PCBs) contaminated soil. Seven samples were taken from stained area around the transformer foundations. The sample results indicated the presence of PCBs, however, the PCB levels were below Toxic Substance Control Act cleanup levels.

Closure Info: Interim: Remedial actions began in November 1999 and were completed in December 2000.

Excavation of the site involved removing contaminated concrete, debris, and contaminated soil. Based on process knowledge and visual observation, the remaining portions (all below ground surface) of the 151-H Building concrete basement walls, foundation, and demolition debris did not require removal and were therefore left in place. The debris is from the demolition of the 151-H Building in 1978. Based on the history of operations at the H Area, the 151-H Building contained mechanical switchgear for control of electrical operations. Operational history, building demolition observations, and remedial action observations indicate that no hazardous materials were stored or used in the building and that there was no contamination associated with the building.

At completion the lowest elevation of the bottom of the excavation was at 121.9 meters (400 feet). The excavation was approximately 12,289.8 square meters (132,286.4 square feet) in area with a maximum depth of approximately 4.6 meters (15 feet). Approximately 19,924 metric tons (21,268 tons) of material from the site were disposed at the Environmental Restoration Disposal Facility (ERDF).

Code:	100-H-28	Classification:	Accepted
Names:	100-H-28; 100-H Water Treatment Facilities Underground Pipelines	Reclassification	Interim Closed Out (9/25/2015)
Type:	Process Sewer	Start Date:	1/1/1949
Status:	Inactive	End Date:	1/1/1965

Description: The waste site encompassed the upstream (pre-reactor) process sewers for the 100-H Reactor, including all underground water lines used to transport reactor cooling water between water treatment facilities and the 105-H Reactor Building. It included all underground lines running between buildings and those that run to drainage facilities and to the emergency cooling high tanks (water towers). It had been divided into eight subsites. All of the subsites have been reclassified, so the Parent Site is considered Interim Closed Out.

Subsite 1 was evaluated and determined to require No action.

Subsite 2 was remediated and Interim Closed Out

Subsite 3 was Interim Closed Out

Subsite 4 was remediated and Interim Closed Out.

Subsite 5 was Interim Closed Out.

Subsite 6 was evaluated and determined to require No action.

Subsite 7 was evaluated and determined to require No action.

Subsite 8 was evaluated and determined to require No action.

The pipelines excluded from 100-H-28 are the pipelines within the building footprints and all the pipelines that were downstream from the reactor building, (i.e., the lines that carried cooling water from the reactor to the retention basin, trench, and/or the river).

Location: The underground lines connect the 181-H River Pumphouse to the 182-H Reservoir, the 183-H Basins and Clearwells, the 190-H Buildings, and to the 105-H Reactor Building. Also, any underground drainage lines running from the water treatment buildings to the 116-H-5 Outfall Structure (1904-H Outfall) are included in this site.

Release

Description:

Related Sites/ Structures: The other pipeline sites at the 100-H Area are 100-H-21 (Reactor Cooling Water Effluent Underground Pipelines); 100-H-34, (River Effluent Pipeline); and 100-H-35, (Clean Water Underground Pipelines). Related structures are the 181-H River Pumphouse, the 182-H Settling Basin, the 190-H Water Treatment and Storage Tank Facility, and the 105-H Reactor.

Process Description: minerals, and pumped to the reactor core at a rate of 1.78E+05 liters (47,000 gallons) to 2.69E+05 liters (71,000 gallons) per minute.

Waste Type: Water

Waste Description: The waste is steel piping, concrete, and soil (if contaminants are present). Chemical additives to the reactor cooling water included aluminum sulfate (alum) with excess hydrated calcium oxide, sulfuric acid, chlorine, and sodium dichromate. Water pH was maintained at about 7.5, and the free chlorine residual was approximately 0.2 milligrams/liter.

This Site has the Following SubSites:

Code: 100-H-28:1
Names: 100-H-28:1; 184-H Power House Ash Sluicing Line

Code: 100-H-28:2
Names: 100-H-28:2; South Process Sewers

Code: 100-H-28:3
Names: 100-H-28:3; North Process Sewers

Code: 100-H-28:4
Names: 100-H-28:4; 1607-H1 Sanitary Sewer Pipeline

Code: 100-H-28:5
Names: 100-H-28:5; 1607-H2 Sanitary Sewer Pipelines

Code: 100-H-28:6
Names: 100-H-28:6; 182-H Reservoir Sump Drains

Code: 100-H-28:7
Names: 100-H-28:7; 183-H Process Water Lines

Code: 100-H-28:8
Names: 100-H-28:8; 190-H Process Water Lines

Code: 100-H-28:1	Classification: Accepted
Names: 100-H-28:1; 184-H Power House Ash Sluicing Line	Reclassification: Interim No Action (7/28/2009)
Type: Process Sewer	Start Date:
Status: Inactive	End Date:

Description: The subsite has been evaluated and determined to require No Action. It consisted of a single 0.20 meter (8-in.) Ashcolite pipeline. It was used to sluice coal ash from the 184-H boiler house to the 126-H-1 ash pit. The total length of the pipeline was approximately 265 meters (870 ft), with an approximate depth of 1.5 meters (5 ft) below existing grade.

Location: This pipeline was located between the east side of the former 184-H boiler house and the east side of the 126-H-1 ash pit. The ash pit is located due west of the 184-H Power House. The subsite exits the former 184-H Power House on the east side, runs north for 56.8 meters (186.3 ft), turns west, runs approximately 192 meters (630 ft) into the ash pit.

Waste Type: Ash

Waste Description: The waste was ash that was transferred through the pipeline from the 184-H Power House to the 188-H Ash Pit.

Closure Info: Interim: During excavation, a 0.20 meter (8-in.) diameter, steel pipeline was encountered. It

was broken at the end and filled with soil and gravel. Field observations of the end of the pipeline and the broken concrete slab determined the pipeline outfall had been demolished in place and backfilled. On September 24, 2008, at test pit 2, the excavator broke into the pipeline, no material was observed inside the pipeline. Therefore, no additional sampling was performed and the excavation was backfilled. To collect a soil sample, a decision was made to excavate below the concrete slab underlying the pipeline.

Confirmatory sampling was performed on August 28, 2008, and September 24, 2008. A focused sampling design was selected for confirmatory sampling based on historical drawings, process knowledge, and other available information.

Due to the expected uniform distribution of residual material, no sampling location was preferred for collecting a focused sample within the pipeline. Therefore, a sample representative of pipeline contents was collected from a location selected based on access considerations at the outfall of the pipeline. The most appropriate focus location for characterization of potential impact to underlying soils was also selected at the outfall of the pipeline, as the pipeline terminus was a free discharge to soil.

The SubSite is Part Of:

Code: 100-H-28

Names: 100-H-28; 100-H Water Treatment Facilities Underground Pipelines

Code: 100-H-28:2

Classification: Accepted

Names: 100-H-28:2; South Process Sewers

Reclassification: Interim Closed Out (9/25/2015)

Type: Process Sewer

Start Date: 1/1/1949

Status: Inactive

End Date: 1/1/1965

Description: This subsite has been remediated and Interim Closed Out. It consisted of the vitrified clay, reinforced concrete, and cast iron process sewer lines formerly servicing the 105-H Reactor Building, 190-H Pumphouse, 183-H clearwells and pumphouse (126-B-2), and miscellaneous 1700-series buildings east of the 190-H Pumphouse. These process sewers formerly drained to the 1906-H lift station, which pumped wastes to the 1904-H Outfall.

Location: The 100-H-28:2 process sewers are part of the 100-HR-1 Operable Unit. They were located around the demolished buildings in the southern portion of the 100-H area. These pipelines are generally in excess of 7.6 meters (25 ft) below existing grade.

Waste Type: Not Specified

Waste Description: The waste is contaminated soil if these lines leaked and any pipelines that may be contaminated from past operations.

Closure Info: Interim (9/25/2015): 100-H-42 and 100-H-28:2 were reclassified in the same Remaining Sites Verification Package. Confirmatory sampling at the 100-H-28:2 subsite was conducted between May 2008 and December 2008. The contents of two french drains that were discovered during the confirmatory sampling activities were sampled and the results for each exceeded groundwater and river protection RAGs for lead. The french drains were located within the planned excavation layback. 100-H-42 waste site was recommended for remediation without confirmatory sampling.

Remedial action at the 100-H-28:2 subsite was performed from September 2011 through March 2012; September 2013 through March 20, 2014 and September 2 through September 23, 2014. The 100-H-28:2 excavation extended to an approximate maximum depth of 9 meters (29.5 ft) bgs. The waste material included 11 to 22 meters (36 to 72 in.) diameter concrete pipe, 1.8 to

2.4 meter (6 to 8 in.) diameter concrete-encased vitrified clay pipe, manhole debris, interfering structural debris, and former building demolition debris. The structural and demolition debris included reinforced concrete, coal ash, steel pipe, asbestos transite, and other general building demolition debris. The asbestos transite debris was encountered at the ground surface prior to excavation of the 100-H-28:2 pipeline. The asbestos transite debris was removed and direct loaded for disposal at the Environmental Restoration Disposal Facility (ERDF). All removal and handling of asbestos transite debris was conducted and directed by asbestos competent individuals. Approximately 21,650 bank cubic meters (BCM) (28,317 bank cubic yards [BCY]) of contaminated soil and debris were removed from the 100-H-28:2 subsite and staged at the staging pile areas (SPAs) pending loadout and disposal.

Remediation at the 100-H-42 waste site began in October 2013 and was completed on March 3, 2014. The waste from this site included reinforced concrete, steel pipe, asphalt, soil, and miscellaneous demolition debris from the large subsurface structure associated with the 1906-H Drainage Lift Station. Approximately 5,200 BCM (6,801 BCY) of contaminated material was removed from the 100-H-42 excavation and staged at the SPA locations for disposal at ERDF. The 100-H-42 waste site was excavated to an approximate depth of 9 meters (29.5 ft) bgs. A large concrete monolith remains at the bottom of the 100-H-42 excavation that protrudes to groundwater.

The SubSite is Part Of:

Code: 100-H-28

Names: 100-H-28; 100-H Water Treatment Facilities Underground Pipelines

Code: 100-H-28:3

Classification: Accepted

Names: 100-H-28:3; North Process Sewers

Reclassification: Interim Closed Out (7/9/2015)

Type: Process Sewer

Start Date: 1/1/1949

Status: Inactive

End Date: 1/1/1965

Description: The 100-H-28:3 subsite was remediated and Interim Closed Out in conjunction with 100-H-28:5 and 100-F-44. It consisted of process sewers formerly servicing the 183-H Filter Plant, 182-H Reservoir, and 184-H Boiler House/Alternative Power House.

Location: The 100-H-28:3 process sewers are part of the 100-HR-1 Operable Unit. These pipelines are located around the former facilities in the northern portion of the 100-H Area. In the vicinity of the 184-H Building, the pipelines are approximately 2.4 meters (8 ft) below grade, sloping down to in excess of 7.6 meters (25 ft) below existing grade in the vicinity of water treatment facilities.

**Related Sites/
Structures:** 100-H-28:5 and 100-F-44

**Process
Description:** The mainline for this sewer consists of 0.38 meter (15 in.), 0.76-m (30-in.), and 1.22-m (48-in.)-diameter reinforced concrete pipe (RCP) up to the confluence with the 100-H-28:2 south process sewers, from which a 1.83-m (72-in.) RCP line carried the combined flow to the 1906-H lift station. Effluent from the process sewers was ultimately discharged to the Columbia River at the 1904-H outfall, but past remediation of radioactive liquid waste effluent pipelines (BHI 2000) and demolition of the 1906-H lift station (WHC 1991) included removal of the most downstream portion of the process sewers to a point slightly west of the 1906-H facility. The feeder lines formerly discharging to the 100-H-28:3 mainline consist of 0.38-m (15-in.) and 0.46 (18-in.) cast iron pipe and larger diameter (up to 1.07-m [42 in.]) RCP. In addition, 100-H-28:3 includes a 10.16 cm (4 in) vitrified clay pipe that received effluent from a sump in the pipe trench near the 183-H car spot.

Waste Type: Not Specified

Waste Description: The waste will include the pipelines and any potential contaminated soil.

Closure Info: Interim (7/9/2015): The 100-H-28:5 and 100-H-44 waste sites were co-located with the 100-H-28:3 waste site, so remedial actions were conducted concurrently. Confirmatory sampling was conducted at the 100-H-28:3 pipeline subsite on June 2, 2008. Confirmatory sampling was conducted at the 100-H-28:5 subsite on June 2 and 3, 2008. Confirmatory sampling was conducted at the 100-H-44 waste site from test pits on November 4 and 5, 2009.

Remedial actions at the 100-H-28:3 and 100-H-28:5 subsites and the 100-H-44 waste site were conducted concurrently and began on July 17, 2013, with removal of overburden material. The overburden was combined with material from the 100-H-28:2 and 100-H-28:4 pipeline subsites. In total, the combined overburden removed from was approximately 117,000 bank cubic meters (BCM) (153,030 bank cubic yards [BCY]). No overburden material was retained from the 100-H-44 waste site remediation. A combined 29,438 BCM of material was removed during the remediation of the three pipeline sites. The waste removed from the 100-H-28:3 and 100-H-28:5 subsites included soil, concrete, steel, vitrified clay pipe debris and a brick manhole debris. Waste materials associated with the 100-H-44 waste site included acid-stained soils, concrete sump debris, and small diameter steel pipe debris. Additional wastes included interfering concrete building foundations, surface asphalt, interfering clean water pipelines, interfering steam lines, coal ash, railroad ties, and miscellaneous building demolition debris (e.g., concrete and steel rebar adjacent to previously demolished buildings).

The 100 Area export water line crossed portions of the northwest sections of the 100-H-28:3 and 100-H-28:5 pipelines. Due to the necessity of not disturbing the export water line, approximately 18 meters (60 ft) of the 100-H-28:3 and 12 meters (40 ft) of the 100-H-28:5 pipelines were left in place.

The SubSite is Part Of:

Code: 100-H-28

Names: 100-H-28; 100-H Water Treatment Facilities Underground Pipelines

Code: 100-H-28:4

Classification: Accepted

Names: 100-H-28:4; 1607-H1 Sanitary Sewer Pipeline

Reclassification: Interim Closed Out (3/5/2015)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. It was the vitrified clay pipelines that carried sanitary wastes to the 1607-H1 septic system. These sewer lines serviced the 105-H Reactor Building, 190-H Pumphouse, and 151-H Electrical Substation.

Location: The 100-H-28:4 sanitary sewers pipelines are located around the former buildings in the southern portion of the 100-H area, terminating at the 1607-H1 septic tank. The septic tank was south of the 151-H substation. These sewers exist deeper than 1.5 meters (5 ft) below existing grade.

Process Description: The sewer was designed to receive waste from the 105-H Reactor Building, the 151-H Electrical Substation and the 190-H Pumphouse.

Waste Type: Not Specified

Waste Description: The waste is the remaining pipelines and contaminated soil (if any) associated with leaks of these pipelines.

Closure Info: Interim (3/5/2015): The results of the confirmatory samples indicated several contaminants exceeded the regulatory goals. Remedial action at the 100-H-28:4 pipeline subsite was performed between November 14, 2013, and March 25, 2014. The depth of the remediation ranged from approximately 0.9 to 3.7 meters (3 to 12 ft) below ground surface, resulting in approximately 1,630 bank cubic meters (2,132 bank cubic yards) of soil and debris being removed for disposal at the Environmental Restoration Disposal Facility (ERDF). The debris consisted primarily of 15 centimeter (6 in.) and 20 centimeter (8 in.) diameter vitrified clay pipe encased in concrete. The waste material was staged in a combined staging pile area (SPA). The waste SPA footprint was included in the 100-H-28:2/100-H-42 verification work instruction and will be addressed in the 100-H-28:2/100-H-42 closure document. Overburden material was removed from above the pipeline and stockpiled along with overburden material from the 100-H-28:2, 100-H-28:3, and 100-H-28:5 subsites for use as clean backfill. The overburden material was included in the 100-H-28:3/100-H-28:5/100-H-44 verification work instruction and will be addressed in the 100-H-28:3/100-H-28:5/100-H-44 closure document. No stained soil or anomalous materials were encountered during the remediation.

The SubSite is Part Of:

Code: 100-H-28

Names: 100-H-28; 100-H Water Treatment Facilities Underground Pipelines

Code: 100-H-28:5

Classification: Accepted

Names: 100-H-28:5; 1607-H2 Sanitary Sewer Pipelines

Reclassification: Interim Closed Out (7/9/2015)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The subsite was remediated and Interim Closed Out in conjunction with 100-H-28:3 and 100-H-44. It included 6 inch and 8 inch diameter vitrified clay pipelines that carried sanitary wastes to the 1607-H2 septic system. The 1607-H2 sewers serviced the 182-H Reservoir pumphouse, 183-H Filter Plant, 184-H Power House, 190-H Pumphouse, and 1700-series buildings east of the 190-H Pumphouse. The administrative boundary of this subsite extended to the boundary of previous remedial activities at the 1607-H2 septic system. The 1607-H2 system was remediated in 1999.

Location: The 100-H-28:5 sanitary sewers are part of the 100-HR-1 Operable Unit. These pipelines were located around the former buildings in the 100-H area, terminating at the remediation boundaries of the 1607-H2 Septic System. The sewers are approximately 1.2 to 1.8 meters (4 to 6 ft) below existing grade.

Related Sites/ Structures: 100-H-28:3 and 100-H-44

Process Description: The sanitary sewer feeder line formerly servicing the 190-H Building is related to sanitary facilities. The former 1700-series buildings serviced by the 100-H-28:5 sanitary sewers included a fueling station (1716-H), paint shop (1722-H), machine shop (1717-H, 100-H-4 waste site), first aid station (1719-H), and administrative building (1704-H).

Waste Type: Not Specified

Waste Description: The waste is the remaining pipelines and contaminated soil (if any) associated with leaks of these pipelines.

Closure Info: Interim (7/9/2015): The 100-H-28:5 and 100-H-44 waste sites were co-located with the 100-H-

28:3 waste site, so remedial actions were conducted concurrently. Confirmatory sampling was conducted at the 100-H-28:3 pipeline subsite on June 2, 2008. Confirmatory sampling was conducted at the 100-H-28:5 subsite on June 2 and 3, 2008. Confirmatory sampling was conducted at the 100-H-44 waste site from test pits on November 4 and 5, 2009.

Remedial actions at the 100-H-28:3 and 100-H-28:5 subsites and the 100-H-44 waste site were conducted concurrently and began on July 17, 2013, with removal of overburden material. The overburden was combined with material from the 100-H-28:2 and 100-H-28:4 pipeline subsites. In total, the combined overburden removed from was approximately 117,000 bank cubic meters (BCM) (153,030 bank cubic yards [BCY]). No overburden material was retained from the 100-H-44 waste site remediation. A combined 29,438 BCM of material was removed during the remediation of the three pipeline sites. The waste removed from the 100-H-28:3 and 100-H-28:5 subsites included soil, concrete, steel, vitrified clay pipe debris and a brick manhole debris. Waste materials associated with the 100-H-44 waste site included acid-stained soils, concrete sump debris, and small diameter steel pipe debris. Additional wastes included interfering concrete building foundations, surface asphalt, interfering clean water pipelines, interfering steam lines, coal ash, railroad ties, and miscellaneous building demolition debris (e.g., concrete and steel rebar adjacent to previously demolished buildings).

The 100 Area export water line crossed portions of the northwest sections of the 100-H-28:3 and 100-H-28:5 pipelines. Due to the necessity of not disturbing the export water line, approximately 18 meters (60 ft) of the 100-H-28:3 and 12 meters (40 ft) of the 100-H-28:5 pipelines were left in place.

The SubSite is Part Of:

Code: 100-H-28

Names: 100-H-28; 100-H Water Treatment Facilities Underground Pipelines

Code: 100-H-28:6

Classification: Accepted

Names: 100-H-28:6; 182-H Reservoir Sump Drains

Reclassification: Interim No Action (10/29/2009)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The subsite has been evaluated and determined to require No Action. The 100-H-28:6 subsite consists of approximately 190 meters (620 ft) of 20 cm (8-in.) vitrified clay pipeline north of the 182-H Reservoir. The pipeline was approximately 4.6 meters (15 ft) below ground surface.

Location: The 100-H-28:6 subsite runs from the north side of the 182 H Reservoir northeast to the upper river bank, approximately 1.8 meters (6 feet) down slope of the present embankment crest. The exact location of the pipeline was documented in drawings P-1215 and P-1216 (GE 1949a, 1953).

Process Description: The pipeline was installed during construction of the 182-H Reservoir. The water that traveled through the pipeline originated directly from the Columbia River via the 181-H Pumphouse, with the exception of steam condensate.

Waste Type: Soil

Waste Description: The waste was pipeline sediment/scale and underlying soil.

Closure Info: Interim: Confirmatory sampling was performed on September 2, 3, and 24, 2008. During test pit excavation and sampling, radiological field screening was performed as specified in the confirmatory sampling work instruction. No radiological contamination was detected above

background levels. Field screening for the presence of volatile organic compounds (VOCs) was also negative. No anomalous media indicated by staining, evidence of burning, and/or debris were observed during test pit excavations. Samples were collected from the outfall in test pit 1 and a manhole structure and outlet pipe in test pit 2.

The SubSite is Part Of:

Code: 100-H-28

Names: 100-H-28; 100-H Water Treatment Facilities Underground Pipelines

Code: 100-H-28:7

Classification: Accepted

Names: 100-H-28:7; 183-H Process Water Lines

Reclassification: Interim No Action (2/20/2013)

Type: Process Sewer

Start Date: 1/1/1949

Status: Inactive

End Date: 1/1/1965

Description: This subsite has been evaluated and determined to require No Action. It included the filtered/treated water supply lines originating at the 183-H Filter Plant, two 0.91-meters (36-inches) steel lines terminating at the 190-H building, a 0.76-meters (30-inches) line terminating at the 182-H Reservoir pumphouse, two 0.25-meters (10-inches) steel lines terminating at the 184-H Power House, and the former supply lines to the emergency cooling water high tanks at the 105-H Reactor Building.

Location: The 100-H-28:7 process water lines are part of the 100-HR-1 Operable Unit. These pipelines are located between the former 183-H Filter Plant Pump House, 184-H Boiler House, 190-H Pump House, the 187 Elevated Water Towers, and the 105-H Reactor. These pipelines are approximately 1.8 to 3 meters (6 to 10 ft) below existing grade.

Process Description: These pipelines were used to transfer treated water from the 183-H Filter Plant Pumphouse to the 182-H Reservoir Pumphouse, 184-H Boiler House, 190-H Pumphouse, and 105-H Reactor facilities (including the 187-H Emergency Cooling Water Tanks).

Waste Type: Not Specified

Waste Description: The waste would be any potentially contaminated soil and remaining pipeline components.

Closure Info: Interim (2/20/2013): Confirmatory sampling of the 100-H-28:7 pipelines occurred over the period beginning September 3, 2008 and concluding on March 3, 2009. The pipelines were accessed and sampled via three test pits. Based on evaluation of the analytical results, it was determined that the 100-H-28:7 subsite does not require remedial action.

At Test Pit 1, two 25 centimeter (10 inch) diameter pipelines were excavated. Both of the 100-H-28:7 pipelines at test pit 1 contained a significant volume of water. Water within each pipe, as well as the soil underlying each pipe, were sampled on September 30 and October 1, 2008. The water contained slightly elevated concentrations of lead and manganese, but at levels which would allow this water to be used for dust suppression. With concurrence from the Washington State Department of Ecology, the water was removed from the pipeline and used for dust suppression. After the water was removed from the pipes, a second sampling of the pipe material at Test Pit 1 occurred on March 19, 2009. Limited scale material was available for collection. Therefore, scale from the north and south pipe sections was collected and combined into a single sample.

Test pit 2 excavation began September 3, 2008 and two pipes were located at approximately 2.1 to 2.4 meters (7 to 8 ft) below ground surface (bgs). The west pipe was 61 centimeters (24 in.) in diameter and the east pipe was 76 cm (30 in.) in diameter. The 61 centimeters (24 in.)

diameter pipe was an unknown pipeline not related to the 100-H-28:7 pipelines and has since been included as part of 100-H-35, 100-H Service Water Pipelines. Scale inside the 100-H-28:7 pipe at test pit 2 and the underlying soil were sampled on October 13 and 15, 2008. Additionally, a sample of suspect Asbestos Containing Material from each pipe was sampled on October 1, 2008.

During excavation at Test Pit 3, on March 23, 2009, a french drain was discovered. Samples were taken both within and below the drain structure. The french drain was not related to the 100-H-28:7 pipelines and has since been included as part of the 100-H-49:1, 184-H Boiler House and 1717-H Hot Shop French Drains subsite. The 100-H-28:7 Test Pit 3 pipeline was also excavated and scale from inside the pipe and the soil underlying the pipe was sampled on March 23, 2009. The pipe contained no water and the scale inside had a similar appearance to that seen in the Test Pit 2 pipe.

The SubSite is Part Of:

Code: 100-H-28

Names: 100-H-28; 100-H Water Treatment Facilities Underground Pipelines

Code: 100-H-28:8

Classification: Accepted

Names: 100-H-28:8; 190-H Process Water Lines

Reclassification Interim No Action (4/19/2007)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The subsite has been evaluated and determined to require No Action. The subsite consisted of four 0.61 meter (24-inch) diameter seamless welded steel pipelines located in two subsurface, reinforced concrete tunnels between the 190-H and 105-H facilities, as well as possible ancillary piping within the tunnels. The 100-H-28:8 pipelines were pressurized lines housed in subsurface tunnels, and have been completely removed by previous decommissioning and demolition activities.

Location: These pipelines ran from the 190-H Pumphouse to the 105-H Reactor Building.

Process Description: These pipelines were used during operations from 1949 to 1965 to provide final treated cooling water originating from the 190-H Pumphouse, limited to the residual portions of the 105-H Reactor Building supply lines within the reactor cooling water tunnels.

Closure Info: Interim: The 190-H Pumphouse was demolished in 1977. The tunnels between the 190-H footprint and the 105-H exclusion fence were excavated and collapsed in 1985. Piping in the tunnels north of the reactor exclusion fence was removed prior to demolition. No piping was observed south of the exclusion fence at the time of demolition activities. The remaining portions of the tunnels between the reactor block and the exclusion fence were excavated and removed during Interim Safe Storage (ISS) activities for the 105-H Reactor Building. Remaining portions of the tunnels and piping at the reactor block were sealed as part of ISS activities and will be addressed as part of closure of the reactor facilities (118-H-6 waste site).

The cooling water tunnels were sloped downwards toward the 190-H Pumphouse; accordingly, any water entering the tunnel would accumulate at the pumphouse facility. There was no known record of any leaks occurring within the cooling water tunnels. Sampling of soils underlying the cooling water tunnels at the 105-C Reactor-where radioactive process water from the reactor back flowed into the tunnels-did not reveal any residual hexavalent chromium or uranium (the sole contaminants of potential concern) above remedial action goals.

The SubSite is Part Of:

Code: 100-H-28
Names: 100-H-28; 100-H Water Treatment Facilities Underground Pipelines

Code: 100-H-30 **Classification:** Accepted
Names: 100-H-30; 110-H Sanitary Sewer Trench **Reclassification:** Interim Closed Out (3/1/2001)
Type: Trench **Start Date:**
Status: Inactive **End Date:**

Description: The site has been remediated and Interim Closed Out. It was a sanitary sewer trench and feed pipeline.

Location: The site was located south of the demolished 110-H Building and east of the 116-H-2 (1608-H) Crib.

Related Sites/ Structures: The site was associated with the demolished 110-H Building.

Process Description: No additional information could be found concerning the site. However, the nearby 116-H-2 (1608-H) Crib is known to have overflowed. It is likely the overflow contaminated this septic trench with the same radionuclide and chemical contamination as the crib. This contributed to the confusion surrounding the 116-H-2 Crib's description and location in various documents.

Waste Type: Process Effluent

Waste Description: The trench is likely to have received radionuclide and chemical contamination from the overflows of the 116-H-2 (1608-H) Crib. The crib received cooling water from the 105-H Reactor Building during the Ball 3X system upgrade program. The site was used during other upgrade programs and on the effluent system when maintenance was necessary.

Waste Type: Sanitary Sewage

Waste Description: The unit received unknown amounts of sanitary sewage from the 110-H Building.

Closure Info: Interim: This area is located in an area that, prior to World War II and formation of the Hanford Site, was occupied by fruit tree orchards.

Remedial action at the 100-H-17 sites group (100-H-17, 100-H-30, 100-H-2 and 116-H-2) began on February 2, 2000. The sites were grouped together for remediation because of location and similar contaminants. Excavation of the area involved removing the overburden materials, miscellaneous debris, the contaminated structure, and underlying contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Contaminated materials were disposed of at ERDF. On February 10, 2000, the excavation was completed.

No evidence of buried waste was found during the excavation of the 100-H-2 site.

At the completion of the remedial action, the total excavation was approximately 6,240 square meters (67,170 square feet) in area with a maximum depth of approximately 2.6 meters (8.5 feet). Approximately 19,920 metric tons (21,960 tons) of material from the site were disposed of at the ERDF.

Code: 100-H-31 **Classification:** Accepted
Names: 100-H-31; Polychlorinated Biphenyl in Soil on North Side of 105-H Reactor Building **Reclassification:** Interim Closed Out (6/22/2006)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The site has been remediated and Interim Closed Out, along with 118-H-6:2 and 118-H-6:3. The site consisted of a surface gravel area near a former electrical substation. There were no visible oil stains or vegetation. The adjacent concrete pad had electrical conduit and wiring extending up to the surface where the electrical equipment was removed. The site was not marked or posted. The reactor exclusion fence was posted as Underground Radioactive Material, Danger, Restricted Area, Multiple Hazards, and No Entry Without Written Authorization.

Location: The site was located on the north side of the 105-H Reactor Building (inside the exclusion area fence) and off the southeast corner of a former electrical transformer pad. The site is 4 meters (11.2 feet) south of 100-H-10 French Drain site.

Release Description: Polychlorinated Biphenyls were detected in the soil.

Related Sites/Structures: The site is related to electrical transformers that were formerly located on the concrete pad near the site and the 105-H Reactor Building (sitecode 118-H-6).

Waste Type: Soil

Waste Description: The waste is polychlorinated biphenyl (PCB) contaminated soil.

Closure Info: Interim: Removal and disposal activities at the 105-H site (118-H-6:2, 118-H-6:3, 118-H-6:6 subsites) were completed in 2004. D&D activities, in preparation for the construction of the 105-H Reactor SSE, also resulted in the removal of 100-H-9, 100-H-10, 100-H-11, 100-H-12, 100-H-13, 100-H-14 french drains and the 100-H-31 electrical transformer soil. All materials from the 105-H Reactor ISS Project were demolished and disposed at ERDF. The overburden piles produced during excavation were found to be contaminated. The overburden was deemed unsuitable for use as backfill of the site and was removed to ERDF.

The site was backfilled with clean soil aggregate from the 100-D Area Borrow Pit 21 and graded to match the surrounding terrain. This 105-H D&D activity generated approximately 4,863 bulk containers of low-level contaminated material that were shipped to ERDF, accounting for approximately 73,966 metric tons (81,365 tons).

Per the Sampling and Analysis Plan, the 105 H Reactor ancillary support areas and below-grade structures (118-H-6:2) did not require sampling and analysis because the structures were removed in their entirety and then disposed at the Environmental Restoration Disposal Facility (ERDF). During the D&D activities, an additional evaluation was required to determine if the soils under the Fuel Storage Basin (FSB) floor (118-H-6:3) had achieved the RAGs. The evaluation of the FSB soils and deep zone side-slope soils (118-H-6:6) also evaluated the soils under the 100-H-11, 100-H-12, and 100-H-14 waste sites. Radiological surveys and verification sampling analysis were performed on the FSB underlying soils and deep zone side-slope soils. The data was used with the RESRAD computer model to verify that cleanup criteria were satisfied. Localized contamination was removed in preparation for clean demolition, and a fixative was applied as required. With one exception, no below-grade structures remaining. The exception is a portion of the FSB floor, at its northern end between the two access labyrinths to the D elevator. It was not removed with this activity.

Verification soil samples were collected from soils under the FSB floor. All demolition debris from excavations associated with the activity was sent to ERDF. Final cleanup verification samples for the FSB underlying soils and deep zone side-slope soils were collected following

evaluation of field screening for radiological contaminants using global positioning environmental radiological surveyor (GPERS) and laser-assisted ranging and data system (LARADS) surveys. This field screening was performed in order to obtain an initial assessment of attainment of radiological cleanup levels

The remaining soils at the 105-H Reactor site were either been deferred to the Field Remediation Closure Project or have been shown to meet the applicable RAGs through verification sampling, analysis, and RESRAD modeling. All excavated materials generated during the D activities were disposed at ERDF, and the area was backfilled to grade with clean backfill. These results also indicate that residual concentrations in the shallow zone will support future land uses that can be represented (or bounded) by a rural-residential scenario and that residual concentrations throughout the site pose no threat to groundwater or the Columbia River.

The three decontamination pads (118-H-6:5) and the Fuel Storage Basin shallow side-slope soils (118-H-6:4) were deferred to the Field Remediation Closure Project and remediated at a later date.

Code:	100-H-33	Classification:	Accepted
Names:	100-H-33; 183-H Solar Evaporation Basins Radionuclide Components	Reclassification	Interim No Action (4/12/2012)
Type:	Retention Basin	Start Date:	1/1/1949
Status:	Inactive	End Date:	1/1/1985

Description: The 100-H-33 waste site has been evaluated and determined to require No Action. 100-H-33 was created to address the radionuclides associated with the former 183-H Solar Evaporation Basins (see sitecode 116-H-6 TSD). The basin had been used for solar evaporation of liquid wastes from the 300 area. The solar basins were remediated in 1985 and 1995. After remediation, the basins were completely demolished in the fall of 1996. The waste site was backfilled and re-vegetated in the spring of 1997. No radiological posting were associated with the backfilled basin.

The non-radiological, RCRA TSD component of the Solar Evaporation Basins (sitecode 116-H-6) was closed out on May 13, 1997, under a Modified Closure signed by Washington State Department of Ecology. The RCRA TSD closure did not address any radionuclide contaminants associated with the solar evaporation basins (gross alpha, gross beta, uranium-234, uranium-235, technetium-99, total uranium, and gamma energy analysis). Consequently, site 100-H-33 waste site was created to address the radionuclide component of the solar evaporation basins. Borehole C7860 (199-H4-84) was drilled in the waste site footprint in February 2011 as part of the Remedial Investigation. Strontium-90, Tc-99 and tritium were detected above background levels.

Location: The solar evaporation basins were located north of the 105-H Reactor and just north of the east 183-H Clearwell (WIDS Site 126-H-2).

Related Sites/ Structures: Sitecode 116-H-6, the 183-H Solar Evaporation Basins, is the associated TSD component for this site.

Process Description: The basins were constructed in 1949 and used for 100-H Area water treatment until the mid-1960's. Beginning in July 1973, radioactive and dangerous (mixed) waste from the 300 Area fuel fabrication facilities was shipped to the basins for storage and treatment. Approximately 1.6E+06 kilograms (3.6E+06 pounds) of waste per year were treated by solar evaporation. The basins had an earthen berm around three sides and an asphalt-covered ramp on the north side to allow tanker truck unloading.

Waste Type: Process Effluent

Waste Description: The facility received routine and nonroutine wastes. The routine wastes consisted of spent acid etch solutions (primarily nitric, sulfuric, hydrofluoric, and chromic acids) generated by the Nuclear Fuel Fabrication process. These acidic solutions were reacted with excess sodium hydroxide before being transported to the 183-H Basins. Metal constituents include copper, silicon, zirconium, nickel, aluminum, chromium, manganese, and uranium, which were in the form of precipitates. Nonroutine wastes consisted of unused chemicals and spent solutions from miscellaneous processes. Beginning in July 1973, radioactive and dangerous (mixed) waste from the 300 Area fuel fabrication facilities was shipped to the basins for storage and treatment. The waste has been designated an Extremely Hazardous Waste (EHW) because of toxicity, waste code (WT01). The basins also received various nonradioactive waste (listed discarded chemical products), resulting in designation for cyanide (P030), vanadium pentoxide (P120), and formic acid (U123). Additionally, Basin #2 was designated EP Toxic because of the presence of chromium (D007). More detailed descriptions of these wastes and quantities are contained in DOE/RL 88-04, Interim Status Closure/Post-Closure Plan 183-H Solar Evaporation Basins. Additional radionuclide contaminants of concern were identified in the Closure/Post Closure Plan.

Closure Info: Interim (4/12/2012): This waste site was determined to be a No Action site on Waste Site Reclassification Form 2011-099.

The shallow zone samples from below the former (116-H-6) concrete basin floor and borehole samples from beneath each of the four basins indicate that the source of radiological contamination has been removed and only low concentrations of residual radionuclides are present in the deep vadose zone beneath the easternmost basin (Basin 1) at the 100-H-33 waste site.

As a part of the modified RCRA closure of the 116-H-6 waste site, four groundwater monitoring wells were drilled. Three wells were placed downgradient of the 183-H Basins in 1991 (199-H4-12C, 199-H4-12A, and 199-H4-3), and one was placed upgradient (199-H4-8). The 2010 results of the groundwater monitoring report show that technetium-99 and total uranium are present but are below the maximum contaminant level for each constituent. Borehole C7860 (199-H4-84) was drilled in the waste site footprint in February 2011 as part of the Remedial Investigation. Strontium-90, Tc-99 and tritium were detected above background levels.

The combination of borehole results and groundwater sampling indicate that source removal has occurred, and that residual radionuclide contamination warranting cleanup is not present in the deep vadose zone. Results of groundwater monitoring for technetium-99 and uranium show continued decline since monitoring was begun, indicating that residual contamination only remains in the groundwater and is slowly dissipating. Groundwater will continue to be monitored for uranium and technetium-99 in coordination with nonradionuclide monitoring performed by the U.S. Department of Energy as a part of the 183-H RCRA Postclosure Plan.

Ecology evaluated the data for this waste site against the WAC 173-340 (2007) cleanup levels for direct contact, groundwater protection and river protection. This evaluation is documented in the letter transmitting Ecology's approval of the waste site's interim reclassification to No Action on the WIDS Waste Site Reclassification form (2011-099).

Code: 100-H-34

Classification: Accepted

Names: 100-H-34; 100H River Effluent Pipelines; 100H River Lines

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This site includes the river effluent pipelines (river lines) that extend from the outfall (116-H-5) into the main channel of the Columbia River. This site includes two 152 centimeter (60 inch) diameter (1.3 centimeter [0.5 inch] thick walls), steel river effluent pipelines that extend 229.5 meters (753 linear feet) from the face of 116-H-5 (the 1904 H outfall structure) into the main channel of the Columbia River.

Location: The river lines are located in the Columbia River, adjacent to the 100H area. The lines extend east into the main channel of the river from the 1904-H outfall. The river effluent pipelines extend perpendicular from the discharge (river side) face of the 1904-H outfall structure for 20.3 meters (66.5 feet), then take a 19-degree downstream bend and continue on for another 209.2 meters (686.5 feet).

Related Sites/ Structures: The site is associated with the 116-H-5 Outfall Structure, 100-H-36 Spillway (Flume), 116-H-7 Retention Basin and 184-H Power House. The site is associated with the 116-H-5 outfall structure, 116-H-7 (the 107-H Retention Basin), the lines (116-H-21) from the retention basin to the outfall structure, and 100-H-36 (the 1904 H spillway).

Process Description: The River Effluent pipelines discharged reactor coolant water to the river. Effluent was received from the 107-H Retention Basin and the area process sewer system to the outfall structure. In the event that the outfall line plugged, effluent would back up into the outfall structure and overflow into an underground concrete sluiceway (flume) that led to the river. Reactor (105-H) effluent cooling water was collected and temporarily stored in the 107 H Retention Basin. This cooling water, as well as process sewer wastes, were discharged to the river via the river effluent pipelines after passing through the 1904-H outfall structure. In the event the pipelines became plugged or were out of service for any reason, the discharge streams would overflow to an underground, emergency spillway (100-H-36), which was also routed to the river. The total drop from the face of the outfall structure to the discharge end of the pipeline is 8.5 meters (28 feet). The pipelines are separated by approximately 90 centimeters (35 inches) and are covered by a minimum of 1 meter (3 feet) of soil over their entire length, as well as large pieces of basalt riprap extending from the face of the outfall to the shoreline. The top portion of the outfall structure has been partially demolished, and backfilled with clean soil. It is not known what condition the outfall ends of the river effluent pipelines were left in following outfall demolition. During February and March 2005 visits to the site, it was noted that the bottom portion of the underground spillway (flume) (100-H-36) associated with the outfall structure is partially intact and visible. The total drop from the face of the outfall structure to the discharge end of the pipeline is 8.5 meters (28 feet). The pipelines are separated by approximately 90 centimeters (35 inches) and are covered by a minimum of 1 meter (3 feet) of soil over their entire length, as well as large pieces of basalt riprap extending from the face of the outfall to the shoreline. The top portion of the outfall structure has been partially demolished, and backfilled with clean soil. It is not known what condition the outfall ends of the river effluent pipelines were left in following outfall demolition. During February and March 2005 visits to the site, it was noted that the bottom portion of the underground spillway (flume) (100-H-36) associated with the outfall structure is partially intact and visible.

Waste Type: Process Effluent

Waste Description: The waste includes the pipelines and the contaminated scale contained within them.

Contaminants of concern/potential concern are based on those for the outfall itself. Contaminants of potential concern include Co-60, Cs-137, Eu-152, -154, -155, Ni-63, Pu-238, -239/240, Am-241, C-14, H-3, Tc-99, Sr-90, U-234, -235, -238, Cr+6, Cr (total), Pb, and Hg.

Code: 100-H-35 **Classification:** Accepted
Names: 100-H-35; 100-H Clean Water Pipelines; 100-H Service Water Pipelines **Reclassification:** Interim No Action (2/28/2012)
Type: Product Piping **Start Date:**
Status: Unknown **End Date:**

Description: Confirmatory sampling of the pipelines supported a No Action Reclassification. The 100-H-35 waste site consists of the underground service water pipelines upstream of the 105-H Reactor that carried water not treated with sodium dichromate. The service water pipelines are those that were used to transport raw water (RW), sanitary water (SW), and steam condensate (CW). The pipes generally ranged in size from 1.9 centimeters (0.75 in.) to 106.7 centimeters (42 in.) and were typically constructed of concrete, cast iron, or steel.

Pipelines excluded from this site include those within buildings, process and sewer pipes, pipes that carried water treated with sodium dichromate, and all lines that were downstream from the reactor building, i.e., those lines that carried cooling water from the reactor to the retention basin, trench, and/or the river.

Location: The clean water (non-contaminated) underground pipelines were located across the 100-H Area, from the 181-H intake structure to the water treatment facilities, reactor (fire and potable water, not reactor cooling water), south to the fire and patrol headquarters near the 1607-H-3 Patrol Headquarters area, west to miscellaneous shops and warehouses, and the 184-H Coal Fired Powerhouse. The export water line entered the H Area from the 100 D/DR Area north of the coal storage area, it turned south along the road then east to the 182-H Reservoir. This line also continued further south and turned east where it entered the 105 H reactor on the north side.

Related Sites/Structures: The clean water and fire protection water pipelines ran to or near virtually all the facilities at the 100-H Area. The other pipeline sites at the 100-H Area are 100-H-21 (Reactor Cooling Water Effluent Underground Pipelines); 100-H-28 (Water Treatment Facilities Underground Pipelines); and 100-H-34, (River Effluent Pipeline).

Process Description: The site encompasses the clean water pipelines for the 100-H Area, including underground pipelines used to transport raw water from the river pumphouse to the water treatment facilities and to 100-H Area facilities and fire hydrants.

Waste Type: Equipment

Waste Description: The waste is the old buried pipes from the clean water pipeline system.

Closure Info: Interim (2/28/2012): Confirmatory sampling of the 100-H-35 waste site occurred primarily in September and October 2010 from test pits. A total of 11 test pits were excavated. Seven samples of underlying soil and four samples of pipeline contents (scale) were collected. Two locations that were sampled during a 2008 and 2010 were resampled in 2010. The confirmatory sampling results supported a reclassification of this site to No Action.

Code: 100-H-36 **Classification:** Accepted
Names: 100-H-36; 116-H-5 Spillway; 1904-H Spillway; 100-H-34:1 Flume (Spillway) for the 116-H-5 Outfall Structure **Reclassification:** None
Type: Outfall **Start Date:**
Status: Inactive **End Date:**

Description: The 100-H-36 Spillway (also referred to as a flume) is an underground concrete sluiceway that led from the 116-H-5 Outfall Structure to the river shoreline.

Location: The site is located on the Columbia River shoreline north of the 116-H-7 Retention Basin. Assuming midline Washington State Plane coordinates, the underground spillway exits the south face of the 116-H-5 outfall, takes an immediate 45 degree turn in the upstream direction, and terminates.

Related Sites/ Structures: The site is associated with the 100-H-34 River Effluent Pipelines and the 116-H-5 Outfall Structure.

Process Description: The spillway carried effluent overflow from the outfall (116-H-5) structure to the shoreline of the river for release. It was planned to be used only if the river effluent pipelines (100-H-34) were blocked, damaged, or undergoing maintenance. There is no corroborated physical or historical evidence that the spillway was ever used. The slope between the outfall and the river is covered with large basalt riprap boulders that have been mortared in place, extending about 73 meters (80 yards) north and south of 116-H-5. The exit end of the underground sluiceway has been covered with concrete rubble and is no longer visible. A shallow, dish-shaped concrete runoff pad extends across the beach from the spillway exit to the low water line.

Waste Type: Construction Debris

Waste Description: Possible chemical and/or radionuclide contamination (see Contaminants of Potential Concern). The contaminants of potential concern are based on those for the 116-H-5 outfall, and include C-14, Cs-137, Sr-90, U-235, -238, and Pu-239/240.

Code: 100-H-41 **Classification:** Accepted

Names: 100-H-41; Contaminated Area; Contaminated Vertical Pipe **Reclassification:** Interim Closed Out (3/15/2011)

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The waste site has been remediated and Interim Closed Out. The site consisted of soil inside a posted Contaminated Area (CA). Within the CA was a 35.6 centimeter (14 inch) diameter, vertical concrete structure. The posted area was as a flat, graded, gravel covered area with rabbit brush. Because the contamination was determined to be due to the presence of mud dauber nests, it was determined that the contamination should be identified as part of the 100-H-37 Mud Dauber Contamination Area waste site.

Location: The site was located 16.29 meters (53.44 feet) east of the 190-H building. It was also within the boundaries of the 100-H-28:2 sample area.

Related Sites/ Structures: 100-H-41 is associated with other contaminated mud dauber nests found in 100-H-37 and 100-H-58. Associated structures include the 183-H and 190-H buildings. Associated WIDS sites include: 100-H-28, Water Treatment Facilities Underground Pipelines and 100-H-35, 100-H Service Water Pipelines, 100-H Clean Water Pipelines.

Process Description: The concrete structure inside the posted Contamination Area (CA) appeared to be associated with a filtered water line from the 183-H facility. The filter water line serviced the 190-H Building operations via a 60.96 centimeter (24 inch) cast iron pipe. The 35.6 centimeter (14 inch) diameter concrete structure may be related to the 100-H-28 Water Treatment Facilities Underground Pipelines. The basis for the radiological posting of the site as a CA was unknown. There was no process knowledge indicating radiological contamination would be present at the location. It is possible the radiological CA posting may have been associated with mud dauber contamination that was prevalent in the 100-H area (also see 100-H-37). Because process knowledge was inconclusive, WIDS information identified the site as an Unplanned Release.

Closure Info: Interim: Prior to performing the excavation, a radiological survey of the surface soil was performed with no radiological contamination detected above background. As the excavation proceeded, plastic sheeting was noted approximately 15 centimeter (6in.) below the ground surface, holding the soil above it from entering the pipe. The pipe was empty below the plastic to a depth of approximately 0.9 meter (3 ft). Mud dauber nests were found on the inside of the pipe. Field radiological surveys of the nests identified up to 450,000 disintegrations per minute beta-gamma contamination on the nests. Because the contamination was determined to be due to the presence of mud dauber nests, it was determined that the contamination was more appropriately identified as part of the 100-H-37 Mud Dauber Contamination Area waste site. Therefore, on November 12, 2009, the Field Remediation project excavated and removed the contaminated materials, including the pipe and soil, for disposal at the Environmental Restoration Disposal Facility as part of the ongoing 100-H-37 remediation effort.

Code: 100-H-42	Classification: Accepted
Names: 100-H-42; 1906-H Drainage Lift Station	Reclassification: Interim Closed Out (9/25/2015)
Type: Pump Station	Start Date:
Status: Inactive	End Date:

Description: The waste site has been remediated and Interim Closed Out. It was a reinforced concrete flume and reservoir designed to receive process sewer discharges from all of the nonradioactive buildings in the 100-H Area.

Location: The site was located approximately 75 meters (246 ft) north of the demolished 107-H retention basin. The approximate center of the remaining underground structure is E578058/N152819 (Washington State Plane coordinates).

Related Sites/ Structures: Primary structures that discharged to 100-H-42 include 182-H, 183-H, 184-H, 190-H, 1908-H, 1715-H, 1716-H, and 1717-H buildings. Other associated structures include: 100-H-36 Spillway, 116-H-5, 1904-H Outfall Structure, 116-H-7 Retention Basis, and 100-H-34 River Effluent Pipelines.

Process Description: The 1906-H Drainage Lift Station was designed to receive process sewer discharges (primarily floor drains) from all of the non-radioactive buildings in H Area. The structure consisted of a rectangular-shaped reinforced concrete reservoir and by-pass flume, surmounted by a one-story concrete-block building over a portion of the reservoir section. The facility originally contained five pumps; three 66,245 LPM (17,500 GPM) electric pumps, one 56,781 LPM (15,000 GPM) electric pump, and one 7,571 LPM (2,000 GPM) electric pump. A concrete dividing wall running the length of the structure separated the flume and reservoir sections. Two electrically operated gates controlled the flow into the structure, and flow between the bypass flume and the reservoir sections. A 15 cm (6 in) concrete slab cover supported the above grade building. This building contained the pump room, switch gear, and controls. A 183 cm (72 in) pipeline entered the facility on the west end of the flume, and exited the east end of the flume directly to the 1904-H Diversion Box (P-2091). Construction materials included 1,489 cubic meters (1,950 cubic yards) of concrete, 126 tonnes (139 tons) of reinforcing steel, 1.36 tonnes (1.5 tons) of structural steel, and 4,370 concrete blocks. In 1974 this above grade building was demolished into the reservoir and the site backfilled with clean soil (letter UNI-7231974). The entire below grade reservoir is made of 0.9 m (3 ft) thick reinforced concrete. The 1908-H Effluent Monitoring Station was used to sample and monitor cooling water process effluent which was being discharged to the river via the 1904-H Diversion Box. The 1904-H Diversion Box received process waste from the 107-H Retention Basin and the 1906-H Drainage Lift Station.

Waste Type: Soil

Waste Description: The waste associated with the 1906-H lift station includes piping and remaining equipment (pipeline and concrete reservoir), rubble and underlying soils associated. Potential contaminants of concern include sodium dichromate, total petroleum hydrocarbons (TPH), polychlorinated biphenyls (PCBs), sulfuric acid, lead, mercury, and paint solvents.

The waste associated with the 1908-H Effluent Monitoring Station includes the piping and underlying soils associated. Potential contaminants of concern include Cs-137, Co-60, Eu-152, Eu-154, Eu-155, Ni-63, Pu-238, Pu-239/240, Sr-90, U-238, hexavalent chromium, total chromium, lead, mercury, paint solvents, sulfuric acid, TPH and PCBs.

Closure Info: Interim (9/25/2015): 100-H-42 and 100-H-28:2 were reclassified in the same Remaining Sites Verification Package. Confirmatory sampling at the 100-H-28:2 subsite was conducted between May 2008 and December 2008. The contents of two french drains that were discovered during the confirmatory sampling activities were sampled and the results for each exceeded groundwater and river protection RAGs for lead. The french drains were located within the planned excavation layback. 100-H-42 waste site was recommended for remediation without confirmatory sampling.

Remedial action at the 100-H-28:2 subsite was performed from September 2011 through March 2012; September 2013 through March 20, 2014 and September 2 through September 23, 2014. The 100-H-28:2 excavation extended to an approximate maximum depth of 9 meters (29.5 ft) bgs. The waste material included 11 to 22 meters (36 to 72 in.) diameter concrete pipe, 1.8 to 2.4 meter (6 to 8 in.) diameter concrete-encased vitrified clay pipe, manhole debris, interfering structural debris, and former building demolition debris. The structural and demolition debris included reinforced concrete, coal ash, steel pipe, asbestos transite, and other general building demolition debris. The asbestos transite debris was encountered at the ground surface prior to excavation of the 100-H-28:2 pipeline. The asbestos transite debris was removed and direct loaded for disposal at the Environmental Restoration Disposal Facility (ERDF). All removal and handling of asbestos transite debris was conducted and directed by asbestos competent individuals. Approximately 21,650 bank cubic meters (BCM) (28,317 bank cubic yards [BCY]) of contaminated soil and debris were removed from the 100-H-28:2 subsite and staged at the staging pile areas (SPAs) pending loadout and disposal.

Remediation at the 100-H-42 waste site began in October 2013 and was completed on March 3, 2014. The waste from this site included reinforced concrete, steel pipe, asphalt, soil, and miscellaneous demolition debris from the large subsurface structure associated with the 1906-H Drainage Lift Station. Approximately 5,200 BCM (6,801 BCY) of contaminated material was removed from the 100-H-42 excavation and staged at the SPA locations for disposal at ERDF. The 100-H-42 waste site was excavated to an approximate depth of 9 meters (29.5 ft) bgs. A large concrete monolith remains at the bottom of the 100-H-42 excavation that protrudes to groundwater.

Code: 100-H-43	Classification: Accepted
Names: 100-H-43; Maintenance Garage; Repair Shop	Reclassification: Interim Closed Out (3/5/2015)
Type: Maintenance Shop	Start Date:
Status: Inactive	End Date:

Description: This site has been remediated and Interim Closed Out. It consisted of the below-grade components at the 1716-H Maintenance Garage. The waste site included a lubrication pit, a waste oil tank, floor drains, underground piping, and two french drains that may have received drainage waste from the facility. The facility was used to service the area vehicles. The site includes the following components:

An 8.4 meter (27.6 ft) long concrete lubrication pit.

A 2,082 liter (550 gal) underground waste oil tank located on the north side of the facility and the 10.2 cm (4 in) diameter underground cast iron pipeline running to it from the lubrication pit. A 10.2 cm (4 in) diameter, underground cast iron pipeline that carried waste from floor drains in the battery room, compressor and oil storage room, lubrication pit, and the repair shop to the process sewer (see 100-H-28:2).

A 61 cm (24 in) french drain on the north side of 1716-H that received steam condensate through a 5.1 cm (2 in) cast iron pipeline. The french drain may also have been available to receive other wastes through a 10.2 cm (4 in) cleanout near the wall opening in the battery room. A 61 cm (24 in) french drain on the north side of 1716-H (just west of the french drain described above) that received effluent from a floor drain and sink in the battery room. The two underground pipelines that carried the waste to the french drain were a 7.6 cm (3 in) cast iron pipe and a 3.8 cm (1.5 in) lead pipe. The piping included two 3.8 cm (1.5 in) cast iron suction lines and two 5.1 cm (2 in) vent risers (partially above grade).

Location: The site is located 200 meters (650 ft) northeast of the former 105-H Reactor, and 40 meters (131 ft) east of the former 105-H Retention Basin. The center of the original facility in Washington State Plane coordinates is at E577990, N152691. The center of the used oil storage tank in Washington State Plane coordinates is E577995, N152709. The center of the lubrication pit is E577995, N152697. The center of the fuel island is E577972, N152683. The center of the two northern french drains are (east and west respectively) E577989, N152709 and E577987, N152709. The center of the southern french drain is E577997, N152673.

Related Sites/ Structures: The 100-H-3, 1716-H Garage Fuel Tanks were approximately 6.7 meters (22 feet) directly south of the building. Other associated structures include: 100-H-28, 100-H Water Treatment Facilities Underground Pipelines, and the 116-H-6, 183-H Solar Evaporation Basins.

Process Description: The 1716-H Maintenance Garage was built during construction of the 100-H Area Reactor and ancillary facilities from 1948 to 1949 to service area vehicles. The original building was a one story, wood-frame structure with an area of 660 square meters (7,100 sq. ft). The building included a tire shop, battery room, compressor oil storage room, and vehicle service area. At some point during its operation about half of the building was converted to shops for maintenance, calibration, and repair of electrical and electronic instruments. There were also underground fuel storage tanks and a fuel pump island at the site that were within the adjacent 100-H-3, 1716-H Garage Fuel Tanks Site. The 100-H-3 waste site was remediated in 2009 and interim closed out in 2011. The 1716-H Building was demolished and the site leveled in 1974.

The building contained a repair shop, tire shop, battery room, compressor and oil storage room, mechanical equipment room, office, parts, toilet, locker, and lunch room.

The 1716-H Maintenance Garage was equipped as a service station, and for light maintenance and repair. At one point about half of the building was converted to shops for maintenance, calibration, and repair of electrical and electronic instruments. Operations were discontinued at the 1716-H building when 105-H was deactivated in 1965. The building was dismantled prior to 1974. The footings and foundation were demolished, backfilled and the site was leveled in 1974. A past employee stated he believed waste oil was commonly dumped on ground surface near auto shop as dust inhibitor.

1716-H was built with the same design details as 1716-F (sitecode 100-F-49). The two facilities are analogous.

Waste Type: Process Effluent

Waste Description: Automobile wastes may include gasoline, diesel, motor oil, antifreeze, automatic transmission fluid, battery acid, engine and radiator flushes, brake fluid, engine and metal degreasers. Contaminants of potential concern include volatile organic compounds, semi-volatile organic compounds, sulfate, pH, lead, cadmium, mercury, chromium, hexavalent chromium, polychlorinated biphenyls, TPH-Gasoline Range, TPH -Diesel Range, and TPH-Oil Range.

Closure Info: Interim (3/5/2015): Because 100-H-43 (1716-H) was analogous with 100-F-49 (1716-F), the previously reviewed confirmatory samples from 1716-F were applied to 100-H-43.

Remedial action at the 100-H-43 waste site began on March 3, 2014, and was completed on March 10, 2014. All components of the waste site have been removed. Approximately 1,500 bank cubic meters (BCM) (1,960 bank cubic yards [BCY]) of contaminated soil and debris was removed and staged at a staging pile area (SPA) pending loadout and disposal. The waste from the site included soil and debris consisting of concrete, asphalt, steel piping, and miscellaneous demolition type debris (e.g., rebar, wood). Asbestos containing materials were not observed during the 100-H-43 remediation. An additional 358 BCM (468 BCY) of soil was removed from the excavation on September 18 and 19, 2014. The excavation extended to a maximum depth of approximately 2.7 meters (9 ft) below ground surface. The spoil pile area (SPA) had previously received waste from the 100-H-46 waste site. Waste staging from the 100-H-43 waste site began on March 3, 2014. Additionally, waste from the 100-H-49:1, 100-H-51:1, and 100-H-51:6 waste sites was added to this SPA. Waste loadout of the SPA with disposal at the Environmental Restoration and Disposal Facility (ERDF) was conducted in July 2014.

Code: 100-H-44	Classification: Accepted
Names: 100-H-44; 183-H Neutralization Pit; H-016	Reclassification: Interim Closed Out (7/9/2015)
Type: Process Unit/Plant	Start Date:
Status: Inactive	End Date:

Description: The site was remediated and Interim Closed Out in conjunction with the 100-H-28:3 and 100-H-28:5 subsites. It consisted of the 183-H Neutralization Pit structure, potentially contaminated soil and associated piping. There were no visible surface features that identified the pit. The neutralization pit was within the footprint of the 100-H-28 Process Sewer. The pipelines were contained in a concrete trench extending from the acid head tank to the neutralization pit and then to the west wall of the 183-H Head House.

Location: The site was located in the 100-HR-1 Operable Unit. The Neutralization Pit was located 59 meters (194 ft) west of the 183-H Head House (west of the railroad car spot) and 9 meters (30 ft) north of the 183-H Flocculent Basin flume wall. The center coordinates are E577712.58, N152881.48.

Related Sites/Structures: The 183-H Neutralization Pit was associated with the 183-H Filter Plant, acid pipelines, railroad car spot, the 100-H -28 Process Sewers (located below and adjacent to the pit)

Process Description: The neutralization pit served as a structure to treat spilled chemicals and excess concentrated sulfuric acid (from acid tank cleanouts) prior to disposal through the 100-H-28:3 pipelines.

The 183-H Filter Plant was designed to treat raw river water before it entered the 190-H building. Chemicals were added to the river water in the head house. The head house was used for the storage, preparation, and addition of alum, chlorine, and sulfuric acid for water treatment. Alum was used as a flocculating agent and sulfuric acid was used to control the acidity of the water. Chlorine was added to control algae. Concentrated sulfuric acid was received by railroad car and stored outside in horizontal storage tanks. Chemicals were delivered as bulk materials and unloaded from railroad cars by either bottom dumping or side unloading to conveyors. Concentrated sulfuric acid, received by railroad car, was stored outside

in horizontal storage tanks. It was pumped from the storage tanks to the head tank through black iron pipelines. Pipelines used to transport lime slurry and acid solutions were encased in an underground concrete trench with a concrete cover. The interior surface of the trench was coated with AMERCO at #55 chemical resistance coating (H-1-5671). Along the length of the trench various pipelines made connection outside of the trench to above grade ancillary equipment including the acid pumps and the acid tanks. The concrete trench was sloped to allow drainage of liquids to the neutralization pit. The neutralization pit served as a structure to treat excess concentrated sulfuric acid (from acid tank cleanouts) prior to disposal through the north process sewer. In addition to receiving sulfuric acid the neutralization pit received lime slurry from the 183-H Head House. The building also contained rooms for chlorine storage, lavatories, janitor's room, electrical switchgear room, and a locker room (HW-74094). The neutralization pit served as a structure to treat excess concentrated sulfuric acid (from acid tank cleanouts) prior to disposal through the north process sewer. The Neutralization Pit received sulfuric acid from two storage tanks and one acid head tank, and lime slurry from the 183-H Head House. The surface elevation was 126.97 m (416.56 ft). In the center of the pit is a vertical orientated vitrified clay pipe (VCP) with a Vitrabond seal at approximately 0.9 m (3 ft) below grade surface (bgs). Vitrabond consists of a conventional glass ionomer, in conjunction with a light-curing resin and hydroxy-ethylmethacrylate. The pit was constructed on top of a concrete monolith and vertically drained with a 10.2 cm. (4 in) VCP into a 76.2 cm (30 in) reinforced concrete pipe (RCP) extra strength process sewer line (100-H-28:3 North Process Sewer). The process sewer pipe was at inverse elevation 123.52 m (405.26 ft). The pit drain line was perforated with the pit itself and within the drain line was a 2.54 cm (1 in) diameter (Hastelloy) rod which seated into a 7.62 cm. (3 in) diameter lead hemisphere. The lead hemisphere was seated in the floor of the pit in the acid proof brick layer. Hastelloy is a trademark for a series of high-strength, nickel based, corrosion resistant alloys produced by Haynes International (H-1-5671). Portions of the above described neutralization pit may remain. The piping included a sulfuric acid supply and drain lines, a lime slurry pipeline, sludge trap drains, filtered water and steam condensate drain lines. The pipelines were contained in a concrete trench extending from the Acid Head tank to the Neutralization Pit and then to the west wall of the 183-H Head House. Also included were short sections of pipelines connecting to ancillary equipment outside of the trench. Also included in the site are two french drains, a steam trap, and acid pump foundation. One 30.48 cm (12 in) french drain (E577728.89, N152882.85) was located adjacent to the covered car spot and was connected to a compressed air line. The second french drain (E577735.51, N152880.58) received steam condensate adjacent to the 183-H Head House Acid Facility Silica Tank. A steam trap was located between the silica tank and the 183-H Head House (E577732.5, N152876.2). The steam trap was the termination point for a silica tank condensate pipeline. Although the french drain and steam trap both supported the silica tank, the relationship of the two to each other is not known. The acid pump foundation (E 577721.0, N152883.2) held two pumps located to the north side of the trench. Portions of the foundation were below grade. Historical documentation does not indicate if the pumps were located above grade and were removed or are still within the below grade portion of the foundation. The foundation had a "Lead Fill" type cover measuring 1/16 of an inch thick.

- Waste Type:** Equipment
- Waste Description:** The site received concentrated sulfuric acid which may have included lead and mercury. There may be contaminated equipment components, piping and soil that remain in place.
- Closure Info:** Interim (7/9/2015): The 100-H-28:5 and 100-H-44 waste sites were co-located with the 100-H-28:3 waste site, so remedial actions were conducted concurrently. Confirmatory sampling was conducted at the 100-H-28:3 pipeline subsite on June 2, 2008. Confirmatory sampling was conducted at the 100-H-28:5 subsite on June 2 and 3, 2008. Confirmatory sampling was conducted at the 100-H-44 waste site from test pits on November 4 and 5, 2009.

Remedial actions at the 100-H-28:3 and 100-H-28:5 subsites and the 100-H-44 waste site were

conducted concurrently and began on July 17, 2013, with removal of overburden material. The overburden was combined with material from the 100-H-28:2 and 100-H-28:4 pipeline subsites. In total, the combined overburden removed from was approximately 117,000 bank cubic meters (BCM) (153,030 bank cubic yards [BCY]). No overburden material was retained from the 100-H-44 waste site remediation. A combined 29,438 BCM of material was removed during the remediation of the three pipeline sites. The waste removed from the 100-H-28:3 and 100-H-28:5 subsites included soil, concrete, steel, vitrified clay pipe debris and a brick manhole debris. Waste materials associated with the 100-H-44 waste site included acid-stained soils, concrete sump debris, and small diameter steel pipe debris. Additional wastes included interfering concrete building foundations, surface asphalt, interfering clean water pipelines, interfering steam lines, coal ash, railroad ties, and miscellaneous building demolition debris (e.g., concrete and steel rebar adjacent to previously demolished buildings).

The 100 Area export water line crossed portions of the northwest sections of the 100-H-28:3 and 100-H-28:5 pipelines. Due to the necessity of not disturbing the export water line, approximately 18 meters (60 ft) of the 100-H-28:3 and 12 meters (40 ft) of the 100-H-28:5 pipelines were left in place.

Code:	100-H-45	Classification:	Accepted
Names:	100-H-45; 1717-H UST; H-015; Underground Propane Tank	Reclassification	Interim No Action (7/8/2010)
Type:	Storage Tank	Start Date:	
Status:	Inactive	End Date:	
Description:	The site has been evaluated and determined to require No Action. It was a suspect propane underground storage tank (UST) and associated below grade piping or features. It is unknown if the propane tank shown in the historical construction drawing (SK-1-7325) was ever installed.		
Location:	The suspect propane UST is located near the northeast corner of the 1717-H building. The tank's location is shown on SK-1-7325 at coordinates E578018, N152621.		
Related Sites/ Structures:	The propane tank is associated with the 1717-H building and the 1717-H Hot Shop (sitecode 100-H-4).		
Process Description:	The 1717-H Building housed a machine shop, sheet metal shop, fabrication, shop, and carpenter shop that provided services for all of the 100 Area operations. The fabrication shop was outfitted for fabrication and repair of reactor system components, particularly those associated with water treatment and pumping systems. A portion of the 1717-H Building was also used as a hot shop, for work on very low-level radioactive materials.		
Waste Type:	Chemical Release		
Waste Description:	Potential contaminants include propane hydrocarbons in the soil.		
Closure Info:	Interim: Geophysical surveys did not identify any anomalies consistent with a buried tank. A test pit was excavated to a depth of 2.4 meters (8 ft). on November 10, 2009. Confirmatory sampling were collected from the test pit. No radiological contamination or organic vapors were observed.		

Code:	100-H-46	Classification:	Accepted
Names:	100-H-46; 190-H Potential Contaminated Soil	Reclassification	Interim Closed Out (4/29/2014)
Type:	Process Unit/Plant	Start Date:	

Status: Inactive**End Date:**

Description: The waste site has been remediated and Interim Closed Out. It consisted of contaminated soils, concrete structures and drain pipes that were beneath 100-H Area sodium dichromate process equipment, piping, unloading dock and railroad spur. This site was within the footprint of the 190-H Pump house, which was demolished and removed to 1 meter (3 ft) below grade in 1977. The site was approximately the northern twenty percent of the facility with original elevation of 421.0 ft.

The site consisted of several locations that existed along the northern and west sections of the 190-H building where sodium dichromate was handled, mixed and injected into the reactor process water system. There were 4 equipment pads which measured 3.04 meters (10 ft) by 1.34 meters (4.4 ft) by 0.61 meters (2 ft) high. There were 3 concrete trenches that formed a "U" shape which measured 7.66 meters (25.16 ft) by 10.56 meters (34.66 ft) by 1.52 meters (5 ft) depth. Each of the four process water storage tanks had concrete drain pits which measured overall 3.04 meters (10 ft) by 4.87 meters (16 ft) by 1.52 meters (5 ft) depth. A 15.24 cm (6 in) drain line which received fifteen percent sodium dichromate, in the form of overflow, exited the building towards the south process sewer at an elevation of 417.5 ft. There was a loading dock, which received the dry sodium dichromate, it was located adjacent to the railroad spur. And there was an elevator which was used to transport dry sodium dichromate to the upper floors.

Location: This waste site was within the footprint of the 190-H Pump house, that was demolished and removed in 1977. The 190-H building was located 77 meters (252 ft) north of the 105-H Reactor.

Related Sites/ Structures: 183-H Filter Building clearwells and pump room; the 187-H1 and 187-H2 emergency high tanks; the 151-H Primary Electrical Substation; 184-H Power House steam supply; 105-H Reactor and the 100-H-28-2 South Process Sewers.

Process Description: The 190-H complex was a process water treatment plant which supplied the 105-H Reactor with nonradioactive cooling water. Sodium dichromate, in dry crystalline form, was added to filtered water as an anticorrosive agent. The fifteen percent sodium dichromate was injected into piping which fed to four 6,624 kL (1,750,000 gal) Process Water Storage Tanks within the 190-H facility. The sodium dichromate process consisted of a mixing tank, two feed tanks, two centrifugal pumps, eighteen proportioning pumps, piping, valves, and associated electrical and instrument equipment.

Bagged sodium dichromate was delivered to the 190-H building via railcar. An unloading dock, with adjacent elevator inside, was used to convey the material from the railcar to an upper level of the 190-H building (P-1315). The mixing and feed tanks each had a 3,236 L (855 gallon) capacity and were located on the second through fourth floors of the 190-H building (P-1315). There was one mixing tank located directly above the two feed tanks. At the top of the mixing tank were an agitator and a wooden cover with a bag hopper where the sodium dichromate was added. Water was added to the sodium dichromate and mixed to a fifteen percent concentration (HW-27270). A 7.62 cm (3 inch) diameter process pipe, with a three way valve for draining purposes, exited the base of the mixing tank to the feed tanks. Also, a 7.62 cm (3 inch) diameter overflow pipe exited near the top of the mixing tank and connected to the tank drain pipe. The 7.62 cm (3 inch) mixing tank pipe entered through the top of two sodium dichromate feed tanks located below the mixing tank. The feed tanks were 1.5 meter (5 ft) in diameter with a conical bottom. A 7.62 cm (3 in) diameter overflow pipe exited near the top of each tank. At the base of the feed tanks was a 3.8 cm (1 inch) diameter pipe that fed the liquid concentrate to four injection pump pads (P-1315). The sodium dichromate concentrate piping was located next to the north wall, elevated above the floor, and ran approximately the full length of the building servicing the four injection pump locations. The sodium dichromate liquid was added to the filtered water by injection pumps through chemical feed injection rings. The injection rings were located inline with 76 cm (30 inch) and 107 cm (42 inch) diameter pipes that entered the

Process Water Storage Tanks through automatic control valves (P-1260, P-1874). The drain pipes from the mixing tank and the feed tanks entered a 15 cm (6 inch) drain pipe that fed to the process sewer system which exited north out of the building (P-1221).

Waste Type: Demolition and Inert Waste

Waste Description: The primary contaminate of concern is sodium dichromate. There may be buried debris, i.e., concrete, rebar, and piping below grade.

Closure Info: Interim (4/29/2014): In November and December 2009, confirmatory samples were collected from Test Pits. The soil was analyzed for Hexavalent Chromium, ICP metals and mercury. In November and December 2009, confirmatory samples were collected from Test Pits. The soil was analyzed for Hexavalent Chromium, ICP metals and mercury. Remedial action at the 100-H-46 waste site began on February 5, 2013, and continued through July 16, 2013. Waste removed from the site included concrete and demolition debris, steel pipe, steel rebar, and chromium-contaminated soil. The original design included removal of material to a depth of approximately 3 meters (10 ft) bgs. However, green-stained concrete with concentrations of hexavalent chromium greater than RAGs was discovered in March 2013. The concrete originated from the western portion of the remediation. Several test pits were excavated with in-process samples collected as deep as 5.5 meters (18 ft) below the original surface grade. Due to the discovery of green-stained concrete and the test pit results, the remedial design was changed to allow removal of additional hexavalent chromium-contaminated material in the western portion of the former 190-H Building. Based on the remediation necessary to remove hexavalent chromium-contaminated soil at the 100-D-30, 185-D Sodium Dichromate Trench in the 190-D Complex, and at the 100-F-57, 190-F Process Water Pump House Debris waste sites, the updated 100-H-46 design conservatively allowed for remediation to the depth of groundwater in the area with hexavalent chromium-contamination.

Due to the increased remediation depth, additional overburden/layback material was removed and staged in a pile to the west of the remediation. The clean overburden pile contained approximately 62,000 bank cubic meters (BCM) (81,100 bank cubic yards [BCY]) of soil.

As remediation progressed, in-process samples were collected to measure hexavalent chromium and chromium (total) concentrations in 1.5 meters (5 ft) depth intervals. A sample collected May 16, 2013, from the southwestern corner of the excavation (J1RMF0) indicated hexavalent chromium concentrations in excess of RAGs extended past the design boundary. The remedial design was then expanded to allow additional removal of material in the southwest area of the excavation.

Remediation in the western portion of the waste site extended to the periodically rewetted zone (PRZ) at an elevation of approximately 117.0 meters (384 ft) above mean sea level (amsl) (a depth of 12.5 meters [41 ft] bgs), effectively removing all of the vadose zone soil in this area. In-process sampling of the sidewalls surrounding the excavation floor in the PRZ indicated that the concentration of hexavalent chromium in the remaining soil was less than RAGs.

During the course of remediation, the portion of the 190-H Building foundation within the 100-H-46 WIDS boundary was totally removed. All 100-H-46 confirmatory sampling locations were removed. The only remaining portion of the 190-H Building foundation that remains lies outside of the 100-H-46 waste site boundary, along the southeast edge of the former building.

Approximately 61,300 BCM (80,200 BCY) of contaminated soil and debris was removed and staged at multiple staging pile areas (SPAs) pending loadout and disposal. The SPAs received waste beginning February 5, 2013. Waste loadout of 100-H-46 material with disposal at the Environmental Restoration Disposal Facility began on June 17, 2013, and was completed March 5, 2014. The SPAs were also used to receive waste from other 100-H remediation areas and were not included in the verification sampling of the 100-H-46 excavation and overburden.

Verification sampling of the SPAs will be conducted with sampling of the other waste sites.

During remediation, a previously unidentified french drain was discovered at Washington State Plane (WSP) coordinates N152655/E577686. The base of the french drain extended to approximately 4.6 meters (15 ft) bgs. Red-stained soil and rock were present in the french drain and were sampled. The hexavalent chromium concentration in the sample (2.3 mg/kg), J1RKM3, slightly exceeded direct exposure and river protection RAGs. The french drain location was within the area of the site in which the vadose zone was removed during remedial action. No other anomalies were discovered.

Code:	100-H-48	Classification:	Accepted
Names:	100-H-48; 184-HA Underground Fuel Oil Tanks Associated Piping	Reclassification	Interim Closed Out (4/2/2014)
Type:	Product Piping	Start Date:	1/1/1965
Status:	Inactive	End Date:	
Description:	The site has been remediated and Interim Closed Out. It consisted of potentially remaining fuel oil piping that was associated with two fuel oil underground storage tanks (UST's) that supported the 184-HA Boiler House Building. The two 45,651 liter (12,036 gallon) fuel oil tanks had been previously removed from the site in 1974.		
Location:	The approximate location for the two fuel tanks was E577833, N152585.		
Related Sites/ Structures:	The piping is associated with the 184-HA boiler, the 190-HA Main Process Pump House Annex and 100-H-52.		
Process Description:	The 184-HA Boiler House Building and associated equipment was constructed in approximately 1965 to replace the 184-H boiler house that was being shutdown in conjunction with deactivation of the 100-H reactor (HW-82720). The reactor was shut down permanently in April of 1965. The boiler provided steam to the administration and Central Shops buildings, which consisted of 1703H, 1704H, 1716H, 1717H, 1719H, 1722H, 1760H, and 1761H.		
	Buildings 1703, 1760, and 1761 were on one supply line and the remaining buildings on another (HW-82720). These steam supply lines were all above grade features (H-1-14575). The 184-H building water/chemical equipment consisted of the following above grade features: (1) fuel oil fired package boiler, (1) brine tank, (2) water softener tanks, (1) chemical treatment tank w/pump, (1) de-aerator w/boiler feed pump.		
	Each tank had a 5.1 centimeter (2 inch) fuel oil supply (FOS) and fuel oil return (FOR) pipe line connected to it that comes from a pump pit on the south side of the building. The fuel oil piping, as it leaves the south end of the pump pit going to the tanks, is at 0.6 meters (2 feet) elevation (H-1-14579). The fuel oil piping consists of ASTM A-53 schedule 40 black steel covered with taping. This buried piping was required to have an exterior coat of coal tar enamel with bonded asbestos felt wrap, with the joints wrapped in coal tar tape (tapecoat). A U-shaped concrete trench in the floor of the 184-HA building contained fuel oil supply and return lines, a propane (PR) line (boiler pilot light connection - H-1-14579), the 5.1 centimeter (2 inch) influent sanitary water (SW), and (2) trench floor drains that connected to the 5.1 centimeter (2 inch) sanitary drain (SD) connected at the east end of the building drain field's (west of the building) 20.3 centimeter (8 inch) perforated concrete main line (H-1-14576 and H-1-14577). Steam line vent valves and a 1.9 centimeter (0.75 inch) soot blower drain valve also emptied effluent into the trench (H-1-14583).		
Waste Type:	Soil		

Waste Description: Fuel oil potentially remains in the piping and the underlying soil.

Closure Info: Interim (4/2/2014): Geophysical surveys were done in 2007. Confirmatory sampling was done from within Test Trenches in November 2009.

Remediation of the combined 100-H-48 and 100-H-52 waste sites was performed from July 25, 2013 through July 29, 2013 to a depth of approximately 4.6 meters (15 ft). A combined volume of approximately 1,576 bank cubic meters (BCM) (2,061 bank cubic yards [BCY]) of contaminated soil and debris was excavated and stockpiled for disposal at the Environmental Restoration Disposal Facility (ERDF). Debris waste included piping associated with the former underground fuel tanks and piping associated with the 100-H-52 drain field. Other concrete and steel debris was encountered at the former underground tank location. During remediation, field screening for VOCs was conducted and no elevated readings were detected. All waste material was stockpiled, prior to shipment and disposal at ERDF. All waste material from the 100-H-48 and 100-H-52 waste sites have yet to be loaded out to ERDF. The waste staging pile area will be sampled and closed out with a separate waste site at a later date.

Code: 100-H-49

Classification: Accepted

Names: 100-H-49; Potentially Contaminated French Drains

Reclassification: Interim Closed Out (3/18/2015)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: All of the subsites have been reclassified, so the parent site is considered Interim Closed Out. The site consisted of sixteen french drains, the underlying soil of the potentially contaminated french drains, and their associated below grade piping components. The site was divided into three subsites:

100-H-49:1 is the 184-H Boiler House and 1717-H Hot Shop French Drains and the 105 H Reactor TP3 drain (Reclassified to Interim Closed Out)

100-H-49:2 is the 119-H, 181-H, 184-H, and 183-H French Drains. (Reclassified to Interim No Action)

100-H-49:3 is the 183-H and 1717-H French Drains (Reclassified to Rejected)

Location: Refer to the subsites for the detailed locations of each french drain.

Related Sites/ Structures: The french drains (and drywells) are related to 119-H, 181-H, 183-H, 184-H, 1717-H, and 1719-H.

Process Description: The french drains were discovered during the Orphan Site Evaluation (OSE) historical review. Each of the facilities that the french drains are associated with, were identified and the process or function of the buildings summarized. This information is incorporated into the list of french drains included in the site description for each of the subsites. Details of the inlet pipes sizes, depths of the french drains, and construction drawings are provided when available. Generally, french drains are a minimum of 4.6 meters (15 ft) from the edge of buildings. When exact locations were not available from construction drawings and these locations have been estimated by placing the location 4.6 meters (15 ft) away from building. In other cases, the piping to the french drains is a well defined location. Orphan sites field investigations were conducted on March 12th and 17th of 2008. Photographs of the present site conditions were obtained.

Waste Type: Equipment

Waste Description: The waste consists of the french drains, piping to the french drains, and potentially contaminated soil. The contaminants of potential concern will be evaluated during work planning and confirmatory sampling.

This Site has the Following SubSites:

Code: 100-H-49:1

Names: 100-H-49:1; 184-H Boiler House and 1717-H Hot Shop French Drains

Code: 100-H-49:2

Names: 100-H-49:2; 119-H, 181-H, 184-H and 183-H French Drains

Code: 100-H-49:3

Names: 100-H-49:3; 183-H and 1717-H French Drains

Code: 100-H-49:1

Classification: Accepted

Names: 100-H-49:1; 184-H Boiler House and 1717-H Hot Shop French Drains

Reclassification: Interim Closed Out (3/18/2015)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: This site has been remediated and Interim Closed Out. It consisted of four french drains, the underlying soil of the potentially contaminated french drains and their associated below grade piping components. The waste remediated waste from the 100-H-49:1 french drains was placed in a combined waste staging pile area (SPA). This SPA will be addressed in the 100-H-43 work instruction and closure document.

The drains included in this subsite are:

FD4 - a 0.9 meter (36 in) french drain with a 11 meter (36.1 ft) long, 0.1 meter (4 in) condensate (CNDS) drain line from the 184-H Boiler House Reclaiming Hopper (P-1418) to the french drain. The pipeline enters the french drain 1.07 meter (3.5 ft) below grade. The 184-H building utilized steam from the boilers to heat the coal conveyor system and coal shack. It's unknown whether a non-contact form of steam heating was used. The resulting condensate was drained to 0.1 meter (4 in) vitrified clay tile (VCT) piping located 1.07 meter (3.5 ft.) below grade and was the inlet piping to the french drain. No documents or records were obtained during historical research to indicate the end state of the french drain or underlying soil.

FD5 - a 0.6 meter (24 in) french drain with a 7.2 meters (24 ft) long, 0.1 meters (4 in) vitrified clay tile (VCT) condensate (CNDS) drain line from the 184-H Boiler House Transfer House to the french drain. The pipeline enters the 1.9 meter (76 in) deep french drain at 1.07 meter (42 in) below grade. The 184-H building utilized steam from the boilers to heat the coal conveyor system and coal shack. It's unknown whether a non-contact form of steam heating was used. The resulting condensate was drained to 0.1 meter (4 in) VCT piping 1.07 meter (3.5 ft) below grade and was the inlet piping to the french drain. No documents or records were obtained during historical research to indicate the end state of the french drain or underlying soil.

FD16- a 0.9 meter (36 in) french drain with a 5.2 meter (17.1 ft) long, and a 11 meter (36.1 ft) long pipeline. Each is a 0.08 meter (3 in) diameter heating/steam return line from 1717-H Hot Shop (west side) to the french drain. No documents or records were obtained during historical research to indicate the end state of the french drain or underlying soil.

The 100-H-28:7 french drain was added to subsite to 100-H-49:1. The french drain was discovered along the edge of a test pit that was being excavated to support confirmatory

sampling for process water lines at the 183-H Filter Plant going to the 105-H Reactor (TP3) at coordinates E577853/N152563, The french drain is a 0.9 meter (36-in.) vitrified clay french drain at coordinates 577848 E/52567 N, on the northeast side of the 105-H Reactor.

Location: The locations for each of the French Drains are listed below. Washington State Plane coordinates are provided for each french drain. The associated drawings were rectified to Washington State Plane coordinates to obtain the coordinates listed below.

FD4 - E577504.29/N153006.45

FD5 - E577553.28/N152996.60

FD16 - E577970.71/N152553.58

100-H-28:7 TP3 FD - E577848/N152567

Process Description: The process description was inferred from the construction drawings and the function of the building that they were associated with. This information is provided for each of the french drains in the Site Description above.

Waste Type: Not Specified

Waste Description: The waste is the french drain, piping to the french drain, and potentially contaminated soil.

Closure Info: Interim (3/18/2015): Remedial action at the 100-H-49:1 subsite was conducted from May 7 through May 20, 2014. French drains FD4, FD5, and FD16 were excavated to approximately 2.7 meters (9 ft) below ground surface (bgs). Because of its proximity to an adjacent utility pole, 100-H-28:7 TP3 was excavated to approximately 1.8 meters (6 ft) bgs. A total of approximately 170 bank cubic meters (222 bank cubic yards) of soil and debris were removed from the excavations. The debris consisted of rock, concrete, and various types of pipe. Coal ash is present on the ground surface near french drains FD4 and FD5. All four french drains are located in close proximity to asphalt roadways. No anomalies were found during remediation of the subsite. No in-process soil samples were collected.

The SubSite is Part Of:

Code: 100-H-49

Names: 100-H-49; Potentially Contaminated French Drains

Code: 100-H-49:2

Classification: Accepted

Names: 100-H-49:2; 119-H, 181-H, 184-H and 183-H French Drains

Reclassification: Interim No Action (10/26/2011)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The subsite was evaluated and determined to require No Action. It consists of nine french drains, the underlying soil of the potentially contaminated french drains, and their associated below grade piping components. The drains include:

FD1 was a dry well that was associated with the 119-H Sample Building. A 5.1 cm (2 in) cast iron pipeline ran from the 119-H Sample Building to the dry well. (H-1-19812, H-19805). During the Orphan Site's Walkdown the dry well could not be proven to exist or not exist from the view point outside the fence of the contamination area for the 105-H Reactor. No documents or records were obtained during historical research to indicate the end state of the dry well or underlying soil. Analogous sites include 100-D-24 and 100-F-46. (See orphan site photo # 031708-976).

FD2 was a 0.6 meter (24 in) french drain with a 4.5 meters (14.8 ft) long, 0.1 meters (4 in) cast iron soil line from the 181-H Battery Room to the french drain (P-1337, P-1334). During the Orphan Site's Walkdown, there was no evidence of a recent disturbance or french drain existing within a 5 meters (16.4 ft) diameter area. No documents or records were obtained during historical research to indicate the end state of the french drain or underlying soil. (See orphan site photo #03172008-973).

FD3 was a 1 meter (36 in) french drain with a 4.7 meters (15.4 in) long, 0.1 m (4 in) vitrified clay type (VCT) condensate (CNDS) drain line (P-1417, P-1418). The french drain is 1.9 meter (76 in) deep with the inlet pipeline at 1.1 meter (42 in) below grade. The pipeline comes from the 184-H Boiler House Coal Shack Track Hopper. The 184-H building utilized steam from the boilers to heat the coal conveyor system and coal shack. It is unknown whether a non-contact form of steam heating was used. The resulting condensate was drained via 0.1 m (4 in) VCT piping 1.07 m (3.5 ft.) below grade and was the inlet piping to the french drain. No documents or records were obtained during historical research to indicate the end state of the french drain or underlying soil. (See orphan site photo # 03172008-974).

FD6 was a 1 meter (36 in) french drain with a 8.7 meter (28.5 ft) long, 0.1 m (4 in) diameter vitrified clay type (VCT) condensate (CNDS) drain line from the 184-H Coal Crusher House to the french drain (P-1417, P-1418). The pipeline enters the 1.9 m (76 in) deep french drain at 1.04 meter (42 in) below grade (P-1417, P-1418). The 184-H building utilized steam from the boilers to heat the coal conveyor system and coal shack. It's unknown whether a non-contact form of steam heating was used. The resulting condensate was drained to a 0.1 m (4 in) VCT pipe 1.07 m (3.5 ft.) below grade and was the inlet piping to french drain. No documents or records were obtained during historical research to indicate the end state of the french drain or underlying soil.

FD7 was a 0.6 meter (24 in) french drain with two pipe segments that are 0.1 meter (4 in) diameter vitrified clay type (VCT) condensate (CNDS) drain lines from the 184-H Coal Transfer Tower to the french drain (P-1418). The pipeline enters the 1.9 meter (76 in) deep french drain at 1.07 meter (42 in) below grade (P-1418). The french drain had a total below grade depth of 1.92 meter (76 in) with two 10.2 cm (4 in) diameter VCT inlet pipes 1.07 meter (42 in) below grade and located 4.5 m (15 ft) east from the transfer house and conveyor system. The piping appears to be condensate from a 15.25 cm (6 in) above grade steam main. No documents or records were obtained during historical research to indicate the end state of the french drain or underlying soil.

FD8 was a 1 meter (36 in) french drain with a 5.9 meter (19.4 ft) long, 0.1 m (4 in) vitrified clay type (VCT) line. The inverse elevation at the french drain is 125.9 meters (413 ft). The pipeline runs from the 184-H Boiler House Battery Room floor drain to the french drain. There is a second inlet from an unknown source. No documents or records were obtained during historical research to indicate the end state of the french drain or underlying soil. The location is estimated. (P-1413, P-1417).

FD9 is a 1 meter (36 in) french drain with a 5.6 meter (18.4 ft) long segment, a 6.6 meter (21.7 ft) long segment, and a 2.4 meter (7.9 ft) long segment of pipe; all are 10.16 cm (4 in) vitrified clay type (VCT) line. The french drain is 1.9 meter (76 in) deep with the line inlet at --1.04 m (42 in) below grade (P-1417). The line runs from the 184-H Boiler House laboratory and radiator heating system to the french drain. There is a second inlet pipe at the french drain from an unknown source. No documents or records were attained/obtained during historical research to indicate the end state of the french drain or underlying soil.

FD12 is a 1 meter (36 in) french drain with a 9.7 meter (37.8 ft) long, 0.1 m (4 in) diameter vitrified clay pipeline from the 1719-H First Aid Building (Laboratory Waste) to the french drain. (P-1235) No documents or records were obtained during historical research to indicate

the end state of the french drain or underlying soil.

FD14 is a 0.9 meter (36 in) french drain with a 5.3 meter (17.4 ft) long, 0.08 m (3 in) diameter cast iron (CI) pipeline from 1717-H (northwest side) pipe shop radiator heater to the french drain (P-1436). The pipeline is 1.07 meters (3.5 ft) below grade. (P-1436) No documents or records were obtained during historical research to indicate the end state of the french drain or underlying soil.

Location: The locations for each of the French Drains are listed below. Washington State Plane coordinates are provided for each french drain. The associated drawings were rectified to Washington State Plane coordinates to obtain the coordinates listed below. Order is maintained with the listing in the site description.

FD1 - E577726.55, N152492.97

FD2 - E577523.25, N153473.24

FD3 - E577454.99, N153009.28

FD6 - E577503.89, N152994.26

FD7 - E577553.38, N152956.89

FD8 - E577537.92, N152954.51

FD9 - E577556.16, N152942.17

FD12 - E577927.32, N152676.63 (No french drain exists)

FD14 - E577970.58, N152592.89 (No french drain exists)

Related Sites/ Structures: The french drains (and drywells) are related to 119-H, 181-H, 184-H, 1717-H, 1719-H.

Process Description: The process description was inferred from the construction drawings and the function of the building that they were associated with. This information is provided for each of the french drains in the Site Description.

Waste Type: Not Specified

Waste Description: The waste consists of the french drain, piping to the french drain, and potentially contaminated soil. COPCs ICP metals, mercury, hexavalent chromium, polyaromatic hydrocarbons, polychlorinated biphenyls and total petroleum hydrocarbons.

Closure Info: Interim (10/26/2011): Confirmatory sampling showed the site that did not need remediation.

The SubSite is Part Of:

Code: 100-H-49

Names: 100-H-49; Potentially Contaminated French Drains

Code: 100-H-49:3

Classification: Accepted

Names: 100-H-49:3; 183-H and 1717-H French Drains

Reclassification: Rejected (1/23/2012)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The original waste site description indicated it consisted of four french drains, the underlying soil of the potentially contaminated french drains, and their associated below grade piping components. Based on historical research, field investigation and confirmatory sampling (performed in 2010), it was concluded that these four french drains were either previously remediated, removed or never constructed. The french drains were identified during the orphan sites evaluation historical review, conducted on March 12 and 17, 2008, and documented in the 100-H Area Orphan Sites Evaluation Report.

The drains considered include:

FD10 - a 0.46 meter (18 in) Drywell with a 45.5 meter (149.3 in) long, 0.1 (4 in) diameter cast iron (CI) pipe to the french drain. The pipeline ran from the 183-H Post Filter Building to the french drain. The site received drainage from the battery, electrical, pump house and chlorine room. The inverse elevation at the french drain is 124.4 meters (408.11 ft). The location is estimated. No documents or records were obtained during historical research to indicate the end state of the french drain or underlying soil. (P-1221, P-4302, P-4305) (See orphan site photo # 03122008-957).

FD11 - a 0.9 meter (36 in) french drain with a 17.9 meter (58.7 ft) long, 0.1 m (4 in) diameter pipeline from 183-H (post filter) to the french drain. The site received drainage from the battery, electrical, pump house and chlorine room. The inverse elevation at the french drain is 124.4 m (408.11 ft). The location is estimated. (P-1221, P4302, P-4305) No documents or records were obtained during historical research to indicate the end state of the french drain or underlying soil. (See orphan site photo # 03122008-958).

FD13 - a 8.0 meter (26.2 ft) long cast iron, 0.08 meter (3 in) diameter pipeline that ran from the 1717-H machine/welding shop typical heaters to a 0.76 m (30 in) french drain (remediated with waste site 100-H-4). No documents or records were obtained during historical research to indicate the end state of the french drain or underlying soil (P-1436) (See orphan site photo # 03122008-967).

FD15 - a 0.76 meter (30 in) french drain with a 7.8 m (25.6 ft) long, 0.08 (3 in) diameter cast iron (CI) pipeline that ran from 1717-H (east side) Electrical Shop and Mechanical Equipment room heaters to the french drain (P-1436). No documents or records were obtained during historical research to indicate the end state of the french drain or underlying soil. (See orphan site photo # 03122008-968).

Location: The locations for each of the French Drains are listed below. Washington State Plane coordinates are provided for each french drain. The associated drawings were rectified to Washington State Plane coordinates to obtain the coordinates listed below.

FD10 - E577782.08, N152761.73 (No french drain exists)

FD11 - E577778.37, N152752.41 (The location is estimated.)

FD13 - E578009.56, N152598.17 (see sitecode 100-H-4; The location is estimated.)

FD15 - E578009.69, N152570.62 (The location is estimated)

Related Sites/ Structures: The french drains (and drywells) are related to 183-H and 1717-H and waste site 100-H-4.

Process Description: The process description was inferred from the construction drawings and the function of the associated building.

Waste Type: Not Specified

Waste Description: The waste is the french drain, piping to the french drain, and potentially contaminated soil.

Closure Info: Interim (1/23/2012): French drain FD 10 and FD 15 test pit locations were excavated up to 0.6 meters (2 ft) below ground surface, attempting to locate the french drains. At FD 15 excavation, a utility encased in concrete was observed approximately 2 feet below ground surface, under asphalt, trending west-east direction. No french drains were observe. Additional scraping was performed to widen the bottom of the 0.6 meter (2 ft) test pit to a 6.1-meter (20 ft) diameter test pit. No french drains or any drain components were found at these locations. Based on the test pit observations and the nature of the soils (i.e., lack of rubble/debris, original asphalted location), it was determined that french drains were not constructed at these locations. The test

pit excavation at FD 11 was not performed due to safety concerns of above ground interferences. A pump and treat water and power line is located next to this test pit location, making it impossible to safely excavate without impacting the power line and the associated water lines. Because both the FD 10 and FD 11 french drain locations were inferred from the construction drawing therefore estimating coordinates and the FD 10 was not found during the test pit excavation, it was determined that FD 11 is also unlikely to be present at its suggested location.

Fragments of drain piping, associated with the FD 13 french drain were remediated and disposed during the 100-H-4, 1717-H Hot Shop, French Drain, and Contaminated Storage Unit waste site excavation. The 100-H-4 waste site was reclassified as Interim Closed Out in June 2011.

The SubSite is Part Of:

Code: 100-H-49

Names: 100-H-49; Potentially Contaminated French Drains

Code: 100-H-50

Classification: Accepted

Names: 100-H-50; 100-H Steam Condensate French Drains

Reclassification: Interim No Action (6/16/2011)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The site was evaluated and determined to require No Action. It consists of fourteen discrete locations, underlying soil and their associated below grade piping components for steam condensate French Drains. The French drains were discovered during the Orphan Site Evaluation (OSE) historical review. Each of the facilities that the French drains are associated with, were identified and processes or functions of the buildings summarized in the list below. Details of inlet pipe sizes, depths and French drain size and construction details and depths are provided when available in the descriptions below. When exact locations were not available from construction drawings the location was estimated by placing the location 4.6 meters (15 feet) away from building. In these cases the inlet piping is in a well defined location. See detailed spatial analysis map for French Drain locations.

Orphan sites field investigations were conducted on March 12th and 17th of 2008. Photographs of the present site conditions were obtained.

FD1. The site is a 1.22 meter (48 in) reinforced concrete pipe French drain with a 0.1 meter (4 in) clay tile 6.1 meters (20 ft) long at a 1% slope (1 in of slope per linear foot of pipe) from 1.1 m (42 in) raw water line. The site is associated with the 182-H Reservoir (north end) (P-4737 Sheet 1, P-4737 Sheet 2). No documents or records were obtained during historical research to indicate a final disposition for the site.

FD2. The site is a 0.9 meter (36 in) French drain with a 0.1 meter (4 in) diameter cast iron (CI) pipeline from the 182-H Reservoir (south side) heater systems to the French drain (P-1368, P-1370). No documents or records were obtained during historical research to indicate a final disposition for the site.

FD3. The site is a 0.46 meter (18 in) dry well with a 2.54 cm (1 in) steam condensate pipeline from the 190-H Building (north side) (H-1-14575, H-1-14580, H-1-14581). No documents or records were obtained during historical research to indicate a final disposition for the site.

FD4. The site is a 0.46 meter (18 in) dry well with a 0.05 meter (2 in) steam condensate

pipeline from the 190-H Building (east side) (H-1-14575, H-1-14580, H-1-14581). No documents or records were obtained during historical research to indicate a final disposition for the site.

FD5. The site is a 0.61 meter (24 in) dry well, 1.4 meters (4.6 ft) deep with a 2.54 cm (1 in) steam condensate pipeline from 190-H Building to the dry well (H-1-14575, H-1-14580, H-1-14581). No documents or records were obtained during historical research to indicate a final disposition for the site.

FD6. The site is a 0.61 meter (24 in) dry well with a steam condensate pipeline from the 1703-H Office Building (west side) to the dry well (P-9340). No documents or records were obtained during historical research to indicate a final disposition for the site.

FD7. The site is a 0.61 m (24 in) French drain with a ventilation drainage pipeline from the 1703-H Office Building (east side) to the French drain (P-9340). No documents or records were obtained during historical research to indicate a final disposition for the site.

FD8. The site is a 0.9 meter (36 in) French drain from the 184-H building (north side) that utilized steam radiator unit heaters with 1.9 cm (0.75 in) condensate blow off traps and drip legs which discharged to French drains with 0.1 m (4 in) diameter vitrified clay type (VCT) inlet piping to the French drain (P-1417).

FD9. The site is a 0.9 meter (36 in) French drain with a 0.1 meter (4 in) diameter VCT pipeline from a return riser and steam supply riser from the 184-H Boiler House (east side) to the French drain (P-1417). No documents or records were obtained during historical research to indicate a final disposition for the site.

FD10. The site is a 0.9 meter (36 in) French drain with a 0.1 meter (4 in) diameter VCT condensate pipeline from the 184-H Boiler House (west side) to the French drain. (P-1417) No documents or records were obtained during historical research to indicate a final disposition for the site.

FD11. The site is a 0.61 meter (24 in) French drain with a 0.1 meter (4 in) diameter VCT pipeline from a return riser and steam supply riser from 184-H Boiler House (south side) to the French drain. (P-1417) No documents or records were obtained during historical research to indicate a final disposition for the site.

FD12. The site is a 1 m (36 in) French drain with a 9.4 meters (31 ft) long, 2.54 cm (1 in) line connecting from the 1901-H Water Tower trap discharge to the French drain (P-1426). There is an additional pipeline to the French drain that is a 8.8 meters (29 ft) long, 3.81 cm (1.5 in) line connecting from the 1901-H Water Tower ejector discharge to the French drain (P-1426). The pipelines are soft water trap discharge lines (P-1416 and P-1426).

FD13. The site is a 0.9 meter (36 in) French drain with a 0.1 meter (4 in) vitrified clay (VC) pipeline to the French drain (P-1237). No documents or records were obtained during historical research to indicate a final disposition for the site.

FD14. The site is a 0.61 meter (24 in) French drain filled with soil/gravel. The drain was discovered in the field during the orphan site evaluation. The french drain does not appear on any construction drawings. The proximity of french drain FD5 to FD14 suggests that they might one in the same. The french drain is believed to receive steam condensate from the 190-H Annex. This drain was later discovered to be the same as (duplicate) FD5.

Location: Selected as built construction drawings were rectified into the Geographic Information System (GIS) for each of the french drains and associated piping locations. The coordinates are provided in Washington State Plane coordinates. The coordinates are listed in the same

sequence as the elements in the site description.

Easting Northing

FD1 - E577818.69, N153047.52
 FD2 - E577757.55, N152923.92
 FD3 - E577860.28, N152695.06
 FD4 - E577869.99, N152659.28
 FD5 - E577799.90, N152581.30
 FD6 - E577911.73, N152556.89
 FD7 - E577946.23, N152551.07
 FD8 - E577535.93, N152954.52
 FD9 - E577556.29, N152918.35
 FD10 - E577523.63, N152909.26
 FD11 - E577540.71, N152880.20
 FD12 - E577527.71, N152963.39
 FD13 - E577926.74, N152624.98 (The location is estimated.)
 FD14 - E577801.04, N152586.00

Process Description: The process descriptions were ascertained from construction drawings and are provided with construction drawing numbers. A spatial analysis was conducted for each of the french drains and dry well and all have been identified as receiving steam condensate. Steam was typically used at all facilities for heating purposes. The 184-H Power House boiler facility supplied high pressure steam to all buildings through an above grade pipeline system. The boiler facility utilized clean filtered water from the 183-H filter building. The steam supply was used in a non-contact radial heating system. As a non-contact system the steam remained uncontaminated. The steam transport process utilized a high pressure supply line and a low pressure return or discharge line. It was necessary to bleed both the supply and return lines to prevent condensate build up. The condensate was typical blow off from the above grade piping system into a below grade covered French Drain as illustrated on construction drawings as a safety precaution. French drains' diameters and construction material varied depending on steam piping size, service capacity or pounds per hour, and expected flow rate received.

Waste Type: Equipment

Waste Description: The waste is the French drain and associated piping.

Closure Info: Interim: Confirmatory sampling activities were performed from October 5 to 11, 2010. One french drain from each of the building locations within the 100-H-50 waste site was selected for sampling, for a total of five french drain test pits. The french drains were selected based on confidence in the location, as determined by surface visibility and/or details from the historical building drawings. The five french drains that were selected for sampling are 2, 5, 6, 11, and 13. Active pump and treat lines were observed at the french drain 2 location during confirmatory sampling, and no excavation or sampling was conducted at the location because of the resulting surface interference. At the location for French Drain 13, an area approximately 3 by 3 meters (12 by 12 ft) was excavated. Based on the absence of debris and rubble observed in the excavated area, it was determined that there is no french drain at the location, and the excavation was backfilled. The remaining site french drain locations were excavated and sampled. The sample results indicated No Action was required.

Code: 100-H-51

Classification: Accepted

Names: 100-H-51; Potentially Contaminated Pipeline Segments

Reclassification: Interim Closed Out (7/9/2015)

Type: Process Sewer

Start Date:

Status: Inactive**End Date:**

Description: This site consists of six subsites. All of the subsites have been addressed, so the parent site is reclassified to Interim Closed Out. Subsite 1 was a 15.2 cm (6 in) vitrified clay pipe sanitary sewer pipeline and was Interim Closed Out. Subsite 2 was a 5.08 cm (2 in) steel brine discharge line and has been Interim Closed Out. Subsite 3 consisted of two parallel pipelines, a 5.1 cm (2 in) steel brine discharge line and a 7.6 cm (3 in) steel filtered water line and has been Interim Closed Out. Subsite 4 is a 15.24 cm (6 in) vitrified clay storm drain (and smaller laterals) that run between the 1701-H, 1709-H and 1720-H buildings and a ditch (100-H-27) and was determined to require No Action. Subsite 5 consists of a 25.4 cm (10 in) carbon steel pipe located between the Columbia River shoreline and the 184-H Power House and was determined to require No Action. Subsite 6 was a potentially contaminated carbon steel pipe located west of 1713-H and has been Interim Closed Out.

Location: These pipeline segments were part of the 100-HR-1 Operable Unit. As built construction drawings were rectified into Washington State Plane coordinates. Pipelines were then incorporated into the Geographic Information System (GIS) for each of the four piping segments referred to in this site.

Related Sites/ Structures: Associated buildings and waste sites include: 1701-H, 1703-H, 1709-H, 1713-H, 1720-H, 184-H, 100-H-28, 116-H-9, 100-H-53, and 100-H-27.

Process Description: The process descriptions were ascertained from construction drawings and are provided with construction drawing numbers. Miscellaneous pipeline segments are associated within unique building processes. Examples of the miscellaneous pipes include: boiler fuel delivery systems, elevator shafts, air conditioning systems, railcar/truck delivery spots, equipment drains, storage tanks pressure relief systems, compressor blow downs, and chemical transfer pipelines.

Waste Type: Equipment

Waste Description: The waste will include the pipelines and any potential contaminated soil. Contaminants of potential concern have not been fully evaluated for each individual pipeline segment.

This Site has the Following SubSites:

Code: 100-H-51:1

Names: 100-H-51:1; 1703-H Sanitary Sewer Segment

Code: 100-H-51:2

Names: 100-H-51:2; 117-H Seal Pit Crib Feedline

Code: 100-H-51:3

Names: 100-H-51:3; 184-H Brine Discharge Line

Code: 100-H-51:4

Names: 100-H-51:4; 100-H Main Gate Storm Drain

Code: 100-H-51:5

Names: 100-H-51:5; Discovery Pipeline at 128-H-1

Code: 100-H-51:6

Names: 100-H-51:6; Carbon Steel Pipe

Code: 100-H-51:1

Classification: Accepted

Names: 100-H-51:1; 1703-H Sanitary Sewer Segment

Reclassification: Interim Closed Out (3/27/2015)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. It consisted of a 15.2 centimeter (6 inch) diameter vitrified clay pipe (VCP) sanitary sewer segment. The line connected the 1703-H building with the 100-H-28:5, 1607-H2 Sanitary Sewer Pipelines. The subsite also included a short section of a 10.16 cm (4 in) pipe where the 15.2 cm (6 in) VCP connected to the 1703-H building.

Location: The pipeline segment is located on the west side of 1703-H building and runs north, terminating at a manhole where it joins the 100-H-28:5 Sanitary Sewer pipeline.

Related Sites/ Structures: The subsite is associated with the 100-H-28:5 waste site.

Process Description: The 1703-H building was constructed in 1949 and contained offices for area administrative and technical personnel. The pipeline exited the west side of the 1703-H Building, turned north, and terminated at a manhole where it joined the 100-H-28:5 sanitary sewer pipeline. The 1703-H building was demolished in 1974, leaving the footings and foundations after demolition. (UNI-7231974).

Waste Type: Soil

Waste Description: The waste has been described as contaminated soil. The COPCs include: arsenic, barium, cadmium, chromium, hexavalent chromium, lead, selenium, silver, mercury, semivolatile organic compounds (SVOCs), polychlorinated biphenyls (PCBs), and chlorinated pesticides.

Closure Info: Interim (3/27/2015): Confirmatory sampling was done in three test pits. Test pit 1 was excavated at Washington State plane (WSP) coordinates N152560, E577899. The pipeline was uncovered at approximately 0.6 meters (2 ft) below ground surface (bgs). The inside of the pipeline was clear of debris, scale, and sediment; therefore, no sample of pipe content was collected. A soil sample was collected from below the pipeline at approximately 0.9 meters (3 ft) bgs. A sample was also taken of the pipe sealant was collected. Test pit 2 was excavated at WSP coordinates N 152619, E 577899. No pipeline was found at this location. Therefore no samples were collected. The Test Pit 3 location was identified as an alternative to the Test Pit 2 location. Test pit 3 was excavated at WSP coordinates N152625, E577908 and measured 4 square meters (12 sq. ft.) and 2 meters (6 ft) deep. No pipeline was observed, so no sample was collected.

Remedial action at the 100-H-51:1 pipeline subsite was performed on May 7, 2014. The remediation extended to approximately 1.5 meters (5 ft) below ground surface, resulting in approximately 200 bank cubic meters (BCM) (262 bank cubic yards [BCY]) of soil and debris being removed for disposal at the Environmental Restoration Disposal Facility. The debris consisted of the vitrified clay pipe and concrete. Approximately 105 linear meters (345 linear feet) of pipeline was removed. Portions of the 100-H-51:1 pipeline were removed during the 100-H-28:3 and 100-H-28:5 pipeline remediation. An additional 280 BCM (366 BCY) of soil was removed from the excavation on September 24, 2014.

The waste material was staged in a waste staging pile area (SPA) prior to loadout to the Environmental Restoration Disposal Facility. The SPA was used for multiple waste sites and will be addressed in the 100-H-28:2/100-H-42 closure document. No overburden material was staged for use as backfill. No stained soil or anomalous materials were encountered during the remediation.

A post-remediation walkaround boundary survey was conducted following remedial action activities. Segments of the 100-H-51:1 overlap the 100-H-28:3 and 100-H-28:5 pipeline remediation and the removal of those segments are shown in the 100-H-28:3 and 100-H-28:5 post-excavation civil survey. A small section of the 100-H-51:1 pipeline was removed during the installation of the ramp into the 100-H-28:3 and 100-H-28:5 deep excavation. All segments of the 100-H-51:1 pipeline have been removed.

The SubSite is Part Of:**Code:** 100-H-51**Names:** 100-H-51; Potentially Contaminated Pipeline Segments**Code:** 100-H-51:2**Classification:** Accepted**Names:** 100-H-51:2; 117-H Seal Pit Crib Feedline**Reclassification** Interim Closed Out (7/9/2015)**Type:** Process Sewer**Start Date:** 1/1/1960**Status:** Inactive**End Date:**

Description: The subsite was remediated and Interim Closed Out. It consisted of a 10 cm (4 in) diameter cement asbestos feed line that ran from the 117-H Air Filter Building (132-H-2) to the 117-H Seal Pit Crib (116-H-9). A distribution header pipeline was approximately 1.5 meter (5 feet) below grade and was covered by a polyethylene barrier.

The pipeline was identified as part of the 116-H-9 waste site initially and later reassigned to the 100-H-51 waste site on 2/19/2009. This was done to facilitate closure of 116-H-9 while postponing remediation of the pipeline.

Location: The pipeline segment is located between the demolished 117-H Air Filter Building (132-H-2) and the 117-H Seal Pit Crib (116-H-9).

Related Sites/ Structures: The 132-H-2 building was Interim Closed Out in 2006 and the 116-H-9 crib was Interim Closed Out in 2009.

Process Description: The 117-H Seal Pit Crib Feedline transported drainage from the 117-H Building seal pits to the seal pit crib where it was discharged to the soil column.

Waste Type: Not Specified

Waste Description: The waste is remaining pipelines and any potentially contaminated soil. COPCs include: carbon-14, cesium-137, cobalt-60, europium-152, europium-154, europium-155, plutonium-238, plutonium-239/240, strontium-90, tritium, radium-226, thorium-228, thorium-232, uranium-238, cadmium, chromium (total), hexavalent chromium, mercury, lead, selenium, silver, and PCBs.

Closure Info: Interim (7/9/2015): Remedial action at the 100-H-51:2 subsite was conducted on September 23 and 24, 2014. The remediation extended to an approximate maximum depth of 2 meters (6.6 ft) below ground surface, resulting in approximately 322 bank cubic meters (421 bank cubic yards) of contaminated soil and debris (cement asbestos pipe) being loaded out and disposed at the Environmental Restoration Disposal Facility (ERDF). The soil and debris were direct loaded for disposal at ERDF. Therefore, no waste staging pile areas were generated. No overburden material was salvaged for use as clean backfill and no anomalies were encountered during remediation. No in-process soil samples were collected. Following remediation, global positional environmental radiological surveyor (GPERS) surveys were conducted over the pipeline excavation.

The SubSite is Part Of:**Code:** 100-H-51**Names:** 100-H-51; Potentially Contaminated Pipeline Segments**Code:** 100-H-51:3**Classification:** Accepted**Names:** 100-H-51:3; 184-H Brine Discharge Line**Reclassification** Interim Closed Out (3/27/2015)

Type: Process Sewer**Start Date:****Status:** Inactive**End Date:**

Description: The subsite has been remediated and Interim Closed Out. It consisted of two parallel pipelines, a 5.1 cm (2 in) steel brine discharge line and a 7.6 cm (3 in) steel filtered water line that ran from the 184-H Power House Building to the 184-H Salt Dissolving Pit and Brine Pump House. The Power House was demolished in 1997. The 184-H Salt Dissolving Pit and Brine Pump House (100-H-16) were probably demolished in place as were similar brine pits at 184-B and 184-D.

Location: The pipelines were located between the 184-H Power House Building and the 184-H Salt Dissolving Pit and Brine Pump House.

Process Description: Filtered water was piped from the 184-H Power House to the 184-H Salt Dissolving Pit and Brine Pump House where sodium chloride was added and crated brine. The brine was pumped back to the 184-H Power House where it was used to regenerate the zeolite ion exchange beds in the water softener tanks.

Waste Type: Not Specified

Waste Description: The waste is the remaining pipelines and any potentially contaminated soil.

Closure Info: Interim (3/27/2015): Confirmatory sampling of the 100-H-51:3 subsite was performed on October 4 and 5, 2010. Confirmatory sampling of the 100-H-51:6 subsite was on November 15, 2010.

Originally, the 100-H-51:6 pipeline was included as part of the 100-H-51:5 pipeline subsite. However, following the confirmatory sampling event, it was determined the southern segment of 100-H-51:5 was a separate pipeline. Therefore, the 100-H-51:5 pipeline subsite was divided into two subsites. The southern segment became the 100-H-51:6 Carbon Steel Pipe subsite.

Remedial action at the 100-H-51:3 pipeline subsite was performed on March 18, 2014. The remediation extended to approximately 1.5 meters (5 ft) below ground surface resulting in approximately 520 bank cubic meters (680 bank cubic yards) of soil and debris being removed for disposal at the Environmental Restoration Disposal Facility (ERDF). The debris consisted of the 5.1 cm and 7.6 cm (2 in. and 3 in.) diameter steel pipelines, concrete, and near surface demolition debris. Coal ash was also present in the pipeline area. No overburden soil was stockpiled for use as backfill. The waste material, including the coal ash, was staged in a waste staging pile area (SPA) and later disposed at ERDF. The waste SPA was used for multiple waste sites and the SPA footprint will be addressed in the 100-H-28:2/100-H-42 verification work instruction and closure document. No stained soil or anomalous materials were encountered during the remediation. Asphaltic material was observed in and around the pipeline excavation.

Due to the above ground pump-and-treat pipelines crossing over the top of a portion of the northern segment of the 100-H-51:6 subsite, remediation of the 100-H-51:6 pipeline in this area was conducted by pulling the pipe through and out of the trench. The soils from above and below the pipeline were not removed.

Remedial action at the 100-H-51:6 pipeline subsite was performed on March 12 and 13, 2014. The depth of the remediation ranged from approximately 0.3 to 0.9 meters (1 to 3 ft) below ground surface, resulting in approximately 450 bank cubic meters (588 bank cubic yards) of soil and debris being removed for disposal at ERDF. The debris consisted primarily of a 25.4 cm (10 in.) diameter steel pipeline. Coal ash was also present on the surface. No overburden soil was stockpiled for use as backfill. The waste material including the coal ash was staged in a

SPA and was disposed at ERDF. The SPA was used for multiple waste sites and the SPA footprint will be addressed in the 100-H-43 verification work instruction and closure document. No stained soil or anomalous materials were encountered during the remediation. Asphaltic material was observed in and around the pipeline excavation.

The SubSite is Part Of:

Code: 100-H-51

Names: 100-H-51; Potentially Contaminated Pipeline Segments

Code: 100-H-51:4

Classification: Accepted

Names: 100-H-51:4; 100-H Main Gate Storm Drain

Reclassification: Interim No Action (5/26/2011)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The subsite has been evaluated and determined to require No Action. It consists of a 15.2 cm (6 in) diameter vitrified clay pipeline (VCP) storm drain that ran north from the 1701-H, 1702-H and 1709-H Buildings to 100-H-27, 100-H Area Patrol Headquarters Storm Runoff Ditch. The pipeline includes two 10.2 cm (4 in) lateral sections of VCP feed pipe from 1702-H and 1709-H buildings to the 15.2 cm (6 in) pipeline.

Location: The subsite was located between the 1701-H Building and the 100-H-27 storm runoff ditch. The pipeline ran parallel and approximately 11 meters (36 ft) north of the former location of the 1607-H3 septic system.

Related Sites/ Structures: 100-H-51:4 is associated with the 100-H-27 storm water ditch.

Waste Type: Not Specified

Waste Description: The waste will include the pipelines and any potential contaminated soil.

Closure Info: Interim: 100-H-51:4 was located adjacent to the 1607-H3 post-excavation boundary. Confirmatory samples for 100-H-51:4 were collected from the inside of the pipe at Test Pit 5. The pipeline was found 3 feet below ground surface. It was encased in concrete. Test Pit 5 was the only location not impacted by the 1607-H3 excavation. Field surveys found no radiological contamination or volatile organic compounds.

A reclassification to No Action for the 100-H-51:4 subsite is supported based on site history, process knowledge, field observations, and comparison of residual contaminant concentrations against RAGs.

The SubSite is Part Of:

Code: 100-H-51

Names: 100-H-51; Potentially Contaminated Pipeline Segments

Code: 100-H-51:5

Classification: Accepted

Names: 100-H-51:5; Discovery Pipeline at 128-H-1

Reclassification: Interim No Action (4/26/2012)

Type: Product Piping

Start Date:

Status: Inactive

End Date:

Description: The confirmatory sampling results support a reclassification to No Action. The pipeline is a

steel pipe that ran from the Columbia River to the sanitary water system just south of the 1713-H building.

Location: The pipeline is located at the Columbia River shoreline and continues south ending 50 meters (164 ft) beyond the 128-H-1 Burn Pit.

Process Description: There is no process history associated with this subsite.

Waste Type: Not Specified

Waste Description: The waste will include the pipelines and any potential contaminated soil.

Closure Info: Interim: The intent of sampling was to determine the size, type, and use of the 100-H-51:5 and 100-H-53 pipelines and to determine the nature and estimate the extent of potential contamination in and under the 100-H-51:5 and 100-H-53 pipelines. Soil was collected from beneath the 100-H-51:5 and 100-H-53 pipelines to determine if a leak associated with the pipelines may have resulted in contamination that would pose a risk to human health and the environment. Confirmatory sampling of the 100-H-51:5/100-H-53 waste sites occurred on November 2010. The exposed portion of the 100-H-53 pipeline was breached with a drill. No material was found inside the pipeline to sample. According to the logbook, the pipe at this location was 3/8-inches thick and had a 10 inch diameter. The soil sample taken from below the pipe was composed of brown silt. A duplicate sample was taken from this location. At the 100-H-51:5 subsite, there was no material to sample inside the exposed end of the pipe. A sample of the brown-tan silt was taken from below the pipe.

The SubSite is Part Of:

Code: 100-H-51

Names: 100-H-51; Potentially Contaminated Pipeline Segments

Code: 100-H-51:6

Classification: Accepted

Names: 100-H-51:6; Carbon Steel Pipe

Reclassification: Interim Closed Out (3/27/2015)

Type: Product Piping

Start Date:

Status: Inactive

End Date:

Description: The 100-H-51:6 subsite has been remediated and Interim Closed Out. It was a section of 25 cm (10 in) pipe that originated approximately 70 meters (231-ft) south of the 100-H-51:5 waste site and terminated near the 1713-H Building. This section of carbon steel pipe connected to the southern side of a temporary wooden water tank and ended near the 1713-H Building. The pipeline and water tank were believed to be part of an extensive temporary water system for construction of the 100-H Area in 1948 (HW-24800-2). This section of pipe (100-H-51:6) had been considered part of the 100-H-51:5 and 100-H-53 waste sites until confirmatory sample results exceeded direct exposure cleanup levels. The section of pipe was designated as a removed, treated, and disposed (RTD) site.

Location: The pipeline was located west of the 1713-H building.

Related Sites/Structures: The piping is associated with 100-H-51:5 and 100-H-53.

Waste Type: Not Specified

Waste Description: The waste will include the pipelines and any potential contaminated soil.

Closure Info: Interim (3/27/2015): Confirmatory sampling of the 100-H-51:3 subsite was performed on October 4 and 5, 2010. Confirmatory sampling of the 100-H-51:6 subsite was on November 15, 2010.

Originally, the 100-H-51:6 pipeline was included as part of the 100-H-51:5 pipeline subsite. However, following the confirmatory sampling event, it was determined the southern segment of 100-H-51:5 was a separate pipeline. Therefore, the 100-H-51:5 pipeline subsite was divided into two subsites. The southern segment became the 100-H-51:6 Carbon Steel Pipe subsite.

Remedial action at the 100-H-51:3 pipeline subsite was performed on March 18, 2014. The remediation extended to approximately 1.5 meters (5 ft) below ground surface resulting in approximately 520 bank cubic meters (680 bank cubic yards) of soil and debris being removed for disposal at the Environmental Restoration Disposal Facility (ERDF). The debris consisted of the 5.1 cm and 7.6 cm (2 in. and 3 in.) diameter steel pipelines, concrete, and near surface demolition debris. Coal ash was also present in the pipeline area. No overburden soil was stockpiled for use as backfill. The waste material, including the coal ash, was staged in a waste staging pile area (SPA) and later disposed at ERDF. The waste SPA was used for multiple waste sites and the SPA footprint will be addressed in the 100-H-28:2/100-H-42 verification work instruction and closure document. No stained soil or anomalous materials were encountered during the remediation. Asphaltic material was observed in and around the pipeline excavation.

Due to the above ground pump-and-treat pipelines crossing over the top of a portion of the northern segment of the 100-H-51:6 subsite, remediation of the 100-H-51:6 pipeline in this area was conducted by pulling the pipe through and out of the trench. The soils from above and below the pipeline were not removed.

Remedial action at the 100-H-51:6 pipeline subsite was performed on March 12 and 13, 2014. The depth of the remediation ranged from approximately 0.3 to 0.9 meters (1 to 3 ft) below ground surface, resulting in approximately 450 bank cubic meters (588 bank cubic yards) of soil and debris being removed for disposal at ERDF. The debris consisted primarily of a 25.4 cm (10 in.) diameter steel pipeline. Coal ash was also present on the surface. No overburden soil was stockpiled for use as backfill. The waste material including the coal ash was staged in a SPA and was disposed at ERDF. The SPA was used for multiple waste sites and the SPA footprint will be addressed in the 100-H-43 verification work instruction and closure document. No stained soil or anomalous materials were encountered during the remediation. Asphaltic material was observed in and around the pipeline excavation.

The SubSite is Part Of:

Code: 100-H-51
Names: 100-H-51; Potentially Contaminated Pipeline Segments

Code: 100-H-52	Classification: Accepted
Names: 100-H-52; 184-HA Septic Drain Field and Associated Piping	Reclassification: Interim Closed Out (4/2/2014)
Type: Drain/Tile Field	Start Date: 1/1/1965
Status: Inactive	End Date: 1/1/1974

Description: The site has been remediated and Interim Closed Out with 100-H-48. It consisted of a drain field and associated piping that supported the 184-HA boiler annex. In the center of the drain field (oriented east/west) were four, 20 centimeter (8 inch) diameter perforated concrete pipe laterals.

Location: The drain field was located on the west side of the 184-HA Building. It was approx. 20.8 meters (68.6 feet) east of the 190-HA building. Global Positioning System (GPS) coordinates for the drain field are E577820 N152595. These are the coordinates of where the 5.1 centimeter (2 inch) sanitary drain (SD) effluent pipe line connects into the east side of the drain field.

Related Sites/ Structures: The septic system is associated with the 184-HA building and 100-H-48.

Process Description: The 184-HA Boiler House Building and associated equipment was constructed in approximately 1965 to replace the 184-H boiler house. The 184-HA building was removed and it's associated footings and foundations were demolished and backfilled in 1974. The site was leveled. The boiler provided steam to the administration and Central Shops buildings, which consisted of 1703H, 1704H, 1716H, 1717H, 1719H, 1722H, 1760H, and 1761H. Blow-down effluent from the boiler, drained via the 10.2 centimeter (4 inch) condensate line, that connected to the east end of the drain field, to the 20 centimeter (8 inch) perforated concrete main line.

Waste Type: Water

Waste Description: The drain field received effluent from two water softeners, the boiler deaerator and condensate from the boiler.

Closure Info: Interim (4/2/2014): Geophysical surveys were done in 2007. Confirmatory sampling was done from within Test Trenches in November 2009.

Remediation of the combined 100-H-48 and 100-H-52 waste sites was performed from July 25, 2013 through July 29, 2013 to a depth of approximately 4.6 meters (15 ft). A combined volume of approximately 1,576 bank cubic meters (BCM) (2,061 bank cubic yards [BCY]) of contaminated soil and debris was excavated and stockpiled for disposal at the Environmental Restoration Disposal Facility (ERDF). Debris waste included piping associated with the former underground fuel tanks and piping associated with the 100-H-52 drain field. Other concrete and steel debris was encountered at the former underground tank location. During remediation, field screening for VOCs was conducted and no elevated readings were detected. All waste material was stockpiled, prior to shipment and disposal at ERDF. All waste material from the 100-H-48 and 100-H-52 waste sites have yet to be loaded out to ERDF. The waste staging pile area will be sampled and closed out with a separate waste site at a later date.

Code: 100-H-53	Classification: Accepted
Names: 100-H-53; Carbon Steel Pipe in River Bank	Reclassification: Interim No Action (4/12/2012)
Type: Process Sewer	Start Date:
Status: Inactive	End Date:

Description: The confirmatory sampling results support a reclassification of this site to No Action. The waste site is a 25 centimeter (10 in) diameter and 1.8 meters (6 ft) long (exposed portion) carbon steel pipe that runs northeast toward the river shore. A WCH Orphan Sites Field Evaluation was conducted in this area in August of 2007. Geophysics (GI # 0590309) was conducted in October 2007. The results indicated that the visible segment of the 25 centimeter (10 in) diameter pipe is not part of an intact system and does not extend below grade beyond the 1.8 meters (6 ft) currently visible.

Location: This waste site is located approximately 28 meters north-northeast of the southeast end of rejected WIDS site 600-258 (Pre-Hanford debris) and it is located near the shoreline.

Related Sites/ Structures: Pipe is northeast of the 600-151, Dumping Areas 50 yards and 200 yards downstream of River Mile 14. It is co-located near 600-258.

Process Description:	The process associated with this pipe is unknown. The pipeline may have been related to pre-Hanford activities, since there is this type of debris associated with 600-258. Site 600-258 is located on top of the bank and the pipe is located towards the south end of 600-258. See site 600-258.
Waste Type:	Equipment
Waste Description:	The waste is the pipeline and any potentially contaminated soil underlying the pipe. Since the pipeline can not be related to any particular human activity, the contaminants of potential concern are unknown.
Closure Info:	Interim: The intent of sampling was to determine the size, type, and use of the 100-H-51:5 and 100-H-53 pipelines and to determine the nature and estimate the extent of potential contamination in and under the 100-H-51:5 and 100-H-53 pipelines. Soil was collected from beneath the 100-H-51:5 and 100-H-53 pipelines to determine if a leak associated with the pipelines may have resulted in contamination that would pose a risk to human health and the environment. Confirmatory sampling of the 100-H-51:5/100-H-53 waste sites occurred on November 2010. The exposed portion of the 100-H-53 pipeline was breached with a drill. No material was found inside the pipeline to sample. According to the logbook, the pipe at this location was 3/8-inches thick and had a 10 inch diameter. The soil sample taken from below the pipe was composed of brown silt. A duplicate sample was taken from this location. At the 100-H-51:5 subsite, there was no material to sample inside the exposed end of the pipe. A sample of the brown-tan silt was taken from below the pipe.

Code:	100-H-57	Classification:	Accepted
Names:	100-H-57; Water Tower Foundations at 100H	Reclassification	Interim No Action (10/21/2013)
Type:	Foundation	Start Date:	
Status:	Inactive	End Date:	

Description: The waste site has been evaluated and determined to require No Action. The site consists of the underground piping, valves, sumps and other structures at the base of the two elevated water towers adjacent to the 105-H Reactor. The valve pits at both of the 105-H water towers were completely removed during the demolition and decontamination activities.

Location: The towers were located on either side of the 105-H Reactor.

Process Description: Water was provided as a means to remove heat from the pile. A network of interconnecting pipelines, by-pass lines, and standby pumping facilities were provided to insure that water service to the pile was maintained even when a part of the system was inoperable (TNX-PG-4). The principal purpose of the two elevated storage tanks at the 105-H Reactor was to provide standby storage of cooling water in the event that the service to the pile was interrupted. The 105-H Reactor had two 300,000 gallon capacity, ellipsoidal steel-plate tanks (187-H1 and 187-H2), elevated 120 feet above the ground level (HW-24800-2). Sodium silicate was supplied to the tanks for corrosion prevention (H-1-13254).

The construction drawings for the 187-H1 and 187-H2 tanks (P-1257 and P-2031) show a french drain receiving condensate through a 3.8 centimeter (1.5 in) pipeline. The drawings also suggest that the sump in the bottom of the valve pit was emptied into this french drain. The drawings show that the french drains were installed a minimum of 4.6 meters (15 ft) on the north side of the tanks. Multiple pipelines were located on the north side of the reactor that ran in an east-west direction just north of each water tower. The pipelines would have interfered with placement of any french drains 4.6 meters (15 ft) north of the towers footer piers. It is likely that the french drains were located elsewhere. The only identified french drain within a 4.6 meters (15 ft) perimeter of the east water tower (187-H2) footings is the 100-H-8 French

Drain B waste site. Based on historical information, this french drain was determined to have received steam condensate from overhead steam lines, but it is possible that it could be associated with the valve pit for the east tower. Confirmatory sampling of the 100-H-8 french drain was performed in November 2008, with soil samples collected from beneath the french drain. Hexavalent chromium was undetected in all samples. Confirmatory sampling results showed the 100-H-8 site achieved remedial action objectives specified in the Remaining Sites ROD (EPA 1999). The site was reclassified to No Action in December 2009. There are no french drains identified in the area near the former 187-H1 west water tower.

Closure Info: Interim (10/21/2013): A field walkdown at the 100-H-57 waste site was performed on November 6, 2012. Two Test Pits were excavated at the locations of each of the foundations on June 21, 2013. The test pits were excavated to a depth of 4 meters (13 ft). Two samples were collected from each test pit. The samples were taken from the backhoe bucket. No anomalies were identified. No radiological activity was detected. The confirmatory sampling results support a reclassification of the 100-H-57 waste site to Interim No Action.

Code: 116-H-1	Classification: Accepted
Names: 116-H-1; 107-H Liquid Waste Disposal Trench	Reclassification: Interim Closed Out (4/3/2001)
Type: Trench	Start Date: 1/1/1952
Status: Inactive	End Date: 1/1/1965

Description: The site has been remediated and closed out. The disposal trench was oriented in a north-south direction and was divided into three separate lobes. The trench was fed by a single 51-centimeter (20-inch) pipeline that originated in the pumphouse located at the northwest corner of the 107-H Retention Basin. The pipeline is part of 100-H-21.

Location: The site was located south of the 107-H Retention Basin (site code 116-H-7).

Related Sites/Structures: The disposal trench is associated with the 105-H Reactor, 116-H-7 Retention Basin and the 100-H-21 pipeline site.

Process Description: The trench operated from 1952 until 1958, receiving mixed waste effluent from the 116-H-7 Retention Basin during reactor shutdowns caused by fuel element ruptures. The process effluent coolant received by this trench reportedly contained debris from fuel element ruptures. Additionally, the trench received water and sludge removed from the 116-H-7 Retention Basin in April and May 1965, during basin deactivation. The primary lobe was supplied by a DN500 50 centimeter (20-inch) steel pipe that entered near its bottom. The pipe originated at the 1607-H Pump House, near the northwest corner of the 116-H-7 Retention Basin.

Waste Type: Water

Waste Description: The site received diversion effluent from the 107-H Retention Basin during reactor outages due to fuel element ruptures and water and sludge from 107-H during deactivation of the unit.

Closure Info: Interim (4/3/2001): Remedial action at the 116-H-1 site began on June 29, 1999. Excavation of the site involved removing the overburden materials and underlying contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Contaminated materials were disposed of at ERDF. On June 8, 2000, the excavation was completed. The elevation of the bottom of the excavation was at 123.4 meters (405 feet) upon completion. The excavation was approximately 12,735 square meters (137,077 square feet) in area with a maximum depth of approximately 4.6 meters (15 feet). Approximately 82,706 metric tons (91,168 tons) of material from the site were disposed of at ERDF.

Cleanup verification sampling for the deep and shallow zones was done on June 15, 2000, and

July 25, 2000, respectively. The final verification samples were submitted to offsite laboratories for analysis using approved U.S. Environmental Protection Agency analytical methods, as required per the SAP (DOE/RL-96-22).

Code: 116-H-2	Classification: Accepted
Names: 116-H-2; 1608-H Crib & Trench; 1608-H Liquid Waste Disposal Trench	Reclassification: Interim Closed Out (3/1/2001)
Type: Trench	Start Date: 1/1/1953
Status: Inactive	End Date: 1/1/1965

Description: The site has been remediated and Interim Closed Out. It included a trench that was fed by a 15 centimeter (6-inch) vitrified clay pipe that originated at the 1608-H Pump House.

Location: The site was located 76 meters (250 feet) south of the 105-H Reactor Building.

Related Sites/Structures: The trench is associated with the 105-H Reactor Building and 1608-H Pump House. In 1953, the 116-H-2 trench overflowed and flooded a triangular area bounded by railroad tracks, known as the 100-H-17 Overflow. The 100-H-30 Sanitary Sewer trench was also contaminated with effluent that overflowed from 116-H-2.

Process Description: From 1953 to 1965, the site received effluent from the 105-H Ball 3X project. Water was pumped from the 105-H Reactor Building to the trench via the 1608 Pump House.

Waste Type: Water

Waste Description: The site received coolant water from the 105-H Reactor Building during the Ball 3X system upgrade program. The site was used during other upgrade programs and when maintenance was necessary on the effluent system.

Closure Info: Interim: This area is located in an area that, prior to World War II and formation of the Hanford Site, was occupied by fruit tree orchards.

Remedial action at the 100-H-17 sites group (100-H-17, 100-H-30, 100-H-2 and 116-H-2) began on February 2, 2000. The sites were grouped together for remediation because of location and similar contaminants. Excavation of the area involved removing the overburden materials, miscellaneous debris, the contaminated structure, and underlying contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Contaminated materials were disposed of at ERDF. On February 10, 2000, the excavation was completed.

No evidence of buried waste was found during the excavation of the 100-H-2 site.

At the completion of the remedial action, the total excavation was approximately 6,240 square meters (67,170 square feet) in area with a maximum depth of approximately 2.6 meters (8.5 feet). Approximately 19,920 metric tons (21,960 tons) of material from the site were disposed of at the ERDF.

Code: 116-H-3	Classification: Accepted
Names: 116-H-3; Perf Decontamination Drain; 105-H Dummy Decontamination French Drain	Reclassification: Interim Closed Out (4/3/2001)
Type: French Drain	Start Date: 1/1/1950
Status: Inactive	End Date: 1/1/1965

Description: This site has been remediated and closed out. The site was a french drain made of vitreous tile conduit. The upper surface of the french drain extended a few inches above the ground and had a metal cover. This waste site included 65 meters (215 feet) of pipeline.

Location: The site was located southeast of the 105-H Building.

**Related Sites/
Structures:** The site was related to the 105-H Reactor Building.

**Process
Description:** The 116-H-3 French Drain received spent nitric acid and rinse water from the decontamination of fuel element spacers, reactor process tube caps, and other reactor hardware between 1950 and 1965.

Waste Type: Process Effluent

**Waste
Description:** The site received spent acid and rinse water from the 105-H Dummy Decontamination Facility, which decontaminated fuel element spacers and other reactor hardware.

Closure Info: Interim: Remedial action at the 116-H-3 site began on February 17, 2000. Excavation of the site involved removing the overburden materials, the french drain, 65 meters of pipeline leading from the reactor building to the french drain, and the underlying contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Contaminated materials were disposed of at ERDF.

On June 26, 2000, the excavation was completed. The elevation of the bottom of the excavation was at 123.5 meters (405 feet) upon completion. The excavation was approximately 855 square meters (9,203 square feet) in area with a maximum depth of approximately 4.6 meters (15 feet). Approximately 2,707 metric tons (2,985 tons) of material from the site were disposed of at the Environmental Restoration Disposal Facility (ERDF).

Code: 116-H-4	Classification: Accepted
Names: 116-H-4; 105-H Pluto Crib	Reclassification: None
Type: Crib	Start Date: 1/1/1950
Status: Inactive	End Date: 1/1/1952

Description: The site is currently a flat, cobble covered field located inside the 105-H security fence. The crib location is not marked.

Location: The crib was located near the southwest corner of the 105-H Building and adjacent to the 132-H-3 Effluent Pumping Station.

**Related Sites/
Structures:** The site was related to the 105-H Reactor.

Waste Type: Process Effluent

**Waste
Description:** The site received effluent from tubes containing ruptured fuel elements. A 1953 document reports that approximately 270 curies of fission products were released to the crib as a result of the rupturing of ten slugs and the presence of 1,000 kilograms (2,200 pounds) of sodium dichromate.

Code: 116-H-5	Classification: Accepted
Names: 116-H-5; 116-H-5 Outfall Structure; 1904-H Outfall Structure	Reclassification: Interim Closed Out (5/3/2012)

Type: Outfall **Start Date:** 1/1/1949

Status: Inactive **End Date:** 1/1/1965

Description: This site has been remediated and Interim Closed Out. It included the open-topped, compartmentalized, reinforced concrete outfall structure. A 183 centimeter (72 inch) concrete process sewer line from the 1906-H Pump House, and two 152 centimeter (60 inch) diameter steel retention basin pipelines entered the eastern face. Two, 152 centimeter (60 inch) concrete pipelines exited the western face and extended to the river.

Location: The site was located on the Columbia River shoreline north of 107-H Retention Basin.

Related Sites/ Structures: The outfall is associated with 116-H-7 Retention Basin, 184-H Power House, 100-H-34 (River Effluent Pipelines), the 100-H-36 spillway, the 100-H-21 process effluent lines, the 100-H-34 river effluent pipelines, and the 1906-H Pump House and associated pipelines.

Process Description: The outfall was a reinforced concrete weir box that directed the water through either the river discharge pipelines (100-H-34) or through the spillway (flume) (100-H-36). The spillway was a concrete flume used when the river pipelines were blocked, damaged or undergoing maintenance. Process sewer wastes, and reactor cooling water collected and temporarily stored in the 107-H retention basin, were pumped to the river via the 116-H-5 outfall structure and associated 100-H-34 river effluent pipelines.

Waste Type: Construction Debris

Waste Description: The site received effluent water through two lines from the 107-H Retention Basin. A third line from the 100 H Area process sewer also discharged to it. Contaminants of potential concern include Co-60, Cs-137, Eu-152, -154, -155, Ni-63, Pu-238, Pu-239/240, Am-241, C-14, H-3, Tc-99, Sr-90, U-234, U-235, U-238, Cr+6, Cr (total), Pb, and Hg.

Closure Info: Interim (5/3/2012): Remedial action at the 116-H-5 waste site began on November 17, 2008, and continued through April 9, 2009, to a depth of approximately 7 meters (23 ft) on the eastern side of the excavation and 13 meters (43 ft) on the western side of the excavation. The excavation resulted in approximately 2,510 bank cubic meters (BCM) (3,283 bank cubic yards [BCY]) of contaminated soil and debris being removed for disposal at the Environmental Restoration Disposal Facility (ERDF). Approximately 15,696 BCM (20,529 BCY) of overburden material was stockpiled southwest of the excavation for use as clean backfill. Columnar basalt riprap boulders, cemented together and used as a retaining wall, were also excavated from the site and will be used as backfill. Most of the soil was direct loaded from the excavation. However, small staging pile areas were used for pipe, concrete, and fence material, which were later loaded out and disposed at the ERDF.

Several pipelines that discharged to or from the 116-H-5, 1904-H Outfall Structure remain at the site. A 183-cm (72-in.) reinforced concrete pipe (part of the 100-H-42, 1906-H Drainage Lift Station waste site that transferred effluent from the 1906-H Building to the 116-H-5 outfall) remains near the base of the western sidewall of the 116-H-5 excavation. The 100-H-36 spillway and the 100-H-34, 100-H River Effluent Pipelines that discharged effluent from the outfall structure to the river also remain.

Code: 116-H-7 **Classification:** Accepted

Names: 116-H-7; 107-H; 107-H Retention Basin **Reclassification:** Interim Closed Out (7/24/2001)

Type: Retention Basin **Start Date:** 1/1/1949

Status: Inactive **End Date:** 1/1/1965

Description: This site has been remediated and closed out. The basin was a concrete-lined rectangular

structure. Prior to the remedial action, the basin had been partially demolished and backfilled to a depth of approximately 1.2 meters (4 feet) above the floor, and sloped to the top of the walls.

Location: The site is located northeast of 105-H.

Release Description: The unit and its effluent line developed leaks during the years of operation. The rate of leakage has been estimated to be as high as 19,000 to 38,000 liters-per-minute (5,000 to 10,000 gallons-per-minute). The extent of contamination from these releases was within the area encompassed by the unit.

Related Sites/ Structures: Sludge and waste removed from this unit during repair work in the spring of 1953 were buried in a trench east of the unit (WIDS Site Code 100-H-5). The trench was originally covered to grade with 1.5 meters (5 feet) of soil. In May 1965, the location was excavated to a depth of approximately 1.8 meters (6 feet) to obtain fill material for this unit. There was no indication of remaining radioactivity, and consequently the trench was released from radiological controls.

Waste Type: Process Effluent

Waste Description: This site received cooling water effluent from the 105-H Reactor for radioactive decay and thermal cooling prior to release to the Columbia River. Seventy percent of the total radionuclide inventory is contained within the soil adjacent to the unit. Approximately 10 curies have leached into the concrete floor and walls.

Closure Info: Interim (7/24/2001): Remedial action at the 116-H-7 site began on March 17, 1999. Excavation of the site involved removing the overburden materials, the contaminated structure, and underlying contaminated soil. Due to leakage from the retention basin and its associated pipelines, numerous plumes were excavated along with the waste site. Based on field screening, overburden materials identified as potentially deen were placed in stockpiles for potential use as backfill. Contaminated materials were disposed of at ERDF. On July 17, 2000, the excavation of the waste site and associated plumes was completed.

Site excavation and waste disposal are complete, and the exposed surfaces have been sampled and analyzed to verify attainment of the RAGs. At the completion of the remedial action, the total excavation was approximately 23,660 square meters (254,700 square feet) in area with a depth of approximately 4.8 meters (15.7 feet). Approximately 218,130 metric tons (240,440 tons) of material from the site were disposed of at the ERDF.

Code: 116-H-9	Classification: Accepted
Names: 116-H-9; 117-H Crib; 117-H Seal Pit Crib	Reclassification: Interim Closed Out (12/22/2010)
Type: Crib	Start Date: 1/1/1960
Status: Inactive	End Date: 1/1/1965

Description: The site has been remediated and Interim Closed Out. It was a gravel filled crib. A distribution header was approximately 1.5 meters (5 feet) below grade and covered by a polyethylene barrier. The polyethylene barrier was covered by 1.2 meters (4 feet) of clean fill material. A large vent pipe marked the site and was placed off center of the crib structure. The site included a 10-centimeter (4-inch) cement asbestos feed pipeline that runs from the demolished 117-H Air Filter Building to the crib. The pipeline was approximately 80 meters (263 feet) long. Based on the results of the applicable Remaining Sites Verification Package (RSVP) document, authorization was given to remove the Soil Contamination Area and Underground Radioactive Material Area postings from this waste site.

Location: The site was located approximately 150 meters (492 ft) southwest of the 105-H Building (118-H-6).

Related Sites/ Structures: The site was associated with the demolished 117-H Air Filter Building.

Process Description: During its period of operation from 1960 to 1965, the 116-H-9 Crib is reported to have received approximately 300,000 liters (79,200 gal) of low-level radioactive effluent that drained from the 117-H Filter Building confinement system seal pits.

Waste Type: Water

Waste Description: The site received drainage from confinement system 117-H Building Seal Pits.

Closure Info: Interim (12/22/2010): Remedial action began on October 28, 2008, and continued through February 3, 2009, to a depth of approximately 4.6 meters (15 ft). Material was direct loaded for disposal, so no staging piles were created. The lateral extent of the excavation was determined based on the September 2008 geophysical survey that clearly defined a distinct boundary. No stained soil or radiological or chemical contamination was identified. Approximately 2,430 bank cubic meters (3,180 bank cubic yards) of soil and debris was removed for disposal at the Environmental Restoration Disposal Facility (ERDF).

Verification sampling was performed in July 2009, to collect data to determine if the site met remedial action goals. The results of the verification sampling showed that residual contaminant concentrations do not preclude any future uses (as bounded by the rural-residential scenario) and allow for unrestricted use of shallow zone soils (i.e., surface to 4.6 meters [15 ft] deep). The results also demonstrate that residual contaminant concentrations are protective of groundwater and the Columbia River.

Code: 126-H-2

Classification: Accepted

Names: 126-H-2; 183-H Clearwells/Disposal Pit

Reclassification: Interim Closed Out (10/18/2012)

Type: Dumping Area

Start Date: 1/1/1975

Status: Inactive

End Date:

Description: The waste site has been remediated and Interim Closed Out. The clearwells were part of the 183-H Water Treatment Facility and consisted of two reinforced concrete basins (east and west), separated by a pump house. During reactor operations, the clearwells held clean, uncontaminated water. The east clearwell basin was later used for disposal of demolition debris, inert waste, and drums that were found to contain oil. The west clearwell basin was not used for waste disposal. A portion of the backfilled clearwells had been posted with Soil Contamination signs.

Location: The site is located approximately 220 meters (721.8 feet) north of the 105-H Reactor Building and just south of the demolished 183-H Solar Evaporation Basins.

Related Sites/ Structures: The clearwells were associated with the 183-H Water Treatment Facility. A number of the drawings that are referenced are related to the 183-H Water Treatment Facility and have been included to provide context information.

Process Description: The 183-H clearwells were part of the 183-H water treatment facility. They consisted of two reinforced concrete basins (east and west) measuring 229 meters (750 ft) long and 41 meters (135 ft) wide with a 38-million-L (10-million-gal) capacity. The treatment facility began operation in 1949 to store Columbia River water being processed for reactor coolant. During reactor operations, the clearwells held clean, uncontaminated water. The east and west clearwells were separated by a pump room that had been previously demolished. The below-grade portion had been filled with pump room rubble, fly ash, and backfill material.

After the 105-H Reactor shut down, in 1965, part of the roof on the east clearwell was demolished to allow inert demolition waste to be placed into the clearwell cavity. Historical information indicates the east clearwell was used for disposal of nonhazardous, nonradioactive debris such as concrete, wood, pipe, insulation, transite, composition roof materials, rebar, and asphalt from 1974 through 1997. Uncertainty regarding the radiological decontamination of rubble disposed in the clearwell from the 183-H Solar Evaporation Basins resulted in a portion of the east clearwell being posted as a radiological Soil Contamination Area and a Radiological Controlled Area. The west clearwell had not been used for waste disposal and remained intact until decommissioning in 2010.

Rubblized material remaining from the demolition of the 183-H Solar Evaporation Basins (116-H-6) was added to the clearwell, in the belief that all requirements for radiological release had been met. The concrete was scabbled to remove the outer layer of surface contamination (approximately 6 millimeters [0.25 inches]). This material was disposed of as radioactive material. The remainder of the concrete and debris was sent to the clearwell on October 23, 1995.

The site consisted of two below grade, reinforced concrete basins, having a capacity of approximately 3.8E+07 liters (1E+07 gallons). Each clearwell had a reinforced concrete roof, supported by 132 concrete columns. The roof was located at grade level and still remains over the west clearwell. The clearwells were separated in the center by a pump room. The pump room was reinforced concrete and largely below grade. The above ground portion of the pump room has been demolished, and the below ground portion has been filled with pump room rubble and backfill material. The east clearwell basin contains demolition debris and other nonradioactive nonhazardous solid waste. The west clearwell remains intact.

Waste Type: Demolition and Inert Waste

Waste Description: The suspected contaminated waste is concrete and debris from the demolition of the 183-H Solar Evaporation Basins (116-H-6). The area is posted as a soil contamination area. After removal of the surface of the concrete, prior to demolition, all surfaces were surveyed with field instrumentation. The survey results for all surfaces were less than 1,000 disintegrations per minute per 100 square centimeters (15.5 square inches) smearable (loose) contamination and less than 5,000 disintegrations per minute per 100 square centimeters (15.5 square inches) total contamination. On October 23, 1995, 2,666.5 cubic meters (3,487.6 cubic yards) of concrete (90%), iron (10%), including superstructure, walls, catwalks, pillars, rebar from 100-H/183-H Solar Basins were disposed of in the 183-H Clearwell.

Waste Type: Demolition and Inert Waste

Waste Description: The unit now contains nonhazardous and nonradioactive demolition and inert waste from demolished facilities. This waste includes rubble from such facilities as 190-H, 151-H, 1701-D and the 183-H Solar Evaporation Basins. The following materials were taken to the 183-H Clearwell:

- On (date unknown), 0.78 cubic meters (27.7 cubic feet) of transite from the 1717H;
- On 11/10/1986, 125.4 cubic meters (164 cubic yards) of insulators from the Hanford power line cleanup;
- On (date unknown), 0.89 cubic meters (31.5 cubic feet) of transite from the 190H Annex;
- On 9/25/1987, 44.3 cubic meters (58 cubic yards) of non-excessible building equipment from the 1713H Storage Facility;
- On 3/3/1987, (volume unknown) of galvanized posts and concrete from the perimeter fence;
- On 11/17/1987, 45.9 cubic meters (60 cubic yards) of decommissioned utility fixtures and cross arms;
- On 1/14/1988, 72.6 cubic meters (95 cubic yards) of decommissioned utility guy wires, rebar, and gravel;

- On 1/15/1988, 22.9 cubic meters (30 cubic yards) of decommissioned utility guy wires and concrete;
- On 10/10/1988, 880 used wooden pallets (1.07 by 1.07 meters [3.5 by 3.5 feet]) from the 183-H Basin;
- On 8/30/1990, 11.5 cubic meters (15 cubic yards) of cement block (60%), wood (30%), insulation (5%), pipe (5%) from 1701-D; (record #1 for 8/30/1990); (radiological release record included);
- On 8/30/1990, 11.5 cubic meters (15 cubic yards) of cement block (60%), wood (30%), insulation (5%), pipe (5%) from 1701-D; (record #2 for 8/30/1990); (radiological release record included);
- On 8/30/1990, 11.5 cubic meters (15 cubic yards) of cement block (60%), wood (30%), insulation (5%), pipe (5%) from 1701-D; (record #3 for 8/30/1990); (radiological release record included);
- On 8/30/1990, 11.5 cubic meters (15 cubic yards) of cement block (60%), wood (30%), insulation (5%), pipe (5%) from 1701-D; (record #4 for 8/30/1990); (radiological release record included);
- On 8/30/1990, 11.5 cubic meters (15 cubic yards) of cement block (60%), wood (30%), insulation (5%), pipe (5%) from 1701-D; (record #5 for 8/30/1990); (radiological release record included);
- On 8/30/1990, 11.5 cubic meters (15 cubic yards) of cement block (60%), wood (30%), insulation (5%), pipe (5%) from 1701-D; (record #6 for 8/30/1990); (radiological release record included);
- On 8/31/1990, 11.5 cubic meters (15 cubic yards) of cement block (60%), wood (30%), insulation (5%), pipe (5%) from 1701-D; (record #1 for 8/31/1990); (radiological release record included);
- On 8/31/1990, 11.5 cubic meters (15 cubic yards) of cement block (60%), wood (30%), insulation (5%), pipe (5%) from 1701-D; (record #2 for 8/31/1990); (radiological release record included);
- On 8/31/1990, 11.5 cubic meters (15 cubic yards) of cement block (60%), wood (30%), insulation (5%), pipe (5%) from 1701-D; (record #3 for 8/31/1990); (radiological release record included);
- On 8/31/1990, 11.5 cubic meters (15 cubic yards) of cement block (90%), rebar (5%), pipe/conduit (5%) from 1701-D; (record #4 for 8/31/1990); (radiological release record included);
- On 8/31/1990, 11.5 cubic meters (15 cubic yards) of cement block (90%), rebar (5%), pipe/conduit (5%) from 1701-D; (record #5 for 8/31/1990); (radiological release record included);
- On 8/31/1990, 11.5 cubic meters (15 cubic yards) of cement block (90%), rebar (5%), pipe/conduit (5%) from 1701-D; (record #6 for 8/31/1990); (radiological release record included);
- On 8/31/1990, 11.5 cubic meters (15 cubic yards) of cement block (90%), rebar (5%), pipe/conduit (5%) from 1701-D; (record #7 for 8/31/1990); (radiological release record included);
- On 8/31/1990, 11.5 cubic meters (15 cubic yards) of cement block (90%), rebar (5%), pipe/conduit (5%) from 1701-D; (record #8 for 8/31/1990); (radiological release record included);
- On 9/7/1990, 9.6 cubic meters (12.5 cubic yards) of roofing asphalt (80%), pipe metal (5%), toilet wood (5%), windows (10%) from 2719-W;
- On 4/26/1991, 245 pallets, 2 cable spools, 53.6 meters (176 feet) of 2 by 6 (9.23 cubic meters [326 cubic feet]) of wood from 100-H;
- On 9/11/1993, 332.6 cubic meters (435 cubic yards) of wood (85%), metal (5%), concrete (10%) from 1722-D and 1713-D; (radiological release record included);
- On 9/12/1993, 137.6 cubic meters (180 cubic yards) of wood (60%), metal (10%), concrete (30%) from 1722-D; (radiological release record included);
- On 11/30/1993, 11.5 cubic meters (15 cubic yards) of material not identified on form from

- 100-H;
- On 2/22/1994, 1.36 cubic meters (48 cubic feet) of metal (70%), wood (20%), cardboard (10%) from 105-D;
 - On 8/10/1994, 0.28 cubic meters (10 cubic feet) of crushed vent ducting (100%) from 105-H; (radiological release survey included);
 - On 2/16/1995, 45.9 cubic meters (60 cubic yards) of wood (40%), concrete (40%), steel (40%) from laydown yard, east of the carpenter shop, outside 100-N double fence;
 - On 2/16/1995, 45.9 cubic meters (60 cubic yards) of wood (40%), concrete (40%), steel (40%) from laydown yard, east of the carpenter shop, outside 100-N double fence; (record #2 for 2/16/1995);
 - On 4/10/1995, 30.6 cubic meters (40 cubic yards) of roofing material, including tar and gravel (asphalt), fiberboard, metal flashing and wood debris from 105-D roof replacement; (radiological release statement included);
 - On 4/11/1995, 30.6 cubic meters (40 cubic yards) of roofing material, including tar and gravel (asphalt), fiberboard, metal flashing and wood debris from 105-D roof replacement; (radiological release statement included);
 - On 10/23/1995, 2,666.5 cubic meters (3,487.6 cubic yards) of concrete (90%), iron (10%), including superstructure, walls, catwalks, pillars, rebar from 100-H/183-H Solar Basins; (See second waste record);
 - On 12/14/1995, 11.5 cubic meters (15 cubic yards) of wood (50%), plastic (40%), metal (10%) from 100-N, N Reactor Deactivation;
 - On 10/11/1995, 38.2 cubic meters (50 cubic yards) of wood (99%), soil/metal (1%) from 100-D/190-D demolition;
 - On 10/11/1995, 7.6 cubic meters (10 cubic yards) of asphalt/concrete from 100-N waterline upgrade;
 - On 10/23/1995, 0.8 cubic meters (1.0 cubic yard) of scrap electrical wire from 100-N potable waterline upgrade;
 - On 11/10/1995, 122.3 cubic meters (160 cubic yards) of metal (75%), concrete (10%), wood (10%), conduit (5%) from 100-N, Buildings 1100 and 1101;
 - On 2/20/1996, 22.9 cubic meters (30 cubic yards) of asphalt (80%), dirt (20%) from 100-N/Field Deactivation;
 - On 3/4/1996, 0.4 cubic meters (0.5 cubic yards) of plastic (100%) from 100-HR-3 Pump and Treat;
 - On 5/9/1996, 12.2 cubic meters (16 cubic yards) of iron (5%), tar-rock (95%) from 100-H;
 - On 5/11/1996, 12.2 cubic meters (16 cubic yards) of tar (40%), iron (30%), wood (20%), tin (10%) from 100-H;
 - On 5/12/1996, 12.2 cubic meters (16 cubic yards) of galvanized metal (60%), wood (40%) from 100-H; (truck #1);
 - On 5/12/1996, 12.2 cubic meters (16 cubic yards) of galvanized metal (40%), wood (60%) from 100-H; (truck #2);
 - On 5/17/1996, 12.2 cubic meters (16 cubic yards) of tar (95%), iron (5%) from 100-H;
 - On 5/18/1996, 12.2 cubic meters (16 cubic yards) of tar (100%) from 100-H; (truck #1)
 - On 5/18/1996, 12.2 cubic meters (16 cubic yards) of tar (85%), steel (15%) from 100-H; (truck #2);
 - On 5/18/1996, 12.2 cubic meters (16 cubic yards) of tar (100%) from 100-H; (truck #2);
 - On 5/19/1996, 12.2 cubic meters (16 cubic yards) of tar-rock (95%), iron (5%) from 100-H;
 - On 8/18/1996, 24.5 cubic meters (32 cubic yards) of concrete (80%), iron (20%) from 100-DR;
 - On 8/19/1996, 24.5 cubic meters (32 cubic yards) of concrete (80%), iron (20%) from 100-DR;
 - On 2/12/1997, 84.1 cubic meters (110 cubic yards) of asphalt (95%), rock (4%), metal (1%) from 100-H/183-H;
 - On 4/11/1997, 34.4 cubic meters (45 cubic yards) of old asphalt from 200 West Area, 200-ZP-1 Phase III;
 - On 7/16/1997, 15.3 cubic meters (20 cubic yards) of fiberglass insulation from the exterior of

the 1715-N Diesel Tanks;

- On 7/15/1997, 22.9 cubic meters (30 cubic yards) of fiberglass insulation from demolition from 163-N roofing;
- On 7/18/1997, 11.5 cubic meters (15 cubic yards) of fiberglass insulation from the exterior of the 1715-N Diesel Tanks;
- On 7/18/1997, 1.5 cubic meters (2 cubic yards) of hatch lid, metal on wood construction from 163-N Roof;
- On 8/7/1997, 7.6 cubic meters (10 cubic yards) of broken asphalt pieces from pipeline road crossings from 100-HR-3 Project;
- On 8/26/1997, 160.6 cubic meters (210 cubic yards) of concrete (80%), rebar (20%) from 100-N/105-NC;
- On 9/25/1997, 107.0 cubic meters (140 cubic yards) of concrete, rebar, metal roofing and miscellaneous steel from 100-N/1734-N;
- On 10/11/1997, 11.5 cubic meters (15 cubic yards) of concrete (90%), wood (10%) from 2614 E2, W2, W4, W5.

Closure Info: Interim (10/18/2012): Remedial action at the 126-H-2 east clearwell basin was performed from August 5, 2009 through January 28, 2010. The west basin had not been used for debris disposal and remained intact until it was demolished in 2012. The remedial activity consisted of removing debris from the east basin, down to the concrete floor. Approximately 29,593 metric tons (32,621 U.S. tons) of material was removed for disposal at the Environmental Restoration Disposal Facility. Coal ash was removed from the pump room area during July through September 2010.

A number of waste items were encountered and removed during remediation, including fire extinguishers, aerosol cans, glass bottles, cylinders, and metal drums. Many of the drums were located in the western portion of the east clearwell and found to contain oil. Some drums were breached during remediation, releasing contents into the soil inside the clearwell structure. Samples of soil, oil, and other waste material were collected as necessary to support waste characterization and disposal.

Radiological surveys performed during remediation did not identify any radiological contamination. However, technicium-99 was identified in samples of concrete debris located near the surface of the clearwell. This concrete is believed to have been disposed from demolition of the adjacent 183-H solar basins.

Code: 132-H-1	Classification: Accepted
Names: 132-H-1; 116-H Reactor Exhaust Stack Burial Site	Reclassification: Interim Closed Out (6/26/2007)
Type: Burial Ground	Start Date: 1/1/1945
Status: Inactive	End Date: 1/1/1965
Description:	The site consists of an excavated trench that contains the demolition rubble of the Reactor Exhaust stack and foundation. The stack was originally part of the 105-H Reactor Gas and Exhaust Air system. The waste site has been evaluated and reclassified to Interim Closed Out.
Location:	The stack was located on the south side (southwest corner) of the 118-H-6 (105-H Reactor Building). The stack burial trench was excavated in a south-by-southwesterly direction from the base of the stack, between the 132-H-2 (117-H Filter Building) and the 132-H-3 (1608-H Lift Station Building).
Related Sites/Structures:	The stack was part of the 118-H-6 (105-H Reactor Gas and Exhaust Air system) and the 132-H-2 (117-H Filter Building).

Process Description: Before demolition the 116-H exhaust stack was part of the reactor building ventilation system, which was designed to provide clean air to the various work sites within the 105-H reactor building. The clean air entered the noncontaminated portions of the reactor building and then moved through zones with increasing levels of contamination before its discharge into the atmosphere.

After the 1960 installation of the 117-H Filter Building, the air passed through HEPA (high-efficiency particulate air) filters and halogen (activated charcoal) filters prior to its atmospheric release. Following completion of the confinement project in 1960, the air was diverted from the 118-H-6 (105-H Reactor) site via underground reinforced concrete ducts to the 132-H-2 (117-H Filter Building). After flowing through the filters, the air went through below-grade and above-grade concrete ducts and into the exhaust stack.

Prior to demolition the stack was 61 meters (200 feet) tall and had a diameter of 5.1 meters (16.58 feet) at its base. The stack was toppled into a 60.96 meter (200 feet) long by 9.14 meter (30 feet) wide by 5.49 meters (18 feet) deep trench.

Waste Type: Demolition and Inert Waste

Waste Description: Air moving from the least contaminated zones through increasingly contaminated zones was discharged to the stack unfiltered. At the time of demolition low-level smearable alpha contamination was present measuring up to 30 disintegrations/minute per 100 square centimeters (190 disintegrations/minute per 100 square inches). Smearable beta contamination ranged from 100 to 5,000 disintegrations/minute per 100 square centimeters (650 to 32,000 disintegrations/minute per 100 square inches).

Closure Info: Interim (6/26/2007): The 116-H exhaust stack was demolished in 1983. The 116-H exhaust stack was demolished using explosives and the concrete rubble was buried under at least 1 meter (3.3 ft) of clean fill. The stack base was removed to a minimum of 0.9 meter (3 ft) below grade before it was buried in situ. The monolithic concrete base attached to the 116-H exhaust stack extends into the deep zone, however, the concrete base was for structural support and did not come into contact with contaminated exhaust. Therefore, no deep zone evaluation is necessary for this site. After demolition activities were completed, the 116-H site was graded to conform with the surrounding terrain. A portion of the vertical 15-centimeter (6-inch) condensate drain pipe remained embedded in the center of the buried stack base. No deep zone evaluation was necessary because the embedded condensate drain did not extend into the deep zone. The pipe was a free draining condensate line that fed into the 1608-H effluent pumping station. The potential contamination remaining within the drain was considered to pose little risk to human health and the environment, such that further sampling activities were not required. Residual contamination that could remain in the floor drain pipe would be analogous to residual contamination in the buried 132-D-4 (105-D Reactor Exhaust Stack) and 132-F-4:2 (105-F Reactor Exhaust Stack) embedded stack condensate drain lines. Although the condensate drain lines were not sampled, these sites were reclassified as "Interim Closed Out" and "No Action," respectively.

Concrete core samples were collected from the 116-H exhaust stack for the purpose of establishing an isotopic inventory of radionuclides and depth of radionuclide penetration into the stack interior surface. Core samples were drilled from the outside surface of the stack inward. A total of five core samples were obtained from the 4.6 meter (15 ft), 5.8 meter (19 ft), 9 meter (30 ft), 17 meter (56 ft), and 24 meter (80 ft) elevations. The depth of contaminant penetration in the concrete was then determined by removing three successive layers from each core. The core layer from the interior of the stack had the highest radiological readings with levels of radiation greater than 200 counts per minute per probe size (2.5 sq. centimeters). Results of the core samples showed that the contamination was confined to a 0.01 inch (0.4 in) surface layer of the concrete wall of the inner surface of the stack. The 1983 sampling results were used to support the waste site reclassification. Using the maximum radiological activities

from the pre-demolition characterization data to represent residual contamination levels over the entire mass of concrete of the former stack, RESidual RADioactivity (RESRAD) modeling was performed in 2006 to support the previous decision to demolish and bury the stack in place.

The RESRAD modeling was performed only for the contaminated rubble which was buried in the shallow zone. An evaluation of the concrete foundation that extended greater than 4.5 meters (15 feet) was not required because the foundation was not contaminated. The condensate drain embedded in the stack foundation was located in the shallow zone. The RESRAD modeling accounted for radioactive decay from 1983 (year of sampling) to 2006 and predicted that the site achieved the dose limits and risk objectives for rural-residential land use, groundwater protection, and river protection.

The horizontal condensate drain line running from the stack base to the 1608-H effluent pumping station was removed during previous remedial actions associated with the 100-H-21 Reactor Effluent Pipelines. Based on excavation boundaries of the demolition activities required to place the 105-H Reactor into interim safe storage, the remaining portion of the horizontal condensate drain line external to the 105-H Reactor Safe Storage Enclosure has been removed. The drain line and underlying soils were not sampled; however, it was believed that contamination related to the drain line, as well as to the embedded drain remaining in the stack, was bounded by the waste profile for the 100-H-21 Reactor Effluent Pipelines.

Code:	132-H-3	Classification:	Accepted
Names:	132-H-3; 1608-H Effluent Pumping Station Site; 1608-H Waste Water Pumping Station Site; 116-H-8	Reclassification	Interim Closed Out (7/12/2012)
Type:	Pump Station	Start Date:	1/1/1949
Status:	Inactive	End Date:	1/1/1965
Description:	The waste site has been remediated and Interim Closed Out. The pumping station was constructed of concrete block walls above ground and reinforced concrete below ground. It extended 3.7 meters (12 feet) above grade and 9.8 meters (32 feet) below grade. The unit included a wastewater collection pit. The building was previously demolished in-situ in 1987.		
Location:	The unit was located on the east side of the 105-H Reactor Building.		
Process Description:	The 1608-H facility was constructed in 1949 and served as a lift station to pump effluent water from the various reactor building drains. From the reactor startup in 1949 until 1953, the 1608-H effluent was pumped into the process effluent waste lines that discharged into the 107-H Retention Basin. From 1953 until the 105-H Reactor shut down in 1965, the 1608-H effluent was pumped into the 116-H-2 liquid waste disposal trench. The effluent pumping station was operational from 1949 until 1965, when the 105-H Reactor and its supporting facilities were shut down.		

The 1608-H Effluent Pumping Station was decommissioned in two phases in 1987. Initial decommissioning entailed the removal and disposal of all asbestos within the building. The asbestos was transported to the Central Landfill in the 600 Area for disposal. The work area was thoroughly cleaned after asbestos removal using vacuum cleaners equipped with high-efficiency particulate air filters and by a complete washdown of the interior of the building. The second phase of decommissioning included removal of the facility's equipment, removal of sump water and sludge, and sampling and characterization of the facility and associated features (e.g., piping and switch gear). Residual water was pumped out and transported by tractor-trailer to the 1325-N Crib (100-N Area) for disposal. The residual sludge in the facility sumps was removed and stabilized in 208-L (55 gal) drums with floor-dry. The 20 drums containing the

sludge were moved to the 105-H transfer bay for storage until final designation. Based upon the sample results at the time, the sludge was believed to require repackaging for final storage and disposal as mixed waste and was sent to the Central Waste Complex (CWC) in the 200 West Area.

Waste Type: Process Effluent

Waste Description: This site received water from reactor building drains and irradiated fuel storage drains containing trace amounts of low-level radionuclides and decontamination chemicals, primarily Turco (a commercial chemical compound with a proprietary composition). Radionuclides were primarily activation and fission products. Other decontamination chemicals consisted of sodium fluoride, oxalic acid, and citric acid.

Closure Info: Interim (7/12/2012): The original demolition activities began in May 1987 with the excavation of the periphery around the 1608-H Building to a depth of approximately 5 meters (16.4 ft). All pipes entering the structure were isolated and plugged to prevent the potential for water draining into the facility after demolition. This piping was later removed and Interim Closed Out in 2001 as part of the 100-H-21 remediation. Prior to building demolition, holes were punched in the bottom of each sump floor in order to facilitate drainage.

Remediation of the 132-H-3 waste site was performed from September 27, 2010, through July 13, 2011. Contaminated soil and concrete debris associated with the demolished 1608-H facility was removed and stockpiled for disposal at the Environmental Restoration Disposal Facility (ERDF). Approximately 34,465 metric tons (15,260 bulk cubic meters) of material was removed for disposal at the ERDF. The excavation proceeded to the planned excavation depth at approximately 116.5 meters (382 ft) above mean sea level (amsl) to support complete removal of the previously demolished pumping station structure. This excavation depth was reached in January 2011. However, stained soil was observed in the north sidewall of the deepest portion of the excavation. Field measurements and in-process soil samples indicated that residual radiological contamination exceeding cleanup criteria for protection of groundwater and the Columbia River was present in this stained soil. Therefore, additional excavation was performed in February 2011 to remove the stained soil on the north wall, to the extent allowed by the safety limits due to the steep slopes of the excavation and the need to prevent undermining the concrete structures northwest of the site. A second round of in-process samples was collected on March 10, 2011, to support a decision if additional excavation was needed. The results of this sampling indicated the presence of residual total chromium, technetium-99, and nickel-63 at concentrations exceeding groundwater and river protection criteria. The staining was believed to be associated with the location where the inlet pipes entered the pumping station (approximate elevation of 122 meters [400 ft] amsl). These pipes may have contained residual liquids that were released to the soil at the time of decommissioning the facility and may have been the source of radiological contamination observed in the north sidewall of the excavation. A decision was made to perform additional stained soil removal on the north excavation wall to the base of the excavation. In-process soil samples were collected on June 6, 2011, on the east, west, and south walls of the excavation to verify that no additional soil removal was required in these areas. The stained soil removal on the north/northwest wall of the excavation was completed in June 2011. An additional round of in-process samples were collected on July 5, 2011, from the north sidewall of the excavation to evaluate whether the stained soil was adequately removed. The results of this sampling indicated that contaminated soil removal was complete. Following remediation, verification sampling of the excavation was conducted on February 15, 2012.

Two pipelines, originally grouped with the 100-H-56 Miscellaneous Pipelines Waste Site (identified as lines 7 and 9), were removed during the excavation and sampling of the 132-H-3 waste site. #7 was a 15.2 cm (6in) vitrified clay sanitary sewer pipe. #9 was a 3.8 cm (1.5 in) steel sanitary water pipe.

Code: 1607-H2 **Classification:** Accepted
Names: 1607-H2; 1607-H2 Sanitary Sewer System; 1607-H2 Septic Tank; 1607-H2 Septic Tank and Associated Drain Field; Septic System; 124-H-2 **Reclassification:** Interim Closed Out (2/5/2001)
Type: Septic Tank **Start Date:** 1/1/1949
Status: Inactive **End Date:** 1/1/1965

Description: The site has been remediated, and a Closeout Verification Package (CVP) has been approved. It is no longer marked or posted in the field. The unit included a septic tank, tile field, and associated piping (about 140 meters (460 feet) from the tank to the intersection with the Water Treatment Plant pipelines).

Location: The septic system was located north of the 105-H Reactor Building, north of the 182-H Reservoir and northeast of the 183-H (116-H-6) Solar Basins.

Related Sites/ Structures: The site received sanitary waste from the 182-H, 183-H, 190-H, and other 100 H Area office and maintenance buildings.

Waste Type: Sanitary Sewage

Waste Description: This unit received unknown amounts of sanitary sewage from 182-H, 183-H, 190-H, and all office and maintenance service buildings with "1700" designations. Based on measured sludge levels, the volume was estimated to be 28,500 liters (7,500 gallons).

Closure Info: Interim (2/5/2001): The site has been remediated and was closed out on February 5, 2001.

Remedial action at the 1607-H2 site began on October 21, 1999. Excavation involved removing the overburden materials, the structure (septic tank, drain field, and piping), and underlying contaminated soil. Approximately 140 meters (460 ft) of the 8 inch diameter sewage influent pipe was removed during excavation. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Contaminated materials were disposed of at ERDF. On November 11, 1999, the excavation was completed. At the completion of the remedial action, the total excavation was approximately 5,054 square meters (54,405 square feet) in area with a maximum depth of approximately 5.6 meters (18.4 feet) for the septic tank/piping excavation and 1.5 meters (4.9 feet) for the drain field excavation. Approximately 12,207 metric tons (13,456 tons) of material from the site were disposed of at the Environmental Restoration Disposal Facility.

On May 5, 2000, a test pit was excavated at the bottom of the 1607-H2 drain field excavation. The purpose of the test pit was to characterize soil lead and mercury concentrations at depth for development of a site-specific model. The test pit was excavated to 4.6 meters (15 ft) below the bottom of the drain field excavation. Samples were collected from the test pit at intervals of 1 meter and analyzed for arsenic, total chromium, mercury, and lead. Test pit samples were not analyzed for radionuclides because the cleanup verification samples collected from the walls and floor of the site excavation indicated that remaining site soil radionuclide concentrations are at or below background.

Results of the sampling, laboratory analyses, and data evaluations for the 1607-H2 site indicate that all remedial action objectives and goals for direct exposure, protection of groundwater, and protection of the Columbia River have been met.

Code: 1607-H3 **Classification:** Accepted
Names: 1607-H3; 1607-H3 Sanitary Sewer System; 1607-H3 Septic Tank; 1607-H3 Septic Tank and **Reclassification:** Interim Closed Out (2/1/2011)

Associated Drain Field; 124-H-3

Type: Septic Tank **Start Date:** 1/1/1948

Status: Inactive **End Date:** 1/1/1968

Description: The waste site was a septic tank and drain field. The tank is constructed of concrete and measures 5.6 by 2.1 by 4.0 meters (18.5 by 7 by 13 feet) deep. The tank had a 100 person capacity with an average detention period of 24 hours.

The drain field was constructed of 10-centimeter (4-inch) vitrified pipe. It measured 15 by 30 meters (50 by 100 feet). It was oriented in-line with, and approximately 24 meters (80 feet) from the septic tank. A row of eight vent pipes were visible, running perpendicular to the entrance road.

Location: The 1607-H3 septic tank and drain field were located along H Avenue northeast of the 1701-H Badge House.

Process Description: The 1607-H3 septic system received sanitary sewage from the 1701-H Badge House, the 1709-H Fire Station, and the 1720-H Security Patrol Change Room. In addition to the sanitary sewage, liquids from the 1701-H Badge House darkroom (used for film badge processing) were disposed to the 1607-H3 septic system.

Waste Type: Sanitary Sewage

Waste Description: This unit received unknown amounts of sanitary sewage from the 1701-H Badge House (security checkpoint), the 1720-H Security Patrol Change Room, offices, and the 1709-H Fire Station. The sewage per capita is 130 liters (35 gallons) plus 20% for sludge.

Closure Info: Interim: All of the facilities associated with the septic system have been removed to grade. Remedial action at the 1607-H3 waste site was performed between October 13 and November 10, 2009, and encompassed the removal of the below-grade septic tank and the drainage field pipelines. The site was excavated to depths ranging from approximately 1.6 meters (5.3 feet) at the drain field to 4 meters (13 feet) at the septic tank location, resulting in approximately 3,763 bank cubic meters (BCM) (4,922 bank cubic yards [BCY]) of soil and piping/debris being removed for disposal at the Environmental Restoration Disposal Facility (ERDF). In addition, approximately 235 meters (771 feet) of vitrified clay pipe were removed. The soil was sorted within the excavation and direct loaded for disposal at ERDF. Approximately 1,729 BCM (2,261 BCY) of overburden soil was removed from above the drain field piping and stockpiled for evaluation for use as clean backfill.

The debris removed from the 1607-H3 waste site was consistent with that of a sewage system and in agreement with the pre-excavation geophysical survey findings. Some six and eight inch diameter piping was excavated that had soldered joints. These pipe segments were segregated for macro-encapsulation as a lead contaminate prior to disposal at ERDF. Small portions of lateral pipelines associated with the 100-H-51:4, 100-H Main Gate Storm Drain waste site were removed during the 1607-H3 waste site remediation.

Code: 1607-H4

Classification: Accepted

Names: 1607-H4; 1607-H4 Sanitary Sewer System; 1607-H4 Septic Tank; 1607-H4 Septic Tank and Associated Drain Field; 124-H-4

Reclassification: Interim Closed Out (2/26/2001)

Type: Septic Tank

Start Date: 1/1/1948

Status: Inactive

End Date: 1/1/1965

Description: This site has been remediated and closed out. The unit included a septic tank, tile field, and

associated piping. The system had a six-person capacity and an average detention period of 24 hours. The tile field was constructed of 10-centimeter (4-inch) pipe, 2.4 meters (8 feet) in length.

Location: The site was located on a bluff above the Columbia River, southeast of the 181-H Building and south of the 181-H access road.

**Related Sites/
Structures:** The septic system was associated with the 181-H River Pumphouse.

Waste Type: Sanitary Sewage

**Waste
Description:** This unit received an unknown amount of sanitary sewage from the 181-H River Pumphouse. The sewage per capita is 130 liters (35 gallons) plus 20% for sludge.

Closure Info: Interim: Remedial excavation at the 1607-H4 site began on November 5, 1999 and completed July 24, 2000. The structure and contaminated underlying soil was removed. The elevation of the bottom of the excavation was at 120.4 meters (394.9 feet) upon completion. The excavation was approximately 161 square meters (1,732 square feet) in area with a maximum depth of approximately 3.6 meters (11.8 feet). Approximately 2,078 metric tons (2,286 tons) of material from the site were disposed at the ERDF.

100-HR-2

Code: 100-H-2 **Classification:** Accepted
Names: 100-H-2; Buried Thimble Site; Thimble Pit **Reclassification** Interim Closed Out (3/1/2001)
Type: Burial Ground **Start Date:** 1/1/1953
Status: Inactive **End Date:**

Description: This site has been remediated and Interim Closed Out. No evidence of buried waste was discovered during the excavation.

Location: The site was located south of the 105-H Reactor Building, in between and near the convergence of 2 north to south-running railroad spurs. This area is located in an area that, prior to World War II and formation of the Hanford Site, was occupied by fruit tree orchards.

Process Description: 100-H Reactor operated from October 1949 to April 1965. Reactor burial sites contain two types of radioactive waste: neutron activated steel and aluminum material containing cobalt-60 and surface contaminated waste contaminated primarily with zinc-65.

Waste Type: Equipment

Waste Description:

Closure Info: Interim: This area is located in an area that, prior to World War II and formation of the Hanford Site, was occupied by fruit tree orchards.

Remedial action at the 100-H-17 sites group (100-H-17, 100-H-30, 100-H-2 and 116-H-2) began on February 2, 2000. The sites were grouped together for remediation because of location and similar contaminants. Excavation of the area involved removing the overburden materials, miscellaneous debris, the contaminated structure, and underlying contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. Contaminated materials were disposed of at ERDF. On February 10, 2000, the excavation was completed.

No evidence of buried waste was found during the excavation of the 100-H-2 site.

At the completion of the remedial action, the total excavation was approximately 6,240 square meters (67,170 square feet) in area with a maximum depth of approximately 2.6 meters (8.5 feet). Approximately 19,920 metric tons (21,960 tons) of material from the site were disposed of at the ERDF.

Code: 100-H-37 **Classification:** Accepted
Names: 100-H-37; 100-H Mud Dauber Contamination Area **Reclassification** Interim Closed Out (8/5/2010)
Type: Contamination Migration **Start Date:** 1/1/2002
Status: Inactive **End Date:** 1/1/2003

Description: 100-H-37 has been remediated and Interim Closed Out. The waste site consisted of multiple radiologically contaminated areas caused by mud dauber wasps that created nests from contaminated mud. The contaminated nests were discovered during remediation of the 105-H Fuel Storage Basin (118-H-6:4). While removing and processing dirt and sediment from the lower 38 cm (15 in) of the FSB, elevated airborne radioactivity levels that exceeded posting

criteria were noted. One of the corrective actions was to maintain at least 5.1 centimeters (2 in) of water on the basin floor. The mud daubers utilized the large source of contaminated mud in the 105-H Fuel Storage Basin (FSB) to construct of their tube nests. The insects transported the contaminated mud from the FSB to multiple areas surrounding the reactor. The majority of the areas contained more than one nest, some were greater than ten nests. Forty three areas of contaminated nests were located. The postings were removed after the areas were remediated.

Location: The nests were estimated to be scattered across approximately 10.1 hectares (25 acres) throughout 100-H Area.

Release Description: On December 11, 2002, while removing and processing dirt and sediment from the floor of the 105-H Fuel Storage Basin (FSB) (118-H-6:4), elevated airborne radioactivity levels were generated and later observed on the air sample filter that was removed from the air sampler located on excavation equipment. A preliminary analysis of the filter indicated radioactivity greater than the threshold for posting an Airborne Radioactivity Area (ARA). The FSB was already posted as a Radiation Area/Contaminated Area (RA/CA) at the time of the work. It was then posted as an Airborne Radioactivity Area (ARA) and no one else entered the area.

Work in the 105-H FSB was to proceed using a manned track-hoe excavator to remove basin fill from the lower 38 cm (15 in) between the basin floor stem walls. A contamination survey of the excavator bucket showed removable contamination levels that were higher than expected for both alpha and beta-gamma contamination. Based on the elevated bucket contamination levels, the entire FSB was re-posted as a High Contamination Area (HCA). Analysis at the Radiological Counting Facility (RCF) indicated the presence of americium and plutonium. Based on the analysis, the FSB was posted and controlled as an Airborne Radioactivity Area (ARA). The probable source of the airborne radioactivity was the contamination entrained in the cement dust released from the basin floor and stem walls during the excavation process.

The 105-H FSB (118-H-6:4) was approximately 6.1 meters (20 ft) deep. The fill consisted of approximately 5.2 meters (17 ft) of clean fill over a 76.2 cm (30 in) layer of sludge, debris and potential fuel fragments. Some dust became airborne during the scraping of the basin floor and stem walls, and airborne radiological posting criteria were exceeded. Consequently, one of the corrective actions was to maintain at least 5.1 centimeters (2 in.) of water on the basin floor to reduce airborne dirt and sediment, which created mud. The mud dauber wasps transported mud from the FSB floor to other areas surrounding the 105-H Reactor Building using the mud for construction of their tube nests. The nests were radiologically contaminated.

Related Sites/ Structures: The 100-H-37 contamination migration is associated with the 105-H Fuel Storage Basin (118-H-6:4). Some contaminated nests were deferred to 100-H-41 and 100-H-58. Other mud dauber sites in 100-H Area were remediated along with these sites, 126-H-2, 116-H-5, 118-H-6:4, 118-H-3, 118-H-5, and 118-H-1.

Waste Type: Soil

Waste Description: The waste is contaminated mud dauber nests and other materials depending on the where the nest(s) were placed, including electrical utility poles, manholes, and other structures. The mud dauber contamination limits: removable - beta-gamma 1000 dpm/100cm²; alpha 20 dpm/100cm². Total - beta-gamma 5000 dpm/100cm²; alpha 100 dpm/100cm². The contaminants of potential concern include beta-gamma emitting isotopes C-14, Ni-63, H-3, Co-60, Sr-90, Cs-137, Eu-152, Eu-154. The alpha emitting isotopes would be Pu-239/240, and Am-241. RCF samples 11261, 11262, 11263, 11259, 11260 were used to determine the radioactive isotopes for the site.

Closure Info: Interim: A mud dauber characterization strategy was developed and approved by DOE and Ecology to guide remediation activities and provide closure documentation for the 100-H-37 waste site. The waste site consisted of seven discrete nest areas east of the 105-H Reactor. A Remaining Sites Verification Package (RSVP) document was not prepared for the 100-H-37 waste site, because the applicable components were better addressed using attachments to the

waste site reclassification form. No separate calculations or comparison to screening levels for the 100-H-37 waste site were done. The 100-H-37 waste site was included in the Explanation of Significant Differences for the 100 Area Remaining Sites Interim Remedial Action Record of Decision, for remediation, treatment, and disposal.

In July 7, 2009, Ecology concurred that the data collected for this study indicated that radiological field instruments are reliable to ensure RAGs are achieved. Remedial action began with the excavation of individual nests with a backhoe, due to the difficulty in hand digging and the sloughing of excavation material. Areas containing numerous and individual nests were removed. The number of nests in an area and the straw covered re-vegetated areas were considered in decisions to excavate individual nests or scrape an entire area. Forty small, dispersed excavations and three large areas of contamination were excavated. The three large areas were scraped to ensure remediation of locations containing many nests and to protect the field radiological instrumentation that could be damaged by taking readings in areas with dense rabbit brush and other vegetation. After excavation, Global Positioning Environmental Radiological Surveyor (GPERS) surveys were performed on these three large areas. Handheld radiological surveys verified that the forty smaller excavations were no longer contaminated. Several of the areas which appeared on the original, overall 100-H-37 site location map were remediated along with other waste sites at the 100-H Area, including 126-H-2, 116-H-5, 118-H-6:4, 118-H-3, 118-H-5, and 118-H-1. Several of the mud dauber areas were located on active power lines that serviced facilities in the 100-H Area. The power poles are located along H Avenue, Herron Avenue, and from the west of the 105-H Reactor Building to the warehouse. These locations have been deferred to the 100-H-58 waste site. Also, during confirmatory sampling activities at waste site 100-H-41, the radiological contamination inside a pipe was confirmed to be the result of contaminated mud dauber nests located on the pipe of concern. The nest was addressed with 100-H-41.

Excavations took place between July 14 and August 21, 2008. Two additional mud dauber areas were excavated in December 2009. This second event only took one day to complete. A total of 19,153 BCM were removed and disposed at ERDF.

The contaminated areas were remediated by removing radiologically contaminated materials to ensure remedial action goals (RAGs) were achieved. No RSVP was prepared. The reclassification was made with supporting documentation attached to reclassification form 2010-007.

Code: 100-H-38	Classification: Accepted
Names: 100-H-38; Trenches and Pit Southwest of 105-H	Reclassification: Interim No Action (11/5/2013)
Type: Burial Ground	Start Date:
Status: Inactive	End Date:
Description: The site has been evaluated and determined to require No Action. It consists of an area, approximately 3 acres in size, marked by ground scars resembling trenches and pits. A large pit in the western portion of this waste site, first identified by the EPA through an aerial photographic analysis of the 100-H Area, was later determined to have been a pre-Hanford gravel pit. The two apparent trenches just east of the gravel pit were associated with preconstruction site cleaning activities at the 100-H Area.	
Location: The site is situated along a natural depression on the western boundary of the 100-H Area perimeter fence.	
Closure Info: Interim (11/5/2013): Confirmatory samples were collected at 100-H-38 on June 14, 2013 from test pits and trenches.	

Test pit 1 (TP1) was excavated to a depth of 3 meters (10 ft) below ground surface (bgs) where native soil was encountered. A sample (J1RP26) was collected from the backhoe bucket of material brought up from the bottom of the excavation, and the excavation was then backfilled.

Test trench 1 (TT1) was excavated to a depth of 2.4 meters (8 ft) where native soil was encountered. A sample (J1RP27) was collected from the backhoe bucket of material brought up from the bottom of the excavation at the approximate midpoint of TT1, and the excavation was then backfilled.

Test trench 2 (TT2) was excavated to a depth of 3 meters (10 ft) where native soil was encountered. Two samples and a duplicate were collected from the backhoe bucket of material brought up from the bottom of the excavation; a sample (J1RP29) was collected at the east end of TT2 excavation, and a sample (J1RP28) and a duplicate (J1RP30) were collected at the west end of TT2 excavation. The excavation was then backfilled.

No elevated radiological or elevated VOC readings were noted in the field. No suspected asbestos-containing material or other anomalous material was observed during confirmatory sampling. Herbicides and pesticides were identified in the sample design, but sample material for these two analyses were not collected. Fortunately, sufficient excess sample material was available in the laboratory from other analyses to perform the overlooked analyses.

Confirmatory sampling results, in conjunction with field instrumentation screening results, indicated that the residual concentrations of contaminants of potential concern (COPC) at this site met the Remedial Action Goals for direct exposure, groundwater protection, and river protection. In accordance with this evaluation, the confirmatory investigation results support a reclassification of the 100-H-38 waste site to No Action.

Code: 100-H-40	Classification: Accepted
Names: 100-H-40; Disposal Pit	Reclassification: Interim No Action (5/20/2010)
Type: Trench	Start Date:
Status: Inactive	End Date:
Description:	The site has been evaluated and determined to require No Action. It consists of a pit used for the disposal of maintenance shop waste.
Location:	The location was described by a former employee as being "west of central access road" (DC-0227). The interviewee sketched the approximate location on a map. The sketch showed the location south-southeast of the 118-H-1 burial ground and northwest of building 1709-H. The boundary of the waste site presented in photo 1 is intended to incorporate this area while allowing for the inherent inaccuracy of the sketch.
Related Sites/ Structures:	The site was associated with 1700-H buildings, including 1709-H, 1716-H, 1717-H and 1720-H (DC-0227).
Process Description:	The 100-H area was constructed between March 1948 and October 1949. The disposal of solid wastes during construction was documented in the Design and Construction History, Project C-165-A, Pile Area "H" (HW-24800-2). The report indicated that a burning pit (128-H-1) was "established at the northwest corner of the area for disposing of the trash and rubbish plus the usual odds and ends of waste construction material". The construction of 100-H area also included the creation of a solid waste burial ground (118-H-1). The burial ground was used for the disposal of solid dry wastes (HW-27337). Other burial grounds were created during the facility operations for the purpose of disposing reactor hardware. Documentation of solid waste disposal during the reactor operations (1949 through 1965) was limited to the facility's

radioactive wastes. The disposition of nonradioactive solid waste is not otherwise documented but presumed to have disposed of at the 118-H-1 and 128-H-1 waste sites, with one notable exception.

Waste Type: Soil

Waste Description: Contaminants of potential concern may include lead, ICP metals, TPH, PAH, PCBs. This site may contain maintenance shop waste, e.g. paint cans and auto repair waste (Denton, L interview 1990).

Closure Info: Interim: Confirmatory sampling activities at the site were performed from October 27 to 29, 2009. The eight locations with indications of geophysical anomalies were excavated to investigate for potential buried maintenance shop debris. Test Pit excavations unearthed small pieces of metallic surface debris and transite siding, native soil and small volumes of debris at shallow depths. At test pit 7, material within the excavation was consistent with the burial of a demolished building.

Code: 100-H-58

Classification: Accepted

Names: 100-H-58; Mud Dauber Nests On Active Powerlines In 100H Area

Reclassification: None

Type: Contamination Migration

Start Date:

Status: Active

End Date:

Description: The site consists of contaminated mud dauber (wasps) nests in the 100-H Area. Multiple mud dauber nests were discovered on power lines and power poles. The nests could not be remediated because the lines are in use.

Location: The nests were identified along H Avenue, Herron Avenue, and from the west of the 105-H Reactor Building to the warehouse.

Related Sites/ Structures: Other mud dauber contamination sites were 100-H-37 and 100-H-41.

Process Description: During cleanup of the 105-H Fuel Storage Basin (FSB), dirt and sediment were removed from the lower 38 cm (15 in.) of the basin, which was 6.1 m (20 ft) below ground surface. Some dust became airborne during the scraping of the basin floor and stem walls, and airborne radiological posting criteria were exceeded. Consequently, one of the corrective actions was to maintain at least 5.1 cm (2 in.) of water on the basin floor to reduce airborne dirt and sediment, which created mud. The mud dauber wasps transported mud from the FSB floor to other sediment and debris areas surrounding the 105-H Reactor Building using the mud for construction of their tube nests. These mud dauber areas became the 100-H-37 waste site. However, during remediation of 100-H-37, multiple mud dauber nests were discovered on power lines that could not be remediated because the lines were in use. These lines are along H Avenue, Herron Avenue, and from the west of the 105-H Reactor Building to the warehouse. The nests are primarily within crevices in the wooden poles, and 35 nests have been counted. It is possible that more nests could be present, as characterization did not occur at heights above 7 ft. A mud dauber characterization strategy was developed and approved by the U.S. Department of Energy and Washington State Department of Ecology (Ecology) to guide remediation activities and provide closure documentation for the 100-H-37 waste site. The strategy included an initial characterization approach to verify the accuracy of radiological field instruments to be used in the place of soil sampling for verification and closeout purposes. On July 7, 2009, Ecology concurred that the data collected for this study indicated that radiological field instruments are reliable to ensure RAGs are achieved for the mud dauber waste site.

Code: 118-H-1	Classification: Accepted
Names: 118-H-1; 100-H Burial Ground No. 1; 100-H-1	Reclassification Interim Closed Out (10/12/2011)
Type: Burial Ground	Start Date: 1/1/1949
Status: Inactive	End Date: 1/1/1965

Description: The waste site has been remediated. During remediation, the burial ground was divided into two subsites - 118-H-1:1; 100-H Burial Ground Trenches and Sorting Cells and 118-H-1:2; Anomaly Staging Area and Fuel Bunker.

The waste site was a mixed solid waste burial ground. The overall site runs east and west. There are numerous trenches of various dimensions, generally running north and south. The boundaries are permanently marked with concrete posts numbered H-65-1 through H-65-23.

Location: The site is located about 396 m (1,300 ft) southwest of the 105-H Building.

Release Description: On October 4, 1960, a controlled fire was set at the north end of the burial site to reduce the volume of contaminated material. Control over the fire was lost when two large explosions and several small explosions occurred from underlying drums containing residual combustible materials.

Process Description: This is the primary solid waste burial ground for the 100-H Area. The wastes disposed of in it include process tubing, contaminated lead bricks, dummy fuel elements, and miscellaneous hardware.

Waste Type: Misc. Trash and Debris

Waste Description: The site received activated components and miscellaneous solid wastes (surface contaminated). Typical examples of activated components are aluminum dummies and process tubing, steel gun barrels and step plugs, thermocouple wires and balls from the 3X safety system. Portions of several horizontal control rods were buried in slit trenches near the southwest corner of the site. Typical examples of surface contaminated materials are hand tools, rags and sweeping compound, light bulbs, sheets of plastic and paper. This type of material was usually sealed in cardboard boxes and placed in separate trenches from the activated components.

This Site has the Following SubSites:

Code: 118-H-1:1

Names: 118-H-1:1; 100-H-1 Burial Ground trenches

Code: 118-H-1:2

Names: 118-H-1:2; Anomaly Staging Areas and Fuel Storage Bunker

Code: 118-H-1:1	Classification: Accepted
Names: 118-H-1:1; 100-H-1 Burial Ground trenches	Reclassification Interim Closed Out (7/29/2011)
Type: Burial Ground	Start Date:
Status: Inactive	End Date:

Description: The 118-H-1:1 subsite has been remediated. It consisted of the original burial ground (trenches A-F) and sorting cells (1-3). In general, all trenches and sorting cells were angled from north to south. Based on the results of the applicable cleanup verification package (CVP or RSVP) documents, authorization was given to remove the Soil Contamination Area and Underground Radioactive Material Area postings from this waste site.

Location: The site was located about 396 meters (1,300 ft) southwest of the 105-H Building.

Process Description: The trenches (A-F) were the primary solid waste burial ground for the 100-H Area. Mixed solid waste such as lead bricks, process tubing, oil drums, and miscellaneous reactor hardware were disposed in the trenches between 1949 and 1965. The trenches were backfilled to grade with 6 feet of soil cover. The sorting cells were created during remediation of the burial ground in 2008 and were used to determine the presence of suspect spent nuclear fuel and anomalies.

The burial ground trenches received activated components and miscellaneous solid wastes (surface contaminated). Typical examples of activated components are aluminum dummies and process tubing, steel gun barrels and step plugs, thermocouple wires and balls from the 3X safety system. Portions of several horizontal control rods were buried in slit trenches near the southwest corner of the site. Typical examples of surface contaminated materials are hand tools, rags and sweeping compound, light bulbs, sheets of plastic and paper. This type of material was usually sealed in cardboard boxes and placed in separate trenches from the activated components.

Closure Info: Interim: Remedial action began on July 22, 2008, and continued through June 29, 2009. Six trenches (A, B, C, D, E, and F) were excavated with approximately 8,160 bank cubic meters (BCM) (10,673 bank cubic yards [BCY]) of overburden soil stockpiled for use as clean fill. Approximately 34,496 BCM (45,119 BCY) of soil and debris were removed for disposal at ERDF. No spent nuclear fuel or thimbles were discovered at the site. Field observations during excavation indicated the presence of concrete, piping, lead bricks, perforated tubes, and control rods among the types of debris removed from the burial ground excavation. There were not any patterns of waste found from one trench to another; there was a random assortment of waste throughout the burial ground. Burial Ground anomalies included a breached pipe with a white solid inside, a forklift battery, suspect hydraulic oil, a damaged drum containing liquid, gray waxy material, oil stained soil, and a deteriorated drum.

The SubSite is Part Of:

Code: 118-H-1

Names: 118-H-1; 100-H Burial Ground No. 1; 100-H-1

Code: 118-H-1:2

Classification: Accepted

Names: 118-H-1:2; Anomaly Staging Areas and Fuel Storage Bunker

Reclassification Interim Closed Out (10/12/2011)

Type: Burial Ground

Start Date:

Status: Inactive

End Date:

Description: The 118-H-1:2 subsite consisted of one anomaly staging area, one anomaly characterization area and a suspect pent nuclear fuel bunker area. The areas were delineated using yellow and magenta rope with radiological postings.

On February 18, 2011, the suspect spent nuclear fuel bunker (SSNF) waste was transported from the 118-H-1:2 bunker staging area to the 100-D, 118-D-3:2 south bunker area. The fuel was later sent to the 100-K fuel storage basins.

All anomalous items found in the 118-H-1:1 Burial Ground were staged in the 118-H-1:2 anomaly staging areas. The anomalies stored there included concrete, piping, lead bricks, process tubing, reactor control rods, oil drums, and miscellaneous reactor hardware. The fuel bunker was constructed to store pieces of reactor fuel prior to characterization and dismantling. The staging area has been remediated.

118-H-1:1 anomalies include a breached pipe with a white solid inside, a forklift battery, suspect hydraulic oil, a damaged drum containing liquid, grey waxy material, oil stained soil,

- and a deteriorated drum. No spent nuclear fuel was discovered at the 118-H-1:1 Burial Ground.
- Location:** The fuel bunker was located approximately 400 meters southwest of the 105-H Reactor Building and north of the 118-H-1:1 Trench E. The two anomaly staging areas were just west of 118-H-1:1 (one was north of Trench F and one was south).
- Process Description:** The subsite area received anomalous material removed during the remediation of the 118-H-1 burial trenches. The material was inspected and sampled in this area prior to disposal.
- Closure Info:** Interim (10/12/2011): On February 18, 2011, the suspect spent nuclear fuel bunker (SSNF) waste was transported from the 118-H-1:2 bunker area to the 100-D, 118-D-3:2 south bunker area. The fuel was shipped from there (100-D Area) to the 100-K Fuel Storage Basins on April 27 and May 3, 2011.

Following the removal of the fuel and the concrete bunkers, and the characterization and processing of staged anomalies, a 0.3 meter (1 ft) scrape of the staging area, characterization area and SSNF bunker area was conducted. The soil was scraped from these areas to ensure that any potential contamination that may exist as a result of the anomaly characterization and processing has been removed. Approximately 272 bank cubic meters (BCM) (356 bank cubic yards [BCY]) of soil was direct loaded for disposal at the ERDF. An additional 80 BCM (105 BCY) was removed on June 8, 2011 to remove residual contamination identified after verification sampling was conducted.

The SubSite is Part Of:

Code: 118-H-1

Names: 118-H-1; 100-H Burial Ground No. 1; 100-H-1

Code: 118-H-2

Classification: Accepted

Names: 118-H-2; H-1 Loop Burial Ground; P-13 Test Loop; 100-H Burial Ground No. 2

Reclassification: Interim Closed Out (11/15/2010)

Type: Burial Ground

Start Date: 1/1/1955

Status: Inactive

End Date: 1/1/1965

Description: The site has been remediated. It was oriented east to west and contained two, in-line concrete vaults. Both vaults were covered to grade with approximately 3.7 meters (12 feet) of soil. The site boundaries were permanently marked with concrete posts numbered H-65-24 through H-65-29. Based on the results of the applicable cleanup verification package (CVP or RSVP) documents, authorization was given to remove the Soil Contamination Area and Underground Radioactive Material Area postings from this waste site.

Location: The site was located approximately 457 meters (1,500 feet) west of the 105-H Reactor Building.

Process Description: The burial ground operated between 1955 and 1965 to receive an irradiated test loop and contaminated piping from the 105-H Reactor. After the 105-H Reactor was shut down in 1965, the concrete vaults were filled and covered to grade with approximately 3.7 meters (12 ft) of soil.

Waste Type: Equipment

Waste Description: The east vault received one stainless steel double tube removed from the reactor in 1955 after several years of irradiation. Within the same area there are also solutions which were used to clean the tube, and miscellaneous capsule components. The west vault was constructed in 1958 and used during deactivation of the 105-H Reactor Building for disposal of a small amount of contaminated pipe.

Closure Info: Interim (11/15/2011): Remedial action began on April 20, 2009, and continued through June 3,

2009, with the removal of 4,366 bank cubic meters (BCM) (5,711 bank cubic yards [BCY]) of soil and debris. An initial Global Positioning Environmental Radiological Survey (GPERS) identified elevated residual radioactivity in the eastern end of the excavated area within the waste site. Additional soil was excavated from that area on June 16, 2009, and a second radiological survey was conducted to verify that the contamination was removed.

Waste encountered during excavation consisted of concrete rubble produced from demolition of the two concrete vaults and some metal piping of varying sizes. One pipe had a 20 R/hr radiological contact dose rate, which distinguished it from the other metal debris. All metal and piping was size-reduced as necessary and disposed at ERDF along with contaminated soil. No spent nuclear fuel or other anomalous material (e.g., containers or stained soils) or indications of previous spills or releases were discovered at the waste site.

Code: 118-H-3	Classification: Accepted
Names: 118-H-3; Construction Burial Ground	Reclassification: Interim Closed Out (6/27/2011)
Type: Burial Ground	Start Date: 1/1/1953
Status: Inactive	End Date: 1/1/1957

Description: This site has been remediated and Interim Closed Out. The site was an uneven polygon with sides measuring approximately 30 by 114 by 95 by 122 meters (100 by 375 by 313 by 400 feet). It ran in a northeast to southwest direction and was permanently marked with concrete posts numbered H-81-1 through H-81-13. The trenches had been covered to grade with 1.8 meters (6 feet) of soil. Based on the results of the applicable cleanup verification package (CVP) document, authorization was given to remove the Soil Contamination Area and Underground Radioactive Material Area postings from this waste site.

Location: The site was located southeast of the 105-H Building.

Process Description: The burial ground received components and hardware from reactor modification programs.

The site operated from 1953 to 1957 to receive approximately 3,000 cubic meters (3,924 cubic yards) of reactor components and hardware, including contaminated 41 cm (16 inch) diameter pipes that were used as chutes that received the reactor vertical safety rod thimbles and other components removed from reactor modification programs. Originally, two northern trenches were used mostly for the disposal waste into the chute pipes. A third trench, south of the original two trenches, was developed later as a disposal site for large reactor components and hardware.

Waste Type: Equipment

Waste Description: The site contains sections of contaminated 41-centimeter (16-inch) diameter pipe used as chutes for removal of thimbles from the 105-H Building during outages, reactor hardware, and components from reactor modification programs. The COCs identified through process knowledge are listed in the 100 Area Remedial Action Sampling and Analysis Plan and are: cobalt-60, cesium-137, europium-152, europium-154, strontium-90, uranium-233/234, and uranium-238.

Closure Info: Interim: Remedial action at the 118-H-3, Construction Burial Ground waste site began on March 4, 2009. The excavation of the waste site continued through April 22, 2009, to a depth of approximately 4.6 to 5.5 meters (15 to 18 ft), resulting in a total 6,384 bank cubic meters (BCM) (8,350 bank cubic yards [BCY]) of debris and soil removed for disposal at the ERDF. All material removed from within the trenches was taken to sorting cells for surveying and unloading. Large metal and reactor hardware components excavated from trench A were stockpiled in a waste staging area on the east side of the trench. These metal sections were

staged for size reduction prior to shipment for disposal. After size reduction was completed on May 18, 2009, the metal debris and an additional 0.3 meter (1 ft) layer of underlying soil (approximately 60 BCM [75 BCY]) within the waste staging area footprint was removed.

The debris from the 118-H-3, Construction Burial Ground consisted mostly of metal components and very large pieces of reactor hardware (pipes, elbows, etc.). Trench C also contained aluminum tubing. No areas of stained soil or anomalous soil material were identified during the excavation. The waste removed from the trenches was consistent with the types of material expected to be present in this burial ground site.

On March 17, 2009, a suspected flammable gas cylinder, believed to be propane, was discovered. This cylinder was approximately 1.2 meters (4 ft) tall and 51 cm (20 in.) in diameter. It was located in the southeastern part of trench A, at Washington State Plane coordinates N152204.8/E 577837.2. No leakage or soil discolored was observed. The cylinder appeared rusted with blue/gray oxidation on the outlet female valve and the circular valve handle. On May 19, 2009, the cylinder was inspected and found to be empty. Following inspection, the cylinder was reduced in size and shipped to ERDF. No other anomalous material was discovered during the excavation.

Code:	118-H-4	Classification:	Accepted
Names:	118-H-4; Ball 3X Burial Ground	Reclassification	Interim Closed Out (12/29/2010)
Type:	Burial Ground	Start Date:	1/1/1953
Status:	Inactive	End Date:	1/1/1953

Description: The waste site has been remediated and Interim Closed Out. It consisted of one trench running north-south. Concrete markers marked the north and south ends. The trench was covered to grade with approximately 1.5 meters (5 feet) of soil.

Location: The site was located directly west of the 105-H Building, within the 105-H exclusion area fence.

Process Description: This site received solid waste from the Ball 3X Project in 1953. The 118-H-4 Burial Ground was a solid waste site that operated in 1953 to receive thimbles, guides, and radioactive materials removed from the 105-H Reactor during installation of the 105-H Ball 3X System. The Ball 3X project replaced the original liquid boron system for emergency reactor shutdown with a system using solid, nickel-plated, boron-steel, and carbon-steel balls.

Waste Type: Equipment

Waste Description: The site contains thimbles, guides, and radioactive materials removed from the 100-H Reactor in 1953.

Closure Info: Interim (12/29/2010): Remedial action began on November 4, 2008, and continued through April 14, 2009 to an approximate depth of 4.5 m (14.8 ft), resulting in approximately 1,600 bank cubic meters (BCM) (2,100 bank cubic yards [BCY]) of soil and debris that were removed for disposal at ERDF. Additional material was removed on May 4, 2010, because verification sample results indicated residual contamination exceeding direct exposure RAGs was present at two statistical sample locations. A total of approximately 48 BCM (63 BCY) were removed from the SZ-9 and SZ-10 sample locations and disposed at ERDF. For verification sampling, the site was divided into two decision units: the burial ground excavation and the waste staging area footprints. Both statistical sampling design and focused sampling was utilized.

Two potentially lead filled cylinders and one carbon steel canister with two metal tubes extending from it were removed from the excavation and staged. It was determined that cylinder was empty and the canister was lead lined, but empty.

Code: 118-H-5	Classification: Accepted
Names: 118-H-5; 105-H Thimble Pit	Reclassification Interim Closed Out (1/5/2010)
Type: Burial Ground	Start Date: 1/1/1953
Status: Inactive	End Date: 1/1/1960

Description: The 118-H-5, 105-H Thimble Pit has been remediated and Interim Closed Out. It was a mixed solid waste burial ground that operated in 1953 to receive a single experimental thimble assembly. It was reopened in 1960 to receive contaminated soil from the original 105-H Pluto Crib Site (116-H-4 waste site). The 105-H Pluto Crib received contaminated cooling water from reactor process tubes containing ruptured fuel elements. Based on the results contained in the cleanup verification package (CVP-2009-00009) document, authorization was given to remove the Soil Contamination Area and Underground Radioactive Material Area postings from this waste site.

Location: The site was located south of the 105-H Building, within the 105-H exclusion area fence.

Related Sites/ Structures: The site is associated with 100-H-39.

Process Description: This site received a single experimental thimble assembly in 1953 and contaminated soil from the 105-H pluto crib in 1960.

Waste Type: Equipment

Waste Description: The site contains a thimble assembly from the B Experimental Hole, 105-H X-level, buried in 1953. In 1960, the 105 Pluto Crib (116-H-4) was excavated due to the construction of the 105-H Confinement System and placed in this site.

Closure Info: Interim (1/5/2010): Remedial action at the 118-H-5, 105-H Thimble Pit waste site began on September 11, 2008 to excavate and expose the single thimble and any other waste buried at the site. Remedial action at the site involved removing contaminated soil and a single thimble for disposal to ERDF. The excavated material was maintained within the waste site footprint; therefore, no staging piles were generated outside of the remediation footprint. After the thimble was located, all material was returned to the excavation until load out began on November 10, 2008. The excavation of the waste site continued through November 12, 2008 to a depth of approximately 3.5 meters (11.5 ft), resulting in approximately 400 bank cubic meters (BCM) (523 bank cubic yards [BCY]) of contaminated soil and debris removed for disposal to the ERDF.

Code: 128-H-1	Classification: Accepted
Names: 128-H-1; 100-H Burning Pit; 100-H Burning Pit No. 1	Reclassification Interim Closed Out (5/8/2012)
Type: Burn Pit	Start Date: 1/1/1949
Status: Inactive	End Date: 1/1/1965

Description: The waste site has been remediated and Interim Closed Out. It was in a large natural depression that appeared to have been a borrow area. It contained scattered surface debris including wood, glass, metal, wire, cable, and clay pipe. There were also fragments of charred material, scattered concrete and metal. The majority of the surface debris was found between a berm and the eastern edge of the site. Some debris appeared to be solvent, spray paint cans, transite and large pieces of metal on wooden pallets. During remediation, a steel pipeline was found running north to south through the burn pit. It was determined to be part of the 100-H-51:5 pipelines. In

2009, the 100-H-56 water line was also found within the burn pit.

Location: The 128-H-1 waste site was located in a large natural depression approximately 15 meters (50 ft) east of the west perimeter road and north of the 126-H-1 ash pit.

Process Description: The site was used for the disposal of nonradioactive, combustible materials, such as paint waste, office waste, and chemical solvents. The 128-H-1, 100-H Burning Pit was an inactive, nonradioactive hazardous solid waste site that operated from 1949 through 1965. It was the primary burn pit for the 100-H Area and was located in a large natural depression. The site was reportedly used for the disposal of nonradioactive combustible materials such as paint waste, office waste, and chemical solvents. Waste oil containing polychlorinated biphenyls (PCBs) may have been disposed here. Old signs were posted at the site that read "Warning, Do Not Deposit Salvable Material".

Waste Type: Misc. Trash and Debris

Waste Description: The site was used for the disposal of nonradioactive, combustible materials, such as paint waste, office waste, and chemical solvents. The burning of solvents and experimental burns have been reported, by a past 100-H Area employee, to have taken place along the east side of the site.

Closure Info: Interim (5/8/2012): Remediation of the 128-H-1 waste site was performed from June 23, 2009, through May 25, 2011. Approximately 16,310 bank cubic meters (21,333 bank cubic yards) of debris (e.g., wood, concrete, glass, ash, and batteries) plus contaminated soil was removed, stockpiled onsite, and later disposed at the Environmental Restoration Disposal Facility. Following remediation, verification sampling was conducted in June 2010. Results showed that six sample locations within the burn pit excavation area and one sample in the soil stockpile area exceeded cleanup criteria for various contaminants. As a result, from April 11 through May 26, 2011, additional remedial excavation was performed to remove contaminated soils in the burn pit excavation and stockpile sample locations. On May 26, 2011, additional samples were collected from the entire burn pit excavation and the new waste staging pile area using a new sample design. On June 16, 2011, a sample was also taken from the original failed location of the stockpile area. These results indicated that, following the additional remediation, residual contaminant concentrations met the remedial action objectives (RAOs) and remedial action goals (RAGs) for the 128-H-1 waste site.

Previous to the Manhattan Project, several orchards existed on the Hanford Site in the 100 Area. Prior to performing remediation, 0.3 meters (1 ft) of topsoil was scraped from this area and staged for post-remediation reuse. It was subsequently determined that surface soil scraped from this area contained arsenic and lead due to historic pesticide use because the waste staging area footprint was located in a historic orchard area. As agreed to by the Tri-Parties (Tri-Party Agreement Change Notice TPA CN 401 [DOE-RL 2010]), lead and arsenic contamination that resulted from pesticide use before the Manhattan Project are excluded as COPCs and will be discussed in a future Comprehensive Environmental Response, Compensation, and Liability Act of 1980 (CERCLA) document.

Excavation of the burn pit area began in early July 2009 and proceeded to a maximum depth of approximately 7 meters (23 ft). Prior to remediation, a test pit was excavated in the burn pit area to a depth of 2.5 meters (8 ft). Batteries, glass, concrete, wood, ash associated with burning, and a blue-green material were found in the burn area.

Code: 128-H-2	Classification: Accepted
Names: 128-H-2; 100-H Burning Ground #2	Reclassification: Interim No Action (1/25/2010)
Type: Burn Pit	Start Date:
Status: Inactive	End Date: 1/1/1965

Description: The site has been evaluated and determined to require No Action. It consisted of a depression and appeared as a graded rocky area with minimal soil. It was originally thought to be a burning ground. During a March 2000 visit, no evidence of burning was found. Although surface debris, including wood, metal cables, cans, lighting fixtures, concrete and a battery had been reported as being present and scattered throughout the site, no surface debris was found during the March 2002 site walk down.

Location: The site is located southwest of the 118-H-1 Burial Ground, west of the southwest corner of the 100-H Area perimeter road. The location of this site was verified by employees who said they had used it.

Waste Type: Misc. Trash and Debris

Waste Description: The site received combustible materials such as vegetation, office waste, paint waste, and chemical solvents.

Closure Info: Interim: Historical photographs show that this site was in the southeast corner of what appears to be an orchard. A cultural resource inspection, performed in 2007, concluded that the trench associated with the 128-H-3 waste site was part of a pre-Hanford Site farm irrigation system and not a burn pit. Confirmatory sampling performed within the waste site mapped boundaries surrounding the cobble field and not within the trench, per agreement with the Washington State Department of Ecology (Ecology) and the U.S. Department of Energy, Richland Operations Office (RL). The site has limited access, deterring its selection as a burn pit site. No debris or waste consistent with burning pits has been found at the site.

A geophysical survey of 128-H-2 was done in August 2004. A geophysical survey of 128-H-3 was done in March 2007. No anomalies were found at 128-H-2. Wire debris was found at 128-H-3 that is similar to wire used in wooden irrigation piping. No anomalies characteristic of buried debris were identified.

Four test pits and one test trench were dug at 128-H-2 and five test pits were excavated at 128-H-3 to evaluate the subsurface soil for evidence of burning activities. Confirmatory sampling from the test pits was conducted on October 27, 2008. Lead was detected at a concentration (94.1 mg/kg) above both the groundwater (10.2 mg/kg) and river protection (10.1 mg/kg) lookup values.

Beyond a few pieces of surface trash consisting of a piece of heavy wire and the lid from a metal can, no debris or evidence of burning was found in the test pits.

Code: 128-H-3	Classification: Accepted
Names: 128-H-3; 100-H Burning Ground #3	Reclassification: Interim No Action (1/25/2010)
Type: Burn Pit	Start Date:
Status: Inactive	End Date:

Description: This site has been evaluated and determined to require No Action. It is a pit that resembles a trench. Dark colored rock is present but was determined by a geologist not to be the result of burning. The pit was almost completely filled with tumbleweeds.

Location: The site is located west of 118-H-1 and north of 128-H-2. The pit is located on a rise above a cobble field.

Waste Type: Ash

Waste Description:

Closure Info: Interim: Historical photographs show that this site was in the southeast corner of what appears to be an orchard. A cultural resource inspection, performed in 2007, concluded that the trench associated with the 128-H-3 waste site was part of a pre-Hanford Site farm irrigation system and not a burn pit. Confirmatory sampling performed within the waste site mapped boundaries surrounding the cobble field and not within the trench, per agreement with the Washington State Department of Ecology (Ecology) and the U.S. Department of Energy, Richland Operations Office (RL). The site has limited access, deterring its selection as a burn pit site. No debris or waste consistent with burning pits has been found at the site.

A geophysical survey of 128-H-2 was done in August 2004. A geophysical survey of 128-H-3 was done in March 2007. No anomalies were found at 128-H-2. Wire debris was found at 128-H-3 that is similar to wire used in wooden irrigation piping. No anomalies characteristic of buried debris were identified.

Four test pits and one test trench were dug at 128-H-2 and five test pits were excavated at 128-H-3 to evaluate the subsurface soil for evidence of burning activities. Confirmatory sampling from the test pits was conducted on October 27, 2008. Lead was detected at a concentration (94.1 mg/kg) above both the groundwater (10.2 mg/kg) and river protection (10.1 mg/kg) lookup values.

Beyond a few pieces of surface trash consisting of a piece of heavy wire and the lid from a metal can, no debris or evidence of burning was found in the test pits.

Code:	132-H-2	Classification:	Accepted
Names:	132-H-2; 117-H Filter Building Site	Reclassification	Interim Closed Out (8/1/2006)
Type:	Burial Ground	Start Date:	1/1/1961
Status:	Inactive	End Date:	1/1/1965
Description:	The site has been remediated and interim closed. The structure had been demolished in-situ in 1984. The site now resembles a gravel parking lot.		
Location:	The site was located southwest of the 118-H-6 (105-H Reactor Building).		
Related Sites/Structures:	The building filtered exhaust air from 118-H-6 (105-H Reactor Building) to the 132-H-1 (116-H Reactor Exhaust Stack).		
Process Description:	The site consisted of a building that housed the filters for the 118-H-6 (105-H Reactor). The building received exhaust fan discharge through an inlet duct from 118-H-6 and discharged the filtered air through a discharge duct and out the 132-H-1 (116-H Stack). The building was a reinforced concrete structure, 10.7 meters (35 feet) high and 90% below grade. The maximum thickness of the walls and floors was 0.6 meter (2 feet), with the majority being 38 centimeters (15 inches) thick. The ducts were made of reinforced concrete with a maximum wall thickness of 46 centimeters (18 inches). The inlet duct was 23.2 meters (76 feet) long and the exhaust duct was 30.8 meters (101 feet) long.		
Waste Type:	Demolition and Inert Waste		
Waste Description:	Total radionuclide inventory in the 117-H Building was estimated to be 0.41 millicuries. The radionuclides comprising this figure are tritium, carbon-14, cobalt-60, cesium-137, strontium-90, europium-154, europium-152, and plutonium-239/240. Of these radionuclides, strontium-90 is the most restrictive in the Allowable Residual Contamination Level (ARCL) calculations.		
Closure Info:	Interim (8/1/2006): Demolition and site grading were completed in October 1984 using conventional heavy equipment, including a crane with a wrecking ball, earth-moving bulldozer, and trucks. Prior to demolition, the building roof covers and selected metal floor gratings were		

surveyed and found to be free of contamination. They were then removed and the 117-H Building floors were perforated to allow for drainage. The ground above the ducts was excavated, then the exposed duct roofs were demolished. The ducts and the 117-H Building were filled to grade level with the demolished concrete and clean fill from nearby sources on the Hanford Site. A portion of the demolition rubble was left in place and covered with least 1 meter (3.3 ft) of clean fill. The rubble from the seal pits was buried under at least 5 meters (16 ft) of clean fill. The site leveled and graded to blend with the surrounding terrain. As part of decommissioning activities, extensive radiological surveying and sampling activities were performed to characterize residual radiological contamination on the accessible internal surface areas of the 117-H Filter Building. Characterization results indicated that residual contamination was confined to the 1 millimeter (0.04 inch) vinyl paint layer. An evaluation of the concrete beneath the paint showed that the contamination did not penetrate the paint or absorb into the concrete.

The residual contamination occurred within a thin surface layer of paint on the interior surfaces of the building. It was determined that it is unlikely any contamination would be detected in the deep zone rubble resulting from demolition of the building. Additional excavation of the waste site to collect more information (i.e., samples) was not likely to result in a change to the Interim Closed Out decision for the 132-H-2 site.

The contaminated material was transported to the 200 Area for disposal.

The site was released for unrestricted use based on the ARCL Calculations for Decommissioning the 117-H Filter Building. The allowable residual contamination level (ARCL) calculation indicated that the demolished facility would contribute less than 1 millirem/year dose to a hypothetical, maximally-exposed site resident if the site was released for unrestricted use after the demolition and burial in situ of the facility. Consequently, demolition and site grading were performed in 1984 using conventional heavy equipment. The rubble was buried under at least 1 meter (3.3 feet) of clean fill, and the site was graded to blend with the natural terrain.

Using the maximum radiological activities from the pre-demolition characterization data to represent residual contamination levels over 100% of the paint and concrete surface of the former building, RESidual RADioactivity (RESRAD) modeling was performed in 2006 to support the previous decision to demolish and bury the building in place. The RESRAD modeling accounts for radioactive decay from 1984 (year of sampling) to 2006 and predicts that the site achieves the dose limits and risk objectives for rural residential land use with institutional controls, groundwater protection, and river protection.

Code: 1607-H1	Classification: Accepted
Names: 1607-H1; 1607-H1 Sanitary Sewer System; 1607-H1 Septic Tank; 1607-H1 Septic Tank and Associated Drain Field; 124-H-1	Reclassification: Interim Closed Out (9/1/2011)
Type: Septic Tank	Start Date: 1/1/1948
Status: Inactive	End Date:
Description: This waste site has been remediated. The 1607-H1 septic tank system was a nonhazardous, nonradioactive liquid waste site that began operation in 1948, and received sanitary sewage from the 105-H Reactor Building and the 151-H Primary Substation. The sanitary wastes from these buildings were conveyed to the 1607-H1 septic tank system via buried vitrified clay pipes (VCPs). These pipes are planned for remediation as the 100-H-28:4, 1607-H1 Sanitary Sewers waste site. The 1607-H1 drain field measured 17.1 by 15.2 m (56 by 50 ft) and was oriented on a northeast-southwest line from the tank. The at-grade portion of the septic tank was a concrete	

pad with two manhole covers and a third manhole cover located adjacent to the tank, which was clearly visible at the site in a photograph taken on September 30, 2009. In 1985, the 1607-H1 septic system was reactivated to be used by service trailers supporting deactivation and decommissioning (D&D) project personnel. At that time, the tank was discovered to have been backfilled with fly ash. The ash was vacuumed out of the septic tank and disposed to the ground surface prior to the successful reactivation of the septic system. No other records were located documenting the backfilling of the septic tank. During an interview with a former employee it was stated that it was common practice for showers and sinks in the 100-H Area change rooms to be used for personnel decontamination, and these drains lead to the sanitary sewers not the process sewers. In January 2007, the 1607-H1 waste site was assigned for remove, treat, and dispose in the interoffice memorandum "1607-H1 Remaining Site for Remedial Action". The septic tank has a 50-person capacity, is constructed of concrete and measures 4.6 by 1.7 by 4.4 meter (15 by 5.5 by 14.5 feet).

Location: The 1607-H1 waste site was located southwest of the 105-H Reactor Building and the 151-H Primary Substation, near the 118-H-2 Burial Ground, in the 100-HR-2 Operable Unit.

Related Sites/ Structures: The septic system is associated with the 105-H Reactor and the 151-H substation.

Waste Type: Sanitary Sewage

Waste Description: This unit received sanitary sewage from 151-H and 105-H Buildings. The flow rate to this unit was estimated to be 503 liters/day (140 gallons/day).

Waste Type: Not Specified

Waste Description: The waste included carbon steel pipes and drainage tiles/pipe from the area of the septic tank inlet, from the drain field, and concrete/brick from the septic tank and adjacent manhole structure, including all soils excavated from below the drain field piping.

Closure Info: Interim: Remedial action at the 1607-H1 waste site was performed between September 24 and November 2, 2009, and included the removal of the below-grade septic tank and the manhole cover surface features. Excavation continued until all debris and contamination associated with the septic tank, drain field pipes, and connecting pipeline structure had been removed. The site was excavated to a depth of approximately 3.2 m (10.5 ft), removing the drain and tile field pipes at approximately 2.5 m (8.2 ft) below surface grade, and to a depth of approximately 4 m (13 ft) at the septic tank and adjacent manhole structure. A total of approximately 1,166 bank cubic meters (BCM) (1,525 bank cubic yards [BCY]) of soil and debris were removed and directly loaded for disposal at the Environmental Restoration Disposal Facility, including all soils excavated from below the drain field piping. This debris included carbon steel pipes and drainage tiles/pipe from the area of the septic tank inlet and the drain field, and concrete/brick from the septic tank and adjacent manhole structure.

An additional 528 BCM (691 BCY) of soil was removed from outside of the septic tank and overlying the drain field to form the overburden pile for the 1607-H1 waste site. The 1607-H1 remediation design identified the separation of overburden soil from the 1607-H1 drain field into two separate soil stockpiles. This overburden soil was intended to be used as backfill after it had been sampled, analyzed, and determined to meet cleanup criteria.

Code: 600-151

Classification: Accepted

Names: 600-151; Dumping Areas 50 Yards and 200 Yards Downstream of River Mile 14; Military Installation NW of 100H Area

Reclassification: Interim Closed Out (10/27/2011)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site has been remediated and Interim Closed Out. It was the debris remaining from a military installation that was located northwest of the 100H Area. A paved road entered the site from the southwest.

The 600-151 waste site consisted of scattered debris from U.S. Army Base Camp 130 (BC-130), a military camp covering approximately 162,000 square meters (40 acres) near the Columbia River, which was occupied from approximately 1950 to 1954. Debris found throughout the area in 1996 included a partially buried washtub, tin cans, a stove pipe, empty fuel and solvent cans painted "army green", broken concrete and transite, an old stove, wire fencing material, and a large pile of steel fence posts (screw in type for barbed wire fencing). There was evidence of ground disturbance at the site including three pits. A vertical culvert was observed at grade level extending into the ground. The culvert interior was obscured due to the presence of tumbleweeds. Several areas of stressed vegetation were also observed in the area. The 600-151 waste site is located within this historic-archaeological site and contains the remnants of a farmstead (and orchards) intentionally demolished by Hanford-related activities. In 2009, prior to field remediation, were some domestic military debris, several pits (some with wood lining), and shallow trenches, related to communication lines, were documented.

Location: The site was located northwest of 105-H Reactor and begins 0.3 kilometers (0.2 miles) downstream of river mile post 14. The site has dirt and paved roads which form its boundary. A paved road enters the site from the southwest.

Waste Type: Equipment

Waste Description: A large pile of steel fence posts was observed at the site.

Waste Type: Soil

Waste Description: Several areas of stressed vegetation were found at the site.

Waste Type: Demolition and Inert Waste

Waste Description: A large pile of broken concrete, electrical wiring, piping and pieces of wood was observed at the site.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: One 208 liter (55 gallon) drum, several 19 liter (5 gallon) cans, and several 0.95 liter (1 quart) cans were noted at the site. The 19 liter (5 gallon) containers appeared to be the type that would hold fuel such as gasoline or kerosene. Empty paint cans that contained "army green" paint are also present.

Closure Info: Interim (10/27/2011): Prior to use by the Hanford Site Manhattan Project, the 600-151 waste site location was part of an historic agricultural site occupying some 202,000 square meters (50 acres) consisting of five tracts of land used circa 1938 to 1943. During the growing season, orchards were sprayed with lead arsenate from the time the trees bloomed until they were harvested. During remediation, a pattern of circular shaped, stained soil areas was noted beyond the areas identified for remediation in the remedial design. Field personnel suspected that these areas might be associated with historic agricultural pesticide applications and were not from Hanford waste disposal activities. In-process soil samples, collected to support waste characterization, identified high concentrations of arsenic (up to 229 mg/kg) and lead (up to 1,750 mg/kg) suspected to be associated with historic agriculture lead arsenate pesticide use.

Remediation of the 600-151 waste site consisted of mechanical excavation of concentrated debris and manually removing scattered debris from the ground surface as identified in the

remediation design drawings. Areas of stained soil and stressed vegetation were scraped and removed to a minimum depth of 0.31 meters (1 ft). In addition, two water valves and a water box associated with the former septic system (the 600-152 waste site) were also removed.

Code: 600-152	Classification: Accepted
Names: 600-152; Military Septic Tanks	Reclassification: Interim Closed Out (4/1/2010)
Type: Septic Tank	Start Date:
Status: Inactive	End Date:
Description: The waste site has been remediated. It consisted of an underground septic tank and several surface features, including three in-line concrete covers and two manholes, which allowed access to the septic tank. Underground piping connected the surface features and the septic tank.	
Location: The site is located northwest of 105-H Reactor and begins 0.2 miles downstream of river mile post 14. The site has dirt and paved roads which form a boundary surrounding the site. A paved road enters the site from the southwest.	
Process Description: The site was constructed to support a military base camp that was created as part of Camp Hanford, which supported the established air defense systems at the camp. Base Camp 130 was located in the vicinity of the 600-151 dumping areas waste site and was abandoned by 1954. In October 2001, liquid in the septic tank was sampled. Results from the sample, described as rainwater, showed elevated gross beta results. No other radionuclides were detected in the analyses. Based on this result, the site was posted with Underground Radioactive Material signs.	
Waste Type: Sanitary Sewage	
Waste Description: The tanks remain in place and may contain remnants of septage. The contents are labeled radioactive here because sampling showed gross beta at 72 pCi/liter (see field work discussion for comparisons with Hanford Site background). The site was posted with Underground Radioactive Material signs.	
Closure Info: Interim (4/1/2010): In October 2001, liquid in the septic tank was sampled. Results from the sample, described as rainwater, showed elevated gross beta results (72 pCi/l). No other radionuclides were detected in the analyses. Based on this result, the site was posted with Underground Radioactive Material signs. Prior to remediation in 2008, a visual inspection of the septic tank interior was conducted. No liquid was observed in the tank at that time. The fate of the liquid that was seen in 2001 is unknown, but it is possible that the liquid had evaporated.	

Remedial action at the 600-152 waste site was performed between October 13 and November 10, 2008, and encompassed the removal of the below-grade septic tank, the surface features (three concrete covers and two manholes), and associated soils. The concrete piping that linked the septic tank to these surface features was also removed. A section of cast iron pipe containing seals made of lead was removed from the waste site. The lead-containing material was containerized after removal from the excavation. The site was excavated up to 5 meters (16 ft) below grade, resulting in the removal of approximately 287 BCM (375 BCY) of material for disposal at the Environmental Restoration Disposal Facility, including approximately 140 meters (460 ft) of pipe. Approximately 1,584 BCM (2,070 BCY) of soil (overburden) was removed and stockpiled for evaluation as clean backfill.

There is no process history to suggest that radiological contamination was present in the 600-152 septic tank. The in-process sample results from the tank contents (J17R76) did not detect radiological contamination; however, an elevated gross beta result from a water sample collected within the tank was reported in 2001. The beta emitter that is of most concern associated with this detection is strontium-90; therefore, strontium-90 was added as a COPC.

Site contamination extended slightly into the deep zone soils, however, the remediation footprint was evaluated against the more restrictive shallow zone criteria. The sample results demonstrated that residual contaminant concentrations support unrestricted future use of shallow zone soil (i.e., surface to 4.6 meters [15 ft]) and contaminant levels remaining in the soil were protective of groundwater and the Columbia River. Therefore, institutional controls to prevent uncontrolled drilling or excavation into the deep-zone are not required.

100-IU-1

Code: 600-44 **Classification:** Accepted
Names: 600-44; 600-68; Enyert Well Empty Pesticide Container Dump; Herbicide/Pesticide Empty Container Pile **Reclassification** Deleted From NPL (7/8/1998)
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The waste site was remediated in 1992 and Deleted from the NPL in 1998. During the Riverland Expedited Response Action, a visual inspection of the area found several empty aldrin and dieldrin herbicide/pesticide containers lying on the surface. The containers were rusty five gallon and one gallon cans covering an area of approximately 20.90 meters squared (225 square feet). The condition of the containers suggested that they were placed there after Hanford operations began. However, the site is located on an old abandoned homestead about 150 meters (500 feet) east of the commercial vineyard on the west side of the cold Creek Road.

Location: The site was located approximately 150 meters (500 feet) east of the commercial vineyard on the west side of Cold Creek Road. The site is on relatively flat ground located within an abandoned homestead site. There is a perimeter access road located approximately 50 feet west of the site. (at NW 1/4 of NW 1/4 of NW 1/4 of Section 26, T13N R24E).

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: The site waste includes empty pesticide and herbicide containers, and debris piles from the homestead.

Closure Info: Final: The containers were removed from the area and properly disposed of as part of the Riverland Expedited Response Action in 1992. In addition, six old batteries north and east of the excavation were removed. The underlying soil showed detected only zinc.

An area 2.1 meters by 5.5 meters (7 by 18 feet) was excavated to a maximum depth of 0.76 meters (30 inches)

Fifteen crushed pesticide containers and twenty five 55 gallon drums of contaminated soil were disposed of at the Hanford Central Landfill (DOE/RL-2002-074).

Code: 600-101 **Classification:** Accepted
Names: 600-101; Riverland Railroad Car Wash Pit; RRCWP **Reclassification** Deleted From NPL (7/8/1998)
Type: Depression/Pit (nonspecific) **Start Date:** 1/1/1945
Status: Inactive **End Date:** 1/1/1963

Description: The waste site has been remediated and Deleted from the National Priority List. During the Expedited Response Action cleanup activities, the site resembled a concrete trench. Excavations were made to uncover the pits for sampling. The rail road car cleaning pits were about 1 meter (3 feet) deep and 2 meters (6 feet) wide. Following remediation activities, the pits were backfilled to grade.

Location: The site is approximately 0.8 kilometers (0.5 miles) west of State Highway 240 and 0.5 kilometers (0.3 miles) southwest of the Vernita Bridge.

Process Description: The Riverland Rail Yard Maintenance Facility (Building 6718) steam cleaned and decontaminated railroad cars of grease and radioactive contamination in two pits prior to service and maintenance activities. The decontamination removed grease and oil from the undercarriage, wheels, axles and brakes. Diesel locomotives had their engine compartment, radiators and fans cleaned. Low levels of radioactive contamination was removed. Radioactively contaminated pads, gloves and other wastes were sent to the 200 Area for disposal. Periodically, the pit floor and walls were cleaned with a broom soaked in diesel fuel, then rinsed with water. Decontamination solutions drained into floor drains which then drained to an open ditch on the north side. The facility operated from 1943 until 1956. The facility was decontaminated in 1963 and the facility structures were sold to the public.

Waste Type: Water

Waste Description: The site was used as a steam cleaning and low-level decontamination station for locomotive engines and cars used at Hanford.

Closure Info: Final: In 1992 and 1993, the Riverland Expedited Response Action characterized and cleaned up the site. About 260 cubic meters (340 cubic yards) of concrete and fill material was removed from the wash pits and recycled through a concrete recycling plant. In the 100-B/C Area, and 330 cubic meters (430 cubic yards) of diesel contaminated soil were sent off site for bioremediation.

Radiological surveys did not identify any levels above background. Small quantities of man-made radionuclides were observed in pre-remediation sampling. (A maximum of 19.6 picocuries per gram of cesium-137.) However, based on the levels observed the operable unit was considered nonradioactive. The cleanup level for diesel fuel residue was 200 parts per million (ppm); the confirmatory sample results showed less than 2 ppm remaining. The confirmatory samples also showed all man-made radionuclides were below 1 picocurie per gram.

About 330 cubic meters (430 cubic yards) of diesel contaminated soil and vitrified clay drain pipe fragments were removed. The diesel contaminated soil was bioremediated by "land farming" in the 100-C Area, and declared completed in 1996. The pits were backfilled with clean material from onsite. No further action was required for this site following the ERA and subsequent ROD. On July 8, 1998 the site was deleted from the NPL.

Code: 600-102	Classification: Accepted
Names: 600-102; 600 AMBS; 600 Area Army Munitions Burial Site	Reclassification: Deleted From NPL (7/8/1998)
Type: Burial Ground	Start Date: 1/1/1971
Status: Inactive	End Date: 1/1/1976

Description: The site has been remediated and Deleted from the National Priority List. It consisted of a shallow excavation area that contained a buried wooden crate. The crate contained emergency supplies of explosives and munitions used for military exercises during the 1970's (Smith & Stanley, 1993). The excavated area was approximately 0.61 meters (2 feet) wide by 0.91 meters (3 feet) long. The explosives were removed in 1986. The excavation was backfilled in 1993.

Location: The site is located northwest of 200 West area, approximately 100 meters west of Gate 12, near the McGee Ranch.

Waste Type: Ordnance

Waste Description: The unit received military explosives as follows: 6 gun blast simulators, Model 110, dated October 1953; 78 boxes (packed 5 to a box) of fuse ignitors; Model M60, Lot KYC-1, dated

May 1960; one trip flare, Model M49; one can containing 50 nonelectrical blasting caps, marked "ARMY"; 43 electrical blasting caps; ~500 ft of time fuse; ~200 ft of detonating cord; and remnants of one grenade or artillery simulator.

Closure Info: Final: On May 22, 1986, the box and its contents were removed and transported to the Yakima Firing Range for destruction. The crate contained six gun blast simulators, seventy eight fuse ignitors, one can of non-electric blasting caps, 43 electrical blasting caps, 500 ft of time fuse, 200 ft of detonating cord and the remnants of one grenade. The excavation was 0.61 meters (2 ft) by 0.91 meters (3 ft). The excavation was backfilled.

Code: 600-274	Classification: Accepted
Names: 600-274; Riverland; 2,4-D Can Site at McGee Ranch	Reclassification: Deleted From NPL (7/8/1998)
Type: Dumping Area	Start Date:
Status: Inactive	End Date: 1/1/1994

Description: The 2,4-D can site is surrounded by old-growth sagebrush with a cheatgrass understory. As it is near the far western border of the Hanford Site, there are no Hanford facilities nearby. Eleven 5-gallon cans were found here, nine of which were buried upright and adjacent to each other, with only their tops showing. Two other cans were on top of the ground nearby. The cans were removed and the soil sampled in 1994 as part of the closeout of the 100-IU-1 Operable Unit. In addition, while the original site was being located with the GPS coordinates in 2001, three other 5-gallon cans were found due north of the site about 100 meters (100 yards), also in sagebrush. This site was also GPS'd and flagged with white tape. All cans have been removed.

Location: The site is about 300 meters (300 yards) north of Highway 24, and 3.2 kilometers (2 miles) west of the Yakima Barricade.

Related Sites/ Structures: It is not apparent who placed the cans at this site, or if they were associated with Hanford operations or a nearby farm.

Process Description: The material in the eleven cans removed in 1994 was 2,4-D, an herbicide. The three cans discovered in 2001 were empty and unmarked.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: The site was 11 old herbicide cans (2,4-D) that had some soil and liquid (in one can) remaining.

Closure Info: Final: The original eleven cans were removed in 1994. One container was laying on the surface, intact, no legible markings. A second container lying on the surface had mostly rusted away. Nine other containers were buried in two adjacent rows. The containers had open bung holes. One container had liquid inside. The other containers had varying amounts of soil inside.

Two composite samples were taken from the soil within the cans and one liquid (with one duplicate) sample. The liquid samples used up all the remaining liquid in the drum. After the cans were dug out of the hole, samples of the remaining soil immediately below the cans, and at 1, 2 and 3 foot depths were taken in three locations.

One of the samplers who was present in 1994, was interviewed in 2001. He said that, based on standard operating procedure, any soil from within the cans would have been placed in the 55-gallon drums, especially if there was an odor of herbicide (as the logbook reports). He also said that the excavation would not have been filled back in, but kept open pending receipt of the sampling results. If the results had indicated a problem, they could have gone back to excavate

further and re-sample. Since the reports concluded there was no problem with the levels remaining at the site, they would not have gone back to the site. He believes the site may still be visible as a depression.

The three remaining drums, located about 100 meters north of the original eleven drums, were removed and disposed of in December 2002. Site personnel determined that these drums were empty and not a RCRA concern. Due to the remote location of the site, it is considered a "Category 1" radioactive area which allows for landfill disposal.

100-IU-2

Code: 600-5 **Classification:** Accepted
Names: 600-5; Asphalt Heliport; White Bluffs Waste Oil Dump **Reclassification** Interim Closed Out (2/1/2011)
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The site has been remediated and Interim Closed Out. It was a non-vegetated area containing two areas of asphalt or heavy oil staining, as well as metal debris and piping. The asphalt or heavy oil material did not appear to contain gravel, and thus was not indicative of a roadway surface. The northwestern corner of the waste site contains household debris on the surface, which was determined to be nonhazardous material and was not removed. The terrain at the waste site is flat and measures approximately 72 meters (240 ft) in length and width. The surface is covered with scattered sagebrush in the southern portion.

Location: The site is located approximately 64 meters (70 yards) south of the gravel road leading to the 100F Reactor, and is located just northwest of mile marker 7. The 600-5 waste site was located approximately 64 meters (210 ft) south of the gravel road that leads to the 105-F Reactor Building.

Waste Type: Oil

Waste Description: The site contains an asphalt or a heavy oil type substance.

Closure Info: Interim: Remediation to remove the two areas of asphalt and tar-like material occurred on February 11, 2010, and resulted in one excavated area. The total depth of the scraped area was approximately 0.3 meter (1 ft). The waste material and soil was placed in a staging pile before being taken to ERDF. The vadose zone beneath the excavation is approximately 7.5 meters (24.6 ft) thick.

Code: 600-52 **Classification:** Accepted
Names: 600-52; White Bluffs Surface Basin **Reclassification** Interim No Action (11/20/2003)
Type: Drain/Tile Field **Start Date:**
Status: Inactive **End Date:**

Description: The site has been evaluated and determined require No Action. The site was a depression containing concrete and demolition debris.

Location: The site was located south of Federal Avenue and west of Route 2 North. It was southeast of the White Bluffs Pickling Acid Cribs (600-106), on the opposite side of a powerline road.

Related Sites/ Structures: 600-106 Pickling Acid Crib

Process Description: A 1948 aerial photograph showed a ditch leading from the ice house waste water drain field to the 600-52 basin. It appeared that the southeast corner of the Pickling Acid Crib (600-106) washed out onto this basin. Three soil samples from this unit were collected during the White Bluffs Pickling Acid Cribs Environmental Risk Assessment (ERA) characterization conducted November and December 1992. Sample data may be found in the source document DOE/RL-93-48.

Waste Type: Process Effluent

Waste Description: Nitric and hydrofluoric acids were discharged to the nearby Pickling Acid cribs. Sampling indicated slightly elevated levels of chrome and chloride when compared to background samples. Generally, the acid was neutralized prior to disposal, but may not have been completely neutralized prior to disposal.

Closure Info: Interim (11/20/2003): This site was assumed to be associated with the Pickling Acid Cribs (sitecode 600-106). The Pickling Acid Cribs were characterized in 1992. Samples were also collected at three locations in the surface basin in 1992. A field walkdown done in April 2003 revealed no debris or anomalies. It was determined that no additional samples would be required.

Code: 600-98

Classification: Accepted

Names: 600-98; East White Bluffs City Landfills; East White Bluffs Dump and East White Bluffs Dump #2; East White Bluffs Landfill; EWBCL

Reclassification: Interim No Action (8/17/2004)

Type: Sanitary Landfill

Start Date:

Status: Inactive

End Date: 1/1/1943

Description: The site has been evaluated and determined to require No Action. It consisted of two, pre Hanford dumping areas. A small amount of scattered surface debris (cans, glass and wood) was visible at dump #1. Dump area #2 was an area of gravel ridges and surface scars.

Location: The dump areas are north of 100-F Area. The East White Bluffs Dump was located approximately 150 meters (492 feet) north of the White Bluffs Ferry Landing. The East White Bluffs Dump #2 was located approximately 275 meters (902 feet) west of the White Bluffs Ferry Landing and north of Federal Avenue.

Process Description: The East White Bluffs Dump reportedly operated from 1850 to 1943. The East White Bluffs Dump #2 operated from 1900 to 1943.

Waste Type: Misc. Trash and Debris

Waste Description: Both sites were used to dispose of industrial and domestic wastes common to the time that it was being used. Surface debris found around the East White Bluffs Dump included cans, glass and wood. Surface debris found the East White Bluffs Dump #2 included wood, metallic, domestic (pots, bowls, and glassware), and industrial debris (cables and plywood sheets). The sites contain no known radioactive constituents.

Closure Info: Interim: A site walkdown was done in June 2004. Scattered surface debris, including glass, cans bricks, wood, wire and nails, was noted. There was no evidence of burning, asbestos or stained soil.

The evaluation of site history reviews, field observations, and geophysical surveys, provided the basis for reclassification of the site to no action.

The 100 Area Remedial Action Sampling and Analysis Plan (SAP) (DOE-RL-96-22, Rev. 4, Draft B) identified contaminants of potential concern (COPCs) for dumping areas. The SAP categorically assumed COPCs associated with disposal of hazardous debris. However, further evaluation of the debris observed at the site during the confirmatory sampling walkdown, indicated the debris to be non-hazardous and disposed of prior to Hanford Operations. Therefore, no further evaluation or confirmatory sampling was necessary for this site.

Code: 600-99 **Classification:** Accepted
Names: 600-99; J. A. Jones #2; JA Jones 2; JA JONES2 **Reclassification** Interim No Action (9/12/2003)
Type: Burial Ground **Start Date:** 1/1/1948
Status: Inactive **End Date:** 1/1/1955

Description: The site has been evaluated and determined to require No Action. It was a previously exhumed, construction debris burial ground.

Location: The site was located northwest of the White Bluffs Townsite, north of H Avenue and east of Route 2.

Waste Type: Construction Debris

Waste Description: This site contained minor construction equipment used by the J. A. Jones Construction Company, including wood scraps, concrete, and some metallic waste. However, the excavation records indicate that the site contents were removed to the 200 Areas Burial Grounds in 1971 because of radioactive contamination in the landfill.

Closure Info: Interim: Historical information indicated the waste site was exhumed in 1971, the contents moved to a 200 Area burial ground and the area was backfilled. A site walkdown was done in April 2003. No debris or anomalies were noted, but a geophysical survey was done to verify no subsurface debris was present. Based on the site history, site walkdown, and GPR evaluation, test pits were dug at the locations of three identified subsurface anomalies on May 20, 2003. These three anomalies were just outside the previously identified boundaries of 600-99, but close enough to be of concern as possible debris left behind from the previous excavation and removal project. Any debris encountered was to be evaluated by the sampler and certified waste shipper and samples taken to support waste designation. Test pits 1 and 3 found no anomalies. Test pit 2 found a concrete foundation, but no debris. The test pits were backfilled the same day they were dug. The results of the field activities demonstrate that there are no materials remaining at the 600-99 site that would exceed the RAGS.

Code: 600-100 **Classification:** Accepted
Names: 600-100; 600-119; WBL; White Bluffs City Dump; White Bluffs City Landfill; White Bluffs Landfill **Reclassification** Interim Closed Out (1/18/2011)
Type: Sanitary Landfill **Start Date:**
Status: Inactive **End Date:** 1/1/1943

Description: The waste site has been remediated and Interim Closed Out. It was believed to be an unlined excavation that received White Bluffs City industrial, commercial, domestic and farm wastes. It has been determined that the waste site was more likely used for opportunistic dumping rather than as a large scale landfill, and that this debris was buried during Hanford-era operations.

Location: The site was located west of Route 2 North and south of Federal Avenue. It is east of the White Bluffs Pickling Acid Cribs (600-106), approximately 540 meters (1,772 feet) south of the intersection of Route 2 North and Federal Avenue.

Related Sites/ Structures: 600-119 is an alias for 600-100 (it is a duplicate entry of this landfill)

Waste Type: Misc. Trash and Debris

Waste Description: The site was used for normal commercial and domestic wastes at the time. It contains no known radioactive constituents. Per BHI-00049, the site was used for disposal of industrial,

commercial, and domestic wastes, cans, bottles, and farm debris.

Closure Info: Interim: For consideration of potentially sensitive archaeological materials at the site, six test trenches were excavated in December 2009. The trench material was brought up in 0.3 meter (1 ft) lifts and sifted by field personnel. The results of the archaeological investigation indicated there was no buried debris or anomalous material. No material from the test trenches was disposed at ERDF and no samples were collected from the test trenches.

Remediation occurred from January 4 to 18, 2010. Because the previous archeological investigation determined buried debris was not present at this site, it was excavated to a depth of only 15 cm (6 in.), to remove surface debris. One 208-L (55-gal) stainless steel container was found while blading the road during remediation. It was unbreached, but partially crushed. Waste characterization and in-process soil samples were collected and analyzed. The surface debris and barrel were disposed at ERDF.

Code: 600-120	Classification: Accepted
Names: 600-120; Spare Parts Burn Pit; White Bluffs Spare Parts Burn Pit	Reclassification: Interim Closed Out (3/16/2011)
Type: Burn Pit	Start Date: 1/1/1943
Status: Inactive	End Date: 1/1/1948

Description: The waste site has been remediated and Interim Closed Out. It was a burn pit that was used for industrial and commercial wastes. The site appeared to have been backfilled with coal ash. Remedial action at the 600-120 waste site was performed from January to March 2010. The remediation resulted in approximately 1 meter (3 ft) of material being scraped from the surface and placed in staging piles adjacent to the waste site prior to being sent to the Environmental Restoration Disposal Facility.

Location: The site was located west of Route 2 North and south of Federal Avenue, under a set of BPA lines. It is north of the exhumed White Bluffs Pickling Acid Cribs (sitecode 600-106).

Related Sites/ Structures: 600-120 is associated with 600-297 because they were co-located and remediated at the same time.

Process Description: White Bluffs Spare Parts Burn Pit waste site appears to have been a burn pit that was used for disposal of industrial and commercial wastes, including flammable wastes, solvents, and waste soils.

Waste Type: Chemicals

Waste Description: The waste was solvents, waste oils, and flammable wastes. The site may have been used to dispose of other solid wastes. The site appears to have been backfilled with coal ash.

Closure Info: Interim (3/16/2011): Remediation of 600-120 and 600-297 occurred from January 7 to March 15, 2010.

On January 7, 2010, several concrete structures associated with the 600-297 Imhoff Tank were encountered during initial remediation. A 10 centimeter (4 inch) diameter vitrified clay pipe was found protruding from each of the concrete structures. During demolition of the concrete structures, a 114 liter (30 gallon) tank was encountered on January 11, 2010. The tank resembled an old boiler and contained a small amount of black, non-oily, non-viscous liquid. A sample (J19WT1) was taken of this liquid on April 14, 2010. The concrete structure was fully removed. The bottom of the structure was at approximately 8 meters (28 feet) below ground surface. The materials that were excavated as a part of this remediation included coal ash and a concrete structure determined to be from the co-located 600-297 White Bluffs Imhoff Tank

waste site. Groundwater was encountered at this location after the 600-297 waste site tank was removed.

600-120 Area 1 was a large depression that appeared to be an abandoned burn pit, backfilled with coal ash. Remedial action at the 600-120 waste site was performed from January to March 2010. Two test trenches were excavated for confirmatory sampling in Area 1. Evidence of vitrified clay pipe, rubber, burned wood, and coal were found. Confirmatory samples collected from the coal ash and native soil locations in Area 1 found that direct exposure remedial action goals (RAGs) were exceeded for benzo(a)pyrene, benzo(b)fluoranthene, chrysene, and indeno(1,2,3-cd)pyrene, indicating that site remediation was required. Barium, copper, and selenium were also present in concentrations exceeding soil cleanup criteria for groundwater or river protection.

600-120 Area 2 was determined to need no remediation.

600-120 Area 3 was identified during the geophysical survey as a depression northeast of Area 1 where buried debris was suspected to be present. One test trench was excavated in Area 3 for confirmatory sampling. Concrete walls, debris, coal ash, apparent rust, and oil stained soil were all observed in this test trench. Confirmatory samples of stained soils showed lead and silver concentrations in excess of direct exposure cleanup RAGs. Herbicides, pesticides, and polychlorinated biphenyls (PCBs) were also present in concentrations exceeding soil cleanup criteria for groundwater or river protection.

Following remediation, verification sampling was conducted in September 2010. The results indicated that the waste removal action achieved compliance with the remedial action objectives (RAOs) and RAGs for the 600-120 and 600-297 waste sites. The results of the verification sampling are used to make reclassification decisions for the 600-120 and 600-297 waste sites in accordance with the TPA-MP-14 procedure. The verification sampling results support a reclassification of this site to Interim Closed Out.

Code: 600-124	Classification: Accepted
Names: 600-124; Burn Site and Paint Disposal Area; White Bluffs Burn Site and Paint Disposal Area	Reclassification: Interim Closed Out (1/27/2011)
Type: Burn Pit	Start Date:
Status: Inactive	End Date:
Description:	The site was remediated and Interim Closed Out. It was a burn area where there is evidence of surface burning and paint disposal. The entire area was littered with burned wood, partly burned roofing materials, glass, nails, metallic debris, transite and isolated paint cans. There was evidence of surface disposal of paint materials in dried paint chips and deposits. There was also a large area with decaying timbers laying in many parallel rows that appeared to be some type of floor structure.
Location:	The site was located south of Federal Avenue and just west of the railroad tracks on the west side of Route 2 North. It was approximately 640 meters (2100 feet) southeast of the intersection of Route 2 North and Federal Avenue.
Waste Type:	Chemicals
Waste Description:	The waste is the remains from paint disposal.
Closure Info:	Interim: Remediation occurred from January 11 to 18, 2010. The excavation extended to a depth of approximately 1 meter (3 ft) bgs. The vadose zone beneath the excavation was

approximately 8.3 meters (27.2 ft) thick. Approximately 1 meter (3 ft) of material was scraped from the surface and disposed at the Environmental Restoration Disposal Facility. Several paint cans containing various colors of paint, tar roofing, wood and vitrified clay piping were encountered during remedial activities.

Code: 600-125 **Classification:** Accepted
Names: 600-125; Waste Disposal Trenches; White Bluffs **Reclassification** Interim Closed Out (2/1/2011)
Waste Disposal Trench 1
Type: Trench **Start Date:**
Status: Inactive **End Date:**

Description: The waste site has been remediated and Interim Closed Out. The site was sandy depression with wood, ceramic and metal debris on the surface.

Location: The site was located west of Route 2 North and south of Federal Avenue. It is approximately 1020 meters (3347 feet) south of the intersection of Route 2 North and Federal Avenue. The site was on the west side of a powerline road.

Waste Type: Misc. Trash and Debris

Waste Description: The waste includes metal shavings, steel piping, plumbing fixtures, paint cans and automotive parts; as well as other metallic and wooden debris. In the same area there are several piles of used railroad ties, broken vitrified clay pipe, concrete pipe, 30.5-centimeter (12-inch) diameter, 6.1-meter (20-foot) long spiral welded pipe, plumbing fixtures, and degraded asbestos insulation.

Closure Info: Interim: The sandy depression contained metal shavings, steel pipe, plumbing fixtures, paint cans, railroad ties, vitrified clay pipe, asbestos insulation and wood debris.

Remediation occurred from February 11 to 17, 2010. The excavated area measured approximately 35 meters (115 ft) across in an irregular shape, and was 0.8 meters (2 ft) deep. The vadose beneath the excavation is approximately 10.6 meters (34.8 ft) thick. The waste material, which included several 12 meter (40 ft) of 12 inch diameter pipes, was staged in an area located southeast of the excavated area prior to being sent to the Environmental Restoration Disposal Facility.

Code: 600-127 **Classification:** Accepted
Names: 600-127; Fuel Storage Area; White Bluffs **Reclassification** Interim Closed Out (4/26/2011)
Loading Docks and Fuel Storage Area
Type: Storage **Start Date:**
Status: Inactive **End Date:**

Description: The site has been remediated and Interim Closed Out. It was two loading docks and a rectangular area surrounded by a low soil berm that measured 0.5 meters (1.6 feet) high. The ground within the berm was covered by a layer of coal ash. The two loading docks, located adjacent to suspect fuel storage areas, were described as the north loading dock and a south loading dock. Each loading dock was approximately 20 meters (66 feet) long by 12 meters (39 feet) wide. A five foot diameter chemical spill area was located west of the north loading dock.

Inside the bermed area were several wooden beams, the tops of which were flush with the ground surface. Wood shims were placed in a manner that suggested they once supported large, round horizontal fuel storage tanks. It appeared that four or five large tanks had been located at

the site. Other small debris piles were located nearby that consisted of broken vitrified clay piping, plumbing fixtures, and concrete piping. On the north side, just outside the berm, was a smaller fuel tank site.

Location: The site is located west of Route 2 North and south of Federal Avenue. It is approximately 1,100 meters (3609 feet) southeast of the intersection of Route 2 north and Federal Avenue. The north loading dock is visible from Route 2 North.

Release Description: Removal of small areas of the ash ground cover reveals soil discoloration and evidence of petroleum product contamination. The soil around the fuel tank site on the north side of the berm is also discolored and appears to be contaminated with a petroleum product, probably gasoline. Adjacent to and on the south side of the berm there appears to have bulk dumping of heavy oils or other petroleum products. The soil contamination in this area extends to the south from the berm for about 4 meters (13 feet). Just west of the north loading dock is a 1.5-meter (4.9-foot) chemical spill spot that appears to consist of a petroleum product.

Waste Type: Oil

Waste Description: The waste is petroleum product contaminated soil.

During remedial activities as documented in RSVP-2004-064, it was observed that the inside of the berm contained coal ash and several wooden beams and shims thought to have once supported large tanks associated with fuel storage. To the west of the north loading dock was a chemical spill spot approximately 1.5 m (5 ft) in diameter, which appeared to consist of a petroleum product (BHI 1995). In addition to these areas, several small debris piles were located in the vicinity, and contained broken vitrified clay piping, plumbing fixtures, and concrete piping. Bulk dumping of petroleum products appeared to have occurred at the waste site.

Closure Info: Interim: Eight test pits and trenches were excavated based on locations identified during a geophysical survey and site walkdown. Five of the test pits (pits 1, 2, 3, 5 and 7) showed no signs of hazardous debris or discolored soil, so no samples were collected. Confirmatory sampling at three locations (pits 4, 6 and 8) had elevated levels of barium, cadmium, copper, lead, zinc, polycyclic aromatic hydrocarbons (PAH), total petroleum hydrocarbons (TPH), and 4,4-DDE and required remediation.

Remedial action at the 600-127 waste site began on January 19, 2010, and was completed on June 7, 2010. The main excavation which encompassed two of the test pit areas was excavated to groundwater (approximately 8.5 meters [28 ft] below ground surface [bgs]) while chasing a plume of diesel or petroleum-product. The north loading dock and adjacent chemical spill spot was excavated to approximately 1 meter (3 ft) bgs, with an adjacent area being scraped to 15 centimeters (6 in.) bgs. Soil and debris were staged in two stages piles prior to disposal at the Environmental Restoration Disposal Facility (ERDF).

Initially, stained soil was observed and removed to approximately 4 meters (12 ft) below ground surface (bgs). A thin layer of black material, approximately 2.5 cm (1in.) thick, was also observed during this initial excavation, and did not appear to be coal ash. Because stained soil was still present after the initial 4 meters (12 ft) depth, the excavation was extended to 5 meters (18 ft). Throughout this initial remediation, a strong odor, described as diesel or petroleum products was observed. However, the organic vapor monitors in the field did not detect any readings above background. On February 3, 2010, a soil sample, J19JX7, was collected from the base of the excavation on the southeast end of the excavation, and the sample was comprised of random aliquots of stained, odorous soil at approximately 5 meters (18 ft) bgs. The excavator then removed an additional 1.5 meters (5 ft) of soil from this same location, and sample J19JX8 was collected from random aliquots of odorous soil at approximately 7 meters (23 ft) bgs. Finally, an additional 1.5 meters (5 ft) was excavated from this location.

Groundwater was encountered at approximately 8.5 meters (28 ft) bgs, and approximately 0.6 meters (2 ft) of groundwater filled the hole. An oily sheen could be observed on top of the water. Sample J19JX9 was collected from the soil just above groundwater. The diesel or petroleum-product smell was still present in the excavation when the sample was collected. A diesel or petroleum-product odor was also noted at the northwest end of the excavation, at coordinates N147119/E578681. The depth of the excavation at this end was approximately 5 meters (18 ft) bgs. Approximately 1.5 meters (5 ft) of additional material was excavated to collect sample J19JY0 at a depth of 7 meters (23 ft). This 1.5 meter (5 ft) deep test pit was backfilled after sample collection. Because of the odor encountered at the 600-127 waste site, the footprint of the excavation design was extended to a depth of 8.5 meters (28 ft) bgs. A final in-process sample, J19Y10, was collected from stained soil in the sidewall on June 7, 2010.

Code: 600-128 **Classification:** Accepted

Names: 600-128; Oil and Oil Filter Dump Site; White Bluffs Oil and Oil Filter Dump Site **Reclassification:** Interim Closed Out (9/16/2003)

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The site has been remediated and Interim Closed Out. The site had been an oil dump area that included several canister-type oil filters. Surface debris was removed in the spring of 2003.

Location: The site was located west of Route 2 North and south of Federal Avenue. It was approximately 730 meters (2395 feet) south of the intersection of Route 2 North and Federal Avenue.

Related Sites/ Structures: The site was associated with the White Bluffs Automotive Repair Shop, site code 600-139.

Process Description: Several Hanford site construction shops and warehouse facilities were located in this area.

Waste Type: Oil

Waste Description: The waste is oil contaminated soil, oil cans and filters. There are also several small areas with broken glass, cans, and other metal debris.

Closure Info: Interim: A remedial action activity was implemented to remove contaminated soil and associated debris identified during the April 2003 site walkdown. The debris was removed to a depth of 25 centimeters (10 inches). Samples were collected to support waste designation. The material was collected and packaged in accordance with waste management plans, and removed from the site for subsequent disposal at the Environmental Restoration Disposal Facility or other approved facilities.

Code: 600-129 **Classification:** Accepted

Names: 600-129; Pre-MED White Bluffs Community Dump Site (Oil Can Site); White Bluffs Pre-MED Community Dump Site 1 **Reclassification:** Interim Closed Out (3/2/2005)

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The site has been remediated and Interim Closed Out. It was a non-radioactive dumping area. It was a large depression containing cans, bottles, oil cans, wire, rope, dry and wet cell batteries

and discarded automobile parts.

Location: The site was located west of Route 2 North, south of Federal Avenue, on the east side of a north/south dirt road. It was approximately 1.7 kilometers (1.1 miles) south-southeast of the intersection of Route 2 North and Federal Avenue.

**Related Sites/
Structures:** The site was co-located with 600-191.

Waste Type: Misc. Trash and Debris

**Waste
Description:** The main part of the site is littered with cans, bottles, oil cans, glass, wire, rope, toys, and automotive bodies and parts. On the southern edge industrial wastes include insulators, fuse boxes, conduit, and six 208-liter (55-gallon) drums, one of which is labeled "Carbon Tet". Because of the large number of oil cans, it is believed that the site was used by both Manhattan Engineering District (MED) and White Bluffs residents for the disposal of domestic type waste (Carpenter, 1994). Three glass vials containing an unknown white powder were found on a site walkdown in 1999. Dry cell batteries were also observed on April 22, 1999.

Closure Info: Interim: The site was 305 meters (1,001 feet) long by 80 meters (262 feet) wide with an irregular shape. The total area was 23,768 square meters (77,979 square feet). The site was an area littered with miscellaneous trash and debris. It appeared that it was used by both Manhattan Engineering District and White Bluffs residents for the disposal of domestic waste materials. The debris was concentrated in a swath along the west side of a dirt road. Areas devoid of vegetation were also observed; most were natural (e.g., clay, insects) and occurred due to a physical disturbance that does not recover for lack of moisture. This site was not originally identified as a remaining site, but was included in the removal action due to similarity in debris items and its location in the vicinity of the 600-129 site.

In May and June 2004, a site walkdown was conducted of the two sites and revealed debris and no evidence of burning. The site walkdown conducted in July 2004 included an EPA representative, who identified hazardous material to be removed. During the walkdown, it was also confirmed that a site-specific sampling plan would not be required. On July 28, 2004, a walkdown was conducted to identify, locate, and flag areas of hazardous material (mainly dry cell batteries) requiring removal. The flagged items were removed in October 2004 by an Environmental Restoration Contractor (ERC) subcontractor. The waste included dry and wet cell batteries, battery cases, asbestos-containing material, and paint materials.

The suspect hazardous debris was collected, characterized, and packaged in accordance with the waste management plan, and removed from the site for subsequent disposal at the Environmental Restoration Disposal Facility (ERDF) or other approved facility. The residual soil and debris remaining at the sites meets the remedial action goals and objectives.

600-191 is located adjacent to 600-129 and contained similar debris. It was agreed that 600-191 would be cleaned up as a proximity site to 600-129.

Interim Closure was based on site walkdowns and the removal and disposal of hazardous material.

Code: 600-131

Classification: Accepted

Names: 600-131; Special Fabrication Shop and Warehouse; White Bluffs Water Station and Special Fabrication Shops and Warehouse

Reclassification Interim Closed Out (9/12/2003)

Type: Dumping Area

Start Date:

Status: Inactive**End Date:****Description:** The site has been remediated and Interim Closed Out. The site included the remnants of the Special Fabrication Shop and Warehouse, boiler house, warehouse, loading dock/well and a water station.**Location:** The site was located approximately 1.3 kilometers (0.8 mile) northwest of the intersection of Route 2 North and Federal Avenue.**Waste Type:** Misc. Trash and Debris**Waste Description:** The waste was miscellaneous trash and debris, including concrete, transite, asphalt shingles, glass, and metallic debris. Transite contains asbestos, which was a hazardous substance. Asbestos was a CERCLA hazardous substance that may require action to mitigate a potential environmental impact. Asbestos wastes are excluded from the Dangerous Waste Regulations (WAC 173-303-071).**Closure Info:** Interim: On April 2003, a field walkdown, was done to gather information to finalize the sampling requirements. During the walkdown, areas of debris and anomalies were marked with flags. A remedial action was implemented to remove contaminated soil and debris from the site. The material was removed to a maximum depth of 1.7 meters (5.5 feet) and sampled to support waste designation. The material was packaged and disposed in ERDF.**Code:** 600-132**Classification:** Accepted**Names:** 600-132; Construction Contractor Shop Landfill; White Bluffs Construction Contractor Shop Landfill**Reclassification:** Interim Closed Out (9/12/2003)**Type:** Depression/Pit (nonspecific)**Start Date:****Status:** Inactive**End Date:****Description:** The site has been remediated and Interim Closed Out. The site was a large open borrow pit. The floor was mostly gravel and cobble with rabbitbrush and grasses. It contained scattered debris, such as broken concrete and pieces of metal, similar to the surrounding area. Surface debris was removed in 2003.**Location:** The site was located east of Route 2 North and north of Federal Avenue, approximately 1000 meters (3,281 feet) northwest of the intersection of Route 2 North and Federal Avenue.**Related Sites/Structures:** 600-132 is nearby the 600-131 fabrication shops.**Waste Type:** Misc. Trash and Debris**Waste Description:** If this site was actually the Construction Contractor Shop Landfill and not a borrow pit, the wastes that may have been disposed there could include oils, solvents, and cleaning agents (for example, carbon tetrachloride), typical of shop wastes. There may also be radioactive wastes, if this was not a mis-identified site (also see site 600-99). Carpenter (1995) identified two locations along the northwest boundary of the site with spots of oil (1.5-meter [4.9-foot] diameter for both spots). The waste that was visible in 1999 was surface debris, common to the entire 100-IU-2 Operable Unit, such as rusted metal cans, concrete rubble, a few pieces of transite, and wire. Two small piles of aluminum shavings are at the site, one on the floor of the pit and one at ground level, near the first pile. A small mound of dirt on the southwest corner, at the surrounding surface elevation, has partially buried pieces of yellow bricks and thick metal. A field walkdown done in April 2003 determined the site was a gravel borrow area and not a landfill.

Closure Info: Interim: After an April 2003 field walkdown, a remedial action activity was implemented to remove identified waste material and debris from the site for subsequent disposal at the Environmental Restoration Disposal Facility (ERDF). Waste included building rubble, wall board, asphalt shingles, oil cans and transite.

Code: 600-139 **Classification:** Accepted
Names: 600-139; Automotive Repair Shop; White Bluffs Automotive Repair Shop and Associated Waste Sites **Reclassification** Interim Closed Out (9/12/2003)
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The site has been remediated and Interim Closed Out. The site was an area thought to be associated with an automotive repair shop. Surface debris included numerous battery caps, engine gaskets, dumped waste oils, and fragments of tail light lenses. The surface debris was removed in May 2003.

Location: The site was located west of Route 2 North and north of Federal Avenue. It was approximately 700 meters (2297 feet) southwest of the intersection of Route 2 North and Federal Avenue.

Waste Type: Oil

Waste Description: The waste included battery caps, engine gaskets, fragments of tail light lenses, and dumped waste oils.

Closure Info: Interim: In April 2003, a field walkdown was conducted to finalize contaminants of potential concern, identify sample locations, and identify sample types for development of a sampling design. Debris and anomalies were marked with flags. The debris included transite, metal cans, gasket material, wood, rubber and piping. A remedial action activity was implemented to remove the identified waste material and debris from the site for disposal at the Environmental Restoration Disposal Facility. The material was removed to a maximum depth of 0.41 meters (1.3 feet).

The maximum detected results and a composite sample of underlying soil at the location, suspected of having the greatest potential for residual contamination, were used to support site reclassification.

Code: 600-176 **Classification:** Accepted
Names: 600-176; White Bluffs Paint Disposal Area **Reclassification** Interim Closed Out (5/25/2011)
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The site has been remediated and Interim Closed Out. It was a dumping area where excess paint materials were disposed of by pouring them on the ground. The ground had dried paint chips on the surface. The paint spills and chips were scattered over a large area. 600-176 was co-located with the 600-295 White Bluffs Paint Shop.

Location: The site was located approximately 570 meters (1870 feet) west of the intersection of Commercial Avenue and Federal Avenue within the warehouse storage area.

Related Sites/ Structures: 600-176 was co-located with the 600-295 White Bluffs Paint Shop.

Waste Type: Construction Debris

Waste Description: Paint chips are on the surface of the ground.

Closure Info: Interim: Confirmatory sampling was done in April and May 2003.

Remedial activities took place from December 7, 2009 to February 10, 2010. Visible, surface paint was placed into 208-L (55-gal) drums prior to excavation. Due to the presence of paint in the subsurface soil, the excavation continued to a depth of approximately 1.5 meters (5 ft). The remedial design for the 600-176 waste site overlapped the 600-295 waste site. Therefore, remediation of the 600-176 waste site resulted in the concurrent remediation of the 600-295 Paint Shop waste site. Data from the 600-176 remediation supported the reclassification of 600-295.

On December 17, 2009, an empty 10-inch diameter vitrified clay pipe (VCP) was encountered during excavation and followed to the northeastern corner of the excavation, where it ended in a possible concrete septic tank that was approximately 1.5 meters (5 ft) long with unknown depth and width. This VCP was believed to be part of the sewer lines associated with the 600-295 paint shop as shown in drawing H-11-3909 (Atkinson-Jones 1948). The VCP was removed with the material excavated during the 600-176 remediation. This septic system and tank have been identified as part of the 600-301 waste site.

Odoriferous green soil was encountered and removed at a depth of an additional 1 meter (3 ft) below the base of the excavation, until the associated solvent odor was no longer present. Although the material had a strong solvent-type odor, nothing was detected with the photo ionization detector (0.0 ppm readings) and soil samples did not reveal the chemical responsible for the odor. Additionally, coal ash was encountered on the southern side of the excavation that was as much as 46 cm (18 in.) thick in some areas and thinned out across the extent of the excavation. This material was removed and included in the stockpile to the southeast of the excavation. Wood debris was also encountered and stockpiled. The final excavation depth was 1.5 meters (5 ft) bgs.

Code: 600-181

Classification: Accepted

Names: 600-181; White Bluffs Oil Dump

Reclassification: Interim Closed Out (9/12/2003)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site has been remediated and Interim Closed Out. The site was an oil dumping area. The surface resembled asphalt in appearance as a result of the large quantities of oil that had been dumped at this location.

Location: The site was located west of Route 2 North and south of Federal Avenue. It was approximately 740 meters (2,428 feet) southeast of the intersection of Route 2 North and Federal Avenue. The site was on the west side of an old powerline access road.

Waste Type: Oil

Waste Description: The waste was oil contaminated soil. The top of the soil had formed into an asphalt-like surface.

Closure Info: Interim: In April 2003, a field walkdown was conducted to finalize contaminants of potential concern, identify sample locations, and identify sample types for development of a sampling design. Locations needing waste removal and areas for sample collection were marked. A remedial action activity was implemented to remove hydro-carbon contaminated soil and debris

from the site for disposal at the Environmental Restoration Disposal Facility (ERDF). The excavation depth was 1 meter (3 feet). The maximum detected results for a composite sample of underlying soil at the location suspected of having the greatest potential for residual contamination were used to support site reclassification.

Code: 600-182	Classification: Accepted
Names: 600-182; White Bluffs Asbestos Pipe Lagging and Excess Piping	Reclassification: Interim Closed Out (1/4/2011)
Type: Dumping Area	Start Date:
Status: Inactive	End Date:

Description: The waste site has been remediated and Interim Closed Out. It was an area that included excess piping materials and an some highly degraded piping insulation that appeared to be asbestos or a similar material. Several 6.1-meter (20-foot) sections of 30.5-centimeter (12-inch) spiral welded steel pipe were nearby. Other small debris piles were located very near that consisted of broken vitrified clay piping, plumbing fixtures, and concrete piping.

Location: The site was located west of Route 2 North and south of Federal Avenue. It is approximately 1050 meters (3445 feet) south of the intersection of Route 2 North and Federal Avenue and west of a power line road.

Waste Type: Asbestos (friable)

Waste Description: The waste is piping insulation material that appears to be made of asbestos or a similar material.

Closure Info: Interim: Remedial action was performed on February 10, 2010. All excess piping material, debris and potential ACM was removed. An overburden pile was created from the topsoil at the main excavation area. In addition to this excavation, two small areas were scraped where asbestos pipe lagging and vitrified clay pipe were found. A waste staging pile area was created to the side of these scraped areas. All scraped areas were excavated to approximately 8 centimeters (3 in.) below ground surface. The vadose zone beneath the excavation is approximately 5.1 meters (16.7 ft) thick.

The largest excavation had an area of approximately 1,000 square meters (10,700 sq ft). The scraped area with asbestos lagging was less than 100 square meters (1,000 sq ft). The scraped area with VCP was approximately 11 square meters (118 sq ft). The waste staging pile area was approximately 4 square meters (43 sq ft). The overburden pile is approximately 90 square meters (970 sq ft).

Code: 600-188	Classification: Accepted
Names: 600-188; White Bluffs Waste Disposal Trench 2	Reclassification: Interim Closed Out (3/16/2011)
Type: Trench	Start Date:
Status: Inactive	End Date:

Description: The site has been remediated and Interim Closed Out. It was an open trench containing industrial waste that filled about one-third of the site. There was evidence of chemical or oil dumping and burning along the east side of the trench. The White Bluffs Technical Baseline Report (BHI-00448) states discolored soils and empty 208-liter (55-gallon) drums that are bulging were present. The drum contents appeared to have been burned with the drums.

Location: The site is located west of Route 2 North and south of Federal Avenue. It is approximately

1000 meters (3,281 feet) southeast of the intersection of Route 2 North and Federal Avenue. The site is on the east side, and adjacent to, a powerline road.

Waste Type: Misc. Trash and Debris

Waste Description: The waste consists of industrial wastes of wooden and metallic debris. There has been chemical or oil dumping and burning. There are also empty 208-liter (55-gallon) drums.

Closure Info: Interim: The 600-188 waste site was remediated on February 10 and 11, 2010. Debris and soil to a depth no more than 1 meters (3 ft) below the existing borrow pit surface were removed from the waste site. The excavation was 2.5 meters (8 ft) below grade at the deepest area. Material removed from the perimeter around the excavation was placed into an overburden pile to be used as backfill material. Waste material was placed in a staging pile area, which was then loaded out to the Environmental Restoration Disposal Facility.

On March 3, 2010, three in-process soil samples (J119L34, J119L35, and J119L36), one duplicate sample (J19L37), and one equipment blank (J19L3 8) were collected to evaluate the adequacy of remediation. The footprint of the excavation was divided into three sample areas, and a sample was collected from multiple aliquots of soil across the top of each area (Appendix A). No contaminant concentrations of in-process soil samples exceeded direct exposure RAGs. Concentrations of several metals exceeded soil cleanup levels for protection of groundwater and/or the Columbia River but no organic chemicals exceeded soil RAGs.

Code: 600-190

Classification: Accepted

Names: 600-190; White Bluffs Warehouse Tar and/or Paint Disposal Area

Reclassification: Interim Closed Out (9/16/2003)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site has been remediated and Interim Closed Out. The site was an area where tar and/or paints appeared to have been dumped.

Location: The site was located east of Route 2 North and north of Federal Avenue. It was approximately 1000 meters (3,281 feet) northwest of the intersection of Route 2 North and Federal Avenue, by the southwest corner of 600-132, White Bluffs Construction Contractor Shop Landfill.

Process Description: It was assumed that the surface chips of paint on the ground were the result of crews dumping partially full cans of paint onto the ground before disposing of the cans.

Waste Type: Chemicals

Waste Description: The waste site consisted of tar and/or paint that had been dumped on the ground.

Closure Info: Interim: In April 2003, a field walkdown was conducted to finalize contaminants of potential concern, identify sample locations, and identify sample types for development of a sampling design. A remedial action activity was implemented to remove contaminated soil and debris identified in the walkdown. The excavation depth was approximately 25 centimeters (10 inches). The material removed was disposal at the Environmental Restoration Disposal Facility. The waste included dried paint, tar, elemental lead and cinders. The maximum detected results and a composite sample of underlying soil at the location suspected of having the greatest potential for residual contamination were used to support site reclassification.

Code: 600-191

Classification: Accepted

Names: 600-191; White Bluffs Pre-MED Community Dump Site 2 **Reclassification** Interim Closed Out (3/2/2005)

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The site has been remediated and Interim Closed-Out. It was a non-radiological dumping area. It was devoid of vegetation and contained miscellaneous trash and debris.

Location: The site was located west of Route 2 North and south of Federal Avenue. It was approximately 1.3 kilometers (0.8 miles) southeast of the intersection of Route 2 North and Federal Avenue. This site was north of 600-129, White Bluffs Pre-MED Community Dump Site 1, on the west side of a north/south dirt road.

Related Sites/ Structures: The site was co-located with 600-129.

Waste Type: Misc. Trash and Debris

Waste Description: The waste is miscellaneous trash and debris, including oil cans, cans, glass, domestic debris, car parts, and a few full 19-liter (5-gallon) cans of grease. During the April 1999 visit, the cans of grease described in the Technical Baseline Report could not be found. However, in addition to the debris already mentioned above, antifreeze containers and dry cell batteries were observed.

Closure Info: Interim: The site was 305 meters (1,001 feet) long by 80 meters (262 feet) wide with an irregular shape. The total area was 23,768 square meters (77,979 square feet). The site was an area littered with miscellaneous trash and debris. It appeared that it was used by both Manhattan Engineering District and White Bluffs residents for the disposal of domestic waste materials. The debris was concentrated in a swath along the west side of a dirt road. Areas devoid of vegetation were also observed; most were natural (e.g., clay, insects) and occurred due to a physical disturbance that does not recover for lack of moisture. This site was not originally identified as a remaining site, but was included in the removal action due to similarity in debris items and its location in the vicinity of the 600-129 site.

In May and June 2004, a site walkdown was conducted of the two sites and revealed debris and no evidence of burning. The site walkdown conducted in July 2004 included an EPA representative, who identified hazardous material to be removed. During the walkdown, it was also confirmed that a site-specific sampling plan would not be required. On July 28, 2004, a walkdown was conducted to identify, locate, and flag areas of hazardous material (mainly dry cell batteries) requiring removal. The flagged items were removed in October 2004 by an Environmental Restoration Contractor (ERC) subcontractor. The waste included dry and wet cell batteries, battery cases, asbestos-containing material, and paint materials.

The suspect hazardous debris was collected, characterized, and packaged in accordance with the waste management plan, and removed from the site for subsequent disposal at the Environmental Restoration Disposal Facility (ERDF) or other approved facility. The residual soil and debris remaining at the sites meets the remedial action goals and objectives.

600-191 is located adjacent to 600-129 and contained similar debris. It was agreed that 600-191 would be cleaned up as a proximity site to 600-129.

Interim Closure was based on site walkdowns and the removal and disposal of hazardous material.

Code: 600-201

Classification: Accepted

Names: 600-201; White Bluffs Paint and Solid Waste Disposal Site **Reclassification** Interim No Action (9/12/2003)

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The site has been evaluated to confirm that it does not require remediation. The site has been reclassified to "No Action". Red paint appeared to have been dumped on the surface. Debris included glass, metal parts, metal shavings and canvas.

Location: The site was located east of Route 2 North and north of Federal Avenue. It was approximately 925 meters (3,035 feet) northwest of the intersection of Route 2 North and Federal Avenue and just south of 600-132, White Bluffs Construction Contractor Shop Landfill.

Waste Type: Misc. Trash and Debris

Waste Description: The waste was red paint and other debris including, glass, metal shavings, metal parts, and army-green canvas material.

Closure Info: Interim: In May 2003, a test pit was dug at an area of anomaly found with GPR. The test pit revealed a flattened steel bucket and some decaying wood. Field screening was done on all debris removed from the pit to determine if a sample needed to be collected. No hazardous material was found. No samples were collected from the pit. The debris was put back into the excavation. The test pit was backfilled the same day it was dug. A single sample of hardened paint was collected.

Code: 600-279 **Classification:** Accepted

Names: 600-279; Vegetation Free Area Between White Bluffs and 100F **Reclassification** Final Closed Out (10/28/2015)

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The site has been remediated, Interim Closed Out and later Final Closed Out. It consisted of a large area of no vegetation covered with ash and bits of burned debris.

Location: The area was located northwest of the 105-F facility. It is on the west side of the 100 F Area western perimeter road, near the northwest corner of the 100-F Area. The coordinates for this waste site are N148089.2 E579584.2.

Process Description: The site was likely related to an old orchard. It is suspected that the site was the remains of a burned storage shed. The yellow material had a sulfur odor. Lead-arsenic and lime sulfur were used in orchards to control mold on fruit. The burned metal pieces could be pieces of farm equipment.

Closure Info: Interim (4/17/2014): (Interim Closed Out) In-process sampling at the 600-279 waste site (for the purpose of waste management) consisted of two composite samples: J1RWK4 collected August 19, 2013, and J1T3J3 collected on October 8, 2013. A portion of the site was observed to be covered with ash, burned debris (pieces of brick, metal, and wood), and yellow stained soil with a sulfur odor in both waste management sampling events. All contaminated soil, ash, and debris was subsequently removed during the waste site remedial actions.

Remediation of the 600-279 waste site was performed over an area of 1,158 square meters (12,465 ft²) from September 30 through October 22, 2013. The 600-279 waste site is situated on a sloped area of land that inclines toward the southeast. Therefore, the maximum excavation depth is approximately 6.1 meters (20 ft) from the west side of the waste site and 3.7 to 4.6

meters (12 to 15 ft) from the east side. All material (stained and affected soil; surface debris such as wood, metal, and bricks) was directly loaded from the excavation into Environmental Restoration Disposal Facility (ERDF) containers for disposal at ERDF. The approximate volume of material removed from the 600-279 waste site was 765 bank cubic meters (1,001 bank cubic yards). No anomalous materials were encountered during the excavation. There are no overburden piles or waste staging pile areas associated with the 600-279 waste site.

Final (10/28/2015): (Final Closed Out) Based upon evaluation of the previous reclassification data against the 100-F/IU Area ROD cleanup levels, no further RTD is required for any of the 26 waste sites (Listed below).

600-279, Vegetation-Free Area Between White Bluffs and 100-F
 600-293, White Bluffs Service Station #1
 600-294, White Bluffs Service Station #2
 600-298, Stained Soil and Surface Debris
 600-299, Surface Debris/Batteries
 600-300, Miscellaneous Surface Debris
 600-301, White Bluffs Sanitary Sewer Pipelines
 600-303, Vertical Pipes
 600-316, Dry Cell Batteries
 600-318, Wet Cell Batteries
 600-320, Oil Stains
 600-321, Suspect ACM Sites
 600-328, Lead Slag
 600-356, Tar Deposit West of Susie Junction
 600-368, Segment 4 Stained Soil #1
 600-369, Segment 4 Bare Ground and Crusted Soil Areas
 600-370, Segment 4 Debris Area #1
 600-371, Segment 4 Chalky Material Area
 600-372, Segment 4 Oil Stain and Filter Area #1
 600-373, Segment 4 Bare Ground and White Stain Area
 600-374, Segment 4 Drum Remnant Area
 600-375, Segment 4 Dry Cell Battery Debris Area #1
 600-376, Segment 4 Stained Soil Area #2
 600-377, Segment 4 Oil Stain and Filter Area #2
 600-378, 506 Telephone Exchange Emergency Generator Building Underground Fuel Storage tank
 600-379, Segment 4 Burn Area #1.

The Reclassification to Final Closed Out applies to all subsites associated with the waste sites listed above.

Code: 600-293	Classification: Accepted
Names: 600-293; White Bluffs Service Station #1	Reclassification: Final Closed Out (10/28/2015)
Type: Unplanned Release	Start Date: 1/1/1944
Status: Inactive	End Date:
Description:	The waste site has been remediated, Interim Closed Out and later Final Closed Out. It was a service station supported the White Bluffs Central Shops. The building was previously demolished around 1975. No underground tank was found at this waste site.
Location:	The site was located in the White Bluffs area, east of Route 2 North and north of Federal Avenue. It is south of Sand Bar Road and is located on the west side of 600-132. It was

approximately 1000 meters (3,281 feet) northwest of the intersection of Route 2 North and Federal Avenue.

- Process Description:** This facility was used for dispensing of fuel for automotive use. This site may include underground storage tank (s), associated piping and the underlying soil.
- Waste Type:** Oil
- Waste Description:** The waste is contaminated soil, tanks and associated piping. Contaminants of potential concern may include petroleum products, TPH, PAH and ICP metals.
- Closure Info:** Interim (1/16/2014): A ground penetrating radar (GPR) scan was done in 2007. The scan identified several anomalies that appeared to be part of the service station infrastructure. Confirmatory sampling from two test trenches was done in October 2010. A steel pipeline was identified. While removing the pipeline, a small amount of brown liquid discharged from the pipe. Three more pipelines were uncovered and one was observed to be leaking a small amount of oil. A concrete trench was uncovered that appeared to be a pit for servicing vehicles. No underground tank (UST) was found.

Remediation of the 600-293, White Bluffs Service Station #1 was performed on March 25 and June 24, 2013. Approximately 432 bank cubic meters (BCM) (659 bank cubic yards [BCY]) of materials were excavated and direct loaded for disposal at the Environmental Restoration Disposal Facility (ERDF). The floor of the 600-293 waste site excavation varies from approximately 2.4 to 3 meters (8 to 10 ft) below ground surface. During the 600-293 waste site remedial activities, no UST was found. A number of pipeline segments associated with the service station were excavated from the 600-293 waste site for disposal at ERDF. Various forms of waste and debris were observed during remediation, including the concrete slab that covered most of the waste site and approximately 0.6 meters (2 ft) of bedding sand below the slab where more pipelines were observed and excavated. One sample location exceeded the remediation goals for PCB's. An additional 30 BCM (39 BCY) of contaminated soil was excavated direct located for disposal at ERDF.

Final (10/28/2015): (Final Closed Out) Based upon evaluation of the previous reclassification data against the 100-F/IU Area ROD cleanup levels, no further RTD is required for any of the 26 waste sites (Listed below).

600-279, Vegetation-Free Area Between White Bluffs and 100-F
 600-293, White Bluffs Service Station #1
 600-294, White Bluffs Service Station #2
 600-298, Stained Soil and Surface Debris
 600-299, Surface Debris/Batteries
 600-300, Miscellaneous Surface Debris
 600-301, White Bluffs Sanitary Sewer Pipelines
 600-303, Vertical Pipes
 600-316, Dry Cell Batteries
 600-318, Wet Cell Batteries
 600-320, Oil Stains
 600-321, Suspect ACM Sites
 600-328, Lead Slag
 600-356, Tar Deposit West of Susie Junction
 600-368, Segment 4 Stained Soil #1
 600-369, Segment 4 Bare Ground and Crusted Soil Areas
 600-370, Segment 4 Debris Area #1
 600-371, Segment 4 Chalky Material Area
 600-372, Segment 4 Oil Stain and Filter Area #1
 600-373, Segment 4 Bare Ground and White Stain Area

600-374, Segment 4 Drum Remnant Area
 600-375, Segment 4 Dry Cell Battery Debris Area #1
 600-376, Segment 4 Stained Soil Area #2
 600-377, Segment 4 Oil Stain and Filter Area #2
 600-378, 506 Telephone Exchange Emergency Generator Building Underground Fuel Storage tank
 600-379, Segment 4 Burn Area #1.

The Reclassification to Final Closed Out applies to all subsites associated with the waste sites listed above.

Code: 600-294	Classification: Accepted
Names: 600-294; White Bluffs Service Station #2	Reclassification: Final Closed Out (10/28/2015)
Type: Unplanned Release	Start Date:
Status: Unknown	End Date:

Description: The site has been remediated, Interim Closed Out and later Final Closed Out. It was the location of a service station with the potential for an underground storage tank (s), associated piping and underlying soils. The service station building was demolished and buried in place in 1975. No underground storage tank was found during remediation.

Location: The site was located in the White Bluffs area west of the railroad tracks, north of Federal Avenue and near the southeast corner of the equipment lot.

Process Description: The service station dispensed fuel for automotive use. The service station contained two gasoline pumps and two buried tanks with a total capacity of 4,000 gallons and one diesel fuel pump and a 1,000 gallon buried tank. It had a lube rack and a steam cleaning pad.

Waste Type: Oil

Waste Description: The waste includes petroleum product contaminated soil, underground storage tanks and associated piping. Contaminants of potential concern may include petroleum products (TPH, PAH) and possibly ICP metals.

Closure Info: Interim (1/16/2014): Confirmatory sampling was conducted on October 20, 2010. Suspected asbestos-containing materials were observed on the ground surface. Characterization sampling involved excavation of two test pits, one test trench and collection of two focused samples and two surface asbestos samples. During excavation of Test Pit 1, two 5 centimeter (2 in.) diameter stainless steel pipelines were uncovered approximately 1 meter (3 ft) bgs. The pipelines were found to be empty. A sample (J1C2C7) of soil underlying the pipelines was collected for analysis at approximately 1.2 meters (4 ft) bgs. No debris, stains or pipelines were uncovered during the excavation of test pit 2. Excavation was extended to 4 meters (13 ft) bgs, although native soil was observed at 1.8 meters (6 ft) bgs. During the excavation of the Test Trench, a 6.1 meter (20 ft) piece of 1.2 meter (4 ft) diameter corrugated pipe was uncovered 1 meter (3 ft) bgs. A 7.6 centimeter (3 inch) diameter steel pipeline was observed protruding from the east side of the corrugated pipe. It was determined the corrugated pipe was a potential drain.

Remediation of the 600-294 south area was performed from March 28 through April 1, 2013. Approximately 63 bank cubic meters (BCM) (82 bank cubic yards [BCY]) of excavated materials were removed for direct disposal at the Environmental Restoration Disposal Facility (ERDF). The final depth of the south area excavation was approximately 1.8 meters (6 ft) bgs. Remediation of the northern area of waste site 600-294 was performed from June 19 through July 16, 2013. Approximately 99 BCM (129 BCY) of excavated materials, including two 1.2 meter (4 ft) diameter sections of corrugated piping, were removed and loaded for direct disposal

at ERDF. The final depth of the northern excavated area was 3 meters (10 ft) bgs. Yellow soil staining was observed during excavation of the northern area. An in-process sample (J1RNY4) was collected from the yellow stained soils and analyzed for metals and hexavalent chromium. The data results showed that metals and hexavalent chromium concentrations were below the remedial action goals (RAGs). An estimated total volume of 162 BCM (211 BCY) of contaminated soil and materials was excavated from the 600-294 waste site and disposed of at ERDF.

Final (10/28/2015): (Final Closed Out) Based upon evaluation of the previous reclassification data against the 100-F/IU Area ROD cleanup levels, no further RTD is required for any of the 26 waste sites (Listed below).

600-279, Vegetation-Free Area Between White Bluffs and 100-F
 600-293, White Bluffs Service Station #1
 600-294, White Bluffs Service Station #2
 600-298, Stained Soil and Surface Debris
 600-299, Surface Debris/Batteries
 600-300, Miscellaneous Surface Debris
 600-301, White Bluffs Sanitary Sewer Pipelines
 600-303, Vertical Pipes
 600-316, Dry Cell Batteries
 600-318, Wet Cell Batteries
 600-320, Oil Stains
 600-321, Suspect ACM Sites
 600-328, Lead Slag
 600-356, Tar Deposit West of Susie Junction
 600-368, Segment 4 Stained Soil #1
 600-369, Segment 4 Bare Ground and Crusted Soil Areas
 600-370, Segment 4 Debris Area #1
 600-371, Segment 4 Chalky Material Area
 600-372, Segment 4 Oil Stain and Filter Area #1
 600-373, Segment 4 Bare Ground and White Stain Area
 600-374, Segment 4 Drum Remnant Area
 600-375, Segment 4 Dry Cell Battery Debris Area #1
 600-376, Segment 4 Stained Soil Area #2
 600-377, Segment 4 Oil Stain and Filter Area #2
 600-378, 506 Telephone Exchange Emergency Generator Building Underground Fuel Storage tank
 600-379, Segment 4 Burn Area #1.

The Reclassification to Final Closed Out applies to all subsites associated with the waste sites listed above.

Code: 600-295	Classification: Accepted
Names: 600-295; White Bluffs Paint Shop	Reclassification Interim Closed Out (4/13/2011)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The site has been remediated and Interim Closed Out. It consisted of surface and underlying soils associated with the former Paint Shop that was used to support the White Bluffs Central Shops. The footprint of the building was easily recognizable due to a lack of vegetation. It was co-located with the 600-176 Paint Disposal Area waste site. The two waste sites were remediated at the same time.

Location: The site is located northwest of Federal Avenue and southeast of Route 2N. The paint shop was located north of Federal Avenue and east of Gasoline Alley. This site is located approximately 17 meters (56 feet) northeast of 600-176 (White Bluffs Paint Disposal Area).

Related Sites/ Structures: The paint shop is associated with the 600-176 dump site.

Process Description: Paint shop supported the White Bluffs shops operations.

Waste Type: Soil

Waste Description: Contaminants of potential concern would include VOA, semi-VOA, ICP metals with mercury in the soil.

Closure Info: Interim (4/13/2011): The 600-176, White Bluffs Paint Disposal Area underwent remediation in November 2010. The remedial design for the 600-176 waste site completely overlapped the 600-295 Paint Shop waste site. Therefore, remediation of the 600-176 waste site resulted in the concurrent remediation of the 600-295, White Bluffs Paint Shop waste site. The location of 600-295 waste site was within the excavation boundary of the 600-176 waste site. Verification sample EXC-10 was collected from within the 600-295 boundary.

Code: 600-296

Classification: Accepted

Names: 600-296; White Bluffs Fire Department Septic System

Reclassification: Interim No Action (4/26/2011)

Type: Sanitary Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site has been evaluated and determined to require No Action. It consisted of the septic system for the White Bluffs Fire Department. It is a 1 by 1.5 meter (3.3 by 5 feet) sump with lid, a soil filled 1.5 by 2 meter (5 by 6.5 feet) concrete below grade box, a potential septic drain field with associated piping and the underlying soil. A 15 centimeter (6 inch) drain line extends from the fire house to the septic tank and onto a drain field. These features are all suspected of being the components of the former Hanford Works Fire Station septic system at White Bluffs.

Location: The site is located near the intersection of White Bluffs road and Route 2N. The fire house was located at the corner of Federal Avenue and First Street. The septic system is located northeast of the fire station.

Process Description: The site is a septic system that was used to support the White Bluffs Fire Station.

Waste Type: Sanitary Sewage

Waste Description: The site includes the septic tank, drain field, associated piping and surrounding soils. Contaminants of potential concern include ICP metals and possibly other hazardous substances.

Closure Info: Interim (4/26/2011): Confirmatory sampling indicated that environmental contamination was not present at this waste site. The analytical results indicate that the residual concentrations of COPCs at this site meet the RAGs and corresponding remedial action objectives for direct exposure, groundwater protection, and river protection. In accordance with this evaluation, the verification sampling results support a reclassification of the 600-296 waste site to No Action.

Code: 600-297 **Classification:** Accepted
Names: 600-297; White Bluffs Imhoff Tank **Reclassification:** Interim Closed Out (3/16/2011)
Type: Settling Tank **Start Date:**
Status: Inactive **End Date:**

Description: This waste site has been remediated and Interim Closed Out. It consisted of an Imhoff tank (separations tank) and its underlying soils. 600-297 (White Bluffs Imhoff Tank) and 600-120 (White Bluffs Spare Parts Burn Pit) were remediated at the same time.

Location: The site was located southwest of Route 2 North and south of Federal Avenue, under a set of BPA lines. The Imhoff Tank was located south of Federal Avenue, west of the Chicago Milwaukee Railroad and approximately 47 meters (154 feet) east of waste site 600-120.

Related Sites/ Structures: The tank is associated with the White Bluffs facility complex and Pickling Acid crib (sitecode 600-106). 600-297 was remediated with the White Bluffs Spare Parts Burn Pit (sitecode 600-120).

Process Description: The 600-297, White Bluffs Imhoff Tank was thought to have consisted of a septic tank associated with the White Bluffs sanitary sewer system. However, during remediation of this waste site, it was determined that the structure was actually an old boiler, and was likely not associated with the sanitary sewer system. Further investigation found it facilitated separation of solids from the influent going to the 600-106 Pickling Acid Cribs (as shown on H-11-3709), located approximately 170 meters (558 feet) southwest of the tank. 600-106 was used to dispose of spent pickling acid that was utilized to pickle galvanized piping. Generally, the hydrofluoric and nitric acid used for pickling was neutralized prior to disposal, but may not have been completely neutralized prior to disposal. The 600-106 Pickling Acid Cribs waste site was Closed-Out in 1996. However no information concerning the Imhoff tank was discussed in the 600-106 report.

Waste Type: Soil

Waste Description: Contaminants associated with the effluent to the tank from the White Bluffs facility complex have not been evaluated, so they are presently unknown.

Closure Info: Interim (3/16/2011): Remediation of 600-120 and 600-297 occurred from January 7 to March 15, 2010.

On January 7, 2010, several concrete structures associated with the 600-297 Imhoff Tank were encountered during initial remediation. A 10 centimeter (4 inch) diameter vitrified clay pipe was found protruding from each of the concrete structures. During demolition of the concrete structures, a 114 liter (30 gallon) tank was encountered on January 11, 2010. The tank resembled an old boiler and contained a small amount of black, non-oily, non-viscous liquid. A sample (J19WT1) was taken of this liquid on April 14, 2010. The concrete structure was fully removed. The bottom of the structure was at approximately 8 meters (28 feet) below ground surface. The materials that were excavated as a part of this remediation included coal ash and a concrete structure determined to be from the co-located 600-297 White Bluffs Imhoff Tank waste site. Groundwater was encountered at this location after the 600-297 waste site tank was removed.

600-120 Area 1 was a large depression that appeared to be an abandoned burn pit, backfilled with coal ash. Remedial action at the 600-120 waste site was performed from January to March 2010. Two test trenches were excavated for confirmatory sampling in Area 1. Evidence of vitrified clay pipe, rubber, burned wood, and coal were found. Confirmatory samples collected from the coal ash and native soil locations in Area 1 found that direct exposure remedial action goals (RAGs) were exceeded for benzo(a)pyrene, benzo(b)fluoranthene, chrysene, and indeno(1,2,3-cd)pyrene, indicating that site remediation was required. Barium, copper, and

selenium were also present in concentrations exceeding soil cleanup criteria for groundwater or river protection.

600-120 Area 2 was determined to need no remediation.

600-120 Area 3 was identified during the geophysical survey as a depression northeast of Area 1 where buried debris was suspected to be present. One test trench was excavated in Area 3 for confirmatory sampling. Concrete walls, debris, coal ash, apparent rust, and oil stained soil were all observed in this test trench. Confirmatory samples of stained soils showed lead and silver concentrations in excess of direct exposure cleanup RAGs. Herbicides, pesticides, and polychlorinated biphenyls (PCBs) were also present in concentrations exceeding soil cleanup criteria for groundwater or river protection.

Following remediation, verification sampling was conducted in September 2010. The results indicated that the waste removal action achieved compliance with the remedial action objectives (RAOs) and RAGs for the 600-120 and 600-297 waste sites. The results of the verification sampling are used to make reclassification decisions for the 600-120 and 600-297 waste sites in accordance with the TPA-MP-14 procedure. The verification sampling results support a reclassification of this site to Interim Closed Out.

Code: 600-298	Classification: Accepted
Names: 600-298; Surface Debris and Stained Soil in 100-IU-2	Reclassification: Final Closed Out (10/28/2015)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:
Description:	The parent site and the subsites were remediated and Interim Closed Out in a single document and Reclassification form (2013-040). The parent site and all the subsites were later Final Closed Out. The site was nine areas of surface debris and stained soil identified during the 2008 100-IU-2 Operable Unit Orphan Sites Evaluation walkdown. The waste site was originally divided into eight subsites. A ninth area was identified in 2011.
Location:	The area of investigation was south of 100-H Area and east of 100-F Area. Eight areas were observed during the Orphan Sites Evaluation of this area. A ninth was discovered in 2011.
Process Description:	Surface debris and material that stained the soil was released to ground during the construction, operating, and decontamination and decommissioning (D & D) activities within the 100-IU-2 Operable Unit (OU).
	The field walkdown was completed using 30 meter by 30 meter grids covering the operable unit. A global positioning system (GPS) was used to navigate each grid and to record the location of field observations. A digital camera was used to photograph each observation as recorded in a field logbook with the GPS record number. The GPS files with coordinates and attributes were downloaded daily to a GIS database for plotting on a map and for maintaining the coordinates and observations electronically. The digital camera files were downloaded daily to a dated folder on a share drive for coordination of photos with GPS data and the field logbook entries. The field walkdown of the Operable Unit did not include known waste sites or posted areas. The field walkdown was limited to observations. No sampling was conducted. Areas potentially containing CERCLA hazardous substances are found scattered throughout the operable unit at the documented coordinates. Observations of potential physical hazards, cultural artifacts, and nonhazardous, non-dangerous solid waste were recorded in logbook EL-1617.
Closure Info:	Interim (11/21/2013): (Interim Closed Out) The 600-298, 600-299 and 600-300 parent sites and

their subsites have been remediated and Interim Closed Out in a single document and three Reclassification forms (2013-040, 2013-041, 2013-042).

The debris was left during deactivation, decontamination, decommissioning, and demolition (D4) activities at the White Bluffs Central Shops Area. 600-298 included eight subsites of surface debris and stained soil, 600-299 included six subsites and 600-300 included twelve subsites. The total material removed from all the areas was 2300 bank cubic meters. It was all disposed at ERDF.

Characterization soil samples were collected in March and April 2011. GPR scans were done over a time span from June 2011 through January 2013. The remediation activities removed soil and debris between January 31, 2012 through March 5, 2013. At 600-298, most areas were remediated to a depth of 0.9 meters (3 ft). 600-298:5 was excavated to a depth of 2.4 meters (8 ft). The depth of excavation at all the 600-299 and 600-300 areas was 0.3 meters (1 ft).

Final (10/28/2015): (Final Closed Out) Based upon evaluation of the previous reclassification data against the 100-F/IU Area ROD cleanup levels, no further RTD is required for any of the 26 waste sites (Listed below).

600-279, Vegetation-Free Area Between White Bluffs and 100-F
 600-293, White Bluffs Service Station #1
 600-294, White Bluffs Service Station #2
 600-298, Stained Soil and Surface Debris
 600-299, Surface Debris/Batteries
 600-300, Miscellaneous Surface Debris
 600-301, White Bluffs Sanitary Sewer Pipelines
 600-303, Vertical Pipes
 600-316, Dry Cell Batteries
 600-318, Wet Cell Batteries
 600-320, Oil Stains
 600-321, Suspect ACM Sites
 600-328, Lead Slag
 600-356, Tar Deposit West of Susie Junction
 600-368, Segment 4 Stained Soil #1
 600-369, Segment 4 Bare Ground and Crusted Soil Areas
 600-370, Segment 4 Debris Area #1
 600-371, Segment 4 Chalky Material Area
 600-372, Segment 4 Oil Stain and Filter Area #1
 600-373, Segment 4 Bare Ground and White Stain Area
 600-374, Segment 4 Drum Remnant Area
 600-375, Segment 4 Dry Cell Battery Debris Area #1
 600-376, Segment 4 Stained Soil Area #2
 600-377, Segment 4 Oil Stain and Filter Area #2
 600-378, 506 Telephone Exchange Emergency Generator Building Underground Fuel Storage tank
 600-379, Segment 4 Burn Area #1.

The Reclassification to Final Closed Out applies to all subsites associated with the waste sites listed above.

This Site has the Following SubSites:

Code: 600-298:1

Names: 600-298:1; Stained Soil/Surface Debris Area 1

Code: 600-298:2
Names: 600-298:2; Stained Soil/Surface Debris Area 2

Code: 600-298:3
Names: 600-298:3; Stained Soil/Surface Debris Area 3

Code: 600-298:4
Names: 600-298:4; Stained Soil/Surface Debris Area 4

Code: 600-298:5
Names: 600-298:5; Stained Soil/Surface Debris Area 5

Code: 600-298:6
Names: 600-298:6; Stained Soil/Surface Debris Area 6

Code: 600-298:7
Names: 600-298:7; Stained Soil/Surface Debris Area 7

Code: 600-298:8
Names: 600-298:8; Stained Soil/Surface Debris Area 8

Code: 600-298:1	Classification: Accepted
Names: 600-298:1; Stained Soil/Surface Debris Area 1	Reclassification Final Closed Out (10/28/2015)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The parent site and the subsites have been Final Closed Out. They were remediated and Interim Closed Out in a single document and Reclassification form (2013-040). The subsite consisted of an area approximately 2 by 10 meter (6.6 by 32.8 ft) with dark stained soil. There was a noticeable fuel-like odor.

Location: The site was located approximately 158 meters (518 ft) west of Federal Avenue and 1.1 km (0.67 miles) south of Route 2 North in the former White Bluffs Community area. Area 1 is at E577397.87, N147549.31.

Closure Info: Interim (11/21/2013): (Interim Closed Out) The 600-298, 600-299 and 600-300 parent sites and their subsites have been remediated and Interim Closed Out in a single document and three Reclassification forms (2013-040, 2013-041, 2013-042).

The debris was left during deactivation, decontamination, decommissioning, and demolition (D4) activities at the White Bluffs Central Shops Area. 600-298 included eight subsites of surface debris and stained soil, 600-299 included six subsites and 600-300 included twelve subsites. The total material removed from all the areas was 2300 bank cubic meters. It was all disposed at ERDF.

Characterization soil samples were collected in March and April 2011. GPR scans were done over a time span from June 2011 through January 2013. The remediation activities removed soil and debris between January 31, 2012 through March 5, 2013. At 600-298, most areas were remediated to a depth of 0.9 meters (3 ft). 600-298:5 was excavated to a depth of 2.4 meters (8 ft). The depth of excavation at all the 600-299 and 600-300 areas was 0.3 meters (1 ft).

The SubSite is Part Of:

Code: 600-298
Names: 600-298; Surface Debris and Stained Soil in 100-IU-2

Code: 600-298:2 **Classification:** Accepted
Names: 600-298:2; Stained Soil/Surface Debris Area 2 **Reclassification** Final Closed Out (10/28/2015)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The parent site and the subsites have been Final Closed Out. They were remediated and Interim Closed Out in a single document and Reclassification form (2013-040). The subsite consisted of an area roughly a 1 by 1 meter (3.3 by 3.3 ft) area with a noticeable yellowish stained soil. A hard crust covers the stained area.

Location: The site was located approximately 106 meter (348 ft) west of Federal Avenue and 1.1 km (0.7 miles) south of Route 2 North in the former White Bluffs Community area. Area 2 is at coordinates E577400.49 N147511.49.

Closure Info: Interim (11/21/2013): (Interim Closed Out) The 600-298, 600-299 and 600-300 parent sites and their subsites have been remediated and Interim Closed Out in a single document and three Reclassification forms (2013-040, 2013-041, 2013-042).

The debris was left during deactivation, decontamination, decommissioning, and demolition (D4) activities at the White Bluffs Central Shops Area. 600-298 included eight subsites of surface debris and stained soil, 600-299 included six subsites and 600-300 included twelve subsites. The total material removed from all the areas was 2300 bank cubic meters. It was all disposed at ERDF.

Characterization soil samples were collected in March and April 2011. GPR scans were done over a time span from June 2011 through January 2013. The remediation activities removed soil and debris between January 31, 2012 through March 5, 2013. At 600-298, most areas were remediated to a depth of 0.9 meters (3 ft). 600-298:5 was excavated to a depth of 2.4 meters (8 ft). The depth of excavation at all the 600-299 and 600-300 areas was 0.3 meters (1 ft).

The SubSite is Part Of:

Code: 600-298
Names: 600-298; Surface Debris and Stained Soil in 100-IU-2

Code: 600-298:3 **Classification:** Accepted
Names: 600-298:3; Stained Soil/Surface Debris Area 3 **Reclassification** Final Closed Out (10/28/2015)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The parent site and the subsites have been Final Closed Out. They were remediated and Interim Closed Out in a single document and Reclassification form (2013-040). The subsite consisted of two spots 1 m (3.3 ft) square each, 1 m (3.3 ft) apart with discolored soil and distressed vegetation.

Location: The site was located approximately 634 m (0.4 miles) west of Federal Avenue and 400 m (0.25 miles) south of Route 2 North in the former White Bluffs Community area. Area 3 is at E577504.87, N148101.70.

Closure Info: Interim (11/21/2013): (Interim Closed Out) The 600-298, 600-299 and 600-300 parent sites and their subsites have been remediated and Interim Closed Out in a single document and three Reclassification forms (2013-040, 2013-041, 2013-042).

The debris was left during deactivation, decontamination, decommissioning, and demolition (D4) activities at the White Bluffs Central Shops Area. 600-298 included eight subsites of surface debris and stained soil, 600-299 included six subsites and 600-300 included twelve subsites. The total material removed from all the areas was 2300 bank cubic meters. It was all disposed at ERDF.

Characterization soil samples were collected in March and April 2011. GPR scans were done over a time span from June 2011 through January 2013. The remediation activities removed soil and debris between January 31, 2012 through March 5, 2013. At 600-298, most areas were remediated to a depth of 0.9 meters (3 ft). 600-298:5 was excavated to a depth of 2.4 meters (8 ft). The depth of excavation at all the 600-299 and 600-300 areas was 0.3 meters (1 ft).

The SubSite is Part Of:

Code: 600-298

Names: 600-298; Surface Debris and Stained Soil in 100-IU-2

Code: 600-298:4

Classification: Accepted

Names: 600-298:4; Stained Soil/Surface Debris Area 4

Reclassification Final Closed Out (10/28/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The parent site and the subsites have been Final Closed Out. They were remediated and Interim Closed Out in a single document and Reclassification form (2013-040). The subsite consisted of two areas. The first was identified as an area of reddish angular material, possibly iron metal. The material, approximately 20.3 cm (0.67 ft) deep, covers an area approximately 20 by 24 meters (65 by 80 ft). The second was identified as an area of dark stained soil approximately 5 by 15 meter (16 ft by 49 ft).

Location: The site was located approximately 107 meters (351 ft) west of Federal Avenue and 616 m (0.4 miles) south of Route 2 North in the former White Bluffs Community area. Area 4 is at coordinates E577688.53 N147743.69

Closure Info: Interim (11/21/2013): (Interim Closed Out) The 600-298, 600-299 and 600-300 parent sites and their subsites have been remediated and Interim Closed Out in a single document and three Reclassification forms (2013-040, 2013-041, 2013-042).

The debris was left during deactivation, decontamination, decommissioning, and demolition (D4) activities at the White Bluffs Central Shops Area. 600-298 included eight subsites of surface debris and stained soil, 600-299 included six subsites and 600-300 included twelve subsites. The total material removed from all the areas was 2300 bank cubic meters. It was all disposed at ERDF.

Characterization soil samples were collected in March and April 2011. GPR scans were done over a time span from June 2011 through January 2013. The remediation activities removed soil and debris between January 31, 2012 through March 5, 2013. At 600-298, most areas were remediated to a depth of 0.9 meters (3 ft). 600-298:5 was excavated to a depth of 2.4 meters (8 ft). The depth of excavation at all the 600-299 and 600-300 areas was 0.3 meters (1 ft).

The SubSite is Part Of:

Code: 600-298

Names: 600-298; Surface Debris and Stained Soil in 100-IU-2

Code: 600-298:5 **Classification:** Accepted
Names: 600-298:5; Stained Soil/Surface Debris Area 5 **Reclassification** Final Closed Out (10/28/2015)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The parent site and the subsites have been Final Closed Out. They were remediated and Interim Closed Out in a single document and Reclassification form (2013-040). The subsite consisted of a 4 by 12 meter (13 by 39 ft) area of three small yellow stains and no vegetation. There is also some wood and metal debris.

Location: The site was located approximately 91 meters (299 ft) west of Federal Avenue and 155 m (509 ft) south of Route 2 North in the former White Bluffs Community area. Area 5 is at E577962.47, N148003.95.

Closure Info: Interim (11/21/2013): (Interim Closed Out) The 600-298, 600-299 and 600-300 parent sites and their subsites have been remediated and Interim Closed Out in a single document and three Reclassification forms (2013-040, 2013-041, 2013-042).

The debris was left during deactivation, decontamination, decommissioning, and demolition (D4) activities at the White Bluffs Central Shops Area. 600-298 included eight subsites of surface debris and stained soil, 600-299 included six subsites and 600-300 included twelve subsites. The total material removed from all the areas was 2300 bank cubic meters. It was all disposed at ERDF.

Characterization soil samples were collected in March and April 2011. GPR scans were done over a time span from June 2011 through January 2013. The remediation activities removed soil and debris between January 31, 2012 through March 5, 2013. At 600-298, most areas were remediated to a depth of 0.9 meters (3 ft). 600-298:5 was excavated to a depth of 2.4 meters (8 ft). The depth of excavation at all the 600-299 and 600-300 areas was 0.3 meters (1 ft).

The SubSite is Part Of:

Code: 600-298
Names: 600-298; Surface Debris and Stained Soil in 100-IU-2

Code: 600-298:6 **Classification:** Accepted
Names: 600-298:6; Stained Soil/Surface Debris Area 6 **Reclassification** Final Closed Out (10/28/2015)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The parent site and the subsites have been Final Closed Out. They were remediated and Interim Closed Out in a single document and Reclassification form (2013-040). The subsite consisted of discolored soil, suspect asbestos containing material (ACM), white porcelain fragments, wood fragments, and two small depressions within the disturbed area. One of the depressions is 0.3 meters (12 in) deep by 0.2 meters (8 in) in diameter. There is also a 7.6 cm (3 in) steel pipe, a welded flat iron, and possible subsurface debris.

Location: The site was located approximately 121 meters (397 ft) east of Federal Avenue and 461 meters (0.3 miles) south of Route 2 North in the former White Bluffs Community area. Area 6 is at E577913.47, N147738.25.

Closure Info: Interim (11/21/2013): (Interim Closed Out) The 600-298, 600-299 and 600-300 parent sites and their subsites have been remediated and Interim Closed Out in a single document and three

Reclassification forms (2013-040, 2013-041, 2013-042).

The debris was left during deactivation, decontamination, decommissioning, and demolition (D4) activities at the White Bluffs Central Shops Area. 600-298 included eight subsites of surface debris and stained soil, 600-299 included six subsites and 600-300 included twelve subsites. The total material removed from all the areas was 2300 bank cubic meters. It was all disposed at ERDF.

Characterization soil samples were collected in March and April 2011. GPR scans were done over a time span from June 2011 through January 2013. The remediation activities removed soil and debris between January 31, 2012 through March 5, 2013. At 600-298, most areas were remediated to a depth of 0.9 meters (3 ft). 600-298:5 was excavated to a depth of 2.4 meters (8 ft). The depth of excavation at all the 600-299 and 600-300 areas was 0.3 meters (1 ft).

The SubSite is Part Of:

Code: 600-298

Names: 600-298; Surface Debris and Stained Soil in 100-IU-2

Code: 600-298:7

Classification: Accepted

Names: 600-298:7; Stained Soil/Surface Debris Area 7

Reclassification Final Closed Out (10/28/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The parent site and the subsites have been Final Closed Out. They were remediated and Interim Closed Out in a single document and Reclassification form (2013-040). The subsite consisted of a wooden floor like structure of approximately 1 by 2 meter (3 by 6 ft) with remnants of a thin stained layer of material. The site lacks vegetation.

Location: The site was located approximately 683 meters (0.4 miles) east of Federal Avenue and 706 meters (0.4 miles) north of Route 2 North in the former White Bluffs Community area. Area 7 is at E578778.82, N148051.95.

Closure Info: Interim (11/21/2013): (Interim Closed Out) The 600-298, 600-299 and 600-300 parent sites and their subsites have been remediated and Interim Closed Out in a single document and three Reclassification forms (2013-040, 2013-041, 2013-042).

The debris was left during deactivation, decontamination, decommissioning, and demolition (D4) activities at the White Bluffs Central Shops Area. 600-298 included eight subsites of surface debris and stained soil, 600-299 included six subsites and 600-300 included twelve subsites. The total material removed from all the areas was 2300 bank cubic meters. It was all disposed at ERDF.

Characterization soil samples were collected in March and April 2011. GPR scans were done over a time span from June 2011 through January 2013. The remediation activities removed soil and debris between January 31, 2012 through March 5, 2013. At 600-298, most areas were remediated to a depth of 0.9 meters (3 ft). 600-298:5 was excavated to a depth of 2.4 meters (8 ft). The depth of excavation at all the 600-299 and 600-300 areas was 0.3 meters (1 ft).

The SubSite is Part Of:

Code: 600-298

Names: 600-298; Surface Debris and Stained Soil in 100-IU-2

Code: 600-298:8 **Classification:** Accepted
Names: 600-298:8; Stained Soil/Surface Debris Area 8 **Reclassification** Final Closed Out (10/28/2015)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The parent site and the subsites have been Final Closed Out. They were remediated and Interim Closed Out in a single document and Reclassification form (2013-040). The subsite consisted of a wooden floor like structure of approximately 1 by 2 meters (3 by 6 ft) with remnants of a thin stained layer of material. The site lacks vegetation.

Location: The site was located approximately 811 meters (0.5 miles) east of Federal Avenue and 877 meters (0.5 miles) north of Route 2 North in the former White Bluffs Community area. Area 8 is at E578932.55, N148079.35.

Closure Info: Interim (11/21/2013): (Interim Closed Out) The 600-298, 600-299 and 600-300 parent sites and their subsites have been remediated and Interim Closed Out in a single document and three Reclassification forms (2013-040, 2013-041, 2013-042).

The debris was left during deactivation, decontamination, decommissioning, and demolition (D4) activities at the White Bluffs Central Shops Area. 600-298 included eight subsites of surface debris and stained soil, 600-299 included six subsites and 600-300 included twelve subsites. The total material removed from all the areas was 2300 bank cubic meters. It was all disposed at ERDF.

Characterization soil samples were collected in March and April 2011. GPR scans were done over a time span from June 2011 through January 2013. The remediation activities removed soil and debris between January 31, 2012 through March 5, 2013. At 600-298, most areas were remediated to a depth of 0.9 meters (3 ft). 600-298:5 was excavated to a depth of 2.4 meters (8 ft). The depth of excavation at all the 600-299 and 600-300 areas was 0.3 meters (1 ft).

The SubSite is Part Of:

Code: 600-298
Names: 600-298; Surface Debris and Stained Soil in 100-IU-2

Code: 600-299 **Classification:** Accepted
Names: 600-299; Surface Debris and Batteries **Reclassification** Final Closed Out (10/28/2015)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The parent site and the subsites have been remediated and Interim Closed Out in a single document and Reclassification form (2013-041). The parent and subsites were later Final Closed Out. The site consisted of six areas of scattered surface debris and batteries found during site walkdowns in 2007. The waste site was originally divided into five subsites. A sixth area was found later and became subsite 6.

Location: The walkdown area was located southwest of Route 2 North and south of Federal Avenue, adjacent to a powerline road.

Process Description: The debris and batteries are believed to have been discarded during the demolition of the White Bluffs Central Shop Area. Subsite 2 was in an old orchard area. From November 2006 to February 2007 a field walk-down of the 100-IU-2 Operable Unit was conducted as a final closure screening activity. The surface debris, which was identified as potentially containing

CERCLA hazardous substances, was precisely located and recorded using Global Positioning Satellite (GPS) technology, digital photography, and field logbook EL-1617. The field walk-down was completed in 30 meter by 30 meter grids that covered the Operable Unit. A hand-held global positioning system (GPS) was used to navigate each grid and to record the location of field observations. A digital camera was used to photograph each observation as recorded in a field logbook with the GPS record number. The GPS files with coordinates and attributes were downloaded daily to a database for plotting on a map and for maintaining the coordinates and observations electronically. The field walk-down of 100-IU-2 did not include known waste sites or posted areas. The field walk-down was limited to observations. No sampling was conducted. Potential CERCLA hazardous substances was found scattered throughout the Operable Unit at the coordinates provided. Observations of potential physical hazards, cultural artifacts, and nonhazardous, non-dangerous solid waste were also recorded.

Waste Type: Batteries

Waste Description: A dry cell battery is typically composed of zinc, ammonium chloride, zinc chloride, carbon and manganese (IV) oxide (http://en.wikipedia.org/wiki/Dry_cell). A wet cell battery may include lead and sulfuric acid as contaminants of potential concern.

Closure Info: Interim (11/21/2013): (Interim Closed Out) The 600-298, 600-299 and 600-300 parent sites and their subsites have been remediated and Interim Closed Out in a single document and three Reclassification forms (2013-040, 2013-041, 2013-042).

The debris was left during deactivation, decontamination, decommissioning, and demolition (D4) activities at the White Bluffs Central Shops Area. 600-298 included eight subsites of surface debris and stained soil, 600-299 included six subsites and 600-300 included twelve subsites. The total material removed from all the areas was 2300 bank cubic meters. It was all disposed at ERDF.

Characterization soil samples were collected in March and April 2011. GPR scans were done over a time span from June 2011 through January 2013. The remediation activities removed soil and debris between January 31, 2012 through March 5, 2013. At 600-298, most areas were remediated to a depth of 0.9 meters (3 ft). 600-298:5 was excavated to a depth of 2.4 meters (8 ft). The depth of excavation at all the 600-299 and 600-300 areas was 0.3 meters (1 ft).

Final (10/28/2015): (Final Closed Out) Based upon evaluation of the previous reclassification data against the 100-F/IU Area ROD cleanup levels, no further RTD is required for any of the 26 waste sites (Listed below).

600-279, Vegetation-Free Area Between White Bluffs and 100-F
 600-293, White Bluffs Service Station #1
 600-294, White Bluffs Service Station #2
 600-298, Stained Soil and Surface Debris
 600-299, Surface Debris/Batteries
 600-300, Miscellaneous Surface Debris
 600-301, White Bluffs Sanitary Sewer Pipelines
 600-303, Vertical Pipes
 600-316, Dry Cell Batteries
 600-318, Wet Cell Batteries
 600-320, Oil Stains
 600-321, Suspect ACM Sites
 600-328, Lead Slag
 600-356, Tar Deposit West of Susie Junction
 600-368, Segment 4 Stained Soil #1
 600-369, Segment 4 Bare Ground and Crusted Soil Areas
 600-370, Segment 4 Debris Area #1

600-371, Segment 4 Chalky Material Area
 600-372, Segment 4 Oil Stain and Filter Area #1
 600-373, Segment 4 Bare Ground and White Stain Area
 600-374, Segment 4 Drum Remnant Area
 600-375, Segment 4 Dry Cell Battery Debris Area #1
 600-376, Segment 4 Stained Soil Area #2
 600-377, Segment 4 Oil Stain and Filter Area #2
 600-378, 506 Telephone Exchange Emergency Generator Building Underground Fuel Storage tank
 600-379, Segment 4 Burn Area #1.

The Reclassification to Final Closed Out applies to all subsites associated with the waste sites listed above.

This Site has the Following SubSites:

Code: 600-299:1
Names: 600-299:1; Surface Debris and Batteries Area 1

Code: 600-299:2
Names: 600-299:2; Surface Debris/Batteries Area 2

Code: 600-299:3
Names: 600-299:3; Surface Debris/Batteries Area 3

Code: 600-299:4
Names: 600-299:4; Surface Debris/Batteries Area 4

Code: 600-299:5
Names: 600-299:5; Surface Debris/Batteries Area 5

Code: 600-299:6
Names: 600-299:6; Debris and Soil From White Bluffs Central Shop Area

Code: 600-299:1	Classification: Accepted
Names: 600-299:1; Surface Debris and Batteries Area 1	Reclassification: Final Closed Out (10/28/2015)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The parent site and the subsites have been remediated, Interim Closed Out and Final Closed Out. The subsite consisted of scattered remnants of batteries that are located through out the area. Most have been removed with the exception of what appear to be thousands of wet cell battery caps. Yellow staining of the soil is found in some places.

Location: The site was located approximately 724 meters (0.4 miles) west of Federal Avenue and 599 meters (0.4 miles) south of Route 2 North in the former White Bluffs Community area. Location 1 is at E577373.69, N148034.57.

Closure Info: Interim (11/21/2013): (Interim Closed Out) The 600-298, 600-299 and 600-300 parent sites and their subsites have been remediated and Interim Closed Out in a single document and three Reclassification forms (2013-040, 2013-041, 2013-042).

The debris was left during deactivation, decontamination, decommissioning, and demolition (D4) activities at the White Bluffs Central Shops Area. 600-298 included eight subsites of surface debris and stained soil, 600-299 included six subsites and 600-300 included twelve subsites. The total material removed from all the areas was 2300 bank cubic meters. It was all

disposed at ERDF.

Characterization soil samples were collected in March and April 2011. GPR scans were done over a time span from June 2011 through January 2013. The remediation activities removed soil and debris between January 31, 2012 through March 5, 2013. At 600-298, most areas were remediated to a depth of 0.9 meters (3 ft). 600-298:5 was excavated to a depth of 2.4 meters (8 ft). The depth of excavation at all the 600-299 and 600-300 areas was 0.3 meters (1 ft).

The SubSite is Part Of:

Code: 600-299

Names: 600-299; Surface Debris and Batteries

Code: 600-299:2

Classification: Accepted

Names: 600-299:2; Surface Debris/Batteries Area 2

Reclassification Final Closed Out (10/28/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The parent site and the subsites have been remediated, Interim Closed Out and Final Closed Out. The subsite consisted of a 6 volt wet cell car battery in a small dump site.

Location: The site was located approximately 452 meters (0.3 miles) east of Federal Avenue and 2.5 kilometers (1.6 miles) north of Route 2 North. It is north of the 100-F Area. Location 2 is at E579511.89, N149122.25.

Closure Info: Interim (11/21/2013): (Interim Closed Out) The 600-298, 600-299 and 600-300 parent sites and their subsites have been remediated and Interim Closed Out in a single document and three Reclassification forms (2013-040, 2013-041, 2013-042).

The debris was left during deactivation, decontamination, decommissioning, and demolition (D4) activities at the White Bluffs Central Shops Area. 600-298 included eight subsites of surface debris and stained soil, 600-299 included six subsites and 600-300 included twelve subsites. The total material removed from all the areas was 2300 bank cubic meters. It was all disposed at ERDF.

Characterization soil samples were collected in March and April 2011. GPR scans were done over a time span from June 2011 through January 2013. The remediation activities removed soil and debris between January 31, 2012 through March 5, 2013. At 600-298, most areas were remediated to a depth of 0.9 meters (3 ft). 600-298:5 was excavated to a depth of 2.4 meters (8 ft). The depth of excavation at all the 600-299 and 600-300 areas was 0.3 meters (1 ft).

The SubSite is Part Of:

Code: 600-299

Names: 600-299; Surface Debris and Batteries

Code: 600-299:3

Classification: Accepted

Names: 600-299:3; Surface Debris/Batteries Area 3

Reclassification Final Closed Out (10/28/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The parent site and the subsites have been remediated, Interim Closed Out and Final Closed Out. The subsite consisted of a pile of old dry cell batteries in a degraded condition covering an

area approximately 1 meters (3 ft) in diameter.

Location: The site was located approximately 199 meters (653 ft) south of Federal Avenue and 2.2 kilometers (1.4 miles) west of Route 2 North in the former White Bluffs Community area. Location 3 is at E576993.83, N146932.63.

Closure Info: Interim (11/21/2013): (Interim Closed Out) The 600-298, 600-299 and 600-300 parent sites and their subsites have been remediated and Interim Closed Out in a single document and three Reclassification forms (2013-040, 2013-041, 2013-042).

The debris was left during deactivation, decontamination, decommissioning, and demolition (D4) activities at the White Bluffs Central Shops Area. 600-298 included eight subsites of surface debris and stained soil, 600-299 included six subsites and 600-300 included twelve subsites. The total material removed from all the areas was 2300 bank cubic meters. It was all disposed at ERDF.

Characterization soil samples were collected in March and April 2011. GPR scans were done over a time span from June 2011 through January 2013. The remediation activities removed soil and debris between January 31, 2012 through March 5, 2013. At 600-298, most areas were remediated to a depth of 0.9 meters (3 ft). 600-298:5 was excavated to a depth of 2.4 meters (8 ft). The depth of excavation at all the 600-299 and 600-300 areas was 0.3 meters (1 ft).

The SubSite is Part Of:

Code: 600-299

Names: 600-299; Surface Debris and Batteries

Code: 600-299:4

Classification: Accepted

Names: 600-299:4; Surface Debris/Batteries Area 4

Reclassification Final Closed Out (10/28/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The parent site and the subsites have been remediated, Interim Closed Out and Final Closed Out. The subsite consisted of a few scattered batteries in an area less than 1 meter (3 ft) in diameter amongst scattered debris (e.g. metal cans, containers and broken glass) from a pre-Hanford agricultural dump site.

Location: The site was located approximately 239 meters (784 ft) south of Federal Avenue and 2.2 kilometers (1.4 miles) west of Route 2 North in the former White Bluffs Community area. Location 4 is at E577025.33, N146914.90.

Closure Info: Interim (11/21/2013): (Interim Closed Out) The 600-298, 600-299 and 600-300 parent sites and their subsites have been remediated and Interim Closed Out in a single document and three Reclassification forms (2013-040, 2013-041, 2013-042).

The debris was left during deactivation, decontamination, decommissioning, and demolition (D4) activities at the White Bluffs Central Shops Area. 600-298 included eight subsites of surface debris and stained soil, 600-299 included six subsites and 600-300 included twelve subsites. The total material removed from all the areas was 2300 bank cubic meters. It was all disposed at ERDF.

Characterization soil samples were collected in March and April 2011. GPR scans were done over a time span from June 2011 through January 2013. The remediation activities removed soil and debris between January 31, 2012 through March 5, 2013. At 600-298, most areas were remediated to a depth of 0.9 meters (3 ft). 600-298:5 was excavated to a depth of 2.4 meters (8

ft). The depth of excavation at all the 600-299 and 600-300 areas was 0.3 meters (1 ft).

The SubSite is Part Of:

Code: 600-299

Names: 600-299; Surface Debris and Batteries

Code: 600-299:5

Classification: Accepted

Names: 600-299:5; Surface Debris/Batteries Area 5

Reclassification Final Closed Out (10/28/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The parent site and the subsites have been remediated and Interim Closed Out in a single document and Reclassification form (2013-041). The subsite consisted of a concentration of degraded dry cell batteries in a 1 meter (3 ft) diameter area.

Location: The site was located approximately 82 meters (269 ft) south of Federal Avenue and 2.0 kilometers (1.2 miles) west of Route 2 North in the former White Bluffs Community area. Location 5 is at E577025.06, N147071.93.

Closure Info: Interim (11/21/2013): (Interim Closed Out) The 600-298, 600-299 and 600-300 parent sites and their subsites have been remediated and Interim Closed Out in a single document and three Reclassification forms (2013-040, 2013-041, 2013-042).

The debris was left during deactivation, decontamination, decommissioning, and demolition (D4) activities at the White Bluffs Central Shops Area. 600-298 included eight subsites of surface debris and stained soil, 600-299 included six subsites and 600-300 included twelve subsites. The total material removed from all the areas was 2300 bank cubic meters. It was all disposed at ERDF.

Characterization soil samples were collected in March and April 2011. GPR scans were done over a time span from June 2011 through January 2013. The remediation activities removed soil and debris between January 31, 2012 through March 5, 2013. At 600-298, most areas were remediated to a depth of 0.9 meters (3 ft). 600-298:5 was excavated to a depth of 2.4 meters (8 ft). The depth of excavation at all the 600-299 and 600-300 areas was 0.3 meters (1 ft).

The SubSite is Part Of:

Code: 600-299

Names: 600-299; Surface Debris and Batteries

Code: 600-299:6

Classification: Accepted

Names: 600-299:6; Debris and Soil From White Bluffs Central Shop Area

Reclassification Final Closed Out (10/28/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The subsite was debris and soil from the demolition of the White Bluffs Central Shop Area. It was remediated in May 2012.

Location: Subsite 6 was located at coordinates N147736.9 E578863.5.

Closure Info: Interim (11/21/2013): (Interim Closed Out) The 600-298, 600-299 and 600-300 parent sites and

their subsites have been remediated and Interim Closed Out in a single document and three Reclassification forms (2013-040, 2013-041, 2013-042).

The debris was left during deactivation, decontamination, decommissioning, and demolition (D4) activities at the White Bluffs Central Shops Area. 600-298 included eight subsites of surface debris and stained soil, 600-299 included six subsites and 600-300 included twelve subsites. The total material removed from all the areas was 2300 bank cubic meters. It was all disposed at ERDF.

Characterization soil samples were collected in March and April 2011. GPR scans were done over a time span from June 2011 through January 2013. The remediation activities removed soil and debris between January 31, 2012 through March 5, 2013. At 600-298, most areas were remediated to a depth of 0.9 meters (3 ft). 600-298:5 was excavated to a depth of 2.4 meters (8 ft). The depth of excavation at all the 600-299 and 600-300 areas was 0.3 meters (1 ft).

The SubSite is Part Of:

Code: 600-299

Names: 600-299; Surface Debris and Batteries

Code: 600-300

Classification: Accepted

Names: 600-300; Miscellaneous Surface Debris Sites

Reclassification Final Closed Out (10/28/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The parent site and the subsites have been remediated, Interim Closed Out and later Final Closed Out. The site consisted of twelve areas containing miscellaneous scattered debris. The site was divided into twelve subsites.

Location: The walkdown area was near the previous White Bluffs community.

Process Description: Various sizes and forms of CERCLA surface debris were created during the construction, operating, and decontamination and decommissioning (D) activities within the 100-IU-2 Operable Unit (OU). From November 2006 to February 2007 a field walk-down of the OU was conducted as a final closure screening activity. Surface debris, which was identified as potentially containing CERCLA hazardous substances, was precisely located and recorded using a hand-held Global Positioning Satellite (GPS) unit, digital photography, and documented in field logbook EL-1617. The field walk-down was completed in 30 meter by 30 meter grids that covered the Operable Unit. A hand-held global positioning unit (GPS) was used to navigate each grid and record the location of field observations. A digital camera was used to photograph each observation as recorded in a field logbook with the GPS record number. The GPS files with coordinates and attributes were downloaded daily for post-processing and data correction and for maintaining the coordinates and observations electronically. The digital camera files were downloaded daily to a dated folder on a share drive for coordination of photos with GPS data and the field logbook entries into EL-1617.

Closure Info: Interim (11/21/2013): (Interim Closed Out) The 600-298, 600-299 and 600-300 parent sites and their subsites have been remediated and Interim Closed Out in a single document and three Reclassification forms (2013-040, 2013-041, 2013-042).

The debris was left during deactivation, decontamination, decommissioning, and demolition (D4) activities at the White Bluffs Central Shops Area. 600-298 included eight subsites of surface debris and stained soil, 600-299 included six subsites and 600-300 included twelve subsites. The total material removed from all the areas was 2300 bank cubic meters. It was all disposed at ERDF.

Characterization soil samples were collected in March and April 2011. GPR scans were done over a time span from June 2011 through January 2013. The remediation activities removed soil and debris between January 31, 2012 through March 5, 2013. At 600-298, most areas were remediated to a depth of 0.9 meters (3 ft). 600-298:5 was excavated to a depth of 2.4 meters (8 ft). The depth of excavation at all the 600-299 and 600-300 areas was 0.3 meters (1 ft).

Final (10/28/2015): (Final Closed Out) Based upon evaluation of the previous reclassification data against the 100-F/IU Area ROD cleanup levels, no further RTD is required for any of the 26 waste sites (Listed below).

600-279, Vegetation-Free Area Between White Bluffs and 100-F
 600-293, White Bluffs Service Station #1
 600-294, White Bluffs Service Station #2
 600-298, Stained Soil and Surface Debris
 600-299, Surface Debris/Batteries
 600-300, Miscellaneous Surface Debris
 600-301, White Bluffs Sanitary Sewer Pipelines
 600-303, Vertical Pipes
 600-316, Dry Cell Batteries
 600-318, Wet Cell Batteries
 600-320, Oil Stains
 600-321, Suspect ACM Sites
 600-328, Lead Slag
 600-356, Tar Deposit West of Susie Junction
 600-368, Segment 4 Stained Soil #1
 600-369, Segment 4 Bare Ground and Crusted Soil Areas
 600-370, Segment 4 Debris Area #1
 600-371, Segment 4 Chalky Material Area
 600-372, Segment 4 Oil Stain and Filter Area #1
 600-373, Segment 4 Bare Ground and White Stain Area
 600-374, Segment 4 Drum Remnant Area
 600-375, Segment 4 Dry Cell Battery Debris Area #1
 600-376, Segment 4 Stained Soil Area #2
 600-377, Segment 4 Oil Stain and Filter Area #2
 600-378, 506 Telephone Exchange Emergency Generator Building Underground Fuel Storage tank
 600-379, Segment 4 Burn Area #1.

The Reclassification to Final Closed Out applies to all subsites associated with the waste sites listed above.

This Site has the Following SubSites:

Code: 600-300:1
Names: 600-300:1; Miscellaneous Surface Debris Area 1

Code: 600-300:2
Names: 600-300:2; Miscellaneous Surface Debris Area 2

Code: 600-300:3
Names: 600-300:3; Miscellaneous Surface Debris Area 3

Code: 600-300:4
Names: 600-300:4; Miscellaneous Surface Debris Area 4

Code: 600-300:5
Names: 600-300:5; Miscellaneous Surface Debris Area 5

Code: 600-300:6
Names: 600-300:6; Miscellaneous Surface Debris Area 6

Code: 600-300:7
Names: 600-300:7; Miscellaneous Surface Debris Area 7

Code: 600-300:8
Names: 600-300:8; Miscellaneous Surface Debris Area 8

Code: 600-300:9
Names: 600-300:9; Miscellaneous Surface Debris Area 9

Code: 600-300:10
Names: 600-300:10; Miscellaneous Surface Debris Area 10

Code: 600-300:11
Names: 600-300:11; Miscellaneous Surface Debris Area 11

Code: 600-300:12
Names: 600-300:12; Miscellaneous Surface Debris Area 12

Code: 600-300:1 **Classification:** Accepted
Names: 600-300:1; Miscellaneous Surface Debris Area 1 **Reclassification:** Final Closed Out (10/28/2015)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The parent site and the subsites have been remediated and Interim Closed Out in a single document and Reclassification form (2013-042). They were later Final Closed Out. The subsite consisted of a single 208 liter (55 gallon) drum with the lid missing and tar inside. The drum was approximately 50% full.

Location: The site was located approximately 112 meters (367 ft) west of Federal Avenue and 1.2 kilometers (0.75 miles) south of Route 2 North in the former White Bluffs Community area. Location 1 is at E577313.36, N147454.43.

Closure Info: Interim (11/21/2013): (Interim Closed Out) The 600-298, 600-299 and 600-300 parent sites and their subsites have been remediated and Interim Closed Out in a single document and three Reclassification forms (2013-040, 2013-041, 2013-042).

The debris was left during deactivation, decontamination, decommissioning, and demolition (D4) activities at the White Bluffs Central Shops Area. 600-298 included eight subsites of surface debris and stained soil, 600-299 included six subsites and 600-300 included twelve subsites. The total material removed from all the areas was 2300 bank cubic meters. It was all disposed at ERDF.

Characterization soil samples were collected in March and April 2011. GPR scans were done over a time span from June 2011 through January 2013. The remediation activities removed soil and debris between January 31, 2012 through March 5, 2013. At 600-298, most areas were remediated to a depth of 0.9 meters (3 ft). 600-298:5 was excavated to a depth of 2.4 meters (8 ft). The depth of excavation at all the 600-299 and 600-300 areas was 0.3 meters (1 ft).

The SubSite is Part Of:

Code: 600-300
Names: 600-300; Miscellaneous Surface Debris Sites

Code: 600-300:2 **Classification:** Accepted
Names: 600-300:2; Miscellaneous Surface Debris Area 2 **Reclassification** Final Closed Out (10/28/2015)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The parent site and the subsites have been remediated and Interim Closed Out in a single document and Reclassification form (2013-042). They were later Final Closed Out. The subsite consisted of a 2 by 2 meter (6.6 by 6.6 ft) area with dried, bright yellow paint chips.

Location: The site was located approximately 61 meters (200 ft) west of Federal Avenue and 858 meters (0.5 miles) south of Route 2 North in the former White Bluffs Community area. Location 2 is at coordinates E577567.28 N147603.22.

Closure Info: Interim (11/21/2013): (Interim Closed Out) The 600-298, 600-299 and 600-300 parent sites and their subsites have been remediated and Interim Closed Out in a single document and three Reclassification forms (2013-040, 2013-041, 2013-042).

The debris was left during deactivation, decontamination, decommissioning, and demolition (D4) activities at the White Bluffs Central Shops Area. 600-298 included eight subsites of surface debris and stained soil, 600-299 included six subsites and 600-300 included twelve subsites. The total material removed from all the areas was 2300 bank cubic meters. It was all disposed at ERDF.

Characterization soil samples were collected in March and April 2011. GPR scans were done over a time span from June 2011 through January 2013. The remediation activities removed soil and debris between January 31, 2012 through March 5, 2013. At 600-298, most areas were remediated to a depth of 0.9 meters (3 ft). 600-298:5 was excavated to a depth of 2.4 meters (8 ft). The depth of excavation at all the 600-299 and 600-300 areas was 0.3 meters (1 ft).

The SubSite is Part Of:

Code: 600-300
Names: 600-300; Miscellaneous Surface Debris Sites

Code: 600-300:3 **Classification:** Accepted
Names: 600-300:3; Miscellaneous Surface Debris Area 3 **Reclassification** Final Closed Out (10/28/2015)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The parent site and the subsites have been remediated and Interim Closed Out in a single document and Reclassification form (2013-042). They were later Final Closed Out. The subsite consisted of a 7.6 liter (2 gal) bucket that is approximately two-thirds full of what appears to be paint.

Location: The site was located approximately 1.2 kilometers (0.75 miles) east of Federal Avenue and 790 meters (0.5 miles) south of Route 2 North in the former White Bluffs Community area. Location 3 is at E578207.22, N147124.71.

Closure Info: Interim (11/21/2013): (Interim Closed Out) The 600-298, 600-299 and 600-300 parent sites and their subsites have been remediated and Interim Closed Out in a single document and three

Reclassification forms (2013-040, 2013-041, 2013-042).

The debris was left during deactivation, decontamination, decommissioning, and demolition (D4) activities at the White Bluffs Central Shops Area. 600-298 included eight subsites of surface debris and stained soil, 600-299 included six subsites and 600-300 included twelve subsites. The total material removed from all the areas was 2300 bank cubic meters. It was all disposed at ERDF.

Characterization soil samples were collected in March and April 2011. GPR scans were done over a time span from June 2011 through January 2013. The remediation activities removed soil and debris between January 31, 2012 through March 5, 2013. At 600-298, most areas were remediated to a depth of 0.9 meters (3 ft). 600-298:5 was excavated to a depth of 2.4 meters (8 ft). The depth of excavation at all the 600-299 and 600-300 areas was 0.3 meters (1 ft).

The SubSite is Part Of:

Code: 600-300

Names: 600-300; Miscellaneous Surface Debris Sites

Code: 600-300:4

Classification: Accepted

Names: 600-300:4; Miscellaneous Surface Debris Area 4

Reclassification Final Closed Out (10/28/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The parent site and the subsites have been remediated and Interim Closed Out in a single document and Reclassification form (2013-042). They were later Final Closed Out. The subsite consisted of an enclosed, 19 liter (5 gal) container. It appeared to be mostly empty but field personnel were not sure. This container may have been used for desiccant or other dry materials.

Location: The site was located approximately 792 meters (0.5 miles) east of Federal Avenue and 260 meters (853 feet) south of Route 2 North in the former White Bluffs Community area. Location 4 is at E578306.11, N147516.74.

Closure Info: Interim (11/21/2013): (Interim Closed Out) The 600-298, 600-299 and 600-300 parent sites and their subsites have been remediated and Interim Closed Out in a single document and three Reclassification forms (2013-040, 2013-041, 2013-042).

The debris was left during deactivation, decontamination, decommissioning, and demolition (D4) activities at the White Bluffs Central Shops Area. 600-298 included eight subsites of surface debris and stained soil, 600-299 included six subsites and 600-300 included twelve subsites. The total material removed from all the areas was 2300 bank cubic meters. It was all disposed at ERDF.

Characterization soil samples were collected in March and April 2011. GPR scans were done over a time span from June 2011 through January 2013. The remediation activities removed soil and debris between January 31, 2012 through March 5, 2013. At 600-298, most areas were remediated to a depth of 0.9 meters (3 ft). 600-298:5 was excavated to a depth of 2.4 meters (8 ft). The depth of excavation at all the 600-299 and 600-300 areas was 0.3 meters (1 ft).

The SubSite is Part Of:

Code: 600-300

Names: 600-300; Miscellaneous Surface Debris Sites

Code: 600-300:5 **Classification:** Accepted
Names: 600-300:5; Miscellaneous Surface Debris Area 5 **Reclassification** Final Closed Out (10/28/2015)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The parent site and the subsites have been remediated and Interim Closed Out in a single document and Reclassification form (2013-042). They were later Final Closed Out. The subsite consisted of various containers ranging in size from 2 to 9 liters (0.5 to 5 gallons). Some are empty while others are partially full of suspect petroleum product. There are approximately ten containers in a 3 by 3 meter (10 by 10 ft) area.

Location: The site was located approximately 1 kilometer (0.6 miles) west of Route 2 North and 1.4 kilometers (0.9 miles) north of Route 1 in the former White Bluffs Community area. Location 5 was at E578472.68, N146629.03.

Closure Info: Interim (11/21/2013): (Interim Closed Out) The 600-298, 600-299 and 600-300 parent sites and their subsites have been remediated and Interim Closed Out in a single document and three Reclassification forms (2013-040, 2013-041, 2013-042).

The debris was left during deactivation, decontamination, decommissioning, and demolition (D4) activities at the White Bluffs Central Shops Area. 600-298 included eight subsites of surface debris and stained soil, 600-299 included six subsites and 600-300 included twelve subsites. The total material removed from all the areas was 2300 bank cubic meters. It was all disposed at ERDF.

Characterization soil samples were collected in March and April 2011. GPR scans were done over a time span from June 2011 through January 2013. The remediation activities removed soil and debris between January 31, 2012 through March 5, 2013. At 600-298, most areas were remediated to a depth of 0.9 meters (3 ft). 600-298:5 was excavated to a depth of 2.4 meters (8 ft). The depth of excavation at all the 600-299 and 600-300 areas was 0.3 meters (1 ft).

The SubSite is Part Of:

Code: 600-300
Names: 600-300; Miscellaneous Surface Debris Sites

Code: 600-300:6 **Classification:** Accepted
Names: 600-300:6; Miscellaneous Surface Debris Area 6 **Reclassification** Final Closed Out (10/28/2015)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The parent site and the subsites have been remediated and Interim Closed Out in a single document and Reclassification form (2013-042). They were later Final Closed Out. The subsite consisted of an unknown white solid substance spilling out of a ruptured rusty metal can that is approximately 1 liter (0.26 gal) in size.

Location: The site was located approximately 16 meters (52 ft) east of Federal Avenue and 256 meters (840 ft) north of Route 2 North in the former White Bluffs Community area. Location 6 was at E578215.89, N148148.50.

Closure Info: Interim (11/21/2013): (Interim Closed Out) The 600-298, 600-299 and 600-300 parent sites and their subsites have been remediated and Interim Closed Out in a single document and three Reclassification forms (2013-040, 2013-041, 2013-042).

The debris was left during deactivation, decontamination, decommissioning, and demolition (D4) activities at the White Bluffs Central Shops Area. 600-298 included eight subsites of surface debris and stained soil, 600-299 included six subsites and 600-300 included twelve subsites. The total material removed from all the areas was 2300 bank cubic meters. It was all disposed at ERDF.

Characterization soil samples were collected in March and April 2011. GPR scans were done over a time span from June 2011 through January 2013. The remediation activities removed soil and debris between January 31, 2012 through March 5, 2013. At 600-298, most areas were remediated to a depth of 0.9 meters (3 ft). 600-298:5 was excavated to a depth of 2.4 meters (8 ft). The depth of excavation at all the 600-299 and 600-300 areas was 0.3 meters (1 ft).

The SubSite is Part Of:**Code:** 600-300**Names:** 600-300; Miscellaneous Surface Debris Sites**Code:** 600-300:7**Classification:** Accepted**Names:** 600-300:7; Miscellaneous Surface Debris Area 7**Reclassification:** Final Closed Out (10/28/2015)**Type:** Unplanned Release**Start Date:****Status:** Inactive**End Date:****Description:** The parent site and the subsites have been remediated and Interim Closed Out in a single document and Reclassification form (2013-042). They were later Final Closed Out. The subsite consisted of an unknown white solid substance spilling out of a ruptured rusty metal can that is approximately 1 liter (0.26 gal) in size.**Location:** The site was located approximately 65 meters (213 ft) east of Federal Avenue and 303 meters (994 ft) north of Route 2 North in the former White Bluffs Community area. Location 7 was at E578255.86, N148140.41.**Closure Info:** Interim (11/21/2013): (Interim Closed Out) The 600-298, 600-299 and 600-300 parent sites and their subsites have been remediated and Interim Closed Out in a single document and three Reclassification forms (2013-040, 2013-041, 2013-042).

The debris was left during deactivation, decontamination, decommissioning, and demolition (D4) activities at the White Bluffs Central Shops Area. 600-298 included eight subsites of surface debris and stained soil, 600-299 included six subsites and 600-300 included twelve subsites. The total material removed from all the areas was 2300 bank cubic meters. It was all disposed at ERDF.

Characterization soil samples were collected in March and April 2011. GPR scans were done over a time span from June 2011 through January 2013. The remediation activities removed soil and debris between January 31, 2012 through March 5, 2013. At 600-298, most areas were remediated to a depth of 0.9 meters (3 ft). 600-298:5 was excavated to a depth of 2.4 meters (8 ft). The depth of excavation at all the 600-299 and 600-300 areas was 0.3 meters (1 ft).

The SubSite is Part Of:**Code:** 600-300**Names:** 600-300; Miscellaneous Surface Debris Sites**Code:** 600-300:8**Classification:** Accepted

Names: 600-300:8; Miscellaneous Surface Debris Area 8 **Reclassification** Final Closed Out (10/28/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The parent site and the subsites have been remediated and Interim Closed Out in a single document and Reclassification form (2013-042). They were later Final Closed Out. The subsite consisted of an unknown white solid substance spilling out of a ruptured rusty metal can that is approximately 1 liter (0.26 gal) in size.

Location: The site was located approximately 154 meters (505 ft) east of Federal Avenue and 365 meters (0.2 miles) north of Route 2 North in the former White Bluffs Community area. Location 8 was at E578325.26, N148123.24.

Closure Info: Interim (11/21/2013): (Interim Closed Out) The 600-298, 600-299 and 600-300 parent sites and their subsites have been remediated and Interim Closed Out in a single document and three Reclassification forms (2013-040, 2013-041, 2013-042).

The debris was left during deactivation, decontamination, decommissioning, and demolition (D4) activities at the White Bluffs Central Shops Area. 600-298 included eight subsites of surface debris and stained soil, 600-299 included six subsites and 600-300 included twelve subsites. The total material removed from all the areas was 2300 bank cubic meters. It was all disposed at ERDF.

Characterization soil samples were collected in March and April 2011. GPR scans were done over a time span from June 2011 through January 2013. The remediation activities removed soil and debris between January 31, 2012 through March 5, 2013. At 600-298, most areas were remediated to a depth of 0.9 meters (3 ft). 600-298:5 was excavated to a depth of 2.4 meters (8 ft). The depth of excavation at all the 600-299 and 600-300 areas was 0.3 meters (1 ft).

The SubSite is Part Of:

Code: 600-300

Names: 600-300; Miscellaneous Surface Debris Sites

Code: 600-300:9

Classification: Accepted

Names: 600-300:9; Miscellaneous Surface Debris Area 9

Reclassification Final Closed Out (10/28/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The parent site and the subsites have been remediated and Interim Closed Out in a single document and Reclassification form (2013-042). They were later Final Closed Out. The subsite consisted of an intact rusted 113 liter (30 gallon) drum. There is no way to determine whether or not the drum is empty.

Location: The site was located approximately 562 meters (0.3 miles) east of Federal Avenue and 854 meters (0.5 miles) north of Route 2 North in the former White Bluffs Community area. Location 9 was at E578791.64, N148183.62.

Closure Info: Interim (11/21/2013): (Interim Closed Out) The 600-298, 600-299 and 600-300 parent sites and their subsites have been remediated and Interim Closed Out in a single document and three Reclassification forms (2013-040, 2013-041, 2013-042).

The debris was left during deactivation, decontamination, decommissioning, and demolition (D4) activities at the White Bluffs Central Shops Area. 600-298 included eight subsites of

surface debris and stained soil, 600-299 included six subsites and 600-300 included twelve subsites. The total material removed from all the areas was 2300 bank cubic meters. It was all disposed at ERDF.

Characterization soil samples were collected in March and April 2011. GPR scans were done over a time span from June 2011 through January 2013. The remediation activities removed soil and debris between January 31, 2012 through March 5, 2013. At 600-298, most areas were remediated to a depth of 0.9 meters (3 ft). 600-298:5 was excavated to a depth of 2.4 meters (8 ft). The depth of excavation at all the 600-299 and 600-300 areas was 0.3 meters (1 ft).

The SubSite is Part Of:

Code: 600-300

Names: 600-300; Miscellaneous Surface Debris Sites

Code: 600-300:10

Classification: Accepted

Names: 600-300:10; Miscellaneous Surface Debris Area
10

Reclassification Final Closed Out (10/28/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The parent site and the subsites have been remediated and Interim Closed Out in a single document and Reclassification form (2013-042). They were later Final Closed Out. The subsite consisted of a single 208 liter (55 gal) drum partially buried and mangled. It is not possible to determine if the drum is empty.

Location: The site was located approximately 620 meters (0.4 miles) east of Federal Avenue and 837 meters (0.5 miles) north of Route 2 North in the former White Bluffs Community area. Location 10 is at E578816.36, N148146.06.

Closure Info: Interim (11/21/2013): (Interim Closed Out) The 600-298, 600-299 and 600-300 parent sites and their subsites have been remediated and Interim Closed Out in a single document and three Reclassification forms (2013-040, 2013-041, 2013-042).

The debris was left during deactivation, decontamination, decommissioning, and demolition (D4) activities at the White Bluffs Central Shops Area. 600-298 included eight subsites of surface debris and stained soil, 600-299 included six subsites and 600-300 included twelve subsites. The total material removed from all the areas was 2300 bank cubic meters. It was all disposed at ERDF.

Characterization soil samples were collected in March and April 2011. GPR scans were done over a time span from June 2011 through January 2013. The remediation activities removed soil and debris between January 31, 2012 through March 5, 2013. At 600-298, most areas were remediated to a depth of 0.9 meters (3 ft). 600-298:5 was excavated to a depth of 2.4 meters (8 ft). The depth of excavation at all the 600-299 and 600-300 areas was 0.3 meters (1 ft).

The SubSite is Part Of:

Code: 600-300

Names: 600-300; Miscellaneous Surface Debris Sites

Code: 600-300:11

Classification: Accepted

Names: 600-300:11; Miscellaneous Surface Debris Area
11

Reclassification Final Closed Out (10/28/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The parent site and the subsites have been remediated and Interim Closed Out in a single document and Reclassification form (2013-042). They were later Final Closed Out. The subsite consisted of a single 208 liter (55 gal) drum partially buried and mangled. It is not possible to determine if the drum is empty.

Location: The site was located approximately 798 meters (0.5 miles) west of Federal Avenue and 1.9 kilometers (1.2 miles) north of Route 2 North in the former White Bluffs Community area. Location 11 is at E578578.30, N149408.50.

Closure Info: Interim (11/21/2013): (Interim Closed Out) The 600-298, 600-299 and 600-300 parent sites and their subsites have been remediated and Interim Closed Out in a single document and three Reclassification forms (2013-040, 2013-041, 2013-042).

The debris was left during deactivation, decontamination, decommissioning, and demolition (D4) activities at the White Bluffs Central Shops Area. 600-298 included eight subsites of surface debris and stained soil, 600-299 included six subsites and 600-300 included twelve subsites. The total material removed from all the areas was 2300 bank cubic meters. It was all disposed at ERDF.

Characterization soil samples were collected in March and April 2011. GPR scans were done over a time span from June 2011 through January 2013. The remediation activities removed soil and debris between January 31, 2012 through March 5, 2013. At 600-298, most areas were remediated to a depth of 0.9 meters (3 ft). 600-298:5 was excavated to a depth of 2.4 meters (8 ft). The depth of excavation at all the 600-299 and 600-300 areas was 0.3 meters (1 ft).

The SubSite is Part Of:

Code: 600-300

Names: 600-300; Miscellaneous Surface Debris Sites

Code: 600-300:12

Classification: Accepted

Names: 600-300:12; Miscellaneous Surface Debris Area 12

Reclassification: Final Closed Out (10/28/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The parent site and the subsites have been remediated and Interim Closed Out in a single document and Reclassification form (2013-042). They were later Final Closed Out. The subsite consisted of concentrated area rusted metal including metal turnings, wood and one dry cell battery. There was no vegetation in about a 1 meter (3 ft) diameter area.

Location: The site was located just outside the 100-F Area approximately 914 meters (0.6 miles) east of Federal Avenue and 2.1 kilometers (1.3 miles) north of Route 2 North. Location 12 is at E579583.47, N148621.43.

Closure Info: Interim (11/21/2013): (Interim Closed Out) The 600-298, 600-299 and 600-300 parent sites and their subsites have been remediated and Interim Closed Out in a single document and three Reclassification forms (2013-040, 2013-041, 2013-042).

The debris was left during deactivation, decontamination, decommissioning, and demolition (D4) activities at the White Bluffs Central Shops Area. 600-298 included eight subsites of

surface debris and stained soil, 600-299 included six subsites and 600-300 included twelve subsites. The total material removed from all the areas was 2300 bank cubic meters. It was all disposed at ERDF.

Characterization soil samples were collected in March and April 2011. GPR scans were done over a time span from June 2011 through January 2013. The remediation activities removed soil and debris between January 31, 2012 through March 5, 2013. At 600-298, most areas were remediated to a depth of 0.9 meters (3 ft). 600-298:5 was excavated to a depth of 2.4 meters (8 ft). The depth of excavation at all the 600-299 and 600-300 areas was 0.3 meters (1 ft).

The SubSite is Part Of:

Code: 600-300

Names: 600-300; Miscellaneous Surface Debris Sites

Code: 600-301

Classification: Accepted

Names: 600-301; White Bluffs Sanitary Sewer Pipelines

Reclassification: Final Closed Out (10/28/2015)

Type: Sanitary Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site has been remediated, Interim Closed Out and later Final Closed Out. It consisted of the sewer pipelines in the White Bluffs area. It included five components consisting of the historical sewer system and underlying soils documented on construction drawing H-11-3709 and four suspected, related features discovered during the Orphan Site Evaluation (OSE) field investigation.

The first related feature was at coordinates E578241/N148296. It consisted of two square holes about 0.5 meters (1.5 feet) deep with 2 clay pipes protruding upward, but still below grade level. The holes were approximately 1 by 1 meter (3 by 3 feet) square and 2 meters (6 feet) apart. It is not known whether this feature is associated with a pre-Hanford farmstead or is a potentially a component of the sanitary sewer system of White Bluffs.

The second related feature was at coordinates E578309.8/N147971.6. It consisted of a 1 meter (3 foot) diameter manhole that is concrete lined with a carbon steel lid. A fifteen centimeter (6 inch) diameter horizontal orientated below grade pipe exited the west side of the manhole. The manhole was located near Washington and Second Avenue, southwest of an unknown facility. It is suspected to be a sanitary sewer cleanout.

The third related feature consisted of a 1 by 1 meter (3 by 3 feet) concrete foundation and potential below grade structure at coordinates E577540.06/N147742.44.

The fourth related feature was a concrete manhole. It was 1.5 meter (61 inches) in diameter, 14 centimeter (5 inch) wall thickness, 23 centimeter (9 inches) deep, and partially filled with dirt. It is at coordinates E577894.91/N147786.64.

Location: The sewer system was located throughout the White Bluffs area.

Related Sites/ Structures: Eleven facilities are shown on H-11-3709, that connect to the sanitary sewer system from the south side of town. See Sitecode 600-176.

Process Description: The sanitary sewer system is a network of pipelines connect to multiple facilities all discharging to a Imhoff Tank prior to being released to the filter and leaching bed, as shown in White Bluffs drawing plot plan H-11-3709. Septic system transfer piping connecting to the septic tank. Little is known about the sanitary sewer service piping. The pipeline size, depth and construction material are all unknown.

Closure Info: Interim (1/16/2014): (Interim Closed Out) Confirmatory samples were collected from four test pits, placed at the locations of the four features related to the 600-301 waste site. Elevated levels of arsenic and nitrate at test pits 1 and 2, as well as elevated concentrations of cadmium and TPH at test pit 7 (main site excavation) were identified in the confirmatory data. Between April 22 and June 20, 2013, approximately 963 bank cubic meters (1,260 bank cubic yards) of rock, gravel, and pipe were removed from the areas associated with test pits 1, 2, and a segment of pipeline associated with test pit 7. These materials were disposed at the Environmental Restoration Disposal Facility (ERDF). The maximum depth of the excavation is approximately 2.1 meters (7.0 ft) below ground surface. All material removed from the waste site was direct loaded for disposal at ERDF, and no soil staging pile areas or overburden areas were utilized.

Final (10/28/2015): (Final Closed Out) Based upon evaluation of the previous reclassification data against the 100-F/IU Area ROD cleanup levels, no further RTD is required for any of the 26 waste sites (Listed below).

600-279, Vegetation-Free Area Between White Bluffs and 100-F
 600-293, White Bluffs Service Station #1
 600-294, White Bluffs Service Station #2
 600-298, Stained Soil and Surface Debris
 600-299, Surface Debris/Batteries
 600-300, Miscellaneous Surface Debris
 600-301, White Bluffs Sanitary Sewer Pipelines
 600-303, Vertical Pipes
 600-316, Dry Cell Batteries
 600-318, Wet Cell Batteries
 600-320, Oil Stains
 600-321, Suspect ACM Sites
 600-328, Lead Slag
 600-356, Tar Deposit West of Susie Junction
 600-368, Segment 4 Stained Soil #1
 600-369, Segment 4 Bare Ground and Crusted Soil Areas
 600-370, Segment 4 Debris Area #1
 600-371, Segment 4 Chalky Material Area
 600-372, Segment 4 Oil Stain and Filter Area #1
 600-373, Segment 4 Bare Ground and White Stain Area
 600-374, Segment 4 Drum Remnant Area
 600-375, Segment 4 Dry Cell Battery Debris Area #1
 600-376, Segment 4 Stained Soil Area #2
 600-377, Segment 4 Oil Stain and Filter Area #2
 600-378, 506 Telephone Exchange Emergency Generator Building Underground Fuel Storage tank
 600-379, Segment 4 Burn Area #1.

The Reclassification to Final Closed Out applies to all subsites associated with the waste sites listed above.

Code: 600-302	Classification: Accepted
Names: 600-302; French Drain with Vent Pipe	Reclassification: Interim No Action (2/9/2011)
Type: French Drain	Start Date:
Status: Inactive	End Date:
Description: This wastes site was evaluated and determined to require No Action site. Letter: MSA-1400080	

(1/27/2014) Contract Deliverable CD1033 Annual Class V Underground Injection Control (UIC) Wells Update for calendar year 2013 states the estimated backfill date of this drain is 10/1/2010. The site consisted of a french drain, and underlying soil, with a vent pipe located approximately 2 meters (6 feet) northeast. The drain is about 1 meter (3 feet) in diameter, both have covers.

Location: The site is located approximately 361 meters NNE of the intersection of Route 2 North and Sand Bar Road.

Closure Info: Interim: Results of confirmatory sampling performed in October 2010 concluded that remediation was not necessary.

During confirmatory sampling, it was observed that the french drain extended to approximately 1 meter (3 ft) below ground surface. The vent pipe was a 1 inch (3 ft) diameter section of pipe that was attached to nothing. The linear features identified on the geophysical survey were determined to be 1 in. diameter, 0.5 in. diameter, and 6 in. diameter stainless steel sewer and vent lines leading directly to the french drain. Material for sampling was not present in these pipelines.

No radiological activity or volatile organic compounds (VOCs) were detected during confirmatory sampling. Additionally, no anomalous or stained soil was observed. Confirmatory sampling indicated that environmental contamination was not present at this waste site. Based on confirmatory sampling, remedial action was determined to be unnecessary.

Code: 600-303	Classification: Accepted
Names: 600-303; Vertical Pipes	Reclassification: Final Closed Out (10/28/2015)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The waste site has been remediated, Interim Closed Out and later Final Closed Out. It consisted of a 3 by 3 meter (9.8 by 9.8 foot) area with 4 vertical pipes, 2.5 to 3.8 centimeter (1 to 1 1/2 inch) in diameter, extending up from the ground.

Location: The site was approximately 361 meters (1185 feet) north/northeast of the intersection of Route 2 North and Sand Bar Road. The feature was located approximately 4 meters from the SE corner of the footprint of the former office building at E577419.03, N148906.44.

Process Description: The purpose of these pipes is unknown.

Closure Info: Interim (8/15/2013): (Interim Closed Out) In October 2010, confirmatory samples were taken at the 600-303 waste site. The project team conducted site visits at various times from June 2011 to January 2013. The objective of the visits was to perform geophysical surveys and determine the extent (if any) of buried debris associated with the waste sites.

Remediation of the 600-303 waste site occurred on February 11, 2012, and February 12, 2012. The soil within this waste site was excavated to a depth of approximately 1.8 meters (6 ft) below ground surface (bgs) and resulted in the removal of 35 bank cubic meters (BCM) (46 bank cubic yards [BCY]) of soil and debris, which were disposed at the Environmental Restoration Disposal Facility (ERDF). The remediation of the 600-321 waste site subsites occurred between June 28, 2011, and March 19, 2013. The soil within the subsites was excavated to a depth of approximately 1.2 meters (4 ft) bgs and resulted in the removal of 235 BCM (307 BCY) of soil and debris, which were disposed at ERDF.

The waste site dimensions were revised during the remedial investigation. The final extent of the excavations at these waste sites removed all subsurface staining and debris present.

Final (10/28/2015): (Final Closed Out) Based upon evaluation of the previous reclassification data against the 100-F/IU Area ROD cleanup levels, no further RTD is required for any of the 26 waste sites (Listed below).

- 600-279, Vegetation-Free Area Between White Bluffs and 100-F
- 600-293, White Bluffs Service Station #1
- 600-294, White Bluffs Service Station #2
- 600-298, Stained Soil and Surface Debris
- 600-299, Surface Debris/Batteries
- 600-300, Miscellaneous Surface Debris
- 600-301, White Bluffs Sanitary Sewer Pipelines
- 600-303, Vertical Pipes
- 600-316, Dry Cell Batteries
- 600-318, Wet Cell Batteries
- 600-320, Oil Stains
- 600-321, Suspect ACM Sites
- 600-328, Lead Slag
- 600-356, Tar Deposit West of Susie Junction
- 600-368, Segment 4 Stained Soil #1
- 600-369, Segment 4 Bare Ground and Crusted Soil Areas
- 600-370, Segment 4 Debris Area #1
- 600-371, Segment 4 Chalky Material Area
- 600-372, Segment 4 Oil Stain and Filter Area #1
- 600-373, Segment 4 Bare Ground and White Stain Area
- 600-374, Segment 4 Drum Remnant Area
- 600-375, Segment 4 Dry Cell Battery Debris Area #1
- 600-376, Segment 4 Stained Soil Area #2
- 600-377, Segment 4 Oil Stain and Filter Area #2
- 600-378, 506 Telephone Exchange Emergency Generator Building Underground Fuel Storage tank
- 600-379, Segment 4 Burn Area #1.

The Reclassification to Final Closed Out applies to all subsites associated with the waste sites listed above.

Code: 600-305	Classification: Accepted
Names: 600-305; Suspect Asbestos Containing Material Sites	Reclassification: Interim Closed Out (10/17/2012)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:
Description: The waste site has been remediated and Interim Closed Out. The waste site consisted of several areas of scattered suspect asbestos debris. It was divided into five subsites. Each subsite area contained surface debris that was potentially asbestos containing material (ACM). The sites are vegetated with native grasses and rabbit brush.	
Location: The coordinates for the five areas are E577632.80, N147948.61; E577696.82, N147936.53; E578195.65, N147168.34; E578293.84, N147397.84; E578926.03, N147948.43.	

Process Description: The debris appeared to have been excess construction materials that was randomly disposed.

Waste Type: Asbestos (friable)

Waste Description: These sites contain suspect asbestos containing materials (ACM).

Closure Info: Interim (10/17/2012): Remediation of the combined 100-IU-2/6 debris and burn area waste sites occurred between August 10, 2011 and May 29, 2012. The activity resulted in a total of approximately 523 bank cubic meters (BCM) (682 bank cubic yards [BCY]) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility (ERDF).

Based on observations during the field walkdowns to support remedial action, it was determined that the 600-305, 600-308, 600-309, 600-310, 600-311, 600-312, 600-313, 600-314, 600-317, 600-319, and 600-324 waste sites required remediation. The 600-314 subsites required removal of only telecommunication equipment on the ground surface with no excavation.

Remediation of the 600-305:1 and 600-305:2 subsites occurred on April 4, 2012. The soil within these subsites was excavated to a depth of approximately 0.3 meters (1 ft) below ground surface (bgs). No excavation occurred at the 600-305:3 waste site since surface removal of a pipe was the only scope. The remediation of the 600-305:4 subsite occurred on May 14, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs. The remediation of the 600-305:5 subsite occurred on May 15, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs.

The remediation of the 600-308 waste site occurred on May 29, 2012. The soil within this waste site was excavated to a depth of approximately 0.6 meters (2 ft) bgs.

The remediation of the 600-309 waste site occurred on May 23 and 24, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-310 waste site occurred on May 22 and 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-311 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-312 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-313 waste site occurred on May 16, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

For the five 600-314 subsites, only component item removal was required, since only telecommunications components were lying on the surface with no stained or additional anomalous material. Component removal at the 600-314 subsites occurred on May 1, 4, and 14, 2012. All the components were disposed of at ERDF.

The remediation of the 600-317 waste site occurred on May 21 and 22, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-319:1 subsite occurred on May 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:2 subsite occurred on May 4, 2012. The soil within this waste site was excavated to a depth

of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:3 subsite occurred on August 10, 2011. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-324 waste site occurred between April 26 and 30, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

A post-excavation global positioning survey (GPS) walk-around for the excavated waste sites was performed following excavation. Excavated material from all subsites and waste sites was direct loaded for disposal to ERDF, and no soil staging pile area or overburden areas were utilized.

This Site has the Following SubSites:

Code: 600-305:1

Names: 600-305:1; Suspect ACM Sites Area 1

Code: 600-305:2

Names: 600-305:2; Suspect ACM Sites Area 2

Code: 600-305:3

Names: 600-305:3; Suspect ACM Sites Area 3

Code: 600-305:4

Names: 600-305:4; Suspect ACM Sites Area 4

Code: 600-305:5

Names: 600-305:5; Suspect ACM Sites Area 5

Code: 600-305:1

Classification: Accepted

Names: 600-305:1; Suspect ACM Sites Area 1

Reclassification: Interim Closed Out (10/17/2012)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The waste site has been remediated and Interim Closed Out. The subsite consisted of a roll of roofing product that was considered potential asbestos containing material (ACM).

Location: The site was located approximately 365 meters (0.2 miles) west of Federal Avenue and 442 meters (0.3 miles) south of Route 2 North in the former White Bluffs Community area.

Closure Info: Interim (10/17/2012): Remediation of the combined 100-IU-2/6 debris and burn area waste sites occurred between August 10, 2011 and May 29, 2012. The activity resulted in a total of approximately 523 bank cubic meters (BCM) (682 bank cubic yards [BCY]) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility (ERDF).

Based on observations during the field walkdowns to support remedial action, it was determined that the 600-305, 600-308, 600-309, 600-310, 600-311, 600-312, 600-313, 600-314, 600-317, 600-319, and 600-324 waste sites required remediation. The 600-314 subsites required removal of only telecommunication equipment on the ground surface with no excavation.

Remediation of the 600-305:1 and 600-305:2 subsites occurred on April 4, 2012. The soil within these subsites was excavated to a depth of approximately 0.3 meters (1 ft) below ground surface (bgs). No excavation occurred at the 600-305:3 waste site since surface removal of a pipe was the only scope. The remediation of the 600-305:4 subsite occurred on May 14, 2012.

The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs. The remediation of the 600-305:5 subsite occurred on May 15, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs.

The remediation of the 600-308 waste site occurred on May 29, 2012. The soil within this waste site was excavated to a depth of approximately 0.6 meters (2 ft) bgs.

The remediation of the 600-309 waste site occurred on May 23 and 24, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-310 waste site occurred on May 22 and 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-311 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-312 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-313 waste site occurred on May 16, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

For the five 600-314 subsites, only component item removal was required, since only telecommunications components were lying on the surface with no stained or additional anomalous material. Component removal at the 600-314 subsites occurred on May 1, 4, and 14, 2012. All the components were disposed of at ERDF.

The remediation of the 600-317 waste site occurred on May 21 and 22, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-319:1 subsite occurred on May 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:2 subsite occurred on May 4, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:3 subsite occurred on August 10, 2011. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-324 waste site occurred between April 26 and 30, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

A post-excavation global positioning survey (GPS) walk-around for the excavated waste sites was performed following excavation. Excavated material from all subsites and waste sites was direct loaded for disposal to ERDF, and no soil staging pile area or overburden areas were utilized.

The SubSite is Part Of:

Code: 600-305

Names: 600-305; Suspect Asbestos Containing Material Sites

Code: 600-305:2

Classification: Accepted

Names: 600-305:2; Suspect ACM Sites Area 2

Reclassification Interim Closed Out (10/17/2012)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The waste site has been remediated and Interim Closed Out. The subsite consisted of a 3 by 3 m (10 by 10 ft) area of insulating material that is potential asbestos containing material (ACM).

Location: The site was located approximately 290 meters (0.2 miles) west of Federal Avenue and 399 meters (0.25 miles) south of Route 2 North in the former White Bluffs Community area.

Closure Info: Interim (10/17/2012): Remediation of the combined 100-IU-2/6 debris and burn area waste sites occurred between August 10, 2011 and May 29, 2012. The activity resulted in a total of approximately 523 bank cubic meters (BCM) (682 bank cubic yards [BCY]) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility (ERDF).

Based on observations during the field walkdowns to support remedial action, it was determined that the 600-305, 600-308, 600-309, 600-310, 600-311, 600-312, 600-313, 600-314, 600-317, 600-319, and 600-324 waste sites required remediation. The 600-314 subsites required removal of only telecommunication equipment on the ground surface with no excavation.

Remediation of the 600-305:1 and 600-305:2 subsites occurred on April 4, 2012. The soil within these subsites was excavated to a depth of approximately 0.3 meters (1 ft) below ground surface (bgs). No excavation occurred at the 600-305:3 waste site since surface removal of a pipe was the only scope. The remediation of the 600-305:4 subsite occurred on May 14, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs. The remediation of the 600-305:5 subsite occurred on May 15, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs.

The remediation of the 600-308 waste site occurred on May 29, 2012. The soil within this waste site was excavated to a depth of approximately 0.6 meters (2 ft) bgs.

The remediation of the 600-309 waste site occurred on May 23 and 24, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-310 waste site occurred on May 22 and 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-311 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-312 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-313 waste site occurred on May 16, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

For the five 600-314 subsites, only component item removal was required, since only telecommunications components were lying on the surface with no stained or additional anomalous material. Component removal at the 600-314 subsites occurred on May 1, 4, and 14, 2012. All the components were disposed of at ERDF.

The remediation of the 600-317 waste site occurred on May 21 and 22, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-319:1 subsite occurred on May 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:2 subsite occurred on May 4, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:3 subsite occurred on

August 10, 2011. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-324 waste site occurred between April 26 and 30, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

A post-excavation global positioning survey (GPS) walk-around for the excavated waste sites was performed following excavation. Excavated material from all subsites and waste sites was direct loaded for disposal to ERDF, and no soil staging pile area or overburden areas were utilized.

The SubSite is Part Of:

Code: 600-305

Names: 600-305; Suspect Asbestos Containing Material Sites

Code: 600-305:3

Classification: Accepted

Names: 600-305:3; Suspect ACM Sites Area 3

Reclassification: Interim Closed Out (10/17/2012)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The waste site has been remediated and Interim Closed Out. The subsite consisted of fabric-like material that was potential asbestos containing material (ACM).

Location: The site was located approximately 1.2 km (0.75 miles) east of Federal Avenue and 759 meters (0.5 miles) south of Route 2 North in the former White Bluffs Community area.

Closure Info: Interim (10/17/2012): Remediation of the combined 100-IU-2/6 debris and burn area waste sites occurred between August 10, 2011 and May 29, 2012. The activity resulted in a total of approximately 523 bank cubic meters (BCM) (682 bank cubic yards [BCY]) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility (ERDF).

Based on observations during the field walkdowns to support remedial action, it was determined that the 600-305, 600-308, 600-309, 600-310, 600-311, 600-312, 600-313, 600-314, 600-317, 600-319, and 600-324 waste sites required remediation. The 600-314 subsites required removal of only telecommunication equipment on the ground surface with no excavation.

Remediation of the 600-305:1 and 600-305:2 subsites occurred on April 4, 2012. The soil within these subsites was excavated to a depth of approximately 0.3 meters (1 ft) below ground surface (bgs). No excavation occurred at the 600-305:3 waste site since surface removal of a pipe was the only scope. The remediation of the 600-305:4 subsite occurred on May 14, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs. The remediation of the 600-305:5 subsite occurred on May 15, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs.

The remediation of the 600-308 waste site occurred on May 29, 2012. The soil within this waste site was excavated to a depth of approximately 0.6 meters (2 ft) bgs.

The remediation of the 600-309 waste site occurred on May 23 and 24, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-310 waste site occurred on May 22 and 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-311 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-312 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-313 waste site occurred on May 16, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

For the five 600-314 subsites, only component item removal was required, since only telecommunications components were lying on the surface with no stained or additional anomalous material. Component removal at the 600-314 subsites occurred on May 1, 4, and 14, 2012. All the components were disposed of at ERDF.

The remediation of the 600-317 waste site occurred on May 21 and 22, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-319:1 subsite occurred on May 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:2 subsite occurred on May 4, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:3 subsite occurred on August 10, 2011. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-324 waste site occurred between April 26 and 30, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

A post-excitation global positioning survey (GPS) walk-around for the excavated waste sites was performed following excavation. Excavated material from all subsites and waste sites was direct loaded for disposal to ERDF, and no soil staging pile area or overburden areas were utilized.

The SubSite is Part Of:

Code: 600-305

Names: 600-305; Suspect Asbestos Containing Material Sites

Code: 600-305:4

Classification: Accepted

Names: 600-305:4; Suspect ACM Sites Area 4

Reclassification Interim Closed Out (10/17/2012)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The waste site has been remediated and Interim Closed Out. The subsite consisted of a 2 by 2 meter (6 by 6 ft) area with potential asbestos containing material (ACM) insulation that might also have been fiberglass.

Location: The site was located approximately 944 m (0.6 miles) east of Federal Avenue and 395 meters (0.25 miles) south of Route 2 North in the former White Bluffs Community area.

Closure Info: Interim (10/17/2012): Remediation of the combined 100-IU-2/6 debris and burn area waste sites occurred between August 10, 2011 and May 29, 2012. The activity resulted in a total of approximately 523 bank cubic meters (BCM) (682 bank cubic yards [BCY]) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility (ERDF).

Based on observations during the field walkdowns to support remedial action, it was determined that the 600-305, 600-308, 600-309, 600-310, 600-311, 600-312, 600-313, 600-314, 600-317, 600-319, and 600-324 waste sites required remediation. The 600-314 subsites required removal of only telecommunication equipment on the ground surface with no excavation.

Remediation of the 600-305:1 and 600-305:2 subsites occurred on April 4, 2012. The soil within these subsites was excavated to a depth of approximately 0.3 meters (1 ft) below ground surface (bgs). No excavation occurred at the 600-305:3 waste site since surface removal of a pipe was the only scope. The remediation of the 600-305:4 subsite occurred on May 14, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs. The remediation of the 600-305:5 subsite occurred on May 15, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs.

The remediation of the 600-308 waste site occurred on May 29, 2012. The soil within this waste site was excavated to a depth of approximately 0.6 meters (2 ft) bgs.

The remediation of the 600-309 waste site occurred on May 23 and 24, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-310 waste site occurred on May 22 and 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-311 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-312 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-313 waste site occurred on May 16, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

For the five 600-314 subsites, only component item removal was required, since only telecommunications components were lying on the surface with no stained or additional anomalous material. Component removal at the 600-314 subsites occurred on May 1, 4, and 14, 2012. All the components were disposed of at ERDF.

The remediation of the 600-317 waste site occurred on May 21 and 22, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-319:1 subsite occurred on May 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:2 subsite occurred on May 4, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:3 subsite occurred on August 10, 2011. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-324 waste site occurred between April 26 and 30, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

A post-excavation global positioning survey (GPS) walk-around for the excavated waste sites was performed following excavation. Excavated material from all subsites and waste sites was direct loaded for disposal to ERDF, and no soil staging pile area or overburden areas were utilized.

The SubSite is Part Of:**Code:** 600-305**Names:** 600-305; Suspect Asbestos Containing Material Sites**Code:** 600-305:5**Classification:** Accepted**Names:** 600-305:5; Suspect ACM Sites Area 5**Reclassification:** Interim Closed Out (10/17/2012)**Type:** Unplanned Release**Start Date:****Status:** Inactive**End Date:****Description:** The waste site has been remediated and Interim Closed Out. The subsite consisted of two sheets of insulation that are potential asbestos containing material (ACM). The sheets were roughly 8 meters (26 ft) apart.**Location:** The site was located approximately 925 m (0.6 miles) east of Federal Avenue and 754 m (0.5 miles) north of Route 2 North in the former White Bluffs Community area.**Closure Info:** Interim (10/17/2012): Remediation of the combined 100-IU-2/6 debris and burn area waste sites occurred between August 10, 2011 and May 29, 2012. The activity resulted in a total of approximately 523 bank cubic meters (BCM) (682 bank cubic yards [BCY]) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility (ERDF).

Based on observations during the field walkdowns to support remedial action, it was determined that the 600-305, 600-308, 600-309, 600-310, 600-311, 600-312, 600-313, 600-314, 600-317, 600-319, and 600-324 waste sites required remediation. The 600-314 subsites required removal of only telecommunication equipment on the ground surface with no excavation.

Remediation of the 600-305:1 and 600-305:2 subsites occurred on April 4, 2012. The soil within these subsites was excavated to a depth of approximately 0.3 meters (1 ft) below ground surface (bgs). No excavation occurred at the 600-305:3 waste site since surface removal of a pipe was the only scope. The remediation of the 600-305:4 subsite occurred on May 14, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs. The remediation of the 600-305:5 subsite occurred on May 15, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs.

The remediation of the 600-308 waste site occurred on May 29, 2012. The soil within this waste site was excavated to a depth of approximately 0.6 meters (2 ft) bgs.

The remediation of the 600-309 waste site occurred on May 23 and 24, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-310 waste site occurred on May 22 and 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-311 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-312 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-313 waste site occurred on May 16, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

For the five 600-314 subsites, only component item removal was required, since only telecommunications components were lying on the surface with no stained or additional anomalous material. Component removal at the 600-314 subsites occurred on May 1, 4, and 14, 2012. All the components were disposed of at ERDF.

The remediation of the 600-317 waste site occurred on May 21 and 22, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-319:1 subsite occurred on May 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:2 subsite occurred on May 4, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:3 subsite occurred on August 10, 2011. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-324 waste site occurred between April 26 and 30, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

A post-excavation global positioning survey (GPS) walk-around for the excavated waste sites was performed following excavation. Excavated material from all subsites and waste sites was direct loaded for disposal to ERDF, and no soil staging pile area or overburden areas were utilized.

The SubSite is Part Of:

Code: 600-305

Names: 600-305; Suspect Asbestos Containing Material Sites

Code: 600-306

Classification: Accepted

Names: 600-306; Burn Site #1

Reclassification: Interim Closed Out (8/2/2012)

Type: Burn Pit

Start Date:

Status: Inactive

End Date:

Description: The site has been remediated and Interim Closed Out. It consisted of a burned area with metal, wood, nails, iron plate, tar paper debris and the underlying soil.

Location: The site is located 21 meters (69 feet) southeast of the White Bluffs sheet metal shop at coordinates E577815.41, N147902.17.

Waste Type: Misc. Trash and Debris

Waste Description: Contaminants may include asbestos and petroleum products. No other waste information was available.

Closure Info: Interim (8/2/2012): Geophysical surveys were conducted to detect subsurface anomalies. Remediation of the 600-306 waste site occurred on April 3 and 4, 2012, and resulted in approximately 73.5 bank cubic meters (96.1 bank cubic yards) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility (ERDF). Remediation of the 600-307 waste site occurred on April 3, 2012, and resulted in approximately 87.6 bank cubic meters (114.6 bank cubic yards) of soil and debris being removed and disposed at the ERDF. The 600-325:1 and 600-325:2 waste subsites were remediated between July 5 and 13, 2011, and resulted in approximately 176.0 bank cubic meters (230.2 bank cubic yards) of soil and debris being removed and disposed at the ERDF. No overburden soil was stockpiled to be used as backfill.

Code: 600-307 **Classification:** Accepted
Names: 600-307; Burn Site #2 **Reclassification** Interim Closed Out (8/2/2012)
Type: Burn Pit **Start Date:**
Status: Inactive **End Date:**

Description: The site has been remediated and Interim Closed Out. It consisted of a burned area with metal, wood, tar paper debris and the underlying soil.

Location: The site is located 38 meters (125 feet) southwest of the Hanford Receiving Warehouse at White Bluffs. The center point coordinates for the site are E577937.09, N147962.07.

Waste Type: Construction Debris

Waste Description: Contaminants may include asbestos and petroleum products.

Closure Info: Interim (8/2/2012): Geophysical surveys were conducted to detect subsurface anomalies. Remediation of the 600-306 waste site occurred on April 3 and 4, 2012, and resulted in approximately 73.5 bank cubic meters (96.1 bank cubic yards) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility (ERDF). Remediation of the 600-307 waste site occurred on April 3, 2012, and resulted in approximately 87.6 bank cubic meters (114.6 bank cubic yards) of soil and debris being removed and disposed at the ERDF. The 600-325:1 and 600-325:2 waste subsites were remediated between July 5 and 13, 2011, and resulted in approximately 176.0 bank cubic meters (230.2 bank cubic yards) of soil and debris being removed and disposed at the ERDF. No overburden soil was stockpiled to be used as backfill.

Code: 600-308 **Classification:** Accepted
Names: 600-308; Garnet Sand **Reclassification** Interim Closed Out (10/17/2012)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The waste site has been remediated and Interim Closed Out. This site consisted of a 6 by 6 meter area with scattered garnet sand and the underlying soil.

Location: The site was located between two rail spurs and approximately 112 meters (367 feet) east of the 105 Warehouse. Center point coordinates for this site are E577594.68, N148649.90.

Waste Type: Soil

Waste Description: The contaminant of potential concern is lead.

Closure Info: Interim (10/17/2012): Remediation of the combined 100-IU-2/6 debris and burn area waste sites occurred between August 10, 2011 and May 29, 2012. The activity resulted in a total of approximately 523 bank cubic meters (BCM) (682 bank cubic yards [BCY]) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility (ERDF).

Based on observations during the field walkdowns to support remedial action, it was determined that the 600-305, 600-308, 600-309, 600-310, 600-311, 600-312, 600-313, 600-314, 600-317, 600-319, and 600-324 waste sites required remediation. The 600-314 subsites required removal of only telecommunication equipment on the ground surface with no excavation.

Remediation of the 600-305:1 and 600-305:2 subsites occurred on April 4, 2012. The soil within these subsites was excavated to a depth of approximately 0.3 meters (1 ft) below ground surface (bgs). No excavation occurred at the 600-305:3 waste site since surface removal of a pipe was the only scope. The remediation of the 600-305:4 subsite occurred on May 14, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs. The remediation of the 600-305:5 subsite occurred on May 15, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs.

The remediation of the 600-308 waste site occurred on May 29, 2012. The soil within this waste site was excavated to a depth of approximately 0.6 meters (2 ft) bgs.

The remediation of the 600-309 waste site occurred on May 23 and 24, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-310 waste site occurred on May 22 and 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-311 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-312 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-313 waste site occurred on May 16, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

For the five 600-314 subsites, only component item removal was required, since only telecommunications components were lying on the surface with no stained or additional anomalous material. Component removal at the 600-314 subsites occurred on May 1, 4, and 14, 2012. All the components were disposed of at ERDF.

The remediation of the 600-317 waste site occurred on May 21 and 22, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-319:1 subsite occurred on May 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:2 subsite occurred on May 4, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:3 subsite occurred on August 10, 2011. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-324 waste site occurred between April 26 and 30, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

A post-excavation global positioning survey (GPS) walk-around for the excavated waste sites was performed following excavation. Excavated material from all subsites and waste sites was direct loaded for disposal to ERDF, and no soil staging pile area or overburden areas were utilized.

Code: 600-309

Classification: Accepted

Names: 600-309; Burn Site #3

Reclassification Interim Closed Out (10/17/2012)

Type: Unplanned Release

Start Date:

Status: Inactive**End Date:****Description:** The waste site has been remediated and Interim Closed Out. The site consisted of a burned area with wood, clay pipe, fabric (suspect asbestos containing material - ACM), rubber hoses and the underlying soil. Soil and cobbles were also dumped here.**Location:** The site was located 254 meters (833 feet) west of sitecode 600-158 - White Bluffs Ground Storage Tank and Booster Pump Station.**Waste Type:** Misc. Trash and Debris**Waste Description:** Contaminants may include asbestos.**Closure Info:** Interim (10/17/2012): Remediation of the combined 100-IU-2/6 debris and burn area waste sites occurred between August 10, 2011 and May 29, 2012. The activity resulted in a total of approximately 523 bank cubic meters (BCM) (682 bank cubic yards [BCY]) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility (ERDF).

Based on observations during the field walkdowns to support remedial action, it was determined that the 600-305, 600-308, 600-309, 600-310, 600-311, 600-312, 600-313, 600-314, 600-317, 600-319, and 600-324 waste sites required remediation. The 600-314 subsites required removal of only telecommunication equipment on the ground surface with no excavation.

Remediation of the 600-305:1 and 600-305:2 subsites occurred on April 4, 2012. The soil within these subsites was excavated to a depth of approximately 0.3 meters (1 ft) below ground surface (bgs). No excavation occurred at the 600-305:3 waste site since surface removal of a pipe was the only scope. The remediation of the 600-305:4 subsite occurred on May 14, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs. The remediation of the 600-305:5 subsite occurred on May 15, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs.

The remediation of the 600-308 waste site occurred on May 29, 2012. The soil within this waste site was excavated to a depth of approximately 0.6 meters (2 ft) bgs.

The remediation of the 600-309 waste site occurred on May 23 and 24, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-310 waste site occurred on May 22 and 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-311 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-312 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-313 waste site occurred on May 16, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

For the five 600-314 subsites, only component item removal was required, since only telecommunications components were lying on the surface with no stained or additional anomalous material. Component removal at the 600-314 subsites occurred on May 1, 4, and 14, 2012. All the components were disposed of at ERDF.

The remediation of the 600-317 waste site occurred on May 21 and 22, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-319:1 subsite occurred on May 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:2 subsite occurred on May 4, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:3 subsite occurred on August 10, 2011. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-324 waste site occurred between April 26 and 30, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

A post-excavation global positioning survey (GPS) walk-around for the excavated waste sites was performed following excavation. Excavated material from all subsites and waste sites was direct loaded for disposal to ERDF, and no soil staging pile area or overburden areas were utilized.

Code: 600-310	Classification: Accepted
Names: 600-310; Burn Site #4	Reclassification: Interim Closed Out (10/17/2012)
Type: Burn Pit	Start Date:
Status: Inactive	End Date:

Description: The waste site has been remediated and Interim Closed Out. The site consisted of a burned area with glass, cinders, slag, metal and the underlying soil.

Location: The site was located 12 meters (39 feet) north east of sitecode 600-171 - White Bluffs Office. The center point coordinates for the site are E578208.20, N148209.90.

Closure Info: Interim (10/17/2012): Remediation of the combined 100-IU-2/6 debris and burn area waste sites occurred between August 10, 2011 and May 29, 2012. The activity resulted in a total of approximately 523 bank cubic meters (BCM) (682 bank cubic yards [BCY]) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility (ERDF).

Based on observations during the field walkdowns to support remedial action, it was determined that the 600-305, 600-308, 600-309, 600-310, 600-311, 600-312, 600-313, 600-314, 600-317, 600-319, and 600-324 waste sites required remediation. The 600-314 subsites required removal of only telecommunication equipment on the ground surface with no excavation.

Remediation of the 600-305:1 and 600-305:2 subsites occurred on April 4, 2012. The soil within these subsites was excavated to a depth of approximately 0.3 meters (1 ft) below ground surface (bgs). No excavation occurred at the 600-305:3 waste site since surface removal of a pipe was the only scope. The remediation of the 600-305:4 subsite occurred on May 14, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs. The remediation of the 600-305:5 subsite occurred on May 15, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs.

The remediation of the 600-308 waste site occurred on May 29, 2012. The soil within this waste site was excavated to a depth of approximately 0.6 meters (2 ft) bgs.

The remediation of the 600-309 waste site occurred on May 23 and 24, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-310 waste site occurred on May 22 and 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-311 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-312 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-313 waste site occurred on May 16, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

For the five 600-314 subsites, only component item removal was required, since only telecommunications components were lying on the surface with no stained or additional anomalous material. Component removal at the 600-314 subsites occurred on May 1, 4, and 14, 2012. All the components were disposed of at ERDF.

The remediation of the 600-317 waste site occurred on May 21 and 22, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-319:1 subsite occurred on May 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:2 subsite occurred on May 4, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:3 subsite occurred on August 10, 2011. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-324 waste site occurred between April 26 and 30, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

A post-excavation global positioning survey (GPS) walk-around for the excavated waste sites was performed following excavation. Excavated material from all subsites and waste sites was direct loaded for disposal to ERDF, and no soil staging pile area or overburden areas were utilized.

Code: 600-311	Classification: Accepted
Names: 600-311; Burn Site #5	Reclassification Interim Closed Out (10/17/2012)
Type: Burn Pit	Start Date:
Status: Inactive	End Date:
Description:	The waste site has been remediated and Interim Closed Out. The site consisted of an area of concentrated burned debris and the underlying soil. Remnants of the burned debris included nails and tar like roofing material. It appeared to be next to an area where a building had once been located.
Location:	The site was located 126 meters (413 feet) southeast of WIDS sitecode 600-200, on the south side of a White Bluffs Office.
Closure Info:	Interim (10/17/2012): Remediation of the combined 100-IU-2/6 debris and burn area waste sites occurred between August 10, 2011 and May 29, 2012. The activity resulted in a total of approximately 523 bank cubic meters (BCM) (682 bank cubic yards [BCY]) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility (ERDF).

Based on observations during the field walkdowns to support remedial action, it was determined that the 600-305, 600-308, 600-309, 600-310, 600-311, 600-312, 600-313, 600-314, 600-317, 600-319, and 600-324 waste sites required remediation. The 600-314 subsites required removal of only telecommunication equipment on the ground surface with no excavation.

Remediation of the 600-305:1 and 600-305:2 subsites occurred on April 4, 2012. The soil within these subsites was excavated to a depth of approximately 0.3 meters (1 ft) below ground surface (bgs). No excavation occurred at the 600-305:3 waste site since surface removal of a pipe was the only scope. The remediation of the 600-305:4 subsite occurred on May 14, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs. The remediation of the 600-305:5 subsite occurred on May 15, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs.

The remediation of the 600-308 waste site occurred on May 29, 2012. The soil within this waste site was excavated to a depth of approximately 0.6 meters (2 ft) bgs.

The remediation of the 600-309 waste site occurred on May 23 and 24, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-310 waste site occurred on May 22 and 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-311 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-312 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-313 waste site occurred on May 16, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

For the five 600-314 subsites, only component item removal was required, since only telecommunications components were lying on the surface with no stained or additional anomalous material. Component removal at the 600-314 subsites occurred on May 1, 4, and 14, 2012. All the components were disposed of at ERDF.

The remediation of the 600-317 waste site occurred on May 21 and 22, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-319:1 subsite occurred on May 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:2 subsite occurred on May 4, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:3 subsite occurred on August 10, 2011. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-324 waste site occurred between April 26 and 30, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

A post-excavation global positioning survey (GPS) walk-around for the excavated waste sites was performed following excavation. Excavated material from all subsites and waste sites was direct loaded for disposal to ERDF, and no soil staging pile area or overburden areas were utilized.

Code: 600-312	Classification: Accepted
Names: 600-312; Burn Site #6	Reclassification: Interim Closed Out (10/17/2012)
Type: Burn Pit	Start Date:
Status: Inactive	End Date:

Description: The waste site has been remediated and Interim Closed Out. The site consisted of an area of concentrated burned debris and the underlying soil. Remnants of the burned debris included nails and tar like roofing material. The site appeared to be next to an area where a building had once been located.

Location: The site was located 138 meters (452 feet) southeast of WIDS sitecode 600-200, on the north side of a White Bluffs Office. Center point coordinates for the site are E578238.91, N147691.25.

Closure Info: Interim (10/17/2012): Remediation of the combined 100-IU-2/6 debris and burn area waste sites occurred between August 10, 2011 and May 29, 2012. The activity resulted in a total of approximately 523 bank cubic meters (BCM) (682 bank cubic yards [BCY]) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility (ERDF).

Based on observations during the field walkdowns to support remedial action, it was determined that the 600-305, 600-308, 600-309, 600-310, 600-311, 600-312, 600-313, 600-314, 600-317, 600-319, and 600-324 waste sites required remediation. The 600-314 subsites required removal of only telecommunication equipment on the ground surface with no excavation.

Remediation of the 600-305:1 and 600-305:2 subsites occurred on April 4, 2012. The soil within these subsites was excavated to a depth of approximately 0.3 meters (1 ft) below ground surface (bgs). No excavation occurred at the 600-305:3 waste site since surface removal of a pipe was the only scope. The remediation of the 600-305:4 subsite occurred on May 14, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs. The remediation of the 600-305:5 subsite occurred on May 15, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs.

The remediation of the 600-308 waste site occurred on May 29, 2012. The soil within this waste site was excavated to a depth of approximately 0.6 meters (2 ft) bgs.

The remediation of the 600-309 waste site occurred on May 23 and 24, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-310 waste site occurred on May 22 and 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-311 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-312 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-313 waste site occurred on May 16, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

For the five 600-314 subsites, only component item removal was required, since only telecommunications components were lying on the surface with no stained or additional

anomalous material. Component removal at the 600-314 subsites occurred on May 1, 4, and 14, 2012. All the components were disposed of at ERDF.

The remediation of the 600-317 waste site occurred on May 21 and 22, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-319:1 subsite occurred on May 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:2 subsite occurred on May 4, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:3 subsite occurred on August 10, 2011. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-324 waste site occurred between April 26 and 30, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

A post-excitation global positioning survey (GPS) walk-around for the excavated waste sites was performed following excavation. Excavated material from all subsites and waste sites was direct loaded for disposal to ERDF, and no soil staging pile area or overburden areas were utilized.

Code: 600-316	Classification: Accepted
Names: 600-316; Dry Cell Batteries	Reclassification: Final Closed Out (10/28/2015)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The parent site and the subsites have been remediated, Interim Closed Out and later Final Closed Out. It was described as six areas with dry cell battery debris lying on the ground surface near Route 2 North. The six areas (subsites) were evaluated in the same document and Interim Closed Out on a single Reclassification form.

Area 1 consisted of debris from a dry cell battery pack in an area less than 1 meter (3 ft) in diameter.

Area 2 consisted of farmstead debris including items such as cans and bottles and included four dry cell batteries in a 5 meters (16 ft) diameter area.

Area 3 consisted of debris from a dry cell battery pack. The affected area was less than 1 meters (3 ft) in diameter.

Area 4 consisted of debris from a dry cell carbon core battery pack in an area less than 1 meter (3 ft) in diameter.

Area 5 consisted of debris from dry cell carbon core batteries in an area less than 1 meter (3 ft) in diameter.

Area 6 consisted of debris from a single dry cell battery that was found during the site visit conducted on 02/20/2008.

Location: The six debris areas were located west of the Hanford Construction Camp and along three miles of Route 2 North.

Area 1 was located approximately 86 meters (282 ft) north of Route 2 North and 1.8 kilometers

(1.1 miles) southeast of the intersection of F Avenue and Route 2 North.

Area 2 was located approximately 848 meters (0.5 miles) west of Route 2 North and 3.2 kilometers (2 miles) north of Route 11A.

Area 3 was located approximately 725 meters (0.5 miles) west of Route 2 North and 1.2 kilometers (0.75 miles) north of Route 11A.

Area 4 was located approximately 235 meters (771 feet) west of Route 2 North and 1.6 kilometers (1.0 miles) north of Route 11A.

Area 5 was located approximately 58 meters (186 feet) west of Route 2 North and 941 meters (0.6 miles) north of Route 11A.

Area 6 was located approximately 61 meters (200 ft) north of Route 2 North and 688 meters (0.4 miles) southeast of the intersection of F Avenue and Route 2 North.

Closure Info: Interim (8/7/2013): (Interim Closed Out) Site visits and geophysical surveys were done in June and November 2011. The results determined that remediation was required. Remediation activities began in July 2011 and continued through February 2013.

The waste site boundaries were re-defined during the remediation process. The excavation extent removed all the debris associated with the battery waste sites.

No anomalous material or stained soil was discovered during remediation activities of either the 600-316 or 600-318 waste sites. All material was direct loaded for disposal to the Environmental Restoration and Disposal Facility (ERDF).

The areas (subsites) were evaluated in the same document and Interim Closed Out on a single Reclassification form.

Final (10/28/2015): (Final Closed Out) Based upon evaluation of the previous reclassification data against the 100-F/IU Area ROD cleanup levels, no further RTD is required for any of the 26 waste sites (Listed below).

600-279, Vegetation-Free Area Between White Bluffs and 100-F
600-293, White Bluffs Service Station #1
600-294, White Bluffs Service Station #2
600-298, Stained Soil and Surface Debris
600-299, Surface Debris/Batteries
600-300, Miscellaneous Surface Debris
600-301, White Bluffs Sanitary Sewer Pipelines
600-303, Vertical Pipes
600-316, Dry Cell Batteries
600-318, Wet Cell Batteries
600-320, Oil Stains
600-321, Suspect ACM Sites
600-328, Lead Slag
600-356, Tar Deposit West of Susie Junction
600-368, Segment 4 Stained Soil #1
600-369, Segment 4 Bare Ground and Crusted Soil Areas
600-370, Segment 4 Debris Area #1
600-371, Segment 4 Chalky Material Area
600-372, Segment 4 Oil Stain and Filter Area #1
600-373, Segment 4 Bare Ground and White Stain Area

600-374, Segment 4 Drum Remnant Area
 600-375, Segment 4 Dry Cell Battery Debris Area #1
 600-376, Segment 4 Stained Soil Area #2
 600-377, Segment 4 Oil Stain and Filter Area #2
 600-378, 506 Telephone Exchange Emergency Generator Building Underground Fuel Storage tank
 600-379, Segment 4 Burn Area #1.

The Reclassification to Final Closed Out applies to all subsites associated with the waste sites listed above.

This Site has the Following SubSites:

Code: 600-316:1
Names: 600-316:1; Dry Cell Batteries Area 1
Code: 600-316:2
Names: 600-316:2; Dry Cell Batteries Area 2
Code: 600-316:3
Names: 600-316:3; Dry Cell Batteries Area 3
Code: 600-316:4
Names: 600-316:4; Dry Cell Batteries Area 4
Code: 600-316:5
Names: 600-316:5; Dry Cell Batteries Area 5
Code: 600-316:6
Names: 600-316:6; Dry Cell Batteries Area 6

Code: 600-316:1	Classification: Accepted
Names: 600-316:1; Dry Cell Batteries Area 1	Reclassification: Final Closed Out (10/28/2015)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The subsite consisted of debris from a dry cell battery pack in an area less than 1 meters (3 ft) in diameter.

Location: Area 1 was located approximately 86 meters (282 ft) north of Route 2 North and 1.8 kilometers (1.1 miles) southeast of the intersection of F Avenue and Route 2 North.

Closure Info: Interim (8/7/2013): (Interim Closed Out) Site visits and geophysical surveys were done in June and November 2011. The results determined that remediation was required. Remediation activities began in July 2011 and continued through February 2013.

The waste site boundaries were re-defined during the remediation process. The excavation extent removed all the debris associated with the battery waste sites.

No anomalous material or stained soil was discovered during remediation activities of either the 600-316 or 600-318 waste sites. All material was direct loaded for disposal to the Environmental Restoration and Disposal Facility (ERDF).

The areas (subsites) were evaluated in the same document and Interim Closed Out on a single Reclassification form.

The SubSite is Part Of:**Code:** 600-316**Names:** 600-316; Dry Cell Batteries**Code:** 600-316:2**Classification:** Accepted**Names:** 600-316:2; Dry Cell Batteries Area 2**Reclassification** Final Closed Out (10/28/2015)**Type:** Unplanned Release**Start Date:****Status:** Inactive**End Date:**

Description: The six areas (subsites) were evaluated in the same document and Interim Closed Out on a single Reclassification form. Area 2 consisted of farmstead debris including items such as cans and bottles and included four dry cell batteries in a 5 meters (16 ft) diameter area.

Location: Area 2 was located approximately 848 meters (0.5 miles) west of Route 2 North and 3.2 km (2 miles) north of Route 11A.

Closure Info: Interim (8/7/2013): (Interim Closed Out) Site visits and geophysical surveys were done in June and November 2011. The results determined that remediation was required. Remediation activities began in July 2011 and continued through February 2013.

The waste site boundaries were re-defined during the remediation process. The excavation extent removed all the debris associated with the battery waste sites.

No anomalous material or stained soil was discovered during remediation activities of either the 600-316 or 600-318 waste sites. All material was direct loaded for disposal to the Environmental Restoration and Disposal Facility (ERDF).

The areas (subsites) were evaluated in the same document and Interim Closed Out on a single Reclassification form.

The SubSite is Part Of:**Code:** 600-316**Names:** 600-316; Dry Cell Batteries**Code:** 600-316:3**Classification:** Accepted**Names:** 600-316:3; Dry Cell Batteries Area 3**Reclassification** Final Closed Out (10/28/2015)**Type:** Unplanned Release**Start Date:****Status:** Inactive**End Date:**

Description: Area 3 consisted of debris from a dry cell battery pack. The affected area was less than 1 meters (3 ft) in diameter.

Location: Area 3 was located approximately 725 meters (0.5 miles) west of Route 2 North and 1.2 km (0.75 miles) north of Route 11A.

Closure Info: Interim (8/7/2013): (Interim Closed Out) Site visits and geophysical surveys were done in June and November 2011. The results determined that remediation was required. Remediation activities began in July 2011 and continued through February 2013.

The waste site boundaries were re-defined during the remediation process. The excavation extent removed all the debris associated with the battery waste sites.

No anomalous material or stained soil was discovered during remediation activities of either the 600-316 or 600-318 waste sites. All material was direct loaded for disposal to the Environmental Restoration and Disposal Facility (ERDF).

The areas (subsites) were evaluated in the same document and Interim Closed Out on a single Reclassification form.

The SubSite is Part Of:

Code: 600-316

Names: 600-316; Dry Cell Batteries

Code: 600-316:4

Classification: Accepted

Names: 600-316:4; Dry Cell Batteries Area 4

Reclassification: Final Closed Out (10/28/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: Area 4 consisted of debris from a dry cell carbon core battery pack in an area less than 1 meter (3 ft) in diameter.

Location: Area 4 was located approximately 235 meters (771 feet) west of Route 2 North and 1.6 kilometers (1.0 miles) north of Route 11A.

Closure Info: Interim (8/7/2013): (Interim Closed Out) Site visits and geophysical surveys were done in June and November 2011. The results determined that remediation was required. Remediation activities began in July 2011 and continued through February 2013.

The waste site boundaries were re-defined during the remediation process. The excavation extent removed all the debris associated with the battery waste sites.

No anomalous material or stained soil was discovered during remediation activities of either the 600-316 or 600-318 waste sites. All material was direct loaded for disposal to the Environmental Restoration and Disposal Facility (ERDF).

The areas (subsites) were evaluated in the same document and Interim Closed Out on a single Reclassification form.

The SubSite is Part Of:

Code: 600-316

Names: 600-316; Dry Cell Batteries

Code: 600-316:5

Classification: Accepted

Names: 600-316:5; Dry Cell Batteries Area 5

Reclassification: Final Closed Out (10/28/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The six areas (subsites) were evaluated in the same document and Interim Closed Out on a single Reclassification form. Area 5 consisted of debris from dry cell carbon core batteries in an area less than 1 meter (3 ft) in diameter.

Location: Area 5 was located approximately 58 meters (186 feet) west of Route 2 North and 941 meters (0.6 miles) north of Route 11A.

Closure Info: Interim (8/7/2013): (Interim Closed Out) Site visits and geophysical surveys were done in June and November 2011. The results determined that remediation was required. Remediation activities began in July 2011 and continued through February 2013.

The waste site boundaries were re-defined during the remediation process. The excavation extent removed all the debris associated with the battery waste sites.

No anomalous material or stained soil was discovered during remediation activities of either the 600-316 or 600-318 waste sites. All material was direct loaded for disposal to the Environmental Restoration and Disposal Facility (ERDF).

The areas (subsites) were evaluated in the same document and Interim Closed Out on a single Reclassification form.

The SubSite is Part Of:

Code: 600-316

Names: 600-316; Dry Cell Batteries

Code: 600-316:6

Classification: Accepted

Names: 600-316:6; Dry Cell Batteries Area 6

Reclassification Final Closed Out (10/28/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The six areas (subsites) were evaluated in the same document and Interim Closed Out on a single Reclassification form. Area 6 consisted of debris from a single dry cell battery that was found during the site visit conducted on 02/20/2008.

Location: Area 6 was located approximately 61 meters (200 ft) north of Route 2 North and 688 meters (0.4 miles) southeast of the intersection of F Avenue and Route 2 North.

Closure Info: Interim (8/7/2013): (Interim Closed Out) Site visits and geophysical surveys were done in June and November 2011. The results determined that remediation was required. Remediation activities began in July 2011 and continued through February 2013.

The waste site boundaries were re-defined during the remediation process. The excavation extent removed all the debris associated with the battery waste sites.

No anomalous material or stained soil was discovered during remediation activities of either the 600-316 or 600-318 waste sites. All material was direct loaded for disposal to the Environmental Restoration and Disposal Facility (ERDF).

The areas (subsites) were evaluated in the same document and Interim Closed Out on a single Reclassification form.

The SubSite is Part Of:

Code: 600-316

Names: 600-316; Dry Cell Batteries

Code: 600-341

Classification: Accepted

Names: 600-341; Inter Areas Battery Remnant Area #1

Reclassification Interim Closed Out (10/21/2010)

Type: Dumping Area**Start Date:****Status:** Inactive**End Date:****Description:** The waste site has been remediated and Interim Closed Out. It consisted of two subsites areas that contained dry cell battery remnants and battery debris. Both subsites, 600-341:1 Inter Areas Battery Remnant Areas 1 and 2 and 600-341:2 Inter Areas Battery Remnant Areas 1 and 2, have been remediated, so the parent site is also considered Interim Closed Out.**Location:** The two debris areas in Subsite 1 were located near 100-B Area. The two debris areas related to Subsite 2 were located south of Route 6 and 0.84 km (0.5 mi) east of SR 24.**This Site has the Following SubSites:****Code:** 600-341:1**Names:** 600-341:1; Inter Areas Battery Remnant Area #1A**Code:** 600-341:2**Names:** 600-341:2; Inter Areas Battery Remnant Area #1B

Code: 600-341:1**Classification:** Accepted**Names:** 600-341:1; Inter Areas Battery Remnant Area #1A**Reclassification:** Interim Closed Out (9/27/2010)**Type:** Dumping Area**Start Date:****Status:** Inactive**End Date:****Description:** The subsite has been remediated and Interim Closed Out. It consisted of two areas that were field identified as Area 1 and Area 2. They contained dry cell battery remnants and battery debris. Area 1 was approximately 1 meter (3 ft) in diameter. Area 2 was observed to be approximately 0.5 meter (1.5 ft) in diameter.**Location:** 600-341:1 Area 1 was located at coordinates N145065/E562123. Area 2 was located at coordinates N145365/E566735. Area 1 was west of 100-B Area and Area 2 was east of 100-B Area.**Process Description:** There was no process history associated with the 600-341:1 subsite, although Area 1 was thought to be associated with a pre-Hanford farm.**Closure Info:** Interim: Subsite 1 consisted of two debris areas. Remediation of Area 2 of the 600-341:1 subsite occurred on February 11, 2010. The excavation was approximately 2.5 by 3.5 meters (8 by 12 ft) and was approximately 0.5 meter (1.5 ft) deep. All of the Area 2 waste was sent to the Environmental Restoration Disposal Facility. Area 1 was remediated on February 16, 2010. Because the characterization sampling of Area 1 showed elevated cadmium levels, it was determined that the best disposal pathway was off-site shipment. Area 1 was excavated by hand to an approximate diameter of 1 meter (3 ft) and a depth of 0.5 meter (1.5 ft). A total of approximately 5 BCM (6.5 BCY) of material was removed from the waste site.**The SubSite is Part Of:****Code:** 600-341**Names:** 600-341; Inter Areas Battery Remnant Area #1

Code: 600-341:2**Classification:** Accepted**Names:** 600-341:2; Inter Areas Battery Remnant Area #1B**Reclassification:** Interim Closed Out (10/21/2010)**Type:** Dumping Area**Start Date:**

Status: Inactive**End Date:**

Description: The subsite has been remediated and Interim Closed Out. It consisted of two adjacent areas, Area 1 and Area 2, that contained dry cell battery remnants. The debris was discovered on October 23, 2008 while the Inter-Areas Segment 1 Orphan Site Evaluation was being conducted. The areas were described as being battery remnants covering an area 2 to 3 meters (7 to 10 ft) in diameter within a larger farmstead dump containing metal cans and glass. The 1943 aerial imagery shows an undeveloped road leading to the site location at the mouth of a large depression.

Location: 600-341:2 Areas 1 and 2 were located 0.33 km (0.2 miles) south of Route 6 and 0.84 km (0.5 mi) east of SR 24. Area 1 was at coordinates N144759/E560022. Area 2 was at coordinates N144771/E560005.

Closure Info: Interim: Staining was not present on the surface at the sample locations, but subsurface debris was observed at approximately 10 cm (4 in.) below the surface. Confirmatory sampling was determined to be unnecessary. Remediation occurred on April 26, 2010. After excavation, Area 1 was approximately 24 square meters (258 sq. ft) and Area 2 was approximately 12 square meters (130 sq. ft.). Each excavation was approximately 0.8 meters (2 ft) deep. The vadose zone beneath the excavation was approximately 12.1 meters (39.7 ft) thick. A total of approximately 15 BCM (20 BCY) of contaminated material was disposed at the Environmental Restoration Disposal Facility.

The SubSite is Part Of:**Code:** 600-341**Names:** 600-341; Inter Areas Battery Remnant Area #1**Code:** 600-342**Classification:** Accepted**Names:** 600-342; Inter Areas Contaminated Clothing Area near Susie Junction**Reclassification** Interim Closed Out (3/5/2010)**Type:** Dumping Area**Start Date:****Status:** Inactive**End Date:**

Description: The waste site has been remediated and Interim Closed Out. The site consisted of a 20 meter (66 ft) diameter area that contained discarded radiological protective clothing.

Location: This site was located 521 meters from "Susie" railroad junction and 140 meters west of waste site 600-38 (Railroad Siding Susie). The clothing debris was located approximately 8 meters southwest of the rail line.

Closure Info: Interim: The contaminated clothing was found in December 2008 in an area measuring approximately 20 meters (66 feet) in diameter. It was located at coordinates N140562/E566665. The radiological control personnel surveyed the clothing and properly disposed of the clothing. The area where the clothing had been located was radiologically surveyed. No contamination was detected.

The 600-342 waste site was remediated as a "plug-in" site in accordance with the Remaining Sites ROD (EPA 1999) and associated Explanation of Significant Difference (ESD) (EPA 2009). Per the 2009 ESD, plug-in sites are documented in the Administrative Record, and an annual fact sheet will be published by DOE identifying sites that have been added to the Remaining Sites ROD. The addition of plug-in waste sites will not have a significant impact on the scope, performance, or costs of the Remaining Sites ROD (EPA 1999). No RSVP document was written. The activity was documented on Reclassification form 2010-008.

Code: 600-343 **Classification:** Accepted

Names: 600-343; Inter Areas Burn Site #1 **Reclassification** Interim Closed Out (9/27/2010)

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: This site has been remediated and Interim Closed Out. It consisted of residual ash from burned material and a trench containing pieces of asphalt.

Location: The site was located approximately 481 meters (0.3 miles) WNW of Susie railroad junction (Gable Butte).

Process Description: The site was discovered on December 10, 2008 while the WCH Inter-Area Segment 1 Orphan Site Evaluation (WCH OSR-2009-0002; 147807) was being conducted. The feature was described as a 6 by 6 square meter (387 sq. ft.) stain resembling ash and asphalt dumped in a trench.

Closure Info: Interim: Remediation of the waste site occurred on February 9, 2010. Approximately 1 meter (3 ft) of fly ash and asphalt material were removed from the trench area. All excavated material was directly loaded into containers for shipment to the Environmental Restoration Disposal Facility. The excavation depth was 1 meter (3 ft) below ground surface. The vadose beneath the excavation was approximately 45 meters (148 ft) thick. A total of approximately 135 BCM (177 BCY) of material was removed from the waste site.

Code: 600-344 **Classification:** Accepted

Names: 600-344; Inter Areas Stain Site #1 **Reclassification** Interim Closed Out (10/21/2010)

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: This site has been remediated and Interim Closed Out. It consisted of an area of stained soil with pre-Hanford, metal container lids.

Location: The site was located in the southeast portion of Section 4 in Township 13N Range 25E, approximately 2.7 km (1.7 miles) northwest of the 100-B/C Area. It was approximately 0.5 km (0.34 miles) south of the Columbia River and 23 meters (75 ft) west of an unmarked road. (E561662.68; N145734.47)

Closure Info: Interim: A site walkdown was done in October 2008. One characterization sample was collected in December 2009. Remediation of the site occurred on April 26, 2010. Approximately 1 meter (3 ft) of stained soil and metal debris was removed from the area. All excavated material was directly loaded into containers for shipment to the Environmental Restoration Disposal Facility. The excavation depth was 1 meter (3 ft) below ground surface. The vadose beneath the excavation is approximately 15 meters (51 ft) thick, based on well data in the area. A total of approximately 120 bank cubic meter (BCM) (157 bank cubic yards [BCY]) of material was removed.

Code: 600-345 **Classification:** Accepted

Names: 600-345; 100-BC Vicinity Oil Stain and Filter Area **Reclassification** Interim Closed Out (10/21/2010)

Type: Unplanned Release **Start Date:**

Status: Inactive**End Date:****Description:** This site has been remediated and Interim Closed Out. It consisted of an area of stained soil with oil filters littered around.**Location:** The site was located on the south side of Route 6 approximately 450 meters (0.28 miles) west of the curve where Route 6 goes from a North/South to an East/West road. The site is approximately 28 meters (92 ft) south of 600-253 at coordinates E563569.11/N145087.08.**Closure Info:** Interim (10/21/2010): Remediation occurred on February 10, 2010. All the oil filters and stained soil were removed. The excavated area measured approximately 4 by 5 meters (12 by 15 ft) and was approximately 46 cm (18 in.) deep. A total of approximately 22 bank cubic meters (BCM) (29 bank cubic yards [BCY]) of material was removed from the waste site.

Following remediation, verification sampling was conducted in May 2010. Due to levels of total petroleum hydrocarbons (TPH) in the Quadrant 4 verification sample that exceeded cleanup criteria, this quadrant was further remediated August 2010. An additional 0.6 meters (2 ft.) of material was removed from Quadrant 4, bringing the total excavation depth to 1.06 meters (3.5 feet). The area was re-sampled. The results of all verification sampling indicated that the waste removal action achieved compliance with the remedial action objectives (RAOs) and remedial action goals (RAGs) for the 600-345 waste site.

Code: 600-346**Classification:** Accepted**Names:** 600-346; 100-BC Vicinity Ash and Debris Area**Reclassification** Interim Closed Out (9/27/2010)**Type:** Unplanned Release**Start Date:****Status:** Inactive**End Date:****Description:** This site has been remediated and Interim Closed out. It consisted of six small fly ash dump areas with metal debris.**Location:** This feature was located 654 meters east of the NE corner of the 100-B/C Area perimeter road, and 480 meters from the Columbia River shoreline at coordinates E566729.25/N145318.31.**Closure Info:** Interim: Remediation occurred on February 11, 2010. The six remediated areas ranged in size from 1.8 by 2.4 meters (6 by 8 ft) to 6 by 9 meters (20 by 30 ft). All excavations extended to approximately 46 cm (18 in.) below ground surface. A total of approximately 42.5 BCM (55.6 BCY) of material was removed from the waste site. The waste material was directly loaded into containers for shipment to the Environmental Restoration Disposal Facility.**Code:** 628-1**Classification:** Accepted**Names:** 628-1; White Bluffs Burn Pit**Reclassification** Interim Closed Out (9/16/2003)**Type:** Burn Pit**Start Date:****Status:** Inactive**End Date:****Description:** The site has been remediated and Interim Closed Out. The site was triangle shaped area, covered with sand and gravel. Physical evidence (e.g. small pieces of ash, etc.) indicates that the area affected was approximately 0.1 hectare (1/4 acre).**Location:** The pit was located approximately 300 meters (1,000 feet) north of the Route 2 North and Federal Avenue intersection.**Waste Type:** Misc. Trash and Debris

Waste Description: Soil sampling will be required to determine what contaminants are present.

Closure Info: Interim: In April 2003, a field walkdown was conducted to finalize contaminants of potential concern, identify sample locations, and identify sample types for development of a sampling design. Surface debris and evidence of burning were noted. A remedial action activity was implemented to remove identified contaminated soil and debris from the site for disposal at the Environmental Restoration Disposal Facility. The excavation depth was 0.37 meters (1.2 ft). Two verification soil samples were collected. The maximum detected results and a composite sample of underlying soil at the location suspected of having the greatest potential for residual contamination were used to support site reclassification.

100-IU-3

Code: 600-8 **Classification:** Accepted
Names: 600-8; Control Center for Battery A Nike Missile; MIL - H-06C; Wahluke Slope Nike Missile Base; WSNMB; 600-103 (Part) **Reclassification** Deleted From NPL (7/8/1998)
Type: Military Compound **Start Date:** 1/1/1950
Status: Inactive **End Date:** 1/1/1964

Description: The unit is an abandoned military installation that consists of a few concrete foundation pads, and a possible disposal location at a leveled area on the north side of the access road. Over the nearby cliff in the "saddle" were a few 19-liter and 208-liter (5-gallon and 55-gallon) drums and a small amount of debris. The Camp Hanford Forward Positions Descriptive Summary states that two 7600-liter (2000-gallon) underground storage tanks and one aboveground 5,700-liter (1,500-gallon) oil tank were included in the list of structures at this site. The document also states that all listed structures were sold to Washington State University and removed.

Location: The Unit is located at the end of a road near the summit of the Saddle Mountains (NE 1/4 of W 1/4 Section 16 T 15N R 27E).

Related Sites/ Structures: The site is related to the Nike Launch Site H-06-L (600-9).

Waste Type: Demolition and Inert Waste

Waste Description: The unit waste includes lumber, concrete, empty 5 gallon and 55 gallon containers and miscellaneous debris.

Code: 600-9 **Classification:** Accepted
Names: 600-9; Battery A Nike Missile Installation Launch Site; MIL - H-06L; Wahluke Slope Nike Missile Base; WSNMB; 600-103 (Part) **Reclassification** Deleted From NPL (7/8/1998)
Type: Military Compound **Start Date:** 1/1/1951
Status: Inactive **End Date:** 1/1/1964

Description: The waste site was remediated and Deleted from the NPL. It was an abandoned military site. All surface structures have been removed or leveled. Remaining features include a building foundation, roadways, parking areas, and drainage structures. The underground structure has been backfilled with 29-cubic yards of slurry. A 55-gallon drum buried to its rim, presumed to be a drywell, was also backfilled. Its function is unknown.

Location: The site was located north of 100-F Area, on the opposite side of the Columbia River. (NW 1/4 Section 34, T 15N R 27E; one mile north of Highway 24 at mile marker 62 1/2).

Related Sites/ Structures: One underground storage tank had been placed at this site during military operations. While the approximate location was known during the remedial activities, no evidence remained of the tank. It was assumed to have been removed during excess operations in the 1970s. A 208 liter (55 gallon) barrel, now backfilled, is buried to the rim at the perimeter of the site. An underground structure has also been filled in with slurry.

Waste Type: Demolition and Inert Waste

Waste Description: The unit contained miscellaneous debris including: paint cans, construction materials, asbestos siding and brake pads, and exposed re-bar associated with structure foundations.

Closure Info: Final: In 1974 the Atomic Energy Commission initiated a cleanup. Two missile magazines were demolished with explosives in June 1974. In 1993, the debris was removed and the underground bunker was filled with 29 cubic yards of slurry.

The 55-gallon drum "drywell" and a rock filled pit were sampled during the Expedited Response Action investigations (Sample numbers B07KQ2 and B07KQ3). No environmental hazards were identified.

As reported in the interim closeout report (DOE-RL 1994), full characterization of the H-06L landfill began in April 1994 as a confirmation of the sampling results per the Action Memorandum (Ecology and EPA 1994). Each location identified by the geophysical investigation (WHC 1992) as having an anomaly was excavated with a bulldozer or backhoe. Suspect waste was sampled for characterization by an offsite laboratory.

Table 4.1 of CDM (1994) details the wide variety of debris found at the anomalies excavated, including construction debris, oil filters, light bulbs, batteries, car frames, 208-liter (55 gallon) drums, transite, sheet metal, roofing tar, empty insecticide cans, bottles, dried paint, wood, shoes, rags, paper, food cans, silverware, auto engines, and a toilet bowl. A small cistern was backfilled. Table 4-4 of CDM (1994) describes the media and location of each of the samples taken from the landfills.

Approximately 459 cubic meters (600 cubic yards) of DDT-contaminated soil was discovered and disposed of at the Chemical Waste Management Hazardous Waste Landfill in Arlington, Oregon. More than 153 cubic meters (200 cubic yards) of petroleum-contaminated soil were found and disposed of in Pasco. Six 208-liter (55-gallon) drums of soil contaminated with metals from paint, tar-like waste, and soil from beneath several pesticide cans were designated and sent to the Hanford 616 waste facility. No ordnance or explosive waste was found.

Based on these discoveries, the U.S. Environmental Protection Agency (EPA) and Washington State Department of Ecology (Ecology) asked that the remaining North Slope disposal areas also be characterized and remediated as needed (DOE-RL 1994). Each of 10 potential landfill sites received a geophysical investigation to identify and excavate anomalies (Smith and Rhoades 1994). Because this site served as an analogous site for all the other military landfills, and because of the elevated levels of contamination found at this site, Ecology and EPA requested that all the military landfills be characterized and remediated as necessary (DOE-RL 1994).

This site was assumed to have an acid neutralization pit, based on facility drawings, but field investigators were unable to locate it at this site. Using the analogous approach, the pit at Site H 12L (600-6) was sampled. No areas of contamination above regulatory limits were detected (CDM 1994).

Code: 600-104	Classification: Accepted
Names: 600-104; USBR 2,4-D Burial Site; USBR-2.4-D	Reclassification: Deleted From NPL (7/8/1998)
Type: Burial Ground	Start Date: 1/1/1966
Status: Inactive	End Date: 1/1/1967
Description: The waste site has been remediated and Deleted from the Nation Priority List. It was a burial trench, approximately 122 meters (400 feet) by 18.3 meters (60 feet), used for disposal eleven empty tanks and soil contaminated with 2,4-Dichlorophenoxyacetic acid (2,4-D). The disposal	

site has been stabilized with native grasses and shrubs.

Location: The 2,4-D burial site is located across the Columbia River from 100 F Area. It is approximately 0.5 miles east of the Columbia River and south of the old White Bluffs townsite at the toe of an encroaching sand dune. (Section 35T, 14N, R27 E)

Process Description: In 1966, the U.S. Bureau of Reclamation (USBR) used this site to bury 46 meters (50 yards) of soil contaminated with 3,407 liters (900 gallon) of 2,4-D that had leaked from storage tanks from a USBR station in Eltopia, Washington (Roos 1990). In 1967, the USBR flattened and buried a reported eleven 2,4-D storage tanks (3.7 meters [12 feet] long with 1.2-meters [4-feet] diameters) in the same excavation as the contaminated soil (Ecology and DOE-RL 1997). The site has not been used since 1967, but the specific location of the burial trench and the dates the items were disposed on are not documented (Ecology and DOE-RL 1997). The half-life of 2,4-D in the soil under dry conditions is usually between 9.4 and 254 days with the average typical half-life under normal application conditions being about 10 days (Cramer 1985, DOE-RL 1994).

Waste Type: Chemicals

Waste Description: In 1966, 2,4-D contaminated soil was generated from leaking storage tanks at a USBR Station in Eltopia, WA. The burial consisted of 900 gallons of 2,4-D that had leaked into 50 cubic yards of soil. A second burial in 1967 consisted of the ten storage tanks, which were flattened and buried in the same location.

Closure Info: Final: Samples were collected from eight evenly spaced auger-rig borehole locations at the site in February 1993. Locations 1, 2, 3, and 4 showed less than detection limit results for field analysis of 2,4-D, so these samples were composited into sample number B07KQ6. Locations 5, 6, and 7, also less than the detection limit for field analysis, were composited into sample B07KQ7. Sample B07KQ5 was taken from location 8, which showed a positive (but near detection limit) field analysis result for 2,4-D (Lucas 1993). The laboratory samples showed no detectable levels of 2,4-D. (DOE/RL-2002-74).

Based on the 1993 sampling results and expected life span of the 2,4-D in the environment, only verification sampling (characterization) and hazard mitigation (if justified) was required for the site. In February and March 1994, geophysical surveys were conducted at the site to more precisely locate the buried tanks so angle borings could be drilled close to the edges of the tanks for the verification sampling. In July 1994, the U.S. Army Corps of Engineers drilled four exploratory holes at an incline under the buried tanks. Four samples were collected per borehole, plus two duplicate samples and one split provided to Ecology for a total of 19 samples. No 2,4 D or breakdown products were detected. The samples were analyzed for chlorinated herbicides with a method detection limit for 2,4-D of 0.2 ppm (Shannon & Wilson 1994c, Ecology and DOE-RL 1997).

In 1997, a hunter reported to the Fish and Wildlife Commission that he had seen the weathered, 2,4 D Burial Site warning signs and he believed there was still contamination at the site. The EPA toured and investigated the site on May 3, 1997 with the hunter and conducted cursory sampling by digging four small pits that were 0.9 meters (3 feet) in diameter and 0.6 meters (2 feet) deep at locations that showed stressed vegetation. These pits were located 1.5 to 3 meters (5 to 10 feet) from the base of the sand dune and at random locations 6.1 to 61 meters (20 to 200 feet) north of the buried tanks. During the investigation, strong chemical odors were encountered (Ecology and DOE-RL 1997).

Four samples were collected, one of which had a detectable level of 2,4-D higher than the cleanup standard of 800 ppm. This "hot spot" had 2,4-D concentrations of 2,500 ppm (Ecology and DOE RL 1997). The "hot spot" was estimated as 7.6 meters long by 4.6 meters wide by 1.5 meters deep (25 feet long by 15 feet wide by 5 feet deep) (Lerch 1998). The results of this "hot spot" sample resulted in EPA approving a sampling plan in May 1997 that would further

characterize the contamination at this spot (Ecology and DOE-RL 1997).

The characterization sampling data showed 2,4-D as high as 17,000 ppm and approximately 15 cubic meters (20 cubic yards) of contaminated soil that were above the cleanup standards. In addition, the 2,4 D sample contained dioxin levels that exceeded the MTCA standards of 0.00000667 ppm. The contamination ranged from 0.6 to 2.4 meters (2 to 8 feet) deep in the soil. Additional hand auger samples to depths of 1.5 meters (5 feet) taken by EPA indicated further 2,4-D levels ranging from 1,000 to 1,300 ppm (Ecology and DOE-RL 1997).

Contamination was considered to potentially go 3 meters (10 feet) deep and all across the area, based on the sampling data. There is no impact on the groundwater in the area as the groundwater is over 90 meter (300 feet) below the surface of the site and, hence, is not contaminated or impacted by the 2,4-D at this location (Ecology and DOE-RL 1997).

The site was reopened and remediated under a CERCLA Action Memorandum issued in 1997 (Ecology and DOE-RL 1997). In August and September 1997, the bioremediation efforts were under way at this site. Excavated soil was placed on a plastic liner 30 mm thick, and composted manure was tilled into the soil and irrigated regularly (Lerch 1998). Random samples were periodically collected until the results fell within the allowable limits for 2,4-D, which marked the end of the bioremediation process for this waste site (Lerch 1998). The 2,4-D and dioxin-contaminated soil from the "hot spot" identified in May 1997 was excavated and shipped as U240-listed waste to the Laidlaw, Deer Park Treatment, Storage, and Disposal Facility in Texas. About 25 cubic meters (80 cubic yards) of contaminated material was shipped to Texas. Ten crushed tanks were found and removed as well (the eleventh tank was not found). They were shipped as U240-listed waste to the Laidlaw, Grassy Mountain Treatment, Storage, and Disposal Facility in Utah (Lerch 1998). As reported in Lerch (1998, sample numbers, cleanup criteria, and results on pages A-1 and A-2 of DOE/RL-2002-74), five confirmation samples were collected from the excavated tank pit, 20 from the excavated trench, and 11 from the bioremediation area. All results were below the cleanup criteria.

All the objectives established in the 1997 Action Memorandum were met as stated in the closure document 100-IU-3 Waste Site 600-104 Remediation Summary (Lerch 1998).

100-IU-4

Code: 600-105	Classification: Accepted
Names: 600-105; SDBDL; Sodium Dichromate Barrel Disposal Landfill	Reclassification: Final Closed Out (2/12/1996)
Type: Burial Ground	Start Date: 1/1/1945
Status: Inactive	End Date: 1/1/1945

Description: The site has been remediated. It contained approximately 5000 crushed 55 gallon drums. The 1993 Sodium Dichromate Expedited Response Action removed the crushed barrels and small amounts of other waste.

Location: The site was located in a small depression between 100-D and 100-H areas. It was approximately 130 meters north of the access road that runs between where the 100-D Badge House and the 100-H Badge House were located.

Process Description: There is very little historical information documented about this site. The landfill was used during the reactor operation years as a disposal site for crushed, empty Sodium Dichromate barrels. Sodium Dichromate was used as a corrosion inhibitor in the reactor cooling water systems.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: The wastes disposed of at this site were empty, crushed drums containing sodium-dichromate residue. It is estimated, assuming that 1% of the original quantity of sodium dichromate remained in the drum on disposal, that 30.9 tons of sodium dichromate were disposed. The sodium dichromate was used for water treatment in the 100 Areas. This disposal technique was used only once at this site.

Closure Info: Final: The crushed drums were removed between March 17, 1993 and April 26, 1993. Conventional earth moving equipment was used to exhume the barrels and to transport them to the Central Landfill. During the removal activities, small quantities of asbestos, waste oil and batteries were found. These items were disposed of as hazardous waste.

The area included 144 anomalies located in eleven subsurface zones. Four zones contained empty, crushed sodium dichromate barrels. The areas were excavated to a maximum depth of 7 feet. Approximately 5000 crushed barrels and miscellaneous debris (wire fencing and wood posts) were transported to the Central Landfill.

Besides containing crushed drums, the four zones included some loose asbestos, one crushed drum full of asbestos. The drum of asbestos went to the Central Landfill asbestos section for disposal. Other anomalies included two 5 gallon roofing tar cans, one paint can, and used oil and grease (about 0.5 gallons total). These materials were placed in three 55 gallon drums and sent to an offsite disposal facility.

This was the only waste site in Operable Unit 100-IU-4. A 1996 Record of Decision was issued stating that no further remedial actions are necessary in 100-IU-4.

100-IU-5

Code: 600-106	Classification: Accepted
Names: 600-106; WBPAC; White Bluff Pickling Acid Cribs; White Bluffs Pickling Acid Cribs	Reclassification: Final Closed Out (2/12/1996)
Type: Crib	Start Date: 1/1/1943
Status: Inactive	End Date: 1/1/1945

Description: The site has been characterized and closed with a No Action alternative. The cribs are located west of 100-F Area, south of the intersection of Route 2 North and Federal Ave. The site consisted of two cribs located side by side. The western crib was 200 feet by 45 feet with a 3 foot diameter riser pipe. The eastern crib was 225 feet by 50 feet. Vent pipes protruded from the surface of each crib at 7 to 9 foot intervals. The surface was covered with large cobbles.

Process Description: It is assumed that the cribs received acid etch solutions from the pipe fabrication facility located northeast of the cribs. Nitric and Hydrofluoric acids were used to "pickle" galvanized pipe before being used in the construction of the 100 Area reactors.

Waste Type: Chemicals

Waste Description: The site was used to dispose spent pickling acid used to pickle galvanized piping for use in the reactor buildings during construction. The process used several thousand gallons of nitric and hydrofluoric acid. Generally, the acid was neutralized prior to disposal, but may not have been completely neutralized prior to disposal. Chromium was also identified as a contaminant of concern.

100-IU-6

Code: 600-3 **Classification:** Accepted
Names: 600-3; Hanford Townsite Excess Material Storage Yard/Paint Pit **Reclassification:** Interim Closed Out (9/14/2011)
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The site has been remediated and Interim Closed Out. It consisted of a shallow trench that appeared to be an old borrow pit. The trench was approximately 37 by 27 by 1.2 meters (120 by 90 by 4 feet). The dumping area spread out over an area approximately 280 by 490 meters (925 by 1,600 feet). Both the dumping area and pit showed signs of an attempt to cover the waste with a bulldozer, as tracks were visible throughout the areas. The site also had evidence of burning. The remains of an old railroad spur was just east of the waste site. Debris included metal items, cans, burned wood, transite piping and rubber. Several radioactively contaminated items were found during the remediation activity.

Location: The site was located north of Gable Mountain, west of Route 2 North, south of Route 1, and approximately 0.8 kilometers (0.5 miles) south of the intersection of Route 1 and Route 2 North.

Waste Type: Misc. Trash and Debris

Waste Description: Dried paint and paint cans can be found on the south side of the pit. Closure rings for 208-liter (55-gallon) drums, roofing paper, and a white fibrous substance suspected of being asbestos are also present. The dumping area contains various solid wastes that include, broken wet cell battery cases and plates, stainless steel pipe and materials, various sizes and types of containers (three which are labeled as containing ethylene glycol), machining operations cuttings, pieces of aluminum, pieces of galvanized sheet, burnt wood, and the remains of dry cell batteries.

Closure Info: Interim (9/14/2011): Based on existing historical information of the 600-3 waste site, the waste site was recommended for remove, treat, and dispose (RTD) in the Remaining Sites ROD (EPA 1999). Remedial action at the 600-3 waste site began in February 2010, and was completed in February 2011.

On February 23, 2010, a piece of 2.5-cm (1-in.) diameter pipe, approximately 5 cm (2 in.) long, was found amid other debris. The pipe had a bright yellow discolored surface and had field radiological readings of approximately 88,000 disintegrations per minute beta/gamma. The radiation was fixed and no dose was coming from the item. This discovery initiated the posting of the area as a contamination area (CA). Work was suspended at 600-3 until a path forward could be determined.

Excavation began again on April 13, 2010, with radiological controls in place. Several beta-gamma contaminated items were found throughout the remediation process, which led to the site being posted as a radiological buffer area (RBA) and soil contamination area (SCA). Other waste items found in concentrated locations at the waste site included paint, pin boxes, drums, crucibles, miscellaneous metal debris, lead sheeting and batteries, and potentially friable asbestos. Several areas of disturbed vegetation, staining, and burning were also found.

The final excavation footprint at the 600-3 waste site consists of a large excavated area divided into the east and west excavations, three waste staging pile area footprints, and smaller areas where concentrated contaminated materials were found, some of which are outside of the main excavation footprint. All of the staged waste was loaded out to the Environmental Restoration Disposal Facility (ERDF). The areas where concentrated lead batteries were found outside of the main excavation also have associated small waste staging pile footprints, which have been

loaded out to the ERDF. Across the main excavation footprint, the depth of excavation ranged from 1 meter (3 ft) to 6 meters (20 ft).

Code:	600-23	Classification:	Accepted
Names:	600-23; Dumping Area Within Gravel Pit #11; Gravel Pit 11	Reclassification	Interim Closed Out (11/30/2001)
Type:	Dumping Area	Start Date:	
Status:	Inactive	End Date:	
Description:	The site has been remediated and Interim Closed Out. The waste site was an area of buried debris inside a large gravel pit (WIDS site code 600-248). The majority of the waste was located in the southern portion of a terrace, which was at the west end of the gravel pit, south of the entrance road. Approximately sixty drums of tar like material were removed from this area, along with concrete, laboratory equipment, batteries and vitrified glass.		
Location:	This site was located north of the Wye Barricade on Route 2 South, near mile marker number 6, south of the Hanford townsite on the east side of the road. The waste site was inside Gravel Pit #11.		
Related Sites/ Structures:	This site was associated with Gravel Pit 11 (site code 600-248).		
Process Description:	The east, southeast and southwest portions of the pit were utilized for dumping of construction debris, equipment and drums. The northeast portion of the pit is still actively used as a gravel source for backfill material.		
Waste Type:	Barrels/Drums/Buckets/Cans		
Waste Description:	Barrels, most of which were empty, were present at the face of the terrace.		
Waste Type:	Asbestos (non-friable)		
Waste Description:	Transite building siding was observed at the site.		
Waste Type:	Construction Debris		
Waste Description:	The middle terrace at the west end of the unit contained construction debris. Based on interviews with Hanford employees, drums, construction debris, laboratory equipment from 1706 KE and large pieces of equipment from the 300 Area may have been buried at the site. It had been indicated that the equipment was located on the east edge of the pit. It was possible that some asbestos may have been present. Some of the material disposed of here may have been radiologically contaminated. The contents of the drums were not known.		
Closure Info:	Interim: Remedial action at the 600-23 site began on February 1, 2001. More than 16,330 metric tons (18,000 tons) of material were excavated from the 600-23 site and transported to ERDF for disposal. In addition, approximately 60 drums of tar and asphalt-like material were removed and sent to an offsite facility for treatment and disposal. Material excavated from the site included soil, concrete, equipment (1706-KE laboratory material), drums, and debris (batteries, elemental lead debris, chromium contaminated debris, vitrified glass). Other than a small amount of liquid present in some of the drums and in a piece of process equipment, there was no liquid waste encountered during the excavation. Clean overlying and co-mingled soil that was segregated during the excavation process was stockpiled at the site for use as backfill. This stockpiled soil is referred to as overburden throughout the rest of this CVP. Approximately 91.7 cubic meters (120 cubic yards) of concrete debris excavated during remediation, with		

individual pieces as large as 1.5 meters by 1.8 meters by 0.6 meters (5 ft by 6 ft by 2 ft), were used to partially backfill the site excavation. The concrete will be covered with backfill soil. Samples collected from the concrete indicated that the concrete is an inert demolition type debris. The agreement to use the concrete debris as backfill and the concrete debris sample results are included in Closeout Verification Package for the 600-23 Site Meeting Minutes.

The remaining soils at the 600-23 site have been sampled, analyzed, and modeled. The results of this effort indicate that residual concentrations in the shallow zone will support future land uses that can be represented (or bounded) by a rural-residential scenario, and that residual concentrations throughout the site are protective of groundwater and the Columbia River. Based on agreement between EPA and DOE on concrete sampling analyses results, remaining site concrete debris will be used to partially backfill the site excavation.

Code:	600-107	Classification:	Accepted
Names:	600-107; Gable Mountain Plutonium Storage Vault Cribs; 213-J & K Cribs; 213-J&K Cribs	Reclassification	Interim No Action (2/9/2004)
Type:	Crib	Start Date:	1/1/1944
Status:	Inactive	End Date:	1/1/1950
Description:	The site has been evaluated and determined to require No Action. The sites consisted of two small cribs (gravel filled culverts) located on the southwest corner of 213-J and the southeast corner of 213-K Storage Vaults.		
Location:	The site was located north of Route 11A, at the base of Gable Mountain.		
Related Sites/ Structures:	The cribs were co-located with the 213-J&K Vaults.		
Process Description:	The cribs were gravel-filled concrete culverts. Each had a black iron distributor pipe, 5.1-centimeter (2-inch) diameter, running its length approximately 1.2 meters (4 feet) below ground level. Each was covered by a 5.1-centimeter (2-inch) thick concrete slab.		
Waste Type:	Water		
Waste Description:	Very little water solution ever entered this unit. The distributor piping was removed and inspected. Rust scale taken from the interior of the pipes was found to be free of radioactivity background levels. The unit was removed from radiation zone status on November 11, 1974.		
Closure Info:	Interim: A backhoe was used in November 1974 to excavate down to the crib structures to allow for radiological surveys and sampling of the soil and inlet piping. No contamination was found above background limits. The backhoe essentially destroyed the crib structures. The excavated material was returned to the hole and backfilled. The cribs were removed from radiation zone status. The words Contaminated Material had been inscribed on the concrete cover slabs. The words were removed with a jack hammer.		

Waste Site Evaluation, 600X-CA-V0025, Rev 3, (BHI 2004) demonstrated that the cleanup verification results from samples of underlying soil support the no action reclassification of the site. Residual material at the site achieves the remedial action objectives and the corresponding remedial action goals established in the Remedial Design Report/Remedial Action Work Plan for the 100 Area (DOE-RL-96-17) and the Interim Action Record of Decision for the 100-BC-1, 100-BC-2, 100-DR-1, 100-DR-2, 100-FR-1, 100-FR-2, 100-HR-1, 100-HR-2, 100-KR-1, 100-KR-2, 100-IU-2, 100-IU-6, and 100-CW-3 Operable Units (EPA 1999).

In May 2003, confirmatory samples were collected from the two cribs by digging a test pit was dug at each crib. Smear samples were collected from the inlet piping of each crib. Subsurface

soil samples were collected from each crib. The sample results verify material at the site does not exceed the Remedial Action Goals (RAG).

Code: 600-108	Classification: Accepted
Names: 600-108; 213-J & K Magazine Waste Storage Cavern; 213-J&K Storage Facility (SF); 213-K Vault; 218-E-16	Reclassification: Interim Closed Out (7/19/2011)
Type: Storage	Start Date: 1/1/1944
Status: Inactive	End Date:

Description: Sitecode 600-108, refers to the 213-K Vault. The 213-J Vault is described in sitecode 600-257. Both vaults have been remediated and Interim Closed Out.

The 213 facility was constructed into the south side of the base of Gable Mountain. The vaults are two parallel reinforced concrete, earth covered storage facilities. The south end of each vault forms a continuous reinforced concrete wing-shaped retaining wall with an attached reinforced concrete loading platform. Distance between the two vaults is 13.6 meters (44.5 feet). Each vault contains three rooms: magazine, vestibule, and instrument room. There are two outside, steel-hinged doors opening onto the loading platform. An inner steel vault door separates the vestibule from the magazine. The 213-J Vault is the western vault. The 213-K Vault is the eastern vault.

Location: The unit is located north of Route 11A, east of Gable Mountain Pond.

Related Sites/Structures: The site is associated with two cribs (sitecode 600-107) and the 213-J Vault, sitecode 600-257.

Process Description: The vaults were originally built to store containers of processed plutonium product and waste boxes. Later, the vaults were used to store explosives and ammunition, and for seismic testing.

The 213-K vault was used to store equipment in drums that had been contaminated with radioactive sodium. A radiological survey done in October 1981 states the drums had maximum dose rates of 5 millirad per hour. The same radiological surveys reported no smearable contamination in the vault. A radiation survey on July 17, 1990, showed no contamination on the drums. Sodium-22 has a half-life of 2.6 years; sodium-24 has a half-life of 15 hours.

Waste Type: Equipment

Waste Description: The vaults were originally constructed for storage of Hanford plutonium product in containers. They were used only briefly, (1944-1947), for that purpose. They were subsequently used to store explosives, ammunition and drums of equipment contaminated with radioactive sodium. Dose rates up to 5 millirad/hour were measured inside 213-K, on the drums containing sodium contaminated equipment (10/21/1981). No smearable radioactivity was detected on any of the surfaces inside the vaults. All contaminated materials have been removed from the 213-K Vault. It is now empty. Both the 213-K and 213-J vaults have been released from radiation zone status.

This site was listed as a candidate for sampling in the 100 Area Remaining Sites ROD. Based on a site walkdown conducted in 2003, it was determined that this site required remedial action. Material containing asbestos and other potentially hazardous material was observed.

Closure Info: Interim: The vaults were used for storage of processed plutonium from 1944 to 1947, and were surrounded by a barbed wire fence and guard tower, both of which are no longer present. Processed plutonium product and waste were sent to the vaults in boxes. The 213-K Vault had also been used to store drums containing equipment that had been contaminated with

radioactive sodium. All contaminated materials have been removed from the 213-K Vault, and it was empty prior to the initiation of remedial activities. The 213-J Vault was used in more recent years to store uncontaminated soil samples for use in fallout studies. These soil samples were removed from the vault in March 2002 in the process of emptying the vault. A waste site walkdown was performed on January 9, 2001, to verify that nothing was stored inside the 213-K Vault. The vault was empty and no radiological postings were found. An additional site walkdown was performed on May 1, 2003, at which time the fan room between the two vaults was assessed. Transite and other potential asbestos containing materials were used in construction of the fan room and in the construction of a fire-safe door in the interior of the vaults. The wood of the fan room building roof was found to be rotting and caving in. A 189-L (50-gal) condensate collection tank was found inside the fan room that may have been connected to the outside condensate piping seen on geophysical surveys of the area. No radiological readings were found in the floor drain or elsewhere in the fan room building.

The 600-108 and 600-257 waste sites were remediated together and documented in the RSVP-2011-051. The vaults were split into two sitecodes in June 1999 to accommodate multiple contractor responsibilities.

Remedial action at the sites began on November 8, 2010, and was completed on January 20, 2011. A small oil spill near the vault entrance was assessed. Concrete and other debris were stockpiled prior to removal from the 600-108 excavation for shipment and disposal to the Environmental Restoration Disposal Facility. The overburden soils that surrounded the vaults were stockpiled adjacent to the waste site and will be used to re-contour Gable Mountain to its pre-Hanford conditions. The foundation of the vaults was removed entirely, to a depth of approximately 1 to 2 meters (3 to 6 ft) at the base.

On December 9, 2010, an oil reservoir was found in the fan room at the 600-108 waste site, and a small amount of oil was released to the ground just south of the vault entrance. Most of this oil spilled onto a concrete slab that was subsequently removed; however, a small amount may have leaked under the wall into the area where the vaults were located. In-process samples were collected from this oil spill. The spilled oil was staged on Griflon to the south of the excavated area.

Code:	600-109	Classification:	Accepted
Names:	600-109; Hanford Trailer Camp Landfill; HTCL	Reclassification	Interim Closed Out (2/1/2011)
Type:	Sanitary Landfill	Start Date:	1/1/1943
Status:	Inactive	End Date:	1/1/1945
Description:	The waste site has been remediated and Interim Closed Out. Surface markings suggest that materials have been covered by bulldozing with excavation spoil. Visible debris, including glass, metal and concrete, was widely scattered within the gravel pit. A large pile of river rock was located in the central part of the excavation.		
Location:	The site was located west of the old Hanford High School, north of Roosevelt Avenue, inside Gravel Pit 15.		
Related Sites/ Structures:	The site is associated with Gravel Pit 15.		
Waste Type:	Misc. Trash and Debris		
Waste Description:	The unit was used for typical domestic wastes that were used during construction of the Hanford Site facilities. Debris includes metal, glass, fabric and rubber. Nondomestic metal scrap, rebar and concrete is also present.		

Closure Info: Interim: During a site walkdown in May 2004, minimal surface debris was found at the site. However, several relatively large anomalous zones were identified that have the character of buried debris or garbage. The majority of the debris appears to be buried within a 120 by 200 meter (394 by 656 feet) area, all within the Gravel Pit 15 boundary. Pre-Hanford orchards were located in this area.

Following an archaeological investigation and waste characterization sampling in September 2009, the site was remediated from January to March 2010. Based on the site walkdown, geophysical survey, and observations during an archaeological investigation, confirmatory sampling was determined to be unnecessary, and the waste site was recommended for Remove, Treat, and Dispose (RTD). The excavation was approximately 4.6 meters (15 ft) deep in most areas with several places that were slightly deeper. Approximately 9,108 bank cubic meters (BCM) (11,913 bank cubic yards [BCY]) of material was removed from the excavation. Potential asbestos-containing material was secluded from the rest of the excavation, and was directly loaded into ERDF cans.

Code: 600-110	Classification: Accepted
Names: 600-110; Hanford Townsite Landfill; HTL	Reclassification: Interim No Action (8/4/2004)
Type: Sanitary Landfill	Start Date:
Status: Inactive	End Date: 1/1/1943

Description: The site has been evaluated and determined to require No Action. It consisted of an unlined excavated area that had been backfilled.

Location: The unit was located south of the Hanford Construction Camp between Route 2S and the Hanford Swimming Pond in the horseshoe bend of the irrigation canal.

Process Description: Research indicated that the landfill was possibly used as a canal that carried water for irrigation. Additional research noted that it operated as an unlined excavation used to dispose of typical industrial and domestic wastes from 1850 to 1943 from the original Hanford townsite. Following the site's operational use, it was backfilled with clean fill for the construction of the Hanford Construction Camp. Stenner et al. (1988) reported that the waste site was not intended to receive radioactive waste. Research also suggested that this waste site was active after 1944 and continued to receive industrial and domestic waste. Early photographs indicated no Hanford Works related ground-disturbing activities prior to March 1944, other than construction for the nearby Hanford Irrigation Canal.

Waste Type: Misc. Trash and Debris

Waste Description: The site was used to dispose of normal industrial and domestic wastes common for the period.

Closure Info: Interim: In February 2004, a site walkdown documented the presence of domestic debris that included milk bottles, canning jars, colored glass and metal cans scattered on the surface of the site. A geophysical survey was done and identified subsurface debris. Three test pits were dug. No hazardous debris or stained soil was found, so no samples were collected.

The site reclassification to No Action decision was supported based on reviews of the site history, field observations, geophysical surveys, and the confirmatory field investigation results conducted for the Remaining Sites Verification Package (RSVP). No hazardous debris or stained soil was found at the surface of the site or in the subsurface soil during excavation of anomalous areas.

Code: 600-111	Classification: Accepted
Names: 600-111; P-11 Critical Mass Laboratory Complex (Buildings, Crib, 2 Septic Systems and Associated Piping)	Reclassification: Interim Closed Out (10/28/2008)
Type: Laboratory	Start Date: 1/1/1949
Status: Inactive	End Date: 1/1/1951

Description: The waste site has been Interim Closed Out. The site consisted of the P-11 Critical Mass Laboratory which included two facilities (120 Experimental Building and 123 Control Building), a crib, two septic system associated tile field and pipelines, and underground piping and remaining soil contamination. The facilities, crib, and underground piping were decontaminated and demolished in 1974. The facility cleanup plan was unclear whether the concrete foundation of the 120 Building was removed. The foundation of the uncontaminated 123 Building does remain below grade. This site also included two septic tanks.

The 120 Building contained two test rooms, a change room with shower, lavatory, service sink and hot water tank. The flooring was a 30.5 cm (12 in) concrete slab perforated by floor drains. The floor drain material went via piping into a below grade catch basin. From the catch basin, the outlet pipeline went to the waste disposal crib.

The waste disposal crib was constructed of concrete slabs interlaced together to form an 2.4 m by 2.4 m by 1.5 m (8 ft by 8 ft by 5 ft) crib. At one time, a fence surrounded the crib.

The septic system was located due east of the 123 Building. There were two septic tanks, an old and a new (identified on drawing H-7-698). The old septic tank, located approximately 14.7 meters (48.2 ft) from the 123 Building was filled with dirt and abandoned in place. Drawing H-7-698 Note 3 identifies that the original tank had been damaged. The piping from the 123 Building to the new septic tank was replaced with new 10 cm (4 in) vitrified pipe. The new septic tank was located approximately 0.5 meter (1.6 ft) east of the abandoned septic tank. The tile field begins approximately 36.7 meters (120.4 ft) further east and had twelve laterals, six per side.

Location: The crib and septic systems were located at the P-11 Critical Mass Laboratory, approximately 4.8 kilometers (3 miles) south-southeast of 100 F Area and 0.5 kilometers (1/3 mile) west of Route 2N.

Release Description: On November 16, 1951, a critical excursion (an uncontrolled criticality) resulted in extensive plutonium contamination to the interior of the 120 Building. During the final stages of decontamination work to reactivate the facility, December 4, 1951, a fire broke out in the southwest part of the building apparently from spontaneous ignition of decontamination materials. The fire gutted the storage room and chemistry laboratory, burned through the ceiling, melted the aluminum filter ducts, and set fire to the exhaust filters. Contamination was extensive in this area and throughout the attic after the vent system was breached. Because connecting doors were open, contamination also spread to other parts of the building, particularly to the process rooms. The spread of contamination was augmented by fire control measures, resulting in radioactive particulates being washed to the outside of the building along the foundation and door thresholds. The contamination was fixed using sealants and concrete grout. The 120 Building was sealed off and abandoned in consideration of the high risk and cost to decontaminate and restore the facility for continued criticality studies.

Related Sites/ Structures: The site is associated with the P-11 Critical Mass Laboratory (120 Building Criticality Laboratory) and UPR-600-16.

Process Description: The P-11 Project was developed as an experimental facility to support proper design of new chemical separation facilities and was a prerequisite to increased batch size in the 200 Area

process. Prior to 1952, the P-11 Facility was used as a laboratory for plutonium criticality studies.

The facility consisted of two buildings, the 123 Building (a converted residence) and the 120 Building. The 123 Building, which served as the control house, had been razed (prior to 1974). No plutonium contamination was involved at this component of the site. The 120 Building, which was a single story sheet metal building (oriented north-south) contained the critical assembly room, a small chemistry laboratory, storage and tank room, and a change room. Drain lines from the building and process equipment were routed to an underground waste crib for retention of any disposed radioactive nuclides in the soil.

The site was specifically sited isolated from the normal process areas because of the nature and hazards of the work. The 123 Experimental Building was located 48.8 m (160 ft) directly south of the 120 control building. The experimental building was so located relative to the control building that neither the generally prevailing breeze nor the force winds would carry any airborne contamination towards the control building.

Waste Type: Soil

Waste Description: Contaminants of Potential Concern (COPCs) included isotopic plutonium, americium-241, gamma-emitting radionuclides, polychlorinated biphenyls (PCBs), inductively coupled plasma (ICP) metals, mercury, and semivolatile organic compounds (SVOCs). Although asbestos was a COPC, it was only to be sampled if suspect asbestos material was observed during sampling activities. The site received low-level plutonium waste from the 120 Building (Critical Assembly Room, Chemistry Laboratory, Storage and Tank Room, and Change Room). The 120 Building and the crib were demolished in 1974. The waste removed from the site during decontamination and demolition activities consisted of seven transuranic waste boxes, fibreglassed plywood and steel, that were buried in trench 8 of 218-W-4B (Burial Ground). All non-transuranic waste was buried in mixed fission product trenches 12 and 14 in 218-W-4A. The seventeen drums of transuranic waste were buried in trench 7 of 218-W-4B. The details are 268 - 208 liter (55 gallon) drums, mixed fission products, weighing 50,770 kilograms (111,695 pounds); 17 - 208 liter (55 gallon) drums, transuranic waste, weighing 3,809 kilograms (8,380 pounds); 5 - fiberglass reinforced plywood boxes, weighing 2,600 kilograms (5,200 pounds); 73 - plywood boxes, weighing 124,682 kilograms (274,300 pounds); 2 - steel boxes, weighing 5,009 kilograms (11,020 pounds); 6 truck loads, 8,364 kilograms (18,400 pounds). A total of 10,909 kilograms (24,600 pounds) were buried as transuranic waste and 183,816 kilograms (404,395 pounds) were buried as mixed fission products. Nontransuranic waste was based on a waste burial limit of 10 nanocuries per gram. This limit was determined by radiation monitoring personnel. These low level wastes were designated as mixed fission products and thus, did not require containment for 20 year retrievability.

Closure Info: Interim: Confirmatory sampling from test pits and trenches was performed from April 29 2004 through May 10, 2004. To track results of confirmatory sampling, the P-11 lab complex waste site was stratified into the following seven areas for evaluation and sample collection. Area 1 was the Former 120 Experimental Building location, Area 2 was the Former P-11 Crib location, Area 3 was the Former 123 Control Building location, Area 4 was the Geophysical anomaly, Area 5 was the Septic Drain Field, Area 6 was the Septic Tank and Area 7 was the Surface Depression. Results of confirmatory sampling at Areas 1, 2,3 and radiological surveys at UPR-600-16 determined no action was required. Confirmatory samples from Areas 5 and 6 found elevated levels of PCB's, arsenic cadmium and lead.

Some minimal radioactivity was detected, but the RESRAD modeling determined the dose rare for all pathways was less than 15 millirem per year.

Remedial action of the septic system tank and drain field (Areas 5 and 6) located at 600-111 was performed between February 25, 2008 and March 25, 2008. The site was excavated to

approximately 4.6 meters (15 ft) below grade (at the deepest portion), resulting in a combined volume of approximately 2,755 cubic meters (3,603 cu. yd) of material removed and disposed at the Environmental Restoration Disposal Facility. Verification soil samples for the septic system remediation were collected on April 21, 2008.

All test pits/trenches were excavated and sampled in late April 2004 through early May 2004 as specified in the sampling work instruction. During excavation, field monitoring for VOCs was performed and no constituents were detected. In addition, FIDLER radiological surveys were performed during the excavations. No radiological contamination above twice the background level was found.

Code: 600-146	Classification: Accepted
Names: 600-146; Steel Structure on Northwest Side of Gable Mountain	Reclassification: Interim Closed Out (7/21/2010)
Type: Dumping Area	Start Date:
Status: Inactive	End Date:

Description: The site has been dismantled and Interim Closed Out. It was a steel frame structure constructed of "I" beam and "L" beams. The interior of the structure contained stainless steel piping running throughout. Metal grating was located on three levels of the structure. The structure appeared to be laying in a horizontal position. Debris observed near the structure included stainless steel pipe, metal rings, metal boxes, empty cans and wood. Two earth berms were located east of the metal structure. To the east of the berms was a small concrete pad approximately 1.5-1.8 square meters (5-6 sq. feet). A pile of lumber was located near the metal structures. Some of the lumber had shingles attached. There was also a small area of discolored soil containing metal fragments and charred wood.

Location: The site is located on the north side of Gable Mountain and just south of the dirt road that runs east west along the north side of Gable Mountain. The site is best accessed by turning east just north of milepost 2 on Route 4 North. Continue east on the paved road until the road begins to turn up the mountain. At this point, continue straight ahead on the dirt road which continues east along the mountain. The site is located approximately 1.9 miles from Route 4 North. The site falls along a section of the dirt road that is bounded by signs reading "Hazardous Area, Keep Out - Authorized Personnel Only".

Waste Type: Equipment

Waste Description: The waste is a steel structure, stainless steel piping, metal parts, metal fragments, and the lid from a military type ammunition can (no label).

Closure Info: Interim: In January 2002, the structure was searched for abandoned explosive material. No explosive material was found.

A radiological survey was conducted in September 2009 to support characterization of the waste site, and no radiological activity above background was indicated. In April and May 2010, the sheared steel, wood were removed and the underlying soil was bladed to flatten the area. The wood debris was sent to ERDF. The steel structure was recycled.

Code: 600-149	Classification: Accepted
Names: 600-149; 600-54; 661 Complex; Rifle and Pistol Range; Small Arms Range	Reclassification: Interim Closed Out (11/15/2011)
Type: Military Compound	Start Date:

Status: Inactive**End Date:****Description:** The site consisted of two subsites. Subsite 1 was the Range complex which included a Range House Building, Well Pump House, and four firing ranges. Subsite 2 consisted of the soil berm located behind the pistol/rifle range area. Both subsites have been investigated and Interim Closed Out, so the parent site is also considered Interim Closed Out.**Location:** The site is located north of the east end of Gable Mountain. It is west of Route 2 North and the Hanford Airport.**Related Sites/ Structures:** The Small Arms Range is associated with 600-349 and 600-358.**Process Description:** The complex operated from the mid-1940's through the 1950's as a practice range for handguns, rifles, shotguns, machine guns, hand grenades, smoke bombs, and other small arms and incendiary devices. Complete information on all types of ordnance used is not readily available. The site was known as the "Machine Gun Range" and contained a club house, a pistol range, a machine gun range and a Tommy gun range. The club house was a wood frame structure, with gypsum board siding that had lighting, water, and heat. The pistol range had a gravel and sand, oiled, rolled surface and contained targets and stands. The machine gun and Tommy gun ranges had the same surface as the pistol range, and had moving targets.**Waste Type:** Ordnance**Waste Description:** Lead bullets and spent cartridges are found throughout the area. Grenade canisters have also been found in the area.**Waste Type:** Asbestos (non-friable)**Waste Description:** The site contains transite piping remnants.**Waste Type:** Misc. Trash and Debris**Waste Description:** The site contains miscellaneous trash scattered about the site.**This Site has the Following SubSites:****Code:** 600-149:1**Names:** 600-149:1; Rifle and Pistol Range; Small Arms Range**Code:** 600-149:2**Names:** 600-149:2; Berm Behind the Pistol/Rifle Range**Code:** 600-149:1**Classification:** Accepted**Names:** 600-149:1; Rifle and Pistol Range; Small Arms Range**Reclassification:** Interim Closed Out (11/15/2011)**Type:** Military Compound**Start Date:****Status:** Inactive**End Date:****Description:** The Small Arms Range complex consisted of a Range House Building, Well Pump House, and four firing ranges. The entire complex was 381 meters (1,250 feet) by 555 meters (1,820 feet) and encompassed approximately 52 acres. It was surrounded on three sides by a barbed wire fence. Gable Mountain formed a natural access barrier on the fourth side. There were four specialized firing ranges: an Army pistol range, a Federal Bureau of Investigation "killer course" range (also known as the "special range"), a submachine gun range, and "walk and

draw" pistol range. The first two ranges were covered with a 5.1 centimeter (2-inch) thick bituminous road mix, and the latter two ranges were equipped with manually operated, moving targets. The Range House Building was located on the opposite side of the access road from the firing ranges. It contained a conference room, equipment storage room, office, rest room, and three brick chimneys for stove heating purposes. The small Well Pumphouse pit was constructed of reinforced concrete and contained a hatch in the roof for the maintenance of pumping equipment.

The waste site shape was modified on 2/2/2011 so that the western boundary followed the irrigation canal. This canal served as a natural boundary for activities associated with the small arms range and was more appropriate than the arbitrary rectangle that was drawn previously. The tract of land that was cut out of 600-149:1 has been reassigned to 600-349.

Location: The area is approximately 19 miles north of Richland, at the foot of the northeastern slope of Gable Mountain.

Related Sites/ Structures: The Small Arms Range is associated with 600-349.

Process Description: The complex operated from the mid 1940's through the 1950's to serve as a practice firing range for hand guns, rifles, machine guns, hand grenades and smoke bombs.

Closure Info: Interim (11/15/2011): The objective of the 600-149 Munitions or Explosives of Concern (MEC) investigation and clearance project was to perform a surface sweep, subsurface characterization to determine the nature and extent of metallic anomalies, and subsurface clearance of MEC and Material Suspected of Potentially Presenting and Explosive Hazard (MPPEH) hazards within limitations defined for the project (> mV reading). A preliminary survey of the area was conducted in March 2006 using visual inspection methods aided by a magnetometer. Phase II was performed in the spring of 2008, using electromagnetic devices for subsurface investigations. Many anomalies were 18 inches below the surface. This activity cleared 7.2 acres of property. Phase III, conducted in October and November 2010, included a surface sweep that cleared 47 acres. Culturally sensitive debris was staged separately.

A Digital Geographic Mapping (DGM) survey of a 100-ft by 100-ft grid was conducted on November 3, 2010. After analyzing the results and initial dig of selected anomalies in the grid, a threshold value of 5 mV was determined to be the appropriate threshold criteria for selecting anomaly dig targets. The second phase of the investigation conducted DGM surveys of each grid between November 4 and December 17, 2010. DGM was conducted for the purpose of locating geophysical anomalies in the subsurface that could potentially be MEC. Sixty one grids were identified as high density (HD), containing large numbers of anomalies.

Dig sheets were provided to the intrusive investigation teams for identification and/or removal. The sifting stage of anomaly investigation and clearance in HD grids commenced on January 17, 2011 and was completed on March 22, 2011. An area near the northeast corner of the Site was thought to be a munitions burial pit, based on unsubstantiated historical information. The dig team sifted soil from an area approximately 20 ft by 10 ft to an average depth of approximately 24 inches.

The SubSite is Part Of:

Code: 600-149

Names: 600-149; 600-54; 661 Complex; Rifle and Pistol Range; Small Arms Range

Code: 600-149:2

Classification: Accepted

Names: 600-149:2; Berm Behind the Pistol/Rifle Range

Reclassification Interim Closed Out (1/20/2009)

Type: Military Compound**Start Date:****Status:** Inactive**End Date:****Description:** The subsite has been evaluated and Interim Closed Out. It consisted of the soil berm behind the pistol/rifle range.**Location:** The berm is located north of the east end of Gable Mountain, west of Route 2, and northwest of the former Hanford town site.**Closure Info:** Interim: Remedial action at the waste site was performed in September 2008. As part of the remedial action, a portion of the surrounding area was evaluated for unexploded ordnance (UXO) by digital geophysical mapping (DGM) using an electromagnetic detection instrument with a geographical mapping system to obtain positioning data over an area of approximately 2.9 hectares (7.2 acres). This area included the boundary of the current remediation excavation, as well as the area to the northeast that was needed to support the site remediation.

Due to concerns that UXO may be present, the soil berm was visually inspected aided with subsurface metal detection prior to the onset of remedial action. Three UXO items were discovered at a depth of approximately 18 cm (0.5 ft) during this inspection. The items included a rifle grenade, a fuse from a smoke grenade, and a riot shell (smoke round). Approximately 1.0 meter (3 ft) of soil was removed from the face of the berm and 0.6 meter (2 ft) of soil from the base/toe of the berm. The resulting 826 bank cubic meters (1,080 bank cubic yards) of soil was disposed at the Environmental Restoration Disposal Facility (ERDF).

The berm soil removal was completed to the extent allowed by the Cultural Resource review. Excavation on the southwest side of the berm was limited so that the PRID canal would not be disturbed. Bullets remain in this portion of the berm. It was agreed that this portion of the berm would be excluded from the 600-149:2 waste site.

Due to concerns that additional UXO may be present in the soil berm, direct load-out of soil for shipment to the ERDF was not performed. The material removed from the berm was staged for inspection of additional UXO and then sent to ERDF.

The SubSite is Part Of:**Code:** 600-149**Names:** 600-149; 600-54; 661 Complex; Rifle and Pistol Range; Small Arms Range

Code: 600-178**Classification:** Accepted**Names:** 600-178; 213-J and 213-K Guard House Toilet Pit **Reclassification** Interim Closed Out (7/19/2011)**Type:** Depression/Pit (nonspecific)**Start Date:****Status:** Inactive**End Date:****Description:** The site has been remediated and Interim Closed Out. It was a toilet pit opening within a 4.3 by 4.9-meter (14 by 16-foot) concrete pad that remained from the demolished guard house. The opening in the concrete was connected to a sanitary sewage pit located beneath the pad. A lid to the septic pit is next to the concrete pad. No evidence of a sewage distribution system (septic tank or tile field) was apparent. No septic tank was found during remediation.**Location:** The site is located north of Route 11A and 150 meters (490 feet) south of the 213-J and 213-K Vaults parking lot.**Process** This unit received human sewage from a guard house.**Description:**

Waste Type: Sanitary Sewage

Waste Description: The waste was human sewage.

Closure Info: Interim: Remediation occurred at the 600-178 waste site on November 4 through 16, 2010. The concrete toilet system was removed entirely, along with a protruding pipe and sludgy material underlying the pipe. The concrete structure had dimensions of approximately 6 by 6 by 1.2 meters (20 by 20 by 4 ft). The excavated concrete, pipe, and associated soils were disposed at the Environmental Restoration Disposal Facility.

Due to the small size of the excavation, which included the waste staging pile area measuring 160 square meters (1,700 sq. ft.) and overburden footprint 100 square meters (1,075 sq. ft.), composite samples were collected, consisting of 25 aliquots of soil distributed across the surface of the sampling area. Two composite samples were collected over the footprint of the excavated area, one was collected at the waste staging pile area footprint, and one was collected over the overburden.

Code: 600-186

Classification: Accepted

Names: 600-186; Hanford Construction Camp Septic Tanks and Sewage Treatment Plants

Reclassification: Interim No Action (9/14/2011)

Type: Trench

Start Date: 1/1/1944

Status: Inactive

End Date:

Description: This site has been evaluated and determined to require No Action. The site includes all the septic tanks and sewage treatment plants at the Hanford Construction Camp. Five components of this site have been identified in the field and mapped.

Three former sewage treatment plant settling basins were identified from visual depressions or trenches. The northernmost site was the largest and deepest, beginning at a group of trees and extending to the river, cutting into the river bank. Small pieces of concrete, concrete pipe, vitrified clay pipe and wood were observed around the trench. The bottom of the trench has fine soil that did not appear to be sludge derived from sewage. The second trench, just south of the first trench was shallower and not as obvious. Small pieces of concrete were observed surrounding the trench. A layer of sludge like material was observed on the east side of the trench. The southernmost trench was obscured by tumbleweeds. The outline of a foundation was found on the north side of the most southern trench. One septic tank was found between this trench and the turn off to the Honey Dump site. A large area west of the sewage treatment plants was searched for septic tanks, but none were found.

Location: The sewage treatment plants were located on the river side of "A" Avenue between Fourth and Sixth Streets East and at Tenth Street East. Two of the treatment plants are located near the east end of 5th Street East. The southernmost treatment plant is located near the intersection of Tenth Street East and "A" Avenue, approximately 216 meters (709 feet) north of Well #A8744.

Related Sites/Structures: The site was related to the Hanford Construction Camp and the need for sanitary facilities. Septic tanks were scattered throughout the Camp Area at required locations for the retention of sewage. The septic tanks were related to waste treatment facilities where sewage was collected, treated and disposed.

Process Description: The Hanford Construction Camp was supported by a system of underground sanitary waste treatment facilities sufficient to support the 50,000 employees who lived there. These facilities consisted of 80 septic tanks and 3 waste treatment plants, in addition to an unspecified number of septic tanks and drain fields that predate the construction camp but were used for camp

purposes. DuPont (1945) describes three sewage treatment plants for the camp. Each included a system of septic tanks and a waste treatment facility, connected by 10.2 to 76.2-centimeter (4 to 30-inch) vitrified clay or concrete pipe. Septic tanks were "standard design, three pass baffle, wooden box type" varying in size from 1.2 by 4.9 by 1.8 meters up to 7.3 by 18.3 by 3.05 meters (4 by 16 by 6 feet up to 24 by 60 by 10 feet). Although these dimensions are confusing, it is clear that some tanks were quite large and that a significant potential for surface collapse may exist at these sites. The septic tanks were scattered throughout the Camp Area at required locations (DuPont 1945). At the beginning of Hanford Camp, wooden grease traps were provided to separate the grease from the main sewage going to the settling basins. Serious trouble resulted when the grease traps were inadequate both in size and design. Further steps to control the grease build-up at the settling basins had to be taken. Garbage from the mess hall kitchens was also a problem, so a device to collect both grease and garbage was required.

Waste Type: Sanitary Sewage

Waste Description: All sewage carried by the three sewage disposal systems was chlorinated.

Description:

Closure Info: Interim (9/14/2011): The results of the confirmatory sampling determined the waste site could be reclassified to No Action.

Code: 600-202

Classification: Accepted

Names: 600-202; Hanford Townsite Four Burn and Burial Pits

Reclassification: Interim Closed Out (5/25/2011)

Type: Burn Pit

Start Date:

Status: Inactive

End Date:

Description: The site has been remediated and Interim Closed Out. It included multiple burn and burial pits, located close together and arranged to form a single rectangle. The waste contains miscellaneous municipal trash. Bulldozer marks suggest that debris was covered. There was extensive signs of burning over the site.

Location: The site is located southeast of the Hanford Construction Camp, near the river bank. It is 550 meters (1805 feet) southeast of the intersection of Avenue A and 9th Street, in the Hanford Construction Camp. It was southeast of the southernmost sewage treatment plant (sitecode 600-186).

Process Description: The area was used as a municipal dump by the Hanford Cap construction crews.

Description:

Waste Type: Misc. Trash and Debris

Waste Description: The waste is miscellaneous trash and debris and includes such items as fire-cracked rock, glass, china, jars, bottles, metal, kitchen materials, broken toilet bowl, and other materials. Bulldozer marks suggest that debris has been covered. The pits vary in depth, apparently because of varying levels of backfill. There is the potential that paints and solvents were burned in the pits. The site needs further evaluation.

Closure Info: Interim: Test pits and trenches were dug in 2005 and 2009 to collect Confirmatory samples. Asphalt shingles, sheet rock, tar paper, glass, batteries, nails, wood and stained soil were observed.

Remediation occurred from March through May 2010. One large and one small area were excavated and a material staging area was created. White material was found that was later determined to be mussel shells. Cultural resources personnel were permanently staged at the

waste site for the remainder of the excavation to oversee the handling of shells. Several batteries were found during excavation. The batteries were drummed and a sample was collected on March 31, 2010 from random aliquots of soil beneath one of the batteries. A 132-L (35-gal) drum filled with dirt was removed and staged for disposal at the Environmental Restoration Disposal Facility (ERDF). On April 14, 2010, a 0.18-L (6-oz) bottle with a small amount of white liquid inside was found. The contents of the bottle were characterized for disposal. At the completion of all remedial activities, the depth of both excavations was approximately 4.8 meters (15.7 ft).

Code: 600-204 **Classification:** Accepted

Names: 600-204; Hanford Townsite Burn and Burial Trench **Reclassification:** Interim Closed Out (9/16/2003)

Type: Burn Pit **Start Date:**

Status: Inactive **End Date:**

Description: The site has been remediated and Interim Closed Out. The site was a long, narrow trench that was used as a burn pit. The trench was oriented north to south.

Location: The site was located approximately 500 meters (1,641 feet) southwest of the intersection of Route 1 and Route 2 North and approximately 200 meters (656 feet) west of the United States Government Railroad.

Process Description: The area was used for dumping and burning trash.

Waste Type: Misc. Trash and Debris

Waste Description: The trash was miscellaneous debris, including metal and glass fragments, nails, fire-scarred rock, cans, and bottles. The waste has been placed in a discernible unit.

Closure Info: Interim: In April 2003, a field walkdown was conducted to finalize contaminants of potential concern, identify sample locations, and identify sample types for development of a sampling design. A remedial action activity was implemented to remove contaminated soil and debris from the site for disposal at the Environmental Restoration Disposal Facility. The material was removed to a depth of 25 centimeters (10 inches).

Code: 600-205 **Classification:** Accepted

Names: 600-205; Hanford Townsite Landfill 2 **Reclassification:** Interim Closed Out (5/25/2011)

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The site has been remediated and Interim Closed Out. It was a large area that was used for pre-Hanford dumping of domestic refuse and also Camp Hanford dumping. Historical photographs show several nearby buildings that appear to be vehicle maintenance facilities. Surface debris was evident and GPR scans identified subsurface anomalies.

Location: The site is located southeast of the intersection of Route 2 North and Route 11A. The area is relatively flat and appears to have been mechanically leveled with scattered domestic and building material.

Related Sites/Structures: The site is related to 600-110 Hanford Townsite Landfill 1.

Waste Type: Misc. Trash and Debris

Waste Description: The waste is domestic debris, including heavy concentrations of tin cans, bottles, auto parts, and other domestic refuse. Bulldozing marks are evident, and it appears that landfill debris has been covered over and that additional concentrations may exist below grade.

Closure Info: Interim: Confirmatory sampling was done in January 2005. A test trench dug to a depth of 3.7 meters (12 feet) into Area 1 found no debris. One soil sample was collected. A test trench dug to a depth of 1.5 meters (5 feet) into Area 2 found no debris. One soil sample was collected. A test trench dug to a depth of 0.9 meters (3 feet) into Area 3 found no debris. One soil sample was collected. A test trench dug to a depth of 1.5 meters (5 feet) into Area 4 found no debris. No soil sample was collected. A test trench dug to a depth of 1.5 meters (5 feet) into Area 5 found no debris. No soil sample was collected. A test trench dug to a depth of 1.5 meters (5 feet) into Area 6 found no debris. One soil sample was collected. A test trench dug to a depth of 1.5 meters (5 feet) into Area 7 found no debris. One soil sample was collected.

Remediation occurred at Area 2 from February 24 to March 2, 2010. The excavated area was approximately 115 square meters (1,240 sq. ft.). The waste was staged to the southwest of the excavation, and had an area of approximately 80 square meters (860 sq. ft.). On March 15, 2010, one in-process sample, J19V17, was collected from the bottom of the waste site and the sidewalls of the excavation.

The battery and surrounding soil found in Area 1 was drummed on May 17, 2010. Per regulatory agreement, no sample was collected from this location.

The final depth of the excavation was approximately 4 meters (13 ft) deep and the staging pile area was 1 meter (3 ft) deep, resulting in 512 bank cubic meters (BCM) [670 bank cubic yards (BCY)] of soil that was loaded out to the Environmental Restoration Disposal Facility.

Code: 600-208

Classification: Accepted

Names: 600-208; Hanford Construction Camp Boiler House Ponds

Reclassification: Interim No Action (8/12/2004)

Type: Pond

Start Date:

Status: Inactive

End Date:

Description: The waste site has been evaluated and determined to require No Action. 600-208 represents a series of liquid disposal ponds or trenches associated with the Hanford Construction Camp steam generating plants. The ponds were estimated to be roughly 6 meters (20 feet) by 20 meters (60 feet) and 1.5 meters (5 feet) deep.

Location: The sites were found within or close to the Hanford Construction Camp. The locations of thirteen of the eighteen ponds have been identified using photos of the camp. The ponds are located as follows: (1) between 1st and 2nd Street and east of Avenue A; (2) between 2nd Street and 3rd Street and east of Avenue A; (3) between 3rd Street and 4th Street and east of Avenue A; (4) between 4th Street and 5th Street and east of Avenue A; (5) at 6th Street and east of Avenue A; (6) between 7th Street and 8th Street and east of Avenue A; (7) east of 9th Street and northeast of the intersection of 9th Street and Avenue B; (8) approximately 250 meters (820 feet) northeast of the intersection of 7th Street and Avenue E; (9) between 5th Street and 6th Street and north of Avenue C; (10) between E Avenue and D Avenue and north of 4th Street; (11) between 3rd Street and 4th Street and south of Avenue C; (12) between 2nd Street and 3rd Street and south of Avenue C, close to the intersection of 3rd Street and Avenue C; (13) approximately 250 meters (820 feet) south of the intersection of Route 2 North and Doolittle Avenue on the east side of Route 2 North.

Process Description: Eighteen boiler houses were used at the Hanford Construction Camp to generate steam. Each boiler house was described as "100 boiler horse power, hand fired, horizontal return tubular boilers, (arranged) either singly or in batteries". Each site had from one to eight boilers. Each had a wood-stave soft water storage tank and an open-boxed pit for the sluicing and removal of ashes by means of clamshell crane. Some had liquid waste disposal ponds. The ponds were designed to receive wastewater and chemicals used for the boiler houses (steam or power plants) at the Hanford Townsite Construction Camp. The steam produced was primarily for heating purposes. The ponds or trenches, referred to as Liquid Seep Ponds, were believed to have existed at each fixed steam plant (boiler house) and to have received waste common to the boilers.

Waste Type: Water

Waste Description: The waste was waste water and chemicals. The chemical released most frequently to the ponds would have been "water softener brine". There are no obvious signs of contamination.

Closure Info: Interim: Geophysical surveys were done in January and February 2004. Site walkdowns were done in May and June 2004.

The No Action decision is based on historical and field observations. No hazardous chemicals were used in the steam generation process.

Code: 600-239

Classification: Accepted

Names: 600-239; 615 Hot Mix Plant Debris; Debris in Pit 16; Hanford Aggregate Pit Debris

Reclassification: Interim No Action (5/31/2001)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site has been evaluated and determined to require No Action. The non-contaminated debris was removed to ERDF in April 2012. It included several large wooden beams, wooden pallets, large diameter steel pipe, steel plates, large mesh steel screens and rubber tires. All wastes observed were lying in neat piles on the ground surface within Pit #16. None of the debris appeared to be partially buried. One stacked pile of metal posts had some radiation warning signs still attached. There was a spot of old paint, about one square foot, in the pit.

Location: The site is located approximately 200 meters (656.2 feet) west of Route 2 North and approximately 1.3 kilometers (0.8 miles) north of Route 11A. The approach to the site is marked with signs on the west side of Route 2 North just south of milepost 1.

Related Sites/Structures: Site 600-240 is similar debris in adjacent Pit 17. 600-20 is the Hot Mix Plant and is the source of much of the debris in both the 600-230 and 600-240 sites.

Process Description: This gravel pit was related to the adjacent Hot Mix Plant (600-20, reclassified as Rejected). However, some of the stored materials in the Pit may have come from other projects.

Waste Type: Misc. Trash and Debris

Waste Description: The waste is wood, metal and rubber.

Closure Info: Interim: The debris was considered Miscellaneous Restoration debris. Debris removal was completed in April, 2012. A total of seven ERDF containers (44.12 US tons) were removed and disposed of to ERDF.

Code: 600-280

Classification: Accepted

Waste Description: Contaminants of potential concern include TPH, PAH, PCBs and ICP metals.

Closure Info: Interim (10/17/2012): Remediation of the combined 100-IU-2/6 debris and burn area waste sites occurred between August 10, 2011 and May 29, 2012. The activity resulted in a total of approximately 523 bank cubic meters (BCM) (682 bank cubic yards [BCY]) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility (ERDF).

Based on observations during the field walkdowns to support remedial action, it was determined that the 600-305, 600-308, 600-309, 600-310, 600-311, 600-312, 600-313, 600-314, 600-317, 600-319, and 600-324 waste sites required remediation. The 600-314 subsites required removal of only telecommunication equipment on the ground surface with no excavation.

Remediation of the 600-305:1 and 600-305:2 subsites occurred on April 4, 2012. The soil within these subsites was excavated to a depth of approximately 0.3 meters (1 ft) below ground surface (bgs). No excavation occurred at the 600-305:3 waste site since surface removal of a pipe was the only scope. The remediation of the 600-305:4 subsite occurred on May 14, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs. The remediation of the 600-305:5 subsite occurred on May 15, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs.

The remediation of the 600-308 waste site occurred on May 29, 2012. The soil within this waste site was excavated to a depth of approximately 0.6 meters (2 ft) bgs.

The remediation of the 600-309 waste site occurred on May 23 and 24, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-310 waste site occurred on May 22 and 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-311 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-312 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-313 waste site occurred on May 16, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

For the five 600-314 subsites, only component item removal was required, since only telecommunications components were lying on the surface with no stained or additional anomalous material. Component removal at the 600-314 subsites occurred on May 1, 4, and 14, 2012. All the components were disposed of at ERDF.

The remediation of the 600-317 waste site occurred on May 21 and 22, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-319:1 subsite occurred on May 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:2 subsite occurred on May 4, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:3 subsite occurred on August 10, 2011. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-324 waste site occurred between April 26 and 30, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

A post-excavation global positioning survey (GPS) walk-around for the excavated waste sites was performed following excavation. Excavated material from all subsites and waste sites was direct loaded for disposal to ERDF, and no soil staging pile area or overburden areas were utilized.

Code: 600-314	Classification: Accepted
Names: 600-314; Telecommunication Components	Reclassification: Interim Closed Out (10/17/2012)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The five subsites have been remediated and Interim Closed Out. Therefore, the parent site is also considered Interim Closed Out. The five areas (subsites) were evaluated in the same document and Interim Closed Out on a single Reclassification form. The site consisted of scattered debris and the underlying soils at five locations where probable telecommunications components were on the surface. The five areas were separated into subsites. The material components had hardened black liquid on the outside surface and leaking out of them.

Location: The coordinates for the five areas included in this waste site were:

Area 1, E580364.1, N145210.4
 Area 2, E580620.6, N144976.8
 Area 3, E581229.8, N143485.8
 Area 4, E581233.1, N143389.9
 Area 5, E582771.6, N140100.2

Process Description: These components appeared to be junctions or splice boxes for telecommunication cables.

Waste Type: Equipment

Waste Description: The waste may be abandoned telecommunications equipment. The components may contain PCB from possible oil inside, suspect asbestos in outer asphaltic covering and possible lead in soldered joints.

Closure Info: Interim (10/17/2012): Remediation of the combined 100-IU-2/6 debris and burn area waste sites occurred between August 10, 2011 and May 29, 2012. The activity resulted in a total of approximately 523 bank cubic meters (BCM) (682 bank cubic yards [BCY]) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility (ERDF).

Based on observations during the field walkdowns to support remedial action, it was determined that the 600-305, 600-308, 600-309, 600-310, 600-311, 600-312, 600-313, 600-314, 600-317, 600-319, and 600-324 waste sites required remediation. The 600-314 subsites required removal of only telecommunication equipment on the ground surface with no excavation.

Remediation of the 600-305:1 and 600-305:2 subsites occurred on April 4, 2012. The soil within these subsites was excavated to a depth of approximately 0.3 meters (1 ft) below ground surface (bgs). No excavation occurred at the 600-305:3 waste site since surface removal of a pipe was the only scope. The remediation of the 600-305:4 subsite occurred on May 14, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs. The remediation of the 600-305:5 subsite occurred on May 15, 2012. The soil within this

subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs.

The remediation of the 600-308 waste site occurred on May 29, 2012. The soil within this waste site was excavated to a depth of approximately 0.6 meters (2 ft) bgs.

The remediation of the 600-309 waste site occurred on May 23 and 24, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-310 waste site occurred on May 22 and 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-311 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-312 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-313 waste site occurred on May 16, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

For the five 600-314 subsites, only component item removal was required, since only telecommunications components were lying on the surface with no stained or additional anomalous material. Component removal at the 600-314 subsites occurred on May 1, 4, and 14, 2012. All the components were disposed of at ERDF.

The remediation of the 600-317 waste site occurred on May 21 and 22, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-319:1 subsite occurred on May 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:2 subsite occurred on May 4, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:3 subsite occurred on August 10, 2011. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-324 waste site occurred between April 26 and 30, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

A post-excavation global positioning survey (GPS) walk-around for the excavated waste sites was performed following excavation. Excavated material from all subsites and waste sites was direct loaded for disposal to ERDF, and no soil staging pile area or overburden areas were utilized.

This Site has the Following SubSites:

Code: 600-314:1

Names: 600-314:1; Telecommunications Component Area 1

Code: 600-314:2

Names: 600-314:2; Telecommunications Component Area 2

Code: 600-314:3

Names: 600-314:3; Telecommunications Component Area 3

Code: 600-314:4

Names: 600-314:4; Telecommunications Component Area 4

For the five 600-314 subsites, only component item removal was required, since only telecommunications components were lying on the surface with no stained or additional anomalous material. Component removal at the 600-314 subsites occurred on May 1, 4, and 14, 2012. All the components were disposed of at ERDF.

The remediation of the 600-317 waste site occurred on May 21 and 22, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-319:1 subsite occurred on May 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:2 subsite occurred on May 4, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:3 subsite occurred on August 10, 2011. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-324 waste site occurred between April 26 and 30, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

A post-excavation global positioning survey (GPS) walk-around for the excavated waste sites was performed following excavation. Excavated material from all subsites and waste sites was direct loaded for disposal to ERDF, and no soil staging pile area or overburden areas were utilized.

The SubSite is Part Of:

Code: 600-314

Names: 600-314; Telecommunication Components

Code: 600-314:2

Classification: Accepted

Names: 600-314:2; Telecommunications Component Area 2

Reclassification: Interim Closed Out (10/17/2012)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. The subsite was a probable telecommunications junction or splice box that has hardened black liquid (possibly tar) on the outside surface. The suspect telephone communication components measure 40.6 cm by 22.9 cm (16 by 9 in) in diameter.

Location: The site was located approximately 25 meters (82 ft) west of F Avenue and 53 meters (174 ft) north of Route 2 North.

Closure Info: Interim (10/17/2012): Remediation of the combined 100-IU-2/6 debris and burn area waste sites occurred between August 10, 2011 and May 29, 2012. The activity resulted in a total of approximately 523 bank cubic meters (BCM) (682 bank cubic yards [BCY]) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility (ERDF).

Based on observations during the field walkdowns to support remedial action, it was determined that the 600-305, 600-308, 600-309, 600-310, 600-311, 600-312, 600-313, 600-314, 600-317, 600-319, and 600-324 waste sites required remediation. The 600-314 subsites required removal of only telecommunication equipment on the ground surface with no excavation.

Remediation of the 600-305:1 and 600-305:2 subsites occurred on April 4, 2012. The soil within these subsites was excavated to a depth of approximately 0.3 meters (1 ft) below ground surface (bgs). No excavation occurred at the 600-305:3 waste site since surface removal of a pipe was the only scope. The remediation of the 600-305:4 subsite occurred on May 14, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs. The remediation of the 600-305:5 subsite occurred on May 15, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs.

The remediation of the 600-308 waste site occurred on May 29, 2012. The soil within this waste site was excavated to a depth of approximately 0.6 meters (2 ft) bgs.

The remediation of the 600-309 waste site occurred on May 23 and 24, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-310 waste site occurred on May 22 and 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-311 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-312 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-313 waste site occurred on May 16, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

For the five 600-314 subsites, only component item removal was required, since only telecommunications components were lying on the surface with no stained or additional anomalous material. Component removal at the 600-314 subsites occurred on May 1, 4, and 14, 2012. All the components were disposed of at ERDF.

The remediation of the 600-317 waste site occurred on May 21 and 22, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-319:1 subsite occurred on May 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:2 subsite occurred on May 4, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:3 subsite occurred on August 10, 2011. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-324 waste site occurred between April 26 and 30, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

A post-excavation global positioning survey (GPS) walk-around for the excavated waste sites was performed following excavation. Excavated material from all subsites and waste sites was direct loaded for disposal to ERDF, and no soil staging pile area or overburden areas were utilized.

The SubSite is Part Of:

Code: 600-314

Names: 600-314; Telecommunication Components

Code: 600-314:3

Classification: Accepted

Names: 600-314:3; Telecommunications Component Area 3 **Reclassification** Interim Closed Out (10/17/2012)

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The subsite has been remediated and Interim Closed Out. It was a probable telecommunications junction or splice box that had hardened black liquid (possibly tar) on the outside surface. The suspect telephone communication components measure 40.6 cm by 22.9 cm (16 by 9 in) in diameter.

Location: The site was located approximately 868 meters (0.5 miles) west of Route 2 North and 4.7 kilometers (2.9 miles) north of Route 11A.

Closure Info: Interim (10/17/2012): Remediation of the combined 100-IU-2/6 debris and burn area waste sites occurred between August 10, 2011 and May 29, 2012. The activity resulted in a total of approximately 523 bank cubic meters (BCM) (682 bank cubic yards [BCY]) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility (ERDF).

Based on observations during the field walkdowns to support remedial action, it was determined that the 600-305, 600-308, 600-309, 600-310, 600-311, 600-312, 600-313, 600-314, 600-317, 600-319, and 600-324 waste sites required remediation. The 600-314 subsites required removal of only telecommunication equipment on the ground surface with no excavation.

Remediation of the 600-305:1 and 600-305:2 subsites occurred on April 4, 2012. The soil within these subsites was excavated to a depth of approximately 0.3 meters (1 ft) below ground surface (bgs). No excavation occurred at the 600-305:3 waste site since surface removal of a pipe was the only scope. The remediation of the 600-305:4 subsite occurred on May 14, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs. The remediation of the 600-305:5 subsite occurred on May 15, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs.

The remediation of the 600-308 waste site occurred on May 29, 2012. The soil within this waste site was excavated to a depth of approximately 0.6 meters (2 ft) bgs.

The remediation of the 600-309 waste site occurred on May 23 and 24, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-310 waste site occurred on May 22 and 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-311 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-312 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-313 waste site occurred on May 16, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

For the five 600-314 subsites, only component item removal was required, since only telecommunications components were lying on the surface with no stained or additional anomalous material. Component removal at the 600-314 subsites occurred on May 1, 4, and 14, 2012. All the components were disposed of at ERDF.

The remediation of the 600-317 waste site occurred on May 21 and 22, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-319:1 subsite occurred on May 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:2 subsite occurred on May 4, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:3 subsite occurred on August 10, 2011. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-324 waste site occurred between April 26 and 30, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

A post-excavation global positioning survey (GPS) walk-around for the excavated waste sites was performed following excavation. Excavated material from all subsites and waste sites was direct loaded for disposal to ERDF, and no soil staging pile area or overburden areas were utilized.

The SubSite is Part Of:

Code: 600-314

Names: 600-314; Telecommunication Components

Code: 600-314:4

Classification: Accepted

Names: 600-314:4; Telecommunications Component Area 4

Reclassification: Interim Closed Out (10/17/2012)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. It was a probable telecommunications junction or splice box that has hardened black liquid (possibly tar) on the outside surface. The suspect telephone communication components measure 40.6 cm by 22.9 cm (16 by 9 in) in diameter.

Location: The site was located approximately 955 meters (0.6 miles) west of Route 2 North and 4.6 kilometers (2.9 miles) north of Route 11A.

Closure Info: Interim (10/17/2012): Remediation of the combined 100-IU-2/6 debris and burn area waste sites occurred between August 10, 2011 and May 29, 2012. The activity resulted in a total of approximately 523 bank cubic meters (BCM) (682 bank cubic yards [BCY]) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility (ERDF).

Based on observations during the field walkdowns to support remedial action, it was determined that the 600-305, 600-308, 600-309, 600-310, 600-311, 600-312, 600-313, 600-314, 600-317, 600-319, and 600-324 waste sites required remediation. The 600-314 subsites required removal of only telecommunication equipment on the ground surface with no excavation.

Remediation of the 600-305:1 and 600-305:2 subsites occurred on April 4, 2012. The soil within these subsites was excavated to a depth of approximately 0.3 meters (1 ft) below ground surface (bgs). No excavation occurred at the 600-305:3 waste site since surface removal of a pipe was the only scope. The remediation of the 600-305:4 subsite occurred on May 14, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs.

The remediation of the 600-305:5 subsite occurred on May 15, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs.

The remediation of the 600-308 waste site occurred on May 29, 2012. The soil within this waste site was excavated to a depth of approximately 0.6 meters (2 ft) bgs.

The remediation of the 600-309 waste site occurred on May 23 and 24, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-310 waste site occurred on May 22 and 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-311 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-312 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-313 waste site occurred on May 16, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

For the five 600-314 subsites, only component item removal was required, since only telecommunications components were lying on the surface with no stained or additional anomalous material. Component removal at the 600-314 subsites occurred on May 1, 4, and 14, 2012. All the components were disposed of at ERDF.

The remediation of the 600-317 waste site occurred on May 21 and 22, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-319:1 subsite occurred on May 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:2 subsite occurred on May 4, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:3 subsite occurred on August 10, 2011. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-324 waste site occurred between April 26 and 30, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

A post-excavation global positioning survey (GPS) walk-around for the excavated waste sites was performed following excavation. Excavated material from all subsites and waste sites was direct loaded for disposal to ERDF, and no soil staging pile area or overburden areas were utilized.

The SubSite is Part Of:

Code: 600-314

Names: 600-314; Telecommunication Components

Code: 600-314:5

Classification: Accepted

Names: 600-314:5; Telecommunications Component Area 5

Reclassification Interim Closed Out (10/17/2012)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. It was a probable telecommunications junction or splice box that has hardened black liquid (possibly tar) on the outside surface. The suspect telephone communication components measured 40.6 cm by 22.9 cm (16 by 9 in) in diameter.

Location: The site was located approximately 1.6 kilometers (1.0 miles) west of Route 2 North and 1.3 kilometers (0.8 miles) north of Route 11A.

Closure Info: Interim (10/17/2012): Remediation of the combined 100-IU-2/6 debris and burn area waste sites occurred between August 10, 2011 and May 29, 2012. The activity resulted in a total of approximately 523 bank cubic meters (BCM) (682 bank cubic yards [BCY]) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility (ERDF).

Based on observations during the field walkdowns to support remedial action, it was determined that the 600-305, 600-308, 600-309, 600-310, 600-311, 600-312, 600-313, 600-314, 600-317, 600-319, and 600-324 waste sites required remediation. The 600-314 subsites required removal of only telecommunication equipment on the ground surface with no excavation.

Remediation of the 600-305:1 and 600-305:2 subsites occurred on April 4, 2012. The soil within these subsites was excavated to a depth of approximately 0.3 meters (1 ft) below ground surface (bgs). No excavation occurred at the 600-305:3 waste site since surface removal of a pipe was the only scope. The remediation of the 600-305:4 subsite occurred on May 14, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs. The remediation of the 600-305:5 subsite occurred on May 15, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs.

The remediation of the 600-308 waste site occurred on May 29, 2012. The soil within this waste site was excavated to a depth of approximately 0.6 meters (2 ft) bgs.

The remediation of the 600-309 waste site occurred on May 23 and 24, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-310 waste site occurred on May 22 and 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-311 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-312 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-313 waste site occurred on May 16, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

For the five 600-314 subsites, only component item removal was required, since only telecommunications components were lying on the surface with no stained or additional anomalous material. Component removal at the 600-314 subsites occurred on May 1, 4, and 14, 2012. All the components were disposed of at ERDF.

The remediation of the 600-317 waste site occurred on May 21 and 22, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-319:1 subsite occurred on May 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-

319:2 subsite occurred on May 4, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:3 subsite occurred on August 10, 2011. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-324 waste site occurred between April 26 and 30, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

A post-excavation global positioning survey (GPS) walk-around for the excavated waste sites was performed following excavation. Excavated material from all subsites and waste sites was direct loaded for disposal to ERDF, and no soil staging pile area or overburden areas were utilized.

The SubSite is Part Of:

Code: 600-314

Names: 600-314; Telecommunication Components

Code: 600-315

Classification: Accepted

Names: 600-315; Black Granular Stain

Reclassification Interim No Action (5/25/2011)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The site has been evaluated and determined to require No Action. It consists of soil associated with a black granular material visible on the surface. There is very little vegetation in the affected area. Confirmatory sampling done in 2010 determined the material was coal ash.

Location: The site is located approximately 487.02 meters (0.3 miles) north and 31.21 meters (102 feet) east of the intersection of F Avenue and Route 2.

Closure Info: Interim: During a site visit in March 2010, it was determined that the black granular material did not appear to be petroleum based, as it was previously suggested. Rather, the black granular material appeared to resemble graphite. However, during confirmatory sampling in November 2010, the material was determined to be coal ash. Based on sampling data, Hanford coal ash is not regulated as a dangerous waste.

Based on confirmatory sampling at the 600-315 waste site, remedial action was determined to be unnecessary, and the confirmatory sampling data has been used to document this waste site for reclassification as a No Action site.

Code: 600-317

Classification: Accepted

Names: 600-317; Battery and Burn Area

Reclassification Interim Closed Out (10/17/2012)

Type: Burn Pit

Start Date:

Status: Inactive

End Date:

Description: The waste site has been remediated and Interim Closed Out. The site was described as scattered surface debris consisting of wet cell battery plates, burned material, and a white granular substance. It was located in the bottom of a borrow pit.

Location: The site was located approximately 342.15 meters (0.2 miles) south and 459.72 meters (0.3 miles) west of the intersection of F Avenue and Route 2. The coordinates for the site are E580184.90/N144555.27.

Waste Type: Batteries

Waste Description: Lead and sulfuric acid from the batteries may be present.

Closure Info: Interim (10/17/2012): Remediation of the combined 100-IU-2/6 debris and burn area waste sites occurred between August 10, 2011 and May 29, 2012. The activity resulted in a total of approximately 523 bank cubic meters (BCM) (682 bank cubic yards [BCY]) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility (ERDF).

Based on observations during the field walkdowns to support remedial action, it was determined that the 600-305, 600-308, 600-309, 600-310, 600-311, 600-312, 600-313, 600-314, 600-317, 600-319, and 600-324 waste sites required remediation. The 600-314 subsites required removal of only telecommunication equipment on the ground surface with no excavation.

Remediation of the 600-305:1 and 600-305:2 subsites occurred on April 4, 2012. The soil within these subsites was excavated to a depth of approximately 0.3 meters (1 ft) below ground surface (bgs). No excavation occurred at the 600-305:3 waste site since surface removal of a pipe was the only scope. The remediation of the 600-305:4 subsite occurred on May 14, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs. The remediation of the 600-305:5 subsite occurred on May 15, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs.

The remediation of the 600-308 waste site occurred on May 29, 2012. The soil within this waste site was excavated to a depth of approximately 0.6 meters (2 ft) bgs.

The remediation of the 600-309 waste site occurred on May 23 and 24, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-310 waste site occurred on May 22 and 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-311 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-312 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-313 waste site occurred on May 16, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

For the five 600-314 subsites, only component item removal was required, since only telecommunications components were lying on the surface with no stained or additional anomalous material. Component removal at the 600-314 subsites occurred on May 1, 4, and 14, 2012. All the components were disposed of at ERDF.

The remediation of the 600-317 waste site occurred on May 21 and 22, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-319:1 subsite occurred on May 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:2 subsite occurred on May 4, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:3 subsite occurred on August 10, 2011. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-324 waste site occurred between April 26 and 30, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

A post-excavation global positioning survey (GPS) walk-around for the excavated waste sites was performed following excavation. Excavated material from all subsites and waste sites was direct loaded for disposal to ERDF, and no soil staging pile area or overburden areas were utilized.

Code: 600-318	Classification: Accepted
Names: 600-318; Wet Cell Batteries	Reclassification: Final Closed Out (10/28/2015)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The waste site and subsites have been remediated, Interim Closed Out and later Final Closed Out. It was described as five areas with wet cell battery debris lying on the ground surface near Route 2 North. The five areas (subsites) were evaluated in the same document and Interim Closed Out on a single Reclassification form.

Area 1 consisted a 3 meter (10 feet) diameter area of wet cell battery debris.

Area 2 consisted of a 3 meter (10 feet) diameter area of wet cell battery debris. It appears to have been car battery.

Area 3 consisted of lead battery debris in an area less than 1 meter (3 feet) in diameter next to a 4 meter by 15 meter (13 by 50 feet) concrete slab. There was also a 3.8 centimeter (1.5 inch) iron pipe and automotive debris present.

Area 4 consisted of lead battery debris in area less than 1 meter (3 feet) in diameter.

Area 5 consisted of a 4 meter by 8 meter (13 by 26 feet) automotive shop dump area with lead battery debris.

Location: The coordinate locations for the five areas (subsites) are:

Area 1 - E580204.7/N144950.3

Area 2 - E580765.7/N144702.4

Area 3 - E584263.8/N140330.5

Area 4 - E584421.9/N139110.4

Area 5 - E584684.6/N138951.9

Waste Type: Batteries

Waste Description: There may be lead and battery acid present at the sites.

Closure Info: Interim (8/7/2013): (Interim Closed Out) Site visits and geophysical surveys were done in June and November 2011. The results determined that remediation was required. Remediation activities began in July 2011 and continued through February 2013.

The waste site boundaries were re-defined during the remediation process. The excavation extent removed all the debris associated with the battery waste sites.

No anomalous material or stained soil was discovered during remediation activities of either the

600-316 or 600-318 waste sites. All material was direct loaded for disposal to the Environmental Restoration and Disposal Facility (ERDF).

The areas (subsites) were evaluated in the same document and Interim Closed Out on a single Reclassification form.

Final (10/28/2015): (Final Closed Out) Based upon evaluation of the previous reclassification data against the 100-F/IU Area ROD cleanup levels, no further RTD is required for any of the 26 waste sites (Listed below).

600-279, Vegetation-Free Area Between White Bluffs and 100-F
 600-293, White Bluffs Service Station #1
 600-294, White Bluffs Service Station #2
 600-298, Stained Soil and Surface Debris
 600-299, Surface Debris/Batteries
 600-300, Miscellaneous Surface Debris
 600-301, White Bluffs Sanitary Sewer Pipelines
 600-303, Vertical Pipes
 600-316, Dry Cell Batteries
 600-318, Wet Cell Batteries
 600-320, Oil Stains
 600-321, Suspect ACM Sites
 600-328, Lead Slag
 600-356, Tar Deposit West of Susie Junction
 600-368, Segment 4 Stained Soil #1
 600-369, Segment 4 Bare Ground and Crusted Soil Areas
 600-370, Segment 4 Debris Area #1
 600-371, Segment 4 Chalky Material Area
 600-372, Segment 4 Oil Stain and Filter Area #1
 600-373, Segment 4 Bare Ground and White Stain Area
 600-374, Segment 4 Drum Remnant Area
 600-375, Segment 4 Dry Cell Battery Debris Area #1
 600-376, Segment 4 Stained Soil Area #2
 600-377, Segment 4 Oil Stain and Filter Area #2
 600-378, 506 Telephone Exchange Emergency Generator Building Underground Fuel Storage tank
 600-379, Segment 4 Burn Area #1.

The Reclassification to Final Closed Out applies to all subsites associated with the waste sites listed above.

This Site has the Following SubSites:

Code: 600-318:1

Names: 600-318:1; Wet Cell Bateriaes in Area 1

Code: 600-318:2

Names: 600-318:2; Wet Cell Batteries in Area 2

Code: 600-318:3

Names: 600-318:3; Wet cell Batteries in Area 3

Code: 600-318:4

Names: 600-318:4; Wet cell Batteries in Area 4

Code: 600-318:5
Names: 600-318:5; Wet cell Batteries in Area 5

Code: 600-318:1 **Classification:** Accepted
Names: 600-318:1; Wet Cell Bateries in Area 1 **Reclassification** Final Closed Out (10/28/2015)
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The waste site consisted of a 3 meter (10 feet) diameter area of wet cell battery debris.
Location: The site was located approximately 351 meters (0.2 miles) south of Route 1 and 385 meters (0.2 miles) west of Route 2 North. Area 1 was located at E580204.7/N144950.3.

Closure Info: Interim (8/7/2013): (Interim Closed Out) Site visits and geophysical surveys were done in June and November 2011. The results determined that remediation was required. Remediation activities began in July 2011 and continued through February 2013.

The waste site boundaries were re-defined during the remediation process. The excavation extent removed all the debris associated with the battery waste sites.

No anomalous material or stained soil was discovered during remediation activities of either the 600-316 or 600-318 waste sites. All material was direct loaded for disposal to the Environmental Restoration and Disposal Facility (ERDF).

The areas (subsites) were evaluated in the same document and Interim Closed Out on a single Reclassification form.

The SubSite is Part Of:

Code: 600-318
Names: 600-318; Wet Cell Batteries

Code: 600-318:2 **Classification:** Accepted
Names: 600-318:2; Wet Cell Batteries in Area 2 **Reclassification** Final Closed Out (10/28/2015)
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The site consisted of a 3 meter (10 feet) diameter area of wet cell battery debris. It appeared to have been a car battery.

Location: The site was located approximately 78 meters (256 ft) south of Route 2 North and 181 meters (594 feet) southeast of the intersection of F Avenue and Route 2 North. Area 2 was located at E580765.7/N144702.4.

Closure Info: Interim (8/7/2013): (Interim Closed Out) Site visits and geophysical surveys were done in June and November 2011. The results determined that remediation was required. Remediation activities began in July 2011 and continued through February 2013.

The waste site boundaries were re-defined during the remediation process. The excavation extent removed all the debris associated with the battery waste sites.

No anomalous material or stained soil was discovered during remediation activities of either the 600-316 or 600-318 waste sites. All material was direct loaded for disposal to the

Environmental Restoration and Disposal Facility (ERDF).

The areas (subsites) were evaluated in the same document and Interim Closed Out on a single Reclassification form.

The SubSite is Part Of:

Code: 600-318

Names: 600-318; Wet Cell Batteries

Code: 600-318:3

Classification: Accepted

Names: 600-318:3; Wet cell Batteries in Area 3

Reclassification Final Closed Out (10/28/2015)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site consisted of lead battery debris in an area less than 1 meter (3 feet) in diameter, next to a 4 meter by 15 meter (13 by 50 feet) concrete slab. There was also a 3.8 centimeter (1.5 inch) iron pipe and automotive debris present.

Location: The site was located approximately 83 meters (266 feet) west of Route 2 North and 1.5 km (0.9 miles) north of Route 11A. Area 3 was at E584263.8/N140330.5.

Closure Info: Interim (8/7/2013): (Interim Closed Out) Site visits and geophysical surveys were done in June and November 2011. The results determined that remediation was required. Remediation activities began in July 2011 and continued through February 2013.

The waste site boundaries were re-defined during the remediation process. The excavation extent removed all the debris associated with the battery waste sites.

No anomalous material or stained soil was discovered during remediation activities of either the 600-316 or 600-318 waste sites. All material was direct loaded for disposal to the Environmental Restoration and Disposal Facility (ERDF).

The areas (subsites) were evaluated in the same document and Interim Closed Out on a single Reclassification form.

The SubSite is Part Of:

Code: 600-318

Names: 600-318; Wet Cell Batteries

Code: 600-318:4

Classification: Accepted

Names: 600-318:4; Wet cell Batteries in Area 4

Reclassification Final Closed Out (10/28/2015)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site consisted of lead battery debris in area less than 1 meter (3 feet) in diameter.

Location: The site was located approximately 49 meters (161 feet) east of Route 2 North and 290 meters (951 feet) north of Route 11A. Area 4 was at E584421.9/N139110.4.

Closure Info: Interim (8/7/2013): (Interim Closed Out) Site visits and geophysical surveys were done in June and November 2011. The results determined that remediation was required. Remediation

activities began in July 2011 and continued through February 2013.

The waste site boundaries were re-defined during the remediation process. The excavation extent removed all the debris associated with the battery waste sites.

No anomalous material or stained soil was discovered during remediation activities of either the 600-316 or 600-318 waste sites. All material was direct loaded for disposal to the Environmental Restoration and Disposal Facility (ERDF).

The areas (subsites) were evaluated in the same document and Interim Closed Out on a single Reclassification form.

The SubSite is Part Of:

Code: 600-318

Names: 600-318; Wet Cell Batteries

Code: 600-318:5

Classification: Accepted

Names: 600-318:5; Wet cell Batteries in Area 5

Reclassification Final Closed Out (10/28/2015)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. The five areas (subsites) were evaluated in the same document and Interim Closed Out on a single Reclassification form. The site consisted of a 4 meter by 8 meter (13 by 26 feet) automotive shop dump area with lead battery debris.

Location: The site was located approximately 309 meters (0.2 miles) east of Route 2 North and 127 m (417 feet) north of Route 11A. Area 5 is at E584684.6/N138951.9.

Closure Info: Interim (8/7/2013): (Interim Closed Out) Site visits and geophysical surveys were done in June and November 2011. The results determined that remediation was required. Remediation activities began in July 2011 and continued through February 2013.

The waste site boundaries were re-defined during the remediation process. The excavation extent removed all the debris associated with the battery waste sites.

No anomalous material or stained soil was discovered during remediation activities of either the 600-316 or 600-318 waste sites. All material was direct loaded for disposal to the Environmental Restoration and Disposal Facility (ERDF).

The areas (subsites) were evaluated in the same document and Interim Closed Out on a single Reclassification form.

The SubSite is Part Of:

Code: 600-318

Names: 600-318; Wet Cell Batteries

Code: 600-319

Classification: Accepted

Names: 600-319; Miscellaneous Debris

Reclassification Interim Closed Out (10/17/2012)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The subsites have been remediated and Interim Closed Out. Therefore the parent site is also considered Interim Closed Out. The three subsites were reclassified on a single form. The waste site was comprised of three areas of surface debris consisting of ferrous metal, stained soil and dried paint. Many items are believed to have supported Army Tent Camp 230. One location consisted of a 0.5 by 0.5 meter (2 by 2 feet) wooden lined, below grade structure that is 0.5 meters (2 feet) deep. It contained empty paint and paint thinner cans. One empty can of military paint thinner had a date of 1956.

Location: The coordinates for the three debris sites are:

Area 1 was at E580195.5/N144963.8.

Area 2 was at E581558.7/N142840.4.

Area 3 was at E585655.5/N139710.0.

Waste Type: Misc. Trash and Debris

Waste Description: Sulfur based cutting oils in the metal turnings and lead in the paint may be present.

Closure Info: Interim (10/17/2012): Remediation of the combined 100-IU-2/6 debris and burn area waste sites occurred between August 10, 2011 and May 29, 2012. The activity resulted in a total of approximately 523 bank cubic meters (BCM) (682 bank cubic yards [BCY]) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility (ERDF).

Based on observations during the field walkdowns to support remedial action, it was determined that the 600-305, 600-308, 600-309, 600-310, 600-311, 600-312, 600-313, 600-314, 600-317, 600-319, and 600-324 waste sites required remediation. The 600-314 subsites required removal of only telecommunication equipment on the ground surface with no excavation.

Remediation of the 600-305:1 and 600-305:2 subsites occurred on April 4, 2012. The soil within these subsites was excavated to a depth of approximately 0.3 meters (1 ft) below ground surface (bgs). No excavation occurred at the 600-305:3 waste site since surface removal of a pipe was the only scope. The remediation of the 600-305:4 subsite occurred on May 14, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs. The remediation of the 600-305:5 subsite occurred on May 15, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs.

The remediation of the 600-308 waste site occurred on May 29, 2012. The soil within this waste site was excavated to a depth of approximately 0.6 meters (2 ft) bgs.

The remediation of the 600-309 waste site occurred on May 23 and 24, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-310 waste site occurred on May 22 and 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-311 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-312 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-313 waste site occurred on May 16, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

For the five 600-314 subsites, only component item removal was required, since only telecommunications components were lying on the surface with no stained or additional anomalous material. Component removal at the 600-314 subsites occurred on May 1, 4, and 14, 2012. All the components were disposed of at ERDF.

The remediation of the 600-317 waste site occurred on May 21 and 22, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-319:1 subsite occurred on May 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:2 subsite occurred on May 4, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:3 subsite occurred on August 10, 2011. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-324 waste site occurred between April 26 and 30, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

A post-excavation global positioning survey (GPS) walk-around for the excavated waste sites was performed following excavation. Excavated material from all subsites and waste sites was direct loaded for disposal to ERDF, and no soil staging pile area or overburden areas were utilized.

This Site has the Following SubSites:

Code: 600-319:1

Names: 600-319:1; Miscellaneous Debris Area 1

Code: 600-319:2

Names: 600-319:2; Miscellaneous Debris Area 2

Code: 600-319:3

Names: 600-319:3; Miscellaneous Debris Area 3

Code: 600-319:1

Classification: Accepted

Names: 600-319:1; Miscellaneous Debris Area 1

Reclassification Interim Closed Out (10/17/2012)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. It was a 7 meter (23 ft) diameter, circular area containing concentrated ferrous metal turnings, broken glass and orange stained soil.

Location: The site was located south of Route 1 and west of Route 2 North, at coordinates E580196.8 N144963.2.

Waste Type: Soil

**Waste
Description:**

Waste Type: Misc. Trash and Debris

**Waste
Description:**

Closure Info: Interim (10/17/2012): Remediation of the combined 100-IU-2/6 debris and burn area waste sites occurred between August 10, 2011 and May 29, 2012. The activity resulted in a total of approximately 523 bank cubic meters (BCM) (682 bank cubic yards [BCY]) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility (ERDF).

Based on observations during the field walkdowns to support remedial action, it was determined that the 600-305, 600-308, 600-309, 600-310, 600-311, 600-312, 600-313, 600-314, 600-317, 600-319, and 600-324 waste sites required remediation. The 600-314 subsites required removal of only telecommunication equipment on the ground surface with no excavation.

Remediation of the 600-305:1 and 600-305:2 subsites occurred on April 4, 2012. The soil within these subsites was excavated to a depth of approximately 0.3 meters (1 ft) below ground surface (bgs). No excavation occurred at the 600-305:3 waste site since surface removal of a pipe was the only scope. The remediation of the 600-305:4 subsite occurred on May 14, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs. The remediation of the 600-305:5 subsite occurred on May 15, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs.

The remediation of the 600-308 waste site occurred on May 29, 2012. The soil within this waste site was excavated to a depth of approximately 0.6 meters (2 ft) bgs.

The remediation of the 600-309 waste site occurred on May 23 and 24, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-310 waste site occurred on May 22 and 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-311 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-312 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-313 waste site occurred on May 16, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

For the five 600-314 subsites, only component item removal was required, since only telecommunications components were lying on the surface with no stained or additional anomalous material. Component removal at the 600-314 subsites occurred on May 1, 4, and 14, 2012. All the components were disposed of at ERDF.

The remediation of the 600-317 waste site occurred on May 21 and 22, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-319:1 subsite occurred on May 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:2 subsite occurred on May 4, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:3 subsite occurred on August 10, 2011. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-324 waste site occurred between April 26 and 30, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

A post-excavation global positioning survey (GPS) walk-around for the excavated waste sites was performed following excavation. Excavated material from all subsites and waste sites was direct loaded for disposal to ERDF, and no soil staging pile area or overburden areas were utilized.

The SubSite is Part Of:

Code: 600-319

Names: 600-319; Miscellaneous Debris

Code: 600-319:2

Classification: Accepted

Names: 600-319:2; Miscellaneous Debris Area 2

Reclassification: Interim Closed Out (10/17/2012)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. The subsite consisted of a 0.5 by 0.5 m (2 by 2 ft) wood lined, below grade structure that was 0.5 m (2 ft) deep. It contained empty paint and paint thinner cans. One empty can of military paint thinner has a date of 1956.

Location: The site is located west of Route 2 North and north of Route 11A at coordinates E581558.1, N142841.0.

Closure Info: Interim (10/17/2012): Remediation of the combined 100-IU-2/6 debris and burn area waste sites occurred between August 10, 2011 and May 29, 2012. The activity resulted in a total of approximately 523 bank cubic meters (BCM) (682 bank cubic yards [BCY]) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility (ERDF).

Based on observations during the field walkdowns to support remedial action, it was determined that the 600-305, 600-308, 600-309, 600-310, 600-311, 600-312, 600-313, 600-314, 600-317, 600-319, and 600-324 waste sites required remediation. The 600-314 subsites required removal of only telecommunication equipment on the ground surface with no excavation.

Remediation of the 600-305:1 and 600-305:2 subsites occurred on April 4, 2012. The soil within these subsites was excavated to a depth of approximately 0.3 meters (1 ft) below ground surface (bgs). No excavation occurred at the 600-305:3 waste site since surface removal of a pipe was the only scope. The remediation of the 600-305:4 subsite occurred on May 14, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs. The remediation of the 600-305:5 subsite occurred on May 15, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs.

The remediation of the 600-308 waste site occurred on May 29, 2012. The soil within this waste site was excavated to a depth of approximately 0.6 meters (2 ft) bgs.

The remediation of the 600-309 waste site occurred on May 23 and 24, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-310 waste site occurred on May 22 and 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-311 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-312 waste site occurred on May 14, 2012. The soil within this

waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-313 waste site occurred on May 16, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

For the five 600-314 subsites, only component item removal was required, since only telecommunications components were lying on the surface with no stained or additional anomalous material. Component removal at the 600-314 subsites occurred on May 1, 4, and 14, 2012. All the components were disposed of at ERDF.

The remediation of the 600-317 waste site occurred on May 21 and 22, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-319:1 subsite occurred on May 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:2 subsite occurred on May 4, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:3 subsite occurred on August 10, 2011. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-324 waste site occurred between April 26 and 30, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

A post-excavation global positioning survey (GPS) walk-around for the excavated waste sites was performed following excavation. Excavated material from all subsites and waste sites was direct loaded for disposal to ERDF, and no soil staging pile area or overburden areas were utilized.

The SubSite is Part Of:

Code: 600-319

Names: 600-319; Miscellaneous Debris

Code: 600-319:3

Classification: Accepted

Names: 600-319:3; Miscellaneous Debris Area 3

Reclassification Interim Closed Out (10/17/2012)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. The subsite consisted of a small area of suspected dried paint. It measured approximately 2 meters by 4 meters (6 by 13 ft).

Location: The site is located south of Avenue A and west of Division Street in the Hanford Construction Camp, at coordinates E585655.5 N139710.0. It was located 90 meters (295 feet) west of the former Richfield Oil Company Gas Station.

Closure Info: Interim (10/17/2012): Remediation of the combined 100-IU-2/6 debris and burn area waste sites occurred between August 10, 2011 and May 29, 2012. The activity resulted in a total of approximately 523 bank cubic meters (BCM) (682 bank cubic yards [BCY]) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility (ERDF).

Based on observations during the field walkdowns to support remedial action, it was determined that the 600-305, 600-308, 600-309, 600-310, 600-311, 600-312, 600-313, 600-314, 600-317, 600-319, and 600-324 waste sites required remediation. The 600-314 subsites required removal of only telecommunication equipment on the ground surface with no

excavation.

Remediation of the 600-305:1 and 600-305:2 subsites occurred on April 4, 2012. The soil within these subsites was excavated to a depth of approximately 0.3 meters (1 ft) below ground surface (bgs). No excavation occurred at the 600-305:3 waste site since surface removal of a pipe was the only scope. The remediation of the 600-305:4 subsite occurred on May 14, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs. The remediation of the 600-305:5 subsite occurred on May 15, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs.

The remediation of the 600-308 waste site occurred on May 29, 2012. The soil within this waste site was excavated to a depth of approximately 0.6 meters (2 ft) bgs.

The remediation of the 600-309 waste site occurred on May 23 and 24, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-310 waste site occurred on May 22 and 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-311 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-312 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-313 waste site occurred on May 16, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

For the five 600-314 subsites, only component item removal was required, since only telecommunications components were lying on the surface with no stained or additional anomalous material. Component removal at the 600-314 subsites occurred on May 1, 4, and 14, 2012. All the components were disposed of at ERDF.

The remediation of the 600-317 waste site occurred on May 21 and 22, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-319:1 subsite occurred on May 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:2 subsite occurred on May 4, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:3 subsite occurred on August 10, 2011. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-324 waste site occurred between April 26 and 30, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

A post-excavation global positioning survey (GPS) walk-around for the excavated waste sites was performed following excavation. Excavated material from all subsites and waste sites was direct loaded for disposal to ERDF, and no soil staging pile area or overburden areas were utilized.

The SubSite is Part Of:

Code: 600-319

Names: 600-319; Miscellaneous Debris

Code: 600-320	Classification: Accepted
Names: 600-320; Oil Stains	Reclassification: Final Closed Out (10/28/2015)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The parent site and nine subsites have been Final Closed Out. The site consisted of nine areas with petroleum based material released to the ground surface. They were identified during a 2007 site walkdown. The nine areas were initially given individual subsite numbers. All nine areas were evaluated, remediated and Interim Closed Out in a single verification package and on a single reclassification form.

Area 1 consisted of a suspected oil dump area that is approximately 3 by 4 meters (10 by 13 feet). The soil was crusted with no vegetation growing in the affected area.

Area 2 consisted of an oil dump area that is approximately 8 by 5 meters (26 by 16 feet). There were two oil filters on the ground. The soil was crusted with no vegetation growing in the affected area.

Area 3 consisted of a suspected oil dump area that is approximately 3 meters (10 feet) in diameter. The soil is crusted with no vegetation growing in the affected area.

Area 4 consisted of a suspected oil dump area that is approximately 2 meters (6 feet) in diameter. The soil is crusted with no vegetation growing in the affected area.

Area 5 consisted of a suspected oil dump area that is approximately 2 meters (6 feet) in diameter. The soil is crusted with no vegetation growing in the affected area.

Area 6 consists of a suspected oil dump area that is approximately 0.5 meters (2 feet) in diameter. The soil is crusted with no vegetation growing in the affected area.

Area 7 consisted of a 3 meter (10 feet) diameter area with no vegetation growing and a crusty surface.

Area 8 consisted of a suspected oil dump area that is approximately 2 meters (6 feet) in diameter. The soil was crusted with no vegetation growing in the affected area.

Area 9 consisted of an area of surface tar. This area was discovered while remediating waste site 600-280. Samples (J1C007 and J1C008) were collected during the 600-280 sampling activity. The sample results had elevated concentrations of lead, so the area was added to waste site 600-320.

Location: The nine area were found in an area extending from the old Hanford Camp to near the intersection of Route 2N and Route 1. The coordinates for the nine soil stained areas are:

Area 1 E580231.4/N144524.1
Area 2 E581892.6/N142045.3
Area 3 E583067.60/N140269.38
Area 4 E583131.98/N140209.13
Area 5 E583217.14/N140082.43
Area 6 E583472.12/N140270.74
Area 7 E585666.2/N140052.5
Area 8 E587461.7/N137843.3
Area 9 E580200.7/ N144927.4

Process Description: Materials found at these locations suggest that petroleum liquid was dumped from an oil accumulation container or was released from large equipment during lubricant change-out.

Waste Type: Oil

Waste Description: These areas may contain ICP metals, PAHs, TPH and possible PCB contamination.

Waste Type: Soil

Waste Description: The waste is potentially contaminated soil. These sites may contain ICP metals, PAHs, TPH and possible PCB contamination within the release areas.

Closure Info: Interim (8/7/2013): (Interim Closed Out) Characterization samples were collected at areas 2, 7, 8 and 9 in March 2011. Geophysical surveys were conducted between March and November of 2011. The size and shape of the areas were redefined following the geophysical surveys.

Remediation of the nine 600-320 subsites occurred between June 27, 2011, and March 21, 2013, resulting in a total of approximately 1,354 bank cubic meters (1,771 bank cubic yards) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility. The excavation depths ranged from 0.3 to 1.2 meters (1 to 4 feet). No overburden soil was stockpiled to be used as backfill at any of the subsites.

Final (10/28/2015): (Final Closed Out) Based upon evaluation of the previous reclassification data against the 100-F/IU Area ROD cleanup levels, no further RTD is required for any of the 26 waste sites (Listed below).

600-279, Vegetation-Free Area Between White Bluffs and 100-F
 600-293, White Bluffs Service Station #1
 600-294, White Bluffs Service Station #2
 600-298, Stained Soil and Surface Debris
 600-299, Surface Debris/Batteries
 600-300, Miscellaneous Surface Debris
 600-301, White Bluffs Sanitary Sewer Pipelines
 600-303, Vertical Pipes
 600-316, Dry Cell Batteries
 600-318, Wet Cell Batteries
 600-320, Oil Stains
 600-321, Suspect ACM Sites
 600-328, Lead Slag
 600-356, Tar Deposit West of Susie Junction
 600-368, Segment 4 Stained Soil #1
 600-369, Segment 4 Bare Ground and Crusted Soil Areas
 600-370, Segment 4 Debris Area #1
 600-371, Segment 4 Chalky Material Area
 600-372, Segment 4 Oil Stain and Filter Area #1
 600-373, Segment 4 Bare Ground and White Stain Area
 600-374, Segment 4 Drum Remnant Area
 600-375, Segment 4 Dry Cell Battery Debris Area #1
 600-376, Segment 4 Stained Soil Area #2
 600-377, Segment 4 Oil Stain and Filter Area #2
 600-378, 506 Telephone Exchange Emergency Generator Building Underground Fuel Storage tank
 600-379, Segment 4 Burn Area #1.

The Reclassification to Final Closed Out applies to all subsites associated with the waste sites

listed above.

This Site has the Following SubSites:

Code: 600-320:1
Names: 600-320:1; Oil Stains Area 1

Code: 600-320:2
Names: 600-320:2; Oil Stains Area 2

Code: 600-320:3
Names: 600-320:3; Oil Stains Area 3

Code: 600-320:4
Names: 600-320:4; Oil Stains Area 4

Code: 600-320:5
Names: 600-320:5; Oil Stains Area 5

Code: 600-320:6
Names: 600-320:6; Oil Stains Area 6

Code: 600-320:7
Names: 600-320:7; Oil Stains Area 7

Code: 600-320:8
Names: 600-320:8; Oil Stains Area 8

Code: 600-320:9
Names: 600-320:9; Oil Stains Area 9

Code: 600-320:1	Classification: Accepted
Names: 600-320:1; Oil Stains Area 1	Reclassification Final Closed Out (10/28/2015)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The subsite was a suspected oil dump area that is approximately 3 by 4 meters (10 by 13 ft). The soil was crusted with no vegetation growing in the affected area.

Location: The site was located west of Route 2 North and south of Route 1 at E580231.4/N144522.9.

Waste Type: Soil

Waste Description: Location suspected of being contaminated with petroleum products.

Closure Info: Interim (8/7/2013): (Interim Closed Out) Characterization samples were collected at areas 2, 7, 8 and 9 in March 2011. Geophysical surveys were conducted between March and November of 2011. The size and shape of the areas were redefined following the geophysical surveys.

Remediation of the nine 600-320 subsites occurred between June 27, 2011, and March 21, 2013, resulting in a total of approximately 1,354 bank cubic meters (1,771 bank cubic yards) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility. The excavation depths ranged from 0.3 to 1.2 meters (1 to 4 feet). No overburden soil was stockpiled to be used as backfill at any of the subsites.

The SubSite is Part Of:

Code: 600-320
Names: 600-320; Oil Stains

Code: 600-320:2 **Classification:** Accepted
Names: 600-320:2; Oil Stains Area 2 **Reclassification** Final Closed Out (10/28/2015)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The subsite consisted of an oil dump area that is approximately 8 by 5 meters (26 by 16 ft). There were two oil filters on the ground. The soil was crusted with no vegetation growing in the affected area.

Location: The site was located west of Route 2 North and north of Route 11A E581895.4/N142044.5.

Waste Type: Soil

Waste Description: Location suspected of being contaminated with petroleum products.

Closure Info: Interim (8/7/2013): (Interim Closed Out) Characterization samples were collected at areas 2, 7, 8 and 9 in March 2011. Geophysical surveys were conducted between March and November of 2011. The size and shape of the areas were redefined following the geophysical surveys.

Remediation of the nine 600-320 subsites occurred between June 27, 2011, and March 21, 2013, resulting in a total of approximately 1,354 bank cubic meters (1,771 bank cubic yards) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility. The excavation depths ranged from 0.3 to 1.2 meters (1 to 4 feet). No overburden soil was stockpiled to be used as backfill at any of the subsites.

The SubSite is Part Of:

Code: 600-320
Names: 600-320; Oil Stains

Code: 600-320:3 **Classification:** Accepted
Names: 600-320:3; Oil Stains Area 3 **Reclassification** Final Closed Out (10/28/2015)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The subsite consisted of a suspected oil and tar dump area that is approximately 3 meters (10 ft) in diameter. The soil was crusted with no vegetation growing in the affected area.

Location: The site was located west of Route 2 North and north of Route 11A at E583068.1/N140269.8.

Waste Type: Soil

Waste Description: Area suspected to be contaminated with petroleum products.

Closure Info: Interim (8/7/2013): (Interim Closed Out) Characterization samples were collected at areas 2, 7, 8 and 9 in March 2011. Geophysical surveys were conducted between March and November of 2011. The size and shape of the areas were redefined following the geophysical surveys.

Remediation of the nine 600-320 subsites occurred between June 27, 2011, and March 21,

2013, resulting in a total of approximately 1,354 bank cubic meters (1,771 bank cubic yards) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility. The excavation depths ranged from 0.3 to 1.2 meters (1 to 4 feet). No overburden soil was stockpiled to be used as backfill at any of the subsites.

The SubSite is Part Of:

Code: 600-320

Names: 600-320; Oil Stains

Code: 600-320:4

Classification: Accepted

Names: 600-320:4; Oil Stains Area 4

Reclassification: Final Closed Out (10/28/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The subsite was a suspected oil dump area that is approximately 2 meters (6 ft) in diameter. The soil was crusted with no vegetation growing in the affected area.

Location: The site was located west of Route 2 North and north of Route 11A at E583131.6/N140209.2.

Waste Type: Soil

Waste Description: Location suspected of being contaminated with petroleum products.

Closure Info: Interim (8/7/2013): (Interim Closed Out) Characterization samples were collected at areas 2, 7, 8 and 9 in March 2011. Geophysical surveys were conducted between March and November of 2011. The size and shape of the areas were redefined following the geophysical surveys.

Remediation of the nine 600-320 subsites occurred between June 27, 2011, and March 21, 2013, resulting in a total of approximately 1,354 bank cubic meters (1,771 bank cubic yards) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility. The excavation depths ranged from 0.3 to 1.2 meters (1 to 4 feet). No overburden soil was stockpiled to be used as backfill at any of the subsites.

The SubSite is Part Of:

Code: 600-320

Names: 600-320; Oil Stains

Code: 600-320:5

Classification: Accepted

Names: 600-320:5; Oil Stains Area 5

Reclassification: Final Closed Out (10/28/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The subsite was a suspected oil dump area that is approximately 2 meters (6 ft) in diameter. The soil was crusted with no vegetation growing in the affected area.

Location: The site was located west of Route 2 North and north of Route 11A at E583217.0/N140082.5.

Waste Type: Soil

Waste Description: Location suspected of being contaminated with petroleum products.

Closure Info: Interim (8/7/2013): (Interim Closed Out) Characterization samples were collected at areas 2, 7, 8 and 9 in March 2011. Geophysical surveys were conducted between March and November of 2011. The size and shape of the areas were redefined following the geophysical surveys.

Remediation of the nine 600-320 subsites occurred between June 27, 2011, and March 21, 2013, resulting in a total of approximately 1,354 bank cubic meters (1,771 bank cubic yards) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility. The excavation depths ranged from 0.3 to 1.2 meters (1 to 4 feet). No overburden soil was stockpiled to be used as backfill at any of the subsites.

The SubSite is Part Of:

Code: 600-320

Names: 600-320; Oil Stains

Code: 600-320:6

Classification: Accepted

Names: 600-320:6; Oil Stains Area 6

Reclassification: Final Closed Out (10/28/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The subsite was a suspected oil dump area that is approximately 0.5 meters (2 ft) in diameter. The soil was crusted with no vegetation growing in the affected area.

Location: The site was located west of Route 2 North and north of Route 11A at E583472.1/N140270.8.

Waste Type: Soil

Waste Description: Area suspected of being contaminated with petroleum products.

Closure Info: Interim (8/7/2013): (Interim Closed Out) Characterization samples were collected at areas 2, 7, 8 and 9 in March 2011. Geophysical surveys were conducted between March and November of 2011. The size and shape of the areas were redefined following the geophysical surveys.

Remediation of the nine 600-320 subsites occurred between June 27, 2011, and March 21, 2013, resulting in a total of approximately 1,354 bank cubic meters (1,771 bank cubic yards) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility. The excavation depths ranged from 0.3 to 1.2 meters (1 to 4 feet). No overburden soil was stockpiled to be used as backfill at any of the subsites.

The SubSite is Part Of:

Code: 600-320

Names: 600-320; Oil Stains

Code: 600-320:7

Classification: Accepted

Names: 600-320:7; Oil Stains Area 7

Reclassification: Final Closed Out (10/28/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The subsite was a 3 meter (10 ft) diameter area with no vegetation growing and crust-like surface.

Location: The site was located east of Route 2 North and north of Route 2 South at E585666.1/N140052.5.

Closure Info: Interim (8/7/2013): (Interim Closed Out) Characterization samples were collected at areas 2, 7, 8 and 9 in March 2011. Geophysical surveys were conducted between March and November of 2011. The size and shape of the areas were redefined following the geophysical surveys.

Remediation of the nine 600-320 subsites occurred between June 27, 2011, and March 21, 2013, resulting in a total of approximately 1,354 bank cubic meters (1,771 bank cubic yards) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility. The excavation depths ranged from 0.3 to 1.2 meters (1 to 4 feet). No overburden soil was stockpiled to be used as backfill at any of the subsites.

The SubSite is Part Of:

Code: 600-320

Names: 600-320; Oil Stains

Code: 600-320:8

Classification: Accepted

Names: 600-320:8; Oil Stains Area 8

Reclassification Final Closed Out (10/28/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The subsite was a suspected oil dump area that is approximately 2 meters (6 ft) in diameter. The soil was crusted with no vegetation growing in the affected area.

Location: The site was located west of ninth street and south of Avenue A in the Hanford Construction Camp at E587461.6/.N137843.5.

Waste Type: Soil

Waste Description: Location suspected of being contaminated with petroleum products.

Closure Info: Interim (8/7/2013): (Interim Closed Out) Characterization samples were collected at areas 2, 7, 8 and 9 in March 2011. Geophysical surveys were conducted between March and November of 2011. The size and shape of the areas were redefined following the geophysical surveys.

Remediation of the nine 600-320 subsites occurred between June 27, 2011, and March 21, 2013, resulting in a total of approximately 1,354 bank cubic meters (1,771 bank cubic yards) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility. The excavation depths ranged from 0.3 to 1.2 meters (1 to 4 feet). No overburden soil was stockpiled to be used as backfill at any of the subsites.

The SubSite is Part Of:

Code: 600-320

Names: 600-320; Oil Stains

Code: 600-320:9

Classification: Accepted

Names: 600-320:9; Oil Stains Area 9

Reclassification Final Closed Out (10/28/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The subsite was an area with tar visible on the surface.

Location: The site was located west of Route 2 North and south of Route 1 at E580202.2/N144925.9.

Waste Type: Soil

Waste Description: Location has tar visible on the soil surface. Samples collected also showed elevated concentrations of lead.

Closure Info: Interim (8/7/2013): (Interim Closed Out) Characterization samples were collected at areas 2, 7, 8 and 9 in March 2011. Geophysical surveys were conducted between March and November of 2011. The size and shape of the areas were redefined following the geophysical surveys.

Remediation of the nine 600-320 subsites occurred between June 27, 2011, and March 21, 2013, resulting in a total of approximately 1,354 bank cubic meters (1,771 bank cubic yards) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility. The excavation depths ranged from 0.3 to 1.2 meters (1 to 4 feet). No overburden soil was stockpiled to be used as backfill at any of the subsites.

The SubSite is Part Of:

Code: 600-320

Names: 600-320; Oil Stains

Code: 600-321

Classification: Accepted

Names: 600-321; Suspect Asbestos Containing Material and Debris

Reclassification: Final Closed Out (10/28/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The parent site and subsites has been remediated, Interim Closed Out and later Final Closed Out. It was four surface soil areas with scattered metal, fire brick, suspect friable asbestos and pipe lagging. The four areas became subsites, but the parent site and all the subsites were Interim Closed in a single document, on a single reclassification form.

Location 1 consisted of an area approximately 10 meters by 7 meters (23 by 33 feet) area of suspect friable asbestos insulation, metal, fire brick and pipe lagging.

Location 2 consisted of an area approximately 1.5 meters in (5 feet) in diameter of suspect friable asbestos insulation.

Location 3 consisted of an area approximately 1.4 meters in (5 feet) in diameter of suspect friable asbestos insulation.

Location 4 consisted of an area approximately 0.4 by 2 meters in (1.5 by 6 feet) of suspect friable asbestos insulation.

Location: Three of the areas are located in the former Hanford Construction Camp and one area is located along Route 2 North, 5.6 km (3.5 mi) north of the former Hanford Construction Camp.

Location 1 was at E580439.1/N144153.2.

Location 2 was at E586098.525/N138015.83.

Location 3 was at E586169.24/N138189.21.

Location 4 was at E586859.096/N138757.09.

Waste Type: Asbestos (friable)

Waste Description: The areas consist of suspect asbestos containing material (ACM) insulation.

Closure Info: Interim (8/15/2013): (Interim Closed Out) In October 2010, confirmatory samples were taken at the 600-303 waste site. The project team conducted site visits at various times from June 2011 to January 2013. The objective of the visits was to perform geophysical surveys and determine the extent (if any) of buried debris associated with the waste sites.

Remediation of the 600-303 waste site occurred on February 11, 2012, and February 12, 2012. The soil within this waste site was excavated to a depth of approximately 1.8 meters (6 ft) below ground surface (bgs) and resulted in the removal of 35 bank cubic meters (BCM) (46 bank cubic yards [BCY]) of soil and debris, which were disposed at the Environmental Restoration Disposal Facility (ERDF). The remediation of the 600-321 waste site subsites occurred between June 28, 2011, and March 19, 2013. The soil within the subsites was excavated to a depth of approximately 1.2 meters (4 ft) bgs and resulted in the removal of 235 BCM (307 BCY) of soil and debris, which were disposed at ERDF.

The waste site dimensions were revised during the remedial investigation. The final extent of the excavations at these waste sites removed all subsurface staining and debris present.

Final (10/28/2015): (Final Closed Out) Based upon evaluation of the previous reclassification data against the 100-F/IU Area ROD cleanup levels, no further RTD is required for any of the 26 waste sites (Listed below).

600-279, Vegetation-Free Area Between White Bluffs and 100-F
 600-293, White Bluffs Service Station #1
 600-294, White Bluffs Service Station #2
 600-298, Stained Soil and Surface Debris
 600-299, Surface Debris/Batteries
 600-300, Miscellaneous Surface Debris
 600-301, White Bluffs Sanitary Sewer Pipelines
 600-303, Vertical Pipes
 600-316, Dry Cell Batteries
 600-318, Wet Cell Batteries
 600-320, Oil Stains
 600-321, Suspect ACM Sites
 600-328, Lead Slag
 600-356, Tar Deposit West of Susie Junction
 600-368, Segment 4 Stained Soil #1
 600-369, Segment 4 Bare Ground and Crusted Soil Areas
 600-370, Segment 4 Debris Area #1
 600-371, Segment 4 Chalky Material Area
 600-372, Segment 4 Oil Stain and Filter Area #1
 600-373, Segment 4 Bare Ground and White Stain Area
 600-374, Segment 4 Drum Remnant Area
 600-375, Segment 4 Dry Cell Battery Debris Area #1
 600-376, Segment 4 Stained Soil Area #2
 600-377, Segment 4 Oil Stain and Filter Area #2
 600-378, 506 Telephone Exchange Emergency Generator Building Underground Fuel Storage tank
 600-379, Segment 4 Burn Area #1.

The Reclassification to Final Closed Out applies to all subsites associated with the waste sites listed above.

This Site has the Following SubSites:

Code: 600-321:1
Names: 600-321:1; Suspect ACM Sites Area 1
Code: 600-321:2
Names: 600-321:2; Suspect ACM Sites Area 2
Code: 600-321:3
Names: 600-321:3; Suspect ACM Sites Area 3
Code: 600-321:4
Names: 600-321:4; Suspect ACM Sites Area 4

Code: 600-321:1 **Classification:** Accepted
Names: 600-321:1; Suspect ACM Sites Area 1 **Reclassification:** Final Closed Out (10/28/2015)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The parent site and subsites has been remediated, Interim Closed Out and later Final Closed Out. It was four surface soil areas with scattered metal, fire brick, suspect friable asbestos and pipe lagging. The four areas became subsites, but the waste site and the subsites were closed in a single document, on a single reclassification form. Subsite 1 consisted of an area approximately 10 meters by 7 meters (23 by 33 ft) area of suspect friable asbestos insulation, metal, fire brick and pipe lagging.

Location: E580231.4 N144522.9

The site is located west of Route 2 North and south-southeast of Route 1.

Closure Info: Interim (8/15/2013): (Interim Closed Out) In October 2010, confirmatory samples were taken at the 600-303 waste site. The project team conducted site visits at various times from June 2011 to January 2013. The objective of the visits was to perform geophysical surveys and determine the extent (if any) of buried debris associated with the waste sites.

Remediation of the 600-303 waste site occurred on February 11, 2012, and February 12, 2012. The soil within this waste site was excavated to a depth of approximately 1.8 meters (6 ft) below ground surface (bgs) and resulted in the removal of 35 bank cubic meters (BCM) (46 bank cubic yards [BCY]) of soil and debris, which were disposed at the Environmental Restoration Disposal Facility (ERDF). The remediation of the 600-321 waste site subsites occurred between June 28, 2011, and March 19, 2013. The soil within the subsites was excavated to a depth of approximately 1.2 meters (4 ft) bgs and resulted in the removal of 235 BCM (307 BCY) of soil and debris, which were disposed at ERDF.

The waste site dimensions were revised during the remedial investigation. The final extent of the excavations at these waste sites removed all subsurface staining and debris present.

The SubSite is Part Of:

Code: 600-321
Names: 600-321; Suspect Asbestos Containing Material and Debris

Code: 600-321:2 **Classification:** Accepted
Names: 600-321:2; Suspect ACM Sites Area 2 **Reclassification:** Final Closed Out (10/28/2015)
Type: Unplanned Release **Start Date:**

Status: Inactive**End Date:**

Description: The parent site and subsites has been remediated, Interim Closed Out and later Final Closed Out. It was four surface soil areas with scattered metal, fire brick, suspect friable asbestos and pipe lagging. The four areas became subsites, but the waste site and the subsites were closed in a single document, on a single reclassification form. Subsite 2 consisted of an area approximately 1.5 meters (5 ft) in diameter of suspect friable asbestos insulation.

Location: E581895.4 N142044.5

The site is located east of Guadalcanal Street and south of Doolittle Avenue in the Hanford Construction Camp.

Closure Info: Interim (8/15/2013): (Interim Closed Out) In October 2010, confirmatory samples were taken at the 600-303 waste site. The project team conducted site visits at various times from June 2011 to January 2013. The objective of the visits was to perform geophysical surveys and determine the extent (if any) of buried debris associated with the waste sites.

Remediation of the 600-303 waste site occurred on February 11, 2012, and February 12, 2012. The soil within this waste site was excavated to a depth of approximately 1.8 meters (6 ft) below ground surface (bgs) and resulted in the removal of 35 bank cubic meters (BCM) (46 bank cubic yards [BCY]) of soil and debris, which were disposed at the Environmental Restoration Disposal Facility (ERDF). The remediation of the 600-321 waste site subsites occurred between June 28, 2011, and March 19, 2013. The soil within the subsites was excavated to a depth of approximately 1.2 meters (4 ft) bgs and resulted in the removal of 235 BCM (307 BCY) of soil and debris, which were disposed at ERDF.

The waste site dimensions were revised during the remedial investigation. The final extent of the excavations at these waste sites removed all subsurface staining and debris present.

The SubSite is Part Of:

Code: 600-321

Names: 600-321; Suspect Asbestos Containing Material and Debris

Code: 600-321:3

Classification: Accepted

Names: 600-321:3; Suspect ACM Sites Area 3

Reclassification: Final Closed Out (10/28/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The parent site and subsites has been remediated, Interim Closed Out and later Final Closed Out. It was four surface soil areas with scattered metal, fire brick, suspect friable asbestos and pipe lagging. The four areas became subsites, but the waste site and the subsites were closed in a single document, on a single reclassification form. Subsite 3 consisted of an area approximately 1.4 meters (5 ft) in diameter of suspect friable asbestos insulation.

Location: E583068.1 N140269.8

The site is located west of 4th Street north of Avenue Din the Hanford Construction Camp.

Related Sites/ Structures: The site is located adjacent to the Welding Shop.

Closure Info: Interim (8/15/2013): (Interim Closed Out) In October 2010, confirmatory samples were taken at the 600-303 waste site. The project team conducted site visits at various times from June 2011

to January 2013. The objective of the visits was to perform geophysical surveys and determine the extent (if any) of buried debris associated with the waste sites.

Remediation of the 600-303 waste site occurred on February 11, 2012, and February 12, 2012. The soil within this waste site was excavated to a depth of approximately 1.8 meters (6 ft) below ground surface (bgs) and resulted in the removal of 35 bank cubic meters (BCM) (46 bank cubic yards [BCY]) of soil and debris, which were disposed at the Environmental Restoration Disposal Facility (ERDF). The remediation of the 600-321 waste site subsites occurred between June 28, 2011, and March 19, 2013. The soil within the subsites was excavated to a depth of approximately 1.2 meters (4 ft) bgs and resulted in the removal of 235 BCM (307 BCY) of soil and debris, which were disposed at ERDF.

The waste site dimensions were revised during the remedial investigation. The final extent of the excavations at these waste sites removed all subsurface staining and debris present.

The SubSite is Part Of:

Code: 600-321

Names: 600-321; Suspect Asbestos Containing Material and Debris

Code: 600-321:4

Classification: Accepted

Names: 600-321:4; Suspect ACM Sites Area 4

Reclassification: Final Closed Out (10/28/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The parent site and subsites has been remediated, Interim Closed Out and later Final Closed Out. It was four surface soil areas with scattered metal, fire brick, suspect friable asbestos and pipe lagging. The four areas became subsites, but the waste site and the subsites were closed in a single document, on a single reclassification form. Subsite 4 consisted of an area approximately 0.4 by 2 meters (1.5 by 6 ft) of suspect friable asbestos insulation.

Location: E583131.6 N140209.2

The site is located south of Avenue A and east of 4th Street in the Hanford Construction Camp.

Closure Info: Interim (8/15/2013): (Interim Closed Out) In October 2010, confirmatory samples were taken at the 600-303 waste site. The project team conducted site visits at various times from June 2011 to January 2013. The objective of the visits was to perform geophysical surveys and determine the extent (if any) of buried debris associated with the waste sites.

Remediation of the 600-303 waste site occurred on February 11, 2012, and February 12, 2012. The soil within this waste site was excavated to a depth of approximately 1.8 meters (6 ft) below ground surface (bgs) and resulted in the removal of 35 bank cubic meters (BCM) (46 bank cubic yards [BCY]) of soil and debris, which were disposed at the Environmental Restoration Disposal Facility (ERDF). The remediation of the 600-321 waste site subsites occurred between June 28, 2011, and March 19, 2013. The soil within the subsites was excavated to a depth of approximately 1.2 meters (4 ft) bgs and resulted in the removal of 235 BCM (307 BCY) of soil and debris, which were disposed at ERDF.

The waste site dimensions were revised during the remedial investigation. The final extent of the excavations at these waste sites removed all subsurface staining and debris present.

The SubSite is Part Of:

Code: 600-321
Names: 600-321; Suspect Asbestos Containing Material and Debris

Code: 600-322 **Classification:** Accepted
Names: 600-322; Rail Spur Pipe **Reclassification** Interim No Action (4/26/2011)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The waste site has been evaluated and determined to require No Action. It is an 8 inch (20 centimeter) diameter carbon steel pipe with a diamond hatched cover plate and the soil beneath the pipe. The pipe and cover are flush with the ground surface. The pipe drains to the south under a rail spur.

Location: This site is located approximately 350 meters (1150 feet) south west of WIDS site 600-240 (Debris in Gravel Pit 17). The coordinates for the pipe are E583129.93/N140262.979.

Related Sites/ Structures: This pipe is located adjacent to a rail system that was constructed between 1943 through 1945. The rail spur possibly transported construction materials from nearby gravel pits.

Closure Info: Interim (4/26/2011): Based on observations during the site visit and review of the history of the 600-322 waste site, confirmatory sampling was performed in November 2011.

Code: 600-323 **Classification:** Accepted
Names: 600-323; Suspect Bermed Area **Reclassification** Interim No Action (4/26/2011)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The site has been evaluated and determined to require No Action. It is described as a bermed area with coal cinders and a ditch running east and west within the area.

Location: This site is located approximately 300 meters (985 feet) west of Route 2 North and 400 meters (1,300 feet) east of WIDS site 600-240 (gravel pit 17). The center point coordinates for the berm are E584073.7/ N140263.2.

Closure Info: Interim: Characterization sampling was collected from four test pits in November 2010. Based on the results of the characterization samples, no remediation was required at this site.

Code: 600-324 **Classification:** Accepted
Names: 600-324; Burnt Debris Area **Reclassification** Interim Closed Out (10/17/2012)
Type: Burn Pit **Start Date:**
Status: Inactive **End Date:**

Description: The waste site has been remediated and Interim Closed Out. The site consisted of the a concrete pad with miscellaneous pipe and auto parts debris with burnt wood, metal debris and the underlying soil.

Location: This site was located approximately 1.5 kilometers (0.9 miles) north of Route 11 and 100 meters (330 feet) west of Route 2 North, 100 meters (330 feet) east of WIDS site 600-239 (gravel pit 16). The coordinates for the site are E584291.4/N140285.7.

Related Sites/ Structures: This site may be associated with the Hanford Aggregate Pit 16 and 615 Hot Mix Plant.

Process Description: Based on the proximity to Gravel Pit 16 (WIDS 600-239), materials may have been used in support of the Hot Mix Plant and aggregate Pit 16 operations.

Closure Info: Interim (10/17/2012): Remediation of the combined 100-IU-2/6 debris and burn area waste sites occurred between August 10, 2011 and May 29, 2012. The activity resulted in a total of approximately 523 bank cubic meters (BCM) (682 bank cubic yards [BCY]) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility (ERDF).

Based on observations during the field walkdowns to support remedial action, it was determined that the 600-305, 600-308, 600-309, 600-310, 600-311, 600-312, 600-313, 600-314, 600-317, 600-319, and 600-324 waste sites required remediation. The 600-314 subsites required removal of only telecommunication equipment on the ground surface with no excavation.

Remediation of the 600-305:1 and 600-305:2 subsites occurred on April 4, 2012. The soil within these subsites was excavated to a depth of approximately 0.3 meters (1 ft) below ground surface (bgs). No excavation occurred at the 600-305:3 waste site since surface removal of a pipe was the only scope. The remediation of the 600-305:4 subsite occurred on May 14, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs. The remediation of the 600-305:5 subsite occurred on May 15, 2012. The soil within this subsite was excavated to a depth of approximately 0.3 meters (1 ft) bgs.

The remediation of the 600-308 waste site occurred on May 29, 2012. The soil within this waste site was excavated to a depth of approximately 0.6 meters (2 ft) bgs.

The remediation of the 600-309 waste site occurred on May 23 and 24, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-310 waste site occurred on May 22 and 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-311 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-312 waste site occurred on May 14, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

The remediation of the 600-313 waste site occurred on May 16, 2012. The soil within this waste site was excavated to a depth of approximately 1 meter (3 ft) bgs.

For the five 600-314 subsites, only component item removal was required, since only telecommunications components were lying on the surface with no stained or additional anomalous material. Component removal at the 600-314 subsites occurred on May 1, 4, and 14, 2012. All the components were disposed of at ERDF.

The remediation of the 600-317 waste site occurred on May 21 and 22, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-319:1 subsite occurred on May 23, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:2 subsite occurred on May 4, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs. The remediation of the 600-319:3 subsite occurred on

August 10, 2011. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

The remediation of the 600-324 waste site occurred between April 26 and 30, 2012. The soil within this waste site was excavated to a depth of approximately 1 meters (3 ft) bgs.

A post-excavation global positioning survey (GPS) walk-around for the excavated waste sites was performed following excavation. Excavated material from all subsites and waste sites was direct loaded for disposal to ERDF, and no soil staging pile area or overburden areas were utilized.

Code: 600-325 **Classification:** Accepted
Names: 600-325; Burned Roofing Materials **Reclassification:** Interim Closed Out (8/2/2012)
Type: Burn Pit **Start Date:**
Status: Inactive **End Date:**

Description: The two subsites have been remediated and reclassified as Interim Closed Out so the parent site is also Interim Closed Out. The site consisted of two adjacent burned roofing materials areas.
Location: The coordinates for the two burn site areas are E585340.60/N139798.85 and E585337.60/N139144.83.

Waste Type: Soil
Waste Description: The waste is potentially contaminated soil and the roofing material. Contaminants may include asbestos and petroleum products.

This Site has the Following SubSites:

Code: 600-325:1
Names: 600-325:1; Burned Roofing Materials Area 1
Code: 600-325:2
Names: 600-325:2; Burned Roofing Materials Area 2

Code: 600-325:1 **Classification:** Accepted
Names: 600-325:1; Burned Roofing Materials Area 1 **Reclassification:** Interim Closed Out (8/2/2012)
Type: Burn Pit **Start Date:**
Status: Inactive **End Date:**

Description: The subsite has been remediated and Interim Closed Out. It consisted of a 5 meters (16 ft) diameter area of burned roofing material.
Location: The site is located west of 5th Street and north of Eisenhower Avenue in the Hanford Construction Camp at coordinates E585338.6 N139794.1.

Closure Info: Interim (8/2/2012): Geophysical surveys were conducted to detect subsurface anomalies. Remediation of the 600-306 waste site occurred on April 3 and 4, 2012, and resulted in approximately 73.5 bank cubic meters (96.1 bank cubic yards) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility (ERDF). Remediation of the 600-307 waste site occurred on April 3, 2012, and resulted in approximately 87.6 bank cubic meters (114.6 bank cubic yards) of soil and debris being removed and disposed at the ERDF. The 600-325:1 and 600-325:2 waste subsites were remediated between July 5 and 13, 2011, and

resulted in approximately 176.0 bank cubic meters (230.2 bank cubic yards) of soil and debris being removed and disposed at the ERDF. No overburden soil was stockpiled to be used as backfill.

The SubSite is Part Of:

Code: 600-325

Names: 600-325; Burned Roofing Materials

Code: 600-325:2

Classification: Accepted

Names: 600-325:2; Burned Roofing Materials Area 2

Reclassification Interim Closed Out (8/2/2012)

Type: Burn Pit

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. It consisted of a 5 by 20 meter (16 by 65 ft) area of burned roofing material.

Location: The site is located east of Guadalcanal Street and south of Doolittle Avenue in the Hanford Construction Camp at coordinates E585344.7, N139138.4. The site was located between the Auditorium and the Service Station.

Closure Info: Interim (8/2/2012): Geophysical surveys were conducted to detect subsurface anomalies. Remediation of the 600-306 waste site occurred on April 3 and 4, 2012, and resulted in approximately 73.5 bank cubic meters (96.1 bank cubic yards) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility (ERDF). Remediation of the 600-307 waste site occurred on April 3, 2012, and resulted in approximately 87.6 bank cubic meters (114.6 bank cubic yards) of soil and debris being removed and disposed at the ERDF. The 600-325:1 and 600-325:2 waste subsites were remediated between July 5 and 13, 2011, and resulted in approximately 176.0 bank cubic meters (230.2 bank cubic yards) of soil and debris being removed and disposed at the ERDF. No overburden soil was stockpiled to be used as backfill.

The SubSite is Part Of:

Code: 600-325

Names: 600-325; Burned Roofing Materials

Code: 600-326

Classification: Accepted

Names: 600-326; Odorous Black Material

Reclassification None

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The waste site is two areas of the underlying soil and material that appear to be brittle. There is also some angular items, black in color that have a hydrogen sulfide odor. Field visits were performed by the Orphan Site Evaluation team in May and July 2007. The site was separated into two subsites. 600-326:1, Black Material Area 1 and 600-326:2, Black Material Area 2.

Location: The subsites are located along the Columbia River in the Hanford Construction Camp.

Waste Type: Construction Debris

Waste Description: The waste consists of the black material. There is also brown staining of the soil around and within these piles of material.

The contaminants of potential concern are unknown. The material may be Foamglas Insulation (Registered Trademark of Pittsburgh Corning Corporation). The material is also called cellular glass. This material contains hydrogen sulfide, carbon monoxide, carbon dioxide, glass dust, crystalline silica. (See MSDS for Foamglas Insulation.)

This Site has the Following SubSites:

Code: 600-326:1

Names: 600-326:1; Black Material Area 1

Code: 600-326:2

Names: 600-326:2; Black Material Area 2

Code: 600-326:1

Classification: Accepted

Names: 600-326:1; Black Material Area 1

Reclassification: None

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The subsite consists of a 2 by 4 meter (6 by 13 ft) area of charcoal gray material suspected to be insulating material. It has a sulfur smell.

Location: The subsite is approximately 76 meters SW of the former 145 Bldg (CMX) facility in the Hanford townsite.

The SubSite is Part Of:

Code: 600-326

Names: 600-326; Odorous Black Material

Code: 600-326:2

Classification: Accepted

Names: 600-326:2; Black Material Area 2

Reclassification: None

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The subsite consists of a 6 meter (20 ft) diameter area of unknown black porous material. There is no vegetation growing in the affected area.

Location: The subsite is approximately 220 meters (720 ft) northwest of site 600-186 Hanford Construction Camp Septic Tanks.

The SubSite is Part Of:

Code: 600-326

Names: 600-326; Odorous Black Material

Code: 600-327

Classification: Accepted

Names: 600-327; Suspect Dichromate Facility

Reclassification: Interim No Action (4/13/2011)

Type: Process Unit/Plant

Start Date:

Status: Inactive

End Date:

Description: The site has been evaluated and determined to require No Action. It is a large depression filled

with Russian thistle. A 2.5 cm (1 inch) diameter water pipe stub is located on the north side of the depression.

- Location:** This site is located approximately 1.8 kilometers (1.2 miles) northwest of the intersection of Route 2 North and Route 11A and approximately 70 meters NW of the 145 Water Treatment Building. The coordinates for the site are E585905.425, N139845.264.
- Process Description:** Its function is not known. Document # IN-163, Monthly Field Report for November 1943, indicates this area contained coal storage and five locomotives that supported the 145 building.
- Waste Type:** Soil
- Waste Description:** Sodium dichromate and other chemicals that were utilized in the 145 Building (CMX) processes.
- Closure Info:** Interim: Confirmatory samples were collected from a test trench in November 2010. Based on the confirmatory sample results, no remediation was required.

-
- | | |
|----------------------------------|--|
| Code: 600-328 | Classification: Accepted |
| Names: 600-328; Lead Slag | Reclassification: Final Closed Out (10/28/2015) |
| Type: Unplanned Release | Start Date: |
| Status: Inactive | End Date: |

- Description:** This site has been remediated, Interim Closed Out and later Final Closed Out. It consisted of three areas of distressed vegetation with scattered lead slag and a small area of visibly stained soil. The staining of the soil appeared to be petroleum based. It is speculated that the original purpose of the lead was to seal joints in cast iron sewer systems.
- Location:** This site was located approximately 1.75 kilometers (1.1 miles) southeast of the intersection of Route 2 North and Route 11A and approximately 900 meters (0.55 miles) east of Route 2. This site was approximately 50 meters southeast of Boiler House #5 of the Hanford Construction Camp. The coordinates for the site are E586117.759, N138520.321.
- Process Description:** The lead may have been used for pouring joints in cast iron sewer systems.
- Waste Type:** Soil
- Waste Description:** This site is potentially contaminated with lead, TPH, PAHs and RCRA metals.
- Closure Info:** Interim (8/7/2013): (Interim Closed Out) Remediation of the 600-328 waste site was conducted between January 30, 2013, and February 4, 2013, resulting in approximately 121 bank cubic meters (BCM) (158 bank cubic yards [BCY]) of soil and battery debris being removed and disposed at the Environmental Restoration Disposal Facility (ERDF). During excavation and remediation, the three areas of the 600-328 waste site were merged creating one excavation. The final excavation depth for the 600-328 waste site is approximately 0.9 meters (3 ft) below ground surface. Excavated materials were directly loaded out for disposal to ERDF. No soil staging pile or overburden areas were created.

Final (10/28/2015): (Final Closed Out) Based upon evaluation of the previous reclassification data against the 100-F/IU Area ROD cleanup levels, no further RTD is required for any of the 26 waste sites (Listed below).

600-279, Vegetation-Free Area Between White Bluffs and 100-F
600-293, White Bluffs Service Station #1

600-294, White Bluffs Service Station #2
 600-298, Stained Soil and Surface Debris
 600-299, Surface Debris/Batteries
 600-300, Miscellaneous Surface Debris
 600-301, White Bluffs Sanitary Sewer Pipelines
 600-303, Vertical Pipes
 600-316, Dry Cell Batteries
 600-318, Wet Cell Batteries
 600-320, Oil Stains
 600-321, Suspect ACM Sites
 600-328, Lead Slag
 600-356, Tar Deposit West of Susie Junction
 600-368, Segment 4 Stained Soil #1
 600-369, Segment 4 Bare Ground and Crusted Soil Areas
 600-370, Segment 4 Debris Area #1
 600-371, Segment 4 Chalky Material Area
 600-372, Segment 4 Oil Stain and Filter Area #1
 600-373, Segment 4 Bare Ground and White Stain Area
 600-374, Segment 4 Drum Remnant Area
 600-375, Segment 4 Dry Cell Battery Debris Area #1
 600-376, Segment 4 Stained Soil Area #2
 600-377, Segment 4 Oil Stain and Filter Area #2
 600-378, 506 Telephone Exchange Emergency Generator Building Underground Fuel Storage tank
 600-379, Segment 4 Burn Area #1.

The Reclassification to Final Closed Out applies to all subsites associated with the waste sites listed above.

Code: 600-329	Classification: Accepted
Names: 600-329; Concrete Outfall Structure	Reclassification: None
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: This site consists of the an unknown concrete structure underlying soils near the Construction Shop of the Hanford Town-site operations, on the high water line of river the edge.

Location: The site is an concrete structure near the Construction Shop of the Hanford Town-site operations. The location of this site is approximately 2 kilometers northwest of intersection Route 2 North and Route 11A. The coordinates for the site are E586323.755, N139532.792.

Process Description: This site appears to be related to the movement of water (spillway from possible storm drain).

Code: 600-331	Classification: Accepted
Names: 600-331; Lime Sulfur Barrel Site	Reclassification: Final Closed Out (6/27/2015)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The site has been remediated and Closed Out. It was the location of the lime sulfur barrel that had deteriorated and collapsed The site consisted of the underlying soil that was the previous

location of the lime sulfur barrel location (UPR-600-19). The lime sulfur barrel site was removed and reclassified to Rejected in 1997. Soil sample data (Hanford Environmental Information System (HEIS)) sample number B0MJ58 indicated that high levels of lead remained. A new sitecode was created (600-331) in 2009. Additional soil remediation was done in April 2014.

Location: The coordinates for the site are E582488.312, N142072.094. The site is located 402 meters (1320 ft) west of Route 2 North and approximately 183 m (600 ft) south of mile marker 3 at the old Herriford (Buckholdt Ranch) home site. The lime sulfur was located about 0.91 meters (3 ft) off the access road, approximately in front of the house foundation and southeast of the well house foundation.

Related Sites/ Structures: This site is located at a pre-Hanford Operations homestead, the Herriford (Buckoldt Ranch) home site and UPR-600-19.

Process Description: The site was an unplanned release. An old wooden barrel, that pre-dated Manhattan Engineering District (MED) operations, deteriorated and collapsed, spilling the contents (about 45 kilograms) [100 lbs] of powdery lime sulfur onto the ground. The area was abandoned in 1943 when the DeWitt Buckholdt Ranch was taken over by the U.S. Army Corps of Engineers. This site is located at a pre-Hanford Operations homestead, the Herriford (Buckoldt Ranch) home site.

Closure Info: Final (6/27/2015): Remedial action at the 600-331 waste site was performed over an area of 39 square meters (420 sq ft) on April 2, 2014. The maximum excavation depth was approximately 1.0 meter (3.3 ft). All stained and affected soil devoid of vegetation was directly loaded from the excavation into containers for disposal at ERDF. The approximate volume of material removed from the 600-331 waste site was 16 bank cubic meters (21 bank cubic yards). No anomalous materials were encountered during the excavation. There were no overburden piles or waste staging pile areas associated with the 600-331 waste site.

Code: 600-332

Classification: Accepted

Names: 600-332; Gable Mountain Firing Range Septic System

Reclassification: Final Closed Out (4/27/2015)

Type: Sanitary Sewer

Start Date:

Status: Inactive

End Date:

Description: The site was evaluated and Closed Out. It consisted of the underlying soil, septic tank, associated piping and drain field for a potential septic system. The Orphan Site's evaluation of historical features identified the septic system that supported the small arms firing range at Gable Mountain. A field investigation was conducted on 2/19/2008 to locate the potential septic system. Based upon the Photo # D-4882-NEG and the field investigation, a fence like object seen in the photo on the northwest side of the building could be a septic tank location. The Washington State Plane coordinates (E581080, N140937) are a potential location of the Firing Range Building, not the coordinates for the septic system shown in the photo. In May 2010, after analysis of a 1958 historic photograph (5380-PHOTO) and the satellite imagery for the area, a second potential location was established.

Location: The site is located in 600-149 (Small Arms Range), which did not previously identify this feature. 600-149 is located north of the east end of Gable Mountain. It is west of Route 2 North and the former Hanford Airport. The original coordinates (E581080, N140937) were an estimated location of the Range Building based upon photo # D-4882-NEG. The location of the 600-332 waste site was changed on May 5, 2010 after analysis of a 1958 historic photograph (5380-PHOTO) and the satellite imagery for the area.

Related Sites/ Structures: The site was related to the Range House which had been previously demolished (year unknown).

Process Description: The septic system supported the Range House building at the firing range, and this building was located on the opposite side of the access road from the firing ranges (HAN-10970 Volume IV). This was a septic tank, associated piping and drain field that supported the Range House building at the firing range. Hanford patrolmen were trained in the use of small arms (HAN-10970 Volume IV).

Waste Type: Equipment

Waste Description: The waste includes the septic tank, associated piping, and drain field underlying soil. There is no reference to a drain field, however it is assumed that one exists. Contaminants of potential concern include heavy metals.

Closure Info: Final (4/27/2015): A geophysical investigation, done in March 2010, found no anomalous features detected that had characteristics typically associated with either a septic tank, drain field, or its associated piping. To exhaust all possibilities that a septic tank existed, a 1 meter (3 ft) excavation was completed on October 12, 2014 at the location where the septic tank was thought to exist prior to the geophysical investigation. There were no anomalous materials, septic tank, or drain field encountered.

Code: 600-333 **Classification:** Accepted

Names: 600-333; Underground Concrete Structure **Reclassification:** Rejected (3/16/2011)

Type: Process Unit/Plant **Start Date:**

Status: Inactive **End Date:**

Description: The waste site consists of a below grade concrete structure with three vertical 0.5 by 0.5 meters (1.6 by 1.6 feet) shafts that are 2.4 meters (8 feet) deep and are open to the surface. The orphan sites evaluation team originally believed that the concrete structure was a septic tank that was associated with the former 101 Building graphic machining facility operations. Further investigation determined it was not a septic tank.

Location: The 600-333, Underground Concrete Structure waste site was located in the 100-IU-6 Operable Unit, near the site of the former 101 Building. The coordinates for the site are E584750.19, N140382.7.

Related Sites/ Structures: The structure is associated with the demolished 101 Graphite Machining Facility.

Process Description: On November 2, 2010, the site was evaluated and it was determined that the 600-333 concrete structure is not a septic tank. The concrete structure was observed to be very large in dimension. It extends deeper than 3.7 meters (12 feet) below ground surface, and is 9.8 meters (32 feet) long and 4.9 meters (16 feet) wide. A very large pipeline enters the east end of the concrete structure. There were no liquids, staining, or hazardous debris observed within the underground concrete structure. Due to the depth, size, and the nature of this concrete structure, no samples were collected from this waste site. The structure is suspected to be an underground facility rather than a septic tank.

Code: 600-334 **Classification:** Accepted

Names: 600-334; CMX Building **Reclassification:** Final Closed Out (8/13/2015)

Type: Process Unit/Plant **Start Date:** 9/1/1943

Status: Inactive**End Date:** 1/1/1945**Description:** This site consists of four areas divided into two subsites. Subsite 1 is three areas that include the CMX Building (Corrosion and Materials Experiment (CMX) Building; building 145) and two surface anomalies.

Subsite 2 consists of a burn area near CMX Building. Both subsites have been addressed so the Parent Site has been reclassified to Final Closed Out.

Subsite 1 has been evaluated and requires No Action.

Subsite 2 was reclassified to Final Closed Out in 2015.

Location: The site is located next to the bank of the Columbia River approximately 275 m (902 ft) upstream of the Hanford town site former ferry landing at the end of Division Street (C-127).**Process Description:** The CMX Building was constructed between June and September 1943. The original purpose of the facility was to perform experiments to determine the corrosion rate of reactor tubes and jackets under simulated operating conditions (IN-6263 Volume 1). The test equipment included six, 3.05 meters (10 ft) long aluminum tubes built according to the design specifications for the production piles. In early 1944, two of the tubes were replaced with full-length, 12.2 meters (40 ft) long pile tubes. Auxiliary facilities consisted of a water laboratory, a completely equipped dark-room for photographic work, water softening equipment used in steam generation and office with locker-room space (HAN-73214-14). The objective was to determine satisfactory treatment of the process water surrounding the aluminum reactor tubes and canned slugs to assure continuous reactor operations, without tube failures.

Although the initial purpose of CMX facility was to investigate corrosion of aluminum and evaluate equipment design, after a short period of operation iron and aluminum compounds were depositing on process equipment. The deposits were sufficiently heavy to cause a significant reduction in flow rate. This caused high slug surface temperatures under plant conditions. Therefore, the program was expanded to include a fundamental study of film formation and its removal. In addition, it was necessary to include the development of several analytical procedures to ensure the precision required for several determinations (HW-7-4444).

Columbia River water was supplied to the CMX Building by two 1,136 liters per minute (300 GPM), self-priming pumps mounted in a moveable shelter at the river's edge on the downstream side of the facility (HAN-73214-14). Alum or an alkali was added prior to being passed through closed settling tanks and sand filters. The water was further treated by passing through one of three treatment systems: a secondary filtered water treatment system, a deaerated water treatment system, or a demineralized water treatment system. These systems fed high-head pumps which produced 350 psi water to the process tubes. The treated water was also heated to the temperatures expected in pile operation.

Between September 1, 1943 and October 30, 1944 the optimum concentrations of critical anti-corrosion (sodium dichromate) and anti-scaling (sodium silicate) chemicals were tested and perfected. Other chemicals used in the process were sulfuric acid, which was used extensively in the building for pH adjustments, ferric sulfate which was used during the development of coagulants, oxalic acid which was used as a film removal agent, and hydrogen peroxide which was used during testing for film removal. Much of the piping was either rubber-lined or stainless steel. Five railroad locomotives were connected in parallel to a single header just northwest of the 145 Building to furnish 1,500 boiler hp and process/heating steam. Air for the instruments and lab was supplied by a steam-driven compressor. Electric power and light was obtained from the Hanford Construction Site system (DUH-11843, HW-7-4444). In June 1944, a flocculator (with agitator) and a 95,635 L (25,000 gal) clearwell were added to CMX to study the removal of iron and aluminum from river water.

Building 145 was shut down October 30, 1944, when the final CMX runs were concluded. The facilities remained in standby condition until January 1945 when satisfactory pile operations in 100-B and 100-D Areas had indicated that no major film or corrosion problems were to be anticipated. The equipment was subsequently dismantled and excessed (HAN-73214-14). Similar experimental work continued through the use of flow laboratories that were installed adjacent to the production piles.

Waste Type: Soil

Waste Description: The waste is potentially contaminated soil and abandoned in-ground piping. The contaminants of potential concern include sodium dichromate, ferric sulfate, lead (from sulfuric acid), mercury (from the sulfuric acid), sulfuric acid and petroleum products.

This Site has the Following SubSites:

Code: 600-334:1

Names: 600-334:1; CMX Building and Surface Anomalies

Code: 600-334:2

Names: 600-334:2; Burn area near CMX Building

Code: 600-334:1

Classification: Accepted

Names: 600-334:1; CMX Building and Surface Anomalies **Reclassification** Interim No Action (4/26/2011)

Type: Process Unit/Plant

Start Date:

Status: Inactive

End Date:

Description: The 600-334:1 subsite has been evaluated and determined to require No Action. It consisted of three areas. Area 1 is a raised footprint where the 145 Building Complex was once located. Area 2 is located on the northwest, upstream side of Area 1, It is a 5 by 5 meter (16 by 16 ft) depression that is approximately 1.5 meters (5 ft) deep. Area 3 is on the north side of Area 1 near the river. It consists of three open-ended outfall pipes that protrude horizontally from what appears to have been the middle of the CMX Building. Two of these are vitrified clay pipe, and the southernmost is stainless steel.

Location: This site is located next to the bank of the Columbia River approximately 275 m (902 ft) upstream of the Hanford town site former ferry landing at the end of Division Street (C-127).

Process Description: Refer to the parent waste site (600-334) for a process description of the 145 building complex.

The site was identified during the Orphan Site Evaluation field walkdowns for the 100-IU-2 and 100-IU-6 areas on May 10, 2007 (EL-1616, OSR-2008-0001). The two vitrified clay pipes were sewers were found. One was the sanitary sewer for the 145 building and the other was the process sewer used to return the treated water back to the Columbia River (M-2899). The purpose of the cast iron pipe is unknown. It was originally thought that the pipes may have carried contaminants from experimental procedures to the river.

Geophysics investigation GI# 0585886 was conducted at this site January 2008 using ground penetrating radar (GPR) and a high sensitivity metal detector (EM-61). The results found the footprint of the 145 building. It is relatively clear in the geophysical data. All three of the exposed pipes were traced from the riverbank to the eastern edge of the building, suggesting that they are associated with the building. Two additional linears features were identified that extend from the river bank to the building footprint.

Closure Info: Interim: Confirmatory sampling of the 600-334:1 subsite was initiated and performed in October 2010. Based on the confirmatory sample results, no remediation was performed at this site.

Samples were collected from one Test Pit, two Test Trenches and from an outfall pipe.

The SubSite is Part Of:

Code: 600-334

Names: 600-334; CMX Building

Code: 600-334:2

Classification: Accepted

Names: 600-334:2; Burn area near CMX Building

Reclassification: Final Closed Out (8/13/2015)

Type: Process Unit/Plant

Start Date:

Status: Inactive

End Date:

Description: Subsite 2 was reclassified to Final Closed Out in 2015, based on sample analysis data. It consists of a 4.6 meter (15 ft) diameter burn area of unknown origin, located near the northwest corner of the former Corrosion and Materials Experiment (CMX) Building complex.

Location: The burn site is located next to the bank of the Columbia River, approximately 275 meters (902 ft) upstream of the Hanford town site former ferry landing at the end of Division Street (C-127).

Process Description: The parent site was identified during the Orphan Site Evaluation field walkdowns for the 100-IU-2 and 100-IU-6 areas on May 10, 2007 (EL-1616, OSR-2008-0001). The nearest facility to the burn site was the CMX Building (Building 145). Refer to the parent waste site (600-334) for a process description of Building 145.

Closure Info: Final (8/13/2015): One focused soil sample was collected in October 2010. Field instrumentation capable of detecting alpha, beta, and gamma radiation was used during sampling. No radiological activity was detected in the field above background levels.

The SubSite is Part Of:

Code: 600-334

Names: 600-334; CMX Building

Code: JA JONES 1

Classification: Accepted

Names: JA JONES 1; JA Jones Construction Pit #1; JA Jones Dumping Pit #1; JA Jones 1

Reclassification: Interim Closed Out (11/8/2001)

Type: Dumping Area

Start Date: 1/1/1975

Status: Inactive

End Date: 1/1/1979

Description: The site has been remediated and Interim Closed Out. The site originally consisted of a trench dug from east to west, located on the west side of a depression and used by the J.A. Jones Company. The area was used for the disposal of miscellaneous debris and paint products.

Location: The JA Jones 1 site is located north of the 300 Area, east of the point where the railroad tracks cross Route 4 South, in the 100-IU-6 Operable Unit of the Hanford Site in southeastern Washington State.

Release Description: In 1980, 77 cubic meters (100 cubic yards) of contaminated soil excavated from the 305-B Berm were placed in this pit (see UPR-600-11). When the contamination was identified, the soil was removed from this pit and taken to the 200 Area for proper disposal.

Related Sites/Structures: This site is associated with UPR-600-11 which was an area within the JA Jones Pit #1 where contaminated material was mistakenly disposed. The contaminated material was removed in 1980 and the area released from radiological control. JA Jones 1 is also associated WIDS waste

site is 600-1, a trench located adjacent to and east of the JA Jones #1 Pit. It was used by the 300 Area Westinghouse facilities as a disposal site for tumbleweeds that collected from the 300 Area fences.

Process Description: This site was used by the JA Jones company for the disposal of miscellaneous debris, construction waste and paint products. An interview with an employee revealed that in 1977, seven to ten pick up truck loads of overstocked paint and solvents were disposed of in this pit. The containers were opened and the contents emptied onto the ground in the pit. The empty containers were then thrown into the pit.

Waste Type: Construction Debris

Waste Description: This site contains miscellaneous nonradioactive solid wastes from various construction sites. It contains wood scraps, concrete, miscellaneous construction wastes and paint products.

Waste Type: Chemical Release

Waste Description: In 1977, seven to ten pick up truck loads of over stocked paint and solvents were disposed of into a pit located north of the 300 Area. A site visit with the employee who dumped the paint indicates it was placed in the trench known as JA Jones Pit 1. He indicated that latex, epoxy and enamel paints, as well as paint thinners were discarded. He opened the containers (one and 5 gallon cans) and emptied the contents into the pit. He then threw the empty containers into the pit.

Waste Type: Misc. Trash and Debris

Waste Description: The site may contain some low level uranium contaminated materials. However, this information can not be confirmed because of the uncertainty the location where the material was dumped.

Closure Info: Interim: Remedial activities began in January 2001 and continued through March 2001. Approximately 12,700 metric tons (14,000 tons) of material was disposed of at the ERDF facility. Material excavated from the site included soil, concrete, construction-type debris, crushed paint cans, dried paint debris, sandblast material, and flame-retardant-like material. The excavation was approximately 2694 square meters with a maximum depth of 3.4 meters (12 feet). The site was backfilled and recontoured using clean soil and some concrete debris that had been excavated from the site. Excavation was driven by remedial action objectives for direct exposure, protection of groundwater, and protection of the Columbia River.

Radiological surveys and Industrial Hygienist monitoring was performed throughout the excavation process. With the exception of the suspect flame retardant, no radioactive material above background levels was identified for the excavated material, anomalous waste, or residual soil. Field instruments used for IH monitoring did not detect any organic vapors in the excavated material, anomalous waste, or residual soil. Visual observation of the excavated material did not identify any areas of discolored soil or concrete.

Code: UPR-600-11	Classification: Accepted
Names: UPR-600-11; Contaminated Soil Dumped at JA Jones Pit #1	Reclassification: Closed Out (1/27/1999)
Type: Unplanned Release	Start Date: 5/29/1980
Status: Inactive	End Date: 5/29/1980

Description: The site was declared Closed Out on Waste Site Reclassification form 98-215, signed in 1999. It was an area within the JA Jones Pit #1 where contaminated material was mistakenly disposed. The contaminated material was removed in 1980 and the area released from radiological control. There is no visual evidence of this occurrence. A Remedial Action was

done at this site in 2001.

Location: The release occurred in the JA Jones Pit #1, which is located about 1.2 kilometers (2 miles) north of 300 Area.

Release Description: On May 29, 1980, during a routine radiological survey, low-level beta-gamma contamination (approximately 600 counts per minute) was detected in a small amount of discarded blacktop rubble laying on the south end of the 305-B Berm. Some of the contaminated blacktop had mixed with the disturbed earthwork. JA Jones subcontractor workers had excavated 76.5 cubic meters (100 cubic yards) of soil from the 305-B Berm, which was thought to be uncontaminated, and taken it to the JA Jones Pit #1 before the contamination was detected. The JA Jones Pit #1 was designated as a non-radioactive landfill. Work was stopped immediately and the appropriate personnel were notified.

Related Sites/Structures: UPR-600-11 was associated with the 305-B Berm (WIDS Sitecode 300-29) and the JA Jones Pit #1 (WIDS Sitecode JA Jones 1).

Waste Type: Soil

Waste Description: The waste included soil and blacktop rubble. Surveys of the blacktop rubble revealed contamination with a maximum reading of 1000 counts per minute. Soil at the dump site had readings of less than 200 counts per minute. This is believed to be the field instrument detection limit. Blacktop and soil samples (quantity unknown) were collected for a laboratory counting. The blacktop had a maximum reading of 600 counts per minute natural uranium. The soil measured at less than detectable.

Closure Info: Interim: The site was declared Closed Out on Waste Site Reclassification form 98-215, signed in 1999.

Following the discovery of the contaminated material in May 1980, the two affected areas (the 305-B Berm and the JA Jones dump site) were roped off, surveyed and posted as radiation zones. The subcontractor personnel and equipment were carefully surveyed and found to be free of contamination. The subcontractor personnel were given whole body and lung counts. All were found to be below detection levels. The contaminated soil dumped into the JA Jones pit was removed and taken to the 200 Area for disposal in 1980. Further soil excavation at the 305-B Berm was closely surveyed by a radiation monitor. The event resulted in 77 cubic meters (100 cubic yards) of contaminated soil needing proper disposal.

The unplanned release was also evaluated in the Cleanup Verification Package for the JA Jones 1 site (CVP-2001-00019).

Remedial Action at the JA Jones 1 site began on January 8, 2001. The lowest elevation of the bottom of the excavation was approximately 112.6 meters (369.4 ft) upon completion. The excavation was approximately 2,694 square meters (29,000 sq. ft.) in area with a maximum depth of approximately 3.4 meters (11.2 ft). The excavation was completed on March 6, 2001. Approximately 12,700 metric tons (14,000 tons) of material from the site were disposed of at ERDF.

Material excavated from the site included soil, concrete, construction-type debris, crushed paint cans, dried paint debris, sandblast material, and flame-retardant-like material. No liquid wastes were encountered during excavation. Clean overlying and co-mingled soil that was segregated during the excavation process was stockpiled at the site for potential use as backfill. Based on agreement between the U.S. Environmental Protection Agency (EPA) and the U.S. Department of Energy Unit Managers, large pieces of concrete debris will be used to partially backfill the site excavation. Approximately 38 cubic meters (50 yd) of concrete debris, with individual pieces as large as 1.2 meters by 2.4 meters by 0.6 meters (4 ft by 8 ft by 2 ft), were used to partially backfill the site excavation. Samples collected from the concrete indicate that the concrete is an inert demolition-type debris.

Code: UPR-600-16 **Classification:** Accepted
Names: UPR-600-16; P-11 Fire and Contamination **Reclassification:** Interim Closed Out (10/28/2008)
 Spread; UN-600-16; UN-616-16
Type: Unplanned Release **Start Date:** 1/1/1951
Status: Inactive **End Date:**

Description: The waste site has been Interim Closed Out. The fire and resulting contamination spread unplanned release occurred on December 4, 1951, when plutonium contamination was spread by a fire that ignited inside the 120 Experimental Building. The area was a flat, featureless field that has been sown with rye grass. The P-11 Laboratory structure had been removed but its location is marked with a permanent concrete benchmark.

Location: The 120 Building was located approximately 4.8 kilometers (3 miles) southeast of 100-F Area, approximately 0.48 kilometers (0.3 mile) west of Route 2 North.

Release Description: The P-11 Facility was a laboratory for plutonium criticality studies. In November 1951, a criticality excursion resulted in extensive plutonium contamination inside the laboratory building (120 Building). Activities in the laboratory were suspended to conduct decontamination work. On December 4, 1951 decontamination was in the final stages when a spontaneous ignition of decontamination materials caused a fire that gutted the entire building. Plutonium contamination was spread by the fire and also washed into the soil by the waster used to extinguish the fire. The area was stabilized with clean soil and gravel to prevent wind from spreading the contamination further. The 120 Building and its crib were removed in 1974 and the area was released from radiological posting.

Related Sites/ Structures: The site was associated with the 120 Building and the P-11 Crib (site code 600-111).

Waste Type: Ash

Waste Description: An estimated amount of 1 to 4 grams (0.035 to 0.14 ounces) of plutonium was deposited over an area approximately 1,660 square meters (18,000 square feet) from a structure fire in 1951.

Closure Info: Interim: Confirmatory sampling from test pits and trenches was performed from April 29 2004 through May 10, 2004. To track results of confirmatory sampling, the P-11 lab complex waste site was stratified into the following seven areas for evaluation and sample collection. Area 1 was the Former 120 Experimental Building location, Area 2 was the Former P-11 Crib location, Area 3 was the Former 123 Control Building location, Area 4 was the Geophysical anomaly, Area 5 was the Septic Drain Field, Area 6 was the Septic Tank and Area 7 was the Surface Depression. Results of confirmatory sampling at Areas 1, 2,3 and radiological surveys at UPR-600-16 determined no action was required. Confirmatory samples from Areas 5 and 6 found elevated levels of PCB's, arsenic cadmium and lead.

Some minimal radioactivity was detected, but the RESRAD modeling determined the dose rare for all pathways was less than 15 millirem per year.

Remedial action of the septic system tank and drain field (Areas 5 and 6) located at 600-111 was performed between February 25, 2008 and March 25, 2008. The site was excavated to approximately 4.6 meters (15 ft) below grade (at the deepest portion), resulting in a combined volume of approximately 2,755 cubic meters (3,603 cu. yd) of material removed and disposed at the Environmental Restoration Disposal Facility. Verification soil samples for the septic system remediation were collected on April 21, 2008.

All test pits/trenches were excavated and sampled in late April 2004 through early May 2004 as

specified in the sampling work instruction. During excavation, field monitoring for VOCs was performed and no constituents were detected. In addition, FIDLER radiological surveys were performed during the excavations. No radiological contamination above twice the background level was found.

100-KR-1

Code: 100-K-57 **Classification:** Accepted
Names: 100-K-57; 107-KE Drainage Ditches **Reclassification:** None
Type: Ditch **Start Date:** 1/1/1967
Status: Inactive **End Date:** 1/1/1971

Description: The site appears as a dry, shallow ditch which extends from the 116-K-3 (1904-K Outfall Structure) and the 116-K-1 Crib. A second ditch extends from the culvert to the Columbia River. The culvert conveyed process effluent leakage from the area surrounding the 107-KE Basins under the road and to the ditch. The two ditches intersect below the bank located just north of the basins. The ditch at the bottom of the bank is approximately 300 meters (980 feet) long and 2 meters (6.6 feet) wide and the ditch leading from the culvert to the river is approximately 270 meters (890 feet) long and the width is generally 2 meters (6.6 feet) wide but widens significantly in the middle section. The southern portion of the ditch is located in an area posted as a "Soil Contamination Area." The ditch is barricaded from the river by a three strand barbed wire fence and is posted with "Keep Out" signs.

Location: The site is located north of 100-K Area, north of the 107-KE Retention Basins. It is between the Columbia River and security road inside the 100 KE Flood Plain (sitecode 100-K-64). It is inside the boundaries of the 100-K-64 radiologically posted area.

Related Sites/ Structures: The drainage ditch received process effluent from the 107-KE Retention Basins. It is associated with 100-K-64 flood plain.

Waste Type: Process Effluent

Waste Description: The site received process effluent from the 107-KE Retention Basins when the site was active.

Waste Type: Soil

Waste Description: The soil in and around the ditch is contaminated with radionuclides as a result of conveying reactor process effluent to the river.

Code: 100-K-63 **Classification:** Accepted
Names: 100-K-63; 100-KW Flood Plain Contamination Area; 100-KW Floodplain; UN-116-KW-1 **Reclassification:** Interim Closed Out (9/7/2012)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The waste site has been remediated and Interim Closed Out. It was a large portion on the flood plain, along the shore of the Columbia River, north of 100-K West Reactor Area. It was posted as a radiological contamination area. Most of it was posted as an Underground Radioactive Material Area, but there were two sections that were Soil Contamination Areas. The waste site also included four culverts that discharged directly into the flood plain that were removed during remediation activities.

Location: The waste site is located along the Columbia River shoreline, north of the 107-KW Basins. Significant quantities of the leakage accumulated on the floodplain over time and created preferential pathways through the natural topography of the site. The effluent concentrated in natural depressions, creating areas with potentially increased levels of contamination. Historical photographs taken during the operating period of the 107-KW Retention Basins show increased

vegetation within the 100-K-63 Waste Site due to the periods of significant effluent leakage from the basins, which overflowed from the open drainage ditches and spread over the floodplain area.

Release Description: The 107-KW Basins developed leaks over time. Leaks were estimated to be as great as 18,900 to 75,700 liters/minute (5,000 to 20,000 gallons/minute). A metal culvert to an open ditch diverted the water to the river shoreline.

Related Sites/ Structures: The 116-KW-3 (107-KW Basins) are related to this site.

Process Description: During reactor operations the 107-KW Retention Basins received cooling water effluent from the 105-KW Reactor to allow for radioactive decay and thermal cooling prior to release to the Columbia River. The 107-KW Retention Basins and their effluent lines developed leaks during their operating life. Most of the leakage was diverted to metal culverts, conveying the effluent to an open drainage ditch through the floodplain, which discharged to the Columbia River.

Closure Info: Interim (9/7/2012): Remediation of the 100-K-63 waste site began in July 2010 and was completed by November 2010. The remediation was conducted with a maximum excavation depth of 4.05 meters (13.3 ft). Radiological surveys of the waste site and in-process samples were used to guide the excavation. All of the areas with elevated radiological readings were remediated. No staining or other visible identifiers which would indicate a need for further remediation were observed. Concurrent with excavation of the waste site, thirty-one discrete and composite surface in-process samples were collected within the excavation area. To evaluate the un-excavated portion of the waste site, pothole sampling was performed at 18 locations. The potholing resulted in an additional forty-six samples, with sample depths ranging from surface to 2.67 meters (14 ft) below ground surface. The sample locations in the unexcavated portion of the waste site were focused in low-lying depressions, channels, and soil erosion locations caused by effluent discharges, which had the greatest potential for contaminant accumulation. Four culverts that discharged directly into the flood plain were also removed.

During active excavation of the waste site on September 23, 2010, there was an inadvertent discovery of cultural material. Work at the 100-K-63 Waste Site was suspended for a cultural resources impact assessment. The maximum excavation depth of 4.6 meters (15 ft) below grade surface was agreed to with cultural resource experts in consult with the Tribes.

All contaminated soils and structures (approximately 85,431 tons) removed as part of the remediation were disposed of at the Environmental Restoration Disposal Facility (ERDF). A fiber mulch was applied to prevent further erosion of the excavated waste site area after sampling. Interim backfill was completed in October of 2011. Interim revegetation was completed in February of 2012.

Code: 100-K-64 **Classification:** Accepted

Names: 100-K-64; 100-KE Flood Plain Contamination Area; 100-KE Floodplain; UN-116-KE-1 **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The site is the portion of the flood plain, along the shore of the Columbia River, north of 100-K East Reactor Area that is posted as a radiological contamination area, Soil Contamination Area and Underground Radioactive Material. It is inside an 8 foot chain link fence. The gate has an Underground Radioactive Material sign posted on it.

Location: The site is located north of the 107-KE Retention Basins, along the Columbia River shoreline,

just west of the 116-K-1 Crib.

Release Description: The 107-KE Basins and associated 1.5 meters (5 ft) diameter effluent pipelines, located less than 305 meters from the Columbia River, developed leaks over time. Leaks were estimated to be as great as 18,900 to 75,700 liters/minute (5,000 to 20,000 gallons/minute). A metal culvert to an open ditch diverted the water to the river shoreline. (see UPR-100-K-1)

Related Sites/Structures: The 116-KE-4 (107-KE Basins), UPR-100-K-1, 100-K-111 and the 100-K-57 Drainage Ditch are related to this site.

Process Description: The 107 retention basin tanks and associated 1.5 meters (5 ft) diameter effluent pipelines developed leaks during their operating life. The leakage rate from the butterfly valves (which conveyed flow to an adjacent trench) could have been as high as 18,930 to 37,850 liters/min (5,000 to 10,000 gal/min).

Code: 100-K-78

Classification: Accepted

Names: 100-K-78; Fenced Contamination Area

Reclassification: Interim No Action (4/6/2011)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The site has been evaluated and determined to require No Action. In April 2000, the site was enclosed within a post and chain area and posted with Contamination Area signs. Based on the sample results reported in the Remaining Sites Verification Package, the posting was removed.

Location: The site is located northeast of the 116-K-1 Crib.

Waste Type: Soil

Waste Description:

Closure Info: Interim: A surface radiological survey was performed at the 100-K-78 waste site on February 25, 2010. A sodium-iodide probe was used to collect information on potential contamination. Although the survey record notes direct beta/gamma readings up to 3.5 times background, no removable contamination above radiological control limits was present at the site.

Confirmatory sampling was performed at 100-K-78 on April 19 and November 5, 2010. During the first sampling event, two samples plus one duplicate were collected of surface soil. One sample was collected at a location previously identified as having the highest radiological readings at the site. The second sample and duplicate were collected from material composited from five locations within the waste site. Field instruments did not detect elevated radiological or organic vapor readings in the sample material.

During the second sampling event, a test pit was excavated near the center of the site. Soil samples were taken in approximate 0.8-meters (2.5-feet) intervals from the surface to 3 meters (10 feet) below ground surface (bgs). Excavated material from 2.1 meters (7 feet) bgs exhibited slightly elevated radiological readings. Background was noted as ~400 counts per minute (cpm); the material was reading ~550 cpm. This material was collected for the 1.5- to 2.3-meters (5.0- to 7.5-feet) bgs sample. No other elevated radiological or organic vapor readings were detected.

No debris, anomalous material, or stained soil was observed during sampling activities.

Code: 100-K-80

Classification: Accepted

Names: 100-K-80; 100KW River Effluent Pipeline;
100KW River Line; River Line (West) from 116-K-3 Outfall

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: 100-K-80 is a 213 centimeters (84 inches) diameter, carbon steel river effluent pipelines that extends from the face of 116-K-3 outfall structure to the Columbia River. The 100-K-96 pipeline runs parallel to 100-K-80. The pipelines are approximately 122 centimeters (48 inches) apart. In January 2012, the river effluent pipeline designations were split. The portion of the 100-K-80 pipeline that extends into the river was given a new WIDS sitecode (100-K-113).

Location: The 100-K-80 river pipeline is located on the Columbia River shore, adjacent to the 100K Area. It is west of the adjacent 100-K-96 pipeline.

Related Sites/ Structures: The pipeline site is associated with the 116-K-3 Outfall Structure, the 100-K-83 Spillway, the 100-K-47 process sewer, 100-K-56 process effluent lines, 100-K-55 process effluent lines, the 100-K-60 process sewer, the 116-KW-3 Retention Basins, the 100-K-96 river pipeline, and the 100-K-113 river pipeline.

Process Description: 105-KW reactor cooling water was collected and temporarily stored in the 107-KW Retention Basins. The cooling water was discharged to the river, bypassing (underneath) the 116-K-3 (1908-K) outfall structure, through the 100-K-80 river pipeline. Process sewer waste, from both 100-KE and 100-KW facilities, entered the outfall structure and dropped into the 100-KE river pipeline (see 100-K-96) through large-diameter, vertical standpipes welded onto the pipelines.

Retention basins lines (100-K-55 and 100-K-56) did not discharge through the outfall structure, but passed under it. They are a continuous line that become the river effluent pipelines downstream of the outfall structure. The pipelines discharge into a recessed, sloped riprap river bed structure, measuring 9 meters (30 feet) wide by 12 meters (40 feet) long and 1 meter (3 feet) thick. The total drop from the face of the outfall structure to the discharge end of the pipelines is 18 meters (60 feet).

In 1955, the river effluent pipelines began to float and break. Both lines were damaged. To remedy the problem, a 2 to 3 meter (6 to 10 feet) thick riprap jetty was placed over the lines from the shoreline to a point approximately 320 meters (1050 feet) from the face of the outfall structure.

Waste Type: Process Effluent

Waste Description: The waste includes the pipeline and the contaminated scale contained within it. The effluent included both reactor cooling water and process sewer waste. The Contaminants of Potential Concern are based on the 116-K-3 outfall, and include Co-60, Cs-137, Eu-152, Eu-154, Pu-239/240, and Sr-90.

Code: 100-K-81

Classification: Accepted

Names: 100-K-81; Contamination Area West of 116-K-3

Reclassification: None

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The site consists of a large cylindrical piece of equipment (tank) surrounded by a rope and posted as Soil Contamination Area.

Location: The posted Soil Contamination area is adjacent to 116-K-3 Outfall Structure, approximately 6.1

meters (20 feet) west of the Outfall Structure fence. It is inside the boundaries of the 100-K-64 (Flood Plain) radiologically posted area.

Related Sites/ Structures: The site is associated with the 100-K-64 flood plain, 116-K-3 Outfall, 100-K-83 spillway, the 116-KE-4 and 116-KE-3 retention basins, the 100-K-55 and 100-K-56 process effluent lines, the 100-K-47 process sewer, and the 100-K-80 and 100-K-113 river effluent pipelines.

Process Description: The large cylindrical piece of equipment could be lowered into the top of the outfall structure. It was used to plug the outfall structure and prevent water from going through the structure.

Waste Type: Construction Debris

Waste Description: The Contaminants of Potential Concern include Co-60, Cs-137, Eu-152, Eu-154, Pu-239/240, and Sr-90.

Code: 100-K-83 **Classification:** Accepted

Names: 100-K-83; 116-K-3; 1904-K Flume; 1904-K Outfall Structure; 1904-K Spillway **Reclassification:** None

Type: Outfall **Start Date:**

Status: Inactive **End Date:**

Description: The 100-K-83 spillway (also referred to as a flume) was a combination of a three-sided, reinforced concrete trough beginning at the 116-K-3 Outfall, followed by an open earthen trench extending from the end of the concrete trough to the Columbia River shore.

Location: The concrete portion of the spillway exits the east side of the 116-K-3 Outfall, takes an immediate 45-degree turn in the downstream direction. An earthen trench continues in the same direction from that point to the river shoreline.

Related Sites/ Structures: The site is associated with 100-K-64 flood plain, 100-K-80, 100-K-96 (100-K River Effluent Pipelines) and 116-K-3 (1904-K) Outfall structure.

Process Description: The spillway was an alternate discharge point for the 116-K-3 Outfall structure. It was planned to be used only if the River Effluent Pipelines (sitecodes 100-K-80 and 100-K-96) were blocked, damaged, or undergoing maintenance. There is no corroborated physical or historical evidence that the spillway was ever used.

Waste Type: Construction Debris

Waste Description: If ever put into service, the COPCs for the 100-K-83 spillway would be the same as for the 116-K-3 outfall, including Cobalt-60, Cesium-137, Europium-152/154, Plutonium 239/240, and Strontium-90. There is no corroborated physical or historical evidence that the spillway was ever used.

Code: 100-K-86 **Classification:** Accepted

Names: 100-K-86; Four Areas of Stained Soil in 100-K Area; 100-K Stain Areas **Reclassification:** Interim Closed Out (12/5/2013)

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The site has been remediated and Interim Closed Out. It consisted of four areas with stained soil in and some surface debris.

Location: The coordinates locations for the areas are:

Area 1 - N568381.27 E146009.94
 Area 2 - N568923.50 E145541.86
 Area 3 - N568443.18 E145437.89
 Area 4 - N568848.48 E145301.50

Waste Type: Soil

Waste Description: The waste is potentially contaminated soil. There was no information describing the release of the observed materials.

Closure Info: Interim (12/5/2013): Waste sites 100-K-84, 100-K-86, 100-K-87, 100-K-91, 100-K-92, 100-K-95 were evaluated and reclassified as a group in the same RSVP document.

Remediation of the waste sites began in November 2012 and was concluded in June 2013. Due to elevated residual concentrations of contaminants after the initial remediation(s), additional remediation was required for the 100-K-84, 100-K-87, and 100-K-95 waste sites. All materials removed from the excavations were disposed at the Environmental Restoration Disposal Facility (ERDF) via direct load out. No staging pile areas were associated with the waste sites.

The excavation at the 100-K-84 waste site began on November 5, 2012, and concluded on March 14, 2013. Approximately 2,695 bank cubic meters (BCM) (3,525 bank cubic yards [BCY]) of soil and rock were removed and disposed at ERDF. The maximum depth of the excavation was approximately 0.91 meters (3 ft) bgs.

The excavation at the 100-K-86 waste site began on November 13, 2012, and concluded on January 22, 2013. Approximately 342 BCM (447 BCY) of debris, soil, and rock were removed and disposed at ERDF. The maximum depth of the excavation was approximately 1.5 meters (5 ft) bgs.

The excavation at the 100-K-87 waste site began on February 26, 2013, and concluded on April 3, 2013. Approximately 72 BCM (94 BCY) of debris, soil, and rock were removed and disposed at ERDF. The maximum depth of the excavation was approximately 0.91 meters (3 ft) bgs.

The excavation at the 100-K-91 waste site was conducted on November 28, 2012. Approximately 0.2 BCM (0.26 BCY) of suspect asbestos, soil, and rock were removed and disposed at ERDF. The maximum depth of the excavation was approximately 1.2 meters (4 ft) bgs.

The excavation at the 100-K-92 waste site began on November 13, 2012, and concluded on December 13, 2012. Approximately 32 BCM (42 BCY) of debris, soil, and rock were removed and disposed at ERDF. The maximum depth of the excavation was approximately 0.6 meters (2 ft) bgs.

The excavation at the 100-K-95 waste site began on January 8, 2013, and concluded on June 24, 2013. Approximately, 4,272 BCM (5,588 BCY) of soil and rock were removed and disposed at ERDF. The maximum depth of the excavation at the 100-K-95 waste site was approximately 1.5 meters (5 ft) bgs.

Code: 100-K-87

Classification: Accepted

Names: 100-K-87; 100-K Asbestos Lagging

Reclassification: Interim Closed Out (12/5/2013)

Type: Unplanned Release

Start Date:

Status: Inactive**End Date:****Description:** The site has been remediated and Interim Closed Out. It consisted of a 0.6 meter (2 ft) segment of suspected friable asbestos pipe lagging and any contaminated soil related to the asbestos.**Location:** The site was located approximately 285 meters (935 ft) south of the southern most corner of the 100-K perimeter fence, and approximately 440 meters (1440 ft) north of Route 1. The site was located approximately 15 meters (50 ft) outside the boundary of the 600-29 waste site (100-K Construction Lay-down Area). The Washington State Plane coordinates for the site are E568610.61 N145586.62.**Related Sites/
Structures:** 600-29 Construction Lay-Down Area**Waste Type:** Asbestos (friable)**Waste
Description:** The waste is soil with potential friable asbestos. The contaminant of potential concern is asbestos.**Closure Info:** Interim (12/5/2013): Waste sites 100-K-84, 100-K-86, 100-K-87, 100-K-91, 100-K-92, 100-K-95 were evaluated and reclassified as a group in the same RSVP document.

Remediation of the waste sites began in November 2012 and was concluded in June 2013. Due to elevated residual concentrations of contaminants after the initial remediation(s), additional remediation was required for the 100-K-84, 100-K-87, and 100-K-95 waste sites. All materials removed from the excavations were disposed at the Environmental Restoration Disposal Facility (ERDF) via direct load out. No staging pile areas were associated with the waste sites.

The excavation at the 100-K-84 waste site began on November 5, 2012, and concluded on March 14, 2013. Approximately 2,695 bank cubic meters (BCM) (3,525 bank cubic yards [BCY]) of soil and rock were removed and disposed at ERDF. The maximum depth of the excavation was approximately 0.91 meters (3 ft) bgs.

The excavation at the 100-K-86 waste site began on November 13, 2012, and concluded on January 22, 2013. Approximately 342 BCM (447 BCY) of debris, soil, and rock were removed and disposed at ERDF. The maximum depth of the excavation was approximately 1.5 meters (5 ft) bgs.

The excavation at the 100-K-87 waste site began on February 26, 2013, and concluded on April 3, 2013. Approximately 72 BCM (94 BCY) of debris, soil, and rock were removed and disposed at ERDF. The maximum depth of the excavation was approximately 0.91 meters (3 ft) bgs.

The excavation at the 100-K-91 waste site was conducted on November 28, 2012. Approximately 0.2 BCM (0.26 BCY) of suspect asbestos, soil, and rock were removed and disposed at ERDF. The maximum depth of the excavation was approximately 1.2 meters (4 ft) bgs.

The excavation at the 100-K-92 waste site began on November 13, 2012, and concluded on December 13, 2012. Approximately 32 BCM (42 BCY) of debris, soil, and rock were removed and disposed at ERDF. The maximum depth of the excavation was approximately 0.6 meters (2 ft) bgs.

The excavation at the 100-K-95 waste site began on January 8, 2013, and concluded on June 24, 2013. Approximately 4,272 BCM (5,588 BCY) of soil and rock were removed and disposed at ERDF. The maximum depth of the excavation at the 100-K-95 waste site was approximately 1.5 meters (5 ft) bgs.

Code: 100-K-88 **Classification:** Accepted
Names: 100-K-88; Yellow and White Granular Material **Reclassification** Interim No Action (4/6/2011)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The site consists of stained soil, scattered yellow granular material and the underlying soil. There is no vegetation within the release area.

Location: The site is located in the 100K Area in the 100-KR-1 Operable Unit. The site is located approximately 422 m (1,385 ft) north of Route 1 and approximately 25 m (82 ft) east of the access road to the 100-K pump and treat facility. The site is located approximately 75 m (250 ft) west of the boundary of the 600-29 waste site (100-K Construction Laydown Area). The site is located at Washington State Plane coordinates E 568356.47, N 145569.09.

Waste Type: Soil

Waste Description: The contaminants of potential concern are unknown. The waste is potentially contaminated soil.

Closure Info: Interim (4/6/2011): Confirmatory sampling was initiated and performed in November 2010. The confirmatory sampling results indicated that the waste site achieved compliance with the remedial action objectives (RAOs) and remedial action goals (RAGs), and remediation was not necessary. A summary of the cleanup evaluation for the soil results against the applicable criteria was presented in Table ES-1 of the RSVP. The results of the confirmatory sampling were used to make reclassification decisions for the waste site in accordance with the TPA-MP-14 procedure in the Tri-Party Agreement Handbook Management Procedures (RL-TPA-90-0001, rev. 1).

Code: 100-K-90 **Classification:** Accepted
Names: 100-K-90; 100-K White Granular Material **Reclassification** Interim No Action (4/6/2011)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The site consists of white granular material and the underlying soil. The vegetation at the site appears to be unaffected by the presence of the substance.

Location: The site is located in the 100K Area in the 100-KR-1 Operable Unit. The site is located approximately 365 m (1,200 ft) north of Route 1 and 32 m (105 ft) east of the access road to the 100 K pump and treat facility. The site is approximately 105 m (345 ft) west of the 600-29 waste site boundary (100-K Construction Lay-down Area). The Washington State Plane coordinates for the site are E 568347.54, N 145512.27.

Closure Info: Interim: In November 2010 a focused sampling approach was used to evaluate the white granular material at 100-K-90 and determine if there is any soil contamination due to its presence (WCH 2010b). One shallow soil sample (0 to 0.15 meters [0 to 6 in.] below ground surface) and one duplicate soil sample were collected from the waste site. No radiological activity or volatile organic compounds (VOCs) were detected during confirmatory sampling. Furthermore, no stained soil or anomalous material was observed during sampling. Analysis was performed to evaluate if contamination associated with the white granular material was present. Confirmatory sampling at the 100-K-90 waste site indicated that environmental contamination above cleanup levels was not present, and remedial action was not necessary.

The confirmatory sampling data has been used for a No Action determination.

Code: 100-K-91	Classification: Accepted
Names: 100-K-91; 100-K Battery	Reclassification: Interim Closed Out (12/5/2013)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The site has been remediated and Interim Closed Out. It consisted of one intact, partially buried, vehicle battery and the underlying soil. The surrounding vegetation appears to be unaffected by its presence.

Location: The site is located off of an unpaved secondary road west of the 100 K operable unit. Traveling west on Route 1 from the intersection with K Avenue proceed 2.3 km (1.4 m) to the unpaved road on the right. Turn right and travel approximately 355 meters (1165 ft). The site is located approximately 33 meters (110 ft) east of the road in an open area. The Washington State Plane coordinates are E567290.29 N145486.16.

Process Description: The origin of this battery, whether from the pre-Hanford or Hanford eras, is unknown. It appears to have been random littering.

Waste Type: Batteries

Waste Description: The contaminants of potential concern may contain lead and possibly sulfuric acid in the soil. The waste is the battery and potentially contaminated soil.

Closure Info: Interim (12/5/2013): Waste sites 100-K-84, 100-K-86, 100-K-87, 100-K-91, 100-K-92, 100-K-95 were evaluated and reclassified as a group in the same RSVP document.

Remediation of the waste sites began in November 2012 and was concluded in June 2013. Due to elevated residual concentrations of contaminants after the initial remediation(s), additional remediation was required for the 100-K-84, 100-K-87, and 100-K-95 waste sites. All materials removed from the excavations were disposed at the Environmental Restoration Disposal Facility (ERDF) via direct load out. No staging pile areas were associated with the waste sites.

The excavation at the 100-K-84 waste site began on November 5, 2012, and concluded on March 14, 2013. Approximately 2,695 bank cubic meters (BCM) (3,525 bank cubic yards [BCY]) of soil and rock were removed and disposed at ERDF. The maximum depth of the excavation was approximately 0.91 meters (3 ft) bgs.

The excavation at the 100-K-86 waste site began on November 13, 2012, and concluded on January 22, 2013. Approximately 342 BCM (447 BCY) of debris, soil, and rock were removed and disposed at ERDF. The maximum depth of the excavation was approximately 1.5 meters (5 ft) bgs.

The excavation at the 100-K-87 waste site began on February 26, 2013, and concluded on April 3, 2013. Approximately 72 BCM (94 BCY) of debris, soil, and rock were removed and disposed at ERDF. The maximum depth of the excavation was approximately 0.91 meters (3 ft) bgs.

The excavation at the 100-K-91 waste site was conducted on November 28, 2012. Approximately 0.2 BCM (0.26 BCY) of suspect asbestos, soil, and rock were removed and disposed at ERDF. The maximum depth of the excavation was approximately 1.2 meters (4 ft) bgs.

The excavation at the 100-K-92 waste site began on November 13, 2012, and concluded on December 13, 2012. Approximately 32 BCM (42 BCY) of debris, soil, and rock were removed and disposed at ERDF. The maximum depth of the excavation was approximately 0.6 meters (2 ft) bgs.

The excavation at the 100-K-95 waste site began on January 8, 2013, and concluded on June 24, 2013. Approximately 4,272 BCM (5,588 BCY) of soil and rock were removed and disposed at ERDF. The maximum depth of the excavation at the 100-K-95 waste site was approximately 1.5 meters (5 ft) bgs.

Code: 100-K-92	Classification: Accepted
Names: 100-K-92; 100-K Reddish Stained Gravels	Reclassification: Interim Closed Out (12/5/2013)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The site has been remediated and Interim Closed Out. It consisted of two areas containing reddish crusted soil and the underlying soil. Area 1 was reddish crusted soil indicating that a liquid may have been dumped to the ground. There is little or no vegetation growing in the stained area. Area 2 was reddish stained soil, metal debris and the remnants of a crushed drum. There is little or no vegetation growing in the affected area.

Location: The Washington State Plane coordinates are:

Area 1 - E568334.35 N145456.30

Area 2 - E568355.99 N145418.29

These areas were outside the 100-K perimeter fence.

**Related Sites/
Structures:** 100-K-84

**Process
Description:** It is suspected that this material is similar to that of 100-K-84 which was described as: crushed iron ore, a component of the concrete used in reactor and other facility construction because it provided additional shielding. The material is highly magnetic.

Waste Type: Construction Debris

**Waste
Description:** The waste is the spilled/abandoned red material.

Closure Info: Interim (12/5/2013): Waste sites 100-K-84, 100-K-86, 100-K-87, 100-K-91, 100-K-92, 100-K-95 were evaluated and reclassified as a group in the same RSVP document.

Remediation of the waste sites began in November 2012 and was concluded in June 2013. Due to elevated residual concentrations of contaminants after the initial remediation(s), additional remediation was required for the 100-K-84, 100-K-87, and 100-K-95 waste sites. All materials removed from the excavations were disposed at the Environmental Restoration Disposal Facility (ERDF) via direct load out. No staging pile areas were associated with the waste sites.

The excavation at the 100-K-84 waste site began on November 5, 2012, and concluded on March 14, 2013. Approximately 2,695 bank cubic meters (BCM) (3,525 bank cubic yards [BCY]) of soil and rock were removed and disposed at ERDF. The maximum depth of the excavation was approximately 0.91 meters (3 ft) bgs.

The excavation at the 100-K-86 waste site began on November 13, 2012, and concluded on

January 22, 2013. Approximately 342 BCM (447 BCY) of debris, soil, and rock were removed and disposed at ERDF. The maximum depth of the excavation was approximately 1.5 meters (5 ft) bgs.

The excavation at the 100-K-87 waste site began on February 26, 2013, and concluded on April 3, 2013. Approximately 72 BCM (94 BCY) of debris, soil, and rock were removed and disposed at ERDF. The maximum depth of the excavation was approximately 0.91 meters (3 ft) bgs.

The excavation at the 100-K-91 waste site was conducted on November 28, 2012. Approximately 0.2 BCM (0.26 BCY) of suspect asbestos, soil, and rock were removed and disposed at ERDF. The maximum depth of the excavation was approximately 1.2 meters (4 ft) bgs.

The excavation at the 100-K-92 waste site began on November 13, 2012, and concluded on December 13, 2012. Approximately 32 BCM (42 BCY) of debris, soil, and rock were removed and disposed at ERDF. The maximum depth of the excavation was approximately 0.6 meters (2 ft) bgs.

The excavation at the 100-K-95 waste site began on January 8, 2013, and concluded on June 24, 2013. Approximately, 4,272 BCM (5,588 BCY) of soil and rock were removed and disposed at ERDF. The maximum depth of the excavation at the 100-K-95 waste site was approximately 1.5 meters (5 ft) bgs.

Code:	100-K-93	Classification:	Accepted
Names:	100-K-93; 100-K Drum Remnant	Reclassification	Consolidated (12/17/2013)
Type:	Unplanned Release	Start Date:	
Status:	Inactive	End Date:	
Description:	The site has been evaluated and reclassified to Consolidated with the 100-K-111 waste site. It consisted of a 208 liter (55 gal) drum remnant with approximately 0.03 cubic meters (1 cu. ft) of solidified gray/black tar like substance and the underlying soil. The drum tar-like material and underlying soil were removed in November 2012. The 0.5 bank cubic meters of material was disposed at ERDF. Cleanup verification samples were collected in February 2103. The sample results contained elevated levels of total chromium and hexavalent chromium. The chromium contamination was determined not to be associated with the drum remnant. Therefore, the residual contaminated soil is being consolidated with the 100-K-111 waste site (see WSRF 2013-063).		
Location:	The site is located approximately 162 meters (530 ft) north of the 116-K-1 crib and 610 meters (2000 ft) northeast of the 181 KE river pump house. The site is approximately 90 meters (300 ft) from the Columbia River. The site is located at Washington State Plane coordinates E569226.34/N147476.24. It is located within the boundaries of waste site 100-K-111.		
Related Sites/ Structures:	100-K-111		
Waste Type:	Sludge		
Waste Description:	The waste is the abandoned drum, tar like substance, and any contaminated soil.		
<u>This Site Was Consolidated With:</u>			

Code: 100-K-111
Names: 100-K-111; Effluent Seepage Area from 116-K-2

Code: 100-K-94 **Classification:** Accepted

Names: 100-K-94; 1702-KE and 1702-KW Guard House
 Dry Wells **Reclassification:** None

Type: French Drain **Start Date:**

Status: Inactive **End Date:**

Description: There are two identical dry wells, one at the 1702-KE guard house and one at the 1702-KW guard house. Each 76 centimeter (30 inch) dry well received drinking water through a 7.6 centimeter (3 inch) cast iron pipe that exited guard houses.

Location: The dry well associated with 1702-KE is approximately north of the facility, centered at Washington State Plane coordinates E 569083.43, N 146600.77. The dry well associated with 1702-KW is approximately north of the facility, centered at Washington State Plane coordinates E 568808.6, N 146453.6.

Process Description: Excess drinking water effluent flowed from the drinking fountain in each guard house through underground piping to the dry well.

Waste Type: Water

Waste Description: No evidence of hazardous or dangerous waste being discharged to these sites was discovered. The waste was excess (unconsumed) water coming from the drinking fountains at both guard houses.

Code: 100-K-95 **Classification:** Accepted

Names: 100-K-95; 100-K Tar Dump **Reclassification:** Interim Closed Out (12/5/2013)

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: This waste site has been remediated and Interim Closed Out. It consisted of a large area, approximately 150 meters (500 ft) in diameter, of scattered tar and the underlying contaminated soil. A field walkdown of the site was conducted on July 07, 2008.

Location: The site was located in the 100K Area at coordinates E569072.38 N145469.5. It was about 60 meters (200 feet) south of the 600-29 Construction Lay-down Area. The nearest maintained road is 270 meters (900 ft) away.

Related Sites/ Structures: Associated with 600-29. Analogous sites include 600-280 and 600-190.

Process Description: These tar dumps, located south of the 600-29 Construction Lay-down Area, probably occurred as a way of disposing of excess oil and tar during 100-K Area Construction.

Waste Type: Construction Debris

Waste Description: The waste is construction debris. The contaminants of potential concern consist of PAHs and PCBs.

Closure Info: Interim (12/5/2013): Waste sites 100-K-84, 100-K-86, 100-K-87, 100-K-91, 100-K-92, 100-K-95 were evaluated and reclassified as a group in the same RSVP document.

Remediation of the waste sites began in November 2012 and was concluded in June 2013. Due to elevated residual concentrations of contaminants after the initial remediation(s), additional remediation was required for the 100-K-84, 100-K-87, and 100-K-95 waste sites. All materials removed from the excavations were disposed at the Environmental Restoration Disposal Facility (ERDF) via direct load out. No staging pile areas were associated with the waste sites.

The excavation at the 100-K-84 waste site began on November 5, 2012, and concluded on March 14, 2013. Approximately 2,695 bank cubic meters (BCM) (3,525 bank cubic yards [BCY]) of soil and rock were removed and disposed at ERDF. The maximum depth of the excavation was approximately 0.91 meters (3 ft) bgs.

The excavation at the 100-K-86 waste site began on November 13, 2012, and concluded on January 22, 2013. Approximately 342 BCM (447 BCY) of debris, soil, and rock were removed and disposed at ERDF. The maximum depth of the excavation was approximately 1.5 meters (5 ft) bgs.

The excavation at the 100-K-87 waste site began on February 26, 2013, and concluded on April 3, 2013. Approximately 72 BCM (94 BCY) of debris, soil, and rock were removed and disposed at ERDF. The maximum depth of the excavation was approximately 0.91 meters (3 ft) bgs.

The excavation at the 100-K-91 waste site was conducted on November 28, 2012. Approximately 0.2 BCM (0.26 BCY) of suspect asbestos, soil, and rock were removed and disposed at ERDF. The maximum depth of the excavation was approximately 1.2 meters (4 ft) bgs.

The excavation at the 100-K-92 waste site began on November 13, 2012, and concluded on December 13, 2012. Approximately 32 BCM (42 BCY) of debris, soil, and rock were removed and disposed at ERDF. The maximum depth of the excavation was approximately 0.6 meters (2 ft) bgs.

The excavation at the 100-K-95 waste site began on January 8, 2013, and concluded on June 24, 2013. Approximately 4,272 BCM (5,588 BCY) of soil and rock were removed and disposed at ERDF. The maximum depth of the excavation at the 100-K-95 waste site was approximately 1.5 meters (5 ft) bgs.

Code: 100-K-99	Classification: Accepted
Names: 100-K-99; 116-KE-4 Contaminated Soil and Items; Radioactive Material Area Remaining After 107-KE Basin Removal	Reclassification: None
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:
Description: On August 25, 2009, while constructing the 100K Container Transfer Area north of 105-KE, the equipment operator unearthed radioactive contaminated material while excavating. The radioactive material was Griffon material. This material was typically used to wrap contaminated items. The 107-KE Retention Basins had been located in this area, but were removed in 1995 (see sitecode 116-KE-4).	
Location: The site is located north of the 105-KE Reactor building, inside the 100-K fence.	
Related Sites/ Structures: The waste site is associated with 116-KE-4.	

Waste Type: Misc. Trash and Debris

Waste Description: Radioactively contaminated soil, Griffon material and a concrete block was found while excavating an area adjacent to the remediated 116-KE-4 basins. 24,000 dpm per 100 centimeters (squared) beta/gamma was found on the Griffon material. 6,000 dpm per 100 centimeters (squared) beta/gamma was found on the soil around the concrete block.

Code: 100-K-100

Classification: Accepted

Names: 100-K-100; 116-KW-3 Remaining Contaminated Soil and Items; Radioactive Material Area Remaining After 107-KW Basin Removal

Reclassification: None

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The waste site is the discovery of potential contaminated soil and material adjacent to the remediation area. The 107-KW Retention Basins had been located in this area, but were removed in 1995 (see sitecode 116-KW-3).

Location: The site is located north of the 105-KW Reactor building, inside the 100-K Area fence.

Code: 116-K-1

Classification: Accepted

Names: 116-K-1; 116-K-1 Trench; 100-K Crib; 100-K Emergency Pond; 100-K Pond; 107-K Pond; 107-K(E) Sump

Reclassification: Interim Closed Out (5/17/2004)

Type: Crib

Start Date: 1/1/1955

Status: Inactive

End Date: 1/1/1956

Description: The site has been remediated and Interim Closed Out.

Location: The site was northeast of 116-KE-4 (107-KE Retention Basins).

Related Sites/Structures: The crib was related to the 107-KE/KW Retention Basins (116-KE-4, 116-KW-3). The crib received cooling water from the reactor via 100-K-55 and 100-K-56 cooling water effluent pipelines.

Process Description: The unit was a structure within a structure, the dimensions were 61 meters (200 feet) by 61 meters (200 feet) at the bottom and 122 meters (400 feet) by 122 meters (400 feet) at the top of diked sides. The inner structure rested within a sand-filled excavation that was 3 meters (10 feet) wide at the sides, 3 meters (10 feet) deep (parallel to the excavation) with 0.3-meter (1-foot) of underlying gravel. Both the inner and outer structures had a side slope ratio of 4:1. The 41-centimeter (16-inch) sewer entered 8 meters (27 feet) below the top of grade. A 107-centimeter (42-inch) drain line entered north of the 41-centimeter (16-inch) line, and 6 meters (20 feet) below the top of the structure. The natural ground elevation was 406 feet (124 meters) above mean sea level (MSL). An earthen dike with a slope ratio of 4:1 surrounded the unit from 2.1 meters (7 feet) below grade (bottom of outer structure) to 8 meters (26 feet) above the natural ground surface (top of structure). A 0.6-meter (2-foot) layer of riprap surrounded the earthen dike from natural grade to 3.4 meters (11 feet) above grade.

Waste Type: Process Effluent

Waste Description: The site received reactor coolant water from the 107-K Retention Basins during reactor outages due to fuel ruptures. The site received 107-K Basin cleanout slurry from February 1955 to May 1956.

Closure Info: Interim: Remedial action at the 116-K-1 site began in September 2003. Excavation of the site involved removing the overburden materials, crib structure, and underlying contaminated soil. Contaminated materials were disposed of at ERDF. The area to the northeast is likely the area where the washout of the crib occurred.

Portions of the 100-K-55 and 100-K-56 pipelines, located within the remedial excavation footprint of the 116-K-1 Crib, were removed during remediation of the 116-K-1 site. Excavations of these pipelines were terminated at the notched portion of the 116-K-1 Crib excavation along the southwest wall of the excavation. Final remediation of these pipelines will be included in a future CVP reports.

At the conclusion of excavation activities, the elevation of the bottom of the excavation was at approximately El. 124.1 meters (407 ft). The excavation was approximately 15,700 square meters (168,900 sq. ft.) in area, with a depth of approximately 11 meters (36 ft) as measured from the uphill or southern surface grade. Approximately 101,396 metric tons (111,536 tons) of material from the site were disposed of at ERDF.

Code:	116-K-2	Classification:	Accepted
Names:	116-K-2; 116-K-2 Trench; Bypass Crib Ditch; K Trench; 100-K Emergency Trench; 100-K Mile Long Trench; 107-K Effluent Trench	Reclassification	Interim Closed Out (3/28/2006)
Type:	Trench	Start Date:	1/1/1955
Status:	Inactive	End Date:	1/1/1971
Description:	The site has been remediated and Interim Closed Out. The site has been backfilled and stabilized using the original spoil piles that were located on either side of the trench.		
Location:	The site was located northeast of 116-KE-4 (107-KE Retention Basins) and ran parallel to the river.		
Release Description:	During reactor operation, several washout areas were created along the river side of the unit. The unit was at a much higher elevation than the area between it and the Columbia River. The washout areas resulted from extensive seepage through the north side of the unit, which ran along the surface of the ground until reaching the river (See 100-K-111).		
Related Sites/Structures:	The site was associated with 116-KE-4 and 116-KW-3 Retention Basins via the 100-K-55 and 100-K-56 pipelines. It is also associated with 100-K-111, Effluent Seepage Area from 116-K-2.		
Process Description:	The trench was fed by a 40.6 centimeter (16 inch) pipe that was part of the retention basin drain system. The trench was originally 1250 meters (4100 feet) long, 17.2 meters (56.5 feet) wide at the top, 1.2 meters (4 feet) wide at the bottom, and 5.3 meters (17.5 feet) deep. The side slope ratio was 1.5:1. The spoil piles on both sides of the trench originally had a top width of approximately 3.7 meters (12 feet). The site received all contaminated effluent from floor drains in the 105-KE and 105-KW Reactors, 105-KE and 105-KW Reactors metal storage basin overflow. Until 105-KE and 105-KW shut down around February 1, 1970, an undetermined amount of Retention Basin effluent leaked through 107-centimeter (42-inch) butterfly valves in the tank bottoms. Other periodic flows included low volume, neutralized, dummy decontamination waste, process-cooling water during charge/discharge; occasional special disposals; and occasional tanks of process cooling water that was collected after a fuel cladding failure. In 1972, a minor construction tractor and hydride tanks removed from 100-K Area facilities were buried in the trench. In 1978, the radioactive inventory at the site was calculated at 2,100 curies.		
Waste Type:	Process Effluent		

Waste Description: The site received all contaminated effluent from floor drains in the 105-KE and 105-KW Reactors (low volume) and approximately 1893 liters (500 gallons) per minute of 105-KE and 105-KW Reactors metal storage basin overflow. Until 105-KE and 105-KW shut down around February 1, 1970, an undetermined amount of Retention Basin effluent leaked through 107-centimeter (42-inch) butterfly valves in the tank bottoms. Leakage was estimated at 37,854 to 75,708 liters (10,000 to 20,000 gallons) per minute. The valve leakage showed a history of increase until the 1968 valve and tank renovation. Leakage gradually increased again after these repairs. Other periodic flows included low volume, neutralized, dummy decontamination waste, process-cooling water during charge/discharge; occasional special disposals; and occasional tanks of process cooling water that was collected after a fuel cladding failure. In 1972, a minor construction tractor and hydride tanks removed from 100-K Area facilities were buried in the trench. In 1978, the radioactive inventory at the site was calculated at 2,100 curies.

Closure Info: Interim: Remedial action activities were conducted from February 17, 2004, to October 27, 2005. Remediation involved excavation and staging of clean overburden material and removal of contaminated soil to the extent required to satisfy the RAOs and corresponding RAGs. A previously disposed construction tractor, a small amount of concrete and steel debris were also excavated at the western end of the former trench. The maximum depth of excavation was 7.6 meters (25 feet).

Approximately 55,540 square meters (597,830 square feet) of plan area was excavated, including excavation within the deep zone (greater than 4.6 meters [15 feet] below ground surface) up to 7.6 meters (25 feet) below ground surface. Approximately 410,000 metric tons (451,900 U.S. tons) of contaminated material from the site was removed and disposed at the ERDF.

The trench received liquid effluent waste via the retention basin drain system (100-K-55 and 100-K-56 pipelines). The liquid consisted of reactor cooling water effluent, overflow from the 105-KW and 105-KE Reactor Building fuel storage basins, contaminated liquid from the 105-KW and 105-KE Reactor Building floor drains, dummy decontamination waste, process cooling water following fuel cladding failures, and some special disposal. Up to 76,000 Liters per minute (20,000 gallons per minute) of leakage through the 100-K retention basin butterfly valves was also discharged to the trench. The 100-K Area was deactivated in 1971 and 1972, at which time the 116-K-2 trench was backfilled with the soil from the original excavation. A small construction tractor and all (empty) 100-K Area hydride tanks were also disposed in the trench during deactivation.

Code: 116-K-3	Classification: Accepted
Names: 116-K-3; 1904-K Outfall Structure; 1908-K Outfall Structure	Reclassification: None
Type: Outfall	Start Date: 1/1/1955
Status: Inactive	End Date:

Description: The waste site includes the concrete outfall structure. Differing from designs at other early reactors, two 213 centimeter (84 inch) retention basin lines did not discharge into the outfall structure, but passed directly and continuously under it, becoming the river effluent pipelines. In the event a pipeline became plugged downstream of the outfall structure, overflow standpipes inside the outfall would divert effluents into the concrete structure, and ultimately out the spillway.

Location: The site is located in the 100-K Area between the 100-K Area perimeter fence and the Columbia River.

Related Sites/ Structures: The site is associated with the 100-K-83 spillway, the 116-KE-4 and 116-KE-3 retention basins, the 100-K-55 and 100-K-56 process effluent lines, the 100-K-47 process sewer, the 100-K-64 flood plain, and the 100-K-80 and 100-K-96 river effluent pipelines. In January 2012, the river effluent pipeline designations were split. The portion of the 100-K-96 pipeline that extends into the river was given a new WIDS sitecode (100-K-114).

Process Description: Process sewer wastes, and reactor cooling water collected and temporarily stored in the 116-KE-4 and 116-KW-3 retention basins, were pumped to the river via the outfall structure's associated 100-K-80 river effluent pipelines.

Waste Type: Construction Debris

Waste Description: The unit received reactor coolant water from the 107-K Retention Basins. The radionuclide content is unknown. The structure also received general area wastes through the concrete box sewer. The concrete box sewer wastes went into the single chamber of the structure and then drained into the two pipelines into the river. The Contaminants of Potential Concern include Co-60, Cs-137, Eu-152, Eu-154, Pu-239/240, and Sr-90.

Code: 116-KE-4	Classification: Accepted
Names: 116-KE-4; 107-KE; 107-KE Retention Basins	Reclassification: Interim Closed Out (6/30/2005)
Type: Retention Basin	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1971

Description: The site has been remediated and Interim Closed Out. The site consisted of three open top, carbon-steel circular tanks with steel bottoms.

Location: The site was located northeast of 118-KE-1 (105-KE Reactor Building).

Release Description: The basins and their 1.5-meter (5-foot) diameter effluent line developed leaks during the site's operating life. The leakage rate from the butterfly valves (which went to an adjacent trench) could have been as high as 18,930 to 37,850 liters/minute (5,000 to 10,000 gallons/minute). Most of the basin leakage was diverted to an open canal and disposed to the river.

Related Sites/ Structures: The associated sites include 100-K-64 (100 KE Contaminated Flood Plain), 100-K-57 (107-KE Drainage Ditch), 100-K-41, 150-KE and 105-KE and 100-K-99 (Contaminated Material).

Process Description: The circular basins were 6.1 meters (20 feet) apart. The basins received 105-KE reactor effluent via a 183-centimeter (72-inch) pipe. Additional effluent from the 150-KE Building was received via 61-centimeter (24-inch), 46-centimeter (18-inch), 10-centimeter (4-inch) and 7.6-centimeter (3-inch) steel pipes. Basin effluent was discharged to the outfall structure via a 152-centimeter (60-inch) pipe. Discharges to the 116-K-1 and 116-K-2 Trenches could be made through 91-centimeter (36-inch) pipes that combined flows in a 106-centimeter (42-inch) pipe.

Waste Type: Process Effluent

Waste Description: This site received cooling water effluent from the 105-KE Reactor for radioactive decay and thermal cooling prior to release to the Columbia River. Eighty percent of the total radionuclide inventory was contained within the soil adjacent to the basin.

Closure Info: Interim: The steel walls of the tanks were removed and the site was interim stabilized in 1995. Decommissioning activities included removal of large steel access plates. The bottoms of the tanks were left in place and 45.7 to 61 centimeters (18 to 24 inches) of uncontaminated backfill was placed over them.

Remedial action activities at the 116-KE-4 site began on October 2, 2003. No clean overburden material was associated with this site. The excavation of the site involved removing piping,

debris, and contaminated soil. Contaminated materials were disposed of at ERDF. Remedial action excavation was completed on March 15, 2005. At the conclusion of excavation activities, the average surface elevation of the bottom of the excavation was approximately 132.6 meters (435 ft). The excavation covered an area of approximately 16,730 square meters (180,000 sq. ft.) with a maximum depth of approximately 4.3 meters (14.1 ft). Approximately 167,634.1 metric tons (184,785 U.S. tons) of material from the site were removed and disposed of at ERDF.

Code:	116-KW-3	Classification:	Accepted
Names:	116-KW-3; 107-KW; 107-KW Retention Basin	Reclassification	Interim Closed Out (4/12/2004)
Type:	Retention Basin	Start Date:	1/1/1954
Status:	Inactive	End Date:	1/1/1970

Description: The site has been remediated and Interim Closed-Out. The unit consisted of three open-top, circular carbon steel tanks with steel bottoms. The tanks were 61 meters (20 feet) apart. Decommissioning activities included removal of large steel access plates.

Location: The site was located north of 118-KW-1 (105-KW Reactor Building).

Release Description: The basins and their effluent lines developed leaks during their operating life. The leak rate from the butterfly valves (that went to an adjacent trench) could have been as high as 18,930 to 37,850 liters/minute (5,000 to 10,000 gallons/minute). Most of the basin leakage was diverted to an open canal and discharged to the Columbia River.

Related Sites/ Structures: The structures associated with the basins were 100-K-63 (100 K West Contaminated Flood Plain), 118-KW-1 (105-KW Reactor Building), 116-KW-4 (150-KW Heat Recovery Station) and 100-K-100 (Contaminated soil).

Process Description: The basins received 105-KW Reactor effluent via a 183-centimeter (72-inch) pipe. Additional effluent from the 150-KW Building was received via 61-centimeter (24-inch), 45.72-centimeter (18-inch), 10-centimeter (4-inch) and 7.6-centimeter (3-inch) steel pipes. Basin effluent was discharged to the outfall structure via a 152.4-centimeter (60-inch) pipe. Discharges to the 116-K-1 and 116-K-2 Trenches could be made through 91.4-centimeter (36-inch) pipes that combined flows in a 106-centimeter (42-inch) pipe.

Waste Type: Process Effluent

Waste Description: This site received cooling water effluent from the 105-KW Reactor for radioactive decay and thermal cooling prior to release to the Columbia River. Eighty percent of the total radionuclide inventory is contained within the soil adjacent to the basin.

Closure Info: Interim: The steel walls of the tanks were removed in 1995. The bottoms of the tanks were left in place with 45.7 to 61 centimeters (18 to 24 inches) of uncontaminated backfill placed over them.

The remedial action at 116-KW-3 began on December 11, 2002 and continued through October 20, 2003. At the completion of remedial action, the excavation was approximately 17,240 square meters (185,570 square feet) in area with an maximum depth of approximately 6.1 meters (20 feet). Approximately 169,893 metric tons (167,209 tons) of material, including soil, debris, and piping were removed from the 116-KW-3 site and disposed of at the Environmental Restoration Disposal Facility (ERDF).

The pipelines beneath the retention basin floor will be addressed during the closeout of the effluent pipelines (100-K-55).

100-KR-2

Code: 100-K-1 **Classification:** Accepted

Names: 100-K-1; 100-K-45; 119-KW Exhaust Air Sample Building French Drain; 119-KW French Drain **Reclassification:** None

Type: French Drain **Start Date:**

Status: Inactive **End Date:**

Description: The site is a 0.46 meter (1.5 foot) diameter concrete french drain that extends approximately 15 centimeters (6 inches) above the surrounding grade. It had a blue metal cover that is posted with "Confined Space" and "Surface Contamination" warning signs. A site visit in April 2000 found the area had been covered with cobble and surrounded with posts and chain. A sign reading "116-KW-1 Storage Basin French Drain" is still marking the area.

Location: The site is located to the east of the 105-KW Reactor Building, north of the 116-KW Stack, and south of the 119-KW Exhaust Air Sample Building.

Waste Type: Water

Waste Description: The unit received heat exchanger cooling water from sample equipment in the 119-KW Building, wastewater from a swamp-type cooler and effluent from a floor drain also located in the 119-KW Building.

Code: 100-K-3 **Classification:** Accepted

Names: 100-K-3; 1706-KE Fish Pond Heat Exchanger Pit, Pump Pit and Associated Piping; Water Studies Semi-Works **Reclassification:** Interim Closed Out (10/23/2012)

Type: Valve Pit **Start Date:** 1/1/1956

Status: Inactive **End Date:** 1/1/1965

Description: The waste site has been remediated and Interim Closed Out. It included the Heat Exchanger Pit, the Pump Pit and the pipelines that were specific to the 1706-KE Water Studies Semi-Works.

The Heat Exchanger Pit was a concrete pad on the surface. The structure was entirely below grade. A 1.2 by 3.0-meter (4 by 10-foot) access hatch was located at the south end. Adjacent to the access hatch was a square inlet ventilation pipe. A 61 centimeters (24 inches) in diameter exhaust vent pipe was visible on the north end. On the west side of the pad, a 7.6-centimeter (3-inch) pipe extended approximately 0.3 meters (1 foot) above the surface of the pad. It was surrounded by a 4.9 by 7.3-meter (16 by 24-foot) yellow wooden fence and a light duty post and chain barricade posted with "Surface Contamination" signs.

The Pump Pit was a concrete pad on the surface. The structure was entirely below grade. The Pump Pit above-grade concrete pad had been painted and marked as a "Confined Space".

Two 3 inch diameter pipelines connected the Heat Exchanger and Pump Pit to the 100-K-56 (36 inch and 72 inch diameter) pipelines. A 2.54-centimeter (1-inch) pipeline exited the 105-KE Reactor, near the two main effluent lines, and extended to the Heat Exchanger Pit. This pipeline is labeled PIEX (Pile Effluent from Experimental Tubes) on drawing H-1-24974KE.

The Heat Exchanger egress pipelines provided raw water that "cooled" process effluent to the

fish troughs in the 1706-KE Wet Fish Studies Laboratory (Sitecode: 100-K-52). The pipelines ran from the Heat Exchanger Pit to the northwest corner of the 1706-KE Building. They included a 7.6-centimeter (3-inch) raw water pipeline, a 2.54-centimeter (1-inch) PIE pipeline, and a 5.1-centimeter (2-inch) PIE pipeline. A 3.8-centimeter (1.5-inch) PIE pipeline and a 5.1-centimeter (2-inch) pipeline that connected the Heat Exchanger Pit and to the Valve Pit at the front of the Fish Pond (Site: 100-K-4). Portions of these pipelines were removed during the demolition of the 1706-KE, KER and KEL buildings in 2010 (see DOE/RL-2012-40). The pipeline removal was completed during the 100-K-3 structure remediation (see DOE/RL-2012-46).

Location: The 1706-KE Heat Exchanger Pit was located west of the northwest corner of the 105-KE Reactor Building. The Pump Pit is located to the east of the Heat Exchanger Pit.

Related Sites/ Structures: The site is related to 100-K-52, 1706-KE Wet Fish Studies Laboratory, 100-K-4, 1706-KE Wet Fish Studies Ponds and Valve Pit and pipeline 100-K-56.

Waste Type: Process Effluent

Waste Description:

Closure Info: Interim (10/23/2012): For the purposes of implementing and documenting remedial activities, the 100-K Area was divided into several informal remediation areas. The waste sites of this remedial activity were informally designated as being located within the Area AG Zone 1 remediation area, adjacent to the northwest corner of the reactor. (Note: One waste site located within Area AG Zone 1, the 116-KE-3 (105-KE Fuel Storage Basin Sub-Basin Drainage Disposal System Crib), was not remediated. Due to the extent of the deep zone contamination attributed to the 116-KE-3 waste site, it was placed in an "excluded region" within Area AG Zone 1. Waste site 116-KE-3 will be addressed at a later date.)

The remediated waste sites located in Area AG Zone 1 include 100-K-68, 100-K-69, 100-K-70, 100-K-71 and 100-K-3. A portion of the 100-K-3 pipeline was remediated with the area AG Zone 2 (see DOE/RL-2012-40). (Note: Portions of 100-K-47 and 100-K-56 pipelines were removed and considered part of the Area AG Zone 1 remediation activities. Approximately 452 feet of the 100-K-56, 36-inch pipeline was removed from Area AG Zone 1 and 3. Approximately 338 feet of the 100-K-56, 72-inch pipeline was removed from Area AG Zone 1 and 3. Approximately 344 feet of the 100-K-47, 12-inch pipeline exiting the 100-K-71 collection box was removed from Area AG Zone 1 and 3. Approximately 344 feet of the 100-K-47, 16-inch pipeline (exiting the 100-K-71 collection box) was removed from Area AG Zone 1 and 3. The remaining portions of the 100-K-47 and 100-K-56 pipelines will be addressed in future remediation activities.)

Remediation of the waste sites within Area AG Zone 1 began in September 2009 and was finished in May 2012. In-process samples were collected and radiological surveys were conducted to guide the remediation. Contaminated structures, pipelines, and associated soil and debris attributed to these waste sites have been removed and disposed at the ERDF. During this remedial activity, Stockpile #3 was created from excavated soil from the overburden and layback from Area AG Zone 1 waste sites. Radiological surveys were conducted on the material prior to placing it in the stockpile. Stockpile #3 was located northwest of Area AG.

The 105-KE fuel storage basin (100-K-42 waste site) borders the Area AG Zone 1. UPR-100-K-1 (105-KE Fuel Storage Basin Leak) is an unplanned release from the discharge chute of the fuel storage basin. It leaked highly radioactive water underneath the basin into the ground for an unknown period of time. Boreholes were drilled to evaluate the subsurface soil conditions. The results indicated significant residual radioactivity underneath the footprint of the fuel storage basin. The residual radioactivity distorted the radiological surveys conducted within the adjacent Area AG Zone 1.

The remediation of the 100-K-3 waste site began in January 2010 and was completed in May 2012. The remediation of this waste site included excavation of the heat exchanger, the pump pit, associated piping and contaminated soil. A total of 709 ERDF containers (11,513 metric tons [12,691 short tons]) was disposed at the ERDF from the Area AG 100-K-3 waste site (Zones 1 and 2 combined). Along with remediation of the waste sites in Area AG Zone 1, a 20.3 cm (8 in.) diameter Process Sewer Outside (PSO) drain line was also excavated. This pipeline exited the 100-K-3 heat exchanger pit and tied into the 100-K-47 concrete process sewer. This portion of pipeline was removed with a composite in-process sample taken along the length of the excavation in August 2011. The in-process sample results did not exceed the RAGs. The region within Area AG Zone 1 where this pipeline was removed was included in the Shallow Zone decision unit. In addition, the 100-K-3, 2.54 cm (1 in.) diameter PIEX pipeline (connecting the 100-K-3 heat exchanger to the 105-KE reactor) was documented in the shallow zone decision unit. This pipeline was originally buried 1.2 meters (4 ft) deep. When removed, the footprint was wholly contained within the layback region of the 100-K-56 waste site.

The 100-K-68 waste site structure (caisson with catch tank) was removed during waste site remediation. The remediation of the 100-K-68 waste site began in April 2010 and was completed in May 2012. The remediation of the waste site excavated the corrugated steel caisson, catch tank and pumping equipment. However, deep residual contamination associated with the 116-KE-3 waste site remains underneath the footprint of the 100-K-68 waste site.

The remediation of the 100-K-69 waste site began in April 2010 and was completed in May 2012. The remediation of the waste site excavated the concrete sump and associated contaminated soil.

The remediation of the contaminated soil beneath the 100-K-70 waste site began in April 2010 and was completed in May 2012. The tank associated with the 100-K-70 waste site had been previously removed, prior to the fuel storage basin demolition in 2008.

A total of 599 ERDF containers (11,920 metric tons [13,139 short tons]) was disposed at the ERDF from the combined 100-K-68, 100-K-69, and 100-K-70 waste sites.

The remediation of the 100-K-71 waste site began in March 2010 and was completed in May 2012. The remediation of the waste site included excavation of the collection box and associated contaminated soil. A total of 285 ERDF containers (5,858 metric tons [6,457 short tons]) was disposed at the ERDF from the 100-K-71 waste site. In-process samples collected at the collection box were analyzed for carbon-14 and tritium. The results indicated no residual contamination of these COCs.

The remediation of portions of the 100-K-47 pipeline began in November 2009 and was completed in September 2011. The partial remediation of the pipeline waste site included excavation of the underground process sewer pipelines and associated contaminated soil. In-process samples were collected within the remediated portion of the 100-K-71 waste site (collection box) footprint, because the 10.2 cm (4 in.) diameter cement asbestos pipeline from the 117-KE Filter Building (100-K-62 waste site) terminated at the collection box. Samples were analyzed for carbon-14 and tritium. The results indicated no residual contamination of these contaminants of concern (COCs). Therefore, carbon-14 and tritium were eliminated from the list of COCs for this waste site. A total of 1,240 ERDF containers (20,802 metric tons [22,930 short tons]) was disposed at the ERDF from the Area AG 100-K-47 waste site (Zones 1 and 3 combined).

The remediation of portions of the 100-K-56 Subsite 2 pipeline began in September 2009 and was completed in June 2011. The remediation excavated the part of the process effluent

underground pipelines and associated contaminated soil. A total of 800 ERDF containers (13,071 metric tons [14,408 short tons]) was disposed at the ERDF from the Area AG 100-K-56 waste site (in Zones 1 and 3 combined).

A total of 63,292 metric tons of material was disposed at the ERDF during the AG Zone 1 remediation activity. (33,873 metric tons was related to the 100-K-47 and 100-K-56 partial pipeline excavations.)

No evidence of spills or leaks from Area AG Zone 1 waste sites was found after remediation. Post remediation, a Global Positioning Environmental Radiological Survey (GPERS) and radiological surveys using hand-held instrumentation were conducted. The GPERS is rendered ineffective in regions close to the 105-KE Reactor fuel storage basin (100-K-42 waste site) and the unplanned release site (UPR-100-K-1) due to the sensitive detection capabilities of the sodium iodide instrumentation and the elevated radiation background levels associated with the fuel storage basin subsurface soil.

Follow-up radiological surveys using hand-held instruments were conducted in the region around the 100-K-68, 100-K-69, 100-K-70, and 100-K-71 waste sites, immediately north of the fuel storage basin. The survey indicated elevated radiological contamination where piping from the 105-KE Reactor fuel storage basin traveled to the 105-KE Collection Box (100-K-71 waste site). One of the pipelines entering the south side of the collection box was equipped with a direct buried flanged gate valve, located at a depth of approximately 8.5 meters (27 ft 11 in.). A focused verification sample of this location was collected to determine contamination levels present in the soil. This follow-up survey also indicated elevated radiological contamination in the area around the 100-K-68 waste site. Verification sampling beneath the 100-K-68 waste site was not conducted because the residual soil contamination is attributed to the 116-KE-3 waste site. NOTE: 116-KE-3 is located within Area AG Zone 1 but was not part of the remediation work scope.

Code:	100-K-4	Classification:	Accepted
Names:	100-K-4; 1706-KE Wet Fish Studies Ponds and Valve Pit	Reclassification	Interim Closed Out (8/4/2010)
Type:	Pond	Start Date:	1/1/1956
Status:	Inactive	End Date:	1/1/1965
Description:	This waste site has been demolished and Interim Closed Out. The site was two, 9.1 meter (30 foot) diameter circular ponds separated by a 2.7 by 9.1 meter (9 by 30 foot) rectangular pond and valve pit. The ponds contained drains which presumably discharged to the process sewer.		
Location:	The ponds were located approximately 50 meters (164 feet) west of the northwest corner of the 105-KE Reactor Building.		
Related Sites/ Structures:	The site was related to the 1706-KE Wet Fish Studies Laboratory (Site: 100-K-52) and the 1706-KE Heat Exchanger Pit (Site: 100-K-3). Process piping connected the ponds to the Heat Exchanger Pit (100-K-3).		
Process Description:	Waste Site 100-K-4, 1706-KE Wet Fish Studies Ponds and Valve Pit, supported the 1706-KE Wet Fish Studies Laboratory (Waste Site 100-K-52) and the 1706-KE Heat Exchanger Pit (Waste Site 100-K-3). Waste Site 100-K-52 was a small laboratory consisting of long troughs used to conduct wet fish studies using a mixture of raw water and heated effluent water from the 105-KE Reactor, which normally flowed to the Heat Exchanger Pit (100-K-3). Originally the laboratory was constructed to function as a backup laboratory in the event of shutdown of the 105-F Reactor and its associated aquatic biology laboratory. The 100-K-4 ponds were constructed in 1956 and operated intermittently through 1965, receiving mixed water effluents		

from the Laboratory (100-K-52).

Waste Type: Water

Waste Description: A mixture of raw water and heated effluent water passed through the troughs.

Closure Info: Interim: The selected remedy for waste site 100-K-4 was Remove, Treat and Dispose. This was achieved through removal and disposal of the 1706-KE Wet Fish Studies Ponds and Valve Pit and remediation of underlying contaminated soil.

The waste site excavation was initiated in January of 2010 and completed in February of 2010. Radiological surveys done during the remediation indicated minor residual radioactivity in the drains. The concrete ponds and associated piping were removed and disposed. The waste site was excavated to a maximum depth of approximately 5.37 meters (17.6 feet) in the deep zone of the excavation. A total of 2,989.26 tons of soil and debris were disposed of at the ERDF. No cracking was noted in the concrete and the piping appeared to be intact. The 100-K-4 Waste Site remediation coincided with the ongoing remediation of the 100-K-3, 100-K-47, and 100-K-56 Waste Sites.

Code: 100-K-5

Classification: Accepted

Names: 100-K-5; 1705-KE French Drain

Reclassification: None

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The site is a french drain consisting of a 0.9 meter (3 foot) diameter vitrified clay pipe which protrudes approximately 0.3 meter (1 foot) above grade and has a heavy wooden cover.

Location: The site is located just east of the 1705-KE Water Treatment Facility.

Waste Type: Process Effluent

Waste Description: The site received waste effluent from floor drains, overflows, and drainage from the 1705-KE Experimental Water Treatment Basin and facilities.

Code: 100-K-6

Classification: Accepted

Names: 100-K-6; 105-KE Vacuum Pit; Cyclone Separator; Vacuum Pit

Reclassification: Interim Closed Out (8/29/2012)

Type: Process Unit/Plant

Start Date:

Status: Inactive

End Date:

Description: The waste site has been remediated and Interim Closed Out. The vacuum pit contained a cyclone separator in a vertically oriented 3-meter (10-foot) diameter culvert which extends from grade level to 9.2 meters (30 feet) below grade.

Location: The site is located on the east side of the 105-KE Reactor Building and just south of the reactor stack.

Related Sites/Structures: The site is associated with the Turco Pit in the 105-KE Reactor Building.

Process Description: The cyclone separator was used to separate solids from the vacuum air stream. The cyclone separator was used to separate solids from the vacuum air stream associated with the reactor

building decontamination solution pit, which was inside the basement of the 105-KE Reactor and contained a large stainless steel tank. The tank was used to mix decontamination solutions within the reactor facility. Site employees report that the vacuum system portion of the cyclone separator was used during maintenance on the reactor core or for the movement of the Ball 3X Safety System balls, which were collected in drums. Vacuum hoses exited and entered the reactor pit via a small concrete trench with a steel lid located at grade and running due east under the concrete sidewalk and into and out of the vacuum pit in a closed loop system, during normal operation.

Waste Type: Soil

Waste Description: The 100-K-6 Waste Site received radiologically-contaminated exhaust air from the decontamination solution pit. The contaminants were cobalt-60, cesium-137, carbon-14, and tritium, as well as strontium-90, europium-152, europium-154, and europium-155. The soil beneath the steam turbine is reported to have been contaminated with radioactive materials and was covered with about 0.3 meters (1 foot) of gravel. The dose rate at the pit opening on January 20, 1994 was slightly less than 2 millirad/hour, suggesting a higher dose rate at the pit bottom.

Closure Info: Interim (8/29/2012): Remediation and sampling began in January of 2009 and was completed in April of 2012. The large excavation area, known as 100-K Area AH, encompassed waste sites 100-K-6, 100-K-46, 100-K-62 and 132-KE-1. The excavation area also included Stockpile #4, which contained overburden and layback soil from the excavation of the 116-KE-1 Condensate Crib. Information supporting the use of Stockpile #4, located within the AH excavation, as backfill was also included in the DOE/RL-2012-38 Remaining Sites Verification Package report.

Remediation of the identified Area AH waste sites was accomplished by demolishing the structures and excavating contaminated soil. All waste (soil and debris) associated with these waste sites was disposed at the Environmental Restoration and Disposal Facility (ERDF). The demolition activities were conducted using standard demolition techniques, including explosives for demolition of 132-KE-1 (116-KE Reactor Exhaust Stack). Approximately 1,809 ERDF containers (37,700 tons) of waste from these waste sites were sent to the ERDF for disposal.

Remediation of the 100-K-6 vacuum pit began in August 2011 and was completed in September 2011. An excavator was used to remove the vacuum pit and excavate the surrounding soil. The original waste site description estimated the depth of the cyclone separator as 9.14 meters (30 ft). However, during remediation the actual excavation depth was measured as 5.8 meters (19 ft).

The remediation of the 100-K-46 french drain was associated with the removal of the 119-KE building, which began in January 2009 and was completed in February 2009. The drywell was less than 1.5 meters (5 ft) deep.

The remediation activities at the 100-K-62 filter building began in August 2010 and were completed in May 2011. An excavator was used to remove the vacuum pit and excavate the surrounding soil. The maximum depth from grade within the waste site footprint was approximately 10.6 meters (34.8 ft).

The remediation activities at waste site 132-KE-1 exhaust stack began in July 2010 and were completed in September 2011. Removal of the above-grade portion of the stack was conducted using explosives placed near the base of the stack. The explosion caused the debris to fall in a designated area. The material was then loaded and disposed at ERDF. The entire below grade portion of the stack base was then removed. The maximum depth from grade within the waste site footprint was approximately 6.1 meters (20 ft).

In October of 2010, excavation of the overburden and layback soil for the 116-KE-1 Crib began and Stockpile #4 was created. Samples were collected in the 116-KE-1 waste site footprint and sent for analytical leach testing of the soils to determine carbon-14 leachability from the 100-K soil. During remediation of the co-located waste sites inside the AH excavation area, the 116-KE-1 crib was partially backfilled with soil from Stockpile #4 as a contamination control measure.

Note: Area-wide carbon-14 contamination exists in the deep zone above the criteria for protectiveness. This contamination is associated with the 105-KE Reactor ventilation filtration system and the deep contamination from the condensate that collected in the previously excavated 116-KE-1 Condensate Crib. Additional remediation of the deep vadose zone cannot be completed in proximity to the 105-KE Reactor without impacting structural stability. Available information about the nature and extent of the carbon-14 contamination has been documented in the 116-KE-1 Condensate Crib waste site description. Due to the depth of the contamination, the carbon-14 remediation will coincide with the final decision on 105-KE reactor removal.

Code: 100-K-13	Classification: Accepted
Names: 100-K-13; French Drain West of the 166-KW Oil Storage Tank Facility	Reclassification: None
Type: French Drain	Start Date:
Status: Inactive	End Date:

Description: The site is a french drain that is a 1.5 meter (5-foot) diameter vertical concrete pipe filled with gravel. Prior to the construction of the Cold Vacuum storage Facility, the drain had been almost flush with the ground surface. Facility construction required the area to be graded. The construction project has scraped the ground down about 1.8 meters (6 feet) leaving the french drain about 2.3 meters (7.5 feet) above ground level. The french drain is now covered by a corrugated metal caisson to protect the french drain structure. Prior to current construction activities, the drain extended above grade about 0.46 meters (1.5 feet) and was surrounded by a yellow wooden barricade.

The french drain has no markings of any kind. No other documentation or drawings could be found that identify the site or its purpose. Prior to current construction, no facilities were close to the site.

Location: The site was located on a small rise that is west of the southwest corner of the 166-KW Oil Storage Tank Facility and 10.4 meters (34 feet) west of the small access road that runs along side of the 166-KW. The Cold Vacuum Storage Facility was recently built in this area and graded the area to accommodate construction.

Code: 100-K-14	Classification: Accepted
Names: 100-K-14; 183-KE Acid Neutralization Pit and Overflow French Drain	Reclassification: None
Type: French Drain	Start Date:
Status: Inactive	End Date:

Description: The pit is 4.6 meters (15 feet) deep with a bottom dimension of 1.5 meters (5 feet) in diameter. Eight to thirteen centimeter (3 to 5 inch) aggregate was placed to a depth of 2.1 meters (7 feet).

A 0.76 meter (2.5 foot) diameter, 2.4 meter (8 foot) long vitrified clay pipe (VCP) was placed vertically in the center of the pit and 1.2 meters (4 feet) of aggregate were placed around the pipe exterior. Approximately 1.5 meters (5 feet) of limestone chips were added to the pipe interior. A 5.1-centimeter (2 inch) schedule 80 polyvinyl chloride (PVC) pipe enters through the side 1 meter (3.3 feet) below grade. The pipe is an overflow and drain line for the 183-KE Day Use Acid Tank. The pit was then backfilled to grade. The VCP is exposed a few inches above grade and is covered with a 0.64 centimeter (0.25 inch) steel plate with four 2.54 centimeter (1 inch) vent holes. Four steel yellow corner posts surround the above grade VCP.

Location: The site is located near the 183-KE Alum Storage Tanks, 11 meters (36 feet) southeast of the railroad track, and directly south of the 183-KE Head House.

Related Sites/ Structures: The site received overflow and drainage from the 183-KE Day Use Acid Tank.

Waste Type: Chemicals

Waste Description: The site received sulfuric acid overflow and drainage from the 183-KE Day Use Acid Tank.

Code: 100-K-18

Classification: Accepted

Names: 100-K-18; 183-KW Caustic Neutralization Pit

Reclassification: Interim Closed Out (6/27/2012)

Type: Sump

Start Date:

Status: Inactive

End Date:

Description: The waste site has been remediated and Interim Closed Out. The pit was a brick lined concrete box with a wooden cover. The pit was constructed in such a way that small volumes of waste chemicals could be held up in a brick lined compartment for neutralization. After neutralization, waste was flushed to a larger compartment within the structure, which then drained to the process sewer.

Location: The site was northeast of the 183-KW Head House, northwest of the railroad tracks running in front of 183-KW, and southeast of the grade-level concrete base of the old caustic soda storage tank.

Waste Type: Process Effluent

Waste Description: The pit received, neutralized, and disposed of caustic (sodium hydroxide) waste from overflow and transfers associated with the 183-KW water treatment system.

Closure Info: Interim (6/27/2012): Remediation of the Area AA, Zone 2 waste sites (100-K-18, 100-K-19, 100-K-79:1, 100-K-79:2, 100-K-97, 120-KW-5 and 120-KW-7) began in May 2010. Throughout the remedial activity, because of the contaminants found in the process equipment and surface soils, in-process samples were collected and analyzed for metals, including chromium VI and anions (e.g., sulfate due to the sulfuric acid), at multiple locations and depths. In-process sampling occurred across all four zones in 100-K Area AA, although this report focuses on Zone 2 only. Throughout remediation, stained areas were targeted for in-process sampling; soils often were yellow-colored and high in lead, total chromium and mercury. Hexavalent chromium, which is the groundwater contaminant of greatest concern at 100-K, was detected on the soil surface down to 6 feet, at the beginning of remediation for Area AA Zone 2. Excavation continued to a final remediation depth of 10.96 meters (35.96 ft).

During a walkdown of Area AA by RL and EPA on September 20, 2011, it was determined that piping found within Zone 1 needed to be further investigated. The piping identified was determined to be a part of the process sewer line and was subsequently removed.

The excavation decision unit was approximately 3,228 square meters (34,745.9 sq. ft.). All contaminated soils and debris from the waste sites was disposed of in the Environmental Restoration Disposal Facility (ERDF).

Code: 100-K-19	Classification: Accepted
Names: 100-K-19; 183-KW Caustic Soda Storage Tank Site	Reclassification: Interim Closed Out (6/27/2012)
Type: Foundation	Start Date: 1/1/1954
Status: Inactive	End Date:

Description: The waste site has been remediated and Interim Closed Out. The site was originally an above-ground, cylindrical, vertical steel storage tank on a concrete base. The above-ground tank was 7.8 meters (25.5 feet) in diameter with a 287,660 liter (76,000 gallon) capacity. Some time in the past (date unknown) the tank was removed. Then the waste site was a 9.1-meter (30-foot) diameter grade-level concrete tank base and the soil surrounding the base.

Location: The site was located 12.2 meters (40 feet) northeast of the southeast corner of the 183-KW Head House and 4.6 meters (15 feet) northwest of the railroad tracks in front of 183-KW.

Release Description: Spills may have occurred near the tank and the piping system may have developed leaks. This is likely to have resulted in sodium hydroxide leaking to the soil beneath and around the tank. No known sampling has been performed at this site.

Related Sites/Structures: The site was related to the 183-KW Head House that controlled and monitored water quality. The site was also related to the 100-K-18 Neutralization Pit. Overflow and transfer waste from this tank was routed to the nearby caustic neutralization pit.

Process Description: Caustic soda (sodium hydroxide) was injected into the filtered water as a pH correction. It was proportioned and metered in a single step operation. Caustic soda was injected into a softened water stream in the 183-KE Head House. The softened water was used as a dilutant and as a vehicle to transport the caustic to the injection point at the clearwells. Since caustic soda was injected at only two points, the proportioning was regulated by the half plant effluent rate. Sodium hydroxide was also used to regenerate the ion exchange columns in the water softener system and for maintaining a neutral pH of the reactor cooling water. It was most likely the neutralizing agent for excess or spilled sulfuric acid that was used in the 183-K facilities.

Waste Type: Chemical Release

Waste Description: The unit was used to store sodium hydroxide. Spills may have occurred near the unit. The piping system may have developed leaks. This is likely to have resulted in sodium hydroxide in the soil beneath and around the unit.

Closure Info: Interim (6/27/2012): Remediation of the Area AA, Zone 2 waste sites (100-K-18, 100-K-19, 100-K-79:1, 100-K-79:2, 100-K-97, 120-KW-5 and 120-KW-7) began in May 2010. Throughout the remedial activity, because of the contaminants found in the process equipment and surface soils, in-process samples were collected and analyzed for metals, including chromium VI and anions (e.g., sulfate due to the sulfuric acid), at multiple locations and depths. In-process sampling occurred across all four zones in 100-K Area AA, although this report focuses on Zone 2 only. Throughout remediation, stained areas were targeted for in-process sampling; soils often were yellow-colored and high in lead, total chromium and mercury. Hexavalent chromium, which is the groundwater contaminant of greatest concern at 100-K, was detected on the soil surface down to 6 feet, at the beginning of remediation for Area AA Zone 2. Excavation continued to a final remediation depth of 10.96 meters (35.96 ft).

During a walkdown of Area AA by RL and EPA on September 20, 2011, it was determined that

pipings found within Zone 1 needed to be further investigated. The piping identified was determined to be a part of the process sewer line and was subsequently removed.

The excavation decision unit was approximately 3,228 square meters (34,745.9 sq. ft.). All contaminated soils and debris from the waste sites was disposed of in the Environmental Restoration Disposal Facility (ERDF).

Code:	100-K-25	Classification:	Accepted
Names:	100-K-25; 183-KE Caustic Neutralization Pit	Reclassification	None
Type:	Sump	Start Date:	
Status:	Inactive	End Date:	
Description:	The 183-KE Caustic Neutralization Pit is an underground concrete structure used to neutralize caustic waste prior to disposal. The structure has been backfilled and covered to grade with gravel. The "pit" is a concrete box that is lined with acid-proof bricks. A 10.2-centimeter (4-inch) vitrified tile drain was located in the bottom of the pit and discharged the neutralized waste to the process sewer. The top of the pit was level with the surface and had a 7.6-centimeter (3-inch) plank cover.		
Location:	The site is located near the 183-KE Head House, southeast of the 183-KE Caustic Soda Storage Tank Site (100-K-27).		
Related Sites/ Structures:	The pit was used to neutralize and dispose of caustic overflow and transfer waste associated with the caustic soda tank and the 183-KE water treatment process. After neutralization, the waste was drained to the process sewer.		
Process Description:	The pit received, neutralized, and disposed of caustic waste from overflow and transfers associated with water treatment at 183-KE. The method of caustic neutralization is not known.		
Waste Type:	Chemicals		
Waste Description:	The pit received and neutralized sodium hydroxide waste.		

Code:	100-K-27	Classification:	Accepted
Names:	100-K-27; 183-KE Caustic Soda Storage Tank Site	Reclassification	None
Type:	Foundation	Start Date:	1/1/1954
Status:	Inactive	End Date:	
Description:	The site was originally an above-ground, cylindrical, vertical steel storage tank on a concrete base. In the past (date unknown) the tank was removed. The above-ground tank was 7.8 meters (25.5 feet) in diameter with a 287,660-liter (76,000-gallon) capacity. Currently, is the 9.1-meter (30-feet) diameter grade-level concrete tank base and the soil surrounding the base remain.		
Location:	The site is located 12.2 meters (40 feet) northeast of the southeast corner of the 183-KE Head House and 4.6 meters (15 feet) northwest of the railroad tracks in front of 183-KE.		
Release Description:	Spills may have occurred near the tank and the piping system may have developed leaks. This is likely to have resulted in sodium hydroxide leaking to the soil beneath and around the tank. No known sampling has been performed at this site.		
Related Sites/ Structures:	The site was related to the 183-KE Head House that controlled and monitored water quality. The site was also related to the 100-K-25 Neutralization Pit. Overflow and transfer waste from		

this tank was routed to the nearby caustic neutralization pit.

Process Description: Caustic soda (sodium hydroxide) was injected into the filtered water as a pH correction. It was proportioned and metered in a single step operation. Caustic soda was injected into a softened water stream in the 183-KE Head House. The softened water was used as a dilutant and as a vehicle to transport the caustic to the injection point at the clearwells. Since caustic soda was injected at only two points, the proportioning was regulated by the half plant effluent rate. Sodium hydroxide was also used to regenerate the ion exchange columns in the water softener system and for maintaining a neutral pH of the reactor cooling water. It was most likely the neutralizing agent for excess or spilled sulfuric acid that was used in the 183-K facilities.

Waste Type: Chemical Release

Waste Description: The tank was used to store sodium hydroxide. There is a possibility the tank and/or piping may have leaked.

Code: 100-K-29

Classification: Accepted

Names: 100-K-29; 183-KE Sandblasting Site

Reclassification: Interim Closed Out (6/24/2004)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site has been remediated and Interim Closed Out. Before remediation the site surface was gravel/cobble and purple garnet. It was irregularly shaped and covered an area of 46 meters (50 yards) x 27 meters (30 yards).

Location: Located 40-feet SW of the 183-KE Chlorine Storage Vault and just west of the 183-KE Alum Storage Tanks (126-KE-1 and 126-KE-2).

Process Description: In the early 1980s, steel components from the 183-KE settling basins were sandblasted at this site prior to being sold as scrap. The site consisted of surface gravel/cobble and red/purple garnet.

Waste Type: Chemicals

Waste Description: At this site in the early 1980's, steel components from the 183-KE settling basins were sandblasted prior to being sold as scrap. Sampling in 1989 indicated the material present to be nonregulated for EP Toxicity.

Closure Info: Interim: A phased sampling approach was implemented at the site based on site photographs, historical use information, suspected waste materials, and statistical information. Confirmatory sampling was conducted during April 2003. The analytical laboratory results for total chromium, lead, hexavalent chromium, and Aroclor-1254 exceeded action levels, indicating that site remediation (remove, treat, and dispose) was required. A cleanup action was implemented during December 2003, removing the sandblast media and approximately 5.1 centimeters (2 inches) of underlying soil from the site.

A total of 187 metric tons (206 tons) of sandblast media and underlying soil were removed and disposed of it at the Environmental Restoration Disposal Facility. The maximum detected results from underlying soil samples collected at locations suspected of having the greatest potential for contamination were shown to meet the cleanup objectives for direct exposure, groundwater protection, and river protection.

Code: 100-K-30

Classification: Accepted

Names: 100-K-30; 183-KE Sulfuric Acid Tank Bases

Reclassification: Interim Closed Out (8/2/2004)

(West Tank)

Type: Storage Tank

Start Date:

Status: Inactive

End Date:

Description: The site has been remediated and Interim Closed Out. The site consisted of two, above ground, U-shaped concrete bases and above ground piping. A cylindrical tank had laid horizontally on the two concrete U-shaped bases. The tank measured 3 meters (10 feet) in diameter, 10 meters (33 feet) long and had a 77,140-liter (20,380-gallon) capacity. It is unknown when the tank was removed.

Location: The site was located in the 100-K Area. It was 8.2 meters (27 feet) northeast of 120-KE-4.

Related Sites/ Structures: The site was associated with 100-K-31 and the 183-KE Water Treatment Plant.

Process Description: The 183-KE Sulfuric Acid Storage Tank was associated with 183-KE Water Treatment Plant. West of this tank were two smaller sulfuric acid tanks (120-KE-4 and 120-KE-5) which were used for the same purpose. East of the tank was another tank the same size, that was used for the same purpose.

Waste Type: Chemicals

Waste Description: The tank bases held a tank that was used to store sulfuric acid.

Closure Info: Interim: Results from the historical research and confirmatory sampling that had been conducted during April 2003 were used to make decisions for reclassifying the site. The soil achieved compliance with the remedial objectives, but the concrete and felt material exceeded the remedial action levels. In January 2004, a remedial action activity was implemented to remove the stained concrete bases and felt to a depth of 1 meter (3 ft.). The material from the site was disposed at the Environmental Restoration Disposal Facility. Since the soil already met the RAOs, no further verification sampling was required.

Code: 100-K-31

Classification: Accepted

Names: 100-K-31; 183-KE Sulfuric Acid Tank Bases (East Tank)

Reclassification: Interim Closed Out (8/2/2004)

Type: Storage Tank

Start Date:

Status: Inactive

End Date:

Description: The site has been remediated and Interim Closed Out. The site consisted of two above ground U-shaped concrete bases and above ground piping.

Location: The unit was located 14.3 meters (47 feet) northeast of 120-KE-4 (60 degrees).

Related Sites/ Structures: This site was associated with sites 100-K-30 and 100-K-32 and the 183-KE Water Treatment Plant.

Process Description: The Sulfuric Acid Storage Tank was associated with 183-KE Water Treatment Plant. West of this tank are two smaller sulfuric acid tanks (120-KE-4 and 120-KE-5) and another tank the same size as the one described here, all of which were used for the same purpose.

Waste Type: Chemicals

Waste Description: The tank was used to store sulfuric acid.

Description:

Closure Info: Interim: The above ground tank had been removed prior to 1994. The aboveground piping was removed in June 2000.

Results from confirmatory sampling that had been conducted in April 2003 were used to make decisions for reclassifying the site. The confirmatory samples exceeded the action levels for, barium, cadmium, lead, mercury and hexavalent chromium. A cleanup action was implemented during December 2003, removing the concrete bases and about 0.61 meters (2 feet) of contaminated soil and disposing them at the Environmental Restoration Disposal Facility.

The sampling results supported a reclassification of the waste site to interim closed out.

Code:	100-K-32	Classification:	Accepted
Names:	100-K-32; 183-KW Sulfuric Acid Tank Bases (East Tank)	Reclassification	Interim Closed Out (7/27/2004)
Type:	Storage Tank	Start Date:	
Status:	Inactive	End Date:	

Description: The site has been remediated and Interim Closed Out. The unit consisted of two above-ground U-shaped concrete bases and aboveground piping. The U-shaped bases were 3.7 meters (12 feet) wide, 1.2 meters (4 feet) long, 1.8 meters (6 feet) high, and 10 meters (33 feet) apart. The surface soils were stained with what appeared to be acid residue.

Location: The site was located east of the 183-KW Head House, south of the end of the railroad tracks and 14.3 meters (47 feet) northeast (60 degrees) of 120-KW-4.

Related Sites/Structures: The Sulfuric Acid Storage Tank was associated with 183-KW Water Treatment Plant. West of this tank were two smaller sulfuric acid tanks (120-KW-3 and 120-KW-4) and another tank (100-K-33) the same size as the one described here, all of which were used for the same purpose.

Process Description: A cylindrical tank (which appeared at the site in a March 1962 photograph) had laid horizontally on two concrete U-shaped bases. The tank was 3 meters (10 feet) in diameter, 10 meters (33 feet) long and had a 77,140-liter (20,380-gallon) capacity. It was unknown when the tank was removed.

Waste Type: Soil

Waste Description: The soil was contaminated from sulfuric acid leaks or spills.

Waste Type: Equipment

Waste Description: Two concrete tank pedestals and associated sulfuric acid piping were at the site.

Closure Info: Interim: The April 2003 analytical laboratory results for cadmium and total chromium in the concrete and lead and mercury in the soil exceeded action levels, indicating that site remediation (remove, treat, and dispose) was required. A cleanup action was implemented during December 2003, removing the concrete bases (including the felt) and about 0.61 meters (2 feet) of contaminated soil from the site and disposing of it at the Environmental Remediation Disposal Facility. Verification sampling was conducted during December 2003 and January 2004. The verification sampling results indicated that the cleanup action had achieved compliance with the remedial action objectives (RAOs) for the site.

Code: 100-K-33

Classification: Accepted

Names: 100-K-33; 183-KW Sulfuric Acid Tank Bases (West Tank) **Reclassification** Interim Closed Out (8/24/2004)

Type: Storage Tank

Start Date:

Status: Inactive

End Date:

Description: The site has been remediated and Interim Closed Out. The unit consisted of two above-ground U-shaped concrete bases and above-ground piping. Yellow stains and tar-like material was in the surrounding gravel.

Location: The unit was located 8.2 meters (27 feet) northeast (60 degrees) of 120-KW-4.

Related Sites/Structures: The Sulfuric Acid Storage Tank was associated with 183-KW Water Treatment Plant. West of this tank were two smaller sulfuric acid tanks (120-KW-3 and 120-KW-4) which were used for the same purpose. East of the tank location described by this entry was another tank (100-K-32) the same size that was used for the same purpose.

Process Description: The U-shaped bases were 3.7 meters (12 feet) wide, 1.2 meters (4 feet) long, 1.8 meters (6 feet) high, and 10 meters (33 feet) apart. A cylindrical tank laying horizontally on the two concrete U-shaped bases was observed in a March 1962 photograph.

The tank was 3 meters (10 feet) in diameter, 10 meters (33 feet) long and had a 77,140-liter (20,380-gallon) capacity. The tank was used to store sulfuric acid and was removed at an unknown date.

Waste Type: Chemicals

Waste Description: The unit consisted of two above-ground U-shaped concrete bases and above-ground piping. The U-shaped bases were 3.7 meters (12 feet) wide, 1.2 meters (4 feet) long, 1.8 meters (6 feet) high, and 10 meters (33 feet) apart. A cylindrical tank laying horizontally on the two concrete U-shaped bases was observed in a March 1962 photograph. The tank was used to store sulfuric acid and was removed at an unknown date.

Closure Info: Interim: A remedial action was implemented in December 2003. The concrete bases, including the felt pads, were removed and about 30 cubic meters (990 cubic feet) of contaminated soil was disposed of at the Environmental Restoration Disposal Facility.

A test pit was dug in the center of the excavation to a depth of 4 meters (13 feet) to collect soil data on mercury for RESidual RADioactivity (ANL 2002) modeling and characterize the potential depth of metals contamination beneath the other 100-K Area sulfuric acid tanks (100-K-30, 100-K-31, and 100-K-32).

Following remediation, verification sampling was conducted during December 2003 and January 2004. The post-remediation verification sampling contaminants of concern (COCs) for the 100-K-33 waste site were identified based on the results of the confirmatory sampling effort. The results indicated that the remedial action achieved compliance with the remedial action objectives for the site. The results of the verification sampling were used to support decisions to reclassify the site in accordance with the waste site reclassification guideline TPA-MP-14 (DOE-RL 1998) process.

Code: 100-K-34

Classification: Accepted

Names: 100-K-34; 183-KW Acid Neutralization Pit

Reclassification Interim Closed Out (7/10/2012)

Type: Sump

Start Date:

Status: Inactive

End Date:

Description: The waste site has been remediated and Interim Closed Out. The acid pit consisted of 2.5 by 1.9-meter (8.3 by 6.3-foot) brick-lined concrete boxes. The boxes were 1.5 meters (5 feet) deep and backfilled with crushed limestone. Drain pipes entered about 0.6 meters (2 feet) below grade and emptied into a 0.9-meter (3-foot) diameter vitrified clay pipe (VCP) placed vertically in limestone chips. The VCP was filled with limestone chips. The VCP was intentionally broken at the top to allow acid solutions to overflow into the interior of the pit.

Location: The unit is located in the 100KW Area, adjacent and 0.6 meters (2 feet) west of 183-KW and 3.7 meters (12 feet) east of the 183-KW Chlorine Vault.

Related Sites/ Structures: The site received transfer and overflow waste from nearby sulfuric acid tanks associated with the 183-KW Water Treatment Plant. The site drained to the process sewer back into the 183.1-KW Headhouse, and into a floor drain to the process sewer line that ran through the 183.7-KW Tunnel.

Waste Type: Chemicals

Waste Description: The site was used to neutralize and dispose of overflow and transfer waste from nearby sulfuric acid tanks.

Closure Info: Interim (7/10/2012): Remediation of the Area AA Zone 1 Waste Sites began in April 2010 and ended in January 2012. The waste site structures and soils have been excavated as part of the remedial activities for the 100-K Area. The excavation area was designated as 100-K Area AA, Zone 1 (Area AA, Zone 1). It encompassed the individual waste sites 100-K-34, 100-K-102 and 1607-K3. Stockpile #11 contains layback soil from remediation of Area AA, Zone 1. These waste sites are adjacent to the 100-K-59 pipelines. Since visible sediment was observed in the severed pipelines, a sample was collected in February 2011 from the open end of the pipe west of the 183.1KW Headhouse. A section of the 100-K-59 pipeline was removed.

Excavation of the waste sites continued to a final remediation maximum depth of 9.82 meters (32.2 ft), which was located within the footprint of 100-K-102. To support the deeper excavation for Area AA, Zone 1, layback soil was accumulated and managed as Stockpile #11. The excavation decision unit was approximately 7,331 square meters (78,910 ft²) for 100-K Area AA, Zone 1. The original footprint prior to additional process sewer pipe removal was divided into evenly spaced areas for statistical sampling outside the waste sites to address any potential for contamination spread.

Code: 100-K-35

Classification: Accepted

Names: 100-K-35; 183-KE Acid Neutralization Pit

Reclassification: None

Type: Sump

Start Date:

Status: Inactive

End Date:

Description: The site is a below grade, 2.5 meter by 1.9 meter (8.33 feet by 6.33 feet) brick-lined concrete box, approximately 1.5 meters (5 feet) deep and backfilled with crushed limestone. Drain pipes entered the pit approximately 0.6 meters (2 feet) below grade and emptied into a vertical 0.9 meter (3 foot) diameter vitrified clay pipe. The vitrified clay pipe is also filled with limestone chips and appears to be broken at the top. The site is covered by a wooden lid labeled "Confined Space" and is surrounded by post and chain.

Location: The site is located between the 183-KE Head House and the 183-KE chlorine vault.

Related Sites/ Structures: The site received transfer and overflow waste from nearby sulfuric acid tanks associated with the 183-KE Water Treatment Plant. The site drained to the process sewer.

Waste Type: Chemicals

Waste Description: The site was used to neutralize and dispose of overflow and transfer waste from nearby sulfuric acid tanks.

Code: 100-K-36 **Classification:** Accepted
Names: 100-K-36; 1706-KE Chemical Storage Facility **Reclassification:** Interim Closed Out (10/19/2012)
 Dry Well
Type: French Drain **Start Date:** 1/1/1962
Status: Inactive **End Date:**

Description: The waste site has been remediated and Interim Closed Out. It was a dry well (french drain) that was added to the 1706-KE Building as part of the Chemical Storage Facility. The drain was located at grade level and centered between the 1706-KE Caustic Tank and the 1706-KE Sulfuric Acid Tank. The french drain was constructed from an 0.46 meter (18 inch) vitrified clay pipe that is 1.2 meters (4 feet) long and extended 7.6 centimeters (3 inches) above grade. The site was filled to grade with crushed limestone. Overflow and drain pipes [two 5.1 centimeter (2 inch) pipelines from each chemical storage tank] extended to just above the surface of the limestone fill.

Location: The site was located in the southeast corner and adjacent to the 1706-KE Building. The site was between the 100-K-37, 1706-KE Sulfuric Acid Tank and 100-K-38, 1706-KE Caustic Soda Tank.

Release Description: The dry well was located near an underground tunnel to the 105-KE Reactor Building. At a point within the tunnel very near the drain, a white crystalline material was seen in the cracks of the tunnel ceiling. This may be sodium hydroxide from the 100-K-38, 1706-KE Caustic Soda Tank. A former site employee reports that small spills did occur during filling operations of the storage tanks on several occasions.

Related Sites/Structures: The site is related to the 1706-KE Building, 100-K-37, 1706-KE Sulfuric Acid Tank, and 100-K-38, 1706-KE Caustic Soda Tank.

Process Description: The chemical storage facility at 1706-KE was installed in 1963 to provide bulk quantities of 93 percent by weight sulfuric acid and 50 percent by weight sodium hydroxide. The chemicals were used to regenerate the ion columns in the 1706-KE demineralizer plant. The demineralizer plant supplied demineralized water to two experimental single pass process tube in the 105-KE reactor core. The demineralizer plant was a duplex unit with two sets of ion columns. It operated with one set in service and the other either being regenerated or in a ready-standby condition. Typically three regenerations were performed each day during this period. Shipping manifests indicate that approximately 7,948.5 liters (2100 gallons) of sulfuric acid and 10,976.5 liters (2900 gallons) of sodium hydroxide were delivered to 1706-KE at 4-6 week intervals. In 1971, the 100-K production reactors were shut down and the demineralizer plant was deactivated. It was reactivated some years later to provide demineralized water to the 100-K area fuel storage basins. The quantity of demineralized water produced during this period of operation was a small fraction of that produced during reactor operation. Thus, the number of regenerations was steadily reduced from an initial amount of approximately 12 times per year to 3 times per year when the demineralizer plant was finally taken out of service.

Waste Type: Chemicals

Waste Description: A white crystalline material that may be sodium hydroxide can be seen in cracks of the tunnel. This may indicate that large quantities of sodium hydroxide and/or water have been disposed to this drain.

Closure Info: Interim (10/19/2012): The D4 (deactivation, decommissioning, decontamination and demolition) organization removed the above ground parts of the 1706-KE, 1706-KEL, and

1706-KER buildings, plus three feet of the below ground structures. The 1706-KE, 1706-KER, 1706-KEL building demolition to grade was completed in October 2010. Directly after completing D4 work, the area was transitioned to the soil remediation organization. The 100-K-36 french drain, and portions of the 100-K-3 pipeline and a portion of the 100-K-79 Subsite 7 pipeline were removed, as designed along with the 1706-KE, 1706-KEL, and 1706-KER buildings.

For the purposes of implementing and documenting remedial activities, the 100-K Area was divided into several informal remediation areas. The waste sites of this remedial activity were informally designated as being located within the Area AG Zone 2 remediation area, adjacent to the southwest corner of the reactor. Remediation of the Area AG, Zone 2 waste sites and removal of the below grade 1706-KE, 1706-KEL, and 1706-KER buildings began in June 2010. Remediated soil and debris disposed were of at the ERDF. Remediation of the waste sites coincided with the removal of the below ground portions of the 1706-KE, 1706-KEL, and 1706-KER buildings. Below-grade demolition 1706-KE and 1706-KER and waste site remediation completed in September 2011. The final maximum remediation depth of excavation for the area was 11.15 meters (36.58 ft) below ground surface.

Pipelines connected to the 1706-KE, 1706-KEL and 1706-KER buildings (excluding 100-K-3 associated pipelines) were gravity flow systems which drained away from the buildings to either the 100-K-47 Process Effluent Line, the 116-KE-2 Crib, the 1607-K4 or the 1607-K5 Sanitary Sewer System waste sites. Remediation of these pipelines was beyond the scope of the remedial action and this RSVP. However, during building removal, portions of these pipelines were removed to the edge of the excavation footprint. Although the ends of the pipelines were not capped due to the higher elevations at the pipeline openings, any residual liquids would flow away from the excavation footprint, rather than into it. Remediation of these pipelines will be completed at a later date during remediation of their respective waste sites. The GPS locations where the lines were severed at the sloped edge of the excavation footprint were documented.

The 100-K-36 dry well remediation area was approximately 0.17 square meters (1.83 sq. ft.). Due to the size of the sample area, only one discrete sample was collected. Following removal of all components of the 100-K-36 french drain waste site, stained soil was found adjacent to the waste site. In-process sampling indicated that copper, chromium and zinc were present in exceedance of the Remedial Action Goals. The stained soil area associated with 100-K-36 was approximately 54.0 square meters (581.3 square feet). Four sample increments were collected from randomly selected nodes within the stained soil sample area and combined into a single composite sample. The stained soil was removed to a depth of approximately 8 meters (26.2 ft) below grade.

The 100-K-79 confirmatory samples collected in August 2011 exceeded the RAGs for metals and the site was assigned a RTD remedy. Two samples were collected for the 100-K-79 Subsite 7 (partial) pipeline remediation area. One was a composite per the sample design. The other was a composite sample collected with the "sample as you go" strategy. The 100-K-79 Subsite 7 pipeline sample area was approximately 65.9 square meters (709.3 sq. ft.). It consisted of one sample area. Four sample increments were collected from randomly selected nodes within the sample area and combined into a single composite sample. The second composite sample was collected from the area extending from the end of the pipeline in AG Zone 2 to where it entered the pipe valve box south of the 105-KE Reactor.

The partial 100-K-3 pipeline remediation area was approximately 196.4 square meters (2,114.0 sq. ft). It consisted of three sample areas. Four sample increments were collected from randomly selected nodes within each sample area and combined into a single composite sample.

A portion of the sewer line discharging from the 1706-KER building was removed (40.8 sq.

meters [439.2 sq. feet]) incidental to the building removal. To evaluate this area, four sample increments were collected from randomly selected nodes within the sample area and combined into a single composite sample.

In August 2012, the sample results were received and excavation backfill activity began.

Code:	100-K-37	Classification:	Accepted
Names:	100-K-37; 1706-KE Sulfuric Acid Tank	Reclassification	Interim Closed Out (8/4/2010)
Type:	Storage Tank	Start Date:	1/1/1963
Status:	Inactive	End Date:	1/1/1986

Description: The waste site has been remediated and Interim Closed Out. It consisted of an above ground, vertical, stainless steel storage tank. The tank rested on a redwood timber deck above a 1.4 meter (4.45 foot) service space (at grade) that is protected by guard posts. A 5.1 centimeter (2 inch) fill line for tank truck usage was also located in the same area. Two 5.1 centimeter (2 inch) drain lines, one for vent and overflow and the other for valve leakage, entered a french drain (Site: 100-K-36) that was located (in the service area) between the caustic soda tank (100-K-38) and the sulfuric acid tank. The tank had a liquid level gauge, a 5.1 centimeter (2 inch) fill line, and a vent and overflow line. The top of the tank could be accessed via a ladder and platform at the top elevation of the tank. The tank was constructed with a bottom sloping towards the drain. When installed, the tank was shimmed to level it.

Location: The site was located southeast of the reactor and adjacent to the 1706-KE Building. 1706-KE Building, 0-Foot Level from the Part B Application shows the location of the tank.

Release Description: Site employees report that during operational history, the tank was rinsed down on a few occasions and the material went to the general soil area.

Related Sites/Structures: The site is related to the 1706-KE Building, 100-K-38, 1706-KE Caustic Soda Tank, and 100-K-36, 1706-KE Chemical Storage Facility Dry Well.

Process Description: The chemical storage facility at 1706-KE was installed in 1963 to provide bulk quantities of 93 percent by weight sulfuric acid and 50 percent by weight sodium hydroxide. The chemicals were used to regenerate the ion columns in the 1706-KE demineralizer plant. The demineralizer plant supplied demineralized water to two experimental single pass process tube in the 105-KE reactor core. The demineralizer plant was a duplex unit with two sets of ion columns. It operated with one set in service and the other either being regenerated or in a ready-standby condition. Typically three regenerations were performed each day during this period. Shipping manifests indicate that approximately 7,948.5 liters (2100 gallons) of sulfuric acid and 10,976.5 liters (2900 gallons) of sodium hydroxide were delivered to 1706-KE at 4-6 week intervals.

in 1971, the 100-K production reactors were shut down and the demineralizer plant was deactivated. It was reactivated some years later to provide demineralized water to the 100-K area fuel storage basins. The quantity of demineralized water produced during this period of operation was a small fraction of that produced during reactor operation. Thus, the number of regenerations was steadily reduced from an initial amount of approximately 12 times per year to 3 times per year when the demineralizer plant was finally taken out of service.

Waste Type: Chemicals

Waste Description: A heel of sulfuric acid remains on the bottom of the tank, and an unknown quantity of sulfuric acid remains in the transfer lines inside the 1706KE facility.

Closure Info: Interim: The 100-K-37 and 100-K-38 waste sites were removed using standard industrial equipment for structural demolition. The removed tanks and related debris were disposed at the

Environmental Restoration Disposal Facility on November 19, 2009 and November 23, 2009. Verification sampling was not required to demonstrate protectiveness for waste sites 100-K-37 and 100-K-38. The CERCLA removal action for the 1706-KE Building will address the underlying foundation.

Code:	100-K-38	Classification:	Accepted
Names:	100-K-38; 1706-KE Caustic Soda Tank	Reclassification	Interim Closed Out (8/4/2010)
Type:	Unplanned Release	Start Date:	1/1/1963
Status:	Inactive	End Date:	1/1/1986
Description:	The waste site has been remediated and Interim Closed Out The site consisted of contaminated soil from spills related to a caustic soda storage tank. The tank was an above ground, vertical, stainless steel storage tank. The tank rested on a redwood timber deck above a 1.4 meter (4.45 foot) service space (at grade) that is protected by guard posts. A 5.1 centimeter (2 inch) fill line for tank truck usage was also located in the same area. Two 5.1 centimeter (2 inch) drain lines, one for vent and overflow and the other for valve leakage, entered a french drain (Site: 100-K-36) that is located (in the service area) between the caustic soda tank and the sulfuric acid tank (Site: 100-K-37). The tank was insulated, had a liquid level gauge, a 5.1 centimeter (2 inch) fill line, a vent and overflow line, thermostat, and heating element. The top of the tank could be accessed via a ladder and platform at the top elevation of the tank. The tank was constructed with a bottom sloping towards the drain. When installed, the tank was shimmed to level it.		
Location:	The site is located in the southeast corner and adjacent to the 1706-KE Building. Figure B-4 1706-KE Building, 0-Foot Level from the Part B Application shows the location of the tank.		
Release Description:	Site employees report that during the operational history, spills occurred. The tank exterior was rinsed down after these spills and the material was released to the soil.		
Related Sites/ Structures:	The site is related to the 1706-KE Building, 100-K-37, 1706-KE Sulfuric Acid Tank, and 100-K-36, 1706-KE Chemical Storage Facility Dry Well.		
Process Description:	The chemical storage facility at 1706-KE was installed in 1963 to provide bulk quantities of 93 percent by weight sulfuric acid and 50 percent by weight sodium hydroxide. The chemicals were used to regenerate the ion columns in the 1706-KE demineralizer plant. The demineralizer plant supplied demineralized water to two experimental single pass process tube in the 105-KE reactor core. The demineralizer plant was a duplex unit with two sets of ion columns. It operated with one set in service and the other either being regenerated or in a ready-standby condition. Typically three regenerations were performed each day during this period. Shipping manifests indicate that approximately 7,948.5 liters (2100 gallons) of sulfuric acid and 10,976.5 liters (2900 gallons) of sodium hydroxide were delivered to 1706-KE at 4-6 week intervals. In 1971, the 100-K production reactors were shut down and the demineralizer plant was deactivated. It was reactivated some years later to provide demineralized water to the 100-K area fuel storage basins. The quantity of demineralized water produced during this period of operation was a small fraction of that produced during reactor operation. Thus, the number of regenerations was steadily reduced from an initial amount of approximately 12 times per year to 3 times per year when the demineralizer plant was finally taken out of service.		
Waste Type:	Chemicals		
Waste Description:	Site employees have reported that spills occurred at the site. The tank exterior was rinsed down after the spills and into the soil column. A white material that may be sodium hydroxide powder can be seen in the cracks of the lower level ceiling beneath the location of the tank base.		
Closure Info:	Interim: The 100-K-37 and 100-K-38 waste sites were removed using standard industrial equipment for structural demolition. The removed tanks and related debris were disposed at the		

Environmental Restoration Disposal Facility on November 19, 2009 and November 23, 2009. Verification sampling was not required to demonstrate protectiveness for waste sites 100-K-37 and 100-K-38. The CERCLA removal action for the 1706-KE Building will address the underlying foundation.

Code: 100-K-42 **Classification:** Accepted

Names: 100-K-42; 100-KE Fuel Storage Basin; 105-KE Fuel Storage Basin; Irradiated Fissile Material Storage; KE Basin; Metal Storage Basin; Potential Asbestos in Soil; 100-K East Basin; 100-K-40 **Reclassification:** None

Type: Storage **Start Date:** 1/1/1955

Status: Inactive **End Date:**

Description: The waste site is the fuel storage basin for the 105-KE Reactor. The fuel storage basin was demolished in 2009. It was located at the rear of the reactor. All that remains is a portion of the discharge chute that is attached to the reactor building. The slab of the basin was also been removed. Portions of the excavation were backfilled in 2012. Determination that asbestos containing material (ACM) was left in place and abated during demolition is based on a Quality Assurance review of project documentation and interviews with activity personnel.

The concrete basin area served as a collection, storage, and transfer facility for the irradiated fuel elements discharged from the reactor. Irradiated reactor fuel elements were stored at the bottom of large water filled storage basins pending their shipment to the chemical separations facilities in the 200 Areas. The water in the basins served both as coolant and as shielding. The basin consists of a discharge chute and fuel element pickup area, a storage area, a transfer area, and a wash pad area.

After reactor operations were terminated in 1975, a number of irradiated uranium fuel elements were found in both fuel storage basins when sludge was removed. Dorian and Richards (1978) reports that the 105-KW storage basin was cleaned, modified and being used for the storage of irradiated fuels from N Reactor. At the time of the report the 105-KE basin had been cleaned and was in the process of being modified for the same purpose. In 1974 and 1975, both basins were modified to a recirculating cooling system by the utilization of heat exchangers once used to transfer heat from the reactor cooling water elimination system to facility heating (Project H-501). The 105-KE basin has been used to store irradiated fuel in open containers. Consequently, the 105-KE basin is considered more radioactively contaminated than the 105-KW basin.

Location: The storage basin extended from the north wall of the 105-KE Reactor Building to the open area behind the reactor, with its longitudinal axis running parallel to the north wall of the building. Its east-west location was roughly in the center of the building.

Release Description: The 105-KE Fuel Storage Basin was constructed with a secondary seepage barrier in the form of an asphalt membrane under the basin floor. The 5.1 centimeters (2 inches) thick membrane was installed under the entire storage basin except for the pickup chute area and was designed to collect leakage in perforated pipes that lie on top of the membrane. These pipes drain to a sump. During testing that was conducted in 1974, a 16 day basin drawdown established a 15.1 liters per minute (4 gallons per minute) seepage rate from the basin system. At least 90 percent of this seepage was thought to be collected by the membrane system and sump. Two automatic pumps were installed in the sump to return any seepage back to the basin. 10 percent of the seepage was assumed to discharge to the soil beneath the basin. In mid-February 1977, an unusually high seep rate 51.1 liters (13.5 gallons per minute) was identified. The increased seepage was determined to have been caused by reduced basin water temperature, which caused concrete contraction to expand existing minor cracks in the basin. Detailed analysis showed that

no radioactivity was being released in liquid effluents from K Area and no water was being collected in the membrane drainage sump. Therefore, all of the seepage was assumed to be going to ground either through or past the membrane. A number of steps were taken to control and reduce the basin leakage, including maintaining higher basin temperatures, identification and repair of seep areas, use of ion exchange system to reduce cesium, and improving monitoring. In spite of the repairs, drawdown testing in 1979 showed that the basin was still leaking (See Releases Section). Eventually, an expansion joint in the floor of the basin discharge chute was isolated by water-tight dams that reduced leakage to a "near zero" rate of 11.4 liters (3 gallons per minute). During the 16 year operating history of the 105-KE Reactor, radioactive material most likely seeped from the basin to the soil beneath the facility through the same pathway that is open today. No direct measurements have been taken of the radionuclide inventories beneath the basin. The total estimated radionuclide inventories in the soil beneath the 105-KE Fuel Storage Basin (from operations between 1975 and 1979) are: cobalt-60 - 3.6 curies; strontium-90 - 1470 curies; cesium-137 - 1050 curies; plutonium-238 - 0.21 curies; plutonium-239/240 - 1.3 curies.

Related Sites/ Structures: The site is associated with the 105-KE Reactor Building, 116-KE-3 crib and UPR-100-K-1.

Process Description: The transfer area contained two sets of standard gauge railway tracks which extend into the building at ground level through the west wall. Adjacent to each track was a loading pit, which lead from the main basin. Irradiated metal slugs dropped from the rear or discharge face of the reactor through a discharge gate to the bottom of the bay between reactor and basin. A heavy rubber mattress was installed to cushion the fall of the slugs. The slugs were picked up by long handled tongs manipulated from the floor grating, and placed into buckets. The loaded buckets were suspended on the monorail conveyor system, and conveyed across and around the storage basin to the loading pits. This transfer was timed in short moves over a lengthy period so that the slugs are stored for some time in the storage basin, for the purpose of dissipating radioactivity. When the slugs reached the transfer area they were placed, still underwater, into large specially constructed containers called "casks". The loaded casks were hoisted from the bottom of the pits and placed on the cask cars, which were switched in on the adjacent tracks. The cars approximate were designed and built for the cask freightage. The viewing and weasel pits at the other end of the storage basin contained equipment for manipulating and examining selected slugs while under water. The function of the entire basin installation was to provide handling of radioactive metal under a shielding layer of water.

During the reactor refueling process, the fuel storage basins were used to receive the discharged fuel rods. New fuel elements were pushed into the process tube by a charging machine which caused the irradiated fuel elements in the tube to be displaced. The discharged irradiated fuel elements dropped into a water filled discharge chute and slid down into the metal pickup area at the end of the storage basin. The water in the chute area provided shielding as the elements accumulated and were sorted into buckets using long, hand-operated tongs. The buckets were then transferred by an overhead monorail system to the storage aisles where they were held for a time to allow the decay of short-lived radionuclides. Following the storage period, the buckets of fuel elements were moved by the overhead monorail system to the transfer area. At the transfer area, the irradiated fuel was loaded into a cask, then raised by a crane and placed in special railroad cars for shipment to the chemical reprocessing facilities in the 200 Area.

Occasionally, fuel elements would rupture or become damaged during handling and storage, causing contamination to the basin shielding water. Experience at other Hanford reactors suggests that the occurrence and inspections of the fuel element ruptures almost certainly occurred at both 100-KE and 100-KW basins throughout their operating histories.

Although the basins originally served the K Reactors, N Reactor fuel was accumulated from 1979 through 1987. Storage at K Basins was intended to be only as needed to sustain operation of N Reactor while the Plutonium and Uranium Recovery through Extraction Facility (PUREX)

was placed in standby for refurbishment and restart. Although PUREX processed much of the N Reactor fuel as planned, the decision by the Department of Energy in December 1993 to deactivate the PUREX facility left approximately 2,100 metric tons (2,310 tons) of N Reactor spent nuclear fuel in the K Basins with no provision for near term removal and processing.

Waste Type: Sludge

Waste Description: The spent nuclear fuel in the KE basin was in the form of irradiated uranium elements clad in aluminum or zirconium alloy and immersed in water. The fuel elements in the K East Basin were stored in open canisters. By-product material which includes corroded cladding, fuel particles, and insoluble plutonium and uranium metal had settled on the basin floor. Concrete debris resulting from erosion of the basin walls, transient soil and other types of dregs had also accumulated in the basins. This concurrent accumulation of various materials in the basins was commonly referred to by the Spent Nuclear Fuel (SNF) Project as the 100-K Basins sludge. The 100-K East Basin contained approximately 50 cubic meters of sludge.

Code: 100-K-43	Classification: Accepted
Names: 100-K-43; 105-KW Fuel Storage Basin; Irradiated Fissile Material Storage; K West Basin; KW Basin	Reclassification: None
Type: Storage	Start Date: 1/1/1955
Status: Active	End Date: 1/1/1971

Description: The site is the fuel storage basin for the 105-KW Reactor. The fuel storage basin is located at the rear of the reactor. The concrete basin area served as a collection, storage, and transfer facility for the irradiated fuel elements discharged from the reactor. Most of the basin is below grade. Irradiated reactor fuel elements were stored at the bottom of large water filled storage basins pending their shipment to the chemical separations facilities in the 200 Areas. The water in the basins served both as coolant and as shielding. The basin consists of a discharge chute and fuel element pickup area, a storage area, a transfer area, and a wash pad area.

The basin area is floored throughout at ground level with steel grating which is suspended from the steelwork of the roof above by means of vertical pipe columns. A grid of 32 monorails evenly spaced crosses the basin, overhead, from north to south, connects at the ends with a monorail which completely encircles the area. Bars suspended from trolleys which roll on these rails extend down through slots in the floor grating to a point near the bottom of the basin, where they support and carry buckets used for conveying the processed metal. Transverse rails extend from the outer rail loop into the transfer area at the west end of the basin, and the viewing and weasel pits at the east end. Crossovers are installed for switching the trolleys from track to track.

The transfer area contains two sets of standard gauge railway tracks which extend into the building at ground level through the west wall. Adjacent to each track is a loading pit, which leads off from the main basin. As the system functions, irradiated metal slugs drop from the rear or discharge face of the reactor through a discharge gate of special design to the bottom of the bay between reactor and basin. A heavy rubber mattress is installed here to cushion the fall. The slugs are picked up by long handled tongs manipulated from the floor grating, and placed into buckets. The loaded buckets are suspended on the monorail conveyor system, by which they are conveyed across and around the storage basin to the loading pits. This transfer is timed in short moves over a lengthy period so that in effect the slugs are stored for some time in the storage basin, for the purpose of dissipating radioactivity. When the slugs reach the transfer area they are placed, still underwater, into large specially constructed containers called "casks". The loaded casks are hoisted from the bottom of the pits and placed on the cask cars, which are

switched in on the adjacent tracks. The cars approximate standard railway equipment in size, and are designed and built for the cask freightage.

The viewing and weasel pits at the other end of the storage basin contain equipment for manipulating and examining selected slugs while under water. The function of the entire basin installation is to provide for handling radioactive metal under a shielding layer of water.

A number of irradiated uranium fuel elements were found in both fuel storage basins when sludge was removed in 1975 after reactor operations were terminated. Dorian and Richards (1978) reports that the 105-KW storage basin was cleaned, modified and being used for the storage of irradiated fuels from N Reactor. At the time of the report the 105-KE basin had been cleaned and was in the process of being modified for the same purpose. In 1974 and 1975, both basins were modified to a recirculating cooling system by the utilization of heat exchangers once used to transfer heat from the reactor cooling water elimination system to facility heating (Project H-501). The 105-KW basin has been used to store fuels in sealed storage containers. Consequently, the 105-KW basin is far less radioactively contaminated than the 105-KE basin.

Location: The storage basin extends from the north wall of the 105-KW Reactor Building to the open area behind the reactor, with its longitudinal axis running parallel to the north wall of the building. Its east-west location is roughly in the center of the building.

Related Sites/ Structures: The fuel storage basin is associated with the 105-KW Reactor Building (sitecode 118-KW-1) and Unplanned Release - sitecode 100-K-82.

Process Description: During the reactor refueling process, the fuel storage basins were used to receive the discharged fuel rods. New fuel elements were pushed into the process tube by a charging machine which caused the irradiated fuel elements in the tube to be displaced. The discharged irradiated fuel elements dropped into a water filled discharge chute and slid down into the metal pickup area at the end of the storage basin. The water in the chute area provided shielding as the elements accumulated and were sorted into buckets using long, hand-operated tongs. The buckets were then transferred by an overhead monorail system to the storage aisles where they were held for a time to allow the decay of short-lived radionuclides. Following the storage period, the buckets of fuel elements were moved by the overhead monorail system to the transfer area. At the transfer area, the irradiated fuel was loaded into a cask, then raised by a crane and placed in special railroad cars for shipment to the chemical reprocessing facilities in the 200 Area.

Occasionally, fuel elements would rupture or become damaged during handling and storage, causing contamination to the basin shielding water. Experience at other Hanford reactors suggests that the occurrence and inspections of the fuel element ruptures almost certainly occurred at both 100-KE and 100-KW basins throughout their operating histories. Although the basins originally served the K Reactors, N Reactor fuel was accumulated from 1979 through 1987. Storage at K Basins was intended to be only as needed to sustain operation of N Reactor while the Plutonium and Uranium Recovery through Extraction Facility (PUREX) was placed in standby for refurbishment and restart. Although PUREX processed much of the N Reactor fuel as planned, the decision by the Department of Energy in December 1993 to deactivate the PUREX facility left approximately 2,100 metric tons (2310 tons) of N Reactor spent nuclear fuel in the K Basins with no provision for near term removal and processing.

Waste Type: Sludge

Waste Description: The spent nuclear fuel in the KW basin was in the form of irradiated uranium elements clad in aluminum or zirconium alloy and immersed in water. The fuel elements in the K West Basin were stored in closed canisters. By-product material which included corroded cladding, fuel particles, and insoluble plutonium and uranium metal gas settled on the basin floor. Concrete debris resulting from erosion of the basin walls, transient soil and other types of dregs had also accumulated in the basins. This concurrent accumulation of various materials in the basins was commonly referred to by the Spent Nuclear Fuel (SNF) Project as the K Basins sludge. The K

West Basin contained relatively little sludge as compared with the K East Basin which had approximately 50 cubic meters (38.2 cubic yards) of sludge.

Code: 100-K-46	Classification: Accepted
Names: 100-K-46; 119-KE French Drain; Drywell	Reclassification: Interim Closed Out (8/29/2012)
Type: French Drain	Start Date: 1/1/1959
Status: Inactive	End Date:

Description: The waste site has been remediated and Interim Closed Out. It was a drywell that received drainage from a floor drain in the 119-KE Sample Building. The site had been covered with crushed rock and there was no visible evidence of the drywell on the ground surface.

Location: The drywell was located 8.7 meters (28.5 meters) from the east side of the 105-KE Reactor Building and 8 feet (2.4 meters) south of the 119-KE Sample Building.

Related Sites/ Structures: The drywell is associated with the 119-KE Sample Building.

Process Description: The 119-KE Sample Building was situated over the intake and exhaust ducts to the 117-KE Filter Building and was used to sample effluent gases and particulates. Floor drainage from the 119-KE Exhaust Air Sample Building was directed to the drywell by a 5 centimeter (2 in) pipe buried at least 0.9 m (3 ft) below grade. In addition, a 1.9 centimeter (0.75 in) pipe from the building evaporative cooler also connected into the 5 centimeter (2 in) floor drain pipe near the southern edge of the building and discharged into the 100-K-46 Waste Site.

Waste Type: Process Effluent

Waste Description: The drywell received effluent from the building's evaporative cooler. It is likely that the floor drain also received sample waste and janitorial waste since the building had no other drains or connections to the process sewer system. The drywell was potentially contaminated with cobalt-60, cesium-137, carbon-14, and tritium, as well as strontium-90, europium-152, europium-154, and europium-155 from the exhaust air system and heavy metals from the floor drain.

Closure Info: Interim (8/29/2012): Remediation and sampling began in January of 2009 and was completed in April of 2012. The large excavation area, known as 100-K Area AH, encompassed waste sites 100-K-6, 100-K-46, 100-K-62 and 132-KE-1. The excavation area also included Stockpile #4, which contained overburden and layback soil from the excavation of the 116-KE-1 Condensate Crib. Information supporting the use of Stockpile #4, located within the AH excavation, as backfill was also included in the DOE/RL-2012-38 Remaining Sites Verification Package report.

Remediation of the identified Area AH waste sites was accomplished by demolishing the structures and excavating contaminated soil. All waste (soil and debris) associated with these waste sites was disposed at the Environmental Restoration and Disposal Facility (ERDF). The demolition activities were conducted using standard demolition techniques, including explosives for demolition of 132-KE-1 (116-KE Reactor Exhaust Stack). Approximately 1,809 ERDF containers (37,700 tons) of waste from these waste sites were sent to the ERDF for disposal.

Remediation of the 100-K-6 vacuum pit began in August 2011 and was completed in September 2011. An excavator was used to remove the vacuum pit and excavate the surrounding soil. The original waste site description estimated the depth of the cyclone separator as 9.14 meters (30 ft). However, during remediation the actual excavation depth was measured as 5.8 meters (19 ft).

The remediation of the 100-K-46 french drain was associated with the removal of the 119-KE building, which began in January 2009 and was completed in February 2009. The drywell was less than 1.5 meters (5 ft) deep.

The remediation activities at the 100-K-62 filter building began in August 2010 and were completed in May 2011. An excavator was used to remove the vacuum pit and excavate the surrounding soil. The maximum depth from grade within the waste site footprint was approximately 10.6 meters (34.8 ft).

The remediation activities at waste site 132-KE-1 exhaust stack began in July 2010 and were completed in September 2011. Removal of the above-grade portion of the stack was conducted using explosives placed near the base of the stack. The explosion caused the debris to fall in a designated area. The material was then loaded and disposed at ERDF. The entire below grade portion of the stack base was then removed. The maximum depth from grade within the waste site footprint was approximately 6.1 meters (20 ft).

In October of 2010, excavation of the overburden and layback soil for the 116-KE-1 Crib began and Stockpile #4 was created. Samples were collected in the 116-KE-1 waste site footprint and sent for analytical leach testing of the soils to determine carbon-14 leachability from the 100-K soil. During remediation of the co-located waste sites inside the AH excavation area, the 116-KE-1 crib was partially backfilled with soil from Stockpile #4 as a contamination control measure.

Note: Area-wide carbon-14 contamination exists in the deep zone above the criteria for protectiveness. This contamination is associated with the 105-KE Reactor ventilation filtration system and the deep contamination from the condensate that collected in the previously excavated 116-KE-1 Condensate Crib. Additional remediation of the deep vadose zone cannot be completed in proximity to the 105-KE Reactor without impacting structural stability. Available information about the nature and extent of the carbon-14 contamination has been documented in the 116-KE-1 Condensate Crib waste site description. Due to the depth of the contamination, the carbon-14 remediation will coincide with the final decision on 105-KE reactor removal.

Code: 100-K-47	Classification: Accepted
Names: 100-K-47; 1904-K Process Sewer	Reclassification: None
Type: Process Sewer	Start Date: 1/1/1955
Status: Inactive	End Date:

Description: This site includes the underground process sewer pipelines that begin at the 105-KE Reactor, 105-KW Reactor, 165-KE, 190-KE, 1706-KE, and terminate either at the 116-K-3 Outfall or join the 100-K-56 Pipeline south of the outfall.

Manholes indicate the location of some sections of the process sewer. The main portion of the sewer that extends from the point of intersection of the 30.5 and 40.6 centimeter (12 and 16 inch) pipelines coming from 105-KW Reactor and 165-KE building with Manhole #5. This section is a 1.68 meters by 1.68 meters (66 inches by 66 inches) concrete sewer. All other process sewer pipelines are constructed of carbon steel. The pipelines near 100-K-71 include a 6 inch clean drain line, a 10 inch contaminated drain line, a 10 inch potentially contaminated drain line, a 6 inch rod cooling water line, a 6 inch drain line to the pluto crib, a 12 inch basin drain line, an 8 inch basin overflow line, a 6 inch vent line and a 4 inch vitrified clay decontamination drain line to the filter.

In 2002, approximately 600 feet of pipe, adjacent to 100-K-39, was removed. Portions of the

	100-K-47 pipeline, located in remediation area AG Zone 1, were removed in 2011.
Location:	This pipeline system includes process sewer lines from both the 105-KE and 105-KW reactor areas. The process sewer piping originates on the south (pre-reactor) and north (post-reactor) sides of the 105-KE and 105-KW Buildings. Portions run in an east-west direction to a point just west of the KE facilities and east of the KW facilities. The pipelines then run in a northerly direction to a point just south of the 116-K-3 Outfall where they intersect into a single discharge line to the Outfall structure.
Related Sites/ Structures:	These pipelines are associated with 165-KE, 190-KE, 105-KW, 105-KE, and 1706-KE. Pipeline 100-K-60 is the corresponding pipeline from 165-KW and joins 100-K-47 midway between the two reactors.
Process Description:	The process sewer system was used to dispose of treated and untreated waste water generated by the water treatment facilities, powerhouse, 1706-KE, and nonradioactive drains in the reactor facilities. The 100-K-47 waste site included underground process sewer pipelines that collected effluent from the 105-KE Reactor, the 105-KW Reactor, the 165-KE Facility, the 190-KE Facility, the 117-KE Filter Building, and the 1706-KE Facility, and either terminated at the 116-K-3 Outfall or joined the 100-K-56 waste site pipeline south of the outfall. Discharges into the 100-K-47 waste site included overflows from chemical makeup facilities that contained chemical additives for reactor cooling water, e.g., aluminum sulfate (alum), with excess hydrated calcium oxide, sulfuric acid, hexavalent chromium, and chlorine. Water pH was maintained at about 7.5, and free chlorine residual was about 0.3 mg/L. Other discharges to the system included filter backflush wastewater, coagulated sediments from the water treatment settling basins, demineralizer regeneration wastes, which included neutralized sulfuric acid and sodium hydroxide, brine wastes from water softeners, and pump cooling wastewater.
Waste Type:	Process Effluent
Waste Description:	Discharges included overflows from chemical makeup facilities that included chemical additives to reactor cooling water, e.g., aluminum sulfate (alum), with excess hydrated calcium oxide, sulfuric acid, and chlorine. Water pH was maintained at about 7.5, and free chlorine residual was about 0.3 milligrams per liter. Other discharges to the system included filter backflush waste water, coagulated sediments from the water treatment settling basins, demineralizer regeneration wastes, which included neutralized sulfuric acid and sodium hydroxide, brine wastes from water softeners, and pump cooling waste water.

Code:	100-K-48	Classification:	Accepted
Names:	100-K-48; 100-KE Oil Contamination Areas	Reclassification	None
Type:	Unplanned Release	Start Date:	
Status:	Inactive	End Date:	
Description:	The waste site is areas that show evidence of past fuel oil spills, especially around the railroad tracks. The spills have been absorbed into the soil and have formed an asphalt like substance. Some areas may have been covered with clean soil.		
Location:	The site is located in 100-K Area just north of the 166-KE Oil Storage Tank at the rail car holding point and just west of the 166-KE Oil Storage Tank.		
Release Description:	The site appears to be oil spillage from rail car off loading procedures. The oil appears to have been absorbed by sand and has formed a hard asphalt-like covering on the surface. It appears that the oil substance has exceeded the capacity of the sand absorbent and has formed a few tar-like patches of liquid oil that appear to be Bunker C type oil. There are some oil stains on the concrete tank top as well.		

Related Sites/ Structures: The site is related to the 166-KE Fuel Oil Storage Bunker.

Waste Type: Oil

Waste Description: The waste is oil solidified into a hard asphalt-like substance.

Code: 100-K-49 **Classification:** Accepted

Names: 100-K-49; 100-KW Oil Contamination Areas **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is areas that show evidence of past fuel oil spills, especially around the railroad tracks. The spills have been absorbed into the soil and have formed an asphalt like substance. The area between the 166-KW and the road south of 166-KW was discovered to be contaminated with oil during excavation of a trench for the Cold Vacuum Drying Facility. An oil contaminated layer of soil about 7.6 to 10.2 centimeters (3 to 4 inches) thick was discovered a few inches below the surface.

Location: The site is located in 100K Area and adjacent to the 166-KW Oil Storage Tank, extending to the road off the north and west sides of 166-KW Oil Storage Tank. The site also extends to the northwest to a depression located 50 to 60 meters (140 to 170 feet) west of the 105-KW Reactor. Due to the discovery of subsurface oil contamination the full extent of the contamination is unknown.

Release Description: The site appears to have been created from spills of fuel oil that occurred during off loading operations. The largest portion of the contamination appears to have been absorbed by sand and formed a hard asphalt-like substance. This substance begins at the railcar offloading area and extends down gradient from the tank to an area west of the 105-KW Reactor Facility.

Related Sites/ Structures: The site is related to the 166-KW Fuel Oil Storage Bunker.

Waste Type: Oil

Waste Description: The waste is oil solidified into a hard asphalt-like substance.

Code: 100-K-50 **Classification:** Accepted

Names: 100-K-50; 1725-K & 1726-K Sanitary Sewer System Holding Tank **Reclassification:** None

Type: Storage Tank **Start Date:** 1/1/1996

Status: Active **End Date:**

Description: The site is an underground, sanitary sewage holding tank that services 1725-K and 1726-K. The site is marked by eight red concrete posts. The tank is constructed of concrete and has three manholes on top and one hinged hatch cover. A 20.3 centimeter (8 inch) sanitary sewer pipeline runs in a north-south direction 9.1 meters (30 feet) east of the 1725-K (MO-293) and the 1726-K (MO-442) buildings into the south side of the holding tank. The tank is divided into two chambers. The normal operating volume is 11,355 liters (3000 gallons) and the total reserve volume is 17,032 liters (4500 gallons).

Location: The site is located approximately 35 meters (115 feet) south southeast of the southeast corner of the 183-KE Settling Basins and 9.1 meters (30 feet) east of 1725-K.

Related Sites/ Structures: The site is related to 1725-K, 1726-K, and 124-N-10. Both 1725-K and 1726-K are mobile offices with alias names of MO-293 and MO-442, respectively.

Process Description: The holding tank collects septage from 1725-K and 1726-K mobile offices. Periodically, the septage is pumped out and taken to the 124-N-10 Sewage Lagoon for disposal.

Waste Type: Sanitary Sewage

Waste Description:

Code: 100-K-53 **Classification:** Accepted

Names: 100-K-53; 100-KE Glycol Heat Recovery Underground Pipelines **Reclassification:** Interim Closed Out (8/29/2012)

Type: Product Piping **Start Date:** 1/1/1955

Status: Inactive **End Date:** 1/1/1971

Description: This waste site has been remediated and Interim Closed Out. It included two underground pipelines that transported glycol solutions from the 116-KE-5 (150 KE Heat Recovery Station) to their entrance to the 165-KE Powerhouse (Power Control Building) facilities. The pipelines consist of two 0.46-meter (1.5-foot) steel supply and return pipelines. It does not include the above-grade pipelines at the 116-KE-4 Station, the 100-K-7 Storage Tanks and piping, or the pipelines housed within these facilities. The waste site consisted two pipelines; one 0.46-meter (1.5-ft) diameter steel supply and one 0.46-m (1.5-ft) diameter steel return pipeline. The two pipelines ran parallel to each other and were buried approximately 1.5 meters (5 ft) below grade surface.

Location: The pipelines were located east of the 105-KE Reactor building. They originated at the 116-KE-5 (150-KE Heat Recovery Station) and terminated at the 165-KE Building north wall. The pipelines ran in a north-south direction.

Related Sites/ Structures: The site was associated with 116-KE-5 (150-KE Heat Recovery Station) and 165-KE (Power Control Building).

Process Description: This system was used to distribute heat taken, via a heat exchanger (116-KE-5, 150-KE Heat Recovery Station) to area buildings for space heating and process needs. The facilities, makeup and storage tanks where the pipelines terminated are not included. The heat recovery station was used to transfer heat from the 105-KE Reactor cooling water effluent. The pipelines contained an ethylene glycol and water solution that was maintained at a slightly positive pressure to preclude leakage of reactor effluent water into the system.

Waste Type: Chemicals

Waste Description: The waste is pipelines that contained an ethylene glycol/water solution that was maintained at a slightly positive pressure to preclude leakage of reactor effluent water into the system via the 150-KE Heat Exchanger.

Closure Info: Interim (8/29/2012): The remediation of the 100-K-53 Waste Site began in May 2010 and was completed in July 2011. Remediation of the pipelines had to be completed in stages due to interference from other buildings and waste sites, which required removal first to provide access to the remaining 100-K-53 pipelines. The ethylene glycol was drained from the pipelines inside the 165-KE Powerhouse and solidified for disposal at ERDF. Excavation and removal of the pipelines then began on the north end. The pipelines were again checked for any ethylene

glycol holdup at the first valve box on that north end and then the piping and valves were removed. As remediation progressed to the south, the pipelines were removed along with other structures and waste sites, which resulted in a deeper excavation (approximately 5.8 to 6.1 meters [19 to 20 ft]) on the east side of the 105-KE Reactor. During remediation, a new substation was built near the south end of the pipelines, resulting in a power line interference. The portion of the pipeline required to remain in place was filled with grout. This interference deviated from the original design drawing for the remediation of the 100-K-53 Waste Site. The remediation of the waste site was completed by removal of the two ethylene glycol pipelines, except for the grouted portion left in place due to the power line interference. The grouted pipelines will remain in place and require no further remediation. The pipeline remediation ended outside the north end of the 165-KE Powerhouse. No holdup of ethylene glycol was found during removal of the pipelines. The pipelines and soils (a total of 22,240 tons) that were excavated were disposed of at the ERDF. No stockpiling of soils was completed during the remediation of 100-K-53.

The deep zone underneath the footprint of 100-K-53 is contaminated with carbon-14 from the reactor ventilation filtration system. The contamination is not associated with 100-K-53, but is associated with the nearby 116-KE-1 Condensate Crib waste site. This residual contamination will be remediated at a future date, and the 100-K-53 waste site and adjacent area will have institutional controls in place until it is remediated.

Code:	100-K-54	Classification:	Accepted
Names:	100-K-54; 100-KW Glycol Heat Recovery Underground Pipelines	Reclassification	None
Type:	Product Piping	Start Date:	1/1/1955
Status:	Inactive	End Date:	1/1/1971
Description:	This site includes those underground pipelines that transported glycol solutions from the 116-KW-4 (150 KW Heat Recovery Station) to their entrance into the 165-KW Powerhouse (Power Control Building) facilities. The pipelines consist of two 0.46-meter (1.5-foot) steel supply and return pipelines. It does not include the above-grade pipelines at the 116-KW-4 Station, the 100-K-8 Storage Tanks and piping, or the pipelines housed within these facilities.		
Location:	The pipelines originate at the 116-KW-4 (150-KW Heat Recovery Station) and terminate at the 165-KW Building north wall. Generally, the pipelines run in a north-south direction (K-Area Hanford Plant Grid). Because the pipelines are housed within facilities from the point where they enter the 165-KW Building, the housed sections are not included as a part of this site.		
Related Sites/ Structures:	The site was associated with 116-KW-4 (150-KW Heat Recovery Station) and 165-KW (Power Control Building).		
Process Description:	This system was used to distribute heat taken, via a heat exchanger (116-KW-4, 150-KW Heat Recovery Station) to area buildings for space heating and process needs. The facilities, makeup and storage tanks where the pipelines terminated are not included.		
Waste Type:	Chemicals		
Waste Description:	The waste is pipelines that contained an ethylene glycol/water solution that was maintained at a slightly positive pressure to preclude leakage of reactor effluent water into the system via the 150-KW Heat Exchanger.		

Code:	100-K-55	Classification:	Accepted
Names:	100-K-55; 100-KR-1 Pipelines; 100-KW Reactor	Reclassification	None

coupling connected. Concrete anchors were provided at each turn in the pipeline. The motor operated valves in the effluent system were controlled from the 105-KW Building Control Room. Miscellaneous piping included pipes to the 116-K-1 Crib, 116-K-2 Trench, and process sewer and piping to and from the 150-KW Heat Recovery Building. Discharges to 116-K-1 and 116-K-2 were made via 910-millimeter (36-inch) pipes that combined to flow into a 1,070-millimeter (42-inch) steel main pipe. Discharges to the process sewer were made through 250-millimeter (10-inch) steel pipes that combined into a 360-millimeter (14-inch) steel main pipe. Effluent from the 150-KW Building consisted of a 610-millimeter (24-inch), 460-millimeter (18-inch), 100-millimeter (4-inch) and 76-millimeter (3-inch) steel effluent piping system. Effluent from the 105-KW and 150-KW Buildings could bypass the retention basins through a 910-millimeter (36-inch) or a 300-millimeter (12-inch) steel pipe. Pipe depth varied from 1.3 meters (4 feet) to 9.7 meters (32 feet). The deepest pipes ran under an elevated contour that coincided with the retention basin exclusion fence.

Waste Type: Process Effluent

Waste Description: The waste was contaminated steel piping, concrete, and soil. Chemical additives to reactor cooling water included aluminum sulfate (alum) with excess hydrated calcium oxide, sulfuric acid, chlorine, diatomaceous earth (a scouring agent), and sodium dichromate. Water pH was maintained at about 7.5, and free chlorine residual was about 0.2 milligrams per liter. Radionuclide content at the retention basin during sampling by Richards for UNI-946, included the following: cesium-134, plutonium 239/240, cesium-137, strontium-90, hydrogen-3, nickel-63, europium-152, europium-154, europium-155, and cobalt-60.

This Site has the Following SubSites:

Code: 100-K-55:1

Names: 100-K-55:1; Process Pipelines Outside of Reactor Fence to Outfall

Code: 100-K-55:2

Names: 100-K-55:2; Effluent Pipelines Inside 105KW Reactor Security Fence

Code: 100-K-55:1

Classification: Accepted

Names: 100-K-55:1; Process Pipelines Outside of Reactor Fence to Outfall

Reclassification: Interim Closed Out (9/23/2005)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: Subsite 1 was remediated and Interim Closed Out. Remedial action activities involved excavation and staging of overburden material and removal of contaminated piping, debris, and soil. The project began on December 9, 2002. Contaminated materials were disposed at the ERDF.

Subsite 1 included the underground process effluent pipelines located on the north side of 105 KW Reactor, from the outside of the security fence to the active utilities 116-K-1 Crib, 116-K-2 Trench and 116-KE-4 Retention Basin, and the Process Water Pipeline between Reactors.

Location: The Process Pipelines were located outside of 105-KW Reactor Security Fence and extended to 116-K-3 Outfall.

Waste Type: Not Specified

Waste Description: The waste is contaminated piping, debris, and soil.

Closure Info: Interim: Remedial action activities at the 100-K reactor effluent pipelines began on December

9, 2002 by Washington Closure Hanford (WCH). Remediation of the pipelines involved excavation and staging of overburden material and removal of contaminated piping, debris and soil at the 100-K-55:1, 100-K-56:1, 116-KW-4 and 116-KE-5 waste sites. Contaminated materials were disposed at the ERDF. Remedial action excavation was completed on April 15, 2005. The previously documented waste site boundaries for the 116-KW-4 and 116-KE-5 sites were much larger than the actual footprint of the heat recovery facilities. The soil area beneath each of the former heat recovery stations was excavated in its entirety with the removal of the co-located pipelines. Approximately 55,960 square meters (602,350 sq ft) of plan area was excavated, including excavation within the deep zone (greater than 4.6 meters [15 ft] below ground surface) up to 8.8 meters (29 ft) below ground surface where necessary to complete remediation. Approximately 86,551 metric tons (95,406 U.S. tons) of material from the sites was removed and disposed at the ERDF. The active 100-K-47 concrete culvert was not removed during remediation of the adjacent section of the 100-K-55 pipeline. Several 100-K-56 pipe segments, located west of 116-KE-4, were not included in the remediation scope.

The contaminated materials from these sites have been excavated and disposed at the ERDF. The remaining soils at the sites have been sampled, analyzed, and modeled, and the results do not preclude any future uses (as bounded by the rural-residential scenario), allow unrestricted use of shallow zone soils, and pose no threat to groundwater or the Columbia River. The 100-K-55:1, 100-K-56:1, 116-KW-4, and 116-KE-5 sites were verified to be remediated in accordance with the ROD and may be backfilled.

The SubSite is Part Of:

Code: 100-K-55

Names: 100-K-55; 100-KR-1 Pipelines; 100-KW Reactor Cooling Water Effluent Underground Pipelines

Code: 100-K-55:2

Classification: Accepted

Names: 100-K-55:2; Effluent Pipelines Inside 105KW Reactor Security Fence

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: Subside 2 consists of the remaining portion of the underground effluent pipeline inside the reactor security fence and some segments near the 116-K-1 Crib, the 116-KW-3 Retention Basin and the 116-K-2 Trench. The ends of the pipelines that were exposed when remediating 100-K-55:1 were covered with plywood prior to backfilling.

Location: The pipelines ran in a north-south direction, north of the 105-KW Reactor Building to the reactor security fence.

Waste Type: Not Specified

Waste Description: The waste is contaminated steel piping, concrete, and soil.

The SubSite is Part Of:

Code: 100-K-55

Names: 100-K-55; 100-KR-1 Pipelines; 100-KW Reactor Cooling Water Effluent Underground Pipelines

Code: 100-K-56

Classification: Accepted

Names: 100-K-56; 100-KE Reactor Cooling Water Effluent Underground Pipelines; 100-KR-1

Reclassification: None

 Pipelines

Type: Radioactive Process Sewer **Start Date:** 1/1/1955
Status: Inactive **End Date:** 1/1/1971

Description: The waste site is the gravity flow effluent pipelines that serviced the 105-KE Reactor. They terminated at the 116-K-1 Crib, the 116-K-2 Trench, and the 116-KE-4 retention basins. The effluent lines were primarily carbon steel pipes ranging in size from 3 inches to 72 inches in diameter. This site has been divided into of three subsites.

Subsite 1 has been remediated and Interim Closed Out. Subsite 1 included the underground process effluent pipelines north of the 105 KE Reactor from the outside of the security fence. The pipelines terminated at the 116-K-1 Crib, the 116-K-2 Trench, and the 116-KE-4 Retention Basins. A portion of 100-K-56:1 was removed with the excavation of the 116-K-1 crib in 2003. The remainder of 100-K-56:1 was remediated and Interim Closed Out in 2005.

Subsite 2 consists of 36 inch and 72 inch diameter process effluent underground pipelines located inside the original 100-K Area security fence (note: the fence has now been removed). These pipelines exited the west side of 105-KE reactor. The 72 inch line extended beyond the former security fence, and was addressed with Subsite 1. The 36 inch line tied into the 100-K-47 concrete sewer. The 100-K-56:2 pipeline that was located in remediation area AG Zone 1 and Zone 3 (northwest of 105KE) was removed in 2011.

Subsite 3 consists of process sewer pipeline segments located near the 116-K-3 Outfall Structure and the 116-K-4 Retention Basins. These pipe segments are adjacent to the remediated 100-K-56:1 excavation area. They were not considered part of the remediation scope in 2003 and were left in place.

In the interest of preserving the reactor security fence and some active underground utility features, some segments of pipe were not removed in 2002-2005.

Location: The pipelines mostly run in a north-south direction, northeast of the 105-KE Reactor Building.

Related Sites/ Structures: The waste site is related to the 105-KE Reactor, 100-K-79, the 116-K-3 Outfall, the 100-K-83 Spillway, the 100-K-80 River Pipelines, the 116-K-1 Crib, the 116-K-2 Trench, the 150-KE, and the 116-KE-4 Retention Basins.

Process Description: The effluent system transported the reactor process effluent water by means of gravity flow to the river. There, the effluent water was discharged underwater to be diluted both thermally and radioactively by the flow of the river. The effluent system piping was located underground to provide shielding from the radioactive water. Before the water was discharged into the river, it was held for a period of time in retention basins, located approximately midway between the reactor building and the river, to allow decay of short-lived radioisotopes. In addition, the basins served to hold up flow of effluent with high radioactive isotope concentrations resulting from a ruptured fuel element. This effluent could be isolated and diverted by gravity to an open pond area, from which the effluent filtered through the ground before discharging to the river. Between the 105-KE Reactor Building downcomer outlet and the diversion valve box at the inlet of the 107-KE Retention Basins, the effluent pipeline was a single, 1.83-meter (72-inch), carbon steel pipeline measuring 277 meters (908 feet) in length. At the diversion valve box the flow could be diverted to any or all of the three retention basins by three, motor-operated, 1.83-meter (72-inch), butterfly valves. A 1.83-meter (72-inch) bypass pipeline was provided around the diversion valve station. This bypass pipeline tied into the inlet piping of one of the retention basins. During normal operation of the effluent system, flow was restricted in this bypass pipeline by an inverted 'U' bend which extended 9.1 meters (30 feet) higher than the elevation of the diversion valve station. However, if all the valves closed, the effluent water flowed over the inverted 'U' bend and into the basin. The inlet 1.83-meter (72-inch) effluent piping ran to

the side of a basin and discharged into an inlet chute, which in turn discharged to the bottom of the basin. The basin discharged to the river through a sump at the center of the basin. The basin discharge piping extended from the sump beneath the basins in reinforced concrete tunnels at the sides of the basins. The basin discharge piping was 1.7-meter (66-inch) carbon steel piping. The basin discharge piping combined into a common effluent pipeline. This pipeline discharged into the outfall structure. The common effluent from the 105-KE Reactor was a 1.7-meter (66-inch) pipeline. The combined length of the discharge pipes from the three basins was 752 meters (2,469 feet). The effluent pipe system was Dresser coupling connected. Concrete anchors were provided at each turn in the pipeline. The motor operated valves in the effluent system were controlled from the 105-KE Building Control Room. Miscellaneous piping included pipes to the 116-K-1 Crib, 116-K-2 Trench, and process sewer and piping to and from the 150-KE Heat Recovery Building. Discharges to 116-K-1 and 116-K-2 were made via 910-millimeter (36-inch) pipes that combined to flow into a 1,070-millimeter (42-inch) steel main pipe. Discharges to the process sewer were made through 250-millimeter (10-inch) steel pipes that combined into a 360-millimeter (14-inch) steel main pipe. Effluent from the 150-KE Building consisted of a 610-millimeter (24-inch), 460-millimeter (18-inch), 100-millimeter (4-inch) and 76-millimeter (3-inch) steel effluent piping system. Effluent from the 105-KE and 150-KE Buildings could bypass the retention basins through a 910-millimeter (36-inch) or a 300-millimeter (12-inch) steel pipe. Pipe depth varied from 1.3 meters (4 feet) to 9.7 meters (32 feet). The deepest pipe ran under an elevated contour that coincided with the retention basin exclusion fence.

Waste Type: Process Effluent

Waste Description: The waste was contaminated steel piping, concrete, and soil. Chemical additives to reactor cooling water included aluminum sulfate (alum) with excess hydrated calcium oxide, sulfuric acid, chlorine, diatomaceous earth (a scouring agent), and sodium dichromate. Water pH was maintained at about 7.5, and free chlorine residual was about 0.2 milligrams per liter. Radionuclide content at the retention basin during sampling by Richards for UNI-946, included the following: cesium-134, plutonium 239/240, cesium-137, strontium-90, hydrogen-3, nickel-63, europium-152, europium-154, europium-155, and cobalt-60.

This Site has the Following SubSites:

Code: 100-K-56:1

Names: 100-K-56:1; 105-KE Reactor Process Effluent North of the Security Fence; Process Water Pipeline Between 105-KE Reactor and 116-K-3 Outfall, 116-K-2 Trench and 116-KE-4 Retention Basin

Code: 100-K-56:2

Names: 100-K-56:2; Effluent Pipelines Inside the 105-KE Reactor Security Fence

Code: 100-K-56:3

Names: 100-K-56:3; Remaining Pipeline near 116-K-3 Outfall Structure

Code: 100-K-56:1

Classification: Accepted

Names: 100-K-56:1; 105-KE Reactor Process Effluent North of the Security Fence; Process Water Pipeline Between 105-KE Reactor and 116-K-3 Outfall, 116-K-2 Trench and 116-KE-4 Retention Basin

Reclassification: Interim Closed Out (9/23/2005)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: 100-K-56 subsite 1 has been remediated and Interim Closed Out. The 100-K-56 pipelines consisted of the gravity-flow process effluent pipelines that formerly serviced the 105-KE

Reactor, terminating at the 116-K-1 Crib, the 116-K-2 Trench, and the 116-KE-4 retention basins. Subsite 1 is the portion of pipeline from the 105-KE reactor building to the 116-K-1 Crib, the 116-K-2 Trench, and the 116-KE-4 retention basins. A portion of the pipeline was removed during the remediation of the 116-K-1 crib.

Location: The pipelines ran from outside the 105-KE Reactor security fence to the 116-K-1 Crib, the 116-K-2 Trench, and the 116-KE-4 retention basins.

Related Sites/ Structures: The remediated pipelines are associated with the 100-K-56:3 pipe segments that were left in place.

Waste Type: Not Specified

Waste Description: The waste is contaminated steel piping, concrete, and soil.

Closure Info: Interim: Remedial action activities at the 100-K reactor effluent pipelines began on December 9, 2002 by Washington Closure Hanford (WCH). Remediation of the pipelines involved excavation and staging of overburden material and removal of contaminated piping, debris and soil at the 100-K-55:1, 100-K-56:1, 116-KW-4 and 116-KE-5 waste sites. Contaminated materials were disposed at the ERDF. Remedial action excavation was completed on April 15, 2005. The previously documented waste site boundaries for the 116-KW-4 and 116-KE-5 sites were much larger than the actual footprint of the heat recovery facilities. The soil area beneath each of the former heat recovery stations was excavated in its entirety with the removal of the co-located pipelines. Approximately 55,960 square meters (602,350 sq ft) of plan area was excavated, including excavation within the deep zone (greater than 4.6 meters [15 ft] below ground surface) up to 8.8 meters (29 ft) below ground surface where necessary to complete remediation. Approximately 86,551 metric tons (95,406 U.S. tons) of material from the sites was removed and disposed at the ERDF. The active 100-K-47 concrete culvert was not removed during remediation of the adjacent section of the 100-K-55 pipeline. Several 100-K-56 pipe segments, located west of 116-KE-4, were not included in the remediation scope.

The contaminated materials from these sites have been excavated and disposed at the ERDF. The remaining soils at the sites have been sampled, analyzed, and modeled, and the results do not preclude any future uses (as bounded by the rural-residential scenario), allow unrestricted use of shallow zone soils, and pose no threat to groundwater or the Columbia River. The 100-K-55:1, 100-K-56:1, 116-KW-4, and 116-KE-5 sites were verified to be remediated in accordance with the ROD and may be backfilled.

The SubSite is Part Of:

Code: 100-K-56

Names: 100-K-56; 100-KE Reactor Cooling Water Effluent Underground Pipelines; 100-KR-1 Pipelines

Code: 100-K-56:2

Classification: Accepted

Names: 100-K-56:2; Effluent Pipelines Inside the 105-KE Reactor Security Fence

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: 100-K-56 Subsite 2 consists of the 1.8 meter (72 in.) diameter pipeline and a 91 cm (36 in.) diameter underground effluent pipeline located inside the 105-KE Reactor security fence (although this fence has since been removed). Both the 91 cm (36 in.) and 1.8 meter (72 in.) diameter process effluent underground pipelines exited the west side of the 105-KE Reactor. The 91 cm (36 in.) diameter pipeline connected with the 100-K-3 heat exchanger pit and pump

pit and traveled north and turned northwest to tie into the 1.68 meter by 1.68 meter (66 in.) 100-K-47 concrete sewer. Short lengths of 5.1 cm (2 in.) and 15.2 cm (6 in.) diameter pipelines connected the 91 cm (36 in.) diameter process effluent line to the 100-K-3 pump pit. The 1.8 meter (72 in.) diameter pipeline exited the reactor and continued north for approximately 90 meters (295 ft.), where it passed under the security fence and became 100-K-56 Subsite 1.

A portion of the 100-K-56:2 pipeline, located in remediation area AG Zone 1 (northwest of 105KE), was removed during 2009 through 2011. The 0.9 m (36 in.) pipeline, located in remediation area AG Zone 3 was also removed in 2011. Sample Area #15 of this excavation site exceeded remediation goals for Eu-152 and received a cover of backfill material. The 1.8 meter (72 in.) diameter pipeline connected to the 100-K-3 heat exchanger pit via a 7.6 cm (3 inch) diameter pipeline. The pipelines connecting the 0.9 meter (36 in.) and 1.8 meter (72 in.) pipelines to 100-K-3 were removed during this activity.

Location: The pipelines run in a north-south direction, north of the 105-KW Reactor Building inside the reactor security fence. They exit the north side of the reactor building and turn north.

Waste Type: Not Specified

Waste Description: The waste is contaminated steel piping, concrete, and soil.

The SubSite is Part Of:

Code: 100-K-56

Names: 100-K-56; 100-KE Reactor Cooling Water Effluent Underground Pipelines; 100-KR-1 Pipelines

Code: 100-K-56:3

Classification: Accepted

Names: 100-K-56:3; Remaining Pipeline near 116-K-3 Outfall Structure

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: Subsite 3 consists of process sewer pipeline segments located near the 116-K-3 Outfall Structure and the 116-K-4 Retention Basins. These pipe segments are adjacent to the remediated 100-K-56:1 excavation area. They were not considered part of the remediation scope in 2005 and were left in place.

The pipe segments either terminated at the 116-K-3 outfall, or tied into the 100-K-47 and 100-K-55 pipelines near the 1908-KE building.

Location: The pipe segments are located north of the 100-KE reactor operation area.

The SubSite is Part Of:

Code: 100-K-56

Names: 100-K-56; 100-KE Reactor Cooling Water Effluent Underground Pipelines; 100-KR-1 Pipelines

Code: 100-K-60

Classification: Accepted

Names: 100-K-60; 1904-K Process Sewer (165-KW)

Reclassification: None

Type: Process Sewer

Start Date: 1/1/1955

Status: Inactive

End Date:

Description: This site includes the underground process sewer pipeline that begins at 165-KW and runs up to the point of intersection with the 30.5 and 40.6-centimeter (12 and 16-inch) pipelines coming from 105-KW Reactor. The portion of the sewer that extends from the 165-KW Building to the point of intersection with the 30.5 and 40.6-centimeter (12 and 16-inch) pipelines coming from 105-KW Reactor is a 1.68 by 1.68-meter (66 by 66-inch) concrete sewer.

This site does not include those underground process sewer pipelines that begin at the 105-KE Reactor, the 105-KW Reactor, the 165-KE, the 190-KE, or the 1706-KE, and terminate at the 116-K-3 Outfall. These components are included in 100-K-47. The site has been split because of the different programmatic responsibilities associated with the two sites.

The site does not include the facilities where the pipelines terminate, or pipelines that are housed within building structures, which are addressed separately. This site does not include the radioactive process sewer pipelines, water supply pipelines, glycol heat pipelines, or other reactor effluent underground pipelines addressed by other sites.

Location: The process sewer originates on the north side of 165-KW and runs east and then northeast to a point where it meets the process sewer pipelines coming from 105-KW. At that point the site is described in 100-K-47.

Related Sites/ Structures: The site is related to the 165-KW Building.

Waste Type: Process Effluent

Waste Description: Discharges included overflows from chemical makeup facilities that included chemical additives to reactor cooling water, e.g., aluminum sulfate (alum), with excess hydrated calcium oxide, sulfuric acid, and chlorine. Water pH was maintained at about 7.5, and free chlorine residual was about 0.3 milligrams per liter. Other discharges to the system included: filter backflush waste water; coagulated sediments from the water treatment settling basins; demineralizer regeneration wastes, which included neutralized sulfuric acid and sodium hydroxide; brine wastes from water softeners; and pump cooling waste water.

Code: 100-K-61	Classification: Accepted
Names: 100-K-61; 117-KW Filter Building and Duct Work	Reclassification: None
Type: Process Unit/Plant	Start Date: 1/1/1960
Status: Inactive	End Date: 1/1/1970

Description: The ventilation exhaust filter building houses blowers and particulate filters used to treat the ventilation exhausted from the 105-KW Reactor Building. Included in this site are the 117-KW Building, the intake ventilation duct from the 105-KW Reactor Building, and the exhaust ventilation ducts to the 116-KW Reactor Exhaust Stack. A large portion of the building is below ground. The building and duct work are all made of reinforced concrete, 0.3 to 0.6 meters (1 to 2 feet) thick. The building is 12.2 meters (40 feet) high with 2.4 meters (8 feet) above grade. A soil berm is built up around the building from grade level to the top of the structure. The hatch on the top of the above ground portion of the filter structure is posted as Contamination Area and Danger-Restricted Area, Multiple Hazards.

The building is divided into two large filter cells with a smaller operating area between them. The filter cells each held six filter frames (two wide and three deep). The filter frames were designed to hold thirty-six filters that were 0.6 meters (2 feet) square by 0.3 meters (1 foot) thick. There are spaces between the frames to allow access for filter maintenance. The operating area between the two cells is divided into two levels. The upper level, called the access gallery

has ten doors that lead from it. Four doors open into each of the filter cells and the two other doors provide access to the intake and exhaust ducts. The operating gallery is located below the access gallery. A sump is located at each end of the operating gallery to collect incidental drainage from above. A large open area extends the full length of the structure above the access gallery and the filter cells. It ranges in height between 2.5 and 2.4 meters (8.1 and 7.8 feet) due to the structure's sloping roof. The space provides access to the cement cover blocks that are positioned over each of the filter frames.

Location: The 117-KW Filter Building is located east of the 105-KW Reactor Building, northeast of the 116-KW Reactor Exhaust Stack.

Related Sites/Structures: The site is associated with the 105-KW Reactor (118-KW-1), the 116-KW Reactor Exhaust Stack (132-KW-1), the 119-KW Sample Building, and the 1904-K Process Sewer (100-K-47).

Process Description: The 117-KW Building was constructed as part of the reactor confinement project. Prior to its use, unfiltered ventilation was exhausted directly from the reactor to the atmosphere. The confinement project diverted the exhaust just before the stack and routed it to the filter building where it passed through a series of filters. The filtered exhaust was then routed back to the ventilation exhaust stack where it was discharged to the atmosphere. Sealwells within the filter building provided the ability to direct the exhaust into one or both of the filter cells.

Waste Type: Equipment

Waste Description: The building contains radiologically contaminated equipment and surfaces that remain from when it was in use.

Waste Type: Demolition and Inert Waste

Waste Description: When the 116-KW Reactor Exhaust Stack was shortened, the debris was placed inside the stack. Some debris is probably within the exhaust duct connecting the filter building to the stack.

Code: 100-K-62	Classification: Accepted
Names: 100-K-62; 117-KE Filter Building	Reclassification: Interim Closed Out (8/29/2012)
Type: Process Unit/Plant	Start Date: 1/1/1960
Status: Inactive	End Date: 1/1/1971

Description: The waste site has been remediated and Interim Closed Out. It was the 117-KE filter building. The 117-KE Filter Building housed particulate and activated charcoal filters to treat the ventilation exhaust air from the 105-KE Reactor. The structure also contained a small exhaust system for use during filter changes.

Location: The 117-KE Filter Building was located east of the 105-KE Reactor Building, northeast of the 116-KE Reactor Exhaust Stack.

Related Sites/Structures: The site is associated with the 105-KE Reactor (118-KE-1), the 116-KW Reactor Exhaust Stack (132-KE-1), the 119-KE Sample Building, and the 1904-K Process Sewer (100-K-47).

Process Description: The 117-KE Building was constructed as part of the reactor confinement project. Prior to its use, unfiltered ventilation was exhausted directly from the reactor to the atmosphere. The confinement project diverted the exhaust just before the stack and routed it to the filter building where it passed through a series of filters. The filtered exhaust was then routed back to the ventilation exhaust stack where it was discharged to the atmosphere. Sealwells within the filter building provided the ability to direct the exhaust into one or both of the filter cells.

Waste Type: Equipment

Waste Description: The building contains radiologically contaminated equipment and surfaces that remain from when it was in use. Sections of the 117-KE Filter Building and associated tunnels were contaminated with cobalt-60, cesium-137, carbon-14, and tritium, as well as strontium-90, europium-152, europium-154, and europium-155.

Waste Type: Misc. Trash and Debris

Waste Description: When the 116-KE Reactor Exhaust Stack was shortened, the debris was placed in the "below ground interior portion" of the stack. Some debris is probably within the exhaust duct connecting the filter building to the stack.

Closure Info: Interim (8/29/2012): Remediation and sampling began in January of 2009 and was completed in April of 2012. The large excavation area, known as 100-K Area AH, encompassed waste sites 100-K-6, 100-K-46, 100-K-62 and 132-KE-1. The excavation area also included Stockpile #4, which contained overburden and layback soil from the excavation of the 116-KE-1 Condensate Crib. Information supporting the use of Stockpile #4, located within the AH excavation, as backfill was also included in the DOE/RL-2012-38 Remaining Sites Verification Package report.

Remediation of the identified Area AH waste sites was accomplished by demolishing the structures and excavating contaminated soil. All waste (soil and debris) associated with these waste sites was disposed at the Environmental Restoration and Disposal Facility (ERDF). The demolition activities were conducted using standard demolition techniques, including explosives for demolition of 132-KE-1 (116-KE Reactor Exhaust Stack). Approximately 1,809 ERDF containers (37,700 tons) of waste from these waste sites were sent to the ERDF for disposal.

Remediation of the 100-K-6 vacuum pit began in August 2011 and was completed in September 2011. An excavator was used to remove the vacuum pit and excavate the surrounding soil. The original waste site description estimated the depth of the cyclone separator as 9.14 meters (30 ft). However, during remediation the actual excavation depth was measured as 5.8 meters (19 ft).

The remediation of the 100-K-46 french drain was associated with the removal of the 119-KE building, which began in January 2009 and was completed in February 2009. The drywell was less than 1.5 meters (5 ft) deep.

The remediation activities at the 100-K-62 filter building began in August 2010 and were completed in May 2011. An excavator was used to remove the vacuum pit and excavate the surrounding soil. The maximum depth from grade within the waste site footprint was approximately 10.6 meters (34.8 ft).

The remediation activities at waste site 132-KE-1 exhaust stack began in July 2010 and were completed in September 2011. Removal of the above-grade portion of the stack was conducted using explosives placed near the base of the stack. The explosion caused the debris to fall in a designated area. The material was then loaded and disposed at ERDF. The entire below grade portion of the stack base was then removed. The maximum depth from grade within the waste site footprint was approximately 6.1 meters (20 ft).

In October of 2010, excavation of the overburden and layback soil for the 116-KE-1 Crib began and Stockpile #4 was created. Samples were collected in the 116-KE-1 waste site footprint and sent for analytical leach testing of the soils to determine carbon-14 leachability from the 100-K soil. During remediation of the co-located waste sites inside the AH excavation area, the 116-KE-1 crib was partially backfilled with soil from Stockpile #4 as a contamination control measure.

Note: Area-wide carbon-14 contamination exists in the deep zone above the criteria for protectiveness. This contamination is associated with the 105-KE Reactor ventilation filtration system and the deep contamination from the condensate that collected in the previously excavated 116-KE-1 Condensate Crib. Additional remediation of the deep vadose zone cannot be completed in proximity to the 105-KE Reactor without impacting structural stability. Available information about the nature and extent of the carbon-14 contamination has been documented in the 116-KE-1 Condensate Crib waste site description. Due to the depth of the contamination, the carbon-14 remediation will coincide with the final decision on 105-KE reactor removal.

Code: 100-K-66 **Classification:** Accepted

Names: 100-K-66; 165-KW Power Control Building **Reclassification:** None

Type: Control Structure **Start Date:**

Status: Inactive **End Date:**

Description: The building is painted a pink color and has three large stacks on the west end of the building. This site is a bomb resistant shelter without windows. All ventilation is supplied by fans. The building is posted Danger - Restricted Area - Asbestos (internal building asbestos).

Location: The 165-KW Building is located between the 183-KW Water Treatment Plant and the 105-KW Reactor Building. The 190-KW Main Pumphouse directly adjoins the south side of the 165-KW Power Control Building.

Process Description: The purpose of the 165-KW Power Control Building was to provide housing for the power house, control room, valve pit, and electrical switchgear of the water supply system.

The control room and valve pit are located directly over the pipe tunnel that extends from the 183 Building to the 105 Building. This section is 15 meters (50 feet) wide, and the two rooms are separated by a 46-centimeter (18-inch) concrete wall. The valve pit contains most of the motor-operated valves included in the cooling water, service water, and raw water systems. Steel grating serves as a floor at the operating level above the pit.

The electrical switchgear room houses all switchgear for the electrical system. Outside and adjoining the building is the 230 kilovolt Switchyard. Directly beneath the 165 Switchgear Room is the electrical cable room, occupied by two battery rooms, control panels for battery power, and 4,160 volt switchgear and building service transformers.

The control room is the nerve center of the entire water and power plant, more so than the comparable 190 Control Rooms in any of the older reactor areas. The importance of this center to the continuity of operation of the area has been recognized by its placement within the bomb-resistant shelter that also encloses the boiler and turbine room, the electrical switchgear, and the valve pit. Virtually all important pieces of equipment pertaining to maintaining water flow are started, stopped, or positioned directly from the control board in this room.

Steam is supplied by three complete package boilers. The steam is used to generate emergency power by three steam-driven turbo-generator sets, which provide 4.16 kilowatts of power to buses supplying selected low-lift pump motors in the 190-KW Building for reactor cooling and miscellaneous critical electrical components in the system. The power may also be used to operate river pumps to supply raw water to the 183-KW Water Treatment Plant.

In addition to the electrically-operated pumping system, a separate steam turbine driven pump is provided in the 190 Building to supply emergency flow to the reactor in the event both primary Bonneville Power Administration (BPA) and turbo-generator electrical power fails.

Waste Type: Equipment

Waste Description: The building contains asbestos and has been cleaned twice (in 1993) for PCBs.

Code: 100-K-67

Classification: Accepted

Names: 100-K-67; 165-KE Power Control Building

Reclassification: None

Type: Control Structure

Start Date:

Status: Active

End Date:

Description: The building is painted a pink color and has three large stacks on the west end of the building. This site is a bomb resistant shelter without windows. All ventilation is supplied by fans. The building is posted Danger - Restricted Area - Asbestos (internal building asbestos).

Location: The 165-KE building is located between the 183-KE Water Treatment Plant and the 105-KE Reactor Building. The 190-KE Main Pumphouse directly adjoins the south side of the 165-KE Power Control Building.

Process Description: The purpose of the 165-KE Power Control Building was to provide housing for the power house, control room, valve pit, and electrical switchgear of the water supply system. It is constructed as a bomb resistant shelter, without windows and all ventilation is supplied by fans.

The control room and valve pit are located directly over the pipe tunnel that extends from the 183 Building to the 105 Building. This section is 50 feet wide, and the two rooms are separated by an 18-inch concrete wall. The valve pit contains most of the motor-operated valves included in the cooling water, service water, and raw water systems. Steel grating serves as a floor at the operating level above the pit.

The electrical switchgear room houses all switchgear for the electrical system. Outside and adjoining the building is the 230 kilovolt Switchyard. Directly beneath the 165 Switchgear Room is the electrical cable room, occupied by two battery rooms, control panels for battery power, and 4160 volt switchgear and building service transformers.

The control room is the nerve center of the entire water and power plant, more so than the comparable 190 Control Rooms in any of the older reactor areas. The importance of this center to the continuity of operation of the area has been recognized by its being placed within the bomb-resistant shelter that also encloses the boiler and turbine room, the electrical switchgear, and the valve pit. Virtually all important pieces of equipment pertaining to maintaining water flow are started, stopped, or positioned directly from the control board in this room.

Steam is supplied by three complete package boilers. the steam is used to generate emergency power by three steam-driven turbo-generator sets, which provide 4.16 kilowatt power to buses supplying selected low-lift pump motors in the 190-KE Building for reactor cooling and miscellaneous critical electrical components in the system. The power may also be used to operate river pumps to supply raw water to the 183-KE Water Treatment Plant.

In addition to the electrically-operated pumping system, a separate steam turbine driven pump is provided in the 190 Building to supply emergency flow to the reactor in the event both primary (BPA) and turbo-generator electrical power fails.

Code: 100-K-68

Classification: Accepted

Names: 100-K-68; 105-KE Pump Gallery and Catch

Reclassification: Interim Closed Out (10/23/2012)

Tank; D Sump

Type: Catch Tank

Start Date:

Status: Inactive

End Date:

Description: The waste site has been remediated and Interim Closed Out. The structure was constructed of an 2.44 meter (8 foot) diameter corrugated steel caisson. A vinyl lined concrete catch tank was located at the bottom of the caisson. The pump gallery, containing two sump pumps and a ladder for access was above the tank. The total depth of the caisson is 10.87 meters (35.67 feet) and extended from just above grade level.

Location: The site was located approximately 22 meters (61.8 feet) north of the northwest corner of the 105-KE Reactor Building and is located just south of 116-KE-3 (105KE Storage Basin French Drain).

Related Sites/ Structures: The catch tank receives basin overflow from an 20.3 centimeter (8 inch) galvanized storage basin overflow header and diverts tank overflow to site 116-KE-3 (Sub basin drainage disposal system).

Waste Type: Water

Waste Description: Waste water from 105-KE Spent Fuel Storage Basin sub-basin drainage header.

Closure Info: Interim (10/23/2012): For the purposes of implementing and documenting remedial activities, the 100-K Area was divided into several informal remediation areas. The waste sites of this remedial activity were informally designated as being located within the Area AG Zone 1 remediation area, adjacent to the northwest corner of the reactor. (Note: One waste site located within Area AG Zone 1, the 116-KE-3 (105-KE Fuel Storage Basin Sub-Basin Drainage Disposal System Crib), was not remediated. Due to the extend of the deep zone contamination attributed to the 116-KE-3 waste site, it was placed in an "excluded region" within Area AG Zone 1. Waste site 116-KE-3 will be addressed at a later date.)

The remediated waste sites located in Area AG Zone 1 include 100-K-68, 100-K-69, 100-K-70, 100-K-71 and 100-K-3. A portion of the 100-K-3 pipeline was remediated with the area AG Zone 2 (see DOE/RL-2012-40). (Note: Portions of 100-K-47 and 100-K-56 pipelines were removed and considered part of the Area AG Zone 1 remediation activities. Approximately 452 feet of the 100-K-56, 36-inch pipeline was removed from Area AG Zone 1 and 3.

Approximately 338 feet of the 100-K-56, 72-inch pipeline was removed from Area AG Zone 1 and 3. Approximately 344 feet of the 100-K-47, 12-inch pipeline exiting the 100-K-71 collection box was removed from Area AG Zone 1 and 3. Approximately 344 feet of the 100-K-47, 16-inch pipeline (exiting the 100-K-71 collection box) was removed from Area AG Zone 1 and 3. The remaining portions of the 100-K-47 and 100-K-56 pipelines will be addressed in future remediation activities.)

Remediation of the waste sites within Area AG Zone 1 began in September 2009 and was finished in May 2012. In-process samples were collected and radiological surveys were conducted to guide the remediation. Contaminated structures, pipelines, and associated soil and debris attributed to these waste sites have been removed and disposed at the ERDF. During this remedial activity, Stockpile #3 was created from excavated soil from the overburden and layback from Area AG Zone 1 waste sites. Radiological surveys were conducted on the material prior to placing it in the stockpile. Stockpile #3 was located northwest of Area AG.

The 105-KE fuel storage basin (100-K-42 waste site) borders the Area AG Zone 1. UPR-100-K-1 (105-KE Fuel Storage Basin Leak) is an unplanned release from the discharge chute of the fuel storage basin. It leaked highly radioactive water underneath the basin into the ground for an unknown period of time. Boreholes were drilled to evaluate the subsurface soil conditions.

The results indicated significant residual radioactivity underneath the footprint of the fuel storage basin. The residual radioactivity distorted the radiological surveys conducted within the adjacent Area AG Zone 1.

The remediation of the 100-K-3 waste site began in January 2010 and was completed in May 2012. The remediation of this waste site included excavation of the heat exchanger, the pump pit, associated piping and contaminated soil. A total of 709 ERDF containers (11,513 metric tons [12,691 short tons]) was disposed at the ERDF from the Area AG 100-K-3 waste site (Zones 1 and 2 combined). Along with remediation of the waste sites in Area AG Zone 1, a 20.3 cm (8 in.) diameter Process Sewer Outside (PSO) drain line was also excavated. This pipeline exited the 100-K-3 heat exchanger pit and tied into the 100-K-47 concrete process sewer. This portion of pipeline was removed with a composite in-process sample taken along the length of the excavation in August 2011. The in-process sample results did not exceed the RAGs. The region within Area AG Zone 1 where this pipeline was removed was included in the Shallow Zone decision unit. In addition, the 100-K-3, 2.54 cm (1 in.) diameter PIEX pipeline (connecting the 100-K-3 heat exchanger to the 105-KE reactor) was documented in the shallow zone decision unit. This pipeline was originally buried 1.2 meters (4 ft) deep. When removed, the footprint was wholly contained within the layback region of the 100-K-56 waste site.

The 100-K-68 waste site structure (caisson with catch tank) was removed during waste site remediation. The remediation of the 100-K-68 waste site began in April 2010 and was completed in May 2012. The remediation of the waste site excavated the corrugated steel caisson, catch tank and pumping equipment. However, deep residual contamination associated with the 116-KE-3 waste site remains underneath the footprint of the 100-K-68 waste site.

The remediation of the 100-K-69 waste site began in April 2010 and was completed in May 2012. The remediation of the waste site excavated the concrete sump and associated contaminated soil.

The remediation of the contaminated soil beneath the 100-K-70 waste site began in April 2010 and was completed in May 2012. The tank associated with the 100-K-70 waste site had been previously removed, prior to the fuel storage basin demolition in 2008.

A total of 599 ERDF containers (11,920 metric tons [13,139 short tons]) was disposed at the ERDF from the combined 100-K-68, 100-K-69, and 100-K-70 waste sites.

The remediation of the 100-K-71 waste site began in March 2010 and was completed in May 2012. The remediation of the waste site included excavation of the collection box and associated contaminated soil. A total of 285 ERDF containers (5,858 metric tons [6,457 short tons]) was disposed at the ERDF from the 100-K-71 waste site. In-process samples collected at the collection box were analyzed for carbon-14 and tritium. The results indicated no residual contamination of these COCs.

The remediation of portions of the 100-K-47 pipeline began in November 2009 and was completed in September 2011. The partial remediation of the pipeline waste site included excavation of the underground process sewer pipelines and associated contaminated soil. In-process samples were collected within the remediated portion of the 100-K-71 waste site (collection box) footprint, because the 10.2 cm (4 in.) diameter cement asbestos pipeline from the 117-KE Filter Building (100-K-62 waste site) terminated at the collection box. Samples were analyzed for carbon-14 and tritium. The results indicated no residual contamination of these contaminants of concern (COCs). Therefore, carbon-14 and tritium were eliminated from the list of COCs for this waste site. A total of 1,240 ERDF containers (20,802 metric tons [22,930 short tons]) was disposed at the ERDF from the Area AG 100-K-47 waste site (Zones 1 and 3 combined).

The remediation of portions of the 100-K-56 Subsite 2 pipeline began in September 2009 and was completed in June 2011. The remediation excavated the part of the process effluent underground pipelines and associated contaminated soil. A total of 800 ERDF containers (13,071 metric tons [14,408 short tons]) was disposed at the ERDF from the Area AG 100-K-56 waste site (in Zones 1 and 3 combined).

A total of 63,292 metric tons of material was disposed at the ERDF during the AG Zone 1 remediation activity. (33,873 metric tons was related to the 100-K-47 and 100-K-56 partial pipeline excavations.)

No evidence of spills or leaks from Area AG Zone 1 waste sites was found after remediation. Post remediation, a Global Positioning Environmental Radiological Survey (GPERS) and radiological surveys using hand-held instrumentation were conducted. The GPERS is rendered ineffective in regions close to the 105-KE Reactor fuel storage basin (100-K-42 waste site) and the unplanned release site (UPR-100-K-1) due to the sensitive detection capabilities of the sodium iodide instrumentation and the elevated radiation background levels associated with the fuel storage basin subsurface soil.

Follow-up radiological surveys using hand-held instruments were conducted in the region around the 100-K-68, 100-K-69, 100-K-70, and 100-K-71 waste sites, immediately north of the fuel storage basin. The survey indicated elevated radiological contamination where piping from the 105-KE Reactor fuel storage basin traveled to the 105-KE Collection Box (100-K-71 waste site). One of the pipelines entering the south side of the collection box was equipped with a direct buried flanged gate valve, located at a depth of approximately 8.5 meters (27 ft 11 in.). A focused verification sample of this location was collected to determine contamination levels present in the soil. This follow-up survey also indicated elevated radiological contamination in the area around the 100-K-68 waste site. Verification sampling beneath the 100-K-68 waste site was not conducted because the residual soil contamination is attributed to the 116-KE-3 waste site. NOTE: 116-KE-3 is located within Area AG Zone 1 but was not part of the remediation work scope.

Code: 100-K-69	Classification: Accepted
Names: 100-K-69; 105-KE Sump C	Reclassification: Interim Closed Out (10/23/2012)
Type: Sump	Start Date:
Status: Inactive	End Date:
Description:	The waste site has been remediated and Interim Closed Out. The 100-K-69 waste site was a rectangular concrete structure, measuring approximately 2.3 meters (7.5 ft) by 1.4 meters (4.6 ft) by 3.7 meters (12 ft) deep. It received water from 105-KE fuel storage basin floor drains. Two electric powered sump pumps returned the drain water to the basin.
Location:	The sump was located just off the north side of the 105-KE Reactor Building and is near the northwest corner of the building.
Waste Type: Process Effluent	
Waste Description:	
Closure Info:	Interim (10/23/2012): For the purposes of implementing and documenting remedial activities, the 100-K Area was divided into several informal remediation areas. The waste sites of this remedial activity were informally designated as being located within the Area AG Zone 1 remediation area, adjacent to the northwest corner of the reactor. (Note: One waste site located

within Area AG Zone 1, the 116-KE-3 (105-KE Fuel Storage Basin Sub-Basin Drainage Disposal System Crib), was not remediated. Due to the extent of the deep zone contamination attributed to the 116-KE-3 waste site, it was placed in an "excluded region" within Area AG Zone 1. Waste site 116-KE-3 will be addressed at a later date.)

The remediated waste sites located in Area AG Zone 1 include 100-K-68, 100-K-69, 100-K-70, 100-K-71 and 100-K-3. A portion of the 100-K-3 pipeline was remediated with the area AG Zone 2 (see DOE/RL-2012-40). (Note: Portions of 100-K-47 and 100-K-56 pipelines were removed and considered part of the Area AG Zone 1 remediation activities. Approximately 452 feet of the 100-K-56, 36-inch pipeline was removed from Area AG Zone 1 and 3. Approximately 338 feet of the 100-K-56, 72-inch pipeline was removed from Area AG Zone 1 and 3. Approximately 344 feet of the 100-K-47, 12-inch pipeline exiting the 100-K-71 collection box was removed from Area AG Zone 1 and 3. Approximately 344 feet of the 100-K-47, 16-inch pipeline (exiting the 100-K-71 collection box) was removed from Area AG Zone 1 and 3. The remaining portions of the 100-K-47 and 100-K-56 pipelines will be addressed in future remediation activities.)

Remediation of the waste sites within Area AG Zone 1 began in September 2009 and was finished in May 2012. In-process samples were collected and radiological surveys were conducted to guide the remediation. Contaminated structures, pipelines, and associated soil and debris attributed to these waste sites have been removed and disposed at the ERDF. During this remedial activity, Stockpile #3 was created from excavated soil from the overburden and layback from Area AG Zone 1 waste sites. Radiological surveys were conducted on the material prior to placing it in the stockpile. Stockpile #3 was located northwest of Area AG.

The 105-KE fuel storage basin (100-K-42 waste site) borders the Area AG Zone 1. UPR-100-K-1 (105-KE Fuel Storage Basin Leak) is an unplanned release from the discharge chute of the fuel storage basin. It leaked highly radioactive water underneath the basin into the ground for an unknown period of time. Boreholes were drilled to evaluate the subsurface soil conditions. The results indicated significant residual radioactivity underneath the footprint of the fuel storage basin. The residual radioactivity distorted the radiological surveys conducted within the adjacent Area AG Zone 1.

The remediation of the 100-K-3 waste site began in January 2010 and was completed in May 2012. The remediation of this waste site included excavation of the heat exchanger, the pump pit, associated piping and contaminated soil. A total of 709 ERDF containers (11,513 metric tons [12,691 short tons]) was disposed at the ERDF from the Area AG 100-K-3 waste site (Zones 1 and 2 combined). Along with remediation of the waste sites in Area AG Zone 1, a 20.3 cm (8 in.) diameter Process Sewer Outside (PSO) drain line was also excavated. This pipeline exited the 100-K-3 heat exchanger pit and tied into the 100-K-47 concrete process sewer. This portion of pipeline was removed with a composite in-process sample taken along the length of the excavation in August 2011. The in-process sample results did not exceed the RAGs. The region within Area AG Zone 1 where this pipeline was removed was included in the Shallow Zone decision unit. In addition, the 100-K-3, 2.54 cm (1 in.) diameter PIEX pipeline (connecting the 100-K-3 heat exchanger to the 105-KE reactor) was documented in the shallow zone decision unit. This pipeline was originally buried 1.2 meters (4 ft) deep. When removed, the footprint was wholly contained within the layback region of the 100-K-56 waste site.

The 100-K-68 waste site structure (caisson with catch tank) was removed during waste site remediation. The remediation of the 100-K-68 waste site began in April 2010 and was completed in May 2012. The remediation of the waste site excavated the corrugated steel caisson, catch tank and pumping equipment. However, deep residual contamination associated with the 116-KE-3 waste site remains underneath the footprint of the 100-K-68 waste site.

The remediation of the 100-K-69 waste site began in April 2010 and was completed in May 2012. The remediation of the waste site excavated the concrete sump and associated contaminated soil.

The remediation of the contaminated soil beneath the 100-K-70 waste site began in April 2010 and was completed in May 2012. The tank associated with the 100-K-70 waste site had been previously removed, prior to the fuel storage basin demolition in 2008.

A total of 599 ERDF containers (11,920 metric tons [13,139 short tons]) was disposed at the ERDF from the combined 100-K-68, 100-K-69, and 100-K-70 waste sites.

The remediation of the 100-K-71 waste site began in March 2010 and was completed in May 2012. The remediation of the waste site included excavation of the collection box and associated contaminated soil. A total of 285 ERDF containers (5,858 metric tons [6,457 short tons]) was disposed at the ERDF from the 100-K-71 waste site. In-process samples collected at the collection box were analyzed for carbon-14 and tritium. The results indicated no residual contamination of these COCs.

The remediation of portions of the 100-K-47 pipeline began in November 2009 and was completed in September 2011. The partial remediation of the pipeline waste site included excavation of the underground process sewer pipelines and associated contaminated soil. In-process samples were collected within the remediated portion of the 100-K-71 waste site (collection box) footprint, because the 10.2 cm (4 in.) diameter cement asbestos pipeline from the 117-KE Filter Building (100-K-62 waste site) terminated at the collection box. Samples were analyzed for carbon-14 and tritium. The results indicated no residual contamination of these contaminants of concern (COCs). Therefore, carbon-14 and tritium were eliminated from the list of COCs for this waste site. A total of 1,240 ERDF containers (20,802 metric tons [22,930 short tons]) was disposed at the ERDF from the Area AG 100-K-47 waste site (Zones 1 and 3 combined).

The remediation of portions of the 100-K-56 Subsite 2 pipeline began in September 2009 and was completed in June 2011. The remediation excavated the part of the process effluent underground pipelines and associated contaminated soil. A total of 800 ERDF containers (13,071 metric tons [14,408 short tons]) was disposed at the ERDF from the Area AG 100-K-56 waste site (in Zones 1 and 3 combined).

A total of 63,292 metric tons of material was disposed at the ERDF during the AG Zone 1 remediation activity. (33,873 metric tons was related to the 100-K-47 and 100-K-56 partial pipeline excavations.)

No evidence of spills or leaks from Area AG Zone 1 waste sites was found after remediation. Post remediation, a Global Positioning Environmental Radiological Survey (GPERS) and radiological surveys using hand-held instrumentation were conducted. The GPERS is rendered ineffective in regions close to the 105-KE Reactor fuel storage basin (100-K-42 waste site) and the unplanned release site (UPR-100-K-1) due to the sensitive detection capabilities of the sodium iodide instrumentation and the elevated radiation background levels associated with the fuel storage basin subsurface soil.

Follow-up radiological surveys using hand-held instruments were conducted in the region around the 100-K-68, 100-K-69, 100-K-70, and 100-K-71 waste sites, immediately north of the fuel storage basin. The survey indicated elevated radiological contamination where piping from the 105-KE Reactor fuel storage basin traveled to the 105-KE Collection Box (100-K-71 waste site). One of the pipelines entering the south side of the collection box was equipped with a direct buried flanged gate valve, located at a depth of approximately 8.5 meters (27 ft 11 in.). A focused verification sample of this location was collected to determine contamination levels

present in the soil. This follow-up survey also indicated elevated radiological contamination in the area around the 100-K-68 waste site. Verification sampling beneath the 100-K-68 waste site was not conducted because the residual soil contamination is attributed to the 116-KE-3 waste site. NOTE: 116-KE-3 is located within Area AG Zone 1 but was not part of the remediation work scope.

Code:	100-K-70	Classification:	Accepted
Names:	100-K-70; 105-KE Waste Storage Tank; Holding Tank	Reclassification	Interim Closed Out (10/23/2012)
Type:	Storage Tank	Start Date:	1/1/1974
Status:	Inactive	End Date:	

Description: The waste site has been remediated and Interim Closed Out. It was a modified steel storage tank for the 105-KE Spent Fuel Storage Basin radioactive drains. The tank was buried under a 1.8 meter (6 foot) deep earth berm. An absolute filter was located on the east end of the tank and a tank level gauge was located on the west end of the tank. A 0.9 meter (3 ft) diameter access port was located at the approximate center of the tank and extended just above grade level. The tank associated with the 100-K-70 waste site was removed prior to the fuel storage basin demolition in 2008.

Location: The site was located approximately 8 meters (22.5 feet) north of the 105-KE Building.

Related Sites/Structures: A pipeline designated as 100-K-47 connected 100-K-70 to the 105-KE waste storage tank. This section of 100-K-47 pipeline was within the remediation area AG Zone 1 and was removed.

Waste Type: Process Effluent

Waste Description:

Closure Info: Interim (10/23/2012): For the purposes of implementing and documenting remedial activities, the 100-K Area was divided into several informal remediation areas. The waste sites of this remedial activity were informally designated as being located within the Area AG Zone 1 remediation area, adjacent to the northwest corner of the reactor. (Note: One waste site located within Area AG Zone 1, the 116-KE-3 (105-KE Fuel Storage Basin Sub-Basin Drainage Disposal System Crib), was not remediated. Due to the extend of the deep zone contamination attributed to the 116-KE-3 waste site, it was placed in an "excluded region" within Area AG Zone 1. Waste site 116-KE-3 will be addressed at a later date.)

The remediated waste sites located in Area AG Zone 1 include 100-K-68, 100-K-69, 100-K-70, 100-K-71 and 100-K-3. A portion of the 100-K-3 pipeline was remediated with the area AG Zone 2 (see DOE/RL-2012-40). (Note: Portions of 100-K-47 and 100-K-56 pipelines were removed and considered part of the Area AG Zone 1 remediation activities. Approximately 452 feet of the 100-K-56, 36-inch pipeline was removed from Area AG Zone 1 and 3. Approximately 338 feet of the 100-K-56, 72-inch pipeline was removed from Area AG Zone 1 and 3. Approximately 344 feet of the 100-K-47, 12-inch pipeline exiting the 100-K-71 collection box was removed from Area AG Zone 1 and 3. Approximately 344 feet of the 100-K-47, 16-inch pipeline (exiting the 100-K-71 collection box) was removed from Area AG Zone 1 and 3. The remaining portions of the 100-K-47 and 100-K-56 pipelines will be addressed in future remediation activities.)

Remediation of the waste sites within Area AG Zone 1 began in September 2009 and was finished in May 2012. In-process samples were collected and radiological surveys were conducted to guide the remediation. Contaminated structures, pipelines, and associated soil and

debris attributed to these waste sites have been removed and disposed at the ERDF. During this remedial activity, Stockpile #3 was created from excavated soil from the overburden and layback from Area AG Zone 1 waste sites. Radiological surveys were conducted on the material prior to placing it in the stockpile. Stockpile #3 was located northwest of Area AG.

The 105-KE fuel storage basin (100-K-42 waste site) borders the Area AG Zone 1. UPR-100-K-1 (105-KE Fuel Storage Basin Leak) is an unplanned release from the discharge chute of the fuel storage basin. It leaked highly radioactive water underneath the basin into the ground for an unknown period of time. Boreholes were drilled to evaluate the subsurface soil conditions. The results indicated significant residual radioactivity underneath the footprint of the fuel storage basin. The residual radioactivity distorted the radiological surveys conducted within the adjacent Area AG Zone 1.

The remediation of the 100-K-3 waste site began in January 2010 and was completed in May 2012. The remediation of this waste site included excavation of the heat exchanger, the pump pit, associated piping and contaminated soil. A total of 709 ERDF containers (11,513 metric tons [12,691 short tons]) was disposed at the ERDF from the Area AG 100-K-3 waste site (Zones 1 and 2 combined). Along with remediation of the waste sites in Area AG Zone 1, a 20.3 cm (8 in.) diameter Process Sewer Outside (PSO) drain line was also excavated. This pipeline exited the 100-K-3 heat exchanger pit and tied into the 100-K-47 concrete process sewer. This portion of pipeline was removed with a composite in-process sample taken along the length of the excavation in August 2011. The in-process sample results did not exceed the RAGs. The region within Area AG Zone 1 where this pipeline was removed was included in the Shallow Zone decision unit. In addition, the 100-K-3, 2.54 cm (1 in.) diameter PIEX pipeline (connecting the 100-K-3 heat exchanger to the 105-KE reactor) was documented in the shallow zone decision unit. This pipeline was originally buried 1.2 meters (4 ft) deep. When removed, the footprint was wholly contained within the layback region of the 100-K-56 waste site.

The 100-K-68 waste site structure (caisson with catch tank) was removed during waste site remediation. The remediation of the 100-K-68 waste site began in April 2010 and was completed in May 2012. The remediation of the waste site excavated the corrugated steel caisson, catch tank and pumping equipment. However, deep residual contamination associated with the 116-KE-3 waste site remains underneath the footprint of the 100-K-68 waste site.

The remediation of the 100-K-69 waste site began in April 2010 and was completed in May 2012. The remediation of the waste site excavated the concrete sump and associated contaminated soil.

The remediation of the contaminated soil beneath the 100-K-70 waste site began in April 2010 and was completed in May 2012. The tank associated with the 100-K-70 waste site had been previously removed, prior to the fuel storage basin demolition in 2008.

A total of 599 ERDF containers (11,920 metric tons [13,139 short tons]) was disposed at the ERDF from the combined 100-K-68, 100-K-69, and 100-K-70 waste sites.

The remediation of the 100-K-71 waste site began in March 2010 and was completed in May 2012. The remediation of the waste site included excavation of the collection box and associated contaminated soil. A total of 285 ERDF containers (5,858 metric tons [6,457 short tons]) was disposed at the ERDF from the 100-K-71 waste site. In-process samples collected at the collection box were analyzed for carbon-14 and tritium. The results indicated no residual contamination of these COCs.

The remediation of portions of the 100-K-47 pipeline began in November 2009 and was completed in September 2011. The partial remediation of the pipeline waste site included

excavation of the underground process sewer pipelines and associated contaminated soil. In-process samples were collected within the remediated portion of the 100-K-71 waste site (collection box) footprint, because the 10.2 cm (4 in.) diameter cement asbestos pipeline from the 117-KE Filter Building (100-K-62 waste site) terminated at the collection box. Samples were analyzed for carbon-14 and tritium. The results indicated no residual contamination of these contaminants of concern (COCs). Therefore, carbon-14 and tritium were eliminated from the list of COCs for this waste site. A total of 1,240 ERDF containers (20,802 metric tons [22,930 short tons]) was disposed at the ERDF from the Area AG 100-K-47 waste site (Zones 1 and 3 combined).

The remediation of portions of the 100-K-56 Subsite 2 pipeline began in September 2009 and was completed in June 2011. The remediation excavated the part of the process effluent underground pipelines and associated contaminated soil. A total of 800 ERDF containers (13,071 metric tons [14,408 short tons]) was disposed at the ERDF from the Area AG 100-K-56 waste site (in Zones 1 and 3 combined).

A total of 63,292 metric tons of material was disposed at the ERDF during the AG Zone 1 remediation activity. (33,873 metric tons was related to the 100-K-47 and 100-K-56 partial pipeline excavations.)

No evidence of spills or leaks from Area AG Zone 1 waste sites was found after remediation. Post remediation, a Global Positioning Environmental Radiological Survey (GPERS) and radiological surveys using hand-held instrumentation were conducted. The GPERS is rendered ineffective in regions close to the 105-KE Reactor fuel storage basin (100-K-42 waste site) and the unplanned release site (UPR-100-K-1) due to the sensitive detection capabilities of the sodium iodide instrumentation and the elevated radiation background levels associated with the fuel storage basin subsurface soil.

Follow-up radiological surveys using hand-held instruments were conducted in the region around the 100-K-68, 100-K-69, 100-K-70, and 100-K-71 waste sites, immediately north of the fuel storage basin. The survey indicated elevated radiological contamination where piping from the 105-KE Reactor fuel storage basin traveled to the 105-KE Collection Box (100-K-71 waste site). One of the pipelines entering the south side of the collection box was equipped with a direct buried flanged gate valve, located at a depth of approximately 8.5 meters (27 ft 11 in.). A focused verification sample of this location was collected to determine contamination levels present in the soil. This follow-up survey also indicated elevated radiological contamination in the area around the 100-K-68 waste site. Verification sampling beneath the 100-K-68 waste site was not conducted because the residual soil contamination is attributed to the 116-KE-3 waste site. NOTE: 116-KE-3 is located within Area AG Zone 1 but was not part of the remediation work scope.

Code: 100-K-71	Classification: Accepted
Names: 100-K-71; 105-KE Collection Box	Reclassification: Interim Closed Out (10/23/2012)
Type: Diversion Box	Start Date: 1/1/1953
Status: Inactive	End Date:
Description: The waste site has been remediated and Interim Closed Out. The 105-KE Collection Box collected effluent from nine underground process sewer lines that originated in the 105-KE Reactor Building and also from the 117-KE filter building (100-K-62). The effluent exited the Collection Box via 12 inch and 16 inch cast iron process sewer pipelines. The Process Sewer pipelines that entered and exited the 100-K-71 Collection Box are part of sitecode 100-K-47.	
Location: The site was located underground approximately, 12 meters north of the 105-KE Reactor	

Building.

Related Sites/ Structures: Two pipelines designated as 100-K-47 exited the north side of the 100-K-71, 105-KE collection box. The portions of the 100-K-47 pipelines that connected to the collection box were within the remediation area AG Zone 1 and were removed.

Waste Type: Process Effluent

Waste Description: The collection box received waste water from the contaminated drain, potentially contaminated drain, clean drain, drain to pluto crib, basin drain line, ink system drain, rod cooling water drain, floor drains, the decon drain to filter and basin overflow drain.

Closure Info: Interim (10/23/2012): For the purposes of implementing and documenting remedial activities, the 100-K Area was divided into several informal remediation areas. The waste sites of this remedial activity were informally designated as being located within the Area AG Zone 1 remediation area, adjacent to the northwest corner of the reactor. (Note: One waste site located within Area AG Zone 1, the 116-KE-3 (105-KE Fuel Storage Basin Sub-Basin Drainage Disposal System Crib), was not remediated. Due to the extend of the deep zone contamination attributed to the 116-KE-3 waste site, it was placed in an "excluded region" within Area AG Zone 1. Waste site 116-KE-3 will be addressed at a later date.)

The remediated waste sites located in Area AG Zone 1 include 100-K-68, 100-K-69, 100-K-70, 100-K-71 and 100-K-3. A portion of the 100-K-3 pipeline was remediated with the area AG Zone 2 (see DOE/RL-2012-40). (Note: Portions of 100-K-47 and 100-K-56 pipelines were removed and considered part of the Area AG Zone 1 remediation activities. Approximately 452 feet of the 100-K-56, 36-inch pipeline was removed from Area AG Zone 1 and 3. Approximately 338 feet of the 100-K-56, 72-inch pipeline was removed from Area AG Zone 1 and 3. Approximately 344 feet of the 100-K-47, 12-inch pipeline exiting the 100-K-71 collection box was removed from Area AG Zone 1 and 3. Approximately 344 feet of the 100-K-47, 16-inch pipeline (exiting the 100-K-71 collection box) was removed from Area AG Zone 1 and 3. The remaining portions of the 100-K-47 and 100-K-56 pipelines will be addressed in future remediation activities.)

Remediation of the waste sites within Area AG Zone 1 began in September 2009 and was finished in May 2012. In-process samples were collected and radiological surveys were conducted to guide the remediation. Contaminated structures, pipelines, and associated soil and debris attributed to these waste sites have been removed and disposed at the ERDF. During this remedial activity, Stockpile #3 was created from excavated soil from the overburden and layback from Area AG Zone 1 waste sites. Radiological surveys were conducted on the material prior to placing it in the stockpile. Stockpile #3 was located northwest of Area AG.

The 105-KE fuel storage basin (100-K-42 waste site) borders the Area AG Zone 1. UPR-100-K-1 (105-KE Fuel Storage Basin Leak) is an unplanned release from the discharge chute of the fuel storage basin. It leaked highly radioactive water underneath the basin into the ground for an unknown period of time. Boreholes were drilled to evaluate the subsurface soil conditions. The results indicated significant residual radioactivity underneath the footprint of the fuel storage basin. The residual radioactivity distorted the radiological surveys conducted within the adjacent Area AG Zone 1.

The remediation of the 100-K-3 waste site began in January 2010 and was completed in May 2012. The remediation of this waste site included excavation of the heat exchanger, the pump pit, associated piping and contaminated soil. A total of 709 ERDF containers (11,513 metric tons [12,691 short tons]) was disposed at the ERDF from the Area AG 100-K-3 waste site (Zones 1 and 2 combined). Along with remediation of the waste sites in Area AG Zone 1, a 20.3 cm (8 in.) diameter Process Sewer Outside (PSO) drain line was also excavated. This pipeline exited the 100-K-3 heat exchanger pit and tied into the 100-K-47 concrete process

sewer. This portion of pipeline was removed with a composite in-process sample taken along the length of the excavation in August 2011. The in-process sample results did not exceed the RAGs. The region within Area AG Zone 1 where this pipeline was removed was included in the Shallow Zone decision unit. In addition, the 100-K-3, 2.54 cm (1 in.) diameter PIEX pipeline (connecting the 100-K-3 heat exchanger to the 105-KE reactor) was documented in the shallow zone decision unit. This pipeline was originally buried 1.2 meters (4 ft) deep. When removed, the footprint was wholly contained within the layback region of the 100-K-56 waste site.

The 100-K-68 waste site structure (caisson with catch tank) was removed during waste site remediation. The remediation of the 100-K-68 waste site began in April 2010 and was completed in May 2012. The remediation of the waste site excavated the corrugated steel caisson, catch tank and pumping equipment. However, deep residual contamination associated with the 116-KE-3 waste site remains underneath the footprint of the 100-K-68 waste site.

The remediation of the 100-K-69 waste site began in April 2010 and was completed in May 2012. The remediation of the waste site excavated the concrete sump and associated contaminated soil.

The remediation of the contaminated soil beneath the 100-K-70 waste site began in April 2010 and was completed in May 2012. The tank associated with the 100-K-70 waste site had been previously removed, prior to the fuel storage basin demolition in 2008.

A total of 599 ERDF containers (11,920 metric tons [13,139 short tons]) was disposed at the ERDF from the combined 100-K-68, 100-K-69, and 100-K-70 waste sites.

The remediation of the 100-K-71 waste site began in March 2010 and was completed in May 2012. The remediation of the waste site included excavation of the collection box and associated contaminated soil. A total of 285 ERDF containers (5,858 metric tons [6,457 short tons]) was disposed at the ERDF from the 100-K-71 waste site. In-process samples collected at the collection box were analyzed for carbon-14 and tritium. The results indicated no residual contamination of these COCs.

The remediation of portions of the 100-K-47 pipeline began in November 2009 and was completed in September 2011. The partial remediation of the pipeline waste site included excavation of the underground process sewer pipelines and associated contaminated soil. In-process samples were collected within the remediated portion of the 100-K-71 waste site (collection box) footprint, because the 10.2 cm (4 in.) diameter cement asbestos pipeline from the 117-KE Filter Building (100-K-62 waste site) terminated at the collection box. Samples were analyzed for carbon-14 and tritium. The results indicated no residual contamination of these contaminants of concern (COCs). Therefore, carbon-14 and tritium were eliminated from the list of COCs for this waste site. A total of 1,240 ERDF containers (20,802 metric tons [22,930 short tons]) was disposed at the ERDF from the Area AG 100-K-47 waste site (Zones 1 and 3 combined).

The remediation of portions of the 100-K-56 Subsite 2 pipeline began in September 2009 and was completed in June 2011. The remediation excavated the part of the process effluent underground pipelines and associated contaminated soil. A total of 800 ERDF containers (13,071 metric tons [14,408 short tons]) was disposed at the ERDF from the Area AG 100-K-56 waste site (in Zones 1 and 3 combined).

A total of 63,292 metric tons of material was disposed at the ERDF during the AG Zone 1 remediation activity. (33,873 metric tons was related to the 100-K-47 and 100-K-56 partial pipeline excavations.)

No evidence of spills or leaks from Area AG Zone 1 waste sites was found after remediation. Post remediation, a Global Positioning Environmental Radiological Survey (GPERS) and radiological surveys using hand-held instrumentation were conducted. The GPERS is rendered ineffective in regions close to the 105-KE Reactor fuel storage basin (100-K-42 waste site) and the unplanned release site (UPR-100-K-1) due to the sensitive detection capabilities of the sodium iodide instrumentation and the elevated radiation background levels associated with the fuel storage basin subsurface soil.

Follow-up radiological surveys using hand-held instruments were conducted in the region around the 100-K-68, 100-K-69, 100-K-70, and 100-K-71 waste sites, immediately north of the fuel storage basin. The survey indicated elevated radiological contamination where piping from the 105-KE Reactor fuel storage basin traveled to the 105-KE Collection Box (100-K-71 waste site). One of the pipelines entering the south side of the collection box was equipped with a direct buried flanged gate valve, located at a depth of approximately 8.5 meters (27 ft 11 in.). A focused verification sample of this location was collected to determine contamination levels present in the soil. This follow-up survey also indicated elevated radiological contamination in the area around the 100-K-68 waste site. Verification sampling beneath the 100-K-68 waste site was not conducted because the residual soil contamination is attributed to the 116-KE-3 waste site. NOTE: 116-KE-3 is located within Area AG Zone 1 but was not part of the remediation work scope.

Code:	100-K-72	Classification:	Accepted
Names:	100-K-72; 105-KW Pump Gallery and Catch Tank; D Sump	Reclassification	None
Type:	Catch Tank	Start Date:	
Status:	Active	End Date:	
Description:	The structure is located below grade. It is constructed of a 2.4 meter (8 foot) diameter corrugated steel caisson. A vinyl lined concrete catch tank is located at the bottom of the caisson. Above the catch tank, is a pump gallery containing two sump pumps and a ladder for access. The total length of the caisson is 11 meters (35 feet 8 inches) and extends from just above grade level at elevation 464.50 feet to elevation 430.83 feet.		
Location:	The site is located approximately 22 meters (73 feet) north of the northwest corner of the 105-KW Reactor Building and is located just south of 116-KW-2 (105KW Storage Basin French Drain).		
Related Sites/ Structures:	The catch tank receives basin overflow from the 20 centimeter (8 inch) sub-basin drainage header and a 2" RDW (Radioactive Drain Water) and diverts the catch tank overflow to site 116-KW-2 (Sub basin drainage disposal system).		
Waste Type:	Water		
Waste Description:	Waste water from 105-KE Spent Fuel Storage Basin sub-basin drainage header.		

Code:	100-K-73	Classification:	Accepted
Names:	100-K-73; 105-KW Collection Box	Reclassification	None
Type:	Diversion Box	Start Date:	
Status:	Inactive	End Date:	
Description:	The 105-KW Collection Box collects effluent from nine underground process sewer lines that		

originate in the 105-KW Reactor Building. The effluent exits the Collection Box via 30 centimeter (12 inch) cast iron and a 41 centimeter (16 inch) cast iron process sewer pipelines. Sewer pipelines entering the "Collection Box" include the following: 15 centimeter (6 inch) clean drain, 25.4 centimeter (10 inch) contaminated drain, 25.4 centimeter (10 inch) potentially contaminated drain, 15 centimeter (6 inch) rod cooling water, 15 centimeter (6 inch) drain to pluto crib, 30 centimeter (12 inch) basin drain line, 20 centimeter (8 inch) basin overflow line, 15 centimeter (6 inch) vent line, and 10 centimeter (4 inch) vitrified clay tile decon drain to filter.

Location: The site is located approximately 6.5 meters (21 feet) north of the 105-KW Reactor Building. The site is underground and its location is not discernible from the ground surface.

Waste Type: Process Effluent

Waste Description: The collection box received waste water from the contaminated drain, potentially contaminated drain, clean drain, drain to pluto crib, basin drain line, ink system drain, rod cooling water drain, floor drains, the decon drain to filter and basin overflow drain.

Code: 100-K-74 **Classification:** Accepted

Names: 100-K-74; 105-KW Waste Storage Tank; Holding Tank **Reclassification:** None

Type: Storage Tank **Start Date:**

Status: Inactive **End Date:**

Description: The site is a steel storage tank for the 105-KW Spent Fuel Storage Basin radioactive drains. The tank is buried under a 1.8 meter (6 foot) deep earth berm. An absolute filter is located on the east end of the tank and a tank level gauge is located on the west end of the tank.

Location: The site is located approximately 8 meters (26 feet) north of the 105-KW Building.

Related Sites/Structures: A 5 centimeter (2 inch) line connects the waste storage tank to the Sump "C" (Site Code 100-K-75).

Waste Type: Process Effluent

Waste Description:

Code: 100-K-75 **Classification:** Accepted

Names: 100-K-75; 105-KW Sump C **Reclassification:** None

Type: Sump **Start Date:**

Status: Inactive **End Date:**

Description: The structure is a concrete sump that receives water from the 105-KW fuel storage basin floor drains in the transfer area. Two electric powered sump pumps return the drain water to the basin and/or the underground holding tank.

Location: The site is located just north of the 105KW Reactor Building and is near the northwest corner of the building.

Related Sites/Structures: Sump "C" pumps return waste water from the floor drains in the 105-KW Basin Transfer Area to the 105-KW Basin and/or the Holding Tank (site code 100-K-74).

Waste Type: Water**Waste
Description:**

Code: 100-K-77 **Classification:** Accepted
Names: 100-K-77; Underground Railroad Ties Southeast of 1706KE **Reclassification:** Interim Closed Out (10/4/2011)
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The waste site has been remediated. The site was railroad ties discovered at the bottom of an open excavation. The excavation measured approximately 2.9 meters by 3.1 meters by 2.1 meters deep (9.5 feet by 10 feet by 6.9 feet deep). The sidewalls were braced with lumber. The open excavation had been backfilled, and the railroad ties at the bottom of the excavation were left in place. The sidewall braces were probably removed prior to backfilling. In June 2011, the area was re-excavated. The railroad ties and original backfill soil was removed. The second excavation was backfilled in July 2011.

Location: The site is located approximately 7 meters (23 feet) east southeast of the 1706KE building.

**Related Sites/
Structures:** The reason for the railroad ties is not known, consequently associated structures are also unknown.

**Process
Description:** The sides of the excavation were braced with lumber to prevent cave in and the top was covered with a tarp to keep precipitation out. Ultrasonic testing was used to find any pipe leaks that might have been causing the subsidences, but no leaks were identified.

Waste Type: Misc. Trash and Debris

**Waste
Description:** Buried railroad ties.

Closure Info: Interim (10/4/2011): The exact location of the buried railroad ties was not known. Several areas near the 1706-KE Building were excavated while searching for the waste site location. When the correct location was identified, the railroad ties and original backfilled soil were removed. Approximately 4,651 tons of railroad ties and soil were disposed of in the ERDF landfill. No visual evidence of spills or leaks was found during or after remediation in the excavation. No in-process sampling was conducted for this waste site. The excavation was backfilled in July 2011.

Code: 100-K-79 **Classification:** Accepted
Names: 100-K-79; Sodium Dichromate and Sulfuric Acid Product Pipelines at 100-KE and 100-KW **Reclassification:** None
Type: Product Piping **Start Date:**
Status: Inactive **End Date:**

Description: This waste site includes the pipelines that carried pure chemical and treated cooling water at both the 105KE and 105KW reactors. The piping in this waste site has been split into eight subsites.

Subsite 1 - The sodium dichromate product pipelines at KW, that ran from the railroad offloading areas to the dichromate storage tanks and then to the adjacent 183.1KW Headhouse, became subsite 1. This subsite has been remediated and is Interim Closed Out.

Subsite 2 - The sulfuric acid product pipelines at KW, that ran from the sulfuric acid storage tanks to the 183.1KW Headhouse, and then adjacent railroad offloading areas, became subsite 2. This subsite has been remediated and is Interim Closed Out.

Subsite 3 - The sodium dichromate lines at 183.1KE became subsite 3.

Subsite 4 - The sulfuric acid lines at 183.1KE became subsite 4.

Subsite 5 - The treated water pipelines, that ran north/south between the 105KW Reactor and 165KW Power Control Building, became subsite 5.

Subsite 6 - The treated water pipelines, that ran north/south between the 105KE Reactor and 165KE Power Control Building became subsite 6.

Subsite 7 - The 0.61-meter (24-inch) process water pipeline that connected the 105KE and 105KW reactor buildings is known as the original cross-tie line. The parallel, replacement 0.61-meter (24-inch) process water pipeline that connected to the 105KE and 105KW reactor buildings is known as the "New" cross-tie line. Both the original and new cross tie lines are considered Subsite 7.

Subsite 8 - The 1.21 meter (48 inch) Clearwell cross tie line became subsite 8.

Location: These pipelines are located south of 105KE and south of 105KW. They connect the 105 Reactor buildings to the 165 and 183.1 Buildings. There is also cross-tie pipeline between the 105KE and 105KW Reactors buildings that is orientated in a east/west direction.

Release Description: No releases to the environment have been recorded from the pipelines enclosed in the tunnels. However, the railroad offloading facilities and pipe valves may have leaked at various times.

Related Sites/Structures: These pipelines are related to the 120-KW-5 and 120-KE-6 dichromate tank foundations, the 120-KE-4, 120-KE-5, 120-KW-3, and 120-KW-4 sulfuric acid tank foundations, the 183.1 Headhouses and the 165 Power Control Buildings, and 105 Reactors.

Process Description: Concentrated sodium dichromate and sulfuric acid flowed through the product lines, which are encased inside concrete pipe tunnels. The pipelines between the 165 Buildings and the 105 Reactors carried treated water with more dilute sodium dichromate.

Waste Type: Equipment

Waste Description: The waste is residual sodium dichromate (chromium 6) and mercury (from sulfuric acid) in the pipes and potential leaks from the offloading station.

This Site has the Following SubSites:

Code: 100-K-79:1

Names: 100-K-79:1; 100-KW Sodium Dichromate Product Pipelines from the Railroad Offloading areas to the Sodium Dichromate storage tanks and 183.1 KW Headhouse

Code: 100-K-79:2

Names: 100-K-79:2; 100-KW Sulfuric Acid Product Pipelines from the Sulfuric Acid storage tanks to the 183.1 KW Headhouse

Code: 100-K-79:3

Names: 100-K-79:3; 100-KE Sodium Dichromate Product Pipelines from the Railroad Offloading areas to the Sodium Dichromate storage tanks and 183.1 KE Headhouse

Code: 100-K-79:4

Names: 100-K-79:4; 100-KE Sulfuric Acid Product Pipelines from the Sulfuric Acid storage tanks to the 183.1 KE Headhouses and the Railroad Offloading areas

Code: 100-K-79:5

Names: 100-K-79:5; Treated Water Pipelines between the 105KW Reactor and 165KW Power Control Building

Code: 100-K-79:6
Names: 100-K-79:6; Treated Water Pipelines between the 105KE Reactor and 165KE Power Control Building

Code: 100-K-79:7
Names: 100-K-79:7; Cross-Tie Line; Original Cross Tie Line and the New Cross Tie Line; Process Water Pipelines between the 105KE and 105KW Reactor Buildings

Code: 100-K-79:8
Names: 100-K-79:8; 48 Inch Line between 183.4 KW and 183.4KE; Clearwell Cross Tie Line

Code: 100-K-79:1 **Classification:** Accepted

Names: 100-K-79:1; 100-KW Sodium Dichromate Product Pipelines from the Railroad Offloading areas to the Sodium Dichromate storage tanks and 183.1 KW Headhouse **Reclassification** Interim Closed Out (6/27/2012)

Type: Product Piping **Start Date:**

Status: Inactive **End Date:**

Description: The subsite has been remediated and Interim Closed Out. It was the sodium dichromate product pipelines that ran from the railroad offloading areas to the sodium dichromate storage tanks and to the adjacent 183.1 KW Headhouse.

Related Sites/ Structures: These pipelines were related to the 120-KW-5 dichromate tank, the 120-KW-3 and 120-KW-4 sulfuric acid tanks, and the 183.1-KW Headhouse.

Process Description: Concentrated sodium dichromate (70% solution) and sulfuric acid flowed through 3/8-inch product lines, which were encased in concrete pipe tunnels. The sulfuric acid was known to have had mercury contamination. In July 1985, a sample of sulfuric acid sludge was collected for analysis; regulated levels of mercury were detected in the sludge with lesser amounts of barium, total chromium, lead, and selenium.

Closure Info: Interim (6/27/2012): Remediation of the Area AA, Zone 2 waste sites (100-K-18, 100-K-19, 100-K-79:1, 100-K-79:2, 100-K-97, 120-KW-5 and 120-KW-7) began in May 2010. Throughout the remedial activity, because of the contaminants found in the process equipment and surface soils, in-process samples were collected and analyzed for metals, including chromium VI and anions (e.g., sulfate due to the sulfuric acid), at multiple locations and depths. In-process sampling occurred across all four zones in 100-K Area AA, although this report focuses on Zone 2 only. Throughout remediation, stained areas were targeted for in-process sampling; soils often were yellow-colored and high in lead, total chromium and mercury. Hexavalent chromium, which is the groundwater contaminant of greatest concern at 100-K, was detected on the soil surface down to 6 feet, at the beginning of remediation for Area AA Zone 2. Excavation continued to a final remediation depth of 10.96 meters (35.96 ft).

During a walkdown of Area AA by RL and EPA on September 20, 2011, it was determined that piping found within Zone 1 needed to be further investigated. The piping identified was determined to be a part of the process sewer line and was subsequently removed.

The excavation decision unit was approximately 3,228 square meters (34,745.9 sq. ft.). All contaminated soils and debris from the waste sites was disposed of in the Environmental Restoration Disposal Facility (ERDF).

The SubSite is Part Of:

Code: 100-K-79
Names: 100-K-79; Sodium Dichromate and Sulfuric Acid Product Pipelines at 100-KE and 100-KW

Code: 100-K-79:2 **Classification:** Accepted
Names: 100-K-79:2; 100-KW Sulfuric Acid Product Pipelines from the Sulfuric Acid storage tanks to the 183.1 KW Headhouse **Reclassification** Interim Closed Out (6/27/2012)
Type: Product Piping **Start Date:**
Status: Inactive **End Date:**

Description: The subsite has been remediated and Interim Closed Out. It was the sulfuric acid product pipelines that ran from the sulfuric acid storage tanks to the 183.1 KW Headhouses and to the adjacent railroad offloading areas.

Location: This pipeline is located south of the 183 KW basins.

Release Description: These pipelines were related to the 120-KW-5 dichromate tank, the 120-KW-3 and 120-KW-4 sulfuric acid tanks, and the 183.1-KW Headhouse.

Process Description: Concentrated sodium dichromate (70% solution) and sulfuric acid flowed through 3/8-inch product lines, which were encased in concrete pipe tunnels. The sulfuric acid was known to have had mercury contamination. In July 1985, a sample of sulfuric acid sludge was collected for analysis; regulated levels of mercury were detected in the sludge with lesser amounts of barium, total chromium, lead, and selenium.

Closure Info: Interim (6/27/2012): Remediation of the Area AA, Zone 2 waste sites (100-K-18, 100-K-19, 100-K-79:1, 100-K-79:2, 100-K-97, 120-KW-5 and 120-KW-7) began in May 2010. Throughout the remedial activity, because of the contaminants found in the process equipment and surface soils, in-process samples were collected and analyzed for metals, including chromium VI and anions (e.g., sulfate due to the sulfuric acid), at multiple locations and depths. In-process sampling occurred across all four zones in 100-K Area AA, although this report focuses on Zone 2 only. Throughout remediation, stained areas were targeted for in-process sampling; soils often were yellow-colored and high in lead, total chromium and mercury. Hexavalent chromium, which is the groundwater contaminant of greatest concern at 100-K, was detected on the soil surface down to 6 feet, at the beginning of remediation for Area AA Zone 2. Excavation continued to a final remediation depth of 10.96 meters (35.96 ft).

During a walkdown of Area AA by RL and EPA on September 20, 2011, it was determined that piping found within Zone 1 needed to be further investigated. The piping identified was determined to be a part of the process sewer line and was subsequently removed.

The excavation decision unit was approximately 3,228 square meters (34,745.9 sq. ft.). All contaminated soils and debris from the waste sites was disposed of in the Environmental Restoration Disposal Facility (ERDF).

The SubSite is Part Of:

Code: 100-K-79
Names: 100-K-79; Sodium Dichromate and Sulfuric Acid Product Pipelines at 100-KE and 100-KW

Code: 100-K-79:3 **Classification:** Accepted
Names: 100-K-79:3; 100-KE Sodium Dichromate Product Pipelines from the Railroad Offloading areas to the Sodium Dichromate storage tanks **Reclassification** None

and 183.1 KE Headhouse

Type: Product Piping

Start Date:

Status: Inactive

End Date:

Description: The subsite is the sodium dichromate product pipelines that ran from the railroad offloading areas to the sodium dichromate storage tanks and to the adjacent 183.1 KE Headhouse.

Location: This pipeline is located south of the 183 KE basins.

The SubSite is Part Of:

Code: 100-K-79

Names: 100-K-79; Sodium Dichromate and Sulfuric Acid Product Pipelines at 100-KE and 100-KW

Code: 100-K-79:4

Classification: Accepted

Names: 100-K-79:4; 100-KE Sulfuric Acid Product Pipelines from the Sulfuric Acid storage tanks to the 183.1 KE Headhouses and the Railroad Offloading areas

Reclassification: None

Type: Product Piping

Start Date:

Status: Inactive

End Date:

Description: The subsite is the sulfuric acid product pipelines that ran from the sulfuric acid storage tanks to the 183.1 KE Headhouse, and to the adjacent railroad offloading areas.

Location: This pipeline is located south of the 183 KE basins.

The SubSite is Part Of:

Code: 100-K-79

Names: 100-K-79; Sodium Dichromate and Sulfuric Acid Product Pipelines at 100-KE and 100-KW

Code: 100-K-79:5

Classification: Accepted

Names: 100-K-79:5; Treated Water Pipelines between the 105KW Reactor and 165KW Power Control Building

Reclassification: None

Type: Product Piping

Start Date:

Status: Inactive

End Date:

Description: The subsite is the treated water pipelines that ran north/south between the 105KW Reactor and 165KW Power Control Building.

The SubSite is Part Of:

Code: 100-K-79

Names: 100-K-79; Sodium Dichromate and Sulfuric Acid Product Pipelines at 100-KE and 100-KW

Code: 100-K-79:6

Classification: Accepted

Names: 100-K-79:6; Treated Water Pipelines between the 105KE Reactor and 165KE Power Control Building

Reclassification: None

Type: Product Piping**Start Date:****Status:** Inactive**End Date:****Description:** The subsite is the treated water pipelines that ran north/south between the 105KE Reactor and 165KE Power Control Building.**The SubSite is Part Of:****Code:** 100-K-79**Names:** 100-K-79; Sodium Dichromate and Sulfuric Acid Product Pipelines at 100-KE and 100-KW

Code: 100-K-79:7**Classification:** Accepted**Names:** 100-K-79:7; Cross-Tie Line; Original Cross Tie Line and the New Cross Tie Line; Process Water Pipelines between the 105KE and 105KW Reactor Buildings**Reclassification:** None**Type:** Product Piping**Start Date:****Status:** Inactive**End Date:****Description:** The 100-K-79, Subsite 7 is known as the Cross Tie Line. It is composed of two, parallel treated water pipelines that connect the 105-KE Reactor and the 105-KW Reactor. One 24-inch pipeline is the Original Cross Tie line. The other 24-inch pipeline is known as the New Cross tie line. It replaced the Original pipeline. They ran east to west. It also includes a 36 inch high pressure discharge line segment, that connected to the 182-K Emergency Cooling Water Pump House.

Both pipelines are constructed from 24 inches in diameter carbon steel. They are connected to each reactor through valve pits located on the south end of each reactor building. The treated water into each pipeline is fed from a 36-inch carbon steel pipeline from the 182-K Emergency Water Reservoir Pump House, which used diesel-fueled pumps to supply treated water for the 100-K Coolant Backup System. The treated water flowed into the 182-K Pump House from the 183.4-KE and 183.4-KW Clearwells.

Each of the 24-inch pipelines is enclosed in 36-inch corrugated piping. The corrugated piping rests on concrete footings. The 36-inch pipeline is enclosed in a 48-inch corrugated pipe which also rests on concrete footings.

A portion of 100-K-79:7 was removed during the demolition of the 1706-KE, KER and KEL buildings in 2010 (see DOE/RL-2012-40). Verification samples collected in 2011 found contamination that exceeded Remedial Action Goals for metals. Additional excavation was required. Verification sampling was completed in July 2012 on the remediated portion of 100-K-79:7.

Location: The parallel pipelines are located in the center of 100-K Area, just south of the reactor buildings.**Related Sites/ Structures:** The pipeline is part of the Reactor Cooling Water Backup System.**The SubSite is Part Of:****Code:** 100-K-79**Names:** 100-K-79; Sodium Dichromate and Sulfuric Acid Product Pipelines at 100-KE and 100-KW

Code: 100-K-79:8 **Classification:** Accepted
Names: 100-K-79:8; 48 Inch Line between 183.4 KW and 183.4KE; Clearwell Cross Tie Line **Reclassification** None
Type: Product Piping **Start Date:**
Status: Inactive **End Date:**

Description: The subsite is an underground 48 inch diameter pipeline that ran wet to east to connected the 183.4 KW Clearwell to the 183.4 KE Clearwell. A pipe segment also extended north to connect with the 182K Emergency Water Reservoir Pump House.

Location: The pipeline is located in the center of 100-K Area, south of the reactor buildings.

Related Sites/ Structures: The pipeline is part of the Reactor Cooling Water Backup System.

The SubSite is Part Of:

Code: 100-K-79
Names: 100-K-79; Sodium Dichromate and Sulfuric Acid Product Pipelines at 100-KE and 100-KW

Code: 100-K-82 **Classification:** Accepted
Names: 100-K-82; 105-KW Fuel Storage Basin Leak **Reclassification** None
Type: Unplanned Release **Start Date:** 1/1/1974
Status: Inactive **End Date:** 1/1/1978

Description: This unplanned release is associated with the 105 KW fuel storage basin (100-K-43). It is analogous to the documented liquid release that occurred at the 105-KE fuel storage basin (100-K-42), known as UPR-100-K-1. The release is not marked or posted. In 1978, leakage was discovered in the 105-KW pickup chute area. The basin leaks were repaired with epoxy fiberglass. It is possible the leakage rates were similar to those noted at the 105-KE basin (see UPR-100-K-1).

Location: The storage basin extends from the north wall of the 105-KW Reactor Building to the open area behind the reactor, with its longitudinal axis running parallel to the north wall of the building. Its east-west location is roughly in the center of the building. The leak occurred on the north side of the 105 KW basin.

Related Sites/ Structures: The release is associated with 100-K-43.

Process Description: In 1978, the 105-KW basin was approved to be used as supplemental storage for irradiated 100-N irradiated fuel storage.

Waste Type: Water

Waste Description: Fuel storage basin effluent that included debris from fuel cladding failures. The release is analogous to the release at 105-KE basin. Cobalt-60, Strontium-90, Cesium-137 and small amounts of plutonium were noted in the soil beneath the 105- K East basin.

Code: 100-K-85 **Classification:** Accepted
Names: 100-K-85; 100-K Temporary Construction Pit **Reclassification** Interim No Action (4/6/2011)
Type: Trench **Start Date:**

Status: Inactive**End Date:****Description:** The site is a large open pit estimated to be 30 m (98 ft) in diameter and appears to have supported construction operations. The site appears as a flat grassy area.**Location:** The site is located in the 100-KR-2 Operable Unit, approximately 284 m (932 ft) southeast of the 1720-K building. It was dug approximately 10 m (33 ft) south of the temporary construction area outside of Site 600-29.**Waste Type:** Construction Debris**Waste Description:** The waste may be temporary construction debris.**Closure Info:** Interim: The 100-K-85, 100-K Temporary Construction Pit waste site, located in the 100-KR-2 Operable Unit, consisted of a large open pit that appears in a historical photograph of 100-K Area from 1953. The pit was expected to be 30 m (100 ft) in diameter, covering an area of approximately 700 m² (7,600 ft²), and assumed to have supported construction operations. A site visit in December 2009 indicated no debris, staining, and no vegetation differences in comparison to the surrounding area.

Based on the 1953 photograph, the 2009 site visit, knowledge of historical processes, and a 2008 geophysical survey of the 100-K-85 waste site, confirmatory sampling was performed in November 2010. The results indicated that the waste site achieved compliance with the remedial action objectives (RAOs) and remedial action goals (RAGs) for the 100-K-85 waste site; therefore, remediation was not necessary. A summary of the cleanup evaluation for the soil analyses against the applicable RAGs is presented in Table ES-1. The results of the confirmatory sampling are used to make reclassification decisions for the 100-K-85 waste site in accordance with the TPA-MP-14 procedure in the Tri-Party Agreement Handbook Management Procedures (DOE-RL 2007).

Code: 100-K-89**Classification:** Accepted**Names:** 100-K-89; 100-K Burn Site**Reclassification:** Interim Closed Out (8/15/2012)**Type:** Burn Pit**Start Date:****Status:** Inactive**End Date:****Description:** The waste site has been remediated and Interim Closed Out. Prior to remediation this site consisted of burnt materials laying on the ground surface. The 100-K-89 waste site was completely remediated and removed when one of the 600-29 excavations was expanded beyond the original waste site boundary to encompass additional contamination found during remediation.**Location:** The site is 60 meters (197 ft) south of site 600-29. The Washington State Plane coordinates for the site are E 568597.54, N 145529.56.**Related Sites/ Structures:** The waste site is associated with 600-29.**Waste Type:** Construction Debris**Waste Description:** Contaminants of potential concern may include asbestos and petroleum products. The waste is burned debris (wood, metal and roofing material) and any potentially contaminated soil.**Closure Info:** Interim (8/15/2012): Remedial action at the 600-29 and 100-K-89 waste sites began on September 21, 2011, and continued through April 5, 2012. Most of the remedial excavations were the result of visible surface debris, stains, and materials. These areas were excavated from

a minimum of 0.3 meter (1 ft) in depth to as much as 3 meters (10 ft) in depth, as needed, to remove contamination. Excavations for french drains ranged from 1.2 to 1.8 meters (4 to 6 ft) in depth. A septic vault in the eastern portion of 600-29 required excavation to 10 feet below ground surface. All materials removed from the excavations were stockpiled within the excavations and then directly loaded for disposal at the Environmental Restoration Disposal Facility (ERDF). No stockpiles external to the excavations were created. The 100-K-89 waste site comprised a burned area with burnt material present on the surface (wood, metal, and roofing material) and the underlying soil. Contamination identified on the southwest edge of the 600-29 waste site led to an excavation that was expanded during remediation based on field observations. The expansion encompassed and completely removed the 100-K-89 waste site.

Contaminated materials removed from the 600-29 waste site consisted of red, black, and white stained soils or colored materials, concrete pads and rubble, a concrete sewer junction box, abandoned iron and vitrified clay piping, abandoned wiring, friable and nonfriable asbestos, metallic and wood debris, burnt wood, ash, tar, and other miscellaneous demolition debris. Materials removed from the 100-K-89 waste site consisted of burned debris (wood, metal, roofing material) and associated soils.

A total volume of 10,293 bank cubic meters (BCM) (6,157 BCM from the east side of 600-29 and 4,136 BCM from the west side of 600-29) was removed and disposed to ERDF during remediation.

Code:	100-K-97	Classification:	Accepted
Names:	100-K-97; 183-KW French Drain and Rail Spur Unplanned Release	Reclassification	Interim Closed Out (6/27/2012)
Type:	French Drain	Start Date:	
Status:	Inactive	End Date:	
Description:	The waste site has been remediated and Interim Closed Out. The site consisted of a French Drain that was used to collect drainage from the chromate system transfer hose after unloading the railcar. It also included an unplanned release along the railroad tracks on the Head House rail spur.		
Location:	The French Drain was located south of the 183 KW Head House, just south of the 100-K-19 (183-KW Caustic Soda Storage Tank Site), southwest of 100-K-18 (183-KW Caustic Neutralization Pit), and north of the railroad.		
Process Description:	The Head House rail spur was used for delivery of water treatment equipment and chemicals. Anecdotal information indicates that sodium dichromate and sulfuric acid spills were not uncommon during railcar unloading operations, which led to the assignment of the unplanned release along the rail spur. After railcar unloading operations were complete, the sodium dichromate transfer hose was placed into the open French Drain to collect excess product in a controlled manner.		
Closure Info:	Interim (6/27/2012): Remediation of the Area AA, Zone 2 waste sites (100-K-18, 100-K-19, 100-K-79:1, 100-K-79:2, 100-K-97, 120-KW-5 and 120-KW-7) began in May 2010. Throughout the remedial activity, because of the contaminants found in the process equipment and surface soils, in-process samples were collected and analyzed for metals, including chromium VI and anions (e.g., sulfate due to the sulfuric acid), at multiple locations and depths. In-process sampling occurred across all four zones in 100-K Area AA, although this report focuses on Zone 2 only. Throughout remediation, stained areas were targeted for in-process sampling; soils often were yellow-colored and high in lead, total chromium and mercury. Hexavalent chromium, which is the groundwater contaminant of greatest concern at 100-K, was detected on the soil surface down to 6 feet, at the beginning of remediation for Area AA Zone		

2. Excavation continued to a final remediation depth of 10.96 meters (35.96 ft).

During a walkdown of Area AA by RL and EPA on September 20, 2011, it was determined that piping found within Zone 1 needed to be further investigated. The piping identified was determined to be a part of the process sewer line and was subsequently removed.

The excavation decision unit was approximately 3,228 square meters (34,745.9 sq. ft.). All contaminated soils and debris from the waste sites was disposed of in the Environmental Restoration Disposal Facility (ERDF).

Code:	100-K-98	Classification:	Accepted
Names:	100-K-98; 183-KE French Drain and Rail Spur Unplanned Release	Reclassification	None
Type:	French Drain	Start Date:	
Status:	Inactive	End Date:	
Description:	The site consists of a French Drain that was used to collect the drainage from the transfer hose after unloading the railcar.		
Location:	The French Drain is located south of the 183 KE Head House, just south of the 100-K-25, 183-KE Caustic Neutralization Pit, southwest of 100-K-25, 183-KE Caustic Neutralization Pit, and north of the railroad.		
Process Description:	The Head House rail spur was used for delivery of water treatment equipment and chemicals. Anecdotal information indicates that sodium dichromate and sulfuric acid spills were not uncommon during railcar unloading operations, which led to the assignment of the unplanned release along the rail spur. After railcar unloading operations were complete, the sodium dichromate transfer hose was placed into the open French Drain to collect excess product in a controlled manner.		

Code:	100-K-101	Classification:	Accepted
Names:	100-K-101; French Drains and Mercury Stained Soils near the 183KE Sedimentation Basin	Reclassification	None
Type:	French Drain	Start Date:	
Status:	Inactive	End Date:	
Description:	The site consists of a French Drain surrounded by mercury stained soil adjacent to the KE Sedimentation Basin near the abutments. There is also a black hose assembly.		
Location:	The site is located in the KE area along the south face of the Sedimentation Basin.		

Code:	100-K-102	Classification:	Accepted
Names:	100-K-102; French Drains and Mercury Stained Soils near the 183KW Sedimentation Basin	Reclassification	Interim Closed Out (7/10/2012)
Type:	French Drain	Start Date:	
Status:	Inactive	End Date:	
Description:	The waste site has been remediated and Interim Closed Out. It consisted of two French drains surrounded by sulfuric acid stained soil adjacent to the 183.2-KW Flocculation and		

Sedimentation Basins near the abutments. It also had a partially exposed acid delivery piping (i.e., dosing pipes) system and associated man-holes.

Location: The site is located in the KW area between the Sedimentation Basin and the Headhouse.

Process Description: Sulfuric acid, along with sodium silicate and alum, was piped from the 183.1-KW Headhouse through the dosing pipes into the abutments to initiate flocculation of the raw river water as an initial step in the reactor cooling water treatment process. The sulfuric acid was contaminated with metals, including mercury with lesser amounts of barium, total chromium, lead and selenium. Disposal of excess acid into the French drains, as well as leakage and overspray from the dosing pipes, led to contamination of the surrounding soils.

Closure Info: Interim (7/10/2012): Remediation of the Area AA Zone 1 Waste Sites began in April 2010 and ended in January 2012. The waste site structures and soils have been excavated as part of the remedial activities for the 100-K Area. The excavation area was designated as 100-K Area AA, Zone 1 (Area AA, Zone 1). It encompassed the individual waste sites 100-K-34, 100-K-102 and 1607-K3. Stockpile #11 contains layback soil from remediation of Area AA, Zone 1. These waste sites are adjacent to the 100-K-59 pipelines. Since visible sediment was observed in the severed pipelines, a sample was collected in February 2011 from the open end of the pipe west of the 183.1KW Headhouse. A section of the 100-K-59 pipeline was removed.

Excavation of the waste sites continued to a final remediation maximum depth of 9.82 meters (32.2 ft), which was located within the footprint of 100-K-102. To support the deeper excavation for Area AA, Zone 1, layback soil was accumulated and managed as Stockpile #11. The excavation decision unit was approximately 7,331 square meters (78,910 ft²) for 100-K Area AA, Zone 1. The original footprint prior to additional process sewer pipe removal was divided into evenly spaced areas for statistical sampling outside the waste sites to address any potential for contamination spread.

Code: 100-K-103 **Classification:** Accepted

Names: 100-K-103; 1704-K and 1717-K Septic Systems; Additional Components of 1607-K4 **Reclassification:** None

Type: Settling Tank **Start Date:**

Status: Inactive **End Date:**

Description: This WIDS site addresses seven components of the 1717K Septic System (1607-K4) that were not included in the Closed Out documentation for the 1607-K4 waste site. 100-K-103 includes the Original Tile Field, the Replacement Septic Tank, one Leaching Trench and four distinct Replacement Tile Field, built in 1995.

Location: The additional septic system components surround the Closed Out 1607-K4 Septic Tank and Tile Field. All of the components are located north of the 1717K building, inside the 100-K Area.

Related Sites/ Structures: 1607-K4 Septic Tank was abandoned in 1999.

Process Description: The leaching trench received waste from only the 1717-L Maintenance Building. The remaining components received waste from both 1717-K and the 1704-K office building.

Code: 100-K-104 **Classification:** Accepted

Names: 100-K-104; 166-KE French Drain **Reclassification:** None

Type: French Drain**Start Date:****Status:** Unknown**End Date:****Description:** A site visit in July 2008 could not visually identify the french drain. The drain was fed by approximately 30 meters (100 feet) of underground piping.**Location:** The french drain is described on drawings to be approximately 30 meters (100 feet) west of the 166-KE building.**Process** The source of the effluent is a sump in the 166-KE Pump Room.**Description:**

Code: 100-K-105**Classification:** Accepted**Names:** 100-K-105; Pit at Southeast Corner of 100K**Reclassification** None**Type:** Depression/Pit (nonspecific)**Start Date:** 1/1/1955**Status:** Inactive**End Date:****Description:** The pit cannot be visually identified at the present time. An open pit was clearly visible on historical photograph 3346-NEG, taken in April 1955. Later photographs do not show any evidence of the pit. It is presumed to have been backfilled prior to 1965.**Location:** The open pit is located in the southwest corner of 100-K West Area, near the perimeter road.**Process** There are no facilities near the open pit. It is not known what the pit was used for.**Description:**

Code: 100-K-106**Classification:** Accepted**Names:** 100-K-106; 182-K Fuel Oil Crib**Reclassification** Interim Closed Out (1/8/2013)**Type:** Crib**Start Date:****Status:** Inactive**End Date:****Description:** The site has been remediated and Interim Closed Out. It was an underground, rock filled drainage crib next to the demolished 182-K Building.**Location:** The centerline of the crib was approximately 6.1 meters (20 feet) west of the northwest corner of the 182-K building.**Process** The crib supported the 182-K midway pump station that contained three diesel powered pumps.**Description:** Discharge to crib was via a 15 centimeter (6 inch) diameter crib drain, that exited the building in two locations. One exited on the north end of the building and entered the east end of crib. Upon entering the crib, the piping consists of a 6 inch diameter corrugated metal perforated pipe. The other source to the crib is through a floor drain that collected drainage from a fuel oil centrifuge and a refrigerated drinking fountain. Influent to the waste site would have been water or, potentially, an oily, nonradioactive liquid waste.**Closure Info:** Interim (1/8/2013): The crib, drain pipeline, and associated contaminated soil from the excavation site (including from beneath the 182-K Emergency Water Pump House) have been removed and disposed at the Environmental Restoration Disposal Facility (ERDF). Approximately 400 ERDF containers (7,324 tons [8,073 short tons]) of soil and debris were disposed at ERDF from the combined waste site and 182-K pump house excavation site.

Remediation of Waste Site 100-K-106 and removal of the drain pipeline coincided with the removal of the below grade portions of the 182-K Emergency Water Pump House, which began in March 2012 and was completed in June 2012. Because the sump of the pump house extended to approximately 10.8 meters (35.5 ft) below grade, the excavation removed the crib structure, the sump and the drain pipeline.

The soil excavated from the waste site appeared to be stained, indicating the possibility of one or more releases to the crib. Soil from the crib area was in-process sampled to characterize residual contamination. Sampling results exceeded land disposal restrictions for chromium and required some of the soil be segregated for treatment before disposal at the ERDF. Sample results also indicated elevated levels of copper, lead, vanadium, and zinc. An area of soil staining was also observed at the excavation floor just east of the waste site. A focused sample was collected from this location during verification sampling. Sample results were below Hanford Site background values or constituents were undetected.

Three stockpiles were created from the excavated soil of the joint 182-K Emergency Water Pump House and Waste Site 100-K-106 excavation site. Stockpile 1 was located northeast of the excavation site. Stockpile 2 was located to the south of the excavation site. Stockpile 3 was located northwest of the excavation site. Due to safety issues associated with the steep side-slopes of the excavation and protruding pipelines, a civil survey of the excavation site was not prepared. A civil survey of the stockpiles was completed post remediation. The combined stockpiles were approximately 5,378 square meters (57,889 sq. ft) and consisted of two sampling subunits with the eight sampling areas. Sampling areas of the stockpiles did not their side slopes because the stockpiles surrounded the edge of the excavation site. The side slopes of the stockpiles joined the steep side slopes of the excavation site, making them unstable. Therefore, for the safety of sampling personnel, stockpile side slopes were not included within the sampling areas.

The crib and pipeline sample area was approximately 9.29 square meters (100 sq. ft.) in size. Four sample increments were collected from randomly selected nodes within this sampling area and combined into a single composite sample for that area. Soil from six discrete locations in the vicinity of the waste site and drain pipeline were sampled.

The excavation was backfilled in August 2012.

NOTE: During excavation activities, evidence of a past fuel oil spill, along with a some concrete, was encountered approximately 30 meters (98 ft) northeast of the pump house. This spill was not explored further, but was covered with a layer of protective soil. Remediation of this spill is planned for future work as a part of either the adjacent 100-KE Oil Contamination Area (sitecode 100-K-48) or the 166-KE Oil Storage Tank bunker waste site (sitecode 130-KE-2). It is not associated with the pump house, Waste Site 100-K-106, or drain pipeline. Also, after backfill for the excavation site was completed, potentially asbestos containing material was found in the footprint of the excavation site. Consequently, a discovery waste site (100-K-119) was assigned to the excavation site which is currently being evaluated for future action to address potential residual asbestos in the soil.

Code: 100-K-107	Classification: Accepted
Names: 100-K-107; 1706-KER Abandoned Drain Field	Reclassification: None
Type: Drain/Tile Field	Start Date:
Status: Inactive	End Date:
Description: A fenced area 31 meters (102 feet) northwest of the northwest corner of the 1706-KER building is assumed to be this abandoned drain field.	

Location: The abandoned drain field is located north and west of 1706-KER.

Process Description: The 1706-KER facility provided experimental data on the effect of water qualities, water temperature and pressure, and physical and chemical properties of materials of construction upon reactor operation and control, upon reactor tubes and slugs, and upon associated equipment when operating closed in-pile recirculation systems at elevated temperatures and pressures. It was also known as a decontamination and hot shop. Effluent from the building toilets and floor drains exited the facility via a 10.2 centimeter (4 inch) drain line to this drain field.

Code: 100-K-108

Classification: Accepted

Names: 100-K-108; 1706-KER Septic System; 1706-KER Septic Tank; Crib and Sewer Line

Reclassification: None

Type: Septic Tank

Start Date:

Status: Unknown

End Date:

Description: The site consists of a septic tank, crib, and associated piping that received effluent from the hot maintenance shop in 1706-KER building.

Location: The septic tank, crib, and associated piping are located northwest of the 1706-KER Building.

Process Description: The 1706-KER facility provided experimental data on the effect of water qualities, water temperature and pressure, and physical and chemical properties of materials of construction upon reactor operation and control, upon reactor tubes and slugs, and upon associated equipment when operating closed in-pile recirculation systems at elevated temperatures and pressures. It was also known as a decontamination and hot shop. The septic tank has a 2271 liter (600 gallon.) capacity tank, measuring 1.37 meters (54 inches) diameter by 1.78 meters (70 inches) depth. It is asphalt coated. The septic tank weighs 197 kilograms (435 pounds) and is constructed of 14 gauge steel. The crib is 1.8 meters (6 feet) wide by 2.1 meters (7 feet) tall. It was constructed of 15.2 by 15.2 centimeter (6x6 inch) treated (coal tar creosote) wooden timbers. The outside of the crib is covered with wire mesh. A 10.2 centimeter (4 inch) vent pipe exits the top of the crib. During operation of the building, the crib was surrounded by wood guard posts. The pipeline has a minimum soil cover of 0.8 meters (2.5 feet).

Waste Type: Chemicals

Waste Description: Contaminants of Potential Concern may include radionuclides (fission products), ICP metals, mercury, TPH and hexavalent chrome.

Code: 100-K-109

Classification: Accepted

Names: 100-K-109; Unplanned Chemical Release near 183.1KW Head House; Yellow Stained Soil adjacent to 183.1KW Head House

Reclassification: Interim Closed Out (11/18/2011)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The waste site has been remediated and Interim Closed Out. It was an area of yellow stained soil, from an unplanned release that is adjacent to the railroad track, south-southwest of the demolished 183.1KW headhouse.

Location: The visible stained soil was located near the southwest corner of the demolished 183.1KW Head House building near the railroad track.

Related Sites/ Structures: The area is associated with the 183.1KW Head House and the 100-K-15 and 100-K-16 Alum tanks.

Process Description: The Head House rail spur was used for delivery of water treatment equipment and chemicals. Anecdotal information indicates that sodium dichromate and sulfuric acid spills were common during railcar unloading operations, which led to the unplanned releases along the rail spur. Historical drawings and photographs show this stained soil area is adjacent to a rail car unloading area. It is also adjacent to a 183.1KW head house and two alum storage tanks (previously removed).

Closure Info: Interim (11/18/2011): Excavation of 100-K-109 began in August, 2010 to remove stained soils, and excavation was completed in June, 2011, when the last stained soil was removed and disposed at the Environmental Restoration Disposal Facility (ERDF). The original area, based on the posted Underground Radioactive Material Area, was estimated to be 48.7 meters (160 ft) long by 21.3 meters (70 ft) wide that equaled an area of 981 square meters (10,559 sq. ft.). The actual remediated area more than double the original estimate. 1,861 square meters (20,031.6 sq. ft.) was excavated, due to removal of a significant amount of stained soils. The excavation was anticipated to end at a depth of 4.6 meters (15 ft). However, the excavation the yellow-colored contaminated soil continued to the final depth of the remediation was 7.84 meters (25.7 ft), due to the ongoing detection of mercury contamination at levels above the RAGs in the RDR/RAWP (DOE/RL-96-17).

Code: 118-K-1	Classification: Accepted
Names: 118-K-1; 100-K Burial Ground; 118-K	Reclassification: Interim Closed Out (2/26/2014)
Type: Burial Ground	Start Date: 1/1/1953
Status: Inactive	End Date: 1/1/1975

Description: The 118-K-1 burial ground has been remediated and Interim Closed Out. The trenches ran northwest and southwest. It contained approximately fifty trenches and pits and eleven silos. The trenches and pit dimensions varied greatly. The silos ranged from 1.4 meter (4.5 feet) to 3 meters (10 feet) in diameter with depths from 7.6 meters (25 feet) to 9.8 meters (32 feet deep). The site had two parts, the main burial ground and the area known as the CGI-791 addition. Based on the results reported in CVP-2013-00002, the radiological postings were removed from the 118-K-1 burial ground in February 2014.

Location: The site was located 244 meters (800 feet) northeast of 105-KE Reactor Building, outside the 100-K Area perimeter fence.

Related Sites/ Structures: The burial ground is associated with sitecode 100-K-132, Deep Contamination Below Trenches N and O of the 118-K-1.

Process Description: This burial ground received solid waste from both the 100-K and 100-N Areas. A low level waste incinerator was located near the southeast corner of the burial ground. The incinerator was constructed of a steel plate box, measuring 1.8 meters (6 feet) by 6.1 meters (20 feet). It had a 2.4 meter (8 foot) high stack. There are eleven silos. Six silos received reactor hardware, three silos contain incinerator ashes and two silos contain irradiated nickel plated boron balls from the emergency 3X system.

Waste Type: Equipment

Waste Description: This unit contains numerous trenches and vertical steel pipes of various sizes that contain radioactive solid waste from 105-K and 105-N Reactors. The trenches miscellaneous debris. Some 100-N waste includes zirconium cladding hulls and basin n sludge. The incinerator operated for several years burning low-level contaminated combustible material. All contaminated burning was halted in October 1960. Six silos received reactor hardware, three

silos contain incinerator ashes and two silos contain irradiated nickel plated boron balls from the emergency 3X system.

Closure Info: Interim (2/26/2014): Remedial action at the 118-K-1 Burial Ground began on May 30, 2006. Trenches A and B were excavated to a depth of approximately 5.5 meters (18 ft) and 4.0 meters (13 ft) bgs, respectively, resulting in approximately 4,035 bank cubic meters (BCM) (5,278 bank cubic yards [BCY]) of material removed for disposal at ERDF. Excavation of Trench M began on July 10, 2006, to a depth of approximately 4.6 m (15 ft) bgs, resulting in approximately 1,170 BCM (1,530 BCY) of material removed for disposal at ERDF. The remediation was partially completed in July 2008 (phase 1 remediation) and then placed in a safe shutdown mode. Two sorting cells were established east of the burial ground and were used to process the soil from the burial ground prior to being loaded out for disposal at ERDF. Field observations during excavation and sorting of material from Trenches A, B, and M indicated that only construction debris was discovered and removed. No spent nuclear fuel (SNF) or other anomalous materials (containers, stained soils, or other waste forms) were discovered. Phase 1 verification sampling indicated that additional remediation was needed for Trench A and a portion of one of the sorting cells. Verification sampling of Trenches B and M indicated that remedial action objectives were met and a backfill concurrence was approved on June 16, 2009.

The stabilization of the remaining trenches, pits, and silos was deferred to the Phase 2 remediation, that resumed in October 2009 and was completed in March 2012. Approximately 127,768 BCM (167,114 BCY) of material was removed for disposal at ERDF or other approved facilities. During the excavation, in-process field radiological surveys using hand-held instrumentation and in-process soil samples were collected. Field screening at the site included using systematic global positioning radiological data mapping surveys (Global Positioning Environmental Radiological Surveyor [GPERS]) in the excavation with instrumentation specific to the detection of radiation associated with gamma- and beta-emitting radionuclides. In-process samples were collected from Trenches C and F; Trenches D, E, P, G; Trench K; Trench N; and Trench O at locations of elevated radiological activity identified by GPERS. In-process sample results for Trenches O and K identified strontium-90 in excess of groundwater and river protection RAGs at the base of the excavation.

On October 27, 2011, test pits were excavated at the base of both Trenches K and O excavations to collect vertical profile samples to evaluate residual strontium-90 activity with depth. Samples were collected at 0.9 meter (3 ft) intervals and analyzed for strontium-90, tritium, nickel-63, carbon-14, and gamma-emitting radionuclides. The results of this sampling showed strontium-90 decreasing with depth to activities less than the RAGs. However, tritium was detected in the deep vadose zone at Trench O with concentrations increasing with depth and above soil lookup values for groundwater protection. Tritium was not detected above RAGs in the Trench K characterization test pit samples. However, tritium above groundwater and river protection RAGs was detected at a separate excavation surface location in the Trench K deep zone.

On March 29, 2012, a test pit was excavated to a depth of 4.6 meters (15 ft) at the base of the Trench N excavation to collect vertical profile samples at 0.9 meter (3 ft) intervals to evaluate residual tritium contamination. Tritium was detected in all the test pit samples at activities exceeding criteria for protection of groundwater. The maximum activity detected was 13,400 pCi/g. All Phase 2 remediation areas have been backfilled. A new waste site, 100-K-132, was created to address residual deep vadose contamination within the context of the future final ROD.

The buried waste removed included non-reactor construction debris, reactor debris, lead shielding, reactor tubing, lead lined pigs, various glass and plastic containers, graphite canisters, drums, boron balls, incinerated radioactive material, zirconium jackets, dried paint, highly

radioactive piping and spent nuclear fuel. High dose rate material was shipped in concrete containers. Twelve pieces of spent nuclear fuel were removed, characterized and shipped to the 100-K Fuel Storage Basins.

Trenches A and B were excavated to a depth of 6 meters (19.7 ft). Trenches C and F were excavated to a depth of 7.1 meters (23 ft). Trenches D, E, P and G were excavated to a depth of 8.4 meters (27.5 ft). Trench H was excavated to a depth of 3.2 meters (10.5 ft). Trench I was excavated to a depth of 10 meters (35.7 ft). Trenches J and L were excavated to a depth of 9.9 meters (32.5 ft). Trench K was excavated to a depth of 9.4 meters (30.8 ft). Trench N was excavated to a depth of 15.6 meters (51.3 ft). Trench O was excavated to a depth of 12.2 meters (40 ft). Trench M contained only construction debris. The Phase 1 excavations were sampled and backfilled.

Remediation of the internal contents of the Trench I silos was completed on May 17, 2011. A total of 1,040 clamshell buckets of waste material were removed to empty these silos. These silos were found to contain soil, spacers, perforated aluminum fuel spacers, fuel baskets, activated metal wire, miscellaneous metal debris, fiberglass, conduit, crushed 208 liter (55 gal) drums, paraffin, various crushed containers, discarded tools, pipe, and pieces of SNF.

All Phase 2 remediation areas have been backfilled.

Code:	128-K-1	Classification:	Accepted
Names:	128-K-1; 100-K Burning Pit	Reclassification	Interim Closed Out (8/24/2004)
Type:	Burn Pit	Start Date:	1/1/1955
Status:	Inactive	End Date:	1/1/1971
Description:	The site has been remediated and Interim Closed Out. The site was a slight depression, about 0.91 meters (3.0 feet) below the surrounding grade, with pieces of concrete and metal debris visible at the surface.		
Location:	The site was located outside of the perimeter fence, southeast of the 100-K Burial Ground (118-K-1) and northeast of the 183-KE Settling Basins.		
Process Description:	This site was used for the disposal of nonradioactive combustible materials such as paint waste, office waste, and chemical solvents.		
Waste Type:	Misc. Trash and Debris		
Waste Description:	The site was used for the disposal of nonradioactive, combustible materials, such as paint waste, office waste, and chemical solvents.		
Closure Info:	Interim: Remedial action at the site consisted of two phases of confirmatory sampling that was conducted at the site in April and May 2003. Phase I consisted of test trenches and a test pit to evaluate the potential presence of buried debris or contaminated soil. Phase II consisted of identification and removal of surface debris with waste characterization and soil sampling, as needed. During the Phase II sampling, one location (P16) was found to have semivolatile organic contamination that required remediation. With agreement from the U.S. Environmental Protection Agency, the area with elevated levels of contamination was excavated during December 2003.		

Debris identified during the May 14, 2003, walkdown was removed and disposed of at the ERDF during Phase II confirmatory sampling. As previously stated, the Phase I confirmatory sampling results indicated that no remediation of the subsurface soil was required. However, based on the results of the Phase II confirmatory soil sampling, selective remediation of the 128-

K-1 site at the P16 location was necessary due to the presence of benzo[a]anthracene, benzo[a]pyrene, benzo[b]fluoranthene, benzo[k]fluoranthene, bis(2-ethylhexyl)phthalate, carbazole, chrysene, dibenzo[a,h]anthracene, and indeo(1,2,3-cd)pyrene, which exceeded the cleanup criteria. The remediation at the P16 location was performed during December 2003 by removing contaminated soil from an approximate 7 by 15 meters (23 by 49 ft) area to a depth of approximately 0.5 meter (1.6 ft) based on field observations of discolored soil. A total of 161 tons of contaminated soil from this location was disposed of at the ERDF.

After remediation, a verification sample of the underlying soil was collected to confirm that cleanup levels had been met. The results indicated that the waste removal action achieved compliance with the remedial action objectives for 128-K-1 site. The maximum detected residual contaminant levels from the soil samples were used to support site reclassification.

Code:	128-K-2	Classification:	Accepted
Names:	128-K-2; 100-K Construction Dump	Reclassification	Interim Closed Out (10/18/2012)
Type:	Burn Pit	Start Date:	
Status:	Inactive	End Date:	
Description:	The waste site has been remediated and Interim Closed Out. The 128-K-2 waste site was a former construction dump and burn pit area. It had been marked with a single chain fence with "Danger - Asbestos" warning signs marks the area.		
Location:	The site was located approximately 0.3 kilometers (0.2 miles) southwest of the 100-K Area perimeter fence, along the old Hanford Irrigation Project Canal.		
Process Description:	The waste site was used as a construction dump pit and burn pit.		
Waste Type:	Misc. Trash and Debris		
Waste Description:	A wide variety of trash is exposed on the ground surface. There is evidence of burning in many locations. Most of the material on the surface is scrap metal and glass. Office waste, paint, solvents, laboratory waste have also been found. The area is also covered with nonfriable and friable asbestos.		
Closure Info:	Interim (10/8/2012): Remedial action at the 128-K-2 waste site began on December 13, 2011 and was completed on May 8, 2012. Excavated material consisted of miscellaneous construction disposal debris scattered throughout the excavation area. The materials removed from the 128-K-2 waste site consisted of friable and nonfriable asbestos, metallic and wood debris, burnt wood, ash, tar, yellow paint, broken and intact glassware, and concrete debris. Remediation of the 128-K-2 waste site extended from 0.3 meter (1 ft) to a maximum depth of 6.5 meters (21 ft) below ground surface (bgs). The excavation resulted in the removal of 13,465 bank cubic meters (BCM) (17,612 bank cubic yards [BCY]) of miscellaneous construction disposal debris including friable and non-friable asbestos, metallic and wood debris, burnt wood, ash, tar, yellow paint, broken and intact glassware, and concrete. All material removed from the site was disposed at the Environmental Restoration Disposal Facility (ERDF).		
	While excavating near the center of the 128-K-2 waste site, field personnel noticed fuel oil odor from the soil at coordinates N146174.9/E567968.3. Additional remediation was performed in the fuel oil-contaminated area with all soil directly loaded out for disposal at ERDF.		

Code:	130-K-2	Classification:	Accepted
Names:	130-K-2; 1717-K Waste Oil Storage Tank	Reclassification	None

Type: Storage Tank **Start Date:** 1/1/1955
Status: Inactive **End Date:** 1/1/1972

Description: The site was an underground waste oil storage tank oriented with the long axis of the tank in a north-south direction. The tank was excavated in July 1989. The tank was used for storing used motor oil. The tank was left with a residual heel when the facilities were deactivated in 1971. The concrete pad over the top of the tanks was removed in July 1989. This allowed Pacific Northwest Laboratories to return to the tank site and perform Ground Penetrating Radar (GPR) to aid in locating the tank without the interference caused by the rebar in the concrete. The soil around where the tanks had been located was sampled, the results analyzed, and the site backfilled to match the surrounding grade.

Location: The site was located approximately 0.3 meters (1 foot) north of the 1717-K Maintenance and Transportation Service Building and 6.1 meters (20 feet) from the northwest corner of this building.

Related Sites/ Structures: The site was related to the 1717-K Maintenance and Transportation Service Building.

Waste Type: Oil

Waste Description: The unit was used for storage of used motor oil.

Code: 1607-K1 **Classification:** Accepted

Names: 1607-K1; 1607-K1 Sanitary Sewer System; 1607-K1 Septic Tank; 1607-K1 Septic Tank and Associated Drain Field; 124-K-1 **Reclassification:** None

Type: Septic Tank **Start Date:** 1/1/1955

Status: Active **End Date:**

Description: The sanitary sewer system is composed of a septic tank, leaching trench and associated piping. The septic tank and dosing chamber are composed of reinforced concrete per Hanford Standard E-5-11. There is a maximum of 1.5 meters (5 feet) of fill on the cover slab. There are 61 meters (200 feet) of 15 centimeter (6 inches) vitrified clay pipe to the septic tank, followed by 6.1 meters (20 feet) of 15 centimeter (6 inches) vitrified clay pipe to the leaching trench. The leaching trench contains 9.1 meters (30 feet) of 15 centimeters (6 inches) vitrified clay pipe laid with open joints.

Location: The system is located east of 1701-K, outside the patrol road and inside the 100K area fence.

Related Sites/ Structures: The system serviced the 1701-K (Badge House) and 1720-K (Offices and Telephone Exchange) buildings.

Waste Type: Sanitary Sewage

Waste Description: This unit receives sanitary sewage from 1701-K Badgehouse (security checkpoint), 1720-K Patrol Offices and Change Room, and 1721-K Trailer. The flow rate to this unit is estimated to have been 1,987 liters (525 gallons) per day.

Code: 1607-K2 **Classification:** Accepted

Names: 1607-K2; 1607-K2 Sanitary Sewer System; 1607-K2 Septic Tank; 1607-K2 Septic Tank and **Reclassification:** None

Associated Drain Field; 124-KE-1

Type: Septic Tank **Start Date:** 1/1/1955
Status: Active **End Date:**

Description: The sanitary sewer system is composed of a septic tank, leaching trench and associated piping. The septic tank is composed of steel per Hanford Standard E-5-11. There is a maximum of 1.5 meters (5 feet) of fill on the cover slab. There are 26 meters (85 feet) of 15 centimeter (6 inches) vitrified clay pipe to the septic tank, followed by 6.1 meters (20 feet) of 15 centimeter (6 inches) vitrified clay pipe to the leaching trench. The leaching trench contains 33.5 meters (110 feet) of 15 centimeters (6 inches) vitrified clay pipe laid with open joints.

Location: The site is located east of 183-KE (Head House) and northeast of the 183-KE Chlorine Vault.

Related Sites/ Structures: The site serviced the 183-KE building.

Waste Type: Sanitary Sewage

Waste Description: This unit receives sanitary sewage from 183-KE Water Treatment Plant. The flow rate is estimated to have been 1230 liters (325 gallons) per day.

Code: 1607-K3 **Classification:** Accepted
Names: 1607-K3; 1607-K3 Sanitary Sewer System; 1607-K3 Septic Tank; 1607-K3 Septic Tank and Associated Drain Field; 124-KW-2 **Reclassification:** Interim Closed Out (7/10/2012)

Type: Septic Tank **Start Date:** 1/1/1955
Status: Inactive **End Date:** 1/1/1970

Description: The waste site has been remediated and Interim Closed Out. The tank and drain field were enclosed within a wooden fence and marked with Septic Tank and Drain Field signs.

Location: The site is located west of 183-KW (Head House) and northwest of the 183-KW Chlorine Vault.

Related Sites/ Structures: The site serviced the 183-KW Building.

Process Description: The 1607-K3 Sanitary Sewer System supported the 183-KW Water Treatment Plant, operating from 1955 to 1970. The volume of waste received is unknown. The sewer system was not known to have received hazardous or radioactive wastes, as it was installed for sanitary use.

The sanitary sewer system is composed of a septic tank, leaching trench, and associated piping. The 1900-liter (500-gallon) septic tank is constructed of steel per Hanford Standard E-5-11. There is a maximum of 1.5 meters (5 feet) of fill on the cover slab. The inlet pipe is 26 meters (85 feet) long and is constructed of 15-centimeter (6-inch) vitrified clay pipe. The pipe from the tank to the leach trench is 6.1 meters (20 feet) long and is also constructed of 15-centimeter (6-inch) vitrified clay pipe. The leaching trench contains 33.5 meters (110 feet) of 15-centimeter (6-inch) vitrified clay pipe laid with open joints.

Waste Type: Sanitary Sewage

Waste Description: This unit received sanitary sewage from 183-KW Water Treatment Plant. The flow rate is estimated to have been 1,230 liters (325 gallons) per day.

Closure Info: Interim (7/10/2012): Remediation of the Area AA Zone 1 Waste Sites began in April 2010 and ended in January 2012. The waste site structures and soils have been excavated as part of the

remedial activities for the 100-K Area. The excavation area was designated as 100-K Area AA, Zone 1 (Area AA, Zone 1). It encompassed the individual waste sites 100-K-34, 100-K-102 and 1607-K3. Stockpile #11 contains layback soil from remediation of Area AA, Zone 1. These waste sites are adjacent to the 100-K-59 pipelines. Since visible sediment was observed in the severed pipelines, a sample was collected in February 2011 from the open end of the pipe west of the 183.1KW Headhouse. A section of the 100-K-59 pipeline was removed.

Excavation of the waste sites continued to a final remediation maximum depth of 9.82 meters (32.2 ft), which was located within the footprint of 100-K-102. To support the deeper excavation for Area AA, Zone 1, layback soil was accumulated and managed as Stockpile #11. The excavation decision unit was approximately 7,331 square meters (78,910 ft²) for 100-K Area AA, Zone 1. The original footprint prior to additional process sewer pipe removal was divided into evenly spaced areas for statistical sampling outside the waste sites to address any potential for contamination spread.

Code: 1607-K5 **Classification:** Accepted

Names: 1607-K5; 1607-K5 Sanitary Sewer System; 1607-K5 Septic Tank; 1607-K5 Septic Tank and Associated Drain Field; 124-KE-2 **Reclassification:** None

Type: Septic Tank **Start Date:** 1/1/1955

Status: Active **End Date:**

Description: The unit includes a tile field.

Location: This septic tank and drain field are east of the 105-KE Reactor and west of the 118-K-1 Burial Ground.

Related Sites/Structures: This site services the 1706-KER Flow Laboratory, 1706-K Water Treatment Laboratory, 165-KE Powerhouse, 105-KE Reactor Building, and 115-KE Gas Recirculation System.

Waste Type: Sanitary Sewage

Waste Description: This unit receives sanitary sewage from 1706-KER Flow Laboratory, 1706-K Water Treatment Laboratory, 165-KE Powerhouse, 105-KE Reactor Building, and 115-KE Gas Recirculation System. The flow rate to this unit is estimated at 700 gal/d.

Code: 1607-K6 **Classification:** Accepted

Names: 1607-K6; 1607-K6 Sanitary Sewer System; 1607-K6 Septic Tank; 1607-K6 Septic Tank and Associated Drain Field; 124-KW-1 **Reclassification:** None

Type: Septic Tank **Start Date:** 1/1/1955

Status: Active **End Date:**

Description: The unit includes a tile field and the piping from the facilities to the tile field.

Location: This facility is east of the 105-KW Reactor.

Related Sites/Structures: This unit receives sanitary sewage from 105-KW Reactor Building, 115-KW Gas Recirculation Building, and 165-KW Powerhouse.

Waste Type: Sanitary Sewage

Waste Description: This unit receives sanitary sewage from 105-KW Reactor Building, 115-KW Gas Recirculation Building, and 165-KW Powerhouse.

Code: 116-KE-1	Classification: Accepted
Names: 116-KE-1; 115-KE Condensate Crib	Reclassification: None
Type: Crib	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1971

Description: The crib and pipeline were remediated in 2004, but the status was not reclassified. The Cleanup Status Report for the 116-KE-1 and 116-KW-1 (BHI-01737), documented the status of remediation at the sites to assist in future decision making. The crib structure was removed along with contaminated soil. At the completion of the 2004 project, the excavation approximately 717 square meters (7713 sq. ft.) with a depth of approximately 9.1 meters (30 ft.). The site excavation was backfilled with clean soil to the average adjacent grade elevation at that time. Carbon-14 was detected in deep zone soil at concentrations ranging from 1,880 pCi/g to 7,600 pCi/g. To avoid impacting adjacent building foundations and because of the depth of residual Carbon-14 contamination, impacted soils that did not meet the objectives of the interim ROD Amendment (EPA -1997) remain in place. Disposition of this site will be determined at a later date.

Remediation and sampling of a large excavation area, known as 100-K Area AH, began in January of 2009 and was completed in April of 2012. It encompassed waste sites 100-K-6, 100-K-46, 100-K-62 and 132-KE-1 waste sites and also the site of the previously excavated 116-KE-1 crib. Area-wide carbon-14 contamination exists in the deep zone above the criteria for protectiveness. This contamination is associated with the 105-KE Reactor ventilation filtration system and the deep contamination from the condensate that collected in the previously excavated 116-KE-1 Condensate Crib. Additional remediation of the deep vadose zone cannot be completed in proximity to the 105-KE Reactor without impacting structural stability. Due to the depth of the contamination, the carbon-14 remediation will coincide with the final decision on 105-KE reactor removal.

Location: The crib was located north of 115-KE and east of 118-KE-1 (105-KE Reactor Building).

Related Sites/Structures: The distribution system was composed of a 10.2-centimeter (4-inch) pipe that led into an 20.3-centimeter (8-inch) corrugated galvanized steel perforated pipe, 3.2 meters (10.5 feet) long, with two 2-meter (6.5-foot) sections branching off at 45 degrees. The site received effluent from the 105-KE Reactor Buildings.

Process Description: The crib was constructed to receive condensate from the 105-KE gas purification system. The base of the crib was 1.8 meters (6 feet) in diameter and was positioned 7.8 meters (25.5 feet) below the ground surface. The top of the crib measures 12.2 meters (40 feet) in diameter. The crib was filled with coarse gravel to 3 meters (10 feet) above the base. The remainder of the crib was backfilled with dirt to grade. The site included the feed pipeline coming from the 115-KE Building.

Waste Type: Process Effluent

Waste Description: The site received condensate and other waste from reactor gas purification systems. Beta/gamma concentrations within the crib, taken from two sample boreholes drilled in 1976, range from 4.5E+05 picocuries per gram to 8.6E+05 picocuries per gram. The radionuclide inventory curies decayed through April 1, 1986, includes tritium (56.5 curies), carbon-14 (110 curies), and small amounts of other elements.

Code: 116-KE-2 **Classification:** Accepted
Names: 116-KE-2; 1706-KER Waste Crib and Pipeline **Reclassification:** None
Type: Crib **Start Date:** 1/1/1955
Status: Inactive **End Date:** 1/1/1971

Description: The waste site is a wooden crib structure and the associated piping.

Location: The crib is located west of the 1706-KER Building.

Waste Type: Process Effluent

Waste Description: The site received wastes from cleanup columns in the 1706-KER loop. Drilling in the mid-1970's next to the crib revealed concentrations of radionuclides in the soil. The total estimated concentration was 38 curies. The radionuclide inventory decayed through April 1, 1986, was estimated at approximately 14.6 curies, and is composed predominantly of cobalt-60 and strontium-90. Approximately 100,000 kilograms (220,500 pounds) of sodium hydroxide may have been disposed of into the crib as well as 100,000 kilograms (220,500 pounds) of sulfuric acid.

Code: 116-KE-3 **Classification:** Accepted
Names: 116-KE-3; 105-KE Fuel Storage Basin Storage Basin French Drain; 105-KE Sub-Basin Drainage Disposal System Crib **Reclassification:** None
Type: Injection/Reverse Well **Start Date:** 1/1/1955
Status: Inactive **End Date:** 1/1/1971

Description: The waste site is part of the sub-basin drainage disposal system for the 105-KE Fuel Storage Basin (100-K-42). The site includes a feed pipe, crib structure, dry well, and test hole. Although 116-KE-3 was located inside the Area AG, Zone 1 boundary, it was in an "excluded region" and not considered part of the AG Zone 1 remediation scope. Remedial action from 2010 through 2012 at adjacent waste sites impacted waste site 116-KE-3. At this location, the excavation depth was approximately 12.5 meters (41 ft) from original grade at 116-KE-3 to 130 meters (426 ft) above mean sea level. Excavation to this depth resulted in the removal of the perforated crib pipelines. The gravel directly below the pipelines and the 8 in. steel well casing to groundwater were not completely removed. Remedial activities did not remove all of the vadose zone contamination encountered at 116-KE-3. The expected depth of the excavation necessary to remediate the contaminated soil was not possible without threat to the integrity of the KE Reactor. To provide immediate protection to human health, the area was backfilled with clean soil.

It had been cobble covered and posted with "Underground Radioactive Material" warning signs. A mound of soil, installed in 1977 or 1978, covered some of the ancillary units related to this site. The test hole's 10.2-centimeter (4-inch) diameter steel casing originally extended above finish grade level but was no longer visible.

A 20.3-centimeter (8-inch) corrugated galvanized steel feed pipe 8.8 meters (29 feet) below grade comes from the fuel storage basin. The feed pipe enters the crib structure at elevation 133 meters (435.5 feet).

The crib structure is trapezoid shaped with the top at grade level (Elevation: 142 meters [464.5 feet]) and approximately 18.3 meters (60 feet) in width (excavation and backfill width) and the bottom (Elevation: 425.5 feet) 3.05 meters (10 feet) in width. The bottom 3.7 meters (12 feet)

of the crib is filled with coarse gravel.

The distribution system (drain field) within the crib is a central feeder with side feeders ("fishbone") located 8.8 meters (29 feet) below grade. All feeder piping is composed of 20.3-centimeter (8-inch) corrugated and perforated galvanized steel pipe. The main feeder pipe within the drain field is 6.1 meters (20 feet) long. The side feeders coming from each side of the central feeder are 2.7 meters, 3.2 meters, 2.6 meters, and 1.5 meters (9.0 feet, 10.5 feet, 8.5 feet, and 5.0 feet) in length, 1.75 meters, 1.7 meters, and 1.3 meters (5.75 feet, 5.5 feet, 4.25 feet) apart, and set at an angle of 30 degrees (Drawing #H-1-23207 is labeled 30 degrees, however, it appears on the drawing to be closer to 60 degrees.) The drain field is 6.1 meters (20 feet) in diameter.

A dry well (injection well) was installed at the midpoint (Washington State Plane Coordinates: Easting 569130.985, Northing 146753.534) of the drain field main feeder pipe. The dry well is constructed of 20.3-centimeter (8-inch) schedule 40 steel well casing. The dry well casing runs from elevation 435.5 feet (8.8 meters/29 feet below grade) downward to a point 3.05 meters (10 feet) below the mean water table. The bottom 6.1 meters (20 feet) of the well casing is perforated.

The 10.2-centimeter (4-inch) steel test hole extended from the surface to the head end of the drain field. The test hole piping was the only part of site's structure that was above grade. The construction of the "D" catch tank modification would have covered the test hole.

Location: The site is located north of the 105-KE Reactor Building (118-KE-1) about 23 meters (75 feet).

Related Sites/ Structures: The site is associated with 100-K-42 fuel storage basin.

Process Description: The site operated from 1955 to 1971 as an overflow crib for sub-basin drainage from the 105-KE Fuel Storage Basin (100-K-42).

Waste Type: Process Effluent

Waste Description: The waste is contaminated structures and soil from the fuel storage basin sub-basin drainage system.

Code: 116-KE-5	Classification: Accepted
Names: 116-KE-5; 150-KE Heat Recovery Station	Reclassification: Interim Closed Out (9/23/2005)
Type: Process Unit/Plant	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1971

Description: The site has been remediated and Interim Closed Out. The facility was constructed on a concrete pad and consisted of heat exchangers and associated piping. The heat exchangers had been removed and are being used elsewhere. Exposed piping had wooden covers installed over the open ends. Remedial action activities at the 100-K reactor sites began on December 9, 2002 by Washington Closure Hanford (WCH). Remediation involved excavation and staging of overburden material and removal of contaminated piping, debris and soil at the 100-K-55:1, 100-K-56:1, 116-KW-4 and 116-KE-5 waste sites. Contaminated materials were disposed at the ERDF. Remedial action excavation was completed on April 15, 2005.

Location: The site was located north of 118-KE-1 (105-KE Reactor Building) and east of the reactor cooling effluent lines near 116-KE-4 (107-KE Retention Basins).

Release Description: There were no known releases from this heat exchange station. Only surface contamination is on the remaining pipes.

Process Description: effluent. The station used an ethylene glycol solution as the heat exchanger medium. The system was no longer intact.

Waste Type: Equipment

Waste Description: Trace amounts of radioactive contamination remain on piping.

Closure Info: Interim: Remedial action activities at the 100-K reactor effluent pipelines began on December 9, 2002 by Washington Closure Hanford (WCH). Remediation of the pipelines involved excavation and staging of overburden material and removal of contaminated piping, debris and soil at the 100-K-55:1, 100-K-56:1, 116-KW-4 and 116-KE-5 waste sites. Contaminated materials were disposed at the ERDF. Remedial action excavation was completed on April 15, 2005. The previously documented waste site boundaries for the 116-KW-4 and 116-KE-5 sites were much larger than the actual footprint of the heat recovery facilities. The soil area beneath each of the former heat recovery stations was excavated in its entirety with the removal of the co-located pipelines. Approximately 55,960 square meters (602,350 sq ft) of plan area was excavated, including excavation within the deep zone (greater than 4.6 meters [15 ft] below ground surface) up to 8.8 meters (29 ft) below ground surface where necessary to complete remediation. Approximately 86,551 metric tons (95,406 U.S. tons) of material from the sites was removed and disposed at the ERDF. The active 100-K-47 concrete culvert was not removed during remediation of the adjacent section of the 100-K-55 pipeline. Several 100-K-56 pipe segments, located west of 116-KE-4, were not included in the remediation scope.

The contaminated materials from these sites have been excavated and disposed at the ERDF. The remaining soils at the sites have been sampled, analyzed, and modeled, and the results do not preclude any future uses (as bounded by the rural-residential scenario), allow unrestricted use of shallow zone soils, and pose no threat to groundwater or the Columbia River. The 100-K-55:1, 100-K-56:1, 116-KW-4, and 116-KE-5 sites were verified to be remediated in accordance with the ROD and may be backfilled.

Code: 116-KE-6A	Classification: Accepted
Names: 116-KE-6A; 1706-KE Condensate Collection Tank; 1706-KE Waste Treatment System	Reclassification: Interim Closed Out (8/4/2010)
Type: Storage Tank	Start Date: 1/1/1984
Status: Inactive	End Date: 1/1/1987

Description: The site has been remediated and Interim Closed Out. The site consisted of a 96 gallon condensate collection tank, which was part of the 1706-KE Waste Treatment System installed in 1984.

Location: The tank was located northwest of the 1706-KER building.

Release Description: On August 18, 1986, a 30 gallon epoxy vessel overheated. The event resulted in the forcible ejection of some of the resin material from the treatment unit. The epoxy overheating caused the emission of thick white vapors but no fire was observed. The ejected waste material was slightly radioactive. The material was cleaned up and packaged for low-level burial by operations personnel. No radioactivity was found outside the radiation zone. The area was cleaned to background radiation levels. (see Event Investigation Report D/T-86-01)

Related Sites/Structures: Other WTS sites were 116-KE-6B, 6C, 6D.

Process Description: In 1984, a new system of radioactive waste treatment was initiated that consisted of an evaporation and epoxy encapsulation unit. During the original operation, a small stream of

waste water was fed into a drum of hot epoxy at a constant rate. The water flashed to steam and traveled to a condenser where it was cooled and collected in the condensate collection tank. The liquid was sampled to determine if the radionuclide content was below releasable limits. Solids were collected in the epoxy. When a sufficient volume of epoxy (containing solid waste) was accumulated, a catalyst was added to harden the epoxy in the drum. The drum of solid epoxy was sealed and transported to a radioactive burial ground. This process ended in August 1986 when an ion exchange column was attached the accumulation tank. This process circulated the radioactive waste water through the ion exchange column until the radionuclide content was below the releasable limit.

Waste Type: Equipment

Waste Description: The unit was used to treat radioactive wastes generated from sample analysis and test activities conducted in the laboratories of the 1706-KE Building. The system stopped operating in 1987. All of the waste was removed in 1994.

Closure Info: Interim: The 1706-KE Waste Treatment System (WTS), was a Treatment, Storage and Disposal (TSD) unit located in the 1706-KER Building under the Resource Conservation and Recovery Act of 1976 (RCRA) and subject to RCRA corrective action requirements. As documented in the 100 Area Remaining Sites ROD, the RCRA corrective actions and CERCLA remedial actions were coordinated such that the result of the remedial action satisfied both sets of requirements. RCRA closure of the WTS was completed in 2009. The DOE/RL-2010-42 RSVP addresses the completion of the CERCLA remedial action.

The 116-KE-6A, 116-KE-6B, 116-KE-6C, and 116-KE-6D waste sites were removed using standard industrial materials and equipment. Remedial action activities were accomplished from June 15 through July 9, 2009. The waste materials from sites 116-KE-6A, 116-KE-6B, and 116-KE-6C were loaded on shipping containers July 1, 2009, and shipped to the Environmental Restoration Disposal Facility (ERDF) on July 9, 2009. The 116-KE-6D site was disposed in October 1996 at the low-level burial grounds. The ion exchange column, 116-KE-6D, was removed from the WTS in 1994. The column was containerized for future disposal at the Low-Level Burial Grounds and disposed in October 1996. Remedial activities for the 116-KE-6A, 116-KE-6B, and 116-KE-6C waste sites were initiated in June 2009, under RCRA TSD closure plan (DOE/RL-2009-29) and the RDR/RAWP for the 100 Area (DOE/RL-96-17) requirements. A pre-existing hatchway located immediately above the WTS area was utilized to move the condensate collection tank (116-KE-6A), evaporator tank (116-KE-6B), and waste accumulation tank (116-KE-6C) directly into shipping containers for disposal. Because of the size of the waste accumulation tank in relation to the hatchway, reducing the size of the tanks was necessary in order to remove them from the building. Following removal of the tanks, the room in which the tanks were located was cleaned of debris and surveyed for radiological contamination.

After completion of the TSD closure activities, Ecology provided an approval letter for the RCRA TSD closure plan. Upon completion of remediation, a Professional Engineer's Certification for the RCRA Closure of the 1706-KE WTS was issued. The engineer's certification and Ecology's acceptance letter were provided in Appendices A and B of the RSVP.

Verification sampling was not required under the scope of closure for the waste sites, since the floor and walls in the 1706-KER Building were not included as part of either the RCRA TSD closure certification or under this CERCLA remedial action.

The cost to remove the above-grade portion of the 1706-KER Facility, which included removal and disposal of the waste sites was approximately \$1.60 million. The effort to remove the waste sites was estimated at 10 percent of the project cost, which yielded an estimated cost of \$160,000 for remediation of the four waste sites.

Code:	116-KE-6B	Classification:	Accepted
Names:	116-KE-6B; 1706-KE Evaporation Tank; 1706-KE Waste Treatment System	Reclassification	Interim Closed Out (8/4/2010)
Type:	Storage Tank	Start Date:	1/1/1984
Status:	Inactive	End Date:	
Description:	The site consisted of a 30 gallon evaporation unit, which was part of the 1706-KE Waste Treatment System installed in 1984.		
Location:	The tank was located northwest of the 1706-KER building.		
Release Description:	On August 18, 1986, a 30 gallon epoxy vessel overheated. The event resulted in the forcible ejection of some of the resin material from the treatment unit. The epoxy overheating caused the emission of thick white vapors but no fire was observed. The ejected waste material was slightly radioactive. The material was cleaned up and packaged for low-level burial by operations personnel. No radioactivity was found outside the radiation zone. The area was cleaned to background radiation levels. (see Event Investigation Report D/T-86-01)		
Related Sites/ Structures:	Other WTS sites were 116-KE-6A, 6C, 6D.		
Process Description:	In 1984, a new system of radioactive waste treatment was initiated that consisted of an evaporation and epoxy encapsulation unit. During the original operation, a small stream of waste water was fed into a drum of hot epoxy at a constant rate. The water flashed to steam and traveled to a condenser where it was cooled and collected in the condensate collection tank. The liquid was sampled to determine if the radionuclide content was below releasable limits. Solids were collected in the epoxy. When a sufficient volume of epoxy (containing solid waste) was accumulated, a catalyst was added to harden the epoxy in the drum. The drum of solid epoxy was sealed and transported to a radioactive burial ground. This process ended in August 1986 when an ion exchange column was attached the accumulation tank. This process circulated the radioactive waste water through the ion exchange column until the radionuclide content was below the releasable limit.		
Waste Type:	Equipment		
Waste Description:	The unit was used to treat radioactive wastes generated from sample analysis and test activities conducted in the laboratories of the 1706-KE Building. The system stopped operating in 1987. All of the waste was removed in 1994.		
Closure Info:	Interim: The 1706-KE Waste Treatment System (WTS), was a Treatment, Storage and Disposal (TSD) unit located in the 1706-KER Building under the Resource Conservation and Recovery Act of 1976 (RCRA) and subject to RCRA corrective action requirements. As documented in the 100 Area Remaining Sites ROD, the RCRA corrective actions and CERCLA remedial actions were coordinated such that the result of the remedial action satisfied both sets of requirements. RCRA closure of the WTS was completed in 2009. The DOE/RL-2010-42 RSVP addresses the completion of the CERCLA remedial action.		
	The 116-KE-6A, 116-KE-6B, 116-KE-6C, and 116-KE-6D waste sites were removed using standard industrial materials and equipment. Remedial action activities were accomplished from June 15 through July 9, 2009. The waste materials from sites 116-KE-6A, 116-KE-6B, and 116-KE-6C were loaded on shipping containers July 1, 2009, and shipped to the Environmental Restoration Disposal Facility (ERDF) on July 9, 2009. The 116-KE-6D site was disposed in October 1996 at the low-level burial grounds. The ion exchange column, 116-KE-6D, was removed from the WTS in 1994. The column was containerized for future disposal at the Low-Level Burial Grounds and disposed in October 1996. Remedial activities for the 116-KE-6A,		

116-KE-6B, and 116-KE-6C waste sites were initiated in June 2009, under RCRA TSD closure plan (DOE/RL-2009-29) and the RDR/RAWP for the 100 Area (DOE/RL-96-17) requirements. A pre-existing hatchway located immediately above the WTS area was utilized to move the condensate collection tank (116-KE-6A), evaporator tank (116-KE-6B), and waste accumulation tank (116-KE-6C) directly into shipping containers for disposal. Because of the size of the waste accumulation tank in relation to the hatchway, reducing the size of the tanks was necessary in order to remove them from the building. Following removal of the tanks, the room in which the tanks were located was cleaned of debris and surveyed for radiological contamination.

After completion of the TSD closure activities, Ecology provided an approval letter for the RCRA TSD closure plan. Upon completion of remediation, a Professional Engineer's Certification for the RCRA Closure of the 1706-KE WTS was issued. The engineer's certification and Ecology's acceptance letter were provided in Appendices A and B of the RSVP.

Verification sampling was not required under the scope of closure for the waste sites, since the floor and walls in the 1706-KER Building were not included as part of either the RCRA TSD closure certification or under this CERCLA remedial action.

The cost to remove the above-grade portion of the 1706-KER Facility, which included removal and disposal of the waste sites was approximately \$1.60 million. The effort to remove the waste sites was estimated at 10 percent of the project cost, which yielded an estimated cost of \$160,000 for remediation of the four waste sites.

Code:	116-KE-6C	Classification:	Accepted
Names:	116-KE-6C; 1706-KE Waste Accumulation Tank; 1706-KE Waste Treatment System	Reclassification	Interim Closed Out (8/4/2010)
Type:	Storage Tank	Start Date:	1/1/1984
Status:	Inactive	End Date:	
Description:	The site consisted of a 550 gallon waste accumulating tank, which was part of the 1706-KE Waste Treatment System installed in 1984.		
Location:	The tank was located northwest of the 1706-KER building.		
Release Description:	On August 18, 1986, a 30 gallon epoxy vessel overheated. The event resulted in the forcible ejection of some of the resin material from the treatment unit. The epoxy overheating caused the emission of thick white vapors but no fire was observed. The ejected waste material was slightly radioactive. The material was cleaned up and packaged for low-level burial by operations personnel. No radioactivity was found outside the radiation zone. The area was cleaned to background radiation levels. (see Event Investigation Report D/T-86-01)		
Related Sites/ Structures:	Other WTS sites were 116-KE-6A, 6B, 6D.		
Process Description:	In 1984, a new system of radioactive waste treatment was initiated that consisted of an evaporation and epoxy encapsulation unit. During the original operation, a small stream of waste water was fed into a drum of hot epoxy at a constant rate. The water flashed to steam and traveled to a condenser where it was cooled and collected in the condensate collection tank. The liquid was sampled to determine if the radionuclide content was below releasable limits. Solids were collected in the epoxy. When a sufficient volume of epoxy (containing solid waste) was accumulated, a catalyst was added to harden the epoxy in the drum. The drum of solid epoxy was sealed and transported to a radioactive burial ground. This process ended in August 1986 when an ion exchange column was attached the accumulation tank. This process		

circulated the radioactive waste water through the ion exchange column until the radionuclide content was below the releasable limit.

Waste Type: Equipment

Waste Description: The unit was used to treat radioactive wastes generated from sample analysis and test activities conducted in the laboratories of the 1706-KE Building. The system stopped operating in 1987. All of the waste was removed in 1994.

Closure Info: Interim: The 1706-KE Waste Treatment System (WTS), was a Treatment, Storage and Disposal (TSD) unit located in the 1706-KER Building under the Resource Conservation and Recovery Act of 1976 (RCRA) and subject to RCRA corrective action requirements. As documented in the 100 Area Remaining Sites ROD, the RCRA corrective actions and CERCLA remedial actions were coordinated such that the result of the remedial action satisfied both sets of requirements. RCRA closure of the WTS was completed in 2009. The DOE/RL-2010-42 RSVP addresses the completion of the CERCLA remedial action.

The 116-KE-6A, 116-KE-6B, 116-KE-6C, and 116-KE-6D waste sites were removed using standard industrial materials and equipment. Remedial action activities were accomplished from June 15 through July 9, 2009. The waste materials from sites 116-KE-6A, 116-KE-6B, and 116-KE-6C were loaded on shipping containers July 1, 2009, and shipped to the Environmental Restoration Disposal Facility (ERDF) on July 9, 2009. The 116-KE-6D site was disposed in October 1996 at the low-level burial grounds. The ion exchange column, 116-KE-6D, was removed from the WTS in 1994. The column was containerized for future disposal at the Low-Level Burial Grounds and disposed in October 1996. Remedial activities for the 116-KE-6A, 116-KE-6B, and 116-KE-6C waste sites were initiated in June 2009, under RCRA TSD closure plan (DOE/RL-2009-29) and the RDR/RAWP for the 100 Area (DOE/RL-96-17) requirements. A pre-existing hatchway located immediately above the WTS area was utilized to move the condensate collection tank (116-KE-6A), evaporator tank (116-KE-6B), and waste accumulation tank (116-KE-6C) directly into shipping containers for disposal. Because of the size of the waste accumulation tank in relation to the hatchway, reducing the size of the tanks was necessary in order to remove them from the building. Following removal of the tanks, the room in which the tanks were located was cleaned of debris and surveyed for radiological contamination.

After completion of the TSD closure activities, Ecology provided an approval letter for the RCRA TSD closure plan. Upon completion of remediation, a Professional Engineer's Certification for the RCRA Closure of the 1706-KE WTS was issued. The engineer's certification and Ecology's acceptance letter were provided in Appendices A and B of the RSVP.

Verification sampling was not required under the scope of closure for the waste sites, since the floor and walls in the 1706-KER Building were not included as part of either the RCRA TSD closure certification or under this CERCLA remedial action.

The cost to remove the above-grade portion of the 1706-KER Facility, which included removal and disposal of the waste sites was approximately \$1.60 million. The effort to remove the waste sites was estimated at 10 percent of the project cost, which yielded an estimated cost of \$160,000 for remediation of the four waste sites.

Code: 116-KE-6D	Classification: Accepted
Names: 116-KE-6D; 1706-KE Ion Exchange Column; 1706-KE Waste Treatment System	Reclassification: Interim Closed Out (8/4/2010)
Type: Process Unit/Plant	Start Date: 1/1/1984

Status: Inactive

End Date:

Description: The site consisted of a 5 cubic foot mixed-bed resin ion exchange column, which was part of the 1706-KE Waste Treatment System installed in 1984.

Location: The ion exchange column was located northwest of the 1706-KER building.

Release Description: On August 18, 1986, a 30 gallon epoxy vessel overheated. The event resulted in the forcible ejection of some of the resin material from the treatment unit. The epoxy overheating caused the emission of thick white vapors but no fire was observed. The ejected waste material was slightly radioactive. The material was cleaned up and packaged for low-level burial by operations personnel. No radioactivity was found outside the radiation zone. The area was cleaned to background radiation levels. (see Event Investigation Report D/T-86-01)

Related Sites/ Structures: Other WTS sites were 116-KE-6A, 6B, 6C.

Process Description: In 1984, a new system of radioactive waste treatment was initiated that consisted of an evaporation and epoxy encapsulation unit. During the original operation, a small stream of waste water was fed into a drum of hot epoxy at a constant rate. The water flashed to steam and traveled to a condenser where it was cooled and collected in the condensate collection tank. The liquid was sampled to determine if the radionuclide content was below releasable limits. Solids were collected in the epoxy. When a sufficient volume of epoxy (containing solid waste) was accumulated, a catalyst was added to harden the epoxy in the drum. The drum of solid epoxy was sealed and transported to a radioactive burial ground. This process ended in August 1986 when an ion exchange column was attached the accumulation tank. This process circulated the radioactive waste water through the ion exchange column until the radionuclide content was below the releasable limit.

Waste Type: Equipment

Waste Description: The unit was used to treat radioactive wastes generated from sample analysis and test activities conducted in the laboratories of the 1706-KE Building. The system stopped operating in 1987. All of the waste was removed in 1994.

Closure Info: Interim: The 1706-KE Waste Treatment System (WTS), was a Treatment, Storage and Disposal (TSD) unit located in the 1706-KER Building under the Resource Conservation and Recovery Act of 1976 (RCRA) and subject to RCRA corrective action requirements. As documented in the 100 Area Remaining Sites ROD, the RCRA corrective actions and CERCLA remedial actions were coordinated such that the result of the remedial action satisfied both sets of requirements. RCRA closure of the WTS was completed in 2009. The DOE/RL-2010-42 RSVP addresses the completion of the CERCLA remedial action.

The 116-KE-6A, 116-KE-6B, 116-KE-6C, and 116-KE-6D waste sites were removed using standard industrial materials and equipment. Remedial action activities were accomplished from June 15 through July 9, 2009. The waste materials from sites 116-KE-6A, 116-KE-6B, and 116-KE-6C were loaded on shipping containers July 1, 2009, and shipped to the Environmental Restoration Disposal Facility (ERDF) on July 9, 2009. The 116-KE-6D site was disposed in October 1996 at the low-level burial grounds. The ion exchange column, 116-KE-6D, was removed from the WTS in 1994. The column was containerized for future disposal at the Low-Level Burial Grounds and disposed in October 1996. Remedial activities for the 116-KE-6A, 116-KE-6B, and 116-KE-6C waste sites were initiated in June 2009, under RCRA TSD closure plan (DOE/RL-2009-29) and the RDR/RAWP for the 100 Area (DOE/RL-96-17) requirements. A pre-existing hatchway located immediately above the WTS area was utilized to move the condensate collection tank (116-KE-6A), evaporator tank (116-KE-6B), and waste accumulation tank (116-KE-6C) directly into shipping containers for disposal. Because of the size of the waste accumulation tank in relation to the hatchway, reducing the size of the tanks was necessary in order to remove them from the building. Following removal of the tanks, the

room in which the tanks were located was cleaned of debris and surveyed for radiological contamination.

After completion of the TSD closure activities, Ecology provided an approval letter for the RCRA TSD closure plan. Upon completion of remediation, a Professional Engineer's Certification for the RCRA Closure of the 1706-KE WTS was issued. The engineer's certification and Ecology's acceptance letter were provided in Appendices A and B of the RSVP.

Verification sampling was not required under the scope of closure for the waste sites, since the floor and walls in the 1706-KER Building were not included as part of either the RCRA TSD closure certification or under this CERCLA remedial action.

The cost to remove the above-grade portion of the 1706-KER Facility, which included removal and disposal of the waste sites was approximately \$1.60 million. The effort to remove the waste sites was estimated at 10 percent of the project cost, which yielded an estimated cost of \$160,000 for remediation of the four waste sites.

Code:	118-KE-2	Classification:	Accepted
Names:	118-KE-2; Rod Cave; 105-KE Horizontal Control Rod Storage Cave	Reclassification	Interim Closed Out (6/14/2011)
Type:	Storage	Start Date:	1/1/1955
Status:	Inactive	End Date:	1/1/1971
Description:	The waste site has been remediated and Interim Closed Out. The site was constructed by pouring a concrete slab 18 meters (60 feet) long by 2.4 meters (8 feet) wide. Two sections of 61-centimeter (24-inch) pipe were cut in half lengthwise, laid open side down on the slab. Vertical concrete walls and steel doors were added to the ends of the pipe sections, with the walls forming a wing at each end. The pipe sections were then covered with 1.8 meters (6 feet) of clean fill material, forming a 12-meter (40-foot) long tunnel. The berm width after the fill material was added is approximately 8 meters (25 feet). The entire structure is above grade.		
Location:	The site is located northeast of the 105-KE Building.		
Related Sites/ Structures:	105-KE Reactor and the 100-K-9 and 100-K-10 french drains.		
Process Description:	The unit was used for temporary storage of radioactive rod tips associated with the 105-KE Reactor for radioactive decay pending subsequent disposal.		
Waste Type:	Equipment		
Waste Description:	This site contains trace amounts of radionuclides. The radiation level at the entrance to the cave with the door open is 1 millirad/hour. The unit was used for temporary storage of radioactive rod tips for radioactive decay pending subsequent disposal.		
Closure Info:	Interim (6/14/2011): The entire 118-KE-2 Waste Site structure, including the concrete slab, was removed in September 2009 to facilitate heavy equipment access to the 105-KE Building and associated Fuel Storage Basin to support ongoing remedial activities. The interim action consisted of successful removal and disposal of the entire 118-KE-2 Waste Site. Materials from the demolition of the structure and shipped to the ERDF for disposal.		

Code:	120-KE-1	Classification:	Accepted
--------------	----------	------------------------	----------

Names: 120-KE-1; 183-KE Acid Neutralization Pit; 183-KE Filter Waste Facility Dry Well; 183-KE Filter Water Facility; 100-K-26; 100-KE-1 **Reclassification** None

Type: Sump **Start Date:** 1/1/1955

Status: Inactive **End Date:** 1/1/1971

Description: The site was an underground concrete structure used to neutralize acid waste prior to disposal. The "pit" was a concrete box lined with acid proof bricks. The structure was divided into three sections by dividing brick weirs. Effluent released into the system was held up in a small chamber by the first weir. Effluent overflowed the first weir into a second small chamber and then overflowed the second weir into the third larger chamber. A 10.2-centimeter (4-inch) vitrified tile drain was located in the bottom of the third large chamber and is believed to discharge to the process sewer (see Site Comment). The top of the pit was level with the surface and had a 7.6-centimeter (3-inch) plank cover that was posted with "Confined Space" and "Caution, Acid" warning signs. In August 2000, the area around the acid tanks was stabilized with gravel. The french drain and sump were backfilled. They are no longer visible. They are not marked or posted.

Location: The site is located near the southeast corner of the 183-KE Head House, south of the 120-KE-5 Sulfuric Acid Tank and east of the 100-K-23 Sodium Silicate Tank Site.

Related Sites/ Structures: The site was associated with the 183-KE Head House and the 183-KE Sulfuric Acid Tanks.

Process Description: The method of acid neutralization is not known. When two other acid neutralization pits (100-K-34 and 100-K-35) that were associated with the elevated day use tanks at 183-KE and 183-KW were opened, crushed limestone was visible. Limestone may also be at the 120-KE-1 site beneath the discarded sludge.

Waste Type: Chemicals

Waste Description: The site received sulfuric acid for neutralization and acid sludge waste that was removed from the sulfuric acid storage tanks in the late 1960's and early 1970's.

Code: 120-KE-2 **Classification:** Accepted

Names: 120-KE-2; 183 KE Filter Water Facility; 183-KE Filter Waste Facility French Drain; 100-KE-2 **Reclassification** None

Type: French Drain **Start Date:** 1/1/1955

Status: Inactive **End Date:** 1/1/1971

Description: The unit was an open-bottomed french drain with a depth of 0.9 meters (3 feet) and a diameter of 0.9 meters (3 feet). It is had been located inside four, yellow posts with chain. In August 2000, the drain was backfilled and the area around the acid tanks was stabilized with gravel. The french drain and sump were backfilled. They are no longer visible. They are not marked or posted.

Location: The site is located 37 meters (121.4 feet) east of the southeast corner of 183-1KE head house and adjacent to the 120-KE-4 Sulfuric Acid Tanks.

Process Description: Hanford drawing H-1-25264 describes this drain as being a 0.9-meter (3-foot) diameter, 1.8-meter (6-foot) long vitrified clay pipe placed vertically in an excavation that was about 4 meters (13 feet) across and 3.4 meters (11 feet) deep. The bottom 0.3 meters (1 foot) of the pipe was filled with course rock, as was the bottom 1.5 to 1.8 meters (5 to 6 feet) of the excavation.

Waste Type: Chemicals

Waste Description: The site received sulfuric acid sludge that was removed from sulfuric acid storage tanks.

Code: 120-KE-3	Classification: Accepted
Names: 120-KE-3; 183-KE Filter Water Facility Trench; 100-KE-3	Reclassification: None
Type: Trench	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1971

Description: The unit was a trench lined with sand. The trench received a sludge-water slurry. The contaminated soil was removed by an offsite vendor.

Location: The site was located east of 183-1KE, head house, north of the 120-KE-4 and 120-KE-5 sulfuric acid tanks, on the north side of the railroad tracks.

Waste Type: Chemicals

Waste Description: The site received sulfuric acid sludge that was removed from sulfuric acid storage tanks.

Code: 120-KE-4	Classification: Accepted
Names: 120-KE-4; 183-KE1 Sulfuric Acid Storage Tank	Reclassification: None
Type: Storage Tank	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1971

Description: The unit was located above ground and has a storage capacity of 38,267 liters (10,109 gallons). In June 2000, the above ground piping, motors, pumps and electrical wiring associated with the acid tanks were removed. The tank has been removed and disposed at ERDF. This tank is no longer in existence. The insides of the acid tanks were inspected, photographed and confirmed to be dry.

Location: The unit was located in the southeast corner of the 183-KE Headhouse.

Release Description: The supply pipe from this unit to the point of use inside the 183-KE Building developed a slow gradual leak. Before the leak was detected, an unknown quantity of sulfuric acid leaked into the ground at the northeast corner of 183-KE Building.

Related Sites/Structures: The site is associated with the 183-KE Headhouse, 120-KE-1, 120-KE-2 and 120-KE-5.

Process Description: The sulfuric acid was used to activate sodium silicate. During seasons of high turbidity, activated silica solution was fed into the raw water to aid in coagulation.

Waste Type: Chemicals

Waste Description: The unit was used for storage of sulfuric acid product.

Code: 120-KE-5	Classification: Accepted
Names: 120-KE-5; 183-KE2 Sulfuric Acid Storage Tank	Reclassification: None

Type: Storage Tank **Start Date:** 1/1/1955

Status: Inactive **End Date:** 1/1/1971

Description: The site was the westernmost of the two original sulfuric acid tanks at the 183-KE Headhouse. The tank has been removed and disposed at ERDF. This tank is no longer in existence. The tank was a horizontal, cylindrical shaped, steel tank supported aboveground on concrete saddles. The tank had a capacity of 38,267 liters (10,109 gallons).

Location: The tank was located near the southeast corner of the 183-KE Headhouse, east of the eastern sodium silicate storage tank site (100-K-23), and west of the second sulfuric acid storage tank (120-KE-4).

Related Sites/ The site is associated with the 183-KE Headhouse and 120-KE-4.

Structures:

Process The sulfuric acid was used to activate sodium silicate. During seasons of high turbidity,
Description: activated silica solution was fed into the raw water as an aid in coagulation.

Code: 120-KE-6 **Classification:** Accepted

Names: 120-KE-6; 183-KE Sodium Dichromate Tank **Reclassification** None

Type: Foundation **Start Date:** 1/1/1955

Status: Inactive **End Date:** 1/1/1971

Description: The site is a foundation where a sodium dichromate storage tank had been placed. The tank has been removed and all that remains is the concrete pad, contaminated soil, and any remaining piping. The vertical steel storage tank was 6.1 meters (20 feet) high, 5.8 meters (19 feet) in diameter, and had a 159,000-liter (42,000-gallon) storage capacity.

Location: The site is located on the east side of the 183-KE Building. The center of the pad is 6.1 meters (20 feet) from the building's east wall.

Release There are no documented releases. However, there is evidence of residual sodium dichromate
Description: in the soil that has accumulated from many years of unloading and handling.

Related Sites/ The site is associated with the 183-KE Building.

Structures:

Process Sodium dichromate was added to the process water as a corrosion inhibitor. It was metered and
Description: proportioned by a single step operation in the head house, and diluted and injected into the process water in the process water pump house. The proportioning pumps took their suction directly from the storage tank. Near the process water pump house, the pumps discharged through a back pressure valve into a service water stream which diluted the dichromate on its way to injection into the process water. The injection point was located on the discharge of the low lift pump. Dichromate injection was determined by the process water flow. The chemical storage facilities at the 183-KE Building were sized to provide sufficient chemicals for two to three months continuous operation. Chemicals were delivered to the 183-KE Building by rail. With the exception of chlorine, all chemicals were transferred to their storage tanks by pumping or by pressurizing the tank cars with compressed air.

Waste Type: Chemicals

Waste Staining from sodium dichromate can be seen in the soil near the concrete pad.
Description:

Code: 120-KE-8	Classification: Accepted
Names: 120-KE-8; 165-KE Brine Mixing Tank; 165-KE Brine Pit	Reclassification: None
Type: Sump	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1971

Description: The unit is a below grade concrete structure the provided brine for the 165-KE Powerhouse. The roof of the structure is approximately 0.3 meters (1 foot) above ground level. The opening into the pit is covered by a wooden cover that is in poor condition. The bottom of the pit has subsided and appears to have leaked or drained to the soils beneath the structure. Just south of the brine pit is a valve pit located within a vertical section of 1.2 meter (4 foot) diameter corrugated galvanized pipe. This valve pit contains residue and apparently was part of the brine operation. The brine pit has inner dimensions of 4.3 meters (14 feet) long by 2.4 meters (8 feet) wide by 2.7 meters (9 feet) tall. The bottom of each pit is filled with a 12.7 centimeter (7 inch) layer of 1.3 to 2.6 centimeter (1/2 to 1 inch) gravel topped by a 17.8 centimeter (7 inch) layer of 0.3 to 0.6 centimeter (1/8 to 1/4 inch) gravel. The pit has a 1.2 meter (4 foot) by 1.1 meter (3.5 foot) opening for receiving salt.

Location: The site is located near the northwest corner of the 165-KE Powerhouse.

Related Sites/ Structures: The site is associated with the 165-KE Powerhouse.

Process Description: The brine was probably used to regenerate the water softeners that treated water prior to steam generation within the 165-KE Powerhouse. Salt was off-loaded from rail cars and placed in the pit. Water was then circulated through the pit, and brine was pumped back to the 165-KE Powerhouse for further use.

Waste Type: Chemicals

Waste Description: The unit contains salt brine and residue. Based on sampling performed at the 120-KE-9 and 120-KW-7 brine pits, the brine and residue may be regulated as dangerous per WAC 173-303.

Code: 120-KE-9	Classification: Accepted
Names: 120-KE-9; 183-KE Brine Pit; 183-KE Salt Dissolving Pits and Brine Pump Pit	Reclassification: None
Type: Sump	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1971

Description: The site was interim stabilized in August 1998 the ceiling structures were demolished and the open chambers were backfilled to grade. Any remaining liquid was removed. All pit utilities were isolated.

The Salt Dissolving Pits and Brine Pump Pit are part of a single below-grade concrete structure that provided brine for the 183-KE Water Treatment Facility. Four wooden covers and one metal cover were visible at the surface. The wooden covers were in poor condition. In August of 1998 the ceiling structures were demolished and the open chambers were backfilled to grade.

The Brine Pump Pit is located adjacent to the two Salt Dissolving Pits. The pit is 3.3 meters (10.67 feet) long by 2.2 meters (7.33 feet) wide by 2.4 meters (8 feet) deep. It holds two pumps and the associated piping for the brine system. A 46 by 46 by 46-centimeter (18 by 18 by 18-inch) sump is located in the corner of the pit. The pump pit was accessible from the surface through a 0.6 by 0.6-meter (2 by 2-foot) opening.

Location: The site is located approximately 37 meters (120 feet) east of the east end of the 183-KE Water Filter Plant and just north of the railroad spur that serviced 183-KE.

Related Sites/ Structures: The brine pit is associated with the 183-KE Water Filter Plant.

Process Description: The salt brine was used to regenerate water softeners.

Waste Type: Chemicals

Waste Description: The unit contains salt brine and residue.

Code: 126-KE-2 **Classification:** Accepted

Names: 126-KE-2; 183-KE Liquid Alum Storage Tank #2 **Reclassification:** None

Type: Storage Tank **Start Date:** 1/1/1955

Status: Inactive **End Date:** 1/1/1971

Description: The site was an above ground vertical stainless steel storage tank mounted on a concrete base. The tank has been removed and disposed at ERDF. This tank is no longer in existence. The tank was part of a system called "The Liquid Alum System", that supplied liquid alum for water treatment. The liquid was supplied either by rail car or tank truck, as both connections are shown on the Liquid Alum System diagram in HW-24800-103. The piping and instrument identification diagram, H-1-16552, shows the pipelines, valves, and instrumentation related to the tank. During the winter, the liquid alum was pumped through heat exchangers for purpose of heating and agitating the chemicals. Use of this tank for the storage of alum was discontinued in the Fall of 1996.

Location: The site was the western-most of two alum storage tanks located approximately 15.2 meters (50 feet) from the southwest corner of the 183-KE Head House and 10.7 meters (35 feet) south of the 183-KE chlorine vault.

Related Sites/ Structures: The tank was associated with the 183-KE Head House. The head house was the water quality center for the entire water treatment plant. In it were the facilities for metering raw water, for chemical injection into raw, filtered, and process water, and for effluent and influent control throughout the filter plant.

Process Description: Alum was used as a coagulant in water treatment. During the season of water high turbidity activated silica was added as an aid in coagulation. Alum was fed from the storage tank and proportioned directly into the raw water line. The proportioning pump was paced by the flow of raw water in its 91 centimeters (36 inches) raw water pipeline and fed at 30 parts per million (ppm) at a maximum flow rate of 121,000 liters per minute (32,000 gallons per minute).

Waste Type: Chemicals

Waste Description: The unit was used for storage of liquid alum (aluminum sulfate). Material Safety Data Sheet (MSDS) #040407 lists aluminum sulfate as an EPA hazardous substance. The tank has not been cleaned out.

Code: 130-KE-1 **Classification:** Accepted

Names: 130-KE-1; 105-KE Emergency Diesel Fuel Tank; 105-KE Emergency Diesel Oil Storage Tank **Reclassification:** Interim Closed Out (6/23/2011)

Type: Storage Tank **Start Date:** 1/1/1955

Status: Inactive **End Date:** 1/1/1971

Description: The 130-KE-1 waste sites consisted of two 7,600-liter (2,000 gallon) capacity storage tanks, 130-KE-1A and 130-KE-1B. Once the storage tanks were removed from the site, the site was backfilled with native soil to grade and covered with gravel.

Location: The site is located on the east side of 105-KE, adjacent to the reactor exhaust stack.

**Related Sites/
Structures:** 105-KE Reactor

**Process
Description:** The 130-KE-1 Waste Site Tank System was used for storing diesel fuel from 1955 to 1971 to support use of the emergency fans housed in the basement of the 105-KE Reactor. The fans were in place as a backup ventilation system for the reactor.

Waste Type: Oil

**Waste
Description:** The unit was used for storage of diesel fuel (product).

Closure Info: Interim (6/23/2011): The 130-KE-1 Waste Site Tank System (including tanks 130-KE-1A and 130-KE-1B) was permanently closed by removal of the below-grade tanks and accessible piping on October 5, 1992. The remedial action for the 130-KE-1 Waste Site included removal and disposal of the tanks and sampling and analysis of the underlying soils for total petroleum hydrocarbons (TPH).

The 130-KE-1 Waste Site was removed using standard industrial equipment. The two tanks were empty upon removal. No visible staining was observed and no organic vapors were detected during monitoring of the excavation and 130-KE-1 Waste Site Tank System removal. Soils samples from the excavated area and the overburden were collected and analyzed in accordance with Ecology Publication 90-52. The 130-KE-1 Waste Site Tank System was received by Northwest EnviroField Services, Inc. on February 5, 1993, for disposal as scrap steel.

A complete site assessment was performed per WAC 173-360-390 immediately following the 130-KE-1 Waste Site Tank System removal. Samples were collected from the excavated area and the overburden. After the 130-KE-1 Waste Site Tank System was removed, the area was sampled and final data received, the site was backfilled to grade.

Code: 130-KE-2 **Classification:** Accepted

Names: 130-KE-2; 166-KE Oil Storage Tank; Oil Bunker **Reclassification:** None

Type: Storage Tank **Start Date:** 1/1/1955

Status: Inactive **End Date:** 1/1/1971

Description: The bunker is an underground, reinforced concrete structure. It has two compartments, each having a storage capacity of 3,033,629 liters (801,400 gallons).

Location: The fuel oil storage tanks are located southwest of 105-KE. They are west of the 165-KE Boilerhouse. The metal oil storage building is located on southeast corner of the site.

**Related Sites/
Structures:** The storage tanks are associated with the 165-KE boiler house.

Process Description: The tank was used for storage of fuel oil (product) for the 165-KW Boilers. Fuel was delivered to the bunkers from rail cars and filled through 15 centimeter (6 inch) diameter gravity lines. Two day tanks are located on the south side of each bunker. Each Day Tank had a 186,621 liter (49,300 gallon) capacity.

Waste Type: Oil

Waste Description: The unit was used for storage of oil (product) for the 165-KE Boilers.

Code: 132-KE-1	Classification: Accepted
Names: 132-KE-1; 116-KE Reactor Exhaust Stack	Reclassification: Interim Closed Out (8/29/2012)
Type: Stack	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1971

Description: The stack has been demolished and Interim Closed Out. It was a reinforced-concrete structure with an original height of 91.4 meters (300 ft). It also included the 3.1 meters (10 ft) below grade portion with a base diameter of 6.25 meters (20.5 ft). The stack was built on a 11 meter (36 ft) octagonal foundation that was approximately 1.2-meter (4 ft) thick. The entire below grade portion of the stack base was removed. The maximum excavation depth was approximately 6.1 meters (20 ft).

The original height of the exhaust stack was 91.5 meters (300 feet). In 1980 and 1981, the exhaust stack was shortened to 53.3 meters (175 ft). The debris from the stack shortening activity was placed inside the remaining portion of the stack. An opening at the bottom, with a steel door cover, provided access to the interior of the exhaust stack. Condensate from the stack discharged through a floor drain into the ground below the stack.

Location: The unit is located on the northeast side of the 105-KE Reactor Building.

Related Sites/Structures: Following completion of the confinement project in 1960, the air was diverted via underground reinforced concrete ducts to the 117-KE Filter Building. After flowing through the filters, the air went through below-grade concrete ducts and into the exhaust stack.

Process Description: The 132-KE-1 Waste Site (aka 116-KE Reactor Exhaust Stack) was designed to discharge ventilation exhaust air into the atmosphere from the 105-KE Reactor Building to prevent the possible buildup of radioactivity near the reactor area. The 116-KE Reactor Exhaust Stack operated from 1955 to 1971. Prior to 1960, air from the 105-KE Reactor Building flowed through concrete ducts directly out of the stack, later the air was diverted via underground reinforced concrete ducts to the 117-KE Filter Building. After flowing through the filters, the air went through below-grade concrete ducts and into the 116-KE Reactor Exhaust Stack.

Waste Type: Demolition and Inert Waste

Waste Description: Discharged ventilated air from the 105-KE Building flowed through concrete ducts directly out of the stack. The Exhaust Stack received radiologically contaminated exhaust air. The contaminants were cobalt-60, cesium-137, carbon-14, europium-152, europium-154, and europium-155, strontium-90 and tritium.

Closure Info: Interim (8/29/2012): Remediation and sampling began in January of 2009 and was completed in April of 2012. The large excavation area, known as 100-K Area AH, encompassed waste sites 100-K-6, 100-K-46, 100-K-62 and 132-KE-1. The excavation area also included Stockpile #4, which contained overburden and layback soil from the excavation of the 116-KE-1 Condensate Crib. Information supporting the use of Stockpile #4, located within the AH excavation, as backfill was also included in the DOE/RL-2012-38 Remaining Sites Verification Package

report.

Remediation of the identified Area AH waste sites was accomplished by demolishing the structures and excavating contaminated soil. All waste (soil and debris) associated with these waste sites was disposed at the Environmental Restoration and Disposal Facility (ERDF). The demolition activities were conducted using standard demolition techniques, including explosives for demolition of 132-KE-1 (116-KE Reactor Exhaust Stack). Approximately 1,809 ERDF containers (37,700 tons) of waste from these waste sites were sent to the ERDF for disposal.

Remediation of the 100-K-6 vacuum pit began in August 2011 and was completed in September 2011. An excavator was used to remove the vacuum pit and excavate the surrounding soil. The original waste site description estimated the depth of the cyclone separator as 9.14 meters (30 ft). However, during remediation the actual excavation depth was measured as 5.8 meters (19 ft).

The remediation of the 100-K-46 french drain was associated with the removal of the 119-KE building, which began in January 2009 and was completed in February 2009. The drywell was less than 1.5 meters (5 ft) deep.

The remediation activities at the 100-K-62 filter building began in August 2010 and were completed in May 2011. An excavator was used to remove the vacuum pit and excavate the surrounding soil. The maximum depth from grade within the waste site footprint was approximately 10.6 meters (34.8 ft).

The remediation activities at waste site 132-KE-1 exhaust stack began in July 2010 and were completed in September 2011. Removal of the above-grade portion of the stack was conducted using explosives placed near the base of the stack. The explosion caused the debris to fall in a designated area. The material was then loaded and disposed at ERDF. The entire below grade portion of the stack base was then removed. The maximum depth from grade within the waste site footprint was approximately 6.1 meters (20 ft).

In October of 2010, excavation of the overburden and layback soil for the 116-KE-1 Crib began and Stockpile #4 was created. Samples were collected in the 116-KE-1 waste site footprint and sent for analytical leach testing of the soils to determine carbon-14 leachability from the 100-K soil. During remediation of the co-located waste sites inside the AH excavation area, the 116-KE-1 crib was partially backfilled with soil from Stockpile #4 as a contamination control measure.

Note: Area-wide carbon-14 contamination exists in the deep zone above the criteria for protectiveness. This contamination is associated with the 105-KE Reactor ventilation filtration system and the deep contamination from the condensate that collected in the previously excavated 116-KE-1 Condensate Crib. Additional remediation of the deep vadose zone cannot be completed in proximity to the 105-KE Reactor without impacting structural stability. Available information about the nature and extent of the carbon-14 contamination has been documented in the 116-KE-1 Condensate Crib waste site description. Due to the depth of the contamination, the carbon-14 remediation will coincide with the final decision on 105-KE reactor removal.

Code: 116-KW-1	Classification: Accepted
Names: 116-KW-1; 115-KW Condensate Crib	Reclassification: None
Type: Crib	Start Date: 1/1/1955

Status: Inactive**End Date:** 1/1/1971

Description: The crib and pipeline were remediated in 2004, but the status was not reclassified. The Cleanup Status Report for the 116-KE-1 and 116-KW-1 (BHI-01737), documented the 2004 status of remediation at the sites to assist in future decision making. The waste site was excavated, to the extent that could be safely conducted in the vicinity of adjacent buildings and to the capability of the onsite excavation equipment. It is considered complete. The excavated waste disposal is complete, and the exposed surfaces of the excavation have been sampled and analyzed to assess remaining contaminant concentrations. The excavation has been backfilled. At the completion of the 2004 project, the excavation for the 116-KW-1 site was approximately 759 meters squared (8,162 square feet) in area. The bottom of the excavation for the site was approximately 9.1 meters (30 feet) below the surrounding grade. Approximately 2,519 bank cubic meters of material from the 116-KW-1 site were disposed of at the Environmental Restoration Disposal Facility (ERDF).

Location: The crib was located north of 115-KW and east of 118-KW-1 (105-KW Reactor Building).

Related Sites/ Structures: The distribution system was composed of a 10.2 centimeter (4 inch) pipe that led into an 20.3 centimeter (8 inch) corrugated galvanized steel perforated pipe that was 3.2 meters (10.5 feet) long, with two 2-meter (6.5 foot) sections branching off at 45 degrees. The site received effluent from the 105-KW Reactor Buildings.

Process Description: The crib was constructed to receive condensate from the 105-KW gas purification system. Before the 2004 remediation the bottom of the crib was 1.8 meters (6 feet) in diameter and was 7.8 meters (25.5 feet) below the ground surface. The top of the crib measures 12.2 meters (40 feet) in diameter. The bottom of the crib was filled with 3 meters (10 feet) of course gravel, then backfilled with dirt to grade. This site included the feed pipeline from the 115-KW Building.

Waste Type: Process Effluent

Waste Description: The site received condensate and other wastewater from reactor gas purification systems. Drilling of the crib in the mid-1970's revealed high concentrations of tritium and carbon-14. The radionuclide inventory in curies decayed through April 1, 1986, includes tritium (81.9 curies), carbon-14 (110 curies), and small amounts of other elements.

Code: 116-KW-2**Classification:** Accepted

Names: 116-KW-2; 105-KW Basin Reverse Well; 105-KW Fuel Storage Basin Sub-Basin Drainage Disposal System Crib; 105-KW Storage Basin French Drain

Reclassification: None**Type:** Injection/Reverse Well**Start Date:** 1/1/1955**Status:** Inactive**End Date:** 1/1/1970

Description: The site is part of the sub-basin drainage disposal system for the 105-KW Fuel Storage Basin (100-K-43). The site includes a feed pipe, the crib structure, a dry well and test hole. The area is cobble covered. It is posted with "Underground Radioactive Material" warning signs. A mound of soil was installed in 1977 or 1978. The mound covers some of the ancillary units related to this site. The test hole is a 10.2-centimeter (4-inch) diameter steel casing that originally extended above grade level, but is no longer visible. The construction of the "D" catch tank modification would have covered the test hole.

Location: The site is located north of the 105-KW Reactor Building (118-KW-1) about 23 meters (75 feet).

Process Description: The site operated from 1955 to 1970 as an overflow crib for sub-basin drainage from the 105-KW Fuel Storage Basin (100-K-43).

Waste Type: Process Effluent

Waste Description: The waste is contaminated structures and soil from the fuel storage basin sub-basin drainage system.

Code: 116-KW-4

Classification: Accepted

Names: 116-KW-4; 150-KW Heat Recovery Station

Reclassification: Interim Closed Out (9/23/2005)

Type: Process Unit/Plant

Start Date: 1/1/1955

Status: Inactive

End Date: 1/1/1970

Description: The site has been remediated and Interim Closed Out. The site consisted of heat exchangers, pumps, and associated piping on a concrete pad. Remedial action activities at the 100-K reactor sites began on December 9, 2002 by Washington Closure Hanford (WCH). Remediation involved excavation and staging of overburden material and removal of contaminated piping, debris and soil at the 100-K-55:1, 100-K-56:1, 116-KW-4 and 116-KE-5 waste sites. Contaminated materials were disposed at the ERDF. Remedial action excavation was completed on April 15, 2005.

Location: The site was located south of 116-KW-3 (107-KW Retention Basins) and north of the 118-KW-1 (105-KW Reactor Building).

Process Description: The site was used to transfer heat from the 105-KW Reactor cooling water effluent. The heat recovery stations used an ethylene glycol solution as the heat exchanger medium. The system is no longer intact.

Waste Type: Equipment

Waste Description: Trace amounts of radioactive contamination remained on the piping. The heat exchange medium consisted of a 34% ethylene glycol-water solution.

Closure Info: Interim: Remedial action activities at the 100-K reactor effluent pipelines began on December 9, 2002 by Washington Closure Hanford (WCH). Remediation of the pipelines involved excavation and staging of overburden material and removal of contaminated piping, debris and soil at the 100-K-55:1, 100-K-56:1, 116-KW-4 and 116-KE-5 waste sites. Contaminated materials were disposed at the ERDF. Remedial action excavation was completed on April 15, 2005. The previously documented waste site boundaries for the 116-KW-4 and 116-KE-5 sites were much larger than the actual footprint of the heat recovery facilities. The soil area beneath each of the former heat recovery stations was excavated in its entirety with the removal of the co-located pipelines. Approximately 55,960 square meters (602,350 sq ft) of plan area was excavated, including excavation within the deep zone (greater than 4.6 meters [15 ft] below ground surface) up to 8.8 meters (29 ft) below ground surface where necessary to complete remediation. Approximately 86,551 metric tons (95,406 U.S. tons) of material from the sites was removed and disposed at the ERDF. The active 100-K-47 concrete culvert was not removed during remediation of the adjacent section of the 100-K-55 pipeline. Several 100-K-56 pipe segments, located west of 116-KE-4, were not included in the remediation scope.

The contaminated materials from these sites have been excavated and disposed at the ERDF. The remaining soils at the sites have been sampled, analyzed, and modeled, and the results do not preclude any future uses (as bounded by the rural-residential scenario), allow unrestricted use of shallow zone soils, and pose no threat to groundwater or the Columbia River. The 100-K-55:1, 100-K-56:1, 116-KW-4, and 116-KE-5 sites were verified to be remediated in accordance with the ROD and may be backfilled.

Code: 118-KW-2	Classification: Accepted
Names: 118-KW-2; 105-KW Horizontal Control Rod Storage Cave	Reclassification: Interim Closed Out (6/14/2011)
Type: Storage	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1971

Description: The waste site has been remediated and Interim Closed Out. The cave was constructed by pouring a concrete slab 18.3 meters (60 feet) long by 2.4 meters (8 feet) wide. Two sections of 0.61-meter (24-inch) pipe were cut in half lengthwise and laid open side down, on the slab. Vertical concrete walls and steel doors were added to the ends of the pipe sections, with the walls forming a wing at each end. The pipe sections were then covered with 1.8 meters (6 feet) of clean fill material, forming a 12.2-meter (40-foot) long tunnel. The berm width after the fill material was added measured 7.6 meters (25 feet). The entire structure was above grade.

Location: The site was located northeast of the 105-KW Building.

Related Sites/ Structures: 105-KW Reactor, 100-K-11 and 100-K-12.

Process Description: The unit was used for temporary storage of radioactive rod tips associated with the 105-KW Reactor for radioactive decay pending subsequent disposal.

Waste Type: Equipment

Waste Description: The unit was used for temporary storage of irradiated and radioactively contaminated horizontal control rods containing unknown quantities of radionuclides. The tunnel contains four rod tips and other rod removal components. The radiation reading at the entrance to the cave with the door open is 50 millirad/hour.

Closure Info: Interim (6/14/2011): The entire 118-KW-2 Waste Site structure, including the concrete slab and drain system, was removed in November 2010 to facilitate future heavy equipment access to the 105-KW Building and associated Fuel Storage Basin to support remedial activities. The interim action consisted of successful removal and disposal of the entire 118-KW-2 Waste Site including rod tips stored within the cave. Minor soil contamination detected after demolition. The soil was excavated and taken to ERDF.

Code: 120-KW-1	Classification: Accepted
Names: 120-KW-1; 183-KW Acid Neutralization Pit; 183-KW Filter Water Facility Dry Well; 100-K-17; 100-KW-1	Reclassification: Interim Closed Out (10/28/2011)
Type: Sump	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1970

Description: The site was an underground concrete structure used to neutralize acid waste prior to disposal. The "pit" was a concrete box with approximate dimensions of 2.5 m (8.5 ft) x 2.0 m (6.3 ft) x 1.5 m (5 ft), and was lined on the sides with acid proof bricks. The structure is divided into three sections by dividing brick weirs. Effluent released into the system was held up in a small chamber by the first weir. Effluent overflowed the first weir into a second small chamber and then overflowed the second weir into the third larger chamber. A 10.2-centimeter (4-inch) vitrified tile drain was located in the bottom of the third chamber and is believed to discharge to the process sewer (see Site Comment). The top of the pit was level with the surface and had a 7.6-centimeter (3-inch) plank cover that is posted with "Confined Space" and "Caution, Acid"

warning signs. In August 2000, the area around the acid tanks was stabilized with gravel. The french drain and sump were backfilled. They are no longer visible. They are not marked or posted.

Location: The site is located near the southeast corner of the 183.1-KW Headhouse, south of the 120-KW-3 Sulfuric Acid Tank and east of the 100-K-21 Sodium Silicate Tank Site.

Related Sites/ Structures: The site was associated with the 183-KW Head House and the 183-KW Sulfuric Acid Tanks.

Process Description: The method of acid neutralization is not known. When two other acid neutralization pits (100-K-34 and 100-K-35) that were associated with the elevated day use tanks at 183-KE and 183-KW were opened, crushed limestone was visible. Limestone may also be at the 120-KW-1 site beneath the discarded sludge. From 1968 to 1971 commercial grade sulfuric acid was stored in the 183-KE/KW acid tanks. A heavy precipitate would accumulate in the bottom of the tanks. The tank sludge was periodically flushed from the tanks to adjacent drywells. When the K Reactors were shut down (1970-1971), the acid was removed from the tanks. Approximately 4950 kilograms (11,000 pounds) of sludge was washed out of the tanks into adjacent drainage trenches. The sludge was packaged into 55 gallon drums and sold to an off site vendor. Small amounts of sludge remained in the 183-KE/KW drywells. The drywell sludge was sampled in July 1985. The drywell at 183-KW exceeded the Washington State Department of Ecology Dangerous Waste Regulations limit for mercury. The dangerous waste limit for mercury was 0.2 parts per million. The sample collected in 1985 contained 0.387 parts per million of mercury.

Waste Type: Chemicals

Waste Description: The site received sulfuric acid for neutralization and acid sludge waste from the sulfuric acid storage tanks. The drywell sludge was sampled in 1985 and was analyzed for arsenic, barium, cadmium, Chromium, lead, mercury, silver and selenium. The sample taken from the 183-KW drywell contained elevated levels of mercury. The Washington State dangerous waste limit for mercury is 0.2 parts per million. The sample contained 0.387 parts per million of mercury. The other metals were below dangerous waste limitations.

Closure Info: Interim (10/28/2011): Waste Sites 120-KW-1, 120-KW-2, 120-KW-3 and 120-KW-4 were remediated to remove the remaining structures and associated contaminated soil between May 2010 and June 2011. The original remediation activity for was anticipated to end once excavation to a depth of 4.6 m (15 ft) was achieved. Excavation to support remediation of the yellow-colored contaminated soil, however, continued due to the ongoing detection of mercury contamination levels above the RAGs in the RDR/RAWP (DOE/RL-96-17). The final depth of the remediation was 14.2 meters (46.6 ft), which was located within the footprint of 120-KW-2. To support the deeper excavation, layback soil was accumulated in stockpiles (#7 and #9).

Stockpile #7 was started on April 19, 2011. No field quality control samples were collected; however the samples were analyzed for metals, hexavalent chromium and anions.

Stockpile #9 was started on May 17, 2011. No field quality control samples were collected however the samples were analyzed for metals, hexavalent chromium and anions.

Remediation south of the sedimentation basin (183.2-KW) at 100-KW was conducted as an area-wide remediation (100-K Area AA) to examine the soil underneath several co-located waste sites. Based on proximity and process, the remediation area was divided into 4 zones. The four waste sites included in this report comprise Zone 3.

Code: 120-KW-2

Classification: Accepted

Names: 120-KW-2; 183-KW Filter Water Facility French

Reclassification Interim Closed Out (10/28/2011)

Drain; 100-KW-2

Type: French Drain **Start Date:** 1/1/1955

Status: Inactive **End Date:** 1/1/1970

Description: The waste site has been remediated and Interim Closed Out. This unit was an open-bottomed french drain with a depth of 0.9 meters (3 feet) and a diameter of 0.9 meters (3 feet). In August 2000, the area around the acid tanks was stabilized with gravel. The french drain and sump were backfilled. They are no longer visible. They are not marked or posted.

Location: The site is located 37 meters (121.4 feet) east of the southeast corner of 183.1-KW Headhouse.

Process Description: The drain was constructed in an excavation that was about 4.0 meters (13 feet) across and 3.4 meters (11 feet) deep. The bottom 1.5 to 1.8 meters (5 to 6 feet) of the excavation was filled with course rock. A 0.9-meter (3-foot) diameter, 1.8-meter (6-foot) long vitrified clay pipe was placed vertically over the rock fill and the excavation was backfilled to grade. The bottom 0.3 meters (1 foot) of the pipe was filled with course rock.

Waste Type: Chemicals

Waste Description: The site received sulfuric acid sludge that was removed from sulfuric acid storage tanks.

Closure Info: Interim (10/28/2011): Waste Sites 120-KW-1, 120-KW-2, 120-KW-3 and 120-KW-4 were remediated to remove the remaining structures and associated contaminated soil between May 2010 and June 2011. The original remediation activity for was anticipated to end once excavation to a depth of 4.6 m (15 ft) was achieved. Excavation to support remediation of the yellow-colored contaminated soil, however, continued due to the ongoing detection of mercury contamination levels above the RAGs in the RDR/RAWP (DOE/RL-96-17). The final depth of the remediation was 14.2 meters (46.6 ft), which was located within the footprint of 120-KW-2. To support the deeper excavation, layback soil was accumulated in stockpiles (#7 and #9).

Stockpile #7 was started on April 19, 2011. No field quality control samples were collected; however the samples were analyzed for metals, hexavalent chromium and anions.

Stockpile #9 was started on May 17, 2011. No field quality control samples were collected however the samples were analyzed for metals, hexavalent chromium and anions.

Remediation south of the sedimentation basin (183.2-KW) at 100-KW was conducted as an area-wide remediation (100-K Area AA) to examine the soil underneath several co-located waste sites. Based on proximity and process, the remediation area was divided into 4 zones. The four waste sites included in this report comprise Zone 3.

Code: 120-KW-3 **Classification:** Accepted

Names: 120-KW-3; 183-KW1 Sulfuric Acid Storage Tank **Reclassification:** Interim Closed Out (10/28/2011)

Type: Storage Tank **Start Date:** 1/1/1955

Status: Inactive **End Date:** 1/1/1970

Description: The site is the westernmost of the two original sulfuric acid tanks at the 183.1-KW Headhouse. The tank is a horizontal, cylindrical-shaped, steel tank supported above ground on concrete saddles. The tank has a capacity of 38,267 liters (10,109 gallons).

Location: The tank is located near the southeast corner of the 183.1-KW Headhouse, east of the eastern Sodium Silicate Storage Tank Site (100-K-21) and west of the second original Sulfuric Acid Storage Tank (120-KW-4).

Release Description: The supply pipe from this unit to the point of use inside the 183.1-KW Building developed slow leaks that deposited an unknown amount of sulfuric acid in the ground between the tanks and the building. The soil in the general area of the leak was neutralized.

Related Sites/ Structures: The site is associated with the 183.1-KW Headhouse, 120-KW-1, 120-KW-2 and 120-KW-4.

Process Description: The sulfuric acid was used to activate sodium silicate. During seasons of high turbidity, activated silica solution was fed into the raw water to aid in coagulation.

Waste Type: Chemicals

Waste Description:

Closure Info: Interim (10/28/2011): Waste Sites 120-KW-1, 120-KW-2, 120-KW-3 and 120-KW-4 were remediated to remove the remaining structures and associated contaminated soil between May 2010 and June 2011. The original remediation activity for was anticipated to end once excavation to a depth of 4.6 m (15 ft) was achieved. Excavation to support remediation of the yellow-colored contaminated soil, however, continued due to the ongoing detection of mercury contamination levels above the RAGs in the RDR/RAWP (DOE/RL-96-17). The final depth of the remediation was 14.2 meters (46.6 ft), which was located within the footprint of 120-KW-2. To support the deeper excavation, layback soil was accumulated in stockpiles (#7 and #9).

Stockpile #7 was started on April 19, 2011. No field quality control samples were collected; however the samples were analyzed for metals, hexavalent chromium and anions.

Stockpile #9 was started on May 17, 2011. No field quality control samples were collected however the samples were analyzed for metals, hexavalent chromium and anions.

Remediation south of the sedimentation basin (183.2-KW) at 100-KW was conducted as an area-wide remediation (100-K Area AA) to examine the soil underneath several co-located waste sites. Based on proximity and process, the remediation area was divided into 4 zones. The four waste sites included in this report comprise Zone 3.

Code: 120-KW-4	Classification: Accepted
Names: 120-KW-4; 183-KW2 Sulfuric Acid Storage Tank	Reclassification: Interim Closed Out (10/28/2011)
Type: Storage Tank	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1970

Description: The unit is an above ground sulfuric acid storage tank and has a capacity of 38,000 liters (10,109 gallons). The site is the easternmost of the two original sulfuric acid tanks at the 183.1-KW Headhouse. The tank is a horizontal, cylindrical-shaped, steel tank supported above ground on concrete saddles.

Location: The unit is located in the southeast corner of the 183.1-KW Headhouse. The tank is located near the southeast corner of the 183.1-KW Headhouse, east of the eastern Sodium Silicate Storage Tank Site (100-K-21) and east of the other Sulfuric Acid Storage Tank (120-KW-3).

Related Sites/ Structures: The site is associated with 120-KW-1, 120-KW-2 and 120-KW-3.

Process Description: The sulfuric acid was used to activate sodium silicate. During seasons of high turbidity, activated silica solution was fed into the raw water to aid in coagulation.

Waste Type: Chemicals

Waste Description: The unit was used for storage of sulfuric acid product.

Closure Info: Interim (10/28/2011): Waste Sites 120-KW-1, 120-KW-2, 120-KW-3 and 120-KW-4 were remediated to remove the remaining structures and associated contaminated soil between May 2010 and June 2011. The original remediation activity for was anticipated to end once excavation to a depth of 4.6 m (15 ft) was achieved. Excavation to support remediation of the yellow-colored contaminated soil, however, continued due to the ongoing detection of mercury contamination levels above the RAGs in the RDR/RAWP (DOE/RL-96-17). The final depth of the remediation was 14.2 meters (46.6 ft), which was located within the footprint of 120-KW-2. To support the deeper excavation, layback soil was accumulated in stockpiles (#7 and #9).

Stockpile #7 was started on April 19, 2011. No field quality control samples were collected; however the samples were analyzed for metals, hexavalent chromium and anions.

Stockpile #9 was started on May 17, 2011. No field quality control samples were collected however the samples were analyzed for metals, hexavalent chromium and anions.

Remediation south of the sedimentation basin (183.2-KW) at 100-KW was conducted as an area-wide remediation (100-K Area AA) to examine the soil underneath several co-located waste sites. Based on proximity and process, the remediation area was divided into 4 zones. The four waste sites included in this report comprise Zone 3.

Code:	120-KW-5	Classification:	Accepted
Names:	120-KW-5; 183-KW Sodium Dichromate Storage Tank	Reclassification	Interim Closed Out (6/27/2012)
Type:	Foundation	Start Date:	1/1/1955
Status:	Inactive	End Date:	1/1/1971

Description: The waste site has been remediated and Interim Closed Out. The site was a foundation where a sodium dichromate storage tank was placed. The tank had been removed in 1971. All that remained was the concrete pad, the contaminated soil, and any remaining piping.

Location: The site was located on the east side of the 183-KW Building. The center of the pad was 6.1 meters (20 feet) from the building's east wall.

Release Description: There are no documented releases. However, there is evidence of residual sodium dichromate in the soil that has accumulated from many years of unloading and handling.

Related Sites/Structures: The site is associated with the 183-KW Building.

Process Description: Sodium dichromate was added to the process water as a corrosion inhibitor. It was metered and proportioned by a single step operation in the head house, and diluted and injected into the process water in the process water pump house. The proportioning pumps took their suction directly from the storage tank. Near the process water pump house, the pumps discharged through a back pressure valve into a service water stream which diluted the dichromate on its way to injection into the process water. The injection point was located on the discharge of the low lift pump. Dichromate injection was determined by the process water flow. The chemical storage facilities at the 183-KW Building were sized to provide sufficient chemicals for two to three months continuous operation. Chemicals were delivered to the 183-KE Building by rail. With the exception of chlorine, all chemicals were transferred to their storage tanks by pumping or by pressurizing the tank cars with compressed air.

Waste Type: Chemicals

Waste Description: Staining from sodium dichromate can be seen in the soil near the concrete pad.

Closure Info: Interim (6/27/2012): Remediation of the Area AA, Zone 2 waste sites (100-K-18, 100-K-19, 100-K-79:1, 100-K-79:2, 100-K-97, 120-KW-5 and 120-KW-7) began in May 2010. Throughout the remedial activity, because of the contaminants found in the process equipment and surface soils, in-process samples were collected and analyzed for metals, including chromium VI and anions (e.g., sulfate due to the sulfuric acid), at multiple locations and depths. In-process sampling occurred across all four zones in 100-K Area AA, although this report focuses on Zone 2 only. Throughout remediation, stained areas were targeted for in-process sampling; soils often were yellow-colored and high in lead, total chromium and mercury. Hexavalent chromium, which is the groundwater contaminant of greatest concern at 100-K, was detected on the soil surface down to 6 feet, at the beginning of remediation for Area AA Zone 2. Excavation continued to a final remediation depth of 10.96 meters (35.96 ft).

During a walkdown of Area AA by RL and EPA on September 20, 2011, it was determined that piping found within Zone 1 needed to be further investigated. The piping identified was determined to be a part of the process sewer line and was subsequently removed.

The excavation decision unit was approximately 3,228 square meters (34,745.9 sq. ft.). All contaminated soils and debris from the waste sites was disposed of in the Environmental Restoration Disposal Facility (ERDF).

Code:	120-KW-6	Classification:	Accepted
Names:	120-KW-6; 165-KW Brine Mixing Tank; 165-KW Brine Pit	Reclassification:	None
Type:	Sump	Start Date:	1/1/1955
Status:	Inactive	End Date:	1/1/1970

Description: The unit is a below grade concrete structure that provided brine for the 165-KW Powerhouse. The roof of the structure was approximately 0.3 meters (1 foot) above ground level. The opening into the pit was covered by a wooden cover. Just south of the brine pit is a valve pit located within a vertical section of 1.2-meter (4-foot) diameter corrugated galvanized pipe. This valve pit contains residue and apparently was part of the brine operation. In August 1998, remaining liquid was removed and the open pit was backfilled to grade. The brine pit has inner dimensions of 4.3 meters (14 feet) long by 2.4 meters (8 feet) wide by 2.7 meters (9 feet) tall. The bottom of each pit is filled with a 13-centimeter (7-inch) layer of 1.3 to 2.6-centimeter (0.5 to 1-inch) gravel topped by a 18-centimeter (7-inch) layer of 0.3 to 0.6-centimeter (1/8 to 1/4-inch) gravel. The pit has a 1.2-meter (4-foot) by 1.1-meter (3.5-foot) opening for receiving salt.

Location: The site is located near the northwest corner of the 165-KW Powerhouse.

Related Sites/ Structures: The site is associated with the 165-KW Powerhouse.

Process Description: The brine was probably used to regenerate the water softeners that treated water prior to steam generation within the 165-KW Powerhouse. Salt was off-loaded from rail cars and placed in the pit. Water was then circulated through the pit, and brine was pumped back to the 165-KW Powerhouse for further use.

Waste Type: Chemicals

Waste Description: The unit contains salt brine and residue. Based on sampling performed at the 120-KE-9 and 120-KW-7 Brine Pits, the brine and residue may be regulated as dangerous waste per

 Washington Administrative Code (WAC) 173-303.

Code: 120-KW-7	Classification: Accepted
Names: 120-KW-7; 183-KW Brine Pit; 183-KW Salt Dissolving Pits and Brine Pump Pit	Reclassification: Interim Closed Out (6/27/2012)
Type: Sump	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1970

Description: The waste site has been remediated and Interim Closed Out. Only four wooden covers and one metal cover were visible at the surface. The wooden covers were in poor condition. The unit contained saltcake and brine. In August 1998, remaining liquid was removed. The pit utilities were isolated, the ceiling slabs were demolished and the unit was backfilled to grade. The area was later excavated and Interim Closed Out.

Location: The site was located approximately 37 meters (120 feet) east of the east end of the 183-KW Water Filter Plant and just north of the railroad spur that serviced the plant.

Related Sites/ Structures: The brine pit is associated with the 183-KW Water Filter Plant.

Process Description: The salt brine was used to regenerate water softeners.

Waste Type: Chemicals

Waste Description: The unit contains salt brine and residue. A minimal sampling was performed at the site. The brine samples were analyzed by Hanford Environmental Health Foundation (HEHF) on September 5, 1989. A sample from one of the dissolving pits was described as a light yellow water-miscible liquid with approximately 1% yellow/orange residue and a pH of 6. The sample contained 12.5% sodium ion, 19.8% chloride ion, and 33 milligrams/liter potassium. The measured concentrations of EP-Toxicity metals were 0.12 milligrams/liter arsenic, 1.3 milligrams/liter barium, 0.1 milligrams/liter cadmium, 0.78 milligrams/liter chromium, 0.58 milligrams/liter lead, 0.28 milligrams/liter selenium, and 0.66 milligrams/liter silver. All other analytes were below detection limits. A sample from the other dissolving pit was also described as a very light yellow water-miscible liquid with approximately 10% white and tan crystals and a pH of 6. The sample contained 7.9% sodium ion, 19.7% chloride ion, and 240 milligrams/liter potassium. The measured concentrations of EP-Toxicity metals were 0.14 milligrams/liter arsenic, 1.9 milligrams/liter barium, 0.57 milligrams/liter chromium, 0.72 milligrams/liter lead, 0.31 milligrams/liter selenium, and 0.58 milligrams/liter silver. All other analytes were below detection limits. Only the liquid portions of the samples were analyzed. An informal review of results by the Sitewide Hazardous Waste Engineering Support Unit (SHWES) indicated that the brine and residue may be regulated as Dangerous Waste per Washington Administrative Code (WAC) 173-303.

Closure Info: Interim (6/27/2012): Remediation of the Area AA, Zone 2 waste sites (100-K-18, 100-K-19, 100-K-79:1, 100-K-79:2, 100-K-97, 120-KW-5 and 120-KW-7) began in May 2010. Throughout the remedial activity, because of the contaminants found in the process equipment and surface soils, in-process samples were collected and analyzed for metals, including chromium VI and anions (e.g., sulfate due to the sulfuric acid), at multiple locations and depths. In-process sampling occurred across all four zones in 100-K Area AA, although this report focuses on Zone 2 only. Throughout remediation, stained areas were targeted for in-process sampling; soils often were yellow-colored and high in lead, total chromium and mercury. Hexavalent chromium, which is the groundwater contaminant of greatest concern at 100-K, was detected on the soil surface down to 6 feet, at the beginning of remediation for Area AA Zone 2. Excavation continued to a final remediation depth of 10.96 meters (35.96 ft).

During a walkdown of Area AA by RL and EPA on September 20, 2011, it was determined that piping found within Zone 1 needed to be further investigated. The piping identified was determined to be a part of the process sewer line and was subsequently removed.

The excavation decision unit was approximately 3,228 square meters (34,745.9 sq. ft.). All contaminated soils and debris from the waste sites was disposed of in the Environmental Restoration Disposal Facility (ERDF).

Code:	130-KW-1	Classification:	Accepted
Names:	130-KW-1; 130-KW-1A/130-KW-1B Tanks; 105-KW Emergency Diesel Fuel Tank; 105-KW Emergency Diesel Oil Storage Tank	Reclassification	None
Type:	Storage Tank	Start Date:	1/1/1960
Status:	Inactive	End Date:	1/1/1971
Description:	The site is the location of two underground diesel storage tanks that were removed in 1992. Although the location description states the diesel tanks were located between the 105-KW exhaust stack and the 119-KW building, a sign is posted at the northwest corner of the 115 KW building that reads "130-KW-1 Diesel Tanks" This is further east and south of the reactor stack. There is no visual evidence of the tanks in either location. The site has been backfilled with uncontaminated soil to grade and covered with gravel. There is a very large Underground Radioactive Material area that surrounds the reactor facility. This site is not separately posted or marked.		
Location:	The site is located on the east side of the 105-KW Reactor Building. The underground diesel tanks were located between the reactor exhaust stack and the 119-KW Building.		
Release Description:	During the excavation of the diesel tanks, the site was found to be radioactively contaminated with contamination levels up to 400 counts per minute in the soil and on the exterior of the tanks. Due to this contamination, the pit was backfilled with uncontaminated soil and posted appropriately. Attempts to decontaminate the tanks were unsuccessful. The tanks were wrapped with plastic and disposed of on the Hanford site. Since the tanks were located very close to the reactor building, the long term plan for is to decontaminate or remove the remaining contaminated soil when the reactor and surrounding site is remediated. The site was not released due to the radioactive contamination.		
Related Sites/ Structures:	100-K-76 is a duplicate entry for this site.		
Process Description:	The tanks contained diesel fuel for the emergency generators during the operation of the 100-KW Reactor.		
Waste Type:	Soil		
Waste Description:	The tanks were used for storage of diesel fuel (product). Radioactive contamination was discovered on the exterior of both tanks when they were removed. The Organic Vapor Monitor readings were below the detection limit.		

Code:	130-KW-2	Classification:	Accepted
Names:	130-KW-2; 166-KW Oil Storage Tank	Reclassification	None
Type:	Storage Tank	Start Date:	1/1/1955
Status:	Inactive	End Date:	1/1/1970

Description: The bunker is an underground, reinforced concrete structure. It has two compartments, each having a storage capacity of 3,033,629 liters (801,400 gallons).

Location: The storage tank is located southwest of 105-KW. It is an underground facility west of the 165-KW Boiler House.

Process Description: The tank was used for storage of fuel oil (product) for the 165-KW Boilers. Fuel was delivered to the bunkers from rail cars and filled through 15 centimeter (6 inch) diameter gravity lines. Two day tanks are located on the south side of each bunker. Each Day Tank had a 186,621 liter (49,300 gallon) capacity.

Waste Type: Oil

Waste Description: The tank was used for storage of oil (product) for the 165-KW Boilers.

Code: 132-KW-1	Classification: Accepted
Names: 132-KW-1; 116-KW Reactor Exhaust Stack	Reclassification: None
Type: Stack	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1970

Description: 132-KW-1 is the 116-KW Reactor Exhaust Stack. The original height for the stack was 91.5 meters (300 feet). The stack was decontaminated and shortened 38 meters (125 feet) between 1980 and 1981. The remaining stack is 53.4 meters (175 feet) high. All debris from the partial stack demolition is contained in the below-ground portion of the waste site.

Location: The stack is located on the northeast side of the 105-KW Building.

Related Sites/Structures: Following completion of the confinement project in 1960, the air was diverted via underground reinforced concrete ducts to the 117-KW Filter Building. After flowing through the filters, the air went out the exhaust stack.

Waste Type: Demolition and Inert Waste

Waste Description: Discharged ventilation air from the 105-KW Building flowed through concrete ducts directly out the exhaust stack.

Code: 600-29	Classification: Accepted
Names: 600-29; 100-K Construction Lay-down Area; 100-K-41	Reclassification: Interim Closed Out (8/15/2012)
Type: Dumping Area	Start Date: 1/1/1952
Status: Inactive	End Date: 1/1/1954

Description: The waste site has been remediated and Interim Closed Out. The 600-29 waste site was approximately 82 acres (333,287 sq. meters) that, prior to remediation, contained multiple french drains, areas of burned material, barren soil, stained soil, suspect asbestos, and a variety of demolition-related surface debris. It was an abandoned dumping area containing several rectangular depressions and burn pits. Many areas of discolored soil included coal, rust colored soil and white residue patches. It also included a cement building foundation with two adjacent french drains. During the 2007 Orphan Site Evaluation (OSE) for the 100-K operable unit, the 600-29 waste site was walked down to collect further site characterization data. A total of forty discrete feature locations within the 600-29 site boundaries were collected using a hand-held

GPS unit. Photographs and GPS coordinates were documented for each feature. Each feature was categorized as a 600-29 waste component or as a miscellaneous restoration or stewardship item.

South of a gravel road that transverses the site is the Strong Motion Accelerometer (SMA) also known as H1K. The SMA site consists of a four-panel solar array and two 30-gallon galvanized drums. The two 30-gallon drums are set in the ground such that the base of the drum is about 1 meter below the surface. One drum houses only the SMA. The other drum contains the batteries and is connected to the SMA drum with a conduit.

Location: The site is located outside of the southern perimeter fence at 100K.

**Related Sites/
Structures:** This site is associated with 100-K-41 and 100-K-89.

**Process
Description:** This location was originally used as the construction camp and lay-down yard during construction of 105-KW. The lay-down area was in operation from approximately 1952 through 1954. The 105-KW was commissioned in January 1955. Discolored soil and suppressed vegetation are evident within the unit. Old roadways and rectangular depressions are still distinguishable today based on 1952 and 1953 aerial photographs. No facilities were on the site prior to the start of construction of the 100-K Reactors. Both new and pre-existing structures moved from other areas around the Hanford Site were used as temporary construction facilities. The structures included warehouses, small offices, huts, and fabrication shops. Areas on the southwest side of the 600-29, 100-K Construction Laydown Area were cleared and made suitable for bus and car parking.

Waste Type: Construction Debris

**Waste
Description:** Unit wastes consist of miscellaneous metals, wood, cans, bottles, construction hardware and materials, what appears to be tar dumped on the ground, buckets and mops covered with what appears to be tar, a 18.725-liter (5-gallon) bucket of oily rags, broken pieces of a toilet bowl, what appears to be asbestos and transite, and wire rope.

Closure Info: Interim (8/15/2012): Remedial action at the 600-29 and 100-K-89 waste sites began on September 21, 2011, and continued through April 5, 2012. Most of the remedial excavations were the result of visible surface debris, stains, and materials. These areas were excavated from a minimum of 0.3 meter (1 ft) in depth to as much as 3 meters (10 ft) in depth, as needed, to remove contamination. Excavations for french drains ranged from 1.2 to 1.8 meters (4 to 6 ft) in depth. A septic vault in the eastern portion of 600-29 required excavation to 10 feet below ground surface. All materials removed from the excavations were stockpiled within the excavations and then directly loaded for disposal at the Environmental Restoration Disposal Facility (ERDF). No stockpiles external to the excavations were created. The 100-K-89 waste site comprised a burned area with burnt material present on the surface (wood, metal, and roofing material) and the underlying soil. Contamination identified on the southwest edge of the 600-29 waste site led to an excavation that was expanded during remediation based on field observations. The expansion encompassed and completely removed the 100-K-89 waste site.

Contaminated materials removed from the 600-29 waste site consisted of red, black, and white stained soils or colored materials, concrete pads and rubble, a concrete sewer junction box, abandoned iron and vitrified clay piping, abandoned wiring, friable and nonfriable asbestos, metallic and wood debris, burnt wood, ash, tar, and other miscellaneous demolition debris. Materials removed from the 100-K-89 waste site consisted of burned debris (wood, metal, roofing material) and associated soils.

A total volume of 10,293 bank cubic meters (BCM) (6,157 BCM from the east side of 600-29 and 4,136 BCM from the west side of 600-29) was removed and disposed to ERDF during remediation.

100-NR-1

Code: 100-N-1	Classification: Accepted
Names: 100-N-1; HGP Settling Pond; HGP SWMU #6	Reclassification: Interim Closed Out (6/15/2004)
Type: Pond	Start Date: 1/1/1965
Status: Inactive	End Date: 1/1/1993

Description: The site has been remediated and Interim Closed Out. The settling pond was cut into the side of a steep slope leading to the river. A concrete flume was located at the south end of the site. An outlet valve and pipe were located on the west side of the site. It received effluent from the 185-N building drains (SWMU #3). After the solids settled, the liquid discharged to the 1908-NE outfall (SWMU #7). The settling pond was excavated and removed in 2001.

Location: The Hanford Generating Plant (HGP) Settling Pond was located between the HGP Seal Well building (1908-NE) and the 185-N Building.

Release Description: An oil spill occurred on January 2, 1987 that was contained in the settling pond. Clean up of the five gallon oil spill was conducted by United Nuclear Corporation (UNC) and JA Jones in February 1987.

Process Description: This unit was constructed to control the Hanford Generating Plant (HGP) waste stream effluents. The effluent flowed into the pond, allowed solids to settle, and the remaining liquid was released to 1908-NE (HGP outfall). A valve was installed on the outlet pipe to prevent the discharge of oil to the outfall. The unit received waste from the HGP condenser pit, service water pumps demineralizer backwash and runoff from the roof and parking lot. An outlet pipe drained the pond directly to 1908-NE (HGP Outfall). The piping from the HGP Building floor drains and sumps to the settling pond was included with the settling pond.

Waste Type: Process Effluent

Waste Description: The pond operated concurrently with the Hanford Generating Plant (HGP) and received process water from the plant that contained trace oxygen scavenging conditioners such as morpholine, hydrazine and ammonia. Sampling has indicated elevated levels of chromium, lead, nickel, calcium, copper, zinc and ammonia. Trace surface radioactive contamination is detectable.

Closure Info: Interim (6/15/2004): The 100-N Reactor provided fuel rods to the plutonium production process at Hanford, but also operated two 430 megawatt turbine generators for the generation of electricity. The Washington Public Supply System, later named Energy Northwest, was responsible for the Hanford Generating Plant located at 100-N Reactor. The Cleanup Verification Package (HGP-CVP-SWMUs 5, 6, 7, 8, 9, & 10) for the Hanford Generating Plant Solid Waste Management units was prepared by Energy Northwest in 2004. Some remedial actions at HGP began in 1992. Other characterization and remediation was completed in 2004. Remedial action activity descriptions include:

100-N-1 Settling Pond (SWMU#6) - Remediation activities conducted in 2001 removed approximately 0.9 meters (3 ft) of soil and settled solids material from the 100-N-1 Settling Pond (SWMU #6). The excavated material was disposed of at the Environmental Restoration Disposal Facility (ERDF).

100-N-3 Maintenance Garage French Drain, 100-N-41 Gate House Septic Tank and 100-N-45 Office Building Septic Tank make up SWMU #9. Remediation was determined not to be necessary for the 100-N-3 site and the 100-N-41 and 100-N-45 septic sites. The below grade structures of the drain and septic sites were demolished in place and backfilled with soil in 2004.

100-N-4 Tile Field (SWMU#5) - Confirmatory sampling activities and data evaluation

determined that remediation was not necessary for the 100-N-4 Tile Field.

100-N-5 Bone Yard (SWMU #10) - Remediation and removal activities for the 100-N-5 Bone Yard (SWMU #10) were primarily conducted in 2001 with the removal of the miscellaneous equipment, metal scrap, and general debris. The limited number of areas with sand blast media, ion exchange resin-like media and areas with soil staining and/or distressed vegetation were remediated in 2003 and 2004. The sand blast, ion exchange resin, and contaminated soil wastes were disposed of at the RABANCO landfill facility in Roosevelt, Washington.

The 100-N-46 Diesel under ground storage tank (UST) was excavated and removed in 2001. Soil contaminated with diesel was also excavated from the UST excavation. Contaminated soil was spread over the demolished 1703-N Office Building concrete slab foundation for attenuation. Upon completion of the remedial excavation, the bottom of the excavation was approximately 6.7 meters (22 ft) below the ground surface at the deepest location (southwest corner of excavation).

100-N-52 Gasoline underground storage tank (UST) was excavated and removed in 1992.

1908-NE Outfall (SWMU#7) - The original preferred remedy for the 1908-NE Outfall was Institutional Controls (continued monitoring). A radiological survey of the Outfall seal well and samples of water and sediment were collected from the Outfall seal well in 2001 to assess potential contamination associated with the Outfall. The outfall structure was demolished by the Washington Closure Hanford D&D organization in 2012, eliminating the Institutional Control requirement.

The 1716-NE Maintenance Garage building (SWMU #8), including the building slab and associated floor drain pipelines, were removed in their entirety during the 2003 and 2004 removal action activities. Prior to the removal action all chemical products were removed from the building and either properly disposed of or transferred to another facility for use. The building debris was used as fill for the 185-N Building basement.

Code:	100-N-3	Classification:	Accepted
Names:	100-N-3; HGP SWMU #9; Maintenance Garage French Drain; Maintenance Garage Waste Water Treatment Unit	Reclassification	Interim Closed Out (6/15/2004)
Type:	French Drain	Start Date:	1/1/1965
Status:	Inactive	End Date:	
Description:	The site has been remediated and Interim Closed Out. The french drain was marked by a 3-meter (10-foot) square barricade and gravel covering a 31-meter (100-foot) square surface. A 1.2-meter (4-foot) diameter steel plate covered the center. (the 100-N-3 garage french drain, the 100-N-41 septic tank and the 100-N-45 septic tank make up Solid Waste Management Unit (SWMU) #9).		
Location:	The site was located in the 100-N Area, at the Washington Public Power Supply System (WPPSS) Hanford Generating Plant Facility, approximately 7.6 meters (25 feet) east of 100-N-78 Hanford Generating Plant (HGP) Maintenance Garage.		
Related Sites/ Structures:	The unit received effluent from 100-N-78, the 1716-NE HGP Maintenance Garage.		
Process Description:	The former HGP consisted of two 430-megawatt turbine generators that operated from 1966 until 1986 using steam from the adjacent 100-N production reactor for generation of electricity. The generators were located in the 185-N Building. The site was an ancillary or support facility		

to the former Hanford Generating Plant.

Waste Type: Oil

Waste Description: The unit received petroleum wastes.

Closure Info: Interim (6/15/2004): The 100-N Reactor provided fuel rods to the plutonium production process at Hanford, but also operated two 430 megawatt turbine generators for the generation of electricity. The Washington Public Supply System, later named Energy Northwest, was responsible for the Hanford Generating Plant located at 100-N Reactor. The Cleanup Verification Package (HGP-CVP-SWMUs 5, 6, 7, 8, 9, & 10) for the Hanford Generating Plant Solid Waste Management units was prepared by Energy Northwest in 2004. Some remedial actions at HGP began in 1992. Other characterization and remediation was completed in 2004. Remedial action activity descriptions include:

100-N-1 Settling Pond (SWMU#6) - Remediation activities conducted in 2001 removed approximately 0.9 meters (3 ft) of soil and settled solids material from the 100-N-1 Settling Pond (SWMU #6). The excavated material was disposed of at the Environmental Restoration Disposal Facility (ERDF).

100-N-3 Maintenance Garage French Drain, 100-N-41 Gate House Septic Tank and 100-N-45 Office Building Septic Tank make up SWMU #9. Remediation was determined not to be necessary for the 100-N-3 site and the 100-N-41 and 100-N-45 septic sites. The below grade structures of the drain and septic sites were demolished in place and backfilled with soil in 2004.

100-N-4 Tile Field (SWMU#5) - Confirmatory sampling activities and data evaluation determined that remediation was not necessary for the 100-N-4 Tile Field.

100-N-5 Bone Yard (SWMU #10) - Remediation and removal activities for the 100-N-5 Bone Yard (SWMU #10) were primarily conducted in 2001 with the removal of the miscellaneous equipment, metal scrap, and general debris. The limited number of areas with sand blast media, ion exchange resin-like media and areas with soil staining and/or distressed vegetation were remediated in 2003 and 2004. The sand blast, ion exchange resin, and contaminated soil wastes were disposed of at the RABANCO landfill facility in Roosevelt, Washington.

The 100-N-46 Diesel under ground storage tank (UST) was excavated and removed in 2001. Soil contaminated with diesel was also excavated from the UST excavation. Contaminated soil was spread over the demolished 1703-N Office Building concrete slab foundation for attenuation. Upon completion of the remedial excavation, the bottom of the excavation was approximately 6.7 meters (22 ft) below the ground surface at the deepest location (southwest corner of excavation).

100-N-52 Gasoline underground storage tank (UST) was excavated and removed in 1992.

1908-NE Outfall (SWMU#7) - The original preferred remedy for the 1908-NE Outfall was Institutional Controls (continued monitoring). A radiological survey of the Outfall seal well and samples of water and sediment were collected from the Outfall seal well in 2001 to assess potential contamination associated with the Outfall. The outfall structure was demolished by the Washington Closure Hanford D&D organization in 2012, eliminating the Institutional Control requirement.

The 1716-NE Maintenance Garage building (SWMU #8), including the building slab and associated floor drain pipelines, were removed in their entirety during the 2003 and 2004 removal action activities. Prior to the removal action all chemical products were removed from the building and either properly disposed of or transferred to another facility for use. The

building debris was used as fill for the 185-N Building basement.

Code: 100-N-4	Classification: Accepted
Names: 100-N-4; HGP SWMU #5; HGP Tile Field	Reclassification: Interim Closed Out (6/15/2004)
Type: Drain/Tile Field	Start Date: 1/1/1966
Status: Inactive	End Date:

Description: The site has been remediated and Interim Closed Out. The tile field received effluent from the 185-N Building drains of the HGP 185-N building chemical laboratory and sanitary drains.

Location: The unit was located between the Hanford Generating Plant (HGP) Seal Well building (1908-NE) and the 185-N Building, upslope and east of the HGP Settling Pond.

Related Sites/ Structures: The tile field is associated with septic tank 100-N-95 (remediated in 2013).

Process Description: The former HGP consisted of two 430 megawatt turbine generators that operated from 1966 until 1986 using steam from the adjacent 100-N production reactor for generation of electricity. The generators were formerly located in the 185-N Building. The site was an ancillary or support facility to the former HGP. The site was an ancillary or support facility to the former HGP, and received effluent from the 185-N Building drains of the HGP Sanitary Sewer and lab. The unit was designed to release waste water by allowing it to percolate into the soil.

Waste Type: Sanitary Sewage

Waste Description: The unit received sanitary sewage and lab waste. Testing for corrosion inhibitors hydrazine and morpholine were performed in the lab. It is likely that reagents used for these tests were discharged to the unit.

Closure Info: Interim (6/15/2004): The 100-N Reactor provided fuel rods to the plutonium production process at Hanford, but also operated two 430 megawatt turbine generators for the generation of electricity. The Washington Public Supply System, later named Energy Northwest, was responsible for the Hanford Generating Plant located at 100-N Reactor. The Cleanup Verification Package (HGP-CVP-SWMUs 5, 6, 7, 8, 9, & 10) for the Hanford Generating Plant Solid Waste Management units was prepared by Energy Northwest in 2004. Some remedial actions at HGP began in 1992. Other characterization and remediation was completed in 2004. Remedial action activity descriptions include:

100-N-1 Settling Pond (SWMU#6) - Remediation activities conducted in 2001 removed approximately 0.9 meters (3 ft) of soil and settled solids material from the 100-N-1 Settling Pond (SWMU #6). The excavated material was disposed of at the Environmental Restoration Disposal Facility (ERDF).

100-N-3 Maintenance Garage French Drain, 100-N-41 Gate House Septic Tank and 100-N-45 Office Building Septic Tank make up SWMU #9. Remediation was determined not to be necessary for the 100-N-3 site and the 100-N-41 and 100-N-45 septic sites. The below grade structures of the drain and septic sites were demolished in place and backfilled with soil in 2004.

100-N-4 Tile Field (SWMU#5) - Confirmatory sampling activities and data evaluation determined that remediation was not necessary for the 100-N-4 Tile Field.

100-N-5 Bone Yard (SWMU #10) - Remediation and removal activities for the 100-N-5 Bone Yard (SWMU #10) were primarily conducted in 2001 with the removal of the miscellaneous equipment, metal scrap, and general debris. The limited number of areas with sand blast media, ion exchange resin-like media and areas with soil staining and/or distressed vegetation were

remediated in 2003 and 2004. The sand blast, ion exchange resin, and contaminated soil wastes were disposed of at the RABANCO landfill facility in Roosevelt, Washington.

The 100-N-46 Diesel under ground storage tank (UST) was excavated and removed in 2001. Soil contaminated with diesel was also excavated from the UST excavation. Contaminated soil was spread over the demolished 1703-N Office Building concrete slab foundation for attenuation. Upon completion of the remedial excavation, the bottom of the excavation was approximately 6.7 meters (22 ft) below the ground surface at the deepest location (southwest corner of excavation).

100-N-52 Gasoline underground storage tank (UST) was excavated and removed in 1992.

1908-NE Outfall (SWMU#7) - The original preferred remedy for the 1908-NE Outfall was Institutional Controls (continued monitoring). A radiological survey of the Outfall seal well and samples of water and sediment were collected from the Outfall seal well in 2001 to assess potential contamination associated with the Outfall. The outfall structure was demolished by the Washington Closure Hanford D&D organization in 2012, eliminating the Institutional Control requirement.

The 1716-NE Maintenance Garage building (SWMU #8), including the building slab and associated floor drain pipelines, were removed in their entirety during the 2003 and 2004 removal action activities. Prior to the removal action all chemical products were removed from the building and either properly disposed of or transferred to another facility for use. The building debris was used as fill for the 185-N Building basement.

Code:	100-N-5	Classification:	Accepted
Names:	100-N-5; HGP Bone Yard; HGP Disposal and Storage Area; HGP SWMU #10	Reclassification	Interim Closed Out (6/15/2004)
Type:	Storage	Start Date:	
Status:	Inactive	End Date:	
Description:	The site has been remediated and Interim Closed Out. The waste site was a surface storage yard. Some of the soil was oil stained. Garnet sandblasting grit was also present. Remedial and removal activities occurred in 2001.		
Location:	The unit was located southwest of the Hanford Generating Plant (HGP) Building (185-N) in the 100-N Area. It was inside the HGP security fence.		
Related Sites/ Structures:	The site was associated with the Hanford Generating Plant (HGP).		
Process Description:	Material and equipment were stored inside the southwest corner of the Hanford Generating Plant facility fence. Some of the material included scrap metal, electrical equipment, pipes and cables. The unit was located on a level area which had several spots of stressed or absent vegetation.		
Waste Type:	Construction Debris		
Waste Description:	The unit contained scrap iron, brass, copper, electrical components, piping, cable, and miscellaneous pieces of metal equipment. The site also contained oil stains, sand blasting grit, and ion exchange resin beads on the soil.		
Closure Info:	Interim (6/15/2004): The 100-N Reactor provided fuel rods to the plutonium production process at Hanford, but also operated two 430 megawatt turbine generators for the generation of electricity. The Washington Public Supply System, later named Energy Northwest, was		

responsible for the Hanford Generating Plant located at 100-N Reactor. The Cleanup Verification Package (HGP-CVP-SWMUs 5, 6, 7, 8, 9, & 10) for the Hanford Generating Plant Solid Waste Management units was prepared by Energy Northwest in 2004. Some remedial actions at HGP began in 1992. Other characterization and remediation was completed in 2004. Remedial action activity descriptions include:

100-N-1 Settling Pond (SWMU#6) - Remediation activities conducted in 2001 removed approximately 0.9 meters (3 ft) of soil and settled solids material from the 100-N-1 Settling Pond (SWMU #6). The excavated material was disposed of at the Environmental Restoration Disposal Facility (ERDF).

100-N-3 Maintenance Garage French Drain, 100-N-41 Gate House Septic Tank and 100-N-45 Office Building Septic Tank make up SWMU #9. Remediation was determined not to be necessary for the 100-N-3 site and the 100-N-41 and 100-N-45 septic sites. The below grade structures of the drain and septic sites were demolished in place and backfilled with soil in 2004.

100-N-4 Tile Field (SWMU#5) - Confirmatory sampling activities and data evaluation determined that remediation was not necessary for the 100-N-4 Tile Field.

100-N-5 Bone Yard (SWMU #10) - Remediation and removal activities for the 100-N-5 Bone Yard (SWMU #10) were primarily conducted in 2001 with the removal of the miscellaneous equipment, metal scrap, and general debris. The limited number of areas with sand blast media, ion exchange resin-like media and areas with soil staining and/or distressed vegetation were remediated in 2003 and 2004. The sand blast, ion exchange resin, and contaminated soil wastes were disposed of at the RABANCO landfill facility in Roosevelt, Washington.

The 100-N-46 Diesel under ground storage tank (UST) was excavated and removed in 2001. Soil contaminated with diesel was also excavated from the UST excavation. Contaminated soil was spread over the demolished 1703-N Office Building concrete slab foundation for attenuation. Upon completion of the remedial excavation, the bottom of the excavation was approximately 6.7 meters (22 ft) below the ground surface at the deepest location (southwest corner of excavation).

100-N-52 Gasoline underground storage tank (UST) was excavated and removed in 1992.

1908-NE Outfall (SWMU#7) - The original preferred remedy for the 1908-NE Outfall was Institutional Controls (continued monitoring). A radiological survey of the Outfall seal well and samples of water and sediment were collected from the Outfall seal well in 2001 to assess potential contamination associated with the Outfall. The outfall structure was demolished by the Washington Closure Hanford D&D organization in 2012, eliminating the Institutional Control requirement.

The 1716-NE Maintenance Garage building (SWMU #8), including the building slab and associated floor drain pipelines, were removed in their entirety during the 2003 and 2004 removal action activities. Prior to the removal action all chemical products were removed from the building and either properly disposed of or transferred to another facility for use. The building debris was used as fill for the 185-N Building basement.

Code: 100-N-6	Classification: Accepted
Names: 100-N-6; 128-N-1; 128N-FS-3	Reclassification: Interim Closed Out (4/10/2013)
Type: Burn Pit	Start Date:
Status: Inactive	End Date:

Description: The waste site has been remediated and Interim Closed Out. In 1994, the site appeared to have been leveled and scraped.

Location: The site is located east of 1120-N and northwest of 124-N-10.

Related Sites/ Structures: The site is associated with 100-N-16 and 128-N-1.

Process Description: This site was used to burn miscellaneous trash and debris.

Waste Type: Misc. Trash and Debris

Waste Description: In 1992 soil samples were collected and analyzed for the 100-NR-1 Remedial Investigation/Corrective Measures Study (RI/CMS). Field screening were less than detectable for volatile organic compounds (VOC), total petroleum hydrocarbons (TPH), and polychlorinated biphenyls (PCB). Heavy metals and metal-complexed compounds did not differ from background.

Closure Info: Interim (4/10/2013): Remediation of 100-N-6, 100-N-16, 100-N-98 area 1, and 128-N-1 waste sites began on August 2, 2010, and was completed on November 28, 2011. A total of approximately 20,334 bank cubic meters (BCM) (26,596 bank cubic yards [BCY]) were excavated and staged for removal to the Environmental Restoration Disposal Facility (ERDF). Between April 16 and 19, 2012, the excavation was expanded to the west to include stained soil Area 2 of the 100-N-98 waste site. Approximately 476 BCM (623 BCY) of soil was removed from 100-N-98 Area 2 and direct loaded for disposal at ERDF. The additional remediation of the spoil pile area (SPA) and the 100-N-6, 100-N-16, 100-N-98, and 128-N-1 waste site excavation generated an additional volume of 5,446 BCM (7,123 BCY) of material for direct load out to ERDF. A total volume of 26,256 BCM (34,342 BCY) was disposed at ERDF, to complete the 100-N-6, 100-N-16, 100-N-98, and 128-N-1 waste site remediation.

The materials removed from the 100-N-6, 100-N-16, 100-N-98, and 128-N-1 waste sites consisted of abandoned wiring, transite pipe, metallic and wood debris, burnt wood, ash, tar, roofing felt, stained soil, a bucket of grout, an open glass bottle, green fibrous material, purple sandy material, a paint ball, drums containing bunker and amber oil, and miscellaneous demolition debris. Anomalous material discovered during remediation included six 208-L (55-gal) drums, small white ceramic balls used as filtering media, and soil with a strong solvent odor.

Code: 100-N-13

Classification: Accepted

Names: 100-N-13; Contaminated Soil Solid Waste Site 1

Reclassification: Interim Closed Out (5/16/2012)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The waste site has been remediated and interim Closed Out. The area contained miscellaneous construction debris. It had been posted at four corners with "Underground Radioactive Material" signs. Approximately 0.3 to 0.6 meters (1 to 2 feet) of soil had been placed on top of the site. The area contained miscellaneous construction debris. The radiological postings were removed in September 2012.

Location: The site was located in the 100 N area, about 124 meters (405 feet) northeast of the 1120-N Building. It was in the northeast quadrant of the dirt road intersection that is northeast of the 1120-N.

Process Description: In May 1993, a radiation survey identified the presence of cobalt-60 at what became the 100-N-13 waste site. The site was posted at four corners with "Underground Radioactive Material" signs, and approximately 0.3 to 0.6 meters (1 to 2 ft) of soil was placed on the top of the site. It was noted in 1994 that a photograph dated about 1963 showed a dark circular area (possibly a burn pit) in the vicinity of the 100-N-13 waste site.

Waste Type: Soil

Waste Description: A May 1993 radiation survey identified the presence of cobalt-60 at the site. A photograph from about 1963 shows a dark circular area (possibly a burn pit) in the vicinity of this site. A 1988 photo shows a crane (possibly regulated) parked in the vicinity of this site.

Closure Info: Interim (5/16/2012): Remedial action at the 100-N-13 waste site was performed between December 27, 2010, and March 7, 2011. Excavation continued until all debris and contamination associated with the waste site had been removed. The 100-N-13 waste site was excavated to a maximum depth of 4.6 meters (15 ft). Approximately 663 bank cubic meters (BCM) (867 bank cubic yards [BCY]) of contaminated soil and debris removed from the excavation and staged in the stockpile area before being loaded for disposal at the Environmental Restoration Disposal Facility (ERDF). Approximately 160 BCM (209 BCY) of soil was scraped and removed from the 100-N-13 stockpile area and disposed at ERDF between June 23 and 27, 2011.

The debris removed from the 100-N-13 waste site consisted of a small amount of metal debris. Although the radionuclide cobalt-60 is listed in the 100-N Area RDR/RAWP as a COPC for the 100-N-13 waste site, no radiologically contaminated material was detected during remediation activities. No indications of previous spills or releases were discovered during remediation of the 100-N-13 waste site.

Code: 100-N-14 **Classification:** Accepted

Names: 100-N-14; Contaminated Soil Solid Waste Site 2 **Reclassification:** Interim Closed Out (4/25/2012)

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The site has been remediated and Interim Closed Out. It had been posted at four corners with "Underground Radioactive Material" signs. Approximately 0.3 to 0.6 meters (1 to 2 feet) of soil has been placed on top of the site. The radiological postings were removed in September 2012.

Location: The site was located in the 100N Area, about 453 meters (1500 feet) east of the 1120-N Building.

Release Description: A May 1993 radiation survey identified the presence of cesium-137 at the site.

Related Sites/Structures: It is associated with 100-N-34 and 100-N-17.

Waste Type: Soil

Waste Description:

Closure Info: Interim (4/25/2012): Remedial action at the 100-N-14, 100-N-17, and 100-N-34 waste sites was performed between August 5, 2010, and January 4, 2011. Excavation continued to a depth of 10 meters (33 ft) at the lowest point, until all debris and visible contamination associated with the waste sites had been removed. The debris removed from the 100-N-14, 100-N-17, and 100-N-34 waste sites consisted of miscellaneous noncombustible debris including concrete, metal,

bricks, vitrified clay pipe, electrical wiring, and asbestos. Approximately 10,527 bank cubic meters (BCM) (13,769 bank cubic yards [BCY]) of contaminated soil and debris were removed from the 100-N-17 and 100-N-34 combined excavation and staged in staging piles to the east before being loaded for disposal at the Environmental Restoration Disposal Facility (ERDF). Approximately 905 BCM (1,184 BCY) of contaminated soil and debris were removed from the 100-N-14 waste site excavation and directly loaded into trucks for shipment and disposal at the ERDF. Excavation continued until all debris and contamination associated with the waste sites had been removed. No radiologically contaminated material was discovered during remediation activities. The excavation boundary was expanded beyond the design during remediation due to debris found beyond the excavation limits.

The radiological postings were removed in September 2012.

Code:	100-N-16	Classification:	Accepted
Names:	100-N-16; 128N-FS-2; Burn Pit 1	Reclassification	Interim Closed Out (4/10/2013)
Type:	Burn Pit	Start Date:	
Status:	Inactive	End Date:	
Description:	The waste site has been remediated and Interim Closed Out. The site had been a 18 meters (20 yards) by 18 meters (20 yards) semi-cleared circular area. Ash was evident on the surface and the area was covered with glass, wire, coil, pipe, tin cans, metal, and other burned debris.		
Location:	The site was located east of 1120-N, northwest of 124-N-10.		
Related Sites/Structures:	Other burn pits (128-N-1, 100-N-6, and 100-N-17) are located near this site and were used for similar purposes.		
Process Description:	Nonhazardous waste (paper, wood, trash) generated at 100-N were burned here.		
Waste Type:	Misc. Trash and Debris		
Waste Description:	Nonhazardous waste (paper, wood, trash) generated at 100-N were burned here. In 1992 soil samples were collected and analyzed for the 100-NR-1 Remedial Investigation/Corrective Measures Study (RI/CMS). Field screening samples were less than detectable for volatile organic compounds (VOC) and total petroleum hydrocarbons (TPH). Heavy metals and metal-complexed compounds did not differ from background. The site tested positive for polychlorinated biphenyls (PCBs).		
Closure Info:	Interim (4/10/2013): Remediation of 100-N-6, 100-N-16, 100-N-98 area 1, and 128-N-1 waste sites began on August 2, 2010, and was completed on November 28, 2011. A total of approximately 20,334 bank cubic meters (BCM) (26,596 bank cubic yards [BCY]) were excavated and staged for removal to the Environmental Restoration Disposal Facility (ERDF). Between April 16 and 19, 2012, the excavation was expanded to the west to include stained soil Area 2 of the 100-N-98 waste site. Approximately 476 BCM (623 BCY) of soil was removed from 100-N-98 Area 2 and direct loaded for disposal at ERDF. The additional remediation of the spoil pile area (SPA) and the 100-N-6, 100-N-16, 100-N-98, and 128-N-1 waste site excavation generated an additional volume of 5,446 BCM (7,123 BCY) of material for direct load out to ERDF. A total volume of 26,256 BCM (34,342 BCY) was disposed at ERDF, to complete the 100-N-6, 100-N-16, 100-N-98, and 128-N-1 waste site remediation.		

The materials removed from the 100-N-6, 100-N-16, 100-N-98, and 128-N-1 waste sites consisted of abandoned wiring, transite pipe, metallic and wood debris, burnt wood, ash, tar, roofing felt, stained soil, a bucket of grout, an open glass bottle, green fibrous material, purple sandy material, a paint ball, drums containing bunker and amber oil, and miscellaneous

demolition debris. Anomalous material discovered during remediation included six 208-L (55-gal) drums, small white ceramic balls used as filtering media, and soil with a strong solvent odor.

Code: 100-N-17 **Classification:** Accepted
Names: 100-N-17; 128N-FS-1; Burn Pit 2 **Reclassification** Interim Closed Out (4/25/2012)
Type: Burn Pit **Start Date:**
Status: Inactive **End Date:**

Description: The site has been remediated and Interim Closed Out. It was covered with gravel, cobbles and dead tumbleweeds. Much of the site had been backfilled with miscellaneous material.

Location: The 100-N-17 waste site is located outside the 100-N industrial area approximately 803 meters (2,635 ft) east of the 105-N Reactor Building, and co-located with 100-N-34.

Related Sites/ Structures: The site is associated with 100-N-34 Dump Site.

Process Description: Combustible materials such as vegetation, office wastes, wood, trash, tools, hardware, and possibly paints and solvents have been burned at this site.

Waste Type: Misc. Trash and Debris

Waste Description: Nonhazardous waste (paper, wood, trash) generated at 100-N were burned here. Other combustible materials such as vegetation, office wastes, tools, hardware, and possibly paints and solvents have been burned at this site. In 1992 soil samples were collected and analyzed for the 100-NR-1 Remedial Investigation/Corrective Measures Study (RI/CMS). Field screening samples were less than detectable for volatile organic compound (VOC), total petroleum hydrocarbons (TPH), and polychlorinated biphenyls (PCB). Heavy metals and metal-complexed compounds did not differ from background.

Closure Info: Interim (4/25/2012): Remedial action at the 100-N-14, 100-N-17, and 100-N-34 waste sites was performed between August 5, 2010, and January 4, 2011. Excavation continued to a depth of 10 meters (33 ft) at the lowest point, until all debris and visible contamination associated with the waste sites had been removed. The debris removed from the 100-N-14, 100-N-17, and 100-N-34 waste sites consisted of miscellaneous noncombustible debris including concrete, metal, bricks, vitrified clay pipe, electrical wiring, and asbestos. Approximately 10,527 bank cubic meters (BCM) (13,769 bank cubic yards [BCY]) of contaminated soil and debris were removed from the 100-N-17 and 100-N-34 combined excavation and staged in staging piles to the east before being loaded for disposal at the Environmental Restoration Disposal Facility (ERDF). Approximately 905 BCM (1,184 BCY) of contaminated soil and debris were removed from the 100-N-14 waste site excavation and directly loaded into trucks for shipment and disposal at the ERDF. Excavation continued until all debris and contamination associated with the waste sites had been removed. No radiologically contaminated material was discovered during remediation activities. The excavation boundary was expanded beyond the design during remediation due to debris found beyond the excavation limits.

The radiological postings were removed in September 2012.

Code: 100-N-18 **Classification:** Accepted
Names: 100-N-18; Hanford Generating Plant Burn Pit; HGP Burn Pit **Reclassification** Interim Closed Out (8/2/2012)
Type: Burn Pit **Start Date:**

Status: Inactive **End Date:** 1/1/1989

Description: The waste site has been remediated and Interim Closed Out. It was an area that contained evidence of burning including charred wood and burned metal. Vegetation at the site was sparse with a few rabbitbrush plants.

Location: The Hanford Generating Plant (HGP) Burn Pit was located approximately 123 meters (404 feet) southwest of the Bonneville Power Administration (BPA) Hanford Substation.

Process Description: Combustible materials such as vegetation, office wastes, wood, trash, tools, hardware, and possibly paints and solvents have been burned at this site.

Waste Type: Misc. Trash and Debris

Waste Description: Soil samples were collected from disturbed areas of the pit and analyzed using field screening methods. Samples tested contained less than detectable concentrations of volatile organic compounds (VOCs), heavy metals, total petroleum hydrocarbons (TPH), and polychlorinated biphenyls (PCBs).

Closure Info: Interim (8/2/2012): Several samples were collected to support waste characterization and designation at the 100-N-18 waste site prior to remediation. Three test pits were excavated within the boundary of the waste site and one soil sample was collected from each test pit at approximately 0.9 to 1.5 meters (3 to 5 ft) bgs. The initial remedial action at the 100-N-18 waste site was performed on September 27, 2011. The excavation continued to an approximate depth of 1.5 meters (5 ft) below ground surface (bgs) resulting in approximately 195 bank cubic meters (BCM) (255 bank cubic yards [BCY]) of soil, metal, ash, and wood debris being removed for disposal at the Environmental Restoration Disposal Facility. Debris similar to that previously removed remained just outside of the 100-N-18 Waste Information Data System boundary. Therefore, remediation resumed on November 15, 2011, resulting in an additional 870 BCM (1,138 BCY) of soil and debris being removed for disposal. The final depth of the excavation extended to 1.5 meters (5 ft) bgs at the deepest point. No anomalous material or radiologically contaminated material was discovered during remediation activities.

Code: 100-N-22 **Classification:** Accepted

Names: 100-N-22; 1705-N Septic Tank and Cesspool; 1706-NA Sanitary Sewer System **Reclassification:** Interim Closed Out (11/1/2012)

Type: Septic Tank **Start Date:**

Status: Inactive **End Date:**

Description: The waste site has been remediated and Interim Closed Out. The waste site consisted of two below-grade structures, a reinforced concrete septic tank and a concrete block cesspool. The two structures were connected by a 10 cm (4 in.) concrete pipe. The septic tank and cesspool were abandoned in the 1980's.

Location: The site is located north-northeast of 1714-NB.

Related Sites/Structures: This facility most likely served the 105-N, 1705-N and 1706-N Buildings.

Waste Type: Sanitary Sewage

Waste Description:

Closure Info: Interim (11/1/2012): Remediation of the 100-N-22 waste site occurred from April 12 to 18, 2012, and resulted in approximately 665 bank cubic meters (870 bank cubic yards) of soil and

debris being removed and disposed at the Environmental Restoration Disposal Facility. During remediation, it was discovered that the septic tank had previously been removed and its former location filled with dirt. The 100-N-22 waste site was excavated to a depth of approximately 4 meters (13 ft) below ground surface. The debris consisted of the concrete cesspool structure, rock, cast iron and polyvinyl chloride piping, and wiring. No anomalies were discovered during remediation. All material was direct loaded from the excavation for disposal at the Environmental Restoration Disposal Facility; therefore, no waste staging pile area was created. Additionally, there is no overburden soil stockpile associated with the 100-N-22 waste site.

Portions of the 100-N-84:1, 100-N-84:3, 100-N-84:5, and 100-N-84:8 pipeline subsites were co-located with the 100-N-22 waste site.

Code:	100-N-23	Classification:	Accepted
Names:	100-N-23; Resin Disposal Pit Liquid Waste Site 1	Reclassification	Interim Closed Out (7/18/2013)
Type:	Process Pit	Start Date:	
Status:	Inactive	End Date:	
Description:	The overflow sump has been remediated and Interim Closed Out. It was an open, rectangular, unlined pit with a 61-centimeter (24-inch) overflow pipe protruding from the north side of the pit. The pit received spent resin from the 163-N Demineralized Water Treatment Plant.		
Location:	The site was located west of the 116-N-8 Facility (163-N Mixed Waste and Hazardous Waste Container Storage Pad).		
Related Sites/ Structures:	There are two drain pipes that discharged into this site. Both pipelines are part of the 100-N-84:6 subsite. The larger drain originated from the 183-NB Clearwell and the other originated from the 163-N Demineralization Plant.		
Waste Type:	Chemicals		
Waste Description:	According to site personnel, the pit was used to dispose of resin generated in the 163-N Demineralized Water Plant. The pit later served as the clearwell overflow up until about 1990. Although it is not used for that purpose anymore, it could be used on an emergency basis. On May 5, 1980 and January 1976 the overflow sump received neutralized waste that was pumped from cleanup actions for an acid spill that occurred on the 108-N/163-N Transfer Line.		
Closure Info:	Interim (7/18/2013): Remedial action at the 100-N-23 waste site was performed from July 20 through July 29, 2011. The excavation depth was approximately 4.5 meters (14.8 ft), resulting in approximately 1,922 bank cubic meters (BCM) (2,514 bank cubic yards [BCY]) of contaminated soil, piping, and resin (also referred to as resin beads). All material was direct loaded from the excavation for disposal at the Environmental Restoration Disposal Facility (ERDF). No anomalous material was encountered during the excavation. Global Positioning Environmental Radiological Surveyor (GPERS) surveys were conducted on August 18, 2011, within the 100-N-23 waste site following the site remedial action. No elevated radioactivity was detected.		

Following analysis of the original excavation verification samples, it was determined that additional remediation was needed within the excavation because of remedial action goal (RAG) exceedances of polychlorinated biphenyls (PCBs) and polycyclic aromatic hydrocarbons (PAH). A total of four additional remediation and sampling campaigns occurred from November 9, 2012, through March 18, 2013, to a depth of approximately 5.8 m (19 ft). During this time, 1,175 BCM (1,537 BCY) of contaminated soil was direct loaded and disposed at the ERDF, for a final waste site disposal volume of 3,097 BCM (4,051 BCY).

Code: 100-N-24	Classification: Accepted
Names: 100-N-24; Hydrogen Dry Well Liquid Waste Site; Hydrogen Peroxide Drywell	Reclassification: Interim Closed Out (7/24/2013)
Type: French Drain	Start Date:
Status: Inactive	End Date:

Description: The site has been remediated and Interim Closed Out. It was a buried vertical concrete pipe with a 0.83-meter (2.75-foot) diameter steel cover. The hydrogen peroxide drywell was a non-reinforced concrete pipe of 0.83-meters (2.75-foot) above a subchamber 2.53 meters (8.3 feet) in diameter. The subchamber was set in a gravel pocket 3.35 meters (11 feet) in diameter. Welded wire fabric cells 15 centimeters (6 inches) by 10.1 centimeters (4 inches) were within the subchamber.

Location: The site was located south of the 184-N Building and west of the southwest corner of the 153-N Switch Gear Building.

Related Sites/ Structures: The hydrogen drywell was connected to a 5-centimeter (2-inch) chemical drain line which extends from the 109-N Building.

Process Description: The hydrogen peroxide drywell was constructed to receive and disperse liquids from the Hydrogen Peroxide Sump Pump to the surrounding soil below ground level.

Waste Type: Chemicals

Waste Description: The waste is the predominantly concrete and metal structure of the hydrogen peroxide drywell. The site received 50 percent hydrogen peroxide and water from the hydrogen peroxide sump under the hydrogen peroxide tank located in the 109-N Decontamination Facility. The solution used for washing down of the storage tank area.

Closure Info: Interim (7/24/2013): The 100-N-61:1 group includes co-located sites 100-N-61:1, 100-N-64:1, 100-N-24, 100-N-29, 100-N-30, 100-N-37 and 100-N-53. Remediation of the 100-N-61:1 grouping of waste sites and the 100-N-53 waste site began in February 2011 and continued through April 2012.

The 100-N-24, 100-N-29, 100-N-30, and 100-N-37 waste sites were located within the remediation boundary and removed during the 100-N-61:1 pipeline remediation. The remaining basement of the 1902-N Building, the 186-N concrete pad, concrete, valves and piping associated with the 163-N sump #2 were located within the remediation boundary and were subsequently removed. A french drain (known as french drain #2) was originally part of the 100-N-103:1 subsite. However, because of its location, the drain was removed with the 100-N-61:1 pipeline remediation. Installation of a haul road was necessary to gain access to the structures. Therefore, the 100-N-53 site and segments of the 100-N-61:1 and 100-N-64:1 pipelines that were located within the roadway boundary were removed and disposed. Verification samples were collected and 100-N-53 was backfilled as part of the haul road installation.

Petroleum-stained soil was observed throughout the excavation, but was determined to be unrelated to the waste site group. Focused verification samples were collected within the stained areas and analyzed for TPH, PAH, and PCBs. Concentrations of TPH and PAH were present in the samples above direct exposure RAGs. The oil staining is considered part of the 100-N-106, Shallow Petroleum-Only Releases waste site and no additional remediation was performed.

Global Positioning Environmental Radiological Surveyor (GPERS) surveys were conducted within the 100-N-61:1 waste site grouping excavation boundary. Radiological measurements

slightly above background were observed in the northern portion of the site. Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Soil, concrete, piping, and rebar were among the types of material removed from the excavation and disposed at the Environmental Restoration Disposal Facility (ERDF). Prior to the material being loaded out for shipment to ERDF, the material was staged in a combined staging pile area (SPA). Verification sampling of the SPA will be addressed with the 100-N-61:4 waste site closeout.

Excavation of the 100-N-61:1 group extended to an approximate maximum depth of 7 meters (23 ft) below ground surface. The 100-N-53 waste site was excavated to an approximate depth of 3 meters (9.8 ft) below ground surface. An estimated 70,000 bank cubic meters (91,557 bank cubic yards) of soil and debris was removed from the entire excavation. A portion of the soil removed from on top of the pipelines was stockpiled for use as clean backfill and is included in the total volume of material removed. Asbestos was detected in the soil at the SZ3-7 location, and hexavalent chromium was detected above a remedial action goal (RAG) at the SZ4-10 location. Therefore, additional remediation was conducted January 21 through February 5, 2013. Asbestos was detected in nonsoil debris (tar/tar paper) at four locations within the excavation. A visual inspection was conducted and the visible pieces of tar and/or tar paper were removed. The volume of additional material removed is included in the estimated volume.

Code:	100-N-25	Classification:	Accepted
Names:	100-N-25; French Drain 1 Liquid Waste Site	Reclassification	Interim Closed Out (12/11/2012)
Type:	French Drain	Start Date:	
Status:	Inactive	End Date:	
Description:	The site has been remediated and Interim Closed Out. It was a 0.9-meter (3-foot) diameter french drain with a metal cover at grade. The surrounding area was covered with gravel.		
Location:	This underground drain was located in the 100-N Area, approximately 82 meters (270 ft) south of 116-N-2 (Golf Ball).		
Process Description:	The purpose of this drain is unknown. The nearest structure was the 1105-N Administrative Office Trailer (MO919), from 1975 to 1986. 1105-N was replaced with 1129-N (MO536) in 1986. 1129-N was removed in 1993.		
Closure Info:	Interim (12/11/2012): No above or below grade pipelines were found to have led to the drain. Therefore, it was speculated that the drain was used for water runoff from the nearby office trailer roof or condensate from an air conditioning unit. Remediation of the 100-N-25 waste site was performed between March 27 and 29, 2012. The waste site was excavated to an approximate depth of 4 meters (13 ft) below ground surface resulting in approximately 333 bank cubic meters (436 bank cubic yards) of soil and debris being removed and disposed at the Environmental Restoration Disposal Facility. There was no evidence of a french drain found during remediation.		

Code:	100-N-26	Classification:	Accepted
Names:	100-N-26; French Drain 2 Liquid Waste Site	Reclassification	Interim Closed Out (9/26/2012)
Type:	French Drain	Start Date:	
Status:	Inactive	End Date:	

Description: This site has been remediated and Interim Closed Out. The vertical concrete pipe extended 5 centimeters (2 inches) above grade and was closed by a vented metal cover. The surrounding area is covered with gravel.

Location: This underground site was in the 100-N Area, north-northeast of the 13-N Building (signed as Fitters Stock N-13 L).

Release Description: Waste sites 100-N-26 and 120-N-4 were impacted by a raw water pipeline break on December 11, 2008. The regulators and tribes have requested that this release information be noted in WIDS.

During the removal of the concrete pad at the 1524-N Hazardous waste storage facility on December 11, 2008 an unknown 1.5 inch tap into the export water line was inadvertently contacted. A rupture of the 12 inch export water line and a release of at least 50,000 gallons of raw water onto the surrounding area resulted. A temporary berm was constructed around the area using excess clean 100 Area Borrow Pit material to contain the release and control potential spread of radiological contamination associated with the 1524-N pad. Once the water line was turned off the water in the area immediately percolated into the ground.

In-process and post-event surface soil radiological field survey results did not find any contamination spread as a result of the water release. A follow-up review of nearby monitoring wells as well as the standard waste site confirmatory sampling will be used to ascertain potential impacts/conditions.

Process Description: The french drain received condensate from Trapping Station No. 3 along the 10 centimeter (4 in) high pressure steam supply line to the 166-N fuel oil unloading and storage facilities, as shown on drawing H-1-29456. The steam was supplied by the 184-N Stand-by Boiler to the 166-N facilities for heating the fuel oil. Steam condensation took place in the distribution piping due to heat loss. Trapping stations were installed at defined intervals to drain condensate and thereby prevent blockage of the steam line. The steam supply was independent of the reactor operation.

Waste Type: Steam Condensate

Waste Description: The site receives yard steam condensate.

Closure Info: Interim: Remedial action at the 100-N-26 waste site was performed on October 27, 2011. The site was excavated to an approximate depth of 3.5 meters (11.5 ft), resulting in complete removal of the french drain structure with approximately 276 bank cubic meters (361 bank cubic yards) of debris, sand, soil, and rocks. All excavated material was direct loaded from the excavation and disposed of at the Environmental Restoration Disposal Facility.

Code: 100-N-28 **Classification:** Accepted

Names: 100-N-28; Resin Disposal Pit Liquid Waste Site 2 **Reclassification:** Interim Closed Out (4/3/2013)

Type: Process Pit **Start Date:**

Status: Inactive **End Date:**

Description: The site has been remediated and Interim Closed Out. It was a slight depression around a 1.5-meter (5-foot) square concrete structure that has a 0.8-meter (2.5-foot) by 0.63-centimeter (0.25-inch) rusted metal cover. The site was surrounded with four heavy steel posts connected with chain. The steel cover was posted as a confined space.

Location: This unit was located south of the 184-N Building and west of the 153-N Building.

- Related Sites/ Structures:** The Resin Disposal Pit is connected to a 7.6-centimeter (3-inch) chemical drain line which originates in the 109-N Building.
- Process Description:** The resin disposal pit was designed to receive the spent resin charge from the 109-N Ion Exchanger. The construction of the pit is such that all liquids entered the pit via the chemical drain line and the liquid entrained in the resin were filtered to the soil below the resin disposal pit. The effective volume of the resin disposal pit was 40.36 cubic meters (1,425 cubic feet) and the maximum resin charge in the ion exchanger was 3.12 cubic meters (110 cubic feet). A 7.62-centimeter (3-inch) chemical drain goes from the 109-N Decontamination Facility to the Resin Disposal Pit.
- Waste Type:** Process Effluent
- Waste Description:** The waste is the below grade structure, including the lead shield plug, piping to the pit from the 109-N Facility, and the pit structure. Site employees report that the pit was initially used for reactor decontamination waste and may have never actually been used as a resin disposal pit. Documentation (HW-69000-Volume II) states that the Resin Disposal Pit was designed to receive the resin charge from the 109-N Ion Exchanger.
- Closure Info:** Interim (4/3/2013): Remediation of the 100-N-28 waste site was performed between January 25 and March 29, 2012. The site was excavated to a depth of 8.4 meters (27.6 ft) below ground surface (bgs) and resulted in the removal of 2,577 BCM (3,371 BCY) of soil and debris. The debris consisted of soil, rock, a concrete resin pit, piping, and wiring. No resin was present in the pit and it is assumed the site was only used for liquid disposal from the 109-N Building. Soil and debris were directly loaded from the 100-N-28 excavation and disposed at the Environmental Restoration Disposal Facility (ERDF).

Remedial actions for the 100-N-61:2, 100-N-62, and 100-N-64:2 sites were performed between April 13, 2011, and March 29, 2012. Excavation depths ranged from 3 meters (9.9 ft) to 8 meters (26.2 ft) bgs. Approximately 24,113 bank cubic meters of contaminated soil and debris associated with the three pipelines was removed from the waste sites and staged in the South Staging Pile Area 1 (SSP Area 1) to the south of the excavation prior to load out for disposal at ERDF. The debris consisted of rock, concrete, piping, and wiring. Verification sampling of the SSP Area 1 will be addressed in the 100-N-61:4 verification work instruction. In addition, overburden (OB) material was stockpiled in three OB piles southwest of the waste sites. The OB piles will also be addressed in the 100-N-61:4 verification work instruction.

Multiple TPH and PAH results collected at the 100-N-61:2, 100-N-62, and 100-N-64:2 excavation exceeded soil RAGs. However, these results were concluded to be cross contamination from petroleum releases unrelated to the waste sites and will be addressed as part of the 100-N-106 (Shallow Petroleum-Only Releases at 100-N; SPOR Releases) waste site and were not used for evaluation in this RSVP.

A valve pit (OSE ID N-244) was discovered at Washington State plane coordinates N149350.37, E571230.54, with asbestos pipe wrapping. The valve pit was a 1 meter (3.3 ft) diameter manhole, with a valve and a 7.6 centimeter (3 in.) pipeline running east to west. Spatial analysis indicated that valve pit N-244 is associated with the 100-N-84:3, potable water line. The valve pit was completely removed and disposed with soil and debris from the 100-N-61:2, 100-N-62, and 100-N-64:2 excavation. No other anomalies were discovered during remediation.

Code: 100-N-29	Classification: Accepted
Names: 100-N-29; Unplanned Release on 25-Centimeter (10-Inch) Blowdown Pipeline #1	Reclassification: Interim Closed Out (7/24/2013)

Type: Unplanned Release**Start Date:****Status:** Inactive**End Date:**

Description: The unplanned release site has been remediated and Interim Closed Out. It was associated with the blowdown pipe connected to the 1300-N Emergency Dump Basin. The area surrounding it was level and graveled with no vegetation. Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Location: The release site was located near the southwest corner of the 104-N Building between valve BDV 6214 and BDV 801 on the 25-centimeter (10-inch) blowdown pipeline.

Release Description: Through process knowledge, it is known that several water leaks occurred around and adjacent to the dump basin in the early 1980's.

Related Sites/Structures: The 1300-N Emergency Dump Basin (116-N-4), 100-N Reactor, 109-N Building and the 259 centimeter (102 inch) Outfall (NPDES 009) are associated with this Unplanned Release site.

Waste Type: Water

Waste Description: An inventory table from an unnumbered document is attached to the listed reference. Contaminants in the Dump Basin liquid include average concentrations of 6.25 E+05 of H-3, 6.12 E+01 of C0-60, 5.70 E+04 of Sr-90, 2.51 E+01 of Zr-95, <5.16 E+01 of Ru-106, 2.16 E+01 of Sb-125, 5.16 E+00 of Cs-134, 9.27 E+02 of Cs-137, 1.62 E-02 of Pu-239 and 1.82 E-01 of Pu.

Closure Info: Interim (7/24/2013): The 100-N-61:1 group includes co-located sites 100-N-61:1, 100-N-64:1, 100-N-24, 100-N-29, 100-N-30, 100-N-37 and 100-N-53. Remediation of the 100-N-61:1 grouping of waste sites and the 100-N-53 waste site began in February 2011 and continued through April 2012.

The 100-N-24, 100-N-29, 100-N-30, and 100-N-37 waste sites were located within the remediation boundary and removed during the 100-N-61:1 pipeline remediation. The remaining basement of the 1902-N Building, the 186-N concrete pad, concrete, valves and piping associated with the 163-N sump #2 were located within the remediation boundary and were subsequently removed. A french drain (known as french drain #2) was originally part of the 100-N-103:1 subsite. However, because of its location, the drain was removed with the 100-N-61:1 pipeline remediation. Installation of a haul road was necessary to gain access to the structures. Therefore, the 100-N-53 site and segments of the 100-N-61:1 and 100-N-64:1 pipelines that were located within the roadway boundary were removed and disposed. Verification samples were collected and 100-N-53 was backfilled as part of the haul road installation.

Petroleum-stained soil was observed throughout the excavation, but was determined to be unrelated to the waste site group. Focused verification samples were collected within the stained areas and analyzed for TPH, PAH, and PCBs. Concentrations of TPH and PAH were present in the samples above direct exposure RAGs. The oil staining is considered part of the 100-N-106, Shallow Petroleum-Only Releases waste site and no additional remediation was performed.

Global Positioning Environmental Radiological Surveyor (GPERS) surveys were conducted within the 100-N-61:1 waste site grouping excavation boundary. Radiological measurements slightly above background were observed in the northern portion of the site. Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Soil, concrete, piping, and rebar were among the types of material removed from the excavation and disposed at the Environmental Restoration Disposal Facility (ERDF). Prior to the material

being loaded out for shipment to ERDF, the material was staged in a combined staging pile area (SPA). Verification sampling of the SPA will be addressed with the 100-N-61:4 waste site closeout.

Excavation of the 100-N-61:1 group extended to an approximate maximum depth of 7 meters (23 ft) below ground surface. The 100-N-53 waste site was excavated to an approximate depth of 3 meters (9.8 ft) below ground surface. An estimated 70,000 bank cubic meters (91,557 bank cubic yards) of soil and debris was removed from the entire excavation. A portion of the soil removed from on top of the pipelines was stockpiled for use as clean backfill and is included in the total volume of material removed. Asbestos was detected in the soil at the SZ3-7 location, and hexavalent chromium was detected above a remedial action goal (RAG) at the SZ4-10 location. Therefore, additional remediation was conducted January 21 through February 5, 2013. Asbestos was detected in nonsoil debris (tar/tar paper) at four locations within the excavation. A visual inspection was conducted and the visible pieces of tar and/or tar paper were removed. The volume of additional material removed is included in the estimated volume.

Code:	100-N-30	Classification:	Accepted
Names:	100-N-30; Unplanned Release on 10-Inch Blowdown Pipeline #2	Reclassification	Interim Closed Out (7/24/2013)
Type:	Unplanned Release	Start Date:	
Status:	Inactive	End Date:	
Description:	The unplanned release site has been remediated and Interim Closed Out. It was a level, graveled area with no vegetation. The area surrounding the dump basin was also graveled.		
Location:	The site was located just off the southwest corner of the 104-N Building at valve BDV 6214 on the 25-centimeter (10-inch) blowdown pipe line.		
Release Description:	Through process knowledge it is known that several water leaks occurred around and adjacent to the dump basin in the early 1980's.		
Related Sites/Structures:	The 1300-N Emergency Dump Basin (116-N-4), 109-N Building and the 259-centimeter (102-inch) Outfall (NPDES 009) are associated with this Unplanned Release site.		
Waste Type:	Water		
Waste Description:	Contaminants in the Dump Basin liquid include average concentrations of 6.25 E+05 of H-3, 6.12 E+01 of C0-60, 5.70 E+04 of Sr-90, 2.51 E+01 of Zr-95, 5.16 E+01 of Ru-106, 2.16 E+01 of Sb-125, 5.16 E+00 of Cs-134, 9.27 E+02 of Cs-137, 1.62 E-02 of Pu-239 and 1.82 E-01 of Pu.		
Closure Info:	Interim (7/24/2013): The 100-N-61:1 group includes co-located sites 100-N-61:1, 100-N-64:1, 100-N-24, 100-N-29, 100-N-30, 100-N-37 and 100-N-53. Remediation of the 100-N-61:1 grouping of waste sites and the 100-N-53 waste site began in February 2011 and continued through April 2012.		

The 100-N-24, 100-N-29, 100-N-30, and 100-N-37 waste sites were located within the remediation boundary and removed during the 100-N-61:1 pipeline remediation. The remaining basement of the 1902-N Building, the 186-N concrete pad, concrete, valves and piping associated with the 163-N sump #2 were located within the remediation boundary and were subsequently removed. A french drain (known as french drain #2) was originally part of the 100-N-103:1 subsite. However, because of its location, the drain was removed with the 100-N-61:1 pipeline remediation. Installation of a haul road was necessary to gain access to the structures. Therefore, the 100-N-53 site and segments of the 100-N-61:1 and 100-N-64:1 pipelines that were located within the roadway boundary were removed and disposed.

Verification samples were collected and 100-N-53 was backfilled as part of the haul road installation.

Petroleum-stained soil was observed throughout the excavation, but was determined to be unrelated to the waste site group. Focused verification samples were collected within the stained areas and analyzed for TPH, PAH, and PCBs. Concentrations of TPH and PAH were present in the samples above direct exposure RAGs. The oil staining is considered part of the 100-N-106, Shallow Petroleum-Only Releases waste site and no additional remediation was performed.

Global Positioning Environmental Radiological Surveyor (GPERS) surveys were conducted within the 100-N-61:1 waste site grouping excavation boundary. Radiological measurements slightly above background were observed in the northern portion of the site. Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Soil, concrete, piping, and rebar were among the types of material removed from the excavation and disposed at the Environmental Restoration Disposal Facility (ERDF). Prior to the material being loaded out for shipment to ERDF, the material was staged in a combined staging pile area (SPA). Verification sampling of the SPA will be addressed with the 100-N-61:4 waste site closeout.

Excavation of the 100-N-61:1 group extended to an approximate maximum depth of 7 meters (23 ft) below ground surface. The 100-N-53 waste site was excavated to an approximate depth of 3 meters (9.8 ft) below ground surface. An estimated 70,000 bank cubic meters (91,557 bank cubic yards) of soil and debris was removed from the entire excavation. A portion of the soil removed from on top of the pipelines was stockpiled for use as clean backfill and is included in the total volume of material removed. Asbestos was detected in the soil at the SZ3-7 location, and hexavalent chromium was detected above a remedial action goal (RAG) at the SZ4-10 location. Therefore, additional remediation was conducted January 21 through February 5, 2013. Asbestos was detected in nonsoil debris (tar/tar paper) at four locations within the excavation. A visual inspection was conducted and the visible pieces of tar and/or tar paper were removed. The volume of additional material removed is included in the estimated volume.

Code: 100-N-31	Classification: Accepted
Names: 100-N-31; Unplanned Release on 30-Inch Pipe Line	Reclassification: Interim Closed Out (9/6/2013)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The waste site has been remediated and Interim Closed Out. Eleven waste sites located west of the 105-N/109-N Reactor Building were remediated as a group. The eleven waste sites included 100-N-31, 100-N-32, 100-N-38, 100-N-61:3, 100-N-64:3, 100-N-68, UPR-100-N-3, UPR-100-N-7, UPR-100-N-10, UPR-100-N-12, and UPR-100-N-39. These waste sites are collectively referred to as the waste sites west of the 105-N/109-N Reactor. The remediation of these waste sites resulted in one large excavation with no demarcation of the individual sites, with the exception of the UPR-100-N-39 waste site. The eleven sites were Interim Closed out in a single document.

100-N-31 was a leak from a valve (FLV-858) transferring radioactively contaminated water from the 105-N Reactor to the 1300-N Emergency Dump Basin. The surface area had no vegetation and was covered with gravel.

- Location:** 100-N-31 and the group of eleven adjacent sites were located west of the 105-N/109-N buildings. The 100-N-31 leak was near the northwest corner of the 109-N building.
- Release Description:** Through process knowledge, it is known that several water leaks occurred around and adjacent to the dump basin in the early 1980's.
- Related Sites/ Structures:** The waste site is associated with 100-N Reactor and 1300-N Emergency Dump Basin. It was adjacent to the 100-N-32, 100-N-38, 100-N-61:3, 100-N-64:3, 100-N-68, UPR-100-N-3, UPR-100-N-7, UPR-100-N-10, UPR-100-N-12, and UPR-100-N-39, UPR-100-N-4 and UPR-100-N-8 waste sites.
- Waste Type:** Water
- Waste Description:** Through process knowledge, it is known that water was slightly chemically treated with hydrazine and morpholine which are very volatile and most likely not detectable. The water was radioactively contaminated.
- Closure Info:** Interim (9/6/2013): Eleven waste sites located west of the 105-N/109-N Reactor Building were remediated as a group. The eleven waste sites included 100-N-31, 100-N-32, 100-N-38, 100-N-61:3, 100-N-64:3, 100-N-68, UPR-100-N-3, UPR-100-N-7, UPR-100-N-10, UPR-100-N-12, and UPR-100-N-39. This group of waste sites was referred to as the waste sites west of the 105-N/109-N Reactor. The footprints of the 1909-N Waste Disposal Valve Pit, the 107-N facility and the pipe trench between 105-N and 107-N were also located within the boundary of the group.

The eleven collocated waste sites located west of the 105-N/109-N Reactor Building were remediated, either partially or completely, by the Deactivation, Decontamination, Decommissioning, and Demolition (D4) Project during the demolition and removal of the portions of the 105-N/109-N Buildings, located outside of the safe storage enclosure (SSE).

The Field Remediation (FR) Project resumed remedial action activities west of the 105-N/109-N Reactor in November 2012. Contaminated soil, structural concrete and rebar, and piping were removed from the collocated waste sites west of the 105-N/109-N Reactor and disposed at the Environmental Restoration Disposal Facility (ERDF). The remediation continued through March 2013 to an approximate maximum depth of 9.5 meters (31 ft) below surface grade. No anomalous materials were encountered during remediation. The remediation resulted in one large excavation with no demarcation of the individual sites, with the exception of the UPR-100-N-39 waste site. Some segments of the 100-N-61:3 and 100-N-64:3 pipelines were removed with remedial action at the 100-N-57, (1304-N) Emergency Dump Tank and 116-N-4, (1300-N) Emergency Dump Basin waste sites.

After the remediation, Global Positioning Environmental Radiological Surveyor (GPERS) surveys were performed in March 2013. Some beta and gamma contamination was detected above background. However, the area with the highest detected activity is associated with residual structures and soils for the 105-N/109-N SSE and is considered part of the 100-N-66, 105-N/109-N Reactor Building Complex waste site. A small area with elevated beta and gamma contamination was detected within the waste sites west of the 105-N/109-N Reactor boundary. Additional soil was removed from this area and disposed at the ERDF. An environmental radiological survey of the area using hand-held instruments verified that the contaminated soils have been removed.

The 1909-N Waste Disposal Valve Pit was removed during general facility demolition in this area by the D4 Project. Due to the proximity and general configuration of demolition and remediation activities on the west side of the reactor, closure of the facility footprint was deferred until nearby waste site remediation by the FR Project occurred. The residual contaminated soil that remained beneath the location of the former 1909-N facility was then

removed.

The 107-N basin structure was completely removed by the D4 Project. However, closure of the basin footprint was deferred to the UPR-100-N-12 waste site. Additional soil was removed from the footprint during general waste site remediation in the area. Surveys found no elevated residual radiological activity.

Several segments of the 100-N-84 pipeline subsites were partially located within the remediation boundary. All of the segments of the 100-N-84:2, 100-N-84:4, 100-N-84:5, and 100-N-84:6 pipeline subsites that were within the excavation boundary were removed and disposed at the ERDF. Reclassification of the total 100-N-84:2, 100-N-84:4, 100-N-84:5 and 100-N-84:6 pipeline subsites will be addressed in separate closure documents.

Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Code:	100-N-32	Classification:	Accepted
Names:	100-N-32; Unplanned Release on 25-Centimeter (10-Inch) Blowdown Pipeline #3	Reclassification	Interim Closed Out (9/6/2013)
Type:	Unplanned Release	Start Date:	
Status:	Inactive	End Date:	
Description:	<p>The waste site has been remediated and Interim Closed Out. The 100-N-31 waste site was located on the west side of the 105-N/109-N Reactor Buildings and adjacent to the 100-N-32, 100-N-38, 100-N-61 :3, 100-N-64:3, 100-N-68, UPR-100-N-3, UPR-100-N-7, UPR-100-N-10, UPR-100-N-12, and UPR-100-N-39 waste sites. These waste sites were collectively referred to as the waste sites west of the 105-N/109-N Reactor. The remediation of these waste sites resulted in one large excavation with no demarcation of the individual sites, with the exception of the UPR-100-N-39 waste site. The eleven sites were Interim Closed out in a single document.</p> <p>100-N-32 was a leak from a valve (BDV-800) transferring radioactively contaminated water from the 105-N Reactor to the 1300-N Emergency Dump Basin. The surface area had no vegetation and was covered with gravel.</p>		
Location:	<p>100-N-32 was located near the northeast side of the 1300-N Emergency Dump Basin at Valve #BDV-800, in the 25-centimeter (10-inch) blow down line between the steam generators and the basin.</p>		
Release Description:	<p>Through process knowledge it is known that several water leaks have occurred around and adjacent to the dump basin in the early 1980's.</p>		
Related Sites/Structures:	<p>The 1300-N Emergency Dump Basin, 109-N Building, and 100-N Reactor are associated with the site.</p>		
Process Description:	<p>The Emergency Dump Basin received contaminated liquid generated during the periodic blowdown of the steam generators located in the 109-N Building. This condensate contained low levels of radioactive contaminants.</p>		
Waste Type:	<p>Water</p>		
Waste Description:			
Closure Info:	<p>Interim (9/6/2013): Eleven waste sites located west of the 105-N/109-N Reactor Building were remediated as a group. The eleven waste sites included 100-N-31, 100-N-32, 100-N-38, 100-N-</p>		

61:3, 100-N-64:3, 100-N-68, UPR-100-N-3, UPR-100-N-7, UPR-100-N-10, UPR-100-N-12, and UPR-100-N-39. This group of waste sites was referred to as the waste sites west of the 105-N/109-N Reactor. The footprints of the 1909-N Waste Disposal Valve Pit, the 107-N facility and the pipe trench between 105-N and 107-N were also located within the boundary of the group.

The eleven collocated waste sites located west of the 105-N/109-N Reactor Building were remediated, either partially or completely, by the Deactivation, Decontamination, Decommissioning, and Demolition (D4) Project during the demolition and removal of the portions of the 105-N/109-N Buildings, located outside of the safe storage enclosure (SSE).

The Field Remediation (FR) Project resumed remedial action activities west of the 105-N/109-N Reactor in November 2012. Contaminated soil, structural concrete and rebar, and piping were removed from the collocated waste sites west of the 105-N/109-N Reactor and disposed at the Environmental Restoration Disposal Facility (ERDF). The remediation continued through March 2013 to an approximate maximum depth of 9.5 meters (31 ft) below surface grade. No anomalous materials were encountered during remediation. The remediation resulted in one large excavation with no demarcation of the individual sites, with the exception of the UPR-100-N-39 waste site. Some segments of the 100-N-61:3 and 100-N-64:3 pipelines were removed with remedial action at the 100-N-57, (1304-N) Emergency Dump Tank and 116-N-4, (1300-N) Emergency Dump Basin waste sites.

After the remediation, Global Positioning Environmental Radiological Surveyor (GPERS) surveys were performed in March 2013. Some beta and gamma contamination was detected above background. However, the area with the highest detected activity is associated with residual structures and soils for the 105-N/109-N SSE and is considered part of the 100-N-66, 105-N/109-N Reactor Building Complex waste site. A small area with elevated beta and gamma contamination was detected within the waste sites west of the 105-N/109-N Reactor boundary. Additional soil was removed from this area and disposed at the ERDF. An environmental radiological survey of the area using hand-held instruments verified that the contaminated soils have been removed.

The 1909-N Waste Disposal Valve Pit was removed during general facility demolition in this area by the D4 Project. Due to the proximity and general configuration of demolition and remediation activities on the west side of the reactor, closure of the facility footprint was deferred until nearby waste site remediation by the FR Project occurred. The residual contaminated soil that remained beneath the location of the former 1909-N facility was then removed.

The 107-N basin structure was completely removed by the D4 Project. However, closure of the basin footprint was deferred to the UPR-100-N-12 waste site. Additional soil was removed from the footprint during general waste site remediation in the area. Surveys found no elevated residual radiological activity.

Several segments of the 100-N-84 pipeline subsites were partially located within the remediation boundary. All of the segments of the 100-N-84:2, 100-N-84:4, 100-N-84:5, and 100-N-84:6 pipeline subsites that were within the excavation boundary were removed and disposed at the ERDF. Reclassification of the total 100-N-84:2, 100-N-84:4, 100-N-84:5 and 100-N-84:6 pipeline subsites will be addressed in separate closure documents.

Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Code: 100-N-33

Classification: Accepted

Names: 100-N-33; 100-N Military Installation Ash Pit **Reclassification** Interim Closed Out (8/2/2012)

Type: Coal Ash Pit **Start Date:**

Status: Inactive **End Date:**

Description: The waste site has been remediated and Interim Closed Out. It was an irregularly-shaped area, covered with dark, uniform grain-size ash, perhaps the remnants of coal burning.

Location: The site is located generally southeast of the 100-N Area and southwest of the 100-N Military Artillery Site. The site is south southeast of the 105-N Reactor Building.

Process The source of the material is unknown.

Description:

Waste Type: Ash

Waste A description of the waste is not known at this time.

Description:

Closure Info: Interim: Remediation of the two waste sites was performed between December 27, 2010, and July 19, 2011.

The 100-N-33 waste site was excavated to a depth of approximately 0.5 to 1.0 meter (1.6 to 3.3 ft) below ground surface (bgs). Remediation of the 100-N-33 waste site involved removal of approximately 221 bank cubic meters (BCM) (289 bank cubic yards [BCY]) of ash and soil, which was staged at the southern staging pile or 100-N-33 staging pile before disposal at the Environmental Restoration Disposal Facility (ERDF).

The 100-N-47 waste site was excavated to a depth of approximately 2.0 to 5.5 meters (6.6 to 18.0 ft) bgs. Remediation of the 100-N-47 waste site included excavation of the septic system, all manholes, septic tanks, the drain field, associated piping, and miscellaneous material/debris. The contents of the septic tank were treated with soda lime to raise the pH above 12.0 in order to kill any coliform bacteria, and then the septage was solidified with Waterworks silica gel. The concrete septic tank, solidified contents of the septic tank, and pipeline between the drainfield and manhole/building footprint were direct loaded to ERDF, while the soil and debris from the remainder of the 100-N-47 waste site were staged in the northern staging pile, before being loaded out to ERDF. Approximately 9,776 BCM (12,787 BCY) of soil and miscellaneous debris, including concrete, solidified sewage, and tiles, from the 100-N-47 waste site was disposed at ERDF. No overburden soil stockpiles were associated with the waste sites.

Code: 100-N-34

Classification: Accepted

Names: 100-N-34; Debris Site

Reclassification Interim Closed Out (4/25/2012)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The 100-N-34 waste site consisted of a debris dumping site that encompassed the smaller 100-N-17 burn pit waste site and adjacent 100-N-14, contaminated soil solid waste site. The site was an irregular shape with gravel/cobble (some in piles), weedy vegetation, and dead tumbleweeds (some in piles) present. Construction debris including asphalt, concrete, and metal pipe were also present.

Location: The 100-N-34 waste site is located outside the 100-N industrial area approximately 803 meters (2,635 ft) east of the 105-N Reactor Building.

Related Sites/ Structures: It is associated with burn pits 100-N-14 and 100-N-17

Process Description: This site received debris from 100-N Area construction and operation activities.

Waste Type: Misc. Trash and Debris

Waste Description:

Closure Info: Interim (4/25/2012): Remedial action at the 100-N-14, 100-N-17, and 100-N-34 waste sites was performed between August 5, 2010, and January 4, 2011. Excavation continued to a depth of 10 meters (33 ft) at the lowest point, until all debris and visible contamination associated with the waste sites had been removed. The debris removed from the 100-N-14, 100-N-17, and 100-N-34 waste sites consisted of miscellaneous noncombustible debris including concrete, metal, bricks, vitrified clay pipe, electrical wiring, and asbestos. Approximately 10,527 bank cubic meters (BCM) (13,769 bank cubic yards [BCY]) of contaminated soil and debris were removed from the 100-N-17 and 100-N-34 combined excavation and staged in staging piles to the east before being loaded for disposal at the Environmental Restoration Disposal Facility (ERDF). Approximately 905 BCM (1,184 BCY) of contaminated soil and debris were removed from the 100-N-14 waste site excavation and directly loaded into trucks for shipment and disposal at the ERDF. Excavation continued until all debris and contamination associated with the waste sites had been removed. No radiologically contaminated material was discovered during remediation activities. The excavation boundary was expanded beyond the design during remediation due to debris found beyond the excavation limits.

The radiological postings were removed in September 2012.

Code: 100-N-35	Classification: Accepted
Names: 100-N-35; Oil Releases from Hanford Generating Plant (HGP) Substation Equipment	Reclassification: Rejected (10/8/2014)
Type: Unplanned Release	Start Date: 7/12/1971
Status: Inactive	End Date:

Description: The waste site has been evaluated and reclassified to Rejected. It was reported releases of oil and hydraulic fluid from equipment located inside the Hanford Generating Plant (HGP) Substation. Two releases occurred in 1989 and were reported and documented.

A review of the 1992 RCRA Facility Assessment concluded no further cleanup action was required. In 2014, Bonneville Power Administration concurred that the waste site should be reclassified to Rejected.

Note: 100-N-35 was originally described in the WIDS database as the Hanford Generating Plant (HGP) Substation facility. The definition was later changed to address the potential for petroleum/PCB contamination in soil.

Location: The waste site is located southwest of the 100-N Reactor area.

Release Description: On June 6, 1989, oil leaked from equipment (BPA nno. 4001 MOD). The source document does not specify oil type or equipment use. On July 16, 1990, a hydraulic leak from a fitting on B-phase circuit breaker was repaired. Soil sampled near the leak at various times showed polychlorinated biphenyl (PCB) concentrations ranging from less than detectable to 7 milligrams/kilogram (7 parts per million).

Related Sites/ Structures: The site is associated with a construction dump area located outside the facility boundary known as Solid Waste Management Unit (SWMU) #11. See WIDS sites 100-N-19 and 100-N-39.

Process Description: The Hanford Generating Plant (185-N Building) produced electricity for the Bonneville Power Association (BPA) grid using steam from the N-Reactor operation. The Hanford Substation distributed the power into the grid. The Hanford Generating Plant operated continuously from April 1966 to December 1986. As of August 2000, the BPA Hanford Substation was still active. A telephone inquiry to MSA in June 2013 indicated the substation is still active.

Waste Type: Oil

Waste Description: There is asbestos insulated piping in the basement of the mechanical room. Mineral oil containing polychlorinated biphenyls and solvents is used during routine equipment maintenance.

Code: 100-N-36

Classification: Accepted

Names: 100-N-36; 107-N Oil Stained Pad

Reclassification: Interim Closed Out (4/8/2013)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The waste site was remediated along with the demolition of the 107-N Recirculation Facility and has been Interim Closed Out. It consisted of a cement air compressor pad adjacent to the 107-N Building. The concrete pad and adjacent asphalt were stained with lubrication oil from the maintenance of air compressor. The area was covered with asphalt except for the concrete pad that measured approximately 1.2 meters (4 feet) by 2.4 meters (8 feet).

Location: The air compressor pad is adjacent to the 107-N Building.

Related Sites/ Structures: The 107-N Building is associated with the site.

Waste Type: Oil

Waste Description: The waste consists of non-hazardous petroleum product (oil) from air compressor leaks.

Closure Info: Interim (4/8/2013): The 100-N-36 waste site was within the layback for removal of the 107-N Building. The removal of the 107-N facility basement in 2012 resulted in the incidental remediation of the 100-N-36 waste site. Soils were excavated to a depth of approximately 7 meters (23 ft) below ground surface at the site location. No stained soil was observed. No verification samples were collected.

Code: 100-N-37

Classification: Accepted

Names: 100-N-37; 109-N Asbestos Release

Reclassification: Interim Closed Out (7/24/2013)

Type: Unplanned Release

Start Date: 1/16/1995

Status: Inactive

End Date:

Description: The waste site has been remediated and Interim Closed Out. It was an area where asbestos insulation lagging from an above ground steam line was affected by a rain event. A large chunk of lagging fell to the ground.

Location: 100-N-37 was located south of 109-N.

Release Description: Heavy rainfall caused a subsidence next to a caisson directly beneath the west elbow of the steam transfer line at the 109-N Building. The same rainfall saturated asbestos insulation lagging on the steam transfer piping causing a large chunk (estimated to weigh 180 to 320 kilograms [400 to 500 pounds]) to fall off. It was apparent that some of the asbestos insulation washed down the subsidence next to the caisson. Surface asbestos material was cleaned up and disposed of. The subsidence was backfilled with clean fill material. No action was taken to remove asbestos contamination from the subsidence.

Related Sites/ Structures: The 109-N Building was associated with the site.

Waste Type: Asbestos (non-friable)

Waste Description:

Closure Info: Interim (7/24/2013): The 100-N-61:1 group includes co-located sites 100-N-61:1, 100-N-64:1, 100-N-24, 100-N-29, 100-N-30, 100-N-37 and 100-N-53. Remediation of the 100-N-61:1 grouping of waste sites and the 100-N-53 waste site began in February 2011 and continued through April 2012.

The 100-N-24, 100-N-29, 100-N-30, and 100-N-37 waste sites were located within the remediation boundary and removed during the 100-N-61:1 pipeline remediation. The remaining basement of the 1902-N Building, the 186-N concrete pad, concrete, valves and piping associated with the 163-N sump #2 were located within the remediation boundary and were subsequently removed. A french drain (known as french drain #2) was originally part of the 100-N-103:1 subsite. However, because of its location, the drain was removed with the 100-N-61:1 pipeline remediation. Installation of a haul road was necessary to gain access to the structures. Therefore, the 100-N-53 site and segments of the 100-N-61:1 and 100-N-64:1 pipelines that were located within the roadway boundary were removed and disposed. Verification samples were collected and 100-N-53 was backfilled as part of the haul road installation.

Petroleum-stained soil was observed throughout the excavation, but was determined to be unrelated to the waste site group. Focused verification samples were collected within the stained areas and analyzed for TPH, PAH, and PCBs. Concentrations of TPH and PAH were present in the samples above direct exposure RAGs. The oil staining is considered part of the 100-N-106, Shallow Petroleum-Only Releases waste site and no additional remediation was performed.

Global Positioning Environmental Radiological Surveyor (GPERS) surveys were conducted within the 100-N-61:1 waste site grouping excavation boundary. Radiological measurements slightly above background were observed in the northern portion of the site. Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Soil, concrete, piping, and rebar were among the types of material removed from the excavation and disposed at the Environmental Restoration Disposal Facility (ERDF). Prior to the material being loaded out for shipment to ERDF, the material was staged in a combined staging pile area (SPA). Verification sampling of the SPA will be addressed with the 100-N-61:4 waste site closeout.

Excavation of the 100-N-61:1 group extended to an approximate maximum depth of 7 meters (23 ft) below ground surface. The 100-N-53 waste site was excavated to an approximate depth of 3 meters (9.8 ft) below ground surface. An estimated 70,000 bank cubic meters (91,557 bank cubic yards) of soil and debris was removed from the entire excavation. A portion of the soil

removed from on top of the pipelines was stockpiled for use as clean backfill and is included in the total volume of material removed. Asbestos was detected in the soil at the SZ3-7 location, and hexavalent chromium was detected above a remedial action goal (RAG) at the SZ4-10 location. Therefore, additional remediation was conducted January 21 through February 5, 2013. Asbestos was detected in nonsoil debris (tar/tar paper) at four locations within the excavation. A visual inspection was conducted and the visible pieces of tar and/or tar paper were removed. The volume of additional material removed is included in the estimated volume.

Code:	100-N-38	Classification:	Accepted
Names:	100-N-38; Unplanned Release at 1300-N	Reclassification	Interim Closed Out (9/6/2013)
Type:	Unplanned Release	Start Date:	
Status:	Inactive	End Date:	
Description:	<p>The waste site has been remediated and Interim Closed Out. The 100-N-31 waste site was located on the west side of the 105-N/109-N Reactor Buildings and adjacent to the 100-N-32, 100-N-38, 100-N-61 :3, 100-N-64:3, 100-N-68, UPR-100-N-3, UPR-100-N-7, UPR-100-N-10, UPR-100-N-12, and UPR-100-N-39 waste sites. These waste sites are collectively referred to as the waste sites west of the 105-N/109-N Reactor. The remediation of these waste sites resulted in one large excavation with no demarcation of the individual sites, with the exception of the UPR-100-N-39 waste site. The eleven sites were Interim Closed out in a single document.</p> <p>100-N-38 was a leak of radioactively contaminated water from the 105-N Reactor to the 1300-N Emergency Dump Basin. The area surrounding the basin had no vegetation and was covered with gravel.</p>		
Location:	100-N-38 was located near the northeast corner of the 1300-N Emergency Dump Basin where the 25-centimeter (10-inch) blow down line connected to the basin.		
Related Sites/ Structures:	The 1300-N Emergency Dump Basin (116-N-4) and the 109-N Building are associated with the site.		
Process Description:	From 1973 to 1987, the Emergency Dump Basin received contaminated liquid generated during the periodic blowdown of the steam generators located in the 109-N Building. This condensate contained low levels of radioactive contaminants.		
Waste Type:	Water		
Waste Description:	Through process knowledge it is known that several water leaks have occurred around and adjacent to the dump basin in the early 1980's. Contaminants in the Dump Basin liquid include average concentrations of 6.25 E+05 of H-3, 6.12 E+01 of C0-60, 5.70 E+04 of Sr-90, 2.51 E+01 of Zr-95, 5.16 E+01 of Ru-106, 2.16 E+01 of Sb-125, 5.16 E+00 of Cs-134, 9.27 E+02 of Cs-137, 1.62 E-02 of Pu-239 and 1.82 E-01 of Pu.		
Closure Info:	Interim (9/6/2013): Eleven waste sites located west of the 105-N/109-N Reactor Building were remediated as a group. The eleven waste sites included 100-N-31, 100-N-32, 100-N-38, 100-N-61:3, 100-N-64:3, 100-N-68, UPR-100-N-3, UPR-100-N-7, UPR-100-N-10, UPR-100-N-12, and UPR-100-N-39. This group of waste sites was referred to as the waste sites west of the 105-N/109-N Reactor. The footprints of the 1909-N Waste Disposal Valve Pit, the 107-N facility and the pipe trench between 105-N and 107-N were also located within the boundary of the group. <p>The eleven collocated waste sites located west of the 105-N/109-N Reactor Building were remediated, either partially or completely, by the Deactivation, Decontamination, Decommissioning, and Demolition (D4) Project during the demolition and removal of the portions of the 105-N/109-N Buildings, located outside of the safe storage enclosure (SSE).</p>		

The Field Remediation (FR) Project resumed remedial action activities west of the 105-N/109-N Reactor in November 2012. Contaminated soil, structural concrete and rebar, and piping were removed from the collocated waste sites west of the 105-N/109-N Reactor and disposed at the Environmental Restoration Disposal Facility (ERDF). The remediation continued through March 2013 to an approximate maximum depth of 9.5 meters (31 ft) below surface grade. No anomalous materials were encountered during remediation. The remediation resulted in one large excavation with no demarcation of the individual sites, with the exception of the UPR-100-N-39 waste site. Some segments of the 100-N-61:3 and 100-N-64:3 pipelines were removed with remedial action at the 100-N-57, (1304-N) Emergency Dump Tank and 116-N-4, (1300-N) Emergency Dump Basin waste sites.

After the remediation, Global Positioning Environmental Radiological Surveyor (GPERS) surveys were performed in March 2013. Some beta and gamma contamination was detected above background. However, the area with the highest detected activity is associated with residual structures and soils for the 105-N/109-N SSE and is considered part of the 100-N-66, 105-N/109-N Reactor Building Complex waste site. A small area with elevated beta and gamma contamination was detected within the waste sites west of the 105-N/109-N Reactor boundary. Additional soil was removed from this area and disposed at the ERDF. An environmental radiological survey of the area using hand-held instruments verified that the contaminated soils have been removed.

The 1909-N Waste Disposal Valve Pit was removed during general facility demolition in this area by the D4 Project. Due to the proximity and general configuration of demolition and remediation activities on the west side of the reactor, closure of the facility footprint was deferred until nearby waste site remediation by the FR Project occurred. The residual contaminated soil that remained beneath the location of the former 1909-N facility was then removed.

The 107-N basin structure was completely removed by the D4 Project. However, closure of the basin footprint was deferred to the UPR-100-N-12 waste site. Additional soil was removed from the footprint during general waste site remediation in the area. Surveys found no elevated residual radiological activity.

Several segments of the 100-N-84 pipeline subsites were partially located within the remediation boundary. All of the segments of the 100-N-84:2, 100-N-84:4, 100-N-84:5, and 100-N-84:6 pipeline subsites that were within the excavation boundary were removed and disposed at the ERDF. Reclassification of the total 100-N-84:2, 100-N-84:4, 100-N-84:5 and 100-N-84:6 pipeline subsites will be addressed in separate closure documents.

Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Code: 100-N-41	Classification: Accepted
Names: 100-N-41; 1701-NE Gate House Septic Tank; HGP SWMU #9	Reclassification: Interim Closed Out (6/15/2004)
Type: Septic Tank	Start Date: 1/1/1965
Status: Inactive	End Date: 1/1/1986
Description: The site has been remediated and Interim Closed Out. The site consisted of a septic system that received effluent from the demolished 1701-NE Gate House. The site was not located in a known contaminated area. (the 100-N-3 garage french drain, the 100-N-41 septic tank and the 100-N-45 septic tank make up Solid Waste Management Unit (SWMU) #9). The septic tank	

was an open bottomed cesspool constructed of concrete blocks and gravel. The septic structure was demolished in place and backfilled with clean soil.

Location: The site was located just off the north corner of the 1701-NE Gate House within the HGP portion of the 100N area.

Process Description: The former HGP consisted of two 430-megawatt turbine generators that operated from 1966 until 1986 using steam from the adjacent 100-N production reactor for generation of electricity. The generators were located in the 185-N Building. The site was an ancillary or support facility to the former HGP.

Waste Type: Sanitary Sewage

Waste Description:

Closure Info: Interim (6/15/2004): The 100-N Reactor provided fuel rods to the plutonium production process at Hanford, but also operated two 430 megawatt turbine generators for the generation of electricity. The Washington Public Supply System, later named Energy Northwest, was responsible for the Hanford Generating Plant located at 100-N Reactor. The Cleanup Verification Package (HGP-CVP-SWMUs 5, 6, 7, 8, 9, & 10) for the Hanford Generating Plant Solid Waste Management units was prepared by Energy Northwest in 2004. Some remedial actions at HGP began in 1992. Other characterization and remediation was completed in 2004. Remedial action activity descriptions include:

100-N-1 Settling Pond (SWMU#6) - Remediation activities conducted in 2001 removed approximately 0.9 meters (3 ft) of soil and settled solids material from the 100-N-1 Settling Pond (SWMU #6). The excavated material was disposed of at the Environmental Restoration Disposal Facility (ERDF).

100-N-3 Maintenance Garage French Drain, 100-N-41 Gate House Septic Tank and 100-N-45 Office Building Septic Tank make up SWMU #9. Remediation was determined not to be necessary for the 100-N-3 site and the 100-N-41 and 100-N-45 septic sites. The below grade structures of the drain and septic sites were demolished in place and backfilled with soil in 2004.

100-N-4 Tile Field (SWMU#5) - Confirmatory sampling activities and data evaluation determined that remediation was not necessary for the 100-N-4 Tile Field.

100-N-5 Bone Yard (SWMU #10) - Remediation and removal activities for the 100-N-5 Bone Yard (SWMU #10) were primarily conducted in 2001 with the removal of the miscellaneous equipment, metal scrap, and general debris. The limited number of areas with sand blast media, ion exchange resin-like media and areas with soil staining and/or distressed vegetation were remediated in 2003 and 2004. The sand blast, ion exchange resin, and contaminated soil wastes were disposed of at the RABANCO landfill facility in Roosevelt, Washington.

The 100-N-46 Diesel under ground storage tank (UST) was excavated and removed in 2001. Soil contaminated with diesel was also excavated from the UST excavation. Contaminated soil was spread over the demolished 1703-N Office Building concrete slab foundation for attenuation. Upon completion of the remedial excavation, the bottom of the excavation was approximately 6.7 meters (22 ft) below the ground surface at the deepest location (southwest corner of excavation).

100-N-52 Gasoline underground storage tank (UST) was excavated and removed in 1992.

1908-NE Outfall (SWMU#7) - The original preferred remedy for the 1908-NE Outfall was Institutional Controls (continued monitoring). A radiological survey of the Outfall seal well and samples of water and sediment were collected from the Outfall seal well in 2001 to assess

potential contamination associated with the Outfall. The outfall structure was demolished by the Washington Closure Hanford D&D organization in 2012, eliminating the Institutional Control requirement.

The 1716-NE Maintenance Garage building (SWMU #8), including the building slab and associated floor drain pipelines, were removed in their entirety during the 2003 and 2004 removal action activities. Prior to the removal action all chemical products were removed from the building and either properly disposed of or transferred to another facility for use. The building debris was used as fill for the 185-N Building basement.

Code:	100-N-45	Classification:	Accepted
Names:	100-N-45; 1703-N Office Building Septic Tank; HGP SWMU #9	Reclassification	Interim Closed Out (6/15/2004)
Type:	Septic Tank	Start Date:	1/1/1965
Status:	Inactive	End Date:	1/1/1987

Description: The site has been remediated and Interim Closed Out. The waste site was septic tank, in a 3.0 meter (10 foot) by 3.0 meter (10 foot) square area of gravel with a 15-centimeter (6-inch) capped pipe at the center. (The 100-N-3 garage french drain, the 100-N-41 septic tank and the 100-N-45 septic tank make up Solid Waste Management Unit [SWMU] #9.) The septic tank was an open bottomed cesspool constructed of concrete blocks and gravel. The septic structure was demolished in place and backfilled with clean soil.

Location: The septic tank was located approximately 20 meters (66 feet) north of the 1703-N building, inside the Hanford Generating Plant (HGP) facility fence.

Related Sites/ Structures: 185-N Building, 1703-N Building

Process Description: The site received effluent from the 1703-N office building.

Waste Type: Sanitary Sewage

Waste Description:

Closure Info: Interim (6/15/2004): The 100-N Reactor provided fuel rods to the plutonium production process at Hanford, but also operated two 430 megawatt turbine generators for the generation of electricity. The Washington Public Supply System, later named Energy Northwest, was responsible for the Hanford Generating Plant located at 100-N Reactor. The Cleanup Verification Package (HGP-CVP-SWMUs 5, 6, 7, 8, 9, & 10) for the Hanford Generating Plant Solid Waste Management units was prepared by Energy Northwest in 2004. Some remedial actions at HGP began in 1992. Other characterization and remediation was completed in 2004. Remedial action activity descriptions include:

100-N-1 Settling Pond (SWMU#6) - Remediation activities conducted in 2001 removed approximately 0.9 meters (3 ft) of soil and settled solids material from the 100-N-1 Settling Pond (SWMU #6). The excavated material was disposed of at the Environmental Restoration Disposal Facility (ERDF).

100-N-3 Maintenance Garage French Drain, 100-N-41 Gate House Septic Tank and 100-N-45 Office Building Septic Tank make up SWMU #9. Remediation was determined not to be necessary for the 100-N-3 site and the 100-N-41 and 100-N-45 septic sites. The below grade structures of the drain and septic sites were demolished in place and backfilled with soil in 2004.

100-N-4 Tile Field (SWMU#5) - Confirmatory sampling activities and data evaluation determined that remediation was not necessary for the 100-N-4 Tile Field.

100-N-5 Bone Yard (SWMU #10) - Remediation and removal activities for the 100-N-5 Bone Yard (SWMU #10) were primarily conducted in 2001 with the removal of the miscellaneous equipment, metal scrap, and general debris. The limited number of areas with sand blast media, ion exchange resin-like media and areas with soil staining and/or distressed vegetation were remediated in 2003 and 2004. The sand blast, ion exchange resin, and contaminated soil wastes were disposed of at the RABANCO landfill facility in Roosevelt, Washington.

The 100-N-46 Diesel under ground storage tank (UST) was excavated and removed in 2001. Soil contaminated with diesel was also excavated from the UST excavation. Contaminated soil was spread over the demolished 1703-N Office Building concrete slab foundation for attenuation. Upon completion of the remedial excavation, the bottom of the excavation was approximately 6.7 meters (22 ft) below the ground surface at the deepest location (southwest corner of excavation).

100-N-52 Gasoline underground storage tank (UST) was excavated and removed in 1992.

1908-NE Outfall (SWMU#7) - The original preferred remedy for the 1908-NE Outfall was Institutional Controls (continued monitoring). A radiological survey of the Outfall seal well and samples of water and sediment were collected from the Outfall seal well in 2001 to assess potential contamination associated with the Outfall. The outfall structure was demolished by the Washington Closure Hanford D&D organization in 2012, eliminating the Institutional Control requirement.

The 1716-NE Maintenance Garage building (SWMU #8), including the building slab and associated floor drain pipelines, were removed in their entirety during the 2003 and 2004 removal action activities. Prior to the removal action all chemical products were removed from the building and either properly disposed of or transferred to another facility for use. The building debris was used as fill for the 185-N Building basement.

Code:	100-N-46	Classification:	Accepted
Names:	100-N-46; HGP Diesel Oil Storage Tank	Reclassification	Interim Closed Out (6/15/2004)
Type:	Storage Tank	Start Date:	1/1/1965
Status:	Inactive	End Date:	
Description:	The site has been remediated and Interim Closed Out. The site consisted of a 5,300 liter (20,000 gallon) underground storage tank (UST) for diesel fuel. The 100-N-46 Diesel UST was excavated and removed in 2001.		
Location:	The UST was on the east side of the 185-N Building.		
Release Description:	There was no indication of a release from this tank.		
Related Sites/ Structures:	185-N Building		
Process Description:	The tank supplied diesel fuel to a backup generator and backup heating boiler. The former HGP consisted of two 430-megawatt turbine generators that operated from 1966 until 1986 using steam from the adjacent 100-N production reactor for generation of electricity. The generators were located in the 185-N Building. The site was an ancillary or support facility to the former		

HGP.

Waste Type: Storage Tank

Waste Description: The site consisted of an underground storage tank containing an unknown amount of diesel fuel.

Closure Info: Interim (6/15/2004): The 100-N Reactor provided fuel rods to the plutonium production process at Hanford, but also operated two 430 megawatt turbine generators for the generation of electricity. The Washington Public Supply System, later named Energy Northwest, was responsible for the Hanford Generating Plant located at 100-N Reactor. The Cleanup Verification Package (HGP-CVP-SWMUs 5, 6, 7, 8, 9, & 10) for the Hanford Generating Plant Solid Waste Management units was prepared by Energy Northwest in 2004. Some remedial actions at HGP began in 1992. Other characterization and remediation was completed in 2004. Remedial action activity descriptions include:

100-N-1 Settling Pond (SWMU#6) - Remediation activities conducted in 2001 removed approximately 0.9 meters (3 ft) of soil and settled solids material from the 100-N-1 Settling Pond (SWMU #6). The excavated material was disposed of at the Environmental Restoration Disposal Facility (ERDF).

100-N-3 Maintenance Garage French Drain, 100-N-41 Gate House Septic Tank and 100-N-45 Office Building Septic Tank make up SWMU #9. Remediation was determined not to be necessary for the 100-N-3 site and the 100-N-41 and 100-N-45 septic sites. The below grade structures of the drain and septic sites were demolished in place and backfilled with soil in 2004.

100-N-4 Tile Field (SWMU#5) - Confirmatory sampling activities and data evaluation determined that remediation was not necessary for the 100-N-4 Tile Field.

100-N-5 Bone Yard (SWMU #10) - Remediation and removal activities for the 100-N-5 Bone Yard (SWMU #10) were primarily conducted in 2001 with the removal of the miscellaneous equipment, metal scrap, and general debris. The limited number of areas with sand blast media, ion exchange resin-like media and areas with soil staining and/or distressed vegetation were remediated in 2003 and 2004. The sand blast, ion exchange resin, and contaminated soil wastes were disposed of at the RABANCO landfill facility in Roosevelt, Washington.

The 100-N-46 Diesel under ground storage tank (UST) was excavated and removed in 2001. Soil contaminated with diesel was also excavated from the UST excavation. Contaminated soil was spread over the demolished 1703-N Office Building concrete slab foundation for attenuation. Upon completion of the remedial excavation, the bottom of the excavation was approximately 6.7 meters (22 ft) below the ground surface at the deepest location (southwest corner of excavation).

100-N-52 Gasoline underground storage tank (UST) was excavated and removed in 1992.

1908-NE Outfall (SWMU#7) - The original preferred remedy for the 1908-NE Outfall was Institutional Controls (continued monitoring). A radiological survey of the Outfall seal well and samples of water and sediment were collected from the Outfall seal well in 2001 to assess potential contamination associated with the Outfall. The outfall structure was demolished by the Washington Closure Hanford D&D organization in 2012, eliminating the Institutional Control requirement.

The 1716-NE Maintenance Garage building (SWMU #8), including the building slab and associated floor drain pipelines, were removed in their entirety during the 2003 and 2004 removal action activities. Prior to the removal action all chemical products were removed from the building and either properly disposed of or transferred to another facility for use. The

building debris was used as fill for the 185-N Building basement.

Code: 100-N-47 **Classification:** Accepted
Names: 100-N-47; Military Artillery Site Solid Waste Site **Reclassification** Interim Closed Out (8/2/2012)
Type: Military Compound **Start Date:** 1/1/1951
Status: Inactive **End Date:** 1/1/1958

Description: The waste site has been remediated and Interim Closed Out. It was a military installation that included ten separate intact concrete foundations and remnants of at least one other. A number of concrete walkways and remnants of walkways were associated with the foundations. There were remnants of asphalt roadways, parking areas, and piles of broken-up asphalt. There is a 0.6-meter (2-foot) diameter sewer manhole and three 1.2 by 1.2 meter (4 by 4 foot) square concrete hatch covers. These are likely to be underground sanitary waste holding areas.

Scattered debris included wood poles, metal cables, wire, metal pipe, glass, paint cans, fire hose, metal cans, broken up concrete, concrete blocks, wood pallets, bricks, and transite siding. A number of 0.3 meter (1 foot) diameter wooden poles were standing, and some had been cut off at ground level. On one concrete foundation were thirty one bee hive boxes left from a Pacific Northwest Laboratory (PNL) experiment conducted from 1981 to 1984.

Location: The site is located generally southeast of the 100-N-Area. Entrance to the site is from the 100-N access road to the west, approximately 1 kilometer (0.6 mile) before the 100-N Reactor entrance. A row of 6 locust trees is on the south side of the dirt road leading to the site.

Related Sites/ Structures: 100-N-91

Closure Info: Interim: Remediation of the two waste sites was performed between December 27, 2010, and July 19, 2011.

The 100-N-33 waste site was excavated to a depth of approximately 0.5 to 1.0 meter (1.6 to 3.3 ft) below ground surface (bgs). Remediation of the 100-N-33 waste site involved removal of approximately 221 bank cubic meters (BCM) (289 bank cubic yards [BCY]) of ash and soil, which was staged at the southern staging pile or 100-N-33 staging pile before disposal at the Environmental Restoration Disposal Facility (ERDF).

The 100-N-47 waste site was excavated to a depth of approximately 2.0 to 5.5 meters (6.6 to 18.0 ft) bgs. Remediation of the 100-N-47 waste site included excavation of the septic system, all manholes, septic tanks, the drain field, associated piping, and miscellaneous material/debris. The contents of the septic tank were treated with soda lime to raise the pH above 12.0 in order to kill any coliform bacteria, and then the septage was solidified with Waterworks silica gel. The concrete septic tank, solidified contents of the septic tank, and pipeline between the drainfield and manhole/building footprint were direct loaded to ERDF, while the soil and debris from the remainder of the 100-N-47 waste site were staged in the northern staging pile, before being loaded out to ERDF. Approximately 9,776 BCM (12,787 BCY) of soil and miscellaneous debris, including concrete, solidified sewage, and tiles, from the 100-N-47 waste site was disposed at ERDF. No overburden soil stockpiles were associated with the waste sites.

Code: 100-N-50 **Classification:** Accepted
Names: 100-N-50; HGP SWMU #4; Turbine Oil Cleaning System; Turbine Oil Filter Unit **Reclassification** Interim Closed Out (6/15/2004)

Type: Single-Shell Tank **Start Date:** 1/1/1966

Status: Inactive **End Date:** 1/1/1986

Description: The site has been remediated and Interim Closed Out. It consisted of two filtration units located in the basement of the 185-N building. The basement floor of the building is approximately 15.2 meters (50 ft) below surrounding grade. The turbines were supported on large concrete support pedestals extending from the basement floor and foundation to approximately surface grade. The reinforced concrete basement floor and foundation is approximately 1.5 meters (5 ft) thick. The entire 185-N Building aboveground structure was demolished during the 2003 and 2004 activities. The debris from demolition of the building as well as from demolition of other HGP structures was used as fill for the 185-N Building basement.

Location: The 100-N-50 Turbine Oil Filter Unit (SWMU #4) was located in the 185-N Building basement along the northeast and southeast walls.

Release Description: No releases are known to have occurred from this unit.

Related Sites/ Structures: 100-N-51 HGP Building Oil Storage Area

Process Description: The former HGP consisted of two 430-megawatt turbine generators that operated from 1966 until 1986 using steam from the adjacent 100-N production reactor for generation of electricity. The generators were located in the 185-N Building.

The filter unit was used to clean turbine oil located in the basement of the Hanford Generating Plant (HGP) Building. It was surrounded by a concrete berm.

Waste Type: Oil

Waste Description: The filters were periodically changed, but no information was available on the location of their disposal. This unit likely managed impurities in the turbine oil such as metals.

Closure Info: Interim: The Hanford Generating Plant (HGP) solid waste management unit (SWMU) removal actions included in this CVP began in 2001 and were completed in 2004. The majority of the removal action activities were completed in 2003 and 2004. The remediation and report were done by Energy Northwest.

The entire 185-N Building aboveground structure was demolished during the 2003 and 2004 activities. The debris from demolition of the building as well as from demolition of other HGP structures was used as fill for the 185-N Building basement. The debris was placed into the building basement from the bottom (15.2 meters [50 ft] below ground surface) to within 7.6 meters (25 ft) of the ground surface. The remaining void spaces among the debris fill were filled using a cement grout controlled density fill. The remaining below grade portion of the basement was backfilled with clean soil. The reinforced concrete turbine pedestals that extend from the basement floor to approximately the ground surface were left in place. Based on agreement with the Washington State Department of Ecology, the portions of the turbine pedestals at the ground surface were covered with 0.9 meter (3 ft) of soil consistent with requirements for other 100 Area facilities. The Removal Action Workplan (DOE-RL 1999) specified removal of structures to a minimum of 0.3 meter (1 ft) below the surrounding grade and other 100 Area action memorandums generally require that a structure be demolished to a minimum of 0.9 meters (3 ft) below the surrounding grade. However, in the case of the turbine pedestals, because of their mass and the amount of steel reinforcement, demolition was deemed impractical. The 0.9 meters (3 ft) of cover for the pedestals was placed to blend in with, and to gently slope with, the surrounding grade.

The 185-N Building is not a SWMU. However, SWMUs #2, 3, and 4 are located within the

building. To provide a complete description of the removal action activities for SWMUs #2, 3, and 4, a summary description of the removal action activities conducted for the 185-N Building is below.

UPR-100-N-37 Transformer Yard (SWMU #1): Eight of the nine transformers located in the transformer yard were removed prior to the Action Memorandum (EPA 1999). The ninth, smaller, operating transformer, was drained of oil and scrapped during the most recent 2003 and 2004 activities. The oil and transformer were disposed of based on historical data indicating that the transformer oil did not contain PCBs. During removal action activities conducted in 2001, minor areas of soil contaminated with oil were excavated from around each transformer pad and properly disposed. During the more recent 2003 and 2004 activities, the concrete pads were demolished, excavated and the concrete rubble used as fill for the demolished 185-N Building basement.

100-N-51 Oil Storage Area (SWMU #2): All stored oil and waste containers were previously removed from the oil storage area and properly disposed of or appropriately used. Miscellaneous concrete stained areas including the sump were cleaned. Cleaning of concrete surfaces included the use of concrete scabbling and water and detergents during the 2001 activities. The 100-N-51 Oil Storage Area (SWMU #2) was located at the bottom of the 185-N Building basement. It has been covered and filled with building debris, a cement grout controlled density fill, and borrow soil.

185-N Building Drains and Sumps (SWMU #3): The 185-N Building basement drains and sumps were emptied and cleaned during the 2001 removal action activities. Cleaning activities involved removal and proper disposal of sludges and liquids. Following removal of the sludges and liquids, the sump concrete and metal surfaces were hand cleaned, pressure washed, and scabbled as needed. During the recent 2003 and 2004 activities three of the sumps contained water. The water was characterized, removed from the sump, and properly disposed. All of the miscellaneous drains were filled with a cement grout controlled density fill during the 2003 and 2004 activities. The sumps were filled with borrow soil and capped with a minimum of 15 cm (6 in.) of cement grout during the 2003 and 2004 activities. Also, the sumps and drains have been covered with building debris fill, cement grout controlled density fill, and borrow soil.

100-N-50 Turbine Oil Filter Unit (SWMU #4): During the 2001 removal action activities, the two steel tank oil filtration units including the internal metal oil filtration screens were drained and cleaned. Residual oil from the units was removed and properly disposed. In addition, the two concrete sumps associated with the filter units were cleaned. Stained concrete was removed from the sumps through chipping and scabbling. These units were located at the bottom of the 185-N Building basement and have been filled and covered with the cement grout controlled density fill.

Code: 100-N-51	Classification: Accepted
Names: 100-N-51; 100-N-51A; HGP Building Oil Storage Area; HGP SWMU #2	Reclassification: Interim Closed Out (6/15/2004)
Type: Storage	Start Date: 1/1/1966
Status: Inactive	End Date:
Description: The site has been remediated and Interim Closed Out. The site consisted of a cinder block room in the basement of 185-N. It was equipped with a fire sprinkler system, steel grate floor, and shelving along the walls. Drums and smaller containers of product (petroleum, oil, and lubricants) were stored on the floor and shelving. A blind concrete sump (no outlet) was located below the grated floor. The basement floor of the building is approximately 15.2 meters (50 ft) below surrounding grade. The turbines were supported on large concrete support pedestals	

extending from the basement floor and foundation to approximately surface grade. The reinforced concrete basement floor and foundation is approximately 1.5 meters (5 ft) thick. The entire 185-N Building aboveground structure was demolished during the 2003 and 2004 activities. The debris from demolition of the building as well as from demolition of other HGP structures was used as fill for the 185-N Building basement.

- Location:** Located in the 185-N Building basement along the northwest basement wall.
- Release Description:** No releases are known to have occurred. Stains on the grate and sump floor indicated that minor leaks from containers had been contained within the unit.
- Related Sites/ Structures:** 100-N-51B HGP Building Floor Drains and Sump, and 100-N-50 Turbine Oil filter Unit, 185-N Building
- Process Description:** The former HGP consisted of two 430-megawatt turbine generators that operated from 1966 until 1986 using steam from the adjacent 100-N production reactor for generation of electricity. The generators were formerly located in the 185-N Building.
- Waste Type:** Oil
- Waste Description:** Used oil and rags from maintenance activities are stored in drums inside the room.
- Closure Info:** Interim: The Hanford Generating Plant (HGP) solid waste management unit (SWMU) removal actions included in this CVP began in 2001 and were completed in 2004. The majority of the removal action activities were completed in 2003 and 2004. The remediation and report were done by Energy Northwest.

The entire 185-N Building aboveground structure was demolished during the 2003 and 2004 activities. The debris from demolition of the building as well as from demolition of other HGP structures was used as fill for the 185-N Building basement. The debris was placed into the building basement from the bottom (15.2 meters [50 ft] below ground surface) to within 7.6 meters (25 ft) of the ground surface. The remaining void spaces among the debris fill were filled using a cement grout controlled density fill. The remaining below grade portion of the basement was backfilled with clean soil. The reinforced concrete turbine pedestals that extend from the basement floor to approximately the ground surface were left in place. Based on agreement with the Washington State Department of Ecology, the portions of the turbine pedestals at the ground surface were covered with 0.9 meter (3 ft) of soil consistent with requirements for other 100 Area facilities. The Removal Action Workplan (DOE-RL 1999) specified removal of structures to a minimum of 0.3 meter (1 ft) below the surrounding grade and other 100 Area action memorandums generally require that a structure be demolished to a minimum of 0.9 meters (3 ft) below the surrounding grade. However, in the case of the turbine pedestals, because of their mass and the amount of steel reinforcement, demolition was deemed impractical. The 0.9 meters (3 ft) of cover for the pedestals was placed to blend in with, and to gently slope with, the surrounding grade.

The 185-N Building is not a SWMU. However, SWMUs #2, 3, and 4 are located within the building. To provide a complete description of the removal action activities for SWMUs #2, 3, and 4, a summary description of the removal action activities conducted for the 185-N Building is below.

UPR-100-N-37 Transformer Yard (SWMU #1): Eight of the nine transformers located in the transformer yard were removed prior to the Action Memorandum (EPA 1999). The ninth, smaller, operating transformer, was drained of oil and scrapped during the most recent 2003 and 2004 activities. The oil and transformer were disposed of based on historical data indicating that the transformer oil did not contain PCBs. During removal action activities conducted in 2001, minor areas of soil contaminated with oil were excavated from around each transformer pad and properly disposed. During the more recent 2003 and 2004 activities, the concrete pads

were demolished, excavated and the concrete rubble used as fill for the demolished 185-N Building basement.

100-N-51 Oil Storage Area (SWMU #2): All stored oil and waste containers were previously removed from the oil storage area and properly disposed of or appropriately used. Miscellaneous concrete stained areas including the sump were cleaned. Cleaning of concrete surfaces included the use of concrete scabbling and water and detergents during the 2001 activities. The 100-N-51 Oil Storage Area (SWMU #2) was located at the bottom of the 185-N Building basement. It has been covered and filled with building debris, a cement grout controlled density fill, and borrow soil.

185-N Building Drains and Sumps (SWMU #3): The 185-N Building basement drains and sumps were emptied and cleaned during the 2001 removal action activities. Cleaning activities involved removal and proper disposal of sludges and liquids. Following removal of the sludges and liquids, the sump concrete and metal surfaces were hand cleaned, pressure washed, and scabbled as needed. During the recent 2003 and 2004 activities three of the sumps contained water. The water was characterized, removed from the sump, and properly disposed. All of the miscellaneous drains were filled with a cement grout controlled density fill during the 2003 and 2004 activities. The sumps were filled with borrow soil and capped with a minimum of 15 cm (6 in.) of cement grout during the 2003 and 2004 activities. Also, the sumps and drains have been covered with building debris fill, cement grout controlled density fill, and borrow soil.

100-N-50 Turbine Oil Filter Unit (SWMU #4): During the 2001 removal action activities, the two steel tank oil filtration units including the internal metal oil filtration screens were drained and cleaned. Residual oil from the units was removed and properly disposed. In addition, the two concrete sumps associated with the filter units were cleaned. Stained concrete was removed from the sumps through chipping and scabbling. These units were located at the bottom of the 185-N Building basement and have been filled and covered with the cement grout controlled density fill.

Code:	100-N-51B	Classification:	Accepted
Names:	100-N-51B; HGP Building Floor Drains and Sumps; HGP SWMU #3	Reclassification	Interim Closed Out (6/15/2004)
Type:	Sump	Start Date:	
Status:	Inactive	End Date:	
Description:	The site has been remediated and Interim Closed Out. It consisted of multiple drains and sumps located in the basement of the 185-N building. The basement floor of the building is approximately 15.2 meters (50 ft) below surrounding grade. The turbines were supported on large concrete support pedestals extending from the basement floor and foundation to approximately surface grade. The reinforced concrete basement floor and foundation is approximately 1.5 meters (5 ft) thick. The entire 185-N Building aboveground structure was demolished during the 2003 and 2004 activities. The debris from demolition of the building as well as from demolition of other HGP structures was used as fill for the 185-N Building basement.		
Location:	Located in the 185-N Building basement along the northwest basement wall.		
Related Sites/ Structures:	100-N-51A, HGP Building Oil Storage Area, 100-N-50 Turbine Oil filter Unit, and the 185-N Building		
Process Description:	The former HGP consisted of two 430-megawatt turbine generators that operated from 1966 until 1986 using steam from the adjacent 100-N production reactor for generation of electricity. The generators were formerly located in the 185-N Building.		

Closure Info: Interim: The Hanford Generating Plant (HGP) solid waste management unit (SWMU) removal actions included in this CVP began in 2001 and were completed in 2004. The majority of the removal action activities were completed in 2003 and 2004. The remediation and report were done by Energy Northwest.

The entire 185-N Building aboveground structure was demolished during the 2003 and 2004 activities. The debris from demolition of the building as well as from demolition of other HGP structures was used as fill for the 185-N Building basement. The debris was placed into the building basement from the bottom (15.2 meters [50 ft] below ground surface) to within 7.6 meters (25 ft) of the ground surface. The remaining void spaces among the debris fill were filled using a cement grout controlled density fill. The remaining below grade portion of the basement was backfilled with clean soil. The reinforced concrete turbine pedestals that extend from the basement floor to approximately the ground surface were left in place. Based on agreement with the Washington State Department of Ecology, the portions of the turbine pedestals at the ground surface were covered with 0.9 meter (3 ft) of soil consistent with requirements for other 100 Area facilities. The Removal Action Workplan (DOE-RL 1999) specified removal of structures to a minimum of 0.3 meter (1 ft) below the surrounding grade and other 100 Area action memorandums generally require that a structure be demolished to a minimum of 0.9 meters (3 ft) below the surrounding grade. However, in the case of the turbine pedestals, because of their mass and the amount of steel reinforcement, demolition was deemed impractical. The 0.9 meters (3 ft) of cover for the pedestals was placed to blend in with, and to gently slope with, the surrounding grade.

The 185-N Building is not a SWMU. However, SWMUs #2, 3, and 4 are located within the building. To provide a complete description of the removal action activities for SWMUs #2, 3, and 4, a summary description of the removal action activities conducted for the 185-N Building is below.

UPR-100-N-37 Transformer Yard (SWMU #1): Eight of the nine transformers located in the transformer yard were removed prior to the Action Memorandum (EPA 1999). The ninth, smaller, operating transformer, was drained of oil and scrapped during the most recent 2003 and 2004 activities. The oil and transformer were disposed of based on historical data indicating that the transformer oil did not contain PCBs. During removal action activities conducted in 2001, minor areas of soil contaminated with oil were excavated from around each transformer pad and properly disposed. During the more recent 2003 and 2004 activities, the concrete pads were demolished, excavated and the concrete rubble used as fill for the demolished 185-N Building basement.

100-N-51 Oil Storage Area (SWMU #2): All stored oil and waste containers were previously removed from the oil storage area and properly disposed of or appropriately used. Miscellaneous concrete stained areas including the sump were cleaned. Cleaning of concrete surfaces included the use of concrete scabbling and water and detergents during the 2001 activities. The 100-N-51 Oil Storage Area (SWMU #2) was located at the bottom of the 185-N Building basement. It has been covered and filled with building debris, a cement grout controlled density fill, and borrow soil.

185-N Building Drains and Sumps (SWMU #3): The 185-N Building basement drains and sumps were emptied and cleaned during the 2001 removal action activities. Cleaning activities involved removal and proper disposal of sludges and liquids. Following removal of the sludges and liquids, the sump concrete and metal surfaces were hand cleaned, pressure washed, and scabbled as needed. During the recent 2003 and 2004 activities three of the sumps contained water. The water was characterized, removed from the sump, and properly disposed. All of the miscellaneous drains were filled with a cement grout controlled density fill during the 2003 and 2004 activities. The sumps were filled with borrow soil and capped with a minimum of 15 cm

(6 in.) of cement grout during the 2003 and 2004 activities. Also, the sumps and drains have been covered with building debris fill, cement grout controlled density fill, and borrow soil.

100-N-50 Turbine Oil Filter Unit (SWMU #4): During the 2001 removal action activities, the two steel tank oil filtration units including the internal metal oil filtration screens were drained and cleaned. Residual oil from the units was removed and properly disposed. In addition, the two concrete sumps associated with the filter units were cleaned. Stained concrete was removed from the sumps through chipping and scabbling. These units were located at the bottom of the 185-N Building basement and have been filled and covered with the cement grout controlled density fill.

Code: 100-N-52	Classification: Accepted
Names: 100-N-52; HGP Gasoline Storage Tank	Reclassification: Interim Closed Out (6/15/2004)
Type: Storage Tank	Start Date: 1/1/1976
Status: Inactive	End Date:

Description: The site has been remediated and Interim Closed Out. The waste site was an underground gasoline storage tank. The UST was excavated and removed in 1992.

Location: The gasoline filling area was located outside the northern corner of 100-N-78, Hanford Generating Plant (HGP) maintenance garage.

Release Description: No releases have been documented.

Process Description: The former HGP consisted of two 430-megawatt turbine generators that operated from 1966 until 1986 using steam from the adjacent 100-N production reactor for generation of electricity. The generators were located in the 185-N Building. The site was an ancillary or support facility to the former HGP. The 100-N-52 (UST) site was located immediately north of the former 1716-NE Maintenance Garage and was used for the storage and dispensing of gasoline for maintenance vehicles.

Waste Type: Storage Tank

Waste Description:

Closure Info: Interim (6/15/2004): The 100-N Reactor provided fuel rods to the plutonium production process at Hanford, but also operated two 430 megawatt turbine generators for the generation of electricity. The Washington Public Supply System, later named Energy Northwest, was responsible for the Hanford Generating Plant located at 100-N Reactor. The Cleanup Verification Package (HGP-CVP-SWMUs 5, 6, 7, 8, 9, & 10) for the Hanford Generating Plant Solid Waste Management units was prepared by Energy Northwest in 2004. Some remedial actions at HGP began in 1992. Other characterization and remediation was completed in 2004. Remedial action activity descriptions include:

100-N-1 Settling Pond (SWMU#6) - Remediation activities conducted in 2001 removed approximately 0.9 meters (3 ft) of soil and settled solids material from the 100-N-1 Settling Pond (SWMU #6). The excavated material was disposed of at the Environmental Restoration Disposal Facility (ERDF).

100-N-3 Maintenance Garage French Drain, 100-N-41 Gate House Septic Tank and 100-N-45 Office Building Septic Tank make up SWMU #9. Remediation was determined not to be necessary for the 100-N-3 site and the 100-N-41 and 100-N-45 septic sites. The below grade structures of the drain and septic sites were demolished in place and backfilled with soil in 2004.

100-N-4 Tile Field (SWMU#5) - Confirmatory sampling activities and data evaluation determined that remediation was not necessary for the 100-N-4 Tile Field.

100-N-5 Bone Yard (SWMU #10) - Remediation and removal activities for the 100-N-5 Bone Yard (SWMU #10) were primarily conducted in 2001 with the removal of the miscellaneous equipment, metal scrap, and general debris. The limited number of areas with sand blast media, ion exchange resin-like media and areas with soil staining and/or distressed vegetation were remediated in 2003 and 2004. The sand blast, ion exchange resin, and contaminated soil wastes were disposed of at the RABANCO landfill facility in Roosevelt, Washington.

The 100-N-46 Diesel under ground storage tank (UST) was excavated and removed in 2001. Soil contaminated with diesel was also excavated from the UST excavation. Contaminated soil was spread over the demolished 1703-N Office Building concrete slab foundation for attenuation. Upon completion of the remedial excavation, the bottom of the excavation was approximately 6.7 meters (22 ft) below the ground surface at the deepest location (southwest corner of excavation).

100-N-52 Gasoline underground storage tank (UST) was excavated and removed in 1992.

1908-NE Outfall (SWMU#7) - The original preferred remedy for the 1908-NE Outfall was Institutional Controls (continued monitoring). A radiological survey of the Outfall seal well and samples of water and sediment were collected from the Outfall seal well in 2001 to assess potential contamination associated with the Outfall. The outfall structure was demolished by the Washington Closure Hanford D&D organization in 2012, eliminating the Institutional Control requirement.

The 1716-NE Maintenance Garage building (SWMU #8), including the building slab and associated floor drain pipelines, were removed in their entirety during the 2003 and 2004 removal action activities. Prior to the removal action all chemical products were removed from the building and either properly disposed of or transferred to another facility for use. The building debris was used as fill for the 185-N Building basement.

Code:	100-N-53	Classification:	Accepted
Names:	100-N-53; 181-N Building Waste Oil Tank	Reclassification	Interim Closed Out (7/24/2013)
Type:	Storage Tank	Start Date:	
Status:	Inactive	End Date:	
Description:	The site has been remediated and Interim Closed Out. It was an empty above-ground waste oil tank. The tank was 1.1 meters (3.5 feet) in diameter and 1.2 meters (4.1 feet) high.		
Location:	The site was located in the 100-N Area, 18 meters (60 feet) east of the 181-N Pumphouse, south of the river road.		
Related Sites/ Structures:	The 181-N Building is associated with this site.		
Process Description:	The site received waste oil from diesel powered emergency pumps in the 181-N Building.		
Waste Type:	Oil		
Waste Description:	The tank has been removed.		

Closure Info: Interim (7/24/2013): The 100-N-61:1 group includes co-located sites 100-N-61:1, 100-N-64:1, 100-N-24, 100-N-29, 100-N-30, 100-N-37 and 100-N-53. Remediation of the 100-N-61:1 grouping of waste sites and the 100-N-53 waste site began in February 2011 and continued through April 2012.

The 100-N-24, 100-N-29, 100-N-30, and 100-N-37 waste sites were located within the remediation boundary and removed during the 100-N-61:1 pipeline remediation. The remaining basement of the 1902-N Building, the 186-N concrete pad, concrete, valves and piping associated with the 163-N sump #2 were located within the remediation boundary and were subsequently removed. A french drain (known as french drain #2) was originally part of the 100-N-103:1 subsite. However, because of its location, the drain was removed with the 100-N-61:1 pipeline remediation. Installation of a haul road was necessary to gain access to the structures. Therefore, the 100-N-53 site and segments of the 100-N-61:1 and 100-N-64:1 pipelines that were located within the roadway boundary were removed and disposed. Verification samples were collected and 100-N-53 was backfilled as part of the haul road installation.

Petroleum-stained soil was observed throughout the excavation, but was determined to be unrelated to the waste site group. Focused verification samples were collected within the stained areas and analyzed for TPH, PAH, and PCBs. Concentrations of TPH and PAH were present in the samples above direct exposure RAGs. The oil staining is considered part of the 100-N-106, Shallow Petroleum-Only Releases waste site and no additional remediation was performed.

Global Positioning Environmental Radiological Surveyor (GPERS) surveys were conducted within the 100-N-61:1 waste site grouping excavation boundary. Radiological measurements slightly above background were observed in the northern portion of the site. Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Soil, concrete, piping, and rebar were among the types of material removed from the excavation and disposed at the Environmental Restoration Disposal Facility (ERDF). Prior to the material being loaded out for shipment to ERDF, the material was staged in a combined staging pile area (SPA). Verification sampling of the SPA will be addressed with the 100-N-61:4 waste site closeout.

Excavation of the 100-N-61:1 group extended to an approximate maximum depth of 7 meters (23 ft) below ground surface. The 100-N-53 waste site was excavated to an approximate depth of 3 meters (9.8 ft) below ground surface. An estimated 70,000 bank cubic meters (91,557 bank cubic yards) of soil and debris was removed from the entire excavation. A portion of the soil removed from on top of the pipelines was stockpiled for use as clean backfill and is included in the total volume of material removed. Asbestos was detected in the soil at the SZ3-7 location, and hexavalent chromium was detected above a remedial action goal (RAG) at the SZ4-10 location. Therefore, additional remediation was conducted January 21 through February 5, 2013. Asbestos was detected in nonsoil debris (tar/tar paper) at four locations within the excavation. A visual inspection was conducted and the visible pieces of tar and/or tar paper were removed. The volume of additional material removed is included in the estimated volume.

Code: 100-N-54	Classification: Accepted
Names: 100-N-54; 151-N Building Drywell; Miscellaneous Stream #727	Reclassification: Interim Closed Out (6/26/2014)
Type: French Drain	Start Date: 1/1/1964

Status: Inactive**End Date:** 1/1/1997**Description:** The site has been remediated and Interim Closed Out. It was a french drain, made of 1.2 meter (4 foot) inner diameter and 1.65 meter (5 foot 5 inch) outer diameter concrete pipe, with a steel cover.

The 151-N building was demolished and completely removed in December 2005, including incidental removal of the 100-N-54 drywell. Following demolition activities, excavation boundaries were surveyed and the site was temporarily backfilled.

Location: The site was located in the 100-N Area, just off the south wall of the 151-N Building. It was approximately 130 meters (430 ft) southeast of the 109-N Building.**Related Sites/ Structures:** This site drains a sink in the 151-N Building, which is the Area Electrical Switchgear Building. It is 215 square meters (2,310 square feet), and takes 230 kilovolts down to 13.8 kilovolts.**Waste Type:** Water**Waste Description:** The site received waste water from the service sink located inside the 151-N building.**Closure Info:** Interim (6/26/2014): Remedial action at the 100-N-54 waste site was conducted on November 4, 2013. The excavation extended to approximately 2 meters (6.6 ft) below ground surface (bgs) resulting in approximately 80 bank cubic meters (BCM) (105 bank cubic yards [BCY]) of soil and debris (transite conduit, concrete, and electrical wire) being removed for disposal at the Environmental Restoration Disposal Facility (ERDF). Additional remediation was conducted on March 4 and 5, 2014, due to several (PAH) and semivolatile organic compounds (SVOCs) exceeding direct exposure remedial action goals (RAGs). An additional 346 BCM (453 BCY) of soil was removed from the excavation. The final remediation depth was approximately 3 meters (9.8 ft) bgs, and a total of 426 BCM (558 BCY) of soil and debris was removed and disposed at the ERDF. All material was direct loaded from the waste site. No waste staging pile area was created.**Code:** 100-N-55**Classification:** Accepted**Names:** 100-N-55; 153-N Building Drywell; Miscellaneous Stream #728**Reclassification:** Interim Closed Out (11/5/2012)**Type:** French Drain**Start Date:****Status:** Inactive**End Date:** 1/1/1997**Description:** The site has been remediated and Interim Closed Out. It was a french drain with a 1.2-meter (4-foot) steel cover. Four yellow steel posts surrounded the drain that was located in a gravel road.**Location:** The site was located in the 100-N Area, just off the northeast corner of the 153-N Building (Washington State Plane coordinates E 571293.6, N 149367.5).**Related Sites/ Structures:** The 153-N Building is associated with this waste site. French drain 100-N-55 was located within the remediation footprint of UPR-100-N-36.**Process Description:** The drywell received steam condensate from a condensate pump and drainage from a service sink in the 153-N Building. The 153-N Building was the switchgear building containing an electrical transformer/substation that reduced 13.8 kilovolt current down to 4160 volts.**Waste Type:** Steam Condensate**Waste Description:** The site receives steam condensate from a condensate pump and drainage from a service sink inside the 153-N Building.

Closure Info: Interim (11/5/2012): Demolition of the 153-N Building was completed in October 2006. The entire facility including the foundation and underground piping was removed to 1.5 meters (5 ft) outside of the building footprint. The site was backfilled and graded to match surrounding terrain. The adjacent 100-N-55 drywell was left intact during demolition operations with minimal disturbance.

The 100-N-55 waste site was remediated incidental to remediation of the co-located waste site, UPR-100-N-36. Remedial action at the UPR-100-N-36 waste site occurred between May 23 and November 11, 2011. This remediation resulted in complete removal of the 100-N-55 drywell structure, its contents and the underlying soil to a depth approximately 4.5 meters below the original ground surface. The 100-N-55 waste site was removed prior to confirmatory sampling or other determination of need for remediation. The removal (remediation) of the 100-N-55 waste site is therefore considered incidental to remediation of UPR-100-N-36.

Code:	100-N-57	Classification:	Accepted
Names:	100-N-57; 1304-N Emergency Dump Tank	Reclassification	Interim Closed Out (3/20/2013)
Type:	Catch Tank	Start Date:	1/1/1970
Status:	Inactive	End Date:	1/1/1988

Description: The waste site has been remediated and Interim Closed Out. The 1304-N was a 500,000 gallon, above-ground storage tank with a dome-shaped top.

Location: The site was located in the 100-N Area, between the 105-N Building and the Columbia River and between the 1908-N Sealwell and the 107-N Building.

Release Description: Four unplanned releases of N-Reactor primary coolant water have occurred from the 1304-N EDT caused by leaking valves associated with the tank and one tank overflow.

Related Sites/Structures: The 105-N Building, 1325-N Crib, and 102 Inch Outfall Discharge are related to this site. The site is associated with UPR-100-N-30.

Process Description: The 1304-N Emergency Dump Tank was a 4.9E+06-liter (1.3E+06-gallon) steel, above-ground storage tank. The tank is constructed of steel and insulated with asbestos and fiberglass under aluminum sheeting. It replaced the 1300-N Emergency Dump Basin as the storage facility used for emergency blowdown of thermally hot pressurized reactor primary coolant water. The tank maintained a constant volume of 2.6E+06 liters (6.8E+05 gallons) of unheated water for quenching the hot water to prevent it from flashing to steam. Because a small flow of primary coolant was maintained to the 1304-N Emergency Dump Tank to keep interconnecting piping in a thermally warm condition, the quench water normally contained a small inventory of radioactive materials.

The primary objective of the 1304-N Decontamination Project was to reduce the dose rate contribution of the Emergency Dump Tank (EDT) by at least 90% in accordance with the Hanford Federal Facility Agreement and Consent Order (Tri-Party Agreement) Milestone N-16-12F. A secondary objective was to demonstrate the effectiveness of decontamination and paint-removal chemicals manufactured by Corpex and distributed by MELE Associates, the licensed applicator.

Waste Type: Misc. Trash and Debris

Waste Description: Between March 14, 1995 and September 29, 1995 approximately 5,300 liters (1,400 gallons) of water, 230 liters (60 gallons) of sand, and 165 bags of debris were removed from the tank. The sectioned piping was left inside the tank and will be removed and disposed of during the subsequent final decontamination and demolition of the tank. Results from Ion Chromatography/Inductively Coupled Plasma analysis at the 222-S Laboratory detected levels

of lead and chromium content classified the waste as mixed.

Closure Info: Interim (2/20/2013): The above ground 1304 Emergency Dump Tank and associated piping were removed in 2004.

Remedial action at the 100-N-57, UPR-100-N-1, UPR-100-N-2, UPR-100-N-29, UPR-100-N-30, and UPR-100-N-32 waste sites was performed between February 21 and May 31, 2011. Excavation continued until all debris and contamination associated with the waste sites had been removed. Contaminated soil, concrete, pipeline segments and debris removed during excavation were staged within the South Staging Pile Area 1 (SSP Area 1) prior to shipment to the ERDF. Approximately 1,848 bank cubic meters (2,417 bank cubic yards) of contaminated soil and debris were removed from the site and disposed at the ERDF. No stained soil or anomalous material was found during the remediation activities.

The debris removed from the waste sites consisted of miscellaneous noncombustible debris and soil. Portions of the 100-N-63:2, 100-N-64, 100-N-84:2, 100-N-84:3, 100-N-84:4, and 100-N-84:5 pipeline waste sites were also removed during 100-N-57 group of waste sites remediation activities. The remaining portions of these pipeline waste sites will be remediated and separate closure documents prepared at a later date.

Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Code:	100-N-58	Classification:	Accepted
Names:	100-N-58; 120-N South Settling Pond; 1324-N South Settling Pond; South Pond	Reclassification	Closed Out (3/28/2002)
Type:	Pond	Start Date:	1/1/1977
Status:	Inactive	End Date:	1/1/1982
Description:	The site has been remediated and closed out.		
Location:	The 100-N-58 site was co-located with 120-N-1, 120-N-2 sites in the 100-N Area in the 100-NR-1 Operable Unit of the Hanford Site in southeastern Washington State. These sites are about 100 m (328 ft) southeast of the 163-N Demineralization Plant Building, and are approximately 400 m (1,312 ft) from the Columbia River.		
Related Sites/ Structures:	The 163-N Building, 183-N Building, 120-N-2 (1324-N) Surface Impoundment, and 120-N-1 (1324-NA) Percolation Pond are associated with this site.		
Process Description:	In 1977 the 120-N-1, 120-N-2, and 100-N-58 sites were initially constructed as the East Percolation Pond and North and South Settling Ponds, respectively. These unlined ponds received 163-N anion/cation regeneration effluent as well as the 183-N Filtered Water Plant filter backwash effluent. In 1982, because of pond percolation problems, the 183-N filter backwash was rerouted to an effluent disposal pond (130-N-1). During this time period the 100-N-58 site was backfilled.		
Waste Type:	Process Effluent		
Waste Description:	The 1324N South Settling Pond received regeneration wastes containing aluminum sulfate, sulfuric acid, sodium hydroxide solutions and cooling water from the 163-N Building and filter backwash water from the 183-N Building.		
Closure Info:	Interim: The site was remediated in September/October 2000. A Reclassification form was completed for 100-N-58. However for 120-N-1 and 120-N-2, Washington State Department of Ecology rejected the certification of closure from DOE. A post-closure groundwater plan must		

be submitted to Ecology and approved prior to approval of the Certification of Closure documentation.

Remedial/corrective action field activities at the 120-N-1, 120-N-2, and 100-N-58 sites were conducted in September 2000, and included the removal and disposal of miscellaneous structural debris-type items. A total of about 120 cubic meters (4,238 cu ft) of material was removed from the sites. The material consisted of about 15 cubic meters (530 cu ft) of concrete, 96 cubic meters (3,390 cu ft) of high-density polyethylene (HDPE) liner, 4 cubic meters (141.3 cu ft) of polyvinyl chloride (PVC) piping, and 0.5 cubic meters (17.7 cu ft) of steel fencing material. The material was disposed of in the inert demolition landfill in the 100-H Area. Waste designation and disposal documentation is kept in project files. The two 20.3-cm (8-in.) diameter influent pipelines were sampled and remain in place.

Closure performance standards were established by the Washington State Department of Ecology, in concurrence with the U.S. Department of Energy, Richland Operations Office. These performance standards are documented in the 100-NR-1 Treatment, Storage, and Disposal Units Corrective Measures Study/Closure Plan (CMS/CP) (DOE-RL-90-22) and the Remedial Design Report/Remedial Action Work Plan for the 100-NR-1 Treatment, Storage, and Disposal Units (RDR/RAWP) (DOE/RL-2000-16). Permit conditions were established in the Hanford Facility Dangerous Waste Permit (Ecology 1994). While sites 120-N-1, 120-N-2, and 100-N-58 are not included in a Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) record of decision (ROD) corrective action activities have been documented in CVP-2001-00021 (CVP).

The soil investigation conducted at these sites in 1992 and 1993 for the CMS/CP indicated that the site did not require soil remediation. Therefore, the selected remedial/corrective action included the removal and disposal of the miscellaneous site structures, including the 120-N-2 liner system, a small sampling shed, fencing, and other miscellaneous debris. The CMS/CP soil investigation indicated that there generally are no contaminants of concern (COCs) for these waste sites. However, because a former overflow area and the waste site influent pipelines required additional sampling (as specified by the CMS/CP), these sites were included in the Sampling and Analysis Plan for the 100-NR-1 Treatment, Storage, and Disposal Units During Remediation and Closeout (SAP) (DOE-RL-2000-07). The verification samples collected under the sampling and analysis plan were analyzed for generally the same inorganic metals and wet chemical anions listed in the CMS/CP soil investigation. The samples were also analyzed for pH. The analytical results from the additional soil sampling and the pipeline scale sampling are presented in Appendix A of the CVP. The analytical results of the soil samples are consistent with the findings of the CMS/CP: soil concentrations are at or below Hanford Site or Washington State background concentrations.

Code:	100-N-59	Classification:	Accepted
Names:	100-N-59; Radioactively Contaminated Soil Northeast of 105-NB Building	Reclassification	Interim Closed Out (1/2/2013)
Type:	Unplanned Release	Start Date:	1/1/1995
Status:	Inactive	End Date:	
Description:	The site has been remediated and Interim Closed Out. It was an area where a contaminated, underground pipeline broke. After excavating and repairing the broken pipe, the site was marked with a single Underground Radioactive Material sign. A site visit in August 2000 found that the single post with the Underground Radioactive Material sign was gone, but an Underground Radioactive Material sign was attached to the fence near the waste site.		
Location:	It was approximately 100 meters (300 ft.) northeast of the 105-NB Building, inside the double		

fence.

Release Description: In September 1995, a 15 centimeter (6 inch) diameter underground liquid waste pipeline was found to be leaking. An area approximately 0.76 meters (2.5 feet) by 1.4 meters (4.5 feet) was excavated to repair the pipe. The soil below the pipe had a beta/gamma reading of 7,000 disintegrations per minute. A direct reading on the broken pipe found 35,000 disintegrations per minute. After repairing the pipe, the excavation was backfilled with clean dirt and posted with an Underground Radioactive Material sign.

Related Sites/Structures: The site is associated with an underground waste line from the 105-N/109-N facility. (see sitecode 100-N-63:2)

Process Description: The soil was radioactively contaminated when a liquid waste line from the 109-N facility broke.

Waste Type: Soil

Waste Description: The soil was radioactively contaminated when a liquid waste line broke.

Closure Info: Interim (1/2/2013): Remedial action excavation at the 100-N-59 waste site was performed during December 2011 along with the 100-N-63:2 subsite, to a depth of approximately 1.5 meters (5 ft) below ground surface. The soil was loaded out directly for disposal at the Environmental Restoration Disposal Facility. No overburden soil stockpiles are associated with this waste site. Additional soil was removed on March 26, 2012.

Code: 100-N-60

Classification: Accepted

Names: 100-N-60; 1314-N Drywell

Reclassification: Interim Closed Out (3/28/2013)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The waste site has been remediated and Interim Closed Out. The dry well was located under the 1314-N. In 1996, the field investigation did not visually locate the french drain, but a partially buried catch tank was observed inside the 1314-N Building. It was suspected that the area surrounding the catch tank may have been referred to as the drywell. Drawing H-1-37675, Detail D, shows a 5 centimeter (2 inch) underground drain pipe to a "drywell".

Location: The french drain was located underneath the southwest corner of the 1314-N building.

Release Description: 100-N Plant Operations personnel were filling a railroad waste tank car with spent decontamination solutions at a the 1314-N Loading Station. After approximately 26,500 liters (7,000 gallons) of solution had been pumped into the 75,700-liter (20,000-gallon) waste tank car, solution began overflowing from the tank car fittings. The tank car loading pump was turned off, then solution began flowing up through the drain in the catch basin beneath the car. The catch basin filled and overflowed into the adjacent drywell which also filled and overflowed. Approximately 380 liters (100 gallons) of solution flowed out of the drywell, covering a 6 by 6-meter (20 by 20-foot) section of ground inside the Radiation Zone at the loading station. The solution that spilled out of the drywell onto the ground was contained with trenches and earthen dams, then covered with plastic to prevent contamination spread. The solution contained in the catch basin was hosed down to remove loose contamination. Inspection of the loading and vent lines on the top of the waste tank car revealed that a manual valve on the vent line was in the closed position resulting in a pressure buildup in the tank car that caused backflow through the loading line, holding tank, and catch basin. Evaluation revealed that about 280 liters (75 gallons) of solution containing a total of 0.011 curies was discharged to the ground (sub surface) through the drywell.

Related Sites/ Structures: The 1314-N Loading Station, UPR-100-N-13 and UPR-100-N-26 are associated with this waste site.

Process Description: The drywell received overflow from the catch tank. The french drain was mapped as the catch tank on some drawings.

The 1314-N Liquid Waste Loadout Station was a 9 meter (30 ft) by 18 meter (60 ft) single story, metal-frame building supported on a reinforced concrete slab foundation. It began to operate in 1972. The facility was a transfer station consisting of numerous valves, pumps, underground and overhead piping and couplings, and underground tanks. It was located approximately 100 meters (300 ft) from the Columbia River. This facility was used to loadout radioactive liquid waste from the 116-N-2 and 107-N facilities into railroad tank cars for shipment to the 200 Areas for processing and disposal. The loadout facility contained a tank car wash station with a sump to collect the wash water. The water drained into a 3,780 liters (1,000 gal) overflow tank. During the filling operation, excess liquid waste was designed to overflow through a closed piping system from the tank car to the overflow tank, which initiated pump shutdown. A 756 liters (200 gal) catch tank was installed to hold liquids that exceeded the capacity of the car wash sump.

Waste Type: Chemicals

Waste Description: The site received spent decontamination solutions from a railroad waste tank car.

Closure Info: Interim (3/28/2013): The 1314-N building was demolished in 2006. 100-N-60 and UPR-100-N-26 were located within the building footprint. UPR-100-N-13 was located near the 1314-N building, but outside the building footprint.

Remedial action for 100-N-60, UPR-100-N-13 and UPR-100-N-26 was performed between September 21 and November 14, 2011. Approximately 2,459.0 bank cubic meters (BCM) (3,216.3 bank cubic yards [BCY]) of contaminated soil and debris were removed from the 100-N-60 group of waste sites excavation and direct loaded for disposal at the Environmental Restoration Disposal Facility (ERDF). Excavation continued until all debris and contamination associated with the waste site had been removed. No anomalous material was discovered during remediation activities.

The stained soil location was evaluated for TPH and PAH with a focused sample (FS-2), but the sample results were used to support a greater effort to identify the extent of the TPH and PAH contamination in the 100-N Area and were not included in the evaluation of the 100-N-60, UPR-100-N-13, UPR-100-N-26 group of waste sites.

Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Code: 100-N-61	Classification: Accepted
Names: 100-N-61; 100-N Water Treatment and Storage Facilities Underground Pipelines	Reclassification: Interim Closed Out (9/6/2013)
Type: Process Sewer	Start Date: 1/1/1963
Status: Inactive	End Date: 1/1/1987

Description: The 100-N-61 waste site encompassed all underground water pipelines used to transport reactor cooling water between water treatment facilities and the 105-N/109-N Buildings. This included all underground pipelines between buildings and those connected to drainage facilities. It was subdivided into four subsites: 100-N-61:1 Water Treatment and Storage Facilities Underground

Pipelines South of 109-N, 100-N-61:2 Water Treatment and Storage Facilities Underground
 Pipelines East of 109-N, 100-N-61:3 Water Treatment and Storage Facilities Underground
 Pipelines West of 109-N and 100-N-61:4 Water Treatment and Storage Facilities Underground
 Pipelines South of 182-N. Each subsite was individually remediated and Interim Closed Out.
 Therefore the parent site is also Interim Closed Out.

Location: The site was located where the underground pipelines run from the 181-N River Pump House to the 163-N Water Treatment Plant, the 182-N Pump House and Storage Tanks, and to the 105-N Reactor Building. Also, any underground drainage pipelines running from the water treatment and storage facilities to the riverside outfall structures. Other underground pipelines running to the outfall structures are included in other waste sites and are therefore excluded from this site.

Related Sites/ Structures: Associated structures and waste sites include the 181-N River Pump House, the 182-N Pump House, the 163-N Water Treatment Plant, the 105-N Reactor Building, 100-N-103 and 100-N-84.

Process Description: Reactor cooling water was pumped from the Columbia River, settled and treated to remove minerals, then injected into the reactor primary coolant loop at a rate of about 760 liters/minute (200 gallons/minute).

Waste Type: Water

Waste Description: The waste is steel piping, concrete, and soil (if contaminants are present). Chemical additives to the reactor cooling water included sulfuric acid, sodium hydroxide, aluminum sulfate (alum) with excess hydrated calcium oxide, sepanan, chlorine, and sodium dichromate. Water pH was maintained at about 7.5, and the free chlorine residual was approximately 0.2 milligrams/liter.

This Site has the Following SubSites:

Code: 100-N-61:1

Names: 100-N-61:1; 109-N South side pipelines of the 100-N Water Treatment and Storage Facilities Underground Pipelines

Code: 100-N-61:2

Names: 100-N-61:2; 109-N East side pipelines of the 100-N Water Treatment and Storage Facilities Underground Pipelines

Code: 100-N-61:3

Names: 100-N-61:3; 109-N West side pipelines of the 100-N Water Treatment and Storage Facilities Underground Pipelines

Code: 100-N-61:4

Names: 100-N-61:4; 182-N South side pipelines of the 100-N Water Treatment and Storage Facilities Underground Pipelines

Code: 100-N-61:1

Classification: Accepted

Names: 100-N-61:1; 109-N South side pipelines of the 100-N Water Treatment and Storage Facilities Underground Pipelines

Reclassification: Interim Closed Out (7/24/2013)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The 100-N-61:1 pipelines have been remediated and Interim Closed Out. The pipes varied in size 4 inch to 108 inch diameter. They were mainly steel and cast iron pipes wrapped in coal tar enamel mastic.

Location: They were located directly south of the 109N Heat Exchanger Building and transported mainly

water between the 109N Building and the water treatment and storage facilities (181-N, 182-N, 183-NA, 1900-N, and 1908N).

Related Sites/ Structures: Co-located associated waste sites and ancillary facilities include 100-N-37, 100-N-29, 100-N-30, 100-N-64:1, 100-N-103:1 (1 french drain on east side of 1902N), 100-N-84:1, :2, :3, :4, :5, :6, :7, Sump #2 (part of 100-N-84:5), and the 186N (slab) pipeline ends at 163N and 183N foundations. The foundations were left in place by the D4 project.

Closure Info: Interim (7/24/2013): The 100-N-61:1 group includes co-located sites 100-N-61:1, 100-N-64:1, 100-N-24, 100-N-29, 100-N-30, 100-N-37 and 100-N-53. Remediation of the 100-N-61:1 grouping of waste sites and the 100-N-53 waste site began in February 2011 and continued through April 2012.

The 100-N-24, 100-N-29, 100-N-30, and 100-N-37 waste sites were located within the remediation boundary and removed during the 100-N-61:1 pipeline remediation. The remaining basement of the 1902-N Building, the 186-N concrete pad, concrete, valves and piping associated with the 163-N sump #2 were located within the remediation boundary and were subsequently removed. A french drain (known as french drain #2) was originally part of the 100-N-103:1 subsite. However, because of its location, the drain was removed with the 100-N-61:1 pipeline remediation. Installation of a haul road was necessary to gain access to the structures. Therefore, the 100-N-53 site and segments of the 100-N-61:1 and 100-N-64:1 pipelines that were located within the roadway boundary were removed and disposed. Verification samples were collected and 100-N-53 was backfilled as part of the haul road installation.

Petroleum-stained soil was observed throughout the excavation, but was determined to be unrelated to the waste site group. Focused verification samples were collected within the stained areas and analyzed for TPH, PAH, and PCBs. Concentrations of TPH and PAH were present in the samples above direct exposure RAGs. The oil staining is considered part of the 100-N-106, Shallow Petroleum-Only Releases waste site and no additional remediation was performed.

Global Positioning Environmental Radiological Surveyor (GPERS) surveys were conducted within the 100-N-61:1 waste site grouping excavation boundary. Radiological measurements slightly above background were observed in the northern portion of the site. Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Soil, concrete, piping, and rebar were among the types of material removed from the excavation and disposed at the Environmental Restoration Disposal Facility (ERDF). Prior to the material being loaded out for shipment to ERDF, the material was staged in a combined staging pile area (SPA). Verification sampling of the SPA will be addressed with the 100-N-61:4 waste site closeout.

Excavation of the 100-N-61:1 group extended to an approximate maximum depth of 7 meters (23 ft) below ground surface. The 100-N-53 waste site was excavated to an approximate depth of 3 meters (9.8 ft) below ground surface. An estimated 70,000 bank cubic meters (91,557 bank cubic yards) of soil and debris was removed from the entire excavation. A portion of the soil removed from on top of the pipelines was stockpiled for use as clean backfill and is included in the total volume of material removed. Asbestos was detected in the soil at the SZ3-7 location, and hexavalent chromium was detected above a remedial action goal (RAG) at the SZ4-10 location. Therefore, additional remediation was conducted January 21 through February 5, 2013. Asbestos was detected in nonsoil debris (tar/tar paper) at four locations within the excavation. A visual inspection was conducted and the visible pieces of tar and/or tar paper were removed. The volume of additional material removed is included in the estimated volume.

The SubSite is Part Of:**Code:** 100-N-61**Names:** 100-N-61; 100-N Water Treatment and Storage Facilities Underground Pipelines**Code:** 100-N-61:2**Classification:** Accepted**Names:** 100-N-61:2; 109-N East side pipelines of the 100-N Water Treatment and Storage Facilities Underground Pipelines**Reclassification:** Interim Closed Out (4/3/2013)**Type:** Process Sewer**Start Date:****Status:** Inactive**End Date:**

Description: The 100-N-61:2 pipelines have been remediated and Interim Closed Out. They were located parallel to and directly east of the 109-N Heat Exchanger Building. They were used to transport transported raw water to the 109N Building from the 182-N High-Lift Pump House. These pipes varied in size 4 inch to 54 inch diameter and were mainly steel, wrapped in coal tar enamel mastic. The geographical location of the 100-N-61:2 sub-site also coincides with the 100-N-62, 100-N 105-N, 109-N, 163-N, 182-N, 183-N and 184-N Underground Pipelines waste site, which lie underneath.

Location: The pipelines were located east of the 105-N and 109-N buildings.

Related Sites/Structures: Co-located associated waste sites and ancillary facilities include 100-N-62, 100-N-84:1, :2, :3, :4, :5, :6, 100-N-63:2 and 100-N-64:2.

Process Description: These pipelines transported reactor cooling water between the water treatment facilities and the 105-N Reactor Building.

Closure Info: Interim (4/3/2013): Remediation of the 100-N-28 waste site was performed between January 25 and March 29, 2012. The site was excavated to a depth of 8.4 meters (27.6 ft) below ground surface (bgs) and resulted in the removal of 2,577 BCM (3,371 BCY) of soil and debris. The debris consisted of soil, rock, a concrete resin pit, piping, and wiring. No resin was present in the pit and it is assumed the site was only used for liquid disposal from the 109-N Building. Soil and debris were directly loaded from the 100-N-28 excavation and disposed at the Environmental Restoration Disposal Facility (ERDF).

Remedial actions for the 100-N-61:2, 100-N-62, and 100-N-64:2 sites were performed between April 13, 2011, and March 29, 2012. Excavation depths ranged from 3 meters (9.9 ft) to 8 meters (26.2 ft) bgs. Approximately 24,113 bank cubic meters of contaminated soil and debris associated with the three pipelines was removed from the waste sites and staged in the South Staging Pile Area 1 (SSP Area 1) to the south of the excavation prior to load out for disposal at ERDF. The debris consisted of rock, concrete, piping, and wiring. Verification sampling of the SSP Area 1 will be addressed in the 100-N-61:4 verification work instruction. In addition, overburden (OB) material was stockpiled in three OB piles southwest of the waste sites. The OB piles will also be addressed in the 100-N-61:4 verification work instruction.

Multiple TPH and PAH results collected at the 100-N-61:2, 100-N-62, and 100-N-64:2 excavation exceeded soil RAGs. However, these results were concluded to be cross contamination from petroleum releases unrelated to the waste sites and will be addressed as part of the 100-N-106 (Shallow Petroleum-Only Releases at 100-N; SPOR Releases) waste site and were not used for evaluation in this RSVP.

A valve pit (OSE ID N-244) was discovered at Washington State plane coordinates N149350.37, E571230.54, with asbestos pipe wrapping. The valve pit was a 1 meter (3.3 ft) diameter manhole, with a valve and a 7.6 centimeter (3 in.) pipeline running east to west.

Spatial analysis indicated that valve pit N-244 is associated with the 100-N-84:3, potable water line. The valve pit was completely removed and disposed with soil and debris from the 100-N-61:2, 100-N-62, and 100-N-64:2 excavation. No other anomalies were discovered during remediation.

The SubSite is Part Of:

Code: 100-N-61

Names: 100-N-61; 100-N Water Treatment and Storage Facilities Underground Pipelines

Code: 100-N-61:3

Classification: Accepted

Names: 100-N-61:3; 109-N West side pipelines of the 100-N Water Treatment and Storage Facilities Underground Pipelines

Reclassification: Interim Closed Out (9/6/2013)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The 100-N-61:3 pipelines have been remediated and Interim Closed Out. The 100-N-31 waste site was located on the west side of the 105-N/109-N Reactor Buildings and adjacent to the 100-N-32, 100-N-38, 100-N-61:3, 100-N-64:3, 100-N-68, UPR-100-N-3, UPR-100-N-7, UPR-100-N-10, UPR-100-N-12, and UPR-100-N-39 waste sites. These waste sites are collectively referred to as the waste sites west of the 105-N/109-N Reactor. The remediation of these waste sites resulted in one large excavation with no demarcation of the individual sites, with the exception of the UPR-100-N-39 waste site. The eleven sites were Interim Closed out in a single document.

100-N-61:3 consisted of a 30 inch diameter emergency raw water supply pipeline from the 182-N High-Lift Pump House, and a 30 inch diameter overflow pipeline located between the 1300-N Emergency Dump Basin and the 1908-N Seal Well Outfall Structure.

Location: The 100-N-61:3 pipelines were located west of the 109-N Heat Exchanger Building and 105-N Reactor Building.

Related Sites/ Structures: Co-located associated waste sites and ancillary facilities include 100-N-84:1, :2, :3, :4, :5, :6, 118-N-1, 100-N-64:3, 100-N-63:2, 100-N-32, 100-N-38, 100-N-64:3, 100-N-68, UPR-100-N-3, UPR-100-N-7, UPR-100-N-10, UPR-100-N-12, and UPR-100-N-39.

Process Description: The 100-N-61 pipelines transported reactor cooling water between water treatment facilities and the 105-N/109-N Buildings.

Closure Info: Interim (9/6/2013): Eleven waste sites located west of the 105-N/109-N Reactor Building were remediated as a group. The eleven waste sites included 100-N-31, 100-N-32, 100-N-38, 100-N-61:3, 100-N-64:3, 100-N-68, UPR-100-N-3, UPR-100-N-7, UPR-100-N-10, UPR-100-N-12, and UPR-100-N-39. This group of waste sites was referred to as the waste sites west of the 105-N/109-N Reactor. The footprints of the 1909-N Waste Disposal Valve Pit, the 107-N facility and the pipe trench between 105-N and 107-N were also located within the boundary of the group.

The eleven collocated waste sites located west of the 105-N/109-N Reactor Building were remediated, either partially or completely, by the Deactivation, Decontamination, Decommissioning, and Demolition (D4) Project during the demolition and removal of the portions of the 105-N/109-N Buildings, located outside of the safe storage enclosure (SSE).

The Field Remediation (FR) Project resumed remedial action activities west of the 105-N/109-N Reactor in November 2012. Contaminated soil, structural concrete and rebar, and piping were

removed from the collocated waste sites west of the 105-N/109-N Reactor and disposed at the Environmental Restoration Disposal Facility (ERDF). The remediation continued through March 2013 to an approximate maximum depth of 9.5 meters (31 ft) below surface grade. No anomalous materials were encountered during remediation. The remediation resulted in one large excavation with no demarcation of the individual sites, with the exception of the UPR-100-N-39 waste site. Some segments of the 100-N-61:3 and 100-N-64:3 pipelines were removed with remedial action at the 100-N-57, (1304-N) Emergency Dump Tank and 116-N-4, (1300-N) Emergency Dump Basin waste sites.

After the remediation, Global Positioning Environmental Radiological Surveyor (GPERS) surveys were performed in March 2013. Some beta and gamma contamination was detected above background. However, the area with the highest detected activity is associated with residual structures and soils for the 105-N/109-N SSE and is considered part of the 100-N-66, 105-N/109-N Reactor Building Complex waste site. A small area with elevated beta and gamma contamination was detected within the waste sites west of the 105-N/109-N Reactor boundary. Additional soil was removed from this area and disposed at the ERDF. An environmental radiological survey of the area using hand-held instruments verified that the contaminated soils have been removed.

The 1909-N Waste Disposal Valve Pit was removed during general facility demolition in this area by the D4 Project. Due to the proximity and general configuration of demolition and remediation activities on the west side of the reactor, closure of the facility footprint was deferred until nearby waste site remediation by the FR Project occurred. The residual contaminated soil that remained beneath the location of the former 1909-N facility was then removed.

The 107-N basin structure was completely removed by the D4 Project. However, closure of the basin footprint was deferred to the UPR-100-N-12 waste site. Additional soil was removed from the footprint during general waste site remediation in the area. Surveys found no elevated residual radiological activity.

Several segments of the 100-N-84 pipeline subsites were partially located within the remediation boundary. All of the segments of the 100-N-84:2, 100-N-84:4, 100-N-84:5, and 100-N-84:6 pipeline subsites that were within the excavation boundary were removed and disposed at the ERDF. Reclassification of the total 100-N-84:2, 100-N-84:4, 100-N-84:5 and 100-N-84:6 pipeline subsites will be addressed in separate closure documents.

Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

The SubSite is Part Of:

Code: 100-N-61

Names: 100-N-61; 100-N Water Treatment and Storage Facilities Underground Pipelines

Code: 100-N-61:4

Classification: Accepted

Names: 100-N-61:4; 182-N South side pipelines of the 100-N Water Treatment and Storage Facilities Underground Pipelines

Reclassification: Interim Closed Out (8/21/2013)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The 100-N-61:4 pipelines have been remediated and Interim Closed Out. The 100-N-61 waste site encompassed all underground water pipelines used to transport reactor cooling water

between water treatment facilities and the 105-N/109-N Buildings. 100-N-61:4 Water Treatment and Storage Facilities Underground Pipelines South of 182-N. The underground pipelines were steel pipes, wrapped in coal tar enamel mastic. They ranged in size from 4 inch to 42 inch diameter.

Location: The lines were located directly south of the 182-N High-Lift Pump House and underneath the 1900-N Water Supply Tank foundations.

Related Sites/ Structures: The pipelines are co-located and associated with 100-N-84 subsites :1, :2 :3, :4, :6 and :7. The pipe ends at 182N. D4 excavated 182N to 3 feet below grade and the 1900N partially removed tank. The tank foundations will need to be removed by D4 program as a TPA ancillary facility.

Process Description: These pipelines transported raw and filtered water in 4 inch to 42 inch diameter steel pipes.

Closure Info: Interim (8/21/2013): Remediation of 100-N-61:4 pipelines began after the deactivation, decontamination, decommissioning, and demolition (D4) of the 182-N Building and 1900-N Facility were completed. Several segments of the 100-N-84 pipelines were co-located in the 100-N-61:4 pipeline excavation. The 100-N South Staging Pile (SSP) began operation on February 16, 2011 and received waste from multiple adjacent or collocated waste sites. It was agreed that the SSP would be closed with the 100-N-61:4 waste site. An overburden staging area for multiple waste sites was also evaluated with 100-N-61:4. Some segments of pipelines described in 100-N-84:4 and 100-N-84:6 were co-located, remediated and sampled with the excavation of 100-N-61:4. The 100-N-61:4 and co-located pipelines were remediated between October 8, 2012, and February 4, 2013. Remediation included removal of soil, steel pipe, asbestos tar paper and mastic, concrete, steel debris, and building demolition debris. The lengths of pipeline removed and disposed at the Environmental Restoration Disposal Facility (ERDF) included approximately 565 meters (1,854 ft) for the 100-N-61:4 subsite, 152 meters (499 ft) for the 100-N-84:4 segments, and 199 meters (653 ft) for the 100-N-84:6 segments. Approximately 20,660 bank cubic meters (BCM) (26,950 bank cubic yards [BCY]) of material was removed during the remediation. Most of the material was directly loaded for disposal at the ERDF with only 4,589 BCM (5,986 BCY) staged at the SSP area prior to disposal. The pipeline excavation extended to a maximum depth of approximately 3.5 meters (11.5 ft) bgs.

Radiological surveys were conducted in March 2013. No anomalies were discovered during the remediation activities, but some soil staining was noted on the south wall of the excavation. Stain sampling found petroleum contamination that will be addressed with the 100-N-106 waste site.

Approximately 85,111 BCM (111,023 BCY) of waste material (from multiple waste sites) in the South Staging Pile was disposed at the ERDF in March 2012. In April 2012, 0.2 meters (0.5 ft) of material was scrapped from the surface of where the staging pile had been located. The area was then used to stage waste from the 100-N-61:4 excavation. This staged material was taken to ERDF in December 2012. Results of the staging area sampling found elevated levels of TPH and PAH. Further remediation of the staging area was not done, due to a previous agreement regarding cross contamination of asphaltic materials.

Three separate areas were used to stage overburden from pipeline remediations. Material with visible debris was removed and properly disposed. The overburden piles were sampled in December 2012. It was agreed that material with elevated levels of PAH would not be used as backfill in areas less than 3 meters (9.9 ft) above groundwater.

The SubSite is Part Of:

Code: 100-N-61
Names: 100-N-61; 100-N Water Treatment and Storage Facilities Underground Pipelines

Code: 100-N-62 **Classification:** Accepted
Names: 100-N-62; 100-N, 105-N, 109-N, 163-N, 182-N, 183-N and 184-N Underground Pipelines **Reclassification:** Interim Closed Out (4/3/2013)
Type: Radioactive Process Sewer **Start Date:** 1/1/1963
Status: Inactive **End Date:** 1/1/1987

Description: This site has been remediated and Interim Closed Out. It included the underground pipelines that transported reactor decontamination chemicals and/or radioactive liquid wastes from the 105-N/109-N Reactor facilities and other pipelines with the potential for radioactive contamination that were co-located on the east side of the 105-N/109-N Building complex. These pipelines consist of potentially contaminated underground steam and condensate return pipelines including a radioactive drain, miscellaneous chemical drains, a backwash return pipeline, chemical drain pipelines and chemical supply pipelines (sodium hydroxide, ammonium hydroxide and phosphoric acid).

This site does not include the pipelines that discharge to the 116-N-4 (1300-N), the 1304-N Emergency Dump Tank, pipelines to and from the 107-N and 105-N Buildings, or pipelines from the 105-N/109-N Buildings to the 1908-N Outfall that are addressed by a separate waste site (sitecode 100-N-65).

Location: The location of this site was all of the potentially radionuclide contaminated underground pipelines leaving the 105-N/109-N Buildings on the east side (east-west direction) and proceeding in a north-south direction to their respective treatment/disposal sites.

Related Sites/ Structures: The related structures are the 105-N Reactor Building, the 109-N Heat Exchange Building, the 184-N Powerhouse, the 100-N-23 and the 100-N-24 waste sites.

Process Description: Water was taken from the Columbia River and treated extensively to purify it prior to its use as reactor cooling water. In the reactor, the water circulated through the reactor core where it carried away heat to maintain safe core temperatures. This heat was transferred to a secondary system via heat exchangers from which the water returned to the reactor core in a closed loop. The secondary cooling system, also a "closed loop" system, could be maintained in a hot pressurized state from the 184-N Powerhouse when the reactor was down for maintenance or other reasons. Because of this interconnection between the auxiliary steam supply system and the contaminated secondary cooling system, the potential for cross-contamination exists. However, the auxiliary steam supply system was isolated by the use of motor operated valves and a "flow control" mode of operation that precluded back pressure contamination of the auxiliary steam system from the secondary cooling system.

Waste Type: Process Effluent

Waste Description: The waste is the underground pipelines from the east side of the 105-N and 109-N Buildings to the 184-N Powerhouse, 100-N-23 (Resin Disposal Pit Liquid Waste Site 1) and 100-N-24 (Hydrogen Dry Well Liquid Waste Site) waste sites. The chemical drain lines are known to have been used for the disposal of decontamination chemicals, however, specific chemicals and radionuclide content is currently unknown.

Closure Info: Interim (4/3/2013): Remediation of the 100-N-28 waste site was performed between January 25 and March 29, 2012. The site was excavated to a depth of 8.4 meters (27.6 ft) below ground surface (bgs) and resulted in the removal of 2,577 BCM (3,371 BCY) of soil and debris. The debris consisted of soil, rock, a concrete resin pit, piping, and wiring. No resin was present in the pit and it is assumed the site was only used for liquid disposal from the 109-N Building.

Soil and debris were directly loaded from the 100-N-28 excavation and disposed at the Environmental Restoration Disposal Facility (ERDF).

Remedial actions for the 100-N-61:2, 100-N-62, and 100-N-64:2 sites were performed between April 13, 2011, and March 29, 2012. Excavation depths ranged from 3 meters (9.9 ft) to 8 meters (26.2 ft) bgs. Approximately 24,113 bank cubic meters of contaminated soil and debris associated with the three pipelines was removed from the waste sites and staged in the South Staging Pile Area 1 (SSP Area 1) to the south of the excavation prior to load out for disposal at ERDF. The debris consisted of rock, concrete, piping, and wiring. Verification sampling of the SSP Area 1 will be addressed in the 100-N-61:4 verification work instruction. In addition, overburden (OB) material was stockpiled in three OB piles southwest of the waste sites. The OB piles will also be addressed in the 100-N-61:4 verification work instruction.

Multiple TPH and PAH results collected at the 100-N-61:2, 100-N-62, and 100-N-64:2 excavation exceeded soil RAGs. However, these results were concluded to be cross contamination from petroleum releases unrelated to the waste sites and will be addressed as part of the 100-N-106 (Shallow Petroleum-Only Releases at 100-N; SPOR Releases) waste site and were not used for evaluation in this RSVP.

A valve pit (OSE ID N-244) was discovered at Washington State plane coordinates N149350.37, E571230.54, with asbestos pipe wrapping. The valve pit was a 1 meter (3.3 ft) diameter manhole, with a valve and a 7.6 centimeter (3 in.) pipeline running east to west. Spatial analysis indicated that valve pit N-244 is associated with the 100-N-84:3, potable water line. The valve pit was completely removed and disposed with soil and debris from the 100-N-61:2, 100-N-62, and 100-N-64:2 excavation. No other anomalies were discovered during remediation.

Code:	100-N-63	Classification:	Accepted
Names:	100-N-63; 100-N Reactor (1314-N, 116-N-1 and 116-N-3) TSD Underground Pipelines	Reclassification	Interim Closed Out (10/1/2013)
Type:	Radioactive Process Sewer	Start Date:	1/1/1963
Status:	Inactive	End Date:	1/1/1987

Description: 100-N-63 was divided into two subsites. Both subsites were Reclassified to Interim Closed Out. Therefore, the parent site is also considered Interim Closed Out. The waste site encompassed the Treatment, Storage, and Disposal (TSD) underground pipelines that transported reactor cooling water and radioactive liquid wastes from the 105-N Reactor facilities to the 116-N-1 (1301-N), 116-N-3 (1325-N) Crib, and 116-N-2 (1310-N Tank).

The pipelines from 1310-N transfer tank (silo) to the 1310-N (aka 116-N-2 or Golf Ball) are 100-N-63:1. A third 30.5 centimeter (12 inch) chemical drain pipeline returns from 1310-N (Golf Ball) to the 1310-N transfer tank. From the 116-N-1 weir box, a 91.4 centimeter (36 inch) underground pipeline (100-N-63:1) connected the 116-N-1 crib and trench to the 1312-N diversion box and continued to the 116-N-3 crib and trench.

The pipelines in site 100-N-63 that exited the 105-N, 109-N and 1714-NB Buildings on the east, west and north sides are 100-N-63:2. They proceeded north-northeast to their respective treatment/disposal facilities. Pipeline diameter sizes beyond the 1322-N Building varied. A 30.5 centimeter (12-inch) radioactive drain originated on the west side of the 109-N Building as a 25.4 centimeter (10-inch) pipeline. It extended north to a 30.5 centimeter (12 inch) disposal system pipeline located east of the number 3 spacer silo. It proceeded north to a point east of the 1314-N Building and extended east to the 1322-N Building. It could be diverted to either the 1310-N (Golf Ball) via the 1310-N transfer tank or to the 1322-NC building and the 116-N-

1 weir box. The final pipeline in this subsite is the 91.4 centimeter (36-inch) contaminated drain/flush pipeline. It originated on the west side of the 105-N Building and passed under the 1722-N building. It continued in a parallel path with the 30.5 centimeters (12-inch) radioactive drain pipeline.

Not included in this waste site are underground pipelines that discharged to the 116-N-4 (1300-N Emergency Dump Basin), 1304-N Emergency Dump Tank, pipelines to and from the 107-N and 105-N Buildings, or pipelines from the 105/109-N Buildings to the 1908-N Outfall that are addressed by 100-N-64 (100-N Reactor 105/109-N Cooling Water Effluent Underground Pipelines) waste site.

Location: The location of the underground reactor effluent lines is between the 105-N Reactor Buildings and the 1314-N, 116-N-1, and 116-N-3 waste sites.

Release Description: A diesel fuel spill occurred on 1/10/2010 at the 100-N BioVenting Pilot Test Site at the 100-N Area. Approximately 330 gallons of diesel fuel were released due to an improper connection of the generator to a 1,000 gallon auxiliary fuel tank supporting the project. Spill cleanup activities on 1/10/2010 generated over 310 tons of contaminated soil that were removed and disposed at ERDF. The area of the spill was almost entirely contained within the 100-N-63:2 pipeline WIDS boundary west of the 1310-N Radioactive and Liquid Waste Treatment Facility (Golf Ball).

Agreement with the Washington State Department of Ecology on 2/4/10 determined that further cleanup actions at the site were not necessary at this time as long as the remediation design for the affected portion of the 100-N-63:2 pipeline was revised to encompass the entire area that was affected by the spill. Contractor remediation activities at 100-N are scheduled to begin in July 2010 and remediation of this portion of the waste site is anticipated to occur in late 2010. An update to the WIDS database was requested, documenting the location, including GPS, of the area impacted by the spill. GPS locations and a map of the spill location have been included in the WIDS database for the 100-N-63:2.

Related Sites/ Structures: The associated structures include: the 105-N Reactor Building, the 116-N-1 and 116-N-3 Cribs and Trenches, the 1322-N Monitoring and Pilot Plant Complex, the 1314-N Waste Transfer Station, and various valve stations, UPR-100-N-31, Radioactive Effluent Water Spill Near 116-N-1 (1301-N), UN-100-N-31.

Process Description: Water was taken from the Columbia River and treated extensively to purify it before its use as reactor cooling water. In the reactor, the water circulated through the reactor core where it carried away heat to maintain the core temperature at a safe level. This heat was yielded in a heat exchanger from which the water returned to the core in a closed loop. A small quantity of cooling water was bled off (about 760 liters/minute [200 gallons/minute]) and was replaced with fresh water from the water treatment plant. The bleed-off water and liquid wastes from other sources including decontamination stations and radioactive drains was transported to either the crib disposal system or to a storage and transportation system for disposal.

Waste Type: Process Effluent

Waste Description: The waste is the contaminated underground pipelines. The following radionuclides were released from the reactor to the 116-N-1 and/or 116-N-3 Cribs and Trenches, passing through the underground pipelines. Residual contaminants of some radionuclides may be expected to remain in the underground pipelines. These include: tritium, zinc-65, iodine-131, plutonium-238, phosphorous-32, strontium-89/90, xenon-133, plutonium-239/240, chromium-51, zirconium-niobium-95, cesium-134/137, neptunium-239, manganese-54, molybdenum-technetium-99, barium-140, iron-59, ruthenium-103/106, cerium-141, cobalt-58/60, antimony-124/125, and cerium-praseodymium-144. Additionally, decontamination chemicals are known to have passed through the underground pipelines, including phosphoric acid and diethylthiourea.

This Site has the Following SubSites:**Code:** 100-N-63:1**Names:** 100-N-63:1; Pipeline Section from 116-N-1 to 116-N-3 Crib Including Concrete Encased Pipe Bypass Structure**Code:** 100-N-63:2**Names:** 100-N-63:2; Pipelines Between 109N, 105N, 107N, 1310N, 1322N, 1926N And 36" Process Drain to Outfall**Code:** 100-N-63:1**Classification:** Accepted**Names:** 100-N-63:1; Pipeline Section from 116-N-1 to 116-N-3 Crib Including Concrete Encased Pipe Bypass Structure**Reclassification** Interim Closed Out (12/23/2002)**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** 100-N-63:1 has been remediated and Interim Closed Out with the 116-N-3 waste site. Two pipelines continued on from the 1312-N Diversion Box to the north then eastward to the southwest end of the crib. One of the pipelines was a pipe encased concrete by-pass structure that ran parallel to the original. The by-pass structure was built at the same time as the 1312-N Retention Basin (also know as the 1312-N LERF). However, neither was put into service.**Location:** These pipelines were located in the northern part of the 100-N Area, between the 116-N-1 and 116-N-3 cribs.**Waste Type:** Not Specified**Waste Description:** The waste is the contaminated underground pipelines.**Closure Info:** Interim: A portion of the pipeline 100-N-63:1 was remediated with the 116-N-3 Crib and Interim Closed Out in CVP-2002-00002. For purposes of the CVP and consistent with the permitted TSD site designation, the 116-N-3 Crib and Trench, the 100-N-63:1 Pipeline, and the bypass structure are collectively referred to as the 116-N-3 site.

Remediation at the 116-N-3 site began on July 21, 2000. Excavation of the site involved removing the overburden materials, debris, the contaminated and uncontaminated structure, and underlying contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. The pipeline bypass (100-N-63:1) trenches were excavated completely and clean backfill was used to provide a temporary road for utilities and crossing. Contaminated materials were disposed of at the ERDF. On December 21, 2001, the excavation was completed. Only the portion of the trench near the crib was excavated. Effluent in the trench percolated into the soil column before overflowing the first earthen dam. Thus, the remainder of the trench beyond the first dam was not affected by waste disposal activities and did not require remediation. The excavation for the entire 116-N-3 site was approximately 21,980 square meters (236,590 sq. ft.) in area. Soils were removed beneath the crib and trench to a minimum of 1.5 meters (5 ft) below the engineered structures. Approximately 140,270 metric tons (154,578 tons) of material from the site were disposed of at the ERDF.

The SubSite is Part Of:**Code:** 100-N-63**Names:** 100-N-63; 100-N Reactor (1314-N, 116-N-1 and 116-N-3) TSD Underground Pipelines

Code: 100-N-63:2 **Classification:** Accepted
Names: 100-N-63:2; Pipelines Between 109N, 105N, **Reclassification** Interim Closed Out (10/1/2013)
 107N, 1310N, 1322N, 1926N And 36" Process
 Drain to Outfall
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The 100-N-63:2 subsite has been remediated and Reclassified to Interim Closed Out. The 100-N-63:2 subsite encompassed the TSD underground pipelines that transported reactor cooling water and radioactive and chemical liquid wastes from the 105-N Reactor facilities to the 116-N-1 (1301-N Crib and Trench) and the 91.4 cm (36 in.) process drain that emptied into the 100-N-77 (100-N River Effluent Pipeline). The 100-N-63:2 pipelines originated on the north, east, and west sides of the 105-N Reactor Building and ran to either the 116-N-1 or the 100-N-77 effluent pipeline. The 100-N-63:2 subsite also includes the area where a diesel fuel spill occurred on January 10, 2010, at the 100-N Bioventing Pilot Test Site. The 100-N-77 effluent pipeline and the diesel fuel spill are not associated with the 100-N-63:2 TSD pipeline under the RCRA Permit (Ecology 2012), but are included in the evaluation of the 100-N-63:2 subsite cleanup.

The 100-N-63:2 waste site pipelines were located throughout the 100-N Area and were co-located with a number of other pipeline waste sites, including but not limited to the 100-N-84, 100-N Miscellaneous Pipelines waste site. During remediation of the 100-N-63:2 waste site, co-located waste sites were also partially or fully remediated.

Location: The 100-N-63:2 waste site pipelines are located throughout the 100-N Area and are collocated with a number of other pipeline waste sites including but not limited to the 100-N-84, 100-N Miscellaneous Pipelines waste site. The pipelines originated on the north, east and west sides of the 105-N Reactor Building and ran to either the 116-N-1 Crib or the 100-N-77 effluent pipeline.

Related Sites/ Structures: 100-N-63:2 is associated with the 100-N-77 and 100-N-84 pipeline sites and UPR-100-N-17.

Waste Type: Not Specified

Waste Description: The waste is the contaminated underground pipelines.

Closure Info: Interim (10/1/2013): The 100-N-63:2 subsite was remediated between June 2009 and May 2013, with all remaining RCRA TSD pipelines being completely removed. Excavation included the removal of the pipelines and the underlying contaminated soil. During the remediation of the 100-N-63:2 pipeline subsite, co-located sites were also either fully or partially removed. Independent site-specific closure documents will be prepared for co-located waste sites per agreement with Ecology. If the boundary of a co-located waste site extended beyond the 100-N-63:2 excavation boundaries, remediation of that waste site may require additional remediation independent of the 100-N-63:2 subsite. Several land bridges were constructed over the 100-N-63:2 excavation using clean fill to provide essential access within the 100-N Area. The remediation also included the area where a diesel spill occurred on January 10, 2010, at the 100-N Bioventing Well Island in the 100-N Area. Approximately 1,247 liters (330 gal) of diesel fuel was released due to an improper connection of the generator to a 3,780 liters (1,000-gal) auxiliary fuel tank supporting the project. Spill cleanup activities on January 10, 2010, generated over 310 tons of contaminated soil that were removed and disposed at ERDF. The area of the spill was almost entirely contained within the 100-N-63:2 pipeline boundary, west of the 116-N-2 waste site (1310-N Radioactive and Liquid Waste Treatment Facility [Golf Ball]).

The remedial action at the 116-N-2 (1310-N Golf Ball) was performed between March 1, 2011, and April 26, 2012 and removed several sections of 100-N-63:2 pipelines, with the exception of one pipeline section that remained on a side slope in the northern part of the excavation. This pipeline was a 7.6 meter (25 ft) long section of 30 cm (12 in.) diameter pipe that was remediated between March 22 and April 18, 2013.

The excavation depth varied from 0.9 to 5.5 meters (3 to 18 ft), below ground surface, depending on the depth of pipeline and the volume of the underlying contaminated soil. Approximately 2,465 meters (8,088 ft) of piping was removed from the 100-N-63:2 excavation. An estimated total volume of 39,753 bank cubic meters (51,995 bank cubic yards) of contaminated soil and pipelines was excavated and disposed of at the Environmental Restoration Disposal Facility. There were no staging pile areas (SPAs) or overburden piles associated with the 100-N-63:2 subsite excavation.

The SubSite is Part Of:

Code: 100-N-63

Names: 100-N-63; 100-N Reactor (1314-N, 116-N-1 and 116-N-3) TSD Underground Pipelines

Code: 100-N-64

Classification: Accepted

Names: 100-N-64; 100-N Reactor 105/109-N Cooling Water Effluent Underground Pipelines

Reclassification: Interim Closed Out (9/6/2013)

Type: Radioactive Process Sewer

Start Date: 1/1/1963

Status: Inactive

End Date: 1/1/1987

Description: The site was divided into three subsites based on geographical locations. The subsites are 100-N-64:1 Cooling Water Effluent Underground Pipelines South of 109-N, 100-N-64:2 Cooling Water Effluent Underground Pipelines East of 109-N and 100-N-64:3 Cooling Water Effluent Underground Pipelines West of 109-N. All the subsites have been remediated and reclassified to Interim Closed Out. Therefore, the parent site is also considered Interim Closed Out.

100-N-64 includes those underground pipelines that transported reactor cooling water from the 105-N Reactor facilities to the 116-N-4 (1300-N), the 1304-N Emergency Dump Basin and Tank respectively, the 107-N Filter Building and the pipelines from these facilities to the 1908-N Outfall Structure. The site does include overflow lines to the 1908-N Outfall Structure, but does not include the 1908-N Outfall Structure. It does not include the underground lines that discharged to the 1301-N (116-N-1) and/or 1325-N (116-N-3) Cribs. (see sitecode 100-N-63).

The 107-N Building includes return pipelines as well as other process pipelines contained in a concrete encasement between the 105-N and 107-N Buildings. This encasement houses 0.26-meter (10-inch) and 0.46-meter (18-inch) demineralized water lines, a 0.3-meter (12-inch) filtered water line, 1.3-centimeter (0.5-inch) instrument air, 5.1-centimeter (2-inch) steam, 15-centimeter (6-inch) fire, line and telephone, instrument, power, and fire alarm lines. The encasement is about 30 meters (98 feet) long. (The remaining underground pipelines associated with the 1300-N and 1304-N include a 0.76-meter [30-inch] flush line, a 0.61-meter [24-inch] vent, a 0.76-meter [30-inch] overflow, a 25.4-centimeter [10-inch] blowdown, and a connection to the 25.4-centimeter [10-inch] radioactive drain line that becomes the 0.3-meter [12-inch] radioactive drain line that are not included with this waste site.)

Location: This site was the underground pipelines running between the 105/109-N Buildings to the 116-N-4 (1300-N), the 1304-N Emergency Dump Basin and Tank, the 107-N Filter Building to the 1908-N Outfall Structure. The pipelines exited the 105-N Reactor Building on the west side and extended to the west to their respective treatment/disposal facilities.

Related Sites/ Structures: The associated structures are the 105-N and 109-N Reactor Buildings. The TSD pipelines are in site 100-N-63.

Process Description: The Emergency Dump Basin (116-N-4/1300-N) and the Emergency Dump Tank (1304-N) were designed to receive "single-pass" reactor cooling water in the case of an emergency. Both systems were used to periodically receive steam blowdown. The 1304-N Tank replaced the 1300-N Basin. This steam condensate normally contained low levels of radionuclide contamination and fission products. Overflow and drain lines to the 1908-N Outfall Structure are include in this waste site. However, the outfall structure is a separate waste site.

Waste Type: Process Effluent

Waste Description: The waste is the contaminated underground pipelines. The following radionuclides were released from the reactor through the underground pipelines to the 116-N-4 (1300-N), 1304-N Emergency Dump Basin and Tank, the 107-N Filter Building and to the 1908-N Outfall Structure. Residual contaminants of some may be expected to remain in the underground pipelines. These include: sodium-24, niobium-95, iodine-131, chromium-51, zirconium-95, tellurium-132, technetium-99, manganese-54, iron-59, ruthenium-103, cerium-144, and cobalt-60. Because of radioactive decay, only manganese-54, cobalt-60, and cerium-144 are expected to remain.

This Site has the Following SubSites:

Code: 100-N-64:1

Names: 100-N-64:1; 109-N South side pipelines of the 100-N Reactor 105/109-N Cooling Water Effluent Underground Pipelines

Code: 100-N-64:2

Names: 100-N-64:2; 109-N East side pipelines of the 100-N Reactor 105/109-N Cooling Water Effluent Underground Pipelines

Code: 100-N-64:3

Names: 100-N-64:3; 109-N West side pipelines of the 100-N Reactor 105/109-N Cooling Water Effluent Underground Pipelines

Code: 100-N-64:1

Classification: Accepted

Names: 100-N-64:1; 109-N South side pipelines of the 100-N Reactor 105/109-N Cooling Water Effluent Underground Pipelines

Reclassification: Interim Closed Out (7/24/2013)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The 100-N-64:1 subsite has been remediated and Interim Closed Out. They were 10 inch diameter pipelines, located directly south of the 109N Heat Exchanger Building. They were used as blowdown lines from the 109N Heat Exchanger Building to the 1908-N Seal Well Outfall Structure.

Location: This site is the location of underground pipelines running between the 105/109-N Buildings to the 116-N-4 (1300-N), the 1304-N Emergency Dump Basin and Tank, the 107-N Filter Building to the 1908-N Outfall Structure. The pipelines exit the 105-N Reactor Building on the west side and extend to the west to their respective treatment/disposal facilities.

Related Sites/ Structures: Co-located associated waste sites and ancillary facilities include: 100-N-37, 100-N-29, 100-N-30, 100-N-61:1, 100-N-103:1 (french drain on east side of 1902N), 100-N-84:1, :2, :3, :4, :5, :6, :7, Sump #2 (part of 100-N-84:5). The 186N (slab) pipeline ends at 163N and 183N foundations. The foundations were left in place by the D4 project.

Process Description: The pipelines transported reactor cooling water to the 1300-N Emergency Dump Basin.

Closure Info: Interim (7/24/2013): The 100-N-61:1 group includes co-located sites 100-N-61:1, 100-N-64:1, 100-N-24, 100-N-29, 100-N-30, 100-N-37 and 100-N-53. Remediation of the 100-N-61:1 grouping of waste sites and the 100-N-53 waste site began in February 2011 and continued through April 2012.

The 100-N-24, 100-N-29, 100-N-30, and 100-N-37 waste sites were located within the remediation boundary and removed during the 100-N-61:1 pipeline remediation. The remaining basement of the 1902-N Building, the 186-N concrete pad, concrete, valves and piping associated with the 163-N sump #2 were located within the remediation boundary and were subsequently removed. A french drain (known as french drain #2) was originally part of the 100-N-103:1 subsite. However, because of its location, the drain was removed with the 100-N-61:1 pipeline remediation. Installation of a haul road was necessary to gain access to the structures. Therefore, the 100-N-53 site and segments of the 100-N-61:1 and 100-N-64:1 pipelines that were located within the roadway boundary were removed and disposed. Verification samples were collected and 100-N-53 was backfilled as part of the haul road installation.

Petroleum-stained soil was observed throughout the excavation, but was determined to be unrelated to the waste site group. Focused verification samples were collected within the stained areas and analyzed for TPH, PAH, and PCBs. Concentrations of TPH and PAH were present in the samples above direct exposure RAGs. The oil staining is considered part of the 100-N-106, Shallow Petroleum-Only Releases waste site and no additional remediation was performed.

Global Positioning Environmental Radiological Surveyor (GPERS) surveys were conducted within the 100-N-61:1 waste site grouping excavation boundary. Radiological measurements slightly above background were observed in the northern portion of the site. Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Soil, concrete, piping, and rebar were among the types of material removed from the excavation and disposed at the Environmental Restoration Disposal Facility (ERDF). Prior to the material being loaded out for shipment to ERDF, the material was staged in a combined staging pile area (SPA). Verification sampling of the SPA will be addressed with the 100-N-61:4 waste site closeout.

Excavation of the 100-N-61:1 group extended to an approximate maximum depth of 7 meters (23 ft) below ground surface. The 100-N-53 waste site was excavated to an approximate depth of 3 meters (9.8 ft) below ground surface. An estimated 70,000 bank cubic meters (91,557 bank cubic yards) of soil and debris was removed from the entire excavation. A portion of the soil removed from on top of the pipelines was stockpiled for use as clean backfill and is included in the total volume of material removed. Asbestos was detected in the soil at the SZ3-7 location, and hexavalent chromium was detected above a remedial action goal (RAG) at the SZ4-10 location. Therefore, additional remediation was conducted January 21 through February 5, 2013. Asbestos was detected in nonsoil debris (tar/tar paper) at four locations within the excavation. A visual inspection was conducted and the visible pieces of tar and/or tar paper were removed. The volume of additional material removed is included in the estimated volume.

The SubSite is Part Of:

Code: 100-N-64

Names: 100-N-64; 100-N Reactor 105/109-N Cooling Water Effluent Underground Pipelines

Code: 100-N-64:2 **Classification:** Accepted
Names: 100-N-64:2; 109-N East side pipelines of the 100-N Reactor 105/109-N Cooling Water Effluent Underground Pipelines **Reclassification** Interim Closed Out (4/3/2013)
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The 100-N-64:2 sub-site has been remediated and Interim Closed Out.

Location: The pipeline was located parallel to and directly east of the 105-N reactor and the 109-N Heat Exchanger Building. The geographical location of the 100-N-61:2 sub-site also coincides with the 100-N-62, 100-N 105-N, 109-N, 163-N, 182-N, 183-N and 184-N Underground Pipelines waste site, that lie underneath.

Related Sites/ Structures: Co-located associated waste sites and ancillary facilities include 100-N-62, 100-N-84:1, :2, :3, :4, :5, :6, 100-N-61:2 and 100-N-63:2.

Process Description: The Emergency Dump Basin (116-N-4/1300-N) and the Emergency Dump Tank (1304-N) were designed to receive "single-pass" reactor cooling water in the case of an emergency. Both systems were used to periodically receive steam blowdown. This steam condensate normally contained low levels of radionuclide contamination and fission products. Overflow and drain lines to the 1908-N Outfall Structure are also included in this waste site.

Closure Info: Interim (4/3/2013): Remediation of the 100-N-28 waste site was performed between January 25 and March 29, 2012. The site was excavated to a depth of 8.4 meters (27.6 ft) below ground surface (bgs) and resulted in the removal of 2,577 BCM (3,371 BCY) of soil and debris. The debris consisted of soil, rock, a concrete resin pit, piping, and wiring. No resin was present in the pit and it is assumed the site was only used for liquid disposal from the 109-N Building. Soil and debris were directly loaded from the 100-N-28 excavation and disposed at the Environmental Restoration Disposal Facility (ERDF).

Remedial actions for the 100-N-61:2, 100-N-62, and 100-N-64:2 sites were performed between April 13, 2011, and March 29, 2012. Excavation depths ranged from 3 meters (9.9 ft) to 8 meters (26.2 ft) bgs. Approximately 24,113 bank cubic meters of contaminated soil and debris associated with the three pipelines was removed from the waste sites and staged in the South Staging Pile Area 1 (SSP Area 1) to the south of the excavation prior to load out for disposal at ERDF. The debris consisted of rock, concrete, piping, and wiring. Verification sampling of the SSP Area 1 will be addressed in the 100-N-61:4 verification work instruction. In addition, overburden (OB) material was stockpiled in three OB piles southwest of the waste sites. The OB piles will also be addressed in the 100-N-61:4 verification work instruction.

Multiple TPH and PAH results collected at the 100-N-61:2, 100-N-62, and 100-N-64:2 excavation exceeded soil RAGs. However, these results were concluded to be cross contamination from petroleum releases unrelated to the waste sites and will be addressed as part of the 100-N-106 (Shallow Petroleum-Only Releases at 100-N; SPOR Releases) waste site and were not used for evaluation in this RSVP.

A valve pit (OSE ID N-244) was discovered at Washington State plane coordinates N149350.37, E571230.54, with asbestos pipe wrapping. The valve pit was a 1 meter (3.3 ft) diameter manhole, with a valve and a 7.6 centimeter (3 in.) pipeline running east to west. Spatial analysis indicated that valve pit N-244 is associated with the 100-N-84:3, potable water line. The valve pit was completely removed and disposed with soil and debris from the 100-N-61:2, 100-N-62, and 100-N-64:2 excavation. No other anomalies were discovered during remediation.

The SubSite is Part Of:**Code:** 100-N-64**Names:** 100-N-64; 100-N Reactor 105/109-N Cooling Water Effluent Underground Pipelines**Code:** 100-N-64:3**Classification:** Accepted**Names:** 100-N-64:3; 109-N West side pipelines of the 100-N Reactor 105/109-N Cooling Water Effluent Underground Pipelines**Reclassification:** Interim Closed Out (9/6/2013)**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:**

Description: This sub-site has been remediated and Interim Closed Out. The 100-N-31 waste site was located on the west side of the 105-N/109-N Reactor Buildings and adjacent to the 100-N-32, 100-N-38, 100-N-61 :3, 100-N-64:3, 100-N-68, UPR-100-N-3, UPR-100-N-7, UPR-100-N-10, UPR-100-N-12, and UPR-100-N-39 waste sites. These waste sites are collectively referred to as the waste sites west of the 105-N/109-N Reactor. The remediation of these waste sites resulted in one large excavation with no demarcation of the individual sites, with the exception of the UPR-100-N-39 waste site. The eleven sites were Interim Closed out in a single document.

100-N-64:3 consisted of pipelines ranging from 2 inches to 32 inches in diameter. The pipelines were used to transport vent, flush, blow-down, filtered, fire line, and demineralized water between the 109-N Building and the 1304-N Emergency Dump Tank, 1300-N Emergency Dump Basin, 107-N Basin Recirculation Facility and the 1303-N Radioactive Dummy Burial Facility/Spacer Silos. It also included utility lines contained in a concrete trench. The hot spot contamination in the northern portion of the 116-N-4 Emergency Dump Basin excavation was deferred to 100-N-64:3.

Location: The 100-N-64:3 pipelines were located west of the 109-N Heat Exchanger Building and 105-N Reactor Building.

Related Sites/ Structures: Co-located associated waste sites and ancillary facilities include: 116-N-4, 100-N-84:1, :2, :3, :4, :5, :6, 118-N-1, 100-N-31 100-N-32, 100-N-38, 100-N-61:3, 100-N-68, UPR-100-N-3, UPR-100-N-7, UPR-100-N-10, UPR-100-N-12, and UPR-100-N-3.

Closure Info: Interim (9/6/2013): Eleven waste sites located west of the 105-N/109-N Reactor Building were remediated as a group. The eleven waste sites included 100-N-31, 100-N-32, 100-N-38, 100-N-61:3, 100-N-64:3, 100-N-68, UPR-100-N-3, UPR-100-N-7, UPR-100-N-10, UPR-100-N-12, and UPR-100-N-39. This group of waste sites was referred to as the waste sites west of the 105-N/109-N Reactor. The footprints of the 1909-N Waste Disposal Valve Pit, the 107-N facility and the pipe trench between 105-N and 107-N were also located within the boundary of the group.

The eleven collocated waste sites located west of the 105-N/109-N Reactor Building were remediated, either partially or completely, by the Deactivation, Decontamination, Decommissioning, and Demolition (D4) Project during the demolition and removal of the portions of the 105-N/109-N Buildings, located outside of the safe storage enclosure (SSE).

The Field Remediation (FR) Project resumed remedial action activities west of the 105-N/109-N Reactor in November 2012. Contaminated soil, structural concrete and rebar, and piping were removed from the collocated waste sites west of the 105-N/109-N Reactor and disposed at the Environmental Restoration Disposal Facility (ERDF). The remediation continued through March 2013 to an approximate maximum depth of 9.5 meters (31 ft) below surface grade. No anomalous materials were encountered during remediation. The remediation resulted in one large excavation with no demarcation of the individual sites, with the exception of the UPR-100-

N-39 waste site. Some segments of the 100-N-61:3 and 100-N-64:3 pipelines were removed with remedial action at the 100-N-57, (1304-N) Emergency Dump Tank and 116-N-4, (1300-N) Emergency Dump Basin waste sites.

After the remediation, Global Positioning Environmental Radiological Surveyor (GPERS) surveys were performed in March 2013. Some beta and gamma contamination was detected above background. However, the area with the highest detected activity is associated with residual structures and soils for the 105-N/109-N SSE and is considered part of the 100-N-66, 105-N/109-N Reactor Building Complex waste site. A small area with elevated beta and gamma contamination was detected within the waste sites west of the 105-N/109-N Reactor boundary. Additional soil was removed from this area and disposed at the ERDF. An environmental radiological survey of the area using hand-held instruments verified that the contaminated soils have been removed.

The 1909-N Waste Disposal Valve Pit was removed during general facility demolition in this area by the D4 Project. Due to the proximity and general configuration of demolition and remediation activities on the west side of the reactor, closure of the facility footprint was deferred until nearby waste site remediation by the FR Project occurred. The residual contaminated soil that remained beneath the location of the former 1909-N facility was then removed.

The 107-N basin structure was completely removed by the D4 Project. However, closure of the basin footprint was deferred to the UPR-100-N-12 waste site. Additional soil was removed from the footprint during general waste site remediation in the area. Surveys found no elevated residual radiological activity.

Several segments of the 100-N-84 pipeline subsites were partially located within the remediation boundary. All of the segments of the 100-N-84:2, 100-N-84:4, 100-N-84:5, and 100-N-84:6 pipeline subsites that were within the excavation boundary were removed and disposed at the ERDF. Reclassification of the total 100-N-84:2, 100-N-84:4, 100-N-84:5 and 100-N-84:6 pipeline subsites will be addressed in separate closure documents.

Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

The SubSite is Part Of:

Code: 100-N-64

Names: 100-N-64; 100-N Reactor 105/109-N Cooling Water Effluent Underground Pipelines

Code: 100-N-65

Classification: Accepted

Names: 100-N-65; Diesel Oil Interceptor Trench; UPR-100-N-17 Interceptor Trench

Reclassification: None

Type: Trench

Start Date: 1/1/1966

Status: Inactive

End Date:

Description: The site is a trench that was excavated along the Columbia River bank to intercept diesel oil before it could reach the river. The trench was excavated as a result of an unplanned release of 303,000 liters (80,000 gallons) of diesel fuel that leaked from a pipeline within 166-N Tank Farm (See UPR-100-N-17). Several smaller unplanned releases also contributed to the need for the trench (See UPR-100-N-19 and UPR-100-N-20). Oil trapped in the trench was ignited and burned. A significant portion of the oil was thus removed before it could reach the river. In 1994, the trench was backfilled with material to the top of the adjacent berm.

Location: The trench was located on the riverbank, northeast of 166-N Tank Farm.

Related Sites/ Structures: The site was related to the 166-N Tank Farm, the Fuel Oil Unloading Trench, and the Fuel Oil Day Tanks (184-N Powerhouse).

Process Description: The trench was excavated along the Columbia River bank to intercept diesel oil before it could reach the river.

Waste Type: Oil

Waste Description: The waste was diesel oil from spills in the 100-N Area diesel oil storage facilities.

Code: 100-N-67 **Classification:** Accepted

Names: 100-N-67; HGP Dumping Area **Reclassification:** Interim No Action (9/11/2000)

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The site has been evaluated and determined to require No Action. It is a pile of metal banding material, barbed wire, wire rope, concrete, and pipe. Some of the materials are partially buried.

Location: The site is located approximately 250 meters (820 feet) west of the Bonneville Power Administration (BPA) substation and Hanford Generating Plant facility fence. It is between the facility fence and the Columbia River. It is directly under the western BPA powerlines that cross the Columbia River.

Process Description: The waste appears to have been generated from the construction of the Bonneville Power Administration (BPA) powerlines.

Waste Type: Construction Debris

Waste Description: The site contains metal banding material, barbed wire, pipe, and concrete.

Closure Info: Interim: In September 2000, Waste Site Reclassification Form 2000-057 declared the metal and concrete debris was not hazardous and reclassified the site to No Action.

Code: 100-N-68 **Classification:** Accepted

Names: 100-N-68; N Basin Low Level Radioactive Water Spill **Reclassification:** Interim Closed Out (9/6/2013)

Type: Unplanned Release **Start Date:** 1/7/1998

Status: Inactive **End Date:** 2/20/1998

Description: The site has been remediated and Interim Closed Out. The 100-N-31 waste site was located on the west side of the 105-N/109-N Reactor Buildings and adjacent to the 100-N-32, 100-N-38, 100-N-61 :3, 100-N-64:3, 100-N-68, UPR-100-N-3, UPR-100-N-7, UPR-100-N-10, UPR-100-N-12, and UPR-100-N-39 waste sites. These waste sites are collectively referred to as the waste sites west of the 105-N/109-N Reactor. The remediation of these waste sites resulted in one large excavation with no demarcation of the individual sites, with the exception of the UPR-100-N-39 waste site. The eleven sites were Interim Closed out in a single document.

100-N-68 was a release of contaminated water onto the floor of the 105-N building that seeped under the roll up doors and onto the ground outside. The release area had been posted with

Contaminated Area signs. In 1998, the contamination was temporarily stabilized with a fixative, tarps and plywood. Later it was stabilized with asphalt.

Location: The site was located just outside the N Basin Transfer area, west of the 105-N Building.

Release Description: On January 7, 1998, at approximately 0810 hours, a Decontamination and Decommissioning (D&D) worker in the 105-N Basin discovered water spraying from a hose connected to the Final Transfer Filtration (FTF) system. The worker immediately shut off the FTF system and notified management.

The event investigation determined the intake hose to the FTF system had split sometime between 2:00-4:00 am, causing contaminated water from the basin to be released to the floor. The estimated amount of water released from the basin is approximately 1.36E+05 liters (36,000 gallons). The basin drains captured most of the water, however an estimated 7,600 liters (2,000 gallons) leaked under a set of roll-up doors and ran outside of the building. This water pooled on concrete and gravel surfaces, in an area 6 by 9 meters (20 by 30 feet). Two pedestrians had walked through the contaminated area and had 30,000 disintegrations/minute beta/gamma contamination on their boots. Three areas, totaling approximately 280 square meters (3,000 square feet), were found to be contaminated.

Approximately 0.42 total curies had been released. No reportable quantities were exceeded. The primary radionuclides in the water are tritium (approximately 0.26 curies), strontium-90 (approximately 0.06 curies), and cesium-137 (approximately 0.013 curies). The calculated amount of N Basin water released to the environment, was 7,380 liters (1,950 gallons), which was used in the calculations and is believed to be conservative. This is because no adjustments were made for water absorbed during cleanup activities, evaporation, or for residual water that would be in the piping between the N Basin floor drains and the Lift Station (where the bulk of the water was collected). The extent of contamination found outside the basin appeared to substantiate the calculated amount.

Process Description: The filtration system at the 100-N Fuel Storage Basin (FSB) experienced a leak through a split hose of about 36,000 gallons of radioactively contaminated water on the morning of January 7, 1998. Approximately 2,000 gallons flowed outside the FSB enclosure. The final transfer filtration system was used to reduce the turbidity of the FSB water while decontamination and decommissioning (D&D) workers recovered items from the basin. The FTF was used to remove particulates from the basin water to increase water clarity.

Waste Type: Water

Waste Description: Using current analytical data on the N Basin water, the total curies released in the spill/leak for all of the radionuclides was calculated to be 0.42 curies. No reportable quantities were exceeded.

Closure Info: Interim (9/6/2013): Eleven waste sites located west of the 105-N/109-N Reactor Building were remediated as a group. The eleven waste sites included 100-N-31, 100-N-32, 100-N-38, 100-N-61:3, 100-N-64:3, 100-N-68, UPR-100-N-3, UPR-100-N-7, UPR-100-N-10, UPR-100-N-12, and UPR-100-N-39. This group of waste sites was referred to as the waste sites west of the 105-N/109-N Reactor. The footprints of the 1909-N Waste Disposal Valve Pit, the 107-N facility and the pipe trench between 105-N and 107-N were also located within the boundary of the group.

The eleven collocated waste sites located west of the 105-N/109-N Reactor Building were remediated, either partially or completely, by the Deactivation, Decontamination, Decommissioning, and Demolition (D4) Project during the demolition and removal of the portions of the 105-N/109-N Buildings, located outside of the safe storage enclosure (SSE).

The Field Remediation (FR) Project resumed remedial action activities west of the 105-N/109-N Reactor in November 2012. Contaminated soil, structural concrete and rebar, and piping were

removed from the collocated waste sites west of the 105-N/109-N Reactor and disposed at the Environmental Restoration Disposal Facility (ERDF). The remediation continued through March 2013 to an approximate maximum depth of 9.5 meters (31 ft) below surface grade. No anomalous materials were encountered during remediation. The remediation resulted in one large excavation with no demarcation of the individual sites, with the exception of the UPR-100-N-39 waste site. Some segments of the 100-N-61:3 and 100-N-64:3 pipelines were removed with remedial action at the 100-N-57, (1304-N) Emergency Dump Tank and 116-N-4, (1300-N) Emergency Dump Basin waste sites.

After the remediation, Global Positioning Environmental Radiological Surveyor (GPERS) surveys were performed in March 2013. Some beta and gamma contamination was detected above background. However, the area with the highest detected activity is associated with residual structures and soils for the 105-N/109-N SSE and is considered part of the 100-N-66, 105-N/109-N Reactor Building Complex waste site. A small area with elevated beta and gamma contamination was detected within the waste sites west of the 105-N/109-N Reactor boundary. Additional soil was removed from this area and disposed at the ERDF. An environmental radiological survey of the area using hand-held instruments verified that the contaminated soils have been removed.

The 1909-N Waste Disposal Valve Pit was removed during general facility demolition in this area by the D4 Project. Due to the proximity and general configuration of demolition and remediation activities on the west side of the reactor, closure of the facility footprint was deferred until nearby waste site remediation by the FR Project occurred. The residual contaminated soil that remained beneath the location of the former 1909-N facility was then removed.

The 107-N basin structure was completely removed by the D4 Project. However, closure of the basin footprint was deferred to the UPR-100-N-12 waste site. Additional soil was removed from the footprint during general waste site remediation in the area. Surveys found no elevated residual radiological activity.

Several segments of the 100-N-84 pipeline subsites were partially located within the remediation boundary. All of the segments of the 100-N-84:2, 100-N-84:4, 100-N-84:5, and 100-N-84:6 pipeline subsites that were within the excavation boundary were removed and disposed at the ERDF. Reclassification of the total 100-N-84:2, 100-N-84:4, 100-N-84:5 and 100-N-84:6 pipeline subsites will be addressed in separate closure documents.

Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Code:	100-N-77	Classification:	Accepted
Names:	100-N-77; River Line from 1908-N Outfall; 100N River Effluent Pipeline	Reclassification	None
Type:	Radioactive Process Sewer	Start Date:	
Status:	Inactive	End Date:	
Description:	This site consists of a 260 centimeter (102 inch) pipeline that exits the northwest face of the Outfall (1908-N) to the Columbia River.		
Location:	The river line is located in the Columbia River, adjacent to the 100N area. The line extends into the main channel of the river from the 1908-N Outfall.		

The 100-N-77 river effluent pipeline originates from, and is perpendicular to, the face of the

1908-N outfall structure. The pipeline extends 118 meters (386 feet) from the outfall face before turning 30 degrees upstream, and continuing for another 148 meters (485 feet) to its discharge point in the Columbia River.

Release Description: On April 18, 1986, there was a 70-minute undocumented liquid unplanned release to the river of wastewater that was beyond the pH limits allowed by the NPDES permit. The pH of the 163-N demineralization plant wastewater was permitted between 6 and 9. For about 60 minutes it was released to the river at a pH below 6, and for an additional 10 minutes at a pH above 9. The total volume released was not known.

Related Sites/Structures: The site is associated with the 1908-N outfall (1908-N), an emergency outfall flume (100-N-79) and the 1300-N Emergency Dump Basin 76-centimeter (30 inch) overflow line.

Process Description: The river effluent pipeline received more than 2 million cubic meters per day of single pass raw river water from the Circulating Raw Water (CRW) System, and discharged it to the river. The CRW supplied once-through untreated river water to 16 dump condensers and 7 surface condensers. The water was used to cool the secondary cooling water for the N Reactor from the 1908-N Seal well (1908-N Outfall) and discharged it to the Columbia River.

Waste Type: Process Effluent

Waste Description: The waste includes the pipeline and the potentially contaminated scale and sediment contained within it.

Code: 100-N-78

Classification: Accepted

Names: 100-N-78; 1716-NE Maintenance Garage; HGP SWMU #8

Reclassification: Interim Closed Out (6/15/2004)

Type: Maintenance Shop

Start Date:

Status: Inactive

End Date:

Description: The site has been remediated and Interim Closed Out. The 1716-NE Maintenance Garage was used for vehicle maintenance. The garage had three vehicle bays, each containing a floor drain that led to the 100-N-3 Maintenance Garage French Drain (SWMU #9).

Location: The 1716-NE Maintenance Garage (SWMU #8) was located to the east of the former 185-N Building.

Related Sites/Structures: The garage is associated with the 100-N-52 Gasoline Storage Tank (UST).

Process Description: The former HGP consisted of two 430-megawatt turbine generators that operated from 1966 until 1986 using steam from the adjacent 100-N production reactor for generation of electricity. The generators were located in the 185-N Building. The site was an ancillary or support facility to the former HGP.

Closure Info: Interim (6/15/2004): The 100-N Reactor provided fuel rods to the plutonium production process at Hanford, but also operated two 430 megawatt turbine generators for the generation of electricity. The Washington Public Supply System, later named Energy Northwest, was responsible for the Hanford Generating Plant located at 100-N Reactor. The Cleanup Verification Package (HGP-CVP-SWMUs 5, 6, 7, 8, 9, & 10) for the Hanford Generating Plant Solid Waste Management units was prepared by Energy Northwest in 2004. Some remedial actions at HGP began in 1992. Other characterization and remediation was completed in 2004. Remedial action activity descriptions include:

100-N-1 Settling Pond (SWMU#6) - Remediation activities conducted in 2001 removed approximately 0.9 meters (3 ft) of soil and settled solids material from the 100-N-1 Settling

Pond (SWMU #6). The excavated material was disposed of at the Environmental Restoration Disposal Facility (ERDF).

100-N-3 Maintenance Garage French Drain, 100-N-41 Gate House Septic Tank and 100-N-45 Office Building Septic Tank make up SWMU #9. Remediation was determined not to be necessary for the 100-N-3 site and the 100-N-41 and 100-N-45 septic sites. The below grade structures of the drain and septic sites were demolished in place and backfilled with soil in 2004.

100-N-4 Tile Field (SWMU#5) - Confirmatory sampling activities and data evaluation determined that remediation was not necessary for the 100-N-4 Tile Field.

100-N-5 Bone Yard (SWMU #10) - Remediation and removal activities for the 100-N-5 Bone Yard (SWMU #10) were primarily conducted in 2001 with the removal of the miscellaneous equipment, metal scrap, and general debris. The limited number of areas with sand blast media, ion exchange resin-like media and areas with soil staining and/or distressed vegetation were remediated in 2003 and 2004. The sand blast, ion exchange resin, and contaminated soil wastes were disposed of at the RABANCO landfill facility in Roosevelt, Washington.

The 100-N-46 Diesel under ground storage tank (UST) was excavated and removed in 2001. Soil contaminated with diesel was also excavated from the UST excavation. Contaminated soil was spread over the demolished 1703-N Office Building concrete slab foundation for attenuation. Upon completion of the remedial excavation, the bottom of the excavation was approximately 6.7 meters (22 ft) below the ground surface at the deepest location (southwest corner of excavation).

100-N-52 Gasoline underground storage tank (UST) was excavated and removed in 1992.

1908-NE Outfall (SWMU#7) - The original preferred remedy for the 1908-NE Outfall was Institutional Controls (continued monitoring). A radiological survey of the Outfall seal well and samples of water and sediment were collected from the Outfall seal well in 2001 to assess potential contamination associated with the Outfall. The outfall structure was demolished by the Washington Closure Hanford D&D organization in 2012, eliminating the Institutional Control requirement.

The 1716-NE Maintenance Garage building (SWMU #8), including the building slab and associated floor drain pipelines, were removed in their entirety during the 2003 and 2004 removal action activities. Prior to the removal action all chemical products were removed from the building and either properly disposed of or transferred to another facility for use. The building debris was used as fill for the 185-N Building basement.

Code:	100-N-80	Classification:	Accepted
Names:	100-N-80; River Line from 1908-NE Outfall	Reclassification	None
Type:	Process Sewer	Start Date:	
Status:	Inactive	End Date:	
Description:	This site includes one, 335-centimeters (132 inches) (2 centimeter (0.75 inch) wall thickness) steel pipeline, extending from the face of the 1908-NE Outfall into the main channel of the Columbia River.		
Location:	The 1908-NE Outfall is located in the 100-N Area, approximately 61 meters (200 feet) downstream of the 181-NE River Pumphouse on the Columbia River at river mile 379.6. The 100-N-80 river effluent pipeline extends from, and is perpendicular to, the face of the 1908-NE outfall structure. The pipeline extends 313 meters (1,028 feet) from the outfall face to its		

discharge point in the Columbia River.

Related Sites/ Structures: The site is associated with the 1908-NE Outfall and the 100-N-1 Settling Pond.

Process Description: The river effluent pipeline received single pass raw river water which had passed through the Hanford Generating Plant (HGP) condensers, as well as waste water from the 100-N-1 Settling Basin. The pipeline contains seven, 20 centimeter (8 inch) vents along its length, and discharges to the river via four, 3.4 meter (11 feet) outlets. The pipeline is buried along its entire length to a depth of at least 1.2 meters (4 feet) with soil, gravel, and riprap.

Waste Type: Process Effluent

Waste Description: The waste includes the pipeline and the potentially contaminated scale and sediment contained within it. The contaminants of concern include cobalt-60, cesium-137, and petroleum hydrocarbons (diesel and heavy oil range hydrocarbons).

Code: 100-N-81

Classification: Accepted

Names: 100-N-81; 100-N Kaiser Shops Garnet Sandblasting Material

Reclassification: Interim Closed Out (5/7/2014)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site was remediated and Interim Closed Out. It consisted of garnet sand and any underlying contaminated soil surrounding the former 1517-N Paint Shop. The garnet sand was purple and covered an area approximately 577 square meters (690 square yards).

Location: The waste site was located at the 1517-N Paint Shop in the Kaiser Shop Area. The Paint Shop was located about 300 meters (1,000 feet) east of the 105-N Reactor facility.

Related Sites/ Structures: The garnet sandblasting operations were likely in support of the 1517-N Fixed Metal Paint Shop mission.

Process Description: The 1517-N Paint Shop was constructed in 1982 (HW-5000, 4/30/1982). It was originally operated by the J.A. Jones Construction Services Company. Kaiser Engineering Hanford (KEH) assumed responsibility for the Paint Shop in 1987 (HW-5000, 6/16/1987). Respiratory protection equipment was stored in part of the building at some point during its operation (CCN 125281). The paint shop was used to store supplies for the craft services painters. Materials needed for various outside jobs are taken from the shop to the job site only in quantities equal to the amount needed for that job or day's work. Unused materials are returned to the shop at the end of each day (WHC-SP-0460).

Paint, solvents, and oils were used at the Paint Shop. There were two waste accumulation areas, one for waste paint and the other for waste oil (DOE/RL-90-22). There was also an associated sandblasting area. An air compressor located east of the paint shop leaked nonhazardous lubrication oil over the years; the surrounding soil is oil-stained. The extent of contamination is unknown. Six drums of contaminated soil were removed (DOE/RL-90-22).

The 1517-N building was demolished in January 2006. Prior to demolition, the extent of the discarded sandblasting grit (garnet sand) was mapped using a global positioning system (GPS). The mapped area in conjunction with a 2004 aerial photograph (04080084-57cn) was used to establish the waste site boundary. The garnet material was stockpiled into the northeast corner of the Kaiser Shop Area in order to prevent its spread during demolition activities (CCN 126707). This stockpiled material falls within the waste site boundary.

Waste Type: Soil

Waste Description: The waste is a red colored granular material. In 2005 a grab sample of the sandblasting waste material was analyzed for metals (J10VC5). The material contained chromium at a level (45.0 mg/kg) exceeding the soil cleanup level (18.5 mg/kg) for protection of groundwater and protection of the river. Contaminants of potential concern have not been established at this time.

Closure Info: Interim (5/7/2014): Remedial action at the 100-N-81 waste site was performed between October 22 and October 31, 2013. The excavation depth ranged from 1 to 2 meters (3.3 to 6.6 ft) bgs resulting in approximately 1,200 bank cubic meters (1,570 bank cubic yards) of soil and debris (garnet sand, concrete, wood, and steel chain-link fencing) removed for disposal at the Environmental Restoration Disposal Facility (ERDF). All material was direct loaded from the excavation into trucks for disposal at the ERDF. Therefore, no waste staging pile area was created and no overburden soil pile associated with the waste site. A boundary survey was conducted following remedial action activities. A glass anomaly was encountered approximately 30 meters (98 ft) north of the 100-N-81 site boundary.

Code: 100-N-82

Classification: Accepted

Names: 100-N-82; 100-N Decontamination Pad

Reclassification: Interim Closed Out (9/9/2014)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The waste site has been remediated and Interim Closed Out. It included the decontamination pad and any underlying soil contamination was found. The decontamination pad had a reinforced (rebar) concrete slab with a center drainage trench and sump. The slab sloped toward the center concrete drainage trench where the water was trapped in the sump. A HDPE liner cover had been installed on top of the decontamination pad to prevent rainwater from entering the trench and sump area (CCN-107899). It was posted with radiological warning signs.

Location: The decontamination pad was located approximately 245 meters (804 ft) northeast of the 1120-N Building.

Related Sites/Structures: The site was related to 1301-N (Sitecode 116-N-1) and 1325-N (Sitecode 116-N-3) cribs and trenches.

Process Description: The decontamination pad was constructed in 2000. It was constructed to support 100-N vehicles and equipment performing remediation work associated with sites 116-N-1 (1301 Crib/Trench) and 116-N-3 Crib/Trench. When a vehicle drove onto the pad, a self-contained steam cleaner, water tank, and pump with suction and discharge hoses was used to decontaminate the vehicle. Runoff water would enter the trench and sump, and, as needed, wash water would be pumped to a tank truck for removal. The pad was covered with a liner upon demobilization to prevent rainwater from entering the trench and sump (CCN-107899).

Waste Type: Equipment

Waste Description: The waste is a contaminated concrete pad. Contaminants of potential concern (COPCs) include Co-60, Cs-134, Cs-137, Pu-238, Pu-239, H-3 and Ru-106.

Closure Info: Interim (9/9/2014): Remediation of the 100-N-82, 100-N Decontamination Pad was performed between March 19 and March 24, 2014. Approximately 194 bank cubic meters (254 bank cubic yards) of excavated materials were removed and direct loaded for disposal at the Environmental Restoration Disposal Facility. The depth of the excavation was approximately 1.5 meters (4.9 ft). Excavated materials included plastic tarp, concrete, railroad ties, steel, rebar, soil, and other miscellaneous debris. The sump located near the center of the decontamination pad was also removed. No soil staining or anomalies were observed during and after the excavation. No

overburden materials were salvaged from the 100-N-82 waste site excavation. There was no overburden pile associated with the 100-N-82 waste site. A 100-N-82 waste site walk around boundary was used to determine the footprint for the 100-N-82 waste site and develop the verification sampling design.

A Global Positioning Environmental Radiological Surveyor (GPERS) survey was conducted within the 100-N-82 waste site open excavation. No radiological contamination was detected above background.

Code:	100-N-83	Classification:	Accepted
Names:	100-N-83; Two Contamination Areas Found Near 116-N-1	Reclassification	None
Type:	Unplanned Release	Start Date:	
Status:	Inactive	End Date:	
Description:	The site consists of two radiologically contaminated areas identified during remediation of 116-N-1 Crib and Trench. The first area is located where an uncontaminated soil stockpile was previously removed. The second area is relatively undisturbed located near and around the eastern end of the former 116-N-1 Trench.		
Location:	The two areas are located along the northeast excavation boundary of the 116-N-1 Crib and Trench. They are bound to the north and east by the security fence shown on drawing 0100N-DD-C0190.		
Waste Type:	Soil		
Waste Description:	The waste is radiologically contaminated soils. The contaminants of potential concern are radiological contaminants.		

Code:	100-N-84	Classification:	Accepted
Names:	100-N-84; 100-N 100-N Miscellaneous Pipelines	Reclassification	Interim Closed Out (10/1/2014)
Type:	Radioactive Process Sewer	Start Date:	
Status:	Inactive	End Date:	
Description:	The parent site is also considered Interim Closed Out. The waste site consisted of all miscellaneous pipelines in the 100-N Area that were identified during the WCH Orphan Site Evaluation (OSE) process that were not associated with an existing waste site. The miscellaneous pipelines supported the reactor operation and related support facilities throughout the N-Area. The waste site had been divided into ten subsites to allow a phased remediation strategy. 100-N-84 includes product pipelines, service water pipelines, sewers and associated features (manholes, storm drains, valve boxes, etc.).		
	The waste site has nine subsites: 100-N-84:1, 100-N Area Raw Water Pipelines; 100-N-84:2, 100-N Area Fuel and Foam Pipelines; 100-N-84:3, 100-N Area Filtered and Potable Water Pipelines; 100-N-84:4, 100-N Area Steam and Condensate Pipeline; 100-N-84:5, 100-N Area Sanitary Pipelines; 100-N-84:6. 100-N Area Chemical and Process Sewer Pipelines; 100-N-84:7, 100-N Area Unidentified and Other Miscellaneous Pipelines; 100-N-84:8, 100-N Area Unidentified Pipelines within Planned Excavations. The tenth subsite, 100-N-84:9, 100-N Area Active Raw Water Pipelines and 100-N-84:10, Miscellaneous Pipelines within the Bioventing Well Island was consolidated with 100-N-107.		
Location:	The pipeline segments are located within the 100-N Area.		

Process Specific process descriptions are contained in the subsite descriptions.
Description:

This Site has the Following SubSites:

- Code:** 100-N-84:1
Names: 100-N-84:1; 100-N Area Raw Water Pipelines
- Code:** 100-N-84:2
Names: 100-N-84:2; 100-N Area Fuel and Foam Pipelines
- Code:** 100-N-84:3
Names: 100-N-84:3; 100-N Area Filter and Potable Water Pipelines
- Code:** 100-N-84:4
Names: 100-N-84:4; 100-N Area Steam and Condensate Pipelines
- Code:** 100-N-84:5
Names: 100-N-84:5; 100-N Area Sanitary Pipelines
- Code:** 100-N-84:6
Names: 100-N-84:6; 100-N Area Chemical and Process Sewer Pipelines
- Code:** 100-N-84:7
Names: 100-N-84:7; 100-N Area Unidentified and Other Miscellaneous Pipelines
- Code:** 100-N-84:8
Names: 100-N-84:8; 100-N Area Unidentified Pipelines within Planned Excavations
- Code:** 100-N-84:9
Names: 100-N-84:9; 100-N Area Active Raw Water Pipelines
- Code:** 100-N-84:10
Names: 100-N-84:10; Miscellaneous Pipelines within the Bioventing Well Island

Code: 100-N-84:1	Classification: Accepted
Names: 100-N-84:1; 100-N Area Raw Water Pipelines	Reclassification: Interim No Action (12/3/2012)
Type: Product Piping	Start Date:
Status: Inactive	End Date:

Description: The subsite has been evaluated and determined to require No Action. It consists of the inactive 100-N Area raw water pipelines including: low pressure water, raw water, raw water return, raw water supply, raw water supply high and low pressure, emergency The lines are raw water supply, sprinkler, vent, fire line, irrigation, fog, and fish line pipelines. They located in various throughout the 100-N Area.

The 100-N Area raw water system was built in 1963 with additional portions added as new support buildings were constructed. Raw water was pumped from the Columbia River at the 181-N Pump House to the 185-N Hanford Generating Plant, the 109-N Heat Exchanger Building, the 182-N High-Lift Pump House, and the 184-N Power House. These large delivery pipelines are not part of the 100-N-84 waste site. The subsite includes pipelines between the 105-N Reactor Building and it's supporting facilities.

The pipelines exiting the 182-N Building transferred raw water to the 105-N, 109-N, 163-N and 183-N Buildings. At the 182-N Building, raw water was passed through screens before it was

stored in 18.6 meter (61 ft) deep, independent pump suction wells for future distribution. Raw water supplied to the 109-N Heat Exchange Buildings supported the dump-condensers, graphite cooling heat exchangers and turbine surface-condensers. Additionally, raw water was supplied to the 182-N Building emergency raw water tank and various heat exchangers, along with the 100-N Area irrigation and fire systems. The fire system pipelines originating at the 182-N supported the 185-N Hanford Generating Plant and substation located outside of the 100-N Fenced area. Raw water from the 109-N and 184-N buildings could also be returned to the Columbia river through the Sealwell.

The pipelines located between the 109-N, 182-N, 163-N and the 183-N Buildings lay within the 100-N-61 water treatment pipeline removal excavation footprint (H-1-89933). This area was excavated and backfilled in 2008 through 2009. Raw water lines collocated with 105-N Reactor Treatment Storage and Disposal Underground Pipelines along the east side of the 109-N and 105-N Buildings lay within the 100-N-63 excavation footprint (H-1-89933). This area was excavated and backfilled in 2009.

Location: The large majority of the pipelines being located in and around the 182-N High-Lift Pump House, 163 Demineralization Plan, 183-N Water Filter Plant, 184-N Power House, the 185-N Hanford Generating Plant, 109-N Heat Exchanger Building and many office buildings and trailers located to the south and south east of the 105-N Reactor Building. One additional 12-inch raw water line, used for temporary construction, is located in the northeastern portion of the 100-N area and connects to the export water pipeline.

Closure Info: Interim (12/3/2012): Confirmatory samples were collected from test pits at nine locations on the 100-N-84:1 subsite between March 8 and July 19, 2012 to support an evaluation to determine if residual contaminant concentrations in the soil meet cleanup criteria. The 100-N-84:9 pipelines are still active while the 100-N-84:1 pipelines have been taken out of service and/or removed. Both subsite pipelines carried the same type of raw water. Therefore the confirmatory sampling conducted at the inactive 100-N-84:1 has been used to evaluate and support the 100-N-84:9 reclassification.

The SubSite is Part Of:

Code: 100-N-84

Names: 100-N-84; 100-N 100-N Miscellaneous Pipelines

Code: 100-N-84:2

Classification: Accepted

Names: 100-N-84:2; 100-N Area Fuel and Foam Pipelines **Reclassification** Interim Closed Out (8/13/2014)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. It included the fuel oil and fire suppression foam, underground pipelines located on the northwest and west side of the 105-N Reactor Building. In addition to the pipelines, the subsite also included a fuel oil unloading facility that was used to unload both fuel oil (No. 6 fuel oil also known as Bunker C) and diesel oil (No. 2 fuel oil).

The fire suppression foam lines that supported the diesel oil tanks and pipelines were co-located with the diesel oil pipelines near the 166-N Building. The northwest portions of the 100-N-84:2 pipelines were located within the 100-N-63 excavation footprint (H-1-89933).

Location: Fuel and fire suppression foam underground pipelines were located in the 100-N Area, on the northwest and west side of the 105-N Reactor Building.

Related Sites/ Structures: UPR-100-N-17, UPR-100-N-18, UPR-100-N-19, UPR-100-N-20, UPR-100-N-21, UPR-100-N-22, UPR-100-N-23, UPR-100-N-36, UPR-100-N-42, and UPR-100-N-43.

Process Description: Diesel oil was used to fire the igniters in the boilers and to fuel the diesel-driven emergency low-lift, high-lift, and fog spray pumps. Bunker C was used as fuel for the 184-N boilers. Bunker C fuel oil was stored in a 5,204,925 liters (1,375,000-gal) capacity above-ground storage tank and transferred through underground lines to the two 184-N fuel oil day tanks. Two fuel oil unloading, storage and transfer systems were used in the 100-N Area. Diesel oil unloaded from rail cars at the 166-N unloading station was transferred for storage to the one of four aboveground storage tanks within the 1715-N Building. The diesel oil was then transferred through a 10.2 cm (4-in) underground supply pipeline to the 184-N Building day tank or through 5.1 cm (2-in) and 10.2 cm (4-in) underground pipelines to the three 56,781 liters (15,000 gal) day tanks outside of the 182-N building. The diesel fuel from the 182-N day tanks was used to support the 182-N and 181-N diesel oil systems. Number 6 fuel oil (also known as Bunker C fuel oil) was unloaded from rail cars at the 1900-N unloading station and transferred to the 166-N Building for storage in a 5,204,941 liters (1,375,000 gal) capacity aboveground storage tank. The No. 6 fuel oil was transferred through underground pipelines from 166-N to two 184-N fuel oil day tanks.

Waste Type: Soil

Waste Description: The waste is the pipeline (if present), scale, sediment, or liquid present within the pipelines, and the underlying soil.

Closure Info: Interim (8/13/2014): Demolition of the 166-N facilities included removal of the fuel oil (Bunker C) tank in January 2006 and removal of the 166-N Pump House and the 166-N Unloading Station in April 2006. The four 1715-N diesel tanks were removed during prior demolition work approximately 10 years earlier, leaving the tank foundations to be removed during the 2006 demolition. The contaminated soil associated with the 166-N facilities to the Field Remediation (FR) Closure Project for remediation.

The D4 Closure Project removed many of the 100-N-84:2 pipelines during facility demolition work that began in 2006 and continued through 2012. In some instances, the pipelines were removed at locations where they entered buildings and tanks. Field remediation of co-located waste sites removed portions of some pipelines during waste site excavation. Prior to removal, the pipelines were drained and the oil collected for waste disposition. It is estimated that over the past 7 years, approximately 3,030 L (800 gal) each of diesel and Bunker C had been drained from the pipelines.

Remediation of the 100-N-84:2 subsite began April 6, 2013, and was completed in March 21, 2014. The depth of the excavation after removal of the pipelines varied based upon the amount of excavation necessary to remove soil staining and petroleum contamination. In general, the pipeline excavations did not extend deeper than 4.9 meters (16 ft) below surface grade. Approximately 41,710 bank cubic meters (54,555 bank cubic yards) of petroleum-contaminated soil was removed for disposal at the Environmental Restoration Disposal Facility (ERDF).

No petroleum contamination or evidence of any release of petroleum was observed in soil associated with the 100-N-84:2 pipelines that ran from the fuel unloading station to the 181-N and 182-N facilities. In agreement with the Washington State Department of Ecology and the U.S. Department of Energy, the excavation associated with the pipelines in this area could be backfilled and no verification sampling was needed.

Significant petroleum-stained soil was present below 4.6 meters (15 ft) depth at the location where the 100-N-84:2 Bunker C and diesel pipelines entered the 166-N pump house and the Bunker C storage tank. A test pit was excavated and sampled on November 20, 2013, to a depth of approximately 9.4 meters (31 ft) bgs, at the location of the worst staining, to evaluate the

vertical extent of petroleum contamination and support decisions concerning the need for additional remediation. Heavily stained petroleum-contaminated soil was noted in the material that was excavated from this test pit and the contamination continued to be present at the base of the test pit (9.4 meters [31 ft] bgs). This petroleum contamination is suspected to be mostly Bunker C and may include weathered, aged diesel. This information was used to support assignment of this portion of the 100-N-84:2 subsite, located below 4.6 meters (15 ft), to the UPR-100-N-17 waste site for in situ bioremediation. The soil contamination in Test Pit #4 was located near the UPR-100-N-17 bioventing wells and was within the air injection radius of influence for the bioremediation system.

The waste site was divided into three sample Areas. Test Pits 1, 2 and 3 were excavated within Area 2, where the highest concentrations and staining of petroleum was observed at the base of the excavation. Test Pit 4 was excavated in Area 3, where heavily stained petroleum-contaminated soil was observed on the floor of the excavation.

Petroleum contamination was not detected above cleanup criteria in soil samples below a depth of approximately 6.7 meters (22 ft) in Test Pits 1, 2, and 3. The petroleum had not migrated deeper than 6.7 meters (22 ft) below ground surface at test pits 1, 2, and 3, indicating that petroleum was not present in groundwater at these test pit locations. However, the petroleum contamination remained present with depth in soil samples collected from Test Pit 4.

The SubSite is Part Of:

Code: 100-N-84

Names: 100-N-84; 100-N 100-N Miscellaneous Pipelines

Code: 100-N-84:3

Classification: Accepted

Names: 100-N-84:3; 100-N Area Filter and Potable Water Pipelines

Reclassification: Interim No Action (11/5/2012)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The 100-N-84:3 subsite has been evaluated and determined to require No Action. The 100-N Area filter and potable water pipelines include makeup water, filter water, demineralized water, and potable water pipelines.

Location: Filtered water lines are located to the north and south of the 105-N reactor Building. The potable water lines are located mainly to the southwest of the 105 reactor building connecting to the 105-N support facilities.

Process Description: Raw water was supplied to 183-N Filter Plant Building for pretreatment and filtration. The 183-N filter plant supplied sanitary water to the entire 100-N Area. The plant also supplied filtered water to various buildings throughout the 100 N Area for use where treated water was not desirable or required. During treatment, liquid alum (aluminum sulfate), Separan (polyacrylamide coagulant), and liquid chlorine were added. Chlorine was added for the control of slime and algae and may have been used to assist in coagulation, odor, and iron removal problems.

During treatment, liquid alum (aluminum sulfate), Separan (polyacrylamide coagulant), and liquid chlorine were added. Chlorine was added for the control of slime and algae and may have been used to assist in coagulation, odor, and iron removal problems. The alum used at 183-N contained trace amounts of naturally occurring radium-226, radium-228, and thorium-228, which may have resulted in formation of Technologically Enhanced Naturally Occurring Radioactive Material (TENORM). Previously, to determine if TENORM was present, a number

of samples downstream of the 183-N chemical mixing tank were collected and subsequently evaluated in the document Post Demolition Summary Report for the 163-N Water Demineralization Plant, 183-N Water Treatment Plant, 183-NA Pump House, 183-NB Clearwell, and the 183-NC Filter Backwash Sump. The evaluation of those samples found no detectable amounts of radioactive contamination.

Demineralized water from 163-N Building was used as makeup water feed for the pretreatment system in 183-N building, while raw water was used for chemical mixing in the 182-N and 183-N Buildings prior to being added to the water. The chemical feed systems were maintained using proportional ratios with the water flow. Demineralized water was used to prevent mineral deposits what would foul pipeline systems. Chlorine was added for the control of slime and algae, and may have been used to assist in coagulation, odor and iron removal problems. Alum was used as the principle coagulant during pretreatment. 100-N-84:3 pipelines located between the 109-N, 182-N, 163-N and the 183-N Buildings lay within the 100-N-61 water treatment pipeline removal excavation footprint (H-1-89932). This area was excavated and backfilled in 2008 through 2009. The north west portions of the 100-N-84:3 pipelines are located within the 100-N-63 excavation footprint (H-1-89933).

Waste Type: Soil

Waste Description: The waste is the pipeline (if present),scale, sediment, or liquid present within the pipelines, and the underlying soil.

Closure Info: Interim (11/5/2012): The 100-N-84:3 pipelines located between the 109-N, 163-N, 181-N, 182-N, 183-N, and 184-N Buildings are co-located with 100-N-61 (100-N Water Treatment and Storage Facilities Underground Pipelines), the 100-N-62 (100-N, 105-N, 109-N, 183-N, and 184-N underground pipelines) and 100-N-63 (100-N Reactor Treatment Storage and Disposal Underground Pipelines). The portions of the 100-N-84:3 pipelines that lay within the 100-N-61 and 100-N-63 excavation footprint will be removed during the excavation of these sites and were not identified for confirmatory sampling during the 100-N-84:3 activities.

Eleven Test Pits were dug. Confirmatory samples were collected from Test Pits 3, 6, 8, and 10. No indications of previous spills or releases associated with the 100-N-84:3 pipelines were detected during confirmatory sampling. The 100-N-84:3 data set indicates elevated polycyclic aromatic hydrocarbons (PAH) in samples from two of the collection areas. The ground surface in much of the 100-N Area was covered with asphalt. Remnants of asphalt are visible on the surface and in excavations in various areas and are thought to be responsible for the PAH results. Also, many of the pipelines are covered in an asphalt mastic coating. Mechanical methods recently employed to access sample materials may also have resulted in small particles of asphalt becoming incorporated in the samples.

The SubSite is Part Of:

Code: 100-N-84

Names: 100-N-84; 100-N 100-N Miscellaneous Pipelines

Code: 100-N-84:4

Classification: Accepted

Names: 100-N-84:4; 100-N Area Steam and Condensate Pipelines

Reclassification Interim Closed Out (9/9/2014)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. It included the 100-N Area steam, condensate, injection and vacuum pump water pipelines located near the reactor building and support facilities. 100-N-103:1 French Drains 9, 10 and 11 were deferred to 100-N-84:4

because they were within the planned pipeline remediation footprint or were removed during previous demolition and removal of the 105-N control room structure. The French drain #9 structure was removed during demolition of the 105-N Control Room structure.

Location: The steam and condensate pipelines are concentrated around the 105-N Reactor building to support facilities and the 185-N Hanford Generating Plant.

Related Sites/ Structures: Some of the 100-N-84:4 pipelines are associated with 100-N-61:4.

Process Description: The 100-N Reactor excess steam was used to generate electricity from 1966 to January 7, 1987. Condensate from the dump condensers was routed back to steam generators for regeneration. The main steam system was designed to distribute steam generated from generators on the roof of the 109-N Building as high, medium and low pressure steam. High pressure steam was exported through a 71 cm (28-in) pipeline to the 184-N Building to support the turbine generator and miscellaneous services. Medium pressure steam was distributed from 109-N for area heating (105-N, 182-N, 163-N, 183-N, 108-N, 1704-N, 1716-N, and 1734-N) and additional miscellaneous services. Low pressure steam was exported to the 184-N and 153-N Buildings for unit heaters and convectors. Stand-by boilers located 184-N were maintained independent of reactor operation supplying steam to the 184-N day tanks, the 166-N fuel unloading facilities and for the 109-N emergency seal water turbines. Once the steam had been utilized in each building condensate return pipelines exported the 184-N Building condenser receiver where it is re-circulated de-aerating heater for reuse. 109-N Building was equipped with a condensate diversion station controlling the levels in the de-aerated water storage tank.

A 10" condensate emergency drain could be used to release condensate from 109N to the 0.17 meters (66-in) raw water pipelines downstream of the Sealwell.

Waste Type: Soil

Waste Description: The waste is the pipeline (if present), scale, sediment, or liquid present within the pipelines, and the underlying soil.

Closure Info: Interim (9/9/2014): Confirmatory sampling was conducted in June and July 2011. No elevated radionuclides or industrial hygiene readings were detected at any of the eight test pits. Therefore, volatile organic analysis, gamma energy analysis, and gross alpha and gross beta analyses were not performed for any of the confirmatory samples.

Three french drains (formerly part of the 100-N-103:1) were added to the 100-N-84:4 subsite because they were within the planned layback of the 100-N-84:4 pipeline remediation. French drain 9 was removed during demolition activities performed in 2009. French drains 10 and 11 were removed and disposed with the remediation of the 100-N-84:4 pipeline subsite. Several segments of the 100-N-84:4 pipeline subsite were removed with previous waste site remediations. These segments were evaluated in the RSVP-2011-118 document.

The remediation of the 100-N-84:4 subsite was performed from December 2, 2013, through February 24, 2014. The depth of the remediation ranged from approximately 1.5 to 5 meters (4.9 to 16.4 ft) below ground surface, resulting in approximately 4,100 bank cubic meters (5,363 bank cubic yards) of soil and pipeline debris being removed for disposal at the Environmental Restoration Disposal Facility (ERDF). All waste material was loaded directly from the excavation into ERDF containers for disposal. No waste staging pile or overburden areas were created for the 100-N-84:4 subsite. Several in-process soil samples were collected from the 100-N-84:4 pipeline subsite during and at the completion of site remediation.

The SubSite is Part Of:

Code: 100-N-84
Names: 100-N-84; 100-N 100-N Miscellaneous Pipelines

Code: 100-N-84:5 **Classification:** Accepted
Names: 100-N-84:5; 100-N Area Sanitary Pipelines **Reclassification** Interim Closed Out (9/9/2014)
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The subsite has been remediated and Interim Closed Out. It included the 100-N Area sanitary pipelines that includes sanitary water, sewer, storm drains, and drain field pipelines. These pipelines included a variety of diameters of pipe ranging from 0.75 in. to 20 in. and were composed of cast iron, concrete, vitrified clay, or steel.

Location: The 100-N-84:5 pipelines are located throughout the 100-N Area's 100-NR-1 operable unit.

Process Description: The 100-N Area was serviced by ten separate sewer systems consisting of one cesspool, one lagoon, one septic tank with an associated tile field, two septic tanks with seepage pits, and five septic tanks associated with drain fields. The septic tanks, pits, cesspools and lagoon are identified as the 124-N-1 through 124-N-10 waste sites. Waste sites 124-N-5, 124-N-6, 124-N-7, 124-N-8 have been reclassified as "rejected". The feed and drainage pipelines associated with these waste sites are included in 100-N-84:5.

Waste Type: Soil

Waste Description: The waste is the pipeline (if present), scale, sediment, or liquid present within the pipelines, and the underlying soil.

Closure Info: Interim (9/9/2014): Portions of the 100-N-84:5 subsite were removed by the Deactivation, Decontamination, Decommissioning, and Demolition (D4) Project in support of the demolition and removal of the 100-N river structures. Installation of a haul road was necessary to gain access to the structures. Therefore, segments of the 100-N-84:5 pipelines that were located within the roadway boundary were removed and disposed. The segments of pipeline associated with the Bonneville Power Administration (BPA) substation are active and expected to remain active for many years. These segments of pipeline were removed from the 100-N-84:5 subsite description. They will be dispositioned with the BPA substation at a future time.

The Field Remediation Closure Project continued the remediation of the 100-N-84:5 subsite from July 8, 2013, through February 28, 2014. The depth of the remediation ranged from approximately 1.5 to 4 meters (4.9 to 13 ft) below ground surface. Approximately 13,534 bank cubic meters (17,702 bank cubic yards) of soil and pipeline debris being removed for disposal at the Environmental Restoration Disposal Facility (ERDF). Some waste material was staged prior for loadout and disposal. A waste staging pile area (SPA) was generated. No overburden material was stockpiled for use as clean backfill. Two segments of the 100-N-84:8 subsite (segments 8 and 12) were located within the 100-N-84:5 subsite excavation. Both segments were removed and disposed at ERDF. Two pneumatic cylinders were found during the waste site remediation. These items were not considered anomalies and were disposed at ERDF. No anomalous material or stained soil was observed during the remediation.

Several segments of the 100-N-84:5 pipelines were approved to be left in place. These pipeline segments were not remediated and subsequently were not included in the verification sample design. Several in-process soil samples were collected from the 100-N-84:5 pipeline subsite during and at the completion of site remediation.

The SubSite is Part Of:

Code: 100-N-84
Names: 100-N-84; 100-N 100-N Miscellaneous Pipelines

Code: 100-N-84:6 **Classification:** Accepted
Names: 100-N-84:6; 100-N Area Chemical and Process Sewer Pipelines **Reclassification:** Interim Closed Out (10/1/2014)
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The subsite has been remediated and Interim Closed Out. It included the 100-N Area Chemical and Process Sewer Pipelines. The lines carried chemical waste, a dummy disposal line and a radioactive drain line. The 100-N-103:1 French Drain 1 is also addressed with the pipelines in 100-N-84:6. The pipelines associated with the 100-N-23 resin pit are part of the 100-N-84:6 subsite.

Location: The 100-N-84:6 waste site pipelines were centrally located between the 100-N Area process buildings (105-N, 109-N, 182-N, 183-N, 184-N, and 163-N).

Related Sites/Structures: Only one pipeline was visually observed at 100-N-23 during site walkdowns done in 2011. Some of the 100-N-84:6 pipelines are associated with 100-N-61:4.

Process Description: The 100-N-84:6 pipelines originate from the 109-N Heat Exchanger Building, the 105-N Reactor Building, the 163-N Demineralization Plant, 182-N High-Lift Pump House, 183-N Filter Plant, and 184-N Power House. Various chemicals were utilized in these buildings. Phosphoric, ascorbic and citric acids, and potassium permanganate were used in the 109-N and 105-N Buildings decontamination processes (WHC-SP-0460). Ammonium hydroxide, morpholine and lithium hydroxide were added to control cooling water pH. Hydrazine was added to reduce oxygen concentrations in cooling water (WHC-SP-0460). The addition of these chemicals and the core's cooling water system design allowed the water to be recycled instead of using raw water as a once through coolant (DOE/RL-90-22).

Sulfuric acid and sodium hydroxide from supply tanks in 163-N Building were primarily consumed in the demineralizer plant. A 93% sulfuric acid solution was used to regenerate the cation resin used at the 163-N Building while a 50% sodium hydroxide solution was used to regenerate the anion resin. The 8-inch acid drain from 163-N connected into the 100-N river channel discharge line to the Columbia River. Sodium sulfite was used as a deoxygenizing chemical for low pressure filter water (182-N). Sodium dichromate was added to filtered water supply and raw water supply for cooling coils in the 105-N Reactor Building.

Radioactive drains at 109-N collect from the coolant systems, hot water quality laboratory, service bay hot shop. The 105-N and 109-N drains run to the 1301-N Liquid Waste Disposal Crib. 100-N-84:6 pipelines located between the 109-N, 182-N, 163-N and the 183-N Buildings lay within the 100-N-61 water treatment pipeline removal excavation footprint (H-1-89932). This area was excavated and backfilled in 2008 through 2009. A small portion of the 100-N-84:6 pipelines also lay within the adjacent 100-N-64 planned excavation (H-1-89934).

Waste Type: Soil

Waste Description: The waste is the pipeline (if present), scale, sediment, or liquid present within the pipelines, and the underlying soil.

Closure Info: Interim (10/1/2014): Portions of the 100-N-84:6 subsite were removed by the Deactivation, Decontamination, Decommissioning, and Demolition Project (D4) in support of the removal of the 100-N river structures. Installation of a haul road was necessary to gain access to the structures. Segments of the 100-N-84:6 pipeline that were located within the roadway boundary

were removed and disposed. A verification soil sample (J1J4H9) and a duplicate sample (J1J4J0) were collected per an approved sampling agreement with the Washington State Department of Ecology (Ecology) and the excavation was backfilled. Several segments of the 100-N-84:6 pipeline subsite were removed with previous waste site remediations. Two segments of the 100-N-84:6 pipelines were approved to be left in place per an agreement with Ecology. Segment 16 of the 100-N-84:8 pipeline subsite was removed and disposed with the 100-N-84:6 remediation.

French drain 1 (formerly part of the 100-N-103:1), was removed during the demolition of the 108-N Building. The french drain was added to the 100-N-84:6 pipeline subsite because it was within the planned excavation footprint of the 100-N-84:6 pipeline remediation.

Remediation of the 100-N-84:6 subsite continued from April 10, 2013 through March 4, 2014. The depth of the remediation ranged from approximately 1.0 to 2.0 meters (3.3 to 6.7 ft) below ground surface, resulting in approximately 3,447 bank cubic meters (4,509 bank cubic yards) of soil and pipeline debris being removed for disposal at the Environmental Restoration Disposal Facility (ERDF). The pipeline debris includes steel pipe, concrete, rebar, wood, Gilsulate bedding material, asphalt, wire, and asbestos. Figure 4 shows the 100-N-84:6 pipeline remediation where it intersects with the UPR-100-N-31 waste site. There were no overburden soil stockpiles or waste staging pile areas associated with the 100-N-84:6 subsite.

Two empty, smashed, and rusted drums and a section of irrigation pipeline covered in friable asbestos insulation were encountered during the remediation. These items were not considered anomalies and were disposed of at ERDF. No anomalous material or stained soil was observed during the remediation.

The SubSite is Part Of:

Code: 100-N-84

Names: 100-N-84; 100-N 100-N Miscellaneous Pipelines

Code: 100-N-84:7

Classification: Accepted

Names: 100-N-84:7; 100-N Area Unidentified and Other Miscellaneous Pipelines

Reclassification: Interim No Action (5/16/2012)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This subsite has been evaluated and reclassified to No Action. The 100-N-84:7 waste site pipelines include sections of various diameter pipelines located within the 100-NR-1 operable unit in and around the 105-N Reactor Building. These sections described as unidentified or multitube could not be positively identified based on review of historical documentation. The pipelines described as multitube are lateral airlines that extend from the 184-N Building to pressure reducing stations. They supplied dry, oil-free, compressed air to the control and instrumentation systems for the water pretreatment plant and the demineralization plant as part of the instrument control air system.

An above ground feature, labeled N-213, was observed during the 100-N Orphan Site Evaluation (OSR-2009-0001). Since it was co-located with the 100-N-84 pipelines, it was decided to incorporate this feature into this subsite.

Location: The 100-N-84:7 pipelines are located throughout the 100-N Area's 100-NR-1 operable in and around the 105-N Reactor Building.

Waste Type: Soil

Waste Description: The waste is the pipeline (if present), scale, sediment, or liquid present within the pipelines, and the underlying soil.

Closure Info: Interim (5/16/2012): Confirmatory sampling was performed in fifteen test pits, between June 27 and July 2, 2011. Suspect asbestos material was found in Test Pit 3. Diesel fumes were noted in Test Pit 5. No samples were collected from Test Pits 2, 4, 6, 7, 8, 10, 11, 12, 13, 14 or 15.

Subsequent to the sample design preparation, additional information regarding the process history of the multitubes that make up a portion of the 100-N-84:7 subsite test pits was obtained. The multitubes are part of an instrument CAS designed to supply dry, oil-free compressed air to the control and instrumentation systems for the water pretreatment plant and the demineralization plant. Therefore, the multitube test pit locations were removed from the confirmatory sampling activities because they were not considered dangerous or hazardous waste. These test pits included 6, 11, 12, 13, and 15.

The 100-N-84:7 pipelines are located throughout the 100-N Area. Due to changing conditions from ongoing other remediation and facilities demolition activities, some pipeline segments were identified to be removed from this scope and combined with other waste sites scheduled for remove, treat, and dispose (RTD) actions. Therefore, test pits include 4, 7, 8, and 14 were excluded.

The pipeline segment at Test Pit 7 was inaccessible for confirmatory sampling due to field activities, and was subsequently removed with the 117-N building.

The pipeline segments at Test Pit 4 and Test Pit 8 will be removed with the remediation of the 100-N-84:5 pipeline waste site.

The pipe at the Test Pit 5 location was uncovered at a depth of approximately 1.2 meters (4 ft). Diesel fumes were noted when the pipe was cut. However, there was nothing inside the pipe to sample. A soil sample (J1JDF9) was collected at a depth of approximately 1.5 meters (5 ft) and analyzed for ICP metals, mercury, hexavalent chromium, SVOCs, polycyclic aromatic hydrocarbons, total petroleum hydrocarbons (TPHs), PCBs, pesticides, volatile organic compounds, gross alpha, gross beta, and by gamma energy analysis. The sample results exceeded direct exposure soil cleanup levels for benzo(a)pyrene. In addition, the groundwater and river protection RAGs were exceeded for benzo(a)anthracene, benzo(b)fluoranthene, benzo(k)fluoranthene, and chrysene. The pipe within Test Pit 5 is in the vicinity of the 100-N-84:2 pipeline subsite, which is scheduled for RTD. The pipeline segment from Test Pit 5 will be removed and documented with the 100-N-84:2 pipeline. The Test Pit 14 location will also be included with the 100-N-84:2 pipeline waste site.

The analytical results indicate that the residual concentrations of contaminants considered at the test pits meet the RAOs for direct exposure, groundwater protection, and river protection. In accordance with this evaluation, the confirmatory sampling results support a reclassification of the 100-N-84:7 subsite to No Action.

The SubSite is Part Of:

Code: 100-N-84

Names: 100-N-84; 100-N 100-N Miscellaneous Pipelines

Code: 100-N-84:8

Classification: Accepted

Names: 100-N-84:8; 100-N Area Unidentified Pipelines within Planned Excavations

Reclassification: Interim No Action (4/2/2014)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive**End Date:**

Description: The 100-N-84:8 waste site has been evaluated and determined to require No Action. It includes seventeen sections of various diameter pipelines located within the 100-NR-1 operable unit in and around the 105-N Reactor Building. These pipe sections are described as unidentified or multi-tube could not be positively identified based on review of historical documentation. Most are believed to be less than 4 meters (13 ft) long or are within the planned remedial action excavation area which will result in removal of the pipeline section. Pipe Segments that were removed with other waste site excavations include segments 1,2,3,4,5,8,12,14,15,16 and 17. Pipe Segments 6,7, 9, 10, 11 and 13 were left in place with No Action required.

Two of the pipeline sections included in the 100-N-84:8 waste site are longer than 4 meters (13 ft). However these pipeline sections lay completely within the planned remediation excavation of the UPR-100-N-21 and UPR-100-N-23 waste sites (H-1-89916), and 100-N-22 waste site (H-1-89924). An above ground feature, labeled N-218, was observed during the 100-N Orphan Site Evaluation (OSR-2009-0001) to be co-located with the 100-N-84 pipelines. As a consequence, this feature was dispositioned as part of 100-N-84.

Location: The 100-N-84:8 pipeline segments are located throughout the 100-N Area's 100-NR-1 operable in and around the 105-N Reactor Building.

Waste Type: Soil

Waste Description: The waste is the pipeline (if present),scale, sediment, or liquid present within the pipelines, and the underlying soil.

Closure Info: Interim (4/2/2014): The subsite consists of 17, previously unidentified, pipeline segments that were located throughout the area north and east of the 105-N Reactor Building. On historical drawings, these pipeline segments are labeled as "Unidentified" or had no labeling. Eleven of the 17 pipeline segments are located within completed or planned excavations. The remaining pipeline segments are associated with systems that serviced administrative offices or buildings that did not store or generate any hazardous or radioactive substances. Based on the review of historical drawings, process knowledge of adjacent waste sites and buildings, and the general location of these segments, it was concluded that contamination would not exist within these pipeline segments. Therefore, the remaining 100-N-84:8 subsite pipeline segments (6, 7, 9, 10, 11, and 13) are being left in place with No Action required.

It was determined that confirmatory sampling test pit excavations of the short sections of pipelines would result in the majority of the length of the pipeline segments being excavated. Therefore, the 100-N-84:8 subsite was recommended for remove, treat, and dispose without confirmatory sampling evaluation. However, because most of the pipeline segments are being removed with other excavations and it was concluded that contamination would not exist within the remaining pipeline segments, no action is required.

Pipe Segments that were removed with other waste site excavations include segments 1,2,3,4,5,8,12,14,15,16 and 17.

Pipe Segments 6,7, 9, 10, 11 and 13 were left in place with No Action required.

The SubSite is Part Of:

Code: 100-N-84

Names: 100-N-84; 100-N 100-N Miscellaneous Pipelines

Code: 100-N-84:9

Classification: Accepted

Names: 100-N-84:9; 100-N Area Active Raw Water

Reclassification Interim No Action (12/3/2012)

 Pipelines
Type: Product Piping**Start Date:****Status:** Active**End Date:**

Description: The subsite has been evaluated and determined to require No Action. The 100-N Area active raw water pipelines range in size from 6 to 12 inches in diameter and are used for fire protection. The 100-N export water line (12 inch) is fed from the main 42 inch raw water export line located between 100-B and 100-D Areas. Smaller pipeline segments connect this line to various fire hydrants located in the 100-N industrial area.

Location: The 100-N-84:9 pipelines are located east of the 105-N Building.

Process Description: Raw water was pumped from the Columbia River and supplied to the fire protection pipelines.

Waste Type: Soil

Waste Description: The waste is the pipeline (if present), scale, sediment, or liquid present within the pipelines, and the underlying soil.

Closure Info: Interim (12/3/2012): Confirmatory samples were collected from test pits at nine locations on the 100-N-84:1 subsite between March 8 and July 19, 2012 to support an evaluation to determine if residual contaminant concentrations in the soil meet cleanup criteria. The 100-N-84:9 pipelines are still active while the 100-N-84:1 pipelines have been taken out of service and/or removed. Both subsite pipelines carried the same type of raw water. Therefore the confirmatory sampling conducted at the inactive 100-N-84:1 has been used to evaluate and support the 100-N-84:9 reclassification.

The SubSite is Part Of:**Code:** 100-N-84**Names:** 100-N-84; 100-N 100-N Miscellaneous Pipelines**Code:** 100-N-84:10**Classification:** Accepted**Names:** 100-N-84:10; Miscellaneous Pipelines within the Bioventing Well Island**Reclassification:** Consolidated (4/2/2014)**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:**

Description: Subsite 10 was consolidated into the 100-N-107 waste site. It is the miscellaneous pipelines located in the Bioventing Wells island.

This Site Was Consolidated With:**Code:** 100-N-107**Names:** 100-N-107; Bioventing Well Islands; Soil Contamination Adjacent to Bioventing Wells**The SubSite is Part Of:****Code:** 100-N-84**Names:** 100-N-84; 100-N 100-N Miscellaneous Pipelines**Code:** 100-N-85**Classification:** Accepted**Names:** 100-N-85; Gas Station Fuel Tanks**Reclassification:** Interim Closed Out (9/25/2015)

Type: Unplanned Release**Start Date:****Status:** Inactive**End Date:**

Description: This site has been remediated and Interim Closed Out. The waste site consisted of soil contaminated with gasoline and diesel that remained after the removal of two underground fuel storage tanks located at the former 1716-N Service Station.

Location: The tanks were located approximately 31.2 meters (102.4 ft) northwest of 1100-N (H-1-45007, sheet 42).

Related Sites/ Structures: 100-N-52 is the Hanford Generating Plant (HGP) gasoline tank.

Process Description: The original tank (100-N-SS-27) was installed in 1967 (WCH 147703 and WHC-SD-L044-CDR-001, Rev. 0). If the tank was originally installed in 1967, it may have been located at the 1716-N Garage Facility. This facility included a Gas Attendant's building and gasoline pumps (according to the official Hanford Atomic Product Operation Buildings List HW-5000 7/25/1967). A self-service gasoline station, 1716-NA, was established in 1972. The Gas Attendant's building and gasoline pumps were relocated to the self service gasoline station at that time. A second gasoline tank (100-N-SS-28) was installed at 1716-NA in 1976 (H-1-15635).

Tank 100-N-SS-27 was an 11,356 L (3000 gal), single wall, 0.48 cm (3/16 in) carbon steel tank with asphalt coating, buried approximately 1.8 meters (6 ft) below grade. The tank was used for regular leaded gasoline storage until 1987, when it began storing unleaded gasoline. The tank was removed from service in June 1990 when it failed a tightness test and a leak was found near the top of the tank. It was subsequently removed from the ground on December 18, 1990, and confirmed to be a release site. The underlying soil was sampled on the same day, and field screening with an organic vapor monitor revealed 200-350 ppm concentration of organic vapor. Approximately 7.6 meters (25 ft) of supply pipeline was also removed (WHC-SD-EN-TI-136).

Tank 100-N-SS-28 was a 7571 liters (2000 gal), single wall, 0.48 cm (3/16 in) carbon steel tank, buried 1 meter (3 ft) below grade (H-1-15635). The tank was originally used for diesel fuel storage and later converted to gasoline. It was removed from the ground on July 17, 1991 (WHC-SD-EN-TI-136). Contamination was believed to be the result of occasionally overfilling these tanks, a loose pipe connection on the delivery line leading from the tank to the pump island, as well as a reported release of 337 liters (89 gal) on January 18, 1988 (WHC-SD-EN-TI-136, appendix C-1). The soil is contaminated to an approximate depth of 11 meters (36 ft) below grade (WHC-SD-EN-TI-136). The lateral extent of the contamination is not documented.

Waste Type: Soil

Waste Description: The waste is soil contaminated with gasoline and/or diesel fuel from underground storage tanks and associated piping. Soil samples obtained from beneath the tanks indicated toluene (4.7 mg/kg), diesel range organics (1,000 mg/kg) and kerosene range organics (3,085 mg/kg) contamination (WHC-SD-EN-TI-136, Table 2).

Closure Info: Interim (9/25/2015): After failing a tank-tightness test, UST 100-N-SS-27 was removed in December 1990. Soil contaminated with petroleum products was detected in the excavation during the UST 100-N-SS-27 tank removal. As much of the contaminated soil as possible was removed without disturbing tank 100-N-SS-28, which was still in service at the time (WHC 1993, BHI 1995). Tank 100-N-SS-27 was closed in accordance with Washington State Department of Ecology (Ecology) requirements.

Tank 100-N-SS-28 was removed on July 17, 1991. Soil contaminated with petroleum products was detected during removal of this tank. Excavation of the contaminated soil was resumed in September 1991, to a depth of 7.6 meters (25 ft), where backhoe limitations prevented further

work. There was no indication that the extent of the contamination plume had been determined. Work was abandoned at this time pending further evaluation. In April 1992, additional soil was excavated to a reported depth of 10 meters (36 ft). Soil contaminated with weathered gasoline and diesel fuel was still detected in a sand lens in the excavation. These soils could not be removed because the backhoe arm was not long enough to dig deeper. Field screening results using an organic vapor monitor (OVM) indicated 760 ppm at 10 meters (36 ft) bgs. Offsite laboratory sample results indicated maximum contaminant concentrations of toluene at 4.7 mg/kg, diesel at 1,000 mg/kg, and kerosene at 3,085 mg/kg. The site was backfilled with clean fill following excavation activities.

In September 1992, a characterization borehole (199-N-83) was installed through the portion of the tank excavation directly beneath the previous location of the 100-N-SS-28 tank. The purpose of the borehole was to determine the depth of contamination and support evaluation of remediation methods. The borehole was drilled to a depth of 16.8 meters (55 ft) bgs. No contamination was detected during drilling or in soil samples. Three soil vapor probes were installed at approximate depths of 12.2 meters (20 ft), 14.3 meters (33 ft), and 16.8 meters (41 ft). No contaminants were detected during field screening analysis of the vapor probe samples. The lack of contamination found during the borehole sampling was speculated to be a result of volatilization and biodegradation of the petroleum products or that the borehole did not intersect the remaining contamination. A test pit investigation was performed in April 1994 to verify the results of the borehole. A small amount of black sand was encountered near the borehole. The sand was moist and a petroleum odor was evident. Cave-in material from the sidewalls of the pit was becoming a problem with increasing depth. The 1994 investigation did not excavate to the recommended depth of 12 meters (40 ft).

A characterization borehole was drilled from in February 2015 to a total depth of 30.46 meters (99.95 ft) below ground surface, at a location between the storage tanks and the service station pumps. It was near where the pipelines intersected at approximately N 149514.1, E 571395.1. The borehole was drilled to support completion as a groundwater monitoring well or bioventing air inject well, if needed. Eleven soil samples and one groundwater sample were collected at discrete depth intervals. No petroleum contamination or other hazardous constituents were detected above soil or groundwater cleanup levels.

Code: 100-N-86	Classification: Accepted
Names: 100-N-86; 151-N Substation Transformer and Oil Circuit Breakers	Reclassification: Interim Closed Out (3/4/2014)
Type: Electrical Substation	Start Date:
Status: Inactive	End Date:
Description:	The site has been remediated and Interim Closed Out. It consisted of concrete support pedestals for a 230-13.8 kv transformer, the concrete pad for three oil circuit breakers (OCBs) and any underlying contaminated soils. The 151-N Substation contained various electrical equipment and a control building surrounded by a fence.
Location:	The 230 to 13.8 kv transformer and OCBs were located south of Trinity Drive and east of Timber Road. The OCBs were 265 meters (870 ft) southeast of the 105-N Reactor and the transformer was located 225 meters (738 ft) southeast of the 105-N Reactor. The oil Circuit Breakers were centered at coordinates E571374.21 N149310.86. The transformer was centered at coordinates E571328.21 N149328.45.
Related Sites/ Structures:	151-N Substation

Process Description: The 151-N Substation was the primary source for "off-site" electrical power for the 100-N Area. The substation was fed by Bonneville Power Administration Midway Switching Station. The 230 kv electrical feed passed through a bank of OCBs to the 230-13.8 kv main power transformer. The 13.8 kv lines went from the low side terminals of the transformer to the 151-N Building. There were three OCBs, one for each phase of electric power.

Construction of the 151-N Substation was completed in November 1961 (HW-83918). The substation continued to serve the 100-N area until it was decommissioned in 1998. The transformer and OCBs were isolated in March 1998. Based on aerial photographs, they were removed between November 2001 and May 2002. The transformer pedestals and OCB pad remained in place. The control building and 13.8-4.16 kv transformer were demolished and removed by the D4 Project in 2006 (D4-100N-0002). The excavation extended to the south pedestal for the 230 kv transformer.

Analogous sites at other reactor operational areas have had releases of polychlorinated biphenyl's (PCBs) and petroleum hydrocarbons to the underlying soil, due to routine maintenance and accidental releases during their operations.

Waste Type: Soil

Waste Description: The waste is potentially contaminated concrete and underlying soils.

Closure Info: Interim (3/4/2014): The transformers and oil circuit breakers were isolated in March 1998 and were removed between November 2001 and May 2002. The transformer pedestal and oil circuit breakers pad remained in place. Between December 2005 and March 2006, portions of the concrete support pedestals were removed by the Deactivation, Decontamination, Decommissioning, and Demolition (D4) project during the demolition of the 151-N Building.

In April 2012, while removing the 151-N Building slab and foundation, D4 also removed the transformer support pedestals that were adjacent to and north of the former 151-N Building. The pedestals were removed to 1 meter (3 ft) bgs. A radiological survey was conducted in May 2012. No gamma-emitting radiological contamination above background was detected. The Field Remediation project resumed remedial action on May 14, 2013 and continued through June 6, 2013. In-process soil samples collected in the west excavation detected polycyclic aromatic hydrocarbons (PAH) above RAGs. Therefore remediation continued on the southern slope of the westernmost excavation on July 29 and 30, 2013. Additional in-process samples were collected following the completion of field remediation.

The excavation extended to approximately 1.5 to 3 meters (4.9 to 9.8 ft) bgs, resulting in approximately 725 bank cubic meters (948 bank cubic yards) of soil and debris being disposed at the Environmental Restoration Disposal Facility (ERDF). No anomalous material or soil staining was encountered during the waste site remediation. The railroad tracks and treated railroad ties that were located adjacent to the 100-N-86 waste site excavation have been removed as miscellaneous restoration items.

Code: 100-N-87	Classification: Accepted
Names: 100-N-87; 116-N Ventilation Stack Piping and French Drain	Reclassification: Interim Closed Out (7/2/2013)
Type: French Drain	Start Date: 1/1/1961
Status: Inactive	End Date: 1/1/1991
Description: The site has been remediated and Interim Closed Out. It consisted of the stack drain piping and french drain for the 116-N ventilation Stack.	

Location: The 116-N Exhaust Stack was located approximately 95 meters (312 ft) north of the 105-N Reactor Building. The french drain was located approximately 13 meters (43 ft) east of 116-N.

**Related Sites/
Structures:** 105-N Reactor Building, 117-N Filter Building

**Process
Description:** The 116-N Exhaust Stack was constructed in 1961 and was in use until the N-Reactor was ordered permanently shut down in 1991. The stack was designed to control worker exposure to airborne radioactive contaminants from the reactor by discharging them high into the atmosphere. Air from all five ventilation confinement zones in the 105-N Reactor Building was routed through moisture separators, high efficiency particulate filters, and charcoal absorbers in the 117-N Filter Building to remove airborne contamination. The filtered air was discharged to the stack. Moisture and other condensates in the filtered air stream would plate out on the inside of the stack. The stack foundation contained a floor drain that discharged the condensate to a french drain through a 5.08 centimeter (2 in) galvanized iron pipe.

Waste Type: Soil

**Waste
Description:** The waste consists of the drain piping, french drains and underlying gravel and soil.

Closure Info: Interim (7/2/2013): Remedial action at the 100-N-87, 100-N-102:1, UPR-100-N-14, and UPR-100-N-9 waste sites was performed during January and February 2011. Remediation involved removal of the foundations of the 116-N stack, the 119-N and 119-NA structures, and the underlying soil. Excavation continued until the french drain, associated piping, and contaminated soil and debris were removed. This excavation exceeded the depth that would be required to remove the 100-N-102:1, UPR-100-N-9, and UPR-100-N-14 waste sites. According to drawing H-1-46389, the depth of the 100-N-102:1 subsite, and therefore the unplanned release waste sites UPR-100-N-9 and UPR-100-N-14, was at 0.76 meters (2.5 ft) bgs. The final excavation depth was approximately 8.5 meters (28 ft) bgs. Because the excavation and removal of the 116-N stack foundation was previously performed by the D4 Project, the exact volume of material removed is unknown.

The debris removed included soil, concrete, piping, and other debris associated with the 116-N, 119-N, and 119-NA structures and french drain. All material from these waste sites was disposed at the Environmental Restoration Disposal Facility (ERDF). No anomalous material was encountered during the excavation.

In March 2012, the D4 Project constructed a ramp across the 100-N-87, 100-N-102:1, UPR-100-N-14, and UPR-100-N-9 excavation to provide access and to support remediation activities at 1303-N (118-N-1) waste site. The ramp material was excavated on September 28, 2012, and also disposed of at ERDF. A walk around the site boundary confirmed that all fill material used to build the ramp had been removed. After the excavation of the ramp material, a gamma survey was performed on October 3, 2012, within the 100-N-87, 100-N-102:1, UPR-100-N-14, and UPR-100-N-9 excavation. The gamma survey results indicated readings above background at two locations. Additional remediation was performed to address areas where the GPERS survey results indicated elevated radiological results. Follow up surveys on October 17, 2012 and October 19, 2012 indicated no elevated readings above background.

Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Code: 100-N-88

Classification: Accepted

Names: 100-N-88; 1143-N French Drain

Reclassification Interim Closed Out (7/2/2013)

Type: French Drain**Start Date:****Status:** Inactive**End Date:****Description:** The site has been remediated and Interim Closed Out. It was a 0.61 meter (24 in) catch basin (french drain), associated 5.1 centimeter (2 in) diameter drain pipeline and the underlying soil. A sink inside the 1143-N Paint Shop discharged to this site. The potential existed for the french drain to receive paint solvents and other hazardous liquids from the activities within the building. The sink was removed about 1997, and discharges to this site ceased.**Location:** The 1143-N Carpenter/Paint Shop was approximately 360 meters (1181 ft) southwest of the 105-N Reactor building. The french drain was located approximately 3.5 meters (11.5 ft) southwest of the 1143-N Carpenter/Paint Shop.**Related Sites/
Structures:** 1143-N Carpenter/Paint Shop**Process
Description:** The south half of 1143-N Building was used as a paint shop after the building was built in the early 1980's until the mid-1990's, when it was converted to a heavy equipment mechanics shop. The french drain received wastewater from a sink located in the south half of the shop from the early 1980's until 1997.**Waste Type:** Soil**Waste
Description:** Soil within and beneath the french drain and associated pipeline, potentially wetted with hazardous solvents and lead-based paints. COPCs consist of paint solvents and lead-based paints.**Closure Info:** Interim (7/2/2013): Remedial action at the 100-N-88 waste site was performed on February 28, 2012, as a part of the 1143-N Building remediation through the D4 Project. The excavation for the 100-N-88 waste site continued to an approximate depth of 1.3 meters (4.3 ft) over an area of 30.6 square meters (329.4 sq. ft.). All material (soil, concrete, gravel, and steel pipe) was directly loaded from the excavation into Environmental Restoration Disposal Facility (ERDF) containers for disposal at ERDF. There are no overburden piles or waste staging pile areas associated with the 100-N-88 waste site. No anomalous materials were encountered during the excavation.

Code: 100-N-89**Classification:** Accepted**Names:** 100-N-89; 117-NVH French Drain**Reclassification** Interim Closed Out (10/22/2013)**Type:** French Drain**Start Date:****Status:** Inactive**End Date:****Description:** The french drain has been remediated and Interim Closed Out. It was a 61 cm (24 in) concrete pipe buried to a depth of 91 cm (36 in). The top of the pipe was at grade and it was filled with gravel. An additional 46 cm (18 in) of gravel was beneath the pipe. A metal plate covered the pipe (H-1-50093).**Location:** The French drain was located on the west side and adjacent to the 117-NVH Valve House. It was approximately 112 meters (367 ft) north of the 105-N Reactor. It was within the excavation footprint when the 100-N-63 pipelines are remediated.**Related Sites/
Structures:** Two 100-N-63, 100-N Reactor Underground Pipelines were located west of the French drain. A 91 cm (36 in) contaminated drain (CD) line was about 2 meter (6.5 ft) west and a 30.5 cm (12 in) radioactive drain (RDR) line was about 2.6 m (8.5 ft) to the west (H-1-45007, sheet 44).

Structures associated with the French drain included 117-N Filter House and the 117-NVH

Valve House. A 25.4 cm (10 in) nitrogen inerting system (NIS) pipe, associated with the construction of the post-Chernobyl upgrades to N Reactor, was buried to the west of the French drain (H-1-50223).

Process Description: The french drain received discharge from back flushing an in-line screen on the 10 cm (4 in) raw water supply line in the 117-NVH Valve House (H-1-50092). The discharge to the french drain was an above-grade 3.8 cm (1.5 in.) high-pressure raw water supply pipeline from the 10 cm (4 inch) raw water supply back flush pipeline.

Waste Type: Soil

Waste Description: The waste includes the concrete pipe and gravel (french drain) and underlying soils if determined to be contaminated. The french drain reportedly received raw water back flushed from an inline screen on the raw water supply. There are no contaminants of potential concern associated with raw water.

Closure Info: Interim (10/22/2013): The 100-N-89 french drain was removed by the Decontamination, Decommissioning, Deactivation, and Demolition (D4) Project during removal of the 117-NVH Valve Control House Building in April 2011. The waste was disposed at the Environmental Restoration Disposal Facility (ERDF). Radiological surveys were performed at an area north of the 118-N-1 spacer silo waste site to support evaluation of remediation of the nearby 100-N-63:2 pipelines detected radiological contamination associated with the 100-N-63:2 waste site that included identification of radiological contamination at the 100-N-89 waste site location. As a result, additional soil remediation was performed between May 22 and 30, 2013, to remove this residual radiological contamination. Approximately 1,448 bank cubic meters (1,894 bank cubic yards) of contaminated soil was removed during the subsequent 100-N-63:2 soil remediation. Additional soil was removed from below the former 100-N-89 french drain and 117-NVH Building locations during subsequent remediation of the 117-N Air Filter House. This additional soil removal was completed in September 2011. The excavation depth below the french drain was approximately 4.5 meters (14.8 ft) below surface grade. All material was disposed at ERDF.

The final excavation depth at the former location of the 100-N-89 french drain is approximately 5.5 meters (18.0 ft) below surface grade. The base of the french drain was approximately 1.4 m (4.5 ft) below surface grade. No anomalies were encountered or observed during the excavation.

Code: 100-N-90

Classification: Accepted

Names: 100-N-90; 100-N Reactor Rod Caves

Reclassification: Interim Closed Out (5/17/2013)

Type: Storage

Start Date:

Status: Inactive

End Date:

Description: The waste site has been remediated and Interim Closed Out. Rod Cave was two 30.5 centimeter (12 in) carbon steel pipes buried in an earth berm on the north side of the 117-N Air Filter Building. The waste site also included potentially contaminated soil underlying the pipes. The west ends of the pipes had aluminum covers. The east ends were buried in the berm. Two vertical pipes for monitoring radiation levels extended through the berm.

Location: The rod cave was located in the earth shield berm on the north side of 117-N, 115 meters (377 ft) north of the 105-N Reactor.

Related Sites/Structures: WIDS site 100-N-63, 100-N Reactor TSD Underground Pipelines, is located about 7 meters (23 ft) west of the rod cave. Facilities associated with the rod cave include the 105-N Reactor and 117-N Air Filter Building.

Process Description:	The Rod Cave was the temporary storage for used control rods from N Reactor.
Waste Type:	Equipment
Waste Description:	The waste consists of two carbon steel pipes used to store control rods. COPCs Carbon-14 and Cobalt-60.
Waste Type:	Soil
Waste Description:	The waste includes potentially contaminated soils underlying the carbon steel pipes. COPCs Carbon-14 and Cobalt-60.
Closure Info:	Interim (5/17/2013): The 100-N-90 Rod Caves were completely removed by the Deactivation, Decontamination, Decommissioning, and Demolition (D4) Project in March 2011 as part of removal of the 117-N Exhaust Air Filter House and the 117-NVH Valve Control House. Two post-demolition Global Positioning Environmental Radiological Surveyor (GPERS) surveys were performed in October 2011. Radiological contamination was identified within the 117-NVH facility footprint and the northern portion of the 117-N facility footprint. Therefore, the facility footprints were then excavated to a deeper extent and the previously contaminated portions of these footprints were resurveyed in December 2012. The soil below the 100-N-90 waste site was excavated to a depth of approximately 7 meters (23 ft) below surface grade as part of the 117-N and 117-NVH facility removal. Radiological surveys for beta and gamma contamination did not identify radiological contamination below the 100-N-90 waste site. Therefore, no verification samples were required and the 100-N-90 waste is reclassified as Interim Closed Out.
	Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Code:	100-N-91	Classification:	Accepted
Names:	100-N-91; 100-N Battery Debris	Reclassification	Interim Closed Out (5/14/2014)
Type:	Dumping Area	Start Date:	
Status:	Inactive	End Date:	
Description:	The site has been remediated and Interim Closed Out. It consisted of an area, approximately 0.6 meter diameter (2 feet) diameter, containing battery debris. The exterior of the batteries had degraded and the contents was mixed into the soil. No vegetation growing was in the affected area.		
Location:	This site was located 805 meters southwest of the 100-N-47 waste site (military camp landfill) at coordinates N148183 E571145.		
Related Sites/ Structures:	100-N Military camp		
Process Description:	This waste site was created due to batteries being discarded in the field.		
Waste Type:	Batteries		
Waste Description:	The waste includes discarded batteries and potentially contaminated underlying soils. The COPCs consist of metals.		
Closure Info:	Interim (5/14/2014): The 100-N-91 waste site was remediated by hand digging on November 12, 2013, based on the recommendation of the remove, treat, and dispose report. Less than 1		

bank cubic meters (1.3 bank cubic yards) of soil was collected in plastic bags for disposal at the Environmental Restoration Disposal Facility. There was no staging pile area or overburden soil stockpile associated with the 100-N-91 waste site excavation. Debris consisting of small dry-cell batteries and pieces of batteries was excavated by hand digging at the 100-N-91 waste site. No other anomalous material or staining was encountered during excavation.

The final depth of the 100-N-91 waste site excavation is approximately 0.5 meter (1.5 ft). Following remediation, a boundary walk-around survey of the 100-N-91 waste site excavation was not performed due to the very small size of the hand-dug excavation. The post-excavation footprint was a small, circular hole of approximately 0.9 meter (3 ft) in diameter resulting in an excavated waste site area of less than 1 square meter (10.8 sq. ft.).

Code:	100-N-92	Classification:	Accepted
Names:	100-N-92; 100-N Stain Area #1	Reclassification	Interim No Action (4/5/2012)
Type:	Dumping Area	Start Date:	
Status:	Inactive	End Date:	
Description:	This site was determined to be a No Action site. The site consisted of a 3 meter (10 feet) diameter area stained with a white substance resembling dried paint and two 4 liter (1 gallon) cans. Confirmatory sampling of the 100-N-92 waste site was performed on January 26, 2011. The results indicated that the waste site achieved compliance with the remedial action objectives (RAOs) and remedial action goals (RAGs) for the 100-N-92 waste site. Therefore, remediation was not necessary.		
Location:	This feature is located approximately 1200 meters southeast of the 105-N Reactor building and 123 meters southwest of 100-N-47 (Military Artillery Site Solid Waste Site). The coordinates for the area are E571851 N148367.		
Related Sites/Structures:	The waste site may be associated with the 100-N Military Artillery Site Solid Waste Site (sitecode 100-N-47).		
Waste Type:	Misc. Trash and Debris		
Waste Description:	Site COPCs consist of volatile organic compounds and lead. The waste consists of the stained soil and debris.		
Closure Info:	Interim (4/5/2012): This is a Confirmatory Sampling/No Action waste site. Three soil samples (one beneath each paint can and one beneath the white substance and one duplicate) were collected from the surface of the 100-N-92 waste site. In addition, a solid sample of the white substance shown was also collected. No additional debris was observed during sampling, other than the paint cans and the black wire noted on May 19, 2010. No sign of oil staining was noted, so total petroleum hydrocarbons (TPH) and polycyclic aromatic hydrocarbons (PAH) analyses were not performed. No radiological activity was detected at this waste site; therefore, radionuclide analysis of the samples was not performed. Based on confirmatory sampling results at the 100-N-92 waste site, remedial action was determined to be unnecessary. The confirmatory sampling data has been used to document this waste site to be reclassified as a No Action site.		

Code:	100-N-93	Classification:	Accepted
Names:	100-N-93; 100-N Stain Area #2	Reclassification	Interim Closed Out (9/9/2014)
Type:	Dumping Area	Start Date:	
Status:	Inactive	End Date:	

Description: The waste site was remediated and Interim Closed Out. The site consisted of potentially contaminated soil. It also included concrete, metal, glass debris, stained soil, suspected friable asbestos, and garnet sand with areas lacking in vegetation.

Location: 100-N-93 was located within the 100-N-19 borrow pit near the west end of the pit. The stain was located 475 meters southwest of the rail spurs entering the south end of 100-N, and 85 meters southeast of the dirt access road between 100-N and 100-K.

**Related Sites/
Structures:** The stain was associated with the 100-N-19 borrow pit.

**Process
Description:** The 100-N-19 pit used for disposal of nonhazardous debris from the 100-N Area and the Hanford Generating Plant (HGP).

Waste Type: Misc. Trash and Debris

**Waste
Description:** The waste consists of potentially contaminated soil, concrete, metal, glass, friable asbestos and garnet sand.

Closure Info: Interim (9/9/2014): Remedial action at the 100-N-93 waste site was performed between March 26, 2013, and March 21, 2014. The depth of the remediation ranged from 4.6 to 6.1 meters (15 to 20 ft) below ground surface resulting in approximately 35,551 bank cubic meters (46,499 bank cubic yards) of soil and debris being removed for disposal at the Environmental Restoration Disposal Facility (ERDF). The debris consisted of lead-acid batteries, asbestos, miscellaneous steel, burnt wood, glass, concrete, empty steel drums, wire, garnet sand, and communications cable. All waste material was loaded directly from the waste site into the ERDF disposal containers. No waste staging pile area or overburden soil stockpiles were created. No anomalous materials were encountered during the remediation.

Code: 100-N-94

Classification: Accepted

Names: 100-N-94; 100-N Oil Filters #1

Reclassification Interim Closed Out (8/20/2014)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site consisted of the underlying soil and approximately 50 oil filters.

Location: The site is located 30 meters west of Route 4 N, south of the railroad tracks near N Ave.

**Process
Description:** This feature appears to have been caused by a random dumping of used oil filters.

Waste Type: Misc. Trash and Debris

**Waste
Description:** Metals, polyaromatic hydrocarbons, total petroleum hydrocarbons, and polychlorinated biphenyls. The waste includes discarded oil filters and potentially contaminated soils.

Closure Info: Interim (8/20/2014): A waste characterization sample was collected on April 22, 2013, prior to the start of remediation. Waste site remediation was conducted on January 31, 2014. The remediation extended to approximately 1 meter (3.3 ft) below ground surface resulting in approximately 47 bank cubic meters (61 bank cubic yards) of soil and debris removed for disposal at the Environmental Restoration Disposal Facility (ERDF). The debris consisted of oil filters and concrete. All material was loaded directly into the ERDF containers. No waste staging pile areas were created. No overburden soil pile associated with the waste site. No anomalous material was encountered during the remediation. All visibly stained soil was removed. A post-remediation walk around boundary survey was conducted following remedial action activities.

Code: 100-N-95	Classification: Accepted
Names: 100-N-95; Hanford Generating Plant (185-N) Septic Tank	Reclassification: Interim Closed Out (3/4/2014)
Type: Sanitary Sewer	Start Date:
Status: Inactive	End Date:
Description: The waste site has been remediated and Interim Closed Out. It consisted of a septic tank, associated piping and underlying soil.	
Location: This septic system was located approximately 4 meters from the NE corner of the Hanford Generating Plant (HGP) tile field (100-N-4).	
Related Sites/ Structures: The septic tank is associated with 100-N-4 (HGP tile field also called SWMU #5).	
Process Description: The septic tank supplied influent to 100-N-4 (Hanford Generating Plant (HGP) tile field). The tank received sanitary waste and lab waste influent from the 185-N building via a 20 cm (8 in) cast iron pipe (H-6-4025 sht. 1 rev. 1). The tank did not receive effluent from the 185-N building drains and sumps, which are identified as SWMU # 3 (per document HGP-CVP-SWMUs 5, 6, 7, 8, 9 & 10 Rev. 0, June 2004). Testing for corrosion inhibitors hydrazine and morpholine were performed in the 185-N lab. It is likely that the tank received these reagents (see sitecode 100-N-4).	
Closure Info: Interim (3/4/2014): Remedial action at the 100-N-95 waste site was performed between April 29 and June 11, 2013, and continued to a maximum depth of approximately 4.0 meters (13.1 ft) below ground surface resulting in the removal of approximately 1,385 bank cubic meters (BCM) (1,812 bank cubic yards [BCY]) of contaminated soil, cast iron pipe, lead bells, and rebar. All material was direct loaded from the excavation for disposal at the Environmental Restoration Disposal Facility (ERDF). No anomalous material was encountered during the excavation. The maximum excavation depth was 4 meters (13 ft). In-process soil samples were collected from the 100-N-95 waste site between April and June 2013.	

Code: 100-N-96	Classification: Accepted
Names: 100-N-96; 100-N Military Camp Disposal Pits	Reclassification: None
Type: Dumping Area	Start Date:
Status: Inactive	End Date:
Description: This site consists of three separate suspect disposal pits located southwest of the 100-N-47 military camp, identified from a 1957 aerial photograph. The suspect disposal pits were located outside the boundary of the military camp.	
Location: The three disposal pits were located about 570 meters (1870 ft) southwest of the military camp. Disposal Pit 1 was centered at 571505.3E, 148238.3N Disposal Pit 2 was centered at 571545.9E, 148068.8N Disposal Pit 3 was centered at E571672.4E N148106.7.	
Related Sites/ Structures: WIDS Site 100-N-47 Military Artillery Site Solid Waste Site, was located to the northeast. Military Camp refuse and garbage was most likely disposed in the disposal pits.	
Process Description: The "Army Agreement" of 1951 provided for the disposal of refuse by the Army as follows: "Army will dispose of its trash and garbage in a manner acceptable to the Atomic Energy Commission (AEC). The Army may make disposal pits off Army land, as necessary, at locations designated by AEC and such pits shall be subject to AEC inspection." (CCN#	

589754). The 1957 aerial photo of the military site shows disturbances to the southwest of the military camp outside what appears to be the perimeter fence. These disturbances are suspect disposal pits. The military camp was in use by the Army from 1951 to 1958.

In 2008 aerial photos (115-rgb.tif and 116-rgb.tif) heavy equipment blade marks are visible which indicate the disposal pits have been backfilled.

Waste Type: Misc. Trash and Debris

Waste Description: The waste consists of solid waste generated by the military camp. Site COPCs were listed as volatile organics, semivolatile organics, polychlorinated biphenyls and metals.

Code: 100-N-97

Classification: Accepted

Names: 100-N-97; 100-N Oil Filters #2

Reclassification: Interim Closed Out (9/9/2014)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The waste site has been remediated and Interim Closed Out. It consisted of underlying soil and 3 oil filters. There was no vegetation growing within the release area.

Location: This feature was located approximately 56 meters (184 ft) west of the southwest corner of the 100-D Area perimeter, near Pumphouse Road.

Waste Type: Misc. Trash and Debris

Waste Description: The waste includes discarded oil filters and potentially contaminated soil. Site COPCs consist of metals, polyaromatic hydrocarbons, total petroleum hydrocarbons, and polychlorinated biphenyls.

Closure Info: Interim (9/9/2014): A characterization sample was collected on April 22, 2013, prior to the start of remediation.

Waste site remediation began on November 12, 2013, and continued through January 8, 2014. Because the waste site was located in a culturally sensitive area, it was remediated by hand digging. The material was placed into plastic bags for disposal. The plastic bags were hand carried to the nearest access road to be disposed in an Environmental Restoration Disposal Facility (ERDF) container.

The remediation extended approximately 0.61 meters (2 ft) below ground surface, resulting in approximately 1.3 bank cubic meters (1.7 bank cubic yards) of soil and debris being removed and disposed at ERDF. No anomalous material was encountered during the remediation of the site. All visibly stained soil was removed.

Two in-process soil samples were collected on November 13, 2013, and analyzed for the site COPCs to determine if remedial action activities were complete and if the site was ready for verification sampling. Total petroleum hydrocarbons (TPH) exceeded the RAG in both samples collected; therefore, remediation continued to remove the residual contaminated soil.

On January 8, 2014, two additional in-process soil samples were collected from the same locations as the previous in-process samples to determine if the residual contaminated soil had been removed. The samples were analyzed for TPH only. The results indicated that the contaminated soil had been removed. Therefore, the remediation was determined to be complete on January 8, 2014.

Code: 100-N-98 **Classification:** Accepted
Names: 100-N-98; 100-N Stain Area #3 **Reclassification** Interim Closed Out (4/10/2013)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The waste site has been remediated and Interim Closed Out. The site consisted of two locations where the surface was stained and no vegetation was growing in the affected area. One location (OSE -N-193) consisted of multiple stained spots in a 30 meter (98.4 feet) diameter area. The other location (OSE -N-194) was a single stained spot approximately 3 meter (9.8 feet) in diameter.

Location: The larger stained area was located approximately 33 meters northwest of 128-N-1 (Burn Pit). The smaller stained area was located approximately 34 meters northeast of 128-N-1.

Waste Type: Soil

Waste Description: The waste consists of the stained soil.

Closure Info: Interim (4/10/2013): Remediation of 100-N-6, 100-N-16, 100-N-98 area 1, and 128-N-1 waste sites began on August 2, 2010, and was completed on November 28, 2011. A total of approximately 20,334 bank cubic meters (BCM) (26,596 bank cubic yards [BCY]) were excavated and staged for removal to the Environmental Restoration Disposal Facility (ERDF). Between April 16 and 19, 2012, the excavation was expanded to the west to include stained soil Area 2 of the 100-N-98 waste site. Approximately 476 BCM (623 BCY) of soil was removed from 100-N-98 Area 2 and direct loaded for disposal at ERDF. The additional remediation of the spoil pile area (SPA) and the 100-N-6, 100-N-16, 100-N-98, and 128-N-1 waste site excavation generated an additional volume of 5,446 BCM (7,123 BCY) of material for direct load out to ERDF. A total volume of 26,256 BCM (34,342 BCY) was disposed at ERDF, to complete the 100-N-6, 100-N-16, 100-N-98, and 128-N-1 waste site remediation.

The materials removed from the 100-N-6, 100-N-16, 100-N-98, and 128-N-1 waste sites consisted of abandoned wiring, transite pipe, metallic and wood debris, burnt wood, ash, tar, roofing felt, stained soil, a bucket of grout, an open glass bottle, green fibrous material, purple sandy material, a paint ball, drums containing bunker and amber oil, and miscellaneous demolition debris. Anomalous material discovered during remediation included six 208-L (55-gal) drums, small white ceramic balls used as filtering media, and soil with a strong solvent odor.

Code: 100-N-99 **Classification:** Accepted
Names: 100-N-99; 100-N Oil Filters #3 **Reclassification** Interim Closed Out (8/20/2014)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The site has been remediated and Interim Closed Out. It consisted of two locations where oil filters were discarded. The affected areas were devoid of vegetation and appear stained.

Location: Both locations were west of Route 4N approximately 1,420 meters (4658 ft) south of Route 2N. The first area (OSE - N-196) was located approximately 148 meters (485 ft) west of Route 4N. The second area (OSE - N-197) was located approximately 55 meters (180 ft) west of Route 4N.

Waste Type: Misc. Trash and Debris

Waste Description: The waste includes discarded oil filters and potentially contaminated soil. Site COPCs consist of metals, polyaromatic hydrocarbons, total petroleum hydrocarbons, and polychlorinated biphenyls.

Closure Info: Interim (8/20/2014): A waste characterization sample was collected on April 22, 2013, prior to the start of remediation. The waste site remediation was conducted on January 31, 2014. The remediation extended to approximately 1 meter (3.3 ft) below ground surface resulting in approximately 47 bank cubic meters (61 bank cubic yards) of soil and debris removed for disposal at the Environmental Restoration Disposal Facility (ERDF). The debris consisted of oil filters. All material was loaded directly into the ERDF containers; therefore, no waste staging pile areas were created. Additionally, there was no overburden soil pile associated with the waste site. No anomalous material was encountered during the remediation. All visibly stained soil was removed.

Two in-process soil samples were collected on February 3, 2014, and analyzed for the site contaminants of potential concern (COPCs) to determine if remedial action activities were complete and if the site was ready for verification sampling.

Code: 100-N-100

Classification: Accepted

Names: 100-N-100; 100-N Oil Filters #4

Reclassification: Interim Closed Out (6/12/2014)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: This site was remediated and Interim Closed Out. It consisted of petroleum based material released to the ground surface and the underlying soils. The soil was crusted and no vegetation was growing in the affected area. There were 4 oil filters at this location.

Location: The site was located approximately 190 meters west of the north side of 116-N-1 at coordinates N150010.8 E571544.1.

Waste Type: Misc. Trash and Debris

Waste Description: The waste includes discarded oil filters and potentially contaminated soils. Site COPCs consists of metals, polyaromatic hydrocarbons, total petroleum hydrocarbons, and polychlorinated biphenyls.

Closure Info: Interim (6/12/2014): Remedial action of the 100-N-100 waste site was performed on November 13, 2013, and February 27, 2014. Due to cultural sensitivity of the area, the waste site was remediated by hand digging. The maximum depth of the excavation was 0.5 meters (1.5 ft) below ground surface and resulted in the removal of less than 1.0 bank cubic meters (1.3 bank cubic yards) of soil and debris. The debris consisted of oil filters in two distinct locations. The contaminated soil and debris were directly loaded into plastic bags and carried out for disposal at the Environmental Restoration Disposal Facility (ERDF). Oil-stained soil was observed during the excavation, and all oil-stained soil was removed and disposed at ERDF. No anomalous material was encountered during excavation.

The results of the initial verification sampling indicated exceedances of direct exposure RAGs for TPH. Therefore, additional remediation and sampling was conducted on February 27, 2014.

Code: 100-N-101

Classification: Accepted

Names: 100-N-101; 100-N Stain Area #4

Reclassification: Interim Closed Out (5/27/2014)

Type: Unplanned Release

Start Date:

Status: Inactive**End Date:****Description:** The site has been remediated and Interim Closed Out. It consisted of an area of multiple stained soil spots with no growing vegetation. It was an area covering approximately 10 meters (33 ft) in diameter.**Location:** The waste site was located east of the 105-N reactor, approximately 13 meters SW of the 100-N-13 site at coordinates N149379.8 E571718.7.**Waste Type:** Soil**Waste Description:** The waste consists of the stained soil.**Closure Info:** Interim (5/27/2014): Confirmatory sampling was performed at the 100-N-101 waste site on January 24, 2011.

The 100-N-101 waste site was remediated on November 5, 2013. Approximately 64 bank cubic meters (BCM) (84 bank cubic yards [BCY]) of soil was direct loaded for disposal at the Environmental Restoration Disposal Facility (ERDF). There is no staging pile area or overburden soil stockpile associated with the 100-N-101 waste site excavation. No debris was uncovered at the 100-N-101 waste site. No anomalous material or staining was encountered during excavation. The final depth of the 100-N-101 waste site excavation is approximately 1 meters (3.3 ft) below ground surface. Following remediation, a boundary walk-around survey of the 100-N-101 waste site excavation was performed.

Code: 100-N-102**Classification:** Accepted**Names:** 100-N-102; Potentially Contaminated French Drains and Drain Lines; 100-N Potentially Contaminated French Drains**Reclassification:** Interim Closed Out (7/2/2013)**Type:** French Drain**Start Date:****Status:** Inactive**End Date:****Description:** This site consists three of potentially contaminated french drains, the associated piping and surrounding soil known as location 1A, 1B and 3. The waste site was divided into two subsites. Subsite 1 has been Interim Closed Out. Subsite 2 was determined to require No Action. Since both subsites have been reclassified, the Parent Site is also considered complete and is reclassified.

In order to facilitate closure of the removed portions, the 100-N-102 site was divided into two subsites:

100-N-102:1, 100-N Potentially Contaminated French Drains and Drain lines, Group 1. It has been excavated along with 100-N-87 and Interim Closed Out.

100-N-102:2, 100-N Potentially Contaminated French Drains and Drain Lines, Group 2. It consists of two french drains, known as location 1B and location 3. It has been evaluated and reclassified to No Action.

Note: The second french drain (166-N Pump House Dry Well), originally described in 100-N-102:2 as location 2, has been removed from this subsite. This drain was within the excavation footprint of the UPR-100-N-18 waste site excavation. It was completely removed as part of the UPR-100-N-18 remediation activity. See UPR-100-N-18 for details.

Location: The 119-N Exhaust Air Monitoring Building Absorption Pit is centered at E571244/N149685.

The French Drain outside the mobile office is centered at E571366/N149478.

Related Sites/ Structures: 105-N Reactor Building, 117-N Filter Building, 119-N Stack Sampler Building, 119-NA Continuous Airborne Effluent Monitoring Building, UPR-100-N-14 (119-N Drain System Leak), UPR-100-N-9 (119-N Cooling Water Drain Line Leak), 166-N Fuel Oil Storage Pump House.

Process Description: Subsite 1 - 119-N Exhaust Air Monitoring Building Absorption Pit -

Although the 116-N Ventilation Stack began operation in 1961, its exhaust stream was not continuously sampled until the construction of the 119-N Exhaust Air Monitoring Building in 1971. The sample stream was filtered, then cooled in a condenser. The 5 GPM cooling water stream for this condenser initially discharged via a 2-inch line to the 36-inch contaminated transfer line between the 105-N Lift Station and the 1301-N Crib. Back pressure from this lift station transfer line backed up the cooling water discharge line and resulted in UPR-100-N-14 in August 1974. The corrective action for this UPR was to construct a new cooling water discharge line and earth absorption pit, and abandon the old line (DC-3322). While this was being done, another release (UPR-100-N-9) occurred from the cooling water discharge line in October 1974, nearer the lift station transfer line. Then in 1984, the 119-NA Air Sample Monitoring Stack Sampler Building was constructed to assist with monitoring the stack exhaust for tritium. Excess tritium effluent condensate was also routed via a floor drain to the absorption pit (H-1-36322), until permanent reactor shut down in the early 1990's.

Subsite 2, French Drain Outside Mobile Office -

H-1-45007, sht 35, shows the french drain adjacent to a buried power line conduit. No lines are shown connecting to it, so sources of discharge to this drain are unknown. The trailers immediately adjacent to the french drain were used for offices and classrooms with restroom facilities and a kitchen.

This Site has the Following SubSites:

Code: 100-N-102:1

Names: 100-N-102:1; Potentially Contaminated French Drains and Drain Lines, Group 1; 100-N Potentially Contaminated French Drains, Group 1

Code: 100-N-102:2

Names: 100-N-102:2; Potentially Contaminated French Drains and Drain Lines, Group 2; 100-N Potentially Contaminated French Drains, Group 2

Code: 100-N-102:1

Classification: Accepted

Names: 100-N-102:1; Potentially Contaminated French Drains and Drain Lines, Group 1; 100-N Potentially Contaminated French Drains, Group 1

Reclassification: Interim Closed Out (7/2/2013)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The site has been remediated and Interim Closed Out. The subsite consisted of potentially contaminated piping associated with two french drains, the associated drain lines that received waste from the 119-N Exhaust Air Monitoring Building and surrounding soil. This was known as location 1A. The portions of piping that remain will be addressed as part of the 100-N-102:2 waste site.

Location: The 119-N Exhaust Air Monitoring Building is centered at E571236/ N149664.

Related Sites/ Structures:	105-N Reactor Building, 117-N Filter Building, 119-N Stack Sampler Building, 119-NA Continuous Airborne Effluent Monitoring Building, UPR-100-N-14 (119-N Drain System Leak), UPR-100-N-9 (119-N Cooling Water Drain Line Leak).
Process Description:	Although the 116-N Ventilation Stack began operation in 1961, its exhaust stream was not continuously sampled until the construction of the 119-N Exhaust Air Monitoring Building in 1971. The sample stream was filtered, then cooled in a condenser. The 5 GPM cooling water stream for this condenser initially discharged via a 2-inch line to the 36-inch contaminated transfer line between the 105-N Lift Station and the 1301-N Crib. Back pressure from this lift station transfer line backed up the cooling water discharge line and resulted in UPR-100-N-14 in August 1974. The corrective action for this UPR was to construct a new cooling water discharge line and earth absorption pit, and abandon the old line (DC-3322). While this was being done, another release (UPR-100-N-9) occurred from the cooling water discharge line in October 1974, nearer the lift station transfer line. Then in 1984, the 119-NA Air Sample Monitoring Stack Sampler Building was constructed to assist with monitoring the stack exhaust for tritium. Excess tritium effluent condensate was also routed via a floor drain to the absorption pit (H-1-36322), until permanent reactor shut down in the early 1990's.
Waste Type:	Not Specified
Waste Description:	The waste will include the pipelines and any potential contaminated soil.
Closure Info:	Interim (7/2/2013): Remedial action at the 100-N-87, 100-N-102:1, UPR-100-N-14, and UPR-100-N-9 waste sites was performed during January and February 2011. Remediation involved removal of the foundations of the 116-N stack, the 119-N and 119-NA structures, and the underlying soil. Excavation continued until the french drain, associated piping, and contaminated soil and debris were removed. This excavation exceeded the depth that would be required to remove the 100-N-102:1, UPR-100-N-9, and UPR-100-N-14 waste sites. According to drawing H-1-46389, the depth of the 100-N-102:1 subsite, and therefore the unplanned release waste sites UPR-100-N-9 and UPR-100-N-14, was at 0.76 meters (2.5 ft) bgs. The final excavation depth was approximately 8.5 meters (28 ft) bgs. Because the excavation and removal of the 116-N stack foundation was previously performed by the D4 Project, the exact volume of material removed is unknown.
	The debris removed included soil, concrete, piping, and other debris associated with the 116-N, 119-N, and 119-NA structures and french drain. All material from these waste sites was disposed at the Environmental Restoration Disposal Facility (ERDF). No anomalous material was encountered during the excavation.
	In March 2012, the D4 Project constructed a ramp across the 100-N-87, 100-N-102:1, UPR-100-N-14, and UPR-100-N-9 excavation to provide access and to support remediation activities at 1303-N (118-N-1) waste site. The ramp material was excavated on September 28, 2012, and also disposed of at ERDF. A walk around the site boundary confirmed that all fill material used to build the ramp had been removed. After the excavation of the ramp material, a gamma survey was performed on October 3, 2012, within the 100-N-87, 100-N-102:1, UPR-100-N-14, and UPR-100-N-9 excavation. The gamma survey results indicated readings above background at two locations. Additional remediation was performed to address areas where the GPERs survey results indicated elevated radiological results. Follow up surveys on October 17, 2012 and October 19, 2012 indicated no elevated readings above background.
	Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

The SubSite is Part Of:

Code: 100-N-102
Names: 100-N-102; Potentially Contaminated French Drains and Drain Lines; 100-N Potentially Contaminated French Drains

Code: 100-N-102:2
Classification: Accepted
Names: 100-N-102:2; Potentially Contaminated French Drains and Drain Lines, Group 2; 100-N Potentially Contaminated French Drains, Group 2
Reclassification: Interim No Action (6/19/2012)
Type: French Drain
Start Date:
Status: Inactive
End Date:

Description: The subsite has been evaluated and reclassified to No Action. It consists of two potentially contaminated french drains and associated piping (known as location 1B and Location 3).

One french drain had an absorption pit and two drain lines, located generally to the north of the former 116-N Ventilation Stack location. These components were associated with the former 119-N and 119-NA Sample Buildings, which sampled potentially contaminated exhaust air and associated condensate from the 116-N Stack. The stack and sample buildings have been demolished, and the line to the absorption pit was capped. The french drain and remaining piping are included in this subsite. It is described as location 1B.

The other french drain was located west of the former 1126-NA Mobile Office. It had had no identified associated piping. The mobile office, as well as other nearby buildings, have been demolished. It is described as location 3.

Location: The first drain is located near the 119-N Exhaust Air Monitoring Building Absorption Pit, centered at 571244E 149685N. It is described as location 1A. The second French Drain is located outside the 1126-NA mobile office, centered at coordinates E571366 N149478. It is described as location 3.

Related Sites/ Structures: 105-N Reactor Building, 117-N Filter Building, 119-N Stack Sampler Building, 119-NA Continuous Airborne Effluent Monitoring Building, UPR-100-N-14 (119-N Drain System Leak), UPR-100-N-9 (119-N Cooling Water Drain Line Leak), 166-N Fuel Oil Storage Pumphouse.

Waste Type: Sludge

Waste Description: The waste included water and miscellaneous floor drainage containing sludge, grit and oil.

Closure Info: Interim (6/19/2012): The 100-N-102:2 subsite consisted of two locations, 1B and 3, that were identified in the Confirmatory Work Instruction (CWI) as potential french drains.

Subsite 2 was reclassified with Waste Site Reclassification Form (WSRF) 2012-001. It addresses only the 100-N-102:2 subsite, which consists of two locations, 1B and 3.

Location 1B was excavated to 4.6 meters (15 ft) for confirmatory sampling, but no indication of a french drain structure, staining, debris, undisturbed soil, or contamination was found. The excavation was increased to 6.1 meters (20 ft), also with no indication of a french drain structure, staining or contamination. An evaluation of this location indicated that the structure was either removed with the 100-N-87 waste site remediation, or it was never present. In accordance with the CWI, location 1B was not sampled.

Excavation for confirmatory sampling at location 3 began, but was stopped when live 220 Kv electrical lines were encountered within the excavation. No samples were collected at location 3

due to safety concerns. Prior to the cessation of activities, the top of the french drain was uncovered. This french drain consists of a metal 55 gallon drum to which a pipe is attached. The drum was filled with cobble. This french drain is associated with a temporary administrative office and classroom trailer (MO 1126-N). An office and classroom trailer would have been supplied with steam for heating but would not be expected to have any chemical or radiological processes associated with the trailer and therefore with the french drain. French drains were constructed with the compatibility of the discharge taken into consideration. Steel would not have been used for acidic or other chemically active discharges because the metal is incompatible with those liquids. Chemically active liquids would have been disposed in clay pipes. The metal of construction of this french drain is consistent with french drains designed for steam condensate. This is also consistent with the historical description of the french drain at location 3 which is identified as servicing the 1126-N Mobile Office and classroom. This type of steam condensate french drain presents a very limited risk for contamination.

The SubSite is Part Of:

Code: 100-N-102

Names: 100-N-102; Potentially Contaminated French Drains and Drain Lines; 100-N Potentially Contaminated French Drains

Code: 100-N-103

Classification: Accepted

Names: 100-N-103; 100-N Steam Condensate French Drains

Reclassification: Interim No Action (7/9/2012)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The waste site consists of 12 steam condensate french drains and their associated below grade piping components discovered during the Orphan Site Evaluation Report (OSR) historical review. It included subsites 100-N-103:1, 100-N Steam Condensate French Drains (eleven inactive drains) and 100-N-103:2, 100-N Steam Condensate French Drains (one active drain). Both subsites have been addressed, so the parent site has also been reclassified. Some of the drywells and their associated pipelines fall within a planned excavation of other waste sites. These french drains will be dispositioned during remediation of those waste sites.

Location: Refer to the subsites for locations of the french drains.

Process Description: Steam was typically used at all facilities for heating purposes. As a non-contact system the steam remained uncontaminated. The steam transport process utilized a high pressure supply line and a low pressure return or discharge line. It was necessary to bleed both the supply and return lines to prevent condensate build up. The condensate was typically blown off from the above grade piping system into a below grade, covered french drain. French drain diameters and construction material varied depending on steam piping size, service capacity pounds per hour, and expected flow rate received.

This Site has the Following SubSites:

Code: 100-N-103:1

Names: 100-N-103:1; 100-N Steam Condensate French Drains (inactive)

Code: 100-N-103:2

Names: 100-N-103:2; 609-E-1; 100-N Steam Condensate French Drains (active)

Code: 100-N-103:1

Classification: Accepted

Names: 100-N-103:1; 100-N Steam Condensate French

Reclassification: Interim No Action (7/9/2012)

Drains (inactive)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The eleven french drains have been evaluated and determined to require No Action.

Subsite 1 consists of 11, inactive steam condensate french drains and their associated below grade piping components.

The site descriptions for each of the 11 steam condensate french drains (FD) are:

FD1. The site was a french drain with a 1.9-cm (0.75-in.) clean medium pressure steam return line from the 108-N Building (H-1-29247). This french drain was removed during the demolition of the 108-N building. 100-N-103:1 French Drain 1 will be addressed with the pipelines in 100-N-84:6 (and 100-N-61). French Drain 1 is not considered a No Action component.

FD2. The site is a 7.6-cm (3-in.) french drain, 2.8-m (9.2-ft) to wall. The site is associated with the 1902-N building, which housed clean export water valving and piping (H-1-45007, sht 22). (removed with 100-N-61)

FD3. The site is a 0.61-m (24-in.) primary flash pipe with a 1.9-cm (0.75-in.) diameter, 13-m (43-ft) long medium pressure steam condensate pipeline from the wall of the 184-NC Building (H-1-45007, sht 28, 29). Confirmatory activities determined FD-3 was removed completely during the demolition of the 184-N Building in 2008.

FD4. The site is a 0.9-m (36-in.) french drain with a 6-m (20-ft) long pipe to the wall of the 1701-N clean badgehouse (H-1-45007, sht 27).

FD5. The site is a 0.9-m (36-in.) dry well abandoned in 1985, replaced by a 1.2-m (48-in) dry well, and received steam condensate from 184-N, 184-NA, and 184-N day tanks. (H-1-45007, sht 29; H-1-48915 shts 1 and 2). Confirmatory activities determined this dry well was removed during the demolition of the 184-N Building in 2008.

FD6. The site is a 1.2-m (48-in.) dry well that replaced a 0.9-m (36-in) dry well in 1985, and received steam condensate from 184-N, 184-NA, and 184-N day tanks. A 7.6-cm (3-in.) pipe enters the dry well (H-1-45007, sht 29). (removed with UPR-100-N-19 remedial excavation)

FD7. The site is a 0.61-m (24-in.) dry well with a 1.3-cm (0.5-in.) diameter, 31.5-m (103-ft) long steam condensate pipeline to the 1101-N wall, and a potable water line from the 1100-N office building (H-1-45007, sht 28). Confirmatory activities determined the structure at this location was a valve box. There was no dry well at the excavation.

FD8. The site is a dry well with a 30-m (98-ft) long, 2.54-cm (1.5-in.) diameter line connecting from the 1100-N Building (H-1-45007, sht 35, H-1-44195). There is a manhole with a valve and pipe inside immediately adjacent to the french drain.

FD9. The site is a 1.2-m (48-in.) dry well with a 10-cm (4-in.) floor drain from an equipment access pit, and a 10-cm (4-in.) cast iron floor drain line from a clean office area at the 105 N Building (H-1-28877, H-1-27705). (French Drain 9 has also been deferred for disposition with 100-N-84:4. This french drain structure was actually removed during demolition of the 105-N Control Room structure.)

FD10. The site is a dry well with a 10-cm (4-in.) steam condensate pipeline from the 105 N

Building and another 10-cm (4-in.) steam condensate pipeline from clean operations in 1712-N (H-1-45007, sht 43). (disposition with remediation of 100-N-84:4)

FD11. The site is a dry well with a 7.6-cm (3-in.) low pressure steam condensate pipeline from the 1734-N gas bottle storage building (H-1-45007, sht 43). (disposition with remediation of 100-N-84:4)

Location: The 100-N-103 Steam Condensate French Drains are located in the 100 NR-1 Operable Unit of the Hanford Site, near the 108-N chemical unloading facility, 1902-N export water tie-in building, 184-N powerhouse, 1701-N Gatehouse, 1100-N and 1101-N Office Buildings, 105-N Reactor, 1712-N Insulation Shop, and the 1734-N gas storage bottle building.

Waste Type: Not Specified

Waste Description: The waste will include the pipelines and any potential contaminated soil.

Closure Info: Interim (7/9/2012): Confirmatory sampling for the 100-N-103:1 subsite was performed between August 29, 2011, and September 19, 2011, to support a determination that residual contaminant concentrations at this site meet the cleanup criteria specified in the RDR/RAWP (DOE/RL-2006b) and the N-Area ROD (EPA 1999).

The french drains identified at each of the locations within the 100-N-103:1 subsite were selected for sampling, with six exceptions. Excavation was being undertaken at the locations of drain numbers 1, 2, 6, and 9 for the purpose of remediating the 100-N-61:1, UPR-100-N-19 waste sites and building demolitions in the vicinity during the confirmatory sampling effort. Access to these french drain locations was not available. The remediations removed the french drains as debris within the field remediation excavation boundaries. Therefore, no confirmatory sampling was performed at these locations. French drains 10 and 11 will be removed in the excavation for the scheduled remediation of the 100-N-84:4 pipeline subsite. These french drains will be dispositioned within the closeout documentation for the 100-N-61:1, UPR-100-N-19, and 100-N-84:4 waste sites, as appropriate.

Geophysical surveys performed at the french drain locations during confirmatory sampling activities revealed that french drain numbers 3 and 5 had been removed in their entirety during the demolition of the 184-N building. Test pits were excavated at the locations of french drain numbers 4 and 8.

The confirmatory sampling results support a reclassification of the 100-N-103:1 subsite to No Action.

The SubSite is Part Of:

Code: 100-N-103

Names: 100-N-103; 100-N Steam Condensate French Drains

Code: 100-N-103:2

Classification: Accepted

Names: 100-N-103:2; 609-E-1; 100-N Steam Condensate French Drains (active)

Reclassification: Rejected (4/5/2012)

Type: French Drain

Start Date:

Status: Active

End Date:

Description: This french drain has been evaluated and Reclassified to Rejected. The french drain is associated with an active export water line. The waste site is an active 1.2 meter (4-ft) diameter, 5 meter (16-ft) long dry well used for a filter and water supply vault. The dry well is buried 7.3

meters (24 ft) below grade with coarse gravel at the bottom. The inlet is a 15-cm (6-in.) diameter cast iron inlet pipe (H-6-302).

Location: The 100-N-103:2 subsite french drain is located in the 100 NR-1 Operable Unit of the Hanford Site, on the east side of Route 4 North, near the 609 Fire Station. It is located adjacent to the active Export Water line.

Related Sites/ Structures: The french drain is associated with an active export water line.

Process Description: Well 609-E-1 is associated with the water supply vault, east of the fire station. The drain is buried 8 feet below grade, the bottom of the well is 24 feet below grade. The vault opening extends above grade. The water supply vault was designed to receive water from the Export Water system and provide treatment by adding sodium hypochlorite prior to importing it into the fire station. This well is connected to a drain in the floor of the vault.

Waste Type: Not Specified

Waste Description: The waste will include the pipelines and any potential contaminated soil.

The SubSite is Part Of:

Code: 100-N-103

Names: 100-N-103; 100-N Steam Condensate French Drains

Code: 116-N-1

Classification: Accepted

Names: 116-N-1; 1301-N Crib and Trench; 1301-N Liquid Waste Disposal Facility

Reclassification: Interim Closed Out (4/14/2009)

Type: Crib

Start Date: 1/1/1963

Status: Inactive

End Date: 1/1/1985

Description: The waste site has been remediated and reclassified to Interim Closed Out. It included a large crib and trench. The crib began operation in 1963. In 1965, the trench was added to enhance percolation capacity. The crib and trench were used for the disposal of N Reactor cooling water. Before remediation, the site was enclosed within a chain link fence and posted with "No Trespassing", "Danger - Unauthorized Personnel Keep Out", "Radiologically Controlled Area", "Underground Radioactive Material" and "Surface Contamination" signs. All radiological postings were removed in 2015.

Location: The crib and trench were located northeast of the 105-N Building, outside the 100-N Area fence line. It was approximately 256 meters (840 feet) from the Columbia River.

Related Sites/ Structures: The site is associated 100-N-63, 100-N Reactor (1314-N, 116-N-1 and 116-N-3) TSD Underground Pipelines and UPR-100-N-31.

Process Description: The crib and trench received radiologically contaminated water from the 105-N Reactor basin floor drains and the 109-N floor drains. The effluent contained activation and fission products as well as small quantities of corrosive liquids and laboratory chemicals. At times, the effluent consisted of water from the primary reactor coolant system, the periphery reactor cooling system and decontamination wastes from these systems. The crib and trench operated in tandem until 1985, when the 116-N-3 Crib became the primary liquid disposal facility for the N Reactor, and the 116-N-1 Crib and Trench were taken out of service.

The crib began operation in 1963. In 1965, the trench was added to enhance percolation capacity. The crib and trench were used for the disposal of N Reactor cooling water. The crib

was an open, rectangular excavation, 88.5 by 38.1 by 1.52 meters (290 by 125 by 5 feet deep). A sloped soil and gravel embankment formed the walls of the crib. The bottom was filled with a 0.9-meter (3-foot) thick layer of large boulders. In 1981, an additional stabilizing layer of large rock was added to the area around the weir box at the south end of the crib.

In 1965 the "zigzag" trench was added to enhance percolation capacity. It measured 15.3 x 488 x 3.7 meter (50 by 1,600 by 12 feet) and ran northeast in a zigzag pattern from the north side of the crib. Wooden poles were laid across the trench to support wire screens to keep birds out of the trench. In 1982, the bird screens were covered with a precast concrete panel cover to minimize wildlife intrusion and airborne contamination. The dimensions of the concrete cover is 15.9 X 424 X 0.20 meters (52 by 1390 by 0.67 feet thick). The panels were placed over the existing wooden beams and the bird screens. The edges of the trench cover were backfilled and covered with shotcrete. Spaces between cover panels were grouted.

Waste Type: Process Effluent

Waste Description: The unit received radioactive water containing activation and fission products and small quantities of corrosive liquids and laboratory chemicals at an average flow rate of approximately 5,680 liters per minute (1,500 gallons per minute) (note: the 8 million liters assumes the crib effluent was steady 24 hours per day). The crib received radioactive effluent streams from the 105-N and 109-N Buildings. After 1965, the trench received the same wastes as the crib. Operational contaminant inventory records from 1964 through 1985 show a total of 3,000 curies of tritium, 2,300 curies of cobalt-60, 1,900 curies of strontium-90, 2,600 curies of cesium-137, and 23 curies of plutonium-239 being released to the crib and trench. An estimate of dangerous wastes from the decontamination of the primary coolant system discharged annually include 2,800 kilogram (6,100 pounds) of hydrazine test solution, 2,800 kilograms (6,100 pound) of ammonia test solution, 3,500 kilograms (7,800 pounds) of chloride test solution and 1,800 kilograms (3,900 pounds) of fluoride test solution per year of operation. No actual amounts are available. The estimates include common floor drains that discharged to the crib.

Closure Info: Interim: Remedial action at the site began in April 2002 and concluded in October 2005. Excavation of the site involved removing the overburden materials, debris, the contaminated and uncontaminated structure, and underlying contaminated soil. Approximately 8 meters (26.2 ft) of piping was also removed between the crib and the 1315-N valve station during excavation of the sidewall of the crib. Closeout of this segment of piping was addressed using the verification sampling for the crib. The contamination within the boundaries of the UPR-100-N-31 waste site was also removed, but the unplanned release waste site is not proposed to be Interim Closed Out because of contaminant plumes that impacted active facilities and cannot be excavated until the active facilities are closed or relocated. Approximately 333,528 metric tons (387,652 tons) of contaminated materials were disposed at ERDF. The crib was excavated to a depth of 6.5 meters (21 feet). The trench was excavated to a depth of 4.5 meters (14.8 feet).

Note: The original CVP-2006-004, Revision 0, was submitted to Ecology in 2006. Ecology rejected the Waste Site Reclassification Form at that time due to the verification sample results exceeding Washington Administrative Code (WAC) 173- 303- 610 (2)(b)(i) closure performance standards for hexavalent chromium of 2.0 mg/kg (based on WAC 173- 340, amended 1996). In 2008, DOE agreed to submit a revised CVP. This revised cleanup verification package (CVP-2006-004, Rev. 1) further documents completion of remedial action for the 116-N-1 Crib and Trench. The revised CVP-2006-0004 Rev. 1 applies only to the 116-N-1 Crib and Trench, which does not encompass the entire 1301-N TSD unit boundary.

Code: 116-N-2

Classification: Accepted

Names: 116-N-2; 1310-N Chemical Waste Storage Tank; 1310-N Waste Storage Area; The Golf Ball

Reclassification Interim Closed Out (5/7/2013)

Type: Storage Tank	Start Date: 1/1/1964
Status: Inactive	End Date: 1/1/1987

Description: The waste site has been remediated and Interim Closed Out. 116-N-2 Facility complex consisted of piping, pumps, a transfer tank (commonly referred to as the silo) and a large, spherical storage tank (commonly referred to as the Golf Ball). The site was used as a collection tank for N Reactor primary piping decontamination wastes. The 3.4E+06-liter (9.0E+05-gallon) spherical tank was partially buried in the ground. A compacted soil radiation barrier, 7.6 meters (25 feet) high, surrounded the tank on three sides.

Location: The unit was located northeast of the 105-N Reactor Building, adjacent to the 116-N-1 Crib.

**Related Sites/
Structures:** 116-N-2 is associated with portions of the 100-N-63 piping.

**Process
Description:** The 116-N-2 Tank was used to temporarily store and neutralize acidic decontamination waste from the internal decontamination of the N Reactor primary loop through an underground pipeline. An additional, small scale transfer line enters the tank from the N Reactor Building. The primary loop was decontaminated every three to five years. Each decontamination event resulted in approximately 2.3E+06 liters (6.0E+05 gallons) of contaminated solution. The decontamination solutions contained approximately 80,000 liters (21,000 gallons) of 70% phosphoric acid and 180 kilograms (400 pounds) of diethylthiourea. The solutions were neutralized in the tank. From 1968 to 1972, the neutralized solutions were pumped into trucks parked on the east side of the containment area and transported to 200 Area for disposal. After 1972, the solution was sent to the 1314-N Liquid Waste Loadout Station. The solutions were also discharged to the 116-N-1 Crib, if necessary.

Waste Type: Process Effluent

**Waste
Description:** Phosphoric acid used in the internal decontamination of the primary loop of the reactor, and successive rinse water were temporarily stored in this tank before being shipped to the 200 Area storage tanks. The liquid in the tank was neutralized with sodium hydroxide. Three unplanned releases of decontamination solution occurred at this site which cumulatively totaled 3.43E+05 liters (90,600 gallons).

Closure Info: Interim (5/7/2013): Remedial action of the 116-N-2 (Golf Ball) waste site was performed between March 1, 2011 and April 26, 2012. Equipment decontamination was conducted within the southeast corner of the waste site excavation, and that area was remediated May 7 and 8, 2012. The maximum depth of the excavation was 13 meters (42.7 ft) bgs and resulted in the removal of approximately 11,144 bank cubic meters (BCM) (14,576 bank cubic yards [BCY]) of soil and debris. The debris consisted of rock, sand, and piping material. The contaminated soil and debris were directly loaded out for disposal at the Environmental Restoration Disposal Facility (ERDF). Also removed with the 116-N-2 excavation were the UPR-100-N-5 and UPR-100-N-25 waste sites, as well as portions of the 100-N-84 and 100-N-63 pipelines. A section of the 100-N-63:2 pipeline remained on a side slope in the northern part of the excavation until it was remediated between March 22, and 25, 2013. No anomalous material was found during remediation. No in-process samples were collected for the 116-N-2 grouping of waste sites.

Clean padding material (soil and gravel) had been previously placed on the ground surface south of the excavation to cover radiological contamination that resulted from the previous D4 activities to remove the golf ball and silo structures. The padding material and approximately 2 meters (6.5 ft) of soil below the padding was scraped and removed for disposal at ERDF.

Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Code: 116-N-3	Classification: Accepted
Names: 116-N-3; 1325-N Crib and Trench; 1325-N Liquid Waste Disposal Facility	Reclassification: Interim Closed Out (12/23/2002)
Type: Crib	Start Date: 1/1/1983
Status: Inactive	End Date: 1/1/1991

Description: The site has been remediated and Interim Closed Out.

Location: The site was located at the northeast corner of the 100-N Area outside the fence line, 305 meters (1,000 feet) east and 61 meters (200 feet) north of the 1301-N Crib.

Related Sites/ Structures: 116-N-3 is associated with the 100-N-63, 100-N Reactor (1314-N, 116-N-1 and 116-N-3) TSD Underground Pipelines and concrete encased pipe by-pass structure.

Process Description: The 116-N-3 Crib (1325-N LWDF) was designed for the disposal of liquid waste percolation through the soil column. It was built to replace the 116-N-1 Crib and first received N Reactor effluent in 1983. The 116-N-3 Trench was activated in September 1985 to provide additional disposal capacity. Effluent reportedly never overflowed beyond the first earthen dam in the trench. The LWDF has not received waste since February 1987 and was closed under interim status.

The process design capacity for the 1325-N LWDF was 1.64E+07 liters (4.32E+06 gallons) per day. The design capacity reflected the maximum volume of water discharged daily, rather than the physical capacity of the unit.

This unit consisted of a rectangular concrete crib that measured 76.25 by 73.20 meters (250 by 240 feet) and a percolation trench. The trench, located on the northeast side of the crib, measured 3 meters (10 ft) wide, 2.1 meters (7 ft) deep, and 915 meters (3,000 ft) in length. It was divided into four equal sections by three earthen dams. The trench was also covered with concrete panels. Effluent was delivered to the 116-N-3 Crib through a 448 meter (1,468 foot) long by 0.9 meter (Diameter Nominal [DN] 900) (36 inch) diameter pipeline that entered the crib at the southwest end. A covered concrete by-pass structure ran parallel to the pipeline and connected to the crib at the southwest end. The by-pass structure was built at the same time as the 1312-N Retention Basin (also known as the Liquid Effluent Retention Facility or LERF).

Waste Type: Process Effluent

Waste Description: This unit received radioactive activation and fission products and small quantities (below regulatory limits) of corrosive liquids and laboratory chemicals. Dangerous waste code numbers include: F003, D002, D006, D007, D008, D009, U133, WC02, and WT02.

Closure Info: Interim: A portion of the pipeline 100-N-63:1 was remediated with the 116-N-3 Crib and Interim Closed Out in CVP-2002-00002. For purposes of the CVP and consistent with the permitted TSD site designation, the 116-N-3 Crib and Trench, the 100-N-63:1 Pipeline, and the bypass structure are collectively referred to as the 116-N-3 site.

Remediation at the 116-N-3 site began on July 21, 2000. Excavation of the site involved removing the overburden materials, debris, the contaminated and uncontaminated structure, and underlying contaminated soil. Based on field screening, overburden materials identified as potentially clean were placed in stockpiles for potential use as backfill. The pipeline bypass (100-N-63:1) trenches were excavated completely and clean backfill was used to provide a temporary road for utilities and crossing. Contaminated materials were disposed of at the ERDF. On December 21, 2001, the excavation was completed. Only the portion of the trench near the crib was excavated. Effluent in the trench percolated into the soil column before overflowing the first earthen dam. Thus, the remainder of the trench beyond the first dam was not affected by waste disposal activities and did not require remediation. The excavation for the

entire 116-N-3 site was approximately 21,980 square meters (236,590 sq. ft.) in area. Soils were removed beneath the crib and trench to a minimum of 1.5 meters (5 ft) below the engineered structures. Approximately 140,270 metric tons (154,578 tons) of material from the site were disposed of at the ERDF.

Code:	116-N-4	Classification:	Accepted
Names:	116-N-4; 1300-N Emergency Dump Basin	Reclassification	Interim Closed Out (5/14/2013)
Type:	Retention Basin	Start Date:	1/1/1963
Status:	Inactive	End Date:	1/1/1987

Description: The waste site has been remediated and Interim Closed Out. It consisted of the 1300-N Emergency dump basin. The 116-N-4 Emergency Dump Basin was a rectangular shaped, outdoor, concrete storage basin with a 10.7-centimeter (0.188-inch) carbon steel liner. During the basin demolition in 2011, hot spot contamination and a potential plume was identified on the north end of the basin excavation. This contamination was deferred to the 100-N-64:33 (105/109-N Cooling Water Effluent Underground Pipelines) site. Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Location: The basin was located on the west side of the 109-N Building and the 105-N Reactor Building.

Release Description: The basin leaked to the soil at the northeast and northwest corners of the basin during the early 1980s.

Related Sites/ Structures: The basin is associated with suspected unplanned releases 100-N-29, 100-N-30 and 100-N-38. It is also associated with 100-N-64:3, due to the hot spot contamination found on the north side of the basin.

Process Description: The 116-N-4 Emergency Dump Basin (EDB) was originally designed to receive emergency single pass cooling water from N Reactor. In the late 1960's the unit was determined to be insufficient for its original purpose because it did not have adequate capacity for the volume of coolant used during an emergency cooling operation. It was replaced with the 1304-N Emergency Dump Tank (EDT) in 1973. The EDB was never used for its original purpose. Instead, 116-N-4 received contaminated liquid generated during the periodic blowdown of the steam generators located in the 109-N Building from 1973 to 1987. This condensate contained low levels of radioactive contaminants. It also received radioactive waste from the N Reactor Lift Station. Since the shutdown of N Reactor in 1987, approximately 2.0E+06 liters (7.5E+05 gallons) of water has been maintained in the basin to cover the layer of sludge in the bottom of the basin to prevent it from drying and causing airborne contamination. Non-filtered river water has been added as needed to maintain an adequate water level.

Waste Type: Sludge

Waste Description: Sediments were sampled in 1995 and found to contain radionuclides exceeding Westinghouse Hanford Company Category I limits and heavy metal concentrations below Resource Conservation and Recovery Act (RCRA) limits. The site is, therefore, radiologically contaminated but is not a mixed waste site. Radionuclide and heavy metal characterization is provided in BHI-00731. Since basin leakage has occurred, additional contaminants may be expected in the soils beneath the basin. Contaminants in the Dump Basin liquid include average concentrations of 6.25 E+05 of H-3, 6.12 E+01 of C0-60, 5.70 E+04 of Sr-90, 2.51 E+01 of Zr-95, <5.16 E+01 of Ru-106, 2.16 E+01 of Sb-125, >>5.16 E+00 of Cs-134, 9.27 E+02 of Cs-137, 1.62 E-02 of Pu-239 and 1.82 E-01 of Pu.

Closure Info: Interim (5/14/2013): DOE agreed to defer the remediation of the "hot spots" plume (north end of the 116-N-4) to occur during the excavation of the collocated 100-N-64 and UPR-100-N-7 waste sites. The northern portion of the 116-N-4 waste site was reassigned to waste site 100-N-64:3 (105/109-N Cooling Water Effluent Underground Pipelines) on April 16, 2013 per the

agreement.

Remedial action at the 116-N-4 Emergency Dump Basin (EDB) waste site was performed between March 21 and June 29, 2011. Due to safety issues involved in removing the fuel storage basin, the northern section of the 116-N-4 waste site was not remediated and was deferred to the 100-N-64 waste site excavation (WCH 2011c). Excavation continued until all debris and contamination associated with the waste site had been removed. Approximately 413 bank cubic meters (BCM) (540 bank cubic yards [BCY]) of contaminated soil and debris was direct loaded for disposal at the Environmental Restoration Disposal Facility (ERDF). Approximately 1,680 BCM (2,197 BCY) of contaminated soil and debris was stockpiled and later loaded out for disposal at the (ERDF). Approximately 1,105 BCM (1,445 BCY) of additional contaminated soil was later direct loaded for disposal at the ERDF for a final disposal volume of 3,198 BCM (4,182 BCY). No stained soil or anomalous material were discovered during remediation activities.

During remediation of the 116-N-4 EDB, it was recommended to include excavation only to a depth necessary to remove the west and south walls and the basin steel structure. The north and east walls (closest to the 105-N/109-N Buildings) were left in place to prevent an unstable condition of other structures, including the 105-N/109-N Buildings and adjacent piping (sitecode 100-N-64). The east wall was eventually removed during the excavation of the 116-N-4 EDB. The remaining contamination from the north and east walls was removed during deactivation, decontamination, decommissioning, and demolition (D4) removal of the fuel storage basin, which was completed in spring 2012. The west excavation boundary borders the 100-N-57, 1304-N Emergency Dump Tank waste site excavation and is included in the 100-N-57 work instruction. Unplanned releases associated with the 116-N-4 waste site will be reclassified separately.

Code:	118-N-1	Classification:	Accepted
Names:	118-N-1; 1303-N Radioactive Dummy Burial Facility; 1303-N Spacer Silos; 100-N Area Silos; 100-N Area Spacer Silos; 118-N	Reclassification	Interim Closed Out (8/16/2013)
Type:	Silo	Start Date:	1/1/1963
Status:	Inactive	End Date:	1/1/1995
Description:	The site has been remediated and Interim Closed Out. The 1303-N Spacer Silos consisted of three buried silos used for temporary storage of irradiated metallic fuel rod spacers removed from the 105-N Reactor. The silos were covered and surrounded with an earth berm and had a 30.5 meters (100 ft) reinforced concrete retaining wall along the west side. The soil berm had scant vegetation growing on it and a single vent stack protruded from the mound. A chain link fence surrounded the site on three sides and was posted with "Contamination Area, Underground Radioactivity and Soil Contamination Area" signs. The western side was barricaded with a 2.1 meter (7 foot) concrete wall. Following surface stabilization in 1998, the site was posted with Underground Radioactive Material signs. The silos were demolished in 2012.		
Location:	The site was located outside the northwest corner of the 105-N Building, approximately 30 meters (98 feet) northwest of the 105-N Transfer Area.		
Related Sites/ Structures:	The spacer transfer line (dummy disposal line) became part of 100-N-84:6. UPR-100-N-3 and UPR-100-N-12 were documented leaks in the spacer transfer line.		
Process Description:	The site contained three concrete silos, each 4.9 meters (16 feet) in diameter. Periodically, the contents were shipped to the 200 Area Burial Grounds for permanent disposal. Two of the silos are open bottomed.		

Silo 1 began operation in 1963 and was a 30.5 centimeter (12 inch) thick reinforced concrete culvert 4 meters (13 ft) in diameter and 7.6 meters (25 ft) long, buried upright and extending about 7.1 meters (20 ft) below grade. Approximately 0.9 meters (3 ft) of packed aluminum turnings were placed at the base of silo 1. Silos 2 and 3 were added in 1967 and were corrugated, galvanized-steel culverts 5.2 meters (17 ft) in diameter and 10.7 meters (35 ft) long that extended 9.1 meters (30 ft) below grade. All three silos were standing vertically on end with the top 1.5 meters (5 ft) being above grade with concrete covers.

When a silo was completely full, the spacers were removed and shipped to the 200 Area burial grounds for disposal.

Waste Type: Equipment

Waste Description: This site received byproduct radioactive metallic fuel spacers from the reactor. Quantities were variable based upon reactor operation levels. The radioactively contaminated fuel spacers were temporarily stored in the underground silos and then shipped to the 200 Area Low-Level Burial Grounds for disposal. All spacers were removed from the silos in September 1995.

Closure Info: Interim (8/16/2013): The 118-N-1 silos were remediated in 2012. Approximately 8,680 bank cubic meters of soil was removed by the Field Remediation project from January 4, 2013, through March 22, 2013. Radiological surveys were performed after the soil was removed. All waste was direct loaded during the excavation and disposed at the ERDF. No anomalies were encountered during the remedial action activities.

Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Code: 120-N-1	Classification: Accepted
Names: 120-N-1; 1324-NA Percolation Pond	Reclassification: None
Type: Pond	Start Date: 1/1/1977
Status: Inactive	End Date: 1/1/1991

Description: The site was remediated in September/October 2000. The remedial activity for sites 100-N-58, 120-N-1 and 100-N-2 was documented in CVP-2001-00021. A Reclassification form was completed for 100-N-58. However for 120-N-1 and 120-N-2, Washington State Department of Ecology rejected the certification of closure from DOE. A post-closure groundwater plan must be submitted to Ecology and approved prior to approval of the Certification of Closure documentation.

Location: The 120-N-1 site was co-located with 100-N-58, 120-N-2 sites in the 100-N Area in the 100-NR-1 Operable Unit. These sites are about 100 m (328 ft) southeast of the 163-N Demineralization Plant Building, and are approximately 400 m (1,312 ft) from the Columbia River.

Release Description: The site has been remediated. This site received intermittent releases of corrosive liquids from the 163-N Demineralized Water Treatment Plant prior to May 1986. The alkaline Hanford soils acted as a buffer to neutralize acidic wastes.

Related Sites/Structures: The 163-N Building, 183-N Building, 120-N-2 (1324-N) Surface Impoundment, and 100-N-58 (1324-N South Settling Pond) are associated with this site.

Process Description: In 1977 the 120-N-1, 120-N-2, and 100-N-58 sites were initially constructed as the East Percolation Pond and North and South Settling Ponds, respectively. These unlined ponds received 163-N anion/cation regeneration effluent as well as the 183-N Filtered Water Plant filter backwash effluent. In 1982, because of pond percolation problems, the 183-N filter

backwash was rerouted to an effluent disposal pond (130-N-1). During this time period the 100-N-58 site was backfilled.

Liquid wastes were transferred to the north and south settling ponds where particulates were allowed to settle out. After the solids, primarily from the filter backwash effluent, had settled the contents of the settling ponds were transferred to the percolation pond. Between 1983 and 1986, the settling ponds were closed and the percolation pond was enlarged. The regeneration effluent was then discharged directly to the percolation pond through a 20-centimeter (8-inch) diameter PVC valved pipeline. The filter backwash effluent was then discharged to the 130-N-1 Filter Backwash Disposal Pond through a rerouted 40-centimeter (16-inch) diameter PVC pipeline that ran under the 100-N-58 South Settling Pond. The south settling pond was backfilled. Effluent was treated in the percolation pond by the alternate addition of acidic (cation) column regeneration effluent and alkaline anion column regeneration effluent. This alternate addition of low and high pH effluent served to neutralize the effluents. The percolation pond also made use of the buffering capacity and calcareous nature of the soil underlying it to neutralize these corrosive wastes.

Waste Type: Process Effluent

Waste Description: Until 1983, the percolation pond received corrosive wastes from the regeneration of the demineralizer column in the 163-N Demineralizer Plant and filter backwash water. It also received nonregulated neutralized waste from the 1324-N Surface Impoundment and non-regulated process and cooling water from the 163-N Plant. Discharge of dangerous wastes was discontinued in April 1986. After November 1988, the percolation pond received neutralized waste water with a pH range between 4 and 11. The percolation pond no longer receives wastes. Sampling and analysis data of surface soils and sediment are listed in DOE/RL-90-22.

Closure Info: Interim: The site was remediated in September/October 2000. A Reclassification form was completed for 100-N-58. However for 120-N-1 and 120-N-2, Washington State Department of Ecology rejected the certification of closure from DOE. A post-closure groundwater plan must be submitted to Ecology and approved prior to approval of the Certification of Closure documentation.

Remedial/corrective action field activities at the 120-N-1, 120-N-2, and 100-N-58 sites were conducted in September 2000, and included the removal and disposal of miscellaneous structural debris-type items. A total of about 120 cubic meters (4,238 cu ft) of material was removed from the sites. The material consisted of about 15 cubic meters (530 cu ft) of concrete, 96 cubic meters (3,390 cu ft) of high-density polyethylene (HDPE) liner, 4 cubic meters (141.3 cu ft) of polyvinyl chloride (PVC) piping, and 0.5 cubic meters (17.7 cu ft) of steel fencing material. The material was disposed of in the inert demolition landfill in the 100-H Area. Waste designation and disposal documentation is kept in project files. The two 20.3-cm (8-in.) diameter influent pipelines were sampled and remain in place.

Closure performance standards were established by the Washington State Department of Ecology, in concurrence with the U.S. Department of Energy, Richland Operations Office. These performance standards are documented in the 100-NR-1 Treatment, Storage, and Disposal Units Corrective Measures Study/Closure Plan (CMS/CP) (DOE/RL-90-22) and the Remedial Design Report/Remedial Action Work Plan for the 100-NR-1 Treatment, Storage, and Disposal Units (RDR/RAWP) (DOE/RL-2000-16). Permit conditions were established in the Hanford Facility Dangerous Waste Permit (Ecology 1994). While sites 120-N-1, 120-N-2, and 100-N-58 are not included in a Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) record of decision (ROD) corrective action activities have been documented in CVP-2001-00021 (CVP).

The soil investigation conducted at these sites in 1992 and 1993 for the CMS/CP indicated that the site did not require soil remediation. Therefore, the selected remedial/corrective action

included the removal and disposal of the miscellaneous site structures, including the 120-N-2 liner system, a small sampling shed, fencing, and other miscellaneous debris. The CMS/CP soil investigation indicated that there generally are no contaminants of concern (COCs) for these waste sites. However, because a former overflow area and the waste site influent pipelines required additional sampling (as specified by the CMS/CP), these sites were included in the Sampling and Analysis Plan for the 100-NR-1 Treatment, Storage, and Disposal Units During Remediation and Closeout (SAP) (DOE-RL-2000-07). The verification samples collected under the sampling and analysis plan were analyzed for generally the same inorganic metals and wet chemical anions listed in the CMS/CP soil investigation. The samples were also analyzed for pH. The analytical results from the additional soil sampling and the pipeline scale sampling are presented in Appendix A of the CVP. The analytical results of the soil samples are consistent with the findings of the CMS/CP: soil concentrations are at or below Hanford Site or Washington State background concentrations.

Code:	120-N-2	Classification:	Accepted
Names:	120-N-2; 1324-N Surface Impoundment	Reclassification	None
Type:	Surface Impoundment	Start Date:	1/1/1986
Status:	Inactive	End Date:	1/1/1988

Description: The site was remediated in September/October 2000. The remedial activity for sites 100-N-58, 120-N-1 and 120-N-2 was documented in CVP-2001-00021. A Reclassification form was completed for 100-N-58. However for 120-N-1 and 120-N-2, Washington State Department of Ecology rejected the certification of closure from DOE. A post-closure groundwater plan must be submitted to Ecology and approved prior to approval of the Certification of Closure documentation.

Location: The 120-N-2 site was co-located with 120-N-1 and 100-N-58 sites in the 100-N Area in the 100-NR-1 Operable Unit of the Hanford Site in southeastern Washington State. These sites are about 100 meters (328 ft) southeast of the 163-N Demineralization Plant Building, and are approximately 400 meters (1,312 ft) from the Columbia River.

Related Sites/ Structures: The 163-N Building, 183-N Building, 100-N-58 (1324-N) South Settling Pond and 120-N-1 (1324-NA) Percolation Pond are associated with this site.

Process Description: In 1977 the 120-N-1, 120-N-2, and 100-N-58 sites were initially constructed as the East Percolation Pond and North and South Settling Ponds, respectively. These unlined ponds received 163-N anion/cation regeneration effluent as well as the 183-N Filtered Water Plant filter backwash effluent. In 1982, because of pond percolation problems, the 183-N filter backwash was rerouted to an effluent disposal pond (130-N-1). During this time period the 100-N-58 site was backfilled. Prior to 1982, approximately 1.63E+06 liters/day (4.3E+05 gallons/day) of acidic and caustic effluents were transferred by underground lines to the 120-N-2 Surface Impoundment to be neutralized. Caustic anion regeneration effluent was generally neutralized in the facility by the addition of acidic cation regeneration effluent. Acid cation regeneration effluent was similarly neutralized by the addition of caustic anion regeneration effluent. Once neutralization was complete, the neutralized effluent was discharged to the 120-N-1 Percolation Pond via a 30-centimeter (12-inch) polyvinyl chloride (PVC) drainline and/or a 30-centimeter (12-inch) PVC overflow line.

Waste Type: Process Effluent

Waste Description: The 1324-N Surface Impoundment received corrosive regeneration effluent and process and cooling water from the 163-N Demineralization Plant. Analytical results from surface soils and sediment test pit sampling are reported in DOE/RL-90-22.

Closure Info: Interim: The site was remediated in September/October 2000. A Reclassification form was

completed for 100-N-58. However for 120-N-1 and 120-N-2, Washington State Department of Ecology rejected the certification of closure from DOE. A post-closure groundwater plan must be submitted to Ecology and approved prior to approval of the Certification of Closure documentation.

Remedial/corrective action field activities at the 120-N-1, 120-N-2, and 100-N-58 sites were conducted in September 2000, and included the removal and disposal of miscellaneous structural debris-type items. A total of about 120 cubic meters (4,238 cu ft) of material was removed from the sites. The material consisted of about 15 cubic meters (530 cu ft) of concrete, 96 cubic meters (3,390 cu ft) of high-density polyethylene (HDPE) liner, 4 cubic meters (141.3 cu ft) of polyvinyl chloride (PVC) piping, and 0.5 cubic meters (17.7 cu ft) of steel fencing material. The material was disposed of in the inert demolition landfill in the 100-H Area. Waste designation and disposal documentation is kept in project files. The two 20.3-cm (8-in.) diameter influent pipelines were sampled and remain in place.

Closure performance standards were established by the Washington State Department of Ecology, in concurrence with the U.S. Department of Energy, Richland Operations Office. These performance standards are documented in the 100-NR-1 Treatment, Storage, and Disposal Units Corrective Measures Study/Closure Plan (CMS/CP) (DOE-RL-90-22) and the Remedial Design Report/Remedial Action Work Plan for the 100-NR-1 Treatment, Storage, and Disposal Units (RDR/RAWP) (DOE/RL-2000-16). Permit conditions were established in the Hanford Facility Dangerous Waste Permit (Ecology 1994). While sites 120-N-1, 120-N-2, and 100-N-58 are not included in a Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) record of decision (ROD) corrective action activities have been documented in CVP-2001-00021 (CVP).

The soil investigation conducted at these sites in 1992 and 1993 for the CMS/CP indicated that the site did not require soil remediation. Therefore, the selected remedial/corrective action included the removal and disposal of the miscellaneous site structures, including the 120-N-2 liner system, a small sampling shed, fencing, and other miscellaneous debris. The CMS/CP soil investigation indicated that there generally are no contaminants of concern (COCs) for these waste sites. However, because a former overflow area and the waste site influent pipelines required additional sampling (as specified by the CMS/CP), these sites were included in the Sampling and Analysis Plan for the 100-NR-1 Treatment, Storage, and Disposal Units During Remediation and Closeout (SAP) (DOE-RL-2000-07). The verification samples collected under the sampling and analysis plan were analyzed for generally the same inorganic metals and wet chemical anions listed in the CMS/CP soil investigation. The samples were also analyzed for pH. The analytical results from the additional soil sampling and the pipeline scale sampling are presented in Appendix A of the CVP. The analytical results of the soil samples are consistent with the findings of the CMS/CP: soil concentrations are at or below Hanford Site or Washington State background concentrations.

Code:	120-N-3	Classification:	Accepted
Names:	120-N-3; 163-N Neutralization Pit and French Drain	Reclassification	Interim Closed Out (3/20/2013)
Type:	French Drain	Start Date:	1/1/1963
Status:	Inactive	End Date:	1/1/1988
Description:	The waste site has been remediated and Interim Closed Out. It was a concrete walled pit that measured 10.2 meters (33.3 feet) by 2.8 meters (9 feet) and is 2.4 meters (8 feet) deep. The drain structure was inside the concrete pit. The pit and the drain structure discharged to the soil (per H-1-37249).		

Location: The site is located west of the 163-N Building.

Release Description: Intermittent small releases of sulfuric acid and sodium hydroxide from the 163-N Demineralized Water Treatment Plant day-storage tanks were disposed to the soil at this location. The alkaline Hanford soils acted as a buffer to neutralize acidic wastes.

Process Description: Intermittent, small releases of sulfuric acid and sodium hydroxide were discharged from 163-N De-mineralized Water Treatment day storage tanks to the site. Two pipelines from the 163-N facility day storage tanks entered the neutralization pit and french drain. The caustic material was released directly to the pit via the western-most pipe. The acid was released to the limestone filled french drain via the eastern most pipe. The french drain was located wholly within the concrete-walled pit.

Waste Type: Chemicals

Waste Description: The unit received unknown amounts of corrosive liquids, such as sodium hydroxide and sulfuric acid.

Closure Info: Interim (3/20/2013): Remedial action at the 120-N-3 waste site was performed August 10, 2011, through January 31, 2012. The excavation continued to a depth of 5 meters (16.4 ft) below ground surface resulting in approximately 3,917 bank cubic meters (5,123 bank cubic yards) of contaminated soil and debris removed for disposal at the Environmental Restoration Disposal Facility (ERDF). All material was direct-loaded from the excavation. No waste staging pile areas are associated with the site.

The waste material removed from the 120-N-3 waste site consisted of soil, concrete, and rebar. No anomalous materials were encountered during the excavation. There are no overburden piles or waste staging pile areas associated with the 120-N-3 waste site.

During remediation of the 120-N-3 waste site, suspect oil-stained soil was observed on the east sidewall of the excavation. This staining was determined not related to the 120-N-3 waste site, but informational in-process soil samples were collected from the stained area. This stained area will be addressed with 100-N-106.

Code: 120-N-4	Classification: Accepted
Names: 120-N-4; 1310-N Hazardous Waste Storage Area; 1310-N Non-Hazardous Waste Pad; 1310-N Waste Oil Storage Pad	Reclassification: Interim Closed Out (5/27/2014)
Type: Storage Pad (<90 day)	Start Date: 1/1/1985
Status: Inactive	End Date: 1/1/1989

Description: The waste site was remediated and Interim Closed Out. The 1310-N Hazardous Waste Storage Area was a concrete pad approximately 20 by 25 meters (70 by 80 feet), surrounded with a concrete berm (curb) and locked chain-link fence. Outside the pad the ground surface is gravel. A small open shed is in the southwest corner of the pad. The site was posted as a Radioactive Materials Area, and is also posted "Contaminated Lead Storage Area (For Re-Use)." In April 2000, the area contained several wrapped objects marked with radioactive warning signs.

Location: The site is located immediately south of the 1310-N Facility.

Release Description: Waste sites 100-N-26 and 120-N-4 were impacted by a raw water pipeline break on December 11, 2008. The regulators and tribes have requested that this release information be noted in WIDS.

During the removal of the concrete pad at the 1524-N Hazardous waste storage facility on

December 11, 2008 a 1.5 inch feed line from the export water line was inadvertently contacted during the excavation of the concrete pad. A rupture of the 12 inch export water line and a release of at least 50,000 gallons of raw water onto the surrounding area resulted. A temporary berm was constructed around the area using excess clean 100 Area Borrow Pit material to contain the release and control potential spread of radiological contamination associated with the 1524-N pad. Once the water line was turned off the water in the area immediately percolated into the ground.

In-process and post-event surface soil radiological field survey results did not find any contamination spread as a result of the water release. A follow-up review of nearby monitoring wells as well as the standard waste site confirmatory sampling will be used to ascertain potential impacts/conditions.

Process Description: The unit stored waste held in drums and containers from 1985 to 1989. The waste oil drums have been removed. The pad is (in April 12, 2000) was used to store lead lined burial casks and radioactive materials.

Closure Info: Interim (5/27/2014): The concrete pad comprising the 120-N-4 waste site was removed and disposed to the Environmental Restoration Disposal Facility (ERDF) between December 2008 and February 2009. During the removal of the concrete pad on December 11, 2008, a 1.5 inch feed line from the export water line was inadvertently contacted during the excavation of the concrete pad. A rupture of the 12 inch export water line and a release of at least 50,000 gallons of raw water onto the surrounding area resulted. A temporary berm was constructed around the area to contain the release and control potential spread of radiological contamination associated with the 1524-N pad. Once the water line was turned off the water in the area immediately percolated into the ground. The soil underlying the concrete pad was evaluated for residual contamination.

Between October 8 and October 10, 2013, 956 bank cubic meters (BCM) of material from the 120-N-4 site was directly loaded out for disposal at ERDF. Along with this, approximately 1 BCM of wire and concrete debris were removed. This excavation was approximately 1 meter (3.3 ft) deep. No anomalies were discovered.

Code:	120-N-7	Classification:	Accepted
Names:	120-N-7; 108-N Acid Unloading Facility French Drain	Reclassification	Interim Closed Out (7/2/2013)
Type:	French Drain	Start Date:	1/1/1963
Status:	Inactive	End Date:	1/1/1987

Description: The site has been remediated and Interim Closed Out. It had been a vertical broken vitrified clay pipe extending above grade on a discolored soil mound. Limestone was visible inside the broken pipe. The overhead lead pipe dripped acid from the boom hose funnel to the french drain. It was visible at grade level, just north of the french drain.

Location: The 120-N-7 French Drain was located at the Railroad Car Unloading Facility, approximately 31 meters (100 feet) east of the 108-N Building.

Release Description: The french drain received unknown amounts of sulfuric acid in intermittent discharges. The average amount released is believed to be less than 3.8 liters (1 gallon).

Process Description: The 120-N-7 french drain was used for containment of small releases of sulfuric acid from an overhead transfer boom, which offloaded sulfuric acid from railroad cars or tank trucks. A lead funnel and pipe directed the small releases to the french drain. Prior to remediation the site appeared as a broken vertical vitrified clay pipe extending above grade on a discolored soil mound. The clay pipe was 1.22 meters (4.0 ft) deep, 0.9 meters (3 ft) in diameter, and filled

with limestone. The lead pipe delivered the acid drips from the boom hose funnel to the french drain. This site was operational from 1963 to 1987.

Waste Type: Chemical Release

Waste Description: The unit received unknown amounts of sulfuric acid in intermittent discharges. Each discharge is estimated to have averaged less than 3.8 liters (1 gallon) of liquid. The concentrated acid may have etched lead from the funnel and pipe as it discharged to the french drain.

Closure Info: Interim (7/2/2013): The 120-N-7 waste site was remediated between December 20 and December 27, 2012. Approximately 145 bank cubic meters (190 cubic yards) of potentially contaminated material was removed and disposed to the Environmental Restoration Disposal Facility. The removed material consisted of stained soil, railroad ties, and lead-cored communication cable.

Code: 124-N-1

Classification: Accepted

Names: 124-N-1; 124-N-1 Septic Tank; 1607-N1; 100-N Sanitary Sewer System No. 1

Reclassification: Interim Closed Out (7/2/2013)

Type: Septic Tank

Start Date: 1/1/1963

Status: Inactive

End Date:

Description: The waste site has been remediated and Interim Closed Out. The cesspool structure and underlying soils were excavated in 2012. The septic tank had been previously demolished in 2009. The upper surface of the 124-N-1 Septic Tank was visible and measured 1.5 by 1 meters (58 by 40 inches) and stood 36 centimeters (14 inches) above grade. The circular seepage pit had 18.4 square meters (200 square feet) of infiltration area and 8,700 liters (2,300 gallons) of capacity. Sanitary wastes entered the septic tank through a 10-centimeter (4-inch) vitrified clay pipe connecting the septic tank to the cesspool.

Location: The septic tank and seepage pit were located about 14 meters (15 yards) south of the south wall of the 163-N Water Treatment Building.

Related Sites/ Structures: This site supported the 163-N Water Treatment Building.

Waste Type: Sanitary Sewage

Waste Description: This unit receives approximately 5,300 liters per day (1,400 gallons per day) of sanitary sewage.

Closure Info: Interim (7/2/2013): The 124-N-1 Sanitary Sewer System consisted of a septic tank and a cesspool. The septic tank was removed by the Deactivation, Decontamination, Decommissioning, and Demolition (D4) Project in June and September 2009 and disposed at the Environmental Restoration Disposal Facility (ERDF). Removal of the cesspool structure and excavation of underlying soils associated with the entire septic system was performed on November 28, 2012 and continued through February 8, 2013. In addition, the portion of the 100-N-84:5 sanitary pipeline that connected the septic tank with the cesspool was removed.

Red-stained soil observed during the initial excavation was sampled on December 6, 2012, and additional soil was removed from the excavation. Approximately 721 bank cubic meters of contaminated soil and debris was directly loaded out for disposal to ERDF.

One anomaly was encountered during the remedial action activities. The anomaly was a 1.2 meter by 1.2 meter by 2.1 meter (4 ft by 4 ft by 7 ft) concrete box that was found to be empty and was disposed to ERDF.

Code: 124-N-2	Classification: Accepted
Names: 124-N-2; 124-N-2 Septic Tank; 1607-N2; 100-N Sanitary Sewer System No. 2	Reclassification: Interim Closed Out (8/21/2013)
Type: Septic Tank	Start Date: 1/1/1963
Status: Inactive	End Date: 1/1/1987

Description: The waste site has been remediated and Interim Closed Out. It was a septic tank and seepage pit. The seepage pit provided approximately 18.4 square meters (200 square feet) of infiltration surface area and 8,700 liters (2,300 gallons) of fluid storage.

Location: The site was located southeast of the 182-N Building.

Process Description: This unit received sanitary sewage from the 182-N Building. The seepage pit provided approximately 18.4 square meters (200 sq. ft.) of infiltration surface area and 8,700 liters (2,300 gal) of fluid storage. During the period of operation, the septic tank received an estimated 757 liters/day (200 gal/day) of sanitary sewage from the 182-N Building.

Waste Type: Sanitary Sewage

Waste Description: During the period of operation, this unit received an estimated 757 liters/day (200 gallons/day) of sanitary sewage from the 182-N Building.

Closure Info: Interim (8/21/2013): The 124-N-2 waste site was remediated between April 12, 2012, and April 18, 2012, along with the remediation of the 182-N Building by the Deactivation, Decontamination, Decommissioning, and Demolition (D4) Project. The septic tank excavation extended approximately 1.7 meters (5.6 ft) below the original ground surface. Materials from the 124-N-2 waste site could not be physically separated from the 182-N Building materials. Therefore, an accurate total volume excavated from the 124-N-2 waste site is unknown. A volume of approximately 240 BCM (314 BCY) of material is estimated to have been excavated from the 124-N-2 waste site by the D4 Project. Materials removed from the excavation included the demolished seepage pit, concrete, soil, and rocks. Additional remediation of the 124-N-2 waste site was performed by the Field Remediation (FR) Project between January 21 and 30, 2013. Approximately 371 BCM (485 BCY) of material was excavated from the 124-N-2 waste site for direct disposal at the ERDF.

On March 28, 2013, remediation at the 124-N-2 waste site resumed to further excavate the entire footprint of the 124-N-2 waste site. The excavation was expanded to the east to remove the adjacent 100-N-84:4 pipelines and to allow the 124-N-2 excavation to proceed to a greater depth. The 124-N-2 excavation was completed on April 25, 2013, and final depth of the excavation is approximately 4.9 to 5.1 meters (16 to 17 ft below ground surface), with some locations extending deeper. The 100-N-84:5, 100-N Area Sanitary Pipeline segments were partially removed within the 124-N-2 excavation area during the remediation effort and were addressed with the 124-N-2 waste site verification sampling.

Approximately 1,185 BCM (1,550 BCY) of additional material was removed from the 124-N-2 excavation. All excavated materials and pipelines were removed for direct disposal at the ERDF.

Code: 124-N-3	Classification: Accepted
Names: 124-N-3; 124-N-3 Septic Tank; 1607-N3; 100-N Sanitary Sewer System No. 3	Reclassification: Interim Closed Out (7/18/2013)
Type: Septic Tank	Start Date: 1/1/1982
Status: Inactive	End Date:

Description: The waste site has been remediated and Interim Closed Out. It was an underground 1900 liter (500 gallon) precast concrete perforated pipe.

Location: The unit was located adjacent to the north side of the 107-N Building at coordinates N149584.6 E571121.2.

Process Description: The unit is a cesspool consisting of a 1,900-liter (500-gallon) precast concrete perforated pipe with a solid cover, resting on a 0.61-meter (2-foot) thick pad of crushed stone. There are no surface indications of the cesspool's location since there is no above-ground access port to the pit.

Waste Type: Sanitary Sewage

Waste Description: When operational, this unit received approximately 170 liters/day (45 gallons/day) of sanitary sewage.

Closure Info: Interim (7/18/2013): Remedial action at the 124-N-3 waste site was performed in August 2012 by the Deactivation, Decontamination, Decommissioning, and Demolition (D4) Project during the demolition and removal of the adjacent 107-N Basin Recirculation Facility. The cesspool structure was completely removed during remediation of the 124-N-3 waste site and the adjoining 107-N Basin Recirculation Facility. A Global Positioning Environmental Radiological Surveyor (GPERS) survey was conducted on December 14, 2012, within the 107-N Building footprint and the 124-N-3 excavation footprint. Radiological contamination remained within the footprint. Therefore, the area was deferred to the Field Remediation project for final cleanup.

The 124-N-3 waste site underwent additional remediation to remove contaminated soil and debris in January 2013. An additional 14 bank cubic meters (18 bank cubic yards) of soil was removed at the 124-N-3 waste site by the Field Remediation Project. The original grade at the 124-N-3 waste site prior to remediation activities was 140 meters (459 ft) above mean sea level. The final grade at the completion of remedial action activities is 135 meters (443 ft) above mean sea level resulting in a 5 meter (16 ft) deep excavation. The assumed maximum depth of the cesspool structure was 4.3 meter (14 ft), based on the available records and typical design.

Code: 124-N-4	Classification: Accepted
Names: 124-N-4; 124-N-4 Septic Tank; 1607-N4; 100-N Sanitary Sewer System No. 4	Reclassification: Interim Closed Out (7/9/2012)
Type: Septic Tank	Start Date: 1/1/1963
Status: Inactive	End Date: 1/1/1987

Description: The 124-N waste site has been remediated and Interim Closed Out. It consisted of two septic tanks and an associated tile field, which served as the primary septic system for the majority of the 100-N Area buildings. Multiple 8-inch diameter cast iron sewer lines connected the two septic tanks to the tile field. They are segments of 100-N-84:5 miscellaneous piping.

Location: The unit was located in the northeast corner of 100-N Area, outside the fence, directly south of 1301-N Crib (116-N-1) and east of 1310-N. Part of the 1310-N shield berm was immediately west of the 124-N-4 waste site and borders the septic tank excavation. The site was located inside a posted Contamination Area/Radiation Area.

Related Sites/Structures: The sanitary sewer lines associated with the 124-N-4 septic system are segments of 100-N-84:5 miscellaneous piping.

Process Description: The unit included a large drain field and two septic tanks, each having a capacity of 63,644 liters (14,000 gallons). The total infiltration surface area of the drain field was 826.8 square

meters (8,900 square feet). The 124-N-4 waste site operated from 1963 to 1987, at which point the 105-N Reactor was put on standby before being permanently shut down in 1991.

Waste Type: Sanitary Sewage

Waste Description: The unit received approximately 136,400 liters/day (30,000 gallons/day) of sanitary sewage.

Closure Info: Interim (7/9/2012): Remedial action at the 124-N-4 waste site was performed between October 28, 2010, and February 16, 2011. Approximately 8,713 bank cubic meters (BCM) (11,396 bank cubic yards [BCY]) of contaminated soil and debris were removed from the 124-N-4 excavation and direct loaded or staged in staging piles prior to being disposed at the Environmental Restoration Disposal Facility (ERDF). Excavation continued until all debris and contamination associated with the waste site had been removed. No radiologically contaminated material was discovered during remediation activities.

The two 124-N-4 septic tanks were sampled on October 13, 2010, to estimate the amount of lime and Water Works absorbent needed to treat and solidify the tank contents prior to remediation. Remedial actions at the 124-N-4 waste site started on October 28, 2010. The tanks were treated and solidified on November 8 and 9, 2010. Once the contents were solidified, the septic tanks were rubblized in place and loaded out for disposal at the Environmental Restoration Disposal Facility (ERDF). Loadout of the 124-N-4 excavation was completed on February 16, 2011.

The 124-N-4 excavation reached a maximum depth of 8 meters (26 ft) below the surrounding ground surface. The septic tank excavations extended approximately 4 meters (13 ft) below the original surface, and the tile field was excavated to approximately 3 meters (10 ft) below the original tile field surface. The remedial action included removal of the four diversion boxes, the 100-N-84:5 pipelines that connected the septic tank to the diversion boxes, and those pipelines from the septic tanks up to the manhole located by the southernmost septic tank. Active power lines extended above the tile field's eastern side between two power poles located near the northeast and southeast corners of the waste site boundary. Due to a need to stabilize the power poles, an estimated 9-meters (30-ft) area surrounding the poles was left in place at the edge of the excavation.

Code: 124-N-9	Classification: Accepted
Names: 124-N-9; 124-N-9 Septic Tank; 1607-N9; 100-N Sanitary Sewer System No. 9	Reclassification: Interim Closed Out (8/5/2013)
Type: Septic Tank	Start Date: 1/1/1985
Status: Inactive	End Date:
Description:	The septic system has been remediated and Interim Closed Out. It consisted of two septic tanks and one drainfield that received sanitary waste from the 1120N building. They were located inside an area that was delineated by light posts and chain.
Location:	The unit was located approximately 46 meters (150 feet) northeast of the 1120-N Building.
Process Description:	The site consisted of 2 septic tanks and a drain field. Each tank has a volume of 11,360 liters (3,000 gallons), and the drain field has an infiltration surface area of 325 square meters (3,500 square feet). The 1120-N Building housed training facilities and offices and also served as a warehouse. For a brief period of time a radiological counting facility was housed in the building. Storage in the warehouse section included janitorial supplies, pest control supplies, sign shop supplies, and radioactive sources. The radioactive sources were calibration standards used to calibrate the equipment used in the radiological counting facility. Floor drains in the

1120-N facility emptied into a 10 cm (4 in.) polyvinyl chloride (PVC) sewer that bypassed the septic tanks and emptied directly to the drain field. Effluent from the restroom drained into a 10 cm (4 in.) PVC sewer that drained into the septic tanks before being discharged to the drain field.

Waste Type: Sanitary Sewage

Waste Description: This unit receives approximately 8,300 liters/day (2,200 gallons/day) of sanitary sewage.

Closure Info: Interim (8/5/2013): Remedial action at the 124-N-9 waste site was performed between August 15 and August 23, 2012. Approximately 975 bank cubic meters (BCM) (1,275 bank cubic yards [BCY]) of soil, rock, concrete, and piping were removed and disposed at the Environmental Restoration Disposal Facility (ERDF). The removed sections of piping between the septic tanks and the drain field are part of the 100-N-84:5 and the 100-N-84:6 waste sites. The excavation was performed to approximately 0.3 meters (1 ft) below the structure of the septic tanks and drain field and is a maximum of approximately 2.8 meters (9.2 ft) deep in the area of the septic tanks and a minimum of 1 meter (3.3 ft) deep in the area of the drain field.

Code: 124-N-10

Classification: Accepted

Names: 124-N-10; 124-N-10 Sanitary Sewer System; 1607-N10; 1904-N 100-N Central Sewer System No. 10; 1904-NA Sanitary Lift Station No.1; Project H-677; 100-N Sewage Lagoon

Reclassification: Interim Closed Out (1/15/2014)

Type: Sewage Lagoon

Start Date: 2/1/1987

Status: Inactive

End Date:

Description: The 124-N-10 site has been remediated and Interim Closed Out. It encompassed the footprints of the 1904-N lagoons and the 1904-NA lift stations. 124-N-10 consisted of a three pond sewage lagoon facility (1904-N), a sewer trunk pipeline and other pipelines, two lift stations (1904-NA), new manholes and associated sewer system instrumentation. The sewer system was deactivated. Demolition began in December 2012 and continued through April 2013. It serviced a minimum of 27 buildings.

Location: The site was located 1 mile northwest of the intersection of N Avenue and Route 4 North cutoff. The sanitary sewer system was parallel with and north of the railroad tracks that intersect N Avenue.

Process Description: This system processed domestic human sewage. Three sewer ponds (or lagoons), identified in the drawings, included a lined aeration pond, a lined stabilization pond, and an unlined infiltration pond, had a total combined length of 822.75 ft by 220 ft wide. The system was designed for a maximum of 2,500 employees and a maximum design flow of 789,000 L (50,000 gal) per day. It began operation in February 1987.

Waste Type: Sanitary Sewage

Waste Description: The maximum design flow for this septic system is 50,000 gallons per day. It is designed for a maximum of 2,500 employees. The site has received domestic wastewater sewage from the 100-N Area and domestic sewage pumped from septic tanks throughout the Hanford Site. Incidental solids (rags, scum, and other debris) are removed from the system and disposed of as solid waste at an approved disposal site. The discharge from the infiltration pond percolates down to the groundwater.

Closure Info: Interim (1/15/2014): Demolition of the 1904-N and 1904-NA facilities was performed from December 2012 through April 2013 by the Deactivation, Decontamination, Decommissioning,

and Demolition (D4) project. The depth of the excavation ranged from approximately 1 meter (3 ft) to 3 meters (9.8 ft) below ground surface. Approximately 18,000 bank cubic meters (23,500 bank cubic yards) of soil and debris was disposed at the Environmental Restoration Disposal Facility (ERDF). All physical components of the 1904-N and the 1904-NA facilities have been removed. Waste characterization samples and in-process soil samples were collected prior to and during the removal of the facilities and the underlying soil. Hexavalent chromium was detected in an in-process soil sample above a remedial action goal (RAG). Therefore, additional soil was removed from the soil sample location.

Following D4 activities, the Field Remediation (FR) project collected in-process soil samples to determine if additional soil remediation was necessary from the 124-N-10 waste site prior to initiating verification sampling activities. The sample results indicated that the waste removal conducted by D4 was sufficient. Therefore, no additional material was removed by the FR project. No anomalies or stained soil were encountered during demolition and removal of the facilities and underlying soil. All material removed from the waste site was direct loaded for disposal at the ERDF. No staging pile areas were associated with the 124-N-10 waste site remediation.

Code:	128-N-1	Classification:	Accepted
Names:	128-N-1; 128-N-1 Burning Pit; 100-N Burning Pit	Reclassification	Interim Closed Out (4/10/2013)
Type:	Burn Pit	Start Date:	1/1/1963
Status:	Inactive	End Date:	1/1/1989
Description:	The waste site has been remediated and Interim Closed Out. The site was an area with evidence of burning, in the form of burnt trash and cans. Most of the site had been backfilled.		
Location:	The site was located approximately 460 meters (1,500 feet) northeast of the 1120-N Building, and was southeast of 116-N-3.		
Related Sites/Structures:	128-N-1 is associated with 100-N-6 and 100-N-16.		
Process Description:	Combustible materials, such as nuisance vegetation and combustible wastes (office waste, tools and hardware, and potentially paints and solvents), have been burned at this site. After the establishment of the Hanford Central Landfill in the early 1973, the pit was used only for burning nuisance vegetation.		
Waste Type:	Misc. Trash and Debris		
Waste Description:	Combustible materials, such as nuisance vegetation and combustible wastes (office waste, tools and hardware, and potentially paints and solvents), have been burned at this site. The quantity of material burned at the site is unknown. Since the establishment of the Hanford Central Landfill (in the early 1970's), this unit has been used for burning nuisance vegetation only.		
Closure Info:	Interim (4/10/2013): Remediation of 100-N-6, 100-N-16, 100-N-98 area 1, and 128-N-1 waste sites began on August 2, 2010, and was completed on November 28, 2011. A total of approximately 20,334 bank cubic meters (BCM) (26,596 bank cubic yards [BCY]) were excavated and staged for removal to the Environmental Restoration Disposal Facility (ERDF). Between April 16 and 19, 2012, the excavation was expanded to the west to include stained soil Area 2 of the 100-N-98 waste site. Approximately 476 BCM (623 BCY) of soil was removed from 100-N-98 Area 2 and direct loaded for disposal at ERDF. The additional remediation of the spoil pile area (SPA) and the 100-N-6, 100-N-16, 100-N-98, and 128-N-1 waste site excavation generated an additional volume of 5,446 BCM (7,123 BCY) of material for direct load out to ERDF. A total volume of 26,256 BCM (34,342 BCY) was disposed at ERDF, to complete the 100-N-6, 100-N-16, 100-N-98, and 128-N-1 waste site remediation.		

The materials removed from the 100-N-6, 100-N-16, 100-N-98, and 128-N-1 waste sites consisted of abandoned wiring, transite pipe, metallic and wood debris, burnt wood, ash, tar, roofing felt, stained soil, a bucket of grout, an open glass bottle, green fibrous material, purple sandy material, a paint ball, drums containing bunker and amber oil, and miscellaneous demolition debris. Anomalous material discovered during remediation included six 208-L (55-gal) drums, small white ceramic balls used as filtering media, and soil with a strong solvent odor.

Code: 130-N-1	Classification: Accepted
Names: 130-N-1; 183-N Backwash Discharge Pond; 183-N Filter Backwash Pond; 126-N-1	Reclassification: Interim Closed Out (9/12/2013)
Type: Pond	Start Date: 1/1/1983
Status: Inactive	End Date: 6/27/2000

Description: 130-N-1 was divided into two subsites: 130-N-1:1, 183-N Northeastern Backwash Discharge Pond and 130-N-1:2, 183-N Southwestern Backwash Discharge Pond. Both subsites have been evaluated. Subsite 1 was remediated and Interim Closed Out. Subsite 2 was evaluated and determined to require No Action. Since both subsites have been reclassified, the parent site is also considered Interim Closed Out.

The site consisted of an irregularly shaped natural marsh-like pond that received filter backwash water from the 183-N Filtration Plant. The pond was originally constructed in 1982, utilizing a natural depression and was known as the Backwash Lake. The construction activities included building a dike to protect a railroad spur that ran along the southern end of the depression and excavating channels to facilitate drainage. The Backwash Lake was put into operation in 1983. It was later referred to as the 183-N Backwash Discharge Pond. The effluent discharge pipe was capped on June 27, 2000.

Location: The site is located approximately 0.4 kilometers (0.25 miles) southeast of the 1324-N Facility.

Related Sites/Structures: 130-N-1 received waste via the 100-N-58 pipeline.

Process Description: The 183-N Water Treatment Plant was constructed in 1963 to support operations of the 100-N Reactor. The water filtration plant provided treated water for cooling purposes, water for auxiliary support systems, and potable water for administrative buildings and offices. The filter backwash was originally discharged to the River via the 1908-N Outfall until September 2, 1977 when it was diverted to the 163/183N facility discharge pond area (100-N-58, 120-N-1 and 120-N-2). The settling ponds were small unlined basins which were used mainly to settle out solids from the filter backwash. By late 1981 it was apparent that annual dredging of the settling ponds was not sufficient to prevent flooding. 130-N-1 was constructed in 1982 to receive the filter backwash waste stream to reduce the particulate loading on the settling ponds. It began receiving effluent in 1983.

When the pond was active, the State Waste Discharge permit application, (1994), identified four wastewater streams that were routed to the 183-N Backwash Discharge Pond (DOE/RL-94-23).

1 - The Coagulator Drains Wastewater stream, derived from the annual draining and washing of the coagulator basins.

2 - The Filter Backwash Wastewater stream, consisting of backwash from the multimedia gravity filters.

3 - The Non-Contact Cooling Water stream, from an air compressor in the 184-N Building and a fire pump in the 182-N Building.

4 - The Stormwater from the 163-N Demineralizer Sump stream, from the 163-N Trench Sump and the 108-N Neutralizing Sump.

The 183-N Backwash Discharge Pond was became inactive after the 183-N Potable Water Plant was shutdown. The effluent discharge pipe was capped on June 27, 2000.

Waste Type: Water

Waste Description: The unit receives filter backwash containing polyacrylamide and aluminum sulfate.

This Site has the Following SubSites:

Code: 130-N-1:1

Names: 130-N-1:1; 183-N Northeastern Backwash Discharge Pond

Code: 130-N-1:2

Names: 130-N-1:2; 183-N Southwestern Backwash Discharge Pond

Code: 130-N-1:1

Classification: Accepted

Names: 130-N-1:1; 183-N Northeastern Backwash Discharge Pond

Reclassification: Interim Closed Out (9/12/2013)

Type: Pond

Start Date:

Status: Inactive

End Date: 6/27/2000

Description: 130-N-1 Subsite 1 has been remediated and Interim Closed Out. It was the northeastern half of the 183-N Backwash Discharge Pond. The northeastern half was described in the original discharge permit application as having three adjoining portions; a rectangular portion, a neck, and a dry pond. The effluent discharge pipe was capped on June 27, 2000.

Location: The site is located approximately 0.4 kilometers (0.25 miles) southeast of the 1324-N Facility.

Related Sites/ Structures: 130-N-1 received waste via the 100-N-58 pipeline.

Process Description: The 183-N Water Treatment Plant was constructed in 1963 to support operations of the 100-N Reactor. The water filtration plant provided treated water for cooling purposes, water for auxiliary support systems, and potable water for administrative buildings and offices. The filter backwash was originally discharged to the River via the 1908-N Outfall until September 2, 1977 when it was diverted to the 163/183N facility discharge pond area (100-N-58, 120-N-1 and 120-N-2). The settling ponds were small unlined basins which were used mainly to settle out solids from the filter backwash. By late 1981 it was apparent that annual dredging of the settling ponds was not sufficient to prevent flooding. 130-N-1 was constructed in 1982 to receive the filter backwash waste stream to reduce the particulate loading on the settling ponds. It began receiving effluent in 1983. When the pond was active, the State Waste Discharge permit application, (1994), identified four wastewater streams that were routed to the 183-N Backwash Discharge Pond (DOE/RL-94-23).

Closure Info: Interim (9/12/2013): Excavation of the soils associated with the entire 130-N-1:1 subsite was performed by the Field Remediation Project beginning on January 15, 2013, and finishing on April 8, 2013. Approximately 1.7 meters (5 ft) of soil was removed from the excavation and disposed at the Environmental Restoration Disposal Facility (ERDF). Approximately 12,217

bank cubic meters was direct loaded to ERDF. No anomalies were encountered during the excavation and the effluent discharge pipe was cut below grade and buried during this time. Any remaining effluent discharge pipe below grade is related to the 100-N-58 waste site. According to the closure document for the 100-N-58 waste site (CVP-2001-00021), all remaining pipelines were closed out and left in place.

The SubSite is Part Of:

Code: 130-N-1

Names: 130-N-1; 183-N Backwash Discharge Pond; 183-N Filter Backwash Pond; 126-N-1

Code: 130-N-1:2

Classification: Accepted

Names: 130-N-1:2; 183-N Southwestern Backwash Discharge Pond

Reclassification: Interim No Action (5/17/2013)

Type: Pond

Start Date:

Status: Inactive

End Date:

Description: 130-N-1 Subsite 2 has been evaluated and determined to require No Action. It was a natural depression in the southwestern portion of the 130-N-1 discharge pond with little vegetation. There is no evidence that this lobe of the pond ever received a significant amount of waste water.

Location: Subsite 2 is the southern half of the 183-N Backwash Discharge Pond. It is located approximately 0.4 kilometers (0.25 miles) southeast of the 1324-N Facility.

Related Sites/ Structures: 130-N-1 received waste via the 100-N-58 pipeline.

Process Description: The pond was originally constructed in 1982 by utilizing a natural depression and was known as the Backwash Lake. The construction activities included building a dike to protect a railroad spur that ran along the southern end of the depression and excavating channels to facilitate drainage. The Backwash Lake was put into operation in 1983. It was later referred to as the 183-N Backwash Discharge Pond, presumably because the area that received water was significantly smaller than originally designed.

The southwestern half of the 183-N Backwash Discharge Pond received little (if any) effluent. The 130-N-1 pond began receiving effluent in 1983 via the 100-N-58 pipeline, which discharged to the northern end of the pond area.

The State Waste Discharge permit application, submitted in June 1994, identified four wastewater streams routed to the 183-N Backwash Discharge Pond (DOE/RL-94-23).

1 - Coagulator Drains Wastewater, derived from the annual draining and washing of the coagulator basins.

2 - Filter Backwash Wastewater, consisting of backwash from the multimedia gravity filters.

3 - Non-Contact Cooling Water, from an air compressor in the 184-N Building and a fire pump in the 182-N Building.

4 - Collection of Stormwater from the 163-N Demineralizer Sump, 163-N Trench Sump, and 108-N Neutralizing Sump.

Closure Info: Interim (5/17/2013): Three in-process samples were collected in the 130-N-1:2 southwestern pond on October 22, 2012. The samples were collected in the lowest elevation (140 meters

[459.3 ft] above sea level), near the effluent entry point of the subsite 2 area, where contamination was most likely to occur. The sample results indicated that no excavation was required.

The SubSite is Part Of:

Code: 130-N-1

Names: 130-N-1; 183-N Backwash Discharge Pond; 183-N Filter Backwash Pond; 126-N-1

Code: 1908-N

Classification: Accepted

Names: 1908-N; 1908-N Outfall

Reclassification: Interim Closed Out (9/6/2012)

Type: Outfall

Start Date: 1/1/1963

Status: Inactive

End Date:

Description: The waste site structure has been demolished and Interim Closed Out. It consisted of an open-topped, compartmentalized, reinforced concrete outfall structure. A 260 centimeter (102 inch) line discharged into the southeast face of the structure. A 260 centimeter (102 inch) pipeline exited the northwest side of the structure and discharged to the Columbia River. The 1908-N above and below grade structure was removed except for a section of the north wall, that was encased in the concrete monolith.

Location: The 1908-N Sealwell (Outfall) was located west of the 109-N Building, west of the 1300-N Emergency Dump Basin and south of the 1301-N Emergency Dump Tank on a steep bank which leads to the river.

Related Sites/Structures: The outfall structure is associated with 100-N-77 (a 259-centimeter (102-inch) River Effluent pipeline), 100-N-79 (an emergency outfall flume) and the 1300-N Emergency Dump Basin 76-centimeter (30 inch) overflow line.

Process Description: The site was an outfall structure (seal well) that was used as a sump for several discharge lines and to drop the liquid discharge level for overflow to the river. The outfall also discharged to a flume which was used as an alternative to the river pipelines. An unknown level of radioactive contamination exists within the structure because the discharge lines were associated with the reactor secondary steam system.

The outfall received more than 2 million cubic meters per day of single pass raw river water from the Circulating Raw Water (CRW) System, and discharged it to the river. The CRW supplied once-through untreated river water to 16 dump condensers and 7 surface condensers.

Waste Type: Construction Debris

Waste Description: The 1908-N Sealwell received raw river water used to cool the secondary cooling water for the N Reactor. An unknown level of radioactive contamination exists within the structure because the discharge lines were associated with the reactor's secondary steam system. Therefore, while no specific COPCs have been identified, the outfall structure has potential radioactive contamination.

Closure Info: Interim (9/6/2012): Radiological scoping surveys were performed on the 1908-N facility prior to and during demolition. These surveys did not identify contamination. A certified asbestos inspection was conducted on June 19, 2006. No samples were taken, but a visual inspection of 1908-N was conducted and no Potential ACM was visible during the inspection. There were no samples taken of the 1908-N for waste characterization/designation purposes. Two samples were taken of the lean concrete monolith to identify whether or not the monolith could be left in place.

Demolition of the 1908-N Outfall was performed March 2012 through June 2012. The entire

above and below grade structure was removed, including the concrete floor, with the exception of a below-grade portion of the north wall that was encased within a lean concrete monolith. The concrete monolith remaining after demolition of the structure was sampled on April 26, 1012, to support a decision for leaving this concrete monolith in place. An evaluation of the results of this sampling indicated that residual contaminant concentrations in the concrete do not preclude any future uses (as bounded by the rural-residential scenario) and allow for unrestricted use of the site. The results also demonstrate that residual contaminant concentrations in the concrete are protective of groundwater and the Columbia River. The Sampling Determination Form included with the Facility Status Change Form documents that there is no indication that any portion of the 1908-N facility or the underlying soil was ever contaminated and that analytical results for the sample collected from the concrete monolith is sufficient to support closeout of this waste site. The removal action was performed in accordance with the Removal Action Work Plan (RAWP) for 100-N Area Ancillary Facilities (DOE-RL-2002-70, Rev. 3) and included removal and disposal of demolition debris at the ERDF.

Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Code:	1908-NE	Classification:	Accepted
Names:	1908-NE; 1908-NE Building; HGP Outfall; HGP SWMU #7	Reclassification	Interim Closed Out (11/5/2012)
Type:	Outfall	Start Date:	1/1/1966
Status:	Inactive	End Date:	1/1/1988
Description:	<p>The site has been Interim Closed Out. The unit consisted of a an open-topped, compartmentalized, reinforced concrete outfall structure. It received effluent from the 100-N-1 settling Pond (SWMU #6) and discharged to the river via an effluent pipeline (see 100-N-80).</p> <p>Although 1908-NE was Reclassified to Interim Closed Out in 2004, the structure still remained and required Institutional Controls to monitor the structure. Demolition of the structure in 2012 eliminated the requirement for the monitoring Institutional Control.</p>		
Location:	<p>The unit was located in the 100-N Area, approximately 61 meters (200 feet) downstream from the 181-NE River Pumphouse Building on the Columbia River at river mile 379.6.</p>		
Related Sites/ Structures:	<p>The site was associated with the 100-N-1 Settling Basin, and the 100-N-80 River Effluent Pipeline.</p>		
Process Description:	<p>The outfall received single pass raw river water which had passed through the Hanford Generating Plant (HGP) condensers, as well as waste water from the 100-N-1 Settling Basin.</p>		
Waste Type:	<p>Construction Debris</p>		
Waste Description:	<p>The unit was designed to provide controlled waste water releases from the Hanford Generating Plant (HGP) facility. The unit was permitted under the National Pollutant Discharge Elimination System (NPDES). Releases to the outfall included coolant water, any releases from the HGP building sump prior to the late 1960s, and discharges from the HGP Settling Pond. The contaminants of potential concern include strontium-90, cobalt-60, cesium-137, arsenic, barium, cadmium, chromium, lead, selenium, silver, mercury, and PCBs.</p>		
Closure Info:	<p>Interim (6/15/2004): The 100-N Reactor provided fuel rods to the plutonium production process at Hanford, but also operated two 430 megawatt turbine generators for the generation of electricity. The Washington Public Supply System, later named Energy Northwest, was responsible for the Hanford Generating Plant located at 100-N Reactor. The Cleanup</p>		

Verification Package (HGP-CVP-SWMUs 5, 6, 7, 8, 9, & 10) for the Hanford Generating Plant Solid Waste Management units was prepared by Energy Northwest in 2004. Some remedial actions at HGP began in 1992. Other characterization and remediation was completed in 2004. Remedial action activity descriptions include:

100-N-1 Settling Pond (SWMU#6) - Remediation activities conducted in 2001 removed approximately 0.9 meters (3 ft) of soil and settled solids material from the 100-N-1 Settling Pond (SWMU #6). The excavated material was disposed of at the Environmental Restoration Disposal Facility (ERDF).

100-N-3 Maintenance Garage French Drain, 100-N-41 Gate House Septic Tank and 100-N-45 Office Building Septic Tank make up SWMU #9. Remediation was determined not to be necessary for the 100-N-3 site and the 100-N-41 and 100-N-45 septic sites. The below grade structures of the drain and septic sites were demolished in place and backfilled with soil in 2004.

100-N-4 Tile Field (SWMU#5) - Confirmatory sampling activities and data evaluation determined that remediation was not necessary for the 100-N-4 Tile Field.

100-N-5 Bone Yard (SWMU #10) - Remediation and removal activities for the 100-N-5 Bone Yard (SWMU #10) were primarily conducted in 2001 with the removal of the miscellaneous equipment, metal scrap, and general debris. The limited number of areas with sand blast media, ion exchange resin-like media and areas with soil staining and/or distressed vegetation were remediated in 2003 and 2004. The sand blast, ion exchange resin, and contaminated soil wastes were disposed of at the RABANCO landfill facility in Roosevelt, Washington.

The 100-N-46 Diesel under ground storage tank (UST) was excavated and removed in 2001. Soil contaminated with diesel was also excavated from the UST excavation. Contaminated soil was spread over the demolished 1703-N Office Building concrete slab foundation for attenuation. Upon completion of the remedial excavation, the bottom of the excavation was approximately 6.7 meters (22 ft) below the ground surface at the deepest location (southwest corner of excavation).

100-N-52 Gasoline underground storage tank (UST) was excavated and removed in 1992.

1908-NE Outfall (SWMU#7) - The original preferred remedy for the 1908-NE Outfall was Institutional Controls (continued monitoring). A radiological survey of the Outfall seal well and samples of water and sediment were collected from the Outfall seal well in 2001 to assess potential contamination associated with the Outfall. The outfall structure was demolished by the Washington Closure Hanford D&D organization in 2012, eliminating the Institutional Control requirement.

The 1716-NE Maintenance Garage building (SWMU #8), including the building slab and associated floor drain pipelines, were removed in their entirety during the 2003 and 2004 removal action activities. Prior to the removal action all chemical products were removed from the building and either properly disposed of or transferred to another facility for use. The building debris was used as fill for the 185-N Building basement.

Interim (11/5/2012): An additional Waste Site Reclassification Form (#2012-088) was approved in November 2012.

The outfall was interim closed in 2004; however, no remedial or demolition activities were performed at the outfall and an institutional control to preclude unauthorized human entry into the structure was applied. Subsequently, decontamination, demolition, and disposal was performed in 2011 through 2012 that included removal of contaminated sediment and demolition and removal of the upper portion of the outfall structure to a depth of 0.9 m (3 ft)

below grade. The remaining structure was then backfilled to grade with clean fill material. Sediment and concrete removed from the structure was disposed at the Environmental Restoration and Disposal Facility (ERDF).

The concrete sample results supported a decision to demolish and remove the outfall to a depth of 0.9 meters (3 ft) below grade, with subsequent backfill of the structure with clean fill material. The removal action also allows for removal of the Institutional Control requirement, since unauthorized human entry into the structure is no longer possible due to backfill of the remaining below-grade structure with clean fill material.

Code:	2607-FSM	Classification:	Accepted
Names:	2607-FSM; 609 Building Septic Tank 2607-FSM; 6607-FSM; 100 Area Fire Station Septic Tank; 1607-FSM	Reclassification	None
Type:	Septic Tank	Start Date:	1/1/1960
Status:	Active	End Date:	
Description:	The 6607-FSM Septic Tank is a single-chamber, reinforced concrete tank. This unit includes a drainfield.		
Location:	The septic system lies at the southwest corner of the 609 Building (100N Fire Station) and northwest of the intersection of Route 1 and Route 4 North in the 600 Area.		
Related Sites/ Structures:	The 6607-FSM septic system is associated with the 609 Building (100N Fire Station).		
Process Description:	The 6607-FSM septic tank receives sanitary effluent from the 609 Building and disposes of it through a sub-surface soil absorption system.		
Waste Type:	Sanitary Sewage		
Waste Description:	The 2607-FSM septic system receives sanitary wastewater at a rate of approximately 550 gallons (2,082 liters) per week.		

Code:	600-35	Classification:	Accepted
Names:	600-35; Debris Area Between 100-N and 100-D Areas	Reclassification	Interim Closed Out (2/1/2012)
Type:	Dumping Area	Start Date:	
Status:	Inactive	End Date:	
Description:	This waste site has been remediated. It consisted of relatively flat ground covered with fine gravel chips with little or no vegetation. The 600-35 waste site was a non-radiologically contaminated waste site that consisted of a 15-meter (50-ft)-diameter area of wood and metal debris, including a partially crushed topless drum laying on its side and a discarded 12 volt lead-acid battery. A well-head (number 87-55) and the 100-N export water line were noted on the southern edge and along the east-west line of the site, respectively. On May 8, 2008, a field evaluation of the site was made by the Orphan Sites Evaluation team. The team described the site as a 15 meter (50 ft) diameter area of wood and metal debris, including a T-handled valve and vent pipe.		
Location:	The 600-35 waste site is located outside the 100-N industrial area in a depression just west of Route 4 N between the 100-N and 100-D Areas. The center of the 600-35 waste site is at		

Washington State Plane coordinates N149940, E572956. The unit is located in a depression just west of Route 4 N between 100-N and 100-D, about 610 meters (2,000 feet) south of junction of the Route 2 N and Route 4 N.

Process Description: This site appears to be a former rock crushing/screening operation area and borrow pit (on the northern edge) with evidence of some dumping.

Waste Type: Misc. Trash and Debris

Waste Description: Miscellaneous surface debris was the only waste identified at this site. This debris includes a ladder, an 20-centimeter (8-inch) diameter steel pipe, metal scrap wire rope, miscellaneous wood debris, pieces of aluminum, and a container lid (no markings). A deteriorated 12 volt lead-acid battery of the type used in heavy equipment. A 208-liter (55-gallon) drum (no marking) was observed approximately 76 meters (250 feet) west of the site.

Closure Info: Interim (2/1/2012): Remedial action at the 600-35 waste site was performed between August 2 and 29, 2010. The debris removed from the 600-35 waste site consisted of miscellaneous metal and wood debris. Excavation continued until all debris and contamination associated with the waste site had been removed. Excavated material was stockpiled and transported to ERDF in December 2010. A 12-volt lead-acid battery and a crushed drum, previously identified, were not found during remediation. It is assumed the battery and drum were removed after the orphan sites evaluation in May 2008. No indications of previous spills or releases were detected during remediation at the 600-35 waste site. Six in-process soil samples were collected at various locations from the excavator bucket, for waste designation purposes, as soil was being removed.

Code: 600-339

Classification: Accepted

Names: 600-339; 100 Area Fire Station Dry Well

Reclassification: None

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: This site consists of a 1.83 meter (six foot) diameter dry well and associated inlet piping, which was part of the original 1960 construction, located west of the 609 Building. The dry well is located 0.61 meters (2 ft) below grade. It is constructed of concrete blocks laid on their sides with 1.3 cm (0.5 in) minimum openings between joints. The open bottom contains a 0.3 meters (1 ft) coarse gravel fill. The opening at the top is secured by a cast iron manhole cover. The 10 cm (4 in) inlet pipe enters the dry well 3 meters (10 ft) above its bottom elevation. The dry well is believed to still be in use, but has been paved over with an asphalt parking lot.

Location: The underground drywell (site is covered with asphalt parking lot) is approximately 6 meters (19.7 ft) west of the center of the 609 Building's west wall at approximately E572202.54 N145349.19.

Process Description: The dry well was designed to collect rain water draining from the roof, as well as floor drain waste from the entire building. All liquid wastes originating from the routine use and maintenance of the fire station vehicles were flushed to this dry well.

Code: 600-340

Classification: Accepted

Names: 600-340; 100 area Fire Station Soil Stained Areas

Reclassification: Interim Closed Out (6/18/2014)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The waste site was remediated and Interim Closed Out. It consisted of two locations, one with discolored top soil and the other with a white granular stain surface area.

Location: The two areas were located at coordinates E572161.02 N145395.78 and E572213.75 N145447.13, approximately 16 meters (52.5 ft) northwest of the 100 Area Fire Station.

Closure Info: Interim (6/18/2014): Ground penetrating radar and electromagnetic induction data were collected over the two stained locations. The entire area surveyed contained scattered surface and near surface debris. Confirmatory sampling was performed at the 600-340 waste site on January 19, 2011.

The staining and debris was observed and excavated well beyond the Waste Information Data System (WIDS) and Stewardship Information System mapped waste site boundaries. The excavation was extended to the southeast to encompass additional burned material and stained soil observed during site remediation. The remediation continued until all visible burned debris and stained soil was removed.

The 600-340 waste site was remediated between June 19 and September 10, 2013, based on the results of confirmatory sampling. The debris removed from the 600-340 waste site consisted of stained soil, broken glass, burned construction debris, asbestos-containing materials, wire, metal, and other debris. Approximately 1,472 bank cubic meters (BCM) (1,925 bank cubic yards [BCY]) of soil and debris were direct loaded for disposal at the Environmental Restoration Disposal Facility (ERDF). There is no staging pile area or overburden soil stockpile associated with the 600-340 waste site excavation. No anomalous material was encountered during excavation.

Code: 600-347

Classification: Accepted

Names: 600-347; 100 Area Fire Station Burn Pit

Reclassification: Interim No Action (11/21/2011)

Type: Burn Pit

Start Date:

Status: Inactive

End Date:

Description: The site consists of an engineered burn pit. The dimensions of the burn pit are 6 meters (20 ft) by 3 meters (10 ft) by 1 meter (0.9 ft) deep. The site was used to dispose various flammable liquids and petroleum products from approximately 1959 to 1984.

Location: The 600-347 waste site is located 47.6 meters (156 ft) northeast of the northeast corner of the 609 Building (100 Area Central Fire Station).

The burn pit is at coordinates E572244.99 N145399.31.

Closure Info: Interim (11/21/2011): Remedial action was determined to be unnecessary. The confirmatory sampling data, collected on January 9, 2011, has been used to document this waste site reclassification as a No Action site.

Code: 600-348

Classification: Accepted

Names: 600-348; 100 Area Fire Station Underground Storage Tanks

Reclassification: None

Type: Storage Tank

Start Date:

Status: Inactive

End Date:

Description: The site consists of two locations. The first site is the underlying soil from the original 1894 L

(500 gallon) fire station gasoline tank removed in late 1987. The second site is a 7571 L (2000 gallon) diesel fuel oil tank and underlying soil used to supply the 609 Building hot water boiler.

Location: E572205.40 N145329.93
E572208.86 N145356.60

Code: 628-2 **Classification:** Accepted
Names: 628-2; 100 Area Fire Station Burn Pit **Reclassification:** Interim Closed Out (4/2/2014)
Type: Burn Pit **Start Date:**
Status: Inactive **End Date:** 1/1/1985

Description: This site has been remediated and Interim Closed Out. It was an unmarked pit composed of sand and dirt with sparse vegetation showing signs of stress. The site had ash, debris, and soil discoloration.

Location: This site was located 130 meters (426.5 feet) north of the 100 Area Fire Station.

Process Description: The original information indicates that mainly motor oil and diesel fuel contaminated with water or deemed unusable was burned here. However, there is no supporting written documentation.

Waste Type: Chemicals

Waste Description: The waste site contains motor oil, diesel fuel, and toluene. Other chemicals were potentially burned at the site.

Closure Info: Interim (4/2/2014): A geophysical investigation was conducted on September 22, 2011. An area measuring 12 by 14 meters (39 by 46 ft) had a significant amount of concentrated debris.

The 628-2 waste site was remediated between June 24 and July 9, 2013. The debris removed from the 628-2 waste site consisted of broken glass, burned construction debris, asbestos-containing materials, wire, metal, and other debris. The estimated volume of excavated materials was approximately 709 bank cubic meters (927 bank cubic yards). Materials were temporarily staged within the 628-2 excavation, prior to removal to the Environmental Restoration Disposal Facility. There were no staging pile areas or overburden piles associated with the 628-2 waste site excavation. No anomalous material was encountered during excavation.

Code: UPR-100-N-1 **Classification:** Accepted
Names: UPR-100-N-1; 100-N 1304-N Dump Tank; Emergency Dump Tank Inlet Valve Box Leak; UN-100-N-1 **Reclassification:** Interim Closed Out (3/20/2013)
Type: Unplanned Release **Start Date:** 3/27/1974
Status: Inactive **End Date:** 3/27/1974

Description: The Unplanned Release has been remediated and Interim Closed Out. The site was an unplanned release covering an area of ground estimated at 20,000 square feet (1,858 square meters).

Location: The site extended from the 1304-N Emergency Dump Tank to the front of the 181-N River Water Pump House, approximately 45 meters (147 feet) from the Columbia River.

Release Description: On March 27, 1974 an estimated 113,550 liters (30,000 gallons) of radioactive water leaked onto the ground due to a line leak from the inlet valve box near the 1304-N Emergency Dump Tank. The water flowed down the bank from the Emergency Dump Tank, covered the roadway below the tank, and extended to the front of the 181-N Building. An estimated 139 square meters (1,500 square feet) was contaminated outside the 100-N area security fence. The security fence is considered the site boundary.

Related Sites/Structures: The site is associated with 1322-N Valve Pit, 105-N Lift Station, 1301-N Crib, a 91 centimeter (36 inch) underground pipeline, 1304-N Emergency Dump Tank, and a 76 centimeter (30 inch) underground pipeline.

Waste Type: Process Effluent

Waste Description: The leak consisted of filtered water in the estimated amount of 113,550 liters (30,000 gallons) containing 0.2 Curies of radioactive constituents.

Closure Info: Interim (2/20/2013): The above ground 1304 Emergency Dump Tank and associated piping were removed in 2004.

Remedial action at the 100-N-57, UPR-100-N-1, UPR-100-N-2, UPR-100-N-29, UPR-100-N-30, and UPR-100-N-32 waste sites was performed between February 21 and May 31, 2011. Excavation continued until all debris and contamination associated with the waste sites had been removed. Contaminated soil, concrete, pipeline segments and debris removed during excavation were staged within the South Staging Pile Area 1 (SSP Area 1) prior to shipment to the ERDF. Approximately 1,848 bank cubic meters (2,417 bank cubic yards) of contaminated soil and debris were removed from the site and disposed at the ERDF. No stained soil or anomalous material was found during the remediation activities.

The debris removed from the waste sites consisted of miscellaneous noncombustible debris and soil. Portions of the 100-N-63:2, 100-N-64, 100-N-84:2, 100-N-84:3, 100-N-84:4, and 100-N-84:5 pipelines waste sites were also removed during 100-N-57 group of waste sites remediation activities. The remaining portions of these pipeline waste sites will be remediated and separate closure documents prepared at a later date.

Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Code:	UPR-100-N-2	Classification:	Accepted
Names:	UPR-100-N-2; 100-N FLV-858 Valve Leak; UN-100-N-2	Reclassification	Interim Closed Out (3/20/2013)
Type:	Unplanned Release	Start Date:	2/19/1980
Status:	Inactive	End Date:	2/19/1980

Description: The Unplanned Release has been remediated and Interim Closed Out. The site was an area of ground covering estimated at 28 square meters (300 square feet).

Location: The release was located in the 100 N Area, on the northeast corner of Emergency Dump Basin (116-N-4), below grade.

Release Description: The release occurred on February 19, 1980, with an estimated 113,550 L (30,000 gal) of contaminated reactor effluent being leaked to a crack in a 2.5 cm (1 in.) relief drain line. The FLV858 valve leaked mildly contaminated reactor effluent from a point 3 meters (10 feet) below grade. The leak rate was estimated at 38 liters/minute (10 gallons/minute) and was determined to be due to corrosion of the valve. Estimated surface area affected is 28 square meters (300 square feet).

Related Sites/ Structures: The site is associated with the 105-N Building.

Waste Type: Process Effluent

Waste Description: The release consisted of primary coolant water containing less than 1 curie of beta/gamma.

Closure Info: Interim (2/20/2013): The above ground 1304 Emergency Dump Tank and associated piping were removed in 2004.

Remedial action at the 100-N-57, UPR-100-N-1, UPR-100-N-2, UPR-100-N-29, UPR-100-N-30, and UPR-100-N-32 waste sites was performed between February 21 and May 31, 2011. Excavation continued until all debris and contamination associated with the waste sites had been removed. Contaminated soil, concrete, pipeline segments and debris removed during excavation were staged within the South Staging Pile Area 1 (SSP Area 1) prior to shipment to the ERDF. Approximately 1,848 bank cubic meters (2,417 bank cubic yards) of contaminated soil and debris were removed from the site and disposed at the ERDF. No stained soil or anomalous material was found during the remediation activities.

The debris removed from the waste sites consisted of miscellaneous noncombustible debris and soil. Portions of the 100-N-63:2, 100-N-64, 100-N-84:2, 100-N-84:3, 100-N-84:4, and 100-N-84:5 pipelines waste sites were also removed during 100-N-57 group of waste sites remediation activities. The remaining portions of these pipeline waste sites will be remediated and separate closure documents prepared at a later date.

Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Code: UPR-100-N-3	Classification: Accepted
Names: UPR-100-N-3; Dummy Fuel Transfer Line; Spacer Disposal System Transport Line Leak; UN-100-N-3; UN-116-N-3	Reclassification: Interim Closed Out (9/6/2013)
Type: Unplanned Release	Start Date: 3/1/1978
Status: Inactive	End Date: 3/8/1978

Description: The release site has been remediated and Interim Closed Out. The 100-N-31 waste site was located on the west side of the 105-N/109-N Reactor Buildings and adjacent to the 100-N-32, 100-N-38, 100-N-61 :3, 100-N-64:3, 100-N-68, UPR-100-N-3, UPR-100-N-7, UPR-100-N-10, UPR-100-N-12, and UPR-100-N-39 waste sites. These waste sites are collectively referred to as the waste sites west of the 105-N/109-N Reactor. The remediation of these waste sites resulted in one large excavation with no demarcation of the individual sites, with the exception of the UPR-100-N-39 waste site. The eleven sites were Interim Closed out in a single document.

The release was first discovered as a 1.2 meter (4-foot) diameter and 0.8 meter (2.5 foot) deep sink hole within a radiation control zone, caused by a pipe leak.

Location: The release occurred in the 100-N Area near the north side of the 105-N Lift Station. It was about 4.7 meters (15.4 feet) northeast of the 1722-N Decontamination Hot Shop. This is same the location where the UPR-100-N-10 and UPR-100-N-12 releases occurred.

Release Description: A leak developed in the dummy fuel spacer transfer line, a 7.6-centimeter (3-inch) reinforced plastic pipe extending from the 100-N Fuel Storage Basin to the dummy disposal pit. The leak rate was estimated to be 74.6 liters (25 gallons) per minute. It was not known how long the leak

had been occurring. However, due to the size of the sink hole, it was judged to have occurred within the week prior to identification. The volume of water that leaked to the soil was estimated to be approximately 1,362,744 liters (350,000 gal).

Related Sites/ Structures: The site is associated with the 100-N Area Spacer Silos (118-N), the 105-N Fuel Storage Basin, 100-N-31 100-N-32, 100-N-38, 100-N-61 :3, 100-N-64:3, 100-N-68, UPR-100-N-3, UPR-100-N-7, UPR-100-N-10, UPR-100-N-12, and UPR-100-N-39.

Waste Type: Water

Waste Description: The release consisted of storage basin water with an estimated radionuclide release of 0.07 curies of cobalt-60, 0.8 curies of strontium-90, 0.25 curies of cesium-137, 0.14 curies of cerium/praseodymium-144, 0.0004 curies of plutonium-239, and 1.0 curies of tritium (assumed).

Closure Info: Interim (9/6/2013): Eleven waste sites located west of the 105-N/109-N Reactor Building were remediated as a group. The eleven waste sites included 100-N-31, 100-N-32, 100-N-38, 100-N-61:3, 100-N-64:3, 100-N-68, UPR-100-N-3, UPR-100-N-7, UPR-100-N-10, UPR-100-N-12, and UPR-100-N-39. This group of waste sites was referred to as the waste sites west of the 105-N/109-N Reactor. The footprints of the 1909-N Waste Disposal Valve Pit, the 107-N facility and the pipe trench between 105-N and 107-N were also located within the boundary of the group.

The eleven collocated waste sites located west of the 105-N/109-N Reactor Building were remediated, either partially or completely, by the Deactivation, Decontamination, Decommissioning, and Demolition (D4) Project during the demolition and removal of the portions of the 105-N/109-N Buildings, located outside of the safe storage enclosure (SSE).

The Field Remediation (FR) Project resumed remedial action activities west of the 105-N/109-N Reactor in November 2012. Contaminated soil, structural concrete and rebar, and piping were removed from the collocated waste sites west of the 105-N/109-N Reactor and disposed at the Environmental Restoration Disposal Facility (ERDF). The remediation continued through March 2013 to an approximate maximum depth of 9.5 meters (31 ft) below surface grade. No anomalous materials were encountered during remediation. The remediation resulted in one large excavation with no demarcation of the individual sites, with the exception of the UPR-100-N-39 waste site. Some segments of the 100-N-61:3 and 100-N-64:3 pipelines were removed with remedial action at the 100-N-57, (1304-N) Emergency Dump Tank and 116-N-4, (1300-N) Emergency Dump Basin waste sites.

After the remediation, Global Positioning Environmental Radiological Surveyor (GPERS) surveys were performed in March 2013. Some beta and gamma contamination was detected above background. However, the area with the highest detected activity is associated with residual structures and soils for the 105-N/109-N SSE and is considered part of the 100-N-66, 105-N/109-N Reactor Building Complex waste site. A small area with elevated beta and gamma contamination was detected within the waste sites west of the 105-N/109-N Reactor boundary. Additional soil was removed from this area and disposed at the ERDF. An environmental radiological survey of the area using hand-held instruments verified that the contaminated soils have been removed.

The 1909-N Waste Disposal Valve Pit was removed during general facility demolition in this area by the D4 Project. Due to the proximity and general configuration of demolition and remediation activities on the west side of the reactor, closure of the facility footprint was deferred until nearby waste site remediation by the FR Project occurred. The residual contaminated soil that remained beneath the location of the former 1909-N facility was then removed.

The 107-N basin structure was completely removed by the D4 Project. However, closure of the basin footprint was deferred to the UPR-100-N-12 waste site. Additional soil was removed

from the footprint during general waste site remediation in the area. Surveys found no elevated residual radiological activity.

Several segments of the 100-N-84 pipeline subsites were partially located within the remediation boundary. All of the segments of the 100-N-84:2, 100-N-84:4, 100-N-84:5, and 100-N-84:6 pipeline subsites that were within the excavation boundary were removed and disposed at the ERDF. Reclassification of the total 100-N-84:2, 100-N-84:4, 100-N-84:5 and 100-N-84:6 pipeline subsites will be addressed in separate closure documents.

Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Code:	UPR-100-N-4	Classification:	Accepted
Names:	UPR-100-N-4; 1322-A Sump Overflow; UN-100-N-4	Reclassification	Interim Closed Out (8/31/2013)
Type:	Unplanned Release	Start Date:	5/7/1977
Status:	Inactive	End Date:	5/7/1977
Description:	The waste site has been remediated and Interim Closed Out. It was an overflow of contaminated water at the 1322-NA (Effluent Water Pilot Plant) that affected the floor inside the building and ground near the front and rear doors outside the building. The site also includes the drainage tank in Building 1322-N (Waste Treatment Pilot Plant Facility).		
Location:	The 1322 Buildings are about 195 meters (640 feet) northeast of the 105-N (Reactor Facility).		
Release Description:	The 1322-N Drainage Tank top vent sprayed low-level radioactive water. The 1322-NA sink drain backed up and flowed over the 15-centimeter (6-inch) curb and onto the ground in the front and back of the building. The release occurred on May 7, 1977.		
Related Sites/Structures:	The site is associated with UPR-100-N-8, UPR-100-N-31 and Buildings 105-N, 1322-N, and 1322-NA.		
Waste Type:	Water		
Waste Description:	The site received low-level radioactive water. The total activity was 0.5 millicuries.		
Closure Info:	Interim (8/13/2013): The 1322N, 1322NA, 1322NB, and 1322NC above-ground buildings and slabs in the vicinity of the unplanned releases were removed during the 100-N deactivation, decommission, decontamination, and demolition (D4) activities. The removal included an excavation that measured approximately 3.7 meters (12 ft) deep. The UPR-100-N-4 and UPR-100-N-8 waste sites are associated with the 1322-N/NA Buildings. The UPR-100-N-31 waste site is associated with the 116-N-1 (1301-N) Crib and Trench. Because the locations of the UPR-100-N-4, UPR-100-N-8, and UPR-100-N-31 unplanned release sites were in close proximity to each other and no information was available to delineate the boundary of each release, the three sites were combined into one excavation. The excavation for remediation of the combined unplanned release sites was immediately adjacent to the former 116-N-1 (1301-N) remediation site. Further remediation of the UPR-100-N-4, UPR-100-N-8, and UPR-100-N-31 waste site soils was performed between December 13, 2011 and March 19, 2012, resulting in a combined excavation approximately 7 meters (23 ft) deep.		

Approximately 5,683 bank cubic meters (BCM) (7,433 bank cubic yards [BCY]) of additional contaminated soil, rocks, and concrete was removed for disposal at the Environmental Restoration Disposal Facility (ERDF). Additional contaminated soil was removed from areas SZ-6, SZ-8, and SZ-9 between January 30, 2013 and February 4, 2013, resulting in an

additional 189 BCM (247 BCY) of contaminated soil removed for disposal at ERDF. Areas of stained soil remained in the deep zone (more than 4.6 meters [15 ft] below ground surface [bgs]) following the completion of the remedial action activities. All material was direct loaded from the excavation for disposal at ERDF. No overburden piles or anomalies were associated with the remediation.

During remediation of the unplanned release sites, increasing radiological activity was observed with depth approaching soils underlying the former 116-N-1 crib. Deep zone sample results from the UPR-100-N-4, UPR-100-N-8, and UPR-100-N-31 remediation are also consistent with residual contamination in the 116-N-1 deep zone. This suggests that the contamination encountered was residual from 116-N-1 left in place in the deep zone, and that deep zone remediation of the UPR-100-N-4, UPR-100-N-8, and UPR-100-N-31 waste sites is considered complete. The liquid waste effluents associated with the UPR-100-N-31 and 116-N-1 waste sites are the same.

Code:	UPR-100-N-5	Classification:	Accepted
Names:	UPR-100-N-5; 116-N-2 Radioactive Chemical Waste Treatment Storage Facility; 1310-N Chemical Waste Storage Tank Leak; UN-100-N-5	Reclassification	Interim Closed Out (5/7/2013)
Type:	Unplanned Release	Start Date:	1/1/1972
Status:	Inactive	End Date:	1/1/1972
Description:	The waste site has been remediated and Interim Closed Out. The release occurred in the 1310-N Radioactive Chemical Waste Handling Facility on the recirculation pump discharge line.		
Location:	The site was located in the 100N Area, northeast of the center of the 105-N (Reactor Facility). It was approximately 10.4 meters (134 feet) northwest of the 1310-N Chemical Waste Storage Tank and 233 meters (833 feet) from the bank of the Columbia River. The spill site was within a radiation control zone.		
Release Description:	A leak occurred in the piping at the Radioactive Chemical Waste Handling Facility, between the recirculation pump and the 116-N-2 Tank, and radioactive waste was discharged to the ground. The start date was June 16, 1972 and the end date was June 27, 1972.		
Related Sites/Structures:	The site is associated with the 105-N Reactor Facility and the 1310-N Chemical Waste Storage Tank.		
Waste Type:	Water		
Waste Description:	The leak consisted of 340,650 liters (90,000 gallons) of radioactive wastewater containing decontaminated chemicals. The waste contained approximately 35 curies of activity, of which 26 curies were cobalt-60. The solution had a pH of approximately 9.		
Closure Info:	Interim (5/7/2013): Remedial action of the 116-N-2 (Golf Ball) waste site was performed between March 1, 2011 and April 26, 2012. Equipment decontamination was conducted within the southeast corner of the waste site excavation, and that area was remediated May 7 and 8, 2012. The maximum depth of the excavation was 13 meters (42.7 ft) bgs and resulted in the removal of approximately 11,144 bank cubic meters (BCM) (14,576 bank cubic yards [BCY]) of soil and debris. The debris consisted of rock, sand, and piping material. The contaminated soil and debris were directly loaded out for disposal at the Environmental Restoration Disposal Facility (ERDF). Also removed with the 116-N-2 excavation were the UPR-100-N-5 and UPR-100-N-25 waste sites, as well as portions of the 100-N-84 and 100-N-63 pipelines. A section of the 100-N-63:2 pipeline remained on a side slope in the northern part of the excavation until it was remediated between March 22, and 25, 2013. No anomalous material was found during remediation. No in-process samples were collected for the 116-N-2 grouping of waste sites.		

Clean padding material (soil and gravel) had been previously placed on the ground surface south of the excavation to cover radiological contamination that resulted from the previous D4 activities to remove the golf ball and silo structures. The padding material and approximately 2 meters (6.5 ft) of soil below the padding was scraped and removed for disposal at ERDF.

Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Code:	UPR-100-N-6	Classification:	Accepted
Names:	UPR-100-N-6; 1 1/2 Inch Chemical Decontam. Waste Drain Line Leaks; Chemical Decontamination Waste Drain Line Leak; UN-100-N-6; UN-116-N-6	Reclassification	Interim Closed Out (1/2/2013)
Type:	Unplanned Release	Start Date:	9/10/1985
Status:	Inactive	End Date:	9/10/1985
Description:	The waste site has been remediated and Interim Closed Out. It was a release from a 1.5 inch diameter, chemical decontamination waste drain line. The release leaked radiologically contaminated water into the surrounding soil. The line was 0.9 meters (3 feet) below grade.		
Location:	The release site was located between the north wall of the 1714-NB building and the 1310-N tank.		
Release Description:	The buried 3.8-centimeter (1.5 inch) line leaked radiologically contaminated water in the general area between buildings 1714-N and 1310-N. The release occurred on September 10, 1985. The release consisted of approximately 6,813 liters (1,800 gal) of radiologically contaminated water containing an estimated 0.2 Ci of cobalt-60, 0.04 Ci of manganese-54, 0.003 Ci of ruthenium-103, and 0.003 Ci of cesium-137. Approximately 16.7 cubic meters (590 cubic feet) of contaminated soil reading 7,000 to 25,000 counts per minute was removed from four locations along the line. The excavations were backfilled with clean soil.		
Related Sites/Structures:	This drain line interconnects with 105-N and 1310-N (Chemical Waste Storage Tank) and 100-N-62:2.		
Process Description:	This site is a 3.8 centimeter (1.5 inch) waste line, buried 0.9 meters (3 feet) below grade. This chemical decontamination waste drain line runs between the 105-N reactor building and the 1310-N (Chemical Waste Storage Tank).		
Waste Type:	Process Effluent		
Waste Description:	The release consisted of approximately 6,813 liters (1,800 gallons) of radiologically contaminated water containing an estimated 0.2 curies cobalt-60, 0.04 curies manganese-54, 0.003 curies ruthenium-103, and 0.003 curies of cesium-137.		
Closure Info:	Interim (1/2/2013): Remedial action at the UPR-100-N-6 waste site to remove the pipeline and associated contaminated soil was performed between September 20, 2011, and April 18, 2012. All excavated materials were direct loaded for disposal at the Environmental Restoration Disposal Facility (ERDF). Excavation continued until all debris and contamination associated with collocated waste sites had been removed. The depth of the excavation was approximately 2.4 to 3.7 meters (8 to 12 ft) below ground surface. All excavated materials were direct loaded for disposal at the Environmental Restoration Disposal Facility (ERDF).		

Because the UPR-100-N-6 waste site originated from 100-N-63:2 pipeline leaks and the excavation was performed to remediate both waste sites simultaneously. The volume of material removed for the UPR-100-N-6 waste site alone was not calculated. The volumes

disposed from this excavation are included in the 100-N-63:2 waste site closeout documents.

Code: UPR-100-N-7	Classification: Accepted
Names: UPR-100-N-7; Ten-Inch Radioactive Drain Return Line Leak; UN-100-N-7; UN-116-N-7	Reclassification: Interim Closed Out (9/6/2013)
Type: Unplanned Release	Start Date: 4/29/1985
Status: Inactive	End Date: 5/1/1985

Description: The release site has been remediated and Interim Closed Out. The 100-N-31 waste site was located on the west side of the 105-N/109-N Reactor Buildings and adjacent to the 100-N-32, 100-N-38, 100-N-61 :3, 100-N-64:3, 100-N-68, UPR-100-N-3, UPR-100-N-7, UPR-100-N-10, UPR-100-N-12, and UPR-100-N-39 waste sites. These waste sites are collectively referred to as the waste sites west of the 105-N/109-N Reactor. The remediation of these waste sites resulted in one large excavation with no demarcation of the individual sites, with the exception of the UPR-100-N-39 waste site. The eleven sites were Interim Closed out in a single document.

It was a leak that occurred in a buried 25.4-centimeter (10-inch) drain line between the 109-N Building and the 1909-N Valve Pit. The release occurred on April 29, 1985.

Location: The site is located near the northwest corner of the 109-N Building. The leak occurred in a section of 25.4 centimeter (10-inch) diameter radioactive drain return pipe located between the 109-N Building and the 1909-N Valve Pit.

Release Description: Adjacent groundwater monitoring wells detected increased levels of iodine-131, indicating a nearby leak to the water table. Approximately 1,907,842 liters (504,000 gallons) had leaked. The release occurred on April 29, 1985.

Related Sites/Structures: The 25.4 centimeter (10 inch) Radioactive Drain Return (RDR) line connected to the 109-N Building and the 1909 Valve Pit. The release site is associated with 100-N-31, 100-N-32, 100-N-38, 100-N-61 :3, 100-N-64:3, 100-N-68, UPR-100-N-3, UPR-100-N-10, UPR-100-N-12, and UPR-100-N-39.

Waste Type: Process Effluent

Waste Description: The release consisted of approximately 1,907,042 liters (504,053 gallons) of radiologically contaminated N-Reactor cooling water containing an estimated 1.0 curies sodium-24, 0.5 curies cobalt-60, 0.09 curies ruthenium-103, 0.4 curies chromium-51, 0.2 curies zirconium-95, 0.3 curies tellurium-132, 0.30 curies manganese-54, 0.1 curies niobium-95, 0.5 curies iodine-131, 1.2 curies iron-59, 0.2 curies cerium-141, 0.2 curies cerium-144, and 0.8 curies technecium-99.

Closure Info: Interim (9/6/2013): Eleven waste sites located west of the 105-N/109-N Reactor Building were remediated as a group. The eleven waste sites included 100-N-31, 100-N-32, 100-N-38, 100-N-61:3, 100-N-64:3, 100-N-68, UPR-100-N-3, UPR-100-N-7, UPR-100-N-10, UPR-100-N-12, and UPR-100-N-39. This group of waste sites was referred to as the waste sites west of the 105-N/109-N Reactor. The footprints of the 1909-N Waste Disposal Valve Pit, the 107-N facility and the pipe trench between 105-N and 107-N were also located within the boundary of the group.

The eleven collocated waste sites located west of the 105-N/109-N Reactor Building were remediated, either partially or completely, by the Deactivation, Decontamination, Decommissioning, and Demolition (D4) Project during the demolition and removal of the portions of the 105-N/109-N Buildings, located outside of the safe storage enclosure (SSE).

The Field Remediation (FR) Project resumed remedial action activities west of the 105-N/109-N Reactor in November 2012. Contaminated soil, structural concrete and rebar, and piping were

removed from the collocated waste sites west of the 105-N/109-N Reactor and disposed at the Environmental Restoration Disposal Facility (ERDF). The remediation continued through March 2013 to an approximate maximum depth of 9.5 meters (31 ft) below surface grade. No anomalous materials were encountered during remediation. The remediation resulted in one large excavation with no demarcation of the individual sites, with the exception of the UPR-100-N-39 waste site. Some segments of the 100-N-61:3 and 100-N-64:3 pipelines were removed with remedial action at the 100-N-57, (1304-N) Emergency Dump Tank and 116-N-4, (1300-N) Emergency Dump Basin waste sites.

After the remediation, Global Positioning Environmental Radiological Surveyor (GPERS) surveys were performed in March 2013. Some beta and gamma contamination was detected above background. However, the area with the highest detected activity is associated with residual structures and soils for the 105-N/109-N SSE and is considered part of the 100-N-66, 105-N/109-N Reactor Building Complex waste site. A small area with elevated beta and gamma contamination was detected within the waste sites west of the 105-N/109-N Reactor boundary. Additional soil was removed from this area and disposed at the ERDF. An environmental radiological survey of the area using hand-held instruments verified that the contaminated soils have been removed.

The 1909-N Waste Disposal Valve Pit was removed during general facility demolition in this area by the D4 Project. Due to the proximity and general configuration of demolition and remediation activities on the west side of the reactor, closure of the facility footprint was deferred until nearby waste site remediation by the FR Project occurred. The residual contaminated soil that remained beneath the location of the former 1909-N facility was then removed.

The 107-N basin structure was completely removed by the D4 Project. However, closure of the basin footprint was deferred to the UPR-100-N-12 waste site. Additional soil was removed from the footprint during general waste site remediation in the area. Surveys found no elevated residual radiological activity.

Several segments of the 100-N-84 pipeline subsites were partially located within the remediation boundary. All of the segments of the 100-N-84:2, 100-N-84:4, 100-N-84:5, and 100-N-84:6 pipeline subsites that were within the excavation boundary were removed and disposed at the ERDF. Reclassification of the total 100-N-84:2, 100-N-84:4, 100-N-84:5 and 100-N-84:6 pipeline subsites will be addressed in separate closure documents.

Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Code:	UPR-100-N-8	Classification:	Accepted
Names:	UPR-100-N-8; 1322-A Sump Overflow; UN-100-N-8	Reclassification	Interim Closed Out (8/31/2013)
Type:	Unplanned Release	Start Date:	5/11/1975
Status:	Inactive	End Date:	5/11/1975
Description:	The waste site has been remediated and Interim Closed Out. It was an overflow of contaminated water at the 1322-NA (Effluent Water Pilot Plant) that affected the area (approximately 2.3 square meters [25 sq. ft]) surrounding the sump, floor, various pieces of equipment, and the ground just outside the rear door (south door).		
Location:	The 1322-NA Building was located approximately 195 meters (640 feet) northeast of the 105-N Reactor Facility. The release took place in the soil immediately outside the south door of 1322-		

NA Effluent Water Pilot Plant. This is partly on the same location as UPR-100-N-4.

- Release Description:** The 0.3-centimeter (1/8-inch) tygon sample tube came off the 91-centimeter (36-inch) radioactive drain return line sampler sample line and up to 379 liters (100 gallons) of radioactive water was released to the soil.
- Related Sites/ Structures:** The site is associated with UPR-100-N-4, UPR-100-N-31 and Buildings 105-N, 1322-N, and 1322-NA.
- Waste Type:** Water
- Waste Description:** The release contained up to 379 liters (100 gallons) of radioactive water contaminated with mixed fission and activation products to a level of 1,000,000 picocuries/liter. The total activity was 0.5 millicuries.
- Closure Info:** Interim (8/13/2013): The 1322N, 1322NA, 1322NB, and 1322NC above-ground buildings and slabs in the vicinity of the unplanned releases were removed during the 100-N deactivation, decommission, decontamination, and demolition (D4) activities. The removal included an excavation that measured approximately 3.7 meters (12 ft) deep. The UPR-100-N-4 and UPR-100-N-8 waste sites are associated with the 1322-N/NA Buildings. The UPR-100-N-31 waste site is associated with the 116-N-1 (1301-N) Crib and Trench. Because the locations of the UPR-100-N-4, UPR-100-N-8, and UPR-100-N-31 unplanned release sites were in close proximity to each other and no information was available to delineate the boundary of each release, the three sites were combined into one excavation. The excavation for remediation of the combined unplanned release sites was immediately adjacent to the former 116-N-1 (1301-N) remediation site. Further remediation of the UPR-100-N-4, UPR-100-N-8, and UPR-100-N-31 waste site soils was performed between December 13, 2011 and March 19, 2012, resulting in a combined excavation approximately 7 meters (23 ft) deep.

Approximately 5,683 bank cubic meters (BCM) (7,433 bank cubic yards [BCY]) of additional contaminated soil, rocks, and concrete was removed for disposal at the Environmental Restoration Disposal Facility (ERDF). Additional contaminated soil was removed from areas SZ-6, SZ-8, and SZ-9 between January 30, 2013 and February 4, 2013, resulting in an additional 189 BCM (247 BCY) of contaminated soil removed for disposal at ERDF. Areas of stained soil remained in the deep zone (more than 4.6 meters [15 ft] below ground surface [bgs]) following the completion of the remedial action activities. All material was direct loaded from the excavation for disposal at ERDF. No overburden piles or anomalies were associated with the remediation.

During remediation of the unplanned release sites, increasing radiological activity was observed with depth approaching soils underlying the former 116-N-1 crib. Deep zone sample results from the UPR-100-N-4, UPR-100-N-8, and UPR-100-N-31 remediation are also consistent with residual contamination in the 116-N-1 deep zone. This suggests that the contamination encountered was residual from 116-N-1 left in place in the deep zone, and that deep zone remediation of the UPR-100-N-4, UPR-100-N-8, and UPR-100-N-31 waste sites is considered complete. The liquid waste effluents associated with the UPR-100-N-31 and 116-N-1 waste sites are the same.

Code: UPR-100-N-9	Classification: Accepted
Names: UPR-100-N-9; 119-N Cooling Water Drain Line Leak; UN-100-N-9	Reclassification: Interim Closed Out (7/2/2013)
Type: Unplanned Release	Start Date: 10/14/1974
Status: Inactive	End Date:

-
- Description:** The site has been remediated and Interim Closed Out. The Unplanned Release was the area where a backhoe ruptured a cooling water drain valve during an excavation activity in 1974. The excavation depth was greater than 1.2 meters (4 feet) below grade and included a 5-centimeter (2-inch) valve on a drain line. The event resulted in radioactively contaminated water flowing into the open excavation.
- Location:** The site is located in the 100N Area, north of 105-N (Reactor Facility) and about 26 meters (85 feet) northwest of 119-N (Air Sample Monitoring Stack Sampler).
- Release Description:** This site was documented on Unusual Occurrence Report Number 74-29. A backhoe accidentally ruptured a buried 5-centimeter (2-inch) diameter cooling water drain valve during exploratory digging. Contaminated water immediately flowed into the excavation hole around the valve at approximately 19 liters (5 gallons) per minute and maintained a water level 1.2 meters (4 feet) below grade. The release occurred on October 14, 1974.
- Related Sites/Structures:** The site is associated with the 105-N (Lift Station), the 116-N-1 Crib and Trench, and the 119-N (Air Sample Monitoring Stack Sampler).
- Waste Type:** Water
- Waste Description:** The release of 8,327 liters (2,200 gallons) of low-level radioactive contaminated water contained about 500,000 picocuries. The water was released from the 119-N cooling water drain line.
- Closure Info:** Interim (7/2/2013): Remedial action at the 100-N-87, 100-N-102:1, UPR-100-N-14, and UPR-100-N-9 waste sites was performed during January and February 2011. Remediation involved removal of the foundations of the 116-N stack, the 119-N and 119-NA structures, and the underlying soil. Excavation continued until the french drain, associated piping, and contaminated soil and debris were removed. This excavation exceeded the depth that would be required to remove the 100-N-102:1, UPR-100-N-9, and UPR-100-N-14 waste sites. According to drawing H-1-46389, the depth of the 100-N-102:1 subsite, and therefore the unplanned release waste sites UPR-100-N-9 and UPR-100-N-14, was at 0.76 meters (2.5 ft) bgs. The final excavation depth was approximately 8.5 meters (28 ft) bgs. Because the excavation and removal of the 116-N stack foundation was previously performed by the D4 Project, the exact volume of material removed is unknown.
- The debris removed included soil, concrete, piping, and other debris associated with the 116-N, 119-N, and 119-NA structures and french drain. All material from these waste sites was disposed at the Environmental Restoration Disposal Facility (ERDF). No anomalous material was encountered during the excavation.
- In March 2012, the D4 Project constructed a ramp across the 100-N-87, 100-N-102:1, UPR-100-N-14, and UPR-100-N-9 excavation to provide access and to support remediation activities at 1303-N (118-N-1) waste site. The ramp material was excavated on September 28, 2012, and also disposed of at ERDF. A walk around the site boundary confirmed that all fill material used to build the ramp had been removed. After the excavation of the ramp material, a gamma survey was performed on October 3, 2012, within the 100-N-87, 100-N-102:1, UPR-100-N-14, and UPR-100-N-9 excavation. The gamma survey results indicated readings above background at two locations. Additional remediation was performed to address areas where the GPERS survey results indicated elevated radiological results. Follow up surveys on October 17, 2012 and October 19, 2012 indicated no elevated readings above background.
- Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).
-

Code: UPR-100-N-10

Classification: Accepted

Names: UPR-100-N-10; 100-N Area 105-N Check Valve; **Reclassification** Interim Closed Out (9/6/2013)
Lift Station Gravity Drain Line Leak; UN-100-N-10

Type: Unplanned Release **Start Date:** 5/13/1975

Status: Inactive **End Date:** 5/13/1975

Description: The waste site has been remediated and Interim Closed Out. The 100-N-31 waste site was located on the west side of the 105-N/109-N Reactor Buildings and adjacent to the 100-N-32, 100-N-38, 100-N-61 :3, 100-N-64:3, 100-N-68, UPR-100-N-3, UPR-100-N-7, UPR-100-N-10, UPR-100-N-12, and UPR-100-N-39 waste sites. These waste sites are collectively referred to as the waste sites west of the 105-N/109-N Reactor. The remediation of these waste sites resulted in one large excavation with no demarcation of the individual sites, with the exception of the UPR-100-N-39 waste site. The eleven sites were Interim Closed out in a single document.

UPR-100-N-10 was a release of contaminated water from a drain line to the ground. The leak occurred in an area previously marked as a radiation zone.

Location: The leak occurred in the 100-N Area near the north side of the 105-N Lift Station, about 4.7 meters (15.4 feet) northeast of the 1722-N Decontamination Hot Shop, and about 160 meters (530 ft) from the Columbia River. This was the same the location as the UPR-100-N-3 and UPR-100-N-12 releases.

Release Description: Approximately 379 liters (100 gallons) of contaminated water leaked to the ground during preparations for the removal of a check valve in the gravity drain line to the lift station on May 13, 1975.

Related Sites/ Structures: The leak is associated with the 105-N Reactor Facility, UPR-100-N-3 and UPR-100-N-12.

Waste Type: Water

Waste Description: The release contained 0.001 curies of mixed fission and activation products.

Closure Info: Interim (9/6/2013): Eleven waste sites located west of the 105-N/109-N Reactor Building were remediated as a group. The eleven waste sites included 100-N-31, 100-N-32, 100-N-38, 100-N-61:3, 100-N-64:3, 100-N-68, UPR-100-N-3, UPR-100-N-7, UPR-100-N-10, UPR-100-N-12, and UPR-100-N-39. This group of waste sites was referred to as the waste sites west of the 105-N/109-N Reactor. The footprints of the 1909-N Waste Disposal Valve Pit, the 107-N facility and the pipe trench between 105-N and 107-N were also located within the boundary of the group.

The eleven collocated waste sites located west of the 105-N/109-N Reactor Building were remediated, either partially or completely, by the Deactivation, Decontamination, Decommissioning, and Demolition (D4) Project during the demolition and removal of the portions of the 105-N/109-N Buildings, located outside of the safe storage enclosure (SSE).

The Field Remediation (FR) Project resumed remedial action activities west of the 105-N/109-N Reactor in November 2012. Contaminated soil, structural concrete and rebar, and piping were removed from the collocated waste sites west of the 105-N/109-N Reactor and disposed at the Environmental Restoration Disposal Facility (ERDF). The remediation continued through March 2013 to an approximate maximum depth of 9.5 meters (31 ft) below surface grade. No anomalous materials were encountered during remediation. The remediation resulted in one large excavation with no demarcation of the individual sites, with the exception of the UPR-100-N-39 waste site. Some segments of the 100-N-61:3 and 100-N-64:3 pipelines were removed with remedial action at the 100-N-57, (1304-N) Emergency Dump Tank and 116-N-4, (1300-N)

Emergency Dump Basin waste sites.

After the remediation, Global Positioning Environmental Radiological Surveyor (GPERS) surveys were performed in March 2013. Some beta and gamma contamination was detected above background. However, the area with the highest detected activity is associated with residual structures and soils for the 105-N/109-N SSE and is considered part of the 100-N-66, 105-N/109-N Reactor Building Complex waste site. A small area with elevated beta and gamma contamination was detected within the waste sites west of the 105-N/109-N Reactor boundary. Additional soil was removed from this area and disposed at the ERDF. An environmental radiological survey of the area using hand-held instruments verified that the contaminated soils have been removed.

The 1909-N Waste Disposal Valve Pit was removed during general facility demolition in this area by the D4 Project. Due to the proximity and general configuration of demolition and remediation activities on the west side of the reactor, closure of the facility footprint was deferred until nearby waste site remediation by the FR Project occurred. The residual contaminated soil that remained beneath the location of the former 1909-N facility was then removed.

The 107-N basin structure was completely removed by the D4 Project. However, closure of the basin footprint was deferred to the UPR-100-N-12 waste site. Additional soil was removed from the footprint during general waste site remediation in the area. Surveys found no elevated residual radiological activity.

Several segments of the 100-N-84 pipeline subsites were partially located within the remediation boundary. All of the segments of the 100-N-84:2, 100-N-84:4, 100-N-84:5, and 100-N-84:6 pipeline subsites that were within the excavation boundary were removed and disposed at the ERDF. Reclassification of the total 100-N-84:2, 100-N-84:4, 100-N-84:5 and 100-N-84:6 pipeline subsites will be addressed in separate closure documents.

Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Code:	UPR-100-N-11	Classification:	Accepted
Names:	UPR-100-N-11; 100-N Area Valve Bonnet; Five Hundred Pound Valve Bonnet Contamination in Uncontrolled Area; UN-100-N-11	Reclassification	Interim Closed Out (1/26/2012)
Type:	Unplanned Release	Start Date:	10/2/1975
Status:	Inactive	End Date:	10/3/1975
Description:	The waste site has been remediated. The contaminated site consisted of asphalt road, shoulder/roadside, and field area.		
Location:	The site was located on the east side of Highway 4 North, approximately 45.7 meters (150 feet) southeast of the center line of 100-N access road.		
Release Description:	A contaminated 227-kilogram (500-pound) valve bonnet, wooden box, and plastic wrapping fell from a truck onto the road and into a field adjacent to the roadway. The wooden box broke open spreading spot contamination on the roadway and in the field. Contamination levels on roadway blacktop at the point of impact was 1,000 mrad/hr (1 rad/hr). Contamination on roadway adjacent to where valve hit was 20,000 to 50,000 counts per minute. The area where valve came to rest measured 5 rads to 10 rads per hour. The area adjacent to where valve came to rest measured 25,000 to 50,000 counts per minute.		

Related Sites/ Structures: The release is associated with the 105-N Reactor Facility.

Waste Type: Equipment

Waste Description: Five to 10 rads per hour were measured where the valve bonnet came to rest in the field. Measurements of 1,000 millirads per hour were taken where it hit the road; 20,000 to 5,000 counts per minute on 18.6 square meters (200 square feet) of road; and 25,000 to 50,000 on the surface of the field adjacent to the valve bonnet.

Closure Info: Interim (1/26/2012): Remediation of the UPR-100-N-11 waste site was completed on November 16, 2010, to a depth of approximately 0.5 meters (1.6 ft). The field area and part of the roadside ditch were the target of remedial actions for the UPR-100-N-11 waste site, which excavated an area approximately 11 by 5 meters (36 by 16 ft). The contaminated soil was direct loaded from the excavation. Radiological surveys were conducted during remediation using hand-held radiological detection instruments. Additionally, a Global Positioning Environmental Radiological Surveyor (GPERS) survey was conducted within the UPR-100-N-11 excavation upon completion of remedial activities. No elevated radiological activity was detected by either of the survey methods. None of the current, existing roadway was removed, because the 1975 occurrence report provided a large amount of detail on removal of the roadway contamination. No stains or other anomalies were observed during field activities.

Code: UPR-100-N-12	Classification: Accepted
Names: UPR-100-N-12; Spacer Transport Line Leak; UN-100-N-12	Reclassification: Interim Closed Out (9/6/2013)
Type: Unplanned Release	Start Date: 1/1/1979
Status: Inactive	End Date: 3/13/1979

Description: The release site has been remediated and Interim Closed Out. The 100-N-31 waste site was located on the west side of the 105-N/109-N Reactor Buildings and adjacent to the 100-N-32, 100-N-38, 100-N-61 :3, 100-N-64:3, 100-N-68, UPR-100-N-3, UPR-100-N-7, UPR-100-N-10, UPR-100-N-12, and UPR-100-N-39 waste sites. These waste sites are collectively referred to as the waste sites west of the 105-N/109-N Reactor. The remediation of these waste sites resulted in one large excavation with no demarcation of the individual sites, with the exception of the UPR-100-N-39 waste site. The eleven sites were Interim Closed out in a single document.

UPR-100-N-12 was first identified as a 0.6 by 0.9 meter (2 by 3 foot) diameter and 0.46 meter (1.5 foot) deep sink hole cause by a pipe leak.

Location: The site is located in the 100-N Area near the north side of the 105-N Lift Station, about 5 meters (15 feet) west of the 1722-N Decontamination Hot Shop, and about 160 meters (530 ft.) from the Columbia River. This was also the same location as the UPR-100-N-3 and UPR-100-N-10 releases.

Release Description: The dummy fuel spacer transfer line, (7.6 centimeter (3 inch) reinforced Bonstrand plastic pipe) extended from the 100-N Fuel Storage Basin to the dummy disposal pit. The maximum leak rate was estimated to be 284 liters (75 gallons) per minute. It is not known how long the leak had been occurring. The approximate maximum time the valve could have been open was 55 hours. The estimated release was 946,000 liters (250,000 gal) of fuel storage basin water. The water was originally from the fuel storage basin and had been used to help transport fuel spacers through the spacer transport line. Dummy spacers were transferred December 4,5,10,11,12,13,14, and January 8. The release was reported March 13, 1979.

Related Sites/ Structures: The release is associated with the 100-N Area Spacer Silos (118-N) and 105-N Fuel Storage Basin, UPR-100-N-3 and UPR-100-N-10.

Waste Type: Water

Waste Description: The release consisted of 946,000 liters (250,000 gallons) of storage basin water containing 0.19 curies of cobalt-60, 0.4 curies of cesium-137, and 0.00057 curies of plutonium-239/240. The water was originally from the fuel storage basin and had been used to help dislodge fuel spacers through the spacer transport line. Excavated soil was checked for radioactivity and read 50 to 100 millirem per hour.

Closure Info: Interim (9/6/2013): Eleven waste sites located west of the 105-N/109-N Reactor Building were remediated as a group. The eleven waste sites included 100-N-31, 100-N-32, 100-N-38, 100-N-61:3, 100-N-64:3, 100-N-68, UPR-100-N-3, UPR-100-N-7, UPR-100-N-10, UPR-100-N-12, and UPR-100-N-39. This group of waste sites was referred to as the waste sites west of the 105-N/109-N Reactor. The footprints of the 1909-N Waste Disposal Valve Pit, the 107-N facility and the pipe trench between 105-N and 107-N were also located within the boundary of the group.

The eleven collocated waste sites located west of the 105-N/109-N Reactor Building were remediated, either partially or completely, by the Deactivation, Decontamination, Decommissioning, and Demolition (D4) Project during the demolition and removal of the portions of the 105-N/109-N Buildings, located outside of the safe storage enclosure (SSE).

The Field Remediation (FR) Project resumed remedial action activities west of the 105-N/109-N Reactor in November 2012. Contaminated soil, structural concrete and rebar, and piping were removed from the collocated waste sites west of the 105-N/109-N Reactor and disposed at the Environmental Restoration Disposal Facility (ERDF). The remediation continued through March 2013 to an approximate maximum depth of 9.5 meters (31 ft) below surface grade. No anomalous materials were encountered during remediation. The remediation resulted in one large excavation with no demarcation of the individual sites, with the exception of the UPR-100-N-39 waste site. Some segments of the 100-N-61:3 and 100-N-64:3 pipelines were removed with remedial action at the 100-N-57, (1304-N) Emergency Dump Tank and 116-N-4, (1300-N) Emergency Dump Basin waste sites.

After the remediation, Global Positioning Environmental Radiological Surveyor (GPERS) surveys were performed in March 2013. Some beta and gamma contamination was detected above background. However, the area with the highest detected activity is associated with residual structures and soils for the 105-N/109-N SSE and is considered part of the 100-N-66, 105-N/109-N Reactor Building Complex waste site. A small area with elevated beta and gamma contamination was detected within the waste sites west of the 105-N/109-N Reactor boundary. Additional soil was removed from this area and disposed at the ERDF. An environmental radiological survey of the area using hand-held instruments verified that the contaminated soils have been removed.

The 1909-N Waste Disposal Valve Pit was removed during general facility demolition in this area by the D4 Project. Due to the proximity and general configuration of demolition and remediation activities on the west side of the reactor, closure of the facility footprint was deferred until nearby waste site remediation by the FR Project occurred. The residual contaminated soil that remained beneath the location of the former 1909-N facility was then removed.

The 107-N basin structure was completely removed by the D4 Project. However, closure of the basin footprint was deferred to the UPR-100-N-12 waste site. Additional soil was removed from the footprint during general waste site remediation in the area. Surveys found no elevated residual radiological activity.

Several segments of the 100-N-84 pipeline subsites were partially located within the remediation boundary. All of the segments of the 100-N-84:2, 100-N-84:4, 100-N-84:5, and

100-N-84:6 pipeline subsites that were within the excavation boundary were removed and disposed at the ERDF. Reclassification of the total 100-N-84:2, 100-N-84:4, 100-N-84:5 and 100-N-84:6 pipeline subsites will be addressed in separate closure documents.

Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Code:	UPR-100-N-13	Classification:	Accepted
Names:	UPR-100-N-13; 1314-N Drywell Overflow; 1314-N Loading Station; UN-100-N-13	Reclassification	Interim Closed Out (3/28/2013)
Type:	Unplanned Release	Start Date:	9/24/1973
Status:	Inactive	End Date:	9/24/1973
Description:	The Unplanned Release has been remediated and Interim Closed Out. It consisted of a release of liquid, radioactively contaminated, spent decontamination solution.		
Location:	The release was located near the northeast corner of the 1314-N building, inside the posted radiation zone at the 1314-N Liquid Waste Loadout Station.		
Release Description:	This release was documented on Unusual Occurrence Report number 73-39. The release occurred on September 24, 1973 and was reported on October 3, 1973. The solution began overflowing from the tank car fittings after approximately 26,500 liters (7,000 gal) had been pumped into the 75,700 liters (20,000 gal) tank car during filling operations. The tank car loading pump was turned off, but the solution began to back flow through the drain in the catch basin beneath the tank car. The catch basin then began to overflow into the adjacent drywell, the capacity of which was also exceeded. The resulting drywell overflow caused the solution to cover a 1.9 square meters (20 ft ²) of ground inside the radiation zone at the loading station. Approximately 380 liters (100 gal) of solution was released to the ground with a total activity on the ground surface estimated at 0.015 curies. Evaluation revealed that approximately 280 liters (75 gal) of solution containing 0.011 curies was discharged to the ground through the drywell. An unknown amount of contaminated soil was removed, packaged, and shipped to the 200 Area burial ground for disposal. Clean fill material was used to cover a portion of the contaminated soil that remained.		
Related Sites/Structures:	This release is associated with the 116-N-2 Radioactive Chemical Treatment and Storage Facility, 107-N Spent Fuel Basin Recirculation Facility and the 100-N-60 french drain.		
Process Description:	The 1314-N Liquid Waste Loadout Station was a 9 meter (30 ft) by 18 meter (60 ft) single story, metal-frame building supported on a reinforced concrete slab foundation. It began to operate in 1972. The facility was a transfer station consisting of numerous valves, pumps, underground and overhead piping and couplings, and underground tanks. It was located approximately 100 meters (300 ft) from the Columbia River. This facility was used to loadout radioactive liquid waste from the 116-N-2 and 107-N facilities into railroad tank cars for shipment to the 200 Areas for processing and disposal. The loadout facility contained a tank car wash station with a sump to collect the wash water. The water drained into a 3,780 liters (1,000 gal) overflow tank. During the filling operation, excess liquid waste was designed to overflow through a closed piping system from the tank car to the overflow tank, which initiated pump shutdown. A 756 liters (200 gal) catch tank was installed to hold liquids that exceeded the capacity of the car wash sump.		
Waste Type:	Water		
Waste Description:	The release consisted of 289 liters (75 gallons) of spent decontamination solution containing 0.011 curies.		
Closure Info:	Interim (3/28/2013): The 1314-N building was demolished in 2006. 100-N-60 and UPR-100-N-		

26 were located within the building footprint. UPR-100-N-13 was located near the 1314-N building, but outside the building footprint.

Remedial action for 100-N-60, UPR-100-N-13 and UPR-100-N-26 was performed between September 21 and November 14, 2011. Approximately 2,459.0 bank cubic meters (BCM) (3,216.3 bank cubic yards [BCY]) of contaminated soil and debris were removed from the 100-N-60 group of waste sites excavation and direct loaded for disposal at the Environmental Restoration Disposal Facility (ERDF). Excavation continued until all debris and contamination associated with the waste site had been removed. No anomalous material was discovered during remediation activities.

The stained soil location was evaluated for TPH and PAH with a focused sample (FS-2), but the sample results were used to support a greater effort to identify the extent of the TPH and PAH contamination in the 100-N Area and were not included in the evaluation of the 100-N-60, UPR-100-N-13, UPR-100-N-26 group of waste sites.

Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Code:	UPR-100-N-14	Classification:	Accepted
Names:	UPR-100-N-14; 119-N Drain System Leak; UN-100-N-14	Reclassification	Interim Closed Out (7/2/2013)
Type:	Unplanned Release	Start Date:	8/5/1974
Status:	Inactive	End Date:	
Description:	The site has been remediated and Interim Closed Out. The waste site is the soil near the 119-N Sample Building that was affected during a release of radioactively contaminated water.		
Location:	This site is on the north and east sides of the 116-N Air Stack, and approximately 100 meters (330 feet) north of the 105-N Reactor Building.		
Release Description:	While maintenance personnel were working on the 119-N drain system, to correct loss of coolant flow in a condensate collection sampler, backflow from the drain occurred. Effluent water was discharged to the ground near the building. This release occurred on August 5, 1974 and is documented on Unusual Occurrence Report number 74-24.		
Waste Type:	Process Effluent		
Waste Description:	The release consisted of effluent water containing 0.0008 curies of beta/gamma activity.		
Closure Info:	Interim (7/2/2013): Remedial action at the 100-N-87, 100-N-102:1, UPR-100-N-14, and UPR-100-N-9 waste sites was performed during January and February 2011. Remediation involved removal of the foundations of the 116-N stack, the 119-N and 119-NA structures, and the underlying soil. Excavation continued until the french drain, associated piping, and contaminated soil and debris were removed. This excavation exceeded the depth that would be required to remove the 100-N-102:1, UPR-100-N-9, and UPR-100-N-14 waste sites. According to drawing H-1-46389, the depth of the 100-N-102:1 subsite, and therefore the unplanned release waste sites UPR-100-N-9 and UPR-100-N-14, was at 0.76 meters (2.5 ft) bgs. The final excavation depth was approximately 8.5 meters (28 ft) bgs. Because the excavation and removal of the 116-N stack foundation was previously performed by the D4 Project, the exact volume of material removed is unknown.		

The debris removed included soil, concrete, piping, and other debris associated with the 116-N, 119-N, and 119-NA structures and french drain. All material from these waste sites was

disposed at the Environmental Restoration Disposal Facility (ERDF). No anomalous material was encountered during the excavation.

In March 2012, the D4 Project constructed a ramp across the 100-N-87, 100-N-102:1, UPR-100-N-14, and UPR-100-N-9 excavation to provide access and to support remediation activities at 1303-N (118-N-1) waste site. The ramp material was excavated on September 28, 2012, and also disposed of at ERDF. A walk around the site boundary confirmed that all fill material used to build the ramp had been removed. After the excavation of the ramp material, a gamma survey was performed on October 3, 2012, within the 100-N-87, 100-N-102:1, UPR-100-N-14, and UPR-100-N-9 excavation. The gamma survey results indicated readings above background at two locations. Additional remediation was performed to address areas where the GPERS survey results indicated elevated radiological results. Follow up surveys on October 17, 2012 and October 19, 2012 indicated no elevated readings above background.

Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Code:	UPR-100-N-17	Classification:	Accepted
Names:	UPR-100-N-17; 166-N Diesel Oil Supply Line Leak; UN-100-N-17	Reclassification	None
Type:	Unplanned Release	Start Date:	8/1/1966
Status:	Inactive	End Date:	8/1/1966
Description:	The site is an unplanned release of diesel oil that occurred at the 166-N Tank Farm. Number 2 and number 6 diesel oil was introduced into the soil over time. In August 1966, approximately 302,833 kiloliters (80,000 gallons) of diesel oil was released from a transfer valve.		
Location:	The 166-N Tank Farm is located between the 116-N Air Stack and the 116-N-2 Facility (Golf Ball).		
Release Description:	External corrosion of a 10.2 centimeter (4 inch) diesel oil supply line, between the oil storage tank and the west dike, caused the line to leak and release diesel oil to the soil in August 1966. The oil drained through the soil to groundwater, where it migrated toward the Columbia River.		
Related Sites/Structures:	100-N-106, 100-N-107		
Waste Type:	Oil		
Waste Description:	The leak consisted of 80,000 gallons of diesel oil.		

Code:	UPR-100-N-18	Classification:	Accepted
Names:	UPR-100-N-18; 166-N Four-Inch Diesel Oil Supply Line to 184-N Leak and Affected French Drain; UN-100-N-18	Reclassification	Interim Closed Out (8/21/2013)
Type:	Unplanned Release	Start Date:	8/1/1973
Status:	Inactive	End Date:	8/1/1973
Description:	The waste site has been remediated and Interim Closed Out. It was the area where diesel oil leaked into the soil in 1973 (per PNL-6456) and affected a french drain.		
Location:	The release occurred between the 166-N Tank Farm and the 184-N Diesel Oil Day Tank.		

Release Description: External corrosion caused leakage in the 10.2 centimeter (4-inch) diesel oil supply line in August 1973.

Related Sites/ Structures: Contamination below 4.6 meters (15 feet) is considered to be part of waste site UPR-100-N-17.

Waste Type: Oil

Waste Description: The leak consisted of diesel oil.

Closure Info: Interim (8/21/2013): Remediation of the UPR-100-N-18, UPR-100-N-20 and UPR-100-N-24 waste sites was combined in a single excavation. Excavation of the Unplanned Release waste sites was performed between June 27, 2011, and March 26, 2013, resulting in a combined excavation approximately 4.6 meters (15 ft) deep. Approximately 12,062 bank cubic meters (15,777 bank cubic yards) of contaminated soil and debris was removed and disposed to ERDF.

The materials removed and disposed to ERDF included those that had been staged at the ex-situ bioremediation Spoil Pile Area (SPA). During removal of materials from the SPA area it was discovered that debris from the previously demolished 1723-N Warehouse was located in the subsurface. The 1723-N debris included asphaltic materials related to a parking lot at that location. The analysis of samples collected after the removal of materials from the ex-situ SPA would have been problematic due to the presence of the 1723-N related asphalt. Therefore an agreement was reached with EPA and DOE to close the ex-situ SPA based on a visual inspection of the area, verifying the UPR-100-N-18/20/24 materials had all been removed. The SPA area is therefore closed.

The UPR-N-18/20/24 waste sites excavation removed the contaminated soil to a depth of 4.6 meters (15 ft) below ground surface. Potentially contaminated soils remaining below 4.6 meters (15 ft) are considered part of the UPR-100-N-17 waste site and will be evaluated separately. A portion of the UPR-100-N-18/20/24 waste site on the northern side of the excavation remains in place to provide protection for the in situ bioremediation wells associated with the UPR-100-N-17 waste site. This area is referred to as the "well island" and will be addressed separately.

Code: UPR-100-N-19 **Classification:** Accepted

Names: UPR-100-N-19; 184-N Day Tank Fuel Oil Spill; UN-100-N-19; UN-116-N-19 **Reclassification** Interim Closed Out (5/31/2013)

Type: Unplanned Release **Start Date:** 4/1/1984

Status: Inactive **End Date:**

Description: The waste site has been remediated and Interim Closed Out. It was oil contaminated soil. 100-N-103:1 French Drains 6 was located in this area and was addressed with UPR-100-N-19.

Location: The release occurred at the 184-N Fuel Oil Day Tank.

Release Description: The day tank was overfilled, and fuel oil spilled onto the ground in April 1984.

Related Sites/ Structures: These releases are also associated with UPR-100-N-42.

Waste Type: Oil

Waste Description: The release consisted of No. 6 fuel oil.

Closure Info: Interim (5/31/2013): Remediation of the UPR-100-N-19, UPR-100-N-21, UPR-100-N-22, UPR-100-N-23, and UPR-100-N-43 waste sites was performed between June and December 2011, resulting in a combined excavation approximately 5 meters (16.4 ft) deep. Approximately 4,577 bank cubic meters (5,986 bank cubic yards) of contaminated soil and debris was removed and disposed at the Environmental Restoration Disposal Facility (ERDF). French drain #6 formerly associated with the 100-N-103:1 subsite was removed during the remediation of the UPR-100-N-19, UPR-100-N-21, UPR-100-N-22, UPR-100-N-23, and UPR-100-N-43 waste sites and disposed at ERDF. French drain #6 was administratively removed from the 100-N-103:1 subsite and included as part of the UPR-100-N-19 waste site. The unplanned release sites are collectively referred to as the UPR-100-N-19 waste site grouping. The excavation removed the contaminated soil to a depth of 5 meters (16.4 ft) below ground surface. Potentially contaminated soil remains below 5 meters (16.4 ft) and is considered part of the UPR-100-N-42 waste site. This will be evaluated separately and is excluded from the UPR-100-N-19 scope.

Additional remediation was conducted following initial verification sampling because elevated total petroleum hydrocarbons (TPH) were detected above the RAG in part of the site. Well 199-N-16 was decommissioned and removed as part of the additional soil remediation.

Code: UPR-100-N-20	Classification: Accepted
Names: UPR-100-N-20; 166-N Two-Inch Diesel Oil Return Line Leak; UN-100-N-20; UN-116-N-20	Reclassification: Interim Closed Out (8/21/2013)
Type: Unplanned Release	Start Date: 6/1/1985
Status: Inactive	End Date: 6/1/1985

Description: This waste site has been remediated and Interim Closed Out. It was approximately 757 liters of diesel oil that drained to the soil. In 1985, the contaminated soil was removed and properly disposed (per WHC-SD-EN-TI-251).

Location: The release site was located near Tank 1 in the 166-N Tank Farm.

Release Description: External corrosion caused the 5-centimeter (2-inch) diesel oil return line to leak in June 1985.

Related Sites/Structures: Contamination below 4.6 meters (15 feet) is considered to be part of waste site UPR-100-N-17.

Waste Type: Oil

Waste Description: The release consisted of Number 2 diesel oil.

Closure Info: Interim (8/21/2013): Remediation of the UPR-100-N-18, UPR-100-N-20 and UPR-100-N-24 waste sites was combined in a single excavation. Excavation of the Unplanned Release waste sites was performed between June 27, 2011, and March 26, 2013, resulting in a combined excavation approximately 4.6 meters (15 ft) deep. Approximately 12,062 bank cubic meters (15,777 bank cubic yards) of contaminated soil and debris was removed and disposed to ERDF.

The materials removed and disposed to ERDF included those that had been staged at the ex-situ bioremediation Spoil Pile Area (SPA). During removal of materials from the SPA area it was discovered that debris from the previously demolished 1723-N Warehouse was located in the subsurface. The 1723-N debris included asphaltic materials related to a parking lot at that location. The analysis of samples collected after the removal of materials from the ex-situ SPA would have been problematic due to the presence of the 1723-N related asphalt. Therefore an agreement was reached with EPA and DOE to close the ex-situ SPA based on a visual inspection of the area, verifying the UPR-100-N-18/20/24 materials had all been removed. The

SPA area is therefore closed.

The UPR-N-18/20/24 waste sites excavation removed the contaminated soil to a depth of 4.6 meters (15 ft) below ground surface. Potentially contaminated soils remaining below 4.6 meters (15 ft) are considered part of the UPR-100-N-17 waste site and will be evaluated separately. A portion of the UPR-100-N-18/20/24 waste site on the northern side of the excavation remains in place to provide protection for the in situ bioremediation wells associated with the UPR-100-N-17 waste site. This area is referred to as the "well island" and will be addressed separately.

Code:	UPR-100-N-21	Classification:	Accepted
Names:	UPR-100-N-21; 184-N Diesel Oil Day Tank Overflow; UN-100-N-21; UN-116-N-21	Reclassification	Interim Closed Out (5/31/2013)
Type:	Unplanned Release	Start Date:	4/25/1986
Status:	Inactive	End Date:	4/25/1986
Description:	The waste site has been remediated and Interim Closed Out. The Day Tanks have been removed. The tank foundations were located inside a chained area marked 184-ND.		
Location:	The site was located at the 184-N Diesel Oil Day Tank.		
Release Description:	Failure of the tank-level annunciator caused overfilling of the day tank during an oil transfer on April 25, 1986.		
Waste Type:	Oil		
Waste Description:	The release consisted of Number 2 diesel oil.		
Closure Info:	Interim (5/31/2013): Remediation of the UPR-100-N-19, UPR-100-N-21, UPR-100-N-22, UPR-100-N-23, and UPR-100-N-43 waste sites was performed between June and December 2011, resulting in a combined excavation approximately 5 meters (16.4 ft) deep. Approximately 4,577 bank cubic meters (5,986 bank cubic yards) of contaminated soil and debris was removed and disposed at the Environmental Restoration Disposal Facility (ERDF). French drain #6 formerly associated with the 100-N-103:1 subsite was removed during the remediation of the UPR-100-N-19, UPR-100-N-21, UPR-100-N-22, UPR-100-N-23, and UPR-100-N-43 waste sites and disposed at ERDF. French drain #6 was administratively removed from the 100-N-103:1 subsite and included as part of the UPR-100-N-19 waste site. The unplanned release sites are collectively referred to as the UPR-100-N-19 waste site grouping. The excavation removed the contaminated soil to a depth of 5 meters (16.4 ft) below ground surface. Potentially contaminated soil remains below 5 meters (16.4 ft) and is considered part of the UPR-100-N-42 waste site. This will be evaluated separately and is excluded from the UPR-100-N-19 scope.		

Additional remediation was conducted following initial verification sampling because elevated total petroleum hydrocarbons (TPH) were detected above the RAG in part of the site. Well 199-N-16 was decommissioned and removed as part of the additional soil remediation.

Code:	UPR-100-N-22	Classification:	Accepted
Names:	UPR-100-N-22; 184-N Diesel Oil Supply Line Leak No. 1; UN-100-N-22; UN-116-N-22	Reclassification	Interim Closed Out (5/31/2013)
Type:	Unplanned Release	Start Date:	1/1/1986
Status:	Inactive	End Date:	1/1/1986

Description:	The waste site has been remediated and Interim Closed Out. Approximately 3,785 liters of diesel oil was released to the soil in 1986 (per WCH-SD-EN-TI-251).
Location:	The site was located just outside the 184-N Power House.
Release Description:	External corrosion caused the diesel oil supply line to leak. The release occurred on June 23, 1986.
Waste Type:	Oil
Waste Description:	The release consisted of Number 2 diesel oil.
Closure Info:	Interim (5/31/2013): Remediation of the UPR-100-N-19, UPR-100-N-21, UPR-100-N-22, UPR-100-N-23, and UPR-100-N-43 waste sites was performed between June and December 2011, resulting in a combined excavation approximately 5 meters (16.4 ft) deep. Approximately 4,577 bank cubic meters (5,986 bank cubic yards) of contaminated soil and debris was removed and disposed at the Environmental Restoration Disposal Facility (ERDF). French drain #6 formerly associated with the 100-N-103:1 subsite was removed during the remediation of the UPR-100-N-19, UPR-100-N-21, UPR-100-N-22, UPR-100-N-23, and UPR-100-N-43 waste sites and disposed at ERDF. French drain #6 was administratively removed from the 100-N-103:1 subsite and included as part of the UPR-100-N-19 waste site. The unplanned release sites are collectively referred to as the UPR-100-N-19 waste site grouping. The excavation removed the contaminated soil to a depth of 5 meters (16.4 ft) below ground surface. Potentially contaminated soil remains below 5 meters (16.4 ft) and is considered part of the UPR-100-N-42 waste site. This will be evaluated separately and is excluded from the UPR-100-N-19 scope.
	Additional remediation was conducted following initial verification sampling because elevated total petroleum hydrocarbons (TPH) were detected above the RAG in part of the site. Well 199-N-16 was decommissioned and removed as part of the additional soil remediation.

Code:	UPR-100-N-23	Classification:	Accepted
Names:	UPR-100-N-23; 184-N Diesel Oil Supply Line Leak No. 2; UN-100-N-23; UN-116-N-23	Reclassification	Interim Closed Out (5/31/2013)
Type:	Unplanned Release	Start Date:	1/1/1987
Status:	Inactive	End Date:	1/1/1987
Description:	The waste site has been remediated and Interim Closed Out. Approximately 757 liters of diesel oil released to the soil in 1987 (per WHC-SD-EN-TI-251).		
Location:	The site was located near the Diesel Oil Day Tank for the 184-N Power House.		
Release Description:	External corrosion of the piping system was the cause of the leak on January 10, 1987. The leak was detected through inventory discrepancy.		
Waste Type:	Oil		
Waste Description:	The release consisted of Number 2 diesel oil.		
Closure Info:	Interim (5/31/2013): Remediation of the UPR-100-N-19, UPR-100-N-21, UPR-100-N-22, UPR-100-N-23, and UPR-100-N-43 waste sites was performed between June and December 2011, resulting in a combined excavation approximately 5 meters (16.4 ft) deep. Approximately 4,577 bank cubic meters (5,986 bank cubic yards) of contaminated soil and debris was removed and disposed at the Environmental Restoration Disposal Facility (ERDF). French drain #6 formerly associated with the 100-N-103:1 subsite was removed during the remediation of the UPR-100-N-19, UPR-100-N-21, UPR-100-N-22, UPR-100-N-23, and UPR-100-N-43 waste sites and		

disposed at ERDF. French drain #6 was administratively removed from the 100-N-103:1 subsite and included as part of the UPR-100-N-19 waste site. The unplanned release sites are collectively referred to as the UPR-100-N-19 waste site grouping. The excavation removed the contaminated soil to a depth of 5 meters (16.4 ft) below ground surface. Potentially contaminated soil remains below 5 meters (16.4 ft) and is considered part of the UPR-100-N-42 waste site. This will be evaluated separately and is excluded from the UPR-100-N-19 scope.

Additional remediation was conducted following initial verification sampling because elevated total petroleum hydrocarbons (TPH) were detected above the RAG in part of the site. Well 199-N-16 was decommissioned and removed as part of the additional soil remediation.

Code:	UPR-100-N-24	Classification:	Accepted
Names:	UPR-100-N-24; 166-N Fuel Oil Supply Line Leak; UN-100-N-24; UN-116-N-24	Reclassification	Interim Closed Out (8/21/2013)
Type:	Unplanned Release	Start Date:	2/1/1987
Status:	Inactive	End Date:	2/1/1987
Description:	The waste site has been remediated and Interim Closed Out. It was in an area where an unknown amount of fuel oil was released to the soil due to corrosion of the fuel supply line (per WHC-SD-EN-TI-251).		
Location:	The site was located near the 166-N Tank Farm, on the west side of the No. 6 fuel oil tank.		
Release Description:	The leak in the 4 inch diameter external supply line was caused by external corrosion caused from a heat trace line. Leakage occurred during routine oil transfer, and waste oil was periodically removed. The release occurred on February 1, 1987.		
Related Sites/ Structures:	Contamination below 4.6 meters (15 feet) is considered to be part of waste site UPR-100-N-17.		
Process Description:	The leak occurred during routine oil transfer.		
Waste Type:	Oil		
Waste Description:	An unknown amount of Number 6 fuel oil.		
Closure Info:	Interim (8/21/2013): Remediation of the UPR-100-N-18, UPR-100-N-20 and UPR-100-N-24 waste sites was combined in a single excavation. Excavation of the Unplanned Release waste sites was performed between June 27, 2011, and March 26, 2013, resulting in a combined excavation approximately 4.6 meters (15 ft) deep. Approximately 12,062 bank cubic meters (15,777 bank cubic yards) of contaminated soil and debris was removed and disposed to ERDF.		

The materials removed and disposed to ERDF included those that had been staged at the ex-situ bioremediation Spoil Pile Area (SPA). During removal of materials from the SPA area it was discovered that debris from the previously demolished 1723-N Warehouse was located in the subsurface. The 1723-N debris included asphaltic materials related to a parking lot at that location. The analysis of samples collected after the removal of materials from the ex-situ SPA would have been problematic due to the presence of the 1723-N related asphalt. Therefore an agreement was reached with EPA and DOE to close the ex-situ SPA based on a visual inspection of the area, verifying the UPR-100-N-18/20/24 materials had all been removed. The SPA area is therefore closed.

The UPR-N-18/20/24 waste sites excavation removed the contaminated soil to a depth of 4.6

meters (15 ft) below ground surface. Potentially contaminated soils remaining below 4.6 meters (15 ft) are considered part of the UPR-100-N-17 waste site and will be evaluated separately. A portion of the UPR-100-N-18/20/24 waste site on the northern side of the excavation remains in place to provide protection for the in situ bioremediation wells associated with the UPR-100-N-17 waste site. This area is referred to as the "well island" and will be addressed separately.

Code:	UPR-100-N-25	Classification:	Accepted
Names:	UPR-100-N-25; UN-100-N-25; Uncontrolled Venting of 1310-N Tank	Reclassification	Interim Closed Out (5/7/2013)
Type:	Unplanned Release	Start Date:	
Status:	Inactive	End Date:	
Description:	The waste site has been remediated and Interim Closed Out. There was no visual evidence of this release.		
Location:	The site was located adjacent to the 1310-N Chemical Waste Tank, 366 meters (1,200 feet) northeast of the 105-N Building.		
Release Description:	On May 15, 1975, the annual chemical decontamination of the N Reactor primary piping was initiated. During this process, radioactive material is flushed from the primary system to the 1301-N storage tank. An operator was stationed at an open manhole (on top of the tank) to confirm that water was entering the tank. Upon observing water flow, the manhole cover was supposed to be replaced to prevent the release of unfiltered air from the tank. As the operator was beginning to replace the manhole cover, a forceful spray of water came out of the manhole. The surge lasted approximately one minute. An estimated 378 to 1900 liters (100 to 500 gallons) of contaminated water was released to the ground inside the posted Radiation Zone. Smearable contamination up to 20,000 counts per minute was found.		
Related Sites/ Structures:	The release is associated with the 1310-N tank (116-N-2).		
Waste Type:	Chemicals		
Waste Description:	The release consisted of primary loop water and decontamination solution containing phosphoric acid and diethylthiourea. Radiological surveys found a maximum of 20,000 counts per minute after the release.		
Closure Info:	Interim (5/7/2013): Remedial action of the 116-N-2 (Golf Ball) waste site was performed between March 1, 2011 and April 26, 2012. Equipment decontamination was conducted within the southeast corner of the waste site excavation, and that area was remediated May 7 and 8, 2012. The maximum depth of the excavation was 13 meters (42.7 ft) bgs and resulted in the removal of approximately 11,144 bank cubic meters (BCM) (14,576 bank cubic yards [BCY]) of soil and debris. The debris consisted of rock, sand, and piping material. The contaminated soil and debris were directly loaded out for disposal at the Environmental Restoration Disposal Facility (ERDF). Also removed with the 116-N-2 excavation were the UPR-100-N-5 and UPR-100-N-25 waste sites, as well as portions of the 100-N-84 and 100-N-63 pipelines. A section of the 100-N-63:2 pipeline remained on a side slope in the northern part of the excavation until it was remediated between March 22, and 25, 2013. No anomalous material was found during remediation. No in-process samples were collected for the 116-N-2 grouping of waste sites.		
	Clean padding material (soil and gravel) had been previously placed on the ground surface south of the excavation to cover radiological contamination that resulted from the previous D4 activities to remove the golf ball and silo structures. The padding material and approximately 2 meters (6.5 ft) of soil below the padding was scraped and removed for disposal at ERDF.		

Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Code: UPR-100-N-26 **Classification:** Accepted
Names: UPR-100-N-26; Backflow of Radioactive Waste in 1314-N Facility; UN-100-N-26 **Reclassification:** Interim Closed Out (3/28/2013)
Type: Unplanned Release **Start Date:** 1/1/1978
Status: Inactive **End Date:** 1/1/1978

Description: The Unplanned Release has been remediated and Interim Closed Out. The release approximately 3,785 liters of reactor decontamination solution (phosphoric acid and diethylthiourea) that was released to the valve pit with a dirt floor. Most of the solution was pumped back into a tank car. The remaining solution was absorbed and sent to the 200 Area for disposal.

Location: The release occurred in the 1314-N Liquid Waste Loadout Station, in the northeast portion of 100-N Area.

Release Description: Reactor decontamination solution backflowed while being pumped into a tank car, contaminating the dirt floor of the valve pit at the 1314-N Radioactive Liquid Waste Load-Out Facility on December 7, 1978.

Related Sites/ Structures: The Unplanned Release is associated with the 100-N-60 French Drain.

Process Description: The 1314-N Liquid Waste Loadout Station was a 9 meter (30 ft) by 18 meter (60 ft) single story, metal-frame building supported on a reinforced concrete slab foundation. It began to operate in 1972. The facility was a transfer station consisting of numerous valves, pumps, underground and overhead piping and couplings, and underground tanks. It was located approximately 100 meters (300 ft) from the Columbia River. This facility was used to loadout radioactive liquid waste from the 116-N-2 and 107-N facilities into railroad tank cars for shipment to the 200 Areas for processing and disposal. The loadout facility contained a tank car wash station with a sump to collect the wash water. The water drained into a 3,780 liters (1,000 gal) overflow tank. During the filling operation, excess liquid waste was designed to overflow through a closed piping system from the tank car to the overflow tank, which initiated pump shutdown. A 756 liters (200 gal) catch tank was installed to hold liquids that exceeded the capacity of the car wash sump.

Waste Type: Chemicals

Waste Description: The release consisted of reactor decontamination solution containing phosphoric acid and diethylthiourea.

Closure Info: Interim (3/28/2013): The 1314-N building was demolished in 2006. 100-N-60 and UPR-100-N-26 were located within the building footprint. UPR-100-N-13 was located near the 1314-N building, but outside the building footprint.

Remedial action for 100-N-60, UPR-100-N-13 and UPR-100-N-26 was performed between September 21 and November 14, 2011. Approximately 2,459.0 bank cubic meters (BCM) (3,216.3 bank cubic yards [BCY]) of contaminated soil and debris were removed from the 100-N-60 group of waste sites excavation and direct loaded for disposal at the Environmental Restoration Disposal Facility (ERDF). Excavation continued until all debris and contamination associated with the waste site had been removed. No anomalous material was discovered during remediation activities.

The stained soil location was evaluated for TPH and PAH with a focused sample (FS-2), but the sample results were used to support a greater effort to identify the extent of the TPH and PAH contamination in the 100-N Area and were not included in the evaluation of the 100-N-60, UPR-100-N-13, UPR-100-N-26 group of waste sites.

Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Code: UPR-100-N-29	Classification: Accepted
Names: UPR-100-N-29; 1304-N Dump Tank; Emergency Dump Tank Bypass Line Leak; UN-100-N-29	Reclassification: Interim Closed Out (3/20/2013)
Type: Unplanned Release	Start Date: 4/23/1974
Status: Inactive	End Date: 4/23/1974

Description: The Unplanned Release has been remediated and Interim Closed Out. The site was approximately 378 liters (100 gallons) of primary reactor coolant water that was released to the soil in 1974. The contaminated soil was removed and sent to the 200 Area burial ground for disposal. The excavation was then backfilled with clean fill.

Location: The release occurred on the east side of the 1304-N Emergency Dump Tank.

Release Description: A leaking check valve caused a release of primary coolant water on April 23, 1974. An estimated 378 L (100 gal) of contaminated primary coolant water was released from a leaking check valve. An area approximately 10.8 square meters (120 sq ft) was contaminated by the release. The contaminated soil was removed and shipped to a 200 Area burial ground for disposal. Following soil disposal, the site was covered with clean fill material.

Waste Type: Water

Waste Description: The leak consisted of primary coolant water containing radioactive fission and activation products, mostly manganese-56 and sodium-24.

Closure Info: Interim (2/20/2013): The above ground 1304 Emergency Dump Tank and associated piping were removed in 2004.

Remedial action at the 100-N-57, UPR-100-N-1, UPR-100-N-2, UPR-100-N-29, UPR-100-N-30, and UPR-100-N-32 waste sites was performed between February 21 and May 31, 2011. Excavation continued until all debris and contamination associated with the waste sites had been removed. Contaminated soil, concrete, pipeline segments and debris removed during excavation were staged within the South Staging Pile Area 1 (SSP Area 1) prior to shipment to the ERDF. Approximately 1,848 bank cubic meters (2,417 bank cubic yards) of contaminated soil and debris were removed from the site and disposed at the ERDF. No stained soil or anomalous material was found during the remediation activities.

The debris removed from the waste sites consisted of miscellaneous noncombustible debris and soil. Portions of the 100-N-63:2, 100-N-64, 100-N-84:2, 100-N-84:3, 100-N-84:4, and 100-N-84:5 pipeline waste sites were also removed during 100-N-57 group of waste sites remediation activities. The remaining portions of these pipeline waste sites will be remediated and separate closure documents prepared at a later date.

Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Code: UPR-100-N-30	Classification: Accepted
---------------------------	---------------------------------

Names: UPR-100-N-30; 1304-N Dump Tank; Emergency Dump Tank Overflow; UN-100-N-30 **Reclassification** Interim Closed Out (3/20/2013)

Type: Unplanned Release **Start Date:** 7/22/1974

Status: Inactive **End Date:** 7/22/1974

Description: The Unplanned Release has been remediated and Interim Closed Out. The site includes the ground surrounding the 1304-N Emergency Dump Tank. There is no visual evidence of this release.

Location: The release occurred adjacent to the 1304-N Emergency Dump Tank.

Release Description: During a drawdown test, the 1304-N Emergency Dump Tank overflowed, spilling approximately 9,463 liters (2500 gallons) of primary coolant water. No water reached the river. The release affected an area measuring approximately 232 square meters (2500 sq. ft.). The contamination levels were 500 counts per minute. The release occurred on July 22, 1974.

Related Sites/Structures: The site is associated with the 1304-N tank (100-N-57).

Waste Type: Water

Waste Description: The release consisted of primary coolant water containing fission and activation products contaminating the area to a maximum of 500 counts/minute.

Closure Info: Interim (2/20/2013): The above ground 1304 Emergency Dump Tank and associated piping were removed in 2004.

Remedial action at the 100-N-57, UPR-100-N-1, UPR-100-N-2, UPR-100-N-29, UPR-100-N-30, and UPR-100-N-32 waste sites was performed between February 21 and May 31, 2011. Excavation continued until all debris and contamination associated with the waste sites had been removed. Contaminated soil, concrete, pipeline segments and debris removed during excavation were staged within the South Staging Pile Area 1 (SSP Area 1) prior to shipment to the ERDF. Approximately 1,848 bank cubic meters (2,417 bank cubic yards) of contaminated soil and debris were removed from the site and disposed at the ERDF. No stained soil or anomalous material was found during the remediation activities.

The debris removed from the waste sites consisted of miscellaneous noncombustible debris and soil. Portions of the 100-N-63:2, 100-N-64, 100-N-84:2, 100-N-84:3, 100-N-84:4, and 100-N-84:5 pipelines waste sites were also removed during 100-N-57 group of waste sites remediation activities. The remaining portions of these pipeline waste sites will be remediated and separate closure documents prepared at a later date.

Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Code: UPR-100-N-31 **Classification:** Accepted

Names: UPR-100-N-31; Radioactive Effluent Water Spill Near 116-N-1 (1301-N); UN-100-N-31 **Reclassification** Interim Closed Out (8/31/2013)

Type: Unplanned Release **Start Date:** 7/22/1974

Status: Inactive **End Date:**

Description: The waste site has been remediated and Interim Closed Out. It was a release of radioactively contaminated water to the soil on the west side of the 116-N-1 crib.

Location: The release occurred on the west side of the berm just west of the 1301-N (116-N-1) Liquid

Waste Disposal Facility.

- Release Description:** While sample lines were being installed in a 15-centimeter (6-inch) steel casing through the berm on the west side of the 1301-N Crib, the water level in the crib was raised 38 to 46 centimeters (15 to 18 inches) as a result of an Emergency Dump Tank drawdown test. Due to the increased water level, approximately 3785 liters (1000 gallons) of effluent was released, contaminating 186 square meters (2,025 square feet) of soil.
- Related Sites/ Structures:** The 116-N-1 Crib and Trench was the originator of the liquid. Also related was 100-N-63, UPR-100-N-4, UPR-100-N-8 and the 100-N Reactor (1314-N, 116-N-1 and 116-N-3) TSD Underground Pipelines.
- Waste Type:** Water
- Waste Description:** The release consisted of radioactive effluent containing fission and activation products. The gross beta/gamma concentration of the spilled water was 700 disintegrations/minute/milliliter.
- Closure Info:** Interim (8/13/2013): The 1322N, 1322NA, 1322NB, and 1322NC above-ground buildings and slabs in the vicinity of the unplanned releases were removed during the 100-N deactivation, decommission, decontamination, and demolition (D4) activities. The removal included an excavation that measured approximately 3.7 meters (12 ft) deep. The UPR-100-N-4 and UPR-100-N-8 waste sites are associated with the 1322-N/NA Buildings. The UPR-100-N-31 waste site is associated with the 116-N-1 (1301-N) Crib and Trench. Because the locations of the UPR-100-N-4, UPR-100-N-8, and UPR-100-N-31 unplanned release sites were in close proximity to each other and no information was available to delineate the boundary of each release, the three sites were combined into one excavation. The excavation for remediation of the combined unplanned release sites was immediately adjacent to the former 116-N-1 (1301-N) remediation site. Further remediation of the UPR-100-N-4, UPR-100-N-8, and UPR-100-N-31 waste site soils was performed between December 13, 2011 and March 19, 2012, resulting in a combined excavation approximately 7 meters (23 ft) deep.

Approximately 5,683 bank cubic meters (BCM) (7,433 bank cubic yards [BCY]) of additional contaminated soil, rocks, and concrete was removed for disposal at the Environmental Restoration Disposal Facility (ERDF). Additional contaminated soil was removed from areas SZ-6, SZ-8, and SZ-9 between January 30, 2013 and February 4, 2013, resulting in an additional 189 BCM (247 BCY) of contaminated soil removed for disposal at ERDF. Areas of stained soil remained in the deep zone (more than 4.6 meters [15 ft] below ground surface [bgs]) following the completion of the remedial action activities. All material was direct loaded from the excavation for disposal at ERDF. No overburden piles or anomalies were associated with the remediation.

During remediation of the unplanned release sites, increasing radiological activity was observed with depth approaching soils underlying the former 116-N-1 crib. Deep zone sample results from the UPR-100-N-4, UPR-100-N-8, and UPR-100-N-31 remediation are also consistent with residual contamination in the 116-N-1 deep zone. This suggests that the contamination encountered was residual from 116-N-1 left in place in the deep zone, and that deep zone remediation of the UPR-100-N-4, UPR-100-N-8, and UPR-100-N-31 waste sites is considered complete. The liquid waste effluents associated with the UPR-100-N-31 and 116-N-1 waste sites are the same.

Code: UPR-100-N-32	Classification: Accepted
Names: UPR-100-N-32; 1304-N Dump Tank; Emergency Dump Tank Bypass Line Leak; UN-100-N-32	Reclassification: Interim Closed Out (3/20/2013)
Type: Unplanned Release	Start Date: 9/16/1974

Status: Inactive**End Date:** 9/16/1974**Description:** The Unplanned Release has been remediated and Interim Closed Out. Approximately 3,785 liters of effluent water was released to the soil in 1974. Most of the contaminated soil was removed in 1974. The remaining contamination was covered with clean fill.**Location:** The release occurred on the southeast side of the 1304-N Emergency Dump Tank.**Release Description:** A leaking check valve in the Emergency Dump Tank bypass line released radioactive effluent water to the ground. An estimated 3,785 liters (1,000 gal) of contaminated effluent being released. A majority of the contaminated soil was removed and disposed at a 200 Area burial ground. The remaining soil that had been contaminated by the release was left in place and covered with clean fill material. The effluent water was analyzed at the release location to provide an estimate of the activity of the release. It was estimated that the radioactive material had an activity of less than 10 micro curies. A mud sample reading was 20,000 counts/minute. The release occurred on September 16, 1974.**Waste Type:** Water**Waste Description:** The release consisted of radioactive effluent water containing fission and activation products. A mud sample read 20,000 counts/minute. The water was analyzed for gross activity. It was estimated that less than 10 millicuries of radioactive material remained on the ground.**Closure Info:** Interim (2/20/2013): The above ground 1304 Emergency Dump Tank and associated piping were removed in 2004.

Remedial action at the 100-N-57, UPR-100-N-1, UPR-100-N-2, UPR-100-N-29, UPR-100-N-30, and UPR-100-N-32 waste sites was performed between February 21 and May 31, 2011. Excavation continued until all debris and contamination associated with the waste sites had been removed. Contaminated soil, concrete, pipeline segments and debris removed during excavation were staged within the South Staging Pile Area 1 (SSP Area 1) prior to shipment to the ERDF. Approximately 1,848 bank cubic meters (2,417 bank cubic yards) of contaminated soil and debris were removed from the site and disposed at the ERDF. No stained soil or anomalous material was found during the remediation activities.

The debris removed from the waste sites consisted of miscellaneous noncombustible debris and soil. Portions of the 100-N-63:2, 100-N-64, 100-N-84:2, 100-N-84:3, 100-N-84:4, and 100-N-84:5 pipeline waste sites were also removed during 100-N-57 group of waste sites remediation activities. The remaining portions of these pipeline waste sites will be remediated and separate closure documents prepared at a later date.

Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Code: UPR-100-N-35**Classification:** Accepted**Names:** UPR-100-N-35; 100-N Fuel Basin Drainage System Leak; 105-N Fuel Storage Basin Drainage System Leak; UN-100-N-35; UN-116-N-35**Reclassification:** Consolidated (4/10/2013)**Type:** Unplanned Release**Start Date:** 2/28/1986**Status:** Inactive**End Date:** 11/1/1986**Description:** This Unplanned Release has been consolidated with 100-N-66 (105N/109N Complex). The release occurred in a crack in the south concrete wall of the lift station pipe tunnel at the 105-N Reactor Building. The pipe tunnel and lift station will remain in place when the 105-N reactor

building is placed in the Safe Storage Enclosure (SSE).

Location: This leak occurred on the south side of the pipe tunnel (north side of the Fuel Storage Basin). It affected the western end of the 105-N Reactor core.

Release Description: Routine sampling of the 100-N Area groundwater wells detected slightly elevated levels of iodine-131. Drawdown tests on the basin determined that the leak was not from the basin. Further tests and investigations determined the intermittent leak to be coming from a sub-basin drain line approximately 8.5 meters (28 feet) below the ground. The leak, estimated to be less than 11 liters (3 gallons) per minute, occurred only during feed and bleed (addition of water) of the 100-N Fuel Basin.

Waste Type: Water

Waste Description: The release consisted of radioactively contaminated water containing an estimated 1.6 curies manganese-5, 0.4 curies cobalt-60, 0.3 curies niobium-95, 0.1 curies iodine-131, 0.4 curies cesium-137 and 0.3 curies cerium-144.

This Site Was Consolidated With:

Code: 100-N-66

Names: 100-N-66; 105-N/109-N Reactor Building Complex

Code: UPR-100-N-36

Classification: Accepted

Names: UPR-100-N-36; 184N; 184N Annex; Diesel Generator Area Unplanned Release

Reclassification: Interim Closed Out (2/26/2013)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The waste site has been remediated and Interim Closed Out. It was a diesel release in a graveled area previously affected by a history of spills.

Location: The site is located between Buildings 153N and 184N.

Release Description: Numerous spills of diesel fuel and motor oil used for normal operation and maintenance occurred over a 13 year period. During this period, the site was used as a diesel air compressor staging area.

Related Sites/Structures: French drain 100-N-55 was located within the remediation footprint of UPR-100-N-36.A separate closure document was prepared to address the 100-N-55 french drain.

Waste Type: Oil

Waste Description: Evidence of spills include stained gravel and a strong smell of petroleum products in the soil beneath (noted during an excavation).

Closure Info: Interim (2/26/2013): Remedial action at the UPR-100-N-36 waste site was performed between May 23, 2011, and November 15, 2011, resulting in an excavation approximately 4.5 meters (14.8 ft) below ground surface. Approximately 8,400 bank cubic meters (BCM) (10,987 bank cubic yards [BCY]) of contaminated soil and debris were removed for disposal at the ERDF. Initially, the soil and debris were placed in a staging pile area to be evaluated for bioremediation. However, based on sampling results and the debris present (concrete, piping, and chunks of hard black material), the material was disposed. The staging pile area is currently in use by multiple waste sites. Therefore, the staging pile area will not be addressed in this closure document but rather will be closed with the UPR-100-N-18 waste site. All soil and debris from remediation of UPR-100-N-36 was disposed at the ERDF. Therefore, no overburden pile is associated with the site. No anomalous materials were encountered during the remediation.

Code: UPR-100-N-37	Classification: Accepted
Names: UPR-100-N-37; HGP Transformer Yard Oil Stained Gravel; SWMU #1	Reclassification: Interim Closed Out (6/15/2004)
Type: Unplanned Release	Start Date: 1/1/1966
Status: Inactive	End Date: 1/1/1986

Description: The site has been remediated and Interim Closed Out. The nine transformers were arranged in a row along the side of the 185-N Building. Each transformer was approximately 6.1 meters (20 ft) tall and 2.4 meters (8 ft) square and was situated on a 3 meter (10 ft) square concrete pad.

Location: The transformer yard was located northwest of the 185-N Building, west of the 100-N operation area.

Process Description: The former HGP was located in the 185-N Building and consisted of two 430-megawatt turbine generators that operated from 1966 until 1986 using steam from the adjacent 100-N production reactor for generation of electricity. Mineral oil containing polychlorinated biphenyls (PCB's) and solvents was used routinely during equipment maintenance. Washington Public Power Supply System personnel indicated that dielectric fluid was used in the transformer that did not contain PCB's.

Waste Type: Oil

Waste Description: Dielectric fluid consisting of mineral oil has seeped onto the ground. Washington Public Power Supply System (WPPSS) personnel have verbally stated that polychlorinated biphenyls (PCBs) have never been used in the transformers. However, the RCRA Facility assessment report states that, based on the dates of operation, the presence of PCB's is suspect.

Closure Info: Interim: The Hanford Generating Plant (HGP) solid waste management unit (SWMU) removal actions included in this CVP began in 2001 and were completed in 2004. The majority of the removal action activities were completed in 2003 and 2004. The remediation and report were done by Energy Northwest.

The entire 185-N Building aboveground structure was demolished during the 2003 and 2004 activities. The debris from demolition of the building as well as from demolition of other HGP structures was used as fill for the 185-N Building basement. The debris was placed into the building basement from the bottom (15.2 meters [50 ft] below ground surface) to within 7.6 meters (25 ft) of the ground surface. The remaining void spaces among the debris fill were filled using a cement grout controlled density fill. The remaining below grade portion of the basement was backfilled with clean soil. The reinforced concrete turbine pedestals that extend from the basement floor to approximately the ground surface were left in place. Based on agreement with the Washington State Department of Ecology, the portions of the turbine pedestals at the ground surface were covered with 0.9 meter (3 ft) of soil consistent with requirements for other 100 Area facilities. The Removal Action Workplan (DOE-RL 1999) specified removal of structures to a minimum of 0.3 meter (1 ft) below the surrounding grade and other 100 Area action memorandums generally require that a structure be demolished to a minimum of 0.9 meters (3 ft) below the surrounding grade. However, in the case of the turbine pedestals, because of their mass and the amount of steel reinforcement, demolition was deemed impractical. The 0.9 meters (3 ft) of cover for the pedestals was placed to blend in with, and to gently slope with, the surrounding grade.

The 185-N Building is not a SWMU. However, SWMUs #2, 3, and 4 are located within the building. To provide a complete description of the removal action activities for SWMUs #2, 3, and 4, a summary description of the removal action activities conducted for the 185-N Building is below.

UPR-100-N-37 Transformer Yard (SWMU #1): Eight of the nine transformers located in the transformer yard were removed prior to the Action Memorandum (EPA 1999). The ninth, smaller, operating transformer, was drained of oil and scrapped during the most recent 2003 and 2004 activities. The oil and transformer were disposed of based on historical data indicating that the transformer oil did not contain PCBs. During removal action activities conducted in 2001, minor areas of soil contaminated with oil were excavated from around each transformer pad and properly disposed. During the more recent 2003 and 2004 activities, the concrete pads were demolished, excavated and the concrete rubble used as fill for the demolished 185-N Building basement.

100-N-51 Oil Storage Area (SWMU #2): All stored oil and waste containers were previously removed from the oil storage area and properly disposed of or appropriately used. Miscellaneous concrete stained areas including the sump were cleaned. Cleaning of concrete surfaces included the use of concrete scabbling and water and detergents during the 2001 activities. The 100-N-51 Oil Storage Area (SWMU #2) was located at the bottom of the 185-N Building basement. It has been covered and filled with building debris, a cement grout controlled density fill, and borrow soil.

185-N Building Drains and Sumps (SWMU #3): The 185-N Building basement drains and sumps were emptied and cleaned during the 2001 removal action activities. Cleaning activities involved removal and proper disposal of sludges and liquids. Following removal of the sludges and liquids, the sump concrete and metal surfaces were hand cleaned, pressure washed, and scabbled as needed. During the recent 2003 and 2004 activities three of the sumps contained water. The water was characterized, removed from the sump, and properly disposed. All of the miscellaneous drains were filled with a cement grout controlled density fill during the 2003 and 2004 activities. The sumps were filled with borrow soil and capped with a minimum of 15 cm (6 in.) of cement grout during the 2003 and 2004 activities. Also, the sumps and drains have been covered with building debris fill, cement grout controlled density fill, and borrow soil.

100-N-50 Turbine Oil Filter Unit (SWMU #4): During the 2001 removal action activities, the two steel tank oil filtration units including the internal metal oil filtration screens were drained and cleaned. Residual oil from the units was removed and properly disposed. In addition, the two concrete sumps associated with the filter units were cleaned. Stained concrete was removed from the sumps through chipping and scabbling. These units were located at the bottom of the 185-N Building basement and have been filled and covered with the cement grout controlled density fill.

Code: UPR-100-N-39	Classification: Accepted
Names: UPR-100-N-39; Corridor 22 Suspect Liquid Unplanned Release (Cleaned Up)	Reclassification: Interim Closed Out (9/6/2013)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:
Description: The release site has been remediated and Interim Closed Out. The 100-N-31 waste site was located on the west side of the 105-N/109-N Reactor Buildings and adjacent to the 100-N-32, 100-N-38, 100-N-61 :3, 100-N-64:3, 100-N-68, UPR-100-N-3, UPR-100-N-7, UPR-100-N-10, UPR-100-N-12, and UPR-100-N-39 waste sites. These waste sites are collectively referred to as the waste sites west of the 105-N/109-N Reactor. The remediation of these waste sites resulted in one large excavation with no demarcation of the individual sites, with the exception of the UPR-100-N-39 waste site. The eleven sites were Interim Closed out in a single document.	

UPR-100-N-39 consisted of contaminated soil and concrete from an unplanned release of

	contaminated water outside the Corridor 22 doorway of the 105-N Reactor.
Location:	The release site was located outside the Corridor 22 doorway, on the west side of the 105-N Reactor Building. Corridor 22 doorway was located near the helium low pressure storage tanks and the 105-NE Fission Product Filter Trap.
Release Description:	In 1983 or 1984, several hundred liters of radioactively contaminated water was spilled outside Corridor 22. Scrub water from the Fission Product Filter Trap overflowed and discharged to the ground and concrete. The concrete was painted to fix the contamination and an indeterminate amount of the contaminated soil was removed.
Related Sites/ Structures:	The 105-N Fission Product Filter Trap is associated with the site.
Waste Type:	Water
Waste Description:	Several hundred liters of radioactively contaminated water from the Fission Product Filter Trap overflowed and discharged to the ground.
Closure Info:	Interim (9/6/2013): Eleven waste sites located west of the 105-N/109-N Reactor Building were remediated as a group. The eleven waste sites included 100-N-31, 100-N-32, 100-N-38, 100-N-61:3, 100-N-64:3, 100-N-68, UPR-100-N-3, UPR-100-N-7, UPR-100-N-10, UPR-100-N-12, and UPR-100-N-39. This group of waste sites was referred to as the waste sites west of the 105-N/109-N Reactor. The footprints of the 1909-N Waste Disposal Valve Pit, the 107-N facility and the pipe trench between 105-N and 107-N were also located within the boundary of the group.

The eleven collocated waste sites located west of the 105-N/109-N Reactor Building were remediated, either partially or completely, by the Deactivation, Decontamination, Decommissioning, and Demolition (D4) Project during the demolition and removal of the portions of the 105-N/109-N Buildings, located outside of the safe storage enclosure (SSE).

The Field Remediation (FR) Project resumed remedial action activities west of the 105-N/109-N Reactor in November 2012. Contaminated soil, structural concrete and rebar, and piping were removed from the collocated waste sites west of the 105-N/109-N Reactor and disposed at the Environmental Restoration Disposal Facility (ERDF). The remediation continued through March 2013 to an approximate maximum depth of 9.5 meters (31 ft) below surface grade. No anomalous materials were encountered during remediation. The remediation resulted in one large excavation with no demarcation of the individual sites, with the exception of the UPR-100-N-39 waste site. Some segments of the 100-N-61:3 and 100-N-64:3 pipelines were removed with remedial action at the 100-N-57, (1304-N) Emergency Dump Tank and 116-N-4, (1300-N) Emergency Dump Basin waste sites.

After the remediation, Global Positioning Environmental Radiological Surveyor (GPERS) surveys were performed in March 2013. Some beta and gamma contamination was detected above background. However, the area with the highest detected activity is associated with residual structures and soils for the 105-N/109-N SSE and is considered part of the 100-N-66, 105-N/109-N Reactor Building Complex waste site. A small area with elevated beta and gamma contamination was detected within the waste sites west of the 105-N/109-N Reactor boundary. Additional soil was removed from this area and disposed at the ERDF. An environmental radiological survey of the area using hand-held instruments verified that the contaminated soils have been removed.

The 1909-N Waste Disposal Valve Pit was removed during general facility demolition in this area by the D4 Project. Due to the proximity and general configuration of demolition and remediation activities on the west side of the reactor, closure of the facility footprint was deferred until nearby waste site remediation by the FR Project occurred. The residual

contaminated soil that remained beneath the location of the former 1909-N facility was then removed.

The 107-N basin structure was completely removed by the D4 Project. However, closure of the basin footprint was deferred to the UPR-100-N-12 waste site. Additional soil was removed from the footprint during general waste site remediation in the area. Surveys found no elevated residual radiological activity.

Several segments of the 100-N-84 pipeline subsites were partially located within the remediation boundary. All of the segments of the 100-N-84:2, 100-N-84:4, 100-N-84:5, and 100-N-84:6 pipeline subsites that were within the excavation boundary were removed and disposed at the ERDF. Reclassification of the total 100-N-84:2, 100-N-84:4, 100-N-84:5 and 100-N-84:6 pipeline subsites will be addressed in separate closure documents.

Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Code:	UPR-100-N-42	Classification:	Accepted
Names:	UPR-100-N-42; 184-N; 184-N Day Tank Area Liquid Unplanned Release; Day Tank Diesel Oil Spill	Reclassification	Interim Closed Out (1/29/2014)
Type:	Unplanned Release	Start Date:	10/9/1987
Status:	Inactive	End Date:	10/9/1987

Description: The unplanned release site has been remediated and Interim Closed Out. Several documented and undocumented spills of fuel oil and diesel oil occurred within the Day Tank area over the life of the facility. The UPR-100-N-42 waste site addresses potential petroleum contamination associated with these releases that may be present in the deep vadose zone, at a depth below 4.6 meters (15 ft). The 184-N Day Tank Area was surrounded by a 1.5-meter (4.8-foot) concrete wall that is 25 meters (85 feet) long by 12.8 meters (42 feet) wide, has a sand floor, and contained two 130,000 liters (35,000 gallons) Number 6 fuel oil tanks and one 30,000 liter (8,000 gallon) diesel oil tank.

Location: The 184-N Day Tank area was located north of the 184-N Power House.

Release Description: On October 9, 1987, an unknown amount of diesel oil was spilled.

Related Sites/Structures: Associated releases include UPR-100-N-19, UPR-100-N-21, UPR-100-N-22, UPR-100-N-23 and UPR-100-N-43. These spill occurred from 1984 through 1987.

Waste Type: Oil

Waste Description: The site received diesel oil.

Closure Info: Interim (1/29/2014): The UPR-100-N-42 waste site addresses potential petroleum contamination that may be present in the deep vadose zone, at a depth below 4.6 meters (15 ft). Associated shallow releases included UPR-100-N-19, UPR-100-N-21, UPR-100-N-22, UPR-100-N-23 and UPR-100-N-43. Verification sampling of the associated shallow zone releases was conducted on June 14, 2012 and documented in the Remaining Sites Verification Package for the UPR-100-N-19, UPR-100-N-21, UPR-100-N-22, UPR-100-N-23, and UPR-100-N-43 waste sites (RSVP-2013-025 through 029). The results indicated that remediation of the petroleum-contaminated soil in the shallow zone was complete with the exception of some residual petroleum contamination exceeding soil remedial action goals (RAGs) located on the

north excavation sidewall near the 199-N-16 groundwater monitoring well. Remediation of the associated shallow zone petroleum waste sites, that overlie the UPR-100-N-42 deep zone waste site (UPR-100-N-19, UPR-100-N-21, UPR-100-N-22, UPR-100-N-23, and UPR-100-N-43), was performed from June 7 through October 10, 2011. Additional remediation on the north excavation sidewall was performed in January 2013, resulting in a combined excavation approximately 5 meters (16.4 ft) deep.

Well 199-N-16 (total depth 80 ft) was decommissioned on December 18, 2012. Groundwater samples were collected on November 6, 2012, prior to decommissioning the well. Petroleum contamination was not detected in the groundwater samples.

Verification sampling to support closure of the UPR-100-N-42 waste site was performed in three phases. Phase I sampling was performed on September 19, 2012, and consisted of sampling the floor of the excavation remaining after remediation of overlying shallow zone petroleum remediated waste sites to support evaluation of the lateral distribution of potential residual petroleum contamination at the UPR-100-N-42 waste site. The results of Phase I verification sampling were then used to establish the location of a test pit for Phase II verification sampling near sample locations showing elevated concentrations of petroleum contamination. Phase II sampling was performed on February 13, 2013, to evaluate the vertical distribution of potential petroleum contamination below the floor of the excavation. The test pit was excavated to a final depth of approximately 5 meters (16.4 ft) below the excavation floor. Phase III verification sampling was performed from September 25 through October 1, 2013, and consisted of installing two vertical push probes to provide additional information concerning potential petroleum contamination below the excavation floor. The results of the verification sampling indicate the UPR-100-N-42 waste site meets remedial action objectives and remedial action goals (RAGs) established by the 100-N Area ROD (EPA 1999) and that in-situ bioremediation of the deep zone (greater than 4.6 meters [15 ft]) was not required.

The selected action involved (1) excavating the shallow zone petroleum unplanned release sites waste sites (UPR-100-N-19, UPR-100-N-21, UPR-100-N-22, UPR-100-N-23, and UPR-100-N-43), (2) disposing of contaminated excavation materials at ERDF, (3) demonstrating through verification sampling that cleanup goals have been achieved, and (4) proposing the site for reclassification as Interim Closed Out.

Code:	UPR-100-N-43	Classification:	Accepted
Names:	UPR-100-N-43; 166-N / 184-N Pipelines Liquid Unplanned Release 2 (4/26/89; Cleaned Up)	Reclassification	Interim Closed Out (5/31/2013)
Type:	Unplanned Release	Start Date:	4/26/1989
Status:	Inactive	End Date:	4/26/1989
Description:	The waste site has been remediated and Interim Closed Out. The release site occurred in 1989 at the oil supply pipe from the 166-N to 184-N Buildings. The diesel oil day tank was connected to the 166-N Storage tanks by a 10 centimeter (4 inch) underground supply line.		
Location:	The leak occurred at three locations along the pipeline, but the three locations were not provided in the historical documentation. The WIDS site is mapped as one data point, about 49 meters (160 feet) southeast of the 105-N Reactor Building, between the 184-N Building and the 184-N Day Tank Area.		
Release Description:	A diesel oil leak occurred at three locations along the pipeline from 166-N to 184-N Buildings at three different flange joints. The exact location of these flange joints is not given in the referenced descriptions. The release was reported on April 26, 1989.		
Waste Type:	Oil		

Waste The spill was diesel oil from the diesel oil supply line to the 184-N Day Tank.

Description:

Closure Info: Interim (5/31/2013): Remediation of the UPR-100-N-19, UPR-100-N-21, UPR-100-N-22, UPR-100-N-23, and UPR-100-N-43 waste sites was performed between June and December 2011, resulting in a combined excavation approximately 5 meters (16.4 ft) deep. Approximately 4,577 bank cubic meters (5,986 bank cubic yards) of contaminated soil and debris was removed and disposed at the Environmental Restoration Disposal Facility (ERDF). French drain #6 formerly associated with the 100-N-103:1 subsite was removed during the remediation of the UPR-100-N-19, UPR-100-N-21, UPR-100-N-22, UPR-100-N-23, and UPR-100-N-43 waste sites and disposed at ERDF. French drain #6 was administratively removed from the 100-N-103:1 subsite and included as part of the UPR-100-N-19 waste site. The unplanned release sites are collectively referred to as the UPR-100-N-19 waste site grouping. The excavation removed the contaminated soil to a depth of 5 meters (16.4 ft) below ground surface. Potentially contaminated soil remains below 5 meters (16.4 ft) and is considered part of the UPR-100-N-42 waste site. This will be evaluated separately and is excluded from the UPR-100-N-19 scope.

Additional remediation was conducted following initial verification sampling because elevated total petroleum hydrocarbons (TPH) were detected above the RAG in part of the site. Well 199-N-16 was decommissioned and removed as part of the additional soil remediation.

200-BC-1

Code: 216-B-14 **Classification:** Accepted
Names: 216-B-14; 216-BC-1 Crib **Reclassification:** None
Type: Crib **Start Date:** 1/1/1956
Status: Inactive **End Date:** 1/1/1956

Description: The 216-B-14, 216-B-15, 216-B-16, 216-B-17, 216-B-18 and 216-B-19 cribs and the 216-BC-201 siphon tank were surface stabilized as a single area. All the surface structures (risers and vents) have been removed. The area has been covered with clean soil and posted as an Underground Radioactive Material area. There are concrete AC 540 markers to identify the site.

Location: The crib is located south of the 200 East Area (across Route 4S) in the BC Crib Area. The BC Cribs and Trenches are located inside the BC Controlled Area.

Related Sites/ Structures: The site is associated with the 216-BC-201 Siphon Tank, 200-E-222-PL, and UPR-200-E-83.

Process Description: The 216-B-14, 216-B-15, 216-B-16, 216-B-17, 216-B-18 and 216-B-19 cribs received tri-butyl phosphate waste from the U-Plant Uranium Recovery operations and scavenged tank farm waste via underground pipelines. From 1952 to 1958, waste containing uranium and fission products, produced by the bismuth phosphate separations process, were removed from underground storage tanks and reprocessed at 221-U Plant to recover the uranium from the waste. After the uranium was removed, the cesium and strontium content of the effluent was precipitated by adding ferrocyanide. The addition of ferrocyanide to the waste was called "scavenging". The supernate liquor was released to the ground in the BC Cribs and Trenches. The unit is a dispersion structure, 3.0 by 3.0 by 0.9 meters (10 by 10 by 3 feet) high, made of wood, cinder block, and steel, over a 1.5-meter (5-foot) bed of 7.6-centimeter (3-inch) gravel, with a 35.6-centimeter (14-inch) inlet pipe located 1.8 meters (6 feet) below grade. The bottom dimensions of the excavation are 12.2 by 12.2 meters (40 by 40 feet) and 3.96 meters (13 feet) deep. The side slope is 2:1.

Waste Type: Process Effluent

Waste Description: The site received the scavenged tributyl phosphate (TBP) supernatant waste from 221-U Building during uranium recovery operations. The waste is high in salt and is neutral to basic. The waste contained inorganic compounds such as ferrocyanide, nitrate and phosphate.

Code: 216-B-15 **Classification:** Accepted
Names: 216-B-15; 216-BC-2 Crib **Reclassification:** None
Type: Crib **Start Date:** 1/1/1956
Status: Inactive **End Date:** 1/1/1957

Description: The 216-B-14, 216-B-15, 216-B-16, 216-B-17, 216-B-18 and 216-B-19 cribs were surface stabilized as a single area. All the surface structures (risers and vents) have been removed. The area has been covered with clean soil and posted as an Underground Radioactive Material area. There are concrete AC 540 markers to identify the site.

Location: The crib is located south of the 200 East Area (across Route 4S) in the BC Crib Area. The BC Cribs and Trenches are located inside the BC Controlled Area.

Related Sites/ Structures: The site is associated with the 216-BC-201 Siphon Tank, 200-E-222-PL and UPR-200-E-83.

Process Description: The 216-B-14, 216-B-15, 216-B-16, 216-B-17, 216-B-18 and 216-B-19 cribs received tri-butyl phosphate waste from the U-Plant Uranium Recovery operations and scavenged tank farm waste via underground pipelines. From 1952 to 1958, waste containing uranium and fission products, produced by the bismuth phosphate separations process, were removed from underground storage tanks and reprocessed at 221-U Plant to recover the uranium from the waste. After the uranium was removed, the cesium and strontium content of the effluent was precipitated by adding ferrocyanide. The addition of ferrocyanide to the waste was called "scavenging". The supernate liquor was released to the ground in the BC Cribs and Trenches. The unit is a dispersion structure, 3.0 by 3.0 by 0.9 meters (10 by 10 by 3 feet) high, made of wood, cinder block, and steel, over a 1.5-meter (5-foot) bed of 7.6-centimeter (3-inch) gravel, with a 35.6-centimeter (14-inch) inlet pipe located 1.8 meters (6 feet) below grade. The bottom dimensions of the excavation are 12.2 by 12.2 meters (40 by 40 feet) and 3.96 meters (13 feet) deep. The side slope is 2:1.

Waste Type: Process Effluent

Waste Description: The site received scavenged tributyl phosphate (TBP) supernatant waste from 221-U Building during uranium recovery operations. The waste is high in salt and is neutral to basic. The waste contained inorganic compounds such as ferrocyanide, nitrate and phosphate.

Code: 216-B-16	Classification: Accepted
Names: 216-B-16; 216-BC-3 Crib	Reclassification: None
Type: Crib	Start Date: 1/1/1956
Status: Inactive	End Date: 1/1/1956

Description: The 216-B-14, 216-B-15, 216-B-16, 216-B-17, 216-B-18 and 216-B-19 cribs were surface stabilized as a single area. All the surface structures (risers and vents) have been removed. The area has been covered with clean soil and posted as an Underground Radioactive Material area. There are concrete AC 540 markers to identify the site.

Location: The crib is located south of the 200 East Area (across Route 4S) in the BC Crib Area. The BC Cribs and Trenches are located inside the BC Controlled Area.

Related Sites/ Structures: The site is associated with the 216-BC-201 Siphon Tank, 200-E-222-PL and UPR-200-E-83.

Process Description: The 216-B-14, 216-B-15, 216-B-16, 216-B-17, 216-B-18 and 216-B-19 cribs received tri-butyl phosphate waste from the U-Plant Uranium Recovery operations and scavenged tank farm waste via underground pipelines. From 1952 to 1958, waste containing uranium and fission products, produced by the bismuth phosphate separations process, were removed from underground storage tanks and reprocessed at 221-U Plant to recover the uranium from the waste. After the uranium was removed, the cesium and strontium content of the effluent was precipitated by adding ferrocyanide. The addition of ferrocyanide to the waste was called "scavenging". The supernate liquor was released to the ground in the BC Cribs and Trenches. The unit is a dispersion structure, 3.0 by 3.0 by 0.9 meters (10 by 10 by 3 feet) high, made of wood, cinder block, and steel, over a 1.5-meter (5-foot) bed of 7.6-centimeter (3-inch) gravel, with a 35.6-centimeter (14-inch) inlet pipe located 1.8 meters (6 feet) below grade. The bottom dimensions of the excavation are 12.2 by 12.2 meters (40 by 40 feet) and 3.96 meters (13 feet) deep. The side slope is 2:1.

Waste Type: Process Effluent

Waste Description: The site received the scavenged tributyl phosphate (TBP) supernatant waste from 221-U Building. The waste is high in salt and is neutral to basic. The waste contained inorganic compounds such as ferrocyanide, nitrate and phosphate.

Code: 216-B-17	Classification: Accepted
Names: 216-B-17; 216-BC-4 Crib	Reclassification: None
Type: Crib	Start Date: 1/1/1956
Status: Inactive	End Date: 1/1/1956

Description: The 216-B-14, 216-B-15, 216-B-16, 216-B-17, 216-B-18 and 216-B-19 cribs were surface stabilized as a single area. All the surface structures (risers and vents) have been removed. The area has been covered with clean soil and posted as an Underground Radioactive Material area. There are concrete AC 540 markers to identify the site.

Location: The crib is located south of the 200 East Area (across Route 4S) in the BC Crib Area. The BC Cribs and Trenches are located inside the BC Controlled Area.

Related Sites/ Structures: The site is associated with the 216-BC-201 Siphon Tank, 200-E-222-PL and UPR-200-E-83.

Process Description: The 216-B-14, 216-B-15, 216-B-16, 216-B-17, 216-B-18 and 216-B-19 cribs received tri-butyl phosphate waste from the U-Plant Uranium Recovery operations and scavenged tank farm waste via underground pipelines. From 1952 to 1958, waste containing uranium and fission products, produced by the bismuth phosphate separations process, were removed from underground storage tanks and reprocessed at 221-U Plant to recover the uranium from the waste. After the uranium was removed, the cesium and strontium content of the effluent was precipitated by adding ferrocyanide. The addition of ferrocyanide to the waste was called "scavenging". The supernate liquor was released to the ground in the BC Cribs and Trenches. The unit is a dispersion structure, 3.0 by 3.0 by 0.9 meters (10 by 10 by 3 feet) high, made of wood, cinder block, and steel, over a 1.5-meter (5-foot) bed of 7.6-centimeter (3-inch) gravel, with a 35.6-centimeter (14-inch) inlet pipe located 1.8 meters (6 feet) below grade. The bottom dimensions of the excavation are 12.2 by 12.2 meters (40 by 40 feet) and 3.96 meters (13 feet) deep. The side slope is 2:1.

Waste Type: Process Effluent

Waste Description: The site received the scavenged tributyl phosphate (TBP) supernatant waste from the 221-U Building. The waste is high in salt and is neutral to basic. The waste contained inorganic compounds such as ferrocyanide, nitrate and phosphate. Curren (1972) states that the 216-B-17 crib received tank farm first cycle scavenged waste in January 1956.

Code: 216-B-18	Classification: Accepted
Names: 216-B-18; 216-BC-5 Crib	Reclassification: None
Type: Crib	Start Date: 1/1/1956
Status: Inactive	End Date: 1/1/1956

Description: The 216-B-14, 216-B-15, 216-B-16, 216-B-17, 216-B-18 and 216-B-19 cribs were surface stabilized as a single area. All the surface structures (risers and vents) have been removed. The area has been covered with clean soil and posted as an Underground Radioactive Material area. There are concrete AC 540 markers to identify the site.

Location: The crib is located south of the 200 East Area (across Route 4S) in the BC Crib Area. The BC Cribs and Trenches are located inside the BC Controlled Area.

Related Sites/ Structures: The site is associated with the 216-BC-201 Siphon Tank, 200-E-222-PL and UPR-200-E-83.

Process Description: The 216-B-14, 216-B-15, 216-B-16, 216-B-17, 216-B-18 and 216-B-19 cribs received tri-butyl phosphate waste from the U-Plant Uranium Recovery operations and scavenged tank farm waste via underground pipelines. From 1952 to 1958, waste containing uranium and fission products, produced by the bismuth phosphate separations process, were removed from underground storage tanks and reprocessed at 221-U Plant to recover the uranium from the waste. After the uranium was removed, the cesium and strontium content of the effluent was precipitated by adding ferrocyanide. The addition of ferrocyanide to the waste was called "scavenging". The supernate liquor was released to the ground in the BC Cribs and Trenches. The unit is a dispersion structure, 3.0 by 3.0 by 0.9 meters (10 by 10 by 3 feet) high, made of wood, cinder block, and steel, over a 1.5-meter (5-foot) bed of 7.6-centimeter (3-inch) gravel, with a 35.6-centimeter (14-inch) inlet pipe located 1.8 meters (6 feet) below grade. The bottom dimensions of the excavation are 12.2 by 12.2 meters (40 by 40 feet) and 3.96 meters (13 feet) deep. The side slope is 2:1.

Waste Type: Process Effluent

Waste Description: The site received the scavenged tributyl phosphate (TBP) supernatant from 221-U Building. The waste is high in salt and is neutral to basic. The waste contained inorganic compounds such as ferrocyanide, nitrate and phosphate.

Code: 216-B-19 **Classification:** Accepted

Names: 216-B-19; 216-BC-6 Crib **Reclassification:** None

Type: Crib **Start Date:** 1/1/1957

Status: Inactive **End Date:** 1/1/1957

Description: The 216-B-14, 216-B-15, 216-B-16, 216-B-17, 216-B-18 and 216-B-19 cribs were surface stabilized as a single area. All the surface structures (risers and vents) have been removed. The area has been covered with clean soil and posted as an Underground Radioactive Material area. There are concrete AC 540 markers to identify the site.

Location: The crib is located south of the 200 East Area (across Route 4S) in the BC Crib Area. The BC Cribs and Trenches are located inside the BC Controlled Area.

Related Sites/ Structures: The site is associated with the 216-BC-201 Siphon Tank and UPR-200-E-83.

Process Description: The 216-B-14, 216-B-15, 216-B-16, 216-B-17, 216-B-18 and 216-B-19 cribs received tri-butyl phosphate waste from the U-Plant Uranium Recovery operations and scavenged tank farm waste via underground pipelines. From 1952 to 1958, waste containing uranium and fission products, produced by the bismuth phosphate separations process, were removed from underground storage tanks and reprocessed at 221-U Plant to recover the uranium from the waste. After the uranium was removed, the cesium and strontium content of the effluent was precipitated by adding ferrocyanide. The addition of ferrocyanide to the waste was called "scavenging". The supernate liquor was released to the ground in the BC Cribs and Trenches via underground pipelines and above ground pipe extensions.

The unit is a dispersion structure, 3.0 by 3.0 by 0.9 meters (10 by 10 by 3 feet) high, made of wood, cinder block, and steel, over a 1.5-meter (5-foot) bed of 7.6-centimeter (3-inch) gravel, with a 35.6-centimeter (14-inch) inlet pipe located 1.8 meters (6 feet) below grade. The bottom dimensions of the excavation are 12.2 by 12.2 meters (40 by 40 feet) and 3.96 meters (13 feet) deep. The side slope is 2:1.

Waste Type: Process Effluent

Waste Description: The site received the scavenged tributyl phosphate (TBP) supernatant waste from the 221-U Building. The waste is high in salt and is neutral to basic. The waste contained inorganic compounds such as ferrocyanide, nitrate and phosphate. Curren (1972) states that the 216-B-19 crib received both U Plant and Tank Farm scavenged waste.

Code: 216-B-20 **Classification:** Accepted

Names: 216-B-20; 216-B-20 Trench; 216-BC-7 Trench **Reclassification:** None

Type: Trench **Start Date:** 1/1/1956

Status: Inactive **End Date:** 1/1/1956

Description: The BC trenches were surface stabilized as a unit. The backfilled trenches have been covered with clean soil and posted as Underground Radioactive Material. Concrete AC 540 markers outline the area where the trenches are located, but do not identify specific trench locations.

Location: The trench is located south of the 200 East Area in the BC Crib Area (across Route 4S). The BC Cribs and Trenches are located inside the BC Controlled Area.

Release Description: See UPR-200-E-83

Related Sites/ Structures: The trench is associated with the U Plant uranium recovery process and UPR-200-E-83.

Process Description: From 1952 to 1958, waste containing uranium and fission products, produced by the bismuth phosphate separations process, were removed from underground storage tanks and reprocessed at 221-U to recover the uranium from the waste. After the uranium was removed, the cesium and strontium content of the effluent was reduced through precipitation by adding ferrocyanide. The supernate liquor was released to the ground in the BC Cribs and Trenches. A total of 16 unlined trenches, 216-B-20 through 216-B-34 and 216-B-52 received waste from the Uranium Recovery Process. Trenches 216-B-53A, 216-B-53B, 216-B-54 and 216-B-58 received laboratory and PRTR waste from 300 Area.

The trench was divided into 19-meter (62.5-foot) sections by 0.6-meter (2-foot) high earthen dams. The side slope is 1:1.5. The depth was designed to be 3 meters (10 feet) but is often documented as 1.8 meters (6 feet).

Waste Type: Process Effluent

Waste Description: The site received scavenged waste from uranium recovery (tributyl phosphate [TBP] solvent extraction from the 221-U Building). The waste is high in salt and is neutral to basic. It included inorganic compounds such as ferrocyanide, nitrate and phosphate.

Code: 216-B-21 **Classification:** Accepted

Names: 216-B-21; 216-B-21 Trench; 216-BC-8 Trench **Reclassification:** None

Type: Trench **Start Date:** 1/1/1956

Status: Inactive **End Date:** 1/1/1956

Description: The BC trenches were surface stabilized as a unit. The backfilled trenches have been covered with clean soil and posted as Underground Radioactive Material. Concrete AC 540 markers outline the area where the trenches are located, but do not identify specific trench locations.

Location: The unit is located on the west side of the 216-B-20 Trench, south of the 200 East Area (across Route 4S) in the BC Crib Area. The BC Cribs and Trenches are located inside the BC

Controlled Area.

Release See UPR-200-E-83

Description:

Related Sites/ The trench is associated with 221-U and UPR-200-E-83.

Structures:

Process From 1952 to 1958, waste containing uranium and fission products, produced by the bismuth phosphate separations process, were removed from underground storage tanks and reprocessed at 221-U to recover the uranium from the waste. After the uranium was removed, the cesium and strontium content of the effluent was reduced by precipitation. The supernate liquor was released to the ground in the BC Cribs and Trenches. A total of 16 unlined trenches, 216-B-20 through 216-B-34 and 216-B-52 received waste from the Uranium Recovery Process. Trenches 216-B-53A, 216-B-53B, 216-B-54 and 216-B-58 received laboratory and PRTR waste from 300 Area.

Waste Type: Process Effluent

Waste The site received the scavenged tributyl phosphate (TBP) supernatant waste from 221-U
Description: Building. The waste is high in salt and is neutral to basic. The waste includes inorganic compounds such as ferrocyanide, nitrate and phosphate.

Code: 216-B-22

Classification: Accepted

Names: 216-B-22; 216-B-22 Trench; 216-BC-9 Trench

Reclassification None

Type: Trench

Start Date: 1/1/1956

Status: Inactive

End Date: 1/1/1956

Description: The BC trenches were surface stabilized as a unit. The backfilled trenches have been covered with clean soil and posted as Underground Radioactive Material. Concrete AC 540 markers outline the area where the trenches are located, but do not identify specific trench locations. The trench was divided into 19 meters (62.5 foot) sections by 0.6-meter (2 foot) high earth dams. The side slope is 1:1.5. The depth was designed to be 3.7 meters (12 feet), but some documents report approximately 1.8 meters (6 feet).

Location: The unit is located on the west side of the 216-B-21 Trench, south of the 200 East Area (across Route 4S). The BC Cribs and Trenches are located inside the BC Controlled Area.

Release See UPR-200-E-83

Description:

Related Sites/ The trench is related to 221-U and UPR-200-E-83.

Structures:

Process From 1952 to 1958, waste containing uranium and fission products, produced by the bismuth phosphate separations process, were removed from underground storage tanks and reprocessed at 221-U to recover the uranium from the waste. After the uranium was removed, the cesium and strontium content of the effluent was reduced by precipitation. The supernate liquor was released to the ground in the BC Cribs and Trenches. A total of 16 unlined trenches, 216-B-20 through 216-B-34 received and 216-B-52 waste from the Uranium Recovery Process. Trenches 216-B-53A, 216-B-53B, 216-B-54 and 216-B-58 received laboratory and PRTR waste from 300 Area.

Waste Type: Process Effluent

Waste The site received the scavenged tributyl phosphate (TBP) supernatant waste from 221-U
Description: Building. The waste is high in salt and is neutral to basic. It contained inorganic compounds

such as ferrocyanide, nitrate and phosphate.

Code: 216-B-23	Classification: Accepted
Names: 216-B-23; 216-B-23 Trench; 216-BC-10 Trench	Reclassification: None
Type: Trench	Start Date: 1/1/1956
Status: Inactive	End Date: 1/1/1956

Description: The BC trenches were surface stabilized as a unit. The backfilled trenches have been covered with clean soil and posted as Underground Radioactive Material. Concrete AC 540 markers outline the area where the trenches are located, but do not identify specific trench locations. The trench is divided into eight 19-meter (62.5-foot) sections by 1.2-meter (4-foot) high earth dams. The unit has a 1:1.5 side slope.

Location: The unit is south of the 200 East Area (across Route 4S). The BC Cribs and Trenches are located inside the BC Controlled Area.

Release Description: See UPR-200-E-83

Related Sites/ Structures: The trench is associated with the U Plant uranium recovery process and UPR-200-E-83.

Process Description: From 1952 to 1958, waste containing uranium and fission products, produced by the bismuth phosphate separations process, were removed from underground storage tanks and reprocessed at 221-U to recover the uranium from the waste. After the uranium was removed, the cesium and strontium content of the effluent was reduced by precipitation. The supernate liquor was released to the ground in the BC Cribs and Trenches. A total of 16 unlined trenches, 216-B-20 through 216-B-34 and 216-B-52 received waste from the Uranium Recovery Process. Trenches 216-B-53A, 216-B-53B, 216-B-54 and 216-B-58 received laboratory and PRTR waste from 300 Area.

Waste Type: Process Effluent

Waste Description: The site received the scavenged tributyl phosphate (TBP) supernatant waste from 221-U Building. The waste is high in salt and is neutral to basic. It contained inorganic compounds such as ferrocyanide, nitrate and phosphate.

Code: 216-B-24	Classification: Accepted
Names: 216-B-24; 216-B-24 Trench; 216-BC-11 Trench	Reclassification: None
Type: Trench	Start Date: 1/1/1956
Status: Inactive	End Date: 1/1/1956

Description: The BC trenches were surface stabilized as a unit. The backfilled trenches have been covered with clean soil and posted as Underground Radioactive Material. Concrete AC 540 markers outline the area where the trenches are located, but do not identify specific trench locations. The trench is divided into eight 19-meter (62.5-foot) sections by 1.2-meter (4-foot) high earthen dams. It has a 1.5:1 side slope.

Location: The unit is directly south of the 216-B-23 Trench, south of the 200 East Area (across Route 4S) in the BC Crib Area. The BC Cribs and Trenches are located inside the BC Controlled Area.

Release Description: See UPR-200-E-83

Related Sites/ Structures: The trench is associated with the U Plant uranium recovery process and UPR-200-E-83.

Process Description: From 1952 to 1958, waste containing uranium and fission products, produced by the bismuth phosphate separations process, were removed from underground storage tanks and reprocessed at 221-U to recover the uranium from the waste. After the uranium was removed, the cesium and strontium content of the effluent was reduced by precipitation. The supernate liquor was released to the ground in the BC Cribs and Trenches. A total of 16 unlined trenches, 216-B-20 through 216-B-34 and 216-B-52 received waste from the Uranium Recovery Process. Trenches 216-B-53A, 216-B-53B, 216-B-54 and 216-B-58 received laboratory and PRTR waste from 300 Area.

Waste Type: Process Effluent

Waste Description: The site received the scavenged tributyl phosphate (TBP) supernatant from 221-U Building. The waste is high in salt and is neutral to basic. It contained inorganic compounds such as ferrocyanide, nitrate and phosphate.

Code: 216-B-25 **Classification:** Accepted

Names: 216-B-25; 216-B-25 Trench; 216-BC-12 Trench **Reclassification:** None

Type: Trench **Start Date:** 1/1/1956

Status: Inactive **End Date:** 1/1/1956

Description: The BC trenches were surface stabilized as a unit. The backfilled trenches have been covered with clean soil and posted as Underground Radioactive Material. Concrete AC 540 markers outline the area where the trenches are located, but do not identify specific trench locations. The trench is divided into eight 19-meter (62.5-foot) sections by 1.2-meter (4-foot) high earthen dams. It has a 1.5:1 side slope.

Location: The site is directly south of the 216-B-24 Trench, south of the 200 East Area (across Route 4S) in the BC Crib Area. The BC Cribs and Trenches are located inside the BC Controlled Area.

Release Description: See UPR-200-E-83

Related Sites/ Structures: The trench is associated with the U Plant uranium recovery process and UPR-200-E-83.

Process Description: From 1952 to 1958, waste containing uranium and fission products, produced by the bismuth phosphate separations process, were removed from underground storage tanks and reprocessed at 221-U to recover the uranium from the waste. After the uranium was removed, the cesium and strontium content of the effluent was reduced by precipitation. The supernate liquor was released to the ground in the BC Cribs and Trenches. A total of 16 unlined trenches, 216-B-20 through 216-B-34 and 216-B-52 received waste from the Uranium Recovery Process. Trenches 216-B-53A, 216-B-53B, 216-B-54 and 216-B-58 received laboratory and PRTR waste from 300 Area.

Waste Type: Process Effluent

Waste Description: The site received the scavenged tributyl phosphate (TBP) supernatant waste from 221-U Building. The waste is high in salt and is neutral to basic. It contained inorganic compounds such as ferrocyanide, nitrate and phosphate.

Code: 216-B-26 **Classification:** Accepted

Names: 216-B-26; 216-B-26 Trench; 216-BC-13 Trench **Reclassification** None

Type: Trench **Start Date:** 1/1/1956

Status: Inactive **End Date:** 1/1/1957

Description: A portion of this trench was excavated in 2008. The BC trenches were surface stabilized as a unit. The backfilled trenches have been covered with clean soil and posted as Underground Radioactive Material. Concrete AC 540 markers outline the area where the trenches are located, but do not identify specific trench locations.

Location: The site is directly south of the 216-B-25 Trench, south of the 200 East Area (across Route 4S) in the BC Crib Area. The BC Cribs and Trenches are located inside the BC Controlled Area.

Release See UPR-200-E-83

Description:

Related Sites/ The trench is associated with the U Plant uranium recovery process and UPR-200-E-83.

Structures:

Process From 1952 to 1958, waste containing uranium and fission products, produced by the bismuth phosphate separations process, were removed from underground storage tanks and reprocessed at 221-U to recover the uranium from the waste. After the uranium was removed, the cesium and strontium content of the effluent was reduced by precipitation. The supernate liquor was released to the ground in the BC Cribs and Trenches. A total of 16 unlined trenches, 216-B-20 through 216-B-34 and 216-B-52 received waste from the Uranium Recovery Process. Trenches 216-B-53A, 216-B-53B, 216-B-54 and 216-B-58 received laboratory and PRTR waste from 300 Area. Although some documentation states the trench is divided into eight 19-meter (62.5-foot) sections by 1.2-meter (4-foot) high earthen dams with a of 1.5:1 side slope, a 1956 photograph shows the trench was divided into only three sections by earth dams.

Waste Type: Process Effluent

Waste The site received the scavenged tributyl phosphate (TBP) supernatant waste from 221-U
Description: Building. The waste is high in salt and is neutral to basic. It contained inorganic compounds such as ferrocyanide, phosphate and nitrate.

Code: 216-B-27 **Classification:** Accepted

Names: 216-B-27; 216-B-27 Trench; 216-BC-14 Trench **Reclassification** None

Type: Trench **Start Date:** 1/1/1957

Status: Inactive **End Date:** 1/1/1957

Description: The BC trenches were surface stabilized as a unit. The backfilled trenches have been covered with clean soil and posted as Underground Radioactive Material. Concrete AC 540 markers outline the area where the trenches are located, but do not identify specific trench locations. The trench is divided into eight 19-meter (62.5-foot) sections, separated by 1.2-meter (4-foot) high earthen dams. It has a 1.5:1 side slope.

Location: The site is directly south of the 216-B-26 Trench, south of the 200 East Area (across Route 4S). The BC Cribs and Trenches are located inside the BC Controlled Area.

Release See UPR-200-E-83

Description:

Related Sites/ The trench is associated with the U Plant uranium recovery process and UPR-200-E-83.

Structures:

Process Description: From 1952 to 1958, waste containing uranium and fission products, produced by the bismuth phosphate separations process, were removed from underground storage tanks and reprocessed at 221-U to recover the uranium from the waste. After the uranium was removed, the cesium and strontium content of the effluent was reduced by precipitation. The supernate liquor was released to the ground in the BC Cribs and Trenches. A total of 16 unlined trenches, 216-B-20 through 216-B-34 and 216-B-52 received waste from the Uranium Recovery Process. Trenches 216-B-53A, 216-B-53B, 216-B-54 and 216-B-58 received laboratory and PRTR waste from 300 Area.

Waste Type: Process Effluent

Waste Description: The site received the scavenged tributyl phosphate (TBP) supernatant waste from 221-U Building. The waste is high in salt and is neutral to basic. It included inorganic compounds such as ferrocyanide, nitrate and phosphate.

Code: 216-B-28	Classification: Accepted
Names: 216-B-28; 216-B-28 Trench; 216-BC-15 Trench	Reclassification: None
Type: Trench	Start Date: 1/1/1957
Status: Inactive	End Date: 1/1/1957

Description: The BC trenches were surface stabilized as a unit. The backfilled trenches have been covered with clean soil and posted as Underground Radioactive Material. Concrete AC 540 markers outline the area where the trenches are located, but do not identify specific trench locations. The trench construction divided it into eight 19-meter (62.5-foot) sections, separated by 1.2-meter (4-foot) high earthen dams. It has a 1.5:1 side slope.

Location: The unit is directly south of the 216-B-27 Trench, south of the 200 East Area (across Route 4S) in the BC Crib Area. The BC Cribs and Trenches are located inside the BC Controlled Area.

Release Description: See UPR-200-E-83

Related Sites/ Structures: This trench is related to UPR-200-E-83.

Process Description: From 1952 to 1958, waste containing uranium and fission products, produced by the bismuth phosphate separations process, were removed from underground storage tanks and reprocessed at 221-U to recover the uranium from the waste. After the uranium was removed, the cesium and strontium content of the effluent was reduced by precipitation. The supernate liquor was released to the ground in the BC Cribs and Trenches. A total of 16 unlined trenches, 216-B-20 through 216-B-34 and 216-B-52 received waste from the Uranium Recovery Process. Trenches 216-B-53A, 216-B-53B, 216-B-54 and 216-B-58 received laboratory and PRTR waste from 300 Area. The following are related to the unit: eight 7.62-centimeter (3-inch) Schedule 40 pipes, approximately 6.7 meters (22 feet) long, placed along the side slope, 19.2 meters (63 feet) apart; eight 7.62-centimeter (3-inch) gate valves for the above pipes, at ground level; wooden cover composed of three 2 by 4s, spaced 3 meters (10 feet) apart, running the length of the unit, with 1 by 6s crossing the width, 1.2 meters (4 feet) apart; 4 by 4 support stakes, 0.76 meters (2 feet 6 inches) long, spaced 2.4 meters (8 feet) apart to secure the wooden cover to the unit.

Waste Type: Process Effluent

Waste Description: The site received the scavenged tributyl phosphate (TBP) supernatant waste from 221-U Building. The waste is high in salt and is neutral to basic. The waste contained inorganic compounds such as ferrocyanide, nitrate and phosphate.

Code: 216-B-29	Classification: Accepted
Names: 216-B-29; 216-BC-16 Trench	Reclassification: None
Type: Trench	Start Date: 1/1/1957
Status: Inactive	End Date: 1/1/1957

Description: The BC trenches were surface stabilized as a unit. The backfilled trenches have been covered with clean soil and posted as Underground Radioactive Material. Concrete AC 540 markers outline the area where the trenches are located, but do not identify specific trench locations. The site is a trench that was used for disposal of medium-activity liquid waste. The trench has been backfilled and the area has been surface stabilized. The trench was a long narrow excavation with a 1:1.75 side slope. It was divided crosswise into two equal sections by an earthen dam. The dam was 1.5 meters (5 feet) high and 1.5 meters (5 feet) wide at the top. A 10.2 centimeter (4 inch) Schedule 40 pipe ran along the top edge of the trench. Four 7.62-centimeter (3-inch) Schedule 40 pipe sections extended laterally from the 10.2-centimeter (4-inch) pipe, down the side slope into the trench. Liquid discharge into the trench was controlled by gate valves located at the top of the lateral lines. A cover, constructed of 1 by 6 and 2 by 4 wood framing and sisalkraft paper, extended the length of the trench. The vertical distance from the cover to the trench bottom was a minimum of 1.5 meters (5 feet).

Location: The trench is located south of the 200 East Area (across Route 4S) in the BC Crib Area. The BC Cribs and Trenches are located inside the BC Controlled Area.

Related Sites/ Structures: The trench is associated with 221-U uranium recovery process and UPR-200-E-83.

Process Description: From 1952 to 1958, waste containing uranium and fission products, produced by the bismuth phosphate separations process, were removed from underground storage tanks and reprocessed at 221-U to recover the uranium from the waste. After the uranium was removed, the cesium and strontium content of the effluent was reduced by precipitation. The supernate liquor was released to the ground in the BC Cribs and Trenches. A total of 16 unlined trenches, 216-B-20 through 216-B-34 and 216-B-52 received waste from the Uranium Recovery Process. Trenches 216-B-53A, 216-B-53B, 216-B-54 and 216-B-58 received laboratory and PRTR waste from 300 Area.

Waste Type: Process Effluent

Waste Description: The site received the scavenged tributyl phosphate (TBP) supernatant waste from the 221-U Building. The waste is high in salt and is neutral to basic. It contained inorganic compounds such as ferrocyanide, nitrate and phosphate.

Code: 216-B-30	Classification: Accepted
Names: 216-B-30; 216-B-30 Trench; 216-BC-17 Trench	Reclassification: None
Type: Trench	Start Date: 1/1/1957
Status: Inactive	End Date: 1/1/1957

Description: The BC trenches were surface stabilized as a unit. The backfilled trenches have been covered with clean soil and posted as Underground Radioactive Material. Concrete AC 540 markers outline the area where the trenches are located, but do not identify specific trench locations. The site is a trench that was used for disposal of medium-activity liquid waste. The trench has been backfilled and the area has been surface stabilized. The trench was a long narrow excavation with a 1:1.75 side slope. It was divided crosswise into two equal sections by an earthen dam. The dam was 1.5 meters (5 feet) high and 1.5 meters (5 feet) wide at the top. A

10.2 centimeter (4 inch) Schedule 40 pipe ran along the top edge of the trench. Four 7.62-centimeter (3-inch) Schedule 40 pipe sections extended laterally from the 10.2-centimeter (4-inch) pipe, down the side slope into the trench. Liquid discharge into the trench was controlled by gate valves located at the top of the lateral lines. A cover, constructed of 1 by 6 and 2 by 4 wood framing and sisalkraft paper, extended the length of the trench. The vertical distance from the cover to the trench bottom was a minimum of 1.5 meters (5 feet).

Location: The unit is directly south of the 216-B-29 Trench, south of the 200 East Area (across Route 4S) in the BC Crib Area. The BC Cribs and Trenches are located inside the BC Controlled Area.

Release See UPR-200-E-83

Description:

Related Sites/ The trench is associated with the U Plant uranium recovery process and UPR-200-E-83.

Structures:

Process From 1952 to 1958, waste containing uranium and fission products, produced by the bismuth phosphate separations process, were removed from underground storage tanks and reprocessed at 221-U to recover the uranium from the waste. After the uranium was removed, the cesium and strontium content of the effluent was reduced by precipitation. The supernate liquor was released to the ground in the BC Cribs and Trenches. A total of 16 unlined trenches, 216-B-20 through 216-B-34 and 216-B-52 received waste from the Uranium Recovery Process. Trenches 216-B-53A, 216-B-53B, 216-B-54 and 216-B-58 received laboratory and PRTR waste from 300 Area.

Waste Type: Process Effluent

Waste The site received the scavenged tributyl phosphate (TBP) supernatant waste from the 221-U Building. The waste is high in salt and is neutral to basic. It contained inorganic compounds such as ferrocyanide, nitrate and phosphate.

Code: 216-B-31	Classification: Accepted
Names: 216-B-31; 216-B-31 Trench; 216-BC-18 Trench	Reclassification None
Type: Trench	Start Date: 1/1/1957
Status: Inactive	End Date: 1/1/1957

Description: The BC trenches were surface stabilized as a unit. The backfilled trenches have been covered with clean soil and posted as Underground Radioactive Material. Concrete AC 540 markers outline the area where the trenches are located, but do not identify specific trench locations. The site is a trench that was used for disposal of medium-activity liquid waste. The trench has been backfilled and the area has been surface stabilized. The trench was a long narrow excavation with a 1:1.75 side slope. It was divided crosswise into two equal sections by an earthen dam. The dam was 1.5 meters (5 feet) high and 1.5 meters (5 feet) wide at the top. A 10.2 centimeter (4 inch) Schedule 40 pipe ran along the top edge of the trench. Four 7.62-centimeter (3-inch) Schedule 40 pipe sections extended laterally from the 10.2-centimeter (4-inch) pipe, down the side slope into the trench. Liquid discharge into the trench was controlled by gate valves located at the top of the lateral lines. A cover, constructed of 1 by 6 and 2 by 4 wood framing and sisalkraft paper, extended the length of the trench. The vertical distance from the cover to the trench bottom was a minimum of 1.5 meters (5 feet).

Location: The unit is directly south of the 216-B-30 Trench, south of the 200 East Area (across Route 4S) in the BC Crib Area. The BC Cribs and Trenches are located inside the BC Controlled Area.

Release See UPR-200-E-83

Description:

Related Sites/ Structures: The trench is associated with the U Plant uranium recovery process and UPR-200-E-83.

Process Description: From 1952 to 1958, waste containing uranium and fission products, produced by the bismuth phosphate separations process, were removed from underground storage tanks and reprocessed at 221-U to recover the uranium from the waste. After the uranium was removed, the cesium and strontium content of the effluent was reduced by precipitation. The supernate liquor was released to the ground in the BC Cribs and Trenches. A total of 16 unlined trenches, 216-B-20 through 216-B-34 and 216-B-52 received waste from the Uranium Recovery Process. Trenches 216-B-53A, 216-B-53B, 216-B-54 and 216-B-58 received laboratory and PRTR waste from 300 Area.

Waste Type: Process Effluent

Waste Description: The site received the scavenged tributyl phosphate (TBP) supernatant waste from the 221-U Building. The waste is high in salt and is neutral to basic. It contained inorganic compounds such as ferrocyanide, nitrate and phosphate.

Code: 216-B-32	Classification: Accepted
Names: 216-B-32; 216-B-32 Trench; 216-BC-19 Trench	Reclassification: None
Type: Trench	Start Date: 1/1/1957
Status: Inactive	End Date: 1/1/1957

Description: The BC trenches were surface stabilized as a unit. The backfilled trenches have been covered with clean soil and posted as Underground Radioactive Material. Concrete AC 540 markers outline the area where the trenches are located, but do not identify specific trench locations. The site is a trench that was used for disposal of medium-activity liquid waste. The trench has been backfilled and the area has been surface stabilized. The trench was a long narrow excavation with a 1:1.75 side slope. It was divided crosswise into two equal sections by an earthen dam. The dam was 1.5 meters (5 feet) high and 1.5 meters (5 feet) wide at the top. A 10.2 centimeter (4 inch) Schedule 40 pipe ran along the top edge of the trench. Four 7.62-centimeter (3-inch) Schedule 40 pipe sections extended laterally from the 10.2-centimeter (4-inch) pipe, down the side slope into the trench. Liquid discharge into the trench was controlled by gate valves located at the top of the lateral lines. A cover, constructed of 1 by 6 and 2 by 4 wood framing and sisalkraft paper, extended the length of the trench. The vertical distance from the cover to the trench bottom was a minimum of 1.5 meters (5 feet).

Location: The unit is directly south of the 216-B-31 Trench, south of the 200 East Area (across Route 4S) in the BC Crib Area. The BC Cribs and Trenches are located inside the BC Controlled Area.

Release Description: See UPR-200-E-83

Related Sites/ Structures: The trench is associated with the U Plant uranium recovery process and UPR-200-E-83.

Process Description: From 1952 to 1958, waste containing uranium and fission products, produced by the bismuth phosphate separations process, were removed from underground storage tanks and reprocessed at 221-U to recover the uranium from the waste. After the uranium was removed, the cesium and strontium content of the effluent was reduced by precipitation. The supernate liquor was released to the ground in the BC Cribs and Trenches. A total of 16 unlined trenches, 216-B-20 through 216-B-34 and 216-B-52 received waste from the Uranium Recovery Process. Trenches 216-B-53A, 216-B-53B, 216-B-54 and 216-B-58 received laboratory and PRTR waste from 300 Area.

Waste Type: Process Effluent

Waste Description: The site received the scavenged tributyl phosphate (TBP) supernatant waste from the 221-U Building. The waste is high in salt and is neutral to basic. It contained inorganic compounds such as ferrocyanide, nitrate and phosphate.

Code: 216-B-33 **Classification:** Accepted
Names: 216-B-33; 216-B-33 Trench; 216-BC-20 Trench **Reclassification:** None
Type: Trench **Start Date:** 1/1/1957
Status: Inactive **End Date:** 1/1/1957

Description: The BC trenches were surface stabilized as a unit. The backfilled trenches have been covered with clean soil and posted as Underground Radioactive Material. Concrete AC 540 markers outline the area where the trenches are located, but do not identify specific trench locations. The site is a trench that was used for disposal of medium-activity liquid waste. The trench has been backfilled and the area has been surface stabilized.

Location: The unit is directly south of the 216-B-32 Trench, south of the 200 East Area (across Route 4S) in the BC Crib Area. The BC Cribs and Trenches are located inside the BC Controlled Area.

Related Sites/ Structures: The trench is associated with the U Plant uranium recovery process and UPR-200-E-83.

Process Description: From 1952 to 1958, waste containing uranium and fission products, produced by the bismuth phosphate separations process, were removed from underground storage tanks and reprocessed at 221-U to recover the uranium from the waste. After the uranium was removed, the cesium and strontium content of the effluent was reduced by precipitation. The supernate liquor was released to the ground in the BC Cribs and Trenches. A total of 16 unlined trenches, 216-B-20 through 216-B-34 and 216-B-52 received waste from the Uranium Recovery Process. Trenches 216-B-53A, 216-B-53B, 216-B-54 and 216-B-58 received laboratory and PRTR waste from 300 Area. The trench was a long narrow excavation with a 1:1.75 side slope. It was divided crosswise into two equal sections by an earthen dam. The dam was 1.5 meters (5 feet) high and 1.5 meters (5 feet) wide at the top. A 10.2 centimeter (4 inch) Schedule 40 pipe ran along the top edge of the trench. Four 7.62-centimeter (3-inch) Schedule 40 pipe sections extended laterally from the 10.2-centimeter (4-inch) pipe, down the side slope into the trench. Liquid discharge into the trench was controlled by gate valves located at the top of the lateral lines. A cover, constructed of 1 by 6 and 2 by 4 wood framing and sisalkraft paper, extended the length of the trench. The vertical distance from the cover to the trench bottom was a minimum of 1.5 meters (5 feet).

Waste Type: Process Effluent

Waste Description: The site received the scavenged tributyl phosphate (TBP) supernatant waste from 221-U Building. The waste is high in salt and is neutral to basic. It contained inorganic compounds such as ferrocyanide, nitrate and phosphate.

Code: 216-B-34 **Classification:** Accepted
Names: 216-B-34; 216-BC-21 Trench **Reclassification:** None
Type: Trench **Start Date:** 1/1/1957
Status: Inactive **End Date:** 1/1/1957

Description: The BC trenches were surface stabilized as a unit. The backfilled trenches have been covered with clean soil and posted as Underground Radioactive Material. Concrete AC 540 markers

outline the area where the trenches are located, but do not identify specific trench locations. The site is a trench that was used for disposal of medium-activity liquid waste. The trench has been backfilled and the area has been surface stabilized.

Location: The unit is directly south of the 216-B-33 Trench, south of the 200 East Area (across Route 4S) in the BC Crib Area. The BC Cribs and Trenches are located inside the BC Controlled Area.

Related Sites/ Structures: The trench is associated with the U Plant uranium recovery process and UPR-200-E-83.

Process Description: From 1952 to 1958, waste containing uranium and fission products, produced by the bismuth phosphate separations process, were removed from underground storage tanks and reprocessed at 221-U to recover the uranium from the waste. After the uranium was removed, the cesium and strontium content of the effluent was reduced by precipitation. The supernate liquor was released to the ground in the BC Cribs and Trenches. A total of 16 unlined trenches, 216-B-20 through 216-B-34 and 216-B-52 received waste from the Uranium Recovery Process. Trenches 216-B-53A, 216-B-53B, 216-B-54 and 216-B-58 received laboratory and PRTR waste from 300 Area. The trench was a long narrow excavation with a 1:1.75 side slope. It was divided crosswise into two equal sections by an earthen dam. The dam was 1.5 meters (5 feet) high and 1.5 meters (5 feet) wide at the top. A 10.2 centimeter (4 inch) Schedule 40 pipe ran along the top edge of the trench. Four 7.62-centimeter (3-inch) Schedule 40 pipe sections extended laterally from the 10.2-centimeter (4-inch) pipe, down the side slope into the trench. Liquid discharge into the trench was controlled by gate valves located at the top of the lateral lines. A cover, constructed of 1 by 6 and 2 by 4 wood framing and sisalkraft paper, extended the length of the trench. The vertical distance from the cover to the trench bottom was a minimum of 1.5 meters (5 feet).

Waste Type: Process Effluent

Waste Description: The site received the scavenged tributyl phosphate (TBP) supernatant waste from the 221-U Building. The waste is high in salt and is neutral to basic. It contained inorganic compounds such as ferrocyanide, nitrate and phosphate.

Code: 216-B-52	Classification: Accepted
Names: 216-B-52; 216-B-52 Trench; 216-BC-22	Reclassification: None
Type: Trench	Start Date: 1/1/1957
Status: Inactive	End Date: 1/1/1958

Description: The BC trenches were surface stabilized as a unit. The backfilled trenches have been covered with clean soil and posted as Underground Radioactive Material. Concrete AC 540 markers outline the area where the trenches are located, but do not identify specific trench locations.

Location: The unit is immediately north of the 216-B-23 Trench, south of the 200 East Area (across Route 4S) in the BC Crib Area.

Related Sites/ Structures: The site is associated with 221-U and UPR-200-E-83.

Process Description: From 1952 to 1958, waste containing uranium and fission products, produced by the bismuth phosphate separations process, were removed from underground storage tanks and reprocessed at 221-U to recover the uranium from the waste. After the uranium was removed, the cesium and strontium content of the effluent was reduced by precipitation. The supernate liquor was released to the ground in the BC Cribs and Trenches. A total of 16 unlined trenches, 216-B-20 through 216-B-34 and 216-B-52 received waste from the Uranium Recovery Process. Trenches 216-B-53A, 216-B-53B, 216-B-54 and 216-B-58 received laboratory and PRTR waste from

300 Area. The unit is divided in half by an earthen dam at the center. The dam is 1.5 meters (5 foot) high and 1.5 meters (5 foot) wide at the top. The side slope of the trench is 1.25:1.

Waste Type: Process Effluent

Waste Description: The site received scavenged waste from the uranium recovery process in 221-U (tributyl phosphate [TBP] solvent extraction). The waste is high in salt and is neutral to basic. It contained inorganic compounds such as ferrocyanide, nitrate and phosphate.

Code: 216-B-53A	Classification: Accepted
Names: 216-B-53A; 216-B-53A Trench; PRTR Trench	Reclassification: None
Type: Trench	Start Date: 1/1/1965
Status: Inactive	End Date: 1/1/1965

Description: The BC trenches were surface stabilized as a unit. The backfilled trenches have been covered with clean soil and posted as Underground Radioactive Material. Concrete AC 540 markers outline the area where the trenches are located, but do not identify specific trench locations.

Location: The trench is located south of the 200 East Area (across Route 4S) in the BC Crib Area. It is located inside the BC Controlled Area.

Release Description: On September 29, 1965, an accident occurred in the 300 Area when some test fuel at the Plutonium Recycle Test Reactor (PRTR) in the 309 building failed, causing failure of the process tube which contaminated the 309 reactor's moderator coolant system. The Rupture Loop Ion Exchange (RLIX) test loop and the PRTR main cleanup system were both contaminated with residual plutonium fuel and fission products. Nearly 3.8 million liters (1 million gallons) of light water was initially contaminated. However additional cooling water was added over many days following the accident and the contaminated water volume rose to nearly 53 million liters (14 million gallons). The contaminated effluent was transferred to the 340 facility and then transported by tanker trucks to the 200 Area. The trucking of contaminated liquid continued on an around the clock basis though October 1965. Some contaminated equipment was transported to the 200 North Area and stored in 212-N.

Related Sites/Structures: The trench is related to the 309 building, the 340 facility and an incident that occurred in the 309 building ion exchange column (sitecode 309-WS-2). It is located inside the BC Radiologically controlled area UPR-200-E-83.

Process Description: The trench was active during October and November 1965. The site received waste from a liquid release at the Plutonium Recycle Test Reactor (PRTR) in the 300 Area. Contaminated liquid was transported to the 200 Area via tanker trucks. Use of the trench discontinued when specific retention capacity was reached. Of all the specific retention trenches at this location, only 216-B-53A is considered to be a TRU waste site, containing 100 grams of plutonium. The trench was divided into two sections by an earthen dam at the center. The dam was 1.5 meters (5 feet) high and 12.7 centimeter (5 inches) wide at the top. The side slope of the open trench was 1.75:1.

Waste Type: Process Effluent

Waste Description: The site received waste from the Plutonium Recycle Test Reactor in the 300 Area. The waste is neutral to basic. This trench received 100 grams of plutonium.

Code: 216-B-53B	Classification: Accepted
Names: 216-B-53B; 216-B-53B Trench; 216-B-53 Trench	Reclassification: None
Type: Trench	Start Date: 1/1/1962

Status: Inactive**End Date:** 1/1/1963

Description: The BC trenches were surface stabilized as a unit. The backfilled trenches have been covered with clean soil and posted as Underground Radioactive Material. Concrete AC 540 markers outline the area where the trenches are located, but do not identify specific trench locations. The BC Cribs and Trenches are located inside the radiologically controlled area known as the BC Controlled Area (UPR-200-E-83).

The trench is divided into two sections by an earthen dam at the center. The dam is 1.5 meters (5 feet) high and 12.7 centimeter (5 inch) wide at the top. The side slope is 1.75:1.

Location: The trench is located south of the 200 East Area (across Route 4S) in the BC Crib Area. The trench is inside the BC Controlled Area.

Release Description: See UPR-200-E-83

Related Sites/ Structures: The trench is associated with 300 Area laboratory waste and the 340 facility.

Process Description: Liquid waste from the 300 Area laboratory facilities was sent to the 340 facility via the process sewer. Waste that was above the release limits for the 300 Area Process Ponds was sent by tanker truck to the 200 Area for disposal.

Waste Type: Process Effluent

Waste Description: The site received liquid waste from the 300 Area Hanford Laboratory Operations. The waste is low in salt and is neutral to basic.

Code: 216-B-54**Classification:** Accepted**Names:** 216-B-54; 216-B-54 Trench**Reclassification:** None**Type:** Trench**Start Date:** 1/1/1963**Status:** Inactive**End Date:** 1/1/1963

Description: The BC trenches were surface stabilized as a unit. The backfilled trenches have been covered with clean soil and posted as Underground Radioactive Material. Concrete AC 540 markers outline the area where the trenches are located, but do not identify specific trench locations. The trench is located inside the Radiologically Controlled Area boundaries known as the BC Controlled Area (UPR-200-E-83).

Location: The trench is located south of the 200 East Area (across Route 4S). The trench is within the BC Controlled Area.

Release Description: In 1969, contaminated Russian thistles were found growing on trenches 216-B-53A, 216-B-53B and 216-B-54. The weeds had a maximum dose rate of 1500 millirem per hour. The contaminated weeds were removed and buried. Action was taken to inhibit weed growth on the trenches.

Related Sites/ Structures: The trench is associated with the 300 Area laboratory facilities and the 340 facility.

Process Description: Liquid waste from the 300 Area laboratory facilities was sent to the 340 facility via the process sewer. Waste that was above the release limits for the 300 Area Process Ponds was sent by tanker truck to the 200 Area for disposal. Although some reference documents state the trench was active from 1963 to 1965, ARH-947 and ARH-2806 state the trench was activated in March 1963 and removed from service in October 1963. The trench was divided into two sections by an earthen dam at the center. The dam was 1.5 meters (5 feet) high and 12.7

centimeter (5 inches) wide at the top. The side slope of the open trench was 1.75:1.

Waste Type: Process Effluent

Waste Description: The site received waste from the Hanford Laboratory Operations (BNWL) in the 300 Area. The waste is low in salt and is neutral to basic.

Code: 216-B-58 **Classification:** Accepted

Names: 216-B-58; 216-B-58 Trench; 216-B-59 Crib **Reclassification:** None

Type: Trench **Start Date:** 1/1/1965

Status: Inactive **End Date:** 1/1/1967

Description: The BC trenches were surface stabilized as a unit. The backfilled trenches have been covered with clean soil and posted as Underground Radioactive Material. Concrete AC 540 markers outline the area where the trenches are located, but do not identify specific trench locations. The trench is within the posted Radiologically Controlled Area known as the BC Controlled Area (UPR-200-E-83). The trench was divided into 7.6-meter (25-foot) sections by 1.2-meter (4-foot) high earthen dams. Each section had a wooden cover. A 1.22-meter (48-inch) diameter pipe was placed along the bottom. The pipe was corrugated with five 10.16-centimeter (4-inch) diameter holes around the bottom half.

Location: The trench is located south of the 200 East Area (across Route 4S) in the BC Crib Area.

Related Sites/ Structures: The trench is associated with 300 Area laboratory facilities and the 340 facility.

Process Description: Liquid waste from the 300 Area laboratory facilities was sent to the 340 facility via the process sewer. Waste that was above the release limits for the 300 Area Process Ponds was sent by tanker truck to the 200 Area for disposal. The trench was covered with 8 wooden cover frames, 5.5 meter (18 feet) wide by 8.5 meter (28 feet) long a 7.62-centimeter (3-inch) schedule 40, carbon steel pipe, approximately 7 meters (23 feet) long placed along a side of the structure.

Waste Type: Process Effluent

Waste Description: The site received Battelle Northwest laboratory (BNWL) waste from the 300 Area. The waste is low in salt and is neutral to basic.

Code: 200-E-14 **Classification:** Accepted

Names: 200-E-14; 216-B-201; 216-BC-201 Siphon Tank **Reclassification:** None

Type: Storage Tank **Start Date:** 1/1/1956

Status: Inactive **End Date:** 1/1/1957

Description: The 216-B-14, 216-B-15, 216-B-16, 216-B-17, 216-B-18 and 216-B-19 cribs and the 216-BC-201 siphon tank were surface stabilized as a single area. All the surface structures (risers and vents) have been removed. There are concrete AC 540 markers to identify the site. The vents were visible until 1981 when the area was surface stabilized. The vent risers were removed at ground level and the area was covered with at least 0.6 meters (2 feet) of additional top soil. The area is posted as Underground Radioactive Material.

Location: The siphon tank is located south of Route 4S, south of the 200 East Area. The tank is north of and adjacent to the 216-B-14 through 216-B-19 Cribs. The tank is 18 meters (60 feet) north of the center line between the 216-B-14 and 216-B-15 Cribs.

Related Sites/ Structures: The tank is associated with the 2805-E-3 and 2805-E-4, 200-E-222-PL pipelines, the 216-B-14, 216-B-15, 216-B-16, 216-B-17, 216-B-18 and 216-B-19 cribs, 241-BY Tank Farm and 221-U.

Process Description: The 216-BC-201 siphon tank was used to discharge waste to the 216-B-14, 216-B-15, 216-B-16, 216-B-17, 216-B-18 and 216-B-19 cribs. The siphon tank would receive and hold the waste until the tank level reached 1.6 meters (5.5 feet). When this level was reached, the siphon action would begin and the tank contents would discharge to the designated crib. The siphon action would stop when the tank level reached 0.07 meters (6 inches). The siphon action was intended to flood the crib area with a significant amount of liquid, resulting in a uniform spread of contaminants throughout the crib, instead of a large amount of contaminants concentrating near the discharge point.

Waste Type: Process Effluent

Waste Description: Most of the liquid waste dispersed through this tank originated from the Uranium Recovery Process in 221-U (U-Plant). The process reclaimed the uranium metal from the tank farm waste derived from the bismuth phosphate fuel processing activities. Curren (1972) states that 216-B-17 and 216-B-19 also received scavenged tank farm waste. The waste includes ferrocyanide, phosphate, cesium, strontium, uranium, cobalt and ruthenium. The total effluent to the six cribs that passed through the 216-BC-201 Siphon Tank was 3.896×10^7 liters (1.032×10^7 gallons). At the time of discharge (1956), the total radionuclide activity for all six cribs equaled 26 curies of cobalt-60, 1,840 curies of cesium-137, 1,850 curies of strontium-90, 70 grams of plutonium and 1,410 kilograms (640 pounds) of uranium.

200-CB-1

Code: 216-B-4 **Classification:** Accepted

Names: 216-B-4; 216-B-4 Dry Well; 216-B-4 French Drain; 216-B-4 Reverse Well **Reclassification:** None

Type: Injection/Reverse Well **Start Date:** 1/1/1945

Status: Inactive **End Date:** 1/1/1949

Description: The site is marked with a single concrete AC-540 marker post, with an Underground Radioactive Material sign attached to the post. The top of the well extends 0.6 meters (2 feet) above ground.

Location: The french drain is located south of the 221-B Building, east of the 222-B building and north of the 292-B Building.

Related Sites/Structures: The french drain is related to the 291-B Stack and the 292-B building. The pipeline associated with this waste site is 200-E-230-PL.

Waste Type: Water

Waste Description: Before August 1947, the site received 291-B Stack drainage. After August 1947, the site received floor drainage from the 292-B Building. The waste is neutral to basic and low salt with less than one curie of total beta contaminants. The B Plant AAMS Report also mentions transuranic fission products.

Code: 216-B-13 **Classification:** Accepted

Names: 216-B-13; 216-B-13 Crib; 216-B-13 French Drain; 216-B-B; 291-B Crib **Reclassification:** None

Type: French Drain **Start Date:** 1/1/1945

Status: Inactive **End Date:** 1/1/1976

Description: A single, concrete AC-540 marker is the only site identifier. There an Underground Radioactive Material sign attached to the concrete post.

Location: The french drain is located south of 221-B and northeast of the 291-B-1 Stack.

Related Sites/Structures: The french drain is associated with the 291-B stack. The pipeline that fed the french drain is sitecode 200-E-243-PL.

Process Description: Many documents state the unit operated from August 1947 to June 1976. In June 1976, the stack drainage was rerouted to a cell drainage sample tank. The french drain is constructed of two 1.22 meter (4 feet) diameter by 1.53 meter (5 feet) long tile pipes, stacked vertically and filled with crushed limestone. The unit has a plywood cover, located 2.44 meters (8 feet) below grade. Two and a half tons (2,270 kilograms) of limestone were used as a base and to fill the tile pipes. The bottom of the drain is 5.5 meters (18 feet) below ground surface. However, an Atlantic Richfield Hanford Company memo, created on October 3, 1974, states the drain line to the french drain was cut and capped in June 1974.

Waste Type: Process Effluent

Waste Description: The site received the 291-B-1 Stack drainage. In 6/76, the stack drainage was rerouted to a catch tank, jetted to the wind tunnel, drained to a sump, and then pumped to a cell drainage sample tank. The waste is low in salt and is neutral to basic.

Code: 216-B-60	Classification: Accepted
Names: 216-B-60; 216-B-60 Crib	Reclassification: None
Type: Crib	Start Date: 1/1/1967
Status: Inactive	End Date: 1/1/1967

Description: The crib is not visible because the 225-B Building was built on top of the crib site in 1975. There is a sign posted on the south wall of the 225-B building indicating where the 216-B-60 crib is located.

Location: The crib is located at the west end of the 221-B Building. The southeast portion of the 225-B Encapsulation Facility was built over the crib site.

Related Sites/ Structures: The crib is associated with the 221-B facility operations.

Process Description: The 216-B-60 crib was a single use, specific retention crib. The crib was constructed of two steel caissons positioned side by side (standing on end) that were 2.4 meters (8 feet) in diameter and 4.2 meters (14 feet) tall. The two caissons were installed in November 1967 to receive waste from the cleanout of the 0.6 meter (24 inch) 221-B cell drain header. The cleanout process was completed in December 1967. The first caisson received 18, 499 liters (4887 gallons) of sludge solids and was capped with concrete. The second caisson received a small volume of flush water. The 0.6 meter (24 inch) line was plugged after cleanout and the caissons were backfilled to grade.

Waste Type: Process Effluent

Waste Description: The site received the cell cleanout solid and liquid waste from the 61 centimeter (24 inch) 221-B Building cell cleanout drain line. The waste was low in salt and was neutral to basic. Composite sample results indicated 715.5 kilograms of uranium, 0.08 grams of plutonium, 777 curies of Ce-144, 8 curies of Cs-137 and 5 curies of Eu-154.

Code: 221-B	Classification: Accepted
Names: 221-B; B Plant Canyon; B Plant Facility	Reclassification: None
Type: Process Unit/Plant	Start Date: 1/1/1945
Status: Inactive	End Date:

Description: The B Plant facility is one of the original Hanford chemical processing buildings. The 221-B Process Canyon is a large, reinforced concrete building. It consists of twenty sections (two cells per section) with expansion joints between each section. The building is divided lengthwise into the gallery side and the canyon chemical processing side by a thick, concrete shielding wall running the full length of the building.

Location: The facility is located inside 200 East Area, on Atlanta Ave.

Code: 200-E-6	Classification: Accepted
Names: 200-E-6; Sanitary Sewer Repair and Replacement 2607-E4; Septic Tank	Reclassification: None
Type: Septic Tank	Start Date: 1/1/1981
Status: Inactive	End Date: 1/1/1998

Description: The septic tank is surrounded by chain with four steel posts painted yellow. The tank is posted with a septic tank sign. The tank has two 10 centimeter (4-inch) PVC pipes which protrude vertically from the ground. The sanitary tile field is surrounded with a steel post and chain barricade and is posted with Caution Underground Radioactive Material signs.

Location: The site is located just east of the 221-B Building and south of the inactive 2607-E4 septic tank.

Process Description: The septic system received waste from the 221-B Building.

Waste Type: Sanitary Sewage

Waste Description: The site received sewage from lavatory facilities within the 221-B Building.

Code: 200-E-55 **Classification:** Accepted

Names: 200-E-55; Effluent Drain East of 291-B Sand Filter; Miscellaneous Stream #322 **Reclassification:** None

Type: French Drain **Start Date:** 1/1/1948

Status: Inactive **End Date:** 1/1/1997

Description: There are no visual surface features for this drain. It has been marked with a single steel post. The drain is below grade and east of the B-Plant Sand Filter. The french drain consists of a hole 1.83 meters (6 feet) in diameter, 0.9 meters (3 feet) deep backfilled with gravel.

Location: The french drain is located 3.6 meters (12 feet) east of the east end of the 291-B Sand Filter (WIDS Site Code 200-E-30).

Related Sites/Structures: The drain is associated with the 291-B Sand Filter (200-E-30). The pipeline to this french drain is sitecode 200-E-214-PL.

Process Description: Sand Filters were added to the B Plant exhaust system in 1948. Condensate from the sand filter drained to a pipe in the bottom of the east end of the sand filter that dispersed the effluent to a gravel filled hole adjacent to the sand filter.

Waste Type: Process Effluent

Waste Description: The drain received condensate from the B-Plant canyon sand filter and rain water that leaked through the sand filter roof. An auger drill sample of the sand filter french drain was collected in September 1994. A spilt spoon sample was collected at 4.8 meters (16 feet) below ground surface. Maximum contamination levels in the soil read 20,000 disintegrations per minute beta/gamma and 2100 disintegrations per minute alpha with hand held instruments. The sample was shipped to a mobile laboratory for analysis.

Code: 2607-E4 **Classification:** Accepted

Names: 2607-E4; 2607-E4 Septic Tank and Tile Field **Reclassification:** None

Type: Septic Tank **Start Date:** 1/1/1963

Status: Inactive **End Date:** 1/1/1998

Description: The septic tank and tile field are marked with a Sanitary Sewer/Drain Field sign and lie with a posted Underground Radioactive Material area. The 2607-E4 Septic Tank is constructed of reinforced concrete that drains to an adjacent tile field.

Location: The 2607-E4 Septic Tank is located northeast of the 221-B Building. The tile field is northeast

of the tank.

Related Sites/ Structures: The 2607-E4 Septic Tank is associated with the 2607-E4 Tile Field and B-Plant Facilities.

Process Description: The 2607-E4 Septic Tank and associated tile field were designed to accept and treat sanitary sewer effluent from B-Plant facilities.

Waste Type: Sanitary Sewage

Waste Description: This septic tank received sanitary wastewater and sewage from B Plant facilities at an estimated rate of 0.24 cubic meters (8.5 cubic feet) per day. The tank was abandoned in 1998. No information was provided related to sampling.

Code: UPR-200-E-1 **Classification:** Accepted

Names: UPR-200-E-1; Waste Line Failure on South Side of 221-B **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1946

Status: Inactive **End Date:** 1/1/1946

Description: The unplanned release is not separately marked or posted. The contamination was assumed to have migrated from the source, which was a pipeline leak that occurred four months earlier.

Location: The release occurred on the south side of the 221-B Building.

Release Description: Soil contamination was detected approximately 24.4 meters (80 feet) from the location of a waste line rupture location that was identified on June 17, 1946. The additional contamination was assumed to be migration from the first line failure. Following the discovery of the additional contamination, test holes were dug to determine the extent of the contamination.

Related Sites/ Structures: This unplanned release is associated with UPR-200-E-80 and 200-E-226-PL.

Waste Type: Process Effluent

Waste Description: The original line break (metal waste line) had dose rates up to 400 rad per hour.

Code: UPR-200-E-2 **Classification:** Accepted

Names: UPR-200-E-2; Spotty Contamination Around the B and T Plant Stacks; UN-200-E-2 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1947

Status: Inactive **End Date:**

Description: This unplanned release is not physically posted or marked.

Location: In 1947, document indicated radioactive particulate contamination was identified in a 300 meter (1000 foot) radius around the B and T Plant stacks.

Release Description: A document written on 11/18/1947 states radioactive particulate matter was found within a 305 meters (1,000 feet) radius around the B Plant and T Plant stacks. A study of the ground contamination found that mist-like particles were released over a larger area and that the particulate matter had magnetic properties.

Waste Type: Chemicals

Waste Description: Spotty ground contamination around the B Plant stack. Most stack releases consisted of ruthenium.

Code: UPR-200-E-44 **Classification:** Accepted

Names: UPR-200-E-44; BCS Waste Line Leak South of 221-B; UN-200-E-44 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1972

Status: Inactive **End Date:**

Description: The release site is not separately marked or posted. There is no visual evidence of the area that caved in.

Location: The unplanned release occurred south of 221-B, near the R-17 Change House. north of 7th Street. The Change House no longer exists.

Release Description: A small cave-in was discovered south of the R-17 change house next, to the black-top road (7th Street). There was no radiological reading identified in the cave-in at the time of discovery. An excavation was done after lunch that identified a leak in the 15 centimeter (6 inch) BCS crib line. Soil removed from the excavation was contaminated from 10,000 to 20,000 counts per minute. The dose rate on the pipe was 20 millirad per hour. There was no contamination spread from the excavation.

Related Sites/ Structures: This site is associated with B Plant and UPR-200-E-103.

Waste Type: Process Effluent

Waste Description: The leaking effluent from the BCS crib line caused the ground to cave in. The dirt was contaminated with readings of 10,000 to 20,000 counts per minute. The pipe was contaminated with readings up to 20 millirem per hour.

Code: UPR-200-E-52 **Classification:** Accepted

Names: UPR-200-E-52; Contamination Spread Outside the North Side of 221-B; UN-200-E-52 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1975

Status: Inactive **End Date:**

Description: In 2008, an area approximately 4 meters (13 feet) wide by 9 meters (30 feet) was posted with a WIDS sign and Underground Radioactive Material Area signs (see photos).

Location: The unplanned release occurred on the north side of 221-B, near the steps that cross the railroad tunnel. Soil contamination occurred under the drain of the steam pressure relief pipe discharge from the E-5-2 Strontium Concentrator.

Release Description: On August 1, 1975, soil contamination ranging to 20,000 counts per minute was detected under the drain of the steam pressure relief pipe discharge from the E-5-2 Strontium Concentrator, and an area about 0.91 meters (3 feet) wide and 2.74 meters (9 feet) high on the north side of the 221-B Building was contaminated to 100,000 counts per minute outdoors. Soil on the western berm adjacent to the railroad cut was also contaminated. The apparent cause was that contamination migrated from the leaking tube bundle of the recently replaced E-5-2 strontium concentrator to the pipe gallery piping. It was then forced outside by operation of the relief valve when the operating steam pressure was increased to 35 pounds per square inch while the relief valve setting remained at 32 pounds per square inch.

Waste Type: Process Effluent

Waste Description: Beta/gamma with readings up to 20,000 counts per minute were found in the soil under the steam pressure relief discharge pipe from the E-5-2 Strontium Concentrator. Another area on the north side of 221-B was contaminated up to 100,000 counts per minute.

Code: UPR-200-E-54

Classification: Accepted

Names: UPR-200-E-54; Contamination Outside 225-B Doorway; UN-200-E-54

Reclassification: None

Type: Unplanned Release

Start Date: 1/1/1977

Status: Inactive

End Date:

Description: There is a sign posted on the south wall of 225-B, next to Door 130, that reads UPR-200-E-54. There is no radiological posting around the doorway or in the soil adjacent to the concrete door pad.

Location: The site is located adjacent to exit door #130 on the south side of the 225-B Building.

Release Description: On July 20, 1977, water used for decontaminating a manipulator seeped under an exit door of the 225-B Building spreading low-level contamination onto the concrete door pad and adjacent soil. Radiation readings on the pad were 25 millirads per hour direct and 20,000 counts per minute smearable. While decontaminating the manipulator, the water spray wand was accidentally directed toward the corridor door by the operator. Water was forced under the door into the corridor. The water trickled down the corridor to a drain in the Service Gallery. As water passed the exit door about 1.89 liters (0.5 gallons) seeped under the unsealed threshold onto the pad and soil.

Waste Type: Water

Waste Description: Water seeping under an exit door caused beta/gamma with readings of 25 millirads/hour direct and 20,000 counts per minute smearable on the concrete pad outside the door at 225-B. Contamination readings in the soil were 10,000 counts per minute. The contaminated liquid was from a manipulator decontamination activity.

Code: UPR-200-E-55

Classification: Accepted

Names: UPR-200-E-55; Contamination Spread South of B Plant; UN-200-E-55

Reclassification: None

Type: Unplanned Release

Start Date: 1/1/1979

Status: Inactive

End Date:

Description: A single post with a sign that reads UPR-200-E-55 is currently located under an aboveground line. The area is not radiologically posted. It marks the approximate location of the release.

Location: The release occurred on the south side of B-Plant, at the 212-B building. Smearable contamination was found around the K-3 filter area, that is located on the roof of the 212-B Building, on the roadway southwest of the K-3 filter area, and the gravel area southwest of the 212-B Building.

Release Description: On April 27, 1979, wind spread contamination from a plastic sheeting in a radiation zone near the 212-B Building to an adjacent area. The incident occurred after the K-3 east filter was changed out. During the changeout plastic was laid down for contamination control within a radiation zone. The wind whipped the contamination plastic as it was being packaged for burial. The general area was surveyed and spots of contamination ranging from 5,000 counts per minute to 30,000 counts per minute were found outside the radiation zone.

Waste Type: Chemicals

Waste Description: While changing the K-3 filter, wind blew beta/gamma contamination (particles), with readings of 5,000 to 30,000 counts per minute, outside the radiation zone.

Code: UPR-200-E-80 **Classification:** Accepted

Names: UPR-200-E-80; 221-B R-3 Line Break; R-3 Radiation Zone; UN-200-E-80; UN-216-E-8 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1946

Status: Inactive **End Date:** 1/1/1946

Description: The unplanned release is not separately marked or posted.

Location: The release occurred in and underground pipeline, located on the south side of the 221-B Canyon Building, near the R-3 stairwell. The leak resulted in a contaminated area measuring 30 meters (100 feet) wide by 152 meters (500 feet) in length, along the south side of the 221-B building.

Release Description: On June 17, 1946, an underground metal waste line failure was detected near section R-3 on the south side of the 221-B building. ARH-780 says the dose rate at ground surface level was 400 rad per hour. The leak was confirmed by hydrostatic testing. A 1946 letter report states the dose rate at the cave-in location was greater than 4000 R/hr. (4000 Rep/hr with a Victoreen probe). Operations were halted for six days to change the waste routing and cover the area with several feet of gravel. A portion of the area had caved in to a depth of approximately 1 meter (3 feet). The excavated contaminated soil was taken to the Dry Waste Burial Ground. The excavation was backfilled. After covering the contamination, the dose rate was reduced to 100 millirad per hour.

Related Sites/Structures: UPR-200-E-80 is associated with an underground metal waste line from the 221-B Canyon Building and UPR-200-E-1. It is likely associated with 200-E-226-PL pipeline (line V743).

Waste Type: Process Effluent

Waste Description: The release consisted of approximately of 10 curies of fission products from the "metal waste" pipe line.

Code: UPR-200-E-85 **Classification:** Accepted

Names: UPR-200-E-85; Line Leak at 221-B Stairwell R-13; UN-200-E-41; UN-200-E-85; UN-216-E-13; UPR-200-E-41 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1972

Status: Inactive **End Date:** 1/1/1972

Description: The R-13 Utility Pit is covered with a steel lid. The site was stabilized in 1984 and posted with Underground Radioactive Material signs.

Location: UPR-200-E-85 occurred south of the center of the 221-B Building, near the R-13 Utility Pit.

Release Description: During a routine survey, it was discovered that an unencased transfer line leading from the ion exchange tank 18-1 in the 221-B building to the 241-BX-154 Diversion Box had leaked process waste near the R-13 Utility Pit. The contaminated waste apparently seeped through a wall joint and ran into the electric utility pit. Radiation measurements were taken near the bottom of the pit. The measurements read 15 rad per hour at a distance of 5 centimeters (2 inches) from the

source.

Related Sites/ Structures: UPR-200-E-85 is associated with the 18-1 Tank in the 221-B Building, the 241-BX-154 Diversion Box and the R-13 Utility Pit. This occurrence was also given the number UPR-200-E-41.

Waste Type: Process Effluent

Waste Description: The waste line contained ion exchange waste from tank 18-1, located inside the B Plant canyon. Soil samples collected in 1972 found the release was predominantly cesium-137. Approximately 30 curies of cesium was released, but half of the release was removed with the soil excavated to expose the line leak.

Code: UPR-200-E-87 **Classification:** Accepted

Names: UPR-200-E-87; 216-E-15; 224-B South Side Plutonium Ground Contamination; UN-200-E-87; UN-216-E-15 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1945

Status: Inactive **End Date:** 1/1/1953

Description: Some areas on the south side of 224-B are posted with Underground Radioactive Material signs. The release site is not specifically marked.

Location: The UPR-200-E-87 site is located on the south side of the 224-B Building in the 200 East Area.

Release Description: Plutonium-239 is believed to have leaked into the soil from underground pipelines located on south side of the 224-B Building because of the large amount of plutonium contaminated soil found while excavating near pipelines at 224-T in 1972. Because 224-T and 224-B were built exactly alike, alpha-laden moisture may also have seeped into the soil from underground pipeline joints at 224-B Building.

Related Sites/ Structures: UPR-200-E-87 is associated with the underground pipelines at the 224-B Building and UPR-200-W-102.

Waste Type: Process Effluent

Waste Description: Approximately 75 grams (3 ounces) of plutonium-239 may have leaked into the soil at 224-B, based on an actual excavation that found contaminated soil at 224-T in 200 West Area.

Code: UPR-200-E-103 **Classification:** Accepted

Names: UPR-200-E-103; BCS Line Leak South of R-17 at 221-B; UN-200-E-103 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1972

Status: Inactive **End Date:** 1/1/1972

Description: The release site is not marked or posted. The change house structure has been removed.

Location: UPR-200-E-103 occurred in the soil surrounding a process transfer line south of the R-17 Change House and adjacent to Seventh Street. The change house structure has been removed.

Release Description: A 0.3 meter (1 foot) diameter depression was noted in the blacktop near 7th Street, just south of the R-17 construction change house. The maximum radiation reading in the depression was 1500 counts per minute. The hole was sealed with a filter and barricaded as a radiation area until the line could be valved off and repaired. The blacktop and dirt were excavated down to the BCS line. Maximum contamination in the dirt was 100,000 counts per minute. The

contaminated dirt was taken to the burial ground. The line was found to have several openings in it. The leaking section of pipe was removed and replaced. There was no spread of contamination or personnel contamination noted during the line repair.

**Related Sites/
Structures:** UPR-200-E-103 was associated with the 221-B Building, the BCS transfer line south of the R-17 Change House, and UPR-200-E-44. It may be associated with pipelines 200-E-161-PL or 200-E-162-PL.

Waste Type: Process Effluent

**Waste
Description:** The release consisted of contaminated liquid from the BCS crib line, with radiation levels up to 1,500 counts per minute at the surface of the depression and 100,000 counts per minute inside the excavation.

200-CP-1

Code: 202-A **Classification:** Accepted
Names: 202-A; PUREX Canyon; PUREX Facility **Reclassification:** None
Type: Process Unit/Plant **Start Date:** 1/1/1955
Status: Inactive **End Date:**

Description: The 202-A facility is a large, reinforced concrete structure that includes a concrete canyon with below grade cells that contain the equipment used for chemical separation.

Location: The PUREX facility is located inside 200 East Area, on 4th Street.

Process Description: The PUREX plant was constructed for the purpose of extracting plutonium, uranium and neptunium from irradiated fuel rods discharged from Hanford reactors. The PUREX (Plutonium/Uranium Extraction) chemical separation process was based on decladding the fuel rods with nitric acid and conducting multiple purification processes of the resultant aqueous solution. These operations occurred inside the canyon cells.

Code: 216-A-11 **Classification:** Accepted
Names: 216-A-11; 216-A-11 French Drain; **Reclassification:** None
Miscellaneous Stream #465
Type: French Drain **Start Date:** 1/1/1956
Status: Inactive **End Date:** 1/1/1972

Description: The site is inside a small area delineated by steel posts and chain. It is posted as an Underground Radioactive Material area. A 0.76 meter (2.5 foot) diameter, circular metal cover is visible. One concrete AC-540 marker identifies the site.

The unit is composed of two reinforced concrete pipes placed vertically end to end. The excavation is 3.0 meters (10 feet) in diameter and extends to a depth of 1.5 meters (5 feet) below the bottom. Both the drain and the excavation are filled with 8-centimeter (3-inch) rock to the top and are backfilled over.

Location: The site is located near the southeast corner of the 202-A Building, south of Trap Pit #1.

Related Sites/ Structures: The site is associated with the PUREX Trap Pit #1 and pipeline 200-E-266-PL.

Process Description: A sump in the bottom of Trap Pit #1 collected steam condensate and equipment leakage that drained into 216-A-11.

Waste Type: Steam Condensate

Waste Description: The site received the Trap Pit #1 drainage from the 202-A Building. The waste was low in salt and was neutral to basic. The site contains less than 50 curies total beta activity.

Code: 216-A-12 **Classification:** Accepted
Names: 216-A-12; Miscellaneous Stream #463 **Reclassification:** None
Type: French Drain **Start Date:** 1/1/1955
Status: Inactive **End Date:** 1/1/1972

Description: The site is not marked or posted. There are no visible surface features for this drain. The wall of the trap pit includes a "French Drain" label. The unit is composed of two reinforced concrete tile pipes placed vertically end to end. The excavation is 3.0 meters (10 feet) in diameter and extends 1.5 meters (5 feet) below the bottom. Both the drain and the excavation are filled with gravel to the top of the unit and backfilled over. This site cannot be visually located.

Location: The site is located at the center of the south side of the 202-A Building, approximately 23 meters (75 feet) from the building.

Related Sites/ Structures: The site is associated with PUREX Trap #3 and pipeline 200-E-267-PL.

Process Description: A sump in the bottom of Trap Pit #3 collected steam condensate, rain water and equipment leakage and drained it to 216-A-12.

Waste Type: Steam Condensate

Waste Description: The site received the Steam Trap Pit #3 drainage from the 202-A Building. The waste was low in salt and was neutral to basic. The site contains less than 50 curies total beta activity. It is possible that more than one Trap Pit drained to this french drain.

Code: 216-A-13 **Classification:** Accepted

Names: 216-A-13; 216-A-13 French Drain; Miscellaneous Stream #460 **Reclassification:** None

Type: French Drain **Start Date:** 1/1/1956

Status: Inactive **End Date:** 1/1/1962

Description: The site is not marked or posted. A 1.2 meter (45 inch) diameter metal cover is visible over the drain. The drain is constructed of two lengths of concrete pipe placed vertically end to end. The unit is filled to a depth of 0.9 meters (3 feet) with 5 to 8 centimeters (2 to 3 inches) of rock. This unit has a bed of gravel around the lower section of pipe extending a minimum of 0.3 meters (1 foot) away from the pipe in all directions.

Location: The site is located approximately 6 meters (20 feet) west and 6 meters (20 feet) south of the southwest corner of the 202-A Building.

Related Sites/ Structures: The site is associated with PUREX, the 216-A-35 French Drain and pipeline 200-E-273-PL.

Process Description: The site received the seal water from the air sampler vacuum pumps in the 202-A Building.

Waste Type: Water

Waste Description: The site received the seal water from the air sampler vacuum pumps in the 202-A Building. The waste is low in salt, neutral to basic, and contains less than 1 curie total beta activity. The 1993 PUREX AAMS Report lists the total volume released as 100,000 liters (30,000 gallons), but does not give the reference for this discrepancy from the original Stenner report. It is assumed that the original number is correct, and the AAMS report added an extra "0" in error.

Code: 216-A-14 **Classification:** Accepted

Names: 216-A-14; French Drain - Vacuum Cleaner Filter Pit; Miscellaneous Stream #462 **Reclassification:** None

Type: French Drain **Start Date:** 1/1/1956

Status: Inactive**End Date:** 1/1/1972

Description: The drain is not marked or posted. There are no visible surface features for this french drain. The Vacuum Cleaner Filter Pit is a concrete box with approximately 0.6 meters (2 feet) above grade. The sump is inside the pit and drains through an underground pipe to the buried french drain. The drain is composed of two reinforced concrete pipes placed vertically end to end. The excavation is 3.0 meters (10 feet) in diameter and extends to a depth of 1.5 meters (5 feet) below the bottom. Both the drain and the excavation are filled with 8-centimeter (3-inch) rock to the top and backfilled over. The filter pit access is labeled Contamination Area, Radiation Area, Airborne Contamination and Confined Space. A 10 centimeter (4 inch) M23b-UD inlet pipe, approximately 1.5 meters (5 feet) long, extends horizontally into the unit, 7.9 meters (26 feet) below grade. The site has a 1.3 centimeter (0.5 inch) thick steel cover.

Location: The site is located south of the center of the 202-A Building, 5.5 meters (18 feet) east of the Filter Pit.

Related Sites/ Structures: The site is associated with the Vacuum Cleaner Filter Pit and pipeline 200-E-268-PL.

Process Description: A sump in the bottom of Filter Pit collected steam condensate, stormwater and equipment leakage that drained to 216-A-14.

Waste Type: Steam Condensate

Waste Description: The site received the vacuum cleaner filter and blower pit drainage from the 202-A Building. The waste was low in salt, neutral to basic, and contains less than 1 curie total beta activity.

Code: 216-A-32**Classification:** Accepted**Names:** 216-A-32; 216-A-32 Crib**Reclassification:** None**Type:** Crib**Start Date:** 1/1/1959**Status:** Inactive**End Date:** 1/1/1972

Description: The site is currently surrounded with cement posts with Underground Radioactive Material signs. There had been an inner area marked with steel posts, chains and Surface Contamination signs. The area was surface stabilized in 2001 and is now covered with clean gravel.

Location: The crib is located northeast of 202-A, inside the PUREX exclusion fence.

Related Sites/ Structures: The site is associated with 202-A and the 200-E-107 stabilized area. The pipeline associated with this crib is sitecode 200-E-194-PL.

Process Description: Perforated vitrified clay pipe was placed horizontally on the fill 1.5 meters (5 feet) above the bottom of the excavation. Two layers of sisalkraft paper separate the crib gravel from the overlying earthen backfill.

Waste Type: Water

Waste Description: The site received the 202-A canyon crane maintenance facility floor, sink, and shower drainage. The site contains less than 1 curie total beta activity. In a letter (Walsar 1966), Isochem Corporation indicates the intent to dispose of 24,600 liters (6,500 gallons) of approximately 50% Soltrol (a brand of purified kerosene) diluent in this crib. BHI-00178 (1995) reports that investigators were unable to verify if the proposed disposal took place.

Code: 216-A-35**Classification:** Accepted

Names: 216-A-35; 216-A-35 Dry Well; 216-A-35 French Drain **Reclassification** None

Type: French Drain **Start Date:** 1/1/1963

Status: Inactive **End Date:** 1/1/1966

Description: The drain is a raised cement structure, painted yellow and surrounded with Underground Radioactive Material signs. The top cover is marked Confined Space.

Location: The site is located approximately 9 meters (30 feet) south of the west end of the 202-A PUREX Building, south of the 216-A-13 French Drain.

Related Sites/ Structures: The site is associated with PUREX, the 216-A-13 French Drain and pipeline 200-E-272-PL.

Process Description: The site is a french drain that was a replacement for the 216-A-13 French Drain. The inlet pipe enters the french drain 3.2 meters (10.5 feet) below grade. Disposal to the site was terminated when the effluent flow rate exceeded the infiltration capacity of the soil. The site was deactivated by capping the effluent pipeline to the unit and rerouting the effluent to the 216-A-29 Ditch via the 202-A Chemical Sewer.

Waste Type: Water

Waste Description: The site received the seal cooling water from the air sampler vacuum pumps in the 202-A Building. The waste is low in salt, neutral to basic, and contains less than 1 curie of total beta activity.

Code: 241-A-151 **Classification:** Accepted

Names: 241-A-151; 241-A-151 Diversion Box **Reclassification** None

Type: Diversion Box **Start Date:** 1/1/1956

Status: Inactive **End Date:**

Description: The site is a reinforced concrete structure with cover blocks. Most of the structure is below grade. It is marked and radiologically posted.

Location: The diversion box is located south of the east end of the 202-A Building.

Release Description: Multiple documented Unplanned Releases are associated with this diversion box.

Related Sites/ Structures: The site is associated with 241-A-302-A Catch Tank, drain line V028, 241-A and 241-A X Tank Farms, UPR-200-E-25, 200-E-183-PL, 200-E-207-PL, 200-E-218-PL, UPR-200-E-26 and UPR-200-E-65.

Process Description: The 241-A-151 diversion box began transferring waste from PUREX to the 241-A Tank Farms in 1956. The diversion box routed waste from the 202-A building to the 241-A-A and 241-A-B valve pits and later to the 241-AW-A and 241-AW-B valve pits. Excess solution drained to the 241-A-302A catch tank. The system is equipped with a leak detector alarm.

Waste Type: Process Effluent

Waste Description: The unit transferred process effluents from the PUREX facility to the tank farms. Lead shielding may also be contained inside the diversion box.

Code: 241-A-302A **Classification:** Accepted

Names: 241-A-302A; 241-A-302-A Catch Tank; Line V028 **Reclassification** None

Type: Catch Tank **Start Date:** 1/1/1956

Status: Inactive **End Date:** 1/1/2005

Description: The unit is an underground, cylindrical vessel made of carbon steel. It sits inside a pump pit with a riser extending to the surface. It is surrounded with posts and chain and marked with radiological signs.

Location: The catch tank is located south of the east end of the 202-A building and west of the 241-A-151 Diversion Box. It is located inside the PUREX security fence.

Related Sites/ Structures: The site is associated with the 241-A-151 Diversion Box. The drain line to this catch tank is V028.

Process Description: The tank received excess process effluent and leaks from the 241-A-151 Diversion Box.

Waste Type: Process Effluent

Waste Description: This unit I collected drainage from the 241-A-151 diversion box. Volumes varied according to specific plant operation. Prior to being pumped out in 1992, the tank contained 13,626 liters (3,605 gallons) of waste. In 1994, it was reported to contain 5984 liters (1583 gallons) of effluent. The 1996 report said it contained 6418 liters (1698 gallons) of waste.

Code: 200-E-65 **Classification:** Accepted

Names: 200-E-65; 202A Building Steam Condensate; Miscellaneous Stream #466 Injection Well (R) **Reclassification** None

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:** 1/1/1996

Description: The site is a 1.2 meter (4 foot) diameter concrete drain with a metal plate cover. It is flush with the ground surface. On October 15, 1998, the inside of the drain was dry.

Location: The site is located on the southeast corner of 202-A, east of railroad tunnel #1 (218-E-14). It is located inside posted boundaries sitecode 200-E-107, that has been recently stabilized and downposted to an Underground Radioactive Material area.

Related Sites/ Structures: The site is associated with the PUREX facility and 200-E-107.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The site received non-contaminated steam condensate. However, the drain is located within an area that had been posted as a Radiological Contamination Area (see sitecode 200-E-107). A radiation survey done in October 1998 did not detect any contamination.

Code: 200-E-67 **Classification:** Accepted
Names: 200-E-67; 202A Building Steam Condensate; Miscellaneous Stream #494 **Reclassification:** None
Type: Injection/Reverse Well **Start Date:**
Status: Inactive **End Date:** 1/1/1996

Description: The drain is located inside a dome shaped caisson. The dome shaped caisson is surrounded by post and chain and posted with Contamination Area signs. The dome is labeled 202-A-417.

Location: The site is located adjacent to the south wall of 202-A.

Related Sites/ Structures: The site is associated with the 202-A-417 Catch tank.

Waste Type: Steam Condensate

Waste Description: The drain is located inside a caisson that is posted as a Contamination Area.

Code: 200-E-70 **Classification:** Accepted
Names: 200-E-70; Injection Well (Q); Line #8801 Steam Condensate; Miscellaneous Stream #64 **Reclassification:** None
Type: Injection/Reverse Well **Start Date:**
Status: Inactive **End Date:** 1/1/1997

Description: The site is a 0.9 meter (3 foot) diameter drain with four holes in the cover located 2.1 meters (7 feet) east of the steam line. There are several open-ended, cut pipes. It is assumed these pipes once were connected to the drain cover. The cover is posted with Confined Space signs. On May 18, 2000, it was located inside a posted Contamination Area.

Location: The site is located south of 202A, on the east side of the railroad tunnel #1 (218-E-14).

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The drain received non-contaminated steam condensate. However, the drain had been located within a large Soil Contamination Area (200-E-107). During a site walkdown in 1998, the RCT found 10,000 disintegration per minute beta/gamma on the steam pipes and in the gravel using a hand held instrument.

Code: 200-E-71 **Classification:** Accepted
Names: 200-E-71; Injection Well (O); Line #8801 Steam Condensate; Miscellaneous Stream #63 **Reclassification:** None
Type: Injection/Reverse Well **Start Date:**
Status: Inactive **End Date:** 1/1/1997

the inside of the covered drain was inspected. The drain was dry, but rust stained.

Location: The site is located southeast of 202A, on the west side of the 218-E-14 tunnel.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The site received non-contaminated steam condensate, but is located within an area that had been posted as a Soil Contamination Area (200-E-103).

Code: 200-E-77 **Classification:** Accepted

Names: 200-E-77; Injection Well (S); Line #8801 Steam Condensate; Miscellaneous Stream #65 **Reclassification:** None

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:** 1/1/1997

Description: The site is a 1.2 meter (4 foot) diameter concrete structure with a metal cover. The structure is slightly above grade and is filled with rocks. On October 15, 1998, the inside of drain was dry.

Location: The site is located on the northeast corner of 202-A. It is located inside a posted Contamination Area (see 200-E-107).

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The site received non-contaminated steam condensate, but is located within an area that had been posted as a Contamination Area (200-E-107).

Code: 200-E-79 **Classification:** Accepted

Names: 200-E-79; Injection Well (T); Line #8801 Steam Condensate; Miscellaneous Stream #66 **Reclassification:** None

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:** 1/1/1997

Description: The site is a 0.9 meter (3 foot) diameter concrete drain under a steam line with a metal cover. There is a rusty pipe going into the drain. On October 15, 1998, the inside of the drain was dry. It was inside a posted Contamination Area.

Location: The site is located on the southeast corner of the PUREX Railroad Cut. It is inside a posted radiologically posted area known as 200-E-107.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: Although the drain received non-contaminated steam condensate, it is located inside an area that had been a posted Contamination Area (200-E-107).

Code: 200-E-84 **Classification:** Accepted

Names: 200-E-84; 202A Building Steam Condensate; Injection Well (C); Miscellaneous Stream #58 **Reclassification:** None

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:** 1/1/1996

Description: The site is a 0.9 meter (3 foot) diameter, gravel filled french drain that received steam condensate. The drain is flush with the surrounding gravel surface except for a small lip on one side. A steel drain pipe extends over the french drain.

Location: The drain is located on the west end of 202-A, under the filter banks. It is located inside a Radiological Buffer Area.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion. The silver pipe above this drain is a pressure relief valve associated with PUREX the building steam system.

Waste Type: Steam Condensate

Waste Description: The drain was installed to receive steam condensate. The Inventory of Miscellaneous Streams Report states the steam source has been eliminated and that it is a gravel filled french drain with no cover, that has a potential to receive stormwater runoff. A site walkdown in 1998 determined the pipe above the drain is a pressure relief valve associated with the PUREX building steam system. The walkdown team believes the drain is not physically located in a location that would collect stormwater runoff.

Code: 200-E-107 **Classification:** Accepted

Names: 200-E-107; Contamination Area East of PUREX; PUREX E Field **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The site was a large, irregularly shaped, posted Contamination Area. The posted contamination east of the tunnels (218-E-14 and 218-E-15) extended into the double security fence. The area east of the Railroad Cut included the 216-A-32 Crib and the 2607-EE Sanitary Septic Tank and Tile Field, but ended at the inner security fence. In May 2000, a narrow corridor was

considered a Radiological Buffer Area and separated the northern portion of the Contamination Area from the southern portion. Both sections are considered to be one waste site. The entire area was stabilized and reposted an Underground Radioactive Material Area in 2001.

Location: The site was the posted Contamination Areas located on the east side of the PUREX tunnels and east of the RR Cut, inside the PUREX facility fence. The area was stabilized and reposted as an Underground Radioactive Material area.

Related Sites/ Structures: The site is associated with the 202-A facility, the 2607-EE septic system and the 216-A-32 crib.

Process Description: Residual surface contamination exists from years of PUREX facility operations. It is not attributed to a single contamination event.

Waste Type: Soil

Waste Description: The ground around the PUREX facility was contaminated from various sources during years of operation activities.

Code: 2607-EE **Classification:** Accepted

Names: 2607-EE; 2607-EE Septic System **Reclassification:** None

Type: Septic Tank **Start Date:** 1/1/1956

Status: Inactive **End Date:**

Description: The site is a septic tank with a drain field extending northeast of the septic tank. The area is surrounded with light duty posts and chain. One riser pipe is visible.

Location: The septic tank is located northeast of 202-A, east of the railroad cut, inside the PUREX exclusion fence.

Related Sites/ Structures: The site is associated with the 202-A facility and the 200-E-107 stabilized area.

Waste Type: Sanitary Sewage

Waste Description: The unit received sanitary wastewater and sewage from the PUREX facility. The source area is in a potentially contaminated zone; therefore, the waste has the potential of being contaminated.

Code: UPR-200-E-28 **Classification:** Accepted

Names: UPR-200-E-28; Contamination Release Inside the PUREX Exclusion Area; UN-200-E-28 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1961

Status: Inactive **End Date:**

Description: This release occurred in the eastern half of the PUREX exclusion area. The exclusion area is posted as a Contamination Area. The release can not be individually distinguished within the zone.

Location: Contamination spread to the eastern half of the PUREX exclusion area.

Release Description: On November 30, 1961, a general spread of low-level contamination to the eastern half of the PUREX exclusion area occurred. Fission products escaped from a trap pit because of failures in a process vessel steam coil and in the trap pit piping.

Related Sites/ Structures: The surface contaminated areas inside the PUREX facility fence were surface stabilized in 1999 and 2001. See WIDS sitecodes 200-E-103 and 200-E-107.

Waste Type: Process Effluent

Waste Description: Fission product specks were released from a PUREX trap pit due to process vessel steam coil failures.

Code: UPR-200-E-39 **Classification:** Accepted

Names: UPR-200-E-39; Release from 216-A-36B Crib Sampler (295-A); UN-200-E-39 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1968

Status: Inactive **End Date:**

Description: The release site is not separately marked or posted. It is located inside a large surface stabilized area known as 200-E-103 that is posted as an Underground Radioactive Material area.

Location: The site release occurred on the ground and blacktop area outside the 216-A-36B Crib Sampler Shack (#295-A). The sample shack is located inside the PUREX Exclusion fence, south of 202-A, adjacent to the west side of the PUREX Storage Tunnel.

Release Description: On February 6, 1968, pressurized ammonia scrubber liquid was found to be spewing from the vent filter at the 216-A-36B Crib Sampling Shack (295-A). The contaminated ammonia scrubber water erupted through the vent and filter and onto the ground around the outside of the sample shack. Approximately 60.4 square meters (650 square feet) of ground and blacktop was affected. Contamination levels ranged from 20 to 450 millirad/hour. The cause was determined to be that the export pressure was too high, resulting in back-pressure through the vent.

Related Sites/ Structures: The site is associated with 216-A-36 Crib, the 295-A Sample Shack and 200-E-103.

Waste Type: Process Effluent

Waste Description: The site received pressurized PUREX ammonia scrubber waste containing fission products. The readings were 20 to 450 millirad/hour.

Code: UPR-200-E-96 **Classification:** Accepted

Names: UPR-200-E-96; Ground Contamination SE of PUREX; UN-200-E-96; UN-216-E-24 **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The site was described in 1980 as an area measuring approximately 1.0 hectare (2.5 acres) located adjacent to the east and south sides of 202-A (PUREX). These areas are now covered with gravel and posted as Underground Radioactive Material areas.

Location: The release site include contaminated areas on the south and east sides of PUREX.

Release Description: From a conversation with Harold Maxfield on October 8, 1981, it was determined the area had become contaminated by residual specks from the operation of the 291-A Stack and work activities in the 241-A-151 diversion box during the operational years of the PUREX Plant.

Related Sites/ Structures: The release site is associated with 200-E-103, 200-E-107, the 291-A Stack and the 241-A-151 Diversion Box.

Waste Type: Process Effluent

Waste Description: The release consisted of low-level radioactive particles resulting from PUREX operations, most likely fall out from the 291-A stack and diversion box activities.

200-CR-1

Code: 202-S **Classification:** Accepted
Names: 202-S; 202-S REDOX; S Plant **Reclassification:** None
Type: Process Unit/Plant **Start Date:** 1/1/1952
Status: Inactive **End Date:** 1/1/1967

Description: The 202-S Building is one of the five canyon buildings. The inactive waste management unit is a large reinforced concrete structure. The canyon's processing areas and equipment are contained in small rooms called cells. The nine cells are arranged in rows that are spanned by a large crane. Each cell is topped by a thick, concrete cover. This cover is removed by the crane, allowing access to the underlying cells. The gallery above the cell cover is the same height as the cell, allowing process equipment to be manipulated during maintenance and operations.

Location: The 202-S Building is located in the southern portion of the 200 West area just north of the 222-S Laboratory.

Related Sites/Structures: Structures associated with this facility include the 200 West Tank Farms, 202-S process equipment, 211-S Tank Farms, the S-Plant (216-S) Cribs, Ditches, and Trenches, and multiple underground waste transfer lines and process sewers.

Process Description: The Reduction Oxidation (REDOX) Facility was used to extract plutonium and uranium from fuel rods irradiated at the Hanford Site reactors. The REDOX process employed an organic solvent extraction process that used methyl isobutyl ketone to separate uranium and plutonium from each other and the fission products in the fuel rod.

Waste Type: Equipment

Waste Description: The unit contains solid radioactive waste.

This Site has the Following SubSites:

Code: 202-S:1
Names: 202-S:1; 211-S Tank Farm

Code: 202-S:1 **Classification:** Accepted
Names: 202-S:1; 211-S Tank Farm **Reclassification:** None
Type: Process Unit/Plant **Start Date:**
Status: Inactive **End Date:**

Description: The 211-S Tank Farm is located west of the 202-S canyon building. It was a liquid chemical storage area. The tank farm consists of eight above ground steel storage tanks ranging from 16,430 liters (4300 gallons) to 186,200 liters (49,000 gallons). The tanks held nitric nonahydrate, nitric acid, sodium dichromate and sodium hydroxide. All of the tanks, pumps and piping were flushed and emptied when the REDOX facility was deactivated. The area had been posted as a Contamination Area due to migration of contamination from nearby contaminated processes and Surface Contamination Areas. The 211-S Tank Farm was covered with a minimum of 15.24 centimeters of clean gravel in November 2002. The area was downposted as an Underground Radioactive Material Area.

The SubSite is Part Of:

Code: 202-S
Names: 202-S; 202-S REDOX; S Plant

Code: 2904-S-170 **Classification:** Accepted
Names: 2904-S-170; 2904-S-170 Control Structure; 2904-S-170 Weir Box **Reclassification:** None
Type: Control Structure **Start Date:** 1/1/1954
Status: Inactive **End Date:** 1/1/1976

Description: The 2904-S-170 Control Structure is an inactive, below grade concrete structure. From the surface it can be identified by four metal posts surrounding the site. It is posted with Underground Radioactive Material signs. Two 76 centimeter (30 inch) diameter vitrified clay pipes provided inlet and outlet underground access to the structure. The 2904-SA sample building is located over the south end of the weir structure. A manhole and a riser are visible adjacent to the 2904-SA building.

Location: The site is located southwest of the 202-S canyon facility, near the southwest corner of the 211-S tank farm.

Related Sites/ Structures: The weir is associated with the 200-W-152-PL pipeline, the 2904-SA sample building, the 202-S facility and the liquid effluent disposal sites.

Process Description: The unit was built to regulate and measure the process waste flow from the REDOX facility before routing the effluent to liquid waste disposal sites.

Waste Type: Process Effluent

Waste Description: This unit contains low-level contaminated concrete and piping. The quantity of contaminated waste has not been determined. There is beta/gamma smearable contamination and penetrating radiation present. Contamination was derived from the effluents traveling through the unit.

Code: 218-W-7 **Classification:** Accepted
Names: 218-W-7; 222-S Vault **Reclassification:** None
Type: Burial Vault **Start Date:** 1/1/1952
Status: Inactive **End Date:** 1/1/1960

Description: The waste site is a carbon steel burial vault. The outer surface of the vault is coated with a layer of hot coal tar enamel to prevent corrosion, 4.3 meters (14 feet) deep, resting on a 0.3-meter (1-foot) concrete foundation. The vault has a dome and vent structure that extends 3.2 meters (10.5 feet) to the surface. The ground surface is graveled, and the vent is protected by yellow metal poles and a chain with radiation zone signs.

Location: The unit is located southeast of the 222-S Building.

Related Sites/ Structures: Site UPR-200-W-137 is the contamination inside this vault, and is (in effect) a duplicate site.

Process Description: The site received dry, packaged laboratory and sampler wastes from the 222-S Building.

Waste Type: Misc. Trash and Debris

Waste Description: This vault received dry, packaged laboratory and sampler waste from the 222-S Laboratory.

Code: UPR-200-W-43 **Classification:** Accepted

Names: UPR-200-W-43; Contaminated Blacktop East of 233-S; UN-200-W-43 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1957

Status: Inactive **End Date:**

Description: The release site is no longer marked or posted. The 233-S building was demolished in 2003 and 2004.

Location: The area of contamination was located east of the 233-S building.

Release Description: A radiation zone was originally established in this area in January 1957, but was surveyed and found to be free of contamination. On February 12, 1957, a small roped area at the corner of the electrical substation east of 233-S was being surveyed for release after being decontaminated. An area of blacktop beyond the posted area was found to be contaminated with levels up to 2,000 disintegrations per minute. The Records Management Officer (RMO) day supervisor, who was observing the survey, contaminated his shoes to 1,000 disintegrations per minute. The contaminated shoes were cleaned to less than 500 disintegrations per minute and released. The cause of the contamination spread could not be determined. However, it is presumed that the contamination from inside the posted area blew out during a wind storm. In 1957, the area was posted as a Radiation Zone pending clean up.

Waste Type: Soil

Waste Description: Alpha with readings up to 2,000 disintegrations per minute was found on the black top north of REDOX and east of 233-S.

Code: UPR-200-W-56 **Classification:** Accepted

Names: UPR-200-W-56; Contamination at the REDOX Column Carrier Trench; UN-200-W-56 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1961

Status: Inactive **End Date:**

Description: The site is located inside the REDOX facility fence. It is not separately marked or posted.

Location: The contamination occurred at the REDOX Column Carrier trench (outlet) west of the 233-S Building and north of REDOX.

Release Description: On February 6, 1961, a sudden heavy rainstorm washed contamination from a papered area of an outside radiation zone into a ground recess adjacent to the zone. A grossly contaminated steel cable was being decontaminated and contamination was spread out of the radiation zone across the sloping terrain. Contamination to 30,000 counts per minute was detected over about 19 square meters (200 square feet) of the graveled surface and 4.7 square meters (50 square feet) of black top directly beneath the paper. The black top was contaminated to 80,000 counts per minute by the rainwater soaking through the seams of the paper.

Waste Type: Chemicals

Waste Description: Beta/gamma contamination was measured at the site with readings at 30,000 counts/minute on the gravel and 80,000 counts/minute on the blacktop.

Code: UPR-200-W-57 **Classification:** Accepted

Names: UPR-200-W-57; 233-S Fire; UN-200-W-57;
UPR-200-E-120 (error in area number
assignment) **Reclassification** None

Type: Unplanned Release **Start Date:** 1/1/1963

Status: Inactive **End Date:**

Description: A fire, which started in the 233-S Building, spread plutonium contamination throughout the building and to a small degree outside of the building. The release site is not physically marked or posted.

Location: The 233-S building had been located in 200 West Area, north of the 202-S building. The building was demolished in 2004.

Release Description: On November 6, 1963, a fire started in the 233-S Building. The underlying cause of the incident was not positively identified. Plutonium contamination was spread within and outside the building by smoke and firefighting operations. It took about 1.5 hours to put out the fire with dry chemical extinguishers (sodium bicarbonate). Alpha radiation levels after the fire were greater than 5 million disintegrations per minute from plutonium-contaminated materials in the soot, ashes, and in the air.

Waste Type: Ash

Waste Description: Alpha radiation levels in plutonium-contaminated materials in the soot, ashes, and in the air greater than 5 million disintegrations per minute.

Code: UPR-200-W-61 **Classification:** Accepted

Names: UPR-200-W-61; REDOX Ground
Contamination; UN-200-W-61 **Reclassification** None

Type: Unplanned Release **Start Date:** 1/1/1966

Status: Inactive **End Date:**

Description: The area is not currently marked or posted.

Location: The incident occurred outside of the REDOX Building near the southwest corner.

Release Description: On April 24, 1966, a fire hose ruptured while flushing the H-10 to 241-SX transfer line. Back flow from the transfer line contaminated an outside ground area. Readings were from 4,000 to 100,000 counts per minute over an area of about 19 square meters (200 square feet).

Waste Type: Process Effluent

Waste Description: Beta/gamma with readings from 4,000 to 100,000 counts/minute was measured at the site.

Code: UPR-200-W-96 **Classification:** Accepted

Names: UPR-200-W-96; 233-S Floor Overflow; 233-SA
Floor Overflow; UN-216-W-4 **Reclassification** None

Type: Unplanned Release **Start Date:** 1/1/1969

Status: Inactive **End Date:** 1/1/1969

Description: The release effected the floor of the 233-SA Filter Exhaust Building, the concrete pad outside the north door of the filter exhaust building, the electric motor pad, and the ground surface on the north side of the 233-SA filter exhaust building. The 233-S facility was demolished in 2003

and 2004. The release site is not specifically marked or posted.

Location: UPR-200-W-96 occurred adjacent to and directly north of the 233-S Filter House (233-SA Filter Exhaust Building).

Release Description: On January 9, 1969, plutonium-contaminated water backed up in the 233-SA Filter House drain and overflowed to a low spot on the ground directly north of the 233-S Building. Because the ground was frozen, the water could not percolate, so a pool formed. The area effected was reported as 150 square yards, which equals 125.42 square meters.

Related Sites/ Structures: UPR-200-W-96 was associated with the 233-SA Filter Exhaust Building.

Waste Type: Process Effluent

Waste Description: The release consisted of water from the filter house drain line that contained 0.1 grams (0.004 ounces) of plutonium-239. Smear samples taken of the water and surfaces involved were as follows: 1) water on the floor of the 233-SA Filter Exhaust Building was greater than 40,000 disintegrations per minute; 2) smears of the concrete pad outside the door of the filter building were 10,000 disintegrations per minute; 3) smears of the electric motor pad were 10,000 disintegrations per minute; and 4) water in the overflow pool was 600 disintegrations per minute.

200-CU-1

Code:	221-U	Classification:	Accepted
Names:	221-U; 221-U Building; 221-U Canyon Building; 276-U; U Plant	Reclassification	None
Type:	Process Unit/Plant	Start Date:	1/1/1952
Status:	Inactive	End Date:	1/1/1958

Description: The 221-U Process Canyon is a large, reinforced concrete building. It consists of twenty sections (two cells per section) with expansion joints between each section. The building is divided lengthwise into the gallery side and the canyon chemical processing side by a thick, concrete shielding wall running the full length of the building. The building contains processing equipment and tanks that supported the uranium recovery process. The canyon deck currently is used to store radioactively contaminated surplus/spare equipment. The 221-U facility is accessed through the 271-U annex, which is attached to the west side of the 221-U building.

From 2009 through 2011, the facility was prepared for decommissioning. The interior of the facility was emptied. The canyon cells were filled with grout. Ancillary equipment and structures were removed. The Interim Completion Report (DOE/RL-2011-80) provides project details.

Location: The 221-U building is located in the central portion of the 200 West Area, near the corner of 16th Street and Beloit Ave.

Related Sites/ Structures: Structures associated with 221-U Building include the 271-U Operations Services Building, the 211 tanks, 276 tanks, 222-U laboratory, 291-U stack and the 224-U Building. The URMA where 211-U and 211-UA had been located is sitecode 200-W-239.

Process Description: 221-U was used for the Uranium Recovery Process. This process extracted relatively pure uranium from the liquid waste from the bismuth phosphate plutonium separation process that was stored in the tank farm tanks. The Uranium Recover process transformed the recovered uranium into uranium trioxide powder. The bismuth phosphate process, used in T Plant and B Plant, isolated only the plutonium from the dissolved, irradiated fuel rods. The bismuth phosphate "Metal Waste" stream, containing uranium and associated the fission products, was transferred to the underground storage tanks in the tank farms. The metal waste stream contained approximately 0.5 pounds of uranium per gallon of liquid waste. The uranium bearing waste in the tank farms was recovered from the underground tanks by sluicing and transferred to 221-U for processing. Tributyl Phosphate (TBP) solvent was used to extract and decontaminate the recovered uranium from the fission products and residual plutonium. The Uranium Trioxide Plant (224-U) was used to the purified uranyl nitrate solutions and calcine into uranium trioxide powder. The operation in 224-U continued after the completion of the Uranium Recovery process ended in 1958. Different chemical separation processes were used in REDOX and PUREX that separated the uranium from the waste stream, in the form of Uranyl Nitrate, before the waste was sent to the tank farms. The Uranyl Nitrate stream from the Redox facility was sufficiently decontaminated from the fission products to permit a direct feed to the 224-U calcination facility via an aboveground pipeline. Uranyl Nitrate from PUREX was delivered to 224-U via tanker trucks. After the Uranium Recovery process ended in 1958, the U Plant canyon was used to decontaminate large pieces of process equipment. This activity was transferred to 221-T in 1961.

Waste Type: Process Effluent

Waste Description: Processing areas and equipment are contaminated with uranium and fission products. Residual chemicals remain from the uranium recovery and equipment decontamination activities.

This Site has the Following SubSites:**Code:** 221-U:1**Names:** 221-U:1; Chemical Storage Tanks; 211-U Tank Farm**Code:** 221-U:2**Names:** 221-U:2; Chemical Storage Tanks; 211-AU Tank Farm; 211-UA**Code:** 221-U:3**Names:** 221-U:3; 276-U Tank Farm; Solvent Storage Tanks**Code:** 221-U:1**Classification:** Accepted**Names:** 221-U:1; Chemical Storage Tanks; 211-U Tank Farm**Reclassification:** None**Type:** Process Unit/Plant**Start Date:****Status:** Inactive**End Date:**

Description: The aboveground features of the 211-U Tank Farm were removed in 2009. It was a bulk liquid storage area, consisting of nine aboveground storage tanks. The tanks were located on the west side of the 221-U building. Six tanks were horizontal tanks, 2.7 meter diameter, 11 meters long (9 foot diameter, 36 feet long). Three of the horizontal tanks were sodium hydroxide storage tanks, one was a demineralized water storage tank and two were considered spare tanks. Three tanks were vertical tanks, 3 meter diameter, 4.2 meters high (10 foot diameter, 14 feet high). One was a demineralized water storage tank and two were chemical make-up tanks. The bulk liquid was transferred to the 211-U tanks from rail cars or trucks. The remaining posted Underground Material Area is sitecode 200-W-239.

In 2002, only four horizontal tanks and one vertical tank remained. The area had been posted with Radiological Buffer Area/Radioactive Material Area signs. The area around the tanks was covered with clean gravel and reposted with Underground Radioactive Material signs. The remaining posted Underground Radioactive Material Area is sitecode 200-W-239.

Related Sites/ Structures: The remaining posted Underground Radioactive Material Area is sitecode 200-W-239.

The SubSite is Part Of:**Code:** 221-U**Names:** 221-U; 221-U Building; 221-U Canyon Building; 276-U; U Plant**Code:** 221-U:2**Classification:** Accepted**Names:** 221-U:2; Chemical Storage Tanks; 211-AU Tank Farm; 211-UA**Reclassification:** None**Type:** Process Unit/Plant**Start Date:****Status:** Inactive**End Date:**

Description: The aboveground features of the 211-UA (alias 211-AU) Tank Farm were removed in 2009. It consisted of sixteen aboveground storage tanks. Thirteen tanks had a capacity of 380,000 liters (100,000 gallons) each. The tanks were located on the west side of the 221-U building. Nine of these tanks were nitric acid storage tanks and four were sodium hydroxide storage tanks. Three smaller tanks 2.7 meters in diameter and 2.7 meters tall (9 feet diameter, 9 feet tall) were nitric acid sample tanks. The bulk liquid was transported to the tanks in railcars or trucks. The remaining posted Underground Radioactive Material Area is sitecode 200-W-239.

The Uranium Recovery Process at 224-U received uranyl nitrate from REDOX and PUREX. After the uranium was removed, the "reclaimed" nitric acid was stored in the 211-UA tanks. It was transferred from 224-U to 211-UA via overhead lines. The slightly radioactive nitric acid was recycled back to REDOX and PUREX. In the 1960's and 1970's it was returned to the separations facilities in railcars. It was pumped out of the 211-UA tanks into the railcars via underground lined and a pump pit. Some leakage was associated with the pumping process and caused low level radioactive contamination around the area.

The reclaimed nitric acid storage was moved from 211-UA to a holding tank within the 224-U facility in the 1980's and the railcar unloading platform was abandoned. Some residual acid and waste water, contaminated above crib release limits, continued to be stored in the 211-UA tanks. All the acid and waste water was removed from the tanks prior to being transitioned to the new Environmental Restoration Contractor in 1994. Although the tanks were emptied, the acid pump pit and underground lines had not been flushed. Leaking valves and seals and residual contamination in the pump pit caused low level radioactive contamination to spread around the tanks and railcar unloading platform. The area was posted as a Contamination Area again in the early 1990's. The lines and pump pit were flushed in 1998 and the surface contamination was covered with gravel. The area was changed to an Underground Radioactive Material Area.

In 2002, only ten tanks remained. They had been posted with Contamination Area signs. The area surrounding the tanks was covered with clean gravel and reposted with Underground Radioactive Material signs.

Related Sites/ Structures: The remaining posted Underground Radioactive Material Area is sitecode 200-W-239.

The SubSite is Part Of:

Code: 221-U

Names: 221-U; 221-U Building; 221-U Canyon Building; 276-U; U Plant

Code: 221-U:3

Classification: Accepted

Names: 221-U:3; 276-U Tank Farm; Solvent Storage Tanks

Reclassification: None

Type: Process Unit/Plant

Start Date:

Status: Inactive

End Date:

Description: The 276-U Solvent storage area consists of six tanks mounted inside a cement basin, located on the south end of the 221-U building. Tank leakage was collected in a sump that could be returned to the tanks, sent to a drum out facility or discharged to cribs. The 276-U tanks are connected to the 221-U building by the hot pipe trench in the 221-U pipe gallery. Organic make-up solutions of tributyl phosphate and diluent were stored and treated and routed to the 221-U vessels via the pipe gallery. The diluent storage tank has a (29,000 gallon) capacity. The tributyl phosphate storage tank has a (6,000 gallon) capacity. The organic receiver storage tank has a (10,000 gallon) capacity. The organic treatment storage tank has a (10,000 gallon) capacity. The organic treatment sample storage tank has a (1,300 gallon) capacity. The RAX feed storage tank has a (10,000 gallon) capacity.

Related Sites/ Structures: This area was also documented in Sitecode 276-U. 276-U is considered a duplicate of 221-U:3.

The SubSite is Part Of:

Code: 221-U
Names: 221-U; 221-U Building; 221-U Canyon Building; 276-U; U Plant

Code: 271-U **Classification:** Accepted
Names: 271-U; 271-U Building; 271-U Office Building **Reclassification:** None
Type: Office **Start Date:** 1/1/1952
Status: Inactive **End Date:**

Description: The 271-U Office Building was the office/service building constructed of a reinforced concrete foundation, floors, and pillars with pumice block walls. The four story structure (including the basement) is physically attached to the gallery side of the 221-U Canyon.

Location: The building is attached to the northern gallery side of 221-U.

Related Sites/ Structures: Structures associated with 271-U include the 221-U Canyon, other U Plant Facilities, and the shops, maintenance, and ventilation equipment in the 271-U basement.

Process Description: The building is had been used primarily for office space. Previously, the building has been used for storing contaminated equipment, craft services, process support functions and training. The third floor of the building was used for preparing chemicals and plutonium storage.

Waste Type: Chemicals

Waste Description: Residual chemicals and radionuclides may be present in some portions of this building. The contamination may be related to vermin intrusion or from processes that were conducted in this unit.

Code: 291-U **Classification:** Accepted
Names: 291-U; 291-U Fan Control House **Reclassification:** None
Type: Process Unit/Plant **Start Date:** 1/1/1945
Status: Inactive **End Date:**

Description: The building is constructed of reinforced concrete foundation and floor, concrete and block walls, and a concrete slab roof covered with asphalt and gravel, trimmed in wood. It is a one-story, one-room building with wooden doors containing the ventilation system instrumentation. Two electric fans are located outside, adjacent to the building. The fan control house is located within a larger, posted Underground Radioactive Material area, although the 291-U building and exhaust fans remain posted as Contamination Areas.

Location: The building is located east of 221-U.

Related Sites/ Structures: The 291-U-1 Stack, 291-U Stack Sand Filter (200-W-44), and 221-U Vessel Vent Pit (216-U-7) are associated with the exhaust system.

Process Description: The 291-U Complex was originally built in 1944-1945 to provide exhaust ventilation for the 221-U Canyon Building. The 221-U Building is retired, but the 291-U exhaust ventilation system still serves its original purpose and is planned to remain in operation until the 221-U Building is decommissioned.

Waste Type: Equipment

Waste Description: The instrument house has likely become contaminated from exhaust from 221-U.

Code: 291-U-1 **Classification:** Accepted
Names: 291-U-1; 291-U-1 Stack, 221-U Stack; 291-U Stack **Reclassification** None
Type: Stack **Start Date:** 1/1/1945
Status: Inactive **End Date:**

Description: The unit consists of a reinforced concrete stack, lined with acid-resistant brick resting on an octagonal, two-tiered foundation of brick and concrete. The stack is 61 meters (200 feet) high and 4.3 meters (14 feet) in diameter at the base. The stack is located within a larger Underground Radioactive Material area, although the 291-U building and exhaust fans remain posted as Contamination Areas.

Location: The stack is located east of 221-U.

Related Sites/ Structures: The 291-U Fan House, 291-U Stack Sand Filter (200-W-44), and 221-U Vessel Vent Pit (216-U-7) are associated with the exhaust system.

Process Description: The ventilation system for U-Plant was taken off line on September 15, 2011. The system was completely deactivated and final effluent samples were obtained. The stack is considered to be inactive.

The 291-U Complex was originally built in 1944-1945 to provide exhaust ventilation for the 221-U Canyon Building. The 221-U Building is retired, but the 291-U exhaust ventilation system still serves its original purpose and is planned to remain in operation until the 221-U Building is decommissioned. In April 2005, the drainage valve from the 291-U-1 stack to the 241-UX-302A catch tank was closed.

Waste Type: Chemicals

Waste Description: The air exhaust system was contaminated with radioactive particulates.

Code: 292-U **Classification:** Accepted
Names: 292-U; 292-U Stack Monitoring Station; 291-U Stack Exhaust Monitoring Building **Reclassification** None
Type: Process Unit/Plant **Start Date:**
Status: Inactive **End Date:**

Description: The 292-U building is a cement block structure.

Location: The 292-U building is located west of Beloit Ave. and south of the 291-U-1 exhaust stack.

Related Sites/ Structures: The 292-U building is associated with the 291-U-1 exhaust stack.

200-CW-1

Code: 216-A-25	Classification: Accepted
Names: 216-A-25; 216-A-25 Swamp; Gable Mountain Pond; Gable Mountain Swamp; Gable Pond	Reclassification: None
Type: Pond	Start Date: 1/1/1957
Status: Inactive	End Date: 1/1/1987

Description: The site was a large, water-filled pond that received cooling water from the Plutonium Uranium Extraction (PUREX) and B-Plant operations. The pond had a total surface area of 32 hectares (82 acres), 28 hectares (71 acres) in the main pond and a 4.4-hectare (11-acre) overflow pond. The average depth of the unit was 1.5 meters (5 feet), with a maximum depth of 3 meters (9 feet). The pond has been backfilled and surface stabilized. The backfilled pond is delineated with concrete markers and posted as Underground Radioactive Material. An additional area of soil contamination was identified in 1996, north of the west end of the overflow pond. This area was given the Waste Information Data System (WIDS) Site Code number 600-118. In 1997, the area was surface stabilized and reposted as Underground Radioactive Material, adding 3.3 hectares (8.2 acres) to the total radiologically posted area.

Location: The site is located south of Gable Mountain, north of Route 11A.

Release Description: Radiation surveys done following the F-15 Tank coil leak in June 1964 found dose rates up to 22 rads/hour at 5 centimeters (2 inches) over the inlet, and 500 millirem per hour at 5 centimeters (2 inches) along the shoreline.

Water samples ranged from 48,000 picocuries per cubic centimeter (collected in June 1964) to 12 picocuries per cubic centimeter (collected in October 1964). A task force was formed consisting of operations management personnel, process engineers, a chemist, a geologist/hydrologist, a biologist, a health physicist and a waste disposal engineer. A follow up report written in 1965 (Radiation Control of Accidentally Contaminated Seepage Ponds, RL-SA-15) determined that of the 10,000 curies of fission products released, the highest percentage of significant contaminants was niobium-95, zirconium-95, yttrium-91, strontium-89, cerium-144 and praseodymium-144. Water fowl were periodically harvested following the incident to determine the amount of external and internal contamination. External contamination on waterfowl collected at Gable Pond ranged from 100 millirem per hour (collected on June 22, 1964) to 500 counts per minute (collected on November 3, 1964). The internal strontium and cesium concentration ranged from 180,000 picocuries per gram of cesium-137 and 370 picocuries per gram of strontium (analyzed in June 1964) to 1 picocuries per gram of cesium-137 and less than detectable strontium (analyzed in November 1964).

Copper sulfate was added on two occasions to Gable Pond to eliminate algae and invertebrates following the 1964 incident in order to eliminate water fowl food sources. Three parts per billion of copper sulfate was the desired concentration.

Most of the contamination was absorbed into the pond bottom sediments. An effort was made to coat the pond bottom with bentonite clay to reduce the percolation rate and raise the liquid level of the pond one foot. Applying a uniform layer of clay was a problem. After adding six and a half tons of clay non uniformly by various methods, other solutions were sought.

In 1964, ground water samples in the vicinity (north/northeast) of Gable Pond were sampled. Analysis ranged from 49 picocuries per cubic centimeter in August 1964 to 11 picocuries per gram in October 1964. The contaminants were mostly ruthenium-103, ruthenium-106 and zirconium-niobium-95. Down gradient wells were at background levels. It was determined that groundwater contamination was not a significant problem. However, groundwater samples

collected in 1984 showed an elevated concentration of strontium-90. An Unusual Occurrence Report (#84-27) was issued and lead to the deactivation and stabilization of the pond.

Related Sites/ Structures: An outfall structure was located at the southeast corner of the unit (see H-2-3332). The pond is also associated with an overflow area known as 600-118.

Waste Type: Water

Waste Description: Until May 1958, the unit received the process cooling water from 202-A Building (Plutonium Uranium Extraction [PUREX] Plant). From May 1958 to 1960, the unit received the above plus cooling water from the contact condenser in the 241-A-431 Building. In 1960, the unit received the above plus the surface condensator cooling water in the 241-A-401 Building (A Tank Farm). From November 1967 to January 1968, the unit received the above plus the wastewater from the 284-E Powerhouse. From January 1968 to March 1969, the unit received the above plus the cooling water and steam condensate from the 244-AR Vault. In March 1969, the pipeline to the contact condenser cooling system from the 241-A-431 Building Vault was valved out. After March 1977, the unit received the above plus the 242-A Evaporator steam condensate cooling water. RHO-CD-798 shows a valve at the east end of the 216-B-2-3 Ditch connecting to PUREX Cooling Water Line to Gable Pond. The graphic is labeled "Effluent Pipelines and Transfer Capabilities for Gable Mountain and B Ponds". The B-Plant Aggregate Area Management Study Report [AAMSR] does not list B-Plant as a contributor to the Gable Pond inventory. However, WHC-SD-DD-TI-036 states that Gable Pond later served B-Plant.

Code: 216-B-3 **Classification:** Accepted

Names: 216-B-3; 216-B-3 Main Pond; 216-B-3 Swamp; B Plant Swamp; B Pond; B Swamp; B-3 Pond; West Side Overflow Pond **Reclassification:** None

Type: Pond **Start Date:** 1/1/1945

Status: Inactive **End Date:** 1/1/1994

Description: The 216-B-3 Pond has been backfilled and surface stabilized. It is marked and posted with Underground Radioactive Material Area signs and Danger - Do Not Enter signs. The main pond was roughly rectangular, with a surface area of 14 hectares (35 acres). The pond was expanded to include three additional lobes, 216-B-3A, 216-B-3B, and 216-B-3C, with areas of 4 hectares (10 acres), 4 hectares (10 acres), and 17 hectares (41 acres), respectively. The three expansion lobes are considered three separate waste sites. The expansion ponds were separate RCRA treatment, storage and disposal (TSD) units.

Location: The pond is located east of the 200 East Area perimeter fence, northeast of the 202-A Building.

Release Description: In addition to routine flows, the following process upsets have added to the inventory of the pond: UPR-200-E-32: In November 1963, a coil leak developed in the 221-B Building 6-1 Tank; UPR-200-E-34: In June 1964, a cooling coil leak developed in the F-15 process waste tank in the Plutonium Uranium Extraction (PUREX) facility; UPR-200-E-51: On 5-18-77 fifteen kilograms of cadmium was released to B Pond via the ditches; UPR-200-E-138: In March 1970, a leaking manometer sensing line from the 221-B Building 8-1 Tank.

Related Sites/ Structures: The site is associated with B Plant and PUREX operations, the 216-B-3 ditches, the 216-A-29 Ditch, 216-B-3A, 216-B-3B, 216-B-3C and the 200-E-126-PL pipeline system.

Process Description: The site received waste between April 1945 and May 1994. Prior to the construction of the 216-B-3A and 216-B-3B Expansion Ponds in 1983, an area directly west of the Main Pond served as an overflow area. The 216-B-3A and 216-B-3B Expansion Ponds were constructed to receive the increased effluent discharge from the restart of the PUREX Facility. The 216-B-3C Expansion Lobe was constructed to received the increased effluent due to the closure of Gable

Mountain Pond.

Waste Type: Process Effluent

Waste Description: Waste streams flowed from the 216-A-29 and 216-B-3-3 Ditches into the 216-B-3 Pond. Discharges to 216-B-3 via 216-B-3-3 included: 221-B Building steam condensate and process cooling water; 284-E Powerhouse water; 244-CR Vault cooling water; 244-AR Vault and 242-A Evaporator cooling water; 202-A process cooling water, condenser cooling water, and air sampler vacuum pumps seal cooling water; 241-BY Tank Farm condenser cooling water; and Waste Encapsulation Storage Facility cooling water. Discharges to 216-B-3 via 216-A-29 included 202-A chemical sewer and acid fractionator condensate. The main pond received corrosive and toxic dangerous waste from two primary sources: the regeneration of the Plutonium Uranium Extraction (PUREX) plant demineralizer columns and from spills of dangerous or mixed waste from PUREX. The spills included hydrazine, cadmium nitrate, and ammonium fluoride/ ammonium nitrate. The backwash from the regeneration of the demineralizer columns included nitric acid, sulfuric acid, sodium hydroxide, and potassium hydroxide.

Code: 216-B-3A RAD **Classification:** Accepted

Names: 216-B-3A RAD; West Expansion Lobe; 216-B-3 1st Overflow Pond; 216-B-3A Expansion Lobe Residual Radioactive Waste **Reclassification:** None

Type: Pond **Start Date:** 1/1/1983

Status: Inactive **End Date:** 1/1/1984

Description: This site is the residual radioactive contamination that remains in the 216-B-3A Pond. The RCRA Treatment, Storage and Disposal Unit associated with this pond was Clean Closed following cleanup of chemical contamination. The unit is roughly rectangular with approximately 4.5 hectares (11 acres) of surface area. It is inactive and dry. It was sampled and released from radiological controls with the exception of the percolation trench that is posted as a Soil Contamination Area. The pond was approximately 5.5 meters (18 feet) lower than the 216-B-3 Main Pond elevation. 8-millimeter (0.3-inch) plastic was placed along the slope of the pond banks and covered with gravel.

Location: The pond is located east of 200 East Area, east of the 216-B-3 Main Pond.

Release Description: In 1958, the dike on the east side of the 216-B-3 Pond broke and flooded into a ravine on the east side of the pond. The area was released from radiological controls in 1970. The area where the release occurred was later used to create the 216-B-3A Lobe of B Pond. Later, in 1984, a break in the barrier between 216-B-3A and 216-B-3B (West and East Expansion Lobes) was noted.

Related Sites/ Structures: The overflow pond is associated with UPR-200-E-14, 216-B-3, 216-B-3B and 216-B-351 Spillway.

Process Description: The 216-B-3A was constructed to receive overflow from the 216-B-3 Main Pond due to increased effluent discharge from the restart of the Plutonium Uranium Extraction (PUREX) plant. The 216-B-3A Overflow Pond was connected to the 216-B-3 Main Pond by the 216-B-351 Spillway. The spillway was designed with a manually operated slide gate in the headwall. The water flowed from the main pond, through the culvert, down a 0.61-meter (2-foot) wide, concrete-lined ditch, to a fiberglass reinforced 0.3-meter (1-foot) flume, to the overflow pond. The pond operated from October 1983 to January 1984, when the dike between the 216-B-3A and 216-B-3B ponds failed (Occurrence Report #84-02). Prior to the dike failure, the 216-B-3B Pond had never been used. All the discharge from the failed dike was contained in the 216-B-3B Pond. In response to the incident, the 216-B-3A and 216-B-3B Ponds were isolated.

Effluent flow to the 216-B-3 Main Pond was reduced. A trench was dug in the 216-B-3A Pond to increase its infiltration rate. The trench measured 182 meters (600 feet) by 9 meters (30 feet) and was 2 meters (6 feet) deep. The debris from the dike failure was removed from the 216-B-3B Pond and a series of trenches were dug to increase its infiltration rate. Both 216-B-3A and 216-B-3B Ponds were fully operational by June 1984.

Waste Type: Process Effluent

Waste Description: 216-B-3A received overflow from the 216-B-3 Main Pond. Potential sources include 221-B steam condensate and process cooling water, 284-E Powerhouse water, 244-CR, 244-AR and 242-A cooling water, 202-A process, condenser, and air sampler vacuum pump cooling water, 202-A chemical sewer, fractionator condensate, and WESF cooling water.

Code: 216-B-3B RAD **Classification:** Accepted

Names: 216-B-3B RAD; East Expansion Lobe; 216-B-3B Expansion Lobe Residual Radioactive Waste **Reclassification:** None

Type: Pond **Start Date:** 1/1/1984

Status: Inactive **End Date:** 1/1/1985

Description: The unit is roughly rectangular with approximately 4.4 hectares (11 acres) of surface area. It is dry with a small radiologically posted area (Surface Contamination) in the northwest corner of the pond. The 216-3A, 3B and 3C Expansion ponds make up a separate RCRA TSD Unit.

Location: The pond is located east of the 200 East Area perimeter fence and east of the 216-B-3 Main Pond.

Release Description: In January 1984, the dike between 216-B-3A and 216-B-3B was found to be breached in the vicinity of the overflow channel. (Unusual Occurrence Report 84-02). The channel and the supporting area were washed away. There was no effluent released beyond the pond boundaries. At the time of the release, radiological surveys of the area found it to be clean and the area was released for the repair crews. There is currently (July 1999) a small Surface Contamination Area posted in the northwest corner of the pond at a rip rap inlet. This inlet may be the "overflow channel" mentioned in the 1984 Unusual Occurrence Report, but no sketch of the release area was included with the occurrence report.

Related Sites/ Structures: The overflow pond is associated with 216-B-3, 216-B-3A and the 216-B-351 Spillway.

Process Description: The 216-B-3A and 216-B-3B were constructed to receive overflow from the 216-B-3 Main Pond due to the increased effluent discharge from the restart of the Plutonium Uranium Extraction (PUREX) plant. In January 1984, the dike between the 216-B-3A and 216-B-3B ponds failed. Prior to the dike failure, the 216-B-3B Pond had never been used. All the discharge from the failed dike was contained in the 216-B-3B Pond. In response to the incident, the 216-B-3A and 216-B-3B Ponds were isolated. Effluent flow to the 216-B-3 Main Pond was reduced. A trench was dug in the 216-B-3A Pond to increase its infiltration rate. The trench measured 182 meters (600 feet) by 9 meters (30 feet) and was 2 meters (6 feet) deep. The debris from the dike failure was removed from the 216-B-3B Pond and a series of trenches were dug to increase its infiltration rate. Both 216-B-3A and 216-B-3B Ponds were declared fully operational by June 1984. Although 216-B-3B was considered an active pond, it never received any effluent with the exception of the 216-B-3A dike failure incident. The spillway between 216-B-3A and 216-B-3b is known as 216-B-351. It consists of a 1 meter (36 inch) diameter corrugated steel culvert.

Waste Type: Process Effluent

Waste Description: With the exception of the 216-B-3A dike failure incident, the 216-B-3B Pond Lobe was never used. In 1991, a characterization borehole was drilled through the 216-B-3B Pond (well # 699-42-41B). It was drilled to a depth of 124 feet with a cable tool rig and split tube sampling. The casing was later pulled and the well was abandoned. Twenty six samples were analyzed for radionuclides (Sample numbers B00GV6 - B00GV9, B00GW0 -B00GW9, B00GX2 -B00GX8, B00GY0- B00GY2, B00GY9, B00GZ2-B00GZ8). No radioactive field readings were noted. Aliquots submitted to the onsite laboratory found no evidence of radioactive contamination. Samples were taken at intervals from depths of 1.5 to 37 meters (5 to 122 feet).

Code: 216-B-3C RAD **Classification:** Accepted

Names: 216-B-3C RAD; 216-B-3C Expansion Lobe Residual Radioactive Waste **Reclassification:** None

Type: Pond **Start Date:** 1/1/1985

Status: Active **End Date:** 1/1/1997

Description: The unit is rectangular pond with approximately 17 hectares (41 acres) of surface area. It was excavated into a very coarse gravel layer with a very high percolation rate. The pond was constructed with eight parallel north-south trenches and one east-west trench at the spillway.

Location: The site is located east of the 200 East Area Perimeter fence and southeast of the 216-B-3 Main Pond.

Related Sites/ Structures: The site is associated with the PUREX facility, 216-B-3 Main Pond and the 200 East Powerhouse Ditch.

Process Description: The 216-B-3C Pond was constructed in 1985 to accommodate the increased effluent flow that resulted from the decommissioning of Gable Mountain Pond. In 1994, when the 216-B-3-3 Ditch and the 216-B-3 Main Pond sites were decommissioned, effluent was routed directly to the 216-B-3C Pond via a pipeline. A spillway (216-B-354) consisting of two 0.76-meter (30-inch) corrugated metal pipes was designed for a maximum flow of 74,000 liters (20,000 gallons) per minute. Later, the pond was considered a contingency pond for the Treated Effluent Disposal Facility (TEDF) effluent could be diverted to 216-B-3C in the event that Pump Station 3 fails.

Waste Type: Process Effluent

Waste Description: The 216-B-3C received effluent from the 216-B-3A Overflow Pond from 1985 to 1994. In 1994, the effluent from the 216-B-3-3 Ditch was routed directly to the 216-B-3C. Effluent included water from the 200 East Powerhouse Ditch. The flow to 216-B-3C was permanently isolated on August 18, 1997.

Code: 216-S-16P **Classification:** Accepted

Names: 216-S-16P; REDOX Pond #2; 202-S Swamp #1; 202-S Swamp and Ditch **Reclassification:** None

Type: Pond **Start Date:** 1/1/1957

Status: Inactive **End Date:** 1/1/1975

Description: The pond has been backfilled and surface stabilized. It is surrounded by concrete markers and posted with Underground Radioactive Material signs. The pond consisted of four lobes separated by dikes and a leach trench that extended east from Lobe #2 toward the 216-S-17 Pond.

Location: The unit is located outside the southwest corner of the 200 West Area perimeter fence.

Release Description: UPR-200-W-47 and UPR-200-W-59 are associated with the 216-S-16 Pond.

Related Sites/Structures: The site is associated with the 216-S-16 Ditch, the 216-U-10 Pond, 216-U-9 Ditch, UPR-200-W-47 and UPR-200-W-59.

Process Description: The pond received cooling water and steam condensate discharge from the REDOX facility via the 216-S-16 Ditch and also overflow from the 216-U-10 Pond via the 216-U-9 Ditch. The 216-S-16 Pond was constructed to replace the 216-S-17 Pond and the 216-S-5 Crib.

Waste Type: Process Effluent

Waste Description: The site received process cooling water and steam condensate from the 202-S Building until June 1967. Only lobe #1 received REDOX process effluent. The 202-S Building process (REDOX) was put on standby in July 1967. After July 1967, the site received condenser and vessel cooling water from concentrator boil-down operations in the 202-S Building via the 216-S-16 Ditch and overflow from the 216-U-10 Pond via the 216-U-9 Ditch.

Code: 216-S-17	Classification: Accepted
Names: 216-S-17; REDOX Swamp; 202-S REDOX Swamp; 202-S Swamp; 216-S-1; 216-S-1 REDOX Pond No. 1	Reclassification: None
Type: Pond	Start Date: 1/1/1951
Status: Inactive	End Date: 1/1/1954

Description: This site consists of a 6.9 to 8.5 hectare (17 to 21 acre) pond. The site was interim stabilized in 1984 and posted as "Underground Radioactive Material". The original pond site was formed by creating an earthen dike approximately one meter (3.3 feet) high on the north and west sides of the site. The designated use area was approximately 23 hectares (57 acres), but photographs indicated that only 8 hectares (20 acres) were inundated at any time. The pond averaged about 0.3 meters (1 foot) deep with a maximum depth of 0.6 meters (2 feet).

Location: This site is southwest of the 202-S Building and west of the 216-S-10 Pond.

Release Description: The pond was contaminated with multiple unplanned releases of fission product contaminants from the 202-S operation. A radiological survey map (hand drawn on 10/7/52) indicated dose rates around the pond perimeter ranging from 10 to 470 millirem per hour. High dose rates were observed in the vegetation growing in the pond. In December 1952, wild water fowl were observed feeding in the grossly contaminated swamp. A duck was killed and found to have a dose rate of 100 millirem per hour. Balloons and noise makers were placed around the pond to keep the birds off the pond. In 1953, naphtha and copper sulfate were added to the pond to kill the vegetation. By February 1954, dose rates at the edge of the pond were as high as 1500 millirem per hour. CAUTIONARY NOTE: Historical radiation survey data indicates that the radioactive inventory data in this site may be larger than the estimated inventories. Do not base safety limits for any intrusive or soil-disturbing activities on estimated inventories without confirmation from site sampling or current survey readings.

Related Sites/Structures: The associated structures are the 202-S Building and the 207-S Retention Basin. The pipeline associated with the 216-S-17 pond is sitecode 200-W-152-PL.

Process Description: The site provided ground disposal of process effluent from the 202-S facility via the 207-S Retention Basin and overflow from the 216-U-10 Pond via the 216-U-9 Ditch.

Waste Type: Process Effluent

Waste Description: Until January 1953, the site received process cooling water and steam condensate from the 202-S Building. After January 1953, the site received the 202-S Building effluent and the overflow from the 216-U-10 Pond via the 216-U-9 Ditch. During April and May of 1953, solvent naphtha was utilized to kill the vegetation, but it did not work. During July 1953, copper sulfate, 2-4-D, and sodium chlorate were also used to kill vegetation. In October 1952, a steam coil failure (UPR-200-W-15) in the REDOX D-12 Waste Concentrator caused gross contamination of process cooling water, the 207-S Retention Basin and the 216-S-17 Swamp. During November 1952, another unplanned release (UPR-200-W-13) caused further contamination at the 207-S Retention Basin and the 216-S-17 Swamp. The major potential radiological contaminants of concern are cesium-137, strontium-90, and uranium-238.

Code: 216-U-9	Classification: Accepted
Names: 216-U-9; U Swamp-S Swamp Ditch; 216-U-6	Reclassification: None
Type: Ditch	Start Date: 1/1/1952
Status: Inactive	End Date: 1/1/1975

Description: The site currently appears as a dry, V shaped depression. It is not marked or radiologically posted. It appears on drawing H-2-44510 as a "Y" shaped ditch. The east fork lead to 216-S-17 Pond and the west fork lead to 216-S-16 Pond. Although historical documentation indicates the fork to the 216-S-17 pond was backfilled, a 1999 site visit noted that both forks of the ditch appear to be dry, "V" shaped excavation.

Location: The north end of the ditch begins at the southwest corner of 216-U-10 Pond and originally terminated at 216-S-17 Pond. Later, the west fork of the 216-U-9 Ditch was dug and connected to the 216-S-16 Ditch. The 216-S-16 Ditch emptied into the 216-S-16 Pond.

Release Description: UPR-200-W-139. It was documented in HW-60807 that the ditch became contaminated in September 1953.

Related Sites/ Structures: The 216-U-9 Ditch is associated with 216-U-10, 216-U-16 and 216-U-17.

Process Description: The 216-U-9 Ditch received overflow from the 216-U-10 Pond through a metal culvert under 13th Street. The overflow was originally directed to the 216-S-17 Pond via the 216-U-9 Ditch. The original ditch became contaminated in 1953, and was backfilled in 1954. The 216-S-17 Pond was also deactivated in 1954.

In 1973, the ditch was reopened and connected to 216-S-16 Pond via the 216-S-16 ditch. This is known as the 216-U-9 west fork. The new ditch utilized approximately 500 feet of the original ditch. No contamination was identified in the reopened portion of the original ditch.

Waste Type: Process Effluent

Waste Description: The site received the overflow from the 216-U-10 Pond.

Code: 216-U-10	Classification: Accepted
Names: 216-U-10; 216-U-10 Pond; 231 Swamp; U Swamp; 216-U-1	Reclassification: None
Type: Pond	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1985

Description: This site is a 12 hectare (30 acre), backfilled, surface stabilized pond. It is posted with Underground Radioactive Material signs.

Location: This site is located south of 16th Street and east of Dayton Avenue. It is west of the 241-S Tank Farm.

Related Sites/ Structures: The site is associated with the 284-W Powerhouse, 231-Z Building, 234-5Z Building, 2723-W Building, 2724-W Building, 221-U Building, 224-U Building, 231-Z Building, 241-U-110 Tank Condenser, 231-Z Laboratory, and the 242-S Evaporator facilities and UPR-200-W-104, UPR-200-W-105, UPR-200-W-106 and UPR-200-W-107. It is also associated with the 216-U-9, 216-U-14, 216-Z-1 D, 216-Z-11, and 216-Z-19 Ditches. The pipeline to the 216-U-11 trench is sitecode 200-W-169-PL.

Process Description: The site received effluents from various facilities at various times. It received steam condensate from 231-Z, 234-5Z Buildings and 231-Z Laboratory wastes via 216-Z-1, 216-Z-11 and 216-Z-19 Ditches. It received 284-W Powerhouse process cooling water, waste water from 2723-W Original Laundry/Mask Cleaning Station and the 2724-W (new) Laundry, chemical sewer wastes from 221-U Building, cooling water from 224-U Building, 241-U-110 Tank condenser and 242-S Evaporator steam condensate water via 216-U-14 Ditch. At first, the pond received effluents only from the 284-W Powerhouse and the original Laundry/Mask Cleaning facility (2723-W). No elevated levels of radioactivity were recorded during this time. When 234-5 (Plutonium Finishing Plant) began adding effluent to the pond in 1949, elevated levels of radioactivity in the pond were noted. In 1966, ARCHO reported an estimated 8 kilograms of plutonium had been released through the Z ditches, but that only an estimated 1.5 kilograms of the plutonium may have reached the 216-U-10 Pond. U Plant began to operate the Uranium Metal Recovery program in 1952. Process waste from U Plant was released to the pond through the 216-U-14 ditch. Several significant releases of cesium and strontium are known to have been released via this route during 1956 and 1957. The Uranium Oxide Facility (224-U) also began adding cooling water to the effluent in the 216-U-14 ditch. An estimated 1,500 kilograms of depleted uranium were released from this facility over 21 years of operation. Small amounts of cesium and strontium was added to the 216-U-14 ditch from the 241-SX farm condenser cooling water effluent.

Waste Type: Process Effluent

Waste Description: The large volumes of low-level wastewater and occasional isolated releases of considerably higher level, non-routine discharges have resulted in the accumulation of transuranic, fission product and activation product inventories. It is estimated that 90% of the plutonium introduced to the waste stream from Z Plant was retained in the ditches (216-Z-1, 216-Z-11 and 216-Z-19).

Code: 216-U-11	Classification: Accepted
Names: 216-U-11; 216-U-11 (New Ditch); 216-U-11 (Old Ditch); 216-U-11 Ditch; 216-U-11 Trench; 216-U-12; U Swamp Extension Ditch	Reclassification: None
Type: Ditch	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1957

Description: This site consists of a backfilled, interim stabilized ditch that is posted with "Underground Radioactive Material" signs.

Location: This site is located on the west side of 216-U-10 Pond outside the west perimeter fence of 200 West Area.

200-CW-3

Code: 200-N-3	Classification: Accepted
Names: 200-N-3; Ballast Pits	Reclassification: Interim No Action (3/17/2010)
Type: Depression/Pit (nonspecific)	Start Date:
Status: Inactive	End Date:

Description: The remedial action chosen for this waste site is No Action. Several open pits are located southwest of the (demolished) 212-P building. Each pit is approximately 12 meters across. The soil contains large amounts of gravel sized rock. Debris in the form of metal pipes, wood, electrical insulators, metal cans and rusted drums were noted inside the pit during a site visit in May 2004.

Location: The pits are located southwest of the (demolished) 212-P building. They are northwest of the intersection of two gravel roads, Deer Street and Delridge Avenue.

Waste Type: Misc. Trash and Debris

Waste Description: A 1992 site visit indicated electrical conduit and mechanical parts were visible in the bottom of the pits. A 1996 site visit found only a small amount of metallic debris in the bottom of one pit. In 2004, metal piping, electrical insulators, wood, rusted 5 gallon cans and small rusted drums were identified in the pit. It is possible there were less tumbleweeds in the pit during this visits that may have obscured some of the debris during other site visits.

Closure Info: Interim: In July 2009, focused and discrete confirmatory soil samples were collected from the 200-N-3 waste site. The analytical results were compared to the Deep and Shallow Zone Look Up Values to determine whether further remediation was required. The analytical results from the soil samples are below the applicable Look Up Values.

The sampling approach included using Radiological field screening surveys of the ground surface as a guide for focused sampling. Test pit sampling or other comparable techniques were used to sample to a depth of 15 feet. A radiological field survey was performed in each test pit (sample location) or direct push at every foot in depth. Cesium-137 or Strontium-90 was used (as appropriate) as an indicator for each sample. Based on the sampling design, the combination of the radiological surveys and samples taken from the most likely candidate locations for contamination, the characteristics of the 200-N-3 are consistent with a surface-level non-radiological debris dump site. No source of contamination or contributor exists or remains in the surrounding media. The findings from these sampling activities are considered representative of the waste site and are adequate to conclusively support a decision of no action.

Soil cleanup levels were established in the Remaining Sites ROD (EPA 1999) based on a limited ecological risk assessment. These soil cleanup levels are referred to as Look Up Values. A baseline risk assessment for the outer area will include a more complete quantitative ecological risk assessment. When complete, this risk assessment will be used to support a future final closeout decision for the 200-N-3 waste site as part of final closure of the outer area.

Code: 216-N-1	Classification: Accepted
Names: 216-N-1; 216-N-1 Covered Pond; 216-N-1 Swamp; 212-N Swamp	Reclassification: Interim Closed Out (6/3/2011)
Type: Pond	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1952

Description: The waste site has been remediated and Interim Closed Out. A portion of the north end of this pond was excavated during remediation. No chains or barriers delineated the boundaries of this site. All radiological postings were removed in 2010, following remediation of the pond. A single permanent concrete monument had marked the north end of the pond site. The concrete marker had one Underground Radioactive Material sign on it.

Location: The site is located approximately 274 meters (900 feet) south, southeast of the demolished 212-N Building.

Related Sites/ Structures: The site is associated with 212-N. The pipeline that fed the pond is sitecode 600-285-PL.

Process Description: The pond received basin overflow cooling water from the 212-N Fuel Storage Facility via an underground 46-centimeter (18-inch) diameter vitrified clay pipe (see sitecode 600-285-PL). The pond consisted of a natural depression in the natural terrain and the discharged water was dispersed by evaporation and percolation into the ground.

Waste Type: Process Effluent

Waste Description: The site received the basin overflow from the 212-N Building. The waste type is low level radioactivity.

Closure Info: Interim (6/3/2011): The selected remedy of Remove Treat and Dispose (RTD) commenced at 216-N-1 waste site on November 5, 2009 and was completed on December 29, 2009. RTD activities involved the removal and disposal of contaminated soil from the 216-N-1 waste site at the Environmental Restoration Disposal Facility (ERDF). The excavation activity was planned to occur in stages with the area of highest contaminant concentration in the center being removed first with the vertical excavation depth set at 3.1 meters (10 ft) below ground surface. Soil removal, followed by verification sampling, was planned to be performed repeatedly until the analytical data showed residual contaminant concentrations in the excavated area were below RAGs; thereby demonstrating that RAOs were attained. With the investigative sample results showing the extent of the contaminated area bounded at sample locations 2, 7 and 8, a maximum of two iterations was anticipated to be required. Ultimately, RAOs were met after only one phase of excavation followed by verification sampling. The final excavation area was 460 square meters (4,740 square feet), measured at ground surface with a slope of 1.5 to 1, to a depth of 3.1 meters (10 feet).

Radiological field screening was performed over the entire surface of the remediated area. Radiological field screening of the remediated surface and the samples collected indicated no detectable dose rates above background. Once the waste site has been backfilled and/or contoured, native plant species will be seeded in the area, as applicable.

Code: 216-N-2	Classification: Accepted
Names: 216-N-2; 216-N-2 Trench; 212-N #1 Trench; 212-N Storage Basin Crib #1; 216-N-1 Trench	Reclassification: Interim No Action (7/30/2007)
Type: Trench	Start Date: 1/1/1947
Status: Inactive	End Date: 1/1/1947

Description: The site has been evaluated and reclassified to "No Action". The site was surrounded by a light weight chain barrier and concrete markers. It was posted with "Underground Radioactive Material" warning signs. A single chain enclosed both the 216-N-2 and 216-N-3 Waste Sites.

Location: The site was located approximately 15 to 30 meters (50 to 100 feet) northwest of the 212-N Building. The trench was adjacent and parallel to the 216-N-3 Trench.

Related Sites/ Structures: The site was associated with the 216-N-3 and 212-N facility.

Process Description: The 216-N-2 Trench was constructed in 1947 to accommodate water from the fuel basin when it was drained for undefined "special testing." Per documentation, in 1952 when activities in 200-N facilities ceased, the trench was taken out of service, the overground pipeline was placed into the trench, then backfilled with clean soil.

Waste Type: Process Effluent

Waste Description: The site received the basin water and sludge from the 212-N Fuel Storage Basin when it was drained for special tests. The site was deactivated by removing the overground piping and backfilling the unit with 1.8 meters (6 feet) of clean soil. Typically practice was to place the aboveground piping in the trench prior to backfilling. The waste type is low activity.

Closure Info: Interim (7/30/2007): Due to the rocky backfill material that had previously been placed in the trench, focused, discrete samples were collected from four test pits on March 7, 2007. The samples were collected from four specific test pits [2 samples at 3 meters (10 feet) depths and 2 samples at 4.6 meters (15 feet) depths].

The site was investigated through field observations, radiological screening, and focused sampling and analysis for the purpose of determining if hazardous or radiological contaminants were present. To confirm the conceptual model of removal, treatment and disposal or No Action, an investigation of the site was performed.

During the excavation and sampling of the test pits, radiological field surveys were conducted on each excavator bucket of soil utilizing a cesium 137 tracer (i.e., indicator) to determine the presence of radiological contamination. The contaminants of concern (COCs) for the site were identified based on existing information for the site and the COCs listed in the Remaining Sites ROD. The COC list included: americium 241, cobalt 60, cesium 137, europium 152, europium 154, europium 155, tritium, strontium 90, plutonium 238, plutonium 239/240, nickel 63, thorium 232, technetium 99, uranium 233/234, uranium 235, uranium 238, hexavalent chromium, mercury, lead, barium, trivalent chromium, cadmium, antimony, arsenic, manganese, zinc, and polychlorinated biphenyls.

The analytical results from the test pit soil sampling were shown to be below the Look Up Values, the RAGs and the RAOs and met the cleanup objectives for direct exposure, groundwater protection, and river protection. The RSVP does not discuss the status of the pipeline that was thought to have been disposed in the trench. All analytical data were found acceptable for decision making purposes and were stored in the Hanford Environmental Information System. The data was also summarized in Appendix E of the RSVP.

These results show that residual soil concentrations support future land uses that can be represented (or bounded) by a rural residential scenario. The results also demonstrated that residual contaminant concentrations support unrestricted future use of shallow zone soil [i.e., surface to 4.6 meters (15 feet)] and that contaminant levels remaining in the soil were protective of groundwater and the Columbia River. There was no deep zone for the site therefore, no institutional controls were required.

In accordance with this evaluation, the sampling results support a reclassification of the site to "No Action", as recorded on Waste Site Reclassification Form 2007-016. According to the RSVP the site will be revegetated with native grasses and regraded in accordance with the RD/RAWP.

Code: 216-N-3

Classification: Accepted

Names: 216-N-3; 216-N-3 Trench; 212-N #2 Grave; 212-N #2 Trench; 212-N Storage Basin Crib #2; 212-N-2 Trench

Reclassification Interim No Action (7/30/2007)

Type: Trench

Start Date: 1/1/1952

Status: Inactive

End Date: 1/1/1952

Description: The site has been evaluated and reclassified to "No Acton". The site was surrounded by a light weight chain barrier and concrete markers. It was posted with Underground Radioactive Material signs. Both the 216-N-2 and 216-N-3 trenches were located within the chained barrier.

Location: The site was located approximately 15 to 30 meters (50 to 100 feet) northwest of the 212-N Building. The trench was adjacent and parallel to the 216-N-2 Trench. A single lightweight chain barrier enclosed both trenches.

Related Sites/ Structures: The site was associated with the 212-N Fuel Storage Facility and co-located with the 216-N-2 trench.

Process Description: In 1952 when activities in the 200-N facilities ceased, the fuel storage basins of each of the 212 Buildings were rinsed clean to remove sludge and residual water. About 7.6 x 10⁶ Liters of sludge/water was pumped into the 216-N-3, 216-N-5, and 216-N-7 Trenches located northwest of each facility via temporary pipelines. The trenches were 3 to 6 meters (10 to 20 feet) wide and 15 to 24 meters (50 to 80 feet) long. When the trenches were taken out of service, the overground pipelines were placed into the trench and the units were backfilled with clean soil. Each building has been used since for storage of contaminated waste or materials, but no additional liquid wastes have been discharged.

A limited radiological characterization of the Annual surface radiological surveys have not detected any surface contamination. Four trenches (216-N-2, 216-N-3, 216-N-5, and 216-N-7) were reported to have received minute quantities of cesium-137 and strontium-90 but no plutonium or uranium. No inventory of organic or inorganic compounds is available for these sites. HW-28471 states that the fuel storage basin at 212-N was drained in 1947 to prepare the facility for special tests that were to be conducted in the basin. There is no documentation that describes the type of special tests done at this site.

Waste Type: Process Effluent

Waste Description: The site received fuel storage basin water and sludge from the 212-N Building when the facility was shut down in 1952. The site was deactivated by removing the overground piping and backfilling the unit with 1.8 meters (6 feet) of clean soil. Typically, the above ground pipe was placed into the trench prior to backfilling. The waste type is low activity.

Closure Info: Interim (7/30/2007): Due to the rocky backfill material that had previously been placed in the trench, focused, discrete samples were collected from four test pits on March 1, 2007. The samples were collected from four specific test pits [2 samples at 3 meters (10 feet) depths and 2 samples at 4.6 meters (15 feet) depths]. An additional sample was collected at the less than 3 meter (10 foot) level that represented an elevated radiological reading (527 counts per minute with a 350 counts per minute background). No hose or piping was found during the test pit excavations.

The current site conditions as documented in the Remaining Sites Verification Package (RSVP) for the site have achieved the Remedial Action Objectives (RAOs) and the corresponding Remedial Action Goals (RAGs) as established in the Remedial Design/Remedial Action Work Plan for Select 200 North Area Waste Sites (216-N-2, -3, -5, & -7) in the 200-CW-3 Operable Unit (RD/RAWP) and the Interim Action Record of Decision for the 100-BC-1, 100-BC-2, 100-DR-1, 100-DR-2, 100-FR-1, 100-FR-2, 100-HR-1, 100-HR-2, 100-KR-1, 100-KR-2, 100-IU-2, 100-IU-6, and 200-CW-3 Operable Units (Remaining Sites ROD).

In accordance with this evaluation, the sampling results support a reclassification of the site to "No Action", as recorded on Waste Site Reclassification Form 2007-017. According to the RSVP the site will be re-vegetated with native grasses and re-graded in accordance with the RD/RAWP.

Code:	216-N-4	Classification:	Accepted
Names:	216-N-4; 216-N-4 Swamp; 212-P Swamp; 216-N-2	Reclassification	Interim Closed Out (6/3/2011)
Type:	Pond	Start Date:	1/1/1944
Status:	Inactive	End Date:	1/1/1952
Description:	The waste site has been remediated and Interim Closed Out. The site had been marked by "Underground Radioactive Material" warning signs attached to concrete AC-540 marker posts that surround the site. The radiological postings were removed in September 2010.		
Location:	The site was located approximately 274 meters (900 feet) south-southeast of the demolished 212-P Building.		
Related Sites/ Structures:	The pond received basin overflow cooling water from the 212-P Storage Facility via an underground 46 centimeter (18-inch) diameter vitrified clay pipe (sitecode 600-286-PL).		
Process Description:	The pond consisted of a natural depression in the terrain and the discharged water was dispersed by evaporation and percolation into the ground. Except for an occasional berm, no excavation or other effort was made to define or enhance the pond formation.		
Waste Type:	Process Effluent		
Waste Description:	The site received the basin overflow waste from the 212-P Building. The waste is low activity.		
Closure Info:	Interim (6/3/2011): Investigative sampling was performed May 22 through June 2, 2009. Twenty sample locations were identified. Sample locations 1, 2, 3, 9, 12, 15, and 20 were targeted because they are located in the influent stream portion of the pond (lowest elevation) to define the extent of downgradient contamination from the point source. Sample locations 4 through 8, 10, 11, 17, and 19 were targeted to define the lateral extent of contamination from the influent stream area. Radiological indicators (dose rate readings above background) were found at seven locations: sample locations 1, 3, 2, 9, 12, 15, and 20. Contaminants at all other sample locations were below Look-Up Values. The results from the first phase of investigative sampling effectively identified and bounded the extent of the contaminated area to be subject to Remove, Treat, Dispose (RTD). This reduced the excavation area to an area of 8,011 square meters (86,229.68 square feet). RTD commenced at 216-N-4 waste site in December 2009 and was completed in July 2010. RTD activities involved the removal of contaminated soil from the 216-N-4 waste site and disposal at the Environmental Restoration Disposal Facility (ERDF). The final excavation footprint was 7,430 square meters (79,975.85 square feet) measured at ground surface with a slope of 1.5 to 1.0.		

Code:	216-N-5	Classification:	Accepted
Names:	216-N-5; 216-N-5 Trench; 212-P Grave; 212-P Storage Basin Crib; 212-P Trench	Reclassification	Interim Closed Out (7/19/2007)
Type:	Trench	Start Date:	1/1/1952
Status:	Inactive	End Date:	1/1/1952

- Description:** The site has been remediated and "Interim Closed Out". Prior to remediation the site was surrounded by a light weight chain barrier and concrete markers. It was posted with "Underground Radioactive Material" warning signs.
- Location:** The site was located approximately 30 meters (100 feet) northwest of the 212-P Building.
- Related Sites/ Structures:** The site was associated with the 216-N-2 Trench, 216-N-3 Trench and 212-N facility.
- Process Description:** In 1952 when activities in the 200-N facilities ceased, the fuel storage basins of each of the 212 Buildings were rinsed clean to remove sludge and residual water. About 7.6 x 10⁶ Liters of sludge/water was pumped into the 216-N-3, 216-N-5, and 216-N-7 Trenches located northwest of each facility via temporary pipelines. The trench was 3 to 6 meters (10 to 20 feet) wide and 15 to 24 meters (50 to 80 feet) long. When the trench was taken out of service, the overground pipeline was placed into the trench and the units were backfilled with clean soil. Each building has been used since for storage of contaminated waste or materials, but no additional liquid wastes have been discharged.

A limited radiological characterization of the Annual surface radiological surveys have not detected any surface contamination. Four trenches (216-N-2, 216-N-3, 216-N-5, and 216-N-7) were reported to have received minute quantities of cesium-137 and strontium-90 but no plutonium or uranium. No inventory of organic or inorganic compounds was available for these sites. The HW-28471 document states that the fuel storage basin at 212-N was drained in 1947 to prepare the facility for special tests that were to be conducted in the basin. There was no documentation that described the type of special tests done at this site.

- Waste Type:** Process Effluent
- Waste Description:** The site received the basin water and sludge cleanout from the 212-P Basin during shutdown of the area. Typically, the above ground piping was placed in the trench prior to backfilling. The waste type is low activity.
- Closure Info:** Interim: The site was investigated through field observations, radiological screening, and focused sampling and analysis for the purpose of determining if hazardous or radiological contaminants were present. Although not required by the Remaining Sites ROD, a comparison against ecological risk screening levels was made for the site contaminants of concern. Screening levels were not exceeded for the site constituents. A baseline risk assessment for the river corridor portion of Hanford began in 2004, which included a more complete quantitative ecological risk assessment. That baseline risk assessment will be used to support a future final closeout decision for the site.

Geophysical survey data indicated a northwest southeast trending feature that had the characteristics typically associated with soil that has been disturbed by excavation or trenching. The disturbed area was roughly six meters (20 feet) wide, 22 meters (72 feet) long, and two meters deep. The northwest end of the area was not distinct but appeared to be slightly outside of the monuments surrounding the trench. There were no concentrations of buried debris or piping identified in the disturbed area. A very large boulder that could not be moved or broken up was identified as the only notable anomaly within the trench boundaries. While awaiting the analytical results, all soil was placed back into the excavated trench, and the area was stabilized.

Remediation of the site began on April 30, 2007 and was completed on May 11, 2007. A total of approximately 1,288 metric tons (1,420 tons) of contaminated material was excavated and disposed at the Environmental Remediation Disposal Facility. The excavation was approximately 316 square meters (3,360 square feet) in area at the top of the excavation with a 1.5 to 1 slope down to 4.6 meters (15 feet).

For the sampling effort, field screening was used to establish site radiological contamination

levels. In addition, field screening for radiological contamination (cesium-137) was used as a "tracer" (i.e., indicator) to locate areas of chemical contamination. When field screening results indicated the presence of radiological contamination, the areas were further characterized with laboratory analytical samples. The post remediation sampling and analysis results indicated achievement of compliance with the RAOs and the RAGs identified in the Remaining Sites ROD and the RD/RAWP. After remediation the waste site was radiologically screened and sampled on May 16, 2007. Laboratory analysis was performed to verify that remediation was complete.

Code: 216-N-6	Classification: Accepted
Names: 216-N-6; 216-N-6 Swamp; 212-R Swamp	Reclassification: Interim Closed Out (6/3/2011)
Type: Pond	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1952

Description: The waste site has been remediated and Interim Closed Out. The site had been marked with "Underground Radioactive Material" warning signs attached to concrete AC-540 marker posts. The postings were removed after remedial activities were completed.

Location: The site was located in the 200 North Area, north of Route 11A. It was approximately 274 meters (900 feet) southeast of the 212-R Building.

Related Sites/ Structures: The site is associated with the 212-R building and its connecting underground pipeline (sitecode 600-287).

Process Description: The site received contaminated fuel basin overflow cooling water from the 212-R Storage Facility via an underground 46-centimeter (18-inch) diameter vitrified clay pipe. The pond consisted of a natural depression in the terrain. Water discharged from the 212-R building was dispersed by evaporation and percolation into the ground. Except for an occasional berm, no excavation or other effort was made to define or enhance the pond formation. A report issued in 1953 documents contamination with a maximum dose rate of 50 mr/hr was observed in this swamp prior to being backfilled.

Waste Type: Process Effluent

Waste Description: The site received the normal overflow from the 212-R Fuel Storage Basin. The waste is low activity.

Closure Info: Interim (6/3/2011): The selected remedy of Remove, Treat, Dispose (RTD) commenced at 216-N-6 Waste Site in July 2010 and was completed in August 2011. RTD activities involved the removal of contaminated soil from the 216-N-6 Waste Site and disposal at the Environmental Restoration Disposal Facility (ERDF). The final excavation area was 2,584 square meters (26,625.8 square feet) measured at ground surface. Additionally, the excavation was finished with a slope of 1.5 to 1.0, to a range of depths with the base (floor) of the excavation varying from roughly 1.21 meters (4 feet) to 2.43 meters (8 feet).

Radiological field screening was performed over the entire surface of the remediated area. Due to process knowledge of comingled radiological and chemical constituents, field screening for radiological contamination was used as an indicator to locate areas of chemical contamination. The survey was performed using standard radiological survey instruments in accordance with approved practices and procedures to obtain dose and contamination measurements with sufficient sensitivity to meet cleanup levels. Radiological screening was also performed on the samples themselves during the collection of verification samples. Radiological field screening of the remediated surface and the samples collected indicated no detectable dose rates above background.

Code: 216-N-7	Classification: Accepted
Names: 216-N-7; 216-N-7 Trench; 212-R Grave; 212-R Storage Basin Crib; 212-R Trench	Reclassification: Interim Closed Out (9/11/2007)
Type: Trench	Start Date: 1/1/1952
Status: Inactive	End Date: 1/1/1952

Description: This trench has been remediated and Interim Closed Out. The trench was excavated and backfilled. It will be revegetated with native grasses. Prior to remediation, the site had been delineated with light weight chain and concrete marker posts and posted with Underground Radioactive Material signs.

Location: The remediated site was located approximately 30 meters (100 feet) northwest of the 212-R Building.

Related Sites/ Structures: The site is associated with the 212-R building.

Process Description: The site received radioactively contaminated water and sludge from the 212-R Fuel Storage Basin cleanout in 1952.

Waste Type: Process Effluent

Waste Description: The site received the water and sludge from 212-R Fuel Storage Basin clean out. The site was retired when 212-R was shut down. The waste type is low activity.

Closure Info: Interim: The 216-N-7 Waste Site was initially investigated through field observations and focused sampling and analysis for the purpose of determining if hazardous or radiological contaminants were present. The results of the focused sampling of test pits identified levels of contaminants of concern above the Remedial Action Goals (RAGs). Consequently, the trench was excavated to a depth of 4.6 meters (15 feet) to remove contaminated soil and debris for remediation of the waste site. No aboveground piping was found during the remediation activity. Remediation began on May 21, 2007 and was completed on June 21, 2007. The excavation was approximately 713 square meters (7,680 square feet) in area at the top of the excavation with a 1.5 to 1 slope down to 4.6 meters (15 feet). Approximately 2,631 metric tons (2,900 tons) of material from the site were disposed at ERDF.

Once the excavation and disposal of the contaminated soil and debris was completed, radiological field surveys were conducted utilizing a cesium-137 tracer (i.e., indicator) to confirm the removal of detectable contamination, and waste site sampling and analysis were conducted using a multi-incremental sampling design. Multi-incremental sampling was implemented on June 26, 2007. The sample results indicated that the site achieved compliance with the RAOs and the RAGs. A summary of the cleanup evaluation for the soil results against the applicable criteria was presented in Table 1 of RSVP.

Soil cleanup levels were established in the Remaining Sites ROD based on a limited ecological risk assessment. These soil cleanup levels are referred to as Look-Up Values. Although not required by the Remaining Sites ROD, a comparison against ecological risk screening levels has been made for the site contaminants of concern. Screening levels were not exceeded for the site constituents. A baseline risk assessment for the river corridor portion of Hanford began in 2004, which includes a more complete quantitative ecological risk assessment. That baseline risk assessment will be used to support a future final closeout decision for the site.

Code: 2607-N	Classification: Accepted
---------------------	---------------------------------

Names: 2607-N; 2743-N Guard House Septic Tank and Tile Field **Reclassification** Rejected (3/17/2010)

Type: Septic Tank **Start Date:** 1/1/1944

Status: Inactive **End Date:** 1/1/1952

Description: The site has been evaluated and reclassified to Rejected per form 2010-016. It is a septic tank and drain field. The tank is a rectangular, open-topped, concrete tank buried to grade level.

Location: The unit is located 6 meter (20 feet) south of the 2743-N Guard House foundation and south of the 212-N Building. The drain field lies south of the septic tank system.

Related Sites/Structures: The 2743-N Guard House was serviced by the 2607-N Septic Tank. Only the guard house foundation remains.

Process Description: The 2607-N septic tank is constructed of reinforced concrete. The tank is 1.2 meters (4 feet) long, 0.6 meters (2 feet) wide and 2.5 meters (8.25 feet) deep (inner dimensions). The tank had a design capacity of 795 liters (210 gallons) based on a user capacity of 6 persons, a flow of 132 liters (35 gallons) of sewage per capita per day, and an average detention time of 1 day. The top of the tank is at the ground surface and the tank is accessible through a 0.9-meter (3-foot) manhole.

Waste Type: Sanitary Sewage

Waste Description: The site received sanitary waste from the 2743-N Guard House.

Code: 2607-P **Classification:** Accepted

Names: 2607-P; 2743-P Guard House Septic Tank and Tile Field **Reclassification** Rejected (3/17/2010)

Type: Septic Tank **Start Date:** 1/1/1944

Status: Inactive **End Date:** 1/1/1952

Description: The site has been evaluated and reclassified to Rejected per form 2010-017. It is a septic tank and drain field. The tank is a rectangular, open-topped, soil filled concrete tank buried to grade level.

Location: The site is located south of the 2743-P Guard House foundation and south the 212-P Building. The drain field lies south of the septic tank.

Related Sites/Structures: The 2743-P Guard House was serviced by the 2607-P Septic Tank. Only the building foundation remains.

Process Description: The 2607-N septic tank is constructed of reinforced concrete. The tank is 1.2 meters (4 feet) long, 0.6 meters (2 feet) wide and 2.5 meters (8.25 feet) deep (inner dimensions). The tank had a design capacity of 795 liters (210 gallons) based on a user capacity of 6 persons, a flow of 132 liters (35 gallons) of sewage per capita per day, and an average detention time of 1 day. The top of the tank is at the ground surface and the tank is accessible through a 0.9-meter (3-foot) manhole.

Waste Type: Sanitary Sewage

Waste Description: The site received sanitary waste from the 2743-P Guard House. The 910-liter (240-gallon) septic tank appears to have been filled with soil.

Code: 2607-R	Classification: Accepted
Names: 2607-R; 2743-R Guard House Septic Tank and Tile Field	Reclassification: Rejected (3/17/2010)
Type: Septic Tank	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1952

Description: The site has been evaluated and reclassified to Rejected per form 2010-018. It is a septic tank and drain field. The tank is a rectangular, open-topped, concrete tank buried to grade level. A field surveillance done in 1998 found the tank to be mostly filled in with soil.

Location: The unit is located south of the 2743-R Guard House foundation and south of the 212-R Building. The drain field lies south of the septic tank.

Related Sites/ Structures: The 2743-R Guard House was serviced by the 2607-R Septic Tank. Only the building foundation remains.

Process Description: The 2607-N septic tank is constructed of reinforced concrete. The tank is 1.2 meters (4 feet) long, 0.6 meters (2 feet) wide and 2.5 meters (8.25 feet) deep (inner dimensions). The tank had a design capacity of 795 liters (210 gallons) based on a user capacity of 6 persons, a flow of 132 liters (35 gallons) of sewage per capita per day, and an average detention time of 1 day. The top of the tank is at the ground surface and the tank is accessible through a 0.9-meter (3-foot) manhole.

Waste Type: Sanitary Sewage

Waste Description: The site received sanitary waste from the 2607-R Guard House. The 910-liter (240-gallon) septic tank appears to have been filled with soil. An associated drain field exists.

Code: 600-285-PL	Classification: Accepted
Names: 600-285-PL; Pipeline from 212-N to 216-N-1 Pond	Reclassification: Interim No Action (10/27/2009)
Type: Radioactive Process Sewer	Start Date: 1/1/1945
Status: Inactive	End Date: 1/1/1952

Description: The waste site is an underground, 46 centimeter (18 inch) diameter, vitrified clay pipe that fed the 216-N-1 pond. A site visit in July 2010 observed the pipeline was posted with Underground Radioactive Material Pipeline signs. The Confirmatory Sampling/No Action remediation alternative was selected for this pipeline. Only a small portion of the clay pipeline was removed and pulverized for sampling. The remainder of the pipeline was left in place and the radiological postings were removed in November 2010.

Location: The pipeline is located in the 200 North Area. It extends south from the 212-N building to the 216-N-1 Pond.

Related Sites/ Structures: The pipeline is associated with the 212-N building and the 216-N-1 Pond.

Process Description: The pond received basin overflow cooling water from the 212-N Fuel Storage Facility via an underground 46-centimeter (18-inch) diameter vitrified clay pipe.

Waste Type: Process Effluent

Waste Description: The contaminants of potential concern (COPCs) for the 600-285-PL, 600-286-PL and 600-287-PL waste sites were identified based on existing information for the site and the COPCs listed

in the Remaining Sites ROD. The COPC list identified in the Sampling and Analysis Plan for Remediation of 200 North Area Waste Sites located in the 200-CW-3 Operable Unit (SAP) (DOE/RL-2007-54) includes americium-241, cobalt-60, cesium-137, europium-152, europium-154, europium-155, tritium, strontium-90, plutonium-238, plutonium-239 and 240, nickel-63, thorium-232, technetium-99, uranium-233/234, uranium-235, uranium-238, hexavalent chromium, mercury, lead, barium, trivalent chromium, cadmium, antimony, arsenic, manganese, zinc, and polychlorinated biphenyls.

Closure Info: Interim (10/27/2009): On June 3 and 9, 2009, focused, discrete samples were collected from 600-285-PL, 600-286-PL and 600-287-PL waste site outfalls. The clay pipe samples were pulverized and divided into two samples (duplicate samples). As described in the SAP, radiological screening was performed prior to and during sampling. Surveys were performed near the origins of the pipelines located at the building each pipeline serviced via a manhole and at the discharge point of the pipelines into the ponds. The culvert and pipelines radiological survey readings did not exceed background. A portion of each pipeline was removed and pulverized before analysis.

Although the Confirmatory Sampling/No Action remediation alternative was selected for pipelines in 2009 for 600-286-PL and 600-287-PL, these two clay pipelines were removed in 2010. The 600-285-PL clay pipe was not removed.

The results of the focused sampling performed per DOE/RL-2007-54, Sampling and Analysis Plan for Remediation of 200 North Area Waste Sites Located in the 200-CW-3 Operable Unit, identified no contaminants above the Remedial Action Goals (RAGs) and are in compliance with the Remedial Action Objectives (RAOs). The waste site confirmatory sampling results, reported in DOE/RL-2009-84, support a reclassification of this site to No Action. The waste site confirmatory sampling results indicate current site conditions are in compliance with the RAOs and RAGs for pipeline 600-285-PL. It was left in place.

Code:	600-286-PL	Classification:	Accepted
Names:	600-286-PL; Pipeline from 212-P to 216-N-4 Pond	Reclassification	Interim No Action (10/27/2009)
Type:	Radioactive Process Sewer	Start Date:	1/1/1945
Status:	Inactive	End Date:	1/1/1952
Description:	The waste site had been an underground, 46 centimeter (18 inch) diameter, vitrified clay pipe that fed the 216-N-4 pond. A site visit in July 2010 observed the pipeline was posted with Underground Radioactive Material Pipeline signs. Although the Confirmatory Sampling/No Action remediation alternative was selected for this pipeline, the clay pipeline was removed in 2010. The radiological posting was removed in January 2011.		
Location:	The pipeline is located in the 200 North Area. It extends south from the 212-P building to the 216-N-4 Pond.		
Related Sites/ Structures:	The pipeline is associated with the 212-P building and the 216-N-4 Pond.		
Process Description:	The pond received basin overflow cooling water from the 212-P Fuel Storage Facility via an underground 46 centimeter (18-inch) diameter vitrified clay pipe.		
Waste Type:	Process Effluent		
Waste Description:	The contaminants of potential concern (COPCs) for the 600-285-PL, 600-286-PL and 600-287-PL waste sites were identified based on existing information for the site and the COPCs listed in the Remaining Sites ROD. The COPC list identified in the Sampling and Analysis Plan for		

Remediation of 200 North Area Waste Sites located in the 200-CW-3 Operable Unit (SAP) (DOE/RL-2007-54) includes americium-241, cobalt-60, cesium-137, europium-152, europium-154, europium-155, tritium, strontium-90, plutonium-238, plutonium-239 and 240, nickel-63, thorium-232, technetium-99, uranium-233/234, uranium-235, uranium-238, hexavalent chromium, mercury, lead, barium, trivalent chromium, cadmium, antimony, arsenic, manganese, zinc, and polychlorinated biphenyls.

Closure Info: Interim (10/27/2009): On June 3 and 9, 2009, focused, discrete samples were collected from 600-285-PL, 600-286-PL and 600-287-PL waste site outfalls. The clay pipe samples were pulverized and divided into two samples (duplicate samples). As described in the SAP, radiological screening was performed prior to and during sampling. Surveys were performed near the origins of the pipelines located at the building each pipeline serviced via a manhole and at the discharge point of the pipelines into the ponds. The culvert and pipelines radiological survey readings did not exceed background. A portion of each pipeline was removed and pulverized before analysis.

Although the Confirmatory Sampling/No Action remediation alternative was selected for pipelines in 2009 for 600-286-PL and 600-287-PL, these two clay pipelines were removed in 2010. The 600-285-PL clay pipe was not removed.

The results of the focused sampling performed per DOE/RL-2007-54, Sampling and Analysis Plan for Remediation of 200 North Area Waste Sites Located in the 200-CW-3 Operable Unit, identified no contaminants above the Remedial Action Goals (RAGs) and are in compliance with the Remedial Action Objectives (RAOs). The waste site confirmatory sampling results, reported in DOE/RL-2009-84, support a reclassification of this site to No Action. The waste site confirmatory sampling results indicate current site conditions are in compliance with the RAOs and RAGs for pipeline 600-285-PL. It was left in place.

Code:	600-287-PL	Classification:	Accepted
Names:	600-287-PL; Pipeline from 212-R to 216-N-6 Pond	Reclassification	Interim No Action (10/27/2009)
Type:	Radioactive Process Sewer	Start Date:	1/1/1945
Status:	Inactive	End Date:	1/1/1952
Description:	The waste site had been an underground, 46 centimeter (18 inch) diameter, vitrified clay pipe that fed the 216-N-6 pond. A site visit in July 2010 observed the pipeline was posted with Underground Radioactive Material Pipeline signs. Although the Confirmatory Sampling/No Action remediation alternative was selected for this pipeline, the clay pipeline was removed in 2010. The radiological posting was removed in January 2011.		
Location:	The pipeline is located in the 200 North Area. It extends south from the 212-R building to the 216-N-6 Pond.		
Related Sites/ Structures:	The pipeline is associated with the 212-R building and the 216-N-6 Pond.		
Process Description:	The pond received basin overflow cooling water from the 212-R Fuel Storage Facility via an underground 46-centimeter (18-inch) diameter vitrified clay pipe.		
Waste Type:	Process Effluent		
Waste Description:	The contaminants of potential concern (COPCs) for the 600-285-PL, 600-286-PL and 600-287-PL waste sites were identified based on existing information for the site and the COPCs listed in the Remaining Sites ROD. The COPC list identified in the Sampling and Analysis Plan for Remediation of 200 North Area Waste Sites located in the 200-CW-3 Operable Unit (SAP)		

(DOE/RL-2007-54) includes americium-241, cobalt-60, cesium-137, europium-152, europium-154, europium-155, tritium, strontium-90, plutonium-238, plutonium-239 and 240, nickel-63, thorium-232, technetium-99, uranium-233/234, uranium-235, uranium-238, hexavalent chromium, mercury, lead, barium, trivalent chromium, cadmium, antimony, arsenic, manganese, zinc, and polychlorinated biphenyls.

Closure Info: Interim (10/27/2009): On June 3 and 9, 2009, focused, discrete samples were collected from 600-285-PL, 600-286-PL and 600-287-PL waste site outfalls. The clay pipe samples were pulverized and divided into two samples (duplicate samples). As described in the SAP, radiological screening was performed prior to and during sampling. Surveys were performed near the origins of the pipelines located at the building each pipeline serviced via a manhole and at the discharge point of the pipelines into the ponds. The culvert and pipelines radiological survey readings did not exceed background. A portion of each pipeline was removed and pulverized before analysis.

Although the Confirmatory Sampling/No Action remediation alternative was selected for pipelines in 2009 for 600-286-PL and 600-287-PL, these two clay pipelines were removed in 2010. The 600-285-PL clay pipe was not removed.

The results of the focused sampling performed per DOE/RL-2007-54, Sampling and Analysis Plan for Remediation of 200 North Area Waste Sites Located in the 200-CW-3 Operable Unit, identified no contaminants above the Remedial Action Goals (RAGs) and are in compliance with the Remedial Action Objectives (RAOs). The waste site confirmatory sampling results, reported in DOE/RL-2009-84, support a reclassification of this site to No Action. The waste site confirmatory sampling results indicate current site conditions are in compliance with the RAOs and RAGs for pipeline 600-285-PL. It was left in place.

Code: UPR-200-N-1	Classification: Accepted
Names: UPR-200-N-1; Unplanned Release at the 212-R Railroad Spur	Reclassification: Interim No Action (3/17/2010)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:
Description: The remediation alternative selected for this site was Confirmatory Sampling/No Action. In 2009, the only postings at UPR-200-N-1 were Contamination Area and Radiation Area postings immediately around the rail cars that remain on the rail spur.	
In 1992, the railroad track was delineated with light weight chain and posted with Surface Contamination signs and measured 91 meters (300 feet) in length. UPR-200-N-1 was the portion of the railroad track extending south from the demolished 212-R building.	
Location:	The site is located in 200 North Area, northwest of the intersection of Route 4 North and Route 11A. The site is adjacent to the 212-R building.
Process Description:	From 1944 to 1952, irradiated fuel rods were transported to 212-R from the 100 Area reactors by train in water filled cask cars. The fuel rods were transferred from the rail cars to water filled storage basins inside the building. The short lived radionuclides were allowed to decay before transporting the fuel rods to the 200 Areas for processing. From 1982 to 1986, the 212-R facility was used as a maintenance facility for radiologically contaminated rail cars in need of brake and wheel maintenance. Over time, movement and repair of contaminated rail cars caused the track to become contaminated. In 1998, two locomotives and five cask cars were being stored at this location within the Surface Contamination Area.
Waste Type:	Equipment

Waste Contaminated rail cars are stored on this railroad spur.

Description:

Closure Info: Interim (3/17/2010): In July 2009, the UPR-200-N-1 waste site was investigated using field observations and focused sampling and analysis for the purpose of determining if hazardous or radiological contaminants were present. This investigative activity was performed in accordance with Sampling and Analysis Plan (DOE/RL-2007-54) and Remedial Design/Remedial Action Work Plan for 200 North Area Waste Sites located in the 200-CW-3 Operable Unit (DOE/RL 2007-55). When the current sampling evolution began, the only postings within or near UPR-200-N-1 were Contamination Area and Radiation Area postings immediately around the rail cars that remain on the rail spur. In July 2009, the UPR-200-N-1 waste site was investigated using field observations and focused sampling and analysis for the purpose of determining if hazardous or radiological contaminants were present. This investigative activity was performed in accordance with Sampling and Analysis Plan (DOE/RL-2007-54) and Remedial Design/Remedial Action Work Plan for 200 North Area Waste Sites located in the 200-CW-3 Operable Unit (DOE/RL 2007-55). When the current sampling evolution began, the only postings within or near UPR-200-N-1 were Contamination Area and Radiation Area postings immediately around the rail cars that remain on the rail spur.

In July 2009, focused and discrete samples were collected from the UPR-200-N-1 waste site from three boreholes. The decision logic associated with judgment/focused methodology includes identifying discrete sample locations based on radiological surveys of the area. Radiological surveys in accordance with COPCs identified for this site, is an indicator of the potential presence of COPCs. Radiological surveys of greater than 90% of the surface area of the waste site (including the tracks beneath the rail cars) showed no radiation levels above background and no detectable contamination. Visual inspection showed discoloration in one location, on the east side of the rail road tracks, approximately mid way down the length of the waste site. Based on the radiological surveys, process knowledge and the visual inspection of the site, three discrete borehole samples were collected. One was collected at the north end of the waste site closest to 21 2-R, the location with the most potential for the presence contamination based on process knowledge. One was collected in roughly the middle on the east side, where discolored soil was identified and one was collected at the south end of the waste site, bounding the furthest extent of the waste site to ensure that the waste site.

Radiological surveys were conducted on the borehole contents after removal from the sample equipment to determine potential locations for obtaining discrete samples. The survey results indicated that the soil sample was below radiological background levels and based upon visual inspections, no evidence existed to support the identification of discrete sample locations. As a result, discrete samples were obtained at each borehole at the approximate midpoint (5 to 7 feet below surface) and at the 15-foot depth in accordance with the SAP.

Code: UPR-200-N-2	Classification: Accepted
Names: UPR-200-N-2; Well Pumphouse East of 212-R; 200-N-2; Unplanned Release Near Well Pumphouse No. 2	Reclassification Interim No Action (3/17/2010)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:
Description: The remedial alternative selected for this waste site was Confirmatory Sampling/No Action. The waste site was a 6.1 by 6.1-meter (20 by 20-foot) area surrounded by a lightweight chain barrier and Underground Radioactive Material warning signs. There were two open, wood lined holes with valves inside the posted area. They measured approximately 1 meter square and were approximately 1 meter deep. A site visit in July 2010 observed the area adjacent to the	

pump house foundation posted with chain and Underground Radioactive Material (URMA) signs. Another area nearby contained debris and was posted with Soil Contamination Area (SCA) signs.

In March 2011 the surface debris inside the Soil Contamination Area was removed. A Walking Stick radiological survey was done on both posted areas and found to be free of contamination. The 2009 sample results were reviewed. All the post, chains and radiological postings were removed on March 7, 2011.

- Location:** The site is adjacent to the northern Well Pump House (Well House No. 2) foundation located east of the demolished 212-R Building. The well house building was demolished in September 2004.
- Release Description:** There is no information available to explain the nature or cause of the contamination. However, on a site walkdown, done in April 2000, a Radiological Control Technician used her instrumentation to do an informal survey of the posted area. No contamination was evident on the surface of the posted area.
- Related Sites/ Structures:** The two valve boxes are associated with the well water supply system located within the barrier.
- Process Description:** The valve boxes appear to have been related to the pump house operation.
- Waste Type:** Soil
- Waste Description:** The contaminants of potential concern (COPCs) for the UPR-200-N-2 waste site were identified based on existing information for the site. COPCs are listed in the Remaining Sites ROD and carried forward to the Sampling and Analysis Plan for Remediation of 200 North Area Waste Sites located in the 200 CW 3 Operable Unit (SAP) (DOE/RL 2007-54) and include americium 241, cobalt 60, cesium 137, europium 152, europium 154, europium 155, tritium, strontium 90, plutonium 238, plutonium 239/240, nickel 63, thorium 232, technetium 99, uranium 233/234, uranium 235, uranium 238, hexavalent chromium, mercury, lead, barium, trivalent chromium, cadmium, antimony, arsenic, manganese, zinc, and polychlorinated biphenyls.
- Closure Info:** Interim: In June 2009, soil samples were collected and radiological surveys were performed on soil removed with a backhoe to a depth of 15 feet. Radiological survey readings did not exceed background levels.

The analytical results from the soil samples meet the remedial action objectives for direct exposure, groundwater protection, and river protection as specified in the Remaining Sites Record of Decision. In accordance with this evaluation, the sampling results support a reclassification of the UPR-200-N-2 waste site to No Action status, as recorded on the Waste Site Reclassification Form included with this report. Per TPA MP-14, No Action status indicates that a waste site does not require any further remedial action under RCRA Corrective Action, CERCLA, or other cleanup standards based on an assessment of quantitative data collected for the waste site as evaluated under this interim Record of Decision. This waste site and the data obtained from the subject sampling evolution will be included in the risk assessment and remedial investigation and feasibility study for final closure of this area.

200-CW-5

Code: 216-Z-1D	Classification: Accepted
Names: 216-Z-1D; Drainage Ditch to U Swamp; Z Plant Ditch; 216-Z-1	Reclassification: None
Type: Ditch	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1959

Description: The 216-Z-1D Ditch is a backfilled, surface stabilized ditch that runs from a point east of the 231-Z Building, curving southward to the 216-U-10 Pond. In 1949, the northern portion of the ditch was backfilled. The backfilled portion of the ditch was replaced with an underground pipeline (see sitecode 200-W-125-PL) to transport 231-Z effluent. The southern portion of the ditch is co-located within a large Underground Radioactive Material area that also includes the 216-Z-11 and 216-Z-19 ditches.

Location: The unit is east of 231-Z Building and runs south to the 216-U-10 Pond. The northern portion of the ditch, which had been converted to a pipeline, was shifted to the east of the original ditch.

Release Description: When the 216-Z-19 Ditch was being excavated in 1971, approximately 130 meters (425 feet) of the backfilled 216-Z-1 Ditch near the pipeline outfall was accidentally exhumed (UPR-200-W-110).

Related Sites/Structures: The 216-Z-1D Ditch is associated with 200-W-125-PL, 200-W-207-PL, the 216-Z-11 and 216-Z-19 Ditches, the stabilized 216-U-10 Pond, and the 231-Z Building outfall.

Process Description: The 216-Z-1D Ditch was used to transfer liquid waste from 231-Z, 234-5Z, and 291-Z Buildings to the 216-U-10 Pond.

The 216-Z-1D Ditch operated from 1944 to 1959. It was 1,295 meters (4,249 ft) long and 0.6 meters (2 ft) deep, with a bottom width of 1.2 meters (4 ft). The side slopes were 2.5:1. Originally, the ditch flowed from a headwall located approximately 60 meters (196 ft) east of Building 231-Z before turning south to connect to the 216-U-10 pond.

In 1949, after approximately 4 years of operations and as part of Building 234-5Z (Z Plant) construction, the north 526 meters (1,725 ft) section of this ditch was abandoned, backfilled, and replaced with process sewer piping (see WIDS 200-W-125-PL) that was routed around 234-5Z facility security fencing. A new headwall was constructed approximately 457 meters (1,500 ft) downstream where the new pipeline emptied into the remaining south portion of the ditch.

The Record of Decision - Hanford 200 Area Superfund Site 200-CW-5 and 200-PW-1, 200-PW-3 and 200-PW-6 Operable Units (ROD) states the north portion of the 216-Z-1D Ditch did not contain significant contamination when it was abandoned in 1949. The early plutonium purification process in the 231-Z Plutonium Isolation Plant that produced the 216-Z-1D Ditch waste stream was a tightly controlled process due to the high value of the concentrated plutonium product being processed. At that time, process waste streams were segregated with regard to their potential to contain plutonium. Waste streams containing a significant amount of plutonium were recycled directly back to the 224-T Concentration Facility. All other secondary waste streams having a potential to contain plutonium were sent to the 231-W-151 Sump where they were analyzed, neutralized, and either recycled back to the 224-T Concentration Facility for reprocessing. If the plutonium was not considered recoverable, it was disposed to the 216-Z-4 Trench, 216-Z-5 Crib, 216-Z-6 Crib, and/or 216-Z-10 Injection/Reverse Well. Waste containing plutonium was not expected to have been disposed to the 216-Z-1D Ditch before 1949.

The coil failures that were the major source of cooling water waste stream contamination

occurred after 1949. No reports of process-upset discharges to the 216-Z-1D (prior to 1949) have been identified. According to sample data gathered in 1981, the north portion of 216-Z-1D is significantly less contaminated than the south portion of the 216-Z-1D Ditch. Samples collected at the north end of the 216-Z-1D Ditch identified a maximum plutonium concentration of less than 70 pCi/g.

The south portion of 216-Z-1D continued to operate until 1959. It had the potential to receive cooling water waste containing constituents associated with the additional processes that occurred at the 231-Z Plutonium Isolation Plant after 1949. Open ditches were routinely surveyed for radiological contamination to control the potential spread of windblown contamination. The cooling water waste streams were not recognized as having a potential to contain plutonium.

Waste Type: Process Effluent

Waste Description: The 216-Z-1D Ditch received process cooling water, steam condensate, and pump sealant waters from the 231-Z, 234-5Z, and 291-Z Buildings. It is classified as a transuranic contaminated soil site. Plutonium and americium are the dominant radionuclides present in the ditch. The majority of the plutonium was retained in the ditch sediments and did not flow into the 216-U-10 Pond. A comparison of annual plutonium discharges for the dates when the 216-Z-1 Ditch was active indicates that at least 1.4 kilograms (3 pounds) of plutonium was released to the 216-Z-1 Ditch. The contamination burden includes 137 curies of Pu-239 and 37 curies of Pu-240. Previously, in 1959, when the entire ditch was open from its original inlet from the 234-5Z Building (before the upper 526 meters were replaced with a pipeline), a mud sampling project took three samples of the ditch sediment every 100 feet from the inlet pipe to the outlet into 216-U-10 Pond (81 samples from the Z-1D ditch, plus others from 216-U-10 Pond shoreline). The levels of plutonium ranged up to 27.1 micrograms per gram plutonium (almost all plutonium 239) at 800 feet from the inlet. The levels at 485 meters (1600 feet) from the inlet were still at 1.7 micrograms per gram plutonium. The 1959 report concluded that there was between 3 and 10 kilograms of plutonium in the ditch.

Code: 216-Z-11	Classification: Accepted
Names: 216-Z-11; 216-Z-11 Ditch; Z Plant Ditch	Reclassification: None
Type: Ditch	Start Date: 1/1/1959
Status: Inactive	End Date: 1/1/1971

Description: The 216-Z-11 ditch is a backfilled, surface stabilized ditch that ran from the east side of the 234-5Z facility southward to the 216-U-10 Pond. The ditch is currently co-located within a large, posted Underground Radioactive Material area that also includes the 216-Z-1D and 216-Z-19 ditches. When active, the unit was a long narrow ditch with 2.5:1 sloped sides and a 0.05% grade.

Location: The ditch began at a point southeast of the 241-Z tanks and ran south to the 216-U-10 Pond. The first 37 meters (120 feet) of the ditch and last 203 meters (665 feet) of the ditch reused portions of the 216-Z-1D Ditch.

Related Sites/Structures: Structures associated with this unit include the remnants of the 216-Z-1D and 216-Z-19 Ditches, UPR-200-W-110, the 216-U-10 Pond, and the culvert beneath Sixteenth street. The pipeline from 231-Z to the ditches is sitecode 200-W-125-PL. The pipeline from 234-5Z to the ditch is sitecode 200-W-207-PL.

Process Description: The 216-Z-11 Ditch was installed to replace the 216-Z-1D ditch. The 216-Z-11 ditch received liquid waste from Plutonium Finishing Plant process sewer, 291-Z and 231-Z until it was deactivated in 1971. The 216-Z-11 was replaced by the 216-Z-19 Ditch. During the 1960's, a

special Space Nuclear Auxiliary Power program was operating in Z-Plant. The program isolated plutonium-238 and released an unknown amount of plutonium 239/240 to the 216-Z-11 ditch as waste.

Waste Type: Process Effluent

Waste Description: The total volume discharged to this ditch is unknown. The ditch received process cooling water and steam condensate from the 234-5Z Building, cooling and seal water from the 291-Z Stack, and laboratory waste from 231-Z. It also received storm water from an elevated tank located south to 234-5Z. The site is a transuranic contaminated soil site. During the 1960's, a special Space Nuclear Auxiliary Power program was operating in Z-Plant. The program isolated plutonium-238 and released plutonium 239/240 to the 216-Z-11 ditch as waste. Plutonium and americium were the dominant radionuclides in the effluent discharge. The ditch has been reported to contain 137 curies of plutonium 239 and 37 curies of plutonium 240.

Code: 216-Z-19

Classification: Accepted

Names: 216-Z-19; 216-Z-19 Ditch; Z Plant Ditch; 216-U-10 Ditch

Reclassification: None

Type: Ditch

Start Date: 1/1/1971

Status: Inactive

End Date: 1/1/1981

Description: The 216-Z-19 Ditch is a backfilled, surface stabilized site. The ditch is currently co-located within a large Underground Radioactive Material area that also includes the 216-Z-1D and 216-Z-11 ditches.

Location: The ditch is an irregular site positioned in a north-south configuration. The head end is located east of the 216-Z-1A Tile Field and extends southward to the 216-U-10 Pond.

Release Description: In March of 1976, an estimated 30 to 60 grams of plutonium was accidentally released to the 216-Z-19 ditch. Soil samples collected from the ditch in March and April 1976 identified large amounts of plutonium and americium. In an effort to keep the contamination contained within the ditch, three earth dams were constructed across the ditch at intervals to impound the water and allow the contaminants to settle to the bottom. A sprinkler system was installed to keep the downstream portions of the ditch from drying and allowing contamination to spread in the wind. The dams were removed in June 1978.

Related Sites/Structures: Structures associated with this site include the remnants of the 216-Z-1D and the 216-Z-11 Ditches, the 216-U-10 Pond, the stormwater and process sewer outfalls from the Plutonium Finishing Plant, and the pipeline from 231-Z. The pipeline from 231-Z is sitecode 200-W-125-PL. The pipeline from 234-5Z to the ditch is sitecode 200-W-207-PL.

Process Description: The 216-Z-19 Ditch operated as a waste disposal/transfer line for various Plutonium Finishing Plant facilities. The ditch received effluent from the 234-5Z, the 291-Z stack, and the 231-Z Buildings. The ditch was fed by three underground process sewer pipelines that entered the head end of the ditch. The ditch was deactivated and backfilled when discharges transferred to the 216-Z-20 Crib.

Waste Type: Process Effluent

Waste Description: The unit is considered a transuranic contaminated soil site. The effluents received by this ditch include process cooling water, steam condensate, pump seal waste from Plutonium Finishing Plant, and cooling water from the 231-Z Buildings. The dominant radionuclides present include plutonium, americium, strontium, and cesium. Approximately 60 grams of plutonium was released to the ditch in March 1976.

Code: 216-Z-20	Classification: Accepted
Names: 216-Z-20; Z-19 Ditch Replacement Tile Field	Reclassification: None
Type: Crib	Start Date: 9/24/1981
Status: Inactive	End Date: 7/19/1995

Description: The site is marked and posted as an Underground Radioactive Material area. The site was permanently isolated by filling the manhole at the head end of the crib with concrete on 6/1/95.

Location: The site is located northwest of the 241-U Tank Farm. It is west of and parallel to the backfilled 216-Z-19 Ditch.

Related Sites/ Structures: The crib is associated with the 234-5 and 236 facilities. The pipeline from 234-5Z to 216-Z-20 is sitecode 200-W-207-PL. Effluent from pipeline 200-W-125-PL was also diverted to 216-Z-20.

Process Description: The crib was built to receive effluent from the Plutonium Finishing Plant facilities and the 231-Z building. It was built to replace the 216-Z-19 ditch. Although drawing H-2-92061 indicates the crib structure has varied depths of 2.7 to 8.8 meters (9 to 29 feet) below ground surface, a recent engineering review determined this to be an error. Note 10 on this drawing states there was a soil mound at this station and other areas. Backfill soil was to be leveled to maintain uniform elevation after 216-Z-20 was constructed. The crib structure varied depths are now assumed to be 2.47 to 3.87 meters (8.09 to 12.69 feet) below ground surface. Three 6 inch (15 centimeter) perforated PVC distribution pipes run the length the crib to the south end, where the pipes are capped. A set of risers (three in a row across the width of the unit) rose to a height of 0.46 meters (1.5 feet) above grade at 4 locations along the length of the unit. The unit was filled with gravel and backfilled over with soil with a side slope of 1:2.

Waste Type: Steam Condensate

Waste Description: The site has received cooling water, steam condensate, storm sewer, building drains, Hanford Engineering and Development Laboratory Radioactive Acid Digestion Test Unit (HEDL RADTU) cooling water, and chemical drains waste from the 234-5Z Building; cooling water steam condensate and laboratory drains from the 231-Z Building; and miscellaneous drains waste from 291-Z, 232-Z, and 236-Z buildings. The unit also received wastes from 2736-Z Building, (Construction Project B-246). In 1987, 70 gallons per minute of non-radioactive, thermally warm (105 degrees F), water from Z Plant was permanently diverted from the 216-Z-20 to the 216-Z-21 Seepage Basin.

Code: UPR-200-W-110	Classification: Accepted
Names: UPR-200-W-110; Contaminated Soil from 216-Z-1; UN-216-W-20 Spoil Trench	Reclassification: None
Type: Trench	Start Date: 1/1/1971
Status: Inactive	End Date: 1/1/1971

Description: The site is a one-time use waste disposal trench. The trench is the location where backfill material from the north end of the 216-Z-1 Ditch was placed following excavation for a new ditch. During construction for the 216-Z-19 Replacement Ditch, workers placed the excavated material on a spoils pile. Later that material was found to be contaminated and it was moved to the disposal trench.

The ditches and the trench have been backfilled and are co-located within an "Underground Radioactive Material" (URM) zone. This area was surface stabilized in 1982. The area is marked with concrete posts and an intermittent light chain. The site is vegetated with crested

	wheatgrass and Indian rice grass over very sandy soil. There is evidence of rodent burrowing on and adjacent to the URM area. An air monitor is on the site at the north end.
Location:	The site is east of and parallel to the north end of the 216-Z-19 and 216-Z-11 ditches in the 200 West Area.
Release Description:	On April 14, 1971, Plant Forces mistakenly dug into the contaminated backfill of the abandoned 216-Z-1 Ditch while excavating a new ditch. A portion of the abandoned 216-Z-1 ditch was uncovered before the error was discovered. An inch-thick decayed vegetation matting from the bottom of the old ditch was found to contain alpha contamination to a maximum of 100,000 disintegrations per minute. The matting was broken up during the excavation and scattered through the "spoil pile" of the new ditch. Only a trace of contamination was detected in the excavation. Work was discontinued until surveys could be completed for a proper routing of the new ditch. A sprinkler system was installed to prevent the wind from spreading contamination from the spoil pile. The new ditch (216-Z-19) was dug approximately 10.7 (35 feet) west of the original buried ditch. The 216-Z-19 was ready for water diversion as soon as the 16th Street culvert was cleaned of sludge and weeds. A 4.6 meter (15 foot) deep, 130 meters (425 feet) long burial trench was dug east of and adjacent to the 216-Z-11 ditch. A 2.1 meter (7 foot) layer of spoils material was placed in the trench and covered with 2.4 meters (8 feet) of clean soil overburden.
Related Sites/ Structures:	UPR-200-W-110 was associated with the 216-Z-1 Ditch and the 216-Z-19 Ditch. The trench (UPR-200-W-110) is within a larger Underground Radioactive Material (URM) area.
Waste Type:	Soil
Waste Description:	Decayed vegetation matting from the bottom of the 216-Z-1 Ditch was found to contain alpha contamination to a maximum of 100,000 disintegrations per minute. The 216-Z-1 Ditch was contaminated with americium and plutonium originating from process leaks contaminating the Z Plant cooling water discharge system. The contamination subsequently settled out of the water or was absorbed by aquatic plant life growing on the sides and bottom of the ditch. Radioactivity computed from soil samples taken from the spoil pile showed an alpha concentration of 0.34 nanocuries per gram of soil. This was 30 times less than the minimum 10 nanocuries per gram standard that required "packaging for recovery" plutonium burials.

200-DV-1

Code: 216-B-5 **Classification:** Accepted

Names: 216-B-5; 241-B-361 Dry Well; 241-B-361 Reverse Well; 241-B-5 Dry Well; 299-E28-29 **Reclassification:** None

Type: Injection/Reverse Well **Start Date:** 4/1/1945

Status: Inactive **End Date:** 10/1/1947

Description: The site is delineated with concrete AC-540 markers. It is posted with Underground Radioactive Material signs. The surface is covered with coarse rock.

Location: The site is located east of Baltimore Avenue, south of 216-B-9 crib. The surveyed coordinates for this well are 573781.063 (Easting) and 136732.009 (Northing).

Related Sites/ Structures: The well was connected to the 241-B-361 settling tank by a 5-centimeter (2-inch) stainless-steel inlet pipe entering 3.7 meters (12 feet) below grade.

Process Description: The 216-B-5 reverse well is the deepest Hanford reverse well and the only one to discharge waste directly to the water table. The reverse well received approximately 30,600,000 liters (8,008,000 gallons) of B Plant and 224-B waste solutions. The waste overflowed into the reverse well from the 241-B-361 settling tank, which removed the particulates. A total of 4.7 kilograms (10.3 pounds) of plutonium was discharged to the settling tank and reverse well. Half of the plutonium was retained in the settling tank. An estimated 2.15 kilograms (4.7 pounds) of plutonium overflowed into the reverse well. A water sample collected from well 299-E33-18 in September 1947 revealed alpha contamination in the groundwater (<20 x 10⁻⁷ micro curies/liter). Eleven additional wells were drilled in 1947 and 1948 to evaluate the contamination plume. The zone of groundwater contamination extended laterally 600 meters (2000 feet) from the reverse well. The reverse well was characterized again in 1980.

The unit is 92 meters (302 feet) long, composed of vertical piping with various sizes in sections measuring 41-centimeter (16-inch) piping from ground level to 4 meters (13 feet); 0.3-meter (12-inch) piping placed inside 41-centimeter (16-inch) sections, extending to 31 meters (100 feet); 25-centimeter (10-inch) piping placed inside 0.3-meter (12-inch) sections, extending to 74 meters (242 feet); 20-centimeter (8-inch) piping placed inside 25-centimeter (10-inch) sections, extending to 92 meters (302 feet) below grade. The lowest 15-meter (50-foot) section of the 20-centimeter (8-inch) pipe is perforated.

Waste Type: Process Effluent

Waste Description: Until September 1946, the site received supernatant overflow from 241-B-361 Settling Tank waste via Tank 5-6 in 221-B Building and liquid waste from 224-B Building. From September 1946 to October 1947, the site received the cell drainage and other liquid waste via Tank 5-6 in 221-B. The 224-B effluent was rerouted to the new 216-B-7A Cribs. The waste was low in salt and was neutral to basic. Approximately 2.15 kilograms (4.7 pounds) of plutonium was discharged to the reverse well.

Code: 216-B-7A&B **Classification:** Accepted

Names: 216-B-7A&B; 216-B-7B Sump; 241-B-1 and 2 Cribs; 241-B-201 Crib; 216-B-7 Crib; 216-B-7A & B; 216-B-7A Sump **Reclassification:** None

Type: Crib **Start Date:** 1/1/1946

Status: Inactive **End Date:** 1/1/1967

Description: The cribs are located beneath a larger area of scraped contaminated soil from the UPR-200-E-144 stabilization. The contaminated soil from the unplanned release area and the cribs were covered with clean backfill and posted with Underground Radioactive Material signs. The crib locations are identified with light post and chain with Cave-in Potential signs.

Location: The site is located north of 241-B Tank Farm and east of Baltimore Avenue. The cribs are approximately 8.6 meters (28.2 feet) apart. 216-B-7B is the northwest crib, and 216-B-7A is the southeast crib.

Related Sites/ Structures: The cribs are associated with 221-B, 224-B, the 241-B Tank Farm, tanks 241-B-201 through 241-B-204, and UPR-200-E-144. The pipeline that fed the cribs is sitecode 200-E-281-PL.

Process Description: The 216-B-7A and 216-B-7B site consists of two wooden cribs, placed side by side, connected by underground piping. They were originally known as the 241-B-1 and 2 cribs. Effluent drained into 216-B-7A and 216-B-7B simultaneously through a T-fitting in the pipeline from the 201-B settling tanks (241-B-201, 241-B-202, 241-B-203 and 241-B-204) located inside the 241-B Tank Farm. Process effluent from 221-B and 224-B was routed to the settling tanks from 1946 through 1967 and dispersed to the cribs. In 1951, cell drainage from 221-B was diverted to the 216-B-9 Crib. In 1954, the 224-B waste stream was diverted to the 216-B-8 Crib when the cribs exceeded their infiltration capacity. The cribs were reactivated and used intermittently from December 1954 through May 1967 when it was determined that they had reached their radionuclide capacity.

A letter written by G.L. Hanson in September 1967 states that the cribs received approximately 49 million liters (13 million gallons) of process waste from 221-B and 224-B from 1946 through 1958. These wastes contained 4300 grams of plutonium and 5400 curies of beta/gamma emitters. After 1958, the cribs received an additional 752,000 liters (198,000 gallons) of B Plant waste containing 2100 curies of beta/gamma emitters that included 14 curies of Cesium-137 and 2080 curies of Strontium-90. Cesium, cobalt, tritium and alpha contamination was detected in groundwater samples taken from well 299-E33-18 in 1967, which monitors these cribs.

Waste Type: Process Effluent

Waste Description: The site received the liquid waste from 221-B and 224-B via overflow of 201-B Settling Tanks. From September 1946 through October 1947, the cribs received waste from 224-B. From October 1947 to August 1948, the site received the 224-B waste stream plus cell drainage (tank 5-6) and other liquid waste from 221-B. From August 1948 to July 1951, the site received liquid waste from 224-B. The tank 5-6 waste was diverted to the 216-B-9 Crib. From July 1951 through December 1954, the cribs continued to receive waste from 224-B. In December 1954 the cribs exceeded their infiltration capacity and the waste was diverted to the 216-B-8 Crib. From December 1954 to October 1961, the site received Cell 5-6 drainage and equipment cleanout waste from 224-B. From October 1961 to May 1967, the site received decontamination and construction waste from 221-B. In May 1967 it was determined that the cribs has reached their radionuclide capacity and were terminated. The B Plant effluent was rerouted to the 216-B-12 Crib. The waste is low in salt, neutral to basic, and contains transuranic (TRU) fission products.

Code: 216-B-8	Classification: Accepted
Names: 216-B-8; 216-B-8TF; 241-B-3 Crib	Reclassification: None
Type: Crib	Start Date: 1/1/1948
Status: Inactive	End Date: 1/1/1954

Description: The crib and tile field are identified with concrete AC-540 monuments and posted with

Underground Radioactive Material signs. The crib is delineated with light post and chain with Cave-In Potential signs. The surface is covered with gravel.

In 1992, the 216-B-8 Crib was covered with 0.45 to 0.61 meters (1.5 to 2 feet) of uncontaminated backfill during the UPR-200-E-144 cleanup activity.

Location: The site is located north of the 241-B Tank Farm, east of Baltimore Avenue. It is north of 216-B-7A and 216-B-7B Cribs.

Related Sites/ Structures: The site is associated with 221-B, 224-B, 241-B, 200-E-45 (Health Instrument Shaft) and UPR-200-E-144. The pipeline associated with this crib is sitecode 200-E-178-PL.

Process Description: B Plant operated from April 1945 through October 1952, separating plutonium from irradiated fuel rods using the bismuth phosphate process. The first separation step removed the metal coating from the fuel rods. Next the uranium was dissolved and the plutonium was extracted. The waste from this step was called Metal Waste. This waste stream contained all of the uranium and 90% of the fission products and was stored in the single shell tanks. The extracted plutonium went through two decontamination cycles to further purify it. The first cycle waste was combined with the coating waste. It contained 10% of the fission products and 1% of plutonium. The second decontamination cycle waste contained less than 0.1% of the fission products. The first and second cycle waste were originally discharged to the single shell tanks. In 1948, due to the lack of waste storage space in the tank farms, second cycle waste stored in the tank farms began to be released to cribs.

The 216-B-8 Crib received second cycle waste from B Plant via the 241-B-110, 241-B-111 and 241-B-112 cascading tanks, located in the 241-B Tank Farm.

Waste Type: Process Effluent

Waste Description: From February 1948 through July 1951, the site received second-cycle waste supernatant from 221-B Building. In August 1948, sludge from the 241-B-104 tank was inadvertently released to the crib and the crib became plugged. The sludge contained roughly 1000 times the amount of plutonium and 5000 times the fission products as would be found in the supernate usually discharged to cribs. Acid was added to the crib in an attempt to unplug the crib. The acid did not significantly improve the crib blockage so the tile field was added to receive crib overflow. From July 1951 to December 1951, the site received the second cycle waste plus cell drainage stored in Tank 5-6 and other liquid waste from in 221-B Building. From December 1951 to December 1952, the site received decontamination and cleanup waste generated during the shutdown of 221-B and 224-B. Some documents state the pipeline to the 216-B-8 Crib was blanked and the effluent routed to 216-B-7A in December 1954. However, H-2-2928 shows the effluent was rerouted to 216-B-11 A&B. The waste is high in salt, is neutral to basic, and contains transuranic (TRU) waste and fission products.

Code: 216-B-9	Classification: Accepted
Names: 216-B-9; 216-B-9TF; 241-B-361 Crib; 5-6 Crib and Tile Field; 216-B-361 Crib	Reclassification: None
Type: Crib	Start Date: 8/1/1948
Status: Inactive	End Date: 7/1/1951

Description: The crib and tile field have been surface stabilized. It is marked and posted as an Underground Radioactive Material (URM) area. The crib is located in the south end of the posted URM area. It is separately marked and posted as a Radiologically Controlled Area, Cave-in Potential. The surface has been planted with wheat grass.

Location: The unit is south of 241-B Tank Farm, east of Baltimore Avenue.

Release Description: (UPR-200-E-7) On November 30, 1954, leakage from the waste line between 221-B and the 241-B-361 crib caused the ground to cave-in near the 241-B-361 crib. Approximately 19,000 liters (5000 gallons) of liquid was lost to the ground. The maximum dose rate observed was 1.7 rads/hour over an area covering 2.7 square meters (30 square feet). The contamination was covered and delineated with a chain fence. The area was posted with "Underground Contamination" signs.

Related Sites/ Structures: The crib is associated with 221-B and UPR-200-E-7. The pipeline associated with this crib is 200-E-195-PL and 200-E-199-PL.

Process Description: The 216-B-9 Crib and Tile Field were built to replace the 241-B-361 Settling Tank and the 216-B-5 Reverse well. The drainage waste from the B Plant 5-6W cells was rerouted directly to this crib, by-passing the 241-B-361 settling tank. The 216-B-9 crib carries an alias of 241-B-361 crib, even though the 241-B-361 tank was by-passed. A total of 18,400,000 liters of waste was discharged to the crib between August 1948 and January 1950. The waste contained approximately 95 grams (3.3 ounces) of plutonium and 2050 curies of fission products. Sludge in the waste plugged the crib and decreased its capacity. Acid was added to the crib to keep it in operation. The crib eventually became sealed with sludge and overflow into the tile field began in November 1948. Test holes were placed in the tile field to inspect its drainage. In April 1949, 7 inches of liquid was found in Test Hole #2. A sample of the liquid was analyzed and revealed 11.5 micro curies/liter of fission products and 9,000 disintegrations per minute per liter of alpha contamination. Test Hole #2 was found to be dry in October 1949. Sediment samples taken at that time revealed 152 micro curies per kilogram of fission products and 943,000 disintegrations per minute per kilogram of alpha contamination.

The unit is a wooden structure, 4.3 by 4.3 meters (14 by 14 feet) (bottom surface) by 2.4 meters (8 feet) high, located in an excavation. The timbers are 15.2 by 15.2 centimeters (6 by 6 inches). The tile field, 55.0 by 25.6 meters (180 by 84 feet), is 165 meters (540 linear feet) of 15.2-centimeter (6-inch) clay tile pipe, with each leg in a trench 1.2 meters (4 feet) wide at the bottom. Pipes are buried 3.7 meters (12 feet) deep at head and 1.8 meters (6 feet) at the other end. Above and below the pipes are 45.7 centimeters (18 inches) of gravel. Roofing felt covers the top side of the pipes. Three legs branch from each side of clay pipe, leaving at 45 degrees to the trunk. The side slope is 1:1.5.

Waste Type: Process Effluent

Waste Description: The site received cell drainage and other liquid waste via Tank 5-6 in 221-B Building. The waste is low in salt, neutral to basic, and contains transuranic (TRU) and fission products. A sample of the sediments collected in 1949 through a well casing revealed 1830 microcuries per kilogram of fission products and 14,800,000 disintegrations per minute per kilogram of alpha contamination.

Code:	216-B-11A&B	Classification:	Accepted
Names:	216-B-11A&B; 216-B-11B; 242-B-1 Crib; 216-B-11 Crib; 216-B-11A & B	Reclassification	None
Type:	French Drain	Start Date:	1/1/1951
Status:	Inactive	End Date:	1/1/1954

Description: The cribs are located beneath a larger area of scraped contaminated soil from the UPR-200-E-144 stabilization, completed in 1992. The consolidated contaminated soil was covered with clean backfill and reposted as Underground Radioactive Material. The crib locations are identified with light post and chain with Cave-in Potential signs. The cribs consists of two corrugated metal culverts that are buried vertically. The metal culverts are perforated with holes that begin 15.24 centimeters (6 inches) from the bottom of the culverts. The culverts are

9.15 meters (30 feet) long and 2.44 meters (8 feet) in diameter. They are filled with 32.13 cubic meters (42 cubic yards) of rock. The culverts are placed 18 meters (60 feet) apart and are connected with a 7.6 centimeter (3 inch) steel pipe.

Location: The cribs are located north of 241-B Tank Farm, and east of Baltimore Avenue, adjacent to the 216-B-7A&B Cribs. The 216-B-11A is the southern crib; 216-B-11B is the northern crib. The cribs are 16 meters (52.5 feet) apart.

Related Sites/ Structures: There are two pipelines associated with these cribs. See sitecodes 200-E-176-PL and 200-E-177-PL.

Process Description: The site originally received condensate waste from the 242-B Evaporator. Drawing H-2-2928 shows 216-B-8 crib waste being rerouted to 216-B-11 A&B in 1954.

Waste Type: Process Effluent

Waste Description: The site originally received condensate waste from the 242-B Evaporator. Drawing H-2-2928 shows 216-B-8 crib waste being rerouted to 216-B-11 A&B in 1954. The waste is low in salt and is neutral to basic.

Code: 216-B-35	Classification: Accepted
Names: 216-B-35; 216-B-35 Trench; 216-BX-1 Trench; 241-BX-1 Grave	Reclassification: None
Type: Trench	Start Date: 1/1/1954
Status: Inactive	End Date: 1/1/1954

Description: The 216-B-35 through 216-B-42 trenches were surface stabilized as a unit. The area is marked with concrete AC-540 posts and Underground Radioactive Material signs. The surface has been planted with wheat grass.

Location: The trench is located north of B Plant and west of the 241-BX Tank Farm.

Related Sites/ Structures: The trench is associated with 221-B and the 241-BX Tank Farm.

Process Description: In order to provide the tank space needed to support the fuel separations operations in 200 East and West Areas, first cycle supernate stored in the single shell tanks was intentionally discharged to specific retention trenches during 1953 and 1954. Specific retention disposal utilized the moisture retention capacity of the relatively dry soils above the regional ground water table. The volume of liquid disposed to each trench was limited to ten percent of the soil volume between the bottom of the trench and the groundwater table. B Plant and T Plant used the bismuth phosphate process to separate plutonium from irradiated fuel from 1944 through 1956. The first step in the process was to dissolve the metal coating from the fuel rods. The next step dissolved the uranium and extracted the plutonium. The uranium waste was known as the metal waste stream. It contained the bulk of the uranium and 90% of the cesium-137 and strontium-90. The plutonium stream went through two additional decontamination cycles to purify it, producing the first and second cycle waste streams. The first cycle waste stream contained approximately 10% of the long lived fission products and 1% of the plutonium. The coating waste was combined with the first cycle waste. The liquid waste from these processes was initially stored in the single shell tanks in tank farms. By 1948, limited space in the tank farms resulted in the decision to discharge the second cycle waste to cribs. In 1951, the 242-B and 242-T Evaporators began to concentrate the first cycle waste to reduce the volume of waste stored in the tank farms. By 1953, the need for tank space resulted in the first cycle waste that was being stored in the single shell tanks, to be discharged via overground pipelines to specific retention trenches. Some specific retention trenches received the waste from the bottoms of the

242-B and 242-T Evaporator tank or tri-butyl phosphate waste from the Uranium Recovery process.

Waste Type: Process Effluent

Waste Description: The site received first-cycle supernatant waste from 221-B Building. The waste is high in salt and is neutral to basic.

Code: 216-B-36

Classification: Accepted

Names: 216-B-36; 216-B-36 Trench; 216-BX-2 Trench; 241-BX-2 Grave

Reclassification: None

Type: Trench

Start Date: 1/1/1954

Status: Inactive

End Date: 1/1/1954

Description: The 216-B-35 through 216-B-42 trenches were surface stabilized as a unit. The area is marked with concrete AC-540 posts and Underground Radioactive Material signs. The surface has been planted with wheat grass.

Location: The trench is located north of B Plant and west of the 241-BX Tank Farm.

Related Sites/ Structures: The trench is associated with the 221-B facility.

Process Description: In order to provide the tank space needed to support the fuel separations operations in 200 East and West Areas, first cycle supernate stored in the single shell tanks was intentionally discharged to specific retention trenches during 1953 and 1954. Specific retention disposal utilized the moisture retention capacity of the relatively dry soils above the regional ground water table. The volume of liquid disposed to each trench was limited to ten percent of the soil volume between the bottom of the trench and the groundwater table. B Plant and T Plant used the bismuth phosphate process to separate plutonium from irradiated fuel from 1944 through 1956. The first step in the process was to dissolve the metal coating from the fuel rods. The next step dissolved the uranium and extracted the plutonium. The uranium waste was known as the metal waste stream. It contained the bulk of the uranium and 90% of the cesium-137 and strontium-90. The plutonium stream went through two additional decontamination cycles to purify it, producing the first and second cycle waste streams. The first cycle waste stream contained approximately 10% of the long lived fission products and 1% of the plutonium. The coating waste was combined with the first cycle waste. The liquid waste from these processes was initially stored in the single shell tanks in tank farms. By 1948, limited space in the tank farms resulted in the decision to discharge the second cycle waste to cribs. In 1951, the 242-B and 242-T Evaporators began to concentrate the first cycle waste to reduce the volume of waste stored in the tank farms. By 1953, the need for tank space resulted in the first cycle waste that was being stored in the single shell tanks, to be discharged via overground pipelines to specific retention trenches. Some specific retention trenches received the waste from the bottoms of the 242-B and 242-T Evaporator tank or tri-butyl phosphate waste from the Uranium Recovery process.

Waste Type: Process Effluent

Waste Description: The site received first-cycle supernatant waste from 221-B Building. The waste is high in salt and is neutral to basic.

Code: 216-B-37

Classification: Accepted

Names: 216-B-37; 216-B-37 Trench; 216-BX-3 Trench;

Reclassification: None

Related Sites/ Structures: The trench is associated with the 221-B facility and 241-BX Tank Farm.

Process Description: In order to provide the tank space needed to support the fuel separations operations in 200 East and West Areas, first cycle supernate stored in the single shell tanks was intentionally discharged to specific retention trenches during 1953 and 1954. Specific retention disposal utilized the moisture retention capacity of the relatively dry soils above the regional ground water table. The volume of liquid disposed to each trench was limited to ten percent of the soil volume between the bottom of the trench and the groundwater table. B Plant and T Plant used the bismuth phosphate process to separate plutonium from irradiated fuel from 1944 through 1956. The first step in the process was to dissolve the metal coating from the fuel rods. The next step dissolved the uranium and extracted the plutonium. The uranium waste was known as the metal waste stream. It contained the bulk of the uranium and 90% of the cesium-137 and strontium-90. The plutonium stream went through two additional decontamination cycles to purify it, producing the first and second cycle waste streams. The first cycle waste stream contained approximately 10% of the long lived fission products and 1% of the plutonium. The coating waste was combined with the first cycle waste. The liquid waste from these processes was initially stored in the single shell tanks in tank farms. By 1948, limited space in the tank farms resulted in the decision to discharge the second cycle waste to cribs. In 1951, the 242-B and 242-T Evaporators began to concentrate the first cycle waste to reduce the volume of waste stored in the tank farms. By 1953, the need for tank space resulted in the first cycle waste that was being stored in the single shell tanks, to be discharged via overground pipelines to specific retention trenches. Some specific retention trenches received the waste from the bottoms of the 242-B and 242-T Evaporator tank or tri-butyl phosphate waste from the Uranium Recovery process.

Waste Type: Process Effluent

Waste Description: The site received first-cycle supernatant waste from 221-B Building. The waste is high in salt and is neutral to basic.

Code: 216-B-39	Classification: Accepted
Names: 216-B-39; 216-B-39 Trench; 216-BX-5 Trench; 241-BX-5 Grave	Reclassification: None
Type: Trench	Start Date: 1/1/1953
Status: Inactive	End Date: 1/1/1954

Description: The 216-B-35 through 216-B-42 trenches were surface stabilized as a unit. The area is marked with concrete AC-540 posts and Underground Radioactive Material signs. The surface has been planted with wheat grass.

Location: The trench is located north of B Plant and west of the 241-BX Tank Farm.

Related Sites/ Structures: The trench is associated with the 221-B facility.

Process Description: In order to provide the tank space needed to support the fuel separations operations in 200 East and West Areas, first cycle supernate stored in the single shell tanks was intentionally discharged to specific retention trenches during 1953 and 1954. Specific retention disposal utilized the moisture retention capacity of the relatively dry soils above the regional ground water table. The volume of liquid disposed to each trench was limited to ten percent of the soil volume between the bottom of the trench and the groundwater table. B Plant and T Plant used the bismuth phosphate process to separate plutonium from irradiated fuel from 1944 through 1956. The first step in the process was to dissolve the metal coating from the fuel rods. The

next step dissolved the uranium and extracted the plutonium. The uranium waste was known as the metal waste stream. It contained the bulk of the uranium and 90% of the cesium-137 and strontium-90. The plutonium stream went through two additional decontamination cycles to purify it, producing the first and second cycle waste streams. The first cycle waste stream contained approximately 10% of the long lived fission products and 1% of the plutonium. The coating waste was combined with the first cycle waste. The liquid waste from these processes was initially stored in the single shell tanks in tank farms. By 1948, limited space in the tank farms resulted in the decision to discharge the second cycle waste to cribs. In 1951, the 242-B and 242-T Evaporators began to concentrate the first cycle waste to reduce the volume of waste stored in the tank farms. By 1953, the need for tank space resulted in the first cycle waste that was being stored in the single shell tanks, to be discharged via overground pipelines to specific retention trenches. Some specific retention trenches received the waste from the bottoms of the 242-B and 242-T Evaporator tank or tri-butyl phosphate waste from the Uranium Recovery process.

Waste Type: Process Effluent

Waste Description: The site received first-cycle supernatant waste from 221-B Building. The waste is high in salt and is neutral to basic.

Code: 216-B-40 **Classification:** Accepted

Names: 216-B-40; 216-B-40 Trench; 216-BX-6 Trench; 241-BX-6 Grave; 241-BX-6 Trench **Reclassification:** None

Type: Trench **Start Date:** 1/1/1954

Status: Inactive **End Date:** 1/1/1954

Description: The 216-B-35 through 216-B-42 trenches were surface stabilized as a unit. The area is marked with concrete AC-540 posts and Underground Radioactive Material signs. The surface has been planted with wheat grass.

Location: The trench is located north of B Plant and west of the 241-BX Tank Farm.

Related Sites/ Structures: The trench is associated with the 221-B facility.

Process Description: In order to provide the tank space needed to support the fuel separations operations in 200 East and West Areas, first cycle supernate stored in the single shell tanks was intentionally discharged to specific retention trenches during 1953 and 1954. Specific retention disposal utilized the moisture retention capacity of the relatively dry soils above the regional ground water table. The volume of liquid disposed to each trench was limited to ten percent of the soil volume between the bottom of the trench and the groundwater table. B Plant and T Plant used the bismuth phosphate process to separate plutonium from irradiated fuel from 1944 through 1956. The first step in the process was to dissolve the metal coating from the fuel rods. The next step dissolved the uranium and extracted the plutonium. The uranium waste was known as the metal waste stream. It contained the bulk of the uranium and 90% of the cesium-137 and strontium-90. The plutonium stream went through two additional decontamination cycles to purify it, producing the first and second cycle waste streams. The first cycle waste stream contained approximately 10% of the long lived fission products and 1% of the plutonium. The coating waste was combined with the first cycle waste. The liquid waste from these processes was initially stored in the single shell tanks in tank farms. By 1948, limited space in the tank farms resulted in the decision to discharge the second cycle waste to cribs. In 1951, the 242-B and 242-T Evaporators began to concentrate the first cycle waste to reduce the volume of waste stored in the tank farms. By 1953, the need for tank space resulted in the first cycle waste that was being stored in the single shell tanks, to be discharged via overground pipelines to specific

retention trenches. Some specific retention trenches received the waste from the bottoms of the 242-B and 242-T Evaporator tank or tri-butyl phosphate waste from the Uranium Recovery process.

Waste Type: Process Effluent

Waste Description: The site received first-cycle supernatant waste from the 221-B Building. The waste is high in salt and is neutral to basic.

Code: 216-B-41 **Classification:** Accepted

Names: 216-B-41; 216-B-41 Trench; 216-BX-7 Trench; 241-BX-7 Grave **Reclassification:** None

Type: Trench **Start Date:** 1/1/1954

Status: Inactive **End Date:** 1/1/1954

Description: The 216-B-35 through 216-B-42 trenches were surface stabilized as a unit. The area is marked with concrete AC-540 posts and Underground Radioactive Material signs. The surface has been planted with wheat grass.

Location: The trench is located north of B Plant and west of the 241-BX Tank Farm.

Related Sites/ Structures: The trench is associated with the 221-B facility.

Process Description: In order to provide the tank space needed to support the fuel separations operations in 200 East and West Areas, first cycle supernate stored in the single shell tanks was intentionally discharged to specific retention trenches during 1953 and 1954. Specific retention disposal utilized the moisture retention capacity of the relatively dry soils above the regional ground water table. The volume of liquid disposed to each trench was limited to ten percent of the soil volume between the bottom of the trench and the groundwater table. B Plant and T Plant used the bismuth phosphate process to separate plutonium from irradiated fuel from 1944 through 1956. The first step in the process was to dissolve the metal coating from the fuel rods. The next step dissolved the uranium and extracted the plutonium. The uranium waste was known as the metal waste stream. It contained the bulk of the uranium and 90% of the cesium-137 and strontium-90. The plutonium stream went through two additional decontamination cycles to purify it, producing the first and second cycle waste streams. The first cycle waste stream contained approximately 10% of the long lived fission products and 1% of the plutonium. The coating waste was combined with the first cycle waste. The liquid waste from these processes was initially stored in the single shell tanks in tank farms. By 1948, limited space in the tank farms resulted in the decision to discharge the second cycle waste to cribs. In 1951, the 242-B and 242-T Evaporators began to concentrate the first cycle waste to reduce the volume of waste stored in the tank farms. By 1953, the need for tank space resulted in the first cycle waste that was being stored in the single shell tanks, to be discharged via overground pipelines to specific retention trenches. Some specific retention trenches received the waste from the bottoms of the 242-B and 242-T Evaporator tank or tri-butyl phosphate waste from the Uranium Recovery process.

Waste Type: Process Effluent

Waste Description: The site received the first-cycle supernatant waste from the 221-B Building. The waste is high in salt and is neutral to basic.

Code: 216-B-42 **Classification:** Accepted

Names: 216-B-42; 216-B-42 Trench; 216-BX-8 Trench; 241-BX-8 Grave **Reclassification** None

Type: Trench **Start Date:** 1/1/1955

Status: Inactive **End Date:** 1/1/1955

Description: The 216-B-35 through 216-B-42 trenches were surface stabilized as a unit. The area is marked with concrete AC-540 posts and Underground Radioactive Material signs. The surface has been planted with wheat grass.

Location: The trench is located north of B Plant and west of the 241-BX Tank Farm.

Related Sites/ Structures: This trench is associated with the Uranium Recovery operation done at the 221-U facility.

Process Description: In order to provide the tank space needed to support the fuel separations operations in 200 East and West Areas, first cycle supernate stored in the single shell tanks was intentionally discharged to specific retention trenches during 1953 and 1954. Specific retention disposal utilized the moisture retention capacity of the relatively dry soils above the regional ground water table. The volume of liquid disposed to each trench was limited to ten percent of the soil volume between the bottom of the trench and the groundwater table. B Plant and T Plant used the bismuth phosphate process to separate plutonium from irradiated fuel from 1944 through 1956. The first step in the process was to dissolve the metal coating from the fuel rods. The next step dissolved the uranium and extracted the plutonium. The uranium waste was known as the metal waste stream. It was combined with the coating waste to form the waste stream known as first cycle waste. It contained the bulk of the uranium and 90% of the cesium-137 and strontium-90. The plutonium stream went through additional decontamination cycles to purify it, producing the second cycle waste stream. The liquid waste from these processes were initially stored in the single shell tanks in tank farms. By 1948, limited space in the tank farms resulted in the decision to discharge the second cycle waste to cribs. In 1951, the 242-B and 242-T Evaporators began to concentrate the first cycle waste to reduce the volume of waste stored in the tank farms. By 1953, the need for tank space resulted in the first cycle waste that was being stored in the single shell tanks, to be discharged via overground pipelines to specific retention trenches. Some specific retention trenches received the waste from the bottoms of the 242-B and 242-T Evaporator tanks or tri-butyl phosphate waste from the Uranium Recovery process.

Waste Type: Process Effluent

Waste Description: The site received the scavenged tributyl phosphate (TBP) supernatant waste from the 221-U Building via the 241-BY tank farm. The waste is high in salt and is neutral to basic.

Code: 216-B-43 **Classification:** Accepted

Names: 216-B-43; 216-BY-1 Cavern; 216-BY-1 Crib **Reclassification** None

Type: Crib **Start Date:** 1/1/1954

Status: Inactive **End Date:** 1/1/1954

Description: The 216-B-43 through 216-B-50 cribs were stabilized as a unit with gravel. The group of cribs are surrounded concrete AC-540 markers and posted Underground Radioactive Material.

Location: The unit is located north of 241-BY Tank Farm and west of Baltimore Avenue in a common area with 216-B-44 through 216-B-50.

Release Description: See UPR-200-E-9 and UPR-200-E-89

Related Sites/ Structures: The crib is associated with the 221-U Uranium Recovery process. The pipeline that fed the BY cribs is discussed in sitecode 200-E-219-PL.

Process Description: From 1952 through 1958, Bismuth Phosphate process waste stored in 241-T, TX, 241-B, BX, BY, 241-C and 241-U tank farms was transferred to 221-U to recover the uranium from the waste after the tank sludge had been thinned with nitric acid. The uranium was extracted from the tank waste using Tri-butyl Phosphate (TPB) in a normal paraffin diluent. The waste from the uranium recovery process was neutralized and transferred to the 241-BY tank farm. The TBP process waste was treated with potassium ferrocyanide to precipitate most of the cesium and strontium. The supernate was decanted first to the 216-B-43 through 49 cribs and later to the BC Cribs and trenches. Crib 216-B-50 was not used for TBP waste.

Waste Type: Process Effluent

Waste Description: The site received the scavenged tributyl phosphate (TBP) supernatant waste from 221-U Building. The waste is high in salt and is neutral to basic. It included inorganic compounds such as ferrocyanide, nitrate and phosphate. (active in November 1954)

Code: 216-B-44 **Classification:** Accepted

Names: 216-B-44; 216-BY-2 Cavern; 216-BY-2 Crib **Reclassification:** None

Type: Crib **Start Date:** 12/1/1954

Status: Inactive **End Date:** 3/1/1955

Description: The 216-B-43 through 216-B-50 cribs were stabilized as a unit with gravel. The group of cribs are surrounded with light chain and posted Underground Radioactive Material.

Location: The unit is north of 241-BY Tank Farm and west of Baltimore Ave. in a common area with the 216-B-43 through 216-B-50 cribs.

Release Description: See UPR-200-E-89

Related Sites/ Structures: The crib is associated with the 221-U Uranium Recovery process. The pipeline that fed the BY cribs is discussed in sitecode 200-E-219-PL.

Process Description: From 1952 through 1958, Bismuth Phosphate process waste stored in 241-T, TX, 241-B, BX, BY, 241-C and 241-U tank farms was transferred to 221-U to recover the uranium from the waste after the tank sludge had been thinned with nitric acid. The uranium was extracted from the tank waste using Tri-butyl Phosphate (TPB) in a normal paraffin diluent. The waste from the uranium recovery process was neutralized and transferred to the 241-BY tank farm. The TBP process waste was treated with potassium ferrocyanide to precipitate most of the cesium and strontium. The supernate was decanted first to the 216-B-43 through 49 cribs and later to the BC Cribs and trenches. Crib 216-B-50 was not used for TBP waste. The crib was constructed of four 1.22-meter (4-foot) diameter by 1.22-meter (4 foot) long concrete culverts placed vertically, 2.14 meters (7 feet) below grade, on a 1.53-meter (5-foot) bed of 7.62-centimeter (3-inch) gravel (291 cubic meters [380 cubic yards]). Pipes are arranged in a square with the centers spaced 4.58 meters (15 feet) apart in a 9.15 by 9.15 by 4.58-meter (30 by 30 by 15-foot) deep excavation. Each culvert was fed by an 20.32-centimeter (8-inch) steel pipe coming from a main and forming a chevron pattern. Each culvert has a concrete cover.

Waste Type: Process Effluent

Waste Description: The site received scavenged tributyl phosphate (TBP) supernatant waste from 221-U Building. The waste is high in salt and is neutral to basic. It included inorganic compounds such as ferrocyanide, nitrate and phosphate. (active December 1954 - March 1955)

Code: 216-B-45	Classification: Accepted
Names: 216-B-45; 216-BY-3 Cavern; 216-BY-3 Crib	Reclassification: None
Type: Crib	Start Date: 4/1/1955
Status: Inactive	End Date: 6/1/1955

Description: The 216-B-43 through 216-B-50 cribs were stabilized as a unit with gravel. The group of cribs are surrounded with light chain and posted Underground Radioactive Material.

Location: The unit is located north of 241-BY Tank Farm and west of Baltimore Avenue in a common area with the 216-B-43 through 216-B-50 cribs.

Related Sites/ Structures: The crib is associated with the 221-U Uranium Recovery process. The pipeline that fed the BY cribs is discussed in sitecode 200-E-219-PL.

Process Description: From 1952 through 1958, Bismuth Phosphate process waste stored in 241-T, TX, 241-B, BX, BY, 241-C and 241-U tank farms was transferred to 221-U to recover the uranium from the waste after the tank sludge had been thinned with nitric acid. The uranium was extracted from the tank waste using Tri-butyl Phosphate (TPB) in a normal paraffin diluent. The waste from the uranium recovery process was neutralized and transferred to the 241-BY tank farm. The TBP process waste was treated with potassium ferrocyanide to precipitate most of the cesium and strontium. The supernate was decanted first to the 216-B-43 through 49 cribs and later to the BC Cribs and trenches. Crib 216-B-50 was not used for TBP waste. The crib was constructed of four 1.22-meter (4-foot) diameter by 1.22-meter (4 foot) long concrete culverts placed vertically, 2.14 meters (7 feet) below grade, on a 1.53-meter (5-foot) bed of 7.62-centimeter (3-inch) gravel (291 cubic meters [380 cubic yards]). Pipes are arranged in a square with the centers spaced 4.58 meters (15 feet) apart in a 9.15 by 9.15 by 4.58-meter (30 by 30 by 15-foot) deep excavation. Each culvert was fed by an 20.32-centimeter (8-inch) steel pipe coming from a main and forming a chevron pattern. Each culvert has a concrete cover.

Waste Type: Process Effluent

Waste Description: The site received the scavenged tributyl phosphate (TBP) supernatant waste from 221-U Building. The waste is high in salt and is neutral to basic. It included inorganic compounds such as ferrocyanide, nitrate and phosphate. (active April - June 1955)

Code: 216-B-46	Classification: Accepted
Names: 216-B-46; 216-BY-4 Cavern; 216-BY-4 Crib	Reclassification: None
Type: Crib	Start Date: 9/1/1955
Status: Inactive	End Date: 12/1/1955

Description: The 216-B-43 through 216-B-50 cribs were stabilized as a unit with gravel. The group of cribs are surrounded with light chain and posted Underground Radioactive Material.

Location: The unit is located north of 241-BY Tank Farm and west of Baltimore Avenue in a common area with the 216-B-43 through 216-B-50 cribs.

Related Sites/ Structures: The crib is associated with the 221-U Uranium Recovery process. The pipeline that fed the BY cribs is discussed in sitecode 200-E-219-PL.

Process Description: From 1952 through 1958, Bismuth Phosphate process waste stored in 241-T, TX, 241-B, BX, BY, 241-C and 241-U tank farms was transferred to 221-U to recover the uranium from the waste after the tank sludge had been thinned with nitric acid. The uranium was extracted from the tank waste using Tri-butyl Phosphate (TPB) in a normal paraffin diluent. The waste from the uranium recovery process was neutralized and transferred to the 241-BY tank farm. The

TBP process waste was treated with potassium ferrocyanide to precipitate most of the cesium and strontium. The supernate was decanted first to the 216-B-43 through 49 cribs and later to the BC Cribs and trenches. Crib 216-B-50 was not used for TBP waste. The crib was constructed of four 1.22-meter (4-foot) diameter by 1.22-meter (4 foot) long concrete culverts placed vertically, 2.14 meters (7 feet) below grade, on a 1.53-meter (5-foot) bed of 7.62-centimeter (3-inch) gravel (291 cubic meters [380 cubic yards]). Pipes are arranged in a square with the centers spaced 4.58 meters (15 feet) apart in a 9.15 by 9.15 by 4.58-meter (30 by 30 by 15-foot) deep excavation. Each culvert was fed by an 20.32-centimeter (8-inch) steel pipe coming from a main and forming a chevron pattern. Each culvert has a concrete cover.

Waste Type: Process Effluent

Waste Description: The site received scavenged tributyl phosphate (TBP) supernatant waste from 221-U Building. The waste is high in salt and is neutral to basic. It included inorganic compounds such as ferrocyanide, nitrate and phosphate. (active September - December 1955)

Code: 216-B-47

Classification: Accepted

Names: 216-B-47; 216-BY-5 Cavern; 216-BY-5 Crib

Reclassification: None

Type: Crib

Start Date: 9/1/1955

Status: Inactive

End Date: 9/1/1955

Description: The 216-B-43 through 216-B-50 cribs were stabilized as a unit with gravel. The group of cribs are surrounded with light chain and posted Underground Radioactive Material.

Location: The unit is located north of 241-BY Tank Farm and west of Baltimore Avenue in a common area with the 216-B-43 through 216-B-50 cribs.

Related Sites/Structures: The crib is associated with the 221-U Uranium Recovery process. The pipeline that fed the BY cribs is discussed in sitecode 200-E-219-PL.

Process Description: From 1952 through 1958, Bismuth Phosphate process waste stored in 241-T, TX, 241-B, BX, BY, 241-C and 241-U tank farms was transferred to 221-U to recover the uranium from the waste after the tank sludge had been thinned with nitric acid. The uranium was extracted from the tank waste using Tri-butyl Phosphate (TPB) in a normal paraffin diluent. The waste from the uranium recovery process was neutralized and transferred to the 241-BY tank farm. The TBP process waste was treated with potassium ferrocyanide to precipitate most of the cesium and strontium. The supernate was decanted first to the 216-B-43 through 49 cribs and later to the BC Cribs and trenches. Crib 216-B-50 was not used for TBP waste. The crib was constructed of four 1.22-meter (4-foot) diameter by 1.22-meter (4 foot) long concrete culverts placed vertically, 2.14 meters (7 feet) below grade, on a 1.53-meter (5-foot) bed of 7.62-centimeter (3-inch) gravel (291 cubic meters [380 cubic yards]). Pipes are arranged in a square with the centers spaced 4.58 meters (15 feet) apart in a 9.15 by 9.15 by 4.58-meter (30 by 30 by 15-foot) deep excavation. Each culvert was fed by an 20.32-centimeter (8-inch) steel pipe coming from a main and forming a chevron pattern. Each culvert has a concrete cover.

Waste Type: Process Effluent

Waste Description: The site received scavenged tributyl phosphate (TBP) supernatant waste from 221-U Building. The waste is high in salt and is neutral to basic. It included inorganic compounds such as ferrocyanide, nitrate and phosphate. (Active September 1955)

Code: 216-B-48

Classification: Accepted

Names: 216-B-48; 216-BY-6 Cavern; 216-BY-6 Crib

Reclassification: None

Type: Crib **Start Date:** 1/1/1955
Status: Inactive **End Date:** 1/1/1955

Description: The 216-B-43 through 216-B-50 cribs were stabilized as a unit with gravel. The group of cribs are surrounded with light chain and posted Underground Radioactive Material.

Location: The unit is located north of 241-BY Tank Farm and west of Baltimore Avenue in a common area with the 216-B-43 through 216-B-50 cribs.

Related Sites/ Structures: The crib is associated with the 221-U Uranium Recovery process. The pipeline that fed the BY cribs is discussed in sitecode 200-E-219-PL.

Process Description: From 1952 through 1958, Bismuth Phosphate process waste stored in 241-T, TX, 241-B, BX, BY, 241-C and 241-U tank farms was transferred to 221-U to recover the uranium from the waste after the tank sludge had been thinned with nitric acid. The uranium was extracted from the tank waste using Tri-butyl Phosphate (TPB) in a normal paraffin diluent. The waste from the uranium recovery process was neutralized and transferred to the 241-BY tank farm. The TBP process waste was treated with potassium ferrocyanide to precipitate most of the cesium and strontium. The supernate was decanted first to the 216-B-43 through 49 cribs and later to the BC Cribs and trenches. Crib 216-B-50 was not used for TBP waste. The crib was constructed of four 1.22-meter (4-foot) diameter by 1.22-meter (4 foot) long concrete culverts placed vertically, 2.14 meters (7 feet) below grade, on a 1.53-meter (5-foot) bed of 7.62-centimeter (3-inch) gravel (291 cubic meters [380 cubic yards]). Pipes are arranged in a square with the centers spaced 4.58 meters (15 feet) apart in a 9.15 by 9.15 by 4.58-meter (30 by 30 by 15-foot) deep excavation. Each culvert was fed by an 20.32-centimeter (8-inch) steel pipe coming from a main and forming a chevron pattern. Each culvert has a concrete cover.

Waste Type: Process Effluent

Waste Description: The site received scavenged tributyl phosphate (TBP) supernatant waste from 221-U Building. The waste is high in salt and is neutral to basic. It included inorganic compounds such as ferrocyanide, nitrate and phosphate. The pipeline to the unit was valved out when specific retention capacity was reached. Crib service duration discrepancies appear in historical documentation. ARH-947, HW-55176 and HW-83718 show November 1955 to February 1957 as the service duration. RHO-CD-673 shows November 1955 to July 1957 as the service duration. ARH-2806 shows November 1955 to November 1955 as the service duration. The start and end dates for adjacent cribs was 1955. In 1956 when a nearby groundwater monitoring well found elevated levels of cobalt-60 and cesium 137, effluent release in this area was discontinued. So the 1957 end date is questionable.

Code: 216-B-49 **Classification:** Accepted
Names: 216-B-49; 216-BY-7 Cavern; 216-BY-7 Crib **Reclassification:** None
Type: Crib **Start Date:** 11/1/1955
Status: Inactive **End Date:** 12/1/1955

Description: The 216-B-43 through 216-B-50 cribs were stabilized as a unit with gravel. The group of cribs are surrounded with light chain and posted Underground Radioactive Material.

Location: The unit is located north of 241-BY Tank Farm and west of Baltimore Avenue in a common area with the 216-B-43 through 216-B-50 cribs.

Related Sites/ Structures: The crib is associated with the 221-U Uranium Recovery process. The pipeline that fed the BY cribs is discussed in sitecode 200-E-219-PL.

Process Description: From 1952 through 1958, Bismuth Phosphate process waste stored in 241-T, TX, 241-B, BX, BY, 241-C and 241-U tank farms was transferred to 221-U to recover the uranium from the waste after the tank sludge had been thinned with nitric acid. The uranium was extracted from the tank waste using Tri-butyl Phosphate (TPB) in a normal paraffin diluent. The waste from the uranium recovery process was neutralized and transferred to the 241-BY tank farm. The TBP process waste was treated with potassium ferrocyanide to precipitate most of the cesium and strontium. The supernate was decanted first to the 216-B-43 through 49 cribs and later to the BC Cribs and trenches. Crib 216-B-50 was not used for TBP waste. The crib was constructed of four 1.22-meter (4-foot) diameter by 1.22-meter (4 foot) long concrete culverts placed vertically, 2.14 meters (7 feet) below grade, on a 1.53-meter (5-foot) bed of 7.62-centimeter (3-inch) gravel (291 cubic meters [380 cubic yards]). Pipes are arranged in a square with the centers spaced 4.58 meters (15 feet) apart in a 9.15 by 9.15 by 4.58-meter (30 by 30 by 15-foot) deep excavation. Each culvert was fed by an 20.32-centimeter (8-inch) steel pipe coming from a main and forming a chevron pattern. Each culvert has a concrete cover.

Waste Type: Process Effluent

Waste Description: The site received scavenged tributyl phosphate (TBP) supernatant waste from 221-U Building. The waste is high in salt and is neutral to basic. It included inorganic compounds such as ferrocyanide, nitrate and phosphate. (Active November-December 1955)

Code: 216-B-50	Classification: Accepted
Names: 216-B-50; 216-BY-8 Cavern; 216-BY-8 Crib	Reclassification: None
Type: Crib	Start Date: 1/1/1965
Status: Inactive	End Date: 1/1/1974

Description: The 216-B-43 through 216-B-50 cribs were stabilized as a unit with gravel. The group of cribs are surrounded with light chain and posted Underground Radioactive Material.

Location: The unit is located north of 241-BY Tank Farm and west of Baltimore Avenue in a common area with the 216-B-43 through 216-B-49 cribs.

Related Sites/Structures: The crib is associated with the 241-BY tank farm and 216-B-57 crib. The pipeline that fed the BY cribs is discussed in sitecode 200-E-219-PL.

Process Description: The 216-B-50 crib received condensate from the 241-BY tank farm In-Tank Solidification system. The crib was originally constructed along with seven others in the same location (216-B-43 through 49) to receive scavenged tributyl phosphate (TBP) waste. The other seven were used for this purpose, but taken out of service when a cobalt-60 and cesium-137 breakthrough to groundwater occurred in 1956. The decision to use the 216-B-50 crib for ITS condensate was made about 8 or 9 years later when monitoring showed that the groundwater radioactivity levels were definitely decreasing. The crib was constructed of four 1.22-meter (4-foot) diameter by 1.22-meter (4 foot) long concrete culverts placed vertically, 2.14 meters (7 feet) below grade, on a 1.53-meter (5-foot) bed of 7.62-centimeter (3-inch) gravel (291 cubic meters [380 cubic yards]). Pipes are arranged in a square with the centers spaced 4.58 meters (15 feet) apart in a 9.15 by 9.15 by 4.58-meter (30 by 30 by 15-foot) deep excavation. Each culvert was fed by an 20.32-centimeter (8-inch) steel pipe coming from a main and forming a chevron pattern. Each culvert has a concrete cover.

Waste Type: Process Effluent

Waste Description: The site received the waste storage tank intermediate level process condensate from the In Tank Solidification (ITS) #1 unit in the 241-BY Tank Farm. Since startup of the #1 ITS in March, 1965, approximately five and one-half million gallons of condensate containing about 120 beta curies of activity, including about 70 curies of cesium-137, have been routed to the 216-B-50

crib (as of April 1968). The crib was originally constructed along with seven others in the same location to receive scavenged tributyl phosphate (TBP) waste. The other seven were used for this purpose, but the crib site was taken out of service when a cobalt-60 and cesium-137 breakthrough occurred. The decision to use the 216-B-50 crib for ITS condensate was made about 8 or 9 years later when it was known that the groundwater activity levels were definitely decreasing. It was recognized that the crib had limited use. 216-B-50 crib has a bottom area of 83.6 square meters (900 square feet), and its capacity had been adequate for the 5-6 gallons per minute flow of condensate. Now that the capacity of #1 ITS has been doubled (Project ICE-618), it is doubtful that the crib will have sufficient capacity without a significant rise in the level of water in the crib. This increase of water level could drive the condensate through the highly contaminated zone under the other seven cribs (216-B-43 through 49) that are located 15 to 76 meters (50 to 250 feet) from the 216-B-50 crib. Flow data obtained from the monitoring wells showed that condensate sent to the 216-B-50 crib tended to migrate under the highly contaminated cribs. To avoid potential flooding of 216-B-50, 216-B-61 crib was proposed. The #2 ITS Unit, also located in the 241-BY Tank Farm used crib 216-B-57, which was designed for receiving only the condensate flow from the #2 Unit. The 216-B-50 crib needed to be taken out of service because of its size limitations and because of the close proximity of the highly contaminated cribs (216-B-43 through 216-B-49) that had been used for scavenged TBP wastes. These seven cribs received over 400,000 curies of beta activity including about 13,000 and 4,000 curies of long lived strontium and cesium, respectively. The groundwater under these cribs still contains detectable concentrations of cesium-137 and cobalt-60 (April

Code:	216-B-57	Classification:	Accepted
Names:	216-B-57; 216-B-57 Enclosed Trench; Hanford Prototype Barrier; 200-BP-1 Prototype Barrier	Reclassification	None
Type:	Crib	Start Date:	2/1/1968
Status:	Inactive	End Date:	6/1/1973
Description:	This crib was selected to be the site of the Hanford Prototype Barrier. The engineered barrier was constructed on top of the crib in 1994. The barrier is 105 meters (340 feet) long, 64 meters (210 feet) wide and 15 meters (49 feet) tall. It is posted Underground Radioactive Material.		
Location:	The unit is located west of Baltimore Avenue and south of 12th Street. It is northeast of 241-BY Tank Farm.		
Related Sites/ Structures:	The crib is associated with the In Tank Solidification (ITS #2) and the 241-BY Tank Farm.		
Process Description:	During construction, the crib was filled to 1.2 meters (4 feet) above the bottom with gravel (approximately 474 cubic meters [620 cubic yards]). A perforated, 30.5-centimeter (12-inch) corrugated pipe runs the length of the crib, 0.9 meters (3 feet) above the bottom. The side slope of the original crib construction is 1.5:1.		
Waste Type:	Storage Tank		
Waste Description:	The site received the waste storage tank condensate from the In Tank Solidification (ITS) #2 Unit in 241-BY Tank Farm.		

Code:	200-E-45	Classification:	Accepted
Names:	200-E-45; Contaminated Pump Run-in Caisson; Health Instrument Shaft; HI Shaft	Reclassification	None
Type:	Silo	Start Date:	1/1/1948

Status: Inactive**End Date:** 1/1/1973

Description: The site is a concrete shaft, 16.6 meters (55 feet) deep. It is constructed of prefabricated concrete sections, 2.4 meters (8 feet) in diameter and 1.9 meters (6 feet 2 inches) high. Steel pipes were installed laterally through holes in the side of the shaft at 3 meters (10 feet) and 6 meters (20 feet) from the surface toward the 216-B-8 Crib. The pipes were 15 centimeters (6 inches) in diameter, and 6.6 meters (22 feet) long. The site is topped with a large circular cover with a smaller manhole, a hatch and a vent pipe. The shaft lid is now covered with clean gravel, surrounded by light duty posts and chain and is posted as an Underground Radioactive Material Area. The waste site is represented by two polygons in the mapping system. The smaller polygon represents the top of the shaft. A larger area, measuring approximately 130 feet by 100 feet represents an area of shallow, surface contamination that is posted as an Underground Radioactive Material Area. The source of the contamination was the 200-E-45 shaft.

Location: The shaft is located north of 241-B Tank Farm and west of the of the 216-B-8 Crib.

**Related Sites/
Structures:** The HI Shaft is associated with the 216-B-8 Crib.

**Process
Description:** The Health Instrument Shaft is located adjacent to the west side of the 216-B-8 Crib. The Health Instrument Shaft was originally installed to allow Health Instrument technicians to descend a ladder and collect liquid and soil samples from a depth of approximately 3 meters (10 feet) and 6 meters (20 feet) below the bottom of the 216-B-8 Crib through openings in the shaft. Perforated lateral pipes extending beneath the crib allowed liquid waste from the crib to enter the pipes and collect in sample cups. Other holes were made in the side of the shaft facing the crib to collect sediment samples. Samples were collected for several years and ended on December 31, 1949. The shaft structure was later filled with water and used to test contaminated tank farm pumps. The last known pump test was done in 1973. In 1949, radiological readings up to 4 rad/hour were recorded at the bottom of the shaft. As of December 1949, 105 liquid samples, 4 sludge samples and 7 sediment samples had been collected and analyzed to characterize the operation of the 216-B-8 Crib. Liquid samples collected at the 3 meter (10 foot) level and the 6 meter (20 foot) level both contained an average of 0.5 microcuries per liter. In August 1948, sludge from the 104-B tank was inadvertently jetted to the 216-B-8 Crib. A sudden decrease in the crib capacity led to the discovery of approximately 37.5 centimeters (15 inches) of sludge in the crib. Some sludge washed to at least 6.1 meters (20 feet) below the crib bottom and was collected in the HI Shaft sample cups. The plutonium activity in the sludge samples was 900 microcuries per kilogram of sludge. This is 1000 times higher than the plutonium content of the supernate liquid usually discharged to cribs. The fission product activity in the sludge samples was 9,000 microcuries per kilogram of sludge. This is roughly 5,000 times greater than the fission product activity in supernate liquid. Liquid sample collected in the HI Shaft prior to the sludge discharge contained less than 1000 disintegrations per minute per liter of alpha contamination. Liquid samples collected after the sludge release contained an average of 17,500 disintegrations per minute per liter of alpha contamination. Sediment samples collected from approximately 5.5 meters (18 feet) below the crib through the HI Shaft prior to the sludge release contained beta-gamma activity of 0.13 microcuries per kilogram. After the sludge release the activity increased to 0.33 microcuries per kilogram. No alpha contamination was found in the sediment samples. This process ended in December 1949.

In the late 1950's, the vertical shaft was used to test contaminated tank farm pumps. It became known as the Contaminated Pump Run-in Caisson. Water was added to the vertical shaft and the contaminated pumps were placed inside and tested. This operation occurred intermittently through 1973.

Waste Type: Process Effluent

Waste Description: The shaft was used to obtain samples from the 216-B-8 Crib. The bottom of the shaft occasionally collected a significant amount of crib seepage that was pumped out of the shaft and back to the crib. Later the shaft was intermittently filled with water and used as a contaminated pump testing pit.

Code: 216-S-9 **Classification:** Accepted

Names: 216-S-9; 216-S-9 Crib **Reclassification:** None

Type: Crib **Start Date:** 1/1/1965

Status: Inactive **End Date:** 1/1/1969

Description: The unit is a gravel structure with a side slope of 1:1.5. Waste flowed into the unit through the distribution system, which consists of 177 meters (581 feet) of 15-centimeter (6-inch) Vitrified Clay Tile (VCT) perforated pipe in a U-shape, 4.6 meters (15 feet) by 89.9 meters (295 feet), and connected by 7.3 meters (24 feet) of 4.6-centimeter (3-inch) Schedule 10 pipe in a Y-shape. The entire distribution system is 6.4 meters (21 feet) below grade.

Location: The crib is located east of 241-S, SX, SY Tank Farms.

Related Sites/Structures: The crib is associated with the 216-S-7 crib, 216-S-23 crib and the 200-W-138-PL and 200-W-139-PL pipelines.

Process Description: The following are related to the unit: two 20-centimeter (8-inch) diameter, 8.5-meter (28-foot) long V.C.T. gage wells, with the bottom 0.9 meters (3 feet) perforated; two 0.6-meter (2-foot) by 0.6-meter (2-foot) by 0.3-meter (1-foot) concrete pads for gage wells; one 30-centimeter (12-inch) diameter, 7.3-meter (24-foot) long, V.C.T. vent with filter; one 0.6-meter (2-foot) by 0.6-meter (2-foot) by 1.2-meter (4-foot) concrete pad for the vent; approximately 1,767 cubic meters (62,400 cubic feet) of gravel fill and 960.3 square meters (10,336 square feet) of plastic barrier; 12,690 cubic meters (448,000 cubic feet) of gravel backfill.

Waste Type: Process Effluent

Waste Description: The site received process condensate from the D-2 Receiver Tank in the 202-S Building. The waste is acidic.

Code: 216-S-13 **Classification:** Accepted

Names: 216-S-13; 216-S-6; 276-S Crib **Reclassification:** None

Type: Crib **Start Date:** 1/1/1952

Status: Inactive **End Date:** 1/1/1972

Description: The crib is surrounded with steel posts and chain. It is posted with Underground Radioactive Material and Cave-In Potential signs. The unit is a square wooden crib box, with open bottom enclosed on four sides with sheathing. The crib box sits in a partially backfilled hole. The unit was then backfilled to grade. The crib box has a riser vent, and one inlet pipe near the top of the box.

Location: The crib is located northwest of the 202-S Building and south of the 216-S-7 crib.

Related Sites/Structures: The site is associated with the 203-S Decontaminated Storage Facility, 204-S Uranium Nitrate Hexahydrate Lag Storage Facility, and the 276-S Organic-Solvent Make-up Facility. The pipelines associated with 216-S-13 crib are discussed in sitecode 200-W-150-PL.

Process Description: From January 1952 to June 1967 the unit received liquid waste from the 203-S Decontaminated Metal Storage Facility, the 203-S Uranium Nitrate Hexahydrate (tank farm), 204-S; 204-S Tank

Farm & Pumphouse, 205-S Process Vault & Chemical Makeup Building and the 276-S Organic-Solvent Make-up Facility. From June 1967 to July 1972 the unit received occasional sump waste from the 204-S Facility.

Waste Type: Process Effluent

Waste Description: The site received mixed, organic waste containing nitrate, methyl isobutyl ketone, and sodium dichromate. Radionuclides include cobalt-60, strontium-90 and cesium-137. The waste was low in salt and is neutral to basic. A 1966 internal memo suggests that 25,000 gallons of hexone from the 276-S tanks 141 and 142 were discharged to the 216-S-13 crib over a three month time period.

Code: 216-S-21	Classification: Accepted
Names: 216-S-21; 216-SX-1; 216-SX-1 Cavern or Crib	Reclassification: None
Type: Crib	Start Date: 1/1/1954
Status: Inactive	End Date: 1/1/1970

Description: The site was interim stabilized in 1991 and is posted "Underground Radioactive Material." The site consists of one wooden crib box with two vent risers and one test well going through the center of the box. This crib box sits in a gravel layer in the bottom of a square pit. The rest of the pit is backfilled.

Location: This site is west of the 241-S Tank Farm and north of 216-S-25.

Related Sites/Structures: The crib is associated with the 241-SX-401 Condenser Facility. The pipeline associated with this crib is sitecode 200-W-160-PL.

Process Description: This site provided subsurface liquid disposal for the 241-SX-401 Condenser Facility.

Waste Type: Process Effluent

Waste Description: The site received 241-SX condensate from the condensers in the 401-SX Condenser Facility via the 241-SX-206 Tank. The waste is low in salt and is neutral to basic. The waste contained sodium and ammonium nitrate.

Code: 216-T-3	Classification: Accepted
Names: 216-T-3; 241-T-361-A Reverse Well; 361-T Reverse Well	Reclassification: None
Type: Injection/Reverse Well	Start Date: 6/1/1945
Status: Inactive	End Date: 8/1/1946

Description: The 216-T-3 identified with concrete AC-540 markers and Underground Radioactive Material signs. The reverse well is constructed of steel pipe extending deep into the ground. There are two wells inside the posted area. The one on the north side of the posted area has a cap with the remnants of a gauge. The one near the southwest side of the area has a plain well cap.

Location: This site is located northwest of the 241-T-361 Settling Tank and northeast of the 216-T-6 Crib.

Related Sites/Structures: The associated structures are the 221-T Building and the 241-T-361 Settling Tank. The pipeline from 224-T that fed the reverse well is sitecode 200-W-226-PL.

Process Description: This reverse well received liquid disposal from the 221-T and the 224-T facilities via the 241-T-361 Settling Tank. Discharge to the reverse well was discontinued in 1946 and the effluent was

routed to the 216-T-6 crib. Some 224-T waste was diverted to the 241-T-252 Diversion box (per H-2-951).

Waste Type: Process Effluent

Waste Description: The reverse well received 221-T and 224-T liquid waste via the 241-T-361 settling tank. The waste included cell drainage from tank 5-6 in 221-T and 224-T waste. The chemical inventory includes nitrate, potassium, sodium, ammonium nitrate, sodium oxalate, fluoride, sulfate and phosphate. The radionuclide inventory includes 3350 grams of plutonium and 2800 curies of fission products.

Code: 216-T-5 **Classification:** Accepted

Names: 216-T-5; 216-T-5 Grave; 216-T-5 Trench; 241-T-5 Trench; 216-T-12 **Reclassification:** None

Type: Trench **Start Date:** 1/1/1955

Status: Inactive **End Date:** 1/1/1955

Description: The 216-T-5 trench is marked and posted with Underground Radioactive Material signs.

Location: This site is located west of the 241-T Tank Farm and northwest of the 216-T-32 Crib.

Related Sites/Structures: The trench is associated with the 221-T Building and the 241-T Tank Farm.

Process Description: This trench received 221-T second cycle supernatant that had been stored in the 241-T-112 tank via an overground pipeline. The trench was active in May 1955. Due to the lack of waste storage space in the tank farms, second cycle waste from the bismuth phosphate fuel separation operations, which had been stored in the tank farms, began to be released to cribs and specific retention trenches in 1948. The extracted plutonium went through two decontamination cycles to further purify it. The first cycle waste was combined with the coating waste. It contained 10% of the fission products and 1% of plutonium. The second decontamination cycle waste contained less than 0.1% of the fission products.

Waste Type: Process Effluent

Waste Description: The site received second cycle supernate waste that contained nitrate, sodium silicate, sodium, ammonium nitrate, fluoride, sulfate, and phosphate. Second cycle waste contained less than 0.1% fission products.

Code: 216-T-6 **Classification:** Accepted

Names: 216-T-6; 241-T-361 (1&2 Cribs); 361-T-1&2 Cribs; 216-T-5 **Reclassification:** None

Type: Crib **Start Date:** 1/1/1946

Status: Inactive **End Date:** 1/1/1951

Description: The 216-T-6 Cribs are delineated with light post and chain and Cave-in Potential signs. The area is surrounded with concrete AC-540 markers and Underground Radioactive Material signs.

Location: The 216-T-6 Cribs are located north of 23rd Street, southwest of the 221-T Building. They are adjacent to the 216-T-3 Reverse Well and the 241-T-361 Tank.

Related Sites/Structures: The associated structures are the 221-T and 224-T Facilities and the 241-T-361 Tank. The pipeline that fed the cribs is sitecode 200-W-227-PL.

Process Description: The cribs received liquid waste from the 221-T and 224-T Facilities via the 241-T-361 Settling Tank. The cribs were built to replace the 216-T-3 Reverse Well when it was abandoned in August 1946. From August 1946 to October 1946, the cribs received cell drainage from Tank 5-6 in the 221-T Building and waste from the 224-T Building via the overflow from 241-T-361 Settling Tank. From October 1946 to June 1951, the site received cell drainage from Tank 5-6 in the 221-T Building. In June 1951, the 241-T-361 Settling Tank was deactivated, and the 224-T Building effluent was rerouted to 216-T-32 Crib. In June 1951 the site was deactivated to evaluate the radionuclide disposal characteristics of the crib. The crib pipeline was blanked south of the 241-T-361 Settling Tank. The 221-T waste was rerouted to the 216-T-7 Crib.

Waste Type: Process Effluent

Waste Description: The cribs received waste from 221-T and 224-T that was low in salt, neutral to basic and contained nitrate, sodium, ammonium nitrate, sodium oxalate, fluoride, sulfate, and phosphate.

Code: 216-T-7 **Classification:** Accepted

Names: 216-T-7; 216-T-7 Tile Field; 216-T-7TF; 241-T-3 Tile Field **Reclassification:** None

Type: Drain/Tile Field **Start Date:** 1/1/1948

Status: Inactive **End Date:** 1/1/1955

Description: The 216-T-7 Tile Field is delineated with concrete AC-540 markers and posted with Underground Radioactive Material signs.

Location: The 216-T-7 Tile Field is located adjacent to the west side of the 241-T Farm fence and north of 23rd Street. A portion of the tile field extends inside the tank farm fence.

Related Sites/Structures: The 216-T-7 Tile Field is associated with the 216-T-7 Crib (site code 200-W-52), the 241-T-112, and the 221-T and 224-T facilities.

Process Description: The 216-T-7 crib (site code 200-W-52) received second cycle supernate from 221-T, 224-T waste and tank 5-6 waste after it cascaded through the 241-T-110, 241-T-111 and 241-T-112 tanks. The 216-T-7 Tile Field received overflow from the crib.

Waste Type: Process Effluent

Waste Description: The site received second-cycle supernatant waste from the 221-T Building until June 1951 via the 241-T-110, 241-T-111 and 241-T-112 tanks. From June 1951 to June 1952, the site received the 221-T Building effluent plus cell drainage from Tank 5-6 in the 221-T Building. From June 1952 to November 1955, the site received the 221-T Building effluent plus waste from the 224-T Building. The waste is high in salt and is neutral to basic and contains nitrate, potassium, sodium, ammonium nitrate, sodium oxalate, fluoride, sulfate, and phosphate.

Code: 216-T-14 **Classification:** Accepted

Names: 216-T-14; 241-T-1 Trench; 216-T-1 Grave; 216-T-13 **Reclassification:** None

Type: Trench **Start Date:** 1/1/1954

Status: Inactive **End Date:** 1/1/1954

Description: The 216-T-14, 216-T-15, 216-T-16 and 216-T-17 trenches were surface stabilized as a unit. The area is identified with concrete AC-540 markers and are posted with Underground Radioactive Material signs. The surface has been planted with wheat grass.

Location: The trench is located north of 23rd Street and northeast of the 241-T Tank Farm.

Related Sites/ Structures: The trench is associated with 221-T, the 241-T Tank Farm and UPR-200-W-166.

Process Description: In order to provide the tank space needed to support the fuel separations operations in 200 East and West Areas, first cycle supernate stored in the single shell tanks was intentionally discharged to specific retention trenches during 1953 and 1954. Specific retention disposal utilized the moisture retention capacity of the relatively dry soils above the regional ground water table. The volume of liquid disposed to each trench was limited to ten percent of the soil volume between the bottom of the trench and the groundwater table. B Plant and T Plant used the bismuth phosphate process to separate plutonium from irradiated fuel from 1944 through 1956. The first step in the process was to dissolve the metal coating from the fuel rods. The next step dissolved the uranium and extracted the plutonium. The uranium waste was known as the metal waste stream. It contained the bulk of the uranium and 90% of the cesium-137 and strontium-90. The plutonium stream went through two additional decontamination cycles to purify it, producing the first and second cycle waste streams. The first cycle waste stream contained approximately 10% of the long lived fission products and 1% of the plutonium. The coating waste was combined with the first cycle waste. The liquid waste from these processes was initially stored in the single shell tanks in tank farms. By 1948, limited space in the tank farms resulted in the decision to discharge the second cycle waste to cribs. In 1951, the 242-B and 242-T Evaporators began to concentrate the first cycle waste to reduce the volume of waste stored in the tank farms. By 1953, the need for tank space resulted in the first cycle waste, that was being stored in the single shell tanks, to be discharged via overground pipelines to specific retention trenches.

Waste Type: Process Effluent

Waste Description: The site received the first-cycle supernatant waste from the 221-T Building via the 241-T-104, 241-T-105 and 241-T-106 Tanks in the 241-T Tank Farm. The waste is high in salt and is neutral to basic.

Code: 216-T-15 **Classification:** Accepted

Names: 216-T-15; 216-T-15 Crib; 241-T-2 Grave; 241-T-2 Trench; 216-T-14 **Reclassification:** None

Type: Trench **Start Date:** 1/1/1954

Status: Inactive **End Date:** 1/1/1954

Description: The 216-T-14, 216-T-15, 216-T-16 and 216-T-17 trenches were surface stabilized as a unit. The area is identified with concrete AC-540 markers and are posted with Underground Radioactive Material signs. The surface has been planted with wheat grass.

Location: The trench is located north of 23rd Street and northeast of the 241-T Tank Farm.

Related Sites/ Structures: The trench is associated with 221-T, the 241-T Tank Farm and UPR-200-W-166.

Process Description: In order to provide the tank space needed to support the fuel separations operations in 200 East and West Areas, first cycle supernate stored in the single shell tanks was intentionally discharged to specific retention trenches during 1953 and 1954. Specific retention disposal utilized the moisture retention capacity of the relatively dry soils above the regional ground water table. The volume of liquid disposed to each trench was limited to ten percent of the soil volume between the bottom of the trench and the groundwater table. B Plant and T Plant used the bismuth phosphate process to separate plutonium from irradiated fuel from 1944 through 1956. The first step in the process was to dissolve the metal coating from the fuel rods. The

next step dissolved the uranium and extracted the plutonium. The uranium waste was known as the metal waste stream. It contained the bulk of the uranium and 90% of the cesium-137 and strontium-90. The plutonium stream went through two additional decontamination cycles to purify it, producing the first and second cycle waste streams. The first cycle waste stream contained approximately 10% of the long lived fission products and 1% of the plutonium. The coating waste was combined with the first cycle waste. The liquid waste from these processes was initially stored in the single shell tanks in tank farms. By 1948, limited space in the tank farms resulted in the decision to discharge the second cycle waste to cribs. In 1951, the 242-B and 242-T Evaporators began to concentrate the first cycle waste to reduce the volume of waste stored in the tank farms. By 1953, the need for tank space resulted in the first cycle waste, that was being stored in the single shell tanks, to be discharged via overground pipelines to specific retention trenches.

Waste Type: Process Effluent

Waste Description: The site received the first-cycle supernatant waste from the 221-T Building via the 241-T-104, 241-T-105 and 241-T-106 Tanks in the 241-T Tank Farm. The waste is high in salt and is neutral to basic.

Code: 216-T-16	Classification: Accepted
Names: 216-T-16; 216-T-16 Crib; 241-T-3 Grave; 241-T-3 Trench; 216-T-15	Reclassification: None
Type: Trench	Start Date: 1/1/1954
Status: Inactive	End Date: 1/1/1954

Description: The 216-T-14, 216-T-15, 216-T-16 and 216-T-17 trenches were surface stabilized as a unit. The area is identified with concrete AC-540 markers and are posted with Underground Radioactive Material signs. The surface has been planted with wheat grass.

Location: The trench is located north of 23rd Street and northeast of the 241-T Tank Farm.

Related Sites/Structures: The trench is associated with 221-T, the 241-T Tank Farm and UPR-200-W-166.

Process Description: In order to provide the tank space needed to support the fuel separations operations in 200 East and West Areas, first cycle supernate stored in the single shell tanks was intentionally discharged to specific retention trenches during 1953 and 1954. Specific retention disposal utilized the moisture retention capacity of the relatively dry soils above the regional ground water table. The volume of liquid disposed to each trench was limited to ten percent of the soil volume between the bottom of the trench and the groundwater table. B Plant and T Plant used the bismuth phosphate process to separate plutonium from irradiated fuel from 1944 through 1956. The first step in the process was to dissolve the metal coating from the fuel rods. The next step dissolved the uranium and extracted the plutonium. The uranium waste was known as the metal waste stream. It contained the bulk of the uranium and 90% of the cesium-137 and strontium-90. The plutonium stream went through two additional decontamination cycles to purify it, producing the first and second cycle waste streams. The first cycle waste stream contained approximately 10% of the long lived fission products and 1% of the plutonium. The coating waste was combined with the first cycle waste. The liquid waste from these processes was initially stored in the single shell tanks in tank farms. By 1948, limited space in the tank farms resulted in the decision to discharge the second cycle waste to cribs. In 1951, the 242-B and 242-T Evaporators began to concentrate the first cycle waste to reduce the volume of waste stored in the tank farms. By 1953, the need for tank space resulted in the first cycle waste, that was being stored in the single shell tanks, to be discharged via overground pipelines to specific retention trenches.

Waste Type: Process Effluent

Waste Description: The site received the first-cycle supernatant waste from the 221-T Building via the 241-T-104, 241-T-105 and 241-T-106 Tanks in the 241-T Tank Farm. The waste is high in salt and is neutral to basic.

Code: 216-T-17 **Classification:** Accepted

Names: 216-T-17; 216-T-4 Grave; 241-T-4 Trench; 216-T-16 **Reclassification:** None

Type: Trench **Start Date:** 1/1/1954

Status: Inactive **End Date:** 1/1/1954

Description: The 216-T-14, 216-T-15, 216-T-16 and 216-T-17 trenches were surface stabilized as a unit. The area is identified with concrete AC-540 markers and are posted with Underground Radioactive Material signs. The surface has been planted with wheat grass.

Location: The trench is located north of 23rd Street and northeast of the 241-T Tank Farm.

Related Sites/Structures: The trench is associated with 221-T, the 241-T Tank Farm and UPR-200-W-166.

Process Description: In order to provide the tank space needed to support the fuel separations operations in 200 East and West Areas, first cycle supernate stored in the single shell tanks was intentionally discharged to specific retention trenches during 1953 and 1954. Specific retention disposal utilized the moisture retention capacity of the relatively dry soils above the regional ground water table. The volume of liquid disposed to each trench was limited to ten percent of the soil volume between the bottom of the trench and the groundwater table. B Plant and T Plant used the bismuth phosphate process to separate plutonium from irradiated fuel from 1944 through 1956. The first step in the process was to dissolve the metal coating from the fuel rods. The next step dissolved the uranium and extracted the plutonium. The uranium waste was known as the metal waste stream. It contained the bulk of the uranium and 90% of the cesium-137 and strontium-90. The plutonium stream went through two additional decontamination cycles to purify it, producing the first and second cycle waste streams. The first cycle waste stream contained approximately 10% of the long lived fission products and 1% of the plutonium. The coating waste was combined with the first cycle waste. The liquid waste from these processes was initially stored in the single shell tanks in tank farms. By 1948, limited space in the tank farms resulted in the decision to discharge the second cycle waste to cribs. In 1951, the 242-B and 242-T Evaporators began to concentrate the first cycle waste to reduce the volume of waste stored in the tank farms. By 1953, the need for tank space resulted in the first cycle waste, that was being stored in the single shell tanks, to be discharged via overground pipelines to specific retention trenches.

Waste Type: Process Effluent

Waste Description: The site received the first-cycle supernatant waste from the 221-T Building via the 241-T-104, 241-T-105 and 241-T-106 Tanks in the 241-T Tank Farm. The waste is high in salt and is neutral to basic.

Code: 216-T-18 **Classification:** Accepted

Names: 216-T-18; 241-T-17 Crib; Scavenged TBP Waste; Test Crib for 221-U Building; 216-T-17 **Reclassification:** None

Type: Crib **Start Date:** 1/1/1953

Status: Inactive**End Date:** 1/1/1953**Description:** The site is marked with concrete AC-540 markers. The site is posted as an "Underground Radioactive Material" area. The surface is covered with gravel.**Location:** This site is located northeast of 241-TY Farm and north of the 216-T-26 Crib.**Related Sites/ Structures:** The site is associated with the uranium recovery process done at 221-U.**Process Description:** Although many references state the crib received scavenged tri-butyl phosphate waste from 221-T (T Plant), it is believed that the reference to T Plant was a typographical error that was carried into subsequent documentation. It should have said 241-T Tank Farm. Document WHC-MR-0227, Tank Wastes Discharged Directly to the Soil at Hanford states that the ferrocyanide (TBP) scavenging process was tested in U Plant in October 1953. HW-33591 states the scavenged waste was pumped from the 241-T-101 tank to a hole in the ground located north of the 241-T-17 monitoring well. Ferrocyanide and nickel were added to the uranium recovery waste to remove cesium-137 from the waste stream so it could be discharged to the ground instead of requiring tank storage. The treated test waste was pumped to a single shell tank for settling (241-T-101) in October 1953. Because of poor pH control during the test, only half of the resultant scavenged waste was discharged to the 216-T-18 crib in December 1953. The other half remained stored in the single shell tank.**Waste Type:** Process Effluent**Waste Description:** There is a discrepancy in the historical documentation of the waste disposed to this crib. Some references state the site received a test batch of ferrocyanide scavenged tri-butyl phosphate waste from 221-U in December 1953. The waste was high in salt, neutral to basic, and contained nitrate, sodium silicate, sodium, sodium hydroxide, sodium aluminate, fluoride, sulfate, phosphate and nitrite. HW-33591 states that 256,000 gallons of waste was pumped from tank 241-T-101 to a hole in the ground located north of the 241-T-17 monitoring well. Maxfield (1979) states the crib received a million liters of first cycle waste from 221-T that included 1800 grams of plutonium.**Code:** 216-T-19**Classification:** Accepted**Names:** 216-T-19; 216-T-19TF; 216-TX-1; 241-TX-153 Crib and Tile Field; 241-TX-3**Reclassification:** None**Type:** Crib**Start Date:** 1/1/1951**Status:** Inactive**End Date:** 1/1/1980**Description:** The crib and tile field are enclosed within a chain barricade. The crib is enclosed within a second chain barricade that is posted with Cave-In Potential signs. The outer chain is posted with "Underground Radioactive Material" signs. The site construction is wooden crib box with a riser, set into a square bottom pit with sloping sides. The crib has an inlet and outlet pipe. The outlet pipe connects to a tile field. The tile field consists of a central pipe running the length of a rectangular trench with sloping sides. Pipes branch off the main pipe over the length of the trench. After construction, the crib and tile field were backfilled to grade.**Location:** This site is located southwest of the 241-TX Tank Farm and east of the 216-Z-7 Crib.**Related Sites/ Structures:** The crib and tile field are associated with the 242-T Building, 221-T Building, the 224-T Building and the 241-TX-153 Diversion Box. The pipeline to the crib is 200-W-213-PL.**Process Description:** The site provided subsurface liquid disposal for process condensate from the waste evaporator in 242-T, cell drainage from Tank 5-6, second-cycle supernatant waste from 221-T, and waste from the 224-T Building.

Waste Type: Process Effluent

Waste Description: The site received waste containing nitrate, sodium, ammonium nitrate, sulfate, and phosphate.

Code: 216-T-21	Classification: Accepted
Names: 216-T-21; 216-TX-1 Grave; 216-TX-3; 241-TX-1 Trench	Reclassification: None
Type: Trench	Start Date: 1/1/1954
Status: Inactive	End Date: 1/1/1954

Description: This site consists of a backfilled trench. It is one of five specific retention trenches (216-T-21, 216-T-22, 216-T-23, 216-T-24 and 216-T-25) that was surface stabilized as one unit. The group of trenches is surrounded with concrete AC-540 markers and Underground Radioactive Material signs.

Location: This site is located west of the 241-TX Tank Farm and north of the 231-Z Building.

Related Sites/Structures: The trench is associated with the 221-T Building and the 241-TX Tank Farm.

Process Description: In order to provide the tank space needed to support the fuel separations operations in 200 East and West Areas, first cycle supernate stored in the single shell tanks was intentionally discharged to specific retention trenches during 1953 and 1954. Specific retention disposal utilized the moisture retention capacity of the relatively dry soils above the regional ground water table. The volume of liquid disposed to each trench was limited to ten percent of the soil volume between the bottom of the trench and the groundwater table. This trench provided subsurface liquid disposal for first-cycle supernatant waste from 221-T via the 241-TX-109, 241-TX-110, and 241-TX-111 Tanks. The site was deactivated when the specific retention capacity was reached. The overground piping was removed and the trench backfilled. The trench was active from June through August 1954.

Waste Type: Process Effluent

Waste Description: The trench received first cycle supernate from 221-T that was high in salt, neutral to basic, and contained fluoride, nitrate, nitrite, phosphate, sodium, sodium aluminate, sodium hydroxide, sodium silicate, and sulfate.

Code: 216-T-22	Classification: Accepted
Names: 216-T-22; 216-TX-2 Grave; 216-TX-4; 241-TX-2 Trench	Reclassification: None
Type: Trench	Start Date: 1/1/1954
Status: Inactive	End Date: 1/1/1954

Description: This site consists of a backfilled trench. It is one of five specific retention trenches (216-T-21, 216-T-22, 216-T-23, 216-T-24 and 216-T-25) that was surface stabilized as one unit. The group of trenches is surrounded with concrete AC-540 markers and Underground Radioactive Material signs.

Location: The site is located west of the 241-TX Tank Farm and north of the 231-Z Building.

Related Sites/Structures: The trench is associated with the 221-T Building and the 241-TX Tank Farm.

Process Description: In order to provide the tank space needed to support the fuel separations operations in 200 East and West Areas, first cycle supernate stored in the single shell tanks was intentionally discharged to specific retention trenches during 1953 and 1954. Specific retention disposal utilized the moisture retention capacity of the relatively dry soils above the regional ground water table. The volume of liquid disposed to each trench was limited to ten percent of the soil volume between the bottom of the trench and the groundwater table. This site was used for subsurface liquid disposal of first-cycle supernatant waste from 221-T via the 241-TX-109, 241-TX-110, and 241-TX-111 Tanks. The trench was active in July and August 1954. The trench was deactivated when the specific retention capacity was reached by removing the overground piping and backfilling the trench.

Waste Type: Process Effluent

Waste Description: The trench received first cycle supernate from 221-T that was high in salt, neutral to basic, and contained fluoride, nitrate, nitrite, phosphate, sodium, sodium aluminate, sodium hydroxide, sodium silicate, and sulfate.

Code: 216-T-23	Classification: Accepted
Names: 216-T-23; 216-TX-3 Grave; 216-TX-5; 241-TX-3 Grave; 241-TX-3 Trench	Reclassification: None
Type: Trench	Start Date: 1/1/1954
Status: Inactive	End Date: 1/1/1954

Description: This site consists of a backfilled trench. It is one of five specific retention trenches (216-T-21, 216-T-22, 216-T-23, 216-T-24 and 216-T-25) that was surface stabilized as one unit. The group of trenches is surrounded with concrete AC-540 markers and Underground Radioactive Material signs.

Location: This site is located west of the 241-TX Tank Farm and north of the 231-Z Building.

Related Sites/Structures: The trench is associated with the 221-T Building and the 241-TX Tank Farm.

Process Description: In order to provide the tank space needed to support the fuel separations operations in 200 East and West Areas, first cycle supernate stored in the single shell tanks was intentionally discharged to specific retention trenches during 1953 and 1954. Specific retention disposal utilized the moisture retention capacity of the relatively dry soils above the regional ground water table. The volume of liquid disposed to each trench was limited to ten percent of the soil volume between the bottom of the trench and the groundwater table. This site was used for subsurface liquid disposal of first cycle supernatant waste from 221-T via the 241-TX-109, 241-TX-110, and 241-TX-111 Tanks. The trench was active during July and August 1954. The trench was deactivated when the specific retention capacity was reached by removing the overground piping and backfilling the trench.

Waste Type: Process Effluent

Waste Description: The trench received first cycle supernate from 221-T that was high in salt, neutral to basic, and contained fluoride, nitrate, nitrite, phosphate, sodium, sodium aluminate, sodium hydroxide, sodium silicate, and sulfate.

Code: 216-T-24	Classification: Accepted
Names: 216-T-24; 216-TX-4 Grave; 216-TX-6; 241-TX-4 Trench	Reclassification: None

Waste Type: Process Effluent

Waste Description: The trench received evaporator bottom waste consisting of sludge from condensing first cycle waste in the 242-T Evaporator. It was high in salt, neutral to basic, and contained fluoride, nitrate, nitrite, phosphate, sodium, sodium aluminate, sodium hydroxide, sodium silicate, and sulfate.

Code: 216-T-26 **Classification:** Accepted

Names: 216-T-26; 216-TX-1 Crib; 216-TY-1 Cavern; 216-TY-1 Crib; 241-TX-1 Cavern **Reclassification:** None

Type: Crib **Start Date:** 1/1/1955

Status: Inactive **End Date:** 1/1/1956

Description: The 216-T-26, 216-T-27 and 216-T-28 cribs are enclosed within a common steel post and chain barricade that is posted "Underground Radioactive Material". The 216-TY-201 flush tank is located in the northeast corner of the area. Two small concrete pads are located east of the crib area.

Location: This site is located inside 200 West Area, south of 23rd Street and east of Camden Ave.

Related Sites/Structures: The associated structures are the 221-T Building, the 241-TY-101, 241-TY-103, and 241-TY-104 tanks and 241-T-112, the 216-TY-201 flush tank. The pipelines associated with this crib are 200-W-175-PL and 200-W-188-PL.

Process Description: The site provided subsurface liquid disposal for first-cycle scavenged supernatant waste from 221-T via an underground pipeline and the 216-TY-201 Flush Tank after cascading through the 241-TY-101, 241-TY-103, and 241-TY-104 tanks and later from 241-T-112 tank.

In 1955, in order to provide enough tank space in the tank farms required to continue to support fuel separation operations and plutonium production, T Plant began to scavenge newly generated first cycle waste before sending it to the tank farms. By adding ferrocyanide to the waste stream, the cesium-137 was precipitated, significantly reducing the quantity of long-lived radionuclides. This process allowed the first cycle waste to be discharged to the ground instead of to single shell tanks.

The unit consists of a steel inlet pipe reducing to a steel pipe, below grade. This pipe branches to four steel pipes, each one extending to a concrete open-end sewer pipe. These structures lie in an excavation with a side slope of 1:1.5. A gravel fill is covered by earth backfill.

Waste Type: Process Effluent

Waste Description: The site received first-cycle scavenged supernatant waste from T Plant containing ferrocyanide, fluoride, nitrate, nitrite, phosphate, sodium, sodium aluminate, sodium hydroxide, sodium silicate and sulfate.

Code: 216-T-32 **Classification:** Accepted

Names: 216-T-32; 216-T-6; 241-T #1 & 2 Cribs **Reclassification:** None

Type: Crib **Start Date:** 1/1/1946

Status: Inactive **End Date:** 1/1/1952

Description: The crib is located inside the 241-T Tank Farm fence. The fence is posted with Radiological Buffer Area/Underground Radioactive Material signs. The tank farm has a gravel surface. The

crib is not separately identified.

Location: This site is located on the west side of the 241-T Farm and north of 216-T-7 Crib. The fence on the west side of the 241-T Tank Farm transects the northwest corner of the crib. Most of the crib is located inside the tank farm fence.

**Related Sites/
Structures:** The crib is associated with the 241-T-201 tank, the 241-T-152 and 241-T-252 Diversion Boxes and the 224-T facility.

**Process
Description:** The 216-T-32 Crib consists of two wooden crib boxes, each set into a square bottom pit with sloping sides. The pits contain backfill. The crib boxes are connected in series by a pipe, with one crib overflowing into the other. The cribs received liquid waste from the 224-T Building via the 241-T-201 Tank. Each box was constructed with a riser vent.

Waste Type: Process Effluent

**Waste
Description:** The site received waste from 224-T via the 241-T-201 Tank. The waste was high in salt, neutral to basic, and contained nitrate, sodium, ammonium nitrate, sodium oxalate, fluoride, sulfate, and phosphate.

200-EA-1

Code: 207-A-NORTH **Classification:** Accepted**Names:** 207-A-NORTH; 207-A-NORTH Retention Basin; 207-A; 207-A North; 207-A Retention Basin **Reclassification:** None**Type:** Retention Basin **Start Date:** 1/1/1977**Status:** Inactive **End Date:** 1/1/1999**Description:** The 207-A North basins consist of three Hypalon lined, concrete basins. The basins are surrounded with posts and chain. There is no radiological posting on the north basins.**Location:** The 207-A-NORTH basins are located east of 242-A Evaporator building, adjacent to the 207-A-SOUTH basin.**Related Sites/ Structures:** The basins are associated with the 242-A Evaporator facility, 216-A-25 Pond and 216-B-3 Pond. The pipelines from 242-A Evaporator to the 207-A basins are sitecode 200-E-234-PL. The basin distribution lines are sitecode 200-E-235-PL.**Process Description:** The basins were alternately filled, sampled, and emptied when meeting specifications. The basins discharged via pipeline to the 216-B-3C pond. Discharge to the 216-B-3C pond was discontinued in early 1997 and the basin effluent was diverted to the 200 Area Treated Effluent Disposal Facility (TEDF). The basin was physically isolated in 1999. The isolation is documented in ECN-653675 and Work Package EL-98-00091.

A 4-in (10 cm) fill line enters each basin, approximately 2 ft (0.6 m) long (inside basin structure) and a 3-in (7.6 cm) drain line exits.

Waste Type: Steam Condensate**Waste Description:** The basins have been receiving steam condensate from the 242-A Evaporator since 1977. Effluent was originally sent to the 216-A-25 (Gable Pond) and later to the B Pond system. When the B-Ponds became inactive, effluent was diverted to TEDF.

Code: 216-A-1 **Classification:** Accepted**Names:** 216-A-1; 216-A-1 Cavern; 216-A-1 Trench **Reclassification:** None**Type:** Crib **Start Date:** 1/1/1955**Status:** Inactive **End Date:** 1/1/1955**Description:** The 216-A-1 and 216-A-7 cribs had been located within the same radiologically posted area. They are marked and posted with Underground Radioactive Material signs.**Location:** The site is located inside the 200 East Area perimeter fence extension, east of the 241-A Tank Farm, along Canton Avenue.**Related Sites/ Structures:** The site is associated with the 202-A sample pit #3 and the 200-E-158-PL pipeline.**Process Description:** The site received start up waste from PUREX during November and December 1955 via an overground pipeline from Sample Pit #3. When the specific retention capacity was reached, the site was deactivated by removing the overground piping and backfilling. The site is composed of 15-centimeter (6-inch) perforated Vitrified Clay Pipe (VCP), 9.1 meters (30 feet) long, running horizontally at 2.7 meters (9 feet) below grade, with two 9.1 meter (30-foot) lengths of

15-centimeter (6-inch) perforated VCP placed perpendicularly to the first length of pipe, forming an H pattern. There is approximately 1.8 meters (6 feet) or 310 cubic meters (11,000 cubic feet) of coarse rock in the excavation bottom. The side slope, surface to 2.1 meters (7 feet) deep, is 1:1.5, 2.1 meters (7 feet) to site bottom is 1:2.

Waste Type: Process Effluent

Waste Description: The site received the depleted uranium waste from the cold startup run in the 202-A Building. Some cesium-137, cobalt-60 and strontium-90 is also present.

Code: 216-A-2 **Classification:** Accepted

Names: 216-A-2; 216-A-2 Cavern; 216-A-2 Crib **Reclassification:** None

Type: Crib **Start Date:** 1/1/1956

Status: Inactive **End Date:** 1/1/1963

Description: The crib is covered with gravel and marked with concrete AC-540 posts. The crib is located within a larger URM, known as 200-E-103.

The unit consists of 15-centimeter (6-inch) perforated vitrified clay pipe lines. Two 6.1-meter (20-foot) lengths form a cross pattern horizontally, 6.4 meters (21 feet) below grade. It has approximately 1.8 meters (6 feet) of coarse rock with a volume of 140 cubic meters (5,000 cubic feet) and is backfilled over. The side slope from grade to 6.4 meters (21 feet) is 1:1.5 and from 6.4 meters (21 feet) to 8.2 meters (27 feet) is 1:2.

Location: The 216-A-2 site is located south of the 202-A Building (PUREX), inside the facility exclusion area fence.

Related Sites/Structures: The site is associated with the 202-A Building, the 241-A-151 Diversion Box and 200-E-103. The pipelines associated with the crib are sitecode 200-E-183-PL and 200-E-184-PL.

Process Description: The site received organic waste from the 202-A building via two 10 centimeter (4 inch) diameter vitrified clay pipes (see sitecode 200-E-184-PL).

Waste Type: Process Effluent

Waste Description: The site received organic wastes from the 202-A Building. The waste is low in salt and is neutral to basic.

Code: 216-A-3 **Classification:** Accepted

Names: 216-A-3; 216-A-3 Cavern; 216-A-3 Crib **Reclassification:** None

Type: Crib **Start Date:** 1/1/1956

Status: Inactive **End Date:** 4/1/1981

Description: The crib is marked and posted with Underground Radioactive Material signs.

Location: The unit is located directly south of the 275-EA Building, west of Canton Avenue and north of the 202-A Building.

Related Sites/Structures: The crib is associated with 203-A. The 216-A-3 pipeline is sitecode 200-E-168-PL.

Process Description: From 1956 to 1967, the site received silica-gel regeneration waste and pump house drainage from 203-A and drainage from the UNH storage pit. The silica gel discharge was discontinued

in 1967. The site was taken out of service in April 1981. The waste was rerouted so that any low level radioactive waste was sent to the 216-A-29 Ditch. The unit contains a 10-centimeter (4-inch) Schedule 10 perforated 304 stainless steel pipe placed horizontally 2.4 meters (8 feet) below grade and two 6.1-meter (20-foot) lengths of this pipe placed perpendicularly to the first pipe, forming an H pattern. The site has approximately 2.4 meters (8 feet) of gravel fill with a volume of 280 cubic meters (10,000 cubic feet) and has been backfilled. The side slope surface to 2.1 meters (7 feet) deep is 1.5:1 and from 2.1 meters (7 feet) to the site bottom is 2:1.

Waste Type: Process Effluent

Waste Description: Until November 1967, the site received wastes from the silica-gel regeneration in the 203-A Building, the uranyl nitrate hexahydrate (UNH) storage pit drainage, and the liquid waste from the 203-A Pump House. After November 1967, the site received UNH Storage Pit drainage, liquid drainage, liquid waste from the 203-A Building enclosure sumps, and the heating coil condensate from the P1 through P4 UNH tanks. Between 1967 and 1970, the site discontinued receiving discharge from silica-gel regeneration wastes. The above wastes are reworked through the uranium cycle and any resulting waste with low radioactivity are sent to 216-A-29. The waste included uranium, cesium-137, strontium-90 and ruthenium-106.

Code: 216-A-4	Classification: Accepted
Names: 216-A-4; 216-A-4 Cavern	Reclassification: None
Type: Crib	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1958

Description: The site is located within a large gravel area, known as the PUREX Stabilized Area (sitecode 200-E-103). A large green vent riser extends above the surface.

Location: The site is located south of the 202-A Building and east of 216-A-2, inside the PUREX Exclusion Fence.

Release Description: UPR-200-E-15 documents the event that occurred in 1958, when the 216-A-4 Crib plugged and caused contaminated liquid to flood the ground surface. The contaminated soil was placed into a trench near the south border of the crib (see sitecode 200-E-102) and covered with 0.3 meters (1 foot) of soil.

Related Sites/Structures: The 216-A-4 crib is associated with 216-A-2 Crib, 241-A-151, the PUREX laboratories, UPR-200-E-15 and 200-E-103. The site has also been identified as receiving drainage from the 291-A Stack (see Site Comment section). The pipelines associated with this site are 200-E-183-PL, 200-E-185-PL and 200-E-196-PL.

Process Description: The crib received laboratory cell drainage from the 202-A building, and possibly drainage from the 291-A stack. The unit consists of two 6.1-meter (20-foot) lengths of 15-centimeter (6-inch) perforated vitrified clay pipe, forming a cross pattern horizontally, 5.5 meters (18 feet) below grade. The excavation has 2.4 meters (8 feet) of coarse rock fill with a volume of 280 cubic meters (10,000 cubic feet) and has been backfilled. The side slope from the surface to 5.5 meters (18 feet) deep is 1:1.5 and from 5.5 meters (18 feet) to the site bottom, 1:2.

Waste Type: Process Effluent

Waste Description: The site received the laboratory cell drainage from the 202-A Building (the site was reported to have also received 291-A-1 Stack drainage, see the Site Comments section under the Summary tab). The waste is low in salt and is neutral to basic. The 216-A-4 Crib also received waste solution from the 216-A-2 waste collection tank, the U Cell U-3 and U-4 laboratory waste receiver tanks (located in the acid storage vault), the dissolver off-gas scrubbers and the 241-A-151 Diversion Box Catch Tank. 216-A-4 was intended to receive a maximum of (75 gallons per minute) low level radioactive liquid waste. Waste volume from the laboratory waste and

cell drain was 52,990 liters (14,000 gallons).

Code: 216-A-5	Classification: Accepted
Names: 216-A-5; 216-A-5 Cavern	Reclassification: None
Type: Crib	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1966

Description: The crib is marked and posted with Underground Radioactive Material signs.

Location: The crib is located south of the 202-A Building between the inner and outer PUREX exclusion area fences.

Related Sites/ Structures: The site is associated with the PUREX process, 200-E-58 and the 216-A-10 crib. The 216-A-5 crib pipeline is sitecode 200-E-239-PL.

Process Description: The crib received acidic process condensate from 202-A from December 1955 through November 1961. After 1961, the crib was used as a back up waste site for the 216-A-10 crib. It received additional waste in October 1966.

The unit consists of a 20-centimeter (8-inch) vitrified clay pipe (VCP) placed horizontally, 7.3 meters (24 feet) below grade and two 10.7-meter (35-foot) lengths of 20-centimeter (8-inch) VCP placed perpendicular to the first pipe, forming an H pattern. The site is backfilled with approximately 2.4 meters (8 feet) of coarse rock fill with a volume of 595 cubic meters (21,000 cubic feet). The side slope from the surface to 7.3 meters (24 feet) deep is 1:1.5 and from 7.3 meters (24 feet) to the bottom, 2:1.

Waste Type: Process Effluent

Waste Description: Until November 1961, the site received process condensate from the 202-A Building. From November 1961 to October 1966, the site was active but received no waste (backup for the 216-A-10 Crib). In October 1966, the site received process condensate from the 202-A Building. The waste is acidic.

Code: 216-A-6	Classification: Accepted
Names: 216-A-6; 216-A-6 Cavern; 216-A-6 Crib	Reclassification: None
Type: Crib	Start Date: 11/1/1955
Status: Inactive	End Date: 1/1/1970

Description: The site is marked with AC-540 markers and posted with Underground Radioactive Material signs. The unit was constructed with a 38-centimeter (15-inch) Vitrified Clay Pipe (VCP) placed horizontally 3.7 meters (12 feet) below grade the length of the unit. Five 31-meter (100-foot) lengths of perforated 15-centimeter (6-inch) VCP are placed perpendicularly to the first pipe at 6.1-meter (20-foot) intervals. The site contains approximately 2,580 cubic meters (91,000 cubic feet) of coarse gravel fill, backfilled over. The side slope from the surface to 2.1 meters (7 feet) is 1:1 and from 2.1 meters (7 feet) to the site bottom, 2:1.

Location: The site is located outside the 200 East Area perimeter fence, east of the Plutonium Uranium Extraction (PUREX) facility and south of 241-AP Tank Farm.

Release Description: UPR-200-E-19, UPR-200-E-21, UPR-200-E-29 are associated with 216-A-6.

Related Sites/ Structures: The crib is associated with the 216-A-30 crib and 200-E-113-PL.

Waste Type: Process Effluent

Waste Description: Until January 1961, the site received the steam condensate, the equipment disposal tunnel floor drainage, the water-filled door drainage and the slug storage basin overflow waste from the 202-A Building. From January 1961 to March 1966, the site was inactive. After March 1966, the site received the previously mentioned effluents again. The waste is low in salt and is neutral to basic.

Code: 216-A-9 **Classification:** Accepted

Names: 216-A-9; 216-A-9 Crib **Reclassification:** None

Type: Crib **Start Date:** 3/1/1956

Status: Inactive **End Date:** 8/1/1969

Description: The crib is a surface stabilized area, marked with light post and chain. It is posted as an Underground Radioactive Material area.

Location: 216-A-9 Crib is located inside 200 East Area, north of 4th Street. The site is located 150 meters (500 feet) west of the 241-A Tank Farm and 275 meters (900 feet) north of 275-EA Building along Fourth Street.

Related Sites/Structures: The site is associated with PUREX processes and N Reactor liquid waste. The pipeline associated with this crib is sitecode 200-E-238-PL.

Process Description: The site contains a 25 centimeter (10-inch) Schedule 30 steel perforated pipe, placed horizontally, 2.7 meters (9 feet) below grade. The site has 1,840 cubic meters (65,000 cubic feet) of gravel fill and has been backfilled. The side slope is 2:1. The crib was used for disposal of PUREX acid fractionator condensate and cooling water. The crib surpassed its capacity in 1958 and was taken out of service. In April 1966, the crib was approved for disposal of liquid N Reactor decontamination waste, that was to that was transported to the crib in tanker trucks. The waste was discharged into the Truck Unloading Station adjacent to the crib. This process continued until October 1966. The crib was inactive until August 1969, when PUREX acid fractionator waste was again sent to the 216-A-9 crib.

Waste Type: Process Effluent

Waste Description: Until February 1958, the site received the acid fractionator condensate and the condenser cooling water from the 202-A Building. From February 1958 to April 1966, the site was inactive. From April 1966 to October 1966, the site received N Reactor decontamination waste via a manhole at the truck unloading station. From October 1966 to August 1969, the site was inactive. In August 1969, the site received the acid fractionator condensate from the 202-A Building. The waste is acidic.

Code: 216-A-10 **Classification:** Accepted

Names: 216-A-10; 216-A-10 Crib **Reclassification:** None

Type: Crib **Start Date:** 1/1/1956

Status: Inactive **End Date:** 1/1/1987

Description: The site is covered with gravel with no vegetation growing on it. It is surrounded with light posts and chain and posted as Underground Radioactive Material.

Location: The site is located south of the 202-A Building.

Related Sites/ Structures: The site is associated with 202-A, and 216-A-5 crib. The pipelines associated with the crib are documented in sitecode 200-E-192-PL. The pipeline to the 216-A-45 crib teed off of the 200-E-200-192-PL (see sitecode 200-E-231-PL).

Process Description: Although the crib was built in 1956, it did not receive contaminated waste until 1961. Early discharge reports list effluent volumes for the 216-A-10 crib that did not contain any plutonium or beta/gamma values. A 1980 telephone conference documentation sheet explained that the crib received water testing effluent in 1956. The crib was active until 1978. The crib was inactive until October 1981, when it again received acidic process condensate from 202-A. The crib was deactivated in March 1987.

The unit consists of a 20-centimeter (8-inch) SST pipe placed horizontally 9.1 meters (30 feet) below grade, 8.2 meters (27 feet) east of the centerline. The site has a wedge-shaped cross section and a side slope of 1:1.5. The excavation has 4.6 meters (15 feet) of rock fill with a volume of 11,700 cubic meters (414,000 cubic feet) of rock fill and has been backfilled over.

Waste Type: Process Effluent

Waste Description: During 1956, the site was used only for testing purposes using nonradioactive water. From 1956 to November 1961, the site was inactive. From November 1961 to January 1978, the site received process condensate from the 202-A Building. From January 1978 to October 1981, the site was again inactive. From October 1981 to 1986, the site received the process condensate from the 202-A Building. The crib received Process Distillate Discharge (PDD), a corrosive/mixed waste, at an average flow rate of 227 liters/minute (60 gallon/minute). The discharge was an acidic waste stream generated from two product concentrators in the Plutonium Uranium Extraction (PUREX) process. The pH of this waste ranged from 1.0 to 2.5 standard units which makes it a corrosive mixed waste. Approximately 62.6 million kilograms (138 million pounds) of waste were disposed of in the crib in 1986. Characterization holes placed through the crib in 2003 found cesium-137 at depths ranging from 48 to 84 feet below ground surface and europium-154 at approximated 84 feet below ground surface.

Code: 216-A-15	Classification: Accepted
Names: 216-A-15; Miscellaneous Stream #461	Reclassification: None
Type: French Drain	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1972

Description: The unit is composed of two, 1.2 meter (4 foot) diameter, 1.2 meter (4 foot) long bell-end, reinforced concrete sewer pipes placed vertically end to end. It is filled with 1.8 meters (6 feet) of stone. Approximately 11 meters (35 feet) of vent pipe extends from the grade surface to the concrete drain structure. 1.6 meters (5.5 feet) of vent pipe extends above grade.

Location: The site is located approximately 82 meters (270 feet) south of the center of the 202-A Building and east of the Sampler Pit #4.

Related Sites/ Structures: The site is associated with PUREX, the 216-A-10 crib and the 216-A-5 crib. The pipeline to this French drain is 200-E-242-PL.

Process Description: The drain received condensate and storm water that collected in the drain at the bottom of the Process Condensate Sample Pit #4. A leak in one of the fittings may have allowed radioactive liquid to be released to the french drain. A manhole cove on the top of the sample pit may have allowed stormwater to enter the pit.

Waste Type: Process Effluent

Waste Description: The site received the drainage from the 216-A-10 Process Condensate Sampler Pit #4. The waste is acidic. The site contains less than 50 curies total beta activity.

Code: 216-A-18 **Classification:** Accepted

Names: 216-A-18; 216-A-18 Crib; 216-A-18 Excavation; 216-A-18 Grave; 216-A-18 Sump **Reclassification:** None

Type: Trench **Start Date:** 11/1/1955

Status: Inactive **End Date:** 1/1/1956

Description: The site is marked and posted with Underground Radioactive Material signs.

Location: The site is located outside of the 200 East Area perimeter fence, east of the 241-AX Tank Farm, along Canton Avenue.

Related Sites/ Structures: The site is associated with the 202-A facility.

Process Description: The trench received start up waste from PUREX via an aboveground pipeline. The site was an excavation with a side slope of 1:2. No crib structure was ever built.

Waste Type: Chemicals

Waste Description: The site received the depleted uranium waste from the cold start-up run at 202-A Building.

Code: 216-A-19 **Classification:** Accepted

Names: 216-A-19; 216-A-19 Crib; 216-A-19 Grave; 216-A-19 Sump; 216-A-19 Test Hole **Reclassification:** None

Type: Trench **Start Date:** 11/1/1955

Status: Inactive **End Date:** 1/1/1956

Description: The site is marked and posted with Underground Radioactive Material signs. In February 2001, a narrow area posted with Soil Contamination Area signs extended between the 216-A-19 southern site boundary and northern boundary of 216-A-34.

Location: The site is located east of the 200 East Area perimeter fence, north of the 216-A-8 Crib.

Related Sites/ Structures: The site is associated with PUREX, 216-A-19, 216-A-20 and 216-A-34.

Process Description: The site received PUREX start up waste during November and December 1955. Several references state it also received condenser cooling water from the 241-A-431 building via the 216-A-34 Ditch. However, drawings do not show the 216-A-34 Ditch connecting to the 216-A-19 Grave. HW-40763 states that in December 1955, the ditch received PUREX waste from "C-203 and C-204 tanks". The ditch was also used for disposing of depleted uranium from the cold start up of PUREX.

Waste Type: Water

Waste Description: The site received the 241-A-431 Building contact condenser cooling water via the 216-A-34 Ditch and the depleted uranium waste from the cold start-up run at the 202-A Building. HW-40763 states that in December 1955, the ditch received PUREX waste from "C-203 and C-204 tanks".

Code: 216-A-20	Classification: Accepted
Names: 216-A-20; 216-A-20 Crib; 216-A-20 Grave; 216-A-20 Sump; 216-A-20 Test Hole	Reclassification: None
Type: Trench	Start Date: 11/1/1955
Status: Inactive	End Date: 12/1/1955

Description: The site is marked and posted with Underground Radioactive Material signs.

Location: The site is located east of the 200 East Area perimeter fence, north of the 216-A-8 Crib.

Release Description: HW-60807 includes a comment note, stating that 216-A-20 overflowed. The overflow covered an area measuring approximately 30 meters (100 feet) north and 60 meters (200 feet) east of the crib site. The overflow area was hand drawn onto H-2-56521.

Related Sites/ Structures: The site is associated with the 241-A-431 building, 202-A, and the 216-A-34 Ditch.

Process Description: 216-A-20 was originally a test hole excavated with a drag line and used for PUREX start-up waste. The site also received cooling water from the 241-A-431 building contact condenser via the 216-A-34 Ditch. The site was backfilled when the specific retention capacity was reached.

Waste Type: Water

Waste Description: The site received the 241-A-431 Building contact condenser cooling water via the 216-A-34 Ditch and the depleted uranium waste from the cold start-up run at the 202-A Building.

Code: 216-A-21	Classification: Accepted
Names: 216-A-21; 216-A-21 Crib	Reclassification: None
Type: Crib	Start Date: 10/1/1957
Status: Inactive	End Date: 6/1/1965

Description: The crib is covered with gravel. It is marked and posted with Underground Radioactive Material signs. A 10-centimeter (4-inch) stainless steel distribution line runs horizontally through the length of the site, 2.1 meters (7 feet) below grade. Branching horizontally from this distribution line are four 1.2-meter (4-foot) sections of 10-centimeter (4-inch) tubing. Branching vertically at the same locations are four 2.4-meter (8-foot) sections of 10-centimeter (4-inch) schedule 40 perforated pipe running to the bottom of the site. The excavation is V-shaped in cross-section with a side slope of 1:1.5. The excavation has approximately 1.8 meters (6 feet) of gravel fill and is backfilled over.

Location: The site is located south of the 202-A Building inside the PUREX Exclusion Fence.

Related Sites/ Structures: The site is associated with the 202-A facility, 293-A, 291-A, 293-A and 200-E-103. The VCP pipeline associated with this crib is sitecode 200-E-193-PL. The stainless steel line is sitecode 200-E-196-PL.

Waste Type: Process Effluent

Waste Description: Until June 1958, the site received sump waste from 293-A Building. From June 1958 to December 1958, the site was inactive. From December 1958 to June 1965, the site received the above effluent, laboratory cell drainage from the 202-A Building, and the 291-A-1 Stack drainage. The waste is low in salt and is neutral to basic.

Code: 216-A-22	Classification: Accepted
Names: 216-A-22; 216-A-22 Crib; 216-A-22 French Drain	Reclassification: None
Type: Crib	Start Date: 11/1/1955
Status: Inactive	End Date: 1/1/1958

Description: The crib is marked with a single cement AC-540 marker and Underground Radioactive Material signs.

Location: The site is located along the north wall of the 203-A Building, north of PUREX.

Release Description: UPR-200-E-17 is described as yellow, uranium contaminated soil on the 216-A-22 Crib. No date is provided for this event, but it was documented in a 1959 report. Another release occurred on April 20, 1961. A UNH tank truck overflowed on the loading apron at 203-A. One thousand three hundred and thirty five pounds of depleted uranium was lost to the ground. The solution drained through an open plug valve in the sump and then went into the 216-A-22 French Drain. No WIDS sitecode is associated with this event.

Related Sites/Structures: The site is associated with the 203-A facility and UPR-200-E-17. The pipeline associated with this drain is sitecode 200-E-159-PL.

Process Description: The 203-A tank farm was used for storage and shipping of uranyl nitrate hexahydrate (UNH) product and concentration of UNH waste. It consisted of 460,000 liter (100,000 gallon) stainless steel tanks for UNH storage and three smaller nitric acid tanks. Two 10-centimeter (4-inch) effluent pipes are associated with the french drain. One pipe entered the crib 0.5 meters (1.5 feet) above original grade. This pipe is no longer visible as it was covered over to stabilize contamination. The pipe from the truck loadout apron enters the site horizontally, 2.4 meters (6 feet) below grade. The excavation is 4.9 meters (16 feet) in diameter at grade and 1.8 meters (6 feet) in diameter at the bottom, with a side slope of 3:1 (V:H). Approximately 3 meters (10 feet) of gravel fills the excavation bottom, and the site is backfilled.

Waste Type: Stormwater Runoff

Waste Description: The site received the drainage from the 203-A Building truck loadout apron, the sump waste from the 203-A Building enclosure, and the heating coil condensate from the P-1 through P-4 uranyl nitrate hexahydrate (UNH) tanks. The waste is low in salt, neutral to basic, and contains less than 1 curie total beta activity. The site received some uranium from the discharges. In 1961, a release from a UNH truck spilled 1335 pounds of uranium on the truck apron. Some of this drained into the 216-A-22 crib.

Code: 216-A-26	Classification: Accepted
Names: 216-A-26; 216-A-26 French Drain; 216-A-26B; Miscellaneous Stream #464	Reclassification: None
Type: French Drain	Start Date: 1/1/1965
Status: Inactive	End Date: 1/1/1991

Description: There are no visible surface features for this drain. The unit is composed of three clay pipe (each 5 feet long) segments buried vertically. Some references state the clay pipe diameter is 3 feet and some state the diameter is 4 feet.

Location: The site is located inside the PUREX security fence, south of the 291-A Control House and approximately 4.57 meters (15 feet) south of 216-A-26A French Drain.

Related Sites/Structures: This site is associated with the 291-A Fan Control Building, the 216-A-26A french drain and pipeline 200-E-270-PL.

Process Description: This french drain was installed to replace the 216-A-26A french drain. Both drains received effluent from floor drains inside the 291-A Fan House. 216-A-26 was removed from service in 1991.

Waste Type: Water

Waste Description: The site received the floor drainage from the 291-A Fan Control House. The waste was low in salt, neutral to basic, and contains less than 1 curie of total beta activity. The quantity of discharge is unknown.

Code: 216-A-26A **Classification:** Accepted

Names: 216-A-26A; 291-A French Drain; 216-A-25 Crib; 216-A-26 French Drain **Reclassification:** None

Type: French Drain **Start Date:** 1/1/1959

Status: Inactive **End Date:** 1/1/1965

Description: There are no surface features for this drain. The unit is composed of three sections of clay pipe each 1.5 meters (5 feet) long, placed vertically end to end below grade. Some references state the pipe diameter was 0.9 meters (3 feet) and other references state the diameter as 1.2 meters (4 feet).

Location: The french drain is located inside the PUREX security fence, south of the 291-A Building.

Related Sites/Structures: The site is associated with the 291-A stack, fan house, the 216-A-26 French Drain and pipeline 200-E-270-PL.

Waste Type: Water

Waste Description: The site received the floor drainage from the 291-A Fan Control Room. The waste is low in salt, neutral to basic, and contains less than 1 curie total beta activity.

Code: 216-A-27 **Classification:** Accepted

Names: 216-A-27; 216-A-27 Crib **Reclassification:** None

Type: Crib **Start Date:** 6/1/1965

Status: Inactive **End Date:** 9/1/1970

Description: The crib is covered with gravel. It is marked and posted with Underground Radioactive Material signs. The crib is constructed of a 15-centimeter (6-inch) stainless steel perforated pipe is placed horizontally the length of the unit, 3 meters (10 feet) below grade. There is 680 cubic meters (24,000 cubic feet) of gravel fill in the excavation bottom. The site is backfilled over. The side slope is 1:1.5.

Location: The 216-A-27 Crib is located south of the PUREX facility, partially inside the double security fence.

Related Sites/Structures: The site is associated with the 293-A, 202-A and 291-A buildings. The stainless steel pipeline that feeds this crib is sitecode 200-E-196-PL.

Waste Type: Process Effluent

Waste Description: The site received the sump waste from the 293-A Building, the lab cell drainage from the 202-A Building, and the 291-A-1 Stack drainage. The waste is low in salt and is neutral to basic.

Code: 216-A-28 **Classification:** Accepted
Names: 216-A-28; 216-A-28 Crib; 216-A-28 French Drain **Reclassification:** None
Type: Crib **Start Date:** 1/1/1958
Status: Inactive **End Date:** 1/1/1967

Description: The site is not currently marked or posted.

Location: The site was located near the northwest corner of the 203-A Building, north of PUREX.

Related Sites/ Structures: The site is associated with 216-A-22, 216-A-3 and the 200-E-159-PL pipeline.

Process Description: The 203-A tank farm was used for storage and shipping of uranyl nitrate hexahydrate (UNH) product and concentration of UNH waste. It consisted of 460,000 liter (100,000 gallon) stainless steel tanks for UNH storage and three smaller nitric acid tanks. The french drain received liquid waste from the 203-A sumps and heating coil condensate from the uranyl nitrate tanks. The effluent piping to the site was blanked off in November 1976 when the flow rate exceeded the infiltration capacity. The excavation had a 6-meter (20-foot) diameter at grade and a 3-meter (10-foot) bottom diameter, with a truncated cone shape. The excavation contained approximately 2.7 meters (9 feet) of gravel fill and was backfilled to grade. The unit contained a 10-centimeter (4-inch) stainless steel 304 perforated pipe, 5.2 meters (17 feet) long, extending horizontally 1.2 meters (4 feet) below grade and a 5-centimeter (2-inch) diameter, schedule 40, perforated stainless steel liquid level riser pipe, 4 meters (13 feet) long.

Waste Type: Process Effluent

Waste Description: The site received the liquid waste from the 203-A Building enclosure sumps and the heating coil condensate from the P1 through P4 uranyl nitrate hexahydrate (UNH) tanks. The waste is low in salt and is neutral to basic. Uranium may have been discharged to the waste site.

Code: 216-A-29 **Classification:** Accepted
Names: 216-A-29; 216-A-29 Ditch; A-29 Ditch; Snow's Canyon **Reclassification:** None
Type: Ditch **Start Date:** 1/1/1955
Status: Inactive **End Date:** 1/1/1991

Description: The ditch was backfilled and surface stabilized in 1991. It is posted as an Underground Radioactive Material area.

Location: The ditch originated southeast of the 241-A Tank Farm (east of 241-AP tank farm) outside of the 200 East Area perimeter fence. The ditch emptied into 216-B-3-3 Ditch which terminated at 216-B-3 Pond.

Related Sites/ Structures: The chemical sewer line that fed the ditch is sitecode 200-E-187-PL. The ditch had two earth dams with wooden gates structures to regulated water flow. They were located at N41150, W45500 and N41550, W45200. The ditch is also associated with the 216-B-3 Pond, the 216-B-3 ditches, 200-E-286 swamp (A Swamp) and UPR-200-E-51.

Process Description: From 1946 through 1953, a shallow depression, known as the Powerhouse Swamp and also the "A Swamp" (See sitecode 200-E-286) was located at W46600/N40400. This swamp area was located approximately in the same location as the head end of the 216-A-29 ditch. The head end of the 216-A-29 ditch was modified several times. The final relocation of the head end occurred 1983, during the construction of the 241-AP tank farm. From 1955 through 1991, the

216-A-29 ditch followed a natural depression, known as Snow's Canyon, toward the 216-B-3 ditch and pond area. The ditch received waste from the PUREX facility between November 1955 and September 1991.

Waste Type: Process Effluent

Waste Description: The unit received waste from 202-A Chemical Sewer, acid fractionator condensate and condenser cooling water that flow to 216-B-3 Pond. Until December 1957, the site received process cooling water and chemical sewer waste from 202-A. From December 1957 to February 1958, the site received all of the above, but the process cooling water was rerouted to 216-A-25 Pond. From February 1958 to December 1962, the ditch received the above plus acid fractionator condensate from 202-A. From December 1962 to December 1963, the ditch also received seal cooling water from air sampler vacuum pumps in 202-A. From December 1963 to January 1966 the vacuum pump cooling water was rerouted to 216-A-35 French Drain.

Code: 216-A-30

Classification: Accepted

Names: 216-A-30; 216-A-30 Crib

Reclassification: None

Type: Crib

Start Date: 1/1/1961

Status: Inactive

End Date: 1/1/1992

Description: The crib is surrounded with concrete AC-540 markers and posted with Underground Radioactive Material signs.

Location: The crib is located outside the 200 East Area perimeter fence, east of the 202-A Building.

Related Sites/ Structures: The crib is associated with PUREX operations. Two 8-inch (20 cm) carbon steel gage wells extending from the bottom to 3 ft (0.9 m) above grade. A 15-inch (38 cm) diameter vent riser extending from the distribution pipe to 3 ft (0.9 m) above grade. Two 16-in (41 cm) by 16-inch (41 cm) by 8-inch (20 cm) concrete pads supporting the gage wells. 47,720 square feet (4430 square meters) of polyethylene sheets were added. The site is associated with the 216-A-6 Crib. The pipeline from PUREX associated with this crib is sitecode 200-E-113-PL and 200-E-260-PL. The pipeline from the 216-A-37-1 distribution box to the 216-A-30 crib distribution box is sitecode 200-E-232-PL. The pipeline from 216-A-30 to the 216-A-37-2 Distribution Box is 200-E-233-PL.

Process Description: The unit includes two distribution pipes: one 38 cm (15 inch) corrugated perforated pipe running approximately 1.2 meters (4 ft) below grade to the center of the unit, the other a 41 cm (16 inch) steel pipe running parallel to the other, 1.2 meters (4 ft) below grade to the center of the unit, then angling 45 degrees and changing to a 38 cm (15 inch) corrugated, perforated pipe running 2.1 to 2.4 meters (7 to 8 ft) below grade to the end of the unit. It is filled with 1.5 meters (5 ft) or a total of 3,480 cubic meters (123,000 cu ft) of gravel, and the site has been backfilled. The side slope is 1.5:1.

Waste Type: Process Effluent

Waste Description: Until 11/65, the site received the steam condensate, equipment disposal tunnel floor and water-filled door drainage, and the slug storage basin overflow waste from 202-A Building. From 11/65 to 1/70, the 216-A-6 Crib was restored to service to receive some of the above effluents because the effluent flow rate had exceeded the infiltration capacity of this unit. From 1/70 to 6/92, the site received the above effluent because the 216-A-6 Crib was deactivated. The waste was low in salt and is neutral to basic. TPA Milestone M-17-22A required that PUREX steam condensate discharge to 216-A-30 Crib be discontinued by June 1992. The fourth amendment to the TPA (89-10 Rev 3) documents that the steam condensate stream was shut down in June 1992 and that all discharges to this crib were discontinued. The unit was permanently isolated in 1995.

Code: 216-A-33	Classification: Accepted
Names: 216-A-33; 216-A-33 Dry Well; 216-A-26B	Reclassification: None
Type: French Drain	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1964
Description: The 291-AE Filter Building has been built over top of the site where this drain was located. The stainless steel (M21-UD) inlet pipe entered the unit 1.5 meters (5 feet) below grade. The french drain had a carbon steel cover.	
Location: The site is located inside the PUREX security fence, south of 202-A, and southwest of the 291-A stack.	
Related Sites/ Structures: The french drain is associated with the 291-A Fan House and pipeline 200-E-269-PL.	
Waste Type: Process Effluent	
Waste Description: The site received the bearing coolant waste from the 291-A-1 Stack electrical exhaust fans. The waste is low in salt, neutral to basic, and contains less than 1 curie of total beta activity.	

Code: 216-A-34	Classification: Accepted
Names: 216-A-34; 216-A-34 Crib; 216-A-34 Ditch	Reclassification: None
Type: Ditch	Start Date: 11/1/1955
Status: Inactive	End Date: 12/1/1957
Description: The site is marked and posted with Underground Radioactive Material signs. It has a small amount of bunch grass vegetation growing on it. In February 2001, a posted Soil Contamination Area extended northward from the edge of 216-A-34 to 216-A-19.	
Location: The site is located east of the 200 East Area perimeter fence. It is north of the 216-A-8 crib.	
Related Sites/ Structures: The site is associated with the 241-A-431 building, the 216-A-19 trench and the 216-A-20 trench. The pipeline to the 216-A-34 crib is discussed in sitecode 200-E-166-PL and UPR-200-E-145.	
Process Description: The site received cooling water from the contact condenser in the 241-A-431 building. Drawings indicate a 38 centimeter (15 inch) diameter clay pipe fed 216-A-34 and was connected to the headwall. Ditch effluent was routed to the 216-A-19 and 216-A-20 trenches. Maxfield (1979) describes the site as two ditches; one ditch measuring 85 meters (280 feet) long and 9 meters (30 feet) wide and a second ditch measuring 39.6 meters (130 feet) long and 9 meters (30 feet) wide. However, it is not clear if there were two ditches or actually a headwall structure and a ditch. The Maxfield ditch dimensions are similar to the headwall structure dimensions. Drawings show the headwall width was 3 meters (10 feet) wide at the west end fanning out to 12 meters (40 feet) wide at the east end. The headwall structure had 1:2 side slopes. The headwall structure was 39.6 meters long (130 feet). It tapered off into an open ditch. The ditch terminated in the 216-A-20 Grave. No documentation has been located to describe how the effluent was directed to the 216-A-19 Grave.	
Waste Type: Water	
Waste Description: The site received the cooling water from the contact condenser in the 241-A-431 Building in route to the 216-A-19 and 216-A-20 Trenches. The site contains less than 1 curie total beta activity.	

Code: 216-A-36A	Classification: Accepted
Names: 216-A-36A; 216-A-36 Crib	Reclassification: None
Type: Crib	Start Date: 9/1/1965
Status: Inactive	End Date: 3/1/1966

Description: The 216-A-36A and 216-A-36B cribs are located inside a common light post and chain area. The 216-A-36A is the at the north end of the chained area. The large chained area is posted with Underground Radioactive Material signs. The risers near the center of the cribs had been posted with Soil Contamination signs, but were surface stabilized in May 2010.

Location: The crib is located south of the 202-A Building and west of Canton Avenue, outside the security fence.

Related Sites/ Structures: The pipeline associated with this crib is 200-E-253-PL.

Process Description: The 216-A-36A portion of the crib was activated in September 1965 to receive ammonia scrubber waste from PUREX. A new annular dissolver was installed in A cell in October 1965. Shortly after the start up of the new dissolver system, it was noted that significant quantities of fission products were being flushed to the 216-A-36A Crib. Monthly discharge records estimated that approximately 135,000 curies of fission products, that included 610 curies of cesium-137 and 625 curies of strontium-90, had been release to the crib from October 1965 through January 1966. In December 1965, a test well was drilled into the crib to determine the extent of the fission products in the ground and to determine if the crib should continue to be used. On December 29, 1965, a soil sample was collected from the boring that read between 300 and 500 R/hour. Work was stopped and special procedures, including use of long handled tongs and exposure time monitoring, were required for handling and disposing of the excavated material. It was calculated that approximately 400,000 curies of contaminants had been discharged to the crib that included 1600 curies of cesium-137. The 216-A-36A portion of the crib was terminated in March 1966. The existing pipeline was extended to the 216-A-36B portion of the crib. A 29 meter (95 foot) concrete dam was placed between the 216-A-36A and 216-A-36B crib sections. The original excavation is 183 meters (600 feet) long by 3.4 meters (11 feet) wide by 6.7 meters (22 feet) deep with a 1:1.5 backslope. The excavation has 0.9 meters (3 feet) of gravel fill and a 15-centimeter (6-inch) M-8 (stainless steel) perforated pipe is placed horizontally. A plastic barrier separates the gravel from the overlying backfill and the site has been backfilled to original grade. The northernmost 30.5 meters (100 feet), now called 216-A-36A, was isolated and deactivated. The remaining 152 meters (500 feet) of the crib was renamed 216-A-36B and remained active during the majority of PUREX operation.

Waste Type: Process Effluent

Waste Description: The site received the ammonia scrubber waste from the 202-A Building. The waste is low in salt and is neutral to basic. The site was deactivated because of a large discharge of fission products. In December 1965, it was calculated (from bore hole soil samples) that approximately 400,000 curies of contaminants had been discharged to the crib that included 1600 curies of cesium-137.

Code: 216-A-36B	Classification: Accepted
Names: 216-A-36B; Purex Ammonia Scrubber Distillate (ASD); 216-A-36 Crib	Reclassification: None
Type: Crib	Start Date: 3/1/1966

Status: Inactive**End Date:** 9/6/1987

Description: The 216-A-36B portion of the crib is located inside the same light post and chain area as the 216-A-36A Crib. The 216-A-36B is the southern end of the chained area. The large chained area is posted with Underground Radioactive Material signs. The risers near the center of the cribs had been posted with Soil Contamination Area signs, but were surface stabilized in May 2010. The 216-A-36B portion of the chained area is considerably larger than the 216-A-36A portion.

Location: The crib is located south of the 202-A Building and west of Canton Avenue, outside the security fence.

Release Description: During the week of May 21 to May 28, 1970, an abnormally large quantity of radionuclides was discharged to the A36-B crib. A letter from C. W. Malody reports that the volume was 1.6 million liters (420,000 gallons), and the sample analysis showed 9.3 kilograms (20.5 pounds) of uranium; 82.3 grams (2.9 ounces) of plutonium; 15,900 Curies of total beta; 9,050 Curies of 95-zirconium; 4,390 Curies of 106-ruthenium; and 5,800 Curies of 144-cerium were released to the crib during those dates. For 1969, the 12 month total of waste to the crib was 10 kilograms (22 pounds) of uranium; 7.2 grams (2.5 ounces) of plutonium; 1790.8 Curies of beta; 6.6 Curies of cobalt-60; 99.1 Curies of strontium-90, 110.2 Curies of cesium-137, and 454.0 Curies of ruthenium-106 in 17.8 million liters (4.695 gallons) volume of liquid.

Related Sites/Structures: The site is associated with 202-A facility and 216-A-36A Crib. The pipeline associated with this crib is 200-E-253-PL.

Process Description: The 216-A-36B Crib was built to replace the 216-A-36A Crib, that had been terminated due to the large amounts of fission products discharged to it. The 216-A-36B Crib was constructed by extending the pipeline from the 216-A-36A Crib in March of 1966. A concrete dam was placed between the two portions of the crib. The 216-A-36B crib received ammonia scrubber waste from the PUREX process. Fuel rods from the 100-N reactor were clad in zirconium. Removal of the zirconium cladding required using ammonium fluoride and ammonium nitrate solutions (AFAN). The dissolving process produced a large amount of ammonia offgasses. The offgas was scrubbed with water to reduce the amount of water released to the air. Spent ammonia scrubber waste was transferred to a concentrator where the waste was distilled. The crib received discharge condensate from the waste stream concentrator. The unit is a gravel structure with a 15-centimeter (6-inch) M-8 perforated pipe placed horizontally, 7 meters (23 feet) below grade. The excavation has 620 cubic meters (22,000 cubic feet) of gravel fill, and the site has been backfilled. The side slope is 1:1.5.

Waste Type: Process Effluent

Waste Description: Until October 1972, the site received the ammonia scrubber waste from the 202-A Building (Plutonium Uranium Extraction [PUREX]). The site was retired in October 1972 when the PUREX plant shut down. In November 1982, the site was reactivated to receive the above wastes when PUREX operations resumed. The waste is low in salt and is neutral to basic. The concentrations of ammonium hydroxide discharged to the crib resulted in the waste stream being classified as a dangerous waste. During the week of May 21 to May 28, 1970, an abnormally large quantity of radionuclides was discharged to the A36-B crib. A letter from C. W. Malody reports that the volume was 1.6 million liters (420,000 gallons). The sample analysis showed 9.3 kilograms (20.5 pounds) of uranium; 82.3 grams (2.9 ounces) of plutonium; 15,900 Curies of total beta; 9,050 Curies of 95-zirconium; 4,390 Curies of 106-ruthenium; and 5,800 Curies of 144-cerium were released to the crib during those dates. For 1969, the 12 month total of waste to the crib was 10 kilograms (22 pounds) of uranium; 7.2 grams (2.5 ounces) of plutonium; 1790.8 Curies of beta; 6.6 Curies of cobalt-60; 99.1 Curies of strontium-90, 110.2 Curies of cesium-137, and 454.0 Curies of ruthenium-106 in 17.8 million liters (4.695 gallons) volume of liquid.

Code: 216-A-37-1	Classification: Accepted
Names: 216-A-37-1; 216-A-37 Crib	Reclassification: None
Type: Crib	Start Date: 1/1/1977
Status: Inactive	End Date: 1/1/1989

Description: The crib is marked and surrounded with concrete AC-540 markers and Underground Radioactive Material signs.

Location: The unit is located outside of the 200 East Area perimeter fence, east of the 202-A Building.

Related Sites/ Structures: The site is associated with the 242-A Evaporator. The pipeline from 207-A to 216-A-37-1 is sitecode 200-E-232-PL.

Process Description: The crib received process condensate waste from the 242-A Evaporator facility. The unit is a gravel structure with a 25-centimeter (10-inch) corrugated, galvanized, perforated pipe located horizontally, 2.1 meters (7 feet) below grade. The excavation contains 1.5 meters (5 feet) of gravel fill with a volume of 150 cubic meters (5,300 cubic feet) and has been backfilled over. The side slope is 1:1.

Waste Type: Process Effluent

Waste Description: The site received process condensate from the 242-A Evaporator. The process condensate had been determined to be regulated as a mixed waste due to the presence of spent halogenated and nonhalogenated solvents and for the toxicity of ammonia. The estimated annual quantity of dangerous waste was 4.912E+07 kilograms (1.083E+08 pounds), representing the maximum annual output of evaporator process condensate during operating campaigns.

Code: 216-A-37-2	Classification: Accepted
Names: 216-A-37-2; 216-A-37-2 Crib	Reclassification: None
Type: Crib	Start Date: 1/1/1983
Status: Inactive	End Date: 1/1/1995

Description: The crib is marked with concrete AC-540 posts and Underground Radioactive Material signs.

Location: The crib is located outside the 200 East Area perimeter fence, east of the 216-A-37-1 Crib on the same centerline, directly north of the 216-A-30 Crib.

Related Sites/ Structures: The crib is associated with the 202-A (PUREX) facility and the 216-A-30 crib. The pipeline connecting the 216-A-30 crib to 216-A-37-2 is sitecode 200-E-233-PL.

Process Description: The crib was built as a replacement for the 216-A-30 crib. The crib received PUREX steam condensate waste. There are two steel drain pipes. One is perforated and runs the length of the unit, and the other is unperforated and runs from west to east only to the center of the unit, 1.5 meters (5 feet) above the bottom. Two vents are located at the center and at the east end. Two liquid-level gage wells are located 106 meters (350 feet) from the ends of the unit. A bed of gravel on the bottom has been covered with a 20 millimeter PVC barrier cover.

Waste Type: Steam Condensate

Waste Description: The site received steam condensate from PUREX (parallel operation of this unit and 216-A-30). The PUREX steam condensate stream was shut down in June 1992 (DOE/RL-82-28). TPA milestone M-17-22A required that PUREX steam condensate discharge to 216-A-37-2 Crib be discontinued by June 1992.

Code: 216-A-38-1	Classification: Accepted
Names: 216-A-38-1; 216-A-38 Crib	Reclassification: None
Type: Crib	Start Date:
Status: Inactive	End Date:

Description: The crib is surrounded by light posts and a chain. It is posted with Underground Radioactive Material signs. There are no concrete AC-540 markers or signs to label the site.

Location: The crib is located southwest of 202-A Building north of 1st Street. It is located south of the PUREX security fence.

Related Sites/ Structures: The site is associated with the 216-A-10 crib. The pipeline to the 216-A-38-1 crib is sitecode 200-E-240-PL. There are two radiological test wells (one at each end of the crib).

Process Description: The crib was built to replace the 216-A-10 crib, but had not been activated when plans for modifying the PUREX head end process were begun. The planned building addition would have been constructed immediately adjacent to the crib. For this reason, the crib was activated. The site is identified in the project proposal (Project IAP-606) as the PUREX Process Condensate Crib - 216-A-38. It was intended to receive the PUREX process condensate waste that was being discharged to the 216-A-10 Crib. The 216-A-10 was showing signs of strontium-90 saturation. The replacement crib was required for continued disposal for the disposal of large volumes [1,040,000 to 1,230,000 liters (275,000 to 325,000 gallons per day)] of condensate waste. There was a potential for this process condensate to become grossly contaminated as a result of reduced vapor phase deentrainment or foaming in the concentrator. The location for the 216-A-38-1 Crib was chosen to shorten piping runs and take advantage of the high percolation rate [76 to 95 liters (20-25 gallons)] per day per square foot. The existing 216-A-10 crib could not be depended upon for continued disposal of process condensate. It had been in operation since June 1961 (five years), and had received about 1,800 million liters (475 million gallons) of condensate which contained about 115,000 curies of beta activity (as of June 1966). Strontium-90 had been verified to be in the groundwater under the crib. There is a 15-centimeter (6-inch) perforated stainless steel distribution pipe (from PUREX and running the length of the crib) reducing to 10-centimeter (4-inch) perforated pipe placed at 10 meters (33 feet) below grade. This pipe was isolated with the installation of a blind flange in 1989. There is 1.5 meters (5 feet) of gravel in the excavation with a membrane barrier between the gravel and the backfill. The excavation was backfilled with excavated material. The side slopes of the excavation were cut at 1:1.

Waste Type: Process Effluent

Waste Description: Although the crib was built to receive PUREX effluent, it was never used.

Code: 216-A-40	Classification: Accepted
Names: 216-A-40; 216-A-40 Retention Basin; 216-A-39 Crib; 216-A-39 Trench	Reclassification: None
Type: Retention Basin	Start Date: 1/1/1968
Status: Inactive	End Date: 1/1/1979

Description: The waste site is a demolished retention basin that was Interim Stabilized. The reduced footprint of the structure was posted with Underground Radioactive Material signs. The corners are marked with concrete AC-540 markers. Some contaminated equipment is being stored on top of the backfilled basin. The stored equipment is posted Radioactive Material Area/Contamination Area.

Location: The site is located northwest of the 244-AR Vault. It is approximately 152 meters (500 feet) west of the 241-AX Tank Farm and approximately 152 meters (500 feet) south of 7th Avenue.

Related Sites/ Structures: The site is associated with the 244-AR Vault facility, UPR-200-E-143, UPR-200-E-100 and UPR-200-E-59. Pipelines associated with the basin are 200-E-274-PL and 200-E-275-PL.

Process Description: The 216-A-40 Basin was built to retain diverted contaminated water from 244-AR Vault. The basin was originally an open, rubber lined trench that was divided into 3 sections. A 0.3 meter (12 inch) diameter schedule 40 distribution pipe ran horizontally through the south end of the unit, 3.7 meters (12 feet) below grade. Collapsible rubber bladders (200,00 gallon capacity) were utilized to contain the contaminated cooling water and steam condensate. Contaminated cooling water and steam condensate from the 244-AR Vault were diverted to the 216-A-40 Retention Basin when the effluent was above standard release limits for the water to be sent to the 216-B-3 or 216-A-25 Ponds. The retention basin bladders failed in 1979 and the unit was removed from service. Although it was not being used, it remained an open basin until 1994. Contamination from inside the open basin affected the surrounding area via wind and animal related contamination migration.

The diverter (diversion box) was a two-compartment concrete structure with a motor driven diverter valve. Each bladder was equipped with a concrete sump and a 3 inch pipeline connected to the pump caisson (lines 321, 322 and 324). The pump pit caisson was connected to a pipeline (line 323 - see WIDS sitecode 216-E-274-PL) that routed contaminated water into the tank farm system, via the 244-A lift station. The cooling water diverter box was associated with WIDS sitecode 200-E-275-PL.

Waste Type: Steam Condensate

Waste Description: The site received and stored in rubber bladders, the diverted cooling water and steam condensate from the 244-AR Vault.

Code: 216-A-41 **Classification:** Accepted

Names: 216-A-41; 216-A-41 Crib; 291-AR Stack Drain; 296-A-13 Stack Drain **Reclassification:** None

Type: Crib **Start Date:** 1/1/1968

Status: Inactive **End Date:** 1/1/1974

Description: The site is a small crib that is no longer marked or posted. The area where the crib is assumed to be located is covered with gravel.

Location: The crib is located northwest of the 296-A-13 stack, west of Buffalo Ave. and north of the 244-AR Vault facility.

Related Sites/ Structures: The crib is associated with the 296-A-13 Stack (291-AR Filter Building Stack) (WIDS Site 296-A-13) and the 291-AR Filter Building. The Filter Building is related to the 244-AR Vault Canyon. The pipeline to the crib is 200-E-276-PL.

Process Description: The crib received drainage from the 296-A-13 Stack (WIDS Site 296-A-13). The stack is connected to the 291-AR Filter Building. The bottom of the crib (elevation: 207 meters [678.5 feet]) is filled with 0.5 meters (1.5 feet) of 3.8 to 25.4-centimeter (1.5 to 10-inch) rock, then 20.3 centimeters (8 inches) of 1.9 to 3.8-centimeter (0.75 to 1.5-inch) gravel, and several centimeters of 1.9-centimeter (0.75-inch) gravel. This material is covered by a layer of 20 millimeter polyethylene and 10.2 centimeters (4 inches) of sand (elevation: 208 meters [681.0 feet]). The site was then backfilled with soil to a ground elevation of 209 meters (684.0 feet) (with the crown at 212 meters [696.0 feet]). The side slope is 1:1. A 10.2-centimeter (4-inch) vitrified clay pipe enters the crib (from the 296-A-13 Stack) at elevation 208 meters (681.0 feet)

and connects to the crib dispersion structure, constructed of 20.3 by 20.3 by 40.6-centimeter (8 by 8 by 16-inch) bond beam concrete blocks placed end-to-end. The pipeline from the stack (296-A-13) to the crib is approximately (15 feet) long and extends northwest (30 degrees west of true north) from the stack. The site is not marked in the field. The mapped center point location of the site is based on drawing coordinates from H-2-61975, "216-A-41 Crib, Plan and Profile". Drawing H-2-44501, "Area Map-200 East, A Plant Facilities", shows the crib at the same location.

Waste Type: Steam Condensate

Waste Description: The site received the 296-A-13 Stack condensate drainage. According to RHO-CD-673, the waste was potentially slightly acidic and contained less than 1 curie total beta activity. Potential contaminants of concern (Stenner) may be tritium, cobalt-60, strontium-90, and cesium-137.

Code: 216-A-42 **Classification:** Accepted

Names: 216-A-42; 216-A-42 Retention Basin; 216-A-42 Trench; 207-AA Retention Basin **Reclassification:** None

Type: Retention Basin **Start Date:** 1/1/1978

Status: Inactive **End Date:** 1/1/1997

Description: The site is surrounded with steel posts and chain. It is posted with Underground Radioactive Material signs. Concrete cover blocks are visible on the top of the basin. The chain link fence has been removed. The site consists of a rubber-lined trench divided into three holding basins by two internal berms. One end of the trench features the inlet structure for the 91-centimeter (36-inch) diameter cooling water line while the other end has the inlet structure for the 20.3-centimeter (8-inch) diameter steam condensate pipeline. Both lines enter at 2.9 meters (9.5 feet) below grade. Outlet drains are located at the low-points in each basin and connect to the 216-A-42A Pump Station. The capacity of the three basins is in excess of 6.1E+06 liters (1.6E+06 gallon). The trench is equipped with a float. Concrete cover blocks were installed over the basins in 1984.

Location: The retention basin is located outside the eastern 200 East Area security fence. It is east of the 202-A Building, directly east of the 216-A-6 Crib.

Related Sites/Structures: The basin is associated with PUREX facility effluents, 216-A-30, 216-A-37-2, 216-B-3, 216-A-25 and UPR-200-E-66. The PUREX Recycle pipeline is 200-E-261-PL. Other pipelines associated with the basin operation are 200-E-113-PL, 200-E-262-PL and 200-E-263-PL.

Process Description: The 216-A-42 Retention Basin was built to hold cooling water or steam condensate that was contaminated above standard release limits and prevent its disposal to the Gable and B Pond systems or to cribs. After the retained effluent contents were analyzed, a built-in recovery system provided the capability of pumping solutions back into the PUREX facility for reprocessing (see sitecode 200-E-261-PL) or to cribs for disposal. Prior to the construction of the 241-AP Tank Farm (1983), the basin was connected to the 0.9 meter (36 inch) diameter corrugated metal pipeline (200-E-127-PL) that flowed to the Gable and B Ponds. A 0.3 meter (1 foot) diameter chemical sewer line (200-E-187-PL) tied the basin to the 216-A-29 ditch. Portions of the chemical sewer line and the corrugated metal pipe were removed during the 241- AP Tank Farm construction.

Waste Type: Process Effluent

Waste Description: The unit received chemically or radioactively contaminated diversions from the PUREX chemical sewer line, cooling water line, and steam condensate lines. Depending upon the treatment required for the contaminant, the waste was released from the unit to the 216-A-30, 216-A-37-1 and 216-A-37-2 Cribs, to PUREX process piping, or to the Tank Farms.

Code: 216-A-45	Classification: Accepted
Names: 216-A-45; 216-A-45 Crib	Reclassification: None
Type: Crib	Start Date: 3/4/1987
Status: Inactive	End Date: 9/1/1991

Description: The crib is surrounded with light post and chain. It is posted as an Underground Radioactive Material area. There is a considerable amount of vegetation growing on the crib surface.

Location: The 216-A-45 Crib is located south of the PUREX facility, southwest of the 216-A-10 Crib.

Release Description: On April 2, 1987, more than 5 pounds of pure nitric acid in 6200 pounds of water was discharged to the 216-A-45 crib. The ph was greater than 2.0. The release was neutralized by adding additional carbonate to the A5 neutralization tank (sitecode 200-E-58).

Related Sites/ Structures: The crib is associated with the 202-A facility. The pipeline that fed this crib is sitecode 200-E-231-PL.

Process Description: The unit has an associated drain field consisting of five 10-centimeter (4 inch) diameter perforated, fiberglass-reinforced pipes evenly spaced across the width. At the bottom is 1.7 meters (5.5 feet) of clean rock, 8 to 13 centimeters (3 to 5 inches) in diameter. A layered cover consisting of a 15 centimeters (6 inches) layer of 8 to 13 centimeters (3 to 5-inch) diameter clean rock, a 15 centimeters (6-inch) layer of 1.9-centimeter (3/4-inch) gravel, a sheet of 10-mil polyethylene, and a 10-centimeter (4-inch) layer of sand are placed over the unit.

Waste Type: Process Effluent

Waste Description: The unit received process condensate from the 202-A Building (PUREX). Discharge to this crib was discontinued in mid-1989 and the waste stream was routed to storage tanks (WHC-EP-0367). TPA milestone M-17-20A required all discharge to the 216-A-45 Crib be ceased by September 1991. The Fourth Amendment to the TPA confirms that this milestone was met.

Code: 207-B	Classification: Accepted
Names: 207-B; 207-B Retention Basin; B Plant Retention Basin	Reclassification: None
Type: Retention Basin	Start Date: 1/1/1945
Status: Inactive	End Date: 1/1/1997

Description: The unit is a concrete-lined basin, divided into two equal sized sections. The basin is surrounded by a 2.4 meter (8 foot) chain link fence and posted with Contamination Area signs.

Location: The site is located inside 200 East Area, northeast of the 221-B Building and south of the 241-B Tank Farm. It is on the east side of Baltimore Ave.

Related Sites/ Structures: The basin has an inlet structure on the west and an outlet structure on the east side. There are two 0.9 square meter (3 square foot) sumps, one for each basin section. The basin is also associated with UPR-200-E-32. The 200-E-112-PL pipeline connects to the west side of the retention basin. The valve box on the east side of the retention basin tied into the pipeline that fed the 216-B-63 Ditch (sitecode 216-E-191-PL). The B Plant Chemical Sewer pipeline (200-E-188-PL), the pipeline to the 216-B-2-1 and 216-B-2-2 ditches (200-E-204-PL) and the pipeline to the 216-B-2-3 ditch (200-E-205-PL) are connected to the valve pit located east of the valve box. The pipeline from 242-B to the basin is sitecode 200-E-264-PL. The cooling water pipeline from 241-BY tank farm to the basin is 200-E-265-PL. In 1987, the entire 216-B-2 ditch system was replaced with a single pipeline (200-E-126-PL) that connected the 207-B retention basin to the 216-B-3 ditch and pond system.

Process Description: The retention basins served as settling basins, receiving B Plant process sewer effluent through an underground pipeline prior to being discharged to the 216-B-2-1, 216-B-2-2, 216-B-2-3 ditches. It was possible to divert effluent to the 216-B-63 ditch. The 216-B-2-1, 216-B-2-2 and 216-B-2-3 ditches were connected to the 216-B-3 ditches and ponds. The 242-B Evaporator also discharged to the 207-B Retention Basin.

Waste Type: Water

Waste Description: The unit received process cooling water from process equipment jackets in the 221-B Building. Normally, activity levels were low, and the water was discharged to the 216-B-3 Pond via the 216-B-2-1, 216-B-2-2, 216-B-2-3 and 216-B-3-1, 216-B-3-2 and 216-B-3-3 ditches. The valve box on the east side of the retention basin tied into the pipeline that fed the 216-B-63 Ditch (sitecode 216-E-191-PL). The B Plant Chemical Sewer pipeline, a pipeline from 242-B Evaporator building and a cooling water pipeline from 241-BX tank farm also fed the retention basin.

Code: 216-B-2-1 **Classification:** Accepted

Names: 216-B-2-1; 216-B-2W; B Ditch; B Swamp Ditch; 216-B-1; 216-B-2 **Reclassification:** None

Type: Ditch **Start Date:** 4/1/1945

Status: Inactive **End Date:** 11/1/1963

Description: The ditch has been backfilled and surface stabilized. It is located within a larger Underground Radioactive Material area that includes the 216-B-2-1, 216-B-2-2 and 216-B-2-3 stabilized ditches. In 2015, an additional 28,000 square feet of bio-barrier material and gravel was added to the surface where growing contaminated tumbleweed had been found.

Location: The ditch is located in the northeast quadrant of 200 East Area. The head end of the unit is located near the east side of the 207-B Retention Basin. The ditch ran in an east-west direction until it connected to a section of underground pipeline near the northeast corner of 218-E-12A Burial Ground.

Release Description: The first 305 meters (1000 feet) became grossly contaminated in 1963 (See UPR-200-E-32).

Related Sites/Structures: The ditch is associated with B-Plant, 207-B, 216-B-3-1, 216-B-3 and UPR-200-E-32. The pipelines associated with the ditch are WIDS sitecodes 200-E-112-PL, 200-E-188-PL and 200-E-204-PL.

Process Description: Process effluent from B-Plant was routed to the 207-B Retention Basin. Effluent was released from the 207-B Retention Basin to the 216-B-2-1 ditch that connected to the 216-B-3-1 ditch and terminated in the 216-B-3 Pond. The 216-B-2-1 ditch was closed after it was grossly contaminated by a coil leak effluent release from B-Plant in 1963 (UPR-200-E-32). It was replaced by the 216-B-2-2 ditch.

Waste Type: Process Effluent

Waste Description: Until March 1952, the site transported steam condensate, process cooling water, and chemical sewer from 221-B waste. After March 1952, the site transported the streams identified above in addition to the 241-CR Vault cooling water.

Code: 216-B-2-2 **Classification:** Accepted

Names: 216-B-2-2; 216-B-2-2W; 216-B-1 Ditch **Reclassification:** None

Waste Type: Process Effluent

Waste Description: From April 1970 to July 1973, the site transported and percolated the 241-CR Vault cooling water, 221-B Plant cooling water, and condenser cooling water from 241-BY Tank Farm ITS (In Tank Solidification) Units 1 and 2. The waste flowed into the 216-B-3 Pond. After July 1973, the ditch received the above-listed effluents except from 241-BY Tank Farm ITS Units 1 and 2.

Code: 216-B-6 **Classification:** Accepted

Names: 216-B-6; 216-B-6 Crib; 216-B-6 Dry Well; 222-B-110 Dry Well; 222-B-110 Reverse Well **Reclassification:** None

Type: Injection/Reverse Well **Start Date:** 1/1/1945

Status: Inactive **End Date:** 1/1/1949

Description: A concrete AC-540 post marks the location of this site and is labeled as an Underground Radioactive Material site. The reverse well is a 15.25-centimeter (6-inch) diameter pipe extending 48 meters (160 feet) below ground surface. The lower 7.6 meters (25 feet) of casing is perforated. The vent pipe was cut below grade.

Location: The reverse well is located 3.6 meters (12 feet) west and 0.9 meters (3 feet) north of the 222-B Building.

Related Sites/Structures: This reverse well is associated with the 222-B Laboratory.

Process Description: The reverse wells at 222-T and 222-B were installed to provide disposal for the laboratory hot sink and sample table. During the bismuth phosphate fuel separation process, batch samples were analyzed in the 222-T and 222-B laboratories. HW-4850, written in 1945, states that the 222-T laboratory was discharging approximately 2.6 curies of fission products and 600 milligrams of plutonium to the dry well per month. Since similar work was done at the 222-B Laboratory, similar waste inventory can be assumed.

Waste Type: Process Effluent

Waste Description: The site received decontamination sink and sample slurper waste from 222-B Building. The site contains not less than 10 curies total beta. HW-4850, written in 1945, states that the 222-T laboratory was discharging approximately 2.6 curies of fission products and 600 milligrams of plutonium to the dry well per month. Since similar work was done at the 222-B Laboratory, similar waste inventory can be assumed. The waste is acidic and contains transuranics and fission products.

Code: 216-B-10A **Classification:** Accepted

Names: 216-B-10A; 222-B-1 Crib; 292-B Drainage; 216-B-10 Crib **Reclassification:** None

Type: Crib **Start Date:** 12/1/1949

Status: Inactive **End Date:** 1/1/1952

Description: The unit is a 3.7 by 3.7 by 1.1 meters (12 by 12 by 3.5 feet) wooden structure in an excavation. The side slope is 1:1. The bottom of the excavation is 6.1 meters (20 feet) below grade. The structure is not gravel-filled and has cave-in potential. The surface of the unit has subsided about 0.9 meters (3 feet) in the center, possibly indicating deterioration of the lumber. The site is marked and posted with Underground Radioactive Material and Cave-In-Potential signs.

Location: The unit is located south of the west end of 222-B Building.

Related Sites/ Structures: The pipelines associated with this crib are WIDS sitecodes 200-E-174-PL and 200-E-175-PL.

Waste Type: Process Effluent

Waste Description: Until December 1951, the site received the decontamination sink and sample slurper waste from 222-B Building and floor drainage from 292-B Building. After December 1951, the site received the same as above minus the 222-B Building waste. The waste is acidic and contains transuranics and fission products.

Code: 216-B-10B **Classification:** Accepted

Names: 216-B-10B; 222-B-2 Crib; 216-B-10 Crib **Reclassification:** None

Type: Crib **Start Date:** 12/1/1949

Status: Inactive **End Date:** 10/1/1973

Description: The unit is a 3.7 by 3.7 by 1.1-meter (12 by 12 by 3.5-foot) wooden structure in an excavation. The side slope is 1:1. The bottom of the excavation is 6.1 meters (20 feet) below grade. The structure is not gravel-filled and has cave-in potential. The earth has subsided about 0.9 meters (3 feet) over the top of the unit. No site marker post is present.

Location: The unit is located south of the west end of 222-B Building.

Related Sites/ Structures: The pipeline associated with this crib is WIDS sitecode 200-E-174-PL.

Waste Type: Process Effluent

Waste Description: From December 1949 to December 1951 the site received the decontamination sink and sample slurper waste from the 222-B Building and the floor drainage from the 292-B Building. From December 1951 to May 1969 the site received only the floor drainage from the 292-B Building. From May 1969 to October 1973 the site received only the decontamination sink and shower waste from the 221-BC Building.

Code: 216-B-12 **Classification:** Accepted

Names: 216-B-12; 216-ER Crib; 216-ER-1,2,3 Cribs **Reclassification:** None

Type: Crib **Start Date:** 11/1/1952

Status: Inactive **End Date:** 11/1/1973

Description: The crib is marked and posted with Underground Radioactive Material and Cave-in Potential signs.

Location: The unit is located northwest of the 221-B Building and north of 7th Street.

Related Sites/ Structures: The crib is associated with the 270-E-1 neutralization pit, 216-B-62 crib and the 200-E-160-PL and 200-E-162-PL pipelines.

Process Description: The 216-B-12 crib originally received 221-U and 224-U condensate waste, transported from 200 West Area via the Cross Site Transfer Line (line V219). The crib also received condensate waste from 221-B Plant via pipeline 200-E-160-PL and later via 200-E-162-PL. A lateral pipe extends to 216-B-12, crib #2, from the 200-E-162-PL pipeline, that also fed the 216-B-62 crib.

The crib received 221-U and 224-U condensate waste from November 1952 through December 1957. The crib was reactivated in May 1967 to receive condensate waste from 221-B until November 1973. A crib collapse was documented in 1973.

The unit consists of a series of 3 cascading, 4.9 by 4.9 by 3.0-meter (16 by 16 by 10-foot) high wooden boxes in an excavation. A 1.3-centimeter (0.5-inch) rock backfill lies in the bottom 3.7 meters (12 feet) of the excavation and beneath each box is approximately 1.2 meters (4 feet) of this rock. The lumber is primarily 15.2 by 20.3-centimeter (6 by 8-inch) Douglas fir. The site contains 2,900 cubic meters (3,800 cubic yards) of 1.3-centimeter (0.5-inch) gravel. The side slope is 1:1.

Waste Type: Process Effluent

Waste Description: From November 1952 to December 1957, the site received the process condensate waste from the tributyl phosphate uranium recovery processes at the 221-U and 224-U Buildings as well as B Plant condensate. From December 1957 to May 1967, the site was inactive. From May 1967 to November 1967, the site received construction waste from 221-B Building. After November 1967, the site received process condensate from 221-B Building. The waste is low in salt and is neutral to basic.

Code: 216-B-51 **Classification:** Accepted

Names: 216-B-51; 216-BY-9 Crib **Reclassification:** None

Type: French Drain **Start Date:** 1/1/1956

Status: Inactive **End Date:** 1/1/1958

Description: The site is a small Underground Radioactive Material area measuring approximately 3 meters by 3 meters (10 feet by 10 feet). The concrete drain structure extends approximately 0.3 meters (1 foot) above the ground surface. The structure is approximately 1.5 meters (5 feet) in diameter with a wooden lid. The structure is also posted with Fixed Contamination Area signs.

Location: The french drain is south of 12 Street and east of Baltimore Ave. It is north of the 241-B Tank Farm and northeast of the 216-B-8 Crib and Tile Field.

Release Description: See UPR-200-E-144

Related Sites/ Structures: The french drain is associated with 200-E-114-PL, 200-E-221-PL and UPR-200-E-144.

Process Description: The french drain received drainage from the pipeline that transferred tri-butyl phosphate waste from the 241-BY Tank Farm to the BC Cribs and Trenches. The drain was active from January 1956 to January 1958. The unit is constructed of sections of 1.5 meter (5 foot) diameter concrete pipe stacked vertically extending 30 centimeters (1 foot) above ground and 4.3 meters (14 feet) below ground. The pipe is filled with 4 meters (13 feet) of gravel. The french drain has a wood cover with vent holes.

Waste Type: Process Effluent

Waste Description: The site received drainage from the BC Crib pipeline. The pipeline carried high salt, neutral to basic scavenged tributyl phosphate waste via 241-BY tank farm to the BC Crib area. The site contains less than 10 curies total beta.

Code: 216-B-55 **Classification:** Accepted

Names: 216-B-55; 216-B-55 Crib; 216-B-55 Enclosed **Reclassification:** None

	Trench		
Type:	Crib	Start Date:	1/1/1967
Status:	Inactive	End Date:	1/1/1991
Description:	The site is marked with concrete AC-540 markers and posted with Underground Radioactive Material signs. The unit is filled with approximately 1380 cubic meters (1,800 cubic yards) of gravel. A perforated 30 centimeter (30 inch) diameter galvanized pipe runs the length of the unit, 0.9 meters (3 feet) above the bottom. The site had two gage wells of 20 centimeter (8 inch) steel pipe with a galvanized sheet metal cap. Each well extended from the crib bottom to approximately 0.9 meters (3 feet) above grade. The crib was constructed with 19,500 square feet of membrane barrier.		
Location:	The site is located west of 225-B, and north of 7th Street.		
Related Sites/ Structures:	The site is associated with the 221-B facility. The pipeline to the 216-B-55 crib is discussed in sitecode 200-E-161-PL.		
Process Description:	The site has received steam condensate from 221-B Building. The waste was low in salt and neutral to basic pH. The steam condensate was sent to the 216-B-55 Crib from 1967 to 1990. (DOE/RL-89-28) TPA milestone M-17-25 required all discharge to the crib to be ceased by Sept. 1991.		
Waste Type:	Steam Condensate		
Waste Description:	The site has received steam condensate from 221-B Building. The waste is low in salt and is neutral to basic. The steam condensate was sent to the 216-B-55 Crib from 1967 to 1990. (DOE/RL-89-28) TPA milestone M-17-25 required all discharge to the crib to be ceased by Sept. 1991.		

Code:	216-B-59	Classification:	Accepted
Names:	216-B-59; 216-B-58 Ditch; 216-B-58 Trench	Reclassification	None
Type:	Trench	Start Date:	1/1/1967
Status:	Inactive	End Date:	1/1/1974
Description:	The original 216-B-59 was an unlined trench. The site was upgraded to a retention basin in 1974 (see 216-B-59B). The lined retention basin was constructed over top of the unlined 216-B-59 trench. There are currently no visual features remaining of the unlined trench. The concrete-lined basin is enclosed by a 2 meter (6 foot) chain link fence.		
Location:	The site is located northeast of 221-B. It is on the east side of Baltimore Ave. and north of 7th Street.		
Related Sites/ Structures:	This site is associated with 216-B-59B and the 221-B facility. The pipeline that fed the site is 200-E-277-PL.		
Process Description:	The original trench (216-B-59) was designed as an emergency cooling water diversion for 221-B cooling water with radionuclide concentrations above those allowed for the existing ponds. The site was activated in 1967 and received only a single discharge of approximately 477,000 liters (126,000 gal) of waste in March 1968. The trench was upgraded in 1974 to a retention basin by adding a hypalon liner and changing its identification number to 216-B-59B. It held diverted cooling water for subsequent reprocessing. It was later upgraded again (in 1983) by replacing the hypalon liner with a concrete liner and cover.		
Waste Type:	Process Effluent		

Waste Description: The site has received process condensate from the 221-B Building Separations Facilities. TPA milestone M-17-26 required all discharge to the Crib to be ceased by Sept. 1991.

Code: 216-B-63 **Classification:** Accepted

Names: 216-B-63; 216-B-63 Ditch; 216-B-63 Trench; B Plant Chemical Sewer Ditch **Reclassification:** None

Type: Ditch **Start Date:** 1/1/1970

Status: Inactive **End Date:** 1/1/1992

Description: The site is a ditch that has been backfilled and surface stabilized. It is posted as an Underground Radioactive Material area and has Danger - Keep Out signs. Prior to stabilization, the ditch had an earth shielding berm and a side slope of 1.5:1.

Location: The site is located inside the 200 East Area, east of the 241-B Tank Farm and northeast of the 207-B Retention Basin.

Related Sites/Structures: The ditch was associated with 221-B, 225-B, and 271-B. The pipeline associated with the ditch is 200-E-191-PL. The B Plant chemical sewer pipeline is sitecode 200-E-188-PL. The chemical sewer and the pipeline to the ditch are connected to a valve pit east of the 207-B Retention Basin.

Process Description: From March 1970 to May 1970, the 216-B-63 ditch received ITS-2 cooling water. The 216-B-63 ditch began to receive B Plant chemical sewer waste in May 1970 and continued through February 1992. The ditch received chemical sewer effluent from 221-B, 225-B and 271-B. The ditch was not connected to the B Pond system. The ditch terminated south of the 218-E-12B Burial Ground. 216-B-63 was designed to also receive diverted contaminated cooling water from 207-B and prevent it from reaching the 216-B-3 Pond, but no cooling water was actually ever diverted to the 216-B-63 ditch (see DOE/RL-92-05). In August 1970, the bottom of the ditch was dredged. The dredged material was contaminated with beta/gamma levels up to 3000 counts per minute. In February 1992, Project W-003 rerouted and replaced the VCP pipeline south of 211-BA, thereby eliminating the use of the 216-B-63 ditch. The chemical sewer effluent was combined with the B Plant cooling water effluent and discharged directly to the 216-B-3 Pond.

Waste Type: Process Effluent

Waste Description: From March 1970 to May 1970, the 216-B-63 ditch received 241-BY tank farm In-Tank Solidification (ITS-2) cooling water. The site has received effluent from the 221-B, 225-B, and 271-B Building floor drains and chemical sewer wastes. Waste included corrosive (acidic and caustic) dangerous waste from the regeneration of demineralizer columns at B Plant. Radiological discharges were considered to be relatively low, with a total of approximately 8.7 curies of beta and 7.6 kilograms (16.7 pounds) of uranium. The unit has not received dangerous waste since September 1985. In 1987, two incidental acid releases occurred. In February 1992, the chemical sewer discharge to the 216-B-63 ditch was eliminated. Effluent was rerouted to 216-B-3 Ponds via underground pipelines. TPA milestone M-17-04B required the elimination of B-Plant Chemical Sewer effluent to the 216-B-63 Ditch by February 1992.

Code: 216-B-64 **Classification:** Accepted

Names: 216-B-64; 216-B-64 Crib; 216-B-64 Retention Basin; 216-B-64 Trench **Reclassification:** Interim No Action (11/29/2004)

Type: Retention Basin **Start Date:** 1/1/1974

Status: Inactive **End Date:** 1/1/1997

Description: The waste site has been evaluated and determined to require No Action. The chain link fence that once surrounded the basin has been removed. It was surrounded with light post and chain and posted as an Underground Radioactive Material Area. The basin contains a rubber bladder with a 190,000 liter (50,000 gallon) capacity. The unit is divided into two 6.1 meter (20 feet) by 19.8 meter (65 feet) sections. A concrete roof covers the basin.

Location: The retention basin is located west of the 225-B building.

Related Sites/ Structures: The basin is associated with 221-B operations and UPR-200-E-64. The pipelines to the basin are discussed in sitecode 200-E-163-PL.

Process Description: The basin was built to serve as an emergency diversion basin for steam condensate that exceeded crib release limits. Under normal conditions the steam condensate stream flowed through the BCS diverter station located at the south end of the basin and was discharged to the 216-B-55 crib. Under emergency conditions, the effluent stream could be diverted to the 216-B-64 basin. The water collected in the basin could be routed through the pump pit, located on the east side of the basin, and pumped back to 221-B or routed to the 216-B-55 crib.

Waste Type: Steam Condensate

Waste Description: The unit was intended to receive steam condensate from the 221-B Building that exceeded release limits. A facility test was conducted, but the basin was never used.

Closure Info: Interim: No remediation was performed at this site. The No Action classification is documented on form 2004-111. The basin was built, but never received any waste.

Code: 241-B-361	Classification: Accepted
Names: 241-B-361; 241-B-361 Settling Tank	Reclassification: None
Type: Settling Tank	Start Date: 1/1/1945
Status: Inactive	End Date: 1/1/1947

Description: The site is delineated with light post and chain. It is posted with Underground Radioactive Material and Inactive Miscellaneous Underground Storage Tank signs. The surface is covered with coarse rock.

Location: The site is located east of Baltimore Ave. and south of the 216-B-5 Reverse Well.

Related Sites/ Structures: The tank is associated with 221-B, 224-B and 216-B-5. The pipeline to the settling tank is sitecode 200-E-195-PL.

Process Description: The tank operated from April 1945 to September 1947, acting as a settling tank for waste originating in B Plant cells 5 and 6 and also low level concentrator condensate from the 224-B facility. The waste was routed first to the 241-B-154 Diversion Box before being transferred to the settling tank. After settling, the supernate from the tank was discharged to the 216-B-5 reverse well. During its period of service, 120 million gallons of waste passed through the tank. The waste contained approximately 4.3 kilograms of plutonium. It is estimated that half of the plutonium overflowed into the reverse well, leaving an estimated 2.4 kilograms of plutonium in the 241-B-361 tank. An estimated two million curies of strontium also remains in the tank. The tank sludge was sampled and analyzed in 1979. The sludge composition was consistent with the bismuth phosphate process.

The 241-B-361 tank is constructed of 15-centimeter (6-inch) reinforced, prestressed concrete. The top of the unit is 1.8 meters (6 feet) below grade. Eleven risers are visible above grade. One is equipped with a manual tape, a second contains two dip tubes, a third vents the unit, and the eight remaining are blanked off.

Waste Type: Sludge

Waste Description: The unit received low salt, alkaline radioactive liquid wastes from cell washings collected in the 5-6W Cells in 221-B and low level concentrator condensate from the 224-B facility. Although some reports estimate the quantity of waste in the tank as 121,000 liters (32,000 gallons), the unit is now estimated to contain 83,000 liters (22,000 gallons) of sludge containing 2.46 kilograms (5.42 pounds) of plutonium and 1,060 curies beta/gamma. The tank solids are primarily bismuth phosphate residue described as black in color with a pudding like consistency. The current volume is unknown and not monitored. The tank contents was sampled in 1979. The sludge contained 3.4 microcuries/gram of Pu-239, 1.4 microcuries/gram of Cs-137, and 23 microcuries/gram of SR-90. The liquid contained 6.1E-7 microcuries/ml of Pu-239, 2.5E-3 microcuries/ml of Cs-137, and 3.1E-5 microcuries/ml of Sr-90.

Code: 216-BY-201

Classification: Accepted

Names: 216-BY-201; 216-BY-47; 241-BY Flush Tank; Supernatant Disposal Flush Tank

Reclassification: None

Type: Settling Tank

Start Date: 1/1/1954

Status: Inactive

End Date: 1/1/1955

Description: The unit is an underground tank that is not discernible from the surface. It is located within an Underground Radioactive Material area and has a sign stating "Restricted Access - 216-BY-201" and "IMUST" (Inactive Miscellaneous Underground Storage Tank). There is one metal covered manhole visible at the tank site and no visible risers or vents. A steel monitoring pit, located near the southeast corner of the tank, is visible and may be identified by a steel cover.

Location: The flush tank is located north of the 241-BY Tank Farm and south of the 216-B-43 through 216-B-50 cribs. It is south of 12th Street and west of Baltimore Ave.

Release Description: See UPR-200-E-9

Related Sites/Structures: The site is related to 241-BY Tank Farm, the 216-B-43 through 49 cribs and UPR-200-E-9. Pipelines associated with the flush tank are 200-E-219-PL and 200-E-220-PL.

Process Description: The flush tank is a rectangular, reinforced concrete disposal structure. The tank received waste from the 241-BY Tank Farm and the TBP (tri-butyl phosphate) Waste Line. The unit was designed to scavenge the TBP waste and discharge the supernatant to the 216-B-43 through 216-B-49 cribs. The 216-B-50 crib did not receive Uranium Recovery waste via the 216-BY-201 tank. The referenced drawing (H-2-2604) shows a vent pipe 15 centimeters (6 inches) in diameter by 2.7 meters (9 feet) long that extends from the top of the tank to 1.2 meters (4 feet) above grade, and a 15 centimeters (6 inches) diameter by 2.1 meters (7 feet) long pipe that extends from the top of the tank to 0.61 meters (2 feet) above grade. The tank is constructed of concrete. A manhole is located at each end of the tank. A 10 centimeter (4 inch) diameter pipe from the 241-BY Tank Farm enters near the top of the tank. A "Miller Siphon" (manufactured by Pacific Flush Tank Company) is located at the bottom of the tank and drains waste through a 35 centimeter (14 inch) line to the 216-B-43 through 216-B-50 cribs. An overflow pipe is also connected to this line.

Waste Type: Process Effluent

Waste Description: The unit received radioactive waste from the 241-BY Tank Farm and the TBP Waste Line. Radiological constituents include strontium and cesium with their associated decay products, yttrium and barium. Chemical waste includes nitrate, sodium, aluminum, carbonate and hydroxide.

Code: 216-C-1	Classification: Accepted
Names: 216-C-1; 216-C-1 Crib; 216-C Crib	Reclassification: None
Type: Crib	Start Date: 1/1/1953
Status: Inactive	End Date: 6/1/1957

Description: The site is marked and posted with Underground Radioactive Material signs. A yellow cement crib marker, labeled 216-C-1, is located inside the chained 241-CX-71 tank area.

Location: The site is located in 200 East Area, south of 7th Street. It is east of the 209-E Facility and southwest of where the 201-C building once stood.

Related Sites/ Structures: The site is associated with 201-C, 241-CX-71, 200-E-156-PL pipeline and 200-E-41.

Process Description: The crib received cold run waste and process condensate from the 201-C (Hot Semiworks) test facility. The 201-C building went through three operational modes. It was originally built in 1949 as a pilot plant for the Reduction Oxidation (REDOX) Process. In 1954, the building was used as a pilot plant for the Plutonium Uranium Extraction (PUREX) Process. The plant was converted to recover strontium from process wastes in 1961. Waste neutralized in the 241-CX-71 tank was discharged to this crib. The structure is 7.0 by 2.4 by 1.7 meters (23 by 8 by 5.5 feet), constructed of 2.4-meter by 20-centimeter by 20-centimeter (8-foot by 8-inch by 8-inch) concrete ties, 2.4-meter by 20-centimeter by 10-centimeter (8-foot by 8-inch by 4-inch) spacer blocks, and 1.1-meter by 2.4-meter by 15-centimeter (3.7-foot by 8-foot by 6-inch) roof slabs. The unit has 1.5 meters (5 feet) or 120 cubic meters (4,200 cubic feet) of gravel fill backfilled over with 0.6 meters (2 feet) of soil, leaving 1.5 meters (5 feet) of the excavation unfilled. The distance from the release point to the site bottom is 1.2 meters (4 feet). The side slope is 1:2.

Waste Type: Process Effluent

Waste Description: From January 1953 until September 1955, the site received high salt waste (HSW), cold-run waste, and the process condensate from the 201-C Building. From September 1955 to June 1957, the site received the HSW cold-run waste from the 201-C Building. Waste neutralized in the 241-CX-71 tank was discharged to this crib. The waste is high in salt and is neutral to basic.

Code: 216-C-2	Classification: Accepted
Names: 216-C-2; 216-C-2 Dry Well; 216-C-2 Reverse Well; 291-C Dry Well	Reclassification: None
Type: Injection/Reverse Well	Start Date: 1/1/1953
Status: Inactive	End Date: 5/16/1988

Description: The reverse well is no longer visible. It is not separately marked or posted from the surrounding stabilized area (200-E-41) that is posted as Underground Radioactive Material.

Location: The unit is located inside the 200-E-41 Stabilized Area, south of 7th Street in 200 East Area. It is southeast of the former 291-C-1 Stack location, in the Hot Semiworks area.

Related Sites/ Structures: The dry well is related to the 291-C-1 Stack and the 291-C-1 Stank Ventilation Filter. The pipelines associated with 216-C-2 are sitecodes 200-E-251-PL and 200-E-252-PL.

Process Description: The dry well was a 30.5-centimeter (12-inch) diameter pipe that extended 0.3 meters (1 foot) above grade to 12 meters (40 feet) below the surface. The bottom 7.6 meters (25 feet) of the pipe was perforated. The drain is surrounded by a concrete collar at grade. A 10-centimeter (4-inch) stainless steel saran-lined inlet pipe connected the unit to the 291-C-1 Stack. A second inlet line constructed of 5.1-centimeter (2-inch) stainless steel pipe connected to the 291-C-1

Stack Ventilation Filter.

Waste Type: Water

Waste Description: The site received 291-C Stack drainage and the seal water drainage from the stack ventilation filters. The volume discharged to the unit is unknown. The waste is low in salt and is neutral to basic. The site contains less than 1 curie total beta activity.

Code: 216-C-3

Classification: Accepted

Names: 216-C-3; 216-C-3 Crib; 201-C Leaching Pit

Reclassification: None

Type: Crib

Start Date: 1/1/1953

Status: Inactive

End Date: 3/1/1954

Description: The crib is identified with a single AC-540 concrete marker post. The site is located inside a larger posted Underground Radioactive Material area known as 200-E-41 (Strontium Semiworks Stabilized Area).

The site consists of 10 centimeter (4 inch) pipes resting on a gravel bed creating a drain field type crib.

Location: The crib is located south of 7th Street, within the Strontium Semiworks stabilized area known as 200-E-41.

Related Sites/Structures: The site is associated with the 201-C, 215-C and 271-C facility operations. The pipeline associated with this crib is sitecode 200-E-169-PL.

Process Description: The crib received acidic process waste from the 201-C, 215-C and 271-C buildings. The crib was deactivated by blanking the inlet pipeline and backfilling the excavation with sand and gravel. When the 216-C-3 leaching pit was blanked, the effluent was diverted to the 216-C-9 excavation.

Waste Type: Process Effluent

Waste Description: The site received waste from the 201-C, 215-C, and 271-C buildings. The waste is acidic.

Code: 216-C-4

Classification: Accepted

Names: 216-C-4; 216-C-4 Crib

Reclassification: None

Type: Crib

Start Date: 1/1/1955

Status: Inactive

End Date: 1/1/1965

Description: The crib has been surface stabilized. It is marked and posted with Underground Radioactive Material signs. An access area has been cut through the 209-E security fence.

Location: The crib is located south of 7th Street in the Hot Semiworks area. The crib is located in between the double security fences surrounding the 209-E Critical Mass Laboratory.

Related Sites/Structures: The pipeline associated with this crib is sitecode 200-E-170-PL.

Process Description: The crib received waste from the 276-C building. The unit is constructed of a 15-centimeter (6-inch) diameter galvanized, corrugated, perforated piping placed horizontally at 3.5 meters (11.5 feet) below grade. Two 6.1 meter (20 foot) lengths are placed perpendicularly to the inlet pipe, forming an H pattern. The side slope is 1:1. The site contains 1.8 meters (6 feet) of gravel fill

[74 cubic meters (2,600 cubic feet)] and has been backfilled. The waste release point is 1.5 meters (5 feet) from the site bottom. The crib bottom is 4.8 meters (16 feet) below ground surface and measures 3 meters (10 feet) by 6 meters (20 feet).

Waste Type: Process Effluent

Waste Description: The site received contaminated organic waste from the 276-C Building. The waste is low in salt and is neutral to basic.

Code: 216-C-5 **Classification:** Accepted

Names: 216-C-5; 216-C-5 Crib **Reclassification:** None

Type: Crib **Start Date:** 3/1/1955

Status: Inactive **End Date:** 6/1/1955

Description: The crib is marked with concrete AC-540 markers and Underground Radioactive Material signs. It is located within the larger, surface stabilized area known as 200-E-41.

Location: The crib is located south of 7th Street, within the Hot Semiworks stabilized area (200-E-41).

Related Sites/Structures: The crib is associated with the 201-C facility, 241-CX-71 and 200-E-41. The pipeline associated with this crib is sitecode 200-E-173-PL.

Process Description: The crib received 201-C "high salt waste" cold run waste via a 15-centimeter (6-inch) diameter galvanized, corrugated, perforated piping placed horizontally at 3.4 meters (11 feet) below grade. Two 6.1-meter (20-foot) lengths are placed perpendicularly to the inlet pipe, forming an H pattern. The side slope is 1:1. The site contains approximately 1.8 meters (6 feet) or 74 cubic meters (2,600 cubic feet) of gravel fill and has been backfilled. The waste release point is 1.5 meters (5 feet) from the site bottom.

Waste Type: Process Effluent

Waste Description: The site received the high salt waste (HSW) cold run waste from the 201-C Building. It received some waste that had passed through the 241-CX-71 Neutralization Tank.

Code: 216-C-6 **Classification:** Accepted

Names: 216-C-6; 241-CX Crib **Reclassification:** None

Type: Crib **Start Date:** 9/1/1955

Status: Inactive **End Date:** 9/1/1964

Description: The crib is covered with gravel and marked with cement posts on the four corners. It is posted with Underground Radioactive Material signs.

Location: The crib is located south of 7th Street, within the Hot Semiworks stabilized area (200-E-41). It is adjacent to the south side of the 241-CX Vault building.

Related Sites/Structures: The site is associated with the 241-CX Vault and the 241-CX-72 crib. The pipeline associated with this crib is 200-E-171-PL.

Process Description: The unit is constructed of 15-centimeter (6-inch) diameter galvanized, corrugated, perforated piping placed horizontally at 3.4 meters (11 feet) below grade. Two 6.1-meter (20-foot) lengths are placed perpendicularly to the inlet pipe, forming an H pattern. The side slope is 1:1. The site contains approximately 1.8 meters (6 feet) or 74 cubic meters (2,600 cubic feet) of gravel fill and has been backfilled. The waste release point is 1.5 meters (5 feet) from the site bottom.

Waste Type: Process Effluent

Waste Description: The site received the process condensate from the 201-C Building and the 241-CX Vault floor drainage in the 241-CX area. The waste is acidic.

Code: 216-C-7

Classification: Accepted

Names: 216-C-7; 216-C-7 Crib

Reclassification: None

Type: Crib

Start Date: 1/1/1961

Status: Inactive

End Date: 1/1/1983

Description: The site is surrounded by steel post and chain. It is posted with Underground Radioactive Material signs.

Location: The site is located southwest of the 209-E Building, inside the 209-E exclusion area fence.

Related Sites/ Structures: The crib is associated with 209-E-WS-3. The pipeline associated with this crib is sitecode 200-E-172-PL.

Process Description: The crib received radioactive liquid waste from the 209-E Critical Mass Laboratory via 5 centimeter (2 inch) diameter steel pipeline that connected to a 0.15 meter (6 inch) diameter, perforated vitrified clay distribution pipe, placed horizontally 3 meters (9 feet) below grade. Two lengths of clay pipe are placed perpendicularly to the first, forming an H pattern. The site contains 123 cubic meters (4,100 cubic feet) of gravel fill and has been backfilled.

Waste Type: Process Effluent

Waste Description: The 216-C-7 crib received liquid waste from the 209-E Building Critical Mass Laboratory. Small tanks held reflector water that contained nitric acid, plutonium, uranium and neutron poisons such as boron, cadmium and gadolinium. The crib was placed on standby in 1983.

Code: 216-C-10

Classification: Accepted

Names: 216-C-10; 216-C-10 Crib

Reclassification: None

Type: Crib

Start Date: 11/1/1964

Status: Inactive

End Date: 10/1/1969

Description: The site is marked with concrete AC-540 markers and Underground Radioactive Material signs. The surface is covered with gravel. In 2015, approximately 3000 square feet of additional gravel was added to prevent the growth of tumbleweeds.

Location: The site is located south of 7th Street and southeast of the 201-C Building core.

Related Sites/ Structures: The site is associated with the 201-C facility and the 200-E-157-PL pipeline.

Process Description: The crib received process condensate from 201-C via a 7.6-centimeter (3-inch) diameter stainless steel pipe, located horizontally, 1.2 meters (4 feet) below grade. The site slope is 1:1.5. The site contains 48 cubic meters (1,700 cubic feet) of gravel fill and has been backfilled with dirt.

Waste Type: Process Effluent

Waste Description: The site received process condensate and liquid waste from the 201-C Building. The waste was acidic.

Code: 291-C-1	Classification: Accepted
Names: 291-C-1; 291-C-1 Stack; 291-C Stack Burial Trench	Reclassification: None
Type: Burial Ground	Start Date: 1/1/1949
Status: Inactive	End Date: 1/1/1987

Description: The 291-C Stack was a double-shell structure made of reinforced concrete, acid-resistant brick and mortar. The stack was demolished in 1988 and now lies in a trench south of where it stood. The area has been surface stabilized with an ash cover (sitecode 200-E-41). The stack burial trench is not marked and cannot be separately distinguished from the rest of the surface stabilized area.

Location: The stack was located east of the 201-C facility, south of 7th Street in 200 East Area.

Related Sites/Structures: The site is associated with 201-C and the 200-E-41 surface stabilized area.

Process Description: The stack provided exhaust air ventilation for the 201-C cells and process vessels. Forty fiber glass filters were located in an underground concrete cell. An array of HEPA filters was contained in another below-grade enclosure.

Waste Type: Demolition and Inert Waste

Waste Description: The radioactively contaminated stack now lies in a trench south of where it stood. It was estimated to contain 100 curies of plutonium and 600 curies of beta contamination.

Code: 2704-C-WS-1	Classification: Accepted
Names: 2704-C-WS-1; Gatehouse French Drain; 2704-C French Drain	Reclassification: None
Type: French Drain	Start Date: 1/1/1949
Status: Inactive	End Date: 1/1/1998

Description: The 2704-C Building was demolished in 1998. The area where the french drain was located is now within a larger gravel area that is posted Underground Radioactive Material (URM). The drain is no longer visible at the location described. The drain could be covered with gravel or by the two dumpsters located in the area. There is a possibility that this site is the same site as that identified in HW-22955 as a quench tank. The description follows. Steam condensate drained to a quench tank at the southwest corner of the building (2704C). Sanitary waste drains through a 10.2 centimeter (4 inch) cast iron line running beneath the floor slab from the toilet room to a point 1.5 meters (5 feet) west of the building where it connects to a 10.2 centimeter (4 inch) tile drain. The overflow from the quench tank also flows into this tile drain which runs to the sanitary waste disposal field. The sanitary waste disposal field is part of the 2607-E7 Septic System. (Drawings H-2-4033, H-2-4012, and H-2-4013 identify a quench tank. Drawing H-2-77665 identifies a french drain).

Location: This site is located in 200 East. It is located at the southwest corner of the 2704-C Building.

Related Sites/Structures: The site was related to the 2704-C, Office and Gate House. The pipeline associated with this french drain is sitecode 200-E-250-PL. The Hot Semiworks surface stabilized area is known as 200-E-41. The demolished 2704-C building and drain are adjacent to the Hot Semiworks stabilized area.

Process Description: The 2704-C building was originally built in 1949 to support the Hot Semiworks operations. It was a one story wooden structure, on a cement slab foundation, that contained the security office (Gate House), a lunch room and a toilet. Building steam condensate drained to a quench tank located at the southwest corner of the building. During the 1980s, 2704C housed the 200 East Tank Farms Health Physics (HPT) Offices. Prior to demolition by Bechtel Hanford Inc. (BHI), the building was designated a contaminated facility.

Waste Type: Steam Condensate

Waste Description: Although the drain received building steam condensate, periodically the drain was labeled with radioactive postings.

Code: 200-E BP **Classification:** Accepted

Names: 200-E BP; 200-E Burning Pit; 200 East Burn Pit **Reclassification:** None

Type: Burn Pit **Start Date:** 1/1/1950

Status: Inactive **End Date:** 1/1/1970

Description: The burn pit is a large depression. There is limited growing vegetation. The surface is mostly rock and gravel. In 2010, most of the burn pit was posted as a Soil Contamination Area, due to contaminated tumbleweed fragments accumulating within the pit.

Location: The burn pit is located in the northeast corner of 200 East Area, south of 12th Street and west of Canton Ave. It is a large excavation located east of the 218-E-8 Burial Ground.

Related Sites/Structures: The site is associated with WIDS sitecode 200-E-8 BPDS, 200-E-109 and UPR-200-E-106.

Process Description: Burn pits were typically used for disposal of non radioactive construction and office wastes. Sometimes paint, solvents and chemicals were dumped there. The pit was also used to burn tumbleweed that were collected off the 200 East Area perimeter fences. In the late 1990's, miscellaneous, non-radioactive material began to be stored inside the burn pit. Many damaged load luggers and large Basin Disposal, Inc. trash containers accumulated in the pit. Some containers were empty, but some containers had material in them. In the spring of 2010, MSA began to remove the containers from the burn pit. The containers were radiological surveyed and released. The released containers were sent off site to Basin Disposal, Inc. One large roll off container may be sent to the Environmental Restoration Disposal Facility (ERDF).

Waste Type: Chemicals

Waste Description: This site received construction and office waste 1,500 cubic meters (1,960 cubic yards), paint wastes, and chemical solvents 1,000 cubic meters (1,300 cubic yards).

Waste Type: Asbestos (friable)

Waste Description: A site visit in 1991 noted an area within the pit posted with asbestos warning signs.

Code: 200-E PD **Classification:** Accepted

Names: 200-E PD; 200-E Powerhouse Ditch; 200 East Powerhouse Pond **Reclassification:** None

Type: Ditch **Start Date:** 1/1/1945

Status: Active **End Date:**

Description: The site currently consists of an open ditch, measuring approximately 580 meters, running east to west. The eastern portion of the original ditch was backfilled in 1996, due to a contamination spread. This portion is currently posted with Underground Radioactive signs.

Location: The ditch is located north of 4th Street and south of the Hot Semi-Works area.

Related Sites/ Structures: The ditch is associated with the 284-E Powerhouse, 283-E, 282-E, 200-E-286 swamp, UPR-200-E-100 and UPR-200-E-143. The pipeline associated with the ditch is sitecode 200-E-237-PL.

Process Description: The ditch is fed from a 42 inch diameter underground pipeline connected to the 282-E, 283-E and 284-E facilities. The original, horse shoe shaped ditch emptied into a shallow depression east of the 200 East Area fence known as the Powerhouse Pond (see 200-E-286) from 1946 through 1953. In 1954, the powerhouse ditch effluent was redirected in a northeast direction, to connect to 216-B-3 Pond. The water was discharged from the ditch to a 24 inch diameter pipeline that led to the 216-B-3C Pond. In 1997, when discharges to the 216-B-3C Pond were discontinued, the effluent from the Powerhouse Ditch was diverted to the 200 Area Treated Effluent Disposal Facility (TEDF). The 284-E powerhouse was completely shut down in 1998. After the powerhouse was shutdown, a small amount of effluent continued to be discharged to the ditch from the 282-E and 283-E water treatment facility and reservoir. During 1997 and 1998, blowdown/boiler condensate from the Johnson Controls facility also discharged to the ditch. A very small amount of effluent continues to be discharged to the pipeline (200-E-237-PL) that feeds the ditch.

Waste Type: Process Effluent

Waste Description: The ditch received cooling water, boiler blowdown, floor drain discharge, softener regeneration effluents, filter backwash, and sedimentation basin cleanout from 282-E, 283-E and 284-E. During 1997 and 1998, a small amount of water from the Johnson Controls package boiler was discharged to the ditch. The volume of discharge has varied of the life of the ditch. Only a very small amount of water is currently discharged to the pipeline and ditch.

Code: 200-E-4	Classification: Accepted
Names: 200-E-4; 209-E North Dry Well; Critical Mass Laboratory Dry Well North; Miscellaneous Stream #730	Reclassification: None
Type: French Drain	Start Date: 1/1/1958
Status: Inactive	End Date: 1/1/1959

Description: The site is a 1.2 meter (4 foot) diameter dry well, covered with a yellow metal cover. In 2011, amended water was sprayed during the 209E building demolition activities. Post-demolition, three to six inches of surface material was removed from all areas affected by the amended water and prior to applying a gravel cap. The final gravel cap was expanded to cover all affected areas. The posted URMA was expanded to include the entire gravel cap. The gravel cap now covers several WIDS sites. The additional WIDS sites under the 209E gravel cap are 200-E-4, 200-E-35, 209-E-WS-1, 209-E-WS-2, 2718-E-WS-1 and 200-E-293 (2718E footprint). The 209-E-WS-3 (Tank 111), adjacent to the south side of the foundation, is within the URMA but was not covered or backfilled.

Location: The site is located approximately 7.6 meters (25 feet) north of the northwest corner of the 209-E Critical Mass Laboratory Service Building.

Related Sites/ Structures: The site is connected to 209-E Critical Mass Lab via underground piping (see sitecode 200-E-249-PL) and the 209E gravel cap (200-E-294).

Waste Type: Steam Condensate

Waste Description: The waste was steam condensate from the steam trap in the valve pit plus steam condensate from the equipment room.

Code: 200-E-13 **Classification:** Accepted

Names: 200-E-13; Rubble Piles from RCRA General Inspection #200EFY95 Item #7 **Reclassification:** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: A 1995 site inspection identified this site and described it as numerous rubble piles. These piles contained inert construction debris, such as wood, asphalt, dirt, pipe and concrete. Another site visit occurred in February 1997. The following debris was identified: asphalt paving, concrete, steel pipe, rebar and PVC pipe. During a GPS survey on August 26, 1998, it was observed that debris was concentrated in piles south of an old borrow area. However, there were also isolated piles/berms of debris beyond this concentration, primarily to the west. Some scattered debris and half-buried towels or rags were observed in the borrow area. A site visit on July 26, 1999, confirmed the previous site conditions.

Location: The site is located inside 200 East Area, south of the PUREX facility. The site is north of First Street, off a dirt road approximately 220 meters (722 feet) west of the intersection of First Street and Canton Avenue.

Waste Type: Construction Debris

Waste Description: The waste contains inert construction debris that includes wood, asphalt, dirt, pipe, and concrete.

Code: 200-E-25 **Classification:** Accepted

Names: 200-E-25; 272-BB French Drain; Insulation Shop French Drain; Miscellaneous Stream #659 **Reclassification:** None

Type: French Drain **Start Date:** 1/1/1971

Status: Inactive **End Date:** 1/1/1991

Description: The french drain structure is not visible from the surface. The french drain's location is marked with an old sign, mounted on two support posts. The sign says "Asbestos Waste Disposal Site - Do No Excavate". A sign stating "200-E-25" has been attached to one of the support posts.

Location: The dry well is located approximately 6 meters (20 feet) north of the northeast corner of the 272-BB Insulation Shop.

Related Sites/Structures: The site is associated with the 272-BB building and the 200-E-209-PL pipeline.

Process Description: The building sink and floor drain were connected to the dry well via a 5.1 centimeter (2 inch), schedule 40 carbon steel pipe. An 0.4 meter (1.5 foot) diameter, 36 inch tall grease trap with a removable cover is located on the east side of the 272-BB building.

Waste Type: Chemicals

Waste Description: Material used in the 272-BB Insulation Shop that possibly could have been flushed into the sink or floor drain include: Calcium Silicate, Fiberglass, Silicate, "Airball" (an insulation cover material) and latex paint. Prior to 1988, it is possible that organic chemicals, oils and grease

may have been introduced into the french drain. A sign posted at the site indicates the presence of asbestos, which is regulated as a hazardous substance under CERCLA.

Code: 200-E-26 **Classification:** Accepted

Names: 200-E-26; Diesel Fuel Contaminated Soil; Heavy Equipment Storage Area **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The site is an area that was used as an equipment staging area for trucks, backhoes, compressors, and other heavy equipment. As of October 2001, the site no longer shows visual evidence of oil contaminating the soil. In 1996, the soil had an odor like diesel fuel, but this was not reported in 2001. The contamination noted in 1996 appeared to be spotty. An electrical receptacle marks each end of the site.

Location: The site is located in the 200 East area, south of B Plant, within the former ICF Kaiser Construction Complex.

Release Description: Heavy equipment was stored in this area for several years. The contaminated soil is most probably due to equipment leakage.

Waste Type: Soil

Waste Description: The soil at the site is contaminated with oil and diesel fuel.

Code: 200-E-29 **Classification:** Accepted

Names: 200-E-29; Unplanned Release from 241-ER-152 Diversion Box **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The site is a large, irregular shaped, posted Underground Radioactive Material (URM) area. A smaller triangular shaped URM area is located adjacent to the east shoulder of Atlanta Ave., northwest of the larger, stabilized 200-E-29 area. Another small URM area is located adjacent to a row of conex boxes, east of the larger stabilized area.

Location: The site is located south of 221-B, south of 7th Street and east of Atlanta Ave. It surrounds the 241-ER-152 Diversion Box.

Related Sites/ Structures: The site is associated with the 241-ER-152 Diversion Box.

Waste Type: Animal Waste

Waste Description:

Code: 200-E-43 **Classification:** Accepted

Names: 200-E-43; Regulated Equipment Storage Area; Tank Car Storage Area; TC-4 Spur Tank Car Storage Area **Reclassification:** None

Type: Storage**Start Date:****Status:** Inactive**End Date:**

Description: This site consists of a chain link fenced portion of the TC-4 Spur located northwest of the PUREX facility. The site was used to store railroad tank cars containing liquid radioactive material that require controls due to radiological dose rate conditions. The fence gate is locked. The area had been posted as a Radioactive Material Area (RMA) and an Underground Radioactive Material area (URM). However, in January 1999, it was only posted as an Underground Radioactive Material area. It is also posted with "Danger - Unauthorized Personnel Keep Out" signs. The ties between the rails are covered with gravel.

Location: The site is located inside 200 East Area, north of 4th Street.

Release Description: On December 17, 2010, approximately 576,000 gallons of potable water discharged to the ground during a construction water line tie in activity. The water flowed south, from the line break and flooded a portion of the TC-4 Spur Railcar Storage Area and the UPR-200-E-88 stabilized railroad track. Although no railcars are being stored here, the area is still fenced and radiologically posted.

Related Sites/ Structures: The site is associated with the TC-4 Railroad Spur and UPR-200-E-88.

Process Description: The fenced area was used to stage railroad tank cars that transported liquid waste to the 204-AR waste unloading facility.

Code: 200-E-53**Classification:** Accepted

Names: 200-E-53; Above Ground Storage Area; Contaminated Zone Adjacent to 218-E-12B and 218-E-8; Overground Storage Area

Reclassification: None**Type:** Unplanned Release**Start Date:** 1/1/1980**Status:** Inactive**End Date:**

Description: The waste site is an irregular shaped area in the bottom of a soil depression. Rockwell document RHO-CD-1048 and photographic documentation from 1982 indicate this area was used to store contaminated equipment. The size, shape and type of posting has varied over the years.

Location: The site is located adjacent to and east of 218-E-12B Burial Ground and adjacent to and south of 218-E-8 Burial Ground inside 200 East Area.

Related Sites/ Structures: This site is associated with 200-E-109, UPR-200-E-50 and UPR-200-E-62.

Waste Type: Soil

Waste Description: Contaminated soil specks, vegetation and animal feces have been identified in this area.

Code: 200-E-56**Classification:** Accepted

Names: 200-E-56; 241-C Waste Line Leak Adjacent to 201-C; Waste Line Leak #1

Reclassification: None**Type:** Unplanned Release**Start Date:**

Status: Inactive**End Date:**

Description: The area adjacent to the demolished 201-C Building has been surface stabilized with flyash. The stabilized area has been given the WIDS Site code 200-E-41 and is posted as an Underground Radioactive Material area. The release site is not separately marked or posted, and may be combined with 200-E-41.

Location: The waste line leak was adjacent to the east side of the 201-C Building.

Release Description: HW-52860 states that teflon flange gaskets on the stainless steel underground waste line from 201-C to 241-C Tank Farm developed leaks. The leaks caused the underground area next to the east side of the 201-C Building and an underground area near the east facility fence to become contaminated (see 200-E-57). Radiation readings in 1957 were greater than 100 rad per hour at a depth of 3.66 meters (12 feet) adjacent to the 201-C Building and near the fence. The underground waste line was abandoned and bypass sections installed. New sections of pipeline were installed south of the leaking sections.

Related Sites/Structures: The site is associated with 200-E-57, surface stabilized area 200-E-41 and pipelines 200-E-149-PL and 200-E-257-PL.

Process Description: The Hot Semiworks Facility was constructed in 1949. The facility was a pilot plant for the testing of the REDOX and PUREX plutonium separation processes from 1952 through 1957. The facility pilot tests used irradiated fuels. The facility was placed in standby status in 1957. In 1961 the plant was converted for the strontium recovery process of waste stored in tank farms. The Hot Semiworks facility permanently shut down in 1967. Decommissioning began in 1983 and was completed in 1987.

Waste Type: Process Effluent

Waste Description: A leaking underground waste line caused the soil beneath the line to become contaminated. The pipeline carried waste from the 201-C Building to the 241-C Tank Farm. Maximum contamination levels in 1957 were greater than 100 rad per hour.

Code: 200-E-57**Classification:** Accepted

Names: 200-E-57; 241-C Waste Line Leak East of 201-C; Waste Line Leak #2

Reclassification: None**Type:** Unplanned Release**Start Date:****Status:** Inactive**End Date:**

Description: The area around the demolished 201-C (Hot Semiworks Facility) has been surface stabilized with flyash. The stabilized area is known as 200-E-41 and is posted with Underground Radioactive Material signs. This release site is separately not marked or posted, and may be combined with 200-E-41.

Location: This release occurred at an underground waste line, located east of the 201-C Building, adjacent to the east Semiworks fence. The fence no longer exists.

Release Description: HW-52680 states that teflon flanges on the 5-centimeter (2-inch) stainless steel underground waste line from 201-C to the 241-C Tank Farm leaked and caused the soil beneath the line to become contaminated. One leaking flange was located near the Semiworks fence. The attached sketch indicates an underground contaminated area measuring 9 meters (30 feet) long. Radiological readings in 1957 ranged from 6 rad per hour at a depth of 0.3 meters (1 foot) to greater than 100 rad per hour at a depth of 4.5 meters (15 feet) at this location. The document states the line also leaked in an area adjacent to the east side of the 201-C Building (see 200-E-56). The underground waste line was abandoned and bypass sections installed. New sections of pipeline were installed south of the leaking sections.

Related Sites/ Structures: The site is associated with 200-E-41 and 200-E-56.

Process Description: The Hot Semiworks Facility was constructed in 1949. The facility was a pilot plant for the testing of the REDOX and PUREX plutonium separation processes from 1952 through 1957. The facility pilot tests used irradiated fuels. The facility was placed in standby status in 1957. In 1961 the plant was converted for the strontium recovery process of waste stored in tank farms. The Hot Semiworks facility permanently shut down in 1967. Decommissioning began in 1983 and was completed in 1987.

Waste Type: Process Effluent

Waste Description: A leaking underground waste line caused the soil beneath the line to become contaminated. The pipeline carried waste from the 201-C Building to the 241-C Tank Farm. Maximum contamination levels in 1957 were greater than 100 rad per hour.

Code: 200-E-58	Classification: Accepted
Names: 200-E-58; 216-A-5 Neutralization Tank; 216-A-5 NU; 270A; Tank A5	Reclassification: None
Type: Neutralization Tank	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1987

Description: The site is an underground tank used to neutralize acidic waste prior to disposal. A 101-centimeter (40-inch) riser is visible at the surface. The cylindrical tank sits vertically on a concrete pad. The tank is constructed of welded stainless steel and has a capacity of approximately 28,400 liters (7,500 gallons). A 20-centimeter (8-inch) inlet pipe enters from the north near the base of the tank. The inlet connects into distribution piping constructed of 20-centimeter (8-inch) stainless steel pipe welded into a cross with 1.9-centimeter (3/4-inch) holes drilled at 23-centimeter (9-inch) intervals. A 20-centimeter (8-inch) outlet pipe exits to the south near the top of the tank. A 101-centimeter (40-inch) riser extends 30 centimeters (12 inches) above the surface. The "charging riser" is for adding limestone to the tank to act as a neutralizing agent.

Location: The tank is located south of PUREX, inside the security fence. It is located south of the 295-AB building, north of the 216-A-5 Crib and northwest of the 216-A-10 Crib.

Related Sites/ Structures: The site is related to the 202-A Building (PUREX Canyon), the 216-A-5 Crib, and the 216-A-10 Crib. The pipelines (lines 7717 and 7718) from PUREX to the neutralization tank and from the neutralization tank to the 216-A-5 Sample Pit #4 are described in sitecode 200-E-241-PL.

Process Description: Acidic liquid waste entered the tank from the bottom and was forced upward through a bed of limestone. Interaction with the limestone neutralized the waste prior to overflow through the outlet pipe. The neutralized waste was discharged to a crib.

Waste Type: Process Effluent

Waste Description: The tank was used to neutralize acid waste from PUREX prior to ground disposal. From 1955 to 1961, the neutralized waste was discharged to the 216-A-5 Crib. From 1961 to 1987 the neutralized waste was discharged to the 216-A-10 Crib.

Code: 200-E-68	Classification: Accepted
Names: 200-E-68; 291A Control House Steam Condensate; Injection Well (L); Miscellaneous Stream #59	Reclassification: None

Type: Injection/Reverse Well

Start Date:

Status: Inactive

End Date:

Description: The site is a 1.2 meter (4 foot) diameter drain with a metal cover. Several disconnected, asbestos covered steam lines hang above it.

Location: The site is located south of PUREX, between the 291-A stack exhaust fans and the 292-AB stack building. It is on the southeast corner of 291-A building. It is located inside a Contaminated Area, which surrounds the 291-A building and stack structures.

Related Sites/ Structures: The site is associated with the 291-A control house.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The site received non-contaminated steam condensate, but is located inside a posted Contamination Area.

Code: 200-E-103

Classification: Accepted

Names: 200-E-103; PUREX Stabilized Area; Radiologically Controlled Area - South Side of PUREX

Reclassification: None

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The waste site area is covered with gravel and currently posted with Underground Radioactive Material signs.

Location: The site is located on the south side of the 202-A building, inside the security fence.

Related Sites/ Structures: The site is associated with 202-A, 291-A and the 241-A-151 Diversion Box. It is also associated with multiple Unplanned Releases that occurred in the area. Other sites inside this area stabilized with gravel include: 216-A-2, 216-A-4, 216-A-5, 216-A-21 and 216-A-31.

Process Description: The site is an area contaminated by many unplanned releases that occurred over time during facility operation.

Waste Type: Soil

Waste Description: The ground around the PUREX facility was contaminated from various sources during years of operation activities.

Code: 200-E-109

Classification: Accepted

Names: 200-E-109; Contaminated Tumbleweed Accumulation; Contamination Spread in Northeast Corner of 200 East Area

Reclassification: None

Type: Contamination Migration **Start Date:** 1/1/1998
Status: Inactive **End Date:**

Description: 200-E-109 is areas of contaminated tumbleweed accumulation located mostly in the northeast portion of 200 East Area. The contaminated vegetation is carried by the wind. When the site was originally added to the WIDS database, it consisted of numerous radiologically posted areas along 12th Street and Canton Avenue inside the 200 East Area as well as inside and around the Liquid Effluent Retention Facility, east of 200 East Area. Some areas were posted Contamination Area with a Radiological Buffer Area and others were posted High Contamination Area with a Radiological Buffer Area. The original posted areas were eventually cleaned up and the posting was removed. However, additional areas of accumulated tumbleweed fragments continue to be discovered and posted over the years. The number of posted areas, their size and shape vary with additional radiological surveys.

Location: The site includes numerous radiologically posted areas, located in the northeast portion of the 200 East Area and beyond the 200 East Area perimeter fence. Contaminated vegetation is often identified on the northern 200 East Area fence line along 12th Street, the eastern fence along Canton Avenue, near Gate 810 and outside the 200 East Area fence in and around the Liquid Effluent Retention Facility. The posted areas size and shape varies often, with additional radiological surveys.

Related Sites/ Structures: UPR-200-E-92 and UPR-200-E-93 reported contaminated tumbleweed fragments along the east perimeter fence of 200 East area in 1980. The tumbleweeds reported in both UPR-200-E-92 and UPR-200-E-93 were removed from the fenceline in 1981. It is also associated with burial ground 218-E-12b, which has been considered a major source of the contaminated

Waste Type: Vegetation

Waste Description: Most of the contamination identified is tumbleweed and tumbleweed fragments.

Code: 200-E-115 **Classification:** Accepted

Names: 200-E-115; Contamination Area East of 241-C Tank Farm **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The site had been a posted Contamination Area surrounded with light posts and chains. Large weeds were growing inside the posted area and there are several radiation flags visible inside the posted area. In June 2004, the site was stabilized with a bio-barrier and gravel. The area was reposted as an Underground Radioactive Material area.

Location: The site is located east of the 241-C Tank Farm, south of 8th Street, across an unnamed gravel road.

Related Sites/ Structures: The site may be related to UPR-200-E-91.

Waste Type: Soil

Waste Description: The contamination consisted of contaminated soil specks and contaminated vegetation.

Code: 200-E-117 **Classification:** Accepted

Names: 200-E-117; Contamination Zone South of B Plant **Reclassification** None

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The site is a small, posted Contamination Area. Inside the chained area, two steel pipes extend approximately 0.6 meters (2 feet) above the ground surface. The pipes have valves on them.

Location: The site is located adjacent to the steam line, south of the 292-B Building and the 291-B Stack.

Process Description: According to H-2-44501, Sheet 85, a raw water line extends southward from the 292-B Building and connects to a 30 centimeter (12 inch) raw water line. The water line on the drawing is in the same location as the valves inside the Contamination Area.

Waste Type: Soil

Waste Description:

Code: 200-E-121

Classification: Accepted

Names: 200-E-121; Soil Contamination Area East and West of Baltimore Avenue

Reclassification None

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The site is a long, narrow area along the east side of Baltimore Avenue marked with metal posts and chain with Soil Contamination Area signs and two smaller areas on the west side of Baltimore Ave., also posted with Soil Contamination Area signs. The power poles inside the posted area are marked with yellow Fixed Contamination signs.

Location: The site is located inside 200 East Area, south of 12th Street. One part is located east of Baltimore Avenue, north of 241-B Tank Farm. Two smaller areas are on the west side of Baltimore Avenue, on the east side of the 241-BY Tank Farm.

Waste Type: Soil

Waste Description:

Code: 200-E-123

Classification: Accepted

Names: 200-E-123; Contamination Area South of 216-B-2 Stabilized Ditches

Reclassification None

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: In 2001, the area was covered with clean backfill material and downposted to an Underground Radioactive Material Area. The site had been surrounded with light duty steel posts and chain and was originally posted as a Soil Contaminated Area. No significant vegetation was observed on the site. In 2001, the area was covered with clean backfill material and downposted to an Underground Radioactive Material Area.

Location: The site is located just south of 216-B-2-3 ditch, on the gravel road where the power lines cross the road between 207-B and C Tank Farm.

Release The source of the contamination is unknown.

Description:

Waste Type: Soil

Waste

Description:

Code: 200-E-124

Classification: Accepted

Names: 200-E-124; URM on East Side of 275-EA

Reclassification None

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The site is posted as an Underground Radioactive Material Area with steel posts. The site has been stabilized with approximately 0.3 meters of clean soil. A few tumbleweeds were observed growing on the site. Railroad tracks run through the site and are buried under the stabilization soil. The contamination area is where railroad cars were parked and offloaded into the 275-EA Building.

Location: The site is locate adjacent to the east side of the 275-EA building. The 275-EA building is located between PUREX and 4th Street.

Waste Type: Soil

Waste

Description:

Code: 200-E-125

Classification: Accepted

Names: 200-E-125; Contamination Area Northwest of 244-AR Building

Reclassification None

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The site is posted as a Contamination Area with light duty posts and chain. The surface is very sandy soil. No vegetation was observed.

Location: The site is located northwest of the 244-AR Building, northeast of the 200-E Carpenter Shop and South of the 2237-E Building (Electrical Shop).

Waste Type: Soil

Waste

Description:

Code: 200-E-128

Classification: Accepted

Names: 200-E-128; Radioactive Contamination "Hot Spot" Under Gravel Road

Reclassification None

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The area where the contamination is located is marked with two Underground Radioactive Material signs, on steel posts. The posts are located on the north and south sides of the road. The contamination is located between the signs, under the surface of the gravel road.

Location: The site is located on an unnamed gravel road east of the 207-B Retention Basin and south of the 216-B-2-3 Ditches.

Process Description: The roads inside 200 East and West Areas are routinely surveyed by a truck mounted with radiation detectors. The detectors are equipped with an alarm that makes an audible sound to alert the driver if radiation above a predetermined limit is detected.

Waste Type: Soil

Waste Description:

Code: 200-E-129	Classification: Accepted
Names: 200-E-129; Stabilized Area on East Side of B Plant Railroad Cut	Reclassification: None
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The area has been covered with gravel and posted with Underground Radioactive Material signs.

Location: The site is located east of the northern end of the B Plant railroad cut, south of Atlanta Ave.

Waste Type: Soil

Waste Description: Soil and rock were found radiologically contaminated with maximum readings of 12,000 disintegrations per minute per 100 centimeter probe area.

Code: 200-E-130	Classification: Accepted
Names: 200-E-130; Stabilized Area on West Side of B Plant Chemical Spur	Reclassification: None
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The site is covered with fine gravel and posted with Underground Radioactive Material (URM) signs.

Location: The site is located on the south side of Atlanta Ave., on the west side of the B Plant chemical spur railroad track.

Waste Type: Soil

Waste Description: There were no records found to determine the site conditions of the area prior it being posted as an Underground Radioactive Material area. However, additional radiation surveys done in August 2002 found contamination levels of 20,000 disintegrations per minute per 100 centimeters square on the edge of the previously posted area.

Code: 200-E-139	Classification: Accepted
------------------------	---------------------------------

Names: 200-E-139; Contamination Area North of C Farm **Reclassification** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: A large posted Underground Radioactive Material area is located on the north side of 8th Street. It contains growing vegetation (Rabbitbrush and tumbleweeds). A small posted Underground Radioactive Material area is located on the south side of 8th Street. The area on the south side of 8th Street has been covered with a bio-barrier and gravel.

Location: The site is two separately posted Underground Radioactive Material Areas, one located on the south side of 8th Street and one located on the north side of 8th Street. The areas are north of 241-C Tank Farm in 200 East Area.

Code: 209-E-WS-2 **Classification:** Accepted

Names: 209-E-WS-2; Critical Mass Lab French Drain **Reclassification** None

Type: French Drain **Start Date:**

Status: Inactive **End Date:**

Description: The drain was a 1.2 meter (4 foot) diameter drain in a gravel area southeast of the building. It was painted with yellow paint and has a metal cover. In 2011, amended water was sprayed during the 209E building demolition activities. Post-demolition, three to six inches of surface material was removed from all areas affected by the amended water and prior to applying a gravel cap. The final gravel cap was expanded to cover all affected areas. The posted URMA was expanded to include the entire gravel cap. The gravel cap now covers several WIDS sites. The additional WIDS sites under the 209E gravel cap are 200-E-4, 200-E-35, 209-E-WS-1, 209-E-WS-2, 2718-E-WS-1 and 200-E-293 (2718E footprint). The 209-E-WS-3 (Tank 111), adjacent to the south side of the foundation, is within the URMA but was not covered or backfilled.

Location: The unit is located at the southeast corner of the Critical Mass Laboratory (laboratory wing).

Related Sites/ Structures: The site is associated with the 209-E Critical Mass Laboratory and 200-E-294. The pipelines to the french drain are described in sitecode 200-E-247-PL.

Process Description: The unit is a french drain that received condensate from the Critical Mass Lab HEPA filters and heat exchange system.

Waste Type: Steam Condensate

Waste Description: The waste at the unit includes steam condensate through a collapsed rusted pipe from the Heat Exchanger located in Room 11 of 209-E and a stainless steel pipe from the clean side of the HEPA filters.

Code: 209-E-WS-3 **Classification:** Accepted

Names: 209-E-WS-3; Critical Mass Laboratory Valve Pit and Hold Up Tank (209-E-TK-111) **Reclassification** None

Type: Valve Pit **Start Date:** 1/1/1960

Status: Inactive **End Date:** 1/1/1989

Description: The Valve Pit has a steel lid and posted with Radioactive Material, Internally Contaminated Systems Located Within, and Confined Space, Dome Loading, Ignition Control and IMUST

warning signs. In December 2011, the 209-E facility was demolished. On 10/10/2011 the task of disconnecting, cutting and plugging five lines in the 209-E Valve Pit (209-E-WS-3) that isolated Tank-111 was completed. The Valve Pit metal lid will be placed back on it. The 209E facility slab is sitecode 200-E-294. The pit will not be covered or back-filled with gravel, because there are other lines still in the valve pit associated with the tank farms and not part of the facility demolition work scope.

In 2011, amended water was sprayed during the 209E building demolition activities. Post-demolition, three to six inches of surface material was removed from all areas affected by the amended water and prior to applying a gravel cap. The final gravel cap was expanded to cover all affected areas. The posted URMA was expanded to include the entire gravel cap. The gravel cap now covers several WIDS sites. The additional WIDS sites under the 209E gravel cap are 200-E-4, 200-E-35, 209-E-WS-1, 209-E-WS-2, 2718-E-WS-1 and 200-E-293 (2718E footprint). The 209-E-WS-3 (Tank 111), adjacent to the south side of the foundation, is within the URMA (200-E-294) but was not covered or backfilled.

Location: The tank is located underground, near the south end of the 209-E Facility. The north edge of the tank is about 3 ft (0.9 m) south of the south wall of the 209-E Building's Critical Assembly Room and abuts the east side of the exhaust equipment pad.

Related Sites/ Structures: There is a thin, cadmium-lined Hold-Up Tank, 209-E-TK-111, associated with and under the Valve Pit (subsite1). The pipelines to the valve pit are described in sitecode 200-E-248-PL. The 209E posted area is 200-E-294.

Process Description: A 189 liter (50 gallon) holding tank (209-E-TK-111) is located under the valve pit. The tank was used as a drain tank. The tank held the condensate prior to being released to the cribs. The tank was routinely sampled for plutonium content to determine that the contents were below crib discharge levels. Present contents of the tank are estimated to consist of residual water from condensate collection, containing only low levels of plutonium. After sampling, the contents was discharged to the 216-C-7 crib. The 216-C-7 crib was placed on standby in 1983.

Waste Type: Process Effluent

Waste Description: The Semi-Works Source Aggregate Area Management Study Report states that no wastes are present in the Critical Mass Laboratory Valve Pit. However, radioactive contamination is present in the valve pit sump, although no specific waste inventories for this unit were found. The Hold Up tank was routinely sampled to verify plutonium levels were below limits prior to discharging the contents to the crib.

This Site has the Following SubSites:

Code: 209-E-WS-3:1

Names: 209-E-WS-3:1; 209-E-TK-111 Hold Up Tank

Code: 209-E-WS-3:1

Classification: Accepted

Names: 209-E-WS-3:1; 209-E-TK-111 Hold Up Tank

Reclassification: None

Type: Valve Pit

Start Date:

Status: Inactive

End Date:

Description: The 209-E-TK-111 tank is inactive. It is a passively ventilated drain tank. A recent vapor sample did not identify any flammable gas within the vessel.

In December 2011, the 209-E facility was demolished. On 10/10/2011 the task of disconnecting, cutting and plugging five lines in the 209-E Valve Pit (209-E-WS-3) that isolated Tank-111 was completed. The tank was used to hold condensate from the facility. It was routinely sampled to determine that plutonium levels were below limits prior to discharging

the contents to the crib. Therefore, it is estimated to consist of residual water from condensate collection and low levels of plutonium. This tank meets the definition of an IMUST tank. It is a 189 liter (50 gallon) capacity tank lined with cadmium. It is located underground, adjacent to the Criticality Assembly Room (CAR) at the south end of the 209-E building. It is covered by a steel pit cover and posted with Radioactive Material, Contamination Area and Confined Space Entry signs.

In 2011, amended water was sprayed during the 209E building demolition activities. Post-demolition, three to six inches of surface material was removed from all areas affected by the amended water and prior to applying a gravel cap. The final gravel cap was expanded to cover all affected areas. The posted URMA was expanded to include the entire gravel cap. The gravel cap now covers several WIDS sites. The additional WIDS sites under the 209E gravel cap are 200-E-4, 200-E-35, 209-E-WS-1, 209-E-WS-2, 2718-E-WS-1 and 200-E-293 (2718E footprint). The 209-E-WS-3 (Tank 111), adjacent to the south side of the foundation, is within the URMA (200-E-294) but was not covered or backfilled.

Location: The tank is located underground, near the south end of the 209-E Facility.

Process Description: The tank supported operations inside the 209E Critical Mass Laboratory. A 189 liter (50 gallon) holding tank (209-E-TK-111) is located under the valve pit. The tank was used as a drain tank. The tank held the condensate prior to being released to the cribs. The tank was routinely sampled for plutonium content to determine that the contents were below crib discharge levels. Present contents of the tank are estimated to consist of residual water from condensate collection, containing only low levels of plutonium. After sampling, the contents was discharged to the 216-C-7 crib. The 216-C-7 crib was placed on standby in 1983.

The SubSite is Part Of:

Code: 209-E-WS-3

Names: 209-E-WS-3; Critical Mass Laboratory Valve Pit and Hold Up Tank (209-E-TK-111)

Code: 218-E-7

Classification: Accepted

Names: 218-E-7; 200 East 222-B Vaults

Reclassification: None

Type: Burial Vault

Start Date: 1/1/1945

Status: Inactive

End Date: 1/1/1952

Description: The site consists of three underground vaults. Two were square, wood structures and one was a round, vertical pipe unit. All three vaults had been connected to the surface with waste disposal chutes. The chutes have been removed and the area has been surface stabilized.

Location: The vaults are located approximate 20 meters (66 feet) south of the 222-B Building, south of an above ground steam line.

Related Sites/ Structures: The vaults are associated with lab waste from the 222-B building.

Waste Type: Misc. Trash and Debris

Waste Description: This site received radioactive, mixed fission product/transuranic (MFP/TRU) wastes.

Code: 270-E-1

Classification: Accepted

Names: 270-E-1; 216-ER-1; 270-E CNT; 270-E Condensate Neutralization Tank

Reclassification: None

Type:	Neutralization Tank	Start Date:	1/1/1952
Status:	Inactive	End Date:	1/1/1957
Description:	The site is an underground steel tank. It is marked and posted with Restricted Access-Inactive Tank signs. It is located within a large Underground Radioactive Material Area that resulted from the stabilization of the adjacent 216-B-64 basin and UPR-200-E-64 sites.		
Location:	This tank is located west of the 221-B Building, near the southwest corner of the 216-B-64 Basin.		
Related Sites/ Structures:	It is associated with 270-E, the 221-B, 224-B Buildings, 200-E-160-PL and the 216-B-12 Crib. UPR-200-E-64 documents that ants brought contamination to the surface in the vicinity of the 270-E Tank and caused contamination to spread.		
Process Description:	The tank was used to neutralize acidic process condensate from the 221-B and the 224-B facilities, via the 241-ER-151 Diversion Box (lines V219, V225, 9719, 9653, 9808). Condensate entered the tank at the bottom and flowed upward through the limestone to an outlet pipe located 2.4 meters (8 feet) above the tank bottom. The tank contained a limestone bed through which the condensate percolated, reacted, and then overflowed to the 216-B-12 Crib. The tank had a 100 centimeter (40 inch) diameter chute and a 15 centimeter (6 inch) diameter riser extending to the surface from the stainless steel below grade tank.		
Waste Type:	Chemicals		
Waste Description:	A 1974 report indicated the surface of the sludge was located at 2.27 meters (7.58 feet). No liquid was visible at this time. Sludge volume was estimated to be 14,440 liters (3,800 gallons). Radiation readings were less than 100 counts per minute direct and smearable, and less than 0.5 millirad/hour at the risers. Waste in this tank should include: limestone, process condensate precipitates, salts and residual process condensates. The process condensate that passed through this tank contained an average of 0.015 grams per gallon of uranium, 2.6 E-7 grams per gallon of plutonium and 1.8 E-6 curies per gallon of beta emitters.		

Code:	299-E24-111	Classification:	Accepted
Names:	299-E24-111; Experimental Test Well Site; Lysimeter Test Site; Miscellaneous Stream #803	Reclassification:	None
Type:	Injection/Reverse Well	Start Date:	9/22/1980
Status:	Active	End Date:	1/1/2000
Description:	The site is an injection well surrounded by 32 observation wells. The 299-E24-111 injection well head is located inside a small posted Underground Radioactive Material area. There is a small Soil Contamination Area (SCA) located southwest of the well. The SCA is where the 5,700 liter (1500 gallon) above ground solution tank (connected to the well) had been located.		
Location:	The site is located southwest of the PUREX facility and west of the 216-A-38-1 Crib.		
Related Sites/ Structures:	The injection well was connected to a 5,700-liter (1,500-gallon) above ground mixing tank. The injection well is surrounded by eight concentric rings of observation wells. There are a total of 32 observation wells. The observation wells are each 15-centimeter (6-inch) diameter steel casings, 19.8 meters (65 feet) long. These observation wells are identified as 299-E24-76 through 299-E24-107. The injection well is constructed of a 4.6-meter (15-foot) long, 2.5-centimeter (1-inch) diameter pipe inside a 4.6-meter (15-foot) casing that is welded together at the lower end. This assembly is cemented inside a 4.6-meter (15-foot), 15-centimeter (6-inch) diameter Schedule 40 steel well.		

Process Description: In 1980, uniform solutions of calcium chloride, calcium nitrate, and selected tracers were placed into the above ground mixing tank on a weekly basis and injected into the well. The 32 observation wells monitored the injected material. The tracers included sorbing and nonsorbing ions. Calcium was added at a concentration of 0.01 normal as 0.005 normal calcium nitrate plus 0.005 normal calcium chloride to reduce permeability changes of the sediments during injection, and to provide the nonsorbing ions nitrate and chloride. Cesium-134 is a gamma emitter and undergoes strong sorption by the sediments. Strontium-85 was chosen because it is a gamma emitter and is moderately sorbed by sediments. Each injection consisted of filling the holding tank, adding the tracers, mixing the water and tracers, and then injecting the solution. Water for each of the 10 weekly injections was transported to the site from a nearby safety shower in 1900 liter (500 gallon) vinyl bags. From the bags, 3800 liters (1000 gallons) of water was metered into a 5700 liter (1500 gallon) tank. Calcium salts and additional sorbing tracers, barium and rubidium, were dissolved in two 50 liter (13 gallon) carboys at the injection site. The carboys were rinsed and the rinsate was added to the tank. The radiological tracers strontium-85 and cesium-134 were delivered for each weekly injection as a 20 milliliter solution. The glass vial containing the tracers arrived at the site in a lead container called a pig. The pig was placed in the tank on a rack before opening and removing the vial. The vial was handled with modified tongs. The cap was unscrewed from the vial, the vial contents poured into the calcium solution in tank, and the vial and cap rinsed using a polyethylene wash bottle. Washing continued until less than 300 counts per minute were observable with a handheld GM probe in contact with the vial and cap. For the first three tanks of solutions, the contents were circulated in tank until the solution was uniform, as evidenced by constant gamma activity at all points on the tank exterior. It was found that a uniform count rate was obtainable within 5 minutes after starting circulation, but mixing was continued for 2 hours. For the remaining injections, the tracer and calcium solutions were added after 1900 liters (500 gallons) of water was metered into the tank. Adding the final 1900 liters (500 gallons) induced enough mixing to obtain a uniform count rate at the tank surface. Both the circulation and partial filling method appeared to provide adequate mixing. In May and June 2000, a new injection well was placed near the original injection well, but outside the posted Underground Radioactive Material area. The new well was injected five times. The third injection contained a potassium bromide tracer. Four soil cores were collected around the new injection well. Each core sample was 18 meters (59 feet) deep.

Waste Type: Chemicals

Waste Description: Eleven 3,780-liter (1,000-gallon) injections of uniform solutions of calcium chloride, calcium nitrate were made into the injection well. Eight injections contained selected radioactive tracers (cesium-134 and strontium-85). Three injections did not contain tracers. In 1995 the injection well was surveyed with a Radiologic Logging System (RLS) down-hole logging probe. No Strontium-85 was identified. Residual cesium-134 peaks were identified at depths between 4.9 and 5 meters (16 and 16.5 feet). The fact that cesium-134 was detected 15 years after injection is an indication of the tracer's high sorption potential. The maximum activity was 0.04 picocuries per gram (pCi/g) at 5 to 5.2 meters (16.5 to 17 feet) below grade level. PNNL scheduled an additional injection experiment at this site in 2000 that added another injection well (10 meters [30 feet] deep) near the center of the cluster, injected a potassium bromide tracer and collected soil cores. Each of the five injections was equal to 4000 liters. Data were obtained by lowering sensors to the desired depth in observation wells. Sensors used included neutron-neutron moisture probes, geiger-Muller (GM) probes, gamma energy analysis (GEA) probes, and gamma-gamma probes.

Code: 2607-E3

Classification: Accepted

Names: 2607-E3; 2607-E3 Septic System; 2607-E3 Septic Tank and Drainfield; TFS of 218-E-4; Tile Field South of 218-E-4

Reclassification: None

Type: Septic Tank **Start Date:** 1/1/1948
Status: Inactive **End Date:** 1/1/1997

Description: The site is a septic tank and drainfield. It is surrounded with a chain and marked with a sign that reads Sanitary Sewer/Drain Field. The septic tank is constructed of reinforced concrete. The tank is 8.7 meters (28 feet 8 inches) long, 2.7 meters (9 feet) wide, and 3.8 meters (12 feet 6 inches) deep (interior dimensions). The tank had a design capacity of 38,680 liters (10,220 gallons) based on a user capacity of 292 persons, a flow of 132 liters (35 gallons) of sewage per capita per day, and an average detention time of 1 day. The top of the tank is at the ground surface. The tank was accessed through three 0.9 meter (3 foot) manholes. The drainfield is comprised of at least 712 meters (2,336 feet) of vitrified clay pipe or drain tile (at least 2.4 meters [8 feet] per capita). The laterals are open jointed and are spaced 2.4 meters (8 feet) apart.

Location: This unit is located approximately 100 meters (400 feet) north of the 221-B Building. The drainfield is located north of the septic tank and south of the 218-E-4 Burial Ground.

Related Sites/ Structures: The 2607-E3 Septic System was associated with B-Plant facilities.

Process Description: The 2607-E3 Septic Tank and Drainfield were designed to accept, treat, and dispose of sanitary sewer effluent from the buildings in the B Plant complex.

Waste Type: Sanitary Sewage

Waste Description: This site received sanitary wastewater and sewage from B Plant facilities at an estimated rate of 509 cubic feet (14.4 cubic meters) per day. The septic tank was abandoned in 1997. No information was provided related to sampling of the tank contents. DOE/RL-92-05 states that the septic tank and tile field are not known to contain radioactive or hazardous waste.

Code: 2607-E5 **Classification:** Accepted

Names: 2607-E5; 276-C, 209-E and 2718-E Septic Tank; 209-E Septic Tank **Reclassification:** None

Type: Septic Tank **Start Date:**

Status: Inactive **End Date:**

Description: In July 2011, the septic tank was properly abandoned per WAC 246-272A-0300. This system included a single compartment tank with a dosing system and a leaching trench. An abandoned tile field, which was replaced by the sanitary leaching trench, is also included with this site. This septic system received sanitary wastewater and sewage from the Critical Mass facilities near 209-E.

Location: This unit lies north of the 209-E Building and east of the 2607-C Sanitary Crib.

Related Sites/ Structures: The 2607-E5 Septic Tank is associated with the 209-E, the 2704-C and the 2718-E Buildings. Original construction of the tank was for buildings 2704-C and 2707-C. Later modifications added two additional septic tanks, 2607-E7 (WIDS 2607-E7A), 2607-E (WIDS 2607-E7B), and the leaching trench. During the history of this system, mobile offices have been connected to the system. Two examples were the addition of MO-337 and MO-543. These mobile offices have since been moved.

Process Description: The connection to 2718E was investigated in 2010. After reviewing available drawings and Ground Penetrating Radar scan results, no sewer line from 2718-E to 2607-E5 could be found. Field walk downs verified there are no restrooms, showers, sinks or floor drains in 2718-E.

WHC-SD-LL-SP-001 indicated the 2607-E5 Septic Tank and associated leaching trench

received sanitary sewer effluent from the 209-E, the 2704-C, 276-C, and the 2718-E Buildings. It states that a construction design was approved in 1995 to add more facilities to the 2607-E5 system, but the project was cancelled. Other documentation and field investigations dispute the accuracy of the document, related to the facilities served by 2607-E5. Drawing M-2904-E, Sheet 27 does not show enough detail to make a determination. H-2-4033 shows that 276-C had no sanitary waste. All liquid waste from this facility went to the 216-C-3 crib. Revision 7 of H-2-4033 (1963) revised the drawing to include the abandoned tile field and the two small inline septic tanks (2607-E7 and 2607-E). (The WIDS numbers for these two tanks are 2607-E7A and 2607-E7B). The two smaller tanks were probably added when 209-E (Critical Mass Laboratory) was tied into the system.

Waste Type: Sanitary Sewage

Waste Description: WHC-SD-LL-SP-001 states this system received sanitary wastewater and sewage from the 209-E, the 2704-C, and the 2718-E Buildings at an estimated rate of 78 cubic feet (2.21 cubic meters) per day. Originally, the 2607-E5 tank serviced the 2707-C Change House. The change house had both a toilet and shower used by personnel working within the Hot Semiworks facilities. There may be a potential for radiological contamination within the 2607-E5, 2607-E7 (WIDS 2607-E7A), 2607-E (WIDS 2607-E7B), Sanitary Leaching Trench, or the Abandoned Tile Field. A 2010 drawing review and facility walkdown found no drains, sinks or toilet facilities in the 2718E building.

Code: 2607-E6	Classification: Accepted
Names: 2607-E6; 2607-E6 Septic Tank and Tile Field	Reclassification: None
Type: Septic Tank	Start Date: 1/1/1953
Status: Inactive	End Date: 1/1/1997

Description: The site is a septic tank and drainfield. The drain field is surrounded by a wooden fence. The surface is vegetated with brush.

Location: This unit is located inside 200 East Area, north of 4th Street and northwest PUREX. It is between two railroad spurs.

Process Description: The unit received sanitary waste from MO405 and the PUREX facility.

Waste Type: Sanitary Sewage

Waste Description: The site received sanitary wastewater and sewage from MO-405 and the PUREX facility. The estimated rate of waste generation is 43.5 cubic meters per day.

Code: 2607-E7A	Classification: Accepted
Names: 2607-E7A; 2607-E7	Reclassification: None
Type: Septic Tank	Start Date: 1/1/1963
Status: Inactive	End Date:

Description: In July 2011, the septic tank was properly abandoned per WAC 246-272A-0300. The septic tank received sanitary wastewater and sewage. This tank is a 1.7 meters (66 inches) by 2.7 meters (105 inches) precast concrete septic tank with a single 61 centimeters (24 inch) diameter cover. The tank is inline with the 2607-E5 septic tank and the 2607-E (WIDS 2607-E7B). The septic tank drained to the sanitary leaching trench.

Location: This system lies north of the 209-E Building and west of the 2607-E5 Septic Tank.

Related Sites/ Structures: The 2607-E7A Septic System is associated with the 209-E, 2704-C, 2718-E, MO-337 (moved) and the MO-543 (moved) Buildings. This system is in series with the 2607-E5, 2607-E7B septic tanks and a leaching trench.

Process Description: The 2607-E7A Septic System and the associated leaching trench were designed to accept and treat sanitary sewer effluent from the 209-E, 2704-C, 2718-C, MO-337 (moved to another location), and MO-543 (moved to another location).

Waste Type: Sanitary Sewage

Waste Description: The 2607-E7A Septic System receives sanitary wastewater and sewage at an estimated rate of 58 cubic feet (1.64 cubic meters) per day.

Code: 2607-E7B **Classification:** Accepted

Names: 2607-E7B; 2607-E7B Septic System; 2607-E7 **Reclassification:** None

Type: Septic Tank **Start Date:** 1/1/1963

Status: Inactive **End Date:**

Description: In July 2011, the septic tank was properly abandoned per WAC 246-272A-0300. This septic tank received sanitary wastewater and sewage. This tank is a 1.7 meters (66 inches) by 2.7 meters (105 inches) precast concrete septic tank with a single 61 centimeters (24 inch) diameter cover. The tank is inline with the 2607-E5 septic tank and the 2607-E7 (WIDS 2607-E7A). The septic tank drained to the sanitary leaching trench.

Location: This system lies north of the 209-E Building and west of the 2607-E5 Septic Tank.

Related Sites/ Structures: The 2607-E7B Septic System is associated with the 209-E, 2704-C, 2718-E, MO-337 (moved) and the MO-543 (moved) Buildings. This system is in series with the 2607-E5, 2607-E7A septic tanks and a leaching trench.

Process Description: The 2607-E7B Septic System and the associated leaching trench were designed to accept and treat sanitary sewer effluent from the 209-E, 2704-C, 2718-C, MO-337 (moved to another location), and MO-543 (moved to another location).

Waste Type: Sanitary Sewage

Waste Description: The 2607-E7B Septic System receives sanitary wastewater and sewage at an estimated rate of 58 cubic feet (1.64 cubic meters) per day.

Code: 2607-E9 **Classification:** Accepted

Names: 2607-E9; 2607-E9 Septic System; 242B/BL Septic Tank and Drain Field **Reclassification:** None

Type: Septic Tank **Start Date:** 1/1/1951

Status: Inactive **End Date:**

Description: This 1,900-liter (500-gallon) septic tank received sanitary wastewater and sewage from the 242-B and the 242-BL Buildings. This system has an associated drain field. It was abandoned and the tank filled with sand. The site is in a contamination area. A brief visit was made to the site in February 2000 to find the drainfield and to try to improve the mapping of the site. A "Drainfield" sign was found on the ground on the eastern side of the contamination area that surrounds the site. The former extent of the drainfield can be approximated using fence posts inside the contamination area (some of which still have chain attached), fallen chain on the

ground plus the fence posts making up the eastern boundary of the contamination area. No access ports, lids or risers associated with the septic tank were visible. Evidence of the septic tank may have been obscured by tumbleweeds growing in the center of the contamination area near the drainfield.

Location: This unit lies north of the 207-B Retention Basin and east of the 242-B Building.

Related Sites/ Structures: The 2607-E9 Septic Tank is associated with a drain field and the 242-B and the 242-BL Buildings.

Process Description: The 2607-E9 Septic Tank and associated drain field were designed to accept sanitary sewer effluent from the 242-B and the 242-BL Buildings.

Waste Type: Sanitary Sewage

Waste Description: The 2607-E9 Septic Tank received sanitary wastewater and sewage at an estimated rate of 0.71 cubic feet (0.02 cubic meters) per day.

Code: 2607-E12

Classification: Accepted

Names: 2607-E12; 2607-E12 Septic System

Reclassification: None

Type: Septic Tank

Start Date:

Status: Active

End Date:

Description: The septic system consists of the original 242-A septic tank and seepage pit (see subsite 1), two newer septic tanks and two drain fields (see subsite 2) that service multiple buildings. The 5,000 gallon (18,927 liters) tank was converted to a dosing chamber when the new 10,000 gallon (37,854 liters) septic tank was installed approximately 45 feet (13.7 meters) to the south. The first drain field is located west of the 207-A Retention Basins. It was replaced with a trench-like drainfield located approximately 400 feet (122 meters) east of the septic tanks and east of the 207-A Retention Basins.

Location: The original 242-A septic tank and seepage pit is located on the 242-A building parking lot. Two newer septic tanks and two drainfields are located east of Canton Avenue, north of 4th Street. The first drainfield is located west of the 207-A South retention basins. The second drainfield is located east of the retention basins and has a barricade marker fence around the large depression.

Related Sites/ Structures: Buildings serviced by this system are: 272-AW, MO-266, MO-268, MO-267, MO-393, MO-996, 241-A Tank Farm, 241-AP, and 242-A.

Process Description: The settling chamber (the larger southern most tank) receives the effluent first. The effluent then goes to the dosing chamber (smaller northern tank) which is connected by underground pipeline to the trench-like drainfield.

Waste Type: Sanitary Sewage

Waste Description: Characteristics of the sanitary waste water from the 200 Areas are considered to be similar to residential sanitary waste. There are no known process or radioactive waste streams entering the sanitary waste system.

This Site has the Following SubSites:

Code: 2607-E12:1

Names: 2607-E12:1; Original Septic Tank and Seepage Pit

Code: 2607-E12:2
Names: 2607-E12:2; 2607-E12 Septic System

Code: 2607-E12:1
Classification: Accepted
Names: 2607-E12:1; Original Septic Tank and Seepage Pit
Reclassification: None
Type: Septic Tank
Start Date:
Status: Active
End Date:

Description: The original Septic Tank and Seepage Pit for the 242-A evaporator building is located beneath the building parking lot, east of 242-A. It is surrounded by yellow protective concrete posts. This portion is inactive.

The SubSite is Part Of:

Code: 2607-E12
Names: 2607-E12; 2607-E12 Septic System

Code: 2607-E12:2
Classification: Accepted
Names: 2607-E12:2; 2607-E12 Septic System
Reclassification: None
Type: Septic Tank
Start Date:
Status: Active
End Date:

Description: 2607-E12 septic tanks and drain filed are located east of Canton Avenue, north of 4th Street and west of the 207-A South retention basins. The drainfield is located east of the retention basins and has a barricade marker fence around the large depression.

The SubSite is Part Of:

Code: 2607-E12
Names: 2607-E12; 2607-E12 Septic System

Code: 2607-EA
Classification: Accepted
Names: 2607-EA; 2607-EA Septic Tank and Drywell
Reclassification: None
Type: Septic Tank
Start Date: 1/1/1976
Status: Inactive
End Date:

Description: The 2607-EA Septic System is a small septic tank and an associated drywell (cesspool). The septic tank is approximately 3.0 meters (10 feet) long and 2.4 meters (8 feet) wide with rounded ends. The associated drywell is connected to the tank by a short (approximately 5 foot [1.5 meter] long) pipeline. The drywell is constructed of 8 courses of concrete blocks arranged in a circle. The alternating courses of blocks have staggered joints with no mortar. It is filled with 1.3 to 5.1 centimeter (0.5 to 2.0 inch) gravel and capped with a concrete lid with a vent in the middle. A vent pipe extends from the lid to 0.6 meters (2 feet) above grade.

Location: The septic tank is located west of the 241-A Tank Farm and directly south of the 244-AR Vault. The drywell is approximately 5 feet (1.5 meters) south of the tank.

Waste Type: Sanitary Sewage

Waste Description: The system received sanitary sewage. When in use, the system was estimated to receive waste at the rate of 60 liters/day (16 gallons/day). There is concern of possible rad contamination based on the facilities served.

Code: UPR-200-E-9 **Classification:** Accepted

Names: UPR-200-E-9; Liquid Overflow at 216-BY-201; UN-200-E-9 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1955

Status: Inactive **End Date:**

Description: The site has been surface stabilized with gravel and is posted as an Underground Radioactive Material area.

Location: The location of this unplanned liquid release is adjacent to the 216-BY-201 Flush Tank, north of the 241-BY Tank Farm. A large area of surface contamination north of 241-BY Tank Farm was later named UPR-200-E-89.

Release Description: On September 15, 1955 approximately 41,600 liters (11,000 gallons) of tri-butyl phosphate (TBP) supernate waste overflowed from the 216-BY-201 flush tank and ran over the ground toward the 216-B-43 crib. Most of the contamination was pushed into a shallow area southeast of the 216-B-43 crib and covered with 0.6 meters (2 feet) of clean dirt. The contamination left near the flush tank was covered with 3 meters (10 feet) of clean soil.

Related Sites/ Structures: UPR-200-E-9 is associated with 216-BY-201 and the 216-B-43 through 50 cribs.

Process Description: The 216-BY-201 flush tank received tri-butyl phosphate waste via the 241-BY tank farm and then released it to the 216-B-43 through 49 cribs. The 216-B-50 crib did not receive tri-butyl phosphate waste.

Waste Type: Process Effluent

Waste Description: The 216-BY-201 Flush Tank leaked supernatant waste from the tributyl phosphate (TBP) process to the ground.

Code: UPR-200-E-10 **Classification:** Accepted

Names: UPR-200-E-10; Contaminated Purex Railroad Spur; UN-200-E-10 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1957

Status: Inactive **End Date:**

Description: A contamination spread occurred along the railroad tracks while transporting tube bundles from PUREX to the burial ground. The release is not separately marked or posted.

Location: The site is along the PUREX railroad right-of-way, both inside and outside the PUREX exclusion fence. The contamination inside the fence is considered part of the Railroad Cut (WIDS site code 200-E-44).

Release Description: In September 1957, contamination ranging from 5 to 20 rads/hour was spread in the craneway, canyon, railroad tunnel, and on the remote crane and railroad right-of-way during transport of two failed waste concentrator tube bundles.

Related Sites/ Structures: The site is associated with 200-E-44 (PUREX Railroad Cut).

Waste Type: Soil

Waste Description: Loose contamination from concentrator tube bundles spread from the PUREX crane, into the tunnel and onto the railroad right-of-way.

Code: UPR-200-E-12 **Classification:** Accepted

Names: UPR-200-E-12; Contaminated Purex Railroad Spur; UN-200-E-12 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1957

Status: Inactive **End Date:**

Description: This unplanned release is no longer marked or posted. Portions of the TC-4 Spur (a.k.a. UPR-200-E-88) and a section of track south of the 218-E-5 Burial Ground (UPR-200-E-95) have been covered with dirt and posted with Underground Radioactive Material signs.

Location: The unplanned release effected the railroad track extending from the PUREX tunnel to an unnamed Burial Ground.

Release Description: On November 15, 1957, a burial box containing failed process jumpers dripped contaminated liquid while in transit to the burial ground. This resulted in spotty contamination of 40 to 1,700 millirads/hour to the railroad roadbed. Contamination also spread to the canyon deck, tunnel, and tunnel cut.

Related Sites/Structures: This site is associated with UPR-200-E-11, UPR-200-E-88, 200-E-43 and 200-E-44.

Process Description: Some burial casks were shielded with water that was removed before placing the material into the burial ground. Sometimes railcars were washed down to remove loose contamination before transporting the load to the burial ground.

Waste Type: Water

Waste Description: Contaminated liquid with readings ranging from 40 to 1,700 millirads/hour dripped on the railroad track during transport of a burial box containing failed process jumpers. The dose rate on the burial box was 450 millirads/hour at 45.8 meters (150 feet).

Code: UPR-200-E-17 **Classification:** Accepted

Names: UPR-200-E-17; Overflow at 216-A-22; UN-200-E-17 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1958

Status: Inactive **End Date:**

Description: The 216-A-22 crib is marked with a single cement post and posted with Underground Radioactive Material signs. The unplanned release is not separately marked or posted. The release cannot be visually identified.

Location: The release effected the ground on top of the 216-A-22 Crib, located north of PUREX, north of the 203-A facility, near the 216-A-28 French Drain.

Release Description: Sufficient splashing occurred when the 216-A-22 Crib inlet failed, causing the ground on top of the crib to become yellow with uranium. No specific occurrence date is mentioned. HW-60807 was issued in July 1959, so it occurred prior to that date. The 216-A-22 french drain was active from 1955 through 1958.

Related Sites/ The site is associated with 216-A-22 and 203-A.

Structures:

Process Description: The 203-A tank farm was used for storage and shipping of uranyl nitrate hexahydrate (UNH) product and concentration of UNH waste. It consisted of 460,000 liter (100,000 gallon) stain less steel tanks for UNH storage and three smaller nitric acid tanks.

Waste Type: Process Effluent

Waste Description: The release consisted of uranium (from UNH storage) contamination on the ground surface from the failed 216-A-22 Crib inlet.

Code: UPR-200-E-19 **Classification:** Accepted

Names: UPR-200-E-19; Contamination Release at 216-A-6 Sampler Pit; UN-200-E-19 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1959

Status: Inactive **End Date:**

Description: The Unplanned Release is not visually obvious, but a single T-Post with a WIDS number is placed near the 220A structure. The 220A area is posted Fixed Contamination/Underground Radioactive Material Area.

Location: The release occurred adjacent to the 220A structure. 220A is synonymous with the A-6 Proportional Sampler. It is located east of the 202-A Building.

Release Description: HW-60807 refers to the A-6 Proportional Sampler Pit on page 17. The report states that low-level fission product seeped into the ground around the edges of the concrete pad. The contamination was caused by moisture dripping from the vent pipe bonnet.

Related Sites/ Structures: The site is associated with the 216-A-6 Crib and 200-E-113-PL and structure 220A.

Process Description: Pipeline 200-E-113-PL passed through the Proportional Sampler before terminating in the 216-A-6 crib.

Waste Type: Process Effluent

Waste Description: The site received low-level fission products that dripped onto the ground from the vent pipe bonnet.

Code: UPR-200-E-20 **Classification:** Accepted

Names: UPR-200-E-20; Contaminated Purex Railroad Spur; UN-200-E-20 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1959

Status: Inactive **End Date:**

Description: The site is located at the PUREX railroad right-of-way. The release is not separately marked or posted.

Location: Contamination occurred on the PUREX railroad bed and right-of-way to the Burial Ground, both inside and outside the PUREX exclusion fence. The contamination inside the fence is considered part of the PUREX Railroad Cut (Waste Information Data System [WIDS] site code 200-E-44).

Release Description: On November 20, 1959, PUREX tube bundles in transit for burial provided some spotty ground contamination.

Waste Type: Process Effluent

Waste Description: While transporting PUREX tube bundles to the burial ground via railcar, spotty contamination was found on the railroad track.

Code: UPR-200-E-21 **Classification:** Accepted

Names: UPR-200-E-21; 216-A-6 Overflow; UN-200-E-21 **Reclassification:** None

Type: Unplanned Release **Start Date:** 2/1/1959

Status: Inactive **End Date:**

Description: The unplanned release is not separately marked or posted. The 216-A-6 Crib area has been surface stabilized and is posted as "Underground Radioactive Material."

Location: Contamination occurred adjacent to the 216-A-6 Crib. The crib is located east of the PUREX facility, outside the 200 East Area perimeter fence.

Release Description: In February 1959, the 216-A-6 Crib overflowed and contaminated the adjacent area to 500 millirads/hour.

Related Sites/ Structures: The release is associated with the 216-A-6 crib.

Waste Type: Process Effluent

Waste Description: The release contaminated the crib surface with beta/gamma with readings to 500 millirads/hour.

Code: UPR-200-E-29 **Classification:** Accepted

Names: UPR-200-E-29; 216-A-6 Overflow; UN-200-E-29 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/20/1961

Status: Inactive **End Date:**

Description: The 216-A-6 Crib area has been surface stabilized and is posted as "Underground Radioactive Material."

Location: The release location is in the area of the 216-A-6 Crib.

Release Description: HW-67985, issued on January 20, 1961, reported the 216-A-6 Crib overflowed.

Related Sites/ Structures: The site is associated with 216-A-6 Crib.

Waste Type: Process Effluent

Waste Description: The release contaminated the crib surface with beta/gamma with readings to 30 rads/hour at a distance of 1.2 meters (4 feet).

Code: UPR-200-E-33 **Classification:** Accepted

Names: UPR-200-E-33; Contaminated Purex Railroad **Reclassification:** None

Tracks; UN-200-E-33

Type: Unplanned Release **Start Date:** 1/1/1964
Status: Inactive **End Date:** 1/1/1964

Description: A contamination spread occurred on the PUREX railroad bed and right-of-way to the burial ground. The contamination was located both inside and outside the PUREX exclusion fence. The contamination inside the fence is considered part of the PUREX Railroad Cut (Waste Information Data System [WIDS] site code 200-E-44).

Location: The release site is located at the railroad right-of-way from PUREX to the 200 East Burial Ground, adjacent to the 216-A-9 crib.

Release Description: On March 20, 1964, a leaking tube bundle burial box in transit to the burial ground contaminated a portion of the railroad right-of-way and area adjacent to the 216-A-9 Crib. The contamination spread occurred in February 1964. The February Monthly Report for 1964 (HW-81078) was issued on 3-20-64. This report states that decontamination was successful, but does not give any details of the decontamination activity.

Waste Type: Chemicals

Waste Description: A description of the waste is not available from documents. Contamination resulted from a leaking tube bundle in a burial box on a railcar.

Code: UPR-200-E-35 **Classification:** Accepted

Names: UPR-200-E-35; 218-E-13; Buried Contaminated Pipe; UN-218-E-1 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1966

Status: Inactive **End Date:** 1/1/1966

Description: The site is the location of a (1966) contaminated concrete pipe repair. The site is no longer marked or posted. It is inside the PUREX exclusion fence.

Location: The site is located west of the PUREX Patrol Gate House south of 4th Street.

Release Description: The release is from an underground concrete line repair in August 1966. This site received broken pieces of contaminated concrete from the pipe trench, which were left in the excavation hole and buried following repair to the piping at that location. The site contains less than 1 curie fission products. It was estimated to be located 107 meters (350 feet) west of the PUREX badge house.

Waste Type: Demolition and Inert Waste

Waste Description: This site received broken pieces of contaminated concrete from the pipe trench, which were left in the excavation hole and buried following repair to the piping at that location. The site contains less than 1 curie fission products.

Code: UPR-200-E-37 **Classification:** Accepted

Names: UPR-200-E-37; Contamination East of Hot Semi-Works; UN-200-E-37; UN-216-E-37; UN-216-E-39 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1967

Status: Inactive **End Date:** 1/1/1989

Description: There is currently no physical evidence of the unplanned release site. It is no longer marked or posted.

Location: The release occurred east of the Hot Semi-Works facility, south of 7th Street.

Release Description: On July 31, 1967, a release from the Strontium Semi-Works (SSW) facility was documented on a Radiation Occurrence Report. At the time of the occurrence, a fence surrounded the facility. The original occurrence description stated that the contamination was confined to the east side of the Strontium Semi-Works, extending a length of 183 meters (200 yards) and also to a dirt road outside the facility fence. The area was roped off, roads were blocked and sprinklers were set up in the contaminated areas. The blacktop roads were cleaned.

Waste Type: Process Effluent

Waste Description: A contamination spread (particulate) was caused by the removal of two Semiworks A cell pumps, with a maximum beta/gamma reading of 200 millirad/hour.

Code: UPR-200-E-43 **Classification:** Accepted

Names: UPR-200-E-43; Road Contamination Near 241-BY Tank Farm; UN-200-E-43 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1972

Status: Inactive **End Date:**

Description: The location of this release is not marked or posted.

Location: The release occurred on a section of the roadway between the 241-BY Tank Farm and the burial ground. The exact location cannot be determined with existing documentation.

Release Description: On January 10, 1972, while in transit for burial, the 102-BY Pump contaminated a section of the road from the 241-BY Tank Farm to the burial ground. Contamination readings ranged from 1,000 to 100,000 counts per minute.

Waste Type: Process Effluent

Waste Description: The road contaminated with beta/gamma with readings of 1,000 to 100,000 counts per minute while transporting a pump from 241-BY-102 to the burial ground.

Code: UPR-200-E-50 **Classification:** Accepted

Names: UPR-200-E-50; Soil Contamination at the Overground Equipment Storage Yard; UN-200-E-50 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1974

Status: Inactive **End Date:**

Description: In 1974, an area of ground contamination was identified that measured from 15 to 30 meters (50 to 100 feet) wide and 137 meters (450 feet) long south southeast of the Overground Storage Area. The release is not currently marked or posted.

Location: The release location was southeast of the Overground Radioactive Equipment Storage Yard and north of 241-C Tank Farm.

Release Description: On September 24, 1974, ground contamination was identified outside the radiation zone at the Overground Radioactive Equipment Storage Yard, north of 241-C Tank Farm. A resulting swath of ground contamination was identified (approximately 75 feet wide and 450 feet long) extending southeast of the Overground Storage Yard with particle contamination ranging from

100,000 counts per minute to 3000 counts per minute, decreasing in intensity and frequency with distance from the source.

Follow-up surveys of the Overground Storage Area identified a possible source to be a 6 meter by 9 meter (20 foot by 30 foot) area of contaminated soil inside the radiation zone. Highly contaminated pumps (250 rad per hour) had been stored in that area with readings of 300 millirem per hour under the where pumps had been sitting. The pumps were moved to the burial ground on April 26, 1974. Due to climatic conditions when the pumps were moved, the soil beneath the pumps was not completely decontaminated. The contaminated ground beneath the pumps was covered with plastic and secured with dirt. On September 26, 1974, high winds blew the plastic cover loose, causing contamination to spread downwind (southeast) of the Overground Storage Yard. An additional survey in the Overground Storage Yard identified two empty capsules with smearable contamination of 30,000 counts per minute and more soil contamination beneath the capsules reading 1.5 rad per hour. A resulting contamination spread, measuring approximately 75 feet wide and 450 feet long was identified extending southeast of the Overground Storage Yard. Levels of contamination ranged from 100,000 counts per minute near the storage area and decreased to 3000 counts per minute. The capsules were taken to the burial ground to avoid further contamination spreads.

Related Sites/ Structures: This release is associated with 200-E-53.

Waste Type: Soil

Waste Description: Wind blew specks of contamination out of the Overground Storage Yard posted radiation zone. The source was from contaminated equipment being stored at the Overground Radioactive Equipment Storage Yard. Maximum beta/gamma readings of 3,000 to 100,000 counts/minute were found on a swath of ground south southeast of the storage area. The intensity of the radiological readings decreased with greater distance away from the source.

Code: UPR-200-E-62	Classification: Accepted
Names: UPR-200-E-62; Transportation Spill Near 200-E Burning Ground; UN-200-E-62; UN-216-E-62	Reclassification: None
Type: Unplanned Release	Start Date: 1/1/1982
Status: Inactive	End Date: 1/1/1982

Description: The 1982 release site was an area approximately 5 centimeters (2 inches) wide and 30 meters (100 feet) long on a hill near the 200 East Overground Storage Area. The release was cleaned up within 3 days. The site is no longer marked or posted.

Location: The release occurred at the 200 East Burning Ground (also known as the 200 East Burn Pit), located south of 12th Street and west of Canton Ave.

Release Description: Radioactive liquid was spilled from a pressure test assembly while in transit. The release occurred on March 19, 1982. The ground contamination was picked up, placed in barrels, and removed to the burial ground. The release was cleaned up to background levels and was released from area posting on March 22, 1982.

Related Sites/ Structures: The release is associated with the Overground Storage Area, sitecode 200-E-53.

Waste Type: Process Effluent

Waste Description: While transporting a pressure test assembly, contaminated liquid dripped onto the dirt road. Contamination consisted of beta/gamma readings to 350 millirads/hour.

Code: UPR-200-E-64 **Classification:** Accepted
Names: UPR-200-E-64; Radioactive Soil and Ant Hills; **Reclassification** None
 UN-200-E-64; UN-216-E-36
Type: Contamination Migration **Start Date:** 1/1/1984
Status: Inactive **End Date:**

Description: The site is a large area posted with chain and Underground Radioactive Material Area signs. The size and shape of the posted area has changed periodically as a result of annual radiological surveys and clean up efforts.

Location: The site is inside 200 East Area, north of 7th Street, adjacent to the west side of the 216-B-64 Basin.

Release Description: The original unplanned release documentation states ants burrowed into contaminated soil that was caused by leakage from the 270-E-1 Tank and brought the contamination to the surface. Later documentation suggests the contamination source was the small diameter vertical pipe (swab riser) located west of 216-B-64 basin.

Waste Type: Soil

Waste Description: The contamination found in the soil and ant hills consisted predominantly of cesium-137 and strontium-90, with readings to 60,000 counts per minute. Several sources of contamination have been suggested. A swab riser on an underground pipeline appears to be the source.

Code: UPR-200-E-66 **Classification:** Accepted
Names: UPR-200-E-66; 216-A-42 Basin Contamination **Reclassification** None
 Release; UN-200-E-66; UN-216-E-66
Type: Unplanned Release **Start Date:** 1/1/1984
Status: Inactive **End Date:**

Description: The release is not separately marked or posted. The 216-A-42 Basin had been surrounded by a wire fence and posted with Soil Contamination signs. In 2001, the fence was removed and the area was surface stabilized. It was covered with clean backfill and down posted to Underground Radioactive Material (URM). The release site is located within the URM area.

Location: The release site was located adjacent to the 216-A-42 Retention Basin, which is located outside of the eastern 200 East Area perimeter fence.

Release Description: A November 7, 1984, a radiation survey identified contamination both inside and outside of the area posted as a radiation zone around the perimeter of the 216-A-42 Basin. Contaminated liquid in the basin had evaporated allowing dried contamination specks to be spread by wind. At the time of this release, contamination levels were 40,000 counts per minute on the ground within the retention basin fence. Smears of the walls and bottom of the basin ranged from 200 to 100,000 counts per minute. The area outside the retention basin fence revealed specks with a maximum level of 3,000 counts per minute located between the road and the fence.

Related Sites/ Structures: The release is associated with the 216-A-42 Basin.

Waste Type: Process Effluent

Waste Description: The contamination consisted of beta/gamma particulates, with readings inside the area to 40,000 counts per minute and outside to 3,000 counts per minute. A routine surface radiation survey done in 1988 found spots of contamination on the south edge of the site with readings up to 200,000 disintegrations per minute (or 20,000 counts per minute). A radiation survey

done outside the 216-A-42 Basin perimeter fence done in 1998 did not identify any contamination outside the basin.

Code: UPR-200-E-69 **Classification:** Accepted

Names: UPR-200-E-69; Railroad Car Flush Water **Reclassification:** None
Radioactive Spill; UN-200-E-69; UN-216-E-69

Type: Unplanned Release **Start Date:** 1/1/1984

Status: Inactive **End Date:**

Description: The railroad tunnel area has a 1.2 meter (4 foot) high fence along the side of the tracks. The area was posted with Radiologically Controlled Area signs. In 1998, the track from the tunnel door to Atlanta Ave. was covered with gravel and reposted as Underground Radioactive Material.

Location: The release effected the 221-B railroad cut, tunnel, and track.

Release Description: On 6-19-84, a concrete burial box (K-3 filter type) was removed from the 221-B railroad tunnel containing waste drums from 225-B and 221-B canyon waste. After loading, the burial string was bumped by the locomotive several times to remove the flush water from the lid of the burial box. No water was seen on the lid of the box or the deck of the flat car when the car left the tunnel. When the train stopped with the burial box about 180 meters (600 feet) from the tunnel door, contamination was noted on and near the west rail of the track. Contamination levels were 20,000 counts per minute with 4000 counts per minute smearable on the track. The water was not noted before the box was moved because high dose rates coming from the burial box (400 millirem/hour at a distance of 100 feet) prevented personnel from getting close enough to identify any liquid. After the contamination was identified, the train could not move back into the tunnel without contaminating the locomotive.

Waste Type: Water

Waste Description: Water dripped from a burial box containing waste was from 225-B and the 221-B canyon. The contamination consists of beta/gamma contamination, with readings to 4,000 to 20,000 counts per minute.

Code: UPR-200-E-88 **Classification:** Accepted

Names: UPR-200-E-88; TC-4 Spur Contaminated **Reclassification:** None
Railroad Track; UN-200-E-88. Ground
Contamination Around the Western Purex
Railroad Spur; UN-216-E-16; UN-216-E-88

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The unfenced portion of the spur was posted as a "Contamination Area." Additional posting on portions of the spur included "Soil Contamination Area" and "Buffer Area." The spur is tracked with the property number "F187418". The site was interim stabilized in December 1998. The stabilized area was posted as an Underground Radioactive Material area. A chain link fenced storage area is located on the north end of the spur (see site code 200-E-43).

Location: The site is located northwest of the 202-A Building at the TC-4 Railroad Spur.

Release Description: In 1981, Harold Maxfield stated that the large radiation zone associated with the TC-4 railroad spur has been incorrectly designated as an unplanned release site. The original perimeter of the zone was posted where the gamma dose rates from radioactive tank cars parked on the railroad

spur would be less than 1 millirads/hour. The site in question was properly known as a Regulated Equipment Storage Area (see 200-E-43). On December 17, 2010, approximately 576,000 gallons of potable water discharged to the ground during a construction water line tie in activity. The water flowed south, from the line break and flooded a portion of the TC-4 Spur Railcar Storage Area and the UPR-200-E-88 stabilized railroad track. Although no railcars are being stored here, the area is still fenced and radiologically posted.

Related Sites/ Structures: The site is associated with 200-E-43.

Waste Type: Process Effluent

Waste Description: The contamination spread consisted of radioactive particulates from contaminated railcars using the tracks. Surface radiological surveys performed in 1991 identified contamination of 20,000 to 60,000 disintegrations per minute on the railroad track near where the tank cars were being staged. South of the tank cars, along the railway, contaminated areas of 2,000 to 20,000 disintegrations/minute were also identified.

Code: UPR-200-E-89 **Classification:** Accepted

Names: UPR-200-E-89; Contamination Migration to the North, East & West of BX-BY Tank Farms; UN-200-E-89; UN-216-E-17 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1978

Status: Inactive **End Date:**

Description: The site is located north of the 241-BY Tank Farm. In 1991, the contaminated soil was consolidated on top of the 216-B-43 through 216-B-50 Cribs and stabilized with a layer of clean dirt. The site also includes an irregularly shaped drill pad area and a contaminated concrete pad that were also covered with clean dirt. All of the stabilized areas of UPR-200-E-89 were zoned off against casual entry and marked with "Underground Radioactive Material" signs.

Location: UPR-200-E-89 was originally identified in 1978 as an area of surface contamination east of the 241-BX Tank Farm. Wind blown contamination from tank farm operations spread the contamination to the north and northwest of the 241-BY Tank Farm. It eventually grew to be approximately 1.2 hectares (3 acres) in size.

Release Description: Airborne particulate matter contaminated the area bounding the north and northeast sides of the 241-BY Tank Farm. The airborne particulate matter was resuspended by wind from activities during the time of 241-BY Tank Farm operations. Airborne particulate matter from the 241-BX Tank Farm spread onto Baltimore Avenue roadway. Ground contamination was discovered at the 241-BX Tank Farm. The contamination was probably due to tank leakage.

Related Sites/ Structures: UPR-200-E-89 is associated with the 241-BX Tank Farm and the 241-BY Tank Farm.

Waste Type: Process Effluent

Waste Description: Airborne particulate matter contaminated an area near the 241-BY Tank Farm. The matter was resuspended by wind. Beta and gamma contamination with readings of 500 to 2,000 counts per minute were detected at the site.

Code: UPR-200-E-95 **Classification:** Accepted

Names: UPR-200-E-95; Ground Contamination Around **Reclassification:** None

RR Spur Between 218-E-2A and 218-E-2; UN-200-E-95; UN-216-E-23

Type: Unplanned Release **Start Date:** 1/1/1980

Status: Inactive **End Date:**

Description: The site is a railroad spur located south of the 218-E-2 and 218-E-5 Burial Grounds and north of the 218-E-2A Burial Ground. It had been barricaded with steel chain and posted as a Contamination Area. In 1998, the track was covered with gravel and reposted as an Underground Radioactive Material area.

Location: UPR-200-E-95 occurred at the railroad spur north of the 221-B Facility, located between the 216-E-2A and 216-E-5 Burial Grounds.

Release Description: The railroad spur was used as an aboveground storage zone for low level contaminated equipment. Equipment from the B Plant and PUREX Plant operations were stored, for the most part, on the beds of railroad flat cars. UPR-200-E-95 is associated with this storage area. The contamination is possibly the result of the accumulation of many small releases over time.

Related Sites/Structures: UPR-200-E-95 is associated with the 218-E-2A and the 218-E-5 Burial Grounds and B-Plant operations.

Waste Type: Soil

Waste Description: The material stored on the rail cars contained unknown beta and gamma contamination with a maximum reading of 100,000 counts per minute. The contamination on the rail bed is the result of contaminated equipment being stored on the tracks over an extended amount of time.

Code: UPR-200-E-98 **Classification:** Accepted

Names: UPR-200-E-98; Ground Contamination East of C Plant (Hot Semi Works); UN-200-E-98; UN-216-E-26 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1955

Status: Inactive **End Date:** 1/1/1965

Description: The location of this site is currently within a large surface stabilized area known as 200-E-41. Much of the contamination was removed and placed into the 218-C-9 Burial Pit in 1992. The area has been surface stabilized with powerhouse ash. The covered area has "Underground Radioactive Material" warning signs posted.

Location: UPR-200-E-98 occurred on the east side of the Hot Semiworks Facility, near the base of the 291-C Stack and around the 216-C-2 Reverse Well. The 291-C Stack was demolished and currently lies in a burial trench adjacent to where it stood.

Release Description: Radioactive particulate matter from the "Hot Semiworks" operations (1955 to 1965) was inadvertently spread to the ground surface. It contaminated the ground near the base of the 291-C Stack and around the 216-C-2 Reverse Well.

Related Sites/Structures: UPR-200-E-98 was associated with the C Plant (Hot Semiworks) Facility, the 291-C Stack and the 216-C-2 Reverse Well. The surface stabilized area is now known as 200-E-41.

Waste Type: Soil

Waste Description: The release consisted of radioactive particulate matter from the Hot Semiworks operation that was deposited onto the ground surface east of the facility. The contamination was primarily strontium-90.

Code: UPR-200-E-101 **Classification:** Accepted

Names: UPR-200-E-101; Radioactive Spill Near 242-B Evaporator; UN-200-E-101; UN-216-E-101; UN-216-E-30 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1985

Status: Inactive **End Date:**

Description: The site, adjacent to the B Tank Farm perimeter fence, is currently a posted as an Underground Radioactive Material area.

Location: The site is located between the 242-B Evaporator and the 241-B Tank Farm fence.

Release Description: Surface contamination was identified between the 241-B Tank Farm fence and the 242-B Evaporator building. It was assigned the Unplanned Release Site Number UN-216-E-30 in August 1985. Windblown particulates from the tank farm or spills from the 242-B Evaporator may have been the cause of the contamination, but an exact cause for this area of contamination has not been determined. A routine radiological survey done in September 1986 found tumbleweeds growing at the site that were reading 1,000 counts per minute beta-gamma.

Related Sites/ Structures: The site is associated with 241-B Tank Farm and 200-E-120.

Waste Type: Soil

Waste Description: The release consisted of an unknown amount of radioactive particulates from the 241-B Tank Farm.

Code: UPR-200-E-112 **Classification:** Accepted

Names: UPR-200-E-112; Contaminated Railroad Track from B-Plant to the Burial Ground; UN-200-E-112 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1979

Status: Inactive **End Date:** 1/1/1979

Description: The contaminated section of track and the Atlantic Avenue crossing were cleaned by noon, February 12, 1979.

Location: UPR-200-E-112 occurred on the railroad track from the 221-B Building to the 200 East Area Burial Ground.

Release Description: During a canyon equipment burial transfer, some contaminated liquid spilled out of a cesium ion exchange column that was being loaded into a burial box atop a rail car. The liquid spilled onto the tracks inside the B Plant railroad tunnel and was carried outside by one wheels of the railroad car, contaminating the track from B Plant to the east boundary of the burial ground. Contamination levels ranged from 40,000 counts per minute to 80,000 counts per minute. Approximately 15 meters (50 feet) of track that crossed Atlanta Ave. was decontaminated immediately. Occurrence Report 79-24 also recommends an effort to continue to clean the contaminated track.

Related Sites/ Structures: UPR-200-E-112 was associated with the 221-B Building and the B Plant Aggregate Area Railroad Cut and Tunnel.

Waste Type: Process Effluent

Waste Description: The release consisted of a spill of liquid from a cesium ion exchange column with beta/gamma readings up to 80,000 counts per minute. The equipment was being transported to the burial ground on a railcar.

Code: UPR-200-E-143 **Classification:** Accepted

Names: UPR-200-E-143; Contamination Adjacent to 244-A Lift Station; UN-216-E-43 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1990

Status: Inactive **End Date:**

Description: Various radiological postings exist in this vicinity that are associated with the 244-A Lift Station and 241-C Tank Farm contamination migration. A WIDS sign has been placed at the approximate location of the release.

Location: Contamination was identified in a large area located south of the 244-A Lift Station and west of 216-A-40 Basin.

Release Description: In October 1990, radiologically contaminated rabbit feces, with a maximum dose of 900 millirem per hour, was found south of the 244-A Lift Station and west of the 216-A-40 Basin. An investigation was initiated to identify the contaminating source. The size and shape of the zone varied over the next few months as clean-up efforts continued and new contamination is identified.

Related Sites/Structures: This release is associated with the 244-A Lift Station, 200-E Powerhouse Ditch and UPR-200-E-100.

Waste Type: Animal Waste

Waste Description: Contaminated rabbit feces and soil contamination were found in the area. Laboratory analysis of the feces found cesium-137 to be the most prevalent contaminant.

Code: UPR-200-E-144 **Classification:** Accepted

Names: UPR-200-E-144; Soil Contamination North of 241-B; UN-216-E-44 **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The site is a large area posted as Underground Radioactive Material.

Location: The site is located north of the 241-B Tank Farm to 12th Street on the east side of Baltimore Ave, east of 241-BY Farm.

Waste Type: Soil

Waste Description: The site consisted of several acres of particulate surface contamination to the north and east of 241-B Tank Farm. The source is assumed to be activities in the 241-B and 241-BY Tank Farms.

200-IS-1

Code: 216-A-508 **Classification:** Accepted**Names:** 216-A-508; 216-A-8 Distribution Box; Control Structure for 216-A-8 Crib **Reclassification:** None**Type:** Control Structure **Start Date:** 1/1/1955**Status:** Inactive **End Date:** 1/1/1995**Description:** The structure is surrounded with radiological chain and posted with Contamination Area and Radiologically Controlled Area signs.**Location:** The site is located east of 200 East Area, outside the 200 East Area fence. It is located adjacent to the west end of the 216-A-8 Crib.**Related Sites/ Structures:** The control structure is associated with the 216-A-8 crib, the 200-E-164-PL pipeline, the 216-A-524 Control Structure and the 241-A Tank Farms.**Process Description:** The 216-A-508 Control Structure, located west of the 216-A-8 Crib, controlled whether the effluent flow was diverted to the 216-A-8 or the 216-A-24 Crib.

Code: 216-A-524 **Classification:** Accepted**Names:** 216-A-524; 216-A-524 Control Structure; 216-A-524 Weir; 216-A-24 Control Structure **Reclassification:** None**Type:** Control Structure **Start Date:** 1/1/1958**Status:** Inactive **End Date:** 1/1/1966**Description:** The 216-A-524 Weir is an underground liquid effluent control structure. The weir is a concrete structure with the interior being divided vertically into three chambers. The outside dimensions are 4.9 meters (16 feet) by 2.4 meters (8 feet) and is 3.4 meters (11 feet) deep. The unit is covered with two removable concrete cover slabs. The aboveground features have been removed.**Location:** The site is located on the west end of the 216-A-24 Crib.**Related Sites/ Structures:** The site is associated with the 216-A-24 crib, the 200-E-165-PL pipeline and the 216-A-508 Control Structure.**Process Description:** The weir controlled the effluent flow to the 216-A-24 crib.**Waste Type:** Process Effluent**Waste Description:** The unit is an underground liquid effluent control structure for the 216-A-24 Crib and contains radioactively contaminated piping and cement. The amounts of radionuclides present are not known. A document published in 1987 (K.H. Cramer) reported radiological readings of 500 counts per minute smearable contamination, 10,000 counts per minute direct beta/gamma on the surface structures.

Code: 241-B-154 **Classification:** Accepted**Names:** 241-B-154; 241-B-154 Diversion Box **Reclassification:** None**Type:** Diversion Box **Start Date:** 1/1/1945

Status: Inactive **End Date:** 1/1/1984

Description: The site is a diversion box that interconnects diversion boxes 241-B-151 and 241-B-152 with the 221-B Building. The unit is a rectangular, reinforced concrete structure. It was sprayed with gray, weatherizing foam. Later, a layer of shot-crete was placed over the diversion box, extending beyond the structure to include the surrounding ground surface.

Location: The unit is located east of 221-B, at the intersection of Baltimore Avenue and Seventh Street.

Related Sites/Structures: The diversion box is associated with B Plant, 241-B-302 Catch Tank, 200-E-116-PL, 200-E-199-PL, 200-E-213-PL 241-B-151, 241-B-152, UPR-200-E-45 and UPR-200-E-77.

Process Description: This diversion box transferred waste solutions generated during fuel processing and decontamination activities from B Plant via 241-B-151 and 241-B-152 to the tank farms.

Waste Type: Process Effluent

Waste Description: The diversion box transferred process waste from B Plant to the tank farms. It is estimated that the diversion box also may contain approximately 23 kilograms (50 pounds) of lead shielding inside this unit.

Waste Type: Chemicals

Waste Description: This unit transferred waste from processing and decontamination operations. Volumes of waste present in the system varied with production operations. Contamination in this unit is estimated to include high alpha, beta, and gamma activity levels.

Code: 241-B-302B **Classification:** Accepted

Names: 241-B-302B; 241-B-302-B Catch Tank; Drain Lines V201 and V127; V217; 241-B-302 **Reclassification:** None

Type: Catch Tank **Start Date:** 1/1/1945

Status: Inactive **End Date:** 5/16/1985

Description: This unit is an underground, horizontal carbon steel tank. The catch tank and the 241-B-154 Diversion Box are surrounded with post and chain. The surface of the area inside the chain has been covered with gravel and sprayed with gray weatherizing material. The site is marked with radiological and IMUST signs.

Location: This catch tank is located north of the 241-B-154 diversion box, adjacent to the corner of 7th Street and Baltimore Avenue.

Related Sites/Structures: This catch tank is associated with 241-B Tank Farm and 241-B-154 Diversion Box and UPR-200-E-77. The drain lines are V201 and V127.

Process Description: This catch tank provided secondary containment for the 241-B-154 Diversion Box. Catch tanks are used to collect spills and leaks that occur in diversion boxes during waste transfer operations. From 1945 to 1952, the diversion box and catch tank were involved in the bismuth phosphate process which generated metal waste, coating wastes, and first and second cycle decontamination wastes. From 1968 to 1978 the diversion box and catch tank were involved in the waste fractionation processes for recovering cesium and strontium with other fissionable materials. Cesium, fissionable materials, and rare earth processing continued until 1985.

Waste Type: Process Effluent

Waste Description: This unit collected leaking and excess waste solutions from processing and decontamination operations that passed through the 241-B-154 Diversion Box. Volumes were variable according to specific plant operation. In 1985, the volume of liquid inside the tank was estimated to be

16,027 liters (4240 gallons). Sludge content was estimated to be 2608 liters (690 gallons).
(Total 4930 gallons of sludge and liquid).

Code: 241-BX-154	Classification: Accepted
Names: 241-BX-154; 241-BX-154 Diversion Box	Reclassification: None
Type: Diversion Box	Start Date: 1/1/1948
Status: Inactive	End Date: 1/1/1985

Description: This diversion box is a reinforced concrete structure.

Location: This diversion box is located south of the 221-B Building and east of the 241-BX-302B Catch Tank.

Related Sites/ Structures: This diversion box is associated with the 241-BX-302-B Catch Tank, 200-E-198-PL and the 241-BX Tank Farm. This unit interconnects the 241-B-252 and 241-BX-155 diversion boxes and the 221-B Building.

Process Description: This diversion box is designed to contain leaks from transfers and drainage from operations within the unit. This unit acts as a secondary containment for transfer line jumper connections.

Waste Type: Process Effluent

Waste Description: This unit was used for transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operation. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Waste Type: Equipment

Waste Description: It was estimated that approximately 50 pounds (23 kilograms) of waste lead was stored in this unit.

Code: 241-BX-155	Classification: Accepted
Names: 241-BX-155; 241-BX-155 Diversion Box	Reclassification: None
Type: Diversion Box	Start Date: 1/1/1948
Status: Inactive	End Date: 1/1/1984

Description: This diversion box is a reinforced concrete structure. The diversion box has been isolated and covered with water proof foam sealant. The area around the diversion box has been surface stabilized with gravel and posted with Underground Radioactive Material signs, except for the surface area above the 241-B-302-C tank. This area does not have the additional layer of gravel and remains posted as a Contamination Area.

Location: This diversion box is located northeast of B Plant on the south side of Atlanta Avenue.

Related Sites/ Structures: This diversion box is associated with the 241-BX-302-C Catch Tank, 200-E-198-PL and the 241-BX Tank Farm.

Process Description: This diversion box transferred tank waste between B Plant and the 241-BX Tank Farm. The transfer system is designed to contain leaks from transfers and drainage from operations within the unit. This unit acts as secondary containment for transfer line jumper connections. The 241-B-302-C Catch Tank held the waste that leaked in this unit.

Waste Type: Equipment

Waste Description: It was estimated that approximately 50 pounds (23 kilograms) of waste lead was stored in this unit.

Waste Type: Process Effluent

Waste Description: This unit was used for transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operation. High levels of beta, gamma and alpha contamination are estimated to be inside this unit. Lead shielding material may also be present.

Code: 241-BX-302B **Classification:** Accepted

Names: 241-BX-302B; 241-BX-302-B Catch Tank; Line V288 **Reclassification:** None

Type: Catch Tank **Start Date:** 1/1/1948

Status: Inactive **End Date:** 1/1/1985

Description: The buried tank is covered with gravel. It is surrounded with post and chain. The tank is marked with radiological and IMUST signs.

Location: The 241-B-302B catch tank is located on the south side of the 221-B Building (near section 12), and northwest of 241-BX-154 Diversion Box.

Related Sites/ Structures: This catch tank is associated with 241-BX-154 Diversion Box and 241-BX Tank Farm. Line V288 is the drain line from the diversion box.

Process Description: The catch tank collected drainage and spills that occurred in diversion box during waste transfer operations.

Waste Type: Process Effluent

Waste Description: This unit collected drainage and spilled waste solutions that passed through the 241-BX-154 Diversion Box. Volumes were variable according to specific plant operation. Residual volume is estimated to be 3591 liters (950 gallons) of sludge and 355 liters (94 gallons) of supernate.

Code: 241-BX-302C **Classification:** Accepted

Names: 241-BX-302C; 241-BX-302-C Catch Tank; Lines V322 and V323 **Reclassification:** None

Type: Catch Tank **Start Date:** 1/1/1948

Status: Inactive **End Date:** 1/1/1985

Description: The catch tank is a direct buried carbon steel tank, positioned horizontally. It is located inside a recently graveled Underground Radioactive Material area, related to the 241-BX-155 Diversion Box surface stabilization. The tank was not covered with extra gravel and is separately posted as a Contamination Area. The tank is marked with radiological and IMUST signs. Pipelines V322 and V323 go to and from the 241-BX-155 diversion box.

Location: The 241-BX-302C catch tank is located southeast of 241-BX -155 Diversion Box, between Atlanta Avenue and Baltimore Avenue.

Related Sites/ Structures: This catch tank is associated with the 241-BX-155 Diversion Box, UPR-200-E-78 and 241-BX Tank Farm. Line V322 is the drain line from the diversion box to the catch tank. Line V323 is the return line from the catch tank to the diversion box.

Process Description: The 241-BX-302C catch tank collected drainage and spills that occurred during waste transfer operations at the 241-BX-155 diversion box.

Waste Type: Process Effluent

Waste Description: This unit collected processing and decontamination drainage from the 241-BX-155 Diversion Box. Volumes were variable according to specific plant operation. In 1984, the tank was estimated to contain 2400 liters (635 gallons) of sludge and 862 liters (228 gallons) of supernate. The tank was declared stabilized and isolated April 12, 1985, as part of Project B-231. When stabilized the tank contained 16 inches of waste and 13 inches of sludge. The solids volume is calculated to be approximately 619 gal of sludge and 224 gal of liquid.

Code: 241-C-154 **Classification:** Accepted

Names: 241-C-154; 241-C-154 Diversion Box **Reclassification:** None

Type: Diversion Box **Start Date:** 1/1/1946

Status: Inactive **End Date:** 1/1/1985

Description: The diversion box has been covered with clean backfill material (ash) and is no longer visible. It is located within the larger Hot Semiworks surface stabilized area (200-E-41). The diversion box is posted with Underground Radioactive Material Area signs.

Location: The diversion box is located south of 7th Street, southeast of the (demolished) 201-C building and northeast of the 216-C-1 crib. It is located within the larger Hot Semiworks surface stabilized area (200-E-41).

Related Sites/Structures: The diversion box is associated with the 201-C C-Cell, 200-E-226-PL (B-Plant Promethium Transfer Line) and 200-E-41 stabilized area.

Process Description: This unit was used for transfer of radioactive solutions from (promethium) B Plant operations.

Waste Type: Equipment

Waste Description: The diversion boxes are estimated to contain approximately 50 pounds (23 kilograms) of waste lead.

Waste Type: Process Effluent

Waste Description: This unit was used to transfer radioactive waste solutions (promethium) from B Plant operations. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Code: 241-CX-70 **Classification:** Accepted

Names: 241-CX-70; 241-CX-TK-70 Tank; Strontium Hot Semi-Works **Reclassification:** None

Type: Storage Tank **Start Date:** 1/1/1952

Status: Inactive **End Date:** 1/1/1957

Description: The 241-CX-70 underground tank is surrounded with post and chain. It is posted with Hazardous Waste, Restricted Area-Inactive Tank signs.

Location: The tank is located south of 7th Street, within the Hot Semiworks stabilized area (200-E-41).

Related Sites/ Structures:	Associated structures include 201-C, 276-C, 2704-C, 241-CX-71, and 241-CX-72. The pipeline to 241-CX-70 is sitecode 200-E-244-PL. It is inside the 200-E-41 stabilized area.
Process Description:	The unit stored Semiworks Process waste. The 241-CX-70 Tank is constructed of concrete with a 2.5-centimeter (1-inch) thick stainless steel plate liner. The sides and top are 0.3 meters (1 foot) thick concrete and the bottom thickness varies from 0.6 meters (2 feet) at the edges to 23 centimeters (9 inches) at the center. The tank is located below grade, with several risers and vents visible above grade.
Waste Type:	Process Effluent
Waste Description:	The unit was used to store high-level process waste in support of the Semiworks process. Prior to sluicing, the unit contained approximately 1.45 meters (4.75 feet) of sludge, that is roughly equivalent to 39,000 liters (10,300 gallons) of waste. Contaminants included 20 curies of plutonium-239/240; 500 curies of cesium-137; 2,900 curies of strontium-90; 7,080 kilograms (7.8 tons) sodium nitrate; 1,000 kilograms (1.1 tons) sodium nitrite; 1,090 kilograms (1.2 tons) sodium fluoride; 450 kilograms (0.5 tons) aluminum sulfate; and 180 kilograms (0.2 tons) sodium chromate. After sluicing only a small quantity of solids and residual caustic/water remain. The estimated contamination levels for piping and equipment are 3 curies plutonium and 6,000 curies beta/gamma. The residual volume remaining after the tank was sluiced was estimated to be (500 gallons) of liquid and (250 gallons) of solids. Later more liquids and gravel-like solids were removed. The tank was dried and is considered to be empty.

Code: 241-CX-71 **Classification:** Accepted

Names: 241-CX-71; 241-CX-TK-71; Strontium Hot Semi-Works; 241-CX Neutralization Tank **Reclassification** None

Type: Neutralization Tank **Start Date:** 1/1/1952

Status: Inactive **End Date:** 1/1/1957

Description: The underground tank is surrounded with steel posts and chain. It is posted with Hazardous Waste, Restricted Area-Inactive Tank signs.

Location: The tank is located south of 7th Street, within the Hot Semiworks stabilized area (200-E-41). It is near the northeast corner of the 216-C-1 Crib.

**Related Sites/
Structures:** Associated structures include: 201-C, 276-C, 2704-C, 216-C-1, 216-C-5, 241-CX-70, and 241-CX-72. The pipeline to 241-CX-71 is sitecode 200-E-245-PL. It is inside the 200-E-41 stabilized area.

**Process
Description:** This tank provided acidic waste neutralization via a flow-through limestone layer for 201-C process condensate and the coil and condensate cooling water stream prior to discharge to the 216-C-1 and 216-C-5 cribs. It may have also received process condensates from REDOX and PUREX pilot plant operations, decontamination flushes, and hot shop sink waste. Replacement limestone was added as needed through a large central riser pipe. This tank is constructed of stainless steel and lies below grade, on a reinforced concrete foundation pad.

Waste Type: Process Effluent

**Waste
Description:** The tank was used for neutralizing the 201-C process condensate and the coil and condenser cooling water via a limestone layer. It also received process condensates from the Reduction Oxidation (REDOX) and Plutonium Uranium Extraction (PUREX) pilot plant processes, which would include hexone and kerosene solvents. From November 1956 to June 1957, the unit received flush wastes during decontamination. This tank currently contains a bottom layer of sludge and the limestone layer. The remainder of the tank was filled with grout in 1986. In October 1990, a drill was used to collect samples from the bottom of the tank, through the grout. Low concentrations of methyl ethyl ketone, xylene and toluene were measured (7-54

parts per billion). Twenty one parts per million of cyanide was found.

Code:	241-CX-72	Classification:	Accepted
Names:	241-CX-72; 241-CX-72 Waste Self Concentrator; 241-CX-TK-72 Vault and Tank; Strontium Hot Semi-Works	Reclassification	None
Type:	Storage Tank	Start Date:	1/1/1957
Status:	Inactive	End Date:	1/1/1958
Description:	The 241-CX-72 tank is located inside a small building. A cover has been placed over the tank with radiological postings and Keep Out signs.		
Location:	The tank is located south of 7th Street, within the Hot Semiworks stabilized area (200-E-41).		
Release Description:	In 1988, during construction of the 291-C stack demolition berm, a portion of an agitator rod was accidentally snagged by heavy equipment. A piece of rod approximately 4.5 meters (15 feet) long was pulled out of the tank. Since the rod was found to be radiologically contaminated, an investigation was begun to assess the situation. The tank had previously been reported to be empty of waste. Failure to identify waste during the 1978 inspection was assumed to be from inadvertently inspecting the drywell adjacent to the tank, which remains free of waste by design. Since the rod had a significant amount of contamination on it, core sampling through the grout layer was planned. An eleven foot layer of fission product and TRU residue was found to be on the bottom of the tank.		
Related Sites/ Structures:	Associated structures include: 201-C, 276-C, 2704-C, 241-CX-70, and 241-CX-71. The pipeline to 241-CX-72 is sitecode 200-E-246-PL. It is inside the 200-E-41 stabilized area.		
Process Description:	The 241-CX-72 Tank was an experimental tank used to study the characteristics of self-concentrating waste from the Plutonium Uranium Extraction (PUREX) process. The 241-CX-72 Tank is vertically oriented with welded steel construction. The tank rests on a concrete pad inside a steel caisson with the tank top below grade. A cylindrical heater is located just above each stiffening ring. A number of penetrations extend through the tank top, including an agitator. This tank was used for approximately one year, during 1957 through 1958. The 241-CX Vault is located below grade adjacent to the 241-CX-72 tank. The vault is constructed of reinforced concrete, divided into two sections. In 1961, the inlet piping was cut and capped.		
Waste Type:	Process Effluent		
Waste Description:	The tank was filled with grout in 1986. Original content information was based on process knowledge. Some solid salt cake, similar to that found in tank farm tanks containing PUREX waste, is believed to remain inside the tank as well as the grout. Smears taken from an agitator rod (accidentally pulled out of the tank by heavy equipment) found a maximum of 8000 disintegrations per minute alpha and 5800 picocuries of gamma. Core samples were obtained from the tank in 1989. An 3.3 meter (eleven foot) layer of fission products and TRU isotopes was found in the bottom of the tank. Estimated radionuclides present include approximately 200 grams of plutonium-239 (as a fluoride compound).		

Code:	200-E-114-PL	Classification:	Accepted
Names:	200-E-114-PL; 216-BC-2805; 2805-E1, 2805-E2, 2805-E3 and 2805-E4; Pipeline from 216-BY- 201 to 216-BC-201; Pipeline from 241-BY Tank Farm to 241-C Tank Farm and BC Cribs and Trenches	Reclassification	None

Type: Radioactive Process Sewer **Start Date:** 1/1/1952
Status: Inactive **End Date:** 1/1/1954

Description: The two parallel underground pipelines are marked with metal posts and Underground Radioactive Material - Pipeline signs. (see subsites) Several areas above the pipeline have been surface stabilized due to growing contaminated vegetation. These areas are also posted as Underground Radioactive Material Areas.

Location: The pipeline begins north of the 241-BY Tank Farm at the 216-BY-201 Flush Tank. It extends eastward to a point between the 216-B-8 Crib and the 216-B-51 French Drain. The pipeline turns southward and connects to a valve pit (see sitecode 200-E-223). A portion of the line diverts from the valve pit to the 241-C Tank Farm. Another portion of pipeline continues south and connects to the 216-BC-201 Siphon Tank in the BC Cribs and Trenches area. The BC Cribs and Trenches are located south of 200 East Area, south of Route 4 South.

Release Description: The Dyncorp Integrated Soil, Vegetation and Animal control group submitted two posted Contamination Areas located on this pipeline to WIDS as a Discovery Sites. In February 2000, they found growing contaminated vegetation on the underground pipeline northeast of 241-B Tank Farm, approximately 27 meters (90 feet) southeast of the 216-B-51 French Drain. The maximum contamination levels identified was 2000 counts per minute beta/gamma. Although some of the contaminated vegetation was removed, the area remains posted as a Contamination Area. A second area with growing contaminated vegetation was identified in October 2000. This area is located north of the 241-B Tank Farm, between the 216-B-8 Tile Field and the 216-B-51 French Drain.

Related Sites/ Structures: The pipeline is associated with the 241-BY Tank Farm, 241-C Tank Farm, the BC Cribs and Trenches, 200-E-221-PL (to 216-B-51) and the 200-E-223 valve pit.

Process Description: The pipeline is constructed of two parallel, 10 centimeter (4 inch) diameter carbon steel pipes buried in the same soil trench. Encasements were constructed at areas where the pipeline crosses under roadways. During the Uranium Recovery project from 1952 through 1954, this pipeline was used to transfer waste from the 241-BY Tank Farm to the BC Cribs and Trenches area. The waste first cascaded through several tanks in the 241-BY Tank Farm to allow some contamination to settle inside the tank farm before being discharged to the cribs and trenches via the underground pipeline. The entire scavenging mission necessitated the construction of the transfer system using pipelines 2805-E1, 2805-E2, 2805-E3 and 2805-E4 (Sitecode 200-E-114-PL). The entire system can be traced on the series of H-2-2900 thru 2909. The valve box (Sitecode 200-E-223) allowed waste to move north to BY or south to BC cribs.

Waste Type: Soil

Waste Description: The waste is the pipeline and adjacent soil contaminated from pipeline leaks. The pipeline carried scavenged uranium recovery process waste (tri-butyl phosphate solvent extraction).

This Site has the Following SubSites:

Code: 200-E-114-PL:1

Names: 200-E-114-PL:1; North/South Pipeline

Code: 200-E-114-PL:2

Names: 200-E-114-PL:2; East/West Pipeline

Code: 200-E-114-PL:3

Names: 200-E-114-PL:3; Underground Steel Line from Gate Valve (North of 216-BC-201 Siphon Tank) to 216-B-20 Trench

Code: 200-E-114-PL:1 **Classification:** Accepted

Names: 200-E-114-PL:1; North/South Pipeline **Reclassification** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: Subsite 1 is the north-south portion of the pipeline that runs from 216-BY-201 Flush Tank to 216-BC-201 Flush Tank. It runs through the 200-E-223 Valve Pit. The pipeline is constructed of two parallel, 10 centimeter (4 inch) diameter pipes buried in the same soil trench. The two parallel underground pipelines are marked with metal posts and Underground Radioactive Material - Pipeline signs. (see subsites) Several areas above the pipeline have been surface stabilized due to growing contaminated vegetation. These areas are also posted as Underground Radioactive Material Areas.

Location: The north/south pipeline begins east of the 241-BY tank farm and extends south, east of Baltimore Ave. It exits the 200 East Area fence and continues under Route 4 South and connects to the 216-BC-201 flush tank.

Process Description: The entire scavenging mission necessitated the construction of the transfer system using pipelines 2805-E1, 2805-E2, 2805-E3 and 2805-E4. The entire system can be traced on the series of H-2-2900 thru 2909. The valve box allowed waste to move north to BY or south to BC cribs.

The SubSite is Part Of:

Code: 200-E-114-PL

Names: 200-E-114-PL; 216-BC-2805; 2805-E1, 2805-E2, 2805-E3 and 2805-E4; Pipeline from 216-BY-201 to 216-BC-201; Pipeline from 241-BY Tank Farm to 241-C Tank Farm and BC Cribs and Trenches

Code: 200-E-114-PL:2 **Classification:** Accepted

Names: 200-E-114-PL:2; East/West Pipeline **Reclassification** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: Subsite 2 is the east-west portion of the pipeline that extends from the 200-E-223 Valve Pit to the 241-C Tank Farm. The pipeline is constructed of two parallel, 10 centimeter (4 inch) diameter pipes buried in the same soil trench.

Location: This segment is located inside 200 East Area, north of 7th Street. It extends from the 200-E-223 Valve Pit to the 241-C Tank Farm.

Process Description: The entire scavenging mission necessitated the construction of the transfer system using pipelines 2805-E1, 2805-E2, 2805-E3 and 2805-E4 (Sitecode 200-E-114-PL). The entire system can be traced on the series of H-2-2900 thru 2909. The valve box allowed waste to move north to BY or south to BC cribs.

The SubSite is Part Of:

Code: 200-E-114-PL

Names: 200-E-114-PL; 216-BC-2805; 2805-E1, 2805-E2, 2805-E3 and 2805-E4; Pipeline from 216-BY-201 to 216-BC-201; Pipeline from 241-BY Tank Farm to 241-C Tank Farm and BC Cribs and Trenches

Code: 200-E-114-PL:3 **Classification:** Accepted

Names: 200-E-114-PL:3; Underground Steel Line from Gate Valve (North of 216-BC-201 Siphon Tank) **Reclassification** None

to 216-B-20 Trench

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: Four inch diameter underground steel line from gate valve (north of 216-BC-201 siphon tank) to 216-B-20 trench. A Notice of Radiological Problem was issued in January 2007. Wind had uncovered a portion of this old radioactive underground line. The maximum dose rate on the line was 60 mr/hr at contact. No removable contamination was identified.

Location: The BC Cribs and Trenches are located south of 200 East Area, south of Route 4 South. The pipeline is located east of the BC cribs.

Process Description: The pipeline subsite begins as an underground line connecting to the 216-BC-201 flush tank. It emerged as an aboveground line west of the encasement (H-2-3203) that diverted waste to the BC trenches.

The SubSite is Part Of:

Code: 200-E-114-PL

Names: 200-E-114-PL; 216-BC-2805; 2805-E1, 2805-E2, 2805-E3 and 2805-E4; Pipeline from 216-BY-201 to 216-BC-201; Pipeline from 241-BY Tank Farm to 241-C Tank Farm and BC Cribs and Trenches

Code: 241-ER-151

Classification: Accepted

Names: 241-ER-151; 241-ER-151 Diversion Box

Reclassification: None

Type: Diversion Box

Start Date: 1/1/1945

Status: Inactive

End Date:

Description: The diversion box is located inside a locked chain link fence. The fence is posted with "Caution - contact Radiological Control and Tank Farm Shift Office prior to entry" signs. The diversion box is surrounded with a metal safety barricade.

Location: The site is located southwest of the B Plant and near the corner of 7th Street and Atlanta Avenue.

Related Sites/Structures: This site is associated with the 241-ER-311 Catch Tank, the Cross Site Transfer Line, 241-EW-151 Vent Station, the 241-BX Double Contained Receiver Tank, and the 241-ER-152, the 241-ER-153, and the 241-UX-154 Diversion Boxes and the 241-ER-311 Catch Tank. It is also associated with pipelines 200-E-111-PL, 200-E-145-PL, 200-E-215-PL, 200-E-217-PL.

Process Description: The 241-ER-151 diversion box distributed waste between locations inside 200 East Area or the waste could be transferred to 200 West Area, via the cross site transfer line. This unit received 200 West Area waste via the 241-UX-154 Diversion Box via transfer lines V360, V361, V362, V363, V364 and V366 and the 241-EW-151 Vent Station. The diversion box also received 200 East Area tank waste from the 241- B, BX, and BY Tank Farms via 244-BX Double Contained Receiver Tank. Drainage from the 241-ER-151 went to the 241-ER-311 Catch tank.

Waste Type: Process Effluent

Waste Description: The diversion distributes chemical process waste between facilities and tank farms. Quantities of waste vary according to specific plant operations. This diversion box facilitates the transfer of waste solutions between the 200 East Area to the 200 West Areas via the Cross Site Transfer Line. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Code: 241-ER-152	Classification: Accepted
Names: 241-ER-152; 241-ER-152 Diversion Box	Reclassification: None
Type: Diversion Box	Start Date: 1/1/1974
Status: Inactive	End Date:

Description: Most of the reinforced concrete diversion box structure is underground. The floor and lower portions of the walls are lined with stainless steel. Cover blocks with lifting hooks are visible from the surface. The 241-ER-152 Diversion Box is surrounded with radiation rope and Contamination Area signs.

Location: This 241-ER-152 Diversion Box is southeast of the 224-B Building, and east of 241-ER-151 Diversion Box, near the corner of Atlanta Ave. and 7th Street.

Release Description: In 1996, intrusion from mice and harvester ants caused a contamination spread over an area measuring approximately 0.5 hectares (1.2 acres) southeast of the diversion box. The contaminated area was surface stabilized with clean gravel and down posted from a Contamination Area/ Soil Contamination Area to an Underground Radioactive Material Area (URM) (see WIDS sitecode 200-E-29).

Related Sites/ Structures: The 241-ER-152 Diversion Box is associated with the 241-ER-151 and 241-ER-153 diversion boxes, the 241-ER-311 Catch Tank and transfer lines (sitecodes 200-E-145-PL and 200-E-215-PL). It is also associated with the stabilized Contamination Area know as 200-E-29. The sump drain line for this diversion box is DR311 (see sitecode 200-E-305-PL). The drain line extends to the 241-ER-311 catch tank, located adjacent to the 241-ER-151 diversion box.

Process Description: Diversion boxes contain jumper piping that routed waste from one transfer line to another. Waste leaks that occur during high-level waste transfers are contained in catch tanks. The diversion boxes generally drain by gravity to nearby catch tanks where any spilled waste is stored.

Waste Type: Process Effluent

Waste Description: The diversion box distributes radioactive waste solutions from between facilities and tank farms. Quantities are variable according to specific plant operations. This diversion box facilitates the transfer of low-level waste for the B Plant to the Double-Shell Tank Farms.

Code: 241-ER-311	Classification: Accepted
Names: 241-ER-311; 241-ER-311 Catch Tank; 241-ER-311A Replacement Tank	Reclassification: None
Type: Catch Tank	Start Date: 1/1/1954
Status: Inactive	End Date: 6/1/2005

Description: The 241-ER-311 underground catch tank is located inside the 241-ER-151 locked, chain link fence. The fence is posted as a Contamination Area and Underground Radioactive Material Area, and is labeled with IMUST signs. The placement of these structures within the fence is the 241-ER-311 Catch Tank is the furthest south, nearest the chain link fence. The 241-ER-311A Catch Tank (original catch tank) is located adjacent to the north side of the 241-ER-311 tank (between the diversion box and the replacement catch tank). The 241-ER-151 Diversion Box is north of the 241-ER-311A Catch Tank.

Location: The catch tank is located south of the B Plant and west of Atlanta Avenue, inside the 241-ER-151 diversion box fence. The centers of two catch tanks (241-ER-311 and 241-ER-311A) are located approximately 17 feet apart (per center coordinates).

Release Description:	A leak was suspected beginning in October 2005. Samples were collected through the test risers. The samples identified Sodium, Nitrate, Nitrite, Fluorine, Chlorine, Sulfate, Phosphate, Strontium-90, and Cesium-137. In 2006 the volume of liquid in the tank was estimated to be 424 gallons, at a rate of roughly 0.4 gallons per day.
Related Sites/ Structures:	The 241-ER-311 catch tank is associated with the 241-ER-311A Catch Tank, 241-ER-151, 241-ER-152, automatic liquid level sensors, leak detection, and a submersible pump. Pipelines associated with these structures are discussed in sitecodes 200-E-228-PL and 200-E-305-PL (drain line).
Process Description:	The 241-ER-311 catch tank replaced the 241-ER-311A Catch Tank. The catch tank collected spills and leaks that occurred in the 241-ER-151, the 241-ER-152, diversion boxes during waste transfer operations. The drain line from 241-ER-152 is line DR-311 (see sitecode 200-E-305-PL). After 1980, the primary liquids received were rain and snow melt, line flushes and some leakage from transfers through the 241-ER-151 diversion box.
Waste Type:	Process Effluent
Waste Description:	The catch tank collected drainage and leaks from the 241-ER-151, 241-ER-152 and 241-ER-153 diversion boxes. Volumes were variable according to specific plant operation, when the tank was active. Decreasing tank volumes were noted in 2005. A tank leak investigation was done in late 2005 and early 2006. The tank is assumed to be leaking.
	The 241-ER-311 Catch Tank received overflow process wastes from the 241-ER-151 and 241-ER-152 Diversion Boxes. These diversion boxes facilitated the transfer of PUREX Acid Sludge [PAS] and PUREX Supernate [PSN]) to B-Plant from 1964-1972 via 241-ER-151 and 241-ER-152. Tri-Butyl Phosphate waste from U-plant passed through 241-ER-151 from 1952-1958. MW1/MW2 Metals Waste and 1C1/1C2 first cycle wastes from B-Plant passed through 241-ER-151 from 1944 to 1956, via pipeline 200-E-217-PL.

Code:	241-ER-311A	Classification:	Accepted
Names:	241-ER-311A; 241-ER-311A Catch Tank; Old 241-ER-311; Original 241-ER-311 Catch Tank	Reclassification	None
Type:	Catch Tank	Start Date:	1/1/1950
Status:	Inactive	End Date:	1/1/1954

Description: 241-ER-311A is an underground tank. It is located within a chain link fence that is posted as a Contamination Area and Underground Radioactive Material Area, and is labeled with IMUST signs. The 241-ER-151 Diversion Box, the 241-ER-311 Catch Tank and the 241-ER-311A Catch Tank are all located inside this chain link fence. The placement of these structures within the fence is the 241-ER-311 Catch Tank is the furthest south, nearest the chain link fence. The 241-ER-311A Catch Tank is located adjacent to the north side of the 241-ER-311 tank (in the middle of the three structures). The 241-ER-151 Diversion Box is north of the 241-ER-311A Catch Tank.

Location: The tank is located southwest of the B Plant. It is south of 7th Street and west of Atlanta Avenue.

Release Description: In 1953, 6,500 liters (1700 gallons) of liquid containing 10 curies of fission product leaked from this tank (see UPR-200-E-84).

Related Sites/ Structures: The tank is associated with the 241-ER-151 Diversion Box and UPR-200-E-84.

Process Description: The catch tank received drainage and leaks from the 241-ER-151 diversion box. The tank is a horizontal, carbon steel underground tank.

Waste Type: Process Effluent

Waste Description: The tank received waste from the 241-ER-151 Diversion Box that was caused from leaks and decontamination activities. The tank was abandoned in place in 1954. Although no records have been found identifying its contents or to verify the tank was pumped, it is unlikely any significant amount of waste remains in the tank.

Code: 216-S-172 **Classification:** Accepted

Names: 216-S-172; 216-S-172 Control Structure; 216-S-172 Weir Box and Control Structure; 2904-S-172 Weir **Reclassification:** None

Type: Control Structure **Start Date:** 1/1/1956

Status: Inactive **End Date:** 1/1/1976

Description: This site is an underground concrete structure with interior hand operated sluice gates. Float wells were attached to the outside north and south walls. The structure has been covered with soil and posted with Underground Radioactive Material/Cave-In Potential signs.

Location: The unit is located outside the southwest corner of the 200 West Area perimeter fence and north of 216-S-5 Crib.

Related Sites/ Structures: The site is associated with the 202-S Building, 200-W-153-PL pipeline, and the 216-S-16 Ditch.

Process Description: The control structure was used to divert 202-S process vessel cooling water to 216-S-6 and steam condensate to the 216-S-16 Ditch.

Waste Type: Process Effluent

Waste Description: The unit contains unquantified amounts of low-level radioactive solid waste. In 1987, the Hanford Site Waste Management Units Report stated the maximum radiation reading on the structure was 25 millirads per hour.

Code: 240-S-151 **Classification:** Accepted

Names: 240-S-151; 240-S-151 Diversion Box **Reclassification:** None

Type: Diversion Box **Start Date:** 1/1/1950

Status: Inactive **End Date:** 1/1/1987

Description: This unit is constructed of reinforced concrete and is rectangular in shape. The 240-S-151 Diversion Box has been weather covered.

Location: The 240-S-151 Diversion Box is located north of the 202-S Canyon Building, west of the 240-S-302 catch tank.

Related Sites/ Structures: 200-W-153-PL, 200-W-187-PL, 200-W-190-PL, 200-W-212-PL, the 240-S-302 Catch Tank, UPR-200-W-82 and 241-S Tank Farm are associated with the 240-S-151 Diversion Box.

Process Description: This unit was used for the transfer of REDOX waste solutions from processing and product decontamination operations to the tank farms.

Waste Type: Process Effluent

Waste Description: This unit was used for transfer of waste solutions from processing and product decontamination operations to the tank farms. Volumes were variable according to specific plant operations.

Waste Type: Equipment

Waste Description: Equipment associated with the diversion box includes transfer piping and nozzles. Waste lead is also stored in the diversion box.

Code: 240-S-152 **Classification:** Accepted

Names: 240-S-152; 240-S-152 Diversion Box **Reclassification:** None

Type: Diversion Box **Start Date:** 1/1/1977

Status: Inactive **End Date:** 1/1/1980

Description: This unit is constructed of reinforced concrete and is rectangular in shape. The 240-S-152 Diversion Box has been weather covered.

Location: The 240-S-152 Diversion Box is located north of the 202-S Canyon Building and north of 240-S-151 Diversion Box.

Related Sites/Structures: 200-W-186-PL, 200-W-187-PL, 240-S-302 Catch Tank and 241-S Tank Farm are associated with the 240-S-152 Diversion Box.

Process Description: This unit was used for the transfer of waste solutions from 204-S to the 240-S-151 Diversion Box.

Waste Type: Process Effluent

Waste Description: This unit was used for transfer of waste solutions from 204-S to the 240-S-152 Diversion Box.

Waste Type: Equipment

Waste Description: Equipment associated with the diversion box includes transfer piping and nozzles. Waste lead is also stored in the diversion box.

Code: 240-S-302 **Classification:** Accepted

Names: 240-S-302; 240-S-302 Catch Tank; Line V556 and V557 **Reclassification:** None

Type: Catch Tank **Start Date:** 1/1/1950

Status: Inactive **End Date:** 1/1/1987

Description: This unit is a horizontal, cylindrical, steel tank. The 240-S-302 Catch Tank is buried underground to provide shielding from radiation. The tank is surrounded with posts and chain and posted with radiological and IMUST signs.

Location: This unit is located north of the 202-S Building and east of the 240-S-151 Diversion Box.

Related Sites/Structures: The 240-S-302 Catch Tank is associated with the 240-S-151 Diversion Box. The drain lines to this catch tank are V556 and V557.

Process Description: The tank received leakage, spillage, line flushes, and drainage associated with waste transfers through Diversion Box 240-S-151.

Waste Type: Storage Tank

Waste Description: This unit received low-level, dilute laboratory waste and drainage from the 240-S-151 Diversion Box. In 1993, the tank was estimated to contain 8603 liters (2276 gallons) of sludge and liquid. Approximately 378 liters (100 gallons) is suspected to be liquid. In 1997, approximately 4900 gallons of rain and snow melt from the 240-S-151 diversion box overflowed into the catch tank. In 2008, approximately 2665 gallons of liquid was removed from the tank leaving approximately 6 gallons of free liquids and 1600 gallons of solid material (per letter CH2M-0802230).

Code: 276-S-141 **Classification:** Accepted

Names: 276-S-141; 276-S-141 Solvent Storage Tank; 276-S-306A; 276-S-TK-141; Hexone Storage Tank; Tank 276-141; 244-SX-15 **Reclassification:** None

Type: Storage Tank **Start Date:** 1/1/1951

Status: Inactive **End Date:** 1/1/1969

Description: The site is a below grade carbon steel tank enclosed in a chain line fenced area. The tank is the southernmost tank in a two tank network connected to the 276-S Solvent Handling Facility. The tank had an 89,000 liter (23,575 gallon) capacity. The tank has been filled with cement.

Location: The underground tank is north of 276-S Building and directly south of the 276-S-142 Tank. The tank is west of the REDOX railroad tracks.

Related Sites/Structures: Structures associated with the tank include: solvent transfer lines, the 276-S-142 Tank, the Tank Car Unloading Station, and process equipment in the 276-S Building. The pipelines associated with the hexone tanks are sitecode 200-W-230-PL.

Process Description: The tank is currently being closed under interim status, containing small amounts of liquid mixed waste. The tank stored various liquid mixed wastes until 1992, when most of the waste was transferred to tank cars for off-site incineration. From 1951 to 1967 the tank was used to store reagent-grade hexone for makeup as a solvent at REDOX. The hexone was delivered to REDOX in rail cars that were unloaded into the 276-S-141 and 241-S-142 tanks via underground lines at the railcar unloading station.

Waste Type: Chemicals

Waste Description: The unit contained radiologically contaminated liquids made up of normal paraffin hydrocarbons, hexone, and phosphate tar. In 1992, the 276-S-141 and 276-S-142 each contained between 19 to 114 liters (5 to 30 gallons) of 93% normal paraffin hydrocarbons and 7% hexone. They also contained up to 950 liters (250 gallons) of phosphate tar. A nitrogen gas blanket and offgas filtration was implemented in 1990 during the distillation phase. In 2002, the nitrogen suppression system was shut off and the tanks were filled with grout. The remaining 19 to 114 liters (5 to 30 gallons) of liquid is expected to be removed by evaporation over time due to the nitrogen purge process.

Code: 276-S-142 **Classification:** Accepted

Names: 276-S-142; 276-S-142 Solvent Storage Tank; 276-S-306B; 276-S-TK-142; Hexone Storage Tank; Tank 276-142; 244-SX-15 **Reclassification:** None

Type: Storage Tank **Start Date:** 1/1/1951

Status: Inactive **End Date:** 1/1/1969

Description: The site is a below grade carbon steel tank. The tank is the northernmost tank in a two tank

network connected to the 276-S Solvent Handling Facility. The tank has a 89,000 liter (23,575 gallon) capacity.

Location: The underground tank is north of the 276-S Building and directly north of the 276-S-141 Tank. The system is west of the railroad tracks.

Related Sites/ Structures: Structures associated with the tank include: solvent transfer lines, the 276-S-141 Tank, the Tank Car Unloading Station, and process equipment in the 276-S Building. The pipelines associated with the hexone tanks are sitecode 200-W-230-PL.

Process Description: The tank is currently being closed under interim status and contains a small amount of liquid mixed waste. The tank stored various liquid mixed waste until 1992, when most of the liquid mixed waste was transferred to tank cars for off site incineration. From 1951 to 1967 the tank was used to store reagent-grade hexone for makeup as a solvent at REDOX. The hexone was delivered to REDOX in rail cars that were unloaded into the 276-S-141 and 241-S-142 tanks via underground lines at the railcar unloading station.

Waste Type: Chemicals

Waste Description: The unit contained radiologically contaminated liquids made up of normal paraffin hydrocarbons, hexone, and phosphate tar. In 1992, 276-S-141 and 216-S-142 contained between 19 to 114 liters (5 to 30 gallons) of 93% normal paraffin hydrocarbons and 7% hexone. They also contain up to 950 liters (250 gallons) of phosphate tar. A nitrogen blanket was added to the tank. In 2002, the nitrogen suppression system was shut off and the tanks were filled with grout. The remaining 19 to 114 liters (5 to 30 gallons) of liquid is expected to be removed by evaporation over time due to the nitrogen purge process.

Code: 2904-S-160 **Classification:** Accepted

Names: 2904-S-160; 2904-S-160 Control Structure; 2904-S-160 Weir **Reclassification:** None

Type: Control Structure **Start Date:** 1/1/1954

Status: Inactive **End Date:** 1/1/1976

Description: The unit is an inactive waste management unit consisting of a below grade pentagonal structure with reinforced concrete walls, floor, and roof. Sixty centimeter (24 inch) diameter vitrified clay pipes provided inlet and outlet flow for the structure. The site has been surface stabilized and is posted with Underground Radioactive Material/Cave-in Potential signs.

Location: The structure is located southwest of the southwest corner of the 200 West Area, outside the perimeter fence and north of the 216-S-5 crib.

Related Sites/ Structures: The site is associated with the 216-S-172 control structure, the 216-S-17 and 216-S-16 Ponds, the 216-S-6 Crib, 200-W-155-PL and 200-W-152-PL pipelines.

Process Description: The unit was built to divert process vessel cooling waste and steam condensate from 202-S Building to the 216-S-17 Pond, 216-S-6 Crib, and 216-S-16 Pond.

Waste Type: Process Effluent

Waste Description: The unit contains low-level contaminated concrete and piping. The quantity of contaminated waste has not been determined. There is beta/gamma contamination in the soil and smearable contamination on the surfaces of the box. Contamination originated from effluents traveling through the weir.

Code: 2904-S-171 **Classification:** Accepted

Names: 2904-S-171; 2904-S-171 Control Structure; 2904-S-171 Weir Box; 216-S-171 **Reclassification** None

Type: Control Structure **Start Date:** 1/1/1954

Status: Inactive **End Date:** 1/1/1976

Description: The 2904-S-171 Control Structure is a below grade, rectangular concrete weir structure. The inlet piping consisted of 46 centimeter (18 inch) diameter vitrified clay pipe. The outlet piping consisted of 46 centimeter (18 inch) diameter corrugated metal pipe. The site has been backfilled with clean material and is posted with Underground Radioactive Material signs.

Location: The site is located southwest of the 200 West Area, outside the perimeter fence, adjacent to the north side of the 216-S-6 Crib.

Related Sites/Structures: The structure is associated with the 216-S-6 Crib and the 200-W-153-PL and 200-W-156-PL pipelines.

Process Description: The unit was built to measure and regulate flow of process waste being routed to the 216-S-6 Crib. Pipeline 200-W-156-PL entered the control structure from the north. Pipeline 200-W-153-PL entered the control structure from the east.

Waste Type: Process Effluent

Waste Description: This unit contains low-level contaminated concrete and piping. The quantity of contaminated waste has not been determined. There were beta/gamma smearable contamination and recordable radiation readings with a Cutie Pie (hand-held radiation monitor) on the above ground portions of the structure before it was surface stabilized.

Code: 241-TX-152 **Classification:** Accepted

Names: 241-TX-152; 241-TX-152 Diversion Box **Reclassification** None

Type: Diversion Box **Start Date:** 1/1/1949

Status: Inactive **End Date:**

Description: The diversion box is a rectangular reinforced concrete structure. Most of the structure is below ground. A few inches of the structure that extends above ground is covered with a gray weather coating. It is surrounded with light posts and chain and is posted with various radiological postings.

Location: This unit is located east of the 241-TX Tank Farm. It is east of Camden Ave. and south of 23rd Street. It is north of the 200 West Area Powerhouse Pond.

Related Sites/Structures: The 241-TX-152 Diversion Box is associated with the T-Plant, 241-SY Tank Farm, UPR-200-W-113, 200-W-182-PL and the 241-TX-154 Diversion Box.

Process Description: The Diversion Box was used to direct liquid waste to other tank farm locations in 200 East and West Areas via jumper connections and underground transfer lines.

Waste Type: Process Effluent

Waste Description: The unit transports waste solutions from processing and decontamination operations. Quantities are variable according to specific plant operations. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Code: 241-TX-154 **Classification:** Accepted

Names: 241-TX-154; 241-TX-154 Diversion Box **Reclassification:** None

Type: Diversion Box **Start Date:** 1/1/1949

Status: Inactive **End Date:**

Description: The diversion box is a rectangular reinforced concrete structure. Most of the structure is below ground. The diversion box is surrounded with post and chain. It is labeled and radiologically posted. The adjacent area has been covered with shotcrete.

Location: This unit is located on the east side of the 221-T Building.

Release Description: Multiple unplanned releases and transfer line breaks are associated with this diversion box.

Related Sites/Structures: The 241-TX-154 diversion Box is associated with T-Plant operations, 241-TX-152 Diversion Box, 241-TX-302C Catch Tank, 241-SY Tank Farm, UPR-200-W-21, UPR-200-W-40, UPR-200-W-38 and UPR-200-W-160. The encased pipeline between 241-TX-154 Diversion Box and 241-TX-155 Diversion Box is sitecode 200-W-143-PL.

Process Description: This unit was used to transfer of waste solutions from decontamination operations at T-Plant to various tank farm facilities via underground transfer lines.

Waste Type: Process Effluent

Waste Description: The unit transports radioactive waste solutions from processing and decontamination operations. Quantities are variable according to specific plant operations. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Code: 241-TX-155 **Classification:** Accepted

Names: 241-TX-155; 241-TX-155 Diversion Box **Reclassification:** None

Type: Diversion Box **Start Date:** 1/1/1949

Status: Inactive **End Date:** 1/1/1980

Description: The diversion box is a rectangular reinforced concrete structure. Most of the structure is below ground. A few inches of the structure that extends above ground is covered with a gray weather coating. It is surrounded with light posts and chain and Contamination Area signs.

Location: This unit is located east of the 241-TX Tank Farm, south of 23rd Street and north of the 200 West Area Powerhouse Pond.

Release Description: Over the years, multiple releases associated with this diversion box and its pipelines have been documented. HW-60807, issued in 1959, states that contamination has spread from this diversion box to the surrounding ground on several occasions. Three sides of the diversion box were covered with black top in an effort to contain the contamination. In November 1952, contaminated nitric acid solution was pumped from the 241-TX-155 catch tank to an excavation nearby and covered with soil. The area was surrounded with a wooden fence and radiation signs in 1952, but is not currently marked. In 1954, a jumper leak in the diversion box caused an area measuring 9 meters by 30.5 meters (30 by 100 feet) to become contaminated. This area was also fenced and posted at the time of the occurrence, but the wooden fence is no longer present. In 1998, 1999 and 2000, several large areas of contamination was identified and posted around the diversion box and on its associated pipelines (See UPR-200-W-113).

Related Sites/Structures: The 241-TX-155 Diversion Box is associated with the 241-TX-302B and 241-TX-302BR Catch Tanks, the 241-T, 241-TX, and 241-TY Tank Farms, UPR-200-W-113, UPR-200-W-5, UPR-200-W-28, UPR-200-W-135 and UPR-200-W-76. The encased pipeline between 241-TX-154 Diversion Box and 241-TX-155 Diversion Box is sitecode 200-W-143-PL. Other transfer lines are 200-W-176-PL, 200-W-177-PL, 200-W-182-PL, 200-W-191-PL.

Process Description: This unit was to transfer waste solutions from processing and decontamination operations to various tank farm facilities via underground transfer lines.

Waste Type: Process Effluent

Waste Description: This unit was used for transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operation. Lead shielding may also be contained inside the diversion box.

Waste Type: Equipment

Waste Description: Equipment associated with the diversion box includes transfer piping and nozzles. Waste lead is also stored in the diversion box.

Code: 241-TX-302B **Classification:** Accepted

Names: 241-TX-302B; 241-TX-302-B Catch Tank; Lines V414 and V415 **Reclassification:** None

Type: Catch Tank **Start Date:** 1/1/1949

Status: Inactive **End Date:** 1/1/1982

Description: This unit is an underground, cylindrical tank made of steel. The drain lines from 241-TX-155 are V414 and V415. The ground surface around the tank has been covered with gravel. The tank is surround with light posts and chain and posted with Contamination Area and IMUST signs.

Location: This tank is located east of the 241-TX Tank Farm, northeast of the 241-TX-155 Diversion Box. It is east of Camden Ave and south of 23rd St.

Related Sites/Structures: The 241-TX-302B Catch Tank is associated with the 241-TX-155 Diversion Box, 241-TX-302BR Catch Tank, UPR-200-W-135 and UPR-200-W-131. The drain lines from 241-TX-155 are V414 and V415.

Process Description: The tank received overflow from the 241-TX-155 Diversion Box.

Waste Type: Process Effluent

Waste Description: This unit was used for containment of waste solution spills that occurred during transfers from processing and decontamination operations. Volumes collected were variable according to specific plant operations. In 1984, the volume was estimated to be 4989.6 liters (1320 gallons). The Stabilization Evaluation Form in Appendix B states that the tank had 14.75 inches of total waste and 14.5 inches of solid waste inside. Therefore, there were 1362 gallons of solid waste and 70 gallons of liquid waste in the tank. A sample from this tank was taken on March 6, 1984. It was reported to have a dose rate of 24 millirad per hour with a pH of 9.95.

Code: 241-TX-302BR **Classification:** Accepted

Names: 241-TX-302BR; 241-TX-302BR Catch Tank; 241-TXR-302BR **Reclassification:** None

Type: Catch Tank **Start Date:** 1/1/1950

Status: Inactive **End Date:** 1/1/1954

Description: This unit is an underground, horizontal, cylindrical tank made of steel. The ground surface around the tank has been covered with gravel. The tank is surrounded with posts and chain and

labeled with IMUST signs.

Location: The 241-TX-302BR Catch Tank is located east of the 241-TX-155 Diversion Box. It is located east of Camden Ave. and south of 23rd Street.

Related Sites/ Structures: This tank is associated with UPR-200-W-131, 241-TX-155 Diversion Box, 241-TX-302B Catch Tank and 216-T-20 acid pit.

Process Description: This tank received drainage from Diversion Box 241-TX-155.

Waste Type: Process Effluent

Waste Description: The unit was used to transfer of waste solutions from processing and decontamination operations. No waste volume was available in 1994.

Code: 241-TX-302C	Classification: Accepted
Names: 241-TX-302C; 241-TX-302-C Catch Tank; Lines V741 and V742	Reclassification: None
Type: Catch Tank	Start Date: 1/1/1947
Status: Inactive	End Date: 1/1/2005

Description: This unit is an underground horizontal, cylindrical tank made of carbon steel. The tank area has been sprayed with shotcrete to control surface contamination.

Location: The 241-TX-302 Catch tank is located southeast of the center of the 221-T Building.

Related Sites/ Structures: The 241-TX-302-C Catch Tank is associated with the 241-TX-154 Diversion Box and UPR-200-W-38. The diversion box drain lines are V741 and V742.

Process Description: This unit received overflow from the 241-TX-154 Diversion Box.

Waste Type: Process Effluent

Waste Description: This unit is used for transfer of radioactive waste solutions from processing and decontamination operations at T Plant. Volumes are variable according to specific plant operation. In 2007, the liquid content was estimated to be approximately 200 gallons (per RPP-RPT-31148, Rev. 2)

Code: 216-TY-201	Classification: Accepted
Names: 216-TY-201; Supernatant Disposal Flush Tank	Reclassification: None
Type: Settling Tank	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1966

Description: The 216-T-26, 216-T-27 and 216-T-28 cribs and the 216-TY-201 Tank are enclosed in a common area with steel post and chain barricade. The area is posted "Underground Radioactive Material". The 216-TY-201 flush tank is located in the northeast corner of the area. It has three risers protruding from a mound of earth. The 216-TY-201 tank is delineated with steel post and chain and marked with Inactive Miscellaneous Underground Storage Tank signs.

Location: The unit is located in the 200-West Area. It is east of Camden Ave and south of 23rd Street.

Related Sites/ Structures: The tank is associated with supernatant waste from tanks 241-TY-101, 241-TY-102, 241-TY-103 and 241-TY-104 in the 241-TY Tank Farm; tanks 241-T-110, 241-T-111 and 241-T-112 in the 241-T Tank Farm, 200-W-175-PL and the 216-T-26, 216-T-27 and 216-T-28 Cribs.

Process Description: HNF-2503 states the flush tank originally received supernate from the TY Tank Farm (1953-1955) and discharged the overflow to the 216-T-26 crib. The pipeline from 241-TY Farm was blanked near the 241-TY Tank Farm eastern fenceline in December 1955. After 1955, the flush tank received waste via another pipeline from tank 241-T-112 in the 241-T Tank Farm. Overflow from the flush tank was discharged to the 216-T-27 and 216-T-28 cribs. (see drawings H-2-2733 and H-2-3019)

Waste Type: Process Effluent

Waste Description: In 1955 and 1956, the 216-TY-201 Flush Tank received scavenged first cycle supernate from 221-T after it had cascaded through the 241-TY-101, 241-TY-103, and 241-TY-104 tanks in 241-TY Tank Farm. From 1960 through 1966 the 216-TY-201 Flush Tank received T Plant steam condensate and process decontamination waste via the 241-T-112 tank in the 241-T Tank Farm. In 1963, 2706-T equipment decontamination waste was added to the waste stream. In 1964, 300 Area laboratory waste was trucked to the 216-T-27 and 216-T-28 cribs and released to the cribs through a riser. The Authorization Basis Status Report (1998) assumes the solid and liquid composition to be the same as those found in tank 241-T-112. Solids are assumed to contain 5110 micrograms per gram (ug/g) aluminum, 28800 ug/g bismuth, 16400 ug/g iron, 41000 ug/g sodium, 395 ug/g lead, 313 ug/g strontium, 3100 ug/g uranium, and 36600 ug/g OH. Solid radionuclides are assumed to include 0.184 microcuries per gram (uCi/g) cesium-137, 6.0 uCi/g strontium-90, 5.71 E-04 uCi/g plutonium-138, 0.07 uCi/g plutonium-139 and 1.0 E-04 uCi/g americium-241. The Supernate is expected to contain 9.0 E-06 uCi/g americium-241.

Code: 241-U-151 **Classification:** Accepted

Names: 241-U-151; 241-U-151 Diversion Box **Reclassification:** None

Type: Diversion Box **Start Date:** 1/1/1946

Status: Inactive **End Date:**

Description: The diversion box is marked and radiologically posted. This unit is constructed of reinforced concrete with multiple encased liquid waste transfer lines. The diversion box structure is mostly below ground. It has three layers of cover blocks.

Location: The 241-U-151 Diversion Box is located northeast of the intersection of Camden Avenue and Sixteenth Street, east of the 241-U Tank Farm.

Related Sites/ Structures: The 241-U-151 Diversion Box is associated with the 241-U-301 Catch Tank and the 244-S and 244-TX Double Contained Receiver Tanks. The unit is also associated with Diversion Boxes 241-U-152, and 241-TX-152, UPR-200-W-6, 200-W-99-PL, 200-W-130-PL, 200-W-183-PL, 200-W-184-PL.

Process Description: This unit was used to transfer waste solutions from processing and decontamination operations.

Waste Type: Process Effluent

Waste Description: The unit transports waste solutions from processing and decontamination operations. Quantities are variable according to specific plant operations. Lead shielding may also be contained inside the diversion box.

Code: 241-U-152	Classification: Accepted
Names: 241-U-152; 241-U-152 Diversion Box	Reclassification: None
Type: Diversion Box	Start Date: 1/1/1946
Status: Inactive	End Date:

Description: The diversion box is marked and radiologically posted. The unit is constructed of reinforced concrete with multiple encased liquid waste transfer lines. The diversion box structure is mostly below ground. It has three layers of cover blocks.

Location: The 241-U-152 Diversion Box is located northeast of the intersection at Camden Avenue and Sixteenth Street, east of the 241-U Tank Farm.

Related Sites/ Structures: The 241-U-152 Diversion Box is associated with the 241-U-301 Catch Tank, the 241-U-153 Diversion Box, 200-W-181-PL, 200-W-182-PL, 200-W-183-PL, 200-W-184-PL and UPR-200-W-6.

Process Description: This unit was used to transfer waste solutions from processing and decontamination operations.

Waste Type: Process Effluent

Waste Description: The unit transports waste solutions from processing and decontamination operations. Quantities are variable according to specific plant operations. Lead shielding may also be contained inside the diversion box.

Code: 241-UX-154	Classification: Accepted
Names: 241-UX-154; 241-UX-154 Diversion Box	Reclassification: None
Type: Diversion Box	Start Date: 1/1/1948
Status: Inactive	End Date: 1/1/2003

Description: The diversion box is marked and radiologically posted. The unit is mostly below grade, constructed of reinforced concrete. Multiple encased liquid waste transfer lines enter the box through its southeast wall.

Location: The 241-UX-154 Diversion Box is located southeast of the 221-U Canyon Building.

Release Description:

Related Sites/ Structures: The 241-UX-154 Diversion Box is associated with the 221-U Canyon Building, 241-WR Vault, 291-U stack, 241-TX-155 Diversion Box, and 241-UX-302 Catch Tank. The 200-W-136 URMA posting was expanded and now includes the diversion box and catch tank.

Process Description: This unit was used to transfer waste solutions from processing and decontamination operations from U Plant to the various tank farms. The 241-UX-154 Diversion Box served as a waste transfer hub not only for the 200 West Area, but also for cross site waste transfers from 200 East Area to 200 West Area through the inter-area (cross-site) transfer line (see 600-284-PL). The diversion box also received drainage from the 291-U stack. The 241-UX-154 diversion box and associated pipelines supported U Plant operations from 1948 through 1958. From 1958 to January 2003, the diversion box received drainage from cross-site transfer line flushes and drainage from pipeline encasements. The U Plant exhaust stack drained to the diversion box from 1958 to 1985 when the stack drain line was re-routed directly to the 241-UX-302A catch tank. The nozzle pit portion of 241-UX-154 diversion box (northeast segment of structure) was weather sealed in 2003. The diversion box is connected to 25 (3 inch stainless steel) encased lines and has two drain lines to the 241-UX-302A catch tank.

Waste Type: Process Effluent

Waste Description: The unit transfers waste solutions from processing and decontamination operations via underground, encased waste lines. Quantities are variable according to specific plant operations. Lead shielding may also be contained within the structure.

Code: 241-UX-302A **Classification:** Accepted

Names: 241-UX-302A; Lines V380 and V381; 241-U-302 Catch Tank; 241-UX-302; 241-UX-302 Catch Tank **Reclassification:** None

Type: Catch Tank **Start Date:** 1/1/1947

Status: Inactive **End Date:** 1/1/2005

Description: The 241-UX-302A waste site is a direct-buried, carbon steel tank that collected drainage from the 241-UX-154 Diversion Box. It is covered with gravel, marked and radiologically posted.

Location: The tank is located southeast of the 221-U Building and south of the 241-UX-154 Diversion Box.

Release Description: A leak assessment test was conducted in March 2006 and concluded the tank was assumed to be leaking, likely through a pin hole at the 10.5" level. ENRAF liquid gauge readings indicated ~ 1,700 gals of waste remained in the tank vs. the 877-gal estimate from video survey conducted as part of the leak assessment test. I

Related Sites/Structures: The unit is associated with 241-UX-154 Diversion Box and U Plant. The drain lines are lines V380 and V381.

Process Description: The catch tank collected excess liquid from the 241-UX-154 Diversion Box and 291-U stack condensate drainage. From 1958 to January 2003, the catch tank received drainage from cross-site transfer line (600-284-PL) flushes, the U Plant exhaust stack drainage and infiltration of rain and snow melt from the 241-UX-154 Diversion Box and pipeline encasements.

Waste Type: Process Effluent

Waste Description: This unit was used for transfer of waste solution from processing and decontamination operations. Volumes were variable according to specific plant operation when it was active. In August 1995, it contained 4232 liters (1118 gallons) of waste. The tank was pumped down to the pump inlet level in January 2003. In March 2006, the tank was estimated to contain 6551 liters (1724 gallons). In October 2006, the more liquid was pumped out of the tank, leaving a residual of approximately 3.8 liters (one gallon).

Code: 200-W-7 **Classification:** Accepted

Names: 200-W-7; 241-S-TK-1; 243-S-TK1; 243S-TK-1; 246-L; 200-W Personnel Decontamination Facility Catch Tank **Reclassification:** None

Type: Catch Tank **Start Date:** 1/1/1978

Status: Inactive **End Date:** 1/1/1988

Description: The underground tank is inside a chained area that measures approximately 3 meters by 3 meters (9 feet by 9 feet), with three risers extending to the surface. The tank is posted with Inactive Miscellaneous Underground Storage Tank (IMUST) signs and radiological postings.

Location: The site is located northwest of 242-S Evaporator and just north of MO-326.

Related Sites/ Structures: The tank is associated with Trailer MO-0326. It was the Personnel Decontamination Facility for 200 West Tank Farms.

Process Description: The underground tank is a 2,082 liter (550 gallon) fiberglass catch tank was connected to trailer MO-0326. The trailer had been used as a personnel decontamination facility. The trailer had a sink and a shower. The trailer has been removed. The underground tank is covered with a minimum of 0.9 meters (3 feet) of overburden. The tank has three risers.

Waste Type: Storage Tank

Waste Description: The tank received effluent from the personnel decontamination sink and shower. The tank contents would include soap, water and low levels of radionuclides.

Code: 200-W-16	Classification: Accepted
Names: 200-W-16; 292-T Underground Tanks; 292-TK-1; 292-TK-2	Reclassification: None
Type: Storage Tank	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1970

Description: The site consists of two underground, stainless steel, 55-gallon drums, encased in a concrete block with lifting eyes. Two metal riser pipes extend about 0.5 meters (1.5 feet) above grade near the southeast corner of the 292-T building addition. Both are capped and one appears to have a pressure relief vent. These pipes extend from two buried tanks (292-TK-1 and 2). There is a chain link fence enclosing the area where the tanks are located. The fence is posted with Access Restricted signs. The site is within a chained area posted "Contamination Area".

Location: The underground tanks are near the southeast corner of the 292-T building addition. The 292-T building is south of the 291-T stack and north of 222-T.

Related Sites/ Structures: The site is associated with 291-T, 221-T, and the 292-T facility (200-W-40).

Process Description: The 292-T building originally housed the 291-T stack gas sampling system and supported the 221-T off gas monitoring operations. When T Plant was built, it was not known what material would escape during the reprocessing of the irradiated fuel. Accordingly the stack was equipped with state of the art monitoring equipment, including scrubbers containing 5% soda ash solutions that the stack effluent was passed through. The solution was dried using refrigeration, and then counted to determine Xenon-133 activity. Extensive reviews of documentation remaining from T Plant operations has not located any documents that quantify the amount of material that was placed in the tanks, but very little emphasis was placed on waste management at that time and it is doubtful that any documents were kept. In 1966, a building addition was added to the existing structure to house a fuel element testing facility, operated by Battelle Northwest. During the lab upgrade, the two underground storage tanks were relocated from southeast of the original 292-T building to their present position, southeast of the 292-T building addition. Fuel failure analysis of irradiated fuel rods was conducted in 292-T in the 1960's and early 1970's. Irradiated N Reactor fuel rods were heated in an induction furnace until rupture or failure occurred. After the rupture occurred, the fuel was transported to the 300 Area for further analysis. The fragments that remained in the oven were removed, and any material that remained on the oven surface was dissolved with nitric acid. It is doubtful that much if any of the aluminum clad was dissolved, since aluminum will not dissolve in nitric acid without the use of a catalyst. The solution of trace amounts of irradiated fuel and nitric acid was poured into the 292-T-TK-1 and 2 tanks through the risers. The solution in the tanks was then neutralized with sodium hydroxide. Neutralization caused the dissolved metals to precipitate and deposit in the tank bottoms.

Waste Type: Storage Tank

Waste Description: Liquid waste was sent to these underground tanks from the 292-T building. Early waste consisted of solutions from the off gas monitoring scrubbers. Later waste was associated with experiments involving failure analysis of irradiated fuel rods. Irradiated N Reactor fuel rods were heated in an induction furnace until rupture or failure occurred. The slag that remained in the furnace was dissolved in nitric acid. A solution of dissolved irradiated fuel and nitric acid was discharged to 292-TK-1 and 292-TK-2. The solution was then neutralized with sodium hydroxide. Neutralization likely caused the dissolved metals to precipitate and deposit in tank bottoms. Dose rate directly above tanks was 2 millirem per hour in 1995.

Code: 200-W-58

Classification: Accepted

Names: 200-W-58; Z-Plant Diversion Box #1

Reclassification: None

Type: Valve Pit

Start Date: 1/1/1958

Status: Inactive

End Date:

Description: The Plutonium Finishing Plant had a gravel covered, fenced exclusion area. The concrete lid of the diversion box is visible above ground. The unit is buried to a depth of 2.7 meters (9 feet) with its upper surface (a thick concrete lid) being slightly above grade. A 20 foot long, 12 inch diameter VCP pipe, extends from the 200-W-58 diversion box to a small drain field.

Location: The site is located south of 234-5Z facility. It is directly south of the 241-Z-361 settling tank. It was between the two fences that made up the double enclosed exclusion area. Most of the fencing around 234-5Z has been removed.

Related Sites/ Structures: This structure is associated with pipelines 200-W-208-PL and 200-W-210-PL, 200-W-174-PL, 200-W-59, the 241-Z-361 settling tank, 216-Z-1, 216-Z-2, 216-Z-3, 216-Z-1A, 216-Z-12 and 216-Z-18.

Process Description: Pipeline 200-W-210-PL extends from 241-Z-361 to this diversion Box. The diversion box contains valves for routing liquid process waste to 216-Z-1, 216-Z-3, 216-Z-18 via 200-W-210-PL or to 216-Z-12 via 200-W-208-PL and diversion box number 2 (sitecode 200-W-59).

Waste Type: Process Effluent

Waste Description: The structure directed the flow of Z Plant process waste to cribs and tile fields located south of the Z Plant complex.

Code: 200-W-59

Classification: Accepted

Names: 200-W-59; Z-Plant Diversion Box #2

Reclassification: None

Type: Valve Pit

Start Date: 1/1/1958

Status: Inactive

End Date:

Description: The Plutonium Finishing Plant had a gravel covered, fenced exclusion area. The concrete lid of the diversion box is visible above ground. The unit is buried to a depth of 2.7 meters (9 feet) with its upper surface (a thick concrete lid) being slightly above grade. A 20 foot long, 12 inch diameter VCP pipe, extends from the 200-W-58 diversion box to a small drain field.

Location: The site is located southwest of the 234-5Z building. It is west of the 216-Z-361 settling tank and directly north of the 216-Z-12 crib. It was between the two fences that made up the double enclosed exclusion area. Most of the fencing around 234-5Z has been removed.

Release Description: The pipe connecting the 200-W-59 diversion box to the 216-Z-12 perforated crib distributor pipe (200-W-208-PL) leaked and caused a thin layer of plutonium contamination between the crib and the diversion box. Four shallow wells were drilled in 1976 to evaluate the leak. Levels of plutonium activity detected were comparable to those found in the 216-Z-12 crib. (see RHO-ST-44 and SGW-39648)

Related Sites/ Structures: 200-W-59 is associated with pipeline 200-W-208-PL, 241-Z-361, 216-Z-12 and 200-W-58.

Process Description: The structure directed the flow of process waste via the 241-Z-361 settling tank to the 216-Z-12 crib, via diversion box number 1 (sitecode 200-W-58). The structure is also referred to as a Valve Pit.

Waste Type: Process Effluent

Waste Description: This diversion box directed the flow of process waste to the 216-Z-12 crib.

Code:	200-W-84-PL	Classification:	Accepted
Names:	200-W-84-PL; U Plant Chemical Process Sewer to 216-U-14 Ditch; VCP Process Sewer; 200-W-84	Reclassification	None
Type:	Radioactive Process Sewer	Start Date:	1/1/1952
Status:	Inactive	End Date:	7/1/1984

Description: The majority of the waste site is an underground, 30 centimeter (12 inch) diameter and 46 centimeter (18 inch) diameter, vitrified clay pipeline. A 20 centimeter (8 inch) diameter process sewer line from 224-U and 222-U connects to the main process sewer line. It terminated at a timber headwall where the flow entered the 216-U-14 Ditch. The surface of the pipeline is marked with Underground Radioactive Material and Pipeline signs. At intervals along the pipeline, there are approximately thirteen, 1.2 meter, (4 foot) diameter manholes.

Location: The underground process sewer line extends from the northwest side of the 221-U Building to the 216-U-14 Ditch. The line runs south, under 16th Street, and turns west until it intersects with the south end of the ditch. A pipeline from 224-U and 222-U extends along the northwest side of these buildings and connects to the main process sewer line in a manhole north of 16th street.

Related Sites/ Structures: The pipeline is associated with the 221-U Plant, 271-U, 224-U, 222-U, 292-U, and the 216-U-14 Ditch. The 216-U-16 crib pipeline (200-W-170-PL) attaches to this process sewer line.

Process Description: The 221-U facility was reconfigured to support the Uranium Recovery process in 1952. The process sewer waste received effluent from 221-U, 271-U, 224-U, 222-U and 292-U and transported it to the 216-U-14 Ditch. This pipeline bypasses the 207-U Retention basin. Feed lines were constructed or removed from service at various times throughout the active service life of this sewer. The 222-U building was demolished in 2005. The 224-U and 224-UA facilities, along with other support structures, were demolished in 2010.

Waste Type: Process Effluent

Waste Description: The 216-U-14 Ditch received 221-U chemical sewer effluent (via this vitrified clay pipeline) From January 1952 through July 1984.

This Site has the Following SubSites:

Code: 200-W-84-PL:1
Names: 200-W-84-PL:1; 12-Inch VCP

Code: 200-W-84-PL:2
Names: 200-W-84-PL:2; 18-Inch VCP

Code: 200-W-84-PL:3
Names: 200-W-84-PL:3; 8-Inch VCP

Code: 200-W-84-PL:1	Classification: Accepted
Names: 200-W-84-PL:1; 12-Inch VCP	Reclassification: None
Type: Radioactive Process Sewer	Start Date: 1/1/1952
Status: Inactive	End Date: 7/1/1984

Description: The 12 inch diameter VCP line is located on the northwest side of 221-U. It ties to the 18 inch VCP portion of the process sewer at a manhole north of 16th Street.

Location: The majority of subsite 1 is located on the west side of 221-U.

The SubSite is Part Of:

Code: 200-W-84-PL
Names: 200-W-84-PL; U Plant Chemical Process Sewer to 216-U-14 Ditch; VCP Process Sewer; 200-W-84

Code: 200-W-84-PL:2	Classification: Accepted
Names: 200-W-84-PL:2; 18-Inch VCP	Reclassification: None
Type: Radioactive Process Sewer	Start Date:
Status: Inactive	End Date:

Description: The 18 inch portion of the process sewer begins at a manhole north of 16th Street and extends south and west to terminate in the 216-U-14 ditch. The portion of the sewer that passes under 16th Street is encased in concrete.

The SubSite is Part Of:

Code: 200-W-84-PL
Names: 200-W-84-PL; U Plant Chemical Process Sewer to 216-U-14 Ditch; VCP Process Sewer; 200-W-84

Code: 200-W-84-PL:3	Classification: Accepted
Names: 200-W-84-PL:3; 8-Inch VCP	Reclassification: None
Type: Radioactive Process Sewer	Start Date:
Status: Inactive	End Date:

Description: The 8 inch VCP line is located on the northwest side of 224-U and 222-U (extending to 292-U). It ties into the main process sewer line at a manhole north of 16th Street.

The SubSite is Part Of:

Code: 200-W-84-PL
Names: 200-W-84-PL; U Plant Chemical Process Sewer to 216-U-14 Ditch; VCP Process Sewer; 200-W-84

Code: 241-Z	Classification: Accepted
Names: 241-Z; 241-Z Sump; 241-Z Tank Farm; 241-Z Tank Pit; 241-Z Treatment and Storage System; 241-Z Treatment and Storage Tanks; 241-Z-D-4; 241-Z-D-5; 241-Z-D-7; 241-Z-D-8	Reclassification: None
Type: Neutralization Tank	Start Date: 11/24/1948
Status: Inactive	End Date: 1/1/2004

Description: Site currently consists the building slab and below grade concrete vault containing four storage and treatment tanks. The above ground features were removed in 2005 through 2007. All of the buildings were removed to grade, leaving a grade level slab or an underground cell. The below grade cells and tanks were deactivated and decontaminated to the extent practicable. Residual contamination was fixed to the structures left in place. Pipe penetrations in the cell walls were verified to be empty and sealed. The hazards were removed. The D6 cell was partially filled with Controlled Density Fill due to structural and contamination control concerns. Approximately 0.6 meters (2 feet) of fill remains in the cell.

The RCRA TSD portion of this facility consists of the tanks (excluding D-6), the internal piping, the concrete vaults, ancillary equipment and the soil directly below the tanks. The external pipelines leading from buildings in 234-5Z to the 241-Z facility are not considered part of this site.

Location: The site is located inside the Z-Plant Security Fence, near the south end of the complex.

Release See UPR-200-W-74, UPR-200-W-75 and UPR-200-W-79.

Description: Over time, it is estimated that up to 40,000 gallons leaked from Tank D6, which may have contained up to 40 grams of plutonium. To stabilize the contamination below the D6 tank, approximately 24 inches of control density fill (CDF) was added to the cell after the final cell survey. The CDF will not only anchor the tank to inhibit moving in the event of a wall collapse but also encapsulate the material to prevent spread of contamination. Process liquid transfers from the 241-Z storage and treatment tanks to Tank Farms were routinely followed by flushing of the line and tank cleaning. Exit surveys were performed for each cell and contamination generally was above high contamination areas (HCA) levels (>2000 DPM/100 cm²) with some areas of up to approximately 100,000 DPM/100 cm². Contamination may reach approximately 4 meters below the D6.

In March 2002, a leak in the system piping that resulted in liquid leaking into the D8 vault was identified. A portion of the Tank D8 ancillary piping was observed leaking. A cell entry was made and it was determined that a drain line had failed resulting in a minor release of liquids. The spill was cleaned up and the line was replaced. D8 cell was noted to have cracked and leaked. As part of the RCRA Closure of 241-Z tank system, samples were taken at three locations within the D8 Cell, as well as within the piping system. All results indicated the detection of only trace levels of constituents of concern.

Related Sites/ Structures: The site is related to 241-Z-D-4, 241-Z-D-5, 241-D-6, 241-Z-D-7, and 241-Z-D-8. Unplanned Releases UPR-200-W-74, UPR-200-W-75 and UPR-200-W-79 are also associated with 241-Z. The sample building (241-ZA) located on the southeast corner of the 241-Z is also part of this site. The pipelines to 241-Z is described in sitecodes 200-W-219-PL. The waste transfer line from 241-Z to 241-TX Tank Farm is 200-W-178-PL. The pipeline from 241-Z to 241-Z-361 settling tank is sitecode 200-W-220-PL. Pipelines that fed 241-Z include 200-W-219-PL, 200-W-224-PL, 200-W-228-PL, and 200-W-229-PL.

Process Description: The 241-Z tanks are a waste treatment, storage and collection system containing below grade tanks in covered concrete cells. The operating capacity of the tank system was 17,000 gallons (65,000 liters). Liquid wastes generated from Plutonium Finishing Plant operations were collected in tank 241-Z-D-8 for interim storage. The waste was transferred to 241-Z-D-5 for

treatment (pH adjustment) prior to discharge to the tank farms via 244-TX receiver tank. Tanks 241-Z-D-4 and 241-Z-D-7 were reserve waste accumulation tanks.

Waste Type: Process Effluent

Waste Description: The unit received waste from 234-5Z. Before treatment, the waste was corrosive (less than pH 2.0) containing predominately nitric acid. Additional constituents known to be present include chromium, lead, aluminum nitrate, aluminum fluoride, and lower concentrations of potassium hydroxide, potassium fluoride, magnesium nitrate, ferric nitrate, calcium nitrate, and other trace metal ions. Treatment occurred in a batch process consisting of the addition of sodium hydroxide, ferric nitrate and sodium nitrate. Batch discharges averaged 125 gallons per week from 1991 to 1994. No discharges were made during 1995.

From 1949 to 2004 the 241-Z storage and treatment tanks received approximately 740,000 gallons of waste from the PFP and transferred that to the Double Shell Tank System (DTS). These included high salt and low salt waste including sodium hydroxide, potassium hydroxide, sodium nitrite, ferric nitrate, carbon tetrachloride, metals, lead, mercury, and trace amounts of plutonium. Tank D4 collected low salt waste from PFP and transferred that to Tank D7. Tank D5 collected waste from Tanks D7 and D8 and treated the mixed waste with sodium hydroxide, ferric nitrate, and sodium nitrite. Sodium hydroxide raises the free hydroxide ion concentration to greater than 1.5 molar. Ferric nitrate is to provide stable solids and sodium nitrite is added to inhibit corrosion. Tank D5 was equipped with a pump and steam jet for waste transfers to the Double Shell Tank System.

Code:	HSVP	Classification:	Accepted
Names:	HSVP; Semiworks Valve Pit; 201-C Diversion Box; 201-C Valve Box; Hot Semiworks Valve Pit	Reclassification	None
Type:	Valve Pit	Start Date:	1/1/1951
Status:	Inactive	End Date:	1/1/1986
Description:	The site is a sealed, concrete-filled, vertically configured, stainless-steel cylinder that is buried beneath the ash barrier which was placed over the decommissioned 201-C Process Building (see 200-E-41). The surface stabilized area is posted with Underground Radioactive Material signs. The valve pit is not separately marked or posted.		
Location:	This valve pit is adjacent to the remains of the 201-C Building and southeast of the main canyon area. It is located within the surface stabilized area known as 200-E-41.		
Related Sites/Structures:	Structures associated with the decommissioned valve pit include: the 201-C Building, valves, transfer lines, the 244-CR Vault, 241-C Tank Farm, and the 241-CX-70 Tank. It is also associated with 200-E-41 Stabilized Area and pipeline 200-E-150-PL.		
Process Description:	This valve pit connected sources within the 201-C Building with discharge locations at the 244-CR Vault, the 241-C Tank Farm, and the 241-CX-70 Storage Tank.		
Waste Type:	Process Effluent		
Waste Description:	This site has been decommissioned. During operation, this valve pit routed pilot REDOX wastes, pilot PUREX wastes, and wastes from strontium recovery efforts to tank farm facilities. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.		

Code:	UPR-200-E-3	Classification:	Accepted
Names:	UPR-200-E-3; Line Leak from 221-B to 241-BX-	Reclassification	None

154; UN-200-E-3

Type: Unplanned Release**Start Date:** 1/1/1951**Status:** Inactive**End Date:****Description:** The release is not separately marked or posted.**Location:** The release occurred on the south side of 221-B, between the 221-B Building and 241-BX-154.**Release Description:** A failure of first-cycle waste line from the 221-B building to 241-BX-154 Diversion Box was identified. Efforts to excavate and inspect for the cause were abandoned when readings of 120 rads per hour were found with 46 centimeters (18 inches) of soil still remaining over the pipe.**Waste Type:** Process Effluent**Waste Description:** The release consisted of B Plant first cycle waste with dose rates up to 120 rad per hour at a distance of 0.4 meters (1.5 feet).**Code:** UPR-200-E-7**Classification:** Accepted**Names:** UPR-200-E-7; Cave-In Near 216-B-9 (241-B-361 Crib); Pipeline Leak; UN-200-E-7**Reclassification:** None**Type:** Unplanned Release**Start Date:** 1/1/1954**Status:** Inactive**End Date:****Description:** The site is an unplanned release to the soil from a waste line break. A single metal post with a WIDS sign marks an estimated release location near the 216-B-9 crib.**Location:** The Unplanned Release occurred on the east side of Baltimore Ave., near the 216-B-9 crib. The 216-B-9 Crib has an alias name of the 241-B-361 Crib. In 1954, a cave-in was noted over the underground line near the 241-B-361 crib.**Release Description:** On November 30, 1954, leakage from the waste line between 221-B and the 241-B-361 crib (alias 216-B-9 crib) caused the ground to cave-in near the 241-B-361 crib. Approximately 19,000 liters (5000 gallons) of liquid was lost to the ground. The maximum dose rate observed was 1.7 rads/hour over an area covering 2.7 square meters (30 square feet). The contamination was covered and delineated with a chain fence. The area was posted with "Underground Contamination" signs.**Related Sites/Structures:** Based on HW-60807, this release is assumed to be associated with pipeline site 200-E-199-PL.**Waste Type:** Process Effluent**Waste Description:** The release consisted of 18,925 liters (5000 gallons) of B Plant cell wash water from the 5-9 tank. The maximum dose rate was 1.7 rads/hour. Approximately, 2.8 square meters (30 square feet) of soil was contaminated by this release.**Code:** UPR-200-E-42**Classification:** Accepted**Names:** UPR-200-E-42; 241-AX-151 Release; UN-200-E-42**Reclassification:** None**Type:** Unplanned Release**Start Date:** 1/1/1972**Status:** Inactive**End Date:****Description:** A WIDS sign has been placed near the diversion box structure to document the release. The

release area is surrounded with posts and chain. It is posted with multiple radiological postings including Radiation Area, Underground Radioactive Material Area and Contamination Area.

Location: The 241-AX-151 Diversion Box is located near the corner of 4th Street and Buffalo Ave., adjacent to the 204-AR Unloading Station. The unplanned release site included a dirt bank east of the 241-AX-151 Diversion Box and weeds east of the established parking lot.

Release Description: Surveys made at the 241-AX-151 Diverter Station on November 6, 1972 revealed direct and smearable contamination of 200 to 300 millirad per hour with a few spots in excess of 5 rad per hour. The green tape sealing the cover block cracks was contaminated to 20 rad per hour. The blacktop east of the diversion box was contaminated up to 3000 counts per minute. The dirt bank east of the posted radiation zone had contaminated spots up to 2000 counts per minute and weeds contaminated from 300 to 800 counts per minute. Follow up surveys indicate the contamination spread to be a result of a steam jet being left on at 244-AR, resulting in the pressurization of the 241-AX-151 Diverter Tank.

Related Sites/ Structures: The release is associated with 241-AX-151 and 244-AR.

Process Description: 241-AX-151 routed waste from PUREX to the 244-AR Vault and to the 241-AY and 241-AZ Tank Farms.

Waste Type: Soil

Waste Description: The contamination spread consisted of specks with beta/gamma levels ranging 300 millirad per hour at the diversion box and from 300 to 3,000 counts per minute found on asphalt and soil surfaces in the vicinity of the 241-AX-151 diversion box. The 241-AX-151 diversion box routed waste from PUREX to the 244-AR Vault and to the 241-AY and 241-AZ Tank Farms.

Code: UPR-200-E-45	Classification: Accepted
Names: UPR-200-E-45; Contamination Spread from the 241-B-154 Diversion Box; UN-200-E-45	Reclassification: None
Type: Unplanned Release	Start Date: 1/1/1974
Status: Inactive	End Date: 1/1/1974

Description: A large area on the northeast corner of 7th Street and Baltimore Avenue is surrounded with post and chain and marked as an Underground Radioactive Material (URM) area. The URM surrounds the 241-B-154 Diversion Box, that has been covered with a coating of gray grout. The original Unplanned Release is not separately marked or posted.

Location: The 241-B-154 Diversion Box is located at the corner of 7th Street and Baltimore Ave. The release involved loose contamination spreading in a southeasterly direction from the 241-B-154 Diversion Box.

Release Description: During a "clean out" operation at the 241-B-154 Diversion Box, wind spread loose contaminated around the work area. The activity involved decontaminating the inside of the diversion box and removing jumpers. The wind caused the spread of loose contamination over an area approximately 91.5 meters (300 feet) by 30.5 meters (100 feet). Five employees, a crane and a water truck were also contaminated. The ground surface between the diversion box and 7th Street levels of contamination ranged from 1,000 counts per minute to 40,000 counts per minute. The contamination on 7th Street (blacktop) ranged from 800 counts per minute to 30,000 counts per minute. An area of contamination on the south side of 7th Street was found to have contamination levels ranging from 300 to 3000 counts per minute.

Related Sites/ Structures: This release is related to the 241-B-154 Diversion Box and UPR-200-E-77.

Waste Type: Process Effluent

Waste Description: Loose, dried, contamination particles (specks) were spread from the inside of the diversion box to the ground in the vicinity of 7th and Baltimore. The contamination spread included beta/gamma readings up to 50,000 counts per minute on the soil surface.

Code: UPR-200-E-67

Classification: Accepted

Names: UPR-200-E-67; Excavation of Radioactively Contaminated Pipe Encasement (V004, V005, V006, V007, V008); UN-200-E-67; UN-216-E-67

Reclassification: None

Type: Unplanned Release

Start Date: 1/1/1984

Status: Inactive

End Date: 1/1/1984

Description: The 1984 excavation has been backfilled. A WIDS sign has been placed at the approximate location of the excavation.

Location: This site was located in an excavation site, north of the 272-AW parking lot, near the corner of 4th Street and Canton Ave.

Release Description: The release occurred on May 7, 1984. An old, contaminated pipe encasement was encountered during the excavation. Contamination levels ranged from 1 to 1.5 milirad per hour.

Related Sites/Structures: The release is associated with pipeline site 200-E-207-PL.

Process Description: An encased pipeline (containing lines V004, V005, V006, V007 and V008) extends between the 241-A-151 Diversion Box, south of PUREX, to the 241-A-152 Diversion box that is located inside the 241-A Tank Farm. (see sitecode 200-E-207-PL)

Waste Type: Misc. Trash and Debris

Waste Description: The contamination levels consisted of beta/gamma readings ranging from 1,000 to 1,500 milliard per hour on the excavated pipe.

Code: UPR-200-E-77

Classification: Accepted

Names: UPR-200-E-77; 241-B-154 Diversion Box Ground Contamination; UN-200-E-77; UN-216-E-5

Reclassification: None

Type: Unplanned Release

Start Date: 1/1/1946

Status: Inactive

End Date:

Description: A large graveled area on the northeast corner of 7th Street and Baltimore Avenue is surrounded with post and chain and marked as an Underground Radioactive Material (URM) area. The URM surrounding the 241-B-154 Diversion Box has been covered with a coating of gray grout (shotcrete). The area appears to have been posted in stages. A large posted oval area (URM) extends north and east from the diversion box. Another posted area (URM) extends west to Baltimore Ave. and turns northward. In January 2000, a separate Contamination Area was posted around a power pole (adjacent to a manhole) within the larger URM. In 2002, the posting around the power pole was removed and a Fixed Contamination Area sign was attached to the pole.

Location: This site is located east of 221-B Building, at the northeast corner of Baltimore Avenue and Seventh Street. It surrounds the 241-B-154 Diversion Box.

Release Description: Metal waste solution contaminated the ground around the 241-B-154 Diversion Box as a result of work associated with a leaky jumper in the box.

Related Sites/Structures: The site is associated with the 241-B-154 Diversion Box.

Process Description: The contamination surrounding the diversion box is associated with the use of the diversion box to transfer contaminated waste via underground pipelines. Leaks and contamination spreads occurred during diversion box activities over the years. The diversion box was actively used between 1948 and 1984. The size and shape of the radiological posting has varied over the years.

Waste Type: Process Effluent

Waste Description: The original release involved metal waste solution from 221-B with fission products measuring approximately 1 curie. A radiological survey of the area done in October 1975 found surface contamination up to 80,000 counts per minute.

Code: UPR-200-E-78 **Classification:** Accepted

Names: UPR-200-E-78; 241-BX-155 Diversion Box Ground Contamination; UN-200-E-78; UN-216-E-6 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1955

Status: Inactive **End Date:**

Description: The release affected the area around the 241-BX-155 diversion Box and the catch tank. The 241-BX-155 diversion box has been isolated and covered with gray grout. The area around the diversion box and the surface area above the 241-BX-302C tank have been surface stabilized with gravel and posted with Underground Radioactive Material signs.

Location: This site is located in the area around the 241-BX-155 Diversion Box, south of the 241-BX Tank Farm, northeast of B-Plant between Atlanta and Baltimore Avenues.

Release Description: During pressure testing of lines and jumpers in the 241-BX-155 Diversion Box, a spill occurred causing the ground to become contaminated. The release affected an 18 square meter (200 square foot) area. At the time of the release, the maximum dose rate was 22.6 rad per hour.

Waste Type: Process Effluent

Waste Description: The release included salt waste from B Plant containing approximately 10 curies of mixed fission product. The maximum dose rate was 22.6 rad per hour at the surface of the spill site (241-BX-155 Diversion Box) in 1955.

Code: UPR-200-E-84 **Classification:** Accepted

Names: UPR-200-E-84; 241-ER-151 Catch Tank Leak (241-ER-311A); UN-200-E-84; UN-216-E-12 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1953

Status: Inactive **End Date:** 1/1/1953

Description: The 241-ER-151 Diversion Box and the 241-ER-311 and 241-ER-311A Catch Tanks are located inside a chain link fence that is radiologically posted. A WIDS sign has been placed at the approximate location of the release.

Location: The release occurred adjacent to the 241-ER-151 Diversion Box, southwest of the 221-B

Building.

Release Description: This release occurred in March 1953. Contaminated acid leaked to the ground from the 241-ER-311(A) Catch Tank. At the time of the event, no ground surface contamination was detected.

Related Sites/Structures: The UPR-200-E-84 is associated with the 241-ER-311A Catch Tank and the 241-ER-151 Diversion Box.

Process Description: The original (241-ER-311) Catch Tank was replaced in 1953. The replacement tank was named 241-ER-311. The original catch tank was re-numbered as 241-ER-311A. Both catch tanks received drainage from the 241-ER-151 Diversion Box.

Waste Type: Process Effluent

Waste Description: The release consisted of contaminated acid with approximately 10 curies of fission products from the 241-ER-311(A) Catch Tank.

Code: UPR-200-E-145 **Classification:** Accepted

Names: UPR-200-E-145; VCP Pipeline Leak; W049H Green Soil **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1993

Status: Inactive **End Date:**

Description: The site currently is a flat, disturbed area, with no vegetation. The area is covered with sandy soil and some rocks and gravel. The release was identified in a pipeline excavation that was oriented north to south. The north end of the excavation was located at a power pole with a blue air sample cabinet. In December 2003, growing contaminated tumbleweeds were found on the surface of this underground pipeline. The weeds were removed and the surface was stabilized. An area measuring approximately 3 meters by 6 meters (10 feet by 20 feet) is posted with Underground Radioactive Material signs.

Location: The site is east of the 241-A Tank Farm entrance, northeast of the 242-A Evaporator Building, and east of Canton Avenue. The coordinates of the excavation were E575490, N136130 on the north end and E575490, N136118 on the south end. H-2-140342 shows a polygon called Deep Rad Zone that is most like the correct location for this release.

Release Description: In 1993, while excavating for the installation of a new pipeline (Project W-049H) and exposing existing utility lines, contaminated soil with a radiological reading of 300,000 disintegrations/minute beta-gamma was detected at a depth of 0.8 meter (2.5 feet). The contamination was found above an existing 38 centimeter (15 inch) vitrified clay pipe, which was suspected to be the source.

Related Sites/Structures: The 38 centimeter (15 inch) vitrified clay pipe is 200-E-166-PL, feeding the 216-A-34 trench.

Process Description: Leakage from the 38 centimeter (15 inch) vitrified clay pipe is the suspected cause of soil contamination. A 38 centimeter (15 inch) pipe runs east to west at this location that was connected to the 216-A-34 crib.

Waste Type: Soil

Waste Description: Contaminated soil reading 300,000 disintegrations per minute of beta/gamma was found in an excavation, above a buried vitrified clay pipeline. The pipeline carried waste from the 216-A-8 Proportional Sample Pit #2 to the 216-A-34 crib. The contaminated soil read 300,000 disintegrations per minute with a GM/P-11 probe instrument. Sample results indicate the contamination was primarily due to uranium oxide from past practices on the Hanford site.

Code:	UPR-200-W-2	Classification:	Accepted
Names:	UPR-200-W-2; UN-200-W-2; Underground Waste Line Leak	Reclassification	None
Type:	Unplanned Release	Start Date:	1/1/1947
Status:	Inactive	End Date:	
Description:	The area around stairwell R-19 at the 221-T facility is currently paved with asphalt. A long, narrow Underground Radioactive Material area is posted around the R-19 area.		
Location:	The cave-in occurred on the southeast side of the 221-T facility, near stairwell R-19.		
Release Description:	On June 23, 1947, a minor ground cave-in occurred at the rear of the T-Plant Canyon Building opposite the R-19 stairwell and directly over one of the underground waste transfer lines. Gross soil contamination levels were found 3 to 3.3 meters (10 to 11 feet) beneath the surface confirming the presence of a leak in one or more of the underground process waste pipe lines. Plans were being formulated to establish the boundaries of the underground contamination at R-19 by the use of test holes. When this survey was completed (in 1947), temporary "danger zone" status was eliminated and a permanent danger zone was established similar to the zone established at B Plant door R-3.		
Related Sites/ Structures:	This site is associated with 221-T and UPR-200-W-98. The pipeline associated with this leak may have been 200-W-132-PL.		
Process Description:	The monthly report for June 1947 states that this is the third documented failure of underground metal waste lines. Operations were stopped as soon as practical and an excavation of the cave-in site was made under careful survey control of the Health Instruments group. Gross soil contamination was found 3 meters (10 feet) below the surface, confirming the presence of one or more leaks in the underground process piping.		
Waste Type:	Process Effluent		
Waste Description:	Hydrostatic tests showed that the 9-1 "metal waste line" had failed and discharged liquid waste to ground. No quantity or physical description of waste in references.		

Code:	UPR-200-W-5	Classification:	Accepted
Names:	UPR-200-W-5; Overflow at 241-TX-155; UN-200-W-5	Reclassification	None
Type:	Unplanned Release	Start Date:	1/1/1950
Status:	Inactive	End Date:	1/1/1950
Description:	The release is marked with a single WIDS sign. In 2000 and 2001 multiple areas of soil and vegetation contamination were identified and all were posted. For consolidation purposes, all of the new Contamination Areas were recorded and mapped as UPR-200-W-113. A WIDS sign has been placed at the approximate location of the release.		
Location:	The site consists of the 241-TX-155 diversion box and the adjacent hillside to the west. The diversion box is located east of Camden Ave., east of the 241-TX Tank Farm.		
Release Description:	In 1950, the 241-TX-155 Diversion Box overflowed and ran down the hillside to the west, contaminating the soil. No information related of the approximate radioactive contamination levels that spilled to the ground is available.		
Related Sites/ Structures:	The site is associated with the 241-TX-155 diversion box, UPR-200-W-28, UPR-200-W-131 and UPR-200-W-113.		

Process Description: The diversion box was constructed in 1949 and used to transfer waste solutions to and from various processing and decontamination facilities.

Waste Type: Process Effluent

Waste Description: The diversion box contained tank farm waste. No volume was recorded for the overflow.

Code: UPR-200-W-6 **Classification:** Accepted

Names: UPR-200-W-6; Contamination Spread from 241-U-151 and 241-U-152 Diversion Boxes; UN-200-W-6 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1950

Status: Inactive **End Date:**

Description: The ground around the 241-U-151 and the 241-U-152 Diversion Boxes has been covered with gravel. The diversion boxes are marked and posted. A WIDS sign has been placed at the approximate location of the release.

Location: The contamination spread occurred at the 241-U-151 and 241-U-152 Diversion Boxes, located east of the 241-U Tank Farm, near the corner of 16th and Camden.

Release Description: During the spring of 1950, work being done at the 241-U-151 and 241-U-152 Diversion Boxes resulted in contamination to the ground around the diversion boxes. The maximum dose rate was 20 millirad per hour on the surface of the soil.

Related Sites/Structures: The release is associated with the 241-U-151 and 241-U-152 Diversion Boxes.

Waste Type: Process Effluent

Waste Description: While working in the 241-U-151 and 241-U-152 Diversion Boxes, loose particulate beta/gamma contamination, with a maximum dose rate of 20 millirads per hour, spread to the soil surrounding the diversion boxes.

Code: UPR-200-W-28 **Classification:** Accepted

Names: UPR-200-W-28; Release from 241-TX-155 Diversion Box; UN-200-W-28 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1954

Status: Inactive **End Date:**

Description: The release is marked with a single WIDS sign. The documented contaminated area occurred west of the 241-TX-155 diversion box. There is a large posted Underground Radioactive Material area west of the diversion box (UPR-200-W-113) and several smaller radiologically posted areas in this vicinity (see UPR-200-W-135). A WIDS sign has been placed at the approximate location of the release.

Location: The release site is located adjacent to the 241-TX-155 Diversion Box, approximately 244 meters (800 feet) east of the 241-TX tank farm and north of the 200 West Area Powerhouse Pond.

Release Description: Contamination has spread from the 241-TX-155 Diversion Box to the surrounding ground at various times in the 1950's. In the spring of 1954, a leak occurred from a one of the jumpers in 241-TX-155 Diversion Box causing the area to the west of the diversion box to become

contaminated (see UPR-200-W-135). The area was covered with clean soil and temporarily posted as a radiation zone. The original fence and signs from 1954 are no longer present.

Related Sites/ Structures: The release is associated with the 241-TX-155 Diversion Box and UPR-200-W-5, UPR-200-W-113, UPR-200-W-131 and UPR-200-W-135.

Process Description: The diversion box was constructed in 1949 and used to transfer waste solutions to and from various processing and decontamination facilities. Multiple releases have occurred at the diversion box and its related underground pipelines.

Waste Type: Process Effluent

Waste Description: Multiple releases from the 241-TX-155 Diversion Box and its associated underground pipelines has resulted in contamination being found in the soil in this vicinity. The contaminated area reference in HW-60807 was given an Unplanned Release number. However, the reference is describing an area where several release events occurred and not a particular event.

Code: UPR-200-W-29 **Classification:** Accepted

Names: UPR-200-W-29; 23rd and Camden Line Break; Transfer Line Leak; UN-200-W-27; UN-200-W-29; UN-216-W-5; UPR-200-W-27 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1954

Status: Inactive **End Date:**

Description: The area is currently surrounded with steel posts, covered with gravel and posted as an Underground Radioactive Material Area.

Location: The site is located at the southeast corner of the intersection of Camden Street and 23rd Street.

Release Description: On November 15, 1954, a broken, underground process line leading from the 241-T-152 Diversion Box to the 241-TX-153 Diversion Box caused a small cave-in (located 23 meters south of 23rd Street and 23 meters east of Camden Ave) over the pipeline. Run off from the release contaminated an area along the east side of Camden Street. An uncased, underground pipeline was being used to transport first cycle waste from the 241-T-105 tank to the 241-TX-118 tank for 242-T Evaporator processing. The waste transfer was begun around 2:45 pm on November 15, 1954, but was discontinued at 11:30 pm due to a leaking jumper. The cave in and waste runoff was not discovered until 10:00 am on November 16, 1954. A maximum dose rate of 11.5 rad per hour, at a distance of 5 centimeters (2 inches), was found over the run off area. It was calculated that less than 3,800 liters (1,000 gallons) of waste actually escaped from the line.

Related Sites/ Structures: The release is associated with the 241-T-152 Diversion Box, UPR-200-W-64 and UPR-200-W-97. Pipelines 200-W-79-PL, 200-W-130-PL and 200-W-167-PL cross inside the radiologically posted area.

Waste Type: Process Effluent

Waste Description: The release consisted of first-cycle supernatant containing rare earth metals plus yttrium, cesium, antimony, cerium, ruthenium, niobium, and tellurium. Dose rates up to 11.5 rad per hour at 5 centimeters (2 inches), including 3.5 rad per hour, was measured over the run-off and fields up to 4.5 rad per hour at a distance of 0.9 meters (3 feet) near the cave-in was found. Less than 3,800 liters (1,000 gallons) of waste were estimated to have escaped from the line.

Code: UPR-200-W-32 **Classification:** Accepted

Names: UPR-200-W-32; UN-200-W-32; UNH Transfer **Reclassification:** None

Line Break**Type:** Unplanned Release**Start Date:** 1/1/1954**Status:** Inactive**End Date:****Description:** The release site is not currently marked or posted. The above ground pipeline has been removed.**Location:** The release occurred near the northwest corner of the REDOX exclusion in 1954.**Release Description:** During the summer of 1954, the above ground uranyl nitrate hexahydrate (UNH) transfer line connecting 224-U to REDOX broke, released an unknown amount of the UNH solution to the ground. The contaminated area was covered and marked as a radiation zone by use of magenta and yellow tape and radiation zone signs.**Related Sites/ Structures:** The site is associated with the 204-S facility.**Waste Type:** Chemicals**Waste Description:** Soil contamination occurred when an unknown amount of uranyl nitrate hexahydrate (UNH) solution leaked from a leak in an above ground pipeline.

Code: UPR-200-W-35**Classification:** Accepted**Names:** UPR-200-W-35; Ground Contamination Near UNH Process Line; REDOX to 224-U UNH Line Leak; UN-200-W-35**Reclassification:** None**Type:** Unplanned Release**Start Date:** 1/1/1955**Status:** Inactive**End Date:****Description:** Much of the area north of REDOX has been surface stabilized. The unplanned release site is not marked or posted.**Location:** The site was located along the above ground uranyl nitrate hexahydrate (UNH) process line, that ran from REDOX to U Plant, at a location just outside and to the north of the REDOX exclusion area.**Release Description:** In September 1955, a leak occurred in the above ground uranyl nitrate hexahydrate (UNH) line from REDOX to U Plant. The area of surface contamination and the quantity or activity of contaminants were not mentioned in reference material.**Waste Type:** Chemicals**Waste Description:** The waste is described as an unknown amount and concentration/activity of uranyl nitrate hexahydrate (UNH) solution being routed from the Reduction Oxidation (REDOX) facility to the U Plant.

Code: UPR-200-W-38**Classification:** Accepted**Names:** UPR-200-W-38; UPR-200-W-40; 216-T-30; Line Break at 241-TX-302C; UN-200-W-38; UPR-200-W-160**Reclassification:** None**Type:** Unplanned Release**Start Date:** 1/1/1955**Status:** Inactive**End Date:** 1/1/1955

Description: The area around the 241-TX-154 diversion box and the catch tank has been stabilized with sprayed concrete (shotcrete). The area is posted with Underground Radioactive Material signs. A WIDS sign has been placed at this location.

Location: The release occurred on the southeast side of T Plant (221-T), between the 241-TX-154 Diversion Box and the 241-TX-302 Catch Tank. The liquid release affected a large area between the 221-T and 222-T buildings.

Release Description: On December 30, 1955, a failure of an underground transfer line between the 241-TX-154 diversion box and the 241-TX-302 catch tank flooded an area approximately 139.35 square meters (1500 square feet) with radioactive metal waste solution. Contamination was spread during cleanup activities and increased the size of the contamination area to approximately 371.6 square meters (4,000 square feet). The incident report indicates that the volume of metal waste involved "appeared to be in the magnitude of several thousand gallons". Prior to this incident, the area had been covered with asphalt because of a previous contamination spread. The liquid was forced up through several feet of soil and pooled on top of this asphalt. An unreported thickness of soil was backfilled onto the area to prevent further contamination spread. It is reported that a hose with 33 rads/hour contamination was buried in the backfill. Additional asphalt was to be laid on top of the fill for contamination control.

Related Sites/Structures: The release is associated with the 241-TX-154 Diversion Box and the 241-TX-302C Catch Tank. UPR-200-W-21 occurred in the same vicinity in 1953.

Process Description: The 241-TX-302C Catch Tank collects drainage from the 241-TX-154 Diversion Box.

Waste Type: Process Effluent

Waste Description: The 1955 release of liquid metal waste produced beta/gamma with a dose rate of 100 rad per hour at a distance of 1 foot (0.3 meters) above the contamination pool. Several thousand gallons of waste was lost to the ground. HW-60807 estimated the release to be 7520 liters (2000 gallons) RHO-CD-673 estimated 19,000 liters (5026 gallons). The waste was high in salt and is neutral to basic. The initial surface pool of liquid was estimated to be 9 meters (30 feet) by 4.5 meters (15 feet).

Code: UPR-200-W-64 **Classification:** Accepted

Names: UPR-200-W-64; Road Contamination at 23rd and Camden; UN-200-W-64 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1969

Status: Inactive **End Date:**

Description: The corner of 23rd and Camden has been stabilized with clean gravel due to two waste line leak events. The stabilized area is surrounded with chain and posted with Underground Radioactive Material signs. The road shoulders are not posted. A WIDS sign has been placed at the approximate location of the release.

Location: The release is located between the east shoulder of Camden Avenue and the posted Underground Radioactive Material area (UPR-200-W-29/UPR-200-W-97), near the corner of 23rd Street and Camden Ave.

Release Description: On February 13, 1969, contamination up to 600 counts per minute was found in mud samples next to Camden Avenue. The contamination was found to be on the shoulder of the roadway, but no detectable contamination was found on the road blacktop. It is believed that the contamination source was the adjacent radiation zone (UPR-200-W-29 and UPR-200-W-97) where two previous underground radioactive waste line leaks that occurred. Runoff from heavy snow may have caused the contamination movement. Dirt samples from the radiation zone to

the east and roadway shoulder samples showed cesium-137 to be the only detectable radioactive isotope.

Related Sites/ Structures: UPR-200-W-29 and UPR-200-W-97 are the apparent source of contamination for this release.

Waste Type: Process Effluent

Waste Description: Mud samples collected in 1969 contained mostly cesium-137, with readings up to 600 counts per minute. No volume estimate was provide. The contamination source appears to be rain water run off from the adjacent area where two process line leaks occurred (see UPR-200-W-29 and UPR-200-W-97). The line leaks included first-cycle supernatant containing rare earth metals plus yttrium, cesium, antimony, cerium, ruthenium, niobium, and tellurium.

Code: UPR-200-W-97 **Classification:** Accepted

Names: UPR-200-W-97; Transfer Line Leak; UN-200-W-97; UN-216-W-5 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1966

Status: Inactive **End Date:** 1/1/1966

Description: The site is located at the corner of 23rd Street and Camden Ave. It is marked and posted as "Underground Radioactive Material". The release site was stabilized with clean soil, sand, ureabore herbicide, and crushed rock.

Location: The release occurred southeast of the 241-T Tank Farm at the corner of 23rd Street and Camden Avenue.

Release Description: In May 1966, liquid waste surfaced and ran to the edge of Camden Avenue. This is the same location of UPR-200-W-29, a waste transfer line break that occurred in 1954. This release occurred when the broken waste line was mistakenly tested, causing liquid waste to surface again.

Related Sites/ Structures: UPR-200-W-97 is associated with the underground pipeline connecting 241-T-152 Diversion Box and the 241-TX-153 Diversion Box. It occurred at the same location as UPR-200-W-29 and adjacent to UPR-200-W-64. The site is associated with UPR-200-W-29 because a repeat release from the same broken transfer line (documented in UPR-200-W-29 in 1954) occurred again in 1966.

Waste Type: Process Effluent

Waste Description: The waste released to the soil consisted of a high salt, neutral to basic liquid tank waste solution containing approximately 10 curies of fission products. The waste consisted of second cycle bismuth phosphate waste from the 241-T-107 tank. The maximum surface dose rate was 5 rad per hour beta/gamma with 3 rad per hour being gamma radiation.

Code: UPR-200-W-98 **Classification:** Accepted

Names: UPR-200-W-98; 221-T Waste Line Break at R-19; UN-200-W-98; UN-216-W-6 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1945

Status: Inactive **End Date:** 1/1/1945

Description: The area around door R-19 is paved with asphalt and posted as an Underground Radioactive Material area. There is not a sign that specifically marks the area as an unplanned release site.

Location: The release site is located near the southeast corner of the 221-T Canyon Building, at door R-19.

Release Description: In the spring of 1945, a leak occurred in an underground metal waste transfer line. The liquid surfaced and spread mixed fission contamination over a small surface area of ground.

Related Sites/ Structures: UPR-200-W-98 was associated with underground pipelines near the R-19 section of the 221-T Canyon Building and UPR-200-W-2.

Process Description: Underground pipelines carried T Plant process material and waste to various destinations. More than one pipeline leak occurred in this area.

Waste Type: Process Effluent

Waste Description: A broken underground process transfer line caused contaminated liquid to surface near R-19 at 221-T. The "metal waste" line contained approximately 10 curies of high salt, neutral to basic fission products with a maximum dose rate of 20 rad per hour at 2 inches (5 centimeters).

Code: UPR-200-W-102	Classification: Accepted
Names: UPR-200-W-102; 224-T Underground Line Leak; UN-200-W-102; UN-216-W-12	Reclassification: None
Type: Unplanned Release	Start Date: 1/1/1972
Status: Inactive	End Date: 1/1/1972

Description: The east and south sides of the 224-T Building are covered with gravel. The area along the east side of the 224-T building is posted as an Underground Radioactive Material area.

Location: UPR-200-W-102 occurred adjacent to the south and east sides of the 224-T Building.

Release Description: During the remodeling of the 224-T Building, gross alpha contamination was found in the soil on the back side of the building. This contamination is believed to have come from alpha-laden moisture that seeped through pipe joints from underground process tank vent lines during the years of process operation.

Related Sites/ Structures: UPR-200-W-102 is associated with underground process lines at the 224-T Building. See 200-W-226-PL.

Waste Type: Process Effluent

Waste Description: The release consisted of alpha-laden moisture from process tank lines that contaminated the soil around the pipeline. An estimated 72 grams of plutonium was contained in the contaminated soil that was removed when the leak was discovered.

Code: UPR-200-W-108	Classification: Accepted
Names: UPR-200-W-108; Line Leak at 216-S-9 Crib; UN-200-W-108; UN-216-W-18	Reclassification: None
Type: Unplanned Release	Start Date: 1/1/1969
Status: Inactive	End Date: 1/1/1969

Description: The release site is posted as a "Surface Contamination Area". The excavation was filled after the work was completed.

Location: UPR-200-W-108 occurred at the junction of the 216-S-9 and 216-S-23 Crib Liners, south of the 216-S-9 Crib and approximately 61 meters (200 feet) north of Thirteenth Street.

Release Description: On January 8, 1969, during the tie-in of the 216-S-9 Crib waste line to the new 216-S-23 Crib, contaminated water was encountered coming from a break at the junction of the two crib lines. Further excavation disclosed a severe expansion buckle in the line at that point, and a similar buckle in the line near the 202-S Building. There is no way of determining how long the line had been leaking or how much waste was discharged to the ground.

Related Sites/Structures: UPR-200-W-108 was associated with pipeline 200-W-139-PL, the 216-S-9 Crib, the REDOX D-2 Receiver Tank, the 240-S-151 Diversion Box, the 216-S-23 Crib and UPR-200-W-109.

Waste Type: Process Effluent

Waste Description: The waste was REDOX process condensate from the D-2 Receiver Tank in the 202-S Building with beta and gamma contamination and dose rate readings of 40 rads/hour at the bottom of the waste line.

Code: UPR-200-W-109 **Classification:** Accepted

Names: UPR-200-W-109; Waste Line Leak Near 218-W-9; UN-200-W-109; UN-216-W-19 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1969

Status: Inactive **End Date:** 1/1/1969

Description: The release was a transfer line break that occurred within the east chain barricade of the 218-W-9 Burial Ground. The 218-W-9 Area was interim stabilized in 1991 with 46 to 61 centimeters (18 to 24 inches) of uncontaminated backfill. The release site was covered with soil and revegetated along with 218-W-9.

Location: UPR-200-W-109 occurred just inside the east perimeter chain of the 218-W-9 Burial Ground, south of which is located north of the 216-S-7 Crib in 200 West Area.

Release Description: UPR-200-W-109 is related to the UPR-200-W-108 incident. After repairing the initial buckled portions of the waste line, a pressure test indicated another leak in the line at some point upstream toward the 202-S Building. Further excavation and pressure testing finally determined a leak to be somewhere between the first discovered leak and the northwest corner of the REDOX area fence. Additional hydrostatic testing finally forced water to bubble to the ground surface. Excavation of the bubble site disclosed a vertical buckling of the pipeline with a sizable break in the line. The buckled and broken waste transfer line was from the 240-S Diversion Box. Dose rates on the liquid were 450 millirads per hour, but as the liquid sank into the ground, the dose rate dropped to 20 millirem per hour.

Related Sites/Structures: UPR-200-W-109 is associated with the 218-W-9 Burial Ground, UPR-200-W-108, 216-S-7, 216-S-23, the D-2 Receiver Tank in the 202-S Building, and the 240-S Diversion Box.

Waste Type: Process Effluent

Waste Description: The waste was process condensate containing acidic unknown beta and gamma contamination. It came from the D-2 Receiver Tank in the 202-S Building. Dose rates of the liquid were 450 millirads/hour at the surface. As the water sank back into the ground, surface dose rates dropped to 20 millirads/hour.

Code: UPR-200-W-113 **Classification:** Accepted

Names: UPR-200-W-113; Contamination Areas Around 241-TX-155 Diversion Box; Soil Contamination East of 241-TX; UN-200-W-113; UN-216-W-23 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1977

Status: Inactive**End Date:**

Description: The original contaminated area was surface stabilized in 1990. It is currently surrounded with concrete marker posts and posted as an Underground Radioactive Material area. In 1998, 1999 and 2000 additional surface contamination was identified in the vicinity of the original surface stabilized area. Smaller contamination areas on the north, south, east and west sides of the 241-TX-152 and 241-TX-155 diversion boxes. At that time, the additional contamination areas were considered extensions of UPR-200-W-113. Many of the contamination areas were found above underground transfer lines going into and out of the 241-TX-155 Diversion Box. They were originally labeled with UPR-200-W-113 signs. Some of the "UPR-200-W-113" signs are being replaced as more information is documented that ties posted contamination areas with other documented Unplanned Releases and pipeline sites that were added to WIDS in 2007.

Location: The site is an area east of the 241-TX Tank Farm, on the east side of Camden Ave. Several radiological posted, labeled UPR-200-W-113, areas are located north, south, west and east of the 241-TX-155 and 241-TX-152 Diversion Boxes.

Release Description: The original unplanned release description stated that during the spring and summer months of 1977, contaminated rabbit feces were found near the 241-TX-155 Diversion Box, prompting an extensive survey to determine the source of radioactive rabbit food. During this survey, low-level, beta/gamma ground surface contamination was found on the hillside below and to the west of the 241-TX-155 Diversion Box. As soil was removed in the attempt to decontaminate the site, radioactivity increased until it was evident that the source of contamination was subsurface, possibly an old leak from a nearby waste transfer line. In August 1977, Unusual Occurrence Report 77-180 was issued, documenting the contaminated rabbit feces problem. This discovery is also detailed in UPR-200-W-76.

Related Sites/Structures: The site is associated with the 241-TX-155 Diversion Box, 241-TX-152, UPR-200-W-28, UPR-200-W-76, UPR-200-W-135 and associated underground pipelines going into and out of the 241-TX-152 and 241-TX-155 diversion boxes.

Process Description: Underground pipelines transferred tank waste between tank farms through diversion boxes. Many pipelines leaked, allowing plant and animal intrusion to spread contamination to the surface.

Waste Type: Animal Waste

Waste Description: Contaminated animal feces and growing contaminated vegetation have been found in this area. The biological uptake is the result of multiple releases in this area associated with the 241-TX-155 Diversion Box and its underground pipelines.

Code: UPR-200-W-114**Classification:** Accepted**Names:** UPR-200-W-114; Ground Contamination East of 241-SX Tank Farm; UN-200-W-114; UN-216-W-24**Reclassification:** None**Type:** Unplanned Release**Start Date:****Status:** Inactive**End Date:**

Description: This site is no longer marked or posted. The release site had been a large area posted with a light chain and Surface Contamination Area signs. The 216-S-8, the 216-S-1, and the 216-S-2 cribs were located within this larger contamination zone. In 1992 through 1993, the surface contamination was scraped up and consolidated into other nearby waste sites (216-S-1 & 2, 216-S-8 and 207-S).

Location: UPR-200-W-114 was located east of the 241-SX Tank Farm, south of the steam line.

Release Description: The site consisted of migrating radioactive particulate matter from operational activities at the 241-SX Tank Farm and the 241-SX-151 and 241-S-151 Diversion Boxes over many years. The contamination spread to the ground surface east of the 241-SX Tank Farm. The resulting large posted Surface Contamination Area (SCA) was assigned an unplanned release number in 1980. The area was expanded to approximately 11.9 acres.

Related Sites/ Structures: UPR-200-W-114 was associated with multiple releases from operation activities in the 241-SX Tank Farm, and the 241-SX-151 and 241-S-151 Diversion Boxes. Documented operational releases extending eastward from the tank farm include UPR-200-W-20, UPR-200-W-49, UPR-200-W-50, UPR-200-W-51, UPR-200-W-52, and UPR-200-W-82. It was remediated in conjunction with the adjacent UPR-200-W-165 site.

Waste Type: Soil

Waste Description: The waste consisted of radioactive particulate matter from operational activities in the adjacent 241-S/SX Tank Farms.

Code: UPR-200-W-115 **Classification:** Accepted

Names: UPR-200-W-115; Ground Contamination Above Transfer Line Along Cooper Street; UN-216-W-25 **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The site had been delineated with light chain barricade and Surface Contamination warning signs. A waste site inspection, done in February 1998, found the area has been covered with gravel and posted as an Underground Radioactive Material area.

Location: UPR-200-W-115 is located above the encased transfer line that runs along the east side of Cooper Street. The pipeline (sitecode 200-W-179-PL) extends between the 242-S Evaporator Facility and the 241-U Tank Farm.

Release Description: The release refers to the radiologically posted soil above the underground, encased transfer line that runs from the 242-S Evaporator Building to the 241-U Tank Farm. In 1981, Harold Maxfield stated that he believed the area was incorrectly designated as an unplanned release. He based his opinion on a radiation survey performed on October 7, 1981. The survey report indicated the soil and the surface features of the pipeline (Clean Out Boxes) were free of removable contamination. The report stated the only radiation detected was a dose rate emitting from the Clean Out Boxes. There was no evidence of loss of radiological control at that time.

Related Sites/ Structures: The release site was associated with the encased transfer lines from the 242-S Evaporator Building to 241-U. The pipelines associated with this release are discussed in sitecode 200-W-179-PL.

Process Description: The site is considered to be the soil above an encased transfer line extending from the 242-S Evaporator to the 241-U Tank Farm. The pipeline is equipped with a series of Clean Out Boxes (COBs) along the length of the line to allow access into the pipeline.

Waste Type: Soil

Waste Description: The soil was contaminated with material from the transfer line Clean Out Boxes.

Code: UPR-200-W-130 **Classification:** Accepted

Names: UPR-200-W-130; Line Leak at 231-W-151 **Reclassification:** None

Sump; UN-200-W-130

Type: Unplanned Release **Start Date:** 1/1/1967

Status: Inactive **End Date:** 1/1/1967

Description: A WIDS sign has been placed at the approximate location of the release.

Location: UPR-200-W-130 occurred in the soil on the east side of the 231-W-151 Sump, near the 231-Z Building.

Release Description: While hand excavating to uncover a waste line adjacent to the 231-W-151 Diversion Box, contamination was detected in the soil. The soil adjacent to the waste line contained 40,000 disintegrations per minute alpha contamination, and 150 millirem per hour beta/gamma contamination. The release was due to a leaking flange. The dose rate on the waste line was 1.5 rad per hour.

Related Sites/ Structures: UPR-200-W-130 was associated with a waste line, the 231-W-151 Sump and the 231-Z Building.

Waste Type: Process Effluent

Waste Description: The soil had alpha readings up to 40,000 disintegrations per minute, with dose rates of 100 millirem/hour of beta and 50 millirem/hour of gamma.

Code: UPR-200-W-131 **Classification:** Accepted

Names: UPR-200-W-131; Release from 241-TX-155 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1953

Status: Inactive **End Date:** 1/1/1953

Description: The 241-TX-155 Diversion Box and 241-TX-302B Catch Tank are surrounded with post and chain. Clean gravel has been placed around the diversion box with Underground Radioactive Material and Bio Barrier signs. A single, UPR-200-W-131 WIDS sign is attached to the chain boundary.

Location: The release occurred near the 241-TX-155 Diversion Box, located east of Camden Ave. and east of the 241-TX Tank Farm.

Release Description: In 1953, a severe leak in the tri-butyl phosphate (TBP) feed jumper caused the catch tank to become full. It was necessary to pump the liquid out of the catch tank via an overground line to the diversion box in order to empty the tank. The liquid in the tank was acidic. The first attempt to pump the tank caused a failure of the black iron pump. A decision was made to neutralize the solution with soda ash to prevent another pump failure. Two hundred pounds of soda ash was carefully added to the catch tank. While flushing the soda ash with water, a fine stream of solution erupted out of the 2.5 centimeter (one inch) electrode riser, causing ground contamination with a dose rate of 6 rad per hour. After plugging the riser, another bag of soda ash was added to a 30 centimeter (12 inch) riser. A foamy solution percolated out this riser and a different (10 centimeter) riser, causing ground contamination with readings of 25 rad per hour at a distance of 0.6 meters (2 feet). No further attempts were made to continue neutralizing or to empty the catch tank. (The release occurred in March 1953. Information related to the Catch Tanks indicate 241-302BR was damaged by acid and replaced with 241-TX-302B)

Related Sites/ Structures: The release is associated with the 241-TX-155 Diversion Box, the 241-TX-302 Catch Tank and UPR-200-W-113.

Waste Type: Process Effluent

Waste Description: The release consisted of a dilute acidic waste solution. Ground contamination up to 25 rad per hour at 0.6 meters (2 feet) was observed.

Code: UPR-200-W-135 **Classification:** Accepted
Names: UPR-200-W-135; Release from 241-TX-155; UN-200-W-135 **Reclassification:** None
Type: Unplanned Release **Start Date:** 1/1/1954
Status: Inactive **End Date:** 1/1/1954

Description: There are three major encased transfer lines associated with the 241-TX-155 Diversion Box. There have been many areas of contamination identified on these transfer lines during 1999, 2000 and 2001. UPR-200-W-135 is located on transfer line 200-W-191-PL, directly west of the 241-TX-155 Diversion Box. It is surrounded with concrete marker posts and Underground Radioactive Material signs. A single metal post, labeled UPR-200-W-135, has been placed adjacent to the Contamination Area. Other signs surrounding the area are labeled UPR-200-W-113.

Location: The oval, posted Underground Radioactive Material Area associated with UPR-200-W-135 is located approximately 46 meters (150 feet) northwest of the 241-TX-155 Diversion Box. The diversion box is located east of Camden Ave and east of the 241-TX Tank Farm.

Release Description: While preparing to begin the 241-TX-302B catch tank replacement job near the 241-TX-155 Diversion Box, elevated dose rates were noticed in the area. The dose rate increased as the investigator descended the hill, moving away from the diversion box. A cave-in, with a diameter of 0.61 meters (2 feet), was noted along the encased pipeline (200-W-191-PL) that connects the 241-TX-155 Diversion Box to the 241-TY Tank Farm. A jumper connection in the diversion box had apparently failed and allowed liquid collect inside the diversion box and drain to the catch tank. The catch tank had a known leak. The liquid leaked out of the catch tank and flowed along the pipeline encasement that caused a visual soil cave-in approximately 46 meters (150 feet) down hill from the diversion box. The cave-in area measured approximately 0.6 meters (2 feet) in diameter. A liquid run off path was noted that measured approximately 12 meters (40 feet) long. The dose rate from the leaking process effluent was 5 rad per hour at a distance of 1 meter (3 feet). It was estimated to be 300 rad per hour at a distance of 10 centimeters (4 inches).

Related Sites/Structures: UPR-200-W-135 is associated with the 241-TX-155 Diversion Box, 241-TX-302B Catch Tank and pipeline 200-W-191-PL.

Waste Type: Process Effluent

Waste Description: The leaking connector (U-15) associated with this release was transferring blended metal waste supernatant from the 244-UR vault to the 241-WR vault when the leak occurred. The amount of liquid released is estimated, since the cave-in was discovered 10 days after the last transfer was made.

Code: UPR-200-W-161 **Classification:** Accepted
Names: UPR-200-W-161; Large Area East of 241-U Tank Farm; UN-200-W-161; UN-216-W-35 **Reclassification:** None
Type: Unplanned Release **Start Date:** 1/1/1990
Status: Inactive **End Date:**

Description: The site is a large radiologically controlled area posted with Underground Radioactive Material

signs. A WIDS number sign has been posted at this location.

Location: The site is located east of 241-U Tank Farm, on the east side of Camden Ave. It extends northward from the corner of 16th Street and Camden Ave. and the 241-U-152 Diversion Box.

Release Description: During a January 12, 1990 radiation survey, an area of approximately 1.9 acres (0.77 hectares) east of the 241-U Tank Farm (and west of the 216-U-14 Ditch) was found to be contaminated. The general contamination was 250 to 450 counts per minute with spots of 600 to 800 counts per minute. One area, approximately 1.5 meters (5 feet) long by 1.5 meters (5 feet) wide, was contaminated up to 8,000 counts per minute. No Occurrence Report was issued, but the area was submitted to the WIDS database on 3-23-90 as an Unplanned Release Site and given the number UN-216-W-35.

Related Sites/Structures: UPR-200-W-161 is associated with the 241-U Tank Farm. Two pipelines associated with tank farm operations are buried in this approximate location (see 200-W-130-PL and 200-W-182-PL).

Waste Type: Soil

Waste Description: Windblown contaminated particles effected the area east of 241-U tank farm. Soil sample results from 1990 indicate that the main radionuclide is strontium (2.93 E3 picocuries per gram). Other contaminants included 6.26 picocuries per gram of cesium-137, 3.27 picocuries per gram of plutonium and 2.6 E-07 grams per gram of uranium. Because this site is associated with the 241-U Tank Farm, the waste is assumed to be mixed waste.

Code: UPR-200-W-164 **Classification:** Accepted

Names: UPR-200-W-164; Overhead UNH Line Leak; UN-216-W-29 **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The above ground UNH line has been removed. The Radiation Area signs that surrounded the pipeline were also removed. A portion of the site was interim stabilized in 1993. An area of contaminated soil found under the steam line, adjacent to the 216-S-9 crib, was covered with clean soil and posted with "Underground Radioactive Material" warning signs.

Location: UPR-200-W-164 effect the soil beneath the aboveground uranyl nitrate hexahydrate (UNH) pipeline that extended from 204-S to 224-U. The UNH line was attached to a steam line, located north of 204-S.

Release Description: The above ground uranyl nitrate hexahydrate transfer line that extended from the 204-S Storage Tanks to the 224-U Building (hung from an existing steam line) was posted as a radiation zone from 1952 to 1967. The zone was established because of a low-level gamma field (dose rate) emanating from the transfer line. The September 1981 correspondence from Harold Maxfield states he believes the area was incorrectly designated as an Unplanned Release, because the posting was necessary due to a dose rate condition and not a release. Later, a small area of soil contamination was identified under the steam line, adjacent to the 216-S-9 crib.

Related Sites/Structures: UPR-200-W-164 was associated with the above ground UNH transfer line from the 204-S Storage Tanks to the 224-U Building.

Process Description: The unplanned release site was an area of soil beneath an above ground uranyl nitrate hexahydrate transfer line that was hung from existing steam pipes.

Waste Type: Soil

Waste Description: The original Unplanned Release was described as the gamma field (dose rate) emanating from the above ground uranyl nitrate hexahydrate (UNH) transfer line. Later, a small area of soil contamination was found under the steam line that the above ground line had been attached. Liquid UNH apparently had dripped onto the soil on an area located adjacent to the 216-S-9 crib.

Code: UPR-200-W-167 **Classification:** Accepted

Names: UPR-200-W-167; Contamination Migration from 241-TY; UN-216-W-32 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1985

Status: Inactive **End Date:**

Description: The original release site, identified in 1985, was a soil contamination area located adjacent to the east side of the 241-TY Tank Farm. After the contamination was scraped and removed in 1986, the site was no longer marked or posted. Later, in 2000, three areas on the east and northeast sides of the 241-TY Tank Farm (within the original boundaries of this Unplanned Release) were reposted as Contamination Areas (CA). Contaminated ant hills and growing contaminated vegetation was found on top of a tank farm transfer line located outside the eastern tank farm fence (also see WIDS sitecode 200-W-78). In November 2000, the CA's were covered with bio-barrier material and gravel. These areas were reposted with Underground Radioactive Material signs. The underground radioactive pipeline is marked with posts and "Radioactive Pipeline" signs. The pipeline runs through the recently stabilized areas.

Location: UPR-200-W-167 was located adjacent to the 241-TY Tank Farm fence, extending east and north from the fence.

Release Description: In 1985 the contamination associated with UPR-200-W-167 was assumed to be the result of migration of contamination from 241-TY Tank Farm operations over a period of time.

Related Sites/ Structures: UPR-200-W-167 was associated with the 241-TY Tank Farm operations and WIDS sitecode 200-W-78.

Waste Type: Soil

Waste Description: The waste consisted of radioactive contamination (specks) that migrated from the 241-TY Tank Farm. Later, contaminated ant hills and contaminated vegetation were also found in this area.

200-OA-1

Code: 200 CP **Classification:** Accepted

Names: 200 CP; Hanford Site Gravel Pit 29; 200 Area Construction Pit; 200 Area Construction Waste Site **Reclassification:** None

Type: Depression/Pit (nonspecific) **Start Date:** 1/1/1945

Status: Inactive **End Date:** 1/1/1955

Description: The site is a large, open gravel area. The pit is no longer being used as a source of gravel. The 2704HV parking lot was placed over a portion of the original pit.

Location: The pit is located west of the west perimeter fence of 200 East Area and northwest of the 2704HV building.

Process Description: The pit has been used as a source of gravel for various Hanford projects. Several truck loads of nonhazardous solid waste, broken blocks of concrete foundation and other debris have been reported to have been placed in the pit over the years.

Waste Type: Construction Debris

Waste Description: Several truck loads of broken blocks of concrete foundations and other structures have been dumped into this gravel pit during the past several years. There have been no known chemicals dumped into this unit.

Code: 216-B-3-1 **Classification:** Accepted

Names: 216-B-3-1; B Swamp Ditch; 216-B-2; 216-B-2E; 216-B-3 Ditch **Reclassification:** None

Type: Ditch **Start Date:** 1/1/1945

Status: Inactive **End Date:** 1/1/1964

Description: The head end is located outside the 200 East perimeter fence, east of 218-E12A Burial Ground. The ditch continues due east to the 216-B-3 Pond. The constructed ditch was approximately 1250 feet long. It widened into a swamp before entering the 216-B-3 Pond. The site is currently backfilled and surface stabilized. It is located within a large posted Underground Radioactive Material area that also includes the 216-B-3-2 backfilled ditch.

Location: The ditch is located east of the 200 East Area perimeter fence.

Related Sites/Structures: The site is associated with B Plant and PUREX facilities, UPR-200-E-34 and 216-B-2-1. It was fed by the 200-E-126-PL pipeline.

Process Description: The ditch received B Plant effluent from the 216-B-2-1 ditch and Purex effluent via a diverter that divided the flow between Gable Pond and B Pond. The 216-A-29 Ditch entered the B Swamp near the east end of the 216-B-3-1 Ditch.

Waste Type: Process Effluent

Waste Description: Until March 1962, the site percolated and transported 221-B Plant steam condensate, process cooling water, chemical sewer waste, and 284-E Powerhouse waste. From March 1952 to November 1955, the site percolated and transported the above-listed streams plus 241-CR Vault cooling water. From November 1955 to December 1957, the site percolated and transported the above-listed streams plus effluent from 216-A-29 Ditch. Wastes include 202-A process cooling water and chemical sewer waste. From December 1957 to February 1958, the site percolated

and transported the above-listed streams minus 202-A process cooling water. From February 1958 to December 1962, the site percolated and transported the above-listed streams plus 202-A Acid Fractionator condensate. From December 1962 to December 1963, the site percolated and transported the above-listed streams plus 202-A seal cooling water from air sampler vacuum pumps. After December 1963, the site percolated and transported the above-listed streams minus 202-A seal cooling water.

Code:	216-B-3-2	Classification:	Accepted
Names:	216-B-3-2; B Swamp Ditch; 216-B Ditch; 216-B-1 Ditch; 216-B-2-2E	Reclassification	None
Type:	Ditch	Start Date:	1/1/1964
Status:	Inactive	End Date:	1/1/1970
Description:	The ditch has been backfilled and surface stabilized. It is located within a large Underground Radioactive Material Area that includes the 216-B-3-1, 216-B-3-2 and 216-B-3-3 covered ditches. The unit was open from the diverter station to the 216-B-3 Pond and was approximately 1.2 to 2.4 meters (4 to 8 feet) deep. It was backfilled in July 1970 after a release of strontium-90 from 221-B Plant.		
Location:	The ditch is located east of the 200 East Area perimeter fence. The ditch began east of the eastern 200 East Area perimeter fence and continued eastward to 216-B-3 Pond.		
Release Description:	UPR-200-E-138: On March 22, 1970, an estimated 1,000 curies strontium-90 release occurred at B Plant during an attempted measurement of the liquid level in Tank 8-1.		
Related Sites/Structures:	The site is associated with 216-B-2-2, 216-B-3 and UPR-200-E-138.		
Process Description:	The ditch received effluent from B Plant and PUREX and transported it to the 216-B-3 Main Pond.		
Waste Type:	Process Effluent		
Waste Description:	Until January 1965, the site transported 221-B Plant process cooling water, steam condensate, and chemical sewer; 241-CR Vault cooling water; 284-E Powerhouse water; and received and transported 202-A chemical sewer waste and fractionator condensate from 216-A-29 Ditch. From January 1965 to January 1966, the site transported the above mentioned streams plus 241-TY Tank Farm ITS Unit 1 condenser cooling water. From January 1966 to November 1967, the site transported the above mentioned streams plus condenser cooling water and air sampler vacuum pump seal cooling water from 202-A Building. From November 1967 to February 1968, the site transported the above mentioned streams minus 284-E Powerhouse wastewater. After February 1968, the site transported the above mentioned streams plus 241-BY Tank Farm ITS Unit 2 condenser cooling water.		

Code:	216-B-3-3	Classification:	Accepted
Names:	216-B-3-3; 216-B-3-3 Ditch; B Swamp Ditch	Reclassification	None
Type:	Ditch	Start Date:	1/1/1970
Status:	Inactive	End Date:	1/1/1994
Description:	The ditch has been backfilled and surface stabilized. It is posted as an Underground Radioactive Material area.		
Location:	The ditch is located east of the 200 East Area perimeter fence. It continued east to 216-B-3		

Pond, south of the 216-B-3-2 Ditch.

Release Description: UPR-200-E-51 occurred in 1977.

Process Description: The ditch received effluent from the B Plant and PUREX facilities. The unit was an open ditch from the diverter station to the 216-B-3 Pond. The unit was 1.2 to 2.4 meters (4 to 8 feet) deep and 0.3 meters (3 feet) wide at the bottom. The 216-A-29 Ditch fed into this unit approximately 305 meters (1,000 feet) upstream of the 216-B-3 Pond outfall.

Waste Type: Process Effluent

Waste Description: Until July 1973, the site transported and percolated 221-B cooling water, 202-A chemical sewer from the 216-A-29 Ditch, 241-BY Tank Farm ITS Units 1 and 2 cooling water, and 244-CR Vault cooling water. From July 1973 to May 1978, the site received the same as above minus ITS Units 1 and 2 cooling water. From May 1978, the site received 221-B cooling water and 202-A chemical sewer from the 216-A-29 Ditch.

Code: 200-E-1 **Classification:** Accepted

Names: 200-E-1; 284-E Landfill; Asbestos in Excavation **Reclassification:** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: There is no visible evidence of a landfill at this location. A covered concrete pad had been built over the area where the landfill was supposed to be located. The 284E Powerhouse was demolished in 2011 (see sitecode 200-E-296). The area was covered with a gravel cap.

Location: The site is located west of 284-E building.

Related Sites/Structures: The site is associated with the demolished 284-E Powerhouse and the gravel cap (sitecode 200-E-296).

Process Description: The unit consists of asbestos waste encountered during below grade trenching activities.

Waste Type: Asbestos (friable)

Waste Description: The waste at this unit consists of asbestos.

Code: 200-E-2 **Classification:** Accepted

Names: 200-E-2; MO-234 Parking Lot; Soil Stains at the 2101-M SW Parking Lot **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The site was originally described as a gravel covered parking lot that contained discolored soil. Two large dark circular stains were visible in front of the access ramp at the south end of MO-234.

Location: The site is at the northwest corner of the intersection of Baltimore and 2nd Street, in 200 East Area. The site is bound by MO-234 to the north and MO-413 and MO-021 to the west.

Process Description: The parking lot is actively being used for vehicle parking. Personnel that may have knowledge of past disposal in this unit were interviewed. Based on these interviews, the unit was used as a parking lot for the Telephone and Utilities Department. Used oil has been used for dust abatement; no other dumping is known to have occurred.

Waste Type: Oil

Waste Description: The unit waste includes used oil for dust abatement. BHI Regulatory Support (B. Vedder) had two concerns about the site. Polychlorinated biphenyls (PCBs) were the biggest concern and heavy metals of lesser concern. PCBs were common in high heat grade hydraulic fluids. Unless there is some strong evidence that only used vehicle motor oil was applied, this site will need to be sampled to verify that there is no PCB contamination. On August 24, 2006, sample number B1KHY0 was collected and analyzed at WSCF lab.

Code: 200-E-7 **Classification:** Accepted

Names: 200-E-7; 2607-EO Septic Tank & Tile Field **Reclassification:** None

Type: Septic Tank **Start Date:** 1/1/1994

Status: Active **End Date:**

Description: The tank is part of the 2607-EP System. Current and proposed additions to this system bring its design daily flow to 20,440 liters (5400 gallons). The tank was pre-fabricated with a 1500 gallon first chamber and a 1000 gallon second chamber. The associated septic field has been abandoned.

Location: This septic tank/pump station is located west of the 2711-E building (Automotive Garage and Shop) and north of 4th Street.

Process Description: As of 1996, the tank serviced 2711-E, but is capable of supporting additional facilities.

Waste Type: Sanitary Sewage

Waste Description:

Code: 200-E-46 **Classification:** Accepted

Names: 200-E-46; Debris Southeast of 282-E; RCRA Permit General Inspection #200EFY96 Item #3 **Reclassification:** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The site appears to be an old lay down area. Scattered debris is visible over a large area.

Location: The site is located on both sides of the dirt road approximately 183 meters (600 feet) southeast of the 282-E Reservoir building and running along the south side of the railroad spur.

Waste Type: Misc. Trash and Debris

Waste Description: Materials observed at the site include wire rope, a steel railroad rail, a metal bar, wood, fiberglass insulation, aluminum cans coal, pipe, aluminum wire, copper wire, concrete, and glass. Most of the debris is in relatively small pieces. Large debris include the steel railroad rail, iron bar, wire rope, and concrete.

Code: 200-E-101	Classification: Accepted
Names: 200-E-101; 200 East Deep Lysimeter Site	Reclassification: Rejected (9/16/2010)
Type: Experiment/Test Site	Start Date: 1/1/1971
Status: Inactive	End Date: 1/1/2009

Description: The site has been evaluated and reclassified to Rejected. It consists of three features, one open bottom pit, one closed bottom pit and an underground equipment storage room. The pits are located 34.6 meters (114 feet) apart. Both pits are constructed from corrugated steel cylinders that were buried and backfilled with soil. Instrument cables were weighted with lead bricks. In February 2001, the underground, equipment storage room access hatch and vents were found inside a chained area, just west of the dirt access road. The closed bottom pit is north of the equipment room, enclosed in a triangular shaped chained area. Lysimeter access pipes are protruding up through the soil and the rim of the closed bottom lysimeter caisson are visible.

The open bottom lysimeter has been decommissioned. The closed bottom lysimeter remained in a "Standby" mode. In 2007, it was still operational, but is not being used.

Location: The site is located southeast of 200 East Area, within the BC Radiologically Controlled Area, approximately one half mile south of Route 3. It is 91.5 meters (300 feet) northwest of well #699-32-49D.

Process Description: The lysimeter pits were used to collect soil information. The sensors in the pits were hard wired to the instrument recorders, located inside the underground equipment storage room. Three 4-centimeter (1.6-inch) diameter aluminum pipes were installed to a depth of 18.3 meters (60 feet) to allow access of a Neutron Moisture Probe. Other pipes contained soil temperature thermocouples and pressure sensor tubes. The closed bottom lysimeter has a 20-centimeter (8-inch) poured concrete slab at the bottom. Holes were bored through the cement slab so the instruments could access the soil below the caisson. The instrument room housed the recording and measurement instruments. The room was buried approximately 0.3 meters (1 foot) below ground level to eliminate climatological influences, such as wind and temperature that could interfere with readings. The room measures 4.5 meters (14.8 feet) by 4.8 meters (15.8 feet) and was located between the two lysimeter pits.

Waste Type: Equipment

Waste Description: In 1999, PNNL said the neutron probe has been left inside the closed bottom pit, but in 2008 PNNL said the probe had been removed. The cables were weighted with 500-gram (1.1 pound) lead bricks that were backfilled in place, inside the pits. This equipment could be considered hazardous.

Code: 200-E-110	Classification: Accepted
Names: 200-E-110; Contaminated Tumbleweed Dump Site	Reclassification: Interim Closed Out (2/25/2011)
Type: Dumping Area	Start Date:
Status: Inactive	End Date:

Description: This waste site was reclassified to Interim Closed Out in 2011. The area was down posted to a non-controlled area in October 2003. The radiological posting signs were removed. The site had been surrounded with light duty steel chain and posts and posted as a Contamination Area. The Contamination Area was surrounded with light duty steel chain and posts and is posted as a Radiological Buffer Area. The area had also been posted as a Radiologically Controlled Area. The ground is sandy soil with rocks and chunks of concrete. The area is free of growing

vegetation and the tumbleweeds have been removed. Only tumbleweed fragments remained.

Location: The site is located just off the northeast corner of 200 East Area, east of Canton Avenue and northeast of Gate 810.

Waste Type: Vegetation

Waste Description: The waste consisted of dried, compacted tumbleweeds.

Closure Info: Interim: In July and August 2009, the 200-E-110 and UPR-600-21 waste sites were investigated through observation, field screening and radiological surveys for the purpose of determining if radiological contaminants were present above the removal action levels (RALs). The survey results analysis confirmed that soil contaminant concentrations are at or below the RALs and that no further action is required. Both 200-E-110 and UPR-600-21 waste sites achieved compliance with the removal action levels (RALs) and thus met the removal action objectives (RAOs). These results support reclassification to Interim Closed Out status.

Code: 200-E-126-PL-A **Classification:** Accepted

Names: 200-E-126-PL-A; Segments of 200-E-126-PL Pipeline Located in the Outer Area **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: Due to the restructuring of Operable Units, as described in the Agreement for Central Plateau Cleanup, the original pipeline site has been split into segments. 216-E-126-PL-A is the segments of pipeline located in the Outer Area. The segments of pipeline associated with 200-E-126-PL-A include the forty eight inch diameter corrugated metal pipes that could feed the lobes of the 216-E-28 Contingency Pond, the thirty inch diameter High Density Polyethylene pipe that fed the 216-B-3B pond lobe and the two thirty inch diameter corrugated metal pipes that connected the 216-B-3A pond lobe to the 216-B-3C pond lobe.

Location: The 200-E-126-PL-A pipeline segments are located east of the 200 East Area fence line, beyond the Inner/Outer Area boundary.

Related Sites/ Structures: This waste site is associated with the 200-E-126-PL-B, 216-E-28 Contingency Pond, 216-B-3A Lobe and 216-B-3B Lobe.

Process Description: The pipeline conveyed B Plant effluent to the 216-B-3 Pond and Ditch system. B Plant cooling water effluent was originally routed through the 207-B Retention Basin to the 216-B-2-1, 216-B-2-2 and 216-B-2-3 ditches. In 1987, the 216-B-2-3 ditch was closed and was replaced by this, 22 inch diameter plastic underground pipeline. It extended from the 207-B basin to Diverter Station #2. By 1994, all of the open ditches (216-B-2-1, 216-B-2-2, 216-B-2-3, 216-B-3-1, 216-B-3-2 and 216-B-3-3) had been backfilled and surface stabilized. After 1994, all the effluent was conveyed to the 216-B-3A and 216-B-3C pond lobes only through underground pipelines. In 1995 the ponds were closed. The remaining effluent was transferred the Treated Effluent Disposal Facility (TEDF). Parts of the pipelines east of 200 East Area, that had fed the ponds, were re-used to feed the TEDF disposal basin. The TEDF portion begins at Manhole #8 and extends to Pump Station #3. In the event of a failure at Pump Station #3, the effluent can be routed to 216-B-3C (C lobe). The section that connects the southeast corner of 216-B-3A to the northwest corner of 216-B-3C is constructed of 76 centimeter (30 inch) corrugated metal pipe.

Code: 200-E-127-PL-A **Classification:** Accepted

Names: 200-E-127-PL-A; Segments of Gable Mountain Pond Pipeline Located in the Outer Area **Reclassification** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: Due to the restructuring of Operable Units, as described in the Agreement for Central Plateau Cleanup, the original pipeline site (200-E-127-PL) has been split into segments. 200-E-127-PL-A is the segments of pipeline located in the Outer Area. The pipeline is marked with steel posts and Underground Radioactive Material - Pipeline signs. The majority of the pipeline is constructed of large diameter corrugated metal pipe. The 36 inch diameter corrugated metal pipe enlarges to 42 inch diameter corrugated metal pipe at Manhole #8 (north of the 600-118 diverter station). The pipeline divides into two sections (a Y shape) near where it crosses Route 11A. Two sections of pipe fed the pond. Near the 810 gate, an area of contaminated vegetation growing on and adjacent to the pipeline was stabilized with biobarrier and posted with Underground Radioactive Material Area signs. A portion of the pipeline is under the Liquid Effluent Retention Facility (LERF) berm and extends into the LERF/ETF facility boundary.

Location: 200-E-127-PL-A is located east and north of the 200 East Area. This segment extends northward from Manhole 5 to the 216-A-25 (Gable Mountain Pond).

Process This portion of pipeline conveyed PUREX and B Plant effluent to the (216-A-25) Gable Pond.

Description: The effluent stream could be directed to Gable Mountain Pond or B Pond via Diverter Station #3. From Diverter Station # 3 northward to the 216-A-25 Pond, the pipeline is constructed of 107 centimeter (42 inch) diameter corrugated metal pipe.

Code: 2607-E1 **Classification:** Accepted

Names: 2607-E1; Septic Tank and Tile Field **Reclassification** Closed Out (11/9/2004)

Type: Septic Tank **Start Date:** 1/1/1948

Status: Inactive **End Date:** 1/1/1997

Description: This septic tank was properly abandoned in 1997. It was constructed of reinforced concrete with walls and floors. The associated drain field is 778 square meters (8,376 square feet).

Location: This septic tank is located north of 4th Street and east of Baltimore Avenue. The tile field is north of the tank.

Related Sites/ Structures: The 2607-E1 Septic Tank is associated with the 2607-E1 Tile Field, the 200 East shops and 282-E.

Process Description: The 2607-E1 Septic Tank and associated drain field were designed to accept and treat sanitary sewer effluent from facilities in central 200 East Area.

Waste Type: Sanitary Sewage

Waste Description: This unit received sanitary wastewater and sewage at an estimate rate of 21,556 liters (5,695 gallons) per day. It service the 200 East Area shops and powerhouse.

Closure Info: Interim: The reclassification to Closed Out is documented on form 2004-116. The system was abandoned in 1997 in accordance with Washington Administrative Code 246-272-18501. This system was tied into 2607-E1A.

Code: 216-N-8 **Classification:** Accepted

Names: 216-N-8; 216-N-8 Pond; Honeyhill Pond; **Reclassification** None

Seepage Pond; West Lake; West Pond

Type: Pond**Start Date:****Status:** Inactive**End Date:****Description:** The site is a pond of water surrounded by a white perimeter ring of dried alkali salt residue. The size and volume of the pond change with the seasons and groundwater levels.**Location:** The site is located south of the western end of Gable Mountain and northwest of 216-A-25. It is east of Route 4 North. An unnamed dirt road leads to West Lake from Route 4 North.**Related Sites/ Structures:** The Gable Mountain Pond (216-A-25) and 600-262 are associated with the unit.**Process Description:** This unit did not receive effluent from any contaminated facilities, but may have received discharge from the 606 Central Mix cement plant (see drawing H-11-4327). This pipeline could also be part of the Export Water line (see HW-70186). Prior to construction of Gable Mountain Pond, it was an intermittent, seasonal pond, only appearing in the winter and spring when the water table was elevated. Early Hanford construction camps disposed of sanitary sewage sludge in this area. This practice is believed to have contributed to the high alkaline and phosphate levels and elevated pH levels in the pond. After Gable Mountain Pond (216-A-25) became active in 1958, West Lake enlarged as a result of the raised water table and became a permanent pond.**Waste Type:** Water**Waste Description:** Prior to the appearance of West Pond, this area was used as a disposal site for sewage sludge from the early Hanford construction camp. High alkaline and phosphate levels, as well as elevated pH values, may be attributed to this use of the pond area. Hanford drawing H-11-4327 shows a water line extending from the 606 Central Mix cement plant settling basins to Honeyhill. It implies the lake may have received water from the cement plant. However, this pipeline could also be part of the Export Water line (see HW-70186). Even though this unit never received direct discharges of contaminated effluents, it contains relatively high amounts of radionuclides (1,055 to 1,098 picocuries/liter in 1976), having the highest gross alpha (naturally occurring except for tritium) concentrations of all the 200 Area ponds. The actual source of existing activity is unknown. A possible main contributor is the leaching of naturally occurring radionuclides from the soil that has been concentrated by evaporation during the entire history of the unit.

Code: 216-S-10D**Classification:** Accepted**Names:** 216-S-10D; 216-S-10D Ditch; Chemical Sewer Trench; Open Ditch to the Chemical Sewer Trench; 202 Chemical Sump #1 and Ditch; 216-S-10 Ditch**Reclassification:** None**Type:** Ditch**Start Date:** 1/1/1951**Status:** Inactive**End Date:** 1/1/1991**Description:** The portion of the ditch nearest the 200 West Area perimeter fence is an open, unlined open ditch. Two thirds of the original ditch has been backfilled. The covered portion is posted with Underground Radioactive Material signs. The open portion is marked, but not radiologically posted.**Location:** The 216-S-10 Ditch begins southwest of the 202-S Building and extends south of the 200 West Area perimeter fence.

Release Description: See UPR-200-W-34.

Related Sites/ Structures: The ditch is associated with the REDOX facility, the REDOX chemical sewer 200-W-157-PL, 216-S-11 and the 216-S-10 Pond.

Process Description: The site started receiving waste from 202-S in August 1951. In February 1954, it became apparent that the 216-S-10 Chemical Sewer (200-W-157-PL) needed a larger leaching area. Thus four leaching ponds (fingers) were dug southwest of the 216-S-10 Ditch, adding approximately 3 acres of leaching surface. By May 1954, the area became swamped again. Two more leach trenches were added that became known as 216-S-11. The May 1954 REDOX Monthly Report indicated contamination levels in the trench to be a maximum of 500 to 800 mrads/hour in spots with lower levels of 80,000 counts per minute in a one acre overflow area that resulted from a break in the east trench (southeast 216-S-11 per Maxfield); see UPR-200-W-34. ANN solution was inadvertently dumped into the Chemical sewer in 1954 and seriously plugged the soil at the terminus of the chemical sewer.

Waste Type: Process Effluent

Waste Description: In the past, 420 liters (110 gallons) of hazardous waste salts including sodium nitrite (NaNO₂) and sodium hydroxide (NaOH) were discharged to the unit. Until 1965, the site received chemical sewer waste from 202-S and overflow from the high water tower. Since October 1991, the site no longer acted as a ditch because the 216-S-10 Pond was stabilized. No dangerous wastes have been discharged to this unit since February 1987. NOTE: The 216-S-11 Pond was credited with all the liquid effluent inventory for the 216-S-10 Pond and Ditch system for many years.

Code: 216-S-10P	Classification: Accepted
Names: 216-S-10P; 216-S-10P Pond; Chemical Sewer Trench; 202-S Chemical Sump #1 and Ditch	Reclassification: None
Type: Pond	Start Date: 1/1/1952
Status: Inactive	End Date: 1/1/1984

Description: The pond was an irregular shape with four trenches known as fingers. The unit has been backfilled and stabilized and posted with Underground Radioactive Material signs.

Location: The unit is located outside the 200 West Area perimeter fence, southwest of the 202-S Building.

Release Description: The unit received one documented discharge of dangerous waste. This discharge consisted of simulated double-shell tank slurry which exhibited dangerous waste characteristics of ignitability, corrosivity, characteristic waste and toxic state-only waste. Approximately 450 kilograms (1,000 pounds) were discharged.

Related Sites/ Structures: The pond is associated with the REDOX facility, the 216-S-10 Ditch and UPR-200-W-34.

Process Description: In February 1954, it became apparent that the 216-S-10 Chemical Sewer need more leaching area, so four leaching ponds (fingers) were dug off the southwest end of the 216-S-10 Ditch. The fingers added approximately 3 acres of leaching surface. By May 1954, the area became swamped again. Two more leach trenches were added that became known as 216-S-11.

The May 1954 REDOX Monthly Report indicated contamination levels in the trench to be a maximum of 500 to 800 mrads/hour in spots with lower levels of 80,000 counts per minute in a one acre overflow area that resulted from a break in the east trench (southeast 216-S-11 per Maxfield).

Waste Type: Process Effluent

Waste Description: Until 1965, the site received the chemical sewer waste from 202-S and overflow from the high water tower via the 216-S-10 Ditch. From 1960's, the site received the bearing cooling water from 202-S. RHO-CD-673 documents two releases of radioactive liquid into the S-10 Disposal System. NOTE: The 216-S-11 Pond was credited with all the liquid effluent inventory for the 216-S-10 Pond and Ditch system for many years.

Code: 216-S-11 **Classification:** Accepted

Names: 216-S-11; 216-S-11 Swamp; Chemical Sewer Trenches; 202-S Chemical Sump #2 **Reclassification:** None

Type: Pond **Start Date:** 1/1/1954

Status: Inactive **End Date:** 1/1/1965

Description: A 1999 site visit found the area to be flat and covered with bunch grass. Neither of the 216-S-11 pond lobes are marked or posted.

Location: This unit is southwest of 202-S Building and just east of 216-S-10 Ponds.

Related Sites/Structures: The site is associated with the 216-S-10 Ditch, UPR-200-W-34 and the 202-S Building.

Process Description: This site provided an additional leaching surface for the disposal of water from the 216-S-10 Ditch. The site consisted of two connecting pond lobes. The south lobe was backfilled in 1975, but there is no documentation of when the north lobe was backfilled.

Waste Type: Process Effluent

Waste Description: The site received the waste from air conditioning and drains in 202-S Building and the chemical sewer waste from the 202-S Building. NOTE: The 216-S-11 Pond was credited with all the liquid effluent inventory for the 216-S-10 Pond and Ditch system for many years.

Code: 216-S-16D **Classification:** Accepted

Names: 216-S-16D; 216-S-24 Ditch; REDOX Pond #2; 202-S Swamp #1; 202-S Swamp (New) and Ditch **Reclassification:** None

Type: Ditch **Start Date:** 1/1/1957

Status: Inactive **End Date:** 1/1/1975

Description: The site is a ditch that connected the 202-S Building to the 216-S-16 Pond. The side slope of the open ditch was 2:1. The ditch has been backfilled and surface stabilized. It is posted with Underground Radioactive Material signs.

Location: The open ditch began 835 meters (2736 feet) southwest of the southwest corner of the 200 West Area perimeter fence, terminating at the eastern edge of the 216-S-16 Pond.

Related Sites/Structures: The site is associate with the REDOX facility, the 216-S-16 Pond, and the 216-U-9 Ditch. The pipeline to the 216-S-16 ditch is discussed in sitecode 200-W-155-PL.

Process Description: The ditch received effluent from the REDOX facility. Prior to reaching the open ditch, the effluent was transported via an underground, 60 centimeter (24 inch) vitrified clay pipeline.

Waste Type: Process Effluent

Waste Description: January 1957 is considered the most accurate start date for this waste unit. The site received process cooling water and steam condensate from 202-S Building until June 1967. After the 202-S Building (REDOX) was put on standby in July 1967, the site received condenser and vessel cooling water from concentrator boil-down operations in the 202-S Building. In 1973, the 216-U-9 ditch was connected to the 216-S-16 ditch to allow the 216-U-10 pond overflow to reach the 216-S-16 pond.

Code: 216-S-19	Classification: Accepted
Names: 216-S-19; 216-S-19 Pond; 216-SL-1; 222-S Lab Swamp; REDOX Lab Swamp	Reclassification: Interim Closed Out (9/21/2011)
Type: Pond	Start Date: 2/1/1952
Status: Inactive	End Date: 10/1/1984

Description: This waste site has been evaluated under a removal action and Interim Closed Out. The pond is no longer marked or posted. The radiological postings were removed in August 2011.

Location: This unit was located south of the 200 West Area perimeter fence, southeast of the 216-S-14 Trench and the 2607-W7 Tile Field.

Release Description: Document HW-60807 states "The 222-S Swamp, located outside 200 West Area, about 1000 yards south of the 222-S laboratory, is used for disposal of drainage from lab sinks and wall drains. In December 1953, contamination up to 200 millirad per hour at the ground surface was discovered over an area measuring approximately 300 feet long and 3 feet wide." Reference 9 on sketch G of this document indicates the location to be the 216-S-19 pond.

Related Sites/ Structures: The associated structures are the 222-S Building, 207-SL Retention Basin, 216-S-26 crib and pipeline sitecode 200-W-147-PL.

Process Description: The pond was opened in February 1952 and closed in October 1984. Until December 1954, the site received effluent from the 222-S/SA Laboratory ventilation cooling water and miscellaneous wastes from laboratory hoods and decontamination sinks via the 207-SL Retention Basin. From December 1954 to October 1955, the site was inactive because the radionuclide concentration in the 207-SL Retention Basin liquid waste was above the prescribed disposal guidelines, and building effluents were rerouted to the 216-S-20 Crib. From October 1955 to October 1984, the site received ventilation cooling water and miscellaneous wastes from laboratory hoods and decontamination sinks in the 222-S Laboratory Building via the 207-SL Retention Basin.

Waste Type: Process Effluent

Waste Description: The site received ventilation cooling water, lab hood waste, and decontamination sink waste.

Closure Info: Interim (9/21/2011): The removal action at the 216-S-19 waste site was conducted from November 2010 through August 2011. Twelve focused confirmatory samples were collected from the north end of the pond, near the discharge pipe. The results of initial sampling indicated concentrations of uranium U-233/234, and U-238 in excess of their respective Removal Action Levels thus initiating RTD. Removal of impacted soils at the 216-S-19 was excavated to a depth of approximately 0.31 to 0.61 meters (1 to 2 ft) below the floor of the pond, at Focused Sample 6, in an attempt to spot clean the area of contamination. The area of excavation was later expanded laterally to encompass the entire floor of the pond. The vertical extent of excavation was refined by in process sampling, conducted during RTD activities. The depth of excavation ranged from approximately 3 to 4 meters (10 to 13 ft) below original grade.

Code: 216-S-26	Classification: Accepted
Names: 216-S-26; 216-S-26 Crib; 216-S-19 Replacement Facility	Reclassification: Interim Closed Out (9/21/2011)
Type: Crib	Start Date: 10/1/1984
Status: Inactive	End Date: 6/1/1995

Description: This crib has been evaluated under a removal action and Interim Closed Out. The crib is no longer marked or posted. The crib had been surrounded with metal posts and chain and was posted with Underground Radioactive Material signs. A 15 centimeter (6 inch) vitrified clay, perforated distribution pipe runs the length of the unit, 46 centimeters (18 inches) above the bottom of the crib. Eight centimeters (4 inches) of gravel covered a membrane barrier. The crib had been filled with 2.9 meters (9.5 feet) of soil. One gage well with a liquid level indicator was located 30 meters (100 ft) from the west end, and a vent riser was located at the east end.

Location: The crib was located southeast of 222-S Building, outside the 200 West Area perimeter fence.

Release Description: During the week of 10/20/84, a spill occurred at the 222-S Lab resulting in the release of water contaminated with Sr-90 to the 207-SL Retention Basin. Concentrations averaged 2 to 3 times the Sr-90 guide but did not exceed RHO-MA-139 standards. The water was released to the new 216-S-26 Crib.

Related Sites/ Structures: The pipeline associated with this crib is WIDS pipeline sitecode 200-W-148-PL.

Process Description: The crib received waste from the 222-S laboratory via the 207-SL retention basin. In 1988, crib infiltration rate problems were noted due to caustic flush water being periodically disposed to the 207-SL basin.

Waste Type: Steam Condensate

Waste Description: The site received steam condensate and sink wastes, which are byproduct radioactive wastes, from the 222-S Laboratory via the 207-SL Retention Basin. The wastes contain a variety of chemicals, including acetone, nitric acid, and lesser amounts of sulfuric and hydrofluoric acids.

Closure Info: Interim (9/21/2011): The removal action at the 216-S-26 and 200-W-148-PL waste sites was conducted from March 2011 through August 2011 and included the removal of overburden soil, and the pipe itself, followed by collection of samples from locations within the excavation. Implementation of the selected Remove, Treat, Dispose (RTD) alternative was performed. Soil and piping were removed from the two waste sites. Direct visual inspection of the site surface was performed as a guide for visual cues such as staining, discoloration, absence of vegetation, presence of debris, and other anomalies. Radiological field screening was performed at the excavation surface of the waste site to provide an indication of the extent of radiological contaminants. Soil was removed to a depth of approximately 4.6 meters (15 ft) below ground surface. Characterization sampling was performed at depths of 4.6, 4.9, 5.5, and 6.1 meters (15, 16, 18, and 20 ft) and the analytical results evaluated to demonstrate achievement of Removal Action Objectives. Backfill of the 216-S-26 and 200-W-148-PL waste sites was completed on August 30, 2011.

Code: 216-T-1	Classification: Accepted
Names: 216-T-1; 216-T-1 Trench; 221-T Ditch; 221-T Trench	Reclassification: None
Type: Ditch	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1995

Description: The ditch has been backfilled. It is currently marked and posted with Underground Radioactive Material signs.

Location: The ditch is located on the north side of 221-T Building, west of Beloit Avenue.

Related Sites/Structures: The ditch was associated with the 221-T facility operations. The pipeline associated with the ditch is 200-W-180-PL.

Process Description: The ditch received cooling water and steam condensate discharge from 221-T and 271-T.

Waste Type: Steam Condensate

Waste Description: From 1944 until 6/56, the site received miscellaneous waste from pilot plant experimental work, intermittent decontamination waste, and waste from the head end of the 221-T Building. From 6/56 to 1/64 the ditch was inactive due to the production operations at T Plant being shut down. From 1/64 to 6/70, the site received cooling water from the blowdown vessel in the 271-T Building and miscellaneous waste from PNL head end operations in the 221-T Building. After 6/70, the site received condensate from steam-heated radiators at the head end of 221-T Building. During standdown of PNL operations, the discharge of 271-T and other 221-T head end waste was discontinued. The site also received sodium hydroxide wash water waste solution (less than 1,000 gal/month [3,800 L/month]) from the Sodium-Air-Water Reaction Emergency Air Cleaning Development-HEDL. This waste water was nonradioactive and generally wet only the bottom of the unit to approximately 150 ft (46 m) from the outfall.

Code: 200-W ADB	Classification: Accepted
Names: 200-W ADB; 200-W Ash Disposal Basin	Reclassification: None
Type: Coal Ash Pit	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/2000

Description: The site is an area of dark soil with cheatgrass growing on the surface. A small depression can be seen in the middle of the site.

Location: The site is located inside 200 West Area, northeast of the 221-U Facility. It is on the east side of Beloit Ave. south of 20th Street.

Related Sites/Structures: The site is associated with the 284-W Powerhouse operation the 200-W Ash Pit. The open pit adjacent to the south side of the 200-W ADB is known as the 200-W Burn Pit (200-W BP).

Process Description: The Ash Disposal Basin received coal ash slurry and ash from the operation of the coal fired 284-W Powerhouse. A 1954 drawing shows an underground ash slurry pipeline extending from the northeast corner of the 284-W Powerhouse to the northwest corner of the Ash Disposal Basin. Later, the site received trucked material, dredged from the 200 West Powerhouse Ash Pit, located south of the powerhouse, on the west side of Beloit Ave.

Waste Type: Ash

Waste Description: The site mainly received coal ash from the 200 West Area Powerhouse operation. However, the open pit was sometimes used for other purposes. The open ash disposal basin was sometimes used as a location for burning tumbleweeds that had collected along area fences during the 1980's. A Tiger Team finding for disposing of steam plant ash without a permit prompted sampling of wet flyash and bottom ash from the 200 Area power houses. Sample results determined the ash to be non-dangerous and non-corrosive and not regulated under Washington Administrative Codes.

Code: 200-W BP **Classification:** Accepted
Names: 200-W BP; 200-W Burning Pit; Gravel Pit 34; Pit 34 **Reclassification:** None
Type: Burn Pit **Start Date:** 1/1/1950
Status: Active **End Date:**

Description: The site is a large open pit.

Location: The site is located within the 200 West Area Ash Disposal Basin, southeast of the 284-W Powerhouse, on the east side of Beloit Ave.

Release Description: UPR-200-W-37 and UPR-200-W-70 have been associated with the 200 West Burn Pit in some documents. It is possible that an early burn pit, located southeast of U Plant, was actually the site of these releases. See 200-W-71.

Related Sites/ Structures: The burn pit is associated with the 200-W Ash Disposal Basin (200-W ADB), 200-W ADS and 200-W-71.

Process Description: 200 Area office waste and non-radioactive construction debris and tumbleweeds have been brought to this site and burned. According to Dave Phipps in April 2002, this site is used as a staging area for uncontaminated tumbleweeds from the 200 Area fences. They are burned semiannually in the spring and the fall. The area is also used as a source of clean backfill (gravel) material.

In 1984, a one time chemical demolition event occurred inside the northern portion of the current 200-W Burn Pit. However, the title of the closure document is the 200 West Area Ashpit Demolition Site Closure Plan (DOE/RL-92-54). A review of this document confirms the location of the chemical demolition was inside the 200-W Burn Pit. Drawing H-2-1495 and historical photograph #3755 show another disposal pit/burn pit, located south of 16th Street, east of Beloit Ave. Early references to the 200 West Burn Pit could be referring to this location.

Waste Type: Demolition and Inert Waste

Waste Description: The unit is used to burn nonradioactive material and tumbleweeds PNL-6456 states the site received construction and office waste (15,000 cubic meters [19,600 cubic yards]), paint waste, and chemical solvents (1,000 liters [260 gallons]).

Code: 200-W-3 **Classification:** Accepted
Names: 200-W-3; 220-W-1; 2713-W North Parking Lot **Reclassification:** None
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is the gravel parking lot, containing an area where discolored soil was identified in an excavation between 10 to 15 centimeters (4 to 6 inches) below the surface.

Location: The waste site is located east of Beloit Ave. and north of 20th Street. It is north of where the 2713-W garage had been located before it was demolished.

Related Sites/ Structures: Building 2713-W and a waste oil storage tank are associated with this unit.

Process Description: The 2713-W building had been a gas station and also contained an oil changing pit for government vehicle maintenance. Oil was often used on gravel areas for dust abatement.

Waste Type: Oil

Waste Description: The waste at the unit includes waste oil that was used for dust abatement. Two soil samples taken at the unit indicate that PCBs (maximum 3 parts per million), lead (maximum 2.1 milligrams per liter EP-TOX), xylene (maximum 1640 parts per billion), and total petroleum hydrocarbons (maximum 620 milligrams per kilograms) were present.

Code: 200-W-33 **Classification:** Accepted
Names: 200-W-33; Debris Near 609 Gate; Solid Waste Dumping Area **Reclassification:** Interim Closed Out (6/3/2011)
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The waste site has been evaluated under a removal action and reclassified to Interim Closed Out. The site originally consisted of an area of debris covering approximately one acre in a stand of open sagebrush. A grass fire burned the area in 2007. Many more cans and drums became visible after the fire, increasing the size of the waste site significantly to approximately 12 acres.

Location: The site is located near the northwest corner of 200 West Area. It is outside the 609 Gate, west of Dayton Ave.

Waste Type: Misc. Trash and Debris

Waste Description: Numerous empty, rust cans and barrels were found. One five gallon can was found that contained an oil substance. Other types of miscellaneous debris included tires, bottles and oil cans. There is evidence of burning in the area.

Closure Info: Interim (6/3/2011): The selected alternative for the 200-W-33 waste site was confirmatory sampling/no further action (CS/NFA). The results of the confirmatory sampling indicated COPC concentrations greater than the RALs in two of the sampled areas. Per the provisions of the Action Memorandum, the removal action activities progressed to implementation of the RTD alternative for those areas, and for debris removal at the waste site. Upon completion of RTD activities, verification sampling was conducted to demonstrate that contaminant concentrations in soil at the 200-W-33 waste site were less than or equal to the RALs, thus demonstrating that the RAOs were met.

The removal action at the 200-W-33 waste site was conducted from February 2010 through March 2011 and included the collection of focused and random samples from locations within the waste site. Remedial activities included the collection of judgmental soil samples based on historical and process knowledge, and visual indicators; excavation of soil under the RTD alternative in zones of potential contamination (ZPCs) 5 and 9; removal of debris scattered throughout the waste site, along with underlying soil and collecting of random samples from ZPCs 5 and 9 for verification purposes.

No radiological postings were present at the waste site. Radiological field screening surveys were performed at the 200-W-33 waste site. No radiological readings greater than the measured background, and no radiological contamination was found.

Debris and approximately 0.3 meters (1 foot) of underlying soil was removed from the ZPCs and the remainder of the waste site during implementation of the RTD alternative.

Revegetation at the 200-W-33 waste site is not required, however, the 200-W-33 waste site has been reseeded.

Code: 200-W-64	Classification: Accepted
Names: 200-W-64; 2724-W Contaminated Laundry Facility Building Foundation	Reclassification: None
Type: Foundation	Start Date: 1/1/1950
Status: Inactive	End Date: 1/1/1994

Description: The building foundation is posted with "Underground Radioactive Material" signs. There is also an area approximately 3 meters (10 feet) by 4.5 meters (15 feet) on the north side of the foundation that is posted as "Fixed Contamination". Several drains and pipes were observed on the concrete pad. All drains and pipes were either capped or grouted. There are three radiologically posted manholes adjacent to the northwest corner of the foundation. The manholes are likely to be a portion of the process sewer. Overtime, equipment items such as pipe, valves, flanges, fence posts have been observed being staged on the southeastern portion of the cement foundation. Some Radiological Material Areas have been noted.

Location: The building foundation is located in 200 West Area, at the corner of Beloit Ave. and 20th Street.

Related Sites/ Structures: The site is associated with the demolished contaminated laundry facility complex which included 2724-WA, 2724 WB Laundry facilities, and the MO-412 Mask Cleaning facility. It replaced the 2723-W (Old Laundry" Facility and mask cleaning station) which was located northeast of the 2724-W facility. Effluent was discharged via 200-W-102 to the U-14 Ditch until 1981 when it was diverted to the 216-W-LWC (Laundry Waste Crib).

Process Description: WHC-EP-0342 states the 2724-W building was built in 1952 and expanded several times. ARH-2155, however, indicates that the new laundry facility (2724-W) began discharging effluent in 1950. This building (2724-W) replaced the 2723-W "Old Laundry" facility which was then used as the mask washing facility. The laundry effluent was discharged via an underground pipeline (200-W-102) to the 216-U-14 Ditch, until it was diverted to the new Laundry Waste Crib (216-W-LWC) in 1981. By 1981, the Laundry Complex included the 2724-W, 2724-WA, 2724-WB and MO-406. MO-412 was placed adjacent to the Laundry Complex in 1984 and housed the Mask Cleaning and Maintenance Facility. Soiled protective work clothing (coveralls, gloves, hoods, canvas boots and rubber shoe covers) were sent to the laundry facility from all the Hanford work areas. Two thirds of the laundry received was radioactively contaminated. One third consisted of "blue" (non contaminated) coveralls and towels. The non-contaminated laundry was washed separately from the contaminated laundry. By 1981, approximately three million pounds of laundry was processed per year in 600 pound capacity washing machines and 400 pound capacity dryers. An average of 26,250,000 liters (691,000 gallons) of waste water was discharged to the 216-W-LWC crib each month.

Waste Type: Construction Debris

Waste Description: The site is the cement foundation of the contaminated laundry facility.

Code: 200-W-102-PL	Classification: Accepted
Names: 200-W-102-PL; Pipeline from Laundry, Powerhouse and Shops to 216-U-14 Ditch; 200-W-102	Reclassification: None
Type: Radioactive Process Sewer	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1981

Description: The waste site is various diameters of vitrified clay and concrete pipes that transferred waste to

	the 216-U-14 ditch. The underground pipeline is not separately marked or posted. Several manholes are visible along the line that have Confined Space and Radiation Area postings.
Location:	The pipeline is located in 200 West area, on the north and south sides of 20th Street. It extends westward on the north side of 20th Street until it terminates at the head end of the 216-U-14 Ditch.
Related Sites/ Structures:	This pipeline discharged effluent from 2723-W (old laundry/mask cleaning), 2724-W Laundry and the 284-W Powerhouse. Additional pipelines from the 282-W water reservoir, 283-W filter plant and the 277-W fabrication shop also connect to the main pipeline. Portions of this pipeline are associated with the 2724-W building foundation (WIDS sitecode 200-W-64). This pipeline is also associated with 200-W-221-PL (Laundry Waste Crib Pipeline).
Process Description:	The pipeline transported radioactive contaminated laundry and mask cleaning effluent to the 216-U-14 Ditch along with non-radioactive effluent from the powerhouse and shops. The waste originated from the 2723-W (Old Laundry) and 2724-W (New Laundry). 2724-W waste was rerouted to 216-W-LWC (laundry crib) in 1981. After 1984, water from the other buildings continued to use this pipeline, but the waste was collected in the Powerhouse Pond that was built on top of the head end of the 216-U-14 Ditch.
	Soiled protective work clothing (coveralls, gloves, hoods, canvas boots and rubber shoe covers) were sent to the laundry facility from all the Hanford work areas. Two thirds of the laundry received was radioactively contaminated. One third consisted of non contaminated blue coveralls and towels. The non-contaminated laundry was washed separately from the contaminated laundry.
	The masks were radiologically decontaminated at 2706-T prior to being washed and sanitized at the 2723-W mask cleaning station. Therefore, the radiological contamination in the 2723-W floor drains and pipeline should be minimal.
	By 1981, when the effluent was rerouted to 216-W-LWC, approximately three million pounds of laundry was processed per year in 600 pound capacity washing machines and 400 pound capacity dryers. The combined average of 26,250,000 liters (691,000 gallons) of waste water was being discharged from the 2723-W and 2724-W facilities in 1981. It should be noted that portions of the existing pipeline were used to reroute effluent to the 216-W-LWC (see sitecode 200-W-221-PL).
Waste Type:	Process Effluent
Waste Description:	Detergents and radioactive contamination from laundry worn in radiation areas are included in the laundry effluent discharge. A 1945 letter indicates the detergent used at the original laundry facility was named Igepal CA. 3% acetic acid was added to remove beta contamination and 3% citric acid was added to remove alpha contamination. Non-radioactive effluent from the 277-W fabrication shop, the powerhouse and the 283-W filter building.

Code:	200-W-147-PL-A	Classification:	Accepted
Names:	200-W-147-PL-A; Portion of 200-W-147-PL Pipeline in the Central Plateau Outer Area	Reclassification	Interim Closed Out (8/11/2011)
Type:	Radioactive Process Sewer	Start Date:	
Status:	Inactive	End Date:	
Description:	The waste site has been evaluated under a removal action and reclassified to Interim Closed Out. Due to the restructuring of Operable Units, as described in the Agreement for Central Plateau Cleanup, the original site (200-W-147-PL) has been split into separate WIDS sites. It		

was an underground 20 centimeter (8 inch) diameter vitrified clay pipe, extending from the 207-SL retention basin to the 216-S-19 pond. 200-W-147-PL-A is the portion of pipeline that extends south of the manhole, south of 200 West Area in the Outer Area, terminating at the 216-S-19 pond. Subsites were created for the portions of pipeline to the north and to the south of the remediation haul road. Both subsite sections were remediated.

Location: This portion of the pipeline was located in the 600 Area, south of 200 West Area and the 222-S facility. It extends from the manhole located in the Outer Area boundary to the 216-S-19 Pond.

Related Sites/ Structures: This portion of pipeline is associated with the 222-S laboratory waste, the 216-S-19 pond and 200-W-147-PL-B portion of the pipeline that remains in the 200 West Inner Area. It is also associated with subsites 200-W-147-PL-A:1 and 200-W-147-PL-A:2.

Process Description: The pipeline carried waste from the 222-S and 202-S facilities to the 216-S-19 Pond via the 207-SL Retention Basin. In 1984, the 216-S-19 Pond was replaced with the 216-S-26 crib. The pipeline to the crib was connected to the 216-S-19 Pond pipeline at manhole #3 (see 200-W-148-PL). The portion of the pipeline from 207-SL to Manhole #3 continued to be used to feed the 216-S-26 crib until 1995. The portion of pipeline southward from Manhole #3 to the 216-S-19 Pond was abandoned in 1984.

Closure Info: Interim (8/11/2011): The removal action at the 200-W-147-PL-A waste site was conducted from November 2010 through June 2011. The activities included the removal of overburden soil, and the pipeline itself, followed by collection of soil samples from locations within the excavation trench, as prescribed in the SAP (DOE/RL-2009-60). During RTD activities, a portion of the 200-W-147-PL-A pipeline beneath an access road to sites 216-S-19 and 216-S-26, could not be excavated without compromising the integrity of the access road. As a result, the pipeline was split into two subsites in WIDS: 200-W-147-PL-A:1 and 200-W-147-PL-A:2. Both segments were eventually properly remediated. Direct visual inspection of the site surface was performed, using available site information as a guide for visual cues such as staining, discoloration, absence of vegetation, presence of debris, and other anomalies. Radiological field screening was performed at the surface of the waste site to provide an indication of the presence of radiological COPCs.

The removal of the 200-W-147-PL-A:1 and 200-W-147-PL-A:2 subsites of the pipeline, and adjacent soils, was completed using radiological field screening and visual indicators to determine the extent of excavation. Where radiological dose rates greater than background were found, excavation continued in the area. The vertical extent of excavation ranged from 3 to 4.6 m (10 to 15 ft) below ground surface. The lateral extent of excavation at the waste site was determined utilizing visual and radiological indicators.

The waste site was backfilled in July 2011.

This Site has the Following SubSites:

Code: 200-W-147-PL-A:1

Names: 200-W-147-PL-A:1; Southern Portion of the 200-W-147-PL-A Pipeline

Code: 200-W-147-PL-A:2

Names: 200-W-147-PL-A:2; Northern Portion of 200-W-147-PL-A

Code: 200-W-147-PL-A:1

Classification: Accepted

Names: 200-W-147-PL-A:1; Southern Portion of the 200-W-147-PL-A Pipeline

Reclassification: Interim Closed Out (8/11/2011)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: 200-W-147-PL-A:1 is the portion of the pipeline extending from the 216-S-19 pond to a point south of the remediation haul road. 200-W-147-PL-A:1 is approximately 460 meters (1513 feet) long. In April 2011, the open excavation and soil pile created while removing segments of pipeline was removed from radiological control.

Closure Info: Interim (8/11/2011): The removal action at the 200-W-147-PL-A waste site was conducted from November 2010 through June 2011. The activities included the removal of overburden soil, and the pipeline itself, followed by collection of soil samples from locations within the excavation trench, as prescribed in the SAP (DOE/RL-2009-60). During RTD activities, a portion of the 200-W-147-PL-A pipeline beneath an access road to sites 216-S-19 and 216-S-26, could not be excavated without compromising the integrity of the access road. As a result, the pipeline was split into two subsites in WIDS: 200-W-147-PL-A:1 and 200-W-147-PL-A:2. Both segments were eventually properly remediated. Direct visual inspection of the site surface was performed, using available site information as a guide for visual cues such as staining, discoloration, absence of vegetation, presence of debris, and other anomalies. Radiological field screening was performed at the surface of the waste site to provide an indication of the presence of radiological COPCs.

The removal of the 200-W-147-PL-A:1 and 200-W-147-PL-A:2 subsites of the pipeline, and adjacent soils, was completed using radiological field screening and visual indicators to determine the extent of excavation. Where radiological dose rates greater than background were found, excavation continued in the area. The vertical extent of excavation ranged from 3 to 4.6 m (10 to 15 ft) below ground surface. The lateral extent of excavation at the waste site was determined utilizing visual and radiological indicators.

The waste site was backfilled in July 2011.

The SubSite is Part Of:

Code: 200-W-147-PL-A

Names: 200-W-147-PL-A; Portion of 200-W-147-PL Pipeline in the Central Plateau Outer Area

Code: 200-W-147-PL-A:2

Classification: Accepted

Names: 200-W-147-PL-A:2; Northern Portion of 200-W-147-PL-A

Reclassification: Interim Closed Out (8/11/2011)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: 200-W-147-PL-A:2 is the northern portion of this pipeline subsite. It is the portion extending (south) from the manhole to a point south of the remediation haul road, but is the north end of the majority of 200-W-147-PL-A. 200-W-147-PL-A:2 is approximately 26.4 meters (87 feet) long. In July 2011, the open excavation and soil pile created while removing segments of pipeline was removed from radiological control.

Closure Info: Interim (8/11/2011): The removal action at the 200-W-147-PL-A waste site was conducted from November 2010 through June 2011. The activities included the removal of overburden soil, and the pipeline itself, followed by collection of soil samples from locations within the excavation trench, as prescribed in the SAP (DOE/RL-2009-60). During RTD activities, a portion of the 200-W-147-PL-A pipeline beneath an access road to sites 216-S-19 and 216-S-26, could not be excavated without compromising the integrity of the access road. As a result, the pipeline was split into two subsites in WIDS: 200-W-147-PL-A:1 and 200-W-147-PL-A:2. Both segments were eventually properly remediated. Direct visual inspection of the site surface was performed, using available site information as a guide for visual cues such as staining, discoloration, absence of vegetation, presence of debris, and other anomalies. Radiological field

screening was performed at the surface of the waste site to provide an indication of the presence of radiological COPCs.

The removal of the 200-W-147-PL-A:1 and 200-W-147-PL-A:2 subsites of the pipeline, and adjacent soils, was completed using radiological field screening and visual indicators to determine the extent of excavation. Where radiological dose rates greater than background were found, excavation continued in the area. The vertical extent of excavation ranged from 3 to 4.6 m (10 to 15 ft) below ground surface. The lateral extent of excavation at the waste site was determined utilizing visual and radiological indicators.

The waste site was backfilled in July 2011.

The SubSite is Part Of:

Code: 200-W-147-PL-A

Names: 200-W-147-PL-A; Portion of 200-W-147-PL Pipeline in the Central Plateau Outer Area

Code: 200-W-148-PL

Classification: Accepted

Names: 200-W-148-PL; 216-S-26 Crib Pipeline

Reclassification: Interim Closed Out (9/21/2011)

Type: Radioactive Process Sewer

Start Date: 10/1/1984

Status: Inactive

End Date: 6/1/1995

Description: The waste site has been evaluated under a removal action and reclassified to Interim Closed Out. The site had been a 15.2 centimeter (6 inch) diameter vitrified clay pipe that connected the west end of the 216-S-26 crib to pipeline 200-W-147-PL (the original 20 centimeter [8 inch] diameter vitrified clay pipe at manhole #3).

The 200-W-147-PL extended from the 207-SL Retention Basin to 216-S-19 Pond. The 216-S-26 crib was built to replace the 216-S-19 Pond.

Location: The 216-S-26 crib and associated piping was located south of the 200 West Area perimeter fence, southeast of the 222-S building.

Related Sites/ Structures: This site is associated with the 216-S-26 crib and the 200-W-147-PL pipeline.

Closure Info: Interim (9/21/2011): The removal action at the 216-S-26 and 200-W-148-PL waste sites was conducted from March 2011 through August 2011 and included the removal of overburden soil, and the pipe itself, followed by collection of samples from locations within the excavation. Implementation of the selected Remove, Treat, Dispose (RTD) alternative was performed. Soil and piping were removed from the two waste sites. Direct visual inspection of the site surface was performed as a guide for visual cues such as staining, discoloration, absence of vegetation, presence of debris, and other anomalies. Radiological field screening was performed at the excavation surface of the waste site to provide an indication of the extent of radiological contaminants. Soil was removed to a depth of approximately 4.6 meters (15 ft) below ground surface. Characterization sampling was performed at depths of 4.6, 4.9, 5.5, and 6.1 meters (15, 16, 18, and 20 ft) and the analytical results evaluated to demonstrate achievement of Removal Action Objectives. Backfill of the 216-S-26 and 200-W-148-PL waste sites was completed on August 30, 2011.

Code: 216-W-LWC

Classification: Accepted

Names: 216-W-LWC; 216-W-LWC Crib; Laundry Waste Crib; 216-W-1; 216-W-LC

Reclassification: None

Type: Crib	Start Date: 1/1/1981
Status: Inactive	End Date: 1/1/1994

Description: The crib is marked and posted with Underground Radioactive Material signs. The unit consists of two independent crib structures (drain fields) and associated underground pipelines connecting to the (sitecode 200-W-64) laundry facilities. The bottom dimension of each crib is 150 feet (47 meters) by 133 feet (40.5 meters). Each crib structure includes an 8-inch (20 centimeters) PVC, central distribution pipe that runs east-west, 14 feet (4.3 m) below grade. Six 4-inch (10 cm) PVC perforated drain lines extend the length of the unit on both sides (150 ft [47 m]). The drain lines run parallel to each other, 23 feet (7.0 m) apart. Beneath each lies a 5-ft (1.5 m) deep rock-filled trench, giving the bottom a serrated appearance. A 7-foot (2.1 m) layer of gravel fill (5,546 yards [4,243 m]) was backfilled over to grade. The side slope is 1.5:1.

Location: The site is located east of Beloit Ave., south of 20th Street.

Related Sites/ Structures: The crib received effluent from the 2724-W, 2724-WA, 2724-WB Laundry facilities, MO-412 Mask Cleaning facility and the 2723-W Old Laundry. The pipeline from the laundry facility to the Laundry Waste Crib is sitecode 200-W-221-PL.

Process Description: The site is constructed of two cribs, surrounded by a single Underground Material posted area. The Laundry Waste Crib began receiving effluent in 1981 from the Laundry Complex which included the 2724-W, 2724-WA, 2724-WB, MO-406 and 2723-W (Old Laundry). In 1984 mask washing was moved from 2723-W to MO-412, which was placed adjacent to the 2724-W Laundry Complex and became the Mask Cleaning and Maintenance Facility.

Soiled protective work clothing (coveralls, gloves, hoods, canvas boots and rubber shoe covers) were sent to the laundry facility from all the Hanford work areas. Two thirds of the laundry received was radioactively contaminated. One third consisted of blue (non contaminated) coveralls and towels. The non-contaminated laundry was washed separately from the contaminated laundry. By 1981, approximately three million pounds of laundry was processed per year in 600 pound capacity washing machines and 400 pound capacity dryers. An average of 2,615,435 liters (691,000 gallons) of waste water was discharged to the new crib each month.

Waste Type: Water

Waste Description: The site received all the process wastewater (averaging 2,615,435 liters per month) from the contaminated laundry facility (2724-W/WA) and mask cleaning station (MO-412). The waste included radioactive residue from the contaminated laundry and detergents. Bleach and flame retardant chemicals were added to some of the wash and rinse cycles. From 1981 to 1983, some waste oils, from a nearby fabrication shop, entered the waste stream through manhole B. The site became inactive in January 1994 when operations were initiated at an offsite contracted laundry facility. TPA M-17-34 required elimination of all discharge to the Crib by January 1995.

Code: 2607-W1	Classification: Accepted
Names: 2607-W1	Reclassification: None
Type: Septic Tank	Start Date: 1/1/1944
Status: Active	End Date:

Description: The 2607-W1 Septic Tank is constructed of reinforced concrete and receives sanitary wastewater and sewage. There is a drain field associated with the system. This system was reconstructed in 1994.

Location: This unit lies southeast and across Bridgeport Avenue from the associated drain field, and northeast of the 2713-WB Building.

Related Sites/ Structures: The 2607-W1 Septic Tank is associated with the 2607-W1 drain field, 2707-W, 2713-W, 283-W, 277-W, 275-W, 274-W, 284-W, 2723-W, 2704-W, 2719-WB, 272-W, MO-278, MO-279, MO-235, MO-406, MO-412, MO-215, MO-056, MO-204, MO-240, and MO-287.

Process Description: The 2607-W1 Septic Tank and associated drain field are designed to accept sanitary sewer effluent from connected facilities. In 1999, PFP waste was diverted to 2607-W1 when 2607-Z1 shut down. The additional volume was more than 2607-W1 could handle. A new septic system, 2607-W16, was built in 2001 to receive the PFP waste.

Waste Type: Sanitary Sewage

Waste Description: The 2607-W1 septic system received sanitary sewer effluent at an estimated rate of 646 cubic feet (18.3 cubic meters) per day in 1987.

Code: 2607-WL **Classification:** Accepted

Names: 2607-WL; 2607-WL Septic System **Reclassification:** None

Type: Septic Tank **Start Date:** 1/1/1962

Status: Inactive **End Date:** 1/1/1999

Description: The 2607-WL Septic System is constructed of reinforced concrete. The septic system includes a trench-type drainfield. The septic tank and drainfield are surrounded by a chain barricade with a sign stating "Septic Tank" posted.

Location: This unit lies north of the 272-WA Building and west of the 2401-W Building.

Related Sites/ Structures: The 2607-WL Septic Tank is associated with a drain field and the 272-WA Building.

Site 200-W-34 was a duplicate of this site, and has been classified as Not Accepted because it is a duplicate entry. Site 2607-WWA may also be a duplicate of this site.

Process Description: The 2607-WL Septic Tank was designed to accept and treat sanitary sewer effluent from the associated facility, and discharge the effluent to the 2607-WL Drain Field. This drain field in turn, discharges the effluent into the ground.

Waste Type: Sanitary Sewage

Waste Description: The current flow rates for the 2607-WL septic system indicate that the drain field is substantially overloaded. In 1995, this unit received effluent from the associated structure at an estimated rate of 2,760 gallons (10,450 liters) per day. The drain field has a capacity of 628 gallons (2,380 liters) per day.

Code: 600 OCL **Classification:** Accepted

Names: 600 OCL; Original CLF; 600 Area Original Central Landfill **Reclassification:** None

Type: Sanitary Landfill **Start Date:** 1/1/1973

Status: Inactive **End Date:** 1/1/1973

Description: This site is a backfilled trench that is posted "Underground Radioactive Material".

Location: This site is located 2.4 kilometers (1.5 miles) southeast of Army Loop Road and 30.5 meters (100 feet) north of Highway 4 South.

Process Description: The site received miscellaneous trash and debris from the Hanford Site.

Waste Type: Misc. Trash and Debris

Waste Description: This site contains general office wastes, some glass, electrical wastes, and minimal metal wastes. Radioactive contamination was found at this site in 1988 during investigative (test pit) activities.

Code: 600-36

Classification: Accepted

Names: 600-36; Ethel Railroad Siding (Burn Pit)

Reclassification: Interim Closed Out (5/20/2011)

Type: Burn Pit

Start Date:

Status: Inactive

End Date:

Description: The waste site has been evaluated under a removal action and Interim Closed Out. The site had been an area of scattered debris and some evidence of burning, adjacent to the Ethel railroad siding. Metal and wood debris were observed during the pre-remediation visual inspection performed in August 2009. The previously documented batteries and burn pit were also observed. Visual indicators of the burn pit included a circular area approximately 9.1 meters (30 ft) in diameter. Several discrete areas of surface discoloration and devegetation were observed in the eastern portion of the waste site. Historical information suggests the discolored areas may have been caused by a release of oil into the ground surface. Tar like deposits not previously identified were also encountered towards the western portion of the waste site.

Location: The site is approximately 1 mile (1.6 kilometers) northeast of the 200 West Area. It is located northwest of the 251 Electrical Substation, north of Route 11A.

Waste Type: Demolition and Inert Waste

Waste Description: The waste at the unit appears to be from burning activities. The current form of all waste material is solid. No evidence exists (historical or present) that chemical or radiological processes involving sustained releases of materials are associated with this waste site.

Waste Type: Oil

Waste Description: There is evidence of oil spills.

Closure Info: Interim (5/20/2011): The removal action at the 600-36 waste site was conducted between September 2009 and September 2010 and included the collection of focused and random samples from locations within the waste site. Radiological field screening was performed at the surface of the waste site to provide an indication of the presence of radiological COPCs. No radiological readings were greater than the measured background and no radiological contamination was found. The selected alternative for the 600-36 waste site was Confirmatory Sampling/No Further Action (CS/NFA). The results of the initial sampling indicated COPC concentrations greater than the RALs in the six sampled areas. The removal action activities progressed to implementation of the RTD alternative for those areas. As a result of analytical results exceeding the Remedial Action Limits, excavation of soil was done in zones of potential contamination (ZPCs) 2 (battery area) and 4 (burn pit), and focused sample (FS) locations FS 1, FS 2, FS 3 (stained and devegetated areas) and FS 5 (tar deposits). Excavation of soil at FS 4, which was considered analogous to FS 1, FS 2, and FS 3 based on visual indicators.

Code: 600-37

Classification: Accepted

Names: 600-37; Browns Wells; Johnson's Wells

Reclassification: Interim Closed Out (3/2/2011)

Type: Injection/Reverse Well**Start Date:****Status:** Inactive**End Date:**

Description: The waste site has been evaluated under a removal action and Interim Closed Out following sampling of the dry wells per SAP DOE/RL-2009-60. Analytical results were less than RALs, thus no action was required. The dry wells and above ground tanks at waste site 600-37 were left in place. The dry wells were not backfilled. They are listed on the UIC Master List as UU221.

The waste site consists of four steel tanks and dry wells. The tanks had been resting on railroad ties approximately 1.2 meters (4 feet) above ground. A range fire burned through the area in June 2000. The southern-most tank was untouched by the fire and the tank supports remain intact. The wooden support structures under the other three tanks were burned and the tanks are now sitting on the ground. The dry wells are double encased with pipe used to center the inner casing within the outer casing. Three of the dry wells have a inside diameter of 38 centimeters (15 inches) and are approximately 4.9 meters (16 feet) deep. The fourth dry well has a much larger diameter, differs from the others with an outside diameter of 2.18 meters (7 ft). It contains an internal substructure in the form of a separate pipe oriented the same as the outer casing. The upper ends of the outer and inner structures terminate at the outer French drain cover. The dry wells were unaffected by the fire in June 2000. There is a dirt road that runs through the unit that appears to be surfaced with used oil.

Location: The site is located southeast of 200 West at the southern boundary of the Environmental Restoration Disposal Facility (ERDF) land easement.

Process Description: The four steel tanks appear to be of military origin. The configuration of the wells and tanks appear appropriate for an infiltration test. Raw water was assumed to have been disposed of in the wells, however sample testing should be conducted in the unit.

Waste Type: Water

Waste Description: Raw water was assumed to have been disposed of in the dry wells, however sample testing is needed to confirm this theory.

Closure Info: Interim (3/2/2011): The 600-37 waste site was reclassified as interim closed out following sampling of the dry wells per SAP DOE/RL-2009-60. Analytical results were less than Removal Action Limits, thus no action was required. The dry wells and above ground tanks at waste site 600-37 were left in place and the dry wells not backfilled.

Soil sampling was conducted between May 18 and 26, 2010. Soil samples were collected from bottom surfaces inside each of the four french drains. The french drains were approximately at 4.9 meters (16 ft) deep. The soil media was a fine soil type collected from beneath the gravel layer in each French drain. One sample was collected from French drain 1, one sample was collected from French drain 2, and one sample was collected from French drain 4. Two samples were collected from the large diameter French drain, known as French drain 3. One sample was taken from the inside the drain structure and one from the annular space between the inner and outer structure.

No radiological postings were present at the waste site. Of the radiological surveys performed during removal action activities, all radiological dose readings were at or below the measured background and no radiological contamination was found.

Code: 600-38**Classification:** Accepted**Names:** 600-38; Railroad Siding Susie; Susie Junction; 600-25**Reclassification:** Interim Closed Out (2/25/2011)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The waste site has been evaluated under a removal action and reclassified to Interim Closed Out. The waste site was at the "Susie" railroad junction. The northeast corner of the junction had an excavated area that may have contained a siding for decontamination of railroad cars.

In 1996, an employee interview stated that debris had been "picked up" by unknown parties, but most of the railroad maintenance equipment was left at the site.

Location: The waste site was located at the southeast quarter of the southeast quarter of the southeast quarter of Section 24, Township 13 North, Range 25 East. "Susie" junction is southwest of Gable Butte. It is north of Route 11A and east of Route 6.

Related Sites/ Structures: The waste site is at the junction of two railroad tracks, known as Susie Junction.

Waste Type: Asbestos (friable)

Waste Description: The site waste potentially included asbestos.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: The site waste included drums.

Waste Type: Equipment

Waste Description: The site contains railroad maintenance equipment.

Waste Type: Misc. Trash and Debris

Waste Description: The site contained miscellaneous trash.

Closure Info: Interim (2/25/2011): Waste Site 600-38 was investigated between December 2009 and March 2010 through field observations and sampling to determine the nature and extent of contaminants of potential concern (COPCs) present in the waste site soils as part of the selected removal action alternative of CS/NFA prescribed in the Action Memorandum. This investigation was performed in accordance with DOE/RL-2009-60, Sampling and Analysis Plan for Selected 200-MG-1 Operable Unit Waste Sites and DOE/RL-2009-53, Removal Action Work Plan for 11 Waste Sites in the 200-MG-1 Operable Unit (RAWP). Through the investigation summarized in this report, it was found that analytical results from confirmatory sampling demonstrated that soil conditions at the waste site did not meet removal action levels (RALs). Therefore, in accordance with the methodology prescribed in the Action Memorandum, the alternative was changed to removal, treatment, and disposal (RTD). The removal action at the 600-38 waste site was conducted between March and October 2010 and included the collection of focused and/or random samples from locations within the waste site.

Direct visual inspection of the site surface was performed, using available site information as a guide for visual cues such as staining, discoloration, absence of vegetation and other anomalies. Observations made during the site walk down included areas of devegetation, areas of darkened soil, and scattered debris consisting of rusted 18.9 liter (5 gallon) containers, metal, wood pallets, and refuse. Based on these observations, 16 individual zones of potential concern (ZPCs) were established at the 600-38 waste site to facilitate an organized removal action approach. Radiological field screening was performed at the surface of the waste site to provide

an indication of the presence of radiological COPCs. No radiological postings were present at the waste site. Of the radiological surveys performed during removal action activities, all radiological readings were at or below measured background, and no radiological contamination was found.

Backfill of the 600-38 Waste Site was completed on February 9, 2011.

Code: 600-40	Classification: Accepted
Names: 600-40; West of West Lake Dumping Area	Reclassification: Interim Closed Out (7/21/2011)
Type: Dumping Area	Start Date:
Status: Inactive	End Date:

Description: This waste site has been remediated. The site had been an old dumping area. The debris was mostly consolidated in one of two locations, either along the road or on the hillside. The waste site included concrete rubble, wood, roofing materials, and miscellaneous metal debris and containers. The area along the road was approximately 364 square meters (3918 square feet). The portion on the hillside was 123 square meters (1324 square feet) in area. The area listed in the dimensions field represents the total area of both dumping areas. Additionally, a few pieces of scattered debris was found on the hillside. The debris at 600-40 was removed and sent to ERDF.

Location: The site was located in the 600 Area, east of route 4 North and 105 meters (345 feet) west of West Lake. The debris was located on a dirt road at the T-intersection from 4 North to West Lake. Additional debris was found on the hillside that slopes down to West Lake.

Process Description: This area is a former waste dump site.

Waste Type: Misc. Trash and Debris

Waste Description: The waste along the dirt road includes chunks and slabs of concrete, lumber, miscellaneous metal debris, rusted cans approximately 30.5 centimeters in diameter and 40.6 centimeters tall (12 inches in diameter and 16 inches tall), and what appears to be roofing (black, tarry sheets with gravel) materials. On the hillside are 2 small wooden structures approximately 1.8 meters by 1.8 meters by 1.2 meters (6 feet by 6 feet by 4 feet), a pile of wooden posts with each post approximately 20.3 centimeters in diameter and 1.8 meters long (8 inches in diameter and 6 feet long), other wood debris, what appears to be a wheelbarrow, and 2 large rusted metal cans approximately 20.3 centimeters by 20.3 centimeters by 35.6 centimeters tall (8 inches by 8 inches by 14 inches tall) and 30.5 centimeters in diameter by 35.6 centimeters tall (12 inches in diameter by 14 inches tall).

Closure Info: Interim (7/21/2011): The waste site was comprised of two discrete debris dump sites. One was located adjacent to the gravel access road, at the T of the access road intersection, known as Zone of Potential Contamination (ZPC 1). The second area was located on the hillside that slopes down toward West Lake (known as ZPCs 2, 3a, and 3b). Initial sampling and analysis indicated that soil concentrations of COPCs were greater than the RALs, thus confirming the implementation of the RTD alternative. Activities involved in the RTD action including soil excavation and verification sampling to demonstrated that the remaining in situ COPC concentrations in soil are less than or equal to the established RALs, and that no additional removal action is required. No radiological dose readings were greater than the measured background, and no radiological contamination was found. Excavation at the four ZPCs commenced in March 2010. Soil removal occurred to a total depth of approximately 0.6 meters (2 ft) and was laterally bound by the areas of wood debris and areas void of surface vegetation. Additionally, three test pits, each evaluated to a total depth of approximately 4.7 meters (15 ft)

below ground surface, were dug east of ZPC 1 to verify that the extent of the 600-40 waste site was limited to the area of excavation. Backfill of the 600-40 waste site was completed on May 26, 2011.

Code: 600-49	Classification: Accepted
Names: 600-49; H-42 Gun Site Building Foundations, Ammunition Storage and Small Arms Firing Range	Reclassification: Interim Closed Out (8/11/2011)
Type: Foundation	Start Date:
Status: Inactive	End Date: 1/1/1958

Description: The waste site has been evaluated under a removal action and Interim Closed Out. It consisted of six concrete foundations, concrete footings and miscellaneous concrete and gravel walkways. Four circular ammunition storage berms, each measuring about 25 meters (80 feet) in diameter, were located in the eastern portion of the site. The wood and part of the sandbags were consumed in the July 2000 fire. The six concrete building foundations measured:

1. kitchen/mess hall with four floor drains, 12.4 meters by 10 meters (40.5 feet by 32.5 feet)
2. toilet/showers with five floor drains, ten toilet drains, 15.4 meters by 6.3 meters (50.5 feet by 20.5 feet)
3. concrete pad, 6.6 meters by 15.4 meters (21.5 feet by 50.5 feet)
4. concrete pad, 4 meters by 6 meters (13 feet by 20 feet)
5. concrete pad, 2.4 meters by 2.4 meters (8 feet by 8 feet)
6. concrete pad, 6 meters by 7.3 meters (20 feet by 24 feet).

A small arms firing range is located southeast of the revetment.

Location: The site was located 6.4 kilometers (4 miles) south of 200 East Area, on the south side of Army Loop Road and east of the powerline road to Rattlesnake Mountain.

Related Sites/Structures: WIDS site 6607-2, Gun Site H-42 Septic Tank, received waste from the kitchen sinks, floor drains and the toilet/shower house. Site 600-226 is the dumping area for this base.

Process Description: This is the location of a former U. S. Army anti-aircraft gun site. Typically, Camp Hanford's anti-aircraft artillery sites were each roughly 20 acres in size and contained any number of buildings (typically around 20), various utility distribution systems, roads, and sidewalks. Each site consisted of emplacements protected by revetments made of sandbags and wood planking, wooden structures, prefabricated metal buildings, and, later, permanent, concrete block structures. The prefabricated buildings had aluminum walls and roofs with wooden or concrete floors set on concrete pier blocks and were the most commonly constructed. The permanent structures included barracks, latrines, mess halls, craft shops, pump houses, motor pools, and radar facilities. Each site typically had a small arms range, water storage cistern, sanitary, and sewage disposal facilities. Pathways, sidewalks, roadways, and parking lots connected the structures.

Waste Type: Demolition and Inert Waste

Waste Description: Concrete building foundations, pads and walkways, pipe, sandbags and sheetmetal remain.

Closure Info: Interim (8/11/2011): The removal action at the 600-49 waste site was conducted between May and June 2011. Activities included direct visual inspection of the site surface using available site information as a guide for visual cues such as staining, discoloration, absence of vegetation and other anomalies; the collection of random verification samples from locations within the shooting range backstop of the waste site and excavation of soil under the RTD alternative from

shooting range backstop to eliminate a source of contamination from lead slugs remaining in the soil. Observations made during previous site evaluations indicated the presence of six concrete foundations and footings, walkways, four artillery emplacements marked by revetments, and some sheet metal and pipe. Radiological field screening performed at the surface of the waste site to provide an indication of the presence of radiological COPCs. No chemical or radiological processes involving sustained releases of material are associated with this site. No radiological contamination was found. The available 600-49 waste site historical information and process knowledge was sufficient to proceed directly to implementation of the RTD alternative without requiring additional field observations or sampling to determine the nature and extent of contaminants of potential concern (COPCs) present in the waste site soil. The shooting range backstop consisted of soil mounded elevated greater than the general surface grade of the area. The mound was removed. No depression was created in the ground surface RTD activities, so backfilling was not required.

Code: 600-51 **Classification:** Accepted

Names: 600-51; Chemical Dump; Pile of White Powder **Reclassification** Interim Closed Out (2/9/2011)

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The waste site has been evaluated under a removal action and Interim Closed Out. The site is an elliptical area with little or no vegetation.

Location: This site is located west of Route 4 North, between Route 1 and Route 11A. It is between the 1901-Z Building and well 699-64-62, just west of the export water line.

Waste Type: Chemicals

Waste Description: A sample of this material was analyzed with the HAZCAT field analysis kit. The bulk of this material appears to be a sodium compound.

Closure Info: Interim (2/9/2011): The waste site was first identified in 1994. Shortly after being discovered, a HAZCAT field sampling kit was used to determine to powder was a sodium substance. A site visit in October 1999 found the pile of material was no longer present. The 600-51 waste site was investigated again in October 2009 through field observations. The original alternative for 600-51 was anticipated to be Remove, Treat and Dispose (RTD). Historical photographs of the pile of white powder (when it was present on the site) defined conservative northern and southern boundaries of the piles footprint. The silty, sandy, and rocky soil matrix showed no signs of discoloration. Confirmatory sampling was done to determine the nature and extent of contaminants of potential concern (COPCs) present in the waste site soils. It was determined that site conditions met removal action levels (RALs) and removal action objectives (RAOs) without further removal action. In accordance with the methodology prescribed in the Action Memorandum, the alternative was changed from RTD to confirmatory sampling/no further action (CS/NFA).

Code: 600-65 **Classification:** Accepted

Names: 600-65; 607 Batch Plant Drum Site **Reclassification** Interim Closed Out (4/12/2011)

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: This waste site has been reclassified to Interim Closed Out. In 1995, two crushed and flattened 55-gal drums, one oil filter housing (approximately 2 quarts [1.9 liters]), a metal cable, one

large concrete block (0.5 cubic yards [0.4 cubic meters]), and indications of possible petroleum disposal were identified. In 2001, the items noted above could not be located, and the area is possibly being used for fill material. Further investigations were conducted between June 2010 and February 2011 through field observations and sampling to determine the nature and extent of contaminants of potential concern.

Location: The debris was located approximately 0.5 miles east of the 200 Area Fire Station. It is west of 200 East Area on the north side of Route 3, near Gravel Pit 30.

**Related Sites/
Structures:** 607 Batch Plant Gravel Pit

Waste Type: Oil

**Waste
Description:** Two crushed and flattened 55-gal drums, one oil filter housing, one large concrete block, and indications of possible petroleum disposal. In October 2001 these items could not be located at the site.

Closure Info: Interim (4/12/2011): The removal action at the 600-65 waste site was conducted between June 2010 and February 2011. It included the collection of focused and random samples from locations both within the boundaries of the waste site and in surrounding areas. The original selected alternative for the subject waste site was Remove Treat and Dispose (RTD). This alternative was selected because, based on the types of debris present, concentrations of contaminants of potential concern (COPCs) had the potential to exceed the Removal Action Levels (RAL). Investigative sampling and analysis demonstrated that soil concentrations of contaminants were less than or equal to the Remedial Action Levels without the need for further action. As a result, in accordance with the Action Memorandum, the alternative was changed to Confirmatory Sampling/ No Further Action (CS/NFA). Field activities included ground penetrating radar (GPR) scanning, radiological surveys and soil sampling. The GPR scan and metal detector survey performed at the last known location of the drums and oil filter identified one anomaly within the WIDS boundary of the 600-65 waste site approximately 1 meter (3 ft) below ground surface and a second anomaly within a mound of overburden. No radiological readings were greater than the measured background, and no radiological contamination were found. Analytical results from the investigative sampling evolution at the 600-65 waste site showed that concentrations of COPCs were less than or equal to RALs, thereby demonstrating compliance with the established RAOs. Sample results determined excavation was not required at the 600-65 waste site. These results also support reclassification to Interim Closed Out status.

Code: 600-66 **Classification:** Accepted

Names: 600-66; 607 Batch Plant Orphan Drums **Reclassification:** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The site consists of one rusted 55-gallon (208 L) drum laying on the ground surface on its side. No label or hazardous substance are evident.

Location: The drum is located north of Route 3, approximately 400 meters (1300 feet) east of the 607 Batch Plant.

**Related Sites/
Structures:** The abandoned drum may be associated with the Batch Plant.

Waste Type: Barrels/Drums/Buckets/Cans

**Waste
Description:** The waste consists of two rusted drums, contents unknown.

Code: 600-71 **Classification:** Accepted
Names: 600-71; 607 Batch Plant Burn Pit **Reclassification:** None
Type: Burn Pit **Start Date:**
Status: Inactive **End Date:**

Description: The site consists of an area of charred ground, a piece of rusted sheet metal and small pieces of debris. In June 2004, the expansion of Gravel Pit 30 pushed soil over the northern portion of the 600-71 Burn Pit.

Location: The site is located west of route 4, north of route 3. Precisely, on the batch plant entrance road turn east on the first dirt road; follow road for about 350 meters (1150 ft); walk north about 70 feet (23 meters) to the site.

Related Sites/ Structures: The 607 Batch Plant is adjacent to the Burn Pit.

Process Description: Although the Burn Pit is located adjacent to the Batch Plant, it does not seem to be associated with the Batch Plant operation.

Waste Type: Misc. Trash and Debris

Waste Description: Metal, wood, glass, and rubber debris. Charred remains of burned material. This material was still present during the 2002 site visit.

Code: 600-218 **Classification:** Accepted
Names: 600-218; H-61-H Anti-Aircraft Artillery Site **Reclassification:** Interim Closed Out (7/21/2011)
Dumping Area
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The waste site has been evaluated under a removal action and Interim Closed Out. It consisted of demolition debris consisting of wood, pipe, barbed wire, metal fence posts, empty oil cans, empty paint cans, food cans, and sheet metal. The dumping area was irregularly shaped and was comprised of two distinct areas. The larger area measured 20 meters by 74 meters (67 feet by 243 feet). The smaller area was approximately 48 meters (157 ft) northeast of the larger portion, and was rectangular in shape, measuring approximately 1.5 meters (5 ft) by 1.8 meters (6 ft).

Location: This site was located just southwest of the intersection of Route 11 and Route 6. It is 0.4 miles south of Route 11 and just west of Army Loop Road. The site is in the east half of the northeast quarter of Section 34, Township 13 north, Range 25 east. The dumping area is located in the SW portion of the site.

Related Sites/ Structures: This dumping area is related to the Anti-Aircraft site 600-216.

Waste Type: Demolition and Inert Waste

Waste Description: Wood waste from former buildings, concrete footings, pipe, sheet metal, barbed wire, steel fence posts.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Empty oil cans, paint cans with dried paint.

Description:

Closure Info: Interim (7/21/2011): The dumping area was irregularly shaped and was comprised of two distinct areas. The larger area measured 20 meters by 74 meters (67 feet by 243 feet). The smaller area was approximately 48 meters (157 ft) northeast of the larger portion, and was rectangular in shape, measuring approximately 1.5 meters (5 ft) by 1.8 meters (6 ft). It consisted of demolition debris consisting of wood, pipe, barbed wire, metal fence posts, empty oil cans, empty paint cans, food cans, and sheet metal. The analytical results from initial sampling demonstrated that soil conditions at the waste site did not comply with established removal action levels (RALs). Therefore, the alternative was changed to removal, treatment, and disposal (RTD). The removal action at the 600-218 waste site was conducted between August 2009 and May 2011, and included the collection of statistically based random and focused samples from locations within the boundaries of the waste site. Nineteen random locations were selected. Locations R4, R9, R11 and R17 were sampled at depths of 4 feet and 8 feet. Soil excavation was required at location R3 and R14. Samples were collected from the excavated areas for remedial verification.

Radiological surveys performed for the 600-218 waste site resulted in no radiological dose readings greater than the measured background, and no radiological contamination was found.

Since RTD activities were limited in depth to less than 0.6 meters (2 ft) (i.e., surface debris removal at the waste site), backfill was not required at the 600-218 waste site.

Code: 600-220	Classification: Accepted
Names: 600-220; H-51 Anti-Aircraft Artillery Site Dumping Area	Reclassification: Interim Closed Out (8/11/2011)
Type: Dumping Area	Start Date:
Status: Inactive	End Date: 1/1/1958

Description: The waste site has been evaluated under a removal action and Interim Closed Out. It consisted of three dumping areas. One area was surrounded with T-posts. Observations made during the 2010 site evaluation included an area covered with a white, granular material, an area containing burned material and other debris, a small area containing what appeared to be a tar-like substance, an area of visible debris such as partially buried containers, and a mound containing a wide variety of debris such as heavily corroded metal cans and containers, glass, and batteries. In addition, two mounds were observed that might have been used as a firing range containment berm. The debris at 600-220 was determined to be culturally significant and was not removed.

Location: The site was on Army Loop Road, approximately 2 miles southwest of 200 West Area and extends to the southwest near SR 240. This site is located in the southeast quarter of Section 15, Township 12 North, Range 25 East.

Related Sites/Structures: This site is associated with 600-53, the site building foundations, and 6607-3, the site's septic system.

Process Description: The dumps are located in three general areas. The July 2000 fire burned off all flammable material, such as wood, that had remained at the site. The dump area with the T-posts around it contains metal, transite, fluorescent light bulbs, metal ducting, fiberglass insulation, an unknown white granular substance, pipe, and wire. The second area is mostly wood, little remains now. The third area is a relatively large area consisting of empty cans and empty food, oil, paint and bleach bottles. Several wooden ammunition boxes and cardboard canisters were observed before 2000, but are now gone. The area appears to have been scraped with a

bulldozer. Several waste materials are partially buried. The permanent structures included barracks, latrines, mess halls, craft shops, pump houses, motor pools, and radar facilities. Each site typically had a small arms range, water storage cistern, sanitary, and sewage disposal facilities. Pathways, sidewalks, roadways, and parking lots connected the structures.

Waste Type: Misc. Trash and Debris

Waste Description: Wood, metal, transite, fiberglass, piping, glass, fluorescent light tubes, a white granular substance, empty cans, buckets, and bottles, fence posts, barbed wire, and concrete.

Waste Type: Asbestos (non-friable)

Waste Description: Transite siding

Closure Info: Interim (8/11/2011): The analytical results from confirmatory sampling demonstrated that soil conditions at the waste site did not meet removal action levels (RALs). Therefore, the alternative was changed to removal, treatment, and disposal (RTD). Radiological surveys performed during sampling activities indicated no radiological readings greater than the measured background, and no radiological contamination was found.

Seven Zones of Potential Concern (ZPC) and three biased locations were established during site evaluation. Focused samples were collected from ZPCs 1 through 4 and biased samples at BS 1 through 3 based on historical and process knowledge and visual indicators from the surface, which is generally defined as 0 to 0.3 m (0 to 1 ft) below ground surface. Random samples were collected from ZPC 5 through 7 (using Visual Sample Plan (VSP) software as direct visual indicators were absent for these ZPCs). Analytical results from the initial sampling evolution indicated contaminants of potential concern (COPC) concentrations exceeded Removal Action Levels in three areas; ZPC 1 (white granular material), ZPC 2 and BS 1 (debris areas) and BS 2 (battery area) thus initiating RTD in those areas. The areas comprising ZPC 1, ZPC 2, and BS 1 were excavated to a vertical depth of approximately 0.9 to 1.2 meters (3 to 4 ft) below ground surface. In addition to the removal of the impacted soil from ZPC 1, ZPC 2, and BS 1, miscellaneous scattered debris, along with approximately 0.9 to 1.2 meters (3 to 4 ft) of underlying soil, was removed, thus enlarging the area of excavation beyond the three areas of impact identified during initial and in process sampling.

Code: 600-222

Classification: Accepted

Names: 600-222; H-60 Gun Site

Reclassification: Interim Closed Out (2/25/2011)

Type: Military Compound

Start Date:

Status: Inactive

End Date:

Description: The waste site has been evaluated under a removal action and Interim Closed Out. There was very little evidence of the former military gun site. A few trees, walkways, roads and an old "Underground Telephone - Contact Signal Officer before excavating" warning sign is present (a second "underground telephone" sign burned in the July 2000 fire). After the July 2000 fire, other material left at the site has become visible, including pieces of ceramic pipe, a dumpsite with two oil filters, coat hangers, and a few small pieces of transite siding. South of the access road are several small piles of decayed batteries or fuses.

Location: The H-60 Gun site was located approximately 1.2 miles west of 200 West Area and is just east of SR240.

Process Description: Several artillery were installed around the 100 and 200 Areas to protect the chemical separation plants and reactors from attack by air. Typically, the artillery sites consisted of residential and office buildings, with gun emplacements situated within semi-circular revetments made of

sandbags and wood planking, which were located separately from the residential and administrative facilities. Buildings at these sites were often prefabricated lumber, metal, and concrete block structures for residential and office use. The use of these gun sites ended in the mid to late 1950s, at which time the structures were removed or demolished.

Waste Type: Batteries

Waste Description: South of the main area and access road are several small piles of decayed batteries or fuses. In another pile are two oil filters, one whole and the other in parts.

Closure Info: Interim (2/25/2011): As a result of the field investigation, it was found that analytical results from confirmatory sampling demonstrated that soil conditions at the waste site did not meet removal action levels (RALs). Therefore the remedy was changed to removal, treatment, and disposal (RTD). The removal action at the 600-222 Waste Site was conducted between April and December 2010, and included the collection of focused samples. The key activities pertinent to the removal action included collecting soil samples based on visual indicators, excavating soil in the zone of potential contamination (ZPC) 3, and areas identified by focused sample locations FS 1, FS 2, FS 2b, and FS 4 as a result of analytical results exceeding the RALs and removing debris and underlying soil at FS 3, as a result of visual indicators. Random and focused samples were collected from the excavated areas for verification purposes, laboratory analysis for COPCs, and evaluation of analytical results to demonstrate compliance with the RALs.

The key activities pertinent to the removal action at the 600-222 Waste Site included the collection of judgmental soil samples based on visual indicators, excavation of soil, under the Remove, Treat, Dispose (RTD) alternative, in the zone of potential contamination (ZPC) 3, and areas identified by focused sample locations FS 1, FS 2, FS 2b, and FS 4 as a result of analytical results exceeding the RALs and the removal of debris and underlying soil at FS 3 as a result of visual indicators. Observations made during a site walkdown in 1997 found little evidence remained of the former artillery site. Features observed included roadways, a few trees, and a sign marking an underground telephone line. Miscellaneous debris included various metal items, small batteries or fuses, ceramic piping, oil filters, and transite siding. Batteries, oil filters, and miscellaneous debris were physically located outside the previously established waste site boundary. However, since these items are included in the site historical site description, the observed debris was considered part of the 600-222 Waste Site, and was included within the scope of this removal action.

Excavation at the 600-222 Waste Site commenced on October 14, 2010. The extent of excavation at the areas impacted was initially determined from the sampling data, using visual indicators to guide excavation depth during RTD. The initial depth of excavation in the impacted areas was determined to be approximately 0.6 meters (2 ft) bgs. In process sampling and chemical field screening were conducted during RTD activities in the areas of excavation at the 600-222 Waste Site. Analytical results of the in-process sampling indicated concentrations of lead (FS 2 only) and total petroleum hydrocarbon (TPH) diesel (FS 1 only) were still present at concentrations greater than the RALs. As a result, in conjunction with the chemical field screening, the excavation depth was further refined to approximately 1.5 meters (5 ft) bgs at FS 1 and FS 2b, and 0.9 meters (3 ft) at FS 2. Although analytical results indicated COPC concentrations were less than the RALs at FS 3, debris in that area was removed during RTD activities, along with underlying soil to a depth of approximately 0.6 meters (2 ft). Backfill activities were completed on February 9, 2011. In accordance with the ecological compliance review conducted for the 600-222 Waste Site, this area does not meet the requirements of a Level III or Level IV designation as described in DOE/RL-96-32, Hanford Site Biological Resources Management Plan; therefore, revegetation at the 600-222 Waste Site is not required.

Code: 600-226

Classification: Accepted

Names: 600-226; Gun Site H-42 Dumping Area **Reclassification** Interim Closed Out (5/20/2011)

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:** 1/1/1958

Description: The waste site has been evaluated under a removal action and Interim Closed Out. The site was an old dumping area for an anti-aircraft site. The surface of the site has scattered and decaying debris including pipe, glass, empty buckets, slightly rusted (not corroded) 55-gallon drum, dried paint, cans, transite, broken concrete, and dry cell batteries. Wood had formerly been present, but was burned in the June 2000 fire (see sitecode 600-281). The range fire in June 2000 exposed several additional areas of debris. This debris included material suspected to be asbestos, glass, metal pipes, gauges, military issue dishes, and other sundry items. Even though the additional exposed debris was presumed to be associated with the H-42 Gun Site (based on the type of debris) and was in close proximity to the 600-226 waste site, these areas were incorporated into the 600-281 waste site.

Location: The site is located 4 miles south of 200 East Area, on the south side of Army Loop Road and on both the east and west sides of the powerline road to Rattlesnake Mountain.

Related Sites/ Structures: This is a dumping area for 600-49, the H-42 Gun Site Building Foundation and Ammunition Storage location. The septic system is site 6607-2. More debris is documented in sitecode 600-281.

Process Description: Typically, Camp Hanford's anti-aircraft artillery sites were each roughly 20 acres in size and contained any number of buildings (typically around 20), various utility distribution systems, roads, and sidewalks. Each site consisted of emplacements protected by revetments made of sandbags and wood planking, wooden structures, prefabricated metal buildings, and, later, permanent, concrete block structures. The prefabricated buildings had aluminum walls and roofs with wooden or concrete floors set on concrete pier blocks and were the most commonly constructed.

The permanent structures included barracks, latrines, mess halls, craft shops, pump houses, motor pools, and radar facilities. Each site typically had a small arms range, water storage cistern, sanitary, and sewage disposal facilities. Pathways, sidewalks, roadways, and parking lots connected the structures.

Closure Info: Interim (5/20/2011): The Remove, Treat, Dispose (RTD) alternative was selected for 600-226 as the preferred alternative as documented in the Action Memorandum. The RTD action included excavation of contaminated soil and other materials. Direct visual inspection of the surface of the 600-226 waste site was conducted, using available information as a guide for visual cues such as staining, discoloration, absence of vegetation, and other anomalies. The visual inspection incorporated observational indicators and historical information to identify areas of concern, which included several rusted metal containers of various capacities (18.9 liters [5 gallon], 3.78 liters [1 gallon], and 0.94 liters [0.25 gallon]) scattered over an area approximately 3.71 square meters (40 square feet) in size. Radiological field screening was conducted at the surface of the waste site to provide an indication of the presence of radiological contaminants. Surface geophysical surveying (using ground penetrating radar) was conducted to identify subsurface features. Chemical field screening performed during RTD activities was used to verify the extent of contamination or, in conjunction with visual indicators, to identify areas of potential contamination that would require RTD. During RTD activities, a section of metal bar stock was observed projecting above the ground surface near the 600-226 waste site. As a result of operational safety concerns, the metal bar stock was removed, which led to the discovery of additional assorted metal debris. The unearthed metal was collected for disposal. Revegetation at the 600-226 waste site is not required, however, the 600-226 waste site has been reseeded.

The removal action at 600-226 was conducted between January and December 2010. Key activities were pertinent to the removal action at 600-226 included collecting investigative soil samples based on visual indicators, excavating impacted soil that, due to analytical results, exceeded the RALs, collecting bias samples from the area adjacent to the excavation to demonstrate that the extent of contamination has been mitigated by the excavation and is bounded by the verification samples and collecting random samples from excavated areas for verification purposes. Backfill and contouring was completed on March 3, 2011.

Code: 600-227	Classification: Accepted
Names: 600-227; H-40 Gun Site Building Foundations	Reclassification: None
Type: Foundation	Start Date:
Status: Inactive	End Date: 1/1/1958

Description: The site has eight building foundations, four ammunition storage structures and a valve pit remaining.

The foundations are: #1. Kitchen/mess hall foundation with four floor drains: 12.4 meters by 9.8 meters (40.5 feet by 32 feet) #2. Shower/toilet foundation with five floor drains and ten toilet drains: 6 meters by 16.5 meters (20 feet by 54 feet) #3. Concrete pad: 4 meters by 3.2 meters (13.5 feet by 10.5 feet) #4. Concrete pad: 15 meters by 7.3 meters (49.5 feet by 24 feet) #5. Concrete pad: 3.7 meters by 5.5 meters (12 feet by 18 feet) #6. Concrete pad: 1.8 meters by 2.4 meters (6 feet by 8 feet) #7. Concrete pad: 5.5 meters by 6.7 meters (18 feet by 22 feet) #8. Concrete pad: 3.7 meters by 6.4 meters (12 feet by 21 feet). The valve pit is a vertical steel culvert, 1.2 meters (4 feet) in diameter by 1.5 meters (5 feet) deep. The water main to the site is visible in the bottom of the pit, with a valve and pipes branching off toward to individual buildings.

The four ammunition storage structures on top of the hill are constructed of rock, soil, sandbags, wood, metal and tar paper. The ammunition storage bunkers are approximately 23 meters (75 feet) in diameter. On the south side of the site is a concrete-transite pipe 35 centimeters (14 inches) high, and 10 centimeters (5 inches) in outside diameter. At the base of the pipe are pebbles averaging 4 centimeters (1.5 inches) in diameter. Neither the pipe nor the pebbles are stained. An area surrounding the pebbles is evidence of boards that have burned away, about 1.8 meters (72 inches) by 2 meters.

Location: This site is located southeast of the 200 East Area, on the south side of Route 4 South. Trees viewed from Route 4 South aid in locating the site.

Related Sites/ Structures: The septic system for this area is 6607-1 and 600-228 is the associated dumping areas.

Process Description: Typically, Camp Hanford's anti-aircraft artillery sites were each roughly 20 acres in size and contained any number of buildings (typically around 20), various utility distribution systems, roads, and sidewalks. Each gun site consisted of emplacements protected by revetments made of sandbags and wood planking, wooden structures, prefabricated metal buildings, and later, permanent, concrete block structures. The prefabricated buildings had aluminum walls and roofs with wooden or concrete floors set on concrete pier blocks and were the most commonly constructed. The permanent structures included barracks, latrines, mess halls, craft shops, pump houses, motor pools, and radar facilities. Each site typically had a small arms range, water storage cistern, sanitary, and sewage disposal facilities. Pathways, sidewalks, roadways, and parking lots connected the structures.

Waste Type: Demolition and Inert Waste

Waste Description: Concrete foundations, pipe, wood and sandbags remain at the site.

Code: 600-228 **Classification:** Accepted
Names: 600-228; H-40 Gun Site Dumping Area **Reclassification:** Interim Closed Out (9/21/2011)
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:** 1/1/1958

Description: The waste site has been evaluated under a removal action and Interim Closed Out. The site included four dumping areas, located in pits in the southern portion of the H-40 area. The pit located west of the main site measured about 12 meters (40 feet) in diameter and contains sheetrock, metal, transite, glass and empty paint cans. Two small pits, located south of the main site, were each about 4 meters (15 feet) in diameter. One pit was empty and the other contains steel fence posts and barbed wire. The largest pit was to the south-southeast, and on the topographic slope facing to the south. It contained a large quantity of metal objects, as well as some transite and glass. The July 2000 fire burned much of the wood debris in this pit and the western pit.

Location: This site is located southeast of the 200 East Area, on the south side of Route 4 South. Trees viewed from Route 4 South aid in locating the site. The dumping areas are located to the southeast and west of the H-40 Gun Site.

Related Sites/ Structures: This site is related to 600-227 (the building foundations), and 6607-1 (the septic tank).

Process Description: These pits received debris from several years of military operation of the anti-aircraft site. Typically, Camp Hanford's anti-aircraft artillery sites were each roughly 20 acres in size and contained any number of buildings (typically around 20), various utility distribution systems, roads, and sidewalks. Each site consisted of emplacements protected by revetments made of sandbags and wood planking, wooden structures, prefabricated metal buildings, and, later, permanent, concrete block structures. The prefabricated buildings had aluminum walls and roofs with wooden or concrete floors set on concrete pier blocks and were the most commonly constructed. The permanent structures included barracks, latrines, mess halls, craft shops, pump houses, motor pools, and radar facilities. Each site typically had a small arms range, water storage cistern, sanitary, and sewage disposal facilities. Pathways, sidewalks, roadways, and parking lots connected the structures.

Closure Info: Interim (9/21/2011): The analytical results from confirmatory sampling demonstrated that soil conditions at the waste site did not meet removal action levels Removal Action Levels (RALs). Therefore, the alternative was changed to removal, treatment, and disposal (RTD). The removal action at the 600-228 waste site was conducted from February 2010 through July 2011 and included the collection of focused and random samples from locations within the waste site.

Direct visual inspection of the site surface was performed for visual cues such as staining, discoloration, absence of vegetation, presence of debris and other anomalies. Due to the presence of empty paint cans and material that appears to be dried paint, the site is listed as having had a potential for liquid release. Radiological surveys were performed. No radiological dose readings above background nor radiological contamination was found.

Each of the four pits were considered zones of potential contamination (ZPCs). Random, focused soil samples were collected during the initial sampling, based on historical and process knowledge of the waste site as a dumping area, and visual indicators from ZPC 1, ZPC 2, ZPC 3 and ZPC 4. Analytical results of samples collected from ZPC 2 and ZPC 3 did not indicate any contaminant concentrations greater than RALs. Areas of scattered debris observed at ZPCs

2 and 3 were removed during the RTD activities at the 600-228 waste site. Initial samples collected from ZPC 1 and ZPC 4 indicated concentrations of antimony and lead were greater than the RALs, thus indicating RTD for those areas. The area comprising ZPC 1 was excavated to depths ranging from approximately 0.91 meters (3 ft) below original ground surface in the southeast corner to approximately 2.4 meters (8 ft) in the northwest corner. The area comprising ZPC 4 was excavated to a depth of approximately 0.61 meters (2 ft) below original ground surface.

Code: 600-262	Classification: Accepted
Names: 600-262; Lysimeter Test Site; West Lake Test Crib	Reclassification: Interim Closed Out (3/2/2011)
Type: Crib	Start Date: 1/1/1959
Status: Inactive	End Date: 1/1/1962

Description: The waste site has been evaluated under a removal action and Interim Closed Out. It was investigated and sampled in 2010. Sample results were below regulatory concerns, so no excavation was required. The radiological posting was removed in April 2010. The site includes a test crib and twenty one monitoring wells, that were grouted in 2007. The entire test site area is surrounded by metal fence posts. In 1999, no warning signs or postings are visible at the site. The ground surface is gently rolling. Northeast of the test crib is a depressed area approximately the same size as the crib. The soil is sandy and no discoloration is apparent. Vegetation at the site is composed primarily of grasses but includes a few small shrubs.

Location: The site is located east of Route 4 North, southwest of West Lake.

Process Description: A model test crib was built in 1959 for a field experiment for predicting crib capacity and crib waste retention. The field experiment was designed to check the validity of laboratory results and allow the scientists to observe the behavior of solutions put into the ground in a field setting. The location near West Lake was chosen because the depth to groundwater was only 3.7 meters (12 feet).

In May 1959, 34,200 liters (9,000 gallons) of calcium nitrate solution spiked with strontium-85 was placed into the 0.36 square meter (4 square foot) crib. According to HW-61476, seven 5 centimeter (2 inch) diameter wells were placed around the crib to monitor the infiltration of the solution through the soil. HW-61476 refers to them as wells "A" through "G." All the wells were drilled vertically except for well "F", located 1.2 meters (4 feet) east of the crib. Well "F" was drilled at an angle that intersected the water table below the center of the crib.

For the first week of the experiment, samples were collected from the wells every four hours. Nitrate was detected after 4256 liters (1120 gallons) of solution had been added to the crib. Well "F" detected strontium-85 after 16,900 liters (4450 gallons) of solution had been added to the crib. Well "E", located (4 feet) northeast of the crib, detected strontium-85 after 21,660 liters (5700 gallons) of solution had been added to the crib. The total infiltration of strontium-85 had not reached completion by the time the experiment was terminated.

HW-71573, written in 1962, describes the test crib being used again for a similar experiment. Fifteen additional monitoring wells were placed in the area. The infiltrate solution was also calcium nitrate spiked with Strontium-85.

Waste Type: Water

Waste Description: A concentrated solution of calcium nitrate and strontium-85 was prepared in the laboratory. 900 milliliters of the concentrated solution was added to a 55 gallon drum containing sanitary water. The resulting solution contained 600 parts per million of calcium and 0.00013

microcuries per milliliter. During the month of May, 1959, 34,200 liters (9000 gallons) of this solution was discharged to the ground through the wooden crib box. In 1961, another test was done at this site. A total of 61,560 liters (16,200 gallons) of water spiked with calcium nitrate and strontium-85 was injected into the crib.

Closure Info: Interim (3/21/2011): The 600-262 Waste Site achieved the established Removal Action Objectives without implementation of the Remove, Treat, Dispose alternative. No excavation was done and no backfill and/or contouring activities were required at this waste site.

Sampling activities at the 600-262 waste site was conducted on February 2, 2010, and included the collection of focused samples from locations within the boundaries of the waste site. A total of six soil samples were collected from two locations. The upper layer of soil (surface depth of approximately 0.5 m [1.6 ft.]) found inside the test crib structure during site evaluation consisted of blown in sand. It was not involved in the experimentation, and was not targeted for sampling. Based on 1959 site historical documentation, an increase of radioactivity was found to be present at about 1 meter (3.3 ft.) below the bottom of the test crib. Therefore, the sampling depth at Sample Location 1 was set at 1.5 meters (5 ft.) below ground surface to target that area. Three samples were collected from Sample Location 1, at 0.5 m (1.6 ft.) below the original soil surface (the bottom of the crib), 1.5 m (5 ft.) below ground surface and at 2.4 m (8 ft.) below ground surface. Sample Location 2 was downgradient, approximately 2.9 meters (9.5 ft) from the test crib box in a northeast direction between capped Wells G and 8. Three samples were taken at this location at 0.3 meters (1 ft), 1.5 meters (5 ft.), and 2.4 meters (8 ft.) below ground surface.

Code: 600-275	Classification: Accepted
Names: 600-275; Army Ammo Site; Igloo Site; Regulated Storage Area; 218-W-14	Reclassification: Interim Closed Out (5/20/2011)
Type: Foundation	Start Date: 1/1/1964
Status: Inactive	End Date:

Description: The waste site has been evaluated under a removal action and Interim Closed Out. The original bunkers and guard house had been previously removed. The site was well defined by a perimeter fence. The access roads are visible bladed areas where the seven bunkers had been located. Rectangular mounds of soil, each approximately one meter (3 feet) high, where the igloo structures had been located, were removed.

Location: The site was located approximately one mile west of the 200 West Area, south of Route 11A.

Process Description: The seven army igloos were originally used for ammunition storage and Nike missile parts. Drilling equipment for the Basalt Waste Isolation Project was also stored in the igloos. Later, radioactive material (plutonium scrap waste) was stored in the igloos.

Drawing H-6-354 is the design plan for the storage units. It is dated 12/14/64. This is believed to be the approximate construction date.

Closure Info: Interim (5/20/2011): A successful completion of the removal action was conducted at the 600-275 waste site, also known as the former Igloo Army Ammo Storage Site. The alternative proposed in DOE/RL-2008-44, Engineering Evaluation/Cost Analysis for the 200-MG-1 Operable Unit Waste Sites (EE/CA) and selected in DOE/RL-2009-48, Action Memorandum for Non-Time Critical Removal Action for 11 Waste Sites in 200-MG-1 Operable Unit (Action Memorandum) was removal, treatment, and disposal (RTD). The 600-275 waste site was investigated in December 2009 through field observations and sampling to determine the nature and extent of contaminants of potential concern (COPCs) present in the waste site soils as part of the selected removal action alternative. In September 2010, the igloo foundations were

removed from the 600-275 waste site; visual inspections of the foundations and underlying soil were conducted, and soil samples were collected between September 2010 and February 2011. Analytical results from initial sampling demonstrated that soil conditions at the waste site did not comply with established removal action levels (RALs).

The removal action at the 600-275 waste site was conducted between December 2009 and February 2011. Activities included the collection of judgmental and random samples from locations within the boundaries of the waste site, removal of seven concrete igloo foundations, and approximately 0.3 meters (1 foot) of underlying soil. Collection of judgmental and random samples was based on historical and process knowledge, and visual indicators. Excavation of soil under the RTD alternative was done in zones of potential contamination (ZPCs) 1 and 2, identified as igloos T-101 and T-104, respectively. Random samples were collected from the excavated areas at ZPC 1 (T-101) and ZPC-2 (T-104) for verification purposes, laboratory analysis for COPCs, and evaluation of analytical results to demonstrate achievement of RALs.

In August 2010, the cover soil was removed from the igloo foundations. Visual inspections and radiological surveys were performed on all seven foundations, which were observed to be intact with only superficial hairline cracks, no visual indicators (i.e., staining or discoloration) were observed, and radiological screening did not indicate evidence of contamination or dose rates greater than background. Concrete patches were observed at the T-104 igloo, indicating that the foundation may have been altered after its original construction, suggesting a potential event may have occurred. All seven foundations were subsequently removed along with approximately 0.15 meters (0.5 feet) of underlying gravel. No soil discoloration was observed beneath the seven igloo foundations.

Excavation of impacted soils at ZPC 1 commenced in January 2011.

Code: 600-281	Classification: Accepted
Names: 600-281; Scattered Debris South of Army Loop Road	Reclassification: Interim Closed Out (9/21/2011)
Type: Dumping Area	Start Date:
Status: Inactive	End Date:
Description:	The waste site has been evaluated under a removal action and Interim Closed Out. After the range fire in June 2000, additional areas of debris were visible. Five areas of concentrated debris were identified. The debris includes material suspected to be asbestos, charred wood, glass, metal pipes, gauges and green metal containers, 55 gallon drums and batteries.
Location:	The waste site has been remediated. The areas of debris are located south of Army Loop Road, approximately 150 meters east of the H-42 Gun Site.
Related Sites/ Structures:	The debris is associated with sitecode 600-49 and 600-226.
Waste Type:	Demolition and Inert Waste
Waste Description:	Five areas of concentrated debris were identified. The debris includes material suspected to be asbestos, charred wood, glass, metal pipes, gauges and green metal containers. Three compressed gas cylinders were found adjacent to well 699-16-51.
Closure Info:	Interim (9/21/2011): Direct visual inspection of the site surface was performed for visual cues such as staining, discoloration, absence of vegetation, presence of debris and other anomalies. Radiological surveys were performed during sampling activities. No radiological readings greater than background, and no radiological contamination was found. The site was confirmed

to be a nonradiological site. Ten Zones of Potential Contamination (ZPC) were identified. Initial random samples were collected from each zone. The results of the initial, confirmatory sampling indicated contaminant concentrations greater than the Removal Action Levels (RAL) in five of the sampled areas (ZPC 1, ZPC 2, ZPC 5, ZPC 6 and ZPC 8), thus the Remove, Treat, Dispose (RTD) option was initiated in these areas. The removal action at the 600-281 waste site was conducted from March 2010 through July 2011 and included the collection of focused and random samples from locations within the waste site. The excavation depths ranged from 2 to 7 feet below ground surface. Two areas of transite debris were identified during site evaluation and were removed during RTD activities at the 600-281 waste site. Additional focused samples were collected from these areas. The excavated areas were contoured and backfilled in August 2011.

Code: 600-282	Classification: Accepted
Names: 600-282; Wood and Coal Debris Piles	Reclassification: Interim Closed Out (8/11/2011)
Type: Dumping Area	Start Date:
Status: Inactive	End Date:

Description: The waste site has been evaluated under a removal action and Interim Closed Out. It consisted of an area of scattered wood debris and a pile of coal. The southern portion of the 600-282 waste site contained an area of debris that appears to have been a structure, an earthen ramp, small coal pile, a portion of a drainage ditch, and what appeared to be a square well supplied by underground piping. A surface veneer of coal ash was strewn in the area between the northern and southern areas. The debris was generally concentrated in several piles in the southern area, as well as sparsely scattered over areas adjacent to the waste site. The debris generally consisted of lumber, metal debris, and cans.

Location: The site was located east of Route 4N and west of West Lake. It is approximately 412 meters (1,351 feet) west and slightly north of the 600-40 dump site.

Waste Type: Misc. Trash and Debris

Waste Description: Coal and wood debris were identified on a site walkdown in 2004.

Closure Info: Interim (8/11/2011): Sampling results from the confirmatory sampling demonstrated that the waste site did not achieve compliance with the removal action levels (RALs). Based on the analytical results, the alternative was changed to removal, treatment, and disposal (RTD).

The removal action at the 600-282 waste site was conducted from August 2010 through April 2011 and included the collection of focused and random soil samples. Based on the visual indicators and observations made during the site evaluation, eight Zones of Potential Contamination (ZPCs) were identified at the 600-282 waste site. Focused samples were collected from each ZPC, based on process knowledge and visual indicators for the initial sampling evolution. Visual indicators observed at ZPC 6 (which appeared to be a well with a rectangular wood frame) and ZPC 7 (an open drainage ditch) suggested a potential for contamination below the surface of the waste site in these areas. Therefore, in process sampling at a depth of approximately 1.2 meters (4 ft) below ground surface was conducted. The analytical results in those areas confirmed that they met the established RALs and did not require RTD.

Zone 2 (ZPC2) exceeded Removal Action Levels (RAL), resulting in the implementation of the RTD alternative. Removal of impacted soils in that area commenced on March 30, 2011, with the lateral extent of excavation at the ZPC determined utilizing visual indicators. Samples were collected at depths of 2.4 and 3.4 meters (8 and 11 ft) below ground surface to refine the

vertical extent of excavation to a total depth of approximately 2.4 meters (8 ft). In addition to excavation at ZPC 2, scattered debris from locations throughout the 600-282 waste site was removed, along with underlying soil to a depth of approximately 1 meter (0.3 ft) during RTD activities. Backfill of the 600-282 waste site was completed on May 26, 2011.

No radiological dose readings were greater than background was identified and no radiological contamination was found.

Code: 616-WS-1	Classification: Accepted
Names: 616-WS-1; 616 NRDWSF French Drain	Reclassification: Closed Out (10/24/2001)
Type: French Drain	Start Date: 1/1/1986
Status: Inactive	End Date: 1/1/2001

Description: This french drain was sampled and Closed Out in 2001. It is a perforated concrete pipe set vertically into the ground. The ground surface is flush with the top of the pipe. The pipe has a layer of gravel at its bottom and a concrete cover over its top. The lid is 10.2 centimeters (4 inches) thick and 1.2 meters (3 feet 10 inches) in diameter. Two railroad ties lie on opposite sides of the lid.

Location: The site is located north of the northeast corner of the 616 Facility. The 616 Building is located on the north side of Route 3 between 200 East and 200 West Areas.

Related Sites/ Structures: The site is associated with the loading pads at the 616 Nonradioactive Dangerous Waste Storage Facility (616 NRDWSF).

Process Description: This french drain was designed to receive liquid collected from the east and north loading pads of the 616 Facility. It serviced both the north and the east loading dock trenches. The loading and unloading areas are provided with a sloped, curbed and plugged drainage trench. All liquid accumulations, including precipitation were sampled. Liquids with chemical concentrations above Ecology guidelines for unconditional release to the environment were recovered, processed, and shipped as regulated waste. Liquids with chemical concentrations below the Ecology guidelines were released to the french drain.

Waste Type: Stormwater Runoff

Waste Description: The unit received liquid from loading pad collection troughs. The water was sampled to ensure it met release criteria before being released to the drain.

Closure Info: Final: Because operating records did not demonstrate that early operations within the 616 facility met spill cleanup requirements, the building was considered potentially contaminated and underwent decontamination. Equipment used for waste handling was removed. The storage cell floors, sumps, trenches, and outdoor loading pads were cleaned using nonregulated detergents. The rinsates were collected, analyzed, designated and disposed of as nondangerous waste. Some minor residual staining/discoloration of coated surfaces remained after decontamination. This was allowed in the closure plan.

Completion of closure plan requirements was certified by a Professional Engineer on 6/13/2001. The RCRA permit Closure Certification was transmitted to the Washington Department of Ecology on 9/5/2001. Ecology accepted the Closure Certification on 10/24/2001.

Sampling of the french drain was required as part of the Closure Plan for the 616 facility. The gravel within the french drain was removed and stored pending sampling results. A single soil sample was taken from the center of the drain. The sample was analyzed for pH, volatile organic compounds, semi-volatile organic compounds, RCRA (Resource Conservation and Recovery Act) metals, PCBs (polychlorinated biphenyls), herbicides, pesticides, phosphorous

pesticides, cyanide, total organic halides, anions, phenols, and chrome VI. The sample met closure standards for all constituents.

Code: CTFN 2703-E **Classification:** Accepted

Names: CTFN 2703-E; 200-E Chemical Drain Field; Chemical Tile Field North of 2703-E **Reclassification:** None

Type: Drain/Tile Field **Start Date:**

Status: Inactive **End Date:**

Description: The waste site consists of a trench and seepage basin. As of 1994, this unit had no free standing liquids nor any sign of natural vegetative growth. The seepage basin is referred to as the 200-E Chemical Drain Field. It has not been backfilled or filled with any materials that would facilitate drainage.

Location: This unit lies west of the 2607-E1 septic system, north of the 2703-E Building and northwest of the intersection of Fourth Street and Baltimore Avenue, in the 200 East Area.

Related Sites/Structures: The CTFN of 2703-E is associated with the 272-E Building and the 2703-E Building. The pipeline associated with this tile field is sitecode 200-E-287-PL.

Process Description: The drain field was designed to receive non-hazardous liquid waste from the 272-E and 2703-E Buildings. Wastewater from the 272-E Building floor drain was discharged to a process sewer line which extends to the disposal site (see 200-E-287-PL). Wastewater from two floor sumps in the 2703-E Building was discharged to the same process sewer line and combined with the 272-E Building effluent before reaching the disposal site.

Waste Type: Process Effluent

Waste Description: The Chemical Tile Field North of 2703-E is currently inactive. The wastewater from the 272-E Building was hydrotesting wastewater which was not treated before being discharged to the floor drain. The wastewater discharged from the two sumps in the 2703-E Building included: floor wash, rinse water, cooling water, sinks, and steam condensate.

Code: OCSA **Classification:** Accepted

Names: OCSA; Old Central Shop Area; Central Shop Area **Reclassification:** None

Type: Foundation **Start Date:** 1/1/1945

Status: Inactive **End Date:**

Description: The site consists of building foundations and scattered debris. The central shops had been surrounded by over 1.3 miles (2.1 kilometers) of fencing. The structures in the shop complex included offices, storage huts, boiler houses, warehouse and storage facilities as well as multiple shop facilities (automotive repair, sheet metal welding, paint, etc). There were also bulk fuel storage and a septic system. A site visit on 12/4/1997 observed pieces of lumber, corrugated metal, bricks, shingles, buckets, a barrel, office furniture, and wooden tables. There are two pits containing debris and nails.

Location: The site is located in the 600 Area approximately half way between 200 East and West areas, south of Route 11A and north of Route 4S.

Process Description: During Hanford construction the central shops were established as a staging area, repair shops, and specialized fabrications area. It was a central location for construction being conducted at 200 East, 200 West, 100-B, 100-D, and 100-F Areas. It included materials storage areas for

construction materials and fuel storage. All facilities in the central shops area were considered temporary construction facilities and were identified as TC-29 Buildings. The sanitary sewer system consisted of a gravity feed septic tank system open trench and open settling ponds.

There were three fuel storage areas: One was associated with a gas station, and had kerosene as well as diesel and gasoline in 3,000-gallon storage tanks (also "white" in a 2,000 gallon tank). The second was a fuel storage yard, with six 25,000 gallon tanks and two 12,000 gallon tanks; the drawings show this as both "Gasoline storage area" on one side and "Fuel Oil storage" on the other. The third is one 100,000-gallon storage tank that was connected to a Boiler, which was likely the heat source for the area buildings.

Waste Type: Sanitary Sewage

Waste Description: The site contained a sanitary sewer system consisting of a tank(s), open trench, and settling ponds.

Waste Type: Demolition and Inert Waste

Waste Description: The site contains miscellaneous demolition debris and several foundations can be seen. There is also evidence of burning.

Code: UPR-200-E-11 **Classification:** Accepted

Names: UPR-200-E-11; Railroad Track Contamination Spread; UN-200-E-11 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1957

Status: Inactive **End Date:**

Description: This unplanned release is no longer marked or posted. Portions of the TC-4 Spur (a.k.a. UPR-200-E-88) and a section of track south of the 218-E-5 Burial Ground (UPR-200-E-95) have been covered with dirt and posted with Underground Radioactive Material signs.

Location: The unplanned release effected the railroad track extending from the PUREX tunnel to the 218-E-5 Burial Ground.

Release Description: In 1957, fission product contamination spots dripped along the railroad track extending from Plutonium Uranium Extraction (PUREX) to the 218-E-5 Burial Ground. Contaminated tracks sections included the track from the PUREX tunnel entrance to the west exclusion area fence, the spur into the 218-E-5 Burial Ground, and the "TC" spur. Specific release details are unknown.

Related Sites/ Structures: The site is associated with UPR-200-E-88, UPR-200-E-95, 200-E-43 and 200-E-44.

Process Description: Some burial casks were shielded with water that was removed before placing the material into the burial ground. Sometimes railcars were washed down to remove loose contamination before transporting the load to the solid waste burial ground.

Waste Type: Water

Waste Description: The release consisted of fission products dripping from a railroad car transporting material from PUREX to the burial ground.

Code: UPR-200-E-83 **Classification:** Accepted

Names: UPR-200-E-83; Zone A, Zone B, Zone C; BC Controlled Area; BC Cribs Controlled Area; **Reclassification:** None

BCCA; UN-200-E-83; UN-216-E-11

Type: Contamination Migration

Start Date: 1/1/1958

Status: Inactive

End Date:

Description: Periodic radiological surveys conducted between 1958 and 1998 (and beyond) have identified radiological contamination outside the boundaries of the engineered crib and trench structures. Each survey effort redefined the soil contamination boundaries. The size and shape of the posted area varied with each survey. Radiological surveys (1996-1998) identified contamination extending south from Route 4 South to Army Loop Road and extending east to the Central Landfill area. A soil remediation project began in 2009 and continued through 2011. For remediation purposes, the BC Controlled Area was re-defined and divided into two subsites; the Northern Area, that includes cleanup areas A and B, and the Southern Area that includes cleanup area C.

Location: The site is located south of 200 East Area, adjacent to the BC Cribs and Trenches.

Release Description: The source of the large contaminated area known as the BC Controlled Area has been determined to be due to the BC Cribs and trenches. The cribs and trenches received large amounts of liquid radioactive process waste from the Uranium Recovery project (1952 to 1956). In 1958, radioactive rabbit and coyote feces were found scattered over the ground surface. A radiation survey (#DS 01266 - May 7, 1958) states the maximum reading on rate on the crib vent was 200 millirad per hour with 40,000 counts per minute smearable contamination. The overground transfer line in 1958 was reading 250 millirem per hour at a distance of 5.1 centimeters (2 inches). The ground under the overground line was reading 10,000 counts per minute. Rabbit droppings found in 1958 were contaminated to levels from 2,000 counts per minute to 100,000 counts per minute. In one area, 80% of the rabbit droppings were contaminated from 5,000 to 100,000 counts per minute. It was determined that a badger or some other animal had burrowed into the 216-B-28 Trench and exposed a radioactive salt layer. Over time, rabbits ingested the contaminated salts and defecated over approximately 10 square kilometers (4 square miles) of undisturbed sagebrush covered land. The burrow was filled with asphalt in 1964. The asphalted area was visible and documented on a 1981 radiation survey (#T81-0930, July 1, 1981). In 1973, Battelle Northwest Laboratories collected data regarding the distribution and contamination levels of animal droppings in the BC Crib and Trench area. Their study attempted to correlate the data to animal behavior patterns, soil characteristics, vegetation, prevailing winds and other environmental influences. From a designated center point, field personnel walked a total of 29 radii. Radiological and biological data was collected at intervals equaling 20 human steps. (approximately 16 meter [52 feet] intervals). Most of the contamination was found south, southeast and southwest of the BC Cribs. The data collected to determine the contamination distribution was recorded in the report (BNWL-1794), but no conclusions were made. A series of radiological surveys done in 1978 showed the contamination had moved onto the roadways in the area. Contamination levels ranged from 300 counts per minute to greater than 100,000 counts per minute. A 1981 radiation survey identified nine highly contaminated areas. Several areas of highly contaminated soil were noted as well as contaminated tumbleweeds, tumbleweed roots and tumbleweed fragments. General contamination levels ranged from 200 to 100,000 counts per minute and areas of 50 to 150 millirem per hour. Other possible sources of contamination include the US Ecology disposal facility and PUREX operations. In October 1960 a significant contamination spread occurred at PUREX. A sketch attached to Radiation Occurrence Report 60-3 shows a large contamination spread from the 241-A-151 Diversion Box spread across Route 4S. The 241-A-151 Diversion Box is located on the south side of the PUREX plant (202-A). Sparsely spaced particles (less than 5 per 9.3 square meters [100 square feet]) are shown in the BC Crib and Trench Area (see UPR-200-E-26). In 1969, the BC Trenches were graded and covered with sand and gravel. In 1973, a Battelle Northwest Laboratory study attempted to define the distribution of the contaminated rabbit feces. A 1981 radiological survey identified a large amount of surface contamination, contaminated tumbleweeds and contaminated

tumbleweed fragments on the BC Cribs and Trenches.

Waste Type: Soil

Waste Description: The contamination spread consists of radioactive feces (and urine) from coyotes and rabbits. Strontium-90 (81 curies) and cesium-137 (14 curies) are the major contaminants in the feces. Specks of contamination found in the soil may be wind blown particulates from filling the open trenches with waste (1952-1958) and major contamination events in 200 East Area. In 1999, the cryptogamic layer and underlying soils were analyzed for a selected number of radionuclides based on the contaminant of concern list. Analysis included plutonium-239, americium-241, cesium-37 and strontium-90.

This Site has the Following SubSites:

Code: UPR-200-E-83:1

Names: UPR-200-E-83:1; Zone A and Zone B; Northern Area; Northern Portion of BC Controlled Area

Code: UPR-200-E-83:2

Names: UPR-200-E-83:2; Zone C; Southern Area; Southern portion of UPR-200-E-83

Code: UPR-200-E-83:1

Classification: Accepted

Names: UPR-200-E-83:1; Zone A and Zone B; Northern Area; Northern Portion of BC Controlled Area

Reclassification: None

Type: Contamination Migration

Start Date:

Status: Inactive

End Date:

Description: The northern portion of the UPR-200-E-83 waste site includes the soil remediation areas known as Zone A and Zone B. Zone A is approximately 140 acres of densely contaminated soil, south of the BC trenches. Zone B is the remaining (approximately 3600 acres) of spotty contaminated soil. During 2009 through 2011, a remediation activity removed approximately 140 acres of contaminated soil from Zones A and B. Zone A and isolated area within Zone B were downposted in August 2011 (per DOE/RL-2011-101).

A low level, high resolution aerial survey was conducted of the site in September 2009, resulting in approximately 1566 acres of Zone B being downposted over time, through September 2010.

The SubSite is Part Of:

Code: UPR-200-E-83

Names: UPR-200-E-83; Zone A, Zone B, Zone C; BC Controlled Area; BC Cribs Controlled Area; BCCA; UN-200-E-83; UN-216-E-11

Code: UPR-200-E-83:2

Classification: Accepted

Names: UPR-200-E-83:2; Zone C; Southern Area; Southern portion of UPR-200-E-83

Reclassification: None

Type: Contamination Migration

Start Date:

Status: Inactive

End Date:

Description: The subsite is BC Controlled Area Zone C. It is the 4700 acre southern portion of UPR-200-E-83. The southern area includes the sand dunes and Zone C. Characterization of a number of small isolated spots of contamination in Zone C, identified by the 2009 aerial survey, have been investigated through field surveys.

Location: Zone C is the southern half of the BC Controlled Area. It extends south from the boundary that separates the northern and southern areas, to the Army loop road.

The SubSite is Part Of:

Code: UPR-200-E-83

Names: UPR-200-E-83; Zone A, Zone B, Zone C; BC Controlled Area; BC Cribs Controlled Area; BCCA; UN-200-E-83; UN-216-E-11

Code: UPR-200-W-8 **Classification:** Accepted

Names: UPR-200-W-8; 200-W-5; Old Burial/Burning Pit; **Reclassification** None
UN-200-W-8; U-Plant Burning Pit/Burial Ground

Type: Unplanned Release **Start Date:** 1/1/1950

Status: Inactive **End Date:**

Description: The site is posted as an Underground Radioactive Material area.

Location: The site is located in the old burning ground, east of the 221-U Building, adjacent to the corner of Beloit and 16th Street.

Release Description: Contamination was discovered in the spring of 1950 in the Old Burning Ground, located east of the U-Plant Facility. An area of approximately 13.9 square meters (150 square feet) was observed to be contaminated, with a maximum dose rate of 45 rads/hour at 5 centimeters (2 inches). The area was covered with 3 meters (10 feet) of clean dirt.

Related Sites/ Structures: This site is associated with 200-W-71.

Process Description: It was covered with 3 meters (10 feet) of soil and posted with Underground Contamination signs in 1950. An April 1966 aerial photograph shows the outline of a large polygon shaped area east of U-Plant. Drawing H-2-44510 identifies this area as "Burial Ground". It measures approximately 130 by 30 meters (425 by 100 feet). The area was removed from radiation zone status in August 1972, but was reposted as an "Underground Radioactive Material" Area in 1992.

Waste Type: Misc. Trash and Debris

Waste Description: Fission products were discovered at the site with approximately 1 curie and a maximum dose rate of 45 rads/hour at the surface.

Code: UPR-200-W-58 **Classification:** Accepted

Names: UPR-200-W-58; Railroad Track Contamination; **Reclassification** None
UN-200-W-58

Type: Unplanned Release **Start Date:** 1/1/1965

Status: Inactive **End Date:**

Description: The Unplanned Release is not separately marked or posted from other postings on the railroad track.

Location: In 1965 this release caused spotty contamination to spread along the railroad track from the T-Plant railroad cut to the 200 West Burial Ground.

Release Description: On April 26, 1965, a beta-gamma contamination spread occurred during the process of transporting 221-T Plant canyon cell blocks from the 221-T canyon and burying them in the

200 West Burial Ground. Two small spots approximately 15 centimeters (6 inches) in diameter with reading of 5 rads/hour were found on one end of the deck of flat car #19382. Railroad bed surfaces in the 221-T cut were found to have spotty contamination to a maximum of 100,000 counts per minute. The undercarriage of the locomotive used was contaminated generally to 20,000 counts per minute. A rigger and a train crew brakeman received contamination on their shoes and socks. The contamination spread from the underside of an improperly prepared cell block to the deck of the flat car. Further spread occurred when the radiation monitor failed to capture the train following detection of loss of radiological control in the 221-T cut.

Waste Type: Chemicals

Waste Description: The release consisted of beta/gamma contamination with levels ranging from 100,000 counts/minute to a maximum of 5 rads/hour.

Code: UPR-200-W-70 **Classification:** Accepted

Names: UPR-200-W-70; Contamination Found at the 200 West Burning Ground East of Beloit Ave. **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1973

Status: Inactive **End Date:**

Description: The release site is not marked or posted. A mapping data point (dot) estimates the location, placing it adjacent to the northwest access road into the 200-W ADB (ash disposal basin). The area is currently covered with several feet of ash.

Location: The 200 West Burning Pit is located south of the 216-W-LWC Crib and east of Beloit Ave. It is located within the 200 West Ash Disposal Basin.

Release Description: On January 22, 1973, a quarterly routine survey of the 200 West Area Burning Pit revealed several spots of beta-gamma contamination measuring 5,000 to 50,000 counts per minute along the bumper rails at the edge of the combustible trench. Additional surveys disclosed other contamination measuring from 20,000 counts per minute to 30 millirads/hour in the trench proper and a one-gallon bucket contaminated in excess of 100,000 counts per minute (250 millirads/hour). Samples of the contamination were obtained for laboratory analysis. A dump area on the south side of the combustible trench, about 3.7 by 6.7 meters (12 by 22 feet), was found to contain alpha contamination with readings ranging from 5,000 to 200,000 disintegrations per minute. The cause of the contamination was the unauthorized disposal of contaminated material in a non contaminated burning trench.

Related Sites/Structures: The site is associated with the 200 West Burn Pit, and is within the 200-W ADB.

Process Description: The burning pits routinely received non-radioactive debris (construction debris, wood, paper, solvents and paint) to be burned as a means of disposal. Radiological waste was not supposed to be placed in burning pits.

Waste Type: Ash

Waste Description: Beta/gamma contamination measuring 5,000 to 50,000 counts/minute was found along the bumper rails at the edge of the combustible trench. Other area of contamination ranging from 20,000 counts/minute to 30 millirads/hour beta/gamma was identified inside the combustible trench. An area on the south side of the combustible trench was found to have contamination ranging from 5,000 to 200,000 disintegrations/minute alpha. A sample from the trench (a chunk of rusty debris) showed americium-plutonium contamination.

Code: UPR-600-12 **Classification:** Accepted

Names: UPR-600-12; UN-600-12; UNH Spill to Route 4S **Reclassification** None

Type: Unplanned Release **Start Date:** 12/30/1954

Status: Inactive **End Date:** 12/30/1954

Description: The waste site is three radiologically posted areas. Two are located on the south shoulder of Route 4S, near the top of the hill, southeast of 200 East Area. All three areas are posted as Underground Radioactive Material Areas. One is on the opposite side of Route 4S.

Location: The release occurred on a portion of Route 4S, southeast of 200 East, in the 600 Area.

Two posted areas are on the south side of Rt 4S (one approximately 30 feet from the road and the other approximately 75 feet from the road). One posted area is on the north side of Rt. 4S, approximately 60 feet from the road.

Release Description: On December 30, 1954 a tractor-trailer overturned on the 200 East Hill, spilling 6,060 liters (1,600 gallons) of uranium nitrate hexahydrate solution onto the road and shoulder. General contamination levels of 60 millirad/hour were found on the road and the shoulder. Part of the contamination was removed and the balance was washed off the road. A thin layer of blacktop was added to the road to cover the spill area. The shoulder contamination was covered with dirt. The contamination levels were reduced to a maximum of 20,000 counts per minute.

Waste Type: Chemicals

Waste Description: The waste consisted of uranium nitrate hexahydrate solution spilled to the road and the soil.

The soil was found to have less than 10 nanocuries/gram of contamination, and a maximum dose rate at the surface of 60 millirads/hour.

Code: UPR-600-20 **Classification:** Accepted

Names: UPR-600-20; Old Cross Site Transfer Line Surface Contamination; UN-216-E-41 **Reclassification** None

Type: Contamination Migration **Start Date:** 1/1/1988

Status: Inactive **End Date:** 1/1/1995

Description: The 600-284-PL underground transfer line extends from the 241-UX-154 diversion box, adjacent to U Plant in 200 West Area, to the 241-ER-151 Diversion Box in 200 East Area. The Unplanned Release waste site includes the contaminated soil and vegetation located on the surface of the cross site transfer line and surrounding the 241-ER-151 Diversion Box. The surface of the underground line has been stabilized and is currently posted with "Underground Radioactive Materials" signs. There is also a large mound of soil, located south of the 241-EW-151 Vent Station, that is associated with the original transfer line surface stabilization activities. The soil mound is posted with Underground Radioactive Material signs.

Location: The site extends from the 241-ER-151 Diversion Box in 200 East Area and to the 241-UX-154 Diversion Box in 200 West Area. The majority of the transfer line is located in the 600 Area, between 200 East and West Areas, south of Route 3. The pipeline is approximately 2.3 miles long.

Release Description: The surface of the buried waste transfer line became contaminated through biological transport of radioactive materials that leaked in the pipeline encasement and windblown particulates from the vent station. In March 1988, while conducting a radiological survey of the 241-EW-151 Vent Station (located approximately mid way between 200 East and 200 West Areas on the transfer line) contamination was identified approximately 100 meters (300 feet) outside the established radiation zone boundaries of the vent station above the transfer line. The Mobile Surface Contamination Monitor (MSCM) tractor was used to survey the entire surface of the

pipeline. Numerous spots of contamination were identified at various locations along the entire length of the transfer line. Contamination levels ranged from a few hundred counts per minute to 750 millirem per hour. To characterize the integrity of the pipeline, eight boreholes were drilled with an auger at four locations along the transfer line. Although no contamination was found to have leaked below the pipeline encasement, contamination was found in sagebrush growing next to the encasement. This indicated that the roots of the sagebrush had penetrated the encasement. The contamination was given an Unplanned Release number in 1989.

Related Sites/ Structures: UPR-600-20 is associated with the 600-284-PL pipeline, the 241-ER-151 Diversion Box (east end of the pipeline), the 241-EW-151 Vent Station (along middle of pipeline), and the 241-UX-154 Diversion Box (west end of the pipeline). Also see 600-296, Replacement Cross Site Transfer Pipeline.

Process Description: The original cross site transfer line was originally constructed in 1952 to support the Uranium Metal Recovery operations. Various process and tank farm waste has been transported between 200 East and 200 West areas through this concrete encased, underground pipeline. The original cross site transfer line (sitecode 600-284-PL) consists of six stainless steel pipelines (V360, V361, V362, V363, V364, V366) inside a concrete encasement. The encasement type is known as 6-59, indicating there are six lines inside a 59 inch wide encasement. The concrete encased stainless steel pipelines are buried at depths that range from 1.5 to 4.5 meters (5 to 15 feet). There are 58 encasement test risers (swab risers) spaced regularly along the pipeline that provided access to the encasement void space. The old original cross site line was replaced with a new pipeline in 1995 (see 600-269).

Waste Type: Process Effluent

Waste Description: The surface of the buried waste transfer line became contaminated through biological transport of radioactive materials that leaked in the pipeline encasement and windblown particulates from the vent station. The contaminated soil contained cesium-137, plutonium-239/240, strontium-90, and uranium from tank farm waste transferred between 200 East Area and 200 West Area through the underground line.

Code: UPR-600-21	Classification: Accepted
Names: UPR-600-21; Contamination Found Northeast of 200 East Area; UN-216-E-31	Reclassification: Interim Closed Out (2/25/2011)
Type: Unplanned Release	Start Date: 1/1/1985
Status: Inactive	End Date: 1/1/1991

Description: The remediation evaluation for this waste site was completed and the waste site reclassified to Interim Closed Out in 2011. The site had been a large radiologically posted area located northeast of 200 East Area. The area is no longer marked or posted. The site was originally posted with Radiological Controlled Area warning signs. In 1990, the Health Physics group changed the posting to Surface Contamination. In 1991, all radiological postings were removed.

Location: Radiological contamination was originally identified in an area located east and northeast of the 200 East Area fence, south of Route 11A.

Release Description: The release was a result of contaminated tumble weeds that migrated and decomposed in the area and possibly specks from the PUREX stack or a nearby burial ground.

Closure Info: Interim: In July and August 2009, the 200-E-110 and UPR-600-21 waste sites were investigated through observation, field screening and radiological surveys for the purpose of determining if radiological contaminants were present above the removal action levels (RALs). The survey results analysis confirmed that soil contaminant concentrations are at or below the RALs and that no further action is required. Both 200-E-110 and UPR-600-21 waste sites achieved compliance with the removal action levels (RALs) and thus met the removal action objectives

(RAOs). These results support reclassification to Interim Closed Out status.

200-PW-1

Code: 216-Z-1&2 **Classification:** Accepted

Names: 216-Z-1&2; 216-Z-7; 234-5 No. 1 Crib; 234-5 No. 2 Crib; 216-Z-1 & 2TF; 216-Z-1 and 216-Z-2 Cribs **Reclassification:** None

Type: Crib **Start Date:** 1/1/1949

Status: Inactive **End Date:** 1/1/1969

Description: The 216-Z-1&2 Cribs consist of two wooden timber boxes connected by a central pipe. The 216-Z-2 crib overflowed into the 216-Z-1 crib which overflowed into the 216-Z-1A tile field. Each unit is set and backfilled in a deep, square excavation. Two risers were visible from the surface of each crib.

Location: The 216-Z-1 and 2 cribs are located south of 234-5Z (Z Plant) facility and west of the 216-Z-3 Crib. They are inside the 216-Z-1A fenced area.

Related Sites/Structures: The cribs are associated with 234-5Z the transfer piping, local monitoring wells, the 241-Z-361 Settling Tank, the 216-Z-3 Crib and the 216-Z-1A Tile Field. The pipeline that fed the cribs is 200-W-210-PL.

Process Description: These cribs were designed to dispose of aqueous and organic wastes in the soil column. The unit received waste from the 234-5Z, the 236-Z, and the 242-Z Buildings.

Waste Type: Process Effluent

Waste Description: The 216-Z-1 and 2 Cribs received liquid process waste from the 234-5Z Building. The cribs received aqueous and organic wastes from the Plutonium Reclamation Facility, Americium Recovery Line wastes from the 236-Z and 242-Z Buildings, and uranium wastes from the 236-Z Building.

Code: 216-Z-1A **Classification:** Accepted

Names: 216-Z-1A; 216-Z-1A Tile Field; 216-Z-1AA; 216-Z-1AB; 216-Z-1AC; 216-Z-7; 234-5 Tile Field **Reclassification:** None

Type: Drain/Tile Field **Start Date:** 1/1/1949

Status: Inactive **End Date:** 1/1/1969

Description: The tile field is located inside a chain link fence. It is a below grade trunk line orientated north to south with seven pairs of lateral pipes spaced in a herring bone pattern. The vitrified clay pipe lies on a gravel bed. The length of the tile field was expanded twice. The original section is known as 216-Z-1AA. The expanded sections are known as 216-Z-1AB, and 216-Z-1AC. The excavation was backfilled to grade. The fence is radiologically posted.

Location: The unit lies south of the 234-5Z facility perimeter fence and immediately south of the 216-Z-1&2 Cribs.

Related Sites/Structures: The tile field is associated with the 216-Z-1&2 Cribs, the 216-Z-3 Crib, 241-Z-361 settling Tank and associated underground transfer lines. The replacement (2 inch) stainless steel lines are documented in sitecode 200-W-174-PL.

Process Description: The site received waste from the Z Plant 234-5Z, 236-Z and 242-Z facility operations. The tile field was originally constructed to receive liquid waste overflow from the 216-Z-1 and the 216-

Z-2 Cribs. Later the cribs were bypassed and the waste was routed directly into the tile field.

The 216-Z-1A Tile Field initially was taken out of service in March 1959 after low concentrations of plutonium were detected in 1958 in the soil at the bottom of a well 46 meters (150 ft) deep, and 15 meters (50 ft) above the water table, near the 216-Z-3 Crib (Well 299-W18-57). The 216-Z-1A Tile Field had been receiving overflow from the 216-Z-3 Crib during this time, and was taken out of service when the 216-Z-3 Crib was replaced. In 1964, the 216-Z-1A Tile Field was reactivated to receive plutonium reclamation operation waste liquids directly through the pipelines from the Plutonium Reclamation Facility, bypassing the 216-Z-1&2 and 216-Z-3 Cribs. Two groundwater wells (Wells 299-W18-6 and 299-W18-7) were drilled on the west and east sides of the tile field, respectively, to monitor the groundwater. From 1964 to 1969, the 216-Z-1A Tile Field was operated as a specific retention facility. The tile field was taken out of service in 1969 when it had received the prescribed liquid waste volume.

Waste Type: Process Effluent

Waste Description: The 216-Z-1A Tile Field originally received overflow from the 216-Z-1 and the 216-Z-2 Cribs. The cribs received aqueous and organic wastes from the Plutonium Reclamation Facility, americium recovery line wastes from the 236-Z and the 242-Z Buildings, and uranium wastes from the 236-Z Building.

Material discharged to the tile field reportedly included 57 kg (126 lb) of plutonium, 1 kg (2.2 lb) of Am-241, 270,000 kg (594,000 lb) of carbon tetrachloride, and 3,000 kg (6,600 lb) of nitrate. The carbon tetrachloride was discharged to the 216-Z-1A Tile Field in combination with other organics, as a small entrained fraction of process aqueous wastes, and as DNAPL.

Code: 216-Z-3 **Classification:** Accepted

Names: 216-Z-3; 216-Z-3 Culvert; 216-Z-8; 234-5 No. 3 & 4 Cribs **Reclassification:** None

Type: Crib **Start Date:** 1/1/1952

Status: Inactive **End Date:** 1/1/1959

Description: The crib is posted with identification signs. It is inside the locked and posted chain link fence surrounding the 216-Z-1A tile field. The 216-Z-3 Crib was constructed of three 1.2 meter (4 foot) long, perforated corrugated metal culverts that were laid horizontally, end to end, on a gravel filled excavation. Wire screens were welded on the ends of the pipes to prevent gravel from intruding into the pipe. 2.5 centimeter (1 inch) holes were drilled every 15 centimeters (6 inches) around the circumference of the pipe at 30 centimeter (1 foot) intervals. The culvert rests on a 5 meter (17 foot) bed of gravel, 2.4 meters (8 feet) below grade. Two layers of asphalt roofing paper were laid over the crib construction and the site was backfilled to grade.

Location: This crib is located south of the 234-5Z Building, and east of the 216-Z-1 and -2 Cribs. It is located inside the chain link fence that surrounds the 216-Z-1A Tile Field.

Related Sites/Structures: Structures associated with this crib include the 241-Z-361 Settling Tank, 216-Z-1A tile field, the chemical sewer line from the 234-5Z, and vent risers. The pipeline that fed the cribs is 200-W-210-PL.

Process Description: The 216-Z-3 Crib received Plutonium Finishing Plant process liquid waste from 1952 to 1959. Waste from the Plutonium Finishing Plant and laboratory waste streams were routed through the 241-Z-361 Settling Tank, and then distributed to the 216-Z-3 Crib. Overflow from the crib went to the 216-Z-1A tile field.

Waste Type: Process Effluent

Waste Description: The site received process waste, analytical and development laboratory wastes from the 234-5Z Building via the 241-Z Settling Tank. The waste was neutral to basic. The waste includes approximately 5.7 kilograms (12.6 lbs) of plutonium.

Code: 216-Z-9 **Classification:** Accepted

Names: 216-Z-9; 216-Z-9 Cavern; 216-Z-9 Covered Trench; 216-Z-9 Crib and Support Structures; 216-Z-9A; 216-Z-9B; 216-Z-9C; 234-5 Recuplex Cavern **Reclassification:** None

Type: Trench **Start Date:** 1/1/1955

Status: Inactive **End Date:** 1/1/1962

Description: The 216-Z-9 trench is marked and posted with Underground Radioactive Material signs. In 1999, a gravel bio-barrier, measuring 6.1 meter (20 feet) by 4 meters (13 feet), was placed over an area of surface contamination. This area is also posted as Underground Radioactive Material.

The 216-Z-9 Crib is an inactive, below grade waste management unit. It is a rectangular structure, with a concrete cover supported by six concrete columns with a concrete cover. The trench walls and support columns are covered in an acid resistant brick. Two stainless steel pipes discharge effluent above the trench bottom. Three above grade structures (216-Z-9A, 216-Z-9B and 216-Z-9C) were constructed to support the crib soil mining operations.

Location: The trench is located south of Nineteenth Street and east of the 234-5Z Building.

Release Description: On November 16, 2010, the 299-W15-47 extraction well head failed, causing more than 95 liters (25 gallons) of groundwater to spill onto the ground. The ground water contained minor amounts of carbon tetrachloride, nitrates, technetium-99, chromium and tritium. The pump and treat process was halted and the area was assessed. The well is located northeast of 216-Z-9 crib.

Related Sites/ Structures: The site is associated with the Z Plant RECUPLEX process, the steel waste transfer lines, and the soil mining facility (216Z9A). A stormwater pond occurred near this crib in the 1960's. See sitecode 200-W-124. The pipeline that fed this crib is sitecode 200-W-206-PL.

Process Description: 216-Z-9 is an enclosed trench that received solvent and aqueous wastes from the Z Plant RECUPLEX process. The 216-Z-9 trench was the only waste site used for solvent disposal during the RECUPLEX operation. Solvents used in the process included carbon tetrachloride, dibutyl phosphate and dibutyl butyl phosphonate (DBBP). In 1976 and 1977 the trench floor was mined for plutonium using remotely operated equipment. Three above grade structures (216-Z-9A, 216-Z-9B and 216-Z-9C) were constructed to support the crib soil mining operations. 216-Z-9A received the excavated crib sediments into a glove box via a conveyor system. The sediments were packaged into 10 liter cans, assayed and removed from the glove box. The cans were placed into overpack drums for storage and transportation. 216-Z-9B contained the observation area (with a leaded glass window into the crib interior) and controls for conducting the remote sediment removal. 216-Z-9C contained the mechanical components of the sediment removal equipment. This structure was sealed at the interface of the cribs concrete slab roof. Removal equipment was suspended from two openings in the crib roof, allowing access to the crib from both the north and the south areas of the crib.

Waste Type: Process Effluent

Waste Description: The trench received aqueous process waste, and organic process waste. The aqueous process waste is characterized as an acidic, high salt, low level radioactive waste, and the organic process is considered slightly acidic, low salt, high organic, radioactive liquid waste with intermediate levels of plutonium and other transuranic components. Fabrication oil used as a

cutting and milling lubricant was estimated to be 50% carbon tetrachloride and 50% lard oil. The site received an estimated 270,000 to 460,000 liters of carbon tetrachloride as waste.

Code: 216-Z-12	Classification: Accepted
Names: 216-Z-12; 241-Z-12 Crib	Reclassification: None
Type: Crib	Start Date: 1/1/1958
Status: Inactive	End Date: 1/1/1973

Description: The site is an inactive, below-grade waste management unit. The site consists of a deep rectangular excavation with a vitrified, perforated, clay pipe running the length of the crib. A second six inch diameter steel pipe (bypass pipeline) was installed in 1968 and runs the length of the crib to the west of the original pipe. The bottom 1.5 meters (5 feet) of the excavation was backfilled with gravel and covered with a polyethylene barrier. In 1987, a soil vitrification test was performed at this crib, resulting in a large, subsurface monolith of vitrified soil. The remaining excavation was backfilled to grade. It is marked and posted with Underground Radioactive Material signs.

Location: This unit is located southwest of the 234-5Z Building, outside the security fence.

Related Sites/ Structures: Structures associated with this crib include 10 monitoring wells, diversion boxes No.1 and No.2 (200-W-58 and 200-W-59), transfer lines, and monitoring instrumentation. The pipeline that fed the crib is 200-W-208-PL.

Process Description: 216-Z-12 was constructed to replace the 216-Z-3 crib. It received Plutonium Finishing Plant liquid process waste and laboratory waste from the 234-5Z Building and support facilities, via the 241-Z tanks and the 241-Z-361 Settling Tank. The crib received 2.8 x 10⁸ liters of low salt, aqueous waste containing 25.1 kg of plutonium. Americium activity was determined to be derived from the in situ decay of Pu-241 not from a separate waste source. No other transuranic elements were discharged to the crib in any significant amounts.

Waste Type: Process Effluent

Waste Description: The site received low salt process waste and analytical and development laboratory waste from the 234-5Z Building and support facilities via 241-Z tanks and the 241-Z-361 Settling Tank. The waste is slightly acidic. Low salt waste was adjusted to a pH of 8 to 10 before disposal. The waste disposed of to the crib included approximately 25 kilograms (55 lbs) of plutonium.

Code: 216-Z-18	Classification: Accepted
Names: 216-Z-18; 216-Z-18 Crib	Reclassification: None
Type: Crib	Start Date: 1/1/1969
Status: Inactive	End Date: 1/1/1973

Description: The 216-Z-18 Crib is a below grade inactive management unit. The crib consists of five parallel, north-south running trenches bisected by a steel distribution pipe. Near the center of each trench two perforated, fiberglass reinforced epoxy pipes exit each side of the distribution line. The distribution and trench piping lie on a 0.3-meter (1-foot) thick bed of gravel. The pipes were buried under an additional 0.3 meters (1 foot) of gravel, a membrane, and sand cover. The trenches were then backfilled to grade. The site is marked and posted with Underground Radioactive Material signs.

Location: This unit is southwest of the 216-Z-1A Tile Field and south of the 234-5Z Building.

Related Sites/ Structures: The crib is associated with 216-Z-1A, 241-Z-361 and UPR-200-W-103. The pipeline to the crib is 200-W-174-PL.

Process Description: 216-Z-18 crib replaced the 216-Z-1A tile field. The unit received wastes via the 241-Z-361 Settling Tank. The crib disposed of solvent and acidic aqueous waste from the Plutonium Reclamation Facility in the 236-Z Building and waste from the 242-Z Waste Treatment and Americium Recovery Facility.

Waste Type: Process Effluent

Waste Description: The crib received solvent and acidic aqueous waste from the Plutonium Reclamation Facility in the 236-Z Building. The crib received high salt, acidic, and organic liquid waste. Wastes disposed of at the site include carbon tetrachloride, tributyl phosphate, and plutonium.

Code: 241-Z-361 **Classification:** Accepted

Names: 241-Z-361; 241-Z-361 Settling Tank **Reclassification:** None

Type: Settling Tank **Start Date:** 1/1/1949

Status: Inactive **End Date:** 1/1/1976

Description: The unit is an underground reinforced concrete structure with a 0.95 centimeter (3/8 inch) steel liner. The tank has inside dimensions of 7.9 by 4.0 meters (26 by 13 feet) with 0.3 meter (1 foot) thick walls. The bottom slopes, resulting in an internal height variation between 5.2 and 5.5 meters (17 and 18 feet). The top is 0.6 meters (2 feet) below grade. A 15 centimeter (6 inch) stainless steel inlet pipe from the 241-Z Tank Pit (WIDS SiteCode 241-Z) enters the tank from the north. A single 20 centimeter (8 inch) stainless steel pipe exits the tanks from the south. There are two manhole covers and frames and several risers visible above grade.

Location: The tank is located south of the 236-Z building and was inside the Z Plant security fence.

Related Sites/ Structures: The site is related to 216-Z-1, 216-Z-2, 216-Z-3, 216-Z-12, 216-Z-1A, 216-Z-18 and the 241-Z tank farm.

Process Description: The tank served as a settling tank for liquid waste from the 234-5Z, 242-Z and 236-Z buildings. The waste streams were routed through the 241-Z sump tanks for neutralization and then to the 241-Z-361 tank to settle out any solids. After passing through the settling tank, the waste was routed to 216-Z-1, 216-Z-2, 216-Z-3, 216-Z-1A, 216-Z-12 and 216-Z-18.

Waste Type: Process Effluent

Waste Description: The unit received radioactively contaminated liquid. The tank is estimated to contain a residual 30 to 75 kilograms (66 to 165 pounds) plutonium in the sludge. (See HNF-8735 for detailed sludge sample analysis)

200-PW-3

Code: 216-A-7	Classification: Accepted
Names: 216-A-7; 216-A-7 Cavern	Reclassification: None
Type: Crib	Start Date: 1/1/1956
Status: Inactive	End Date: 1/1/1966

Description: The crib is marked and posted with Underground Radioactive Material (URM) signs. Both the 216-A-7 and 216-A-1 cribs are inside the same posted URM area.

Location: The site is located inside of the 200 East Area perimeter fence, east of 241-A Tank Farm and east of Canton Avenue.

Related Sites/Structures: The site is associated with PUREX, the 241-A-152 Diversion Box and the 241-A-302B catch tank. The pipeline associated with this crib is Sitecode 200-E-182-PL.

Process Description: The crib began receiving catch tank and sump waste from the 241-A-152 Diversion Box in January 1956. The effluent pipeline between the 241-A-152 Diversion Box sump and the crib was blanked off in July 1959. The sump waste was rerouted to the catch tank. From July 1959 through November 1966, the crib received TBP-Soltról from PUREX and pump pit/catch tank drainage from the 241-A-152 Diversion Box. A 15 centimeter (6 inch) perforated vitrified clay pipe is placed horizontally 3.0 meters (10 feet) below grade. A 3.0 meters (10 feet) length of 15 centimeter (6 inch) perforated vitrified clay pipe is perpendicular to the first pipe, forming a cross pattern. It is 4.9 meters (16 feet) deep and is filled with approximately 2.1 meters (7 feet) of coarse rock with a volume of 99 cubic meters (3,500 cubic feet). The site has been backfilled. The side slope from the surface to 3.0 meters (10 feet) is 1:1 and from 3.0 meters (10 feet) to the bottom, 2:1.

Waste Type: Process Effluent

Waste Description: From January 1956 through July 1959, the site received the catch tank overflow waste, the sump waste, and the pump pit drainage from the 241-A-152 Diversion Box. From July 1959 to November 1966, the site received the catch tank overflow waste and the pump pit drainage from the 241-A-152 Diversion Box. In November 1966, the site received the tri-butyl phosphate soltról organic inventory from the 202-A Building. The waste is low in salt and is neutral to basic.

Code: 216-A-8	Classification: Accepted
Names: 216-A-8; 216-A-8 Crib and Overflow Pond	Reclassification: None
Type: Crib	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1991

Description: The crib and overflow area are surrounded by chain and concrete AC-540 markers. They are posted with Underground Radioactive Material signs. Crib overflow was accomplished through a 40.6 centimeter (16 inch) diameter pipe exiting to the north at the east end of the crib (see H-2-56157). The pipe emptied into a narrow ditch that flowed northward. A small overflow pond was excavated at the northeast end of the ditch to receive the excess waste water from the crib.

A 61 centimeter (24 inch) diameter, schedule 20, perforated distribution pipe is located 2.1 meters (7 feet) below grade along the length of the crib. The site contains approximately 5830 cubic meters (206,000 cubic feet) of gravel fill. The crib excavation side slope is 1:2. Four test

risers extended above grade. A 20 centimeter (8 inch) diameter vent riser extended from the distribution pipe had been located at the west end of the crib. The vent riser was removed in 1995. Two layers of sisalkraft paper separate the gravel fill from the backfill. The 216-A-508 control structure is located west of the crib (See drawing H-2-56157).

Location:	The crib is located east of the 200 East Area perimeter fence, east of the 241-A Tank Farm.
Related Sites/ Structures:	The site is associated with the 241-A, 241-AX, 241-AY, 241-AZ Tank Farms, the 200-E-164-PL pipeline, the 216-A-8 Control Structure (WIDS sitecode 200-E-285) and the 216-A-508 Control Structure.
Process Description:	The crib was originally constructed in 1955 to receive condensate and cooling water discharge from the 241-A and 241-AX tank farms. In May 1958, it was determined that the crib had reached its radionuclide capacity. The effluent was routed to the 216-A-24 crib via the 216-A-508 control structure. The cooling water was routed to the 216-A-25 pond. However, the 216-A-8 crib was intermittently reactivated over the years (from 1966 until 1983) to receive additional tank farm condensate effluent.
Waste Type:	Process Effluent
Waste Description:	From 11/55 to 12/57, the site received condensate from the waste storage tanks in the 241-A and -AX farms. From 12/57 to 5/58, the site received the above effluents and cooling water from the contact condenser in the 241-A-431 Building. The site was inactive except for the following periods: 1/66-4/76, received condensate from 241-A and -AX farms; 1/78-4/78, received 241-A, -AX, & -AY farm condensate; 10/83, received 241-AY and -AZ farm condensate; 3/84, same as 10/83. In early 1985, flow was again diverted from the crib to double-shell tanks. Document RPP-7494 reports a total discharge of 1.18E+09 liters differing slightly from the WIDS total. Condensate has not been discharged to the crib since early 1985. The distribution box was filled with concrete in 1995 to permanently isolate the crib.

Code:	216-A-24	Classification:	Accepted
Names:	216-A-24; 216-A-24 Crib	Reclassification	None
Type:	Crib	Start Date:	1/1/1958
Status:	Inactive	End Date:	1/1/1966

Description:	The site is surrounded with concrete AC-540 markers and posted with Underground Radioactive Material signs. The crib was built with four sections, each 107 meters (350 feet) long, separated by soil berms. The sections were installed at increasingly lower elevations, to allow the effluent to cascade from one section to the next. The crib was constructed with a 38 centimeter (15 inch) diameter (perforated bottom half), galvanized, corrugated pipe, placed horizontally 3 meters (10 feet) below grade. The crib excavation has 4100 cubic meters (1.46E+03 cubic feet) of gravel fill. There is 46,200 square feet of polyethylene barrier laid between the gravel and the soil backfill. The side slope is 1.5:1. Eight 20 centimeter (8 inch) diameter wells on concrete pads are located on this crib. The wells extend from the bottom of the crib to 0.9 meters (3 feet) above grade. Four 38 centimeter (15 inch) corrugated risers extend from the distributor pipe to grade with filter box assemblies on top of the risers.
Location:	The crib is located east of the 200 East Area perimeter fence, and north of the 216-A-8 Crib.
Release Description:	The crib was believed to have been valved out in January 1966. However, it was found to still be receiving liquid in 1979. In June 1979, it was reported that moisture was being encountered in an excavation north of the crib, where dirt was being taken for the construction of the 241-AN Tank Farm. Follow-up surveys found a maximum of 8000 counts per minute in the moist soil (JA Jones Occurrence Report 79-19). In October 1979, seepage was again encountered on the north side of the 216-A-24 Crib (Occurrence Report 79-113). An investigation revealed

that the source of the liquid was from the 216-A-508 Control Structure, located at the 216-A-8 Crib. The valve in the control structure was found to be in an open position, allowing an unknown amount of effluent to flow to the 216-A-24 Crib. The 216-A-24 Crib had been classified as inactive since January 1966. The fact that the open valve allowed effluent to flow to the 216-A-24 Crib for thirteen years warranted the situation to be classified as an Occurrence. The 216-A-508 Diverter Box was permanently isolated with concrete in 1995.

Related Sites/ Structures: The crib is associated with the 216-A-524 Diversion Box (control structure), located at the west end of the 216-A-24 Crib. The crib is also associated with the 216-A-508 Diversion Box (control structure), located west of the nearby 216-A-8 Crib. The pipeline between the two control structures is sitecode 200-E-165-PL. The Control Structures controlled whether the effluent flow was diverted to the 216-A-8 or the 216-A-24 Crib. This site is also associated with the PUREX process, the 241-A tank farms and UPR-200-E-56.

Process Description: The crib was built to receive condensate waste from the 241-A, 241-AX, 241-AY and 241-AZ tank farms. The installation of surface condensers greatly reduced the volume of liquid being discharged to the cribs.

Waste Type: Process Effluent

Waste Description: The site received condensed vapors from the waste storage tanks in the 241-A and 241-AX Tank Farms via the 241-E-411 and 241-E-412 Contact Condensers from 1958 through the early 1960's and until 1966, via the 241-A-401 and A-417 Tank. This crib was constructed to receive the condensate after the 216-A-8 Crib reached its radionuclide capacity. The waste is low in salt, neutral to basic and has a record of organic content. The crib was believed to have been valved out in January 1966. However, it was found to still be receiving liquid in 1979 (Occurrence Report #79-113). The valve has since been closed. Because of this inadvertent use, the radionuclide exact inventory and waste volume are unknown for 1967 through 1979. Document RPP-7494 reports a total discharge of 7.94E+08 liters differing slightly from the WIDS total.

Code: 216-A-31	Classification: Accepted
Names: 216-A-31; 216-A-31 Crib	Reclassification: None
Type: Crib	Start Date: 7/1/1964
Status: Inactive	End Date: 11/1/1966

Description: The crib is located inside a large Underground Radioactive Material area that has a WIDS sitecode of 200-E-103. The crib is marked with cement posts on four corners.

Location: The site is located approximately 152 meters (500 feet) south of the 202-A Building.

Release Description: Although no contamination was released, a dose rate incident report was written in August 1961. The report indicates that the 216-A-31 Crib tie-in was made on August 25, 1961. No final inspection of the welds was done at this time. On August 27, 1961, an attempt was made to jet solvent from the F-13 tank to the new crib. Some material was transferred, but it appeared that the line was plugged. The transfer effort resulted in radioactive material being trapped in an uncovered crib line. On August 28, 1961, two employees entered the crib excavation to inspect the welds. They were in the crib excavation for approximately 5 minutes. Later the inspectors were told that an attempt had been made over the week-end to use the new crib. Radiological surveys were made to clarify what the dose rate conditions were in the crib excavation. On August 29, 1961, the exposed crib line was reading a maximum of 500 R/hr. This condition resulted in an exposure of 2 R/hr for the two weld inspectors.

Related Sites/ Structures: The crib is associated with 202-A (L cell) and the 241-A-151 Diversion Box. The pipelines associated with this crib are sitecodes 200-E-183-PL and 200-E-186-PL.

Process Description: The crib received effluent from 202-A "L-Cell" via the 241-A-151 Diversion Box. L-Cell was the location of the final plutonium concentration step in the PUREX process. The site was deactivated in 1966 by blanking the L Cell nozzles to the 241-A-151 Diversion Box, which routed effluents to the unit. The unit consists of a 21 by 3.1 by 7.3 meters (70 by 10 by 24 feet) deep excavation that includes a 7.6-centimeter (3-inch) schedule 10 stainless steel perforated distribution pipe placed horizontally 6.4 meters (21 feet) below grade. The excavation has 1.8 meters (6 feet) of gravel fill and has been backfilled. The side slope is 1:1.5.

Waste Type: Process Effluent

Waste Description: The site received organic waste from 202-A Building (L Cell - Pu concentration waste). The waste was low in salt and is neutral to basic. Most documents state that 10,000 liters (3000 gallons) of organics were discharged to the unit since startup. However, ARH-231 states that a total of 30,545 liters (8070 gallons) were discharged to the crib from the date it was put into service (January 1963).

Code: UPR-200-E-56 **Classification:** Accepted

Names: UPR-200-E-56; 216-A-24 Crib Excavation; Excavated Contamination Adjacent to 216-A-24 Crib; UN-200-E-56; UN-216-E-33 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1979

Status: Inactive **End Date:**

Description: The site is currently a surface stabilized area located north of the west end of the 216-A-24 Crib. It is posted and marked as an "Underground Radioactive Material" area.

Location: The site is located adjacent to the north side of the 216-A-24 Crib.

Release Description: On June 13, 1979, Radiation Monitoring was informed that moisture was noticed in the excavation east of the 200 East Area perimeter fence where fill dirt was being obtained for the construction of 241-AN Tank Farm. The construction contractor backfilling around the new tanks in 241-AN Tank Farm had mistakenly selected a borrow area adjacent to the 216-A-24 Crib instead of the designated area, which was further north. Radiological surveys revealed beta contamination up to 8,000 counts per minute in the moist excavation, on the earthmoving equipment, and in the newly hauled-in soil around the new 241-AN Tanks. The source of the contamination was determined to be moisture from the 216-A-24 Crib that had migrated laterally over the surface of a 10.2-centimeter (4-inch) crust of hardpan. The hardpan was approximately 4.6 meters (15 feet) below normal ground surface. The excavation was dug sloping from 1.5 to 6.1 meters (5 to 20 feet) deep, 131.1 meters (430 feet) long, and an average of 33.5 meters (110 feet) wide. The size of the excavation was approximately 0.4 hectare (1 acre).

Related Sites/Structures: The site is associated with the 216-A-24 and 216-A-8 Cribs. UPR-200-E-91, UPR-200-E-92 and UPR-200-E-93, UPR-200-E-100 were also scraped and placed into this excavation.

Waste Type: Process Effluent

Waste Description: The contamination found in the moist excavation included beta/gamma readings up to 8,000 counts per minute. When the mistakenly excavated soil was returned to the excavation area from 241-AN Tank Farm, there was not sufficient volume to fill the hole. It was decided to place contaminated soil and vegetation from several areas along the perimeter and tank farm fences to help fill the void before covering with a layer of clean dirt. Additional contaminated soil from around the 244-A Lift Station was also disposed in this location in 1985.

200-PW-6

Code: 216-Z-5	Classification: Accepted
Names: 216-Z-5; 231-W Sumps; 231-W-1 & 2 Cribs	Reclassification: None
Type: Crib	Start Date: 1/1/1945
Status: Inactive	End Date: 1/1/1947

Description: The 216-Z-5 Crib is an inactive waste management unit located below grade. The crib is oriented in a north-south configuration with a transfer pipe connecting to two wooden sump boxes. Each box was placed at the bottom of a rectangular excavation. The two excavations were the backfilled to grade.

Location: The unit is located northeast of the 231-Z Building and north of the 231-W-151 Vault.

Related Sites/Structures: The crib is associated with the vent risers, transfer lines, and the 231-W-151 Vault. The pipeline to the cribs is sitecode 200-W-202-PL.

Process Description: This crib received 231-Z Building plutonium contaminated process waste via the 231-W-151 Vault. The liquid process waste was discharged to the soil column via the crib. Over seven million gallons of waste was discharged to the cribs that contained approximately 3000 grams of plutonium.

Waste Type: Process Effluent

Waste Description: The site received process waste from the 231-Z Building via the 231-W-151 Vault. An estimated 3,000 grams of plutonium was discharged from 231-Z to these cribs. The cribs were plugged with sludge and abandoned. It is believed the plutonium is in the sludge or directly beneath the crib area.

Code: 216-Z-8	Classification: Accepted
Names: 216-Z-8; 216-Z-8 Crib; 216-Z-9; 234-5 Recuplex French Drain	Reclassification: None
Type: French Drain	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1962

Description: The french drain is constructed of two sections of 0.9-meter (3-foot) high standard clay tile culverts, stacked vertically underground. The culverts are filled with gravel and rest on a 1.5-meter (5-foot) diameter by 0.9-meter (3-foot) deep bed of gravel with a slope of 2.5:1. There is a 10-centimeter (4-inch) thick concrete top that is 2.4 meter (8 feet) below grade. The bottom of the french drain is 5.57 meters (17 feet) below grade.

Location: The french drain is located east of the 234-5Z Building, west of Camden Avenue and south of 19th Street.

Related Sites/Structures: The french drain is associated with the 241-Z-8 Silica Slurry Tank. There is a 0.46 square meters (5 square feet), 10-centimeter (4-inch) concrete collar around the base of the unit and a 10-centimeter (4-inch) steel effluent pipe leading from the silica storage tank to the top of the french drain (see sitecode 200-W-205-PL). The unit contains 2.8 cubic meters (100 cubic feet) of 2.5-centimeter (1-inch) to 7.6-centimeter (3-inch) gravel and 2.32 square meters (25 square feet) of 6.8-kilogram (15-pound) building paper over the gravel bed and beneath the top.

Process Description: The silica storage tank supernate overflowed into the 216-Z-8 French Drain from 1955 to 1962. Approximately 9,590 liters (2,530 gallons) of neutral-basic waste overflowed from the

tank during that time.

Waste Type: Process Effluent

Waste Description: The site received overflow from the Recuplex Silica Tank (neutral to basic Recuplex waste). As of June 30 1978 the calculated radionuclide content included 48.4 grams (0.1 pounds) of plutonium. The adjacent well (#299-W15-202) shows a maximum of 4,400 picocuries/gram of plutonium-239 and 440 picocuries/gram of americium-241 near the bottom of the french drain structure.

Code: 216-Z-10 **Classification:** Accepted

Names: 216-Z-10; 216-Z-2; 231-W Reverse Well; 231-W-150; 231-W-151 Dry Well or Reverse Well; 231-Z Well; 299-W15-51 **Reclassification:** None

Type: Injection/Reverse Well **Start Date:** 1/1/1945

Status: Inactive **End Date:** 1/1/1945

Description: This site is a reverse well that protruded approximately 0.31 meters (1 foot) above grade. The protruding end is capped with a flange. The well casing is constructed of steel pipe. The site was interim stabilized in 1990.

Location: The reverse well is east of the 231-Z Building and west of the 216-Z-17 Crib.

Related Sites/Structures: Structures associated with this reverse well include a manometer, three inlet lines, the 231-Z-151 Sump, and three monitoring wells (299-W15-59, 299-W15-60 and 299-W15-61). The pipeline from 231-W-151 vault to 216-Z-10 is sitecode 200-W-204-PL. The pipeline to 216-Z-5 (200-W-202-PL) includes an overflow line connected to the 216-Z-10 pipeline.

Process Description: The 216-Z-10 Reverse Well received process and laboratory waste from the 231-Z Building via the 231-Z-151 Sump between February and June 1945.

Waste Type: Process Effluent

Waste Description: The site received process and laboratory waste from the 231-Z Building, via the 231-W-151 Sump. The transuranic contaminated process waste was discharged at a rate of 76 liters (20 gallons) per minute. HW-28471 states that the small diameter well became plugged with sludge in June 1945. Approximately 988,000 liters (260,000 gallons) of liquid containing approximately 50 grams of plutonium was discharged to this unit.

Code: 241-Z-8 **Classification:** Accepted

Names: 241-Z-8; 241-Z-TK-8; Silica Slurry Tank; 216-Z-8 **Reclassification:** None

Type: Settling Tank **Start Date:** 1/1/1955

Status: Inactive **End Date:** 1/1/1962

Description: The tank is a horizontal cylindrical vessel located 1.8 meters (6 feet) below grade. The area above the tank is surrounded by a light weight chain barricade marked "Caution Underground Radioactive Material" and IMUST signs. Inside the barricade on the north end are two capped 10 centimeters (4 inches) steel vent pipes.

Location: This unit is located in 200 West Area, due east of the 234-5Z building. It is south of 19th Street and west of Camden Ave.

Release Description:	In July 1959, records indicated that the tank was at its overflow capacity, which is 58,430 liters (15,435 gallons). The tank was deactivated in 1962, and no records were found that the tank had been pumped prior to that. Surveillance data from April 6, 1974, indicates a liquid content of 28,960 liters (7,650 gallons) and sludge content of 1,890 liters (500 gallons), for a total waste volume of 30,850 liters (8,150 gallons). This means that up to 27,580 liters (7,285 gallons) may have been lost between 1962 and 1974. This possible loss has not been accounted for and no records found explain the loss.
Related Sites/ Structures:	The 216-Z-8 french drain received overflow from this unit. The pipeline to the tank is sitecode 200-W-205-PL.
Process Description:	The tank was used as a solids settling tank for back flushes of the Recuplex feed filters. Silica gel was used as a settling agent. The solids and silica gel were flushed to the 241-Z-8 tank with nitric acid. Overflow from the tank went to the 216-Z-8 French Drain, located approximately 11 meters (36 feet) east of the settling tank.
Waste Type:	Sludge
Waste Description:	The tank was used as a solids settling tank for backflushes of the feed filter in the Recuplex. Silica gel was used as a settling agent on the dissolved solids. The solids and the silica gel were then flushed to this unit with nitric acid. In July 1959, records indicate the tank was filled to capacity 58,428 liters (15,435 gallons). No records were found to indicate the tank was pumped between 1959 and 1962. In 1974, a total waste volume of 30,850 liters (8,150 gallons) was reported. A total of 27,580 liters (7,285 gallons) has not been accounted for in historical records. The tank measures 2.4 meters (8 feet) diameter, by 12.2 meters (40 feet) length, constructed of 0.79 centimeters (5/16 inch) steel or wrought iron plate, buried horizontally about 1.8 meters (6 feet) below grade. There are two blanked inlet pipes on the west end and on overflow pipe on the east end of the tank, all three are 15 centimeters (6 inches) below tank top. In the east half of the top centerline of the tank, there are two 10 centimeters (4 inches) vent risers that extend above grade, a 0.3 meters (1 foot) diameter pump access opening, and a 0.6 meter (2 feet) diameter manhole; both bolted over.

200-SW-1

Code: 600 CL **Classification:** Accepted

Names: 600 CL; 671 Facility; Central Landfill; Central Waste Landfill; CWL; Solid Waste Landfill; SWL; 600 Area Central Landfill **Reclassification:** None

Type: Sanitary Landfill **Start Date:** 1/1/1973

Status: Inactive **End Date:** 1/1/1996

Description: The landfill is approximately 15.4 hectares (38 acres) consisting of 39 unlined solid waste trenches and 5 unlined liquid disposal trenches. All trenches have been backfilled. The landfill had been enclosed by a 2.4 meter (8 foot) tall fence with lockable gates. Only the southern portion of the fence still remains, due to the 2000 range fire. The Nonradioactive Dangerous Waste Landfill (NRDWL) is located adjacent to the Phase I trenches, on the north end of the landfill.

Location: The landfill is located southeast of 200 East Area on Army Loop Road (south of Route 4S).

Related Sites/Structures: The Non-Radioactive Dangerous Waste Landfill (NRDWL) is located adjacent to the Central Landfill property. The two landfills are separated by a fence. NRDWL was isolated from the Central Landfill in 2001, when the NRDWL was completely enclosed by a chain-link fence with a separate lockable gate.

Waste Type: Asbestos (friable)

Waste Description: Prior to 1982, detailed log books were not maintained. It is estimated that Phase I received approximately 179,000 cubic meters, (234,000 cubic yards) and Phase II received approximately 417,000 cubic meters (546,000 cubic yards) of solid waste. Forty percent of the solid waste is assumed to be office waste consisting mostly of paper products. Construction and demolition debris consists mostly of wood and wooden pallets. Asbestos waste accounts for approximately 10% (by volume) of the inventory. Trenches 36, 37, 38 and 40 contain asbestos. Miscellaneous wastes include empty containers, medical waste from the first-aid stations and inert materials. Large bulky items such as appliances and office furniture were also placed in the solid waste trenches. An estimated 3,800,000 to 5,700,000 liters (1,000,000 to 1,500,000 gallons) of sewage and 380,000 liters (100,000 gallons) of 1100 Area catch basin wastes were placed in the liquid trenches. Spot checks of items in the landfill found occasional low level radioactive material on SWP (special work permit) clothing. Remediation waste from the Sodium Dichromate Barrel Disposal Landfill (sitecode 600-105) included approximately 5000 crushed barrels that were transported to the Central Landfill in 1993.

Code: 600 NRDWL **Classification:** Accepted

Names: 600 NRDWL; Nonradioactive Dangerous Waste Landfill (Central Landfill); NRDW Landfill; NRDWL; 600 Area Nonradioactive Dangerous Waste Landfill **Reclassification:** None

Type: Sanitary Landfill **Start Date:** 1/1/1975

Status: Inactive **End Date:** 1/1/1988

Description: This Nonradiological Dangerous Waste Landfill (NRDWL) consists of nineteen unlined trenches. Several trenches received asbestos containing material. The nineteen trenches are located adjacent to the Phase I trenches, on the north end of the Central Waste Landfill (CWL) (WIDS sitecode 600 CL). The Phase I trenches and the Phase II (CWL) trenches are separated

	by a wire fence. Both the CWL trenches and the NRDWL trenches have been backfilled and covered with 1.8 to 3 meters (6 to 10 feet) of soil.
Location:	This site is located on Army Loop Road, southwest of the intersection with Route 4 South and southeast of the 200 East Area.
Release Description:	In February and March 2001, the average result of quadruplicate samples from downgradient wells 699-25-34A and 699-25-34B exceeded the critical mean value for specific conductance. A notification was reported to the DOE for transmittal to Ecology. The specific nonconductance is believed to be caused by nonhazardous constituents (sulfate, calcium, magnesium, and chloride) from the adjacent solid Waste Landfill.
Related Sites/ Structures:	This site is adjacent to 600 CL, the Central Waste Landfill.
Process Description:	This site provided disposal of dangerous waste generated from process operations, research and development laboratories, maintenance activities, and transportation functions throughout the Hanford Site. The permitted chemical trenches ceased to operate in 1985. One asbestos trench was active until 1988.
Waste Type:	Abandoned Chemicals
Waste Description:	This waste consisted of small quantity laboratory chemicals, bulk organic waste, solvent waste, battery acid, paints, paint thinners, waste oils and empty containers. Some small containers of liquid wastes were included. Trenches 2N, 20, 21, 22, 23, 25, 27, 29 and 30 were used for disposal of asbestos waste from 1975 through 1988. Trenches 19N, 26, 28, 31, 33, and 34 were used for the above described chemicals.
Waste Type:	Asbestos (friable)
Waste Description:	The bulk of the waste asbestos material came from building demolition or renovation activities. This material was disposed of in Trenches 2N, 20, 21, 22, 23, 25, 27, 29, and 30. The asbestos waste was generally not containerized before disposal. It is probably a mix of friable and non-friable material.
Waste Type:	Misc. Trash and Debris
Waste Description:	This waste consisted largely of office and lunchroom waste and construction/demolition debris. Trench 1N received this waste.
Waste Type:	Sludge
Waste Description:	One instance occurred where Trench 34 received approximately 5,300 liters (1,400 gallons) of septic tank sludge.

200-SW-2

Code: 216-C-9 **Classification:** Accepted

Names: 216-C-9; 216-C-9 C Canyon Excavation **Reclassification** None
Semiworks Swamp; 216-C-9 Pond; 216-C-9
Swamp; Former 221-C Canyon Excavation; Semi-
Works Swamp; 216-C-7 Swamp

Type: Pond **Start Date:** 6/1/1953

Status: Inactive **End Date:** 1/1/1985

Description: The entire site is currently backfilled and surface stabilized. It is posted as an Underground Radioactive Material area. The solid waste burial portion of the site is not separately marked or posted from the liquid waste portion of the site.

Location: The unit is located north of 7th Street and north of the Hot Semi Works Area.

**Related Sites/
Structures:** Pipelines that fed the 216-C-9 Pond are sitecodes 200-E-254-PL, 200-E-255-PL, 200-E-256-PL, 200-E-257-PL, 200-E-258-PL and 200-E-259-PL.

**Process
Description:** The 221-C facility excavation was divided into sections with dikes. Piping was arranged to provide three discharge points, one to each section.

Waste Type: Water

**Waste
Description:** Until August 1960, the site received process cooling water from the 201-C Building; 201-C, 215-C, 271-C, and 276-C Building floor drains; and miscellaneous water from the 209-E Building and the Hot Semiworks facilities. From August 1960 to October 1969, the site received the same effluents as above plus miscellaneous wastewater from the 209-E Building. From October 1969 to December 1985, the site received miscellaneous wastewater from the Hot Semiworks facilities and the 209-E Building.

Code: 218-C-9 **Classification:** Accepted

Names: 218-C-9; 218-C-9 Burial Ground; 218EC9; Dry **Reclassification** None
Waste No.0C9

Type: Burial Ground **Start Date:** 1/1/1985

Status: Inactive **End Date:** 1/1/1989

Description: The entire site has been backfilled and surface stabilized. It is posted as an Underground Radioactive Material area. The solid waste burial portion of this waste site is not separately marked or posted from the liquid waste portion of the site.

Location: The unit is located north of 7th Street and north of Hot Semiworks Area.

**Process
Description:** The original burial pit portion was located at the east end of the dried 216-C-9 Pond excavation. The excavated area was originally intended to be the foundation for the 221-C Canyon Facility that was never built. In 1953 the facility excavation began to be used for disposal of cooling water and steam condensate from the Hot Semiworks facilities and the 209-E building. It was known as 216-C-9. Liquid discharges ceased in 1983 and the pond area began to dry. The dried pond area was covered with a layer of washed gravel. In 1985, a decision was made to use the open excavation to dispose of solid waste material from the Hot Semiworks deactivation activities. The waste site number was change to 218-C-9 to designate the area as a solid waste disposal site. A review of waste inventory records contained in the Solid Waste Inventory and Tracking System (SWITS) database found that solid waste

continued to be placed in the open excavation until September 1989. SWITS coordinates indicate truck loads of soil were placed in the excavation west of the area originally defined as 218-C-9. In 2007, the size and shape of 218-C-9 was modified to match the information found in the SWITS database.

Waste Type: Demolition and Inert Waste

Waste Description: The waste consists of radiologically contaminated concrete rubble, large equipment (pulsers), roofing material, metal scrap and other demolition debris from the decommissioning of the 201-C and other Hot Semiworks facilities. Contaminated soil from adjacent areas located east and southeast of 201-C (known as UN-216-E-37 and UN-216-E-39) was also placed into the pit.

Waste Type: Chemicals

Waste Description: Asbestos has been disposed to this burial ground, but the report does not specify if it was friable or non-friable.

Code: 218-E-1	Classification: Accepted
Names: 218-E-1; 200 East Dry Waste No. 001	Reclassification: None
Type: Burial Ground	Start Date: 1/1/1945
Status: Inactive	End Date: 1/1/1953

Description: The burial ground consists of fifteen 61 meter (200-foot) long trenches running north and south, ranging from 5 to 6 meters (16 to 20 feet) wide. The site has been backfilled and surface stabilized. It is surrounded with concrete marker posts and Underground Radioactive Material signs.

Location: The unit is located west of PUREX (202-A) and south of 4th Street.

Process Description: The site received solid waste from facilities in 200 East Area.

Waste Type: Misc. Trash and Debris

Waste Description: This unit received mixed fission product/transuranic dry waste, mostly from B Plant that began operations in 1945.

Code: 218-E-2	Classification: Accepted
Names: 218-E-2; Equipment Burial Ground #2; 200 East Industrial Waste No. 002	Reclassification: None
Type: Burial Ground	Start Date: 1/1/1945
Status: Inactive	End Date: 1/1/1953

Description: The site is a burial ground that consists of 9 industrial waste trenches. The area is posted with Underground Radioactive Material signs.

Location: The site is located north of B Plant and southeast of 241-BX Tank Farm. The site is co-located with Burial Grounds 218-E-5, 5A and 9.

Waste Type: Misc. Trash and Debris

Waste Description: This site received 0.0031 cubic meters (0.1 cubic feet) of mixed fission products/transuranic (MFP/TRU) dry wastes, which were backfilled over.

Code: 218-E-2A **Classification:** Accepted
Names: 218-E-2A; Burial Trench; Regulated Equipment Storage Site No. 02A **Reclassification:** None
Type: Burial Ground **Start Date:** 1/1/1945
Status: Inactive **End Date:** 1/1/1950

Description: The site contains a single east-west trench and was also used as an above-ground storage site for contaminated equipment. The trench is marked as an Underground Radioactive Material area.

Location: The site is located north of B Plant and south of 218-E-2. A railroad spur separates 218-E-2 from 218-E-2A.

Waste Type: Equipment

Waste Description: There are no burial records available for waste disposed of at this trench.

Code: 218-E-4 **Classification:** Accepted
Names: 218-E-4; Equipment Burial Ground #4; 200 East Minor Construction No. 4 **Reclassification:** None
Type: Burial Ground **Start Date:** 1/1/1955
Status: Inactive **End Date:** 1/1/1956

Description: It is marked and posted with "Underground Radioactive Material" signs.

Location: The site is located north of 221-B. It is an irregularly shaped polygon located between two railroad tracks.

Process Description: The site received repair and construction waste from the 221-B Building modifications. The number of trenches within this burial ground is unknown. The site was surface stabilized in 1980.

Waste Type: Construction Debris

Waste Description: This site received repair and construction wastes from the 221-B Building modifications.

Code: 218-E-5 **Classification:** Accepted
Names: 218-E-5; Equipment Burial Ground #5; 200 East Industrial Waste No. 05 **Reclassification:** None
Type: Burial Ground **Start Date:** 1/1/1954
Status: Inactive **End Date:** 1/1/1956

Description: The is site marked and posted with Underground Radioactive Material signs. It contains 2 trenches areas. One area is 104 meters (340.5 feet) long by 40 meters (131 feet) wide, containing multiple narrow trenches. The second area is a single trench 102 meters (334.5 feet) long by 19.5 meters (64 feet) wide. The trench is orientated in a north-south direction.

Location: The site is located north of B Plant and southeast of 241-BX Tank Farm, adjacent to 218-E-2 Burial Ground.

Waste Type: Equipment

Waste Description: The large area with multiple narrow trenches received industrial dry waste and small boxes. The north end of the long single trench contains railroad boxcars contaminated with uranyl nitrate hexahydrate (UNH).

Code: 218-E-5A **Classification:** Accepted

Names: 218-E-5A; Equipment Burial Ground #5A; 200 East Industrial Waste No. 005A **Reclassification:** None

Type: Burial Ground **Start Date:** 1/1/1956

Status: Inactive **End Date:** 1/1/1959

Description: The 1980 Burial Ground Characterization Report indicates the site to be a single, large excavation measuring 30.5 by 36.6 meters (100 by 120 feet).

Location: The site is located north of B-Plant and southeast of 241-BX Tank Farm, adjacent to the 218-E-5 Burial Ground. The site is co-located with Burial Grounds 218-E-2, 5 and 9.

Waste Type: Equipment

Waste Description: The site received waste from PUREX L Cell, referred to as the 202-A Burial Package, in the form of 4 large boxes containing failed equipment and industrial wastes. One of the boxes was damaged during unloading. The contents were pushed into the trench. The D-2 Column from PUREX K Cell and a J-2 Pulse column were also buried in this site.

Code: 218-E-8 **Classification:** Accepted

Names: 218-E-8; 200 East Construction Burial Grounds **Reclassification:** None

Type: Burial Ground **Start Date:** 1/1/1958

Status: Inactive **End Date:** 1/1/1959

Description: The site consists of an unknown number of trenches. The trenches are backfilled.

Location: The site is located north of the 218-E-12A, on the hillside adjacent to the 218-E-12B Burial Ground.

Waste Type: Construction Debris

Waste Description: The site received mixed fission product/transuranic (MFP/TRU) waste, including repair and construction wastes from 293-A and the PUREX new crane addition.

Code: 218-E-9 **Classification:** Accepted

Names: 218-E-9; Burial Vault (HISS); 200 East Regulated Equipment Storage Site No. 009 **Reclassification:** None

Type: Burial Ground **Start Date:** 1/1/1953

Status: Inactive **End Date:** 1/1/1958

Description: The site was used as an above-ground storage site, covering 62,000 square meters (74,000 square yards). The unit was never used as a burial ground.

Location: The site is located north of B Plant and east of the 218-E-2 Burial Ground.

Waste Type: Equipment

Waste Description: This unit was a storage site for fission product equipment that became contaminated in the uranium recovery program at the tank farm.

Code: 218-E-10 **Classification:** Accepted

Names: 218-E-10; Equipment Burial Ground #10; 200 East Industrial Waste No. 10 **Reclassification:** None

Type: Burial Ground **Start Date:** 1/1/1960

Status: Active **End Date:**

Description: The site consists of 18 trenches running north and south and 1 trench running east-west. Trench #1 is 7.3 meters (24 feet) deep with bottom dimensions of 400 meters (1,300 feet) long by 4.6 meters (15 feet) wide. Trenches #2 to #17 are 4.6 meters (15 feet) deep, 4.9 meters (16 feet) wide at the bottom, and vary in length from 245 meters (805 feet) to 350 meters (1,145 feet). The backfilled trench running east-west has bottom dimensions of 30 meters (100 feet) long by 4.6 meters (15 feet) wide.

Location: The site is located inside 200 East Area, northwest of B Plant and directly west of the 218-E-5A Burial Ground.

Release Description: On June 10, 1960, a partially covered burial box containing PUREX tube bundles caused an airborne contamination spread (UPR-200-E-23). UPR-200-E-24 documents the large plume of contamination discovered on June 12, 1960 that resulted from the burial box that collapsed at the 218-E-10 Burial Ground, identified several days after the box was buried. UPR-200-E-30 occurred on April 20, 1961. A wooden burial box, containing highly contaminated process jumpers and other equipment was pivoted on the railroad car and pulled down the unloading ramp. The box collapsed as it was being covered over with soil in the burial trench. Contamination (maximum 500 millirad/hour) was spread over a 400,000 square foot area within the burial ground. The majority of the contamination was confined to the burial ground.

Related Sites/Structures: The 218-E-10 Burial Ground is associated with the designated expansion area known as WIDS sitecode 200-E-20.

Process Description: The site has received failed equipment and mixed industrial wastes from PUREX, B-Plant and 100-N.

Waste Type: Equipment

Waste Description: The site has received failed equipment and mixed industrial wastes from PUREX, B-Plant and 100-N. The trench, running east to west, contains 69 PUREX cover blocks and 4 PUREX centrifuge blocks. Other waste includes concrete and wooden burial boxes containing tube bundles, jumper vessels, pumps, columns and filters. The trenches contain low level radiological waste, low level mixed waste, and unsegregated, remote handled waste. Trenches 9 and 12 contain some mixed-waste. Trench 9 specifically contains asbestos, di-n-octyl phthalate, and lead as mixed wastes. As of August 1995, this burial ground had received 21,764 cubic meters of waste.

Code: 218-E-12A **Classification:** Accepted

Names: 218-E-12A; 200 East Dry Waste No. 12A **Reclassification:** None

Type: Burial Ground **Start Date:** 1/1/1953

Status: Inactive **End Date:** 1/1/1967

Description: The site contains 28 burial trenches that have been backfilled and surface stabilized. The site is marked with concrete AC-540 markers and posted "Underground Radioactive Material." The area of the burial ground is 10.5 hectares (26 acres).

Location: The site is located northwest of the 241-C Tank Farm and south of 218-E-12B Burial Ground.

Waste Type: Misc. Trash and Debris

Waste Description: Trenches 1 through 3, 12 through 14, and 17 through 25 contain predominately dry waste packaged in cardboard boxes and plastic bags. Trenches 4 through 11, 15 through 16, and 26 through 28 contain predominantly acid-soaked material. Specific contents of Trench 28 are unlisted. A waste inventory logbook dated March 24, 1960 to February 16, 1961 documents burials of tank farm dip tubes, an impact wrench, contaminated cable, jumpers, animal carcasses from 108-F and an offsite shipment of depleted uranium.

Code: 218-E-12B **Classification:** Accepted

Names: 218-E-12B; 218-E-12B Burial Ground; 200 East Dry Waste No. 12B **Reclassification:** None

Type: Burial Ground **Start Date:** 1/1/1967

Status: Inactive **End Date:**

Description: The burial ground is marked and radiologically posted. The original burial ground was designed to have 29 trenches. The expansion to the north and west enlarged the burial ground to include the potential for a total of 138 trenches running north and south. Only 38 of the proposed trenches received waste. The unused, expansion area became WIDS sitecode 218-E-12B ANNEX. In 2014, the active, naval reactor core component of 218-E-12B (Trench 94) was separated into a new WIDS waste site (see 200-E-304) and the 218-E-12B site was considered inactive.

Location: The burial ground is located inside 200 East Area, north of the 241-C Tank Farm and south of 12th Street.

Related Sites/Structures: This burial ground is associated with WIDS sitecode 218-W-12B ANNEX and 200-E-304 (Trench 94).

Process Description: The burial ground received waste from 200 East Area facilities. It was designed to receive a variety of container types and a broad spectrum of waste types. Only thirty six trenches were filled completely and two trenches were partially filled (38 total). The first six trenches were 0.9 meters (3 feet) wide and 1.2 meters (4 feet) deep. The rest of the trenches were designed to be 4.8 meters (16 feet) deep. Two trenches contain retrievably stored TRU waste. A large portion of the property designated as 218-E-12B was never been used (see 218-E-12B ANNEX).

Waste Type: Equipment

Waste Description: All trenches are orientated in a north-south direction. This burial ground was used primarily for low-level waste generated mostly from facilities located in the 200 East Area. A special burial of Mixed Fission Product (MFP) was placed in Trench 28. Two trenches (trenches 17 and 27) contain 55-gallon drums, 30-gallon drums, fiberboard boxes, metal boxes, HEPA filters and equipment suspected of containing TRU waste. Coordinates for these drums were documented to allow them to be retrieved. Some waste included plutonium contaminated process piping, pumps and other equipment. As of 1995, the site had received 78,740 cubic meters of waste. Thirty six trenches were filled, two were partially filled, Trenches 38, 43, 48 and 53 was used for low-level mixed waste that included asbestos and copper. (Trench 94, used for the disposal of U.S. Navy vessel defueled reactor compartments, became WIDS sitecode 200-E-304)

Waste Type: Chemicals

Waste Description: From 1987 to 1990, asbestos and copper were disposed in Trenches 38, 43, 48 and 53.

Code: 216-T-4-2 **Classification:** Accepted

Names: 216-T-4-2; 216-T-4-2 Ditch **Reclassification:** None

Type: Ditch **Start Date:** 1/1/1972

Status: Inactive **End Date:** 1/1/1995

Description: The ditch has been backfilled and surface stabilized. It is currently marked and posted with Underground Radioactive Material signs. It has a grass cover.

Location: The site is located north of 23rd Street and north of the 241-T Tank Farm. The first 15 meters (50 feet) from the fallout (head of unit) was part of the original 216-T-4-1 Ditch. At that point, it made a 90-degree turn to the north, paralleling the old 216-T-4-1 Ditch where it went through a culvert under the railroad tracks and continued to the 216-T-4B Pond.

Related Sites/ Structures: The site is associated with the 207-T Retention Basin and the 216-T-4B Pond. The pipeline from 207-T that fed the ditch is sitecode 200-W-164-PL.

Process Description: This unit was dug as a replacement for the 216-T-4-1 Ditch in May 1972. The first 15 meters (50 feet) of the new ditch is common with the original ditch. It received T Plant cooling water and condensate waste via the 207-T Retention Basin. A 1978 radiological survey found the first 15 meters (50 feet) to be contaminated, but the remainder of the ditch was not radiologically contaminated. The ditch was constructed with riprap at head end. A 76 centimeter (30 inch) diameter, 12-gauge corrugated galvanized inlet pipe was located 0.9 meters (3 feet) below grade.

Waste Type: Steam Condensate

Waste Description: The site received steam condensate and condenser cooling water from the 242-T Evaporator and nonradioactive wastewater from 221-T air conditioning filter units and floor drains.

An early WIDS citation titled "March & May Computer Listings Research and Engineering" by MW Gibson (no date) listed the 216-T-4-2 Ditch as having 1.41g of plutonium. This source cannot be located. However, the document "Hanford Defense Waste Environmental Impact Statement Engineering Data Package: Transuranic Contaminated Soil Sites" also by MW Gibson (SW-WM-DP-007, 9/30/1985) does not list the 216-T-4-2 Ditch in its list of plutonium contaminated sites.

Code: 216-T-4A **Classification:** Accepted

Names: 216-T-4A; 216-T-4 Swamp; 216-T-4-1 (P); 216-T-4-1 Pond **Reclassification:** None

Type: Pond **Start Date:** 1/1/1944

Status: Inactive **End Date:** 1/1/1972

Description: The pond was located in a natural surface depression forming an L-shaped shallow pond covering approximately 6.5 hectares (16 acres). The pond is no longer visible. It was exhumed in 1972 to make room for the expansion of the 216-W-2A Burial Ground.

Location: The pond was located in northeast portion of the current of the 218-W-2A Burial Ground.

Release Description: A number of process vessel leaks in the 221-T Building released radioactivity to this unit over the ensuing years. At the shutdown of the 221-T process in 1957, Geiger-Mueller (GM)

radiation readings taken around the shoreline of the unit ranged from 2,000 to 15,000 counts/minute.

Related Sites/ Structures: The site is associated with the 216-T-4-1 Ditch and the 218-W-2A Burial Ground.

Process Description: The pond received cooling water and steam condensate from 221-T and 224-T via the 207-T Retention Basin and the 216-T-4-1 Ditch. The pond became active in November 1944 with the startup of the 221-T Chemical Separation Plant. The waste water in the ditch flowed through a culvert that went under the 218-W-2A Burial Ground railroad spur and then ran into a shallow ditch cut to a natural surface depression in the desert floor.

Waste Type: Steam Condensate

Waste Description: Until September 1951, the site received process cooling water from 221-T and 224-T Buildings via 207-T Retention Basin and steam condensate from 221-T Building. From September 1951 to July 1955, the site received same as above plus condenser cooling water and steam condensate from the 242-T Evaporator. From July 1955 to August 1956, same as November 1944 to September 1951. From August 1956 to June 1957, the site received steam condensate from 221-T Building. From June 1957 to July 1964, the site was on standby. From July 1964 to December 1965, the site received decontamination waste from 2706-T Building. From December 1965 to November 1970, same as above plus condenser cooling water from 242-T Building. After November 1970, the site received condenser cooling water from 242-T Building.

Code: 216-T-4B **Classification:** Accepted

Names: 216-T-4B; 216-T-4 New Pond; 216-T-4-2 (P); 216-T-4-2 Pond **Reclassification:** None

Type: Pond **Start Date:** 1/1/1972

Status: Inactive **End Date:** 1/1/1995

Description: The pond is no longer visible. The a portion of the pond is located within the area designated as the 218-W-3AE burial ground. It is not separately marked or posted from the burial ground postings.

Location: The pond was located east of old the pond 216-T-4A, north of 23rd Street. A portion of the 218-W-3AE Burial Ground was built over the dry pond location. The pond's size has been estimated as 1.5 acres.

Related Sites/ Structures: The pond was associated with the 216-T-4-2 Ditch, 200-W-81 and the 218-W-3AE Burial Ground.

Process Description: The pond was a natural depression that received overflow run off from the 216-T-4-2 Ditch. The effluent was usually absorbed in the ditch, leaving the pond area dry.

Waste Type: Steam Condensate

Waste Description: The site received steam condensate and condenser cooling water from the 242-T Evaporator and nonradioactive wastewater from 221-T air conditioning filter units and floor drains.

Code: 218-W-1 **Classification:** Accepted

Names: 218-W-1; Solid Waste Burial Ground #1; 200-W Area Dry Waste No. 001 **Reclassification:** None

Type: Burial Ground **Start Date:** 1/1/1944

Status: Inactive **End Date:** 1/1/1953

Description: The burial ground has been backfilled and surface stabilized. It is inside a 1.83 meter (6 foot) fence that encompasses this burial ground and also 218-W-4A, 218-W-11 and 218-W-2. The site contains 15 trenches that run east and west. Twelve of the trenches are "V" shaped 2.4 meters (8 feet) deep and 4.9 meters (16 feet) wide at ground level. The other 3 trenches are flat-bottom trenches 2.7 meters (9 feet) deep and 7.3 meters (24 feet) wide at the surface.

Location: The site is located northwest of the 234-5Z Building. It is east of Dayton Avenue, between the 218-W-2 and 218-W-11 Burial Grounds.

Release Description: UPR-200-W-16 is associated with the operation of this burial ground.

Waste Type: Misc. Trash and Debris

Waste Description: This site received unsegregated, pre-1970 transuranic (TRU) and miscellaneous dry waste. The radionuclide inventory is estimated to be 7E+05 grams of uranium, 9.4E+04 grams of plutonium, 3.9 curies of Sr-90 and 4.2 curies of Cs-137. The contaminated soil volume is approximately 1.6E+04 cubic meters.

Code: 218-W-1A **Classification:** Accepted

Names: 218-W-1A; Equipment Burial Ground #1; 200-W Area Industrial Waste Burial Ground #1 **Reclassification:** None

Type: Burial Ground **Start Date:** 1/1/1944

Status: Inactive **End Date:** 1/1/1960

Description: The burial ground has been backfilled and surface stabilized. It is surrounded with cement marker posts and Underground Radioactive Material signs.

Location: The burial ground is located northwest of 221-T, between two railroad spurs.

Process Description: This site was the first burial site in the 200 West Area to receive large, contaminated equipment. The site contains approximately 10 burial areas. Some are typical trenches but several areas are described as burial holes. The exact locations of the burial holes are not known, but they are within the area designated as No. 3 on H-2-2516. A semi-circular railroad spur divided the area into north and south sections. The spur is no longer visible. Most of the equipment was buried in wooden boxes, which eventually rotted and settled, causing the surface to subside. Most of these sink holes were filled in 1975. Prior to stabilization, large 1.8-meter (6-foot) thick concrete cell blocks were stored above ground, south of the railroad tracks.

Waste Type: Equipment

Waste Description: The burial ground received failed contaminated equipment and industrial waste (per RHO-CD-673).

Code: 218-W-2 **Classification:** Accepted

Names: 218-W-2; Dry Waste Burial Ground No. 2; 200-W Area Dry Waste No. 002 **Reclassification:** None

Type: Burial Ground **Start Date:** 1/1/1953

Status: Inactive **End Date:** 1/1/1956

Description: The site is a burial ground that contains 20 miscellaneous dry waste trenches, running east-

west. The site had been backfilled and stabilized. It is posted as Underground Radioactive Material.

Location: The site is northwest of the 234-5Z Building between 218-W-4B and 218-W-1.

Waste Type: Misc. Trash and Debris

Waste Description: This site received pre-1970 transuranic (TRU) and miscellaneous contaminated dry waste.

Code: 218-W-2A **Classification:** Accepted

Names: 218-W-2A; Equipment Burial Ground #2; Industrial Waste No. 02A **Reclassification:** None

Type: Burial Ground **Start Date:** 1/1/1954

Status: Inactive **End Date:** 1/1/1985

Description: The site has been backfilled and stabilized. It is posted as Underground Radioactive Material.

Location: The site is located west of the 221-T Building, north of 23rd Street and directly east of the 218-W-3 Burial Ground.

Process Description: The site is an industrial, solid waste burial site containing 19 trenches (numbered #1 to #11, and #20 to #27). Trenches #11 through #15 are considered a cell block burial area. They have a north-south orientation, located between Trenches #24 and #27. All trenches were dug with centerlines running northwest from the railroad tracks, except Trenches #1 to #3, which are shorter trenches, grouped in the extreme southwest corner of the site. Trench #16 is located east of Trench #24.

Waste Type: Equipment

Waste Description: The unit contains mostly miscellaneous radioactive solid waste from facilities located in the 200 West area. The solid waste consists mainly of tanks, concrete blocks, facility wastes, and process equipment. Sixteen trenches are filled with dry industrial waste. Trench #27 contains contaminated soil scraped from the 216-T-4-1 Pond. Waste buried since November 1980 does not contain hazardous materials. It is possible that wastes disposed of prior to this date may contain hazardous wastes. Of the 25,100 cubic meters (887,000 cubic feet) of waste contained in the unit, only 340 cubic meters (12,000 cubic feet) were disposed of after November 1980. The waste disposed of before November 1980 is both low-level and byproduct, while the waste disposed of since that date is strictly low-level. A waste burial logbook dated January 1958 through November 1963 specifically documents the burial of REDOX centrifuges, jumpers, pumps, filters and miscellaneous cell equipment and wastes. Many of the shipments were contained in large wooden or concrete boxes. One specific inventory sheet states that on October 10, 1973 a large burial box (marked B-Plant 58526) was placed in Trench 21 and contained a PU glove box and miscellaneous scrap.

Code: 218-W-3 **Classification:** Accepted

Names: 218-W-3; Dry Waste No. 003 **Reclassification:** None

Type: Burial Ground **Start Date:** 1/1/1957

Status: Inactive **End Date:** 1/1/1961

Description: This site is a burial ground that contains 20 dry waste trenches. The site has been backfilled and surface stabilized. It is posted as Underground Radioactive Material.

Location: The site is located west of the 221-T Building and directly west of the 218-W-2A Burial Ground.

Waste Type: Misc. Trash and Debris

Waste Description: This site received miscellaneous unsegregated mixed transuranic (TRU) and non-TRU wastes. A logbook dated February 1959 through June 1961 documents the burial of 109 drums of uranium scrap (depleted) from California and Oregon, placed in Trench 17, a vehicle (ID - 491) buried at the east end of Trench 14 and 49 barrels of depleted uranium from Colorado and Oregon placed in Trench 14. Waste from 221-T, 291-T, 222-U, 234-5Z, 231-Z, 202-S, 308 building and lab waste is also noted.

Code: 218-W-3A **Classification:** Accepted

Names: 218-W-3A; Dry Waste No. 003A **Reclassification:** None

Type: Burial Ground **Start Date:** 1/1/1970

Status: Active **End Date:**

Description: The site is a burial ground that was designed to contain 61 dry and industrial waste trenches running in an east-west direction. Seven are 163 meters (535 feet) long, thirty-five are 284 meters (930 feet) long, and ten are 275 meters (900 feet) long. The remaining trenches range in length from 123 meters (403 feet) to 156 meters (512 feet). The side slopes are 1:1 or as required to match the natural angle of repose. Trench depths range from 3.7 to 5.8 meters (12 to 19 feet). Four trenches have not been dug.

Location: The site is located west of the 221-T Building and north of 218-W-3 Burial Ground.

Related Sites/ Structures: 218-W-3A is associated with UPR-200-W-134.

Waste Type: Soil

Waste Description: Trench #8 contains non-TRU and TRU waste. Trenches #17 and #5 contain TRU waste. Trench #40 contains industrial waste. Trench #14 contains 10 large concrete burial boxes of radioactive soil from the 241-S Tank Farm following a salt waste spill from the 102-S Tank transfer piping in 1973. Dose rates at the site of the spill before removal of the ground ranged to a maximum of 9 mR/h. Trench #17 contains fiberglass reinforced polyester (FRP) plywood boxes in various sizes. Trench #7 contains waste from the cleanup efforts at Three Mile Island Nuclear Plant (TMI-2). All remaining filled trenches contain dry and industrial waste. Additional waste information is available in the WIDS hardcopy file for 218-W-3A.

Waste Type: Chemicals

Waste Description: Wastes disposed to this burial ground since 1987 include: 1,2,4-trimethylbenzene, acetonitrile, aliquot 336, alloy with mercury, asbestos, barium, beryllium, butyl acetate, cadmium, chromium, cyclohexanone, dibutyl-n/n-diethylcarbomyl phosphate, dioxane, ethanol, ethanalamine, isopropyl alcohol, lead, mercury, methanol, naphthalene, normal paraffins, oil, silver, toluene, tri-butyl phosphate, trioctylphosphine oxide, and xylene.

Code: 218-W-3AE **Classification:** Accepted

Names: 218-W-3AE; Dry Waste No. 3AE; Industrial Waste No. 3AE **Reclassification:** None

Type: Burial Ground **Start Date:** 3/31/1981

Status: Active **End Date:**

Description: The site was originally designed to consist of 24 trenches. To make the best use of available space, the site was redesigned to contain 12 trenches with deeper depths.

Location: This site is directly east and adjacent to the 218-W-3A Burial Ground in the 200 West Area.

Related Sites/ Structures: The site is related to the 216-T-4B Pond.

Waste Type: Misc. Trash and Debris

Waste Description: The site has been receiving miscellaneous wastes such as rags, paper, rubber gloves, disposable supplies, broken tools, etc. and industrial waste such as failed equipment, tanks, pumps, ovens, agitators, heaters, hoods, jumpers, and accessories. Trenches 2 and 3 have received remote-handled low-level waste. Trenches 5 and 10 are wide bottom stacking trenches. 218-W-3AE Trench 8 and 13 contain waste that has been encased in concrete monoliths (aka HIC or High Integrity Container). Some HICs are rectangular, measuring approximately 25 ft long by 10 ft wide and 13 feet tall. Some HICs are circular and vary in diameter. Most of the monoliths are placed together with only a cold joint separating them. Waste in the monoliths is typically category 3 waste and/or waste that requires stabilization because of mobile radionuclides. The HICs have concrete lids and are covered with a shallow layer of soil. Trench 26 was designed for disposal of contaminated railroad cars and large tanks.

Waste Type: Chemicals

Waste Description: Wastes disposed of to this site include: aluminum, asbestos, beryllium, bis(2-ethylhexyl)phthalate (DOP), calcium carbonate, cement, charcoal, clay, silicas, talc, copolymer of styrene, copper, di-n-octyl phthalate, graphite, hydrotreated heavy naphtha isopropyl alcohol, lead, mixed esters, phthalate, nylon, peroxydisulfuric acid, disodium salt, resin, sodium chloride, sodium nitrate, sodium phosphate dibasic, steel, tantalum, uranium, and yttrium oxide.

Code: 218-W-4A	Classification: Accepted
Names: 218-W-4A; Dry Waste No. 04A	Reclassification: None
Type: Burial Ground	Start Date: 6/30/1961
Status: Inactive	End Date: 2/28/1968

Description: The site is a burial ground that has been backfilled and stabilized. It is inside a chain link fence and is posted as Underground Radioactive Material. The unit contains 21 miscellaneous dry waste trenches and six vertical storage units (dry wells). The trenches are oriented in an east to west direction with Trench #1 on the southern end of the site and Trench #21 on the northern end. The six 4.6 meter (15-foot) deep dry wells were installed near the east end of Trench #16. The wells were made by welding together 210 liter (55-gallon) steel drums with the ends cut out. The units were buried vertically and used for remote disposal of small, highly radioactive items. The site may also contain two larger caissons located at the extreme east end of the burial ground, between Trenches #17 and #18 and between Trenches #18 and #19. A Hanford drawing (H-2-32487) describes them 12 gage, 66 centimeter (26 inch) diameter well casings that extend 14.6 meters (48 feet) below grade.

Location: The site is located southeast of the intersection of 23rd Street and Dayton Avenue.

Waste Type: Equipment

Waste Description: This site received miscellaneous dry, unsegregated mixed transuranic (TRU) and non-TRU waste. Specific trench contents are mentioned on Drawing H-2-32487 and in the Burial Ground logbook. These sources document the burial of approximately 500 drums of depleted uranium from offsite contractors, pumps and equipment, laboratory hoods from 234-5 Z, 231-Z, 222-U

and REDOX, and plutonium contaminated 300 Area laboratory waste. On 5-7-65, ten concrete barrels of high level plutonium were placed in Trench 16. On February 2, 1966 a Special Burial of waste from 234-5Z was made in Trench 20. Drawing H-2-32487 indicates the east end of Trench 19 contains Recuplex waste. (additional information available in the WIDS library)

Code: 218-W-4B	Classification: Accepted
Names: 218-W-4B; Dry Waste No. 04B	Reclassification: None
Type: Burial Ground	Start Date: 1/1/1967
Status: Active	End Date: 1/1/1990

Description: The site contains 13 trenches and one row of 12 caissons. Trenches 7 and 11 contain retrievable TRU waste. The other trenches contain unsegregated TRU and non TRU radioactive waste. The row of caissons include 5 alpha caissons, 6 mixed fission product (MFP) caissons and one silo type caisson used for high activity N-Reactor waste. The alpha caissons and 2 of the MFP caissons are 2.7-meter (8.75-foot) diameter, 3-meter (10-foot) high concrete containers with steel lifting lugs and a 91-centimeter (36-inch) diameter access chute. Two of the MFP caissons are constructed of corrugated steel instead of concrete. The silo type caisson is a 3-meter (10-foot) diameter, 9-meter (30-foot) tall container placed on a concrete foundation with a top concrete shielding slab. It has a 107-centimeter (42-inch) diameter access chute. All three caisson types are equipped with air filter systems.

Location: The site is northwest of the 234-5Z Building, directly west of 231-Z Building.

Waste Type: Misc. Trash and Debris

Waste Description: The site received miscellaneous radioactive solid waste from 100, 200 and 300 Areas as well as offsite shipments. Solid waste consists of rags, paper, cardboard, plastic, pumps, tanks, process equipment, and other miscellaneous high dose rate and TRU dry waste. The site contains 114,300 cubic feet of segregated (post-1970) TRU waste. Trenches 7 and 11 contain retrievable TRU waste. The other trenches contain unsegregated TRU and radioactive waste. There are twelve caissons that received remote handled high dose rate and TRU wastes. Five caissons were designated as alpha caissons, but only four were used. They were used from 1970 to 1979. Seven caissons were designated as beta/gamma caissons and were used from 1968 to 1979. The last shipment of waste was deposited into MFP caisson #6 in 1990. No additional waste is planned to be placed in the caissons. As of August 1995, the burial ground had received a total of 10,466 cubic meters of waste. (The WIDS Library has an original logbook for this burial ground)

Code: 218-W-4C	Classification: Accepted
Names: 218-W-4C; Dry Waste No. 004C	Reclassification: None
Type: Burial Ground	Start Date: 1/1/1978
Status: Active	End Date:

Description: The burial ground is located on the east side of Dayton Ave. The trenches are marked with Radiation Area, Radioactive Material Area and Underground Radioactive Material Area signs.

Location: This burial ground is located southwest of the 234-5Z Building, east of Dayton Ave.

Related Sites/Structures: 218-W-4C burial Ground is associated with the unused portion known as WIDS sitecode 218-W-4C Annex.

Process Description: The burial ground and annex were designed to contain up to 65 trenches. The main burial ground was designed to include forty-eight trenches, orientated east to west. The burial ground annex was designed to include seventeen trenches, running north to south. The burial ground annex area has never been used. Only fifteen trenches in the main burial ground have been activated. The 218-W-4C activated trench numbers are NC, 1, 4, 7, 14, 19, 20, 23, 24, 28, 29, 33, 48, 53 and 58. The burial ground annex was never used.

Waste Type: Equipment

Waste Description: Trenches #1, 4, 7, 20, 24 and 29 contain retrievably stored, suspect TRU waste. Trench #19 contains one drum of CH-TRU that is mixed with LLW. Trench 19 is being evaluated for redefinition as a Low Level Waste trench. Trench #1 contains drums with plutonium-contaminated soil from the 216-Z-9 trench and noncombustible TRU waste. Trench #4 contains drums of assorted combustible TRU waste and one module of noncombustible TRU waste. The remaining trenches are proposed. Additional waste information is available in the WIDS hardcopy file for 218-W-4C.

Waste Type: Chemicals

Waste Description: Wastes disposed of to this site include: copper, bis(2-ethylhexyl)phthalate (DOP), lead, and nitrogen.

Code: 218-W-5 **Classification:** Accepted

Names: 218-W-5; Dry Waste Burial Ground; Low-Level Radioactive Burial Grounds **Reclassification:** None

Type: Burial Ground **Start Date:** 8/29/1986

Status: Inactive **End Date:**

Description: The waste site is a large solid waste burial ground, backfilled with soil and cobbles. It is marked with radiological postings.

In 1979, a large area adjacent to the northwest corner of 200 West Area was annexed and designated the Central Waste Complex and 218-W-5 burial ground. The annexed area extended north from 16th Street to 27th Street and westward to coordinates E564176/N137630. Within the large annex, 84 acres were designated as Low Level Solid Waste Burial Grounds. 218-W-5 originally was designed to contain 18 low level solid waste trenches and 4 low level mixed waste trenches. Of the original trenches, only ten low level solid waste trenches and two low level mixed waste trenches were used. Later, line trenches 31 and 34 were constructed.

Location: The 218-W-5 Burial Ground is located in the northwest section of 200 West Area. It is west of Dayton Ave. and north of 23rd Street.

Related Sites/Structures: The Active mixed waste trenches (trench 31 and trench 34) are described in sitecode 200-W-254.

Waste Type: Not Specified

Waste Description: This unit was originally designed to store non-TRU waste and retrievable TRU waste. There were five distinct storage and disposal areas within the expansion. However, it now includes only low level radiological solid waste. The mixed waste component is sitecode 200-W-254.

Code: 218-W-11 **Classification:** Accepted

Names: 218-W-11; Regulated Storage Site **Reclassification:** None

Type: Burial Ground

Start Date: 1/1/1960

Status: Inactive

End Date: 1/1/1960

Description: The unit consists of two burial trenches. Trench #1 is 77 meters (258 feet) long, and Trench #2 is 46 meters (150 feet) long.

Location: The unit is located northwest of the 234-5Z Building, and north of 218-W-1.

Waste Type: Equipment

Waste Description: This unit was used for burial of low-level, contaminated sluicing equipment that had been used in the uranium recovery program. Some of the equipment was later taken from the unit and used in the strontium/cesium recovery program.

200-WA-1

Code: 207-S **Classification:** Accepted

Names: 207-S; 207-S Retention Basin; REDOX Retention Basin **Reclassification:** None

Type: Retention Basin **Start Date:** 1/1/1951

Status: Inactive **End Date:** 1/1/1954

Description: The basin has been backfilled to grade with dirt. It is surrounded with concrete marker posts and is currently posted with Underground Radioactive Material signs.

Location: The site is located west of the 222-S Laboratory buildings and north of 10th Street.

Release Description: A number of leaks in process vessel coils in the REDOX Plant released radionuclides into the unit from late 1952 until the unit was taken out of service. UPR-200-W-13, UPR-200-W-15, UPR-200-W-95 are associated with the site.

Related Sites/Structures: The basin is associated with the 202-S facility, the 216-S-17 pond, UPR-200-W-13, UPR-200-W-15, UPR-200-W-95 and the 200-W-152-PL pipeline.

Process Description: The basin received process cooling water and steam condensate from the 202-S facility before it was discharged to the 216-S-17 or 216-S-16 ponds. The basin was removed from service in 1954 following a 202-S coil leak that contaminated the basin above permissible limits.

The basin was a 39.6 meter by 39.6 meter (130 foot by 130 foot) concrete structure with a volume of 3.23E+06 liters (8.53E+05 gallons). The walls are approximately 25 centimeters (10 inches) thick, and the floors are 20.3 centimeters (8 inches) thick. The system included approximately 610 meters (2,000 feet) of 61-centimeter (24-inch) diameter vitrified clay pipe used to convey the waste water into and out of the unit. There is an overflow tank located in the center of the north end, just inside the basin wall, composed of 0.48-centimeter (3/16-inch) steel walls, 1.7 meters (5.5 feet) high. The tank diameter was 6.1 meters (20 feet). There is also an outlet weir structure adjacent to the south wall, outside the basin.

Waste Type: Process Effluent

Waste Description: The site received process cooling water and steam condensate from the 202-S Building. The water was then discharged to the 216-S-17 Pond or the 216-S-16 Pond. Coil leaks inside the 202-S facility often caused contaminated effluent to be discharged to the retention basin.

Code: 216-S-1&2 **Classification:** Accepted

Names: 216-S-1&2; 216-S-5 Crib; 216-S-1 & 2 **Reclassification:** None

Type: Crib **Start Date:** 1/1/1952

Status: Inactive **End Date:** 1/1/1956

Description: The cribs are located within a common radiologically posted area. The surface is free of vegetation. The area is marked and posted with Underground Radioactive Material and Cave-in Potential signs. There is an additional, small posted Underground Radioactive Material area adjacent to the south side of the cribs and the 299-W22-11 well. The Dyncorp Integrated Soil, Vegetation and Animal Control group has stated that growing, contaminated weeds were found inside this area in September 2000. The contaminated weeds were removed and disposed of properly. The site consists of two open-bottomed crib boxes made of timbers. The cribs are connected in series where overflow from the crib box S1 flows into crib box S2 via an underground pipe. The boxes were set in a gravel lined trench and backfilled.

Location: The cribs are located east of the 241-SX Tank Farm, and southeast of the 241-S-151 Diversion Box.

Release Description: In August 1955, process vapors and high dose rates were observed at the 207-S-11 Test Well (alias 299-W22-3), adjacent to the cribs. See UPR-200-W-36.

Related Sites/Structures: The associated structure is the 241-S-151 Diversion Box, 200-W-137-PL pipeline and the 216-S-7 crib.

Process Description: This unit was used as a subsurface liquid distribution system that received cell drainage and process condensate from the REDOX facility. The waste had a pH of 2.1. The waste was discharged to the cribs in batches. Each batch was approximately 19,000 liters (4940 gallons). An average of 10 batches were discharged each day. When the crib was abandoned, it had received approximately 750,000 curies of mixed fission products. It was replaced by the 216-S-7 crib.

Waste Type: Process Effluent

Waste Description: The site received cell drainage from the D-1 Receiver Tank and process condensate from the D-2 Receiver Tank in the 202-S Building. The inorganics disposed of at the site were nitrate, aluminum nitrate, nitric acid, and sodium.

Code: 216-S-4	Classification: Accepted
Names: 216-S-4; 216-S-4 Sump or Crib; 216-S-7; UN-216-W-1	Reclassification: None
Type: French Drain	Start Date: 1/1/1953
Status: Inactive	End Date: 1/1/1956

Description: The site is marked and posted with Underground Radioactive Materials signs. The site is constructed of two vertically buried metal culvert pipes.

Location: This unit is located to the east of the 216-U-10 Pond and northwest of the 216-S-21 Crib.

Related Sites/Structures: The site is associated with the condensers on the 241-S-101 and 241-S-104 Tanks located inside the 241-S Tank Farm.

Process Description: The site is constructed of two rock-filled, 6.1 meter (20 foot) long metal culverts, connected in parallel. The site received liquid from the 241-S-101 and 241-S-104 tank condensers via an aboveground pipe. The site was deactivated by removing the aboveground piping.

Waste Type: Process Effluent

Waste Description: During August and September 1953, the site received condensate and cooling water from condensers on the 241-S-101 and 241-S-104 Tanks in the 241-S Tank Farm. After September 1953, the site received the cooling water but the condensate waste was routed to the 216-S-3 Crib. The chemical component of this waste was nitrate.

Code: 216-S-5	Classification: Accepted
Names: 216-S-5; 216-S-5 Cavern #1; 216-S-6 Crib; 216-S-9	Reclassification: None
Type: Crib	Start Date: 1/1/1954
Status: Inactive	End Date: 1/1/1957

Description: The site consists of a gravel-filled crib and an overflow trench. The crib was constructed of

two lengths of perforated, corrugated metal pipe that form a cross. The crib has been surface stabilized. It is marked and posted with Underground Radioactive Material signs. The overflow trench is located south of the crib structure (see subsites).

Location: This unit is outside of the 200 West Area perimeter fence, southwest of 207-S Retention Basin and west of the 216-S-10 Ditch.

Related Sites/ Structures: The site is associated with the 202-S Building, the 207-S Retention Basin, and 216-S-6. The pipelines to the 216-S-5 crib is discussed in sitecode 200-W-154-PL and 200-W-152-PL.

Process Description: This unit received subsurface liquid disposal for the 202-S Building process vessel cooling water and steam condensate via an underground clay pipeline. The crib was built to replace the 216-S-17 Pond.

Waste Type: Process Effluent

Waste Description: The site received process vessel cooling water and steam condensate from 202-S Building via the 207-S Retention Basin. The waste was acidic and contained nitrates.

This Site has the Following SubSites:

Code: 216-S-5:1

Names: 216-S-5:1; 216-S-5 Crib

Code: 216-S-5:2

Names: 216-S-5:2; 216-S-5 Overflow Pond; 216-S-5 Overflow Trench

Code: 216-S-5:1

Classification: Accepted

Names: 216-S-5:1; 216-S-5 Crib

Reclassification: None

Type: Crib

Start Date:

Status: Inactive

End Date:

Description: The site consists of a gravel-filled crib containing two lengths of perforated, corrugated metal pipe that form a cross. The crib has been surface stabilized.

The SubSite is Part Of:

Code: 216-S-5

Names: 216-S-5; 216-S-5 Cavern #1; 216-S-6 Crib; 216-S-9

Code: 216-S-5:2

Classification: Accepted

Names: 216-S-5:2; 216-S-5 Overflow Pond; 216-S-5 Overflow Trench

Reclassification: None

Type: Crib

Start Date:

Status: Inactive

End Date:

Description: In 1956, the large cooling water discharge volumes made it necessary to cut a hole along the top edge of the crib to discharge overflow cooling water to a trench immediately southwest of the crib structure rather than allowing the crib to flood (see drawing H-6-466). The overflow of 50 to 100 gallons per minute represented approximately 5% of the total flow to the 216-S-5 crib. The emergency overflow continued throughout the summer of 1956. In September 1956, the REDOX A-2 dissolver and H-4 coils failed. The dose rates along the edge of the crib overflow area increased from 100 millirad per hour to 350 millirad per hour with some spots reading up to 17 rad per hour. The emergency crib overflow pond was used until the 216-S-16 Pond was

completed in September 1957.

The SubSite is Part Of:

Code: 216-S-5

Names: 216-S-5; 216-S-5 Cavern #1; 216-S-6 Crib; 216-S-9

Code: 216-S-6

Classification: Accepted

Names: 216-S-6; 216-S-6 Cavern #2; 216-S-13 Crib; 216-S-5 Crib

Reclassification: None

Type: Crib

Start Date: 1/1/1954

Status: Inactive

End Date: 1/1/1972

Description: This unit consists of a square pit filled with gravel with corrugated metal perforated pipe running down the center, and six pipes branching off perpendicular to the main pipe. The site is backfilled and marked with Underground Radioactive Material signs.

Location: This unit is located outside the 200 West Area perimeter fence, northwest of 216-S-5 crib and north of 216-S-17 Pond.

Related Sites/ Structures: The site is associated with the 202-S Building, the 207-S Retention Basin, the 2904-S-171 Control Structure and the 216-S-5 Crib. The pipeline to the 216-S-6 crib is discussed in sitecodes 200-W-153-PL and 200-W-156-PL.

Process Description: This unit received subsurface process cooling water and steam condensate from the 202-S Building waste via an underground pipelines (see sitecodes 200-W-153-PL, 200-W-155-PL and 200-W-156-PL). The 2904-S-171 Control Structure was built to measure and regulate flow of process waste being routed to the 216-S-6 Crib.

Waste Type: Process Effluent

Waste Description: From November 1954 until June 1967, the site received the process vessel cooling water and steam condensate from the 202-S Building. From June 1967 to July 1967, production operations were shut down and the 202-S Building was put on standby. After July 1967, the site received the steam condensate from the D-12 and D-14 Waste Concentrators in the 202-S Building. The waste is low in salt, neutral to basic, and contains nitrates.

Code: 216-S-7

Classification: Accepted

Names: 216-S-7; 216-S-7 Crib; 216-S-15

Reclassification: None

Type: Crib

Start Date: 1/1/1956

Status: Inactive

End Date: 1/1/1965

Description: The crib is marked and posted with Underground Radioactive Material and Cave-In Potential signs.

Location: The crib is located north of 10th Street, northwest of the 202-S Building.

Related Sites/ Structures: The associated structure is the 202-S Building, 240-S-151 Diversion Box and the 200-W-138-PL pipeline.

Process Description: The crib was built to replace the 216-S-1 & 2 cribs. It received REDOX cell drainage and process condensate waste. The unit consists of two wooden cribs measuring 4.9 meters (16.1 feet) square and 1.6 meters (5.2 feet). The crib boxes are set 15.3 meters (50 feet) apart, center to center, in one excavation. The cribs were set in gravel and covered with backfill. The two

cribs are connected in parallel by a pipe, allowing the flow to be equally distributed to both cribs. Each crib box had two risers that extended to the surface.

Waste Type: Process Effluent

Waste Description: From January 12, 1956 to April 12, 1959, the unit received REDOX cell drainage from the D-1 Receiver Tank, process condensate from the D-2 Receiver Tank, and condensate from the H-6 Condenser in 202-S Building. A buildup of beta activity in this crib prompted the rerouting of H-6 waste material. On April 12, 1959, jumper changes were completed that routed the H-6 liquid waste to the underground waste storage tanks. The crib continued to receive waste from D-1 and D-2 Vessels until July 1965. The chemicals disposed at the site included nitrate, aluminum nitrate, nitric acid, and sodium.

Code: 216-S-8 **Classification:** Accepted

Names: 216-S-8; Cold Aqueous Crib; Cold Aqueous Grave; Cold Aqueous Trench; Unirradiated Uranium Waste Trench; 216-S-3 **Reclassification:** None

Type: Trench **Start Date:** 1/1/1951

Status: Inactive **End Date:** 1/1/1952

Description: The site consists of one trench that has been backfilled to grade. It was fed with aboveground piping. It is marked and posted with Underground Radioactive Material signs.

Location: This unit is located on the east side of the 241-SX Tank Farm and southwest of the 216-S-1 & 2 Cribs.

Related Sites/ Structures: The associated structure is the 202-S Building.

Process Description: The site was a single use trench that received unirradiated uranium start-up waste from the 202-S Building.

Waste Type: Process Effluent

Waste Description: The site received unirradiated start-up waste from the 202-S Building. The Monthly Report for October 1951 stated approval had been given for the excavation of a trench to receive uranium test run waste. Waste concentrations were estimated to be 0.2 grams of uranium per liter. The estimated total volume was expected to be only 152,000 liters (40,000 gallons). HW-28471 states that the trench was used between October 1951 through January 1952. This document states that a total of 309,700 liters (81,500 gallons) containing 193 kilograms (430 pounds) of unirradiated uranium was discharged to this trench.

Code: 216-S-12 **Classification:** Accepted

Names: 216-S-12; 291-S Stack Wash Sump; REDOX Stack Flush Trench; UPR-200-W-30 **Reclassification:** None

Type: Trench **Start Date:** 1/1/1954

Status: Inactive **End Date:** 1/1/1954

Description: This site consists of one, single-use liquid waste disposal trench. The site is surrounded with cement marker posts and chain, posted with "Underground Radioactive Material" signs. It labeled 216-S-12.

Location: The site is located northeast of the 202-S (REDOX) facility, north of the 291-S Stack.

Related Sites/ Structures: The site is associated with the 291-S Stack.

Process Description: This site was used for liquid disposal of 291-S Stack flush water. It was fed with an overground pipeline. In July 1954, the REDOX stack was flushed and approximately 68,100 liters (18,000 gallons) of flush water that was drained into this trench.

Waste Type: Water

Waste Description: The site received 68,100 liters (18,000 gallons) of flush water from the 291-S (REDOX) Stack. The water contained ammonium nitrate (600 kilograms). The material contained an estimated five curies of beta particle emitters and two to three curies of gamma particle emitters that were predominantly ruthenium and zirconium-niobium. Potential contaminants of concern include cobalt-60, cesium-137, strontium-90, plutonium-239/240, and uranium-238.

Code: 216-S-14 **Classification:** Accepted

Names: 216-S-14; 216-S-4 Burial Contaminated Hexone; Buried Contaminated Hexone; Cold Organic Trench or Grave **Reclassification:** None

Type: Trench **Start Date:** 1/1/1952

Status: Inactive **End Date:** 1/1/1952

Description: The trench is not marked or posted. Some areas of distressed vegetation and bare ground are in the vicinity of the location indicated in historical documentation.

Location: This unit is south of 222-S, and northwest of 216-S-19 Pond. The exact location cannot be determined. HW-60807 states it is approximately 46 meters (150 feet) southeast of the 222-S Sanitary Tile Field.

Related Sites/ Structures: The site is associated with the 202-S Building.

Process Description: This site consists of a backfilled trench that received hexone contaminated with trace amounts of unirradiated uranium from the initial test runs in the 202-S REDOX facility. The waste site was fed with and aboveground pipeline.

Waste Type: Chemicals

Waste Description: The site received approximately 76,000 liters (20,000 gallons) of hexone (methyl isobutyl ketone) contaminated with trace amounts of unirradiated uranium used in the initial testing of the 202-S Building (REDOX). The site was retired when discharge of hexone to the unit was completed. The radionuclide content is unknown, but it is assumed to be low-level contamination. In 1971 core drillings were taken at this site. There was a strong odor of hexone from each of the sample cores and core holes. No radioactivity was found and the site was released from radiation zone status.

Code: 216-S-18 **Classification:** Accepted

Names: 216-S-18; 241-SX Steam Cleaning Pit; 216-S-14 Steam Cleaning Pit **Reclassification:** None

Type: Trench **Start Date:** 1/1/1954

Status: Inactive **End Date:** 1/1/1954

Description: The site consists of one backfilled trench. The area has been surface stabilized. It is posted

with light weight chain and Underground Radioactive Material signs.

Location: The site is located north of 13th Street, east of 241-S Tank Farms and southwest of 216-S-9 Crib.

Related Sites/ Structures: The site is associated with UPR-200-W-114.

Process Description: This site was originally used as a steam cleaning pit for contaminated equipment. It was later used to consolidate contaminated soil from the surrounding area and backfilled to grade.

Waste Type: Water

Waste Description: The site was originally a vehicle decontamination pit. The pit was excavated in 1972. The contaminated material was taken to a 200 West Area burial ground. In 1995 and 1997, the open trench was used to consolidate nearby surface soil contamination. The contaminated soil was covered with 1.8 meters (6 feet) of clean dirt to bring the site up to grade. The area was posted as an "Underground Radioactive Material" area.

Code: 216-S-20	Classification: Accepted
Names: 216-S-20; 216-SL-1&2 Crib; 216-SL-2	Reclassification: None
Type: Crib	Start Date: 1/1/1952
Status: Inactive	End Date: 1/1/1972

Description: The site is posted with Underground Radioactive Material (URM) signs at each corner. Two areas above the crib structures, inside the URM, are marked with post and chain and Cave-In Potential signs. An abandoned waste unloading station is located approximately 7.6 meters (25 feet) south of the posted crib. The unloading station was posted with Contamination Area signs, but later backfilled and changed to Underground Radioactive Material Area.

Location: The unit is located southeast of the 202-S (REDOX) facility and east of the 222-S Laboratory building.

Related Sites/ Structures: The site is associated with the 222-S Building, 219-S building, the 207-SL Retention Basin, and the "manhole" unloading station that received 300 Area Laboratory wastes via truck. The pipelines associated with 216-S-20 crib are discussed in sitecode 200-W-149-PL.

Process Description: The site received liquid waste from the 222-S Building and 300 Area laboratory waste via truck that was unloaded into the manhole. The manhole unloading structure is located approximately 7.6 meters (25 feet) south of the 216-S-20 radiologically posted area. The unit contains two 3.7 meter by 3.7 meter (12 foot by 12 foot) crib boxes that are 15 meters (50 feet) apart. The bottom of each wooden crib box is filled with 1.2 meters (4 feet) of gravel. Each wooden crib box has two risers extending from the top of the box to above ground. The crib boxes are connected in series with one box overflowing into another via a pipe. The cribs are backfilled to grade.

Waste Type: Process Effluent

Waste Description: From January 1952 to July 1953, the site received miscellaneous waste from lab hoods and decontamination sinks in the 222-S Building via the 219-S Retention Building. From July 1953 to September 1963, the site received the above effluent via the 207-SL Retention Basin, the 219-S Retention Building and 300 Area laboratory waste via truck, unloaded into the manhole. From September 1963 to January 1969, the site received miscellaneous waste from lab hoods and decontamination sinks in 222-S via the 219-S Retention Building. From January 1969 to November 1972, the crib was inactive due to surface subsidence on this unit. The 300 Area lab waste was rerouted to the 216-T-28 Crib.

Code: 216-S-22	Classification: Accepted
Names: 216-S-22; 216-S-22 Crib	Reclassification: None
Type: Crib	Start Date: 1/1/1957
Status: Inactive	End Date: 1/1/1967

Description: The crib is marked and posted with Underground Radioactive Material signs.

Location: The crib is located east of 202-S Building and northeast of 216-S-20 Crib.

Related Sites/ Structures: The structure is associated with the 293-S Building. The crib pipeline is WIDS sitecode 200-W-146 PL.

Process Description: The site provided subsurface liquid disposal for the 293-S Building waste. The crib is a gravel structure with a side slope of 1:1.5. A pipe enters the unit below grade, branches out at right angles downwards to the bottom, and runs along the bottom for the length of the unit. The section of pipe along the crib bottom has open joints. The rest of structure is filled with backfill. (see sitecode 200-W-146 PL)

Waste Type: Process Effluent

Waste Description: The site received liquid waste from the acid recovery facility in the 293-S Building. The chemicals disposed at the site were nitrate and sodium.

Code: 216-S-23	Classification: Accepted
Names: 216-S-23; 216-S-23 Crib	Reclassification: None
Type: Crib	Start Date: 1/1/1969
Status: Inactive	End Date: 1/1/1972

Description: The crib is marked with concrete AC-540 markers and posted with Underground Radioactive Material signs.

Location: This unit is located northeast of the 241-SY Tank Farm and north of the 216-S-9 crib.

Related Sites/ Structures: The crib is associated with the 202-S building, the 240-S-151 diversion box, 216-S-7 crib, 216-S-23 crib and the 200-W-138-PL, 200-W-139-PL and 200-W-141-PL pipelines.

Process Description: This unit provided subsurface liquid disposal for the 202-S Building. The unit is a crib with a perforated pipe set in a gravel layer, running the length of the crib. At one end of the crib a filter and gage well riser connects to the pipe. The rest of the crib contains backfill.

Waste Type: Process Effluent

Waste Description: The site received REDOX process condensate from D-2 Receiver Tank in the 202-S Building. The waste is low in salt and is neutral to basic.

Code: 216-S-25	Classification: Accepted
Names: 216-S-25; 216-S-25 Crib	Reclassification: None
Type: Crib	Start Date: 1/1/1973
Status: Inactive	End Date: 1/1/1992

Description: The site is marked with AC-540 markers and posted with Underground Radioactive Material

signs. A distribution pipe is located 2.1 meters (7 feet) below grade. The site contains approximately 1160 cubic meters (41,000 cubic feet) of gravel. Three gage wells and vent systems made of 20 centimeter (8 inch) SCH 40 PVC with a 15 centimeter (6 inch) SCH 40 PVC perforated distribution pipe.

Location: The crib is located south of 13th Street and west of the 241-SX Tank Farm; outside the 200 West perimeter fence, south and east of 216-U-10 Pond.

Release Description: The Groundwater Monitoring Compliance Report for August 1986 states that well #299-W23-09: contaminant alpha had been exceeding the U-238 concentration limit since July 1985. An increasing trend is evident due to either remedial action involving 216-U-1 & 2 cribs or to the deactivated U Pond. However, concentrations of all uranium isotopes are below their respective concentration limits. Contaminant H-3 continues to show an increasing trend even though discharge to the unit from U-1 and U-2 pumping has stopped. Well #299-W23-10: contaminant alpha has exceeded the U-238 concentration limit since June 1985. Uranium isotopic analysis of the October sample indicates U-238 exceeds the concentration limit. This report led to a groundwater pump and treat activity. The treated water was discharged to the 216-S-25 crib.

Related Sites/Structures: The crib is associated with the 242-S Evaporator building. The pipeline associated with this crib is sitecode 200-W-161-PL.

Process Description: The crib received effluent from the 242-S Evaporator building via a ten centimeter (4 inch) diameter underground pipeline (sitecode 200-W-161-PL). In 1984, the pipeline from 241-SX-402 (sitecode 200-W-159-PL) was tied into the 216-S-25 crib pipeline.

Waste Type: Steam Condensate

Waste Description: Until 11/80, the site received the 242-S Evaporator process steam condensate. Since 11/80, the 242-S Evaporator has been in standby mode. In 1985, this crib received the effluent from the 216-U-1 & 2 groundwater pump and treat effort. The 241-SX Sludge Cooler Steam Heater was shut off in 1992 due to leaking tubes. A new steam heater unit was installed in 1993 and scheduled to start up in 1995. It was to operate for five months (through winter and early spring) producing approximately 15 to 30 liters (4-8 gallons) of condensate per hour that would be discharged to the 216-S-25 crib.

Code: 216-SX-2 **Classification:** Accepted

Names: 216-SX-2; 216-SX-2 Crib **Reclassification:** None

Type: Crib **Start Date:** 1/1/1952

Status: Inactive **End Date:** 1/1/1965

Description: The crib is currently surrounded by light post and chain and posted with Underground Radioactive Material signs. It is labeled "216-SX-2" on three sides with old style black and white signs. It is a gravel filled crib topped with a subsurface layer of Sisalkraft paper.

Location: The crib is located on the east side of Cooper Ave. adjacent to the 241-SX tank Farm. It is approximately 7.6 meters (25 feet) south of the 241-SX-701 Compressor house and 23 meters (75 feet) west of the 241-SX Tank Farm fence.

Related Sites/Structures: The crib is associated with the 241-SX-701 Compressor House. The pipeline associated with this crib is sitecode 200-W-162-PL.

Waste Type: Steam Condensate

Waste Description: The crib received waste from the 241-SX-701 Compressor House.

Code:	207-T	Classification:	Accepted
Names:	207-T; 207-T Retention Basin; T Plant Retention Basin	Reclassification	None
Type:	Retention Basin	Start Date:	1/1/1944
Status:	Inactive	End Date:	1/1/1995
Description:	The retention basin has been backfilled to grade. It is delineated with concrete AC-540 markers that define it as an Underground Radioactive Material area. There is a single WIDS sitecode sign that says 207-T.		
Location:	The site is located west of 221-T Building and north of 23rd Street.		
Release Description:	On September 12, 1985, 1900 liters (500 gallons) of aqueous 5% sodium hydroxide solution containing 100 kilograms (219 pounds) of sodium hydroxide was released from T Plant to the basins and subsequently to 214-T-4-2 Ditch. At the time of the release, pH was 12.5. No cleanup actions were undertaken. After 6 hours of dilution by continued condensate discharge, the pH was 7.67.		
Related Sites/ Structures:	The basin is associated with 221-T, 224-T, 216-T-12, 200-W-53 and 216-T-4-1 and 216-T-4-2 Ditches. The inlet pipelines associated with this basin are WIDS sitecodes 200-W-88-PL, 200-W-165-PL, 200-W-166-PL and 200-W-167-PL. The outlet pipeline that leads to the 216-T-4 ditch is WIDS sitecode 200-W-164-PL.		
Process Description:	The unit was a concrete structure, divided into two sections, with a 3,800,000 liters (1,000,000 gallon) capacity. The bottom dimensions for each basin are 106 by 106 feet (32.3 by 32.3 meters). The basin received cooling water effluent from 221-T and 224-T. The basin effluent was released to the 216-T-4-1 and 216-T-4-2 Ditches. There was an inlet structure on the east side and an outlet structure on the west side, adjacent to the outside walls of the basins. Two 40.6 centimeter (16 inch) diameter cast iron pipes connected to two 0.9 meter (3 foot) sumps, one for each basin. Approximately 1830 meter (6000 feet) of 61 centimeter (24 inch) diameter vitrified clay pipeline was used to convey waste water to and from the basin. H-2-3019 shows a black iron pipeline that exits the east side of the basin, traveling south, connecting to a pipeline that is associated with the 216-TY-201 flush tank.		
	Periodically the sludge that accumulated on the bottoms of the basins was cleaned out. The sludge was placed in holes located around the perimeter of the basin and covered with clean dirt. One of these holes is documented as 216-T-12. Additional holes were probably dug and filled with sludge, but not individually documented.		
Waste Type:	Steam Condensate		
Waste Description:	The unit received potentially low-level radioactive waste from T Plant process cooling and ventilation steam condensate, which was discharged to the 216-T-4-1 and 214-T-4-2 Ditches. From 11/44 to the 1950's, the site received process cooling water from process equipment jackets in 221-T and 224-T buildings. From early 1950's to 1955, the site received the same, plus 242-T Evaporator cooling water. From 1955 to 1965, the site received the same minus 242-T Evaporator cooling water. From 1965 to late 1960's, the site received the same plus 242-T Evaporator cooling water. From late 1960's to 1973, the site received the same minus 242-T Evaporator cooling water. From 1973 to 1976, the site received the same plus 242-T Evaporator cooling water. After 1976, the site received intermittent flow from 221-T, 221-TA, and 224-T buildings. The effluent discharge was rerouted to the 200 Area TEDF in 1995. The unit was backfilled with dirt in 1996.		

Code:	216-T-2	Classification:	Accepted
--------------	---------	------------------------	----------

Names: 216-T-2; 222-T Reverse Well; 222-T-110 Dry Well **Reclassification** None

Type: Injection/Reverse Well **Start Date:** 1/1/1945

Status: Inactive **End Date:** 5/1/1950

Description: The reverse well is a below grade 15.2 centimeter well casing with a 7.6-centimeter (3-inch) diameter vent pipe extending approximately 1.2 meters (4 feet) above grade. It has been capped and is surrounded with light post and chain. A single cement AC-540 marker identifies the site. It is posted as an Underground Radioactive Material Area.

Location: The site is located near the southwest corner of the 222-T Building.

Related Sites/ Structures: The reverse well is associated with activities in the 222-T laboratory.

Process Description: During the bismuth phosphate fuel separation process, batch samples were analyzed in the 222-T and 222-B laboratories. The reverse wells were installed to provide disposal for the laboratory "hot" sink and sample table. HW-4850 states that the 222-T laboratory was discharging approximately 2.6 curies of fission products and 600 milligrams of plutonium to the dry well per month.

The well consists of a pipe extending vertically 22.9 meter (75 feet) below grade, with the last 6.1 meter (20 foot) of the pipe perforated with 39 1.3-centimeter (1/2-inch) holes-per-meter (approximately 12 holes-per-foot).

Waste Type: Process Effluent

Waste Description: The site received decontamination sink waste and sample slurper waste from the 222-T Building. HW-4850, written in 1945, states that the 222-T laboratory was discharging approximately 2.6 curies of fission products and 600 milligrams of plutonium to the dry well per month. The waste is acidic.

Code: 216-T-4-1D **Classification:** Accepted

Names: 216-T-4-1D; 216-T-4 Ditch; 216-T-4 Swamp **Reclassification** None

Type: Ditch **Start Date:** 11/1/1944

Status: Inactive **End Date:** 5/1/1972

Description: The original ditch is not currently visible. The ditch was replaced by the 216-T-4-2 Ditch in 1972. The first 15 meters (50 feet) of the original (216-T-4-1D) ditch was reused in the replacement ditch construction. The 216-T-4-1 Ditch was surface stabilized along with the 216-T-4-2 replacement ditch in 1995. The area is posted as an Underground Radioactive Material area.

Location: The site was located north of 23rd Street, west of the 221-T Building and northwest of the 241-T Tank Farm.

Related Sites/ Structures: The ditch is associated with the 216-T-4A Pond and the 216-T-4-2 Ditch. Pipeline 200-W-163-PL connected to the ditch. The pipeline from 207-T that fed the ditch is sitecode 200-W-164-PL.

Process Description: The ditch received T Plant cooling water and condensate waste via the 207-T Retention Basin.

Waste Type: Steam Condensate

Waste Description: From 1944 to September 1951, the site received process cooling water from the 221-T and 224-T Buildings via the 207-T Retention Basin and steam condensate from 221-T Building. From September 1951 to July 1955, the site received the above listed streams plus condenser cooling water and steam condensate from 242-T Evaporator. From July 1955 to August 1956, the site received the same as November 1944 to September 1951. From August 1956 to June 1957, the site received steam condensate from 221-T. From June 1957 to July 1964, the site was on standby. From July 1964 to December 1965, the site received decontamination waste from 2706-T. From December 1965 to November 1970, the site received the above listed streams plus condenser cooling water from 242-T Building. After November 1970, the site received condenser cooling water from 242-T Building. The total plutonium is 1.41 grams (3.1E-3 pounds) according to Hanford Defense Waste Environmental Impact Statement data.

Code: 216-T-8	Classification: Accepted
Names: 216-T-8; 222-T-1 & 2 Cribs	Reclassification: None
Type: Crib	Start Date: 1/1/1950
Status: Inactive	End Date: 1/1/1951

Description: The site consists of two wood crib boxes, each set into a pit with sloped sides. Each crib pit has 4.3-meter (14-foot) by 4.3-meter (14-foot) bottom dimension, with a 1:1 side slope. The pits are 23 meters (75 feet) apart. The boxes have risers and are connected in series by a pipe. One box overflows into the other. The pits are backfilled.

Location: This site is located just on the east side of the 224-T Building.

Related Sites/Structures: The associated structure is the 222-T and 292-T Facilities (see 200-W-40). The pipeline to 216-T-8 is sitecode 200-W-142-PL.

Process Description: This site provided subsurface liquid disposal for 222-T Decontamination Sink Waste and Sample Slurper waste. A pipeline from 292-T teed into the 216-T-8 waste line.

Waste Type: Process Effluent

Waste Description: The waste was neutral to basic, and contained sulfuric acid, nitric acid, and sodium dichromate.

Code: 216-T-9	Classification: Accepted
Names: 216-T-9; Decontamination Trenches; Equipment Decontamination Area	Reclassification: None
Type: Trench	Start Date: 1/1/1951
Status: Inactive	End Date: 1/1/1954

Description: This site consists of a backfilled trench. The site is no longer marked or posted.

Location: This site is located west of the 221-T Building and southwest of the 216-T-33 Crib.

Related Sites/Structures: The site is associated with trenches 216-T-10 and 216-T-11.

Process Description: This site was used for subsurface liquid disposal of vehicle decontamination waste from heavy equipment and other vehicles.

Waste Type: Water

Waste Description: The site received heavy equipment and vehicle decontamination waste. No radionuclide or chemical contamination has been documented for this site according to DOE/RL-91-61. However, ARH-2757 states that all contamination (maximum 3000 counts per minute) was buried in the 200 West Dry Waste Burial Ground. Although no cleaning agents are listed, the possibility of hazardous chemical contamination exists.

Code: 216-T-10 **Classification:** Accepted

Names: 216-T-10; Decontamination Trenches; Equipment Decontamination Area **Reclassification:** None

Type: Trench **Start Date:** 1/1/1951

Status: Inactive **End Date:** 1/1/1954

Description: This site consists of a backfilled trench. The site is no longer marked or posted.

Location: This site is located west of the 221-T Building and southwest of the 216-T-33 Crib.

Related Sites/ Structures: The site is associated with trenches 216-T-9 and 216-T-11.

Process Description: This site was used for subsurface liquid disposal of heavy equipment and vehicle decontamination waste.

Waste Type: Water

Waste Description: The site received heavy equipment and vehicle decontamination waste. No radionuclide or chemical contamination has been documented for this site according to DOE/RL-91-61. However, ARH-2757 states that all contamination (maximum 3000 counts per minute) was buried in the 200 West Dry Waste Burial Ground. Although no cleaning agents are listed, the possibility of hazardous chemical contamination exists.

Code: 216-T-11 **Classification:** Accepted

Names: 216-T-11; Decontamination Trenches; Equipment Decontamination Area **Reclassification:** None

Type: Trench **Start Date:** 1/1/1951

Status: Inactive **End Date:** 1/1/1954

Description: This site consists of a backfilled trench. The site is no longer marked or posted.

Location: This site is located west of 221-T and southwest of the 216-T-33 Crib.

Related Sites/ Structures: The site is associated with the 216-T-9 and 216-T-10 trenches.

Process Description: This site was used for subsurface liquid disposal of heavy equipment and vehicle decontamination waste.

Waste Type: Water

Waste Description: The site received heavy equipment and vehicle decontamination waste. No radionuclide or chemical contamination has been documented for this site according to DOE/RL-91-61. However, ARH-2757 states that all contamination (maximum 3000 counts per minute) was buried in the 200 West Dry Waste Burial Ground. Although no cleaning agents are listed, the possibility of hazardous chemical contamination exists.

Code: 216-T-12	Classification: Accepted
Names: 216-T-12; 207-T Sludge Grave; 207-T Sludge Pit; 216-T-11	Reclassification: None
Type: Trench	Start Date: 1/1/1954
Status: Inactive	End Date: 1/1/1954

Description: There is no visible evidence of this waste site. The area around the 207-T Retention Basin, including the northeast corner where this pit was located, has been stabilized with clean backfill material and posted with Underground Radioactive Material signs. The sludge pit is not separately marked.

Location: This site is located at the northeast corner of the 207-T Retention Basin.

Related Sites/ Structures: The associated structure is the 207-T Retention Basin.

Process Description: The site was a small trench that was dug November 1954 with a backhoe at the northeast corner of the 207-T Retention Basin. Sludge dredged from the 207-T Retention Basin was put into the trench and covered.

Waste Type: Sludge

Waste Description: The site received contaminated sludge from the 207-T Retention Basin. The waste is low in salt and is neutral to basic.

Code: 216-T-13	Classification: Accepted
Names: 216-T-13; 269-W Decontamination Pit or Trench; 269-W Regulated Garage; 269-W Regulated Garage Decontamination Pit; 216-T-12	Reclassification: None
Type: Trench	Start Date: 1/1/1954
Status: Inactive	End Date: 1/1/1964

Description: The site consisted of a single open trench located west of the 269-W Regulated Garage. The garage has been demolished. Currently, there is a concrete ramp covered with 0.6 meters (2 feet) of gravel that is visible near the site of the garage. The trench is no longer marked or posted.

Location: This site is located on the north side of the 241-TY Farm, north of the tank farm perimeter fence. The site has been shown at two locations on different maps. Drawing H-2-1495 (originally made in 1952) shows the location of the trench adjacent to the 269-W garage and northwest of the 241-TY Tank Farm, while a later drawing (H-2-32526, 1967 Rev 3) shows the trench due north of the 241-TY Tank Farm. The mapped location in HGIS is due north of the Tank Farm as of December 2001.

Related Sites/ Structures: The site was associated with activities at the 269-W Regulated Garage, but the garage was not physically connected to the vehicle decontamination trench.

Process Description: This site was used to clean contaminated vehicles. A Tip Rack was located in the bottom of the open trench. Vehicles were driven into the trench and onto the rack. The vehicles were then sprayed with water or steam to remove the contamination. The decontamination was often required prior to vehicles being serviced at the 269-W Garage.

Waste Type: Water

Waste Description: The site received vehicle decontamination liquid waste. The inventory prior to the removal of 3.06 cubic meters (4 cubic yards) of soil was estimated through 1972 as follows. ARH-2757, part 3 states the volume was 0.98E+05 liters; <0.100E+00 grams - plutonium; 0.840E+02 curies - beta; 0.100E00 curies - strontium-90; 0.400E+02 curies - ruthenium-106; 0.100E+00 curies - cesium-137; > < 0.100E+00 curies - cobalt-60; <0.500E-01 kilograms - uranium. ARH-1608 states the volume was 0.026E+06 liters; ><0.100E+00 grams - plutonium; 60 curies - beta; 1.00E+00 curies - strontium-90; 40 curies - ruthenium-106; 1.00E+00 curies - cesium-137; > < 0.100E+00 curies - cobalt-60; <.1 pounds of uranium. Readings up to 1,500 counts per minute were measured in the excavated soil. Although no cleaning agents are listed, the possibility of hazardous chemical contamination.

Code: 216-T-20 **Classification:** Accepted

Names: 216-T-20; 216-T-20 Crib; 216-TX-2; 241-TX-155 Contaminated Acid Grave **Reclassification:** None

Type: Trench **Start Date:** 11/1/1952

Status: Inactive **End Date:** 11/1/1952

Description: The site has a small concrete block structure on the surface with a metal lid labeled Confined Space and Potential Internal Contamination. There is a single concrete marker with an Underground Radioactive Material sign on it. The concrete block structure is surrounded with the same type of cobbles that surround the powerhouse pond.

Location: The unit is located east of Camden Avenue, adjacent to the north end of the 200 West Area Power House Pond.

Related Sites/Structures: The site is associated with the 241-TX-155 Diversion Box.

Process Description: The historical documentation describes the site as an excavation, similar to a pit. It was a single use pit dug specifically to receive contaminated acid from the 241-TX-155 Diversion Box. There is no mention of the concrete block access structure currently located at the site.

Waste Type: Process Effluent

Waste Description: The site received contaminated nitric acid from 241-TX-155 Diversion Box Catch Tank.

Code: 216-T-27 **Classification:** Accepted

Names: 216-T-27; 216-TX-2 Cavern; 216-TX-2 Crib; 216-TY-2 Cavern; 216-TY-2 Crib **Reclassification:** None

Type: Crib **Start Date:** 1/1/1965

Status: Inactive **End Date:** 1/1/1965

Description: The 216-T-26, 216-T-27 and 216-T-28 cribs are enclosed within a common steel post and chain barricade that is posted "Underground Radioactive Material". The 216-TY-201 flush tank is located in the northeast corner of the area.

Location: This site is located inside 200 West Area, south of 23rd Street and east of Camden Ave.

Related Sites/Structures: The crib is associated with 221-T, 2706-T, 216-TY-201 Flush Tank, 200-W-188-PL and 200-W-82 Truck Unloading Station. The pipelines associated with this crib are 200-W-175-PL and 200-W-188-PL.

Process Description: The underground pipeline from the 241-TY Tank Farm to the 216-T-26 crib was isolated with a blank flange in 1956. An underground pipeline from the 241-T Tank Farm was used to transfer waste from T Plant (after it cascaded through tanks 241-T-110, 241-T-111 and 241-T-112) to the 216-T-27 and 216-T-28 cribs. The tanks contained steam condensate and process decontamination waste from T Plant along with 2607-T equipment decontamination waste. In 1964, 300 Area laboratory waste was shipped from the 340 facility by truck to the 200 West Area. The 300 Area waste was combined with the T-Plant waste that was discharged to cribs 216-T-27 and 216-T-28. Lundgren (1971) mentions a crib riser being used for the disposal of 300 Area waste (see sitecode 200-W-82).

A letter written by G.L. Ritter (1966) stated that the 300 Area waste and the T Plant waste had been diverted from the 216-T-28 Crib to the 216-T-27 Crib in November 1965 due to an increase in the groundwater contamination levels below the 216-T-28 Crib. Only a limited amount of 300 Area waste had been expected and the 216-T-27 Crib was estimated to be used for approximately 18 months. However, information was collected that indicated the 300 Area waste discharged to the 216-T-27 Crib did not react favorably with the soil at this crib location. It was recommended that this crib be deactivated earlier than expected (see ISO-636).

Waste Type: Process Effluent

Waste Description: The site received 300 Area lab waste containing nitrates, 221-T steam condensate and process decontamination waste and equipment decontamination waste from 2706-T. A page of typed, unsigned notes was found that documents the transport of "round the clock" trucking of waste from the PRTR rupture incident in September 1965. The notes indicate that the waste would be discharged into the 216-T-27 crib. A different page of notes, also unsigned, states that more than 100 truck loads of liquid waste from the PRTR incident was discharged into the 216-T-28 crib during September and October 1965. Since the same truck unloading station would have been used for either crib, it is difficult to be sure how much waste was discharged to the 216-T-27 and how much was discharged to the 216-T-28 crib.

Code: 216-T-28 **Classification:** Accepted

Names: 216-T-28; 216-TX-3 Cavern; 216-TX-3 Crib; 216-TY-3 Cavern; 216-TY-3 Crib **Reclassification:** None

Type: Crib **Start Date:** 1/1/1960

Status: Inactive **End Date:** 1/1/1966

Description: The 216-T-26, 216-T-27 and 216-T-28 cribs are enclosed within a common steel post and chain barricade that is posted "Underground Radioactive Material". The 216-TY-201 flush tank is located in the northeast corner of the area.

Location: This site is located inside 200 West Area, south of 23rd Street and east of Camden Ave.

Related Sites/ Structures: The associated structures are the 221-T Building, 2706-T Building, 216-TY-201 Flush Tank and 200-W-82 Truck Unloading Station. The pipelines associated with this crib are 200-W-175-PL and 200-W-188-PL.

Process Description: The underground pipeline from the 241-TY Tank Farm to the 216-T-26 crib was isolated in 1956. The 216-T-27 and 216-T-28 Cribs were active from February 1960 to December 1966. An underground pipeline from the 241-T Tank Farm was used to transfer waste from T Plant (after it cascaded through tanks 241-T-110, 241-T-111 and 241-T-112) to the 216-T-27 and 216-T-28 cribs. The tanks contained steam condensate and process decontamination waste from T Plant along with 2607-T equipment decontamination waste. In 1964, 300 Area laboratory waste was shipped from the 340 facility by truck to the 200 West Area. The 300 Area waste was combined with the T-Plant waste that was discharged to cribs 216-T-27 and 216-T-28.

Lundgren (1971) mentions a crib riser being used for the disposal of 300 Area waste (see sitecode 200-W-82 Truck Unloading Station). In May 1966, waste from the 2706-T Building was rerouted to the 216-T-4 Ditch. In December 1966, the pipeline to the crib and the 300 Area waste disposal riser were isolated. The 300 Area laboratory waste was sent to the 216-T-34 Crib. The T Plant effluent was rerouted to the 216-T-36 Crib.

Waste Type: Process Effluent

Waste Description: From February 1960 through February 1963, the crib received steam condensate and process decontamination waste via the 241-T-112 tank in the 241-T Tank Farm. In 1963, 2706-T equipment decontamination waste was added to the waste stream. In 1964, 300 Area laboratory waste was sent to this crib via tanker trucks from the 340 Waste Transfer Facility. A page of typed, unsigned notes dated October 26, 1965 indicated that 189 truck loads of liquid waste from 300 Area were discharged into the 216-T-28 crib between September 13, 1965 and October 25, 1965. The total volume during that time was 945,000 gallons. Most of the waste was from the PRTR rupture incident. The crib was deactivated in December 1966 when the prescribed radionuclide disposal limit was reached.

Code: 216-T-29 **Classification:** Accepted

Names: 216-T-29; 216-T-29 French Drain; 291-T Sand Filter Sewer **Reclassification:** None

Type: French Drain **Start Date:** 1/1/1949

Status: Inactive **End Date:** 1/1/1964

Description: The 291-T Sand Filter is located northeast of the 221-T building. The 216-T-29 French Drain is part of the sand filter construction. The sand filter is marked and posted as a Contamination Area. There is a vent riser protruding through the roof of the northwest corner of the sand filter. This is assumed to be the location of the drain.

Location: The french drain is located adjacent to the north end of the 291-T Sand Filter and northeast of the 221-T Building.

Related Sites/ Structures: The associated structure is 200-W-45 (291-T Sand Filter).

Process Description: This site received canyon air condensate from the 291-T Sand Filter. In the 1950's, silver reactor filters, made of fiberglass soaked in silver nitrate, were added to the stack ducts.

Waste Type: Steam Condensate

Waste Description: The site waste was moisture condensed from canyon air and included 8000 kilograms of nitric acid. In the 1950's, silver reactor filters were added to the stack ducts. They were made of fiberglass soaked in silver nitrate. The filters reacted with the radioiodine to form silver iodide.

Code: 216-T-31 **Classification:** Accepted

Names: 216-T-31; 216-T-31 French Drain **Reclassification:** None

Type: French Drain **Start Date:** 1/1/1954

Status: Inactive **End Date:** 1/1/1962

Description: The site consisted of a 0.9 meter (3 foot) diameter french drain. The drain was exhumed and left unmarked. A post with the WIDS Sitecode 216-T-31 now marks the approximate location of where the french drain had been.

Location: This site was located west of Camden Ave., near the southeast corner of the 241-TX Farm, on the east side of 241-TX Tank Farm fence.

Process Description: The unit was in operation in 1954 and abandoned in 1959 after it was contaminated by steam condensate from a steam line blowout during efforts to unplug a waste line (October 1959). A new steam line was installed in 1959 and a new steam condensate drain was made to replace the contaminated drain.

Waste Type: Steam Condensate

Waste Description: The drain was accidentally contaminated by contaminated steam condensate from a blowout through the steam line during efforts to unplug a waste line in October 1959.

Code: 216-T-33	Classification: Accepted
Names: 216-T-33; 216-T-33 Crib	Reclassification: None
Type: Crib	Start Date: 1/1/1963
Status: Inactive	End Date: 1/1/1963

Description: The site is surrounded with light metal posts and chain. It is posted with Underground Radioactive Material signs. The site consists of a rectangular crib with perforated vitreous clay inlet pipe set into a gravel layer. A layer of plastic sheeting, clean sand, and backfill are above the pipe.

Location: This unit is located west of 221-T Canyon Building and southwest of 2706-T.

Related Sites/Structures: The site is associated with the 2706-T Decontamination Building. The pipeline associated with this crib is 200-W-173-PL.

Process Description: This site provided subsurface liquid disposal for the 2706-T Building. After the line plugged, the 2706-T waste was routed to the 216-T-28 crib, via the 241-T-112 tank.

Waste Type: Water

Waste Description: The site received equipment decontamination waste from the 2706-T Building. The waste is low in salt, neutral to basic, and contains sodium hydroxide. There total effluent discharged to the crib is questionable, due to the fact that the discharge line plugged shortly after the crib became active.

Code: 216-T-34	Classification: Accepted
Names: 216-T-34; 216-T-34 Crib	Reclassification: None
Type: Crib	Start Date: 1/1/1966
Status: Inactive	End Date: 1/1/1967

Description: The site is a crib posted with "Underground Radioactive Material" signs. The crib's piping consists of perforated vitrified clay pipe rectangular loop, and a vitreous clay pipe extending into the center of the crib. The piping rests on a layer of gravel. Two gage well risers and one filter riser are visible from the surface.

Location: This site is located northwest of the 221-T Building, on the east side of the 216-T-35 Crib.

Related Sites/Structures: The crib is associated with the 340 waste facility located in the 300 Area. This crib also had an associated railcar unloading station (200-W-21). The pipeline from the railcar unloading station to the 216-T-34 crib is sitecode 200-W-196-PL. The pipeline from the truck unloading

station to the crib is sitecode 200-W-198-PL.

Process Description: This site provided subsurface liquid disposal for waste from the 340 Building in the 300 Area. The waste was transported to 200 West Area in railroad tank cars and 5000 gallon tank trucks.

Waste Type: Process Effluent

Waste Description: The site received liquid 300 Area laboratory waste from the 340 Facility. The waste was low in salt, neutral to basic, and contained nitrate.

Code: 216-T-35 **Classification:** Accepted

Names: 216-T-35; 216-T-35 Crib **Reclassification:** None

Type: Crib **Start Date:** 1/1/1967

Status: Inactive **End Date:** 1/1/1968

Description: The site is a surface stabilized crib that is marked and posted with Underground Radioactive Material signs. The crib was constructed with one perforated drain line, and one perforated crib waste distribution line, in parallel. Both lines were placed horizontally below grade and covered by gravel. The crib has two gage well risers and one vent riser visible from the surface.

Location: This site is located west of the 221-T Building and west of the 216-T-34 crib.

Related Sites/Structures: The crib is associated with the 340 Building in the 300 Area, the railcar unloading station (200-W-21) and the 216-T-34 crib. The pipeline associated with this crib is 200-W-197-PL. The pipeline from the truck unloading station is 200-W-198-PL.

Process Description: This site provided subsurface liquid disposal for waste from the 340 Building in the 300 Area. The 216-T-35 crib replaced the 216-T-34 crib. The drain line from the unloading station (200-W-21) was extended to the 216-T-35 crib distributor pipe. The 216-T-34 crib drain line was blanked. Waste was transported from the 340 facility in railroad tanker cars and 19,000 liter (5,000 gallon) tank trucks.

Waste Type: Process Effluent

Waste Description: The crib received waste from the 300 Area laboratory facilities via railroad tank cars and tank trucks. The site waste contained nitrate.

Code: 216-T-36 **Classification:** Accepted

Names: 216-T-36; 216-T-36 Crib **Reclassification:** None

Type: Crib **Start Date:** 5/1/1967

Status: Inactive **End Date:** 1/1/1973

Description: The site consists of a interim stabilized crib posted as "Underground Radioactive Material". The site consists of a single vitreous clay distribution pipe resting in a gravel layer that is in a rectangular trench. Backfill covers the pipe and gravel. The crib also has a gage well riser and a filter riser.

Location: The site is located southwest of the 241-T Tank Farm and south of the 216-T-7 Tile Field.

Release Description: The May 2000, the Dyncorp Integrated Site Vegetation and Animal Control (ISVAC) Priority List and the Contamination Zone map identified a long, narrow area of posted contamination adjacent to the east end of the 216-T-36 Crib (#12 on their list). The posted area appears to be located over the buried pipeline that fed the crib. (See WIDS 200-W-79-PL).

Related Sites/ Structures: The associated structures are the 221-T, 221-U, 2706-T Buildings and the 241-T-151 Diversion Box. The pipelines associated with this crib is 200-W-79-PL and 200-W-130-PL.

Process Description: This site provided subsurface liquid disposal for steam condensate, equipment decontamination waste, and miscellaneous waste from the 221-T and 221-U Buildings. It also received decontamination waste from the 2706-T Building.

Waste Type: Process Effluent

Waste Description: The site received steam condensate, equipment decontamination waste, and miscellaneous waste from the 221-T, 221-U and the 2706-T buildings. Some waste contained sodium hydroxide.

Code: 241-T-361 **Classification:** Accepted

Names: 241-T-361; 241-T-361 Settling Tank; 361-T-TANK **Reclassification:** None

Type: Settling Tank **Start Date:** 1/1/1944

Status: Inactive **End Date:** 1/1/1951

Description: The 241-T-361 Tank is enclosed with light post and chain and concrete AC-540 markers. The underground tank is posted with Inactive Miscellaneous Underground Storage Tank and Underground Radioactive Material signs.

Location: The tank is located southwest of the 221-T Building and north of 23rd Street. It is adjacent to the 216-T-6 Cribs.

Related Sites/ Structures: The settling tank is associated with the 216-T-3 Reverse Well, 216-T-6 Cribs and the 221-T and 224-T facilities. The pipeline from 224-T that fed the reverse well via the 241-T-361 tank is sitecode 200-W-226-PL.

Process Description: The 241-T-361 Settling Tank received radioactive contaminated liquid from the 221-T and 224-T Buildings. The tank discharged to the 216-T-3 Reverse Well during 1945 and 1946. When the reverse well was abandoned, the settling tank discharge was directed to the 216-T-6 Cribs. The 241-T-361 Settling Tank was deactivated in June 1951. Settling Tank 241-T-361 is cylindrical and is made of reinforced, pre-stressed concrete. The tank is located underground for shielding purposes.

Waste Type: Storage Tank

Waste Description: The tank received waste from 221-T and 224-T. Sludge samples taken in 1976 contained 23 micrograms of plutonium, 12 microcuries per gram of strontium-90 and 67.6 microcuries per gram of cesium-137. The liquid supernate contained 3.71 microcuries per gallon of cesium-137 and 14.5 milligrams per gallon of plutonium.

Code: 207-U **Classification:** Accepted

Names: 207-U; 207-U Retention Basin **Reclassification:** None

Type: Retention Basin **Start Date:** 1/1/1952

Status: Inactive **End Date:**

Description: The basin is a concrete basin divided into two equal halves, with a capacity of 3.785E+06 liters (1E+06 gallons). One half of the basin is lined with plastic. The basin structure is posted as a Contamination Area.

Location: The site is located inside 200 West Area, near the corner of 16th St and Camden Ave. It is west

of 221-U Building, north of 16th Street, and east of the 241-U Tank Farm.

Release Description: Occurrence Report 86-46 states that on August 6, 1986, 2365 liters (625 gallons) of recovered nitric acid, containing 39 kilograms (86 pounds) of uranium was discharged through the chemical sewer to the 207-U retention Basin. Prior to the discovery of the release, the outlet valves on the retention basin were open to the 216-U-14 Ditch. The acid released to the ditch was greatly diluted with the 300 gallon per minute flow of cooling water from the 224-U facility being processed through the chemical sewer system. The Hanford Site Waste Management Units Report (1987) reported different release values. It states that approximately 3,000 liters (796 gallons) of 50% reprocessed nitric acid was released to the basin and subsequently to 216-U-14 Ditch. The total release to the environment consisted of approximately 102,000 kilograms (225,000 pounds) of corrosive solution (pH less than 2.0) and 45.4 kilograms (100 pounds) of uranium.

Related Sites/ Structures: There is an inlet structure on the east and an outlet structure on the west side, on the outside of the basins. Each basin has a 0.9 by 0.9-meter (3 by 3-foot) sump. There is also a sampler cabinet and a sample vault on the east side of the basins near the inlet structure. The chemical sewer pipeline that fed the basin is sitecode 200-W-192-PL. The outlet pipe to the 216-U-14 ditch is sitecode 200-W-222-PL.

Process Description: During the Uranium Trioxide (UO₃) facility deactivation, the trench that runs between 224-UA and 224-U was tied into the 207-U retention basin pipeline to route the stormwater buildup from the contaminated zones on the backside of the facility to the 207-U Basins for solar evaporation. The basin outlets have been isolated with concrete. The stormwater accumulating in the basin is allowed to evaporate. The Hanford Operational Environmental Monitoring Program will continue to monitor the air and soil in the vicinity of the basins to meet requirements stated in the National Emissions Standards for Hazardous Air Pollutants (NESHAP) for monitoring of diffuse and fugitive sources. Originally, the basin received chemical sewer waste from the 221-U Building and cooling water from the 224-U Building. The water was held in the basin, sampled, and then discharged to the 216-U-10 Pond via the 216-U-14 Ditch. For several years, the basin receives stormwater runoff from the 224-U Building and grounds. The outlet was plugged so that the basins would serve as an evaporation pond for the stormwater it received. During the U Plant Deactivation Project, manholes in two process sewer pipelines (200-W-84-PL and 200-W-192-PL) were filled with grout to isolate U Plant and 224-U from the retention basin. This also eliminated the flow of stormwater to the basin.

Waste Type: Steam Condensate

Waste Description: Until 1972, the unit received steam condensate and cooling water from 224-U Building and chemical sewer waste from the 221-U Building. After 1972, the unit has received only cooling water from 224-U Building. The basin was temporarily replaced by 216-U-16 Crib (1984 through 1986) but was reactivated when 216-U-16 Crib was taken out of service. The effluent from the basin was discharged to the 216-U-10 Pond via the 216-U-14 Ditch until the basin outlet was plugged in 1994. The basin later received storm water run off from the 224-U building area. The water was directed to a plastic lined portion of the basin and allowed to evaporate.

Code: 216-U-1&2 **Classification:** Accepted

Names: 216-U-1&2; 216-U-2; 216-U-3; 216-UR #1&2 **Reclassification:** None
Cribs; 361-WR (Crib 2); 216-U-1; 216-U-1 & 2

Type: Crib **Start Date:** 1/1/1951

Status: Inactive **End Date:** 1/1/1967

Description: The crib area has been surface stabilized with clean dirt. The wood timber cribs are co-located

in a common Underground Radioactive Material area. Each crib is delineated with posts and chain with Cave-In Potential signs.

Location: The site is north of 16th Street, west of 221-U and east of the 207-U Retention Basin.

Release Description: See UPR-200-W-19 and Unusual Occurrence 85-17.

Related Sites/ Structures: The cribs are associated with the 241-U-361 Settling Tank, UPR-200-W-19, the 224-U Building and 221-U Building. The pipeline associated with this crib is 200-W-194-PL.

Process Description: The cribs received overflow from the 241-U-361 Settling Tank. The tank received cell drainage from the 5-6 tank in 221-U and waste from the 224-U Building until the Uranium Recovery process operations shut down in 1957. From July 1957 through May 1967, the 216-U-1&2 Cribs received waste from the 224-U Facility and equipment decontamination waste and reclamation waste from the 221-U canyon. The cribs are two wooden structures that operated in series.

Waste Type: Process Effluent

Waste Description: From March 1952 to June 1957, the site received cell drainage from Tank 5-6 (221-U Building) and waste from the 224-U Building via the overflow from the 241-U-361 Settling Tank. From June 1957 to July 1957, the site received waste from the 224-U Building via the overflow from the 241-U-361 Settling Tank and contaminated solvent from the 276-U Settling Tank Solvent Storage area. The discharge of 221-U waste was discontinued during shutdown of production operations. From July 1957 to May 1967, the site received waste from the 224-U Building and equipment decontamination and reclamation wastes from Chemical Processing Division (CPD) Services Operations in the 221-U Building canyon. Crib 2 was deactivated in May 1967. The waste is low in salt and is neutral to basic.

Code: 216-U-3 **Classification:** Accepted

Names: 216-U-3; 216-U-3 French Drain; 216-U-11 **Reclassification:** None

Type: French Drain **Start Date:** 1/1/1954

Status: Inactive **End Date:** 1/1/1955

Description: This site consists of a french drain with light steel posts and chain with "Underground Radioactive Material" signs. The drain is a 3.6 meter (12 foot) deep, 1.8 meter (6 foot) diameter, rock-filled excavation with sloping sides and a 10 centimeter (4 inch) diameter vent riser.

Location: This site is located south of the 241-U Tank Farm on the south side of 16th Street.

Related Sites/ Structures: The french drain is associated with the 241-U-104, 241-U-110 Tanks and the 200-W-169-PL pipeline.

Process Description: This site received condensate from the steam condensers on the 241-U-104 and 241-U-110 Tanks. Most reference documents mention this site receiving waste from 241-U-110, but drawing H-2-44004 also shows the 241-U-104 tank having a condenser that is attached to the same pipeline as the 241-U-110 tank.

Waste Type: Steam Condensate

Waste Description: This 216-U-3 crib received condensate from the steam condensers on the 241-U-104 and 241-U-110 tanks. The 241-U-104 and 241-U-110 tanks held REDOX boiling waste. The site waste contains nitrate. The closed loop cooling water for the condensers was discharged to the 216-U-14 ditch.

Code: 216-U-4 **Classification:** Accepted
Names: 216-U-4; 216-U-4 Reverse Well; 222-U Dry Well; 222-U-110 Dry Well; 216-U-2 **Reclassification:** None
Type: Injection/Reverse Well **Start Date:** 3/1/1947
Status: Inactive **End Date:** 7/1/1955

Description: This site consists of a deactivated reverse well. The well consists of a three inch diameter pipe sunk into the ground to a depth of 75 feet. The bottom 25 feet of pipe is perforated. The end of the pipe is nearly closed by flattening. The site was marked with a small cement cover and a bronze medallion. It is posted as "Underground Radioactive Material".

Location: This site is located at the southwest corner of the 222-U Building.

Related Sites/ Structures: The site is associated with the 222-U Building.

Process Description: The site received acidic decontamination waste containing fission products from the 222-U Laboratory hood sinks.

Waste Type: Process Effluent

Waste Description: RHO-CD-673 states that both plutonium and fission products were discharged to the site from laboratory hoods and sinks. (U Plant did not process plutonium. It is not clear what the 222-U laboratory may have tested) The site waste contains nitrate. A limited field investigation of high-priority waste units was conducted from August 1993 through August 1994. This site was included in that investigation. DOE/RL-95-13 includes information related to characterization borehole 299-W19-98 that was drilled between 216-U-4 and 216-U-4A. Cesium-137, cobalt-60 and europium-154 were identified.

Code: 216-U-4A **Classification:** Accepted
Names: 216-U-4A; 216-U-4 Dry Well; 216-U-4 Reverse Well Replacement French Drain **Reclassification:** None
Type: French Drain **Start Date:** 1/1/1955
Status: Inactive **End Date:** 1/1/1970

Description: This site is a french drain that is posted "Underground Radioactive Material". The drain consists of a vertically set concrete pipe. The drain rests on undisturbed soil and is not gravel filled. The top of the drain is painted yellow and has a removable lid.

Location: This site is located at the southwest corner of the 222-U Building. It is approximately one foot southeast of the 216-U-4 reverse well.

Related Sites/ Structures: The site is associated with the 222-U Building and the 216-U-4 Reverse Well.

Process Description: From July 1955 to January 1965 the site received acidic decontamination waste containing fission products from hood sinks in the 222-U. Waste flowed to the 216-U-4A French Drain via the overflow line from the deactivated 216-U-4 Reverse Well. From January 1965 to July 1970 the site received Pacific Northwest Laboratory operations decontamination waste from a hood sink in the 222-U Building.

Waste Type: Process Effluent

Waste Description: The site waste contains nitrate, phosphate, and sodium. RHO-CD-673 states that both plutonium and fission products were discharged to the site from laboratory hoods and sinks. A limited field investigation of high-priority waste units was conducted from August 1993 through August 1994. DOE/RL-95-13 includes information related to characterization borehole 299-W19-98 that was drilled between 216-U-4 and 216-U-4A. Cesium-137, cobalt-60 and europium-154 were identified.

Code: 216-U-4B **Classification:** Accepted

Names: 216-U-4B; 216-U-4B Dry Well; 216-U-4B French Drain **Reclassification:** None

Type: French Drain **Start Date:** 1/1/1960

Status: Inactive **End Date:** 1/1/1970

Description: The site consists of a french drain that is under a cement pad. A one inch diameter stainless steel vent riser extends approximately 1.2 meters (4 feet) above the surface. It is posted with "Underground Radioactive Material" signs.

Location: This site is located on the southeast side of the 222-U Building.

Related Sites/Structures: The site is associated with the 222-U Building. The 200-W-107 Miscellaneous Stream drain is located very near the 216-U-4B site.

Process Description: From January 1960 to July 1970 the site received waste from a hot cell and hood in the 222-U Building. From January 1965 to July 1970, the site received waste from hoods and hot cells in 222-U from Pacific Northwest Laboratory work.

Waste Type: Process Effluent

Waste Description: From January 1960 to July 1970 the site received waste from a hot cell and hood in the 222-U Building. From January 1965 to July 1970 the site received hot cell and hood waste from Pacific Northwest Laboratory experiments conducted in 222-U. The site waste contains nitrate.

Code: 216-U-5 **Classification:** Accepted

Names: 216-U-5; 221-U Cold U Trench #2; 216-U-4 **Reclassification:** None

Type: Trench **Start Date:** 1/1/1952

Status: Inactive **End Date:** 1/1/1952

Description: This site consists of a backfilled trench that is posted "Underground Radioactive Material".

Location: The site is located northwest of the 221-U building.

Related Sites/Structures: The site is associated with the 221-U building and the 216-U-6 trench.

Process Description: This site was used as liquid disposal site for unirradiated uranium waste from the cold start-up run at 221-U.

Waste Type: Process Effluent

Waste Description: This site received liquid unirradiated uranium waste from the cold start-up run at 221-U. The waste contained 200 kilograms of nitrate.

Code: 216-U-6 **Classification:** Accepted

Names: 216-U-6; 221-U Cold U Grave #1; 221-U Cold U Trench; U Facility Unirradiated Uranium Waste Trench; 216-U Cold U Trench #1; 216-U-5 **Reclassification** None

Type: Trench **Start Date:** 1/1/1952

Status: Inactive **End Date:** 1/1/1952

Description: This site consists of a backfilled trench that is posted "Underground Radioactive Material".

Location: The site is located northwest of the 221-U building.

Related Sites/ Structures: The site is associated with the 221-U building and the 216-U-5 trench.

Process Description: This site was used as liquid disposal site for unirradiated uranium waste from the cold start-up run at 221-U.

Waste Type: Process Effluent

Waste Description: In March 1952, the site received liquid, unirradiated uranium waste from the cold start-up run at 221-U. The waste included 200 kilograms of nitrate.

Code: 216-U-7 **Classification:** Accepted

Names: 216-U-7; 221-U Counting Box French Drain; 221-U Vessel Vent Blower Pit French Drain **Reclassification** None

Type: French Drain **Start Date:** 1/1/1952

Status: Inactive **End Date:** 1/1/1957

Description: The french drain is within a larger area that has been stabilized and posted with Underground Radioactive Material signs. This drain is constructed of a concrete pipe set vertically into the ground. Gravel fills 1.1 meters (3.5 feet) of the pipe.

Location: This site is located on the southeast side of the 221-U Building near Section 6. It is northwest of the 241-UX-154 Diversion Box.

Related Sites/ Structures: The site is associated with the 221-U Building, UPR-200-W-162 and UPR-200-W-138. The pipeline from the counting box to the french drain is sitecode 200-W-217-PL.

Process Description: This site received liquid wastes from a counting box floor drain during the metal recovery program at the 221-U Building.

Waste Type: Process Effluent

Waste Description: The site received liquid wastes from a counting box floor drain during the metal recovery program. The site waste contains nitrate. Due to UPR-200-W-138, it is assumed that 13 kilograms (30 pounds) of uranium in uranyl nitrate hexahydrate (UNH) solution were also introduced to the soil through the 216-U-7 French Drain. However, the release associated with UPR-200-W-138 may be associated with a different french drain. The release information is vague. It is possible the event effected the 216-U-7 French Drain if sufficient liquid volume was released to the surface to flow southward and reach the 216-U-7 French Drain location.

Code: 216-U-8 **Classification:** Accepted

Names: 216-U-8; 216-U-9; 216-WR-1,2,3 Cribs **Reclassification** None

Type: Crib **Start Date:** 1/1/1952
Status: Inactive **End Date:** 1/1/1960

Description: The site is marked and posted with Underground Radioactive Material signs. Adjacent contaminate soil was scraped and placed on top of the crib, creating a mound. The contaminated soil was covered with an additional 0.3 to 0.6 meters (1 to 2 feet) of clean soil.

Location: The site is located west of Beloit Avenue and south of 16th Street.

Related Sites/ Structures: The site is associated with 270-W, 216-U-12, 200-W-42, the 221-U and 224-U Buildings and the 291-U Stack.

Process Description: The cribs received acidic process condensate from the 221-U and 224-U buildings along with drainage from the 291-U stack via an underground vitrified clay pipeline.

Waste Type: Process Effluent

Waste Description: The site received process condensate from 221-U and 224-U Buildings and the 291-U Stack drainage. The waste is acidic.

Code: 216-U-12 **Classification:** Accepted

Names: 216-U-12; 216-U-12 Crib **Reclassification:** None

Type: Crib **Start Date:** 1/1/1960

Status: Inactive **End Date:** 1/1/1988

Description: The site is marked and posted with Underground Radioactive Material.

The bottom of the crib was filled with approximately 264 cubic meters (9,320 cubic feet) of gravel. A perforated 30-centimeter (12-inch) vitrified clay pipe runs horizontally the length of the unit below grade.

Location: The crib is located south of 16th Street and west of Beloit Avenue. It is south of the 216-U-8 crib.

Related Sites/ Structures: The crib is associated with 270-W, 216-U-8, the 224-U facility, 291-U stack and pipeline sites 200-W-42-PL and 200-W-151-PL.

Process Description: The 216-U-12 Crib was built in 1960 to replace the 216-U-8 Crib when it showed signs of cave-in potential. 216-U-12 was operational until 1988, when the pipeline was cut and capped. The 216-U-12 Crib was replaced by the 216-U-17 Crib.

Waste Type: Process Effluent

Waste Description: From April 1960 to May 1967, the site received 291-U-1 Stack drainage, 241-WR Vault waste (aka 244-WR vault), and 224-U process condensate via the C-5 Tank. Contaminated water from the 241-WR Vault was discharged to the crib in October 1965 that included 3.14 kilograms (6.9 pounds) of thorium. From May 1967 to September 1972, the site received the above wastes (excluding the 241-WR Vault waste) and occasional waste via the C-7 Tank in the 224-U building. From September 1972 to November 1981, the site was taken out of service. From November 1981 to January 1987, the site received corrosive process condensate (corrosive: [D002] typical pH range is 0.5-1.5) from the 224-U building. The crib also received miscellaneous storm drain wastes from 224-U building. Between April 1960 and September 1972, 6.7 E5 kilograms of nitrate was released to the crib from the Uranium Tri-Oxide process.

Code: 216-U-13	Classification: Accepted
Names: 216-U-13; 216-U-13 Cribs; Vehicle Steam Cleaning Pit	Reclassification: None
Type: Trench	Start Date: 1/1/1952
Status: Inactive	End Date: 1/1/1956

Description: This site consisted of two trenches of equal dimensions. The trenches were sloped so that vehicles could be driven down to the decontamination station at the bottom. The two trenches are no longer marked or posted. Some debris is visible in the area. The area is not level. Many deep gullies are located in the area west of the 241-U Tank Farm.

Location: This site was located west of the 241-U Tank Farm.

Process Description: The site received drainage from equipment steam cleaning and decontamination activities done inside the trenches. The pits were used mainly to decontaminate trucks and cranes bearing low levels of radioactive contamination. Several large pumps used in the Uranium Recovery process were also cleaned here, but the residue was scraped and taken to the 200 West Burial Grounds.

Waste Type: Water

Waste Description: The site used steam and water hoses to remove radioactive contaminants from vehicles, equipment and pumps from the Uranium Recovery operation. The site waste may include traces of detergent and nitric acid.

Code: 216-U-14	Classification: Accepted
Names: 216-U-14; 216-U-14 Ditch; Laundry Ditch	Reclassification: None
Type: Ditch	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1995

Description: The entire ditch has been backfilled and surface stabilized. It is posted as Underground Radioactive Material.

Location: The ditch originated west of the 284-W Powerhouse, west of Bridgeport Avenue. It extended southward, terminating at the 216-U-10 Pond.

Release Description: Occurrence Report 86-46 states that on August 6, 1986, 2365 liters (625 gallons) of recovered nitric acid, containing 39 kilograms (86 pounds) of uranium was discharged through the chemical sewer to the 207-U retention Basin. Prior to the discovery of the release, the outlet valves on the retention basin were open to the 216-U-14 Ditch. The acid released to the ditch was greatly diluted with the 1140 liter (300 gallon) per minute flow of cooling water from the 224-U facility being processed through the chemical sewer system. The outlet valves from the retention basin were closed shortly after the discovery of the release and the remainder of the acid release was contained in the retention basin. The effluent in the retention basin was neutralized with 270 kilograms (600 pounds) of sodium carbonate. The Hanford Site Waste Management Units Report (1987) reported different release values. It stated approximately 3000 liters (796 gallons) of 50% reprocessed nitric acid was released to the unit. The total release to the environment consisted of approximately 101,250 kilograms (225,000) pounds of corrosive solution (pH less than 2.0) and 45.4 kilograms (100 pounds) of uranium.

Related Sites/Structures: The ditch is associated with the 284-W Powerhouse, 2723-W (old laundry facility), 2724-W (new laundry facility), 221-U, 224-U, 271-U the 242-S Evaporator building and the 241-U-110 tank. The 200 West Area Powerhouse Pond was constructed over the location of the head end of the 216-U-14 Ditch. The direct pipeline from 221-U is 200-W-84-PL. The pipeline from

2724-W is 200-W-102-PL. A pipeline from 241-U tank farm to the 216-U-14 ditch is sitecode 200-W-168-PL. The outlet pipe from 207-U is sitecode 200-W-222-PL. The effluent discharge pipe from 242-S Evaporator to the 216-U-14 ditch is sitecode 200-W-223-PL.

Process Description: The 216-U-14 ditch was excavated in 1944 and was the original effluent route to the 216-U-10 Pond. It received powerhouse waste water, laundry waste water (until 1981) via 200-W-102 Pipeline, and steam condensate and cooling water from 221-U, 224-U and the 242-S Evaporator. Near the head end of the ditch, a 0.6 meter (2 foot) diameter pipe allowed 284-W Powerhouse and laundry effluent to flow under 19th Street and connect to the main portion of the ditch. The ditch also had a 1.22 meter (4 foot) diameter culvert that allowed effluent to flow under 16th Street to the portion of the ditch located north of the 242-S Evaporator and also flowed under Cooper Ave. to terminate at 216-U-10 Pond.

Waste Type: Process Effluent

Waste Description: From 7/44 to 9/44, the site received wastewater from the 284-W Powerhouse. From 9/44 to 1/50, the same plus waste from 2723-W (original laundry and mask cleaning station). From 1/50 to 3/52, received wastewater from 284-W and 2724-W Laundry Building (new laundry facility). From 3/52 to 5/54, the same plus chemical sewer waste from 221-U and cooling water from 224-U. From 5/54 to 8/55, the same plus cooling water from 241-U-110 condenser tank. From 8/55 to 11/73, the same plus 271-U cooling water. From 11/73 to 4/80, the same plus 242-S Evaporator condensate and cooling water. From 4/80 to 9/81, the same minus 242-S condensate, 2723-W and 2724-W waste. From 9/81 to 7/84, the same minus 221-U, 224-U, and 271-U waste. The 221-U and 224-U effluent entered the ditch after passing through the 207-U Retention Basin. The 216-U-16 crib was built in 1984 to accept 224-U effluent that had previously been discharged to the ditch. However, the 216-U-16 crib failed in 1985. Some 224-U effluent was diverted back to the 216-U-14 Ditch until November 1994, when the outlet pipe to the 207-U Retention Basin was permanently isolated and filled with concrete. The portion of the ditch, located west of Cooper Ave., received effluent from the 242-S Evaporator and remained active until April 1995. Discharge from the 242-S Evaporator was eliminated in 1995 ending all discharges to this unit.

Code: 216-U-15 **Classification:** Accepted

Names: 216-U-15; 388-U Tank Dumping; U-152 **Reclassification:** None
Interface Crud Burial; UN-200-W-158; UN-216-W-10; UPR-200-W-125

Type: Trench **Start Date:** 1/1/1957

Status: Inactive **End Date:** 1/1/1957

Description: The site is the result of a deliberate discharge of liquid waste into a hole in the ground. No surface markers exist to identify the exact location of this waste unit. Originally, the site was delimited by a wooden fence and posted with Underground Contamination signs. The perimeter fence and all identification markings of this site were removed in 1971.

Location: The site was located west of the 271-U Building and north of 16th Street.

Related Sites/ Structures: The 216-U-15 Trench was associated with the 388-U Tank and the 276-U Solvent Storage Area.

Process Description: Approximately 26,500 liters (7000 gallons) of material was discharged via an overground pipeline. The hole was backfilled and the piping was removed after the transfer was completed. HW-50584 indicates conflicting information. The May 1957 monthly report states that 79,494 liters (21,000 gallons) of organic solution (RAX) was originally scheduled to be transferred to the PUREX plant, but was buried because it was found to be incompatible with the PUREX process. The material was buried, with minor ground contamination occurring

when the overground line used to transport the material from 276-U leaked. One 8 inch culvert was replaced and the contaminated ground was dug up and buried.

Waste Type: Chemicals

Waste Description: This site received 26,500 liters (7,000 gallons) of waste from the 388-U Tank in the 276-U Solvent Building. The waste consisted of interface crud, activated charcoal, and diatomaceous earth containing approximately 1 curie of fission products. HW-50584 indicates conflicting information. The May 1957 monthly report states that 79,494 liters (21,000 gallons) of organic solution (RAX) was originally scheduled to be transferred to the PUREX plant, but was buried because it was found to be incompatible with the PUREX process.

Code: 216-U-16

Classification: Accepted

Names: 216-U-16; UO3 Crib

Reclassification: None

Type: Crib

Start Date: 1/1/1984

Status: Inactive

End Date: 1/1/1987

Description: The crib is identified with concrete AC-540 markers and is posted with Underground Radioactive Material signs.

Location: The crib is located south of 16th Street, between Beloit and Cooper Avenues, southwest of the 224-U Building.

Related Sites/ Structures: The crib is associated with the 224-U and the 221-U facilities and the 216-U-14 ditch. The pipeline that feeds this crib is sitecode 200-W-170-PL.

Process Description: The crib was activated on July 20, 1984. The 216-U-16 crib was built to receive waste from the 224-U Uranium Oxide Processing Facility. The crib is constructed of two header pipes, 20 centimeters (8 inch) reducing to 15 centimeters (6 inch) that are located 0.9 meters (3 feet) above the crib bottom, running the length of the unit, one on each side. At each end of the pipe is a 15 centimeter (6 inch) vent pipe. Connecting the two header pipes were twenty-two 10 centimeter (4 inch) perforated pipes running the width of the unit, equally spaced, 0.9 meters (3 feet) above the bottom. Each header pipe has a 10 centimeter (4 inch) vent riser. An acid resistant distribution box is located at the crib inlet (northeast edge). A short pipeline connected the crib to the existing VCP Process Sewer line. In July 2000, the vent risers were sealed and cut off below grade. There are three gage wells, one near the north and south ends and one near the center. The bottom is filled with 1.5 meters (5 feet) of gravel. Covering the gravel is a reinforced polyethylene liner extending 2.4 meters (8 feet) up the sides of the excavation. The crib structure has been backfilled over to grade. A 15 centimeter (6 inch) subdrainage pipe runs the width of the unit at the west side.

Waste Type: Process Effluent

Waste Description: The site received 224-U steam condensate, 224-U chemical sewer waste, 271-U compressor cooling water, 221-U chemical sewer waste, and 224-U process condensate.

Code: 216-U-17

Classification: Accepted

Names: 216-U-17; 216-U-17 Crib

Reclassification: None

Type: Crib

Start Date: 1/1/1988

Status: Inactive

End Date: 1/1/1994

Description: The crib is marked and posted with Underground Radioactive Material signs.

Location: The crib is located south of 16th Street and east of Beloit Ave. inside the 200 West Area. It is southeast of the 221-U facility.

Related Sites/ Structures: The crib is associated with the 224-U facility and the 200-W CSLA. The pipeline associated with the crib is sitecode 200-W-195-PL.

Process Description: The crib was built to replace the 216-U-12 cribs. The crib received effluent from the 224-U building process condensate from the conversion of uranyl nitrate hexahydrate (UNH) to Uranium Tri-oxide (UO₃) through the calcining operations. The process condensate was neutralized prior to discharge to the crib. Effluent flow was evenly distributed over the entire unit from the distribution line lying in an aggregate field with a PVC vapor barrier. The site footprint is 70 meters by 26 meters (230 feet by 86 feet). The stormwater runoff from the 224-U facility was rerouted to the 207-U basins.

Waste Type: Process Effluent

Waste Description: The unit received 224-U process condensate. A neutralization system was placed into operation before startup of this crib to preclude the discharge of process condensate outside the range of 2.0 to 12.5 pH.

Code: 241-U-361 **Classification:** Accepted

Names: 241-U-361; 241-U-361 Settling Tank; 361-U-TANK **Reclassification:** None

Type: Settling Tank **Start Date:** 1/1/1951

Status: Inactive **End Date:** 1/1/1967

Description: The 241-U-361 Tank is an underground settling tank constructed of reinforced concrete. The 216-U-1&2 Cribs and the 241-U-361 Settling Tank are co-located within a common radiologically controlled area. It is posted with Underground Radioactive Material (URM). Due to the 1953 release, the surface surrounding the settling tank has been covered with shotcrete. The tank is posted with Inactive Miscellaneous Underground Storage Tank (IMUST) signs.

Location: The 241-U-361 Settling Tank is located southwest of 221-U, north of 16th Street.

Related Sites/ Structures: This unit is associated with the 221-U building, UPR-200-W-19 and the 216-U-1 and 216-U-2 Cribs. The pipeline to the tank is sitecode 200-W-193-PL. The pipeline from the tank to the 216-U-1 and 2 cribs is sitecode 200-W-194-PL.

Process Description: The tank received cell drainage from the 5-6 tank in 221-U and waste from the 224-U building until the Uranium Recovery operations shut down in 1957. From July 1957 through May 1967, the 216-U-1&2 Crib system received waste from the 224-U facility and equipment decontamination waste and reclamation waste from the 221-U canyon via the 241-U-361 tank. The waste flowed through the 241-U-361 settling tank and then to the 216-U-1 and 2 cribs, located 26 meters (85 feet) west, via an underground pipe (sitecode 200-W-193-PL).

Waste Type: Process Effluent

Waste Description: The tank received radioactively contaminated liquid from U Plant. It is presently estimated to contain 104,100 liters (27,500 gallons) of sludge with an unknown plutonium content. Sample data collected in 1976 estimated the tank contained 760 curies of strontium-90, 1365 curies of cesium-137, 69,000 kilograms of uranium and less than one gram of plutonium.

Code: 200-W-1 **Classification:** Accepted

Names: 200-W-1; REDOX Mud Pit West **Reclassification** None

Type: Mud Pit **Start Date:**

Status: Inactive **End Date:**

Description: The site was originally described as a pit that is approximately 15.3 meters (50 feet) by 31 meters (100 feet). The surface of the area has the appearance of drilling mud, and has the typical surface that is left from evaporated or percolated liquid. Vegetation is absent from the area.

Two samples were collected in 1995. The results identified bentonitic clay and diatomaceous material.

The following observations were made during a field visit in August 1999. The site is in a shallow depression. It is difficult to discern the precise boundaries of the site because the general area appears to have been disturbed by heavy equipment. One section of the site is devoid of vegetation and appears to have some soil discoloration. West of this section is an area where the ground surface is broken up and sparsely vegetated. These two distinctive areas are surrounded by sparse to moderate vegetation cover, composed primarily of cheatgrass and tumbleweeds. An approximately 2.5 centimeter (1 inch) diameter rubber hose was seen near the west edge of the site and some lumber and a wooden stake were found at the unvegetated spot.

Location: The site is located west of REDOX, outside the REDOX exclusion fence. It is north of 10th Street.

Related Sites/ Structures: The site is associated with 200-W-17 and 200-W-18.

Waste Type: Chemicals

Waste Description: Site characterization is required for this site.

Code: 200-W-2 **Classification:** Accepted

Names: 200-W-2; REDOX Berms West **Reclassification** None

Type: Spoils Pile/Berm **Start Date:**

Status: Inactive **End Date:**

Description: The majority of the area is level, with evidence of soil disturbance over several acres. The site consists of two bermed areas. One berm is approximately 1.5 meters (5 feet) high by 9.2 meters (30 feet) wide. The other berm is approximately 3.1 meters (10 feet) high and 15.3 meters (50 feet) wide. The berms are not marked or posted.

Location: The site is located northwest of the 202-S Facility, outside the REDOX exclusion area fenceline.

Waste Type: Soil

Waste Description: The wastes at this unit are unknown. Characterization studies need to be performed.

Code: 200-W-6 **Classification:** Accepted

Names: 200-W-6; 200-W Painter Shop Paint Solvent Disposal Area **Reclassification** None

Type: Dumping Area**Start Date:****Status:** Inactive**End Date:****Description:** The site consists of contaminated soil. The soil was identified in 1993, while performing building modifications at the paint shop.**Location:** The site is located inside 200 West Area, north of 19th Street and east of Bridgeport Ave. It is within the construction forces shop complex at the 2318W Annex (previously referred to at 15019 shop building).**Release Description:** Soil within an excavation exhibited a strong solvent odor.**Process Description:** The construction forces shop complex has been situated at this location for many years.**Waste Type:** Chemicals**Waste Description:** Paint solvents were routinely disposed of to the soil in this area prior to 1984, according to conversations with "old timers".

Code: 200-W-9**Classification:** Accepted**Names:** 200-W-9; Project W291 Excavation VCP Contamination**Reclassification:** None**Type:** Unplanned Release**Start Date:** 1/1/1994**Status:** Inactive**End Date:****Description:** The site is currently a gravel area with two metal caissons. The area is not marked or posted. The tops of the caissons are labeled MH T-1 and MH T-2. While excavating for MH T-2 manhole for the new TEDF line from T-Plant to the 200 Area Treated Effluent Disposal Facility (project W291), contamination was discovered on an existing 25 cm (10 inch) vitrified clay pipe that was exposed during the excavation activity.**Location:** The site is located in 200 West Area, near the southeast corner of 221-T. It is 42 meters (138 ft) north of 23rd street.**Release Description:** An old vitrified clay pipe was uncovered while excavating for MH T-2 manhole for the new waste line from T-Plant to the 200 Area Treated Effluent Disposal Facility (project W291). The pipeline was left in the excavation.**Related Sites/ Structures:** The 25 centimeter (10 inch) vitrified clay pipe (see 200-W-163-PL) carried chemical sewer effluent from 291-T, 222-T and 224-T to the 216-T-3 crib.**Process Description:** The old vitrified clay pipe is assumed to be a chemical sewer line associated with 221-T and 222-T (see 200-W-163-PL).**Waste Type:** Soil**Waste Description:**

Code: 200-W-11**Classification:** Accepted**Names:** 200-W-11; Concrete Foundation South of 241-S; S-Farm Foundation and Dump Site**Reclassification:** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: A concrete foundation, small burn areas, bare areas and scattered debris are located south of 241-S Tank Farm.

Location: The site is north of 10th Street and west of Camden Ave., south of the 241-S Tank Farm.

Related Sites/ Structures: The site is possibly associated with the construction of the 241-SX, 241-SY, 241-S Tank Farms.

Waste Type: Misc. Trash and Debris

Waste Description: concrete foundation, small burn areas, bare areas, scattered debris including wire, weld rod, paint cans, oil cans, solvent cans, vehicle parts, cable, melted roofing material, glass, wood, pipe, rubber brick, metal, concrete, etc.

Code: 200-W-12 **Classification:** Accepted

Names: 200-W-12; 201-W Soil Mound and Plastic Pipe **Reclassification:** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The site consists of a soil mound with one 0.76-meter (2.5-foot) above-ground plastic pipe and one 20-centimeter (8-inch) above-ground plastic pipe topped with tees and elbows. There are also insulated electrical wires and an electrical heat controller.

Location: The site is located northwest of 201-W and approximately 75 meters (246 feet) north of 13th Street and west of Albany Avenue.

Related Sites/ Structures: The site may be associated with other adjacent test sites. See 200-W-35 and 200-W-10.

Process Description: During the 1970's, the Atlantic Richfield (ARCO) and Rockwell Research Departments used this area for testing equipment and processes to support the waste management operations. This area was selected for testing because it was adjacent to the REDOX facility (where the Research Department offices were located) and because the area did not contain any contaminated facilities or vadose contamination.

Waste Type: Equipment

Waste Description: The site consists of a soil mound (about 0.3-meter [1-foot] above grade) with one 0.76-meter (2.5-foot) above ground poly pipe and one 20-centimeter (8-inch) above ground poly pipe topped with tees and elbows. The site includes insulated wire and a heat controller. A below ground tank is suspected but unverified.

Code: 200-W-13 **Classification:** Accepted

Names: 200-W-13; 2713-WB Green Hut Complex; Regulated Vehicle Maintenance Shop Parking Areas **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is the areas of discolored soil (petroleum possibly) adjacent and near 2713-WB.

Miscellaneous regulated equipment has been stored outside and north of 2713-WB in the past. Trash and debris are scattered around 2713-WB including vitrified clay pipe, wood, metal, glass, cloth, plastic, rubber, brick, and aerosol cans. There is a coated (pink) steam line on south side of 2713-WB indicating asbestos.

Location: The site is located within the 200 West Area, north of 19th Street. 2713-WB is approximately 100 meters west of Bridgeport Ave.

Related Sites/ Structures: The site is related to the Minor Construction Area, Paint Shop, Shops, and the Power House.

Process Description: The site was used for regulated (i.e., containing radioactive material) vehicle maintenance and storage. In 1995, the north parking area and the area on the west side of the building were chained and posted with Contamination Area signs.

Waste Type: Soil

Waste Description: There are areas of discolored soil (presumed to be petroleum products) adjacent and near 2713-WB and areas with radiation protection postings. Regulated radioactive material and equipment have been stored outside and north of 2713-WB. The inside of the building was the Regulated Vehicle repair shop during the 1980's.

Code: 200-W-14 **Classification:** Accepted

Names: 200-W-14; 200 West Heavy Equipment Storage Area **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1995

Status: Inactive **End Date:**

Description: The site appears as a bare area. Several large, discolored areas were previously documented in this area. During August through October 2014, the adjacent buildings and structures, known as the Engineering Projects and Construction camp, were demolished to slab on grade. This activity also removed the oil stained soil. It was disposed in ERDF. No verification samples were collected.

Location: The site is located northwest of the intersection of Bridgeport Ave. and 19th Street, in 200 West Area. It is near the 2713 WB Maintenance Shop. It was also adjacent to several craft shop buildings.

Related Sites/ Structures: The site is associated with the building trades craft shops and support structures.

Process Description: The site was a heavy equipment (including cranes, forklifts, diesel generators, backhoes, vehicles) parking area with five or six large spots of petroleum contaminated soil. Contaminated soil was encountered down to a depth of 0.61 meters (2 feet) or more. During the 1995 site visit, the equipment continued to overflow and leak. No drip pans or containment were being used.

Waste Type: Oil

Waste Description: The soil at the site contains petroleum (oil, fuel, etc.) from leaky and overflowing (especially during hot weather) equipment (cranes, generators, front end loaders, forklifts, etc.).

Code: 200-W-15 **Classification:** Accepted

Names: 200-W-15; S Plant Project W-087 Hexone Discovery **Reclassification:** None

Type: Unplanned Release**Start Date:****Status:** Inactive**End Date:****Description:** The pipe trench where the hexone soil was found has been back filled to grade with soil originally removed from the excavation. Hexone contaminated soil was also put back into the excavation. There is currently no visual evidence of this excavation on the surface. The area is now under asphalt. It is not marked or posted.**Location:** The site is located approximately 18 meters (59 feet) southwest of the southwest corner of REDOX (202-S). It is above the 200-W-189-PL pipeline.**Release Description:** In June, 1995, while excavating pipe trench for Project W-087 (new transfer lines from 222-S to 244-S), a dark 4.6-centimeter (3-inch) thick layer of soil was noted at about 0.6-meter (2-foot) depth. It was determined to be hexone and surfactants (source: 8/4/1995 Email from L Marquardt - not available). The hexone soil was stockpiled and returned to the excavation after the pipe was installed in the trench.**Related Sites/ Structures:** The 202-S, 222-S, and 244-S are associated with the site.**Process Description:** Hexone was used in the adjacent facility 202-S REDOX.**Waste Type:** Chemical Release**Waste Description:** The waste consists of soil containing hexone and surfactants.

Code: 200-W-21**Classification:** Accepted**Names:** 200-W-21; 204-T Unloading Station; T-Plant Waste Railcar Unloading Facility; Unloading Station 1 and Unloading Station 2**Reclassification:** None**Type:** Pump Station**Start Date:** 1/1/1966**Status:** Inactive**End Date:** 1/1/1968**Description:** The unloading station consisted of two unloading platforms, Unloading Station 1 and Unloading Station 2. The platforms and piping from both stations were removed in 1996. The area has a short railroad siding extending from the main rail line into T-Plant. The concrete structure foundations remain and are posted with Underground Radioactive Material signs.**Location:** The 204-T Unloading Station platform structures were located west of 221-T at the north end of the 216-T-34 crib.**Related Sites/ Structures:** The site is associated with the 216-T-34 crib, 216-T-35 crib and the 340 facility in 300 Area. The pipeline from Unloading Station 1 to the 216-T-34 crib is sitecode 200-W-196-PL. The pipeline from Unloading Station 2 to the 216-T-35 crib is sitecode 200-W-197-PL.**Process Description:** The platform structures were used to unload 300 Area liquid laboratory waste sent in railroad tanker cars from the 340 Facility. The waste was pumped into the adjacent 216-T-34 and 216-T-35 Cribs.**Waste Type:** Equipment**Waste Description:** The platform structures and equipment supported the unloading of liquid waste from the 300 Area into the 216-T-34 and 216-T-35 cribs.

Code: 200-W-22	Classification: Accepted
Names: 200-W-22; 203-S/204-S/205-S Stabilized Area	Reclassification: None
Type: Unplanned Release	Start Date: 1/1/1952
Status: Inactive	End Date: 1/1/1983

Description: The site consists of multiple consolidated sites. All above ground surface features have been removed. The site is currently posted as an Underground Radioactive Material Area (URMA). There are also two small, posted URMA's located under the abandoned steam line, on the south end of this site.

Location: The site is located northwest of the 202-S Facility.

Related Sites/ Structures: The site is associated with the 203-S & 205-S UNH Processing Facilities, the REDOX UNH Unloading Facility and UPR-200-W-32, UPR-200-83, UPR-200-W-10, UPR-200-W-69, UPR-200-W-86, UPR-200-W-116 and UPR-200-W-123.

Process Description: The 203-S, and 205-S Facilities were constructed in the early 1950's to process and decontaminate the uranyl nitrate hexahydrate (UNH) produced by Reduction Oxidation (REDOX) operations. The primary process unit consisted of a column filled with silica gel that removed traces of fission products from the UNH. The silica gel column (SG-1) was located in the underground 205-S Vault. The vault also contained a waste neutralization tank. Operations in the vault were accomplished remotely. The 205-S Facility was a two story, aboveground, chemical make-up building. It contained two chemical make-up tanks, a UNH sample room and extensive piping connected to the REDOX facility and the underground vault. The 203-S Facility was an aboveground UNH storage facility that consisted of two 19,000 liter (5,000 gallon) stainless steel tanks that were set in an open concrete basin. There was also a 204-S Tank Farm, that consisted of four 190,000 liter (50,000 gallon) above-ground tanks set in two open concrete basins. A UNH Unloading Facility was located at the adjacent railroad siding. An above-ground UNH pipeline connected the 203-S, 204-S, 205-S Area to the 224-U Facility. During the REDOX Plant operation, the UNH solution was pumped from REDOX to the 205-S silica gel column for purification. The purified UNH was stored in the 203 and 204 tanks and the routed to 224-U, via an above ground line, for final processing. The fission products left in the silica gel column were stripped out with nitric acid. The acid was neutralized and send to cribs. UNH from the PUREX Plant were transported by truck to the unloading station and placed in the 204-S tanks. The PUREX solutions were then processed through the silica gel column. After REDOX shut down (1965), the 203-S and 205-S were placed on standby. The Unloading Station was converted to a railcar unloading station. The 204-S tanks continued to store material from the Unloading Station. Shipments included thorium nitrate from PUREX, 100-N Reactor decontamination solutions and 300 Area Laboratory wastes. The thorium nitrate was stored in tanks 204-S-1, 204-2 and 204-3. After an extended storage time, the thorium nitrate was shipped to Fernald, Ohio. The 203-1, 203-2 and 203-3 tanks were flushed. Tank 204-S-4 tank was used to hold the 100-N Reactor and 300 Area wastes. Tank 4 was connected to the 240-S-151 Diversion Box so that waste could be transferred to tank farms. Substantial dose rates were associated with these shipments. Several feet of sludge built up in the bottom of tank 4 and increased the dose rate problem. Increasing dose rate issues and contamination spreads lead to the construction of an enclosed unloading facility in 200 East Area (204-AR) that opened in 1981 and replaced this outdoor unloading station at REDOX.

Waste Type: Soil

Waste Description: Waste processed and stored in this area included contaminated UNH from REDOX and PUREX, Thorium Nitrate from PUREX, 100-N Reactor decontamination waste and 300 Area Laboratory waste. Radiological contaminants may be present in and around the remaining contaminated structures (cement basins and piping) that were not removed in the 1983 stabilization efforts.

Code: 200-W-42	Classification: Accepted
Names: 200-W-42; 200-W-42-PL; U Plant Radioactive Process Sewer from 221-U to 216-U-8 & 216-U-12 Cribs	Reclassification: None
Type: Radioactive Process Sewer	Start Date: 1/1/1952
Status: Inactive	End Date: 1/1/1988

Description: A large portion of this pipeline was removed in 2006. The portion removed was from the neutralization tank (southward) to the 216-U-8 crib. The excavation (approximately 15 feet deep) was left open when remediation activities ceased in 2006. The open trench is marked with steel posts along the entire length. The angle of the side slopes were greater than the requirements for safe entry. The steepness of the slope resulted in surveillance, tumbleweed removal and sampling activities being conducted remotely from the top of the trench. Blown in tumbleweeds and live, growing contaminated tumbleweeds in the open trench caused the area to be posted as a Contamination Area. In 2010, six to 36 inches of clean backfill material was added to the open excavation on the south side of 16th Street. The area was downposted to Underground Radioactive material Area. In 2012 six to 36 inches of clean backfill was added to the open excavation on the north side of 16th Street. This activity achieved a safe side slope and covered residual radiological contamination. The Contamination Area on the north side of 16th Street was downposted to an Underground Radioactive Material Area in July 2012. A portion of the pipeline from 221-U to the neutralization Pit still remains. The portion of the pipeline from 216-U-8 to 216-U-12 crib is also still intact.

Location: The waste site is an underground pipeline that extends from the 221-U Building to the 216-U-8 and 216-U-12 Cribs. It is located west of Beloit Avenue. A portion of the pipeline is north of 16th Street, but the majority of it is located south of 16th Street.

Release Description: Over the years, growing contamination over the pipeline absorbed radioactive contamination. The posted contaminated area over the pipeline south of 16th Street was given the number UPR-200-W-163.

Related Sites/Structures: The pipeline is associated with 221-U Building, 224-U Facility, 270-W, 291-U Stack, 216-U-8 Crib and 216-U-12 Crib, UPR-200-W-163 and 200-W-151-PL.

Process Description: The underground vitrified clay pipeline transferred process condensate from the 221-U and 224-U Buildings and the 291-U Stack to the 216-U-8 and 216-U-12 Cribs. The waste was acidic. The pipeline was originally connected to the 216-U-8 Crib which became active in 1952. The 216-U-12 Crib was built in 1960 to replace the 216-U-8 Crib when it showed potential signs of cave-in. A WYE joint was made in the 216-U-8 Crib pipeline to reroute and extended the pipeline to the 216-U-12 Crib.

Waste Type: Process Effluent

Waste Description: From 1952 to 1960, the line transferred waste from 221-U, 224-U and 291-U to the 216-U-8 crib. The 216-U-12 crib replaced the 216-U-8 crib in 1960. The pipeline was extended further south to the 216-U-12 location. From April 1960 to May 1967, the pipeline received waste from the 291-U-1 Stack drainage, 241-WR Vault waste, and 224-U process condensate via C-5 Tank. Disposal of contaminated water from 241-WR Vault was accomplished in October 1965 and included 3.14 kilograms (6.9 pounds) of thorium. From May 1967 to September 1972, the site received the above wastes excluding the 241-WR Vault waste and occasional waste via the C-7 Tank in the 244-U Building. From September 1972 to November 1981, the site was taken out of service. After November 1981, the pipeline received process condensate (corrosive: typical pH range is 0.5-1.5) from the 224-U Building. In the past, this facility also received miscellaneous storm drain wastes from 224-U. A Limited Field Investigation was done in 1994 to characterize selected waste sites in the 200-UP-2 Operable Unit. Fourteen surface and

subsurface soil samples along with four vegetation samples were collected to characterize the vitrified clay pipeline (VCP) leading to the 216-U-8 Crib. An attempt was made to determine if the contamination had spread laterally from the pipeline by digging holes with an auger rig where subsurface contamination had been identified. An increase in activity was noted at approximately 3 meters (10 feet). At a depth of 3.3 meters (11 feet) the auger was stopped by large cobbles. The samples were analyzed for cesium-137, strontium-90, gross alpha and gross beta. Specific sample data is documented in BHI-00033.

Code: 200-W-51	Classification: Accepted
Names: 200-W-51; Septic Tank (Abandoned)	Reclassification: None
Type: Septic Tank	Start Date:
Status: Inactive	End Date: 1/1/1994

Description: The site is an abandoned septic tank that has been filled and covered. The septic tank was discovered during excavations (for exhauster upgrades) outside 241-SY Tank Farm. The tank walls were collapsed to the greatest extent practicable to increase the over-burden of soil. The site was backfilled and compacted with clean fill dirt. The tank is marked with a WIDS sitecode sign.

Location: The site is located north (and slightly east) of the 241-SY-101 tank, north of the 241-SY Tank Farm fence.

Waste Type: Sanitary Sewage

Waste Description: The waste is the heel remaining in an abandoned septic tank.

Code: 200-W-53	Classification: Accepted
Names: 200-W-53; Contaminated Soil East of 207-T Retention Basin	Reclassification: None
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: This site was an area of surface soil contamination located east of the 207-T Retention Basins. It was identified in 1994, resulting in approximately 155,706 square feet of land being marked and posted as a Soil Contamination Area (SCA). The contaminated soil was scraped and placed inside the 207-T Retention Basin. The scraped area is currently posted as an Underground Radioactive Material Area (URM). A site visit in 2014 found the posting had not changed.

Location: The site is a large area of posted Underground Radioactive Material, located east of the 207-T Retention Basin. The source of the contamination was assumed to be the 241-T Tank Farm and the 207-T Retention Basin. A small Underground Radioactive Material area surrounding well 299-W11-28, on the west side of the retention basin, is considered to be part of 200-W-53 also.

Release Description: Specks of contamination spread from the operation of 241-T Tank Farm on the wind.

Related Sites/ Structures: The site is associated with the 207-T basin.

Waste Type: Soil

Waste Description: Contaminated soil specks were identified.

Code: 200-W-54	Classification: Accepted
Names: 200-W-54; Contamination Migration from 241-SX Tank Farm	Reclassification: None
Type: Contamination Migration	Start Date:
Status: Inactive	End Date:

Description: This site is an expanding area of contamination migration. A major radiological zone reduction activity was done in October 2011. Three and one half acres were covered with gravel and downposted to Underground Radioactive Material Area. The original unplanned release was defined in 1997. It was a large, irregular shaped Soil Contamination Area (SCA) located on the east side of 241-S/SX Tank Farms. In 1997, it measured approximately 175 meters (575 feet) by 100 meters (330 feet). Another Global Positioning Survey was done in 1998. The posted Soil Contamination Area had been extended approximately 50 meters (165 feet) to the west (up to the tank farm fence) and approximately 200 meters (660 feet) in the north-south direction. A site visit in August 2000 found multiple additional radiologically chained and posted areas in this vicinity. There is also one separately posted Contamination Area located north of 241-SY Tank Farm, across a gravel road. In 2009, contaminated rabbit feces were found outside the posted areas. Some areas of rabbit feces and specks were delineated and posted as a Contamination Area. The posted area size and shape varies with additional radiological surveys.

Location: The site is located east and north of the 241-S, SX, SY Tank Farm fence. It extends eastward to the west edge of the 216-S-9 Crib. The posted area size and shape varies often, with additional radiological surveys.

Related Sites/ Structures: The site is associated with activity in the 241-S, SX and SY Tank Farms.

Waste Type: Soil

Waste Description: The posted soil contamination areas are the result of contamination migration out of the tank farms.

Code: 200-W-63	Classification: Accepted
Names: 200-W-63; Contaminated Concrete Pad	Reclassification: None
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The site was a "T" shaped concrete pad that had been posted with Surface Contamination Area signs. A site visit in September 1999 found the pad had been covered with gravel and reposed as Underground Radioactive Material.

Location: The pad is located approximately 180 meters (591 feet) northwest of 241-TY Tank Farm and 80 meters (262 feet) south of 23rd Street in 200 West Area.

Process Description: Employees who have worked in 200 West Area state the pad was used to store radiologically contaminated tanks in the late 1980's. The tanks were removed in 1991 and the pad was left posted as a Surface Contamination Area.

Waste Type: Equipment

**Waste
Description:**

Code: 200-W-67	Classification: Accepted
Names: 200-W-67; Contaminated Soil at the Corner of Cooper and 16th Street	Reclassification: None
Type: Unplanned Release	Start Date: 1/1/1998
Status: Inactive	End Date:

Description: The site is currently posted as an Underground Radioactive Material area.

Location: The site is located inside 200 West Area, east of the 16th Street and Cooper Ave. intersection. It is adjacent to the 216-U-3 Crib.

Release Description: A radiological survey done by the 200 West Tank Farm Radiological Protection group in April 1998 identified contamination specks and a contaminated ant hill near the intersection of 16th Street and Cooper Ave. The maximum reading on the specks was 11 mr/hr. Another speck was found that read 6 mr/hr. Other contamination levels ranged from 500 counts per minute to 70,000 counts per minute. The ant hill read 3000 counts per minute. Some of the contamination was removed as it was found. The rest of the area was posted as a Contamination Area (CA) in April 1998. The source of the contamination has not been determined.

Waste Type: Soil

**Waste
Description:**

Code: 200-W-71	Classification: Accepted
Names: 200-W-71; Undocumented Burn Pit; Undocumented Trench	Reclassification: None
Type: Trench	Start Date:
Status: Inactive	End Date:

Description: The open trench was visible on a 1948 aerial photograph of 200 West Area. The trench is also visible on photograph number 3757, taken in May 1956. Smoke is emitting from the trench, indicating it was used as a burn pit. The trench has been backfilled. The area where the trench had been located is not marked or posted. The area seems somewhat disturbed and is covered with cheatgrass and some rabbitbrush.

Location: The open trench was located southeast of the 221-U facility. It was south of 16th Street and east of Beloit Avenue.

Related Sites/ Structures: The site is associated with the Construction Surface Laydown Area (sitecode 200-W CSLA).

Process Description: It is not known exactly what the trench was used for. Hanford drawing H-2-1495 shows the trench and labeled it "Maintenance Disposal Ground". The 1948 aerial photograph shows an open trench and a spoil pile. Historical photographs from 1950 and 1956 show smoke emitting from the trench, indicating it was used as a burn pit. There are no designated burial grounds at this location. Later, the same area was used as a construction lay down area for the reconfiguration of U Plant for the uranium recovery process. When choosing the site for the 216-U-17 Crib, a meeting was held on July 2, 1987 with several knowledgeable long time employees. The subject of the existence of an old burial ground located adjacent to the 216-U-

17 Crib site was discussed. The obvious surface debris was attributed to the surface lay down area that supported the U Plant re-construction activities. There was a general recollection among the older employees that natural uranium was once sent to a trench in this area. However, no radioactivity was ever detected during various core sampling done in the area over the years.

Waste Type: Misc. Trash and Debris

Waste Description: Drawing H-2-1495 labels the trench as the Maintenance Disposal Ground. Historical photographs show smoke emitting from the trench, indicating it was used as a burn pit.

Code: 200-W-75 **Classification:** Accepted

Names: 200-W-75; Radiological Logging System (RLS) Calibration Silos **Reclassification:** None

Type: Experiment/Test Site **Start Date:** 1/1/1978

Status: Inactive **End Date:**

Description: The site consists of four underground Radiological Logging System (RLS) equipment calibration silos. The silos are galvanized steel containers with metal lids bolted on top. The silos have somewhat different design constructions, for calibrating different types of equipment. One type consisted of a 25 centimeter (6 inch) capped well casing is inserted through the centers of the silos. There are two risers with bolted lids adjacent to the well casing. The silos are posted with Underground Radioactive Material signs.

Location: Three calibration silos are located west of the 202-S building, south of the 276-S building and north of the 211-S tanks. One calibration silo is located west of the 211-S tanks, across an asphalt access road.

Process Description: In the late 1970's, test well mockups were used to calibrate in-well radionuclide detectors. The calibration mockups were constructed of a steel container approximately 2.4 meters (8 feet) deep filled with soil. Tubes containing radioactive sources were inserted into the soil at distances of 2.5, 7.6, 15, 30, 46 and 61 centimeters from the well casing that was located in the center of the mockup. The mockup silo was buried so that a Radiological Logging System vehicle could drive up to the calibration silo and drop its logging probe into the center well casing.

Waste Type: Equipment

Waste Description: The calibration silos contained radioactive sources consisting of known quantities of cobalt-60, strontium-90, ruthenium-106 and cerium-144 in sealed capsules. Since the silo covers are posted with Underground Radioactive Material signs, it is assumed the sources are still inside the silos.

Code: 200-W-77 **Classification:** Accepted

Names: 200-W-77; Posted Contamination Area East of 216-U-14 Ditch **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The site was a small area marked with posts and chain, posted with Contamination Area signs. After being backfilled with gravel, the area was downposted to Underground Radioactive Material.

Location: The site is located adjacent to the railroad track, west of 216-U-16 Crib and east of the stabilized 216-U-14 Ditch.

Waste Type: Vegetation

Waste Description:

Code: 200-W-80 **Classification:** Accepted

Names: 200-W-80; Mound of Contaminated Soil Southwest of T Plant; Stabilized Contaminated Soil Area Southwest of T Plant **Reclassification:** None

Type: Spoils Pile/Berm **Start Date:**

Status: Inactive **End Date:**

Description: The site is a gravel area surrounded with post and chain and Underground Radioactive Material Area signs. The site had been a mound of soil surrounded with radiation rope and posted with Contamination Area signs. The mound was approximately 1.5 meters (5 feet) high, 8.2 meters (27 feet) long, and 3 meters (10 feet) wide. The mound of soil and the surrounding area contained many pieces of asphalt, similar to that in the adjacent parking lot of T Plant. The mound and surrounding area is covered by a thin growth of cheatgrass and tumbleweeds. About 3 meters (10 feet) east of the site is a small posted URM, with one capped well inside the posted area and one just outside. The capped well outside is locked and has a warning of potential contamination. Across the northern part of the contamination area are fence posts marking an underground pipeline, traveling east-west, posted as a URM. Another posted underground pipeline goes under the mound of soil, in a north-south direction, and is also posted as a URM.

Location: The site is located west of 221-T and northeast of the 241-T-361 settling tank. It is about 15 meters (50 feet) west of the steam pipeline.

Waste Type: Soil

Waste Description: The site consists of a mound of soil surrounded with radiation rope and Contamination Area signs. A survey of the mound surface did not detect any contamination. It is not known if there is contamination inside the mound.

Code: 200-W-81 **Classification:** Accepted

Names: 200-W-81; Contaminated Tumbleweed Fragments Along Railroad Track East of 218-W-3AE **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The site was three posted Contamination Areas on the railroad track east of the burial ground, south of the 610 Gate of the 200 West Area fence. In 2009, each Contamination Area was radiologically surveyed and downposted to Soil Contamination Areas. Later, six inches of clean gravel was placed on the areas and the postings were changed Underground Radioactive Material Areas.

Location: The sites are located east of the 218-W-3AE Burial Ground along the railroad track, south of 12th Street.

Waste Type: Soil

**Waste
Description:**

Code: 200-W-82 **Classification:** Accepted

Names: 200-W-82; Crib Unloading Station; Risers East of 216-TY-201 and 216-T-26, 216-T-27 and 216-T-28 Cribs; Truck Unloading Station **Reclassification** None

Type: Product Piping **Start Date:** 1/1/1960

Status: Inactive **End Date:** 1/1/1966

Description: The site consists of two concrete pads with flanged risers, surrounded by Contamination Area postings.

Location: The site is located east of Camden Avenue, east of the 216-TY-201 Flush Tank and 216-T-26, 216-T-27, and 216-T-28 Cribs.

**Related Sites/
Structures:** The site is associated with the 216-T-27 and 216-T-28 Cribs. The pipeline associated with the unloading station is described in 200-W-188-PL.

**Process
Description:** Based on the available information, it is believed that this site is a liquid waste truck unloading station. It is assumed that the short pipeline, shown on drawing H-2-2733, extended eastward to the risers. The unloading station was built to accommodate tanker trucks unloading 300 Area liquid wastes into the 216-T-27 and 216-T-28 cribs. The unloading station jetted waste from the trucks to the cribs and was capable of unloading two trucks at a time.

Waste Type: Equipment

**Waste
Description:** The 216-T-27 and 216-T-28 received liquid waste from the 300 Area via trucks. The waste at the unloading station is the underground transfer piping, risers and pads and adjacent soil contaminated from leaks.

Code: 200-W-83 **Classification:** Accepted

Names: 200-W-83; Contamination Area North of 2727W **Reclassification** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The site had been a posted Contamination Area extending across the railroad track north of the 2727-W Sodium Storage building. In April 2007, the contamination was backfilled with clean dirt and the area posting was changed to Underground Radioactive Material. The railroad tracks are no longer used.

Location: The site is located on the railroad tracks, north of the 2727-W building.

**Related Sites/
Structures:** The 2727-W Building, about 100 meters (100 yards) of this site, is posted with "Danger" signs for the sodium stored inside. It, and three nearby mobile trailers, are posted as Radiological Materials Areas.

**Process
Description:** No source of the contamination at this site is obvious from field conditions.

Waste Type: Soil

**Waste
Description:**

Code: 200-W-85	Classification: Accepted
Names: 200-W-85; Soil Contamination Area East of 2727 W	Reclassification: None
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The site was originally a posted Soil Contamination Area. The posting surrounded some growing rabbit brush and grass. No soil discoloration or disturbance was apparent. In December 2001, the area was covered with clean backfill material and downposted to an Underground Radioactive Material Area.

Location: The site is located approximately 30 meters (100 feet) east of the fenced 2727-WA equipment storage yard.

Process Description: It is not known what caused the contamination at this location. No radiological survey could be found to determine when the area was posted or the radiological conditions inside the posted area.

Waste Type: Soil

**Waste
Description:**

Code: 200-W-86	Classification: Accepted
Names: 200-W-86; Contamination Area Around Light Pole	Reclassification: None
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The site was originally a small, graveled Soil Contamination Area around an active (in use) pole with a street light attached, near the intersection of the U plant railroad spur and Bridgeport Avenue. In December 2001, the utility pole was removed and the area was covered with clean backfill. The area was downposted to Underground Radioactive Material.

Location: The site is located northwest of 221-U, on a gravel road known as Bridgeport Avenue.

**Related Sites/
Structures:** The light pole is related to the electrical utility facilities.

Waste Type: Equipment

Waste Description: The history (source and amount of contamination) of the site is unknown, but the power pole is surrounded by a small Soil Contamination Area.

Code: 200-W-87	Classification: Accepted
Names: 200-W-87; Unplanned Release on Chemical Spur Railroad Track Northwest of 221-U Plant	Reclassification: None
Type: Unplanned Release	Start Date:

Status: Inactive**End Date:****Description:** The site was originally a posted Contamination Area on a portion of the railroad spur. The spur is no longer active. In December 2001, the area was covered with clean backfill material and downposted to an Underground Radioactive Material Area.**Location:** The site is located approximately 61 meters (200 feet) northwest of the 2714-U building and T-Hopper yard on the U Plant chemical spur railroad track.**Related Sites/ Structures:** UPR-200-W-118 is another unplanned release located on the same railroad spur, but closer to the 221-U building. This unplanned release was associated with material being transported to the 211-U Tank Farm area. The 211-U Chemical Unloading Station was removed and the area stabilized with gravel in 1998. The graveled area is posted with Underground Material Area signs. The demolished 2714-U was in this area.**Process Description:** The chemical spur railroad track was used to transport chemicals to and from the 211-U Tank Farm and also to transport "T-Hopper" containers. The T-Hoppers contained calcined, uranium powder that had been processed in the 224-U Uranium Trioxide (UO₃) plant. They were stored in a fenced area west of the 2714-U Building. However, the posting on this spur is the result of rail cars and engine parked here (see Site Comment).**Waste Type:** Soil**Waste Description:****Code:** 200-W-89**Classification:** Accepted**Names:** 200-W-89; 252-U; C8S17 Substation; U Plant Electrical Substation; U-Cat Substation**Reclassification:** None**Type:** Foundation**Start Date:****Status:** Inactive**End Date:****Description:** The site was a gravel Underground Radioactive Material (URM) area, located where the 252-U Electrical Substation had been located. The site is now located within the boundaries of the larger Underground Radioactive Material Area, known as 200-W-136. The 200-W-136 WIDS site includes the back side of 221-U and also the demolished 224-U, 224-UA, 203U, 203UX and the 272-U Hot Shop footprints.**Location:** The site is located near the intersection of Beloit and 16th Street in 200 West Area, east of the (demolished) 224-U building.**Related Sites/ Structures:** The site is associated with 221-U and 224-U and 200-W-136.**Process Description:** The 252-U Substation provided electric utility support to the 221-U and 224-U facilities.**Waste Type:** Soil**Waste Description:** The waste in this area is residual radioactive contamination in soil. After the electrical substation was decommissioned, a posted Underground Radioactive Material area remains. Laboratory analysis of metal, ceramic pieces and asbestos fibers (August 1998) identified cesium 134 and cesium 137. Some barium, cadmium, chrome and lead was also noted. No PCB's were identified. The radioactive contamination is assumed to have been deposited on the substation from U Plant and 224-U stack emissions.

Code: 200-W-90 **Classification:** Accepted
Names: 200-W-90; Underground Radioactive Material **Reclassification:** None
Areas Posted Along 23rd Street in 200 West Area
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The site is comprised of three posted Underground Radioactive Material areas. Two are located on the south side of 23rd Street, across from the 218-W-2A Burial Ground. One is located further east, on the south side of 23rd Street, across from the 241-T Tank Farm.

Location: The posted areas are located along the south shoulder of 23rd Street, in 200 West Area, between Camden and Dayton Avenues.

Related Sites/ Structures: It is possible the areas are related to UPR-200-W-63.

Waste Type: Soil

Waste Description:

Code: 200-W-92 **Classification:** Accepted
Names: 200-W-92; Contaminated Mound of Soil and **Reclassification:** None
Debris; Soil Mound West of 241-TY Tank Farm
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is a mound of soil is approximately 1.5 meters (5 feet) high. It had been surrounded with chain and posted with Contamination Area signs. Several radiation flags were placed in the mound to identify significant contamination. Rocks, asphalt and chunks of cement were visible. Some vegetation, including rabbitbrush, had been growing on the mound. In April 2007, clean gravel was placed on top of the contamination and the site was down posted to Underground Radioactive Material.

Location: The mound is located west of an unnamed gravel road, west of the 241-TY Tank Farm.

Waste Type: Misc. Trash and Debris

Waste Description: Maximum contamination levels of 1,600,000 disintegrations per minute per 100 square centimeters of beta gamma and 14,000 disintegrations per minute per 100 square centimeters of alpha were found on the soil and debris.

Code: 200-W-106 **Classification:** Accepted
Names: 200-W-106; Soil Contamination Area Adjacent **Reclassification:** None
to 200-W-55 Dump Site
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: Soil contamination was found and posted on February 13, 2003. In March 2010, the area was surface stabilized and downposted to Underground Radioactive Material.

Location: The site is located west of the 241-TX Tank Farm, west of the 216-T-25 Trench and northeast of the 200-W-55 debris dump site.

Code: 200-W-127 **Classification:** Accepted

Names: 200-W-127; Surface Stabilized Area East of UPR-200-W-29/UPR-200-W-97 (UN-216-W-5) **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The site is a posted Underground Radioactive Material area that has been covered with gravel.

Location: The site is located on the south side of 23rd Street in 200 West Area. It is west of T Plant and east of UPR-200-W-29/UPR-200-W-97, a posted Underground Radioactive Material area on the corner of 23rd St. and Camden Ave.

Related Sites/ Structures: Encased pipeline 200-W-129-PL crosses this radiologically posted area.

Code: 200-W-128 **Classification:** Accepted

Names: 200-W-128; Underground Radioactive Material Area East of 218-W-4A **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The site is posted with Underground Radioactive Material signs. A considerable amount of sand appears to have blown onto the posted area.

Location: The site is located approximately 100 feet south of 23rd Street, inside 200 West Area. It is adjacent to the 218-W-4A fence.

Related Sites/ Structures: The area is associated with the 218-W-4A burial ground.

Code: 200-W-231 **Classification:** Accepted

Names: 200-W-231; Temporary Facilities Construction Trailer Septic Tank and Tile Field **Reclassification:** None

Type: Septic Tank **Start Date:** 1/1/1951

Status: Inactive **End Date:**

Description: The septic and tile field are not visible. They are not marked or posted. They were noticed on Hanford Site drawing H-2-2289. Exact coordinates are not available.

Location: The septic tank and tile field are located west of Camden Ave. and south of 23rd St. They are approximately 16.7 meters (55 feet) south of the 200-W-79-PL pipeline, the pipeline that feed the 216-T-36 crib.

Process Description: During the 1950's, many Temporary Construction buildings were set up to support construction activities. H-2-2289 was drawn in February 1951. It shows a septic tank and tile field that supported a Temporary Construction office and an X-ray laboratory. The Temporary

construction facilities were supporting the construction of 241-TY Tank Farm.

Waste Type: Sanitary Sewage

Waste Description: H-2-2289 was drawn in February 1951. It shows a septic tank and tile field that supported a Temporary Construction office and an X-ray laboratory. It is possible that x-ray development solutions were discharged to the septic system.

Code: 200-W-244-PL **Classification:** Accepted

Names: 200-W-244-PL; Encased Pipelines from 221-U Canyon Building to 241-WR Vault; Lines 4705, 4707, 4709, 4711, 4861, 4871 **Reclassification:** None

Type: Encased Transfer Piping **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is a grouping of six pipelines in a concrete encasement. Four lines connect to Section 3 of the 221-U canyon. Two lines connect to Section 4 of the 221-U canyon. All six lines also connect to the 241-WR Vault.

Location: The encased pipeline is located on the east side of the 221-U facility, west of Beloit Ave.

Process Description: The 241-WR Vault received uranium and thorium slurry solutions (via underground encased pipelines) from the single shell tanks and prepared the waste to be fed into 221-U facility to extract the uranium and thorium. The 241-WR vault added chemicals and adjusted the pH before it was transferred to the 221-U canyon to be processed through the tributyl phosphate extraction columns. The 241-WR vault (tank 241-WR-001) also received neutralized waste from the 221-U extraction process (via underground encased pipelines) and stored it until it was transferred back to the tank farms via the 241-UX-154 Diversion Box.

Code: 200-W-248-PL **Classification:** Accepted

Names: 200-W-248-PL; Direct Buried lines from 241-UX-154 to 200-W-244-PL and 241-WR Vault; Line Numbers 4866, 4976 and 4977 **Reclassification:** None

Type: Direct Buried Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is three underground, stainless steel pipeline buried in the same soil trench. Three stainless steel pipelines (lines 4866, 4976 and 4977) exit the north side of the 241-UX-154 Diversion Box. The three lines extend northward, buried in a single soil trench. They connect into the 200-W-244-PL concrete encasement near the south wall of the 241-WR vault.

Location: The three direct buried pipelines are located on the east side of the 221-U building.

Code: 218-W-8 **Classification:** Accepted

Names: 218-W-8; 222-T Vault **Reclassification:** None

Type: Burial Vault **Start Date:** 1/1/1945

Status: Inactive **End Date:** 1/1/1952

Description: Three underground vaults are contained in this site. The two original vaults are 3 by 3 by 3.7

meters (10 by 10 by 12 feet) deep, made of 5.1 by 30.5-centimeter (2 by 12-inch) wooden planking, with the tops 1.5 meters (5 feet) below grade. The third replacement vault is a concrete culvert pipe encasement 2.4 meters (8 feet) in diameter and 7.6 meters (25 feet) long and 1 meter (3.2 feet) below grade. The top of the encasement is a 23-centimeter (9-inch) precast concrete cover and the bottom is a 30.5-centimeter (12-inch) thick concrete floor. The disposal chutes for the wooden vault were removed.

Location: The unit is located southeast of the 222-T Building.

Waste Type: Misc. Trash and Debris

Waste Description: This site contains laboratory process sample waste from the 222-T Building.

Code: 218-W-9 **Classification:** Accepted

Names: 218-W-9; Dry Waste Burial Ground No. 9; Non-TRU Dry Waste No. 009 **Reclassification:** None

Type: Burial Ground **Start Date:** 1/1/1954

Status: Inactive **End Date:** 1/1/1954

Description: The burial area is 42.7 meters (140 feet) by 29.8 meters (98 feet). The location is designated by four corner posts and chain. No data is available regarding depth, slope, or actual area used inside the posted area.

Location: The site is located northwest of the 202-S Building and north of 216-S-7 Crib.

Release Description: UPR-200-W-109 states that after repairing the buckled portions of the waste line near the 216-S-9 crib, a pressure test indicated another leak in the line. Additional hydrostatic testing finally forced the water to bubble to the surface. It surfaced inside the radiation zone marking the 218-W-9 burial trench. Dose rates of the liquid were 450 mR/hr, but as the water sank back into the soil, the dose rate dropped to 20 mR/hr. Excavation of the liquid bubble site disclosed a vertical buckle in the pipeline with a sizable break in the line at that point. The event occurred in 1969. (RHO-CD-673)

Related Sites/Structures: The waste site is associated with pipeline 200-W-139-PL. The pipeline runs beneath the eastern edge of the 218-W-9 posted area. The Unplanned Release UPR-200-W-109 documents a break in the (200-W-139-PL) pipeline occurred inside the posted area of the 218-W-9 waste site.

Waste Type: Misc. Trash and Debris

Waste Description: The unit contains an unknown amount of sheet metal scrap, including the 211-S Tank taken from the REDOX Facility. The waste contains less than 0.1 curie total beta activity. ARH-2015 part 4 says the REDOX scrap metal was contaminated with ruthenium-106.

Code: 231-W-151 **Classification:** Accepted

Names: 231-W-151; 231-W-151 Sump; 231-W-151 Vault; 231-W-151-001 (Tank); 231-W-151-002 (Tank); 231-Z-151 Sump **Reclassification:** None

Type: Receiving Vault **Start Date:** 1/1/1948

Status: Inactive **End Date:** 1/1/1974

Description: The unit is a concrete vault partially underground with 3 steel risers and one vent structure

protruding from holes in the top. The vault contains two tanks (see subsites). It is posted with Contamination Area/Radiation Area signs and Restricted Access Unsafe Structure, Confined Space and IMUST signs.

- Location:** The site is located approximately 36.6 meters (120 feet) east of 231-Z building.
- Release Description:** In September 2002, alpha contamination was discovered on the concrete surface, around the riser. Maximum contamination levels were 210,000 disintegrations per minute (direct) and 420 disintegrations per minute removable.
- Related Sites/Structures:** The site is related to 231-Z building, 216-Z-5, 216-Z-6, 216-Z-7, 216-Z-10 and UPR-200-W-130. The pipelines from 231-Z to this vault are sitecode 200-W-199-PL. The pipeline from the vault to 216-Z-5 is sitecode 200-W-202-PL. The pipeline from the vault to 216-Z-7 is sitecode 200-W-203-PL. The pipeline from the vault to 216-Z-10 is 200-W-204-PL.
- Process Description:** The 231-W-151 vault tanks were installed to receive drainage from about 75 floor drains in Building 231-Z. Solids in the floor drainage would settle out leaving sludge and sediment in the bottom of the tanks. Waste was diverted to the 216-Z-5, 216-Z-6, 216-Z-7 cribs and the 216-Z-10 Reverse Well through this vault. The tanks were used for neutralizing 231-Z Building wastes prior to disposal to a crib. Since 231-Z was used to finish plutonium, any wastes or chemicals generated or used in the process may have conceivably been introduced to the 231-W-151 vault tanks.
- Waste Type:** Process Effluent
- Waste Description:** The unit consists of a vault containing the two tanks, 231-W-151-001 and 231-W-151-002, installed to receive drainage from 75 floor drains in Building 231-Z. Floor drainage solids settled, leaving sludge and sediment in the tanks. Plutonium finishing wastes or chemicals from building 231-Z may have been introduced to the two tanks. A water sample taken from 231-W-151-001 May 9, 1974 showed Cs137, Sr89, Sr90, and Uranium. 231-W-151-001 was reported to contain only ~0.001 grams of plutonium then, and little or no ferrocyanides. A water sample taken from 231-W-151-002 May 9, 1974 showed cesium-137, strontium-89/strontium-90, uranium, plutonium-238, plutonium-239, plutonium-240, and americium-241. In summary, these results indicate a content of 228 grams of plutonium in the sludge in 231-W-151-002, and less than 0.001 grams in the supernatant.

This Site has the Following SubSites:

- Code:** 231-W-151:1
Names: 231-W-151:1; 231-W-151-001; Overflow Tank
- Code:** 231-W-151:2
Names: 231-W-151:2; 231-W-151-002

-
- | | |
|---|---------------------------------|
| Code: 231-W-151:1 | Classification: Accepted |
| Names: 231-W-151:1; 231-W-151-001; Overflow Tank | Reclassification: None |
| Type: Receiving Vault | Start Date: |
| Status: Inactive | End Date: |

- Description:** Tank 231-W-151-001 is located within the 231-W-151 Vault. It is a 15,140 liter (4000 gallon) stainless steel tank that received drainage from the 231-Z building floor drains. The drainage was routed to 231-W-151-002, which when filled, overflowed into 231-W-151-001 (second in the process). The solids would settle out into the tanks and the supernate was discharged to the 216-Z-7 crib. Tank operations began in 1948 and were discontinued in 1974. The inlet lines to the tank have been blanked off. In 1974, a sample was taken that indicated 231-W-151-001 contained only 0.001 grams of plutonium. The tank contents were reported to be 5,413 liters (1430 gallons) of supernate and no sludge.

Process Description: The 231-W-151 vault tanks were installed to receive drainage from about 75 floor drains in Building 231-Z. Solids in the floor drainage would settle out leaving sludge and sediment in the bottom of the tanks. Waste was diverted to the 216-Z-5, 216-Z-6, 216-Z-7 cribs and the 216-Z-10 Reverse Well through this vault. The tanks were used for neutralizing 231-Z Building wastes prior to disposal to a crib. Since 231-Z was used to finish plutonium, any wastes or chemicals generated or used in the process may have conceivably been introduced to the 231-W-151 vault tanks.

The SubSite is Part Of:

Code: 231-W-151

Names: 231-W-151; 231-W-151 Sump; 231-W-151 Vault; 231-W-151-001 (Tank); 231-W-151-002 (Tank); 231-Z-151 Sump

Code: 231-W-151:2

Classification: Accepted

Names: 231-W-151:2; 231-W-151-002

Reclassification: None

Type: Receiving Vault

Start Date:

Status: Inactive

End Date:

Description: Tank 231-W-151-002 is located within the 231-W-151 Vault. It is a 3,596 liter (950 gallon) stainless steel tank that received drainage from the 231-Z building floor drains. It is the first tank in a series of two tanks. The solids would settle out into the tanks and the supernate was discharged to the 216-Z-7 crib. Tank operations began in 1948 and were discontinued in 1974. The inlet lines to the tank have been blanked off. In 1974, a sample was taken that indicated 231-W-151-002 contained 228 grams of plutonium in the sludge and less than 0.001 grams of plutonium in the supernate. The tank contents were reported to be 3,615 liters (955 gallons) of supernate and 45 liters (12 gallons) of sludge.

Process Description: The 231-W-151 vault tanks were installed to receive drainage from about 75 floor drains in Building 231-Z. Solids in the floor drainage would settle out leaving sludge and sediment in the bottom of the tanks. Waste was diverted to the 216-Z-5, 216-Z-6, 216-Z-7 cribs and the 216-Z-10 Reverse Well through this vault.

The SubSite is Part Of:

Code: 231-W-151

Names: 231-W-151; 231-W-151 Sump; 231-W-151 Vault; 231-W-151-001 (Tank); 231-W-151-002 (Tank); 231-Z-151 Sump

Code: 270-W

Classification: Accepted

Names: 270-W; 270-W Neutralization Tank; 270-W Tank

Reclassification: None

Type: Neutralization Tank

Start Date: 1/1/1952

Status: Inactive

End Date: 1/1/1960

Description: There is no visual evidence for this tank. The tank was located beneath the cement foundation of the 2715-UA building. The 2715-UA building was removed in August 2005, leaving the foundation slab in place. After the demolition, the 270-W tank risers were protected with a cement block. A review of drawings indicated the 2715 UA building was placed over the 270-W tank. The 270-W consists of an underground, stainless steel tank that is 2.7 meters (9 feet) tall and 2.7 meters (9 feet) in diameter. The nominal capacity of the tank is 14,300 liters (3780 gallons). The area was covered with gravel.

Location: The unit is located under the northeast end of 2715-UA building, inside the 224-U facility fence.

Related Sites/ Structures: The tank is associated with the 224-U facility and pipeline sites 200-W-136, 200-W-42-PL, and 200-W-151-PL.

Process Description: The tank was filled with limestone and used to neutralize acidic process condensate generated from the 224-U building. Following the pH adjustment, the waste was released to the 216-U-8 crib via a 15 centimeter (6 inch) VCP line. The 216-U-8 crib was taken out of service in 1960 and replaced with the 216-U-12 crib. A letter report, written in 1974, indicated that the 270-W tank was part of the waste line to the 216-U-12 crib. The report states that "the UO₃ plant is scheduled to restart in 1977. Since the integrity of the 270-W tank could not be assured, a bypass line should be installed around the tank before the plant begins to discharge waste". The letter also states that based on the last liquid to flow through the tank, the liquid composition in the tank may include 2.64 X 10⁻⁹ curies/gallon of beta emitters, 9.69 X 10⁻⁵ grams/gallon of uranium and 1 X10⁻⁹ grams/gallon of plutonium.

Waste Type: Process Effluent

Waste Description: The unit was filled with limestone and used to neutralize acidic 224-U process condensate from the UO₃ plant operation. Contributors to the process condensate included feed UNH concentrator offgas, calciner offgas, phosphoric acid, and potassium hydroxide. Analyses of process condensate samples have revealed trace amounts of hydrogen fluoride, mercury, acetone, 1-butanol, 2-butanone, and n-nitrosodimethylamine. Analysis of the last liquid to flow through the tank revealed beta emitters, uranium, and plutonium. (Harlow Internal Memo states : 2.64E-9 curies per gallon of beta emitters, 9.69E-5 grams per gallon of uranium and 1E-9 grams per gallon of plutonium [unit conversion equals 6.97E-10 curies per liter of beta emitters, 2.56E-5 grams per liter of uranium, and 2.64E-9 grams per liter of plutonium]).

Code: 2607-W3	Classification: Accepted
Names: 2607-W3	Reclassification: None
Type: Septic Tank	Start Date: 1/1/1944
Status: Inactive	End Date: 8/1/1998

Description: This system includes a drain field that was expanded in the 1950's. In August 1998, under project W-396, the 2607-W3 Septic Tank was pumped, sampled, filled with sand and abandoned in place per WAC codes. The 2607-W3 Septic Tank was constructed of reinforced concrete. At one time, the eastern access was posted with a Radioactive Material warning sign.

Location: This unit lies northeast of the 241-T-361 Settling Tank, approximately 61 meters (200 feet) north of 23rd Street and 244 meters (800 feet) southwest of the 221-T Building.

Related Sites/ Structures: The 2607-W3 Septic Tank as associated with the 221-T, the 222-T, the 224-T, and the 271-T Buildings.

Process Description: The 2607-W3 Septic Tank and associated drain field were designed to accept sanitary sewer effluent from the 221-T, the 222-T, the 224-T, and the 271-T Buildings. After being properly abandoned, the 2607-W3 effluent was redirected to the 2607-W1 system.

Waste Type: Sanitary Sewage

Waste Description: The 2607-W3 septic system has been abandoned in place. This system has been redirected to the 2607-W1 system. Prior to this, the 2607-W3 septic system received sanitary sewer effluent at an estimated rate of 501 cubic feet (14.2 cubic meters) per day.

Code: 2607-W4	Classification: Accepted
----------------------	---------------------------------

Names: 2607-W4; 221-T Head End Septic Tanks and Drainfields	Reclassification None
Type: Septic Tank	Start Date: 1/1/1944
Status: Inactive	End Date: 6/1/1998

Description: The 2607-W4 site consists of two septic systems that both used the 2607-W4 identifier. Both systems supported the 221-T Head End Addition.

The original 2607-W4 septic system was installed in 1944 and taken out of service in 1985. The septic tank had a single chamber with inside dimensions of 4 feet (1.2 meters) long, 2 feet (0.6 meters) wide and 8 feet 4 inches (2.5 meters) deep. The tank extended approximately 6 inches (15 centimeters) above grade when it was constructed and had a wooden lid. The drainfield would have a minimum of 64 linear feet of perforated drain tile, but the location and configuration of the drainfield has not been found on drawings. No features of this system are visible at the surface.

The replacement 2607-W4 septic system was installed in 1985 and taken out of service in 1998. The septic tank is a 1000-gallon (3700-liter), pre-cast concrete tank with two chambers. The drainfield is roughly 56 feet (17 meters) by 16 feet (4.9 meters). The abandoned tank has a metal manhole cover. The abandoned drainfield is located in a depression and was surrounded by post and chain when it was photographed during a 2000 site visit.

Location: Both septic systems are located northwest of the 221-T Head End Addition and adjacent to each other. The drainfield for the replacement tank is located northwest of the tank. The location for the original drainfield is not known.

Related Sites/ Structures: The 2607-W4 septic systems are associated with the 221-T Head End Addition.

Process Description: The 2607-W4 septic systems received sanitary sewer effluent from the 221-T Head End Addition.

Waste Type: Sanitary Sewage

Waste Description: The 2607-W4 septic systems received sanitary sewer effluent. In 1987 it was estimated that the replacement tank was receiving waste at a rate of 2,800 gallons (10,600 liters) per day [reported in source document as 374 cubic feet]. In 1995 it was estimated that the replacement tank was receiving at a rate of 1,330 gallons (5,000 liters) per day.

Code: 2607-W5	Classification: Accepted
Names: 2607-W5; Septic Tank and Drain Field	Reclassification None
Type: Septic Tank	Start Date: 1/1/1944
Status: Inactive	End Date:

Description: The 2607-W5 Septic Tank has been determined to be inactive.

It was a single-compartment tank constructed of concrete and has three entry openings on the top, each protected by a wooden cover. A pipe connects the septic tank to a concrete diversion box, and then to a second concrete diversion box before entering the drainfield. The septic system has two drain fields. The original drain field is located west and north of the septic tank, outside the URM area boundary. The replacement tile field is located north and east of the septic tank.

The septic tank and diversion box are currently located within an Underground Radioactive Material (URM) area related to the 216-U-1, 216-U-2 cribs and the 241-U-361 stabilization.

Location: This unit lies southwest of the 221-U Canyon Building and east of the 207-U Retention Basin. It is north of the 241-U-361 settling tank.

Release Description: UPR-200-W-19 occurred in 1953. The 241-U-361 tank overflowed and caused the ground to become contaminated. The Underground Radioactive Material area, located adjacent to the 2607-W5, is the result of the surface stabilization of this unplanned release.

Related Sites/ Structures: The 2607-W5 Septic Tank is associated with the 221-U Canyon Building, the 222-U Laboratory, the 224-U Facility, the 271-U Building and UPR-200-W-19.

Process Description: The original tile field was built in 1944. A replacement tile field was built east of the original tile field in 1954. The 2607-W5 Septic Tank and associated drain field were designed to accept sanitary sewer effluent from U Plant facilities. In 1998, the system was being used by MO-107 and MO-419. These two mobile trailers have been removed from the area.

Waste Type: Sanitary Sewage

Waste Description: The 2607-W5 Septic System received sanitary sewer effluent at an estimated rate of 1,741 liters (460 gallons) per day in 1995. This unit received sanitary sewer effluent at an estimated rate of 12.2 cubic meters (431 cubic feet) per day in 1987.

Code: 2607-W7	Classification: Accepted
Names: 2607-W7; Septic Tank	Reclassification: None
Type: Septic Tank	Start Date: 1/1/1954
Status: Inactive	End Date:

Description: The 2607-W7 Septic Tank was a small, 950 liter (350 gallon) tank constructed of reinforced concrete. Previous documentation stated the 2607-W7 Septic System includes a septic tank and drain field that lie within a radiation zone. A site visit done in 1999 found the septic tank to be located between two Underground Radioactive Material areas. The location of the drain field was visually not apparent. HNF-SD-LL-SP-001 shows the drain field west of the septic tank.

Location: This unit lies 14 meters (45.9 feet) north of the northernmost corner of the 221-U Canyon Building.

Related Sites/ Structures: The 2607-W7 Septic Tank is associated with the 221-U Canyon Building.

Process Description: The 2607-W7 Septic Tank and associated drain field are designed to accept sanitary waste sewer effluent from the connected facility, a single restroom.

Waste Type: Sanitary Sewage

Waste Description: No radionuclides or hazardous chemicals are associated with this system. The current flow rate to the 2607-W7 Septic System is unknown. However, this system received sanitary sewer effluent at an estimated rate of 1.02 cubic meters (36 cubic feet) per day in 1987.

Code: 2607-W8	Classification: Accepted
Names: 2607-W8	Reclassification: None
Type: Septic Tank	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1998

Description: This system is located adjacent to posted radiation zone containing the 216-Z-5 and 216-Z-4 cribs. The 2607-W8 Septic Tank is constructed of reinforced concrete and has three manhole covers visible on the surface. It is a single compartment tank with an attached dosing siphon. This unit includes a tile field. The site is marked with a sign that read "Septic Tank - 2607-W8".

Location: This unit lies northeast of the 231-Z Building and east of the 216-Z-16 Crib.

Related Sites/ Structures: The 2607-W8 Septic Tank is associated with a sanitary tile field and the 231-Z Building.

Process Description: The 2607-W8 Septic Tank and associated tile field were designed to accept sanitary sewer effluent from the 231-Z Building. The 231-Z Building was associated with the plutonium product finishing process. The tank capacity and dimensions include the settling tank and dosing siphon chamber.

Waste Type: Sanitary Sewage

Waste Description: Although the site is located within a posted radiological area and is associated with the 231-Z Building, DOE/RL-91-58 states that no radionuclides or hazardous chemicals have been associated with this system. The 2607-W8 septic system received sanitary sewer effluent at an estimated rate of 5,015 liters (1,325 gallons) per day in 1992. The estimated rate was 5.45 cubic meters (192 cubic feet) per day in 1987.

Code: 2607-WC **Classification:** Accepted

Names: 2607-WC; 2607-WC Septic System **Reclassification:** None

Type: Septic Tank **Start Date:** 1/1/1971

Status: Inactive **End Date:**

Description: The 2607-WC Septic System has been determined to be inactive. It consists of two tanks and a trench type drain field. A site visit by MSA in July 2015 observed 2607-WC appears to be functional, although not currently being used. The control panel is not operating but could be fixed and brought back into service.

Location: This unit is on the west side of Cooper Ave., across from the 242-S Evaporator Building and northeast of the 272-S Maintenance Shop.

Related Sites/ Structures: The 2607-WC septic system is associated with the 272-S Building, the 242-S Building and MO-027.

Process Description: The 2607-WC Septic Tanks and associated drain field are designed to accept sanitary sewer effluent from the connected facilities.

Waste Type: Sanitary Sewage

Waste Description: The current flow rate to septic system 2607-WC is unknown. The 2607-WC system received sanitary waste at an estimated rate of 1,260 gallons (4,770 liters) per day in 1995.

Code: 2607-WZ **Classification:** Accepted

Names: 2607-WZ **Reclassification:** None

Type: Septic Tank **Start Date:** 1/1/1944

Status: Inactive **End Date:**

Description: The 2607-WZ Septic System includes a drain field. A WIDS sitecode sign on a post marks the

assumed location.

Location: This unit is assumed to be located inside 200 West Area, southwest of the 241-SX Tank Farm and southeast of the 216-S-25 Crib.

Related Sites/ Structures: The 2607-WZ Septic Tank is associated with the 241-SX Tank Farm.

Process Description: The 2607-WZ Septic Tank was designed to accept sanitary sewer effluent.

Waste Type: Sanitary Sewage

Waste Description: The current flow rates for the 2607-WZ Septic System are unknown. The system received sanitary sewer effluent at an estimated rate of 22.6 cubic meters (798 cubic feet) per day in 1987.

Code: 241-WR VAULT **Classification:** Accepted

Names: 241-WR VAULT; 241-WR Vault (Tanks -001 Through -009); 241-WR-01 Thru 09; 244-WR Vault; 296-U-6 Stack; 241WR; 241-WR Diversion Station Vault **Reclassification:** None

Type: Receiving Vault **Start Date:** 1/1/1952

Status: Inactive **End Date:** 1/1/1976

Description: The vault is a below grade, reinforced concrete structure. There are nine compartments arranged in two rows with a 189,000 liter (50,000 gallon) tank in each compartment. A concrete wall separates the two rows of tanks. In addition to the tanks, the vault contains miscellaneous agitators, pumps, and valves. It is marked and posted with Underground Radioactive Material area signs. The exhaust stack and dry well are included in this site. See sub-site descriptions.

Location: This site is located northeast of the 221-U Building, west of Beloit Ave.

Release Description: Tank leaks within the vault were noted in the 1960's. 241-WR-001 was reported to have collapsed during the TBP operation (1952-1958) and was observed to be empty in 1965. However, the 001 sump contained 51,786 liters (13,700 gallons) of liquid. Samples taken at that time indicated the liquid to be slightly contaminated water. All of the sumps and tanks were pumped out in 1965. The liquid was sent to the 216-U-12 crib. When tank 002 was pumped, it floated loose from its base, rupturing the lines connected to the tank. A significant clean up and repair effort was required to return the facility to service. Tanks WR-001, WR-002, WR-004 and WR-005 are suspected to have leaked. Individual specific occurrence reports were not issued. The "hot side" tanks have reportedly contaminated the "cold side" of the vault.

Related Sites/ Structures: The vault is associated with the 296-U-6 Stack, 221-U Plant Uranium Recovery processes, Thorium Recovery process, 200-W-244-PL, 200-W-248-PL, 200-W-105-PL, 241-UX-154 and BC Cribs and Trenches.

Process Description: The 241-WR Vault received uranium and thorium slurry solutions (via underground encased pipelines) from the single shell tanks and prepared the waste to be fed into 221-U facility to extract the uranium and thorium. The 241-WR vault added chemicals and adjusted the pH before it was transferred to the 221-U canyon to be processed through the tributyl phosphate extraction columns. The 241-WR vault (WR-001) also received neutralized waste from the 221-U extraction process and stored it until it was transferred back to the tank farms.

During the WR vaults active operation, it stored uranyl nitrate hexahydrate, nitric acid, and

tributyl phosphate wastes transferred into the vault storage tanks via underground pipelines. During U Plant Uranium Recovery Process operations (1952 to 1958), uranyl nitrate hexahydrate was stored and used as feed for 221-U. Recovered nitric acid was temporarily stored in WR vault to be used again. Tributyl phosphate wastes were stored in WR Vault before being routed to the BC cribs and trenches via the 241-UX-154 Diversion Box and the Cross Site Transfer line (600-284-PL). Following termination of uranium recovery operations in 1958, the vault was used to store nitric acid and thorium from the REDOX and PUREX processes.

In October 1965, contaminated water, including 3.14 kilograms of thorium, was discharged to 216-U-12 crib.

Waste Type: Process Effluent

Waste Description: The site waste contains nitric acid, tributyl phosphate, uranyl nitrate hexahydrate from the TBP process, and thorium nitrate storage. The unit also contains radioactively contaminated equipment and structures. Approximately 60 curies of beta contamination remains inside the vault structure.

This Site has the Following SubSites:

Code: 241-WR VAULT:1

Names: 241-WR VAULT:1; 296-U-6 Stack

Code: 241-WR VAULT:2

Names: 241-WR VAULT:2; 296-U-6 Dry Well

Code: 241-WR VAULT:1

Classification: Accepted

Names: 241-WR VAULT:1; 296-U-6 Stack

Reclassification: None

Type: Receiving Vault

Start Date:

Status: Inactive

End Date:

Description: The surface features of the stack were removed in 1986. The remaining below grade structure includes a 1.04 meter (3 foot 8 inch) octagonal concrete foundation extending 1.23 meters (4 feet) below grade, which encases a portion of the 45.72 centimeter (18 inch) stack that extends 0.31 meters below grade.

Above grade features included a 5.08 centimeter (2 inch) drain pipe exited northwest side of the stack, under the duct, and entered the ground at that point; a 1.9 centimeter (0.75 inch) drain pipe exited the duct just before meeting the stack, and flowed straight down, meeting the 5.08 centimeter (2 inch) drain below grade and a 2.54 centimeter (1 inch) fan drain pipe exited the concrete foundation below the fan, above grade. This pipe entered the ground and connected to the 5.08 centimeter (2 inch) pipe and a 60.96 centimeter (24 inch) dry well.

The 3.81 centimeter (18 inch) diameter, carbon-steel, 296-U-6 vault exhaust stack was mounted on a 1.04 meter (3 foot 8 inch) octagonal concrete foundation. The stack extended 14.63 meters (48 feet) above grade level. The stack was used to discharge unfiltered ventilation air from the storage of UNH for feed to 221-U, then from HNO₃ storage, and later from the storage of thorium.

The SubSite is Part Of:

Code: 241-WR VAULT
Names: 241-WR VAULT; 241-WR Vault (Tanks -001 Through -009); 241-WR-01 Thru 09; 244-WR Vault; 296-U-6 Stack; 241WR; 241-WR Diversion Station Vault

Code: 241-WR VAULT:2 **Classification:** Accepted
Names: 241-WR VAULT:2; 296-U-6 Dry Well **Reclassification:** None
Type: Receiving Vault **Start Date:**
Status: Inactive **End Date:**

Description: A 5.08 centimeter (2 inch) drain pipe ran from the north side of the concrete stack foundation, southeast to a 60.96 centimeter (24 inch) dry well. The exact location of the dry well is not known. The dry well is located southeast of where the stack once stood.

The SubSite is Part Of:

Code: 241-WR VAULT
Names: 241-WR VAULT; 241-WR Vault (Tanks -001 Through -009); 241-WR-01 Thru 09; 244-WR Vault; 296-U-6 Stack; 241WR; 241-WR Diversion Station Vault

Code: 207-Z **Classification:** Accepted
Names: 207-Z; 207-Z Retention Basin; 241-Z Retention Basin; 241-ZRB; 241-Z-RB **Reclassification:** None
Type: Retention Basin **Start Date:** 1/1/1949
Status: Inactive **End Date:** 1/1/1959

Description: The basins were filled with high density grout in 2006. The site had been a concrete basin structure divided into two halves. The two sides were separated by a 0.3 meter (1 foot) thick concrete wall. Each basin contained a sump with a sump pump. A 1.8 meter (6 feet) high chain link fence used to surround the basins.

Location: The concrete basins are located inside the Z Plant Exclusion Area fence, south of 236-Z building.

Related Sites/ Structures: The retention basin is associated with the 241-Z and 234-5Z facilities. Pipelines associated with the basin are discussed in sitecode 200-W-209-PL.

Waste Type: Steam Condensate

Waste Description: The site received potentially contaminated waste. Steam condensate and cooling water, via the D-3 piping system, was sent to this holding facility then released to the 216-Z-1 and 216-Z-11 Ditches.

Code: 216-Z-4 **Classification:** Accepted
Names: 216-Z-4; 216-Z-4 Crib; 231-W-3 Crib; 231-W-3 Pit; 231-W-3 Sump; 216-Z-3 **Reclassification:** None
Type: Trench **Start Date:** 1/1/1945
Status: Inactive **End Date:** 1/1/1945

Description: The 216-Z-4 Trench is an inactive waste management unit. The unit was backfilled and deactivated in 1945. The original configuration was a large unlined excavation.

Location: 216-Z-4 crib is east of 231-Z and north of 216-Z-17 crib.

Related Sites/ Structures: Structures associated with this trench include the capped pipeline from the 231-Z Building and the 231-W-151 Vault sump.

Process Description: The trench was constructed in 1945 to temporarily receive liquid laboratory waste from the 231-Z Building. The 216-Z-4 Trench was deactivated and backfilled when it was discovered to be too small for the waste stream. The laboratory effluent was rerouted to the 216-Z-6 Crib. (since the 216-Z-6 crib was fed with an aboveground pipeline, it is likely the 216-Z-4 was also fed with an above ground pipeline).

Waste Type: Process Effluent

Waste Description: The site received the process and laboratory waste from the 231-Z Building. The waste was neutral to basic.

Code: 216-Z-6 **Classification:** Accepted

Names: 216-Z-6; 216-Z-6 & 6A Crib; 231-W Crib; 231-W-4 Crib; 231-Z-6; 216-W-4; 216-Z-4 **Reclassification:** None

Type: Crib **Start Date:** 1/1/1945

Status: Inactive **End Date:** 1/1/1945

Description: The 216-Z-6 is a below grade, inactive waste management unit. The site consists of a rectangular wooden box set in the base of an excavation. The trench was fed by an above ground pipeline.

Location: The crib is located east of the 231-Z Building and north of Nineteenth Street.

Process Description: The 216-Z-6 Crib received process waste from the 231-Z Building, via an overground line from the 231-W-151 Sump. The site was only used for one month, and abandoned due to plugging of the surrounding soil by process sludge and precipitates.

Waste Type: Process Effluent

Waste Description: The site received process waste from the 231-Z Building via an above ground line from the 231-W-151 Sump Tank.

Code: 216-Z-7 **Classification:** Accepted

Names: 216-Z-7; 231-W Crib; 231-W Trench; 216-Z-6 **Reclassification:** None

Type: Crib **Start Date:** 1/1/1947

Status: Inactive **End Date:** 1/1/1967

Description: The 216-Z-7 Crib is an inactive below grade waste management unit. The crib trench was backfilled upon retirement in 1967. The crib consists of two parallel wooden structures placed in two shallow parallel trenches within a single terraced excavation. Each wooden box consists of three timber tiers, with a perforated distribution box running the length of the second tier. The interior trenches are backfilled and covered with wood planks.

Location: The site is located east of the 231-Z Building and north of Nineteenth Street.

Related Sites/ Structures: Structures associated with this unit include four vent boxes and vent risers, transfer pipes, the 231-Z-151 Sump, and the distribution piping (sitecode 200-W-203-PL). There are two waste unloading stations west of the center line of the crib.

Process Description: Crib 216-Z-7 received process waste from the 231-Z Building from 1947 to 1967. The crib was built to replace Crib 216-Z-5. A riser on the west side of the crib received 300 Area liquid waste from tanker trucks.

Waste Type: Process Effluent

Waste Description: From 1947 to 1953 this crib received process waste from the 231-Z Building via the 231-Z-151 Sump. Beginning in 1953, the site received Hanford laboratory waste from the 231-Z Building, until 1965. From 1965 to 1967, the site received laboratory waste generated by Pacific Northwest Laboratory operations inside the 231-Z Building, and waste delivered in tanker trucks from the 340 Building.

Code: 216-Z-13 **Classification:** Accepted

Names: 216-Z-13; 216-Z-13 A and B; 216-Z-13 Dry Well; 234-5 Dry Well #1; Miscellaneous Stream #261, #261A, #654 **Reclassification:** None

Type: French Drain **Start Date:** 1/1/1949

Status: Inactive **End Date:** 1/1/1999

Description: The site has been determined to be inactive. It consists of a two part drain system. The lower drain is not visible from the surface. The covered top of the upper french drain is visible on the surface, adjacent to a single cement marker post with a metal plate labeled 216-Z-13 (see 1985 photograph 122440-250cn).

Location: The french drain is located northeast of the 291-Z1 stack.

Related Sites/ Structures: This french drain is associated with include two effluent discharge pipes, the ET-8 exhaust fan turbine, and the 291-Z Building. The pipeline to the french drain is 200-W-214-PL.

Process Description: The lower french drain is constructed of two tile culverts placed end-to-end, and backfilled beneath 9 feet (2.7 meters) of gravel. It is located approximately 6 meters (20 feet) south of the drain structure visible on the surface. Two pipes discharged to the lower french drain. The miscellaneous stream (#261) to the drain has been eliminated. The lower french drain received cooling water and steam condensate from the 291-Z ET-8 exhaust fan turbine, building steam condensate and cooling water drainage from the S-13 and S-14 coolers and a floor drain (Misc. Streams #261, 261A and #654). The upper portion of the drain received steam condensate from the 291-Z turbine exhaust stack. Due to the common nature of the discharge to the upper and lower drain systems, there is a potential for historical documentation related to the drains to be confusing. Due to the common nature of the waste discharged to the drains, the upper and lower drains are treated as a single waste site.

Waste Type: Steam Condensate

Waste Description: This french drain received emergency condensate from the turbine of the ET-8 exhaust fan, and 291-Z building steam condensate and floor drainage. Due to the french drain's location, low levels of vadose zone contamination are assumed.

Code: 216-Z-14 **Classification:** Accepted

Names: 216-Z-14; 216-Z-14 A and B; 216-Z-14 Dry Well; 234-5 Dry Well #2; Miscellaneous Stream #261, #263 and #263A **Reclassification:** None

Type: French Drain **Start Date:** 1/1/1949

Status: Active **End Date:**

Description: The site consists of two drain systems. The upper drain is marked with a single cement marker post. The top of the drain has been paved over with asphalt. The lower drain system is not visible from the surface. It is located approximately 6 meters (20 feet) southeast of the cement marker post. The lower french drain is constructed of two tile culverts placed end to end, and backfilled beneath 9 feet (2.7 meters) of gravel. Two pipes discharge to the french drain. The culvert is filled with cobble.

Location: The french drain is located northwest of the 291-Z1 Stack.

Related Sites/ Structures: The lower french drain is associated with two effluent discharge pipes, the ET-9 exhaust fan turbine, and the 291-Z Building. The pipeline to the french drain is 200-W-215-PL.

Process Description: The lower french drain receives cooling water and steam condensate from the turbine of the ET-9 exhaust fan and 291-Z floor drainage. The condensate discharged to the upper drain system has been disconnected and now discharges to the ground. Due to the common nature of the discharge to the upper and lower drain systems, the drains are considered to be a single waste site. There is a potential for historical documentation related to the drains to be confusing.

Waste Type: Steam Condensate

Waste Description: The french drain receives emergency condensate and steam condensate from the turbine of the ET-9 exhaust fan along with 291-Z building steam condensate and floor drainage. Due to the french drain's location, low levels of vadose zone contamination are assumed. The site is addressed in the Miscellaneous Streams Best Management Practices Report, as a b stream (a stream discharging in a surface contaminated area). Based on process history, the drain receives non contaminated effluent.

Code: 216-Z-15	Classification: Accepted
Names: 216-Z-15; 216-Z-15 Dry Well; 234-5 Dry Well #3; Miscellaneous Stream #262	Reclassification: None
Type: French Drain	Start Date: 1/1/1949
Status: Inactive	End Date: 1/1/1997

Description: The 216-Z-15 Dry Well is an inactive, below grade french drain. The drain structure is 9 feet below grade and not visible from the surface. The site is marked with a single concrete marker post that reads "Buried Radioactivity - Do Not Excavate." The marker post is believed to be located directly above the drain structure. The unit is composed of two sections of vitrified clay pipe in a vertical configuration. There is one inlet pipe. The pipe is filled with cobbles and the upper end is covered with a wood plank.

Location: The unit is adjacent to the southeast corner of the 2731-Z Building and north of the 291-Z Ventilation Building.

Related Sites/ Structures: The french drain was associated with the 291-Z building. The pipeline to the french drain is 200-W-216-PL.

Process Description: The french drain received condensate drainage from the 291-Z building S-12 Evaporator Cooler via a floor drain in the northwest corner of the 291-Z building. The source was later re-routed to the 291-Z Sump and batch discharged to the PFP Low Level Waste Treatment Facility.

Waste Type: Process Effluent

Waste Description: The site used to receive the drainage from the 291-Z building S-12 Evaporator Cooler. That source was eliminated in May 1997. Low levels of contamination are assumed, due to the possibility of accidents or unusual events in nearby areas.

Code: 216-Z-16	Classification: Accepted
Names: 216-Z-16; 216-Z-16 Crib	Reclassification: None
Type: Crib	Start Date: 1/1/1968
Status: Inactive	End Date: 1/1/1977

Description: The site is a rectangular excavation with gravel filling the bottom third. A perforated pipe runs the length of the excavation. The gravel is covered with a polyethylene barrier. The excavation is backfilled to grade.

Location: The crib is located northwest of the 231-Z Building.

Related Sites/Structures: Eleven crib penetrating monitoring wells, one gage well, two monitoring wells adjacent to the crib, a vent riser, and the waste transfer line from 231-Z Building comprise structures associated with this trench. The crib pipeline is sitecode 200-W-200-PL.

Process Description: The crib was used to dispose of 231-Z laboratory waste in the soil column.

Waste Type: Process Effluent

Waste Description: The site received waste from Pacific Northwest Laboratory operations in the 231-Z Building. The waste was neutral to basic, and included approximately 0.08 kilograms (0.16 pounds) of plutonium.

Code: 216-Z-17	Classification: Accepted
Names: 216-Z-17; 216-Z-17 Ditch	Reclassification: None
Type: Trench	Start Date: 1/1/1967
Status: Inactive	End Date: 1/1/1968

Description: The 216-Z-17 is an inactive waste site has been deactivated and backfilled. During operation this unit was configured as a long excavation that had sloped sides. The carbon steel effluent discharge pipe fed into a metering box that in turn discharged to the open trench.

Location: This unit is due east of the 231-Z Building, and immediately east of the 216-Z-6 Crib.

Related Sites/Structures: Structures associated with the 216-Z-17 Trench include the 231-W-151 Sump Tank, waste transfer lines, the metering box, and the effluent discharge pipe. The pipeline that fed the 216-Z-17 crib is sitecode 200-W-201-PL.

Process Description: The trench was used to dispose of laboratory waste from Laboratory operations in the 231-Z Building.

Waste Type: Process Effluent

Waste Description: The site received waste from Pacific Northwest Laboratory operations in the 231-Z Building. The waste is neutral to basic, and contained approximately 0.05 kilograms (0.11 pounds) of plutonium.

Code: 2607-Z	Classification: Accepted
Names: 2607-Z	Reclassification: None
Type: Septic Tank	Start Date: 1/1/1949

Status: Inactive **End Date:** 6/1/1999

Description: The septic system was abandoned per the requirements of Washington Administrative Code 246-272-18501 in 1999. The 2607-Z Septic Tank and drain field lie in a fenced area. The septic tank is constructed of concrete and is a two chamber tank. Three manholes are provided for personnel entry. The drain field measures approximately 86 meters (282 feet) in length and 47 meters (154 feet) in width. The tile field is located inside a fenced area.

Location: This unit lies east of the 236-Z Building and southeast of the 234-5Z Building.

Related Sites/ Structures: The 2607-Z Septic Tank is associated with the 234-5Z, 2704-Z, 270-Z, 236-Z, 292-Z, 2701-Z, 2701-ZA, and the 2701-ZB Buildings.

Process Description: The 2607-Z Septic Tank and drain field are designed to accept sanitary sewer effluent from the associated facilities. It received waste from 234-5Z and 2704-Z.

Waste Type: Sanitary Sewage

Waste Description: No radionuclides or hazardous chemicals have been associated with this waste unit. Current flow rates indicate that the drain field is not providing adequate effluent treatment. This unit received sanitary sewer effluent at an estimated rate of 6,000 gallons (23,000 liters) per day in 1992.

Code: 2607-Z1 **Classification:** Accepted

Names: 2607-Z1; Septic Tank and Drainfield **Reclassification:** None

Type: Septic Tank **Start Date:** 1/1/1958

Status: Inactive **End Date:** 1/1/1999

Description: The septic system was abandoned per the requirements of Washington Administrative Code 246-272-18501 in 1999. The system (septic tank and drainfield) was constructed in 1958 and was pumped once a week. The drainfield location has been used as a laydown area in the past and the underground laterals may have been damaged.

Location: The site is located west of the 2721-Z Building, west of the 234-5Z facility.

Related Sites/ Structures: The site is associated with 234-5Z Building Annex and 2736-ZB.

Waste Type: Sanitary Sewage

Waste Description: The waste is sanitary sewage.

Code: 600-70 **Classification:** Accepted

Names: 600-70; Solid Waste Management Unit (SWMU) #2 - Miscellaneous Solid Waste **Reclassification:** None

Type: Dumping Area **Start Date:** 1/1/1950

Status: Inactive **End Date:**

Description: The site is located on relatively flat terrain except for natural depressions and evidence that trenches may have been dug. Large amounts of construction materials such as concrete, wood, metal, cans, barrels and transite are visible. Numerous areas of burned materials were also observed.

Location: The site is located 360 meters (1,181 feet) east of REDOX, outside the 200-W Area perimeter fence.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: Large piles of debris that includes concrete cover blocks, concrete chunks, wood, scrap metal, cans, buckets, barrels, glass and transite are spread over a large area.

Waste Type: Construction Debris

Waste Description: Concrete, rebar.

Waste Type: Misc. Trash and Debris

Waste Description: Metal lathe turnings, glass, lumber and tar.

Waste Type: Asbestos (friable)

Waste Description: Suspected friable asbestos.

Waste Type: Asbestos (non-friable)

Waste Description: Transite

Code: UPR-200-W-3 **Classification:** Accepted

Names: UPR-200-W-3; Railroad Contamination; UN-200-W-3 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1949

Status: Inactive **End Date:**

Description: The T-Plant Railroad Cut is a posted Contamination Area from the tunnel door westward to a chain link gate. A 1.8 meter by 1.8 meter (6 foot by 6 foot) posted Contamination Area is located approximately 6 meters (20 feet) west of the T-Plant chain link fence that crosses the railroad cut track and encloses the T-Plant facility.

Location: The site is located on the T Plant railroad cut track, northwest of the 221-T Canyon Building.

Release Description: On several occasions in 1949, contaminated equipment being hauled to the 200 West Burial Ground from T Plant contaminated ground near the railroad.

Waste Type: Chemicals

Waste Description: The release was undefined radioactive contamination.

Code: UPR-200-W-4 **Classification:** Accepted

Names: UPR-200-W-4; Railroad Contamination; UN-200-W-4 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1949

Status: Inactive **End Date:**

Description: The release is not physically marked or posted.

Location: The contamination spread was located on the railroad tracks extending from the 221-T Canyon Building Tunnel to the Heavy Equipment Burial Ground.

Release Description: In 1949, contamination spread from a burial box that had been transported from the 221-T Canyon Building to the Heavy Equipment Burial Ground. After the box was buried, the bulldozer used to cover the trench was found to be contaminated with dust which had readings up to 10,000 counts/minute. A complete survey was made from the Canyon Building to the Heavy Equipment Burial Ground, which revealed a spread of contaminated particles. The most contamination was found in the vicinity northeast of the burial ground.

Waste Type: Soil

Waste Description: Contamination specks were found along the RR track with readings averaging 7 millirem/hour.

Code: UPR-200-W-14	Classification: Accepted
Names: UPR-200-W-14; Waste Line Leak at 242-T Evaporator; UN-200-W-14	Reclassification: None
Type: Unplanned Release	Start Date: 10/1/1952
Status: Inactive	End Date: 10/1/1952

Description: The Unplanned Release site is described as contamination on the surface above the waste line between the 242-T Evaporator and the 207-T Retention Basin (see 200-W-166-PL). Since the exact location of this 1952 Unplanned Release is not documented, it was considered possible that one of the areas stabilized in 2001 is in the same location as the 1952 line leak. The mapping coordinates for the 1952 contamination have been estimated from the limited information provided. A posted URMA with Bio Barrier signs is currently located at the location indicated in the 1952 hand drawn sketch. A WIDS sitecode sign was placed at this posted URMA in 2014.

Location: The 1952 release occurred in an underground pipeline causing water to be observed on the surface, east of the 241-TY Tank Farm. The exact location was not documented. A hand drawn sketch in HW-60807 places the release location near the 241-TY east fence. The mapping coordinates have been estimated.

Release Description: In October 1952, a steam coil in the 242-T waste evaporator tank caused ground contamination along the surface above the leaking cast iron pipe which carries cooling water and steam condensate from the waste evaporator building to the 207-T Retention Basin.

Related Sites/Structures: The release is associated with the 242-T Evaporator, 207-T Basin and pipelines 200-W-166-PL.

Process Description: H-2-44511 shows a cast iron pipeline that connects the 242-T Evaporator with the 207-T Retention Basin (see pipeline sitecode 200-W-166-PL). The pipeline carried steam condensate from the building to the basin. The line runs north to south along the east side of the 241-TY Tank Farm, parallel to an encased waste transfer line.

Waste Type: Steam Condensate

Waste Description: Cooling water and steam condensate from the 242-T waste evaporator that was routed to the 207-T retention basin through an underground cast iron pipeline. The contaminants were not identified, but since 242-T was the source of the stream, the material probably has a similar composition to the liquid discharged to the cribs.

Code: UPR-200-W-19 **Classification:** Accepted
Names: UPR-200-W-19; 241-U-361 Overflow; UN-200-W-19 **Reclassification:** None
Type: Unplanned Release **Start Date:** 1/1/1953
Status: Inactive **End Date:**

Description: The site is an unplanned release. The area where the release occurred is covered with shotcrete and currently marked as a "Underground Radioactive Material" (URM) area that also contains the 216-U-1 Crib, 216-U-2 Crib, the 241-U-361 Settling Tank. A portion of the 2607-W5 tile field is also included in the URM area. In 2014, the posted area was expanded to the east due to growing contaminated vegetation. An area measuring approximately 36 by 36 feet, on the east side of a gravel road, was also included in this expansion. In 2015, an area on the north side, adjacent and overlapping 2607-W5, was expanded due to elevated radiological readings being detected with the Rad tractor.

Location: The release occurred north of 16th Street, near the 361-U Settling Tank and the 216-U-1&2 Crib.

Release Description: In the Spring of 1953, organic wastes and cell drainage from the Tributyl Phosphate (TBP) process in 221-U and waste from 224-U (UO₃) overflowed to the ground by way of the tank (241-U-361) and crib vents (216-U-1 and 216-U-2). Contamination readings of 11.5 rads per hour at a distance of 7.6 centimeters (3 inches) were reported over an area of approximately 4.6 square meters (50 square feet).

Related Sites/ Structures: The release is associated with the 221-U, 224-U, 241-U-361 tank and the 216-U-1&2 Crib.

Waste Type: Chemicals

Waste Description: The release contained an unknown quantity of organic wastes and cell drainage from the Tributyl Phosphate (TBP) and Uranium Trioxide (UO₃) plants with readings to 11.5 rads/hour at 7.6 centimeters (3 inches).

Code: UPR-200-W-23 **Classification:** Accepted
Names: UPR-200-W-23; Waste Box Fire at 234-5Z; UN-200-W-23 **Reclassification:** None
Type: Unplanned Release **Start Date:** 1/1/1953
Status: Inactive **End Date:** 1/1/1953

Description: A 1999 facility walkdown could not locate this unplanned release site. The approximate area is marked with a WIDS sign painted on the asphalt. The event occurred in June 1953. In 2015, the 234-5Z Complex was in the demolition process and affects the area of this Unplanned Release.

Location: A sketch included in HW-60807 places this release near the south wall of 234-5Z, approximately 61 meters (200 feet) north of the 291-Z Stack.

Release Description: In June 1953, a fire in a waste box resulted in approximately 28 square meters (300 square feet) of ground contamination. The fire caused a spread of plutonium contamination with readings up to 10,000 disintegrations per minute.

Waste Type: Ash

Waste Description: Plutonium contamination up to 10,000 disintegrations was spread by a fire in a waste box in June 1953.

Code: UPR-200-W-33 **Classification:** Accepted

Names: UPR-200-W-33; Ground Contamination at 224-U; UN-200-W-33 **Reclassification:** None

Type: Unplanned Release **Start Date:** 3/1/1955

Status: Inactive **End Date:** 3/1/1955

Description: The release site occurred inside the fenced 224-U facility boundary. The 224-U and 224-UA buildings were demolished in 2010. The area is covered with gravel. The release site is not separately marked or posted.

Location: The site is located approximately 28 meters (90 feet) east of the 224-U Building.

Release Description: In March 1955, a leaking flange of the C-5 Condensate Line from the 224-U Building caused a small area 3 by 4.5 meters (10 by 15 feet) of ground to become contaminated.

Related Sites/ Structures: The release is associated with the Uranium Recovery process at the 224-U facility.

Waste Type: Process Effluent

Waste Description: A leaking flange in the C-5 condensate line at the 224-U building caused an area of ground contamination measuring approximately 0.9 meters by 0.9 meters (3 foot by 3 foot).

Code: UPR-200-W-36 **Classification:** Accepted

Names: UPR-200-W-36; Groundwater Contamination at 216-S-1 and 216-S-2 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1955

Status: Inactive **End Date:** 1/1/1955

Description: The 216-S-1 & 2 cribs are currently bare ground, marked by concrete posts and a light chain, posted with "Underground Radiation Material" area and "Cave-in Potential" signs. The well is painted yellow and marked 299-W22-3.

Location: The release occurred at a well located near the east end of 216-S-1 & 2 cribs, east of the 241-SX Tank Farm.

Release Description: On August 2, 1955, process vapors were smelled near the 216-S-1 & 2 cribs. A Radiation Monitor investigated the area and found the well cap on test well 207-S-11 (alias 299-W22-3) to have a dose rate of 4 rad per hour on the well cap. A water sample was collected from the well on August 4, 1955 that resulted in a personnel contamination incident. The sampler also reported a gurgling sound coming from the well. It was concluded that the well casing had failed or ruptured. The rupture was apparently allowing process waste to bypass the crib soil column and flow directly into the groundwater. The well was promptly backfilled with sand.

Related Sites/ Structures: The release is associated with the 216-S-1 & 2 cribs and well 299-W22-3.

Process Description: The test well originally consisted of a 20.3 centimeter (8 inch) steel casing driven to a depth of 45.7 meters (150 feet). In January of 1955, the well was extended an additional 50 meters (163 feet), beneath the groundwater table which was at a depth of about 65.5 meters (215 feet) in 1955.

Waste Type: Process Effluent

Waste Description: The 216-S-1 and 216-S-2 Cribs received cell drainage from the D-1 Receiver Tank and redistilled condensate from the D-2 Receiver Tank in the 202-S Canyon Building. The inorganics found at the site include: aluminum, nitrate, nitric acid, and sodium. The radionuclides found at this site are: cobalt-60, americium-241, cesium-137, uranium, and plutonium. An unknown volume of this waste entered the groundwater beneath the crib through a rupture in the well casing. During the time between the last normal reading from the well (June 1955) and the time the incident was discovered, about 7,500,000 liters (2,000,000 gallons) of liquid waste, with an estimated gross beta activity of 7,500 curies had passed into the crib. Also, within this span of time about 40 grams (1.4 ounces) of plutonium had entered the crib.

Code: UPR-200-W-39 **Classification:** Accepted

Names: UPR-200-W-39; 224-U Buried Contamination Trench; UN-200-W-39 **Reclassification:** None

Type: Unplanned Release **Start Date:** 3/1/1954

Status: Inactive **End Date:** 3/1/1954

Description: The release site is not marked because the 224-UA Building was built over the release location. The 224-U and 224-UA buildings were demolished in 2010. The area is now covered with gravel.

Location: According to available references, the release occurred on the southeast side of the 224-U building. The disposal trench is located under the 224-UA (Calcliner Building) addition.

Release Description: A leak from 224-U, during March 1954, spread to an area southeast of the 224-U Building. The contamination was placed in a trench that measured 3.1 meters (10 feet) wide by 15.2 meters (50 feet) long. The contamination was covered with 0.9 meters (3 feet) of clean soil.

Related Sites/ Structures: The release is associated with the 224-U Facility.

Waste Type: Process Effluent

Waste Description: The release was described as a leak from 224-U. The effected soil was placed in a nearby trench. A later reference described the contamination as uranium, less than 10 nanocuries/gram. No volume estimate is provided.

Code: UPR-200-W-41 **Classification:** Accepted

Names: UPR-200-W-41; Railroad Contamination; REDOX Railroad Cut Contamination; UN-200-W-41 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1956

Status: Inactive **End Date:**

Description: The railroad track from the 202-S Tunnel to the first gravel road intersection has been covered with clean backfill material. The berms on the sides of railroad cut have been pushed in and posted as an "Underground Radioactive Material" area.

Location: The release occurred on the railroad right-of-way from the 202-S Railroad cut to the burial ground. The railroad cut and the railroad track north of REDOX has been backfilled, stabilized and posted as Underground Radioactive Material.

Release Description: On July 7, 1956, during the transit of a box containing the J-5 Filter and miscellaneous equipment from the 202-S Building Canyon, spotty contamination up to 1,000 millirads/hour at surface was spread along the right-of-way from the 202-S Building railroad cut to the burial ground presumably from liquid contained in the burial box. Six spots of 1,000 millirads/hour were found on the east side of the track on the blacktop at the 16th Avenue crossing. The area was immediately roped off and was eventually decontaminated to less than 1,000 counts per minute. Initial surveys indicated spotty contamination from 100 to 500 millirads/hour along the east side of the right-of-way diminishing in frequency from 19th Avenue to the burial ground. A check of the flat car used for the burial revealed low level contamination on all horizontal surfaces of 10,000 to 20,000 counts per minute and several areas on the paper in the southeast corner of the flat car to 3,000 millirads/hour at surface. Special fiberglass deposition filters placed along the tracks did not indicate a general contamination spread.

Related Sites/ Structures: The site is associated with 202-S and UPR-200-W-42.

Process Description: Radiologically contaminated fuel rods were transported to the REDOX facility for processing by rail car. Contaminated material and equipment were transported to the burial grounds on the same rail road track. Over time the railroad track became contaminated.

Waste Type: Chemicals

Waste Description: The waste was contaminated with beta/gamma with readings to 1,000 millirads/hour.

Code: UPR-200-W-46	Classification: Accepted
Names: UPR-200-W-46; Contaminated Railroad Track; H-2 Centrifuge Burial; UN-200-W-46	Reclassification: None
Type: Unplanned Release	Start Date: 1/1/1957
Status: Inactive	End Date:

Description: The railroad track from the 202-S Tunnel to the first gravel road intersection has been covered with clean backfill material. The railroad cut located inside the facility fence is posted as a "Contamination Area." The section of covered track from the fence to the first gravel road intersection is posted as an "Underground Radioactive Material" area.

Location: Burial operation of the H-2 Centrifuge from REDOX resulted in spotty contamination in the REDOX, 234-5Z, and 224-U Plant areas. General low level smearable contamination was also found along the railroad right-of-way to the burial ground.

Release Description: Problems began when the H-2 Centrifuge was placed in a burial box in the REDOX Railroad Tunnel on December 30, 1957. After a short period of time fumes were observed coming from the centrifuge. Corrective measures to control the escape of fumes were attempted but were generally unsuccessful. After about four hours of this condition, fumes escaped the tunnel and began circulating throughout the REDOX Building via the ventilation system. By 4:30 A.M., December 31, 1957, respiratory protection was required for all personnel entering the north side of REDOX or the 233-S Building. Later, the respiratory protection requirements were extended to the south operating areas of REDOX. Considerable surface contamination was deposited in and around REDOX, including construction work areas outside the building. The centrifuge was transported by train to the burial ground. The burial box was observed to be "puffing" slightly as it proceeded to the burial site but no contamination was observed along the railroad right of way. It was buried at about 10:00 A.M on December 31, 1957. Dose rates related to the centrifuge burial were documented as 185 millirads/hour at 177 meters (580 feet), and about 2 millirads/hour at 0.8 kilometers (0.5 mile). Radiation fields averaging 1 rad/hour during backfilling of the centrifuge box in the burial ground prevented the box from being completely

buried in one day. Two employees received face and nostril contamination during the backfill operation. Two days later, radiation surveys revealed a general low level smearable contamination along the railroad right-of-way.

Waste Type: Equipment

Waste Description: The waste was contaminated fumes emitting from a centrifuge, with beta/gamma readings up to 1 rad/hour noted during burial. The centrifuge was ruthenium contaminated.

Code: UPR-200-W-48 **Classification:** Accepted

Names: UPR-200-W-48; Contaminated Railroad Track
Near 221-U; UN-200-W-48 **Reclassification:** None

Type: Unplanned Release **Start Date:** 7/9/1958

Status: Inactive **End Date:**

Description: The area is no longer marked or posted. The waste site was a spread of radioactive contamination in 1958.

Location: The contamination spread occurred at the west end of the 221-U railroad cut at Bridgeport Avenue, west of 221-U.

Release Description: On July 9, 1958, a survey of the railroad area revealed a spread of contamination in the vicinity of the road intersection with the 221-U railroad. The incident occurred when a jumper, wrapped in plastic, was transferred from a flat-bed truck to a railroad flat-car at the railroad crossing. The jumper was transferred from the truck to the railroad car by a crane and moved into the 221-U railroad tunnel. Dose rates up to 9 rad per hour over an area of about 93 square meters (1,000 square feet) were detected. The contamination spread was caused by the plastic wrapping on the jumper being damaged during transfer.

Waste Type: Chemicals

Waste Description: The release site contained beta/gamma with readings to 9 rads/hour that spread while moving a plastic wrapped, waste transfer jumper off a flat bed truck. It is not known what facility the jumper came from.

Code: UPR-200-W-51 **Classification:** Accepted

Names: UPR-200-W-51; UPR-200-W-52; Release from
241-S Diversion Box; UN-200-W-51 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1958

Status: Inactive **End Date:**

Description: The release site is not currently marked or posted. The area where this release had been located (in 1958) is near an area that was surface stabilized in 1992 (UPR-200-W-165).

Location: The contamination spread southward from the 241-S-151 Diversion Box (inside the 241-S tank farm) to approximately 91.4 meters (100 yards) beyond the 200 West Area fence. The plume was approximately 100 meters (300 feet) wide.

Release Description: On September 12, 1958, high pressure steam was applied to the D-8 line of the 241-S Diversion box in an attempt to unplug it. The pressure bled back into the diversion box and caused a release of contamination. A follow up survey revealed contamination readings up to 1 rad/hour immediately around the box. Contamination levels 30 meters (100 feet) south of the diversion box were 50 milirad per hour. A narrow strip of contamination extended southward, across Tenth Street, with contamination levels of 4,000 counts per minute. The contamination

continued southward approximately 91.44 meters (100 yards) beyond the 200 West Area fence. The particles outside of the 200 West Area fence read on the order of 5,000 counts per minute. The contaminated areas were posted and the gross contamination was flushed with water.

Related Sites/ Structures: The site is associated with the 241-S-151 Diversion Box, UPR-200-W-52, UPR-200-W-114 and UPR-200-W-165.

Waste Type: Process Effluent

Waste Description: Beta/gamma particulates with readings up to 50 millirads/hour within 100 feet (30.48 meters) of the diversion box and readings on Tenth Street to about 4,000 counts/minute and 5,000 counts per minute outside the fence were documented. Beta/gamma readings of up to 1 rad/hour were identified immediately around the 241-S-151 Diversion Box. Specific contaminants were not identified.

Code: UPR-200-W-55 **Classification:** Accepted

Names: UPR-200-W-55; Uranium Powder Spill at 224-U; UN-200-W-55 **Reclassification:** None

Type: Unplanned Release **Start Date:** 4/12/1960

Status: Inactive **End Date:** 4/12/1960

Description: The site is no longer marked or posted. The 224-U building was demolished in 2010. The area is now covered with gravel.

Location: The spill occurred at the 224-UA Building Loadout Room asphalt loading ramp. The nearby roadway, and ground surface around the ramp were contaminated.

Release Description: On April 12, 1960, a 224-UA Loadout Room container overrun caused 1.36 metric tons (1.5 tons) of uranium powder to spill onto the asphalt loading ramp when a loading hose broke. This resulted in the contamination of the 224-UA Building asphalt loading ramp and a nearby roadway. During cleanup uranium was spread to nearby ground.

Waste Type: Chemicals

Waste Description: On April 12, 1960, 1.36 metric tons (1.5 tons) of uranium powder that had been separated from fission products spilled on the ground. Most of the powder was picked up and drummed.

Code: UPR-200-W-60 **Classification:** Accepted

Names: UPR-200-W-60; Railroad Contamination; UN-200-W-60 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1966

Status: Inactive **End Date:**

Description: The U Plant Railroad had been surrounded with soil berms on the north and south sides of the track and posted with Contamination Area signs. The area was surface stabilized in 2001. The stabilization included the UPR-200-W-60 area. The entire area, including the railroad tracks, is now covered clean dirt and posted with Underground Radioactive Material Area signs.

Location: Spotty contamination extended from the 221-U tunnel door along the railroad tracks for a distance of about 68.6 meters (225 feet).

Release Description: On February 25, 1966, contaminated water dripped from a hole in the bottom of a PUREX equipment transfer box as the box was being pulled from the 221-U Building tunnel. Radioactivity along the railroad track ranged from a few thousand counts per minute to a

maximum of 1 rad/hour. The release effected approximately 68 meters (225 feet) of rail road track.

Related Sites/ Structures: The site is associated with the 221-U building and UPR-200-W-117.

Waste Type: Chemicals

Waste Description: PUREX equipment was being transferred to U Plant in a rail car filled with water (for shielding). Beta/gamma contamination was found on the railroad tracks with readings ranging from a few thousand counts per minute to a maximum of 1 rad/hour.

Code: UPR-200-W-63 **Classification:** Accepted

Names: UPR-200-W-63; Road Contamination Along the South Shoulder of 23rd Street; UN-200-W-63 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1966

Status: Inactive **End Date:**

Description: The release site is not currently marked.

Location: The contamination spread effected the road surface of 23rd Street in 200 West Area. ARH-2015 and ARH-2757 state the contamination was spread began 152.4 meters (500 feet) west of the west railroad crossing on 23rd Street and extended (eastward) to the intersection of Bridgeport and 23rd Street, along the south shoulder of 23rd Street. The document also gives approximate Hanford Site coordinates of N43175, W74025/N43175, W77500.

Release Description: On September 21, 1966, strontium-90 in the form of particulate matter spread from a used diversion box jumper as it was being transported from the 200 West Dry Waste Burial Ground to the 221-T Canyon. The jumper had just previously been removed from the 241-TX-153 Diversion Box. Spotty contamination on 23rd Street was found along the road and shoulder. Speck contamination approximated one per square yard of ground surface along the shoulder of 23rd Street.

Related Sites/ Structures: It is possible this release is associated with the radiologically posted areas 200-W-90.

Waste Type: Chemicals

Waste Description: The contamination was in the form of strontium-90 with an activity of about 1 curie. Spots of contamination up to 500 millirads/hour were removed from the road.

Code: UPR-200-W-65 **Classification:** Accepted

Names: UPR-200-W-65; Contamination in the T-Plant Railroad Cut; UN-200-W-65 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1969

Status: Inactive **End Date:**

Description: The railroad cut is currently posted as a Contamination Area, extending from the tunnel door westward to a chain link gate and fence.

Location: The contamination was found in the T Plant railroad cut, that is located on the west side of the 221-T facility adjacent to the railroad tunnel.

Release Description: On October 27, 1969, contamination was found during a routine survey of the 221-T Plant railroad cut. Spots of contamination from 5,000 counts per minute to 150 millirads/hour were found between the rails of the spur line and adjacent to the spur line. One area, about 45.72 meters (50 yards) from the tunnel door, was generally contaminated over an area measuring 0.9 meters (3 feet) by 3 meters (10 feet). From this area west, the contamination spots were spaced a few inches to a few feet until approximately 114.3 meters (125 yards) from the tunnel door, where the contamination was non-detectable. The exact source of the contamination is unknown, but the location limits the cause to a rail car carrying radioactive material which was not effectively contained.

Process Description: Contaminated equipment was sent to T Plant on railcars for repair and decontamination.

Waste Type: Chemicals

Waste Description: Beta/gamma with readings from 5,000 counts/minute to 150 millirads/hour.

Code: UPR-200-W-67 **Classification:** Accepted

Names: UPR-200-W-67; Contamination Near 2706-T; UN-200-W-67 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1970

Status: Inactive **End Date:**

Description: The unplanned release site is marked with a single post with a WIDS site number sign. The sign is adjacent to the MO433 trailer.

Location: The contamination was located on the north side of 2706-T Building adjacent to the MO433 trailer.

Release Description: On August 5, 1970, a contaminated electric lift was parked outside a radiation zone on the north side of the 2706-T building. Contamination from the vehicle affected the ground beneath the vehicle; an area of approximately 0.91 meters (3 feet) by 7.32 meters (24 feet). The ground was contaminated with a maximum of 20,000 counts per minute. The lift had been positioned outside of the radiation zone awaiting a radiological release survey. The electric lift was from 221-B Plant, but had not been properly surveyed before being moved to 2706-T.

Process Description: The 2706-T building is a vehicle and equipment decontamination facility.

Waste Type: Equipment

Waste Description: Beta/gamma with readings of 20,000 counts/minute on the ground. The contaminated electric lift read as high as 500 millirads/hour.

Code: UPR-200-W-73 **Classification:** Accepted

Names: UPR-200-W-73; Contaminated Railroad Track at 221-T; UN-200-W-73 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1974

Status: Inactive **End Date:**

Description: The railroad cut adjacent to the 221-T tunnel is currently posted as a Contamination Area. The rail spur leading into the 2706-T facility is currently not posted. The Unplanned Release area is

	not specifically marked or posted.
Location:	The contamination was located on the railroad tracks that connect the 221-T Building Tunnel to the 2706-T Building.
Release Description:	On October 16, 1974, a contamination spread from a leaking multi-purpose transfer box was discovered. During a routine survey in the 221-T Building Tunnel, on October 14, 1974, contamination levels up to 3,800 millirads/hour were detected on the bed of the multi-purpose transfer box railroad car. Decontamination of the rail car was scheduled for October 15, 1974. During the decontamination effort, a hair-line crack was observed in a weld of the outer shell of the transfer box. Radiation readings on the transfer box were reduced to 350 millirads/hour and 600 counts per minute smearable on October 16, 1974. The railcar was moved to the 2706-T Building so repairs could be made. A follow-up survey of the railcar at 2706-T indicated that additional contamination had seeped out. Radiation readings on the rail car had increased to 50,000 counts per minute smearable. A survey of approximately 365.76 meters (400 yards) of railroad track between 221-T Building Tunnel and the 2706-T Building revealed spots of contamination up to 40 millirads/hour. The cause of the leakage was migration of decontamination solution to the hair-line crack area and subsequent leaking due to rail movement of the transfer box.
Process Description:	Contaminated equipment was transferred to T Plant on railcars for repair and decontamination.
Waste Type:	Chemicals
Waste Description:	Spotty beta/gamma contamination with readings to 40 millirads/hour on the ground.

Code:	UPR-200-W-76	Classification:	Accepted
Names:	UPR-200-W-76; Contamination Found at 241-TX-155; UN-200-W-76	Reclassification	None
Type:	Unplanned Release	Start Date:	1/1/1977
Status:	Inactive	End Date:	

Description: In 2008, the area surrounding 241-TX-152 Diversion Box, 241-TX-155 Diversion Box and 241-TX-302B catch tank has been covered with a layer of clean gravel. It is posted with Bio-Barrier and Underground Radioactive Material signs. A single white sign with black letters reading "WIDS UPR-200-W-76" is hanging on the chain on the near the south side of the 241-TX-152 Diversion Box.

Location: The site is located east of Camden Ave. The radiologically posted area surrounds the 241-TX-152 Diversion Box, 241-TX-155 Diversion Box and 241-TX-302B catch tank.

Release Description: On August 24, 1977, contaminated rabbit fecal pellets were found around the 241-TX-155 Diversion Box. A more extensive survey revealed contaminated pellets with readings as high as 100 millirads/hour scattered in an area of about 50 yards (45.72 meters) by 100 yards (91.44 meters) around the diversion box. Two pellets were analyzed for radiological contaminants and found to contain mostly cesium-137. Subsequent surveys found additional spotty contamination extending in a 152 meter (500 foot) radius around the 241-TX-155 diversion box. The source of the contamination was traced to leaks from the 241-TX-155 Diversion Box. The east side of the diversion box had been partially excavated in 1976. The excavation was left open for more than a year, allowing access for animal intrusion.

Related Sites/Structures: The site is associated with the 241-TX-155 and 241-TX-152 Diversion Boxes.

Process Description: The original Occurrence Report (77-180) described the release as contaminated rabbit feces extending 100 yards (91.44 meters) by 50 yards (45.72 meters) around the 241-TX-155 Diversion Box and additional specks of contamination extending to a 152 meter (500 foot) radius around the 241-TX-155 diversion box.

Waste Type: Animal Waste

Waste Description: Radioisotopic analyses on two individual rabbit pellets revealed: 18.6 microCuries cesium-137 per gram of sample, 0.044 microCuries cesium-134 per gram of sample, 0.093 microCuries europium-155 per gram of sample, 0.026 microCuries europium-154 per gram of sample, and 2.63 microCuries strontium-90 per gram of sample. Beta-gamma readings up to 100 millirads/hour were found.

Code: UPR-200-W-78 **Classification:** Accepted

Names: UPR-200-W-78; UN-200-W-78; UO3 Powder **Reclassification:** None
Spill at 224-U

Type: Unplanned Release **Start Date:** 8/21/1970

Status: Inactive **End Date:** 8/21/1970

Description: The site is no longer marked or posted. The 224-U building was demolished in 2010. The area is now covered with gravel.

Location: The release caused an area, located 36 meters (40 yards) south of the Uranium Tri-Oxide barrel storage area, to become contaminated.

Release Description: On August 21, 1970 a radiation survey done with a truck mounted road monitor. The equipment detected an area measuring approximately 3.72 square meters (40 square feet) contaminated with levels up to 20,000 counts/minute. It is assumed that some uranium powder spilled prior to March 1969, when the last pallets were moved from 224-U.

Waste Type: Chemicals

Waste Description: Uranium trioxide powder was spilled on the ground. Contamination up to 20,000 counts per minute was found.

Code: UPR-200-W-82 **Classification:** Accepted

Names: UPR-200-W-82; Contamination Spread at 240-S-151; UN-200-W-82 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1980

Status: Inactive **End Date:** 1/1/1980

Description: A WIDS sign has been placed on the chain link fence north of 202-S. The fenced area is also marked with Underground Radioactive Material Area signs. The 240-S-151 Diversion Box is posted with radiological warning signs. The contamination spread occurred in the soil adjacent to the diversion box.

Location: The contamination spread occurred on the north and east side of the 240-S-151 Diversion Box and the 240-S-302 Catch Tank, on the north side of the REDOX facility (202-S).

Release Description: A piece of equipment moved in for the 240-S-151 Diversion Box installation, was caught under the late snow cover. Moisture from the melting snow and rain penetrated the plastic wrap, and ran off toward the catch tank area spreading contamination over the areas of run-off. Traffic from daily routine surveillance of the catch tank liquid levels apparently tracked some

contamination to the chain boundary and step-off area.

Related Sites/ Structures: UPR-200-W-82 was associated with the 240-S-151 Diversion Box and the 240-S-302 Catch Tank. May be a Duplicate entry - see UPR-200-W-20.

Waste Type: Process Effluent

Waste Description: The release consisted of beta/gamma particulates that spread from a contaminated piece of equipment, with readings up to 80,000 counts per minute found outside the radiation zone.

Code: UPR-200-W-99 **Classification:** Accepted

Names: UPR-200-W-99; 241-153-TX Diversion Box Contamination Spread; UN-200-W-99; UN-216-W-7 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1966

Status: Inactive **End Date:** 1/1/1966

Description: The waste site is the result of airborne contamination (in 1966) affecting the ground on both sides of Camden Ave. The area on the east of Camden Avenue, east of the 241-TX Tank Farm was stabilized with soil and grass. It is marked with "Underground Radioactive Material" signs.

Location: The release site is located east of the 241-TX Tank Farm, extending approximately 69 to 91 meters (75 to 100 yards) east of Camden Avenue.

Release Description: UPR-200-W-99 occurred on September 21, 1966. Two plumes of airborne contamination from the 241-TX-153 Diversion Box floated northeast and southeast. The releases contaminated the ground and road on both sides of Camden Avenue. The total length of contamination was identified to be 228 meters (750 feet) north and south along Camden Ave. The contamination extended a maximum of 91 meters (300 feet) east of Camden Ave. The maximum contamination found was 700 millirem per hour.

Related Sites/ Structures: UPR-200-W-99 was associated with the 241-TX-153 Diversion Box and Camden Avenue.

Waste Type: Process Effluent

Waste Description: Airborne particulates containing approximately 1 curie of strontium-90, with maximum readings of up to 700 millirads/hour, contaminated a large area around the diversion box.

Code: UPR-200-W-101 **Classification:** Accepted

Names: UPR-200-W-101; 221-U Acid Spill R-1 Through R-9; UN-200-W-101; UN-216-W-9 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1957

Status: Inactive **End Date:** 1/1/1957

Description: The UPR-200-W-101 release site was posted with "Surface Contamination" warning signs. The contaminated ground was covered with sand and gravel. A larger contaminated area (UPR-200-W-162), also located on the east side of 221-U, was surface stabilized in 1998. UPR-200-W-101 was located within the UPR-200-W-162 posted area. After being covered with clean material, the posting was changed to Underground Radioactive material. UPR-200-W-101 is not separately marked or posted within the area.

Location: UPR-200-W-101 occurred at the northeast end of the 221-U Building (sections R-1 through R-9) in the 200 West Area.

Release Description: UPR-200-W-101 occurred in March 1957, when reclaimed acid was spilled onto the ground at the northeast end of the 221-U Building. Approximately 1 curie of fission products was released. An area 19.8 meters (65 feet) by 27.5 meters (90 feet) was covered with 3 inches of sand and gravel after the occurrence.

Related Sites/ Structures: UPR-200-W-101 was associated with sections R-1 through R-9 of the 221-U Building and UPR-200-W-162.

Process Description: Reclaimed acid was distributed via overhead pipelines between 224-U and 211-U.

Waste Type: Chemicals

Waste Description: At the time of discharge, the reclaimed acid contained approximately one curie of strontium-90.

Code: UPR-200-W-103 **Classification:** Accepted

Names: UPR-200-W-103; 216-Z-18 Line Break; Pipe Line Leak; UN-200-W-103; UN-216-W-13 **Reclassification:** None

Type: Unplanned Release **Start Date:** 4/1/1971

Status: Inactive **End Date:** 4/1/1971

Description: The release site is posted with Underground Radioactive Material (URM) warning signs. Contamination still remains under the clean soil. A WIDS number sign has been placed inside the URM to mark the approximate release location. The pipeline waste site associated with this release is 200-W-174-PL.

Location: UPR-200-W-103 occurred within the Z Plant exclusion area, approximately 1.8 meters (6 feet) south and 3.7 meters (12 feet) west of the southwest corner of the 236-Z Building in the 200 West Area.

Release Description: In 1971, the 216-Z-18 Crib line broke near the southwest corner of the 236-Z Building. An excavation of the area uncovered gross alpha contamination in the soil.

Related Sites/ Structures: UPR-200-W-103 is associated with the 216-Z-18 Crib line (200-W-174-PL), the 234-5 Building, and the 236-Z Building.

Waste Type: Process Effluent

Waste Description: The release contained approximately 10 grams of plutonium with gross alpha contamination greater than 6,000,000 disintegrations per minute.

Code: UPR-200-W-111 **Classification:** Accepted

Names: UPR-200-W-111; Sludge Trench at 207-U; UN-216-W-21 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1960

Status: Inactive **End Date:**

Description: The site is a trench near the south wall of the 207-U South Retention Basin. The site had been posted with "Surface Contamination" signs. In 1997, contaminated soil in the vicinity of the 207-U Retention Basin was scraped and consolidated around the basin perimeter. The contaminated soil was covered with clean backfill. The radiological posting was changed to "Underground Radioactive Material."

Location: The site is approximately 3 meters (10 feet) from the concrete wall on the south side of the 207-U South Retention Basin in the 200 West Area.

Release Description: Sludge was scraped from the bottom of the south 207-U Retention Basin and placed in a narrow trench adjacent to the south wall of the basin. The sludge was covered with 1.2 meters (4 feet) of clean soil.

Related Sites/Structures: UPR-200-W-111 was associated with the 207-U South Retention Basin.

Waste Type: Sludge

Waste Description: Approximately 21 cubic meters (27 cubic yards) of sludge from the 207-U South Retention Basin was buried adjacent to the Retention Basin. Until 1972, the retention basins received steam condensate and cooling water from the 224-U Building and chemical sewer waste from the 221-U Building.

Code: UPR-200-W-112	Classification: Accepted
Names: UPR-200-W-112; Sludge Trench at 207-U; UN-216-W-22	Reclassification: None
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The site had been posted with "Surface Contamination" warning signs. In 1997, the contaminated area in the vicinity of the 207-U Retention Basin was scraped and consolidated. The area was covered with clean soil and the radiological posting was changed to "Underground Radioactive Material."

Location: The site is approximately 3 meters (10 feet) from the concrete wall on the north side of the 207-U North Retention Basin in the 200 West Area.

Release Description: Sludge was scraped from the bottom of the north 207-U Retention Basin and placed in a narrow trench adjacent to the north basin wall. The sludge was covered with 1.2 meters (4 feet) of clean soil.

Related Sites/Structures: UPR-200-W-112 was associated with the 207-U North Retention Basin.

Waste Type: Sludge

Waste Description: Approximately 21 cubic meters (27 cubic yards) of sludge from the 207-U North Retention Basin was buried adjacent to the north side of the Retention Basin. Until 1972, the retention basins received steam condensate and cooling water from the 224-U Building and chemical sewer waste from the 221-U Building.

Code: UPR-200-W-116	Classification: Accepted
Names: UPR-200-W-116; Ground Contamination North of 202-S; UN-200-W-116; UN-216-W-26	Reclassification: None
Type: Unplanned Release	Start Date: 1/1/1968
Status: Inactive	End Date: 1/1/1981

Description: The site has a light chain barricade and is posted with Underground Radioactive Material signs.

Location: The release affected an area east of the 204-S Unloading Station, north of the 202-S Building and west of the REDOX railroad cut.

Release Description: The area designated as UPR-200-W-116 in 1980 was contaminated with particulates spreading by wind from the 204-S Waste Storage Tank exhaust and the related Railroad Tanker Waste Unloading Station. Radioactive particulates traveled eastward and affected an area approximately 0.8 hectares (2 acres) in size. In 1974, ground contamination, with radioactive levels up to 20,000 counts per minute, was identified.

Related Sites/Structures: UPR-200-W-116 was associated with the 204-S Waste Storage Tank, the 204-S Railroad Tanker Waste Unloading Station, and sitecode 200-W-22 (a larger area posted as Underground Radioactive Material).

Waste Type: Chemicals

Waste Description: The release contaminated 0.81 hectares (2 acres) of land with radioactive specks from the 204-S area.

Code: UPR-200-W-117 **Classification:** Accepted

Names: UPR-200-W-117; 221-U Railroad Cut Contamination; Railroad Track Contamination; UN-200-W-117; UN-216-W-27 **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: In November 2000, a posted Soil Contamination Area was located on the railroad spur leading into the 221-U railroad cut and tunnel. Most of the posted area is the railroad track on a bed of gravel. There is an unusual patch of asphalt across a portion of the railroad track, inside the posted Soil Contamination Area. In December 2001, the area was covered with clean backfill material and downposted to an Underground Radioactive Material Area.

Location: The release site was the ground around the railroad cut northwest of the 221-U Building in the 200 West Area.

Release Description: This site is the result of contaminated liquid and particulate matter dropping from railroad cars moving equipment and waste into and out of the 221-U Facility over time.

Related Sites/Structures: UPR-200-W-117 was associated with the 221-U Building and the railroad cars servicing that facility.

Process Description: The track leads to the 221-U tunnel door. Material and equipment was transported in and out of the U Plant canyon via the tunnel entrance.

Waste Type: Chemicals

Waste Description: The contamination was primarily fission products and uranium from chemical processing operations.

Code: UPR-200-W-118 **Classification:** Accepted

Names: UPR-200-W-118; Contamination at 211-U; UN-200-W-118; UN-216-W-28 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1960

Status: Inactive **End Date:** 1/1/1972

Description: The release site consisted of the ground outside the concrete unloading station at the 211-U Tank Farm. The unplanned release site is no longer marked or posted. The area around the

211-U tanks and railroad spur has been stabilized with gravel and is posted as an Underground Radioactive Material area.

Location: UPR-200-W-118 was located on the railroad spur, northwest of the 221-U Building, adjacent to the 211-U Chemical Tank Farm.

Release Description: This contaminated area was the result of drips and spills from the reclaimed nitric acid unloading station at the 211-U Chemical Tank Farm. Wind-borne particulate matter spread to the ground surface outside the concrete unloading station, contaminating approximately 0.4 hectares (1 acre) of ground.

Related Sites/Structures: UPR-200-W-118 is associated with the 211-U and 211-UA Chemical Tank Farms.

Process Description: The Uranium Recovery Process at 224-U received uranyl nitrate from REDOX and PUREX. After the uranium was removed, the reclaimed nitric acid was stored in the 211-UA tanks. It was transferred from 224-U to 211-UA via overhead lines. The slightly radioactive nitric acid was recycled back to REDOX and PUREX. In the 1960's and 1970's it was returned to the separations facilities in railcars. It was pumped out of the 211-UA tanks into the railcars via underground lines and a pump pit. Some leakage was associated with the pumping process and caused low level radioactive contamination around the area. The reclaimed nitric acid storage was moved from 211-UA to a holding tank within the 224-U facility in the 1980's and the railcar unloading platform was abandoned. Some residual acid and waste water, contaminated above crib release limits, continued to be stored in the 211-UA tanks. All the acid and waste water was removed from the tanks prior to being transitioned to the new Environmental Restoration Contractor in 1994. Although the tanks were emptied, the acid pump pit and underground lines had not been flushed. Leaking valves and seals and residual contamination in the pump pit caused low level radioactive contamination to spread around the tanks and railcar unloading platform. The area was posted as a Contamination Area again in the early 1990's. The lines and pump pit were flushed in 1998 and the surface contamination was covered with gravel. The area was changed to an Underground Radioactive Material Area.

Waste Type: Chemicals

Waste Description: The waste consisted of radioactive reclaimed nitric acid that spilled to the soil.

Code: UPR-200-W-138 **Classification:** Accepted

Names: UPR-200-W-138; UPR-200-W-22; 221-U Vessel Vent Blower Pit French Drain; UN-200-W-138; UN-200-W-22; UN-216-W-11 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1953

Status: Inactive **End Date:** 1/1/1953

Description: The site was described as the ground near the R-3 entrance to the 221-U Building. The area has been surface stabilized and posted with Underground Radioactive Material signs within a larger area known as UPR-200-W-162. The UPR-200-W-138 Unplanned Release is not separately marked or posted.

Location: UPR-200-W-138 occurred at the northwest corner of the 221-U Building, near the R-3 entrance. It is located inside the larger, surface stabilized area, UPR-200-W-162.

Release Description: Uranyl nitrate hexahydrate (UNH) solution overflowed into the 221-U Building Vessel Vent Blower Pit, then onto the ground through the French Drain.

Related Sites/Structures: UPR-200-W-138 was associated with the 221-U Building Vessel Vent Blower Pit and the larger surface stabilized area UPR-200-W-162. It may also be associated with the 216-U-7

french drain.

Waste Type: Process Effluent

Waste Description: An estimated 140 kilograms (300 pounds) of uranium nitrate hexahydrate (UNH) solution, containing 14 kilograms (30 pounds) of uranium, was released to the ground through the French Drain. The information for this release is vague. Some documentation indicates the french drain involved was the 216-U-7, but drawing reviews indicate the blower pit is located north of 216-U-7. The blower pit drained to the 241-WR vault. If the event involved surface liquid being released, it is possible it flowed southward and could have effected the 216-U-7 drain.

Code: UPR-200-W-162 **Classification:** Accepted

Names: UPR-200-W-162; Contaminated Area on East Side of 221-U; UN-216-W-37 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1991

Status: Inactive **End Date:**

Description: The waste site was originally posted with "Surface Contamination" warning signs. The area was backfilled with clean material from the 200 Area Ash Pit in 1998. The radiological posting was changed to "Underground Radioactive Material." In 2011, after the demolition of 224-U and 224-UA, the 200-W-136 Underground Radioactive Material Area was greatly expanded. It was extended to the back side of the 221-U building. This eliminated the need for a separate radiological posting for the UPR-200-W-162 waste site.

Location: The release site is the area adjacent to and east of the 221-U Canyon Building from Section R-1 to R-19 in the 200 West Area.

Release Description: The site consists of surface radiological speck contamination.

Related Sites/Structures: UPR-200-W-162 was associated with the 221-U Canyon Building. The 200-W-136 posted area was expanded and now encompasses the area previously known as UPR-100-W-162. Also associated with UPR-200-W-101 and UPR-200-138 are located inside this larger Underground Radioactive Material Area.

Waste Type: Chemicals

Waste Description: The site consists of surface speck contamination.

Code: UPR-200-W-165 **Classification:** Accepted

Names: UPR-200-W-165; Contamination Area East of 241-S; UN-216-W-30 **Reclassification:** Interim No Action (5/12/2014)

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is no longer marked or posted. The area was Interim Stabilized, over time from 1992 through 1995. The site was evaluated and reclassified to Interim No Action in 2014.

The site had been a large area of posted Surface Contamination, located east of the 241-S Tank Farm, north of the steam line. The radiologically posted areas were scraped and the contaminated soil combined with other waste sites. The 216-S-23 and 216-S-18 waste sites

were inside the Surface Contamination Area posting. Some of the contaminated soil was placed on top of the 216-S-23 crib. Some was used to backfill the 216-S-18 depression. After collecting soil samples of the scraped area, the area was removed from radiological control in 1993.

Location: UPR-200-W-165 was located east of the 241-S, 241-SX, and 241-SY Tank Farms, west of the 216-S-9 Crib and north of the steam line.

Release Description: Radioactive surface contamination migrated from the 241-S, 241-SX, and 241-SY Tank Farms, eventually contaminating an area of approximately 4.7 hectares (11.5 acres).

Related Sites/ Structures: UPR-200-W-165 was associated with contamination migration from operational activities in the 241-S, the 241-SX, and the 241-SY Tank Farms. It was remediated in conjunction with the adjacent UPR-200-W-114 site (contaminated soil south of the steam line).

Waste Type: Chemicals

Waste Description: The waste consisted of contamination specks that migrated from the 241-S, 241-SX, and 241-SY Tank Farms.

Closure Info: Interim: This waste site Interim Stabilization began in 1992, but no Reclassification form was processed at that time. The Reclassification form was processed in 2014.

The posted radiological surface contamination was divided into three sections, based on the locations of aboveground steam lines that restricted the earth moving equipment. Areas adjacent to the 241-S, SX and SY tank farm fences were not stabilized.

The contaminated surface soil in the northern section was scraped and consolidated onto the top of the 216-S-23 crib. A layer (18 to 24 inches deep) of clean soil was placed on top to cover the contaminated soil. Approximately 5.9 acres was decontaminated. The area decontamination was completed in July 1992. The contaminated surface soil in the southern section was scraped and consolidated onto the top of the 216-S-1 & 2 and 216-S-8 cribs. Some contaminated soil was placed inside the 207 Retention basin. A layer (18 to 24 inches deep) of clean soil was placed on top to cover the contaminated soil. Approximately 11.7 was decontaminated and another 2 acres were covered with clean dirt. This area was completed in September 1992.

The soil contamination area between the steam lines was found to be greater than 1 foot deep. From December 1994 through February 1995, approximately 5000 square feet was decontaminated and the radiological posting removed. Some of the contaminated soil was consolidated on top of the 216-S-9 crib and some was placed into the 216-S-18 depression and covered with clean dirt. Construction debris was uncovered in this area. The area under the steamline remained a posted Contamination Area until the steamline was removed.

The scraped areas were revegetated with wheatgrass. Approximately 60 acres inside 241-S and SX tank farm fences were treated with a soil fixative to prevent recontamination of areas outside the fence.

Code: UPR-200-W-166 **Classification:** Accepted

Names: UPR-200-W-166; Contamination Migration from 241-T Tank Farm; UN-216-W-31 **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The site was originally defined as a large, irregularly shaped area of surface soil contamination located north and east of the 241-T Tank Farm. The areas of soil contamination have been

scraped and consolidated onto the west slope of the 216-T-14 through 216-T-17 Trenches and also into the 207-T Retention Basin. The unplanned release is no longer separately marked or posted.

Location: In 1985, the original area of soil contamination was described as being located north and east of 241-T Tank Farm, west of the 216-T-14 through 216-T-17 Trenches and surrounding the 207-T Retention Basin. In 1996, additional soil contamination was found east of the 207-T Retention Basin and was also considered to be UPR-200-W-166.

Release Description: The site consisted of spotty contamination which is suspected to have originated from 241-T Tank Farm.

Related Sites/Structures: UPR-200-W-166 was associated with the 216-T-14 through 216-T-17 Trenches, 241-T Tank Farm, the 207-T Retention Basin and 200-W-53.

Process Description: Contamination in the soil surrounding the exterior of the 241-T Tank Farm and the 207-T Retention Basin ranged from 25,000 to 250,000 disintegration per minute. The source of the contamination is suspected to be years of operating activities in the tank farm and dried particles blowing out of the retention basin.

Waste Type: Soil

Waste Description: The waste consisted of spotty contamination which is suspected to have originated from the 241-T Tank Farm.

300-FF-1

Code: 300 ASH PITS **Classification:** Accepted
Names: 300 ASH PITS; 300 Area Ash Pits; 300 Ash Pits **Reclassification:** Final Closed Out (12/17/1997)
Type: Coal Ash Pit **Start Date:** 1/1/1944
Status: Inactive **End Date:** 1/1/1994

Description: In 1997, samples collected from test pits determined no further action was required. The unit consisted of two separate excavations that are 4.6 to 6.1 meters (15 to 20 feet) deep and 7,400 square meters (80,000 square feet) in area.

Location: The site is located in the 300 Area, south of the 316-1 Process Pond and west of the 300 Area Filter Backwash Pond (300 FBP).

Process Description: The 300 Area coal-fired power house generated coal ash starting in about 1944. The ash was suspended in a water slurry and sluiced to the South Process Pond (SPP) until 1951. When the coal fly ash was dry, it was hauled to several locations, including these disposal pit located west of the 300 Area. These pits received about 56,000,000 liters per year (15,000,000 gallons per year) of fly ash slurry during operations.

Waste Type: Ash

Waste Description: Coal fly ash was periodically sluiced from the 384 Powerhouse to the pits with water at the rate of 57 million liters/year (15 million gallons/year). Analysis of the fly ash according to 173-303 WAC indicated it was non-Extraction Procedure toxic. Filter backwash water was diverted to the east ash pit from 1992 to June 1995 to allow for the construction of a liner in the filter backwash pond and resolution of permitting issues.

Closure Info: Final: During the 300-FF-1 Phase 1 remedial investigations (RI), samples of ash showed that metals concentrations were below cleanup standards. However, the ash pits were constructed in an area that at one time was part of the South Process Pond (SPP). The Remedial Investigation did not collect samples from soils below the ash pit sediments that could contain contaminants from the SPP. Therefore, the 300-FF-1 Record of Decision required remedial action at the ash pits to verify no contaminants below the ash pits remained from previous SPP operations.

Six sample test pit locations were randomly identified at the ash pits. Samples were taken below the ash pit sediments, at a depth about 4.6 meters (15 feet) below surface grade. Field screening was performed at about 0.3 meter (1 foot) intervals in the ash, but did not identify any contaminants of concern above the cleanup levels. Samples were collected in August 1997 at a depth below the layers of ash, and the pits backfilled. Field screening did not identify any contaminants of concern. The sample results indicated no further action was required.

Code: 300 FBP **Classification:** Accepted
Names: 300 FBP; 300 Area Filter Backwash Pond **Reclassification:** Final No Action (11/7/2000)
Type: Surface Impoundment **Start Date:** 1/1/1987
Status: Inactive **End Date:** 1/1/1998

Description: This site has been reclassified as "No Action." The unit consists of two subsites; one is a single, rubber lined basin measuring 97.5 meters (320 feet) by 65 meters (213 feet), 7.6 meters (25 feet) deep. From 1987 to 1992, the basin operated as an unlined percolation pond, which is the second subsite. In 1992, the basin was lined with a synthetic liner on a concrete foundation.

Location: The site is located north of the 338 Building and east of the 300 Area Ash Pits, near the banks

of the Columbia River. The basin is enclosed by a locked chain link fence.

Related Sites/ Structures: The site is associated with the 384 Powerhouse and the 300 Area Treated Effluent Disposal Facility (TEDF).

Process Description: Before the pond was lined, filter backwash was discharged to it and allowed to percolate to groundwater. After 1995, the backwash was held in the lined pond to clarify. The clarified water was sent to the 300 Area TEDF (Treated Effluent Disposal Facility). The Hanford Site Waste Management Units Report reports that the unit received water and nonhazardous alum from backwash filters used to filter water for sanitary and process use. Analysis of the backwash showed it to be nonhazardous. The accumulated sediment in the ponds is not regulated and could be disposed of in a landfill.

Waste Type: Water

Waste Description: The unit receives 76 million liters/year (20 million gallons/year) of water and alum backwashed from filters. Analysis of the backwash has shown it to be nonhazardous.

This Site has the Following SubSites:

Code: 300 FBP:1

Names: 300 FBP:1; 300 FBP (Unlined)

Code: 300 FBP:2

Names: 300 FBP:2; 300 FBP (Lined)

Code: 300 FBP:1

Names: 300 FBP:1; 300 FBP (Unlined)

Type: Surface Impoundment

Status: Inactive

Classification: Accepted

Reclassification: Final No Action (2/19/1998)

Start Date:

End Date:

Description: The subsite represents the unlined pond that operated from 1987 to 1992. This component of the 300 FBP is included as a "no action" site within the 300-FF-1/300-FF-5 Record of Decision.

Closure Info: Final: No remediation was performed.

The SubSite is Part Of:

Code: 300 FBP

Names: 300 FBP; 300 Area Filter Backwash Pond

Code: 300 FBP:2

Names: 300 FBP:2; 300 FBP (Lined)

Type: Surface Impoundment

Status: Inactive

Classification: Accepted

Reclassification: Final No Action (11/7/2000)

Start Date:

End Date:

Description: This subsite is the lined filter backwash pond. This site is not addressed within the 300-FF-1/300-FF-5 Record of Decision.

Closure Info: Final: No remediation was performed.

The SubSite is Part Of:

Code: 300 FBP
Names: 300 FBP; 300 Area Filter Backwash Pond

Code: 300 RFBP **Classification:** Accepted
Names: 300 RFBP; East Bay of South Process Pond; **Reclassification** Final Closed Out (7/23/2003)
 Pond 5; 300 Area Retired Filter Backwash Pond
Type: Pond **Start Date:** 1/1/1975
Status: Inactive **End Date:** 1/1/1987

Description: The site has been remediated and closed out. When the South Process Pond became inactive in 1975, the east lobe started to be used by the 300 Area Water Treatment Facility as a filter backwash pond.

Location: The unit was located west of the 300 Area, in the east lobe of the 300 Area South Pond.

Related Sites/ Structures: This site was associated with the South Pond (316-1); the Contaminated Soil West of the South Process Pond (300-262); and unplanned release (UPR) sites UPR 300-32, UPR-300-33, UPR-300-34, UPR-300-35, UPR-300-36, UPR-300-37, and UPR-300-FF-1.

Process Description: The 300 RFBP and the 316-1 South Process Pond, collectively referred to as the 316-1 South Process Pond site, are the site of former high-volume liquid waste disposal activities located north of the 300 Area complex, near the Columbia River. The easternmost boundary of the 316-1 South Process Pond is approximately 49 meters (160 feet) west of the shoreline of the Columbia River. The 316-1 South Process Pond site was built in 1943 and was the first 300 Area process liquid disposal unit. It was originally a single, large infiltration pond to which dikes were later added, forming three settling ponds and a large main infiltration pond. The east lobe of the site was used by the 300 Area water treatment plant as a filter backwash pond (WIDS site 300 RFBP). Combined process wastes discharged from the fuel fabrication facilities to the South and North Process Ponds ranged from 1,514,000 to 11,360,000 liters/day (400,000 to 3,000,000 gallons/day). During their operational life, the process ponds received thousands of kilograms of uranium as dissolved material and finely divided solids. Much of the uranium was carried with the infiltration water, but some remained in the pond soils. Discharging of waste to the process ponds ended in 1975.

Waste Type: Process Effluent

Waste Description: The unit received 3.8E+07 to 7.6E+07 liters/year (1E+07 to 2E+07 gallons/year) of water and nonhazardous alum from backwashing filters. Analysis of the backwash has shown it to be nonhazardous.

Closure Info: Interim (7/23/2003): Remediation activities at the 316-1 South Process Pond site began in 1997 with excavating trenches around the periphery of the 316-1 site. Trenching was performed to assess the lateral extent of contamination. The majority of remedial excavation and disposal activities were conducted in 1999 and 2000. Excavation at the site involved removing the overburden (scraped surface) soils and contaminated soils. The contaminated soil was transported to the ERDF for disposal. Based on field screening, overburden materials and comingled soil identified as potentially clean were placed in stockpiles for potential use as backfill. Soil samples were collected adjacent to utility poles located in the 316-1 site. Where these samples indicated contaminant concentrations above the cleanup criteria, the soil was removed and the area immediately backfilled and compacted with clean material to maintain the integrity of the utility pole. Excavation and disposal of the 316-1 South Process Pond remediation waste was completed in June 2000. The filter backwash pond (WIDS site 300 RFBP) was a lobe on east side of the process pond. During remediation, soil was primarily removed from the area on the west side of the process pond, near the pond inlet. The two north-south parallel soil berms inside the pond were removed. Areas to the south and west of the

original pond boundaries were also removed during remediation. The general elevation at the bottom of the excavation used for analysis was 111.3 meters (365 ft) upon completion. The excavation depth was approximately 5.7 meters (19 ft).

Code: 300-3 **Classification:** Accepted

Names: 300-3; 300-FF-1 Aluminum Hydroxide **Reclassification:** Final No Action (7/17/1996)

Type: Burial Ground **Start Date:**

Status: Inactive **End Date:**

Description: The waste site was investigated and determined to require No Action per the 1996 Record of Decision for 300-FF-1. It was a wooden structure consisting of several horizontal (0.30 to 0.46 meters [1 to 1.5 ft] diameter) cedar logs forming a vertical wall. The structure contained a white, chalky substance.

Location: This site is about 100 meters (330 feet) northwest of the 316-1 South Process Pond.

Process Description: Photos from 1956 indicate the site was possibly used to receive sodium aluminate/aluminum hydroxide scrapings from the South and North Process Ponds.

Waste Type: Chemicals

Waste Description: Sample analysis of the white, chalky material was consistent with aluminum hydroxide, or hydrous aluminum oxide, but the uranium levels were very small. Uranium content for one sample was 58 picocuries/gram and another was 30 picocuries/gram. Uranium concentrations in pond scrapings are usually higher.

Closure Info: Final: The structure was investigated by the site historical group. Photos from 1956 indicate the site was possibly used to receive sodium aluminate/aluminum hydroxide scrapings from the South and North Process Ponds. The white chalky substance was sampled and analyzed in October 1993.

According to page 50 of the Declaration of the Record of Decision for the 300-FF-1 and 300-FF-5 Operable Units (1996 DOE Document Number 038509), remedial action is not needed at the 300-3 Aluminum Hydroxide Site. Regulator concurrence with supporting documentation eliminates the need for signatures on the Reclassification form.

Code: 300-44 **Classification:** Accepted

Names: 300-44; R-32; UN-300-FF-1; UPR-300-FF-1 **Reclassification:** Final Closed Out (12/17/1997)

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: This site was located southwest of 618-4 Burial ground. It has been remediated and was closed out in 1997. It had been a posted Underground Radiological Material Area.

Location: The site was near the southwest end of the 618-4 Burial Ground. The surface area was derived from a Global Position Survey (GPS) of the site boundary.

Related Sites/ Structures: The site is associated with WIDS sitecode UPR-300-FF-1.

Waste Type: Soil

Waste Description: The soil contamination appears to be the result of shallow buried materials.

Closure Info: Final: The waste site was approximately 159 square meters (1711 sq. ft). A layer of overburden ranging in depth from 0.3 to 0.9 meters (1 to 3 feet) was removed prior to the excavation and stockpiled. Only an additional 0.3 meters (1 foot) was removed to complete the excavation, based on radiological surveys. Contaminated soil was disposed at the Environmental Restoration Disposal Facility. Four verification samples were collected; two from the bottom of the excavation and two from the stockpiled overburden. The samples were analyzed for 300-FF-1 Operable Unit contaminants of concern.

Code: 300-49

Classification: Accepted

Names: 300-49; Landfill 1a; UN-300-FF-1; UPR-300-FF-1

Reclassification: Final Closed Out (5/28/2003)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site has been remediated and closed out in July 1999. It was a large, rectangular area with visible debris on the surface and areas of subsidence. After excavation and closure activities the area was included in the 2004, 300-FF-1 Regrading Plan.

Location: The site was located southeast of 618-5 Burial Ground, near the Columbia River bank.

Related Sites/ Structures: The site was associated with WIDS sitecode UPR-300-FF-1.

Waste Type: Misc. Trash and Debris

Waste Description: Material visible on the surface included empty acid and mercury bottles, ceramics, and other glassware that appeared to be of laboratory origin, metal, and a partially buried 208-liter (55-gallon) drum. Materials that are radiologically contaminated include soil, tumbleweeds, pipes, ceramics, glass, and a small amount of yellow material that resembles "yellow cake" (a complex uranium compound, the product of chemically refining natural uranium).

Closure Info: Interim: The cleanup verification package (CVP-2000-00020) has documented that the 300-49 site has achieved the remedial action objectives (RAOs) and corresponding remedial action goals (RAGs) as established in the Final Record of Decision for the 300-FF-1 and 300-FF-5 Operable Units (ROD) (EPA 1996) and the Remedial Design Report/Remedial Action Work Plan for the 300 Area (RDR/RAWP) (DOE RL-96-70).

Site contaminants of concern (COCs) and contaminants of potential concern (COPCs) identified in the 300-FF-1 Remedial Design Report/Remedial Action Work Plan (1997 RDR/RAWP) consisted of the following: cobalt-60, uranium-234, uranium-235, uranium-238, polychlorinated biphenyls (PCBs). COPC's: arsenic, thallium, benzo(a)pyrene, chrysene. Of the PCBs analyzed, only Aroclor-1254 was detected in cleanup verification samples and was therefore evaluated as a site COC.

The COPC arsenic was not detected in cleanup verification samples at concentrations above Washington State background of 20 mg/kg (Washington Administrative Code 173-340) (the maximum detected value was 5.5 mg/kg) and is therefore not included as a COC in the evaluation of the site for cleanup verification. The COPCs thallium and the two polynuclear aromatic hydrocarbons (benzo[a]pyrene and chrysene) were not detected in cleanup verification samples at the detection limits specified in the RDR/RAWP and are therefore not included as COCs in evaluation of the site for cleanup verification.

An additional contaminant (lead) was identified from analysis of material excavated during remediation and evaluated as a site COPC. Lead was detected at levels above Hanford Site background of 10.2 mg/kg in cleanup verification samples and is therefore evaluated as an additional site COC for cleanup verification of the Landfill 1A site.

Landfill 1A (300-49) and Landfill 1B (300-50) have been surface stabilized.

Cleanup verification samples were taken on June 28, 2000. The site excavation and overburden soil sample data were recorded in HEIS as SAF B00-037.

At the completion of the remedial action, the total excavation was approximately 6,906 square meters (74,340 square feet) in area with a maximum depth of approximately 3 meters (10 feet). Approximately 17,761 metric tons (19,578 tons) of material from the site were disposed at the Environmental Restoration Disposal Facility. All visible debris was removed from the Landfill 1A site, and the site was excavated to native soil. An additional 5,644 metric tons (6,221 tons) of material (overburden) identified as potentially clean was stockpiled at the site for potential use as backfill.

Results of the sampling, laboratory analysis, and data evaluations of the Landfill 1A site indicate that all remedial action objectives and goals for direct exposure, protection of groundwater, and protection of Columbia River have been met.

Code:	300-50	Classification:	Accepted
Names:	300-50; Landfill 1b; UN-300-FF-1; UPR-300-FF-1	Reclassification	Final Closed Out (5/29/2003)
Type:	Dumping Area	Start Date:	
Status:	Inactive	End Date:	
Description:	The site was remediated in 2000 and closed out in 2003.		
	The site was an area of surface disturbance. After excavation and closure activities were completed the area was included in the 2004, 300-FF-1 Regrading Plan.		
Location:	The site was located directly south of 618-5. It was bounded on the south by the north perimeter fence of the North Process Pond (316-2), and on the west by the east perimeter fence of the Process Trenches (316-5).		
Related Sites/ Structures:	The site was associated with WIDS sitecode UPR-300-FF-1 and 300-49 (Landfill 1a).		
Waste Type:	Misc. Trash and Debris		
Waste Description:	A large number of discrete objects were detected by ground penetrating radar.		
Closure Info:	Interim: Remedial action objectives for the Landfill 1B site were established by the U.S. Environmental Protection Agency (EPA) and the U.S. Department of Energy, Richland Operations Office, in concurrence with the Washington State Department of Ecology. These objectives are documented in the Record of Decision for the 300-FF-1 and 300-FF-5 Operable Units (ROD) (EPA, 1996) and the 300-FF-1 Remedial Design Report/Remedial Action Work Plan (1997 RDR/RAWP) (DOE/RL96-70).		
	The selected remedial action for the Landfill 1B site included excavation to the extent required to meet specified soil cleanup levels and disposal of contaminated excavation materials at the		

Environmental Restoration Disposal Facility. The remedial action also included the removal and disposal of solid waste and all construction debris. Excavation was driven by remedial action objectives for direct exposure, protection of groundwater, and protection of the Columbia River. For the respective points of compliance, remedial action goals (RAGs) were established in the 1997 RDR/RAWP and updated in the Remedial Design Report/Remedial Action Work Plan for the 300 Area (2002 RDR/RAWP) (DOE/RL-2001-47). Waste site contaminants of concern (COCs) and contaminants of potential concern (COPCs) identified from knowledge of the processes used in the 300 Area and previous 300-FF-1 Operable Unit investigations were listed in Table 2-1 of the 1997 RDR/RAWP.

Site excavation and waste disposal are complete, and the exposed surfaces have been sampled and analyzed to verify attainment of the RAGs. At the completion of remedial action, the total excavation was approximately 10,498 square meters (113,000 square feet) in area with a maximum depth of approximately 3.1 meters (10 feet). Approximately 35,652 metric tons (39,300 tons) of material from the site were disposed at the Environmental Restoration Disposal Facility. All visible debris was removed from the Landfill 1B site, and the site was excavated to native soil. Overburden material identified as potentially clean was stockpiled at the site for potential use as backfill at this waste site.

The results of the sampling, laboratory analysis, and data evaluations of the Landfill 1B site indicate that all remedial action objectives and goals for direct exposure, protection of groundwater, and protection of Columbia River have been met.

Cleanup verification samples were collected from the excavation and overburden soil and analyzed for the established contaminants of concern. The excavation soil sample were collected on July 5, 2000. The overburden soil samples were collected on June 28, 2000. The sample results can be located on the HEIS database under the SAF number B00-038.

The CVP demonstrates that remedial action at the Landfill 1B site has achieved the RAOs and corresponding RAGs established in the approved ROD, the 1997 RDR/RAWP, and the 2002 RDR/RAWP. The remaining soils at the Landfill 1B site have been sampled, analyzed, and modeled. The results of this effort indicate that the materials from the Landfill 1B site containing COCs at concentrations exceeding RAGs have been excavated and disposed of at the ERDF. These results also indicate that residual concentrations in remaining site soil will support future land uses that can be represented (or bounded) by the industrial land-use scenario, and that residual concentrations throughout the site are protective of groundwater and the Columbia River. The CVP demonstrates acceptability for industrial land use; therefore, institutional controls limiting land use to industrial are required. Institutional controls preventing uncontrolled drilling or excavating are also required. The Landfill 1B site is verified to be remediated in accordance with the ROD and may be backfilled.

Code: 300-51	Classification: Accepted
Names: 300-51; Landfill 1c; UN-300-FF-1; UPR-300-FF-1	Reclassification: Final No Action (7/17/1996)
Type: Dumping Area	Start Date:
Status: Inactive	End Date:
Description: The waste site was Closed Out per the 300-FF-1 Record of Decision. The debris has been removed. The site is no longer marked or posted.	
Location: The site is located at a small point of land directly east of the northeast corner of 316-2 (North Process Pond).	

Related Sites/ Structures: The site is associated with WIDS sitecode UPR-300-FF-1.

Waste Type: Misc. Trash and Debris

Waste Description: The site contained radiologically contaminated surface debris.

Closure Info: Final: The debris at Landfill 1C (300-51) has been removed. Geophysical surveys did not find any anomalies. This site was formerly part of UPR-300-FF-1.

According to page 50 of the Declaration of the Record of Decision for the 300-FF-1 and 300-FF-5 Operable Units (1996 DOE Document Number 038509), remedial action is not needed at Landfill 1c.

Code: 300-52

Classification: Accepted

Names: 300-52; 300 Area Sanitary Trenches

Reclassification: Final No Action (7/17/1996)

Type: Trench

Start Date: 1/1/1948

Status: Inactive

End Date: 1/1/1996

Description: The waste site was reclassified to No Action per the 300-FF-1 Record of Decision in 1996. 300 Area Sanitary Trenches site includes two septic tanks and unlined trenches that were connected to the 300 Area Sanitary Sewer System (sitecode 300 SSS).

Location: The Sanitary Trenches are located north of the 316-1 Process Pond and south of the North Process Pond Scraping Disposal Area (618-12).

Process Description: While in operation, the site received sanitary waste from throughout the 300 Area and small discharges of chemical waste from the 3713 Sign Shop. On October 1, 1996 the 300 Area Sanitary Sewer System began to discharge to the City of Richland's sewage system. The pipeline to the 300 Area Sanitary Trenches was permanently isolated by welding a plate in place and filling manhole #6 with concrete.

Waste Type: Sanitary Sewage

Waste Description: The trenches received sanitary waste from 300 Area facilities.

Waste Type: Chemicals

Waste Description: Prior to 1985, discharges from the 3713 Sign Shop included an estimated 1 gallon (3.8 liters) per week of miscellaneous photochemicals used in the process. The trench has also received trace nonhazardous concentrations of carry over fixers, developers, inks, thinners, and solvents from sign developing operations and silkscreen cleaning.

Closure Info: Final: The effluent pipes to the trenches were isolated (blanked and manhole #6 filled with concrete) in October 1996. Prior to being backfilled in 1999 surface debris (fencing and fence posts) was pushed into the trenches.

According to page 50 of the Declaration of the Record of Decision for the 300-FF-1 and 300-FF-5 Operable Units (1996 DOE Document Number 038509), remedial action is not necessary at sanitary sewage waste sites identified within the ROD.

Code: 316-1

Classification: Accepted

Names: 316-1; South (Old) Pond; 300 Area South Process Pond **Reclassification** Final Closed Out (7/23/2003)

Type: Pond **Start Date:** 1/1/1943

Status: Inactive **End Date:** 5/1/1975

Description: The site has been remediated and Closed Out. Approximately 47, 600 square meters (512, 000 sq. ft) of soil was excavated, to a depth of approximately 18 feet below ground surface.

The site is no longer marked or posted. The pond was a 32,000 square meter (8-acre), unlined infiltration pond containing five separate pond sections. Ponds 1, 2, and 3 were separated by two 9.1-meter (30-foot) dikes. Pond 4, the largest pond, was separated from Ponds 1, 2, and 3 to the west by a 4.9-meter (16-foot) dike and from Pond 5 to the east by 3.1 meters (100 feet) of land. The dikes were bulldozed into three sections, and the fill was used to cover loose material.

Location: The unit was located east of the 306 Building and west of the Columbia River.

Related Sites/ Structures: This site was associated with Retired Filter Backwash Pond (300 RFBP); the Contaminated Soil West of the South Process Pond (300-262); and unplanned release (UPR) sites UPR 300-32, UPR-300-33, UPR-300-34, UPR-300-35, UPR-300-36, UPR-300-37, and UPR-300-FF-1.

Process Description: The 316-1 South Process Pond and 300 RFBP sites, collectively referred to as the 316-1 South Process Pond site, are the site of former high-volume liquid waste disposal activities located north of the 300 Area complex, near the Columbia River. The easternmost boundary of the 316-1 South Process Pond is approximately 49 meters (160 feet) west of the shoreline of the Columbia River. The 316-1 South Process Pond site was built in 1943 and was the first 300 Area process liquid disposal unit. It was originally a single, large infiltration pond to which dikes were later added, forming three settling ponds and a large main infiltration pond. The east lobe of the site was used by the 300 Area water treatment plant as a filter backwash pond (WIDS site 300 RFBP). Combined process wastes discharged from the fuel fabrication facilities to the South and North Process Ponds ranged from 1,514,000 to 11,360,000 liters/day (400,000 to 3,000,000 gallons/day). During their operational life, the process ponds received thousands of kilograms of uranium as dissolved material and finely divided solids. Much of the uranium was carried with the infiltration water, but some remained in the pond soils. Discharging of waste to the process ponds ended in 1975.

Waste Type: Process Effluent

Waste Description: The site originally received cooling water and low-level liquid wastes from the fuel fabrication facilities and early laboratories (313, 314, 3706 and 321 Buildings). Contaminants from these facilities included uranium, copper cobalt and small amounts of plutonium. Later, laboratory facility wastes went first to the 307 Retention Basins. Waste above discharge limits was diverted to holding tanks for disposal in the 200 Areas. The process ponds received waste via the 307 Retention Basins from 1963 to 1975.

Due to remedial activities, the uranium inventory at this site has been reduced. According to Mike Schwab (2000), an estimated 40,000 kilograms of uranium contained in soil was scraped from the pond and transported to the Environmental Restoration Disposal Facility (ERDF), near 200 West Area.

Closure Info: Interim (7/23/2003): Remediation activities at the 316-1 South Process Pond site began in 1997 with excavating trenches around the periphery of the 316-1 site. Trenching was performed to assess the lateral extent of contamination. The majority of remedial excavation and disposal activities were conducted in 1999 and 2000. Excavation at the site involved removing the overburden (scraped surface) soils and contaminated soils. The contaminated soil was transported to the ERDF for disposal. Based on field screening, overburden materials and comingled soil identified as potentially clean were placed in stockpiles for potential use as

backfill. Soil samples were collected adjacent to utility poles located in the 316-1 site. Where these samples indicated contaminant concentrations above the cleanup criteria, the soil was removed and the area immediately backfilled and compacted with clean material to maintain the integrity of the utility pole. Excavation and disposal of the 316-1 South Process Pond remediation waste was completed in June 2000. The filter backwash pond (WIDS site 300 RFBP) was a lobe on east side of the process pond. During remediation, soil was primarily removed from the area on the west side of the process pond, near the pond inlet. The two north-south parallel soil berms inside the pond were removed. Areas to the south and west of the original pond boundaries were also removed during remediation. The general elevation at the bottom of the excavation used for analysis was 111.3 meters (365 ft) upon completion. The excavation depth was approximately 5.7 meters (19 ft).

Code:	316-2	Classification:	Accepted
Names:	316-2; North (New) Pond; 300 Area North Process Pond	Reclassification	Final Closed Out (8/24/1999)
Type:	Pond	Start Date:	1/1/1948
Status:	Inactive	End Date:	5/1/1974
Description:	The site was remediated and closed out in 1999. This site consisted of seven separate sections separated by 3.7-meter (12-foot) wide dikes. The whole pond was a 40,000-square meter (10-acre) area, surrounded by a dike 4.6 meters (15 feet) wide and approximately 3.0 meters (10 feet) high. The radiological posted was removed. The pond is no longer marked or posted.		
Location:	The unit was located northeast of the 306 Building and north of the 316-1 Pond.		
Related Sites/Structures:	Associated structures include: five 86-centimeter (34-inch) diameter by 7.3-meter (24-foot) long flumes. Two were filled with an unknown material and abandoned.		
Process Description:	The North Process Pond was constructed and activated in 1948, following a dike failure at the existing South Process Pond. Both ponds operated until 1975, when the units were replaced by the 300 Area Process Trenches (WIDS site 316-5). The site originally received cooling water and low-level liquid process waste from 300 Area fuel fabrication facilities and the early laboratory facilities in the 313, 314, 3706, and 321 Buildings. Later, laboratory facility waste was first routed to the 307 Retention Basins. Waste that was above discharge limits was diverted to holding tanks for shipment and disposal in the Hanford Site 200 Area. The North and South Process Ponds received laboratory waste via the 307 Retention Basins from 1963 to 1975. There was no effluent outlet from the North Process Pond. All of the effluent either infiltrated the soil column or evaporated. Lack of infiltration was a problem for the pond. Between 1948 and 1969, the basins were periodically dredged to improve infiltration when sludge in the bottom of the pond slowed the percolation rate. The sludge contained large amounts of uranium and copper and was deposited on the pond dikes and put in the Scraping Disposal Area or put into Landfill 1B (WIDS site 300-50) just north of the pond. During operation, there were several unplanned releases to the North Process Pond.		
Waste Type:	Process Effluent		
Waste Description:	The site originally received cooling water and low-level liquid process wastes from the fuel fabrication facilities and the early laboratories (313, 314, 3706 and 321 Buildings). Later, laboratory facility wastes went first to the 307 Retention Basins. Waste above discharge limits was diverted to holding tanks for disposal in the 200 Areas. The process ponds received laboratory waste via the 307 Retention Basins from 1963 to 1975.		
	Due to remedial activities, the uranium inventory at this site has been removed. According to Mike Schwab (2000), an estimated 30,000 kilograms of uranium contained in soil was scraped		

from the pond and transported to the Environmental Restoration Disposal Facility (ERDF), near 200 West Area.

Closure Info: Final (8/24/1999): Remediation activities were initiated in May 1998 and continued into January 1999. On January 25, 1999 a decision was made to suspend excavation activities at the North Process Pond and mobilize work crews to the South Process Pond pending resolution of contractual issues with the remedial action subcontractor. Work crews remobilized to the North Process Pond and completed excavation activities in June 1999.

Based on data collected during the remedial investigation, the pond was divided into the Above Cleanup Level (ACL), Below Cleanup Level (BCL), and Undetermined Contamination Level (UCL) areas prior to excavation. The UCL area included the Scraping Disposal Area (sitecode 618-12). Four UPRs associated with the north pond were also associated with the south pond. UPR-300-34, UPR-300-35, UPR-300-36 and UPR-300-37 were addressed with the South Pond remediation (316-1). UPR-300-7 was closed out with the North Pond (316-2).

Code: 316-5	Classification: Accepted
Names: 316-5; 3904 Process Waste Trenches; 300 APT; 300 Area Process Trenches	Reclassification: Final Closed Out (8/13/1998)
Type: Trench	Start Date: 1/1/1975
Status: Inactive	End Date: 1/1/1994

Description: The site has been remediated and Closed Out. The site is no longer marked or posted. Sample analysis found the north end of the process trenches to be contaminated above cleanup levels. This area was excavated. The southern portion of the trenches were below cleanup levels. No soil excavation was required in this area. The maximum excavation depth was 14 feet deep. The site was partly remediated through an expedited response action (ERA) in 1991. Remediation was completed in 1997. The site was clean closed through RCRA and closed out under CERCLA regulations.

Location: The unit is located north of the 300 Area.

Release Description: Sixteen unplanned releases are associated with this site: UPR-300-8, UPR-300-9, UPR-300-15, UPR-300-19, UPR-300-20, UPR-300-21, UPR-300-22, UPR-300-23, UPR-300-24, UPR-300-25, UPR-300-26, UPR-300-27, UPR-300-28, UPR-300-29, UPR-300-30, and UPR-300-47. These sites were closed out when the cleanup verification package for the Process Trenches was approved.

Waste Type: Process Effluent

Waste Description: This unit served as the discharge site for the 300 Area Process Sewer system. The site received approximately 9.8E+06 liters (2.6E+06 gallons) of water per day. This water was chlorinated by the water filter plant for the 300 Area and contained minerals added to the water during use. Water discharged to the process sewer is used primarily for cooling purposes and is not modified. Other sources of discharge include steam condensates, janitorial solutions from washing and waxing floors, water treatment (primarily salt), laboratories, process water from fuel fabrication and other aqueous solutions not designated as dangerous wastes by WAC-173-303. The annual waste quantity is 4.5E+08 kilograms (1E+09 pounds) per year and reflects the total flow to the unit, not a volume of dangerous waste discharged to the unit. No dangerous wastes have been discharged to the unit since November 1985. All discharge to the trenches was discontinued on December 29, 1995. Discharges after that date are sent to the 300 Area Treated Effluent Disposal Facility.

Closure Info: Final (8/13/1998): CERCLA remediation activities were initiated in July 1997 and completed in February 1998. Remediation of the 300 Area Process Trenches included removal and disposal

of bird screens covering the trenches, demolition and disposal of the headworks structure located at the southern end of the trenches, demolition and disposal of the blockhouse structure, and excavation and disposal of contaminated soil that accounted for several unplanned release waste sites.

In 1991, an expedited response action (ERA) was performed to reduce the migration of radioactive and inorganic (heavy metals) contaminants to groundwater. This was accomplished by excavating contaminated sediments in the south end of the trenches, using them to fill in the north end of the trenches, and immobilizing them. The ERA uniformly excavated approximately 0.3 meters (1ft) and 1.3 meters (4 ft) of contaminated soil from the sides and bottom of each trench, respectively. The contaminated material was stockpiled in the northwest corner of the west trench and the north end of the east trench (referred to as a spoils area). Based on process history, the Part A submitted by the U.S. Department of Energy, Richland Operations Office (DOE-RL) assigned several listed waste codes to the ERA spoils pile. The spoils area was covered with plastic and aggregate to allow continued operation of the trenches without flushing residual contaminants into the groundwater. Post-excavation sample results indicated that the ERA successfully reduced contamination in all areas of the trenches, other than the spoils area.

RCRA closure of the process trenches was performed in accordance with the 300 Area Process Trenches Modified Closure Post Closure Plan (DOE-RL 1995). An independent registered professional engineer was tasked to review the 300-FF-1 remedial action activities to ensure that the TSD closure met the WAC 173-303-610 performance standards. The permit was closed with post-closure requirements.

Code: 618-4	Classification: Accepted
Names: 618-4; Burial Ground No. 4; 318-4	Reclassification: Final Closed Out (7/12/2004)
Type: Burial Ground	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1961
Description:	The site has been remediated and Interim Closed Out. The waste site was a solid waste disposal pit.
Location:	The burial ground was located approximately 0.5 kilometers (1/3 mile) north of the 300 Area northern boundary fence.
Related Sites/ Structures:	This site was associated with UPR-600-15.
Process Description:	The site received dry waste from the 300 Area operations.
Waste Type:	Misc. Trash and Debris
Waste Description:	The site contains an unknown quantity of uranium-contaminated miscellaneous materials. During remedial activities, drums of depleted uranium packed in oil were uncovered. The presence of these drums was not previously known, therefore, the documented uranium inventory for this burial ground did not include these (estimated to be up to 1500) barrels of depleted uranium. The inventory contained in the drums has been estimated to be 110,600 kilograms (243,800 pounds) (Schwab 2000).
Waste Type:	Barrels/Drums/Buckets/Cans
Waste Description:	In 1998, drums of unknown material were uncovered during remedial action activities. It is suspected the drums contain depleted uranium filings and mineral oil.

Closure Info: Interim: Excavation activities were performed in two phases, between 1998 and 2003. At the completion of field operations in 2003, the total excavation was approximately 7,342.6 square meters (79,043 square feet) in area with a maximum depth of approximately 11 meters (36 feet) below the surrounding grade. Approximately 46,585 metric tons (51,360 tons) of bulk soil and debris were excavated from the site and disposed of at ERDF. In addition, 786 drums containing depleted uranium waste were excavated from this site and transported to ERDF for interim staging and/or disposal. 266 drums containing depleted uranium oxide were grouted and disposed of at ERDF. In September 2003, 520 drums containing depleted uranium chips immersed in polychlorinated biphenyl-contaminated oil were transported from the ERDF staging area to Perma-Fix in Oak Ridge, Tennessee, for treatment. Overburden material and excavated soil identified as potentially clean were stockpiled at the site for subsequent use as backfill material.

Excavation operations were driven by remedial action objectives for removal of the burial ground contents as well as direct exposure limits, protection of groundwater, and protection of the Columbia River. For the respective points of compliance, remedial action goals were established in the 300-FF-1 Remedial Design Report/Remedial Action Work Plan (DOE-RL 1997) and updated in the Remedial Design Report/Remedial Action Work Plan for the 300 Area (DOE RL 2004).

Because residual soil concentrations indicated that cleanup levels for more stringent land uses may have been achieved for the 618-4 Burial Ground, a supplemental evaluation was performed against the unrestricted land-use cleanup objectives established in the 300-FF-2 ESD (EPA 2004). Results of the evaluation demonstrated that remedial actions at the site have achieved all of the objectives for unrestricted land uses. Consequently, no institutional controls are required at the site.

Code:	618-12	Classification:	Accepted
Names:	618-12; North Process Pond Scraping Disposal Area	Reclassification	Final Closed Out (8/29/1999)
Type:	Burial Ground	Start Date:	1/1/1949
Status:	Inactive	End Date:	1/1/1964
Description:	The site was closed out in conjunction with the North Process Ponds in 1999. Contaminated material was excavated and transported to ERDF. The site is not marked or posted. The pond had been backfilled with ashes. The backfilled area measured approximately 248 by 141 meters (814 by 462 feet).		
Location:	The North Process Pond Scraping Disposal Area extended approximately 61 meters (200 feet) south of the North Process Ponds.		
Process Description:	The scraping disposal area was used for disposal of uranium-contaminated soil from the bottom of the North Process Pond and from beneath the 321 Building during excavation for hydraulic core mockup.		
Waste Type:	Soil		
Waste Description:	This site was used for disposal of uranium-contaminated soil that was scraped from the 316-2 Pond (North Process Pond) and some uranium-contaminated soil that was removed from beneath the 321 Building during excavation for hydraulic core mockup.		
Closure Info:	Final (8/24/1999): Remediation activities were initiated in May 1998 and continued into January 1999. On January 25, 1999 a decision was made to suspend excavation activities at the North Process Pond and mobilize work crews to the South Process Pond pending resolution of		

contractual issues with the remedial action subcontractor. Work crews remobilized to the North Process Pond and completed excavation activities in June 1999.

Based on data collected during the remedial investigation, the pond was divided into the Above Cleanup Level (ACL), Below Cleanup Level (BCL), and Undetermined Contamination Level (UCL) areas prior to excavation. The UCL area included the Scraping Disposal Area (sitecode 618-12). Four UPRs associated with the north pond were also associated with the south pond. UPR-300-34, UPR-300-35, UPR-300-36 and UPR-300-37 were addressed with the South Pond remediation (316-1). UPR-300-7 was closed out with the North Pond (316-2).

Code: 628-4	Classification: Accepted
Names: 628-4; Landfill 1D	Reclassification: Final Closed Out (7/1/2003)
Type: Burn Pit	Start Date: 1/1/1962
Status: Inactive	End Date: 1/1/1974
Description: The site has been remediated and Closed Out. The waste site was used as an alternate burning site, in conjunction with the burning in Burial Ground 5 (618-5), to allow the units to cool between burnings.	
Location: The site was located just north of the west end of 300-52 (300 Area Sanitary Trenches).	
Waste Type: Misc. Trash and Debris	
Waste Description: The unit was used mainly for burning paper, wood, paint cans, and other operations debris; however, some incidental radioactive materials may have also been burned.	
Closure Info: Interim (7/1/2003): Remedial action at the Landfill 1D site began in 1999. Excavation at the site involved removing the overburden (scraped surface) soils, buried landfill waste and ash, and comingled soil. The buried landfill waste was sorted and sent to ERDF for treatment as necessary and disposal. During remediation, elevated concentrations of lead were identified in excavated soil. Because of the large volume of soil containing lead, a site-specific lead treatment standard was established for soil excavated from the Landfill 1D site through an Explanation of Significant Difference (ESD). Excavation and disposal of the Landfill 1 D remediation waste was completed in June 2000.	

The selected remedial action for the Landfill 1D site included excavation to the extent required to meet specified soil cleanup levels and disposal of contaminated excavation materials at the Environmental Restoration Disposal Facility at the 200 Areas of the Hanford Site. The remedial action also included the removal and disposal of solid waste and construction debris. Excavation was driven by remedial action objectives for direct exposure, protection of groundwater, and protection of the Columbia River. For the respective points of compliance, remedial action goals (RAGs) were established in the 1997 RDR/RAWP and updated in the Remedial Design Report/ Remedial Action Work Plan for the 300 Area (2002 RDR/RAWP) (DOE RL 2002).

At the completion of the remedial action, the total excavation was approximately 2,100 square meters (22,600 square feet) in area with a maximum depth of approximately 5.7 meter (19 feet). Approximately 5,635 metric tons (6,198 tons) of material from the site were disposed at the Environmental Restoration Disposal Facility. All visible debris was removed and the site was excavated to native soil. Overburden material identified as potentially clean was stockpiled at the site for potential use as backfill.

The site meets cleanup standards and has been reclassified as "closed out" in accordance with the Hanford Federal Facility Agreement and Consent Order (Ecology et al. 1998) and the Waste

 Site Reclassification Guideline TPA-MP-14 (RL TPA-90-0001) (DOE-RL 1998).

Code: UPR-300-FF-1 **Classification:** Accepted

Names: UPR-300-FF-1; 300-FF-1 Hot Spots; Surface Radiation Survey for 300-FF-1; UN-300-FF-1 **Reclassification:** Final Closed Out (7/23/2003)

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The site has been remediated and closed out.

Location: The posted release sites were widely spaced in the area north of the 300 Area fence.

Related Sites/Structures: The release sites were located in the 300-FF-1 Operable Unit and associated with WIDS sites 300-44, 300-49, 300-50, 300-51, the 316-1 South Process Pond and 316-2 North Process Pond.

Waste Type: Soil

Waste Description: Primarily, contamination was associated with the soil; however, some contaminated metal and other materials were also found. GM/P-11 instrument readings range from 100 to 50,000 counts/minute. Analysis of samples showed that the radiation levels were caused primarily by the presence of uranium. Some soil samples also contained relatively high concentrations of copper.

Closure Info: Interim (7/23/2003): Remediation activities at the 316-1 South Process Pond site began in 1997 with excavating trenches around the periphery of the 316-1 site. Trenching was performed to assess the lateral extent of contamination. The majority of remedial excavation and disposal activities were conducted in 1999 and 2000. Excavation at the site involved removing the overburden (scraped surface) soils and contaminated soils. The contaminated soil was transported to the ERDF for disposal. Based on field screening, overburden materials and comingled soil identified as potentially clean were placed in stockpiles for potential use as backfill. Soil samples were collected adjacent to utility poles located in the 316-1 site. Where these samples indicated contaminant concentrations above the cleanup criteria, the soil was removed and the area immediately backfilled and compacted with clean material to maintain the integrity of the utility pole. Excavation and disposal of the 316-1 South Process Pond remediation waste was completed in June 2000. The filter backwash pond (WIDS site 300 RFBP) was a lobe on east side of the process pond. During remediation, soil was primarily removed from the area on the west side of the process pond, near the pond inlet. The two north-south parallel soil berms inside the pond were removed. Areas to the south and west of the original pond boundaries were also removed during remediation. The general elevation at the bottom of the excavation used for analysis was 111.3 meters (365 ft) upon completion. The excavation depth was approximately 5.7 meters (19 ft).

Code: UPR-300-8 **Classification:** Accepted

Names: UPR-300-8; Caustic Spill from 311 Tank Farm to Process Sewer **Reclassification:** Final Closed Out (8/13/1998)

Type: Unplanned Release **Start Date:** 1/1/1980

Status: Inactive **End Date:** 1/1/1980

Description: This release was confined to the 300 Area Process Trench.

Location: UPR-300-8 originated at the caustic storage tank in the 311 Tank Farm and was confined to the 300 Area Process Trench.

Release Description: The release occurred from September 20-22, 1980. A defective valve in the storage tank steam sparge line allowed steam condensate to overflow the caustic storage tank contents into the process sewer system.

Related Sites/Structures: UPR-300-8 was associated with the caustic storage tank in the 311 Tank Farm and the 316-5 Process Trenches.

Waste Type: Chemicals

Waste Description: The release consisted of 50% sodium hydroxide solution. The pH in the process sewer was 11.95.

Closure Info: Final (8/13/1998): CERCLA remediation activities were initiated in July 1997 and completed in February 1998. Remediation of the 300 Area Process Trenches included removal and disposal of bird screens covering the trenches, demolition and disposal of the headworks structure located at the southern end of the trenches, demolition and disposal of the blockhouse structure, and excavation and disposal of contaminated soil that accounted for several unplanned release waste sites.

In 1991, an expedited response action (ERA) was performed to reduce the migration of radioactive and inorganic (heavy metals) contaminants to groundwater. This was accomplished by excavating contaminated sediments in the south end of the trenches, using them to fill in the north end of the trenches, and immobilizing them. The ERA uniformly excavated approximately 0.3 meters (1ft) and 1.3 meters (4 ft) of contaminated soil from the sides and bottom of each trench, respectively. The contaminated material was stockpiled in the northwest corner of the west trench and the north end of the east trench (referred to as a spoils area). Based on process history, the Part A submitted by the U.S. Department of Energy, Richland Operations Office (DOE-RL) assigned several listed waste codes to the ERA spoils pile. The spoils area was covered with plastic and aggregate to allow continued operation of the trenches without flushing residual contaminants into the groundwater. Post-excavation sample results indicated that the ERA successfully reduced contamination in all areas of the trenches, other than the spoils area.

RCRA closure of the process trenches was performed in accordance with the 300 Area Process Trenches Modified Closure Post Closure Plan (DOE-RL 1995). An independent registered professional engineer was tasked to review the 300-FF-1 remedial action activities to ensure that the TSD closure met the WAC 173-303-610 performance standards. The permit was closed with post-closure requirements.

Code: UPR-300-9	Classification: Accepted
Names: UPR-300-9; Nitric Acid Leak from 306-W to the Process Sewer	Reclassification: Final Closed Out (8/13/1998)
Type: Unplanned Release	Start Date: 1/1/1976
Status: Inactive	End Date: 1/1/1976

Description: This release originated in Room 120 of the 306-W Building and drained into the 300 Area process drainage system.

Location: UPR-300-9 originated in Room 120 of Building 306-W and drained to the process sewer leading to the north process trench.

Release Description: Nitric acid solution drained from a storage tank in Room 120 of the 306 Building into the 300 Area process drainage system.

Related Sites/Structures: UPR-300-9 was associated with Room 120 of Building 306-W and the process sewer leading to the 316-5 process trenches.

Waste Type: Chemicals

Waste Description: The release consisted of nitric acid solution containing 267.9 pounds (121.5 kilograms) of depleted uranium.

Closure Info: Final (8/13/1998): CERCLA remediation activities were initiated in July 1997 and completed in February 1998. Remediation of the 300 Area Process Trenches included removal and disposal of bird screens covering the trenches, demolition and disposal of the headworks structure located at the southern end of the trenches, demolition and disposal of the blockhouse structure, and excavation and disposal of contaminated soil that accounted for several unplanned release waste sites.

In 1991, an expedited response action (ERA) was performed to reduce the migration of radioactive and inorganic (heavy metals) contaminants to groundwater. This was accomplished by excavating contaminated sediments in the south end of the trenches, using them to fill in the north end of the trenches, and immobilizing them. The ERA uniformly excavated approximately 0.3 meters (1ft) and 1.3 meters (4 ft) of contaminated soil from the sides and bottom of each trench, respectively. The contaminated material was stockpiled in the northwest corner of the west trench and the north end of the east trench (referred to as a spoils area). Based on process history, the Part A submitted by the U.S. Department of Energy, Richland Operations Office (DOE-RL) assigned several listed waste codes to the ERA spoils pile. The spoils area was covered with plastic and aggregate to allow continued operation of the trenches without flushing residual contaminants into the groundwater. Post-excavation sample results indicated that the ERA successfully reduced contamination in all areas of the trenches, other than the spoils area.

RCRA closure of the process trenches was performed in accordance with the 300 Area Process Trenches Modified Closure Post Closure Plan (DOE-RL 1995). An independent registered professional engineer was tasked to review the 300-FF-1 remedial action activities to ensure that the TSD closure met the WAC 173-303-610 performance standards. The permit was closed with post-closure requirements.

Code: UPR-300-15	Classification: Accepted
Names: UPR-300-15; Uranium Bearing Acid Release from 313 to the Process Sewer	Reclassification: Final Closed Out (8/13/1998)
Type: Unplanned Release	Start Date: 1/1/1980
Status: Inactive	End Date: 1/1/1980

Description: The site was a release that flowed into the 313 Process Sewer leading to the 316-5 Trench.

Location: UPR-300-15 was located at the end of the 313 Process Sewer at the 316-5 Trench.

Release Description: Uranium-bearing Acid Storage Tanks 3 and 4 in Building 313 overflowed the catch barrel and trickled over into the process sewer. Further inspection revealed that Tank 3 had discharged downward into Tank 4 through interconnected discharge lines. The discharge line for Tank 4 was wide open.

Related Sites/Structures: UPR-300-15 was associated with uranium-bearing acid storage Tanks 3 and 4, the overflow catch barrel in Building 313, and the 316-5 Process Trenches.

Waste Type: Process Effluent

Waste Description: The waste contained uranium-bearing acid.

Closure Info: Final (8/13/1998): CERCLA remediation activities were initiated in July 1997 and completed in February 1998. Remediation of the 300 Area Process Trenches included removal and disposal of bird screens covering the trenches, demolition and disposal of the headworks structure located at the southern end of the trenches, demolition and disposal of the blockhouse structure, and excavation and disposal of contaminated soil that accounted for several unplanned release waste sites.

In 1991, an expedited response action (ERA) was performed to reduce the migration of radioactive and inorganic (heavy metals) contaminants to groundwater. This was accomplished by excavating contaminated sediments in the south end of the trenches, using them to fill in the north end of the trenches, and immobilizing them. The ERA uniformly excavated approximately 0.3 meters (1ft) and 1.3 meters (4 ft) of contaminated soil from the sides and bottom of each trench, respectively. The contaminated material was stockpiled in the northwest corner of the west trench and the north end of the east trench (referred to as a spoils area). Based on process history, the Part A submitted by the U.S. Department of Energy, Richland Operations Office (DOE-RL) assigned several listed waste codes to the ERA spoils pile. The spoils area was covered with plastic and aggregate to allow continued operation of the trenches without flushing residual contaminants into the groundwater. Post-excavation sample results indicated that the ERA successfully reduced contamination in all areas of the trenches, other than the spoils area.

RCRA closure of the process trenches was performed in accordance with the 300 Area Process Trenches Modified Closure Post Closure Plan (DOE-RL 1995). An independent registered professional engineer was tasked to review the 300-FF-1 remedial action activities to ensure that the TSD closure met the WAC 173-303-610 performance standards. The permit was closed with post-closure requirements.

Code:	UPR-300-19	Classification:	Accepted
Names:	UPR-300-19; Chemical Release to the Process Sewer	Reclassification	Final Closed Out (8/13/1998)
Type:	Unplanned Release	Start Date:	1/1/1980
Status:	Inactive	End Date:	1/1/1980
Description:	The release originated at the 313 Building floor trenches and was confined to the 300 Area Process Trench.		
Location:	UPR-300-19 occurred in the 313 Building and was washed into the 300 Area Process Sewer. The 300 Area Process Sewer is routed to the 316-5 Trench.		
Release Description:	Two 14 gallon drums of incoming deoxidization chemicals (nitric-sulfuric-chromic acid mixture) were found to be leaking. After the leaks were discovered, the floor was washed off, resulting in discharge to the process sewer. The process sewer showed high nitrate, fluoride, and pH values as a result of this incident. The event is documented on Unusual Event Report SO-80-12.		
Related Sites/Structures:	UPR-300-19 was associated with the floor trenches in the 313 Building and the 300 Area Process Sewer (316-5).		
Waste Type:	Chemicals		
Waste Description:	The waste contained nitric, sulfuric and chromic acid, followed by an ammonium bifluoride and sodium hydroxide discharge with incoming acid used in copper component deoxidizing.		
Closure Info:	Final (8/13/1998): CERCLA remediation activities were initiated in July 1997 and completed in February 1998. Remediation of the 300 Area Process Trenches included removal and disposal		

of bird screens covering the trenches, demolition and disposal of the headworks structure located at the southern end of the trenches, demolition and disposal of the blockhouse structure, and excavation and disposal of contaminated soil that accounted for several unplanned release waste sites.

In 1991, an expedited response action (ERA) was performed to reduce the migration of radioactive and inorganic (heavy metals) contaminants to groundwater. This was accomplished by excavating contaminated sediments in the south end of the trenches, using them to fill in the north end of the trenches, and immobilizing them. The ERA uniformly excavated approximately 0.3 meters (1ft) and 1.3 meters (4 ft) of contaminated soil from the sides and bottom of each trench, respectively. The contaminated material was stockpiled in the northwest corner of the west trench and the north end of the east trench (referred to as a spoils area). Based on process history, the Part A submitted by the U.S. Department of Energy, Richland Operations Office (DOE-RL) assigned several listed waste codes to the ERA spoils pile. The spoils area was covered with plastic and aggregate to allow continued operation of the trenches without flushing residual contaminants into the groundwater. Post-excavation sample results indicated that the ERA successfully reduced contamination in all areas of the trenches, other than the spoils area.

RCRA closure of the process trenches was performed in accordance with the 300 Area Process Trenches Modified Closure Post Closure Plan (DOE-RL 1995). An independent registered professional engineer was tasked to review the 300-FF-1 remedial action activities to ensure that the TSD closure met the WAC 173-303-610 performance standards. The permit was closed with post-closure requirements.

Code:	UPR-300-20	Classification:	Accepted
Names:	UPR-300-20; Acid Release to the Process Sewer	Reclassification	Final Closed Out (8/13/1998)
Type:	Unplanned Release	Start Date:	1/1/1980
Status:	Inactive	End Date:	
Description:	The release originated at the 313 Building Uranium Recovery Area and was confined to the 300 Area Process Trenches (316-5).		
Release Description:	On 8-19-80, an overflow of a storage tank in the 313 Building resulted in an overflow of the catch barrel into the process sewer system. The release was documented on Occurrence Report 80-26.		
Process Description:	An overflow of a storage tank in the 313 Building resulted in an overflow of the catch barrel into the process sewer system, releasing an unknown quantity of uranium-bearing nitric acid and sulfuric acid into the 316-5 Process Trench.		
Waste Type:	Chemicals		
Waste Description:	Nitric and sulfuric acids with uranium in solution, quantity unknown.		
Closure Info:	Final (8/13/1998): CERCLA remediation activities were initiated in July 1997 and completed in February 1998. Remediation of the 300 Area Process Trenches included removal and disposal of bird screens covering the trenches, demolition and disposal of the headworks structure located at the southern end of the trenches, demolition and disposal of the blockhouse structure, and excavation and disposal of contaminated soil that accounted for several unplanned release waste sites.		

In 1991, an expedited response action (ERA) was performed to reduce the migration of radioactive and inorganic (heavy metals) contaminants to groundwater. This was accomplished

by excavating contaminated sediments in the south end of the trenches, using them to fill in the north end of the trenches, and immobilizing them. The ERA uniformly excavated approximately 0.3 meters (1ft) and 1.3 meters (4 ft) of contaminated soil from the sides and bottom of each trench, respectively. The contaminated material was stockpiled in the northwest corner of the west trench and the north end of the east trench (referred to as a spoils area). Based on process history, the Part A submitted by the U.S. Department of Energy, Richland Operations Office (DOE-RL) assigned several listed waste codes to the ERA spoils pile. The spoils area was covered with plastic and aggregate to allow continued operation of the trenches without flushing residual contaminants into the groundwater. Post-excavation sample results indicated that the ERA successfully reduced contamination in all areas of the trenches, other than the spoils area.

RCRA closure of the process trenches was performed in accordance with the 300 Area Process Trenches Modified Closure Post Closure Plan (DOE-RL 1995). An independent registered professional engineer was tasked to review the 300-FF-1 remedial action activities to ensure that the TSD closure met the WAC 173-303-610 performance standards. The permit was closed with post-closure requirements.

Code:	UPR-300-21	Classification:	Accepted
Names:	UPR-300-21; Nitric Acid Release to the Process Sewer	Reclassification	Final Closed Out (8/13/1998)
Type:	Unplanned Release	Start Date:	1/1/1980
Status:	Inactive	End Date:	1/1/1980

Description: The release originated in the 333 Building and was confined to the 300 Area Process Trench.

Location: UPR-300-21 originated in the 333 Building Chemical Bay Area, but was confined to the 300 Area Process Trench.

Release Description: Nitric acid fill lines to Tanks 13, 15, and 16 in the 333 Building were removed. Some residual nitric acid from these lines was discharged into the process sewer.

Related Sites/Structures: UPR-300-21 was associated with Tanks 13, 15, and 16 in Building 333 and the 300 Area Process Trench.

Waste Type: Chemicals

Waste Description: The waste contained a small quantity of nitric acid.

Closure Info: Final (8/13/1998): CERCLA remediation activities were initiated in July 1997 and completed in February 1998. Remediation of the 300 Area Process Trenches included removal and disposal of bird screens covering the trenches, demolition and disposal of the headworks structure located at the southern end of the trenches, demolition and disposal of the blockhouse structure, and excavation and disposal of contaminated soil that accounted for several unplanned release waste sites.

In 1991, an expedited response action (ERA) was performed to reduce the migration of radioactive and inorganic (heavy metals) contaminants to groundwater. This was accomplished by excavating contaminated sediments in the south end of the trenches, using them to fill in the north end of the trenches, and immobilizing them. The ERA uniformly excavated approximately 0.3 meters (1ft) and 1.3 meters (4 ft) of contaminated soil from the sides and bottom of each trench, respectively. The contaminated material was stockpiled in the northwest corner of the west trench and the north end of the east trench (referred to as a spoils area). Based on process history, the Part A submitted by the U.S. Department of Energy, Richland

Operations Office (DOE-RL) assigned several listed waste codes to the ERA spoils pile. The spoils area was covered with plastic and aggregate to allow continued operation of the trenches without flushing residual contaminants into the groundwater. Post-excavation sample results indicated that the ERA successfully reduced contamination in all areas of the trenches, other than the spoils area.

RCRA closure of the process trenches was performed in accordance with the 300 Area Process Trenches Modified Closure Post Closure Plan (DOE-RL 1995). An independent registered professional engineer was tasked to review the 300-FF-1 remedial action activities to ensure that the TSD closure met the WAC 173-303-610 performance standards. The permit was closed with post-closure requirements.

Code:	UPR-300-22	Classification:	Accepted
Names:	UPR-300-22; Acid Release to the Process Sewer	Reclassification	Final Closed Out (8/13/1998)
Type:	Unplanned Release	Start Date:	1/1/1980
Status:	Inactive	End Date:	1/1/1980
Description:	The release site originated in the 333 Building and was confined to the 300 Area Process Trench.		
Location:	UPR-300-22 originated in the 333 Building Chemical Bay Area, but was confined to the 300 Area Process Trench.		
Release Description:	Acid Etch Tanks No. 13 and 15 were leaking, discharging acid into the process sewer.		
Related Sites/ Structures:	UPR-300-22 was associated with Tanks 13 and 15 in Building 333 and the 300 Area Process Trench.		
Waste Type:	Chemicals		
Waste Description:	The waste consisted of a small quantity of etch acids (nitric and hydrofluoric acids).		
Closure Info:	Final (8/13/1998): CERCLA remediation activities were initiated in July 1997 and completed in February 1998. Remediation of the 300 Area Process Trenches included removal and disposal of bird screens covering the trenches, demolition and disposal of the headworks structure located at the southern end of the trenches, demolition and disposal of the blockhouse structure, and excavation and disposal of contaminated soil that accounted for several unplanned release waste sites.		

In 1991, an expedited response action (ERA) was performed to reduce the migration of radioactive and inorganic (heavy metals) contaminants to groundwater. This was accomplished by excavating contaminated sediments in the south end of the trenches, using them to fill in the north end of the trenches, and immobilizing them. The ERA uniformly excavated approximately 0.3 meters (1ft) and 1.3 meters (4 ft) of contaminated soil from the sides and bottom of each trench, respectively. The contaminated material was stockpiled in the northwest corner of the west trench and the north end of the east trench (referred to as a spoils area). Based on process history, the Part A submitted by the U.S. Department of Energy, Richland Operations Office (DOE-RL) assigned several listed waste codes to the ERA spoils pile. The spoils area was covered with plastic and aggregate to allow continued operation of the trenches without flushing residual contaminants into the groundwater. Post-excavation sample results indicated that the ERA successfully reduced contamination in all areas of the trenches, other than the spoils area.

RCRA closure of the process trenches was performed in accordance with the 300 Area Process Trenches Modified Closure Post Closure Plan (DOE-RL 1995). An independent registered professional engineer was tasked to review the 300-FF-1 remedial action activities to ensure that the TSD closure met the WAC 173-303-610 performance standards. The permit was closed with post-closure requirements.

Code:	UPR-300-23	Classification:	Accepted
Names:	UPR-300-23; Acid Release to the Process Sewer	Reclassification	Final Closed Out (8/13/1998)
Type:	Unplanned Release	Start Date:	1/1/1980
Status:	Inactive	End Date:	1/1/1980

Description: The release site was confined to the 300 Area Process Trench and originated at the 333 Building.

Location: UPR-300-23 originated in the 333 Building nitric and sulfuric acid fill lines and was confined to the 300 Area Process Trenches.

Release Description: Leak inspection revealed two leaks in the nitric and sulfuric acid fill lines.

Related Sites/ Structures: UPR-300-23 was associated with nitric and sulfuric acid fill lines and the 300 Area Process Trench.

Waste Type: Chemicals

Waste Description: The waste consisted of a small quantity of incoming etch acids (nitric and sulfuric acid).

Closure Info: Final (8/13/1998): CERCLA remediation activities were initiated in July 1997 and completed in February 1998. Remediation of the 300 Area Process Trenches included removal and disposal of bird screens covering the trenches, demolition and disposal of the headworks structure located at the southern end of the trenches, demolition and disposal of the blockhouse structure, and excavation and disposal of contaminated soil that accounted for several unplanned release waste sites.

In 1991, an expedited response action (ERA) was performed to reduce the migration of radioactive and inorganic (heavy metals) contaminants to groundwater. This was accomplished by excavating contaminated sediments in the south end of the trenches, using them to fill in the north end of the trenches, and immobilizing them. The ERA uniformly excavated approximately 0.3 meters (1ft) and 1.3 meters (4 ft) of contaminated soil from the sides and bottom of each trench, respectively. The contaminated material was stockpiled in the northwest corner of the west trench and the north end of the east trench (referred to as a spoils area). Based on process history, the Part A submitted by the U.S. Department of Energy, Richland Operations Office (DOE-RL) assigned several listed waste codes to the ERA spoils pile. The spoils area was covered with plastic and aggregate to allow continued operation of the trenches without flushing residual contaminants into the groundwater. Post-excavation sample results indicated that the ERA successfully reduced contamination in all areas of the trenches, other than the spoils area.

RCRA closure of the process trenches was performed in accordance with the 300 Area Process Trenches Modified Closure Post Closure Plan (DOE-RL 1995). An independent registered professional engineer was tasked to review the 300-FF-1 remedial action activities to ensure that the TSD closure met the WAC 173-303-610 performance standards. The permit was closed with post-closure requirements.

Code: UPR-300-24 **Classification:** Accepted
Names: UPR-300-24; Acid Release to the Process Sewer **Reclassification:** Final Closed Out (8/13/1998)
Type: Unplanned Release **Start Date:** 1/1/1980
Status: Inactive **End Date:** 1/1/1980

Description: The release originated at the 333 Building Waste Acid System and was confined to the 300 Area Process Trench.

Location: UPR-300-24 originated in the 333 Building Waste Acid System, but was confined to the 300 Area Process Trench.

Release Description: Leak inspection revealed two small drip leaks around a newly installed etch tank.

Related Sites/Structures: UPR-300-24 was associated with the 333 Building Waste Acid System and the 300 Area Process Trench.

Waste Type: Chemicals

Waste Description: The waste consisted of a small quantity of waste etch acids (nitric and hydrofluoric acid).

Closure Info: Final (8/13/1998): CERCLA remediation activities were initiated in July 1997 and completed in February 1998. Remediation of the 300 Area Process Trenches included removal and disposal of bird screens covering the trenches, demolition and disposal of the headworks structure located at the southern end of the trenches, demolition and disposal of the blockhouse structure, and excavation and disposal of contaminated soil that accounted for several unplanned release waste sites.

In 1991, an expedited response action (ERA) was performed to reduce the migration of radioactive and inorganic (heavy metals) contaminants to groundwater. This was accomplished by excavating contaminated sediments in the south end of the trenches, using them to fill in the north end of the trenches, and immobilizing them. The ERA uniformly excavated approximately 0.3 meters (1ft) and 1.3 meters (4 ft) of contaminated soil from the sides and bottom of each trench, respectively. The contaminated material was stockpiled in the northwest corner of the west trench and the north end of the east trench (referred to as a spoils area). Based on process history, the Part A submitted by the U.S. Department of Energy, Richland Operations Office (DOE-RL) assigned several listed waste codes to the ERA spoils pile. The spoils area was covered with plastic and aggregate to allow continued operation of the trenches without flushing residual contaminants into the groundwater. Post-excavation sample results indicated that the ERA successfully reduced contamination in all areas of the trenches, other than the spoils area.

RCRA closure of the process trenches was performed in accordance with the 300 Area Process Trenches Modified Closure Post Closure Plan (DOE-RL 1995). An independent registered professional engineer was tasked to review the 300-FF-1 remedial action activities to ensure that the TSD closure met the WAC 173-303-610 performance standards. The permit was closed with post-closure requirements.

Code: UPR-300-25 **Classification:** Accepted
Names: UPR-300-25; Release to the Process Sewer **Reclassification:** Final Closed Out (8/13/1998)
Type: Unplanned Release **Start Date:** 1/1/1980
Status: Inactive **End Date:** 1/1/1980

Description: The release originated at the 333 Building Uranium Mill Tank and was confined to the 300 Area Process Trench.

Location: UPR-300-25 originated in the steam coils in the Uranium Mill Tank Number 32 and was confined to the 300 Area Process Trench.

Release Description: Leaks in steam coils in the uranium mill tank caused acid to be siphoned into the cooling coils at the nightly shutoff. During startup in the morning, steam discharged the acid in the coils into the process sewer system.

Related Sites/ Structures: UPR-300-25 was associated with the steam coils in the Uranium Mill Tank in the 333 Building and the 300 Area Process Trench.

Waste Type: Chemicals

Waste Description: The waste consisted of a small quantity of uranium etch acids (nitric and sulfuric acid) in uranium solution.

Closure Info: Final (8/13/1998): CERCLA remediation activities were initiated in July 1997 and completed in February 1998. Remediation of the 300 Area Process Trenches included removal and disposal of bird screens covering the trenches, demolition and disposal of the headworks structure located at the southern end of the trenches, demolition and disposal of the blockhouse structure, and excavation and disposal of contaminated soil that accounted for several unplanned release waste sites.

In 1991, an expedited response action (ERA) was performed to reduce the migration of radioactive and inorganic (heavy metals) contaminants to groundwater. This was accomplished by excavating contaminated sediments in the south end of the trenches, using them to fill in the north end of the trenches, and immobilizing them. The ERA uniformly excavated approximately 0.3 meters (1ft) and 1.3 meters (4 ft) of contaminated soil from the sides and bottom of each trench, respectively. The contaminated material was stockpiled in the northwest corner of the west trench and the north end of the east trench (referred to as a spoils area). Based on process history, the Part A submitted by the U.S. Department of Energy, Richland Operations Office (DOE-RL) assigned several listed waste codes to the ERA spoils pile. The spoils area was covered with plastic and aggregate to allow continued operation of the trenches without flushing residual contaminants into the groundwater. Post-excavation sample results indicated that the ERA successfully reduced contamination in all areas of the trenches, other than the spoils area.

RCRA closure of the process trenches was performed in accordance with the 300 Area Process Trenches Modified Closure Post Closure Plan (DOE-RL 1995). An independent registered professional engineer was tasked to review the 300-FF-1 remedial action activities to ensure that the TSD closure met the WAC 173-303-610 performance standards. The permit was closed with post-closure requirements.

Code: UPR-300-26	Classification: Accepted
Names: UPR-300-26; Caustic Release to the Process Sewer	Reclassification: Final Closed Out (8/13/1998)
Type: Unplanned Release	Start Date: 1/1/1980
Status: Inactive	End Date: 1/1/1980

Description: The release originated in the 311 Tank Farm and was confined to the 300 Area Process Trench.

Location: UPR-300-26 originated in the Caustic Storage Tank in the 311 Tank Farm and was routed to the 300 Area Process Trench for disposal.

Release Description: Condensate from a steam heating line in the caustic storage tank caused overflow to the process sewer.

Related Sites/ Structures: UPR-300-26 was associated with the caustic storage area at the 313 Tank Farm and the 300 Area Process Trench.

Waste Type: Chemicals

Waste Description: The waste consisted of a very small quantity of 50% sodium hydroxide consisting of less than 0.1 pound (0.05 kilograms) of sodium hydroxide.

Closure Info: Final (8/13/1998): CERCLA remediation activities were initiated in July 1997 and completed in February 1998. Remediation of the 300 Area Process Trenches included removal and disposal of bird screens covering the trenches, demolition and disposal of the headworks structure located at the southern end of the trenches, demolition and disposal of the blockhouse structure, and excavation and disposal of contaminated soil that accounted for several unplanned release waste sites.

In 1991, an expedited response action (ERA) was performed to reduce the migration of radioactive and inorganic (heavy metals) contaminants to groundwater. This was accomplished by excavating contaminated sediments in the south end of the trenches, using them to fill in the north end of the trenches, and immobilizing them. The ERA uniformly excavated approximately 0.3 meters (1ft) and 1.3 meters (4 ft) of contaminated soil from the sides and bottom of each trench, respectively. The contaminated material was stockpiled in the northwest corner of the west trench and the north end of the east trench (referred to as a spoils area). Based on process history, the Part A submitted by the U.S. Department of Energy, Richland Operations Office (DOE-RL) assigned several listed waste codes to the ERA spoils pile. The spoils area was covered with plastic and aggregate to allow continued operation of the trenches without flushing residual contaminants into the groundwater. Post-excavation sample results indicated that the ERA successfully reduced contamination in all areas of the trenches, other than the spoils area.

RCRA closure of the process trenches was performed in accordance with the 300 Area Process Trenches Modified Closure Post Closure Plan (DOE-RL 1995). An independent registered professional engineer was tasked to review the 300-FF-1 remedial action activities to ensure that the TSD closure met the WAC 173-303-610 performance standards. The permit was closed with post-closure requirements.

Code: UPR-300-27	Classification: Accepted
Names: UPR-300-27; Acid Release to the Process Sewer	Reclassification: Final Closed Out (8/13/1998)
Type: Unplanned Release	Start Date: 1/1/1979
Status: Inactive	End Date: 1/1/1979

Description: The release originated in the Uranium Bearing Acid Storage Tank in the 333 Building and was confined to the 300 Area Process Trench.

Location: UPR-300-27 originated in the Uranium Bearing Acid Storage Tank piping in the 333 Building and was routed to the 300 Area Process Trench.

Release Description: Failure of a check valve in the piping system resulted in discharge of a stream of uranium-bearing acid into the 300 Area process sewer system. An operator noticed the leakage and immediately shut down the transfer pump, stopping the release.

Related Sites/ Structures: UPR-300-27 was associated with holding tank 24 in the 333 Building Chemical Bay and the 300 Area Process Trench.

Waste Type: Chemicals

Waste Description: The waste contained an unknown quantity of uranium-bearing acid waste consisting of nitric and sulfuric acids.

Closure Info: Final (8/13/1998): CERCLA remediation activities were initiated in July 1997 and completed in February 1998. Remediation of the 300 Area Process Trenches included removal and disposal of bird screens covering the trenches, demolition and disposal of the headworks structure located at the southern end of the trenches, demolition and disposal of the blockhouse structure, and excavation and disposal of contaminated soil that accounted for several unplanned release waste sites.

In 1991, an expedited response action (ERA) was performed to reduce the migration of radioactive and inorganic (heavy metals) contaminants to groundwater. This was accomplished by excavating contaminated sediments in the south end of the trenches, using them to fill in the north end of the trenches, and immobilizing them. The ERA uniformly excavated approximately 0.3 meters (1ft) and 1.3 meters (4 ft) of contaminated soil from the sides and bottom of each trench, respectively. The contaminated material was stockpiled in the northwest corner of the west trench and the north end of the east trench (referred to as a spoils area). Based on process history, the Part A submitted by the U.S. Department of Energy, Richland Operations Office (DOE-RL) assigned several listed waste codes to the ERA spoils pile. The spoils area was covered with plastic and aggregate to allow continued operation of the trenches without flushing residual contaminants into the groundwater. Post-excavation sample results indicated that the ERA successfully reduced contamination in all areas of the trenches, other than the spoils area.

RCRA closure of the process trenches was performed in accordance with the 300 Area Process Trenches Modified Closure Post Closure Plan (DOE-RL 1995). An independent registered professional engineer was tasked to review the 300-FF-1 remedial action activities to ensure that the TSD closure met the WAC 173-303-610 performance standards. The permit was closed with post-closure requirements.

Code: UPR-300-28	Classification: Accepted
Names: UPR-300-28; Release to the Process Sewer	Reclassification: Final Closed Out (8/13/1998)
Type: Unplanned Release	Start Date: 1/1/1978
Status: Inactive	End Date: 1/1/1978

Description: The release was an overflow to the 334A Containment Pit. The UPR was routed to the 300 Area Process Trench.

Location: UPR-300-28 originated with an overflow into the 334A Containment Pit from the 334A Storage Tank. The UPR was routed to the 300 Area Process Trench.

Release Description: An open water fill line in the 333 Building caused the process tank to overflow into the 334A Storage Tanks, which overflowed into the containment pit. The pit then overflowed into the process sewer system. Overflow to the process sewer apparently began at 7:30 a.m. on June 3, 1978 and was discovered on the morning of June 5, 1978. The sewer pH monitor indicated the pH dropped from 7.4 to 6.8 after the solution from the pit entered the sewer, indicating very little acid was dumped into the sewer. In Fiscal Year 1998, the R-12 refrigerant in all eight chillers was replaced with R-134A, which is nonhazardous and non-ozone depleting.

Related Sites/Structures: UPR-300-28 was associated with the 334A Storage Tanks, 334A Containment Pit, and the 300 Area Process Trench.

Waste Type: Chemicals

Waste Description: The release consisted of solution containing hydrofluoric, nitric, and sulfuric acids with copper, uranium, and zirconium in solution.

Closure Info: Final (8/13/1998): CERCLA remediation activities were initiated in July 1997 and completed in February 1998. Remediation of the 300 Area Process Trenches included removal and disposal of bird screens covering the trenches, demolition and disposal of the headworks structure located at the southern end of the trenches, demolition and disposal of the blockhouse structure, and excavation and disposal of contaminated soil that accounted for several unplanned release waste sites.

In 1991, an expedited response action (ERA) was performed to reduce the migration of radioactive and inorganic (heavy metals) contaminants to groundwater. This was accomplished by excavating contaminated sediments in the south end of the trenches, using them to fill in the north end of the trenches, and immobilizing them. The ERA uniformly excavated approximately 0.3 meters (1ft) and 1.3 meters (4 ft) of contaminated soil from the sides and bottom of each trench, respectively. The contaminated material was stockpiled in the northwest corner of the west trench and the north end of the east trench (referred to as a spoils area). Based on process history, the Part A submitted by the U.S. Department of Energy, Richland Operations Office (DOE-RL) assigned several listed waste codes to the ERA spoils pile. The spoils area was covered with plastic and aggregate to allow continued operation of the trenches without flushing residual contaminants into the groundwater. Post-excavation sample results indicated that the ERA successfully reduced contamination in all areas of the trenches, other than the spoils area.

RCRA closure of the process trenches was performed in accordance with the 300 Area Process Trenches Modified Closure Post Closure Plan (DOE-RL 1995). An independent registered professional engineer was tasked to review the 300-FF-1 remedial action activities to ensure that the TSD closure met the WAC 173-303-610 performance standards. The permit was closed with post-closure requirements.

Code: UPR-300-29	Classification: Accepted
Names: UPR-300-29; Release to the Process Sewer	Reclassification: Final Closed Out (8/13/1998)
Type: Unplanned Release	Start Date: 1/1/1975
Status: Inactive	End Date: 1/1/1975

Description: This site originated in the Waste Acid System in the 333 Building and was routed to the 300 Area Process Trench.

Location: UPR-300-28 originated as leaks in the PVC chemical waste piping system in the 333 Building. The UPR was routed to the 300 Area Process Trench.

Release Description: Leak testing of the system revealed three leaks in the PVC piping system. In addition, one leak was found in the incoming nitric acid supply line.

Related Sites/Structures: UPR-300-29 was associated with the PVC chemical waste drain piping system in the 333 Building and the 300 Area Process Trench.

Waste Type: Chemicals

Waste Description: The waste consisted of an unknown quantity of waste etch acids containing hydrofluoric, nitric, sulfuric, and chromic acids with copper, uranium, and zirconium in solution.

Closure Info: Final (8/13/1998): CERCLA remediation activities were initiated in July 1997 and completed in February 1998. Remediation of the 300 Area Process Trenches included removal and disposal of bird screens covering the trenches, demolition and disposal of the headworks structure

located at the southern end of the trenches, demolition and disposal of the blockhouse structure, and excavation and disposal of contaminated soil that accounted for several unplanned release waste sites.

In 1991, an expedited response action (ERA) was performed to reduce the migration of radioactive and inorganic (heavy metals) contaminants to groundwater. This was accomplished by excavating contaminated sediments in the south end of the trenches, using them to fill in the north end of the trenches, and immobilizing them. The ERA uniformly excavated approximately 0.3 meters (1ft) and 1.3 meters (4 ft) of contaminated soil from the sides and bottom of each trench, respectively. The contaminated material was stockpiled in the northwest corner of the west trench and the north end of the east trench (referred to as a spoils area). Based on process history, the Part A submitted by the U.S. Department of Energy, Richland Operations Office (DOE-RL) assigned several listed waste codes to the ERA spoils pile. The spoils area was covered with plastic and aggregate to allow continued operation of the trenches without flushing residual contaminants into the groundwater. Post-excavation sample results indicated that the ERA successfully reduced contamination in all areas of the trenches, other than the spoils area.

RCRA closure of the process trenches was performed in accordance with the 300 Area Process Trenches Modified Closure Post Closure Plan (DOE-RL 1995). An independent registered professional engineer was tasked to review the 300-FF-1 remedial action activities to ensure that the TSD closure met the WAC 173-303-610 performance standards. The permit was closed with post-closure requirements.

Code:	UPR-300-30	Classification:	Accepted
Names:	UPR-300-30; Acid Release to the Process Sewer	Reclassification	Final Closed Out (8/13/1998)
Type:	Unplanned Release	Start Date:	1/1/1975
Status:	Inactive	End Date:	1/1/1975
Description:	The release originated at the Waste Acid System in the 333 Building and was routed to 300 Area Process Trench.		
Location:	UPR-300-30 originated in the 333 Building and was routed to the 300 Area Process Trench.		
Release Description:	A chemical reaction occurred when a carbonate-bearing solution was added to the waste acid solution. This caused foaming and eventually an overflow of the process tanks that discharged to the process sewer.		
Related Sites/Structures:	UPR-300-30 was associated with the waste receiving tank and chemical processing tanks in the 333 Building and the 300 Area Process Trench.		
Waste Type:	Chemicals		
Waste Description:	The waste consisted of a small quantity of waste etch acids and spent film chemicals containing hydrofluoric, nitric, sulfuric, and chromic acids.		
Closure Info:	Final (8/13/1998): CERCLA remediation activities were initiated in July 1997 and completed in February 1998. Remediation of the 300 Area Process Trenches included removal and disposal of bird screens covering the trenches, demolition and disposal of the headworks structure located at the southern end of the trenches, demolition and disposal of the blockhouse structure, and excavation and disposal of contaminated soil that accounted for several unplanned release waste sites.		

In 1991, an expedited response action (ERA) was performed to reduce the migration of radioactive and inorganic (heavy metals) contaminants to groundwater. This was accomplished

by excavating contaminated sediments in the south end of the trenches, using them to fill in the north end of the trenches, and immobilizing them. The ERA uniformly excavated approximately 0.3 meters (1ft) and 1.3 meters (4 ft) of contaminated soil from the sides and bottom of each trench, respectively. The contaminated material was stockpiled in the northwest corner of the west trench and the north end of the east trench (referred to as a spoils area). Based on process history, the Part A submitted by the U.S. Department of Energy, Richland Operations Office (DOE-RL) assigned several listed waste codes to the ERA spoils pile. The spoils area was covered with plastic and aggregate to allow continued operation of the trenches without flushing residual contaminants into the groundwater. Post-excavation sample results indicated that the ERA successfully reduced contamination in all areas of the trenches, other than the spoils area.

RCRA closure of the process trenches was performed in accordance with the 300 Area Process Trenches Modified Closure Post Closure Plan (DOE-RL 1995). An independent registered professional engineer was tasked to review the 300-FF-1 remedial action activities to ensure that the TSD closure met the WAC 173-303-610 performance standards. The permit was closed with post-closure requirements.

Code:	UPR-300-32	Classification:	Accepted
Names:	UPR-300-32; Acid Leaks at the 333 Building	Reclassification	Final Closed Out (7/23/2003)
Type:	Unplanned Release	Start Date:	1/1/1974
Status:	Inactive	End Date:	1/1/1974
Description:	The site has been remediated and closed out.		
Location:	UPR-300-32 occurred within the uranium bearing system in Building 333 and was routed to the 300 Area Process Pond.		
Release Description:	Leak testing of the system revealed one leak in the piping, three leaking transfer pumps, and five leaks in the uranium mill tank.		
Related Sites/ Structures:	UPR-300-32 was associated with piping, transfer pumps, the uranium mill tank at the 333 Building, and the 300 Area Process Pond.		
Waste Type:	Chemicals		
Waste Description:	The waste consisted of an unknown quantity of uranium etch acids containing nitric and sulfuric acid with uranium in solution.		
Closure Info:	Interim (7/23/2003): Remediation activities at the 316-1 South Process Pond site began in 1997 with excavating trenches around the periphery of the 316-1 site. Trenching was performed to assess the lateral extent of contamination. The majority of remedial excavation and disposal activities were conducted in 1999 and 2000. Excavation at the site involved removing the overburden (scraped surface) soils and contaminated soils. The contaminated soil was transported to the ERDF for disposal. Based on field screening, overburden materials and comingled soil identified as potentially clean were placed in stockpiles for potential use as backfill. Soil samples were collected adjacent to utility poles located in the 316-1 site. Where these samples indicated contaminant concentrations above the cleanup criteria, the soil was removed and the area immediately backfilled and compacted with clean material to maintain the integrity of the utility pole. Excavation and disposal of the 316-1 South Process Pond remediation waste was completed in June 2000. The filter backwash pond (WIDS site 300 RFBP) was a lobe on east side of the process pond. During remediation, soil was primarily removed from the area on the west side of the process pond, near the pond inlet. The two north-south parallel soil berms inside the pond were removed. Areas to the south and west of the original pond boundaries were also removed during remediation. The general elevation at the		

bottom of the excavation used for analysis was 111.3 meters (365 ft) upon completion. The excavation depth was approximately 5.7 meters (19 ft).

Code: UPR-300-33 **Classification:** Accepted
Names: UPR-300-33; Waste Leak at the 333 Building **Reclassification:** Final Closed Out (7/23/2003)
Type: Unplanned Release **Start Date:** 1/1/1974
Status: Inactive **End Date:** 1/1/1974

Description: The site has been remediated and closed out.

Location: UPR-300-33 occurred in the acid drain system and incoming acid fill line in the 333 Building and was routed to the 300 Area Process Pond.

Release Description: A leak test in the chemical waste drain system revealed 16 leaks from the 333 Building to the 334-A Building. Additionally, 5 leaks were found in the incoming acid fill lines (presumably nitric or sulfuric acid system).

Related Sites/ Structures: UPR-300-33 was associated with the acid drain system and acid fill lines in the 333 Building and the 300 Area Process Pond.

Waste Type: Chemicals

Waste Description: The waste consisted of an unknown quantity of waste etch acids containing hydrofluoric, nitric, and chromic acids with copper, uranium, and zirconium in solution.

Closure Info: Interim (7/23/2003): Remediation activities at the 316-1 South Process Pond site began in 1997 with excavating trenches around the periphery of the 316-1 site. Trenching was performed to assess the lateral extent of contamination. The majority of remedial excavation and disposal activities were conducted in 1999 and 2000. Excavation at the site involved removing the overburden (scraped surface) soils and contaminated soils. The contaminated soil was transported to the ERDF for disposal. Based on field screening, overburden materials and comingled soil identified as potentially clean were placed in stockpiles for potential use as backfill. Soil samples were collected adjacent to utility poles located in the 316-1 site. Where these samples indicated contaminant concentrations above the cleanup criteria, the soil was removed and the area immediately backfilled and compacted with clean material to maintain the integrity of the utility pole. Excavation and disposal of the 316-1 South Process Pond remediation waste was completed in June 2000. The filter backwash pond (WIDS site 300 RFBP) was a lobe on east side of the process pond. During remediation, soil was primarily removed from the area on the west side of the process pond, near the pond inlet. The two north-south parallel soil berms inside the pond were removed. Areas to the south and west of the original pond boundaries were also removed during remediation. The general elevation at the bottom of the excavation used for analysis was 111.3 meters (365 ft) upon completion. The excavation depth was approximately 5.7 meters (19 ft).

Code: UPR-300-34 **Classification:** Accepted
Names: UPR-300-34; Release to the Process Pond **Reclassification:** Final Closed Out (7/23/2003)
Type: Unplanned Release **Start Date:** 1/1/1973
Status: Inactive **End Date:** 1/1/1975

Description: The site has been remediated and closed out.

Location: UPR-300-34 was the result of the failed limestone neutralization tank at the 333 Building causing the acid stream to be routed to the Process Pond, north of the 300 Area.

-
- Release Description:** On August 1, 1973, failure of the limestone neutralization tank resulted in a discharge of acidic waste solutions to the ground beneath the tank (see 300-21) and the routing of the acid waste to the process pond. The spent etch acid solution potential contaminants are described in the Waste Characterization Report for Phase II of the Decontamination and Inspection Plan for the 333 Building and the 334-A Facility. Potential contaminants of concern are those generated by the 333 N-Fuels WATS processes. These can include nitrate and sulfate salts of hexavalent chromium, uranium, copper, aluminum, beryllium, nickel, manganese, hexafluorozirconates, and iron. The potential acids involved include nitric acid, sulfuric acid, and hydrofluoric acid.
- Related Sites/ Structures:** UPR-300-34 was associated with the 333 Building, the limestone neutralization tank (see Site Code 300-21), the 300 Area Process Sewer, and the 316-1 Process Pond and UPR-300-32 through UPR-300-37.
- Process Description:** Prior to August, 1973, spent etch acids from the 333 N-Fuels manufacturing process drained via a polyvinyl chloride (PVC) line in the pipe trench (see 300-258) to an underground 14,380 liter (3800 gallon) tank (see WIDS 300-21) on the east side of the 333 Building. The waste acid was then pumped to an overhead waste acid storage tank (see WIDS 334 TFWAST) and from there it was pumped via a 5.1 centimeters. (2 inches.) PVC pipe in the Pipe Trench to the 313 Building for neutralization and waste disposal. On August 1, 1973, the spent etch acid waste solutions were rerouted to the process sewer which discharged to the 300 Area Process Pond pending the replacement of the failed underground waste acid receiving tank (WIDS 300-21). Sodium hydroxide was added to the Process Sewer during each discharge of spent acid solutions to neutralize (i.e. in-line) the waste acid solutions. pH control was used to maintain the discharges from the Process Sewer at a high pH.
- The 334-A Facility was put into service in January 1975 with two acid receiving tanks (see WIDS 334-A-TK-B and C). The 334-A Facility received the spent etch acid solutions from the 333 Building via drain pipes in the Pipe Trench. In-line neutralization in the Process Sewer was discontinued with the availability of the 334-A Facility. The site of the limestone neutralization tank was partially excavated during removal of the failed tank. It is assumed that some of the acid-contaminated soil beneath the tank was removed and the subsoil area was neutralized with water and sodium bicarbonate. Records for the leak cleanup activities are being sought. The subsoil site was partially excavated for the installation of the foundation of the 334-A Facility. The 334-A Facility included a below grade tank pit area with three tanks, pumps, and associated piping (see 334-A-TK-B and 334-A-TK-C).
- Waste Type:** Chemicals
- Waste Description:** An unknown quantity of waste etch acids were discharged to the soil. The waste etch acids contained hydrofluoric, nitric, and chromic acids with copper, uranium, and zirconium in solution.
- Closure Info:** Interim (7/23/2003): Remediation activities at the 316-1 South Process Pond site began in 1997 with excavating trenches around the periphery of the 316-1 site. Trenching was performed to assess the lateral extent of contamination. The majority of remedial excavation and disposal activities were conducted in 1999 and 2000. Excavation at the site involved removing the overburden (scraped surface) soils and contaminated soils. The contaminated soil was transported to the ERDF for disposal. Based on field screening, overburden materials and comingled soil identified as potentially clean were placed in stockpiles for potential use as backfill. Soil samples were collected adjacent to utility poles located in the 316-1 site. Where these samples indicated contaminant concentrations above the cleanup criteria, the soil was removed and the area immediately backfilled and compacted with clean material to maintain the integrity of the utility pole. Excavation and disposal of the 316-1 South Process Pond remediation waste was completed in June 2000. The filter backwash pond (WIDS site 300 RFBP) was a lobe on east side of the process pond. During remediation, soil was primarily removed from the area on the west side of the process pond, near the pond inlet. The two north-south parallel soil berms inside the pond were removed. Areas to the south and west of the

original pond boundaries were also removed during remediation. The general elevation at the bottom of the excavation used for analysis was 111.3 meters (365 ft) upon completion. The excavation depth was approximately 5.7 meters (19 ft).

Code: UPR-300-35	Classification: Accepted
Names: UPR-300-35; Leak at the 333 Building	Reclassification: Final Closed Out (7/23/2003)
Type: Unplanned Release	Start Date: 1/1/1973
Status: Inactive	End Date: 1/1/1973

Description: The site has been remediated and closed out.

Location: UPR-300-35 occurred in the acid overflow alarm system behind Tank 32 in the 333 Building Uranium Bearing Acid Facility and in a uranium bearing acid transfer pump. The unplanned release was routed to the 300 Area Process Pond (316-1).

Release Description: A leak was discovered in the overflow alarm system in the uranium mill tank. The uranium acid transfer pump was also discovered to be leaking.

Related Sites/Structures: UPR-300-35 was associated with the overflow alarm system in uranium mill Tank 32, a uranium-bearing acid transfer pump, 316-1 South Process Pond and UPR-300-32 through UPR-300-37.

Waste Type: Chemicals

Waste Description: The waste consisted of an unknown quantity of uranium-bearing etch acids containing nitric and sulfuric acids with uranium in solution.

Closure Info: Interim (7/23/2003): Remediation activities at the 316-1 South Process Pond site began in 1997 with excavating trenches around the periphery of the 316-1 site. Trenching was performed to assess the lateral extent of contamination. The majority of remedial excavation and disposal activities were conducted in 1999 and 2000. Excavation at the site involved removing the overburden (scraped surface) soils and contaminated soils. The contaminated soil was transported to the ERDF for disposal. Based on field screening, overburden materials and comingled soil identified as potentially clean were placed in stockpiles for potential use as backfill. Soil samples were collected adjacent to utility poles located in the 316-1 site. Where these samples indicated contaminant concentrations above the cleanup criteria, the soil was removed and the area immediately backfilled and compacted with clean material to maintain the integrity of the utility pole. Excavation and disposal of the 316-1 South Process Pond remediation waste was completed in June 2000. The filter backwash pond (WIDS site 300 RFBP) was a lobe on east side of the process pond. During remediation, soil was primarily removed from the area on the west side of the process pond, near the pond inlet. The two north-south parallel soil berms inside the pond were removed. Areas to the south and west of the original pond boundaries were also removed during remediation. The general elevation at the bottom of the excavation used for analysis was 111.3 meters (365 ft) upon completion. The excavation depth was approximately 5.7 meters (19 ft).

Code: UPR-300-36	Classification: Accepted
Names: UPR-300-36; Acid Leak at the 333 Building	Reclassification: Final Closed Out (7/23/2003)
Type: Unplanned Release	Start Date: 1/1/1973
Status: Inactive	End Date: 1/1/1973

Description: The site has been remediated and closed out.

Location: UPR-300-36 occurred in the acid drain system and incoming nitric acid lines of the 333 Building. The waste was routed to 316-1, 300 Area Process Pond.

Release Description: Leak testing of the acid drain system showed nine leaks. Four leaks were also found in the incoming nitric acid lines.

Related Sites/ Structures: UPR-300-36 was associated with the acid drain system and incoming nitric acid lines in the 333 Building Waste Acid System, 316-1, the South Process Pond and UPR-300-32 through UPR-300-37.

Waste Type: Chemicals

Waste Description: The waste consisted of an unknown quantity of waste etch acids containing hydrofluoric, nitric, and chromic acids with copper, uranium, and zirconium in solution.

Closure Info: Interim (7/23/2003): Remediation activities at the 316-1 South Process Pond site began in 1997 with excavating trenches around the periphery of the 316-1 site. Trenching was performed to assess the lateral extent of contamination. The majority of remedial excavation and disposal activities were conducted in 1999 and 2000. Excavation at the site involved removing the overburden (scraped surface) soils and contaminated soils. The contaminated soil was transported to the ERDF for disposal. Based on field screening, overburden materials and comingled soil identified as potentially clean were placed in stockpiles for potential use as backfill. Soil samples were collected adjacent to utility poles located in the 316-1 site. Where these samples indicated contaminant concentrations above the cleanup criteria, the soil was removed and the area immediately backfilled and compacted with clean material to maintain the integrity of the utility pole. Excavation and disposal of the 316-1 South Process Pond remediation waste was completed in June 2000. The filter backwash pond (WIDS site 300 RFBP) was a lobe on east side of the process pond. During remediation, soil was primarily removed from the area on the west side of the process pond, near the pond inlet. The two north-south parallel soil berms inside the pond were removed. Areas to the south and west of the original pond boundaries were also removed during remediation. The general elevation at the bottom of the excavation used for analysis was 111.3 meters (365 ft) upon completion. The excavation depth was approximately 5.7 meters (19 ft).

Code: UPR-300-37	Classification: Accepted
Names: UPR-300-37; 333 Building Leaks	Reclassification: Final Closed Out (7/23/2003)
Type: Unplanned Release	Start Date: 1/1/1972
Status: Inactive	End Date: 1/1/1972

Description: The site has been remediated and closed out.

Location: UPR-300-37 occurred in the 333 Building Waste Acid System and was routed to the 316-1, 300 Area Process Pond.

Release Description: Leak testing of the waste line revealed several large and numerous small leaks that discharged directly to the process sewer.

Related Sites/ Structures: UPR-300-37 was associated with acid tank drains in the 333 Building Waste Acid System and the 316-1, 300 Area Process Pond and UPR-300-32 through UPR-300-37.

Waste Type: Chemicals

Waste Description: The waste consisted of an unknown quantity of waste etch acids containing hydrofluoric, nitric, and chromic acids with copper, uranium, and zirconium in solution.

Closure Info: Interim (7/23/2003): Remediation activities at the 316-1 South Process Pond site began in 1997

with excavating trenches around the periphery of the 316-1 site. Trenching was performed to assess the lateral extent of contamination. The majority of remedial excavation and disposal activities were conducted in 1999 and 2000. Excavation at the site involved removing the overburden (scraped surface) soils and contaminated soils. The contaminated soil was transported to the ERDF for disposal. Based on field screening, overburden materials and comingled soil identified as potentially clean were placed in stockpiles for potential use as backfill. Soil samples were collected adjacent to utility poles located in the 316-1 site. Where these samples indicated contaminant concentrations above the cleanup criteria, the soil was removed and the area immediately backfilled and compacted with clean material to maintain the integrity of the utility pole. Excavation and disposal of the 316-1 South Process Pond remediation waste was completed in June 2000. The filter backwash pond (WIDS site 300 RFBP) was a lobe on east side of the process pond. During remediation, soil was primarily removed from the area on the west side of the process pond, near the pond inlet. The two north-south parallel soil berms inside the pond were removed. Areas to the south and west of the original pond boundaries were also removed during remediation. The general elevation at the bottom of the excavation used for analysis was 111.3 meters (365 ft) upon completion. The excavation depth was approximately 5.7 meters (19 ft).

Code:	UPR-300-47	Classification:	Accepted
Names:	UPR-300-47; 309 Building; Ethylene Glycol Release; Glycol Spill from the 309 Chiller System	Reclassification	Final Closed Out (8/13/1998)
Type:	Unplanned Release	Start Date:	1/1/1993
Status:	Inactive	End Date:	1/1/1993
Description:	The release site was the sump in the machinery room at the 309 Building. The release site was cleaned up and waste generated during the cleanup was disposed of properly on May 7, 1993.		
Location:	UPR-300-47 originated at the number 3 water chiller, drained to the sump, and discharged to the process sewer in the 309 Building.		
Release Description:	On April 30, 1993 at approximately 1:30 a.m., a leak from the 309 Building cooling system was identified. About 2:00 a.m., the automatic sump pump in the 309 Building was turned off. The sump had collected the ethylene glycol and discharged approximately 800 gallons (3,030 liters) of 38 percent ethylene glycol solution to the process sewer before being turned off. At approximately 3:45 a.m. operations personnel observed green liquid coming from the process trench weir box. The release was due to failure of the expansion joint in the number 3 water chiller.		
Related Sites/ Structures:	UPR-300-47 was associated with the 309 Building cooling system, sump, process sewer and process trenches (316-5).		
Waste Type:	Chemicals		
Waste Description:	The waste consisted of 38 percent ethylene glycol solution.		
Closure Info:	Final (8/13/1998): CERCLA remediation activities were initiated in July 1997 and completed in February 1998. Remediation of the 300 Area Process Trenches included removal and disposal of bird screens covering the trenches, demolition and disposal of the headworks structure located at the southern end of the trenches, demolition and disposal of the blockhouse structure, and excavation and disposal of contaminated soil that accounted for several unplanned release waste sites.		

In 1991, an expedited response action (ERA) was performed to reduce the migration of radioactive and inorganic (heavy metals) contaminants to groundwater. This was accomplished

by excavating contaminated sediments in the south end of the trenches, using them to fill in the north end of the trenches, and immobilizing them. The ERA uniformly excavated approximately 0.3 meters (1ft) and 1.3 meters (4 ft) of contaminated soil from the sides and bottom of each trench, respectively. The contaminated material was stockpiled in the northwest corner of the west trench and the north end of the east trench (referred to as a spoils area). Based on process history, the Part A submitted by the U.S. Department of Energy, Richland Operations Office (DOE-RL) assigned several listed waste codes to the ERA spoils pile. The spoils area was covered with plastic and aggregate to allow continued operation of the trenches without flushing residual contaminants into the groundwater. Post-excavation sample results indicated that the ERA successfully reduced contamination in all areas of the trenches, other than the spoils area.

RCRA closure of the process trenches was performed in accordance with the 300 Area Process Trenches Modified Closure Post Closure Plan (DOE-RL 1995). An independent registered professional engineer was tasked to review the 300-FF-1 remedial action activities to ensure that the TSD closure met the WAC 173-303-610 performance standards. The permit was closed with post-closure requirements.

Code:	UPR-600-15	Classification:	Accepted
Names:	UPR-600-15; Contaminated Material found at 618-4; UN-600-15	Reclassification	Final No Action (7/12/2004)
Type:	Unplanned Release	Start Date:	1/1/1979
Status:	Inactive	End Date:	1/1/1979
Description:	The release site was an area of soil outside the entrance to the 618-4 Burial Ground. A new fence around the 618-4 Burial Ground was built in 1974. However, the fence was installed in a new location that did not include the location of the fuel elements. The discovered release site was outside the new boundary of the 618-4 burial ground. The previous fenced area included the release site.		
Location:	UPR-600-15 occurred in an area of soil running north and south of the west boundary fence of the 618-4 Burial Ground in the 600 Area.		
Release Description:	Depleted uranium fuel elements were improperly discarded outside the entrance to the 618-4 Burial Ground. They were found 9/20/1979.		
Related Sites/ Structures:	UPR-600-15 was associated with the 618-4 Burial Ground.		
Waste Type:	Chemicals		
Waste Description:	The contamination came from buried fuel elements containing 0.15 percent uranium-235. A dose rate of 4,000 millirads/hour was detected on the soil surface.		
Closure Info:	Final: Depleted uranium fuel elements were improperly discarded outside the entrance to the 618-4 Burial Ground. They were found 9/20/1979.		
	The 618-4 Burial Ground was excavated between 1998 and 2003. The remediation activity included the area where the fuel elements had been located.		

300-FF-2

Code:	300 RLWS	Classification:	Accepted
Names:	300 RLWS; 300 Area Radioactive Liquid Waste Sewer; 300 Area RLWS	Reclassification	None
Type:	Radioactive Process Sewer	Start Date:	1/1/1979
Status:	Inactive	End Date:	1/1/1998

Description: The inactive 300 Area Radioactive Liquid Waste Sewer (RLWS) consists of a network of underground, stainless-steel pipe, double-encased with reinforced-fiberglass or plastic pipe as secondary containment. The sewer system was divided into three subsites. Subsite 1 was the portions of the RLWS sewer that were associated with 300 Area buildings except for the 309 building. It was remediated and reclassified to Final closed Out. Subsite 2 was the portion of the sewer from the 309 building to the 340 facility. It was remediated and reclassified to Final closed Out. Subsite 3 is the portions of piping that were required to remain in place, due to adjacent active facilities.

The system drained into the 340 Vault facility. Leak detection systems were attached inside the outer encasement. Fifteen valve boxes were spaced along the gravity-drained pipeline between waste generating facilities and the 340 Vault. The west leg of the RLWS collected discharge from the 329, 326, 325, 325-A and 327 buildings. The east leg collected effluent from the 324 building. Both legs join at valve box VB-8, between the 307 basins and the 340 Building. From VB-8 the flow drained to VB-9, and from VB-9 effluent drained to the 340 Vault. Generating facilities were isolated from the RLWS by closed valves outside of each facility. The 340 Vault tanks and the 340-A tanks were also valve-isolated from the RLWS.

On October 1, 1998, the 300 RLWS was isolated from the 340 Complex and waste generating facilities. The 340 Complex was demolished in 2011.

Location: The underground pipeline segments are located beneath a large portion of the 300 Area, connecting the 325, 325-A, 324, 326, 327, and 329 Buildings with the 340 Facility Complex.

Release Description: An Occurrence Report was issued stating that on 04/26/12, at approximately 0951 hours, a Washington Closure Hanford (WCH) subcontractor tasked with removing and size reducing utility lines located near the 327 Building in the 300 Area was utilizing an excavator equipped with a shear attachment to reduce exposed, deactivated steam lines for their eventual disposal. Located near the steam lines being reduced was an exposed deactivated Radiological Liquid Waste System (RLWS) line. While size reducing the steam line into four and five foot sections, the excavator operator inadvertently cut the RLWS line. Although the immediate work area was posted as a Contamination Area (CA), the inadvertent breaching of the RLWS line was unanticipated; therefore, the applicable radiological controls were not in place for the RLWS line upon it being breached. Upon breaching the RLWS line, work was stopped and radiological control personnel responded to the area to conduct surveys and verify radiological boundaries.

Related Sites/ Structures: Structures associated with the system include the 324, 325, 325-A, 326, 327, and 329 Buildings and the 340 Complex. Valve boxes VB-1 through VB-15 regulate flow through the system. From VB-9, the RLWS flows into the 340 Vault tanks. At each generating facility, instrumentation and a valve connect the Retention Process Sewer (RPS) to the RLWS. Prior to RLWS isolation in 1998, if the instrumentation detected activities in RPS from waste higher than the alarm point, the valve routed the RPS waste into the RLWS. A transfer station at the 307 retention basins was also available to route RPS waste to the RLWS.

Process Description: The sewer system was designed to transfer radioactive liquid wastes from various generating facilities to the 340 Complex. The 340 Complex received and sampled the effluent. High

activity effluent was transferred to the 200 Area for storage and disposal.

The original radioactive liquid waste sewer (300 RRLWS) was put into service in 1953 to convey higher activity wastes from sluice pots and designated sinks in the chemical and metallurgical laboratories to storage tanks in the 340 Building. In 1960, a process waste disposal system consisting of an 8-cm (3-in.)-diameter single-walled carbon steel transfer line (300 RLWS:2) was added to handle liquid radioactive wastes from the 309 Building. In approximately 1974, the decision was made to upgrade the original radioactive waste sewer from a single-walled stainless steel pipe to a double-walled pipe. This project was completed in 1979. The original radioactive waste sewer was abandoned in place and became known as the RRLWS. The replacement radioactive liquid waste sewer has been given the site code 300 RLWS:1. Also in 1979, a batch discharge control policy was implemented. Facilities had to obtain written permission to discharge to the 300 RLWS in order to prevent excessive quantities of waste and radiological activity levels from accumulating in the 340 Complex.

Waste Type: Process Effluent

Waste Description: The sewer received radioactive liquid waste from various 300 Area research and development laboratories. Wastes consisted of radioactive effluent with small quantities of various chemicals, decontamination solutions, acids and bases. Effluent was typically derived from Hanford Site groundwater samples, tank waste samples, contaminated sediments, destructive examination of nuclear fuels, R&D process wastes, and residual waste from waste treatment studies. The waste was sampled at the 340 complex and stored for less than 90 days. Waste was then transported to the 200 West Area for storage or disposal.

This Site has the Following SubSites:

Code: 300 RLWS:1

Names: 300 RLWS:1; 300 Area Radioactive Liquid Waste Sewer Segments Excluding 309 Building Sewer

Code: 300 RLWS:2

Names: 300 RLWS:2; 309 Contaminated Sewer; Radioactive Sewer from 309 Building to 340 Facility

Code: 300 RLWS:3

Names: 300 RLWS:3; Retained Sections of the Radioactive Liquid Waste Sewer and 309 Process Sewer

Code: 300 RLWS:1

Classification: Accepted

Names: 300 RLWS:1; 300 Area Radioactive Liquid Waste Sewer Segments Excluding 309 Building Sewer

Reclassification: Final Closed Out (9/9/2015)

Type: Radioactive Process Sewer

Start Date: 1/1/1979

Status: Inactive

End Date: 10/1/1998

Description: Subsite 1 was remediated in 2014 and reclassified to Final Closed Out in 2015. It was the segments of the process sewer throughout the 300 Area that are not associated with the 309 building (segments associated with the 309 building are described in 300 RLWS:2). The 300 RLWS waste site consisted of a network of underground pipelines that drained to the 340 Complex. On October 1, 1998, the 300 RLWS was isolated from the 340 Complex and waste generating facilities. The 340 Complex was demolished in 2011.

Location: The underground pipeline system is located beneath a large portion of the 300 Area, connecting the 325, 325-A, 324, 326, 327, and 329 Buildings with the 340 Facility Complex.

Related Sites/Structures: The 300 RLWS pipeline is associated with the 340 Facility and the Retention Process Sewer (300-214).

Process Description: The radioactive liquid waste sewer (RLWS) was a network of underground, double-encased stainless-steel pipe (encased in reinforced-fiberglass or plastic pipe as secondary containment) that drained to the 340 Complex. Leak detection systems were attached inside the outer encasement. Fifteen valve boxes are spaced along the gravity-drained pipeline between waste generating facilities and the 340 Vault. The west leg of the RLWS collected discharges from the 329, 326, 325, 325-A and 327 buildings. The east leg collected effluent from the 324 building. Both legs join at valve box VB-8, between the 307 basins and the 340 Building. From VB-8 the flow drained to VB-9, and from VB-9 effluent drained to the 340 Vault. Generating facilities are isolated from the RLWS by closed valves outside of each facility. The 340 Vault tanks and the 340-A tanks are also valve-isolated from the RLWS.

The sewer system was designed to transfer radioactive liquid wastes from various 300 Area research and development laboratories to the 340 Complex. The waste was sampled at the 340 Complex and stored for load out to the 200 Area double-shell tanks. High activity effluent was transferred (via truck or rail) to the 200 Area for storage and disposal.

As part of the 1953 laboratory expansion projects, the 307 Retention Basins, the Retention Process Sewer (RPS) and the original Radioactive Liquid Waste Sewer (RLWS) were constructed. The RPS drained to the 307 Retention Basins, and retention waste above discharge limits was diverted to the 340 vault tanks via the RLWS. In 1993, Project W-345 re-lined the basins and provided a batch release capability.

The 340 Complex received and sampled the 300 Area radioactive liquid waste. Waste routed by the RLWS was accumulated and stored in two underground tanks. The waste was stored for less than 90 days. It was transferred to the 200 Areas by rail car for storage and disposal. Retention process sewer waste is collected at the 340 complex in the 307 retention basins, sampled, and discharged to the process sewer. Waste exceeding discharge criteria is held for transport to the 200 Areas.

Closure Info: Final (9/9/2015): Waste Sites 300 RLWS:1, 300 RLWS:2, 300 RRLWS:1 and 300-214:1 were remediated as a group and documented in CVP-2015-00011. The final action 300 Area ROD for the 300 RLWS:1, 300 RLWS:2, 300 RRLWS:1, and 300-214:1 subsites established RAOs based on an industrial land use.

Remediation of the 300 RLWS:1, 300 RLWS:2, 300 RRLWS:1, and 300-214:1 subsites, performed from March 26 through December 15, 2014, consisted of removal and disposal of contaminated soil, gravel, pipe, and concrete. The excavation resulted in approximately 15,071 bank cubic meters (19,712 bank cubic yards) of contaminated soil and debris being disposed at the Environmental Restoration Disposal Facility. No overburden soil was salvaged from the 300 RLWS:1, 300 RLWS:2, 300 RRLWS:1, and 300-214:1 subsites excavation and no staging pile areas were utilized.

Pipeline segments of the west side of the 308 Building and within the 340 Complex were removed with the demolition and excavation of the facilities.

Remediation of the 300 RLWS:1 and 300 RLWS:2 subsites was performed from March 26 to December 15, 2014. Approximately 9,321 bank cubic meters (BCM) (12,191 bank cubic yards [BCY]) of excavated materials were removed and direct loaded for disposal at the ERDF.

Remediation of the 300 RRLWS:1 subsite was performed from June 3 through December 15, 2014. Approximately 106 BCM (139 BCY) of excavated materials were removed and direct loaded for disposal at ERDF.

Remediation of the 300-214:1 subsite was performed from May 13 through November 20, 2014. Approximately 5,643 BCM (7,381 BCY) of excavated materials were removed and direct

loaded for disposal at ERDF.

No elevated radiological readings (above background levels) were detected within 300 RLWS:1, 300 RLWS:2, 300 RRLWS:1, and 300-214:1 excavation areas.

Because some piping systems were located immediately adjacent to each other, there was a significant overlap of the 300 RLWS:1, 300 RLWS:2, 300 RRLWS:1, and 300-214:1 subsite excavations. Therefore, the volumes for each subsite excavation were estimated.

The SubSite is Part Of:

Code: 300 RLWS

Names: 300 RLWS; 300 Area Radioactive Liquid Waste Sewer; 300 Area RLWS

Code: 300 RLWS:2

Classification: Accepted

Names: 300 RLWS:2; 309 Contaminated Sewer;
Radioactive Sewer from 309 Building to 340
Facility

Reclassification: Final Closed Out (9/9/2015)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: Subsite 2 has been remediated and Final Closed Out. It was the segments of the Radioactive Liquid Waste Sewer (RLWS) associated with the 309 building. It was made a separate subsite because the 309 Contaminated Sewer system was similar to the Retired Radioactive Liquid Waste Sewer (RRLWS) in construction, but significantly older than the 300 RLWS. It is a separate system from the RRLWS and RLWS and handled a narrower range of contaminants than the RRLWS/RLWS. By 1984, the 309 Building had been isolated from the sewer by cutting and capping the pipes.

Location: The pipeline extended from the northeast corner of the 309 Building, to the north, to the 340 Complex.

Process Description: The piping carried the waste from the PRTR (309 Bldg) to the holdup tanks and to the 340 Complex. The 309 Contaminated Sewer is a network of single-walled steel and vitrified clay piping that connected 309 Building radioactive contaminated effluent to the 309 building tank farm (sitecodes 309-TW-1, 309-TW-2 and 309-TW-3). In 1960, a separate 8 centimeter (3-in.) diameter carbon steel line was installed to connect the 309 Building tank farm to the 340 facility tanks. Contaminated effluent from the 309 Building facility was designed to be directed to the PRTR transfer waste tank farm (also known as TW Tank or Holdup Tank). It was located to the northeast of the 309 Building reactor containment vessel. The tank farm consisted of three underground tanks on a buried concrete pad, an adjacent concrete valve pit, and underground piping. The tanks are commonly known as TW-1, TW-2, and TW-3. The 309 Retention Waste Sewer was designed to accommodate potentially contaminated effluent and is connected to the 300 Area RPS (300-214) west of the 324 Building.

Closure Info: Final (9/9/2015): Waste Sites 300 RLWS:1, 300 RLWS:2, 300 RRLWS:1 and 300-214:1 were remediated as a group and documented in CVP-2015-00011. The final action 300 Area ROD for the 300 RLWS:1, 300 RLWS:2, 300 RRLWS:1, and 300-214:1 subsites established RAOs based on an industrial land use.

Remediation of the 300 RLWS:1, 300 RLWS:2, 300 RRLWS:1, and 300-214:1 subsites, performed from March 26 through December 15, 2014, consisted of removal and disposal of contaminated soil, gravel, pipe, and concrete. The excavation resulted in approximately 15,071 bank cubic meters (19,712 bank cubic yards) of contaminated soil and debris being disposed at the Environmental Restoration Disposal Facility. No overburden soil was salvaged from the

300 RLWS:1, 300 RLWS:2, 300 RRLWS:1, and 300-214:1 subsites excavation and no staging pile areas were utilized.

Pipeline segments of the west side of the 308 Building and within the 340 Complex were removed with the demolition and excavation of the facilities.

Remediation of the 300 RLWS:1 and 300 RLWS:2 subsites was performed from March 26 to December 15, 2014. Approximately 9,321 bank cubic meters (BCM) (12,191 bank cubic yards [BCY]) of excavated materials were removed and direct loaded for disposal at the ERDF.

Remediation of the 300 RRLWS:1 subsite was performed from June 3 through December 15, 2014. Approximately 106 BCM (139 BCY) of excavated materials were removed and direct loaded for disposal at ERDF.

Remediation of the 300-214:1 subsite was performed from May 13 through November 20, 2014. Approximately 5,643 BCM (7,381 BCY) of excavated materials were removed and direct loaded for disposal at ERDF.

No elevated radiological readings (above background levels) were detected within 300 RLWS:1, 300 RLWS:2, 300 RRLWS:1, and 300-214:1 excavation areas.

Because some piping systems were located immediately adjacent to each other, there was a significant overlap of the 300 RLWS:1, 300 RLWS:2, 300 RRLWS:1, and 300-214:1 subsite excavations. Therefore, the volumes for each subsite excavation were estimated.

The SubSite is Part Of:

Code: 300 RLWS

Names: 300 RLWS; 300 Area Radioactive Liquid Waste Sewer; 300 Area RLWS

Code: 300 RLWS:3

Classification: Accepted

Names: 300 RLWS:3; Retained Sections of the Radioactive Liquid Waste Sewer and 309 Process Sewer

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The site consists of those portions of the 300 RLWS, 300 Area Radioactive Liquid Waste Sewer that are being retained due to adjacent active facilities.

Location: This section is primarily along Spruce Street between Wisconsin Avenue and Riverview Loop.

Related Sites/ Structures: Associated with the 309, 324, 325, 325-A, 326, 327, and 329 Buildings

The SubSite is Part Of:

Code: 300 RLWS

Names: 300 RLWS; 300 Area Radioactive Liquid Waste Sewer; 300 Area RLWS

Code: 300 RRLWS

Classification: Accepted

Names: 300 RRLWS; Contaminated Sewer; Crib Waste System; Intermediate Level Radioactive Liquid Waste System; 300 Area Retired Radioactive

Reclassification: None

Liquid Waste Sewer System; 300 Area Retired
RLWS

Type: Radioactive Process Sewer **Start Date:** 1/1/1954
Status: Inactive **End Date:** 1/1/1975

Description: The RRLWS is the original sewer network of 5, 8, 10, and 15 centimeter (2, 3, 4, and 6-inch) single-walled stainless steel piping and carbon steel fittings buried between 3 and 6 meters (10 and 20 feet) below grade. No isolation valves, radiation monitors, or other leak detection capabilities were built into the original (RRLWS) system. Since the potential for corrosion was low, the retired system was abandoned in place. A separate 8 centimeter (3 inch) carbon steel transfer line was installed in 1960 to connect the 309 Building to the 340 Complex.

The 300 Area Retired Radioactive Liquid Waste Sewer (RRLWS) site has been divided into two subsites. Subsite 1 was remediated and Final Closed Out. It was the portions of the RRLWS piping that have been removed. Subsite 2 is the portions of the RRLWS that have been retained.

Location: The unit lies below grade throughout the 300 Area. Brass monuments locate several of the sewer clean outs. The piping connected the 308, 309, 324, 325, 326, 327, and 329 Buildings with the 340 Facility Complex.

Related Sites/ Structures: Structures associated with the retired system include the 340 Complex, which received and treated effluent from the sewer system; the 308, 309, 324, 325, 326, 327, and 329 Buildings, which discharged effluents to the system; and the brass monuments located above eleven of the sewer clean outs. It sewer is also associated with UPR-300-1 and UPR-300-11.

Process Description: While in service, the system transferred radioactive liquid waste from laboratories and facilities in the 300 Area to the 340 Complex for sampling and disposal. The sewer was retired in 1975 and does not receive effluent.

Waste Type: Process Effluent

Waste Description: The unit received radioactive wastes from various 300 Area facilities including the fuel fabrication and research and development laboratories. Wastes discharged to the sewer included water and small quantities of chemicals, decontamination solutions, aqueous fuel fabrication solutions, acids, and bases. Wastes discharged to the system by the 309 Building included reactor operational wastes such as resin backwash and deionizing solutions. The system handled approximately 100,000 liters per month (25,000 gallons per month) of beta-gamma waste with an upper radiation level of 20 rem per hour. A 1992 video survey shows that highly corrosive materials were transferred by this system. The survey also suggests that mercury contamination and high radiation levels are present.

This Site has the Following SubSites:

Code: 300 RRLWS:1

Names: 300 RRLWS:1; Removed Sections of the 300 Area Retired Radioactive Liquid Waste Sewer System

Code: 300 RRLWS:2

Names: 300 RRLWS:2; Retained Sections of the 300 Area Retired Radioactive Liquid Waste Sewer System

Code: 300 RRLWS:1 **Classification:** Accepted

Names: 300 RRLWS:1; Removed Sections of the 300 Area Retired Radioactive Liquid Waste Sewer System **Reclassification:** Final Closed Out (9/9/2015)

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive

End Date:

Description: The site has been remediated and reclassified to Final Closed Out. It consisted of the portions of the 300 RRLWS, 300 Area Retired Radioactive Liquid Waste Sewer System that were removed prior to 2015. There were brass monuments located above eleven of the sewer clean out pipes.

Location: The sewer system was located throughout the 300 Area. This piping connected the 308, 309, 324, 325, 326, 327, and 329 Buildings to the 340 Facility Complex.

Release Description: A history of leakage from the piping system began during construction of the west addition of the 327 Building in 1958 and 1959. During 1976, the system was leak tested as part of the new upgrades being performed at the 327 Building. This leak test resulted in replacement of the entire system. Excavation for the west addition building foundation and basin uncovered contaminated soil that was attributed to the system. The leak was determined to have been the result of the use of carbon steel transition pieces in the stainless steel system. This leak was located near the southwest corner of the building near Pecan Street. Several truckloads of radioactive material that measured up to 500 mRad/hr, were removed to 300 Area burial grounds.

Related Sites/Structures: Structures associated with the retired system include the 340 Complex, which received and treated effluent from the sewer system, as well as the 308, 324, 325, 326, 327, and 329 Buildings, which discharged effluents to the system.

Process Description: The 300 Area RRLWS consisted of a network of underground single-walled stainless steel pipelines that drained to the 340 Complex. The site was divided into two subsites. The 300 RRLWS:1, is the sections of the Retired Radioactive Liquid Waste Sewer System that were removed. 300 RRLWS:2 is the sections of the Retired Radioactive Liquid Waste Sewer System that were retained in place due to interference with active facilities or utilities.

Closure Info: Final (9/9/2015): Waste Sites 300 RLWS:1, 300 RLWS:2, 300 RRLWS:1 and 300-214:1 were remediated as a group and documented in CVP-2015-00011. The final action 300 Area ROD for the 300 RLWS:1, 300 RLWS:2, 300 RRLWS:1, and 300-214:1 subsites established RAOs based on an industrial land use.

Remediation of the 300 RLWS:1, 300 RLWS:2, 300 RRLWS:1, and 300-214:1 subsites, performed from March 26 through December 15, 2014, consisted of removal and disposal of contaminated soil, gravel, pipe, and concrete. The excavation resulted in approximately 15,071 bank cubic meters (19,712 bank cubic yards) of contaminated soil and debris being disposed at the Environmental Restoration Disposal Facility. No overburden soil was salvaged from the 300 RLWS:1, 300 RLWS:2, 300 RRLWS:1, and 300-214:1 subsites excavation and no staging pile areas were utilized.

Pipeline segments of the west side of the 308 Building and within the 340 Complex were removed with the demolition and excavation of the facilities.

Remediation of the 300 RLWS:1 and 300 RLWS:2 subsites was performed from March 26 to December 15, 2014. Approximately 9,321 bank cubic meters (BCM) (12,191 bank cubic yards [BCY]) of excavated materials were removed and direct loaded for disposal at the ERDF.

Remediation of the 300 RRLWS:1 subsite was performed from June 3 through December 15, 2014. Approximately 106 BCM (139 BCY) of excavated materials were removed and direct loaded for disposal at ERDF.

Remediation of the 300-214:1 subsite was performed from May 13 through November 20, 2014. Approximately 5,643 BCM (7,381 BCY) of excavated materials were removed and direct loaded for disposal at ERDF.

No elevated radiological readings (above background levels) were detected within 300 RLWS:1, 300 RLWS:2, 300 RRLWS:1, and 300-214:1 excavation areas.

Because some piping systems were located immediately adjacent to each other, there was a significant overlap of the 300 RLWS:1, 300 RLWS:2, 300 RRLWS:1, and 300-214:1 subsite excavations. Therefore, the volumes for each subsite excavation were estimated.

The SubSite is Part Of:

Code: 300 RRLWS

Names: 300 RRLWS; Contaminated Sewer; Crib Waste System; Intermediate Level Radioactive Liquid Waste System; 300 Area Retired Radioactive Liquid Waste Sewer System; 300 Area Retired RLWS

Code: 300 RRLWS:2

Classification: Accepted

Names: 300 RRLWS:2; Retained Sections of the 300 Area Retired Radioactive Liquid Waste Sewer System

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The site consists of those portions of the 300 RRLWS, 300 Area Retired Radioactive Liquid Waste Sewer System that are being retained due to their proximity to adjacent active facilities.

Location: These sections of piping are located primarily along Spruce Street between Wisconsin Avenue and Riverview Loop.

Process Description: The system transferred radioactive liquid waste from fuel fabrication and research and development laboratories including 308, 309, 324, 325, 326, 327, 329 Buildings to the 340 Complex for sampling and disposal.

The SubSite is Part Of:

Code: 300 RRLWS

Names: 300 RRLWS; Contaminated Sewer; Crib Waste System; Intermediate Level Radioactive Liquid Waste System; 300 Area Retired Radioactive Liquid Waste Sewer System; 300 Area Retired RLWS

Code: 300 VTS

Classification: Accepted

Names: 300 VTS; In-Situ Vitrification (ISV) Test Site; 300 Area Vitrification Test Site

Reclassification: Final Closed Out (2/18/2014)

Type: Process Unit/Plant

Start Date: 1/1/1983

Status: Inactive

End Date: 1/1/1986

Description: The site has been remediated and Interim Closed Out in 2006. It was considered Final Closed Out in 2014. The site consisted of a mobile pilot plant trailer, a Terra-Vit melter structure, Large-Scale ISV Off-Gas Assembly (hood), storage units, metal sheds, sea-land units, spare parts and other support structures, most of which were removed in 1999. The vitrified material and soil, miscellaneous equipment, empty barrels, crates, metal scaffolding, and pallets of miscellaneous materials were also removed. Five in-situ vitrified monoliths (up to 1000 tons) had been in the ground on the west side of the site. One of these monoliths was located below the Large-Scale Off-Gas Hood. Within the test site was a fenced concrete pad, where an electrical substation had been located. The electrical transformer pad had been a separate waste site, 300-231, Vitrification Test Site Transformer Pad, Substation C3-S15, but it was Consolidated with 300 VTS. The transformers have been removed.

Location:	The area was located west of Route Four South, across from the 300 Area and 9 meters (30 feet) south of 618-7 Burial Ground.
Related Sites/ Structures:	The site was associated with the 300 Area Thermal Treatment Research and Development Facilities and the 300-231 electrical transformers.
Process Description:	<p>The site was used in the 1980's and 1990's as a field demonstration site for the melting of soils containing waste simulatates. Tests using PCB's and limited tests with very low levels of radioactivity were conducted at the site.</p> <p>The site was used by Pacific Northwest National Laboratory (PNNL) between 1983 and 1986 as a field demonstration site for in situ vitrification (ISV) of soils containing simulated waste. After the vitrification tests were conducted in the 1980s, all contaminated soil and equipment was removed from the site. In 1993 a large-scale melter (the Terra-Vit) was constructed at the site but never used. During 1998 and 1999 the ISV site was cleaned up by PNNL for transfer to the Bechtel Hanford, Inc. surveillance and maintenance program.</p> <p>In-situ vitrification (ISV) was a thermal treatment process that converted contaminated soils and sludges into a glass and crystalline product. An electrical current was passed among an array of four electrodes imbedded in the contaminated soil or sludge, melting and glassifying it. The process continued outward and downward until the appropriate vitrification depth was obtained.</p> <p>Radioactive mixed waste (RMW) and dangerous waste constituents were stabilized in the glass and crystalline product. Organic contaminants were destroyed by pyrolysis, and the pyrolysis products oxidized as they migrated to the surface. An off-gas assembly was used to collect and treat off-gases to ensure complete containment of the waste materials. PNNL operated four treatability testing units (bench-, engineering-, pilot-, and large-scale). The engineering and bench-scale units were located in the 324 Building. The pilot and large-scale units were transportable within the Hanford Site. The maximum design capacity of the large-scale unit (at the ISV site) was 64,345 liters (17,000 gallons) per day.</p>
Waste Type:	Soil
Waste Description:	The site contains soil and vitrified blocks remaining from testing.
Waste Type:	Soil
Waste Description:	Vitrification was performed on wastes containing americium, plutonium, cesium, cobalt, strontium, and ruthenium. After these tests were performed, the site was cleaned up to regulatory limits and the area released. Other simulated waste tests were performed which produced solid waste materials including five monoliths weighing up to 1000 tons. These large monoliths remain in the ground as of 7/29/98. All simulated in-situ vitrification tests were performed using chemical additives which will require a waste disposition review as part of the site characterization process. Empty ethylene glycol drums remain at the site. Some cooling systems may still contain glycol.
Waste Type:	Equipment
Waste Description:	The site contains excess piping, drums, electrodes, bricks, transformers, HEPA filters, off-gas handling units, cement/grout materials, glass frit, and storage sheds. Some of the material on outside pallets is deteriorating because of weathering.
Closure Info:	Interim (3/6/2006): Remedial action at the 300 VTS site began in December 2004. The ISV melter structure was demolished using mechanical shears. The off-gas containment hood was sheared and sent to ERDF for disposal. The support frame was sheared and the scrap metal recycled. Test equipment and buried vitrified monoliths have been demolished or excavated,

removed from the site, and recycled or disposed. The rubble was then sent to 600-246, (Gravel Pit #9, Inert/Demolition Waste Landfill) for disposal. All rubble met the requirements of the February 2005 inert landfill regulation (Washington Administrative Code [WAC] 173-350-410). Two test trenches were also excavated, the locations of which were based on historical information and geophysical anomalies. No soil contamination, except cesium-137, which was below the RAGs, was found in the test trenches. Debris included graphite electrodes that were sent to ERDF and pipe casings that were recycled.

Final cleanup verification samples were collected on August 22, 2005, to confirm acceptability of residual contaminant concentrations in the soil. Based on the overall footprint of the area and depth of excavation. The site was classified as one shallow zone decision unit.

A total of 83 metric tons (91 US tons) of structural steel was recycled from the demolition of the Terra-Vit melter and off-gas hood support structure. Disposal of the off gas containment structure resulted in 10 metric tons (11 US tons) of material being sent to ERDF. A total of 5,218 metric tons (5,752 US tons) of vitrified soil was excavated and sent to Gravel Pit #9, Inert/Demolition Waste Landfill (600-246) for disposal.

The Cleanup Verification Package for the 300 VTS Waste Site (CVP) has documented that the site was remediated in accordance with the Record of Decision for the 300-FF-2 Operable Unit, Hanford Site (ROD), as modified by the Explanation of Significant Differences for the 300-FF-2 Operable Unit Interim Record of Decision (ESD). Remedial action at the site has achieved the Remedial action objectives (RAOs) and corresponding remedial action goals (RAGs) established in the ROD and the Remedial Design Report/Remedial Action Work Plan for the 300 Area (RDR/RAWP).

Final (2/18/2014): The group of sites were reclassified to Final Closed Out in 2014. They are listed in the 300-FF-2 Record of Decision and meet the criteria for unrestricted landuse.

Code: 300-1	Classification: Accepted
Names: 300-1; Old North Richland Automotive Maintenance Yard	Reclassification: Final No Action (2/18/2014)
Type: Dumping Area	Start Date:
Status: Inactive	End Date:
Description:	In 1998, the site was evaluated and determined to require No Action. In 2014, it was reclassified to Final No Action. The site had been used by North Richland residents to conduct automotive repairs. It was the proposed location of the Environmental and Molecular Sciences Laboratory (EMSL). Surface debris was removed by Pacific Northwest Laboratory (PNL) technicians in late 1993, in preparation for excavations at the proposed EMSL site, which began in April 1994. During excavations, it was discovered that a Native American burial ground is in the area.
Location:	The site is located east of the George Washington Way extension and south of the 300 Area fence line, inside the chained off area.
Waste Type:	Misc. Trash and Debris
Waste Description:	The area was used by North Richland residents to conduct automotive repairs and recreational activities. No evidence exists that radiological contamination may be at the site. Debris removed from the area in late 1993 included empty bottles, lumber, empty cans of automotive oil, 19-liter (5-gallon) cans and buckets, an 46-centimeter (18-inch) wooden wire spool, an automotive front grill, old automotive oil filters, etc.

Closure Info: Interim: The reclassification is documented on form 98-081. Due to the culturally sensitive issues in this area, the decision makers associated with the 300-FF-2 Limited Field Investigation concluded that no further action would be necessary at this site.

Final (2/18/2014): The group of sites is listed in the 300-FF-2 Record of Decision and meet the criteria for unrestricted landuse.

Code: 300-2	Classification: Accepted
Names: 300-2; Contaminated Light Water Disposal; Potential Trench Location #1	Reclassification: Final No Action (5/12/2014)
Type: Trench	Start Date: 1/1/1965
Status: Inactive	End Date: 1/1/1966

Description: The waste site has been evaluated and determined to require No Action. In 2014, the site was reclassified to Final No Action. It was an intentional release of contaminated water to soil in 1965.

Location: The exact location of the waste site is questionable. It is described as being located east of the 309 Building parking lot. 300-2 is one potential location, approximately beneath the demolished 3766 Building. An alternate location is described in sitecode 300-283. One estimated waste site dimensions is documented as 22.86 by 15.24 meters (75 by 50 ft). Another estimate is described in the Focused Feasibility Study for the 300-FF-2 Operable Unit as an irregularly shaped trench measuring 103.6 meters (340 ft) long by 85.3 meters (280 ft) wide. Both are estimated dimensions of a disposal event that would have had unknown, or at best, approximate boundaries. The dimensions reported were taken from separate source documents.

Release Description: About 189,250 liters (50,000 gallons) of secondary cooling water and other contaminated water containing 33 millicuries iodine-133 and 12 millicuries iodine-131 were disposed of to ground. About 10 microcuries of alpha emitters (calculated as Pu-239) and about 40 microcuries of non-volatile beta emitters plus rutheniums were transferred to the trench during the first 36 hours of the incident. A small number of short pumpings were made after that, however, the total gallonage and radioisotopic inventory are insignificant in comparison to those during the first 36 hours.

Related Sites/ Structures: 300-2 is associated with sitecode 300-283, another potential location of the disposal trench. 300-283 was evaluated and reclassified to No Action in 2012. The contaminated light water came from the 309 Building also called the Plutonium Recycle Test Reactor (PRTR) - see H-3-11002.

Process Description: Radioactively contaminated water from a 1965 release at the Plutonium Recycle Test Reactor (309 Building) was pumped to the ground to avoid direct discharge to the Columbia River.

Waste Type: Water

Waste Description: About 189,250 liters (50,000 gallons) of secondary cooling water and other contaminated water containing 33 millicuries iodine-133 and 12 millicuries iodine-131 were disposed of to ground. About 10 microcuries of alpha emitters (calculated as plutonium-239) and about 40 millicuries of non-volatile beta emitters plus rutheniums were transferred to the trench during the first 36 hours of the incident. A small number of short pumpings were made after that, however, the total gallonage and radioisotopic inventory are insignificant in comparison to those during the first 36 hours.

Closure Info: Interim (5/8/2013): Because the exact location of the trench cannot be definitively determined, two suspected 300-2 waste site locations were investigated and sampled. The primary 300-2 waste site location is east of the 309 Building parking lot, beneath the location of the former 3766 Building, at Washington State Plane (WSP) coordinates N115607.4/ E594192.2. The

secondary location of the disposal of the contaminated liquid from this incident was described in the Compilation of Historical Information of 300 Area Facilities and Activities document as being located beneath the location of the former 3763 Building. This potential location is 24 meters (79 ft) east of the former 3766 Building at coordinates WSP N115612/E594216.

A third potential location is sitecode 300-283, Contaminated Light Water Disposal Site #2. A test pit for the 300-283 location was sampled at WSP coordinates N115596.6/E594259.7 on April 26, 2012. The 300-283 sample location is approximately 68 meters (223 ft) east of the primary 300-2 waste site coordinates given above. The 300-283 waste site was reclassified as Interim No Action in July 2012, as documented in the Remaining Sites Verification Package for the 300-283, Contaminated Light Water Disposal Site #2.

The confirmatory sampling instructions for the 300-2 waste site directed sampling at each of the two potential 300-2 waste site locations. Two test pits were dug on January 22, 2013. The first test pit was located in the footprint of the demolished 3766 Building at WSP coordinates N115607.4/E594192.2. One discrete soil sample was collected from the base of this test pit at 5.2 meters below ground surface (bgs). The second test pit was located in the footprint of the demolished 3763 Building at WSP coordinates N115612/E594216. One discrete sample was collected from the base of this test pit at 4.6 meters bgs.

Radiological surveying with field instrumentation did not indicate readings above background during excavation and confirmatory sampling of test pit 1 and test pit 2. No additional debris was observed during sampling and no soil staining was noted.

Final (5/12/2014): Two suspected 300-2 waste site locations were investigated and sampled on January 22, 2013. The 300-2 waste site has been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). Evaluation of previous confirmatory sampling results show that the concentrations of COC's meet the CUL's for direct exposure and groundwater protection and river protection and support a residential land use scenario. Institutional controls to prevent uncontrolled drilling or excavation into the deep zone are not required. In accordance with this evaluation, the confirmatory sampling results support a reclassification of the 300-2 waste site to Final No Action.

Code: 300-4	Classification: Accepted
Names: 300-4; DOE 351 Substation Soil Contamination	Reclassification: Final Closed Out (7/28/2015)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:
Description:	The site has been remediated and Closed Out. It consisted of the contaminated soil inside the southwest corner of the fenced, 351 electrical substation. The above grade features of the 351 Substation were removed in October 2014. Building footings, foundations, and high voltage footings remained after the facility demolition.
Location:	The DOE 351 Electrical Substation was located in the 300 Area, north of Ginko St. and west of Alaska Ave. It was north of the demolished 305 Building.
Release Description:	During a routine inspection of the BPA area in 1987, 19 soil samples were collected and analyzed for PCB content. Four of the samples contain PCBs in the range of 1 to 3 milligram/kilogram. Four capacitors (capacitors 3 and 31 north phase and 17 and 18 middle phase) were de-energized and removed in August 1989, because of insulating oil leaks. All soil samples collected when the capacitors were removed showed PCB concentrations of less than 2 milligrams/kilogram. No spills to the soil have been documented by BPA. On October 18, 1990, the removal crew discovered radioactive yellow cake uranium clinging to the below ground portions of the footings.

Process Description: The DOE 351 Substation was operated by the Bonneville Power Administration (BPA) from March 30, 1973 until February 11, 1991, when all BPA equipment was removed. After 1991, the facility was operated by DOE/RL contractors.

Mineral oil containing polychlorinated biphenyls (PCBs) and solvents were used during routine equipment maintenance. No spills to the soil were documented by the Bonneville Power Administration (BPA). Four capacitors (capacitors 3 and 31 north phase and capacitors 17 and 18 middle phase) were de-energized and removed in August 1989 because of insulating oil leaks. There is no evidence, however, that fluid leaked onto the ground from any of the removed capacitors. See analytical results for soil samples.

On October 17, 1990, removal of all BPA equipment was begun. On October 18, 1990 the removal crew discovered radioactive yellow cake uranium clinging to the below ground portions of the footings. The uranium is most likely associated with DOE-RL's fuel fabrication activities in the 300 Area and not any BPA related activities. Work was suspended until the area could be evaluated. Removal of the items (excluding the uranium contaminated footings) was completed on February 11, 1991.

Waste Type: Chemicals

Waste Description: The waste is uranium contaminated soil. According to the referenced document, there is a potential for spillage of polychlorinated biphenyl (PCB) to the soil. This statement was based on four samples that contained PCBs in the range of 1 to 3 milligrams per kilogram. The 300-FF-2 Record of Decision for this site also lists solvents as a potential contaminant.

Closure Info: Final (7/28/2015): Remedial action at the 300-4 waste site began on December 1, 2014, and continued through January 15, 2015. Site remediation focused on removing the below grade features of the 351 Substation and included soil, concrete foundations and footings, basement structures, metal, nonfriable asbestos from electrical ductwork, and vitrified clay piping. The cable vault beneath the 351B Building was also removed and disposed. The remediation extended to an estimated maximum depth of 3.5 meters (11.5 ft) below ground surface, resulting in approximately 5,304 bank cubic meters (BCM) (6,937 bank cubic yards [BCY]) of contaminated soil and debris being removed and disposed at the ERDF. All material was direct loaded from the excavation into ERDF cans for disposal; therefore, no waste staging pile area was created. No overburden material was salvaged for use as backfill material. No anomalies were observed during the remediation. An area of stained soil was observed in the northwest portion of the excavated waste site. One In-Process sample was above cleanup levels for TPH, that resulted in the removal of 543 BCM of additional soil.

No elevated radiological readings were detected.

Code: 300-5	Classification: Accepted
Names: 300-5; 3709A Fire Station; 300 Area Fire Station Fuel Tanks	Reclassification: None
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The site was two underground fuel tanks, the pump island, ancillary piping, and contaminated soil. An unknown quantity of contaminated soil, under the fuel dispensing island at the 3709-A Building (300 Area Fire Station) was discovered on April 10, 1992. The fueling facility consisted of two 1893 liter (500 gallon) underground storage tanks (USTs), one containing unleaded gasoline (Tank 300-FS-15), the other diesel (Tank 300-FS-16), and approximately 9.1 meters (30 feet) of piping that lead to the fuel dispenser and island. The release was due in part

to sections of corroded flex piping (with multiple pinhole size perforations) located directly under the pump island and also possibly from loose pipe/pump fittings. The pump island was removed immediately following the removal of the tanks and piping. Evidence that confirmed the release consisted of petroleum product odors that were detected by personnel immediately following the lifting of the pump island. The release was additionally confirmed by sampling performed during the site assessment. The system was undergoing permanent closure due to a failed tightness test conducted on August 26, 1991. These tanks were removed on April 14, 1992. The site is not marked in the field. Based on maps and descriptions, the site is under a paved portion of the access driveway on the southeast side of 3709A Building. A section of the asphalt has been patched where the tanks were dug up.

Location: The site is in the 300 Area, adjacent to the 3709A Fire Station on the south side, south and west of the east wall of 3709A. From this site it is approximately 28 meters (92 feet) to groundwater monitoring well #399-5-4B.

Release Description: The leaks are associated with two 1890 liter (500 gallon) tanks and were discovered during a tightness test of the tanks in August 1991. One of the tanks contained gasoline and the other, diesel fuel. The release was due in part to sections of corroded flex piping located directly under the pump island and also possibly from loose pipe/pump fittings.

Related Sites/ Structures: The site was associated with the 300 Area Fire Station, also known as building 3709A.

Process Description: The gasoline and diesel tanks were used to refuel vehicles. The leaks were likely caused by corroded flex pipes and leaks in the fittings.

Waste Type: Oil

Waste Description: One of the storage tanks contained gasoline and the other contained diesel fuel.

Code: 300-6	Classification: Accepted
Names: 300-6; 366/366A Fuel Oil Bunkers	Reclassification: Final Closed Out (5/12/2014)
Type: Storage Tank	Start Date: 1/1/1964
Status: Inactive	End Date: 1/1/1998

Description: The waste site has been remediated and Interim Closed Out. In 2014, the site was reclassified to Final Closed Out. Prior to excavation, the oil bunkers had consisted of four separate underground concrete fuel oil tanks (bunkers). It had been a large excavated area with soil staged adjacent to the excavation. The soil will eventually be used as fill. The area was isolated by a rope and orange safety fence.

Location: The site is in the 300 area on the south side of the 3715 and 303-J buildings.

Related Sites/ Structures: The site was related to the 384 Powerhouse, the 384 Powerhouse Fuel Oil Day Tanks #1 and #2 (WIDS Site 300-223), and ancillary piping (300-273).

Process Description: Prior to excavation, the oil bunkers had consisted of four separate underground concrete fuel oil tanks (bunkers). The site was north of a low berm wall (about 0.6 meters [2 feet] tall) and appeared on the surface as a rectangular concrete pad with manhole access plates and equipment and piping on the surface. Bunker 366 was under the west end of the concrete pad, and 366A was under the east end. Fuel oil tanks #1 and #2 were designated 366, while tanks #3 and #4 were designated as 366A.

The soil on the south side of the fuel bunkers appeared black, due to coal residue from the coal storage area that had been located here. Prior to 1964, the 384 Powerhouse was fueled with

coal. The bunkers were installed to store fuel oil for the 384 powerhouse boilers when they were converted to oil burners. The first of the tanks was installed in 1964 to support the first oil-fired boiler at the 384 Powerhouse that same year. The additional three underground fuel oil tanks were constructed between 1970 and 1974 to support the conversion of coal fired boilers to oil. The tanks were originally unlined and used to store Bunker C Oil or Fuel Oil #6. A liner was installed in each tank when the decision was made to utilize #2 Diesel Oil in 1972. In approximately 1980, the powerhouse switched back to Bunker C Oil because of the increased cost of diesel. The liners were left in place.

During the time when #6 fuel was being used, the fuel from the underground tanks was continually heated using closed-loop steam lines in the tanks. The fuel oil was pumped from the main tanks (the bunkers) into the day tanks (site code 300-223) for additional heating prior to use for steam production in the powerhouse. The fuel oil becomes a very thick tar-like substance when left unheated and loses the ability to flow.

In 1991 the liner material had begun to deteriorate and sections of the liner were plugging up the suction heater, causing the pumps to cavitate. Also, the steam coils on the fuel bundles had deteriorated to the point that they were discharging steam into the fuel. There was also a significant build-up of sludge in the bottom of the tanks. A project was then completed to remove all of the sludge from the tanks and remove the liners and the river rock under the liners from the tanks. Several motors, heaters and other equipment pieces were also replaced under the same project. Since they were not required under regulation, neither the rock nor the liners were replaced.

Waste Type: Oil

Waste Description: Prior to the tanks and residual fuel being removed, the bunkers stored product fuel oil for use in the 384 powerhouse boilers.

Closure Info: Interim (1/9/2012): The 300-6 waste site (fuel oil bunkers) was expected to be excavated to groundwater, a depth of approximately 15.8 meters (52 ft) below ground surface (bgs), as necessary to remediate contaminated soil. Remediation of the waste site was performed from August 2 to December 8, 2010. The western portion of the 300-6 waste site excavation did reach the groundwater, and a pool of water remains in the floor of the excavation. The excavation was approximately 15 meters (49.5 ft) deep in the 300-6 west borehole location (when measured to the surface of the pool of water) and approximately 11.5 meters (37.7 ft) deep in the 300-6 east borehole location. The 300-6 and associated waste sites' excavation resulted in approximately 34,770 bank cubic meters (45,477 bank cubic yards) of material removed for disposal at the Environmental Restoration Disposal Facility (ERDF).

Debris (piping and concrete) and soil from the remediation of the 300-6 and associated waste sites were direct loaded to ERDF. No overburden soil stockpiles were associated with the waste sites as a result of remediation, and no anomalies were noted.

The 300-123 UIC was identified as a WIDS waste site. The french drain was removed as part of the layback to remove the contaminated soil at the 300-6 waste site. The french drain consisted of soil and rock that extended to approximately 1.4 meters (4.5 ft) bgs. The existing floor of the 300-6 waste site excavation is approximately 11.3 m (37 ft) bgs.

The 300-65, 300-66, 300-122, and 300-124 UICs were located within the footprint of the 300-6 excavation layback and also removed during the 300-6 excavation. The 3715, 303E and 303J building slabs were removed during the 300-6 waste site excavation because they were located in the excavation layback as well.

The 300-268 site was located within the 300-6 layback area. It was excavated to a depth of 3.0 meters (9.8 ft).

During excavation of the 300-6 waste site, it was verified that the eastern half of the 300-273 waste site pipeline had been previously removed. In addition, as the project conducted test pits along the western half of the 300-273 waste site pipeline right-of-way on November 3, 2010, no pipeline structure was encountered at the elevations presented in the as-built drawings for the pipeline (USAEC 1974). Also in November 2010, the project excavated two test pits along the former 384 Powerhouse foundation within the UPR-300-42 waste site. No below-grade structure was noted, and no visible soil staining was observed, as was expected since the site was reportedly removed in 2009.

During excavation of the 300-6 waste site, it was verified that the eastern half of the 300-273 waste site pipeline had been previously removed. In addition, as the project conducted test pits along the western half of the 300-273 waste site pipeline right-of-way on November 3, 2010, no pipeline structure was encountered at the elevations presented in the as-built drawings for the pipeline. Also in November 2010, the project excavated two test pits along the former 384 Powerhouse foundation within the UPR-300-42 waste site. No below-grade structure was noted, and no visible soil staining was observed, as was expected since the site was reportedly removed in 2009 with the demolition of the 384 powerhouse structure.

Final: The 300 Area Fuel Oil bunkers and associated waste sites were remediated in 2010. The excavation extended to groundwater at a depth of 52 feet. The 300-6, 300-123, 300-268, 300-273, and UPR-300-42 waste sites were remediated and have been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). Verification sampling results show that the site meets the CUL's for direct exposure and groundwater protection and river protection and support a residential land use scenario. Contamination that extended into the deep zone (greater than 4.6 meters [15 ft] bgs) has been removed; therefore, institutional controls to prevent uncontrolled drilling or excavation into the deep zone are not required. In accordance with this evaluation, the verification sampling results support a reclassification of the 300-6, 300-123, 300-268, 300-273, and UPR-300-42 waste sites to Final Closed Out.

Code: 300-7	Classification: Accepted
Names: 300-7; Possible Early Burial Ground Site; Undocumented Solid Waste Burial Ground Adjacent to 618-8	Reclassification: Final Closed Out (6/29/2015)
Type: Burial Ground	Start Date:
Status: Inactive	End Date:
Description:	The site has been remediated and Final Closed Out. It was an area with multiple mounds of soil that extended to the north and west from the 300 Area North Parking Lot. It formed an irregular shaped polygon where the north edge of the parking lot is the south edge of the waste site. Scarred areas could be seen in several historical photographs. Surface debris piles were visible and subsurface disturbances were identified with Ground Penetrating Radar. The site was covered with natural vegetation. Some of the visible surface debris consisted of concrete, trash and cables. The area of subsurface anomalies was not marked.
Location:	The site is located north of the 300 Area North Parking Lot, adjacent to and west of the north end of 618-8 Burial Ground. The results of a Global Positioning survey done in 1998 enlarged the footprint of the site.
Related Sites/ Structures:	It is adjacent to and slightly overlaps the 618-8 Burial Ground site.

Process Description: Contamination was identified during the installation of utility poles by the Bonneville Power Administration in 1952 and again in 1980. No official burial site was ever documented at this location. Photographs from the 1950's were examined. A photograph taken in May 1954 shows a large portion of the area in this location had been disturbed in a fan shape with the apex at the southeast corner. Large piles of soil had been placed in the area, now the soil mounds. The large concrete blocks that remain at 300-7 are visible in this photograph.

Waste Type: Construction Debris

Waste Description: The site contains solid construction debris, such as concrete, metallic waste, asbestos, and uranium contamination.

Closure Info: Final (6/29/2015): Remediation of the 300-7 waste site was performed from July 8 through July 31, 2014. Approximately 7,870 bank cubic meters (10,293 bank cubic yards) of excavated materials were removed and loaded for direct disposal at the Environmental Restoration Disposal Facility (ERDF). According to the post-excavation civil survey the maximum depth of the waste site excavation was approximately 2.0 meters (6.6 ft). However, due to the mounded nature of the waste site surface, some areas of the 300-7 waste site excavation extended to a depth of 3.8 meters (12.5 ft), below the original ground surface. Excavated materials consisted of soil, gravel, wood, steel, wire, and concrete debris. In addition, one truck battery, two old steel cart wheels, and two metal pails were removed from the 300-7 excavation and disposed at ERDF. No overburden materials were salvaged from the 300-7 waste site excavation; therefore, there is no overburden pile associated with the 300-7 waste site. No staging pile areas were utilized during 300-7 waste site remediation.

Code: 300-8

Classification: Accepted

Names: 300-8; Aluminum Recycle Storage Area; Aluminum Shavings Area; North of Railroad and North of 618-8

Reclassification: Final Closed Out (2/18/2014)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The has been remediated and Interim Closed Out. The Aluminum Recycle Staging area consisted of six irregularly shaped Soil Contamination Areas located along the railroad track north of 300 Area. The contamination areas were on both sides of the railroad track and separated by unposted dirt roads.

Location: The site was located north of 300 Area and 618-8. It was west of the 316-5 Process Trenches. It consisted of a posted Soil Contamination Area adjacent to the rail spur. Another posted Soil Contamination Area was north of the rail road spur, across a dirt road.

Related Sites/ Structures: The 300-9; Early Burial Ground site was located within the mapped boundaries of the 300-8; Aluminum Recycle Storage Area; Aluminum Shavings Area. The 300-8 waste site was remediated in 2004 and 2005 by removing the layer of soil containing the aluminum shavings and was disposed at ERDF. However, the remediation did not include removing material within the boundaries of the 300-9 waste site.

Process Description: The site was used to stage scrap metal from the 300 Area. In 1962, recycling of aluminum scrap began. The material was staged until a sufficient quantity was collected for offsite salvage vendors to propose bids. The accumulated metal piles and the process of loading it onto rail cars scattered metal shavings over a large area. Some of the metal was radiologically contaminated with low levels of uranium and beryllium.

Waste Type: Misc. Trash and Debris

Waste Description: The area was used to stage uranium contaminated aluminum scrap to be sold to salvage contractors. Other contaminants include aluminum-silicon alloy and beryllium contaminated aluminum.

Closure Info: Interim (10/28/2005): The remedial activity was conducted from December 2004 through May 2005. Initially, material within the site boundaries was removed to a depth of 0.3 meters (1 foot). Following excavation, geophysical surveys and ground-truthing excavations indicated that significant quantities of metal shavings, on the order of one to a few per square meter, remained at the site. Consequently, an additional 0.3 meters (1 foot) of material was removed from the entire area. Following this excavation, additional geophysical surveys were performed at thirty-five randomly located 3- by 3 meters (10 by 10 feet) test areas within the waste site boundaries. Within the 324 square meters (3,488 square feet) surveyed, fewer than 10 discrete pieces of metallic debris were detected. Based on these results and ground-truthing excavations, it was concluded that remediation was complete. Excavation of the site included the removal of small quantities of miscellaneous metal construction-type debris (e.g., nuts, bolts), aluminum metal shavings, and soil. No indications of liquid waste disposal or land disposal restricted materials were observed during excavation.

The Cleanup Verification Package for the 300-8 Waste Site (CVP-2005-00007), documented that remedial action objectives and goals have been achieved and meet the cleanup standards specified in the Record of Decision for the 300-FF-2 Operable Unit (ROD) and Remedial Design Report/Remedial Action Work Plan for the 300 Area (RDR/RAWP). Remedial actions were performed to support future industrial land use and to protect groundwater and the Columbia River.

The contaminated materials, approximately 39,750 metric tons (43,820 U.S. tons) of material, was removed for disposal at the ERDF. Results of post-remediation geophysical surveys demonstrated that only trace levels of metallic debris remained at the site. The remaining soil at the site has been sampled, analyzed, and evaluated. Results indicate that the site supports future land uses that can be represented (or bounded) by the industrial land-use scenario and poses no threat to groundwater or the Columbia River. Consequently, the 300-8 waste site is verified to be remediated in accordance with the ROD.

Because residual soil concentrations indicated that cleanup levels for more stringent land uses may have been achieved for the 300-8 waste site, a supplemental evaluation was performed against the unrestricted land-use RAGs established for the 300 Area in the ESD. This evaluation demonstrated that the results of verification sampling do not preclude any future uses (as bounded by the rural-residential scenario) and allow unrestricted use of shallow zone soils.

Final (2/18/2014): The group of sites were reclassified to Final Closed Out in 2014. They are listed in the 300-FF-2 Record of Decision and meet the criteria for unrestricted landuse.

Code: 300-9	Classification: Accepted
Names: 300-9; Possible Early Burial Ground Sites North of RR and North of 618-8; Solid Waste Burial Ground	Reclassification: Final Closed Out (5/13/2015)
Type: Burial Ground	Start Date: 1/1/1943
Status: Inactive	End Date: 1/1/1945

Description: The waste site was remediated in 2014 and reclassified to Final Closed Out. The location of the site referred to as the Early Burial Ground is not well documented. It has been confused with the 618-8 Burial Ground and the Undocumented Solid Waste Burial Ground (site code 300-7)

located adjacent to 618-8. A suspect location was identified in the 300-FF-2 Technical Baseline Report using a historical aerial photograph (negative #2530 taken in 1954), but additional review of the information determined that site to be a borrow pit. Other historical aerial photographs (negative #9619 taken in 1962) were studied and determined two other suspect areas. These locations were selected for geophysical surveys during the 300-FF-2 Operable Unit Limited Field Investigation activities. Later, an aerial photograph taken in 1948 was found (picture number 89711).

Location: The exact location of this site has never been confirmed. It was only described as a trench located 686 meters (750 yards) north of the 300 Area. Hand drawn sketches in two documents (HW-39076 and a letter report from AJ Stevens to AR Keen) indicate the location is north of the 300 area, east of the railroad tracks. The current location of the 300-9 waste site was established based on additional historical aerial photography showing that the suspect area extends eastward beyond the area investigated in 1995 during the limited field investigation. The current boundaries of the 300-9 waste site are less than 100 m (330 ft) from the approximate locations described by Paas in 1955.

Related Sites/ Structures: The 300-9 Early Burial Ground was located within the mapped boundaries of the 300-8; Aluminum Recycle Storage Area; Aluminum Shavings Area. The 300-8 waste site was remediated in 2004 and 2005 by removing the layer of soil containing the aluminum shavings and was disposed at ERDF. However, the remediation did not include removing material within the boundaries of the 300-9 waste site.

Waste Type: Misc. Trash and Debris

Waste Description: Actual burial inventory is unknown. Process knowledge suggests the waste would consist of the uranium contaminated waste from very early 300 Area experimental processes.

Waste Type: Misc. Trash and Debris

Waste Description: Uranium contaminated aluminum shavings are scattered on the surface of the site. Other surface contaminants may include aluminum-silicon alloy and beryllium contaminated aluminum.

Closure Info: Final (5/13/2015): Two suspect sites were surveyed with Ground Penetrating Radar equipment in 1995. No concentration of anomalies was detected at either site. The current location of the 300-9 waste site was established based on additional historical aerial photography showing that the suspect area extends eastward beyond the area investigated during the limited field investigation. Another geophysical survey was performed at the 300-9 site in January 2005 to locate and map subsurface features. Data were collected using ground-penetrating radar and electromagnetic induction. The survey revealed a shallow historic depression with very shallow side slopes (3:1 to 4:1) near the eastern corner of the site. A distinctive layer within the depression, approximately 1 meter (3 ft) below ground surface [bgs], was also observed and interpreted as possible capping material, though subsequently determined to be a thin gravel layer during confirmatory sampling. A second anomalous area was observed southwest of the haul road transecting the site and consisted of suspect metallic material less than 0.5 meter (1.6 ft) bgs underlain by a highly reflective geologic horizon at approximately 2 meters (6.5 ft) bgs. No other anomalies indicative of a possible burial ground were observed.

Confirmatory sampling of the 300-9 waste site was performed on March 28, 2006. Excavation at the eastern geophysical anomaly (test trench 1) revealed an approximately 0.15 meter (6 in.) thick gravel layer between predominant sand layers, but no features suggestive of a burial ground were identified. Excavation continued to approximately 3 meters (10 ft) bgs, where a native soil sample was collected. Excavation at the southwestern geophysical anomaly (test trench 2) revealed scrap aluminum tubing in the shallow subsurface (less than 0.9 meter [3 ft] bgs), consistent with the debris associated with the 300-8 waste site. Field radiological instrumentation indicated elevated alpha and beta particle activity on the aluminum debris, and a sample was collected from soil contained within the tubing. Native soil was encountered at

approximately 0.9 meter (3 ft) bgs, where a soil sample was collected. No indications of a historic burial ground were identified at the locations of the geophysical anomalies.

Remediation of the 300-9 waste site began on November 23, 2014, and continued through December 4, 2014. The remediation extended to an approximate maximum depth of 1.5 meters (5 ft) bgs, resulting in approximately 3,891 bank cubic meters (5,089 bank cubic yards) of soil being removed for disposal at ERDF. Some laboratory thimbles were also removed and disposed. All material was direct loaded from the excavation; therefore, no waste staging pile area was generated.

Code: 300-10	Classification: Accepted
Names: 300-10; Burial Trench West of Process Trenches	Reclassification: Final Closed Out (2/20/2014)
Type: Burial Ground	Start Date: 1/1/1950
Status: Inactive	End Date:

Description: This waste site was remediated in 1997 and reclassified to Closed Out. The northwest corner terminates very near a dirt road that intersects the midpoint of the west 316-5 Process Trenches. A field walkdown done on 11/18/94 reported the site appeared as a soil covered field with natural vegetation. The site has been remediated and closed out, and revegetated with crested wheatgrass. It was considered Final Closed Out in 2014.

Location: The site is adjacent to the west side of the 316-5 Process Trenches.

Closure Info: Interim: Waste site 300-10 was initially excavated to a depth of 1.2 meters (4 ft) below grade based on the 300-FF-1 remedial design. The "Confirm as Clean" procedure documented in the RDR/RAWP (DOE-RL 1997) was then implemented to remove 0.3 meters (1 ft) lifts as necessary to complete the excavation. After completion of the 1.2 meter (4 ft) excavation and each subsequent 0.3 meter (1 ft) lift, a radiological survey of the remaining soil was performed to determine if additional removal was required. Only one additional 0.3 meter (1 ft) lift was required based on the radiological survey results. An initial set of verification samples was collected following the radiological survey results. Contaminated soil removed from waste site 300-10 was transported to the Environmental Restoration Disposal Facility for disposal. In addition to the radiological surveys, a metal detector was used to identify metal shavings in the soil. Although radiological screening instruments did not indicate soil contamination, the metallic anomalies were noted after completion of the 1.2 meter (4 ft) and 0.3 meter (1 ft) lifts. Metallic anomalies consisting of nails, iron scraps, and aluminum shavings were excavated by hand and transported to the Environmental Restoration Disposal Facility for disposal. None of the identified metallic objects were radiologically contaminated. After completion of the metal detector surveys, a second set of verification samples were collected.

Analysis of verification samples of the remaining soil show the area to be below cleanup standard levels. The area no longer poses a threat to human health or the environment and a December 17, 1997 (date approved) TPA change form (Control Number 116) lists the site as Closed Out.

Final (2/20/2014): This group of sites is considered Final Closed Out in the 300-FF-2 Record of Decision and meets the criteria for unrestricted landuse.

Code: 300-11	Classification: Accepted
Names: 300-11; 382 Pumphouse UGT; 382-1; Pumphouse Underground Gasoline Tank	Reclassification: Final No Action (1/15/2015)

Type: Unplanned Release **Start Date:** 1/1/1943

Status: Inactive **End Date:** 1/1/1992

Description: The waste site has been reclassified to Final No Action. The site was releases to the soil that were discovered following the removal of the 382-1 underground gasoline tank in September 1992. The site was not marked in the field.

Originally, there were 3 tanks at this location, Tanks 382-1, 382-2, and 382-3. The 382-2 and 382-3 tanks were excavated and removed in 1994. A full site assessment (WAC 173-360-385) was performed for these tanks. There was no contamination found in the soil.

Location: The site is in the 300 Area, near the intersection of Wisconsin and Apple Streets. The three underground gasoline storage tanks were near the northwest corner of the 382 Pumphouse Building. The 382-1 tank was located at the northwest corner of the building. The 382-2 tank was located on the west side of the 382 Building about 3 meters (10 feet) south of the 382-1. The 382-3 tank was located on the west side of the 382 Building 4 meters (13 feet) west of the 382-2 fuel tank.

Release Description: The tank had failed a leak test. When tank 382-1 was removed, an unknown quantity of contaminated soil was discovered under the south end of the tank. The south end of the excavation corresponded to the fill-pipe end of the tank. Soil samples and field-screening samples were analyzed using an immunoassay field test kit for petroleum products. Soil collected from the south end of the tank excavation contained greater than 1,000 parts-per-million (ppm) Total Petroleum Hydrocarbons (TPH). Soil collected from the north end of the tank excavation was below the regulatory limit of 100 ppm TPH.

Related Sites/ Structures: These tanks (382-1, 382-2, and 383-3) were related to the adjacent 382 Pumphouse Building.

Process Description: The underground gasoline fuel storage tanks were used to store leaded and unleaded gasoline for use by the emergency gasoline engine powered pumps in the 382 Building.

Waste Type: Oil

Waste Description: The gasoline fuel storage tanks were used to store leaded and unleaded gasoline for use by the emergency gasoline engine powered pumps in the 382 Building. Tank 382-1 was removed in 1992. Tanks 382-2 and 382-3 were removed in 1994.

Closure Info: Final (1/15/2015): On June 4, 2013, a pothole was excavated to a depth of 5.5 meters (18ft). Blue plastic was encountered at approximately 2 meters (6ft) below grade. The blue plastic had been placed here following tank removal in 1992. An in-process sample (J1TRR8) was collected at the depth of 5.5 meters (18 ft), below ground surface. In-process sampling results indicated that gasoline and VOCs were undetected at this location. No gasoline odor was observed during excavation and no VOCs were detected with field monitoring equipment.

The 300-11 waste site was remediated between June 2 and July 22, 2014, during remediation of the adjacent 300-15:3 pipelines. The 300-11 waste site was excavated to a depth of 4.6 meters (15ft). A second in-process sample (J1TX26) was collected at this depth. Sampling results indicated that gasoline and VOCs were undetected. Screening for volatile organic compounds was performed during and immediately following remediation. No VOCs were detected within the 300-11 excavation area. Radiological monitoring was performed during the duration of the 300-11 waste site excavation with no radiological activity detected in the field during remediation activities.

Code: 300-15 **Classification:** Accepted

Names: 300-15; 300 Area Process Sewer System **Reclassification** None

TEDF) was Consolidated with 300-15.

Process Description: There are three primary contributors to the 300 Area process sewer wastewater: purified potable water, equipment cooling water, and contributors with some chemical contamination. Flows from buildings are combined into one or two main waste pipes before exiting the building. Steam production activities accounted for a significant part of the waste water produced. These activities produced large quantities of waste cooling water and significant amounts of waste brine solution. A smaller portion of the flow is from laboratory sinks and drains connected to the sewer.

Past activities from the fuel fabrication facilities in the 313 and 333 Buildings were the most significant sources of chromium, copper, uranium, nitrate, sulfate, and fluoride ions, as well as caustics and degreasing solvents (e.g. perchloroethylene and 1,1,1-trichloroethane) entering the process sewer. In 1978, administrative controls were established that required the end-of-pipe discharge to meet drinking water standards. In 1985 additional administrative controls were placed into effect to gain greater control of the waste water. These included discontinuing chemical discharges from chemical and biological laboratories, fuels fabrication, photographic processing, and many maintenance operations. In 1995 discharges to the 316-5 trenches were halted. Instead, discharges were transferred via a new pipeline (see 600-352-PL) to the 300 Area TEDF (310 Facility) for treatment and discharge to the Columbia River.

Waste Type: Process Effluent

Waste Description: Process sewer waste typically included: potable water, cooling water, precipitation runoff (which includes 4 stormwater catch basins next to the 3701U building, H-3-304714 Sht. 3 Rev. 1), waste brine solution (sodium chloride with magnesium salts), chromium, copper, uranium nitrate, sulfate, and fluoride ions. Effluent is traditionally composed of three sources: potentially contaminated effluent, sanitary water, and cooling water. Nearly 70 percent of the process sewer effluent results from once-through cooling for HVAC systems, pumps, compressors, and other equipment. More than 80 percent of the discharge points contribute less than 19 liters per minute (5 gallons per minute) of effluent to the process sewer. Discharge rates were reported as high as 4900 liters per minute (1300 gallons per minute) in the 1980's, while current figures estimate flow rates of less than 760 liters per minute (200 gallons per minute). Four chief chemical contaminants in the process sewer have been lead, silver, acetone, and cyanide. Silver was most likely contributed from the 3705 photographic processes. Cyanide compounds were detected downstream of the 384 powerhouse, and are attributable to either coal dust or the regeneration salt and softening resin used in water conditioning. Most of the lead is believed to have entered the process sewer from prior 3709 building (paint shop) processes. Acetone releases appear to have occurred in small quantities when labware was washed.

This Site has the Following SubSites:

Code: 300-15:1

Names: 300-15:1; Active and Retained Portions of 300 Area Process Sewer

Code: 300-15:2

Names: 300-15:2; 300 Area Process Sewer North of Apple St.

Code: 300-15:3

Names: 300-15:3; 300 Area Process Sewer South of Apple St.

Code: 300-15:4

Names: 300-15:4; North Side of 3906 and 3906-B Lift Stations

Code: 300-15:5

Names: 300-15:5; 310 Retention Transfer System

Code: 300-15:6
Names: 300-15:6; 305A Sewer Process and 24 Inch Process Sewer Main North of Apple Street

Code: 300-15:1 **Classification:** Accepted

Names: 300-15:1; Active and Retained Portions of 300 Area Process Sewer **Reclassification:** None

Type: Process Sewer **Start Date:**

Status: Active **End Date:**

Description: The subsite is the portions of the 300 Area Process Sewer that are being retained and are considered active.

Location: The subsite is a network of active underground piping extending throughout the 300 Area.

Related Sites/ Structures: 600-352-PL and 600-117 are associated with this subsite.

Process Description: There are three primary contributors to the 300 Area process sewer wastewater: purified potable water, equipment cooling water, and contributors with some chemical contamination. Effluent from buildings was combined into one or two main waste pipes before exiting the building. Steam production activities accounted for a significant part of the waste water produced. These activities produced large quantities of waste cooling water and significant amounts of waste brine solution. A smaller portion of the flow was from laboratory sinks and drains connected to the sewer.

The SubSite is Part Of:

Code: 300-15
Names: 300-15; 300 Area Process Sewer System

Code: 300-15:2 **Classification:** Accepted

Names: 300-15:2; 300 Area Process Sewer North of Apple St. **Reclassification:** Final Closed Out (10/5/2015)

Type: Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: Subsite 2 was the inactive, excavated segments of the 300 Area Process sewer that were located north of Apple Street. It was reclassified to Interim Closed Out in 2013. In 2015, it was evaluated and reclassified to Final Closed Out.

Location: This subsite is the network of underground piping extending throughout the 300 Area, located north of Apple Street.

Process Description: There are three primary contributors to the 300 Area process sewer wastewater: purified potable water, equipment cooling water, and contributors with some chemical contamination. Flows from buildings are combined into one or two main waste pipes before exiting the building. Steam production activities accounted for a significant part of the waste water produced. These activities produced large quantities of waste cooling water and significant amounts of waste brine solution. A smaller portion of the flow is from laboratory sinks and drains connected to the sewer.

Closure Info: Interim (3/21/2013): Remediation of the 300-15:2 subsite was performed from July 17, 2012 through January 4, 2013. The subsite was divided into three decision units and a separate

decision unit for the spoil pile areas. The majority of the soil within the footprint of the subsite was excavated to a depth of 0.5 to 4.9 meters (1.6 to 16 ft) below ground surface (bgs). The resulting 44,715.8 bank cubic meters (54,488.3 bank cubic yards) of soil was disposed at the Environmental Restoration Disposal Facility (ERDF). The 300-15 process sewer in or near the 351 substation were retained since they were not accessible. The segments of 300-15 pipelines located within the 618-1 Burial Ground boundary were previously removed and Interim Closed out with the 618-1 Burial Ground waste site (per CVP-2010-00001).

The lengths of excavated pipelines for each 300-15:2 decision unit are: Decision Unit 1= 693.9 meters (2,276.6 ft); Decision Unit 2 = 1,285.7 meters (4,218.2 ft); Decision Unit 3 = 1,212.4 meters (3977.7 ft).

Summary for Final Closure (October 2015) -- Based upon evaluation of the previous subsite reclassification data against the 300 Area ROD cleanup levels, no further RTD is required for 300-15:2 subsite. Evaluation for the 300-15:2, 300 Area Process Sewer North of Apple Street subsite is provided to support reclassification to Final Closed Out. The 300-15:2 subsite was remediated and has been evaluated against the criteria established for the industrial land-use scenario in the 300 Area ROD (EPA 2013) and meets the requirements of the 300-FF-2 RDR/RAWP (DOE-RL 2015). Results indicate that the site supports future land uses that can be represented (or bounded) by the industrial land-use scenario and poses no threat to groundwater or the Columbia River. Because the subsite was remediated to achieve CULs for industrial land use, institutional controls to maintain industrial land use are required. The 300-15:2 subsite are verified to be remediated in accordance with the 300 Area ROD (EPA 2013) and have been reclassified to a status of Final Closed Out (reclassification form 2015-081).

The SubSite is Part Of:

Code: 300-15

Names: 300-15; 300 Area Process Sewer System

Code: 300-15:3

Classification: Accepted

Names: 300-15:3; 300 Area Process Sewer South of Apple St.

Reclassification Final Closed Out (9/9/2015)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: Subsite 3 has been remediated and Final Closed Out. It was the inactive segments of the 300 Area Process Sewer piping that were located south of Apple Street.

Location: This subsite is the network of underground piping extending throughout the 300 Area located south of Apple Street.

Related Sites/ Structures: This piping is associated with the discovery of contaminated soil described in Sitecode 300-34.

Process Description: There are three primary contributors to the 300 Area process sewer wastewater: purified potable water, equipment cooling water, and contributors with some chemical contamination. Effluent from buildings was combined into one or two main waste pipes before exiting the building. Steam production activities accounted for a significant part of the waste water produced. These activities produced large quantities of waste cooling water and significant amounts of waste brine solution. A smaller portion of the flow was from laboratory sinks and drains connected to the sewer.

Closure Info: Final (9/9/2015): Remediation of the 300-15:3 and 300-34 waste sites was performed from January 14, 2014, to March 26, 2015. Approximately 73,961 bank cubic meters (96,737 bank

cubic yards) of excavated materials were removed and direct loaded for disposal at ERDF. The 300-34 (manhole leak) waste site was located within the 300-15:3 subsite excavation. Therefore, the 300-34 waste was included in the 300-15:3 waste site remediation volume. Waste materials consisted of contaminated soil, gravel, pipe, and concrete. No overburden soil was salvaged from the excavations and no staging pile areas were utilized.

During demolition and excavation of the 3709, 3745A, 3745B, 3746, 3746A, 3730, 3621B/C, 3621D, 331D, 331G, 331H, 3706, 308, 321, 323, 382 Complex, 327, 327BA, 326BA, 340 Complex, 338, 337, 337B, 337BA, 3718M, 335, and 336 Buildings, it was noted that portions of the 300-15:3 pipelines had been removed if within the footprint of the building excavation boundaries. One 300-15:3 pipeline segment, less than 10 meters long, remains in-place, south of the 338 Building, due to an interfering active underground electrical line. Sections of the 300-15:3 pipeline north of the 326 Building remain in-place. This pipe was found to be filled with grout and lined. Pipelines associated with the 382 Buildings are remain in-place and connect to the 326 Building. Two sections of 300-15:3 pipeline associated with the 329 Building, south of 3701D Building also remain in-place.

The SubSite is Part Of:

Code: 300-15

Names: 300-15; 300 Area Process Sewer System

Code: 300-15:4

Classification: Accepted

Names: 300-15:4; North Side of 3906 and 3906-B Lift Stations

Reclassification: Final No Action (7/28/2015)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: Subsite 4 has been evaluated and determined to require No Action. It is the north side of the 3906 Lift Station and 3906-B structures. The 3906 and 3906-B lift stations were both isolated and inactivated in late 2012 and demolished in 2013.

Location: The 3906 Lift Station structure was located northeast of the demolished 337 building, south of Locust Road. The 3906-B Lift Station structure was located east of Riverview Loop, near the original 3906 Lift Station structure.

Related Sites/ Structures: The lift station is associated with the 300-257 pipeline (309 Process Sewer to River).

Process Description: The 3906 Lift Station provided a gravity drain collection point in the southeast part of the 300 Area for both the sanitary sewer system and the process sewer system. Waste water was pumped westward, where it could then flow by gravity to the end of the sewage systems. The northern portion of the 3906 facility served the sanitary sewer system. In later years of operation, both portions received process sewer effluent as a result of temporary system reconfigurations that supported utility reroutes.

Closure Info: Final (7/28/2015): Field inspections, scoping surveys, and characterization sampling of the 3906 North and 3906-B Lift Stations indicated that no materials were present that required removal prior to demolition of the structures. The lift stations were outside of the 300 Area industrial radioactive material area. Radiological scoping surveys did not identify any radiological contamination present within either facility. Demolition of the above grade structures for the two lift stations was completed in July 2013. The below-grade portion of the 3906 Lift Station was removed to 0.9 meters (3 ft) below grade. No portion of the 3906-B below-grade structure was removed because of interference from adjacent and active utilities. The debris was removed and disposed of at the Environmental Disposal Facility. No anomalies

were discovered during demolition and post-demolition. The soils displayed no evidence of staining or discoloration.

Based upon facility inspections, process knowledge, and scoping surveys it was determined that characterization of the sludge present in the 3906 North Lift Station and the 3906-B Lift Station was needed to determine if the sludge required removal prior to demolition of the lift stations.

The southern half of the 3906 Lift Station was addressed as part of the 300-257 waste site and has been separately reclassified to Final No Action.

The SubSite is Part Of:

Code: 300-15

Names: 300-15; 300 Area Process Sewer System

Code: 300-15:5

Classification: Accepted

Names: 300-15:5; 310 Retention Transfer System

Reclassification: Final No Action (5/13/2015)

Type: Process Sewer

Start Date: 1/1/1996

Status: Inactive

End Date: 1/1/2014

Description: The subsite was evaluated and determined to require No Action. It consists of two sections of pipeline that transferred nonradiological and nonhazardous water. The first section is a 10-inch high-density polyethylene pipe that runs between the 342 Lift Station (LS) and the 310 Treated Effluent Disposal Facility (TEDF). The second section is a 3-inch polyvinyl chloride pipe that runs from the 310 TEDF to 3906D, LS-10. Collectively they were part of the 310 Retention Transfer System (RTS).

Location: The pipeline is located in the northern half of the 300 Area. It runs parallel to Route 4 between 3906S Lift Station (LS-10) and 310 TEDF. A section along runs between 342 LS and 310 TEDF.

Release

Description:

Related Sites/ Structures: The subsite is associated with the consolidated 600-352-PL site.

Process

Description:

The 310 TEDF was constructed in 1994 and was designed to treat industrial wastewaters. Most of this wastewater originated from the 300 Area process sewers, although some industrial wastewater from other Hanford Site operations was also treated. The primary wastewater constituents requiring removal were low levels of heavy metals, mercury, organics, and cyanide. After receipt from the 342 Waste Collection Sump/Lift Station, the wastewater was processed at a nominal 300 GPM sequentially through an iron co-precipitation system to remove heavy metals, an ion-exchange system to remove mercury, and a hydrogen-peroxide/ultraviolet radiation system to destroy organics and cyanide. The primary process chemicals, stored in tanks just outside the east wall, included ferric chloride (6,000 gal tank), sodium hydroxide (6,000 gal tank), sulfuric acid (4,000 gal tank), and hydrogen peroxide (1,000 gal tank).

Two clarifiers were part of the iron co-precipitation process. Following addition of chemicals and a flocculant, the wastewater was gravity-fed to the clarifiers where solids precipitated. Clarified wastewater overflowed the tanks for further processing, and the solids were pumped to a filter press for dewatering and eventual disposal.

The purpose of the 300-15:5 piping segment was to convey non-radiological and non-

hazardous process wastewater from the 342 Lift Station to the 310 Treated Effluent Disposal Facility (TEDF). 310 TEDF was constructed in 1994 as a non-hazardous, non-radiological, Clean Water Act facility that treated 300 Area process wastewater that was subsequently discharged to the Columbia River in accordance with a National Pollutant Discharge Elimination System (NPDES) permit. In 2009, 310 TEDF was deactivated and reconfigured into the 310 Retention Transfer System (RTS). In this latter configuration, RTS served to accumulate process sewer effluent from the 325 Building, screen the effluent for radiological contamination and pH, then batch discharge the effluent into the combined 300 Area process/sanitary sewer, which was in turn discharged to the City of Richland Publically Owned Treatment Works (POTW). Discharge to the POTW was performed in accordance with an Industrial Waste Water Discharge Permit issued by the City of Richland. During RTS operation, the return leg of sanitary sewer piping became a process sewer and is thus included this waste site. This return length of piping runs from 310 RTS to 3906S Lift Station (LS-10) in the southern 300 Area. The original segment from 342 to 310 TEDF/RTS consists of 4,300 ft of 10-in. high-density polyethylene pipe. The return segment from 310 TEDF/RTS consists of 5,900 ft of 3-in. polyvinyl chloride pipe.

Closure Info: Final (5/13/2015): The known operational history of the 310 TEDF/310 RTD and associated process sewer piping; quantitative characterization of the 310 TEDF influent contaminants; qualitative data from smear samples at piping segments left in place; and quantitative data from pipe coupons and soils are supportive of reclassification of the 300-15:5 subsite to Final No Action. Results from the 300-15:5 subsite indicate that the site supports future and uses that can be represented (or bounded) by the residential land-use scenario and poses no threat to groundwater or the Columbia River.

The SubSite is Part Of:

Code: 300-15

Names: 300-15; 300 Area Process Sewer System

Code: 300-15:6

Classification: Accepted

Names: 300-15:6; 305A Sewer Process and 24 Inch Process Sewer Main North of Apple Street

Reclassification: Final Closed Out (9/9/2015)

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and reclassified to Final Closed Out. It consisted of three sections of pipeline. The first was a section of 6 inch, vitrified clay pipe that conveyed waste from the 305A building. The second section was a 300 meter (990 ft) length of the 24 inch, vitrified clay pipe that ran northeast from Apple Street near California Avenue and discharged to the 316-1 South Process Pond. The third section was a 5 meter (16.5 ft) length of 6 inch diameter vitrified clay pipe, located east of the 351 substation. It also included portions of the lines that branched off from the main line and were removed in 2015.

Location: The subsite is three distinct sections of pipe located in the 300 Area north of Apple Street. One section exited the 305-A building and extended under the 351 Electrical Substation. The second section ran northeast from Apple Street near California Avenue and discharged to the 316-1 South Process Pond. The third section was east of the 351 substation.

Process Description: There are three primary contributors to the 300 Area process sewer wastewater: purified potable water, equipment cooling water, and contributors with some chemical contamination. Effluent from buildings was combined into one or two main waste pipes before exiting the building. Steam production activities accounted for a significant part of the waste water produced. These activities produced large quantities of waste cooling water and significant amounts of waste brine solution. A smaller portion of the effluent was from laboratory sinks and drains that

connected to the sewer.

Closure Info: Final (9/9/2015): Remediation of the 300-15:6 subsite was performed from December 1, 2014, to March 19, 2015. The remediation also included removing a small segment of the 300-15:2 pipeline subsite, approximately 3 meters (9.8 ft) long, near the 351 Substation. This segment of pipeline had been assigned to other 300-15 subsites, but due to remedial action activities near the 351 Substation, the pipeline segment was administratively moved to 300-15:6. A portion of the south end of the eastern pipe segment was left in place, due to the proximity to a river warning siren and a groundwater monitoring well.

The remediation extended to an approximate maximum depth of 5.5 meters (18 ft) below ground surface, resulting in approximately 15,125 bank cubic meters (19,783 bank cubic yards) of excavated waste materials being removed and direct loaded for disposal at ERDF. Waste materials consisted of soils, clay tile piping, and concrete. No overburden soil was salvaged from the 300-15:6 subsite excavation. No staging pile areas were utilized.

No elevated radiological activity was detected in the post remediation survey.

The SubSite is Part Of:

Code: 300-15

Names: 300-15; 300 Area Process Sewer System

Code: 300-16

Classification: Accepted

Names: 300-16; Contamination Found During Utility Pole Replacements; Solid Waste Near 314 Building

Reclassification: Final Closed Out (5/12/2014)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The site consisted of three utility poles that surrounded the 314 Building. The poles were cutoff at ground level in 2005 and were no longer visible from the surface (per Excavation Permit DAN-2743). Three utilities poles were assigned to three separate subsites - 300-16:1, Utility Pole Northwest of 314 Building, 300-16:2, Utility Pole East of 314 Building and 300-16:3, Utility Pole Southeast of 314 Building. The subsites have been Interim Closed out, so the parent site is also considered Interim Closed Out. In 2014, the site and subsites were reclassified to Final Closed Out.

Location: The utility poles were located around the 314 Building.

Release Description: In May 1994, subsurface contamination was discovered at the site when a damaged power pole was being replaced. A truck driver had backed into a utility pole located southeast of the 314 Building. The incident caused enough damage to require the pole to be replaced. Underground radiological contamination was discovered during the replacement of the damaged utility pole. When the pole was pulled from the ground, "yellow cake" (a combination of uranium and sulfuric acid) was found to be attached to the subsurface portion of the pole, indicating subsurface contamination at this location.

Related Sites/ Structures: These incidents are associated with the contamination found along Ginko Street, recorded in 300-28 and also 300-24.

Process Description: The site was identified in 1994 during the development of the 300-FF-2 Operable Unit Technical Baseline Report (BHI-00012). The information was obtained from interviews was documented in an email (Email dated 5/5/1994). The interviewees reported that a driver backed into a steam utility pole and caused enough damage that the pole required replacement. When the old pole was pulled out of the ground it was discovered that "yellow cake"

(uranium/sulfuric acid combination) was adhering to the subsurface portion of the pole. The exact location of the incident was unknown but was reported to be near the 314 Building. The technical baseline report identified the pole in Figure 3-65. This pole corresponds with the location of 300-16:3.

Waste Type: Soil

Waste Description: On March 6, 1992, May 4, 1994, September 22, 1995 radioactive contamination (yellow-cake uranium) was discovered on the bottom ends of several utility poles that had been removed.

Closure Info: Final (5/12/2014): 300-16:1 is the Utility Pole Northwest of the 314 Building waste site. The 300-16:1 waste site was remediated and has been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). Verification sampling results show that the site meets the CULs for direct exposure and groundwater protection and river protection and support an industrial land use scenario. Because the sample results do not meet the CULs for residential land use, the waste site requires institutional controls to maintain industrial land use. In accordance with this evaluation, the verification sampling results support a reclassification of the 300-16:1 waste site to Final Closed Out

300-16:2 was addressed with 300-24, 300-80 and 300-218. Remediation occurred in 2009 and 2010 to a depth of 9.8 feet.

300-16:3, Utility Pole Southeast of 314 Building waste site was remediated with 300-28, 300-43 and 300-249.

This Site has the Following SubSites:

Code: 300-16:1

Names: 300-16:1; Utility Pole Northwest of 314 Building

Code: 300-16:2

Names: 300-16:2; Utility Pole East of 314 Building

Code: 300-16:3

Names: 300-16:3; Utility Pole Southeast of 314 Building

Code: 300-16:1

Classification: Accepted

Names: 300-16:1; Utility Pole Northwest of 314 Building

Reclassification: Final Closed Out (5/12/2014)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. In 2014, the site was reclassified to Final Closed Out. It consisted of the buried remains of a telephone pole located northwest of the 314 Building. A routine radiation survey for electrical upgrades in the 300 Area revealed contamination on a telephone pole on May 17, 1994 (Radiological Survey Report 165951). The radiation survey report indicated that the contamination level was 7,000 counts per minute on the top of the pole. The contamination at the bottom of the pole was measured at 3,500 counts per minute.

Location: The site was located 12 meters (39 feet) north of the 314 Building just south of 305-B Storage Facility at Washington State Plane (WSP) coordinates N116143.95 E593708.5.

Related Sites/ Structures: 314 Building

Closure Info: Interim (1/18/2012): Remediation in the vicinity of the 300-16:1 utility pole was conducted in

the first quarter of calendar year 2011. The excavation extended approximately 1.5 meters (5 ft) below grade at the 300-16:1 utility pole. There was no waste staging pile area footprint or overburden soil stockpile associated with this waste site. All removed materials were disposed via direct loadout to the Environmental Restoration Disposal Facility.

Final (5/12/2014): 300-16:1 is the Utility Pole Northwest of the 314 Building waste site. The 300-16:1 waste site was remediated and has been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). Verification sampling results show that the site meets the CULs for direct exposure and groundwater protection and river protection and support an industrial land use scenario. Because the sample results do not meet the CULs for residential land use, the waste site requires institutional controls to maintain industrial land use. In accordance with this evaluation, the verification sampling results support a reclassification of the 300-16:1 waste site to Final Closed Out

300-16:2 was addressed with 300-24, 300-80 and 300-218. Remediation occurred in 2009 and 2010 to a depth of 9.8 feet.

300-16:3, Utility Pole Southeast of 314 Building waste site was remediated with 300-28, 300-43 and 300-249.

The SubSite is Part Of:

Code: 300-16

Names: 300-16; Contamination Found During Utility Pole Replacements; Solid Waste Near 314 Building

Code: 300-16:2

Classification: Accepted

Names: 300-16:2; Utility Pole East of 314 Building

Reclassification: Final Closed Out (5/12/2014)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: This subsite has been remediated and Interim Closed Out. In 2014, the site was reclassified to Final Closed Out. The site consisted of the buried remains of a utility pole, located east of the 314 Building. One of three utility poles in the 300-16 waste site was located within the footprint of the current excavation for the 314 Buildings waste sites.

Location: The site was located east of the 314 Building.

Related Sites/ Structures: These incidents are associated with the contamination found along Ginko Street, recorded in waste sites 300-28 and 300-24 and the 314 building demolition.

Process Description: On September 22, 1995 a telephone pole located on the east side of the 314 Building was removed. The lower four feet was found to be contaminated (Radiological Survey Report 194873). The radiation survey report indicated that the contamination level was 8,000 counts per minute on the base of the pole.

Closure Info: Interim (9/29/2011): Remedial action activities at the 300-16:2, 300-24, 300-80, and 300-218 waste sites were carried out from December 21, 2009 to May 20, 2010. The excavation reached a maximum depth of 3.0 meters (9.8 ft) near the center and southwest corner of the collective waste sites. Approximately 6,275 cubic meters or 14,995 tons of materials were removed from the waste site excavation and direct loaded for disposal at the ERDF. There was no waste staging pile area footprint or overburden soil stockpile associated with these waste sites. The utility pole that was associated with the 300-16:2 subsite was removed. The autoclave pit underlying the former 314A Building was removed. The structures associated with the 300-80 drain were removed. The concrete slabs associated with the 314, 314A, and 314B Buildings have been removed.

During remediation, a suspected french drain was found at the base of the exterior stairwell on the southwest edge of the 314 Building slab. Discussions with the EPA concluded that this drain could be remediated concurrently with the 314 Building waste sites. This suspected french drain was removed. Two pits within the main 314 Building extended below the level of the current excavation. Discussions with EPA concluded that the remaining portions of these pits could remain in place. The 300-285 (300FF2-018; FD 32), 300FF2-270 and 300-240 underground injection control (UIC), wells, were within the footprint of the 314 excavation layback. The listed UIC wells are not part of the waste site. They are listed for tracking purposes. The UIC wells have a "Not Accepted" classification status and are still present at the site.

All the foundation debris such as concrete, metal rebar, miscellaneous piping (e.g., steam, water, etc.), and electrical conduit was excavated and removed from the waste sites. No anomalous materials were observed during remedial activities.

Post-excavation radiological survey of the 314 Building slab was performed in June 2010. Additional radiological surveys of the 300-16:2 utility pole were performed in March 2011. The field radiological measurements survey results did not identify any residual radiological contamination above background levels.

Final: The 300-24, 300-80, 300-218, and 300-16:2 waste sites were remediated and have been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). Verification sampling results show that the site meets the CUL's for direct exposure and groundwater protection and river protection and support an industrial land use scenario. Contamination at these waste sites did not extend into the deep zone soils. Because the remediation of the waste sites did not meet residential land use cleanup levels, the waste sites require institutional controls to maintain industrial land use. In accordance with this evaluation, the verification sampling results support a reclassification of the 300-24, 300-80, 300-218, and 300-16:2 waste sites to Final Closed Out.

The SubSite is Part Of:

Code: 300-16

Names: 300-16; Contamination Found During Utility Pole Replacements; Solid Waste Near 314 Building

Code: 300-16:3

Classification: Accepted

Names: 300-16:3; Utility Pole Southeast of 314 Building

Reclassification: Final Closed Out (5/12/2014)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The site has been remediated and Interim Closed Out. It consisted of the buried remains a telephone poles located south of the 314 Building.

Location: The site is located within the 300-28 waste sites. The site was located south of the 314 Building between the 303-A and 3722 buildings.

Related Sites/ Structures: These incidents are associated with the contamination found along Ginko Street, recorded in waste sites 300-28 and 300-24.

Process Description: On March 6, 1992 a telephone pole, located south of the 314 Building was removed. The pole was found to be contaminated (survey RSR-37049). The radiation survey report indicated that the contamination level was 3,000 counts per minute.

Closure Info: Interim (11/28/2011): The 300-28, 300-43, 300-48, 300-249, and 300-16:3 excavation of

building foundations, associated pipelines, and soils began on June 28 and was completed by July 29, 2010. Due to elevated radiologically contaminated soil found north of 303E Building, additional remediation was performed September 30, 2010, targeting specific locations with elevated readings. The excavation of the 300-28, 300-43, 300-48, 300-249, and 300-16:3 waste sites resulted in a total of approximately 2,914 bank cubic meters (BCM) (3,811 bank cubic yards [BCY]) of contaminated soil and debris. All material was direct loaded for disposal at the Environmental Restoration Disposal Facility (ERDF).

Remediation of the 300-28, 300-43, 300-48, 300-249, and 300-16:3 waste site excavations included removal of the 303A, 304, 304A, 303B, 3732, 303C, 3707D, and 303E Buildings concrete slabs. The manholes and intersections of the 300-15 process sewer were excavated and removed from within the excavation boundaries. All the foundation debris such as concrete, metal rebar, miscellaneous piping (steam, water, etc.), and electrical conduit was excavated and removed from the waste sites. No anomalous materials were observed during remedial activities.

Although remediation and verification sampling was performed for the 300-161 waste site, it was then noted that 300-161 waste site was reclassified as a Rejected site and therefore did not require remediation or site closure process. The 300-161 waste site was removed from the RSVP. The 300-60, 300-61, 300-62, 300-161, 300-162, 300-176, 300-193 and 300-237 Rejected waste sites were located within the 300-28, 300-43, 300-48, 300-249, and 300-16:3 excavation layback.

Final: (Final) No additional remediation was performed at the site.

The SubSite is Part Of:

Code: 300-16

Names: 300-16; Contamination Found During Utility Pole Replacements; Solid Waste Near 314 Building

Code: 300-18

Classification: Accepted

Names: 300-18; SCA #4; Surface Contaminated Area #4

Reclassification Final Closed Out (2/18/2014)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site has been remediated and Interim Closed Out. It was considered Final Closed Out in 2014. The site was identified during routine surveillance activities on April 23, 1993. Soil and metal shavings were identified with contamination levels of 3000 to 4000 disintegrations per minute. On April 26, 1993 six pieces of contaminated concrete reading 2000 to 4000 disintegrations per minute were found. An area approximately 4.5 meters (15 feet) by 6.1 meters (20 feet) was posted as a Soil Contamination Area. Approximately 0.46 meters (18 inches) to 0.61 meters (2 feet) of dirt was placed on the site. It was reposted as an Underground Radioactive Material Area.

Location: The site was located south of 600-117, the 300 Area Treated Effluent Disposal Facility.

Waste Type: Misc. Trash and Debris

Waste Description: The site contained contaminated soil, metal shavings, nuts and bolts and concrete reading 3,000 to 4,000 disintegrations/minute beta-gamma.

Closure Info: Interim: Remedial action at the 300-18 site began in December 2004. Excavation of the site included the removal of small quantities of metal shavings, miscellaneous construction type debris, and soil. No indications of liquid waste disposal or land disposal restricted materials were observed during excavation. Remedial action excavation was completed in February 2005, with approximately 392 metric tons (432 U.S. tons) removed for transport to ERDF. The

excavation covered an area of approximately 220 square meters (2,370 sq ft) with an average depth of approximately 1 meter (3 ft). Cleanup Verification Package CVP-2005-00004 documents that the waste site was remediated in accordance with the Record of Decision for the 300-FF-2 Operable Unit, (ROD). Remedial action objectives (RAOs) and remedial action goals (RAGs) for the site were documented in the ROD and the Remedial Design Report/Remedial Action Work Plan for the 300 Area (RDR/RAWP).

Because residual soil concentrations indicated that cleanup levels for more stringent land uses may have been achieved for the site, a supplemental evaluation was performed against unrestricted land-use cleanup objectives established in the Explanation of Significant Differences for the 300-FF-2 Operable Unit Record of Decision.

Excavation was driven by RAOs for direct exposure, protection of groundwater, and protection of the Columbia River. Preliminary waste site COCs were identified in the 300 Area Remedial Action (SAP). The site may be backfilled with clean soil to match surrounding grade elevation.

Final (2/18/2014): This group of sites are considered Final Closed Out in the 300-FF-2 Record of Decision and meet the criteria for Unrestricted Landuse.

Code:	300-22	Classification:	Accepted
Names:	300-22; 309 Building B-Cell Cleanout Leak	Reclassification	Final Closed Out (8/7/2015)
Type:	Unplanned Release	Start Date:	9/20/1962
Status:	Inactive	End Date:	9/20/1962
Description:	The site has been remediated and reclassified to Final Closed Out. It was an unplanned release from a separated hose coupling that contaminated the ground outside the emergency airlock of the 309 Building on September 20, 1962. The site is covered with new asphalt. The asphalt area is roped off and trucks are not allowed on the asphalt. The rupture loop annex is present below ground at the site.		
Location:	In 1962, the spill occurred outside the emergency airlock to the 309 Plutonium Recycle Test Reactor. The emergency airlock was located on the northwest side of the reactor dome. The spill area was within the 309 building demolition footprint.		
Release Description:	During decontamination procedures at the 309 Building on September 20, 1962, a hose that was backflushing waste from the B-Cell to a waste trailer uncoupled at a joint near the emergency airlock. At the time of the incident, an area of ground 6.1 meters (20 feet) by 2.4 meters (8 feet) was roped off and tagged. The maximum radiological readings were 80,000 counts per minute on the ground near the spill.		
Related Sites/ Structures:	The release is associated with the B-Cell of the 309 Building.		
Process Description:	The Plutonium Recycle Test Reactor (PRTR) was a heavy water moderated, light water cooled, nuclear reactor. The PRTR was operated in support of the Plutonium Utilization Program to develop an optimum reactor fuel design for recycling plutonium to stretch the uranium fuel supply for commercial nuclear reactors. The B-Cell was the 7.5 m (24.5 ft) wide area between the outer containment wall and the outer reactor shield wall on the northwest quadrant of the PRTR below the main floor (5 ft to 32 ft.) It contained the in-vessel rupture loop equipment, the gas loop equipment, and the cooling blowers for the Hot Fuel Exam Facility. The release occurred during a decontamination of the B-Cell.		
Waste Type:	Process Effluent		

Waste Description: The waste is soil that was contaminated from decontamination efforts intended to reduce the overall levels of radioactivity within the reactor following the unplanned release that occurred on October 19, 1962.

Closure Info: Final (8/7/2015): Remedial actions for waste sites 300-22, 300-255 and UPR-300-5 were combined and addressed in CVP-2015-00013.

In January 2014, the 1,082-ton 309 PRTR was removed and transported to ERDF for disposal. The remaining containment structure consisted of 0.3 meters (1 ft) thick concrete surrounded by metal sheeting. It was demolished to 9.8 meters (32 ft) below ground surface (bgs) and disposed at ERDF. The remaining 3.4 meters (11 ft) of the containment structure, from 9.8 to 13 meters (32 to 43 ft) below ground surface, was sampled and left in place.

The 300-22, 300-255, and UPR-300-5 waste sites excavation along with the demolition of the 309 containment structure was performed from March 12, 2014, to February 12, 2015. The excavation resulted in removal of approximately 78,120 bank cubic meters (BCM) (102,177 bank cubic yards [BCY]) of contaminated materials. All material was direct loaded for disposal at ERDF. The 300-22, 300-255, and UPR-300-5 waste sites were excavated to a depth of 11 meters (36 ft) bgs. Excavated materials consisted of concrete, metal tanks, building debris, asphalt, and various types of piping, including carbon steel, stainless steel, clay tile, and concrete tile. No anomalous materials or stained soils were observed during remedial activities. No radiological contamination above background was detected in the shallow zone of the 309 Building excavation. An additional weak-gamma survey was performed to target americium-241 and the associated plutonium. This survey detected radiological contamination above background within the north side of the excavation and 309 PRTR remaining containment structure. Verification samples were collected in the vicinity of the radiological detects above background locations. Sampling results indicated that all cleanup levels were met for the samples in these areas.

Code: 300-24	Classification: Accepted
Names: 300-24; Soil Contamination at the 314 Metal Extrusion Building	Reclassification: Final Closed Out (5/12/2014)
Type: Unplanned Release	Start Date: 1/1/1994
Status: Inactive	End Date:

Description: The waste site has been remediated and Interim Closed Out. In 2014, the site was reclassified to Final Closed Out. The area around the 314 building was mostly paved with a few areas of exposed soil. A site visit in June 1995 found the area posted with Underground Radioactive Material signs and "Contact Radiological Control Group prior to excavating". Later, the Underground Radioactive Material signs were moved to the 300 Area fence to eliminate the need for smaller individually posted areas inside 300 Area.

Location: The 314 building is located on the northeast corner of Alaska and Ginko Streets, inside 300 Area.

Release Description: Utility upgrades, being done by Power City Electric, required trenches to be excavated through the asphalt in the 300 Area. In June 1994, 600,000 disintegrations per minute beta/gamma and 350 disintegrations per minute alpha was found in the trench soil near the southwest corner of the 314 building. In June 2001, during an excavation on the south side of the building, radioactively contaminated soils containing approximately 557 picoCuries per gram of uranium were uncovered. Because of this, the size of this site was extended to the south.

Related Sites/Structures: The 314 Building is a separate WIDS site (sitecode: 300-218). Miscellaneous stream #268 (sitecode: 300-80) is located adjacent to the west wall of the 314 Building. Soil contamination in this area is documented in 300-16 and 300-28.

Process Description:	The 314 building (and the 314B extension) served as a facility for several fuel fabrication processes. The processes included the metal extrusion process, uranium scrap recovery process, oxide burner operation, melt plant operations, research and craft services. The oxide burner operations caused contamination to spread and be deposited around the 314 Building area. Uranium metal dust from the fuel fabrication activities provided a pathway for heavy metal dust to become airborne and accumulated in the soils throughout the northern portion of the 300 Area.
Waste Type:	Soil
Waste Description:	Soil samples of the dirt in the trench near the 314 Building found mostly uranium and a trace of cesium-137. The gross alpha count was 896 picocuries per gram.
Closure Info:	Interim (9/29/2011): Remedial action activities at the 300-16:2, 300-24, 300-80, and 300-218 waste sites were carried out from December 21, 2009 to May 20, 2010. The excavation reached a maximum depth of 3.0 meters (9.8 ft) near the center and southwest corner of the collective waste sites. Approximately 6,275 cubic meters or 14,995 tons of materials were removed from the waste site excavation and direct loaded for disposal at the ERDF. There was no waste staging pile area footprint or overburden soil stockpile associated with these waste sites. The utility pole that was associated with the 300-16:2 subsite was removed. The autoclave pit underlying the former 314A Building was removed. The structures associated with the 300-80 drain were removed. The concrete slabs associated with the 314, 314A, and 314B Buildings have been removed.

During remediation, a suspected french drain was found at the base of the exterior stairwell on the southwest edge of the 314 Building slab. Discussions with the EPA concluded that this drain could be remediated concurrently with the 314 Building waste sites. This suspected french drain was removed. Two pits within the main 314 Building extended below the level of the current excavation. Discussions with EPA concluded that the remaining portions of these pits could remain in place. The 300-285 (300FF2-018; FD 32), 300FF2-270 and 300-240 underground injection control (UIC), wells, were within the footprint of the 314 excavation layback. The listed UIC wells are not part of the waste site. They are listed for tracking purposes. The UIC wells have a "Not Accepted" classification status and are still present at the site.

All the foundation debris such as concrete, metal rebar, miscellaneous piping (e.g., steam, water, etc.), and electrical conduit was excavated and removed from the waste sites. No anomalous materials were observed during remedial activities.

Post-excavation radiological survey of the 314 Building slab was performed in June 2010. Additional radiological surveys of the 300-16:2 utility pole were performed in March 2011. The field radiological measurements survey results did not identify any residual radiological contamination above background levels.

Final: The 300-24, 300-80, 300-218, and 300-16:2 waste sites were remediated and have been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). Verification sampling results show that the site meets the CUL's for direct exposure and groundwater protection and river protection and support an industrial land use scenario. Contamination at these waste sites did not extend into the deep zone soils. Because the remediation of the waste sites did not meet residential land use cleanup levels, the waste sites require institutional controls to maintain industrial land use. In accordance with this evaluation, the verification sampling results support a reclassification of the 300-24, 300-80, 300-218, and 300-16:2 waste sites to Final Closed Out.

Code: 300-28

Classification: Accepted

Names: 300-28; Contamination Found Along Ginko Street; Solid Waste Site Near 303-G Building **Reclassification** Final Closed Out (5/12/2014)

Type: Unplanned Release **Start Date:** 1/1/1994

Status: Inactive **End Date:**

Description: The site has been remediated and Interim Closed Out. In 2014, the site was reclassified to Final Closed Out. It was contaminated asphalt and soil beneath Ginko Street. Patches of new asphalt were visible where utility trenches were excavated. The dimensions of this waste site were estimated to be approximately 168 meters (551 ft) long and 6.5 meters (21.3 ft) wide.

Location: The site was located inside the 300 Area, along Ginko Street.

Release Description: During October 1994, radiological surveys documented the daily activities of the utility installations. The contamination along Ginko Street began southeast of the 314 Building and continued to the southwest corner of the 306-W Building. Contamination levels recorded ranged from 10,000 disintegration per minute to 200,000 disintegrations per minute (beta/gamma).

Related Sites/ Structures: The contamination is associated with activities in the 314, 333, 3715, 304 and the 303 (A, B, C, G and K) Buildings.

Process Description: The oxide burner operations caused contamination to spread and be deposited around the 314 Building area. Uranium metal dust from the fuel fabrication activities provided a pathway for heavy metal dust to become airborne and accumulated in the soils throughout the northern portion of the 300 Area.

Waste Type: Soil

Waste Description: The waste is radioactively contaminated soil found just beneath the asphalt paving.

Closure Info: Interim (11/28/2011): The 300-28, 300-43, 300-48, 300-249, and 300-16:3 excavation of building foundations, associated pipelines, and soils began on June 28 and was completed by July 29, 2010. Due to elevated radiologically contaminated soil found north of 303E Building, additional remediation was performed September 30, 2010, targeting specific locations with elevated readings. The excavation of the 300-28, 300-43, 300-48, 300-249, and 300-16:3 waste sites resulted in a total of approximately 2,914 bank cubic meters (BCM) (3,811 bank cubic yards [BCY]) of contaminated soil and debris. All material was direct loaded for disposal at the Environmental Restoration Disposal Facility (ERDF).

Remediation of the 300-28, 300-43, 300-48, 300-249, and 300-16:3 waste site excavations included removal of the 303A, 304, 304A, 303B, 3732, 303C, 3707D, and 303E Buildings concrete slabs. The manholes and intersections of the 300-15 process sewer were excavated and removed from within the excavation boundaries. All the foundation debris such as concrete, metal rebar, miscellaneous piping (steam, water, etc.), and electrical conduit was excavated and removed from the waste sites. No anomalous materials were observed during remedial activities.

Although remediation and verification sampling was performed for the 300-161 waste site, it was then noted that 300-161 waste site was reclassified as a Rejected site and therefore did not require remediation or site closure process. The 300-161 waste site was removed from the RSVP. The 300-60, 300-61, 300-62, 300-161, 300-162, 300-176, 300-193 and 300-237 Rejected waste sites were located within the 300-28, 300-43, 300-48, 300-249, and 300-16:3 excavation layback.

Final: (Final) No additional remediation was performed at the site.

Code: 300-29	Classification: Accepted
Names: 300-29; 305-B Berm; Source Location of UPR-600-11 Contaminated Soil	Reclassification: Final No Action (2/18/2014)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:
Description: The site had been reclassified to No Action. In 2014, it was reclassified to Final No Action. It is a U shaped soil berm that surrounds the east wing of the 305-B Chemical Waste Storage Building. No radiological postings are currently present.	
Location: The 305 building is on the east side of the Alaska Street inside the 300 Area. The berm was around the 305-B Chemical Waste Storage Building, east of the 305-B main building. The berm that surrounded the building covered a surface area of 184 square meters.	
Release Description: On May 29, 1980, the JA Jones subcontractor workers had excavated 76.5 cubic meters (100 cubic yards) of soil from the 305-B berm before the contaminated rubble was detected and work was stopped. The contaminated material had been taken to the JA Jones Pit #1, which was designated as a non-radioactive landfill. Work was stopped immediately after the contamination was identified and the appropriate personnel were notified. Low-level beta-gamma contamination (600 - 4000 counts per minute) was discovered in a small amount of blacktop rubble on the south side of the berm.	
Related Sites/ Structures: The associated structure was the 305-B Chemical Waste Storage Building, UPR-600-11 and JA Jones Pit #1 (600-1).	
Waste Type: Soil	
Waste Description: The waste is radioactively contaminated soil (reported 5/29/80).	
Closure Info: Interim: Following the identification of contaminated material in 1980, work was stopped and the area carefully surveyed. All of the remaining contaminated blacktop was removed from the berm and the area was released from radiation zone status. Additional excavated material was surveyed by a Radiation Monitor. A radiological survey done in August 1998 did not find any detectable contamination on the berm surface.	
The reclassification to No Action is documented on form 2004-100.	
Final (2/18/2014): The group of sites is listed in the 300-FF-2 Record of Decision and meet the criteria for unrestricted landuse.	

Code: 300-32	Classification: Accepted
Names: 300-32; 333 Building; 333 Building Remaining Soils; 333 N Fuels Manufacturing Building; New Fuel Cladding Facility	Reclassification: Final Closed Out (5/12/2014)
Type: Foundation	Start Date: 1/1/1961
Status: Inactive	End Date:
Description: The waste site has been remediated and Interim Closed Out. In 2014, the site was reclassified to Final Closed Out. It was the soil remaining after the demolition of the 333 building. The 333 building above grade structure was demolished in 2006. After demolition, the foundation slab remained and was posted as a Radiologically Controlled Area (RCA). The contaminated soil was beneath the building footprint. It included the concrete pad, the subgrade soil and piping. The Lowery Press Pit was in the center of the 333 building footprint.	

Location:	The 333 building had been located in the northeast corner of the 300 Area, north of Ginko St. The 300-32 contaminated soil was beneath the building footprint.
Related Sites/ Structures:	The 333 Building is related to the 334-A Chemical Waste Receiving Station, the 334 Chemical Handling Building, 313 Sludge Recovery, and the Waste Acid Treatment System.
Process Description:	<p>The contamination in the 333 building includes all of the fuel components and chemicals used in the fuel rod fabrication process. Uranium Fuel for N Reactor was enriched to 95% uranium-235, and with 13% enriched to 1.25 uranium-235. A small amount of natural uranium was used. As well as beryllium, copper, zirconium, tin, iron, chromium and silicon. Nitric, sulfuric, hydrofluoric and other acids were used. TCE and other degreasers were used.</p> <p>The co-extrusion process steps included the following steps. The components were inspected and cleaned with nitric, nitric-hydrofluoric, and Chromic-nitric-sulfuric acid (combined in a commercial product called Zinctone). The components were extruded in an extrusion press. The components were machined to create fuel sections. Nitric acid was used to remove copper-silicon residues. Nitric-sulfuric acid was used to chemically mill excess uranium on fuel element ends. The element was etched with nitric-hydrofluoric acids and brazed with a specific beryllium-Zircaloy-2 alloy. The fuel supports or projections were welded on and the element underwent audioradiography. The element received a final etch with nitric-hydrofluoric acid. The element then underwent autoclave testing and inspection and was stored as finished fuel.</p>
Waste Type:	Chemicals
Waste Description:	Chemical wastes included nitric, sulfuric, hydrofluoric, chromic-nitric-sulfuric and other acids, along with degreasers trichloroethylene in the 1960's and early 1970's and perchloroethylene and 111-trichloroethane in the 1970's and 1980's. Heat treatment salts included sodium nitrate, sodium and potassium nitrite, and sodium and potassium chloride. Additionally, many alcohol and acetone cleansers were used throughout the building's history.
Closure Info:	<p>Interim (3/21/2013): Demolition of the 333 Building above-grade structure was completed in September 2006. The 333 Building slab with press pit was removed to 1 meter (3.3 ft) below ground surface in July 2010. Confirmatory sampling at the 300-32 waste site was performed on January 9 and 10, 2012. Confirmatory sampling results indicated that additional remediation was required at sample location 15, due to total petroleum hydrocarbons (TPH) analyses exceeding the direct exposure clean up level. On January 2, 2013, remediation was performed at confirmatory focused sample location 15, with additional remediation surrounding the perimeter of the press pit concrete foundation. Verification sampling of the re-excavated area was performed on January 3, 2013.</p> <p>Remediation at the 300-32 waste site was performed on January 3, 2013, and included removal of 1 meter (3.3 ft) of soil surrounding the entire perimeter of the remaining press pit concrete foundation. The removal extended 1 meter (3.3 ft) from the perimeter of the Loewy press pit concrete foundation. The final depth of removal for soil surrounding the concrete foundation was 2 meters (6.6 ft). All soil was direct loaded for disposal at ERDF. No stained concrete or soil was observed during additional remediation.</p> <p>The excavation of the press pit area of the 300-32 waste site resulted in a total of approximately 398 bank cubic meters (521 bank cubic yards) of contaminated soil and debris being removed. All material was direct loaded for disposal at ERDF.</p> <p>Final (5/12/2014): The 300-32, 333 Building waste site is the footprint of the demolished 333 Building. On January 2, 2013, remediation was performed at this location, with additional remediation surrounding the perimeter of the press pit concrete foundation. Verification sampling of the re-excavated area was performed on January 3, 2013. The maximum remediation depth extended to 2 m (6.6 ft) below ground surface. The 300-32 waste site was</p>

remediated and has been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). Verification sampling results show that the site meets the CUL's for direct exposure and groundwater protection and river protection and support a residential land use scenario. Contamination at the waste site did not extend into the deep zone soils. Therefore, institutional controls to prevent uncontrolled drilling or excavation into the deep zone are not required. In accordance with this evaluation, the verification sampling results support a reclassification of the 300-32 waste site to Final Closed Out.

Code:	300-33	Classification:	Accepted
Names:	300-33; 306W Metal Fabrication Development Building Releases	Reclassification	Final Closed Out (2/18/2014)
Type:	Unplanned Release	Start Date:	
Status:	Inactive	End Date:	
Description:	<p>The site was the contaminated soil around and under the 306W Building. The area around the 306W building was paved and posted as having underground radioactive contamination.</p> <p>During remedial activities in 2009, the 300-33 and 300-256 combined waste sites were re-defined to include subsurface four pits ranging from 3 to 16 meters (12 to 45 ft) below the concrete slab surface of the 306 Building. The four pits included the tube pit located in Room 172 of the 306E Building, the assembly pit located in the western high bay of the 306E Building, the furnace pit located in the northwestern corner of the 306E Building, and the press pit located in the northeastern corner of the high bay. Because these are nonstandard structures, agreements were reached between the Department of Energy, Richland Operations Office, and the U.S. Environmental Protection Agency to document status and closure requirements for these pit structures in a separate closure report (Refer to 306E/W Below Grade Pits Closure Report, CCN 147876, Washington Closure Hanford, Richland, Washington).</p>		
Location:	The site is located in the main 300 Area on the north side of Ginkgo Street between Wisconsin and California Streets.		
Release Description:	Multiple leaks and fires occurred over the years in and around the 306 building, in barrels and waste "load luggers" containing uranium, thorium, heavy metals, and other fuel component scrap. These fires oxidized and volatilized uranium and other wastes: long-lived contamination, which can be recirculated today, settled in building sumps, crevices, and nearby soil.		
Related Sites/ Structures:	The site is related to the 306W Building, 333 building, 300 Area process sewer, and 300 area sanitary sewer.		
Process Description:	The 306W Building was completed in 1956 and named the Fuel Element Pilot Plant. The facility was constructed to support the 313 Building operations. It was expanded in 1960 to contain the co-extrusion fabrication processes for N Reactor fuels fabrication. In 1972, the east half, the new half, was designated as 306E and that portion of the building became the Hanford Engineering Development Laboratory (HEDL) operated by Westinghouse Electric Corporation. The west portion of the building, which is older, was named 306W and was allocated to Pacific Northwest Laboratories (PNL).		
Waste Type:	Soil		
Waste Description:	The waste is contaminated soil under the paved areas surrounding the 306W building.		
Closure Info:	Interim: Demolition of the 306E, 306W, and 306E-BA facilities, which were located on top of		

the soil waste sites, was completed between November 2006 and December 2007. Remediation of the combined 300-33, 300-256, and 300-41 waste sites occurred between July 10 and November 9, 2009. The remediation activities included the removal of the neutralization tank, valve pit, soil, and other debris within the footprint of the 306E/W Building including the partial removal and backfill of the 306E Building assembly pit. All debris and excavation materials have been removed to the Environmental Restoration Disposal Facility.

The 300-33 and 300-256 combined waste sites included four pits ranging from 3 to 16 meters (12 to 45 ft) below the concrete slab surface of the 306 Building. The four pits included the tube pit located in Room 172 of the 306E Building, the assembly pit located in the western high bay of the 306E Building, the furnace pit located in the northwestern corner of the 306E Building, and the press pit located in the northeastern corner of the high bay. Because these are nonstandard structures, agreements were reached between the Department of Energy, Richland Operations Office, and the U.S. Environmental Protection Agency to document status and closure requirements for these pit structures in a separate closure report (Refer to 306E/W Below Grade Pits Closure Report, CCN 147876, Washington Closure Hanford, Richland, Washington).

Final (2/18/2014): This group of sites is listed in the 300-FF-2 Record of Decision as Final Closed Out. Institutional Controls to maintain Industrial Landuse are required.

Code:	300-34	Classification:	Accepted
Names:	300-34; 300 Area Process Sewer Leak (Found During Project L-070 Excavation at Manhole PS-87)	Reclassification	Final Closed Out (9/9/2015)
Type:	Unplanned Release	Start Date:	1/1/1995
Status:	Inactive	End Date:	
Description:	The site has been remediated and Final Closed Out. It was a release to soil that was discovered in 1995, during an excavation to install a new manhole (PS-87). PS-87 is a 0.7 meter (2.3 feet) diameter sewer opening with a round metal cover at grade. In 1998, the cover was labeled "Confined Space" and "Radioactive Material Internally Contaminated."		
Location:	Manhole PS-87 is located on the south side of Apple Street, inside the 300 Area. It is directly north of main entrance to 3506-B. The manhole is in a parking area for buildings 3506-A and 3506-B. A recent view of the manhole cover was obscured by sand and gravel.		
Release Description:	On December 12, 1995, during an excavation for the 300 Area Process Sewer Upgrade (Project L-070), contaminated soil was found at a depth of 3.6 meters (12 feet) near manhole PS-87. The maximum contamination identified in the dirt was 10,000 disintegrations per minute. Contaminated soil was removed from the excavation and placed into drums. After excavation and repairs were completed, the soil was put back in place. A leak from a cracked portion of the Process Sewer is suspected to have resulted in the contaminated soil. The cracked portion had been patched with grout a long time ago, possibly when it was originally installed. The broken pipe was replaced with a section of polyvinyl chloride (PVC) piping.		
Related Sites/ Structures:	The site is associated with the 300 Area Process Sewer (300-15), and Manhole PS-87.		
Process Description:	The source of the contamination release is believed to be a crack in the 300-15 Process Sewer, a vitrified clay pipe that held radioactive liquid.		
Waste Type:	Soil		

Waste Description: Soil contaminated with radioactive material was found at about the 3.65 meter (12 foot) depth during excavation and installation of manhole PS-87, Project L-070 (300 Area Process Sewer Upgrade). Maximum soil contamination levels were beta-gamma 10,000 disintegrations per minute. Soil sample results reported 525 picocuries per gram Total Beta and 91 picocuries per gram Total Alpha.

Closure Info: Final (9/9/2015): Remediation of the 300-15:3 and 300-34 waste sites was performed from January 14, 2014, to March 26, 2015. Approximately 73,961 bank cubic meters (96,737 bank cubic yards) of excavated materials were removed and direct loaded for disposal at ERDF. The 300-34 (manhole leak) waste site was located within the 300-15:3 subsite excavation. Therefore, the 300-34 waste was included in the 300-15:3 waste site remediation volume. Waste materials consisted of contaminated soil, gravel, pipe, and concrete. No overburden soil was salvaged from the excavations and no staging pile areas were utilized.

During demolition and excavation of the 3709, 3745A, 3745B, 3746, 3746A, 3730, 3621B/C, 3621D, 331D, 331G, 331H, 3706, 308, 321, 323, 382 Complex, 327, 327BA, 326BA, 340 Complex, 338, 337, 337B, 337BA, 3718M, 335, and 336 Buildings, it was noted that portions of the 300-15:3 pipelines had been removed if within the footprint of the building excavation boundaries. One 300-15:3 pipeline segment, less than 10 meters long, remains in-place, south of the 338 Building, due to an interfering active underground electrical line. Sections of the 300-15:3 pipeline north of the 326 Building remain in-place. This pipe was found to be filled with grout and lined. Pipelines associated with the 382 Buildings are remain in-place and connect to the 326 Building. Two sections of 300-15:3 pipeline associated with the 329 Building, south of 3701D Building also remain in-place.

Code: 300-40	Classification: Accepted
Names: 300-40; Corrosion of Vitriified Clay Process Sewer Pipe	Reclassification: Final Closed Out (5/12/2014)
Type: Unplanned Release	Start Date: 1/1/1980
Status: Inactive	End Date:

Description: The waste site has been remediated and Interim Closed Out. In 2014, the site was reclassified to Final Closed Out. The waste site is potential soil contamination associated with the corroded process sewer piping near the demolished 303-F building and 311 tank farm. The site was an uneven gravel covered area. It was bounded by a concrete curb and concrete pad on the west and a rail spur on the east. The southern section of the site included the area around 303-F and the 311 Tank Farm. The northern end of the site had been covered by the demolished 3712 building.

Location: The site was located directly north of the 311 Tank Farm and south of the 3712 Building.

Release Description: During removal of the 311 Stillhouse in 1980, it was discovered that the vitriified clay process sewer line was severely corroded. The section between the neutralization pit and the 3712 manhole was corroded to a point where the entire lower half of the pipe was missing. It was estimated that at least 60 meters (200 feet) of the pipe is in similar condition.

Documentation suggested that wastes were released to the soil column from badly corroded sections of the process sewer piping between the 311 Tank Farm and 3712. The extent of soil contamination was unknown. No occurrence report has been located for this waste site.

Related Sites/Structures: The site is associated with the 311 Tank Farm drains and the 300 Area Process Sewer, UPR-300-39, UPR-300-40 and UPR-300-45.

Process Description: This section of pipe was part of the 300 Area process sewer until it was isolated. This leg of pipe collected rain water drainage from the 311 Tank Farm and the 303-F floor drains. The

piping also collected effluent from the 311 Stillhouse.

Waste Type: Process Effluent

Waste Description: Potential wastes received in this piping system would consist of chemicals used in the 313 Building fuels manufacturing process. These include nitric acid, sodium hydroxide, alcohol, trichloroethylene, phosphoric acid, Duponol-M-3, hydrofluorosilicic acid, thorium, uranium, cutting oils, etc.

Closure Info: Interim (4/13/2012): Remediation of the 300-40, UPR-300-40, UPR-300-39, and UPR-300-45 waste sites was performed from May 24, 2010, through July 20, 2010. The soil within the waste site footprints was excavated to a depth of 1 meter (3.3 ft) below ground surface, and the resulted in 911 bank cubic meters (1,192 bank cubic yards) of soil being disposed at the Environmental Restoration Disposal Facility. On March 8, 2011, radiological field screening for beta and gamma activity was conducted in the 300-40, UPR-300-40, UPR-300-39, and UPR-300-45 waste site areas. The radiological field screening surveys did not indicate any significant residual radiological activity.

Final: The 300-40, Corrosion of Vitrified Clay Process Sewer Pipe, UPR-300-40, Acid Release at the 303-F Pipe Trench, UPR-300-39, Sodium Hydroxide Leak at 311 Tank Farm, and UPR-300-45, 303-F Building Uranium-Bearing Acid Spill were located in close proximity. The southern section of the 300-40 waste site consists of the area around the footprint of the demolished 303-F Building and 311 Tank Farm. The northern section of the 300-40 waste site is within the footprint of the demolished 3712 Building. The UPR-300-40 waste site is associated with the drain pipe connections between the 303-F Building and the 300 Area process sewer. The waste consisted of uranium-bearing acid waste containing nitric and sulfuric acid with uranium in solution and chromic acids with copper and zinc in solution. The UPR-300-39 waste site is the soil adjacent to the caustic storage tanks in the 311 Tank Farm. The UPR-300-45 waste site is the soil beneath the former uranium-bearing acid transfer pipeline, adjacent to the 303-F Building. The uranium-bearing acid transfer pipeline ran through the pipe trench from the 333 Building to the valve box at the southeast corner of the 313 Building outside the Uranium Recovery Room. The leak contained uranium-bearing waste acids identified as nitric acid and sulfuric acid with uranium in solution. Remediation occurred in 2010 to a depth of 3 feet.

The 300-40, UPR-300-40, UPR-300-39, and UPR-300-45 waste sites were remediated and have been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). Verification sampling results show that concentrations of COCs meet the CULs for direct exposure and groundwater protection and river protection and support a residential land use scenario. Contamination at the 300-40, UPR-300-40, UPR-300-39, and UPR-300-45 waste sites did not extend into the deep zone (below 4.6 meters [15 ft]). Therefore, institutional controls to prevent uncontrolled drilling or excavation into the deep zone of the site are not required. In accordance with this evaluation, the verification sampling results support a reclassification of the 300-40, UPR-300-40, UPR-300-39, and UPR-300-45 waste sites to Final Closed Out.

Code: 300-41	Classification: Accepted
Names: 300-41; 306E Neutralization Tank; Underground Lime Tank and Valve Pit	Reclassification: Final Closed Out (2/18/2014)
Type: Neutralization Tank	Start Date:
Status: Inactive	End Date:
Description: The site included a neutralization tank and valve pit. The valve pit was constructed of concrete and is covered by a 2.18 meter (7.15 foot) diameter metal lid. The top of the pit was flush with	

the ground surface on its north side and approximately 5 centimeters (2 inches) above grade on its south side. A rectangular hatch in the lid allowed access to the pit. The hatch is labeled "Confined Space." It appeared as though there are three ports in the lid where pipes or hoses could enter the pit. These three ports were closed.

The pit was surrounded by sand and four metal safety posts. All that is visible of the neutralization tank is a riser that appears to be made of metal; the riser appears to be discolored by rust. The riser is covered by a 0.72 meter (2.36 foot) diameter metal lid, that is greater in diameter than the riser itself. The lid is labeled "Neutralization Tank" in fading black paint. The lid is held in place by a metal bar, bolts and wing nuts. The metal bar has discolored the lid with rust. The top of the lid is 0.42 meters (1.4 feet) above the ground surface, which is sand.

- Location:** The site was located west-northwest of the northeast corner of the 306E Building.
- Release Description:** From 1956 to 1967, and once after 1967, the neutralization tank and valve pit intercepted and neutralized nitric acid-bearing chemical wastes before discharge to the process sewer. In 1976, the pit was inspected, along with the process waste sump, sewer manholes, and the inlet box to the process sewer leaching trenches, after several hundred gallons of slightly enriched uranyl nitrate hexahydrate solution was spilled in the sump. The investigation found that much uranium and thorium contamination lies in and beneath the entire 306 Building floor, slab, pipe trenches, and sewer lines. No significant accumulation was found in the pit and sewer manholes. In 1979, a HEDL Radiological Engineering report stated, among other things, "The lime pit...contain[s] uranium and thorium sludge." The soil contamination is addressed by WIDS Site 300-42.
- Related Sites/Structures:** The site is associated with the 306E Fabrication and Testing Laboratory Releases (WIDS Site 300-42) and 306E Building - HVAC Condensate, Miscellaneous Stream #454 (WIDS Site 300-71), and the process sewer (WIDS Site 300-15).
- Waste Type:** Chemicals
- Waste Description:** The neutralization tank and valve pit intercepted and neutralized nitric acid-bearing chemical wastes before discharge to the process sewer. In 1979, a HEDL Radiological Engineering report stated, among other things, "The lime pit...contain[s] uranium and thorium sludge."
- Closure Info:** Interim: Demolition of the 306E, 306W, and 306E-BA facilities, which were located on top of the soil waste sites, was completed between November 2006 and December 2007. Remediation of the combined 300-33, 300-256, and 300-41 waste sites occurred between July 10 and November 9, 2009. The remediation activities included the removal of the neutralization tank, valve pit, soil, and other debris within the footprint of the 306E/W Building including the partial removal and backfill of the 306E Building assembly pit. All debris and excavation materials have been removed to the Environmental Restoration Disposal Facility.
- The 300-33 and 300-256 combined waste sites included four pits ranging from 3 to 16 meters (12 to 45 ft) below the concrete slab surface of the 306 Building. The four pits included the tube pit located in Room 172 of the 306E Building, the assembly pit located in the western high bay of the 306E Building, the furnace pit located in the northwestern corner of the 306E Building, and the press pit located in the northeastern corner of the high bay. Because these are nonstandard structures, agreements were reached between the Department of Energy, Richland Operations Office, and the U.S. Environmental Protection Agency to document status and closure requirements for these pit structures in a separate closure report (Refer to 306E/W Below Grade Pits Closure Report, CCN 147876, Washington Closure Hanford, Richland, Washington).
- Final (2/18/2014): This group of sites is listed in the 300-FF-2 Record of Decision as Final Closed Out. Institutional Controls to maintain Industrial Landuse are required.

Code: 300-43	Classification: Accepted
Names: 300-43; Unplanned Release Outside the 304 Building	Reclassification: Final Closed Out (5/12/2014)
Type: Unplanned Release	Start Date: 1/1/1972
Status: Inactive	End Date: 1/1/1989

Description: The waste site has been remediated and Interim Closed Out. It was the uranium contaminated soil around the 304 building (formerly the 304 Concretion Facility). The site also included residual contamination remaining in the 304 Storage Area (304 SA). The 304 Building had been posted "Fixed Contamination Area." Sections of concrete and asphalt on the north side of the building were painted gray and posted "Fixed Contamination Area," including the fenced area. The painted and posted "Fixed Contamination Area" continued in a thin strip along the west side of the building, then grew to include a concrete or asphalt pad on the south side of the building. A thin strip of gray paint continued along the east side of 304, ending at the south wall of the change room. This painted area on the east side of the building was not posted "Fixed Contamination Area," but the unpainted asphalt further east was posted. The signs in the unpainted asphalt were approximately in line with the east edge of the 304 change room. A row of "Radiologically Controlled Area" signs runs along the south side of the 304 and 303A Buildings with the signs facing to the south.

Location: The contamination was on the east, south, and west sides of the demolished 304 Building.

Release Description: Until 1989, the walls of the facility were not sealed to the concrete pad and there were numerous small holes in the walls. During concretion operations the floors and walls of the facility were washed down daily. This washing and splashing against the walls may have carried contamination out of the building. Additionally, there was no provision to contain this wash water at either of the large door openings. The fenced north pad also has no containment system for spills, wash water, or precipitation runoff.

Related Sites/ Structures: The site is related to operations in the 304 Building and Storage Area.

Process Description: During concretion operations, the 304 Facility floor was washed down daily with water. Because the steel walls of the main building were not sealed to the concrete wall base until 1989 (and there were numerous small holes in the walls) rinse water splashing against the steel walls might have carried contamination out of the building. In addition, there were no berms at the north and south doors to stop washdown water from leaving the building. The north fenced pad does not have a berm to contain spills or precipitation.

Waste Type: Soil

Waste Description: The waste is uranium contaminated soil remaining following operations of the 304 CF and 304 SA facilities. Sampling and analysis during TSD closure activities for the 304 CF and 304 SA showed uranium contamination at levels up to 256 micrograms/gram for shallow soils at the exterior storage pad.

Closure Info: Interim (11/28/2011): The 300-28, 300-43, 300-48, 300-249, and 300-16:3 excavation of building foundations, associated pipelines, and soils began on June 28 and was completed by July 29, 2010. Due to elevated radiologically contaminated soil found north of 303E Building, additional remediation was performed September 30, 2010, targeting specific locations with elevated readings. The excavation of the 300-28, 300-43, 300-48, 300-249, and 300-16:3 waste sites resulted in a total of approximately 2,914 bank cubic meters (BCM) (3,811 bank cubic yards [BCY]) of contaminated soil and debris. All material was direct loaded for disposal at the Environmental Restoration Disposal Facility (ERDF).

Remediation of the 300-28, 300-43, 300-48, 300-249, and 300-16:3 waste site excavations

included removal of the 303A, 304, 304A, 303B, 3732, 303C, 3707D, and 303E Buildings concrete slabs. The manholes and intersections of the 300-15 process sewer were excavated and removed from within the excavation boundaries. All the foundation debris such as concrete, metal rebar, miscellaneous piping (steam, water, etc.), and electrical conduit was excavated and removed from the waste sites. No anomalous materials were observed during remedial activities.

Although remediation and verification sampling was performed for the 300-161 waste site, it was then noted that 300-161 waste site was reclassified as a Rejected site and therefore did not require remediation or site closure process. The 300-161 waste site was removed from the RSVP. The 300-60, 300-61, 300-62, 300-161, 300-162, 300-176, 300-193 and 300-237 Rejected waste sites were located within the 300-28, 300-43, 300-48, 300-249, and 300-16:3 excavation layback.

Final: (Final) No additional remediation was performed at the site.

Code:	300-45	Classification:	Accepted
Names:	300-45; Location 3: Bird Droppings Area (Southwest Corner of the 316-5 Process Trenches Fence Line); SCA #1; Surface Contamination Area	Reclassification	Final Closed Out (2/20/2014)
Type:	Unplanned Release	Start Date:	
Status:	Inactive	End Date:	
Description:	The waste site was remediated in 1997 and Closed Out. Heavy vegetation growth and anthills are in the area. The area has been downposted and released. It is no longer marked or posted.		
Location:	The site was located adjacent to the southwest corner of the 316-5 Process Trench fence.		
Release Description:	It has been determined the area consisted of contaminated soil caused by the spread of radioactive rabbit feces.		
Waste Type:	Soil		
Waste Description:			
Closure Info:	Interim: One composite sample from the material was collected by the sampling team on 1/20/95, effectively removing much of the contamination. Scattered low-level contamination still remained. During the preparation of the Remedial Design Report/Remedial action Work Plan (RDR/RAWP) (DOE/RL-96-70), a decision was made to include this site with the remediation activities of the 316-5 Process Trenches in the 300-FF-1 Operable Unit work scope.		
	In 1997 the contaminated soil was removed and disposed of in the Environmental Restoration Disposal Facility (ERDF). Analysis of verification samples of the remaining soil show the area to be below cleanup standard levels. The area no longer poses a threat to human health or the environment and a December 17, 1997 (approval date) TPA change form (Control Number 118) lists the site as Closed Out.		
	Final (2/20/2014): This group of sites is considered Final Closed Out in the 300-FF-2 Record of Decision and meets the criteria for unrestricted landuse.		

Code:	300-46	Classification:	Accepted
Names:	300-46; Soil Contamination and French Drains	Reclassification	Final Closed Out (5/12/2014)

 Surrounding 3706 Building
Type: Unplanned Release**Start Date:****Status:** Inactive**End Date:**

Description: This waste site has been remediated and Interim Closed Out. In 2014, the site was reclassified to Final Closed Out. It consisted of the contaminated soil and nineteen french drains that surround the 3706 building. The 3706 building was demolished in June 2007. The extent of uranium, transuranic and chemical contamination of the 3706 Building and the surrounding area was estimated. The ground surrounding the 3706 building was not posted as a radiologically controlled area. The 3706 Building was posted "Fixed Contamination Area." Numerous pipes were observed exiting the exterior walls on all sides of the building. Several of these pipes were associated with rust stains on the side of the building and the nearby ground. Several french drains were also observed on all sides of the building.

Nineteen recognized miscellaneous stream drains (WIDS sitecodes 300-131 through 300-149) were located within the boundary of the waste site and have been consolidated with 300-46. Eighteen underground injection wells located within the 300-46 area were excavated and removed. One underground injection well (WIDS sitecode 300-149) was not removed because of its close proximity to the active 399-6-5 monitoring well.

Location: The 3706 building was located in the 300 Area on the southeast corner of Apple Street and Alaska Street.

Release Description: Contamination of the area surrounding the 3706 Building is believed to have resulted primarily from the operations and associated spills and releases. Although radiological surveys near and around the 3706 Building have not detected any radiologically contaminated soil, subsurface contamination is suspected. Contamination within the 3706 building that may have contributed to outdoor contamination is described in the "Past Practices Technical Characterization Study - 300 Areas - Hanford Site", WHC-MR-388. According to the report, the 3706 Building is contaminated with both radiological and chemical constituents, including high-activity substances. These wastes are composed of all components of the bismuth phosphate, REDOX, PUREX, and RECUPLEX processes along with laboratory cleansers, reagents and drying agents, as well as plutonium, uranium, thorium, and beryllium. Mercury deposits from multiple laboratory uses also were very prevalent. Additional chemical wastes result from bioassay and environmental sample analyses. Among these substances were sodium thiosulfate, hydroxylamine hydrochloride, barium chloride, barium nitrate, magnesium perchlorate, sodium iodine, sodium carbonate, thenoyltrifluoroacetone, thenoyltrifluoroacetone-benzene solutions, boric acid, silver nitrate, cupric oxide, arsenic nitrate, zinc nitrate, ammonium chloride, tartaric acid, and cupferron. Other wastes result from the spread of irradiated metal dusts and fines from the machining and grinding of metallurgical test samples. Contamination results from both inadequate containment systems and from spills, overflows, vaporizations, spreads of radioactive dusts and fines, and other incidents involving the loss of control of radioactive materials. The 3706 Building was never connected to the RLWS. All non-sanitary wastes from the structure were disposed to the 300 Area process sewer system. In the case of uranium, as with early work with uranium in other HEW facilities, few special precautions for work with radioactive substances were taken. Uranium contamination, especially dusts and fines from metallurgical testing, was spread from the hands, shoes, hair, and clothing of personnel into the 300 Area sanitary sewer system.

Related Sites/ Structures: The 3707C building was once connected to the 3706 building. The 3707C was demolished in 1996. Nineteen miscellaneous streams are documented around the 3706 and 3706A Buildings in the "Inventory of Miscellaneous Streams", Revision 3. These sites are identified in WIDS as site codes 300-131 through 300-149. It is also associated with an underground diesel tank - see sitecode 300-35.

Process Description: The original mission of the 3706 Building was to perform small-scale experiments with both low- and high-activity radioactive materials in support of all HEW production activities. The largest portion of staff and facilities in the building performed radiochemical trials aimed at improvements in the bismuth phosphate process. During the war years, some of the important variables and factors studied in the 3706 Building were the substitution of potassium permanganate for sodium dichromate as an oxidizing agent for plutonium, variations in acid strengths in several steps of the separations process, a decrease in the "digestion time" in the reduction step, methods for improving the centrifugability of lanthanum fluoride, the solubility of plutonium compounds and other substances in process solutions, methods of counting specific plutonium activity, characterization of fission products and plutonium decay products, the effects of hydrazine and lead in the dissolution process, and process equipment decontamination and corrosion studies. Other large sections of staff time and laboratories in the 3706 Building were devoted to metallurgical examination of irradiated fuel elements from the reactors, fuel development for the 313 Building, "physical technical" examination of graphite from the experimental levels of the 100 Area piles, special sample analyses from the 231 Plutonium Isolation Building in the 200 Areas separations plants, spectroscopy and radiocounting activities, and multifaceted sample analyses for the H. I. Division's environmental and personnel survey programs. In 1954, the 3706 Building underwent a major decontamination and remodeling effort, in which many of the laboratories were converted to offices. However, control (sampling) laboratories for fuel fabrication operations continued to operate in the building through the mid-1960's until they were transferred to the 3720 Building. Uranium fuel slugs, uranium powder, beryllium, and thorium continued to be handled, primarily in Laboratories 207-224, throughout this period. Rooms were renumbered in the building in early 1956, and the structure received a new roof in 1959. By 1964, the 3706 Building was called the General Services Building. Although it still contained some analytical laboratories, a majority of its space was devoted to mail services, duplicating, photographic, and drafting services, a first aid station, 300 Area patrol headquarters, and other administrative and clerical functions. During the 1970's and 1980's, the 3706 Building underwent several other minor remodelings as all laboratory work eventually was phased out. Today, the structure is unoccupied.

Waste Type: Chemicals

Waste Description: Contamination of the area surrounding the 3706 Building is believed to have resulted primarily from operations and associated spills and releases. Although radiological surveys near and around the 3706 Building have not detected any radiologically contaminated soil, subsurface contamination is suspected. The 3706 Building is contaminated with both radiological and chemical constituents, including high-activity substances. These wastes are composed of all components of the bismuth phosphate, REDOX, PUREX, and RECUPLEX processes along with laboratory cleansers, reagents and drying agents, as well as plutonium, uranium, thorium, and beryllium. Mercury deposits from multiple laboratory uses also were very prevalent. Additional chemical wastes include: sodium thiosulfate, hydroxylamine hydrochloride, barium chloride, barium nitrate, magnesium perchlorate, sodium iodine, sodium carbonate, thenoyltrifluoroacetone, thenoyltrifluoroacetone-benzene solutions, boric acid, silver nitrate, cupric oxide, arsenic nitrate, zinc nitrate, ammonium chloride, tartaric acid, and cupferron. Other wastes result from the spread of irradiated metal dusts and fines from the machining and grinding of metallurgical test samples. Contamination results from both inadequate containment systems and from spills, overflows, vaporizations, spreads of radioactive dusts and fines, and other incidents involving the loss of control of radioactive materials.

Closure Info: Interim (5/17/2013): The demolition of the 3706 Building aboveground structures was completed in June 2007. The 300-46 excavation of building foundations, associated pipelines, and soils began on January 17, 2011, and was completed by April 19, 2012, to a depth of 1.5 meters (5 ft).

The excavation of the 300-46 waste site resulted in a total of approximately 6,445 bank cubic

meters (BCM) (8,430 bank cubic yards [BCY]) of contaminated soil and debris. Based on historical drawings, approximately 300 meters (990 ft) of process sewer pipelines located within the 300-46 slab areas was also removed during excavation. All material was direct loaded for disposal at the Environmental Restoration Disposal Facility (ERDF).

Remediation of the 300-46 waste site excavation included removal of the 3706 Building concrete slab. All the foundation debris such as concrete, metal rebar, and miscellaneous piping (steam, water, etc.) was excavated and disposed at the ERDF. No anomalous materials or stained soil were observed during remedial activities.

Eighteen underground injection wells located within the 300-46 area were excavated and removed. One underground injection well (WIDS sitecode 300-149) was not removed because of its close proximity to the active 399-6-5 monitoring well.

On December 16, 2010, six characterization soil samples were collected from soils 0.5 meters (1.7 ft) below the slab area of the 3706 Building and from adjacent perimeter soils. On January 6, and 10, 2011, a total of 14 waste designation soil samples were collected from soils surrounding the 3706 Building. On February 10 through the 22, 2011, nine in-process soil samples were collected of the soil underlying the 300-15 pipeline surrounding the 3706 Building. Following sample analysis of the original excavation, it was determined that additional remediation was needed because one focused sample location (FS-131) exceeded groundwater and river protection RAGs for antimony and arsenic and could not be modeled to show protectiveness. This extra remediation, with agreement from the EPA was conducted on January 23, 2013. This remediation at the FS-131 area proceeded to a depth of approximately 3 meters (10 ft) below ground surface. Additional soil was removed from this location and disposed at the ERDF.

Final (5/12/2014): The 300-46, Soil Contamination and French Drains Surrounding 3706 Building waste site consisted of the remaining 3706 Building foundation and subgrade soils and structures including french drains. Remediation occurred in 2012 to a depth of 10 feet. Verification sampling was done in 2012 and 2013. The 300-46 waste site was remediated and has been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). Verification sampling results show that the site meets the CUL's for direct exposure and groundwater protection and river protection and support an industrial land use scenario. Contamination at the waste site did not extend into the deep zone (below 4.6 meters [15 ft]). Because the sample results do not meet the CULs for residential land use, the waste site will require institutional controls to maintain industrial land use. In accordance with this evaluation, the verification sampling results support a reclassification of the 300-46 waste site to Final Closed Out.

Code: 300-48	Classification: Accepted
Names: 300-48; 3732 Building Foundation; Thorium Oxide and Fuel Fabrication Chemical Wastes Around 3732 Building	Reclassification: Final Closed Out (5/12/2014)
Type: Unplanned Release	Start Date: 1/1/1949
Status: Inactive	End Date: 1/1/1970
Description:	This site has been remediated and Interim Closed Out. It was the 3732 Building foundation and the surrounding soil contamination. The site appeared as a gravel covered mound. There were no hazard postings except for two signs related to the adjacent 303B Building.
Location:	The site was located just north of the 3708 Building (south side of Ginko Street), between the 303B and 303C Buildings.

Release Description: The handling of thorium powder targets spread fine and particulate contamination throughout the 3732 building. Decontamination practices included hosing down the facility floors and walls, allowing contaminated liquid to be released to the surrounding soil.

Related Sites/ Structures: This site was associated with the 3732 Building (now demolished), and WIDS Sites 300-192 and 300-193.

Process Description: The 3732 Process Equipment Development Laboratory was constructed in 1949 as an engineering pilot plant for the triple-dip and lead-dip fuel canning processes. Powdered thorium oxide fuel targets for uranium-233 production were fabricated in the 3732 Building from 1965 to 1967. The thorium oxide program switched to pelletized targets in the 3722 Building in 1968. These new fuel targets were canned in the 3732 Building through 1970.

Waste Type: Demolition and Inert Waste

Waste Description: The foundation of the 3732 Building was not removed as part of demolition activities. The contamination areas on the foundation were covered with a fixative paint before the site was stabilized.

Waste Type: Soil

Waste Description: The 3732 Building contained standard fuel fabrication chemical wastes, as well as residual thorium oxide contamination in crevices and areas throughout and near the building. The contaminated soil is underground. The practice of flushing contamination on floors outside to the dirt is a possible explanation for the source of the soil contamination.

Closure Info: Interim (11/28/2011): The 300-28, 300-43, 300-48, 300-249, and 300-16:3 excavation of building foundations, associated pipelines, and soils began on June 28 and was completed by July 29, 2010. Due to elevated radiologically contaminated soil found north of 303E Building, additional remediation was performed September 30, 2010, targeting specific locations with elevated readings. The excavation of the 300-28, 300-43, 300-48, 300-249, and 300-16:3 waste sites resulted in a total of approximately 2,914 bank cubic meters (BCM) (3,811 bank cubic yards [BCY]) of contaminated soil and debris. All material was direct loaded for disposal at the Environmental Restoration Disposal Facility (ERDF).

Remediation of the 300-28, 300-43, 300-48, 300-249, and 300-16:3 waste site excavations included removal of the 303A, 304, 304A, 303B, 3732, 303C, 3707D, and 303E Buildings concrete slabs. The manholes and intersections of the 300-15 process sewer were excavated and removed from within the excavation boundaries. All the foundation debris such as concrete, metal rebar, miscellaneous piping (steam, water, etc.), and electrical conduit was excavated and removed from the waste sites. No anomalous materials were observed during remedial activities.

Although remediation and verification sampling was performed for the 300-161 waste site, it was then noted that 300-161 waste site was reclassified as a Rejected site and therefore did not require remediation or site closure process. The 300-161 waste site was removed from the RSVP. The 300-60, 300-61, 300-62, 300-161, 300-162, 300-176, 300-193 and 300-237 Rejected waste sites were located within the 300-28, 300-43, 300-48, 300-249, and 300-16:3 excavation layback.

Final: (Final) No additional remediation was performed at the site.

Code: 300-53	Classification: Accepted
Names: 300-53; Unplanned Release East Side of 303-G	Reclassification: Final Closed Out (2/18/2014)
Type: Unplanned Release	Start Date: 10/8/1996
Status: Inactive	End Date: 10/16/1996

Description: The site was remediated in 1996 and reclassified to Closed Out in 1999. It was considered Final Closed Out in 2014. The site was contaminated soil that was discovered on the surface of soil erosion area located within a posted Underground Radioactive Material (URM) Area. The actual erosion was at the end of a concrete splash guard underneath the water discharge pipe. A test of the fire suppression system exposed sub-surface contamination that had been previously covered with clean soil.

Location: The site is located on the east side of the 303-G Building, under the fire suppression water discharge pipe. On October 16, 1996, exposed contaminated soil was cleaned up and covered with clean soil.

Release Description: The contaminated area was identified on October 8, 1996. Removable radiological contamination measuring up to 36,000 disintegrations per minute beta-gamma per 100 cubic centimeter were reported on the surface of some slightly eroded soil. The soil area measured about 0.3 meter by 0.9 meter (1 foot by 3 feet). The radiological contamination was exposed when water was discharged from the building's fire suppression system. The water was directed onto a concrete splash guard, but still had substantial velocity when it left the splash guard and contacted the soil. The contaminated soil was exposed because of erosion. The area was posted with Contamination Area signs.

Waste Type: Soil

Waste Description: The waste was contaminated soil.

Closure Info: Interim: The WIDS Reclassification form 99-014 states that the exposed contaminated soil was cleaned up and covered with clean soil on October 16, 1996. The classification was changed to Closed Out in 1999.

Final (2/18/2014): This site is listed in the 300-FF-2 Record of Decision. Institutional Controls to maintain industrial land use are required. It does not meet the criteria for unrestricted landuse.

Code: 300-80	Classification: Accepted
Names: 300-80; 314 Building Stormwater Runoff and Steam Condensate; Miscellaneous Stream #268	Reclassification: Final Closed Out (5/12/2014)
Type: French Drain	Start Date:
Status: Inactive	End Date:

Description: The waste site has been remediated and Interim Closed Out. In 2014, the site was reclassified to Final Closed Out. The drain structure was removed along with the 314 building foundation and soil. The site was a square concrete structure adjacent to the 314 Building and next to a fenced stairway leading down. The site was covered by a steel plate marked with a sign "Radioactive material, internally contaminated." The site does not appear to be a stormwater drain. it was above the surrounding grade and no drain pipes from the roof enter the site. The "Inventory of Miscellaneous Streams", Revision 3, says the stream has been eliminated because the source has been permanently abandoned and rerouted to the process sewer.

The responsible contractor agrees that the site did previously receive steam condensate, but is unable to verify stormwater discharges. Further inspection under the steel cover and the review of facility drawings are required to verify the function and site type.

Location: The site was on the west side of the 314 Building, adjacent to the wall, 9 meters (27 feet) north of the southwest corner.

Related Sites/ Structures: The french drain is related to the 314 Building (sitecode 300-218). An area of soil

contamination exists outside the 314 Building. This unplanned release (sitecode 300-24) may be the source of the contamination within structure.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Equipment

Waste Description: The structure for this site appears to have become contaminated (see photograph).

Waste Type: Steam Condensate

Waste Description: DOE/RL-95/82, Revision 3 says that the site was used for stormwater runoff and steam condensate. This site does not appear to be used for stormwater runoff, since it is above the surrounding grade and no pipes from a roof enter the site. The stream was eliminated March, 1995 and rerouted to the process sewer.

Closure Info: Interim (9/29/2011): Remedial action activities at the 300-16:2, 300-24, 300-80, and 300-218 waste sites were carried out from December 21, 2009 to May 20, 2010. The excavation reached a maximum depth of 3.0 meters (9.8 ft) near the center and southwest corner of the collective waste sites. Approximately 6,275 cubic meters or 14,995 tons of materials were removed from the waste site excavation and direct loaded for disposal at the ERDF. There was no waste staging pile area footprint or overburden soil stockpile associated with these waste sites. The utility pole that was associated with the 300-16:2 subsite was removed. The autoclave pit underlying the former 314A Building was removed. The structures associated with the 300-80 drain were removed. The concrete slabs associated with the 314, 314A, and 314B Buildings have been removed.

During remediation, a suspected french drain was found at the base of the exterior stairwell on the southwest edge of the 314 Building slab. Discussions with the EPA concluded that this drain could be remediated concurrently with the 314 Building waste sites. This suspected french drain was removed. Two pits within the main 314 Building extended below the level of the current excavation. Discussions with EPA concluded that the remaining portions of these pits could remain in place. The 300-285 (300FF2-018; FD 32), 300FF2-270 and 300-240 underground injection control (UIC), wells, were within the footprint of the 314 excavation layback. The listed UIC wells are not part of the waste site. They are listed for tracking purposes. The UIC wells have a "Not Accepted" classification status and are still present at the site.

All the foundation debris such as concrete, metal rebar, miscellaneous piping (e.g., steam, water, etc.), and electrical conduit was excavated and removed from the waste sites. No anomalous materials were observed during remedial activities.

Post-excavation radiological survey of the 314 Building slab was performed in June 2010. Additional radiological surveys of the 300-16:2 utility pole were performed in March 2011. The field radiological measurements survey results did not identify any residual radiological contamination above background levels.

Final: The 300-24, 300-80, 300-218, and 300-16:2 waste sites were remediated and have been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). Verification sampling results show that the site meets the CUL's for direct exposure and groundwater protection and river protection and support an industrial

land use scenario. Contamination at these waste sites did not extend into the deep zone soils. Because the remediation of the waste sites did not meet residential land use cleanup levels, the waste sites require institutional controls to maintain industrial land use. In accordance with this evaluation, the verification sampling results support a reclassification of the 300-24, 300-80, 300-218, and 300-16:2 waste sites to Final Closed Out.

Code:	300-109	Classification:	Accepted
Names:	300-109; 333 Building Stormwater Runoff; Miscellaneous Stream #455	Reclassification	Final Closed Out (2/20/2014)
Type:	Injection/Reverse Well	Start Date:	
Status:	Inactive	End Date:	
Description:	The waste site was remediated and Interim Closed Out. The french drain and contaminated soil were removed and disposed into ERDF in January 2010. The site consisted of a 10-cm (4-in.) collection line and a french drain disposal system for stormwater collection and disposal north of the 333 Building. This system was designed and installed in 1990.		
Location:	The Inventory of Miscellaneous Streams Report states it is located approximately 18.3 meters (60 feet) north of the 333 Building.		
Related Sites/ Structures:	The site is associated with the 333 Building and UPR-300-46.		
Process Description:	The Inventory of Miscellaneous Streams Report states the injection well is below grade and drains a network of four catch basins. The network is known as SS-2 in document WHC-SD-L125-ES-001. A 300 Area Storm Water Engineering Study noted that the existing 10-cm (4-in.) collection pipe was undersized for the projected flow. A white PVC pipe emerged laterally from the asphalt in the approximate location described in the Inventory of Miscellaneous Streams (DOE-RL-95-82, Rev. 3).		
Waste Type:	Stormwater Runoff		
Waste Description:	The "Inventory of Miscellaneous Streams", Revision 3, states that the site receives less than 1.9 liters per minute (0.50 gallons per minute) of stormwater runoff only.		
Closure Info:	Interim: Remediation of the UPR-300-46 waste site was performed from April 28 through June 4, 2009. The soil within the waste site footprint was excavated to a depth of 1 meter (3 ft) below ground surface (bgs), and the resulting 75 bank cubic meters (BCM) (100 bank cubic yards [BCY]) of soil was disposed at the Environmental Restoration Disposal Facility (ERDF). Remediation of the 300-109 waste site was performed from April 28 through April 29, 2009. The soil and asphalt within the waste site footprint were excavated to an average depth of 2.6 meters (8.5 ft) bgs, with a maximum depth of 3.7 meters (12 ft) below ground surface at the location of the drain. The resulting 325 BCM (425 BCY) of soil was disposed at ERDF. The french drain and associated vitrified clay pipe was found and removed during the remediation. The PVC pipe noted in documentation from the 1990's was not found during remediation. A radiological survey was done to confirm the excavations were complete.		

This report demonstrates that the 300-109, 333 Building Stormwater Runoff and UPR-300-46, Contamination North of 333 Building sites have met the rural-residential scenario RAOs established in the RDR/RAWP and the ROD. The evaluation shows that the sites have been successfully remediated and that there are no residual hazardous/dangerous materials present above the RAOs in the soil. Therefore, the 300-109 and UPR-300-46 waste sites are protective of human health, groundwater, and the Columbia River.

Final (2/20/2014): This group of sites is considered Final Closed Out in the 300-FF-2 Record of

Decision and meets the criteria for unrestricted landuse.

Code: 300-110 **Classification:** Accepted
Names: 300-110; 333 Building Stormwater Runoff; **Reclassification** Final Closed Out (2/18/2014)
Miscellaneous Stream #456
Type: Injection/Reverse Well **Start Date:**
Status: Inactive **End Date:**

Description: The 300-110 waste site was Interim Closed Out with the 618-1 site. Remedial actions at this site have been performed in accordance with remedial action objectives and goals established by the U.S. Environmental Protection Agency and the U.S. Department of Energy, Richland Operations Office, in concurrence with the Washington State Department of Ecology. The selected remedial action involved excavating the site to the extent required to meet specified soil cleanup levels and disposing of contaminated excavation materials at the Environmental Restoration Disposal Facility

The site was a 0.41 meter diameter drain with a metal grate labeled "Internal Radioactive Contamination" due to its proximity to the WIDS Site 618-1 Burial Ground. The drain had a dirt bottom that is approximately 0.61 (2 feet) below the surface of the asphalt and an overflow line that drains to the process sewer.

Location: The site was a drain located 12.6 meters (41.3 feet) east of the southeast end of the 333 Building.

Related Sites/ Structures: The site is associated with the 333 Building. This site is associated with an unplanned release WIDS Site UPR-300-17. The 618-1 Burial Ground is located adjacent to and just northeast of this unplanned release.

Waste Type: Stormwater Runoff

Waste Description: The "Inventory of Miscellaneous Streams", Revision 3, lists the flow rate as less than 1.9 gallons per minute (0.50 gallons per minute). This document lists the stream as containing stormwater only. The disposal structure is labeled as being internally contaminated.

Closure Info: Interim: The 618-1 Burial Ground, two subsites, three consolidated sites and four co-located sites were remediated as a group. This group included WIDS sitecodes 618-1, 618-1:1, 618-1:2, 333 LHWSA, UPR-300-13, UPR-300-14, 300-110, 303-M SA, 303-M UOF and 333 ESHWSA. Parts of waste sites 300-15, 300-259 and UPR-300-17 were also remediated along with 618-1. Several facilities were built over the top of portions of the 618-1 Burial Ground after it ceased to operate. These facilities were demolished and their debris taken to the Environmental Restoration Disposal Facility (ERDF) prior to the start of the burial ground remediation project.

Field remediation activities at the 618-1 Burial Ground were performed between September 17, 2008 and September 10, 2009, in accordance with the RDR/RAWP. Approximately 47,332 metric tons (52,160 US tons) of soil and debris was excavated and disposed of at ERDF. No excavated soil was used as backfill. Waste encountered during excavation of the 618-1 waste site consisted mostly of contaminated soil, metal pipe, crucibles, laboratory glassware, empty metal containers, and some LDR material. Twenty metal drums containing personal protective equipment (PPE) were removed from the trenches. The PPE was about 80% decomposed. Several bottles containing liquid and/or powder were also removed. One relatively large area on the south side of the burial ground was stained yellow presumably from acid leaks known to have occurred at the site.

Some land disposal restricted (LDR) materials, like lead solids contaminated with barium and chromium, were identified among the debris. The LDR material was segregated from the bulk soil and non-LDR debris for disposal. The bulk soil and non-LDR debris was sorted and segregated in the burial trenches. After sorting, the remaining bulk soil debris stockpiles were sampled to ensure that the material was in compliance with land disposal restrictions. The released stockpiled material was transported to ERDF for disposal. Land disposal restricted materials that had been segregated for treatment were transported to ERDF under a separate waste profile.

Three sites (300-15 Process Sewer, 300-259 and UPR-300-17 Metal Shavings Fire) were partially remediated with the 618-1 remedial action.

Final (2/18/2014): This group of sites is listed in the 300-FF-2 Record of Decision as Final Closed Out. Institutional Controls to maintain Industrial Landuse are required.

Code:	300-121	Classification:	Accepted
Names:	300-121; 3621D Building Stormwater Runoff; Injection Well #26; Miscellaneous Stream #403	Reclassification	None
Type:	French Drain	Start Date:	
Status:	Inactive	End Date:	
Description:	The site is a french drain with a concrete base. The site is on a slope so the top of the drain rises between 8 to 27 centimeters (3.1 to 10.6 inches) above the ground surface. Approximately 20 centimeters (7.9 inches) from its top, the drain starts to narrow. The drain is covered by a 1.37 meter (4.49 foot) metal lid. The lid appears to fit flush with the concrete base. The lid is labeled "Confined Space" and has "FD 26" written on it. The site is surrounded by sandy soil and rocks.		
Location:	The site is west of the southwest corner of the 3621D Building. It is outside the fence that surrounds the building. The 3621D building is located southeast of the intersection of Locust Street and the George Washington Way extension.		
Related Sites/ Structures:	The site is associated with the 3621D Building.		
Process Description:	The drain received effluent from floor drains inside the 3621-D building. All the floor drains inside the 3621-D building have been plugged.		
Waste Type:	Water		
Waste Description:	The site received condensate from the air receivers inside the 3621D Building. It may also have received any spills that reached the floor drains. There is a potential for contamination from petroleum and from ethylene glycol.		

Code:	300-123	Classification:	Accepted
Names:	300-123; 366 Building Fuel Oil Bunker Loading Station Steam Condensate French Drain; Miscellaneous Stream #342	Reclassification	Final Closed Out (5/12/2014)
Type:	French Drain	Start Date:	
Status:	Inactive	End Date:	
Description:	The waste site has been remediated and Interim Closed Out with the 300-6 waste site. In 2014,		

the site was reclassified to Final No Action. The site was a french drain that received steam condensate from the 366 Building fuel oil bunker loading station. The french drain was removed between August 24 and September 14, 2010 during the excavation of waste site 300-6 (D4-300-018). The french drain was a metal culvert that is covered with a 0.69 meter (2.25 foot) diameter diamond plate metal cover with four 1.9 centimeter (0.75 inch) holes in the cover. The lid is discolored by rust. Inside the french drain, there is soil and rock about 1.4 meters (4.5 feet) from the top of the culvert. There are also granular ash deposits on the ground in the general area east northeast of the 384 powerhouse. The soil on the south side of the French Drain has eroded into the excavation for 300-6 exposing the metal culvert.

- Location:** The site is located southwest of the southeast corner of the 3715 building.
- Related Sites/ Structures:** The site received effluent steam condensate from the 366 Building fuel oil bunker loading station. In the area were also ancillary piping 300-273 and 300-6, 366/366A Fuel Oil Bunkers.
- Process Description:** Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.
- Waste Type:** Steam Condensate
- Waste Description:** According to the "Inventory of Miscellaneous Streams," Revision 3, the site has the potential to be contaminated with fuel oil. When this site was active, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute). As part of the DynCorp review, Michelle Gunter was contacted. She recalled a spill to one of the injection wells. Documentation was found for a small spill (less than one gallon) into injection well #342 (300-123). Historical documentation for changes to the "Inventory of Miscellaneous Steams" was reviewed. It was found that streams 653 (300-124), 342, and 344 (300-122) all have the same comment. This may be a mistake in the report. No evidence of discharges to streams 653 and 344 have been found.
- Closure Info:** Interim (1/9/2012): The 300-6 waste site (fuel oil bunkers) was expected to be excavated to groundwater, a depth of approximately 15.8 meters (52 ft) below ground surface (bgs), as necessary to remediate contaminated soil. Remediation of the waste site was performed from August 2 to December 8, 2010. The western portion of the 300-6 waste site excavation did reach the groundwater, and a pool of water remains in the floor of the excavation. The excavation was approximately 15 meters (49.5 ft) deep in the 300-6 west borehole location (when measured to the surface of the pool of water) and approximately 11.5 meters (37.7 ft) deep in the 300-6 east borehole location. The 300-6 and associated waste sites' excavation resulted in approximately 34,770 bank cubic meters (45,477 bank cubic yards) of material removed for disposal at the Environmental Restoration Disposal Facility (ERDF).
- Debris (piping and concrete) and soil from the remediation of the 300-6 and associated waste sites were direct loaded to ERDF. No overburden soil stockpiles were associated with the waste sites as a result of remediation, and no anomalies were noted.
- The 300-123 UIC was identified as a WIDS waste site. The french drain was removed as part of the layback to remove the contaminated soil at the 300-6 waste site. The french drain consisted of soil and rock that extended to approximately 1.4 meters (4.5 ft) bgs. The existing floor of the 300-6 waste site excavation is approximately 11.3 m (37 ft) bgs.
- The 300-65, 300-66, 300-122, and 300-124 UICs were located within the footprint of the 300-6 excavation layback and also removed during the 300-6 excavation. The 3715, 303E and 303J building slabs were removed during the 300-6 waste site excavation because they were located in the excavation layback as well.

The 300-268 site was located within the 300-6 layback area. It was excavated to a depth of 3.0 meters (9.8 ft).

During excavation of the 300-6 waste site, it was verified that the eastern half of the 300-273 waste site pipeline had been previously removed. In addition, as the project conducted test pits along the western half of the 300-273 waste site pipeline right-of-way on November 3, 2010, no pipeline structure was encountered at the elevations presented in the as-built drawings for the pipeline (USAEC 1974). Also in November 2010, the project excavated two test pits along the former 384 Powerhouse foundation within the UPR-300-42 waste site. No below-grade structure was noted, and no visible soil staining was observed, as was expected since the site was reportedly removed in 2009.

During excavation of the 300-6 waste site, it was verified that the eastern half of the 300-273 waste site pipeline had been previously removed. In addition, as the project conducted test pits along the western half of the 300-273 waste site pipeline right-of-way on November 3, 2010, no pipeline structure was encountered at the elevations presented in the as-built drawings for the pipeline. Also in November 2010, the project excavated two test pits along the former 384 Powerhouse foundation within the UPR-300-42 waste site. No below-grade structure was noted, and no visible soil staining was observed, as was expected since the site was reportedly removed in 2009 with the demolition of the 384 powerhouse structure.

Final: The 300 Area Fuel Oil bunkers and associated waste sites were remediated in 2010. The excavation extended to groundwater at a depth of 52 feet. The 300-6, 300-123, 300-268, 300-273, and UPR-300-42 waste sites were remediated and have been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). Verification sampling results show that the site meets the CUL's for direct exposure and groundwater protection and river protection and support a residential land use scenario. Contamination that extended into the deep zone (greater than 4.6 meters [15 ft] bgs) has been removed; therefore, institutional controls to prevent uncontrolled drilling or excavation into the deep zone are not required. In accordance with this evaluation, the verification sampling results support a reclassification of the 300-6, 300-123, 300-268, 300-273, and UPR-300-42 waste sites to Final Closed Out.

Code: 300-175	Classification: Accepted
Names: 300-175; 3714 Building Steam Condensate; Miscellaneous Stream #434	Reclassification: None
Type: French Drain	Start Date:
Status: Inactive	End Date: 1/1/1995
Description: The site was a 36 centimeter (14.2 inch) diameter, concrete french drain with a metal cover on the west side of the demolished 3714 building. The inside had been dry and filled with cobbles. There are no steam lines entering the site, and no steam lines are visible inside the drain. In August 2011, the drain structure was filled with grout.	
Location: The 300-174 french drain is located on the west side of the 3714 Building.	
Related Sites/ Structures: The site was related to the 3714 Building.	
Process Description: Steam was produced from sanitary water that has been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites receive steam condensate from the steam distribution lines. When	

used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The waste was nondangerous/nonradioactive steam condensate only. The flow rate when the site was active was less than 0.038 liters (0.01 gallons) per minute.

Code: 300-214

Classification: Accepted

Names: 300-214; 300 Area Retention Process Sewer; 300 RPS

Reclassification: None

Type: Radioactive Process Sewer

Start Date: 1/1/1953

Status: Inactive

End Date:

Description: The waste is an underground carbon steel and polyvinyl chloride pipeline connecting the 300 Area laboratory facilities (308, 324, 325, 326, 327, and 329 buildings) to the 307 Retention Basins. The Retention Process Sewer (RPS) provided radioactive monitoring and transport of nonhazardous, potentially radioactive process waste. The site has been divided into two subsites. Subsite 1 has been remediated and reclassified to Final Closed Out. It was the Removed Sections of the 300 Area Retention Process Sewer. Subsite 2 is the Retained Sections of the 300 Area Retention Process Sewer.

Location: The RPS lies below grade in the 300 Area. The system connects the 324, 325, 326, 327, 329, and 309 Buildings, discharging to the 307 Retention Basins.

Related Sites/Structures: The retention process sewer includes four diverter stations, a sample pit northwest of basin 1, and the 3707-F control shack. The system is related to the 340 Waste Handling Complex, the process sewer, and the 300 RLWS.

Process Description: The Retention Process Sewer (RPS) collected non-hazardous, potentially radiologically-contaminated waste from the 324, 325, 326, 327, and 329 buildings. When the 308 building was active, it also generated effluent discharged to the RPS. The potentially contaminated effluent is discharged to the 307 Retention Basins. The retention basins are periodically sampled and analyzed. Waste below a predetermined level (5,000 picocuries per liter) is discharged from the basins through the Process Sewer to the 300 Area Treated Effluent Disposal Facility (TEDF). Waste above the discharge criteria is held for transport to the 200 Area double shell tanks. Beta-gamma detectors in the four diverters at the laboratory buildings monitor the RPS waste activity. Prior to October 1, 1998, if the RPS waste was contaminated, it was diverted to the Radioactive Liquid Waste Sewer (RLWS). During normal operations the waste from the RPS is held in one of the 307 Retention Basins for sampling and discharge. If the facility beta-gamma detector alarm trips, all waste flowing in the RPS is rerouted to a different one of the 307 retention basins. This waste will be sampled, analyzed and disposed of accordingly. The 324 and 327 Buildings have opted not to use this method of containment. In the event that the facility RPS beta-gamma detector alarms at either of these facilities, the waste transfer to the RPS is halted and contained at the facility.

Waste Type: Process Effluent

Waste Description: The waste discharged to the Retention Process Sewer (RPS) is nonhazardous, potentially radioactive waste (not to exceed 5,000 picocuries per liter) from the 300 Area Laboratory facilities. In FY 1998, approximately 12 million liters (3 million gallons) flowed through the RPS to the 307 Retention Basins.

This Site has the Following SubSites:

Code: 300-214:1
Names: 300-214:1; Removed Sections of the 300 Area Retention Process Sewer
Code: 300-214:2
Names: 300-214:2; Retained Sections of the 300 Area Retention Process Sewer

Code: 300-214:1 **Classification:** Accepted
Names: 300-214:1; Removed Sections of the 300 Area Retention Process Sewer **Reclassification:** Final Closed Out (9/9/2015)
Type: Radioactive Process Sewer **Start Date:**
Status: Active **End Date:**

Description: The subsite consists of those portions of the 300-214, of the 300 Area Retention Process Sewer that were removed prior to 2015.

Location: The system was located throughout the 300 Area. It connected the 324, 325, 326, 327, 329, and 309 Buildings, discharging to the 307 Retention Basins. There was a leg of piping from the 3714 Building that connected into the 300-214, 300 Area Retention Process Sewer, on the north side of the 325 Building.

Process Description: The RPS collected nonhazardous, potentially radiologically contaminated waste from the 324, 325, 326, 327, and 329 Buildings. When the 308 Building was active, it also generated effluent that was discharged to the RPS. The potentially contaminated effluent was transported to the 307 Retention Basins. The retention basins were periodically sampled and analyzed. In later years of operation, effluent below a predetermined level (5,000 picocuries per liter) was discharged from the basins through the Process Sewer to the 300 Area Treated Effluent Disposal Facility. Effluent above the discharge criteria was held for truck or rail transport to the 200 Area double shell tanks. Prior to October 1, 1998, if the RPS effluent was radiologically contaminated it was diverted to the 300 Area RLWS.

Closure Info: Final (9/9/2015): Waste Sites 300 RLWS:1, 300 RLWS:2, 300 RRLWS:1 and 300-214:1 were remediated as a group and documented in CVP-2015-00011. The final action 300 Area ROD for the 300 RLWS:1, 300 RLWS:2, 300 RRLWS:1, and 300-214:1 subsites established RAOs based on an industrial land use.

Remediation of the 300 RLWS:1, 300 RLWS:2, 300 RRLWS:1, and 300-214:1 subsites, performed from March 26 through December 15, 2014, consisted of removal and disposal of contaminated soil, gravel, pipe, and concrete. The excavation resulted in approximately 15,071 bank cubic meters (19,712 bank cubic yards) of contaminated soil and debris being disposed at the Environmental Restoration Disposal Facility. No overburden soil was salvaged from the 300 RLWS:1, 300 RLWS:2, 300 RRLWS:1, and 300-214:1 subsites excavation and no staging pile areas were utilized.

Pipeline segments of the west side of the 308 Building and within the 340 Complex were removed with the demolition and excavation of the facilities.

Remediation of the 300 RLWS:1 and 300 RLWS:2 subsites was performed from March 26 to December 15, 2014. Approximately 9,321 bank cubic meters (BCM) (12,191 bank cubic yards [BCY]) of excavated materials were removed and direct loaded for disposal at the ERDF.

Remediation of the 300 RRLWS:1 subsite was performed from June 3 through December 15, 2014. Approximately 106 BCM (139 BCY) of excavated materials were removed and direct loaded for disposal at ERDF.

Remediation of the 300-214:1 subsite was performed from May 13 through November 20, 2014. Approximately 5,643 BCM (7,381 BCY) of excavated materials were removed and direct loaded for disposal at ERDF.

No elevated radiological readings (above background levels) were detected within 300 RLWS:1, 300 RLWS:2, 300 RRLWS:1, and 300-214:1 excavation areas.

Because some piping systems were located immediately adjacent to each other, there was a significant overlap of the 300 RLWS:1, 300 RLWS:2, 300 RRLWS:1, and 300-214:1 subsite excavations. Therefore, the volumes for each subsite excavation were estimated.

The SubSite is Part Of:

Code: 300-214

Names: 300-214; 300 Area Retention Process Sewer; 300 RPS

Code: 300-214:2

Classification: Accepted

Names: 300-214:2; Retained Sections of the 300 Area Retention Process Sewer

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Active

End Date:

Description: The site consists of those portions of the 300-214, 300 Area Retention Process Sewer that are being retained due to their proximity to adjacent active facilities and utilities.

Location: This section is primarily along Spruce Street between Wisconsin Avenue and Riverview Loop.

The SubSite is Part Of:

Code: 300-214

Names: 300-214; 300 Area Retention Process Sewer; 300 RPS

Code: 300-218

Classification: Accepted

Names: 300-218; 314; 314A and 314B Buildings; Engineering Development Laboratory

Reclassification: Final Closed Out (5/12/2014)

Type: Fabrication Shop

Start Date: 1/1/1943

Status: Inactive

End Date: 1/1/1996

Description: The waste site has been remediated and Interim Closed Out. In 2014, the site was reclassified to Final Closed Out. It consisted of the 314 Building and the associated 314A and 314B Buildings. Both the 314A and 314B buildings were attached to the 314 Building. Because the 314A building was demolished some time ago, the remaining 314 and 314B buildings were often referred to as the 314 facilities, or collectively as the 314 Building. The 314 and 314B facilities were demolished down to the slab October thru December 2005. The buildings have been demolished down to the slab.

The 314A Autoclave Pit was attached on the northeast corner of the 314 Building. The 314A Building included a basement which became radiologically contaminated by the autoclave operations. The above ground portion of the building was previously demolished, in the 1950s. The history and details of the 314A Building and its demolition are not well documented. The basement was left in place, filled with dirt and covered with concrete. The concrete slab was fenced off.

The 314B Stress Rupture Test Facility was attached to the northwest corner of the building and consisted of eight small rooms with blow out roof panels and blast doors for the purpose of conducting high pressure experiments. The facility was placed in standby in June of 1996. The water and sprinkler systems were drained, and the ventilation was shutdown and capped where needed. The facility was cleaned out with the exception of a few large pieces of equipment, which were excessed in place or have storage agreements with the owners.

Location: The 314 and 314A buildings were located in the northwest section of 300 Area, near the corner of Alaska and Ginko Streets.

Release Description: A number of known releases occurred at the 314 building during the period from 1943 to 1971 when the building was used for reactor fuel manufacturing. Many were associated with sludge or turnings fires and autoclave explosions. Others resulted from the lathe and machining operations, extrusion press work, outgassing and other fuel fabrication operations.

A fire occurred in the high bay area during the 1950's. The fire spread contamination through the high bay area. Water used to fight the fire contaminated soil around the facility. The smoke permanently contaminated the inside of the building. Another large fire occurred several years later and is known to have contaminated the exterior grounds with washdown run off. Historical practices were also known to include washing the floor with hoses and directing the flow outdoors. Other operations with uranium also are known to have contributed to exterior soil contamination. Historical documents have noted underground radioactive contamination on the west side of the building. Efforts to decontaminate the site included removal of a concrete slab, water drainage trench, and supporting lumber and soil under the slab. Documents also indicate uranium contamination embedded in the concrete walls, floors and overhead piping inside the building, principally in the high bay area.

Related Sites/ Structures: The building is associated with 300-16, 300-24 and 300-28.

Process Description: The 314 "Press Building", built in 1944, had numerous uses before being retired. The original mission of the 314 Building was fabrication of uranium metal fuel for single pass production reactors. Processes included uranium casting machining, and chemical milling, however in 1944 the facility was used for outgassing and straightening of fuel rods that were extruded offsite. In 1945, the onsite fuel rod extrusion process began in the 314 building. The uranium billets arrived at the 314 building for extrusion, outgassing and straightening. Then they were sent to the 313 building for machining, canning and inspection. The rods were returned to the 314 building for autoclaving and radiographic testing. Other related operations included chip recover, melt plant operations, and oxide burner operations for uranium recovery from scraps and dust. Later, the facility was used for testing of zirconium fuel cladding alloys.

After the closure of the single pass reactors, the 314 building housed several research and craft activities. These included space for test equipment and mockups. The space was used for housing autoclaves, high-pressure and high temperature loops and prototype equipment that was in development and testing. A combined shop and repair area were located in the building. Charging machines and reactor auxiliary equipment were developed in the building. Since the 1970's, laboratory work was done by PNL's Materials Department.

This building was one of the original World War II era 300 Area, MED/DuPont structures. Several rectangular additions have been constructed along the north side of both 314 and 314B. The building frame work was bolted steel. The gable roof was constructed of corrugated asbestos. Exterior walls and partitions were concrete block. The floor was reinforced concrete with test pits and a basement room at the west end. A small second floor or mezzanine existed at the west end of the building. The principal utilities were sanitary water and sewer, steam, normal building power, compressed air and process sewer. The building had a wet sprinkler system. Air conditioning and heating was provided in the office areas along the north side of

the building and in the second floor mezzanine through the use of heat pump systems. Evaporative cooling and heating by steam space heaters was provided within the high/open bay area. Electric service was provided from a 1000 KVA transformer outside the building. Service voltage was 480/277 V. Distribution voltage within the building from dry transformers, was 120/208 V and 120/240 V. A 7.5 ton bridge crane serves the high bay on the south side.

The 314B Stress Rupture Test Facility was attached to the northwest corner of the building and consisted of eight small rooms with blow out roof panels and blast doors for the purpose of conducting high pressure experiments. The facility was placed in standby in June of 1996. The water systems and sprinkler systems were drained and the ventilation was shutdown and capped where needed. The facility was cleaned out with the exception of a few large pieces of equipment, which were excessed in place or have storage agreements with the owners. Power remained connected to the facility. Some interest was shown in possibly leasing the facility to a private enterprise. However, the legacy contamination remaining in the high bay prevented this from occurring.

Waste Type: Sludge

Waste Description: After the facility demolition in 2006 the pits and trenches were filled with soil. In 1997 sludge and dust residue was observed in the building. Sludge was retrieved from a pit and a trench inside the 314 building in 1996. The sludge contained PCB's, lead and mercury at regulated levels. Other contaminants included uranium, thorium, cadmium, bismuth, aluminum and barium. Contaminated soil is likely to be found around the building exterior.

Waste Type: Equipment

Waste Description: The building had contaminated duct work that was posted and contained a large inventory of fixed uranium contamination. The HEPA filtered exhaust system had the potential for radiological contamination and was posted. There was also contaminated equipment and items that were being stored or had been excessed in place. All equipment was disposed during facility demolition in 2006.

Waste Type: Asbestos (non-friable)

Waste Description: The 314 Building was over 50 years old, and as such, its construction materials contained asbestos, mercury switches, light fixtures containing PCB's, and possibly lead based paints. Asbestos may be found in tile, insulation, and transite. Significant amounts of asbestos exist in the materials of construction such as the roof, pipe insulation, etc. During the facility demolition in 2006 all the materials were removed and disposed of.

Waste Type: Equipment

Waste Description: The building was likely to have contained contaminated floor drains, both chemical and radioactive. There was a potential that mercury could exist in some of the older drains and sewer lines. No known inventory (mercury) was found during the facility characterization.

Closure Info: Interim (9/29/2011): Remedial action activities at the 300-16:2, 300-24, 300-80, and 300-218 waste sites were carried out from December 21, 2009 to May 20, 2010. The excavation reached a maximum depth of 3.0 meters (9.8 ft) near the center and southwest corner of the collective waste sites. Approximately 6,275 cubic meters or 14,995 tons of materials were removed from the waste site excavation and direct loaded for disposal at the ERDF. There was no waste staging pile area footprint or overburden soil stockpile associated with these waste sites. The utility pole that was associated with the 300-16:2 subsite was removed. The autoclave pit underlying the former 314A Building was removed. The structures associated with the 300-80 drain were removed. The concrete slabs associated with the 314, 314A, and 314B Buildings have been removed.

During remediation, a suspected french drain was found at the base of the exterior stairwell on the southwest edge of the 314 Building slab. Discussions with the EPA concluded that this

drain could be remediated concurrently with the 314 Building waste sites. This suspected french drain was removed. Two pits within the main 314 Building extended below the level of the current excavation. Discussions with EPA concluded that the remaining portions of these pits could remain in place. The 300-285 (300FF2-018; FD 32), 300FF2-270 and 300-240 underground injection control (UIC), wells, were within the footprint of the 314 excavation layback. The listed UIC wells are not part of the waste site. They are listed for tracking purposes. The UIC wells have a "Not Accepted" classification status and are still present at the site.

All the foundation debris such as concrete, metal rebar, miscellaneous piping (e.g., steam, water, etc.), and electrical conduit was excavated and removed from the waste sites. No anomalous materials were observed during remedial activities.

Post-excavation radiological survey of the 314 Building slab was performed in June 2010. Additional radiological surveys of the 300-16:2 utility pole were performed in March 2011. The field radiological measurements survey results did not identify any residual radiological contamination above background levels.

Final: The 300-24, 300-80, 300-218, and 300-16:2 waste sites were remediated and have been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). Verification sampling results show that the site meets the CUL's for direct exposure and groundwater protection and river protection and support an industrial land use scenario. Contamination at these waste sites did not extend into the deep zone soils. Because the remediation of the waste sites did not meet residential land use cleanup levels, the waste sites require institutional controls to maintain industrial land use. In accordance with this evaluation, the verification sampling results support a reclassification of the 300-24, 300-80, 300-218, and 300-16:2 waste sites to Final Closed Out.

Code: 300-219	Classification: Accepted
Names: 300-219; 300 Area Waste Acid Transfer Line	Reclassification: Final Closed Out (5/12/2014)
Type: Process Sewer	Start Date:
Status: Inactive	End Date:
Description: This site has been remediated and Interim Closed Out. In 2014, the site was reclassified to Final Closed Out. It included the transfer lines connecting the various components of the 300 Area Waste Acid Treatment System (WATS) and the 300 Area Uranium Recovery Operations. The piping, located in the Pipe Trench (300-224), included the 333 N Fuels process transfer lines connected to the process acid waste solution storage tanks in the 333 and 334-A Facilities, the waste transfer lines to the waste treatment facilities in the 313 Uranium Recovery/WATS Neutralization Room, the transfer lines to/from the 313 Building to the neutralized acid waste storage tanks in the 311 Tank Farm, the ethylene glycol supply and return lines in the Pipe Trench between the 333 Building and the 313 Building used to heat this portion of the Pipe Trench, the fresh acid (nitric and sulfuric) lines from the 334 Tank Farm to the 333 Building, and the caustic lines from the Tank Farm to the 313 WATS/URO Room. As of 11/1/98, all process and waste piping inside the associated facilities had been disconnected from the Pipe Trench. Only the piping inside the Pipe Trench or outside the facilities (e.g. tank farm piping) remained for pipes associated with the 300 Area Waste Acid Treatment System or the 300 Area U-Bearing Acid Treatment System. The 300 Area Waste Acid Treatment System was closed in phases. It was totally closed on 10/30/2005.	
Location: The WATS transfer lines were located inside the Pipe Trench. Some portions of the transfer lines, located inside the 334-A Facility, the 313 WATS and URO, and the 303-F Building, were removed during the Decontamination and Inspection Plans for Phases I and II of the closure	

plan.

Related Sites/ Structures: The Pipe Trench (300-224), the 333 Building, the 334 Tank Farm, the 334-A Building, the 303-F Building, the 311 Tank Farm, and the Uranium Recovery Operations in the 313 Building.

Process Description: WATS Process Drain: The 333 N-Fuels spent etch acid drain lines in the Pipe Trench to the 334-A Facility (storage tanks) are 10.2 cm. and 7.6 cm. (4 in. and 3 in.) PVC lines.

Upstream WATS Acid Transfer: Batches of WATS waste acid solutions were pumped from the 334-A tanks through 5.1 cm. (2 in.) PVC lines in the Pipe Trench to the 313-TK-2 neutralization tank in the 313 Building.

WATS Neutralized Acid Waste Transfer: After neutralization with caustic, the batch of neutralized acid waste solution was pumped through 5.1 cm. (2 in.) lines in the Pipe Trench to storage tanks in the 311 Tank Farm. In 1995, recycle piping was installed in the Pipe Trench from the 311 Tank Farm waste storage tanks to the 313 Building to allow additional solids removal if required.

URANIUM-BEARING ACID transfer: The U-bearing waste acid solutions were collected in the Interim Storage/Blending Tank 333-TK-24 in the 333 Building and batch transferred via 5.1 cm. (2 in.) stainless steel lines in the Pipe Trench to Storage Tanks 1 and 2 in the 333 West Tank Farm. The stored U-bearing acid was transferred through a 2 in. stainless steel line in the Pipe Trench back into the 333 Building to a valving manifold where it was routed west through stainless steel piping in the Pipe Trench, south and east to the 303-F Building and then on to the acid storage tanks 313-TK-3 and 313-TK-4 in the 313 Uranium Recovery Operation (300 URO).

URANIUM RECOVERY: The U-bearing waste acid solutions were neutralized, filtered, and transferred through pipes in the Pipe Trench to the same waste storage tanks in the 311 Tank Farm as used to store the WATS neutralized acid waste solution.

Closure Info: Interim (1/9/2012): Note that the portions of the WATS trench that were inside the 333 Building and east of the 333 Building are not part RSVP-2011-106 interim closeout document. The portion of the 300-219 and 300-224 waste sites that were in the 618-1 Burial Ground were clean closed as part of the 300 Area WATS Resource Conservation and Recovery Act of 1976 (RCRA) treatment, storage, and disposal unit (TS-3-1). The portions of the 300-219 and 300-224 waste sites addressed in the RSVP-2011-016 document are the portions of the WATS trench from the 313 Building to the 333 Building.

Remediation of the 300-219 and 300-224 waste sites was performed from December 14, 2009, through May 23, 2011. The majority of the soil within the waste sites footprints were excavated to a depth of 0.5 to 1.0 meters (1.6 to 3.3 ft) below ground surface (bgs). The soil under the 300-224 loading area was excavated to a depth of over 1.5 meters (4.9 ft) bgs. Remediation of the 333 WSTF waste site was performed on December 14, 2009. The soil within the waste site footprint was excavated to a depth of 1.0 meter (3.3 ft) bgs, resulting in 40 BCM (52 BCY) of soil was being disposed at the ERDF. The resulting 581 bank cubic meters (BCM) (760 bank cubic yards [BCY]) of soil was disposed at the Environmental Restoration Disposal Facility (ERDF).

Final: The 300-219 waste site consists of the transfer lines inside the 300-224 Waste Acid Treatment System (WATS) trench. The 300-224 WATS trench ran between the 313 Building, 303-F Building, 311 Tank Farm, 333 Building, 334-A Building, and 334 Tank Farm. The 333 WSTF waste site, located on the west side of the former 333 Building, was an above-grade tank farm with a concrete containment basin. Remediation occurred from 2009 through 2011 with a maximum depth of 4.9 feet. The 300-219, 300-224, and 333 WSTF waste sites were remediated

and have been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). Verification sampling results show that the site meets the CULs for direct exposure and groundwater protection and river protection and support an industrial land use scenario. Because the sample results do not meet the CULs for residential land use, the waste sites require institutional controls to maintain industrial land use. In accordance with this evaluation, the verification sampling results support a reclassification of the 300-219, 300-224, and 333 WSTF waste sites to Final Closed Out.

Code:	300-224	Classification:	Accepted
Names:	300-224; WATS and U-Bearing Piping Trench	Reclassification	Final Closed Out (5/12/2014)
Type:	Trench	Start Date:	1/1/1960
Status:	Inactive	End Date:	1/1/1988

Description: This site has been remediated and Interim Closed Out. In 2014, the site was reclassified to Final Closed Out. It was a subsurface, concrete pipe trench with concrete block and metal plate covers. The pipe trench had several sections which allowed piping connections to be made between process operations in the 313 Building, the 303-F Building, the 311 Tank Farm, the 333 Building, the 334-A Building, and the 334 Tank Farm.

The portions of the 300-219 and 300-224 waste sites addressed in the RSVP-2011-016 document are the portions of the WATS trench from the 313 Building to the 333 Building.

The west part of the concrete pipe trench, that connected the 333 Building and the 313 Building, was approximately 188 meters (617 ft) long with internal dimensions of about 45.7 cm by 45.7 cm (18 in by 18 in). This section of the pipe trench had ethylene glycol heating lines used for freeze protection. An access box or valve box with a metal lid connected to the west wall of 333 where the pipe trench emerges from the building. The pipe trench was covered by concrete lids, each measuring 1.21 meters by 0.64 meters (4 ft by 2.1 ft). The concrete covers were numbered, with # 1 being the closest to the west wall of 333. Some of the covers adjacent to 333 and the 333 West Tank Farm were posted "Fixed Contamination Area." The entire length of the pipe trench was posted "Radioactive Material, Internally Contaminated." The pipe trench ran south along the west side of the 333 Bldg. and made a 90 degree turn to the west at the building's southwest corner. It crossed the street and made another 90 degree turn to the south and ran along the east side of the 3712 Building. A metal access lid was found on the east side of 3712, between the covers numbered # 65 and # 66. This allowed access to the pipe trench and the helium lines that ran between 306W and 3712.

Location: The pipe trench runs between the 313 Building, the 303-F Building, the 311 Tank Farm, the 333 Building, the 334-A Building, and the 334 Tank Farm, as shown in the attached scanned schematic diagram.

Related Sites/ Structures: The pipe trench is associated with the 300-258 pipe trench, the 334-A Acid Treatment Facility, 300-64, the 333 U-bearing acid storage area, the 311 Tank Farm, the 303-F building, the 313 Uranium Recovery Operations and Waste Acid Neutralization Operations, and (after about 1977) the process sewer. The site was associated with the 618-1:2 Neutralization Pit.

Process Description: The 333 Building portion of the pipe trench contains chemical process transfer piping for the 300 Area Waste Acid Treatment System including the waste etch acids drains to the 334-A Building (WATS) and the transfer lines from 333-TK-24 to the additional U-bearing waste acid storage tanks in the 333 West Tank Farm. The pipe trench also contains transfer piping for fresh acids and for fresh oil and waste oil (for the 333 co-extrusion press). Until 1977, the concrete pipe trench on the east side of 333 drained into a limestone pit (618-1:2) located over the 618-1 Burial Ground. This end of the pipe trench was sealed in July 1975 and a drain was installed to the process sewer.

The 313 Building portion of the pipe trench contains transfer piping for the 300 Area WATS, for the 313 Uranium Recovery Operation (URO), for fresh caustic for neutralization, for the neutralized acid waste (WATS) stream, and the neutralized U-bearing acid waste (URO) stream between 313 Building and the neutralized waste storage tanks in the 311 Tank Farm.

Waste Type: Chemicals

Waste Description: The pipe trench and subsurface soil have become contaminated due to multiple releases into the trench. Releases included acids, bases, and solvents. Some of released acids contained dissolved uranium. See the "Releases" section for information on the individual releases.

Closure Info: Interim (1/9/2012): Note that the portions of the WATS trench that were inside the 333 Building and east of the 333 Building are not part RSVP-2011-106 interim closeout document. The portion of the 300-219 and 300-224 waste sites that were in the 618-1 Burial Ground were clean closed as part of the 300 Area WATS Resource Conservation and Recovery Act of 1976 (RCRA) treatment, storage, and disposal unit (TS-3-1). The portions of the 300-219 and 300-224 waste sites addressed in the RSVP-2011-016 document are the portions of the WATS trench from the 313 Building to the 333 Building.

Remediation of the 300-219 and 300-224 waste sites was performed from December 14, 2009, through May 23, 2011. The majority of the soil within the waste sites footprints were excavated to a depth of 0.5 to 1.0 meters (1.6 to 3.3 ft) below ground surface (bgs). The soil under the 300-224 loading area was excavated to a depth of over 1.5 meters (4.9 ft) bgs. Remediation of the 333 WSTF waste site was performed on December 14, 2009. The soil within the waste site footprint was excavated to a depth of 1.0 meter (3.3 ft) bgs, resulting in 40 BCM (52 BCY) of soil was being disposed at the ERDF. The resulting 581 bank cubic meters (BCM) (760 bank cubic yards [BCY]) of soil was disposed at the Environmental Restoration Disposal Facility (ERDF).

Final: The 300-219 waste site consists of the transfer lines inside the 300-224 Waste Acid Treatment System (WATS) trench. The 300-224 WATS trench ran between the 313 Building, 303-F Building, 311 Tank Farm, 333 Building, 334-A Building, and 334 Tank Farm. The 333 WSTF waste site, located on the west side of the former 333 Building, was an above-grade tank farm with a concrete containment basin. Remediation occurred from 2009 through 2011 with a maximum depth of 4.9 feet. The 300-219, 300-224, and 333 WSTF waste sites were remediated and have been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). Verification sampling results show that the site meets the CULs for direct exposure and groundwater protection and river protection and support an industrial land use scenario. Because the sample results do not meet the CULs for residential land use, the waste sites require institutional controls to maintain industrial land use. In accordance with this evaluation, the verification sampling results support a reclassification of the 300-219, 300-224, and 333 WSTF waste sites to Final Closed Out.

Code: 300-251	Classification: Accepted
Names: 300-251; Unplanned Release Outside the 303-K Building	Reclassification: Final Closed Out (5/12/2014)
Type: Unplanned Release	Start Date: 1/1/1943
Status: Inactive	End Date:
Description: The site has been remediated and Interim Closed Out. In 2014, the site was reclassified to Final Closed Out. It consisted of uranium contaminated soil around and under the 303-K Building (also known as the 303-K Contaminated Waste Storage). The 303-K building was removed and the TSD was clean closed on July 22, 2002. The soil remediation activity occurred in 2010 and	

	2011.
Location:	The unit is located in the 300 Area, on the north side of Ginko Street between the 313 and 314 Buildings.
Release Description:	Releases may have occurred during decontamination activities within the facility or the storage of materials outside the facility. Individual events were not always documented.
Related Sites/ Structures:	The site is related to WIDS Site 303-K Contaminated Waste Storage (303-K CWS). The 303-K CWS had been a Treatment, Storage and Disposal (TSD) Unit. The TSD was clean closed and the building demolished in July 2002.
Process Description:	The building was constructed of cinder blocks that rested on a concrete slab. The building was constructed in 1943 for storage to support uranium fuel production. In 1953, building modifications and outdoor storage pads (concrete and asphalt) were constructed to support the decontamination of aluminum reactor spacers. From 1953 to 1977, decontamination operations were conducted at this site. From 1977 to 1982, the building was used to cure and test concreted billets of uranium chips and fines from the 303 Concretion facility. Since 1953, radioactive waste has been stored at the facility including the outdoor areas. From 1986 to 1995, low-level radioactive waste and mixed waste was stored within the building and the outdoor area.
Waste Type:	Soil
Waste Description:	The waste is contaminated soil from operations at the 303-K Contaminated Waste Storage Facility.

The following information is provided about operations inside the facility. Since 1943, the building has been used to store various amounts of low-level radioactive wastes. Solids are stored outside, while liquids are contained inside the building. Mixed waste stored after January 1986 included: a. Neutralized solid waste for the unrecoverable uranium stream of the 300 Area Waste Acid Treatment System, b. Uranium contaminated metallic lead, c. Salt and sludge containers from beta and quench metal heat treatment furnaces, d. Uranium contaminated perchloroethylene, chloroform, and ethyl acetate, e. Beryllium/zircaloy-2 alloy chips and fines generated at the stepcut lathe, before and after concreting at the 304 Concretion Facility, f. Spent coolant from counterbore lathes in the 333 Building, g. Waste oil and hydraulic fluids that are known, or strongly suspected, to be contaminated with uranium, h. Salt crystals (copper fluorozirconate) from the bottom of the waste storage tanks in the 334-A Building, i. Acids (HNO₃, HF, and H₂SO₄ mixtures) as a solution and sorbed on opal clay. Analyses of soil samples taken in 1977 for RCRA closure resulted in the conclusion that there are no metals or semivolatile organic constituents of concern present in the soil.

Closure Info: Interim (9/29/2011): Initial remediation of the waste site was performed June 21 to 22, 2010. The waste site was excavated to a depth of 0.5 meters (1.6 ft) below ground surface, resulting in approximately 432 bank cubic meters (BCM) (565 bank cubic yards [BCY]) of soil disposed at the Environmental Restoration Disposal Facility (ERDF). Concrete and asphalt were also found within the excavation and were removed for disposal. All material was direct loaded from the excavation; therefore, no waste staging piles were created. No overburden soil stockpiles are associated with the waste site.

A post-excavation radiological survey for gamma and beta activity was conducted following the completion of remedial action to confirm that waste site excavation was complete. No elevated gamma activity was detected. The radiological field screening survey identified two locations with elevated beta activity, with one judged to be potentially above cleanup levels. This location is on the southeast margin of the excavation. Additional soil from the southeast location (approximately 8 BCM [10.5 BCY]) was removed by hand shoveling and was disposed at ERDF. A focused sample was collected from each of the two locations exhibiting elevated beta activity.

A supplemental remedial action at the 300-251 waste site was done on June 1, 2011. Approximately 42 BCM (55 BCY) of additional soil was removed for disposal to ERDF. The supplemental remedial action was due to a total petroleum hydrocarbons (TPH) result greater than direct exposure RAGs for a verification soil sample (J1DWL3) taken at sample location EXC-9.

Final (5/12/2014): The 300-251, Unplanned Release Outside the 303-K Building waste site, consisted of potentially contaminated soil around and under the former 303-K Contaminated Waste Storage Building. Remedial action was performed in June 2010 and June 2011. The waste site was excavated to a depth of 1.6 feet. The 300-251 waste site was remediated and has been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). Verification sampling results show that the site meets the CUL's for direct exposure and groundwater protection and river protection and support an industrial land use scenario. Contamination at this waste site did not extend into the deep zone soils. Because the remediation of the waste site did not meet residential land use cleanup levels, the waste site requires institutional controls to maintain industrial land use. In accordance with this evaluation, the verification sampling results support a reclassification of the 300-251 waste site to Final Closed Out.

Code:	300-253	Classification:	Accepted
Names:	300-253; 384-W Original Brine Pit; 384-W Original Salt Dissolving Pit and Brine Pump Pit	Reclassification	Final Closed Out (3/10/2014)
Type:	Sump	Start Date:	
Status:	Inactive	End Date:	1/1/1977
Description:	<p>The waste site had been evaluated and determined to require No Action. In 2014, the site was reclassified to Final Closed Out. It was a two-chambered concrete brine pit. No surface features were noted at the structure's location except a patch of asphalt that was darker than the surrounding material.</p> <p>The structure was located partially below grade with the top 83 centimeters (33 inches) visible. It had either a concrete or metal lid (see Site Comment). The larger chamber, was the salt dissolving pit, also identified as the "Salt Storage Pit" on drawing H-3-36240. This section held the salt that was dissolved to make the brine. Typically, the salt dissolving pit was connected to the brine pump pit by a piece of perforated pipe located at the bottom of the structure. The pipe was covered by layers of gravel and sand. The smaller chamber was the brine pump pit, also identified as "brine" on drawing H-3-36240. This chamber held the filtered brine for use in powerhouse operations. The pump pit was connected to the powerhouse by a 5.1 centimeter (2 inch) line and a 2.5 centimeter (1 inch) line.</p>		
Location:	<p>The original 384 brine pit was located approximately 0.6 meters (2 feet) south of the 384 Building's southwest corner. The brine pit's west wall was in line with the west wall of the 384 Building.</p>		
Related Sites/ Structures:	<p>The site is related to the 384 Powerhouse. It was replaced by another brine pit, WIDS Site Code 300-222.</p>		
Process Description:	<p>The steam system used "soft" water. Brine was used to regenerate the ion exchange demineralizers in the water softeners. The brine was created by distributing water across the surface of the salt. As the water passed through the salt, the solution became saturated. The brine solution passed through layers of sand and gravel which filtered out salt crystals and other particles. The filtered brine passed into the pump pit via a pipe that connected the chambers. Flow through the brine pit was achieved by the addition of new water into the salt dissolving pit</p>		

and the removal of brine from the pump pit.

Waste Type: Abandoned Chemicals

Waste Description: Salt cake may be present as part of any demolition debris at the site. Salt cake may be designated as a dangerous waste under the Model Toxics Control Act (MTCA).

Closure Info: Interim: The reclassification status of No Action is documented of form 99-042. Any remaining material will be addressed as part of decommissioning the 384 Powerhouse.

Final: In 2014, the site was reclassified to Final Closed Out on form 2014-012 and requires Institutional Controls.

Code: 300-255

Classification: Accepted

Names: 300-255; 309 Tank Farm Contaminated Soil

Reclassification: Final Closed Out (8/7/2015)

Type: Unplanned Release

Start Date: 1/1/1960

Status: Inactive

End Date: 1/1/1969

Description: The site has been remediated and reclassified to Final Closed Out. It was contaminated soil located inside the 309 Building Tank Farm fenced area. The source of the contamination was probably the piping related to tanks 309-TW-1, 309-TW-2 and 309-TW-3 (aka 309 Tank Farm).

Location: The site was located northeast of the 309 Building and inside the 309 Tank Farm fence. The contaminated soil was located within the 309 building demolition footprint.

Related Sites/Structures: The site was related to operations at the 309 Building (PRTR - Plutonium Recycle Test Facility), 309 Tank #1 (WIDS Site 309-TW-1), 309 Tank #2 (WIDS Site 309-TW-2), 309 Tank #3 (WIDS Site 309-TW-3), an underground concrete covered valve pit, above and below ground transfer pipelines, an ion exchange vessel, and a control panel.

Process Description: The underground tanks were constructed in conjunction with the Plutonium Recycle Test Reactor (PRTR) (a.k.a. 309 Building) in the late 1950's. The tanks are described in WIDS Sites 309-TW-1, 309-TW-2, and 309-TW-3. The 309-TW-3 tank typically collected liquid waste from the storage basin overflow and drain system, the Rupture Loop Annex Cell sump, contaminated floor drains, Loadout Facility drains, exhaust fan pit drain, stack and duct drains, and the exhaust air filter drain. Tank 309-TW-2 was used as a backup for 309-TW-3. Tank 309-TW-1 was used as a process holding tank where liquid from the other two tanks was treated or prepared for pumping liquid waste to the 340 Complex. Sometime after the initial installation of the tanks, an ion exchange column was installed between tanks 309-TW-2 and 309-TW-1. The ion exchange column was used to treat liquid from Tanks 309-TW-2 and 309-TW-3 before sending the liquid to the 340 Complex for disposal (contaminated stream). If the contamination was removed by the ion exchange resin processing, it was sent through the 300 Area Retention Process Sewer to the 307 Retention Basins.

Waste Type: Soil

Waste Description: The waste is contaminated soil. Potential radioactive contaminants of concern are cesium-137, cobalt-60, and americium-241. Potential hazardous contaminants are barium, cadmium, chromium, lead, and selenium. The related contaminated structures, e.g., tanks, valve pit and ancillary piping will need to be removed under a decontamination and decommissioning action prior to soil remediation. The tanks, 309-TW-1, 309-TW-2, and 309-TW-3 are separate sites in WIDS.

Closure Info: Final (8/7/2015): Remedial actions for waste sites 300-22, 300-255 and UPR-300-5 were combined and addressed in CVP-2015-00013.

In January 2014, the 1,082-ton 309 PRTR was removed and transported to ERDF for disposal. The remaining containment structure consisted of 0.3 meters (1 ft) thick concrete surrounded by metal sheeting. It was demolished to 9.8 meters (32 ft) below ground surface (bgs) and disposed at ERDF. The remaining 3.4 meters (11 ft) of the containment structure, from 9.8 to 13 meters (32 to 43 ft) below ground surface, was sampled and left in place.

The 300-22, 300-255, and UPR-300-5 waste sites excavation along with the demolition of the 309 containment structure was performed from March 12, 2014, to February 12, 2015. The excavation resulted in removal of approximately 78,120 bank cubic meters (BCM) (102,177 bank cubic yards [BCY]) of contaminated materials. All material was direct loaded for disposal at ERDF. The 300-22, 300-255, and UPR-300-5 waste sites were excavated to a depth of 11 meters (36 ft) bgs. Excavated materials consisted of concrete, metal tanks, building debris, asphalt, and various types of piping, including carbon steel, stainless steel, clay tile, and concrete tile. No anomalous materials or stained soils were observed during remedial activities. No radiological contamination above background was detected in the shallow zone of the 309 Building excavation. An additional weak-gamma survey was performed to target americium-241 and the associated plutonium. This survey detected radiological contamination above background within the north side of the excavation and 309 PRTR remaining containment structure. Verification samples were collected in the vicinity of the radiological detects above background locations. Sampling results indicated that all cleanup levels were met for the samples in these areas.

Code:	300-256	Classification:	Accepted
Names:	300-256; 306E Fabrication and Testing Laboratory Releases	Reclassification	Final Closed Out (2/18/2014)
Type:	Unplanned Release	Start Date:	1/1/1956
Status:	Inactive	End Date:	
Description:	The site was contaminated soil under and around the 306E Building. The area around the 306E building is paved and was posted as underground radioactive contamination. During remedial activities, the 300-33 and 300-256 combined waste sites were re-defined to include four subsurface pits ranging from 3 to 16 meters (12 to 45 ft) below the concrete slab surface of the 306 Building. The four pits included the tube pit located in Room 172 of the 306E Building, the assembly pit located in the western high bay of the 306E Building, the furnace pit located in the northwestern corner of the 306E Building, and the press pit located in the northeastern corner of the high bay. Because these are nonstandard structures, agreements were reached between the Department of Energy, Richland Operations Office, and the U.S. Environmental Protection Agency to document status and closure requirements for these pit structures in a separate closure report (Refer to 306E/W Below Grade Pits Closure Report, CCN 147876, Washington Closure Hanford, Richland, Washington).		
Location:	The 306E Building was on the north side of Ginko Street, in the northeast corner of the 300 Area.		
Release Description:	Without distinguishing between the 306E and 306W Buildings, Gerber, WHC-MR-0388, states the following. Airborne dust and particulate contamination in and near this facility included uranium and thorium, as well as all of the components of the beryllium-Zircaloy-2 brazing material developed for N Reactor fuel elements. Zircaloy-2 was a blend of zirconium alloyed with small amounts of tin, iron, chromium, and nickel. The N Reactor co-extrusion process also required an exterior jacket of copper-silicon alloy. Poor ventilation was a continual problem throughout at least the first fifteen years of 306 Building history. Additionally, multiple fires and leaks occurred over the years in and around the 306 Building, in barrels and waste "load luggers" containing uranium, thorium, heavy metals, and other fuel component		

scraps. Fires also occurred around and in building equipment, such as centerless grinders, lathes, electric saws, and other machinery. These fires oxidized and volatilized uranium and other wastes; long-lived airborne contamination, which can be recirculated today, settled in building sumps, crevices, and nearby soil. In addition, tools and fabrication work areas within the building often displayed contamination levels of 20,000 to 80,000 counts per minute during the 1950's and 1960's. As recently as 1987, contaminated equipment entered the building from off the Hanford Site, spreading spotty contamination up to 100,000 disintegrations per minute. Gerber continues, again without distinguishing between 306E and 306W. In addition to airborne and machinery contamination, multiple drain and piping leaks (WIDS Site 300-15) and spills have occurred in the 306 Building over the years. These spills have included chemicals, cleansers, solvents, reagents, oils containing polychlorinated biphenyls (PCBs), and other substances used in fuel fabrication processes. From 1956 to 1967 (and once after 1967), a lime tank and valve pit just north of the east end of the 306 Building (WIDS Site 300-41) intercepted and neutralized nitric acid-bearing chemical wastes before discharge to the process sewer. In 1976, this pit was inspected, along with the process waste sump, sewer manholes, and the inlet box to the process sewer leaching trenches, after several hundred gallons of slightly enriched uranyl nitrate hexahydrate solution was spilled into the sump. The investigation found that much uranium and thorium contamination lies in and beneath the 306 Building floor, slab, pipe trenches, and sewer lines. Specifically, two large deposits - 2.4 meters (8 feet) long by 0.6 meters (2 feet) wide by 15 centimeters (6 inches) thick - of uranium-bearing particulate matter were found in the inlet box, but the accumulated radioactivity levels were determined to be nondangerous (3.6 grams of uranium per liter of sludge). No significant accumulation was found in the lime pit and sewer manholes. In 1975, piping that had been installed to transfer fresh nitric acid from the 333 Building to the 306 Building, and to route used acids in the reverse direction, were partially removed. However, several feet of pipe "spurs" nearest the 306 Building remain in place. These and other pipes, along with pipe trenches, sumps, sewers, and drains can be expected to hold hazardous chemical residues as well as the metal residues listed previously. In 1979, a HEDL Radiological Engineering report stated: "All sewer lines (WIDS Site 300-15) leading from this building are suspect. The lime pit...contain[s] uranium and thorium sludge. Surface and near surface contamination around this building is to be expected."

- Related Sites/ Structures:** The site is related to the 306E Building, 333 building, 300 Area process sewer, and 300 Area sanitary sewer. The contaminated soil beneath the 306E Building is WIDS Site 300-256 and the contaminated soil beneath the adjacent 306W Metal Fabrication Development Building is documented as WIDS Site Code 300-33.
- Process Description:** The original 306 Building was completed in 1956 and named the Fuel Element Pilot Plant. The facility was constructed to support the 313 Building operations. It was expanded in 1960 to contain the co-extrusion fabrication processes for N Reactor fuels fabrication. In 1972, the new eastern half was designated as 306E and became the Hanford Engineering Development Laboratory (HEDL) operated by Westinghouse Electric Corporation. The original western portion of the building, was designated as 306W and was allocated to Pacific Northwest Laboratories (PNL).
- Waste Type:** Soil
- Waste Description:** The waste is contaminated soil under and around the 306E Building.
- Closure Info:** Interim: Demolition of the 306E, 306W, and 306E-BA facilities, which were located on top of the soil waste sites, was completed between November 2006 and December 2007. Remediation of the combined 300-33, 300-256, and 300-41 waste sites occurred between July 10 and November 9, 2009. The remediation activities included the removal of the neutralization tank, valve pit, soil, and other debris within the footprint of the 306E/W Building including the partial removal and backfill of the 306E Building assembly pit. All debris and excavation materials have been removed to the Environmental Restoration Disposal Facility.

The 300-33 and 300-256 combined waste sites included four pits ranging from 3 to 16 meters (12 to 45 ft) below the concrete slab surface of the 306 Building. The four pits included the tube pit located in Room 172 of the 306E Building, the assembly pit located in the western high bay of the 306E Building, the furnace pit located in the northwestern corner of the 306E Building, and the press pit located in the northeastern corner of the high bay. Because these are nonstandard structures, agreements were reached between the Department of Energy, Richland Operations Office, and the U.S. Environmental Protection Agency to document status and closure requirements for these pit structures in a separate closure report (Refer to 306E/W Below Grade Pits Closure Report, CCN 147876, Washington Closure Hanford, Richland, Washington).

Final (2/18/2014): This group of sites is listed in the 300-FF-2 Record of Decision as Final Closed Out. Institutional Controls to maintain Industrial Landuse are required.

Code: 300-257	Classification: Accepted
Names: 300-257; 309 Process Sewer to River	Reclassification: Final Closed Out (5/12/2014)
Type: Process Sewer	Start Date:
Status: Inactive	End Date:

Description: The waste site has been evaluated and determined to require No Action. In 2014, the site was reclassified to Final Closed Out. It is the underground process sewer piping that was originally connected to the 309 Building's Rupture Loop Holding Tank. The rupture tank was removed in the late 1970's. The pipeline extended to a 36 inch diameter corrugated pipe that emptied into the Columbia River. All connections to the Radioactive Liquid Waste Sewer (300 RLWS) were severed and plugged. The area where the Rupture Loop Holding Tank was located is now covered with asphalt and is being used as a parking lot. No pipeline is visible on the river bank or the edge of the river.

Location: The waste site was evaluated and reclassified to Final Closed Out in 2014. Structures associated with the 300-257 waste site are the 3906 Lift Station and the 300-257 Overflow Structure. The pipeline began southeast of the location of the 309 Rupture Loop Holding Tank (WIDS Site 300-55) and joins other process sewer lines. It runs due east to a sump (overflow structure) at the top of the river bank.

Related Sites/ Structures: The site was related to the Rupture Loop Holding Tank (WIDS Site 300-55), 3906 lift station, a valve box, the Radioactive Liquid Waste Sewer (WIDS Site 300 RLWS), manhole #3 and contributory piping coming into manhole #3, an overflow structure at the east end of the site, and piping that exits into the Columbia River.

Process Description: Liquid waste from the 309 Building (Plutonium Recycle Test Reactor) was routed to the Rupture Loop Holding Tank for sampling. If it was contaminated it was sent to the 340 Complex through a 7.6 centimeter (3 inch) underground pipeline. If the waste was not contaminated, it was diverted to the Columbia River via a 1 meter (3 foot) diameter pipeline to the outfall.

The holding tank had a set of incoming piping that included a 7.6 centimeter (3 inch) steel process sewer pipeline and a 10.2 centimeter (4 inch) steel vent pipeline. The outgoing piping was more complex, with two outgoing pipelines being interconnected inside a valve box. One 7.6 centimeter (3 inch) steel pipe run started at the pump on the center top of the tank and ran to the valve box. This pipeline was for pump discharge and was the means of lowering the tank level. The second pipe was a 15 centimeter (6 inch) steel overflow pipe that drained to manhole #3. This pipe exited the tank 22.9 centimeters (9 inches) from the top of the tank.

The valve box (pit) was a 1.8 meter by 1.8 meter (6 foot by 6 foot) mostly below grade concrete box with a gravel bottom. The valve box had a manhole and ladder for direct access to the valves. There were also three grade level openings in the top of the valve box for access to the valves with a gate key. It is unknown if the valve box remains in place. The valve box was located approximately 2.1 meters (7 feet) from the Rupture Loop Holding Tank. It may have been removed at the same time as the tank.

There was one 7.6 centimeter (3 inch) incoming pipeline to the valve box and two 7.6 centimeter (3 inch) exit pipelines. Contaminated waste water was diverted at the valve box to the high level waste pipeline that went to the 340 Complex. Uncontaminated water was sent to the process sewer where it teed into the overflow pipeline. At manhole #3, five pipelines converge and flow into a 1 meter (36 inch) 10 gauge corrugated steel pipeline that flowed to the Columbia River. The five pipelines that enter manhole #3 are all process sewer piping with the following sizes and descriptions: (1) a 15.2 (6 inch) steel pipeline from the Rupture Loop Holding Tank overflow line and the valve box, (2) a 30.5 centimeter (12 inch) vitrified clay pipe coming from the 309 Building, (3) a 30.5 centimeter (12 inch) steel line with a 5.1 centimeter (2 inch) condensate drain above the steel pipeline from the 309 Reactor, (4) a 0.76 meter (2.5 foot) steel pipeline from the Condenser Facility (demolished), and (5) a 15.2 centimeter (6 inch) vitrified clay pipe from the 309 Building. According to DOE/EIS-0113, the streams from the 309 Building included cooling water from air conditioning chillers and floor drains from the south basement service area.

The corrugated steel pipe enters a manhole (overflow structure) at the top of the river bank. The structure is 3.8 meters (12.5 feet) deep with the invert to the structure at 1.9 meters (6.2 feet) from the top of the open grate cover. The pipe exits at a depth of 3.8 meters (12.5 feet) on the opposite side of the structure (going towards the river). No pipeline is visible on the river bank or at the edge of the river. DOE/EIS-0113 shows the top view and the profile of this pipeline. The pipeline from the overflow structure (concrete box) is covered by 3.15 meters by 3.15 meters by 0.9 meters (10 feet by 10 feet by 3 feet) deep riprap. Additional riprap has been placed at the terminus of the pipe. At the pipeline terminus there is a minimum of 1.2 meters (4 feet) of riprap cover over the pipeline. This pipeline was identified as discharge No. 014 309 Building Outfall Structure Columbia River Mile 344.5.

According to the Water Utilities group, the corrugated pipe had collapsed (due to deterioration) in some places causing subsidences that were filled with dirt.

Waste Type: Equipment

Waste Description: The waste is a pipeline that carried potentially radioactively contaminated water to the river.

Closure Info: Interim (6/27/2013): Characterization sampling was performed, and the analytical results indicate that the residual concentrations of COPCs at this site meet the RAOs for industrial direct exposure, groundwater protection, and river protection. In accordance with this evaluation, the characterization sampling and modeling results support a reclassification of the 300-257 waste site to Interim No Action. The waste site is evaluated using the human health direct exposure cleanup levels for industrial land use and applicable standards for groundwater and river protection in the shallow zone (i.e., surface to 4.6 meters [15 ft] deep).

Final (5/12/2014): The 300-257, 309 Process Sewer to River waste site consisted of process sewer piping that originally connected to the 309 Building Rupture Loop Holding Tank and extended to the Columbia River bank. Sediment samples were collected at two locations on February 19 and March 7, 2013. The 300-257 waste site has been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). RESRAD modeling predicts that the radionuclide characterization sampling results meet the excess cancer risk and allowable radiation dose and are protective of groundwater and the

Columbia River under an industrial land use scenario. Sample concentrations of nonradionuclides COC's meet the CUL's for direct exposure and groundwater protection and river protection and support an industrial land use scenario. Because the sample results do not meet the CUL's for residential land use, the waste site requires institutional controls to maintain industrial land use. In accordance with this evaluation, the site sampling results support a reclassification of the 300-257 waste site to Final Closed Out.

Code:	300-258	Classification:	Accepted
Names:	300-258; Abandoned Pipe Trench Between 334 Tank Farm and 306E	Reclassification	Final Closed Out (5/12/2014)
Type:	Trench	Start Date:	1/1/1960
Status:	Inactive	End Date:	1/1/1975

Description: The northern portion of this waste site was remediated with the 618-1 Burial Ground in 2010. The southern portion was sampled and determined that no remediation was required in the southern portion. In 2014, the waste site was reclassified to Final Closed Out. The site was an abandoned subsurface concrete pipe trench. The top of the pipe trench was level with the ground surface and covered with metal plates that measure approximately 0.9 meters by 0.3 meters (3 feet by 1 foot). The metal plates were posted "Radioactive Material, Internally Contaminated." Between the 306E Building and the fence south of the 333 Building, the trench is surrounded by asphalt. The metal cover plates and concrete walls are constructed to allow vehicle traffic on the north side of the 306E Building to drive over the pipe trench. Between the 333 Building fence and the 334 Tank Farm, the trench is primarily surrounded by gravel. The pipe trench is covered by solid plate over most of its length. However, approximately 10 meters (32.8 feet) at the north end have metal plates with approximately 5 centimeter (2 inch) holes. Pipes are visible through these holes.

Location: The pipe trench ran northwest from the north wall of the 306E Building to the southwest corner of the 334 Tank Farm where it joined the south end of the 300-224 pipe trench.

Related Sites/ Structures: The site is associated with the 306E Building chemical processing facilities, the 334 Tank Farm, and the 300-224 pipe trench.

Process Description: The pipe trench was used to house acid transfer piping from the 334 Tank Farm to the 306E Building chemical processing bay in the northeast corner of this facility. From about 1972 to 1975, waste etch solution may have been transferred from the 306E Building chemical bay to the 333/334 Waste Acid Treatment System.

Closure Info: Interim (10/17/2011): The northern portion of the 300-258 waste site that was addressed in the 618-1 Burial Ground excavation is interim closed out within this document based on the results presented in the Cleanup Verification Package for the 618-1 Burial Ground. The 618-1 Burial Ground excavation occurred from September 17, 2008, to September 10, 2009. Two focused, in-process samples were collected from the southern portion of the pipe trench. After sampling, the southern portion of the pipe trench of soil and debris were removed (August 6, 2009) and sent to the Environmental Restoration Disposal Facility (ERDF).

Final (5/12/2014): The 300-258, Abandoned Pipe Trench between 334 Tank Farm and 306E waste site was a concrete pipe trench between the 306E Development Fabrication Test Laboratory and the 334 Tank Farm facilities where it joined the 300-224 pipe trench. The northern portion of the 300-258 waste site was removed with the 618-1 Burial Ground remediation, which occurred from September 17, 2008, to September 10, 2009 (WCH 2010). The southern portion of the pipe trench was removed on August 6, 2009. Verification sampling of the southern portion of the 300-258 waste site was conducted on June 9, 2011. The 300-258 waste site was remediated and has been evaluated in accordance with the 300 Area Final Action

ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). Verification sampling results of the 300-258 waste site shows that the site meets the CUL's for direct exposure and groundwater protection and river protection and support a residential land use scenario. Institutional controls to prevent uncontrolled drilling or excavation into the deep zone are not required. In accordance with this evaluation, the verification sampling results support a reclassification of the 300-258 waste site to Final Closed Out.

Code: 300-259 **Classification:** Accepted
Names: 300-259; Contamination Area Surrounding 618-1 Burial Ground **Reclassification:** Final Closed Out (2/20/2014)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The Contamination Area (CA) was posted with light posts and plastic chain that encompasses the 618-1 Burial Ground. The concrete markers for the burial ground (WIDS Site 618-1) were inside the Contamination Area chain. The Contamination Area and Burial Ground were both covered with gravel. A concrete pipe trench (WIDS Site 300-258) and a concrete storage pad (WIDS Site 333 LHWSA) were also located inside the Contamination Area.

Location: The Contamination Area (CA) is located in the northeast corner of the 300 Area, north and east of the 618-1 Burial Ground.

Related Sites/ Structures: The site is related to the 618-1 burial ground and 300-258.

Waste Type: Misc. Trash and Debris

Waste Description:

Closure Info: Interim (5/11/2012): Remediation of the 300-259 waste site was performed from March 18 through May 18, 2009. Approximately 6,600 metric tons (7,300 U.S. short tons) of debris and soil were removed. The soil within the waste site footprint was excavated to a depth of 1 m (3 ft) below ground surface (bgs), and the resulting 3,000 bank cubic meters (4,000 bank cubic yards) of soil was disposed at ERDF. Observations during excavation supported the findings of the geophysical survey that indicated the 300-259 waste site contamination was limited to the surface, as the soil below the gravel added in 1991 appeared undisturbed

In accordance with the Remaining Sites Verification Package, RSVP-2009-059, the verification sampling results supports a reclassification of the 300-259 waste site to Interim Closed Out. The current site conditions have achieved the remedial action objectives (RAOs) and the corresponding remedial action goals (RAGs) as established in the Remedial Design Report/Remedial Action Work Plan for the 300 Area (RDR/RAWP) (DOE-RL-2001-47, Rev. 3) and in the 300-FF-2 Interim Action ROD.

Remedial actions were performed to support future industrial land use and to protect groundwater and the Columbia River. Further, the residual contaminant concentrations achieved do not preclude any future uses (as bounded by the rural-residential scenario) and allow for unrestricted use of shallow zone soils (i.e., surface to 4.6 m [15 ft] deep).

Final (2/20/2014): This group of sites is considered Final Closed Out in the 300-FF-2 Record of Decision and meets the criteria for unrestricted landuse.

Code: 300-260 **Classification:** Accepted
Names: 300-260; Contaminated Soil West of 313 Building **Reclassification:** Final No Action (3/18/2014)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The site has been evaluated and determined to require No Action. It was reclassified to Final No Action 2014. It consisted of an area of formerly contaminated soil west of the former 313 Building. The site is no longer radiologically posted. Before reclassification it was surrounded by light posts and a yellow rope, no signs of any kind were present. A small amount of equipment and large wooden boxes were stored inside the roped area.

Location: The site was located inside the 300 Area, north of Ginko Street, north of 303-K and west of the 313 Building.

Closure Info: Interim: The reclassification is based on samples collected during the excavation of a concrete pad that was located on top of the 300-260 contaminated soil. The excavation removed a concrete pad for an electrical vault along with incidental soil. Samples taken were collected from eight test trenches on June 2 and June 3, 2010. Approximately 1,278 metric tons (1,672 U.S. tons) of material was excavated and disposed of at the Environmental Restoration Disposal Facility.

Final (3/18/2014): This site is listed in the 300-FF-2 Record of Decision and meets the criteria for unrestricted landuse.

Code: 300-262 **Classification:** Accepted
Names: 300-262; Contaminated Soil West of South Process Pond **Reclassification:** Final Closed Out (3/10/2014)
Type: Unplanned Release **Start Date:** 1/1/1943
Status: Inactive **End Date:** 1/1/1975

Description: In 2003, the site was remediated and reclassified to Closed Out. In 2014, the status was changed to Final Closed Out.

Location: The site is located west of the 316-1, South Process Pond, west of the railroad tracks, and approximately 61 meters east of 3713 Building.

Release Description: The contaminated soil was discovered on July 19, 1994 during excavation work to install a new utility pipeline. Excavated soils were contained in accordance with applicable established procedures. The contamination appears to have existed prior to the construction of the railroad spur that runs next to the 316-1, South Process Pond.

Related Sites/Structures: This site was associated with the South Pond (316-1); the Retired Filter Backwash Pond (300 RFBP) and unplanned release (UPR) sites UPR 300-32, UPR-300-33, UPR-300-34, UPR-300-35, UPR-300-36, UPR-300-37, and UPR-300-FF-1.

Waste Type: Soil

Waste Description: The waste is radioactively contaminated soil. The survey report indicates readings up to 15,000 disintegrations per minute (dpm) Beta/Gamma. The contamination is suspected to be scrapings from the 316-1, South Process Pond. Potential contaminants of concern may be the same as those for 316-1, including uranium-238 and cobalt-60. Other contaminants may be copper, chromium, ammonia, and polychlorinated biphenyls (PCBs).

Closure Info: Interim (7/23/2003): Remediation activities at the 316-1 South Process Pond site began in 1997

with excavating trenches around the periphery of the 316-1 site. Trenching was performed to assess the lateral extent of contamination. The majority of remedial excavation and disposal activities were conducted in 1999 and 2000. Excavation at the site involved removing the overburden (scraped surface) soils and contaminated soils. The contaminated soil was transported to the ERDF for disposal. Based on field screening, overburden materials and comingled soil identified as potentially clean were placed in stockpiles for potential use as backfill. Soil samples were collected adjacent to utility poles located in the 316-1 site. Where these samples indicated contaminant concentrations above the cleanup criteria, the soil was removed and the area immediately backfilled and compacted with clean material to maintain the integrity of the utility pole. Excavation and disposal of the 316-1 South Process Pond remediation waste was completed in June 2000. The filter backwash pond (WIDS site 300 RFBP) was a lobe on east side of the process pond. During remediation, soil was primarily removed from the area on the west side of the process pond, near the pond inlet. The two north-south parallel soil berms inside the pond were removed. Areas to the south and west of the original pond boundaries were also removed during remediation. The general elevation at the bottom of the excavation used for analysis was 111.3 meters (365 ft) upon completion. The excavation depth was approximately 5.7 meters (19 ft).

Final (3/10/2014): The site is listed in the 300-FF-2 Record of Decision. Institutional Controls to maintain industrial land use are required.

Code:	300-263	Classification:	Accepted
Names:	300-263; 324 Building Diversion Tank	Reclassification	Final Closed Out (9/17/2015)
Type:	Catch Tank	Start Date:	1/1/1969
Status:	Inactive	End Date:	1/1/1969
Description:	The waste site was remediated and reclassified to Final Closed Out. It was an underground, 77,071 liter (20,360 gallon), cylindrical tank. It was approximately 36 feet long and 10 feet deep. The top of the tank was approximately 60 inches below ground surface. The tank was excavated in the fall of 2014.		
Location:	The tank was located in the 300 Area, east of the former 3718G Building. It was inside the boundary of the 316-3 trenches.		
Related Sites/ Structures:	The tank was associated with the 324 Building and the 316-3 trenches. There were three supporting caissons (valving, pump and ion exchange).		
Process Description:	The site is an inactive catch tank. The tank was originally installed to hold contaminated process solutions that were too contaminated to be released directly to the crib/trenches (316-3) without additional treatment.		
	<p>Shortly after the tank was installed, the 340 Complex came on line. At that time, the piping system to the 324 diversion tank was bypassed and capped. The 324 Building then transferred its waste to the 340 Complex. The tank was kept in reserve as a diversion tank in the event of a radioactive release from the facility (324 Building), although it is believed it never received any 324 building waste. Drawing H-3-28455 shows the isolation of the system and was visually verified at the caissons.</p> <p>In January 1999, the tank contents was sampled. Some bolts were missing from the flange cover. Approximately 6 inches of water was in the bottom of the tank. No radiological contamination was identified.</p>		
Waste Type:	Equipment		

Waste Description: The waste is an inactive tank. Hazardous or radioactive waste was never transferred from the 324 Building to the tank. The tank is isolated and the pipelines are capped. Sample results, Sample Id S8171-01, indicated cesium-137 to be 509 picocuries per liter (13.9% counting error). Gross Beta was 1,700 picocuries per liter (10% method error). At the time the site was sampled, there was 15.2 centimeters (6 inches) of rainwater. The water is believed to have come from intrusion because many of the flange bolts were missing. The site is located in a low area where pooling of water can occur. The contamination is believed to be from surface contamination. This site lies in the middle of WIDS Site 316-3, 307 Disposal Trenches.

Closure Info: Final (9/15/2015): The 300-263 tank and the 316-3 trenches were reclassified to Final Closed out in the CVP-2015-00015 document. The 300-263 tank was located within the boundaries of the 316-3 trenches waste site.

Subsurface investigation sampling for the 316-3 waste site was conducted between August 13 and September 11, 2012. Samples were collected from seven test pits. The results for test pit sampling indicated that the 316-3 waste site achieved compliance with the remedial action objectives and remedial action goals for industrial land use. The site was reclassified as No Action on January 17, 2013.

During excavation of the 300-263 tank, in fall 2014, isolated locations of discolored soil were observed that were emitting elevated levels of radiation based on hand-held instrument readings. This contamination, determined to be uranium, was attributed to the 316-3 trench waste site. Consequently, the No Action reclassification status for the 316-3 site was rendered void, and remediation of the site was required.

Remediation of the 300-263 waste site began on September 24, 2014. During remediation of the 300-263 waste site and adjacent Radioactive Liquid Waste Sewer pipeline, stained soil and elevated radiological readings were observed on the west sidewall inside the 300-263 waste site excavation. In-process radiological sample data indicated that elevated uranium concentrations were associated with the stained soil. Based on the process knowledge, uranium contamination was attributed to the co-located 316-3 waste site.

Remediation of the 316-3 waste site was performed from December 17, 2014, to April 30, 2015. Six rounds of in-process sampling, routine radiological screening, and field observations were used to guide waste site remediation. Approximately 1,814 bank cubic meters (BCM) (2,372 bank cubic yards [BCY]) of excavated materials were removed from the 300-263 waste site and direct loaded for disposal at the ERDF. Approximately 68,020 BCM (88,967 BCY) of excavated materials were removed from the 316-3 waste site. The maximum depth of the 300-263 and 316-3 waste sites excavation was approximately 11.3 meters (37 ft) bgs on the west end, and approximately 9.8 meters (32 ft) bgs at the center and east end of the excavation. Excavated materials consisted of radiologically contaminated soil, gravel, coal ash, and limited debris associated with deactivated underground utilities.

No overburden materials were salvaged from the 300-263 and 316-3 waste sites excavation; therefore, there is no overburden pile associated with the 300-263 and 316-3 waste sites. All excavated soils were direct loaded. Therefore, no staging pile areas were utilized.

Code: 300-265	Classification: Accepted
Names: 300-265; Pipe Trench Between 324 and 325 Buildings	Reclassification: None
Type: Radioactive Process Sewer	Start Date: 1/1/1971
Status: Inactive	End Date:

Description: The site is a 5 centimeter (2 inch), underground encased stainless-steel waste transfer line encased within a 10 centimeter (4-inch) fiberglass-reinforced epoxy pipe. The pipeline has a downward slope of about 0.5% from the 325 Building to the 324 Building. Inside the pipeline are two other stainless-steel Schedule 40 pipes, one is 3/8 inch and the other is 3/4 inch. The inner pipes were driven through the 5 centimeter (2 inch) pipe several years after the larger pipe was installed.

The route of the pipeline is marked at the ground surface and is totally within the exclusion area to prevent accidental excavation. The depth of the pipeline ranges from 1 to 4 meters (3 to 12 feet) underground. The encasement surrounding the two smaller pipelines was used both for secondary containment and as a route for transfer of the process off-gas for discharge through the 324 Building stack. Before venting through the stack, it flowed into B Cell and was treated with the B Cell ventilation exhaust.

Location: The transfer line runs in an east-west direction, north of the 324, 308 and 325-A buildings, inside the 300 Area.

Related Sites/ Structures: This pipeline connects the 324 and 325 Buildings.

Process Description: This stainless steel transfer system allowed liquefied High Level Waste (HLW) to be pumped back and forth from the 324 and 325 Buildings for vitrification experiments for spent nuclear fuel waste.

Waste Type: Process Effluent

Waste Description: The transfer line carried liquid High Level Waste from spent nuclear fuel processing.

Code: 300-268

Classification: Accepted

Names: 300-268; 3741 Building Foundation; Box Storage Building Foundation; Special Machine Shop

Reclassification: Final Closed Out (5/12/2014)

Type: Foundation

Start Date: 1/1/1944

Status: Inactive

End Date: 1/1/1956

Description: The waste site has been remediated and Interim Closed Out with the 300-6 waste site remediation. In 2014, the site was reclassified to Final No Action. The building has been removed. The building foundation was covered with gravel. There were no visual signs or markers to indicate where the building footprint had been located. The site cannot be precisely located without geophysical scans or excavation. The entire 300 Area is a posted Underground Radioactive Material area. There is no separate radiological posting for this site.

Location: The 3741 Building was east of where the 384 Power Plant and south of the 303-J buildings had been located. The mapped location was adjusted in 2009, based on drawing research.

Process Description: The building was used to store and prepare samples of irradiated graphite, flux wires, and uranium from the 305 Test Pile, in cardboard boxes. The word "box" in the name Box Storage Building was derived from these boxes. The building was also used as a Special Machine Shop. It contained lathes, drills, saws and other machinery for cutting and preparing metal samples for analysis.

Waste Type: Demolition and Inert Waste

Waste Description: The contamination related to this building were a result of passive dust from machining irradiated uranium, graphite, and other metallic samples from the 305 Test Pile. The contamination, if remaining, would be associated with any remaining concrete foundation.

Closure Info: Interim (1/9/2012): The 300-6 waste site (fuel oil bunkers) was expected to be excavated to groundwater, a depth of approximately 15.8 meters (52 ft) below ground surface (bgs), as necessary to remediate contaminated soil. Remediation of the waste site was performed from August 2 to December 8, 2010. The western portion of the 300-6 waste site excavation did reach the groundwater, and a pool of water remains in the floor of the excavation. The excavation was approximately 15 meters (49.5 ft) deep in the 300-6 west borehole location (when measured to the surface of the pool of water) and approximately 11.5 meters (37.7 ft) deep in the 300-6 east borehole location. The 300-6 and associated waste sites' excavation resulted in approximately 34,770 bank cubic meters (45,477 bank cubic yards) of material removed for disposal at the Environmental Restoration Disposal Facility (ERDF).

Debris (piping and concrete) and soil from the remediation of the 300-6 and associated waste sites were direct loaded to ERDF. No overburden soil stockpiles were associated with the waste sites as a result of remediation, and no anomalies were noted.

The 300-123 UIC was identified as a WIDS waste site. The french drain was removed as part of the layback to remove the contaminated soil at the 300-6 waste site. The french drain consisted of soil and rock that extended to approximately 1.4 meters (4.5 ft) bgs. The existing floor of the 300-6 waste site excavation is approximately 11.3 m (37 ft) bgs.

The 300-65, 300-66, 300-122, and 300-124 UICs were located within the footprint of the 300-6 excavation layback and also removed during the 300-6 excavation. The 3715, 303E and 303J building slabs were removed during the 300-6 waste site excavation because they were located in the excavation layback as well.

The 300-268 site was located within the 300-6 layback area. It was excavated to a depth of 3.0 meters (9.8 ft).

During excavation of the 300-6 waste site, it was verified that the eastern half of the 300-273 waste site pipeline had been previously removed. In addition, as the project conducted test pits along the western half of the 300-273 waste site pipeline right-of-way on November 3, 2010, no pipeline structure was encountered at the elevations presented in the as-built drawings for the pipeline (USAEC 1974). Also in November 2010, the project excavated two test pits along the former 384 Powerhouse foundation within the UPR-300-42 waste site. No below-grade structure was noted, and no visible soil staining was observed, as was expected since the site was reportedly removed in 2009.

During excavation of the 300-6 waste site, it was verified that the eastern half of the 300-273 waste site pipeline had been previously removed. In addition, as the project conducted test pits along the western half of the 300-273 waste site pipeline right-of-way on November 3, 2010, no pipeline structure was encountered at the elevations presented in the as-built drawings for the pipeline. Also in November 2010, the project excavated two test pits along the former 384 Powerhouse foundation within the UPR-300-42 waste site. No below-grade structure was noted, and no visible soil staining was observed, as was expected since the site was reportedly removed in 2009 with the demolition of the 384 powerhouse structure.

Final: The 300 Area Fuel Oil bunkers and associated waste sites were remediated in 2010. The excavation extended to groundwater at a depth of 52 feet. The 300-6, 300-123, 300-268, 300-273, and UPR-300-42 waste sites were remediated and have been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). Verification sampling results show that the site meets the CUL's for direct exposure and groundwater protection and river protection and support a residential land use scenario. Contamination that extended into the deep zone (greater than 4.6 meters [15 ft] bgs) has been removed; therefore, institutional controls to prevent uncontrolled drilling or excavation into the deep zone are not required. In accordance with this evaluation, the verification sampling results

support a reclassification of the 300-6, 300-123, 300-268, 300-273, and UPR-300-42 waste sites to Final Closed Out.

Code: 300-269 **Classification:** Accepted

Names: 300-269; 331-A Virology Laboratory Foundation **Reclassification** None

Type: Foundation **Start Date:** 1/1/1972

Status: Active **End Date:** 1/1/1995

Description: The site is a rectangular concrete building foundation. New air conditioner units are installed on the concrete foundation to support the adjacent 331 facility.

Location: The 331-A foundation is located adjacent to the northwest side of the existing 331 Building.

Related Sites/ Structures: The 331-A Building was part of the original 331 Building complex.

Process Description: The 331-A Building was a roughly T-shaped, one-story, concrete-block building with a sloped wood frame roof. The building was originally used for biological research to investigate radiation effects of animals. The purpose of the research was to investigate radiation damage to tissue from plutonium and fission products. Animals that were contaminated were held in other areas of the 331 complex until their feces showed no significant contamination. In the early 1980s, the facility was converted to a virology laboratory to study bacterial and viral growth in animals. Virology research continued until 1995.

Waste Type: Equipment

Waste Description: Residual contamination may be on the pad from past releases at the building.

Code: 300-270 **Classification:** Accepted

Names: 300-270; Unplanned Release at 313 Building **Reclassification** Final Closed Out (5/12/2014)

Type: Unplanned Release **Start Date:** 1/1/2000

Status: Inactive **End Date:** 1/1/2000

Description: The Unplanned Release site has been remediated and Interim Closed Out. In 2014, the site was reclassified to Final Closed Out. The 300-270 waste site was an unplanned release of a milky-white flow of water that came out of a pipe located below the loading dock on the east side of the 313 Building. The pipe drained storm water from the roof of the 313 Building. The release was on the surface of the ground in an area of compacted gravel and soil.

Location: The release occurred on the east side of the 313 Building.

Related Sites/ Structures: The release of whitish stormwater came from a pipe under the loading dock on the east side of the 313 Building. The pipe drains the roof of the 313 Building, according to the e-mail summarizing the sampling activities.

Process Description: The source of the stormwater was the roof of the 313 Building, but the reason for the discoloration was not determined. The liquid tested and found to be nonradioactive and nondangerous. The matter was not pursued further.

Waste Type: Soil

Waste Description: The stormwater is nondangerous and nonradioactive. Soil collected from the area near the pipe showed elevated levels of lead. The contaminated soil was not caused by the milky-white

liquid. The source of the lead contamination is unknown.

Closure Info: Interim (4/30/2012): The UPR-300-38 waste site consisted of contaminated soil beneath the 313 Building, as well as the foundation. The contamination resulted from multiple unplanned release events. The 313 ESSP (East Side Storage Pad) waste site was the footprint of a large concrete pad adjacent to the southeastern side of the former 313 Building, with an asphalt ramp that connected the pad to Ginko Street. The 300- 270 waste site was the area of a release of whitish storm water that came from a pipe under the loading dock on the east side of the former 313 Building. The pipe drained the roof of the former 313 Building.

Remediation of the UPR-300-38 waste site was performed from January 10, 2010, through June 2, 2011. The soil within the northern portion of the waste site footprint was excavated to an approximate average depth of 1 meter (3.3 ft) below ground surface (bgs). The southern area of the waste site was excavated to an approximate average depth of 2 meters (6.6 ft) bgs, with limited areas of deeper soil contamination to 5 meters (16.4 ft) bgs. The resulting 15,204 bank cubic meters (BCM) (19,887 bank cubic yards [BCY]) of soil was disposed at the Environmental Restoration Disposal Facility (ERDF).

Remediation of a large portion of the 313 ESSP waste site was performed by the excavation of concrete, asphalt, and underlying soil during the remediation of the UPR-300-38 waste site and the adjacent area near the footprint of the former 303-F Building. This work was performed on July 8, 2011. The soil within the waste site footprint was excavated to a depth of 1 meter (3.3 ft) bgs, and the resulting 153 BCM (205 BCY) of soil was disposed at ERDF. Approximately 98 BCM (128 BCY) was associated with the UPR-300-38 excavation; the remainder (55 BCM [72 BCY]) was associated with the 313 ESSP excavation near the footprint of the former 303- F Building. An additional 38 BCM (50 BCY) was removed from the northeast corner and the southern edge of the 313 ESSP waste site on August 26, 2011, resulting in a total of 191 BCM of debris and soil removed from the 313 ESSP waste site.

Remediation of the 300- 270 waste site was performed May 23, 2011. The soil within the waste site footprint was excavated to a depth of 0.5 meter (1.6 ft) bgs, and the resulting 40 BCM (52 BCY) of soil was disposed at ERDF.

A total of 15,435 bank cubic meters (20,194 bank cubic yards) of soil and debris from the remediation of all three waste sites was disposed at the Environmental Restoration Disposal Facility.

Final: The UPR-300-38, Soil Contamination Beneath the 313 Building; 313 ESSP, 313 East Side Storage Pad; and 300-270, Unplanned Release at 313 Building waste sites were either within or immediately adjacent to the footprint of the demolished 313 Building. The UPR-300-38 waste site consisted of contaminated soil beneath the 313 Building, as well as the foundation. The contamination resulted from multiple unplanned release events. The 313 ESSP waste site was the footprint of a large concrete pad adjacent to the southeastern side of the former 313 Building, with an asphalt ramp that connected the pad to Ginko Street. The 300-270 waste site was the area of a release of whitish storm water that came from a pipe under the loading dock on the east side of the former 313 Building. The pipe drained the roof of the former 313 Building. Remediation of the UPR-300-38 waste site was performed from January 2010 through June 2011. Remediation of a large portion of the 313 ESSP waste site occurred July 8 and August 26, 2011 and included excavation of concrete, asphalt, and underlying soil. Remediation of the 300-270 waste site was performed May 23, 2011. The maximum depth of the remediation at the UPR-300-38 waste site was 5 meters (16.4 ft) below ground surface. The 313 ESSP and 300-270 waste sites were remediated to 1 meters (3.3 ft) bgs.

The 300-270, 313 ESSP, and UPR-300-38 waste sites were remediated and have been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area

RDR/RAWP (DOE-RL 2014). Site-specific RESRAD modeling predicts that the radionuclide verification focused sampling results meet the excess cancer risk and allowable radiation dose and are protective of groundwater and the Columbia River under an industrial land use scenario. The remaining verification sampling results show that the site meets the CUL's for direct exposure and groundwater protection and river protection and support an industrial land use scenario. Contamination at these waste sites did not extend into the deep zone soils. Because the remediation of the waste sites did not meet residential land use cleanup levels, the waste sites require institutional controls to maintain industrial land use. In accordance with this evaluation, the verification sampling results support a reclassification of the 300-270, 313 ESSP, and UPR-300-38 waste sites to Final Closed Out.

Code:	300-273	Classification:	Accepted
Names:	300-273; 366 Bunker Pipeline; Fuel Oil Transfer Pipeline	Reclassification	Final Closed Out (5/12/2014)
Type:	Product Piping	Start Date:	1/1/1964
Status:	Inactive	End Date:	1/1/1998
Description:	The waste site has been remediated and Interim Closed Out with the 300-6 waste site remediation. In 2014, the site was reclassified to Final No Action. The site was an encased underground pipeline. The encased pipeline contained two 7.6 centimeter (3 inch diameter) stainless steel lines. It was not visually marked on the surface.		
Location:	The pipeline was located northeast of the 384 Powerhouse, between the 366 Bunker site and the day tanks.		
Related Sites/Structures:	The encased pipeline contains two 7.6 centimeter (3 inch diameter) stainless steel lines. It is associated with WIDS sites 300-6 and 300-223.		
Process Description:	The underground pipeline transferred fuel oil from the 366 Fuel Oil Bunkers (300-6) to the underground Fuel Oil Day Tanks (300-223) to run the 384 Powerhouse. The system operated between 1964 and 1998.		
Closure Info:	Interim (1/9/2012): The 300-6 waste site (fuel oil bunkers) was expected to be excavated to groundwater, a depth of approximately 15.8 meters (52 ft) below ground surface (bgs), as necessary to remediate contaminated soil. Remediation of the waste site was performed from August 2 to December 8, 2010. The western portion of the 300-6 waste site excavation did reach the groundwater, and a pool of water remains in the floor of the excavation. The excavation was approximately 15 meters (49.5 ft) deep in the 300-6 west borehole location (when measured to the surface of the pool of water) and approximately 11.5 meters (37.7 ft) deep in the 300-6 east borehole location. The 300-6 and associated waste sites' excavation resulted in approximately 34,770 bank cubic meters (45,477 bank cubic yards) of material removed for disposal at the Environmental Restoration Disposal Facility (ERDF).		

Debris (piping and concrete) and soil from the remediation of the 300-6 and associated waste sites were direct loaded to ERDF. No overburden soil stockpiles were associated with the waste sites as a result of remediation, and no anomalies were noted.

The 300-123 UIC was identified as a WIDS waste site. The french drain was removed as part of the layback to remove the contaminated soil at the 300-6 waste site. The french drain consisted of soil and rock that extended to approximately 1.4 meters (4.5 ft) bgs. The existing floor of the 300-6 waste site excavation is approximately 11.3 m (37 ft) bgs.

The 300-65, 300-66, 300-122, and 300-124 UICs were located within the footprint of the 300-6 excavation layback and also removed during the 300-6 excavation. The 3715, 303E and 303J

building slabs were removed during the 300-6 waste site excavation because they were located in the excavation layback as well.

The 300-268 site was located within the 300-6 layback area. It was excavated to a depth of 3.0 meters (9.8 ft).

During excavation of the 300-6 waste site, it was verified that the eastern half of the 300-273 waste site pipeline had been previously removed. In addition, as the project conducted test pits along the western half of the 300-273 waste site pipeline right-of-way on November 3, 2010, no pipeline structure was encountered at the elevations presented in the as-built drawings for the pipeline (USAEC 1974). Also in November 2010, the project excavated two test pits along the former 384 Powerhouse foundation within the UPR-300-42 waste site. No below-grade structure was noted, and no visible soil staining was observed, as was expected since the site was reportedly removed in 2009.

During excavation of the 300-6 waste site, it was verified that the eastern half of the 300-273 waste site pipeline had been previously removed. In addition, as the project conducted test pits along the western half of the 300-273 waste site pipeline right-of-way on November 3, 2010, no pipeline structure was encountered at the elevations presented in the as-built drawings for the pipeline. Also in November 2010, the project excavated two test pits along the former 384 Powerhouse foundation within the UPR-300-42 waste site. No below-grade structure was noted, and no visible soil staining was observed, as was expected since the site was reportedly removed in 2009 with the demolition of the 384 powerhouse structure.

Final: The 300 Area Fuel Oil bunkers and associated waste sites were remediated in 2010. The excavation extended to groundwater at a depth of 52 feet. The 300-6, 300-123, 300-268, 300-273, and UPR-300-42 waste sites were remediated and have been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). Verification sampling results show that the site meets the CUL's for direct exposure and groundwater protection and river protection and support a residential land use scenario. Contamination that extended into the deep zone (greater than 4.6 meters [15 ft] bgs) has been removed; therefore, institutional controls to prevent uncontrolled drilling or excavation into the deep zone are not required. In accordance with this evaluation, the verification sampling results support a reclassification of the 300-6, 300-123, 300-268, 300-273, and UPR-300-42 waste sites to Final Closed Out.

Code: 300-274	Classification: Accepted
Names: 300-274; Surface Debris	Reclassification: Final Closed Out (5/12/2014)
Type: Dumping Area	Start Date:
Status: Inactive	End Date:
Description: The waste site has been remediated and Interim Closed Out. In 2014, the site was reclassified to Final Closed Out. A field walkdown of the 300-FF-1 Operable Unit was done in July and December of 2004 to identify remaining debris, hazards and potential new waste sites. Miscellaneous surface debris found consisted mostly of transite, wood, asphalt, metal and broken glass. For remediation purposes, the site was evaluated as three areas. Area 1 was the Miscellaneous Debris Area. Area 2 was the Glass Bottle Location and Area 3 was the PCB Stained Soil Area.	
Location: The 300-FF-1 Operable Unit boundary extends north of the northeast corner of 300 Area to south of the Treated Effluent Disposal Facility (TEDF). It is bounded on the east by the Columbia River. The western edge is irregularly shaped. The majority of the debris was located in the southern portion of the 300-FF-1 Operable Unit, south of the filter backwash ponds.	

The 300-274 - Area 1 Surface Debris locations were found along the western and southern boundary of the 300-FF-1 Operable Unit (OU). They extended from near the Filter Backwash pond in the southeast corner of the OU northwest to in the vicinity of the northern border of the 300-FF-1 OU. The majority of the debris was located in the southern portion of the 300-FF-1 OU, south of the 300 Area Filter Backwash Pond.

The 300-274 - Area 2 Glass Bottle location was identified at Washington State Plane coordinates N117054 E593840.

The 300-274 - Area 3 Soil Staining was identified northwest of the 618-4 Burial Ground, north of the 300-289 waste site and southeast of the 300 Area Treated Effluent Disposal Facility.

Process Description: Various forms and sizes of potentially hazardous or dangerous surface debris waste was created during 300 Area construction and operation and during decommissioning and remedial action activities.

Waste Type: Asbestos (non-friable)

Waste Description: Transit pipe, treated wood, insulation and various forms of transit were identified during the Operable Unit walkdown. The debris was determine to be Potential Asbestos Containing Material (PACM).

Closure Info: Interim (5/8/2013): For remediation purposes, the site was evaluated as three areas. Area 1 was the Miscellaneous Debris Area. Area 2 was the Glass Bottle Location and Area 3 was the PCB Stained Soil Area.

Area 1 Surface Debris consisted of noncontiguous debris areas with no observable impact to the surrounding soil or vegetation. Materials observed scattered at most of the locations included transit, wood, asphalt, metal, and broken glass. Surface debris was picked up by hand. Items that visually indicated potential asbestos were marked with paint. A team trained in asbestos removal collected these items. The debris items were visually evaluated to determine if they contained potential hazardous or dangerous constituents. Locations were evaluated for contamination in the soil. No soil contamination was identified and no samples were collected. The debris was disposed in ERDF.

Area 2 Glass Bottle location resulted in the bottle and 0.03 cubic meters (1 cubic ft) of soil being placed in a plastic bag and disposed in ERDF.

Area 3 was a stained soil site that measured approximately 12 meters (39 ft) by 13 meter (43 ft). Area 3 PCB Stained soil resulted in several phases of excavation and sampling. A test pit excavation extended to groundwater (46 feet deep) in one area. A total of 2330 bank cubic meters of soil was taken to ERDF.

Final (5/12/2014): The 300-274 Surface Debris waste site consisted of Area 1, surface debris areas, Area 2, a glass bottle location, and Area 3, a polychlorinated biphenyl (PCB)-stained soil area. Remedial action at the 300-274 Area 1 surface debris areas was remediated by hand pickup and removal of surface debris. Area 2 glass bottle location was remediated by removing the glass underlying soil. A verification sample was collected on October 12, 2009. The Area 3 PCB-stained soil area was remediated during several phases of excavation. The verification samples collected on October 12, 2009 indicated elevated PCB contamination was present. Additional remediation was performed and a second verification sampling was performed on September 19, 2011. Elevated PCBs were measured at the location of sample EXC-7. Additional remediation was performed at this location to approximately 7.5 meters (25 ft) below ground surface (bgs). Characterization samples of groundwater and sediment were collected from a test pit extending to groundwater at approximately 11.9 meters (39 ft) bgs.

The 300-274 waste site was remediated and has been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the RDR/RAWP (DOE-RL 2014). Contamination in portions of this site extended to groundwater. Verification sampling results show that the residual site soil meets the CUL's for direct exposure and groundwater protection and river protection and support an industrial land use scenario. Because the remediation of the waste site did not meet residential land use cleanup levels, the waste site requires institutional controls to maintain industrial land use. In accordance with this evaluation, the verification sampling results support a reclassification of the 300-274 waste site to Final Closed Out.

Code: 300-275	Classification: Accepted
Names: 300-275; Potential Landfill on River Edge	Reclassification: Final Closed Out (2/18/2014)
Type: Sanitary Landfill	Start Date:
Status: Inactive	End Date:

Description: The waste site has been remediated and Interim Closed Out. Before remediation the site consisted of seven areas of debris in two regions, a northern and southern one. There were three surface debris areas and four subsurface debris areas.

Location: There were two separate regions of debris. The northern region was approximately 40 meters (131 feet) west of the Columbia River shoreline and 140-meters (459-feet) north of the remediated 300-49, Landfill 1a site. The southern region with one surface debris area and two subsurface areas was located 9 meters (29.5 feet) northeast of 300-49.

Waste Type: Misc. Trash and Debris

Waste Description: Contaminants of Potential Concern: Asbestos The two surface debris areas in the northern region contain sparsely scattered surface debris, including small fragments of potential asbestos containing shingles and concrete. Other sparse, but visible debris includes rusted cans, metal fragments of unknown origin, pieces of insulated electrical cable, and a few pieces of broken glass. The underground debris is of unknown type. The surface debris area in the southern region includes small fragments of potential asbestos containing shingles, metal fragments, a few small pieces of concrete debris, glass fragments, and porcelain jar fragments. There is also a small segment of stainless steel pipe and a broken graduated cylinder, both likely related to the Hanford laboratory work in the 300 Area. The underground debris is of unknown type. (Logbook EL-1583-5, pp.20-21)

Closure Info: Interim: The first phase of remediation of the 300-275 waste site was accomplished by hand pick up and removal of surface debris. Surface debris identified at both the northern and southern regions of the site included small fragments of potentially asbestos-containing shingles (transite), metal fragments, concrete pieces, porcelain jar fragments, rusted cans, metal fragments, insulated electrical cable, broken glass, pieces of copper tubing, a broken graduated cylinder, and other trash. Materials removed were disposed at ERDF. The second phase involved excavation of subsurface debris in the northern and southern regions of the site. Excavation occurred between July 25, 2007, and August 9, 2007. Transite and other possible asbestos-containing materials were found in the subsurface debris at both regions of the 300-275 waste sites.

A total of 1,148 bank cubic meters (1,502 bank cubic yards) of material were excavated from the overall site, resulting in approximately 2,754 metric tons (3,036 tons) of material disposed at the Environmental Restoration Disposal Facility (ERDF). The soil directly below items of surface debris was visually evaluated during removal of the debris. If staining or other evidence of a release of contaminants (e.g., impacted vegetation) to the underlying soil had been observed, the impacted soil would have been removed and verification soil samples collected.

None of the soil underlying surface debris collected exhibited evidence of a release of contaminants such as staining or impacted soil. In accordance with this evaluation, the verification sampling results support a reclassification of the site to Interim Closed Out. The Remaining Sites Verification Package (RSVP-2008-059) has documented that the current site conditions achieve the remedial action objectives (RAOs) and the corresponding remedial action goals (RAGs) established in the Remedial Design Report/Remedial Action Work Plan for the 300 Area (RDR/RAWP) and in the 300-FF-2 Interim Action ROD.

Final (2/18/2014): This group of sites are considered Final Closed Out in the 300-FF-2 Record of Decision and meet the criteria for Unrestricted Landuse.

Code:	300-276	Classification:	Accepted
Names:	300-276; 3607 Sanitary Sewer System; 3607 Sanitary System Miscellaneous Components; 3707; 300 Area Sanitary Sewer Disposal System	Reclassification	Final Closed Out (5/12/2014)
Type:	Sanitary Sewer	Start Date:	1/1/1943
Status:	Inactive	End Date:	1/1/1996
Description:	The waste site has been remediated and Interim Closed Out. In 2014, the site was reclassified to Final Closed Out. It consisted of the components of the original septic system which processed sanitary effluent from the 300 Area Sanitary Sewer System (300 SSS) piping. The site included the surface and subsurface sewer system components of manhole SS6, the influent diversion box, the effluent diversion box, the sludge pumping equipment, the sludge pit, the system's original septic tank, the system's original tile field, a retention basin and the measuring weir/diversion trenches.		
Location:	The components of 300-276 were located in the northeast section of 300 Area, east of the 333 building.		
Release Description:	WHC-MR-088 states the Sanitary Sewer System may have received undocumented contamination via cross contamination from other waste systems and from connections to change houses, lunchrooms, restrooms and First Aide stations populated by contaminated workers. A 1948 Health Instrument division report stated significant increases of uranium were found in the 300 Area sanitary water due to seepage from the process waste ponds. A 1991 radiological survey of the septic tank sludge pump displayed readings of 25,000 counts per minute.		
Related Sites/Structures:	This site is associated with 300-52 and 300 SSS.		
Process Description:	The original, gravity flow 300 Area Sanitary Sewer System operated from 1944 through 1996. In 1996, the ground disposal portion of the system was replaced with a pressurized system and routed to the City of Richland sewer system. This WIDS site is the pre-1996 sewer system, downstream of Manhole SS6.		
	The original sanitary sewer system (1943) consisted of one septic tank that received effluent via manhole SS6 and a tile field. In 1951, two more septic tanks, two diversion boxes, and a sludge pit and pumping system were added. The tile field was replaced by two large leaching trenches. (WIDS site 300-52 represents the two 1951 septic tanks and two leaching trenches) More improvements were made in 1960. A chlorination station was added in 1972.		
Waste Type:	Equipment		
Waste Description:	The equipment (diversion boxes, pumps, tanks) associated with the Sanitary Sewer System is potentially chemically and radioactively contaminated. WHC-MR-0388 states that a 1991		

radiation survey of the septic tank sludge pump and pipes had readings of 25,000 counts per minute.

Waste Type: Sanitary Sewage

Waste Description: The Sanitary Sewer System is potentially contains radioactive and chemical contaminants.

Closure Info: Interim (12/8/2011): The demolition of the three septic tanks, associated equipment, the liquid chlorine bottle storage facility foundation, and the loadout of demolished debris and soil, began on November 8, 2010. It was completed February 3, 2011. Debris from the demolition and excavation of the septic system included concrete, rebar, piping, valves, sand (used for tank fills), and residual sludge.

Excavation at the 300-276 waste site resulted in a total of approximately 2,228 bank cubic meters (2,914 bank cubic yards) of contaminated soil and debris. All material was direct loaded for disposal at the Environmental Restoration Disposal Facility (ERDF). A post-excavation radiological survey for gamma activity was conducted following the completion of remedial action to confirm that no radiological contamination was present. No elevated gamma activity was detected.

Final (5/12/2014): The 300-276, 3607 Sanitary System Miscellaneous Components waste site consisted of surface and subsurface sewer system components downstream from the sanitary sewer manhole SS6, including piping, an influent diversion box, sludge pumping equipment, septic tanks, tile field, and the former locations of a sludge pit, a retention basin, and a measuring weir/diversion trench facility. The foundation for an adjacent liquid chlorine bottle storage facility (chlorination station) was considered part of the 300-276 waste site for the remedial action. The demolition of the septic tanks, associated equipment, and the foundation of the former chlorination station, began in November 2010 and was completed in February 2011. The excavation extended to a maximum depth of approximately 4.5 meters (15 ft) below ground surface.

The 300-276 waste site was remediated and has been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). Verification sampling results show that concentrations of COCs meet the CUL's for direct exposure and groundwater protection and river protection and support a residential land use scenario. Contamination at the 300-276 waste site did not extend into the deep zone (below 4.6 meters [15 ft]). Therefore, institutional controls to prevent uncontrolled drilling or excavation into the deep zone of the site are not required. In accordance with this evaluation, the verification sampling results support a reclassification of the 300-276 waste site to Final Closed Out.

Code: 303-M SA	Classification: Accepted
Names: 303-M SA; 303-M Storage Area; 303-M Building Storage Area	Reclassification: Final Closed Out (2/18/2014)
Type: Storage	Start Date: 1/1/1983
Status: Inactive	End Date: 1/1/1987

Description: The 303-M SA waste site was Interim Closed Out with the 618-1 Burial Ground CERCLA remediation activities. Remedial actions were performed in accordance with remedial action objectives and goals established by the U.S. Environmental Protection Agency and the U.S. Department of Energy, Richland Operations Office, in concurrence with the Washington State Department of Ecology. The selected remedial action involved excavating the site to the extent required to meet specified soil cleanup levels and disposing of contaminated excavation

materials at the Environmental Restoration Disposal Facility in the 200 Area of the Hanford Site. This site was a RCRA TSD (part of 303-M Oxide Facility) that was transferred into the CERCLA remediation scope.

The 303-M Storage Area was an inactive, curbed, concrete pad adjacent to the west side of the 303-M Uranium Oxide Facility (UOF). The concrete surface was painted with a heavy gray paint as a fixative. Several "fixed radioactive contamination" signs were on the surface. The area was used for storage of pyrophoric uranium and Zircaloy-2 chips and fines awaiting treatment in the 303-M UOF. The metal turnings were stored underwater in 114-L (30-gal) metal drums. The drums of fines were stored in a spaced array defined by painted yellow circles on the pad.

Location: The unit is 21 feet (6.4 meters) east of the 333-N Building and enclosed within a 6-inch high concrete curb adjacent to the west wall of the 303-M Uranium Oxide Facility.

Related Sites/ Structures: Structures associated with this unit include the 333-N Building, the 303-M Building, the remnants of the 303-L Building, and the 618-1 Burial Ground.

Process Description: The storage area was used to store drums of uranium and zircaloy-2 chips and fines, prior to oxidation in the 303-M Uranium Oxide Facility. Lift trucks with barrel clamps were used to transport the drums of uranium metal turnings from the 333-N Fuels Fabrication Building to a designated storage spot (a solid yellow circle painted on) the storage pad. Water levels in the drums were maintained within six inches of the top of the drum, well above the level of the fines in the drum. Barrel clamps were used to pick up a drum and take it into the 303-M Uranium Oxide Facility for processing.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: The area was used for storage of pyrophoric uranium and zirconium fines awaiting treatment in the 303-M Oxidation Facility. The metal turnings were stored under water in 30 gallon metal drums. The drums of uranium fines were stored in a spaced array defined by painted yellow circles on the pad. An estimated 127 tons (115,300 kilograms) of uranium were treated during the 303-M Facilities operation from 1983 to 1987.

Closure Info: Interim: The 618-1 Burial Ground, two subsites, three consolidated sites and four co-located sites were remediated as a group. This group included WIDS sitecodes 618-1, 618-1:1, 618-1:2, 333 LHWSA, UPR-300-13, UPR-300-14, 300-110, 303-M SA, 303-M UOF and 333 ESHWSA. Parts of waste sites 300-15, 300-259 and UPR-300-17 were also remediated along with 618-1. Several facilities were built over the top of portions of the 618-1 Burial Ground after it ceased to operate. These facilities were demolished and their debris taken to the Environmental Restoration Disposal Facility (ERDF) prior to the start of the burial ground remediation project.

Field remediation activities at the 618-1 Burial Ground were performed between September 17, 2008 and September 10, 2009, in accordance with the RDR/RAWP. Approximately 47,332 metric tons (52,160 US tons) of soil and debris was excavated and disposed of at ERDF. No excavated soil was used as backfill. Waste encountered during excavation of the 618-1 waste site consisted mostly of contaminated soil, metal pipe, crucibles, laboratory glassware, empty metal containers, and some LDR material. Twenty metal drums containing personal protective equipment (PPE) were removed from the trenches. The PPE was about 80% decomposed. Several bottles containing liquid and/or powder were also removed. One relatively large area on the south side of the burial ground was stained yellow presumably from acid leaks known to have occurred at the site.

Some land disposal restricted (LDR) materials, like lead solids contaminated with barium and chromium, were identified among the debris. The LDR material was segregated from the bulk soil and non-LDR debris for disposal. The bulk soil and non-LDR debris was sorted and

segregated in the burial trenches. After sorting, the remaining bulk soil debris stockpiles were sampled to ensure that the material was in compliance with land disposal restrictions. The released stockpiled material was transported to ERDF for disposal. Land disposal restricted materials that had been segregated for treatment were transported to ERDF under a separate waste profile.

Three sites (300-15 Process Sewer, 300-259 and UPR-300-17 Metal Shavings Fire) were partially remediated with the 618-1 remedial action.

Final (2/18/2014): This group of sites are listed in the 300-FF-2 Record of Decision. Institutional Controls to maintain industrial land use are required.

Code:	303-M UOF	Classification:	Accepted
Names:	303-M UOF; 303-M Uranium Oxide Facility	Reclassification	Final Closed Out (2/18/2014)
Type:	Process Unit/Plant	Start Date:	1/1/1983
Status:	Inactive	End Date:	
Description:	<p>The 303-M Building was demolished in March 2006, and the debris shipped to the ERDF as described in Facility Status Change Form D4-300-008. This site was a RCRA TSD that was transferred into the CERCLA remediation scope.</p> <p>The site was a reinforced concrete structure containing a high bay area and a one-story extension on the north side of the building. The 303-M SA is located on the west side of the building. The building was used to oxidize pyrophoric uranium metal turnings and chips and Zircaloy-2 fines generated during fuel fabrication machining operations in the 333 Building. During the 4 years that it was operational (1983 to 1987), the 303-M UOF converted 115 metric tons of uranium scrap into oxide form.</p>		
Location:	<p>The unit is located in the north central 300 Area, east of the 333 Building. All contaminated surfaces have been fixed by paint.</p>		
Related Sites/ Structures:	<p>Structures related to the 303-M Building include the 303-M Storage Area (WIDS Site Code 303-M SA), the 333 Building, the 618-1 Burial Ground, and the remnants of the 303-L Building.</p>		
Process Description:	<p>The facility was used to oxidize pyrophoric uranium metal turnings and chips and zircalloy-2 fines generated during fuel fabrication machining operations in the 333 Building. The metal turnings were received in 30 gallon drums filled with water for fire prevention. The metal turnings were removed, screened, hand fed into a shredder/chopper, and small bags of metallic fines were placed inside a burner chamber for oxidation.</p>		
Waste Type:	Chemicals		
Waste Description:	<p>The oxidation process feed material was pyrophoric uranium and zircalloy-2 fines. Approximately 127 tons (115,300 kilograms) of material was oxidized during operations. Waste currently at the facility may include residual radiological and chemical contamination in the process equipment, on surfaces, and in the process sewer.</p>		
Closure Info:	<p>Interim: The 618-1 Burial Ground, two subsites, three consolidated sites and four co-located sites were remediated as a group. This group included WIDS sitecodes 618-1, 618-1:1, 618-1:2, 333 LHWSA, UPR-300-13, UPR-300-14, 300-110, 303-M SA, 303-M UOF and 333 ESHWSA. Parts of waste sites 300-15, 300-259 and UPR-300-17 were also remediated along with 618-1. Several facilities were built over the top of portions of the 618-1 Burial Ground after it ceased to operate. These facilities were demolished and their debris taken to the Environmental Restoration Disposal Facility (ERDF) prior to the start of the burial ground</p>		

remediation project.

Field remediation activities at the 618-1 Burial Ground were performed between September 17, 2008 and September 10, 2009, in accordance with the RDR/RAWP. Approximately 47,332 metric tons (52,160 US tons) of soil and debris was excavated and disposed of at ERDF. No excavated soil was used as backfill. Waste encountered during excavation of the 618-1 waste site consisted mostly of contaminated soil, metal pipe, crucibles, laboratory glassware, empty metal containers, and some LDR material. Twenty metal drums containing personal protective equipment (PPE) were removed from the trenches. The PPE was about 80% decomposed. Several bottles containing liquid and/or powder were also removed. One relatively large area on the south side of the burial ground was stained yellow presumably from acid leaks known to have occurred at the site.

Some land disposal restricted (LDR) materials, like lead solids contaminated with barium and chromium, were identified among the debris. The LDR material was segregated from the bulk soil and non-LDR debris for disposal. The bulk soil and non-LDR debris was sorted and segregated in the burial trenches. After sorting, the remaining bulk soil debris stockpiles were sampled to ensure that the material was in compliance with land disposal restrictions. The released stockpiled material was transported to ERDF for disposal. Land disposal restricted materials that had been segregated for treatment were transported to ERDF under a separate waste profile.

Three sites (300-15 Process Sewer, 300-259 and UPR-300-17 Metal Shavings Fire) were partially remediated with the 618-1 remedial action.

Final (2/18/2014): This group of sites are listed in the 300-FF-2 Record of Decision. Institutional Controls to maintain industrial land use are required.

Code:	311 MT1	Classification:	Accepted
Names:	311 MT1; 311 Tank Farm Underground Methanol Tank #1; 311-1; 311 Methanol Tank 1	Reclassification	Final Closed Out (2/18/2014)
Type:	Storage Tank	Start Date:	1/1/1955
Status:	Inactive	End Date:	1/1/1971
Description:	The waste site was reclassified to Closed Out in 1999. It was considered to be Final Closed Out in 2014. The underground tank was removed in 1989. The excavation was backfilled and covered with gravel. Prior to removal, the waste site consisted of an underground, horizontal, flat-ended cylindrical tank.		
Location:	The site was northwest of 303-G and northeast of 303-F.		
Related Sites/ Structures:	Structures associated with the tank include the other 311 Methanol Tank (WIDS Site 311 MT2), the 313 Methanol Tank (WIDS Site 313 MT), transfer piping, and the 313 Building. WIDS Site 300-40 (Corrosion of Vitriified Clay Sewer Pipe) is located to the west of the site.		
Process Description:	The unit is no longer active and has been removed. While in service the unit stored pure methanol used as a final rinse to remove water from aluminum end caps and cans in the " triple dip" and "lead dip" fuel fabrication processes.		
Waste Type:	Chemicals		
Waste Description:	The unit contained an aqueous solution of methanol. Methanol was used as a drying agent for the aluminum cleaning process. The methanol was pumped from the tank in 1971. The tank was removed in 1989.		

Closure Info: Interim: The tank was removed August 30, 1989. The 311 MT1 tank and two others (311 MT2 and 313 MT) were taken to the Nonradioactive Dangerous Waste Landfill (NRDWL) for storage.

The tank impressions from all three tanks were surveyed with a photo ionization organic vapor detector (HNU Model P1-101). There were no readings. Narrow holes were bored into the sand at suspicious locations. There were no readings. There was no stained soil. Samples (random) were collected at four locations around the tank. The excavation was backfilled on the completion of the tank removal.

Review of the results of soil tests from 311 MT1, 311 MT2, and 313 MT excavations indicate that none of the tanks had leaked.

The reclassification is documented on form 99-06.

Final (2/18/2014): This group of sites is listed in the 300-FF-2 and 300-FF-5 Records of Decision and the 300-FF-1 ROD Amendment as requiring no further action. They were reclassified to Final Closed Out in February 2014 on reclassification form 2014-009.

Code: 311 MT2	Classification: Accepted
Names: 311 MT2; 311 Tank Farm Underground Methanol Tank #2; 311-2; 311 Methanol Tank 2	Reclassification: Final Closed Out (2/18/2014)
Type: Storage Tank	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1971

Description: The waste site was reclassified to Closed Out in 1999. It was considered to be Final Closed Out in 2014. The tank was removed in 1989. The excavation was backfilled and covered with gravel. Prior to removal, the site consisted of a horizontal, flat-ended cylindrical tank.

Location: The tank was located northwest of 303-G and northeast of 303-F.

Related Sites/Structures: Structures associated with the tank include the other 311 Methanol Tank (WIDS Site 311 MT1), the 313 Methanol Tank (WIDS Site 313 MT), transfer piping, and the 313 Building. WIDS Site 300-40 (Corrosion of Vitriified Clay Sewer Pipe) is located to the west of the site.

Process Description: While in service the MT2 tank stored used methanol solution generated in the 313 fuel fabrication/final rinse processes, until the solution was de-watered in the still. The de-watered methanol was then added to the 311 Methanol Tank (WIDS Sitecode 311 MT1).

Waste Type: Chemicals

Waste Description: The unit contained an aqueous solution of methanol. Methanol was used as a drying agent for the aluminum cleaning process. The methanol was removed from the tank in 1971. The tank was removed in 1989.

Closure Info: Interim: The tank was removed August 30, 1989. The 311 MT2 tank and two others (311 MT1 and 313 MT) were taken to the Nonradioactive Dangerous Waste Landfill (NRDWL) for storage.

The tank impressions from all three tanks were surveyed with a photo ionization organic vapor detector (HNU Model P1-101). There were no readings. Narrow holes were bored into the sand at suspicious locations. There were no readings. There was no stained soil. Samples (random) were collected at four locations around the tank. The excavation was backfilled on the completion of the tank removal.

Review of the results of soil tests from 311 MT1, 311 MT2, and 313 MT excavations indicate that none of the tanks had leaked.

The Reclassification is documented on form 99-07.

Final (2/18/2014): This group of sites is listed in the 300-FF-2 and 300-FF-5 Records of Decision and the 300-FF-1 ROD Amendment as requiring no further action. They were reclassified to Final Closed Out in February 2014 on reclassification form 2014-009.

Code:	313 ESSP	Classification:	Accepted
Names:	313 ESSP; 313 Building East Site Storage Pad; 313 East Side Storage Pad	Reclassification	Final Closed Out (5/12/2014)
Type:	Storage	Start Date:	
Status:	Inactive	End Date:	
Description:	<p>The 313 East Side Storage Pad (ESSP) has been remediated and Interim Closed Out. In 2014, the site was reclassified to Final Closed Out. The 313 ESSP waste site previously staged radiological waste from 313 Building operations and, during fuel fabrication operations, staged mixed waste from the 313 Building centrifuge and uranium waste from the 313 Building filter press. The unit was also used to stage raw materials received by rail cars.</p> <p>It was a large concrete pad with an asphalt ramp that connected the pad to Ginko street. The Waste Acid Treatment System pipe trench (WIDS Site 300-224) passed east-west through the site and was posted as internally contaminated with radioactive material. Two areas of the pad, located adjacent to the east wall near the southern end of the 313 building had been painted gray. Signs were placed at the base of the walls, just above the painted areas that read "Fixed Contamination - Contamination Under Grey Paint on Ground".</p>		
Location:	<p>The unit is adjacent to the south eastern side of the 313 Building. The unit extends from the 313 Building to approximately 15 meters (50 feet) from the railroad tracks east of the 313 Building and south to the north side of Ginko Street.</p>		
Related Sites/ Structures:	<p>Structures associated with the unit include the 313 Buildings, the 303 Buildings, the Waste Acid Treatment System pipe trench (WIDS Site 300-224), and the railroad tracks along the east side of the pad.</p>		
Process Description:	<p>Previously the site staged radiological waste from 313 Building operations and, during fuel fabrication operations, staged mixed waste from the 313 Centrifuge and uranium waste from the 313 Filter Press. The unit was also used to stage raw materials received by rail cars.</p>		
Waste Type:	Barrels/Drums/Buckets/Cans		
Waste Description:	<p>The area was used to stage mixed waste including byproduct waste materials from the fuels fabrication process and neutralized solids from the 313 Recovery Operations process.</p>		
Closure Info:	<p>Interim (4/30/2012): The UPR-300-38 waste site consisted of contaminated soil beneath the 313 Building, as well as the foundation. The contamination resulted from multiple unplanned release events. The 313 ESSP (East Side Storage Pad) waste site was the footprint of a large concrete pad adjacent to the southeastern side of the former 313 Building, with an asphalt ramp that connected the pad to Ginko Street. The 300- 270 waste site was the area of a release of whitish storm water that came from a pipe under the loading dock on the east side of the former 313 Building. The pipe drained the roof of the former 313 Building.</p>		

Remediation of the UPR-300-38 waste site was performed from January 10, 2010, through June 2, 2011. The soil within the northern portion of the waste site footprint was excavated to an

approximate average depth of 1 meter (3.3 ft) below ground surface (bgs). The southern area of the waste site was excavated to an approximate average depth of 2 meters (6.6 ft) bgs, with limited areas of deeper soil contamination to 5 meters (16.4 ft) bgs. The resulting 15,204 bank cubic meters (BCM) (19,887 bank cubic yards [BCY]) of soil was disposed at the Environmental Restoration Disposal Facility (ERDF).

Remediation of a large portion of the 313 ESSP waste site was performed by the excavation of concrete, asphalt, and underlying soil during the remediation of the UPR-300-38 waste site and the adjacent area near the footprint of the former 303-F Building. This work was performed on July 8, 2011. The soil within the waste site footprint was excavated to a depth of 1 meter (3.3 ft) bgs, and the resulting 153 BCM (205 BCY) of soil was disposed at ERDF. Approximately 98 BCM (128 BCY) was associated with the UPR-300-38 excavation; the remainder (55 BCM [72 BCY]) was associated with the 313 ESSP excavation near the footprint of the former 303-F Building. An additional 38 BCM (50 BCY) was removed from the northeast corner and the southern edge of the 313 ESSP waste site on August 26, 2011, resulting in a total of 191 BCM of debris and soil removed from the 313 ESSP waste site.

Remediation of the 300-270 waste site was performed May 23, 2011. The soil within the waste site footprint was excavated to a depth of 0.5 meter (1.6 ft) bgs, and the resulting 40 BCM (52 BCY) of soil was disposed at ERDF.

A total of 15,435 bank cubic meters (20,194 bank cubic yards) of soil and debris from the remediation of all three waste sites was disposed at the Environmental Restoration Disposal Facility.

Final: The UPR-300-38, Soil Contamination Beneath the 313 Building; 313 ESSP, 313 East Side Storage Pad; and 300-270, Unplanned Release at 313 Building waste sites were either within or immediately adjacent to the footprint of the demolished 313 Building. The UPR-300-38 waste site consisted of contaminated soil beneath the 313 Building, as well as the foundation. The contamination resulted from multiple unplanned release events. The 313 ESSP waste site was the footprint of a large concrete pad adjacent to the southeastern side of the former 313 Building, with an asphalt ramp that connected the pad to Ginko Street. The 300-270 waste site was the area of a release of whitish storm water that came from a pipe under the loading dock on the east side of the former 313 Building. The pipe drained the roof of the former 313 Building. Remediation of the UPR-300-38 waste site was performed from January 2010 through June 2011. Remediation of a large portion of the 313 ESSP waste site occurred July 8 and August 26, 2011 and included excavation of concrete, asphalt, and underlying soil. Remediation of the 300-270 waste site was performed May 23, 2011. The maximum depth of the remediation at the UPR-300-38 waste site was 5 meters (16.4 ft) below ground surface. The 313 ESSP and 300-270 waste sites were remediated to 1 meters (3.3 ft) bgs.

The 300-270, 313 ESSP, and UPR-300-38 waste sites were remediated and have been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). Site-specific RESRAD modeling predicts that the radionuclide verification focused sampling results meet the excess cancer risk and allowable radiation dose and are protective of groundwater and the Columbia River under an industrial land use scenario. The remaining verification sampling results show that the site meets the CUL's for direct exposure and groundwater protection and river protection and support an industrial land use scenario. Contamination at these waste sites did not extend into the deep zone soils. Because the remediation of the waste sites did not meet residential land use cleanup levels, the waste sites require institutional controls to maintain industrial land use. In accordance with this evaluation, the verification sampling results support a reclassification of the 300-270, 313 ESSP, and UPR-300-38 waste sites to Final Closed Out.

Code: 313 MT	Classification: Accepted
Names: 313 MT; 313 Building Underground Methanol Storage Tank; 313 Methanol Tank	Reclassification: Final Closed Out (2/18/2014)
Type: Storage Tank	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1971

Description: The waste site was reclassified to Closed Out in 1999. It was considered to be Final Closed Out in 2014. The 313 Methanol Tank was emptied in 1987 and removed in 1989. The excavation was backfilled and the floor was patched with concrete. Prior to removal the site consisted of a steel cylindrical tank lying horizontally. The tank was below the floor of the 313 Building.

Location: The tank was located below the floor in the southeast portion of the 313 Building.

Release Description: No releases have been identified.

Description:

Related Sites/ Structures: Structures associated with the tank include the 311 Methanol Tank 1 (WIDS Site 311 MT1), the 311 Methanol Tank 2 (WIDS Site 311 MT2), transfer piping, and the 313 Building.

Process Description: Prior to removal, the tank was used as an emergency dump tank. In case of a fire in the 313 Building, the methanol from the dehydration tanks could be released to the underground tank. The tank was never used for an emergency dump.

Waste Type: Chemicals

Waste Description: From 1971 to 1987 the tank contained an aqueous methanol solution. The tank was removed in 1989. The tank never received an emergency methanol dump.

Closure Info: Interim: The tank was removed August 30, 1989. The 313 MT tank and two others (311 MT2 and 311 MT2) were taken to the Nonradioactive Dangerous Waste Landfill (WIDS Site NRDWL) for storage.

The tank impressions from all three tanks were surveyed with a photo ionization organic vapor detector (HNU Model P1-101). There were no readings. Narrow holes were bored into the sand at suspicious locations. There were no readings. There was no stained soil. Samples (random) were collected at four locations around the tank. The excavation was backfilled on the completion of the tank removal.

Review of the results of soil tests from 311 MT1, 311 MT2, and 313 MT excavations indicate that none of the tanks had leaked.

The reclassification is documented on form 99-08.

Final (2/18/2014): This group of sites is listed in the 300-FF-2 and 300-FF-5 Records of Decision and the 300-FF-1 ROD Amendment as requiring no further action. They were reclassified to Final Closed Out in February 2014 on reclassification form 2014-009.

Code: 316-3	Classification: Accepted
Names: 316-3; Process Water Trenches; 307 Disposal Trenches	Reclassification: Final Closed Out (9/17/2015)
Type: Trench	Start Date: 1/1/1953
Status: Inactive	End Date: 1/1/1963

Description: The waste site was remediated and reclassified to Final Closed Out. In 2014 and 2015 the

trenches were excavated. In 2013, the waste site had been evaluated and determined to require No Action. The trenches are no longer visible. A large portion of the location has been paved and fenced. During the excavation of the 300-263 tank, contamination was found that prompted the 316-3 trenches to be re-evaluated and excavated.

Location: The trenches were located east of 300 Area, southeast of the 340 Facility. Most of the waste site was inside the 324 building fence.

Related Sites/ Structures: The trenches are associated with the 340 Complex. Facilities that discharged to the 307 trenches via the retention basins, included 324, 325, 326, 327, 329, and the 308 buildings. It is also associated with the 300-263 catch tank.

Process Description: From 1953 to 1963, process sewer effluent below discharge limits was released from the 307 Retention Basins and discharged to the parallel trenches. Effluent above discharge limits was transported to the 200 Area for disposal. The 316-3 waste site received wastes from the 300 Area Laboratory expansion facilities including the 329 Biophysics Laboratory, 327 Radiometallurgy Building, 324 Radiochemistry Building, 326 Pile Technology Building, and 329 Mechanical Development Building.

The trenches were taken out of service in 1963 and the contaminated sediments were excavated and transported to the 618-10 Burial Ground. The trenches were backfilled in 1965. The trenches were backfilled in 1965 and were no longer visible. A large portion of the location had been paved and fenced. The 3727, 3719E and 3718G buildings were built on top of the backfilled trenches.

In 1987, the west end of the 316-3 waste site was used to test a grout liquid waste solidification process. A 15.2 by 6.1 by 3.0 meters (50 by 20 by 9 ft) trench was excavated immediately west of the former 3718E Building. Contaminated material was encountered. Five soil samples were collected. The radiological detector measured maximum radiological activities of 378 picocuries per gram (pCi/g) beta and 234 pCi/g alpha. In 1991, three boreholes were drilled through the trenches to a depth of approximately 65 feet. Field instruments detected a maximum of 650 counts per minute.

Waste Type: Process Effluent

Waste Description: The site received wastes from the 300 Area Laboratory expansion facilities (329 Biophysics Laboratory, 327 Radiometallurgy Building, 324 Radiochemistry Building, 326 Pile Technology Building, and 329 Mechanical Development Building). The wastes first went through the 307 Retention Basin. Retention Basin waste below discharge limits was released to the trenches from 1953 to 1963. The trenches were excavated in 1963, and the contaminated soil was taken to 300 North (618-10) Burial Ground. The trenches were backfilled with process pond scrapings and fly ash in 1965. In 1987 the west end of the 316-3 (near the 3727 building) was used to test a grout liquid waste solidification process. A 6.1 meter by 6.1 meter by 3.0 meter (20 foot by 20 foot by 9 foot) deep section of the trenches was excavated, and contaminated material (probably backfill from the south process pond) was encountered. Activities measured were as high as 378 picocuries per gram beta and 234 picocuries per gram alpha.

Closure Info: Interim (1/17/2013): Subsurface investigation sampling for the 316-3 waste site was conducted between August 13 and September 11, 2012. Samples were collected from seven test pits. Due to buried utilities in the area, the test pits locations were adjusted to minimize the potential impact of encountering active utility lines. Because the waste site had potentially contaminated backfill material, sampling was performed at 2 meter (6.6 ft) intervals to analyze potential vertical contamination and the soil underlying the backfill material.

Test pit 1 was excavated on September 11, 2012 to a depth of 20 feet.

Test pit 2 excavation was performed on August 20, 2012 to a depth of 20 feet.

Test pit 3 excavation began on August 23, 2012. A layer of asphalt was discovered at

approximately 0.33 meter (1 ft) depth. Several utility interferences were encountered to a depth of 6.6 feet.

Test pit 4 excavation was performed on August 14, 2012 to a depth of 20 feet.

Test pit 5 excavation was performed on August 15, 2012 to a depth of 20 feet.

Test pit 6 excavation was performed on August 21, 2012. A buried asphalt pad was discovered at approximate depth of 0.5 meter (1.6) bgs. Due to the close proximity of interferences, such as RLWS line and 300-15 process sewer line, the test pit could not be excavated safely. Therefore, only one surface soil sample was collected at the TP-6 location.

Test pit 7 excavation was performed on August 13, 2012 to a depth of 20 feet.

Final (9/15/2015): The 300-263 tank and the 316-3 trenches were reclassified to Final Closed out in the CVP-2015-00015 document. The 300-263 tank was located within the boundaries of the 316-3 trenches waste site.

Subsurface investigation sampling for the 316-3 waste site was conducted between August 13 and September 11, 2012. Samples were collected from seven test pits. The results for test pit sampling indicated that the 316-3 waste site achieved compliance with the remedial action objectives and remedial action goals for industrial land use. The site was reclassified as No Action on January 17, 2013.

During excavation of the 300-263 tank, in fall 2014, isolated locations of discolored soil were observed that were emitting elevated levels of radiation based on hand-held instrument readings. This contamination, determined to be uranium, was attributed to the 316-3 trench waste site. Consequently, the No Action reclassification status for the 316-3 site was rendered void, and remediation of the site was required.

Remediation of the 300-263 waste site began on September 24, 2014. During remediation of the 300-263 waste site and adjacent Radioactive Liquid Waste Sewer pipeline, stained soil and elevated radiological readings were observed on the west sidewall inside the 300-263 waste site excavation. In-process radiological sample data indicated that elevated uranium concentrations were associated with the stained soil. Based on the process knowledge, uranium contamination was attributed to the co-located 316-3 waste site.

Remediation of the 316-3 waste site was performed from December 17, 2014, to April 30, 2015. Six rounds of in-process sampling, routine radiological screening, and field observations were used to guide waste site remediation. Approximately 1,814 bank cubic meters (BCM) (2,372 bank cubic yards [BCY]) of excavated materials were removed from the 300-263 waste site and direct loaded for disposal at the ERDF. Approximately 68,020 BCM (88,967 BCY) of excavated materials were removed from the 316-3 waste site. The maximum depth of the 300-263 and 316-3 waste sites excavation was approximately 11.3 meters (37 ft) bgs on the west end, and approximately 9.8 meters (32 ft) bgs at the center and east end of the excavation. Excavated materials consisted of radiologically contaminated soil, gravel, coal ash, and limited debris associated with deactivated underground utilities.

No overburden materials were salvaged from the 300-263 and 316-3 waste sites excavation; therefore, there is no overburden pile associated with the 300-263 and 316-3 waste sites. All excavated soils were direct loaded. Therefore, no staging pile areas were utilized.

Code: 316-4	Classification: Accepted
Names: 316-4; 316-N-1; 321 Cribs; 616-4; 300 North Cribs	Reclassification: None
Type: Crib	Start Date: 1/1/1948

Status: Inactive**End Date:** 1/1/1956

Description: The crib structures were removed in 2004. The crib consisted of two bottomless tanks, buried 3 meters (10 feet) below grade, resting on gravel strata. A waste influent line extended from 0.6 meters (2 feet) above the bottom of one of the tanks and continued, at an angle, to grade level. A vent riser extended from the top of the tank to 2.4 meters (8 feet) above grade. The tanks were 0.6 meters (2 feet) apart, with a stainless steel overflow pipe connecting them just below the top of each tank. (see H-3-5305) The area was marked with AC-540 markers marked "Crib 316-4". A 1995 Geophysical Investigation survey verified the tanks had concrete footings and sat on a bed of gravel. It also states the tanks are believed to be 8 foot in diameter, 7 ft tall, with the tops of the tanks being located approximately 10 feet below the surface.

The crib excavation was backfilled in 2005 with 4221 meters of clean dirt.

Location: The site is located northwest of the 300 Area, approximately 45 meters (150 feet) southeast of the 618-10 (300 North) Burial Ground.

Release Description: A cumulative total of 895 kgs (1974 pounds) of uranium was discharged into the cribs as U-bearing organic wastes from the 321 Building from 1948 through June 23, 1954.

Process Description: The site received hexone-bearing uranium wastes and limited amounts of other uranium-bearing wastes from the 321 Building. Calculations up to and including July 1955 indicated liquid wastes containing a total of 550 kg (1,230 lbs) of uranium had been discharged to this site. Additional documentation has been found indicating 12,040 L (3,182 gal) of liquid organic waste was being shipped to the 300 North Cribs in 1962.

Waste Type: Process Effluent

Waste Description: The site received hexone-bearing uranium wastes and limited amounts of other uranium-bearing wastes from the 321 Building. Calculations up to and including July 1955 indicated liquid wastes containing a total of 550 kilograms (1,230 pounds) of uranium had been discharged to this site. Additional documentation has been found indicating 12,040 liters (3,182 gallons) of liquid organic waste was being shipped to the 300 North Cribs in 1962.

Code: 331 LSLDF**Classification:** Accepted**Names:** 331 LSLDF; 331 Life Sciences Laboratory Drainfield; 331 LSL Drain Field**Reclassification:** Final Closed Out (3/10/2014)**Type:** Drain/Tile Field**Start Date:** 1/1/1970**Status:** Inactive**End Date:** 1/1/1974

Description: In 2008, The 331 LSLDF waste site was evaluated and determined to require No Action. In 2014, it was reclassified to Final Closed Out. It is a septic system consisting of a diversion chamber, two (dual-chambered) septic tanks, a distribution box, and a drain field connected to the 331 complex. The 331 LSLDF septic system was operational from 1970 to 1974, at which time the sanitary sewer connections were rerouted to the 300 Area Sanitary Sewer. The 331 LSLDF septic system was fully isolated and abandoned in place in 1974. The waste line has been capped west of the septic tanks. The drainfield is marked with a single sign at the site center.

Location: The unit is located southeast of the 331 Building.

Related Sites/ Structures: The drainfield is associated with the 331 Life Sciences Laboratory.

Process Description: The septic system was designed to receive sanitary wastewater associated with animal studies from the 331-A and 331-B Buildings for discharge into the soil column. However, field

observations and testing suggest this system did not receive any discharges. It is probable that all of the animal study discharges were routed to the 331 Life Sciences Laboratory Trenches 1 and 2 (331 LSLT1 and 331 LSLT2), the 331 LSLT1 Animal Waste Pit, the 300 Area Sanitary Sewer, or transported to the 100 Area.

The animal studies involved the use of radioisotopes, and the animal waste was segregated on the basis of radiological activity. Solid animal waste exceeding 200 pCi/g specific activity was transported to the 100 F Area trenches. Other solid animal waste (less than 200 pCi/g specific activity) was allowed to flush into the 331 waste system(s). The 331 Building, located in the Hanford Site's 300 Area, was constructed in 1970. The largest portion is a three story facility, consisting of laboratories on the first and third floors. The first floor laboratory area initially contained a multi-room, inhalation toxicology, and exposure suite. The third floor laboratories included small animal facilities, and related animal physiology and inhalation toxicology laboratories, low-level and high-level radiochemistry laboratories, as well as tissue culture, virology, histology, hematology, biochemistry, histochemistry, pathology, and microbial physiology laboratories. Two smaller ancillary structures, 331-A and 331-B, made up another segment of the 331 Building. The 331-A Building is detached and located on the northwest side of the 331 Building and contained 15 pen areas for large animals (e.g., swine). The 331-B Building, connected to the west and southwest portion of the 331 Building, is a one-story concrete block structure with long, narrow, animal runs. The run area originally contained 110 concrete living units for dogs. The north section was comprised of an animal clinic, hospital, food preparation room, and change room. An equipment room and a metabolism room were located at the south end of the animal runs. The dog runs were built as a wing adjacent to 331-B. It also contained dog habitat areas.

A semi-high bay building, 331-D, was erected southeast of the 331 Building in 1974. The 331-D Building was to serve as an Animal Waste Treatment Facility. It contained a 94,625 liters per day (25,000 gallons per day) capacity waste treatment plant, which was designed to chemically treat, mechanically flocculate, settle, and gravity filter animal wastes. A sludge dryer also was installed to heat and dry 54.4 kilograms per hour (120 pounds per hour) of sewage sludge product from the treatment facility.

Waste Type: Animal Waste

Waste Description: The unit may have received animal waste from the 331 Buildings prior to construction of the 331-D Treatment Facility. Since most of the animal studies involved the use of radio isotopes, animal waste was segregated on the bases of activity. Solid animal waste, exceeding 200 picocuries per gram specific activity, was transported to the 100-F Area trenches on a regular basis. All other solid animal waste (less than 200 picocuries per gram specific activity) was allowed to flush into the 331 waste system. However, specific cases of contamination have occurred at the 331 complex. In January 1975, between 25 and 2,500 microcuries of plutonium-238 from contaminated soil used in a botanical experiment was washed into the process sewer. This material may have ended up in the 331 Life Science Laboratory Drainfield (LSLDF). The constituents of concern listed below reflects those which could potentially still be present in the subsurface at the 331 Building WIDS sites. During the course of identifying the constituents of concern no evidence of any waste containing PCBs was discovered during a records review. A walkthrough of the facility did not reveal the presence of any PCB containing equipment with the exception of possible PCB laden light ballast. All transformers were of the dry design. Therefore, PCBs are not listed among the constituents of concern. These contaminants are americium-241, curium-244, neptunium-237, plutonium-238, plutonium-239, uranium-232, uranium-233, cadmium, chromium, lead, uranium (total).

Waste Type: Sanitary Sewage

Waste Description: The unit received sanitary wastewater from the 331-A and 331-B Buildings for discharge into the soil column.

Closure Info: Interim (10/16/2008): This septic system was designed to receive sanitary wastewater associated with animal studies from the 331-A and 331-B Buildings for discharge into the soil column. However, field observations and testing suggest this system did not receive any discharges. Similar to the septic tanks, all of the drain field laterals were found to be clean, almost new in appearance. Sediments within the laterals were only sparingly available, and the little that could be collected (from the fifth and sixth laterals in the northern trench and the sixth lateral in the southern trench) had to be combined to achieve a sufficient sample size for fixed laboratory analysis.

During the RSVP evaluation field radiological surveys were performed to evaluate the presence of radioisotopes from the animal studies. No radiological activity was detected in the field or in the samples analyzed at the laboratories. The sample results did indicate detections for 17 non-radioactive COPCs. It is probable that all of the animal study discharges were routed to the 331 Life Sciences Laboratory Trenches 1 and 2 (331 LSLT1 and 331 LSLT2), the 331 LSLT1 Animal Waste Pit, the 300 Area Sanitary Sewer, or transported to the 100 Area

Confirmatory sampling of the drain field and of the soil around the distribution box was performed in April 2007. Similar to the septic tanks, all of the drain field laterals were found to be unexpectedly clean, and almost new in appearance. Sediments within the laterals were only sparingly available, and the little that could be collected from each lateral was combined to achieve a sufficient sample size for fixed laboratory analysis.

Final (3/10/2014): This site is listed in the 300-FF-2 Record of Decision. Institutional Controls to maintain industrial land use are required.

Code:	331 LSLT1	Classification:	Accepted
Names:	331 LSLT1; 331 Life Sciences Laboratory Trench #1; 331 LSL Trench 1	Reclassification	None
Type:	Trench	Start Date:	1/1/1966
Status:	Inactive	End Date:	1/1/1969
Description:	The trench is currently marked with a single sign at the site centerline and surrounded with Underground Radioactive Material signs. The 331 Life Sciences Laboratory Trench 1 (LSLT1) is an abandoned leaching trench that has been backfilled. The site was a rectangular excavation. The site includes connecting waste transfer lines.		
Location:	The unit was located underneath or near the east end of the 331 Building. The north leaching trench has been arbitrarily designated as the 331 LSLT1 unit. The site is located just north of the 331 LSLT2.		
Related Sites/ Structures:	The structures associated with this site include the 331 LSLT2 trench immediately to the south, the No. 1 and No. 2 Diversion Chambers, the animal waste unloading pit, the 331-B Sanitary Septic Tank, the 331-B (and possibly 331-A) Building, and the waste transfer lines. Other associated structures are the 331 Life Sciences Laboratory Drain Field and the 331-D Animal Waste Treatment Facility.		
Process Description:	The 331 Leaching Trenches disposed of sanitary and animal wastes to the soil column. Sanitary waste flowed from the 331-B Septic Tank and animal waste flowed from the animal waste unloading pit, entered Diversion Chamber No. 1, and was subsequently discharged to the leaching trenches.		
Waste Type:	Sanitary Sewage		

Waste Description: The unit received sanitary wastewater.

Waste Type: Animal Waste

Waste Description: The unit received liquid animal waste from the animal waste pit. Since most of the animal studies involved the use of radio isotopes, animal waste was segregated on the bases of activity. Solid animal waste, exceeding 200 picocuries per gram specific activity, was transported to the 100-F Area trenches on a regular basis. All other solid animal waste (less than 200 picocuries per gram specific activity) was allowed to flush into the 331 waste system. However, specific cases of contamination have occurred at the 331 complex. The constituents of concern reflect those contaminants which could potentially still be present in the subsurface at the 331 Building WIDS sites. These include americium-241, curium-244, neptunium-237, plutonium-238, plutonium-239, uranium-232, uranium-233, cadmium, chromium, lead, uranium (total). During a records review to identify the constituents of concern, no evidence of any waste containing PCBs was discovered. A walkthrough of the facility did not reveal the presence of any PCB containing equipment with the exception of possible PCB laden light ballasts. All transformers were of the dry design. Therefore, PCBs are not listed among the constituents of concern.

Code: 331 LSLT2

Classification: Accepted

Names: 331 LSLT2; 331 Life Sciences Laboratory Trench #2; 331 LSL Trench 2

Reclassification: None

Type: Trench

Start Date: 1/1/1966

Status: Inactive

End Date: 1/1/1974

Description: The trench is currently marked with a single sign at the site centerline and surrounded with Underground Radioactive Material signs. The 331 LSLT2 is an abandoned leaching trench that has been backfilled. The site was a rectangular excavation. The site includes connecting waste transfer lines.

Location: The unit was located underneath or near the east end of the 331 Building. The south leaching trench has been arbitrarily designated as the 331 LSLT2 Unit. The site is located just south of the 331 LSLT1.

Related Sites/Structures: The structures associated with this site include the LSLT1, the No. 1 and No. 2 Diversion Chambers, the animal waste unloading pit, the 331-B Sanitary Septic Tank, the 331-B (and possibly 331-A) Buildings, and the waste transfer lines. Other associated structures are the 331 Life Sciences Laboratory Drain Field and the 331-D Animal Waste Treatment Facility.

Process Description: The 331 Leaching Trenches disposed of sanitary and animal wastes to the soil column. Sanitary waste flowed from the 331-B Septic Tank and animal waste flowed from the animal waste unloading pit, entered Diversion Chamber No. 1, and was subsequently discharged to the leaching trenches.

Waste Type: Animal Waste

Waste Description: The unit received liquid animal waste from the animal waste pit. Animal wastes were the most prominent wastes, in terms of volume, generated by the 331 complex. Originally, liquid animal wastes from the complex including washdowns from the "hog and dog runs" were disposed to a large, unlined pit, east of the 331-D Building. Sewers carrying animal waste from the 331 complex were also connected to this pit. Since most of the animal studies involved the use of radio isotopes, animal waste was segregated on the bases of activity. Solid animal waste, exceeding 200 picocuries per gram specific activity, was transported to the 100-F Area trenches on a regular basis. All other solid animal waste (less than 200 picocuries per gram specific

activity) was allowed to flush into the 331 waste system. However, specific cases of contamination have occurred at the 331 complex. The constituents of concern reflect those contaminants which could potentially still be present in the subsurface at the 331 Building WIDS sites. These include americium-241, curium-244, neptunium-237, plutonium-238, plutonium-239, uranium-232, uranium-233, cadmium, chromium, lead, uranium (total). During a records review to identify the constituents of concern, no evidence of any waste containing PCBs was discovered. A walkthrough of the facility did not reveal the presence of any PCB containing equipment with the exception of possible PCB laden light ballasts. All transformers were of the dry design. Therefore, PCBs are not listed among the constituents of concern.

Waste Type: Sanitary Sewage

Waste Description: The unit received sanitary wastewater. In 1974, the clean (non-radioactive) animal sewage was connected to the regular 300 Area Sanitary Sewer System.

Code: 333 ESHWSA

Classification: Accepted

Names: 333 ESHWSA; 333 Building East Side Hazardous Waste Storage Area; 333 East Side HWSA

Reclassification: Final Closed Out (2/18/2014)

Type: Storage

Start Date: 1/1/1964

Status: Inactive

End Date:

Description: The 333 East Side Hazardous Waste Storage Area is part of the asphalt paved area near the northeast corner of the 333 Building, within the building fence line. No barrels of hazardous waste are stored here anymore, only miscellaneous non-hazardous materials. Currently, several large trash dumpsters are at this location.

Location: The unit is located northeast of the 333 Building, in the northern part of the 300 Area.

Related Sites/Structures: The unit is associated with the 333 Building Operations. This site was located adjacent to the 618-1 Burial Ground.

Process Description: The unit provided temporary storage for miscellaneous hazardous wastes.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: The area contained small quantities of miscellaneous waste oils, cutting lubricants, chemicals, and solvents stored in containers. In previous years, the area was used for miscellaneous radioactive and hazardous waste storage. Currently this area is used only to store miscellaneous non-hazardous solid building waste.

Closure Info: Interim: The 618-1 Burial Ground, two subsites, three consolidated sites and four co-located sites were remediated as a group. This group included WIDS sitecodes 618-1, 618-1:1, 618-1:2, 333 LHWSA, UPR-300-13, UPR-300-14, 300-110, 303-M SA, 303-M UOF and 333 ESHWSA. Parts of waste sites 300-15, 300-259 and UPR-300-17 were also remediated along with 618-1. Several facilities were built over the top of portions of the 618-1 Burial Ground after it ceased to operate. These facilities were demolished and their debris taken to the Environmental Restoration Disposal Facility (ERDF) prior to the start of the burial ground remediation project.

Field remediation activities at the 618-1 Burial Ground were performed between September 17, 2008 and September 10, 2009, in accordance with the RDR/RAWP. Approximately 47,332 metric tons (52,160 US tons) of soil and debris was excavated and disposed of at ERDF. No excavated soil was used as backfill. Waste encountered during excavation of the 618-1 waste

site consisted mostly of contaminated soil, metal pipe, crucibles, laboratory glassware, empty metal containers, and some LDR material. Twenty metal drums containing personal protective equipment (PPE) were removed from the trenches. The PPE was about 80% decomposed. Several bottles containing liquid and/or powder were also removed. One relatively large area on the south side of the burial ground was stained yellow presumably from acid leaks known to have occurred at the site.

Some land disposal restricted (LDR) materials, like lead solids contaminated with barium and chromium, were identified among the debris. The LDR material was segregated from the bulk soil and non-LDR debris for disposal. The bulk soil and non-LDR debris was sorted and segregated in the burial trenches. After sorting, the remaining bulk soil debris stockpiles were sampled to ensure that the material was in compliance with land disposal restrictions. The released stockpiled material was transported to ERDF for disposal. Land disposal restricted materials that had been segregated for treatment were transported to ERDF under a separate waste profile.

Three sites (300-15 Process Sewer, 300-259 and UPR-300-17 Metal Shavings Fire) were partially remediated with the 618-1 remedial action.

Final (2/18/2014): This group of sites are listed in the 300-FF-2 Record of Decision. Institutional Controls to maintain industrial land use are required.

Code:	340 COMPLEX	Classification:	Accepted
Names:	340 COMPLEX; 340 Radioactive Liquid Waste Handling Facility; 340 Vault	Reclassification	Final Closed Out (7/10/2015)
Type:	Storage Tank	Start Date:	1/1/1953
Status:	Inactive	End Date:	
Description:	The 340 Complex and the consolidated Unplanned Release sites have been remediated and reclassified to Final Closed Out. Demolition of above-grade portions of 340A and 3707F buildings was completed in November of 2011. Demolition of below-grade portions was completed in January 2012. The building debris were removed and disposed of at ERDF. The demolition was performed with Radiological and Industrial Hygiene controls. Residual soil contamination was left in place and backfill of both buildings is being deferred to on-going remediation of the 340 Complex. Final surveys close-out sampling and backfill will be performed as part of 300-FF-2 remediation activities. UPR-300-1, UPR-300-2, and UPR-300-11 sites are adjacent to the 340 facility. Demolition of the facility and remediation of the soil waste site includes the areas of these unplanned release sites. It is not practical to distinguish these sites from the larger site. The UPR sites (UPR-300-1, UPR-300-2 and UPR-300-11) were reclassified to Consolidated and are considered part of the 340 Complex.		

The 340 Complex was located on the east side of the 300 Area. The 340 Complex consists of buildings 340, 340-A, 340-B, 3707-F, and two office trailers. Other 340 complex systems included the 307 Retention Basins, two tanks in an underground vault, six aboveground tanks in 340A, underground transfer pipes, load-out and decontamination equipment, and instrumentation. Prior to 1963, the 340 Complex also included the 316-3 trenches, which disposed of retention process waste that met release criteria.

The 340 Building and Annex included a control room, decontamination area, mechanical equipment room, change and rest rooms, truck load-out facilities, and an operator's office. The process water, vacuum, and compressed dry-air subsystems were contained within these structures. The 340 Vault was directly east of the 340 building. It was a below-grade concrete basin, with large concrete cover-blocks. The Vault contained two 57,000-liter (15,000-gallon)

tanks, once used for primary Radioactive Liquid Waste Sewer (RLWS) storage. The 340-A building was east of the vault, and housed six 30,000-liter (8,000-gallon) above ground tanks for auxiliary RLWS storage. The tanks were vented through the Vault filter system. 304-B building was divided into east and west sections. The east section was used for RLWS load-outs by rail to the 200 Areas. The west section was used for radioactive solid waste storage and for housing the east side ventilation system. The 3707-F building contained the retention process sewer sampling equipment and controls. MO-741 was the health physics technicians' office and survey station. MO-036 was a double-wide trailer that provides offices for engineering, radiation control, and operations personnel.

Location: The 340 Complex was located inside 300 Area, east of California Street and north of the 3728 building.

Related Sites/ Structures: The 340 Complex received radioactive liquid waste from the 300 Area laboratory buildings via the 300 Area Radioactive Liquid Waste Sewer. The buildings discharging waste to the sewer include the 324, 325, 326, 327, and 329 buildings. Retention process sewer waste is generated by 324, 325, 326, 327, and the 329 buildings and discharge to the 307 Retention Basins, located in the 340 Complex.

Unplanned releases associated with this facility are UPR-300-1, UPR-300-2, and UPR-300-11.

Process Description: The 340 facility was completed in 1953 along with the initial Radioactive Liquid Waste Sewer (RLWS) piping system, the 307 Basins and the Retention Process Sewer (RPS) piping system. These systems represented an attempt to deal with radioactive effluents from several new laboratories in a modern, controlled manner. The 340/307 system was fed by pipelines from the 325, 326, 327, and 329 Buildings (and later the 308 and 325 Buildings) in a system known as the Retention Process Sewer (RPS) or the Diversion Waste System. Liquid process wastes that had the potential to be contaminated were disposed to the RPS and routed to the 307 Basins for sampling. If radioactivity was not detected above release limits, these wastes were disposed to the 307 Trenches. If levels proved to be above release limits, the effluents were pumped into the 340 Building RLWS tanks.

The 340 Complex received and sampled the 300 Area radioactive liquid waste. Waste routed by the RLWS was accumulated and stored in two underground tanks. The waste was stored for less than 90 days. It was transferred to the 200 Areas by rail car for storage and disposal. Retention process sewer waste is collected at the 340 complex in the 307 retention basins, sampled, and discharged to the process sewer. Waste exceeding discharge criteria is held for transport to the 200 Areas.

Waste Type: Soil

Waste Description: Several spills and leaks over the operational history of the 340 Complex have contributed radionuclides (such as Cesium and Strontium) and chemical waste to the soil column.

Waste Type: Process Effluent

Waste Description: The 340 Complex receives liquid effluent from 300 Area laboratories via the 300 Area Radioactive Liquid Waste Sewer and the Retention Process Sewer. The sewer effluent was collected in the 340 underground vault tanks and the 307 Retention Basins. Waste may also include organic and inorganic laboratory chemicals, acids, bases, and decontamination solutions.

Closure Info: Final (7/10/2015): The 340 Complex Buildings (340, 340A, 3707F, 340B) were demolished in 2011. Demolition of the 307 Retention Basins was completed in June 2012. The excavation was left open. Final closure surveys and backfill was deferred to the completion of the ongoing remediation of the 340 Complex. Remediation of subsurface structures and soils, and construction of the ramp for removal of the 340 underground vault began in March 2012. The 340 vault contained two 56,700 liter (15,000-gal) stainless steel tanks that were located below grade. The vault was 12.5 meters (41 ft) long, 8.8 meters (29 ft) wide and 7.6 meters (25 ft)

high. It had a lift weight of 2.3 million pounds and a transport weight of 3 million pounds. The stainless steel tanks were stabilized in place with grout. Soil around the entire vault was excavated to provide access for equipment used to lift and transport the vault to ERDF. In August 2012, approximately 2,455 bank cubic meters (BCM) (3,211 bank cubic yards [BCY]) of contaminated soils were removed and disposed at ERDF. In 2013, during the installation of the lift supports for vault removal, highly contaminated soil under the 340 Vault was identified near the vault's sump area. The vault removal was delayed to characterize the soil contamination beneath the vault. After sampling, radiological controls and shielding was put in place. The vault was removed in January 2014 and disposed in ERDF. An estimated 35,496 BCM (46,427 BCY) of soils and materials associated with the 340 facility, including vault and ramp construction, was removed.

Following vault removal, the 340 Complex excavation resumed to remove underlying contaminated soils and additional contamination found on the sidewalls of the excavation. Remediation of the 340 Complex was completed on October 13, 2014. A total of approximately 40,874 BCM (53,461 BCY) of excavated materials were removed and loaded for direct disposal at the ERDF. The maximum depth of the waste site excavation was approximately 11 meters (36 ft). Excavated materials consisted of soil, gravel, concrete, piping, and other demolition debris. The 340 Complex waste site was remediated to groundwater.

The Following Sites Were Consolidated With This Site:

Code: UPR-300-1

Names: UPR-300-1; 307-340 Waste Line Leak; 316-1A; UN-300-1

Code: UPR-300-2

Names: UPR-300-2; Releases at the 340 Facility; UN-300-2; UN-316-2

Code: UPR-300-11

Names: UPR-300-11; UN-300-11; Underground Radioactive Liquid Line Leak near 340 Facility

Code: 400-37

Classification: Accepted

Names: 400-37; Fuel Oil Tank South of 4732-B

Reclassification: None

Type: Storage Tank

Start Date:

Status: Inactive

End Date:

Description: The site is an underground fuel oil tank. There is no visual evidence of the tank on the surface. A GPR scan, done in 2008, found a tank like object 5 meters southwest of the location noted on H-4-152061.

Location: The tank is located near the southeast corner of the 4732-B building in the 400 Area.

Process Description: A temporary (inflatable) structure was used during the construction of FFTF. It was removed when the 4732-A building was erected. The tank supplied diesel fuel to a standby electric generator. The generator powered fans that inflated the temporary equipment storage facility. The inflatable building was removed in the early 1980's.

Code: 400-38

Classification: Accepted

Names: 400-38; Fuel Oil Tank East of 4722-A Building Slab

Reclassification: None

Type: Storage Tank

Start Date:

Status: Inactive

End Date:

Description: The 4722-A building has been removed. The concrete slab still remains. The waste site is an underground fuel tank that supported 4722-A. There is no visual evidence of the tank on the surface.

Location: The tank is located east and slightly south of the centerline of the demolished 4722-A building cement slab (see 400-42). It is west of the 4760 building.

Process Description: The tank adjacent to the 4722-A foundation is believed to be a heating oil tank which was buried for this building.

Code: 600-22	Classification: Accepted
Names: 600-22; UFO Landing Site	Reclassification: Final No Action (2/18/2014)
Type: Dumping Area	Start Date: 1/1/1942
Status: Inactive	End Date:

Description: The site was reclassified to Interim No Action in 1998 and to Final No Action in 2014. It appears on aerial photos as a large, asterisk-shaped area. It is a vegetation-free area that is not marked or easily distinguished on the ground from the surrounding terrain.

The vegetation in the area was removed in the 1940's to create a visual practice target for military airplanes. Some vegetation has grown back over the years and the site is not as distinct as it once was. However, the surrounding terrain has a more diverse mix of vegetation than exists in the area of the target. A pre-Hanford fence bisects part of the site. An area at the southeast corner of the site has green steel posts, but no warning signs or barricade chains are present. Within the area marked by the steel green posts is an inactive telephone pole. The site is littered with several large pieces of "practice bombs".

The site was nicknamed "UFO Landing Site" because of its appearance from the air. Its shape and the presence of dead vegetation suggest that herbicides were used to create the shape. A site visit as part of an ecological review on October 29, 1994 indicated the vegetation abnormalities appear to be caused from a combination of mechanical disturbance and a fire that occurred in 1985. There are no Hanford records of herbicides being used at this site.

Location: The site is located southwest of the former 618-9 Burial Ground and west of the 300 Area.

Waste Type: Chemicals

Waste Description: Areas with minor vegetation disturbance are scattered throughout the site, but little obvious soil disturbance is evident. The vegetation at the site shows signs of stress and appears to have been sprayed with a herbicide.

Waste Type: Ordnance

Waste Description: Bomb fragments are scattered throughout the site, but are concentrated at the site's southeastern corner. No unexploded bombs have been found in the area.

Practice bombs are constructed of thin sheet metal which can be easily bent with manual pressure and appear to be the size of 113.6 kilogram (250 pound) bombs. The items are completely hollow. There are no nose or tail fuses nor evidence of the use of spotting charges in the nose. In some cases, the items collapsed upon impact without fragmenting leaving recognizable tailfins and noses. Also, filler caps were found in the nose which were possibly used to fill the practice bombs with sand or water.

Closure Info: Interim: Bomb fragments are scattered throughout the site, but are concentrated at the site's southeastern corner. No unexploded bombs have been found in the area. Practice bombs are

constructed of thin sheet metal which can be easily bent with manual pressure and appear to be the size of 113.6 kilogram (250 pound) bombs. The items are completely hollow. There are no nose or tail fuses nor evidence of the use of spotting charges in the nose. In some cases, the items collapsed upon impact without fragmenting leaving recognizable tailfins and noses. Also, filler caps were found in the nose which were possibly used to fill the practice bombs with sand or water.

Based on aerial photographs that were available and a surface topographic map, the sample points were selected prior to going to the field. The locations were visually confirmed by the samplers prior to sampling. A sample location on the outer edge of one of the "spokes" was selected for the first sample location. The remnants of a fence line to the south, as shown on the topographical map, and a distinct break in the vegetation growth pattern on the north suggested that the correct location had been found. In addition, the area of the spoke had a slightly raised appearance. Upon arriving at the location of the center of the site, the second sample location, the samplers observed the surrounding area. The surface appeared to be physically disturbed, as the surface soils had been removed leaving a surface of scattered gravels. Vegetation has grown up amongst the gravels. To the north, it appeared as though the surface dirt had been piled up or pushed into several areas. To the west and northwest, the faint outlines of at least two other spokes could be inferred by changes in the vegetation patterns. In the center of the area, which was chosen as the sample location, an area had a raised "pitcher's mound" appearance much like a bull's-eye for a target. The area was surveyed. Approximately 8 to 10 remnants of dummy bombs were found to the west and southwest of the sampling location. These remnants ranged from pieces of rusted sheet metal to bombs that were almost completely intact; several had tail fins, nose cone, and other distinct features clearly visible. Several photographs were taken of the bomb fragments. On August 17, 1995, sampling was completed at the 600-22 site (the UFO Landing Site) and the indicate that all herbicide values were nondetects and not near MTCA Method B limits; gross alpha and beta values were typical of background values. Values typical of background, found in the Phase I RI report for the 300-FF-2 Operable Unit.

Final (2/18/2014): The group of sites is listed in the 300-FF-2 Record of Decision and meet the criteria for unrestricted landuse.

Code: 600-46	Classification: Accepted
Names: 600-46; Cutup Oil Dump	Reclassification: Final Closed Out (2/18/2014)
Type: Dumping Area	Start Date:
Status: Inactive	End Date: 1/1/1995
Description:	The waste site was remediated and Closed Out in 1995. It was considered to be Final Closed Out in 2014. It was a small patch of oil-stained sand littered with used oil filters. Other debris included an empty can of starting fluid., an empty 208-liter (55-gallon) drum and scattered pieces of wood.
Location:	This site was located on the west bank of the Columbia River, west of the south end of Wooded Island, and south of United States Geological Survey marker "Cutup." The site was approximately 5 kilometers (3 miles) north of the 300 Area. The site was on a terrace overlooking the river, approximately 25 meters from the river.
Related Sites/Structures:	Based on the physical makeup of the site, DOE-RL, EPA, and Ecology believed that this area once contained a diesel pump used for irrigation purposes.
Process Description:	The site's prior use was related to the pre-history of Hanford. The presence of irrigation piping and valving confirmed the conclusion that the site's prior use was irrigation related.
Waste Type:	Misc. Trash and Debris

Waste Description:	The site contained wood debris.
Waste Type:	Barrels/Drums/Buckets/Cans
Waste Description:	The site contained one empty 208-liter (55-gallon) drum.
Waste Type:	Chemicals
Waste Description:	The site contained used diesel oil filters, an empty can of starting fluid, pieces of lumber, and an empty 208-liter (55-gallon) drum (Summary sentence applies to waste records 1, 2, and 3.). It was the consensus of DOE-RL, EPA, and Ecology that the only potential contaminants involved with past use of the site were total petroleum hydrocarbons (TPH), polychlorinated biphenyls (PCBs), and possibly lead, cadmium and chromium. Following sampling, only PCBs and TPH were found. Approximately, 10 cubic meters (13 cubic yards) of soil were removed from the site. On August 16, 1995, 84 waste drums containing the PCB-contaminated soil removed from the site were shipped offsite to a waste transfer company for ultimate disposal to a Toxic Substances Control Act landfill.
Closure Info:	Interim: On June 15, 1995, cleanup actions began with the removal of the miscellaneous surface debris, including a section of irrigation pipe and valving which was found just north of the oil stained area. On June 20, 1995, sampling and removal of oil-stained soil was initiated. Miscellaneous surface debris and approximately 10 cubic meters of soil contaminated with petroleum hydrocarbons and polychlorinated biphenyls (PCBs) were removed from the site. Field screening and laboratory analytical results indicated that the excavated soils were contaminated with PCBs at levels up to 55 parts per million (ppm) and TPH levels up to 350 parts per million. No other contaminants were detected above natural background levels. On August 16, 1995, 84 waste drums containing the PCB-contaminated soil removed from the site were shipped off site to a waste transfer company for ultimate disposal to a Toxic Substances Control Act (TSCA) landfill. Following cleanup activities, the site was revegetated with native shrubs and grasses. Final (2/18/2014): This group of sites is listed in the 300-FF-2 and 300-FF-5 Records of Decision and the 300-FF-1 ROD Amendment as requiring no further action. They were reclassified to Final Closed Out in February 2014 on reclassification form 2014-009.

Code:	600-47	Classification:	Accepted
Names:	600-47; Dumping Area North of 300-FF-1	Reclassification	Final Closed Out (2/18/2014)
Type:	Dumping Area	Start Date:	
Status:	Inactive	End Date:	
Description:	The site has been remediated and interim closed out. This site consisted of several areas of debris and Underground Radioactive Material Areas.		
Location:	This site was located north of the 300 Area above the bank of the Columbia River west of Johnson Island.		
Related Sites/ Structures:	The 600-210 Outfall Structure and pipeline are also located in this area.		
Waste Type:	Misc. Trash and Debris		
Waste Description:	Debris found at the site includes concrete, brick, cinder block, glass, stainless steel, steel millings/filings, plastic, tar roofing paper, wire, pipe, bottles, sheet metal, screen, clay pipe,		

irrigation pipe, etc. Concreted soils were found during test diggings, burned wood was found on top of the rise. A "Danger Area" sign was located on the ground just north of the rise. A photo of the area from 1950 shows soil disturbance in the area.

Closure Info: Interim (8/25/2005): Debris found at the site included wood, concrete, bricks, glass, steel, plastic, paper, wire, piping, broken bottles, and clay pipe. Contaminated material identified in field surveys included four areas of soil, wood, nuts, bolts, and other metal debris. The four areas of contaminated soil and debris were covered with approximately 0.6 to 0.9 meters (2 to 3 ft) of soil for surface stabilization. The area within and around the 600-47 waste site is considered culturally sensitive based on proximity to the river and the historical location of the pre-Hanford Fruitvale community. Some of the debris at the site may have pre-dated Hanford Site operations.

Remedial action activities at the 600-47 site began in December 2004. The site was divided into seven subareas, based on observed occurrences of contamination. Material in the radiologically posted and surface stabilized subareas (1, 3, 5, and 7) was sorted as it was excavated and stockpiled within the area of contamination pending sampling and subsequent disposal. Excavated material consisted of contaminated soil and small quantities of metal shavings and miscellaneous construction-type debris. No land disposal restriction materials (e.g. lead solids), anomalies, or liquid wastes were identified in the bulk soil and debris during the excavation process. In addition to the remedial action activities performed in radiologically posted areas, visible surface debris was removed by hand from the unposted, nonstabilized subareas (2,4,6). Remedial action excavation was completed in February 2005. Approximately 2,159 metric tons (2,380 U.S. tons) of material from the site were removed and disposed of at ERDF.

The cleanup verification package, CVP-2005-00005, documented that the site has been remediated in accordance with the Record of Decision for the 300-FF-2 Operable Unit (ROD), as modified by the Explanation of Significant Differences for the 300-FF-2 Operable Unit Interim Record of Decision (ESD). Remedial action objectives and goals established for the site in the ROD and ESD are reflected in the Remedial Design Report/Remedial Action Work Plan for the 300 Area (RDR/RAWP).

The contaminated excavation materials were disposed at the Environmental Restoration Disposal Facility (ERDF) in the 200 Area of the Hanford Site, and the site was backfilled with clean soil to the average adjacent grade elevation. Cleanup objectives were based on the 300 Area unrestricted land-use scenario established by the ESD. Excavation was driven by remedial action objectives for direct exposure, protection of groundwater, and protection of the Columbia River.

Final (2/18/2014): This group of sites are considered Final Closed Out in the 300-FF-2 Record of Decision and meet the criteria for Unrestricted Landuse.

Code: 600-63	Classification: Accepted
Names: 600-63; Buried Waste Test Facility; BWTF; Recharge Study Site; Vadose Zone Field Study - 300 North; VZFS300N; 300-N Lysimeter Area	Reclassification: None
Type: Experiment/Test Site	Start Date: 1/1/1984
Status: Active	End Date: 1/1/1994
Description: The site is enclosed within a chain link fence with barbed wire top and a locked gate. The fenced area is posted with "Restricted Area - Contact PNL Radiological Office" and "Underground Radioactive Material" signs. Outside the fence there is a considerable amount of debris. Two large wooden cabinets, pallets, piping and a fire extinguisher were noted.	

Location: The unit is located southeast of 400 Area, west of Route 4 South. It is southeast of the 618-10 Burial ground.

Related Sites/ Structures: The site is associated with 600-259. In 1999, programmatic responsibility for the lysimeter site was split between PNNL and ERC. PNNL retained responsibility for the active Buried Waste Lysimeter (see 600-63). The inactive Grout Waste Lysimeter facility and the Special Waste Form lysimeter were transitioned to the Environmental Restoration Contractor. A chain link fence had been previously added to physically separate the active portion of the site from the inactive portion.

Process Description: The Buried Waste Test Facility is located in the northeast corner of the fenced area. A solar panel, some metal scaffolds and a concrete cover are visible. In 1998, the west side of the site had a large amount of blown-in tumbleweeds collected along the fence. The tumbleweeds had been removed before the 1999 site visit. The BWTF was established in 1978 to investigate recharge and radionuclide migration in Hanford soil. Six drainage lysimeters (7.6 meters deep) and two weighing lysimeters (1.5 meters deep) were installed. A trace amount of Co-60 was mixed in one centimeter of soil and placed 60 centimeters below the surface of two of the drainage lysimeters. Trace amounts of tritium was placed in two other lysimeters. The migration of the contaminants was monitored. The columns were sampled in 1990. No tritium or cobalt was found at the 180 centimeter level using hand-held instruments and field level screens.

Waste Type: Soil

Waste Description: A trace amount of Co-60 was mixed in one centimeter of soil and placed 60 centimeters below the surface of two of the drainage lysimeters. Trace amounts of tritium were placed in two other lysimeters. The migration of the contaminants was monitored.

Code: 600-243 **Classification:** Accepted

Names: 600-243; Bioremediation Pad Inside Gravel Pit #6; Oil Contaminated Soil; Petroleum Contaminated Soil Bioremediation Pad; Pit 6 **Reclassification:** Final Closed Out (2/18/2014)

Type: Surface Impoundment **Start Date:**

Status: Inactive **End Date:**

Description: The site has been remediated and Interim Closed Out. It was a treatment facility for petroleum contaminated soil. It was a rectangular shaped area, 48.5 meters (159 feet) long by 38.7 meters (127 feet) wide. A 0.9 meters (3 foot) berm surrounds the site. The site was lined with heavy black plastic. The contaminated soil had visible rust stains and pieces of clear plastic mixed into the soil. Tumbleweeds and cheatgrass were growing on the surface. No petroleum odors were observed at the site. The site is posted Keep Out - Petroleum Contaminated Soil - For Entry Contact 376-7053 and WIDS Site 600-243.

Location: The site is located approximately 300 meters (984 ft) west of the 300 Area and south of a dead end dirt road that heads west from Route 4 South. The site boundaries as identified in the remedial action design drawing are E593130.19, N116110.00; E593125.56, N116156.22; E593181.25, N116158.01; E593179.63, N116118.95.

Related Sites/ Structures: The bioremediation pad is located within the original boundaries of Gravel Pit #6 (site code 600-244).

Process Description: The site was used as a bioremediation pad for petroleum-contaminated soils. The soil originated from remediation activities performed in 1994 as part of the L-044 Project. The project generated contaminated soils during the removal of underground storage tanks at the 300 Area Fire Station (300-5) and in the 1100 Area. Petroleum tanks removed from these areas during the

L-044 project included those that stored gasoline, diesel and waste oil. Moisture and nutrients were periodically added to the site to facilitate bioremediation of the hydrocarbons. Eight samples were collected in 1995 and analyzed for gasoline, diesel, and heavy oils. Eleven samples were collected in 2001 and analyzed for diesel and heavy oils. The results indicated that the soil still exceeded Model Toxics Control Act (MTCA) 1996 Method A cleanup levels for soil (200 mg/kg TPH based on protection of groundwater). Motor oil range hydrocarbons were detected as high as 3700 mg/kg. Diesel range hydrocarbons were not detected.

Waste Type: Soil

Waste Description: The waste is petroleum contaminated soil from Project LO-44, Underground Storage Tank Removals. The contaminants of potential concern (COPCs) for the 600-243 waste site were petroleum hydrocarbons in the diesel and motor oil ranges, benzo(k)fluoranthene, chrysene, fluoranthene, benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, dibenzo(a,h)anthracene, indeno(1,2,3-cd)pyrene, PCBs, and lead.

Closure Info: Interim (11/7/2008): The 600-243 waste site was remediated in August 2007. Approximately 2,134 BCM (2,791 BCY) of soil and plastic was removed via direct loadout and disposed to the Environmental Restoration Disposal Facility (ERDF). Visual observation of the area surrounding the 600-243 waste site established that this area was used for placement of coal ash. As expected based on the geophysical investigation and observations of the soil surrounding the waste site, a significant amount of coal ash was found below the plastic liner of the waste site during remediation. A Global Positioning Environmental Radiological Surveyor (GPERS) with instrumentation specific to the detection of radiation associated with beta- and gamma-emitting radionuclides was used to perform final radiological surveys of the site after remediation.

The Remaining Sites Verification Package (RSVP-2007-033) demonstrates that the 600-243 petroleum-contaminated soil bioremediation pad meets the objectives for interim closure as established in the Remedial Design Report/Remedial Action Work Plan for the 300 Area (RDR/RAWP) and the Interim Action Record of Decision for the 300-FF-2 Operable Unit, (ROD). While a limited sampling of surrounding coal ash was undertaken, a full evaluation of the coal ash underlying and surrounding the waste is outside the scope of this remaining sites verification package. Radiological field surveys were performed to ensure that radiological contamination was not present at the waste site.

A comparison against ecological risk screening levels was made for the site contaminants of concern and other constituents. Screening levels were exceeded for antimony, barium, boron, cadmium, copper, lead, manganese, selenium, vanadium, and zinc. Exceedance of screening values does not necessarily indicate the existence of risk to ecological receptors. Because concentrations of antimony, manganese, and vanadium are below Hanford Site background levels, it is believed that the presence of these constituents does not pose a risk to ecological receptors. The remaining metals that exceed ecological risk screening levels are due to coal ash, which is ubiquitous in the general area of the 600-243 waste site. The bioremediation pad had been placed directly on coal ash, and the verification sample results reflect the composition of the coal ash. A more complete quantitative ecological risk assessment will be presented in the baseline risk assessment for the river corridor portion of the Hanford Site and will be used to support the final closeout decision for this site.

Final (2/18/2014): The group of sites were reclassified to Final Closed Out in 2014. They are listed in the 300-FF-2 Record of Decision and meet the criteria for unrestricted landuse.

Code: 600-259

Classification: Accepted

Names: 600-259; Grout Waste Test Lysimeter; Inactive Lysimeter Site East End; Special Waste Form

Reclassification: Final Closed Out (2/18/2014)

Lysimeter

Type: Experiment/Test Site **Start Date:** 1/1/1984

Status: Inactive **End Date:** 1/1/1994

Description: The entire site has been remediated and interim closed out. The waste site consisted of The Grout Waste Test Facility (subsite 1) which was exhumed in 1994. The Special Waste Form lysimeter (subsite 2) was remediated in 2005.

Location: The unit was located southeast of 400 Area, just west of Route 4 South. It was southeast of the 618-10 Burial ground.

Release Description: On January 25, 1991, it was concluded that the lysimeter may have been damaged during backfilling causing a reportable quantity of effluent to leak into the soil. It was estimated that over a 3 year period, as much as 300 liters of contaminated liquid may have leaked. It was noted that one of the Grout Waste Test Facility lysimeter caissons (B1) was not collecting recharge water. The caisson was not exhumed to determine the cause, but it was speculated that the weld at the bottom of the caisson had been compromised when it was filled with gravel. It was decided that the buried caisson had probably leaked into the underlying sediments, contaminating them with radioactive materials. The release was estimated to have occurred over a 3 year period. The maximum concentration of contaminants in the sediments was estimated to be 6E-05 microcuries/milliliter to 1.3E-04 microcuries/milliliter of Technetium-99. When the Grout Lysimeter Facility was removed in September 1994, extensive sampling was conducted for all constituents identified in the caissons. Background samples were collected and compared to the sample results. It was concluded that no radiological constituents had leaked from either caisson during the lysimeter test. Although there was clear evidence that the B1 Lysimeter did have a large seam weld crack at the bottom, the leak contained only atmospheric moisture. No final report was issued for the sample analysis due to

Related Sites/ Structures: The site was associated with 600-63 and a 1991 Occurrence Report indicating an unplanned release to the soil may have occurred (RL--PNNL-PNLBOPER-1991-0018) at the Grout Waste Test Facility.

Process Description: The lysimeters were designed to test the leaching and migration rates of grout solidified low level radioactive waste. Routine monitoring and leachate collection activities were conducted until January 1989.

Waste Type: Soil

Waste Description: The Special Waste Form lysimeter contained masonry cement, Portland cement and vinyl ester styrene waste forms spiked with Mn-54, Co-60, Cs-134 and Cs-137. The waste forms were placed into the lysimeters at various depths. The leachate was collected and disposed of. The research was completed in 1992. The lysimeters were capped in 1995 to prevent any further water intrusion. The leachate was drained for the last time by PNNL in 1996.

Waste Type: Soil

Waste Description: The Grout Waste Lysimeter caissons (A-1 and B-1) contained layers of waste, containing small amounts of both radioactive and non-radioactive tracer agents embedded into grout material. The waste layers were separated by layers of soil. The lysimeter caissons were buried below ground. The radioactive tracers used in this test were primarily Co-60 (up to 330 Ci/L) and lesser amounts of Cobalt-58, Iron-59, Chromium-51 and Manganese-54.

Closure Info: Interim: The Grout Waste Test Facility (subsite 1) which was exhumed in 1994. The Special Waste Form lysimeter (subsite 2) was remediated in 2005. The remedial action was conducted from September 2004 through July 2005. Remedial action at the 600-259:2 site was conducted from September 2004 to July 2005. Excavation of the site included the removal of all caisson structures and radioactive waste forms. Overburden material was segregated and stockpiled for possible use as backfill material pending the results of verification sampling. No anomalies

were identified within the bulk soil and debris during remedial activities, and no indications of liquid waste migration beyond the caisson units were observed. Approximately 950 metric tons (1,050 U.S. tons) of material was removed for disposal at ERDF.

The Cleanup Verification Package for the 600-259 Waste Site (CVP-2005-00008), demonstrated that the waste site was remediated in accordance with the Record of Decision for the 300-FF-2 Operable Unit, Hanford Site (ROD), as modified by the Explanation of Significant Differences for the 300-FF-2 Operable Unit Interim Record of Decision (ESD). Remedial action of both subsites has achieved the remedial action objectives (RAOs) and remedial action goals (RAGs) established in the Remedial Design Report/Remedial Action Work Plan for the 300 Area (RDR/RAWP).

Remedial action was conducted from September 2004 to July 2005. Excavation of the site included the removal of all caisson structures and radioactive waste forms. Overburden material was segregated and stockpiled for possible use as backfill material pending the results of verification sampling. No anomalies were identified within the bulk soil and debris during remedial activities, and no indications of liquid waste migration beyond the caisson units were observed.

Approximately 950 metric tons (1,050 U.S. tons) of contaminated material was removed and disposed of at the ERDF. The remaining soil was sampled, analyzed, and evaluated. Results indicated that the site supports future land uses that can be represented (or bounded) by an unrestricted land-use scenario and that residual concentrations throughout this site pose no threat to groundwater or the Columbia River.

The 600-259 (subsites 1 and 2), waste site has been verified to be remediated in accordance with the ROD and the ESD and may be backfilled.

Final (2/18/2014): This group of sites are considered Final Closed Out in the 300-FF-2 Record of Decision and meet the criteria for Unrestricted Landuse.

This Site has the Following SubSites:

Code: 600-259:1

Names: 600-259:1; Grout Waste Test Facility Lysimeter

Code: 600-259:2

Names: 600-259:2; Special Waste Form Lysimeter

Code: 600-259:1

Classification: Accepted

Names: 600-259:1; Grout Waste Test Facility Lysimeter

Reclassification: Final Closed Out (2/18/2014)

Type: Experiment/Test Site

Start Date:

Status: Inactive

End Date:

Description: The lysimeters were exhumed in September 1994. The Grout Waste Test Facility consisted of four large lysimeters designed to test the leaching and migration rates of grout solidified low level radioactive waste. The four caissons were placed vertically in the ground, forming a square. The four lysimeters were designated as A1, A2, B1 and B2. A2 and B2 were never used. Lysimeter A1 contained phosphate/sulfate waste and B1 contained Cladding Removal Waste. Twenty four radioactive waste forms were placed on each lysimeter. The waste forms were placed in layers, separated by soil and gravel. Routine monitoring and leachate collection activities were conducted until January 1989.

Location: The unit is located southeast of 400 Area, just west of Route 4 South. It is southeast of the 618-10 Burial ground, and adjacent to 600-63.

Process Description: The lysimeters were designed to test the leaching and migration rates of grout solidified low level radioactive waste. Routine monitoring and leachate collection activities were conducted until January 1989.

Closure Info: Interim: The Grout Waste Test Facility (subsite 1) which was exhumed in 1994. The Special Waste Form lysimeter (subsite 2) was remediated in 2005. The remedial action was conducted from September 2004 through July 2005. Remedial action at the 600-259:2 site was conducted from September 2004 to July 2005. Excavation of the site included the removal of all caisson structures and radioactive waste forms. Overburden material was segregated and stockpiled for possible use as backfill material pending the results of verification sampling. No anomalies were identified within the bulk soil and debris during remedial activities, and no indications of liquid waste migration beyond the caisson units were observed. Approximately 950 metric tons (1,050 U.S. tons) of material was removed for disposal at ERDF.

The Cleanup Verification Package for the 600-259 Waste Site (CVP-2005-00008), demonstrated that the waste site was remediated in accordance with the Record of Decision for the 300-FF-2 Operable Unit, Hanford Site (ROD), as modified by the Explanation of Significant Differences for the 300-FF-2 Operable Unit Interim Record of Decision (ESD). Remedial action of both subsites has achieved the remedial action objectives (RAOs) and remedial action goals (RAGs) established in the Remedial Design Report/Remedial Action Work Plan for the 300 Area (RDR/RAWP).

Remedial action was conducted from September 2004 to July 2005. Excavation of the site included the removal of all caisson structures and radioactive waste forms. Overburden material was segregated and stockpiled for possible use as backfill material pending the results of verification sampling. No anomalies were identified within the bulk soil and debris during remedial activities, and no indications of liquid waste migration beyond the caisson units were observed.

Approximately 950 metric tons (1,050 U.S. tons) of contaminated material was removed and disposed of at the ERDF. The remaining soil was sampled, analyzed, and evaluated. Results indicated that the site supports future land uses that can be represented (or bounded) by an unrestricted land-use scenario and that residual concentrations throughout this site pose no threat to groundwater or the Columbia River.

The 600-259 (subsites 1 and 2), waste site has been verified to be remediated in accordance with the ROD and the ESD and may be backfilled.

The SubSite is Part Of:

Code: 600-259

Names: 600-259; Grout Waste Test Lysimeter; Inactive Lysimeter Site East End; Special Waste Form Lysimeter

Code: 600-259:2

Classification: Accepted

Names: 600-259:2; Special Waste Form Lysimeter

Reclassification: Final Closed Out (2/18/2014)

Type: Experiment/Test Site

Start Date:

Status: Inactive

End Date:

Description: The Special Waste-Form Lysimeter was constructed in the summer of 1983 and consisted of ten soil filled caissons (1.83 meters [6 feet] in diameter by 3.05 meters [10 feet] deep) placed concentrically around a central access caisson that measured 3.65 meters (in diameter, 3.65 meters deep). Each lysimeter is equipped with a gravity drain attached to the central caisson for

leachate collection. The central caisson also provides access to the ten lysimeters through horizontal sample ports. A 15 centimeter diameter monitoring well is installed adjacent to each lysimeter caisson to allow for downwell gamma scanning and neutron probe measurements of the caissons. Each of the ten lysimeter caissons contains one waste-form sample that is in direct contact with the soil. Samples of commercial reactor waste was obtained and solidified in cement, bitumen or vinyl-ester styrene to create a waste form. Information was collected regarding the amount and types of contaminants that leached into the soil over time. Test data was collected between 1984 and 1992.

Location: The unit is located southeast of 400 Area, just west of Route 4 South. It is southeast of the 618-10 Burial ground, and adjacent to 600-63.

Process Description: Samples of commercial reactor waste were obtained and solidified in cement, bitumen or vinyl-ester styrene to create a waste form. Information was collected regarding the amount and types of contaminants that leached into the soil over time. Test data were collected between 1984 and 1992.

Closure Info: Interim: The Grout Waste Test Facility (subsite 1) which was exhumed in 1994. The Special Waste Form lysimeter (subsite 2) was remediated in 2005. The remedial action was conducted from September 2004 through July 2005. Remedial action at the 600-259:2 site was conducted from September 2004 to July 2005. Excavation of the site included the removal of all caisson structures and radioactive waste forms. Overburden material was segregated and stockpiled for possible use as backfill material pending the results of verification sampling. No anomalies were identified within the bulk soil and debris during remedial activities, and no indications of liquid waste migration beyond the caisson units were observed. Approximately 950 metric tons (1,050 U.S. tons) of material was removed for disposal at ERDF.

The Cleanup Verification Package for the 600-259 Waste Site (CVP-2005-00008), demonstrated that the waste site was remediated in accordance with the Record of Decision for the 300-FF-2 Operable Unit, Hanford Site (ROD), as modified by the Explanation of Significant Differences for the 300-FF-2 Operable Unit Interim Record of Decision (ESD). Remedial action of both subsites has achieved the remedial action objectives (RAOs) and remedial action goals (RAGs) established in the Remedial Design Report/Remedial Action Work Plan for the 300 Area (RDR/RAWP).

Remedial action was conducted from September 2004 to July 2005. Excavation of the site included the removal of all caisson structures and radioactive waste forms. Overburden material was segregated and stockpiled for possible use as backfill material pending the results of verification sampling. No anomalies were identified within the bulk soil and debris during remedial activities, and no indications of liquid waste migration beyond the caisson units were observed.

Approximately 950 metric tons (1,050 U.S. tons) of contaminated material was removed and disposed of at the ERDF. The remaining soil was sampled, analyzed, and evaluated. Results indicated that the site supports future land uses that can be represented (or bounded) by an unrestricted land-use scenario and that residual concentrations throughout this site pose no threat to groundwater or the Columbia River.

The 600-259 (subsites 1 and 2), waste site has been verified to be remediated in accordance with the ROD and the ESD and may be backfilled.

The SubSite is Part Of:

Code: 600-259

Names: 600-259; Grout Waste Test Lysimeter; Inactive Lysimeter Site East End; Special Waste Form Lysimeter

Code: 600-290 **Classification:** Accepted
Names: 600-290; Contaminated Concrete Foundation **Reclassification** Final Closed Out (5/12/2014)
 West of 618-13; Pad and Loading Dock Near 618-13; 300 West Storage Area
Type: Foundation **Start Date:** 1/1/1947
Status: Inactive **End Date:** 1/1/1950

Description: Both subsites have been reclassified. In 2014, the subsites were reclassified to Final Closed Out and Final No Action. Therefore the parent site is considered Final Closed Out. The foundation and loading dock were remediated in 2009. Prior to remediation, the concrete pad had been posted as a radiological fixed contamination area. The site consists of two subsites. Subsite 1 included the contaminated foundation and loading dock. It was remediated and Interim Closed Out. Subsite 2 is the rest of the waste site boundary and is known as the 300 West Storage Area. It was evaluated and determined to be a No Action site.

Location: The concrete foundation had been located due west of 300 Area, at the end of a gravel road. It is approximately 730 meters (0.45 miles) west of Stevens Drive.

Related Sites/ Structures: The concrete foundation is associated with the excavated 618-9 burial ground, the 618-13 soil mound and the 321 building.

Process Description: The 300 Area was constructed between June 1943 and January 1945. At that time, the area surrounding the 600-290 waste site was inconspicuous except for a dirt road that ran along the north side of the gravel pit. A 1948 aerial photograph (IDMS-N2139826) shows a disturbed tear drop shaped area similar to the present condition. Two structures are visible in the photograph. One is at the center of the tear drop shape and the other borders the dirt road on the north side. The structure to the north is surrounded by a square feature resembling a fence. WHC-MR-0388 states that a 500 gallon Columbian stainless steel tank and several agitators, used by Du Pont in the early 321 Building bismuth phosphate tests, was buried in 1947 west of 300 Area. The area west of 300 Area was later used to bury solvent waste from 321 Building. The burial site (618-9) is known as the "300 West Burial Ground" and the "Dry West Burial Site No. 9". Dried hexone from solvent extraction studies in the 321 Building was placed in black iron drums and moved to a fenced storage area near the desert dry chemical storage hut in March 1950 (HW-17410). The 321 Building sustained significant damage from a hexone explosion on January 23, 1949 (HW-13812). The facility management would have been particularly sensitive to the dangers of hexone following the explosion. The location of this remote area was ideal for storing dangerous materials, away from buildings and personnel. In October 1950 all hexone from the 321 Building tanks was removed to provide room for the less-flammable Shell Deodorized Spray Base Solvent. The hexone was dried and stored in black metal drums for use in subsequent Redox studies (HW-15843 and HW-19325). Top soil from the 303 Area was removed in 1950 and piled approximately one-half to three quarters of a mile northwest of the 300 Area, and covered with two feet of clean soil. Total activity buried here is not known. The 618-13 soil mound of covered contaminated material has been posted as a radiation zone (HW-39076). This waste site, is visible in aerial photographs as early as April 30, 1951 (350-NEG). Contaminated soil was reportedly found inside the 300 Area, on October 23, 1950, during construction of the new Instrument Division Building. The new building was being located between the existing Instrument Shop and the Metal Fabrication Plant (313 Building). The activities involved excavating the earth around two existing tile pipe lines (one sanitary and one liquid process waste line from the Metal Fabrication Plant). The incident report (DDTS-Generated-3822) speculated that the contaminated soil was from a wooden French Drain or crib installed on this site in 1944 to temporarily receive wastes from experimental autoclaves. The soil had a maximum dosage-rate of 50 mrep/hr (HW-19325). Facility personnel, in 1971, identified the soil mound (618-13) as the location that received soil from the excavation near the 313 Building (in 1952) (Richmond 1971). The evidence from

aerial photographs and historical documents appears to indicate that the soil mound was constructed shortly after October 23, 1950. The facility personnel, in 1971, also described the earth mound as having been constructed to serve as a blast shield for any explosions which might result from solvent storage in the [300-W] Equipment Storage Yard. The 1951 training manual for the 321 Building identified one of the related facilities as the "300 West Area Storage for chemicals and solvents" (HW-19791). Aerial photography from this period shows only one location (near the mound) fitting this description. An aerial photograph (2406-PHOTO), dated December 1, 1953, has features that resemble objects contained in a fenced area north of the soil mound. This is the same location where a square feature resembling a fence was observed in a 1948 aerial photograph (IDMS number N2139826). It appears that the dry chemical storage was located just north of the 600-290 waste site, near the location of the 300 West Burial Ground (618-9). The 300 West Burial Ground was constructed in June 1954 when about 18,927 liters (5,000 gallons) of solvent waste from the 321 Building, contained in 208 liter (55 gallon) drums, was buried and covered with about 1.2 meters (4 feet) of clean soil (HW-39076). The burial ground is also described in document WHC-MR-0388. This report states that nearly 100 drums that had been generated in 1949 to 1950. The drums were stored on an outdoor pad for nearly 5 years. The drums were later placed in the 300 West Burial Ground (sitecode 618-9). The fence that surrounded the soil mound (618-13) is visible in a May 15, 1956 aerial photograph (3746-PHOTO). Two large structures are also visible in the photograph that resemble huts. The area (fence, roads, storage buildings and earth barricade) is depicted in drawing M-3600 sheet 46, originally drawn in 1958. The mound, fence, hutments and various objects inside the fence are also visible in aerial photographs taken in 1962 and 1968 (29033 and 48300-20-CN). The fenced area is identified in the 1975 Final Environmental Statement (ERDA-1538) as a "Contaminated Equipment Storage Area". This report states that all of the equipment had been removed and that the ground was slightly contaminated. The purpose of the concrete pad and loading dock was described in the 300-FF-2 Operable Unit Technical Baseline Report (Reference: Appendix A of BHI-00012, Letter from Keene, A. R., 02/03/1961, "Burial of Solid Wastes in the Vicinity of the 300 Area"). The report states that the pad and dock were used for the storage of depleted solvents that were subsequently buried in the nearby 618-9 burial ground. The soil mound, and the pad and loading dock, was all that remained by 1976 (aerial photograph 74962-11CN). The fence, hutments and fenced in objects had all been removed.

Waste Type: Chemical Release

Waste Description: The waste is the remains of the concrete pad (apron), the loading dock and surrounding soil. The loading dock was obviously stained with rust colored and yellow staining. Contaminants of potential concern may include uranium and nitric acid (uranyl nitrate). Volatile organic compounds (including hexone), semi-volatile organic compounds, polychlorinated biphenyls, chlorinated hydrocarbons, and lead. Five areas of fixed radiological contamination were identified during a radiological survey on 5/1/2006 (RSR-300PS-06-0808).

Closure Info: Final (5/12/2014): 600-290:1 was remediated with waste sites 300 VTS, 300-8, 600-243. 618-7, 618-9, 618-13 in 2006. In 2014, the group of sites was reclassified to Final Closed Out.

The 600-290:2, 300 West Storage Area waste subsite consisted of the remaining areas within the 600-290 waste site boundary, excluding the previously remediated 618-13 Burial Ground waste site and the 600-290:1 subsite. The majority of the 600-290:2 area was enclosed by a fence and was used for storage of contaminated equipment. Confirmatory sampling of the 600-290:2 subsite was performed on April 3, 2012. Samples were collected up to 1 meters (3.3 ft) below ground surface to account for revegetation work performed after the previous remediation.

The 600-290:2 subsite has been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). Previous sampling results show that the concentrations of COCs meet the CULs for direct exposure and groundwater protection

and river protection and support a residential land use scenario. Institutional controls to prevent uncontrolled drilling or excavation into the deep zone are not required. In accordance with this evaluation, the previous sampling results support a reclassification of the 600-290:2 subsite to Final No Action.

This Site has the Following SubSites:

Code: 600-290:1

Names: 600-290:1; Contaminated Concrete Foundation West of 618-13; Pad and Loading Dock Near 618-13

Code: 600-290:2

Names: 600-290:2; 300 West Storage Area

Code: 600-290:1

Classification: Accepted

Names: 600-290:1; Contaminated Concrete Foundation West of 618-13; Pad and Loading Dock Near 618-13

Reclassification: Final Closed Out (2/18/2014)

Type: Foundation

Start Date:

Status: Inactive

End Date:

Description: This subsite has been remediated and was Interim Closed Out. In 2014, the subsite was reclassified to Final Closed Out. A gravel road leads to the concrete pad on the north side of the soil mound. The area was designed to allow a truck to back up onto the concrete pad adjacent to the loading dock and offload drums of waste. Circular rust colored patterns, in the size and shape as 308 liter (55 gallon) drums, suggest that drums were once stored on the loading dock. The foundation and loading dock were remediated in 2009. Prior to remediation, the concrete pad had been posted as a radiological fixed contamination area.

Closure Info: Interim: The concrete pad and loading dock were remediated in 2009. Field remediation of the 618-13 Burial Ground and the 600-290:1 concrete pad and loading dock occurred between January 5 and February 2, 2009. The activity removed the soil mound, concrete pad, and loading dock. The mound and concrete pad were removed to ground surface level. No sub-grade excavation was required. The excavated material was maintained within the waste site footprint; therefore, no staging piles were generated outside of the waste site boundary. Contaminated soil, pieces of decayed wood, and concrete were the only materials found during remediation of the site. A radiological survey of the 618-13 footprint was done on February 12, 2009. The results indicated the soil beneath the excavated mound was less than two times the background for beta-gamma radionuclides.

Cleanup Verification Package CVP-2009-00005 demonstrates that remedial action at the 618-13 Burial Ground and the collocated 600-290:1 Pad and Loading Dock Near 618-13 has achieved the remedial action objectives (RAOs) and corresponding remedial action goals (RAOs) established for the unrestricted landuse scenario in the Interim Action Record of Decision (EPA 2001), the Explanation of Significant Differences for the 300-FF-2 Operable Unit (EPA 2004), and the Remedial Design/Remedial Action Work Plan for the 300 Area (DOE/RL 2009b).

The contaminated materials from the site have been excavated and disposed at ERDF. The remaining soil at the 618-13 and 600-290:1 sites have been sampled, analyzed, and evaluated. Results indicate that the site supports future land uses that can be represented (or bounded) by the residential land-use scenario and poses no threat to groundwater or the Columbia River.

Final (2/18/2014): The group of sites were reclassified to Final Closed Out in 2014. They are listed in the 300-FF-2 Record of Decision and meet the criteria for unrestricted landuse.

The SubSite is Part Of:**Code:** 600-290**Names:** 600-290; Contaminated Concrete Foundation West of 618-13; Pad and Loading Dock Near 618-13; 300 West Storage Area**Code:** 600-290:2**Classification:** Accepted**Names:** 600-290:2; 300 West Storage Area**Reclassification** Final No Action (5/12/2014)**Type:** Foundation**Start Date:****Status:** Inactive**End Date:**

Description: This subsite was evaluated and determined to require No Action. In 2014, the subsite was reclassified to Final No Action. It included the remaining area covered by the WIDS boundary that was not addressed in subsite 1. The majority of the area had been enclosed by a fence and was used for storage of contaminated equipment. A portion of the subsite extends north of the fence where anomalies were visible in an old aerial photograph.

Process Description: The majority of the 600-290:2 area was enclosed by a fence and was used for storage of contaminated equipment.

Closure Info: Interim (7/5/2012): Confirmatory sampling for the 600-290:2 subsite was conducted on April 3, 2012, to support a determination that residual contaminant concentrations at these sites meet the cleanup criteria specified in the 300 Area RDR/RAWP (DOE/RL 2009) and the 300-FF-2 ROD (EPA 2001). Twelve statistical discrete soil samples were collected on the grid within the footprint of the site. A soil sample was collected at each of the of the identified sample locations at a depth of 0.3 meter (1 ft) to 1 meter (3 ft) below ground surface. During excavation and sampling, radiological field screening was performed as specified in the confirmatory work instruction. No radiological contamination was detected above background levels. Field screening for the presence of volatile organic compounds (VOCs) was also negative.

The confirmatory sampling and the analytical results indicate that the residual concentrations of COPCs at this site meet the remedial action objectives for direct contact, groundwater protection, and river protection. These results also indicate that residual concentrations will support future land uses that can be represented (or bounded) by a rural-residential scenario and that residual concentrations throughout the site pose no threat to groundwater or the Columbia River. Institutional controls to prevent uncontrolled drilling or excavation are not required. Accordingly, a reclassification to No Action is supported for the 600-290:2 subsite.

Final (5/12/2014): 600-290:1 was remediated with waste sites 300 VTS, 300-8, 600-243. 618-7, 618-9, 618-13 in 2006. In 2014, the group of sites was reclassified to Final Closed Out.

The 600-290:2, 300 West Storage Area waste subsite consisted of the remaining areas within the 600-290 waste site boundary, excluding the previously remediated 618-13 Burial Ground waste site and the 600-290:1 subsite. The majority of the 600-290:2 area was enclosed by a fence and was used for storage of contaminated equipment. Confirmatory sampling of the 600-290:2 subsite was performed on April 3, 2012. Samples were collected up to 1 meters (3.3 ft) below ground surface to account for revegetation work performed after the previous remediation.

The 600-290:2 subsite has been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). Previous sampling results show that the concentrations of COCs meet the CULs for direct exposure and groundwater protection and river protection and support a residential land use scenario. Institutional controls to prevent

uncontrolled drilling or excavation into the deep zone are not required. In accordance with this evaluation, the previous sampling results support a reclassification of the 600-290:2 subsite to Final No Action.

The SubSite is Part Of:

Code: 600-290

Names: 600-290; Contaminated Concrete Foundation West of 618-13; Pad and Loading Dock Near 618-13; 300 West Storage Area

Code: 618-1

Classification: Accepted

Names: 618-1; Solid Waste Burial Ground No. 1; 300 Area Burial Ground No. 1; 318-1

Reclassification: Final Closed Out (8/7/2015)

Type: Burial Ground

Start Date: 1/1/1945

Status: Inactive

End Date: 1/1/1951

Description: The 618-1 Burial Ground, two subsites, three consolidated sites and four co-located sites were remediated as a group. The sites were reclassified to Interim Closed Out in 2010 and reclassified to Final Closed Out in 2015. The group included WIDS sitecodes 618-1, 618-1:1, 618-1:2, 333 LHWSA, UPR-300-13, UPR-300-14, 300-110, 303-M SA, 303-M UOF and 333 ESHWSA. Three sites (300-15 Process Sewer, 300-259 and UPR-300-17 Metal Shavings Fire) were partially remediated with the 618-1 remedial action.

Drawing H-3-1172 shows the Burial Ground consisted of at least two trenches running north-south, that measure 5 meters (16 feet) wide by 61 meters (200 feet) long and are 2.4 meters (8 feet) deep. The south end of the burial ground contained a series of pits that are estimated to be 6.1 meters (20 feet) deep and possibly two shorter, east-west trenches. The burial ground had been marked with yellow, concrete AC-540 markers and radiation area chain on three sides. Five other Buried Radioactive Material medallions, inserted flush with the asphalt pavement along the east side of the 333 Building, marked the western extent of the burial ground. In 1998, the burial ground was located within a larger area posted as a Contamination Area. Over time, multiple facilities and portions of operational support structures were placed on top of the backfilled burial ground footprint. The 303-M Building was built over a portion of the original burial ground.

Location: The site was located in the northeast corner of the 300 Area, adjacent to the east side of the 333 Building.

Related Sites/ Structures: The burial ground is associated with early 300 Area facility operations. Several facilities had been constructed over the top of portions of the burial ground. The 303-M facility was built over the top of the north end of the west trench (Burial Trench 1). The 334 building, the 334-A building, and the 334 Waste Acid Tanks (above ground tank farm) were also placed over portions of the west side of the burial ground. WIDS SubSites 618-1:1 (aka 333 ESHTSSA) and 618-1:2 (aka Limestone Neutralization Pit) are associated with the site since they were physically located on or immediately adjacent to the burial ground. The burial ground is associated with acid releases, WIDS Site UPR-300-13 and WIDS Site UPR-300-14, and two storage areas, 333 LHWSA and 333 ESHTSSA (see the consolidated sites under the Regulatory tab). WIDS Site 300-259 (Contaminated Soil East of 618-1 Burial Ground) surrounded 618-1 Burial Ground.

Process Description: The burial ground received waste from early 300 Area facility operations, including the 305 Reactor, 3706 Laboratory and the 3741 Building. Conflicting operational dates have been cited in various documentation. HW-39076 states the operational dates of 618-1 were 1945 through 1951, when it was replaced by 618-2. Historical photograph (Negative number 2406) is dated December 1953. The 618-1 Burial Ground appears to be backfilled and inactive in this aerial

photograph. The 618-2 Burial Ground is also visible in this photograph and indicates multiple burial trenches are open and active. Other documents and letters indicate the end date for this burial ground as 1956 or 1957.

Waste Type: Misc. Trash and Debris

Waste Description: 618-1 was estimated to contain large quantities of uranium (~16 tons [14,500 kilograms]) from the fuel fabrication activities and small quantities of plutonium and fission products from laboratory operations. Specific items include contaminated gloves, miscellaneous equipment, bronze crucibles, and solid laboratory waste. A 1946 report states that lead sink traps from the 321 laboratory were removed and taken to the burial ground. Radiological readings on the sink traps indicated 6,000 d/m alpha and 15 mr/hr beta/gamma. A monthly report from August 1946 mentions the burial of a bronze crucible that read 170 millireps/hour (179 millirads/hour) and 5.5 mr/hr (millirads/hour) at a distance of 10.2 centimeters (4 inches). UPR-300-13 contributed process acid that included 4,432 pounds (2,012 kilograms) of nitrate, 447 pounds (202.9 kilograms) of copper, and 3 pounds (1.4 kilograms) of uranium. During the burial ground remediation, in 2008 and 2009, items found in the burial ground included metal drums, iron and bronze crucibles, metal boxes, glass laboratory flasks and bottles. Some of the bottles contained unknown liquids and powders. One drum was labeled Poison Waste. Some drums were leaking oily liquid.

Waste Type: Chemical Release

Waste Description: Additional waste from unplanned releases (WIDS Site UPR-300-13) from facilities that were constructed over the burial ground would have contributed additional chemicals to the soil column as a liquid release. Sample results showed that 2015 kilograms (4432 pounds) of nitric acid, 44 kilograms (96 pounds) of fluoride, 217 kilograms (477 pounds) of copper and 1.4 kilograms (3 pounds) equivalent to 0.0005 curies of uranium were lost to the ground. 870 kilograms (1910 pounds) of caustic was added to the leaking tank and allowed to leak into the soil to neutralize the acid that had escaped into the ground. The leak rate of the tank was 582.9 liters (154 gallons) per hour. A release on July 18, 1975 (WIDS Site UPR-300-14) of 4,540 liters (1,200 gallons) of 93% sulfuric acid solution from the 334 Tank Farm drained to a limestone pit (WIDS Site 300-246). Since the pit had an open bottom and was located over the 618-1 Burial Ground, the release drained to the burial ground.

Waste Type: Chemicals

Waste Description: WIDS Site 333 ESHTSSA stored above ground containers of solidified heat-treat salt waste from the fuels fabrication facility. The waste consisted of sodium chloride, potassium chloride, sodium nitrite, sodium nitrate, and potassium nitrate. Approximately, thirty to fifty 208 liter (55 gallon) drums accumulated each year (1964-1987).

Closure Info: Interim: The 618-1 Burial Ground, two subsites, three consolidated sites and four co-located sites were remediated as a group. This group included WIDS sitecodes 618-1, 618-1:1, 618-1:2, 333 LHWSA, UPR-300-13, UPR-300-14, 300-110, 303-M SA, 303-M UOF and 333 ESHWSA. Parts of waste sites 300-15, 300-259 and UPR-300-17 were also remediated along with 618-1. Several facilities were built over the top of portions of the 618-1 Burial Ground after it ceased to operate. These facilities were demolished and their debris taken to the Environmental Restoration Disposal Facility (ERDF) prior to the start of the burial ground remediation project.

Field remediation activities at the 618-1 Burial Ground were performed between September 17, 2008 and September 10, 2009, in accordance with the RDR/RAWP. Approximately 47,332 metric tons (52,160 US tons) of soil and debris was excavated and disposed of at ERDF. No excavated soil was used as backfill. Waste encountered during excavation of the 618-1 waste site consisted mostly of contaminated soil, metal pipe, crucibles, laboratory glassware, empty metal containers, and some LDR material. Twenty metal drums containing personal protective equipment (PPE) were removed from the trenches. The PPE was about 80% decomposed.

Several bottles containing liquid and/or powder were also removed. One relatively large area on the south side of the burial ground was stained yellow presumably from acid leaks known to have occurred at the site.

Some land disposal restricted (LDR) materials, like lead solids contaminated with barium and chromium, were identified among the debris. The LDR material was segregated from the bulk soil and non-LDR debris for disposal. The bulk soil and non-LDR debris was sorted and segregated in the burial trenches. After sorting, the remaining bulk soil debris stockpiles were sampled to ensure that the material was in compliance with land disposal restrictions. The released stockpiled material was transported to ERDF for disposal. Land disposal restricted materials that had been segregated for treatment were transported to ERDF under a separate waste profile.

Three sites (300-15 Process Sewer, 300-259 and UPR-300-17 Metal Shavings Fire) were partially remediated with the 618-1 remedial action.

Final (8/7/2015): No additional soil remediation was required. The uranium in the groundwater beneath the waste site will be addressed with the 300-FF-5 groundwater Operable Unit. The Final Closed Out status is documented on Waste Site Reclassification forms 2015-069, 2015-071 and 2015-072.

Basis for Reclassification:

Interim remedial actions were performed so as to allow industrial land use and to protect groundwater and the Columbia River, as described in the Cleanup Verification Packages for the 618-1 Burial Ground, CVP-2010-00010, Rev. 0, 618-2 Burial Ground, CVP-2010-00001, Rev. 0, and 618-3 Burial Ground, CVP-2010-00005, Rev. 0, Washington Closure Hanford, Richland, Washington. Previous verification sampling results were evaluated as part of development of the Hanford Site 300 Area, Record of Decision for 300-FF-2 and 300-FF-5, and Record of Decision Amendment for 300-FF-1, Hanford Site, Benton County, Washington (300 Area Final Action ROD), U.S. Environmental Protection Agency, Region 10, Seattle, Washington. The 300 Area Final Action ROD identified 618-1, 618-2 and 618-3 as three of seven 300 Area sites that had contributed to uranium groundwater contamination and, thus, associated it with the selected enhanced natural attenuation remedy component. However, the location of the 618-1 waste site is physically separate from the target treatment area and no further remediation activities were identified at the waste site location. Implementation of the broader enhanced attenuation remedy for the 300 Area will be implemented in accordance with the Remedial Design Report/Remedial Action Work Plan Addendum for the 300 Area Groundwater, DOE/RL-2014-13-ADD 2, Rev. 0, U.S. Department of Energy, Richland Operations Office, Richland, Washington.

This Site has the Following SubSites:

Code: 618-1:1

Names: 618-1:1; 333 East Side Heat Treat Salt Storage Area; 333 ESHTSSA

Code: 618-1:2

Names: 618-1:2; Limestone Neutralization Pit; WATS Trench Neutralization Pit; 300-246

Code: 618-1:1

Classification: Accepted

Names: 618-1:1; 333 East Side Heat Treat Salt Storage Area; 333 ESHTSSA

Reclassification Final Closed Out (8/7/2015)

Type: Burial Ground

Start Date:

Status: Inactive

End Date:

Description: This area has been remediated and reclassified to Interim Closed Out with the 618-1 Burial Ground.

The 333 ESHTSSA was an inactive storage area. The unit included various locations inside the 333 Building fence where heat-treat salts were stored. The heat-treat salts were stored on the paved area near the southeast corner of the building or in the adjacent area located over a portion of the 618-1 Burial Ground. Several areas of the asphalt pavement have been painted over and posted fixed radiological contamination (see WIDS Site UPR-300-17). The area stored containers of solidified heat-treat salt waste from the fuels fabrication facility. The waste consisted of sodium chloride, potassium chloride, sodium nitrite, sodium nitrate, and potassium nitrate. Approximately, thirty to fifty 208 liter (55 gallon) drums accumulated each year (1964-1987).

The SubSite is Part Of:

Code: 618-1

Names: 618-1; Solid Waste Burial Ground No. 1; 300 Area Burial Ground No. 1; 318-1

Code: 618-1:2

Classification: Accepted

Names: 618-1:2; Limestone Neutralization Pit; WATS Trench Neutralization Pit; 300-246

Reclassification: Final Closed Out (8/7/2015)

Type: Burial Ground

Start Date:

Status: Inactive

End Date:

Description: The neutralization pit has been remediated and reclassified as Interim Closed Out with the 618-1 Burial Ground. The centerline of the Pit was 26.8 meters (88 feet) south of the centerline of the 333 Building East Pipe Trench, aligned with where the pipe trench exited the east wall of the 333 Building (see H-3-18520). The upper wooden covers for the Limestone Neutralization Pit had been removed and the pit had been backfilled with soil. It was no longer visible at the surface. The concrete pipe trench branch to the pit was visible prior to remediation (see photos). The drain line from the concrete pipe trench to the pit was sealed and the neutralization pit shut down in 1975, following a large acid spill (WIDS Site UPR-300-14). This incident caused concern for the groundwater. The original pit was constructed of a 0.46 meter (1.5 foot) deep bed of limestone with 7.6 centimeter (3 inch) rock on top of a 0.3 meter (1 foot) deep bed of washed gravel. The top of the limestone bed was 15.2 centimeters (6 inches) above grade and 1.2 meters (4 feet) above the surface of the limestone bed. The Limestone Neutralization Pit received drainage from the WATS pipe trench and the 334 Tank Farm sump trench. The pit was filled with limestone rocks used to neutralize acidic aqueous solutions draining from the pipe trench. The pit had an open top to allow the addition of limestone rocks as needed. It was open at the bottom to drain to the soil column. The soil column effected part of the of the 618-1 Burial Ground, located beneath the neutralization pit. The 334 Tank Farm had four elevated tanks, two for storing concentrated nitric acid, one to store concentrated sulfuric acid, and one tank to store waste etch acid. A sump trench beneath the elevated acid tanks collected leaks from tanks, valves, and piping. The acid transfer lines from the 334 Tank Farm to the 333 Building were installed in the Pipe Trench. Rainwater collected in the sump trenches and the pipe trench drained to the pit.

The SubSite is Part Of:

Code: 618-1

Names: 618-1; Solid Waste Burial Ground No. 1; 300 Area Burial Ground No. 1; 318-1

Code: 618-2

Classification: Accepted

Names: 618-2; Solid Waste Burial Ground No. 2; 318-2 **Reclassification** Final Closed Out (8/7/2015)

Type: Burial Ground **Start Date:** 1/1/1951

Status: Inactive **End Date:** 1/1/1954

Description: The site has been remediated. It was reclassified to Interim Closed Out in 2006 and reclassified to Final Closed Out in 2015. Remediation activities (excavation) began in 2004. The burial ground contained three or four trenches running east-west. The largest trench was 54 meters (175 feet) long and 18 meters (60 feet) wide.

Location: The unit was located north of the 333 Building, on the north side of the 300 Area Exclusion Area.

Process Description: The site received solid waste from the 300 Area operations. This included waste from the 325 and 327 laboratory facilities, which began operations in 1953. A 1995 Ground Penetrating Radar survey found the northern most trench to be 49 meters (160 feet) long and 9 meters (30 feet) wide. The southern most trench was 55 meters (180 feet) long and 15 meters (50 feet) wide. The center trench was 54 meters (175 feet) long and 18 meters (60 feet) wide. The discrepancy of whether there were three or four trenches could be due to the fact that the geometry of the middle trench was broken into two pieces at the east end.

Waste Type: Equipment

Waste Description: The unit was used for disposal of uranium-contaminated equipment and materials, plutonium, and fission products. The uranium waste was typically solid metallic uranium oxides in the form of metal cuttings from Reactor Fuel Fabrication facilities in the 300 Area. The plutonium and fission products came from 300 Area laboratory facilities, that began to operate in 1953. The burial ground may also contain tin from the triple dip canning process and lead from the lead dip process.

In December 2004, during remedial excavation of this burial ground, a combination lock safe was unearthed. A plutonium contaminated cup, a one-gallon jug containing liquid waste, a 250-milliliter flask and several metal cans were found inside the safe.

Closure Info: Interim (12/28/2006): Remedial action activities at the 618-2 waste site began in November 2004 and were completed in August 2006. Excavation of contaminated soil and debris was performed until native soil was reached at the floor of each trench. The determination of native soil was based on the absence of debris materials, plus radiological surveys and visual observations of the soil at the base of the excavation. The total excavated depth was approximately 6 meters (19.7 feet), with the shallow zone consisting of the excavation sidewalls to a depth of 4.6 meters (15 feet) and the deep zone consisting of the excavation sidewalls below 4.6 meters (15 feet) together with the floor of the excavation. In-process radiological field screening was conducted during the site remedial actions to guide the excavation and quickly assess the presence and level of contamination. The radiological survey results indicated the presence of isotopes of uranium and plutonium, as well as cesium-137. The buried waste consisted primarily of a wide variety of laboratory and construction type debris. Excavation activities found no indication of bulk liquid waste disposal at this waste site. During the initial excavation phase, contaminated soil and debris were excavated from the burial ground and transported to a designated "stockpile" area for sorting and sampling. Sorting and sampling of the excavated soil and debris was performed in a designated staging pile area. This staging pile area supported the 618-2, 618-3, and 618-8 Burial Ground excavations and is included with the closure of the 618-2 waste site.

Excavation and load-out operations were suspended from December 2004 to December 2005, due to the discovery of higher than anticipated levels of plutonium-contaminated waste. When operations resumed in December 2005, the first materials designated for load-out were the existing sorted stockpiles located on the east side of the designated stockpile sorting area.

Following a sampling campaign to ensure compliance with Land Disposal Restrictions (LDRs), these sorted stockpiles were loaded into ERDF containers and transported to ERDF for disposal. Concurrent with the load-out of the existing sorted stockpile material, additional stockpiles of previously unsorted and unsampled 618-2 material, located on the west side of the designated stockpile/sorting area, were thoroughly sorted and subsequently sampled. Upon receipt of sample results confirming compliance with LDR restrictions, these stockpiles were also loaded into ERDF containers and transported to ERDF for disposal. In January 2006, excavation and sorting operations resumed at the 618-2 Burial Ground trenches utilizing a revised material handling strategy that eliminated the requirement for hauling the excavated material to a designated stockpile area. The revised strategy provided a mechanism for direct sorting and stockpiling of the excavated material inside the boundaries of the existing trenches. After sorting, the "in-trench" stockpiles were then sampled to ensure compliance with LDR restrictions. Upon receipt of sample results confirming compliance with LDR restrictions, the "in-trench" stockpiles were loaded into ERDF containers and transported to ERDF for disposal.

Land disposal restriction (LDR) materials, primarily consisting of lead solids, were identified and separated from the bulk soil and debris during excavation and sorting operations. All excavated materials were disposed of at ERDF. Approximately 71,203 metric tons (78,488 U.S. tons) of material from the site was removed and disposed of at ERDF. Excavated material consisted of contaminated soil and a wide variety of miscellaneous debris. Some Land Disposal Restriction (LDR) materials, (primarily lead solids) were identified among the debris and were subsequently segregated from the bulk soil and non-LDR debris, then designated for separate load-out as LDR material. Subsequent to sorting, the remaining bulk soil and non-LDR debris material stockpiles were sampled to ensure that the material was in compliance with LDR restrictions. Upon receipt of sample results confirming compliance with LDR restrictions, the released stockpile material was loaded into ERDF containers and transported to ERDF for disposal. LDR materials that had been segregated for treatment were subsequently loaded-out and transported to ERDF under a separate waste profile.

In June 2006, an area of discolored soil, exhibiting high plutonium contamination, was located in the eastern portion of the middle trench at a depth of 8 meters (26.2 ft) below grade. This location likely corresponds with the "high activity" waste disposal area of the middle trench that is discussed in a historical memo concerning the February 17, 1954 fire at the 618-2 Burial Ground. An additional 1 meter (3.3 ft) of soil was removed from this area and a soil sample collected at a depth of 9 meters (29.5 ft) below grade. The sample results indicated residual plutonium activities decreasing with depth, but not at a rate that would support an evaluation of protection of groundwater. A review of historical groundwater levels in the vicinity of the 618-2 site indicated a groundwater low of 104 meters (341.2 ft) above sea level (15 m [49.2 ft] below grade) and a groundwater high of 107.5 meters (352.7 ft) above sea level (11.5 m [37.7] below grade). Considering this information, a test pit was excavated to groundwater in August 2006, to remove the contaminated soil and to collect discrete soil samples for laboratory analysis to support further evaluation of protection of groundwater. A grab sample of water at the base of the test pit was also collected. Four additional potholes were dug, surrounding the test pit location. Discolored soil and residual contamination indicated additional excavation was needed.

Final (8/7/2015): No additional soil remediation was required. The uranium in the groundwater beneath the waste site will be addressed with the 300-FF-5 groundwater Operable Unit. The Final Closed Out status is documented on Waste Site Reclassification forms 2015-069, 2015-071 and 2015-072.

Basis for Reclassification:

Interim remedial actions were performed so as to allow industrial land use and to protect groundwater and the Columbia River, as described in the Cleanup Verification Packages for the 618-1 Burial Ground, CVP-2010-00010, Rev. 0, 618-2 Burial Ground, CVP-2010-00001, Rev.

0, and 618-3 Burial Ground, CVP-2010-00005, Rev. 0, Washington Closure Hanford, Richland, Washington. Previous verification sampling results were evaluated as part of development of the Hanford Site 300 Area, Record of Decision for 300-FF-2 and 300-FF-5, and Record of Decision Amendment for 300-FF-1, Hanford Site, Benton County, Washington (300 Area Final Action ROD), U.S. Environmental Protection Agency, Region 10, Seattle, Washington. The 300 Area Final Action ROD identified 618-1, 618-2 and 618-3 as three of seven 300 Area sites that had contributed to uranium groundwater contamination and, thus, associated it with the selected enhanced natural attenuation remedy component. However, the location of the 618-1 waste site is physically separate from the target treatment area and no further remediation activities were identified at the waste site location. Implementation of the broader enhanced attenuation remedy for the 300 Area will be implemented in accordance with the Remedial Design Report/Remedial Action Work Plan Addendum for the 300 Area Groundwater, DOE/RL-2014-13-ADD 2, Rev. 0, U.S. Department of Energy, Richland Operations Office, Richland, Washington.

Code:	618-3	Classification:	Accepted
Names:	618-3; Burial Ground #3; Dry Waste Burial Ground No. 3; Solid Waste Burial Ground No. 3; 318-3	Reclassification	Final Closed Out (8/7/2015)
Type:	Burial Ground	Start Date:	1/1/1954
Status:	Inactive	End Date:	1/1/1955
Description:	The site has been remediated. It was Interim Closed Out in 2006 and Final Closed Out in 2015. Prior to remediation the site was fenced and posted with Underground Radioactive Material signs. The original surface dimensions were 107 meters (350 feet) long by 50 meters (165 feet) wide. An extension to the north end of the burial ground appeared on Drawings H-6-933 and H-6-939, lengthening the site by 15 meters (50 feet). A 1995 Ground Penetrating Radar survey indicated that this burial ground was dominated by one continuous north-south trending trench. Within the interpreted trench boundary, areas of debris were readily identified continuously covering an area of about 335 feet by 90 feet.		
Location:	The site was located north of the 300 Area Exclusion Fence, adjacent to and west of the 618-2 Burial Ground.		
Process Description:	This disposal site was first used in the summer of 1954. It received mostly contaminated waste from the remodeling of the 313, 303-J and 303-K Buildings and the construction of the 311 Facility.		
Waste Type:	Demolition and Inert Waste		
Waste Description:	The site consisted of uranium-contaminated waste, primarily building materials from the remodeling of the 313 Building. It may have also contained waste from the 303-J and K upgrades. In 1986, the volume of contaminated soil was estimated to be 12,549 cubic meters (443,160 cubic feet), with 12,643 cubic meters (446,480 cubic feet) of overburden.		
Closure Info:	Interim: Remedial action activities at the 618-3 waste site were conducted from September 9, 2004, to October 28, 2004. Remediation activities were conducted in accordance with the RDR/RAWP. Remediation involved excavation and removal of buried waste and contaminated soil to the extent required to satisfy the RAOs and corresponding RAGs. In-process radiological field screening was conducted during the site remedial actions. Field screening was used to guide the excavation to quickly assess the presence and level of contamination. The radiological survey results were consistent with the presence of uranium, at relatively low concentrations. There was no indication of additional radioactive contamination beyond the low levels of uranium.		

The buried waste consisted primarily of a wide variety of construction-type debris. Excavation activities found no indication of bulk liquid waste disposal at this waste site. Land disposal restriction materials, primarily consisting of lead solids, were identified and separated from the bulk soil and debris during excavation and sorting operations. Sorting and sampling of the excavated soil and debris was performed in a designated staging pile area. This staging pile area supported the 618-2, 618-3, and 618-8 Burial Ground excavations and will be closed out with the 618-2 waste site. No overburden piles were created during the waste site excavation. All excavated materials were disposed at ERDF. A total of approximately 30,878 metric tons (34,037 U.S. tons) of material was removed and disposed at ERDF.

Final (8/7/2015): No additional soil remediation was required. The uranium in the groundwater beneath the waste site will be addressed with the 300-FF-5 groundwater Operable Unit. The Final Closed Out status is documented on Waste Site Reclassification forms 2015-069, 2015-071 and 2015-072.

Basis for Reclassification:

Interim remedial actions were performed so as to allow industrial land use and to protect groundwater and the Columbia River, as described in the Cleanup Verification Packages for the 618-1 Burial Ground, CVP-2010-00010, Rev. 0, 618-2 Burial Ground, CVP-2010-00001, Rev. 0, and 618-3 Burial Ground, CVP-2010-00005, Rev. 0, Washington Closure Hanford, Richland, Washington. Previous verification sampling results were evaluated as part of development of the Hanford Site 300 Area, Record of Decision for 300-FF-2 and 300-FF-5, and Record of Decision Amendment for 300-FF-1, Hanford Site, Benton County, Washington (300 Area Final Action ROD), U.S. Environmental Protection Agency, Region 10, Seattle, Washington. The 300 Area Final Action ROD identified 618-1, 618-2 and 618-3 as three of seven 300 Area sites that had contributed to uranium groundwater contamination and, thus, associated it with the selected enhanced natural attenuation remedy component. However, the location of the 618-1 waste site is physically separate from the target treatment area and no further remediation activities were identified at the waste site location. Implementation of the broader enhanced attenuation remedy for the 300 Area will be implemented in accordance with the Remedial Design Report/Remedial Action Work Plan Addendum for the 300 Area Groundwater, DOE/RL-2014-13-ADD 2, Rev. 0, U.S. Department of Energy, Richland Operations Office, Richland, Washington.

Code: 618-5	Classification: Accepted
Names: 618-5; Burial Ground No. 5; Regulated Burning Ground; 318-5	Reclassification: Final Closed Out (2/18/2014)
Type: Burial Ground	Start Date: 1/1/1945
Status: Inactive	End Date: 1/1/1962
Description:	The site was remediated in 2003 and interim closed out in 2004.
Location:	The unit was located north of the 300 Area. It was north of the remediated 316-2 Pond and east of the 316-5 Process Trenches. The site was approximately 1.6 kilometers (1 mile) north of the Richland City limits.
Process Description:	The site received 300 Area waste from 1945 through 1962. The site was one large (single) pit. It was also used as a burn pit.
Waste Type:	Misc. Trash and Debris
Waste Description:	HW-39076 states the area was a burning trench as well as a storage area for aluminum silicate containing 17% uranium and bronze crucibles with radiation levels up to 200 mr/hr. The site

was used for the disposal of uranium-bearing trash. Characterization test pits dug in 1992 encountered radiologically contaminated lead bricks, steel pipes, wood fragments and other garbage. Asbestos was found in Test Pit 2.

Closure Info: Interim: Remedial activities occurred between March and August 2003. Historical information documenting operation of the 618-5 Burial Ground as a burn pit was consistent with the type and condition of waste observed during the excavation process. In addition to the major waste streams encountered, smaller quantities of asbestos, wood debris, intact bottles, dried paint, tar, and other items were unearthed in discrete areas of the burial ground. A detailed listing of waste unearthed from the burial ground and managed as no bulk material was maintained in the 300 Area project files (i.e., waste tracking sheet). At the completion of field operations in 2003, the total excavation was approximately 8,110 square meters (87,300 square feet) in area with a maximum depth of approximately 7.5 meters (24.6 feet) below the surrounding grade. Approximately 46,300 metric tons (50,930 tons) of bulk soil and debris were excavated from the site, put into adjacent staging pile areas, and subsequently transported to the Environmental Restoration Disposal Facility for disposal. Overburden material and excavated soil identified as potentially clean was stockpiled (below cleanup level soil stockpile) at the site for subsequent use as backfill material.

Remedial action objectives and goals for the 618-5 Burial Ground were established by the U.S. Environmental Protection Agency and the U.S. Department of Energy, Richland Operations Office, in concurrence with the Washington State Department of Ecology. These goals and objectives were based on industrial land use and are documented in the Record of Decision for the 300-FF-2 Operable Unit (ROD).

Excavation operations were driven by remedial action objectives for removal of the burial ground contents as well as direct exposure limits, protection of groundwater, and protection of the Columbia River. For the respective points of compliance, remedial action goals were established in the ROD and the Remedial Design Report/Remedial Action Work Plan for the 300 Area.

Because residual soil concentrations indicated that cleanup levels for more stringent land uses may have been achieved for the 618-5 Burial Ground, a supplemental evaluation was performed against the unrestricted land-use cleanup objectives established in the 300-FF-2 ESD. Results of the evaluation demonstrated that remedial actions at the site have achieved all of the objectives for unrestricted land uses. Consequently, no institutional controls are required at the site.

Final (2/18/2014): This group of sites are considered Final Closed Out in the 300-FF-2 Record of Decision and meet the criteria for Unrestricted Landuse.

Code: 618-7	Classification: Accepted
Names: 618-7; Burial Ground #7; Solid Waste Burial Ground No. 7; 318-7	Reclassification: Final Closed Out (2/18/2014)
Type: Burial Ground	Start Date: 1/1/1960
Status: Inactive	End Date: 1/1/1973
Description: The site has been remediated and Interim Closed Out. It was backfilled with clean soil to match adjacent grade elevations. The burial ground consisted of two east-west oriented trenches and one V-shaped pit. Prior to remediation, the burial ground was a vegetation-covered area, with patches of cobbles, surrounded by wooden poles and an 2.4 meter (8 foot) wire fence. A locked gate was located on the east side of the fenced area and was posted with Underground Radioactive Material signs.	

- Location:** The site was located northwest of the 300 Area, west of Stevens Drive. It was 9 meters (29.5 feet) north of the Vitrification Test Site (site code 300 VTS).
- Process Description:** Most of the waste in this burial ground originated from the 313 and 333 buildings (operated by Douglas United Nuclear [DUN]). Some waste was generated by the JA Jones, Battelle Northwest and Westinghouse companies, located in the 300 Area. Between 1962 and 1973, hundreds of drums of zircaloy chips (slightly contaminated with Beryllium) were disposed at this burial ground. The zircaloy chips are waste from the process of machining the ends of zircaloy clad fuel elements. The chips vary in size, but are generally 0.14 millimeters (4 to 5 mils) thick and 0.6 centimeters (0.25 inches) wide. The chips may be contaminated with beryllium and uranium. The material was considered to be pyrophoric and was placed in 114 liter (30 gallon) iron drums, filled with water. No records were kept to identify the exact quantities and locations of these drums. The practice was discontinued in June, 1973.
- Waste Type:** Equipment
- Waste Description:** Materials buried at this site were primarily from the 321, 313, 333, 3722 and 3732 Buildings. Miscellaneous contaminated equipment and hundreds of 114 liter (30 gallon) drums of zircaloy chips contaminated with moderate amounts of beryllium and uranium were buried in the trenches from 1960 to 1973. Since the zircaloy was considered pyrophoric, the drums were filled with water to avoid spontaneous combustion. It is highly possible the water has leaked out of the drums. It has been suggested the waste remain undisturbed to avoid oxidation. An explosive hazard may be present. Other low-level material, slightly contaminated with uranium and thorium, was also buried in the trenches. A 1972 memo states that from January through August 1972, 91 cubic meters (3024 cubic feet) of waste contaminated with uranium was placed in Burial Ground 7. It also states that during that same period, 55 cubic meters (1848 cubic feet) of thoria contaminated waste, 25 cubic meters (848 cubic feet) of thorium oxide and 30 cubic meters (1000 cubic feet) of non-radioactive beryllium contaminated waste was placed in Burial Ground 7.
- Closure Info:** Interim (1/7/2009): Remedial action activities at the 618-7 Burial Ground began January 4, 2008, and were completed on November 15, 2008. Remediation activities involved excavation and removal of buried waste and contaminated soil to the extent required to satisfy the RAOs and corresponding RAGs. In-process radiological field screening was conducted during the site remedial actions to guide the excavation and quickly assess the presence and level of contamination. Waste encountered during excavation of the trenches was consistent with the types of material anticipated based on its reported use for disposal of contaminated equipment from the 300 Area Facilities and drums of Zircaloy chips.

A total of 117 drums containing Zircaloy packed in water-soluble oil were removed. Because these drums contained PCBs and other contaminants, they were sent to an off-site treatment facility. Approximately 20 stainless steel tanks (2 to 3 meters [8 to 10 ft] in diameter and 1 to 3 meters [4 to 10 ft] in length) and a solvent extraction column (1 meter [3 ft] in diameter and 9 meters [30 ft] tall) were also recovered from the thoria trench. The tanks and solvent extraction column were associated with the Plutonium Uranium Reduction Extraction (PUREX) prototype facility that operated in the 321 Building. Several of the tanks contained cooling coils filled with an ethylene glycol solution. Process furnaces and hundreds of empty five gallon buckets from the thoria target fabrication line (located in the 3722 Building) were also found in the thoria trench. The north and middle trenches, collectively referred to as the main trench, contained a large volume of aluminum turnings mixed with soil. A total of 200 drums were recovered that contained aluminum turnings and aluminum rods. Approximately 200 drums containing vermiculite were recovered. The vermiculite was slightly contaminated with low levels of uranium and was suspected to have been used as an absorbent. Approximately 50 drums containing different types of oil were removed. Approximately 200 bottles ranged in size from 100 mL to 20 liters were recovered from the three trenches. In August 2008, a silvery

powder was unearthed that ignited when it was exposed to air. The fire was immediately extinguished with pre-staged soil.

Contaminated debris and soil were segregated and sorted within the trench excavation boundaries. Excavation was performed until native soil was reached at the floor of each trench. The determination of native soil was based on the absence of debris materials, radiological surveys, and visual observations of the soil at the base of the excavation. In total, approximately 160,920 metric tons (177,380 US tons) of material from the site was removed and disposed. All excavated materials were disposed at the ERDF, with the exception of the radiologically contaminated oil and the Zircaloy, which were sent for treatment and/or disposal at an approved off site facility. Approximately 18,140 metric tons (20,000 US tons) of aluminum turnings and solids contained lead above land disposal restriction (LDR) levels and required solidification prior to disposal at ERDF. Aluminum turnings and aluminum rods from approximately 200 drums were mixed with soil and sent to ERDF. The contaminated vermiculite was also mixed with soil for disposal at ERDF. The bottles recovered from the 3 trenches (approximately 200) were emptied and the bottles were disposed at ERDF. The contents of the bottles were sent to an analytical laboratory for characterization prior to disposal.

Final (2/18/2014): The group of sites were reclassified to Final Closed Out in 2014. They are listed in the 300-FF-2 Record of Decision and meet the criteria for unrestricted landuse.

Code: 618-8	Classification: Accepted
Names: 618-8; Early Solid Waste Burial Ground; Solid Waste Burial Ground No. 8; 318-8	Reclassification: Final Closed Out (2/20/2014)
Type: Burial Ground	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1954

Description: The site has been remediated and interim closed.

The site originally consisted of a solid waste burial ground. Later, when a parking lot was constructed over the majority of the site the radiation monuments were cut down to grade. Medallions embedded in the asphalt then marked the location of the burial ground. The original footprint of the burial ground was expanded to the north in 1980. This area was delineated by post and chain. The site was posted as Underground Radioactive Material.

Location: The site was located north of the 300 Area, beneath a portion of the 300 Area North Parking Lot (in the vicinity of Washington State Plane coordinates E 593820, N 116410) and an extended area north of the parking lot.

Waste Type: Construction Debris

Waste Description: The site is assumed to have been used for the disposal of uranium-contaminated solid waste from fuel fabrication facilities.

Closure Info: Interim: Remedial action activities at the 618-8 waste site began on November 1, 2004, and were completed on November 8, 2004. Remediation involved excavation and staging of clean overburden material and removal of contaminated soil to the extent required to satisfy the RAQ's and corresponding RAG's. The excavated material consisted of soil and a wide variety of construction-type debris. Some land disposal restricted materials (primarily three metal drums) were identified and separated from the bulk soil and debris during excavation and sorting operations. Sorting and sampling of the excavated soil and debris was performed in a designated staging pile area. After sorting and receiving of sampling results, the released material was loaded into ERDF containers and transported to the ERDF for disposal. Material designated as land disposal restricted materials were loaded out and transported to the ERDF

under a separate waste profile.

The staging pile area used for the 618-8 waste site also supported the 618-2 and 618-3 Burial Ground excavations. In December 2004, load-out operations at the 618-8 Burial Ground staging piles were suspended, due to the discovery of plutonium-contaminated waste at the 618-2 Burial Ground. Part of mitigation actions was to stabilize the excavated, staged waste and debris. A soil cover was placed on all the stockpiled material from the 618-8 Burial Ground. Load-out of the 618-8 stockpiled material resumed on September 1, 2005. The activity was completed on September 13, 2005. Final cleanup verification sampling was conducted on January 31, 2006.

Approximately 6,462 metric tons (7,125 U.S. tons) of material from the site was removed and disposed at the ERDF.

Geophysical, ground-penetrating radar (GPR) surveys were performed in 1987 and additional characterization in 2002. These GPR surveys identified two distinct areas containing substantial amounts of buried waste in the areas located north of the parking lot (inside the area previously delineated by the "post and chain" boundaries). The GPR surveys could not identify a traditional trench configuration or evidence of buried waste under the area delineated by the medallions in the parking lot. Subsequent test excavations and trenching performed at the parking lot area did not expose any evidence of buried waste or debris in that area. A total of eight soil samples were collected from soil removed during the trenching and test excavations. These samples were analyzed for Resource Conservation and Recovery Act of 1976 metals and a wide range of radionuclides. Analytical results showed all results were either undetected or detected below lookup values. As a result, the area under the parking lot was not excavated further.

Site excavation and waste disposal are complete, and the exposed surfaces have been sampled and analyzed to verify attainment of the remedial action goals. Results of the sampling, laboratory analyses, and data evaluations for the site indicated that all remedial action objectives and goals for direct exposure, protection of groundwater, and protection of the Columbia River have been met for industrial land use.

Because residual soil concentrations indicated that cleanup levels for more stringent land uses may have been achieved for the site, a supplemental evaluation was performed against unrestricted land-use cleanup objectives established in the Explanation of Significant Differences for the 300-FF-2 Operable Unit Record of Decision.

The cleanup verification package (CVP) 2006-00006 documents that the waste site has been remediated in accordance with the Interim Action Record of Decision for the 300-FF-2 Operable Unit, (ROD) (EPA 2001) and has met the remedial action objectives (RAOs) and remedial action goals (RAGs) for this site for interim closure as established in the Remedial Design Report/Remedial Action Work Plan for the 300 Area (RDR/RAWP).

Final (2/20/2014): This group of sites is considered Final Closed Out in the 300-FF-2 Record of Decision and meets the criteria for unrestricted landuse.

Code: 618-9	Classification: Accepted
Names: 618-9; Dry Waste Burial Site No. 9; 300 West Burial Ground; 318-9	Reclassification Final Closed Out (2/18/2014)
Type: Burial Ground	Start Date: 1/1/1950
Status: Inactive	End Date: 1/1/1956

Description: The site was remediated and Closed Out. It was a burial ground composed of a single trench and enclosed within a fence measuring 105 by 95 meters (344 by 312 feet). The waste site was exhumed during an Expedited Response Action in 1991-1992. The empty trench was backfilled and revegetated. The site was released from Radiological Control and the fence was removed.

Location: The site was located northwest of the 300 Area and southwest of the 618-7 Burial Ground.

Waste Type: Chemicals

Waste Description: Historical reports indicated 6,000 kilograms (13,200 pounds) of tributyl phosphate, 10,000 kilograms (22,000 pounds) of paraffin hydrocarbon, and 19,000 liters (5,000 gallons) of uranium-contaminated organic solvents were disposed of in the burial trench. In 1991, this burial ground was excavated. Approximately 2,600 liters (700 gallons) of methyl isobutyl ketone, aka hexone, and 3,400 liters (900 gallons) of kerosene solvent were recovered from 120 drums in the trench's western end. The kerosene solvent was normal paraffin hydrocarbon and tributyl phosphate, known as NPH/TBP. Severely corroded drums were also found at the eastern end of the trench. Approximately 39.6 cubic meters (1,400 cubic feet) of debris was also found, including more than 80 empty drums, a wheelbarrow, scrap process equipment, construction debris, two breached bags of ammonium nitrate, unidentified white powders, and several lead bricks. Debris and soil were removed to the 200 Area Low-level Radioactive Burial Ground. Liquid wastes were sent to licensed off site waste handling facilities.

Closure Info: Interim: An Expedited Response Action was approved to remove hazardous and radioactive material from this trench. Excavation of the 618-9 Burial Ground began on February 28, 1991. Digging originated at the center of the trench over an area showing anomalies in the geophysical survey. To avoid breaching the drums, soil was machine excavated, leaving 0.3 to 0.6 meters (1 to 2 feet) of overburden. Hand digging was performed on the remaining soil. Approximately 2,650 liters (700 gallons) of methyl isobutyl ketone (hexone) and 3,400 liters (900 gallons) of kerosene were recovered from 42 drums. Over 80 empty barrels were removed, along with a significant amount of scrap process equipment and debris.

The initial excavation uncovered a variety of debris covered by 1.2 meters (4 feet) of backfill. The debris included empty waste drums, a wheel barrow, construction debris (corrugated siding, process vessels, and piping) and two bags of ammonium nitrate fertilizer. Extensive follow-up soil gas and soil sampling showed only insignificant amounts of kerosene. Hexone was not detected.

The Expedited Response Action was considered complete in October 1992.

Final (2/18/2014): The group of sites were reclassified to Final Closed Out in 2014. They are listed in the 300-FF-2 Record of Decision and meet the criteria for unrestricted landuse.

Code: 618-10	Classification: Accepted
Names: 618-10; 300 North Solid Waste Burial Ground; 318-10	Reclassification: None
Type: Burial Ground	Start Date: 3/1/1954
Status: Inactive	End Date: 9/1/1963

Description: The site consists of 12 trenches and 94 vertical pipe units. The trenches range in size from 97 meters (320 feet) long by 21 meters (70 feet) wide, 7.6 meters (25 feet) deep to 15 meters (50 feet) long by 12 meters (40 feet) wide, 7.6 meters (25 feet) deep. The vertical pipe units are 56 centimeter (22 inch) diameter, 4.6 meter (15 feet) long waste receptacles constructed by welding five 55-gal (208 L) bottomless drums together. The column of drums were buried vertically. When they reached their waste capacity level, they were backfilled and topped with

concrete. The site perimeter is fenced and marked with concrete AC-540 Markers numbered 3-64-1 through 3-64-68. The site has been surface stabilized and vegetated with grasses. The site is posted with Underground Radioactive Material signs.

Location: The site is located approximately 4 miles northwest of the 300 Area, west of Route 4 South.

Release Description: See UPR-600-1, UPR-600-2 and UPR-600-3.

Related Sites/ Structures: The site is associated with the 300 Area facilities and the 618-11 Burial Ground.

Process Description: The burial ground received a variety of waste from the 300 Area operations. Low level activity waste and large items were placed in the burial trenches. Some high activity waste liquid waste or plutonium contaminated liquid was placed inside barrels and sealed with concrete. The "concrete barrels" were also disposed of in the trenches. Intermediate waste consisted of waste containing between 10 and 1000 curies per cubic foot. High level waste contained greater than 1000 curies per cubic foot. The intermediate and high level wastes were remotely deposited into the vertical pipe units.

Waste Type: Equipment

Waste Description: The site contains a broad spectrum of low- to high-level dry wastes, primarily fission products and some transuranic (TRU) from the 300 Area. Low-level wastes are buried in trenches, and medium- to high-level beta/gamma wastes are mostly in the vertical pipe units. Some higher activity wastes were placed in concrete shielded drums and disposed in the trenches. Following a Plutonium Nitrate spill in the 305-B Building (3-3-61) miscellaneous contaminated debris was taken to the 300 North Burial Ground. A plutonium contaminated glove box was shipped to the 300 North Burial Ground on 6-8-60. Document D&D-23840 found evidence of high dose rate waste being placed in the trenches, some dose rates exceeding 20 rad per hour. One 1964 radiation survey provides a hand drawing map of 619-10 and shows where barrels of depleted uranium were placed.

Code: 618-11	Classification: Accepted
Names: 618-11; Y Burial Ground; 300 Wye Burial Ground; 318-11	Reclassification: None
Type: Burial Ground	Start Date: 1/1/1962
Status: Inactive	End Date: 1/1/1967

Description: The burial ground perimeter is marked with concrete AC-540 markers numbered 2-68-1 through 2-68-28. The site surrounded by an 2.4 meter (8 foot) chain link fence with a locked gate. The fence labeled 618-11 Burial Ground and posted with Underground Radioactive Material signs. The site consists of three "V" shaped trenches, 2 large diameter caissons and 50 vertical pipe storage units. The trenches are 270 meters (900 feet) long by 15 meters (50 feet) wide (surface dimensions) and 7.6 meters (25 feet) deep. The 50 vertical pipe storage units were made by welding five 208-liter (55-gallon) drums together. The welded drums formed a cylinder 56 centimeters (22 inches) in diameter, 4.6 meters (15 feet) long that was buried vertically. The bottoms of the units were 4.6 meters (15 feet) below ground surface. The units were open to the soil at the bottom. The two large diameter caissons were constructed of 2.4 meters (8 feet) diameter corrugated metal pipe, 3.0 meters (10 feet) long, with the top of the caisson being 4.6 meters (15 feet) below grade, connected to the surface by an offset 91-centimeter (36-inch) diameter pipe with a dome type cap. The caissons were open to the soil at the bottom. The bottoms of the caissons were 7.6 meters (25 feet) below ground surface. An additional 0.6 meters (2 feet) of topsoil was added to the site when it was surface stabilized in 1983.

Location: The site is northwest of the 300 Area, directly west of the Energy Northwest commercial power plant (formerly known as the Washington Public Power Supply System (WPPSS) Plant # 2).

Release Description: There are seven documented Unplanned Releases associated with this burial ground. They are UPR-600-4, UPR-600-5, UPR-600-6, UPR-600-7, UPR-600-8, UPR-600-9, and UPR-600-10.

Related Sites/Structures: The burial ground is associated with 300 Area operations and the 618-10 Burial Ground.

Process Description: The burial ground received a variety of waste from the 300 Area operations. Low level activity waste and large items were placed in the burial trenches. Some high activity waste liquid waste or plutonium contaminated liquid was placed inside barrels and sealed with concrete. The "concrete barrels" were also disposed of in the trenches. Intermediate waste consisted of waste containing between 10 and 1000 curies per cubic foot. High level waste contained greater than 1000 curies per cubic foot. The intermediate and high level wastes were remotely deposited into the vertical pipe units. Contaminants included fission products, plutonium and beryllium.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: The site contains a broad spectrum of low to high level dry wastes, including fission products and plutonium. Low-level wastes in cardboard boxes and large pieces of equipment were buried in the trenches. The trenches also include 55 gallon drums with high activity or small amounts of liquid, encased in cement. Most of the high activity wastes were remotely placed into the pipe storage units and caissons. These wastes were contained in small cans. Historical research related to the burial ground waste inventory resulted in the review of many Radiological Shipment Records (RSR's) and Radiological Survey Records. Document D&D-23840 identifies larger items with significant dose rates were placed in the trenches, as well as drums containing depleted uranium and material contaminated with beryllium, thorium and plutonium. Many of these records were copied and bound into miscellaneous report documents. A summary is included in the 618-11 Expedited Response Proposal. One 1963 memorandum, authored by EA Berreth, indicates that all plutonium waste from the 325 building was to be sent to the 200 Area burial grounds. 325 building waste with high dose rates would be sent to 618-11 burial pipes.

Code: 618-13	Classification: Accepted
Names: 618-13; 618-13 Burial Ground; 303 Building Contaminated Soil Burial Site; 318-13	Reclassification: Final Closed Out (2/18/2014)
Type: Burial Ground	Start Date: 1/1/1950
Status: Inactive	End Date: 1/1/1950

Description: The 618-13 waste site was remediated in 2009 and Interim Closed Out. The waste site had been of a mound of soil approximately 4.6 to 6.1 meters (15 to 20 feet) high by 38 meters (125 feet) long by 15 meters (50 feet) wide, covered with 0.6 meters (2 feet) of clean soil.

Location: The waste site was located west of the 300 Area, across Route 4 South, adjacent to the excavated 618-9 Burial Ground.

Related Sites/Structures: 618-13 is associated with the 600-290:1 Concrete Pad and Loading Dock and 600-290:2 300 West Storage Area.

Process Description: The site was originally a single use disposal site for contaminated soil removed from the 303 Building perimeter in 1950. It is believed that the large mound of soil was added later and served as a safety shield (blast shield) for drums of hexone stored in buildings on the west side of the berm, prior to being buried in the 618-9 Burial Trench in 1954. A concrete building

foundation and loading dock remained directly west of the mound (see sitecode 600-290:1).

Waste Type: Soil

Waste Description: This site presumably received uranium contaminated topsoil removed from around the 303 Building area. Total activity buried in the site is not known. During remediation, only soil and a small amount of wood debris was identified. No other debris was found in the soil pile.

Closure Info: Interim: The concrete pad and loading dock were remediated in 2009. Field remediation of the 618-13 Burial Ground and the 600-290:1 concrete pad and loading dock occurred between January 5 and February 2, 2009. The activity removed the soil mound, concrete pad, and loading dock. The mound and concrete pad were removed to ground surface level. No sub-grade excavation was required. The excavated material was maintained within the waste site footprint; therefore, no staging piles were generated outside of the waste site boundary. Contaminated soil, pieces of decayed wood, and concrete were the only materials found during remediation of the site. A radiological survey of the 618-13 footprint was done on February 12, 2009. The results indicated the soil beneath the excavated mound was less than two times the background for beta-gamma radionuclides.

Cleanup Verification Package CVP-2009-00005 demonstrates that remedial action at the 618-13 Burial Ground and the collocated 600-290:1 Pad and Loading Dock Near 618-13 has achieved the remedial action objectives (RAOs) and corresponding remedial action goals (RAOs) established for the unrestricted landuse scenario in the Interim Action Record of Decision (EPA 2001), the Explanation of Significant Differences for the 300-FF-2 Operable Unit (EPA 2004), and the Remedial Design/Remedial Action Work Plan for the 300 Area (DOE/RL 2009b).

The contaminated materials from the site have been excavated and disposed at ERDF. The remaining soil at the 618-13 and 600-290:1 sites have been sampled, analyzed, and evaluated. Results indicate that the site supports future land uses that can be represented (or bounded) by the residential land-use scenario and poses no threat to groundwater or the Columbia River.

Final (2/18/2014): The group of sites were reclassified to Final Closed Out in 2014. They are listed in the 300-FF-2 Record of Decision and meet the criteria for unrestricted landuse.

Code:	UPR-300-1	Classification:	Accepted
Names:	UPR-300-1; 307-340 Waste Line Leak; 316-1A; UN-300-1	Reclassification	Consolidated (10/16/2014)
Type:	Unplanned Release	Start Date:	12/1/1969
Status:	Inactive	End Date:	12/1/1969
Description:	The site was a release to the soil in the area between the 307 Retention Basins and the 340 Building. There is no readily apparent sign of subsurface contamination beneath the gravel covered area. UPR-300-1, UPR-300-2, and UPR-300-11 sites are adjacent to the 340 facility. Demolition of the facility and remediation of the soil waste site includes the areas of these unplanned release sites. It is not practical to distinguish these sites from the larger site. The UPR sites have been reclassified to Consolidated with the 340 Complex.		
Location:	UPR-300-1 occurred in the soil between the 307 Retention Basins and the 340 Building in the 300 Area.		
Release Description:	A long-duration leak was discovered in the cast iron transfer line between the 307 Retention Basins and the 340 Vault. On December 9, 1969, operators experienced difficulty transferring retention waste from the 307 Basins to the 340 Vault. The next day the pump was tried again and it continued to work at reduced output. Eventually the pump was stopped when water		

appeared at ground surface between the basins and the 340 building. After stopping the pump, the area of the flooding was excavated and the bottom half of the Retention Basin transfer line adjacent to the junction of the transfer line with the Radioactive Liquid Waste Sewer (RLWS) line was found to be severely corroded. The corroded section of carbon steel pipe discharged approximately 900 curies of short-lived radionuclides (including 10 curies each of strontium-90 and cesium-137) to the soil column over a period as long as a year. Investigation suggested that the cause of the corrosion was RLWS waste backing up into the section of transfer line near the junction.

Related Sites/ Structures: UPR-300-1 was associated with the 340 Building/307 Retention Basins transfer line, and the Radioactive Liquid Waste Sewer (RLWS). Well 399-3-8 is also associated with this site. This well was drilled through the middle of the contamination to determine if the plume had reached groundwater in 1970. Review of the site shows that this well has been "missing" for some time. Numerous drawing searches have been performed, aerial photographs have been reviewed, a geophysical study was performed, and site personnel have been interviewed in attempts to locate and determine what happened to the well. The presumed location of the well coincides with the location of RLWS valve box number 8. Construction of valve box number 8 took place in 1970, the last date of well sampling. It is possible that construction activities disturbed the well. Thus, it is possible that the well casing was cut off below grade, or completely removed.

Process Description: The 307 Retention Basins are fed by the Retention Process Sewer (RPS) and discharge to the Process Sewer. In the event that effluent in the 307 Retention Basins does not meet release criteria for the process sewer, the waste is transferred to the 340 Tank vault for storage until it can be transported to the 200 Area Tank Farms.

Waste Type: Process Effluent

Waste Description: The waste discharged to the soil column consisted of process effluent contaminated by transuranic fission products including 900 curies of short-lived radionuclides (mainly promethium-147) and 10 curies each of strontium-90 and cesium-137.

This Site Was Consolidated With:

Code: 340 COMPLEX

Names: 340 COMPLEX; 340 Radioactive Liquid Waste Handling Facility; 340 Vault

Code: UPR-300-2

Classification: Accepted

Names: UPR-300-2; Releases at the 340 Facility; UN-300-2; UN-316-2

Reclassification: Consolidated (10/16/2014)

Type: Unplanned Release

Start Date: 1/1/1954

Status: Inactive

End Date:

Description: The waste site is the result of multiple releases from ongoing decontamination and waste handling activities, starting in January 1954, that affected the soil around the 340 facility. UPR-300-1, UPR-300-2, and UPR-300-11 sites are adjacent to the 340 facility. Demolition of the facility and remediation of the soil waste site includes the areas of these unplanned release sites. It is not practical to distinguish these sites from the larger site. The UPR sites have been reclassified to Consolidated.

Location: UPR-300-2 affected the soil within 3 to 6 meters (10 to 20 feet) of the north, east, and south walls of the 340 Building.

Release Description: Several leaks have occurred that contributed significant amounts of radioactivity to the soil around 340 Building. Soil contamination that extends several feet down adjacent to the 340 Building south wall suggests that the sump (truck tanker loadout) overflowed during the tanker

truck era. Strontium-90 has been identified in the soil. The short-lived radionuclides are gone, and the ground surface is stabilized. However, contamination is known to extend several feet into the soil. In the same vicinity, a drain was exposed to allow the draining of tanker trucks for maintenance on the tanker valves. Minor leakage occurred around the drain pipe. This area is also covered and stabilized, but contamination is known to extend several feet into the soil.

A major leak on a retention waste line was discovered December 9, 1969 (See WIDS Site UPR-300-1). The last known ground contamination found in the same area occurred during the V-659 project on October 31, 1977. A leaking tee on the 15.2 centimeter (6 inch) radioactive liquid waste line had gone undetected until the line was uncovered (See WIDS Site UPR-300-11). Known contamination is also present on the north side of the vault. The most affected area is near the northwest corner of the vault (near the control room). A HEPA filter in the vault exhaust system was located there, and condensation from the vault atmosphere collected in the filter enclosure and dripped on the ground. The condition was corrected with the V-677 project, and the surface soil was removed. A potential for low level nuisance contamination is present in the yard, especially downwind (east-northeast) of known problem areas. A systematic search was made for this contamination in 1979, and none was found. Soil samples were taken and surface surveys were made.

Related Sites/ Structures: UPR-300-2 is associated with 340 Building processes.

Process Description: The 340 facility was completed in 1953 along with the initial Radioactive Liquid Waste Sewer (RLWS) piping system, the 307 Basins and the Retention Process Sewer (RPS) piping system. These systems represented an attempt to deal with radioactive effluents from several new laboratories in a modern, controlled manner. The 340/307 system was fed by pipelines from the 325, 326, 327, and 329 Buildings (and later the 308 and 325 Buildings) in a system known as the Retention Process Sewer (RPS) or the Diversion Waste System. Liquid process wastes that had the potential to be contaminated were disposed to the RPS and routed to the 307 Basins for sampling. If radioactivity was not detected above release limits, these wastes were disposed to the 307 Trenches. If levels proved to be above release limits, the effluents were pumped into the 340 Building RLWS tanks.

Waste Type: Process Effluent

Waste Description: 10 millicuries of cesium-137 is provided in the original source document and is designated as an estimate only. It is unknown if this was related to a single event or all events over the time period (1954 to date).

This Site Was Consolidated With:

Code: 340 COMPLEX

Names: 340 COMPLEX; 340 Radioactive Liquid Waste Handling Facility; 340 Vault

Code: UPR-300-4

Classification: Accepted

Names: UPR-300-4; Contaminated Soil Beneath the 321 Building; UN-300-4

Reclassification: Final Closed Out (5/12/2014)

Type: Unplanned Release

Start Date: 1/1/1945

Status: Inactive

End Date: 1/1/1955

Description: The waste site has been remediated and Interim Closed Out. In 2014, the site was reclassified to Final Closed Out. It consisted of the soil beneath and south of the 321 Building. The 323 building was also known as 321-A. The waste site represents numerous releases that occurred from 1945 to 1988 related to operations in this facility. This time period covers the development of the REDOX, PUREX, RECUPLEX, Metal Recovery and the bismuth

phosphate processes, and numerous other pilot operations. No specific occurrence reports have been identified.

Location: UPR-300-4 was located beneath and south of the 321 Building.

Release Description: Uranium, thorium and uranyl nitrate have been associated with the processes performed in the 321 canyon and basement shop areas. Significant detectable uranium contamination was etched into the concrete of the canyon walls and on cranes, decks, and overhead areas. Modification of the facility over the years required cleaning and painting to contain the contamination. However, drilling or otherwise breaching the surface area released residual uranium/thorium contamination. The use of small quantities of plutonium in the early operations has not been substantiated.

More recent history (radiation surveys) indicated that contamination in and around 321 and 321-A (323 Building) was significant and extensive. Excavation inside the canyon area for the HEDL (FFTF) Hydraulic Core Mock-UP (HCM) uncovered higher concentrations of uranium waste than had been previously reported. A yellow substance (presumably uranyl nitrate) measured 20 millirad per hour and extended 4.6 - 6.1 meters (15 - 20 feet) under the canyon floor and beyond. Cleanup stopped at the depth needed for the HCM. Excavation south of the building also uncovered significant quantities of uranium contamination (25 millirad per hour) and was covered with 0.9 - 1.2 meters (3 - 4 feet) of backfill. A manhole between 321 and 321-A (323 Building) read approximately 75 millirad per hour.

Specific contamination events in the 321 Building included a large explosion of a hexone/nitric acid mixture on January 23, 1949. The explosion occurred in E-Cell when a spark from an electric motor being used to test a turbine pump bearing arced through the air and touched off the mixture. The actual volume was only about 20 gallons of liquid in a 55 gallon drum. The explosion spread uranium powder and solution throughout the canyon and lifted the roof because there were no blow-out panels in the building. Ceilings and floors cracked, but the hard concrete walls did not. The aqueous makeup room in the north portion of the building and the back/south dock that held building process solutions were severely jarred by the event, and some chemicals and process solutions splattered and spilled. An entire drum of uranyl nitrate hexahydrate flew through the air on the back dock, spilling its contents. The cleanup consisted of large and repeated water flushings that spread the contamination to surrounding soils and to the Process Ponds.

Other contamination events in the 321 Building included an explosion and resultant fire in dissolver vessel A-5, in A-Cell in May 1957. The vessel contained enriched (0.95% uranium-235) uranyl nitrate solution. In January 1962, a concentrator experienced overpressurization and sprayed uranyl nitrate hexahydrate as far as the roof of 3706 Building. A release of iodine-131 both within the building and out of the stack occurred during a chlorine gas-scrubbing experiment in 1964. There were many smaller leaks and contamination incidents in addition to these more serious events.

A 1988 exterior radiological survey of the 321 Building found several areas of fixed contamination, including flaking exterior paint chips reading 150,000 disintegrations per minute beta/gamma and 25,000 disintegrations per minute alpha, attributed to "pre PUREX R radiological chemical separation operations." To control this contamination, the structure was painted in 1990. Loose, smearable contamination was found during a routine survey of the building's interior in 1991, again attributed to residual contamination from past operations.

Related Sites/Structures: This site is associated with the 321 Building and possibly 323 (321-A) Building. It is also associated with the four 323 Tanks.

Five documented miscellaneous stream drains are located around the 321 Building (see "Inventory of Miscellaneous Streams", Revision 3). These sites are identified in WIDS as site

codes 300-81, 300-82, 300-83, 300-84 and 300-92. They have been consolidated into the UPR-300-4 waste site.

Process Description: The 321 facility was originally constructed as a pilot scale plant for testing chemical process improvements using unirradiated or low-activity substances. The facility was ultimately used to trouble shoot, research, and develop radioactive processes associated with REDOX, PUREX, RECUPLEX, the Metal Recovery process, and the bismuth phosphate process. Additionally, reactor fuel development and miscellaneous support of the other 300 Area laboratories also took place in the 321 Building.

Over the years, a long list of unplanned releases associated with the 321 Building was compiled. Among these were several sizeable explosions, one of which lifted the building concrete slab roof and cracked the floor of this heavily reinforced structure. The same explosion spread uranium powder around the facility, spilled and splattered various process solutions, and sent a drum of uranyl nitrate hexahydrate hurtling through the air and onto the back dock spilling its contents. In another event, a dissolver vessel over pressurized and sprayed a solution of uranyl nitrate hexahydrate as far as 30.5 meters (100 ft), onto the roof of the 3706 Building. The primary cleanup method for contaminant releases in and around the 321 Building was to flush the contamination with water and into the surrounding soils, thus accounting for much of the near surface contamination in the soils around the 321 Building. Uranyl nitrate is a yellow substance that is produced during the processing of spent nuclear fuel in preparation for isotopic separation of the uranium and was a major part of the research conducted within the 321 Building. Uranyl nitrate (hexahydrate) appears repeatedly in the descriptions of the unplanned releases at the 321 Building.

The 323 Building was also known as 321-A. It provided feed storage in below grade tanks (see 323 Tanks) and lay down space and storage above grade. Four stainless steel tanks (323 Tanks 1, 2, 3, 4) were approximately 14.6 meters long by 3.05 meters in diameter (48 feet long by 10 feet in diameter) located under the 323 Building. They contained uranium/thorium sludge. The tanks were filled with water to reduce corrosion of the tanks. Total quantities of radionuclides and tank volumes were unknown. Reference Drawing H-75032 has details on tank locations, size and elevation. An access door is located in the northeast corner of 323 under a stairwell. Building 323 also contains a shielded cell used for stress analysis of various irradiated fuel cladding materials. Stringent contamination control measures were applied for specimens prepared in 327 Building and transferred to 323. No significant problems have been associated with shielded cell. However, the exhaust duct, primary HEPA filter and downstream exhaust fans and filter plenum located on the south side of 323 have a potential for low level mixed fission product and activation product contamination.

Waste Type: Process Effluent

Waste Description: Because the 321 Building was a pilot plant, the Building's mission changed a number of times. These mission changes altered the potential contaminants that may have contributed to the soil contamination. Wastes and contamination include all of the components of the many chemical processes tested in this facility over the years and result from both waste management practices and from unplanned contamination events and accidents.

Components of the bismuth phosphate process included many acids (nitric, phosphoric, hydrofluoric, oxalic, and others), bismuth nitrate, sodium dichromate, potassium permanganate, calcium, lanthanum and sodium fluorides, ammonium fluorosilicate, peroxide, sodium hydroxide, and other substances. Components of the REDOX process and its development include methyl isobutyl ketone (hexone), aluminum nitrate, ammonium nitrate, many acids (including nitric, sulfuric, oxalic, and others), ferrosulfamate, sodium hydroxide, mercury, resins and other substances.

Components of the Metal Recovery process and the PUREX process were quite similar to each

other and included tri-butyl phosphate, normal paraffin hydrocarbon, acids (including nitric, oxalic, and others), ammonium fluoride, ammonium nitrate and other substances.

The RECUPLEX process used tri-butyl phosphate, carbon tetrachloride, many acids (including nitric, oxalic, hydrofluoric, and others), sodium fluoride, sodium hydroxide, and other substances. All of these chemicals became waste constituents, along with trace isotopes of plutonium, uranium, thorium, strontium, cesium, aluminum, iron, copper, and zinc.

Additionally, cell and equipment decontamination reagents, cleansers, and drying materials, including carbon tetrachloride, trichloroethylene, acetone, A-butanone, and many commercial products, became a part of the 321 waste stream.

Closure Info: Interim (8/7/2013): Remediation of the UPR-300-4 waste site was conducted between February 22, 2011, and January 16, 2013. This included the removal of the 321, 321B, 321C, 321D, 323, and 3718-S building foundations. The four 323 underground tanks and five steam condensate drywells and storm drains (300-81, 300-82, 300-83, 300-84, and 300-92) were also completely removed.

Approximately 24,108 bank cubic meters (BCM) (31,532 bank cubic yards [BCY]) of soil, rock, building debris, and piping were removed from the UPR-300-4 excavation. Of that, approximately 1,945 BCM (2544 BCY) was sampled and designated for use as backfill under a separate agreement with the U.S. Environmental Protection Agency (EPA). The balance of the material removed from the UPR-300-4 excavation was disposed to the Environmental Restoration Disposal Facility (ERDF)

The four 323 tanks, located beneath the 323 building foundation were completely removed as part of the UPR-300-4 scope. This included emptying the 323 waste tanks, removing all the associated debris and the potentially impacted soils surrounding the tanks. Approximately 613,719 L (162,145 gal) of water were removed and disposed to the Effluent Treatment Facility (ETF) in September 2012. Approximately 6,623 BCM (8,663 BCY) of soil, rock, building debris, and piping were removed and disposed to ERDF in 2012. A decontamination pad, located on the west side of the excavation, was remediated on February 14, 2013. Approximately 0.30 meter (1 ft) of soil and rock were removed and disposed to ERDF. This resulted in the removal of approximately 114 tons, or 51.8 BCM (67.8 BCY), of soils.

The excavation of the UPR-300-4 waste site extended to groundwater, at a depth of approximately 15 meters (50 ft) below ground surface (bgs). The design for the excavation facilitated the removal of the structure of the 321 Building down to that level. A concrete footing remains at and below groundwater. During the initial excavation groundwater was uncovered near the concrete footing. Fill material was used, with the concurrence of EPA, to cover groundwater and facilitate the ongoing excavation. During this excavation a visible yellow stain was identified on the south sidewall. The stain was found to contain significant uranium and is thought to be the result of a release of uranyl nitrate. Uranyl nitrate is specifically listed in the documentation of several of the unplanned releases that occurred in and around the 321 facility. The plume associated with the yellow stain was excavated and removed down to the level of groundwater. Contamination extending into the groundwater is beyond the scope of the UPR-300-4 waste site and will be addressed as part of the 300-FF-5 operable unit.

Final (5/12/2014): The UPR-300-4, Contaminated Soil Beneath the 321 Building waste site, consisted of contaminated soil around and below the 321 Building including soils below the adjacent 323 Building where waste tanks received liquids via underground piping from operations within the 321 Building. Remediation of the UPR-300-4 waste site, which included removal of the 323 waste tanks and associated piping, was conducted between February 2011, and January 2013 to a maximum depth of 14 meters (46 ft) below ground surface. Verification

sampling for the UPR-300-4 waste site was conducted on March 18 and 19, 2013.

The UPR-300-4 waste site was remediated and has been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). Verification sampling results show that the site meets the CUL's for direct exposure and groundwater protection and river protection and support an industrial land use scenario. Because the remediation of the waste site did not meet residential land use cleanup levels, the waste site requires institutional controls to maintain industrial land use. In accordance with this evaluation, the verification sampling results support a reclassification of the UPR-300-4 waste site to Final Closed Out.

Code:	UPR-300-5	Classification:	Accepted
Names:	UPR-300-5; Spill at 309 Storage Basin; UN-300-5	Reclassification	Final Closed Out (8/7/2015)
Type:	Unplanned Release	Start Date:	8/31/1973
Status:	Inactive	End Date:	8/31/1973
Description:	The site has been remediated and reclassified to Final Closed Out. It was a release of contaminated water that overflowed the storage basin area. It affected the filter vault, the stack base, the truck stall, and the truck ramp outside the 309 Building. The truck ramp was paved with asphalt. Prior to remediation, no radiological postings or markers were present to identify the location of this release.		
Location:	The UPR-300-5 release occurred in 1973 on the east side of the 309 Building. It affected the 309 Building filter pit, stack base and the truck stall, and the outside truck ramp. This release area was within the 309 building demolition footprint.		
Release Description:	The release occurred on August 31, 1973. The 309 Fuel Storage Basin water level was found to be slightly low. Water was added to prevent the exposed walls of the basin from drying and causing possible airborne contamination in the basin room. The operator opened the fill line, but became distracted by other activities in the Fuel Basin Storage area. The employees forgot the water supply line was turned on and it was left open overnight. The water filled the basin and began to flow into the overflow drain. The overflow drain line for tank TW-3 is also connected to the drains in the stack filter pit, the stack and the truck stall. The basin overflow caused water in the drains to back up into the filter pit, the stack base and the truck stall. In 1973, the truck ramp sloped below the 309 building grade. The truck ramp filled with 0.68 meters (1.5 feet) of water. The problem was first discovered by an employee who observed water leaking out from under the roll-up door in the truck stall. Since the truck ramp extends outside the building, contamination was found both inside and outside the 309 Building. The release extended approximately 4 feet (1.2 meter) outside the 309 Building on the truck ramp. The width was the full width of the truck ramp. Surveys of the truck ramp outside of the building and of the truck stall floor within the storage basin area prior to initial decontamination revealed direct radiation levels to 20 millirad per hour and smearable contamination of 30 millirad per hour, respectively. The smearable contamination within the truck stall and on the floor in the storage basin area were initially reduced by flushing with water to levels up to 25,000 counts per minute and 10,000 counts per minute, respectively.		
Related Sites/ Structures:	UPR-300-5 is associated with the 309 Fuel Storage Basin overflow drain line, the TW-3 Storage Tank, the stack base, the filter vault, truck stall, and the truck ramp.		
Waste Type:	Process Effluent		
Waste Description:	The waste was low-level radioactive water. The primary isotope was cesium-137.		
	Surveys of the truck ramp outside of the building and of the truck stall floor within the storage basin area prior to initial decontamination revealed direct radiation levels to 20 millirad per		

hour and smearable contamination of 30 millirad per hour, respectively. The smearable contamination within the truck stall and on the floor in the storage basin area was initially reduced by flushing with water to levels up to 7,000 counts per minute (wet), 25,000 counts per minute (dry), and 4,000 counts per minute (wet), 10,000 counts per minute (dry), respectively. Further decontamination efforts reduced these levels to 7,000 counts per minute (dry) and 1,000 counts per minute (dry), respectively. Air concentrations remained normal following the incident. No detectable radioactive stack emissions were revealed by the continuous exhaust air monitoring equipment or the air sampling system in the stack pit.

Closure Info: Final (8/7/2015): Remedial actions for waste sites 300-22, 300-255 and UPR-300-5 were combined and addressed in CVP-2015-00013.

In January 2014, the 1,082-ton 309 PRTR was removed and transported to ERDF for disposal. The remaining containment structure consisted of 0.3 meters (1 ft) thick concrete surrounded by metal sheeting. It was demolished to 9.8 meters (32 ft) below ground surface (bgs) and disposed at ERDF. The remaining 3.4 meters (11 ft) of the containment structure, from 9.8 to 13 meters (32 to 43 ft) below ground surface, was sampled and left in place.

The 300-22, 300-255, and UPR-300-5 waste sites excavation along with the demolition of the 309 containment structure was performed from March 12, 2014, to February 12, 2015. The excavation resulted in removal of approximately 78,120 bank cubic meters (BCM) (102,177 bank cubic yards [BCY]) of contaminated materials. All material was direct loaded for disposal at ERDF. The 300-22, 300-255, and UPR-300-5 waste sites were excavated to a depth of 11 meters (36 ft) bgs. Excavated materials consisted of concrete, metal tanks, building debris, asphalt, and various types of piping, including carbon steel, stainless steel, clay tile, and concrete tile. No anomalous materials or stained soils were observed during remedial activities. No radiological contamination above background was detected in the shallow zone of the 309 Building excavation. An additional weak-gamma survey was performed to target americium-241 and the associated plutonium. This survey detected radiological contamination above background within the north side of the excavation and 309 PRTR remaining containment structure. Verification samples were collected in the vicinity of the radiological detects above background locations. Sampling results indicated that all cleanup levels were met for the samples in these areas.

Code:	UPR-300-10	Classification:	Accepted
Names:	UPR-300-10; Contamination Under 325 Building; UN-300-10	Reclassification	None
Type:	Unplanned Release	Start Date:	1/1/1977
Status:	Inactive	End Date:	1/1/1977
Description:	The site was an unplanned release to the soil beneath the northwest corner of the 325 Building.		
Location:	UPR-300-10 occurred in the radioactive waste sewer line that served the 325-B Hot Cells, between the west basement wall of Room 32 and the north foundation wall of Room 202 of Building 325.		
Release Description:	Leak testing of the radioactive liquid waste sewer identified a leak between the west basement wall of Room 32 in the 325 Building and the north foundation wall of Room 202.		
Related Sites/ Structures:	UPR-300-10 was associated with the radioactive liquid waste sewer that served the 325-B Hot Cells.		
Process Description:	The 325 Radiochemistry Building was built to safely house and handle multi-curie level chemical development work with high activity substances. The High-Level Radiochemistry addition, with its three larger hot cells, housed several pioneering "isotope campaigns". A		

number of new techniques developed in the 325 Building separated or fractionized specific isotopes from high-level waste by ion exchange, carrier precipitation, solvent extraction, and various combinations of these and other methods. In addition, studies that were part of a Nuclear Waste Vitrification Project took place in the Hot Cells from 1977 to 1980.

Waste Type: Chemicals

Waste Description: UPR-300-10 included waste from dissolution of highly radioactive samples including irradiated reactor fuels.

Code: UPR-300-11	Classification: Accepted
Names: UPR-300-11; UN-300-11; Underground Radioactive Liquid Line Leak near 340 Facility	Reclassification: Consolidated (10/16/2014)
Type: Unplanned Release	Start Date: 10/31/1977
Status: Inactive	End Date: 10/31/1977

Description: The site was a release to the soil that involved a 1.22 meter (4 foot) diameter column of gravel-covered soil in the 340 Complex yard, located immediately south of the 340 Vault. The release occurred around and below a leaking flanged-tee that connected the Retired Radioactive Liquid Waste Sewer (RRLWS) to the 340 Vault. UPR-300-1, UPR-300-2, and UPR-300-11 sites are adjacent to the 340 facility. Demolition of the facility and remediation of the soil waste site includes the areas of these unplanned release sites. It is not practical to distinguish these sites from the larger site. The UPR sites have been reclassified to Consolidated.

Location: UPR-300-11 occurred in the soil on the southeast side of the 340 Building, southwest of the 340 Vault.

Release Description: On October 31, 1977, during a project to install a new double-contained system to replace the old Radioactive Liquid Waste System piping (Project V-659), contamination was found in the soil beneath leaking flanges on a tee section of the RRLWS south of the 340 vault. When sheets of lead shielding were found draped over the old line, a shovel-full of soil was removed from beneath the shielding and counted. Subsequent excavation around the flanged tee revealed contamination caused by effluent leaking from between the flanges. The leak contaminated a column of soil approximately 1.22 meters (4 feet) in diameter and 5.5 meters (18 feet) long. The contamination was first identified approximately 2 meters (7 feet) below the top of the 340 vault. The highest dose rate (5 rads per hour) was measured under the lead sheet draped over the waste line. Smears of the area showed that alpha contamination was also present. At a depth of approximately 7.6 meters (25 feet), contamination spread laterally in an interface between the undisturbed soil and backfill.

Related Sites/ Structures: UPR-300-11 is associated with a flanged "tee" connecting the east and west legs of the Retired Radioactive Liquid Waste Sewer (RRLWS) to the 340 Facility. Analysis of the contamination below the "tee" suggested the effluent was derived from 325-A building processes.

Process Description: While in service, the Retired Radioactive Liquid Waste Sewer (RRLWS) system transferred liquid waste from laboratories and facilities in the 300 Area to the 340 Complex for sampling and disposal.

Waste Type: Process Effluent

Waste Description: Soil samples collected near the broken pipe were analyzed and yielded concentrations of 0.2 strontium-90, 0.24 europium-155, 0.09 cerium-144, 0.0017 plutonium-239 and 240, and 0.014 americium-241 and plutonium-238 (all microcuries per cubic centimeter). Approximately 1 curie of contamination was left in place.

This Site Was Consolidated With:

Code: 340 COMPLEX
Names: 340 COMPLEX; 340 Radioactive Liquid Waste Handling Facility; 340 Vault

Code: UPR-300-12 **Classification:** Accepted
Names: UPR-300-12; Contaminated Soil Beneath the 325 Building; UN-300-12 **Reclassification:** None
Type: Unplanned Release **Start Date:** 1/1/1979
Status: Inactive **End Date:** 1/1/1979

Description: The site was an unplanned release to the soil under the floor on the east side of the 325-A Building.

Location: UPR-300-12 occurred in the basement floor of the 325-A Building. The waste migrated through cracks in the floor to the soil beneath the building.

Release Description: On January 8, 1979, a Pacific Northwest Laboratory (PNL) supervisor located in the 325-A building notified the Westinghouse 340 facility supervisor that approximately 15,140 liters (4,000 gallons) of contaminated liquid needed to be transferred from tank WT-1. Shortly before 1600 hours, the transfer began utilizing a steam jet pump. The jet pump had ran all night and was still operating the next morning. The liquid level on tank WT-1 located indicated decrease approximately 15,140 liters (4,000 gallons) had been transferred. However, the 340 facility reported they had not received the liquid waste. An investigation of the Radioactive Liquid Waste System line-up revealed that an isolation valve on the discharge line, outside the building, was shut, thus precluding discharge of the water to the storage and retention tanks at the 340 Building. The valve was opened and a rush of water was heard. However, the 340 facility storage tank revealed only a negligible amount of water. The 325-A Building was examined for the presence of waste water. Water was noticed on the floor of Room 50-A. No other unexplained volumes of water could be found in 325-A Building. The discharge stop valve for 325-A Building was opened and residual water in the combined drain line allowed to gravity drain to the 340 Building waste storage complex. Tank levels were rechecked and verified that approximately 11,355 liters (3,000 gallons) of low level radioactive water could not be accounted for. A test was initiated in Room 50-A that wetted the floor with 265 liters (70 gallons) clean water. It was estimated that over 189.25 liters (50 gallons) flowed into the confluence of the wall and floor, primarily along the northern and eastern walls. It was the consensus of opinion from all interested parties that the subject water flowed down the drain line, through the sump pump discharge line, into the sump and thence to the floor where it exited through existing cracks to the soil. The floor of Room 50-A in the 325 Building was core drilled to obtain a sample of the earth below the floor. The earth was analyzed to determine if radionuclides present in the soil matched the material that was transferred from the 325-A Building on January 8 and 9, 1979.

Related Sites/Structures: UPR-300-12 was associated with the WT-1 Tank, 325 Sump Tank, 325 Overflow Tank, Room 50-A in the 325-A Building and the 340 Complex.

Process Description: The 325 Radiochemistry Building was built to safely house and handle multi-curie level chemical development work with high activity substances. The High-Level Radiochemistry addition, with its three larger hot cells, housed several pioneering "isotope campaigns". A number of new techniques developed in the 325 Building separated or fractionized specific isotopes from high-level waste by ion exchange, carrier precipitation, solvent extraction, and various combinations of these and other methods. In addition, studies that were part of a Nuclear Waste Vitrification Project took place in the Hot Cells from 1977 to 1980.

Waste Type: Process Effluent

Waste Description: The site received radioactive rinse water overflow containing nitrate ions, promethium-147, fission products, and transuranic nuclides. The total activity in the rinse water was estimated to be 70 Curies, of which 95% was promethium-147. The rinse water contained nitrate ions, promethium-147, fission products, and transuranic radionuclides. Nitrate ions, but no radionuclides, were detected in samples taken from a nearby groundwater monitoring well. PNL (Occurrence Report #79-2) reports that coring through the cement floor of Room 50-A and sampling of the soils below was completed on January 26, 1979.

Code: UPR-300-17 **Classification:** Accepted
Names: UPR-300-17; Metal Shavings Fire; UN-300-17 **Reclassification:** Final Closed Out (2/18/2014)
Type: Unplanned Release **Start Date:** 1/1/1979
Status: Inactive **End Date:** 1/1/1979

Description: The release site has been remediated and Interim Closed Out. It was the asphalt area at the southeast corner of Building 333. The site was not marked or labeled in the field, and its location was not apparent. The site was within a "Radiologically Controlled Area" that surrounded the 333 Building on its north, south and east sides. The asphalt and concrete at the southeast corner of 333 were painted gray and labeled "Fixed Contamination Area." The unpainted asphalt east of the "Fixed Contamination Area" was old and cracked. There was no clear indication where the asphalt was replaced in 1979.

Location: UPR-300-17 was confined to the asphalt area at the southeast corner of Building 333.

Release Description: The release occurred on September 2, 1979, when a garbage can containing oily rags and other waste material caught fire. Rain caused metal shavings, which were believed to be uranium, in the can to ignite. The can was inside a plastic-lined wooden burial box, which also caught on fire. Smoke from the fire contaminated a propane tank located about 3.0 meters (10 feet) away to 500 counts per minute, a forklift about the same distance away to 700 counts per minute, and a 15.2 meter (50 foot) piece of fire hose to 1500 counts per minute. The ground about 0.6 meters (2 feet) from the wooden burial box was contaminated to 15,000 counts per minute for approximately 1.2 meters (4 feet). Contamination was limited to the ground around the wooden burial box, with a radius of approximately 3 meters (10 feet). The propane bottle and fork lift were decontaminated and released. The ground and burial box were covered with plastic. According to site personnel, the asphalt in the contaminated area was removed and the area was patched with new asphalt. The effectiveness of the cleanup was not documented.

Related Sites/ Structures: The site was adjacent to the 618-1 Burial Ground.

Waste Type: Chemicals

Waste Description: The waste consisted oily rags and other waste material, including what was believed to be uranium shavings.

Closure Info: Interim: Remediation of the waste site was performed from May 5 through May 11, 2009. Approximately 445 metric tons (490 US short tons) of concrete, asphalt and soil were removed. The soil within the waste site footprint was excavated to a depth of 1 meter (3 ft) below ground surface, and the resulting 195 bank cubic meters (255 bank cubic yards) of soil was disposed at the Environmental Restoration Disposal Facility.

On July 27, 2009, radiological field screening for beta and gamma activity was conducted following the site remedial action to confirm that waste site excavation was complete.

A large portion of the site was documented as having been painted gray, but it is unknown how much of the painted area has been replaced or has worn away over time. Areas within and

outside of the formerly painted area were either simply loose gravel or unpainted asphalt, and the boundary of the waste site on the north and west sides of the site were extended to the edges of the 333 Building and 3716 Building. The excavation was performed to remove the fixed contamination area composed of painted or unpainted asphalt and concrete. Also, the excavation for the 618-1 waste site remediation extended into and below the eastern portion of the WIDS boundary for the UPR-300-17 waste site. The area excavated as part of the 618-1 waste site is therefore excluded from the UPR-300-17 waste site remediation scope and will be closed out as part of the 618-1 waste site scope and was closed out as part of the 618-1 waste site scope CVP-2010-00001.

Final (2/18/2014): This group of sites are listed in the 300-FF-2 Record of Decision. Institutional Controls to maintain industrial land use are required.

Code:	UPR-300-38	Classification:	Accepted
Names:	UPR-300-38; 313 Slab; Demolished 313 Building Foundation; Soil Contamination Beneath the 313 Building	Reclassification	Final Closed Out (5/12/2014)
Type:	Unplanned Release	Start Date:	
Status:	Inactive	End Date:	
Description:	The Unplanned Release site has been Interim Closed Out. In 2014, the site was reclassified to Final Closed Out. The contamination resulted from multiple unplanned release events. The 313 building was demolished in 2004 and the foundation/slab was left in place. UPR-300-38 consisted of the contaminated soil beneath the 313 Building, as well as the foundation. The 313 building foundation was removed in 2011. WIDS sites 313 URO and UPR-300-44 were consolidated with UPR-300-38.		
Location:	The soil contamination is beneath the southern half of the 313 Building. The 313 Building is located at the north end of the main 300 Area (within the security fence). It is located north of Ginko Street, east of the 303K, 305, and 314 Buildings, and west of the 3712 and 3720 Buildings.		
Release Description:	Unplanned release site UPR-300-38 represents the area of soil contamination beneath the southern half of the 313 Building. Because of a general failure of the process sewer line beneath the building, any discharges into the process sewer may have contributed to the contamination.		
	In the early 1970's, during floor repairs in the 313 Building, liquid was observed flowing over the acid brickwork installed beneath the concrete floor. The liquid was collected and processed through the uranium recovery operation. Some of the subfloor was removed and replaced. According to site personnel, the pipe trench (which runs east to west) and the filter press were lined with stainless steel after the spill. The sump in this trench which leads to the process sewer has been grouted.		
Related Sites/ Structures:	The contamination is associated with releases from the 313 Uranium Recovery Operations (WIDS Site 313 URO) and the 300 Area Waste Acid Treatment System (300 WATS). WIDS sites 313 URO and UPR-300-44 were Consolidated into UPR-300-38.		
Waste Type:	Chemicals		
Waste Description:	Materials released to the soil beneath the building may have included uranium-bearing acid (nitric and sulfuric acid with uranium in solution), neutralized acid waste (typically sodium fluoride, sodium nitrate, sodium dichromate, and sodium sulfate in solution with precipitates of uranium, chromium, copper and zirconium), etch acids (nitric, hydrofluoric, sulfuric, and chromic acids), tetrachloroethene (perchloroethylene), sodium hydroxide solutions, and contaminated water.		

Closure Info: Interim (4/30/2012): The UPR-300-38 waste site consisted of contaminated soil beneath the 313 Building, as well as the foundation. The contamination resulted from multiple unplanned release events. The 313 ESSP (East Side Storage Pad) waste site was the footprint of a large concrete pad adjacent to the southeastern side of the former 313 Building, with an asphalt ramp that connected the pad to Ginko Street. The 300- 270 waste site was the area of a release of whitish storm water that came from a pipe under the loading dock on the east side of the former 313 Building. The pipe drained the roof of the former 313 Building.

Remediation of the UPR-300-38 waste site was performed from January 10, 2010, through June 2, 2011. The soil within the northern portion of the waste site footprint was excavated to an approximate average depth of 1 meter (3.3 ft) below ground surface (bgs). The southern area of the waste site was excavated to an approximate average depth of 2 meters (6.6 ft) bgs, with limited areas of deeper soil contamination to 5 meters (16.4 ft) bgs. The resulting 15,204 bank cubic meters (BCM) (19,887 bank cubic yards [BCY]) of soil was disposed at the Environmental Restoration Disposal Facility (ERDF).

Remediation of a large portion of the 313 ESSP waste site was performed by the excavation of concrete, asphalt, and underlying soil during the remediation of the UPR-300-38 waste site and the adjacent area near the footprint of the former 303-F Building. This work was performed on July 8, 2011. The soil within the waste site footprint was excavated to a depth of 1 meter (3.3 ft) bgs, and the resulting 153 BCM (205 BCY) of soil was disposed at ERDF. Approximately 98 BCM (128 BCY) was associated with the UPR-300-38 excavation; the remainder (55 BCM [72 BCY]) was associated with the 313 ESSP excavation near the footprint of the former 303- F Building. An additional 38 BCM (50 BCY) was removed from the northeast corner and the southern edge of the 313 ESSP waste site on August 26, 2011, resulting in a total of 191 BCM of debris and soil removed from the 313 ESSP waste site.

Remediation of the 300- 270 waste site was performed May 23, 2011. The soil within the waste site footprint was excavated to a depth of 0.5 meter (1.6 ft) bgs, and the resulting 40 BCM (52 BCY) of soil was disposed at ERDF.

A total of 15,435 bank cubic meters (20,194 bank cubic yards) of soil and debris from the remediation of all three waste sites was disposed at the Environmental Restoration Disposal Facility.

Final: The UPR-300-38, Soil Contamination Beneath the 313 Building; 313 ESSP, 313 East Side Storage Pad; and 300-270, Unplanned Release at 313 Building waste sites were either within or immediately adjacent to the footprint of the demolished 313 Building. The UPR-300-38 waste site consisted of contaminated soil beneath the 313 Building, as well as the foundation. The contamination resulted from multiple unplanned release events. The 313 ESSP waste site was the footprint of a large concrete pad adjacent to the southeastern side of the former 313 Building, with an asphalt ramp that connected the pad to Ginko Street. The 300-270 waste site was the area of a release of whitish storm water that came from a pipe under the loading dock on the east side of the former 313 Building. The pipe drained the roof of the former 313 Building. Remediation of the UPR-300-38 waste site was performed from January 2010 through June 2011. Remediation of a large portion of the 313 ESSP waste site occurred July 8 and August 26, 2011 and included excavation of concrete, asphalt, and underlying soil. Remediation of the 300-270 waste site was performed May 23, 2011. The maximum depth of the remediation at the UPR-300-38 waste site was 5 meters (16.4 ft) below ground surface. The 313 ESSP and 300-270 waste sites were remediated to 1 meters (3.3 ft) bgs.

The 300-270, 313 ESSP, and UPR-300-38 waste sites were remediated and have been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). Site-specific RESRAD modeling predicts that the radionuclide verification focused sampling results meet the excess cancer risk and allowable radiation dose

and are protective of groundwater and the Columbia River under an industrial land use scenario. The remaining verification sampling results show that the site meets the CUL's for direct exposure and groundwater protection and river protection and support an industrial land use scenario. Contamination at these waste sites did not extend into the deep zone soils. Because the remediation of the waste sites did not meet residential land use cleanup levels, the waste sites require institutional controls to maintain industrial land use. In accordance with this evaluation, the verification sampling results support a reclassification of the 300-270, 313 ESSP, and UPR-300-38 waste sites to Final Closed Out.

Code:	UPR-300-39	Classification:	Accepted
Names:	UPR-300-39; Sodium Hydroxide Leak at 311 Tank Farm; UN-300-39	Reclassification	Final Closed Out (5/12/2014)
Type:	Unplanned Release	Start Date:	1/1/1954
Status:	Inactive	End Date:	1/1/1954
Description:	The waste site has been remediated and Interim Closed Out. The waste site was the soil adjacent to the caustic storage tanks in the 311 Tank Farm. The location and extent of the release was not visibly discernible in the field. The ground around the two tanks was covered by a concrete containment, that was surrounded by more concrete and gravel. The concrete containment was not marked or labeled in any way to warn about excavating in the area. In February 2006, the 311 Tank Farm and concrete containment was demolished, including the two sodium hydroxide tanks that had been labeled "Empty."		
Location:	UPR-300-39 occurred in the soil adjacent to the caustic storage tanks in the 311 Tank Farm, which is located between the 303-F and 303-G Buildings.		
Release Description:	An unplanned release occurred in the 311 Tank Farm when one of two 37,850 liter (10,000 gallon) sodium hydroxide tanks leaked. A 50 percent sodium hydroxide solution contaminated soil around the tanks.		
Related Sites/ Structures:	UPR-300-39 was associated with the caustic storage tanks in the 311 Tank Farm.		
Process Description:	The 311 Building and Tank Farm were constructed to distill methanol for re-use. They operated until 1971 when the last single-pass reactor closed at the Hanford Site. The 311 Building and 311 Tank Farm wastes consisted of chemical spills and leaks (primarily methanol, trichloroethylene and perchloroethylene).		
Waste Type:	Chemicals		
Waste Description:	The waste consisted of caustic solution containing 50 percent sodium hydroxide solution.		
Closure Info:	Interim (4/13/2012): Remediation of the 300-40, UPR-300-40, UPR-300-39, and UPR-300-45 waste sites was performed from May 24, 2010, through July 20, 2010. The soil within the waste site footprints was excavated to a depth of 1 meter (3.3 ft) below ground surface, and the resulted in 911 bank cubic meters (1,192 bank cubic yards) of soil being disposed at the Environmental Restoration Disposal Facility. On March 8, 2011, radiological field screening for beta and gamma activity was conducted in the 300-40, UPR-300-40, UPR-300-39, and UPR-300-45 waste site areas. The radiological field screening surveys did not indicate any significant residual radiological activity.		
	Final: The 300-40, Corrosion of Vitrified Clay Process Sewer Pipe, UPR-300-40, Acid Release at the 303-F Pipe Trench, UPR-300-39, Sodium Hydroxide Leak at 311 Tank Farm, and UPR-300-45, 303-F Building Uranium-Bearing Acid Spill were located in close proximity. The		

southern section of the 300-40 waste site consists of the area around the footprint of the demolished 303-F Building and 311 Tank Farm. The northern section of the 300-40 waste site is within the footprint of the demolished 3712 Building. The UPR-300-40 waste site is associated with the drain pipe connections between the 303-F Building and the 300 Area process sewer. The waste consisted of uranium-bearing acid waste containing nitric and sulfuric acid with uranium in solution and chromic acids with copper and zinc in solution. The UPR-300-39 waste site is the soil adjacent to the caustic storage tanks in the 311 Tank Farm. The UPR-300-45 waste site is the soil beneath the former uranium-bearing acid transfer pipeline, adjacent to the 303-F Building. The uranium-bearing acid transfer pipeline ran through the pipe trench from the 333 Building to the valve box at the southeast corner of the 313 Building outside the Uranium Recovery Room. The leak contained uranium-bearing waste acids identified as nitric acid and sulfuric acid with uranium in solution. Remediation occurred in 2010 to a depth of 3 feet.

The 300-40, UPR-300-40, UPR-300-39, and UPR-300-45 waste sites were remediated and have been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). Verification sampling results show that concentrations of COCs meet the CULs for direct exposure and groundwater protection and river protection and support a residential land use scenario. Contamination at the 300-40, UPR-300-40, UPR-300-39, and UPR-300-45 waste sites did not extend into the deep zone (below 4.6 meters [15 ft]). Therefore, institutional controls to prevent uncontrolled drilling or excavation into the deep zone of the site are not required. In accordance with this evaluation, the verification sampling results support a reclassification of the 300-40, UPR-300-40, UPR-300-39, and UPR-300-45 waste sites to Final Closed Out.

Code:	UPR-300-40	Classification:	Accepted
Names:	UPR-300-40; Acid Release at the 303-F Pipe Trench; UN-300-31; UN-300-40; UPR-300-31	Reclassification	Final Closed Out (5/12/2014)
Type:	Unplanned Release	Start Date:	1/1/1974
Status:	Inactive	End Date:	1/1/1974
Description:	The waste site has been remediated and Interim Closed Out. The release was associated with leaks from the drain pipe connections between the 303-F Building and the 300 Area process sewer. The release site to the soil was located between the 311 Tank Farm and the 303-F Building.		
Location:	UPR-300-40 occurred in the soil between the 311 Tank Farm and the 303-F Building.		
Release Description:	In October 1974, broken drain connections between the pipe trench, the 303-F Building, and the process sewer were discovered. The bottom of the trench was severely eroded, indicating that a spill had occurred. The trench floor is still contaminated. The total volume of spilled material is unknown; however, evidence of uranium contamination in the soil has been found.		
Related Sites/ Structures:	UPR-300-40 was associated with the drain connections between the 303-F Building and the process sewer.		
Process Description:	The 303-F and 303-K Buildings were upgraded in 1954 as part of the project 313 Building expansion and the construction of the 311 Tank Farm. The 303-F Building served as a chemical makeup facility for the solutions (mostly acids) used in the aluminum cleaning, stripping, and anodizing processes performed in the 313 Building. In 1973, it became the pumping facility for the 300 Area Waste Acid Treatment System (WATS) operations. The waste acids treated in the WATS operation included nitric, sulfuric, hydrofluoric, and chromic-nitric-sulfuric acids bearing uranium, Zircaloy-2 components, copper, beryllium, and other fuel fabrication materials.		

Waste Type: Chemicals

Waste Description: The waste consisted of uranium-bearing acid waste containing nitric and sulfuric acid with uranium in solution and chromic acids with copper and zinc in solution.

Closure Info: Interim (4/13/2012): Remediation of the 300-40, UPR-300-40, UPR-300-39, and UPR-300-45 waste sites was performed from May 24, 2010, through July 20, 2010. The soil within the waste site footprints was excavated to a depth of 1 meter (3.3 ft) below ground surface, and the resulted in 911 bank cubic meters (1,192 bank cubic yards) of soil being disposed at the Environmental Restoration Disposal Facility. On March 8, 2011, radiological field screening for beta and gamma activity was conducted in the 300-40, UPR-300-40, UPR-300-39, and UPR-300-45 waste site areas. The radiological field screening surveys did not indicate any significant residual radiological activity.

Final: The 300-40, Corrosion of Vitrified Clay Process Sewer Pipe, UPR-300-40, Acid Release at the 303-F Pipe Trench, UPR-300-39, Sodium Hydroxide Leak at 311 Tank Farm, and UPR-300-45, 303-F Building Uranium-Bearing Acid Spill were located in close proximity. The southern section of the 300-40 waste site consists of the area around the footprint of the demolished 303-F Building and 311 Tank Farm. The northern section of the 300-40 waste site is within the footprint of the demolished 3712 Building. The UPR-300-40 waste site is associated with the drain pipe connections between the 303-F Building and the 300 Area process sewer. The waste consisted of uranium-bearing acid waste containing nitric and sulfuric acid with uranium in solution and chromic acids with copper and zinc in solution. The UPR-300-39 waste site is the soil adjacent to the caustic storage tanks in the 311 Tank Farm. The UPR-300-45 waste site is the soil beneath the former uranium-bearing acid transfer pipeline, adjacent to the 303-F Building. The uranium-bearing acid transfer pipeline ran through the pipe trench from the 333 Building to the valve box at the southeast corner of the 313 Building outside the Uranium Recovery Room. The leak contained uranium-bearing waste acids identified as nitric acid and sulfuric acid with uranium in solution. Remediation occurred in 2010 to a depth of 3 feet.

The 300-40, UPR-300-40, UPR-300-39, and UPR-300-45 waste sites were remediated and have been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). Verification sampling results show that concentrations of COCs meet the CULs for direct exposure and groundwater protection and river protection and support a residential land use scenario. Contamination at the 300-40, UPR-300-40, UPR-300-39, and UPR-300-45 waste sites did not extend into the deep zone (below 4.6 meters [15 ft]). Therefore, institutional controls to prevent uncontrolled drilling or excavation into the deep zone of the site are not required. In accordance with this evaluation, the verification sampling results support a reclassification of the 300-40, UPR-300-40, UPR-300-39, and UPR-300-45 waste sites to Final Closed Out.

Code: UPR-300-41	Classification: Accepted
Names: UPR-300-41; 300 Area #340 Building Phosphoric Acid Spill; UN-300-41	Reclassification: Final Closed Out (2/18/2014)
Type: Unplanned Release	Start Date: 6/3/1986
Status: Inactive	End Date: 6/3/1986
Description: The site was Closed Out in 1999. It was considered to be Final Closed Out in 2014. The Unplanned Release involved an acid spill to asphalt and soil in the 340 Complex yard. The spilled material was neutralized, absorbed and packed into drums in 1986.	
Location: UPR-300-41 occurred approximately 4.6 meters (15 feet) west of the 340 Building. Facility personnel do not know the exact location of the spill.	

Release Description: Three drums, allegedly containing nitric acid, were received from Battelle for use in a charcoal filter efficiency test on April 17, 1986. On June 3, 1986, one of the 55 gallon plastic drums was found to have failed. Approximately 113.6 liters (30 gallons) of liquid had contaminated part of an asphalt pad and an area of soil next to the pad.

The drum was labeled "Sulfuric Acid." The initial clean up involved using sodium bicarbonate and water to neutralize the acid. The spill area did not respond to the clean up method so a sample of the spilled liquid was analyzed. The results indicated the spilled material was actually phosphoric acid, with high concentrations of chromium, manganese, iron, and nickel in solution. The drum had been labeled incorrectly.

Related Sites/ Structures: UPR-300-41 was associated with an asphalt pad west of the 340 Building.

Waste Type: Chemicals

Waste Description: A detailed analysis on a sample taken from the leaking drum showed the released liquid consisted of phosphoric acid containing 14,000 parts per million chromium, 1,900 parts per million manganese, 1,700 parts per million iron, and 400 parts per million nickel.

Closure Info: Interim: The WIDS Reclassification Form (99-011) states the spilled material was neutralized, absorbed and packed into drums in 1986.

When the original neutralization process did not respond as expected, it was determined the drum was labeled incorrectly. Litmus paper indicated a pH of 6. A sample was collected and determined the drum contents was phosphoric acid containing chromium, manganese, iron and nickel.

Contaminated soils were excavated to a maximum depth of 4 inches. The soil was placed in drums for disposal. The asphalt pad was scrubbed with detergent. Cleanup was judged to be complete when the concentration of chromium in soil samples was less than 5 parts per million.

Final (2/18/2014): This group of sites is listed in the 300-FF-2 and 300-FF-5 Records of Decision and the 300-FF-1 ROD Amendment as requiring no further action. They were reclassified to Final Closed Out in February 2014 on reclassification form 2014-009.

Code: UPR-300-42	Classification: Accepted
Names: UPR-300-42; 300 Area Powerhouse Fuel Oil Spill; UN-300-42	Reclassification: Final Closed Out (5/12/2014)
Type: Unplanned Release	Start Date: 1/1/1983
Status: Inactive	End Date: 1/1/1983

Description: The waste site has been remediated and Interim Closed Out with the 300-6 waste site remediation. In 2014, the site was reclassified to Final No Action. The group of sites were evaluated and Interim Closed out in a single document and on a single reclassification form (form 2011-107) This release was not visible on the surface. The release was an overflow of Number 6 fuel oil onto the ground adjacent to the Number 2 Day Tank, an underground storage tank. The surface area around the day tanks was paved with asphalt.

Because the unplanned release extended below the powerhouse structure, remediation of UPR-300-42 was deferred until the 384 powerhouse was demolished. During the demolition of the 384 building below-grade structures in 2009-2010, shallow dark, stained soil was encountered near the northwest corner of the building near the approximate location of the 300-223 day tanks and UPR-300-42 waste site. The Post Demolition Summary Report for the 384 and 3503

Location: Buildings (CCN-152459) stated that the UPR-300-42 waste site was removed with the building. The release occurred adjacent to the Number 2 Day Tank on the north side of the 384 Powerhouse.

Release Description: Due to an automatic shutoff failure, approximately 750 to 1135 liters (200 to 300 gallons) of number 6 fuel oil overflowed from the Number 2 Day Tank and spilled onto the ground.

Related Sites/ Structures: UPR-300-42 was associated with the Number 2 Day Tank (WIDS Site 300-223) and the 384 Powerhouse.

Waste Type: Oil

Waste Description: The release consisted of approximately 750 to 1135 liters (200 to 300 gallons) of #6 fuel oil.

Closure Info: Interim (1/9/2012): The 300-6 waste site (fuel oil bunkers) was expected to be excavated to groundwater, a depth of approximately 15.8 meters (52 ft) below ground surface (bgs), as necessary to remediate contaminated soil. Remediation of the waste site was performed from August 2 to December 8, 2010. The western portion of the 300-6 waste site excavation did reach the groundwater, and a pool of water remains in the floor of the excavation. The excavation was approximately 15 meters (49.5 ft) deep in the 300-6 west borehole location (when measured to the surface of the pool of water) and approximately 11.5 meters (37.7 ft) deep in the 300-6 east borehole location. The 300-6 and associated waste sites' excavation resulted in approximately 34,770 bank cubic meters (45,477 bank cubic yards) of material removed for disposal at the Environmental Restoration Disposal Facility (ERDF).

Debris (piping and concrete) and soil from the remediation of the 300-6 and associated waste sites were direct loaded to ERDF. No overburden soil stockpiles were associated with the waste sites as a result of remediation, and no anomalies were noted.

The 300-123 UIC was identified as a WIDS waste site. The french drain was removed as part of the layback to remove the contaminated soil at the 300-6 waste site. The french drain consisted of soil and rock that extended to approximately 1.4 meters (4.5 ft) bgs. The existing floor of the 300-6 waste site excavation is approximately 11.3 m (37 ft) bgs.

The 300-65, 300-66, 300-122, and 300-124 UICs were located within the footprint of the 300-6 excavation layback and also removed during the 300-6 excavation. The 3715, 303E and 303J building slabs were removed during the 300-6 waste site excavation because they were located in the excavation layback as well.

The 300-268 site was located within the 300-6 layback area. It was excavated to a depth of 3.0 meters (9.8 ft).

During excavation of the 300-6 waste site, it was verified that the eastern half of the 300-273 waste site pipeline had been previously removed. In addition, as the project conducted test pits along the western half of the 300-273 waste site pipeline right-of-way on November 3, 2010, no pipeline structure was encountered at the elevations presented in the as-built drawings for the pipeline (USAEC 1974). Also in November 2010, the project excavated two test pits along the former 384 Powerhouse foundation within the UPR-300-42 waste site. No below-grade structure was noted, and no visible soil staining was observed, as was expected since the site was reportedly removed in 2009.

During excavation of the 300-6 waste site, it was verified that the eastern half of the 300-273 waste site pipeline had been previously removed. In addition, as the project conducted test pits along the western half of the 300-273 waste site pipeline right-of-way on November 3, 2010, no pipeline structure was encountered at the elevations presented in the as-built drawings for the

pipeline. Also in November 2010, the project excavated two test pits along the former 384 Powerhouse foundation within the UPR-300-42 waste site. No below-grade structure was noted, and no visible soil staining was observed, as was expected since the site was reportedly removed in 2009 with the demolition of the 384 powerhouse structure.

Final: The 300 Area Fuel Oil bunkers and associated waste sites were remediated in 2010. The excavation extended to groundwater at a depth of 52 feet. The 300-6, 300-123, 300-268, 300-273, and UPR-300-42 waste sites were remediated and have been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). Verification sampling results show that the site meets the CUL's for direct exposure and groundwater protection and river protection and support a residential land use scenario. Contamination that extended into the deep zone (greater than 4.6 meters [15 ft] bgs) has been removed; therefore, institutional controls to prevent uncontrolled drilling or excavation into the deep zone are not required. In accordance with this evaluation, the verification sampling results support a reclassification of the 300-6, 300-123, 300-268, 300-273, and UPR-300-42 waste sites to Final Closed Out.

Code:	UPR-300-45	Classification:	Accepted
Names:	UPR-300-45; 303-F Building Uranium-Bearing Acid Spill; UN-300-45	Reclassification	Final Closed Out (5/12/2014)
Type:	Unplanned Release	Start Date:	1/1/1985
Status:	Inactive	End Date:	1/1/1985
Description:	The waste site has been remediated and Interim Closed Out. The waste site was the soil beneath the former uranium-bearing acid transfer piping, adjacent to the 303-F Building. The uranium-bearing acid transfer line ran through the pipe trench from the 333 Building to the valve box at the southeast corner of the 313 Building outside the Uranium Recovery Room. The 5.1 centimeter (2 inch) stainless steel line from the top of the valve box, ran up the wall of the 313 Building and entered the 313 building as an overhead line attached to the Uranium Recovery Room.		
Location:	The release occurred in the soil beneath the transfer piping, east of the 303-F Building, which lies at the southeast corner of the 313 Building.		
Release Description:	In February 1985, a leak occurred along the uranium-bearing acid transfer line. The leak was the result of a gasket failure caused by freezing of the solution in the line. The gasket leak spilled to the valve box, the Pipe Trench below the pipe joint and to the paved area between the 313 Building and the 303-F Building. The soil beneath the leaking gasket was reported to have been contaminated. The gasket was replaced and heat tracing was installed on the exposed piping.		
Related Sites/ Structures:	UPR-300-45 was associated with the Pipe Trench (WIDS Site 300-224), the uranium bearing waste acid transfer line (WIDS Site 300-219) from the 333 Building, and the 313 Uranium Recovery Operation (WIDS Site 313 URO).		
Waste Type:	Process Effluent		
Waste Description:	The leak contained uranium-bearing waste acid identified as nitric and sulfuric with uranium in solution. Analysis showed the solution to contain 3,480 parts per million nitrate, 6,960 parts per million sulfate, and 920 parts per million uranium.		
Closure Info:	Interim (4/13/2012): Remediation of the 300-40, UPR-300-40, UPR-300-39, and UPR-300-45 waste sites was performed from May 24, 2010, through July 20, 2010. The soil within the waste site footprints was excavated to a depth of 1 meter (3.3 ft) below ground surface, and the resulted in 911 bank cubic meters (1,192 bank cubic yards) of soil being disposed at the		

Environmental Restoration Disposal Facility. On March 8, 2011, radiological field screening for beta and gamma activity was conducted in the 300-40, UPR-300-40, UPR-300-39, and UPR-300-45 waste site areas. The radiological field screening surveys did not indicate any significant residual radiological activity.

Final: The 300-40, Corrosion of Vitrified Clay Process Sewer Pipe, UPR-300-40, Acid Release at the 303-F Pipe Trench, UPR-300-39, Sodium Hydroxide Leak at 311 Tank Farm, and UPR-300-45, 303-F Building Uranium-Bearing Acid Spill were located in close proximity. The southern section of the 300-40 waste site consists of the area around the footprint of the demolished 303-F Building and 311 Tank Farm. The northern section of the 300-40 waste site is within the footprint of the demolished 3712 Building. The UPR-300-40 waste site is associated with the drain pipe connections between the 303-F Building and the 300 Area process sewer. The waste consisted of uranium-bearing acid waste containing nitric and sulfuric acid with uranium in solution and chromic acids with copper and zinc in solution. The UPR-300-39 waste site is the soil adjacent to the caustic storage tanks in the 311 Tank Farm. The UPR-300-45 waste site is the soil beneath the former uranium-bearing acid transfer pipeline, adjacent to the 303-F Building. The uranium-bearing acid transfer pipeline ran through the pipe trench from the 333 Building to the valve box at the southeast corner of the 313 Building outside the Uranium Recovery Room. The leak contained uranium-bearing waste acids identified as nitric acid and sulfuric acid with uranium in solution. Remediation occurred in 2010 to a depth of 3 feet.

The 300-40, UPR-300-40, UPR-300-39, and UPR-300-45 waste sites were remediated and have been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). Verification sampling results show that concentrations of COCs meet the CULs for direct exposure and groundwater protection and river protection and support a residential land use scenario. Contamination at the 300-40, UPR-300-40, UPR-300-39, and UPR-300-45 waste sites did not extend into the deep zone (below 4.6 meters [15 ft]). Therefore, institutional controls to prevent uncontrolled drilling or excavation into the deep zone of the site are not required. In accordance with this evaluation, the verification sampling results support a reclassification of the 300-40, UPR-300-40, UPR-300-39, and UPR-300-45 waste sites to Final Closed Out.

Code:	UPR-300-46	Classification:	Accepted
Names:	UPR-300-46; Contamination North of 333 Building	Reclassification	Final Closed Out (2/18/2014)
Type:	Unplanned Release	Start Date:	1/1/1989
Status:	Inactive	End Date:	1/1/1989
Description:	In January 2010, the UPR-300-46 waste site was remediated by excavating to remove contaminated soil and debris. All debris and excavation materials were disposed into the Environmental Restoration Disposal Facility.		
	The release site was a layer of radioactively contaminated soil found during a pipe trench excavation. There is currently no visual evidence of the release. The area is not marked or posted. The gravel east of the telephone pole along the north perimeter fence appears to be slightly newer than other gravel in the vicinity.		
Location:	The release site was an area of soil inside the 333 building fence. It occurred east of a telephone pole at the north end of the 333 facility property.		
Release Description:	On June 21, 1989, radioactively contaminated soil was discovered while excavating a pipe trench north of the 333 Building. The contamination appeared to be confined to a narrow band of soil approximately 2.5 to 5 centimeters (1 to 2 inches) thick.		

Related Sites/ Structures: UPR-300-46 was associated with the 333 Building and a french drain known as Miscellaneous Stream #455 (See WIDS Site 300-109).

Waste Type: Process Effluent

Waste Description: The contaminated soil was analyzed, and it was determined that the soil did not contain any significant quantities of hazardous chemicals. The truck load of contaminated soil was disposed of as low-level waste. The contamination was likely caused by a spill of Uranyl Nitrate.

Closure Info: Interim: Remediation of the UPR-300-46 waste site was performed from April 28 through June 4, 2009. The soil within the waste site footprint was excavated to a depth of 1 meter (3 ft) below ground surface (bgs), and the resulting 75 bank cubic meters (BCM) (100 bank cubic yards [BCY]) of soil was disposed at the Environmental Restoration Disposal Facility (ERDF). Remediation of the 300-109 waste site was performed from April 28 through April 29, 2009. The soil and asphalt within the waste site footprint were excavated to an average depth of 2.6 meters (8.5 ft) bgs, with a maximum depth of 3.7 meters (12 ft) below ground surface at the location of the drain. The resulting 325 BCM (425 BCY) of soil was disposed at ERDF. The french drain and associated vitrified clay pipe was found and removed during the remediation. The PVC pipe noted in documentation from the 1990's was not found during remediation. A radiological survey was done to confirm the excavations were complete.

This report demonstrates that the 300-109, 333 Building Stormwater Runoff and UPR-300-46, Contamination North of 333 Building sites have met the rural-residential scenario RAOs established in the RDR/RAWP and the ROD. The evaluation shows that the sites have been successfully remediated and that there are no residual hazardous/dangerous materials present above the RAOs in the soil. Therefore, the 300-109 and UPR-300-46 waste sites are protective of human health, groundwater, and the Columbia River.

Final (2/18/2014): This group of sites are listed in the 300-FF-2 Record of Decision. Institutional Controls to maintain industrial land use are required.

Code: UPR-300-48 **Classification:** Accepted

Names: UPR-300-48; 325 Building Basement Topsy Pit **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:** 1/1/1991

Description: The site is radioactively contaminated soil that occurred as a result of a release through a crack in the process sewer drain pipe elbow.

Location: The site is located underneath the 325 Building foundation in room 30 under a process sewer drain elbow.

Release Description: On October 23, 1991, during the confirmation of the 325 Building sewer system configuration, a potential problem with one of the drain lines was discovered. As a precaution, residual material at the bottom of the sump was analyzed. This analysis showed the presence of mercury (700 parts per million) in the sample. The presence of mercury in the sump was believed to be a result of prior, not current, building operations. Further analysis of the sewer line discovered an elbow in a feeder line to the main line had deteriorated and allowed liquids to leak to soil under the basement floor. Soil samples were taken and analyzed.

Related Sites/ Structures: The site is associated with the Process Sewer.

Waste Type: Soil

Waste Description: The site received radioactive liquid from a leak in the process sewer drain pipe. The site was discovered during dye testing of drains during development of the Facility Effluent Monitoring Plan development for the 325 Building. The contamination may have resulted from routine releases and accumulated in the soil under the crack. Samples of the soil under the drain were analyzed for gross radioactivity and for hazardous metals by TCLP. Radioactivity up to 1700 disintegrations per minute alpha was detected. The TCLP results were below regulatory limits.

Code: UPR-600-22

Classification: Accepted

Names: UPR-600-22; WPPSS Windrow Site; 600-21

Reclassification: Final Closed Out (8/14/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The site has been remediated and reclassified to Final Closed Out. It consisted of a series of small parallel berms, which were approximately 0.6 meters (2 feet), 0.9 meters (3 feet) wide and 91 meters (100 yards) long. The berms formed a triangle approximately 137 meters (150 yards) by 91 meters (100 yards) long. Perimeter berms were approximately 1.2 meters (4 feet) tall.

Location: The site is located west of the former Washington Public Power Supply System (WPPSS) Plant #2, adjacent to the north fence of the 618-11 Burial Ground. (WPPSS has been renamed Energy Northwest)

Release Description: The area was contaminated prior to 1972 with particulate fallout from caisson burial activities in the 618-11 Burial Grounds. UPR-600-9 occurred on April 14, 1967 and indicates a fan-shaped area (approximately 230 meters [250 yards] long and 91 meters [100 yards] wide) was contaminated during a routine cask unloading operation. The wind on that day was documented to be between 10 and 15 miles per hour to the northeast. The dose rate at the dump chute and pipe unit was 450 milirad per hour. Radiological surveys of the ground 90 ft away from the burial site were 50,000 counts per minute and diminished further from the burial site. Radiological readings beyond 750 feet from the burial site were at background levels. The contamination found outside the burial ground fence was turned over with bulldozer to bury the contamination and soil windrows were created.

Related Sites/ Structures: The site is associated with UPR-600-9 and 618-11.

Waste Type: Soil

Waste Description: The area was contaminated prior to 1972 with particulate fallout from burial activities in the 618-11 Burial Grounds. The contaminated area was covered by scraping the affected ground into windrows. On October 24, 1972, a backhoe was used to cut across each windrow at a spacing of every 15 meters (50 feet) to a depth of 15 centimeters (6 inches) below ground level. Radiological surveys were made of all soils removed and of the walls of each cut. No beta, gamma, or alpha radioactivity was detected above the normal background of 100 counts/minute.

Closure Info: Final (8/14/2015): A global positioning environmental radiological surveyor (GPERS) survey was conducted in September 2011. One area of slightly elevated gamma activity was detected.

Soil removal from the two failed sample locations at the UPR-600-22 waste site was conducted between March 23 and 25, 2015. The remediation extended to approximately 1.2 meters (4 ft) below ground surface, resulting in approximately 40 bank cubic meters (52 bank cubic yards) of soil being removed and disposed at ERDF. Following soil removal, the windrows were flattened and a GPERS survey of the entire waste site was conducted. No elevated radiological activity was observed.

1100-EM-1

Code: 1100-1 **Classification:** Accepted
Names: 1100-1; 1171 Building Sandpit Spills; Battery Acid Pit; UPR-1100-1 **Reclassification** Deleted From NPL (9/30/1996)
Type: Depression/Pit (nonspecific) **Start Date:** 1/1/1954
Status: Inactive **End Date:** 1/1/1977

Description: This site has been cleaned up under the 1100 Area Record of Decision. The 1100-1 Battery Acid Pit was an unlined, sand-filled pit excavated in native soil. The site is not visible at the surface. The pit was backfilled to grade when it was withdrawn from service.

Location: The unit is located below grade, northwest of the 1176 Building.

Related Sites/ Structures: The unit was associated with the 1100 Area Maintenance and Service Operations.

Process Description: The unit was used to dispose of battery acid from vehicle maintenance activities. Information suggests that the unit may have been used to dispose of waste oil, waste antifreeze, and spent solvents.

Waste Type: Chemicals

Waste Description: Historical documents record an estimated 15,000 gallons (57,000 liters) of battery acid wastes may have been disposed of between 1954 and 1977. Other substances including antifreeze and solvents may have also been disposed of at the site. The sand lining was removed and deposited in an undisclosed location when the sand became saturated. New sand was then added to the pit for further acid disposal.

Code: 1100-2 **Classification:** Accepted
Names: 1100-2; Paint and Solvent Pit; UPR-1100-2 **Reclassification** Deleted From NPL (9/30/1996)
Type: Depression/Pit (nonspecific) **Start Date:** 1/1/1954
Status: Inactive **End Date:** 1/1/1985

Location: The unit is located along a railroad spur north of the 1171 Building.

Related Sites/ Structures: The unit is associated with the 1100 Area maintenance and construction operations. The pit is also known as Gravel Pit #2 (site code 1100-14).

Process Description: The pit served as a disposal site for construction debris. Paints, solvents, and thinners have been reportedly disposed of at this location.

Waste Type: Chemicals

Waste Description: Paint, solvents, and thinners may have been disposed of in this location.

Waste Type: Construction Debris

Waste Description: The site received construction debris from Hanford Site demolition activities. Principal components of the waste included concrete rubble, asphalt, and wood debris.

Code: 1100-3 **Classification:** Accepted

Names: 1100-3; Antifreeze and Degreaser Pit; Antifreeze Pit; UPR-1100-3 **Reclassification** Deleted From NPL (9/30/1996)

Type: Depression/Pit (nonspecific) **Start Date:** 1/1/1979

Status: Inactive **End Date:** 1/1/1985

Description: The site was originally a gravel pit used as a source of backfill material. This contaminated soils have been cleaned up under the 1100 Area Record of Decision. The site currently appears as a shallow roughly circular depression.

Location: The unit is located north of 1171 Building and west of the Hanford Rail Line inside Gravel Pit #3 (Site Code 1100-15).

Related Sites/ Structures: The waste is related to Hanford construction activities and 1171 Building Operations. The site is associated with Hanford Gravel Pit #3.

Process Description: The site was used to dispose of waste construction material. Prior to use as a disposal site, the unit was a sand and gravel pit known as Pit #3 (Site Code 1100-15).

Waste Type: Construction Debris

Waste Description: Construction waste material including roofing and concrete rubble was disposed of at this site.

Waste Type: Chemicals

Waste Description: Ethylene glycol, degreasing solvents and wash water from engine cleaning may have been disposed of at this site although it is not documented.

Code: 1100-4 **Classification:** Accepted

Names: 1100-4; 1171 Building Spills; Antifreeze Tank Site; UN-1100-4; UPR-1100-4 **Reclassification** Deleted From NPL (9/30/1996)

Type: Storage Tank **Start Date:** 1/1/1976

Status: Inactive **End Date:** 1/1/1986

Description: This site was cleaned up under the 1100 Area Record of Decision. This site is the former location of a steel underground storage tank.

Location: The unit was located below grade under the northern section of the 1171 Building.

Related Sites/ Structures: The was associated with the 1171 Building vehicle maintenance activities.

Process Description: The unit temporarily stored waste antifreeze from vehicle maintenance activities. Because there were no risks identified with this site, no further action is required.

Waste Type: Chemicals

Waste Description: The unit stored waste antifreeze until removal in 1986. Recent investigations have found metals contamination and slight ethylene glycol contamination.

Code: 1100-11 **Classification:** Accepted

Names: 1100-11; Ephemeral Pool **Reclassification** Deleted From NPL (9/30/1996)

Type: Pond **Start Date:**

Status: Inactive**End Date:** 1/1/1995

Description: The site has been regraded to a smooth, uniform surface. The Ephemeral Pool site was a long, narrow depression designed to act as a drainage collection point for precipitation runoff flowing from the 1171 parking area. The north and south boundaries of the site were not distinct because the depression gradually rose toward both the north and south to near the elevation of the surrounding land. Settlement and/or poor grading of the depression floor resulted in the formation of a series of linked pools after rainfall events that temporarily held a portion of the collected moisture within the drainage way until it evaporated or infiltrated into the ground. A pervious gravel lining encouraged infiltration of the collected runoff into the vadose zone beneath this site.

Location: The Ephemeral Pool was located west of the 1171 parking area, near the U.S. Government Railroad lines.

Related Sites/ Structures: The site is associated with the 1171 parking area.

Waste Type: Chemicals

Waste Description: Before cleanup, soil sampling indicated the presence of PCB's (Aroclor 1260) at concentrations ranging from 300 to 42,000 micrograms per kilogram.

Waste Type: Stormwater Runoff

Waste Description: The site was designed to receive stormwater runoff from the adjacent 1171 Building parking area.

Code: HRD**Classification:** Accepted

Names: HRD; ITT Waste Disposal Landfill; Gravel Pit 4; Gravel Pit 5; Horn Rapid Landfill (HRL); Horn Rapids Disposal

Reclassification: Deleted From NPL (9/30/1996)**Type:** Sanitary Landfill**Start Date:****Status:** Inactive**End Date:**

Description: This site has been cleaned up based on the 1100 Area Record of Decision. It was Deleted from the National Priority List (NPL). This site consists of an inactive landfill that has been capped with clean soil (asbestos cap) and revegetated. A security fence surrounds the site.

Location: This site is located on the north side of Horn Rapids Roads, west of the intersection of Horn Rapid Road and Stevens Drive.

Process Description: From the late 1940's to the 1970's this site operated as an uncontrolled landfill. This solid waste facility was used primarily for the disposal of office and construction waste, asbestos, sewage sludge, fly ash, and reportedly, numerous drums of unidentified organic liquids. Classified documents were also incinerated at a burn cage located at the northern edge of the landfill.

Waste Type: Oil

Waste Description: Hydraulic oil contaminated with polychlorinated biphenyls was disposed at the site.

Waste Type: Misc. Trash and Debris

Waste Description: Automotive debris was found in all areas of the landfill. Stainless steel lathe shavings were found in the central portion of the landfill. Miscellaneous trash including paint containers was also found at the site.

Waste Type: Construction Debris

Waste Description: Various types of construction debris were found at the site.

Waste Type: Asbestos (friable)

Waste Description: Asbestos was found to be distributed throughout the landfill.

Waste Type: Chemicals

Waste Description: During the remedial investigation of the site, a small amount of medical waste was discovered. It consisted of a milky white substance, an eye dropper bottle with clear liquid and another bottle with clear liquid. A single plastic intravenous dispenser bag was also found. Because of the unknown hazards associated with this waste, it was reburied in the landfill.

Closure Info: Final: Remedial actions began January 3, 1995 at the site. Fourteen characterization boreholes were drilled. Sixty three surface and subsurface soil samples were collected during Phase I and twenty one soil samples were collected during Phase II Remedial Investigations. Geophysical and soil gas sampling was also done. Eight exploration trenches were excavated. Tires found in an open trench at the site were radiologically surveyed and removed for recycling. Approximately 1,230 cubic meters (1,608 cubic yards) of polychlorinated biphenyl (PCB) contaminated soil was removed from the site and disposed in Arlington, Oregon. A 25 acre soil cap was placed over the landfill. The soil cap was revegetated.

Five groundwater monitoring wells were installed in August 1995, down gradient from the landfill.

Code: UPR-1100-5	Classification: Accepted
Names: UPR-1100-5; 1171 Parking Lot; UN-1100-5	Reclassification: Deleted From NPL (9/30/1996)
Type: Unplanned Release	Start Date: 1/1/1962
Status: Inactive	End Date: 1/1/1962

Description: The site of the release was a transport truck in the 1171 Building parking lot.

Location: The release occurred in the parking lot northwest of 1171 Building.

Release Description: A missing O-ring resulted in zirconium and plutonium oxide contaminated water being released from a transport truck carrying liquid waste from Idaho. The truck was decontaminated. Although additional corrective action may have been provided, there are no documents describing the cleanup of the parking lot.

Related Sites/ Structures: The release was related to a transport truck from Idaho.

Waste Type: Chemical Release

Waste Description: The chemical release consisted of water in which metal specimens were immersed. One metal capsule ruptured contaminating the water with zirconium and plutonium oxides.

Code: UPR-1100-6	Classification: Accepted
Names: UPR-1100-6; Discolored Soil Site; UN-1100-6	Reclassification: Deleted From NPL (9/30/1996)
Type: Depression/Pit (nonspecific)	Start Date:

Status: Inactive

End Date: 1/1/1995

Description: The site was a patch of oily, dark-stained soil within an elongated east-west oriented depression. This site was remediated in 1995 under the 1100-EM-1 Record of Decision.

Location: The site was located northwest of the 1171 Building, in a depression west of the Hanford Rail Line and southeast of an irrigation canal.

Release Description: The source of the soil discoloration is conjectured to be the isolate, unauthorized disposal of one or more containers of liquid material to the ground surface. No records exist that explain the nature or origin of the material found at the site.

**Related Sites/
Structures:** adjacent to Gravel Pit #1

**Process
Description:** The site was used for the isolated, unauthorized disposal of liquid waste.

Waste Type: Abandoned Chemicals

**Waste
Description:** The site consists of dark-colored, oily residue, and soil. The material includes metal, organic, and pesticide contaminants. Bis(2-ethylhexyl)phthalate (BEHP) and chlordane were identified. BEHP is a probable human carcinogen.

Closure Info: Final: Fifteen soil samples were collected during the Phase I, 1100 Area Investigation. Contaminants identified included lead, potassium, zinc, alpha-chlordane, gamma-chlordane, 4,4"-DDE, bis(2-ethylhexyl) phthalate (BEHP), heptachlor, 3-hexanone, di-n-octylphthalate and 1,1,1-trichloroethane. In Phase II, fourteen soil gas probes were installed to depths ranging from 0.46 meters (1.5 feet) to 1.22 meters (4 feet). No contaminants were identified in the soil gas samples. The remedial action chosen was to excavate 90 cubic yards of contaminated soil.

The soil was removed on February 14, 1995 and transported to a permitted, offsite incinerator (Aragonite, Utah). After incineration, the residuals were disposed of in that facility's ash disposal landfill.

1100-EM-2

Code: 700 WST **Classification:** Accepted
Names: 700 WST; 703-1; 700 Area Underground Waste Solvent Tank; 700 Area Waste Solvent Tank **Reclassification** Deleted From NPL (9/30/1996)
Type: Storage Tank **Start Date:**
Status: Inactive **End Date:** 1/1/1989

Description: The waste site was an underground steel storage tank that was removed and examined. The tank was empty. There was a thick crust of soil over much of the tank bottom that prevented a detailed observation of the tank. There were no obvious holes. The waste site was Deleted from the NPL.

Location: This site was located east of the 703 Building approximately 30.5 centimeters (12 inches) from the foundation. The long axis of the tank was north-south. The top of the tank was approximately 45.7 centimeters (18 inches) below grade.

Waste Type: Chemicals

Waste Description: The unit contained combustible solution of aliphatic hydrocarbons with 162 parts per million of 1,1,1-trichloroethane.

Closure Info: Final: In 1989, the tank was excavated (but still in place), there was an odor of solvents. The soil around the tank was stained dark in places. Readings of the excavation with an HNU model F1 101 10.2 Electron Volt lamp (photo ionization organic vapor detector) showed breathing zone of 3 parts per million, varying from 0-4 parts per million with occasional spikes greater than 7 parts per million. The narrow space beneath the tank read greater than 20 parts per million. HNU readings less than 2.5 centimeters (1 inch) from the soil surface seemed to indicate greater contamination near the south end of the tank impression (after pulling the tank).

Soil was removed from the south end of the tank impression using a backhoe and non-decontaminated shovels.

During the excavation, surface contamination was reported above the tank. Contaminated surface soil was disposed of in five 208 liter (55 gallon) drums by Operations Support Services (OSS) during excavation. Drum contents were sampled analyzed. The drums and the tank were removed from the site by OSS personnel.

Code: 1100 BSUHR **Classification:** Accepted
Names: 1100 BSUHR; 1100 Area Bus Shop Underground Hoist Rams **Reclassification** Deleted From NPL (9/30/1996)
Type: Storage Tank **Start Date:** 1/1/1953
Status: Inactive **End Date:**

Description: This site was cleaned up under the 1100 Area Record of Decision. The 1100 BSUHR Site consists of four single manifold, triple tank hoists. Each is related to the 1171 Building Maintenance activities.

Location: The units are located within the 1171 Building Bus Shops.

Related Sites/ Structures: The site is associated with the 1171 Building Maintenance activities.

Process The storage tanks hold hydraulic oil for the operation of the hoists.

Description:

Waste Type: Oil

Waste The units contain non-PCB hydraulic oil.

Description:

Code: 1100 HWSA

Classification: Accepted

Names: 1100 HWSA; 1100 Area Hazardous Waste Storage Area; 1100 Area HWSA

Reclassification Deleted From NPL (9/30/1996)

Type: Storage Pad (<90 day)

Start Date: 1/1/1985

Status: Inactive

End Date: 1/1/1990

Description: The site consists of a fenced gravel pad that is used to store waste containers.

Location: The site was located north of the 1100 Area Building.

Related Sites/ Structures: The unit was associated with 1171 Building operations.

Process The unit was used to stage hazardous waste for periods less than 90 days.
Description:

Waste Type: Barrels/Drums/Buckets/Cans

Waste The waste staged at the site included: used oil, antifreeze, degreasers, acids, and paint-related wastes.
Description:

Code: 1100 UOT4

Classification: Accepted

Names: 1100 UOT4; 1171-4; 1100 Area Underground Used Oil Tank (Tank #4); 1100 Area Used Oil Tank 4

Reclassification Deleted From NPL (9/30/1996)

Type: Storage Tank

Start Date: 1/1/1953

Status: Inactive

End Date: 1/1/1995

Description: The 1100 UOT4 Site was an unlined, underground steel tank. The tank was removed.

Location: The unit was located below the Light Maintenance Shop in the 1171 Building.

Related Sites/ Structures: The tank was associated to the 1171 Building Maintenance.

Process The tank provided temporary storage for used oil prior to shipment off site for recycling.
Description:

Waste Type: Oil

Waste The unit received used oil designated for recycling.
Description:

Code: 1100 UOT5

Classification: Accepted

Names: 1100 UOT5; 1171-5; 1100 Area Underground Used Oil Tank (Tank #5); 1100 Area Used Oil Tank 5

Reclassification: Deleted From NPL (9/30/1996)

Type: Storage Tank

Start Date: 1/1/1953

Status: Inactive

End Date: 1/1/1994

Description: The 1100 UOT5 Site was an unlined, underground steel tank. The tank was removed.

Location: The unit was located east of the 1171 Building.

Related Sites/ Structures: The unit was associated with the 1171 Building Maintenance activities.

Process Description: The tank stored used oil prior to shipment off site for recycling.

Waste Type: Oil

Waste Description: The unit received used oil designated for recycling.

Code: 1100 UOT6

Classification: Accepted

Names: 1100 UOT6; 1171-6; 1100 Area Underground Used Oil Tank (Tank #6); 1100 Area Used Oil Tank 6

Reclassification: Deleted From NPL (9/30/1996)

Type: Storage Tank

Start Date: 1/1/1953

Status: Inactive

End Date: 1/1/1995

Description: The 1100 UOT6 was a below grade, unlined steel tank. The tank has been removed.

Location: The tank was below grade north of the 1171 Building.

Related Sites/ Structures: The unit was related to the 1171 Building Maintenance activities.

Process Description: The tank stored waste oil prior to shipment off site for recycling.

Waste Type: Oil

Waste Description: The unit received used oil designated for recycling.

Code: 1100 USPT2

Classification: Accepted

Names: 1100 USPT2; 1171-2; 1100 Area Underground Steam Pad Tank 2

Reclassification: Deleted From NPL (9/30/1996)

Type: Storage Tank

Start Date: 1/1/1984

Status: Inactive

End Date: 1/1/1995

Description: The site was fiberglass-reinforced plastic tank. The tank was removed.

Location: The 1100 USPT2 Site was on the north side of the 1171 Building. The unit is below grade.

**Related Sites/
Structures:** The unit was associated with the 1171 Building Steam Cleaning Facilities.

**Process
Description:** The unit stored wastewater from the 1171 Building steam cleaning activities.

Waste Type: Chemicals

**Waste
Description:** The unit received oily water from bus washing activities.

Code: 1100 USPT3

Classification: Accepted

Names: 1100 USPT3; 1171-3; 1100 Area Underground
Steam Pad Tank 3

Reclassification Deleted From NPL (9/30/1996)

Type: Storage Tank

Start Date: 1/1/1984

Status: Inactive

End Date: 1/1/1995

Description: The 110 USPT3 Site was a fiberglass-reinforced plastic tank. The tank has been removed.

Location: The unit was located near the northwest corner of the 1171 Building.

**Related Sites/
Structures:** The unit was associated with the 1171 Building Steam Cleaning Facilities.

**Process
Description:** The tank stored wastewater from steam cleaning activities.

Waste Type: Water

**Waste
Description:** The unit received oily water from washing heavy equipment.

Code: 1100-8

Classification: Accepted

Names: 1100-8; 1171 Hoist Oil Leak

Reclassification Deleted From NPL (9/30/1996)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The DB-1-N hoist in the 1171 building was used for vehicle maintenance. The hoist was repaired and the oil that leaked from the hoist into the soil has been removed.

**Release
Description:** Oil leaked from the ram and containment pan of the DB-1-N hoist in the 1171 Building into the soil.

**Related Sites/
Structures:** 1171 building

**Process
Description:** The equipment was a vehicle maintenance hoist.

Waste Type: Oil

**Waste
Description:** The waste included Industrial Oil, UNOCAL UNAX AW 32, MSDS #12615 (HEHF).

1100-EM-3

Code: 3000 JYHWSA **Classification:** Accepted

Names: 3000 JYHWSA; Hazardous Waste Storage Area (Jones Yard); 3000 Area Jones Yard Hazardous Waste Storage Area; 3000 Area Jones Yard HWSA **Reclassification** Deleted From NPL (9/30/1996)

Type: Storage Pad (<90 day) **Start Date:** 1/1/1965

Status: Inactive **End Date:**

Description: The site consisted of a hazardous waste storage area.

Location: The hazardous waste staging area was located south of the 1226 Building in the southeast corner of the fenced area of the 3000 Area.

Process Description: The unit was used to stage hazardous waste for periods of less than 90 days.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: A maximum of 200 55-gallon (208-liter) drums of nonregulated oils were stored in this area, along with 14 55-gallon (208-liter) drums of antifreeze and paint-reacted materials.

Code: 3000 UUOT **Classification:** Accepted

Names: 3000 UUOT; 3000-12; 3000 Area Underground Used Oil Tank **Reclassification** Deleted From NPL (9/30/1996)

Type: Storage Tank **Start Date:** 1/1/1983

Status: Inactive **End Date:** 1/1/1993

Description: This was the site of a underground storage tank. The tank has been exhumed, and the site remediated.

Location: The site is located just southeast of the 1226 Building on the west side of the 1226 Loading Dock.

Process Description: The site was used for storage of used oil and lubricants for recycling. The materials were generated by vehicle maintenance activities in the 1226 Building.

Waste Type: Oil

Waste Description: At the time the tank was exhumed, it contained some oil sludge.

Code: 3000/1208 HWSA **Classification:** Accepted

Names: 3000/1208 HWSA; Hazardous Waste Storage Area (1208); 3000 Area 1208 Building Hazardous Waste Storage Area; 3000 Area 1208 HWSA **Reclassification** Deleted From NPL (9/30/1996)

Type: Storage Pad (<90 day) **Start Date:** 1/1/1967

Status: Inactive **End Date:** 1/1/1995

Description: The site consists of a concrete pad that was used to store waste containers.

Location: The hazardous waste staging area was located at the northeast corner of the 1208 Building Shop in the 3000 Area.

Related Sites/ Structures: The hazardous waste staging area was associated with the 1208 Building Paint Shop.

Process Description: The unit was used to stage hazardous waste for periods less than 90 days.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: Typical wastes contained in the staging area included paints and solvents. The unit received approximately 300 gallons (1,140 liters) per year.

Code: 3000/1226 HWSA **Classification:** Accepted

Names: 3000/1226 HWSA; Hazardous Waste Storage Area (1226); 3000 Area 1226 Building Hazardous Waste Storage Area; 3000 Area 1226 HWSA **Reclassification:** Deleted From NPL (9/30/1996)

Type: Storage Pad (<90 day) **Start Date:** 1/1/1954

Status: Inactive **End Date:** 1/1/1995

Description: The site was a concrete pad that was used to store waste containers.

Location: The hazardous waste staging area was located at the 1226 Building Automotive Shop.

Related Sites/ Structures: The hazardous waste staging area was associated with the 1226 Building.

Process Description: The unit was used to stage hazardous waste for less than 90 days.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: Typical wastes contained in the staging area included oils, solvents, antifreeze, and degreasers in 55-gallon (208-liter) drums. The unit received approximately 300 gallons (1,140 liters) per year.

Code: 3000/1234 **Classification:** Accepted

Names: 3000/1234; 1234 Building Storage Yard; 1234 Laydown Yard; 3000 Area 1234 Storage Yard **Reclassification:** Deleted From NPL (9/30/1996)

Type: Storage **Start Date:**

Status: Inactive **End Date:** 1/1/1995

Description: This site is an open area surrounded by a fence. Access was controlled by a single locked gate. This site was used for the storage of raw and structural materials. The Simulated High-Level Waste Treatment and Storage (SHLWST) sites were located within this site. The SHLWST was a permitted Treatment, Storage, and Disposal (TSD) unit that was clean closed.

Location: This site is located just southwest of the intersection of Stone Street and "W" Avenue.

Related Sites/ Structures: This site was associated with the Simulated High-Level Waste Slurry Treatment and Storage (SHLWST).

Waste Type: Equipment

Waste Description: This area was used for storage of raw materials and equipment. Raw materials included grout used in the Simulated High-Level Waste Slurry Treatment/Storage.

Code: 3000/1240 HWSA **Classification:** Accepted

Names: 3000/1240 HWSA; Hazardous Waste Storage Area (1240); 3000 Area 1240 Building Hazardous Waste Storage Area; 3000 Area 1240 HWSA **Reclassification:** Deleted From NPL (9/30/1996)

Type: Storage Pad (<90 day) **Start Date:** 1/1/1951

Status: Inactive **End Date:** 1/1/1995

Description: The site consisted of a concrete pad that was used to store waste containers. There were two drains in the storage pad that drained to the soil. The pad contained old stains.

Location: The hazardous waste staging area was located at the southeast corner of the 1240 Building in the 3000 Area.

Related Sites/ Structures: The hazardous waste staging area was associated with the 1240 Building.

Process Description: The unit was used to stage hazardous waste for periods less than 90 days.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: Typical wastes contained in the staging area include lubricating oils, cutting oils, solvents, and degreasers in 55-gallon (208-liters) drums. The unit receives approximately 200 gallons (760 liters) per year.

Code: UPR-3000-1 **Classification:** Accepted

Names: UPR-3000-1; Release from the Physical Science Laboratory; UN-3000-1 **Reclassification:** Deleted From NPL (9/30/1996)

Type: Unplanned Release **Start Date:** 1/1/1973

Status: Inactive **End Date:** 1/1/1973

Description: The release site was a sink used only for nonradioactive work in Room 1623 of the Physical Science Laboratory Building. A sign was installed by the sink and the whole middle island was designated plainly as a cold region. The whole middle island was marked with floor tape and a bench top tape to plainly segregate the area from the radioactive area.

Location: UPR-3000-1 originated in the sink in Room 1623 of the Physical Science Laboratory Building. The Physical Science Laboratory Building lies west of the Math Building, south of the Engineering Development Laboratory, and northeast of the intersection of Battelle Boulevard and Stevens Drive in the 3000 Area.

Release Description: A technician disposed of 1,650 milliliters of waste cesium-134 solution into a cold drain that empties into the Richland City sewer system.

**Related Sites/
Structures:** UPR-3000-1 was associated with the sink in Room 1623 of the Physical Science Laboratory Building.

Waste Type: Chemicals

**Waste
Description:** The waste consisted of a tracer solution containing 2 microcuries of cesium-134.

1100-IU-1

Code: 600-28 **Classification:** Accepted
Names: 600-28; Rattlesnake Construction Dump **Reclassification** Deleted From NPL (9/30/1996)
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The site consists of numerous low piles of excavated soil, rock, and construction debris. This site has a very irregular slope. Sagebrush and other vegetation are growing on the piles.

Location: This site is located just north of the Nike Missile Launch Site H-52-L at Rattlesnake Mountain.

Waste Type: Asbestos (non-friable)

Waste Description: The waste consists of a small quantity of transite siding and asbestos pipe.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: The site contains numerous empty paint cans.

Code: 600-112 **Classification:** Accepted
Names: 600-112; 6652-C Space Science Laboratory **Reclassification** Deleted From NPL (9/30/1996)
Active Septic Tank; 6652-C SSL Active Septic Tank; 6652-C SSLAST
Type: Septic Tank **Start Date:** 1/1/1955
Status: Inactive **End Date:** 1/1/1994

Description: The site consists of a concrete septic tank with two square access lids and a retention tank connected to the outlet of the septic tank. Both structures are underground. There is no visual evidence of a second septic tank or a retention tank. There is a chained area marked with signs stating "Caution, Sanitary Tile Field".

Location: This site is located on the southeast side of the 6652-C Space Science Laboratory Building. This laboratory is located at the top of Rattlesnake Mountain, inside the fenced boundary.

Related Sites/ Structures: The associated structure is the 6652-C Space Science Laboratory (see sitecode 600-116).

Process Description: This site provided sanitary sewage disposal for the 6652-C Space Science Laboratory. This laboratory was formerly the barricades and bachelor officers quarters for the U. S. Army Nike missile radar site H-52-C. From 1955 to 1960 the U. S. Army used this facility, and from 1967 to 1994 Battelle Northwest used this site.

Waste Type: Sanitary Sewage

Waste Description: The unit received sanitary wastewater.

Code: 600-113 **Classification:** Accepted
Names: 600-113; 6607-15; 6652-C Space Science **Reclassification** Deleted From NPL (9/30/1996)

Laboratory Inactive Septic Tank; 6652-C SSL

Inactive Septic Tank; 6652-C SSLIST

Type: Septic Tank **Start Date:** 1/1/1955

Status: Inactive **End Date:** 1/1/1960

Description: This site consists of a septic tank with two access covers and connecting, cobble covered drainfield. Both the septic tank and the drain field are located outside the Hanford Site boundary barbed wire fence.

Location: This site is located at the northwest end of the 6652-C Space Science Laboratory Complex. This complex is at the summit Rattlesnake Mountain, outside the fenced boundary.

Related Sites/ (see sitecode 600-116)

Structures:

Process This site provided sanitary sewage disposal for a latrine that was associated with two barracks
Description: and one officers quarters. These facilities were part of the former U. S. Army Nike missile Radar Site H-52-C.

Waste Type: Sanitary Sewage

Waste The unit received sanitary sewage from U.S. Army facilities.
Description:

Code: 600-114

Classification: Accepted

Names: 600-114; 6607-14B; 6652-G ALE Field Storage **Reclassification** Deleted From NPL (9/30/1996)
Building Septic Tank; 6652-G ALEFSBST

Type: Septic Tank **Start Date:** 1/1/1955

Status: Inactive **End Date:** 1/1/1960

Description: This site was properly abandoned and Deleted from the NPL. It consisted of a septic tank with two round access lids, a concrete distribution box with a wooden lid, and the connecting tile field. The distribution box is located partly inside and partly outside of the tile field chained boundary.

Location: This site is located in the northwest section of the Fitzner/Eberhardt Arid Lands Ecology Headquarters at the foot of Rattlesnake Mountain.

Related Sites/ The associated structure is the 6652-G Field Storage Building. (see sitecode 600-116).

Structures:

Process This site provided sanitary sewage disposal for the officers quarters and barracks building at the
Description: former U. S. Army Nike missile launch site H-52-L.

Waste Type: Sanitary Sewage

Waste The unit received sanitary sewage from U.S. Army facilities.
Description:

Closure Info: Final: This septic system was abandoned per the requirements of Washington Administrative Code 246-272-18501. All septage inside the tank was removed and the empty tank was filled to eliminate void space. Per an agreement with the Washington Department of Health, the septic system lids were left in place.

The Preliminary Assessment Screening (PAS) was completed in April 1994. The PAS

identified hazards or potential hazards, either environmental or physical, remaining on ALE Reserve lands.

Code: 600-115 **Classification:** Accepted

Names: 600-115; 6607-14; 6652-I ALE Headquarters Septic Tank; 6652-I ALEHST; 6652-I Arid Lands Ecology (ALE) Headquarters Septic Tank **Reclassification** Deleted From NPL (9/30/1996)

Type: Septic Tank **Start Date:** 1/1/1955

Status: Inactive **End Date:** 1/1/1996

Description: This site has been properly abandoned and Deleted from the NPL. It consists of a septic tank with a round base and a 72 centimeter access lid, a distribution box covered with a wooden lid, a square diverter box, and the connecting drain field.

Location: This site is located at the Fitzner/Eberhardt Arid Lands Ecology headquarters at the foot of Rattlesnake Mountain, on its east side.

Related Sites/Structures: The 6652-I, 6652-J, and 6652-H Buildings at the Arid Lands Ecology Reserve (ALE) headquarters were serviced by this system. (see sitecode 600-116).

Process Description: From 1955 to 1960 this site provided sanitary sewage disposal for the officers quarters, the barracks, the mess hall, and the administration building at the former U. S. Army Nike Missile Launch Site H-52-L.

Waste Type: Sanitary Sewage

Waste Description: The unit received sanitary wastewater.

Closure Info: Final: The septic system was abandoned per the requirements of Washington Administrative Code 246-272-1851. All septage inside the tank was removed and the empty tank was filled to eliminate void spaces. Per an agreement with the Washington Department of Health, the septic system lids were left in place.

Code: 600-116 **Classification:** Accepted

Names: 600-116; 6652 buildings; Rattlesnake Mountain Nike Missile Base; RMNMB **Reclassification** Deleted From NPL (9/30/1996)

Type: Military Compound **Start Date:** 1/1/1955

Status: Inactive **End Date:** 1/1/1961

Description: The area was evaluated, Deleted from the NPL and reclassified in 1996. This site consisted of a former U. S. Army Nike Missile Base. The base is split into two parts: the radar site is on top of Rattlesnake Mountain and the missile launch area is at the foot of Rattlesnake Mountain on the southeast slope. Some of these facilities were subsequently used by Battelle Northwest. The following buildings are found at the site: 6652C (Space Science Laboratory), 6652CSHED (Storage Building), 6652D (Pumphouse), 6651DOME1 (Observatory), 6652DOME2 (Small Observatory), 6652E (Garden Building), 6652G (ALE Field Storage), 6652H (ALE Laboratory I), 6652I (ALE Headquarters), 6652J (ALE Laboratory II), 6652K, 6652L (Underground Missile Bunkers), 6652LP (Rattlesnake Mountain Lower Pumphouse), 6652M (Fallout Laboratory), 6652O (Missile Assembly and Test Building), 6652P (Generator Building), 6652R (Paint Shed/ Flammable Storage Block Shed), and 6652UP (Rattlesnake Mountain Upper Pumphouse).

In 2010, footprint reduction activities were done on the Fitzner/Eberhardt Arid Lands Ecology Reserve (ALE). Structures on the Upper ALE included research facilities, storage buildings, water storage tanks and distribution piping, and electric and communications wires and cables both aboveground and below ground. The slabs were removed, and utilities were disconnected and excavated to 0.9 meters (3 ft) below grade. Septic tanks and drain fields were properly closed (per WAC code) and left in place.

Removal of excess buildings at the Upper ALE eliminated approximately 750 square meters (8,100 sq. ft) of existing facilities, along with excess power and phone lines, and a quantity of miscellaneous debris. When considering the removal of roads, parking areas, utilities, and other use areas that supported building operations, the developed footprint at the top of the ridge was reduced from approximately 43,432 square meters (467,500 sq. ft.) to approximately 3,716 square meters (40,000 sq. ft.). In addition, the height of the communication towers was reduced from a total of 192 vertical meters (630 ft) to 91 vertical meters (300 ft). Miscellaneous debris collected on the Upper ALE is listed with demolition debris. The two waste streams were consolidated for disposal.

Upper ALE structures removed included 623A, 6631, 6632, 6633, 6635, 6636, 6637, 6652C, 6652CSHED, 6652G, 6652T and 6652U.

Lower ALE structures removed included 6652G, 6652H, 6652I, 6652J, 6652M, 6652R and 6652S.

Septic tanks and drain fields were closed and left in place.

Location: The site is located at the summit of Rattlesnake Mountain and the toe of the southeast slope of Rattlesnake Mountain.

Related Sites/ Structures: Site Codes 600-112, 600-113, 600-114, and 600-115 are septic tanks associated with this site. Septic tanks and drain fields were closed and left in place. Sites 600-270 Horseshoe Landfill and 600-271 Nike Missile Base Landfill have also been deleted from the NPL.

The following buildings were associated with the missile base: 6652C (Space Science Laboratory), 6652CSHED (Storage Building), 6652D (Pumphouse), 6651DOME1 (Observatory), 6652DOME2 (Small Observatory), 6652E (Garden Building), 6652G (ALE Field Storage), 6652H (ALE Laboratory I), 6652I (ALE Headquarters), 6652J (ALE Laboratory II), 6652K, 6652L (Underground Missile Bunkers), 6652LP (Rattlesnake Mountain Lower Pumphouse), 6652M (Fallout Laboratory), 6652O (Missile Assembly and Test Building), 6652P (Generator Building), 6652R (Paint Shed/ Flammable Storage Block Shed), and 6652UP (Rattlesnake Mountain Upper Pumphouse).

The following buildings were used by PNNL and are recorded as being contaminated as of 1998 (source: 1998 Vulnerability & Legacy Report - ALE Buildings - not available): 6652C, Space Science Laboratory on top of Rattlesnake Mt., including 6652D, the Fire System Pumphouse (lead-based paint, PCBs in light fixture ballasts, mercury switches, and asbestos insulation are suspected based on the age of the facility) 6652C-SHED, also on top of Rattlesnake Mt., includes both an upper pumphouse (6652-UP) and Lower Pumphouse (6652-LP) (The shed has asbestos siding and shingles). 6652E, the Garden Building (Sealed neutron probes are stored in the building as of 11/6/1998 for field tests).

6652DOME1 This is the observatory on Rattlesnake Mt. (A slight potential exists for lead-based paint and mercury switches). This facility is still (8/2001) operating and under the control of Alliance for the Advancement of Science through Astronomy (AASTA).

6652G, the ALE Field Storage building (The building has asbestos tiles, siding, and insulation,

and may have lead-based paint and mercury switches).

6652H and 6652I (Connected buildings; Labs 202, 204, and 206 previously contained radioactively contaminated equipment and ductwork, including HEPA filters these were removed in August 2000. Also reported at the site in the Vulnerability and Legacy report are PCBs, which may be in transformers and ballasts, lead-based paint may have been used for the building, asbestos tile and insulation are present, and mercury may be in switches and thermostats).

6652J (Lead-based paint and lead sheets in the vent lines are possible, mercury is expected in the thermostats, and floor tiles are asbestos).

6652L, the Nike missile bunkers (PCBs are expected in light ballasts, lead is expected in the paint, lead batteries, and in the form of 20 tons of lead bricks, mercury is suspected in light switches, freons are expected in the refrigerant system, and asbestos is in the tiles, insulation, and siding).

6652M, the Fallout laboratory (There is potential for lead-based paint and lead around the vent pipes on the roof).

Process Description: The site is a former NIKE missile base consisting of structures which supported missile launch, control, and maintenance functions, as well as living quarters for base personnel and storage buildings for hazardous substances used in the maintenance of the physical plant and missile operations. As of July 1999, all base facilities had been abandoned with the exception of 6652L, the underground missile bunkers, which were actively being used for an experiment according to a sign outside the door. The large observatory (Dome 1) is also still operating (as of 8/2001) and under the control of a non-profit organization, the Alliance for the Advancement of Science through Astronomy.

Waste Type: Ordnance

Waste Description: The site previously contained unexploded ordnance waste, according to DOE/RL-92-67.

Waste Type: Asbestos (friable)

Waste Description: The site contains PCB's from transformers, asbestos in insulation, tiles, and siding, mercury in switches, and lead-based paint and bricks in various buildings.

Closure Info: Final: The area was evaluated, Deleted from the NPL and reclassified in 1996. Structures were removed in 2010.

Prior to intrusive investigations at the two landfills, Horseshoe and Nike Base, geophysical surveys were conducted by Golder to identify areas where wastes were present. Eleven anomalous areas within the 2.8 hectare (6.9 acre) Horseshoe Landfill site and nine anomalous areas within the 1.9 hectare (4.6 acre) Nike Base Landfill were identified. (See Sitecodes 600-270 and 600-271).

In 1994, Geophysical investigations were done to identify underground storage tanks (USTs) in the area. Two 7600 liter (2000 gallon) underground fuel storage tanks were identified at buildings 6652-G and 6652-H. These two tanks were removed. The soil beneath the tanks was sampled and found to be clean. 4.6 cubic meters (6 cubic yards) of petroleum contaminated soil was found inside another underground fuel storage tank at 6652-G. This soil was taken to a landfarm in to 100 Area. Other UST's were identified at 6652-H, 6652-I and 6652-J. One abandoned fuel oil UST, with an unknown volume, was found south of 6652-H. One 22,800 liter (6000 gallon) underground diesel fuel tank was identified near the observatory dome, at 6652-C. This tank was closed in place in 1994.

In 2010, footprint reduction activities were done on the Fitzner/Eberhardt Arid Lands Ecology Reserve (ALE). Structures on the Upper ALE included research facilities, storage buildings, water storage tanks and distribution piping, and electric and communications wires and cables both aboveground and below ground. The slabs were removed, and utilities were disconnected and excavated to 0.9 meters (3ft) below grade. Septic tanks and drain fields were closed and left in place. Septic tanks were cleaned and closed in accordance with WAC 246-272A-0300, "On-Site Sewage Systems, Abandonment," as part of the building removal process on the Upper ALE and Lower ALE, including the tank at Building 646 at Rattlesnake Springs.

Removal of excess buildings at the Upper ALE eliminated approximately 750 square meters (8,100 sq. ft.) of existing facilities, along with excess power and phone lines, and a quantity of miscellaneous debris. When considering the removal of roads, parking areas, utilities, and other use areas that supported building operations, the developed footprint at the top of the ridge was reduced from approximately 43,432 square meters (467,500 sq. ft.) to approximately 3,716 square meters (40,000 sq. ft.). In addition, the height of the communication towers was reduced from a total of 192 vertical meters (630 ft) to 91 vertical meters (300 ft). Miscellaneous debris collected on the Upper ALE is listed with demolition debris. The two waste streams were consolidated for disposal.

Upper ALE structures removed included 623A, 6631, 6632, 6633, 6635, 6636, 6637, 6652C, 6652CSHED, 6652G, 6652T and 6652U.

Structures on Lower ALE that were not in use by US Fish and Wildlife Services (6652-E, -K, -O, -PH) or to support ongoing gravitational studies (6652-L) were demolished as part of the footprint reduction activities. In addition, Hodges Well, located along the 106 Road to the ridgeline, was removed, along with the power lines and poles that supplied electricity to the well. Building slabs were removed, and utilities were disconnected and excavated to 0.9 meters (3 ft) below grade. Septic tanks and drain fields were closed (properly abandoned) and left in place.

Lower ALE structures removed included 6652G, 6652H, 6652I, 6652J, 6652M, 6652R and 6652S.

Approximately 3,300 square meters (35,500 sq. ft.) of facilities were demolished and removed from the Lower ALE. Considering parking areas, roads, and other developed sites, approximately 74,000 square meters (800,000 sq. ft.) of disturbed land will be restored by planting native vegetation. Approximately 2,464,564 kilograms (5,422,040 lb) of building rubble was generated from the demolition of structures at the Lower ALE. In addition to the removal of structures, numerous debris items totaling 178,372 kilograms (329,418 lb) were removed in the vicinity of the Lower ALE.

WMA A/AX

Code: 216-A-16 **Classification:** Accepted
Names: 216-A-16; 216-A-16 Dry Well **Reclassification:** None
Type: French Drain **Start Date:** 1/1/1956
Status: Inactive **End Date:** 3/1/1969

Description: The unit is composed of bell-end concrete pipe, 1.8 meters (6 feet) long, placed vertically 3.4 meters (11 feet) below grade. The unit is rock-filled with a 1.9-centimeter (3/4-inch) carbon-steel cover. A 5-centimeter (2-inch) steel vent riser extends 0.9 meters (3 feet) from the top. There is a carbon steel inlet pipe, approximately 0.6 meters (2 feet) long coming from the 216-A-17 French Drain.

Location: The french drain is located in the southeast corner of the 241-A Tank Farm, inside the tank farm fence.

Related Sites/ Structures: The site is associated with 216-A-17 French Drain, the 241-A-431 building and the 296-A-11 exhaust stack.

Process Description: The site received the floor drainage and the 296-A-11 Stack drainage from the 241-A-431 Building.

Waste Type: Water

Waste Description: The site received the floor drainage and the 296-A-11 Stack drainage from the 241-A-431 Building. The waste is low in salt, neutral to basic, and contains less than 1 curie total beta activity.

The authors of PNL-6456 and RHO-CD-673 confused sites 216-A-16 and 216-A-17. 216-A-16 french drain received overflow from the 216-A-17 french drain. Because of this, 216-A-17 would have a larger rad inventory and volume of waste received than 216-A-16. The rad inventory (<1 Ci total beta) and waste volume (60,000 Liters) attributed in those documents to 216-A-17 is for 216-A-16.

Code: 216-A-17 **Classification:** Accepted
Names: 216-A-17; 216-A-17 Dry Well **Reclassification:** None
Type: French Drain **Start Date:** 1/1/1956
Status: Inactive **End Date:** 1/1/1969

Description: The unit is composed of bell-end concrete pipe, 1.8 meters (6 feet) long, placed vertically 3.3 meters (11 feet) below grade. The unit is rock-filled with a carbon steel cover. The side slope of the excavation is assumed to have been 1:1.

Location: The french drain is in the southeast corner of the 241-A Tank Farm, inside the tank farm fence.

Related Sites/ Structures: The french drain is associated with the 241-A-431 Building, the 296-A-11 Stack and the 216-A-16 French Drain.

Process Description: The french drain receives floor drainage from 241-A-431 and stack drainage from 296-A-11 Stack.

Waste Type: Water

Waste Description: The site received the floor drainage and the 296-A-11 Stack drainage from the 241-A-431 Building. The waste is low in salt, neutral to basic, and contains less than 10 curies total beta activity.

The authors of PNL-6456 and RHO-CD-673 confused sites 216-A-16 and 216-A-17. 216-A-16 french drain received overflow from the 216-A-17 french drain. Because of this, 216-A-16 would have a smaller rad inventory and volume of waste received than 216-A-17. The rad inventory (<10 Ci total beta) and waste volume (122,000 Liters) attributed in those documents to 216-A-16 is for 216-A-17.

Code: 216-A-23A **Classification:** Accepted

Names: 216-A-23A; 216-A-23-A French Drain **Reclassification:** None

Type: French Drain **Start Date:** 9/1/1957

Status: Inactive **End Date:** 3/1/1969

Description: The unit is a 1.07-meter (3.5-foot) diameter, 1.8-meter (6-foot) long bell-end concrete pipe, placed vertically 1.98 meters (6.5 feet) below grade. The concrete pipe is filled with 0.9 meters (3 feet) of rock and has a carbon steel cover. A 5.1-centimeter (2-inch) carbon steel vent riser extends from the top to 0.9 meters (3 feet) above grade. A Schedule 80 steel inlet pipe enters approximately 2.7 meters (9 feet) below grade.

Location: This waste site is located in the southeast corner of the 241-A Tank Farm, just south of the 241-A-431 Fan House building.

Related Sites/Structures: The french drain is associated with the 241-A-431 Building. The 216-A-23-A French Drain is connected to the 216-A-23-B French Drain, located 3 meters (10 feet) to the west, by an underground overflow pipe.

Process Description: The site received the deentrainer tank condensate and the back flush waste from the 241-A-431 Building.

Waste Type: Process Effluent

Waste Description: The site received the deentrainer tank condensate and the back flush waste from the 241-A-431 Building. The waste is low in salt, neutral to basic and contains less than 50 curies total beta activity. The total amount discharged by this waste stream, 6,000 liters (1,580 gallons), applies to both A-23A and A-23B.

Code: 216-A-23B **Classification:** Accepted

Names: 216-A-23B; 216-A-23-B French Drain **Reclassification:** None

Type: French Drain **Start Date:** 1/1/1957

Status: Inactive **End Date:** 1/1/1969

Description: The unit is a 1.07-meter (3.5-foot) diameter, 1.8-meter (6-foot) long bell-end concrete pipe, placed vertically 1.98 meters (6.5 feet) below grade. The unit is filled with 0.9 meters (3 feet) of rock and has a carbon steel cover. The side slope is assumed to be 1:1.

Location: This site is located in the southeast corner of the 241-A Tank Farm, just south of the 241-A-431 Fan House.

Related Sites/Structures: The french drain is associated with the 241-A-431 Building. The 216-A-23-B French Drain is connected to the 216-A-23-A French Drain by an underground overflow pipe.

Process Description: The site received the deentrainer tank condensate and the backflush waste from the 241-A-431 Building.

Waste Type: Process Effluent

Waste Description: The site received the deentrainer tank condensate and the backflush waste from the 241-A-431 Building. The waste is low in salt, neutral to basic and contains less than 5 curies total beta activity. Total waste stream discharge was 6,000 liters (1,580 gallons) to the 216-A-23A and 216-A-23B French Drains.

Code: 241-A-A **Classification:** Accepted

Names: 241-A-A; 241-A-A Diversion Box; 241-A-A Structural Valve Pit **Reclassification:** None

Type: Valve Pit **Start Date:** 1/1/1974

Status: Inactive **End Date:**

Description: The unit is an underground structure with reinforced concrete walls, floor, and cover blocks.

Location: The valve pit is located inside the 241-A Tank Farm complex, south of tanks 241-A-101 and 241-A-102.

Related Sites/Structures: The unit is associated with 241-A-350, 241-A Tank Farm, 200-E-167-PL, 200-E-210-PL.

Process Description: The 241-A Tank Farm valve pits were used to route wastes to and from the 242-A Evaporator; 241-AN, 241-AW, 241-AY, and 241-AZ Tank Farms, PUREX and the 244-A DCRT. The 204-AR Facility was connected to 241-A-A, but waste was re-routed to 241-AW-A valve pit in 2003 when line LIQW-702 was tied into line SN-220. Transfers from 244-A may include cross-site, 244-CR, and B-Plant wastes.

Waste Type: Process Effluent

Waste Description: The 241-A Tank Farm valve pits are used to route wastes to and from the 242-A Evaporator; 241-AN, 241-AW, 241-AY, and 241-AZ Tank Farms; PUREX; and the 244-A DCRT. The 204-AR Facility was connected to 241-A-A, but waste was re-routed to 241-AW-A valve pit in 2003 when line LIQW-702 was tied into line SN-220. Transfers from 244-A may include cross-site, 244-CR, and B-Plant wastes.

Code: 241-A-B **Classification:** Accepted

Names: 241-A-B; 241-A-B Diversion Box; 241-A-B Structural Valve Pit **Reclassification:** None

Type: Valve Pit **Start Date:** 1/1/1974

Status: Inactive **End Date:**

Description: The unit is an underground reinforced concrete structure with walls, a floor, and cover blocks.

Location: The valve pit is located inside the 241-A Tank Farm complex, south of tanks 241-A-101 and 241-A-102.

Related Sites/Structures: This unit is associated with 241-A-350, 241-A Tank Farm, 200-E-167-PL, 200-E-210-PL.

Process Description: The 241-A Tank Farm valve pits were used to route wastes to and from the 242-A Evaporator; 241-AN, 241-AW, 241-AY, and 241-AZ Tank Farms; PUREX; and the 244-A DCRT.

Transfers from 244-A may have included cross-site, 244-CR, and B-Plant wastes.

Waste Type: Process Effluent

Waste Description: The 241-A Tank Farm valve pits are used to route wastes to and from the 242-A Evaporator; 241-AN, 241-AW, 241-AY, and 241-AZ Tank Farms; PUREX; and the 244-A DCRT. Transfers from 244-A may include cross-site, 244-CR, and B-Plant wastes.

Code: 241-A-101

Classification: Accepted

Names: 241-A-101; 241-A-TK-101

Reclassification: None

Type: Single-Shell Tank

Start Date: 1/1/1956

Status: Inactive

End Date: 1/1/1980

Description: The unit is carbon-steel lined, with a reinforced concrete shell, dome, and base. The dome is located below grade for shielding. This is a third-generation tank with an increased operating depth and a flat (instead of dished) bottom.

Location: The 241-A-101 tank is located in the southwestern portion of the 241-A Tank Farm.

Process Description: The tank is used for the storage of mixed waste generated at Hanford.

Waste Type: Storage Tank

Waste Description: Activity in Tank 241-A-101 began when it was filled with PUREX high-level waste and organic wash waste in 1956. Activity ceased when the tank was deactivated in November 1980.

Code: 241-A-102

Classification: Accepted

Names: 241-A-102; 241-A-TK-102

Reclassification: None

Type: Single-Shell Tank

Start Date: 1/1/1956

Status: Inactive

End Date: 1/1/1980

Description: The unit is carbon-steel lined, with a reinforced concrete shell, dome, and base. The dome is located below grade for shielding. This is a third-generation tank with an increased operating depth and a flat (instead of dished) bottom.

Location: The 241-A-102 tank is located in the southwestern portion of the 241-A Tank Farm.

Process Description: The tank is used for the storage of mixed waste generated at Hanford.

Waste Type: Storage Tank

Waste Description: Tank 241-A-102 was filled with PUREX waste in 1956. The tank was declared deactivated in November 1980 and intrusion prevention was completed during 1982. The tank was interim stabilized in August 1989 after most of the supernatant was pumped. The tank waste is classified as double-shell slurry feed.

Code: 241-A-103

Classification: Accepted

Names: 241-A-103; 241-A-TK-103

Reclassification: None

Type: Single-Shell Tank

Start Date: 1/1/1956

Status: Inactive **End Date:** 1/1/1980

Description: The unit is carbon-steel lined, with a reinforced concrete shell, dome, and base. The dome is located below grade for shielding. This is a third-generation tank with an increased operating depth and a flat (instead of dished) bottom.

Location: The 241-A-103 tank is located in the southern portion of the 241-A Tank Farm.

Process Description: The tank is used for the storage of mixed waste generated at Hanford.

Waste Type: Storage Tank

Waste Description: Tank 241-A-103 was filled with self-concentrating PUREX waste from 1956 until 1969. Tank 241-A-103 was declared inactive in August 1980.

Code: 241-A-104 **Classification:** Accepted

Names: 241-A-104; 241-A-TK-104 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1958

Status: Inactive **End Date:** 1/1/1975

Description: The unit is carbon-steel lined, with a reinforced concrete shell, dome, and base. The dome is located below grade for shielding. This is a third-generation tank with an increased operating depth and a flat (instead of dished) bottom.

Location: The 241-A-104 tank is located in the western portion of the 241-A Tank Farm.

Process Description: The tank is used for the storage of mixed waste generated at Hanford.

Waste Type: Storage Tank

Waste Description: The tank contains non-complexed waste.

Code: 241-A-105 **Classification:** Accepted

Names: 241-A-105; 241-A-TK-105 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1962

Status: Inactive **End Date:**

Description: The unit is carbon-steel lined, with a reinforced concrete shell, dome, and base. The dome is located below grade for shielding. This is a third-generation tank with an increased operating depth and a flat (instead of dished) bottom.

Location: The 241-A-105 tank is located in the center portion of the 241-A Tank Farm, between tanks 241-A-104 and 241-A-106.

Process Description: The tank is used for the storage of mixed waste generated at Hanford.

Waste Type: Storage Tank

Waste Description: The waste in this tank is non-complexed.

Code: 241-A-106	Classification: Accepted
Names: 241-A-106; 241-A-TK-106	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1957
Status: Inactive	End Date: 1/1/1980

Description: The unit is carbon-steel lined, with a reinforced concrete shell, dome, and base. The dome is located below grade for shielding. This is a third-generation tank with an increased operating depth and a flat (instead of dished) bottom.

Location: The 241-A-106 tank is located in the eastern portion of the 241-A Tank Farm, north of than 241-A-103.

Process Description: The tank is used for the storage of mixed waste generated at Hanford.

Waste Type: Storage Tank

Waste Description: Tank 241-A-106 received deentrained waste and condensate waste from the boiling waste tanks in the A Tank Farm from 1957 to 1960. The waste is classified as concentrated phosphate.

Code: 241-A-152	Classification: Accepted
Names: 241-A-152; 241-A-152 Diversion Box	Reclassification: None
Type: Diversion Box	Start Date: 1/1/1956
Status: Inactive	End Date: 1/1/1980

Description: This diversion box is a reinforced concrete structure containing four stainless steel transfer pipes and adequate space to allow for jumper replacement activities. The major portion of the diversion box is below grade with concrete cover blocks and lifting hooks.

Location: The unit is located inside the 241-A Tank Farm fence, east of the 241-A-106 Tank.

Related Sites/Structures: It is associated with the 241-A-302-B Catch Tank, drain line V062, 216-A-7 crib, 200-E-182-PL and 200-E-207-PL.

Process Description: This unit routed waste from 241-A-151 Diversion Box to 241-CR-151 Diversion Box through a pipe encasement containing four stainless steel lines.

Waste Type: Process Effluent

Waste Description: Waste transferred through 241-A-152 includes fuel decladding waste, organic wash waste, sump waste, and laboratory waste. Lead shielding may also be contained inside the diversion box.

Waste Type: Equipment

Waste Description: The diversion box contains lead shielding.

Code: 241-A-153	Classification: Accepted
Names: 241-A-153; 241-A-153 Diversion Box; 241-A-153 Transfer Station	Reclassification: None

Type: Diversion Box **Start Date:** 1/1/1956

Status: Inactive **End Date:** 1/1/1985

Description: This diversion box is a reinforced concrete structure sized to accommodate the pipes and provide space for jumper replacement. The 241-A-153 is one type of diversion box, known as a transfer box. It connects one common pipe to several others, one at a time, uses only one jumper and has the several nozzles arranged in a circle about the common nozzle.

Location: The 241-A-153 Diversion Box is located inside the 241-A Tank Farm fence, southwest of tank 241-A-104.

Related Sites/ Structures: This tank is associated with the 241-A Tank Farm and the 244-AR Vault.

Process Description: This unit routes waste from the 241-A Tank Farm to the 244-AR Vault.

Waste Type: Process Effluent

Waste Description: This unit contains PUREX high level waste, and PUREX organic wash waste. Lead shielding may also be contained inside the diversion box.

Waste Type: Equipment

Waste Description: This unit contains lead shielding.

Code: 241-A-302B **Classification:** Accepted

Names: 241-A-302B; 241-A-302-B Catch Tank; V062 **Reclassification:** None

Type: Catch Tank **Start Date:**

Status: Inactive **End Date:**

Description: The east slope of the 241-A Tank Farm has been sprayed with shotcrete. The shotcrete surrounds the area where the 241-A-302B Catch Tank is located. A riser and electrical box are visible. A staircase has been installed to provide access to the tank surface. The underground tank is positioned horizontally. The tank is marked and radiologically posted.

Location: The 241-A-302B catch tank is buried outside the tank farm perimeter fence, east of 241-A Tank Farm, adjacent to Canton Ave.

Related Sites/ Structures: The unit is associated with 241-A Tank Farm and 241-A-152 Diversion Box and the 200-E-182-PL pipeline. The drain line to this catch tank is V062.

Process Description: The tank received liquid effluents from the 241-A-151 Diversion Box, located south of PUREX, and the 241-A-152 diversion box, that is located inside the tank farm perimeter fence.

Waste Type: Process Effluent

Waste Description: This unit was used for transfer of waste solutions from processing and decontamination operations to the tank farms. Volumes varied according to specific plant operation. The tank was isolated in 1985 and stabilized (pumped) in 1990. The volume of waste reported to be remaining in the tank is not consistent in all documents. The Miscellaneous Underground Radioactive Tanks report (1992) states there is 8581 liters (2270 gallons) of supernate and 3137 liters (830 gallons) of sludge. The Waste Tank Summary Report for April 1996 states there is a total of 18,685 liters (4943 gallons) of waste remaining in the tank.

Code: 241-A-350 **Classification:** Accepted

Names: 241-A-350; 241-A-350 Catch Tank; 241-A-350 Drainage Lift Station **Reclassification:** None

Type: Catch Tank **Start Date:** 1/1/1956

Status: Inactive **End Date:** 1/1/2005

Description: The unit is an underground reinforced concrete pump pit, with a cover block. The pump pit drains any leaks from the pump through the pump pit floor drain to an 800-gallon (3000-liter) stainless steel tank below.

Location: The unit is located inside the 241-A Tank Farm fence, southeast of tank 241-A-106.

Related Sites/Structures: The unit is associated with 241-A Tank Farm and 241-A-A and 241-A-B diversion boxes and 207-A.

Process Description: The unit is designed to receive drainage from the 241-A-A and 241-A-B valve pits, 241-A service pit, 241-A&B flush pits, 241-A clean out boxes, 241-A-431 ventilation equipment, and out of specification 241-A-207 retention basin solution.

Waste Type: Storage Tank

Waste Description: This unit contains aging PUREX high-level waste, PUREX acid concentrator waste, organic wash waste, and 241-A-207 Retention Basin solution.

Code: 241-A-417 **Classification:** Accepted

Names: 241-A-417; 241-A-417 Condensate Tank **Reclassification:** None

Type: Catch Tank **Start Date:** 1/1/1959

Status: Inactive **End Date:** 1/1/2005

Description: This unit is an underground cylindrical concrete vault lined with an all welded steel liner. Two overflow lines near the top of the vault prevent overflow of the tank. Above the tank are two rectangular pits, a pump pit and a valve pit. The floor of both pits slope to drains that empty to the tank.

Location: The tank is located inside the 241-A Tank Farm fence, east of the 241-A-702 Building.

Release Description: On March 25, 1980, a routine pressure test of the underground F-100 condensate return pipeline from the AX-501 Valve Pit to the 241-A-417 condensate catch tank failed. An April 3, 1980 investigation found a leak at the flange connection. An excavation at the pipeline leak was done. Two barrels of contaminated soil, reading 10,000 counts per minute, was taken to a burial ground. A new gasket was installed.

Related Sites/Structures: The unit is associated with 241-A Tank Farm, 241-AX Tank Farm, and the 216-A-24 Crib.

Process Description: This unit collects condensate from the 241-A-401 Condenser House, 241-A-702, and from 241-AZ-154. Condensate may be pumped back to the 241-AX Tank Farms or overflow to the 216-A-24 Crib.

Waste Type: Steam Condensate

Waste Description: This unit collects condensate for the 241-A-702 process condensate, the 241-A-401 process condensate, and the 241-AZ-154 steam condensate.

Code: 241-A-431 **Classification:** Accepted
Names: 241-A-431; 241-A-431 Tank Farm Ventilation Building; 241-A-431 Ventilation Building **Reclassification:** None
Type: Process Unit/Plant **Start Date:** 1/1/1955
Status: Inactive **End Date:** 1/1/1969

Description: The unit is a concrete structure, with the lower portion below grade. The unit is divided into two sections. One section houses the ventilation equipment. The other section houses the de-entrainment equipment. The building is 8 meters (25 feet) high, with the lower 4.9 meters (16 feet) below grade.

Location: The unit is located southeast of the 241-A-103 Tank, inside the 241-A Tank Farm fence.

Related Sites/ Structures: The building is associated with the 241-A Tank Farm, 216-A-16, 216-A-17, 216-A-23-A and 216-A-23-B French Drains, 216-A-34, 216-A-19, 216-A-20 and the 296-A-11 Stack.

Process Description: This structure is a tank farm ventilation building that provided off gas de-entrainment for the 241-A Tank Farm and also received the 296-A-11 Stack drainage.

Waste Type: Equipment

Waste Description: The unit contains radioactively contaminated equipment and concrete. It provided off-gas de-entrainment for the 241-A Tank Farm and also received the 296-A-11 Stack drainage.

Code: 241-A-501 **Classification:** Accepted
Names: 241-A-501; 241-A-501 Contact Condenser Valve Pit **Reclassification:** None
Type: Valve Pit **Start Date:**
Status: Inactive **End Date:**

Location: The valve pit is located inside 241-A Tank Farm, west of 241-A-152 diversion box and east of 241-A-106 tank.

Related Sites/ Structures: The structure is associated with the 216-A-8 crib.

Process Description: The 241-A-501 valve pit received raw water and cooling water from the PUREX facility, via the 241-A201 storage tank. The cooling water ran out of the valve pit to the E-411 (EP-241-A-161) and E-412 (EP-241-A-162) contact condensers. The output from the contact condensers went to the 241-A-401 condenser building.

Code: 241-A-702-WS-1 **Classification:** Accepted
Names: 241-A-702-WS-1; 702-A Drain Lines **Reclassification:** None
Type: French Drain **Start Date:** 1/1/1968
Status: Inactive **End Date:** 1/1/1995

Description: The unit is a french drain that received steam condensate from the 241-A-702 Ventilation Building.

Location: The unit is located inside the 241-A Tank Farm fence, west of the 241-A-702 Ventilation Building.

Related Sites/ Structures: The unit is associated with the 241-AY and 241-AZ Tank Farm and the 241-A-702 Ventilation Building.

Process Description: The drain is used in association with the 241-A-702 ventilation system. Process steam was used in steam heaters during normal and reduced operating conditions to raise the temperature of vent gases from the 241-AY and 241-AZ Tanks to prevent wetting of filters. The drain was used in conjunction with a steam trap for the system.

Waste Type: Steam Condensate

Waste Description: The unit received steam condensate from the 241-A-702 Ventilation Building.

Code: 241-AX-A **Classification:** Accepted

Names: 241-AX-A; 241-AX-A Diversion Box; 241-AX-A Structural Valve Pit; 241-AX-A Valve Pit **Reclassification:** None

Type: Valve Pit **Start Date:** 1/1/1965

Status: Inactive **End Date:**

Description: The unit is an underground reinforced concrete structure with 1 foot (0.31 meter) thick walls and floor.

Location: The 241-AX-A is located inside the 241-AX Tank Farm, southwest of tank 241-AX-104.

Related Sites/ Structures: This unit is associated with 241-AY-102 and 241-AX Tank Farm. The unit is interconnected with the 241-AX-B Valve Pit, the 241-A-A Pit, the 241-A-B Pit, and the 242-A Evaporator.

Process Description: 241-AX-A direct slurry into tanks or supernate out of tanks by manipulation of the correct valve.

Waste Type: Process Effluent

Waste Description: The unit transports waste solutions from processing and decontamination operations. Quantities are variable according to specific plant operation.

Code: 241-AX-B **Classification:** Accepted

Names: 241-AX-B; 241-AX-B Diversion Box; 241-AX-B Structural Valve Pit; 241-AX-B Valve Pit **Reclassification:** None

Type: Valve Pit **Start Date:** 1/1/1965

Status: Inactive **End Date:**

Description: The unit is an underground reinforced concrete structure with 1foot (.31 meters) thick walls and floor.

Location: The 241-AX-B is located inside the 241-AX Tank Farm, southwest of tank 241-AX-104.

Related Sites/ Structures: The unit is associated with the 241-AY-102 and the 241-AX Tank Farm. The unit is interconnected with the 241-AX-A Valve Pit, the 241-A-A Pit, the 241-A-B Pit, and the 242-A Evaporator.

Process Description: 241-AX-B directed slurry into tanks or supernate out of tanks by manipulation of the correct valve.

Waste Type: Process Effluent

Waste Description: The unit transports waste solutions from processing and decontamination operations. Quantities are variable according to specific plant operation.

Code: 241-AX-IX **Classification:** Accepted
Names: 241-AX-IX; 241-AX Ion Exchanger **Reclassification:** None
Type: Storage Tank **Start Date:** 1/1/1967
Status: Inactive **End Date:** 1/1/1976

Description: The ion exchange system consists of an above ground filter and ion exchange column. The ion exchange column is enclosed in a shielded structure. The ion exchange column sits on top of a 2.4 meter (8 foot) concrete structure.

Location: The 241-AX-IX is located in the southern portion of the 241-AX Tank Farm. It is northeast of the 241-A-417 condensate hold up tank, between the 241-A and 241-AX tank farms.

Related Sites/ Structures: The system is associated with the 216-A-8 crib.

Process Description: The 241-AX-IX is an ion exchanger comprised of the exchange column and underground piping. The resin column is located inside a shielded structure that is open at the top. It was installed in 1967 and operated from 1973 to 1976 to remove cesium from the 702-A tank vapor condensate, collected in the 241-A-417 tank. Condensate was pumped from 241-A-417 through the filter and into the top of the ion exchange column. The condensate would gravity flow through the column and normally be discharged to the 218-A-8 crib.

Waste Type: Equipment

Waste Description: The 241-AX-IX removed cesium from the 702-A tank vapor condensate, collected in the 241-A-417 tank.

Code: 241-AX-101 **Classification:** Accepted
Names: 241-AX-101; 241-AX-TK-101 **Reclassification:** None
Type: Single-Shell Tank **Start Date:** 1/1/1965
Status: Inactive **End Date:** 1/1/1980

Description: The unit is carbon-steel lined, with a reinforced concrete shell, dome, and base. This is a third-generation tank having a flat bottom, and an additional grid of drain slots beneath the steel liner bottom. The dome is below grade for shielding.

Location: The 241-AX-101 tank is located in the northeast corner of the 241-AX Tank Farm.

Process Description: The 241-AX tanks received high level self boiling waste from PUREX operations.

Waste Type: Storage Tank

Waste Description: Double shell slurry feed is waste concentrated just before reacting the sodium aluminate saturation boundary in the evaporator without exceeding the receiver tank composition limit.

Code: 241-AX-102 **Classification:** Accepted
Names: 241-AX-102; 241-AX-TK-102 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1966
Status: Inactive **End Date:** 1/1/1980

Description: The unit is carbon-steel lined, with a reinforced concrete shell, dome, and base. The dome is below grade for shielding. This is a third-generation tank having a flat bottom, and an additional grid of drain slots beneath the steel liner bottom.

Location: The 241-AX-102 tank is located in the southeast corner of the 241-AX Tank Farm.

Process Description: 241-AX tanks received high-level self boiling waste from PUREX operations.

Waste Type: Storage Tank

Waste Description: This tank received concentrated complexant which is a concentrate product from the evaporation of dilute complexed waste.

Code: 241-AX-103 **Classification:** Accepted
Names: 241-AX-103; 241-AX-TK-103 **Reclassification:** None
Type: Single-Shell Tank **Start Date:** 1/1/1965
Status: Inactive **End Date:** 1/1/1980

Description: The unit is carbon-steel lined, with a reinforced concrete shell, dome, and base. This is a third-generation tank having a flat bottom, and an additional grid of drain slots beneath the steel liner bottom. The dome is below grade for shielding.

Location: The 241-AX-103 tank is located in the northwest corner of the 241-AX Tank Farm.

Process Description: 241-AX tanks received high-level, self-boiling waste from PUREX operations.

Waste Type: Storage Tank

Waste Description: This tank received concentrated complexant which is concentrated product form the evaporation of dilute complexed waste.

Code: 241-AX-104 **Classification:** Accepted
Names: 241-AX-104; 241-AX-TK-104 **Reclassification:** None
Type: Single-Shell Tank **Start Date:** 1/1/1966
Status: Inactive **End Date:** 1/1/1976

Description: The unit is carbon-steel lined, with a reinforced concrete shell, dome, and base. The dome is below grade for shielding. This is a third-generation tank having a flat bottom, and an additional grid of drain slots beneath the steel liner bottom.

Location: The 241-AX-104 tank is located in the southwestern portion of the 241-AX Tank Farm.

Process Description: 241-AX tanks received high level self boiling waste from PUREX operations.

Waste Type: Storage Tank

Waste Description: This tank received non-complexed waste which is a general waste term applied to all Hanford Site non-complexed liquors non-identified as complexed.

Code: 241-AX-152DS **Classification:** Accepted
Names: 241-AX-152DS; 241-AX-152-DS Diverter Station; Line V713; 241-AX-152 Diverter Station **Reclassification:** None
Type: Diversion Box **Start Date:** 1/1/1965
Status: Inactive **End Date:** 1/1/2001

Description: The unit is a reinforced concrete structure with the top at ground level. There are two diverter tanks in a common cell with a stainless steel liner on the floor that extends approximately 1 foot (0.31 meters) up the cell wall. There is also a pump pit that does not have a stainless steel liner. The cell and pump pit drain to a catch tank below.

Location: The 241-AX-152 Diverter Station is located in the western portion of the 241-AX Tank Farm.

Related Sites/Structures: The unit is associated with the 241-AX, 241-AZ, and 241-AY tank farms and the 241-AX-152 Catch Tank. The drain line is V713.

Process Description: Diverter station 241-AX-152DS is used to transfer mixed waste solutions from processing and decontamination operations.

Waste Type: Equipment

Waste Description: This unit transports waste solutions from processing and decontamination operations. Volumes are variable according to specific plant operation.

Waste Type: Chemicals

Waste Description: This unit transports waste solutions from processing and decontamination operations. Volumes are variable according to specific plant operation.

Code: 241-AX-153 **Classification:** Accepted
Names: 241-AX-153; 241-AX-153 Isolation Jumper Pit **Reclassification:** None
Type: Diversion Box **Start Date:**
Status: Inactive **End Date:**

Description: The site is an underground cement structure with cement cover blocks.

Location: The 241-AX-153 Jumper Pit is located west of 241-AX-103 tank and east of the 241-AX-152 diverter Station, inside the 241-AX Tank Farm.

Process Description: The isolation jumper pit had three transfer lines going into it - a three inch line, number 4026 (from 241-AX-152 Diverter station), three inch line number 4026 (a construction pipe that has been isolated - welded cap) and a three inch line number 4021 (line bypasses the 241-AX-152 Diverter Station). Line 4021 was isolatable from the 241-AX-152 diverter station because of this isolation jumper pit.

Code: 241-AX-501 **Classification:** Accepted
Names: 241-AX-501; 241-AX-501 Condensate Valve Pit; 241-AX-501 Valve Pit **Reclassification:** None

Type: Valve Pit**Start Date:****Status:** Inactive**End Date:****Description:** The unit is a reinforced concrete structure that contains a valve that routes the tank farm condensate to the 241-A-417 Pump Pit.**Location:** This unit is located inside the north end of the 241-A Tank Farm, northwest of 241-A-417.**Related Sites/
Structures:** The unit interconnects AX Tank Farm to the 241-A-417 Pump Pit and Tank.**Process
Description:** The valve routes and receives tank farm condensate.**Waste Type:** Storage Tank**Waste
Description:** The unit receives and routes tank farm condensate.

Code: 241-AY-152**Classification:** Accepted**Names:** 241-AY-152; 241-AY-152 Diverter Station; 241-AY-152 Sluice Transfer Box; Line DR0074**Reclassification:** None**Type:** Diversion Box**Start Date:** 1/1/1971**Status:** Inactive**End Date:** 1/1/1985**Description:** The unit is an underground, reinforced concrete structure.**Location:** 241-AY-152 is located in the western portion of the 241-AX Tank Farm.**Related Sites/
Structures:** The unit is associated with the 241-A and the 241-AX single-shell tank farm. The drain line is DR0074.**Process
Description:** This unit is used to transport radioactive waste solutions between storage and process facilities.**Waste Type:** Process Effluent**Waste
Description:** This diversion box received PUREX organic wash, PUREX acid, PUREX high level waste and B Plant high level waste. Lead shielding may also be contained inside the diversion box.**Waste Type:** Equipment**Waste
Description:** This diversion box contains lead shielding.

Code: 241-AY-501**Classification:** Accepted**Names:** 241-AY-501; 241-AY-501 Condensate Valve Pit**Reclassification:** None**Type:** Valve Pit**Start Date:****Status:** Inactive**End Date:****Description:** The pit is an underground cement structure with cement cover blocks. The valve pit has been isolated and weather sealed.**Location:** The valve pit is located inside the 241-AX Tank Farm fence, east of tank 241-AY-101 and west

of 241-AX-103.

Related Sites/ Structures: The site is associated with 241-A-417.

Process Description: The 241-AY-501 valve pit was used to distribute condensate from the 702-A ventilation system to the 241-AX, 241-AY and 241-AZ tank farms. The condensate collected in the 241-A-417 tank.

Code: 200-E-131 **Classification:** Accepted

Names: 200-E-131; Contaminated Soil Associated with 241-A Tank Farm Complex **Reclassification:** None

Type: Contamination Migration **Start Date:**

Status: Inactive **End Date:**

Description: The site is the soil inside and adjacent to the chain link fence that surrounds the 241-A, AN, AX, AY and AZ Tank Farms. Various radiological postings and warning signs are attached to the chain link fence. The interior of the tank farm complex is covered with gravel. Many risers and monitoring devices for the underground structures are visible on the surface. The individual unplanned releases are not marked or posted. Occasionally, radioactive contamination is found adjacent to the outside of the tank farm fence, resulting in a contamination zone extension. These areas will also be considered tank farm soil.

Location: This site is defined as the fenced area containing the 241-A, AN, AX, AY, and AZ Tank Farms. It is inside 200 East Area, west of Canton Ave.

Release Description: The exact extent (horizontal and vertical) of the soil contaminated by unplanned releases that occurred within this farm complex over the years are not known. Some of the single shell tanks have leaked to the soil below the tank farm. Other releases spread contamination to the surface soil surrounding the tanks. Document HW-53449 states that in 1957 the pipeline to the 433 de-entrainment tank were replaced because the lines had failed and leaked. Does rates varied from 2 millirem per hour to 2 rad per hour during the activity. Several hundred gallons of condensed vapors from the 241-A waste storage tanks were pumped out of a stub on the west side of the 417-A jumper pit 11 in 1964. Construction forces were preparing to make the final weld in a line to tie tank 105-A into the 151-AX diverter station. The line was observed to shake and liquid spill out on to the ground in the excavation as a result of a pressurization event in tank A-105. Radiation readings of 400 rads/hr @ 1foot was observed on January 28,1965. On March 25, 1980, a routine pressure test of the underground F-100 condensate return pipeline from the AX-501 Valve Pit to the 241-A-417 condensate catch tank failed. An April 3, 1980 investigation found a leak at the flange connection. An excavation at the pipeline leak was done. Two barrels of contaminated soil, reading 10,000 counts per minute, was taken to a burial ground. A new gasket was installed. On January 29, 1968, hot water and a pressurized line from a fire truck was used to try to unplug the 241-AX-102 to 241-C-102 pipeline. Liquid was noticed coming up near the 241-AX-103 tank, so the flushing operation was discontinued.

Related Sites/ Structures: Previously individually defined unplanned releases that were identified in WIDS located inside the A Tank Farm Complex are UPR-200-E-47, UPR-200-E-48, UPR-200-E-115, UPR-200-E-119, UPR-200-E-125, and UPR-200-E-126. Some of these sites are listed in TPA Appendix B as TSD-associated sites, but all are to be addressed with the closeout of the tank farm TSD. As such, site 200-E-131 is also a TSD-associated site.

Waste Type: Process Effluent

Waste Description: Liquid releases occurred from underground leaks in tanks and transfer lines. Airborne contamination spreads occurred from activities conducted in valve pits and diversion boxes.

Both types of releases contributed to the contamination in the soil.

Code: 200-E-200-PL **Classification:** Accepted
Names: 200-E-200-PL; Lines 801, 802, 806 and 805; Pipelines from 244-AR Vault to 241-AY-152 and 241-A-153 Diversion Boxes **Reclassification:** None
Type: Direct Buried Tank Farm Pipeline **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is four underground, 15 centimeter (6 inch) diameter carbon steel pipelines buried in the same soil trench. The lines split into a "Y" east of the 241-A Tank Farm fence. Lines 802 and 806 divert to 241-AY-152 Diversion Box. Lines 801 and 805 divert to the 241-A-153 Diversion Box.

Location: The pipelines extend from the 244-AR Vault building to the 241-A Tank Farm. The lines cross under Buffalo Ave.

Related Sites/ Structures: The transfer line is associated with 244-AR Vault, 241-A-153 and 241-AY-152.

Code: 2607-EC **Classification:** Accepted
Names: 2607-EC **Reclassification:** None
Type: Septic Tank **Start Date:** 1/1/1963
Status: Inactive **End Date:**

Description: This unit includes a septic tank and dry well.

Location: HNF-SD-LL-SP-001 shows the location of the septic tank in the northeast corner of 241-A tank farm, near the fence.

Related Sites/ Structures: HNF-6612 says the septic tank is associated with 241-AR-271.

Waste Type: Sanitary Sewage

Waste Description: Sanitary wastewater and sewage. In 1995, the estimated rate of waste generation is 0.45 cu m/d.

Code: 2607-ED **Classification:** Accepted
Names: 2607-ED **Reclassification:** None
Type: Septic Tank **Start Date:** 1/1/1980
Status: Inactive **End Date:**

Description: The 2607-ED Septic Tank receives sanitary wastewater and sewage from the 2707-AX Building and drains to the drain field. The drain field has a capacity of 257 gallons (973 liters) per day.

Location: This unit lies south of the 241-AX-102 tank, inside the tank farm fence.

**Related Sites/
Structures:** The 2607-ED Septic Tank is associated with the 2707-AX Building and lies within the AX Tank Farm.

**Process
Description:** The 2607-ED Septic Tank and associated drain field are designed to accept sanitary sewer effluent from the 2707-AX Building.

Waste Type: Sanitary Sewage

**Waste
Description:** The 2607-ED Septic Tank receives sanitary wastewater and sewage from the 2707-AX Building at an estimated rate of 10 cubic feet (0.28 cubic meters) per day.

WMA B/BX/BY

Code: 241-B-101	Classification: Accepted
Names: 241-B-101; 241-B-TK-101	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1945
Status: Inactive	End Date: 1/1/1974

Description: The unit is comprised of a carbon steel liner within a reinforced concrete shell, 9 meters (30 feet) high, with a capacity of 2,017,405 liters (533,000 gallons). The bottom is 11.3 meters (37 feet) below grade, and the dome is located below grade for shielding purposes. This type was built to the original single-shell design, having a dished bottom and a 5.2 meters (17 feet) operating depth. The tank is passively ventilated.

Location: The tank is located about 914 meters (3,000 feet) north northeast of the 221-B building.

Release Description: A leak of 30,280 liters (8,000 gallons) occurred prior to or during 1974. The leak estimate of 30,280 liters (8,000 gallons) is an average total from 19 tanks.

Waste Type: Storage Tank

Waste Description: Initially tank B-101 received metal waste in 1945. The tank received and transferred waste via cascade lines from 1945 until 1963. During 1953, B-101 processed feed for U Plant. From 1953 until 1963, the tank contained supernatant containing evaporator bottoms waste from 241-B tanks. During 1957, in-farm scavenged feed was sent to the 244-CR Vault. From 1960 until 1970, B-101 received wastewater. Also, it was found that during 1960 wastewater leaked into the pipe encasement which drained to B-101. During 1963 the tank received PUREX coating waste. B-101 received B Plant high-level waste (Cell 23) from 1969 until 1970. From 1970 until 1973, the tank received B Plant, Cell 23 evaporator bottoms. The tank also received bismuth phosphate metal waste and waste in route to in-tank solidification. Presently, the waste material is classified as non-complexed and has a total waste volume of 427,705 liters (113,000 gallons). Sludge comprises the total 427,705 liters (113,000 gallons). There is no saltcake or pumpable liquid and 6,000 gallons of drainable interstitial liquid remaining. An analysis was conducted on a B-101 sludge sample in February 1976. The sample was found to have a consistency of soft mud and was dark brown. A heat generation rate based on strontium-89, strontium-90, and cesium-137 was calculated to be 0.0201 watts/liter of sludge. The resulting solids remaining in this tank (based on core samples) contain an estimated 4 million Curies of strontium (92,000 BTU/h). The curie content listed is not decayed to a consistent date; therefore, a cumulative total is inappropriate.

Code: 241-B-102	Classification: Accepted
Names: 241-B-102; 241-B-TK-102	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1945
Status: Inactive	End Date: 1/1/1978

Description: The unit is comprised of a carbon steel liner within a reinforced concrete shell, 9 meters (30 feet) high, with a capacity of 2,017,405 liters (533,000 gallons). The bottom is 11.3 meters (37 feet) below grade, and the dome is located below grade for shielding purposes. This type was built to the original single-shell design, having a dished bottom and a 5.2 meters (17 feet) operating depth. Tank 241-B-102 is the second tank in a "cascade" connecting it to tanks 241-B-101 and 241-B-103. The tank is passively ventilated.

Location: Tank 241-B-102 is located on the north side of the 200 East Area about 914 meters (3,000 feet) north northeast of the 221-B building.

Release Description: While pumping supernatant from tank 241-B-102 to tank 241-B-101, tank farm personnel noticed soil discoloration around the 241-B-102 heel pit indicating a leak in the transfer line. Surface soil contamination with readings of 10 R/hr were recorded. The contaminated ground area was immediately covered with asphalt to reduce radionuclide migration. This UPR is reported as UPR-200-E-108.

Waste Type: Storage Tank

Waste Description: Tank 241-B-102 went into service in 1945 by receiving metal waste produced by the bismuth phosphate process. The tank was sluiced in 1953 to remove the metal waste for uranium recovery then filled with a transfer from tank 241-B-105 (the active receiver tank for the 242-B Evaporator). Most of the contents of the tank were sent to tank 241-C-112 in 1957 for ferrocyanide scavenging of the supernate. Later that year the tank received water. The tank stood idle until 1963, when it began to receive cladding waste supernate from other tanks. The tank received a supernatant transfer from 241-B-101 in 1969 and was receiving high level waste from B Plant. Most of this supernate was transferred out of the tank in 1970. The tank received ion-exchange waste (B Plant) which was later transferred in a large supernate transfer in 1971. The tank also received low level waste from B Plant (1972), water waste transfer and pumpable liquids from other single-shell tanks (B-105, 107, and 110) that were being taken out of service (1972-1976). During this time tank 241-B-102 was also transferring supernate to tanks 241-B-103, 241-B-106, and 241-SX-106. The tank also received cladding removal waste supernate from the Plutonium-Uranium Extraction (PUREX) process and supernate from the fission product recovery process at B Plant. The tank also received ion exchange waste and evaporator bottoms from 241-B, -BX, and -C tank farms. Presently, the waste material is classified as non-complexed and has a total waste volume of 121,120 liters (32,000 gallons). Sludge comprises 68,130 liters (18,000 gallons) of the tank contents, saltcake 37,850 liters (10,000 gallons) and there is 15,140 liters (4,000 gallons) of drainable supernatant liquid remaining. The waste level is very low 17.8 centimeters (~7 inches).

Code: 241-B-103	Classification: Accepted
Names: 241-B-103; 241-B-TK-103	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1945
Status: Inactive	End Date: 1/1/1977

Description: The unit is a single-shell tank constructed of 0.3 meter (1 foot) thick reinforced concrete with a 6.4 millimeters (0.25 inch) mild carbon steel liner (ASTM A 283 Grade C) on the bottom and sides and a 0.38 meter (1.25 foot) thick domed concrete top. The top of the steel liner is 5.5 meters (18 feet) above the bottom of the tank (at the side wall). The tank has a dished bottom, with a maximum depth of 30 centimeters (12 inches) below the side wall of the tank and a 4 foot 1.2 meters (4 feet) radius knuckle. The tank has a 5.2 meters (17 feet) operating depth. The tank is set on a reinforced concrete foundation 11.3 meters (37 feet) below grade. A three-ply cotton fabric waterproofing was applied over the foundation and steel tank. Four coats of primer paint were sprayed on all exposed interior tank surfaces. The tank ceiling dome was covered with three applications of magnesium zincfluorosilicate wash. Lead flashing was used to protect the joint where the steel liner met the concrete dome. Asbestos gaskets were used to seal the manholes in the tank dome. The tank was waterproofed on the sides and top with tar and gunnite. Tank capacity is 2,017,405 liters (533,000 gallons). The tank was covered with approximately 2.2 meters (7.25 feet) of overburden for shielding purposes. Tank 241-B-103 is the third and final tank in a "cascade" connecting to tanks 241-B-101 and 241-B-102. The cascade overflow height is approximately 4.86 meters (192 inches) from the tank bottom (at the sidewall) and 0.61 meters (2 feet) below the top of the steel liner. The tank is passively ventilated.

Location: Tank 241-B-103 is located on the north side of the 200 East Area about 3,000 feet (914 m)

north northeast of the 221-B building.

Release Description: A leak of 30,280 liters (8,000 gallons) occurred prior to or during 1978. The leak estimate of 30,280 liters (8,000 gallons) is an average total from 19 tanks.

Waste Type: Storage Tank

Waste Description: Tank 241-B-103 went into service in 1945 by receiving waste cascaded from tank 241-B-102 until it was declared full in 1946. The tank was sluiced in 1953 for uranium recovery. From 1954 until 1963 the tank received supernate, evaporator bottoms waste and unknown waste from an unknown source. The tank also received bismuth phosphate metal waste; PUREX coating waste; and supernatant containing ion exchange waste, N Reactor waste, organic wash waste; PNNL waste, REDOX high-level waste, coating waste, evaporator bottoms, B Plant low-level waste, decontamination waste, tributyl phosphate waste, and laboratory waste from 241-B, -BX, and -C tank farms. Additional sources of waste are first and second cycle waste from B Plant and in-tank solidification (ITS-1 & ITS-2) evaporator bottoms. Presently, the waste material is classified as non-complexed and has a total waste volume of 59,000 gallons (223,315 L). Sludge is reported to comprise 59,000 gallons (223,315 L) of the tank contents with no saltcake, drainable, or pumpable liquid remaining. However, the Tank Layer Model (Agnew et al. 1994), estimates that the tank contains mostly saltcake 56,000 gallons (211,960 L), with a small amount of metal waste 3,000 gallons (11,355 L). The waste level in the tank is (~14 inches) 35 cm.

Code: 241-B-104	Classification: Accepted
Names: 241-B-104; 241-B-TK-104	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1946
Status: Inactive	End Date: 1/1/1972

Description: The single-shell tank is constructed of 0.3 meters (1 foot) thick reinforced concrete with a 6.4 millimeter (0.25 inch) mild carbon steel liner (ASTM A 283 Grade C) on the bottom sides and a 0.38 meter (1.25 foot) thick domed concrete top. The top of the steel liner is 5.5 meters (18 feet) above the bottom of the tank (at the side wall). The tank has a dished bottom, with a maximum depth of 30 centimeters (12 inches) below the side wall of the tank and at 1.2 meters (4 foot) radius knuckle. The tank has a 5.2 meters (17 foot) operating depth. The tank is set on a reinforced concrete foundation 11.3 meters (37 feet) below grade. A three-ply cotton fabric waterproofing was applied over the foundation and steel tank. Four coats of primer paint were sprayed on all exposed interior tank surfaces. The tank ceiling dome was covered with three applications of magnesium zincfluorosilicate wash. Lead flashing was used to protect the joint where the steel liner met the concrete dome. Asbestos gaskets were used to seal the manholes in the tank dome. The tank was waterproofed on the sides and top with tar and gunnite. Tank capacity is 2,017,405 liters (533,000 gallons). The tank was covered with approximately 2.2 meters (7.25 feet) of overburden for shielding purposes. The tank is passively ventilated.

Location: Tank 241-B-104 is located on the north side of the 200 East Area about 914 meters (3,000 feet) north northeast of the 221-B building.

Waste Type: Storage Tank

Waste Description: Tank 241-B-104 is equipped to cascade to tank 241-B-105 and is first in the three-tank cascade flow series. The tank received bismuth phosphate first and second-cycle waste; evaporator bottoms, and supernatant containing evaporator bottoms from the 241-B tanks. Presently, the waste material is classified as non-complexed and has a total waste volume of 371,000 gallons (1,404,235 L). Sludge is reported to comprise 301,000 gallons (1,139,285 L) and saltcake 69,000 (261,165 L). There is 40,000 gallons (151,400 L) pumpable liquid remaining and 47,000 gallons (177,895 L) of drainable liquid remaining. Drainable liquid includes 46,000

gallons (174,110 L) interstitial and 1,000 gallons (3,785 L) of supernatant liquid. The volume of waste converts to a waste level of almost 11 feet (3.4 m). More sample material is needed for full characterization of the waste.

Code: 241-B-105	Classification: Accepted
Names: 241-B-105; 241-B-TK-105	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1947
Status: Inactive	End Date: 1/1/1972

Description: The single-shell tank is constructed of 0.3 meters (1 foot) thick reinforced concrete with a 6.4 millimeter (0.25 inch) mild carbon steel liner (ASTM A 283 Grade C) on the bottom and sides and a 0.38 meters (1.25 foot) thick domed concrete top. The top of the steel liner is 5.5 meters (18 feet) above the bottom of the tank (at the side wall). The tank has a dished bottom, with a maximum depth of 30 centimeters (12 inches) below the side wall of the tank and a 1.2 meters (4 foot) radius knuckle. The tank has a 5.2 meters (17 foot) operating depth. The tank is set on a reinforced concrete foundation 11.3 meters (37 feet) below grade. A three-ply cotton fabric waterproofing was applied over the foundation and steel tank. Four coats of primer paint were sprayed on all exposed interior tank surfaces. The tank ceiling dome was covered with three applications of magnesium zincfluorosilicate wash. Lead flashing was used to protect the joint where the steel liner met the concrete dome. Asbestos gaskets were used to seal the manholes in the tank dome. The tank capacity is 2,017,405 liters (533,000 gallons). The tank was covered with approximately 2.2 meters (7.25 feet) of overburden for shielding purposes. The tank is passively ventilated.

Location: Tank 241-B-105 is located on the north side of the 200 East Area about 3,000 feet (914 m) north northeast of the 221-B building.

Release Description: A leak of 30,280 liters (8,000 gallons) occurred prior to or during 1978. The leak estimate of 30,280 liters (8,000 gallons) is an average total from 19 tanks. Tank B-105 was categorized "questionable integrity" due to the unexplained high level of activity in Dry Wells 20-05-06 and 20-06-06.

Waste Type: Storage Tank

Waste Description: Tank 241-B-105 is equipped to receive waste via cascade from tank B-104 and cascade to tank 241-B-106 and is second in the three-tank cascade flow series. The tank received bismuth phosphate first and second-cycle waste and flush water containing evaporator bottoms from the 241-B tanks. Presently, the waste material is classified as non-complexed and has a total waste volume of 306,000 gallons (1,158,210 L). Sludge is reported to comprise 40,000 gallons (151,400 L) and saltcake 266,000 (1,006,810 L). There is 23,000 gallons (87,055 L) of drainable liquid remaining and no pumpable liquid remaining. The volume of waste converts to a waste level of almost 9 feet (2.7 m). No samples have been taken from tank 241-B-105.

Code: 241-B-106	Classification: Accepted
Names: 241-B-106; 241-B-TK-106	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1947
Status: Inactive	End Date: 1/1/1977

Description: The single-shell tank is constructed of 0.3 meters (1 foot) thick reinforced concrete with a 6.4 millimeters (0.25 inch) mild carbon steel liner (ASTM A 283 Grade C) on the bottom and sides and a 0.38 meters (1.25 foot) thick domed concrete top. The top of the steel liner is 5.5 meters (18 feet) above the bottom of the tank (at the side wall). The tank has a dished bottom, with a

maximum depth of 30 centimeters (12 inches) below the side wall of the tank and a 1.2 meter (4 foot) radius knuckle. The tank has at 5.2 meters (17 foot) operating depth. The tank is set on a reinforced concrete foundation 11.3 meters (37 feet) below grade. A three-ply cotton fabric waterproofing was applied over the foundation and steel tank. Four coats of primer paint were sprayed on all exposed interior tank surfaces. The tank ceiling dome was covered with three applications of magnesium zincfluorosilicate wash. Lead flashing was used to protect the joint where the steel liner met the concrete dome. Asbestos gaskets were used to seal the manholes in the tank dome. The tank was waterproofed on the sides and top with tar and gunnite. Tank capacity is 2,017,405 liters (533,000 gallons). The tank was covered with approximately 2.2 meters (7.25 feet) of overburden for shielding purposes.

Location: Tank 241-B-106 is located on the north side of the 200 East Area about 914 meters (3,000 feet) north northeast of the 221-B building.

Waste Type: Storage Tank

Waste Description: The tank received bismuth phosphate first and second-cycle waste; Hanford Laboratory operations waste; supernatant containing tributyl phosphate waste; 224-U wastes, PNL waste, evaporator bottoms, B Plant low-level waste, ion exchange waste, and bismuth phosphate first-cycle waste from 241-B, -BX, -BY, and -C tanks. Presently, the waste material is classified as non-complexed and has a total waste volume of 442,845 liters (117,000 gallons). Sludge is reported to comprise 439,060 liters (116,000 gallons) and supernatant liquids comprise 3,785 liters (1,000 gallons). There is 26,495 liters (7,000 gallons) of drainable liquid remaining and no pumpable liquid remaining. The volume of waste is between 100.6-96.5 centimeters (39.6-38 inches). More sample material is needed for full characterization of tank waste.

Code: 241-B-107	Classification: Accepted
Names: 241-B-107; 241-B-TK-107	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1945
Status: Inactive	End Date: 1/1/1969

Description: The single-shell tank is constructed of 0.3 meter (1 foot) thick reinforced concrete with a 6.4 millimeter (0.25 inch) mild carbon steel liner (ASTM A 283 Grade C) on the bottom and sides and a 0.38 meters (1.25 feet) thick domed concrete top. The top of the steel liner is 5.5 meters (18 feet) above the bottom of the tank (at the side wall). The tank has a dished bottom, with a maximum depth of 30 centimeters (12 inches) below the side wall of the tank and a 1.2 meters (4 feet) radius knuckle. The tank has a 5.2 meters (17 feet) operating depth. The tank is set on a reinforced concrete foundation 11.3 meters (37 feet) below grade. A three-ply cotton fabric waterproofing was applied over the foundation and steel tank. Four coats of primer paint were sprayed on all exposed interior tank surfaces. The tank ceiling dome was covered with three applications of magnesium zincfluorosilicate wash. Lead flashing was used to protect the joint where the steel liner met the concrete dome. Asbestos gaskets were used to seal the manholes in the tank dome. The tank was waterproofed on the sides and top with tar and gunnite. Tank capacity is 2,017,405 liters (533,000 gallons). The tank was covered with approximately 2.2 meters (7.25 feet) of overburden for shielding purposes.

Location: Tank 241-B-107 is located on the north side of the 200 East Area about 914 meters (3,000 feet) north northeast of the 221-B building.

Release Description: Soil surrounding the 241-B-107 tank became contaminated in 1968 when approximately 30,280 liters (8,000 gallons) of waste containing 2,000 Ci of cesium-137 leaked from tank 241-B-107 in 1968. This UPR is recorded as UPR-200-E-127.

Waste Type: Storage Tank

Waste Description: 241-B-107 tank received PUREX coating waste; bismuth phosphate first-cycle waste; and supernatant containing bismuth phosphate first-cycle waste, bismuth phosphate second-cycle waste, and evaporator bottoms from the 241-B tanks. The tank also received uranium recovery waste, tri-butyl phosphate waste, non-complexed waste, 242-B evaporator saltcake, and wastewater. Presently, the waste material is classified as non-complexed and has a total waste volume of 165,000 gallons (624,525 L). Sludge is reported to comprise 164,000 gallons (620,740 L) and supernatant liquids comprise 1,000 gallons (3,785 L). There is 13,000 gallons (49,205 L) of drainable liquid remaining and 7,000 gallons (26,495 L) of pumpable liquid remaining. The volume of waste is about 4.5 feet (1.4 m) in the tank. There have been no samples taken of the tank waste.

Code: 241-B-108	Classification: Accepted
Names: 241-B-108; 241-B-TK-108	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1945
Status: Inactive	End Date: 1/1/1977

Description: The single-shell tank is constructed of 0.3 meter (1 foot) thick reinforced concrete with a 6.4 millimeters (0.25 inch) mild carbon steel liner (ASTM A 283 Grade C) on the bottom and sides and a 0.38 meter (1.25 foot) thick domed concrete top. The top of the steel liner is 5.5 meters (18 feet) above the bottom of the tank (at the side wall). The tank has a dished bottom, with a maximum depth of 30 centimeters (12 inches) below the side wall of the tank and a 1.2 meters (4 feet) radius knuckle. The tank has a 5.2 meter (17 feet) operating depth. The tank is set on a reinforced concrete foundation 11.3 meters (37 feet) below grade. A three-ply cotton fabric waterproofing was applied over the foundation and steel tank. Four coats of primer paint were sprayed on all exposed interior tank surfaces. The tank ceiling dome was covered with three applications of magnesium zincfluorosilicate wash. Lead flashing was used to protect the joint where the steel liner met the concrete dome. Asbestos gaskets were used to seal the manholes in the tank dome. The tank was waterproofed on the sides and top with tar and gunnite. Tank capacity is 2,017,405 liters (533,000 gallons). The tank was covered with approximately 2.2 meters (7.25 feet) of overburden for shielding purposes.

Location: Tank 241-B-108 is located on the north side of the 200 East Area about 914 meters (3,000 feet) north northeast of the 221-B building.

Waste Type: Storage Tank

Waste Description: 241-B-108 tank received PUREX coating waste; bismuth phosphate first-cycle waste, and supernatant containing evaporator bottoms and ion exchange waste from the 241-B and -BY tank farms. The tank also received non-complexed waste and 242-B evaporator saltcake waste. Presently, the waste material is classified as non-complexed and has a total waste volume of 94,000 gallons (355,790 L). Sludge is reported to comprise the 94,000 gallons (355,790 L). There is 4,000 gallons (15,140 L) of drainable interstitial liquid remaining and no pumpable liquid remaining. The volume of waste converts to approximately 2.5 feet (.8 m) in the tank. There have been no samples taken of the tank waste.

Code: 241-B-109	Classification: Accepted
Names: 241-B-109; 241-B-TK-109	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1946
Status: Inactive	End Date: 1/1/1977

Description: The single-shell tank is constructed of 0.3 meters (1 foot) thick reinforced concrete with a 6.4

millimeter (0.25 inch) mild carbon steel liner (ASTM A 283 Grade C) on the bottom and sides and a 0.38 meter (1.25 foot) thick domed concrete top. The top of the steel liner is 5.5 meters (18 feet) above the bottom of the tank (at the side wall). The tank has a dished bottom, with a maximum depth of 30 centimeters (12 inches) below the side wall of the tank and a 1.2 meters (4 foot) radius knuckle. The tank has a 5.2 meters (17 foot) operating depth. The tank is set on a reinforced concrete foundation 11.3 meters (37 feet) below grade. A three-ply cotton fabric waterproofing was applied over the foundation and steel tank. Four coats of primer paint were sprayed on all exposed interior tank surfaces. The tank ceiling dome was covered with three applications of magnesium zincfluorosilicate wash. Lead flashing was used to protect the joint where the steel liner met the concrete dome. Asbestos gaskets were used to seal the manholes in the tank dome. The tank was waterproofed on the sides and top with tar and gunnite. Tank capacity is 2,017,405 liters (533,000 gallons). The tank was covered with approximately 2.2 meters (7.25 feet) of overburden for shielding purposes. At present, the tank farm is enclosed by a 1.8 meter (6-foot) high chain link fence. The tanks are marked by yellow riser pipes and the ground surface is covered with gravel.

Location: Tank 241-B-109 is located on the north side of the 200 East Area about 914 meters (3,000 feet) north northeast of the 221-B building.

Waste Type: Storage Tank

Waste Description: 241-B-109 tank received PUREX coating waste; bismuth phosphate first-cycle waste, and supernatant containing evaporator bottoms, and ion exchange waste. The tank also received coating waste from the 241-B, -BY, and -S tank farms, non-complexed waste, waste water, 224-U waste, and 242-B evaporator saltcake waste. Presently, the waste material is classified as non-complexed and has a total waste volume of 127,000 gallons (480,822 L). There is disparity between sources for tank inventories. One source lists sludge for the total waste volume at 8,000 gallons (30,280 L) of drainable interstitial liquid. Another source reports the waste comprises 30,000 gallons (113,550 L) of unknown waste; 13,000 gallons (49,205 L) of sludge; and 84,000 gallons (317,940 L) of saltcake. The volume of waste converts to approximately 3.5 feet (1.1 m) in the tank. There have been no samples taken of the tank waste.

Code: 241-B-110	Classification: Accepted
Names: 241-B-110; 241-B-TK-110	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1945
Status: Inactive	End Date: 1/1/1971

Description: The single-shell tank is constructed of 0.3 meter (1 foot) thick reinforced concrete with a 6.4 millimeter (0.25 inch) mild carbon steel liner (ASTM A 283 Grade C) on the bottom and sides and a 0.38 meter (1.25 foot) thick domed concrete top. The top of the steel liner is 5.5 meter (18 feet) above the bottom of the tank (at the side wall). The tank has a dished bottom, with a maximum depth of 30 centimeters (12 inches) below the side wall of the tank and a 1.2 m (4 foot) radius knuckle. The tank has a 5.2 meters (17 foot) operating depth. The tank is set on a reinforced concrete foundation 11.3 meters (37 feet) below grade. A three-ply cotton fabric waterproofing was applied over the foundation and steel tank. Four coats of primer paint were sprayed on all exposed interior tank surfaces. The tank ceiling dome was covered with three applications of magnesium zincfluorosilicate wash. Lead flashing was used to protect the joint where the steel liner met the concrete dome. Asbestos gaskets were used to seal the manholes in the tank dome. The tank was waterproofed on the sides and top with tar and gunnite. Tank capacity is 2,017,405 liters (533,000 gallons). The tank was covered with approximately 2.2 meters (7.25 feet) of overburden for shielding purposes. At present, the tank farm is enclosed by a 1.8 meters (6-foot) high chain link fence. The tanks are marked by yellow riser pipes and the ground surface is covered with gravel.

Location: Tank 241-B-110 is located on the north side of the 200 East Area about 914 meters (3,000 feet) north northeast of the 221-B building.

Release Description: An unplanned release occurred in 1969 when approximately 31,416 liters (8,300 gallons) of waste containing about 4,300 Ci of cesium-137 leaked from tank 241-B-110 contaminating the soil surrounding the tank. The leak volume estimate is based solely on observed liquid level decreases in this tank and is considered to be the most accurate method for estimating leak volumes. This UPR is recorded as UPR-200-E-128.

Waste Type: Storage Tank

Waste Description: 241-B-110 tank received Bismuth phosphate first-cycle waste; bismuth phosphate second-cycle wastes; fission product waste; B Plant high-level waste (waste fractionization); B Plant waste from cells 5 and 6; B Plant flushes; and ion exchange waste; B Plant low-level waste; evaporator bottoms; non-complexed waste; decontamination waste; PUREX high-level waste; in-tank solidification waste; cesium recovery waste; and waste water. The waste material is classified as non-complexed and presently has a total waste volume of 931,001 liters (246,000 gallons). Sludge comprises the total except for 3,785 liters (1,000 gallons) of supernatant liquid. There is 64,345 liters (17,000 gallons) of pumpable liquid remaining. Level adjustments in 1982 and 1985 brought waste level measurements in the tank to current readings. The volume of waste converts to approximately 2.2 meters (7 feet) in the tank. While characterization of the solid contents has been performed, complete analysis of the upper layer must take place to more fully characterize this portion of the waste.

Code: 241-B-111	Classification: Accepted
Names: 241-B-111; 241-B-TK-111	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1945
Status: Inactive	End Date: 1/1/1976

Description: The single-shell tank is constructed of 0.3 meters (1 foot) thick reinforced concrete with a 6.4 millimeter (0.25 inch) mild carbon steel liner (ASTM A 283 Grade C) on the bottom and sides and a 0.38 meter (1.25 foot) thick domed concrete top. The top of the steel liner is 5.5 meters (18 feet) above the bottom of the tank (at the side wall). The tank has a dished bottom, with a maximum depth of 30 centimeters (12 inches) below the side wall of the tank and a 1.2 meter (4 foot) radius knuckle. The tank has a 5.2 meter (17 foot) operating depth. The tank is set on a reinforced concrete foundation 11.3 meter (37 feet) below grade. A three-ply cotton fabric waterproofing was applied over the foundation and steel tank. Four coats of primer paint were sprayed on all exposed interior tank surfaces. The tank ceiling dome was covered with three applications of magnesium zincfluorosilicate wash. Lead flashing was used to protect the joint where the steel liner met the concrete dome. Asbestos gaskets were used to seal the manholes in the tank dome. The tank was waterproofed on the sides and top with tar and gunnite. Tank capacity is 2,017,405 liters (533,000 gallons). The tank was covered with approximately 2.2 meters (7.25 feet) of overburden for shielding purposes. At present, the tank farm is enclosed by a 1.8 meters (6-foot) high chain link fence. The tanks are marked by yellow riser pipes and the ground surface is covered with gravel.

Location: Tank 241-B-111 is located on the north side of the 200 East Area about 914 meters (3,000 feet) north northeast of the 221-B building.

Release Description: A leak of 8,000 gallons (30,280 L) occurred prior to or during 1978. The leak estimate of 30,280 liters (8,000 gallons) is an average total from 19 tanks. Tank B-111 was categorized "questionable integrity" due to the unexplained activity in Dry Wells 20-11-09 and 20-12-06.

Waste Type: Storage Tank

Waste Description: 241-B-111 tank received bismuth phosphate first-cycle waste; bismuth phosphate second-cycle wastes; ion exchange waste (waste fractionization); fission product waste; B Plant waste from cells 5 and 6; evaporator bottoms; non-complexed waste; decontamination waste; PUREX high-level waste; cesium recovery waste; and waste water. The waste material is classified as non-complexed and presently has a total waste volume of 237,000 gallons (897,045 L) comprised of sludge. There is 60,560 liters (16,000 gallons) of pumpable liquid and 83,270 liters (22,000 gallons) of drainable liquid remaining. The volume of waste converts to approximately 2.2 meters (7 feet) in the tank. More sample material is needed for full characterization of tank waste.

Code: 241-B-112	Classification: Accepted
Names: 241-B-112; 241-B-TK-112	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1946
Status: Inactive	End Date: 1/1/1977

Description: The single-shell tank is constructed of 1 foot (.3 m) thick reinforced concrete with a 0.25 inch (6.4 mm) mild carbon steel liner (ASTM A 283 Grade C) on the bottom and sides and a 1.25 foot (.38 m) thick domed concrete top. The top of the steel liner is 18 feet (5.5 m) above the bottom of the tank (at the side wall). The tank has a dished bottom with a maximum depth of 12 inches (30 cm) below the side wall of the tank and a 4 foot (1.2 m) radius knuckle. The tank has a 17 foot (5.2 m) operating depth. The tank is set on a reinforced concrete foundation 37 feet (11.3 m) below grade. A three-ply cotton fabric waterproofing was applied over the foundation and steel tank. Four coats of primer paint were sprayed on all exposed interior tank surfaces. The tank ceiling dome was covered with three applications of magnesium zincfluorosilicate wash. Lead flashing was used to protect the joint where the steel liner met the concrete dome. Asbestos gaskets were used to seal the manholes in the tank dome. The tank was waterproofed on the sides and top with tar and gunnite. Tank capacity is 533,000 gallons (2,017,405 L). The tank was covered with approximately 7.25 feet (2.2 m) of overburden for shielding purposes. At present, the tank farm is enclosed by a 6-foot (1.8 m) high chain link fence. The tanks are marked by yellow riser pipes and the ground surface is covered with gravel.

Location: Tank 241-B-112 is located on the north side of the 200 East Area about 3,000 feet (914 m) north northeast of the 221-B building.

Release Description: A leak of 2,000 gallons (7,570 L) occurred prior to or during 1978. Tank B-112 was categorized "questionable integrity" due to the unexplained activity in Dry Wells 20-12-03 and 20-12-06.

Waste Type: Storage Tank

Waste Description: 241-B-112 tank received bismuth phosphate second-cycle wastes; B Plant low-level waste; fission product waste; ion exchange waste; evaporator bottoms from the 241-B and -BX tanks; non-complexed waste; first cycle waste; decontamination waste; and waste water. The waste material is classified as non-complexed and presently has a total waste volume of 33,000 gallons (124,905 L) comprised of 30,000 gallons (113,550 L) sludge and 3,000 gallons (11,355 L) of drainable supernatant liquid. Another source indicates that the 30,000 gallons (11,355 L) of sludge is composed of 14,000 gallons (52,990 L) of sludge and 16,000 gallons (60,560 L) of salt cake. The volume of waste converts to approximately 1 foot (.3 m) in the tank. Based on analytical results from the 1995 Auger sampling event, the waste in the tank does not appear to present any immediate safety concerns.

Code: 241-B-151	Classification: Accepted
------------------------	---------------------------------

Names: 241-B-151; 241-B-151 Diversion Box**Reclassification** None**Type:** Diversion Box**Start Date:** 1/1/1945**Status:** Inactive**End Date:** 1/1/1984**Description:** 241-B-151 Diversion Box is an underground structure constructed of reinforced concrete with a height of approximately 15 feet (4.6 m). Only an approximate 1 foot (.3 m) of this diversion box appears above grade. The outer dimensions are approximately 20 feet (6.1 m) by 9 feet (2.7 m). Wall thickness ranges from about 2 feet (.61 m) for the lower half to a three step progressively thinner thickness to accommodate the three layers of tapered concrete blocks that make up the cover. The cover is made up in sections consisting of fifteen pre-formed concrete blocks. The layers of concrete blocks are arranged in three stacked rows, the bottom row having the shortest length and the top row having the longest length. The tapered ends aid in locating the blocks into place and each block overlaps with the one above and/or below it. Each block is about 20 inches (51 cm) high and range in length from around 6.8 to 8 feet (2 to 2.4 m).**Location:** 241-B-151 Diversion Box is located inside 241-B Tank Farm, approximately 66.6 meters (219 feet) south of tank 241-B-110.**Release** UPR-200-E-4, UPR-200-E-73.**Description:****Related Sites/ Structures:** 241-B-151 Diversion Box is associated with the 241-B-152, 241-B-153 diversion boxes, 241-B Tank Farm, 241-BX Tank Farm and the 241-B-301B catch tank.**Process Description:** 241-B-151 Diversion Box transferred waste solutions from processing and decontamination operations to the 241-B and 241-BX Tank Farms.**Waste Type:** Process Effluent**Waste Description:** This unit was used for transfer of liquid waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operation. It is estimated that approximately 50 pounds (23 kilograms) of waste lead is also stored in each diversion box.

Code: 241-B-152**Classification:** Accepted**Names:** 241-B-152; 241-B-152 Diversion Box**Reclassification** None**Type:** Diversion Box**Start Date:** 1/1/1945**Status:** Inactive**End Date:** 1/1/1984**Description:** 241-B-152 Diversion Box is an underground structure constructed of reinforced concrete with a height of approximately 4.6 meters (15 feet). Approximate 0.3 meters (1 foot) is above grade. The outer dimensions are approximately 8.5 meters (28 feet) by 2.7 meters (9 feet). Wall thickness is progressively thinner to accommodate for three layers of tapered concrete cover blocks. The layers of concrete blocks are arranged in three stacked rows, the bottom row having the shortest length and the top row having the longest length.**Location:** The 241-B-152 Diversion Box is located inside the 241-B Tank Farm, approximately 61 meters (200 feet) southwest of tank 241-B-110.**Release** UPR-200-E-74 and UPR-200-E-38 occurred at this diversion box.**Description:****Related Sites/ Structures:** 241-B-152 Diversion Box is associated with the 241-B Tank Farm, 241-E-216-PL, 241-B-151, 241-B-153, 241-B-154, 241-B-252, 241-BX-153, and 241-BX-155 diversion boxes and the 241-B-301 Catch Tank.

Process Description: 241-B-152 Diversion Box transferred waste solutions from processing and decontamination operations to the 241-B and 241-BX Tank Farms.

Waste Type: Process Effluent

Waste Description: This unit was used for transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operation. It is estimated that approximately 50 pounds (23 kilograms) of waste lead is stored in each diversion box.

Code: 241-B-153 **Classification:** Accepted

Names: 241-B-153; 241-B-153 Diversion Box **Reclassification:** None

Type: Diversion Box **Start Date:** 1/1/1945

Status: Inactive **End Date:** 1/1/1984

Description: The 241-B-153 Diversion Box is an underground structure constructed of reinforced concrete with a height of approximately 10.4 meters (34 feet). Approximate 0.3 meters (1 foot) is above grade. The outer dimensions are approximately 10.4 meters (34 feet) by 2.7 meters (9 feet). The wall thickness gets progressively thinner to accommodate three layers of tapered concrete cover blocks. The layers of concrete blocks are arranged in three stacked rows.

Location: The 241-B-153 Diversion Box is located inside the 241-B Tank Farm, approximately 23.8 meters (78 feet) south of tank 241-B-110.

Release Description: UPR-200-E-6, UPR-200-E-75 and UPR-200-E-76 are associated with this site.

Related Sites/Structures: 241-B-153 Diversion Box is associated with the 241-B Tank Farm, 241-B-151 and 241-B-152 diversion boxes and the 241-B-301 Catch Tank.

Process Description: The 241-B-153 Diversion Box transferred waste solutions from processing and decontamination operations to the 241-B and 241-BX Tank Farms.

Waste Type: Process Effluent

Waste Description: This unit was used for transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operation. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Code: 241-B-201 **Classification:** Accepted

Names: 241-B-201; 241-B-TK-201 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1946

Status: Inactive **End Date:** 1/1/1948

Description: The tanks are marked by yellow riser pipes and the ground surface is covered with gravel. The single-shell tank is constructed of reinforced concrete with a 6.4 millimeter (0.25 inch) steel liner on the bottom and sides and a 0.48 meters (1.58 foot) thick domed concrete top. The tank has a 6.1 meters (20 foot) diameter and a 7.5 meter (24.9 foot) operating depth. The tank is set on a concrete foundation 11.5 meters (37.9 feet) below grade. Tank capacity is 208,175 liters (55,000 gallons). The tank was covered with approximately 3.3 meters (11 feet) of overburden for shielding purposes. At present, the tank farm is enclosed by a 1.8 meters (6-foot) high chain link fence.

Location: Tank 241-B-201 is located on the north side of the 241-B Tank Farm, inside the tank farm

fence.

Related Sites/ Structures: The tank is associated with the 216-B-7A and 7B cribs.

Process Description: The smaller 241-B-201, 202, 203 and 204 tanks operated independently from the large capacity cascading tanks in 241-B Tank Farm. The tank overflow cascaded to the 216-B-7A crib. In 1946, it was determined that discharging 224-B waste into the 216-B-5 reverse well was a mistake. The waste stream was rerouted to the 241-B-201 tank in 1946. 224-B waste had an average plutonium concentration of 99 micrograms per liter and an average beta concentration of 26 microcuries per liter. 221-B 5-6 tank waste was temporarily combined with the 224-B waste in 1947. 241-B-201 was removed from service in 1948 when it filled with sludge. The influent line was redirected to the 241-B-204 tank and the 241-B-202, 203 and 204 tanks were tied together in a cascade series (with 241-B-202 the last tank in the cascade). Some references indicate the tank was reactivated in 1952 for Uranium Recovery waste that originated in 221-U Plant.

Waste Type: Storage Tank

Waste Description: 224-B building wastes and 221-B metal waste, non-complexed waste, and waste water. The waste material is classified as non-complexed and presently has a total waste volume of 109,765 liters (9,000 gallons) comprised of 105,980 liter (28,000 gallons) sludge, 3,785 liters (1,000 gallons) of supernatant, 15,140 liters(4,000 gallons) drainable liquid, and no pumpable liquid remaining. The volume of waste, in 1996, converts to approximately 3.8 meters (12.5 feet) depth in the tank.

Code: 241-B-202	Classification: Accepted
Names: 241-B-202; 241-B-TK-202	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1951
Status: Inactive	End Date: 1/1/1977

Description: The single-shell tank is the smallest of the tank farm designs with a 6.1 meter (20 foot) diameter, a 7.5 meter (24.9 foot) operating depth, and a 208,175 liters (55,000 gallon) capacity. The tank is constructed of reinforced concrete with a 6.4 millimeter (0.25 inch) steel liner on the bottom and sides and a 0.48 meter (1.58 foot) thick domed concrete top. The tank is set on a concrete foundation 11.5 meters (37.9 feet) below grade. The tank was covered with approximately 3.3 meters (11 feet) of overburden for shielding purposes. At present, the tank farm is enclosed by a 1.8 meters (6-foot) high chain link fence. The tanks are marked by yellow riser pipes and the ground surface is covered with gravel.

Location: Tank 241-B-202 is located on the north side of the 200 East Area about 914 meters (3,000 feet) north northeast of the 221-B building.

Waste Type: Storage Tank

Waste Description: Wastes consist of : 224 building wastes (lanthanum fluoride), metal waste, non-complexed waste, and B Plant high-level waste. The waste material is classified as non-complexed and presently has a total waste volume of 102,195 liters (27,000 gallons) comprised of 102,195 liters (27,000 gallons) sludge. There is 11,355 liters (3,000 gallons) of drainable liquid remaining. The volume of waste converts to approximately 3.7 meters (12 feet) depth in the tank.

Code: 241-B-203	Classification: Accepted
------------------------	---------------------------------

Names: 241-B-203; 241-B-TK-203	Reclassification None
Type: Single-Shell Tank	Start Date: 1/1/1951
Status: Inactive	End Date: 1/1/1977

Description: The single-shell tank is the smallest of the tank farm designs with a 20 foot (6.1 m) diameter, a 24.9 foot (7.5 m) operating depth, and a 55,000 gallon (208,175 L) capacity. The tank is constructed of reinforced concrete with a 0.25 inch (6.4 mm) steel liner on the bottom and sides and a 1.58 foot (.48 m) thick domed concrete top. The tank is set on a concrete foundation 37.9 feet (11.5 m) below grade. The tank was covered with approximately 11 feet (3.3 m) of overburden for shielding purposes. At present, the tank farm is enclosed by a 6-foot (1.8 m) high chain link fence. The tanks are marked by yellow riser pipes and the ground surface is covered with gravel.

Location: Tank 241-B-203 is located on the north side of the 200 East Area about 3,000 feet (914 m) north northeast of the 221-B building.

Release Description: Between 1951 and 1977, unplanned release (UPR) occurred when about 300 gallons (1,136 L) of lanthanum fluoride escaped from tank 241-B-203 and contaminated the soil surrounding and beneath the tank. This UPR is recorded as UPR-200-E-130. The leak volume estimate is based solely on observed liquid level decreases in this tank and is considered to be the most accurate method for estimating leak volumes. Operating Limit Deviation Report (OLDR) No. 82-08 was issued in May 1982 because the liquid level exceeded the decrease criterion. Environmental Protection Deviation Report 83-02 was issued in November 1983 because of evidence of liquid level decreases, settling of solids around the tank perimeter, and liner corrosion.

Waste Type: Storage Tank

Waste Description: Wastes consist of : 224 building wastes (lanthanum fluoride), metal waste, and non-complexed waste. The waste material is classified as non-complexed and presently has a total waste volume of 51,000 gallons (193,035 L) comprised of 50,000 gallons (189,250 L) sludge. There is 6,000 gallons (22,710 L) of drainable liquid remaining. The volume of waste converts to approximately just over 21 feet (6.4 m) depth in the tank.

Code: 241-B-204	Classification: Accepted
Names: 241-B-204; 241-B-TK-204	Reclassification None
Type: Single-Shell Tank	Start Date: 1/1/1951
Status: Inactive	End Date: 1/1/1977

Description: The single-shell tank is the smallest of the tank farm designs with a 6.1 meters (20 foot) diameter, a 7.5 meters (24.9 foot) operating depth, and a 208,175 liters (55,000 gallon) capacity. The tank is constructed of reinforced concrete with a 6.4 millimeter (0.25 inch) steel liner on the bottom and sides and a 0.48 meters (1.58 foot) thick domed concrete top. The tank is set on a concrete foundation 11.5 meters (37.9 feet) below grade. The tank was covered with approximately 3.3 meters (11 feet) of overburden for shielding purposes. At present, the tank farm is enclosed by a 1.8 meter (6-foot) high chain link fence. The tanks are marked by yellow riser pipes and the ground surface is covered with gravel.

Location: Tank 241-B-204 is located on the north side of the 200 East Area about 914 meters (3,000 feet) north northeast of the 221-B building.

Release Description: Approximately 1,514 liters (400 gallons) leaked from tank 241-B-204 before or during 1984. The leak volume estimate is based solely on observed liquid level decreases in this tank and is considered to be the most accurate method for estimating leak volumes. Environmental Protection Deviation Report 83-02 was issued in November 1983 because of evidence of liquid

level decreases, settling of solids around the tank perimeter, and liner corrosion.

Waste Type: Storage Tank

Waste Description: Wastes consist of: 224 building wastes (lanthanum fluoride), metal waste, B Plant flushes, and non-complexed waste. The waste material is classified as non-complexed and presently has a total waste volume of 189,250 liters (50,000 gallons) comprised of 185,465 liters (49,000 gallons) sludge. There is 22,710 liters (6,000 gallons) of drainable liquid remaining. The volume of waste converts to approximately 6.4 meters (21 feet) depth in the tank. Reported Date: May 31, 1996

Code: 241-B-252

Classification: Accepted

Names: 241-B-252; 241-B-252 Diversion Box

Reclassification: None

Type: Diversion Box

Start Date: 1/1/1945

Status: Inactive

End Date: 1/1/1984

Description: The site is a 0.6 meter (2 foot) thick, reinforced concrete structure, 4.6 meters (15 feet) deep. The outer dimensions are 11 meters (36 feet) long by 2.7 meters (9 feet) wide. There are twenty four 7.6 centimeter (three inch) Hanford type nozzles housed inside. The top of the box is a concrete cover block which usually extends a few inches above grade.

Location: Diversion Box 241-B-252 is located in the northwest corner of the 241-B Tank Farm, east of Baltimore Avenue.

Related Sites/Structures: Diversion Box 241-B-252 interconnects with the following: The 241-B and 241-BY Tank Farms, 241-B-151, 241-B-152, and 241-BX-154 Diversion Boxes, 109-BY Valve Pit, and 241-B-301 Catch Tank.

Waste Type: Process Effluent

Waste Description: This unit was used for transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operation. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Code: 241-B-301

Classification: Accepted

Names: 241-B-301; 241-B-301B; 241-B-301-B Catch Tank; Drain Lines V238 and V312

Reclassification: None

Type: Catch Tank

Start Date: 1/1/1945

Status: Inactive

End Date: 1/1/1984

Description: The site is an underground tank, located within the 241-B Tank Farm chin link fence. The tank is surrounded by a steel chain and marked with radiological and IMUST signs. Four yellow risers are visible at the surface.

Location: The 241-B-301 Catch Tank is located on the west side of the 241-B Tank Farm, inside the tank farm fence. It is south of 12th Street and west of Baltimore Ave.

Related Sites/Structures: The 241-B-301 Catch Tank is connected to the 241-B-151, 241-B-152, 241-B-153, 241-B-154, 241-B-252, 242-B-151 diversion boxes in the 241-B Tank Farm. Lines V312, V238 and V238 are the drain lines from the diversion boxes.

Process Description: The 241-B-301 Catch Tank was designed to collect waste leaks from the 241-B diversion boxes that occurred during transfers.

Waste Type: Process Effluent

Waste Description: 1993, the tank was estimated to contain 2230 liters (590 gallons) of supernate and 81648 liters (21,600 gallons) of sludge. Analytical data for tank liquid show moderately basic pH with extremely low levels of fissile materials. Cesium levels are also very low. The radionuclide analyses have been adjusted for 17.4 year radioactive decay (October 1974 to April 1992). From preliminary observations, supernate in this tank would not be In designated as dangerous waste or prove a criticality hazard.

Code: 242-B-151 **Classification:** Accepted

Names: 242-B-151; 242-B Evaporator Building Diversion Box **Reclassification:** None

Type: Diversion Box **Start Date:** 1/1/1945

Status: Inactive **End Date:** 1/1/1984

Description: Diversion Box 242-B-151 is constructed of reinforced concrete with a height of approximately 4 meters (13 feet). Approximate 0.3 meters (1 foot) of the diversion box concrete cover appears above grade. The outer dimensions are approximately 3.7 meters (12 feet) by 2.4 meters (8 feet). The structure's cover is in sections consisting of three interlocking pre-formed concrete blocks.

Location: Diversion Box 242-B-151 is located inside the 241-B Tank Farm. It is northwest of the 242-B Evaporator building and approximately 16.2 meters (53 feet) south of tanks 241-B-104 and 241-B-107.

Related Sites/Structures: Diversion Box 242-B-151 connects with the 242-B Evaporator to the 241-B Tank Farm.

Process Description: Diversion boxes and receiving vaults drain to catch tanks or single-shell tanks.

Waste Type: Process Effluent

Waste Description: This unit was used for transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operation. This unit received byproduct cake solution and waste solution from the first decontamination waste cycle from 242-B. This contained ~10% of original fission product, 1% Plutonium, and the remainder of miscellaneous chemicals. The major chemical component was bismuth phosphate. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Code: 241-BR-152 **Classification:** Accepted

Names: 241-BR-152; 241-BR-152 Diversion Box **Reclassification:** None

Type: Diversion Box **Start Date:** 1/1/1948

Status: Inactive **End Date:** 1/1/1984

Description: Tank Farm drawings show 241-BR-152 is co-located in a series of three diversion boxes that are joined together. 241-BXR-152 is the center diversion box. 241-BR-152 Diversion Box is on the eastern end and 241-BYR-152 is the most western of the diversion boxes in this group. They are located south of the 241-B-101 tank.

Location: Diversion Box 241-BR-152 is located in the southeastern portion of the 241-BY Tank Farm, inside the tank farm fence.

Related Sites/ Structures:	Diversion Box 241-BR-152 interconnects with the following: 241-BXR-151 Diversion Box, the 241-B Tank Farm, and building 242-B (242-B Evaporator). The transfer line to 241-B Tank Farm is discussed in sitecode 200-E-197-PL.
Process Description:	Diversion boxes and receiving vaults drain to catch tanks or single-shell tanks. Diversion Box 241-BR-152 is constructed of reinforced concrete with walls approximately 3.7 meters (12 feet) high and ranging from 0.3-0.6 m (1-2 feet) thick. The outer dimensions are approximately 12.2 meters (40 feet) by 11 meters (36 feet). The concrete cover is about 0.3 meters (1 foot) above grade and is made up in sections consisting of thirty interlocking pre-formed concrete blocks. The concrete blocks range in thickness from 0.37 meters (1.2 feet) to 0.82 meters (2.7 feet) and are equipped with lifting bails made from approximate 3.43 centimeters (1.35 inch) diameter steel bar. Cranes were used to lift the blocks. The blocks were sealed with a combination of hot sealing compound and a flexcell bituminous fiber expansion joint.
Waste Type:	Process Effluent
Waste Description:	This unit was used for transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operation. It is estimated that approximately 50 pounds (23 kilograms) of lead shielding may stored in each diversion box.

Code:	241-BX-101	Classification:	Accepted
Names:	241-BX-101; 241-BX-TK-101	Reclassification	None
Type:	Single-Shell Tank	Start Date:	1/1/1948
Status:	Inactive	End Date:	1/1/1975

Description:	The 22.9 meter (75 foot) diameter single-shell tank is constructed of 0.3 meters (1 foot) thick reinforced concrete with a 1 centimeter (0.375 inch) mild carbon steel liner (ASTM A 283 Grade C) on the bottom and sides and a 0.38 m (1.25 foot) thick domed concrete top. The top of the steel liner is 5.5 meters (18 feet) above the bottom of the tank (at the side wall). The tank has a dished bottom, with a maximum depth of 30 centimeter (12 inches) below the side wall of the tank and a 1.2 meter (4 foot) radius knuckle. The tank has a 16 foot 4.9 meters (4 foot) operating depth. The tank is set on a reinforced concrete foundation about 11.3 meters (37 feet) below grade. A three-ply cotton fabric waterproofing was applied over the foundation and steel tank. Four coats of primer paint were sprayed on all exposed interior tank surfaces. The tank ceiling dome was covered with three applications of magnesium zincfluorosilicate wash. Lead flashing was used to protect the joint where the steel liner met the concrete dome. Asbestos gaskets were used to seal the manholes in the tank dome. The tank was waterproofed on the sides and top with tar and gunnite. Tank capacity is 2,017,405 liters (533,000 gallons). The tank was covered with approximately 2.2 meters (7.25 feet) of overburden for shielding purposes. At present, the tank farm is surrounded by a chain link fence, topped with three strands of barbed wire. The ground surface is covered with gravel and no vegetation is seen.
Location:	Tank 241-BX-101 is located on the north side of the 200 East Area about 850 meters (2,800 feet) north of the 221-B (B Plant) building.
Release Description:	A leak of 30,280 liters (8,000 gallons) occurred prior to or during 1972. The leak volume estimate is an average of approximately 30,280 liters (8,000 gallons) for 19 tanks.
Waste Type:	Storage Tank
Waste Description:	241-B-101 tank received bismuth phosphate metal waste; evaporator bottoms; B Plant low-level waste, ion exchange waste (waste fractionization), and supernatant containing B Plant low-level waste; PUREX organic wash waste, cladding waste, coating waste, #1 acid and concentrator waste, ion exchange waste; REDOX ion exchange waste from 241-BY, -BX, -B, and -C tanks; tributyl phosphate waste; inorganic wash waste; coating waste; uranium recovery

waste; complex waste; double-shell slurry feed; evaporator feed; organic wash waste; metal waste; non-complexed waste; waste water; in-tank solidification saltcake; cesium recovery waste. The unit received an inadvertent transfer of ~6,813 liters (1,800 gallons) of ARC-359 organic ion exchange resin in early 1972. The waste material is classified as non-complexed and presently has a total waste volume of 162,755 liters (43,000 gallons) comprised of 158,970 liters (42,000 gallons) sludge and 3,785 liters (1,000 gallons) of drainable supernatant liquid. The volume of waste converts to approximately 0.3 meters (1 foot) in the tank.

Code: 241-BX-102	Classification: Accepted
Names: 241-BX-102; 241-BX-TK-102	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1948
Status: Inactive	End Date: 1/1/1971

Description: The 22.9 meter (75 foot) diameter single-shell tank is constructed of 0.3 meters (1 foot) thick reinforced concrete with a 1 centimeter (0.375 inch) mild carbon steel liner (ASTM A 283 Grade C) on the bottom and sides and a 0.38 m (1.25 foot) thick domed concrete top. The top of the steel liner is 5.5 meters (18 feet) above the bottom of the tank (at the side wall). The tank has a dished bottom, with a maximum depth of 30 centimeters (12 inches) below the side wall of the tank and a 1.2 meters (4 foot) radius knuckle. The tank has a 4.9 meters (16 foot) operating depth. The tank is set on a reinforced concrete foundation about 11.3 meters (37 feet) below grade. A three-ply cotton fabric waterproofing was applied over the foundation and steel tank. Four coats of primer paint were sprayed on all exposed interior tank surfaces. The tank ceiling dome was covered with three applications of magnesium zincfluorosilicate wash. Lead flashing was used to protect the joint where the steel liner met the concrete dome. Asbestos gaskets were used to seal the manholes in the tank dome. The tank was waterproofed on the sides and top with tar and gunnite. Tank capacity is 2,017,405 liters (533,000 gallons). The tank was covered with approximately 2.2 meters (7.25 feet) of overburden for shielding purposes. At present, the tank farm is surrounded by a chain link fence, topped with three strands of barbed wire. The ground surface is covered with gravel and no vegetation is seen.

Location: Tank 241-BX-102 is located on the north side of the 200 East Area about 850 meters (2,800 feet) north of the 221-B (B Plant) building, directly west of the 241-B Tank Farm.

Release Description: The 241-BX-102 tank was overfilled in 1951, causing a large volume of liquid waste to overflow into the soil column. It was estimated that 348,000 liters (91,600 gallons) of tank waste was lost in the 1951 event. Assuming the metal waste stream contained 0.5 pounds of uranium per gallon of liquid waste, approximately 22.5 tons of uranium was released to the soil. A 1971 report identified 264,950 liters (70,000 gallons) was released from this tank prior to or during 1971. Some or all of the found in 1971 can be attributed to the 1951 overflow event.

Waste Type: Storage Tank

Waste Description: 241-BX-102 tank received bismuth phosphate metal waste; diatomaceous earth; supernatant containing tributyl phosphate waste; metal waste; PUREX coating waste; B Plant low level waste; evaporator bottoms from 241-BX, -BY, -B, and -C tanks; organic wash waste; metal waste; non-complexed waste. The waste material is classified as non-complexed and presently has a total waste volume of 363,360 liters (96,000 gallons) comprised of 147,615 liters (39,000 gallons) of unknown waste; 64,345 liters (17,000 gallons) of diatomaceous earth; 151,400 liters (40,000 gallons) of sludge; no pumpable liquid remaining, and 15,140 liters (4,000 gallons) of drainable supernatant liquid. The volume of waste converts to approximately 0.8 meters (2.5 feet) in the tank.

Code: 241-BX-103	Classification: Accepted
Names: 241-BX-103; 241-BX-TK-103	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1948
Status: Inactive	End Date: 1/1/1977

Description: The 22.9 meters (75 foot) diameter single-shell tank is constructed of 0.3 meters (1 foot) thick reinforced concrete with a 1 centimeter (0.375 inch) mild carbon steel liner (ASTM A 283 Grade C) on the bottom and sides and a 0.38 meter (1.25 foot) thick domed concrete top. The top of the steel liner is 5.5 meters (18 feet) above the bottom of the tank (at the side wall). The tank has a dished bottom, with a maximum depth of 30 centimeters (12 inches) below the side wall of the tank and at 1.2 meters (4 foot) radius knuckle. The tank has a 4.9 meters (16 foot) operating depth. The tank is set on a reinforced concrete foundation about 11.3 meters (37 feet) below grade. A three-ply cotton fabric waterproofing was applied over the foundation and steel tank. Four coats of primer paint were sprayed on all exposed interior tank surfaces. The tank ceiling dome was covered with three applications of magnesium zincfluorosilicate wash. Lead flashing was used to protect the joint where the steel liner met the concrete dome. Asbestos gaskets were used to seal the manholes in the tank dome. The tank was waterproofed on the sides and top with tar and gunnite. Tank capacity is 2,017,405 liters (533,000 gallons). The tank was covered with approximately 2.2 meters (7.25 feet) of overburden for shielding purposes. At present, the tank farm is surrounded by a chain link fence, topped with three strands of barbed wire. The ground surface is covered with gravel and no vegetation is seen.

Location: Tank 241-BX-103 is located on the north side of the 200 East Area about 850 meters (2,800 feet) north of the 221-B (B Plant) building, directly west of the 241-B Tank Farm.

Release Description: The contaminated soil in the vicinity of dry wells 21-03-03, 21-03-05, and 21-03-12 is believed to have been caused by tank overflow and spillage a number of years ago. 113,550 to 340,650 liters (30,000 to 90,000 gallons) of waste spilled on the ground between tank BX-102 and BX-103 in 1951.

Waste Type: Storage Tank

Waste Description: 241-BX-103 tank received bismuth phosphate metal waste; supernatant containing metal waste; tributyl phosphate waste; PUREX coating waste, #1 acid concentrator waste, ion exchange waste, low and high-level waste, and sludge supernatant wastes; organic wash waste; decontamination waste; PNL waste; N Reactor waste; laboratory waste; evaporator feed, evaporator bottoms; REDOX ion exchange waste; non-complexed waste; waste water; B Plant low-level waste from 241-B, -BX, -BY, -C tanks, BXR-002 diversion box, and ER-311 catch tank. The waste material is classified as non-complexed and presently has a total waste volume of 257,380 liters (68,000 gallons) comprised of 234,670 liters (62,000 gallons) of sludge and 22,710 liters (6,000 gallons) of drainable supernatant liquid. There is no pumpable liquid remaining. The volume of waste converts to approximately 0.5 meters (1.7 feet) in the tank.

Code: 241-BX-104	Classification: Accepted
Names: 241-BX-104; 241-BX-TK-104	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1949
Status: Inactive	End Date: 1/1/1980

Description: The 22.9 meters (75 foot) diameter single-shell tank is constructed of 0.3 meters (1 foot) thick reinforced concrete with a 1 centimeter (0.375 inch) mild carbon steel liner (ASTM A 283 Grade C) on the bottom and sides and a 0.38 meters (1.25 foot) thick domed concrete top. The top of the steel liner is 5.5 meters (18 feet) above the bottom of the tank (at the side wall). The tank has a dished bottom, with a maximum depth of 30 centimeters (12 inches) below the side

wall of the tank and a 1.2 meters (4 foot) radius knuckle. The tank has a 4.9 meters (16 foot) operating depth. The tank is set on a reinforced concrete foundation about 11.3 meters (37 feet) below grade. A three-ply cotton fabric waterproofing was applied over the foundation and steel tank. Four coats of primer paint were sprayed on all exposed interior tank surfaces. The tank ceiling dome was covered with three applications of magnesium zincfluorosilicate wash. Lead flashing was used to protect the joint where the steel liner met the concrete dome. Asbestos gaskets were used to seal the manholes in the tank dome. The tank was waterproofed on the sides and top with tar and gunnite. Tank capacity is 2,017,405 liters (533,000 gallons). The tank was covered with approximately 2.2 meters (7.25 feet) of overburden for shielding purposes. At present, the tank farm is surrounded by a chain link fence, topped with three strands of barbed wire. The ground surface is covered with gravel and no vegetation is seen.

Location: Tank 241-BX-104 is located on the north side of the 200 East Area about 850 meters (2,800 feet) north of the 221-B (B Plant) building, directly west of the 241-B Tank Farm.

Waste Type: Storage Tank

Waste Description: 241-BX-104 tank received bismuth phosphate metal waste; PUREX coating waste, cladding waste; ion exchange waste (waste fractionization); evaporator bottoms; supernatant containing REDOX high-level waste; complexed and non-complexed waste; double-shell slurry feed; tributyl phosphate waste; water and waste water; cesium recovery waste; in-tank solidification saltcake; B Plant low-level waste, and ion exchange waste from 241-B, -BX, -BY, -C, and -SY tanks, and ER-302-C and ER-311 catch tanks. The waste material is classified as non-complexed and presently has a total waste volume of 374,715 liters (99,000 gallons) comprised of 363,360 liters (96,000 gallons) of sludge and 124,905 liters (33,000 gallons) of drainable supernatant liquid and 102,195 liters (27,000 gallons) of pumpable liquid remaining. The volume of waste converts to approximately 0.8 meters (2.6 feet) in the tank.

Code: 241-BX-105	Classification: Accepted
Names: 241-BX-105; 241-BX-TK-105	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1949
Status: Inactive	End Date: 1/1/1980

Description: The 22.9 meters (75 foot) diameter single-shell tank is constructed of 0.3 meters (1 foot) thick reinforced concrete with a 1 centimeter (0.375 inch) mild carbon steel liner (ASTM A 283 Grade C) on the bottom and sides and a 0.38 meters (1.25 foot) thick domed concrete top. The top of the steel liner is 5.5 meters (18 feet) above the bottom of the tank (at the side wall). The tank has a dished bottom, with a maximum depth of 30 centimeters (12 inches) below the side wall of the tank and a 1.2 meters (4 foot) radius knuckle. The tank has a 4.9 meters (16 foot) operating depth. The tank is set on a reinforced concrete foundation about 11.3 meters (37 feet) below grade. A three-ply cotton fabric waterproofing was applied over the foundation and steel tank. Four coats of primer paint were sprayed on all exposed interior tank surfaces. The tank ceiling dome was covered with three applications of magnesium zincfluorosilicate wash. Lead flashing was used to protect the joint where the steel liner met the concrete dome. Asbestos gaskets were used to seal the manholes in the tank dome. The tank was waterproofed on the sides and top with tar and gunnite. Tank capacity is 2,017,405 liters (533,000 gallons). The tank was covered with approximately 2.2 meters (7.25 feet) of overburden for shielding purposes. At present, the tank farm is surrounded by a chain link fence, topped with three strands of barbed wire. The ground surface is covered with gravel and no vegetation is seen.

Location: Tank 241-BX-105 is located on the north side of the 200 East Area about 850 meters (2,800 feet) north of the 221-B (B Plant) building, directly west of the 241-B Tank Farm.

Waste Type: Storage Tank

Waste Description: 241-BX-105 tank received bismuth phosphate metal waste; PUREX coating waste; ion exchange waste; evaporator bottoms; supernatant containing metal waste; uranium recovery waste; B Plant low-level waste; concentrated reduction and oxidation (REDOX) waste; complexed and non-complexed waste; double-shell slurry feed from 241-BX, -BY, -C, -S, and -SX tanks; tributyl phosphate waste; evaporator feed; waste water. The waste material is classified as non-complexed and presently has a total waste volume of 193,035 liters (51,000 gallons) comprised of 162,755 liters (43,000 gallons) of sludge; 11,355 liters (3,000 gallons) of saltcake; 18,925 liters (5,000 gallons) of supernatant liquid. There remains 41,635 liters (11,000 gallons) drainable liquid and 15,140 liters (4,000 gallons) of pumpable liquid remaining. The volume of waste converts to approximately 0.3 meters (1 foot) in the tank (WHC-EP-0182-98). It should be noted that recent FIC gauge level readings taken from riser 1 of the tank indicate a waste depth of 24.8 inches (0.6 m). Core samples recovered from risers 1 and 8 seem to confirm the waste depth and volume indicated by the FIC gauge (WHC-SD-WM-ER-406, Rev. 0B).

Code: 241-BX-106	Classification: Accepted
Names: 241-BX-106; 241-BX-TK-106	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1949
Status: Inactive	End Date: 1/1/1977

Description: The 22.9 m (75 foot) diameter single-shell tank is constructed of 0.3 meter (1 foot) thick reinforced concrete with a 1 centimeter (0.375 inch) mild carbon steel liner (ASTM A 283 Grade C) on the bottom and sides and a 0.38 meter (1.25 foot) thick domed concrete top. The top of the steel liner is 5.5 meter (18 feet) above the bottom of the tank (at the side wall). The tank has a dished bottom, with a maximum depth of 30 centimeter (12 inches) below the side wall of the tank and a (1.2 m) radius knuckle. The tank has a 16 foot 4.9 meters (4 foot) operating depth. The tank is set on a reinforced concrete foundation about 11.3 meters (37 feet) below grade. A three-ply cotton fabric waterproofing was applied over the foundation and steel tank. Four coats of primer paint were sprayed on all exposed interior tank surfaces. The tank ceiling dome was covered with three applications of magnesium zincfluorosilicate wash. Lead flashing was used to protect the joint where the steel liner met the concrete dome. Asbestos gaskets were used to seal the manholes in the tank dome. The tank was waterproofed on the sides and top with tar and gunnite. Tank capacity is 2,017,405 liters (533,000 gallons). The tank was covered with approximately 2.2 meters (7.25 feet) of overburden for shielding purposes. At present, the tank farm is surrounded by a chain link fence, topped with three strands of barbed wire. The ground surface is covered with gravel and no vegetation is seen.

Location: Tank 241-BX-106 is located on the north side of the 200 East Area about 850 meters (2,800 feet) north of the 221-B (B Plant) building, directly west of the 241-B Tank Farm.

Waste Type: Storage Tank

Waste Description: 241-BX-106 tank received bismuth phosphate metal waste; PUREX coating waste, ion exchange waste; evaporator bottoms; supernatant containing metal waste; B Plant low-level waste; REDOX ion exchange waste from 241-B, -BX, and -BY tanks; organic wash waste; evaporator feed; non-complexed waste; waste water; tributyl phosphate waste. The waste material is classified as non-complexed and presently has a total waste volume of 143,830 liters (38,000 gallons) comprised of 143,830 liters (38,000 gallons) of sludge. There is no drainable liquid or pumpable liquid remaining. The volume of waste converts to less than 0.3 meters (1 foot) in the tank.

Code: 241-BX-107	Classification: Accepted
-------------------------	---------------------------------

Names: 241-BX-107; 241-BX-TK-107	Reclassification None
Type: Single-Shell Tank	Start Date: 1/1/1948
Status: Inactive	End Date: 1/1/1977

Description: The 22.9 meters (75 foot) diameter single-shell tank is constructed of 0.3 meters (1 foot) thick reinforced concrete with a 1 centimeter (0.375 inch) mild carbon steel liner (ASTM A 283 Grade C) on the bottom and sides and a 0.38 meters (1.25 foot) thick domed concrete top. The top of the steel liner is 5.5 meters (18 feet) above the bottom of the tank (at the side wall). The tank has a dished bottom, with a maximum depth of 30 centimeters (12 inches) below the side wall of the tank and a 1.2 meters (4 foot) radius knuckle. The tank has a 4.9 meters (16 foot) operating depth. The tank is set on a reinforced concrete foundation about 11.3 meters (37 feet) below grade. A three-ply cotton fabric waterproofing was applied over the foundation and steel tank. Four coats of primer paint were sprayed on all exposed interior tank surfaces. The tank ceiling dome was covered with three applications of magnesium zincfluorosilicate wash. Lead flashing was used to protect the joint where the steel liner met the concrete dome. Asbestos gaskets were used to seal the manholes in the tank dome. The tank was waterproofed on the sides and top with tar and gunnite. Tank capacity is 2,017,405 liters (533,000 gallons). The tank was covered with approximately 2.2 meters (7.25 feet) of overburden for shielding purposes. At present, the tank farm is surrounded by a chain link fence, topped with three strands of barbed wire. The ground surface is covered with gravel and no vegetation is seen.

Location: Tank 241-BX-107 is located on the north side of the 200 East Area about 850 meters (2,800 feet) north of the 221-B (B Plant) building, directly west of the 241-B Tank Farm.

Waste Type: Storage Tank

Waste Description: 241-BX-107 tank received bismuth phosphate first-cycle waste; metal waste; supernatant containing ion exchange waste from the 241-BX tank farm; evaporator feed; non-complexed waste; uranium recovery waste. The waste material is classified as non-complexed and presently has a total waste volume of 1,302,040 liters (344,000 gallons) comprised of 1,302,040 liters (344,000 gallons) of sludge. There are 113,550 liters (30,000 gallons) drainable liquid and 87,055 liters (23,000 gallons) pumpable liquid remaining. The volume of waste converts to about a 3 meters (10 foot) depth in the tank.

Code: 241-BX-108	Classification: Accepted
Names: 241-BX-108; 241-BX-TK-108	Reclassification None
Type: Single-Shell Tank	Start Date: 1/1/1949
Status: Inactive	End Date: 1/1/1974

Description: The 22.9 meters (75 foot) diameter single-shell tank is constructed of 0.3 meters (1 foot) thick reinforced concrete with a 1 centimeters (0.375 inch) mild carbon steel liner (ASTM A 283 Grade C) on the bottom and sides and a 0.38 meters (1.25 foot) thick domed concrete top. The top of the steel liner is 5.5 meters (18 feet) above the bottom of the tank (at the side wall). The tank has a dished bottom, with a maximum depth of 30 centimeters (12 inches) below the side wall of the tank and a 1.2 meters (4 foot) radius knuckle. The tank has a 4.9 meters (16 foot) operating depth. The tank is set on a reinforced concrete foundation about 11.3 meters (37 feet) below grade. A three-ply cotton fabric waterproofing was applied over the foundation and steel tank. Four coats of primer paint were sprayed on all exposed interior tank surfaces. The tank ceiling dome was covered with three applications of magnesium zincfluorosilicate wash. Lead flashing was used to protect the joint where the steel liner met the concrete dome. Asbestos gaskets were used to seal the manholes in the tank dome. The tank was waterproofed on the sides and top with tar and gunnite. Tank capacity is 2,017,405 liters (533,000 gallons). The tank was covered with approximately 2.2 meters (7.25 feet) of overburden for shielding

purposes. At present, the tank farm is surrounded by a chain link fence, topped with three strands of barbed wire. The ground surface is covered with gravel and no vegetation is seen.

Location: Tank 241-BX-108 is located on the north side of the 200 East Area about 850 meters (2,800 feet) north of the 221-B (B Plant) building, directly west of the 241-B Tank Farm.

Release Description: A leak of about 9,463 liters (2,500 gallons) occurred prior to or during 1974.

Waste Type: Storage Tank

Waste Description: 241-BX-108 tank received bismuth phosphate first-cycle waste; supernatant containing tributyl phosphate waste; PUREX coating waste; B Plant cesium recovery waste; ion exchange waste from 241-BX and -C tanks; non-complexed waste; uranium recovery waste; cladding waste. The waste material is classified as non-complexed and presently has a total waste volume of 98,410 liters (26,000 gallons) comprised of 98,410 liters (26,000 gallons) of sludge. There are 3,785 liters (1,000 gallons) drainable interstitial liquid and no pumpable liquid remaining. The volume of waste converts to about a 10 centimeters (4 inch) depth in the tank.

Code: 241-BX-109	Classification: Accepted
Names: 241-BX-109; 241-BX-TK-109	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1950
Status: Inactive	End Date: 1/1/1974

Description: The 22.9 meters (75 foot) diameter single-shell tank is constructed of 0.3 meters (1 foot) thick reinforced concrete with a 1 centimeter (0.375 inch) mild carbon steel liner (ASTM A 283 Grade C) on the bottom and sides and a 0.38 meter (1.25 foot) thick domed concrete top. The top of the steel liner is 5.5 meter (18 feet) above the bottom of the tank (at the side wall). The tank has a dished bottom, with a maximum depth of 30 centimeters (12 inches) below the side wall of the tank and a 1.2 meters (4 foot) radius knuckle. The tank has a 4.9 meters (16 foot) operating depth. The tank is set on a reinforced concrete foundation about 11.3 meters (37 feet) below grade. A three-ply cotton fabric waterproofing was applied over the foundation and steel tank. Four coats of primer paint were sprayed on all exposed interior tank surfaces. The tank ceiling dome was covered with three applications of magnesium zincfluorosilicate wash. Lead flashing was used to protect the joint where the steel liner met the concrete dome. Asbestos gaskets were used to seal the manholes in the tank dome. The tank was waterproofed on the sides and top with tar and gunnite. Tank capacity is 2,017,405 liters (533,000 gallons). The tank was covered with approximately 2.2 meters (7.25 feet) of overburden for shielding purposes. At present, the tank farm is surrounded by a chain link fence, topped with three strands of barbed wire. The ground surface is covered with gravel and no vegetation is seen.

Location: Tank 241-BX-109 is located on the north side of the 200 East Area about 2,800 feet (850 m) north of the 221-B (B Plant) building, directly west of the 241-B Tank Farm.

Waste Type: Storage Tank

Waste Description: 241-BX-109 tank received bismuth phosphate first-cycle waste; tributyl phosphate waste; PUREX coating waste; cesium recovery waste; ion exchange waste (waste fractionization) and supernatant containing tributyl phosphate waste from 241-BY and -C tanks; non-complexed waste; uranium recovery waste; waste water. The waste material is classified as non-complexed and presently has a total waste volume of 730,505 liters (93,000 gallons) comprised of 730,505 liters (193,000 gallons) of sludge. There is 49,205 liters (13,000 gallons) drainable interstitial liquid and 30,280 liters (8,000 gallons) pumpable liquid remaining. The volume of waste converts to about a 1.7 meters (5.5 foot) depth in the tank.

Code: 241-BX-110	Classification: Accepted
Names: 241-BX-110; 241-BX-TK-110	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1949
Status: Inactive	End Date: 1/1/1977

Description: The 22.9 meters (75 foot) diameter single-shell tank is constructed of 0.3 meters (1 foot) thick reinforced concrete with a 1 centimeter (0.375 inch) mild carbon steel liner (ASTM A 283 Grade C) on the bottom and sides and a 0.38 meter (1.25 foot) thick domed concrete top. The top of the steel liner is 5.5 meters (18 feet) above the bottom of the tank (at the side wall). The tank has a dished bottom, with a maximum depth of 30 centimeters (12 inches) below the side wall of the tank and a 1.2 meters (4 foot) radius knuckle. The tank has a 4.9 meters (16 foot) operating depth. The tank is set on a reinforced concrete foundation about 11.3 meters (37 feet) below grade. A three-ply cotton fabric waterproofing was applied over the foundation and steel tank. Four coats of primer paint were sprayed on all exposed interior tank surfaces. The tank ceiling dome was covered with three applications of magnesium zincfluorosilicate wash. Lead flashing was used to protect the joint where the steel liner met the concrete dome. Asbestos gaskets were used to seal the manholes in the tank dome. The tank was waterproofed on the sides and top with tar and gunnite. Tank capacity is 2,017,405 liters (533,000 gallons). The tank was covered with approximately 2.2 meters (7.25 feet) of overburden for shielding purposes. At present, the tank farm is surrounded by a chain link fence, topped with three strands of barbed wire. The ground surface is covered with gravel and no vegetation is seen.

Location: Tank 241-BX-110 is located on the north side of the 200 East Area about 850 meters (2,800 feet) north of the 221-B (B Plant) building, directly west of the 241-B Tank Farm.

Release Description: A leak of 30,280 liters (8,000 gallons) occurred prior to or during 1976. The leak volume estimate is an average of approximately 30,280 liters (8,000 gallons) for 19 tanks.

Waste Type: Storage Tank

Waste Description: 241-BX-110 tank received bismuth phosphate first-cycle waste; evaporator bottoms; supernatant containing coating waste; cesium recovery waste; ion exchange waste (waste fractionization) and B Plant first-cycle waste from 241-B and -C tank farms; non-complexed waste; waste water. The waste material is classified as non-complexed and presently has a total waste volume of 783,495 liters (207,000 gallons) comprised of 738,075 liters (195,000 gallons) sludge, 34,065 liters (9,000 gallons) saltcake, and 11,355 liters (3,000 gallons) supernatant liquid. There is 71,915 liters (19,000 gallons) drainable liquid and 49,205 liters (13,000 gallons) pumpable liquid remaining. The volume of waste converts to about a 1.8 meters (6 foot) depth in the tank.

Code: 241-BX-111	Classification: Accepted
Names: 241-BX-111; 241-BX-TK-111	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1950
Status: Inactive	End Date: 1/1/1977

Description: The 22.9 meters (75 foot) diameter single-shell tank is constructed of 0.3 meters (1 foot) thick reinforced concrete with a 1 centimeter (0.375 inch) mild carbon steel liner (ASTM A 283 Grade C) on the bottom and sides and a 0.38 meters (1.25 foot) thick domed concrete top. The top of the steel liner is 5.5 meters (18 feet) above the bottom of the tank (at the side wall). The tank has a dished bottom, with a maximum depth of 30 centimeters (12 inches) below the side wall of the tank and a 1.2 meters (4 foot) radius knuckle. The tank has a 4.9 meters (16 foot) operating depth. The tank is set on a reinforced concrete foundation about 11.3 meters (37 feet) below grade. A three-ply cotton fabric waterproofing was applied over the foundation and steel

tank. Four coats of primer paint were sprayed on all exposed interior tank surfaces. The tank ceiling dome was covered with three applications of magnesium zincfluorosilicate wash. Lead flashing was used to protect the joint where the steel liner met the concrete dome. Asbestos gaskets were used to seal the manholes in the tank dome. The tank was waterproofed on the sides and top with tar and gunnite. Tank capacity is 2,017,405 liters (533,000 gallons). The tank was covered with approximately 2.2 meters (7.25 feet) of overburden for shielding purposes. At present, the tank farm is surrounded by a chain link fence, topped with three strands of barbed wire. The ground surface is covered with gravel and no vegetation is seen.

Location: Tank 241-BX-111 is located on the north side of the 200 East Area about 850 meters (2,800 feet) north of the 221-B (B Plant) building, directly west of the 241-B Tank Farm.

Release Description: A leak of 30,280 liters (8,000 gallons) occurred prior to or during 1984. The leak volume estimate is an average of approximately 30,280 liters (8,000 gallons) for 19 tanks.

Waste Type: Storage Tank

Waste Description: 241-BX-111 tank received bismuth phosphate first-cycle waste; evaporator bottoms; in-tank solidification (ITS-2) bottoms and recycle system; supernatant containing ion exchange waste; coating waste; first-cycle waste from 241-BX tanks; evaporator feed; non-complexed waste. The waste material is classified as non-complexed and presently has a total waste volume of 613,170 liters (162,000 gallons) comprised of 196,820 liters (52,000 gallons) sludge, 412,565 liter (109,000 gallons) saltcake, and 3,785 liter (1,000 gallons) supernatant liquid. There is 11,355 liters (3,000 gallons) drainable liquid and 3,785 liters (1,000 gallons) pumpable liquid remaining. The volume of waste converts to about a 1.4 m (4.5 foot) depth in the tank.

Code: 241-BX-112 **Classification:** Accepted

Names: 241-BX-112; 241-BX-TK-112 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1950

Status: Inactive **End Date:** 1/1/1977

Description: The 22.9 meters (75 foot) diameter single-shell tank is constructed of 0.3 meters (1 foot) thick reinforced concrete with a 1 centimeter (0.375 inch) mild carbon steel liner (ASTM A 283 Grade C) on the bottom and sides and a 0.38 meter (1.25 foot) thick domed concrete top. The top of the steel liner is 5.5 meters (18 feet) above the bottom of the tank (at the side wall). The tank has a dished bottom, with a maximum depth of 30 centimeters (12 inches) below the side wall of the tank and a 1.2 meters (4 foot) radius knuckle. The tank has a 4.9 meters (16 foot) operating depth. The tank is set on a reinforced concrete foundation about 11.3 meters (37 feet) below grade. A three-ply cotton fabric waterproofing was applied over the foundation and steel tank. Four coats of primer paint were sprayed on all exposed interior tank surfaces. The tank ceiling dome was covered with three applications of magnesium zincfluorosilicate wash. Lead flashing was used to protect the joint where the steel liner met the concrete dome. Asbestos gaskets were used to seal the manholes in the tank dome. The tank was waterproofed on the sides and top with tar and gunnite. Tank capacity is 2,017,405 liters (533,000 gallons). The tank was covered with approximately 2.2 meters (7.25 feet) of overburden for shielding purposes. At present, the tank farm is surrounded by a chain link fence, topped with three strands of barbed wire. The ground surface is covered with gravel and no vegetation is seen.

Location: Tank 241-BX-112 is located on the north side of the 200 East Area about 850 meters (2,800 feet) north of the 221-B (B Plant) building, directly west of the 241-B Tank Farm.

Waste Type: Storage Tank

Waste Description: 241-BX-112 tank received first-cycle waste; evaporator bottoms; supernatant containing evaporator bottoms waste; tri-butyl phosphate; ion exchange waste (waste fractionization); first-

cycle waste from 241-C tanks: waste water; PUREX coating waste; non-complexed waste. The waste material is classified as non-complexed and presently has a total waste volume of 624,525 liters (165,000 gallons) comprised of 620,740 liters (164,000 gallons) sludge and 3,785 liters (1,000 gallons) supernatant liquid. There is 30,280 liters (8,000 gallons) drainable liquid and 7,570 liters (2,000 gallons) pumpable liquid remaining. The volume of waste converts to about a 1.4 meters (4.5 foot) depth in the tank.

Code: 241-BX-153 **Classification:** Accepted

Names: 241-BX-153; 241-BX-153 Diversion Box **Reclassification:** None

Type: Diversion Box **Start Date:** 1/1/1948

Status: Inactive **End Date:** 1/1/1983

Description: Diversion Box 241-BX-153 is constructed of reinforced concrete structure built mostly below grade. Only approximate 38 centimeters (15 inches) of this diversion box appears above grade. The cover blocks are made up in sections consisting of thirty one pre-formed concrete blocks. The layers of concrete blocks are arranged in three stacked rows, the bottom row having the shortest length and the top row having the longest length with 11 total sections. The tapered ends aid in locating the blocks into place and each block overlaps with the one above and/or below it. Each block is about 51 centimeters (20 inches) high and 1.17 meters (46 inches) wide.

Location: Diversion Box 241-BX-153 is located in the southeastern portion of the 241-BX Tank Farm.

Related Sites/Structures: Diversion Box 241-BX-153 interconnects with the following: 241-B-152 diversion box and 241-B-155 diversion box, 200-E-216-PL, 241-BX Tank Farm, 241-BY Tank Farm, and 241-BX-302A Catch Tank.

Waste Type: Process Effluent

Waste Description: This unit was used for transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operation. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Code: 241-BX-302A **Classification:** Accepted

Names: 241-BX-302A; 241-BX-302-A Catch Tank; 9053; 9253; 9453; Drain Lines V357 **Reclassification:** None

Type: Catch Tank **Start Date:** 1/1/1948

Status: Inactive **End Date:** 1/1/1985

Description: The buried tank is located inside the fenced 241-BX-155 Tank Farm. It is covered with gravel and surrounded with post and chain. The tank is marked with radiological and IMUST signs.

Location: The 241-BX-302A catch tank is located inside the 241-BX Tank Farm, southeast of the 241-BX-101 tank.

Related Sites/Structures: 241-BX-302A catch tank is associated with the 241-BR-152, 241-BX-153, 241-BYR-152 and 241-BXR-152 diversion boxes. Lines V357, 9053, 9253, 9453 are the drain lines from the diversion boxes.

Process Description: 241-BX-302A catch tank was designed to collect waste drainage and spills from the diversion boxes during transfers.

Waste Type: Process Effluent

Waste Description: The total tank volume was estimated in 1984 to be 3,160 liters (835 gallons) of sludge with no supernate. The volume of waste converts to a waste level of about 26 cm (10.25 inches) in the tank. The contents of this tank does not meet the definition of dangerous waste (according to Ecology) and in its present condition, poses no immediate environmental or human safety hazard, either from a criticality risk or leakage of hazardous waste.

Code: 244-BX DCRT **Classification:** Accepted

Names: 244-BX DCRT; 244-BX Double-Contained Receiver Tank; 244-BX Receiver Tank; 244-BX Receiver Vault; 244-BX RT; 244-BX-TK/SMP **Reclassification:** None

Type: Receiver Tank **Start Date:** 1/1/1983

Status: Inactive **End Date:** 1/1/2005

Description: 244-BX Receiver Tank is an underground, double-contained receiver tank (DCRT) constructed of carbon steel with a 117,335 liters (31,000 gallons) design capacity. The tank sets lengthwise in a reinforced concrete, steel-lined vault. The lowest portion of the vault is 8.5 m (28 feet) below grade and houses the tank. The upper portion of the vault is comprised of three sections; the pump pit in the southern section comprises almost half the space. The filter pit is in the middle section and the instrumentation pit is in the northern section of this part of the vault.

Location: 244-BX Receiver Vault is located on the north side of the 200 East Area about 847 meters (2,780 feet) north of the 221-B (B Plant) building and about 22.1 meters (72.6 feet) east of tank 241-BX-101.

Related Sites/Structures: 244-BX Receiver Vault interconnects with the following: 241-B, 241-BX, & 241-BY Tank Farms.

Waste Type: Chemicals

Waste Description: 244-BX Receiver Tank can accept/transport waste from 241-B, 241-BX, & 241-BY Tank Farms. This tank last received waste from the 241-BY-102 and 241-BY-109 Single-Shell Tanks during the 1991 Stabilization Campaign. The tank currently contains 17,636 gallons (66,752 L) of waste. This represents just over one-half of the tank's design capacity.

Code: 241-BXR-151 **Classification:** Accepted

Names: 241-BXR-151; 241-BXR-151 Diversion Box **Reclassification:** None

Type: Diversion Box **Start Date:** 1/1/1948

Status: Inactive **End Date:** 1/1/1984

Description: Diversion Box 241-BXR-151 is an underground structure constructed of concrete. Approximately 0.3 meters (1 foot) of the diversion box concrete cover appears above grade. The outer dimensions are approximately 14.6 meters (48 feet) by 9.4 meters (30.7 feet). The structure is L shaped from the side view with 4 meters (13 feet) of the north side being 5.1 meters (16.7 feet) high and 5.4 m (17.7 feet) of the southern portion being 2.4 meters (7.75 feet) high. The southern portion of the structure is 2.3 meter (7.5 feet) below grade. The concrete cover is made up in sections consisting of twenty nine interlocking pre-formed concrete blocks. The concrete blocks are about 0.9 meters (3 feet) wide and range in thickness from 0.46 meters (1.5 feet) to 0.61 meters (2 feet). Each cover block is equipped with lifting bails made from steel bar. The blocks were sealed with a combination of hot sealing compound and a flexcell bituminous fiber expansion joint.

Location: Diversion Box 241-BXR-151 is located in the southern portion of the 241-BX Tank Farm,

south of the 241-BX-107 tank.

**Related Sites/
Structures:** The diversion box is associated with the 244-BXR vault.

**Process
Description:** Diversion Box 241-BXR-151 connects with the 244-BXR Vault with the 241-BX Tank Farm.

Waste Type: Process Effluent

**Waste
Description:** This unit was used for the transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operation. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Code: 241-BXR-152 **Classification:** Accepted

Names: 241-BXR-152; 241-BXR-152 Diversion Box **Reclassification** None

Type: Diversion Box **Start Date:** 1/1/1948

Status: Inactive **End Date:** 1/1/1984

Description: 241-BXR-152 is an underground concrete structure. It is co-located in a series of three diversion boxes that are joined together. 241-BXR-152 is the center diversion box. 241-BR-152 Diversion Box is on the eastern end and 241-BYR-152 is on the west end of the diversion box group. Its cover blocks and lifting bails are visible from the surface.

Location: Diversion Box 241-BXR-152 is located in the southeastern portion of the 241-BX Tank Farm, inside the tank farm fence. It is south of the 241-BX-101 tank.

**Related Sites/
Structures:** Diversion Box 241-BXR-152 is associated with the 241-BX Tank Farm and the 241-BX-302A catch tank.

**Process
Description:** Diversion Box 241-BXR-152 is constructed of concrete with a height of approximately 3.4 meters (11.1 feet). Approximately 0.3 meters (1 foot) of the diversion box concrete cover appears above grade. The outer dimensions are approximately 10.7 meters (35 feet) by 11.5 meters (37.8 feet). The structure's cover is in sections consisting of several interlocking pre-formed concrete blocks. Diversion Boxes and receiving vaults drain to catch tanks or single-shell tanks.

Waste Type: Process Effluent

**Waste
Description:** This unit was used to transfer waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operation. It is estimated that approximately 50 pounds (23 kilograms) of lead shielding may be stored in each diversion box.

Code: 241-BXR-153 **Classification:** Accepted

Names: 241-BXR-153; 241-BXR-153 Diversion Box;
Line 9453 **Reclassification** None

Type: Diversion Box **Start Date:** 1/1/1948

Status: Inactive **End Date:** 1/1/1984

Description: The 241-BXR-153 Diversion box is co-located with the 241-BYR-153 Diversion Box. 241-BXR-153 is on the east side of the 241-BYR-153 Diversion Box. The diversion boxes are underground concrete structures. Their cover blocks and lifting bails are visible from the surface.

Location: Diversion Box 241-BXR-153 is located in the southern portion of the 241-BX Tank Farm, inside the tank farm fence. It is south of the 241-BX-104 tank.

Related Sites/ Structures: Diversion Box 241-BXR-153 is associated with the 241-BX and 241-BY Tank Farms and the 241-B-152 and 241-B-155 diversion boxes. Line 9453 is the drain line.

Process Description: Diversion boxes and receiving vaults drain to catch tanks or single-shell tanks. Diversion Box 241-BXR-153 is constructed of concrete with a height of approximately 3.7 meters (12 feet). Approximately 0.3 meters (1 foot) of the diversion box concrete cover appears above grade. The outer dimensions are approximately 11.6 meters (38 feet) by 12 meters (39.3 feet). The structure's cover is in sections consisting of several interlocking pre-formed concrete blocks. The northern section consists of 12 blocks, center section has 11, and the southern section has 8 cover blocks.

Waste Type: Process Effluent

Waste Description: This unit was used to transfer waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operation. It is estimated that approximately 50 pounds (23 kilograms) of lead shielding may be stored in each diversion box.

Code: 244-BXR VAULT	Classification: Accepted
Names: 244-BXR Vault; 244-BXR VAULT; Lines 9765 and 7453; 244-BXR Receiving Vault	Reclassification: None
Type: Receiving Vault	Start Date: 1/1/1948
Status: Inactive	End Date: 1/1/1985

Description: 244-BXR Vault is an underground concrete structure. Only 0.3 meters (1 foot) of the vault concrete cover appears above grade. The vault is surrounded with post and chain and marked with IMUST signs. The vault houses four tanks of two different sizes in the lower portion of the structure, each within a large concrete chamber. The tanks are numbered BXR-001, BXR-002, BXR-003, and BXR-011 from east to west. Each tank is tied individually to diversion box 241-BXR-151. The concrete cover is made up in sections consisting of twenty-nine interlocking pre-formed concrete blocks. The concrete blocks are about 1 meter (3.4 feet) wide and just over 2.4 meters (8 feet) long.

Location: The 244-BXR Vault is located in the southern portion of the 241-BY Tank Farm, inside the tank farm fence.

Related Sites/ Structures: The 244-BXR Vault interconnects with the 241-BXR-151 Diversion Box and the 241-BX Tank Farm. Lines 9765 and 7453 are the drain lines to the 244-BXR sump.

Waste Type: Storage Tank

Waste Description: This unit was used for transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operation. The waste volumes in tanks 244-BXR-001, 244-BXR-002, 244-BXR-003, and 244-BXR-011 are currently unknown. WHC-EP-0560 indicates large volumes of sludge and high cesium-137 concentrations in the 244-BXR vault. In addition, the nitrate and nitrite contents are elevated and could cause this waste to be designated as "dangerous" under the EPA and Ecology criteria. This vault does not pose a criticality hazard from the levels of fissionable isotopes that were found.

This Site has the Following SubSites:

Code: 244-BXR VAULT:1
Names: 244-BXR VAULT:1; 244-BXR-001; 244-BXR-001 Tank and Sump

Code: 244-BXR VAULT:2
Names: 244-BXR VAULT:2; 244-BXR-002; 244-BXR-002 Tank and Sump

Code: 244-BXR VAULT:3
Names: 244-BXR VAULT:3; 244-BXR-003; 244-BXR-003 Tank and Sump

Code: 244-BXR VAULT:4
Names: 244-BXR VAULT:4; 244-BXR-011; 244-BXR-011 Tank and Sump

Code: 244-BXR VAULT:1 **Classification:** Accepted

Names: 244-BXR VAULT:1; 244-BXR-001; 244-BXR-001 Tank and Sump **Reclassification** None

Type: Receiving Vault **Start Date:**

Status: Inactive **End Date:**

Description: Tank 244-BXR-001 is located in an individual cell inside of the 244-BXR Vault. The concrete cell contains a sump with a capacity of 170 liters (45 gallons). Each cell within the vault is separated from the adjacent cell by a 0.6 meter (2 foot) thick concrete wall. The tank is constructed of 0.64 centimeter (1/4 inch) carbon steel and is 6.1 meters (20 feet) in diameter, 6.1 meters (20 feet) tall, and has a nominal capacity of 189,000 liters (50,000 gallons). When in service, the tank was used as a slurry accumulation tank receiving a maximum of 51,930 liters (13,720 gallons) per day of metal waste slurry from tanks in the 241-BX and 241-BY Tank Farms. Tank 244-BXR-001 was isolated in 1985 as part of the 244-BXR Vault isolation. The results for samples taken from the tank and sump in 1984 are available in WHC-SD-EN-ES-040, Rev 0.

The SubSite is Part Of:

Code: 244-BXR VAULT

Names: 244-BXR Vault; 244-BXR VAULT; Lines 9765 and 7453; 244-BXR Receiving Vault

Code: 244-BXR VAULT:2 **Classification:** Accepted

Names: 244-BXR VAULT:2; 244-BXR-002; 244-BXR-002 Tank and Sump **Reclassification** None

Type: Receiving Vault **Start Date:**

Status: Inactive **End Date:**

Description: Tank 244-BXR-002 is located in an individual cell inside of the 244-BXR Vault. The concrete cell contains a sump with a capacity of 170 liters (45 gallons). Each cell within the vault is separated from the adjacent cell by a 0.6 meter (2 foot) thick concrete wall. The tank is constructed of 0.64 centimeter (1/4 inch) Type 347 stainless steel and is 4.3 meters (14 feet) in diameter, 3.7 meters (12 feet) tall, and has a nominal capacity of 56,800 liters (15,000 gallons). The tank contains in-tank cooling coils. When in service, Tank 244-BXR-002 and Tank 244-BXR-003 were configured and used identically. The tanks were used as a pair in waste blending operations. Under normal conditions a slurry stream was brought in from tank 244-BXR-001 and mixed with nitric acid. Tank 244-BXR-002 received a maximum of 53,860 liters (14,230 gallons) per day from tank 244-BXR-001 and a maximum of 29,500 liters (7,800 gallons) per day of nitric acid. The blended solution was then pumped to Tank 244-BXR-011. Tank 244-BXR-002 was isolated in 1985 as part of the 244-BXR Vault isolation. The results

for samples taken from the tank and sump in 1984 are available in WHC-SD-EN-ES-040, Rev 0. The sump may contain ferrocyanide discharged from the 241-BXR-151 diversion box.

The SubSite is Part Of:**Code:** 244-BXR VAULT**Names:** 244-BXR Vault; 244-BXR VAULT; Lines 9765 and 7453; 244-BXR Receiving Vault

Code: 244-BXR VAULT:3**Classification:** Accepted**Names:** 244-BXR VAULT:3; 244-BXR-003; 244-BXR-003 Tank and Sump**Reclassification:** None**Type:** Receiving Vault**Start Date:****Status:** Inactive**End Date:**

Description: Tank 244-BXR-003 is located in an individual cell inside of the 244-BXR Vault. The concrete cell contains a sump with a capacity of 170 liters (45 gallons). Each cell within the vault is separated from the adjacent cell by a 0.6 meter (2 foot) thick concrete wall. The tank is constructed of 0.64 centimeter (1/4 inch) Type 347 stainless steel and is 4.3 meters (14 feet) in diameter, 3.7 meters (12 feet) tall, and has a nominal capacity of 56,800 liters (15,000 gallons). The tank contains in-tank cooling coils. When in service, Tank 244-BXR-002 and Tank 244-BXR-003 were configured and used identically. The tanks were used as a pair in waste blending operations. Under normal conditions a slurry stream was brought in from tank 244-BXR-001 and mixed with nitric acid. Tank 244-BXR-003 received a maximum of 53,860 liters (14,230 gallons) per day from tank 244-BXR-001 and a maximum of 29,500 liters (7,800 gallons) per day of nitric acid. The blended solution was then pumped to Tank 244-BXR-011. Tank 244-BXR-003 was isolated in 1985 as part of the 244-BXR Vault isolation. The results for samples taken from the tank and sump in 1984 are available in WHC-SD-EN-ES-040, Rev 0.

The SubSite is Part Of:**Code:** 244-BXR VAULT**Names:** 244-BXR Vault; 244-BXR VAULT; Lines 9765 and 7453; 244-BXR Receiving Vault

Code: 244-BXR VAULT:4**Classification:** Accepted**Names:** 244-BXR VAULT:4; 244-BXR-011; 244-BXR-011 Tank and Sump**Reclassification:** None**Type:** Receiving Vault**Start Date:****Status:** Inactive**End Date:**

Description: Tank 244-BXR-011 is located in an individual cell inside of the 244-BXR Vault. The cell contains a sump with a capacity of 170 liters (45 gallons). Each cell within the vault is separated from the adjacent cell by a 0.6 meter (2 foot) thick concrete wall. The tank is constructed of 0.64 centimeter (1/4 inch) Type 347 stainless steel and is 6.1 meters (20 feet) in diameter, 6.1 meters (20 feet) tall, and has a nominal capacity of 189,000 liters (50,000 gallons). When in service, the tank was used as a pump tank for the Uranium Recovery operations. It received approximately 103,000 liters (27,200 gallons) per day of acid solutions from Tanks 244-BXR-002 and 244-BXR-003. The solutions were pumped from 244-BXR-011 to the 241-ER-151 diverter station and from there to U Plant for uranium recovery. Tank 244-BXR-011 was isolated in 1985 as part of the 244-BXR Vault isolation. The results for a tank solids analysis performed in 1978 are available in WHC-SD-EN-ES-040, Rev. 0. Literature indicates that the wall of the Tank 244-BXR-011 is buckled. Occurrence report 79-70 describes

the condition of the tank. The tank failure was due to an overpressure condition on the exterior of the tank from a higher than allowed liquid level in the cell.

The SubSite is Part Of:

Code: 244-BXR VAULT

Names: 244-BXR Vault; 244-BXR VAULT; Lines 9765 and 7453; 244-BXR Receiving Vault

Code: 241-BY-101

Classification: Accepted

Names: 241-BY-101; 241-BY-TK-101

Reclassification: None

Type: Single-Shell Tank

Start Date: 1/1/1950

Status: Inactive

End Date: 1/1/1971

Description: The unit is comprised of a carbon steel liner within a reinforced concrete shell, 11.3 meters (37 feet) high, with a capacity of 2,869,030 liters (758,000 gallons). The bottom of the unit is 13.7 meters (45 feet) below grade, and the dome is located below grade for shielding purposes. This type was built to the original design, having a dished bottom but with an increased operating depth of 7 meters (23 feet).

Location: The 241-BY Tank Farm is directly north of the 241-BX Tank Farm. The 241-BY-101 tank is located in the southeast portion of the 241-BY Tank Farm.

Waste Type: Storage Tank

Waste Description: The tank received bismuth phosphate metal waste and supernatant containing tributyl phosphate waste and evaporator bottoms from 241-BY and -C tank farms. Presently, the waste material is classified as non-complexed and has a total waste volume of 1,465,182 liters (387,000 gallons). Saltcake comprises 1,052,230 liters (278,000 gallons), sludge comprises 412,565 liters (109,000 gallons), and no supernatant. There is no pumpable liquid remaining and 18,925 liters (5,000 gallons) drainable liquid remaining. Reported Date: April 30, 1996

Code: 241-BY-102

Classification: Accepted

Names: 241-BY-102; 241-BY-TK-102

Reclassification: None

Type: Single-Shell Tank

Start Date: 1/1/1950

Status: Inactive

End Date: 1/1/1977

Description: The unit is comprised of a carbon steel liner within a reinforced concrete shell, 11.3 meters (37 feet) high, with a capacity of 2,869,030 liters (758,000 gallons). The bottom of the unit is 13.7 meters (45 feet) below grade, and the dome is located below grade for shielding purposes. This type was built to the original design, having a dished bottom but with an increased operating depth of 7 meters (23 feet).

Location: The 241-BY Tank Farm is directly north of the 241-BX Tank Farm. The 241-BY-102 tank is located in the eastern portion of the 241-BY Tank Farm.

Waste Type: Storage Tank

Waste Description: The tank received bismuth phosphate metal waste and supernatant containing tributyl phosphate waste, coating waste; and evaporator bottoms from 241-C, -BX, and -BY tanks. Presently, the waste material is classified as non-complexed and has a total waste volume of 277,000 gallons (1,048,445 L). Saltcake comprises the 1,048,445 liters (277,000 gallons) with no sludge or pumpable liquid remaining. There is 41,635 liters (11,000 gallons) of drainable liquid remaining. Reported Date: April 30, 1996

Code: 241-BY-103	Classification: Accepted
Names: 241-BY-103; 241-BY-TK-103	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1950
Status: Inactive	End Date: 1/1/1973

Description: The unit is comprised of a carbon steel liner within a reinforced concrete shell, 11.3 meters (37 feet) high, with a capacity of 2,869,030 liters (758,000 gallons). The bottom of the unit is 13.8 meters (45.3 feet) below grade, and the dome is located below grade for shielding purposes. This type was built to the original design, having a dished bottom but with an increased operating depth of 7 meters (23 feet).

Location: The 241-BY Tank Farm is directly north of the 241-BX Tank Farm. The 241-BY-103 tank is located in the northeast portion of the 241-BY Tank Farm.

Release Description: UPR-200-E-134

Waste Type: Storage Tank

Waste Description: Bismuth phosphate metal waste; PUREX coating waste; and supernatant containing evaporator bottoms, cladding waste, tributyl phosphate waste, and PUREX high-level and organic wash wastes from 241-BX, -BY, -C, and -B tanks. Currently contains non-complexed waste with a total waste volume of 1,514,000 liters (400,000 gallons). Saltcake comprises 1,480,200 liters (391,000 gallons), sludge comprises 34,065 liters (9,000 gallons), and no supernatant. Pumpable liquid remaining is 518,545 liters (137,000 gallons).

Code: 241-BY-104	Classification: Accepted
Names: 241-BY-104; 241-BY-TK-104	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1950
Status: Inactive	End Date: 1/1/1977

Description: The unit is a single-shell tank built in 1948. It is comprised of a carbon steel liner within a reinforced concrete shell, 11.3 meters (37 feet) high, with a capacity of 2,869,030 liters (758,000 gallons). The bottom of the unit is 13.7 meters (45 feet) below grade, and the dome is located below grade for shielding purposes. This type was built to the original design, having a dished bottom but with an increased operating depth of 7 meters (23 feet).

Location: The 241-BY Tank Farm is directly north of the 241-BX Tank Farm. The 241-BY-104 tank is located in the southern portion of the 241-BY Tank Farm.

Process Description: The tank received metal waste via cascade from 241-BX-106 (1951). It overflowed to 241-BY-105 via cascade (1951).

Waste Type: Storage Tank

Waste Description: Bismuth phosphate metal waste; tributyl phosphate waste; and supernatant containing coating waste, tributyl phosphate waste, ion exchange waste, and evaporator bottoms from 241-BY, -BX, and -C tanks. Tank BY-104 contains metal waste from BX tank farms (1951-4). Received accumulated sludge from other ferrocyanide settling tanks. Coating waste, ion exchange waste, and evaporator bottoms waste was sent to the tank through 1977. Currently contains non-complexed waste with a total waste volume of 1,385,310 liters (406,000 gallons), sludge comprises 151,400 liters (40,000 gallons), and no supernatant. There is no pumpable liquid remaining and 68,130 liters (18,000 gallons) drainable liquid remaining. This is an ITS-2 unit.

Code: 241-BY-105	Classification: Accepted
Names: 241-BY-105; 241-BY-TK-105	Reclassification: None
Type: Single-Shell Tank	Start Date: 6/1/1951
Status: Inactive	End Date: 1/1/1974

Description: The unit is a single-shell tank built in 1948-1949. It is comprised of a carbon steel liner within a reinforced concrete shell, 11.3 meters (37 feet) high, with a capacity of 2,869,030 liters (758,000 gallons). The bottom of the unit is 13.7 meters (45 feet) below grade, and the dome is located below grade for shielding purposes. This type was built to the original design, having a dished bottom but with an increased operating depth of 7 meters (23 feet).

Location: The 241-BY Tank Farm is directly north of the 241-BX Tank Farm. The 241-BY-105 tank is located in the central portion of the 241-BY Tank Farm.

Release Description: This tank is an assumed leaker with a leak of approximately 30,280 liters (8,000 gallons) reported in 1984.

Process Description: The tank received U Plant uranium recovery process waste from 241-BY-107 and 241-BY-110. The metal waste was received via cascade from 241-BY-104, which had received metal waste via cascade from 241-BX-106.

Waste Type: Storage Tank

Waste Description: Tank BY-105 received metal waste via cascade (1951), U Plant waste from tanks 241-BY-107 and 241-BY-110 (1954) and U Plant waste intermittently until 1966. The tank received wastewater (1957-1974), coating waste (1962-1967), and was an in-tank solidification bottoms receiver (1967). The tank contained evaporator bottoms waste from the in-tank solidification program (1968-1974). Sixty-three tons of Portland cement was added in 1977. Presently, the waste material is classified as non-complexed and has a total waste volume of 1,903,855 liters (503,000 gallons). Saltcake comprised 1,737,315 liters (459,000 gallons), sludge comprises 166,540 liters (44,000 gallons), and no supernatant. There is no pumpable liquid remaining and 726,720 liters (192,000 gallons) drainable liquid remaining.

Code: 241-BY-106	Classification: Accepted
Names: 241-BY-106; 241-BY-TK-106	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1953
Status: Inactive	End Date: 1/1/1977

Description: The unit is a single-shell tank built in 1948 which is comprised of a carbon steel liner within a reinforced concrete shell, 11.3 meters (37 feet) high, with a capacity of 2,869,030 liters (758,000 gallons). The bottom of the unit is 13.7 m (45 feet) below grade, and the dome is located below grade for shielding purposes. This type was built to the original design, having a dished bottom but with an increased operating depth of 7 meters (23 feet).

Location: The 241-BY Tank Farm is directly north of the 241-BX Tank Farm. The 241-BY-106 tank is located in the northern portion of the 241-BY Tank Farm.

Release Description: Current tank leak volume estimate of 30, 280 liters (8, 000 gallons) is based on an average of 19 tanks.

Process Description: The tank was used as a settling tank for ferrocyanide scavenged uranium recovery process waste in 1956.

Waste Type: Storage Tank

Waste Description: Bismuth phosphate first-cycle waste (1953), in-plant ferrocyanide waste from 1955-7, wastewater (1957-1974), and supernatant containing coating waste (1961-1970). In 1968 the tank began to receive evaporator bottoms from 241-BY and -C tank farms waste. The tank received in-tank solidification bottoms and recycle waste between 1970 and 1976 and evaporator feed from 1976-7. The tank also received tributyl phosphate waste. Presently, the waste material is classified as non-complexed and has a total waste volume of 2,429,970 liters (642,000 gallons). Saltcake comprises 2,070,395 liters (547,000 gallons), sludge comprises 359,575 liters (95,000 gallons), and no supernatant. There is 616,955 liters (163,000 gallons) pumpable liquid remaining and 757,000 liters (200,000 gallons) drainable liquid remaining. This is an ITS-2 unit.

Code: 241-BY-107 **Classification:** Accepted

Names: 241-BY-107; 241-BY-TK-107 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1950

Status: Inactive **End Date:** 1/1/1974

Description: The unit is comprised of a carbon steel liner within a reinforced concrete shell, 11.3 meters (37 feet) high, with a capacity of 2,869,030 liters (758,000 gallons). The bottom of the unit is 45 feet below grade, and the dome is located below grade for shielding purposes. This type was built to the original design, having a dished bottom but with an increased operating depth of 7 meters (23 feet).

Location: The 241-BY Tank Farm is directly north of the 241-BX Tank Farm. The 241-BY-107 tank is located in the southern portion of the 241-BY Tank Farm.

Release Description: A leak in the amount of 57,153 liters (15,100 gallons) occurred prior to or during 1984. The leak volume was based on observed liquid level decreases within the tank.

Waste Type: Storage Tank

Waste Description: The tank received tributyl phosphate waste; bismuth phosphate first-cycle waste; and supernatant containing tributyl phosphate waste, coating waste, and evaporator bottoms from 241-C, -BX, and -T (BY) tank farms. Presently, the waste material is classified as non-complexed and has a total waste volume of 1,006,810 liters (266,000 gallons). Saltcake comprises 779,710 liters (206,000 gallons), sludge comprises 227,100 liters (60,000 gallons), there is 94,625 liters (25,000 gallons) of drainable liquid and no pumpable liquid remaining. This is an ITS-2 unit.

Code: 241-BY-108 **Classification:** Accepted

Names: 241-BY-108; 241-BY-TK-108 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1951

Status: Inactive **End Date:** 1/1/1972

Description: The unit is a single-shell tank built in 1948. It is comprised of a carbon steel liner within a reinforced concrete shell, 11.3 meters (37 feet) high, with a capacity of 2,869,030 liters (758,000 gallons). The bottom of the unit is 13.7 meters (45 feet) below grade, and the dome is located below grade for shielding purposes. This tank type was built to the original design, having a dished bottom but with an increased operating depth of 7 meters (23 feet).

Location: The 241-BY Tank Farm is directly north of the 241-BX Tank Farm. The 241-BY-108 tank is located in the central portion of the 241-BY Tank Farm.

Release UPR-200-E-135

Description:

Related Sites/ Structures: 241-BY-108 is the second tank in a three-tank cascade series (241-BY-107, 241-BY-108 and 241-BY-109).

Waste Type: Storage Tank

Waste Description: Initially tank BY-108 received first cycle waste from the tank 241-BY-107 cascade from 1951-1953. The tank received U Plant waste from 1953-1959. The tank received in-plant ferrocyanide waste from 1954-1957. The tank contained U Plant waste and coating waste from 1959-1968. The tank received evaporator bottoms waste from 1968 to 1973. From 1972-1975, the tank received wastewater. Presently, the waste material is classified as non-complexed and has a total waste volume of 862,980 liters (228,000 gallons). Saltcake comprises 280,090 liters (74,000 gallons), sludge comprises 582,890 liters (154,000 gallons), and no supernatant. There is no pumpable liquid remaining and 34,065 liters (9,000 gallons) drainable liquid remaining. This is an ITS-2 unit.

Code: 241-BY-109

Classification: Accepted

Names: 241-BY-109; 241-BY-TK-109

Reclassification None

Type: Single-Shell Tank

Start Date: 1/1/1953

Status: Inactive

End Date: 1/1/1979

Description: The unit is comprised of a carbon steel liner within a reinforced concrete shell, 11.3 meters (37 feet) high, with a capacity of 2,869,030 liters (758,000 gallons). The bottom of the unit is 13.7 meters (45 feet) below grade, and the dome is located below grade for shielding purposes. This type was built to the original design, having a dished bottom but with an increased operating depth of 7 meters (23 feet). It is surrounded by a safety fence within the tank farm.

Location: The 241-BY Tank Farm is directly north of the 241-BX Tank Farm. The 241-BY-109 tank is located in the northern portion of the 241-BY Tank Farm.

Waste Type: Storage Tank

Waste Description: The tank received supernatant containing tributyl phosphate waste; evaporator bottoms; and PUREX organic wash waste from 241-B, -BX, -BY, and -C tank farms. Presently, the waste material is classified as non-complexed and has a total waste volume of 1,601,055 liters (423,000 gallons). Saltcake comprises 1,286,900 liters (340,000 gallons) and sludge comprises 314,155 liters (83,000 gallons). There is 105,980 liters (28,000 gallons) of drainable and 15,140 liters (4,000 gallons) of pumpable liquid remaining.

Code: 241-BY-110

Classification: Accepted

Names: 241-BY-110; 241-BY-TK-110

Reclassification None

Type: Single-Shell Tank

Start Date: 1/1/1951

Status: Inactive

End Date: 1/1/1977

Description: The unit is a single-shell tank built in 1948. The unit is comprised of carbon steel liner within a reinforced concrete shell, 11.3 meters (37 feet) high, with a capacity of 2,869,030 liters (758,000 gallons). The bottom of the unit is 13.7 meters (45 feet) below grade, and the dome is located below grade for shielding purposes. This type was built to the original design, having a dished bottom but with an increased operating depth of 7 meters (23 feet).

Location: The 241-BY Tank Farm is directly north of the 241-BX Tank Farm. The 241-BY-110 tank is

located in the southwestern portion of the 241-BY Tank Farm.

Waste Type: Storage Tank

Waste Description: Initially tank 241-BY-110 received first cycle waste in 1951. The tank received decontamination waste in 1952. The tank contained first cycle supernatant until 1954 when it was pumped to a ditch. The tank received in-plant ferrocyanide waste from 1954-1947. The tank contained U Plant uranium recovery process waste and coating waste from 1957-1958. The tank also received wastewater in 1957. The tank contained coating waste in 1968-1969. From 1969-1976, the tank was used for storage of evaporator bottoms waste. The tank contained concentrated evaporator feed bottoms waste from 1976-1967. Presently, the waste material is classified as non-complexed and has a total waste volume of 1,506,430 liters (398,000 gallons). Saltcake comprises 1,116,575 liters (295,000 gallons), sludge comprises 398,000 liters (103,000 gallons), and no supernatant. There is no pumpable liquid remaining and 34,065 liters (9,000 gallons) drainable liquid remaining.

Code: 241-BY-111	Classification: Accepted
Names: 241-BY-111; 241-BY-TK-111	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1952
Status: Inactive	End Date: 1/1/1977

Description: The unit is comprised of a carbon steel liner within a reinforced concrete shell, 11.3 meters (37 feet) high, with a capacity of 2,869,030 liters (758,000 gallons). The bottom of the unit is 13.7 meters (45 feet) below grade, and the dome is located below grade for shielding purposes. This type was built to the original design, having a dished bottom but with an increased operating depth of 7 meters (23 feet).

Location: The 241-BY Tank Farm is directly north of the 241-BX Tank Farm. The 241-BY-111 tank is located in the western portion of the 241-BY Tank Farm.

Waste Type: Storage Tank

Waste Description: The tank received bismuth phosphate metal waste; tributyl phosphate; PUREX coating waste; organic wash waste; and supernatant containing evaporator bottoms, tributyl phosphate waste, and organic wash waste from 241-BY and -C tanks. Presently, the waste material is classified as non-complexed and has a total waste volume of 1,737,315 liters (459,000 gallons). Saltcake comprises 1,657,830 liters (438,000 gallons), sludge comprises 79,485 liters (21,000 gallons), there is no drainable liquid or pumpable liquid remaining. Net total of liquids pumped from this tank is 1,185,462 liters (313,200 gallons).

Code: 241-BY-112	Classification: Accepted
Names: 241-BY-112; 241-BY-TK-112	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1951
Status: Inactive	End Date: 1/1/1976

Description: The unit is comprised of a carbon steel liner within a reinforced concrete shell, 11.3 meters (37 feet) high, with a capacity of 2,869,030 liters (758,000 gallons). The bottom of the unit is 13.7 meters (45 feet) below grade, and the dome is located below grade for shielding purposes. This type was built to the original design, having a dished bottom but with an increased operating depth of 7 meters (23 feet).

Location: The 241-BY Tank Farm is directly north of the 241-BX Tank Farm. The 241-BY-112 tank is

located in the northwestern portion of the 241-BY Tank Farm.

Waste Type: Storage Tank

Waste Description: The tank received bismuth phosphate metal waste; tributyl phosphate; supernatant containing tributyl phosphate; coating waste, and evaporator bottoms from 241-B, -BX, -BY, and -C tanks. Presently, the waste material is classified as non-complexed and has a total waste volume of 1,010,435 liters (291,000 gallons). Saltcake comprises 1,082,510 liters (286,000 gallons), sludge comprises 18,925 liters (5,000 gallons), there is no pumpable liquid remaining and 8,000 gallons (30,280 L) of drainable liquid remaining.

Code: 241-BY-ITS1 **Classification:** Accepted

Names: 241-BY-ITS1; In-Tank Solidification System; ITS-1 **Reclassification:** None

Type: Storage Tank **Start Date:** 1/1/1965

Status: Inactive **End Date:** 1/1/1974

Description: The system includes three vessels; the IX column, IX feed tank and the scrub solution circulation tank. Although portions of the equipment and ducting have been removed, the bulk of the off-gas equipment remains. It is enclosed in a locked chain link fence posted with a High Radiation Area sign. The facility is constructed primarily above-ground with some underground components.

Location: The ITS-1 system is located on the east side of the 241-BY tank farm. It is inside the tank farm fenced boundary.

Related Sites/ Structures: The system is associated with tanks 241-BY-101 and 241-BY-102 and pipeline 200-E-265-PL. 241-BY-ITS2 is discussed in sitecodes 200-E-59 and 200-E-60.

Process Description: The purpose of the In Tank Solidification System was to concentrate the waste in the underground storage tanks. Evaporation was achieved by sparging hot air into the tank waste solutions. The 241-BY tank farm is the only tank farm to include the operation of the in-tank solidification (ITS) system. The ITS 1 system was installed for tanks 241-BY-101 and 241-BY-102. Hot air was used to evaporate tank waste. The process condensate was drained to the 216-BY-201 flush tank and then disposed to cribs located north of 241-BY Tank Farm. Most of the components of the system have been removed. The remaining components include the de-entrainer, condenser, exhauster and ion exchanger containing zeolite resin. ITS-1 was later converted to a cooler for the ITS-2 system.

Code: 241-BYR-09A **Classification:** Accepted

Names: 241-BYR-09A; 241-BY-109 Valve Pit **Reclassification:** None

Type: Valve Pit **Start Date:** 1/1/1951

Status: Inactive **End Date:**

Description: The valve pit is an underground, concrete structure extending approximately 6.1 meters (20 feet) below ground surface.

Location: The valve pit is located inside the 241-BY Tank Farm, on the northwest side of the 241-BY-109 tank.

Process Description: The valve pit contained a pipe valve. The valve handle extended above the ground surface. It was installed as part of the uranium recovery operation project.

Code:	241-BYR-152	Classification:	Accepted
Names:	241-BYR-152; 241-BYR-152 Diversion Box	Reclassification	None
Type:	Diversion Box	Start Date:	1/1/1950
Status:	Inactive	End Date:	1/1/1984

Description: 241-BYR-152 is co-located in a series of three diversion boxes that are joined together. 241-BXR-152 is the center diversion box. 241-BR-152 Diversion Box is on the east end and 241-BYR-152 is on the west end of the diversion box group. The diversion boxes are underground cement structures. Their cover blocks and lifting bails are visible from the surface.

Location: Diversion Box 241-BYR-152 is located in the southeastern portion of the 241-BX Tank Farm, inside the tank farm fence. It is south of the 241-BX-101 tank.

Related Sites/ Structures: Diversion Box 241-BYR-152 is associated with the 241-BX Tank Farm and 241-BY Tank Farms and the 241-BXR-152 Diversion Box.

Process Description: Diversion Box 241-BYR-152 is constructed of concrete with a height of approximately 3.7 meters (12 feet). Approximately 0.3 meters (1 foot) of the diversion box concrete cover appears above grade. The outer dimensions are approximately 11 meters (36.1 feet) by 11.5 meters (37.8 feet). The structure's cover is in sections consisting of several interlocking pre-formed concrete blocks. Diversion boxes and receiving vaults drain to catch tanks or single-shell tanks.

Waste Type: Process Effluent

Waste Description: This unit was used for the transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operation. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Code:	241-BYR-153	Classification:	Accepted
Names:	241-BYR-153; 241-BYR-153 Diversion Box	Reclassification	None
Type:	Diversion Box	Start Date:	1/1/1950
Status:	Inactive	End Date:	1/1/1984

Description: The diversion boxes are underground concrete structures. Their cover blocks and lifting bails are visible from the surface. The 241-BYR-153 Diversion box is co-located with the 241-BXR-153 Diversion Box. 241-BYR-153 is on the west side of the 241-BXR-153 Diversion Box.

Location: Diversion Box 241-BYR-153 is located in the southern portion of the 241-BX Tank Farm, inside the tank farm fence. It is south of the 241-BX-104 tank.

Related Sites/ Structures: Diversion Box 241-BYR-153 is associated with the 241-BX and 241-BY Tank Farms.

Process Description: Diversion boxes and receiving vaults drain to catch tanks or single-shell tanks. Diversion Box 241-BYR-153 is constructed of concrete with a height of approximately 3.7 meters (12 feet). Approximately 0.3 meters (1foot) of the diversion box concrete cover appears above grade. The outer dimensions are approximately 11.3 meters (37 feet) by 10.5 meters (34.5 feet). The structure's cover is in sections consisting of several interlocking pre-formed concrete blocks. The northern section consists of 10 blocks, center section has 11, and the southern section has 8 cover blocks.

Waste Type: Process Effluent

Waste Description: This unit was used for transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operation. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Code: 241-BYR-154 **Classification:** Accepted
Names: 241-BYR-154; 241-BYR-154 Diversion Box **Reclassification:** None
Type: Diversion Box **Start Date:** 1/1/1950
Status: Inactive **End Date:** 1/1/1984

Description: The diversion box is an underground concrete structure. Its cover blocks and lifting bails are visible from the surface.

Location: Diversion Box 241-BYR-154 is located in the southwestern portion of the 241-BX Tank Farm, inside the tank farm fence. It is south of the 241-BX-110 tank.

Related Sites/ Structures: Diversion Box 241-BYR-154 interconnects with the following: 241-BY Tank Farm.

Process Description: Diversion Box 241-BYR-154 is constructed of concrete with a height of approximately 3.7 meters (12 feet). Approximately 0.3 meters (1 foot) of the diversion box concrete cover appears above grade. While the outer dimensions are approximately 9.9 meters (32.5 feet) by 9.9 meters (32.5 feet), the structure's shape is irregular because the north section of the diversion box is short by 2.7 meters (9 feet) and the south side is short by 4.1 meters (13.5 feet). The structure's cover is in sections consisting of several interlocking pre-formed concrete blocks. The northern section consists of 10 blocks, center section has 9, and the southern section has 4 cover blocks. Diversion boxes and receiving vaults drain to catch tanks or single-shell tanks.

Waste Type: Process Effluent

Waste Description: This unit was used for the transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operation. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Code: 200-E-59 **Classification:** Accepted
Names: 200-E-59; 241-BY-ITS2 Condenser Vessel; 241-BY-ITS2-TK-1; ITS-2 **Reclassification:** None
Type: Storage Tank **Start Date:** 1/1/1968
Status: Inactive **End Date:** 1/1/1977

Description: The above ground components have been removed. This tank was abandoned in place. The tank is surrounded with a metal fence with IMUST signs.

Location: The In Tank Solidification (ITS 2) system tank is located inside the 241-BY Tank Farm. The tank is inside the 241-BY-112 Tank Sluice Pit in the northwest portion of the tank farm.

Related Sites/ Structures: The tank is associated with tanks 241-BY-111 and 241-BY-112, and the ITS-2 System (In-Tank Solidification), sitecode 200-E-60 Heater Flush Tank and Sitecode 241-BY-ITS1. The system is associated with pipeline 200-E-265-PL.

Process Description: The 241-BY tank farm is the only tank farm to include the operation of the in-tank solidification (ITS) system. ITS-2 was first installed in tanks 241-BY-111 and 241-BY-112. It was later extended to the remaining 241-BY tanks. The tank received condensate from the

heated in-ground waste tank for return to the 241-BY-112 tank. The ITS-2 system used electric immersion heaters.

The most notable difference between the BY tank farm and the other SST facilities is the placement and operation of the in-tank solidification (ITS) system in the tank farm. ITS-1, which used heated air circulated through tank waste, was installed for tanks BY-101 and BY-102. This system began operation in 1965. ITS-2, using an in-tank heater, was installed first in tanks BY-111 and BY-112 and began operation in 1968. ITS-2 was extended to the remaining BY tanks by 1971 and ITS-1 was converted to a cooler for ITS-2. The ITS Process was superseded by salt-well pumping and was shut down in 1974.

Waste Type: Equipment

Waste Description: The abandoned tank is considered to be the waste. The current contents of the tank is not known.

Code: 200-E-60	Classification: Accepted
Names: 200-E-60; 241-BY-ITS2 Heater Flush Tank; 241-BY-ITS2-TK-2; ITS-2	Reclassification: None
Type: Storage Tank	Start Date: 1/1/1968
Status: Inactive	End Date: 1/1/1977

Description: The above ground components have been removed and the tank was abandoned in place. The tank is inside a concrete pit with a metal cover, surrounded with a metal fence with IMUST signs.

Location: The flush tank is located inside 241-BY Tank Farm, between tank 241-BY-111 and 241-BY-112.

Related Sites/ Structures: The Heater Flush Tank is associated with 200-E-59, the 241-BY-ITS2 Condenser Vessel.

Process Description: The 241-BY tank farm is the only tank farm to include the operation of the in-tank solidification (ITS) system. ITS-2 used an in-tank heater. The flush tank was used as a decontamination solution receiver tank for the decontamination of in-tank heater assemblies in the ITS-2 system. It is constructed of carbon steel and is encased in a two piece caisson. The upper section of the caisson is 122 centimeters (48 inches) in diameter and extends 5.17 meters (17 feet) below the surface. The lower section is 118 centimeters (46.5 inches) in diameter extending to the bottom of the flush tank.

The most notable difference between the BY tank farm and the other SST facilities is the placement and operation of the in-tank solidification (ITS) system in the tank farm. ITS-1, which used heated air circulated through tank waste, was installed for tanks BY-101 and BY-102. This system began operation in 1965. ITS-2, using an in-tank heater, was installed first in tanks BY-111 and BY-112 and began operation in 1968. ITS-2 was extended to the remaining BY tanks by 1971 and ITS-1 was converted to a cooler for ITS-2. The ITS Process was superseded by salt-well pumping and was shut down in 1974.

Waste Type: Storage Tank

Waste Description: The chemical and radiological contents are not known, but the composition of any residual material is expected to consist of the same material in the heated waste tank.

Code: 200-E-120	Classification: Accepted
------------------------	---------------------------------

Names: 200-E-120; Contaminated Soil at 241-B Tank Farm; Contamination Migration Beyond the 241-B fence **Reclassification** None

Type: Contamination Migration **Start Date:** 1/1/1944

Status: Inactive **End Date:** 1/1/1999

Description: The site is the soil inside and adjacent to the chain link fence that surrounds the 241-B Tank Farm. Various radiological postings and warning signs are attached to the chain link fence. The interior of the tank farm complex is covered with gravel. Many risers and monitoring devices for the underground structures are visible on the surface. The individual unplanned releases associated with the 241-B Tank Farm are not separately marked or posted. Occasionally, radioactive contamination is found adjacent to the outside of the tank farm fence, resulting in a contamination zone extension around the tank farm perimeter. These areas will also be considered tank farm soil. A posted Contamination Area, marked with steel posts and chain, currently extends east and south outside the 241-B Tank Farm fence. The posted area size and shape varies with additional radiological surveys.

Location: The site is located east of Baltimore Ave. and south of 12th Street in 200 East Area.

Release Description: The exact extent (horizontal and vertical) of the soil contaminated by unplanned releases that occurred within this farm over the years are not known. Some of the single shell tanks have leaked to the soil below the tank farm. Other releases spread contamination to the surface soil surrounding the tanks.

Related Sites/ Structures: Unplanned Releases UPR-200-E-4, UPR-200-E-6, UPR-200-E-38, UPR-200-E-73, UPR-200-E-74, UPR-200-E-75, UPR-200-E-76, UPR-200-E-108, UPR-200-E-109, UPR-200-E-127, UPR-200-E-128, UPR-200-E-129, and UPR-200-E-130 are associated with the 241-B Tank Farm. Two of these sites are listed in TPA Appendix B as TSD-associated sites (UPR-200-E-76 and UPR-200-E-109). All are to be addressed with the closeout of the tank farm TSD. As such, site 200-E-120 is also a TSD-associated site.

Waste Type: Soil

Waste Description: Liquid releases occurred from underground leaks in tanks and transfer lines. Airborne contamination spreads occurred from activities conducted in valve pits and diversion boxes. Both types of releases contributed to the contamination in the soil.

Code: 200-E-132 **Classification:** Accepted

Names: 200-E-132; 241-BX/BY Tank Farm Contaminated Soil; Contamination Migration Beyond the 241-BX/BY fence **Reclassification** None

Type: Contamination Migration **Start Date:** 1/1/1948

Status: Inactive **End Date:**

Description: The site is the soil inside and adjacent to the chain link fence that surrounds the 241-BX/BY Tank Farms. Various radiological postings and warning signs are attached to the chain link fence. The interior of the tank farm complex is covered with gravel. Many risers and monitoring devices for the underground structures are visible on the surface. The individual unplanned releases associated with the 241-BX/BY Tank Farms are not separately marked or posted. Occasionally, radioactive contamination is found adjacent to the outside of the tank farm fence, resulting in a contamination zone extension around the tank farm perimeter. These areas will also be considered tank farm soil. A steep slope is located adjacent to the north and northeast sides of the 241-BY Tank Farm. The contaminated slope has been stabilized with cobble and gravel. The slope is considered part of the tank farm perimeter.

Location: The 241-BX/BY Tank Farm complex is located south of 12th Street and west of Baltimore Ave., inside 200 East Area.

Release Description: The exact extent (horizontal and vertical) of the soil contaminated by unplanned releases that occurred within this farm complex over the years are not known. Some of the single shell tanks have leaked to the soil below the tank farm. Other releases spread contamination to the surface soil surrounding the tanks.

Related Sites/Structures: Previously reported unplanned releases that were identified in WIDS and located inside the 241-BX/BY Tank Farm Complex are UPR-200-E-5, UPR-200-E-135, UPR-200-E-134, UPR-200-E-133, UPR-200-E-132, UPR-200-E-131, UPR-200-E-116, UPR-200-E-110, and UPR-200-E-105. Site UPR-200-E-105 is listed in TPA Appendix B as a TSD-associated site. All the sites are to be addressed with the closeout of the tank farm TSD. As such, site 200-E-132 is also a TSD-associated site.

Waste Type: Process Effluent

Waste Description: Liquid releases occurred from underground leaks in tanks and transfer lines. Airborne contamination spreads occurred from activities conducted in valve pits and diversion boxes. Both types of releases contributed to the contamination in the soil.

Code: 200-E-197-PL **Classification:** Accepted

Names: 200-E-197-PL; Encased Pipelines Between 241-BR-152 Diversion Box and 241-B Tank Farm; Lines 9002, 9006, 9010, 9014, 9017, 9020, 9031, 9032, 9035, 9037, 9038, 9041, 9044 and 9047 **Reclassification:** None

Type: Encased Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground concrete transfer line encasement. Fourteen 10 centimeter (6 inch) diameter, carbon steel lines are located within the same concrete encasement. They are placed with seven lines on the bottom of the encasement and seven lines above those lines within the concrete encasement.

Location: The pipeline extends from 241-BR-152 Diversion Box, inside 241-BX Tank Farm to the 241-B-101, 241-B-102 and 241-B-103 tanks inside 241-B Tank Farm.

Related Sites/Structures: The waste lines are associated with 241-BR-152 diversion Box, 241-B-101, 241-B-102 and 241-B-103 single shell tanks.

Code: 200-E-208-PL **Classification:** Accepted

Names: 200-E-208-PL; Lines V304 and V305 from 241-BY Tank Farm to 241-B-252 Diversion Box **Reclassification:** None

Type: Direct Buried Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is two underground, 10 centimeter (4 inch) diameter, carbon steel lines buried in the same soil trench.

Location: The lines extend out of the north side of the 241-BY Tank Farm, turn south on the west side of Baltimore Ave. and cross under Baltimore Ave. to connect to the 241-B-252 Diversion Box, located inside the 241-B Tank Farm.

Related Sites/ Structures: The lines are associated with tanks 241-BY-109 and 241-BY-111 and 241-B-252 Diversion Box.

Code: 200-E-216-PL **Classification:** Accepted
Names: 200-E-216-PL; Lines V235, V236, V237, V242, C251, V252, and V253; Transfer Lines Between 241-BX-153, 241-B-151 and 241-B-152 Diversion Boxes **Reclassification:** None
Type: Direct Buried Tank Farm Pipeline **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is seven stainless steel lines that are buried in the same soil trench. All of the lines are 9 centimeter (3.5 inch) diameter lines.

Location: The transfer lines are located southeast of 241-BX Tank Farm. The lines exit the southeast corner of 241-BX Tank Farm and cross under Baltimore Ave. to connect to the diversion boxes inside 241-B Tank Farm. The lines branch off, forming a "V". Lines V251, V252, V253 and V242 go to the 241-B-152 Diversion Box. Lines V235, V236 and V237 go to the 241-B-151 Diversion Box (see subsites).

Related Sites/ Structures: The transfer lines are associated with the 241-BX-153 Diversion Box, located inside 241-BX Tank Farm and 241-B-151 and 241-B-152 Diversion Boxes, located inside 241-B Tank Farm.

This Site has the Following SubSites:

Code: 200-E-216-PL:1
Names: 200-E-216-PL:1; Portion of Soil Trench Containing All Seven Lines (V235, V23, V237, V251, V252, V253 and V242)
Code: 200-E-216-PL:2
Names: 200-E-216-PL:2; Northern Portion of Soil Trench Containing Lines V235, V236 and V237
Code: 200-E-216-PL:3
Names: 200-E-216-PL:3; Southern Portion of Soil Trench Containing Lines V251, V252, V253 and V242

Code: 200-E-216-PL:1 **Classification:** Accepted
Names: 200-E-216-PL:1; Portion of Soil Trench Containing All Seven Lines (V235, V23, V237, V251, V252, V253 and V242) **Reclassification:** None
Type: Direct Buried Tank Farm Pipeline **Start Date:**
Status: Inactive **End Date:**

Description: Subsite 1 is the portion of the group of lines exiting the 241-BX Tank Farm where all seven lines are in the same soil trench.

The SubSite is Part Of:

Code: 200-E-216-PL
Names: 200-E-216-PL; Lines V235, V236, V237, V242, C251, V252, and V253; Transfer Lines Between 241-BX-153, 241-B-151 and 241-B-152 Diversion Boxes

Code: 200-E-216-PL:2 **Classification:** Accepted
Names: 200-E-216-PL:2; Northern Portion of Soil Trench Containing Lines V235, V236 and V237 **Reclassification:** None
Type: Direct Buried Tank Farm Pipeline **Start Date:**
Status: Inactive **End Date:**

Description: Subsite 2 is the northern portion of the split soil trench containing lines V235, V236 and V237 that connects to the 241-B-151 Diversion Box.

The SubSite is Part Of:

Code: 200-E-216-PL
Names: 200-E-216-PL; Lines V235, V236, V237, V242, C251, V252, and V253; Transfer Lines Between 241-BX-153, 241-B-151 and 241-B-152 Diversion Boxes

Code: 200-E-216-PL:3 **Classification:** Accepted
Names: 200-E-216-PL:3; Southern Portion of Soil Trench Containing Lines V251, V252, V253 and V242 **Reclassification:** None
Type: Direct Buried Tank Farm Pipeline **Start Date:**
Status: Inactive **End Date:**

Description: Subsite 3 is the southern portion of the split soil trench containing lines V251, V252, V253 and V242 that connects to the 241-B-152 Diversion Box.

The SubSite is Part Of:

Code: 200-E-216-PL
Names: 200-E-216-PL; Lines V235, V236, V237, V242, C251, V252, and V253; Transfer Lines Between 241-BX-153, 241-B-151 and 241-B-152 Diversion Boxes

WMA C

Code: 216-C-8 **Classification:** Accepted

Names: 216-C-8; 216-C-8 Crib; 216-C-8 French Drain; 271-CR Crib **Reclassification:** None

Type: French Drain **Start Date:** 6/1/1962

Status: Inactive **End Date:** 6/1/1965

Description: In June 2001, the area was covered with gravel during road construction in the vicinity of 7th Street and Buffalo Ave. The crib was not re-marked. In 2006, only a single post and sign marked the crib. The pipeline that fed 216-C-8 is WIDS sitecode 200-E-290-PL.

Location: The site is located southeast of the 241-C Tank Farm, outside the tank farm perimeter fence.

Related Sites/Structures: The site is associated with the 271-CR building and pipeline 200-E-290-PL.

Process Description: The site received radioactively contaminated ion exchange waste from the 271-CR Building. The waste site is composed of a 1.8-meter (6-foot) diameter, 2.4-meter (8-foot) long concrete culvert, placed vertically into the ground. The top of the structure is 1.2 meters (4 feet) below grade. It was placed into a 2.4-meter (8-foot) diameter by 4.9-meter (16-foot) deep excavation. A 5 centimeter (2 inch) diameter steel vent pipe was placed vertically through the center of the culvert and extended 1 meter (3 feet) above the surface. The culvert is filled with gravel. An underground feed pipe entered near the top of the culvert.

Waste Type: Process Effluent

Waste Description: The site received the ion exchange waste from the 271-CR Building. The waste volume is unknown. The site contains less than 10 curies total beta.

Code: 241-C-101 **Classification:** Accepted

Names: 241-C-101; 241-C-TK-101 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1946

Status: Inactive **End Date:** 1/1/1970

Description: The tank is an underground, steel tank with a cylindrical reinforced-concrete wall that rests on a reinforced-concrete cylindrical footing. The footing gradually tapers to a reinforced-concrete basemat foundation. The basemat foundation is dished-shaped and lined with a layer of grout and a layer of asphaltic waterproofing membrane. A steel liner lines the bottom and sidewall of the tank.

Location: The 241-C-101 tank in the eastern portion of the 241-C Tank Farm.

Related Sites/Structures: Four monitoring drywells are identified for this tank. Additionally this tank is equipped with pumps, thermocouples and other ancillary equipment. This tank cascades to 241-C-102. Nine risers are associated with the tank.

Process Description: The 241-C-101 tank received bismuth phosphate metal waste, tributyl phosphate process waste, and PUREX process coating waste from tank 241-C-106, which had high levels of strontium in the waste. From 1952 to 1955 the tank was sluiced to recover uranium that had been discharged as waste.

Waste Type: Storage Tank

Waste Description: This tank contains bismuth phosphate metal waste, tributyl phosphate waste, and PUREX coating waste. Document WHC-SD-WM-ER-349 references the most complete estimated inventory for this tank. Because this tank was the first tank in a cascading series, most of the solids precipitated out of the solutions into this tank.

Code: 241-C-102 **Classification:** Accepted

Names: 241-C-102; 241-C-TK-102 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1946

Status: Inactive **End Date:** 1/1/1976

Description: The tank is an underground steel tank with a cylindrical reinforced-concrete wall that rests on a reinforced-concrete cylindrical footing. The footing gradually tapers to a reinforced-concrete basemat foundation. The basemat foundation is dished-shaped and lined with a layer of grout and a layer of asphaltic waterproofing membrane. A steel liner lines the bottom and sidewall of the tank.

Location: The 241-C-102 tank is located in the eastern portion of the 241-C tank Farm.

Related Sites/ Structures: Structures associated with this tank includes, saltwater pump system, tank monitoring instrumentation, and waste cascade tanks (241-C-103) and piping.

Process Description: Tank 241-C-102 is the second tank in the 241-C-101, 241-C-102, and 241-C-103 cascade line. These tanks received 221-B Building bismuth phosphate process waste. Later, this tank received small amounts from Semiworks (201-C) and the Critical Mass Laboratory, as well as Uranium Recovery and PUREX process wastes.

Waste Type: Storage Tank

Waste Description: This tank received bismuth phosphate metal waste, tributyl phosphate waste, PUREX coating waste, high-level waste, PUREX organic wash waste, supernatant containing organic wash wastes and coating wastes from the 241-A, -AX, and -C Tanks.

Code: 241-C-103 **Classification:** Accepted

Names: 241-C-103; 241-C-TK-103 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1946

Status: Inactive **End Date:** 1/1/1979

Description: The tank is an underground steel tank with a cylindrical reinforced-concrete wall that rests on a reinforced-concrete cylindrical footing. The footing gradually tapers to a reinforced-concrete basemat foundation. The basemat foundation is dished-shaped and lined with a layer of grout and a layer of asphaltic waterproofing membrane. A steel liner lines the bottom and sidewall of the tank.

Location: The 241-C-103 tank is located in the northeastern corner of 241-C Tank Farm.

Release Description: In 2008, the Hanford C-Farm Leak Assessment Report (RPP-ENV-33418) was issued. It documented failed pipelines and unplanned releases associated with C Farm activities. In 1965, a liquid level rise in the 241-C-103 cesium feed tank was apparently caused by a failed line in the encasement between the 241-CR-152 diversion box and 241-C-102. This permitted coating waste from the Purex Plant to leak into the encasement and drain to Tanks 241-C-101, 241-C-102 and 241-C-103 via the tank pump pits. Coating waste was routed through a spare line to 241-C-102 and no further leaks were detected. The coating waste solution accumulated in 241-C-103 did not significantly affect cesium loading capability as a cask was loaded normally

following the incident.

Related Sites/ Structures: Structures associated with this tank include 5 drywells, tank monitoring instrumentation, tank risers, the three other tanks in this waste cascading series, and associated piping.

Process Description: Tank 241-C-103 is the third tank in the 241-C-101, 241-C-102, 241-C-103 cascade line. These tanks largely received waste from the B Plant bismuth phosphate process. Additional waste was received from the semi-works and the critical mass laboratory. Later waste received by the tank was generated by PUREX and U Plant.

Waste Type: Storage Tank

Waste Description: This tank has waste from the following process: PUREX coating waste, tributyl phosphate waste, coating waste, PUREX high-level waste, B Plant high-level waste, B Plant waste fractionization low-level waste, PUREX sludge supernatant, PUREX low-level waste, waste fractionization PUREX sludge, PUREX organic wash waste, laboratory waste, decontamination waste, REDOX ion exchange waste, REDOX high-level waste, noncomplexed waste, waste fractionization ion exchange waste, N Reactor waste, PNL waste, and evaporator bottoms from 241-A -B, -BX, and -C tank farms. This unit was used as the receiver for operating P-10 saltwell systems within the 241-C Tank Farm. An additional source of waste is PUREX and insoluble strontium-rich sluicing solids from the operation of 244-CR Vault.

Code: 241-C-103 VP **Classification:** Accepted

Names: 241-C-103 VP; 241-C Valve Pit; 241-C-103 Valve Pit **Reclassification:** None

Type: Valve Pit **Start Date:** 1/1/1979

Status: Inactive **End Date:**

Description: The waste site is an underground corrugated metal structure.

Location: The valve pit is located inside 241-C tank farm, on the southwest side of the 241-C-103 tank.

Process Description: The valve pit was installed as part of the C Farm tank waste interim stabilization salt well system.

Code: 241-C-104 **Classification:** Accepted

Names: 241-C-104; 241-C-TK-104 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1946

Status: Inactive **End Date:** 1/1/1980

Description: The underground tank is constructed with a cylindrical reinforced-concrete wall that rests on a reinforced-concrete cylindrical footing. The footing gradually tapers to a reinforced-concrete basemat foundation. The basemat foundation is dished-shaped and lined with a layer of grout and a layer of asphaltic waterproofing membrane. A steel liner lines the bottom and sidewall of the tank.

Location: Tank 241-C-104 is located in the southern row of tanks, inside the 241-C Tank Farm.

Related Sites/ Structures: Tank 241-C-104 is the first tank in the 241-C-104, 241-C-105, and 241-C-106 cascade line. Other associated structures include ventilation, monitoring drywells, instrumentation, and piping.

Process Description: This tank was sluiced during the 1952 to 1955 uranium recovery sluicing operation. During 1954, this tank was used as a tank-to-tank sluicing receiver. This waste was later sent to the 244-CR process vault. The tank began receiving bismuth phosphate metal waste in 1946.

Waste Type: Storage Tank

Waste Description: Waste is comprised of unknown waste, sludge, and pumpable liquid. This tank received bismuth phosphate metal waste starting in 1946, strontium-leached sluicing solids in 1977, and fissile material (including uranium-223) from PUREX thorium campaigns.

Code: 241-C-105	Classification: Accepted
Names: 241-C-105; 241-C-TK-105	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1946
Status: Inactive	End Date: 1/1/1979

Description: The underground tank is constructed with a cylindrical reinforced-concrete wall that rests on a reinforced-concrete cylindrical footing. The footing gradually tapers to a reinforced-concrete basemat foundation. The basemat foundation is dished-shaped and lined with a layer of grout and a layer of asphaltic waterproofing membrane. A steel liner lines the bottom and sidewall of the tank.

Location: Tank 241-C-105 is located near the center of the 241-C Tank Farm.

Related Sites/ Structures: The tank is associated with Radiation monitoring wells, 8 active; Operating exhauster; Temperature element, read manually; Liquid level gage, and automatic on CASS.

Process Description: As part of the 241-C-104, 241-C-105, 241-C-106 cascade line, this tank received bismuth phosphate metal waste from 1947 until 1953. This tank was used as a receiver for PUREX sludge supernate enroute to B Plant for cesium ion exchange processing. This tank was sluiced during 1952 and 1953 for the uranium recovery program.

Waste Type: Storage Tank

Waste Description: This tank was used as a receiver tank for PUREX sludge supernate enroute to B Plant. It received bismuth phosphate metal waste from 1947 to 1953. The tank contains unknown waste, sludge, and pumpable liquid.

Code: 241-C-106	Classification: Accepted
Names: 241-C-106; 241-C-TK-106	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1947
Status: Inactive	End Date: 1/1/1979

Description: The underground tank is constructed with a cylindrical reinforced-concrete wall that rests on a reinforced-concrete cylindrical footing. This footing gradually tapers to a reinforced-concrete basemat foundation. The basemat foundation is dished shaped and lined with a layer of grout and a layer of asphaltic waterproofing membrane. A partial spherical shell dome rests on the cylindrical wall. A steel liner lines the bottom and sidewall of the tank. The operating depth for this tank is 5.2 meters (17 feet).

Location: The tank is located in the northeastern portion of the 241-C Tank Farm.

Related Sites/ Structures: Associated structures for 241-C-106 include monitoring equipment, cascade piping and tanks, ventilation and drywells.

Process Description: This tank is the last tank in the 241-C-104, 241-C-105 and 241-C-106 cascade. One of the first generation tanks, this unit was designed to receive non-boiling waste. Tank 241-C-106 received bismuth phosphate metal waste in 1947. The tank was sluiced from 1952 to 1955 for uranium recovery efforts.

Waste Type: Storage Tank

Waste Description: This tank received bismuth phosphate metal waste, and PUREX process fission product waste, which included large amounts of strontium. The tank was sluiced in 1952 -1955 for the uranium recovery project. The waste contains process supernate, unknown waste products, sludge, and pumpable liquid.

Code: 241-C-107	Classification: Accepted
Names: 241-C-107; 241-C-TK-107	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1946
Status: Inactive	End Date: 1/1/1978

Description: The underground tank is constructed with a cylindrical reinforced-concrete wall that rests on a reinforced-concrete cylindrical footing. This footing gradually tapers to a reinforced-concrete basemat foundation. The basemat foundation is dished shaped and lined with a layer of grout and a layer of asphaltic waterproofing membrane. A partial spherical shell dome rests on the cylindrical wall. A steel liner lines the bottom and sidewall of the tank. The operating depth for this tank is 5.2 meters (17 feet).

Location: The 241-C-107 tank is located in the northwestern portion of the 241-C Tank Farm.

Related Sites/ Structures: Structures associated with this tank include other tanks in the cascade, piping and pumps, instrumentation, and ventilation.

Process Description: This is the first tank in the 241-C-107, 241-C-108, 241-C-109 cascade line, designed to receive non-boiling waste. Tank 241-C-107 received first cycle waste and process decontamination wastes from B Plant. This tank also received insoluble, strontium-leached sluicing solids.

Waste Type: Storage Tank

Waste Description: This tank received Bismuth Phosphate first cycle waste beginning in 1946. The tank received insoluble strontium leached, sluicing solids in 1977. This unit is a low-heat load, passively ventilated tank.

Code: 241-C-108	Classification: Accepted
Names: 241-C-108; 241-C-TK-108	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1947
Status: Inactive	End Date: 1/1/1977

Description: The underground tank is constructed with a cylindrical reinforced-concrete wall that rests on a reinforced-concrete cylindrical footing. This footing gradually tapers to a reinforced-concrete basemat foundation. The basemat foundation is dished shaped and lined with a layer of grout and a layer of asphaltic waterproofing membrane. A partial spherical shell dome rests on the cylindrical wall. A steel liner lines the bottom and sidewall of the tank. The operating depth for this tank is 5.2 meters (17 feet).

Location: Tank 241-C-108 is located near the center of the 241- C Tank Farm.

Related Sites/ Structures: Structures associated with this tank include cascade piping, tanks 241-C-107, and 241-C-109, dry wells, instrumentation, and ventilation.

Process Description: Tank 241-C-108 was designed as the second tank of the 241-C-107, 241-C-108, 241-C-109 cascade series. It received non-boiling, cascade overflow from tank 241-C-107. Wastes received by this tank include first cycle waste, and process decontamination waste from B Plant. The tank also acted as a primary settling tank for "In-Farm" waste scavenging for the Uranium Recovery process.

Waste Type: Storage Tank

Waste Description: Tank 241-C-108 received cascade overflow from tank 241-C107 in 1947. This tank was also used as a primary settling tank for "In-Farm" scavenging for the Uranium Recovery process. This tank is on the ferrocyanide watch list. Waste is composed entirely of sludge, with no pumpable liquid.

Code: 241-C-109	Classification: Accepted
Names: 241-C-109; 241-C-TK-109	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1948
Status: Inactive	End Date: 1/1/1978

Description: The underground tank is constructed with a cylindrical reinforced-concrete wall that rests on a reinforced-concrete cylindrical footing. This footing gradually tapers to a reinforced-concrete basemat foundation. The basemat foundation is dished shaped and lined with a layer of grout and a layer of asphaltic waterproofing membrane. A partial spherical shell dome rests on the cylindrical wall. A steel liner lines the bottom and sidewall of the tank. The operating depth for this tank is 5.2 meters (17 feet).

Location: The 241-C-109 tank is located in the northeastern portion of the 241-C Tank Farm.

Related Sites/ Structures: This tanks associated structures include six drywells, piping, instrumentation, and the rest of this cascade system.

Process Description: Tank 241-C-109 is the third tank of the cascade series. It received non-boiling cascade overflow from tank 241-C-108. Wastes received by this tank include bismuth phosphate first cycle waste and process decontamination waste from B Plant. The tank acted as a primary settling tank for "in farm" scavenging for the Uranium Recovery process.

Waste Type: Storage Tank

Waste Description: Tank 241-C-109 was receiving cascade overflow (B Plant first-cycle waste and decontamination waste) from tank 241-C-108 in 1948. This tank was also used as a primary settling tank for "in farm" scavenging for the Uranium Recovery process. This tank is on the ferrocyanide watch list. In 1994 the tank was described as containing unknown waste and sludge, with no saltcake or pumpable liquid remaining.

Code: 241-C-110	Classification: Accepted
Names: 241-C-110; 241-C-TK-110	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1946
Status: Inactive	End Date: 1/1/1976

Description: The underground tank was constructed with a cylindrical reinforced-concrete wall that rests on a reinforced-concrete cylindrical footing. This footing gradually tapers to a reinforced-concrete

basemat foundation. The basemat foundation is dished shaped and lined with a layer of grout and a layer of asphaltic waterproofing membrane. A partial spherical shell dome rests on the cylindrical wall. A steel liner lines the bottom and sidewall of the tank. The operating depth for this tank is 5.2 meters (17 feet).

Location: Tank 241-C-110 is located in the southwestern portion of 241-C Tank Farm.

Release Description: This tank is an assumed leaker, with a loss of 2,000 gallons (7,600 liters).

Related Sites/ Structures: Associated structures with this tank include four dry wells, instrumentation the two other tanks in the cascade series, piping, and ventilation.

Process Description: This tank is the first tank in the 241-C-110, 241-C-111, 241-C-112 cascade line. It was designed to receive non-boiling waste. The tank received bismuth phosphate first cycle waste from 1946 to 1967. Tanks 241-C-108, 241-C-109, 241-C-110, 241-C-111, and 241-C-112 were also used as primary settling tanks for "In-Farm" scavenging for the Uranium Recovery process.

Waste Type: Storage Tank

Waste Description: Tank 241-C-110 is the first tank in the 241-C-110, 241-C-111, and 241-C-112 cascade line. This tank received bismuth phosphate first cycle waste and process decontamination waste from B Plant. Additionally, this tank was used as a primary settling tank for "In-Farm" scavenging for the Uranium Recovery process.

Code: 241-C-111

Classification: Accepted

Names: 241-C-111; 241-C-TK-111

Reclassification: None

Type: Single-Shell Tank

Start Date: 1/1/1946

Status: Inactive

End Date: 1/1/1978

Description: The underground tank is constructed with a cylindrical reinforced-concrete wall that rests on a reinforced-concrete cylindrical footing. This footing gradually tapers to a reinforced-concrete basemat foundation. The basemat foundation is dished shaped and lined with a layer of grout and a layer of asphaltic waterproofing membrane. A partial spherical shell dome rests on the cylindrical wall. A steel liner lines the bottom and sidewall of the tank. The operating depth for this tank is 5.2 meters (17 feet).

Location: The 241-C-111 tank is located on the western side of the 241-C Tank Farm.

Related Sites/ Structures: Associated with this tank include five dry wells, instrumentation, the two other tanks in the cascade series, piping, and ventilation.

Process Description: This tank is the second tank in the 241-C-110, 241-C-111, 241-C-112 cascade line. It was designed to receive non-boiling waste. The tank received bismuth phosphate first cycle waste beginning in 1946. Tanks 241-C-108, 241-C-109, 241-C-110, 241-C-111, and 241-C-112 were also used as primary settling tanks for "In-Farm" scavenging for the Uranium Recovery process.

Waste Type: Storage Tank

Waste Description: Tank 241-C-111 is the second tank in the 241-C-110, -111, and -112 cascade line. This tank received bismuth phosphate first cycle waste and B Plant decontamination waste. Additionally, this tank was used as a primary settling tank for "In-Farm Scavenged Uranium". There is no pumpable liquid remaining in the tank.

Code: 241-C-112

Classification: Accepted

Names: 241-C-112; 241-C-TK-112

Reclassification None

Type: Single-Shell Tank

Start Date: 1/1/1946

Status: Inactive

End Date: 1/1/1976

Description: The underground tank is constructed with a cylindrical reinforced-concrete wall that rests on a reinforced-concrete cylindrical footing. This footing gradually tapers to a reinforced-concrete basemat foundation. The basemat foundation is dished shaped and lined with a layer of grout and a layer of asphaltic waterproofing membrane. A partial spherical shell dome rests on the cylindrical wall. A steel liner lines the bottom and sidewall of the tank. The operating depth for this tank is 5.2 meters (17 feet).

Location: The 241-C-112 tank is located in the northwestern portion of 241-C Tank Farm.

Related Sites/ Structures: Associated structures include four dry wells, instrumentation, the two other tanks in the cascade series, piping, and ventilation.

Process Description: This tank is the third tank in the 241-C-110, -111, -112 cascade line, and was designed to receive non boiling waste. The tank received bismuth phosphate first cycle waste starting in 1976. Tanks -108, -109, -110, and -112 were also used as primary settling tanks for "In-Farm Scavenged Uranium".

Waste Type: Storage Tank

Waste Description: Tank 241-C-112 is the third tank in the 241-C-110, 241-C-111, and 241-C-112 cascade line. This tank received bismuth phosphate first cycle waste and process decontamination waste from B Plant. Additionally, this tank was used as a primary settling tank for "In-Farm" scavenging for the Uranium Recovery process.

Code: 241-C-151

Classification: Accepted

Names: 241-C-151; 241-C-151 Diversion Box

Reclassification None

Type: Diversion Box

Start Date: 1/1/1946

Status: Inactive

End Date: 1/1/1985

Description: The diversion box is an underground, reinforced concrete structure. Surface features include concrete coverblocks with lifting bails.

Location: The 241-C-151 Diversion Box is located in the southwestern portion of the 241-C Tank Farm.

Related Sites/ Structures: This diversion box is associated with the 241-C Tank Farm and the soil described in sitecode 200-E-133. It is connected to the 241-C-152 and 241-C-153 diversion boxes.

Process Description: Diversion boxes and receiving vaults drain to catch tanks. They are designed to contain leaks and spills from waste transfers and drainage during jumper operations within the unit.

Waste Type: Process Effluent

Waste Description: This unit was used to transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operations. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box. Radiological contamination is estimated to be high in alpha, beta, and gamma.

Waste Type: Chemicals

Waste Description: This unit was used to transfer waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operations. Chemical residues may be present. Radiological contamination is estimated to be high in alpha, beta, and gamma.

Code: 241-C-152	Classification: Accepted
Names: 241-C-152; 241-C-152 Diversion Box	Reclassification: None
Type: Diversion Box	Start Date: 1/1/1946
Status: Inactive	End Date: 1/1/1985

Description: This diversion box is a reinforced concrete structure.

Location: The 241-C-152 Diversion Box is located in the southwestern portion of the 241-C Tank Farm, west of the 241-C-151 Diversion Box.

Related Sites/ Structures: The 241-C-152 diversion box is associated with 241-C-301 Catch Tank. This unit interconnects the 241-B-154, and 241-B-153 diversion boxes with the 241-C Tank Farm.

Process Description: Diversion boxes and receiving vaults drain to catch tanks. They are designed to contain leaks or spills from waste transfers and drainage during jumper operations within the unit.

Waste Type: Equipment

Waste Description: It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Waste Type: Process Effluent

Waste Description: This unit was used to transfer waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operations. Radiological contamination is estimated to be extremely high.

Code: 241-C-153	Classification: Accepted
Names: 241-C-153; 241-C-153 Diversion Box	Reclassification: None
Type: Diversion Box	Start Date: 1/1/1946
Status: Inactive	End Date: 1/1/1985

Description: The diversion box is an underground, reinforced concrete structure. Surface features include concrete cover blocks and lifting bails.

Location: The 241-C-153 Diversion Box is located in the southwestern portion of the 241-C Tank Farm, south of the 241-C-110 tank.

Related Sites/ Structures: The diversion box is associated with the 241-C-301 Catch Tank and 241-C-Tank Farm. This unit interconnects the 241-C-151 and 241-C-152 diversion boxes.

Process Description: Diversion boxes and receiving vaults drain to catch tanks. They are designed to contain leaks or spills resulting from waste transfers during jumper operations within the unit.

Waste Type: Process Effluent

Waste Description: The diversion box transferred liquid waste from the processing plants to the tank farms. The Part A Permit assumed that 50 pounds (23 kilograms) of lead shielding bricks may also be stored in this diversion box.

Waste Type: Chemicals

Waste Description: This unit was used to transfer waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operation. Diversion box contamination is estimated to be high in alpha, beta, and gamma. Chemical residues may be present.

Code:	241-C-201	Classification:	Accepted
Names:	241-C-201; 241-C-TK-201	Reclassification	None
Type:	Single-Shell Tank	Start Date:	1/1/1947
Status:	Inactive	End Date:	1/1/1977
Description:	The underground tank is a vertically configured, reinforced-concrete cylinder, with a slab roof. It is lined with steel. The tank rests on a footing which is integral to the tank base.		
Location:	The 241-C-201 tank is located on the north side of the 241- C Tank Farm, inside the tank farm fence.		
Related Sites/ Structures:	Structures associated with this tank include: ventilation, piping, instrumentation, and the 241-C-202, 241-C-203 and 241-C-204 tanks.		
Process Description:	This tank is a 200-series single-shell tank, designed to receive non-boiling waste. Tanks 241-C-201, 241-C-202, 241-C-203, and 241-C-204 have tie lines between each tank to equalize the waste volumes in each tank. This tank received metal waste, and is plumbed to the 241-C-252 diversion box.		
Waste Type:	Storage Tank		
Waste Description:	Tank 241-C-201 began to operate in 1947 by receiving bismuth phosphate metal waste. This tank was sluiced during the uranium recovery process. No pumpable liquid remains in the tank.		

Code:	241-C-202	Classification:	Accepted
Names:	241-C-202; 241-C-TK-202	Reclassification	None
Type:	Single-Shell Tank	Start Date:	1/1/1947
Status:	Inactive	End Date:	1/1/1977
Description:	The underground tank is a vertically configured, reinforced-concrete cylinder, with a slab roof. It is lined with steel. The tank rests on a footing which is integral to the tank base.		
Location:	Tank 241-C-202 is located on the north side of the 241-C Tank Farm, inside the tank farm fence.		
Related Sites/ Structures:	Structures associated with this tank include: ventilation, piping, instrumentation, and the other 200-series tanks.		
Process Description:	This tank is a 200-series single-shell tank, designed to receive non boiling waste. Tanks 241-C-201, 241-C-202, 241-C-203, and 241-C-204 have lines between each tank to equalize the waste volumes in each tank. This tank received metal waste, and is plumbed to the 241-C-252 diversion box.		
Waste Type:	Storage Tank		
Waste Description:	Tank 241-C-202 began to operate in 1947 by receiving metal waste. Tanks 241-C-201, -202, -203, and -204 were used to settle waste while supernatant was sent to a crib. This tank was sluiced for uranium recovery. No pumpable liquid remains in the tank. Metal waste in the tank was removed in 1954 and the tank received waste from hot semi-works in 1955 and 1956. Most of the hot semi-works waste was removed in 1970. Waste retrieval completed in August 2005 with the retrieval of 1,032 gallons of waste, resulting in an ending volume in the tank of 147 gallons. Retrieval was accomplished using a vacuum retrieval system. Waste was transported to 241-AN-106 through a hose-in-hose transfer line.		

Code: 241-C-203 **Classification:** Accepted
Names: 241-C-203; 241-C-TK-203 **Reclassification:** None
Type: Single-Shell Tank **Start Date:** 1/1/1947
Status: Inactive **End Date:** 1/1/1976

Description: The site is a vertically configured, underground reinforced-concrete tank, with a slab roof. It is lined with steel. The tank rests on a footing which is integral to the tank base.

Location: The 241-C-203 tank is located on the north side of the 241- C Tank Farm, inside the tank farm fence.

Related Sites/ Structures: Structures associated with this tank include; ventilation, piping, instrumentation, and the other 200-series tanks.

Process Description: This tank is a 200-series single-shell tank, designed to receive non-boiling waste. Tanks 241-C-201, 241-C-202, 241-C-203, and 241-C-204 have lines between each tank to equalize the waste volumes. This tank received metal waste and is plumbed to the 241-C-252 diversion box.

Waste Type: Storage Tank

Waste Description: Tank 241-C-203 began to operate in 1947 by receiving metal waste. In 1986, a cracked sludge surface was observed with no visible liquids. Approximately 9504 liters (2501 gallons) of waste was removed from this tank and transferred to double shell tank 241-AN-106 in 2004.

Code: 241-C-204 **Classification:** Accepted
Names: 241-C-204; 241-C-TK-204 **Reclassification:** None
Type: Single-Shell Tank **Start Date:** 1/1/1948
Status: Inactive **End Date:** 1/1/1977

Description: The tank is a vertically configured, reinforced-concrete cylinder, with a slab roof. The tank is lined with steel. The tank rests on a footing which is integral to the tank base.

Location: The 241-C-204 tank is located on the north side of the 241- C Tank Farm, inside the tank farm fence.

Related Sites/ Structures: Structures associated with this tank include; ventilation, piping, instrumentation, and the other 200-series C Tank Farm tanks.

Process Description: This tank is a 200-series single shell tank, designed to receive non-boiling waste. Tanks 241-C-201, 241-C-202, 241-C-203, and 241-C-204 have lines between each tank to equalize the waste volumes in each tank. This tank received metal waste, and is plumbed to the 241-C-252 diversion box.

Waste Type: Storage Tank

Waste Description: Tank 241-C-204 began to operate in 1948 by receiving metal waste. Tanks 241-C-201, -202, -203, and -204 were used to settle waste while supernatant was sent to a crib. This tank was sluiced for uranium recovery. No pumpable liquid remains in the tank.

Code: 241-C-252 **Classification:** Accepted
Names: 241-C-252; 241-C-252 Diversion Box **Reclassification:** None

Type: Diversion Box **Start Date:** 1/1/1946

Status: Inactive **End Date:** 1/1/1985

Description: The diversion box is an underground, reinforced concrete structure. Surface features include concrete cover blocks and lifting bails.

Location: The diversion box is located in the northwest portion of the 241-C Tank Farm, west of tank 241-C-204.

Related Sites/ Structures: Diversion box 241-C-252 is associated with the 241-C-301 Catch Tank and the 241-C Tank Farm. The unit interconnects diversion box 241-C-151 and the 241-C Tank Farm.

Process Description: Diversion boxes and receiving vaults drain to catch tanks. They are designed to contain leaks and spills from waste transfers and drainage during jumper operations within the unit.

Waste Type: Process Effluent

Waste Description: This unit was used to transfer waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operations. Radiological contamination is expected to be high in alpha, beta, and gamma. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Waste Type: Equipment

Waste Description: It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Code: 241-C-301 **Classification:** Accepted

Names: 241-C-301; 241-C-301C; 241-C-301-C Catch Tank; Lines V114 and V155 **Reclassification:** None

Type: Catch Tank **Start Date:** 1/1/1946

Status: Inactive **End Date:** 1/1/1985

Description: The 241-C-301 Catch tank is an underground tank. It is surrounded with post and chain and marked with Inactive Miscellaneous Underground Storage Tank (IMUST) signs.

Location: The 241-C-301 catch tank is located in the northwest portion of the 241-C Tank Farm, northwest of the 241-C-112 tank.

Related Sites/ Structures: This tank is associated with 241-C-151, 241-C-152, 241-C-153, 241-C-252 diversion boxes and 241-C Tank Farm. Line V114 and V155 are the drain lines from the diversion boxes.

Process Description: Tank 241-C-301C received drainage from diversion boxes 241-C-151, 241-C-152, 241-C-153, and 241-C-252. These diversion boxes received wasted transfers from and the C Farm, B Plant, and PUREX. Incidental wastes were received from the Hot Semiworks operations. Catch tanks are components of tank farms that collect spills and/or leaks during waste transfers between processing facilities and tank farms. Catch tanks also received any water from rainfall, snowmelt, or dust that entered the diversion boxes (the diversion boxes were later weather proofed.) The tanks were coal coated for corrosion protection, and later underwent two cathodic protection upgrades. The catch tank was constructed with 15.2 centimeter (6 inch) thick walls, coated with Amercoat to obtain a non-porous surface.

Waste Type: Storage Tank

Waste Description: The 241-C-151, 241-C-152, 241-C-153 and 241-C-252 diversion boxes drained waste solutions from leaks or spills that occurred during waste transfer operations. The wastes received in the

catch tank include waste from B Plant, PUREX and Hot Semiworks operations. In 1994, the tank contained 5586 liters (1470 gallons) of liquid supernate and 34,260 liters (9016 gallons) of sludge. The tank may also have received ferrocyanide waste.

Code: 241-C-801	Classification: Accepted
Names: 241-C-801; 241-C-801 Cesium Loadout Facility	Reclassification: None
Type: Process Unit/Plant	Start Date: 1/1/1962
Status: Inactive	End Date: 1/1/1976

Description: The site is a single story building located inside the 241-C Tank Farm. The upper portion of the building is constructed of prefabricated metal. The bottom 2.9 meters (9.5 feet) of the building is constructed of concrete walls and foundations, approximately 0.3 meters (1 foot) thick. This part of the structure is covered with earth. The main building sections include the loadout room, which is 9.8 by 4.3 by 6.1 meters (32 by 14 by 20 feet). The operating room, which is 4.3 by 3.7 by 6.1 meters (14 by 12 by 20 feet). A valve pit, measuring 2.4 by 2.1 by 2.4 meters (8 by 7 by 8 feet) is located in the southwest portion of the building. A rollup door that allowed truck access to the High Bay portion of the building. The High Bay occupies approximately half of the building and has a 5 ton capacity crane bridge.

There are two dry wells associated with this building (H-2-4566). One drywell is located inside the tank farm fence, near the north wall of 801-C. The other dry well is located approximately 23 meters (75 feet) north of the 801-C building, outside the tank farm fence, that is fed by two stainless steel pipelines.

Location: The Cesium Loadout Facility is located in the northeastern portion of the 241-C Tank Farm.

Related Sites/Structures: The 241-C-801 Facility is associated with the 241-C-102 and 241-C-103 tanks and two drywells.

Process Description: Two tank farm underground storage tanks are associated with this facility. The 241-C-103 tank was used for cesium feed storage. Waste from this tank was pumped into the 801-C Loadout facility into a truck mounted demineralizer. The demineralizer removed the cesium from the liquid waste and retained it inside the shielded container. The cesium depleted waste was transferred to the 241-C-102 tank. The truck containing the cesium was transported offsite. The 241-C Valve pit was installed in the upper level of the 241-C-801, Cesium Loadout Facility, which received cesium-rich waste from tank 241-C-103. The waste was pumped through an ion exchanger before being transferred to tank 241-C-102. The Cesium Loadout Facility was declared inactive and isolated in September 2002.

Waste Type: Process Effluent

Waste Description: The unit is a radioactively contaminated structure. Contamination levels are estimated at 30 curies beta. There may be residual chemicals and radioactive material in processing equipment and piping. There are no storage tanks inside this building. The drywell located north of the building, outside the fence, is posted with Contamination Area signs.

Code: 241-CR-151	Classification: Accepted
Names: 241-CR-151; 241-CR-151 Diversion Box	Reclassification: None
Type: Diversion Box	Start Date: 1/1/1946
Status: Inactive	End Date:

Description: The diversion box is an underground, reinforced concrete structure. Surface features include

concrete cover blocks and lifting bails.

Location: The 241-CR-151 Diversion Box is located in the southern portion of the 241-C Tank Farm, adjacent to the 244-CR Vault.

Related Sites/ Structures: This unit lies between the 241-CR-153 and the 241-CR-153 diversion boxes and the 244-CR vault.

Process Description: This covered diversion box is designed to contain leaks from transfers and drainage from operations within the unit. This unit acts as a secondary containment for the transfer line jumper connections.

Waste Type: Chemicals

Waste Description: This unit was used for transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operation.

Waste Type: Equipment

Waste Description: It was estimated that approximately 50 pounds (23 kilograms) of waste lead was stored in this unit.

Code: 241-CR-152 **Classification:** Accepted

Names: 241-CR-152; 241-CR-152 Diversion Box; Line 8253 **Reclassification:** None

Type: Diversion Box **Start Date:** 1/1/1946

Status: Inactive **End Date:** 1/1/1985

Description: The diversion box is an underground, reinforced concrete structure. Surface features include concrete cover blocks and lifting bails.

Location: The 241-CR-152 Diversion Box is located in the southern portion of the 241-C Tank Farm, northwest of the 244-CR Vault. It is attached to the 241-CR-153 Diversion Box.

Related Sites/ Structures: This unit is interconnected to both the 241-CR-151 diversion box and all the tanks of the 241-C Tank Farm. Line 8253 is the diversion box drain line.

Process Description: This diversion box is designed to contain leaks from transfers and drainage from operations within the unit. This unit acts as a secondary containment for transfer line jumper connections.

Waste Type: Equipment

Waste Description: It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Waste Type: Process Effluent

Waste Description: This unit was used for transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operation.

Code: 241-CR-153 **Classification:** Accepted

Names: 241-CR-153; 241-CR-153 Diversion Box; Line 8307 **Reclassification:** None

Type: Diversion Box **Start Date:** 1/1/1946

Status: Inactive **End Date:** 1/1/1985

Description: The diversion box is an underground, reinforced concrete structure. Surface features include concrete cover blocks and lifting bails.

Location: The 241-CR-153 Diversion Box is located in the southern portion of the 241-C Tank Farm, northwest of the 244-CR Vault. It is attached to the 241-CR-152 Diversion Box.

Related Sites/ Structures: This unit adjoins the 241-C-152 diversion box. Line 8307 is the diversion Box drain line.

Process Description: This diversion box is designed to contain leaks from transfers and drainage from operations within the unit. This unit acts as secondary containment for transfer line jumper connections.

Waste Type: Chemicals

Waste Description: This unit was used for transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operation.

Waste Type: Equipment

Waste Description: It was estimated that approximately 50 pounds (23 kilograms) of waste lead was stored in this unit.

Code: 244-CR VAULT **Classification:** Accepted

Names: 244-CR VAULT; Line 8765; 244-CR Vault **Reclassification:** None

Type: Receiving Vault **Start Date:** 1/1/1946

Status: Inactive **End Date:** 1/1/1988

Description: This vault is an underground, reinforced concrete structure. It is a two-level, multi-cell structure (cells 1, 2, 3 and 11). The lower cell contains the process vessels. Upper cells contain piping and equipment. The structure is constructed with concrete cover blocks which, when removed, allow access to the upper cells. The lower cells contain four process vessels: TK-CR-001, TK-CR-011, TK-CR-002, and TK-CR-003 (see subsites).

Location: This unit is located in the southern portion of the 241-C Tank Farm, southeast of the 241-CR-151 Diversion Box.

Release Description: In 2008, the Hanford C-Farm Leak Assessment Report (RPP-ENV-33418) was issued. It documented failed pipelines and unplanned releases associated with C Farm activities. On February 18, 1965, the 244-CR Vault was found flooded up to approximately the level of the tank tops. Immediate steps were taken to reduce the liquid level by jetting the solution to the 011 Tank. Partial cause of the flooding is attributed to a failure in the coating waste line which enters the 241-CR-151 diversion box. Drainage from this diversion box collects in the 002-CR vault sump. Water from a sampler flush line and drainage from rain and snow contributed to the liquid level in the vault. To date, the 001, 002, and 003 sumps have been emptied, and the 011 sump is being emptied, to the 011 Tank. This liquid is being pumped from the 011 Tank to Tank 103-A in the 241-A Tank Farm. In May 1966, a leak in the PUREX coating waste route (via 241-CR-152 diversion box) was detected by an abnormal liquid level increase of the 002-CR vault sump. The leaking flexible jumper in the 241-CR-152 diversion box was replaced. Diversion box 241-CR-152 and 244-CR Vault sump are concrete structures with painted surfaces. It is uncertain whether leaked waste was contained inside diversion box 241-CR-152 and 244-CR Vault sump.

Related Sites/ Structures: The associated structures include the 241-C Tank Farm and the Hot Semiworks operations. Line 8765 is the drain line from 241-CR-151 to the 244-CR sump.

Process Description: The receiver was used for interim storage and processing operations of 241-C Tank Farm. It had the capacity to add chemicals, mix solutions and cool the tank contents. Waste was also received from the Hot Semiworks Facility. The 244-CR-003 Tank in the 244-CR Vault is used for the interim storage of salt well waste from 241-C Tank Farm.

Waste Type: Storage Tank

Waste Description: The unit contained the following wastes: metal waste, first cycle waste, B Plant decontamination waste, PUREX fission product waste, uranium recovery sluicing waste, coating waste, radioactive condensates, sink wastes, REDOX spent solvent waste, other REDOX waste, PUREX organic wash waste, PUREX acid process waste, PUREX spent solvent waste, strontium recovery waste, and critical mass laboratory waste.

This Site has the Following SubSites:

Code: 244-CR VAULT:1

Names: 244-CR VAULT:1; 244-CR-001 Tank and Sump; 244-CR-TK-001

Code: 244-CR VAULT:2

Names: 244-CR VAULT:2; 244-CR-002 Tank and Sump; 244-CR-TK-002

Code: 244-CR VAULT:3

Names: 244-CR VAULT:3; 244-CR-TK-003

Code: 244-CR VAULT:4

Names: 244-CR VAULT:4; 244-CR-TK-011; 244-CR

Code: 244-CR VAULT:1

Classification: Accepted

Names: 244-CR VAULT:1; 244-CR-001 Tank and Sump; 244-CR-TK-001
Reclassification: None

Type: Receiving Vault

Start Date:

Status: Inactive

End Date:

Description: 244-CR-001 is a 189,250 liter (50,000 gallon) tank located in a 6.7 meter (22 foot) by 7.9 meter (26 foot) by 8.8 meter (29 foot) cell (cell 1) within the 244-CR Vault. The concrete cell has a 170 liter (45 gallon) capacity sump. The 244-CR Vault and associated tanks and cells were used as the uranium sludge recovery and distribution vault for the 241-C Tank Farm. CR Vault was also used for the interim storage and transfer of waste from B-Plant, PUREX and Hot Semi-Works. Tank 244-CR-001 was the slurry accumulator, receiving waste from the C Farm tanks. The slurry was processed with nitric acid. In 2002, the tank was estimated to contain 7,570 liters (2,000 gallons) of waste solids from the Uranium Recovery Program. In 2005, the tank contained 5,197 liters (1,375 gallons) of liquid and sludge. Cell #1 contained 291 liters (77 gallons) of liquid.

The SubSite is Part Of:

Code: 244-CR VAULT

Names: 244-CR VAULT; Line 8765; 244-CR Vault

Code: 244-CR VAULT:2

Classification: Accepted

Names: 244-CR VAULT:2; 244-CR-002 Tank and Sump; 244-CR-TK-002
Reclassification: None

Type: Receiving Vault

Start Date:

Status: Inactive

End Date:

Description: 244-CR-001 is a 56,775 liter (15,000 gallon) tank located in a 4.9 meter (16 foot) by 6.0 meter (20 foot) by 5.79 meter (19 foot) cell (cell 2) within the 244-CR Vault. The concrete cell has a 170 liter (45 gallon) capacity sump. The 244-CR Vault and associated tanks and cells were used as the uranium sludge recovery and distribution vault for the 241-C Tank Farm. CR Vault was also used for the interim storage and transfer of waste from B-Plant, PUREX and Hot Semi-Works. Tank 244-CR-002 was the blending tank, mixing waste from the 244-CR-001 with nitric acid. In 2002, the tank was estimated to contain 5,678 liters (1,500 gallons) of waste solids from the Uranium Recovery Program. In 2005, the tank contained 2,846 liters (753 gallons) of liquid and sludge. Cell 2 contained 5,579 liters (1,476 gallons) of liquid and sludge.

The SubSite is Part Of:

Code: 244-CR VAULT

Names: 244-CR VAULT; Line 8765; 244-CR Vault

Code: 244-CR VAULT:3

Classification: Accepted

Names: 244-CR VAULT:3; 244-CR-TK-003

Reclassification: None

Type: Receiving Vault

Start Date:

Status: Inactive

End Date:

Description: 244-CR-003 is a 56,775 liter (15,000 gallon) tank located in a 4.9 meter (16 foot) by 6.0 meter (20 foot) by 5.79 meter (19 foot) cell (cell 3) within the 244-CR Vault. The concrete cell has a 170 liter (45 gallon) capacity sump. The 244-CR Vault and associated tanks and cells were used as the uranium sludge recovery and distribution vault for the 241-C Tank Farm. CR Vault was also used for the interim storage and transfer of waste from B-Plant, PUREX and Hot Semi-Works. Tank 244-CR-003 was a blending tank, mixing waste from the 244-CR-001 with nitric acid. In 2002, the tank was estimated to contain 15,973 liters (4,200 gallons) of saltwell waste with an unknown amount of solids. In 2005, the tank contained 8,112 liters (2,146 gallons) of liquid and sludge. Cell 3 contained 6,709 liters (1,775 gallons) of liquid and sludge. 244-CR-003 was the last active tank in the CR Vault. The tank had been available to be used for saltwell pumping of the C Tank Farm.

The SubSite is Part Of:

Code: 244-CR VAULT

Names: 244-CR VAULT; Line 8765; 244-CR Vault

Code: 244-CR VAULT:4

Classification: Accepted

Names: 244-CR VAULT:4; 244-CR-TK-011; 244-CR

Reclassification: None

Type: Receiving Vault

Start Date:

Status: Inactive

End Date:

Description: 244-CR-011 is a 189,250 liter (50,000 gallon) tank located in a 6.7 meter (22 foot) by 7.9 meter (26 foot) by 8.8 meter (29 foot) cell (cell 11) within the 244-CR Vault. The concrete cell has a 170 liter (45 gallon) capacity sump.

The 244-CR Vault and associated tanks and cells were used as the uranium sludge recovery and distribution vault for the 241-C Tank Farm. CR Vault was also used for the interim storage and transfer of waste from B-Plant, PUREX and Hot Semi-Works. Initially, tank 244-CR-011 acted as a process pump tank for the transfer of processed waste from the CR Vault to the diversion station for transfer to the Uranium Recovery facility or other operations. In 2002, the tank was

estimated to contain 132,475 liters (35,000 gallons) of supernate and rainwater. In 2005, 15,082 liters (3,990 gallons) of sludge was reported. No liquid volume was remaining in the tank. Cell 11 contained 27,639 liters (7,312 gallons) of liquid and sludge.

The SubSite is Part Of:

Code: 244-CR VAULT

Names: 244-CR VAULT; Line 8765; 244-CR Vault

Code: 244-CR-WS-1

Classification: Accepted

Names: 244-CR-WS-1; 244-CR French Drain

Reclassification: None

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The waste site is a 24 inch diameter french drain, It is covered and partially filled with gravel.

Location: The drain is located on the south side of the 291-CR Ventilation Building stack, inside the 241-C Tank Farm fence.

Related Sites/ Structures: The structure is associated with the 291-CR ventilation building.

Process Description: This drain received condensate from the 291-CR Stack, plenum chamber exhaust fans and the plenum inlet.

Waste Type: Water

Waste Description: This unit received condensate from the 291-CR Stack, the plenum chamber exhaust fans and the plenum inlet.

Code: 200-E-133

Classification: Accepted

Names: 200-E-133; Contaminated Soil at 241-C Tank Farm; Contamination Migration Beyond the fence at C Farm

Reclassification: None

Type: Contamination Migration

Start Date: 1/1/1946

Status: Inactive

End Date:

Description: The site is the soil inside and adjacent to the chain link fence that surrounds the 241-C Tank Farm. Various radiological postings and warning signs are attached to the chain link fence. The interior of the tank farm complex is covered with gravel. Many risers and monitoring devices for the underground structures are visible on the surface. The individual unplanned releases associated with the 241-C Tank Farms are not separately marked or posted. Occasionally, radioactive contamination is found adjacent to the outside of the tank farm fence, resulting in a contamination zone extension around the tank farm perimeter. These areas are also part of this site.

Location: The 241-C Tank Farm is located at the intersection of 7th Street and Buffalo Ave. in 200 East Area.

Release Description: The exact extent (horizontal and vertical) of the soil contaminated by unplanned releases that occurred within this farm complex over the years are not known. Some of the single shell tanks have leaked to the soil below the tank farm. Other releases spread contamination to the surface soil surrounding the tanks. In 2008, the Hanford C-Farm Leak Assessment Report (RPP-ENV-

33418) was issued. It documented failed pipelines and unplanned releases associated with activities inside the 241-C Tank Farm. Some of the releases included the underground process line (V172) from the 252-C diversion box to 241-C-112 tank in C Tank Farm failure. The failed pipeline, inside C tank farm, was isolated. Jumpers were fabricated and installed to establish a new process route. Line V112, adjacent to diversion box 241-C-151, was identified as a leaker. The date and amount of waste leaker from this pipeline is unknown. In August 1974, Occurrence Report 74-120 states that pipeline V-103, located inside 241-C farm, leaked and caused high levels of contamination between tanks 241-C-104 and 241-C-105. High readings were noted in dry well 30-03-02. A liquid level rise in Tank 103-C, the cesium feed tank, was apparently caused by a failed line in the encasement between the 152-CR diversion box and Tank 102-C which permitted coating waste from the Purex Plant to leak into the encasement and drain to Tanks 101-C, 102-C, and 103-C via the tank pump pits. Coating waste has been routed through a spare line to Tank 102-C and no further leaks have been detected. The coating waste solution accumulated in Tank 103-C did not significantly affect cesium loading capability as a cask was loaded normally following the incident.

Related Sites/ Structures: The site is associated with UPR-200-E-16, UPR-200-E-27, UPR-200-E-68, UPR-200-E-81, UPR-200-E-82, UPR-200-E-107, UPR-200-E-118, UPR-200-E-136, and UPR-200-E-137. Most of these sites are listed in TPA Appendix B as TSD-associated sites, and are to be addressed with the closeout of the tank farm TSD. As such, site 200-E-133 is also a TSD-associated site.

Waste Type: Process Effluent

Waste Description: Liquid releases occurred from underground leaks in tanks and transfer lines. Airborne contamination spreads occurred from activities conducted in valve pits and diversion boxes. Both types of releases contributed to the contamination in the soil.

Code: 2607-EG	Classification: Accepted
Names: 2607-EG	Reclassification: None
Type: Septic Tank	Start Date: 1/1/1951
Status: Inactive	End Date:

Description: There were two, 2607-EG septic tanks. The first tank failed and was replaced in 1972. A large diameter, vertical concrete pipe extends above the ground surface. It received sanitary wastewater and sewage from the 271-CR Building. The associated drain field had a capacity of 619 gallons (2,350 liters) per day.

Location: This septic tanks are located southeast of the 241-C Tank Farm fence and east of the 271-CR Building.

Related Sites/ Structures: The 2607-EG Septic Tank is associated with the 241-C Tank Farm and the 271-CR Building.

Process Description: The 2607-EG Septic Tanks and associated drain fields were designed to accept sanitary sewer effluent from the 271-CR Building.

Waste Type: Sanitary Sewage

Waste Description: The current flow rates to Septic Tank 2607-EG are unknown. However, the 2607-EG septic system received sanitary sewer effluent from the 271-CR Building at a rate of 6 cubic feet (0.2 cubic meters) per day in 1987.

Code: UPR-200-E-72	Classification: Accepted
---------------------------	---------------------------------

Names: UPR-200-E-72; Radioactive Contamination from Uncovered Buried Waste; UN-200-E-72 **Reclassification** None

Type: Unplanned Release **Start Date:** 1/1/1985

Status: Inactive **End Date:**

Description: A WIDS sign has been placed at the approximate location of the site.

Location: The site is located south of the 241-C Tank Farm, near the 216-C-8 Crib.

Release Description: In 1985, radiological surveys were being performed outside the 241-C Tank Farm fence following a contamination incident at 241-C-151. A contaminated area was found south of 241-C Tank Farm that indicated the burial of previously undocumented contaminated material. The area contained specks of contamination reading up to 7 rad per hour. The source of the contamination is assumed to be the buried material.

Waste Type: Misc. Trash and Debris

Waste Description: The contamination consisted of beta/gamma particulates with dose rates up to 7 rad per hour on the uncovered material and the surrounding area.

Code: UPR-200-E-91 **Classification:** Accepted

Names: UPR-200-E-91; UN-200-E-91; UN-216-E-19 **Reclassification** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: This site was a large area of contaminated soil, located north and east of the 241-C Tank Farm. In 1981, the contaminated soil was removed from this area and taken to another location (UPR-200-E-56). The radiological posting was removed in 1981. This release site is no longer marked or posted.

Location: UPR-200-E-91 was located adjacent to the northeast corner of the 241-C Tank Farm.

Release Description: The release occurred over time, due to radioactive particles migrating out of the adjacent 241-C Tank Farm. At one time, water from an equipment decontamination station, located inside the tank farm, seeped downhill into this area. Vapor emissions and windblown particulates from the contaminated surfaces of the tank farm contributed to the buildup of ground contamination at the site.

Related Sites/Structures: UPR-200-E-91 was associated with the 241-C Tank Farm. The contaminated soil was removed to UPR-200-E-56. A smaller radiologically posted area is located in the vicinity of where this unplanned release had been. See WIDS site code 200-E-115.

Waste Type: Soil

Waste Description: The release consisted of wind blown radiologically contaminated soil from tank farm activities and water run off from an equipment decontamination located inside 241-C tank farm. The contaminated soil was removed. The area outside the tank farm fence was revegetated with perennial wheatgrass and cheatgrass in 1981.

WMA S/SX

Code: 216-S-3	Classification: Accepted
Names: 216-S-3; 216-S-3 Crib; 216-S-5	Reclassification: None
Type: Crib	Start Date: 1/1/1953
Status: Inactive	End Date: 1/1/1956

Description: The unit consists of two open bottomed crib boxes 3.1 meters (10 feet) by 3.1 meters (10 feet) made of timbers. The two crib boxes are connected in series 15 meters (50 feet) apart, with overflow from one box into the other via a pipe. These boxes are set into a gravel layer in the bottom of a trench. The trench was the backfilled. Each box contains two flanged riser pipes extending from the top of the box.

Location: The unit was located outside the 241-S Tank Farm east fence. In 1996, the eastern tank farm fence line was expanded. The crib is now inside the tank farm fence.

Related Sites/ Structures: The crib is associated with the condensers on the 241-S-101 and 241-S-104 tanks located inside the 241-S Tank Farm. The site is also associated with the 216-S-15 Pond.

Process Description: The unit received condensate from the riser condensers on the 241-S-101 and 241-S-104 Tanks.

Waste Type: Process Effluent

Waste Description: The site received condensate from condensers on the 241-S-101 and 241-S-104 Tanks in the 241-S Tank Farm. The waste is low in salt and is neutral to basic. The inorganics at the site consist of nitrate, sodium, sodium dichromate, sodium hydroxide, sodium aluminate, and ammonium nitrate. The Reduction Oxidation (REDOX) Radiation Monitoring Report for September 1953 states that the condensate diverted to this crib was sampled. The analysis indicated 95% of the activity was due to zirconium-niobium.

Code: 216-S-15	Classification: Accepted
Names: 216-S-15; 216-S-2; 241-S-110 Pond; UN-216-W-3; 110-S Tank Overflow Pond	Reclassification: None
Type: Pond	Start Date: 1/1/1951
Status: Inactive	End Date: 1/1/1952

Description: This site consists of a pond that was deactivated by removing the above-ground piping and backfilling it with clean soil.

Location: This site is located at the northeast corner of the 216-S-3 Crib. The site was located outside the east 241-S Tank Farm fence. In 1996, the eastern tank farm fence line was expanded. The site is now inside the tank farm fence.

Related Sites/ Structures: The site is associated with the 241-S-110 tank.

Process Description: The site provided surface liquid disposal for the 241-S-110 Tank condenser spray cooling water.

Waste Type: Process Effluent

Waste Description: The site received condenser spray cooling water from the 241-S-110 Tank. The waste was low in salt, neutral to basic, and contained nitrates.

Code: 241-S-A **Classification:** Accepted
Names: 241-S-A; 241-S-A Diversion Box; 241-S-A Valve Pit **Reclassification:** None
Type: Valve Pit **Start Date:** 1/1/1952
Status: Inactive **End Date:**

Description: This unit is a rectangular concrete structure used to divert waste flow to the proper destination. Valve handles extend through and above a concrete cover block on the 241-S-A Valve Pit.

Location: The 241-S-A Valve Pit is located in the 241-S Tank Farm, between Tanks 241-S-102 and 241-S-101.

Related Sites/Structures: Structures associated with the 241-S-A Valve Pit include: a flush pit, a leak detector, valve handles, and the 241-S-102 Tank.

Process Description: The 241-S-A Valve Pit is used to direct waste flow.

Waste Type: Process Effluent

Waste Description: The unit transports waste solutions from processing and decontamination operations. Quantities of waste are variable according to specific plant operations. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Code: 241-S-B **Classification:** Accepted
Names: 241-S-B; 241-S-B Diversion Box; 241-S-B Valve Pit **Reclassification:** None
Type: Valve Pit **Start Date:** 1/1/1952
Status: Inactive **End Date:**

Description: This unit is a rectangular concrete structure used to divert waste flow to the proper destination. Valve handles extend through and above a concrete cover block on the 241-S-B Valve Pit.

Location: The 241-S-B Valve Pit is located in the 241-S Tank Farm, south of Tanks 241-S-102 and 241-S-101.

Related Sites/Structures: Structures associated with the 241-S-B Valve Pit include: a flush pit, a leak detector, valve handles, and the 241-S-102 Tank.

Process Description: The 241-S-B Valve Pit is used to direct waste flow.

Waste Type: Process Effluent

Waste Description: The unit transports waste solutions from processing and decontamination operations. Quantities of waste are variable according to specific plant operations. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Code: 241-S-C **Classification:** Accepted
Names: 241-S-C; 241-S-C Diversion Box; 241-S-C Valve Pit **Reclassification:** None

Type: Valve Pit **Start Date:** 1/1/1952
Status: Inactive **End Date:**

Description: This unit is a rectangular concrete structure used to divert waste flow to the proper destination. Valve handles extend through and above a concrete cover block on the 241-S-C Valve Pit.

Location: The 241-S-C Valve Pit is located in the 241-S Tank Farm, south of Tanks 241-S-107 and 241-S-108.

Related Sites/ Structures: Structures associated with the 241-S-C Valve Pit include: a flush pit, a leak detector, valve handles, and the 241-S-107 Tank.

Process Description: The 241-S-C Valve Pit is used to direct waste flow.

Waste Type: Process Effluent

Waste Description: The unit transports waste solutions from processing and decontamination operations. Quantities of waste are variable according to specific plant operations. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Code: 241-S-D **Classification:** Accepted
Names: 241-S-D; 241-S-D Diversion Box; 241-S-D Valve Pit **Reclassification:** None

Type: Valve Pit **Start Date:** 1/1/1952
Status: Inactive **End Date:**

Description: This unit is a rectangular concrete structure used to divert waste flow to the proper destination. Valve handles extend through and above a concrete cover block on the 241-S-D Valve Pit.

Location: The 241-S-D Valve Pit is located in the 241-S Tank Farm, south of Tanks 241-S-107 and 241-S-108.

Related Sites/ Structures: Structures associated with the 241-S-D Valve Pit include: a flush pit, a leak detector, valve handles, and the 241-S-107 Tank.

Process Description: The 241-S-D Valve Pit is used to direct waste flow.

Waste Type: Process Effluent

Waste Description: The unit transports waste solutions from processing and decontamination operations. Quantities of waste are variable according to specific plant operation. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Code: 241-S-101 **Classification:** Accepted
Names: 241-S-101; 241-S-TK-101 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1953
Status: Inactive **End Date:** 1/1/1980

Description: This unit is a second generation single-shell storage tank. Tank 241-S-101 is the first tank of a three-tank cascade series. This tank is a reinforced concrete, cylindrical structure with a single steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to

provide radiation shielding.

Location: Tank 241-S-101 is located within 241-S Tank Farm Facility. This facility is located on Thirteenth Street, northwest of the REDOX Plant.

Related Sites/ Structures: Structures associated with Tank 241-S-101 include passive ventilation, a liquid observation well, five drywells, temperature and surface level measurement instruments.

Process Description: Tank 241-S-101 received waste from REDOX, Pacific Northwest Laboratory, and PUREX facilities. Additional sources include N reactor, 241-U, 241-S, and 241-SX Tank Farms.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-S-101 included: REDOX high-level wastes, REDOX coating waste, supernatant containing Pacific Northwest Laboratory waste, coating waste, PUREX low-level waste, laboratory waste, B Plant high-level waste, terminal liquor and evaporator bottoms, partial neutralization feed, N Reactor waste, ion exchange waste, and double-shell slurry feed from 241-U, 241-S and 241-SX Tank Farms.

Code: 241-S-102

Classification: Accepted

Names: 241-S-102; 241-S-TK-102

Reclassification: None

Type: Single-Shell Tank

Start Date: 1/1/1953

Status: Inactive

End Date: 1/1/1980

Description: This unit is a second generation single-shell storage tank. Tank 241-S-102 is the second tank of a three-tank cascade series. This tank is concrete reinforced, cylindrical, and dome-roofed with a single steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-S-102 is located within 241-S Tank Farm Facility. This facility is located on Thirteenth Street, northwest of the REDOX Plant.

Release Description: On 7/27/2007, a spill was reported inside the 241-S Tank Farm at the S-102 Pump Pit. Higher than normal radiation levels (200-250 mr/hr at 8-15 feet) were observed. A spill of liquid from an above ground transfer line occurred while attempting to backflush a clogged pump screen. The release was estimated to be less than 100 gallons.

Related Sites/ Structures: Structures associated with Tank 241-S-102 include a passive ventilation liquid observation well, eight dry wells, and temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-S-102 include the REDOX facility and 241-U, 241-S, 241-SX, and 241-SY Tank Farms.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-S-102 include: evaporator bottoms, REDOX high-level waste, noncomplexed waste, double-shell slurry feed, and partial neutralization feed from 241-S, 241-SX, 241-SY, and 241-U Tank Farms.

Code: 241-S-103

Classification: Accepted

Names: 241-S-103; 241-S-TK-103

Reclassification: None

Type: Single-Shell Tank

Start Date: 1/1/1953

Status: Inactive

End Date: 1/1/1980

Description: This unit is a second generation single-shell storage tank. Tank 241-S-103 is the third tank of a three-tank cascade series. This tank is a reinforced concrete, cylindrical structure with a single steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-S-103 is located within 241-S Tank Farm Facility. This facility is located on Thirteenth Street, northwest of the REDOX Plant.

Related Sites/ Structures: Structures associated with Tank 241-S-103 include passive ventilation, a liquid observation well, drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-S-103 include the REDOX facility and 241-S, 241-SX, 241-SY, and 241-U Tank Farms.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-S-103 included REDOX high-level waste, REDOX coating waste, evaporator bottoms, noncomplexed waste, partial neutralization feed, and double-shell slurry feed from 241-S, 241-SX, 241-SY, and 241-U Tank Farms.

Code: 241-S-104

Classification: Accepted

Names: 241-S-104; 241-S-TK-104

Reclassification: None

Type: Single-Shell Tank

Start Date: 1/1/1953

Status: Inactive

End Date: 1/1/1968

Description: This unit is a second generation single-shell storage tank. Tank 241-S-104 is the first tank of a three-tank cascade series. This tank is a reinforced concrete, cylindrical structure with a single steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-S-104 is located within 241-S Tank Farm Facility. This facility is located on Thirteenth Street, northwest of the REDOX Plant.

Related Sites/ Structures: Structures associated with Tank 241-S-104 include passive ventilation, drywells, temperature and surface level measurement instruments.

Process Description: Tank 241-S-104 received waste from the REDOX facility and the 241-S Tank Farm.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-S-104 included REDOX high-level and coating waste, and waste from 241-S Tank Farm.

Code: 241-S-105

Classification: Accepted

Names: 241-S-105; 241-S-TK-105

Reclassification: None

Type: Single-Shell Tank

Start Date: 1/1/1953

Status: Inactive

End Date: 1/1/1976

Description: This unit is a second generation single-shell storage tank. Tank 241-S-105 is the second tank of a three-tank cascade series. This tank is a reinforced concrete, cylindrical structure with a single steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-S-105 is located within 241-S Tank Farm Facility. This facility is located on Thirteenth Street, northwest of the REDOX Plant.

Related Sites/ Structures: Structures associated with Tank 241-S-105 include passive ventilation, a liquid observation well, five drywells, temperature and surface level measurement instruments.

Process Description: Tank 241-S-105 received waste from the REDOX facility.

Waste Type: Storage Tank

Waste Description: REDOX coating and high-level waste were transferred to Tank 241-S-105.

Code: 241-S-106	Classification: Accepted
Names: 241-S-106; 241-S-TK-106	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1953
Status: Inactive	End Date: 1/1/1976

Description: This unit is a second generation single-shell storage tank. Tank 241-S-106 is the third tank of a three-tank cascade series. This tank is a reinforced concrete, cylindrical structure with a single steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-S-106 is located within 241-S Tank Farm Facility. This facility is located on Thirteenth Street, northwest of the REDOX Plant.

Related Sites/ Structures: Structures associated with Tank 241-S-106 include passive ventilation, a liquid observation well, six drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-S-106 include the REDOX facility and 241-S Tank Farms.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-S-106 included REDOX high-level waste and evaporator bottoms from the 241-S Tank Farm.

Code: 241-S-107	Classification: Accepted
Names: 241-S-107; 241-S-TK-107	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1952
Status: Inactive	End Date: 1/1/1980

Description: This unit is a second generation single-shell storage tank. Tank 241-S-107 is the first tank of a three-tank cascade series. This tank is a reinforced concrete, cylindrical structure with a single steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-S-107 is located within 241-S Tank Farm Facility. This facility is located on Thirteenth Street, northwest of the REDOX Plant.

Related Sites/ Structures: Structures associated with Tank 241-S-107 include passive ventilation, six drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-S-107 include REDOX and PUREX facilities, Pacific Northwest Laboratory, N Reactor, and 241-BX, 241-C, 241-S, 241-SX, 241-SY, 241-U Tank Farms.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-S-107 included REDOX high-level waste and coating waste, decontamination waste, B Plant high-level and low-level waste, Pacific Northwest Laboratory waste, laboratory waste, N Reactor waste, PUREX low-level waste, ion exchange waste, fractionization waste, evaporator bottoms, double-shell slurry feed, partial neutralization feed, and complexed concentrate from 241-BX, 241-C, 241-S, 241-SX, 241-SY, and 241-U Tank Farms.

Code: 241-S-108 **Classification:** Accepted

Names: 241-S-108; 241-S-TK-108 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1952

Status: Inactive **End Date:** 1/1/1979

Description: This unit is a second generation single-shell storage tank. Tank 241-S-108 is the second tank of a three-tank cascade series. This tank is a reinforced concrete, cylindrical structure with a single steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-S-108 is located within 241-S Tank Farm Facility. This facility is located on Thirteenth Street, northwest of the REDOX Plant.

Related Sites/Structures: Structures associated with Tank 241-S-108 include passive ventilation, a liquid observation well, five drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-S-108 include the REDOX facility, 241-S, and 241-SX Tank Farms.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-S-108 included REDOX high-level waste, supernatant containing REDOX high-level waste, and evaporator bottoms from 241-S and 241-SX Tank Farms.

Code: 241-S-109 **Classification:** Accepted

Names: 241-S-109; 241-S-TK-109 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1952

Status: Inactive **End Date:** 1/1/1979

Description: This unit is a second generation single-shell storage tank. Tank 241-S-109 is the third tank of a three-tank cascade series. This tank is a reinforced concrete, cylindrical structure with a single steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-S-109 is located within 241-S Tank Farm Facility. This facility is located on Thirteenth Street, northwest of the REDOX Plant.

Related Sites/Structures: Structures associated with Tank 241-S-109 include passive ventilation, a liquid observation well, six drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-S-109 include the REDOX facility and Tank 241-S-102.

Description:

Waste Type: Storage Tank

Waste Description: Tank 241-S-109 received REDOX high-level waste and supernatant containing evaporator bottoms from 241-S-102 Tank.

Code: 241-S-110

Classification: Accepted

Names: 241-S-110; 241-S-TK-110

Reclassification: None

Type: Single-Shell Tank

Start Date: 1/1/1952

Status: Inactive

End Date: 1/1/1976

Description: This unit is a second generation single-shell storage tank. Tank 241-S-110 is the first tank of a three-tank cascade series. This tank is a reinforced concrete, cylindrical structure with a single steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-S-110 is located within 241-S Tank Farm Facility. This facility is located on Thirteenth Street, northwest of the REDOX Plant.

Related Sites/Structures: Structures associated with Tank 241-S-110 include passive ventilation, a liquid observation well, seven drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-S-110 include the REDOX facility, B-Plant, 224-U, 241-S, 241-SX, 241-BX, 241-T, 241-TX, and 241-U Tank Farms.

Waste Type: Storage Tank

Waste Description: Waste transferred to 241-S-110 included REDOX high-level coating, ion exchange waste, 224-U waste, coating waste, decontamination waste, B Plant low-level waste, and organic wash waste from 241-BX, 241-S, 241-SX, 241-T, 241-TX, and 241-U Tank Farms.

Code: 241-S-111

Classification: Accepted

Names: 241-S-111; 241-S-TK-111

Reclassification: None

Type: Single-Shell Tank

Start Date: 1/1/1952

Status: Inactive

End Date: 1/1/1972

Description: This unit is a second generation single-shell storage tank. Tank 241-S-111 is the second tank of a three-tank cascade series. This tank is a reinforced concrete, cylindrical structure with a single steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-S-111 is located within 241-S Tank Farm Facility. This facility is located on Thirteenth Street, northwest of the REDOX Plant.

Related Sites/Structures: Structures associated with Tank 241-S-111 include passive ventilation, a liquid observation well, five drywells, a hydrogen monitoring system, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-S-111 include the REDOX facility and 241-S Tank Farms.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-S-111 included REDOX high-level waste and supernatant containing evaporator bottoms from 241-S Tank Farm.

Code: 241-S-112	Classification: Accepted
Names: 241-S-112; 241-S-TK-112	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1952
Status: Inactive	End Date: 1/1/1974

Description: This unit is a second generation single-shell storage tank. Tank 241-S-112 is the third tank of a three-tank cascade series. This tank is a reinforced concrete, cylindrical structure with a single steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-S-112 is located within 241-S Tank Farm Facility. This facility is located on Thirteenth Street, northwest of the REDOX Plant.

Related Sites/Structures: Structures associated with Tank 241-S-112 include passive ventilation, a hydrogen monitoring system, a liquid observation well, five drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-S-112 include the REDOX facility and 241-S Tank Farm.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-S-112 included REDOX high-level waste and evaporator bottoms from 241-S Tank Farm. The tank contained 614,000 gallons (82,075 cubic feet) of waste, primarily salt cake. A retrieval campaign was completed in May 2005, retrieving 583,000 gallons (77931 cubic feet) of waste. As of May 2005, 31,000 gallons (4,144 cubic feet) of waste remained in the tank.

Code: 241-S-151	Classification: Accepted
Names: 241-S-151; 241-S-151 Diversion Box	Reclassification: None
Type: Diversion Box	Start Date: 1/1/1952
Status: Inactive	End Date:

Description: This unit is constructed of reinforced concrete and is rectangular in shape.

Location: This unit is located inside the 241-S, SX, SY fence, northeast of 241-SX-101 and west of the 241-S-302 catch tank.

Related Sites/Structures: The unit interconnects 240-S-151 Diversion Box, 241-SX-151 Diversion Box, 241-SY Tank Farm, and 241-S Tank Farm (see transfer line sitecodes 200-W-97-PL, 200-W-99-PL and 200-W-100-PL). The 241-S-302A Catch Tank is associated with the 241-S-151 Diversion Box.

Process Description: This unit was used for the transfer of waste solutions from processing and decontamination operations.

Waste Type: Process Effluent

Waste Description: The unit transports waste solutions from processing and decontamination operations. Quantities are variable according to specific plant operations. Lead shielding may also be contained inside the diversion box.

Code: 241-S-152 **Classification:** Accepted

Names: 241-S-152; 241-S-152 Diversion Box **Reclassification:** None

Type: Diversion Box **Start Date:** 1/1/1977

Status: Inactive **End Date:** 1/1/1980

Description: This unit is constructed of reinforced concrete and is rectangular in shape. The 241-S-152 Diversion Box has been weather covered.

Location: The 241-S-152 Diversion Box is located east of the 242-S Evaporator Building.

Related Sites/ Structures: The 241-S-152 Diversion Box is associated with the 241-S Tank Farm. The drain line is DR324.

Process Description: This unit was used for the transfer of waste solutions from processing and decontamination operations.

Waste Type: Process Effluent

Waste Description: This unit was used for transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operations. Lead shielding may also be contained inside the diversion box.

Waste Type: Equipment

Waste Description: Equipment associated with the diversion box includes transfer piping and nozzles. Waste lead is also stored in the diversion box.

Code: 241-S-302A **Classification:** Accepted

Names: 241-S-302A; 241-S-302-A Catch Tank; Lines V542, V763, V764, and DR324 **Reclassification:** None

Type: Catch Tank **Start Date:** 1/1/1949

Status: Inactive **End Date:** 1/1/1991

Description: This unit is a cylindrical, steel tank. The catch tank is buried underground for radiation shielding. The tank is surrounded with posts and chain and labeled with IMUST signs.

Location: The 241-S-302A Catch Tank is located east of the 241-S and the 241-SX Tank Farms, inside the tank farm fence. It is north of the 241-S-151 diversion box.

Related Sites/ Structures: The 241-S-302A Catch Tank is associated with the 241-S-151 and the 241-SX-151 Diversion Boxes. Drain lines V542, V763, V764 and DR324 are associated with the diversion boxes.

Process Description: The tank was installed to receive spills, leakage, line flushes, and drainage associated with waste transfers through the 241-S-151 and 241-SX-151 Diversion Boxes.

Waste Type: Process Effluent

Waste Description: The tank collected leaking and excess process waste that passed through the 241-S-151 and 241-SX-152 Diversion Boxes. Wastes characteristic of the 241-S, 241-SX and 241-U Tank Farms as well as the 222-S Laboratory are expected to be present in the catch tank.

Code: 241-S-304 **Classification:** Accepted

Names: 241-S-304; 241-S-304 Catch Tank **Reclassification:** None

Type: Catch Tank **Start Date:** 1/1/1991

Status: Inactive **End Date:** 1/1/2005

Description: The catch tank is below ground surface, inside a concrete pump pit with concrete cover blocks. The pump pit measures 3 meters by 3 meters (10 foot by 10 foot) and is 1.75 meters (5.75 feet) deep. The catch tank is constructed of carbon steel.

Location: The 241-S-304 Catch Tank is located east of 241-SX Tank Farm and northeast of the 241-S-151 Diversion Box. It is inside the fenced boundary of the 241-S, SX and SY Tank Farm complex.

Related Sites/ Structures: The tank is associated with the 241-S-151 Diversion Box.

Process Description: The 241-S-304 catch tank received precipitation drainage and drainage from the 241-S-151 Diversion Box. This tank was placed into service in 1991 to replace the 241-S-302A catch tank.

Waste Type: Process Effluent

Waste Description: The catch tank receives precipitation drainage and 241-S-151 Diversion Box drainage.

Code: 244-S DCRT **Classification:** Accepted

Names: 244-S DCRT; 244-S Double-Contained Receiver Tank; 244-S Receiver Tank; 244-S RT; 244-S-TK/SMP; Lines 5350 and 5351; 244-S Catch Station **Reclassification:** None

Type: Receiver Tank **Start Date:** 1/1/1987

Status: Inactive **End Date:** 1/1/2005

Description: The 244-S Receiver Tank is constructed of carbon steel. It sets vertically inside a reinforced concrete, steel lined vault with 0.31 meters (1 foot) thick walls and a 1.4 meters (4.5 foot) thick base. The tank vault is separated from a pump pit above by a 30 centimeter (12 inch) thick concrete slab.

Location: The 244-S Receiver Tank is located inside the S, SX, SY Tank Farm fence, south of the 241-SY-103 Tank.

Related Sites/ Structures: This unit is associated with Diversion Boxes 241-S-151 and 241-UX-154. The 244-S Receiver Tank is also associated with 222-S, Plutonium Finishing Plant, U Plant, and T Plant Facilities.

Process Description: The 244-S Receiver Tank served as an interim storage area for liquid radioactive mixed waste.

Waste Type: Storage Tank

Waste Description: The unit stores and transports radioactive mixed waste solutions from processing and decontamination operations. Quantities are variable according to specific plant operations.

Code: 241-SX-A **Classification:** Accepted

Names: 241-SX-A; 241-SX-A Diversion Box; 241-SX-A Valve Pit **Reclassification:** None

Type: Valve Pit **Start Date:** 1/1/1954

Status: Inactive**End Date:****Description:** This unit is a rectangular concrete structure used to divert waste flow to the proper destination. It has been covered with foam. Valve handles extended through and above the concrete cover block.**Location:** The 241-SX-A Valve Pit is located southeast of Tank 241-SX-102 and northeast of Tank 241-SX-105.**Related Sites/
Structures:** Structures associated with the 241-SX-A Valve Pit include: a flush pit, a leak detector, valve handles, and Tank 241-SX-102.**Process** The 241-SX-A Valve Pit is used to direct waste flow.**Description:****Waste Type:** Process Effluent**Waste**
Description: The unit is used to transport radioactive waste solutions from processing and decontamination operations. Quantities are variable according to specific plant operation. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Code: 241-SX-B**Classification:** Accepted**Names:** 241-SX-B; 241-SX-B Diversion Box; 241-SX-B Valve Pit**Reclassification** None**Type:** Valve Pit**Start Date:** 1/1/1954**Status:** Inactive**End Date:****Description:** This unit is a rectangular concrete structure used to divert waste flow to the proper destination. The structure has been covered with foam. Valve handles extended through and above the concrete cover block.**Location:** The 241-SX-B Valve Pit is located southeast of Tank 241-SX-101 and northwest of Tank 241-SX-104.**Related Sites/
Structures:** Structures associated with the 241-SX-B Valve Pit include: a flush pit, a leak detector, valve handles, and Tank 241-SX-102.**Process** The 241-SX-B Valve Pit is used to direct waste flow.**Description:****Waste Type:** Process Effluent**Waste**
Description: The unit is used to transport radioactive waste solutions from processing and decontamination operations. Quantities are variable according to specific plant operation. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Code: 241-SX-101**Classification:** Accepted**Names:** 241-SX-101; 241-SX-TK-101**Reclassification** None**Type:** Single-Shell Tank**Start Date:** 1/1/1954**Status:** Inactive**End Date:** 1/1/1980**Description:** This unit is a third generation single-shell tank designed for self-boiling waste. Tank 241-SX-101 is the first tank of a three tank cascade series. This tank is a reinforced concrete, cylindrical structure with a steel liner. The tank is buried underground to provide radiation shielding.

Location: Tank 241-SX-101 is located in the 241-SX Tank Farm. This facility is located on Thirteenth Street, northwest of the REDOX Plant.

Related Sites/ Structures: Structures associated with Tank 241-SX-101 include: drywells, a liquid observation well, a hydrogen monitor, temperature and surface level measurement instruments. This tank is actively vented through Tank 241-SX-109 which is connected to the 241-SX Sludge Cooler.

Process Description: Waste sources for Tank 241-SX-101 include the REDOX facility, and 241-BX, 241-S, 241-SX, and 241-U Tank Farms.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-SX-101 included: REDOX high-level waste and ion exchange waste, evaporator bottoms, partial neutralization feed, and complexed waste from 241-S, 241-BX, 241-SX, and 241-U Tank Farms.

Code: 241-SX-102	Classification: Accepted
Names: 241-SX-102; 241-SX-TK-102	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1954
Status: Inactive	End Date: 1/1/1980

Description: This unit is a third generation single-shell tank designed for self-boiling waste. Tank 241-SX-102 is the second tank of a three tank cascade series. This tank is a reinforced concrete, cylindrical structure with a steel liner. The tank is buried underground to provide radiation shielding.

Location: Tank 241-SX-102 is located in the 241-SX Tank Farm. This facility is located on Thirteenth Street, northwest of the REDOX Plant.

Related Sites/ Structures: Structures associated with Tank 241-SX-102 include: drywells, a liquid observation well, a hydrogen monitor, temperature and surface level measurement instruments. This tank is actively vented through Tank 241-SX-109 which is connected to the 241-SX Sludge Cooler.

Process Description: Waste sources for Tank 241-SX-102 include the REDOX facility, and the 241-BX, 241-TX, 241-SX, and 241-U Tank Farms.

Waste Type: Storage Tank

Waste Description: Waste transferred to 241-SX-102 included: REDOX high-level waste, carbonate waste, concrete, REDOX high-level waste, ion exchange waste, evaporator bottoms, and partial neutralization feed from 241-BX, 241-SX, 241-TX, and 241-S Tank Farms.

Code: 241-SX-103	Classification: Accepted
Names: 241-SX-103; 241-SX-TK-103	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1954
Status: Inactive	End Date: 1/1/1980

Description: This unit is a third generation single-shell tank designed for self-boiling waste. Tank 241-SX-103 is the third tank of a three tank cascade series. This tank is a reinforced concrete, cylindrical structure with a steel liner. The tank is buried underground to provide radiation shielding.

Location: Tank 241-SX-103 is located in the 241-SX Tank Farm. This facility is located on Thirteenth Street, northwest of the REDOX Plant.

Related Sites/ Structures: Structures associated with Tank 241-SX-103 include: drywells, a liquid observation well, a hydrogen monitor, temperature and surface level measurement instruments. This tank is actively vented through Tank 241-SX-109 which is connected to the 241-SX Sludge Cooler.

Process Description: Waste sources for Tank 241-SX-103 include the REDOX facility, and the 241-BX, 241-S, and 241-SX Tank Farms.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-SX-103 included: REDOX high-level waste, concrete, coating waste, evaporator bottoms, organic wash waste, and partial neutralization feed from 241-BX, 241-SX, and 241-S Tank Farms.

Code: 241-SX-104	Classification: Accepted
Names: 241-SX-104; 241-SX-TK-104	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1980

Description: This unit is a third generation single-shell tank designed for self-boiling waste. Tank 241-SX-104 is the first tank of a three tank cascade series. This tank is a reinforced concrete, cylindrical structure with a steel liner. The tank is buried underground to provide radiation shielding.

Location: Tank 241-SX-104 is located in the 241-SX Tank Farm. This facility is located on Thirteenth Street, northwest of the REDOX Plant.

Related Sites/ Structures: Structures associated with Tank 241-SX-104 include: drywells, a liquid observation well, a hydrogen monitor, temperature and surface level measurement instruments. This tank is actively vented through Tank 241-SX-109 which is connected to the 241-SX Sludge Cooler.

Process Description: Waste sources for Tank 241-SX-104 include the REDOX facility, the 241-S, and the 241-SX Tank Farms.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-SX-104 included: REDOX high-level waste and ion exchange waste, double-shell slurry feed, and evaporator bottoms from the 241-S and the 241-SX Tank Farms.

Code: 241-SX-105	Classification: Accepted
Names: 241-SX-105; 241-SX-TK-105	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1980

Description: This unit is a third generation single-shell tank designed for self-boiling waste. Tank 241-SX-105 is the second tank of a three tank cascade series. This tank is a reinforced concrete, cylindrical structure with a steel liner. The tank is buried underground to provide radiation shielding.

Location: Tank 241-SX-105 is located in the 241-SX Tank Farm. This facility is located on Thirteenth Street, northwest of the REDOX Plant.

Related Sites/ Structures: Structures associated with Tank 241-SX-105 include: lateral wells, drywells, a liquid observation well, a hydrogen monitor, temperature and surface level measurement instruments.

This tank is actively vented through Tank 241-SX-109 which is connected to the 241-SX Sludge Cooler.

Process Description: Waste sources for Tank 241-SX-105 include the REDOX facility, the 241-BX, 241-S, 241-TX and 241-U Tank Farms.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-SX-105 included: REDOX high-level waste and ion exchange waste, double-shell slurry feed, evaporator bottoms, and partial neutralization feed from 241-BX, 241-S, 241-TX, and 241-U Tank Farms.

Code: 241-SX-106 **Classification:** Accepted

Names: 241-SX-106; 241-SX-TK-106 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1954

Status: Inactive **End Date:** 1/1/1980

Description: This unit is a third generation single-shell tank designed for self-boiling waste. Tank 241-SX-106 is the third tank of a three tank cascade series. This tank is a reinforced concrete, cylindrical structure with a steel liner. The tank is buried underground to provide radiation shielding.

Location: Tank 241-SX-106 is located in the 241-SX Tank Farm. This facility is located on Thirteenth Street, northwest of the REDOX Plant.

Related Sites/Structures: Structures associated with Tank 241-SX-106 include drywells, a liquid observation well, a hydrogen monitor, temperature and surface level measurement instruments. This tank is actively vented through Tank 241-SX-109 which is connected to the 241-SX Sludge Cooler.

Process Description: Waste sources for Tank 241-SX-106 include the REDOX facility, B Plant, PUREX, and the 241-B, 241-C, 241-S, 241-SY, 241-SX, 241-TX and 241-U Tank Farms.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-SX-106 included: Hanford laboratory waste, Pacific Northwest Laboratory waste, REDOX and waste fractionation ion exchange waste, evaporator bottoms, B Plant low level waste, PUREX low level waste, coating waste, and partial neutralization feed from 241-B, 241-BX, 241-C, 241-S, 241-SX, 241-SY, 241-TX, and 241-U Tank Farms.

Code: 241-SX-107 **Classification:** Accepted

Names: 241-SX-107; 241-SX-TK-107 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1956

Status: Inactive **End Date:** 1/1/1964

Description: This unit is a third generation single-shell tank designed for self-boiling waste. Tank 241-SX-107 is the first tank of a three tank cascade series. This tank is a reinforced concrete, cylindrical structure with a steel liner. The tank is buried underground to provide radiation shielding.

Location: Tank 241-SX-107 is located in the 241-SX Tank Farm. This facility is located on Thirteenth Street, northwest of the REDOX Plant.

Related Sites/Structures: Structures associated with Tank 241-SX-107 include lateral wells, drywells, temperature and surface level measurement instruments. This tank is actively ventilated through the 241-SX Sludge Cooler.

Process Description: Waste sources for Tank 241-SX-107 include the REDOX facility, 100 F Area, and the 241-SX Tank Farm.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-SX-107 included: coating waste and REDOX high-level waste. The unit contains 41 small bottles of neutralized waste from 100 F Area, each containing less than 1 gram (0.04 ounce) Plutonium 239.

Code: 241-SX-108 **Classification:** Accepted

Names: 241-SX-108; 241-SX-TK-108 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1955

Status: Inactive **End Date:** 1/1/1962

Description: This unit is a third generation single-shell tank designed for self-boiling waste. Tank 241-SX-108 is the first tank of a three tank cascade series. This tank is a reinforced concrete, cylindrical structure with a steel liner. The tank is buried underground to provide radiation shielding.

Location: Tank 241-SX-108 is located in the 241-SX Tank Farm. This facility is located on Thirteenth Street, northwest of the REDOX Plant.

Related Sites/Structures: Structures associated with Tank 241-SX-108 include: lateral wells, drywells, temperature and surface level measurement instruments. This tank is actively vented through the 241-SX Sludge Cooler.

Process Description: Waste sources for Tank 241-SX-108 include the REDOX facility, and the 241-SX Tank Farm.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-SX-108 included: REDOX high-level waste, concrete, and supernatant containing REDOX high-level waste from the 241-SX Tank Farm.

Code: 241-SX-109 **Classification:** Accepted

Names: 241-SX-109; 241-SX-TK-109 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1955

Status: Inactive **End Date:** 1/1/1965

Description: This unit is a third generation single-shell tank designed for self-boiling waste. Tank 241-SX-109 is the third tank of a three tank cascade series. This tank is a reinforced concrete, cylindrical structure with a steel liner. The tank is buried underground to provide radiation shielding.

Location: Tank 241-SX-109 is located in the 241-SX Tank Farm. This facility is located on Thirteenth Street, northwest of the REDOX Plant.

Related Sites/Structures: Structures associated with Tank 241-SX-109 include: lateral wells, drywells, hydrogen monitor, temperature and surface level measurement instruments. Tanks 241-SX-101 through Tank 241-SX-106 are actively vented through Tank 241-SX-109 which is connected to the 241-SX Sludge Cooler.

Process Description: Waste sources for Tank 241-SX-109 include the REDOX Facility and the 241-SX Tank Farm.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-SX-109 included: REDOX high-level waste and supernatant containing REDOX high-level waste from the 241-SX Tank Farm.

Code: 241-SX-110

Classification: Accepted

Names: 241-SX-110; 241-SX-TK-110

Reclassification: None

Type: Single-Shell Tank

Start Date: 1/1/1960

Status: Inactive

End Date: 1/1/1976

Description: This unit is a third generation single-shell tank designed for self-boiling waste. Tank 241-SX-110 is the first tank of a three tank cascade series. This tank is a reinforced concrete, cylindrical structure with a steel liner. The tank is buried underground to provide radiation shielding.

Location: Tank 241-SX-110 is located in the 241-SX Tank Farm. This facility is located on Thirteenth Street, northwest of the REDOX Plant.

Related Sites/ Structures: Structures associated with Tank 241-SX-110 include: lateral wells, drywells, temperature and surface level measurement instruments. This tank is actively vented through the 241-SX Sludge Cooler.

Process Description: Waste sources for Tank 241-SX-110 include the REDOX Facility, Pacific Northwest Laboratory, B Plant, the 241-B, 241-BX, 241-SX, and 241-U Tank Farms.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-SX-110 included: REDOX high-level waste, concrete, Pacific Northwest Laboratory waste, B Plant low-level waste, ion exchange waste, evaporator bottoms, and 224-U waste from 241-B, 241-BX, and 241-SX Tank Farms. Additionally sixteen plastic bottles or containers containing a total of 4 ounces (110 grams) natural uranium, 2 ounces (62 grams) depleted uranium, 0.21 ounce (6 grams) enriched uranium, and 7 ounces (204 grams) plutonium were added to this unit.

Code: 241-SX-111

Classification: Accepted

Names: 241-SX-111; 241-SX-TK-111

Reclassification: None

Type: Single-Shell Tank

Start Date: 1/1/1956

Status: Inactive

End Date: 1/1/1974

Description: This unit is a third generation single-shell tank designed for self-boiling waste. Tank 241-SX-111 is the second tank of a three tank cascade series. This tank is a reinforced concrete, cylindrical structure with a steel liner. The tank is buried underground to provide radiation shielding.

Location: Tank 241-SX-111 is located in the 241-SX Tank Farm. This facility is located on Thirteenth Street, northwest of the REDOX Plant.

Related Sites/ Structures: Structures associated with Tank 241-SX-111 include: lateral wells, drywells, temperature and surface level measurement instruments. This tank is actively vented through the 241-SX Sludge Cooler.

Process Description: The waste source for Tank 241-SX-111 is the REDOX Facility.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-SX-111 included: REDOX high-level waste and supernatant containing REDOX high-level waste and REDOX ion exchange waste from the 241-SX Tank Farm.

Code: 241-SX-112	Classification: Accepted
Names: 241-SX-112; 241-SX-TK-112	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1956
Status: Inactive	End Date: 1/1/1969

Description: This unit is a third generation single-shell tank designed for self-boiling waste. Tank 241-SX-112 is the third tank of a three tank cascade series. This tank is a reinforced concrete, cylindrical structure with a steel liner. The tank is buried underground to provide radiation shielding.

Location: Tank 241-SX-112 is located in the 241-SX Tank Farm. This facility is located on Thirteenth Street, northwest of the REDOX Plant.

Related Sites/ Structures: Structures associated with Tank 241-SX-112 include: lateral wells, drywells, temperature and surface level measurement instruments. This tank is actively vented through the 241-SX Sludge Cooler.

Process Description: Waste sources for Tank 241-SX-112 include the REDOX Facility, and the 241-SX Tank Farm.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-SX-112 included: REDOX high-level waste and supernatant containing REDOX high-level waste from 241-SX Tank Farm.

Code: 241-SX-113	Classification: Accepted
Names: 241-SX-113; 241-SX-TK-113	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1958
Status: Inactive	End Date: 1/1/1962

Description: This unit is a third generation single-shell tank designed for self-boiling waste. Tank 241-SX-113 is the first tank of a three tank cascade series. This tank is a reinforced concrete, cylindrical structure with a steel liner. The tank is buried underground to provide radiation shielding.

Location: Tank 241-SX-113 is located in the 241-SX Tank Farm. This facility is located on Thirteenth Street, northwest of the REDOX Plant.

Related Sites/ Structures: Structures associated with Tank 241-SX-113 include: lateral wells, drywells, temperature and surface level measurement instruments. This tank has passive ventilation.

Process Description: The waste source for Tank 241-SX-113 is the REDOX Facility.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-SX-113 included: REDOX high-level waste. Diatomaceous earth was also added in 1962.

Code: 241-SX-114	Classification: Accepted
Names: 241-SX-114; 241-SX-TK-114	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1957
Status: Inactive	End Date: 1/1/1972

Description: This unit is a third generation single-shell tank designed for self-boiling waste. Tank 241-SX-114 is the second tank of a three tank cascade series. This tank is a reinforced concrete, cylindrical structure with a steel liner. The tank is buried underground to provide radiation shielding.

Location: Tank 241-SX-114 is located in the 241-SX Tank Farm. This facility is located on Thirteenth Street, northwest of the REDOX Plant.

Related Sites/ Structures: Structures associated with Tank 241-SX-114 include: lateral wells, drywells, temperature and surface level measurement instruments. This tank is actively vented through the 241-SX Sludge Cooler.

Process Description: The waste source for Tank 241-SX-114 is the REDOX Facility and the 241-SX Tank Farm.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-SX-114 included: REDOX high-level waste and ion exchange waste, and evaporator bottoms from 241-SX Tank Farm.

Code: 241-SX-115	Classification: Accepted
Names: 241-SX-115; 241-SX-TK-115	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1958
Status: Inactive	End Date: 1/1/1965

Description: This unit is a third generation single-shell tank designed for self-boiling waste. Tank 241-SX-115 is the third tank of a three tank cascade series. This tank is a reinforced concrete, cylindrical structure with a steel liner. The tank is buried underground to provide radiation shielding.

Location: Tank 241-SX-115 is located in the 241-SX Tank Farm. This facility is located on Thirteenth Street, northwest of the REDOX Plant.

Related Sites/ Structures: Structures associated with Tank 241-SX-115 include: lateral wells, drywells, and a surface level measurement instrument. This tank has passive ventilation.

Process Description: The waste source for Tank 241-SX-115 is the REDOX Facility.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-SX-115 included: REDOX high-level waste and supernatant containing REDOX high-level waste.

Code: 241-SX-151	Classification: Accepted
Names: 241-SX-151; 241-SX-151 Diversion Box	Reclassification: None
Type: Diversion Box	Start Date: 1/1/1954

Status: Inactive**End Date:** 1/1/1983**Description:** The diversion box is a rectangular reinforced concrete structure. Most of the structure is below ground. A few inches of the structure that extends above ground is covered with a gray weather coating. The tank farm fence is posted with various radiological postings.**Location:** The 241-SX-151 Diversion Box is located northeast of tank 241-SX-101, inside the 241-SX Tank Farm fence.**Related Sites/ Structures:** The 241-SX-151 Diversion Box is associated with the 241-S-151 and 241-SX-152 Diversion Boxes and the 241-SX Tank Farm.**Process Description:** The 241-SX-151 Diversion Box was used to direct liquid waste to other tank farm locations in 200 East and West Areas via jumper connections and underground transfer lines.**Waste Type:** Process Effluent**Waste Description:** This unit was used for transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operation. Lead shielding may also be contained inside the diversion box.**Waste Type:** Equipment**Waste Description:** Equipment associated with the diversion box includes transfer piping and nozzles. Waste lead is also stored in the diversion box.

Code: 241-SX-152**Classification:** Accepted**Names:** 241-SX-152; 241-SX-152 Diversion Box; 241-SX-152 Transfer Box**Reclassification:** None**Type:** Diversion Box**Start Date:** 1/1/1954**Status:** Inactive**End Date:** 1/1/1981**Description:** The diversion box is a rectangular reinforced concrete structure. Most of the structure is below ground. A few inches of the structure that extends above ground is covered with a gray weather coating. The tank farm fence is posted with various radiological postings.**Location:** The 241-SX-152 Diversion Box is located north of Tank 241-SX-101, inside the 241-SX Tank Farm fence.**Related Sites/ Structures:** The 241-SX-152 Diversion Box is associated with the 241-SX-151 Diversion Box, the 241-U-151 Diversion Box, 231-SX-302 catch tank through line V595, and the 241-SX Tank Farm.**Process Description:** The 241-SX-152 Diversion Box was used to direct liquid waste to other tank farm locations in 200 East and West Areas via jumper connections and underground transfer lines.**Waste Type:** Process Effluent**Waste Description:** This unit was used for transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operation. Lead shielding may also be contained inside the diversion box.**Waste Type:** Equipment**Waste Description:** Equipment associated with the diversion box includes transfer piping and nozzles. Waste lead is also stored in the diversion box.

Code: 241-SX-302**Classification:** Accepted

Names: 241-SX-302; 241-SX-302 Catch Tank; Line V595; SX-304 **Reclassification** None

Type: Catch Tank **Start Date:** 1/1/1954

Status: Inactive **End Date:** 1/1/1983

Description: The 241-SX-302 Catch Tank an underground, horizontal, cylindrical steel tank. Three yellow risers are visible on the surface. It is surrounded with post and chain and marked with radiological and IMUST signs.

Location: The 241-SX-302 Catch Tank is located east of the 241-SX-101 Tank, inside the tank farm fence.

Related Sites/ Structures: The 241-SX-302 Catch Tank is associated with drain line V595, the 241-SX-151 Diversion Box and the 241-SX-152 Diversion Box.

Process Description: Drainage and leaks from the 241-SX-151 Diversion Box and the 241-SX-152 Diversion Boxes collected and were stored in the 241-SX-302 Catch Tank.

Waste Type: Process Effluent

Waste Description: This tank collected excess and leaking waste that transferred through the 241-SX-151 and 241-SX-152 Diversion Boxes. In 1993, the tank was estimated to contain 1152 liters (305 gallons) of liquid supernate and 3969 liters (1050 gallons) of sludge.

Code: 241-SX-401 **Classification:** Accepted

Names: 241-SX-401; 241-SX-401 Condenser Shielding Building; 241-SX-401 Waste Disposal Condenser House **Reclassification** None

Type: Process Unit/Plant **Start Date:** 1/1/1954

Status: Inactive **End Date:** 1/1/1975

Description: This unit is constructed of reinforced concrete with walls varying in thickness from 0.31 to 0.77 meters (1 to 2.5 feet) thick for shielding purposes.

Location: The 241-SX-401 Condenser Building is located west of Tank 241-SX-106, inside the 241-SX Tank Farm.

Related Sites/ Structures: A dry well is associated with the condenser building, 216-S-21 crib and pipeline 200-W-160-PL.

Process Description: This building processed condensation from the 241-SX Tank Farm off gases.

Waste Type: Equipment

Waste Description: The unit contains radioactively contaminated equipment and concrete. The quantity of waste has not been determined. Radiation levels are high.

Code: 241-SX-402 **Classification:** Accepted

Names: 241-SX-402; 241-SX-402 Condenser Shielding Building; 241-SX-402 Waste Disposal Condenser House **Reclassification** None

Type: Process Unit/Plant **Start Date:** 1/1/1954

Status: Inactive **End Date:** 1/1/1975

Description: This unit is constructed of reinforced concrete with walls varying in thickness from 0.31 to 0.77 meters (1 to 2.5 feet) thick for shielding purposes.

Location: The 241-SX-402 Condenser Building is located west of Tank 241-SX-109 within 241-SX Tank Farm.

Related Sites/ Structures: A dry well is associated with the condenser building, 216-S-21 crib and pipeline 200-W-160-PL.

Process Description: This unit processed condensation for the 241-SX Tank Farm off gases.

Waste Type: Equipment

Waste Description: The unit contains radioactively contaminated equipment and concrete. The quantity of waste has not been determined. The unit is only mildly contaminated.

Code: 200-W-96 **Classification:** Accepted

Names: 200-W-96; Contaminated Soil at 241-S/SX/SY Tank Farm **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The site is the soil inside and adjacent to the chain link fence that surrounds the 241-S/SX/SY Tank Farms. Various radiological postings and warning signs are attached to the chain link fence. The interior of the tank farm complex is covered with gravel. Many risers and monitoring devices for the underground structures are visible on the surface. The individual unplanned releases associated with the 241-S, SX, SY Tank Farms are not separately marked or posted. Occasionally, radioactive contamination is found adjacent to the outside of the tank farm fence, resulting in a contamination zone extension around the tank farm perimeter. These areas will also be considered tank farm soil. The 216-S-3 crib, 216-S-15 overflow pond and a portion of the 242-S Evaporator building are also located inside the tank farm fence.

Location: The site is located east of Cooper Ave., inside 200 West Area.

Release Description: The exact extent (horizontal and vertical) of the soil contaminated by unplanned releases that occurred within this farm over the years are not known. Some of the single shell tanks have leaked to the soil below the tank farm. Other releases spread contamination to the surface soil surrounding the tanks. On 7/27/2007, a spill was reported inside the 241-S Tank Farm at the S-102 Pump Pit. Higher than normal radiation levels (200-250 mr/hr at 8-15 feet) were observed. A spill of liquid from an above ground transfer line occurred while attempting to backflush a clogged pump screen. The release was estimated to be less than 100 gallons.

Related Sites/ Structures: Unplanned Releases UPR-200-W-49, UPR-200-W-50, UPR-200-W-80, UPR-200-W-81, UPR-200-W-127, UPR-200-W-140, UPR-200-W-141, UPR-200-W-142, UPR-200-W-143, UPR-200-W-144, UPR-200-W-145, UPR-200-W-146, and 200-W-37 occurred inside the tank farm and were consolidated into 200-W-96. 200-W-54 is located adjacent to the tank farm fence and is associated with the 241-S/SX/SY Tank Farms operations.

Waste Type: Process Effluent

Waste Description: Liquid releases occurred from underground leaks in tanks and transfer lines. Airborne contamination spreads occurred from activities conducted in valve pits and diversion boxes. Both types of releases contributed to the contamination in the soil.

WMA T

Code: 241-T-101	Classification: Accepted
Names: 241-T-101; 241-T-TK-101	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1979

Description: This unit is a first generation, underground single-shell storage tank. Tank 241-T-101 is the first tank of a cascade that also includes tanks 241-T-102 and 241-T-103. The tank is cylindrical, dome-roofed, and concrete-reinforced with a steel liner lying across the tank bottom and up the concrete wall. This unit is below grade for shielding purposes.

Location: Tank 241-T-101 is located on the north side of the 241-T Tank Farm, which is located north of the intersection of 23rd Street and Camden Avenue.

Related Sites/Structures: Structures associated with Tank 241-T-101 include: thermocouple tree, liquid observation wells, surface level measurement device, and leak detection dry wells.

Process Description: Tank 241-T-101 received waste from multiple sources including Tank 241-SX-106, Tank 241-S-110, B Plant and T Plant.

Waste Type: Storage Tank

Waste Description: Waste sources for 241-T-101 include coating waste from Tank 241-SX-106, coating and ion exchange waste from B Plant, and metal waste from T Plant operations.

Code: 241-T-102	Classification: Accepted
Names: 241-T-102; 241-T-TK-102	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1945
Status: Inactive	End Date: 1/1/1976

Description: This unit is a first generation, underground single-shell storage tank. Tank 241-T-102 is the second tank of a cascade that also includes tanks 241-T-101, and 241-T-103. The tank is cylindrical, dome roofed, concrete reinforced with a steel liner lying across the tank bottom and up the concrete wall. This unit is below grade for shielding purposes.

Location: Tank 241-T-102 is located on the north side of the 241-T Tank Farm, which is located north of the intersection of 23rd Street and Camden Avenue.

Related Sites/Structures: Structures associated with Tank 241-T-102 include surface level measurement device, liquid observation well, salt well screen, and nozzles.

Process Description: Tank 241-T-102 received waste cascading from Tank 241-T-101. Additional sources include waste from Tank 241-S-110, Tank 241-C-102, and the T-Plant.

Waste Type: Storage Tank

Waste Description: Waste sources for the 241-T-102 include coating waste from Tank 241-SX-106, coating and ion exchange waste from B Plant, and metal waste from the T Plant operations.

Code: 241-T-103	Classification: Accepted
Names: 241-T-103; 241-T-TK-103	Reclassification: None

Type: Single-Shell Tank	Start Date: 1/1/1945
Status: Inactive	End Date: 1/1/1974

Description: This unit is a first generation, underground single-shell storage tank. Tank 241-T-103 is the third and final tank of a cascade that also includes tanks 241-T-101 and 241-T-102. The tank is a cylindrical, dome roofed, concrete reinforced structure with a steel liner lying across the tank bottom and up the concrete wall. This unit is below grade for shielding purposes.

Location: Tank 241-T-103 is located in the center portion of the 241-T Tank Farm. The 241-T Farm is located north of the intersection of 23rd Street and Camden Avenue.

Related Sites/ Structures: Associated structures include the thermocouple tree, the dry wells, and the manual and automatic surface monitors.

Process Description: Waste sources for Tank 241-T-103 include waste cascaded from Tanks 241-T-101 and 241-T-102, waste from Tank 241-C-102 and waste from the T Plant operations.

Waste Type: Storage Tank

Waste Description: Waste in Tank 241-T-103 include bismuth phosphate metal waste, low level coating and supernate from the B Plant, REDOX ion exchange, REDOX high level waste, and evaporation bottoms.

Code: 241-T-104	Classification: Accepted
Names: 241-T-104; 241-T-TK-104	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1946
Status: Inactive	End Date: 1/1/1974

Description: This unit is a first generation, underground single-shell storage tank. Tank 241-T-104 is the first tank of the second cascade of tanks receiving waste in the T Farm. Tank 241-T-105 and 106 are the second and third tanks in the series.

Location: Tank 241-T-104 is located in the eastern portion of the 241-T Tank Farm, north of the intersection of 23rd Street and Camden Avenue.

Related Sites/ Structures: Structures associated with 241-T-104 include a temperature element, a liquid observation well, drywells, passive ventilation, and a surface level measurement device.

Process Description: Tank 241-T-104 received first cycle decontamination waste.

Waste Type: Storage Tank

Waste Description: Tank 241-T-104 received bismuth phosphate first cycle waste.

Code: 241-T-105	Classification: Accepted
Names: 241-T-105; 241-T-TK-105	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1946
Status: Inactive	End Date: 1/1/1976

Description: This unit is a first generation, underground single-shell tank. Tank 241-T-105 is the second tank of the second cascade of tanks receiving waste in the 241-T Farm. The tank is cylindrical,

dome-roofed, and concrete-reinforced with a steel liner lying across the tank bottom and up the concrete wall. This unit is below grade for shielding purposes.

Location: Tank 241-T-105 is located in the center portion of the 241-T Tank Farm, which is located north of the intersection of 23rd Street and Camden Avenue.

Related Sites/ Structures: Structures associated with 241-T-105 include drywells, passive ventilation, and a surface level measurement device.

Process Description: Waste sources for 241-T-105 include decontamination waste coating and ion exchange waste.

Waste Type: Storage Tank

Waste Description: Waste sources include bismuth phosphate first-cycle and second-cycle waste, REDOX coating waste, Hanford Laboratory operations waste, supernatant containing low-level waste, and ion exchange waste.

Code: 241-T-106	Classification: Accepted
Names: 241-T-106; 241-T-TK-106	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1947
Status: Inactive	End Date: 1/1/1973

Description: This unit is a first generation, underground single-shell tank. Tank 241-T-106 is the third tank of the second cascade of tanks receiving waste in the 241-T-Farm. The tank is cylindrical, dome-roofed, and concrete-reinforced with a steel liner lying across the tank bottom and up the concrete well. This unit is below grade for shielding purposes.

Location: Tank 241-T-106 is located in the western portion of the 241-T Tank Farm, which is located north of the intersection of 23rd Street and Camden Avenue.

Release Description: See UPR-200-W-148.

Related Sites/ Structures: Structures associated with 241-T-106 include dry wells, passive ventilation, temperature monitoring device, and surface level measurement devices.

Process Description: The waste source for 241-T-106 is second cycle decontamination cascade overflow waste from Tank 241-T-105.

Waste Type: Storage Tank

Waste Description: Waste types transferred to Tank 241-T-106 include bismuth phosphate first cycle waste, supernatant containing coating waste, low-level waste from B Plant, and ion exchange waste.

Code: 241-T-107	Classification: Accepted
Names: 241-T-107; 241-T-TK-107	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1976

Description: This unit is a first generation, underground single-shell tank. Tank 241-T-107 is the first tank of the third cascade of tanks receiving waste in the T-Farm. The tank is cylindrical, dome-roofed, and concrete-reinforced with a steel liner lying across the tank bottom and up the concrete well. This unit is below grade for shielding purposes.

Location: Tank 241-T-107 is located in the eastern portion of the 241-T Tank Farm, which is located north of the intersection of 23rd Street and Camden Avenue.

Related Sites/ Structures: Structures associated with 241-T-107 include dry wells, passive ventilation, temperature measurement device, and surface level measurement devices.

Process Description: Waste sources for Tank 241-T-107 include B Plant ion exchange waste from Tank 241-BX-104, coating waste from Tank 241-C-102, tributyl phosphate waste and first cycle decontamination waste.

Waste Type: Storage Tank

Waste Description: Waste types transferred to Tank 241-T-107 include first cycle bismuth phosphate waste, tributyl phosphate, ion exchange waste, and coating waste.

Code: 241-T-108 **Classification:** Accepted

Names: 241-T-108; 241-T-TK-108 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1945

Status: Inactive **End Date:** 1/1/1974

Description: This unit is a first generation, underground single-shell tank. Tank 241-T-108 is the second tank of the third cascade of tanks receiving waste in the T-Farm. The tank is cylindrical, dome-roofed, and concrete-reinforced with a steel liner lying across the tank bottom and up the concrete well. This unit is below grade for shielding purposes.

Location: Tank 241-T-108 is located in the center of the 241-T Tank Farm, which is located north of the intersection of 23rd Street and Camden Avenue.

Related Sites/ Structures: Structures associated with 241-T-108 include drywells, passive ventilation, temperature measurement device, and surface level measurement devices.

Process Description: Waste sources for Tank 241-T-108 include: evaporator bottoms from Tank 241-TX-117, tributyl phosphate process waste, and first cycle decontamination waste. It received cascade overflow waste from Tank 241-T-107.

Waste Type: Storage Tank

Waste Description: Waste types transferred to Tank 241-T-108 include: tributyl phosphate, bismuth phosphate first-cycle waste, Hanford Laboratory operations waste, supernatant containing tributyl phosphate waste, B Plant low-level waste, ion exchange waste, and evaporator bottoms.

Code: 241-T-109 **Classification:** Accepted

Names: 241-T-109; 241-T-TK-109 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1945

Status: Inactive **End Date:** 1/1/1974

Description: This unit is a first generation, underground single-shell tank. Tank 241-T-109 is the third tank of the third cascade of tanks receiving waste in the T Farm. The tank is cylindrical, dome-roofed, and concrete-reinforced with a steel liner lying across the tank bottom and up the concrete wall. This unit is below grade for shielding purposes.

Location: Tank 241-T-109 is located in the western portion of the 241-T Tank Farm, which is located north of the intersection of 23rd Street and Camden Avenue.

Related Sites/ Structures: Structures associated with the 241-T-109 include drywells, passive ventilation, temperature, and surface level measurement device.

Process Description: Waste sources for Tank 241-T-109 include saltcake from 241-T Evaporator that was added from Tank 241-TX-117, tributyl phosphate, and first cycle decontamination cascade overflow waste from Tank 241-T-108.

Waste Type: Storage Tank

Waste Description: Waste types transferred to Tank 241-T-109 include: bismuth phosphate first-cycle waste, tributyl phosphate waste, evaporator bottoms, B Plant low-level waste, ion exchange waste, and waste from 241-T and -TX tank farms.

Code: 241-T-110 **Classification:** Accepted

Names: 241-T-110; 241-T-TK-110 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1944

Status: Inactive **End Date:** 1/1/1976

Description: This unit is a first generation, underground single-shell tank. Tank 241-T-110 is the first tank of the fourth cascade of tanks receiving waste in the T Farm. The tank is cylindrical, dome-roofed, and concrete-reinforced with a steel liner lying across the tank bottom and up the concrete wall. This unit is below grade for shielding purposes.

Location: Tank 241-T-110 is located in the southeastern portion of the 241-T Tank Farm, which is located north of the intersection of 23rd Street and Camden Avenue.

Related Sites/ Structures: Structures associated with 241-T-110 include drywells, passive ventilation, liquid observation well, and a surface level measurement device.

Process Description: Waste sources for Tank 241-T-110 include 224-U waste and second cycle decontamination waste.

Waste Type: Storage Tank

Waste Description: Waste types transferred to 241-T-110 include bismuth phosphate second-cycle waste and the 224-U Building waste.

Code: 241-T-111 **Classification:** Accepted

Names: 241-T-111; 241-T-TK-111 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1945

Status: Inactive **End Date:** 1/1/1974

Description: This unit is a first generation, underground single-shell tank. Tank 241-T-111 is the second tank of the fourth cascade of tanks receiving waste in the T Farm. The tank is cylindrical, dome-roofed, and concrete-reinforced with a steel liner lying across the tank bottom and up the concrete wall. This unit is below grade for shielding purposes.

Location: Tank 241-T-111 is located in the southern portion of the 241-T Tank Farm, which is located north of the intersection of 23rd Street and Camden Avenue.

Related Sites/ Structures: Structures associated with 241-T-110 include drywells, passive ventilation, liquid observation well, and a surface level measurement device.

Process Description: Waste sources for Tank 241-T-111 include 224-U waste and second cycle decontamination cascade overflow waste from Tank 241-T-110.

Waste Type: Storage Tank

Waste Description: Waste types transferred to Tank 241-T-111 include: bismuth phosphate second-cycle waste and 224-U Building waste.

Code: 241-T-112 **Classification:** Accepted

Names: 241-T-112; 241-T-TK-112 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1946

Status: Inactive **End Date:** 1/1/1976

Description: This unit is a first generation, underground single-shell tank. Tank 241-T-112 is the third tank of the fourth cascade of tanks receiving waste in the T Farm. The tank is cylindrical, dome-roofed, and concrete-reinforced with a steel liner lying across the tank bottom and up the concrete wall. This unit is below grade for shielding purposes.

Location: Tank 241-T-112 is located in the southwestern portion of the 241-T Tank Farm, which is located north of the intersection of 23rd Street and Camden Avenue.

Related Sites/Structures: Structures associated with 241-T-112 include drywells, passive ventilation, temperature and surface level measurement devices.

Process Description: Waste sources for tank 241-T-112 include second cycle decontamination waste, decontamination waste, and laboratory waste.

Waste Type: Storage Tank

Waste Description: Waste types transferred to Tank 241-T-112 include: bismuth phosphate second-cycle waste, Pacific Northwest Laboratory waste, decontamination waste; and supernatant containing B Plant low-level waste and ion exchange waste from the 241-T tank.

Code: 241-T-151 **Classification:** Accepted

Names: 241-T-151; 241-T-151 Diversion Box **Reclassification:** None

Type: Diversion Box **Start Date:** 1/1/1944

Status: Inactive **End Date:** 1/1/1980

Description: The diversion box is a rectangular reinforced concrete structure. Most of the structure is below ground. A few inches of the structure that extends above ground is covered with a gray weather coating. The tank farm fence is posted with various radiological postings.

Location: The 241-T-151 Diversion Box is located near the southeast corner of 241-T Tank Farm, inside the tank farm fence.

Related Sites/Structures: The 241-T-151 Diversion Box is associated with the 241-T-153 and 241-U-151 Diversion Box, the 241-T-301 Catch Tank, and the 241-T Tank Farm.

Process Description: The 241-T-151 Diversion Box was used to direct liquid waste to other tank farm locations in 200 East and West Areas via jumper connections and underground transfer lines.

Waste Type: Process Effluent

Waste Description: This unit was used for transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operation. Lead shielding may also be contained inside the diversion box.

Waste Type: Equipment

Waste Description: Equipment associated with the diversion box includes transfer piping and nozzles. Waste lead is also stored in the diversion box.

Code: 241-T-152 **Classification:** Accepted

Names: 241-T-152; 241-T-152 Diversion Box **Reclassification:** None

Type: Diversion Box **Start Date:** 1/1/1944

Status: Inactive **End Date:** 1/1/1983

Description: The diversion box is a rectangular reinforced concrete structure. Most of the structure is below ground. A few inches of the structure that extends above ground is covered with a gray weather coating. The tank farm fence is posted with various radiological postings.

Location: The 241-T-152 Diversion Box is located in the southeastern portion of the 241-T Tank Farm.

Related Sites/Structures: The 241-T-152 Diversion Box is associated with the 241-T-301 Catch Tank, and Diversion Boxes 241-T-153, 241-TX-153, and 241-TX-155 and UPR-200-W-29 and UPR-200-W-97.

Process Description: The 241-T-152 Diversion Box was used transfer liquid waste to various locations including the 241-T Tank Farm, the 221-T Canyon Building, the 241-T-301 Catch Tank, and Diversion Boxes 241-T-153, 241-TX-153, and 241-TX-155 via underground transfer lines.

Waste Type: Equipment

Waste Description: Equipment associated with the 241-T-152 Diversion Box includes transfer piping and nozzles. Waste lead is also stored in the diversion box.

Waste Type: Process Effluent

Waste Description: This unit was used for transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operations. Lead shielding may also be contained inside the diversion box.

Code: 241-T-153 **Classification:** Accepted

Names: 241-T-153; 241-T-153 Diversion Box **Reclassification:** None

Type: Diversion Box **Start Date:**

Status: Inactive **End Date:**

Description: The diversion box is a rectangular reinforced concrete structure. Most of the structure is below ground. A few inches of the structure that extends above ground is covered with a gray weather coating. The tank farm fence is posted with various radiological postings.

Location: The 241-T-153 Diversion Box is located inside the 241-T Tank Farm, east of Tank 241-T-110.

Related Sites/Structures: The 241-T-153 Diversion Box is associated with the 241-T-301 Catch Tank, the 221-T Building, and Diversion Boxes 241-T-151, 241-T-152, 241-T-155 and 241-TX-153.

Process Description: The 241-T-153 Diversion Box was used to transfer liquid waste to various locations including the 241-T-301 Catch Tank, and the Diversion Boxes 241-T-155 and 241-TX-153 via

underground transfer lines.

Waste Type: Process Effluent

Waste Description: This unit was used for transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operations. Lead shielding may also be contained inside the diversion box.

Waste Type: Equipment

Waste Description: Equipment associated with this unit include transfer piping and nozzles. Waste lead is also stored in the diversion box.

Code: 241-T-201

Classification: Accepted

Names: 241-T-201; 241-T-TK-201

Reclassification: None

Type: Single-Shell Tank

Start Date: 1/1/1952

Status: Inactive

End Date: 1/1/1976

Description: This unit is an underground, concrete-reinforced vertical single-shell tank. Tank 241-T-201 has a steel liner and rests upon a concrete base slab. This unit is below grade for shielding purposes.

Location: Tank 241-T-201 is located in the western portion of the 241-T Tank Farm.

Related Sites/Structures: The tank is associated with the 216-T-32 crib and the 241-T-252 Diversion Box. Equipment associated with 241-T-201 includes passive ventilation, temperature, and surface level measurement devices.

Process Description: Some documents state the waste in 241-T-201 is from the 224-U Building. However, WHC-SD-WM-ER-351 states the 241-T-201 was full of "224" waste when initial level readings were taken in 1952, but does not specify if the waste was from 224-T or 224-U. ARH-2155 and RHO-CD-673 both state that the 216-T-32 Crib received 224-T waste via the 241-T-201 tank.

Waste Type: Storage Tank

Waste Description: Waste in Tank 241-T-201 is from the 224 Building.

Code: 241-T-202

Classification: Accepted

Names: 241-T-202; 241-T-TK-202

Reclassification: None

Type: Single-Shell Tank

Start Date: 1/1/1952

Status: Inactive

End Date: 1/1/1976

Description: This unit is an underground, concrete-reinforced vertical single-shell tank. Tank 241-T-202 has a steel liner and rests upon a concrete base slab. This unit is below grade for shielding purposes.

Location: Tank 241-T-202 is located in the western portion of the 241-T Tank Farm.

Related Sites/Structures: Structures associated with 241-T-202 include the 241-T-252 Diversion Box, passive ventilation, temperature, and surface level measurement devices.

Process Description: Some documents state the waste in 241-T-201 is from the 224-U Building. However, WHC-SD-WM-ER-351 states the 241-T-201 was full of "224" waste when initial level readings were taken in 1952, but does not specify if the waste was from 224-T or 224-U. ARH-2155 and RHO-CD-673 both say that the 216-T-32 Crib received 224-T waste via the 241-T-201 tank.

Waste Type: Storage Tank

Waste Description: Waste in Tank 241-T-202 is from the 224 Building.

Code: 241-T-203 **Classification:** Accepted

Names: 241-T-203; 241-T-TK-203 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1952

Status: Inactive **End Date:** 1/1/1976

Description: This unit is an underground, concrete-reinforced vertical single-shell tank. Tank 241-T-203 has a steel liner and rests upon a concrete base slab. This unit is below grade for shielding purposes.

Location: Tank 241-T-203 is located in the western portion of the 241-T Tank Farm.

Related Sites/ Structures: Structures associated with 241-T-203 include the 241-T-252 Diversion Box, passive ventilation, temperature, and surface level measurement devices.

Process Description: Some documents state the waste in 241-T-201 is from the 224-U Building. However, WHC-SD-WM-ER-351 states the 241-T-201 was full of "224" waste when initial level readings were taken in 1952, but does not specify if the waste was from 224-T or 224-U. ARH-2155 and RHO-CD-673 both say that the 216-T-32 Crib received 224-T waste via the 241-T-201 tank.

Waste Type: Storage Tank

Waste Description: Waste in Tank 241-T-203 is from the 224 Building.

Code: 241-T-204 **Classification:** Accepted

Names: 241-T-204; 241-T-TK-204 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1952

Status: Inactive **End Date:** 1/1/1976

Description: This unit is an underground, concrete-reinforced vertical single-shell tank. Tank 241-T-204 has a steel liner and rests upon a concrete base slab. This unit is below grade for shielding purposes.

Location: Tank 241-T-204 is located in the western portion of the 241-T Tank Farm.

Related Sites/ Structures: Structures associated with 241-T-204 include the 241-T-252 Diversion Box, passive ventilation, temperature, and surface level measurement devices.

Process Description: Some documents state the waste in 241-T-201 is from the 224-U Building. However, WHC-SD-WM-ER-351 states the 241-T-201 was full of "224" waste when initial level readings were taken in 1952, but does not specify if the waste was from 224-T or 224-U. ARH-2155 and RHO-CD-673 both say that the 216-T-32 Crib received 224-T waste via the 241-T-201 tank.

Waste Type: Storage Tank

Waste Description: Waste in Tank 241-T-204 is from the 224 Building.

Code: 241-T-252 **Classification:** Accepted

Names: 241-T-252; 241-T-252 Diversion Box **Reclassification** None

Type: Diversion Box **Start Date:** 1/1/1944

Status: Inactive **End Date:** 1/1/1983

Description: This unit is a reinforced concrete structure, constructed mostly below grade. The 241-T-252 has a concrete cover block with lifting bails. The diversion box has been entirely coated with protective foam.

Location: The 241-T-252 Diversion Box is located in the southwestern portion of the 241-T Tank Farm, southwest of the 241-T-112 Tank.

Related Sites/ Structures: The diversion box is associated with 241-T-201, 241-T-202, 241-T-203, 241-T-204, 241-T-153, 221-T, and 241-T Tank Farm. The diversion box drains to the 241-T-301 Catch Tank.

Process Description: This unit transported waste solutions from processing and decontamination operations.

Waste Type: Process Effluent

Waste Description: This unit transported various mixed waste solutions from processing and decontamination operations. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Waste Type: Equipment

Waste Description: Transfer piping and nozzles are associated with the 241-T-252 Diversion Box.

Waste Type: Equipment

Waste Description: Waste lead is also stored in the diversion box.

Code: 241-T-301B **Classification:** Accepted

Names: 241-T-301B; 241-T-301-B; Lines V664 and V727; 241-T-0301; 241-T-301 Catch Tank **Reclassification** None

Type: Catch Tank **Start Date:** 1/1/1944

Status: Inactive **End Date:** 1/1/1985

Description: The 241-T-301B Catch Tank is an underground, reinforced concrete tank. The tank is surrounded with posts and chain and labeled with IMUST signs. This unit has a concrete-domed lid and uses a vertical construction design. The catch tank is below grade for shielding purposes.

Location: The 241-T-301B catch tank is located in the southwestern portion of the 241-T Tank Farm, east of the 241-T-252 Diversion Box.

Related Sites/ Structures: The 241-T-301 Catch Tank is associated with the 241-T-151, 241-T-152, 241-T-153, and 241-T-252 diversion boxes. Drain lines V664 and V727 connect the diversion boxes to the catch tank.

Process Description: This unit collected overflow waste from diversion boxes 241-T-151, 241-T-152, 241-T-153, and 241-T-252 via a 15.2 centimeter (6 inch) schedule 40 stainless steel pipe.

Waste Type: Process Effluent

Waste Description: This tank collected overflow radioactive process waste from 241-T-252, 241-T-151, 241-T-152 and 241-T-153 Diversion Boxes.

Code: 241-TR-152 **Classification:** Accepted

Names: 241-TR-152; 241-TR-152 Diversion Box; Line 6053 **Reclassification:** None

Type: Diversion Box **Start Date:** 1/1/1944

Status: Inactive **End Date:** 1/1/1980

Description: This unit is constructed of reinforced concrete and is rectangular in shape.

Location: This unit is located east of Tank 241-T-104 within the 241-T Tank Farm.

Related Sites/Structures: The 241-TR-152 Diversion Box is associated with the 241-TR-153 and 241-TXR-151 Diversion Boxes, and the 241-T Tank Farm. The drain line is line 6053.

Process Description: This unit was used for the transfer of waste solutions from processing and decontamination operations.

Waste Type: Equipment

Waste Description: It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Waste Type: Equipment

Waste Description: Equipment associated with the diversion box includes transfer piping and nozzles.

Waste Type: Process Effluent

Waste Description: This unit was used for transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operations.

Code: 241-TR-153 **Classification:** Accepted

Names: 241-TR-153; 241-TR-153 Booster Pump Pit; 241-TR-153 Diversion Box; Line 6172 **Reclassification:** None

Type: Diversion Box **Start Date:** 1/1/1944

Status: Inactive **End Date:** 1/1/1983

Description: This unit is constructed of reinforced concrete and is rectangular in shape.

Location: The 241-TR-153 Diversion Box is located east of Tank 241-T-107 within the 241-T Tank Farm.

Related Sites/Structures: The 241-TR-153 Diversion Box is associated with the 241-TR-152 and 241-TXR-151 Diversion Boxes, 241-T Tank Farm, and the 241-T-301B Catch Tank. The drain line to 241-T-102 is number 6172.

Process Description: This unit was used for the transfer of waste solutions from processing and decontamination operations.

Waste Type: Equipment

Waste Description: Waste lead is stored in the diversion box.

Waste Type: Equipment

Waste Description: Equipment associated with the diversion box includes transfer piping and nozzles.

Waste Type: Chemicals

Waste Description: This unit was used for transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operation.

Code: 200-W-52

Classification: Accepted

Names: 200-W-52; 216-T-7 Crib; 241-T-3 Crib

Reclassification: None

Type: Crib

Start Date: 1/1/1948

Status: Inactive

End Date: 1/1/1955

Description: The crib is located inside the 241-T Tank Farm fence. The fence is posted with Radiological Buffer Area/Underground Radioactive Material signs. The tank farm has a gravel surface. The crib is not separately identified.

Location: The crib is located inside the 241-T Tank Farm fence, east of the 216-T-7 Tile Field.

Related Sites/ Structures: The crib is associated with the 216-T-7 Tile Field, the 241-T Tank Farm, 221-T and 224-T.

Process Description: The site consists of one wooden crib box with inlet and outlet piping and a riser pipe. The box is set into a gravel layer in the bottom of a pit with sloping sides. It is connected to a tile field that is located west of the crib. The 216-T-7 crib received second cycle supernate from 221-T, 224-T waste and tank 5-6 waste after it cascaded through the 241-T-110, 241-T-111 and 241-T-112 tanks. The 216-T-7 Tile Field received overflow from the crib.

Waste Type: Process Effluent

Waste Description:

Code: 200-W-93

Classification: Accepted

Names: 200-W-93; Contaminated Soil at 241-T Tank Farm

Reclassification: None

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The site is the soil inside and adjacent to the chain link fence that surrounds the 241-T Tank Farm. Various radiological postings and warning signs are attached to the chain link fence. The interior of the tank farm complex is covered with gravel. Many risers and monitoring devices for the underground structures are visible on the surface. The 216-T-7 and 216-T-32 Crib are located inside the tank farm fence and are marked with "Crib" signs. The 216-T-7 Tile Field is partially inside the tank farm, but most of it extends westward, beyond the fence line. The individual unplanned releases associated with the 241-T Tank Farm are not separately marked or posted. Occasionally, radioactive contamination is found adjacent to the outside of the tank farm fence, resulting in a contamination zone extension around the tank farm perimeter. These areas will also be considered tank farm soil. A posted Underground Radioactive Material area currently extends outside the 241-T Tank Farm fence on the west side.

Location: The site is located west of 221-T, at the intersection of 23rd Street and Camden Ave., in 200 West Area.

Release Description: The exact extent (horizontal and vertical) of the soil contaminated by unplanned releases that occurred within this farm over the years are not known. Some of the single shell tanks have leaked to the soil below the tank farm. Other releases spread contamination to the surface soil surrounding the tanks.

Related Sites/ Structures: Unplanned Releases UPR-200-W-7, UPR-200-W-147 and UPR-200-W-148 are associated with the 241-T Tank Farm. The 216-T-7 and 216-T-32 Cribs are located inside the tank farm fence.

Waste Type: Process Effluent

Waste Description: Liquid releases occurred from underground leaks in tanks and transfer lines. Airborne contamination spreads occurred from activities conducted in valve pits and diversion boxes. Both types of releases contributed to the contamination in the soil.

WMA TX/TY

Code: 242-T	Classification: Accepted
Names: 242-T; 242-T Evaporator Facility; 241-T Evaporator	Reclassification: None
Type: Evaporator	Start Date: 1/1/1950
Status: Inactive	End Date: 1/1/1986

Description: The 242-T is a reinforced concrete and structural steel building. The facility consists of the 242-T building with the control room in the southeast portion, 242-TB and the 242-TA vault. The evaporator portion of 242-T contains a feed cell, an evaporator vessel, a cyclone separator, a catch tank and two preheater tanks. The condensate portion contains the off-gas vessels, two condensate catch tanks and a sample gallery. The 242-TA Vault is a concrete lined pit with a ground level steel cover. A 15,120 liter (4000 gallon) receiver tank is inside the vault. This tank received Z Plant waste.

Location: The building is adjacent to the east side of the 241-TX/TY Tank Farm fence.

Related Sites/Structures: The 242-T is associated with the 241-TX/TY tanks and the 200-W-166-PL and 200-W-167-PL pipelines.

Process Description: The 242-T Evaporator Facility was originally constructed to increase storage capacity in the existing underground tank farm tanks through a batch evaporation, waste concentration process. From 1950 to 1955 and 1965 through 1976, 242-T operated as a tank waste evaporator. The evaporation operation of non-boiling tank farm waste was discontinued in 1976. From 1976 to 1980, the 242-T Evaporator was used to neutralize Z Plant salt acid waste. This process ended in 1980, with the completion of the 244-TX Double-Shell Receiver Tank. From 1980 to 1985 the control area of the facility was utilized to support the saltwell pumping program.

Waste Type: Process Effluent

Waste Description: During the 1950's, the facility concentrated separation process, first cycle decontamination waste from the tank farms. First cycle waste typically contained 10% of the original fission products and 1% plutonium in solution with nitrates, phosphates and sulfates. From the 1960's to the late 1970's, it received single-shell supernatant waste, complexed radioactive waste, and dilute miscellaneous radioactive waste. From 1976 to 1980, the evaporator was used to neutralize Z Plant waste. During its active life, the facility received and processed 127,204,560 liters (33,652,000 gallons) of waste.

Code: 242-T-135	Classification: Accepted
Names: 242-T-135	Reclassification: None
Type: Storage Tank	Start Date:
Status: Inactive	End Date:

Description: The unit is a tank partially below grade, constructed of stainless steel. An agitator and a hopper are installed on top of the tank. The tank is surrounded with steel posts and chain, located behind a steel radiation shield wall. The area surrounding the tank is posted with Contamination Area and IMUST signs.

Location: The tank is located adjacent to the east wall of the 242-T Catch Tank Room and north of the 242-T Control Room. The 242-T buildings are located adjacent to the 241-TX Tank Farm, outside the fence.

Related Sites/ Structures: The unit is associated with the operation of the 242-T evaporator.

Process Description: The tank was installed to hold decontamination solutions from the 242-T Evaporator. The solutions were charged through a hopper on the top of the tank and removed through the top using a jet.

Waste Type: Process Effluent

Waste Description: The contents of the tank are not known. The tank mission was storage of 242-T decontamination solutions. The content of the tank would include 242-T decontamination solutions.

Code: 242-T-151 **Classification:** Accepted

Names: 242-T-151; 242-T-151 Diversion Box. Drain Line V830 **Reclassification:** None

Type: Diversion Box **Start Date:**

Status: Inactive **End Date:**

Description: This unit is constructed of reinforced concrete and is rectangular in shape. Weather covering has been applied. The drain line for this diversion box is V830.

Location: This unit is located southeast of the 241-TX-116 Tank, inside the 241-TX Tank Farm.

Related Sites/ Structures: The 242-T-151 Diversion Box is associated with the 241-TX Tank Farm, 241-T-153 Diversion Box, and 242-T Evaporator.

Process Description: This unit was used for the transfer of waste solutions from processing and decontamination operations.

Waste Type: Equipment

Waste Description: It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Waste Type: Process Effluent

Waste Description: This unit was used for the transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operations.

Waste Type: Equipment

Waste Description: Equipment associated with the diversion box includes transfer piping and nozzles.

Code: 242-TA-R1 **Classification:** Accepted

Names: 242-TA-R1; Receiver Tank TK-R1; Receiver TK-Vault; Z Waste; 242-TA; 242-TA Receiver Tank Vault **Reclassification:** None

Type: Receiving Vault **Start Date:**

Status: Inactive **End Date:**

Description: The unit is a below-grade 16 foot diameter (at bottom) by 20 foot high cylindrical structure, with a 16 foot octagon-shaped top at grade level. The vault is constructed of concrete and

contains a 4200 gallon tank. The surface is surrounded with a metal rail fence and labeled with IMUST signs.

Location: The unit is located inside the 241-TX Tank Farm, adjacent to the southwest corner of the 242-T Building.

Related Sites/ Structures: The tank is associated with the 241-Z facility.

Process Description: The Z Waste Receiver Tank received high salt waste from tank D-5 in the 241-Z building. The Z Waste Receiver Tank waste was sent to the Blend Tank TK-B1 inside the 242-T building. Off-gasses from the tank are sent to the vessel vent system in the 242-TB building.

Waste Type: Process Effluent

Waste Description: The waste reportedly contains 0.007 grams per gallon of Plutonium; 4.756 molar concentration of nitrate ion; 0.15 molar concentration of Sodium ion; 0.842 molar concentration of trivalent Aluminum; 0.648 molar concentration of free Hydrogen atoms; 0.454 molar concentration of divalent Aluminum Fluoride; 0.180 molar concentration of bivalent Magnesium; 0.087 molar concentration of trivalent Iron; 0.059 molar concentration of Potassium ion; 0.013 molar concentration of Sulphate ion; and 0.0005 molar concentration of divalent Uranium Oxide.

Code: 241-TX-101	Classification: Accepted
Names: 241-TX-101; 241-TX-TK-101	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1949
Status: Inactive	End Date: 1/1/1980

Description: This unit is a second-generation underground single-shell storage tank. Tank 241-TX-101 is the first tank of a four-tank cascade series. This cylindrical tank is concrete-reinforced with a single steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-TX-101 is located in the southeastern portion of the 241-TX Tank Farm.

Related Sites/ Structures: Structures associated with Tank 241-TX-101 include passive ventilation, drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-TX-101 included the REDOX Facility, PUREX, and B-Plant.

Waste Type: Storage Tank

Waste Description: Waste transferred to this unit includes bismuth phosphate metal waste, REDOX waste, coating waste, tributyl phosphate, and waste fractionation ion exchange waste. Other waste includes high level and low level waste from B-Plant, non-complexed waste, PUREX low-level waste, organic wash waste, partial neutralization feed waste, and evaporator bottoms. The unit also received decontamination waste from 241-C, -BX, -SX, -TX Tank Farms.

Code: 241-TX-102	Classification: Accepted
Names: 241-TX-102; 241-TX-TK-102	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1950
Status: Inactive	End Date: 1/1/1975

Description: This unit is a second-generation, underground single-shell storage tank. Tank 241-TX-102 is

the second tank of a four-tank cascade series. This cylindrical tank is concrete-reinforced with a single steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-TX-102 is located in the southern portion of the 241-TX Tank Farm.

Related Sites/ Structures: Structures associated with Tank 241-TX-102 include passive ventilation, drywells, and a surface level measurement instrument.

Process Description: Waste sources for Tank 241-TX-102 included the REDOX Facility, 242-T, and 241-TX Tanks.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-TX-102 included bismuth phosphate metal waste, 242-T Evaporator waste, and supernatant containing REDOX high-level waste, and evaporator bottoms from 241-TX Tanks.

Code: 241-TX-103 **Classification:** Accepted

Names: 241-TX-103; 241-TX-TK-103 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1950

Status: Inactive **End Date:** 1/1/1980

Description: This unit is a second-generation, underground single-shell storage tank. Tank 241-TX-103 is the third tank of a four-tank cascade series. This cylindrical tank is concrete-reinforced with a single steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-TX-103 is located in the southern portion of the 241-TX Tank Farm.

Related Sites/ Structures: Structures associated with Tank 241-TX-103 include passive ventilation, drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-TX-103 included the 242-A Evaporator, and the 241-TX Tanks.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-TX-103 included bismuth phosphate metal waste, 242-T Evaporator waste, noncomplexed waste, tributyl phosphate waste, and partial neutralization feed from 241-TX Tanks.

Code: 241-TX-104 **Classification:** Accepted

Names: 241-TX-104; 241-TX-TK-104 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1950

Status: Inactive **End Date:** 1/1/1977

Description: This unit is a second-generation, underground single-shell storage tank. Tank 241-TX-104 is the fourth tank of a four-tank cascade series. This cylindrical tank is concrete-reinforced with a single steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-TX-104 is located in the southwestern portion of the 241-TX Tank Farm.

Related Sites/ Structures: Structures associated with Tank 241-TX-104 include passive ventilation, drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-TX-104 included the REDOX Facility, PUREX, and B-Plant, 242-T Evaporator, and Tank Farms 241-TY and 241-TX.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-TX-104 included bismuth phosphate metal waste, 242-T Evaporator waste, and supernatant containing REDOX ion exchange and high-level waste, PUREX organic wash waste, B Plant low-level waste, and tributyl phosphate from 241-TY and 241-TX Tanks.

Code: 241-TX-105 **Classification:** Accepted

Names: 241-TX-105; 241-TX-TK-105 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1952

Status: Inactive **End Date:** 1/1/1976

Description: This unit is a second-generation, underground single-shell storage tank. Tank 241-TX-105 is the first tank of a four-tank cascade series. This cylindrical tank is concrete-reinforced with a single steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-TX-105 is located in the southeastern portion of the 241-TX Tank Farm.

Related Sites/ Structures: Structures associated with Tank 241-TX-105 include passive ventilation, drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-TX-105 included the REDOX Facility, PUREX, and the 241-BX and 241-SX Tank Farms.

Waste Type: Storage Tank

Waste Description: Waste transferred to tank 241-TX-105 included bismuth phosphate metal waste, 242-T Evaporator waste, and supernatant containing REDOX ion exchange and high-level waste, and PUREX organic wash waste from 241-BX and 241-SX Tank Farms.

Code: 241-TX-106 **Classification:** Accepted

Names: 241-TX-106; 241-TX-TK-106 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1952

Status: Inactive **End Date:** 1/1/1977

Description: This unit is a second-generation, underground single-shell storage tank. Tank 241-TX-106 is the second tank of a four-tank cascade series. This cylindrical tank is concrete-reinforced with a single steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-TX-106 is located in the southeastern portion of the 241-TX Tank Farm.

Related Sites/ Structures: Structures associated with Tank 241-TX-106 include passive ventilation, drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-TX-106 included the REDOX Facility, PUREX, 242-T Evaporator, and the 241-TX Tank Farm.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-TX-106 included bismuth phosphate metal waste, tributyl phosphate waste, 242-T Evaporator waste, and supernatant containing REDOX ion exchange and high-level waste, PUREX organic wash waste, evaporator bottoms, and coating waste from 241-TX Tanks.

Code: 241-TX-107 **Classification:** Accepted

Names: 241-TX-107; 241-TX-TK-107 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1952

Status: Inactive **End Date:** 1/1/1977

Description: This unit is a second-generation, underground single-shell storage tank. Tank 241-TX-107 is the third tank of a four-tank cascade series. This cylindrical tank is concrete-reinforced with a single steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-TX-107 is located in the southwestern portion of the 241-TX Tank Farm.

Related Sites/Structures: Structures associated with Tank 241-TX-107 include passive ventilation, drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-TX-107 included the REDOX Facility, and the 242-T Evaporator.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-TX-107 included bismuth phosphate metal waste, 242-T Evaporator waste, and REDOX high-level waste from the 241-TX Tanks.

Code: 241-TX-108 **Classification:** Accepted

Names: 241-TX-108; 241-TX-TK-108 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1952

Status: Inactive **End Date:** 1/1/1977

Description: This unit is a second-generation, underground single-shell storage tank. Tank 241-TX-108 is the fourth tank of a four-tank cascade series. This cylindrical tank is concrete-reinforced with a single steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-TX-108 is located in the southwestern portion of the 241-TX Tank Farm.

Related Sites/Structures: Structures associated with Tank 241-TX-108 include passive ventilation, drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-TX-108 included the REDOX Facility, the 242-T Evaporator, and the 241-TX and 241-TY Tank Farms.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-TX-108 included bismuth phosphate metal waste, REDOX high-level waste, 242-T Evaporator waste, supernatant containing decontamination waste, tributyl phosphate waste, and evaporator bottoms from 241-TX and -TY Tanks.

Code: 241-TX-109	Classification: Accepted
Names: 241-TX-109; 241-TX-TK-109	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1949
Status: Inactive	End Date: 1/1/1977

Description: This unit is a second-generation, underground single-shell storage tank. Tank 241-TX-109 is the first tank of a four-tank cascade series. This cylindrical tank is concrete-reinforced with a single steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-TX-109 is located in the eastern portion of the 241-TX Tank Farm.

Related Sites/ Structures: Structures associated with Tank 241-TX-109 include passive ventilation, a liquid observation well, drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-TX-109 included the 242-T Evaporator and the 241-T, 241-TX, and 241-TY Tank Farms.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-TX-109 included: bismuth phosphate first-cycle waste, 242-T Evaporator waste, and evaporator bottoms from the 241-T, 241-TX, and 241-TY Tanks.

Code: 241-TX-110	Classification: Accepted
Names: 241-TX-110; 241-TX-TK-110	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1949
Status: Inactive	End Date: 1/1/1977

Description: This unit is a second-generation, underground single-shell storage tank. Tank 241-TX-110 is the second tank of a four-tank cascade series. This cylindrical tank is concrete-reinforced with a single steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-TX-110 is located in the central portion of the 241-TX Tank Farm.

Related Sites/ Structures: Structures associated with Tank 241-TX-110 include passive ventilation, a liquid observation well, drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-TX-110 included the 242-T Evaporator and T Plant.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-TX-110 included bismuth phosphate first-cycle waste and 242-T Evaporator waste.

Code: 241-TX-111	Classification: Accepted
Names: 241-TX-111; 241-TX-TK-111	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1950
Status: Inactive	End Date: 1/1/1977

Description: This unit is a second-generation, underground single-shell storage tank. Tank 241-TX-111 is the third tank of a four-tank cascade series. This cylindrical tank is concrete-reinforced with a single steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-TX-111 is located in the central portion of the 241-TX Tank Farm.

Related Sites/ Structures: Structures associated with Tank 241-TX-111 include passive ventilation, a liquid observation well, drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-TX-111 included the 242-T Evaporator, T Plant, and the 241-TY Tanks.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-TX-111 included bismuth phosphate first-cycle waste, 242-T Evaporator waste, and supernatant containing tributyl phosphate waste from 241-TX Tanks.

Code: 241-TX-112 **Classification:** Accepted

Names: 241-TX-112; 241-TX-TK-112 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1950

Status: Inactive **End Date:** 1/1/1976

Description: This unit is a second-generation, underground single-shell storage tank. Tank 241-TX-112 is the fourth tank of a four-tank cascade series. This cylindrical tank is concrete-reinforced with a single steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-TX-112 is located in the western portion of the 241-TX Tank Farm.

Related Sites/ Structures: Structures associated with Tank 241-TX-112 include passive ventilation, a liquid observation well, drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-TX-112 included the 242-T Evaporator, T Plant, and the 241-TY Tanks.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-TX-112 included 242-T Evaporator waste, bismuth phosphate first-cycle waste, and supernatant containing evaporator bottoms from the 241-TX Tanks.

Code: 241-TX-113 **Classification:** Accepted

Names: 241-TX-113; 241-TX-TK-113 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1952

Status: Inactive **End Date:** 1/1/1976

Description: This unit is a second-generation, underground single-shell storage tank. Tank 241-TX-113 is the first tank of a three-tank cascade series. This cylindrical tank is concrete-reinforced with a single steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-TX-113 is located in eastern portion of the 241-TX Tank Farm.

Related Sites/ Structures: Structures associated with Tank 241-TX-113 include passive ventilation, a liquid observation well, drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-TX-113 included the 242-T Evaporator and the 241-TX Tanks.

Waste Type: Storage Tank

Waste Description: Waste Transferred to Tank 241-TX-113 included 242-T Evaporator waste and supernatant containing evaporator bottoms from 241-TX Tanks.

Code: 241-TX-114 **Classification:** Accepted

Names: 241-TX-114; 241-TX-TK-114 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1952

Status: Inactive **End Date:** 1/1/1975

Description: This unit is a second-generation, underground single-shell storage tank. Tank 241-TX-114 is the second tank of a three-tank cascade series. This cylindrical tank is concrete-reinforced with a single steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-TX-114 is located in the central portion of the 241-TX Tank Farm.

Related Sites/ Structures: Structures associated with Tank 241-TX-114 include passive ventilation, a liquid observation well, drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-TX-114 included the 242-T Evaporator, T Plant, and the 241-TX Tanks.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-TX-114 included 242-T Evaporator waste, supernatant containing bismuth phosphate first-cycle waste, and evaporator bottoms from the 241-TX Tanks.

Code: 241-TX-115 **Classification:** Accepted

Names: 241-TX-115; 241-TX-TK-115 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1952

Status: Inactive **End Date:** 1/1/1977

Description: This unit is a second-generation, underground single-shell storage tank. Tank 241-TX-115 is the third tank of a three-tank cascade series. This cylindrical tank is concrete-reinforced with a single steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-TX-115 is located in the western portion of the 241-TX Tank Farm.

Related Sites/ Structures: Structures associated with Tank 241-TX-115 include passive ventilation, a liquid observation well, drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-TX-115 included the 242-T Evaporator, T Plant, and Tank Farms 241-U, 241-T, and 241-TX.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-TX-115 included 242-T Evaporator waste, tributyl phosphate waste, coating waste, decontamination waste, and evaporator bottoms from 241-U, 241-S, 241-T, and 241-TX Tanks.

Code: 241-TX-116 **Classification:** Accepted
Names: 241-TX-116; 241-TX-TK-116 **Reclassification:** None
Type: Single-Shell Tank **Start Date:** 1/1/1952
Status: Inactive **End Date:** 1/1/1976

Description: This unit is a second-generation, underground single-shell storage tank. Tank 241-TX-116 is the first tank of a three-tank cascade series. This cylindrical tank is concrete-reinforced with a single steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-TX-116 is located in the northeastern portion of the 241-TX Tank Farm.

Related Sites/Structures: Structures associated with Tank 241-TX-116 include passive ventilation, drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-TX-116 included the 241-TX Tanks.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-TX-116 included supernatant containing evaporator bottoms from 241-TX Tanks. Diatomaceous earth was added in 1969.

Code: 241-TX-117 **Classification:** Accepted
Names: 241-TX-117; 241-TX-TK-117 **Reclassification:** None
Type: Single-Shell Tank **Start Date:** 1/1/1952
Status: Inactive **End Date:** 1/1/1976

Description: This unit is a second-generation, underground single-shell storage tank. Tank 241-TX-117 is the second tank of a three-tank cascade series. This cylindrical tank is concrete-reinforced with a single steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-TX-117 is located in the northern portion of the 241-TX Tank Farm.

Related Sites/Structures: Structures associated with Tank 241-TX-117 include passive ventilation, a liquid observation well, drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-TX-117 included the 242-T Evaporator and 241-TX Tanks.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-TX-117 included supernatant containing first-cycle waste and evaporator bottoms from 241-TX Tanks. Diatomaceous earth was also added in 1969.

Code: 241-TX-118 **Classification:** Accepted

Names: 241-TX-118; 241-TX-TK-118**Reclassification** None**Type:** Single-Shell Tank**Start Date:** 1/1/1952**Status:** Inactive**End Date:** 1/1/1980**Description:** This unit is a second-generation, underground single-shell storage tank. Tank 241-TX-118 is the third tank of a three-tank cascade series. This cylindrical tank is concrete-reinforced with a single steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.**Location:** Tank 241-TX-118 is located northwestern portion of the 241-TX Tank Farm.**Related Sites/Structures:** Structures associated with Tank 241-TX-118 include passive ventilation, a liquid observation well, drywells, temperature and surface level measurement instruments.**Process Description:** Waste sources for Tank 241-TX-118 included 242-T Evaporator, 234-Z and 235-Z Buildings, and the 241-T, 241-TX, 241-TY, 241-U Tank Farms.**Waste Type:** Storage Tank**Waste Description:** Waste transferred to tank 241-TX-118 included 242-T Evaporator feed tank waste, 234-Z and 235-Z Buildings waste, caustic solution, tributyl phosphate waste, decontamination waste, bismuth phosphate first-cycle waste, evaporator bottoms, partial neutralization feed, and coating waste from the 241-T, 241-TX, 241-TY, and 241-U Tank Farms.

Code: 241-TX-153**Classification:** Accepted**Names:** 241-TX-153; 241-TX-153 Diversion Box**Reclassification** None**Type:** Diversion Box**Start Date:** 1/1/1949**Status:** Inactive**End Date:** 1/1/1980**Description:** The diversion box is a rectangular reinforced concrete structure. Most of the structure is below ground. A few inches of the structure that extends above ground is covered with a gray weather coating. The tank farm fence is posted with various radiological postings.**Location:** This unit is located inside the 241-TX Tank Farm, southeast of the 241-TX-101 Tank.**Related Sites/Structures:** The 241-TX-153 Diversion Box is associated with the 241-TX-155 Diversion Box and the 241-TX Tank Farm, the 241-TX-302A and 241-TX-302B Catch Tanks and UPR-200-W-126. The pipeline from the diversion box to the 216-T-19 crib is sitecode 200-W-213-PL.**Process Description:** This unit is used to transfer of solutions from processing and decontamination operations to various tank farm facilities via underground transfer lines.**Waste Type:** Process Effluent**Waste Description:** This unit was used for transfer of waste solution from processing and decontamination operations. Volumes were variable according to specific plant operations. Lead shielding may also be contained inside the diversion box.**Waste Type:** Equipment**Waste Description:** Equipment associated with the diversion box includes transfer piping and nozzles. Waste lead is also stored in the diversion box.

Code: 241-TX-302A**Classification:** Accepted

Names: 241-TX-302A; 241-TX-302-A Catch Tank; Lines V627 and V628 **Reclassification** None

Type: Catch Tank **Start Date:** 1/1/1949

Status: Inactive **End Date:** 1/1/1982

Description: This unit is an underground, horizontal cylindrical tank made of steel. The tank farm surface has been covered with gravel. The tank is surrounded with posts and chain and labeled with IMUST signs.

Location: This tank is located southwest of the 241-TX-153 Diversion Box, inside the 241-TX Tank Farm.

Related Sites/Structures: This unit is associated with the 241-TX-153 Diversion Box and the 241-TX-302X Catch Tank. Lines V627 and V628 are the drain lines from the 241-TX-153 diversion Box.

Process Description: The 241-TX-302A Catch Tank received drainage from Diversion Box 241-TX-153 and associated encasements.

Waste Type: Process Effluent

Waste Description: This tank collected waste solution spills that occurred during transfers from processing and decontamination operations via the 241-TX-153 Diversion Box. Volumes collected were variable according to specific plant operations. In 1994, it was estimated the tank contained approximately 113 liters (30 gallons) of supernate liquid and 9261 liters (2450 gallons) of sludge.

Code: 241-TX-302XB **Classification:** Accepted

Names: 241-TX-302XB; 241-TX-302B Catch Tank; 241-TX-302-X; 241-TX-302-X (B) **Reclassification** None

Type: Catch Tank **Start Date:** 1/1/1948

Status: Inactive **End Date:** 1/1/1985

Description: This unit is a horizontal, cylindrical tank made of carbon steel. The tank is surrounded with posts and chain and labeled with IMUST signs. The tank is buried underground to provide radiation shielding.

Location: This catch tank is located east of Tank 241-TX-101, inside the 241-TX Tank Farm.

Related Sites/Structures: The 241-TX-302-X Catch Tank is associated with Diversion Box 241-TX-153.

Process Description: This tank received drainage from a concrete encasement originating at the 241-TX-153 Diversion Box.

Waste Type: Storage Tank

Waste Description: This unit was used for containment of waste solution spills that occurred during transfers from processing and decontamination operations. The contents include metal waste and radiological mixed waste. As of May 1994, 1341 liters (353 gallons) remained in the tank. Per WRPS-0901391, the liquid waste level at that time was 6.5 inches and the solid waste level was 3 inches. The solids volume is 103 gallons. The amount of liquid waste in the tank was estimated to be 237 gallons. The total volume is 340 gallons.

Code: 244-TX DCRT **Classification:** Accepted

Names:	244-TX DCRT; 244-TX Double-Contained Receiver Tank; 244-TX Receiver Tank; 244-TX Receiver Vessel; 244-TX RT; 244-TX-TK/SMP	Reclassification	None
Type:	Receiver Tank	Start Date:	1/1/1981
Status:	Inactive	End Date:	1/1/2005
Description:	This unit is an underground, horizontal cylindrical vessel that sets in a reinforced concrete, steel-lined vault.		
Location:	The unit is located north of the 241-TX Tank Farm, within the 241-TY Tank Farm fence.		
Related Sites/ Structures:	The 244-TX Receiver Tank is associated with the Plutonium Finishing Plant, T-Plant, 241-T Tank Farm, and 241-TX-152 Diversion Box.		
Process Description:	Waste sources for the 244-TX Receiver Tank included the Plutonium Finishing Plant, T Plant, and the 241-T Tank Farm.		
Waste Type:	Process Effluent		
Waste Description:	Waste transferred to this unit include T Plant decontamination waste, Plutonium Finishing Plant waste, and waste solution stored in the 241-T Tank Farms.		

Code:	241-TXR-151	Classification:	Accepted
Names:	241-TXR-151; 241-TXR-151 Diversion Box; Line 7765	Reclassification	None
Type:	Diversion Box	Start Date:	1/1/1949
Status:	Inactive	End Date:	1/1/1980
Description:	The diversion box is a rectangular reinforced concrete structure. Most of the structure is below ground. A few inches of the structure that extends above ground is covered with a gray weather coating. The tank farm fence is posted with various radiological postings.		
Location:	This unit is located east of the 244-TXR Vault, inside the 241-TX Tank Farm fence.		
Related Sites/ Structures:	Structures associated with the 241-TXR-151 Diversion Box include the 241-TR-152 and 241-TR-153 Diversion Boxes and the 244-TXR Vault. The drain line to the 244-TXR sump is line 7765.		
Process Description:	This unit is used to transfer waste solutions from processing and decontamination operations to various tank farm facilities.		
Waste Type:	Process Effluent		
Waste Description:	This unit was used for transfer of radioactive waste solutions from processing and decontamination operations. Contamination in the diversion box is estimated to be high in alpha, beta and gamma radiation. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.		
Waste Type:	Equipment		
Waste Description:	Equipment associated with the diversion box includes transfer piping and nozzles. Waste lead is also stored in the diversion box.		

Code:	241-TXR-152	Classification:	Accepted
--------------	-------------	------------------------	----------

Names: 241-TXR-152; 241-TXR-152 Diversion Box;
Line 7053 **Reclassification** None

Type: Diversion Box **Start Date:** 1/1/1949

Status: Inactive **End Date:** 1/1/1980

Description: This unit is constructed of reinforced concrete and is rectangular in shape. The 241-TXR-152 has been weather covered.

Location: This unit is located east of Tank 241-TX-105, inside the 241-TX Tank Farm.

Related Sites/ Structures: The 241-TXR-152 Diversion Box is associated with the 241-TXR-151 Diversion Box and the 241-TX Tank Farm and drains to the 241-TX-101 Tank through line 7053.

Process Description: This unit was used for the transfer of waste solutions from processing and decontamination operations.

Waste Type: Equipment

Waste Description: Equipment associated with the diversion box includes transfer piping and nozzles. Waste lead is also stored in the diversion box.

Waste Type: Process Effluent

Waste Description: This unit was used for transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operations. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Code: 241-TXR-153 **Classification:** Accepted

Names: 241-TXR-153; 241-TXR-153 Diversion Box;
Line 7253 **Reclassification** None

Type: Diversion Box **Start Date:** 1/1/1949

Status: Inactive **End Date:** 1/1/1980

Description: This unit is constructed of reinforced concrete and is rectangular in shape. The 241-TXR-153 has been weather covered.

Location: This unit is located east of Tank 241-TX-105, inside the 241-TX Tank Farm.

Related Sites/ Structures: The 241-TXR-153 Diversion Box is associated with the 241-TXR-151 Diversion Box and the 241-TX Tank Farm and drains to the 241-TX-105 Tank through line 7253.

Process Description: This unit was used for the transfer of waste solutions from processing and decontamination operations.

Waste Type: Process Effluent

Waste Description: This unit was used for transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operations. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Waste Type: Equipment

Waste Description: Equipment associated with the diversion box includes transfer piping and nozzles. Waste lead is also stored in the diversion box.

Code: 244-TXR VAULT **Classification:** Accepted

Names: 244-TXR VAULT; 244-TXR Vault (Tanks TXR-001, -002, -003); 241-TXR-244; 244-TXR **Reclassification** None

Type: Receiving Vault **Start Date:** 1/1/1950

Status: Inactive **End Date:** 1/1/1957

Description: The 244-TXR Vault is a rectangular, reinforced concrete pit. The vault is surrounded with post and chain and marked with IMUST signs. The vault houses three steel storage tanks (244-TK-TXR-1, -TXR-2, and TXR-3; see "Subsite" sections). The 244-TK-TXR-1 Tank has a 50,000 gallon (189,000 liter) capacity and the 244-TK-TXR-2 and TXR-3 each have a 15,000 gallon (56,800 liters) capacity. The vault is buried to a depth that places the upper surface of its lid about 12 inches (30.5 centimeters) above grade.

Location: The vault is located within the tank farm fence, south of the 241-TX Tank Farm and west of Camden Avenue.

Related Sites/Structures: The 244-TK-TXR-1, TXR-2, and TXR-3 Tanks are housed in the 244-TXR Vault. The vault is connected to the 241-TXR-151, 241-TR-152, and 241-TR-153 Diversion Boxes.

Process Description: The vault and associated tanks were used for processing was from 241-T and 241-TX tank farms and to transfer the processed waste to U Plant for uranium recovery.

Waste Type: Equipment

Waste Description: Equipment associated with the 244-TXR Vault includes the steel tanks, piping, nozzles, and other miscellaneous equipment.

Waste Type: Chemicals

Waste Description: The vault received uranium waste, generated at T-Plant, that was transferred to the 241-T and 241-TX Tank Farms. The vault product consisted of processed slurry that was transferred to U Plant for uranium recovery.

This Site has the Following SubSites:

Code: 244-TXR VAULT:1

Names: 244-TXR VAULT:1; 244-TXR-001

Code: 244-TXR VAULT:2

Names: 244-TXR VAULT:2; 244-TXR-002

Code: 244-TXR VAULT:3

Names: 244-TXR VAULT:3; 244-TXR-003

Code: 244-TXR VAULT:1 **Classification:** Accepted

Names: 244-TXR VAULT:1; 244-TXR-001 **Reclassification** None

Type: Receiving Vault **Start Date:**

Status: Inactive **End Date:**

Description: Tank 244-TXR-0001 is located in a concrete cell, inside the 244-TXR Vault. The cell is 6.7 meters (22 feet) by 7.9 meters (26 feet) by 8.8 meters (28.8 feet). The tank is 6.1 meters (20 feet) tall and 6.1 meters (20 feet) in diameter. The tank has a 189,000 liter (50,000 gallon) capacity. The tank was used as a slurry accumulator for bismuth phosphate waste from tanks in T and TX farms. The tank is isolated and stabilized. Samples were collected and analyzed in 1984 from both the tank and the sump. Results included 1.05 micro curies/liter Total Alpha, 4,510 micro curies/liter Total Beta, and 4,490 micro curies/liter cesium-137 GEA. 0.108 N02

and 0.442 N03 were noted without units. Hanford Occurrence Report 79-68 indicates this tank is of questionable integrity.

The SubSite is Part Of:

Code: 244-TXR VAULT

Names: 244-TXR VAULT; 244-TXR Vault (Tanks TXR-001, -002, -003); 241-TXR-244; 244-TXR

Code: 244-TXR VAULT:2

Classification: Accepted

Names: 244-TXR VAULT:2; 244-TXR-002

Reclassification: None

Type: Receiving Vault

Start Date:

Status: Inactive

End Date:

Description: Tank 244-TXR-002 is located in a concrete cell, inside the 244-TXR Vault. The cell is 4.9 meters (16 feet) by 6.1 meters (20 feet) by 5.8 meters (19 feet). The tank is 3.7 meters (12 feet) tall and 4.3 meters (14 feet) in diameter. It has a 56,775 liter (15,000 gallon) capacity. The tank was used to acidify material for the uranium recovery process. Slurry was transferred from tank 001 and nitric acid was added prior to being pumped to U-Plant. The tank is isolated and stabilized. The tank contains 11,147 liters (2945 gallons) of sludge and no supernate. Samples were collected and analyzed in 1975 from the tank and had a dose rate of 1.5 R/hr. Results included 0.72 microcuries/liter Pu, 100 microcuries/liter Cs-134, 22,000 microcuries/liter Cs-137 and 10 microcuries/liter Sr-90. There was also 630 mg/L Al, 19,400 mg/L Na, 82,500 mg/L NO3 and 110 mg/L Cl.

The SubSite is Part Of:

Code: 244-TXR VAULT

Names: 244-TXR VAULT; 244-TXR Vault (Tanks TXR-001, -002, -003); 241-TXR-244; 244-TXR

Code: 244-TXR VAULT:3

Classification: Accepted

Names: 244-TXR VAULT:3; 244-TXR-003

Reclassification: None

Type: Receiving Vault

Start Date:

Status: Inactive

End Date:

Description: Tank 244-TXR-003 is located in a concrete cell, inside the 244-TXR Vault. The cell is 4.9 meters (16 feet) by 6.1 meters (20 feet) by 5.8 meters (19 feet). The tank is 3.7 meters (12 feet) tall and 4.3 meters (14 feet) in diameter. It has a 56,775 liter (15,000 gallon) capacity. The tank was used to acidify material for the uranium recovery process. Slurry was transferred from tank 001 and nitric acid was added prior to being pumped to U-Plant. The tank is isolated and stabilized. The tank contains 26,450 liters (6460 gallons) of sludge and no supernate. No sample information is mentioned.

The SubSite is Part Of:

Code: 244-TXR VAULT

Names: 244-TXR VAULT; 244-TXR Vault (Tanks TXR-001, -002, -003); 241-TXR-244; 244-TXR

Code: 241-TY-101

Classification: Accepted

Names: 241-TY-101; 241-TY-TK-101

Reclassification: None

Type: Single-Shell Tank

Start Date: 1/1/1953

Status: Inactive **End Date:** 1/1/1973

Description: This unit is a second-generation, underground single-shell storage tank. Tank 241-TY-101 is the first tank of a two-tank cascade series. This tank is concrete-reinforced, cylindrical, and dome-roofed with a steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-TY-101 is located in the northeastern portion of the 241-TY Tank Farm.

Related Sites/ Structures: Structures associated with Tank 241-TY-101 include passive ventilation, drywells, temperature and surface level measurement devices.

Process Description: Waste sources for Tank 241-TY-101 include the 242-T Evaporator and T-Plant.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-TY-101 included bismuth phosphate first-cycle waste, tributyl phosphate waste, and evaporator bottoms from 241-TY, -TX, and -SX Tank Farms.

Code: 241-TY-102 **Classification:** Accepted

Names: 241-TY-102; 241-TY-TK-102 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1953

Status: Inactive **End Date:** 1/1/1979

Description: This unit is a second-generation, underground single-shell storage tank. Tank 241-TY-102 is the second tank of a two-tank cascade series. This tank is concrete-reinforced, cylindrical, and dome-roofed with a steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-TY-101 is located in the northwestern portion of the 241-TY Tank Farm.

Related Sites/ Structures: Structures associated with Tank 241-TY-102 include passive ventilation, drywells, temperature and surface level measurement devices.

Process Description: Waste sources for Tank 241-TY-102 include the 242-T Evaporator and T-Plant.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-TY-102 included supernatant containing B Plant low-level waste, REDOX high-level waste, PUREX organic wash waste, REDOX ion exchange waste, and evaporator bottoms from 241-TX and -TY Tank Farms.

Code: 241-TY-103 **Classification:** Accepted

Names: 241-TY-103; 241-TY-TK-103 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1953

Status: Inactive **End Date:** 1/1/1976

Description: This unit is a second-generation single-shell storage tank. Tank 241-TY-103 is the first tank of a two-tank cascade series. This tank is concrete-reinforced, cylindrical, and dome-roofed with a steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-TY-103 is located on the east side of the 241-TY Tank Farm.

Related Sites/ Structures: Structures associated with Tank 241-TY-103 include passive ventilation, a liquid observation well, drywells, temperature and surface level measurement devices.

Process Description: Waste sources for Tank 241-TY-103 include the 242-T Evaporator and T-Plant.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-TY-103 included, bismuth phosphate first-cycle waste, tributyl phosphate waste, PUREX organic wash waste, REDOX ion exchange waste, coating waste, evaporator bottoms, and decontamination waste from 241-BX, -T, -TX, -TY, and -AX Tank Farms.

Code: 241-TY-104	Classification: Accepted
Names: 241-TY-104; 241-TY-TK-104	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1953
Status: Inactive	End Date: 1/1/1974

Description: This unit is a second-generation single-shell storage tank. Tank 241-TY-104 is the second tank of a two-tank cascade series. This tank is concrete-reinforced, cylindrical, and dome-roofed with a steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-TY-104 is located on the west side of the 241-TY Tank Farm.

Related Sites/ Structures: Structures associated with Tank 241-TY-104 include passive ventilation, drywells, temperature and surface level measurement devices.

Process Description: Waste sources for Tank 241-TY-104 include the 242-T Evaporator and T-Plant.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-TY-104 included tributyl phosphate waste, REDOX ion exchange waste, PUREX organic wash waste, bismuth phosphate first-cycle waste, and decontamination waste from 241-TX and -TY Tank Farms.

Code: 241-TY-105	Classification: Accepted
Names: 241-TY-105; 241-TY-TK-105	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1953
Status: Inactive	End Date: 1/1/1960

Description: This unit is a second-generation single-shell storage tank. Tank 241-TY-105 is the first tank of a two-tank cascade series. This tank is concrete-reinforced, cylindrical, and dome-roofed with a steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-TY-105 is located in the southeast portion of the 241-TY Tank Farm.

Related Sites/ Structures: Structures associated with Tank 241-TY-105 include passive ventilation, drywells, temperature and surface level measurement devices.

Process Description: Tank 241-TY-105 received tributyl phosphate waste.

Description:

Waste Type: Storage Tank

Waste Description: Tank 241-TY-105 received tributyl phosphate waste.

Code: 241-TY-106 **Classification:** Accepted

Names: 241-TY-106; 241-TY-TK-106 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1953

Status: Inactive **End Date:** 1/1/1959

Description: This unit is a second generation single-shell storage tank. Tank 241-TY-106 is the second tank of a two-tank cascade series. This tank is concrete-reinforced, cylindrical, and dome-roofed with a steel liner lying across the tank bottom and up the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-TY-106 is located in the southwestern portion of the 241-TY Tank Farm.

Related Sites/Structures: Structures associated with Tank 241-TY-106 include passive ventilation, drywells, temperature and surface level measurement devices.

Process Description: Tank 241-TY-106 received tributyl phosphate waste.

Waste Type: Storage Tank

Waste Description: Tank 241-TY-106 contains tributyl phosphate waste. Diatomaceous earth was added in 1969.

Code: 241-TY-153 **Classification:** Accepted

Names: 241-TY-153; 241-TY-153 Diversion Box **Reclassification:** None

Type: Diversion Box **Start Date:** 1/1/1953

Status: Inactive **End Date:** 1/1/1981

Description: This unit is constructed of reinforced concrete and is rectangular in shape.

Location: This unit is located in the southeast corner of the 241-TY Tank Farm.

Related Sites/Structures: The 241-TY-153 Diversion Box is associated with the 241-TY Tank Farm, the 241-TY-302A Catch Tank, and the 241-TX-153 and 241-TX-155 Diversion Boxes. The drain line is V651.

Process Description: This unit was used for the transfer of waste solutions from processing and decontamination operations.

Waste Type: Equipment

Waste Description: Equipment associated with the diversion box includes transfer piping and nozzles.

Waste Type: Equipment

Waste Description: Waste lead is stored in the diversion box.

Waste Type: Process Effluent

Waste Description: This unit was used for transfer of waste solution from processing and decontamination operations. Lead shielding may also be contained inside the diversion box.

Code: 241-TY-302A **Classification:** Accepted

Names: 241-TY-302A; 241-TY-302-A Catch Tank; Line V651 **Reclassification:** None

Type: Catch Tank **Start Date:** 1/1/1953

Status: Inactive **End Date:** 1/1/1981

Description: This unit is a horizontal, cylindrical tank made of steel. The tank is surrounded with post and chain and marked with IMUST signs. The tank is buried underground to provide radiation shielding.

Location: This unit is located in the southeast corner of the 241-TY Tank Farm.

Related Sites/Structures: The 241-TY-302A Catch Tank is associated with the 241-TY-153 Diversion Box and the 241-TY Tank Farm. The drain line is line V651.

Process Description: The catch tank received drainage from Diversion Box 241-TY-153.

Waste Type: Process Effluent

Waste Description: This tank collected overflow waste solutions from processing and decontamination operations that passed through the 241-TY-153 Diversion Box. Volumes were variable according to specific plant operation. The volume is unknown and not monitored.

Code: 241-TY-302B **Classification:** Accepted

Names: 241-TY-302B; 241-TY-302-B Catch Tank **Reclassification:** None

Type: Catch Tank **Start Date:** 1/1/1953

Status: Inactive **End Date:** 1/1/1981

Description: This unit is a horizontal, cylindrical tank made of steel. The tank is surrounded with post and chain and marked with IMUST signs. The tank is buried underground to provide radiation shielding.

Location: This unit is located in the northeast corner of the 241-TY Tank Farm.

Related Sites/Structures: The 241-TY-302B Catch Tank is associated with the 241-TY-153 Diversion Box.

Process Description: This catch tank received drainage from a concrete encasement originally at Diversion Box 241-TY-153.

Waste Type: Storage Tank

Waste Description: This unit accepted overflow waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operation.

Code: 200-W-94 **Classification:** Accepted

Names: 200-W-94; Contaminated Soil at 241-TX/TY Tank Farm **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The site is the soil inside and adjacent to the chain link fence that surrounds the 241-TX/TY Tank Farm complex. Various radiological postings and warning signs are attached to the chain link fence. The interior of the tank farm complex is covered with gravel. Many risers and monitoring devices for the underground structures are visible on the surface. The individual unplanned releases associated with the 241-TX/TY Tank Farms are not separately marked or posted. Occasionally, radioactive contamination is found adjacent to the outside of the tank farm fence, resulting in a contamination zone extension around the tank farm perimeter. These areas will also be considered tank farm soil. A portion of the 242-T Evaporator building is located inside the tank farm fence.

Location: The site is located south of 23rd Street and west of Camden Ave., in 200 West Area.

Release Description: The exact extent (horizontal and vertical) of the soil contaminated by unplanned releases that occurred within this farm over the years are not known. Some of the single shell tanks have leaked to the soil below the tank farm. Other releases spread contamination to the surface soil surrounding the tanks.

Related Sites/ Structures: Unplanned Release sites UPR-200-W-12, UPR-200-W-17, UPR-200-W-100, UPR-200-W-126, UPR-200-W-129, UPR-200-W-149, UPR-200-W-150, UPR-200-W-151, UPR-200-W-152 and UPR-200-W-153 are associated with the 241-TX/TY Tank Farms.

Waste Type: Process Effluent

Waste Description: Liquid releases occurred from underground leaks in tanks and transfer lines. Airborne contamination spreads occurred from activities conducted in valve pits and diversion boxes. Both types of releases contributed to the contamination in the soil.

Code: 2607-WT **Classification:** Accepted

Names: 2607-WT; 241-T-601 Control Bldg. Tile Field **Reclassification:** None

Type: Septic Tank **Start Date:** 1/1/1952

Status: Inactive **End Date:**

Description: The 2607-WT Septic Tank is surrounded by a chain link fence and is marked with Miscellaneous Inactive Storage Facility (MISF) signs and two WIDS waste site signs. This septic tank is connected to a sanitary tile field.

Location: The septic system is located west of the 242-T Evaporator inside the tank farm fence. It is between the 241-TX and the 241-TY Tank Farms.

Related Sites/ Structures: The 2607-WT Septic Tank is associated with a drain field and the 242-T Evaporator Control Building. The replacement for this abandoned system is sitecode 200-W-232.

Process Description: The 2607-WT Septic Tank and associated drain field were designed to accept sanitary sewer effluent from the connected structures.

Waste Type: Sanitary Sewage

Waste Description: The current flow rate for the 2607-WT septic system is unknown. The 2607-WT septic system received sanitary wastewater and sewage at an estimated rate of 0.71 cubic feet (0.02 cubic

meters) per day in 1987.

Code: 2607-WTX	Classification: Accepted
Names: 2607-WTX	Reclassification: None
Type: Septic Tank	Start Date: 1/1/1950
Status: Inactive	End Date:

Description: The 2607-WTX Septic Tank and associated sanitary tile field are surrounded with post and chain and a sign that reads "MISF". The acronym stands for Miscellaneous Inactive Storage Facility.

Location: The septic tank and tile field is located on the south side (outside) of the 241-TX Tank Farm.

**Related Sites/
Structures:** The 2607-WTX Septic Tank is associated with the 241-TX Tank Farm and the former 241-TXR Control House.

**Process
Description:** The 2607-WTX Septic Tank and drain field were designed to accept and treat sanitary sewer effluent from the associated structure.

Waste Type: Sanitary Sewage

**Waste
Description:** The current flow rates for the 2607-WTX system are unknown. This unit received sanitary sewer effluent at an estimated rate of 26 cubic feet (0.74 cubic meters) per day in 1987.

WMA U

Code: 241-U-A **Classification:** Accepted

Names: 241-U-A; 241-U-A Diversion Box; 241-U-A Valve Pit **Reclassification:** None

Type: Valve Pit **Start Date:** 1/1/1973

Status: Inactive **End Date:**

Description: This unit is a rectangular reinforced concrete structure. The valve pit is below grade with the cover block above grade. It has been covered with foam. Valve handles extended above the cover block through penetrations.

Location: Valve Pit 241-U-A is located southeast of Tank 241-U-102 and northeast of Tank 241-U-105.

Release Description: This unit is designed to contain leaks from transfers and drainage from operations within the unit.

Related Sites/ Structures: The 241-U-A Valve Pit is associated with the 241-U Tank Farm and the 241-U-105 Tank. Flush Pit 241-U-A is also associated with the valve pit.

Process Description: This unit was designed to route waste solutions to the 241-U Tanks from the 242-S Evaporator Building.

Waste Type: Process Effluent

Waste Description: The unit transports waste solutions from processing and decontamination operations. Quantities are variable according to specific plant operations. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Code: 241-U-B **Classification:** Accepted

Names: 241-U-B; 241-U-B Diversion Box; 241-U-B Valve Pit **Reclassification:** None

Type: Valve Pit **Start Date:** 1/1/1973

Status: Inactive **End Date:**

Description: This unit is a rectangular reinforced concrete structure that has been covered with foam. The valve pit is below grade with the cover block above grade. Valve handles extended above the cover block through penetrations.

Location: Valve Pit 241-U-B is located southwest of Tank 241-U-101 and northwest of Tank 241-U-104.

Related Sites/ Structures: The 241-U-B Valve Pit is associated with the 241-U Tank Farm and the 241-U-105 Tank. Flush Pit 241-U-B is also associated with the valve pit.

Process Description: This unit was designed to route waste solutions to the 241-U Tanks from the 242-S Evaporator Building.

Waste Type: Process Effluent

Waste Description: The unit transports waste solutions from processing and decontamination operations. Quantities are variable according to specific plant operations. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Code: 241-U-C **Classification:** Accepted

Names: 241-U-C; 241-U-C Diversion Box; 241-U-C Valve Pit **Reclassification:** None

Type: Valve Pit **Start Date:** 1/1/1973

Status: Inactive **End Date:**

Description: This unit is a rectangular reinforced concrete structure that has been covered with foam. The valve pit is below grade with the cover block above grade. Valve handles extend above the cover block through penetrations.

Location: Valve Pit 241-U-C is located southeast of Tank 241-U-108 and northeast of Tank 241-U-111.

Related Sites/Structures: The 241-U-C Valve Pit is associated with the 241-U Tank Farm and the 241-U-111 Tank. Flush Pit 241-U-C is also associated with the valve pit.

Process Description: This unit was designed to route waste solutions to the 241-U Tanks from the 242-S Evaporator Building.

Waste Type: Process Effluent

Waste Description: The unit transports waste solutions from processing and decontamination operations. Quantities are variable according to specific plant operations. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Code: 241-U-D **Classification:** Accepted

Names: 241-U-D; 241-U-D Diversion Box; 241-U-D Valve Pit **Reclassification:** None

Type: Valve Pit **Start Date:** 1/1/1973

Status: Inactive **End Date:**

Description: This unit is a rectangular reinforced concrete structure that has been covered with foam. The valve pit is below grade with the cover block above grade. Valve handles extend above the cover block through penetrations.

Location: Valve Pit 241-U-D is located southwest of Tank 241-U-107 and northwest of Tank 241-U-110.

Related Sites/Structures: The 241-U-D Valve Pit is associated with the 241-U Tank Farm and the 241-U-111 Tank. Flush Pit 241-U-D is also associated with the valve pit.

Process Description: This unit was designed to route waste solutions to the 241-U Tanks from the 242-S Evaporator Building.

Waste Type: Process Effluent

Waste Description: The unit transports waste solutions from processing and decontamination operations. Quantities are variable according to specific plant operations. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Code: 241-U-101 **Classification:** Accepted

Names: 241-U-101; 241-U-TK-101 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1946

Status: Inactive **End Date:** 1/1/1959

Description: This unit is a first-generation, underground single-shell storage tank. Tank 241-U-101 is the first tank of a three-tank cascade series. This tank is concrete-reinforced, cylindrical, dome-roofed with a single steel liner lying across the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-U-101 is located northeastern portion of the 241-U Tank Farm.

Related Sites/ Structures: Structures associated with Tank 241-U-101 include passive ventilation, two drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-U-101 included the T-Plant and REDOX Facilities.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-U-101 included metal waste from T-Plant. Waste was received from various storage tanks for processing in the 242-T Evaporator. Tank 241-U-101 received a variety of solid waste items. These included experimental fuel elements, shroud tubes, and samarium balls. The total fissile material contents of the waste was 54.01 ounces (1,530 grams) of 4.5 percent enriched uranium and 0.21 ounces (6 grams) of plutonium.

Code: 241-U-102 **Classification:** Accepted

Names: 241-U-102; 241-U-TK-102 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1946

Status: Inactive **End Date:** 1/1/1976

Description: This unit is a first-generation, underground single-shell storage tank. Tank 241-U-102 is the second tank of a three-tank cascade series. This tank is concrete-reinforced, cylindrical, dome-roofed with a single steel liner lying across the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-U-102 is located in the northern portion of the 241-U Tank Farm.

Related Sites/ Structures: Structures associated with Tank 241-U-102 include passive ventilation, six drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-U-102 included the T-Plant and REDOX Facilities.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-U-102 included metal waste from T-Plant. Waste was also received from various storage tanks for processing in the 242-T Evaporator.

Code: 241-U-103 **Classification:** Accepted

Names: 241-U-103; 241-U-TK-103 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1947

Status: Inactive **End Date:** 1/1/1978

Description: This unit is a first-generation, underground single-shell storage tank. Tank 241-U-103 is the third tank of a three-tank cascade series. This tank is concrete-reinforced, cylindrical, dome-roofed with a single steel liner lying across the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-U-103 is located in the northwestern portion of the 241-U Tank Farm.

Release Description: UPR-200-W-128.

Related Sites/ Structures: Structures associated with Tank 241-U-103 include a hydrogen monitor, passive ventilation, liquid observation well, five drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-U-103 included the T-Plant and REDOX Facilities.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-U-103 included metal waste from T-Plant and waste from various storage tanks for processing in the 242-T Evaporator.

Code: 241-U-104	Classification: Accepted
Names: 241-U-104; 241-U-TK-104	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1947
Status: Inactive	End Date: 1/1/1961

Description: This unit is a first-generation, underground single-shell storage tank. Tank 241-U-104 is the first tank of a three-tank cascade series. This tank is concrete-reinforced, cylindrical, dome-roofed with a single steel liner lying across the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-U-104 is located in the eastern portion of the 241-U Tank Farm.

Release Description: UPR-200-W-155

Related Sites/ Structures: Structures associated with Tank 241-U-104 include passive ventilation, four drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-U-104 included the T-Plant and REDOX Facilities.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-U-104 included bismuth phosphate metal waste. Diatomaceous earth was added in 1969.

Code: 241-U-105	Classification: Accepted
Names: 241-U-105; 241-U-TK-105	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1947
Status: Inactive	End Date: 1/1/1978

Description: This unit is a first-generation, underground single-shell storage tank. Tank 241-U-105 is the second tank of a three-tank cascade series. This tank is concrete-reinforced, cylindrical, dome-roofed with a single steel liner lying across the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-U-105 is located in the central portion of the 241-U Tank Farm.

Related Sites/ Structures: Structures associated with Tank 241-U-105 include, a hydrogen monitor, passive ventilation, liquid observation well, five drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-U-105 included the T-Plant and REDOX Facilities.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-U-105 included bismuth phosphate metal waste, REDOX waste, coating waste, decontamination waste, and evaporator feed and bottoms waste.

Code: 241-U-106 **Classification:** Accepted

Names: 241-U-106; 241-U-TK-106 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1948

Status: Inactive **End Date:** 1/1/1977

Description: This unit is a first-generation, underground single-shell storage tank. Tank 241-U-106 is the third tank of a three-tank cascade series. This tank is concrete-reinforced, cylindrical, dome-roofed with a single steel liner lying across the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-U-106 is located in the western portion of the 241-U Tank Farm.

Related Sites/ Structures: Structures associated with Tank 241-U-106 include passive ventilation, liquid observation well, four drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-U-106 included the T-Plant and REDOX Facilities.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-U-106 included bismuth phosphate metal waste, REDOX waste, coating waste, decontamination waste, and evaporator feed and bottoms waste.

Code: 241-U-107 **Classification:** Accepted

Names: 241-U-107; 241-U-TK-107 **Reclassification:** None

Type: Single-Shell Tank **Start Date:** 1/1/1948

Status: Inactive **End Date:** 1/1/1980

Description: This unit is a first-generation, underground single-shell storage tank. Tank 241-U-107 is the first tank of a three-tank cascade series. This tank is concrete-reinforced, cylindrical, dome-roofed with a single steel liner lying across the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-U-107 is located in the eastern portion of the 241-U Tank Farm.

Related Sites/ Structures: Structures associated with Tank 241-U-107 include a hydrogen monitor, passive ventilation, liquid observation well, four drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-U-107 included the T Plant and REDOX Facilities.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-U-107 included bismuth phosphate metal waste, REDOX waste, coating waste, decontamination waste, and evaporator feed and bottoms waste.

Code: 241-U-108 **Classification:** Accepted
Names: 241-U-108; 241-U-TK-108 **Reclassification:** None
Type: Single-Shell Tank **Start Date:** 1/1/1949
Status: Inactive **End Date:** 1/1/1979

Description: This unit is a first-generation, underground single-shell storage tank. Tank 241-U-108 is the second tank of a three-tank cascade series. This tank is concrete-reinforced, cylindrical, dome-roofed with a single steel liner lying across the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-U-108 is located in the central portion of the 241-U Tank Farm.

Related Sites/Structures: Structures associated with Tank 241-U-108 include a hydrogen monitor, passive ventilation, liquid observation well, four drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-U-108 included the T Plant, U Plant, and REDOX Facilities.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-U-108 included bismuth phosphate metal waste, REDOX waste, coating waste, decontamination waste, and evaporator feed and bottoms waste.

Code: 241-U-109 **Classification:** Accepted
Names: 241-U-109; 241-U-TK-109 **Reclassification:** None
Type: Single-Shell Tank **Start Date:** 1/1/1949
Status: Inactive **End Date:** 1/1/1980

Description: This unit is a first-generation, underground single-shell storage tank. Tank 241-U-109 is the third tank of a three-tank cascade series. This tank is concrete-reinforced, cylindrical, dome-roofed with a single steel liner lying across the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-U-109 is located in the western portion of the 241-U Tank Farm.

Related Sites/Structures: Structures associated with Tank 241-U-109 include a hydrogen monitor, passive ventilation, liquid observation well, four drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-U-109 included the T Plant, U Plant, and REDOX Facilities.

Waste Type: Storage Tank

Waste Description: Waste transferred to this unit included bismuth phosphate metal waste, REDOX waste, coating waste, decontamination waste, and evaporator feed and bottoms waste.

Code: 241-U-110 **Classification:** Accepted
Names: 241-U-110; 241-U-TK-110 **Reclassification:** None

Type: Single-Shell Tank	Start Date: 1/1/1946
Status: Inactive	End Date: 1/1/1975

Description: This unit is a first-generation, underground single-shell storage tank. Tank 241-U-110 is the first tank of a three-tank cascade series. This tank is concrete-reinforced, cylindrical, dome-roofed with a single steel liner lying across the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-U-110 is located in the southeastern portion of the 241-U Tank Farm.

Related Sites/ Structures: Structures associated with Tank 241-U-110 include a hydrogen monitor, passive ventilation, five drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-U-110 included the T Plant, U Plant, and REDOX Facilities.

Waste Type: Storage Tank

Waste Description: This unit received first-cycle decontamination waste, REDOX waste, and evaporator feed.

Code: 241-U-111	Classification: Accepted
------------------------	---------------------------------

Names: 241-U-111; 241-U-TK-111	Reclassification: None
---------------------------------------	-------------------------------

Type: Single-Shell Tank	Start Date: 1/1/1947
--------------------------------	-----------------------------

Status: Inactive	End Date: 1/1/1980
-------------------------	---------------------------

Description: This unit is a first-generation, underground single-shell storage tank. Tank 241-U-111 is the second tank of a three-tank cascade series. This tank is concrete-reinforced, cylindrical, dome-roofed with a single steel liner lying across the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-U-111 is located in the southern portion of the 241-U Tank Farm.

Related Sites/ Structures: Structures associated with Tank 241-U-111 include a hydrogen monitor, passive ventilation, liquid observation well, five drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-U-111 included the T Plant and REDOX Facilities.

Waste Type: Storage Tank

Waste Description: Tank 241-U-111 received first-cycle decontamination waste, REDOX waste, and 242-T Evaporator waste.

Code: 241-U-112	Classification: Accepted
------------------------	---------------------------------

Names: 241-U-112; 241-U-TK-112	Reclassification: None
---------------------------------------	-------------------------------

Type: Single-Shell Tank	Start Date: 1/1/1947
--------------------------------	-----------------------------

Status: Inactive	End Date: 1/1/1975
-------------------------	---------------------------

Description: This unit is a first-generation, underground single-shell storage tank. Tank 241-U-112 is the third tank of a three-tank cascade series. This tank is concrete-reinforced, cylindrical, and dome-roofed with a single steel liner lying across the tank wall. The tank is buried underground to provide radiation shielding.

Location: Tank 241-U-112 is located in the southwestern portion of the 241-U Tank Farm.

Related Sites/ Structures: Structures associated with Tank 241-U-112 include a hydrogen monitor, passive ventilation, five drywells, temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-U-112 included the T Plant and REDOX Facilities.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-U-112 included bismuth phosphate first-cycle waste and REDOX high-level waste from the 241-U Tank Farm.

Code: 241-U-153	Classification: Accepted
Names: 241-U-153; 241-U-153 Diversion Box	Reclassification: None
Type: Diversion Box	Start Date: 1/1/1946
Status: Inactive	End Date: 1/1/1981

Description: The tank farm is surrounded with a locked chain link fence. The tank farm has been covered with a layer of gravel. The 241-U-153 Diversion Box structure is mostly below ground. It is a reinforced concrete structure with 3 inch (8 centimeter) Hanford style nozzles.

Location: The 241-U-153 Diversion Box is located in the southeast corner of the 241-U Tank Farm. It is east of the 241-U-110 tank.

Related Sites/ Structures: This unit is associated with the 241-U-151, 241-U-152, 241-UR-152, 241-U-153 Diversion Boxes, 200-W-181-PL, 200-W-184-PL, 200-E-185-PL and the 241-U Tank Farm.

Process Description: This unit was used for the transfer of waste solutions from processing and decontamination operations.

Waste Type: Equipment

Waste Description: Waste lead is stored in the diversion box.

Waste Type: Process Effluent

Waste Description: This unit was used for transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operations. Lead shielding may also be contained inside the diversion box.

Waste Type: Equipment

Waste Description: Equipment associated with the diversion box includes transfer piping and nozzles.

Code: 241-U-201	Classification: Accepted
Names: 241-U-201; 241-U-TK-201	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1956
Status: Inactive	End Date: 1/1/1977

Description: This tank is made of reinforced-concrete and is lined with a steel cylinder. The structure has a concrete base slab and is buried underground to provide radiation shielding.

Location: Tank 241-U-201 is located inside the 241-U Tank Farm, west of tank 241-U-109.

Related Sites/ Structures: 241-U-201 is associated with 241-U-202, 241-U-203, 241-U-204 and 241-U-252. It has passive ventilation and temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-U-201 included the REDOX Facility and 241-U Tanks.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-U-201 included supernatant containing REDOX high-level waste from the 241-U Tank Farm.

Code: 241-U-202	Classification: Accepted
Names: 241-U-202; 241-U-TK-202	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1956
Status: Inactive	End Date: 1/1/1978

Description: This tank is made of reinforced-concrete and is lined with a steel cylinder. The structure has a concrete base slab and is buried underground to provide radiation shielding.

Location: Tank 241-U-202 is located inside the 241-U Tank Farm, west of tank 241-U-109.

Related Sites/ Structures: 241-U-202 is associated with 241-U-201, 241-U-203, 241-U-204 and 241-U-252. It has passive ventilation and temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-U-202 included the REDOX Facility and 241-U Tanks.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-U-202 included supernatant containing REDOX high-level waste from the 241-U Tank Farm.

Code: 241-U-203	Classification: Accepted
Names: 241-U-203; 241-U-TK-203	Reclassification: None
Type: Single-Shell Tank	Start Date: 1/1/1956
Status: Inactive	End Date: 1/1/1977

Description: This tank is made of reinforced-concrete and is lined with a steel cylinder. The structure has a concrete base slab and is buried underground to provide radiation shielding.

Location: Tank 241-U-203 is located inside the 241-U Tank Farm, west of the 241-U-112 tank.

Related Sites/ Structures: 241-U-203 is associated with 241-U-201, 241-U-202, 241-U-204 and 241-U-252. It has passive ventilation and temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-U-203 included the REDOX Facility and 241-U Tanks.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-U-203 included supernatant containing REDOX high-level waste from the 241-U Tank Farm.

Code: 241-U-204 **Classification:** Accepted
Names: 241-U-204; 241-U-TK-204 **Reclassification:** None
Type: Single-Shell Tank **Start Date:** 1/1/1954
Status: Inactive **End Date:** 1/1/1978

Description: This tank is made of reinforced-concrete and is lined with a steel cylinder. The structure has a concrete base slab and is buried underground to provide radiation shielding.

Location: Tank 241-U-204 is located inside the 241-U Tank Farm, west of the 241-U-112 tank.

Related Sites/ Structures: 241-U-204 is associated with 241-U-201, 241-U-202, 241-U-203, and 241-U-252. It has passive ventilation and temperature and surface level measurement instruments.

Process Description: Waste sources for Tank 241-U-204 included the REDOX Facility and 241-U Tanks.

Waste Type: Storage Tank

Waste Description: Waste transferred to Tank 241-U-204 included supernatant containing REDOX high-level waste from the 241-U Tank Farm.

Code: 241-U-252 **Classification:** Accepted
Names: 241-U-252; 241-U-252 Diversion Box **Reclassification:** None
Type: Diversion Box **Start Date:** 1/1/1946
Status: Inactive **End Date:** 1/1/1983

Description: The 241-U-252 Diversion Box is a reinforced concrete structure with 3 inch (8 centimeter) Hanford style nozzles.

Location: The 241-U-252 Diversion Box is located in the southwest corner of the 241-U Tank Farm.

Related Sites/ Structures: This unit is associated with the 241-U-301 Catch Tank, 241-U-152, and 241-U-153 Diversion Boxes, and 241-U Tank Farm.

Process Description: This unit was used for the transfer of waste solutions from processing and decontamination operations.

Waste Type: Equipment

Waste Description: Waste lead is stored in the diversion box.

Waste Type: Equipment

Waste Description: Equipment associated with the diversion box includes transfer piping and nozzles.

Waste Type: Process Effluent

Waste Description: This unit was used for transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operations. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Code: 241-U-301 **Classification:** Accepted

Names: 241-U-301; 241-U-301B; V478; 231-U-301 Catch Tank **Reclassification** None

Type: Catch Tank **Start Date:** 1/1/1946

Status: Inactive **End Date:** 1/1/2005

Description: The 241-U-301 structure consists of a catch tank and a pump pit directly above the catch tank. The catch tank is an unlined, reinforced concrete tank buried below grade to provide radiation shielding.

Location: The 241-U-301 Catch Tank is located inside the 241-U Tank Farm, south of the 241-U-112 Tank and east of the 241-U-252 Diversion Box.

Related Sites/ Structures: The catch tank is associated with 241-U Tank Farm, and the 241-U-151, 241-U-152, 241-U-153, and 241-U-252 Diversion Boxes and drain line (V478) discussed in sitecode 200-W-184-PL.

Process Description: The 241-U-301 Catch Tank, located inside the tank farm fence, collected overflow and leaks from Diversion Boxes 241-U-151 and 241-U-152. These two diversion boxes are located outside the tank farm fence, near the corner of 16th St and Canton Ave.

Waste Type: Storage Tank

Waste Description: This unit was used as containment for waste solutions that were transferred from processing and decontamination operations.

Code: 244-U DCRT **Classification:** Accepted

Names: 244-U DCRT; 244-U Double-Contained Receiver Tank; 244-U Receiver Tank; 244-U Receiving Vault; 244-U RT; 244-U-TK/SUMP **Reclassification** None

Type: Receiver Tank **Start Date:** 1/1/1987

Status: Inactive **End Date:**

Description: This site consists of an underground reinforced concrete structure in a steel-lined vault. Inside the vault (lower part of structure) is a 21,000-gallon (79,500 liter) carbon steel tank, set horizontally. The structure also contains a pump pit and sump. Approximately 0.31 meter (1 foot) of the structure extends above ground.

Location: This site is located near the southeast corner of the 241-U Tank Farm.

Related Sites/ Structures: The unit is associated with 241-U Tank Farm and the 244-U-2904 Flush Pit.

Process Description: This site was intended to receive saltwell waste from the 241-U Tank Farm. This site has not been used for its intended purpose. No waste has been placed in this tank.

Waste Type: Water

Waste Description: This site does not contain waste, although the site was designed to receive saltwell waste. The unit tank does contains water from operational tests.

Code: 244-U-2904 **Classification:** Not Accepted

Names: 244-U-2904; 244-U Flush Pit **Reclassification** None

Type: Flush Pit **Start Date:**

Status: Inactive**End Date:**

Description: The site is a building inside the 241-U tank farm fence. The building does not contain any radioactive or hazardous material. The postings on the 241-U Tank Farm fence include Contamination Area, Radiation Area, Radioactive Material and Underground Radioactive Material Area signs.

Location: The flush pit is located in the southeast corner of the 241-U Tank Farm, inside the tank farm fence. It is directly south of the 244-U Double Contained Receiver Tank.

Related Sites/ Structures: The flush pit is associated with the 244-U DCRT.

Process Description: The 244-U DCRT was never commissioned and hence has never seen any waste. The flush pit associated with this DCRT has never had any waste associated with it and is considered inactive.

Code: 241-UR-151**Classification:** Accepted**Names:** 241-UR-151; 241-UR-151 Diversion Box; Drain Lines 5764 and 5765**Reclassification:** None**Type:** Diversion Box**Start Date:** 1/1/1949**Status:** Inactive**End Date:** 1/1/1980

Description: The diversion box and surrounding area has been covered with shotcrete. This unit is constructed of reinforced concrete and is rectangular in shape.

Location: The 241-UR-151 Diversion Box is located in the northern portion of the 241-U Tank Farm, inside the tank farm fence.

Related Sites/ Structures: The 241-UR-151 Diversion Box is associated with the 241-UR-152, 241-UR-153, 241-UR-154, and 241-U-151 Diversion Boxes. The unit is also associated to the 221-U Canyon Building and various 200 West Area Operations Facilities. The drain lines are 5764 and 5765.

Process Description: This unit is the master diversion box for the 241-U Tank Farm. The diversion box was used to transfer waste solution to and from the tank farm.

Waste Type: Process Effluent

Waste Description: This unit was used for transfer of waste solutions from processing and decontamination. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Waste Type: Equipment

Waste Description: Equipment associated with the diversion box includes transfer piping and nozzles.

Waste Type: Equipment

Waste Description: Waste lead is stored in the diversion box.

Code: 241-UR-152**Classification:** Accepted**Names:** 241-UR-152; 241-UR-152 Diversion Box; Line 5053**Reclassification:** None

Type: Diversion Box **Start Date:** 1/1/1949
Status: Inactive **End Date:** 1/1/1980

Description: This unit is an underground reinforced concrete structure. All nozzles are 4 inch (10 centimeters) REDOX style.

Location: This unit is located east of Tank 241-U-101, inside the 241-U Tank Farm.

Related Sites/ Structures: The 241-UR-152 Diversion Box is associated with the 241-UR-151 Diversion Box and the 241-U-101, 241-U-102, and 241-U-103 cascade series. The drain line to 241-U-102 is line 5053.

Process Description: This unit was used for the transfer of waste solutions from processing and decontamination operations.

Waste Type: Equipment

Waste Description: Equipment associated with the diversion box includes transfer piping and nozzles.

Waste Type: Equipment

Waste Description: Waste lead is stored in the diversion box.

Waste Type: Chemicals

Waste Description: This unit was used for transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operations.

Code: 241-UR-153 **Classification:** Accepted

Names: 241-UR-153; 241-UR-153 Diversion Box; Line 5253 **Reclassification:** None

Type: Diversion Box **Start Date:** 1/1/1946

Status: Inactive **End Date:** 1/1/1983

Description: This unit is a reinforced concrete structure.

Location: This unit is located east of the 241-U-104 Tank, inside the 241-U Tank Farm.

Related Sites/ Structures: The 241-UR-153 Diversion Box is associated with the 241-U-153 and 241-UR-152 Diversion Boxes and the 241-U-104, 241-U-105, 241-U-106 Cascade Series. The drain line to tank 241-U-105 is line 5253.

Process Description: This unit was used for the transfer of waste solutions from processing and decontamination operations.

Waste Type: Process Effluent

Waste Description: This unit was used for transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operation.

Waste Type: Equipment

Waste Description: Equipment associated with the diversion box includes transfer piping and nozzles.

Waste Type: Equipment

Waste Description: It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Code: 241-UR-154 **Classification:** Accepted

Names: 241-UR-154; 241-UR-154 Diversion Box; Line 5453 **Reclassification:** None

Type: Diversion Box **Start Date:** 1/1/1949

Status: Inactive **End Date:** 1/1/1980

Description: This unit is a reinforced concrete structure.

Location: The 241-UR-154 Diversion Box is located east of the 241-U-107 Tank, inside the 241-U Tank Farm.

Related Sites/Structures: This unit is associated with the 241-U-153, 241-U-151, 241-U-152, 241-UR-153 Diversion Boxes and the 241-U-107, 241-U-108, 241-U-109 Cascade Series. The drain line to tank 241-U-107 is line 5453.

Process Description: This unit was used for the transfer of waste solutions from processing and decontamination operations.

Waste Type: Equipment

Waste Description: Equipment associated with the diversion box includes transfer piping and nozzles.

Waste Type: Equipment

Waste Description: It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Waste Type: Process Effluent

Waste Description: This unit was used for transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operations.

Code: 244-UR VAULT **Classification:** Accepted

Names: 244-UR VAULT; 244-UR Vault (Tanks -001 Through -004); Lines 5764 and 5765 **Reclassification:** None

Type: Receiving Vault **Start Date:** 1/1/1952

Status: Inactive **End Date:** 1/1/1975

Description: The 241-U Tank Farm is posted as a Contamination Area. The vault was covered with pumped concrete in 1992. The vault is surrounded with post and chain and marked with IMUST signs.

The 244-UR Vault is an underground concrete structure divided vertically into four sections (process vaults). Each section houses a tank and a sump. The sections are divided horizontally to provide pump pits above the tanks. The pump pits contain pumps and piping that were used during liquid transfers. The walls, floors, horizontal divisions, and roofs (ground level) are constructed of reinforced concrete. The sumps are located in the sections occupied by Tanks 244-UR-001, 244-UR-002, 244-UR-003 and 244-UR-004. Tank 244-UR-001 is a slurry accumulator tank. Tanks 244-UR-002 and 244-UR-003 are identical blend tanks. Tank 244-UR-004 is a process tank. There are also above ground service facilities that include four

instrument shelters, an inlet filter enclosure, and six risers used to measure liquid levels in tanks and sumps. Conditioned inlet air to the vault was supplied through an above grade supply system located just north of the vault. Exhaust air from the vault was passed through an underground filter chamber, then to an above grade exhaust fan and discharge stack.

The 244-UR Vault was used until 1956 and was taken out of regular service in 1957. Apparently, the vault tanks were not used after this time and the entire vault was interim stabilized in 1985.

Presumably, some wastes (sludges and liquids) were left in the tanks of the 244-UR Vault at the close of active vault use in the 1950's as records from the 1970's and early 1980's report varying amounts of wastes in the tanks and tank pits/sumps. Intrusion of water (precipitation) from the ground surface above the vault contributed to the varying amounts of liquid found in the tank pits during this period. SD-WM-TI-356 lists liquid level readings (and the reasons for increases and decreases in the liquid level readings) in the tanks and sumps over the period from 1974 through 1985.

The records associated with the tank isolation project (B-231) of the mid 1980's provide the most reliable current estimates of tank and tank pit waste volumes. These estimates are provided for each of the tanks (see subsites section). Project B-231 isolated the 244-UR Vault as a single system. Four above grade instrument and electrical enclosures were removed. The underground conduit trenches existing between each enclosure and the companion vault compartment were sealed by casting a concrete slab over the enclosure footing. Grade level raw water nozzles that connected to the vault internal piping were cut and capped. Grade level steam distribution piping and control valving were removed. Process steam lines that connected to the vault internal piping were cut and capped. Encased process pipelines interconnect the 244-UR Vault with the 241-UR-151 Diversion Box. Closure of these lines was not required as both diversion boxes were already isolated. Process air lines were cut and blind flanges were installed onto both sides of each branch line isolated. The evaporative cooling unit was abandoned in place and the ducting cut, then sealed with a concrete plug. The above grade ventilation fans, above grade ducting, and discharge stack were previously removed. The fan inlet plenum was built into the fan base structure and was plugged by filling the plenum with sand and casting a fiberglass weather cover over the fan inlet ducts. The grade level vault cover blocks were sealed by a fiberglass weather cover. WHC-EP-0560 states that liquid level readings for 1979 indicate the 244-UR-001 and 244-UR-003 had been pumped down to "minimum level", whereas 244-UR-002 was still listed as "active" ("Auxiliary Tanks, Sumps, and Vaults Solid and Liquid Volumes", J. E. Mirabella, 1978). Tank 244-UR-004 was also pumped to a minimum level.

Location:	This site is located at the north end of the 241-U Tank Farm.
Related Sites/ Structures:	The unit is associated with 241-U Tank Farm and transfer lines. The drain lines to the sump are lines 5764 and 5765.
Process Description:	The 244-UR Vault was constructed in 1951 for use in conjunction with uranium recovery processing conducted in U Plant (221-U). The function of the vault included reception of uranium-bearing waste slurries from Tanks 241-U-101, 241-U-102, 241-U-103, and 241-U-107 in the 241-U Tank Farm, which at that time contained neutralized metal waste generated by the original bismuth phosphate process. The vault was used for subsequent blending, pH adjustment (acidification) and conditioning of this waste as feed material for the tributyl phosphate uranium extraction process in the U Plant Canyon.
Waste Type:	Process Effluent
Waste Description:	This unit received waste from 241-U Tank Farm. The volumes in Tanks 244-UR-001, 244-UR-002, 244-UR-003 and 244-UR-004 are unknown and not monitored. Tank volume estimates are provided in WHC-SD-EN-ES-040, Rev. 0 (see subsites information).

Waste Type: Equipment

Waste Description: The vault equipment, tanks, and concrete surfaces are contaminated.

Waste Type: Asbestos (non-friable)

Waste Description: The vault contains a pipe that has asbestos insulation and is encased in concrete. This pipe is also radioactively contaminated.

This Site has the Following SubSites:

Code: 244-UR VAULT:1

Names: 244-UR VAULT:1; 244-UR-001

Code: 244-UR VAULT:2

Names: 244-UR VAULT:2; 244-UR-002

Code: 244-UR VAULT:3

Names: 244-UR VAULT:3; 244-UR-003

Code: 244-UR VAULT:4

Names: 244-UR VAULT:4; 244-UR-004

Code: 244-UR VAULT:1

Classification: Accepted

Names: 244-UR VAULT:1; 244-UR-001

Reclassification: None

Type: Receiving Vault

Start Date:

Status: Inactive

End Date:

Description: The site is a vertical 0.635-centimeter (0.25-inch) carbon steel plate tank having a capacity of 189,250 liters (50,000 gallons). The tank dimensions are 6.1 meters by 6.1 meters (20 feet by 20 feet). The tank contains 7,010 liters (1,872 gallons) of sludge and 1476.2 liters (390 gallons) of supernatant. The tank was constructed in 1951 and was in operation from 1952 to 1956. The tank was taken out of service in 1957. Currently, the tank is stabilized and isolated. Tank 244-UR-001 was used as a slurry accumulator tank (comparable to 244-BXR Vault Tank, 244-BX-001 and 244-TXR Vault Tank, 244-TX-001). As such, it was used as the collection point for waste slurries sluiced-mined from the U Tank Farm. The accumulated wastes were pumped from Tank 244-UR-001 to other tanks in the vault for further conditioning (see subsites 244-UR-002 and 244-UR-003). Limited analytical data on the contents of Tank 244-UR-001 are available from a 1977 Atlantic Richfield Hanford Company (ARHCO) employee memorandum, "Isolation Criteria for 'Auxiliary' Tanks", C. M. Walker (Memorandum not in Waste Information Data System [WIDS] files). The values listed below have been taken from WHC-SD-EN-ES-040, Rev. 0. - pH 7.5, radiation level 25 millirads/hour, specific gravity 1.0 - cesium-137 476 microcuries/liter (1,800 microcuries/gallon) - uranium 0.528 milligrams/liter (2 milligrams/gallon) - total beta 845 microcuries/liter (3,200 microcuries/gallon) - total alpha 0.032 microcuries/liter (0.12 microcuries/gallon). Limited information on the contents of the 244-UR-001 Sump were reported in the same memorandum listed above. The values listed below have been taken from WHC-SD-EN-ES-040, Rev. 0. - pH 8.6, radiation level 30 millirads/hour - cesium-137 673 microcuries/liter (1,700 microcuries/gallon) - total beta 845 microcuries/liter (3,200 microcuries/gallon) - total alpha 0.0145 microcuries/liter (0.055 microcuries/gallon) WHC-SD-EN-ES-040, Rev.0 has listed the following safety issues: - Hydrogen Buildup: Low risk since the total waste volume in the tank and sump is limited to about 18,925 liters (5,000 gallons). - Ferrocyanide: No risk since little or no ferrocyanides are present and the tank contains mostly water. - Organic Salts: Tributyl phosphate containing wastes were present in this tank, so some amount of organic salts is probably present.

However, it is expected that this represents a low risk as the wastes are dilute. - Flammability: Low risk as little or no flammable material and no ignition sources are present. - Vapor Emission: Low risk because present waste content is not expected to contain significant amounts of volatile material. - Tank Integrity: No evidence of leaks emerged in the 1970's. Present waste content is not strongly corrosive, yet design life of the tank has been exceeded. Consequently, there is low to moderate risk of tank leakage. - Criticality Safety: Low risk (traces of plutonium only). - Radiological Hazard: High risk because UPR-200-W-24 resulted in contamination of soils surrounding the vault. Background readings in the vault are the 1 to 50 millirem range. - Heat Generation: Low risk (No Data). SD-WM-TI-356 lists liquid level readings and cumulative change history for the tank and sump. The last reading for the tank, on July 15, 1985, was 20.3 centimeters (8.00 inches). The last reading in the sump, on June 27, 1985, was 55.9 centimeters (22.00 inches).

The SubSite is Part Of:

Code: 244-UR VAULT

Names: 244-UR VAULT; 244-UR Vault (Tanks -001 Through -004); Lines 5764 and 5765

Code: 244-UR VAULT:2

Classification: Accepted

Names: 244-UR VAULT:2; 244-UR-002

Reclassification None

Type: Receiving Vault

Start Date:

Status: Inactive

End Date:

Description: The site is a vertical type 347, stainless steel, 0.635-centimeter (0.25-inch) thick tank having a capacity of 56,775 liters (15,000 gallons). The tank is 3.66 meters by 4.27 meters (12 feet by 14 feet). The tank contains 8720.6 liters (2,304 gallons) of sludge and 810 or 2157.5 liters (214 or 570 gallons) (conflicting data) of supernatant. The tank was constructed in 1951 and believed to be in operation from 1952 to 1976. The tank is stabilized and isolated.

Tanks 244-UR-002 and 244-UR-003, essentially identical tanks, were used for blending, temperature adjustment, acidification, and venting of wastes received from 244-UR-001 (comparable to 244-BXR Vault Tank, 244-BX-002 and 244-TXR Vault Tank, 244-TX-002). Nitric acid used in this conditioning was received from Tank 244-UR-004.

A sample of liquid was obtained from cell 2 of the 244-UR Vault on November 5, 1974 (Sample # T-9505 - laboratory data not available in the Waste Information Data System [WIDS] files.) The results listed below have been taken from WHC-SD-EN-ES-040, Rev. 0 and WHC-EP-0560.

- visual appearance, yellow with no solids
- pH 9.1, radiation level 1 millirad/hour, specific gravity 1.01
- cesium-137 177 microcuries/liter (670 microcuries/gallon)
- aluminum <.0013 molar (< 35 milligrams/liter)
- sodium .0732 molar (1,690 milligrams/liter)
- nitrite .000645 molar (30 milligrams/liter)
- nitrate .0306 molar (1,900 milligrams/liter)
- plutonium < 1.40 micrograms/liter (<5.34 micrograms/gallon)
- phosphate <.00356 molar (340 milligrams/liter)
- iron .0000414 molar (<1 milligram/liter)
- carbonate .0325 molar (2,000 milligrams/liter)
- strontium-89,90 5.68 microcuries/liter (21.5 microcuries/gallon)
- water 99.95%

Although the memorandum indicates that the sample was from Tank 244-UR-002, it is suspected that the sample is actually from the pit or sump since the June 7, 1977 Atlantic Richfield Company (ARCHO) internal memorandum, "Isolation Criteria for 'Auxiliary' Tanks", C. M. Walker, 1977, gives limited analytical results for Tank 244-UR-002 and sump contents as follows.

- total beta 845 microcuries/liter (3,200 microcuries/gallon)
- total alpha 0.032 microcuries/liter (0.12 microcuries/gallon).

Tank

- pH 0.7, radiation level 50 millirads/hour
- specific gravity 1.03
- cesium-137 0.87 microcuries/liter (3.3 microcuries/gallon)
- total beta 1321 microcuries/liter (5,000 microcuries/gallon)
- total alpha 0.37 microcuries/liter (1.4 microcuries/gallon)

Sump

- pH 9.0, radiation level 10 millirads/hour
- cesium-137 47.56 microcuries/liter (180 microcuries/gallon)
- total beta 66.05 microcuries/liter (250 microcuries/gallon)
- total alpha 0.1 microcuries/liter (0.38 microcuries/gallon)

WHC-SD-EN-ES-040, Rev.0 has listed the following safety issues.

- Hydrogen Buildup: Low risk since the total waste volume in the tank and sump is limited to about 11,355 liters (3,000 gallons) of dilute liquid waste. Any hydrogen generated should readily diffuse out of the tank and vault.
- Ferrocyanide: No risk since little or no ferrocyanides are present and the tank contains mostly water.
- Organic Salts: Tributyl phosphate containing wastes were present in this tank, so some amount of organic salts is probably present. However, it is expected that this represents a low risk as the wastes are dilute.
- Flammability: Low risk as little or no flammable material and no ignition sources are present.
- Vapor Emission: Low risk because present waste content is not expected to contain significant amounts of volatile material.
- Tank Integrity: No evidence of leaks emerged in the 1970's. Present waste content is not moderately corrosive, and the design life of the tank has been exceeded. Consequently, there is moderate to high risk of tank leakage.
- Criticality Safety: Low risk (traces of plutonium only).
- Radiological Hazard: High risk because UPR-200-W-24 resulted in contamination of soils surrounding the vault. Background readings in the vault are the 1 - 50 millirem range.
- Heat Generation: Low risk (No Data).

SD-WM-TI-356 lists liquid level readings and cumulative change history for the tank and sump. The last reading for the tank, on July 12, 1985, was 71.8 centimeters (28.25 inches). The last reading in the sump, on April 23, 1985, was 55.9 centimeters (15.25 inches).

The SubSite is Part Of:

Code: 244-UR VAULT

Names: 244-UR VAULT; 244-UR Vault (Tanks -001 Through -004); Lines 5764 and 5765

Code: 244-UR VAULT:3

Classification: Accepted

Names: 244-UR VAULT:3; 244-UR-003

Reclassification None

Type: Receiving Vault

Start Date:

Status: Inactive

End Date:

Description: The site is a vertical type 347, stainless steel, 0.635-centimeter (0.25-inch) thick tank having a capacity of 56,775 liters (15,000 gallons). The tank is 3.66 meters by 4.27 meters (12 feet by 14 feet). The tank contains 5934.9 liters (1,568 gallons) of sludge and 0 liters of supernatant. The tank was constructed in 1951. It is believed to be in operation from 1952 to 1976. The tank is stabilized and isolated.

Tank 244-UR-002 and 244-UR-003, essentially identical tanks, were used for blending, temperature adjustment, acidification, and venting of wastes received from 244-UR-001 (comparable to 244-BXR Vault Tank, 244-BX-002 and 244-TXR Vault Tank, 244-TX-002). Nitric acid used in this conditioning was received from Tank 244-UR-004.

A sample of liquid was obtained from cell 3 of the 244-UR Vault on November 5, 1974 (Sample # T-9505 laboratory data not available in the Waste Information Data System [WIDS] files.) The sample results listed below have been taken from WHC-SD-EN-ES-040, Rev. 0 and WHC-EP-0560.

- visual appearance, yellow with no solids
- pH 9.1, radiation level 1 millirad/hour, specific gravity 1.01
- cesium-137 177 microcuries/liter (670 microcuries/gallon)
- aluminum <.0013 molar (< 35 milligrams/liter)
- sodium .0732 molar (1,690 milligrams/liter)
- nitrite .000645 molar (30 milligrams/liter)
- nitrate .0306 molar (1,900 milligrams/liter)
- plutonium < 1.40 micrograms/liter (<5.34 micrograms/gallon)
- phosphate <.00356 molar (340 milligrams/liter)
- iron .0000414 molar (<1 milligram/liter)
- carbonate .0325 molar (2,000 milligrams/liter)
- strontium-89,90 5.68 microcuries/liter (21.5 microcuries/gallon)
- water 99.95%

Although the memorandum indicates that the sample was from Tank 244-UR-003, it is suspected that the sample is actually in the pit or sump since the June 7, 1977 Atlantic Richfield Company (ARCHO) internal memorandum, "Isolation Criteria for 'Auxiliary' Tanks", C. M. Walker, 1977, gives limited analytical results for Tank 244-UR-003 and sump contents as follows.

- total beta 845 microcuries/liter (3,200 microcuries/gallon)
- total alpha 0.032 microcuries/liter (0.12 microcuries/gallon).

Tank

- pH 0.7, radiation level 50 millirads/hour
- specific gravity 1.03
- cesium-137 0.87 microcuries/liter (3.3 microcuries/gallon)
- total beta 1321 microcuries/liter (5,000 microcuries/gallon)
- total alpha 0.37 microcuries/liter (1.4 microcuries/gallon)

Sump

- pH 9.0, radiation level 10 millirads/hour

- cesium-137 47.56 microcuries/liter (180 microcuries/gallon)
- total beta 66.05 microcuries/liter (250 microcuries/gallon)
- total alpha 0.1 microcuries/liter (0.38 microcuries/gallon)

WHC-SD-EN-ES-040, Rev.0 has listed the following safety issues.

- Hydrogen Buildup: Low risk since the total waste volume in the tank and sump is limited to about 11,355 liters (3,000 gallons) of dilute liquid waste. Any hydrogen generated should readily diffuse out of the tank and vault.
- Ferrocyanide: No risk since little or no ferrocyanides are present and the tank contains mostly water.
- Organic Salts: Tributyl phosphate containing wastes were present in this tank, so some amount of organic salts is probably present. However, it is expected that this represents a low risk as the wastes are dilute.
- Flammability: Low risk as little or no flammable material and no ignition sources are present.
- Vapor Emission: Low risk because present waste content is not expected to contain significant amounts of volatile material.
- Tank Integrity: No evidence of leaks emerged in the 1970's. Present waste content is not moderately corrosive, and the design life of the tank has been exceeded. Consequently, there is moderate to high risk of tank leakage.
- Criticality Safety: Low risk (traces of plutonium only).
- Radiological Hazard: High risk because UPR-200-W-24 resulted in contamination of soils surrounding the vault. Background readings in the vault are the 1 - 50 millirem range.
- Heat Generation: Low risk (No Data).

SD-WM-TI-356 lists liquid level readings and cumulative change history for the tank and sump. The last reading for the tank, on July 15, 1985, was 41.9 centimeters (16.5 inches). The last reading in the sump, on July 15, 1985, was 66.7 centimeters (26.25 inches).

The SubSite is Part Of:

Code: 244-UR VAULT

Names: 244-UR VAULT; 244-UR Vault (Tanks -001 Through -004); Lines 5764 and 5765

Code: 244-UR VAULT:4

Classification: Accepted

Names: 244-UR VAULT:4; 244-UR-004

Reclassification: None

Type: Receiving Vault

Start Date:

Status: Inactive

End Date:

Description: The 244-UR-004 is a stainless steel process tank measuring 3 meters (10 feet) in diameter and 4.2 meters (14 feet) tall. The tank has a 31,150 liter (8,230 gallon) capacity. The UR-004 was used to store nitric acid and has been reported to be empty. This tank fed nitric acid to the UR-002 and UR-003 tanks, during the Uranium Recovery Process operation in the 1950's. Because it was an acid feed tank, it is not believed to be radiologically contaminated.

The SubSite is Part Of:

Code: 244-UR VAULT

Names: 244-UR VAULT; 244-UR Vault (Tanks -001 Through -004); Lines 5764 and 5765

Code: 200-W-95

Classification: Accepted

Names: 200-W-95; Contaminated Soil at 241-U Tank Farm; Contamination Migration Beyond the 241-

Reclassification: None

U fence

Type: Contamination Migration

Start Date:

Status: Inactive

End Date:

Description: The site is the soil inside and adjacent to the chain link fence that surrounds the 241-U Tank Farm. Various radiological postings and warning signs are attached to the chain link fence. The interior of the tank farm complex is covered with gravel. Many risers and monitoring devices for the underground structures are visible on the surface. The individual unplanned releases associated with the 241-U Tank Farm are not separately marked or posted. Occasionally, radioactive contamination is found adjacent to the outside of the tank farm fence, resulting in a contamination zone extension around the tank farm perimeter. These areas will also be considered tank farm soil. A small area near the west access gate, outside the fence, was excavated to attempt to remove contaminated soil. This area was marked with Contamination Area signs but was covered with clean dirt and downposted to an Underground Radioactive Material area in December 2003.

Location: The site is located at the intersection of 16th Street and Camden Ave., in 200 West Area.

Release Description: The exact extent (horizontal and vertical) of the soil contaminated by unplanned releases that occurred within this farm over the years are not known. Some of the single shell tanks have leaked to the soil below the tank farm. Other releases spread contamination to the surface soil surrounding the tanks.

Related Sites/ Structures: Unplanned Releases UPR-200-W-128, UPR-200-W-132, UPR-200-W-154, UPR-200-W-155, UPR-200-W-156, UPR-200-W-157, UPR-200-W-24 and 200-W-91 are associated with the 241-U Tank Farm. These WIDS sitecodes have been consolidated into 200-W-95.

Waste Type: Process Effluent

Waste Description: Liquid releases occurred from underground leaks in tanks and transfer lines. Airborne contamination spreads occurred from activities conducted in valve pits and diversion boxes. Both types of releases contributed to the contamination in the soil.

Not Applicable

Code: 100-B-4 **Classification:** Not Accepted

Names: 100-B-4; Building Foundation; Undocumented Solid Waste Site **Reclassification:** None

Type: Spoils Pile/Berm **Start Date:**

Status: Inactive **End Date:**

Description: The site is a rectangular area 8.5 meters (28 feet) east/west by 13.1 meters (43 feet) north/south and encircled by large stones neatly stacked 0.3 meters (1 foot) high. Inside the area and on the north end is a 4 meter (13 foot) by 4.0 meter (13 foot) area encircled by 0.3 meter (1 foot) soil berm. Two 0.3 meter (1 foot) mounds of soil are in the south portion of the area. The surrounding area appears to have been a plowed field that was cleared of large stones. A long line of similar rocks runs parallel to the perimeter road, between the encircled area and the road. The site is distinguishable from the surrounding area only by the arrangement of large stones and soil. During a site visit on 9/13/94, two metal objects were present nearby, but didn't appear to be necessarily associated with this site. One of the objects looked like an empty, rusty paint can.

Location: The site is in the 100B area, 760 meters (2500 feet) northeast of the 105-B reactor building and 170 meters (550 feet) northwest of 1607-B1. It is due west of the perimeter road.

Code: 100-B-7 **Classification:** Not Accepted

Names: 100-B-7; 100-B Clean Water Pipelines; 100-B Service Water Pipelines **Reclassification:** None

Type: Product Piping **Start Date:** 1/1/1944

Status: Inactive **End Date:** 1/1/1968

Description: The site encompasses the clean water upstream pipelines for the 100-B Area, including underground pipelines used to transport raw, fire, export, and sanitary water from the river pumphouse, to the water treatment facilities and to 100-B Area facilities and fire hydrants. Excluded lines are those within buildings, process and septic sewer pipes, pipes that carried water treated with sodium dichromate, and all lines that are downstream from the reactor building, i.e., those lines that carry cooling water from the reactor to the retention basin, trench, and/or the river are excluded.

Location: The location is described as underground lines running from the 181-B Pumphouse to the 183-B Water Treatment Facilities, and from there to other 100-B Area buildings, fire hydrants, and south to the 100-C Area, stopping at a line about half-way between the B and C areas, at about northing 144370 N.

Related Sites/ Structures: Related structures include the 181-B River Pumphouse, the 182-B Reservoir, 108-B Building, 183-B Basins and Clearwells, 185-B Building, 190-B Building, and 105-B Reactor. Associated pipeline sites include 100-B-14 (Septic and Process Sewer Pipelines), 100-B-8 (Effluent Pipelines), and 100-C-5 (100-C Area Water Treatment Facility Pipelines, which connect to these in the 100-B Area).

Process Description: Reactor cooling water was pumped from the Columbia River, settled and treated to remove minerals, and pumped to the reactor core at a rate of 1.93E+05 liters (51,000 gallons) to 2.69E+05 liters (71,000 gallons) per minute.

Waste Type: Water

Waste Only uncontaminated piping remains.

Description:

Code: 100-B-17

Classification: Accepted

Names: 100-B-17; Transite on Columbia River Shoreline at 100B

Reclassification Rejected (8/19/2010)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site is an old dumping area. The site is below the high water mark and is visible only at very low river flow.

Location: The site is located just west of 181-B River Pumphouse on the Columbia River shoreline. At approximate coordinates, E 564499.8, N 145319.2 and E 564509.9 and N 145332.3.

Waste Type: Demolition and Inert Waste

Waste Description: The waste is a mixture of material ranging from corrugated transite, fire brick, milk bottles, concrete form fittings, small rebar, pipe fittings, chunks of vitrified clay, nuts and bolts. The corrugated transite consists of 15-20 large chunks that vary from 0.61 to 1.83 m (2 to 6 ft), 0.15 to 0.61 m (0.5 to 2 ft) wide, spread over most of a 220 sq m (2400 sq ft), in a single layer orientation. The transite is covered with green slime and the metal pieces are extremely rusted. Likely, the material has been in the river for a long time. The corrugated transite is not breaking into smaller chunks.

Code: 100-B-29

Classification: Not Accepted

Names: 100-B-29; Pipe Located Southeast of the 183-B Clearwells

Reclassification None

Type: Product Piping

Start Date:

Status: Inactive

End Date:

Description: The site consisted of an approximately 0.15 m (6 in) diameter carbon steel pipe, about 3 m (10 ft) long, with a partially intact mastic wrap (P6120025). The pipe was oriented in a northwest to southeast direction. The northwesterly end was jagged metal suggesting that it may have been severed during an excavation.

Location: The site is located in the 100-B/C Area southeast of the 183-B Clearwells and southeast of the road intersection of Bodie and Bow Streets. The approximate Washington State Plane coordinates are E 564943, N 144341.

Code: 100-B-30

Classification: Not Accepted

Names: 100-B-30; Pipe Located South of the 100-B/C Perimeter Road

Reclassification None

Type: Product Piping

Start Date:

Status: Inactive

End Date:

Description: The site consists of an approximately 0.08 m (3 in) carbon steel pipe, over 4 m (13 ft) long, with a coupling joint on one end. The pipe appears to be lined with concrete. The other end was severed, possibly with the use of a cutting torch. The pipe is oriented in a northwest to

southeast direction and is not part of an intact system. The southeasterly end of the pipe is partially buried below grade and the presence of vegetation at that end suggests that the pipe has been at this location for an extended period of time. There is no evidence of staining or any additional pipe or piping systems in the area, and is located in an area of other scattered surface debris outside the 100-B/C perimeter fence. The pipe is believed to be surficial debris only.

Location: The site is located in 100-B/C Area, south of the 100-B/C perimeter road, and north of the railroad tracks. At approximate Washington State Plane Coordinates E 564732, N 143699, The inner pipe material was sampled on February 18, 2009 (Sample No. J18HX2) and analyzed for asbestos using Polarized Light Microscopy. The results showed that the material did not contain asbestos minerals.

Waste Type: Equipment

Waste Description: The waste is a single segment of pipe.

Code: 118-B-7	Classification: Accepted
Names: 118-B-7; 111-B Solid Waste Burial Site	Reclassification: Rejected (12/9/2004)
Type: Burial Ground	Start Date: 1/1/1951
Status: Inactive	End Date: 1/1/1968

Description: The unit appears as the southern portion of a cobble-covered field. The central portion of the field is covered with natural vegetation and there is a permanent concrete marker in the southern section.

Location: This unit is located adjacent to and just south of the 111-B Decontamination Station.

Process Description: This site received decontamination materials and assorted equipment from the 111-B Decontamination Facility and workshop from 1951 to 1968.

Waste Type: Equipment

Waste Description: This unit received small amounts of waste from the 111-B Facility, which was originally used as a charge makeup and reactor fuel inspection station. After one year, the 111-B Facility was used as a decontamination facility for equipment and a workshop for low-level contaminated equipment. This unit also received decontamination materials and assorted equipment from that building. Small amounts of reactor hardware may have also been placed in this unit. Potential contaminants include: Co-60, Ni-63, RCRA metals.

Code: 126-B-1	Classification: Accepted
Names: 126-B-1; 184-B Power House Ash Pit; 188-B Ash Disposal Area	Reclassification: Rejected (6/25/1998)
Type: Coal Ash Pit	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1969

Description: The 126-B-1 site is a large vegetation covered depression and surrounding ash piles. The depression is approximately 60 meters (200 feet) long, 60 meters (200 feet) wide, and 3 meters (10 feet) deep. An earthen berm divides the site into two sections. The pit is bounded on the north, east, and west sides by three large ash piles that extend 9 to 10 meters (30 to 33 feet) high. On the west side of the pit is a large wooden ramp that is in a state of disrepair. A large pipe enters the depression in the southwest corner. Including the surrounding ash piles, the

Location: overall site dimensions are approximately 200 meters by 200 meters (650 feet by 650 feet).
The 126-B-1 Ash Pit is located north of the 184-B Powerhouse.

Related Sites/ Structures: The ash pit is related to the 184-B Powerhouse.

Process Description: Coal ash from the 184-B Powerhouse was mixed with raw river water and sluiced in slurry form to the ash pit via a 20 centimeter (8 inch) ashcolite pipe.

Waste Type: Ash

Waste Description: The site received coal ash from the 184-B Powerhouse. Coal ash from analogous sites has been analyzed using the EP Toxicity Test in accordance with WAC 173-303, and no hazardous materials were found.

Code: 126-B-4

Classification: Accepted

Names: 126-B-4; 126-B-4 Brine Pit. 184-B Salt Dissolving Pit and Brine Pump House; B Area Brine and Salt Dilution Pits

Reclassification: Rejected (9/9/1997)

Type: Sump

Start Date: 1/1/1944

Status: Inactive

End Date: 1/1/1969

Description: The salt dissolving pits and brine pump pit were part of a single below-grade concrete structure that provided brine for the 184-D Powerhouse. The structure has been demolished and buried in situ. No evidence of the site remains at the surface. Before the structure was demolished, it was described as being partially backfilled with rubble with approximately 1900 liters (500 gallons) of water in the brine pump pit. The two salt dissolving pits each had inner dimensions of 4.3 meters (14 feet) long by 2.4 meters (8 feet) wide by 2.8 meters (9.25 feet) tall. They had a design high water line 2.4 meters (7.75 feet) from the pit bottom. An overflow slot connecting the two dissolving pits was located 0.3 meters (1 foot) above the high water line. The bottom of each pit was filled with a 12.7 centimeter (5 inch) layer of 1.3 to 2.6 centimeter (1/2 to 1 inch) gravel topped by a 17.8 centimeter (7 inch) layer of 0.3 to 0.6 centimeter (1/8 to 1/4 inch) gravel. The dissolving pits each had a 2.4 meter (8 foot) by 0.9 meter (3 feet) opening at the top for receiving salt. Each pit had a capacity of 23,600 kilograms (52,000 pounds) of salt. The brine pump pit is located adjacent to the two salt dissolving pits. The pit was 3.3 meters (10.67 feet) long by 2.2 meters (7.33 feet) wide by 2.1 meters (7 feet) deep. It held two pumps and associated piping (all brass) for the brine system. The floor of the pump pit sloped toward a 46 by 46 by 46 centimeter (18 by 18 by 18 inch) sump in a corner.

Location: The site is located north of 184-B and just south of the railroad tracks.

Related Sites/ Structures: The site is associated with the 184-B Power House.

Process Description: The brine was used to regenerate the zeolite ion exchange demineralizers that were part of the powerhouse water treatment system.

Waste Type: Demolition and Inert Waste

Waste Description: The structure was demolished and buried in situ.

Code: 128-B-1

Classification: Not Accepted

Names: 128-B-1; 100 B/C Burning Pit; 100-B Burning Pit **Reclassification** None

Type: Burn Pit **Start Date:** 1/1/1943

Status: Inactive **End Date:** 1/1/1968

Description: The site has been described as a burn pit. During a field investigation on October 17, 1995, it was noted that the area is covered with cheatgrass and appears undisturbed with no evidence of burning. An elevated area to the south is covered with rabbitbrush, boulders, and appears to be disturbed. The elevated area also shows no evidence of burning.

Location: The 128-B-1 burn pit is identified in PNL-6456 as a 30 meters (100 feet) by 30 meters (100 feet) pit at coordinates WCS83S E565942.7, N145244.7 (N71500 W78500). This places it in a low area southeast of 116-C-1 and west of the perimeter road.

Code: 132-B-2 **Classification:** Accepted

Names: 132-B-2; 132-B-2 Stack; 116-B Reactor Exhaust Stack **Reclassification** None

Type: Stack **Start Date:** 1/1/1944

Status: Inactive **End Date:** 1/1/1968

Description: The unit is part of the 105-B Reactor Gas and Exhaust Air System. The unit is still standing and constructed of reinforced concrete with a base diameter of approximately 4.9 meters (16 feet).

Location: The unit is located on the south side of 105-B.

Related Sites/Structures: Following completion of the confinement project in 1960, the air was diverted via an above-ground aluminum duct and an underground, reinforced concrete duct to the 117-B Filter Building. After flowing through the filters, the air went through a below-grade concrete duct and an above-grade aluminum duct into the exhaust stack.

Waste Type: Demolition and Inert Waste

Waste Description: Until the 117 Filter Building was built in 1960, air moving from the least contaminated zones through increasingly contaminated zones was discharged to the unit unfiltered. The unit received low-level contamination from the reactor.

Code: 1607-B3 **Classification:** Accepted

Names: 1607-B3; 1607-B3 Sanitary Sewer System; 1607-B3 Septic Tank System; 124-B-3 **Reclassification** Closed Out (5/31/2001)

Type: Septic Tank **Start Date:** 1/1/1944

Status: Inactive **End Date:** 1/1/1974

Description: The site is a Closed Out septic system which includes a septic tank, tile field, and associated piping. It was demolished in place in 1988. The site is no longer visually apparent and appears as a cobble-covered field with natural vegetation growing on its surface.

The 1607-B3 Septic Tank was constructed of reinforced concrete. The tank was 2.9 meters (9.5 feet) long, 1.4 meters (4.5 feet) wide and 3.5 meters (11.42 feet) deep (inner dimensions). The tank had a design capacity of 6,360 liters (1,680 gallons) based on a user capacity of 48 persons, a flow of 132 liters (35 gallons) of sewage per capita per day, and an average detention time of 1 day. The top of the tank was at the ground surface and the tank was accessible

through three 0.9-meter (3-foot) manholes.

Location: The site is located approximately 60 meters (200 feet) north of the 184-B Building.

**Related Sites/
Structures:** The site is associated with the 184-B Powerhouse.

Waste Type: Sanitary Sewage

**Waste
Description:** This unit received an unknown amount of sanitary sewage from 184-B Powerhouse.

Closure Info: Final: The 1607-B3 Septic Tank was demolished and buried in-situ between January and March 1988 as part of the 184-B Powerhouse decommissioning. Prior to demolition, the contents of the tank were sampled. No significant radioactivity was found above background and the Hanford Environmental Health Foundation (HEHF) Laboratory detected no reportable concentrations of heavy metals. The remaining contents were taken to 124-N-10 Sanitary Sewer System for disposal. Holes were punched into the bottom of the tank for drainage. The tank was then partially backfilled with rubble which was compacted in place to minimize subsidence. The area was then leveled to grade with at least 0.9 meters (3 feet) of clean fill. The reclassification is documented on form 2001-015.

Code: 1607-B4	Classification: Accepted
Names: 1607-B4; 1607-B4 Sanitary Sewer System; 1607-B4 Septic Tank; 1607-B4 Septic Tank System; 124-B-6	Reclassification: Closed Out (2/23/2001)
Type: Septic Tank	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/2000

Description: The site is a Closed Out septic system associated with the 151-B Substation. A sign stating Abandoned Septic Tank per WAC (246-272-18501) DynCorp Environmental is posted at the site. There are four yellow posts surrounding the structure. Within the posts are the old wooden cover, a pile of sand, and cobble.

The septic tank is concrete box that had a wooden lid covered with asphalt roofing material. The reinforced concrete septic tank is 1.8 meters (6 feet) long, 0.9 meters (3 feet) wide, and 2.5 meters (8 feet, 4 inches) deep (inner dimensions). The tank had a design capacity of 1325 liters (350 gallons) based on a user capacity of 10 persons, a flow of 132 liters (35 gallons) of sewage per capita per day, and an average detention time of 1 day. The tank walls are 20 centimeters (8 inches) thick with a 15 centimeter (6 inch) floor. The tile field was constructed of 10 centimeter (4 inch) pipes with a minimum length of 2.4 meter (8 feet) per capita. The laterals are open-jointed and spaced 2.4 meters (8 feet) apart.

Location: The tank is located near the northwest corner of the 151-B Substation. The tile field is located west of the tank.

**Process
Description:** This site received sanitary sewage from the 151-B Substation.

Waste Type: Sanitary Sewage

**Waste
Description:** This unit received sanitary sewage from 151-B Electrical Distribution Facility. The flow rate to the unit was estimated at less than 132 Liters (35 gallons) per day.

Closure Info: Final: Closure of the septic tank was completed in 2000. The tank contents were sampled and analyzed for radiological contaminants. The sample results were lower than detection limits.

The tank contents were pumped out and the tank was filled with clean fill material. A letter was sent to notify the Washington State Department of Health of the abandonment. The closure and abandonment are documented on Reclassification Form 2000-121.

Code: 1607-B6 **Classification:** Accepted

Names: 1607-B6; 1607-B6 Septic Tank System; 124-B-5; **Reclassification** None
1607-B5; 1607-B5 Sanitary Sewer System; 1607-B5 Septic Tank System

Type: Septic Tank **Start Date:** 1/1/1944

Status: Active **End Date:**

Description: The site currently appears as a small concrete box with a wooden lid. It is posted with a "Confined Space" warning sign. There is a yellow steel post at each of its four corners. The reinforced concrete septic tank is 8 ft 4 in (2.5 m) deep with a 25-person capacity (35 gal [130 L] per capita) and an average detention period of 24 hr. Its walls are 8 in (20 cm) thick and its floor is 6 in (15 cm) thick. The tile drain field is 4 in (10 cm) vitrified pipe, concrete pipe or drain tile with a minimum of 8 linear ft (2.4 m) per capita. The laterals are open-jointed and spaced 8 ft (2.4 m) apart. This system is active. This system includes the feed pipeline from the 183-B Filter House, the septic tank, and the drain field.

Location: This septic system is south of the 182-B Reservoir and Pumphouse.

Waste Type: Sanitary Sewage

Waste Description: This unit receives 35 gal/day (130 L/day) of sanitary sewage from the 182-B Pump Station and cooling water and leakage from pumps located in the 182-B facility. It also received sewage from 183-B Headhouse, which was decommissioned in 1987.

Code: 100-C-2 **Classification:** Not Accepted

Names: 100-C-2; Monitoring Station 1614-B-1; Possible **Reclassification** None
Building Foundation and Parking Lot

Type: Foundation **Start Date:**

Status: Inactive **End Date:**

Description: The site is a small square concrete slab and nearby gravel parking area. Northwest of the slab is a gravel road with a gravel area on the other side. A few small pieces of asbestos transite, a few dry-cell batteries, and some steel anchoring cable were noted around the site during a 9/13/94 field investigation by Kathryn J. Moss.

Location: The site is located near the southwest corner of the 100BC Area, adjacent to the southwest corner of the patrol road. The site is approximately 170 meters (558 feet) southwest of the 118-B-1 Burial Ground.

Code: 100-C-4 **Classification:** Not Accepted

Names: 100-C-4; Export Water Line Valve Pit **Reclassification** None

Type: Valve Pit **Start Date:**

Status: Active **End Date:**

Description: The site is a valve pit located along the export water line. The pit is marked with post and

chain. The 1.8 by 1.8 meter (6 by 6 foot) wooden cover is caving into the valve pit. The cover is posted with a "Danger: Cave-In Potential" sign.

Location: The site is located approximately 600 meters (2000 feet) east of the 105-C Reactor Building, between the 100-B Perimeter Road and Route 1 near mile post 9.

Related Sites/ Structures: The site is associated with the export water line from 182-B Reservoir to the 200 Areas.

Code: 100-C-5	Classification: Not Accepted
Names: 100-C-5; 100-C Clean Water Pipelines; 100-C Service Water Pipelines	Reclassification: None
Type: Product Piping	Start Date: 1/1/1952
Status: Inactive	End Date: 1/1/1969

Description: The site encompasses the clean water upstream pipelines for the 100-C Area, including underground pipelines used to transport raw, fire, export, and sanitary water from the river pump house, to the water treatment facilities and to 100-C Area facilities and fire hydrants. Lines within buildings, process and septic sewer pipes, pipes that carried water treated with sodium dichromate, and all lines that are downstream from the reactor building, i.e., those lines that carry cooling water from the reactor to the retention basin, trench, and/or the river are excluded.

Location: The location is described as underground lines running from the 181-C Pump house to the 183-C Water Treatment Facilities, and from there to other 100-C Area buildings, fire hydrants, and north to the 100-B Area, stopping at a line about half-way between the B and C areas, at about northing 144370 N.

Related Sites/ Structures: Related structures are the 181-C Pump house, 182-C Reservoir, the 183-C Basins and Clearwells, the 190-C Buildings, and the 105-C Reactor Building. Other pipeline sites in the 100-B/C Area include 100-C-9, the 100-C Area Process and Sanitary (Septic) Sewer Underground Pipelines; 100-C-6, the Effluent Pipelines; and 100-B-7, the 100-B Area Water Treatment Facilities Pipelines.

Process Description: Reactor cooling water was pumped from the Columbia River, settled and treated to remove minerals, and pumped to the reactor core at a rate of 1.93E+05 liters (51,000 gallons) to 2.69E+05 liters (71,000 gallons) per minute.

Waste Type: Water

Waste Description: Only uncontaminated piping remains.

Code: 100-C-8	Classification: Accepted
Names: 100-C-8; 105C Hydraulic Oil Release	Reclassification: Rejected (3/13/2002)
Type: Unplanned Release	Start Date: 1/1/1998
Status: Inactive	End Date: 1/1/1998

Description: The site is not marked or posted, no visible evidence of the spill remains because the concrete rubble that it was spilled on has been removed.

Location: The spill was located below the Rod Control Room of the 105-C Reactor Building, in a pile of concrete rubble approximately 7 feet deep. This rubble was contained within the basement

directly below the old (now demolished) Outer Rod Room.

Release Description: On Monday, August 24, 1998, at approximately 0900 hours, the CAT 375 excavator broke a main hydraulic line while dismantling a concrete pad at 105-C. The excavator was taken out of service for repair. The exact quantity was not known at the time of the hose failure and was believed to be below the DOE reportable threshold of 160 liters (42 gallons). A large area was sprayed due to the hydraulic system being under pressure. On Wednesday, August 26, 1998, the 105-C Task Lead was notified the excavator hydraulic line was repaired and the replacement fluid equaled 182 liters (48 gallons). It is assumed that the entire hydraulic system was full to capacity prior to the hose failure and that the amount released was the exact amount of product that was put back into the reservoir [182 liters (48 gallons)].

Waste Type: Oil

Waste Description: Unocal Unax AW46 Hydraulic Oil, unregulated product.

Code: 100-C-10 **Classification:** Not Accepted

Names: 100-C-10; Yellow Stained Soil Northwest of 183-C Headhouse **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The discovery of stained soil has been determined to be inclusive of 100-C-7:1 and classified as a Not Accepted waste site. An area of yellow stained was discovered in the layback of the western end of the 100-C-7:1 waste site while excavating in May 2011. Soil samples of the discolored soil were collected on May 19, 2011 and analyzed for metals and hexavalent chromium analysis. The sample having the highest result (197 mg/kg) of hexavalent chromium was J1JCD9.

Location: The stained soil waste site is located west of the intersection of Burnett Road and Belle Street. The stained area was visible approximately 65 meters (213 ft) west of the 183-C sedimentation basins, north of the Head House.

Related Sites/ Structures: This site is associated with 100-C-7:1.

Code: 124-C-4 **Classification:** Not Accepted

Names: 124-C-4; Sanitary Waste Site **Reclassification:** None

Type: Sanitary Sewer **Start Date:**

Status: Inactive **End Date:**

Description: This site was assigned by Bill Hayward based on the information from BHI D&D in the 1995 RARA Summary Report. D&D could not identify the site location nor could the BHI historian. The site is thought to be either 1607-B10 or 1607-B11 as they are the only remaining septic systems in the 100B Area that have a 124 alias assigned to them. If a determination can be made that it is one of above referenced septic systems, the 124-C-4 will be added to the site as an alias. This site reference (as a separate site) will then be removed from the database.

Code: 100-D-10 **Classification:** Not Accepted

Names: 100-D-10; Storm Drain Outfall; Undocumented Liquid Waste Site **Reclassification** None

Type: Depression/Pit (nonspecific) **Start Date:**

Status: Inactive **End Date:**

Description: The Technical Baseline Report (section 4.40) states that reportedly there was a small outfall structure upstream of the 1907-DR outfall. It was demolished at the same time as the 1907-DR outfall. The Technical Baseline Report states that the structure was similar in construction to the 1907-DR, only much smaller. It was used as a discharge outfall for the storm drain system of the 190-DR tank pit, which consisted of drains, sump, and pump to lift runoff to the outfall. The trench from the outfall structure to the waterline is apparent and appears to have a telephone cable buried in its bottom.

Location: The structure was located adjacent to the concrete block telephone building on the Columbia River bank and just south of the 100-D Area fence.

Related Sites/ Structures: The site was related to the 190-DR tank pit.

Waste Type: Stormwater Runoff

Waste Description: The unit reportedly received storm water run-off from the 190-DR tank pit.

Code: 100-D-11 **Classification:** Not Accepted

Names: 100-D-11; Temporary Garage and Gasoline Dispensing Station; Temporary Garage TC-21 **Reclassification** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:** 1/1/1950

Description: The temporary garage was destroyed by a fire on May 2, 1950. Since this site cannot be located, existence of an underground storage tank cannot be verified. No releases have been documented. The waste site has been it has been classified as Not Accepted.

Location: The site's location is not known. Temporary construction facilities were generally placed near the site of the project. The water treatment facilities are located south-southwest of the 105-DR Reactor.

Waste Type: Oil

Waste Description: This site has the potential for soil contamination from gasoline, oil, and engine coolant.

Code: 100-D-17 **Classification:** Accepted

Names: 100-D-17; Burn Pit; Undocumented Solid Waste Site **Reclassification** Rejected (8/27/1997)

Type: Burn Pit **Start Date:**

Status: Inactive **End Date:**

Description: The site is a burn pit that is visible in 1948 photos (#901 and #922). The site now appears as a large, vegetation covered field. There are no features that clearly identify the site.

Location: The site is located southeast of the 105-DR Reactor, outside of the 100D perimeter fence and north of Route 2 North.

Waste Type: Construction Debris

Waste Description: The site likely contains burned construction debris.

Code: 100-D-26 **Classification:** Not Accepted

Names: 100-D-26; Borrow Pit; Potential Burial Trenches **Reclassification:** None

Type: Depression/Pit (nonspecific) **Start Date:**

Status: Inactive **End Date:**

Description: The site is a borrow pit used as a source of clean fill. On July 10, 1997 a field investigation was performed by T. F. Johnson. The site appeared as a depression approximately 330 feet (100 meters) in diameter that was created from excavations with heavy equipment. Four distinct trenches were observed within the depression. All four trenches were covered with blown in tumbleweeds. A few tumbleweeds were removed for inspection and no waste or discolored soil was observed. An empty 208 liter (55 gallon) steel drum was located at the end of one trench and an empty 0.95 liter (1 quart) oil can was also observed near the site.

Location: The site is located approximately 250 meters (820 feet) east of the northeast corner of the patrol road that surrounds 100-D Area.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: An empty steel 55 gallon drum and an empty 1 quart oil can were observed at the site.

Code: 100-D-33 **Classification:** Accepted

Names: 100-D-33; Minor Construction Burial Ground #4 East Trench **Reclassification:** Rejected (3/20/2008)

Type: Burial Ground **Start Date:** 1/1/1954

Status: Inactive **End Date:**

Description: The site appeared as a vegetation-free, cobble-covered field. The trench was estimated to have been approximately 30 meters (100 feet) long by 15 meters (50 feet) wide. A Ground Penetrating Radar scan, done in 2004, did not identify any trench-like features.

Location: The site was located east/southeast of the 105-D Reactor, just south of the rail spur to the fuels transfer bay and east of 100-D-35. The site was outside the security fence for the 105-D Reactor Building.

Related Sites/Structures: Co-located with 100-D-35, Minor Construction Burial Ground #4 East Trench.

Process Description: The site was thought to have been used for disposal of low-level construction wastes from reactor modifications.

Waste Type: Construction Debris

Waste Description: The site received low-level construction wastes from the reactors. Potential contaminants include: Co-60, Ni-63.

Code: 100-D-34 **Classification:** Not Accepted
Names: 100-D-34; Exclusion Area; 100-D/DR Grounds **Reclassification** None
Surrounding Deactivated Areas
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The grounds within the 100-D/DR exclusion area that are not part of other waste sites.

Code: 100-D-35 **Classification:** Accepted
Names: 100-D-35; Minor Construction Burial Ground #4 **Reclassification** Rejected (3/20/2008)
East Trench
Type: Burial Ground **Start Date:** 1/1/1954
Status: Inactive **End Date:**

Description: During the March 31, 1999 site visit, no evidence of a trench was visible. The suspected site area appeared as a vegetation-free, cobble-covered field. A Ground Penetrating Radar scan, done in 2004, did not identify any trench like features.

Location: The site was thought to be located west of 100-D-33 east/southeast of the 105-D Reactor, just south of the rail spur to the fuels transfer bay and outside the security fence for the 105-D Reactor Building.

Related Sites/ Structures: Co-located with 100-D-33, Minor Construction Burial Ground #4 East Trench

Process Description: The expected purpose of the burial ground was to dispose of 105-D Reactor thimbles, rod guides, and miscellaneous waste during the Ball 3X conversion project.

Waste Type: Construction Debris

Waste Description: The site received low-level construction wastes from the reactors. Potential contaminants include: Co-60, Ni-63.

Code: 100-D-36 **Classification:** Not Accepted
Names: 100-D-36; 100-N-20; Monitoring Station 1614-D- **Reclassification** None
1; Undocumented Concrete Pad
Type: Foundation **Start Date:**
Status: Inactive **End Date:**

Description: The site is a 1.8 meter by 1.8 meter (6 foot by 6 foot) concrete pad with anchor bolts set in the surrounding edges.

Location: The site is located approximately 20 meters (65 feet) southwest of the southwest corner of the 100-D Area Patrol Road.

Code: 100-D-37 **Classification:** Not Accepted
Names: 100-D-37; 1614-D-3 Monitoring Station; **Reclassification** None

Undocumented Concrete Pad

Type: Foundation

Start Date:

Status: Inactive

End Date:

Description: The site is a 1.8 meter by 1.8 meter (6 foot by 6 foot) concrete pad with anchor bolts set in around the outer edges.

Location: The site is located northeast of the northeast corner of the Patrol Road in 100-D Area.

Code: 100-D-38

Classification: Not Accepted

Names: 100-D-38; Suspect Septic Tank

Reclassification: None

Type: Septic Tank

Start Date:

Status: Inactive

End Date:

Description: The site is a junction box and manhole associated with the 1607-D2 Septic System. The site is identifiable in the field by a steel lid on top of a circular brick base.

Location: The site is located north of 105-D, just northeast of the intersection where north-south road that passes west of the 105-D and 105-DR reactors crosses the east-west road that passes north of the 105-D reactor and between the 1700 buildings.

Code: 100-D-40

Classification: Accepted

Names: 100-D-40; Minor Construction Burial Ground #5 Hole

Reclassification: Rejected (3/20/2008)

Type: Burial Ground

Start Date:

Status: Inactive

End Date:

Description: The burial ground area appeared as a vegetation covered area. A 2004 Ground Penetrating Radar scan, did not identify any trench like features.

Location: The site was thought to be located 220 meters (720 feet) east of the 105-D Reactor Building and 23 meters (75 feet) south of the railroad tracks that service the 105-D Reactor Building.

Related Sites/ Structures: Co-located with 100-D-41 Minor Construction Burial Ground #5 Trench.

Waste Type: Equipment

Waste Description: The burial ground was dug to receive contaminated material and equipment from the 105-D Reactor Building. Potential contaminants included: Co-60, Ni-63.

Code: 100-D-41

Classification: Accepted

Names: 100-D-41; 118-18; 118-D-18; Minor Construction Burial Ground #5 Trench

Reclassification: Rejected (3/20/2008)

Type: Burial Ground

Start Date: 1/1/1956

Status: Inactive

End Date: 1/1/1956

Description: During a 1999 walkdown, no evidence of the burial ground was observed. The area appeared as

a vegetation covered field.

Location: The site was thought to be located 210 meters (700 feet) east of the 105-D Reactor Building and 23 meters (75 feet) south of railroad tracks that serviced the 105-D Reactor Building.

Related Sites/ Structures: Co-located with 100-D-40, Minor Construction Burial Ground #5 Hole.

Process Description: This burial ground has been described as receiving irradiated reactor parts, dummies, thimbles, rods, gun barrels, and other contaminated solid wastes. During the March 31, 1999 site visit, no evidence of the trench was visible. A Ground Penetrating Radar scan, done in 2004, did not identify any trench like features.

Waste Type: Construction Debris

Waste Description: The waste is miscellaneous construction related solid wastes from the 100-D Reactors. Potential contaminants include: Co-60, Ni-63.

Code: 100-D-53

Classification: Accepted

Names: 100-D-53; 117-DR Filter Building; 117-DR HEPA Filter Building

Reclassification: Interim Closed Out (3/4/2004)

Type: Process Unit/Plant

Start Date: 1/1/1960

Status: Inactive

End Date:

Description: The site has been remediated and Interim Closed Out for CERCLA. It has two entries in the WIDS database. Sitecode 122-DR-1:4 documented the RCRA component closure of this site.

The ventilation exhaust filter building housed blowers and particulate filters used to treat the ventilation exhausted from the 105-DR Reactor Building. Included in this site were the 117-DR Building, the intake ventilation duct from the 105-DR Reactor Building, and the exhaust ventilation duct to the 116-DR Reactor Exhaust Stack. The building and below-grade duct work were made of reinforced concrete 0.3 to 0.6 meters (1 to 2 feet) thick. Above grade ducts were constructed of 10 gauge black steel. The building was approximately 20.7 meters (68 feet) long, 11.9 meters (39 feet) wide, and 10.4 meters (34 feet) high with 2.4 meters (8 feet) above grade. A soil berm was built up around the building from grade level to the top of the structure.

Location: The site was located south of the 105-DR Reactor (118-DR-2), near the 116-DR Stack (132-DR-2).

Related Sites/ Structures: The site was associated with the 105-DR Reactor (118-DR-2), the 116-DR Stack (132-DR-2), the 119-DR Sample Building, 122-DR-1:4 and the 117-DR Seal Pit Crib (116-DR-8).

Process Description: Before filter buildings were used, unfiltered ventilation was exhausted directly from the reactor to the atmosphere. The reactor confinement system diverted the exhaust just before the stack and routed it to the filter building where it passed through a series of filters. The filtered exhaust was then routed back to the ventilation exhaust stack where it was discharged to the atmosphere. Sealwells within the filter building provided the ability to direct the exhaust into one or both of the filter cells. The building was divided into two large filter cells with a smaller operating area between them. The filter cells each could hold six filter frames (two wide and three deep). The filter frames were designed to hold twenty-four filters that were 0.6 meters (2 feet) square by 0.3 meters (1 foot) thick. There are spaces between the frames to allow access for filter maintenance. The operating area between the two cells was divided into two levels. The upper level, called the access gallery had ten doors that led from it. Four doors opened into each of the filter cells and the other two doors provided access to the intake and exhaust ducts. The operating gallery was located below the access gallery. A sump was located at each end of

the operating gallery to collect incidental drainage from above. A large open area extended the full length of the structure above the access gallery and the filter cells. It ranged in height between 2.5 and 2.4 meters (8.1 and 7.8 feet), due to the structure's sloping roof. The space provided access to the cement cover blocks that were positioned over each of the filter frames.

Waste Type: Equipment

Waste Description: The site contained radiologically contaminated surfaces and contamination from 105-DR Reactor ventilation exhaust. Hazardous residue from the Large Sodium Fire Facility is accounted for within that site (122-DR-1).

Closure Info: Interim: Note - The 105-DR reactor operated between 1950 and 1964 for plutonium production. In 1973, the exhaust system portions of the 105-DR reactor were reactivated and re-purposed to support the Large Sodium Fire Facility (LSFF). The LSFF (sitecode 122-DR-1) was a RCRA TSD. Most of the components of the reactor exhaust system have two entries in the WIDS database, one representing the CERCLA (radioactive) contaminants and the other representing the RCRA hazardous chemical contaminants.

The portions of the LSFF TSD that are included in this remedial activity are the 117-DR Exhaust Filter Building (100-D-53/122-DR-1:4), the underground exhaust tunnel (122-DR-1:2), the 119-DR Exhaust sample building (100-D-64), two dry wells (100-D-23 and 100-D-54) and the 116-DR Exhaust Stack (132-DR-2/122-DR-1:5) Four of the seven 122-DR-1 subsites (122-DR-1:1, 122-DR-1:3, 122-DR-1:6 and 122-DR-1:7) were closed out under the 105-DR Large Sodium Fire Facility RCRA Closure Plan (LSFF Closure Plan) are were not discussed in the CVP-2003-00018 Cleanup Verification Package.

The remedial objective for the structures was to remove each structure to a minimum of 0.9 meters (3 feet) below surface grade. In July 2003, remedial/removal action activities removed the 117-DR Exhaust Filter Building (100-D-53/122-DR-1:4), the downstream (post-filter) tunnel and the additional 0.9 meters (3 ft) of the 116-DR Reactor Exhaust Stack (132-DR-2/122-DR-1:5). The aboveground portion of the 132-DR stack had been demolished in 1999.

Large Sodium Fire Facility (LSFF) subsite 122-D-1:2 (underground tunnel between the 105-DR Building) and the 117-DR Exhaust Filter Building were entirely removed. The 315 and 316 exhaust plenums, (aka upper and lower exhaust tunnels) are also associated with the 122-D-1:2 subsite. The upper exhaust tunnel and approximately the top 0.9 meters (3 ft) of the lower exhaust tunnel were removed. The 119-DR Exhaust Stack Sampling Building and two stack sampling building dry wells (100-D-23 and 100-D-64) were also demolished and excavated as part of the remedial/removal action activities in July 2003.

At the completion of the remedial action, the total excavation was approximately 1,010 square meters (10,872 square feet) in area with an approximate depth of 5 meters (16.4 feet). Approximately 14,011 metric tons (15,412 tons) of material from the site were disposed of at the Environmental Restoration Disposal Facility.

Code: 100-D-55

Classification: Not Accepted

Names: 100-D-55; Gravel Pit #21; Pit 21

Reclassification: None

Type: Depression/Pit (nonspecific)

Start Date:

Status: Active

End Date:

Description: The site is a large excavation containing another waste site, 100-D-15, which is debris in the east end of the pit. The debris is marked with post and chain and labeled as a separate waste site. The remainder of the pit is available to use as clean fill material (Gravel Pit #21). There is no other waste material in the pit. The soil is sandy.

Location: The gravel pit is located south of the 100-D Area perimeter road.

**Related Sites/
Structures:** The pit is associated with the dumping area known as Site Code 100-D-15.

Waste Type: Demolition and Inert Waste

**Waste
Description:** There is an area of discarded debris located in the east end of this gravel pit. The debris is a separate waste site known as 100-D-15. In 1994, Kaiser Hanford removed sediments from the 182-D basins and deposited them inside this gravel pit, partially over top of the previously discarded debris. The sediment was determined to be "clean dredge soil" as defined in Washington Administrative Code 173-304-100. The total content of the discarded debris is unknown.

Code: 100-D-57

Classification: Not Accepted

Names: 100-D-57; Earth Crib Near 107-DR

Reclassification None

Type: Crib

Start Date: 1/1/1955

Status: Inactive

End Date:

Description: This site is a duplicate of 100-D-4, which has been excavated and closed out. Site 100-D-57 was initially identified from Drawing H-1-8630-DR, which shows an "Earth Crib" at an unrecognizable, but short, distance off the southeast side of the 116-DR-9 Retention Basin. Through examination of Ground Penetrating Radar results, other documents, and excavations of the 116-DR-9, 100-D-4, and 100-D-49 sites, which effectively removed all soil and subsurface structures in this area, it has been determined that this site, 100-D-57, was created in error.

Location: The crib is located 30 meters (100 feet) east of the southeast corner of the 116-DR-9 Retention Basin.

Code: 100-D-58

Classification: Accepted

Names: 100-D-58; 100-DR Area On-Site Sewage System for MO-980 & 4-Closet Restroom Facility; 100-DR OSS

Reclassification Closed Out (11/19/2012)

Type: Septic Tank

Start Date: 1/1/1998

Status: Inactive

End Date:

Description: The septic tank has been properly abandoned and Closed Out per Washington State Code requirements. The septic tank is surrounded by yellow steel posts and the drain field is surrounded with light duty chain and steel fence posts. The drainfield area is covered with tumbleweeds. The septic tank is a 5,680 liter (1,500 gallon), two compartment tank with a 5,680 liter (1500 gallon) pump chamber. The tank can be accessed through 0.765 meter (30 inch) diameter ribbed PVC risers that extend to grade and are covered by fiberglass lids that are bolted in place. The risers are centered over 0.609 meter (24 inch) diameter openings through the concrete lid.

Location: The site is located approximately 183 meters, (600 feet) north northwest of the 105-DR Reactor Building and 76 meters, (250 feet) southwest of the 105-D Reactor Building.

**Related Sites/
Structures:** The site received sanitary sewage from MO-980 and the restroom trailer. There are no radiation zones or known contamination areas in or near MO-980 or the restroom trailer.

Process Description: The septic tank separated the settleable solids and floating effluent scum from the clear liquid.

The effluent was passed from the septic tank to the pump chamber through a "Bio-Tube" effluent filter. The filter was located at the outlet end of the septic tank. The filter was accessed through one of the 0.203 meter (30 inch) PVC risers. It had a removable filter element which can be easily cleaned. A 0.203 meter (4 inch) diameter PVC pipe carried the effluent from the outlet of the filter to a 5,676 liter (1,500 gallon) pump chamber. The disposal area consisted of buried pressurized PVC pipe distribution system constructed in a gravel-lined trench. The outlet orifices of the system were sized at 4.76 millimeter (3/16 inch) diameter [1.5 millimeters (1/16 inch) larger than the effluent screen] to avoid orifice plugging. The disposal area provided the absorption area for disposal of the clear sewage liquid.

Waste Type: Sanitary Sewage

Waste Description:

Closure Info: Final (11/19/2012): The requirements for septic tank abandonment for the 100-D-58 sewage system fall under WAC 246-272A-0300. On August 2 and 6, 2012, approximately 1.3 meters (4 feet) of soil was removed to expose the septic tank. The lid was removed and crushed. The tank was filled with sand and gravel. The abandoned tank was backfilled to grade. The electronic components, pump, and float switches associated with the septic system were removed and either disposed or recycled. The drain-field inspection ports, consisting of polyvinyl chloride (PVC) pipes placed vertically in the drainfield, were also removed and disposed. All below-grade PVC piping associated with the sewage system was abandoned in place. The site has been abandoned in accordance with WAC 246-272A-0300 and is Closed Out.

Code: 100-D-59 **Classification:** Accepted

Names: 100-D-59; French Drain at the 183-D Acid Transfer Station **Reclassification:** Rejected (1/30/2003)

Type: French Drain **Start Date:**

Status: Inactive **End Date:**

Description: The site is an upright vitrified clay pipe adjacent to the acid transfer structure at the railroad tracks next to the 183-D Building. Pipes used to transfer the acids from the rail cars are still on the structure, but the pipe sending overflow to the french drain has been disconnected (part of the pipe has been removed). The french drain is about 25 centimeters (10 inches) high, and 45 centimeters (18 inches) in diameter, with a steel cover and a 2.5-centimeter (1-inch) galvanized steel pipe rising up through the steel cover.

Location: The drain is on the east side of the railroad tracks that lead up the west side of the 183-D Building. It is between the transfer station and the underground pipe channel.

Related Sites/Structures: This drain is associated with the acid transfer station at the 183-D Building.

Process Description: Sulfuric acid was used to adjust the pH of the water in the 183-D Water Treatment Facility. It arrived in railcars and was transported to the facility via underground pipelines. The french drain received overflow from the acid transfer operations.

Waste Type: Chemical Release

Waste Description: The waste disposed to the french drain was overflow sulfuric acid from railroad car transfer operations. Any waste acid would be neutralized in the alkaline Hanford soils.

Code: 100-D-68 **Classification:** Accepted
Names: 100-D-68; 190-DR Process Water Pump House **Reclassification:** Interim No Action (7/25/2005)
Type: Process Unit/Plant **Start Date:**
Status: Inactive **End Date:**

Description: The waste site has been evaluated and determined to require No Action. The pump house has been demolished to 1 meter (3 feet) below-grade and backfilled. Before demolition the building included a basement, pipe gallery operating floor, suction tunnel and hot well bay, process tunnels, and two valve houses.

Location: The facility was located due south of the 151-D Substation, east of the 183-DR Clearwells and southeast of the 105-DR Reactor.

Related Sites/ Structures: The associated structures include the 126-DR-1 (183-DR Clearwell Tank Pit), the 118-DR-2 (105-DR Reactor), 100-D-27, (151-D Substation), and the 100-D-28 septic system, piping and tile fields.

Process Description: The Process Water Pump House provided high volume treated water to 105-DR Reactor for cooling. The facility contained eight electric primary water pumps that pumped treated water from the clearwell tanks to the reactor. The discharge water pipelines were composed of four sets of lines with each line 30.5 cm (12 in) in diameter. These pipelines combined into four 30.5 cm (24 in) discharge pipelines. Two sets of dual 30.5 cm (24 in) pipelines ran from the 190-DR facility to two valve pits. From each valve pit, the dual 30.5 cm (24 in) pipelines routed the process water to the 105-DR Reactor.

Waste Type: Construction Debris

Waste Description: Prior to demolition, above-grade wastes included polychlorinated biphenyls (PCBs), asbestos (roofing, siding, pipe trays, and thermal piping insulation), mercury (installed in instrumentation and control systems), lead (lead-based paint and lead washers), and oils/greases. Since the above-grade structure was completely removed during demolition, the only remaining waste was the below-grade structure. The waste in the basement included water, sludge and potentially contaminated concrete.

Closure Info: Interim: Prior to demolition, all friable asbestos was removed, including all asbestos containing material and all potential asbestos containing material from ventilation fan housings, pipes, and loose materials that had fallen to the ground. Additionally, biological hazards, i.e., bird droppings, small dead birds, and eggshells were removed.

In the spring of 2005, the above-grade portion of the facility was demolished and the below-grade portion of the facility was demolished to 1 meter (3 feet) below-grade. The debris went to ERDF. The remainder of the concrete facility was left in place. The two valve houses were also demolished.

Approximately, 20 to 25 centimeters (8 to 10 inches) of standing water that had accumulated from runoff of storm water was present in the north and south annex basement areas (B and C Bays). B Bay (a.k.a., main basement sump) contained sludge that had accumulated. The water was removed prior to below-grade demolition. In order to leave the basement in place as clean concrete, sampling results had to show that contaminants in the concrete were below the applicable remedial action goals as defined in the Remedial Design Report/Remedial Action Work Plan for the 100 Area (DOE/RL-96-17).

The water tunnels were left in place and are currently being used as bat habitat. All of the piping was removed and recycled.

Code: 100-D-79 **Classification:** Accepted
Names: 100-D-79; SCA Area 1; SCA Area 2; 100D **Reclassification** Rejected (9/15/2010)
 Posted Soil Contamination Areas
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: This site consists of two posted radiological soil contamination areas (SCA). Area 1 is an SCA that was found during the 2006 Orphan Site Evaluation (OSE) field investigation. The SCA is posted and is in an area of previously disturbed soils. Area 2 is also an SCA that was identified during the 100-D Orphan Site field investigation in 2006.

Location: There are two posted soil contamination areas located north of 105-D. Area 1 is near the north perimeter road and southeast of the 1904-DR outfall. A hand held Global Positioning unit found the center of Area 1 coordinates to be E573663.40, N152389.29. Area 2 is located on the north side of the 126-D-1 (188-D) ash pile. A hand held Global Positioning unit found the center of Area 2 to be at coordinates E573470.92, N152198.90.

Process Description: Construction drawing M-1600-D, Sheet 8 indicates that Area 1 was located in was used as a spoil pile area in 1947. No other information is available. No information was available for Area 2.

Code: 100-D-89 **Classification:** Not Accepted
Names: 100-D-89; Power Pole and Junction Box Debris **Reclassification** None
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: This site consists of two surface debris areas containing abandoned electrical components.

Location: This site is located 83 meters (272 feet) north of the 108-D Chemical Facility.

Related Sites/ Structures: The 100-D-31 Process Sewer runs below this location.

Process Description: The electrical service box is sitting on a 1.5 meter (5 foot) tall frame and is fed through the bottom with ridged conduit. Attached to the frame is a cord hanger with several feet of electrical cord. The electrical cord has been disconnected from the strain relief. It was most likely used as a power source for engine block warming of heavy equipment. It is not known if the utility pole serviced the electrical box.

Waste Type: Equipment

Waste Description: No contaminants of potential concern were noted. This electrical box was used as a junction box and should not have contained PCB's.

Code: 100-D-91 **Classification:** Not Accepted
Names: 100-D-91; 100-D/DR Electrical Components **Reclassification** None
 Debris
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The site consists of a flat gravel area where pallets of electrical components once were staged.

Location: This site is located 12 m (39 ft) northeast of the 1713-D Store House.

Related Sites/ Structures: The closest structure was the 1713-D Store House.

Waste Type: Equipment

Waste Description: There are no contaminants of concern.

Code: 100-D-92

Classification: Accepted

Names: 100-D-92; Second Potential UST Near Dichromate Station

Reclassification: Rejected (2/11/2010)

Type: Storage Tank

Start Date:

Status: Inactive

End Date:

Description: This waste site consists of an underground concrete utility encasement for freshwater pipelines and the underlying soil located below a rail line. The site was originally reported, in a geophysical investigation, as a potential underground storage tank (UST). A detailed spatial analysis was conducted and determined that the feature was a known piping encasement located below the railroad tracks.

Location: This structure is co-located with 100-D-93 and associated with the 183-D Water Treatment facilities, the 100-D-12 Sodium Dichromate Transfer Station (pump station), 100-D-63, 100-D/DR Service Water Pipelines, 100-D/DR Clean Water Pipelines, and 100-D-56, 100-D Area Sodium Dichromate Underground Supply Lines (see subsites).

Related Sites/ Structures: This structure is co-located with 100-D-93 and associated with the 183-D Water Treatment facilities, the 100-D-12 Sodium Dichromate Transfer Station (pump station), 100-D-63, 100-D/DR Service Water Pipelines, 100-D/DR Clean Water Pipelines, and 100-D-56, 100-D Area Sodium Dichromate Underground Supply Lines (see subsites).

Process Description: The encasement protected utilities buried beneath rail road lines and is located approximately 0.91meter (3 feet) below grade. A 7.6 centimeter (3 inch) sodium dichromate pipeline and a 40.64 centimeter (16 inch) freshwater pipeline was observed inside the encasement.

Waste Type: Process Effluent

Waste Description: The encasement contains a portion of the 100-D-56 pipeline. WIDS 100-D-56 states "Historical review, geophysical surveys and a site visit in 2005 concluded that the site appeared to contain hazardous constituents (i.e. hexavalent chromium) at levels in exceedance of remedial action goals" Potential Contaminants of Concern: As stated in the Site Comment, the encasement location consists of a portion of the 100-D-56 pipeline. WIDS 100-D-56 states "Historical review, geophysical surveys and a site visit in 2005 concluded that the site appeared to contain hazardous constituents (i.e. hexavalent chromium) at levels in exceedance of remedial action goals".

Code: 100-D-93

Classification: Accepted

Names: 100-D-93; Potential UST Near Dichromate Station

Reclassification: Rejected (5/20/2010)

Type: Storage Tank

Start Date:

Status: Inactive

End Date:

Description: This site consists of an underground concrete utility encasement for freshwater pipelines and the underlying soil located below a rail line. The site was originally reported, during a geophysical investigation, as a potential underground storage tank (UST). A detailed spatial analysis was conducted and determined that the feature was a known piping encasement located below the railroad tracks.

Location: This site is located 10 meters (32 feet) east of the 100-D-12 Sodium Dichromate Transfer Station and 73 meters (239 feet) southeast of the 183-D building. It is approximately 1.54 m (5 ft) below grade.

Related Sites/ Structures: This structure is co-located with 100-D-92 and associated with the 183-D Water Treatment facilities, the 100-D-12 Sodium Dichromate Transfer Station (pump station), 100-D-63, 100-D/DR Service Water Pipelines, 100-D/DR Clean Water Pipelines, and 100-D-56, 100-D Area Sodium Dichromate Underground Supply Lines (see subsites).

Process Description: The encasement protected utilities buried beneath rail road lines and is located approximately 0.91 meter (3 feet) below grade. A 7.6 centimeter (3 inch) sodium dichromate pipeline and a 40.64 centimeter (16 inch) freshwater pipeline was observed inside the encasement.

Waste Type: Process Effluent

Waste Description: The encasement contains a portion of the 100-D-56 pipeline. WIDS 100-D-56 states "Historical review, geophysical surveys and a site visit in 2005 concluded that the site appeared to contain hazardous constituents (i.e. hexavalent chromium) at levels in exceedance of remedial action goals."

Code: 100-D-95 **Classification:** Accepted

Names: 100-D-95; 100-D/DR Unnumbered Septic Tanks and Tile Field **Reclassification:** Rejected (11/10/2010)

Type: Septic Tank **Start Date:**

Status: Inactive **End Date:**

Description: The site was suspected to consist of two septic tanks and a tile field. Gravel and rabbit brush were observed on the surface of the site. Based on information gathered during the geophysical investigation, and historical review it was determined that a septic tank and drain field do not exist at the 100-D-95 site. The site was reclassified to Rejected on form 2009-04.

Location: This site is located approximately 150 meters (492 feet) northwest of the 182-D Reservoir. The coordinates are the centroid of the geophysics performed.

Related Sites/ Structures: This septic system may have serviced the 1735-D Division Engineers Office, Training Headquarters, Miscellaneous Storage Facility and other temporary construction facilities.

Process Description: During construction of the Hanford Engineer Works, temporary sewer lines and septic tanks were installed for the disposal of sanitary sewage. The "Plot Plan of Temporary Construction Facilities 100-D Area, August 1944" indicated that a septic tank and tile field were proposed at this location to service several temporary buildings.

Waste Type: Sanitary Sewage

Waste Description: Transfer of non-radioactive liquid sanitary sewage waste.

Code: 120-D-1 **Classification:** Accepted

Names: 120-D-1; 100-D Ponds **Reclassification:** Closed Out (8/27/1999)

Type: Pond **Start Date:** 1/1/1977
Status: Inactive **End Date:** 5/27/1994

Description: The waste site was originally a single excavation created in 1977 in the Ash Disposal Basin to receive non-hazardous 183-D sand filter backwash water. It modified in 1979 to form a two-compartment pond, one overflowing to the other. The north pond was a percolation pond and the south pond was a settling pond. From 1979 through 1994, it received corrosive dangerous waste from the regeneration of three ion exchange columns located in the 185-D/189-D building. It was designated as a RCRA TSD unit.

On August 27, 1999, a letter was issued from the State of Washington Department of Ecology that declared the Treatment Storage and Disposal (TSD), RCRA Part A permit portion of this unit to be closed.

Location: This site is located within the 100-D Ash Disposal Basin (126-D-1).

Process Description: The waste site was originally a single excavation created in 1977 in the Ash Disposal Basin to receive non-hazardous 183-D sand filter backwash water. The 100-D Ponds received corrosive waste from the regeneration of ion exchange columns located in 185-D and 189-D. Successive discharge of acidic waste and caustic waste to the ponds served to neutralize the waste in the ponds. Approximately 45,000 gallons (170,000 liters) per day was treated in the ponds. A fraction of this amount was corrosive dangerous waste. It received the last discharge of dangerous waste in January 1986. It last received a discharge of non-regulated process water in May 1994.

Waste Type: Process Effluent

Waste Description: This site received nonhazardous 183-D Sandfilter backwash, small quantities of filtered, chlorinated water from hydraulic test loops, and fuel discharge trampoline tests in 1977. The estimated flow rate was 1.7E+05 liters/day (45,000 gallons/day). After 1979, it received corrosive demineralizer recharge effluent from two sources was released at intervals of once every 2 to 3 years for one regenerate source and once every 6 years for the other. Sampling indicates the potential for mercury and polychlorinated biphenyl (PCB) contamination.

Closure Info: Final: This was a RCRA TSD unit. On August 27, 1999, a letter was issued from the State of Washington Department of Ecology that declared the Treatment Storage and Disposal (TSD), RCRA Part A permit portion of this unit to be closed.

Code: 126-D-1 **Classification:** Accepted
Names: 126-D-1; 184-D Powerhouse Ash Pit; 188-D Ash Disposal Area; 100-D Ash Disposal Basin **Reclassification** Rejected (6/25/1998)
Type: Coal Ash Pit **Start Date:** 1/1/1950
Status: Inactive **End Date:** 1/1/1960

Description: The 126-D-1 site is a large ash disposal area. The site was originally a large excavated basin approximately 60 meters (200 feet) long, 60 meters (200 feet) wide, and 3 meters (10 feet) deep. The extent of the original basin obscured by ash piles.

Location: The site is located north of the 184-D Powerhouse.

Process Description: Coal ash from the 184-D Powerhouse was mixed with raw river water and sluiced in slurry form to the ash pit via a 20 centimeter (8 inch) ashcolite pipe.

Waste Type: Ash

Waste Description: This site received an unknown amount of coal ash that was sluiced to pits with raw river water from the 184-D Powerhouse. The ash has been determined by testing in accordance with WAC 173-303 to be nonextraction process (EP) toxic.

Code: 126-D-3 **Classification:** Accepted
Names: 126-D-3; 184-D Salt Dissolving Pit and Brine Pump House; D Area Brine and Salt Dilution Pits **Reclassification:** Rejected (10/2/1997)
Type: Sump **Start Date:**
Status: Inactive **End Date:**

Description: The salt dissolving pits and brine pump pit were part of a single below-grade concrete structure that provided brine for the 184-D Powerhouse. The structure has been demolished and buried in situ. No evidence of the site remains at the surface. The two salt dissolving pits each had inner dimensions of 4.3 meters (14 feet) long by 2.4 meters (8 feet) wide by 2.8 meters (9.25 feet) tall. They had a design high water line 2.4 meters (7.75 feet) from the pit bottom. An overflow slot connecting the two dissolving pits was located 0.3 meters (1 foot) above the high water line. The bottom of each pit was filled with a 12.7 centimeter (5 inch layer) of 1.3 to 2.6 centimeter (1/2 to 1 inch) gravel topped by a 17.8 centimeter (7 inch) layer of 0.3 to 0.6 centimeter (1/8 to 1/4 inch) gravel. The dissolving pits each had a 2.4 meter (8 foot) by 0.9 meter (3 feet) opening at the top for receiving salt. Each pit had a capacity of 23,600 kilograms (52,000 pounds) of salt. The brine pump pit is located adjacent to the two salt dissolving pits. The pit was 3.3 meters (10.67 feet) long by 2.2 meters (7.33 feet) wide by 2.1 meters (7 feet) deep. It held two pumps and associated piping (all brass) for the brine system. The floor of the pump pit sloped toward a 46 by 46 by 46 centimeter (18 by 18 by 18 inch) sump in a corner.

Location: The site is located north of 184-D and just south of the railroad tracks.

Related Sites/ Structures: The site is associated with the 184-D Power House.

Process Description: The brine was used to regenerate the zeolite ion exchange demineralizers that were part of the powerhouse water treatment system.

Waste Type: Demolition and Inert Waste

Waste Description: The structure was demolished and buried in situ.

Code: 132-D-4 **Classification:** Accepted
Names: 132-D-4; 105-D Reactor Exhaust Stack; 116-D Reactor Exhaust Stack **Reclassification:** Interim Closed Out (7/27/2005)
Type: Stack **Start Date:** 1/1/1944
Status: Inactive **End Date:** 1/1/1967

Description: The site has been remediated and Interim Closed Out. It was the reactor exhaust stack. The stack was demolished in 1999 and the rubble taken to ERDF. It was evaluated for reclassification in 2005.

Location: The stack was located south of the 105-D Reactor Building.

Process Description: The unit was a monolithic structure constructed of reinforced concrete. The maximum wall thickness was 0.46 meters (1.5 feet) at the base. It rested on a double octagon-shaped base that

extended 5.3 meters (17.5 feet) below grade. An opening at the base provided access to its interior portion. This opening was fitted with a steel door. The outside rungs had been removed to about 3 meters (10 feet) above grade. Originally exhaust air flowed directly from the 105-D Building to the exhaust stack. Following completion of the confinement project in 1960, the exhaust air was diverted to the 117-D Filter Building, via underground ducts, prior to release through the stack.

Waste Type: Demolition and Inert Waste

Waste Description: This unit was used to exhaust confinement air that originated from the work areas in the 105-D Reactor Building. The interior of the stack contains an unknown quantity of low-level radioactive materials.

Closure Info: Interim: In 1984 when the reactor shut down, the Fuel Storage Basin (FSB) water level was lowered and the basin was cleaned out. Ruptured fuel elements had caused the shielding water to become highly contaminated. The remaining water was processed and released to 116-D-10 pond. Then an asphalt emulsion was applied to the floors and walls of the basin to fix the loose contamination to the basin structure. The hardware remaining in the basin (perfs, buckets, and sludge) were packaged and disposed of as low-level radioactive waste in the 200 Area burial grounds. The 132-D-4 stack was demolished and remediated to a depth of 0.9 meters (3 ft) below grade in 1999.

Removal and disposal activities at the 105-D site began in January 2000. For remediation purposes, the reactor area was divided into several Demolition Zones, the reactor core and the remaining portion of 132-D stack foundation. These areas were surveyed, and contamination was removed in preparation for clean demolition. With the exception of the Fuel Storage Basin walls and floor below 4.6 meters (15 feet), all structures in this zone were removed due to surface contamination being present. Sampling of underlying soils was not required because structures in this zone were not subjected to standing contaminated water and there was no mechanism for residual surface contamination to penetrate into the concrete and the underlying soil. The above and below grade structures were demolished. The demolition debris sent to ERDF. A section of 100-D-48:4 effluent pipeline remains buried under what was room 210. This section of pipeline will be considered separately from Demolition Zone 1 and deferred to the Remedial Action Project.

All known flammable and hazardous material was removed inside and outside of the Safe Storage Enclosure (SSE), with the exception of non-removable lead, generally in the form of lead-based paint inside the SSE. Concentrations of lead in the lead-based paint were determined to be below regulatory limits. After the hazardous materials were removed, the above and below grade structures at the 105-D site were ready for demolition. The above-grade structures were demolished, the overburden around the foundations was excavated, and the below-grade structures were demolished. During the demolition process, the resulting debris was loaded out and shipped to ERDF for disposal. The 105-D site D&D activities included complete removal of above-grade structures outside of the 105-D Reactor core shield walls. A majority of the below-grade structures outside of the 105-D Reactor core shield walls were completely demolished. A portion of the south wall of the valve pit area (demolished to 0.9 meters [3 ft] below grade) and the entire Fuel Storage Basin floor and a portion of the walls (demolished to 4.6 meters [15 ft] below grade) were left in place based on deep zone cleanup criteria. The overburden piles produced during excavation were found to be contaminated. The overburden was deemed unsuitable for use as backfill of the site and was disposed in ERDF. The site was backfilled with clean soil/aggregate, using material from Borrow Pit 21 and graded to match the surrounding terrain. The 105-D D&D activities generated approximately 1,585 bulk containers of low-level contaminated material that were shipped to ERDF, accounting for approximately 21,613 metric tons (23,824 tons).

It was determined in the Sampling and Analysis Plan for Interim Closure of the 105-D and 105-

H Reactor Below-Grade Structures and Underlying Soils that the 105-D FSB would not be cored to sample the underlying soils because this Fuel Storage Basin was not known to have leaked (the water level variations were consistent with evaporation). Coring would have been very difficult and potentially unsafe. The soils beneath the 100-C and 105-DR FSBs were found to be clean. The 100-D Reactor Site Technical Baseline Report suggests that all of the FSBs had leaked. However, this statement is not supported by the process history of the 105-D FSB. Sampling of the underlying soils at the 105-C and 105-DR FSBs showed that they had not leaked. The FSB concrete floors from all of the previously decommissioned reactors were found to have various types of contamination that penetrated only a maximum of a few millimeters into the concrete. Sampling showed the contamination had not penetrated through the 0.3 to 0.6 meters (1 to 2 feet) of concrete in the FSB floors.

The north decontamination pad, a section of 100-D-48:4 effluent pipeline, and the FSB side-slope soils remained to be addressed, having been deferred to the Remedial Action Project.

Code:	1607-D3	Classification:	Accepted
Names:	1607-D3; 1607-D3 Sanitary Sewer System; 1607-D3 Septic Tank; 1607-D3 Septic Tank and Associated Drain Field	Reclassification	Closed Out (2/23/2001)
Type:	Septic Tank	Start Date:	1/1/1944
Status:	Inactive	End Date:	1/1/2000
Description:	<p>The site is an inactive, abandoned septic system associated with the 151-D Substation. A sign stating "Abandoned Septic Tank per WAC 246-272-1850 DynCorp Environmental" is posted at the site. The tank has been abandoned per WAC 246-272-18501 and as of August 2000 is indistinguishable in a dirt and cobble field.</p> <p>The reinforced concrete tank is 1.8 meters (6 feet) long, 0.9 meters (3 feet wide), and 3 meters (9 feet 10 inches) deep (inner dimensions). The tank had a design capacity of 1325 liters (350 gallons) based on a user capacity of 10 persons, a flow of 132 liters (35 gallons) of sewage per capita per day, and an average detention time of 1 day. The walls are 20 centimeters (8 inches) thick. The floor is 15 centimeters (6 inches) thick. The tile field was constructed of 10 centimeter (4 inch) vitrified or concrete pipe, or drain tile with a minimum of 2.4 meter (8 foot) per capita. The laterals are open jointed and spaced 2.4 meters (8 feet) apart. Prior to decommissioning, the septic tank was surrounded by light posts and chain.</p>		
Location:	The septic tank and drain field are located east of the 151-D Electrical Substation.		
Process Description:	The site serviced the 151-D Electrical Substation.		
Waste Type:	Sanitary Sewage		
Waste Description:	This unit received sanitary waste from the 151-D Electrical Distribution Substation. The flow rate to this unit was estimated at 3,970 Liters (1,050 gallons) per day.		
Closure Info:	Final: The tank has been abandoned per WAC 246-272-18501. The septage was removed from the tank sometime in the past. In July 2000, the lid was removed from the tank and the void space in the tank was filled with soil. A radiological survey was done on the empty tank and excavated soil. The reclassification is documented on form 2000-122.		

Code:	122-DR-1	Classification:	Accepted
Names:	122-DR-1; LSFF; 100-D-51; 105-DR Large	Reclassification	Closed Out (7/1/2004)

Sodium Fire Facility; 105-DR Sodium Fire Facility

Type: Laboratory **Start Date:** 1/1/1972
Status: Inactive **End Date:** 1/1/1986

Description: The Large Sodium Fire Facility RCRA TSD (T-1.1) has been Closed Out. The facility RCRA closure plan divided the facility into seven areas for sampling and closure purposes. The seven areas became subsites of the 122-DR-1 WIDS site. Some components of the facility also required CERCLA remediation. These components were addressed in a Cleanup Verification Package (CVP-2003-00018). The TSD was Closed Out under RCRA on 7/1/2004, after the CERCLA remediation was completed. A Certification of Closure Acceptance Letter, signed by Ecology, was issued to document completion of the RCRA TSD closure.

Four of the seven 122-DR-1 subsites (122-DR-1:1, 122-DR-1:3, 122-DR-1:6 and 122-DR-1:7) were Closed Out under the 105-DR Large Sodium Fire Facility RCRA Closure Plan (LSFF Closure Plan) (DOE-RL 1995). The remaining components are discussed in the CVP-2003-00018 Cleanup Verification Package.

Location: The 105-DR Large Sodium Fire Facility was located in the supply and exhaust fan wing of the 105-DR Reactor Building.

Process Description: The Large Sodium Fire Facility (LSFF) was used to study the fire and safety aspects associated with sodium and other alkali metal fires for application to liquid metal reactors. The LSFF occupied the former supply/exhaust fan room of the 106-DR Reactor Building and used the 105-DR Reactor Building exhaust system, which includes the 117-DR Filter Building, exhaust tunnels, exhaust stack, exhaust stack sampling building, and exhaust stack sampling building drywell. The 105-DR Reactor Building exhaust system began operations in 1960, and ceased operations in 1964 in conjunction with the 105-DR Reactor. The exhaust system was reactivated and re-purposed in 1972 to support the LSFF and continued operation until 1986.

The laboratory tests conducted at the 105-DR Large Sodium Fire Facility (LSFF) can be grouped into the following general types by test purposes: (1) formation of alkali metal aerosols in air, steam, nitrogen, or carbon dioxide atmospheres for the purpose of determining aerosol properties and release ratios, using both pool and spray fires; (2) reaction of an alkali metal with concrete and insulation to study corrosion rates and to determine the reaction products formed; (3) generation of aerosols to be used for testing and measurement of air-cleaning filter and scrubber performance and for evaluating hydrogen ignition characteristics; (4) production of fire and smoke to test alkali metal fire extinguishing methods and equipment, to test protective equipment, and for training in equipment use; (5) testing of purchased lithium-lead alloy reaction rates and aerosol formation in various atmospheres; (6) development tests using cesium and zinc metal to demonstrate aerosol generation techniques; and (7) thermal treatment of sodium residue (sodium waste) generated in other facilities.

Waste Type: Chemicals

Waste Description: Wastes consisted of sodium, lithium, sodium-potassium alloy, lithium-lead alloy, and their oxidation products.

This Site has the Following SubSites:

Code: 122-DR-1:1

Names: 122-DR-1:1; Office Area; Storage; Testing; 100-D-51; 105-DR 90-Day Waste Accumulation Area; 122-DR-1 Area 1

Code: 122-DR-1:2

Names: 122-DR-1:2; Exhaust Tunnels; 122-DR-1 Area 2

Code: 122-DR-1:3
Names: 122-DR-1:3; Gravel Scrubber; 122-DR-1 Area 3

Code: 122-DR-1:4
Names: 122-DR-1:4; 117-DR HEPA Filter Building; 122-DR-1 Area 4

Code: 122-DR-1:5
Names: 122-DR-1:5; 116DR Reactor Exhaust Stack; 122-DR-1 Area 5

Code: 122-DR-1:6
Names: 122-DR-1:6; 116-DR-8 Crib (RCRA Action); 122-DR-1 Area 6

Code: 122-DR-1:7
Names: 122-DR-1:7; Outdoor Storage Area; 122-DR-1 Area 7

Code: 122-DR-1:1 **Classification:** Accepted

Names: 122-DR-1:1; Office Area; Storage; Testing; 100-D-51; 105-DR 90-Day Waste Accumulation Area; 122-DR-1 Area 1 **Reclassification** Closed Out (10/1/1996)

Type: Laboratory **Start Date:**

Status: Inactive **End Date:**

Description: The RCRA TSD component was clean closed. The facility RCRA closure plan divided the facility into seven areas for sampling and closure purposes. The seven areas became subsites of the 122-DR-1 WIDS site.

Area 1 consists of the exhaust fan room, small fire room, large fire room, sodium handling room, and an office area.

The exhaust fan room is 6.2 meters (20.5 feet) wide, 8.2 meters (27 feet) long, and 6.4 meters (21 feet) high. In this room, waste alkali metals from various sources, including residuals from tests, failed equipment, and drum heels, were reacted at atmospheric pressure. The burn pans and equipment were cleaned periodically using water and the rinsate was collected in a sump. The wash water was pumped from the sump to a seal pit where it was neutralized prior to discharge.

The small fire room is 6.2 meters (20.5 feet) wide, 8.2 meters (27 feet) long, and 6.4 meters (21 feet) high. It contains one steel cylindrical pressure vessel with a dished top. The vessel has a volume of approximately 14 cubic meters (500 cubic feet). When in use, the vessel could be purged with nitrogen or argon to maintain a controlled atmosphere. This vessel was the only one used to burn lithium-lead alloy waste.

The large fire room is 6.2 meters (20.5 feet) wide, 8.2 meters (27 feet) long, and 6.4 meters (21 feet) high. It contains the Large Test Cell which is a steel cubicle 110 cubic meters (3,700 cubic feet) in volume. The cell could be purged with nitrogen or argon to maintain a controlled atmosphere.

The sodium handling room contained drum melters and a 3,400 liter (900 gallon) type-304 stainless-steel sodium batch tank which provided sodium to the Large Test Cell. The tank was resupplied from sodium drums that were heated to liquefy the sodium, which was then discharged into the tank with inert gas.

The office area provided space for office work and storage of nondangerous materials.

During cleanup activities equipment was removed from the rooms, decontaminated and stockpiled for either recycling or reuse. The interiors of the Large Test Cell and the pressure vessel were decontaminated with a high pressure water blast to remove lead and carbonate contamination. The rooms were washed down using a pressure washer and a mildly acidic solution to remove visible residue. All penetrations into the reactor exhaust tunnels were sealed to isolate the area and prevent recontamination.

A 90-day waste accumulation area was set up at the north end of the office area for use during clean up activities. The accumulation area was enclosed within a wire cage. When the waste was removed, the unit was closed.

Location: The 105-DR Large Sodium Fire Facility is located in the supply and exhaust fan wing of the 105-DR Reactor Building.

The SubSite is Part Of:

Code: 122-DR-1

Names: 122-DR-1; LSFF; 100-D-51; 105-DR Large Sodium Fire Facility; 105-DR Sodium Fire Facility

Code: 122-DR-1:2

Classification: Accepted

Names: 122-DR-1:2; Exhaust Tunnels; 122-DR-1 Area 2

Reclassification: Closed Out (7/1/2004)

Type: Laboratory

Start Date:

Status: Inactive

End Date:

Description: This subsite has been remediated and Interim Closed Out for CERCLA. The RCRA LSFF Closure Plan deferred the remaining three LSFF TSD subsites (122-DR-1:2, 122-DR-1:4, and 122-DR-1:5) to the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 (CERCLA) process. The facility RCRA closure plan divided the facility into seven areas for sampling and closure purposes. The seven areas became subsites of the 122-DR-1 WIDS site. Prior to RCRA closure, subsites 122-DR-1:2, 122-DR-2:4, and 122-DR-1:5 had been reclassified as Interim Closed Out under CERCLA. The reclassification status for these subsites was changed to Closed Out to be consistent with the reclassification of the main site.

Area 2 consisted of the upper and lower exhaust tunnel, the blower that moved Large Sodium Fire Facility (LSFF) exhaust from the lower to the upper tunnel, the exterior underground tunnel to the 117-DR HEPA Filter Building, and the ducts to the submerged gravel scrubber. Steel barricades at the north end of the tunnels blocked air flow to and from the reactor. The tunnel had low, but measurable radioactivity when sampled in 1987 (see DOE/RL-90-25, Rev 2, Appendix A for sampling information). This area is part of the 105-DR Reactor Building and is also included in its Waste Information Data System (WIDS) site (118-DR-2).

Closure Info: Interim: Note - The 105-DR reactor operated between 1950 and 1964 for plutonium production. In 1973, the exhaust system portions of the 105-DR reactor were reactivated and re-purposed to support the Large Sodium Fire Facility (LSFF). The LSFF (sitecode 122-DR-1) was a RCRA TSD. Most of the components of the reactor exhaust system have two entries in the WIDS database, one representing the CERCLA (radioactive) contaminants and the other representing the RCRA hazardous chemical contaminants.

The portions of the LSFF TSD that are included in this remedial activity are the 117-DR Exhaust Filter Building (100-D-53/122-DR-1:4), the underground exhaust tunnel (122-DR-1:2), the 119-DR Exhaust sample building (100-D-64), two dry wells (100-D-23 and 100-D-54) and the 116-DR Exhaust Stack (132-DR-2/122-DR-1:5) Four of the seven 122-DR-1 subsites (122-DR-1:1, 122-DR-1:3, 122-DR-1:6 and 122-DR-1:7) were closed out under the 105-DR Large Sodium Fire Facility RCRA Closure Plan (LSFF Closure Plan) are were not discussed in

the CVP-2003-00018 Cleanup Verification Package.

The remedial objective for the structures was to remove each structure to a minimum of 0.9 meters (3 feet) below surface grade. In July 2003, remedial/removal action activities removed the 117-DR Exhaust Filter Building (100-D-53/122-DR-1:4), the downstream (post-filter) tunnel and the additional 0.9 meters (3 ft) of the 116-DR Reactor Exhaust Stack (132-DR-2/122-DR-1:5). The aboveground portion of the 132-DR stack had been demolished in 1999.

Large Sodium Fire Facility (LSFF) subsite 122-D-1:2 (underground tunnel between the 105-DR Building) and the 117-DR Exhaust Filter Building were entirely removed. The 315 and 316 exhaust plenums, (aka upper and lower exhaust tunnels) are also associated with the 122-D-1:2 subsite. The upper exhaust tunnel and approximately the top 0.9 meters (3 ft) of the lower exhaust tunnel were removed. The 119-DR Exhaust Stack Sampling Building and two stack sampling building dry wells (100-D-23 and 100-D-64) were also demolished and excavated as part of the remedial/removal action activities in July 2003.

At the completion of the remedial action, the total excavation was approximately 1,010 square meters (10,872 square feet) in area with an approximate depth of 5 meters (16.4 feet). Approximately 14,011 metric tons (15,412 tons) of material from the site were disposed of at the Environmental Restoration Disposal Facility.

The SubSite is Part Of:

Code: 122-DR-1

Names: 122-DR-1; LSFF; 100-D-51; 105-DR Large Sodium Fire Facility; 105-DR Sodium Fire Facility

Code: 122-DR-1:3

Classification: Accepted

Names: 122-DR-1:3; Gravel Scrubber; 122-DR-1 Area 3

Reclassification Closed Out (10/1/1996)

Type: Laboratory

Start Date:

Status: Inactive

End Date:

Description: The RCRA TSD component was clean closed. The facility RCRA closure plan divided the facility into seven areas for sampling and closure purposes. The seven areas became subsites of the 122-DR-1 WIDS site.

Area 3 consists of a submerged gravel scrubber and ducts that were installed in 1982 as part of a filter development program. Installation of the gravel scrubber allowed the offgas from tests or burning to bypass the 117-DR HEPA Filter Building. The scrubber water was confirmed to be within pH tolerances (2.0 to 12.5) and discharged to the 116-DR-8 Crib. Two gravel samples numbered B0G9F6 and B0G9F7 were taken from the gravel scrubber. Based on evaluation of the sample data, the gravel did not designate as a Dangerous Waste (see WHC-SD-EN-EV-034, Rev. 1 for sample results). The gravel that had been removed from the unit was made available for reuse. The associated ductwork was removed. The area was clean closed.

Location: The site was located at the south end of the 100 D/DR Exclusion Fence.

The SubSite is Part Of:

Code: 122-DR-1

Names: 122-DR-1; LSFF; 100-D-51; 105-DR Large Sodium Fire Facility; 105-DR Sodium Fire Facility

Code: 122-DR-1:4

Classification: Accepted

Names: 122-DR-1:4; 117-DR HEPA Filter Building; 122-

Reclassification Closed Out (7/1/2004)

DR-1 Area 4

Type: Laboratory

Start Date:

Status: Inactive

End Date:

Description: The RCRA TSD component was clean closed. The facility RCRA closure plan divided the facility into seven areas for sampling and closure purposes. The seven areas became subsites of the 122-DR-1 WIDS site. Prior to RCRA closure, subsites 122-DR-1:2, 122-DR-2:4, and 122-DR-1:5 had been reclassified as Interim Closed Out under CERCLA. The reclassification status for these subsites was changed to Closed Out to be consistent with the reclassification of the main site. The CERCLA remediation for this subsite is documented in WIDS sitecode 100-D-53.

Area 4 consisted of the 117-DR HEPA Filter Building and the downstream tunnel to the reactor stack. The filter building housed the exhaust air filters. The building was about 18 meters (59 feet) long, 12 meters (39 feet) wide, and 11 meters (35 feet) high. The Filter Building was connected by underground concrete ductwork to the 116-DR exhaust stack. The filter building contained the HEPA filters, which were installed in four filter frames (24 filters per frame). In 1972, the original HEPA filters from the 105-DR Reactor were replaced before Large Sodium Fire Facility (LSFF) operations began. However, remnant radioactivity from the exhaust tunnels or filter holders had probably been picked up by the new filters. The 117-DR Filter Building was also a separate Waste Information Data System (WIDS) site (100-D-53).

Closure Info: Interim: Note - The 105-DR reactor operated between 1950 and 1964 for plutonium production. In 1973, the exhaust system portions of the 105-DR reactor were reactivated and re-purposed to support the Large Sodium Fire Facility (LSFF). The LSFF (sitecode 122-DR-1) was a RCRA TSD. Most of the components of the reactor exhaust system have two entries in the WIDS database, one representing the CERCLA (radioactive) contaminants and the other representing the RCRA hazardous chemical contaminants.

The portions of the LSFF TSD that are included in this remedial activity are the 117-DR Exhaust Filter Building (100-D-53/122-DR-1:4), the underground exhaust tunnel (122-DR-1:2), the 119-DR Exhaust sample building (100-D-64), two dry wells (100-D-23 and 100-D-54) and the 116-DR Exhaust Stack (132-DR-2/122-DR-1:5). Four of the seven 122-DR-1 subsites (122-DR-1:1, 122-DR-1:3, 122-DR-1:6 and 122-DR-1:7) were closed out under the 105-DR Large Sodium Fire Facility RCRA Closure Plan (LSFF Closure Plan) are were not discussed in the CVP-2003-00018 Cleanup Verification Package.

The remedial objective for the structures was to remove each structure to a minimum of 0.9 meters (3 feet) below surface grade. In July 2003, remedial/removal action activities removed the 117-DR Exhaust Filter Building (100-D-53/122-DR-1:4), the downstream (post-filter) tunnel and the additional 0.9 meters (3 ft) of the 116-DR Reactor Exhaust Stack (132-DR-2/122-DR-1:5). The aboveground portion of the 132-DR stack had been demolished in 1999.

Large Sodium Fire Facility (LSFF) subsite 122-D-1:2 (underground tunnel between the 105-DR Building) and the 117-DR Exhaust Filter Building were entirely removed. The 315 and 316 exhaust plenums, (aka upper and lower exhaust tunnels) are also associated with the 122-D-1:2 subsite. The upper exhaust tunnel and approximately the top 0.9 meters (3 ft) of the lower exhaust tunnel were removed. The 119-DR Exhaust Stack Sampling Building and two stack sampling building dry wells (100-D-23 and 100-D-64) were also demolished and excavated as part of the remedial/removal action activities in July 2003.

At the completion of the remedial action, the total excavation was approximately 1,010 square meters (10,872 square feet) in area with an approximate depth of 5 meters (16.4 feet). Approximately 14,011 metric tons (15,412 tons) of material from the site were disposed of at

the Environmental Restoration Disposal Facility.

The SubSite is Part Of:

Code: 122-DR-1

Names: 122-DR-1; LSFF; 100-D-51; 105-DR Large Sodium Fire Facility; 105-DR Sodium Fire Facility

Code: 122-DR-1:5

Classification: Accepted

Names: 122-DR-1:5; 116DR Reactor Exhaust Stack; 122-DR-1 Area 5

Reclassification: Closed Out (7/1/2004)

Type: Laboratory

Start Date:

Status: Inactive

End Date:

Description: The RCRA TSD component was clean closed. The facility RCRA closure plan divided the facility into seven areas for sampling and closure purposes. The seven areas became subsites of the 122-DR-1 WIDS site. Prior to RCRA closure, subsites 122-DR-1:2, 122-DR-2:4, and 122-DR-1:5 had been reclassified as Interim Closed Out under CERCLA. The reclassification status for these subsites was changed to Closed Out to be consistent with the reclassification of the main site. The CERCLA remediation for this subsite is documented in WIDS sitecode 132-DR-2.

Area 5 consisted of the reactor exhaust stack. Over the life of the Large Sodium Fire Facility (LSFF) there were two routes for exhaust to take before entering the reactor exhaust stack. The first route was through the HEPA filters which had a 99.95 percent efficiency rating. The second route was through the submerged gravel scrubber which had an efficiency rating of approximately 99 percent. It was expected that there were no measurable deposits of residue from LSFF operation within the stack. This subsite (116-DR Reactor Exhaust Stack) is also documented in Waste Information Data System (WIDS) as sitecode (132-DR-2).

Closure Info: Interim: Note - The 105-DR reactor operated between 1950 and 1964 for plutonium production. In 1973, the exhaust system portions of the 105-DR reactor were reactivated and re-purposed to support the Large Sodium Fire Facility (LSFF). The LSFF (sitecode 122-DR-1) was a RCRA TSD. Most of the components of the reactor exhaust system have two entries in the WIDS database, one representing the CERCLA (radioactive) contaminants and the other representing the RCRA hazardous chemical contaminants.

The portions of the LSFF TSD that are included in this remedial activity are the 117-DR Exhaust Filter Building (100-D-53/122-DR-1:4), the underground exhaust tunnel (122-DR-1:2), the 119-DR Exhaust sample building (100-D-64), two dry wells (100-D-23 and 100-D-54) and the 116-DR Exhaust Stack (132-DR-2/122-DR-1:5). Four of the seven 122-DR-1 subsites (122-DR-1:1, 122-DR-1:3, 122-DR-1:6 and 122-DR-1:7) were closed out under the 105-DR Large Sodium Fire Facility RCRA Closure Plan (LSFF Closure Plan) are were not discussed in the CVP-2003-00018 Cleanup Verification Package.

The remedial objective for the structures was to remove each structure to a minimum of 0.9 meters (3 feet) below surface grade. In July 2003, remedial/removal action activities removed the 117-DR Exhaust Filter Building (100-D-53/122-DR-1:4), the downstream (post-filter) tunnel and the additional 0.9 meters (3 ft) of the 116-DR Reactor Exhaust Stack (132-DR-2/122-DR-1:5). The aboveground portion of the 132-DR stack had been demolished in 1999.

Large Sodium Fire Facility (LSFF) subsite 122-D-1:2 (underground tunnel between the 105-DR Building) and the 117-DR Exhaust Filter Building were entirely removed. The 315 and 316 exhaust plenums, (aka upper and lower exhaust tunnels) are also associated with the 122-D-1:2 subsite. The upper exhaust tunnel and approximately the top 0.9 meters (3 ft) of the lower

exhaust tunnel were removed. The 119-DR Exhaust Stack Sampling Building and two stack sampling building dry wells (100-D-23 and 100-D-64) were also demolished and excavated as part of the remedial/removal action activities in July 2003.

At the completion of the remedial action, the total excavation was approximately 1,010 square meters (10,872 square feet) in area with an approximate depth of 5 meters (16.4 feet). Approximately 14,011 metric tons (15,412 tons) of material from the site were disposed of at the Environmental Restoration Disposal Facility.

The SubSite is Part Of:

Code: 122-DR-1

Names: 122-DR-1; LSFF; 100-D-51; 105-DR Large Sodium Fire Facility; 105-DR Sodium Fire Facility

Code: 122-DR-1:6

Classification: Accepted

Names: 122-DR-1:6; 116-DR-8 Crib (RCRA Action);
122-DR-1 Area 6

Reclassification Closed Out (10/1/1996)

Type: Laboratory

Start Date:

Status: Inactive

End Date:

Description: The RCRA TSD component was clean closed. The facility RCRA closure plan divided the facility into seven areas for sampling and closure purposes. The seven areas became subsites of the 122-DR-1 WIDS site.

Area 6 consists of the 116-DR-8 Crib meeting RCRA requirements. The crib was originally used from 1960 to 1964 to percolate low-level waste drainage from the 117-DR Building seal pits. When used for the Large Sodium Fire Facility (LSFF), the 116-DR-8 Crib received only water reported not to have been corrosive (the pH level was less than 12.5). This area is considered closed for the purposes of Washington Administrative Code (WAC) 173-303-610. Any contamination associated with Area 6 will be remediated in accordance with the 100-HR-3 RFI/CMS process.

The 117-DR Seal Pit Crib is documented in WIDS as two separate sites. The first site, 122-DR-1:6, is part the Large Sodium Fire Facility associated with a RCRA TSD. The RCRA permit has been closed for hazardous/dangerous constituents. The second site, 116-DR-8, represents the radioactive constituents remaining at the site that were addressed under CERCLA.

Location: The unit is located south of the exclusion area fence and directly east of the 118-DR-1 Burial Ground.

The SubSite is Part Of:

Code: 122-DR-1

Names: 122-DR-1; LSFF; 100-D-51; 105-DR Large Sodium Fire Facility; 105-DR Sodium Fire Facility

Code: 122-DR-1:7

Classification: Accepted

Names: 122-DR-1:7; Outdoor Storage Area; 122-DR-1
Area 7

Reclassification Closed Out (10/1/1996)

Type: Laboratory

Start Date:

Status: Inactive

End Date:

Description: The RCRA TSD component was clean closed. The facility RCRA closure plan divided the

facility into seven areas for sampling and closure purposes. The seven areas became subsites of the 122-DR-1 WIDS site.

Area 7 consists of the area to the north and west of the 117-DR HEPA filter building. The burn pans used in the alkali metal fires were sometimes stored in this area. Six soil samples, three random and three authoritative, were collected for this site. The samples were number B0G979 through B0G984. All samples were well below the Hanford Site background 95% thresholds for both lithium and sodium in soil (see WHC-SD-EN-TI-307 for sample results). The area was clean closed.

Location: Area 7 consists of the area to the north and west of the 117-DR HEPA filter building.

The SubSite is Part Of:

Code: 122-DR-1

Names: 122-DR-1; LSFF; 100-D-51; 105-DR Large Sodium Fire Facility; 105-DR Sodium Fire Facility

Code: 132-DR-2

Classification: Accepted

Names: 132-DR-2; 116-DR Reactor Exhaust Stack

Reclassification Interim Closed Out (3/4/2004)

Type: Stack

Start Date: 1/1/1950

Status: Inactive

End Date: 1/1/1986

Description: The site has been remediated and Interim Closed Out for CERCLA. The RCRA Large Sodium Fire Facility (LSFF) Closure Plan deferred the remaining three (LSFF) TSD subsites (122-DR-1:2, 122-DR-1:4, and 122-DR-1:5) to the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 (CERCLA) process. This waste site represents the CERCLA evaluation for 122-DR-1:5. The stack has been demolished. The unit was a monolithic, reinforced concrete structure with a maximum wall thickness of 0.46 meter (1.5 feet) at the base. It rested on a double octagon-shaped base that extended 5.3 meters (17.5 feet) below grade. An opening at the base provided access to its interior portion. This opening was fitted with a steel door.

132-DR-2 is also included in WIDS as subsite 122-DR-1:5 to document the RCRA component closure. The reclassification status for these subsites was changed to Closed Out to be consistent with the reclassification of the main site.

Location: The unit was located on the south side of the 105-DR Building.

Related Sites/ Originally, 105-DR exhaust air flowed directly from the 105-DR to the exhaust stack.

Structures: Following completion of the confinement project in 1960, the exhaust air was diverted to the 117-DR Filter Building, via underground ducts, prior to release through the stack.

Process Description: The 116 Reactor Exhaust Stacks were used to exhaust confinement air that originated from the work areas in the 105 Reactor Buildings. This stack was later reactivated to support exhausted emissions from the 105-DR Large Sodium Fire Facility operations.

Waste Type: Chemicals

Waste Description: Until 1964 the unit discharged exhaust air from the 105-DR Building. Since 1972, the unit was used to support operations relating to the 105-DR Large Sodium Fire Facility (122-DR-1). The interior of the unit contains an unknown quantity of low-level radioactive materials.

Closure Info: Interim: Note - The 105-DR reactor operated between 1950 and 1964 for plutonium production. In 1973, the exhaust system portions of the 105-DR reactor were reactivated and re-purposed to support the Large Sodium Fire Facility (LSFF). The LSFF (sitecode 122-DR-1) was a RCRA TSD. Most of the components of the reactor exhaust system have two entries in the WIDS

database, one representing the CERCLA (radioactive) contaminants and the other representing the RCRA hazardous chemical contaminants.

The portions of the LSFF TSD that are included in this remedial activity are the 117-DR Exhaust Filter Building (100-D-53/122-DR-1:4), the underground exhaust tunnel (122-DR-1:2), the 119-DR Exhaust sample building (100-D-64), two dry wells (100-D-23 and 100-D-54) and the 116-DR Exhaust Stack (132-DR-2/122-DR-1:5) Four of the seven 122-DR-1 subsites (122-DR-1:1, 122-DR-1:3, 122-DR-1:6 and 122-DR-1:7) were closed out under the 105-DR Large Sodium Fire Facility RCRA Closure Plan (LSFF Closure Plan) are were not discussed in the CVP-2003-00018 Cleanup Verification Package.

The remedial objective for the structures was to remove each structure to a minimum of 0.9 meters (3 feet) below surface grade. In July 2003, remedial/removal action activities removed the 117-DR Exhaust Filter Building (100-D-53/122-DR-1:4), the downstream (post-filter) tunnel and the additional 0.9 meters (3 ft) of the 116-DR Reactor Exhaust Stack (132-DR-2/122-DR-1:5). The aboveground portion of the 132-DR stack had been demolished in 1999.

Large Sodium Fire Facility (LSFF) subsite 122-D-1:2 (underground tunnel between the 105-DR Building) and the 117-DR Exhaust Filter Building were entirely removed. The 315 and 316 exhaust plenums, (aka upper and lower exhaust tunnels) are also associated with the 122-D-1:2 subsite. The upper exhaust tunnel and approximately the top 0.9 meters (3 ft) of the lower exhaust tunnel were removed. The 119-DR Exhaust Stack Sampling Building and two stack sampling building dry wells (100-D-23 and 100-D-64) were also demolished and excavated as part of the remedial/removal action activities in July 2003.

At the completion of the remedial action, the total excavation was approximately 1,010 square meters (10,872 square feet) in area with an approximate depth of 5 meters (16.4 feet). Approximately 14,011 metric tons (15,412 tons) of material from the site were disposed of at the Environmental Restoration Disposal Facility.

Code: 100-F-1	Classification: Not Accepted
Names: 100-F-1; 100-FR-2 Depression	Reclassification: None
Type: Depression/Pit (nonspecific)	Start Date:
Status: Inactive	End Date:
Description: The site is a depression surrounded by a post and chain barricade with warning signs stating "DANGER, KEEP AWAY." The surface of the depression is grass-covered. The site may be the location of a valve box along the raw water line that went from 190-C to the Pump House for the Radiological Science Laboratory Building and the Grazing Plot. During the April 1999 visit, metal and wooden stakes were observed on the ground and a soil gas probe was visible.	
Location: The depression is approximately 91 meters (300 feet) southwest of the 100-FR-2 Vent Pipe and 30.5 meters (100 feet) north of the northwest corner of 118-F-1 Burial Ground.	
Related Sites/ Structures: The site was probably related to the 190-C Building, the Radiological Science Laboratory Building and the Grazing Plot.	
Process Description: The GPR survey correlates fairly well with drawing SK-1-2847, High Purity Water System for 100F Biology. A raw water line tees from the raw water exiting from 190-C, goes south along the outside edge of the 105-F exclusion area fence, along the railroad track and above the north edge of the 118-F-1 Burial Ground and over to a pump house that supplied water to the Radiological Science Laboratory Building and Grazing Plot. According to the Technical Baseline Document, WHC-SD-EN-TI-169, the Grazing Plot (10-acres) was used to pasture pregnant animals and animals too young for experiments. The document goes on to state that	

no contaminants are known to exist at this location.

Code: 100-F-5	Classification: Accepted
Names: 100-F-5; 1717-F Building Drywell	Reclassification Rejected (7/29/1997)
Type: French Drain	Start Date:
Status: Inactive	End Date:

Description: The site is a 1.2 meters (48 inches) diameter french drain (drywell). The drywell was constructed per Hanford Standard AC-5-3 and was surrounded by steel post and chain barrier. The purpose of the site was to receive boiler steam condensate from blowdown valves. A 10 centimeter (4 inches) pipeline connected the boilers (2) of the 1717-F Building to the drywell.

Location: The site is approximately 26 meters (85 feet) west of the 1717-F Building.

Related Sites/ Structures: The site was related to the 1717-F Building (Combined Shops). The site is associated with site 100-F-32, 1717-F Building Underground Fuel Oil Tanks.

Waste Type: Steam Condensate

Waste Description: The unit received steam condensate from automatic blowdown valves connected to the boilers. The steam generation system for 1717-F was a once through system. The condensate would have received some residual salt (sodium chloride) from water softeners. Backflush from the water softeners went to the sanitary sewer system. Review of the drawings shows no indication of any additional chemical treatment during water softening. Steam condensate was not recycled to the boiler system. Drawing H-1-14566, Steam Generating Equipment Installation Piping Diagrams, shows the steam generation equipment including, the boilers, automatic blow down valves, piping to the drywell, and the drywell.

Code: 100-F-6	Classification: Not Accepted
Names: 100-F-6; 1716 FA Fuel Tank and Pump	Reclassification None
Type: Storage Tank	Start Date:
Status: Inactive	End Date: 1/1/1945

Description: The site is the 1716-FA Automotive Repair Shop gas tanks and gas pumps. Hanford Drawing M-2938 shows the location of the shop and gas tanks.

During the April 1999 visit, a survey grade GPS was used to locate the site based on its mapped coordinates. The surrounding area was covered with cobbles and rocks with sparse vegetation, primarily rabbitbrush and grasses. Some debris was visible, including metal, concrete chunks and fragments of automobile headlights or taillights. An approximately 3.7 meter (12 foot) tall pile of soil and rock was visible to the south and appeared to be old borrow material.

Location: The site is located north of the western half of the 100F Coal Storage Area.

Related Sites/ Structures: The site was related to the 1716-FA Automotive Repair Shop.

Waste Type: Oil

Waste Description:

Code: 100-F-8 **Classification:** Accepted
Names: 100-F-8; French Drains Near 105-F Gate **Reclassification** Rejected (7/29/1997)
Type: French Drain **Start Date:**
Status: Inactive **End Date:**

Description: The two french drains are constructed of 91 centimeter (36 inch) concrete pipe of unknown length buried to a depth which places their upper surfaces a few inches above grade. An excavation permit was issued in September 2010 for the removal of the two 100-F-8 French drains (DAN-4018-1A). A sample was taken to support development of an ERDF profile for disposal of removed material. The French drains have been excavated and backfilled.

Location: The french drains are near the main (north) entrance gate to the 105-F Reactor Building security fence. The first drain is about 22.9 meters (75 feet) south of the gate and the second is in line with the first and about 7.6 meters (25 feet) further south.

Waste Type: Water

Waste Description:

Code: 100-F-17 **Classification:** Not Accepted
Names: 100-F-17; 108-F Chemical Pump House; **Reclassification** None
 Chemical Storage Tanks at 108-F; Chemicals
 Used at 108-F Building
Type: Storage Tank **Start Date:**
Status: Inactive **End Date:**

Description: The Pump House and storage tanks have been removed. The site was a four story steel framed building with concrete block walls, concrete foundation and floors, and a concrete tile roof with a tar and gravel surface. The entire building was in poor condition. The chemical storage tanks that were originally located on the west side of the building have been removed. A loading dock extends from the south end of the east wall. A gas dock is attached to the south end of the building. Abandoned equipment and debris is scattered around the southwest corner of the building.

Location: The 108-F building is located approximately 100 meters (330 feet) east of the 105-F Reactor Building.

Process Description: The 108-F was originally built to be used as a chemical pump house to hold and pump various chemicals needed in reactor water treatment and reactor purging (internal cleansing). It contained many holding and mixing tanks and pumps, along with storage bins for dry materials, conveyor systems, hoppers, and power shovels. Shortly after the F Reactor began operation, it was determined that such treatment would not be required and cooling water treatment could be performed elsewhere in the systems. The 108-F building was then converted to be used as a biological laboratory where the effects of radiation and contamination on plant and animal life were studied.

Waste Type: Asbestos (friable)

Waste Description:

Code: 100-F-21 **Classification:** Not Accepted
Names: 100-F-21; Exclusion Area; Grounds Surrounding Deactivated Areas **Reclassification:** None
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The grounds within the 100-F exclusion area that are not part of other waste sites.

Code: 100-F-28 **Classification:** Accepted
Names: 100-F-28; Septic Tank and Drainfield **Reclassification:** Rejected (1/29/2003)
Type: Septic Tank **Start Date:**
Status: Inactive **End Date:**

Description: This site has been reclassified to Rejected. It was a septic tank and its drainfield for an isolated office building, discovered on a 1954 drawing. No septic tank or markers were found during a field investigation at this site. The tank's mapped location placed it within an area that had been previously excavated to a depth of between 3.1 and 4.6 meters (10 and 15 feet) for fill material. The area was lightly vegetated with cheatgrass and shrubs. The septic tank was not found.

Location: The site was located northwest of the 182-F Reservoir, east of the powerlines, approximately 50 meters (160 feet) west of the roadway, and 180 meters (590 feet) south of the perimeter road.

Waste Type: Sanitary Sewage

Waste Description: The unit would have received sanitary sewage. Because the unit appears to have supported only one building and that building is not near any contaminated facilities, it is highly unlikely that it received any radiological contamination.

Code: 100-F-30 **Classification:** Not Accepted
Names: 100-F-30; 144-F Drywell **Reclassification:** None
Type: French Drain **Start Date:**
Status: Inactive **End Date:**

Description: The site is a drywell that was observed on drawing H-1-14123 on the south side of 144-F. During a site investigation on 1/2/97, no evidence of a drywell was visible. During the April 1999 visit, a survey grade GPS was used to locate the site based on its mapped coordinates. No evidence of the site was found at this point. The area is sparsely covered with rabbitbrush and grasses.

Location: The site is located in the 100-F Area within the former Pacific Northwest Laboratory's Experimental Animal Farm site. The 144-F building was located between the 141-C building and the 107-F Retention Basin. The drywell was located approximately 30 meters (100 feet) west of the 107-F Retention Basin Fence.

Process Description: The dry well received rainwater from the roof of the 144-F Building. See drawing H-1-14123, Facilities for Radiation Inhalation Studies.

Waste Type: Stormwater Runoff

Waste Description: The drywell received stormwater from the roof of the 144-F building.

Code: 100-F-32 **Classification:** Not Accepted
Names: 100-F-32; 1717-F Underground Fuel Oil Tanks **Reclassification:** None
Type: Storage Tank **Start Date:**
Status: Inactive **End Date:**

Description: The site is three underground fuel oil storage tanks. Each tank had a capacity of 94,625 liters (25,000 gallons). Each tank was 10.7 meters (35 feet) long and 2.4 meters (8 feet) in diameter. Pipelines ran to the 1717-F Building (Combined Shops) through a pump pit immediately east of the tanks.

Location: The three tanks are located approximately 33.5 meters (110 feet) west of 1717-F Building.

Related Sites/ Structures: The site was related to 1717-F Building. The site is associated with 100-F-5, 1717-F Building Drywell.

Code: 100-F-40 **Classification:** Accepted
Names: 100-F-40; Animal Farm Surface Impoundment **Reclassification:** Rejected (2/28/2002)
Type: Surface Impoundment **Start Date:**
Status: Inactive **End Date:**

Description: This site has been evaluated and reclassified to Rejected. It is a pair of impoundments and the associated ditches. They are no longer visible in the field. It was discovered on aerial photos from 1965 and consisted of two surface impoundments, one covered with tumbleweeds and the other new and unvegetated. The older impoundment had a slightly meandering ditch coming to the north end from the animal farm buildings. This ditch was dry in the September 1965 photo. A straight ditch, with water in it in the September 1965 photo, runs to the northern side of the northern impoundment, also coming from the same animal farm buildings.

Location: The impoundments are north of the 116-F-9 Trench and east of the animal farm. They are on the west side of, and adjacent to, the 100-F Area perimeter road. The approximate coordinates for the centroid of the impoundments are N147970/E5811115.

Waste Type: Animal Waste

Waste Description: Samples collected in April 2001 determined the surface ponds held only uncontaminated animal waste resulting from pen cleaning.

Code: 100-F-41 **Classification:** Accepted
Names: 100-F-41; 100-F Clean Water Pipelines; 100-F Service Water Pipelines **Reclassification:** Rejected (2/8/2007)
Type: Product Piping **Start Date:**
Status: Inactive **End Date:**

Description: The site was divided into four subsites. All four subsites have been reclassified to Rejected. Therefore, the parent site is also Rejected.

The site included underground pipelines used to transport raw, fire, export, filtered, and sanitary water from the river pump house, to 100-F Area facilities, including the water treatment

facilities and fire hydrants. This site does not include lines within buildings, process or septic sewer lines, chemical transfer pipelines, pipelines that carried water treated with sodium dichromate, or pipelines that were downstream from the reactor building, i.e., those lines that carried cooling water from the reactor to the retention basin, Lewis Canal and/or the river.

A total of four (4) major pipelines and (43) smaller pipelines were identified as being associated with the 100-F-41 Service Water Pipelines site.

Location: The pipes were located across the 100-F Area, from the 181-F intake structure to the water treatment facilities, reactor (fire and potable water, not reactor cooling water), strontium gardens, south to the fire and patrol headquarters near the 1701-F gatehouse, west to join with the export water line from the 100-D Areas, and east to the animal farm area.

Related Sites/ Structures: The clean water and fire water pipelines ran to or near virtually all the facilities at the 100-F Area. Pipeline sites in the 100-F Area include 100-F-19, Process Effluent Pipelines; 100-F-26, Water Treatment Pipelines; the 100-F-39 river effluent lines; the 100-F-41 clean water pipelines; the 100-F-29 experimental animal farm pipelines and the 100-F-44 miscellaneous pipelines.

The other pipeline sites at the 100-F Area are 100-F-19 (Reactor Cooling Water Effluent); 100-F-26 (Water Treatment Plant Process Sewers); 100-F-29 (Experimental Animal Farm Process Sewers), and 100-F-39 (River Effluent Pipelines).

Waste Type: Equipment

Waste Description: The waste is the old buried pipes from the clean water pipeline system. No Contaminants of Potential Concern (COPC's) are identified for underground water service lines. Asbestos-containing wrapping on underground water lines were determined to be neither a hazardous nor a dangerous material of construction (Unit Managers Meeting Minutes for July 2005).

This Site has the Following SubSites:

Code: 100-F-41:1

Names: 100-F-41:1; North/South 4-Inch Steel Pipeline North of 183-F

Code: 100-F-41:2

Names: 100-F-41:2; East/West 2-Foot Steel Pipeline Connected to 190-F

Code: 100-F-41:3

Names: 100-F-41:3; North/South 4-Inch Pipeline East of 1704-F

Code: 100-F-41:4

Names: 100-F-41:4; East/West 4-Inch Steel Pipeline at West End of 115-F

Code: 100-F-41:1

Classification: Accepted

Names: 100-F-41:1; North/South 4-Inch Steel Pipeline North of 183-F

Reclassification: Rejected (2/8/2007)

Type: Product Piping

Start Date:

Status: Inactive

End Date:

Description: The subsite has been reclassified to Rejected.

The subsite consisted of a north-south oriented, 10 centimeter (4 inch) steel pipeline segment of unknown length. It was approximately 0.6 meters (2 feet) below ground surface. It was identified during an excavation for confirmatory sampling. The line was broken, when sampling was completed the steel pipe was returned to the test pit prior to backfilling with original

material. The pipe had no insulation or wrapping of any kind. No samples were collected of the pipe or pipe interior. Drawing H-1-12436 shows a north-south 10 centimeter (4 inch) diameter Fire & Sanitary Water Line.

Location: The pipeline segment was north of the 183-F Filter Building and south of the 182-F Reservoir, and is defined by the following coordinates: N148161 E580436, N148152 E580436, N148152 E580483, and N148112 E580483.

Waste Type: Not Specified

Waste Description: The waste is the buried lines from the clean water pipeline system. These pipelines are not CERCLA hazardous waste.

The SubSite is Part Of:

Code: 100-F-41

Names: 100-F-41; 100-F Clean Water Pipelines; 100-F Service Water Pipelines

Code: 100-F-41:2

Classification: Accepted

Names: 100-F-41:2; East/West 2-Foot Steel Pipeline Connected to 190-F

Reclassification: Rejected (2/8/2007)

Type: Product Piping

Start Date:

Status: Inactive

End Date:

Description: The subsite has been reclassified to rejected.

The subsite consisted of an east-west oriented, 0.6 meter (2 feet) steel pipeline segment. It was found approximately 1.8 meters (6 feet) below ground surface during an excavation for confirmatory sampling at 100-F-26:4. The pipe had no insulation or wrapping of any type. No samples were taken. This pipe was later identified on drawings H-1-12436 and H-1-12377 as a raw water line.

Location: The 100-F-41:2 pipeline segment was connected to the 190-F building foundation on the east side at coordinates N147736 E580503, and continued to N147736 E580611, N148162 E580610, and N148162 E580482.

Waste Type: Not Specified

Waste Description: The waste is the buried lines from the clean water pipeline system. These pipelines are not CERCLA hazardous waste.

The SubSite is Part Of:

Code: 100-F-41

Names: 100-F-41; 100-F Clean Water Pipelines; 100-F Service Water Pipelines

Code: 100-F-41:3

Classification: Accepted

Names: 100-F-41:3; North/South 4-Inch Pipeline East of 1704-F

Reclassification: Rejected (2/8/2007)

Type: Product Piping

Start Date:

Status: Inactive

End Date:

Description: The subsite has been reclassified to Rejected.

During excavation at the 100-F-26:9 sanitary sewers for collection of confirmatory samples, a north-south oriented, 10 centimeter (4 inch) pipeline was discovered approximately 1.2 meters (4 feet) below ground surface. It was intact and had no insulation or wrapping.

Construction drawing H-1-14562 showed a 7.6 centimeter (3 inch) sanitary water line trending south to north 3 meters west of the junction box sampling location. No depth was indicated on the drawing. The 1.1 centimeter (3 inch) sanitary water line shown on the construction drawing was within 1 meter of the estimated location of the discovered pipe. No reference to pipe diameter was documented to explain the size discrepancy indicated between logbook and the drawing. The discrepancy in pipeline size between the historic drawing and field observations was attributed to erroneous field measurements or the use of a larger diameter pipeline during construction.

Location: The 100-F-41:3 pipeline was located east of the south corner of the 1704-F building beginning at coordinates N147793/E580672, and continuing to N147793/E580675 and N147783/E580675.

Waste Type: Not Specified

Waste Description: The waste is the buried lines from the clean water pipeline system. These pipelines are not CERCLA hazardous waste.

The SubSite is Part Of:

Code: 100-F-41

Names: 100-F-41; 100-F Clean Water Pipelines; 100-F Service Water Pipelines

Code: 100-F-41:4

Classification: Accepted

Names: 100-F-41:4; East/West 4-Inch Steel Pipeline at West End of 115-F

Reclassification: Rejected (2/8/2007)

Type: Product Piping

Start Date:

Status: Inactive

End Date:

Description: The subsite consists of an east-west oriented, 10 centimeter (4 inch) steel pipeline approximately 1 meter (3 feet) below ground surface. The segment was identified during an excavation for confirmatory sampling. The steel pipe appeared to have no insulation or wrapping of any type. No samples were taken from the pipe. The pipe was left intact and the test pit was backfilled with the removed material.

Construction drawing H-1-12367 shows a cast iron (CI) fire and sanitary water line near the location of the discovered pipeline. BHI-01504 indicates a 10 centimeter (4 inch) cast iron service water pipe exits the west side of the 115-F Building.

Location: It is located at the west end of the 115-F Building beginning at N147582/E580314, and continuing to N147582/E580299 and N147643/E580299.

Waste Type: Not Specified

Waste Description: The waste is the buried lines from the clean water pipeline system. These pipelines are not CERCLA hazardous waste.

The SubSite is Part Of:

Code: 100-F-41

Names: 100-F-41; 100-F Clean Water Pipelines; 100-F Service Water Pipelines

Code: 116-F-13

Classification: Not Accepted

Names: 116-F-13; 1705-F Experimental Garden French Drain **Reclassification** None

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The site has been described as a french drain. A review of documents and drawings has found no indication that a french drain ever existed at the 1705-F Experimental Garden. This site appears to be confused with both the 146-FR fish rearing ponds and the 1607-F6 septic tank.

Location: The 1705-F Experimental Garden was part of the Experimental Animal Farm which was located in the northwest corner of the 100F area. The garden was north of the 141-F building (demolished) and east of the 1705-F building (demolished).

Related Sites/ Structures: The site is associated with 100-F-34.

Code: 118-F-9

Classification: Accepted

Names: 118-F-9; PNL Rad Site

Reclassification Rejected (8/24/2006)

Type: Burial Ground

Start Date:

Status: Inactive

End Date:

Description: The site has been reclassified to Rejected based on analytical data and minor excavation. The site consisted of one trench running east to west. It has been backfilled and vegetation has re-established itself after the remediation. The site was not marked or posted.

Location: The site was located south of and adjacent to the southeast corner of 126-F-1.

Related Sites/ Structures: The site was associated with the 100-F Experimental Animal Farm. The site was identified as being in the same area as the 126-F-1 Ash Pit and the 100-F-20 burial ground.

Process Description: The site was believed to have received undocumented miscellaneous solid wastes from animal research studies at the Experimental Animal Farm.

Code: 132-F-2

Classification: Not Accepted

Names: 132-F-2; 132-F-2 Inhalation Laboratory; 144-F; 144-FB

Reclassification None

Type: Laboratory

Start Date:

Status: Inactive

End Date:

Description: The facility was evaluated and determined not to meet the criteria of a waste site. The site was a laboratory that was part of the Experimental Animal Farm. The building has been demolished. It was a rectangular one-story, 302 square meter (3,250 square foot), concrete block building. The building contained an office, laboratories, and indoor and outdoor animal runs.

During the April 1999 visit, a survey grade GPS was used to locate the site using its mapped coordinates. A wooden stake was found in the ground at those coordinates. No evidence of the site was found. However, the area had been disturbed by heavy equipment, concrete chunks were visible and vegetation was sparse.

Location: The building was located south of the 141-F (132-F-1) sheep barn and east of the 141-C hog barn.

Related Sites/ Structures: Effluent from the lab site went to the 100-F-31 Septic System, south of the building.

Process Description: The laboratory was used for particulate exposure experiments and for a series of studies on the effects of ionizing radiation on dogs. Between 300 and 400 beagles were housed at the nearby dog kennels during the studies. The primary isotopes used for the dog studies were plutonium-239 and radium-226.

Code: 100-H-6 **Classification:** Not Accepted

Names: 100-H-6; Suspect Waste Site: Contaminated Ramp **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The site was a contaminated concrete ramp connected to the 105-H Reactor Building. The concrete ramp was enclosed in heavy wire mesh and is posted as a "Contamination Area". The 100-H-105 Reactor building has been cocooned and placed in Interim Safe Storage.

Location: The ramp is located on the east side of the 105-H reactor building. It is considered part of the Reactor building (118-H-6).

Release Description: Site personnel believe the ramp may have become contaminated from moving contaminated material out of the reactor basement level. They believe the wire mesh was installed to prevent tumbleweeds from accumulating in the ramp area.

Code: 100-H-15 **Classification:** Not Accepted

Names: 100-H-15; 100-H-25; Possible Septic Tank & Tile Field **Reclassification:** None

Type: Septic Tank **Start Date:**

Status: Inactive **End Date:**

Description: The site appears in a photograph taken in 1950 as a rectangular site enclosed by a white rail fence. In the photograph, a line of disturbed soil is visible extending from the east end of the fenced area to a point near the southeast corner of the 151-H Electrical Substation. It appears to terminate at a manhole associated with the 1607-H1 septic tank.

Location: The site is located east of the southeast corner of the 151-H electrical substation site, at or very near the location of 118-H-2 Burial Ground (see Site Comment).

Code: 100-H-16 **Classification:** Accepted

Names: 100-H-16; 184-H Brine Pit; 184-H Salt Dissolving Pit and Brine Pump House; H Area Power House Brine Pit **Reclassification:** Rejected (8/12/1997)

Type: Sump **Start Date:** 1/1/1948

Status: Inactive **End Date:**

Description: The salt dissolving pits and brine pump pit were part of a single below-grade concrete structure that provided brine for the 184-H Powerhouse. No evidence of the structure can be seen today. The salt dissolving pits each had inner dimensions of 4.3 meters (14 feet) long by 2.4 meters (8

feet) wide by 2.8 meters (9.25 feet) tall. They had a design high water line 2.4 meters (7.75 feet) from the pit bottom. An overflow slot that connected the two dissolving pits was located 0.3 meters (1 foot) above the high water line. The bottom of each pit was filled with a 12.7 centimeter (5 inch) layer of 1.3 to 2.6 centimeter (1/2 to 1 inch) gravel topped by a 17.8 centimeter (7 inch) layer of 0.3 to 0.6 centimeter (1/8 to 1/4 inch) gravel. The dissolving pits each had a 2.4 meter (8 feet) by 0.9 meter (3 feet) opening at the top for receiving salt. Each pit had a capacity of 23,600 kilograms (52,000 pounds) of salt. The brine pump pit is located adjacent to the two salt dissolving pits. The pit was 3.3 meters (10.67 feet) long by 2.2 meters (7.33 feet) wide by 2.1 meters (7 feet) deep. It held two pumps and associated piping (all brass) for the brine system. The floor of the pump pit sloped toward a 46 by 46 by 46 centimeters (18 by 18 by 18 inches) sump in a corner. A sump pump discharged to a nearby french drain (100-H-32).

Location: The site is located south of 184-H and just north of the railroad tracks.

Related Sites/ Structures: The site is associated with 184-H Power House and the 100-H-32 French Drain.

Process Description: The brine was used to regenerate the zeolite ion exchange demineralizers that were part of the powerhouse water treatment system.

Waste Type: Demolition and Inert Waste

Waste Description: The site was probably demolished in place. No documentation has been located related to cleanup. It is not known if salt cake was left in the structure.

Code: 100-H-18

Classification: Not Accepted

Names: 100-H-18; Undocumented Unplanned Airborne Release: Stack Emission No. 1

Reclassification: None

Type: Unplanned Release

Start Date: 1/1/1955

Status: Inactive

End Date:

Description: There are no posted areas related to this release.

Location: Affected areas included the 100-H Area and the Wahluke Slope. Figure 3 in HW-54636 shows the particulate density with the 100-H Area.

Release Description: The 105-H stack emitted approximately 0.6 curies of filterable gross beta contamination on May 3, 1955, when two ruptured slugs were removed from the reactor. The amount of material released was calculated based on the ground deposition.

Waste Type: Process Effluent

Waste Description: The waste consisted of airborne radioactive particulates released through the 105-H stack.

Code: 100-H-19

Classification: Not Accepted

Names: 100-H-19; Undocumented Unplanned Airborne Release: Stack Emission No. 2

Reclassification: None

Type: Unplanned Release

Start Date: 1/1/1955

Status: Inactive

End Date:

Description: There are no posted areas related to this site.

Location: Affected areas included 100-H and parts of the 600 Area to the west and south. Figure 4 in HW-54636 shows the particulate density within the 100-H Area. Figure 5 in HW-54636 has a larger scale and shows the particulate density over the greater area.

Release Description: On November 1, 1955, a ruptured slug burned briefly during discharge from the reactor. Approximately 0.8 curie of filterable gross beta contamination, mostly barium and rare earth plus yttrium, was emitted from the 105-H stack. The south one-third portion of the 100-H Area was found contaminated with concentrations as high as 12 particles per 9.3 square meters (100 square feet). The contamination level was 1,000 to 10,000 counts/minutes, with isolated particles as high as 1 100 millirads/hour. One particle, found near the 100-H Gatehouse, had a dose rate of 700 millirads/hour. The contamination was found to have spread south of 100-H Area, covering an area of approximately 18.1 square kilometers (7 square miles).

Waste Type: Process Effluent

Waste Description: The waste consisted of airborne radioactive particulates released through the 105-H stack.

Code: 100-H-20 **Classification:** Not Accepted

Names: 100-H-20; Undocumented Unplanned Release: Swallow Nests and Droppings **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1956

Status: Inactive **End Date:**

Description: There are no posted areas related to this release.

Location: The release contaminated an area extending from around the 100-H water tower over a flight path toward the White Bluffs. Figure 6 in HW-54636 shows the levels of contamination that were detected within the 100-H Area.

Release Description: After isolated cases of personnel and vehicle contamination were detected on May 15, 1956, it was discovered that swallows were making nests out of contaminated mud taken from the 107-H Liquid Waste Disposal Trench. The contaminated mud was being dropped around the 100-H water towers and at scattered locations over the flight path to the White Bluffs across the Columbia River. Concentrations ranged from 0 to 6 particles per 9.3 square meters (100 square feet), with a maximum recorded reading of 150 millirads/hour.

Related Sites/Structures: The release is related to the 107-H Liquid Waste Disposal Trench (116-H-1) and the 100-H Water Towers.

Waste Type: Soil

Waste Description: The 107-H Liquid Waste Disposal Trench received highly contaminated cooling water from the 107-H Retention Basin. The mud used by the swallows would have contained radioactive contamination from fuel element rupture.

Code: 100-H-26 **Classification:** Not Accepted

Names: 100-H-26; Exclusion Area; Grounds Surrounding Deactivated Areas **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The grounds within the 100-H exclusion area that are not part of other waste sites.

Code: 100-H-27 **Classification:** Not Accepted
Names: 100-H-27; 100-H Area Patrol Headquarters **Reclassification** None
Storm Runoff Ditch
Type: Ditch **Start Date:**
Status: Inactive **End Date:**

Description: The site is a ditch that receives stormwater runoff from a nearby asphalt parking areas. The ditch runs northward from a 15 centimeter (6 inch) vitrified clay pipe that discharged at a headwall. A site visit in March 1999 found the ditch almost completely filled with tumbleweeds. The ditch is not marked or posted.

Location: The site is located southeast of the 105-H Reactor facility. It is west of and adjacent to the 1607-H3 septic tank and tile field.

Waste Type: Stormwater Runoff

Waste Description:

Code: 100-H-32 **Classification:** Accepted
Names: 100-H-32; 184-H Brine Pit French Drain **Reclassification** Rejected (1/30/2003)
Type: French Drain **Start Date:**
Status: Inactive **End Date:**

Description: There is no visual evidence of a french drain at this location. It was likely removed with the associated brine pit (100-H-16).

Location: The french drain site was located on the northeast corner of the 184-H Brine Pit (100-H-16), west of the 184-H Power House.

Related Sites/ Structures: This site is associated with the 100-H-16 Brine Pit.

Process Description: The site is a french drain that received sump drainage from the 184-H Brine Pit (100-H-16). The drain was constructed of 61-centimeter (24-inch) diameter pipe. The french drain was not visible in the field during investigations for the 100-H Area Technical Baseline Report (BHI-00175). The french drain would have received only brine water.

Waste Type: Chemicals

Waste Description: The french drain received any water or brine that collected in the 184-H Brine Pit Sump. The liquid would be expected to have contained high concentrations of sodium chloride (salt).

Code: 100-H-39 **Classification:** Accepted
Names: 100-H-39; Orphan Site H-007; Possible Thimble Pit Locations; Potential Thimble Burial Site **Reclassification** Rejected (5/3/2010)
Type: Trench **Start Date:**
Status: Inactive **End Date:**

Description: The waste site was reclassified to Rejected because it could not be definitively located. The four

potential thimble pit or trench locations were evaluated with geophysical surveys and test pit excavations.

Location: Four potential burial sites were determined from document and photographic research. Location one is at Ground position system (GPS) coordinates E577777, N152214 (north end); E577783, N152175 (south end); E577790, N152196 (east side). The west side is the railroad tracks. Location two is approximate coordinates E577752.8, N152287.5 and E577752.8, N152257.0. Location three is coordinates E577758, N152188. Location four is the north and south centroid coordinates of the a trench - E577737.6, N152458.9 and E577737.3, N152433.

Related Sites/ Structures: This potential thimble burial site is associated with 118-H-5, 118-H-6:5 and 100-H-2.

Process Description: Historical documents indicate areas that may have been used to bury thimbles or materials related to the removal of thimbles in 100-H Area.

Waste Type: Equipment

Waste Description: Radioactive Thimbles may be buried at these locations. The 100-H-2 waste site is an analogous site. There are two types of radioactive waste associated with Thimbles; neutron activated steel and aluminum material containing cobalt-60 and surface contaminated waste primarily with zinc-65.

Code: 100-H-47

Classification: Accepted

Names: 100-H-47; 1717-H Geophysical Anomaly; Orphan Site H-015; Possible UST

Reclassification Rejected (2/22/2010)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: This waste site is an anomaly found during a geophysical investigation. It is possibly an underground propane tank (shown on drawing SK-1-7326) associated with the demolished 1717-H building.

Location: The underground anomaly is located approximately 6 meters (20 feet) to east of the former site of the 1717-H building. The coordinates of the feature are E578008.5, N152616.5.

Related Sites/ Structures: The (potential) underground tank is associated with the 1717-H building.

Process Description: The 1717-H building was a maintenance shop and hot shop (see sitecode 100-H-4).

Code: 100-H-55

Classification: Accepted

Names: 100-H-55; Cast Iron Pipe

Reclassification Rejected (2/25/2010)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The site has been evaluated and found to be a valve access can not a pipe. Originally, this feature was reported to be a 20 cm (8 in) diameter cast iron pipe protruding 30 cm (12 in) from the ground at an angle (08082007-038-630). The pipe was discovered during an Orphan Sites Field Evaluation conducted in August of 2007 (EL-1628 p. 2). Geophysics was conducted in February 2009, and the results indicate that the visible segment of the 20 cm (8 in) diameter cast iron pipe is not part of an intact system (0596705). The pipe extends under the road at a

depth of 0.8 m (2.6 ft) and terminates at the edge of the other side of the road.

Location: The site is located northwest of the 105-H Reactor and approximately 0.2 miles downstream of river mile post #14. The site is bordered by paved and dirt roads. The site is also located in the vicinity of accepted WIDS site 600-151 (Military Dumping Area) and 600-152 (Military Septic Tanks).

Process Description: The process associated with this pipe is unknown. The pipe may have been related to pre-Hanford homestead activities or associated with the former military Base Camp 130 (BC 130).

Waste Type: Soil

Waste Description: The waste consists of the pipe and underlying soil. Since the pipe can not be related to any particular human activity, the contaminants of potential concern are unknown.

Code: 116-H-6	Classification: Accepted
Names: 116-H-6; 183-H Solar Evaporation Basins	Reclassification: Closed Out (5/13/1997)
Type: Retention Basin	Start Date: 1/1/1949
Status: Inactive	End Date: 1/1/1985

Description: The four basins used for waste evaporation were completely demolished in the fall of 1996. The RCRA TSD permit was closed in May 1997. The site was backfilled and re-vegetated in the spring of 1997. Sitecode 100-H-33 is the 183-H Solar Evaporation Basins Radionuclide Components. It was evaluated and determined to be reclassified to No Action in 2012. The site was a concrete water storage and treatment basin divided into four sections. Each section was subdivided into a deep subsidence basin and a shallow flocculation basin.

Location: The basins were located north of the 105-H Reactor and north of the east 183-H Clearwell (WIDS Site 126-H-2).

Related Sites/ Structures: Sitecode 100-H-33 is the 183-H Solar Evaporation Basins Radionuclide Components.

Process Description: The basins were constructed in 1949 and used for 100-H Area water treatment until the mid-1960's. Most of the water treatment structures, including 12 additional adjoining basins were demolished in 1974. The four remaining basins were inactive until July 1973, when radioactive and dangerous (mixed) waste from the 300 Area fuel fabrication facilities began to be shipped to the basins for storage and treatment. The last shipment of waste to the basins took place on November 8, 1985. As of September 1988, all the remaining sludge materials had been removed from each basin. During 1988 and 1989, Basin Number 1 and 4 were partially decontaminated by wet sandblasting. From June to December 1989, the remaining liquid wastes in Basins Number 2 and 3 had been removed and solidified into 208 liter (55 gallon) drums and transported to the 200 West Area Central Waste Complex, Retrievable Waste Storage Facility.

The water treatment basins received a maximum of approximately 1.5E+06 liters (400,000 gallons) of waste a year. The basins had a tank treatment design capacity of 2,650 liters (700 gallons) per day treated by evaporation and a tank storage design capacity of 8.2E+06 liters (2.2E+06 gallons), a collective value representing all four basins.

Waste Type: Process Effluent

Waste Description: The facility received routine and nonroutine wastes. The routine wastes consisted of spent acid etch solutions (primarily nitric, sulfuric, hydrofluoric, and chromic acids) generated by the Nuclear Fuel Fabrication process. These acidic solutions were reacted with excess sodium hydroxide before being transported to the 183-H Basins. Metal constituents include copper, silicon, zirconium, nickel, aluminum, chromium, manganese, and uranium, which were in the

form of precipitates. Nonroutine wastes consisted of unused chemicals and spent solutions from miscellaneous processes. The waste has been designated an Extremely Hazardous Waste (EHW) because of toxicity, waste code (WT01). The basins also received various nonradioactive waste (listed discarded chemical products), resulting in designation for cyanide (P030), vanadium pentoxide (P120), and formic acid (U123). Additionally, Basin #2 was designated EP Toxic because of the presence of chromium (D007). More detailed descriptions of these wastes and quantities are contained in DOE/RL 88-04, Interim Status Closure/Post-Closure Plan 183-H Solar Evaporation Basins.

Closure Info: Final: The 116-H-6 basins structures were remediated in late 1995 and 1996. All detectable contamination was removed, packaged and disposed. The contaminated surface of the concrete was scabbled and disposed. The remaining concrete was surveyed. The rubble was placed into the adjacent 183-H Clearwells. The residual radioactivity in the rubble was calculated with the RESRAD model. Clean closure of the basin waste site was not achieved due to levels of fluoride and nitrate remaining in the soil below the excavated 6.1 meters (20 feet). The levels were determined to be above the Method B cleanup levels of the Model Toxics Control Act (MTCA), Washington Administrative Code (WAC) 173-340. Therefore, the RCRA unit was closed under the partial closure option, with specified remedial measures provided under post closure care. The modified closure certification was accepted by the State of Washington Department of Ecology on May 13, 1997. The site was backfilled and revegetated in the spring of 1997.

Remedial measures included the placing of a vapor barrier at the bottom of the excavation and replacing the excavated soils with clean, compacted backfill. Post closure groundwater monitoring will continue at the unit under WAC 175-303-645 final status permit, compliance monitoring program. Corrective actions for the contaminated groundwater attributable to 183-H will be coordinated with remedial actions for the 100-HR-3 operable unit pursuant to CERCLA.

The footprint of the basins was released from radiological posting after 0.6 meters (2 feet) of soil was removed. Chemical contaminants were identified and removed to a maximum depth of 6.1 meters (20 feet).

Three boreholes were drilled through the site in 1991. Borehole C7860 (199-H4-84) was drilled in the waste site footprint in February 2011 as part of the Remedial Investigation. Strontium-90, Tc-99 and tritium were detected above background levels.

Reclassification form 99-124 was created to document the TSD closure, with the 1997 Ecology Acceptance of Certification Closure letter attached.

Code: 126-H-1	Classification: Accepted
Names: 126-H-1; 184-H Powerhouse Ash Pit; 188-H Ash Disposal Area	Reclassification: Rejected (6/25/1998)
Type: Coal Ash Pit	Start Date: 1/1/1948
Status: Inactive	End Date: 1/1/1965

Description: The 126-H-1 site is a large ash disposal pit and ash pile. The ash pit is approximately 76.2 meters (250 feet) long, 76.2 meters (250 feet) wide and 3.7 meters (12 feet) deep. The pit is divided into two parts by a 2.4 meter (8 foot) berm that runs east to west. The floor of the ash pit is evenly covered with ash and cinder. Some light vegetation is evident. An ash pile is located just south of the pit. The pile measures approximately 25 meters (82.0 feet) by 60 meters (196.9 feet).

Location: The site is located northwest of the 105-H Reactor and west of the where the 184-H Powerhouse was located.

Process Description: Coal ash from the 184-H powerhouse was mixed with raw river water and sluiced in slurry to the ash pit via a 20 centimeter (8 inch) steel pipeline.

Waste Type: Ash

Waste Description: Unknown amounts of coal ash were sluiced to the pit with raw river water. Ash from other Hanford ash pits has been analyzed using the EP Toxicity Test in accordance with WAC 173-303, and no hazardous materials were found.

Code: 100-K-2

Classification: Accepted

Names: 100-K-2; 118-K-2; 118-K-2 Sludge Burial Ground; Burial Area

Reclassification: Rejected (12/14/2010)

Type: Burial Ground

Start Date:

Status: Inactive

End Date:

Description: The site was evaluated and reclassified to Rejected. The site consists of a suspected sludge burial ground. The size of the trench was unknown. Historical documentation has indicated different locations on several sketch type drawings for the burial ground. The actual location cannot be verified.

In 2010, two test trenches and one test pit were dug to evaluate the site. Soil samples did not indicate the presence of any contamination. Visual observations did not indicate any sludge or other material.

Location: The site is located east of the 107-KE Retention Basins, between the 107-KE Retention Basins and the 100-K Perimeter Road.

Related Sites/ Structures: The site was related to the 107-KE and 107-KW Retention Basins.

Process Description: The site is a burial ground that was used to dispose of sludge from the 116-KE-4 (107-KE) and 116-KW-3 (107-KW) Retention Basins.

Waste Type: Sludge

Waste Description: The site is described as having received sludge from the retention basins (107-KE and 107-KW). Although an exact inventory for this sludge trench is not available, it is analogous to the 107-B retention basin sludge trench (116-B-14). Characterization done at the 107-B trench in 1978 found an average concentration of plutonium of 0.7 picocuries per gram and an average beta/gamma concentration of 240 picocuries per gram. The expected radionuclides include europium-155, cobalt-60, cesium-137, strontium-90 and nickel-63. Note: DOE/RL-94-61 Appendix K (Draft A), mistakenly lists the average plutonium concentration for the 107-B Sludge Trench (116-B-14) as 0.7 curies per gram. The original report for this sampling activity lists the value as 0.7 picocuries per gram (see UNI-946, page 2-36).

Code: 100-K-7

Classification: Not Accepted

Names: 100-K-7; 165-KE Ethylene Glycol Tanks; 165-KE-E and 165-KE-W

Reclassification: None

Type: Storage Tank

Start Date: 1/1/1955

Status: Inactive

End Date: 1/1/1971

Description: The site was two carbon steel underground (positioned horizontally) ethylene glycol storage

tanks. Both tanks were excavated and removed for reuse in June of 1994. All piping was blanked at the foundation of the 165-KE Building and exterior piping from the foundation of the building to the tanks was removed. Process knowledge from the excavation of the glycol tank at the 165-KW (August of 1993) indicated that the piping needed to be removed in order to remove the tanks. There was no evidence in the soil of a leak and the tanks appeared to be intact. One tank contained pure ethylene glycol and the other tank contained a mixture of water and ethylene glycol. The tanks supplied mixed and pure ethylene glycol for injection into process water pipelines to prevent freezing during cold periods. A pair of 10 centimeters (4 inches) fill pipelines led to a street box that contained a 10 centimeters (4 inches) cap. The street box was used for making a connection to railroad tank cars. The street box was just off the edge of a railroad spur.

Today, the site is gravel covered and no evidence of the site remains.

Location: The unit was located directly north of the 165-KE Building, adjacent to the 165-KE Building, and west of the personnel entry door.

Related Sites/ Structures: The site was related to the 165-KE Building, the 116-KE-5 (150-KE Heat Recovery Station), and process pipelines.

Waste Type: Chemicals

Waste Description: The waste was tanks that contained ethylene glycol.

Code: 100-K-8	Classification: Not Accepted
Names: 100-K-8; 165-KW Ethylene Glycol Tanks; 165-KW-E and 165-KW-W	Reclassification: None
Type: Storage Tank	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1970

Description: The site was two carbon steel underground (positioned horizontally) ethylene glycol storage tanks. Both tanks were excavated and removed for reuse on August 16, 1993. All piping was blanked at the foundation of the 165-KW Building and exterior piping from the foundation of the building to the tanks was removed. Process knowledge from the excavation of the glycol tanks at the 165-KW indicated that the piping needed to be removed in order to remove the tanks. There was no evidence in the soil of a leak and the tanks appeared to be intact. One tank contained pure ethylene glycol and the other tank contained a mixture of water and ethylene glycol. The tanks supplied mixed and pure ethylene glycol for injection into process water pipelines to prevent freezing during cold periods. A pair of 10 centimeters (4 inches) fill pipelines led to a street box that contained a 10 centimeters (4 inches) cap. The street box was used for making a connection to railroad tank cars. The street box was just off the edge of a railroad spur.

All piping associated with these tanks utilized welded joints with threaded couplings at the top of each tank. The pipelines related to these tanks were: (1) suction line -- 2.54 centimeters (1 inch) outside diameter by 6.1 meters (20 feet) to the building; (2) -- 10.2 centimeters (4 inches) outside diameter by 6.1 meters (20 feet) to the building (165-KW-E [east] tank only); (3) vent line -- 10.2 centimeters (4 inches) outside diameter by 9.1 meters (30 feet) (including the above ground components); (4) fill connection and street box -- 10.2 centimeters (4 inches) outside diameter by 4.6 meters (15 feet) long (empty during normal operation); (5) cross tie line -- 10.2 centimeters (4 inches) by 3.05 meters (10 feet) long (empty during normal operation).

Today, the site is gravel covered and no evidence of the site remains.

Location: The unit was located 3.05 meters (10 feet) north of the 165-KW Building and west of the personnel entry door.

Related Sites/ Structures: The site was related to 165-KW Building, 116-KW-4 (150-KW Heat Recovery Station) and process pipelines.

Waste Type: Chemicals

Waste Description: The waste was tanks that contained Ethylene glycol. The tanks had been rinsed and flushed during the shut down of the 105-KW Reactor and did not contain any fluid.

Code: 100-K-9 **Classification:** Not Accepted

Names: 100-K-9; 104-K Dry Well; 118-KE-2 French Drain (North) **Reclassification:** None

Type: French Drain **Start Date:**

Status: Inactive **End Date:**

Description: The site was the northernmost of two french drains at the 118-KE-2 rod storage cave. The drain structure was removed during the 118-KE-2 remediation. The french drain was a 0.6 meters (2 feet) diameter steel pipe with a steel cover. It was gravel filled to grade and surrounded by a yellow wooden barricade. The steel cover was posted with a confined space sign. The adjacent area was covered with gravel and cobbles.

Location: The site is located 3.5 meters (11.5 feet) from the northwest side of the 118-KE-2, 105-KE Horizontal Control Rod Storage Cave.

Related Sites/ Structures: The site is related to the 118-KE-2, 105-KE Horizontal Control Rod Storage Cave (118-KE-2 Thimble Cave) and 100-K-10.

Waste Type: Stormwater Runoff

Waste Description: The inlet to this french drain is between the two semi-circular steel pipes. It received stormwater that percolated down through the earth berm covering the caves.

Code: 100-K-10 **Classification:** Not Accepted

Names: 100-K-10; 104-K Dry Well; 118-KE-2 French Drain (South) **Reclassification:** None

Type: French Drain **Start Date:** 1/1/1953

Status: Inactive **End Date:**

Description: The site was the southernmost of two french drains at the 118-KE-2 rod cave. The drain structure was removed during the 118-KE-2 remediation. The french drain was a 0.6 meters (2 feet) diameter steel pipe with a steel cover. It was gravel filled to grade and surrounded by a yellow wooden barricade. The steel cover was posted with a confined space sign. The adjacent area was covered with gravel and cobbles.

Location: The site is located 3.5 meters (11.5 feet) from the northwest side of the 118-KE-2, 105-KE Horizontal Control Rod Storage Cave.

Related Sites/ Structures: The site is related to the 118-KE-2, 105-KE Horizontal Control Rod Storage Cave (118-KE-2 Thimble Cave) and the 100-K-9 french drain.

Waste Type: Stormwater Runoff

Waste Description: The inlet to this french drain is between the two semi-circular steel pipes. It received stormwater that percolated down through the earth berm covering the caves.

Code: 100-K-11 **Classification:** Not Accepted

Names: 100-K-11; 104-K Dry Well; 118-KW-2 French Drain (North) **Reclassification:** None

Type: French Drain **Start Date:**

Status: Inactive **End Date:**

Description: The site was the northernmost of two french drains at the 118-KW-2. The drain structure was removed during the 118-KW-2 remediation. The french drain was a 0.6 meters (2 feet) diameter steel pipe with a steel cover. It was gravel filled to grade and surrounded by a yellow wooden barricade. The steel cover was posted with a confined space sign. The adjacent area was covered with gravel and cobbles.

Location: The site is located on the northwest side of the 118-KW-2, 105-KW Horizontal Control Rod Storage Cave.

Related Sites/Structures: The site is related to the 118-KW-2, 105-KE Horizontal Control Rod Storage Cave (118-KW-2 Thimble Cave).

Waste Type: Stormwater Runoff

Waste Description: The inlet to this french drain is between the two semi-circular steel pipes. It received stormwater that percolated down through the earth berm covering the caves.

Code: 100-K-12 **Classification:** Not Accepted

Names: 100-K-12; 104-K Dry Well; 118-KW-2 French Drain (South) **Reclassification:** None

Type: French Drain **Start Date:**

Status: Inactive **End Date:**

Description: The site is the southernmost of two french drains at the 118-KW-2. The drain structure was removed during the 118-KW-2 remediation. The french drain was a 0.6 meters (2 feet) diameter steel pipe with a steel cover. It was gravel filled to grade and surrounded by a yellow wooden barricade. The steel cover was posted with a confined space sign. The adjacent area was covered with gravel and cobbles.

Location: The site is located on the northwest side of the 118-KW-2, 105-KW Horizontal Control Rod Storage Cave.

Related Sites/Structures: The site is related to the 118-KW-2, 105-KE Horizontal Control Rod Storage Cave (118-KW-2 Thimble Cave).

Waste Type: Stormwater Runoff

Waste Description: The inlet to this french drain is between the two semi-circular steel pipes. It received stormwater that percolated down through the earth berm covering the caves.

Code: 100-K-15 **Classification:** Not Accepted

Names: 100-K-15; 183-KW Liquid Alum Storage Tank **Reclassification:** None

(West)

Type: Storage Tank**Start Date:****Status:** Inactive**End Date:**

Description: The site was an above-ground vertical stainless-steel storage tank mounted on a concrete base. The tank has been removed and disposed at ERDF. This tank is no longer in existence. The tank was part of a system called "The Liquid Alum System", that supplied liquid alum for water treatment.

Location: The site was the western-most of two alum storage tanks located approximately 15.2 meters (50 feet) from the southwest corner of the 183-KW Head House and 10.7 meters (35 feet) south of the 183-KW Chlorine Vault.

Related Sites/ Structures: The tank was associated with the 183-KW Head House. The 183-KW Head House was the water quality center for the entire water treatment plant. In it were the facilities for metering raw water, for chemical injection into raw, filtered, and process water, and for effluent and influent control throughout the filter plant.

Process Description: Alum was used as a coagulant in water treatment. During the season of high water turbidity, activated silica was added as an aid in coagulation. Alum was fed from the storage tank and proportioned directly into the raw water line. The proportioning pump was paced by the flow of raw water in its 91-centimeter (36-inch) raw water line and fed at 30 parts per million (ppm) at a maximum flow rate of 121,000 liters per minute (32,000 gallons per minute). The liquid was supplied either by rail car or tank truck, as both connections are shown on the Liquid Alum System diagram in HW-24800-103. The piping and instrument identification diagram, H-1-16552, shows the pipelines, valves, and instrumentation related to the tank. During the winter, the liquid alum was pumped through heat exchangers for purpose of heating and agitating the chemicals.

Code: 100-K-16**Classification:** Not Accepted**Names:** 100-K-16; 183-KW Liquid Alum Storage Tank (East)**Reclassification:** None**Type:** Storage Tank**Start Date:****Status:** Inactive**End Date:**

Description: The site is an above-ground vertical stainless steel storage tank mounted on a concrete base. The tank has been removed and disposed at ERDF. This tank is no longer in existence. The tank was part of the Liquid Alum System that supplied liquid alum for water treatment.

Location: The site was the eastern-most of two alum storage tanks located approximately 10.7 meters (35 feet) south of the southwest corner of the 183-KW Head House and 10.7 meters (35 feet) south of the 183-KW Chlorine Vault. The liquid was supplied either by rail car or tank truck, as both connections are shown on the Liquid Alum System diagram in HW-24800-103. The piping and instrument identification diagram, H-1-16552, shows the pipelines, valves, and instrumentation related to the tank. During the winter, the liquid alum was pumped through heat exchangers for purpose of heating and agitating the chemicals.

Related Sites/ Structures: The tank was associated with the 183-KW Head House. The Head House was the water quality center for the entire water treatment plant. In it were the facilities for metering raw water, for chemical injection into raw, filtered, and process water, and for effluent and influent control throughout the filter plant.

Process Description: Alum was used as a coagulant in water treatment. During the season of high water turbidity, activated silica was added as an aid in coagulation. Alum was fed from the storage tank and

proportioned directly into the raw water line. The proportioning pump was paced by the flow of raw water in its 91-centimeter (36-inch) raw water pipeline and fed at 30 parts per million (ppm) at a maximum flow rate of 121,000 liters per minute (32,000 gallons per minute).

Code: 100-K-20	Classification: Not Accepted
Names: 100-K-20; 183-KW Sodium Silicate Storage Tank (West)	Reclassification: None
Type: Foundation	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1964

Description: The site was the western-most of the above-ground vertical tanks that were used to store liquid sodium silicate. Initially, tank trucks supplied the chemical for the tanks. Estimating from procurement and construction drawings for the bauxite tank (Project CAI 105), the sodium silicate tanks were removed in 1964 or 1965. Following removal, the bagged dry powder form of the chemical was used. The grade-level concrete base remained following removal of the tanks. The west tank base (Sodium Silicate Tank #1) is occupied by a bauxite storage tower (silos) and transfer system.

Location: The site is the western-most of two sodium silicate storage tanks that were located southeast of the 183-KW Head House and adjacent to the sulfuric acid tanks. The western-most tank was 10.7 meters (35 feet) southeast of the 183-KW Head House.

Related Sites/ Structures: The site was related to the 183-KW Head House.

Structures:

Process Description: During the seasons of high water turbidity, activated silica solution was fed into the raw water as an aid in coagulation. The silica was activated by sulfuric acid and prepared in two open-top, flat-bottom cylindrical steel mixing tanks. Each tank was 3.5 meters (11.5 feet) in diameter and 3.35 meters (11 feet) high, and was capable of mixing a batch to supply one-half of the plant for three hours at maximum rate. The batch cycle was completely automatic and electrically controlled, with sequence operation initiated by float level. Components (sodium silicate, sulfuric acid and water), of the activated silica were measured by displacement type meters and quantities were controlled by impulse counters. After batching, the activated silica was transferred to one of four steel tanks provided within the building for storing the solution. Each tank was sized to supply one-half of the plant for five hours at maximum flow and maximum parts per million. From the storage tanks the activated silica was pumped through metering orifices before injection into the raw water stream. The quantity of activated silica injected was regulated by a control valve whose operation was calibrated so that the metered quantity was in proportion to raw water flow. HW-24800-103, Vol 2, Page 137 shows the process flow for the sodium silicate system.

Waste Type: Chemicals

Waste Description: The unit stored sodium silicate. While the tanks were in use, the sodium silicate was purchased and stored in liquid form.

Code: 100-K-21	Classification: Not Accepted
Names: 100-K-21; 183-KW Sodium Silicate Storage Tank (East)	Reclassification: None
Type: Foundation	Start Date:
Status: Inactive	End Date:

-
- Description:** The site was the eastern-most of the above-ground vertical tanks that were used to store liquid sodium silicate. Initially, tank trucks supplied the chemical for the tanks. Estimating from procurement and construction drawings for the bauxite tank (Project CAI 105), the sodium silicate tanks were removed in 1964 or 1965. Following removal, the bagged dry powder form of the chemical was used. The grade-level concrete base remained following removal of the tanks.
- Location:** The site is the eastern-most of two sodium silicate storage tanks that were located southeast of the 183-KW Head House and adjacent to the sulfuric acid tanks. The eastern-most tank was 4.3 meters (14 feet) northeast of the other sodium silicate tank and 4.3 (14 feet) southeast of 120-KW-3, Sulfuric Acid Tank.
- Related Sites/ Structures:** The site was related to the 183-KW Head House.
- Process Description:** During the seasons of high water turbidity, activated silica solution was fed into the raw water as an aid in coagulation. The silica was activated by sulfuric acid and prepared in two open-top, flat-bottom cylindrical steel mixing tanks. Each tank was 3.5 meters (11.5 feet) in diameter and 3.35 meters (11 feet) high, and was capable of mixing a batch to supply one-half of the plant for three hours at maximum rate. The batch cycle was completely automatic and electrically controlled, with sequence operation initiated by float level. Components (sodium silicate, sulfuric acid and water), of the activated silica were measured by displacement type meters and quantities were controlled by impulse counters. After batching, the activated silica was transferred to one of four steel tanks provided within the building for storing the solution. Each tank was sized to supply one-half of the plant for five hours at maximum flow and maximum parts per million. From the storage tanks the activated silica was pumped through metering orifices before injection into the raw water stream. The quantity of activated silica injected was regulated by a control valve whose operation was calibrated so that the metered quantity was in proportion to raw water flow. HW-24800-103, Vol 2, Page 137 shows the process flow for the sodium silicate system.
- Waste Type:** Chemicals
- Waste Description:** The unit stored sodium silicate. While the tanks were in use, the sodium silicate was purchased and stored in liquid form.
-

Code:	100-K-22	Classification:	Not Accepted
Names:	100-K-22; 183-KE Sodium Silicate Storage Tank (West)	Reclassification	None
Type:	Foundation	Start Date:	1/1/1955
Status:	Inactive	End Date:	1/1/1964

- Description:** The site was the western-most of the above-ground vertical tanks that were used to store liquid sodium silicate. Initially, tank trucks supplied the chemical for the tanks. Estimating from procurement and construction drawings for the bauxite tank (Project CAI 105), the sodium silicate tanks were removed in 1964 or 1965. Following removal, the bagged dry powder form of the chemical was used. The grade-level concrete base remained following removal of the tanks. The west tank base (Sodium Silicate Tank #1) is occupied by a bauxite storage tower (silo) and transfer system.
- Location:** The site is the western-most of two sodium silicate storage tanks that were located southeast of the 183-KE Head House and adjacent to the sulfuric acid tanks. The western-most tank was 10.7 meters (35 feet) southeast of the 183-KE Head House.
-

Related Sites/ The site was related to the 183-KE Head House.

Structures:

Process Description: During the seasons of high water turbidity, activated silica solution was fed into the raw water as an aid in coagulation. The silica was activated by sulfuric acid and prepared in two open-top, flat-bottom cylindrical steel mixing tanks. Each tank was 3.5 meters (11.5 feet) in diameter and 3.35 meters (11 feet) high, and was capable of mixing a batch to supply one-half of the plant for three hours at maximum rate. The batch cycle was completely automatic and electrically controlled, with sequence operation initiated by float level. Components (sodium silicate, sulfuric acid and water), of the activated silica were measured by displacement type meters and quantities were controlled by impulse counters. After batching, the activated silica was transferred to one of four steel tanks provided within the building for storing the solution. Each tank was sized to supply one-half of the plant for five hours at maximum flow and maximum parts per million. From the storage tanks the activated silica was pumped through metering orifices before injection into the raw water stream. The quantity of activated silica injected was regulated by a control valve whose operation was calibrated so that the metered quantity was in proportion to raw water flow. HW-24800-103, Vol 2, Page 137 shows the process flow for the sodium silicate system.

Waste Type: Chemicals

Waste Description: The unit stored sodium silicate. While the tanks were in use, the sodium silicate was purchased and stored in liquid form.

Code: 100-K-23	Classification: Not Accepted
Names: 100-K-23; 183-KE Sodium Silicate Storage Tank (East)	Reclassification: None
Type: Foundation	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1964

Description: The site was the eastern-most of the above-ground vertical tanks that were used to store liquid sodium silicate. Initially, tank trucks supplied the chemical for the tanks. Estimating from procurement and construction drawings for the bauxite tank (Project CAI 105), the sodium silicate tanks were removed in 1964 or 1965. Following removal, the bagged dry powder form of the chemical was used. The grade-level concrete base remained following removal of the tanks.

Location: The site is the eastern-most of two sodium silicate storage tanks that were located southeast of the 183-KE Head House and adjacent to the sulfuric acid tanks. The eastern-most tank was 4.3 meters (14 feet) northeast of the other sodium silicate tank and 4.3 (14 feet) southeast of 120-KE-3, Sulfuric Acid Tank.

Related Sites/ The site was related to the 183-KE Head House.

Structures:

Process Description: During the seasons of high water turbidity, activated silica solution was fed into the raw water as an aid in coagulation. The silica was activated by sulfuric acid and prepared in two open-top, flat-bottom cylindrical steel mixing tanks. Each tank was 3.5 meters (11.5 feet) in diameter and 3.35 meters (11 feet) high, and was capable of mixing a batch to supply one-half of the plant for three hours at maximum rate. The batch cycle was completely automatic and electrically controlled, with sequence operation initiated by float level. Components (sodium silicate, sulfuric acid and water), of the activated silica were measured by displacement type meters and quantities were controlled by impulse counters. After batching, the activated silica was transferred to one of four steel tanks provided within the building for storing the solution.

Each tank was sized to supply one-half of the plant for five hours at maximum flow and maximum parts per million. From the storage tanks the activated silica was pumped through metering orifices before injection into the raw water stream. The quantity of activated silica injected was regulated by a control valve whose operation was calibrated so that the metered quantity was in proportion to raw water flow. HW-24800-103, Vol 2, Page 137 shows the process flow for the sodium silicate system.

Waste Type: Chemicals

Waste Description: The unit stored sodium silicate. While the tanks were in use, the sodium silicate was purchased and stored in liquid form.

Code: 100-K-24	Classification: Not Accepted
Names: 100-K-24; 183-KW Bauxite Tank	Reclassification: None
Type: Storage Tank	Start Date: 1/1/1966
Status: Inactive	End Date: 1/1/1972

Description: The site was a single bauxite (aluminum oxide) above-ground storage tank (silo). The tank has been removed and disposed at ERDF. This tank is no longer in existence. The addition of the tank was part of a proposal to reduce water treatment costs by approximately \$278,000 per year in the 183-KE and KW Buildings. Hanford document, HW-76926, is the engineering study that proposed replacing the existing liquid alum coagulant feed process with one which fed bauxite and sulfuric acid.

The tank was constructed on the site of the former Sodium Silicate #1 Tank. The tank had a capacity of 109,000 kilograms (240,000 pounds). One of the unused solution tanks, 45,400 kilograms (100,000 pounds) in capacity in the 183 Building (KE and KW) was converted to a bauxite feed bin. The feed bin was vented and equipped with a bag filter. The two silos (KE and KW) and the feed bin together provided approximately 33 days storage capacity. Other components of the system are listed below.

A pneumatic conveying system was provided that was equipped with cyclone separators to transfer bauxite from hopper cars or boxcars to the outside silos and from either silo to the feed bin inside the building. The bauxite was transferred intermittently from the silos to the feed bin and did not interfere with any rail car unloading. The system was sized to unload a rail car in a single work shift. Two dry feeders, including one spare, moved bauxite from the feed bin to a slurry mix tank. The spare feeder was included to eliminate the need to prepare slurry manually on a batch basis during maintenance shutdown of the other feeder.

A mix tank, with agitator, for slurring bauxite and water was a component of the system. Two pumps in parallel were used to transfer the slurry to reaction vessels.

Two parallel systems, each consisting of a glass-lined reaction vessel, with glass-lined pipe tie-ins; an eductor which took suction from the reaction vessel, adding dilution water; and a pump, in series with the eductor, discharged through the chlorine injection piping to the raw water headers. Glass-lined pipe was used between the reaction vessel and eductor, and plastic pipe between the eductors and injection piping. Acid was supplied to the reaction vessel, where it was mixed with the bauxite slurry by steam sparging, from an existing head tank by gravity feed. An exhaust system included a water scrubber to remove steam, air, and acid fumes from the reaction vessels.

Location: The unit was located 11.6 meters (38 feet) southeast of the 183-KW Head House and on the northwest portion of the original Sodium Silicate Tank concrete base.

Related Sites/ Structures: The site was related to the 183-KW, (183.2) Flocculation and Sedimentation Basins and the (183.1) Head House.

Process Description: The bauxite (hydrous aluminum oxide) in combination with sulfuric acid was used as a coagulant in the water treatment process. Mixing of the chemicals, water and sediment caused a gelatin-like flake (floc) to form. The water with the floc flowed from the Head House to the Sedimentation Basins where the flocs allowed to settle.

Waste Type: Chemicals

Waste Description: The tank was used to store dry bauxite (hydrous aluminum oxide or hydroxides with various impurities). The tank appears to have been emptied, although dry powder can be seen through the plexiglass cover indicating that no additional cleanup was performed. Bauxite is not listed in 40 CFR 302.4 as a hazardous substance and is not a CERCLA pollutant. No dangerous wastes or CERCLA hazardous substances, pollutants, or contaminants were stored or disposed of at this site.

Code: 100-K-28

Classification: Not Accepted

Names: 100-K-28; 183-KE Bauxite Tank

Reclassification: None

Type: Storage Tank

Start Date: 1/1/1966

Status: Inactive

End Date: 1/1/1972

Description: The site was a single bauxite (aluminum oxide) above-ground storage tank (silo). The tank has been removed and disposed at ERDF. This tank is no longer in existence. The addition of the tank was part of a proposal to reduce water treatment costs by approximately \$278,000 per year in the 183-KE and KW Buildings. Hanford document, HW-76926, is the engineering study that proposed replacing the existing liquid alum coagulant feed process with one which fed bauxite and sulfuric acid.

The tank was constructed on the site of the former Sodium Silicate #1 Tank. The tank had a capacity of 109,000 kilograms (240,000 pounds). One of the unused solution tanks, 45,400 kilograms (100,000 pounds) in capacity in the 183 Building (KE and KW) was converted to a bauxite feed bin. The feed bin was vented and equipped with a bag filter. The two silos (KE and KW) and the feed bin together provided approximately 33 days storage capacity. Other components of the system are listed below.

A pneumatic conveying system was provided that was equipped with cyclone separators to transfer bauxite from hopper cars or boxcars to the outside silos and from either silo to the feed bin inside the building. The bauxite was transferred intermittently from the silos to the feed bin and did not interfere with any rail car unloading. The system was sized to unload a rail car in a single work shift. Two dry feeders, including one spare, moved bauxite from the feed bin to a slurry mix tank. The spare feeder was included to eliminate the need to prepare slurry manually on a batch basis during maintenance shutdown of the other feeder. A mix tank, with agitator, for slurring bauxite and water was a component of the system. Two pumps in parallel were used to transfer the slurry to reaction vessels.

Two parallel systems, each consisting of a glass-lined reaction vessel, with glass-lined pipe ties; an eductor which took suction from the reaction vessel, adding dilution water; and a pump, in series with the eductor, discharged through the chlorine injection piping to the raw water headers. Glass-lined pipe was used between the reaction vessel and eductor, and plastic pipe between the eductors and injection piping. Acid was supplied to the reaction vessel, where it was mixed with the bauxite slurry by steam sparging, from an existing head tank by gravity feed. An exhaust system included a water scrubber to remove steam, air, and acid fumes from

the reaction vessels.

Location: The unit was located 11.6 meters (38 feet) southeast of the 183-KE Head House and on the northwest portion of the original Sodium Silicate Tank concrete base.

Related Sites/ Structures: The site was related to the 183-KE, (183.2) Flocculation and Sedimentation Basins and the (183.1) Head House.

Process Description: The bauxite (hydrous aluminum oxide) in combination with sulfuric acid was used as a coagulant in the water treatment process. Mixing of the chemicals, water and sediment caused a gelatin-like flake (floc) to form. The water with the floc flowed from the Head House to the Sedimentation Basins where the floc was allowed to settle.

Waste Type: Chemicals

Waste Description: The tank was used to store dry bauxite, aluminum oxide or hydroxides with various impurities. The tank appears to have been emptied, although dry powder can be seen through the plexiglass cover indicating that no additional cleanup was performed.

Code: 100-K-39

Classification: Not Accepted

Names: 100-K-39; 118-K-3 Filter Crib

Reclassification: None

Type: Crib

Start Date:

Status: Inactive

End Date:

Description: The site was reported to be a crib. The first reference to a site identified as 118-K-3 Filter Crib was DOE/RL-90-20 (1992). In this document, it states that the site was used to dispose of demineralizer, and research and development waste from the 1706-KE Building. A sketch, Figure 5-1. Proposed Boring Locations at 100-KR-1 Operable Unit High Priority Liquid Waste Facilities, shows a site labeled 118-K-3 Filter Crib between and south of the retention basins. The area where this site is mapped is the identical location of a fenced electrical distribution intertie that connects electrical service between 100K East and 100K West. WHC-SD-EN-TI-239, 100-K Area Technical Baseline Report states that the crib could not be located during field investigations for the report. Further, it says that a fenced, high-voltage power distribution system is located at the site described by DOE/RL-90-20. The document continues with the crib received liquid wastes from the 1705KE/KER Laboratory. Discussions with present and former site employees, and investigations using Hanford Drawings (H-1-20305, H-1-23215, and H-1-24226), indicate that all cribbed wastes from the 1706-KE/KER facilities were disposed in the 116-KE-2 Crib. The initial Waste Information Data System (WIDS) entry for this site was not done until 1994. The information contained on the data entry form (A-6000-501) was based on WHC-SD-SD-TI-239. It was also recommended that the site not be entered as a waste site due to the uncertainty of the site's existence. A field visit by WIDS personnel was performed on August 16, 1994. There was no evidence of a waste site at the prescribed location.

Location: The 118-K-3 Filter Crib was purported to be located between the 116-KW-3 and 116-KE-4 Retention Basins.

Related Sites/ Structures: According to DOE/RL-90-20 the site was related to the 1706-KE Building. According to Waste Information Data System (WIDS) 1994 Data Entry Form (A-6000-501) signed by the operable unit manager, the site was related to the 1705KE/KER Laboratory.

Code: 100-K-44

Classification: Not Accepted

Names: 100-K-44; Exclusion Area; Grounds Surrounding

Reclassification: None

Deactivated Areas

Type: Unplanned Release**Start Date:****Status:** Inactive**End Date:****Description:** The grounds within the 100-K exclusion area that are not part of other waste sites.**Code:** 100-K-51**Classification:** Accepted**Names:** 100-K-51; 105-KE 90-Day Waste Accumulation Area; 100K 90-Day Waste Storage Facility**Reclassification:** Rejected (9/14/2000)**Type:** Storage Pad (<90 day)**Start Date:****Status:** Inactive**End Date:****Description:** The site is a white, portable steel building, with no windows, and three doors that are all on one side. The site is being used by the Spent Fuel Division for the 90 day storage of hazardous waste.**Location:** The site is located approximately 150 meters (492 feet) west southwest of the 105-KE Reactor Building, and northwest of the 1717K Maintenance Building.**Waste Type:** Chemicals**Waste****Description:****Code:** 100-K-52**Classification:** Not Accepted**Names:** 100-K-52; 1706-KE Wet Fish Studies Laboratory**Reclassification:** None**Type:** Storage**Start Date:** 1/1/1956**Status:** Inactive**End Date:** 1/1/1965**Description:** The site was a laboratory (used by Pacific Northwest Laboratory) that conducted studies on fish using effluent cooling water. There was a small "wet lab" located inside the 1706-KE Building and three small outdoor ponds. The building and pond structures have been removed and disposed at ERDF. This facility no longer exists.**Location:** The site was located in the northwest corner of the 1706-KE Building.**Related Sites/ Structures:** The site was related to 100-K-3, 1706-KE Fish Pond Valve Pit and Heat Exchanger Pit and 100-K-4, 1706-KE Wet Fish Studies Laboratory Ponds.**Process Description:** The laboratory consisted of eight 1.5 meters (5 feet) long by 0.3 meters (1 foot) wide troughs containing a mixture of raw water and heated effluent water. The water was diverted from the heat exchanger pit (Site: 100-K-3) on the 105-KE Reactor discharge pipeline and passed through the troughs. Originally, the laboratory was planned in the event of shutdown of the 105-F Reactor and its laboratory. The laboratory was later used as a store room.**Waste Type:** Water**Waste Description:** A mixture of raw water and heated effluent water passed through the troughs. The troughs and laboratory equipment have been removed from the building.**Code:** 100-K-58**Classification:** Not Accepted

Names: 100-K-58; 100-KE Clean Water Pipelines; 100-KE Service Water Pipelines **Reclassification** None

Type: Product Piping **Start Date:** 1/1/1957

Status: Inactive **End Date:**

Description: The waste site is the upstream (pre-reactor) pipelines that carried raw river water from the 181-KE Pumphouse to the KE water treatment facilities and carried treated water to the 105-KE Reactor. The waste site includes all water lines that connected the different sections of the water treatment plant.

There are two raw water lines that run between the 181-KE Pumphouse and the 165-KE Control House. They are constructed of 152-centimeter (60-inch) diameter steel pipe with 1.3-centimeter (0.5-inch) thick walls.

Location: The site includes pipelines located between the 181-KE Pumphouse and the 165-KE Control House. Other lines included in this site are located between sections of the water treatment facility and between the 165-KE Control House and the 105-KE Reactor.

Related Sites/Structures: Related structures include the 181-KE River Pumphouse, the 165-KE Control House, 183.1-KE Headhouse, the 183.2-KE Basins, the 183.3-KE Filters, the 183.4-KE Clearwells, and the 190-KE Process Water Pumphouse.

Process Description: Water from the Columbia River was extensively treated before passing through the reactors. Treatment included settling, chemical treatment, filtering, and pH management to purify and prepare the water. Water flow rate to the 105-KE Reactor was in excess of 380,000 liters (100,000 gallons) per minute. After system upgrades in 1962, the flow rate was as high as 760,000 liters (200,000 gallons) per minute.

Waste Type: Water

Waste Description: The pipelines included carried raw, sanitary, and fire water throughout the 100-KE Area.

Code: 100-K-59 **Classification:** Not Accepted

Names: 100-K-59; 100-KW Clean Water Pipelines; 100-KW Service Water Pipelines **Reclassification** None

Type: Product Piping **Start Date:** 1/1/1957

Status: Inactive **End Date:**

Description: The site consists of the upstream (pre-reactor) pipelines that carried raw river water from the 181-KW Pumphouse to the KW water treatment facilities and carried sanitary and fire water to various facilities. The site includes all water lines that connected the different sections of the water treatment plant, except for the sulfuric acid and sodium dichromate pipelines on the south side of the water treatment plant, and the treated water pipelines running from the 165-KW Building to the 105-KW Reactor (WIDS site 100-K-79). It includes the sanitary water pipelines connecting the 165 KE and KW Control Houses (to a point half-way between them) and the sanitary water pipeline connecting the 183 KE and KW Head Houses (to a point half-way between them).

There are two raw water lines that run between the 181-KW Pumphouse and the 165-KW Control House. They are constructed of 152-centimeter (60-inch) diameter steel pipe with 1.3-centimeter (0.5-inch) thick walls.

Location: The site includes pipelines located between the 181-KW Pumphouse and the 165-KW Control

House. Other lines included in this site are located between sections of the water treatment facility and between the 165-KW Control House and the 105-KW Reactor.

Related Sites/ Structures: Related structures include the 181-KW River Pumphouse, the 165-KW Control House, 183.1-KW Headhouse, the 183.2-KW Basins, the 183.3-KW Filters, the 183.4-KW Clearwells, and the 190-KW Process Water Pumphouse.

Process Description: Water from the Columbia River was extensively treated before passing through the reactors. Treatment included settling, chemical treatment, filtering, and pH management to purify and prepare the water. Water flowing to the 105-KW Reactor was in excess of 380,000 liters (100,000 gallons) per minute. After system upgrades in 1962, the flow rate was as high as 760,000 liters (200,000 gallons) per minute.

Waste Type: Water

Waste Description: The pipelines included carried raw, sanitary, and fire water throughout the 100-KE Area.

Code: 100-K-76

Classification: Not Accepted

Names: 100-K-76; 105-KW Unplanned Release
Discovered Near 130-KW-1 Emergency Diesel Tank

Reclassification: None

Type: Unplanned Release

Start Date: 1/1/1992

Status: Inactive

End Date:

Description: This site is a duplicate of 130-KW-1. The site is the location of two removed underground diesel storage tanks. The "unplanned release" is the radiation contamination detected when the tanks were excavated. The excavated tank site has been backfilled with uncontaminated soil to grade and covered with gravel. There is no separate radiological posting. However, the 100-KE/KW Reactor Areas are posted Underground Radioactive Material on the perimeter fences.

Location: The site is located in the 100-K Area, on the east side of the 105-KW Reactor Building and adjacent to the reactor exhaust stack. The underground diesel tanks were located between the stack and the 119-KW Building. Although the location description states the diesel tanks were located between the 105-KW exhaust stack and the 119-KW building, a sign is erroneously posted at the northwest corner of the 115 KW building that reads "130-KW-1 Diesel Tanks" This is further east and south of the reactor stack. There is no visual evidence that the tanks had been in either location.

Release Description: During the tank excavation, the site was found to be radioactively contaminated to a maximum of 400 counts per minute. The source and the extent of the contamination is unknown.

Related Sites/ Structures: The site is a duplicate of 130-KW-1.

Waste Type: Soil

Waste Description: The site contains radioactively contaminated soil.

This Site Was Consolidated With:

Code: 130-KW-1

Names: 130-KW-1; 130-KW-1A/130-KW-1B Tanks; 105-KW Emergency Diesel Fuel Tank; 105-KW Emergency Diesel Oil Storage Tank

Code: 126-K-1	Classification: Accepted
Names: 126-K-1; 100-K Gravel Pit	Reclassification Rejected (4/29/2009)
Type: Inert/Demolition Landfill	Start Date: 1/1/1975
Status: Inactive	End Date:

Description: The site has been reclassified to rejected. The debris disposed was of an inert/demolition type not regulated under CERCLA. The site status was changed to inactive since the gravel pit is not in use.

This unit is a gravel borrow pit that resulted from 100-K Area construction. The slope of the southwest corner contains demolition waste. This area is covered with pit run backfill material. The bottom contains one layer approximately 1.5-meter (5-foot) thick of demolition and inert waste covered with approximately 0.3 meters (1 foot) of pit run backfill material. Approximately 80% of this unit is unused.

Location: The western perimeter of this unit is located approximately 191 meters (625 feet) east of the 100-K Area's east perimeter fence and borders the eastern perimeter of the 118-K-1 Burial Ground.

Waste Type: Demolition and Inert Waste

Waste Description: The unit contains demolition and inert waste from the 100-K Area, the Near Surface Test Facility (NSTF) at Gable Mountain, and the Exploratory Shaft (ES) Site. Waste consists primarily of concrete, wood, steel pipe, structural steel, conduit, and wire.

Code: 130-K-1	Classification: Not Accepted
Names: 130-K-1; 1717-K Gasoline Storage Tank	Reclassification None
Type: Storage Tank	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1972

Description: The site was an underground gasoline storage tank oriented with the long axis of the tank in an east-west direction. The tank was excavated in July 1989. A 6.4 centimeters (2.5 inches) pipeline connected the tank to the building. The tank was emptied and rinsed with water when the facilities were deactivated in 1971. The concrete pad over the top of the tanks was removed in July, 1989. This allowed Pacific Northwest Laboratories to return to the tank site and perform Ground Penetrating Radar (GPR) to aid in locating the tank without the interference caused by the rebar in the concrete. The tank was excavated in July 1989. The soil around where the tanks had been located was sampled, the results analyzed, and the site backfilled to match the surrounding grade.

Location: The site was located approximately 3.7 meters (12 feet) north of the 1717-K, Maintenance and Transportation Service Building and 10.7 meters (35 feet) from the northwest corner of this building.

Related Sites/ Structures: The site was related to the 1717-K, Maintenance and Transportation Service Building.

Waste Type: Oil

Waste Description: The unit was used for storage of gasoline (product).

Code: 130-K-3	Classification: Not Accepted
Names: 130-K-3; 130-K-3A and 130-K-3B; 182-K Emergency Diesel Oil Storage Tank	Reclassification: None
Type: Storage Tank	Start Date: 1/1/1961
Status: Inactive	End Date: 1/1/1970

Description: The unit consisted of two steel underground diesel oil storage tanks. The tanks were excavated and removed on April 13, 1993. The tanks were used to supply diesel fuel to three engines located within the 182-K (Emergency Water Pump House). The engines ran emergency pumps used to provide backup cooling water for the 105-KE and 105-KW Reactors.

The tanks were covered by a bermed mound of soil with the top of the mound 1.5 meters (5 feet) above grade level. The top of each tank was 1.2 meters (3.5 feet) above grade and covered by 0.46 meters (1.5 feet) of the soil berm. A 0.7 meters (2 feet) diameter manway (0.64 centimeters [0.25 inches] thick bolted steel plate cover) was located in the center of each tank. All piping associated with the tanks utilized welded joints with no threaded couplings. The piping and conduit associated with each tank was: 3 fuel oil pipelines -- 3.2 centimeters (1.25 inches) outside diameter by 3.7 meters approximately (12 feet) to the building; 1 fuel oil return pipeline -- 0.64 centimeters (3 inches) outside diameter by approximately 4.6 meters (15 feet) to the building (empty during normal operation); 1 centrifuge fuel oil pipeline -- 3.2 centimeters (1.25 inches) outside diameter by approximately 9.1 meters (30 feet) to the building; 1 vent pipeline - 0.64 centimeters (3 inches) outside diameter by approximately 6.1 meters (20 feet) (including above ground components); 1 vertical fill pipeline connection -- 10.2 centimeters (4 inches) outside diameter by 15.2 centimeters (6 inches) tall (empty during normal operation); 1 fuel oil cross tie pipeline -- 7.6 centimeters (3 inches) outside diameter by approximately 3.05 meters (10 feet) long (empty during normal operation); 1 fuel level indicator conduit -- electrical and did not contain product.

There was no history of repairs made to these tanks.

In about 1970, the tanks were pumped empty of product and abandoned.

The tanks were excavated on April 13, 1993 following the Site Assessment Process. The soil around where the tanks had been located was sampled, the results analyzed, and the site was backfilled to match the surrounding grade.

Location: The tanks were located (5 feet) north of the north wall of the 182-K, Emergency Water Pump House. They were 1.5 meters (5 feet) apart.

Release Description: Prior to the removal of these tanks, there were no known leaks (unplanned releases) associated with the them.

Related Sites/ Structures: The site was related to the 182-K Emergency Water Pump House (Coolant Backup System).

Waste Type: Oil

Waste Description: The two tanks were used for storage of diesel oil (product).

Code: 1607-K4	Classification: Accepted
Names: 1607-K4; 1607-K4 Sanitary Sewer System; 1607-K4 Septic Tank; 1607-K4 Septic Tank and Associated Drain Field; 124-K-2	Reclassification: Closed Out (3/5/2001)

Type: Septic Tank **Start Date:** 1/1/1955

Status: Inactive **End Date:**

Description: The sanitary sewer system was properly abandoned and Closed Out in 1999. It is composed of a septic tank, two leaching trenches and associated piping. The septic tank and dosing chamber are composed of reinforced concrete per Hanford Standard E-5-11. There is a maximum of 1.5 meters (5 feet) of fill on the cover slab. There are 149 meters (150 + 238 + 102 feet) of 20 centimeter (8 inches) vitrified clay pipe to the septic tank, followed by 6.1 meters (20 feet) of 15 centimeter (6 inches) vitrified clay pipe to the larger leaching trench. There are an additional 68 meters (122 + 102 feet) of 15 centimeter (6 inches) of vitrified pipe connecting 1717-K to the system. The leaching trench contains 128 meters (420 feet) of 15 centimeters (6 inches) vitrified clay pipe laid with open joints. The second leaching trench is connected directly to the system piping with 6.1 meters (20 feet) of vitrified piping. The piping within the leach trench is a single 9.1 meters (30 feet) of vitrified piping. (also see 100-K-103)

Location: The system is north and northeast of 1704-K and 1717-K buildings.

Related Sites/ Structures: 100-K-103 contains components of this septic system that may not have been addressed with the 1999 sewer abandonment. The system serviced 1704-K (Offices) and 1717-K (Maintenance Shop) buildings.

Waste Type: Sanitary Sewage

Waste Description: This unit received sanitary sewage from the 1704-K Office Building and the 1717-K Maintenance Shop.

Closure Info: Final: The septic system was abandoned in 1999 per the requirements of Washington Administrative Code 246-272-1851. All septage inside the tank was removed and the empty tank was filled to eliminate void spaces. The septic system lids were left in place, in accordance with an agreement with the Washington Department of Health. The reclassification is documented on form 99-103.

Code: 126-KE-3 **Classification:** Not Accepted

Names: 126-KE-3; 183-KE Liquid Alum Storage Tank #1 **Reclassification:** None

Type: Storage Tank **Start Date:** 1/1/1955

Status: Inactive **End Date:** 1/1/1997

Description: The site was an above ground vertical stainless steel storage tank mounted on a concrete base. The tank has been removed and disposed at ERDF. This tank is no longer in existence. The tank was part of a system called the Liquid Alum System that supplied liquid alum for water treatment. The liquid was supplied either by rail car or tank truck, as both connections are shown on the Liquid Alum System diagram in HW-24800-103. The piping and instrument identification diagram, H-1-1652, shows the pipelines, valves, and instrumentation related to the tank.

Location: The site was the eastern-most of two alum storage tanks located approximately 10.7 meters (35 feet) south of the southwest corner of the 183-KE Head House and 10.7 meters (35 feet) south of the 183-KE Chlorine Vault.

Related Sites/ Structures: The tank was associated with the 183-KE Head House. The head house was the water quality center for the entire water treatment plant. In it were the facilities for metering raw water, for chemical injection into raw, filtered, and process water, and for effluent and influent control throughout the filter plant.

Process Description: Alum was used as a coagulant in water treatment. During the season of water high turbidity activated silica was added to aid in coagulation. Alum was fed from the storage tank and proportioned directly into the raw water line. The proportioning pump was paced by the flow of raw water in its 91-centimeter (36-inch) raw water pipeline and fed at 30 parts per million (ppm) at a maximum flow rate of 121,000 liters/minute (32,000 gallons/minute). During the winter, the liquid alum was pumped through heat exchangers for purpose of heating and agitating the chemicals.

Waste Type: Chemicals

Waste Description: The unit was used for storage of liquid alum (aluminum sulfate). Material Safety Data Sheet (MSDS) #040407 lists aluminum sulfate as an EPA hazardous substance. It is believed that this tank has been cleaned out.

Code: 100-N-7 **Classification:** Not Accepted

Names: 100-N-7; 182-N Facility Liquid Unplanned Release (Remediated) **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1987

Status: Inactive **End Date:** 1/1/1987

Description: The release site consists of a concrete flume on the river bank that extends into the river. The release at this site was approximately 19 liters (5 gallon) of oil that was mixed with a continuous permitted water discharge. The oil was dispersed into the river with the rest of the permitted discharge from the flume. The flume is currently dry and there is no evidence of the release.

Location: The site is located on the Columbia River upstream of the 181-N Building, and extends from the 182-N Tank Farm into the river.

Release Description: On February 6, 1987, approximately 19 liters (5 gallons) of turbine oil was discharged to the Columbia River through the 182N tank farm raw water return line. A small (pin hole size) leak in a lube oil line in the No. 2 drive turbine allowed oil to enter the secondary steam system. Steam condensate from this system returns to the 100-N steam condensate system that drains to the river. The leak in the lube line was repaired.

Related Sites/Structures: This site is related to the 182-N Tank Farm Overflow Outfall (NPDES Permit Outfall #005).

Waste Type: Oil

Waste Description:

Code: 100-N-8 **Classification:** Accepted

Names: 100-N-8; 108-N CUF; 108-N Facility **Reclassification:** Rejected (9/11/2000)

Type: Loading Dock **Start Date:** 1/1/1963

Status: Inactive **End Date:** 1/1/1990

Description: The 108-N Chemical Unloading Facility (CUF) was designed to remove liquids from railroad cars. The 108-N Building, metal structure used to offload chemicals, tank foundations, and tank pit are part of this site and remain at the location. The ground surface around these facilities is graveled.

Location: The 108-N CUF is located within the 100-N Exclusion Area perimeter fence near the southeast corner, and east of the 116-N-8, less than 90-day storage pad.

Related Sites/ Structures: The 120-N-5 Acid/Caustic Transfer Trench and Neutralization Unit, the 120-N-6 Sulfuric Acid Tank french drains, and the 120-N-7 Unloading Station french drain are associated with the unit.

Process Description: The unit was used for offloading, storage and transfer of 93% sulfuric acid and 50% sodium hydroxide solutions received by railroad car or tank truck. The 120-N-7 Unloading Station french drain was used for containment of small releases from the overhead transfer boom during offloading from railcar or truck. The facility had three 38,000 liter (10,000 gallon) above ground steel sulfuric acid tanks and one 290,000 liter (76,800 gallon) sodium hydroxide tank. Adjacent to the sulfuric acid tanks are five 120-N-6 sulfuric acid french drains where tank overflows were vented. The french drains are 0.6 meter (2 feet) in diameter and consist of a clay pipe packed with lime. The acid transfer system used a 3,800 liter (1,000 gallon) steel transfer tank located in a pit west of the 108-N Building. The tank filled with acid via gravity flow from the storage tanks. Air pressure was used to transfer acid by way of piping through the trench to the 163-N Day Tank. There are no french drains associated with the sodium hydroxide tank. Transfer pumps in the 108-N Building transferred the sodium hydroxide directly to the 163-N Day Tank from the storage tank.

Waste Type: Chemicals

Waste Description: The site received 93% sulfuric acid, and 50% sodium hydroxide solutions.

Code: 100-N-9	Classification: Accepted
Names: 100-N-9; 120-N-5 Facility Liquid Unplanned Release 1 (08/07/87)	Reclassification: Rejected (9/11/2000)
Type: Unplanned Release	Start Date: 1/1/1987
Status: Inactive	End Date: 1/1/1987

Description: The site is an unplanned release of sulfuric acid that occurred on the north side of 163-N. There is no remaining evidence of the spill at the site.

Location: The release site is located outside the 163-N north wall near sump number 1 (H-1-29204).

Release Description: On August 7, 1987, sulfuric acid was found leaking outside of the 163-N Plant extending to an area of the 120-N-5 Transfer Trench that had not yet been treated with a polymer coating. The acid had corroded away the exposed concrete, and some of the liquid may have reached the soil. The extent of the release is unknown.

Related Sites/ Structures: The 120-N-5 Acid Caustic Transfer Line is associated with the site.

Waste Type: Chemical Release

Waste Description: The unplanned release was sulfuric acid.

Code: 100-N-10	Classification: Accepted
Names: 100-N-10; 120-N-5 Facility Liquid Unplanned Release 2 (09/02/87)	Reclassification: Rejected (9/11/2000)
Type: Unplanned Release	Start Date: 1/1/1987

Status: Inactive **End Date:** 1/1/1987

Description: The release occurred at the 120-N-5 Acid/Caustic Transfer Trench. There is no remaining evidence of the spill at the concrete-lined trench.

Location: The site is located within the 120-N-5 Acid/Caustic Transfer Trench. The transfer trench is a polymer lined concrete trench located between the 108-N Chemical Unloading Facility and the 163-N Demineralization Plant.

Release Description: On September 2, 1987 a leak was noted in the piping during a caustic transfer from the 108-N Storage Tank to the 163-N Caustic Day Tank. The caustic collected in the 120-N-5 Transfer Trench. When the leak was noticed, the transfer was stopped and the pipeline was repaired. There is no documentation to indicate the caustic reached the soil.

Related Sites/Structures: This site is related to the 108-N Chemical Unloading Facility, 163-N Demineralization Plant, and the 120-N-5 Acid/Caustic Transfer Trench.

Waste Type: Chemical Release

Waste Description: The site received caustic sodium hydroxide.

Code: 100-N-11 **Classification:** Accepted

Names: 100-N-11; 120-N-5 Transfer Trench Liquid Unplanned Release 3 **Reclassification:** Rejected (9/11/2000)

Type: Unplanned Release **Start Date:** 1/1/1987

Status: Inactive **End Date:** 1/1/1987

Description: The site is the soil adjacent to 120-N-5, a concrete-lined neutralization pit and acid/caustic transfer trench. There is no remaining evidence of the spill at the site.

Location: The site is located at the 120-N-5 Transfer Trench, south of the 163-N Building and northwest of the 108-N building, at the 90 degree bend in the transfer trench.

Release Description: On November 9, 1987 a leak of approximately 760 liters (200 gallons) of sulfuric acid occurred during a transfer from the 108-N Storage Tank to the 163-N Facility. On December 4, 1987, it was noticed that the trench was open to the soil at the location where the leak occurred. This open area was found to be a dry well installed in 1986 during upgrading of the trench. The dry well was installed for steam trap drainage, not for containment of acid spills. An estimated 57 to 114 liters (15 to 30 gallons) of sulfuric acid was released to the ground.

Related Sites/Structures: The 120-N-5 Transfer Trench is associated with the release.

Waste Type: Chemical Release

Waste Description: The site received an estimated 57 to 114 liters (15 to 30 gallons) of sulfuric acid.

Code: 100-N-12 **Classification:** Not Accepted

Names: 100-N-12; 166-N / 184-N Pipelines Liquid Unplanned Release 1 (10/14/87 Cleaned Up) **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1987

Status: Inactive **End Date:** 1/1/1987

Description: The site is a leak of fuel oil found contained in a drain trench, inside the 184-N Facility. The oil was absorbed and the trench cleaned up immediately. The Auxiliary Operations Supervisor for N-Reactor at the time stated the spill did not reach the drain at the far end of the trench.

Location: The spill occurred inside the 184-N Building and accumulated in a drain trench.

Release Description: This spill was included in the 100-NR-1 Work Plan (DOE/RL-90-22 Draft E) and the 100-N Technical Baseline Report (WHC-SD-EN-TI-251). The work plan says "an unknown amount of fuel oil leaked from a loose pipe fitting at the 184-N Annex. Oil was being transferred from the day tank to the No. 2 Boiler. The oil was contained in the 184-N Annex drain trench and cleaned up.

As part of the WIDS site investigation in 1994, an interview was conducted with the former Auxiliary Operations Supervisor and remembered this particular spill. He said it was a very small spill contained within the trench and did not reach the drain at the far end of the trench. According to Fact Sheet No. 100N-87-95 the spill was cleaned up, and the probable cause listed as: "The most likely cause is the coupling was loosened to perform work on the transmitter, and upon recognizing that the transmitter was not isolated, an attempt was made to retighten the coupling." The spill date was October 14, 1987.

Related Sites/ Structures: The spill occurred in the 184-N annex building.

Waste Type: Oil

Waste Description:

Code: 100-N-19 **Classification:** Accepted

Names: 100-N-19; HGP Construction Debris Dump Solid Waste Site; SWMU #11 **Reclassification:** Rejected (6/30/2004)

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The site is a large area consisting of a series of pits and depressions containing soil, rock, concrete, metal, wood, and asphalt that have been dumped in the area over time. The site is relatively long [more than 1000 meters (3000 feet) long] and narrow [about 150 meters (500 feet) wide] in shape.

Location: The Hanford Generating Plant (HGP) Construction Debris Dump is located south and east of the Bonneville Power Administration (BPA) Hanford Substation along a dirt road.

Related Sites/ Structures: The site is associated with 600-32 and 100-N-39 which are duplicate codes for the same site, a dumping area contained within the larger 100-N-19 Dumping Area.

Process Description: The site was used to dispose of non hazardous construction debris from 100-N and the Hanford Generating Plant.

Waste Type: Construction Debris

Waste Description: The site contains mounds of soil, rock, concrete, metal, wood, and asphalt that have been dumped in the area.

Code: 100-N-21 **Classification:** Accepted

Names: 100-N-21; 1143-N Blast Yard; Blast Yard Solid **Reclassification:** Rejected (9/11/2000)

Waste Site

Type: Dumping Area**Start Date:****Status:** Inactive**End Date:****Description:** The area has thin, scattered patches of red garnet sandblasting material. Paint chips, reported in 1994 as being mixed in with the garnet (Cote 1994), are no longer visible. The site is in use as a parking lot.**Location:** The site is located in the southeast portion of the 100-N Area, southwest of MO-535 and MO-229 and east-southeast of the 1143-N Paint Shop.**Related Sites/
Structures:** The 1143-N Paint Shop is related to this site.**Process
Description:** The garnet was used to sandblast non-contaminated equipment prior to painting.**Waste Type:** Soil**Waste
Description:** The area has scattered patches of red garnet sandblasting material.**Code:** 100-N-27**Classification:** Accepted**Names:** 100-N-27; 108-N Neutralization Pit; 108-N Sump **Reclassification** Rejected (9/11/2000)**Type:** Sump**Start Date:** 1/1/1963**Status:** Inactive**End Date:** 1/1/1990**Description:** The acid neutralization pit is constructed of concrete with a brick lining, and is covered with a steel lid.**Location:** The unit is located west of the 108-N Building.**Release
Description:** No known leaks occurred in the system.**Related Sites/
Structures:** This facility received drainage from the 108-N floor drains and from the acid transfer tank. Neutralized waste was sent from the 108-N Neutralization Unit by the water jet pump to the 183-N Facility where it was then discharged to the river through the 259-centimeter (102 inch) outfall line.**Process
Description:** The pit was used to manually neutralize waste acid. This site received drainage from the 108-N floor drains and from the acid transfer tank. The neutralized waste was sent via a water jet pump to the 183-N facility where it was then discharged to the river through the 260 centimeter (102 inch) outfall line. Sufficient quantities of 50% sodium hydroxide were used to neutralize the 93% sulfuric acid waste. The brick lining was replaced at least once.**Waste Type:** Chemicals**Waste
Description:** The pit was used to neutralize waste sulfuric acid before eventual release to the river. Chemicals received by the pit included 93% sulfuric acid and 50% sodium hydroxide.**Code:** 100-N-39**Classification:** Accepted**Names:** 100-N-39; Hanford Substation Construction Dump Area; SWMU #11 **Reclassification** Rejected (7/14/2005)

Type: Dumping Area**Start Date:****Status:** Inactive**End Date:****Description:** This site should be rejected because it is a duplicate of 600-32 and contained within the larger dumping area 100-N-19. There is no similar dump near the area originally mapped (in Arcview) as the site location, inside the BPA Substation fence.

The site is a construction dump with evidence of burning activity. The Hanford Generating Plant RCRA Facility Assessment Report states "The site is a large, irregular shaped burn pit and a large borrow pit covering 5 to 10 acres. The site contains large blocks of concrete and miscellaneous debris."

Location: The site is approximately 305 meters (1000 feet) south of the Hanford Generating Plant property fence.**Related Sites/ Structures:** This site is a duplicate of 600-32 and 100-N-19.**Waste Type:** Construction Debris**Waste Description:** The waste includes construction debris and combustible construction waste that was burned.

The site contains large blocks of concrete, miscellaneous debris, one empty drum and one pile of sand blast grit

This Site Was Consolidated With:**Code:** 600-32**Names:** 600-32; N Area Landfill

Code: 100-N-40**Classification:** Accepted**Names:** 100-N-40; Unplanned Release at 108-N**Reclassification:** Rejected (9/11/2000)**Type:** Unplanned Release**Start Date:** 1/1/1987**Status:** Inactive**End Date:** 1/1/1987**Description:** The site is a graveled field at the 108-N Chemical Unloading Facility.**Location:** The site is located at the railcar unloading station at the 100-N-8 (108-N Chemical Unloading Facility) and 120-N-6.**Release Description:** Approximately 38 liters (10 gallons) of sodium hydroxide was spilled to the ground on December 26, 1987. Difficulties during the transfer of sodium hydroxide from a rail car to the caustic storage tank prompted the operator to disconnect the transfer line and set it on the ground.**Related Sites/ Structures:** This release occurred at the 100-N-8 (108-N) Chemical Unloading Facility.**Waste Type:** Chemical Release**Waste Description:** The waste is sodium hydroxide spilled to the ground.**Description:**

Code: 100-N-56**Classification:** Accepted**Names:** 100-N-56; 181-N Building Drywell**Reclassification:** Rejected (9/11/2000)**Type:** French Drain**Start Date:**

Status: Inactive

End Date:

Description: The drywell is not visible from ground surface and is apparently located underground. The drywell, judging by the site drawing, is adjacent to the fenceline north of the 181-N Building. The ground surface is graveled. Another drywell, 100-N-73 (Miscellaneous Stream 395) is in this area, but it drains a parking lot north of the 107-N Building via a concrete trench.

Location: The site is located in the 100-N Area, north of the 181-N Building and between the double security exclusion area fences.

Related Sites/ Structures: The 181-N Building is associated with this waste site.

Process Description: The site received waste water from the 181-N River Pumphouse Building. According to Don Eckert of 100-N Operations, only river water entered the pipeline leading to the drywell.

Waste Type: Water

Waste Description: River water from inside the 181-N Pumphouse is the only source of waste water to this site.

Code: 100-N-69

Classification: Not Accepted

Names: 100-N-69; 105-NB Stormwater Injection Well; Miscellaneous Stream #801

Reclassification: None

Type: Injection/Reverse Well

Start Date:

Status: Inactive

End Date:

Description: The injection well was properly decommissioned in 2007. It was filled with concrete and can no longer receive stormwater runoff.

The site was covered with a 0.56 meter (1.8 foot) diameter steel grate and is 2.56 meters (8.4 feet) deep. The drywell was constructed of concrete. The site appears to have drained stormwater that accumulated at a low point and from roof drains on the 105-NB building. Flow rates to the drain were estimated to be less than 19 liters (5 gallons) per minute. No contaminated areas were observed at the time of the inspection.

Location: The site is located 5.4 meters (18 feet) north of the 105-NB north entrance door.

Related Sites/ Structures: The site is associated with 105-NB building.

Waste Type: Stormwater Runoff

Waste Description: This site receives less than 19 liters (5 gallons) per minute of stormwater only.

Code: 100-N-70

Classification: Not Accepted

Names: 100-N-70; 1705-N Stormwater Injection Well; Miscellaneous Stream #802

Reclassification: None

Type: Injection/Reverse Well

Start Date:

Status: Inactive

End Date:

Description: The site was backfilled and capped with asphalt in January 2006. It had been covered with a 1

meter (3.3 foot) diameter steel grate at grade level and is constructed of concrete. The site was filled with gravel and is located in a depression. The site appeared to be a drain for stormwater that collects in a depression from the surrounding area and the roof of 1705-N. The flow rates to the site is estimated to be less than 19 liters (5 gallons) per minute. No contaminated areas were observed at the time of the inspection.

Location: The site was located between 1705-N Building and the northwest corner of the 1714-NA Building.

Related Sites/ Structures: This site drained stormwater from the 1705-N Building.

Waste Type: Stormwater Runoff

Waste Description: This site received less than 19 liters (5 gallons) per minute of stormwater runoff only.

Code: 100-N-71 **Classification:** Not Accepted

Names: 100-N-71; Project 4546.010; 100-N Sewer System **Reclassification:** None

Type: Septic Tank **Start Date:**

Status: Unknown **End Date:**

Description: This site was added to WIDS before the septic system was built; subsequently the project has been cancelled because of lack of funds (per Nolan Draper).

Location: Original planned location (not built): One Type II septic tank is located south of 1310-N. Two Type I septic tanks are located southeast of 1120-N. The new drain field is located east of 1120-N. A pipeline connects the parts of the system.

Process Description: System as designed (not built): The Type II septic tank measures 3.6 meters by 2.4 meters (12 feet by 8 feet). The Type I septic tanks measure 2.4 meters by 1.8 meters (8 feet by 6 feet). The new drain field measures 52.7 meters by 51.2 meters (173 feet by 168 feet). The total length of the associated piping is approximately 305 meters (1000 feet). The pipeline was to be routed from Lift Station #3 (south of 1310-N) to Manhole #5 (southwest of 1120-N) and to the new drain field (east of 1120-N).

Code: 100-N-72 **Classification:** Not Accepted

Names: 100-N-72; 107-N Building East Area Stormwater Runoff; Miscellaneous Stream #396 **Reclassification:** None

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:**

Description: The site is a concrete french drain, about 0.5 meters (1.5 feet) in diameter, with an open metal grate cover. The bottom is about 0.3 meters (1 foot) deep, and only sand and cobbles are visible. A concrete trench, about 18 meters (60 feet) long, drains the paved and graveled area north of the 107-N Building and empties into this french drain. The trench prevents stormwater from flowing to the west, and down a steep slope in the area fenced for security exclusion. The area is posted with underground radioactive materials (URM) signs, like most of the 100-N Area. This french drain receives stormwater only, however.

Location: This stormwater runoff is in the area east of the 107-N Building.

Process Description: This Miscellaneous Stream is stormwater runoff.

Waste Type: Stormwater Runoff

Waste Description:

Code: 100-N-73 **Classification:** Not Accepted

Names: 100-N-73; 107-N Building West Area Stormwater Runoff; Miscellaneous Stream #395 **Reclassification:** None

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:**

Description: The drain is a concrete structure with a steel lid, fed by a concrete trough running from north of the 107-N Building, along the base of the security fence.

Location: This Miscellaneous Stream is a drywell on the north side of the 181-N Pumphouse.

Related Sites/Structures: This drywell drains the security exclusion area from north of the 107-N Building south to the french drain.

Process Description: This Miscellaneous Stream drains stormwater from the area north and west of the 107-N Building and flows via a concrete trench to a drywell on the north side of the 181-N Pumphouse. It is designed to prevent erosion on the river bank that could otherwise be caused by stormwater.

Waste Type: Stormwater Runoff

Waste Description:

Code: 100-N-74 **Classification:** Accepted

Names: 100-N-74; 183-N Building Fire System Drain; Miscellaneous Stream #492 **Reclassification:** Rejected (9/11/2000)

Type: Injection/Reverse Well **Start Date:**

Status: Active **End Date:**

Description: The site is in a graveled lot on the north side of the 183-N Building. A fire system relief valve (site 100-N-75) extends about 1 meter (3 feet) above the ground, and is surrounded by six steel barrier poles to protect it from vehicles. Two metal 10 centimeter (4 inch) pipes with handles for turning valves are next to the relief valve, but no pit is visible.

Location: The Miscellaneous Stream is in a valve pit on the north side of the 183-N Building.

Related Sites/Structures: The Miscellaneous Stream is for the 183-N Building fire system.

Process Description: When fire system piping is opened at the valve pit for repair, untreated water from the Columbia River (via the Hanford Site export water system) drains from pipes into the pit.

Waste Type: Water

**Waste
Description:**

Code: 100-N-75	Classification: Accepted
Names: 100-N-75; 183-N Building Fire System Relief Valve; Miscellaneous Stream #493	Reclassification Rejected (9/11/2000)
Type: French Drain	Start Date:
Status: Active	End Date:

Description: The relief valve is visible in a large graveled area north of the 183-N Building. It is surrounded by 6 metal posts that protect it from vehicles. The relief valve is just under 1 meter (3 feet) high, and painted red. The entire area is marked "Underground Radioactive Materials."

Location: This Miscellaneous Stream is north of the 183-N Building, adjacent to the valve pit.

Process Description: This stream is a relief valve that releases during upset conditions in the plant fire system. Released water flows into a container, and overflows onto the ground. The water is from the Columbia River, via the Hanford Site export water line.

Waste Type: Water

**Waste
Description:**

Code: 100-N-76	Classification: Accepted
Names: 100-N-76; 181-N Pumphouse French Drains	Reclassification Rejected (4/12/2004)
Type: French Drain	Start Date:
Status: Inactive	End Date: 1/1/2001

Description: The two french drains were plugged with grout and can no longer receive steam condensate or stormwater drainage. The drains were plugged with grout on June 13, 2001. The french drains were connected to each other underground, and provided steam condensate and stormwater drainage just east of the 181-N Pumphouse. These drains are believed to have been built to receive steam condensate blowdown. However, when the steam line was removed the drains were left behind, and drained excess stormwater.

Both drains are about 46 centimeters (18 inches) in diameter and constructed of concrete. A 10 centimeter (4 inch) pipe connects them; this pipe is about 20 centimeters below the lip in the southern drain and about 1 meter (3 feet) below the lip of the northern drain. Because the northern drain is noticeable higher than the southern drain, it is difficult to tell if the pipe is level or drains preferentially toward either side. The drains are about 16 meters (52 feet) apart.

Location: The drains are on the east side of the paved and graveled road that is east of the 181-N Pumphouse.

Process Description: These drains originally were built to drain steam condensate, but later drained excess stormwater.

Waste Type: Steam Condensate

**Waste
Description:**

Code: 116-N-8 **Classification:** Accepted

Names: 116-N-8; 116-N-8 Storage Pad; 1330-N; 163-N Mixed Waste and Hazardous Waste Container Storage Pad **Reclassification** Rejected (9/6/2000)

Type: Storage Pad (<90 day) **Start Date:** 12/1/1986

Status: Inactive **End Date:**

Description: The site status was changed to inactive since the hazardous materials were removed and the above-grade structure and concrete pad were demolished in June 2008 (per document D4-100N-0018).

Containers were stored on a curbed and fenced concrete pad. The pad was covered by an open metal shed, divided into three storage areas each with its own locked gate. The entire unit was approximately 45 by 18 meters (150 by 60 feet). A small cabinet in front held personal protective equipment and spill response materials. The front of the unit was an asphalt parking/driving area; the sides and back were gravel.

Location: The site is located south of the 163-N Building.

Release Description: No spills have been recorded at this site. No stains are visible on the concrete.

Waste Type: Soil

Waste Description: This site receives radioactively contaminated oil and miscellaneous hazardous process chemicals in drums and containers. The amounts received are variable based on operations.

Code: 120-N-5 **Classification:** Accepted

Names: 120-N-5; 108-N/163-N Transfer Line and Neutralization Pit **Reclassification** Rejected (9/11/2000)

Type: Product Piping **Start Date:** 1/1/1963

Status: Inactive **End Date:** 1/1/1990

Description: The Transfer Line and Neutralization Pit is a 220-meter (720-foot) long polymer lined concrete pipe trench (encasement) that contains two transfer lines that run between the 108-N and the 163-N Buildings. The trench has concrete bottom and sides and a metal plate cover. The enclosed lines are one 6.4-centimeter (2.5-inch) sodium hydroxide line and one 10.2-centimeter (4-inch) sulfuric acid line. The trench runs 50 meters (154 feet) south from the 163-N Building to a neutralization pit, east for 132 meters (433 feet), and then north for 26 meters (85 feet) to the 108-N Building. The 1.22-meter (4-foot) by 3.05-meter (10-foot) concrete neutralization pit, located at coordinates N149307 and E571120, is designed to receive waste spills from within the encasement. Its upper surface is a few inches above grade. The neutralization pit has two 61-centimeter (24-inch) steel manhole covers, one marked "acid" and the other "caustic", that provide pit access. DOE/RL-90-22 describes its internal dimensions as two vaults, each measuring 1.8 by 1.8 by 3.1 meters (6 by 6 by 10 feet) deep.

Location: The site is a pipe trench that is located between the 108-N and the 163-N Buildings.

Release Description: See UPR-100-N-34, 108-N Tank Transfer, Sulfuric Acid Line Break; UPR-100-N-15, 108-N Neutralization Sump Spill; 100-N-9, 120-N-5 Facility Liquid Unplanned Release 1 (08/07/87); 100-N-10, 120-N-5 Facility Liquid Unplanned Release 2 (09/02/87); 100-N-11, 120-N-5 Transfer Trench Liquid Unplanned Release 3.

Related Sites/ Structures: The piping was used to transfer acids and caustics from the 108-N Chemical Unloading Facility to the 163-N Demineralization Plant.

Process Description: The site transfers sulfuric acid and sodium hydroxide from the 108-N Chemical Unloading Facility to the 163-N Water Demineralization Plant for use in water treatment.

Waste Type: Chemicals

Waste Description: The unit transferred sodium hydroxide and sulfuric acid reagents from a chemical unloading facility to the point-of-use at the 163-N Demineralization Plant via transfer pipes contained in a concrete trench. Several leaks to the soil resulted from corrosion of the transfer pipes and concrete trench by the concentrated solutions.

Code: 120-N-6

Classification: Accepted

Names: 120-N-6; 108-N Acid Tank Vent French Drains

Reclassification: Rejected (9/11/2000)

Type: French Drain

Start Date: 1/1/1963

Status: Inactive

End Date: 1/1/1988

Description: This site consisted of five french drains which were removed in 1988. No evidence of the former french drains remains. The area is surrounded by posts, chain, and a sign stating "Controlled Area - Authorized Personnel Only" and "108-N/ WIDS Site 120-N-6".

Location: The site is located on the south side of the 108-N Building and south of the 105-N Reactor Building.

Release Description: Unknown quantities of sulfuric acid tank overflows and condensate were discharged to the drains. An unplanned release of an unknown quantity of soda ash (soda ash is purified sodium carbonate) sufficient to cover a 6.1 by 9.2-meter (20 by 30-foot) area occurred in 1981. Soda ash was used to neutralize acid spills. Hanford Drawings H-1-45007, Sheets 1,14, and 15, and H-1-29247 show the location of this release. Any remaining amounts of this material would have been removed with the french drains and the surrounding soil in 1988.

Process Description: Three french drains were designed to receive inadvertent overflows and condensate from the three sulfuric acid storage tanks located south of the 108-N Building. Two other french drains were designed to receive tank vent overflows and condensate from the transfer tank which was located in a concrete pit just west of the 108-N building. The drains were packed with limestone to neutralize the acid before entering the soil column.

Waste Type: Chemicals

Waste Description: The drains received unknown quantities of sulfuric acid overflows from the acid storage tanks and transfer lines in intermittent discharges. Each discharge is estimated to have averaged less than 3.8 liters (1 gallon) of liquid.

Code: 120-N-8

Classification: Accepted

Names: 120-N-8; 163-N Sulfuric Acid Tank Vent French Drain

Reclassification: Rejected (9/11/2000)

Type: French Drain

Start Date: 1/1/1963

Status: Inactive

End Date: 1/1/1988

Description: The french drain was removed in 1988 and the site has been covered with gravel. There is currently no evidence of the former french drain at the site.

Location: The site is located approximately 1 meter (3 feet) west of the west wall of the 163-N Building at

a point approximately 5 meters (16 feet) south of its northwest corner.

Release Description: The releases are described as intermittent small discharges of sulfuric acid from 163-N Demineralized Water Treatment Plant day storage tank. The average amount of each discharge is estimated to be less than 3.8 liters (1 gallon). There are no documented unplanned releases associated with the unit.

Related Sites/Structures: The drain received sulfuric acid from the 163-N Demineralized Water Treatment Plant sulfuric acid day storage tank.

Process Description: The unit is a french drain used to receive overflow of sulfuric acid from the 163-N demineralization plant sulfuric acid day tank. The unit was constructed of clay pipe filled with limestone to neutralize the sulfuric acid releases.

Waste Type: Chemicals

Waste Description: The unit received unknown amounts of sulfuric acid in intermittent discharges. Each discharge is estimated to have averaged less than 3.8 liters (1 gallon) of corrosive liquid.

Code: 124-N-5

Classification: Accepted

Names: 124-N-5; 124-N-5 Septic Tank; 1607-N5; 100-N Sanitary Sewer System No. 5

Reclassification: Rejected (9/11/2000)

Type: Septic Tank

Start Date: 1/1/1981

Status: Inactive

End Date: 1/1/1987

Description: The site is in the middle of a large graveled lot, free of vegetation. When the tank was deactivated, it was covered with a layer of parking lot gravel and is no longer visible.

Location: The unit is located south of 1115N (MO050) and west of 1135N (MO352).

Related Sites/Structures: This sewer system served office buildings 1111-N, 1116-N, 1117-N 1118-N, 1123-N 1124-N, and 1131-N.

Process Description: Untreated sanitary sewage enters the septic tank where the heavy solids settle to the bottom of the tank. The lighter solids, fats and greases partially decompose and rise to the surface and form a layer of scum. The solids that have settled to the bottom are attacked by bacteria and form sludge. The clear sewage then enters a system of properly sized and constructed narrow trenches partially filled with a bed of washed gravel or crushed stone into which perforated or open joint pipe is placed. The discharge from the septic tank is distributed through these pipes into trenches and surrounding soil.

Waste Type: Sanitary Sewage

Waste Description: This unit received approximately 14,000 liters/day (3,800 gallons/day) of sanitary sewage.

Code: 124-N-6

Classification: Accepted

Names: 124-N-6; 124-N-6 Septic Tank; 1607-N6; 100-N Sanitary Sewer System No. 6

Reclassification: Rejected (9/11/2000)

Type: Septic Tank

Start Date: 1/1/1979

Status: Inactive

End Date: 1/1/1987

Description: A site visit in July 1999 was unable to visually locate this site. The site was covered with parking lot gravel and the exact location cannot be visually identified.

Location: The unit is located south of the 1113-N Trailer.

Related Sites/ Structures: The septic system received sanitary sewage from office trailers 1113-N, 1114-N, and 1115-N. This septic system was directly hooked up to Sanitary Sewer System No.7, (124-N-7).

Process Description: Untreated sanitary sewage enters the septic tank where the heavy solids settle to the bottom of the tank. The lighter solids, fats and greases partially decompose and rise to the surface and form a layer of scum. The solids that have settled to the bottom are attacked by bacteria and form sludge. The clear sewage then enters a system of properly sized and constructed narrow trenches partially filled with a bed of washed gravel or crushed stone into which perforated or open joint pipe is placed. The discharge from the septic tank is distributed through these pipes into trenches and surrounding soil.

Waste Type: Sanitary Sewage

Waste Description: This unit received an unknown amount of sanitary sewage.

Code: 124-N-7 **Classification:** Accepted

Names: 124-N-7; 124-N-7 Septic Tank; 1607-N7; 100-N Sanitary Sewer System No. 7 **Reclassification:** Rejected (9/11/2000)

Type: Septic Tank **Start Date:** 1/1/1984

Status: Inactive **End Date:** 1/1/1987

Description: A site visit in July 1999 found a 0.61 meter (2 foot) diameter manhole and two 19.6 centimeter (8 inch) diameter access ports labeled "Sewer". No drain field was identified. However, the 100-N Facility Manager said (see Deford 1996 reference below) that when the tank was pumped and filled with sand, it was covered with a layer of parking lot gravel and can no longer be located.

Location: The unit is located southwest of the 1115-N Trailer.

Related Sites/ Structures: The system received sanitary sewage from office trailers 1103-N, 1104-N, and 1145-N and after modifications received sanitary sewage from 124-N-6 Sanitary Sewer System and the 1145-N Building.

Process Description: Untreated sanitary sewage enters the septic tank where the heavy solids settle to the bottom of the tank. The lighter solids, fats and greases partially decompose and rise to the surface and form a layer of scum. The solids that have settled to the bottom are attacked by bacteria and form sludge. The clear sewage then enters a system of properly sized and constructed narrow trenches partially filled with a bed of washed gravel or crushed stone into which perforated or open joint pipe is placed. The discharge from the septic tank is distributed through these pipes into trenches and surrounding soil.

Waste Type: Sanitary Sewage

Waste Description: This unit received approximately 19,700 liters/day (5,200 gallons/day) of sanitary sewage from office trailers.

Code: 124-N-8 **Classification:** Accepted

Names: 124-N-8; 124-N-8 Septic Tank; 1607-N8; 100-N Sanitary Sewer System No. 8 **Reclassification:** Rejected (9/11/2000)

Type: Septic Tank **Start Date:** 1/1/1983

Status: Inactive**End Date:** 1/1/1987

Description: A site visit in July 1999 found two concrete pads (0.6 meters by 0.6 meters [2 X 2 feet]) with 19.6 centimeter (8 inch) lids marked "Sewer" in the general location of this site. It is not known if one of the markers is from the old system (124-N-8) or the replacement sewage system (124-N-10).

Location: The unit is located southwest of 1135N (MO352).

Related Sites/ Structures: The system received sanitary sewage from office trailers 1132-N, 1133-N, 1134-N and 1135-N.

Process Description: Untreated sanitary sewage enters the septic tank where the heavy solids settle to the bottom of the tank. The lighter solids, fats and greases partially decompose and rise to the surface and form a layer of scum. The solids that have settled to the bottom are attacked by bacteria and form sludge. The clear sewage then enters a system of properly sized and constructed narrow trenches partially filled with a bed of washed gravel or crushed stone into which perforated or open joint pipe is placed. The discharge from the septic tank is distributed through these pipes into trenches and surrounding soil.

Waste Type: Sanitary Sewage

Waste Description: This unit received approximately 3,400 liters/day (900 gallons/day) of sanitary sewage from office trailers.

Code: 200 ETF**Classification:** Accepted**Names:** 200 ETF; 2025-E; 200 Area Effluent Treatment Facility (ETF)**Reclassification:** None**Type:** Process Unit/Plant**Start Date:** 1/1/1995**Status:** Active**End Date:**

Description: The Effluent Treatment Facility contains several tanks and process systems that make up the primary and secondary treatment trains for the treatment of dilute waste water generated at the Hanford Facility. The primary treatment train receives waste water in the surge tank, located outside the Effluent Treatment Facility Building on the south side. The secondary treatment train collects, concentrates, dries and packages the waste (generated by the primary treatment train systems) in lined steel containers.

Location: The Effluent Treatment Facility lies north of the Liquid Effluent Retention Facility an east of Canton Avenue in the 200 East Area.

Related Sites/ Structures: The Effluent Treatment Facility is associated with the 242-A Evaporator and the Liquid Effluent Retention Facility.

Process Description: Mixed waste stored in the double-shell tank system is transferred to the 242-A Evaporator, where the waste is concentrated through an evaporation process. The concentrated slurry waste is returned to the double-shell tank system, and the evaporated constituents are re-condensed, collected, and transferred to the Liquid Effluent Retention Facility until they are transferred to the Effluent Treatment Facility for additional treatment. The facility consists of a primary and a secondary treatment train. The primary treatment train removes or destroys dangerous and mixed waste components from the waste water. The primary treatment train consists of the following treatment operations: pH adjustment, filtration, ultraviolet oxidation, hydrogen peroxide decomposition, fine filtration, de-gasification, reverse osmosis, polishing (ion exchange column) and final pH adjustment and verification. The secondary treatment train processes the waste byproducts removed by the primary treatment train. The secondary waste

is dried to a powder, containerized and transferred to a mixed waste treatment, storage and/or disposal unit. The secondary treatment train includes the following treatment components: secondary waste receiving tanks, Effluent Treatment Facility Evaporator (forced circulation evaporator), concentrate tank, thin film dryer, container handling, and support systems. Treated effluent meets delisting requirements and is discharged as nondangerous waste to the State-Approved Land Disposal System.

Waste Type: Process Effluent

Waste Description: The unit treats process condensate containing small amounts of volatile and semivolatile organic constituents, inorganic constituents and radionuclides.

Code: 200-A TEDF **Classification:** Accepted

Names: 200-A TEDF; 216-E-43A and 216-E-43B; 600-145; TEDF Basin; 200 Area Treated Effluent Disposal Facility **Reclassification:** None

Type: Pond **Start Date:** 1/1/1995

Status: Active **End Date:**

Description: The 357 meter by 192 meter (1172 ft by 629 ft) fenced area contains two adjacent five acre gravel disposal basins and a metal sampling building (#6653). Pond B is north of Pond A. The 6653 metal sampling building is 4.2 meters by 6.1 meters (14 ft by 20 ft) and is located near the east fence line and gate.

Location: Pond A (216-E-43A - South Pond) and B (216-E-43B - North Pond) and 6653 are located about 660 meters east of 216-B-3C, which is east of and outside the 200 East security fence.

Related Sites/Structures: Liquid waste from seven Hanford facilities (Plutonium Finishing Plant, 222-S Complex, T-Plant Complex, 284-W Power Plant, PUREX Plant, B-Plant, and 242-A-81 Water Services Building) is transported via eleven miles of pipe to the two evaporation/infiltration ponds (Pond A and Pond B). There are two pumping stations associated with the pipeline (one in 200 E and one in 200 W). The pipeline is WIDS sitecode 600-291.

Process Description: Liquid waste from seven Hanford facilities (Plutonium Finishing Plant, 222-S Complex, T-Plant Complex, 284-W Power Plant, PUREX Plant, B-Plant, and 242-A-81 Water Services Building) is transported via eleven miles of pipe to the two evaporation/infiltration ponds (Pond A and Pond B). TEDF includes no treatment.

Waste Type: Water

Waste Description: Liquid waste is discharged to TEDF from the Plutonium Finishing Plant, 222-S Complex, T-Plant Complex, 284-W Power Plant, PUREX Plant, B-Plant, and 242-A-81 Water Services Building. Examples of waste include non-contact process cooling water, lab waste, steam condensate, air conditioning condensate, housekeeping water, outdoor sumps (rain water), reservoir overflow, boiler blowdown, sanitary sources (water softener, safety shower/eye wash, etc), floor drains, HVAC sanitary water, raw water, storm water, strainer backflush.

Code: 202-A HWSA **Classification:** Accepted

Names: 202-A HWSA; 202-A Hazardous Waste Storage Area **Reclassification:** Rejected (9/6/2000)

Type: Storage Pad (<90 day) **Start Date:** 1/1/1986

Status: Inactive **End Date:** 1/1/1996

Description: All remaining 90 day storage areas were removed when PUREX was closed down and cleaned to meet the deactivation end point criteria prior to transition from Westinghouse Hanford Co. to Bechtel Hanford Inc. (BHI).

Location: The site was located north of the 202-A Building and east of the 2714-A Chemical Warehouse in the 200-East Area.

Release Description: There were no known releases from this site.

Description:

Related Sites/ Structures: This pad was related to the PUREX facility.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: When this unit was active, typical wastes contained in the staging area over a 1-year period included approximately 1,000 kilograms (2,205 pounds) of flammable waste oils, 1,900 kilograms (4,190 pounds) of combustible waste oils, and 1,600 kilograms (3,530 pounds) of wastes unidentified prior to receipt of analysis.

Code: 202-A NU

Classification: Accepted

Names: 202-A NU; Elementary Neutralization Unit/202-A Building; PUREX; 202-A Neutralization Unit

Reclassification: Rejected (6/18/2014)

Type: Neutralization Tank

Start Date: 7/1/1986

Status: Active

End Date:

Description: The waste site has been evaluated and reclassified to Rejected. The site had been defined as an elementary neutralization unit, that was an "in-line" waste treatment process occurring inside the PUREX facility (202-A). Potassium hydroxide was added to the waste stream to reduce the pH before discharging to cribs, ponds or ditches.

TPA-MP-14, Rev. 2, Section 2.0 states that WIDS does not document buildings or facilities that do not contain TSD units. It further states that, after buildings are demolished, the footprint will be evaluated for potential soil contamination. If present, the soil contamination will be added to WIDS as a Discovery Site.

Location: The in-line neutralization process was located inside the PUREX (202-A) Building. A neutralization tank (WIDS sitecode 200-E-58) was placed underground, outside 202-A, near the 216-A-5 crib.

Related Sites/ Structures: The site is associated with 202-A, 216-A-5, 200-E-58 and 216-A-10.

Waste Type: Process Effluent

Waste Description: The system treats process condensate. A nominal flow $2.7E+05$ liters (72,000 gallons) per day, is neutralized in line from a pH of between 1 and 2 to a pH of approximately 4 by addition of potassium hydroxide. This stream then passes through a 26,500-liter (7,000-gallon) underground tank containing 27 metric tons (30 tons) of calcium carbonate rock (installed January 1987) for neutralization to a final pH of between 6 and 7. It is then discharged to the 216-A-45 Crib.

Code: 202-A-E-F11

Classification: Accepted

Names: 202-A-E-F11; 202-A-TK-E-F11; PUREX Tank E-F11

Reclassification: None

Type: Storage Tank **Start Date:** 1/15/1956
Status: Inactive **End Date:**

Description: The unit is a tank with a 9,840-liter (2,600-gallon) capacity.
Location: The tank is located in the PUREX Building.

Waste Type: Process Effluent

Waste Description: The unit contains ammoniacal (ammonia based) radioactive mixed waste (RMW) which is processed with sodium hydroxide (NaOH) and sodium nitrate (NaNO₃). Prior to September 1987, these wastes were sent to the 216-A-36B Crib. Currently, the waste is discharged to Tank G7 for neutralization.

Code: 202-A-E5 **Classification:** Accepted
Names: 202-A-E5; 202-A-TK-E5; PUREX Tank E5 **Reclassification:** None
Type: Neutralization Tank **Start Date:** 1/15/1956
Status: Inactive **End Date:**

Description: The unit has a 18,900-liter (5,000 gallon) capacity.
Location: The tank is located in the PUREX Building.

Waste Type: Process Effluent

Waste Description: The unit contains: 1) decladding wastes; 2) metathesis wastes; or 3) miscellaneous wastes including flushes with similar chemical makeups. Wastes are neutralized with sodium nitrate (NaNO₃) and potassium hydroxide (KOH) or sodium hydroxide (NaOH) before going to double-shell underground storage tanks.

Code: 202-A-F15 **Classification:** Accepted
Names: 202-A-F15; 202-A-TK-F15; PUREX Tank F-15 **Reclassification:** None
Type: Neutralization Tank **Start Date:** 1/15/1956
Status: Inactive **End Date:**

Description: The unit has a 18,900-liter (5,000-gallon) capacity.
Location: The tank is located in the PUREX Building.

Waste Type: Process Effluent

Waste Description: The unit contains high-level acid wastes which are neutralized with sugar, sodium hydroxide (NaOH), and sodium nitrite (NaNO₂) before going to double-shell underground storage tanks.

Code: 202-A-F16 **Classification:** Accepted
Names: 202-A-F16; 202-A-TK-F16; PUREX Tank F16 **Reclassification:** None
Type: Neutralization Tank **Start Date:** 1/15/1956
Status: Inactive **End Date:**

Description: The unit has a 18,900-liter (5,000-gallon) capacity.

Location: The tank is located in the PUREX Building.

Waste Type: Process Effluent

Waste Description: The unit contains high-level acid wastes which are neutralized with sugar, sodium hydroxide (NaOH), and sodium nitrite (NaNO₂) before going to double-shell underground storage tanks.

Code: 202-A-F18 **Classification:** Accepted

Names: 202-A-F18; 202-A-TK-F18; PUREX Tank F18 **Reclassification:** None

Type: Neutralization Tank **Start Date:** 1/15/1956

Status: Inactive **End Date:**

Description: The unit has a 18,900-liter (5,000-gallon) capacity.

Location: The tank is located in the PUREX Building.

Waste Type: Process Effluent

Waste Description: The unit contains miscellaneous wastes collected from all sections of the plant. The dangerous wastes consist mainly of nitric acid (HNO₃). The wastes are neutralized with sodium hydroxide (NaOH) and sodium nitrite (NaNO₂) to a pH greater than 12.5 before going to double-shell underground storage tanks.

Code: 202-A-G7 **Classification:** Accepted

Names: 202-A-G7; 202-A-TK-G7; PUREX Tank G7 **Reclassification:** None

Type: Neutralization Tank **Start Date:** 1/15/1956

Status: Inactive **End Date:**

Description: The unit has a 53,000-liter (14,000-gallon) capacity.

Waste Type: Process Effluent

Waste Description: The unit receives ammonia distillate from Tank E-F11 and is neutralized with sodium hydroxide (NaOH) and sodium nitrite (NaNO₂) before going to double-shell underground storage tanks.

Code: 202-A-U3 **Classification:** Accepted

Names: 202-A-U3; PUREX Tank U3; 202-A-TK-U3 **Reclassification:** None

Type: Neutralization Tank **Start Date:** 1/15/1956

Status: Inactive **End Date:**

Description: The unit has a 30,280-liter (8,000-gallon) capacity.

Location: The tank is located in the PUREX Building.

Waste Type: Process Effluent

Waste Description: The unit contains miscellaneous wastes collected from all sections of the plant. The dangerous wastes consist mainly of nitric acid (HNO₃). The wastes are neutralized with sodium hydroxide (NaOH) and sodium nitrite (NaNO₂) to pH of greater than 12.5 before going to double-shell underground storage tanks.

Code: 202-A-U4	Classification: Accepted
Names: 202-A-U4; PUREX Tank U4; 202-A-TK-U4	Reclassification: None
Type: Neutralization Tank	Start Date: 1/15/1956
Status: Inactive	End Date:

Description: The unit has a 30,280-liter (8,000-gallon) capacity.

Location: The tank is located in the PUREX Building.

Waste Type: Process Effluent

Waste Description: The unit contains miscellaneous wastes collected from all sections of the plant. The dangerous wastes consist mainly of nitric acid (HNO₃). The wastes are neutralized with sodium hydroxide (NaOH) and sodium nitrite (NaNO₂) to pH of greater than 12.5 before going to double-shell underground storage tanks.

Code: 202-A-WS-1	Classification: Accepted
Names: 202-A-WS-1; PUREX Waste Piles	Reclassification: None
Type: Storage	Start Date: 1/1/1956
Status: Inactive	End Date:

Description: This site is located in the PUREX Building on the canyon deck and F-Cell canyon floor.

Location: The pile of material is located inside the 202-A building.

Waste Type: Equipment

Waste Description: The PUREX Containment Building is permitted for the storage of waste designated TCLP toxic for lead (D008), cadmium (D006), and chromium, (D007) and toxic (WT01). Discarded process equipment removed from service in the PUREX Plant and known to have shielding, weights, and or counterweights containing elemental cadmium or lead was stored on the canyon deck within the containment building. However, this waste has been removed and placed on a burial box inside the PUREX Storage Tunnel 2. In November 1996, chromium contaminated concrete solids from the E-Cell floor were stored in F-Cell within the containment building as well as a lead-lined remote camera assembly on the West Crane Maintenance Platform.

Code: 205-A	Classification: Accepted
Names: 205-A; 205-A Silica Gel Facility	Reclassification: Rejected (6/18/2014)
Type: Process Unit/Plant	Start Date: 1/1/1956
Status: Inactive	End Date: 1/1/1976

Description: The waste site has been evaluated and Reclassified to Rejected. The site is a small building constructed of transite. It contains lead lined silica gel beds, made from lead shielded 55 gallon drums. The structure is 3.6 meters by 3 meters by 2.4 meters (12 feet long, 10 feet wide and 8 feet high). It sits on a concrete pad inside the 203-A tank farm enclosure.

TPA-MP-14, Rev. 2, Section 2.0 states that WIDS does not document buildings or facilities that do not contain TSD units. It further states that, after buildings are demolished, the footprint will be evaluated for potential soil contamination. If present, the soil contamination will be added to

Location: WIDS as a Discovery Site.
The building is located within the 203-A Basin, north of the PUREX canyon building. It is inside the PUREX facility fence.

Process Description: The Silica Gel facility was a prototype unit, placed in service in 1956 to prove process feasibility. The uranium solution from the solvent extraction systems often required further treatment to meet product specifications. Silica gel absorbed the zirconium and niobium contaminants, without significant loss of uranium. After successfully demonstrating the process, the 205-A unit was converted to product use. Another silica gel facility was also built at REDOX. Since the PUREX unit was not designed for continuous operation, uranium solutions from PUREX were often transferred to REDOX of treatment.

Waste Type: Process Effluent

Waste Description: The unit contains silica gel and process and flush solutions. The amount of radionuclides present is not known. There is less than 2,000 counts/minute smearable beta/gamma; 5 millirad/hour nonpenetrating, 1 millirem/hour penetrating and detectable alpha. The tanks are assumed to contain silica gel and may contain either process or flush solutions.

Code: 207-A-SOUTH **Classification:** Accepted

Names: 207-A-SOUTH; 207-A-SOUTH Retention Basin and Pump Pit; 207-A; 207-A Retention Basin; 207-A South **Reclassification:** None

Type: Retention Basin **Start Date:** 1/1/1977

Status: Inactive **End Date:** 1/1/1989

Description: The 207-A South basin was demolished in 2015. It consisted of three, unlined concrete cells that are coated with a (white) polyurethane sealant. They were marked, but were no longer posted with radiological warning signs. The cells were fed from the pump pit, located between the 207-A South and 207-A North basins. A 10-centimeter (4-inch) fill line entered each cell inside the basin structure. A 7.6-centimeter (3-inch) drain line exits the bottom of the each cell. The 200-E-236-PL basin distribution pipelines were consolidated into the 207-A South Basin waste site.

Location: The 207-A Retention Basins were located east of the 242-A Evaporator Building, on the east side of Canton Ave.

Related Sites/Structures: The basins are associated with the 242-A Evaporator and the 216-A-37-1 Crib. The pipeline from the basin to the 216-A-37-1 crib is sitecode 200-E-232-PL. The pipelines from 242-A Evaporator to the 207-A basins are sitecode 200-E-234-PL. The south basin distribution lines are sitecode 200-E-236-PL.

Process Description: The basins provided interim storage of 242-A evaporator process condensate. When operating, the three cells of the 207-A South Basins were filled alternately, sampled, and discharged to the 216-A-37-1 Crib after meeting release specifications. The 242-A Evaporator could retrieve the liquid waste for reprocessing or storage in the tank farm, via line 300, if discharge specifications were not met. After the 207-A North and South basins ceased to operate, the 242-A effluent was diverted to the 200 Area Treated Effluent Disposal Facility or the Liquid Effluent Facility basins.

Waste Type: Steam Condensate

Waste Description: The unit was used for the interim storage of the 242-A Evaporator process condensate to allow for sampling and analysis prior to being discharged to the 216-A-37-1 Crib.

The Following Sites Were Consolidated With This Site:**Code:** 200-E-236-PL**Names:** 200-E-236-PL; 207-A South Basin Distribution Lines; Lines 557, 558, 559, 560, 562, and 563**Code:** 211-A NU**Classification:** Accepted**Names:** 211-A NU; Elementary Neutralization Unit/211-A Building; PUREX; 211-A Neutralization Unit**Reclassification:** Rejected (6/18/2014)**Type:** Neutralization Tank**Start Date:** 1/1/1986**Status:** Inactive**End Date:** 1/1/1990**Description:** The site has been evaluated and reclassified to Rejected. The 211-A Neutralization Unit was located inside the 211-A Building.

TPA-MP-14, Rev. 2, Section 2.0 states that WIDS does not document buildings or facilities that do not contain TSD units. It further states that, after buildings are demolished, the footprint will be evaluated for potential soil contamination. If present, the soil contamination will be added to WIDS as a Discovery Site.

Location: The 211-A building is located adjacent to the north side of 202-A.

Process Description: PUREX process water was required to be very pure. The 211-A building contained the demineralizer columns (deionizer units). When the deionizers became loaded, they were recharged with acidic and basic solutions. The spent acid and basic solutions were combined in the 211-A Neutralization Unit. The pH was tested and adjusted until it was 7.0 pH. Then the solution was discharged to the chemical process sewer.

Waste Type: Chemicals

Waste Description: Approximately 318 kilograms (700 pounds) per year of 9% sulfuric acid is combined with 272 kilograms (600 pound) per year of sodium hydroxide within the water demineralizer columns during regeneration.

Code: 216-A-39**Classification:** Accepted**Names:** 216-A-39; 216-A-39 Crib; 216-A-39 Trench**Reclassification:** None**Type:** Crib**Start Date:** 1/1/1966**Status:** Inactive**End Date:** 1/1/1966

Description: The site consists of a crib and two trenches dug from the north door of the 241-AX-801-A Building. The trenches extended to the brow of the north hill, then over the hill to the flat ground below. The trenches continued eastward 27 meters (90 feet). Later, a pipeline was added that connected the 241-AX-801-B building to the 216-A-39 crib.

Drawing H-2-33295 shows the crib structures. Each crib has three SCH 40 pipes. The drawing also states the crib was covered with approximately 6 meters (20 feet) of dirt in 1973. The risers were extended above the new grade in May 1973.

Location: Site is located near the southeast corner of the 241-AZ tank farm, inside the tank farm fence.

Release Description: This crib was built in 1966 to accommodate a liquid release that contaminated the 241-AX-801-A building. A team was changing out a valve on the 241-AX-103 tank recirculator line. The radioactive line pressurized and resulted in a release to the floor of the instrument (241-AX-801-A) building. Dose rates from the release were greater than 5 rad per hour at a distance of 3

meters (10 feet). A trench, 0.9 meters (3 feet deep), was dug to receive the liquid. The trench extended from the north side of the 241-A-801-A building to the brow of the north hill, then continued over the hill to the flat ground below. The trench extended eastward approximately 27 meters (90 feet). A hole was cut through the back side of the 801 Building and a fire hose was used to wash the contamination out the door and into the trench. The first trench was covered with dirt and a second trench was dug, parallel to the first, to receive a second rinsing of the 241-AX-801-A building floor. This trench was also backfilled. A residual dose rate remained on the floor of the building.

It should be noted that the RHO-CD-673 document states the release occurred at the 241-AX-801-B building. Physical evidence found at the 241-AX-801-A building and interviews with long time tank farm employees has shown that the release actually occurred at the 241-AX-801-A building.

Related Sites/ Structures: The crib is associated with the 241-AX-801-A and 241-AX-801-B buildings.

Process Description: The 216-A-39 originally consisted of two trenches that received liquid from a spill of radioactive material in June 1966. In 1969, a pipeline was added to connect the 241-AX-801B building to the crib.

Waste Type: Process Effluent

Waste Description: The site originally received waste from a radioactive spill in the 241-AX-801-A Building (June 1966). The maximum dose rate from this release was 5 rad per hour at a distance of 3 meters (10 feet). Later, the crib received floor drainage via a pipeline from the 241-AX-801-B building.

Code: 242-A **Classification:** Accepted

Names: 242-A; 242-A Evaporator **Reclassification:** None

Type: Evaporator **Start Date:** 1/1/1977

Status: Active **End Date:**

Description: The 242-A Building contains the evaporator vessel, supporting process equipment, and the principal process components of the evaporator-crystallizer system. The building comprises two adjoining, structurally independent structures, designated A and B. Structure A houses the processing and service areas while structure B houses operating and personnel support areas.

Location: This Evaporator building is located adjacent to the south side of the 241-A Tank Farm, outside the tank farm fence. It is near the corner of 4th Street and Canton Ave.

Related Sites/ Structures: The structures associated with the unit include: the 241-AN, the 241-AP, and the 241-AW Tank Farms, and the 207-A Retention Basins. The pipelines from 242-A to the 207-A basins are sitecode 200-E-234-PL.

Process Description: The 242-A Evaporator is used to treat mixed waste from the Double-Shell Tank System by removing water and most volatile organics. Two waste streams leave the 242-A Evaporator following the treatment process. The first waste stream, the concentrated slurry, is pumped back into the Double-Shell Tank System (Tank Farms AN, AW, and/or AP). The second waste stream, process condensate, is routed through condensate filters for treatment before release to the Liquid Effluent Retention Facility and receives final treatment at the Effluent Treatment Facility.

Waste Type: Chemicals

Waste Description: Waste types include: dilute non-complexed radioactive waste, PUREX dilute miscellaneous waste, PUREX cladding removal waste, and complexed radioactive waste. Hazardous

chemicals used include: sodium nitrate used to regenerate ion exchange column, sodium hydroxide used for decontamination applications, and the antifoam agent used in the evaporator vessel.

Code: 296-A-13	Classification: Accepted
Names: 296-A-13; 291-AR Filter Building Stack	Reclassification: None
Type: Stack	Start Date:
Status: Inactive	End Date: 1/1/1997

Description: The site is a process effluent stack that was part of the 244-AR Canyon Exhaust Ventilation System (K-3). The stack is mounted on a buried concrete stand. The stack is equipped with a galvanized steel ladder, a stainless steel breech, a cleanout access, two stainless steel monitoring holes, 7.6 centimeters (3 inches) and 20.3 centimeters (8 inches), and spray rings. When the stack is operating, the exit temperature is 25.6 degrees Centigrade (78 degrees Fahrenheit) and exit velocity is 5 meters per second (16.4 feet per second). The stack has been plugged with grout and has not operated since 1997.

Location: The site is located due north of 291-AR Filter Building about 8.7 meters (28.5 feet) and 23 meters (75 feet) north of 244-AR Vault Building. The Washington State Plane coordinates listed in the Hanford Site Air Operating Permit Application are E575220 and N136090.

Related Sites/ Structures: The site is related to the 291-AR Filter Building, 244-AR Vault Building, 291-AR Filter Building Extension and 216-A-41 Crib.

Process Description: The purpose of the ventilation system, identified as K-3, is to filter radiological contaminants from the canyon exhaust air prior to exhausting it to the atmosphere. Ventilation air exits Cell 1 (within 244-AR Vault) through a concrete air duct. The main duct terminates at a concrete gate and the branch turns left running south of the existing 291-AR Building where it connects to the east wall of the 291-AR Filter Vault Extension.

Two concrete exhaust ducts, each 3.5 meters (11.4 feet) wide by 2 meters (6.4 feet) deep, are located on the east and west corners of the ceiling at the north end of the filter building. These exhaust ducts extend 3.05 (10 feet) above the ceiling and are connected to the canyon exhaust ventilation fans (K3-9-1 and K3-9-2) located between the exhaust ducts. These fans draw the ventilation air from the canyon through the filters and exhaust to the canyon ventilation stack (296-A-13) located north of the 291-AR Filter Building. The ventilation system has been taken out of service and the suction fans have been blanked from the filter system.

Waste Type: Process Effluent

Waste Description: The site received condensate and air exhaust from the 291-AR Filter Building. According to RHO-CD-673 (reference to 216-A-41 Crib), the waste was potentially slightly acidic and contained less than 1 curie total beta activity. Potential contaminants of concern (Stenner) may be tritium, cobalt-60, strontium-90, and cesium-137. WHC-SD-EN-RPT-007 states that radionuclide inventory is based on levels for "very high removable contamination" (WHC-CM-1-6) assuming worst case alpha (americium-241) and beta (strontium-90/yttrium-90) as representative nuclides. The level of contamination is assumed to be uniformly distributed over all ventilated surface areas. For americium-241 the contamination is 2,000 disintegrations per 100 square centimeters (dpm/100²) and total activity of 0.00021 curies. For strontium-90 the contamination is 100,000 disintegrations per 100 square centimeters (dpm/100²) and total activity of 0.0105 curies. For yttrium-90 the contamination is 100,000 disintegrations per 100 square centimeters (dpm/100²) and total activity of 0.0105 curies. DOE/RL-94-51 lists the total alpha as 0.000000023 curies. Total beta is listed as 0.000000036 curies.

Code: 241-AN-A **Classification:** Accepted
Names: 241-AN-A; 241-AN-A Diversion Box **Reclassification:** None
Type: Valve Pit **Start Date:** 1/1/1981
Status: Active **End Date:**

Description: This valve pit is fabricated of reinforced concrete. This valve pit accommodates pipes and jumpers and nozzles that go to different tanks. The valve pit is below grade with the cover block a few inches above grade.

Location: The unit is located inside the 241-AN Tank Farm fence, between the 241-AN-105 and 241-AN-106 tanks.

Related Sites/ Structures: This unit is associated with the 241-A Tank Farm, the 241-AN-101 Tank, and the 242-A Evaporator.

Process Description: The valve pit has two functions. It routes slurry from the 242-A Evaporator to the designated 241-AN tanks and routes supernate from other tank farms to the 241-AN tanks.

Waste Type: Process Effluent

Waste Description: This unit contains non-complexed waste, double-shell slurry waste, B Plant low-level waste, and PUREX low-level waste.

Code: 241-AN-B **Classification:** Accepted
Names: 241-AN-B; 241-AN-B Diversion Box **Reclassification:** None
Type: Valve Pit **Start Date:** 1/1/1981
Status: Active **End Date:**

Description: This valve pit is fabricated of reinforced concrete. This valve pit accommodates pipes and jumpers and nozzles that go to different tanks. The valve pit is below grade with the cover block a few inches above grade.

Location: The unit is located inside the 241-AN Tank Farm fence, between the 241-AN-102 and 241-AN-103 tanks.

Related Sites/ Structures: The unit is associated with the 241-A Tank Farm and the 241-AN-101 Tank.

Process Description: The valve pit has two functions. It routes slurry from the 242-A Evaporator to the designated 241-AN tanks and routes supernate from other tank farms to the 241-AN tanks. Waste material is routed through the 241-AN-B Valve Pit and then to the designated double-shell tanks. The 241-AN-B Valve Pit is connected by slurry lines and supernatant lines to the 241-AN-101, 241-AN-102, 241-AN-103 Double-Shell Tanks and the 241-AN-A Valve Pit.

Waste Type: Process Effluent

Waste Description: The unit contains non-complexed waste, double-shell slurry waste, B Plant low level waste, and PUREX low level waste.

Code: 241-AN-101 **Classification:** Accepted
Names: 241-AN-101; 241-AN-TK-101 **Reclassification:** None
Type: Double-Shell Tank **Start Date:** 9/1/1981

Status: Active**End Date:****Description:** The unit is comprised of a heat-treated, stress-relieved primary steel liner and a nonstress-relieved outer steel liner, both inside the reinforced concrete shell. The top of the dome was placed below grade for shielding.**Location:** The 241-AN-101 Tank is located in the eastern portion of the 241-AN Tank Farm.**Process Description:** The Double-Shell Tank System is used for the interim storage of liquid mixed waste generated on the Hanford Facility.**Waste Type:** Storage Tank**Waste Description:** Tank 241-AN-101 began service by receiving non-complexed waste from PUREX in September 1981. Non-complexed waste was received and transferred through this tank until September 1990 when it began receiving dilute non-complexed waste. During this time, the tank also received low-level waste from B Plant, decontamination waste from N Reactor, and dilute non-complexed waste from the 200 East Area Single-Shell Tanks. As of March 1994, the tank was receiving only dilute non-complexed waste. The tank is an active dilute receiver tank which receives non-complexed salt well waste.

Code: 241-AN-102**Classification:** Accepted**Names:** 241-AN-102; 241-AN-TK-102**Reclassification:** None**Type:** Double-Shell Tank**Start Date:** 9/1/1981**Status:** Active**End Date:****Description:** The unit is comprised of a heat-treated, stress-relieved primary steel liner and a nonstress-relieved outer steel liner, both inside the reinforced concrete shell. The top of the dome was placed below grade for shielding.**Location:** The 241-AN-102 Tank is located in the center portion of the 241-AN Tank Farm.**Process Description:** The Double-Shell Tank System is used for the interim storage of liquid mixed waste generated on the Hanford Facility.**Waste Type:** Storage Tank**Waste Description:** Tank 241-AN-102 began service by receiving non-complexed waste from Tank 241-SY-102 in September 1981. The tank received non-complexed waste until December 1982. The tank received complexant concentrate waste from January 1983 until October 1983. From November 1983 until June 1984, the tank again received non-complexed waste. During 1984, the tank received low-level waste from PUREX. The tank received complexant concentrate waste from Tank 241-AW-101 from July 1984 until 1992 and has not received any waste since 1992. The tank is considered a concentrated waste holding tank.

Code: 241-AN-103**Classification:** Accepted**Names:** 241-AN-103; 241-AN-TK-103**Reclassification:** None**Type:** Double-Shell Tank**Start Date:** 9/1/1981**Status:** Active**End Date:****Description:** The unit is comprised of a heat-treated, stress-relieved, primary steel liner and a nonstress-relieved outer steel liner, both inside the reinforced concrete shell. The top of the dome was placed below grade for shielding.

Location: The 241-AN-103 Tank is located in the western portion of the 241-AN Tank Farm.

Process Description: The Double-shell Tank System is used for the interim storage of liquid mixed waste generated on the Hanford facility.

Waste Type: Storage Tank

Waste Description: Tank 241-AN-103 began service by receiving non-complexed waste from Tank 241-SY-102 in September 1981. The tank received non-complexed waste until February 1984. During 1983, the tank received low-level waste from B Plant and dilute non-complexed waste from the 200-East Area single shell tanks. The tank received double-shell slurry feed waste from March 1984 until April 1986. Since May 1986, the tank has contained double-shell slurry waste. The tank has not received any waste, other than wash water, since 1986. The tank is considered a concentrated waste holding tank.

Code: 241-AN-104	Classification: Accepted
Names: 241-AN-104; 241-AN-TK-104	Reclassification: None
Type: Double-Shell Tank	Start Date: 9/1/1981
Status: Active	End Date:

Description: The unit is comprised of a heat-treated, stress-relieved primary steel liner and a nonstress-relieved outer steel liner, both inside the reinforced concrete shell. The top of the dome was placed below grade for shielding.

Location: The 241-AN-104 Tank is located in the eastern portion of the 241-AN Tank Farm.

Process Description: The Double-Shell Tank System is used for the interim storage of liquid mixed waste generated on the Hanford facility.

Waste Type: Storage Tank

Waste Description: Tank 241-AN-104 began service by receiving non-complexed waste in September 1981. The majority of the waste was sent from Tank 241-AW-102 during 1982. The tank continued to receive non-complexed waste until November 1982. The tank has contained double-shell slurry feed waste from December 1982 until the present. During 1983, the tank also received low-level waste from PUREX. The tank has not received waste since 1985. The tank is considered a concentrated waste holding tank.

Code: 241-AN-105	Classification: Accepted
Names: 241-AN-105; 241-AN-TK-105	Reclassification: None
Type: Double-Shell Tank	Start Date: 9/1/1981
Status: Active	End Date:

Description: The unit is comprised of a heat-treated, stress-relieved primary steel liner and a nonstress-relieved outer steel liner, both inside the reinforced concrete shell. The top of the dome was placed below grade for shielding.

Location: The 241-AN-105 Tank is located in the central portion of the 241-AN Tank Farm.

Process Description: The Double-Shell Tank System is used for the interim storage of liquid mixed waste generated on the Hanford Facility.

Waste Type: Storage Tank

Waste Description: Tank 241-AN-105 began service by receiving non-complexed waste in September 1981. The tank continued to receive non-complexed waste until November 1982. The tank received double-shell slurry feed waste from Tanks 241-AW-102 and 241-AN-104 from December 1982 until 1985, when waste reception ceased. The tank is considered a concentrated waste holding tank.

Code: 241-AN-106 **Classification:** Accepted
Names: 241-AN-106; 241-AN-TK-106 **Reclassification:** None
Type: Double-Shell Tank **Start Date:** 9/1/1981
Status: Active **End Date:**

Description: The unit is comprised of a heat-treated, stress-relieved primary steel liner and a nonstress-relieved outer steel liner, both inside the reinforced concrete shell. The top of the dome was placed below grade for shielding.

Location: The 241-AN-106 Tank is located in the western portion of the 241-AN Tank Farm.

Process Description: The Double-Shell Tank System is used for the interim storage of liquid mixed waste generated on the Hanford Facility.

Waste Type: Storage Tank

Waste Description: Tank 241-AN-106 began service by receiving non-complexed waste in September 1981. The tank continued to receive non-complexed waste until January 1983. From February 1983 until February 1984, the tank received concentrated customer waste. The tank contained Hanford facility waste from March 1984 until May 1990. From June 1990 until the present, the waste contained in the tank has been designated as phosphate waste. The tank has not received any waste, other than wash water, since 1984. The supernatant was pumped to Tank 241-AP-102 during 1992. The tank is considered a concentrated waste holding tank.

Code: 241-AN-107 **Classification:** Accepted
Names: 241-AN-107; 241-AN-TK-107 **Reclassification:** None
Type: Double-Shell Tank **Start Date:** 9/1/1981
Status: Active **End Date:**

Description: The unit is comprised of a heat-treated, stress-relieved primary steel liner and a nonstress-relieved outer steel liner, both inside the reinforced concrete shell. The top of the dome was placed below grade for shielding.

Location: The 241-AN-107 Tank is located in the northwestern portion of the 241-AN Tank Farm.

Process Description: The Double-Shell Tank system is used for the interim storage of liquid mixed waste generated on the Hanford Facility.

Waste Type: Storage Tank

Waste Description: Tank 241-AN-107 began service by receiving non-complexed waste in September 1981 from Tank 241-AN-102. The tank continued to receive non-complexed waste until June 1983. From July 1983 until the present, the tank has contained complexant concentrate waste, most of which was received from Tank 241-AZ-102 during 1983. The tank has not received any waste since 1986. The tank is considered a concentrated waste holding tank.

Code: 241-AP VP **Classification:** Accepted
Names: 241-AP VP; 241-AP Valve Pit **Reclassification:** None
Type: Valve Pit **Start Date:** 1/1/1986
Status: Active **End Date:**

Description: The cover block is made in two sections. The valve pit has a floor drain that empties to tank 241-AP-103. On the east end of the pit is a jumper storage area separated from the process side by a wall. The jumper storage area has 10 gage stainless steel liner on the floors and walls. The floor drain is in both the process and storage sides of the valve pit. It is not initially encased from the floor, but is encased as it leaves the valve pit area. All concrete and ferrous materials are treated with protective coating.

Location: The valve pit is located on the west side of the 241-AP Tank Farm, between tanks 241-AP-103 and 241-AP-105.

Related Sites/ Structures: The valve pit is associated with the 241-AP Tank Farm and 241-AP-103 Tank.

Process Description: The unit is used for the transfer of liquid mixed waste within the tank farm.

Waste Type: Equipment

Waste Description: The AP Tank Farm began receiving waste in July 1986. The waste consisted of non-complexed waste, Hanford Site facilities waste, double-shell slurry waste, low-level waste from PUREX, and N Reactor decontamination waste.

Code: 241-AP-101 **Classification:** Accepted
Names: 241-AP-101; 241-AP-TK-101 **Reclassification:** None
Type: Double-Shell Tank **Start Date:** 1/1/1986
Status: Active **End Date:**

Description: The tank is a double-shell tank with an outer structure of reinforced concrete lined with carbon steel. The primary tank is carbon steel located within the secondary liner. The tanks are separated by an annular space. The tank is placed on a concrete foundation. The dome is below grade for shielding.

Location: The 241-AP-101 tank is located in the northwest corner of the 241-AP Tank Farm.

Process Description: The Double-Shell tank system is used for the interim storage of liquid mixed waste generated on the Hanford Facility.

Waste Type: Storage Tank

Waste Description: Tank 241-AP-101 began service by receiving non-complexed waste in July 1986. During 1987, 1988, and 1989, the tank received waste from PUREX. The tank received non-complexed waste until May 1990. From June 1990 until the present, the tank has contained dilute non-complexed waste. The tank has not received any waste since the fourth quarter of 1989. The tank is currently an active dilute receiver tank containing waste that is being concentrated by the 242-A Evaporator.

Code: 241-AP-102 **Classification:** Accepted
Names: 241-AP-102; 241-AP-TK-102 **Reclassification:** None

Type: Double-Shell Tank
Status: Active

Start Date: 1/1/1986
End Date:

Description: The tank is a double-shell tank with an outer structure of reinforced concrete lined with carbon steel. The primary tank is carbon steel located within the secondary liner. The tanks are separated by an annular space. The tank is placed on a concrete foundation. The dome is below grade for shielding.

Location: The 241-AP-102 tank is located in the northeast corner of the 241-AP Tank Farm.

Process Description: The Double-Shell Tank System is used for the interim storage of liquid mixed waste generated on the Hanford Facility.

Waste Type: Storage Tank

Waste Description: Tank 241-AP-201 began service by receiving Hanford facility waste in July 1986. The tank received Hanford facility waste until May 1990. During 1988 and 1989, waste was transferred from the tank to the grout vaults. The tank received waste from PUREX during the third and fourth quarters of 1989. The tank has contained dilute non-complexed waste since June 1990. The tank has not received any waste since 1992. The tank is currently an inactive, grout feed tank containing excess water from the grout facility.

Code: 241-AP-103

Classification: Accepted

Names: 241-AP-103; 241-AP-TK-103

Reclassification: None

Type: Double-Shell Tank

Start Date: 1/1/1986

Status: Active

End Date:

Description: The tank is a double-shell tank with an outer structure of reinforced concrete lined with carbon steel. The primary tank is carbon steel located within the secondary liner. The tanks are separated by an annular space. The tank is placed on a concrete foundation. The dome is below grade for shielding.

Location: The 241-AP-103 tank is located on the west side of the 241-AP Tank Farm.

Process Description: The Double-Shell Tank System is used for the interim storage of liquid mixed waste generated on the Hanford Facility.

Waste Type: Storage Tank

Waste Description: Tank 241-AP-103 began service by receiving non-complexed waste in July 1986. The tank received non-complexed waste until May 1990. The tank received waste from PUREX during the first, second, and third quarters of 1988. From June 1990 until the present, the tank has contained dilute non-complexed waste. The tank has not received waste since 1991. The tank is currently an inactive dilute receiver tank.

Code: 241-AP-104

Classification: Accepted

Names: 241-AP-104; 241-AP-TK-104

Reclassification: None

Type: Double-Shell Tank

Start Date: 1/1/1986

Status: Active

End Date:

Description: The tank is a double-shell tank with an outer structure of reinforced concrete lined with carbon steel. The primary tank is carbon steel located within the secondary liner. The tanks are

separated by an annular space. The tank is placed on a concrete foundation. The dome is below grade for shielding.

Location: The 241-AP-104 tank is located on the east side of the 241-AP Tank Farm.

Process Description: The Double-Shell Tank System is used for the interim storage of liquid mixed waste generated on the Hanford Facility.

Waste Type: Storage Tank

Waste Description: Tank 241-AP-104 began service by receiving Hanford Facility waste in July 1986 and continued receiving this waste until May 1990. The tank received decontamination waste from N Reactor from the first quarter until the third quarter of 1987. From June 1990 until the present, the tank contained dilute non-complexed waste. Currently, the tank is an inactive grout feed tank.

Code: 241-AP-105

Classification: Accepted

Names: 241-AP-105; 241-AP-TK-105

Reclassification: None

Type: Double-Shell Tank

Start Date: 1/1/1986

Status: Active

End Date:

Description: The tank is a double-shell tank with an outer structure of reinforced concrete lined with carbon steel. The primary tank is carbon steel located within the secondary liner. The tanks are separated by an annular space. The tank is placed on a concrete foundation. The dome is below grade for shielding.

Location: The 241-AP-105 tank is located in the southwest portion of the 241-AP Tank Farm.

Process Description: The Double-Shell Tank System is used for the interim storage of liquid mixed waste generated on the Hanford Facility.

Waste Type: Storage Tank

Waste Description: Tank 241-AP-105 began service by receiving non-complexed waste in July 1986. The tank received non-complexed waste until June 1989. From July 1989 until the present, the tank has contained double-shell slurry feed waste. The tank has not received waste since 1989. The tank is currently an inactive concentrated waste holding tank.

Code: 241-AP-106

Classification: Accepted

Names: 241-AP-106; 241-AP-TK-106

Reclassification: None

Type: Double-Shell Tank

Start Date: 1/1/1986

Status: Active

End Date:

Description: The tank is a double-shell tank with an outer structure of reinforced concrete lined with carbon steel. The primary tank is carbon steel located within the secondary liner. The tanks are separated by an annular space. The tank is placed on a concrete foundation. The dome is below grade for shielding.

Location: The 241-AP-106 tank is located in the southwest portion of the 241-AP Tank Farm.

Process Description: The Double-Shell Tank System is used for the interim storage of liquid mixed waste generated on the Hanford Facility.

Waste Type: Storage Tank

Waste Description: Tank 24-AP-106 began service by receiving Hanford Facility waste in July 1986. The tank continued to receive Hanford Facility waste until September 1986. From October 1986 until May 1990, the tank received non-complexed waste. From June 1990 until the present, the tank has contained dilute non-complexed waste. The tank has not received waste since 1989. The tank is currently an inactive dilute receiver tank.

Code: 241-AP-107 **Classification:** Accepted
Names: 241-AP-107; 241-AP-TK-107 **Reclassification:** None
Type: Double-Shell Tank **Start Date:** 1/1/1986
Status: Active **End Date:**

Description: The tank is a double-shell tank with an outer structure of reinforced concrete lined with carbon steel. The primary tank is carbon steel located within the secondary liner. The tanks are separated by an annular space. The tank is placed on a concrete foundation. The dome is below grade for shielding.

Location: The 241-AP-107 tank is located in the southwest corner of the 241-AP Tank Farm.

Process Description: The Double-Shell Tank System is used for the interim storage of liquid mixed waste generated on the Hanford Facility.

Waste Type: Storage Tank

Waste Description: The 241-AP-107 began service by receiving double-shell slurry feed waste in July 1986. The tank received double-shell slurry feed waste until September 1986. From October 1986 until May 1990, the tank received non-complexed waste. The tank received waste from PUREX during 1990. The tank has contained dilute non-complexed waste from June 1990 until the present. The tank has not received waste since 1990. The tank is currently an active dilute receiver tank containing waste that is being concentrated by the 242-A Evaporator.

Code: 241-AP-108 **Classification:** Accepted
Names: 241-AP-108; 241-AP-TK-108 **Reclassification:** None
Type: Double-Shell Tank **Start Date:** 1/1/1986
Status: Active **End Date:**

Description: The tank is a double-shell tank with an outer structure of reinforced concrete lined with carbon steel. The primary tank is carbon steel located within the secondary liner. The tanks are separated by an annular space. The tank is placed on a concrete foundation. The dome is below grade for shielding.

Location: The 241-AP-108 tank is located in the southeast corner of the 241-AP Tank Farm.

Process Description: The Double-Shell Tank System is used for the interim storage of liquid mixed waste generated on the Hanford Facility.

Waste Type: Storage Tank

Waste Description: The tank has contained dilute non-complexed waste from June 1990 until the present. The tank is currently an active dilute receiver tank with waste that is being concentrated by the 242-A Evaporator. From 1990 until 1992, the tank received waste from PUREX. From October 1986 until May 1990, the tank received non-complexed waste. Tank 241-AP-108 began service by receiving double-shell slurry feed waste in July 1986, and continued to receive this waste until September 1986.

Code: 204-AR **Classification:** Accepted
Names: 204-AR; 204-AR Waste Unloading Station; 204-AR-TK-1 **Reclassification:** None
Type: Loading Dock **Start Date:** 1/1/1982
Status: Active **End Date:**

Description: The 204-AR Unloading Facility is a reinforced concrete structure. The structure includes a shielded railcar unloading room, floor drains, a 5700 liter (1500 gallon) capacity catch tank, transfer pumps and four chemical storage tanks. The chemical tanks contain caustic, nitrite and pH buffer solutions.

Location: This unit is located near the corner of 4th Street and Buffalo Ave, northwest of the 241-AX-151 Diversion Box and south of the 244-AR Vault.

Related Sites/ Structures: The facility includes four chemical storage/makeup tanks and a catch tank (204-AR-TK-1).

Process Description: The 204-AR Facility receives railroad tank cars of liquid radioactive waste to be remotely unloaded inside a fully enclosed, heated, and ventilated building. The structure is a versatile facility that allows the pumping, sampling, and sluicing of the tank cars. Sluicing removes sludge buildup from the tanks and is done during or after the material is pumped out. When samples results show the contents of the railroad car or the catch tank do not meet tank farm specifications, chemical adjustments are made inside the rail car or catch tank. Liquids in the catch tank is periodically to the tank farm on a batch basis. Liquid in excess of the catch tank capacity overflows into the sump pit, that can be pumped to the 241-A-A valve pit.

Waste Type: Storage Tank

Waste Description: The unit receives wastes generated from decontamination and regeneration operations in the 100 and the 200 Areas; from recovery, fuels fabrication, and laboratory operations in the 200 and the 300 Areas; and from decontamination operations in the 400 Area. The waste is chemically adjusted in-line during pump-out to double-shell underground storage tanks to meet corrosion specifications.

Code: 241-AW-A **Classification:** Accepted
Names: 241-AW-A; 241-AW-A Diversion Box; 241-AW-A Valve Pit **Reclassification:** None
Type: Valve Pit **Start Date:** 1/1/1980
Status: Active **End Date:**

Description: The 241-AW valve pits are fabricated from reinforced concrete. The cover block for each pit is made in two sections. Each valve pit has a floor drain. Drain lines empty into tank 241-AW-102. All concrete and ferrous materials are treated with protective coating.

Location: The valve pit is located inside the 241-AW Tank Farm, between the 241-AW-101 and 241-AW-103 tanks.

Related Sites/ Structures: The unit is associated with 241-AW Tank Farm, the 241-AW-102 Tank and 200-E-210-PL.

Process Description: The 241-AW Tank Farm valve pits are used in three ways: (1) to route slurry from 242-A to designated 241-AW tanks; (2) to route supernatant between tanks in 241-AW Tank Farm or to

other tank farms from 241-AW tanks; and (3) to route PUREX nonaging waste to 241-AW tanks.

Waste Type: Process Effluent

Waste Description: Low-level PUREX waste, complexant concentrate waste, complexed waste and dilute non-complexed waste, and non-complexed waste was received and distributed to all tanks via this diversion box.

Code: 241-AW-B **Classification:** Accepted

Names: 241-AW-B; 241-AW-B Diversion Box; 241-AW-B Valve Pit **Reclassification:** None

Type: Valve Pit **Start Date:** 1/1/1980

Status: Active **End Date:**

Description: The 241-AW valve pits are fabricated from reinforced concrete. The cover block for each pit is made in two sections. Each valve pit has a floor drain. Drain lines empty into tank 241-AW-102. All concrete and ferrous materials are treated with protective coating.

Location: The valve pit is located inside the 241-AW Tank Farm, between the 241-AW-101 and 241-AW-103 tanks.

Related Sites/Structures: The unit is associated with 241-AW Tank Farm, 241-AW-102 Tank and 200-E-210-PL.

Process Description: The 241-AW Tank Farm valve pits are used in three ways: (1) to route slurry from 242-A to designated 241-AW tanks; (2) to route supernatant between tanks in 241-AW Tank Farm or to other tank farms from 241-AW tanks; and (3) to route PUREX non-aging waste to 241-AW tanks.

Waste Type: Process Effluent

Waste Description: Low-level PUREX waste, complexant concentrate waste, complexed waste and dilute non-complexed, double-shell slurry waste, and non-complexed waste was received and distributed to all tanks via this diversion box.

Code: 241-AW-101 **Classification:** Accepted

Names: 241-AW-101; 241-AW-TK-101 **Reclassification:** None

Type: Double-Shell Tank **Start Date:** 1/1/1980

Status: Active **End Date:**

Description: The unit is comprised of a heat-treated, stress-relieved primary steel liner and a nonstress-relieved outer steel liner, both inside the reinforced concrete shell. The top of the dome is below grade for shielding.

Location: The 241-AW-101 tank is located in the northwest corner of the 241-AW Tank Farm.

Process Description: The Double-Shell Tank System is used for the interim storage of liquid mixed waste generated on the Hanford Facility.

Waste Type: Storage Tank

Waste Description: Tank 241-AW-101 began service by receiving non-complexed waste in July 1980. The tank continued to receive non-complexed waste until November 1981, and again from December

1982 until March 1983. From December 1981 until November 1982, the tank received dilute double-shell slurry feed waste. The tank received complexant concentrate waste from April 1982 until June 1984. From July 1984 until April 1986, the tank again received non-complexed waste. The tank received waste from PUREX and dilute non-complexed waste from the 200-East Area Single-Shell Tanks from 1984 until 1986. The tank contained double-shell slurry feed waste from May 1986 until the present. The tank has not received waste since 1986. The tank is currently an inactive concentrated waste holding tank.

Code:	241-AW-102	Classification:	Accepted
Names:	241-AW-102; 241-AW-TK-102	Reclassification	None
Type:	Double-Shell Tank	Start Date:	1/1/1980
Status:	Active	End Date:	
Description:	The unit is comprised of a heat-treated, stress-relieved primary steel liner and a nonstress-relieved outer steel liner, both inside the reinforced concrete shell. The top of the dome is below grade for shielding.		
Location:	The 241-AW-102 tank is located in the northeast corner of the 241-AW Tank Farm.		
Process Description:	The Double-Shell Tank System is used for the interim storage of liquid mixed waste generated on the Hanford Facility.		
Waste Type:	Storage Tank		
Waste Description:	Tank 241-AW-102 began service by receiving non-complexed waste in July 1980. The tank received non-complexed waste until May 1983. The tank received evaporator feed waste from June 1983 until December 1984. During 1983 and 1984, the tank received dilute non-complexed waste from the 200-East Area Single-Shell Tanks. Between January 1985 and April 1986, the tank received Hanford Facility waste. From May 1986 until May 1990, the tank received non-complexed waste from other Double-Shell Tanks. The tank has contained dilute non-complexed waste from June 1990 until the present. The tank is currently an active, evaporator feed tank for the 242-A Evaporator.		

Code:	241-AW-103	Classification:	Accepted
Names:	241-AW-103; 241-AW-TK-103	Reclassification	None
Type:	Double-Shell Tank	Start Date:	1/1/1980
Status:	Active	End Date:	
Description:	The unit is comprised of a heat-treated, stress-relieved primary steel liner and a nonstress-relieved outer steel liner, both inside the reinforced concrete shell. The top of the dome is below grade for shielding.		
Location:	The 241-AW-101 tank is located on the west side of the 241-AW Tank Farm.		
Process Description:	The Double-Shell Tank System is used for the interim storage of liquid mixed waste generated on the Hanford Facility.		
Waste Type:	Storage Tank		
Waste Description:	Tank 241-AW-103 began service by receiving non-complexed waste in July 1980. From August 1980 until November 1981, the tank received double-shell slurry feed waste. The tank received PUREX waste from 1983 until 1988. From December 1981 until March 1983, the tank received dilute double-shell slurry feed waste. During April and May 1983, the tank		

received non-complexed waste from June 1983 until May 1990. From June 1990 until the present, the tank has contained dilute non-complexed and PUREX neutralized cladding removal waste. The tank has not received waste since 1992. The tank is currently an inactive dilute receiver tank.

Code: 241-AW-104 **Classification:** Accepted

Names: 241-AW-104; 241-AW-TK-104 **Reclassification:** None

Type: Double-Shell Tank **Start Date:** 1/1/1980

Status: Active **End Date:**

Description: The unit is comprised of a heat-treated, stress-relieved primary steel liner and a nonstress-relieved outer steel liner, both inside the reinforced concrete shell. The top of the dome is below grade for shielding.

Location: The 241-AW-101 tank is located on the east side of the 241-AW Tank Farm.

Process Description: The Double-Shell Tank System is used for the interim storage of liquid mixed waste generated on the Hanford Facility.

Waste Type: Storage Tank

Waste Description: Tank 241-AW-104 began service by receiving non-complexed waste in July 1980. The tank received non-complexed waste until July 1981, and again from October 1982 until May 1990. During August, September, and October 1981, the tank received complexant concentrate waste. From November 1981 to September 1982, the tank received complexed waste. The tank contained non-complexed waste from October 1982 until May 1990. The tank received waste from PUREX from 1986 until 1991. From June 1990 until the present, the tank has contained dilute non-complexed waste. The tank has not received waste since the third quarter of 1992. Currently, the tank is an inactive dilute receiver tank.

Code: 241-AW-105 **Classification:** Accepted

Names: 241-AW-105; 241-AW-TK-105 **Reclassification:** None

Type: Double-Shell Tank **Start Date:** 1/1/1980

Status: Active **End Date:**

Description: The unit is comprised of a heat-treated, stress-relieved primary steel liner and a nonstress-relieved outer steel liner, both inside the reinforced concrete shell. The top of the dome is below grade for shielding.

Location: The 241-AW-105 tank is located in the southwest corner of the 241-AW Tank Farm.

Process Description: The Double-Shell Tank System is used for the interim storage of liquid mixed waste generated on the Hanford Facility.

Waste Type: Storage Tank

Waste Description: Tank 241-AW-105 began service by receiving non-complexed waste in July 1980. The tank received complexant concentrate waste from August 1980 until May 1983. The tank received waste from PUREX from 1983 until 1988. From June 1982 until May 1990, the tank received non-complexed waste. During July 1986, the tank received double-shell slurry feed waste. From June 1990 until the present, the tank has contained dilute non-complexed waste and PUREX neutralized cladding removal waste. The tank is currently an active, dilute receiver tank receiving waste from PUREX.

Code: 241-AW-106 **Classification:** Accepted
Names: 241-AW-106; 241-AW-TK-106 **Reclassification:** None
Type: Double-Shell Tank **Start Date:** 1/1/1980
Status: Active **End Date:**

Description: The unit is comprised of a heat-treated, stress-relieved primary steel liner and a nonstress-relieved outer steel liner, both inside the reinforced concrete shell. The top of the dome is below grade for shielding.

Location: The 241-AW-101 tank is located in the southeast corner of the 241-AW Tank Farm.

Process Description: The Double-Shell Tank System is used for the interim storage of liquid mixed waste generated on the Hanford Facility.

Waste Type: Storage Tank

Waste Description: Tank 241-AW-106 began service by receiving complexant concentrate waste in July 1980. The tank received complexed waste during August and September 1980. From October 1980 to February 1983, the tank received concentrated customer waste. The tank received double-shell slurry feed waste from March 1983 until May 1990. During July 1986, the tank received non-complexed waste. Since June 1990, the tank has contained dilute non-complexed waste. Currently, the tank is an active slurry receiver tank for the 242-A Evaporator.

Code: 241-AX-151:1 **Classification:** Accepted
Names: 241-AX-151:1; 241-AX-151CT; 241-AX-151 Catch Tank **Reclassification:** None
Type: Diversion Box **Start Date:**
Status: Inactive **End Date:**

Description: The catch tank is a 41,640 liter (11,000 gallon) stainless steel lined catch tank located below the four diverter tanks inside the 241-AX-151 Diverter Station. The catch tank received drainage from the diverter tanks, cells and pump pit. The contents of the catch tank could be jetted to diverter tank E or F. The catch tank contains 11,150 liters (2946 gallons) of supernate waste that is anticipated to consist of waste similar to that contained in AX tank farm. The capacity of the catch tank is approximately 12,200 gallons (per RPP-RPT-31102).

The SubSite is Part Of:

Code: 241-AX-151
Names: 241-AX-151; 241-AX-151 Diversion Box; 241-AX-151 Diverter Station

Code: 241-AX-151:2 **Classification:** Accepted
Names: 241-AX-151:2; 241-AX-151-TK-D; 241-AX-151 Diverter Tank D **Reclassification:** None
Type: Diversion Box **Start Date:**
Status: Inactive **End Date:**

Description: Tank D is a 76.2 centimeter (30 inch) diameter stainless steel tank that is 132 centimeters (52 inches) high. It is located within a concrete cell with a stainless steel liner on the cell floor, in

the 241-AX-151 Diverter Station. The cell is equipped with a diverter mechanism. The tank has a 602 liter (159 gallon) capacity. The tank was used in conjunction with the other three diverter tanks to provide waste routing from PUREX to the A, AX and AY Tank Farms and the 244-AR Vault.

The SubSite is Part Of:**Code:** 241-AX-151**Names:** 241-AX-151; 241-AX-151 Diversion Box; 241-AX-151 Diverter Station

Code: 241-AX-151:3**Classification:** Accepted**Names:** 241-AX-151:3; 241-AX-151-TK-E; 241-AX-151 Diverter Tank E
Reclassification None**Type:** Diversion Box**Start Date:****Status:** Inactive**End Date:**

Description: Tank E is a 76.2 centimeter (30 inch) diameter stainless steel tank that is 132 centimeters (52 inches) high. It is located within a concrete cell with a stainless steel liner on the cell floor, in the 241-AX-151 Diverter Station. The cell is equipped with a diverter mechanism. The tank has a 602 liter (159 gallon) capacity. The tank was used in conjunction with the other three diverter tanks to provide waste routing from PUREX to the A, AX and AY Tank Farms and the 244-AR Vault.

The SubSite is Part Of:**Code:** 241-AX-151**Names:** 241-AX-151; 241-AX-151 Diversion Box; 241-AX-151 Diverter Station

Code: 241-AX-151:4**Classification:** Accepted**Names:** 241-AX-151:4; 241-AX-151-TK-F; Diverter Tank F
Reclassification None**Type:** Diversion Box**Start Date:****Status:** Inactive**End Date:**

Description: Tank F is a 76.2 centimeter (30 inch) diameter stainless steel tank that is 132 centimeters (52 inches) high. It is located within a concrete cell with a stainless steel liner on the cell floor, in the 241-AX-151 Diverter Station. The cell is equipped with a diverter mechanism. The tank has a 602 liter (159 gallon) capacity. The tank was used in conjunction with the other three diverter tanks to provide waste routing from PUREX to the A, AX and AY Tank Farms and the 244-AR Vault.

The SubSite is Part Of:**Code:** 241-AX-151**Names:** 241-AX-151; 241-AX-151 Diversion Box; 241-AX-151 Diverter Station

Code: 241-AX-151:5**Classification:** Accepted**Names:** 241-AX-151:5; 241-AX-151-TK-G; Diverter Tank G
Reclassification None**Type:** Diversion Box**Start Date:**

Status: Inactive**End Date:**

Description: Tank G is a 76.2 centimeter (30 inch) diameter stainless steel tank that is 132 centimeters (52 inches) high. It is located within a concrete cell with a stainless steel liner on the cell floor, in the 241-AX-151 Diverter Station. The cell is equipped with a diverter mechanism. The tank has a 602 liter (159 gallon) capacity. The tank was used in conjunction with the other three diverter tanks to provide waste routing from PUREX to the A, AX and AY Tank Farms and the 244-AR Vault.

The SubSite is Part Of:**Code:** 241-AX-151**Names:** 241-AX-151; 241-AX-151 Diversion Box; 241-AX-151 Diverter Station

Code: 241-AX-152CT**Classification:** Accepted**Names:** 241-AX-152CT; 241-AX-152-CT Catch Tank**Reclassification:** Consolidated (5/3/2006)**Type:** Catch Tank**Start Date:** 1/1/1965**Status:** Inactive**End Date:**

Description: The site is an underground catch tank. It is constructed of 0.76 meter (2.5 foot) thick concrete walls. The tank walls and floor are lined with stainless steel. The catch tank is under the diverter station.

Location: The 241-AX-152 Catch Tank and Diverter Station are located in the western portion of the 241-AX Tank Farm.

Related Sites/ Structures: The Catch tank is associated with the 241-AX-152 Diverter Station. The diverter station and the catch tank are part of the same structure. The drain line is line V713.

Waste Type: Process Effluent

Waste Description: This unit transfers mixed waste solutions from processing and decontamination operations.

Description: Volumes are variable according to specific plant operation. Lead shielding may also be contained inside the diversion box.

This Site Was Consolidated With:**Code:** 241-AX-152DS**Names:** 241-AX-152DS; 241-AX-152-DS Diverter Station; Line V713; 241-AX-152 Diverter Station

Code: 241-AX-155**Classification:** Accepted**Names:** 241-AX-155; 241-AX-155 Diversion Box; Line V713**Reclassification:** None**Type:** Diversion Box**Start Date:** 1/1/1983**Status:** Inactive**End Date:**

Description: The surface features of the diversion box have been sprayed with a weather protective coating.

Location: This 241-AX-155 Diversion Box is located inside the 241-AY Tank Farm, adjacent to the 241-AX/241-AY dividing fence.

Related Sites/ Structures: This unit is associated with the 241-AX, 241-AY and the 241-AZ tank farms and the 241-AX-152 diversion box. Line V713 drains to 241-AX-152.

Waste Type: Process Effluent

Waste Description: The unit transports waste solutions from processing and decontamination operations. Quantities are variable according to specific plant operation. Lead shielding may also be contained inside the diversion box.

Waste Type: Equipment

Waste Description: It is estimated that approximately 50 pounds (23 kilograms) of waste lead is stored in each diversion box.

Code: 241-AY-101

Classification: Accepted

Names: 241-AY-101; 241-AY-TK-101

Reclassification: None

Type: Double-Shell Tank

Start Date: 1/1/1971

Status: Active

End Date:

Description: The unit is composed of a heat-treated, stress-relieved primary steel liner and a nonstressed-relieved secondary steel liner, both inside a reinforced concrete shell. The dome is located below grade for shielding purposes.

Location: The 241-AY-101 tank is located on the north end of the 241-AY Tank Farm.

Related Sites/Structures: Structures associated with this tank include leak detection, monitoring and radiation instrumentation, ventilation systems, and risers.

Process Description: The tank is used for interim storage of waste generation on the Hanford Facility.

Waste Type: Storage Tank

Waste Description: Dilute complexed waste is characterized by a high content of organic carbon including organic complexants, including: ethylenediaminetetra-acetic acid, citric acid, and hydroxyethyl-ethylenediaminetriacetic acid, being the major complexants used. Main sources of dilute complexed waste in the double shell tank system are saltwell liquid inventory.

Code: 241-AY-102

Classification: Accepted

Names: 241-AY-102; 241-AY-TK-102

Reclassification: None

Type: Double-Shell Tank

Start Date: 1/1/1972

Status: Active

End Date:

Description: The unit is composed of a heat-treated, stress-relieved primary steel liner and a nonstressed-relieved secondary steel liner, both inside a reinforced concrete shell. The dome is located below grade for shielding purposes.

Location: The 241-AY-102 tank is located in the center of the 241-AY Tank Farm.

Related Sites/Structures: Structures associated with this tank include leak detection monitoring and radiation instrumentation, ventilation systems and risers.

Process Description: The tank is used for interim storage of liquid mixed waste generated on the Hanford Site.

Waste Type: Storage Tank

Waste Description: The unit has received neutralized high-level waste and double-shell slurry feed and is currently a dilute noncomplexed waste receiver tank. Prior to evaporator processing, samples are taken and analyzed for parameters such as visual appearance; percent solids; exotherms or endotherms; total organic carbon; gamma energy spectrum; weight percent water; pH; specific gravity; viscosity; and for the specific ions Al, OH, Cl, CO₃, F, Na, NO₂, NO₃, Pm, PO₄, Pu, SO₄, Sr, Am, and Np. The unit received supernatant consisting of double-shell slurry feed and noncomplexed waste from A and BX tank farms.

Code: 241-AY-151 **Classification:** Accepted

Names: 241-AY-151; 241-AY-151 Diversion Box; 241-AY-151 Pump Out Pit **Reclassification:** None

Type: Diversion Box **Start Date:** 1/1/1975

Status: Inactive **End Date:**

Description: This unit is an underground, reinforced concrete structure. It contains four PUREX style nozzles.

Location: The 241-AY-151 is located in the southern portion of the 241-AY Tank Farm.

Related Sites/Structures: The unit is associated with single shell Tank Farms 241-A and 241-AX.

Process Description: This unit was used to transport radioactive waste solutions between storage and process facilities.

Waste Type: Chemicals

Waste Description: The diversion box contains PUREX organic wash, aging PUREX, PUREX acid, and B Plant high level wastes.

Waste Type: Process Effluent

Waste Description: The diversion box transferred liquid process waste between the processing plants and the tank farms. Lead shielding may also be contained inside the diversion box.

Code: 241-AZ VP **Classification:** Accepted

Names: 241-AZ VP; 241-AZ Valve Pit **Reclassification:** None

Type: Valve Pit **Start Date:**

Status: Active **End Date:**

Description: The valve pit surface features include a cement structure extending a few inches above the ground, with white cover blocks. T-handles and instrumentation extend through the cover blocks.

Location: The valve pit is located east of 241-AZ-101, inside the tank farm fence.

Process Description: The 241-AZ Valve Pit distributes waste between the 200 East Area double shell tank farms. The AZ valve pit has transfer lines internal to the AY and AZ Tank Farms (line SN-633 to 241-AY-02A pump pit, Floor Drain to AZ-101, and line SN-632 to 241-AZ-01A pump pit) and external transfer lines (line SN-630 to 241-AN-01A pump pit and line SN-637 to 241-AP-A valve pit). This AZ valve pit is RCRA compliant and is active.

Code: 241-AZ-101	Classification: Accepted
Names: 241-AZ-101; 241-AZ-TK-101	Reclassification: None
Type: Double-Shell Tank	Start Date: 1/1/1976
Status: Active	End Date:

Description: The unit is composed of a heat-treated, stress-relieved primary steel liner and a non-stressed-relieved secondary steel liner, both inside a reinforced concrete shell. The dome is below grade for shielding purposes.

Location: The 241-AZ-101 tank is located near the northeast corner of the 241-AZ Tank Farm.

Related Sites/ Structures: The tank contains air lift circulators, heating coils, drains, risers, and ports.

Process Description: The Double-Shell tank system is used for the interim storage of liquid mixed waste generated on the Hanford facility.

Waste Type: Storage Tank

Waste Description: Tank 241-AZ-101 began service by receiving evaporator waste in 1976. The tank continued to receive evaporator waste until 1977. From 1978 until September 1980, the tank received complexed waste, double-shell slurry feed waste, non-complexed waste, water, evaporator waste, residual liquor, and complexant concentrate waste. The tank received non-complexed waste from October 1980 until January 1984. From 1981 until 1986, the tank received waste from PUREX. The tank has contained aging waste from February 1984 until the present. The tank is currently an inactive, concentrated waste holding tank that receives only condensate from other aging waste tanks.

Code: 241-AZ-102	Classification: Accepted
Names: 241-AZ-102; 241-AZ-TK-102	Reclassification: None
Type: Double-Shell Tank	Start Date: 1/1/1976
Status: Active	End Date:

Description: The unit is composed of a heat-treated, stress-relieved primary steel liner and a nonstressed-relieved secondary steel liner, both inside a reinforced concrete shell. The dome is below grade for shielding purposes.

Location: The 241-AZ-102 tank is located near the northwest corner of the 241-AZ Tank Farm.

Related Sites/ Structures: This tank contains air lift circulators, heating coils, drains, and nozzles.

Process Description: The double-shell tank system is used for the interim storage of liquid mixed waste generated on the Hanford Facility.

Waste Type: Storage Tank

Waste Description: The tank is currently an inactive, dilute receiver tank that receives only condensate from other aging waste tanks. From April 1986 until the present, the tank has contained aging waste. The tank received waste from PUREX from 1986 until 1990. From February 1984 until February 1986, the tank received non-complexed waste. The tank received complexant concentrate waste from 1978 until November 1983. During December 1983 and January 1984, the tank received complexed waste. During 1977, the tank received residual liquor waste. Tank 241-AZ-102 began service by receiving water in 1976 and was labeled as a spare. The

tank received evaporator waste from 1976 until 1977.

Code: 241-AZ-151CT **Classification:** Accepted

Names: 241-AZ-151CT; 241-AZ-151 Catch Tank **Reclassification:** Consolidated (5/3/2006)

Type: Catch Tank **Start Date:** 1/1/1977

Status: Inactive **End Date:**

Description: The catch tank is not visible from the surface. The catch tank portion is constructed below the diverter station.

Location: The 241-AZ-151 diverter station and catch tank are located southwest of 241-AZ-102 tank, inside the 241-AZ Tank Farm fence.

Related Sites/ Structures: The 241-AZ-151 Diverter Station structure, which includes the diverter station and the catch tank, is associated with the 241-AZ Tank Farm tanks and facilities. The catch tank portion is constructed below the diverter station.

Process Description: The 241-AZ-151 Diverter Station structure transfers radioactive solutions, from various processing and decontamination operations, to tank farm tanks and facilities. Multiple transfer lines enter a 189 liter (50 gallon) tank in the diverter station. A spigot from the tank is rotated to engage in one of several pipe terminal openings to complete a desired routing. Containment is provided by the concrete walls, floor and cover blocks. The 241-AZ-151 Catch Tank is located directly below the receiving tank to contain transfer leakage. The catch tank (catch basin) has a concrete floor that slopes to a sump and collects leakage from both the pump pit and diverter room portions of the diverter station.

Waste Type: Process Effluent

Waste Description: This unit was used for transfer of mixed waste solutions from processing and decontamination operations. In 1994, it contained 15846 liters (4,170 gallons) of waste. In 2000, it contained 8037 liters (2115 gallons). The Tank Waste Summary documents indicate the diverter station and catch basin are active and the liquid volume changes daily. The liquid is pumped to the 241-AZ-102 tank as needed. Lead shielding may also be contained inside the diversion box.

This Site Was Consolidated With:

Code: 241-AZ-151DS

Names: 241-AZ-151DS; 241-AZ-151-DS Diverter Station; 241-AZ-151 Diverter Station

Code: 241-AZ-151DS **Classification:** Accepted

Names: 241-AZ-151DS; 241-AZ-151-DS Diverter Station; 241-AZ-151 Diverter Station **Reclassification:** None

Type: Diversion Box **Start Date:** 1/1/1976

Status: Inactive **End Date:**

Description: The diverter station is an underground reinforced concrete structure. The catch tank is located under the 241-AZ-151DS Diverter Station (Drawing H-2-67256). It is part of the diverter station structure.

Location: 241-AZ-151 Diverter Station is located southwest of 241-AZ-102 tank, inside the 241-AZ Tank Farm fence.

Related Sites/ Structures: The 241-AZ-151 Diverter Station and catch tank are associated with the 241-AZ Tank Farm, the AZ Loop Seal, and the 241-AZ-151 Catch Tank.

Process Description: The 241-AZ-151 Diverter Station transfers radioactive solutions, from processing and decontamination operations, to various tank farm tanks and facilities. Multiple transfer lines enter a small, 189 liters (50 gallons) tank. A spigot from the tank is rotated to engage in one of several pipe terminal openings to complete a desired routing. Containment is provided by the concrete walls, floor and cover blocks. The 241-AZ-151 Catch Tank is located directly below the receiving tank to contain transfer leakage. The catch tank is located under the 241-AZ-151DS Diverter Station (Drawing H-2-67256). It is part of the diverter station structure.

Waste Type: Process Effluent

Waste Description: This unit was used to transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operation. The types of waste received by this unit include: aging waste, concentrated complexant, double-shell slurry feed, and non-complexed waste. In 1994, it contained 15846 liters (4,170 gallons) of waste. In 2000, it contained 8037 liters (2115 gallons). The Tank Waste Summary documents indicate the diverter station and catch basin are active and the liquid volume changes daily.

The Following Sites Were Consolidated With This Site:

Code: 241-AZ-151CT

Names: 241-AZ-151CT; 241-AZ-151 Catch Tank

Code: 241-AZ-152 **Classification:** Accepted

Names: 241-AZ-152; 241-AZ-152 Diversion Box; 241-AZ-152 Sluice Transfer Box **Reclassification:** None

Type: Diversion Box **Start Date:** 1/1/1977

Status: Inactive **End Date:**

Description: 241-AZ-152 is a reinforced concrete diversion box. All nozzles are 4 inch (10 centimeter) PUREX style.

Location: The 241-AZ-152 Diversion Box is located in the southwestern portion of the 241-AZ Tank Farm, east of the 241-AZ-151 Diverter Station.

Related Sites/Structures: The 241-AZ-152 interconnects the 241-AZ Tank Farm, the 241-AY Tank Farm, 241-AZ-151CT, and the 241-AY-152.

Process Description: The 241-AZ-152 diversion box transports radioactive waste solutions from processing and decontamination operations. Drainage is collected in the 241-AZ-151 Catch Tank.

Waste Type: Process Effluent

Waste Description: 241-AX-152 contains high-level B Plant waste, aging waste, B Plant cesium feed waste, non-complexed waste, concentrated complex waste, cesium/strontium recovery waste, evaporator waste, double-shell tank slurry, low-level waste from B Plant, condensate (aging waste), residual liquor, and PUREX low-level waste. Lead shielding may also be contained inside the diversion box.

Code: 241-AZ-154 **Classification:** Accepted

Names: 241-AZ-154; 241-AZ-154 Catch Tank **Reclassification:** None

Type: Catch Tank **Start Date:**

Status: Inactive **End Date:**

Description: The site is an underground carbon steel tank with a stainless steel liner. It has been isolated and a weather cover installed.

Location: The catch tank is located inside the 241-AZ tank farm, south of tank 241-AZ-101.

Related Sites/ Structures: The catch tank is associated with 241-AZ-101, 241-AZ-102 and 241-A-417.

Process Description: The 241-AZ-154 catch tank collected condensate from 241-AZ-101 and 241-AZ-102 in-tank steam heating coils. The catch tank was pumped into 241-A-417, but could also overflow into 241-AZ-102. The condensate passed through a radiation detector (241-F505) and then to a crib or to 241-A-417.

Waste Type: Process Effluent

Waste Description: The catch tank received steam condensate from the 241-AZ-101 and 241-AZ-102 in-tank heating coils as well as precipitation and runoff. The only potential source of radioactive contamination was tank waste leaking into the steam coils that contaminated the condensate.

Code: 241-AZ-155 **Classification:** Accepted

Names: 241-AZ-155; 241-AZ-155 Contaminated Storage Pit **Reclassification:** None

Type: Silo **Start Date:**

Status: Active **End Date:**

Location: The pit is located inside the 241-AZ tank farm, southwest of the 241-AZ-102 tank.

Process Description: The storage pit was and can be used to house failed long length contaminated equipment (e.g., transfer pumps, instrument trees). There are no jumpers or transfer lines that come into the pit. Should any liquid be found in the pit a jet pump could be installed in the pits sump to pump the liquid out.

Code: 216-B-3A **Classification:** Accepted

Names: 216-B-3A; B Pond First Expansion Lobe; B Pond Lobe A; West Expansion Lobe **Reclassification:** Closed Out (6/27/1995)

Type: Pond **Start Date:** 1/1/1983

Status: Inactive **End Date:** 1/1/1994

Description: The 216-3-3A, 216-B-3B and 216-B-3C Expansion Ponds were considered a single RCRA TSD unit in the Hanford Facility Dangerous Waste Part A Permit Application (section 4.2.3.11). This RCRA TSD unit was Clean Closed on June 27, 1995. This waste site is RCRA constituent of a pond that was used for overflow from 216-B-3. The pond is roughly rectangular with approximately 4.5 hectares (11 acres) of surface area. It is inactive and dry. It was sampled and released from radiological controls with the exception of the percolation trench that is posted as a Soil Contamination Area. Radiological issues related to these expansion ponds will be addressed separately (see WIDS Sitecodes 216-B-3A RAD, 216-B-3B RAD, 216-B-3C RAD).

Location: The site is located east of the 200 East Area perimeter fence. It is directly east of 216-B-3 Main Pond.

Related Sites/ Structures: The site is associated with the 216-C-3A RAD site, the PUREX facility, the 216-B-3 Pond and UPR-200-E-14.

Process Description: The 216-B-3A was constructed to receive overflow from the 216-B-3 Main Pond due to the increased effluent discharge from the restart of the Plutonium Uranium Extraction (PUREX) plant (202-A). The 216-B-3A Overflow Pond was connected to the 216-B-3 Main Pond by the 216-B-351 Spillway. The spillway was designed with a manually operated slide gate in the headwall. The water flowed from the main pond, through the culvert, down a 0.61-meter (2-foot) wide, concrete-lined ditch, to a fiberglass reinforced 0.3-meter (1-foot) flume, to the overflow pond. The pond operated from October 1983 to January 1984, when the dike between the 216-B-3A and 216-B-3B ponds failed (Occurrence Report #84-02). Prior to the dike failure, the 216-B-3B Pond had never been used. All the discharge from the failed dike was contained in the 216-B-3B Pond. In response to the incident, the 216-B-3A and 216-B-3B Ponds were isolated. Effluent flow to the 216-B-3 Main Pond was reduced. A trench was dug in the 216-B-3A Pond to increase its infiltration rate. The trench measured 182 meters (600 feet) by 9 meters (30 feet) and was 2 meters (6 feet) deep. The debris from the dike failure was removed from the 216-B-3B Pond and a series of trenches were dug to increase its infiltration rate. Both 216-B-3A and 216-B-3B Ponds were fully operational by June 1984. In April 1994, discharges to the main pond and 216-B-3A lobe ceased and all effluent was rerouted to the 216-B-3C lobe via a pipeline.

Waste Type: Process Effluent

Waste Description: The site received overflow from the 216-B-3 Main Pond. Potential sources include 221-B steam condensate and process cooling water, 284-E Powerhouse water, 244-CR, 244-AR and 242-A cooling water, 202-A process, condenser, and air sampler vacuum pump cooling water, 202-A chemical sewer, fractionator condensate, and WESF cooling water.

Closure Info: Final: A letter was issued by the Washington State Department of Ecology on June 27, 1995, accepting the TSD clean closure certification for the 216-B-3 Expansion Ponds in accordance with Washington State Administrative Code 173-303-610 (6).

Code: 216-B-3B	Classification: Accepted
Names: 216-B-3B; B Pond Lobe B; B Pond Second Expansion Lobe; East Expansion Lobe	Reclassification: Closed Out (6/27/1995)
Type: Pond	Start Date: 1/1/1983
Status: Inactive	End Date: 1/1/1995

Description: The 216-3-3A, 216-B-3B and 216-B-3C Expansion Ponds are considered a single RCRA TSD unit in the Hanford Facility Dangerous Waste Part A Permit Application (section 4.2.3.11). This RCRA TSD unit was clean closed on June 27, 1995. The waste site is RCRA constituent of a pond that was used for overflow from 216-B-3A pond. The pond is approximately 6.27 hectares (15.5 acres) of surface area. It is inactive and dry with a small posted radiological area in the northwest corner. Radiological issues related to these expansion ponds will be addressed separately (see WIDS Sitecodes 216-B-3A RAD, 216-B-3B RAD, 216-B-3C RAD).

Location: The site is located east of the 200 Area perimeter fence. It is southeast of 216-B-3 Main Pond, adjacent to the east side of the 216-B-3A overflow pond.

Process Description: The 216-B-3A and 216-B-3B Expansion Ponds were built in 1983 to receive overflow from the 216-B-3 Main Pond due to increased discharges of effluent from the restart of PUREX. In January 1984, the dike between the 216-B-3A and 216-B-3B ponds failed. Prior to the dike failure, the 216-B-3B Pond had never been used. All the discharge from the failed dike was contained in the 216-B-3B Pond. In response to the incident, the 216-B-3A and 216-B-3B Ponds were isolated. Effluent flow to the 216-B-3 Main Pond was reduced. A trench was dug in the 216-B-3A Pond to increase its infiltration rate. The trench measured 182 meters (600 feet) by 9 meters (30 feet) and was 2 meters (6 feet) deep. The debris from the dike failure was

removed from the 216-B-3B Pond and a series of trenches were dug to increase its infiltration rate. Both 216-B-3A and 216-B-3B Ponds were fully operational by June 1984. Although 216-B-3B was considered an active pond, it never received any effluent with the exception of the 216-B-3A dike failure incident.

Waste Type: Process Effluent

Waste Description: The 216-B-3A and 3B Expansion Lobes were constructed in 1983 to receive increased discharges from the 216-B-3 Main Pond due to the increased water volume from the restart of the PUREX Plant. A dike between the 216-B-3A and 3B ponds failed in January of 1984. The discharge from the failed dike was contained with the 216-B-3B lobe. Prior to the dike failure the 216-B-3B lobe had never received any effluent. In response to the incident, the 3A and 3B lobes were isolated and trenches were dug in the bottoms of the expansion ponds to increase infiltration rates. The 216-B-3B lobe was taken out of service in May of 1985. It remained potentially active until it was clean closed in June of 1995.

Closure Info: Final: A letter was issued by the Washington State Department of Ecology on June 27, 1995, accepting the TSD clean closure certification for the 216-B-3 Expansion Ponds in accordance with Washington State Administrative Code 173-303-610 (6).

Code: 216-B-3C

Classification: Accepted

Names: 216-B-3C; B Pond Lobe C; B Pond Third Expansion Lobe

Reclassification: Closed Out (6/27/1995)

Type: Pond

Start Date: 1/1/1985

Status: Inactive

End Date: 1/1/1997

Description: The 216-3-3A, 216-B-3B and 216-B-3C Expansion Ponds are considered a single RCRA TSD unit in the Hanford Facility Dangerous Waste Part A Permit Application (section 4.2.3.11). This RCRA TSD unit was clean closed on June 27, 1995. The waste site is RCRA constituent of a pond that was used for overflow from 216-B-3 and the 216-B-3-3 ditch. The pond is a rectangular shaped pond with approximately 17 hectares (41 acres) of surface area. It was excavated into a very coarse gravel layer with a very high percolation rate. It contained eight parallel trenches that ran in a north-south direction, extending the entire length of the pond. An area on the east side of the pond has been backfilled and surface stabilized. It is posted as an Underground Radioactive Material Area. The remainder of the pond is posted as a Contamination Area. Radiological issues related to these expansion ponds will be addressed separately (see WIDS Sitecodes 216-B-3A RAD, 216-B-3B RAD, 216-B-3C RAD).

Location: The site is located east of the 200 East Area perimeter fence and southeast of the 216-B-3 Main Pond.

Related Sites/Structures: The site is associated with the PUREX facility, 216-B-3 Main Pond, 216-B-3A Lobe, 200-E-126-PL pipeline and the 200 East Powerhouse Ditch.

Process Description: The 216-B-3C Lobe was constructed in 1985 to accommodate the increased effluent flow to the B Pond complex due to the decommissioning of the 216-A-25 (Gable Pond). From 1985 to 1994, the site received overflow from the 216-B-3 Main Pond. In 1994, when the 216-B-3-3 Ditch and the 216-B-3 Main Pond sites were decommissioned, effluent was routed directly to the 216-B-3C Pond via a pipeline. The pond received diminishing amounts of effluent until 1997, when the last remaining effluent was permanently diverted to the 200 Area Treated Effluent Disposal Facility.

Waste Type: Process Effluent

Waste Description: The site received non-RCRA regulated waste water consisting of steam condensate and cooling water.

Closure Info: Final: A letter was issued by the Washington State Department of Ecology on June 27, 1995, accepting the TSD clean closure certification for the 216-B-3 Expansion Ponds in accordance with Washington State Administrative Code 173-303-610 (6).

Code: 216-B-56	Classification: Accepted
Names: 216-B-56; 216-B-56 Crib	Reclassification: Rejected (1/25/2000)
Type: Crib	Start Date:
Status: Inactive	End Date:

Description: The site is enclosed with post and chain and labeled "crib". There are no radiological postings. A site visit on July 29, 1999, found the site surrounded by post and chain and labeled "CRIB". Three risers are visible in the center of the crib. Most of the site soil with some grasses and rabbit brush growing on the surface. There is no evidence that any stabilization has taken place. The pipeline connection to the unit was not installed. A pipe exits the ground south of the crib and extends vertically above grade approximately 0.9 meters (3 feet). The vertical pipe is labeled 'end of stub.' Well 299-E28-14 (well id A6792) is located northwest of the crib's southwest corner.

Location: The crib is located northeast of the 221-B Building, north of 7th Street and south of 216-B-59 and 216-B-59B Basins.

Related Sites/ Structures: Within the crib structure, there are two 20.3 centimeter (8 inch) diameter liquid level gauge wells constructed of steel with galvanized metal caps. These wells are about 4.6 meters (15 feet) long and extend 0.9 meters (3 feet) above grade. These monitoring wells are located on each side of the pipe that runs the length of the crib. There is also a 10.2 centimeter (4 inch) vent pipe, 4.6 meters (15 feet) long rising from the north end of the distributor pipe and extending 1.2 meters (4 feet) above grade. The site was planned to be connected by a steel pipeline to 241-B-154 Diversion Box, but it never was. The crib was constructed with a side slope of 1:1.5. The crib was constructed with 1.2 meters (4 feet) of 1.9 - 3.8 centimeter (0.75 - 1.5 inch) gravel at the bottom of the crib, followed by 0.4 meters (1.25 feet) of 0.64 to 1.3 centimeter (0.25 to 0.5 inch) gravel, followed by a membrane barrier covered by sand. A membrane barrier was placed over the gravel and 0.61 meters (2 feet) up the sides of the crib. The site was then backfilled. A perforated 10.2 centimeter (4 inch) vitrified clay pipe runs the length of the crib 0.9 meters (3 feet) above the bottom. The site was associated with 221-B (B-Plant).

Process Description: Originally, the site was constructed to receive organic waste from 221-B (B-Plant). The pipeline connection to the site was never installed because of a change in disposal practices. Organic waste disposal to the ground was stopped, so this crib was never activated.

Waste Type: Process Effluent

Waste Description: The site was built but never used. No inventory is listed for the crib.

Code: 216-B-61	Classification: Accepted
Names: 216-B-61; 216-B-61 Crib	Reclassification: Rejected (1/25/2000)
Type: Crib	Start Date: 1/1/1968
Status: Inactive	End Date:

Description: The site is a backfilled crib that has never been used. It appears as a vegetated field. Boreholes, sampling, drawings, and process knowledge show that the crib was never used. The surface had been posted as a Contamination Area. The contamination is assumed to be the result of wind-blown contamination from adjacent areas (see sitecode 200-E-105). The contamination and the Contamination Area postings have been removed. The site is technically considered a Radiologically Controlled Area (RCA), because the 200 East Area perimeter fence is posted RCA. The crib is located inside the perimeter fence.

Location: The unit is 152 meters (500 feet) northwest of 241-BY Tank Farm and 61 meters (200 feet) south of 12th Street.

Related Sites/ Structures: The surface of the crib and an extended area to the south had been posted as a Soil Contamination Area (SCA). The posted SCA is WIDS site 200-E-105. The pipeline associated with this crib is sitecode 200-E-181-PL. The length of the pipeline that leads from the waste line toward the crib is 268 meters (880 feet) long, 10 centimeters (4 inch) diameter carbon steel and was designed for a waste flow up to 45.4 liters (12 gallons) per minute with equal distribution over the crib area. However, the final 60 meters (200 feet) and the tie-in connecting the 216-B-61 Crib pipeline to the waste transfer line were never installed (per 1973 drawing H-2-34522, Rev. 2). Groundwater wells 299-E33-25 and 299-E33-26 were originally drilled for the purpose of monitoring 216-B-61 Crib waste.

Process Description: The crib was built to receive intermediate level process condensate from the ITS #1 unit (located in the 241-BY Tank Farm) when the 216-B-50 Crib reached its radionuclide capacity. However, the 216-B-61 crib was never used. A 0.6 meter by 0.6 meter by 0.3 foot (2 foot by 2 foot by 1 foot) thick concrete pad was laid in the crib bottom. The crib was filled with 122 cubic meters (160 cubic yards) of 1.9 to 7.6 centimeter (0.75 to 3 inch) gravel. 279 square meters (3,000 square feet) of plastic membrane barrier were laid over the gravel. 22 cubic meters (30 cubic yards) of sand were laid over the membrane. A gage well constructed of vitrified clay 20 centimeters (8 inches) in diameter and 3.96 meters (13 feet long) extended from the crib bottom to 0.6 meters (2 feet) above grade. This vent pipe has a filter on top of the pipe. The bottom 0.6 meters (2 feet) of the pipe are perforated. A 10.2 centimeter (4 inch) diameter perforated pipe runs the length of the crib, 0.3 meters (1 foot) above the bottom of the crib.

Waste Type: Steam Condensate

Waste Description: This crib was built to receive condensate from the ITS (In Tank Solidification) unit, but never received any waste. It was never used.

Code: 217-B NU	Classification: Accepted
Names: 217-B NU; Elementary Neutralization Unit/217-B Building; 217-B Neutralization Unit	Reclassification: Rejected (6/18/2014)
Type: Neutralization Tank	Start Date: 1/1/1993
Status: Inactive	End Date:

Description: The site has been evaluated and reclassified to Rejected. 217-B is a structural steel frame building with corrugated asbestos/cement siding on a concrete slab. The building has one room containing the deactivated demineralizer, chemical regeneration tanks, and piping. Entrances to this unit have been sealed.

TPA-MP-14, Rev. 2, Section 2.0 states that WIDS does not document buildings or facilities that do not contain TSD units. It further states that, after buildings are demolished, the footprint will be evaluated for potential soil contamination. If present, the soil contamination will be added to WIDS as a Discovery Site.

Location: The 217-B Building is directly north of the 221-B Canyon and northeast of 271-B.

Related Sites/ Structures: Structures associated with this site include supply and return water lines, blanked steam supplies, and the demineralizer equipment.

Process Description: The building is currently inactive because a new ion pure system was installed in 271-B during 1993. From 1985 to 1993, the building used an Illinois water treatment demineralizer system to provide demineralized water to the B Plant and Waste Encapsulation and Storage Facility. The systems resin was depleted in 1993. Sulfuric acid and nitric acid were used to regenerate the ion exchange columns.

Waste Type: Asbestos (non-friable)

Waste Description: The building has concrete/asbestos corrugated siding.

Waste Type: Chemicals

Waste Description: Demineralizer operations generated waste when the ion exchange columns were regenerated. Sodium hydroxide was used to regenerate the anion column, while sulfuric acid was used to regenerate the cation column. The sulfuric acid was neutralized with sodium carbonate, while the sodium hydroxide was neutralized with monosodium phosphate prior to discharge the 216-B-63 trench.

Code: 221-B NANU	Classification: Accepted
Names: 221-B NANU; 221-B Nitric Acid Neutralization Unit; 221-B Elementary Neutralization Unit for Nitric Acid	Reclassification: Interim No Action (10/6/2005)
Type: Neutralization Tank	Start Date: 1/1/1980
Status: Inactive	End Date: 1/1/1997

Description: This site had been a blue plastic, acid neutralization tank. The tank has been excessed.

Location: The tank was located inside the 211-BA building, north of 221-B.

Related Sites/ Structures: The site was associated with the B Plant chemical sewer.

Process Description: Chemical waste from 221-B and 217-B flowed through underground chemical sewer lines to a lift station located near the southwest corner of 211-BA. The effluent was pumped out of the chemical sewer and into 211-BA building where it was diverted either to the acid neutralization tank or the sodium hydroxide neutralization tank to adjust the pH levels. The neutralized waste was released back into the underground chemical sewer line for disposal.

Waste Type: Process Effluent

Waste Description: Approximately 400 gallons (1,500 liters) per year of 1 Molar nitric acid is neutralized with 350 pounds (160 kilograms) per year of sodium carbonate.

Code: 221-B SDT	Classification: Accepted
Names: 221-B SDT; 221-B Settle and Decant Tank; 221-B-8-1 and 221-B-8-2; 221-B-TK-8-1 and 221-B-TK-8-2; B Plant Settle and Decant Tank	Reclassification: None
Type: Settling Tank	Start Date: 1/1/1945

Status: Inactive**End Date:****Description:** The 221-B Settle and Decant Tank consists of two cylindrical tanks in Cell 8: 221-B-8-1 and 221-B-8-2. The two tanks are isolated and decommissioned. The tanks were used in the neutralized current acid waste pretreated mission.**Location:** The two tanks take up most of the spare Cell 8, near the east end of 221-B Building.**Related Sites/ Structures:** Structures associated with this site include the cell, the jumpers and transfer lines in this cell, the two tanks in the cell, and the rest of the neutralized current acid waste system.**Process Description:** The unit was designed to operate as part of the neutralized current acid waste treatment process. The tanks were used as part of the primary solid/liquid separation process where solids were allowed to settle and the supernatant was decanted.**Waste Type:** Chemicals**Waste Description:** The unit received neutralized current acid waste during the pretreatment mission, where the tanks acted as settling tanks. Prior to this, the tanks were used in the cesium and strontium recovery efforts.**Code:** 221-B SHNU**Classification:** Accepted**Names:** 221-B SHNU; 221-B Sodium Hydroxide Neutralization Unit; 221-B Elementary Neutralization Unit for Sodium Hydroxide**Reclassification:** Interim No Action (10/6/2005)**Type:** Neutralization Tank**Start Date:** 1/1/1984**Status:** Inactive**End Date:** 1/1/1997**Description:** This site had been a blue plastic, sodium hydroxide neutralization tank. The tank has been exceeded.**Location:** The tank was located inside the 211-BA building, north of 221-B.**Related Sites/ Structures:** The site is associated with the B Plant chemical sewer.**Process Description:** Chemical waste from 221-B and 217-B flowed through underground chemical sewer lines to a lift station located near the southwest corner of 211-BA. The effluent was pumped out of the chemical sewer and into 211-BA building where it was diverted either to the acid neutralization tank or the sodium hydroxide neutralization tank to adjust the pH levels. The neutralized waste was released back into the underground chemical sewer line for disposal.**Waste Type:** Process Effluent**Waste Description:** Approximately 400 gallons (1,514 liters) per year of 2 Molar sodium hydroxide is neutralized with 800 pounds (360 kilograms) per year of monosodium phosphate.**Code:** 221-B-WS-1**Classification:** Accepted**Names:** 221-B-WS-1; B Plant Storage**Reclassification:** None**Type:** Storage**Start Date:****Status:** Inactive**End Date:****Description:** This cell is a heavy walled concrete pit with a concrete block cover. The cover is the only means of entry. The cell is currently used for contained storage.

Location: Cell 4 is located near the west end of the B Plant Canyon, inside 221-B.

**Related Sites/
Structures:** Structures associated with this cell include: the hoist and cover blocks, the canyon deck, and any equipment or piping which remains in the cell.

**Process
Description:** This cell is now used to store drums of solid mixed waste (with no free liquids).

Waste Type: Misc. Trash and Debris

**Waste
Description:** Material stored in this area includes light bulbs with lead solder, and other solid mixed waste.

Code: 221-B-WS-2 **Classification:** Accepted

Names: 221-B-WS-2; B Plant Waste Piles **Reclassification** None

Type: Storage **Start Date:** 1/1/1945

Status: Inactive **End Date:**

Description: The TPA and the RCRA Part A Permit Application classify this site as a waste pile that lies within a containment building. The site encompasses solid mixed waste (jumpers, counterweights, failed process equipment, and shielding) that is stored in cells and on the canyon deck.

Location: The location of the waste piles include the 221-B Canyon Deck and Cells, inside 221-B.

**Related Sites/
Structures:** Since this storage site includes the canyon deck and most of the cells, there are many structures associated with the site. Associated structures include: piping, tanks, cells, overhead equipment, tools, instrumentation, and process materials.

**Process
Description:** The designation of this area as a Treatment Storage or Disposal Unit is intended to satisfy requirements for the storage of solid/mixed waste within the canyon cells and on the canyon deck.

Waste Type: Equipment

**Waste
Description:** This waste includes lead shielding in the cells and on the canyon deck.

Waste Type: Equipment

**Waste
Description:** This waste includes jumpers, and other failed or isolated process equipment which may have been contaminated with wastes from fuel processing.

Code: 221-B-26-1 **Classification:** Accepted

Names: 221-B-26-1; 221-B-TK-26-1; B Plant Radioactive Organic Waste Solvent Tank 1 **Reclassification** None

Type: Storage Tank **Start Date:** 1/1/1945

Status: Inactive **End Date:**

Description: This tank is a stainless steel cylindrical tank.

Location: The tank is located on the south side of cell 26.

**Related Sites/
Structures:** Structures associated with the tank include piping and fittings, the other cell 26 tanks,

equipment, and instrumentation.

Process Description: This tank was used to support the solvent extraction and organic treatment process that was performed at the B Plant to recover strontium from PUREX acidified sludge.

Waste Type: Chemicals

Waste Description: This tank received organic mixed waste from the solvent extraction process of the strontium recovery program. The tank is maintained ready for use on an as needed basis.

Code: 221-B-27-2 **Classification:** Accepted

Names: 221-B-27-2; 221-B-TK-27-2; 221-B Tank 27-2 **Reclassification:** None

Type: Storage Tank **Start Date:**

Status: Inactive **End Date:**

Description: The tank is only visible if the cell cover blocks are removed. The tank is a 7,571 liter (2000 gallon) stainless steel tank.

Location: The tank is located inside cell #27, inside the 221-B Plant canyon.

Process Description: The 221-B-27-2 tank is part of the organic mixed waste storage system that was contained in cells 26, 27, 28, 29 and 30 of the B Plant canyon. The organic waste was used in the recovery and purification of strontium and cesium.

Waste Type: Process Effluent

Waste Description: The tank contained organic mixed waste used in the recovery and purification of strontium and cesium.

Code: 221-B-27-3 **Classification:** Accepted

Names: 221-B-27-3; 221-B-TK-27-3; B Plant Radioactive Organic Waste Solvent Tank 2 **Reclassification:** None

Type: Storage Tank **Start Date:** 1/1/1963

Status: Inactive **End Date:**

Description: This tank is a carbon steel cylinder, with an internal cooling coil and 17 nozzles on the head of the tank.

Location: The tank is located in the northeast corner of cell 27.

Related Sites/Structures: Structures associated with this tank include piping and fittings, the other cell 27 tanks and equipment, and instrumentation.

Process Description: This tank was used to support the solvent extraction and organic treatment process that was performed at the B Plant to recover strontium from PUREX acidified sludge.

Waste Type: Chemicals

Waste Description: This tank received organic mixed waste from the solvent extraction process of the strontium recovery program. The tank contained waste as of September 1996.

Code: 221-B-27-4 **Classification:** Accepted

Names: 221-B-27-4; 221-B-TK-27-4; B Plant
Radioactive Organic Waste Solvent Tank 3

Reclassification: None

Type: Storage Tank

Start Date: 1/1/1963

Status: Inactive

End Date:

Description: This tank is a rectangular, stainless steel slab tank.

Location: This tank is in the northwest corner of cell 27.

Related Sites/ Structures: Associated structures for this sight include the other cell 27 tanks, piping and instrumentation.

Process Description: This tank was used to support the solvent extraction process that was performed at the B Plant to recover strontium from PUREX acidified sludge.

Waste Type: Chemicals

Waste Description: This tank received organic mixed waste from the solvent extraction process of the strontium recovery program.

Code: 221-B-28-3

Classification: Accepted

Names: 221-B-28-3; 221-B-TK-28-3; B Plant
Radioactive Organic Waste Solvent Tank 4

Reclassification: None

Type: Storage Tank

Start Date: 1/1/1963

Status: Inactive

End Date:

Description: This tank is a stainless steel cylindrical tank.

Location: This tank lies in the northeast corner of cell 28.

Related Sites/ Structures: Structures associated with this tank include the other cell 28 tanks, equipment, and piping.

Process Description: This tank was used to support the solvent extraction and organic treatment process that was performed at the B Plant to recover strontium from PUREX acidified sludge.

Waste Type: Chemicals

Waste Description: This tank received organic mixed waste from the solvent extraction process of the strontium recovery program. The tank contained waste as of September 1996.

Code: 221-B-28-4

Classification: Accepted

Names: 221-B-28-4; 221-B-TK-28-4; B Plant
Radioactive Organic Waste Solvent Tank 5

Reclassification: None

Type: Storage Tank

Start Date: 1/1/1963

Status: Inactive

End Date:

Description: This tank is a rectangular, stainless steel slab tank.

Location: This tank is located in the northwest corner of cell 28.

Related Sites/ Structures: Structures associated with this tank include other cell 28 tanks, equipment, and piping.

Process Description: This tank was used to support the solvent extraction process that was performed at the B Plant to recover strontium from PUREX acidified sludge.

Waste Type: Chemicals

Waste Description: This tank received organic mixed waste from the solvent extraction process of the strontium recovery program. The tank was empty as of September 1996.

Code: 221-B-29-4 **Classification:** Accepted

Names: 221-B-29-4; 221-B-TK-29-4; B Plant **Reclassification:** None
Radioactive Organic Waste Storage Tank #7; 221-B TK-29-4

Type: Storage Tank **Start Date:** 1/1/1961

Status: Inactive **End Date:**

Description: This tank is a stainless steel cylindrical tank.

Location: This tank is located along the middle of the eastern half of cell 29.

Related Sites/Structures: The structures related to this tank include the other cell 29 tanks, equipment, and piping.

Process Description: This tank was used to support the solvent extraction process that was performed at the B Plant to recover strontium from PUREX acidified sludge.

Waste Type: Chemicals

Waste Description: This tank received organic mixed waste from the solvent extraction process of the strontium recovery program. The tank was empty as of September 1996.

Code: 221-B-30-3 **Classification:** Accepted

Names: 221-B-30-3; 221-B-TK-30-3; B Plant **Reclassification:** None
Radioactive Organic Waste Solvent Tank #6; 221-B TK-30-3

Type: Storage Tank **Start Date:** 1/1/1963

Status: Inactive **End Date:**

Description: This tank is a rectangular, stainless steel slab tank.

Location: This tank resides in the northeastern corner of cell 30.

Related Sites/Structures: Structures associated with this tank include cell 30 tanks, piping, and equipment.

Process Description: This tank was used to support the solvent extraction process that was performed at B Plant to recover strontium from PUREX acidified sludge.

Waste Type: Chemicals

Waste Description: This tank received organic mixed waste from the solvent extraction process of the strontium recovery program. The tank was empty as of September 1996. This tank is maintained so it can receive waste on an as needed basis.

Code: 224-B	Classification: Accepted
Names: 224-B; 224-B Concentration Facility	Reclassification: None
Type: Process Unit/Plant	Start Date: 1/1/1945
Status: Inactive	End Date: 1/1/1976

Description: The 224-B Concentration Facility is a roughly rectangular concrete block structure.

Location: This building lies south of the 221-B Canyon, and west of 222-B Laboratory.

Related Sites/ Structures: Structures associated with this facility include tanks, agitators, process equipment, and instrumentation.

Process Description: The 224-B Concentration Facility received dilute plutonium nitrate solution that was the product of the 221-B Bismuth Phosphate process. This facility purified and reduced the volume of product. After concentration, the plutonium nitrate product was then shipped from 224-B to the 231-Z Isolation Building. The Plutonium Concentration Facility concentrated the liquid output from the plutonium separations plant from 1,249 liters to 30 liters. The concentration took place in six radiologically contaminated process cells (Cells A, B, C, D, E, & F), located in the southeastern 1/3 of the 224-T building. The cells contained various tanks and piping. Cells A, B, D, and E contained a 40 inch centrifuge on a platform. Cell C is a pit that connects to the underground pipe tunnel from Sections 13 & 14 of 221-T. Cell F was "L" shaped and included an office and a glass enclosure where partial finished product was collected for transfer to 231-W. The contaminated process cell equipment was flushed when the process was terminated (1960's). The amount of radiological or regulated material remaining within the process cells and piping is unknown. The plutonium concentration process was identical to the concentration process done at 224-T in 200 West Area. A thorough radiological characterization was done of the 224-B Hot Cells in 1985. An inventory of radioactive material remaining in the 224-B hot cells, based on average measurements, estimated 1.1 curies of cesium-137, 22 curies of strontium-90, 3.7 curies of cobalt-60, 5 curies of americium-241, 31 curies of plutonium-239 and 2 curies of other plutonium isotopes.

Waste Type: Chemicals

Waste Description: The building contains residual processing agents. Hazardous constituents include mercury, polychlorinated biphenyls, cleaning agents, and radionuclides (including plutonium, americium, strontium, cobalt, and cesium). An inventory of radioactive material remaining in the 224-B hot cells (1985), based on average measurements, is estimated to be 1.1 curies of Cs-137, 22 curies of Sr-90, 3.7 curies of Co-60, 5 curies of Am-241, 31 curies of Pu-239 and 2 curies of other plutonium isotopes.

Waste Type: Equipment

Waste Description: This facility contains radiologically contaminated equipment, and concrete surfaces.

Code: 226-B HWSA	Classification: Accepted
Names: 226-B HWSA; 226-B Hazardous Waste Storage Area	Reclassification: Rejected (9/6/2000)
Type: Storage Pad (<90 day)	Start Date: 1/1/1985
Status: Active	End Date:

Description: Documents dated 1987 and 1992 described the site known as the 226-B Hazardous Waste Storage Area (HWSA) as a concrete pad surrounded by a light chain barricade. It was posted with "226-B Hazardous Waste 90-Day Staging Area", and "PCB 30 Day Storage" signs.

Additional information was provided by Ron Weissenfels (B-Plant Engineer) in 1998 that described the area as temporarily being three separate storage pads located north of B-Plant, and adjacent to the 211-BA and 219-B Buildings. However, a field visit in April 2000 found only one small, locked metal shed labeled "226-B<90 Day Storage - Dangerous/Hazardous Waste". Correspondence with the responsible contractor confirmed that the three pads were consolidated into one location prior to the area being turned over to WESF (Waste Encapsulation and Storage Facility).

Location: The pad is located north of B Plant, north of 211-BA and 219-B Buildings.

Related Sites/ Structures: This storage pad is associated with B Plant activities and 200-E-32.

Process Description: This staging area provides temporary (less than 90 days) storage for hazardous wastes. The first waste receipt was on May 30, 1985.

Waste Type: Chemicals

Waste Description: The staging areas temporarily store a wide variety of dangerous waste. Examples of waste previously stored here include: halogenated hydrocarbons, caustic liquids, acids, solvents, toxic chemicals and coolants and PBC's.

The Following Sites Were Consolidated With This Site:

Code: 200-E-32

Names: 200-E-32; 226-B Pad East Side 90-Day Waste Accumulation Area

Code: 242-B

Classification: Accepted

Names: 242-B; 242-B Evaporator

Reclassification: Rejected (6/18/2014)

Type: Evaporator

Start Date: 1/1/1951

Status: Inactive

End Date: 1/1/1985

Description: The WIDS site has been evaluated and reclassified to Rejected. TPA-MP-14, Rev. 2, Section 2.0 states that WIDS does not document buildings or facilities that do not contain TSD units. It further states that, after buildings are demolished, the footprint will be evaluated for potential soil contamination. If present, the soil contamination will be added to WIDS as a Discovery Site. The facility remains in a shutdown condition. The following sections describe as of September 1998.

The 242-B Building was constructed in 1952 and used during the Hanford production plant era as a waste tank supernate evaporation facility. Originally, the building consisted of three sections. The north section contained the evaporator vessel (a steam-heated pot evaporator) along with the associated process components. The center section consisted of the control facilities (a plutonium laboratory, a storage room, a change room, an office area, and lunch room). Use of the building as an evaporation facility was terminated in 1962. At that time, Rooms 1 and 2 of 242-B were cleaned up to some extent and the waste evaporation equipment was removed and buried. The 242-B building became a research facility operated by PNL-BNW.

Location: 242-B Evaporator building is located on the east side of Baltimore Ave., south of the 241-B Tank Farm fence.

Related Sites/ Structures: 242-B Evaporator interconnected with the following 242-B building components: cyclone stainless steel catch tank (75 gallons/284 L), cyclone separator, condenser, two catch tanks (4,185 gallons/15,840 L), feed tank (4,185 gallons/15,840 L), two pre-heaters (75 gallons/284 L).

Waste was also directed to the following: 241-B-152, 241-B-154, 241-BR-152, 242-B-151, 241-C-152 diversion boxes; 241-B-104, 241-B-105, 241-B-106, 241-B-107, 241-B-108, 241-B-109, 241-C-109 single shell tanks; 241-B Retention Basin; 216-B-37 retention trench and the 216-B-11A and 216-B-11B reverse wells.

242-B is associated with 242-BL, the Cask Loadout Facility.

This site is also associated with the 2607-E9 septic tank and tile field and the 200-E-176-A and 200-E-176-B pipelines.

Process Description: The 242-B Facility was the former first cycle evaporator building and former control building. The evaporator was installed to evaporate cladding/first cycle waste and reduce the waste volume.

In the 1960's, PNL began using the facility as an Aerosol Research Facility. Studies such as free fall of powders and liquids and the burning of various types of materials were conducted. PNL also participated in tests on ruptured fuel, conducted in 242-B and 242-BL.

From 1970 through 1980s, the 242-B Building, except Rooms 1 and 2, was used for research on radioactive particles. This work consisted of simulating accidents related to airborne releases of radioactive material using depleted uranium as the particle. A wind tunnel and radioactive aerosol release tanks (RART) remain installed in Room 4 of the facility.

Waste Type: Equipment

Waste Description: Until October 1954, the treatment unit received byproduct cake solution and waste solution from the first decontamination waste cycle associated with the 241-B tank farm. The waste contained ~10% of original fission product, 1% Plutonium, and the remainder of miscellaneous chemicals. The major chemical component was bismuth phosphate. Over its active life, the unit processed (evaporated) 7,172,000 gallons (27,146,020 L) of waste.

Waste Type: Soil

Waste Description: Soil contamination exists outside the facility. Some of the contamination can be attributed to a diverter box failure from the tank farm operations in the nearby 241-B Tank Farm. Tank 241-B-103 historically would "burp" and contaminate the surroundings. The 207-B basin, located south of 242-B, also was known to have "upsets" which led to general contamination of the area around the retention basin.

Code: 215-C	Classification: Not Accepted
Names: 215-C; 215-C Gas Preparation Building	Reclassification: None
Type: Process Unit/Plant	Start Date: 1/1/1949
Status: Inactive	End Date: 1/1/1985

Description: The 215-C Gas Preparation Building is single-level concrete building that was within the radiation control area for the Semiworks Complex. The building has two rooms and a gas bottle storage area on the south side of the building. The building is now adjacent to the Hot Semi Works surface stabilized area, known as WIDS sitecode 200-E-41. Site visits in 2005 and 2007 found a Contamination Area posting is attached to the stairway to the 215-C roof, indicating contamination on the roof.

TPA-MP-14, Rev. 2, Section 2.0 states that WIDS does not document buildings or facilities that do not contain TSD units. Therefore, this has been classified as Not Accepted. It further states

that, after buildings are demolished, the footprint will be evaluated for potential soil contamination. If present, the soil contamination will be added to WIDS as a Discovery Site.

Location: This building is located in the Semiworks Area, directly south of Seventh Street.

Related Sites/ Structures: The associated structures for this site include other Semiworks facilities, and the equipment stored within the building.

Process Description: The 215-C Gas Preparation Building was constructed to support the 201-C Process Building. It provided compressed air for pneumatic equipment and instruments. It also supplied inert gas for use in the 201-C Building. In 1985, the unit was decontaminated and almost all equipment was removed from in and around the building. It has later been used for the storage of miscellaneous equipment. The building is currently empty, except for one or two pieces of original equipment. There are no active systems. The electricity to this facility was disconnected and removed from the pole in 1997.

Waste Type: Equipment

Waste Description: The unit consists of a previously radioactively contaminated structure. The building was decontaminated in 1985, and was subsequently used to store equipment. The Semiworks Aggregate Area Management Study Report (DOE/RL-92-18) does not show any remaining radionuclide waste inventory for the 215-C Building.

Code:	200-E PAP	Classification:	Accepted
Names:	200-E PAP; 200-E Powerhouse Ash Pit and Ash Disposal Pile; Ash Basin	Reclassification	Rejected (5/21/2008)
Type:	Coal Ash Pit	Start Date:	1/1/1943
Status:	Inactive	End Date:	1/1/1998

Description: The ash pit is a large open depression located east of the 284-E Powerhouse. The Ash Disposal Pile is a large mound of material dredged, over years of operation, from the Ash Pit.

Location: The Ash Pit is located inside 200 East Area, south of 4th Street and 30 meters (100 feet) east of the 284-E Powerhouse. The Ash Disposal Pile is located east of the Ash Pit.

Related Sites/ Structures: This pit received ash from the 284-E Powerhouse.

Process Description: The site received ash from the 200 East Powerhouse. The powerhouse consisted of three coal fired boilers that were used to generate steam for the 200 East Area. An ash and water slurry was produced when the ash was sluiced from the powerhouse. The slurry was placed in the 200 East Powerhouse Ash Pit. When the ash pit became full, heavy equipment was used to remove the ash from the pit and place it in the Ash Disposal Pile, located east of the Ash Pit. The ash pit is a large basin divided into two parts by an earthen dam. Ash slurry could be directed to either compartment. The compartments were used alternately to allow one side to dry while the other was being filled. The rate of ash generation was approximately 9,480 cubic yards per year (7252 cubic meters per year) when the powerhouse was active. The pit capacity was approximately 81,020 cubic yards (61980 cubic meters) of ash. The dried ash was removed (pushed with bull dozers) periodically from the ash basins and placed in the eastern portion of the Ash Pit (known as the disposal pile). As of April 2000, the remaining ash in the pit and disposal pile is estimated to be less than a meter deep.

Waste Type: Ash

Waste Description: A waste determination of the Hanford Site 200 Area steam plant ash was performed in the early 1990s. The coal ash waste stream was determined to be nondangerous. Samples were analyzed

using the TCLP (Toxicity Characteristic Leaching Procedure), and all were below the regulatory limits. Eleven sample results were also reported for pH: the results ranged from 7.66 to 11.91, with an average of 9.27. The second and third highest pH results were 10.09 and 9.94.

The rate of ash generation was approximately 9,480 cubic yards per year (7252 cubic meters per year) when the powerhouse was active. The pit held approximately 81,020 cubic yards (61980 cubic meters) of ash.

Code: 200-E-3 **Classification:** Accepted

Names: 200-E-3; Paint/Solvent Dump; Toluene Dump Site **Reclassification:** Consolidated (5/6/2004)

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The site consists of an area inside a large depression. The bottom of the pit has hard pan type soil, while the sides are gravel and sand. Asphalt and other debris are on the sides of the road berm. There is no visual evidence of the dumping.

Location: The Waste Information Data System (WIDS) Information Form submitted on September 3, 1992 states the location is a pit adjacent to a berm on the north end of the 241-AN Tank Farm and west of Canton Avenue inside 200 East Area.

Release Description: There are two reports of releases to the pit north of 241-AN Tank Farm. In 1991, it was reported that approximately 39 liters (10 gallons) of toluene was dumped inside the pit during the summer of 1984 or 1985. In 1995, two ICF Kaiser painters reported disposing of liquid paint waste to the ground inside the pit north of 241-AN Tank Farm. They recalled dumping approximately 95 liters (25 gallons) of liquid in one visit and another 95 liters (25 gallons) in a second visit. In 1996, a visit to the pit with one of the painters verified the pit north of 241-AN Tank Farm, just west of Canton Ave. as the dumping site location. He indicated the area in the southeast portion of the pit as the dump site. The area effected by the chemical dumping measured approximately 9 meters by 9 meters (30 feet by 30 feet).

Waste Type: Chemicals

Waste Description: The waste dumped into the pit included approximately 229 liters (60 gallons) of paint wastes like toluene, solvents, and methyl ethyl ketone.

This Site Was Consolidated With:

Code: 200-E-10

Names: 200-E-10; 200-E-3 Toluene Dump Site; Paint/Solvent Dump South of Sub Trenches

Code: 200-E-5 **Classification:** Accepted

Names: 200-E-5; 2607-E2; 2607-E2 Septic Tank & Tile Field **Reclassification:** None

Type: Septic Tank **Start Date:** 1/1/1948

Status: Inactive **End Date:** 1/1/1997

Description: The septic tank has three access ports. It is a single compartment 18,730 liter (4950 gallon) capacity tank with a 1900 liter (500 gallon) dosing siphon. As of February 15, 2001, it was not marked in the field.

Location: The tank and drain field are located in the south portion of 200 East Area, adjacent to 1st Street and east of Baltimore Ave.

Related Sites/ Structures: It is associated with MO-245, 246, 247 and 248, which are located south of 2750-E.

Process Description: The septic system serviced mobile office units (MO-245, MO-246, MO-247 and MO-248) that did not contain radioactive material.

Waste Type: Sanitary Sewage

Waste Description: The septic system serviced mobile office trailers that did not contain radioactive material.

Code: 200-E-8 **Classification:** Not Accepted

Names: 200-E-8; 200 East Trench 94 Diesel Spill **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1995

Status: Inactive **End Date:**

Description: The spill occurred in the northwest portion of Trench 94. There is no longer any visible evidence of the spill. The spill site was remediated on June 15, 1995.

Location: Trench 94 is in the northeast corner of the 218-E-12B Burial Ground. The burial ground is in the northeast corner of 200 East Area.

Release Description: On May 1, 1995, the Westinghouse Solid Waste Management group was notified that discolored soil had been observed in the northwest corner of Trench 94. The spot measured 9.7 meters by 4.5 meters (32 feet by 15 feet). The spill was determined to be a release of approximately 37 to 40 liters (10 to 15 gallons) of diesel oil. The soil was discolored and had a diesel fuel odor. The soil was saturated, but there was no standing liquid. It appeared that the spill had occurred approximately one week previous to being reported.

Related Sites/ Structures: The site is associated with the 218-E-12B burial ground.

Waste Type: Oil

Waste Description: The spilled material consisted of 38 to 57 liters (10 to 15 gallons) of diesel oil to the soil.

Code: 200-E8 BPDS **Classification:** Accepted

Names: 200-E8 BPDS; 218-E-8 Borrow Pit Demolition Site; 218-E8 BPDS; 218-E-8 BPDS; 200-E Burn Pit Demolition Site; 200-E8 Borrow Pit Demolition Site **Reclassification:** Closed Out (10/26/1995)

Type: Experiment/Test Site **Start Date:** 1/1/1984

Status: Inactive **End Date:** 1/1/1995

Description: The chemical demolition site is no longer marked or posted. A single event of thermal treatment of abandoned chemicals occurred in November 1984. The RCRA TSD was closed in 1995.

Location: The site was in the located in the northeast corner of 200 East Area, inside the 200-E Burn Pit. It is east of the 218-E-8 Burial Ground.

Related Sites/ Structures: The site is associated with the 200 East Burn Pit (200-E BP).

Process Description: The site was used as a thermal treatment (detonation) pit for excess shock sensitive or potentially explosive chemical waste in 1984. A single event of thermal treatment of abandoned chemicals occurred in November 1984.

Waste Type: Chemicals

Waste Description: This unit had detonations of the following chemicals: 1984: Isopropyl Ether 8 L (2.1 gal), 1,4-Dioxane 1,250 mL (0.33 gal), 2-Butoxyethanol 19 L (5.0 gal), Methyl Ethyl Ketone 177 mL (0.05 gal), Hydrogen Peroxide 11.36 L (3.0 gal), Dioxane 946 mL (0.25 gal), Sodium Azide 473 mL (0.12 gal), Phosphoric Acid 189 L (0.05 gal); 1985: None; 1986: None.

Code: 200-E-9 **Classification:** Accepted

Names: 200-E-9; 2607-EN; 2607-EN Septic Tank/Pump Station; 2727-E Septic System **Reclassification:** None

Type: Septic Tank **Start Date:**

Status: Active **End Date:**

Description: The above ground area is posted "Septic Tank 2607-EN". The area is surrounded with metal fence posts and chain. Three concrete and one PVC cylinders (manholes) with covers protrude above grade in the underground tank area. The surface is disturbed and covered with Russian thistle, cheat grass, and other weedy species. Two "Sanitary Tile Field" signs are located south of the septic tank.

Location: The site is 75 feet south of the southwest corner of the 2727-E Safeguards and Security Building (which is in 200 East Area on 4th Street).

Related Sites/ Structures: The 2727-E building was serviced by this septic system.

Process Description: Receives sanitary sewage from 2727-E Safeguards and Security Building.

Waste Type: Sanitary Sewage

Waste Description: Sanitary sewage from 2727-E Safeguards and Security Building.

Code: 200-E-10 **Classification:** Accepted

Names: 200-E-10; 200-E-3 Toluene Dump Site; Paint/Solvent Dump South of Sub Trenches **Reclassification:** Rejected (5/13/2008)

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: A site visit in 1997 identified a large gravel depression north of 241-AN Tank Farm. The site consists of an area within this large depression. The bottom of the depression has hard pan type soil, while the sides are gravel and sand. Asphalt and other debris are on the sides of the road berm. Another site visit in May 2004 found the appearance has not changed. There is no definite visual evidence of liquid dumping. The actual dumping area is not marked or posted.

Location: The site is located north of 241-AN tank farm and west of Canton Avenue inside the 200 East Area.

Release Description: In 1991, it was reported that approximately 39 liters (10 gallons) of toluene was dumped inside the pit north of 241-AN Tank Farm during the summer of 1984 or 1985. In 1995, two ICF Kaiser painters reported disposing of liquid paint waste to the ground inside the pit north of 241-AN Tank Farm. They recalled dumping approximately 95 liters (25 gallons) of liquid in one visit and another 95 liters (25 gallons) in a second visit. In 1996, a visit to the pit with one of the painters verified the pit north of 241-AN Tank Farm, just west of Canton Ave. as the dumping site location. He indicated the place in the southeast portion of the pit as the area effected by the dumping. It measured approximately 9 meters by 9 meters (30 feet by 30 feet).

Waste Type: Chemicals

Waste Description: The waste dumped into the pit included approximately 229 liters (60 gallons) of paint wastes like toluene, solvents, and methyl ethyl ketone. CERCLA reportable quantities are listed at 40 CFR 302, in Table 302.4. The RQ for toluene is 1000 lbs. There is no RQ listing for paint. The reported disposal at 200-E-10 was 25 gallons (twice) = 50 gallons, or about 400 pounds. Conservatively estimating the paint as 100% toluene, the disposal was less than the CERCLA RQ. Therefore, the release was not (is not) a threat to human health and the environment.

The Following Sites Were Consolidated With This Site:

Code: 200-E-3

Names: 200-E-3; Paint/Solvent Dump; Toluene Dump Site

Code: 200-E-11

Classification: Not Accepted

Names: 200-E-11; Diesel Oil Spill at BX-BY Tank Farm

Reclassification: None

Type: Unplanned Release

Start Date: 1/1/1995

Status: Inactive

End Date: 1/1/1995

Description: The site is a spill of non-regulated diesel oil on August 7, 1995. The oil and soil were excavated and the site backfilled by September 7, 1995.

Location: The incident occurred just outside the fence directly west of tanks BY-112 and BY-111.

Release Description: A fuel truck driver on his daily refueling rounds discovered a leak of diesel oil from a generator. It was discovered that about 75 to 95 liters (20 to 25 gallons) had leaked out of the unit's two 57-liter (15-gallon) tanks. The oil had leaked out of a failed gasket on the fuel suction line between the tank and first fitting. The tanks were cascaded, and thus the fuel from the second tank was siphoned out. An analysis of the fuel was made, and it was determined that the fuel was non-regulated.

Waste Type: Oil

Waste Description: The spill was diesel oil.

Code: 200-E-12

Classification: Accepted

Names: 200-E-12; Sand Piles from RCRA General Inspection #200EFY95 Item #5

Reclassification: Rejected (1/19/2000)

Type: Laboratory

Start Date:

Status: Inactive

End Date:

Description: A 1995 site inspection discovered this site and described it as two sandy areas which are a different color sand than the surrounding sand. The two sand piles were approximately 27 meters (30 yards) apart. During a February 1997 visit, an empty, stainless steel tank and a

nearby pit were also observed at the site. The tank, labeled "X-12," measured 1.47 meters (58 inches) high and 1.35 meters (53 inches) in diameter. The area has been roped off with steel posts and rope. The sandy areas were approximately 3.7 meters (4 yards) in diameter. The site was visited again on August 26, 1998, for a GPS survey. The two sand piles appeared to have been removed; only traces of the piles remained. Between the remains of the two sand piles were equipment for some sort of experiment. A small pit with deteriorated clear plastic was observed by the "X-12" tank. The experiment equipment consisted of two large polypropylene water tanks, a large rectangular pit and a metal frame set up over the pit. One of the tanks was 2.7 to 3.0 meters (9-10 feet) tall with a 2840 liter (750 gallon) capacity. It was labeled "Non Hazardous River Water" and appeared to be approximately half full. The second water tank was only about 1.5 meters (5 feet) tall and had a larger diameter than the first tank. It was also labeled "Non Hazardous River Water" and appeared to be approximately three-quarters full. There were no volume markings on this tank. The shorter tank was also posted "Experiment in Process, Contact Ray Clayton @ 372-6037." The rectangular pit was approximately 4.6 meters (15 feet) long and 1.5 meters (5 feet) wide and 0.9 meters (3 feet) deep. The bottom of the pit was covered with a tarp and the sides appeared to be covered with plywood. Over the top of the pit was a metal frame suspending a spray device over the pit. The site was revisited on July 26, 1999, in order to confirm the current conditions of the site. The "X-12" tank is still there, sitting on a wooden pallet. The small pit with the deteriorated plastic is there and looks unchanged. The two large polypropylene tanks observed in 1998 are gone. The space where they had been located was occupied by wood debris and PVC pipe. The large rectangular pit has been filled in. What appears to have been the metal frame over the former pit is now lying on the ground to the north. A cylinder of compressed nitrogen is within 2 meters (6.6 feet) of the south sand pile remnant. The cylinder is labeled "For Research Use. Please do not move from this site. POC Fenton Khan 372-0426 or Janelle Downs 376-6641." The cylinder is resting on a metal plate and is secured to a metal post. This cylinder is the only material that is part of an ecological experiment for the vitrification project, and is separate from the other material found at the site.

Location: The site is located inside 200 East Area, southwest of PUREX. It is along a dirt road that runs north from First Street, approximately 0.8 kilometers (0.5 miles) west of the intersection of First Street and Canton Avenue. The site is approximately 0.5 kilometers (0.3 miles) north of First Street.

Process Description: After some research, it was discovered that the sand piles, identified in 1995, are actually the remains of several experiments in preparation for locating a suitable site for long term storage for vitrified material. The sand piles are evidence of seasonal soil infiltration tests, using water. The sand is not a waste site. Later, PNNL used the same area for water infiltration tests.

Code: 200-E-16 **Classification:** Accepted

Names: 200-E-16; B Plant Waste Concentrator; Low Level Waste Concentrator; Single-Stage Thermal Siphon Reboiler **Reclassification:** None

Type: Evaporator **Start Date:**

Status: Inactive **End Date:**

Location: The low-level waste concentrator is located in cell #23 of building 221-B. Cell #23 is the first cell east of 221-BC.

Process Description: The low-level waste concentrator was operated to concentrate the low-level waste in the low-level waste storage and treatment tank system. The low-level waste concentrator is a thermal siphon and shell and tube heat exchanger. This system has been used only for concentration of the B Plant Complex low-level waste stream. No NCAW waste has been concentrated with the

B Plant low-level waste concentrator. This system currently is inactive with no intention of resuming operation and is included to reflect past operations. The low-level waste concentrator system includes the following equipment: the waste concentrator (E-23-3), the deentrainer (D-23-2), the condenser (E-23-4), and receiving tank (TK-23-1). The maximum process design capacity for the low-level waste concentrator is 7,300 gallons (27,633 liters) per day.

Waste Type: Process Effluent

**Waste
Description:**

Code: 200-E-17 **Classification:** Accepted

Names: 200-E-17; LERF Basins; 200 Area Liquid Effluent Retention Facility (LERF) **Reclassification:** None

Type: Surface Impoundment **Start Date:** 1/1/1994

Status: Active **End Date:**

Description: The 200 Area Liquid Effluent Retention Facility (LERF) is comprised of a group of surface impoundments. The site is surrounded by a fence (about 700 meters by 400 meters). The three LERF basins are located in the southern portion and are numbered from west to east as 242AL42, 242AL43, and 242AL44, respectively. Each basin is constructed with 2 liners; a leachate collection system; sampling and liquid level risers; and a floating cover. There are three metal buildings within the fence.

Location: The basins are located in the northeast corner of 200 East Area; about 300 meters south of the 2025E building and just east of Canton Ave.

**Related Sites/
Structures:** Double Shell Tanks (DST), 242-A Evaporator, 2025E, 200 Area Effluent Treatment Facility (ETF), 600-211 (SALDS).

**Process
Description:** Mixed waste from the Double-Shell Tank System is transferred to the 242-A Evaporator, where the waste is concentrated by evaporation. The evaporated constituents are recondensed, collected, and transferred to LERF. Other facility effluents may be added later. The effluent is stored in the basins until it is processed by the 200 Area Effluent Treatment Facility (ETF). Waste from the ETF may be recycled via the LERF for additional treatment.

Waste Type: Process Effluent

**Waste
Description:** Process condensate from the evaporator contains small amounts of volatile and semivolatile organics; inorganics; and radionuclides. By permit, constituents may include spent halogenated and non-halogenated solvents and ammonia.

Code: 200-E-19 **Classification:** Not Accepted

Names: 200-E-19; 216-B-3 Borrow Pit; B Pond Borrow Area **Reclassification:** None

Type: Depression/Pit (nonspecific) **Start Date:** 1/1/1994

Status: Inactive **End Date:**

Description: The 216-B-3 Borrow Pit is a shallow, scarred gravel area adjacent to the northeast corner of the backfilled 216-B-3 Pond. It is slowly revegetating with native grasses and crested wheatgrass, but large areas of bare ground remain.

Location: The site is located east of the 200 East Area perimeter fence. It is northwest of the backfilled

216-B-3 Main Pond, and north of a posted Underground Radioactive Material Area (the 216-B-3 Ditches).

Related Sites/ Structures: The borrow pit is associated with the 216-B-3 Pond.

Process Description: Fill material was taken from this area in 1994 for 216-B-3 stabilization activities. No waste has been placed into the borrow pit.

Code: 200-E-20 **Classification:** Not Accepted

Names: 200-E-20; 218-E-10 Annex; 218-E-10 Borrow Area; 218-E-10 Borrow Pit; Unused Portion of 218-E-10 Burial Ground **Reclassification:** None

Type: Depression/Pit (nonspecific) **Start Date:** 1/1/1980

Status: Inactive **End Date:**

Description: The area is posted with signs that read "Do Not Enter - 218-E-10 Burial Ground - Authorized Personnel Only." The area has revegetated naturally.

Location: The site is located inside the 200 East Area, north of the 218-E-10 burial trenches. It is near the corner of 12th Street and Akron Ave.

Related Sites/ Structures: The borrow pit and unused designated trench area is associated with the 218-E-10 Burial Ground. The unused portion of the burial ground is associated with WIDS sitecode 200-E-292, which documents a small amount of debris.

Process Description: The area was originally reserved for additional 218-E-10 Burial Ground trenches. No additional burial trenches were placed in this area. In 1980, clean backfill material was taken from the east side of the unused Annex area to surface stabilize the eastern 10 hectares (25 acres) of the 218-E-10 burial ground trenches. No waste has been placed into the pit. Only clean backfill material has been removed.

Code: 200-E-21 **Classification:** Not Accepted

Names: 200-E-21; 218-E-12A and 218-E-12B Borrow Pit; 218-E-12A and 218-E-12B Soil Borrow Area; Pit 33 **Reclassification:** None

Type: Depression/Pit (nonspecific) **Start Date:** 1/1/1979

Status: Active **End Date:**

Description: The 218-E-12A / 218-B-12B Burial Ground Borrow Pit is a large scraped area located west of the 218-E-12A Burial Ground and south of the 216-B-2 Covered Ditches. It is not marked or posted.

Location: The Borrow Pit is located west of the 218-E-12A Burial Ground and south of the 216-B-2 Covered Ditches.

Related Sites/ Structures: The borrow pit is associated with 218-E-12A and 218-E-12B Burial Grounds.

Process Description: Clean backfill material from this borrow pit area was used on both the 218-E-12A and 218-E-12B Burial Grounds. The 218-E-12A Burial Ground was initially surface stabilized with material from this borrow pit in 1980. The southeast portion of the 218-E-12B Burial Ground

was surface stabilized with material from this borrow pit in 1981. Additional backfill material was added to the burial grounds from this borrow pit in 1994. No waste has been placed into the borrow pit.

Code: 200-E-23 **Classification:** Not Accepted
Names: 200-E-23; UN-216-E-33 Borrow Pit; UPR-200-E-56 Borrow Pit **Reclassification:** None
Type: Depression/Pit (nonspecific) **Start Date:** 1/1/1979
Status: Inactive **End Date:**

Description: The borrow pit is not marked or posted, and is partially vegetated.
Location: The site is located east of the 200 East Area perimeter fence, north of the 216-A-24 Crib and UPR-200-E-56.
Release Description: See UPR-200-E-56.
Related Sites/ Structures: The site is associated with UPR-200-E-56 (alias UN-216-E-33) and the 216-A-24 crib.
Process Description: This borrow pit was the source of clean fill to cover contaminated material placed at the UPR-200-E-56 site. No waste has been placed in the pit.
Waste Type: Soil
Waste Description: After earthmoving equipment mistakenly dug into contaminated soil adjacent to the 216-A-24 crib, contaminated soil from other areas in 200 East Area were placed into the excavation to fill up the hole.

Code: 200-E-24 **Classification:** Accepted
Names: 200-E-24; 2704-HV Septic System; 6607-11 **Reclassification:** None
Type: Septic Tank **Start Date:**
Status: Active **End Date:**

Description: The septic and dosing tank area (about 60 ft by 10 ft) has five manholes at grade and two 7-ft high 4-in diameter metal pipe air vents. The drain field is within a fenced area about 300 ft north of the septic tank area. The drain field fenced area is about 360 feet by 130 feet and has six valve boxes and a gate at the south end. The drain field consists of three trenches and one trench reserved for future use.
Location: The site is west of B-Plant and east of route 4 south. It is east of 2704-HV and west of the 216-B-62 crib. A GPS survey was done in August 1998.
Related Sites/ Structures: 2704-HV, 2701-HV, MO723, MO850, MO046
Process Description: This system receives sanitary sewer from 2704-HV, 2701-HV, MO723, MO850, MO046.
Waste Type: Sanitary Sewage
Waste Description: This system receives sanitary sewage from 2704-HV, 2701-HV, MO723, MO850, MO046.

Code: 200-E-28 **Classification:** Accepted

Names: 200-E-28; 221-B Building Contaminated Steam Condensate Release **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1990

Status: Inactive **End Date:**

Description: The release occurred inside the 221-B building. Liquid was observed seeping through the 221-B Canyon wall expansion joint located between cells 38 and 39 in the electrical gallery. Visible portions of the expansion joint are 3/4" to 1" wide however, the actual point of release is below grade and is not visible. The expansion joint is located 40 feet from the west end of the building between cells 38 and 39.

Location: The release occurred at the 221-B Building (B Plant), 40 feet from the west end and under 221-B Building.

Release Description: On July 17, 1990, a nuclear process operator discovered a solution seeping from the expansion joint between cells 38 and 39, inside the electrical gallery. The seepage was collecting in the gallery floor sump. It was later determined that the release involved approximately 80,000 gallons to 230,000 gallons (over a one year time span) of radioactive steam condensate that could not be accounted for. The steam condensate contained Sr-90 and Cs-137. It is assumed to have been released to the soil column.

Related Sites/ Structures: The release is associated with B Plant operations.

Waste Type: Steam Condensate

Waste Description: The waste was approximately 80,000 to 230,000 gallons of steam condensate contaminated with Cs-137 and Sr-90 that leaked through the expansion joint between cells 38 and 39 of the B Plant Canyon Building directly into the soil column.

Code: 200-E-32 **Classification:** Accepted

Names: 200-E-32; 226-B Pad East Side 90-Day Waste Accumulation Area **Reclassification:** Consolidated (4/20/2000)

Type: Storage Pad (<90 day) **Start Date:**

Status: Inactive **End Date:**

Description: This site is a duplicate of 226-B HWSA, according to Fen Simmons, the Environmental Compliance Officer for the facility. It was entered into WIDS as a Discovery site in 1996 in error. In addition, it was entered at a time when WIDS was required to track <90 Day Storage Pads. WIDS is no longer required to track these areas per TPA-MP-14.

This Site Was Consolidated With:

Code: 226-B HWSA

Names: 226-B HWSA; 226-B Hazardous Waste Storage Area

Code: 200-E-33 **Classification:** Accepted

Names: 200-E-33; PUREX 214-A 90-Day Waste Accumulation Areas **Reclassification:** Rejected (9/14/2000)

Type: Storage Pad (<90 day) **Start Date:**

Status: Inactive **End Date:** 1/1/1996

Description: This 90 day storage area and any residual contamination were removed when PUREX was closed down and cleaned to meet the deactivation end point criteria prior to transition from Westinghouse Hanford Co. to Bechtel Hanford Inc. (BHI).

Location: The unit was the 214-A Bay Dangerous Waste Storage area in PUREX.

Related Sites/ Structures: This pad was one of the 90 day storage areas for PUREX.

Code: 200-E-34 **Classification:** Accepted

Names: 200-E-34; PUREX High Level Waste Room 90-Day Waste Accumulation Area **Reclassification** Rejected (9/14/2000)

Type: Storage Pad (<90 day) **Start Date:**

Status: Inactive **End Date:** 1/1/1996

Description: All 90 day storage pads were removed when PUREX was closed down and cleaned to meet the deactivation end point criteria prior to transition from Westinghouse Hanford Co. to Bechtel Hanford Inc. (BHI), per J.D. Showman (e-mail communication, March 2000).

Location: This site was in the PUREX facility High Level Waste Room.

Related Sites/ Structures: This site was associated with the PUREX facility.

Code: 200-E-35 **Classification:** Accepted

Names: 200-E-35; 209-E 90-Day Waste Accumulation Area; 209-EA **Reclassification** Rejected (9/14/2000)

Type: Storage Pad (<90 day) **Start Date:**

Status: Inactive **End Date:**

Description: The site had been a concrete pad with a peaked roof supported by beams. The sides were fenced. The east side of the pad was the Hazardous Material storage area. The west side of the pad was the mixed waste storage area. In 2011, amended water was sprayed during the 209E building demolition activities. Post-demolition, three to six inches of surface material was removed from all areas affected by the amended water and prior to applying a gravel cap. The final gravel cap was expanded to cover all affected areas. The posted URMA was expanded to include the entire gravel cap. The gravel cap now covers several WIDS sites. The additional WIDS sites under the 209E gravel cap are 200-E-4, 200-E-35, 209-E-WS-1, 209-E-WS-2, 2718-E-WS-1 and 200-E-293 (2718E footprint). The 209-E-WS-3 (Tank 111), adjacent to the south side of the foundation, is within the URMA but was not covered or backfilled.

Location: The site was located inside the 200 East Area, on the west side of the 209-E building.

Process Description: Waste generated at tank farm facilities is transported to 209-E for storage. The storage pad is divided into two areas. One part is used for storage of mixed waste, the other part is used for storage of hazardous material.

Code: 200-E-36 **Classification:** Accepted

Names: 200-E-36; 241-AZ 90-Day Waste Accumulation Area **Reclassification** Rejected (9/6/2000)

Type: Storage Pad (<90 day)

Start Date:

Status: Inactive

End Date: 1/1/1993

Description: This site has been inactive at least since 1993, according to the current (May 2000) manager of 90 Day Pads for the River Protection Program (RPP). Its previous location is unknown, but only enclosed conex boxes (self-contained with a spill berm) had been used for 90 Day Storage in the past in the tank farms. This 90 Day Area was moved to RPP's only remaining 90-Day Area, at 209-E (200-E-35) before 1993.

Related Sites/ This site was associated with the 241AZ Tank Farm.

Structures:

Code: 200-E-39

Classification: Accepted

Names: 200-E-39; Hood 32 90-Day Waste Accumulation Area; PUREX Room 52 **Reclassification** Rejected (9/14/2000)

Type: Storage Pad (<90 day)

Start Date:

Status: Inactive

End Date: 1/1/1996

Description: All 90 day storage pads were removed when PUREX was closed down and cleaned to meet the deactivation end point criteria prior to transition from Westinghouse Hanford Company (WHC) to Bechtel Hanford Inc. (BHI), per J. D. Showman (e-mail communication March 2000).

Location: This site was in room 52 of the PUREX facility.

Related Sites/ This site was associated with the PUREX facility.

Structures:

Code: 200-E-40

Classification: Accepted

Names: 200-E-40; PUREX Sample Gallery 90-Day Waste Accumulation Area **Reclassification** Rejected (9/14/2000)

Type: Storage Pad (<90 day)

Start Date:

Status: Inactive

End Date: 1/1/1996

Description: All 90 day storage pads were removed when PUREX was closed down and cleaned to meet the deactivation end point criteria prior to transition from Westinghouse Hanford Co. (WHC) to Bechtel Hanford Inc. (BHI).

Location: This pad was in the Sample Gallery at PUREX.

Related Sites/ This site was associated with the PUREX facility.

Structures:

Code: 200-E-42

Classification: Accepted

Names: 200-E-42; 291-A Release; PUREX Stack Release; UN-216-E-34 **Reclassification** Rejected (7/28/2008)

Type: Unplanned Release

Start Date: 1/1/1985

Status: Inactive**End Date:** 1/1/1994**Description:** A release from the PUREX stack caused a ground surface contamination area adjacent to the outside east of the PUREX perimeter fence measuring approximately 2.6 hectares (6.5 acres). The site is not currently marked or posted.**Location:** The site was adjacent to the east side of the PUREX exclusion fence.**Release Description:** On July 18, 1985 a radiation survey of the ground adjacent to the east PUREX fence and around Air Sampler #971 found contamination levels ranging from 300 counts per minute to 5,000 counts per minute. The area was posted as a Surface Contamination Area. On 8-6-86 the site was assigned the Unplanned Release number UN-216-E-34.**Process Description:** During PUREX operations, ammonium nitrate would build up on the 291-A stack walls. Periodically the material build up would flake off and was blown out of the stack with the stack air flow. The flakes were distributed on the ground around the stack and the surrounding area, dependent on wind direction and velocity.**Waste Type:** Process Effluent**Waste Description:** Gamma Spectrum Analysis of ammonium nitrate flakes from the PUREX stack showed the flakes contained 2.53 microcuries of ruthenium-106, 0.05 microcuries of ruthenium-103, 2.56 microcuries of rhodium-106 and 0.01 microcuries of cesium-137.**Code:** 200-E-47**Classification:** Accepted**Names:** 200-E-47; RCRA Permit General Inspection #200EFY96 Item #7**Reclassification:** Rejected (5/31/2001)**Type:** Dumping Area**Start Date:****Status:** Inactive**End Date:****Description:** The site is a small pile of scrap steel angle iron, sheet metal, and piping, discovered during an annual RCRA General Inspection July 15 -16, 1996. The surrounding area is covered with tumbleweeds, cheatgrass, and sagebrush. However, the soil on top of the metal is bare, due to the inability of vegetation to grow on the very shallow soils covering the metal.**Location:** The site is located in the 200 East Area approximately 600 meters east-southeast of 12th Street and east of Akron Avenue. The area is just east of a north-south dirt powerline road. It is west of the 241-BX/BY tank farms.**Waste Type:** Misc. Trash and Debris**Waste Description:** Steel beams and piping.**Code:** 200-E-48**Classification:** Not Accepted**Names:** 200-E-48; RCRA Permit General Inspection #200EFY96 Item #15**Reclassification:** None**Type:** Dumping Area**Start Date:****Status:** Inactive**End Date:****Description:** The site is an abandoned steel I beam is 9 meters (30 feet) long and 0.3 meters (1 foot) wide. The site is not marked or posted.**Location:** The site is located in the 200 East area, approximately 30 meters (100 feet) northeast of the 207

 B Retention Basin.

Waste Type: Equipment

Waste Description: The site is a 9 meter (30 foot) long steel I beam.

Code: 200-E-49	Classification: Not Accepted
Names: 200-E-49; Borrow Pit North of BC Cribs and Trenches	Reclassification: None
Type: Depression/Pit (nonspecific)	Start Date: 1/1/1981
Status: Inactive	End Date:

Description: The site is a shallow, scraped area located north of the BC Trenches. The borrow pit is currently located inside the boundary of the posted BC Radiologically Controlled Area (WIDS sitecode UPR-200-E-83) and is considered part of the BC Controlled Area.

Location: The site is located south of 200 East Area on the south side of Route 4S.

Related Sites/Structures: The borrow pit is associated with the surface stabilization of the BC Cribs and Trenches (216-B-14 through 19 Cribs, and Trenches 216-B-21 through 34 and 216-B-52 through 58) and the BC Controlled Area (UPR-200-E-83).

Process Description: Because of recurring surface contamination problems, the surfaces of the backfilled 200 BC Cribs and Trenches were surface stabilized beginning in August of 1981. Clean backfill material was taken from the area north of and adjacent to the BC Trenches. No waste was placed into the borrow pit.

Code: 200-E-50	Classification: Accepted
Names: 200-E-50; 284-E Brine Pit; 284-E Salt Dissolving Pit and Brine Pump Pit	Reclassification: Rejected (4/20/2000)
Type: Sump	Start Date: 1/1/1942
Status: Inactive	End Date: 1/1/1995

Description: The brine pit is no longer visible. It was cleaned out, demolished into itself, and backfilled with gravel in 1999. It is not marked or posted. The salt dissolving pits and brine pump pit were part of a single below-grade concrete structure that provided brine for the 284-E Powerhouse.

The two salt dissolving pits each had inner dimensions of 4.3 meters (14 feet) long by 2.4 meters (8 feet) wide by 2.8 meters (9.25 feet) tall. They had a designed high water line 2.4 meters (7.75 feet) from the pit bottom. An overflow slot connecting the two dissolving pits was located 0.3 meters (1 foot) above the high water line. The bottom of each pit was filled with a 12.7 centimeter (5 inch) layer of 1.3 to 2.6 centimeter (1/2 to 1 inch) gravel topped by a 17.8 centimeter (7 inch) layer of 0.3 to 0.6 centimeter (1/8 to 1/4 inch) gravel. The dissolving pits each had a 2.4 meter (8 foot) by 0.9 meter (3 feet) opening at the top for receiving salt. Each pit had a capacity of 23,600 kilograms (52,000 pounds) of salt.

The brine pump pit was located adjacent to the two salt dissolving pits. The pit was 3.3 meters (10.67 feet) long by 2.2 meters (7.33 feet) wide by 2.1 meters (7 feet) deep. It held two pumps and associated piping (all brass) for the brine system. The floor of the pump pit sloped toward a 46 by 46 by 46 centimeter (18 by 18 by 18 inch) sump in a corner.

Location: The brine pit was located south of the 282-E Water Reservoir near the railroad track.

**Related Sites/
Structures:** The site is associated with the 284-E Powerhouse.

**Process
Description:** The brine was used to regenerate the ion exchange demineralizers that were part of the powerhouse water treatment system. The brine was created by adding water to the salt in the dissolving pit. As the water passed through the salt, the solution became saturated. The brine passed through the layers of gravel which filtered out salt crystals and other particles. The filtered brine was then drawn off by a pipe connecting to the adjacent brine pump pit. A float valve was used to maintain the water/brine level.

Waste Type: Demolition and Inert Waste

**Waste
Description:** The structure was cleaned out, demolished, and buried in place.

Code: 200-E-51 **Classification:** Accepted

Names: 200-E-51; 284-E Powerhouse Coal Ramp Washdown Pit; Miscellaneous Stream #177; 200 East Powerhouse Coal Ramp Washdown Pit **Reclassification** Rejected (4/20/2000)

Type: Depression/Pit (nonspecific) **Start Date:**

Status: Inactive **End Date:** 1/1/1997

Description: The site is an open pit, partially filled with tumbleweeds and surrounded with metal fence posts and a broken light chain. A shallow 10-centimeter (4-inch) steel pipe enters the pit from the north.

Location: The washdown pit is south of the 200 East Powerhouse and coal ramp.

**Related Sites/
Structures:** The pit is associated with the 284-E Powerhouse.

**Process
Description:** The powerhouse coal ramp was washed down periodically. The washdown water was collected in three sumps. During the summer months, the sumps were pumped approximately two times per week, discharging the water into the washdown pit. During the winter months, the sumps were pumped two times per day. When the 284-E Powerhouse began shut down activities in December 1997, the pit became inactive. The process was eliminated from the Inventory of Miscellaneous Streams report in June 1998.

Waste Type: Water

**Waste
Description:** The pit received effluent pumped from sumps that held coal ramp wash water.

Code: 200-E-52 **Classification:** Accepted

Names: 200-E-52; 200 East Powerhouse Coal Pile **Reclassification** Rejected (5/13/2008)

Type: Depression/Pit (nonspecific) **Start Date:** 1/1/1944

Status: Inactive **End Date:** 1/1/1998

Description: Only a shallow surface covering of coal remains at the site. On the east and south banks there are large pieces of metal debris (I-beam, metal grate). A coal-covered metal plate covers the chute to the conveyor belt.

Location: The coal pile was located south of the 284 Powerhouse and east of the coal ramp.

Related Sites/ Structures: The site is associated with the 284-E Powerhouse.

Process Description: Large piles of coal had been stored in this area to fuel the 284-E Powerhouse. The powerhouse was shut down in December 1997.

Waste Type: Misc. Trash and Debris

Waste Description: A thin layer of coal and coal dust remains on the surface of the area. A few pieces of metal debris are located at the east end of the coal storage area. A waste determination for Anthracite (Anthrafil) was performed in 1994. A waste determination for bituminous coal dust was performed in 1996. The waste streams for both types of coal were determined to be nondangerous.

Code: 200-E-54	Classification: Accepted
Names: 200-E-54; Liquid Release to the Environment from PUREX Deep Filter Bed #1	Reclassification: Consolidated (6/30/2004)
Type: Unplanned Release	Start Date: 1/1/1991
Status: Inactive	End Date:

Description: The Unplanned Release has been consolidated into the larger, 200-E-103 waste site. It was a release to the soil that occurred as a result of a significant water line rupture in the basement of the 293-A building that affected the Deep Filter Bed.

Location: The release occurred south of the 202 A building, inside the PUREX facility fence (aka 200-E-103).

Release Description: On January 13, 1991 (ref. occurrence report RL--WHC-PUREX-1991-035) a raw water line ruptured in the basement of the 293-A building, resulting in over 380,000 liters (100,000 gallons) of water flooding the basement and backing up into the PUREX Canyon exhaust ventilation ductwork, including the #1 deep bed fiberglass filter. At the time of the release, pumping the water to the tank farms was not possible due to limited available tank storage space. Disposing the water to a crib was ruled out due to the large radionuclide content. While disposal options were being discussed, the liquid remained in the ventilation ductwork for 21 months. Since the ductwork was not designed to retain liquids, the possibility of a liquid release to the environment was reported in September 1992. Approval to transfer the liquid to the tank farms was given in September 1992. Based on the original release estimate of 380,000 liters (100,000 gallons), it is believed that approximately 201,400 liters (53,000 gallons) leaked to the soil over the 21 months from the release date to the date the liquid was transferred.

Waste Type: Water

Waste Description: The water leaked into the soil over a period of 21 months.

This Site Was Consolidated With:

Code: 200-E-103
Names: 200-E-103; PUREX Stabilized Area; Radiologically Controlled Area - South Side of PUREX

Code: 200-E-61	Classification: Not Accepted (Proposed)
Names: 200-E-61; 202A Building Stormwater Runoff; Miscellaneous Stream #467	Reclassification: None

Type: Injection/Reverse Well**Start Date:****Status:** Active**End Date:****Description:** The site is a circular stormwater drain with a metal-grate cover. The drain is considered to be active.**Location:** The site is located north of 202-A (PUREX Canyon), at the northwest corner of the asphalt walkway leading from the guard house to 202-A.**Waste Type:** Stormwater Runoff**Waste Description:** The site receives stormwater runoff from the north side of the PUREX facility.

Code: 200-E-62**Classification:** Accepted**Names:** 200-E-62; 202A Building Steam Condensate; Injection Well (Z); Miscellaneous Stream #71**Reclassification:** None**Type:** Injection/Reverse Well**Start Date:****Status:** Inactive**End Date:** 1/1/1996**Description:** The drain has a portion of metal culvert extending above the surface. It has a metal cover with a rusty pipe going into it. The steam plant that fed the pipeline that drained condensate to this site has been shut down and could not be easily re-started.**Location:** The site is located inside the PUREX fence, on the north side of 203-A, north of the containment dike for tank TK-P3. It is south of 275-EA.**Process Description:** Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.**Waste Type:** Steam Condensate**Waste Description:** The site received non-contaminated steam condensate.

Code: 200-E-63**Classification:** Accepted**Names:** 200-E-63; Injection Well (AA); Line #8801 Steam Condensate; Miscellaneous Stream #72**Reclassification:** None**Type:** Injection/Reverse Well**Start Date:****Status:** Inactive**End Date:** 1/1/1996**Description:** The drain is a 1.22 meter (4 foot) diameter, concrete drain with a metal cover.**Location:** The site is located north of 202-A, on the northwest corner of the 211-A tanks, between tank TK-41 and the 211-A chemical access railroad tracks.**Process Description:** Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and

process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The site received non-contaminated steam condensate.

Code: 200-E-64 **Classification:** Accepted

Names: 200-E-64; Injection Well (W); Line #8801 Steam Condensate; Miscellaneous Stream #69 **Reclassification:** None

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:** 1/1/1996

Description: The drain is a 0.9 meter (3 foot) diameter concrete drain, covered by a steel plate, with a rusty pipe going into it from the steam line above.

Location: The site is located on the north side of 202A, adjacent to the west end of the laboratory sample receiving dock.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The site received non-contaminated steam condensate.

Code: 200-E-69 **Classification:** Accepted

Names: 200-E-69; Injection Well (A); Line #8801 Steam Condensate; Miscellaneous Stream #56 **Reclassification:** None

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:** 1/1/1997

Description: The site is a 1.3 meter (4.5 foot) diameter drain, with a metal cover, located beneath the steam line in the northwest corner of the PUREX complex. The rocks and soil around the drain cover are stained with rust.

Location: The site is in the northwest corner of the PUREX complex, on the east side of the interior security fence.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The site received non-contaminated steam condensate.

Code: 200-E-72 **Classification:** Accepted

Names: 200-E-72; Injection Well (G); Line #8801 Steam Condensate; Miscellaneous Stream #60 **Reclassification:** None

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:** 1/1/1997

Description: The drain is adjacent to the abandoned steam line. It is flush with the surrounding grade surface and has a 0.9 meter (3 foot) diameter metal cover.

Location: The site is located south of PUREX, near the west side of the #04 access gate.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The site received non-contaminated steam condensate.

Code: 200-E-75 **Classification:** Accepted

Names: 200-E-75; Injection Well (B); Line #8801 Steam Condensate; Miscellaneous Stream #57 **Reclassification:** None

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:** 1/1/1997

Description: The drain is underneath the steam line. It is a concrete french drain with a 0.9 meter (3 foot) steel cover.

Location: The site is located near the southwest corner of the PUREX canyon, within the PUREX security fence.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The site received non-contaminated steam condensate.

Code: 200-E-76 **Classification:** Accepted
Names: 200-E-76; Injection Well (U); Line #8801 Steam Condensate; Miscellaneous Stream #67 **Reclassification:** None
Type: Injection/Reverse Well **Start Date:**
Status: Inactive **End Date:** 1/1/1997

Description: The drain is a concrete structure with a 1.5 meter (5 foot) diameter metal cover. The inside of the drain is dry with rust colored rocks. It is labeled 2A-501 - Confined Space.

Location: The drain is located at the northeast corner of the PUREX complex, inside the inner security fence. It is east of the railroad cut.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The site received non-contaminated steam condensate.

Code: 200-E-78 **Classification:** Accepted
Names: 200-E-78; Injection Well (Y); Line #8801 Steam Condensate; Miscellaneous Stream #70 **Reclassification:** None
Type: Injection/Reverse Well **Start Date:**
Status: Inactive **End Date:** 1/1/1996

Description: The site is a drainage area that received steam condensate from a pipe extending from overhead steam lines. The pipe is attached to the south side of the 203-A building and terminates in cobble filled depression. No drain structure is visible. The steam pipe terminates into the soil inside a Contamination Area that surrounds the 203-A building.

Location: The site is located north of 202-A, on the southeast corner of the 203-A UNH (uranyl nitrate hexahydrate) Pumphouse.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: Although the drain received non-contaminated steam condensate, the point where the steam pipe terminates into the ground is located inside a posted Contamination Area.

Code: 200-E-80 **Classification:** Accepted
Names: 200-E-80; Injection Well (V); Line #8801 Steam **Reclassification:** None

Condensate; Miscellaneous Stream #68

Type: Injection/Reverse Well

Start Date:

Status: Inactive

End Date: 1/1/1996

Description: The site is a gravel area with some rusty pipes going into the ground. No drain structure is visible from the surface. The site received steam condensate.

Location: The site is located on the northeast side of 202A, next to the north wall of the 206-A fractionator.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The site received non-contaminated steam condensate.

Code: 200-E-81

Classification: Accepted

Names: 200-E-81; Miscellaneous Stream #533; MO-035 Facility Water Valve

Reclassification: None

Type: Injection/Reverse Well

Start Date:

Status: Inactive

End Date: 1/1/1997

Description: No drain is visible. The mobile office trailers have been removed. In December of 1997, a layer of clean gravel was laid over the area where the trailers once stood, covering the drain structure.

Location: The site is located north of 202-A, inside the double exclusion fence, just south of the PUREX Badgehouse. It was adjacent to where mobile office MO-035 had been located.

Related Sites/Structures: The drain was associated with Mobile Office MO-035.

Waste Type: Water

Waste Description: The drain received water valve drainage from a Mobile Office trailer that has been removed from the area.

Code: 200-E-82

Classification: Accepted

Names: 200-E-82; Miscellaneous Stream #115; Steam Trap 2P; Yard-MSS-TRP-040

Reclassification: None

Type: Injection/Reverse Well

Start Date:

Status: Inactive

End Date: 1/1/1997

Description: The site is a 1.3 meter (4.5 foot) diameter, corrugated metal steam valve pit. It has a metal cover. There are two valves inside the pit. The pit was dry on the day of the inspection.

Location: The site is located north of 202-A, outside the double security fence.

Related Sites/ Structures: The site is associated with the PUREX to 204-AR valve pit.

Process Description: The steam plant and the steam pipelines associated with PUREX have been shut down, so the condensate drains are also inactive. Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The site received non-contaminated steam condensate.

Code: 200-E-85 **Classification:** Accepted

Names: 200-E-85; 202A Building Pump Seal Water; Miscellaneous Stream #459 **Reclassification:** None

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:**

Description: A piece of 1/2 inch diameter PVC pipe extends approximately 0.6 meters (2 feet) out of the ground on the north side of the 2712-A building. No drain is visible at this location. It is assumed that a drain pipe from the 2712-A building may have been previously connected to this PVC pipe. It is also possible Stream ID #459 is a duplicate of 216-A-35, located west of the 2712-A building. 216-A-35 is a 1.5 meter (4 foot) diameter drain extending approximately 0.3 meters (1 foot) above ground and is painted yellow.

Location: The Inventory of Miscellaneous Streams Report states this drain is located on the southwest corner of the 202-A building. The coordinates listed in the document place it in the same location as 216-A-35. A PVC drain pipe is located adjacent to the north wall of 2712-A Building, south of 202A. This is a possible location of Stream #459, since the building contained pumps.

Related Sites/ Structures: The site is associated with 202-A, 2712-A and 216-A-35

Process Description: The site documented site description for stream #459 has created some confusion. In 1998, when the site walkdown was done, the 2712-A Building housed air sampling pumps. This building was considered the source of pump seal water drainage. The Inventory of Miscellaneous Streams Report states that Stream ID 459 received pump seal water, but indicated it was located near the southwest corner of 202-A. The coordinates in the document indicate it is in the same location as 216-A-35.

Waste Type: Water

Waste Description: The site received pump seal water.

Code: 200-E-88 **Classification:** Accepted

Names: 200-E-88; B Plant Yard Steam Condensate; **Reclassification:** None

Miscellaneous Stream #3

Type: Injection/Reverse Well

Start Date:

Status: Inactive

End Date: 1/1/1997

Description: The site received steam condensate. It is now a pile of rust colored rocks and broken clay tile pipe.

Location: The site is located southeast of the 291-B Sand Filter, adjacent to the steam line.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The site received non-contaminated steam condensate.

Code: 200-E-89

Classification: Accepted

Names: 200-E-89; B Plant Yard Steam Condensate; Miscellaneous Stream #4

Reclassification: None

Type: Injection/Reverse Well

Start Date:

Status: Inactive

End Date: 1/1/1997

Description: The site is a 0.9 meter (3 foot) diameter cement culvert with a rusted metal lid, used for draining steam condensate.

Location: The site is located south of the 292-B Building, adjacent to the steam line.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The site received non-contaminated steam condensate.

Code: 200-E-90

Classification: Accepted

Names: 200-E-90; B Plant Yard Steam Condensate; Miscellaneous Stream #5

Reclassification: None

Type: Injection/Reverse Well

Start Date:

Status: Inactive

End Date: 1/1/1997

Description: The site is a 1 meter (3 foot) diameter concrete culvert, with two steel covers, one covering the drain and one inside.

Location: The site is located south of 224-B, adjacent to the steam line.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The site received non-contaminated steam condensate.

Code: 200-E-91 **Classification:** Accepted

Names: 200-E-91; B Plant Yard Steam Condensate; Miscellaneous Stream #6 **Reclassification:** None

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:** 1/1/1997

Description: The site is a 0.6 meter (2 foot) diameter, rock filled drain with no cover. The rocks are rust stained.

Location: The site is located southwest of 224-B, adjacent to the steam line.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The site received non-contaminated steam condensate.

Code: 200-E-92 **Classification:** Accepted

Names: 200-E-92; B Plant Yard Steam Condensate; Miscellaneous Stream #7 **Reclassification:** None

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:** 1/1/1997

Description: The site is a 0.75 meter (2.5 foot) diameter drain with a fiberglass cover. The site had been covered with dirt during recent grading activities.

Location: The site is located south of 7th Street, south of the 225-B Building, adjacent to the steam line.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added

to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The site received non-contaminated steam condensate.

Code: 200-E-93

Classification: Accepted

Names: 200-E-93; B Plant Yard Steam Condensate;
Miscellaneous Stream #8

Reclassification: None

Type: Injection/Reverse Well

Start Date:

Status: Inactive

End Date: 1/1/1997

Description: The site is a 0.9 meter (3 foot) diameter concrete culvert with a metal cover. Approximately 0.3 meters (1 foot) of the structure is aboveground. The drain structure has been damaged. One side is broken.

Location: The site is located adjacent to the south side of the 292-B Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The site received non-contaminated steam condensate.

Code: 200-E-94

Classification: Accepted

Names: 200-E-94; B Plant Yard Steam Condensate;
Miscellaneous Stream #9

Reclassification: None

Type: Injection/Reverse Well

Start Date:

Status: Inactive

End Date: 1/1/1997

Description: There are no visual surface features for this drain. It was buried under clean gravel when the water tower and associated steam pipelines were removed. The area is currently being used as an equipment laydown area.

Location: The site is located south of 7th Street and east of Atlanta Ave., southwest of B Plant.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The site received non-contaminated steam condensate.

Code: 200-E-95 **Classification:** Accepted
Names: 200-E-95; 222B Steam Condensate; **Reclassification:** None
Miscellaneous Stream #308
Type: French Drain **Start Date:**
Status: Inactive **End Date:** 1/1/1994

Description: The site is a 0.4 meter (18 inch) diameter french drain with a blue metal cover. The drain received steam and air conditioner condensate originating from inside the 222-B Building. The place where the source pipe protruded from the concrete block wall above the drain is visible, but it was cut and capped inside the building.

Location: The site is located adjacent to the north wall of the 222-B building, near the northeast corner of the building.

Process Description: The drain received steam and air conditioner condensate. Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion. The air conditioner condensate was atmospheric moisture condensing on the cooling coils.

Waste Type: Steam Condensate

Waste Description: The site received steam condensate and air conditioner condensate. The condensate was batch discharged during winter.

Code: 200-E-97 **Classification:** Accepted
Names: 200-E-97; 212B Building Steam Condensate; **Reclassification:** None
Miscellaneous Stream #470
Type: French Drain **Start Date:**
Status: Inactive **End Date:** 1/1/1997

Description: The site is a 0.4 meter (18 inch) diameter cement french drain with no lid. The cement drain structure has a cement ring that rises 5 centimeters (2 inches) above the surrounding grade. It is filled with dirt and is dry.

Location: 212-B is located near the southwest corner of the canyon 221-B building. This drain is located adjacent to the north wall of the 212-B building, in between 212-B and 221-B.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The drain received steam condensate from the 212-B building.

Code: 200-E-98 **Classification:** Accepted

Names: 200-E-98; 271B Building Ice Machine Overflow; Miscellaneous Stream #490 **Reclassification:** None

Type: French Drain

Start Date:

Status: Inactive

End Date: 1/1/1997

Description: The drain is not visible. A sheet metal shroud and a guard rail have been placed over the area that included the drain to keep small animals from accessing the building where pipes were removed. A portion of the source pipe is visible protruding from the cement block wall above the shroud. The pipe has been cut and capped. The shroud was placed over the site to keep stormwater and animals out of the basement of the 271-B Building. When the pipe connecting the air compressors in the basement with the air tanks outside was disconnected (see attached photo, blue structure on right is the tank, blue pipe above is the air pipe), a potential entry point for stormwater and animal entry into the building remained. The steel cover protects the building.

Location: The site is located adjacent to the east wall of 271-B.

Related Sites/ Structures: The site is associated with the 271-B building.

Process Description: The drain received overflow drainage from an ice machine in a second floor lunchroom, via a copper pipe through a cement block wall. The stream was eliminated as a Miscellaneous Stream in July 1997.

Waste Type: Water

Waste Description: The drain received overflow from an ice machine located inside 271-B.

Code: 200-E-99 **Classification:** Accepted

Names: 200-E-99; Miscellaneous Stream #570; Steam Trap 2P-Yard-MSS-TRP-017 **Reclassification:** None

Type: French Drain

Start Date:

Status: Inactive

End Date: 1/1/1998

Description: There is no drain structure. It is a low spot in the soil where the steam line discharged steam. The rocks and soil are stained with rust. There is a tag on the steam line that identifies it as MSS-TRP-017.

Location: The site is located adjacent to the steam line, east of the 291-B Sand Filter, near Baltimore Ave.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The site received non-contaminated steam condensate.

Code: 200-E-100 **Classification:** Accepted
Names: 200-E-100; Miscellaneous Stream #571; Steam Trap 2P-Yard-MSS-TRP-019 **Reclassification:** None
Type: French Drain **Start Date:**
Status: Inactive **End Date:** 1/1/1998

Description: The site is a low spot in the ground under the steam line where steam discharged. The rocks and soil are slightly stained with rust. There is a tag that identifies it as MSS-TRP-019.

Location: The site is located east of the 291-B Sand Filter, near Baltimore Ave. It is 6 meters (20 feet) west of the steam trap MSS-TRP-017 (site code 200-E-99).

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium).

Code: 200-E-105 **Classification:** Accepted
Names: 200-E-105; Soil Contamination Area on the 216-B-61 Crib **Reclassification:** Rejected (7/28/2008)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: This site had been a radiologically posted area located on top of the 216-B-61 Crib and also extended to an area where loose tumbleweeds had accumulated between the south edge of the crib and a soil berm. The posted areas had been designated as Soil Contamination Area (SCA) and Contamination Area (CA). Later, only a very small posted (1.2 by 1.2 meters) Contamination Area, located approximately 30 meters (100 feet) west of the 216-B-61 crib remained. In October 2003, the remaining area was also down posted. All the individual radiological postings have been removed. Since the 200 East Area perimeter fence is posted as a Radiologically Controlled Area (RCA), everything inside the fence is technically a RCA.

Location: The site located in the northwest portion of 200-E Area, south of 12th Street. It is northwest of the Hanford Prototype Barrier that covers the 216-B-57 Crib.

Waste Type: Vegetation

Waste Description: The contamination is a result of blown-in tumbleweeds.

Code: 200-E-106 **Classification:** Discovery
Names: 200-E-106; IDF Integrated Disposal Facility; IDWF; ILAW; Immobilized Low-Activity Tank Waste; Immobilized Low-Activity Waste **Reclassification:** None

Type: Trench**Start Date:****Status:** Inactive**End Date:****Description:** As of January 2002, the plans for this site are to construct trenches in the middle of the southern section of the 200 East Area.**Location:** The area designated for the trenches is between 1st and 4th Streets and between the coal plant and the PUREX facility in 200 East.**Related Sites/ Structures:** The site is associated with the RCRA Sand Pile site (site code 200-E-12, Rejected). The existing four vaults constructed for the Grout Treatment Facility Landfill (WIDS site code GTFL), may be used for disposal of ILAW or other wastes.**Process Description:** The tank waste remediation program will separate the wastes into two fractions. One fraction, consisting of high-activity wastes, will be vitrified and stored at Hanford until a national repository can be licensed. The low-activity wastes will also be vitrified, but permanently disposed at Hanford in the Immobilized Low-Activity Waste vaults.**Waste Type:** Process Effluent**Waste Description:** The waste disposed in these trenches will be vitrified low-activity waste from the single and double-shelled tanks. More than 200,000 cubic meters (7,000,000 cubic feet) of waste is expected to be disposed at the site.

Code: 200-E-108**Classification:** Not Accepted**Names:** 200-E-108; Well Drilling Laydown Yard Pit**Reclassification:** None**Type:** Depression/Pit (nonspecific)**Start Date:****Status:** Inactive**End Date:****Description:** The site is located within a large chain link fenced area with a locked gate. It is an empty hole in the ground that has been covered with a piece of plywood.**Location:** The pit is located in the southwest section of the fenced laydown yard. The laydown yard is located inside 200 East Area, north of 4th Street and east of Baltimore Avenue.

Code: 200-E-119**Classification:** Not Accepted**Names:** 200-E-119; 225-B West Side 90 Day Pad**Reclassification:** None**Type:** Storage Pad (<90 day)**Start Date:** 1/1/1997**Status:** Inactive**End Date:** 1/1/2000**Description:** This site is a discontinued 90 Day Storage Pad. Material had been stored in two, self-contained steel cabinets. When the 90 Day Storage Pad was no longer needed, the empty cabinets were moved to the 226-B laydown area. There is no visual evidence remaining at the location of where the cabinets had been located.**Location:** The pad was located near the southeast corner of the intersection of 7th and Atlanta Avenues, southwest of the 225-B Waste Encapsulation and Storage Facility (WESF).**Related Sites/ Structures:** This site was related to the 225-B Building.

Process The cabinets contained PCBs, solvents, and dangerous and mixed wastes.

Description:

Waste Type: Barrels/Drums/Buckets/Cans

Waste

Description:

Code: 200-E-122

Classification: Accepted

Names: 200-E-122; CF Bullpen; Construction Forces
Bullpen; Equipment Storage Yard; Laydown Yard

Reclassification Rejected (5/13/2008)

Type: Storage

Start Date:

Status: Inactive

End Date: 1/1/2004

Description: The site had been an equipment/material storage yard that was enclosed in a locked, chain link fence. The fence was marked Radiological Buffer Area. Inside the fence, several groups of material were surrounded with radiation rope and marked with Contamination Area signs. Some of the material inside the fence includes, scaffolding, barrels, wood, scrap metal, wooden crates, tables and cabinets. In 2004, the area was cleaned up. The chain link fence was removed. No posted contamination areas remain. A single post and WIDS sign marks the area.

Location: The site is located south of B Plant and south of 222-B.

Waste Type: Equipment

Waste Radioactively contaminated material was stored inside the fenced area.

Description:

Code: 200-E-126-PL

Classification: Accepted

Names: 200-E-126-PL; Underground Pipeline from 207-B to 216-B-3 Ditch

Reclassification Rejected (10/19/2010)

Type: Radioactive Process Sewer

Start Date: 1/1/1987

Status: Inactive

End Date: 1/1/1997

Description: Due to the restructuring of Operable Units, as described in the Tentative Agreement for Central Plateau Cleanup, this pipeline has been split into segments (200-E-126-PL-A and 200-E-126-PL-B). The waste site was originally described as an underground pipeline from 207-B Retention Basin to the 216-B-3A, 216-B-3B and 216-B-3C Ponds. The portion of pipeline east of Canton Ave. (that fed the B Pond lobes) is being excluded from this site description because it is being re-used to feed the Treated Effluent Disposal Facility (TEDF) and is active (see 600-291-PL). The pipeline from 207-B to Diverter Station #2 is constructed of 56 centimeter (22 inch) diameter plastic pipe (subsite 1). The pipeline east of Diverter Station #2 splits into two pipelines. Southern part extends from Diverter Station #2 to the head end of the 216-B-3 ditches. It is constructed of 53 centimeter (21 inch) diameter vitrified clay pipe (subsite 2). The northern part extends from Diverter Station #2 to Diverter Station #3 and is constructed of 61 centimeter (24 inch) diameter corrugated metal pipe (subsite 3). The pipelines are marked with steel posts and Underground Radioactive Material - Pipeline signs. A piece of (30 inch) diameter corrugated Metal pipe that connects the southeast corner of 216-B-3A pond to the northeast corner of 216-B-3C pond. It is considered part of this waste site (subsite 4) because it is associated with pond effluent distribution and is not part of the TEDF system.

Location: The pipeline extends eastward from the 207-B Retention Basin, to Diverter Station #2. The

pipeline splits into two branches east of Diverter Station #2. A portion of pipeline extends from Diverter #2 to the 216-B-3 ditches. A branch of pipeline extends eastward from Diverter Station #2 and runs to Diverter Station #3. A separate section of corrugated metal pipe connects the southeast corner of the 216-B-3A Lobe to the northwest corner of the 216-B-3C lobe.

Related Sites/ Structures: The site is associated with Diverter Stations #2 and Diverter Station #3 (see sitecode 200-E-118) as well as the 207-B Retention Basin, B Plant, PUREX and the 200 East Powerhouse. Portions of the original pipeline were re-used to feed the TEDF system (600-291-PL).

Process Description: The pipeline conveyed B Plant effluent to the 216-B-3 Pond and Ditch system. B Plant cooling water effluent was originally routed through the 207-B Retention Basin to the 216-B-2-1, 216-B-2-2 and 216-B-2-3 ditches. In 1987, the 216-B-2-3 ditch was closed and was replaced by this, 22 inch diameter plastic underground pipeline. It extended from the 207-B basin to Diverter Station #2. By 1994, all of the open ditches (216-B-2-1, 216-B-2-2, 216-B-2-3, 216-B-3-1, 216-B-3-2 and 216-B-3-3) had been backfilled and surface stabilized. After 1994, all the effluent was conveyed to the 216-B-3A and 216-B-3C pond lobes only through underground pipelines. In 1995 the ponds were closed. The remaining effluent was transferred the Treated Effluent Disposal Facility (TEDF). Parts of the pipelines east of 200 East Area, that had fed the ponds, were re-used to feed the TEDF disposal basin. The TEDF portion begins at Manhole #8 and extends to Pump Station #3. In the event of a failure at Pump Station #3, the effluent can be routed to 216-B-3C (C lobe). The section that connects the southeast corner of 216-B-3A to the northwest corner of 216-B-3C is constructed of 76 centimeter (30 inch) corrugated metal pipe.

Waste Type: Process Effluent

Waste Description: The pipeline transported 221-B Plant, PUREX, and 200 East Area Powerhouse effluent that included process cooling water, steam condensate and chemical sewer waste.

This Site has the Following SubSites:

Code: 200-E-126-PL:1

Names: 200-E-126-PL:1; 22-Inch Diameter Poly Pipe from 207-B to Diverter Station 2

Code: 200-E-126-PL:2

Names: 200-E-126-PL:2; 21 Inch Vitrified Clay Pipe from Diverter Station 2 to the Head End of 216-B-3 Ditches

Code: 200-E-126-PL:3

Names: 200-E-126-PL:3; 24-Inch Corrugated Metal Pipe from Diverter Station #2 to Diverter Station #3

Code: 200-E-126-PL:4

Names: 200-E-126-PL:4; 216-B-3B; 216-B-3C and 216-E-28 Contingency Pond; Pond Inlet Piping to 216-B-3A

Code: 200-E-126-PL:5

Names: 200-E-126-PL:5; 30-Inch Corrugated Metal Pipe Connecting 216-B-3A Pond to 216-B-3C Pond

Code: 200-E-126-PL:1

Classification: Accepted

Names: 200-E-126-PL:1; 22-Inch Diameter Poly Pipe from 207-B to Diverter Station 2

Reclassification: Rejected (10/19/2010)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This subsite became part of 200-E-126-PL-B.

Location: The pipeline segments in this waste site are located inside 200 East Area, west of the

Inner/Outer Area boundary. The waste site begins at the 207-B retention basin and terminates at the Inner/Outer Area boundary.

The SubSite is Part Of:

Code: 200-E-126-PL

Names: 200-E-126-PL; Underground Pipeline from 207-B to 216-B-3 Ditch

Code: 200-E-126-PL:2

Classification: Accepted

Names: 200-E-126-PL:2; 21 Inch Vitrified Clay Pipe from Diverter Station 2 to the Head End of 216-B-3 Ditches

Reclassification Rejected (10/19/2010)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This segment is the original pipeline from the 216-B-2 ditches to the 216-B-3 ditches. It is rejected because it became part of 200-E-126-PL-B.

Location: The pipeline segments in this waste site are located inside 200 East Area, west of the Inner/Outer Area boundary. The waste site begins at the 207-B retention basin and terminates at the Inner/Outer Area boundary.

The SubSite is Part Of:

Code: 200-E-126-PL

Names: 200-E-126-PL; Underground Pipeline from 207-B to 216-B-3 Ditch

Code: 200-E-126-PL:3

Classification: Accepted

Names: 200-E-126-PL:3; 24-Inch Corrugated Metal Pipe from Diverter Station #2 to Diverter Station #3

Reclassification Rejected (10/19/2010)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This segment was rejected because it became part of 200-E-126-PL-B.

Location: The pipeline segments in this waste site are located inside 200 East Area, west of the Inner/Outer Area boundary. The waste site begins at the 207-B retention basin and terminates at the Inner/Outer Area boundary.

The SubSite is Part Of:

Code: 200-E-126-PL

Names: 200-E-126-PL; Underground Pipeline from 207-B to 216-B-3 Ditch

Code: 200-E-126-PL:4

Classification: Accepted

Names: 200-E-126-PL:4; 216-B-3B; 216-B-3C and 216-E-28 Contingency Pond; Pond Inlet Piping to 216-B-3A

Reclassification Rejected (10/19/2010)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: These segments were rejected because they became part of 200-E-126-PL-A. These are individual pipe segments that fed the 216-B-3A from the northwest corner of the pond, the 216-B-3b from the northwest corner of the pond and the 216-B-3C from the northwest corner of the pond. This subsite also includes the inlet piping that could have fed the 216-E-28 Contingency Pond.

Location: The 200-E-126-PL-A pipeline segments are located east of the 200 East Area fence line, beyond the Inner/Outer Area boundary.

The SubSite is Part Of:

Code: 200-E-126-PL

Names: 200-E-126-PL; Underground Pipeline from 207-B to 216-B-3 Ditch

Code: 200-E-126-PL:5

Classification: Accepted

Names: 200-E-126-PL:5; 30-Inch Corrugated Metal Pipe Connecting 216-B-3A Pond to 216-B-3C Pond

Reclassification: Rejected (10/19/2010)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This segment was rejected because it became part of 200-126-PL-A.

Location: The 200-E-126-PL-A pipeline segments are located east of the 200 East Area fence line, beyond the Inner/Outer Area boundary.

The SubSite is Part Of:

Code: 200-E-126-PL

Names: 200-E-126-PL; Underground Pipeline from 207-B to 216-B-3 Ditch

Code: 200-E-127-PL

Classification: Accepted

Names: 200-E-127-PL; Line 1601; Pipeline from PUREX to Gable and B-Ponds (216-A-25 and 216-B-3); PUREX Cooling Water Line

Reclassification: Rejected (10/19/2010)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: Due to the restructuring of Operable Units, as described in the Tentative Agreement for Central Plateau Cleanup, this pipeline has been split into segments (see 200-E-127-PL-A and 200-E-127-PL-B). The majority of the pipeline is constructed of large diameter corrugated metal pipe. The 36 inch diameter corrugated metal pipe enlarges to 42 inch diameter corrugated metal pipe at Manhole #8 (north of B Pond). The pipeline is marked with steel posts and Underground Radioactive Material - Pipeline signs. Near the 810 gate, an area of growing contaminated vegetation was stabilized with biobarrier and posted with Underground Radioactive Material Area signs. A portion of the pipeline is under the Liquid Effluent Retention Facility (LERF) berm.

Location: The pipeline extends northward, along the east side of 200 East Area. It begins at the PUREX facility and the 216-A-42 Retention Basin. It continues northward to the 216-A-25 Pond (Gable Mountain Pond). A portion of the pipeline extends between the 241-A-201 Emergency Cooling Water storage tanks and the 216-A-42 diverter station.

Related Sites/ Structures: The pipeline is associated with the PUREX, B Plant and the 242-A Evaporator facilities and 216-A-25 (Gable Mountain Pond). Also see sitecode 200-E-118 (Diverter Structure #3), 241-A-201 Emergency Cooling Water Storage Tanks, 216-A-42 basin, 200-E-127-PL-A and 200-E-127-PL-B.

Process Description: The pipeline conveyed PUREX and B Plant effluent to the (216-A-25) Gable Pond or the (216-B-3) B Pond system. The effluent stream was directed to the preferred pond via Diverter Station #3. The pipeline south of Diverter Station #3 is constructed of 91 centimeter (36 inch) diameter corrugated metal. From Diverter Station # 3 northward to the 216-A-25 Pond, the pipeline is constructed of 107 centimeter (42 inch) diameter corrugated metal pipe. The portion of the pipeline between the 241-A-201 cooling water storage tanks and the 216-A-42 basin (30 inch VCP) was taken out of service in June 1992.

Waste Type: Process Effluent

Waste Description: The pipeline conveyed process cooling water from 202-A Building (Plutonium Uranium Extraction [PUREX] Plant). From May 1958 to 1960, the unit received the above plus cooling water from the contact condenser in the 241-A-431 Building. In 1960, the unit received the above plus the surface condensator cooling water in the 241-A-401 Building (A Tank Farm). From November 1967 to January 1968, the unit received the above plus the wastewater from the 284-E Powerhouse. From January 1968 to March 1969, the unit received the above plus the cooling water and steam condensate from the 244-AR Vault. In March 1969, the pipeline to the contact condenser cooling system from the 241-A-431 Building Vault was valved out. After March 1977, the unit received the above plus the 242-A Evaporator steam condensate cooling water. RHO-CD-798 shows a valve at the east end of the 216-B-2-3 Ditch connecting to PUREX Cooling Water Line to Gable Pond. The graphic is labeled "Effluent Pipelines and Transfer Capabilities for Gable Mountain and B Ponds".

Code: 200-E-134 **Classification:** Accepted

Names: 200-E-134; Potentially Contaminated Soil in 241-AW Tank Farm **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1980

Status: Inactive **End Date:**

Description: The site is the potentially contaminated soil inside the chain link fence that surrounds the 241-AW Tank Farm. Various radiological postings and warning signs (RA, RBA, RMA, URMA, Internally Contaminated Systems) are attached to the chain link fence. The interior of the tank farm complex is covered with gravel. Many risers and monitoring devices for the underground structures are visible on the surface. Currently, Contamination Area postings are located around the HEPA filter housing, pits, Clean Out Boxes and other equipment within the tank farm. In November 2010, the east side of the tank farm fence was expanded (150 feet long, 5 feet wide) to allow room for vehicles to maneuver around the exhauster skid.

Location: The 241-AW Tank Farm is located at the intersection of 4th Street and Canton Ave. in 200 East Area.

Process Description: The six tanks in the 241-AW Tank Farm are double shell construction.

Code: 200-E-136 **Classification:** Accepted

Names: 200-E-136; 202-A TSD; PUREX **Reclassification:** None

Type: Process Unit/Plant **Start Date:** 1/1/1956

Status: Active**End Date:** 1/1/1990

Description: This site is the entire PUREX Treatment, Storage, and Disposal (TSD) facility. It includes the individual tanks that had been provided separate WIDS codes; they are to be consolidated into this site. The PUREX Storage Tunnels are a separate TSD and are not a part of this site. The main part of the facility is the 202-A Building, in which the fuels were reprocessed. It is a reinforced concrete structure, 1,005 feet by 119 feet by 100 feet high (306 meters by 36 meters by 30 meters), with about 40 feet (12 meters) of the height below grade. The building consists of three main structural components: (1) a thick-walled concrete 'canyon' in which the equipment for radioactive processing is contained in cells below grade; (2) a pipe, sample, and storage gallery section; and (3) a steel and transite annex that houses offices, process control rooms, laboratories, and the building services. The portion of the canyon below grade is subdivided into a row of 12 process equipment cells paralleled by a ventilation air tunnel and pipe tunnel through which intercell solution transfers are made. The air tunnel exhausts the ventilation air from the cells to the main ventilation filters and stack.

Location: The PUREX Plant is located in the southeast corner of the 200 East Area.

Related Sites/ Structures: This site is associated with the individual components of this TSD that have their own WIDS numbers as of September 2001 are: 202-A-E-F11 (PUREX Tank E-F11), 202-A-E5 (PUREX Tank E5), 202-A-F15 (PUREX Tank F-15), 202-A-F16 (PUREX Tank F-16), 202-A-F18 (PUREX Tank F18), 202-A-G7 (PUREX Tank G7), 202-A-U3 (PUREX Tank U3), 202-A-U4 (PUREX Tank U4), and 202-A-WS-1 (PUREX Waste Piles). Site 216-A-29 (Snow's Canyon, PUREX Chemical Sewer) is TSD D-2-3. Sites 218-E-14 and 218-E-15 (PUREX Tunnels No. 1 and No. 2) are also a separate TSD S-2-1. Some of the major liquid effluent disposal facilities associated with PUREX are Gable Mountain Pond (216-A-25), B-Pond (216-B-3), and the 216-A-42 Trench, which received emergency radioactive discharges that were diverted from going to the ponds. Process condensate from the final uranium cycle was monitored for radioactivity and discharged through a stainless steel pipe to the 216-A-10 Crib south of the west end of PUREX. Steam condensate was also monitored for radioactivity and discharged to the 216-A-30 Crib east of PUREX. Ammonia scrubber waste condensate was sent to the 216-A-36B Crib south of PUREX. Steam and process condensates and acid overflow from the 203-A Area tanks were sent to the 216-A-3 Crib, north of the 203-A Tank Farm. Several radiologically controlled areas are adjacent to PUREX, including 200-E-103 on the south side and 200-E-107 on the east side. Site 200-E-44 is the PUREX Railroad Cut.

Process Description: PUREX was designed and constructed to provide supplemental fuel reprocessing capabilities to separate plutonium and uranium products from irradiated fuel. The PUREX process was designed to reprocess aluminum-clad uranium metal fuel to recover weapons-grade plutonium and depleted uranium. The process was later modified to reprocess zirconium alloy clad fuel from N Reactor to recover fuels-grade plutonium, slightly enriched uranium, and neptunium.

Waste Type: Equipment

Waste Description: Some of the waste remaining in the facilities include lead (in paint, light bulb contacts, shielding, pipe joints, washers affixing transite), mercury (thermostats and switches), asbestos (transite siding, insulation, gaskets), organic substances (greases and residues in gearboxes and bearings), PCBs (transformers, ballasts, lubricants, oils), cadmium (dissolver moderator lining in canyon cells), and silver (silver reactor in cells), chromium (in cell debris).

Code: 200-E-137**Classification:** Accepted**Names:** 200-E-137; 291-B Exhaust Stack; 291-B-1**Reclassification:** None**Type:** Stack**Start Date:** 1/1/1944**Status:** Inactive**End Date:** 1/1/1998

Description: The unit consists of a reinforced concrete stack, lined with acid-resistant brick resting on an octagonal, two-tiered foundation of brick and concrete. The stack is 61 meters (200 feet) high and 4.3 meters (14 feet) in diameter at the base.

Location: The exhaust stack is located south of the 221-B canyon building, west of the 291-B sand filter.

Related Sites/ Structures: The stack is associated with the 216-B-13 French Drain and the Sand Filter (sitecode 200-E-30).

Process Description: The stack provided air exhaust for the 221-B Canyon building. Sand Filters were added to the B Plant exhaust systems in 1948. The sand filter was constructed for use in conjunction with the bismuth phosphate process. Later, HEPA pre-filters (291-BC and BD, BF and BH) were installed in parallel with the sand filter.

Waste Type: Process Effluent

Waste Description: The air exhaust system was contaminated with radioactive particulates.

Code: 200-E-138 **Classification:** Accepted

Names: 200-E-138; 291-B Replacement Stack; 296-B-1 Exhaust Stack; Canyon Exhaust System; Canyon Ventilation Upgrade **Reclassification:** None

Type: Stack **Start Date:** 1/1/1998

Status: Active **End Date:**

Description: The 296-B-1 exhaust stack is a 29 meter (95 foot) carbon steel pipe anchored to the south side of the 221-B building.

Location: The 296-B-1 Stack is located adjacent to the south side of 221-B, Section 8.

Related Sites/ Structures: The stack is associated with 221-B, 221-BK and the ACT prefilter and HEPA filter banks. It replaced the 291-B Exhaust Stack (200-E-137).

Process Description: The new canyon exhaust system consists of two parallel Air Cleanup Trains (ACT) prefilters and two banks of High Efficiency Particulate Air (HEPA) filters.

Waste Type: Process Effluent

Waste Description: Filtered canyon air is exhausted through the stack.

Code: 200-E-140 **Classification:** Not Accepted

Names: 200-E-140; Gravel Pit 32 **Reclassification:** None

Type: Depression/Pit (nonspecific) **Start Date:**

Status: Inactive **End Date:**

Description: The site had been an open excavation containing gravel. A site visit in October 2004 noted that the construction of the new Immobilized Low-Activity Waste (ILAW) site had extended over the gravel pit area. No evidence of the gravel pit remains.

Location: The site is located south of the PUREX facility. It is north of 1st Street and west of Canton Ave. It is on the west side of the gravel road that leads to PUREX.

Related Sites/ Structures: 200-E-106 (Immobilized Low-Activity Waste storage)

Process Description: The site was used as a source of clean backfill material. It is a good source of sand and sandy soil.

Waste Type: Soil

Waste Description: The site is a source of backfill material. No waste is stored at this site.

Code: 200-E-146-PL

Classification: Accepted

Names: 200-E-146-PL; Tank Farm Transfer Line A-4013; Transfer Line from 241-CR-152 to 241-AX-151

Reclassification: Rejected (10/26/2006)

Type: Direct Buried Tank Farm Pipeline

Start Date:

Status: Inactive

End Date:

Description: A-4013 is a DUPLICATE entry. It is the same line as line 4103, described in sitecode 200-E-144-PL. Transfer Line A-4013 is radiologically posted as an Underground Radioactive Material Area. The pipeline is a 3 inch diameter, stainless steel pipe. The transfer line is located in the Interplant Transfer Encasement per drawing H-2-44501, sheet 92.

Location: Line A-4013 originates inside the 241-C Farm at the 241-CR-152 Diversion Box, passes through the 241-ER-153 Diversion Box and terminates at the 241-AX-151 Diverter Station at the corner of 4th Street and Buffalo Avenue in 200 East Area.

Related Sites/ Structures: Associated with Sitecode 200-E-144-PL

Code: 200-E-163-PL

Classification: Not Accepted

Names: 200-E-163-PL; Pipeline from BCS Diverting Pit to 216-B-64 Retention Basin

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The effluent line from the B Plant Condensate Steam (BCS) diversion pit consisted of three pipelines. Two lines were 5 centimeter (2 inch) carbon steel and one was an 20 centimeter (8 inch carbon) steel line.

Location: The pipeline is located west of 225-B, west of Atlanta Ave.

Related Sites/ Structures: The pipeline is associated with the 216-B-64 basin.

Code: 200-E-176-PL

Classification: Not Accepted

Names: 200-E-176-PL; Pipeline from 242-B to 216-B-11-A&B

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: Due to the restructuring of Operable Units, as described in the Tentative Agreement for Central Plateau Cleanup, this pipeline has been split into segments (see 200-E-176-PL-A and 200-E-176-PL-B). The waste site is an underground, 7.6 centimeter (3 inch) diameter, carbon steel pipeline.

Location: The pipeline extends northward from the 242-B Evaporator building to the 216-B-11 A cribs.

Related Sites/ Structures: The pipeline is associated with the 242-B evaporator and the 216-B-11 A&B cribs.

Process Description: The pipeline transported evaporator condensate waste to the cribs.

Code: 200-E-181-PL

Classification: Not Accepted

Names: 200-E-181-PL; 216-B-61 Crib Pipeline

Reclassification: None

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is an underground 10 centimeter (4 inch) diameter cast iron pipeline that was partially built, but never used.

Location: The pipeline is located northwest of the 241-BY Tank Farm.

Related Sites/ Structures: The pipeline is associated with the 216-B-61 crib.

Code: 200-E-210-PL

Classification: Accepted

Names: 200-E-210-PL; Lines Between 241-AW Tank Farm and 242-A Evaporator Building; Lines SL-167, SL-168, SN-219, SN-220, SN-269 and SN-270

Reclassification: None

Type: Direct Buried Tank Farm Pipeline

Start Date:

Status: Active

End Date:

Description: The waste site is four underground, carbon steel lines within the same trench. The lines are double contained, separated with a wood frame. Lines SL-167 and SL-168 are 5 centimeter (2 inch) diameter lines. Lines SN-219, SN-220, SN-269 and SN-270 are 7.6 centimeter (3 inch) diameter lines.

Location: The group of transfer lines extend northward from the 241-AW Tank Farm and connects to the west side of the 242-A Evaporator building. The lines cross under 4th Street.

Related Sites/ Structures: The lines are associated with the 241-AW-A and 241-AW-B, 241-A-A, 241-A-B valve pits, and the 242-A Evaporator facility.

Process Description: Lines SN-219 and SN-220 drop out of the encasement near the southwest corner of the 242-A Evaporator building and continue into the 241-A Tank Farm. They connect to the 241-A-A and 241-A-B Valve Pits. SN-219 and SN-220 are inactive lines. In October 2009, SL-167 and SN-269 are considered to be active lines. SL-168 and SN-270 are back up lines that could be used if SL-167 or SN-269 failed.

Code: 200-E-211-PL **Classification:** Accepted

Names: 200-E-211-PL; Lines DR334, DR335 and DR343; Transfer Lines from 241-AW to 242-A Evaporator Building **Reclassification:** None

Type: Direct Buried Tank Farm Pipeline **Start Date:**

Status: Active **End Date:**

Description: The waste site is three underground transfer lines buried in the same soil trench. Lines DR334 and DR335 are 25 centimeter (10 inch) diameter carbon steel lines double contained within 30 centimeter (12 inch) diameter carbon steel pipes. Line DR343 is a direct buried 15 centimeter (6 inch) diameter carbon steel pipe.

Location: The group of lines extend north from 241-AW Tank Farm to connect to the north side of the 242-A Evaporator Building. The lines cross under 4th Street.

Related Sites/ Structures: The lines are associated with 241-AW and the 242-A Evaporator.

Process Description: In October 2009, these lines were considered to be active.

Code: 200-E-212-PL **Classification:** Accepted

Names: 200-E-212-PL; Lines SL-509, SL-510, SN-609 and SN-610; Transfer Lines Between 241-AW Tank Farm and 241-AP Tank Farm **Reclassification:** None

Type: Direct Buried Tank Farm Pipeline **Start Date:**

Status: Active **End Date:**

Description: The waste site is four underground carbon steel pipelines buried in the same soil trench. Lines SL-509 and SL-510 are 5 centimeter (2 inch) diameter carbon steel pipes double contained inside 10 centimeter (4 inch) diameter carbon steel pipes. Lines SN-609 and SN-610 are 7.6 centimeter (3 inch) diameter carbon steel pipes double contained inside 15 centimeter (6 inch) diameter carbon steel pipes.

Location: The transfer lines extend from the east side of 241-AW Tank Farm to the west side of 241-AP Tank Farm. The cross under Canton Ave., north of 272-AW.

Related Sites/ Structures: The pipelines are associated with the 241-AW and 241-AP Tank Farms.

Process Description: In October 2009, these lines were considered to be active pipelines.

Code: 200-E-235-PL **Classification:** Accepted

Names: 200-E-235-PL; 207-A North Basin Distribution Lines; Lines 501,502, 503, 504, 506, and 507 **Reclassification:** Consolidated (5/31/2011)

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is 7.6 centimeter (3 inch) and 10 centimeter (4 inch) diameter carbon steel pipes that distributed waste from the 207-A pump pit to the three sections of the 207-A North basin.

Location: The 207-A North Retention Basin is located east of Canton Ave. and north of 4th Street. The distribution lines extend north from the 207-A pump pit.

Related Sites/ Structures: The distribution lines are associated with the 207-A pump pit and the 207-A North basins.

This Site Was Consolidated With:

Code: 207-A-NORTH

Names: 207-A-NORTH; 207-A-NORTH Retention Basin; 207-A; 207-A North; 207-A Retention Basin

Code: 200-E-236-PL

Classification: Accepted

Names: 200-E-236-PL; 207-A South Basin Distribution Lines; Lines 557, 558, 559, 560, 562, and 563

Reclassification: Consolidated (5/31/2011)

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is 7.6 centimeter (3 inch) and 10 centimeter (4 inch) diameter carbon steel pipes that distributed waste from the 207-A pump pit to the three sections of the 207-A South basin.

Location: The 207-A South Retention Basin is located east of Canton Ave. and north of 4th Street. The distribution lines extend south from the 207-A pump pit.

Related Sites/ Structures: The distribution lines are associated with the 207-A pump pit and the 207-A South basins.

This Site Was Consolidated With:

Code: 207-A-SOUTH

Names: 207-A-SOUTH; 207-A-SOUTH Retention Basin and Pump Pit; 207-A; 207-A Retention Basin; 207-A South

Code: 200-E-286

Classification: Accepted

Names: 200-E-286; A Swamp; A-Swamp and Ditch; Original 200 East Area Powerhouse Effluent Pond; Powerhouse Swamp

Reclassification: Rejected (11/4/2009)

Type: Pond

Start Date: 1/1/1946

Status: Inactive

End Date: 1/1/1953

Description: There is no longer any visible signs of the A-Swamp or the distal end of the ditch. The eastern end of ditch originally terminated east of where 241-A was built. The eastern end of the ditch was removed during the construction of 241-A Tank Farm and the later construction of 241-AP Tank Farm. The area where the swamp had been located is now underneath where the Grout Facility and Waste Treatment Plant were built.

Location: The Powerhouse Swamp had been located east of the 200 East Area fence, approximately where the head end of the 216-A-29 Ditch and Grout Facility were later constructed.

Related Sites/ Structures: This site is associated with the 200 East Powerhouse Ditch (sitecode 200-E PD) and the 216-A-29 Ditch.

Process Description: The original, horse shoe shaped ditch emptied into a shallow depression east of the 200 East Area fence known as the Powerhouse Pond from 1946 through 1953. In 1954, the powerhouse ditch effluent was redirected to B Pond. This is the ditch currently known as the 200 East Powerhouse Ditch (sitecode 200-E PD).

Code: 200-E-302 **Classification:** Accepted

Names: 200-E-302; 2715EC Steam Condensate and Overflow Drain; Miscellaneous Stream #224 **Reclassification:** None

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:**

Description: The drain is a 3 foot diameter, concrete structure.

Location: The drain is located southwest of the 2266 E building. It is near the northeast corner of 2715EC at N135661.2/E573627, approximately 1 foot from the corner of the building.

Code: 200-E-304 **Classification:** Accepted

Names: 200-E-304; 218-E-12B Trench 94, Submarine Trench **Reclassification:** None

Type: Burial Ground **Start Date:**

Status: Active **End Date:**

Description: The waste site is a large open pit. Many vessel reactor compartments are visible inside the trench.

Location: The burial ground is located inside 200 East Area, north of the 241-C Tank Farm and south of 12th Street.

Release Description: In 1995, 15 gallons diesel oil spilled to soil in Trench 94. The affected area was approximately 32 by 15 feet, 28 inches deep. The area was remediated and the soil was removed to Hanford Central Landfill. Reported Date: May 2, 1995.

Related Sites/Structures: The active trench 94 is associated with the inactive 218-E-12B burial ground.

Process Description: Trench 94 was designated to receive U.S. Navy defueled vessel nuclear reactor compartments (BHI-00178).

Code: 209-E-WS-1 **Classification:** Accepted

Names: 209-E-WS-1; 209-E French Drain **Reclassification:** Rejected (1/25/2000)

Type: French Drain **Start Date:**

Status: Inactive **End Date:**

Description: In 2011, amended water was sprayed during the 209E building demolition activities. Post-demolition, three to six inches of surface material was removed from all areas affected by the amended water and prior to applying a gravel cap. The final gravel cap was expanded to cover all affected areas. The posted URMA was expanded to include the entire gravel cap. The gravel cap now covers several WIDS sites. The additional WIDS sites under the 209E gravel cap are 200-E-4, 200-E-35, 209-E-WS-1, 209-E-WS-2, 2718-E-WS-1 and 200-E-293 (2718E)

footprint). The 209-E-WS-3 (Tank 111), adjacent to the south side of the foundation, is within the URMA but was not covered or backfilled.

The drain had a metal cover that was painted bright yellow, because it was located in a paved parking area. The unit was a french drain that is 1.2 meters (4 feet) in diameter and 2.4 meters (8 feet) deep.

Location: The unit is located in the parking area at the northeast corner of the 209-E Critical Mass Building, office wing.

Related Sites/ Structures: The site is associated with the 209-E Building and 200-E-294.

Process Description: This site received steam condensate only. Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The unit received steam trap condensate and steam condensate from 209-E.

Code: 216-E-28 **Classification:** Not Accepted

Names: 216-E-28; 200 East Area Contingency Pond; 216-E-25 **Reclassification:** None

Type: Pond **Start Date:** 1/1/1986

Status: Inactive **End Date:**

Description: This 216-E-28 Contingency Pond is inactive and dry. It is a large cobble filled depression that is divided into three lobes by soil berms. Each lobe has a 1.2 meter (48 inch) diameter corrugated metal culvert. It is not marked or posted.

Location: The 216-E-28 Contingency Pond is located east of the 200 East Area perimeter fence and north of the 216-B-3 Main Pond.

Related Sites/ Structures: The 216-E-28 Contingency Pond is associated with the 216-B-3 Pond system.

Process Description: When the 216-B-3 Main Pond and 216-B-3-3 Ditch were isolated, a new pipeline was built to divert effluent to the 216-B-3 Pond Expansion Lobes and this Contingency Pond. The 216-E-28 Contingency Pond was designed to receive effluents from the B Pond streams. It was held in reserve for any future embankment failures in the ponds. It was never needed and never used for this process. However, in 2007 drill cuttings and mud, from three boreholes and one corehole drilled at the Waste Treatment Project Vitrification site, was placed into the Contingency Pond.

Code: 218-E-3 **Classification:** Not Accepted

Names: 218-E-3; Construction Scrap Pit **Reclassification:** None

Type: Burial Ground **Start Date:** 1/1/1954

Status: Inactive **End Date:** 1/1/1971

Description: The pit was exhumed and material removed. It is now part of an open field with sparse vegetation (rabbitbrush and cheatgrass) growing in the gravel.

Location: The site was located in the extreme southwest corner of 200 East Area, north of Highway 4S. It was north of 1st Street and east of Akron Ave.

Waste Type: Construction Debris

Waste Description: The site received metal slip forms, barrels and timbers from the construction of 202-A that became contaminated with ruthenium-106 from a REDOX stack release.

Code: 218-E-6 **Classification:** Accepted

Names: 218-E-6; B Stack Shack Burning Pit; Buried Contamination **Reclassification** Rejected (5/13/2008)

Type: Burial Ground **Start Date:** 1/1/1955

Status: Inactive **End Date:** 1/1/1955

Description: The site is no longer marked or posted.

Location: Originally the site (burn pit) was located in the southeast corner of the 221-B Exclusion Area approximately 94 meters (300 feet) south of 221-B.

Related Sites/ Structures: The site was related to the 221-B exclusion area. Materials that were burned were collected from within this area and burned in the pit.

Process Description: At one time the site was a burn pit that was used to burn wooden items removed from the 291-B stack area during cleanup of the 221-B Exclusion Area. A trench approximately 1.2 meters (4 feet) deep was dug. The contaminated material was then burned and the remaining ashes were covered with soil. The site was excavated to determine the remaining activity. Pieces of partially burned wood and ashes were uncovered at a depth of 1.2 meters (4 feet). Radioactivity was non-detectable. The zone was released from Radiation Zone status in 1972.

Waste Type: Demolition and Inert Waste

Waste Description: According to the documentation, no waste remains at this site. In 1955, contaminated wooden forms, a shack and other wooden items were placed into a 1.2-meter (4-foot) deep trench and burned. The ashes were backfilled with dirt and the area was marked with "Underground Contamination" signs. In 1971, the site was excavated to a depth of 1.2 meters (4 feet). A radiological survey was done on the ashes and partially burned wood. No radiological contamination was found. The site was released from Radiation Zone status. Stenner et al. (1988) report that the site has been exhumed and the contents removed to a 200 East Area burial ground.

Code: 218-E-12B ANNEX **Classification:** Not Accepted

Names: 218-E-12B ANNEX; 218-E-12B Western Portion West of Trench 37; Unused Portion of 218-W-12B **Reclassification** None

Type: Burial Ground **Start Date:**

Status: Inactive **End Date:**

Description: The area is a barren field. The area designated for additional waste trenches in the western

portion of the 218-E-12B Burial Ground was never used.

Location: This site is located south of 12th Street in 200 East Area. It is west of trench 37 in the 218-E-12B burial ground.

Related Sites/ Structures: The 218-E-12B Annex is associated with WIDS sitecode 200-E-288, which documents a small amount of debris.

Process Description: Sixty-one of the proposed trenches were designed to be 370 meters (1,212 feet) long, thirty-one of the trenches were designed to be 293 meters (960 feet) long. The remaining proposed trenches would vary in length from 94 meters (307 feet) to 580 meters (1,901 feet).

Code: 218-E-14 **Classification:** Accepted

Names: 218-E-14; PUREX Storage Tunnel; PUREX Tunnel No. 1 **Reclassification:** None

Type: Storage **Start Date:** 1/1/1960

Status: Inactive **End Date:** 1/1/1965

Description: PUREX Tunnel Number 1 is an extension of the canyon railroad tunnel, extending south of the east end of the 202-A Building. It is an enclosed, above ground storage facility. It is approximately 109 meters (358 feet) long, 5.8 meters (19 feet) wide, and 6.9 meters (22.5 feet) high. The railroad tracks have a one percent downgrade to the south. The tunnel is ventilated by an absolute filtered exhauster at the south end of the tunnel. A water-fillable door has been drained and the tunnel door is sealed shut.

Location: The site is located south of the east end of the 202-A building.

Process Description: The tunnel construction was completed in 1956. The tunnel is filled to capacity with failed equipment from the PUREX canyon cells, on eight rail cars. A water-fillable door has been drained and the tunnel door has been sealed shut.

Waste Type: Equipment

Waste Description: This site received extremely large, heavy or highly contaminated waste equipment stored on eight railroad flatcars. The volume of waste on the rail cars ranges from 53 to over 168 cubic meters (1,900 to over 6,000 cubic feet). The curie content decayed through 1990 was 945.3 of cesium-137, 845.2 of strontium-90 and 0.0684 of ruthenium-106. Railcars 1&2 contain a HA column and jumpers with approximately 2400 curies of radioactive material. Railcar 3 contains a failed E-F11, 1WW waste concentrator with approximately 40,000 curies of radioactive material. Railcar 4 contains a G-2 centrifuge with approximately 3,000 curies of radioactive material. Railcar 5 contains a failed E-H4 waste concentrator with approximately 1,000 curies of radioactive material. Railcar 6 contains a failed E-F6, 2WW waste concentrator with approximately 700 curies of radioactive material. Railcar 7 contains a second failed E-F11, 1WW waste concentrator with approximately 40,000 curies of radioactive material. Railcar 8 contains a spare failed, waste concentrator with approximately 700 curies of radioactive material. 230 kilograms of lead is associated with the material on the railcars.

Code: 218-E-15 **Classification:** Accepted

Names: 218-E-15; PUREX Storage Tunnel; PUREX Tunnel No. 2 **Reclassification:** None

Type: Storage **Start Date:** 1/1/1967

Status: Inactive **End Date:** 1/1/1996

Description: The above grade tunnel is covered with soil. The railroad tracks have a one percent downgrade to the south end of the tunnel. The tunnel is constructed of a bituminous coated steel liner attached to external reinforced concrete. The tunnel is ventilated by a filtered exhauster at the south end of the tunnel. The water has been removed from the "water filled" door and the tunnel door has been sealed.

Location: PUREX Tunnel Number 2, located southeast of the 202A Building, is an extension of the railroad tunnel. It is east of 218-E-14 (Tunnel Number 1).

Process Description: The tunnel construction was completed in 1964. The tunnel stores contaminated equipment on flat bed rail cars and three empty liquid waste tank cars. Seventeen shipments were received during 1995 and 1996 from the 324 Laboratory Facility clean out activity. The last railcar was received in June 1996. The tunnel contained a total of 28 rail cars as of July 1996.

Waste Type: Equipment

Waste Description: The unit received extremely large, heavy or highly-contaminated waste equipment stored on railroad flat cars. The tunnel has the capacity to hold 40 railcars. As of June 1996, 28 railcars had been placed in the tunnel. The tunnel contains an estimated total of 2,730,000 curies of radionuclides and 762 grams (27 ounces) of plutonium. In addition to radioactive contaminants, the equipment stored in the tunnel also contains lead, silver, mercury, cadmium, chromium, barium and oil.

Code: 2607-E1A **Classification:** Accepted

Names: 2607-E1A; 2607-E1-A; 2607-E1A Septic System; L-272 Regional System **Reclassification:** None

Type: Septic Tank **Start Date:** 1/1/1997

Status: Active **End Date:**

Description: The system includes a septic tank, a dosing chamber and a three section drain field. The area is covered with gravel and marked appropriately.

Location: The septic system is located inside 200 East Area, north of 4th Street and west of Baltimore Ave.

Process Description: This system is designed to replace several smaller septic systems located in 200 East Area. The septic system is approved for a flow rate of 54,890 liters per day (14,500 gallons per day). The septic tank is a 82,350 liter (21411 gallon) tank, located east of the three drain fields. An area west of the drain fields has been reserved for a fourth drain field, that has been proposed for future use. A 52,500 liter (13,650 gallon) dosing tank is located adjacent to the septic tank.

Waste Type: Sanitary Sewage

Waste Description: The septic system receives sanitary waste with volumes up to 54,890 liters (14,500 gallons) per day.

Code: 2607-E8 **Classification:** Accepted

Names: 2607-E8; 2607-E8 Septic Tank and Tile Field **Reclassification:** Closed Out (11/9/2004)

Type: Septic Tank **Start Date:** 1/1/1953

Status: Inactive **End Date:** 1/1/1997

Description: The septic tank was properly abandoned in 1997. The septic tank surface is identified by two circular access ports surrounded with concrete. A sign, on the ground in April 2001, reads

"2607-E8". The associated drain field had a capacity of 13,400 liters (3,533 gallons) per day.

Location: This unit is located north of 1st Street and east of Baltimore Avenue, across from the 2101-M Building.

Related Sites/ Structures: The 2607-E8 Septic Tank was associated with the 2607-E8 Tile Field, the 2101-M Building, the MO-021, the MO-042, the MO-043, the MO-407, the MO-413, and the MO-234 Buildings. It was replaced by the 2607-E8A regional system.

Process Description: The 2607-E8 Septic Tank and associated drain field were designed to accept and treat sanitary sewer effluent from the connected facilities.

Waste Type: Sanitary Sewage

Waste Description: Septic Tank 2607-E8 receives sanitary wastewater and sewage at an estimated rate of 220 cubic feet (6.24 cubic meters) per day.

Closure Info: Final: The reclassification to Closed Out is documented on form 2004-121. The system was abandoned in 1997 in accordance with Washington Administrative Code 246-272-18501.

Code: 2607-E8A	Classification: Accepted
Names: 2607-E8A; 2607-E8-A; 2607-E8A Regional Septic System	Reclassification: None
Type: Septic Tank	Start Date: 1/1/1996
Status: Active	End Date:

Description: The septic system is surrounded with light posts and chain.

Location: The septic system is located south of the 284-E Powerhouse, on the east side of Baltimore Ave.

Related Sites/ Structures: The new regional system replaced the 2607-E8 septic tank and tile field.

Process Description: The system was constructed in 1996. It is approved by the State of Washington to receive a flow of 54,890 liters per day (14,500 gallons per day).

Waste Type: Sanitary Sewage

Waste Description:

Code: 2607-E10	Classification: Accepted
Names: 2607-E10	Reclassification: None
Type: Septic Tank	Start Date: 1/1/1993
Status: Active	End Date:

Description: The 2607-E10 Septic Tank system consists of two tanks and receives sanitary wastewater and sewage. The drain field associated with this system has a design capacity of 1,298 gallons (4,900 liters) per day.

Location: This unit lies north of the 216-A-37-1 Crib and east of the 241-AP Tank Farm, in the area known as the Grout Treatment Facility.

Related Sites/ Structures: The 2607-E10 Septic Tank is associated with a drain field, the Grout Trailer, MO-392, MO-041, MO-282, MO-283, MO-284, MO-997 and MO-243-G4.

Process Description: The 2607-E10 Septic Tank and associated drain field are designed to accept and treat sanitary sewer effluent from the connected facilities.

Waste Type: Sanitary Sewage

Waste Description: The 2607-E10 Septic Tank receives sanitary wastewater and sewage at an estimated rate of 665 gallons (2,500 liters) per day.

Code: 2607-E11

Classification: Accepted

Names: 2607-E11; 2607-E11 Septic Tank

Reclassification: Closed Out (11/9/2004)

Type: Septic Tank

Start Date: 1/1/1985

Status: Inactive

End Date: 1/1/1997

Description: The unit was properly abandoned in 1997. It is a two-chamber tank. The tank has an associated drain field and had a capacity of 3,500 liters (927 gallons) per day.

Location: The site is located inside 200 East Area, north of 4th Street and east of Baltimore Ave. The system is located southeast of the Dry Materials Receiving and Handling silos.

Related Sites/Structures: The 2607-E11 Septic Tank was installed to support the Dry Materials Receiving and Handling Facility (2400-E) Building, the Transportable Grout Facilities, and the MO-385, MO-386, MO-354 trailers.

Process Description: The 2607-E11 Septic Tank and associated drain field were designed to accept sanitary sewer effluent from the 2400-E Building, the Transportable Grout Facilities, MO-385, MO-386, MO-354 and the Dry Materials Receiving and Handling Facility. This project was abandoned and it's associated buildings are no longer occupied.

Waste Type: Sanitary Sewage

Waste Description: This system received sanitary wastewater and sewage at an estimated rate of 835 gallons (3160 liters) per day. There are no sampling results or inventory information available for this site.

Closure Info: Final: The Closed Out reclassification is documented on form 2004-104. The system was abandoned in 1997 in accordance with Washington Administrative Code 246-272-18501. It was replaced by a new regional system.

Code: 2607-E14

Classification: Accepted

Names: 2607-E14; A Farm Pipefitters Shop Septic; 242-AC Septic

Reclassification: None

Type: Septic Tank

Start Date:

Status: Active

End Date:

Description: The waste site is an underground septic tank that services the A Tank Farm Pipefitters shop building.

Location: The 242-AC Pipefitter Shop is located near the corner of 4th Street and Buffalo Ave. in 200 East Area. The septic tank is located north of 242-AC.

Code: 2607-EH

Classification: Accepted

Names: 2607-EH; 2607-EH Septic System

Reclassification: Rejected (5/31/2001)

Type: Septic Tank**Start Date:****Status:** Inactive**End Date:****Description:** WIDS site 2607-EH has been described as a septic tank and associated drain field.**Location:** This septic system has been described as being located on the west side of Baltimore Avenue adjacent to the east side of the 2101-M Building.**Waste Type:** Sanitary Sewage**Waste Description:** According to the Hanford Site Waste Management Units Report (Cramer, 1987), the 2607-EH Septic System received sanitary wastewater and sewage from the 2101-M building at an estimated rate of 1.36 cubic meters (48.00 cubic feet) per day.

Code: 2607-EJ**Classification:** Accepted**Names:** 2607-EJ; 2607-EJ Septic System**Reclassification:** Closed Out (5/31/2001)**Type:** Septic Tank**Start Date:****Status:** Inactive**End Date:****Description:** The 2607-EJ Septic System was removed during the construction of the 241-AP Tank Farm. It was the original system that serviced the 272-AW building. The tank and drainfield were removed as part of the 50 foot deep excavation for the 241-AP Tank Farm.

The concrete septic tank was divided into two compartment with volumes of 7800 liters (2000 gallons) and a 3900 liters (1000 gallons). It measured 5.9 meters (19.5 feet) long, 2.1 meters (7 feet) wide, and 1.8 meters (6 feet) deep (outer dimensions). The tank had three 0.6 meter (2 foot) access ports which were covered with concrete lids. The tank was connected to a small concrete distribution box which routed the waste from the tank to the sanitary drainfield. The drainfield consisted of five 15 meter (50 foot) runs of perforated drain tile.

Location: The 2607-EJ Septic System was located east of 272-AW and west of tank 241-AP-103.**Related Sites/ Structures:** The 2607-EJ Septic System was associated with the 272-AW Building.**Process Description:** The 2607-EJ Septic Tank and the associated drain field were designed to accept sanitary sewer effluent.**Waste Type:** Sanitary Sewage**Waste Description:** The 2607-EJ Septic System received sanitary wastewater and sewage.**Closure Info:** Final: The reclassification to Closed Out is documented on form 2001-025. The 2607-EJ Septic System was removed during site preparation for the construction 241-AP Tank Farm. The tank and drainfield were in the layback for the 15 meter (50 foot) deep excavation for the tank farm.

Code: 2607-EK**Classification:** Accepted**Names:** 2607-EK**Reclassification:** Closed Out (5/31/2001)**Type:** Septic Tank**Start Date:** 1/1/1975**Status:** Inactive**End Date:** 1/1/1997**Description:** The 2607-EK Septic Tank is a reinforced concrete tank and posted in the field as "Septic Tank"

2607EK." The associated drainfield is east of the tank. The drainfield is comprised of eleven parallel runs of 15 centimeter (6 inch) perforated drain pipe. The runs are 27 meters (90 feet) long and spaced 2.4 meters (8 feet) apart.

Location: The 2607-EK septic system is located east of Baltimore Avenue, northeast of the 2750-E building, and south of the 2607-E8 Septic System.

Related Sites/ Structures: The 2607-EK Septic Tank is associated with the 2750-E Building.

Process Description: The 2607-EK Septic Tank and associated drain field were designed to accept sanitary sewer effluent from the 2750-E Building.

Waste Type: Sanitary Sewage

Waste Description: The 2607-EK septic system received sanitary sewer effluent from the 2750-E Building at an estimated rate of 39.2 cubic meters (1,384 cubic feet) per day.

Closure Info: Final: The reclassification to Closed Out is documented on form 2001-031. The 2607-EK system was abandoned in 1997 in accordance with Washington Administrative Code 246-272-18501.

Code: 2607-EL **Classification:** Accepted

Names: 2607-EL; 2607-EL Septic Tank/Pump Station **Reclassification** None

Type: Septic Tank **Start Date:**

Status: Active **End Date:**

Description: The site is surrounded with steel posts and chain. It is marked with Septic Tank signs. Three access ports are visible on the surface. This septic tank/pump station is a part of the 2607-EP System which was reconstructed in 1994. 2607-EL is permitted and approved by the Washington Department of Health for a flow of 54, 890 liters per day.

Location: The site is located south of 4th Street, near the western entrance to 200 East Area. The septic system is located south of 2727-E and west of MO-294.

Process Description: The unit receives sanitary sewage from MO-286 and MO-294.

Waste Type: Sanitary Sewage

Waste Description: The waste is human sanitary sewage.

Code: 2607-EM **Classification:** Accepted

Names: 2607-EM **Reclassification** None

Type: Septic Tank **Start Date:** 1/1/1984

Status: Active **End Date:**

Description: The site consists of the 2607-EM Septic Tank and pump station. The system is connected to the 2607-EP dosing chamber, which is connected to the 2607-EP Drainfield (soil absorption system).

Location: This unit lies northwest of the associated drain field and southeast of the 2721-E Building.

Related Sites/ Structures: The 2607-EM Septic Tank is associated with the 2721-E Building.

Process Description: The 2607-EM Septic Tank and associated drain field receive sanitary sewer effluent from the 2721-E Building. The tank is constructed of reinforced concrete and receives sanitary wastewater and sewage from the 2721-E Building.

Waste Type: Sanitary Sewage

Waste Description: The 2607-EM septic system receives sanitary sewer effluent from the 2721-E Building at an estimated rate of 217 cubic feet (6.14 cubic meters) per day.

Code: 2607-EP	Classification: Accepted
Names: 2607-EP; 2607-EP Septic System	Reclassification: None
Type: Septic Tank	Start Date: 1/1/1984
Status: Active	End Date:

Description: The 2607-EP Septic System includes a septic tank and associated drainfield.

Location: This unit is located inside 200 East Area, south of 4th Street. It lies southeast of the MO-388 and northeast of the 2721-E Building.

Related Sites/ Structures: The 2607-EP Septic Tank is associated with systems 2607-EM, 2607-EN, and 2607-EO. Prior to 1994, this system (consisting of two underground tanks) received sanitary sewage effluent from the 2721-EA Building and the MO-388.

Process Description: The 2607-EP Septic Tank and associated drain field are designed to accept sanitary sewer effluent from the 2607-EM, the 2607-EN, and the 2607-EO systems, as well as the 2721-EA building and the MO-388.

Waste Type: Sanitary Sewage

Waste Description: The 2607-EP system receives effluent from the 2721-EA Building and MO-388 at an estimated rate of 28.30 cubic feet (0.80 cubic meters) per day.

Code: 2607-EQ	Classification: Accepted
Names: 2607-EQ	Reclassification: None
Type: Septic Tank	Start Date: 1/1/1985
Status: Active	End Date:

Description: The 2607-EQ Septic Tank is constructed of reinforced concrete. The associated drainfield is approximately 4,644 square feet (431 square meters).

Location: This unit lies northwest of the 2753-E Building and southeast of the Ames Avenue and Second Street intersection.

Related Sites/ Structures: The 2607-EQ Septic Tank is associated with the 2751-E, the 2752-E, and the 2753-E Buildings, as well as the MO-276, the MO-277 and the MO-285.

Process Description: The 2607-EQ Septic Tank and associated drain field are designed to accept sanitary sewer effluent from connected facilities (2571-E, 2752-E, 2753-E, MO-276, MO-277 and MO-285).

Waste Type: Sanitary Sewage

Waste Description: The 2607-EQ septic system receives sanitary sewage effluent at an estimated rate of 477 cubic feet (13.5 cubic meters) per day in 1987.

Code: 2607-ER **Classification:** Accepted
Names: 2607-ER **Reclassification:** Closed Out (5/31/2001)
Type: Septic Tank **Start Date:** 1/1/1980
Status: Inactive **End Date:** 1/1/1997

Description: The 2607-ER system was properly abandoned in 1997. It includes a septic tank and a trench type drain field. The tank has two access ports. As of February 20, 2001, it was not posted in the field.

Location: The site is located north of the 2101-M Building and west of Baltimore Avenue, just south of the railroad tracks.

Related Sites/ Structures: The 2607-ER Septic Tank is associated with the MO-047, the MO-251, the MO-252, and the MO-253.

Process Description: The 2607-ER Septic Tank and associated drain field were designed to accept sanitary sewer effluent from connected facilities (MO-047, the MO-251, the MO-252, and the MO-253).

Waste Type: Sanitary Sewage

Waste Description: The 2607-ER septic system received sanitary sewage effluent from the MO-047, the MO-251, the MO-252, and the MO-253 at an estimated rate of 5,753 liters (1,520 gallons) per day.

Closure Info: Final: The reclassification to Closed Out is documented on form 2001-032. The system was abandoned in 1997 in accordance with Washington Administrative Code 246-272-18501. The facilities were connected to a new regional system designated 2607-E8A.

Code: 2703-E HWSA **Classification:** Accepted
Names: 2703-E HWSA; 2703-E Hazardous Waste Storage Area **Reclassification:** Rejected (9/6/2000)
Type: Storage Pad (<90 day) **Start Date:** 1/1/1984
Status: Inactive **End Date:** 1/1/1996

Description: The site was a hazardous waste storage area located in a three-sided steel shed. The shed is on a concrete pad. The site is currently in use as an equipment storage area. There is a metal cabinet in the shed that is used to hold non-regulated soiled shop rags for pickup by the laundry services.

Location: The site was located in a steel shed on the east side of 2703-E, north of the compressor building.

Related Sites/ Structures: The 2703-E Hazardous Waste Staging Area was associated with the 2703-E Building.

Process Description: The 2703-E Hazardous Waste Staging Area was designed to temporarily store liquid hazardous waste before disposal.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: The 2703-E Hazardous Waste Staging Area typically contained wastes such as alkaline liquids, sodium hydroxide, sodium dichromate containing process solutions, and waste acids. Use of the 90-day waste storage pad was discontinued by November 4, 1996.

Code: 2704-E HWSA **Classification:** Accepted
Names: 2704-E HWSA; 2704-E Hazardous Waste Storage Area **Reclassification** Rejected (9/14/2000)
Type: Storage Pad (<90 day) **Start Date:** 11/1/1985
Status: Inactive **End Date:** 1/1/1991

Description: The site was an asphalt pad. It is no longer visible. The location is not marked or posted, and the area is now covered with grass.

Location: The 2704-E Hazardous Waste Staging Area was located southwest of the current MO-257 and northeast of the intersection of Atlanta Avenue and Fourth Street. This 2704-E building was located east of the 2711-E Garage, but has been demolished.

Related Sites/ Structures: The 2704-E Hazardous Waste Staging Area was associated with the former 2704-E Building.

Process Description: The 2704-E Hazardous Waste Staging Area was designed to temporarily store hazardous materials before disposal.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: Typical liquid wastes contained at the 2704-E Hazardous Waste Staging Area included antifreeze, grease, diesel fuel, and asphalt.

Code: 2718-E-WS-1 **Classification:** Accepted
Names: 2718-E-WS-1; 2718 French Drains **Reclassification** Rejected (1/25/2000)
Type: French Drain **Start Date:**
Status: Active **End Date:**

Description: The site consists of two french drains associated with the 2718-E Building. One of the french drains is not visible in the field. It was used to drain a swamp cooler, according to Hanford drawing H-2-44301. The other french drain is actually a pit used only to drain clean water from the fire sprinkler system at the 2718-E building. It has a metal lid. The inside is dry with a valved pipe in the bottom.

Location: The site is located north of 2718-E Building, inside the 209-E security fence.

Related Sites/ Structures: The site is related to the 2718-E Building.

Process Description: One is used to drain a swamp cooler, the other drains clean water from the fire sprinkler system at the 2718-E. The fire system is a dry pipe system, needing occasional testing. After testing, the water must be drained. There are no other sinks, drains or other water sources going to these french drains.

Waste Type: Water

Waste Description: One french drain receives clean raw water from testing the fire system; the other received water from a swamp cooler when it was drained for the winter.

Code: 2715-EA HWSA **Classification:** Accepted

Names: 2715-EA HWSA; 2715-EA Paint Spray Booth Annex; 2715-EA Hazardous Waste Storage Area **Reclassification** Rejected (9/14/2000)

Type: Storage Pad (<90 day) **Start Date:** 1/1/1984

Status: Inactive **End Date:**

Description: The 2715-EA Hazardous Waste Staging Area is no longer active. All associated wastes have been removed. The area is currently used for storing new drums, excess material, scrap metal for recycling, non-regulated wastes, and flammable materials.

The pad was in a shed, which is still standing, with a chain link fence as the front wall. Adjacent to the west side of the shed are two conex boxes and two chain-link fenced areas which are used as additional storage space. During a site visit on April 11, 2000, it was observed that the shed is labeled "No Smoking," "New Drum Storage" and "Danger - Items in this Building Contain Asbestos." The shed corresponds to the mapped location for building 2715-EA but the shed is not labeled with this number nor could any nearby building be located with this number. The shed contains primarily drums and also some packaged material sitting on a pallet. Material sitting on the concrete in front of the shed includes: other new drums, dollies for moving the drums, wooden boxes and metal cabinets. Some of the metal cabinets are marked "Excess." There are two conex boxes just west of the shed. These are marked "Conex 1" and "Conex 2." Conex 2 is closest to the shed. Both conex boxes have vents on the top. The area between the two conex boxes and the area between Conex 2 and the shed are fenced. The area between the two conex boxes is labeled "No Smoking or Open Flame" and "Non-regulated Waste Storage." The area between Conex 2 and the shed is labeled "Empty Drums to be Crushed for Scrap Metal." This second fenced area also contains two yellow metal cabinets marked "Flammable." Deford and Carpenter (1995) reported that one of these fenced areas was labeled with "Hazardous Waste 90-Day Storage" signs.

Location: This site is located northwest of the 275E Building and east of the 2715-ED Building.

Process Description: The 2715-EA Hazardous Waste Staging Area was designed to temporarily store hazardous waste related to the paint shop activities before disposal.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: The typical wastes held here were waste paint and thinning solvents.

Code: 2607-FSN **Classification:** Accepted

Names: 2607-FSN; 609A Building Septic Tank 2607-FSN; 6607-04; 6607-4 **Reclassification** Closed Out (11/9/2004)

Type: Septic Tank **Start Date:** 1/1/1960

Status: Inactive **End Date:** 1/1/1988

Description: The 2607-FSN Septic Tank was properly abandoned in 1988. The tank and drainfield lie beneath an asphalt walkway and several trees.

Location: The 2607-FSN septic system was located at the southeast corner of the 609-A Building (200 Area Fire Station), which is located on the south side of Route 3 in the 600 Area.

Related Sites/ Structures: The 2607-FSN system was associated with the 609-A Building.

Process Description: The 2607-FSN Septic Tank system received sanitary wastewater and sewage from the 609-A Building and disposed of it through a sub-surface soil absorption system.

Waste Type: Sanitary Sewage

Waste Description: The 2607-FSN septic system received sanitary wastewater at a rate of approximately 1,250 gallons (4,731 liters) per week.

Closure Info: Final: The reclassification to Closed Out is documented on form 2004-113. The system was abandoned and replaced by the 6607-4 septic system in 1988. It also is tied into the 2607-EP tank.

Code: 2607-GF

Classification: Accepted

Names: 2607-GF; 2607-GF Septic System; 2607-GF Septic Tank and Drain Field

Reclassification: Rejected (5/31/2001)

Type: Septic Tank

Start Date:

Status: Inactive

End Date:

Description: WIDS site 2607-GF was described in Cramer (1987) as a septic tank and associated drain field. However, it likely does not exist.

Location: This system has been described as being located north of the Dry Materials Receiving and Handling Facility (2400E) and across the railroad tracks that run on the north side of the facility.

Waste Type: Sanitary Sewage

Waste Description: According to the Hanford Site Waste Management Units Report (Cramer, 1987), the 2607-GF Septic System is not currently in use. This unit received sanitary sewage effluent from the Dry Materials Receiving and Handling Facility.

Code: 2101-M POND

Classification: Accepted

Names: 2101-M POND; 2101-M Pond

Reclassification: Closed Out (10/26/1995)

Type: Pond

Start Date: 1/1/1953

Status: Inactive

End Date: 1/1/1995

Description: The site RCRA TSD Permit was Closed Out in 1995. The pond was an unlined, "U" shaped ditch. It was surrounded with post and chain. Many tumbleweeds collected in this area.

Location: The pond was located west of the 2101-M Building.

Related Sites/Structures: The site is associated with the 2101-M building effluent discharges.

Process Description: The pond had been in service since 1953. The BWIP laboratory has been located in this building since 1983. Prior to the July 1985 initiation of administrative controls 'in the BWIP laboratory to prohibit discharge of hazardous waste, the 2101-M pond received laboratory waste solutions including solutions of barium chloride, and nitric and hydrochloric acids. The total amount of barium chloride discharged to the site is estimated to be more than 1 but less than 10 kg (2.7 to 27 lb) from 1983 to 1985. (The laboratory hazardous wastes are now * collected for offsite disposal.) The inventory of items purchased for this laboratory includes about 300 chemicals and commercial chemical products. Between September 1985 and September 1986, approximately 860 kg (2,320 lb) of hazardous waste solutions were collected for disposal at the 2101-M laboratory. Similar annual amounts may have been discharged via the laboratory drains from 1983 until July 1985.

The pond became active in 1953 to receive swamp cooler water from the 2101-M air

conditioning system, storm water run off and steam traps. In 1983, the Basalt Waste Isolation Project added some laboratories to the 2101-M building. The laboratory sinks also drained to the 2101-M Pond until 1985. In July 1985, administrative controls were implemented to prevent the discharge of regulated waste to the 2101-M Pond.

Waste Type: Water

Waste Description: From 1953 until 1983, the pond received small volumes of swamp-cooler condensate, overflow drain wastewater from the 2101-M air conditioning system, steam trap condensate and storm water runoff. From 1983 to July 1984, approximately 1200 gallons of laboratory waste, including as barium chloride solutions, nitric acid and hydrochloric acid, were discharged to the unit. Quantities are estimated at less than 1900 liters per year (500 gallons per year). Nitric acid and hydrochloric acid discharge quantities are estimated at 1 to 10 kilograms per year (2.2 to 22 pounds per year).

Closure Info: Final: The site has been sampled and analyzed for hazardous components. The RCRA TSD unit was Clean Closed in accordance with the Washington Administrative Code (WAC) closure performance standards. The letter of acceptance from Ecology was received 10/30/1995.

Code: 212-N

Classification: Accepted

Names: 212-N; 212-N Building; 212-N Fissile Storage Facility; Metal and Fuel Storage Basin Facility

Reclassification: Rejected (5/18/2010)

Type: Storage

Start Date: 1/1/1945

Status: Inactive

End Date: 1/1/1952

Description: The waste site was evaluated and reclassified to Rejected. The 212-N building was demolished under a CERCLA Removal Action in 2009. 212-N was composed of high bay, a fuel storage basin and a heater room. Each section has a concrete slab and roof and walls constructed of concrete and concrete block. Exterior dimensions of the high bay section is 8.2 by 23 by 9 meters (27 by 74 by 30 feet) high. The fuel storage basin section is 15 by 22 by 3.7 meters (49 by 72 by 12 feet) high. The heater room is 4.3 by 7.9 by 3.7 meters (14 by 26 by 12 feet) high. The total area is 555 square meters (5,970 square feet), the storage basin is 307 square meters (3,300 square feet), and the transfer basin is 37 square meters (400 square feet).

Location: The site was located north of Route 11A, halfway between the 200 East and 200 West Areas.

Related Sites/Structures: The building is associated with pipeline 600-285-PL, 216-N-1, 216-N-2 and 216-N-3.

Process Description: From 1945 to 1952, the facility was used to provide underwater storage of irradiated slugs from the 100 Areas. Slugs were stored in the 6.1-meter (20-foot) reinforced concrete basins. In 1970, twenty four boxes of transuranic (TRU) contaminated laboratory hoods and equipment from the 300 Area Plutonium Recycle Test Reactor (PRTR) were placed in the facility for storage.

Waste Type: Equipment

Waste Description: From 1944 to 1952, the facility was used to provide underwater storage of irradiated slugs from the 100 Areas. Slugs were stored in the 6.1-meter (20-foot) reinforced concrete basins. In 1970, twenty four boxes of transuranic (TRU) contaminated laboratory hoods and equipment from the 300 Area Plutonium Recycle Test Reactor (PRTR) were placed in the facility for storage. There is estimated to be 40 gram (1.4 ounces) of plutonium (byproduct). The total waste volume is 2.7 cubic meters (7,651 cubic feet). The waste was removed in 2006 and 2007.

Closure Info: Final: The basis for the reclassification of this site has been documented in the Response Action Report (RAR) for 212-N, 212-P, and 212-R Facilities Removal Action, DOE/RL-2010-031.

Functions of this removal action as discussed in the Remedial Design/Remedial Action Work Plan for 200 North Area Waste Sites located in the 200-CW-3 Operable Unit (RAWP) included utility isolations, characterization sampling, hazardous material removal, decontamination, structure demolition, disposition of waste materials and site stabilization (DOE/RL-2007-55). Removal design included removal of the discrete structural components and removal of the soils up to a depth of 1 meter (3.3 ft) beneath the basin and transfer pit of each structure. According to the RAWP, decontamination and demolition activities were conducted within the footprint of each structure, defined as the area covered by the structure as seen from a plan view, plus an additional 30 meters (98 ft) out from the perimeter of the walls. No formal design requirements were applicable to this removal action.

The removal action commenced in accordance with the RAWP in July 2009. Removal actions began on the 212-R and 212-N buildings in July 2009 and for 212-P in October 2009. Demolition and excavation activities were completed in November 2009. Post excavation soil evaluation activities began in October 2009 and concluded in January 2010.

In accordance with the Sampling and Analysis Plan (DOE/RL-2007-54), focused discrete samples were collected at visually indicated (soil that appeared to be visually darker or a different color than surrounding soil) locations and areas expected to contain higher levels of contamination based on process knowledge. One visually indicated (discoloration at 212-R) and a total of 37 judgmental samples were collected, 11 from 212-N and 13 each from 212-P and 212-R as indicated in Appendix A of the RAR. Detailed analytical data values were provided in Appendix B of the RAR.

Soil sampling data did not contribute to the overall completion of the removal action for the 212-N, 212-P and 212-R facilities. Rather, it addressed the post demolition soil evaluation discussed in the RAWP and SAP by which the soil areas remaining in the locations of the removed structures were investigated against the interim cleanup standards developed for the collocated wastes sites in the 200-CW-3 Operable Unit. The evaluation serves an investigative purpose to determine if further remediation was needed. Results of this evaluation demonstrated that a waste site designation for these areas for further remediation is not applicable.

During the collection of focused soil samples, radiological surveys were performed of the sample matrix. Surveying was performed using standard radiological survey instruments in accordance with accepted protocols and procedures to obtain dose and contamination measurements. No elevated dose rates (dose rates above established area background) were encountered to be further investigated.

Code: 212-P	Classification: Accepted
Names: 212-P; 212-P Building PCB Storage Facility; 212-P Storage Facility	Reclassification: Rejected (5/18/2010)
Type: Storage	Start Date: 1/1/1945
Status: Inactive	End Date:
Description: The waste site has been evaluated and reclassified to Rejected. The 212-P building was demolished under a CERCLA Removal Action in 2009. The building was composed of two main sections (High Bay and low roof sections) and a heater room. Each section had a concrete slab floor and walls constructed of concrete and concrete block.	
Location: The site was located north of Route 11A, halfway between 200 East and 200 West areas.	
Related Sites/ Structures: Associated with pipeline 600-286-PL, 216-N-4 and 216-N-5	

Process Description: From 1944 to 1952 the facility was used to store irradiated fuel rods prior to chemical processing in the 200 Areas. In 1982, the facility began to be used for storage of electrical transformers contaminated with PCB's. Shipments were made from the facility quarterly or as necessary to comply with the TSCA 9-month storage limitation. The High Bay portion of the building was used to store equipment and a 10,000 gallon tank of oil. The oil tank was placed on a "drip pan" secondary containment. A Dyncorp employee reported that the equipment and oil tank stored inside the High Bay has been removed.

Waste Type: Oil

Waste Description: Since 1982, this unit has held PCBs, and PCB-contaminated waste (nonradioactive) in temporary (up to 9 months) storage, according to TSCA (Toxic Substance Control Act). Radioactively contaminated PCBs are stored in another area of this unit. Waste types include 854 kg oil less than 50 p/M PCB; 1,348 kg oil greater than 50 p/M PCB; 703 PCB light ballasts, overpacked; 1,159 kg oil greater than 500 p/M PCB; 7 sealed transformers with less than 30 p/M PCB oil; 1 capacitor with 1% PCB askarel fluid; 11 low-voltage capacitors with greater than 50 p/M PCB oil; 2 electron microscope power supplies with greater than 50 p/M PCB oil; and 42 kg regulated solvents with greater than 500 p/M PCB. Drained items (as allowed under TSCA) are occasionally stored on an asphalt pad at the southwest corner of the building.

Waste Type: Equipment

Waste Description: Originally, the unit was built to provide underwater storage of irradiated slugs from the 100 Areas. Slugs were stored in the 20-ft reinforced concrete basins.

Closure Info: Final: The basis for the reclassification of this site has been documented in the Response Action Report (RAR) for 212-N, 212-P, and 212-R Facilities Removal Action, DOE/RL-2010-031. Functions of this removal action as discussed in the Remedial Design/Remedial Action Work Plan for 200 North Area Waste Sites located in the 200-CW-3 Operable Unit (RAWP) included utility isolations, characterization sampling, hazardous material removal, decontamination, structure demolition, disposition of waste materials and site stabilization (DOE/RL-2007-55). Removal design included removal of the discrete structural components and removal of the soils up to a depth of 1 meter (3.3 ft) beneath the basin and transfer pit of each structure. According to the RAWP, decontamination and demolition activities were conducted within the footprint of each structure, defined as the area covered by the structure as seen from a plan view, plus an additional 30 meters (98 ft) out from the perimeter of the walls. No formal design requirements were applicable to this removal action.

The removal action commenced in accordance with the RAWP in July 2009. Removal actions began on the 212-R and 212-N buildings in July 2009 and for 212-P in October 2009. Demolition and excavation activities were completed in November 2009. Post excavation soil evaluation activities began in October 2009 and concluded in January 2010.

In accordance with the Sampling and Analysis Plan (DOE/RL-2007-54), focused discrete samples were collected at visually indicated (soil that appeared to be visually darker or a different color than surrounding soil) locations and areas expected to contain higher levels of contamination based on process knowledge. One visually indicated (discoloration at 212-R) and a total of 37 judgmental samples were collected, 11 from 212-N and 13 each from 212-P and 212-R as indicated in Appendix A of the RAR. Detailed analytical data values were provided in Appendix B of the RAR.

Soil sampling data did not contribute to the overall completion of the removal action for the 212-N, 212-P and 212-R facilities. Rather, it addressed the post demolition soil evaluation discussed in the RAWP and SAP by which the soil areas remaining in the locations of the removed structures were investigated against the interim cleanup standards developed for the collocated wastes sites in the 200-CW-3 Operable Unit. The evaluation serves an investigative

purpose to determine if further remediation was needed. Results of this evaluation demonstrated that a waste site designation for these areas for further remediation is not applicable.

During the collection of focused soil samples, radiological surveys were performed of the sample matrix. Surveying was performed using standard radiological survey instruments in accordance with accepted protocols and procedures to obtain dose and contamination measurements. No elevated dose rates (dose rates above established area background) were encountered to be further investigated.

Code:	212-R	Classification:	Accepted
Names:	212-R; 212-R Storage Facility	Reclassification	Rejected (5/18/2010)
Type:	Storage	Start Date:	1/1/1945
Status:	Inactive	End Date:	1/1/1952
Description:	The waste site has been evaluated and reclassified to Rejected. The 212-R building was demolished under a CERCLA Removal Action in 2009. 212-R was composed of two main sections (the High Bay and the basin storage section) and a heater room. Each section has a concrete slab foundation and roof. The walls are constructed of concrete and concrete block.		
Location:	The site was located north of Route 11A, halfway between the 200 East and 200 West Areas.		
Related Sites/ Structures:	The facility is associated with pipeline 600-287-PL, 216-N-6, 216-N-7, UPR-200-N-1 and UPR-200-N-2.		
Process Description:	The 212-R Storage Facility was originally built to provide underwater storage of irradiated fuel rods from the 100 Areas. The fuel rods were allowed to decay in water filled basins (20 feet deep) before being sent to the 200 Areas for processing.		
Waste Type:	Equipment		
Waste Description:	The building and equipment within it may be contaminated. A 1988 Internal Memo related to the Strontium SemiWorks HEPA Filter 2 stored at 212-R states that the filter contains 9.0 mCi of Sr-90 and 185 uCi of Cs-137.		
Closure Info:	Final: The basis for the reclassification of this site has been documented in the Response Action Report (RAR) for 212-N, 212-P, and 212-R Facilities Removal Action, DOE/RL 2010-031. Functions of this removal action as discussed in the Remedial Design/Remedial Action Work Plan for 200 North Area Waste Sites located in the 200-CW-3 Operable Unit (RAWP) included utility isolations, characterization sampling, hazardous material removal, decontamination, structure demolition, disposition of waste materials and site stabilization (DOE/RL 2007 55). Removal design included removal of the discrete structural components and removal of the soils up to a depth of 1 meter (3.3 ft) beneath the basin and transfer pit of each structure. According to the RAWP, decontamination and demolition activities were conducted within the footprint of each structure, defined as the area covered by the structure as seen from a plan view, plus an additional 30 meters (98 ft) out from the perimeter of the walls. No formal design requirements were applicable to this removal action.		
	The removal action commenced in accordance with the RAWP in July 2009. Removal actions began on the 212-R and 212-N buildings in July 2009 and for 212-P in October 2009. Demolition and excavation activities were completed in November 2009. Post excavation soil evaluation activities began in October 2009 and concluded in January 2010.		
	In accordance with the Sampling and Analysis Plan (DOE/RL-2007-54), focused discrete samples were collected at visually indicated (soil that appeared to be visually darker or a different color than surrounding soil) locations and areas expected to contain higher levels of		

contamination based on process knowledge. One visually indicated (discoloration at 212-R) and a total of 37 judgmental samples were collected, 11 from 212-N and 13 each from 212-P and 212-R as indicated in Appendix A of the RAR. Detailed analytical data values were provided in Appendix B of the RAR.

Soil sampling data did not contribute to the overall completion of the removal action for the 212-N, 212-P and 212-R facilities. Rather, it addressed the post demolition soil evaluation discussed in the RAWP and SAP by which the soil areas remaining in the locations of the removed structures were investigated against the interim cleanup standards developed for the collocated wastes sites in the 200-CW-3 Operable Unit. The evaluation serves an investigative purpose to determine if further remediation was needed. Results of this evaluation demonstrated that a waste site designation for these areas for further remediation is not applicable.

During the collection of focused soil samples, radiological surveys were performed of the sample matrix. Surveying was performed using standard radiological survey instruments in accordance with accepted protocols and procedures to obtain dose and contamination measurements. No elevated dose rates (dose rates above established area background) were encountered to be further investigated.

Code:	203-S & 205-S	Classification:	Accepted
Names:	203-S & 205-S; 203-S Uranyl Nitrate Hexahydrate Tank Farm; 204-S; 204-S Tank Farm & Pumphouse; 205-S Process Vault & Chemical Makeup Building; 205-S Stabilized Area; 205-S Uranyl Nitrate Hexahydrate Processing Facility; 203-S	Reclassification	Consolidated (1/19/2005)
Type:	Process Unit/Plant	Start Date:	1/1/1953
Status:	Inactive	End Date:	1/1/1965
Description:	The aboveground tanks and features of these facilities were removed in 1983. The area was backfilled and surface stabilized. The site is currently a posted Underground Radioactive Material area.		
Location:	The facilities were located northwest of the 202-S (REDOX) facility.		
Related Sites/ Structures:	Structures associated with this site include the remains of the 205-S Chemical Makeup System, the 203-S Secondary Containment, the 205-S Vault, the above ground (dismantled) uranyl nitrate hexahydrate cross site transfer line, underground utilities, the salvaged or decommissioned tanks, and process equipment. It is also associated with 200-W-22 and unplanned releases UPR-200-W-10, UPR-200-W-83, UPR-200-W-86 and UPR-200-123.		
Process Description:	The 203, and 205-S Facilities were constructed in the early 1950's as a process unit for the decontamination of uranyl nitrate hexahydrate (UNH) produced by Reduction Oxidation (REDOX) operations. The primary process unit consisted of a column filled with silica gel that removed traces of fission products from the UNH. The silica gel column (SG-1) was located in the underground 205-S vault. The vault also contained a waste neutralization tank. Operations in the vault were accomplished remotely. The 205-S facility was a two story, aboveground, chemical make-up building. It contained two chemical make-up tanks, a UNH sample room and extensive piping connected to the REDOX facility and the underground vault. The 203-S facility was an aboveground UNH storage facility that consisted of two 19,000 liter (5,000 gallon) stainless steel tanks that were set in an open concrete basin. There was also a 204-S Tank Farm, that consisted of four 190,000 liter (50,000 gallon) aboveground tanks set in two open concrete basins. A UNH Unloading Facility was located at the adjacent railroad siding. An aboveground UNH pipeline connected the 203-S, 204-S, 205-S Area to the 224-U (UO3		

Plant). During the REDOX Plant operation, the UNH solution was pumped from REDOX to the 205-S silica gel column for purification. The purified UNH was stored in the 203 and 204 tanks and the routed to 224-U, via an above ground line, for final processing. The fission products left in the silica gel column were stripped out with nitric acid. The acid was neutralized and send to cribs. UNH from the PUREX Plant were transported by truck to the unloading station and placed in the 204-S tanks. The PUREX solutions were then processed through the silica gel column. After REDOX shut down (1965), the 203-S and 205-S were placed on standby. The Unloading Station was converted to a railcar unloading station. The 204-S tanks continued to store material from the Unloading Station. Shipments included thorium nitrate, 100-N Reactor decontamination solutions and 300 Area Laboratory wastes.

Waste Type: Process Effluent

Waste Description: Waste processed and stored in this area included contaminated UNH from REDOX and PUREX, Thorium Nitrate from PUREX, 100-N Reactor decontamination waste and 300 Area Laboratory waste. Radiological contaminants may be present in and around the remaining contaminated structures (cement basins and piping) that were not removed in the 1983 stabilization efforts.

This Site Was Consolidated With:

Code: 200-W-22

Names: 200-W-22; 203-S/204-S/205-S Stabilized Area

Code: 219-S-101

Classification: Accepted

Names: 219-S-101; 219-S-TK-101; TK-101 Crib Waste Receiver; TK-101 Receiver Tank; 219-S

Reclassification: None

Type: Storage Tank

Start Date: 1/1/1951

Status: Active

End Date:

Description: The 219-S-101 Tank is a monitored stainless steel receiver tank resting in a below grade concrete vault at the 219-S Waste Handling Facility.

Location: The tank is located in the north side of Cell A in the 219-S Building. The 219-S Building is located north of the northeast end of the 222-S Building.

Related Sites/Structures: The tank is associated with the other two 219-S Tanks, transfer lines, and the 222-S Laboratory (200-W-69).

Process Description: The 219-S-101 Tank receives liquid mixed waste from the 222-S Laboratory processes. Waste batches from Tank 219-S-101 and 219-S-104 are pumped to Tank 219-S-102, where sodium hydroxide and sodium nitrite are added to treat the waste. Tank 219-S-102 then pumps the waste to the double-shell tank farms.

The 219-S facility was built in the early 1950s as part of the 222-S liquid waste disposal system. 219-S originally consisted of three tanks (tanks 101, 102 and 103), enclosed in an epoxy coated, underground concrete vault. The vault has two cells. Cell A contains tanks 101 and 102. Cell B contains tanks 103 and 104. Tanks 101 and 103 (103 was later replaced with tank 104) collect and store liquid waste from the 222-S laboratory. When enough waste was collected, it is transferred to tank 102 and sampled, prior to being transferred to the tank farms. Prior to 1989, waste was transferred to the tank farm via underground lines, routed through 202-S. After 1989, the waste was transported to the tank farm via tank trailer trucks.

Waste Type: Process Effluent

Waste Description: The unit receives liquid mixed waste from the 222-S Analytical Laboratory processes. The waste is transferred to Tank 219-S-TK-102 for treatment with sodium hydroxide and sodium nitrate.

Code: 219-S-102 **Classification:** Accepted

Names: 219-S-102; 219-S-TK-102; 219-S Primary Treatment Tank TK-102; 219-S Storage Tank 102 **Reclassification:** None

Type: Neutralization Tank **Start Date:** 6/1/1951

Status: Active **End Date:**

Description: The 219-S-102 Tank is a monitored stainless steel treatment and transfer tank resting in a below grade concrete vault at the 219-S Waste Handling Facility.

Location: The tank is located in a below grade concrete vault in the south side of Cell A in the 219-S Building. The 219-S Building is located north of the northeast end of the 222-S Building.

Related Sites/Structures: The tank is associated with the other two 219-S Tanks, transfer lines, the double-shell tank farms, and the 222-S Laboratory (200-W-69).

Process Description: The 219-S facility was built in the early 1950s as part of the 222-S liquid waste disposal system. 219-S originally consisted of three tanks (tanks 101, 102 and 103), enclosed in an epoxy coated, underground concrete vault. The vault has two cells. Cell A contains tanks 101 and 102. Cell B contains tanks 103 and 104. Tanks 101 and 103 (103 was later replaced with tank 104) collect and store liquid waste from the 222-S laboratory. When enough waste was collected, it is transferred to tank 102 and sampled, prior to being transferred to the tank farms. Prior to 1989, waste was transferred to the tank farm via underground lines, routed through 202-S. After 1989, the waste was transported to the tank farm via tank trailer trucks.

Waste batches from tanks 219-S-101 and 219-S-104 are pumped to tank 219-S-102, where sodium hydroxide and sodium nitrite are added to treat the waste. Tank 219-S-102 then pumps the waste to the double-shell tank farms.

Waste Type: Process Effluent

Waste Description: The unit receives high activity mixed waste from the 222-S Laboratory processes. The waste is normally transferred from Tanks 101 and 104 for treatment. The waste is treated with sodium hydroxide to a pH greater than 12 and sodium nitrite to a concentration greater than 600 parts per million.

Code: 219-S-103 **Classification:** Accepted

Names: 219-S-103; 219-S Storage Tank 103 **Reclassification:** None

Type: Storage Tank **Start Date:** 6/1/1951

Status: Inactive **End Date:**

Description: The 219-S-103 Tank is a monitored stainless steel receiver tank resting in a below grade concrete vault at the 219-S Waste Handling Facility.

Location: The tanks are located in a below grade concrete vault in the south side of Cell B in the 219-S Building. The 219-S Building is located north of the northeast end of the 222-S Building.

Related Sites/Structures: The tanks are associated with the other two 219-S Tanks, transfer lines, the double-shell tank farms, and the 222-S Laboratory (200-W-69).

Process Description: The 219-S facility was built in the early 1950s as part of the 222-S liquid waste disposal system. 219-S originally consisted of three tanks (tanks 101, 102 and 103), enclosed in an epoxy coated, underground concrete vault. The vault has two cells. Cell A contains tanks 101 and 102. Cell B contains tanks 103 and 104. Tanks 101 and 103 (103 was later replaced with tank 104) collect and store liquid waste from the 222-S laboratory. When enough waste was collected, it is transferred to tank 102 and sampled, prior to being transferred to the tank farms. Prior to 1989, waste was transferred to the tank farm via underground lines, routed through 202-S. After 1989, the waste was transported to the tank farm via tank trailer trucks.

Tank 103 and its replacement tank 104 began service in 1996. Tank 103 was removed from service, blanked off, and left in place in 1999. They are both monitored stainless steel treatment and transfer tanks resting in a below grade concrete vault at the 219-S Waste Handling Facility. The 219-S-103 Tank used to receive high activity liquid mixed waste from the 222-S Laboratory processes. Waste batches from tanks 219-S-101 and 219-S-103 were pumped to tank 219-S-102, where sodium hydroxide and sodium nitrite were added to treat the waste. Tank 219-S-102 then pumped the waste to the double-shell tank farms. A 3.5 foot diameter (3 foot high) off gas filter is above 219-S-103. Drawing H-2-5234 labels the off gas filter tk-105.

Waste Type: Process Effluent

Waste Description: Tank 104 receives liquid mixed waste from the 222-S Analytical Laboratory processes. The waste is transferred to Tank 219-S-TK-102 for treatment with sodium hydroxide and sodium nitrite. Tank 103 used to receive high activity liquid mixed waste, that was then transferred to Tank 219-S-102 for treatment before being sent to the double-shell tank farms for storage.

Code: 219-S-104 **Classification:** Discovery

Names: 219-S-104; 219-S-TK-104; 219-S Storage Tank 104; 219-S-103 Replacement Tank **Reclassification:** None

Type: Storage Tank **Start Date:**

Status: Active **End Date:**

Description: 219-S-104 is the Replacement Tank for the 219-S-103 tank. The 219-S stainless steel tanks are located in a below grade concrete vault under the 219-S Waste Handling Facility building.

Location: The tanks are located on the south side of Cell B in the 219-S Building. The 219-S Building is located north of the northeast end of the 222-S Building.

Process Description: The 219-S tanks provide storage for hazardous and mixed waste. Tank 104 began service in 1996. Tank 219-S-104 replaced 219-S-103, which was removed from service and isolated. Similar to previous Tank 103 operations, Tank 104 receives liquid mixed waste, also from the 222-S Laboratory processes. Waste batches from tank 219-S-101 and 104 are pumped to tank 219-S-102, where sodium hydroxide and sodium nitrite are added to treat the waste. Tank 219-S-102 then pumps the waste to the double-shell tank farms.

The 219-S facility was built in the early 1950s as part of the 222-S liquid waste disposal system. 219-S originally consisted of three tanks (tanks 101, 102 and 103), enclosed in an epoxy coated, underground concrete vault. The vault has two cells. Cell A contains tanks 101 and 102. Cell B contains tanks 103 and 104. Tanks 101 and 103 (103 was later replaced with tank 104) collect and store liquid waste from the 222-S laboratory. When enough waste was collected, it is transferred to tank 102 and sampled, prior to being transferred to the tank farms. Prior to 1989, waste was transferred to the tank farm via underground lines, routed through 202-S. After 1989, the waste was transported to the tank farm via tank trailer trucks.

Code: 233-S	Classification: Accepted
Names: 233-S; 233-S Plutonium Concentration Facility	Reclassification: Rejected (6/25/2014)
Type: Process Unit/Plant	Start Date: 1/1/1952
Status: Inactive	End Date: 1/1/1967

Description: The above ground 233-S and 233-SA building structures were demolished in 2003 and 2004. A concrete cap was placed over the foundations. The area was then covered with gravel. A locked chain link fence surrounds the area. The fenced area is posted with Underground Radioactive Material Area signs.

Location: The facility was located at the northwest side of 202-S Building.

Related Sites/ Structures: Structures associated with the facility include process equipment, the 202-S Building, the 233-SA Building, UPR-200-W-57, UPR-200-W-43 and 200-W-253.

Process Description: From 1978 to 1980 the facility was used as a demonstration project for decommissioning of contaminated facilities. Between 1963 and 1967 the facility was used to concentrate neptunium and plutonium nitrate solutions from REDOX. Prior to 1963 the facility provided the final purification and concentration of plutonium solutions using ion exchange technologies. The 233-S Plutonium Concentration Facility was an inactive (retired) limited access facility after 1967. The building was a reinforced concrete and structural steel assembly with corrugated steel and concrete walls. The building had eight rooms, an airlock, and a highbay area. These rooms were divided into two zones by a vertical partition of transparent plastic and structural steel. The two zones include a process area and a process viewing area.

Waste Type: Chemicals

Waste Description: Chemical and radiological contaminants may still be present as residual materials in building systems.

Waste Type: Equipment

Waste Description: Process equipment, systems, and building surfaces may have fixed and removable contamination as a result of processing and UPR-200-W-57.

Waste Type: Asbestos (non-friable)

Waste Description: Piping insulation, wire insulation, and ventilation components may be insulated with asbestos containing materials. Transite is used on certain building components.

Code: 241-S-302B	Classification: Accepted
Names: 241-S-302B; 241-S-302-B Catch Tank	Reclassification: None
Type: Catch Tank	Start Date: 1/1/1952
Status: Inactive	End Date: 1/1/1985

Description: This unit is a horizontal, cylindrical steel tank. Tank 241-S-302B is underground to provide radiation shielding protection. The tank is surrounded with posts and chain and labeled with IMUST signs.

Location: The 241-S-302B Catch Tank is located east of tank 241-S-101, south of tank 241-SY-102 and southwest of tank 241-SY-103, inside the tank farm fence.

Related Sites/ Structures: The 241-S Tank Farm and 241-S-151 Diversion Box are associated with this unit.

Waste Type: Storage Tank

Waste Description: This unit was used for transfer of waste solutions from processing and decontamination operations. Volumes were variable according to specific plant operations.

Code: 242-S **Classification:** Accepted

Names: 242-S; 242-S Evaporator **Reclassification:** None

Type: Evaporator **Start Date:** 1/1/1973

Status: Inactive **End Date:** 1/1/1985

Description: The 242-S Evaporator is an inactive waste management unit. The principal operating areas of the evaporator include two adjoining, but structurally independent sections. Structure A, the processing and service area, is constructed of reinforced concrete shear walls and slab floors. Structure B of the building houses operating and support areas and is constructed of concrete block walls and structural steel.

Location: The site is located directly north of Tank 241-S-103 and lies outside the 241-S Tank Farm.

Related Sites/Structures: The structures associated with this facility include tanks 242-S-TK-C-100 and 242-S-TK-1, the 241-S Tank Farm, the 216-U-14 Ditch, the 216-S-25 crib, pipeline 200-W-161-PL, the HVAC Pad south of the building, and internal process equipment.

Process Description: The evaporation process reduced the volume of radioactive liquid by removing the water. The cooled vapor formed saltcake and residual liquor. This facility is currently in Condition III Standby, and the "B" Structure is used as a shift office for Tank Farms Operations Personnel. The "242-S Facility Shutdown/Standby Plan" provides a list of isolation work accomplished including pipelines that were blanked and equipment removed. Prior to 1980, the system was used to reduce the volume of radioactive liquid waste by evaporating water from the feed solution to produce a concentrated saltcake solution. The process condensate was sent back to the tanks. In 1985, a portion of the facility was used to process contaminated groundwater from the 216-U-1 and 216-U-2 crib area via the ion exchange column.

Waste Type: Chemicals

Waste Description: The unit received liquid radioactive mixed waste from the single-shell tanks through 1980. The evaporation process reduced the volume of radioactive liquid by removing the water. The cooled vapor formed saltcake and residual liquor.

Code: 276-S **Classification:** Accepted

Names: 276-S; 276-S Solvent Facility; 276-S Solvent Handling Facility **Reclassification:** Rejected (6/25/2014)

Type: Process Unit/Plant **Start Date:** 1/1/1952

Status: Inactive **End Date:** 1/1/1967

Description: The 276-S Building is a concrete and steel building, with transite siding on the portions of the building constructed of steel frame. The floor of the building is below grade, making up the processing area. Tanks and pumps make up most of the process equipment in the building.

Location: The building is located north of the 211-S Tanks and south of the 276-S-141 and 276-S-142 Hexone Tanks.

Related Sites/Structures: Structures associated with the site include several tanks and pumps inside the building, solvent transfer lines, the 211-S Tank Farm, and the 276-S-141 and -142 Solvent Storage Tanks.

Process Description: The 276-S Facility provided for the storage and treatment of REDOX process solvent (methyl isobutyl ketone).

Waste Type: Chemicals

Waste Description: This unit contains contaminated surfaces inside pumps, pits, and tanks. No inventory has been determined. Hexone contamination may also be present in building systems.

The Following Sites Were Consolidated With This Site:

Code: 296-S-12

Names: 296-S-12; 296-S-12 Stacks

Code: 291-S

Classification: Not Accepted

Names: 291-S; 291-S Fan and Filter Building; 291-S Fan Control Building; 291-S Fan House

Reclassification: None

Type: Process Unit/Plant

Start Date: 1/1/1952

Status: Active

End Date:

Description: The 291-S fan house is an above ground concrete structure with outside dimensions of 4.2 meters by 6 meters (14 feet by 20 feet) and contains the blowers for the REDOX main ventilation system.

TPA-MP-14, Rev. 2, Section 2.0 states that WIDS does not document buildings or facilities that do not contain TSD units. Therefore, this has been classified as Not Accepted. It further states that, after buildings are demolished, the footprint will be evaluated for potential soil contamination. If present, the soil contamination will be added to WIDS as a Discovery Site.

Location: The fan house is located adjacent to and southeast of the 291-S Stack.

Related Sites/Structures: The 291-S-1 Stack and sand filter are associated with the unit.

Waste Type: Equipment

Waste Description: The unit received exhaust air from the 202-S Process Building. The fans have very low levels of radiological contamination.

Code: 291-S-1

Classification: Not Accepted (Proposed)

Names: 291-S-1; 291-S-1 Stack; REDOX Process and Canyon Exhaust; 202-S Stack

Reclassification: None

Type: Stack

Start Date: 1/1/1952

Status: Active

End Date:

Description: The unit is a double-shell structure. The outer shell is made of reinforced concrete and the inner shell is constructed of acid-resistant brick and mortar.

Location: The stack is located northeast of the 202-S Building.

Release Description: During the operation of the REDOX Facility, multiple stack emissions occurred causing areas of surface contamination. Most of the emissions consisted of short lived radionuclides.

Related Sites/Structures: The sand filter and fan house are associated with the unit.

Waste Type: Process Effluent

Waste Description: The stack exhausts filtered air from the 202-S Process Building.

Code: 292-S	Classification: Accepted
Names: 292-S; 292-S Jet Pit House Building	Reclassification: Rejected (6/25/2014)
Type: Process Unit/Plant	Start Date: 1/1/1952
Status: Inactive	End Date: 1/1/1967

Description: The unit is a concrete building. The 292-S Jet Pit House was in service from 1952 to 1967 to provide housing for the jets for the Reduction Oxidation (REDOX) process vessel vent systems. It contains radioactively contaminated surface on the tanks and piping with in the building.

Location: The site is east of the 202-S Building.

Waste Type: Process Effluent

Waste Description: The unit contains radioactively contaminated surfaces on tanks, piping, and concrete (preliminary estimate is 4 curies beta).

Code: 293-S	Classification: Accepted
Names: 293-S; 293-S Off Gas Treatment; 293-S Off-Gas Treatment and Recovery; 293-S Offgas Treatment Facility	Reclassification: Rejected (6/25/2014)
Type: Process Unit/Plant	Start Date: 1/1/1958
Status: Inactive	End Date: 1/1/1967

Description: The 293-S Off Gas Treatment building is a reinforced concrete structure. It is internally contaminated.

Location: The site is located east of the 202-S Building.

Process Description: From 1958 through 1967 the building absorbed nitrogen oxides and volatile fission products from the REDOX dissolver gasses.

Waste Type: Process Effluent

Waste Description: This unit and structure are radioactively contaminated.

Code: 296-S-1	Classification: Accepted
Names: 296-S-1; 296-S-1 Stack	Reclassification: Consolidated (11/10/2004)
Type: Stack	Start Date: 1/1/1950
Status: Inactive	End Date: 1/1/1976

Description: The unit is constructed of metal, and it extends from grade level to 1.8 meters (6 feet) above the roof.

Location: The stack is attached to the outside south wall of the service portion of the south pipe gallery of 202-S.

Related Sites/ Structures: The stack is associated with the 202-S facility.

Waste Type: Process Effluent

Waste Description: The unit contains surface radioactive contamination, exact amount unknown (1,000 counts/minute beta/gamma direct). The unit discharged filtered air from the south sample gallery and sample hoods of 202-S.

This Site Was Consolidated With:

Code: 202-S

Names: 202-S; 202-S REDOX; S Plant

Code: 296-S-2

Classification: Accepted

Names: 296-S-2; 296-S-2 Stack; Hoods Ventilation and PR Cage; REDOX North Sample Gallery

Reclassification: Consolidated (11/10/2004)

Type: Stack

Start Date:

Status: Inactive

End Date:

Description: The unit is constructed of metal and extends from the sample gallery level to above the roof. The fan and motor are in place. The fan and base are on a contaminated surface.

Location: The stack is located on the outside north wall of the 202-S Building.

Related Sites/ Structures: The stack is associated with the 202-S building.

Process Description: This stack was constructed to exhaust filtered air from REDOX north and south sample galleries and hoods.

Waste Type: Process Effluent

Waste Description: The unit contains an unknown amount of surface radioactive contamination. The unit discharged filtered air from the north sample gallery and sample hoods of 202-S.

This Site Was Consolidated With:

Code: 202-S

Names: 202-S; 202-S REDOX; S Plant

Code: 296-S-4

Classification: Accepted

Names: 296-S-4; Low-Level Decontamination Sink and Special Work Permit Lobby Vent; REDOX Decontamination Room; Regulated Shop; Regulated Tool Room

Reclassification: Consolidated (11/10/2004)

Type: Stack

Start Date:

Status: Inactive

End Date:

Description: The unit is constructed of metal, and extends from grade level to 1.8 meters (6 feet) above the roof. The fan and motor are in place. The fan and stack base are in a surface contaminated area.

Location: The stack is located on the east outside wall of the 202-S building.

**Related Sites/
Structures:** The stack is associated with the 202-S building.

**Process
Description:** The unit discharged filtered air from the decontamination room and regulated shop and unfiltered air from the regulated tool room low-level decontamination sink and Special Work Permit (SWP) lobby.

Waste Type: Process Effluent

**Waste
Description:** The unit contains trace amounts of surface radioactive contamination. The unit discharged filtered air from the decontamination room and regulated shop and unfiltered air from the regulated tool room low-level decontamination sink and Special Work Permit (SWP) lobby.

This Site Was Consolidated With:

Code: 202-S

Names: 202-S; 202-S REDOX; S Plant

Code: 296-S-6

Classification: Accepted

Names: 296-S-6; 296-S-6 Stack; REDOX Silo Ventilation

Reclassification Consolidated (11/10/2004)

Type: Stack

Start Date:

Status: Inactive

End Date:

Description: The unit is constructed of metal, and it extends from the fan base in the feed tank area to 3.5 meters (11.5 feet) above the roof.

Location: The stack is located on the roof in the northeast corner of 202-S.

**Process
Description:** 296-S-6 was built to discharge unfiltered air from the silo gallery, organic feed tank and sample elevator.

Waste Type: Process Effluent

**Waste
Description:** The unit contains trace amounts of surface radioactive contamination. The unit discharged unfiltered air from the silo gallery, organic feed tank, and sample elevator.

This Site Was Consolidated With:

Code: 202-S

Names: 202-S; 202-S REDOX; S Plant

Code: 296-S-7

Classification: Not Accepted

Names: 296-S-7; 296-S-7 East and West Stacks; 296-S-7E; 296-S-7W; Dual Stacks; REDOX Product Building (233-S) Ventilation

Reclassification None

Type: Stack

Start Date:

Status: Inactive

End Date:

Description: The 233-SA building and stacks were demolished in 2004. The waste site consisted of two stacks, constructed of metal, extending from the fan base to above the 233-SA roof level. The units included a six meter (20 feet) intake duct and two electric drive fans. The systems were operated one at a time and were alternated weekly. The stacks were removed when the building was demolished.

Location: The stacks were located on the outside north wall of the 233-SA building.

Related Sites/ Structures: The stacks are associated with the 233-SA building and the 200-W-253 Contaminated Soil Footprint waste site.

Process Description: The stacks were constructed to exhaust filtered air from the 233-S Building, the REDOX plutonium processing greenhouse, the process vessel ventilation and load out area.

Waste Type: Process Effluent

Waste Description: The stacks contained an unknown amount of radioactive contamination. The units discharged air from 233-S.

Code: 296-S-12

Classification: Accepted

Names: 296-S-12; 296-S-12 Stacks

Reclassification: Consolidated (11/10/2004)

Type: Stack

Start Date:

Status: Inactive

End Date:

Description: There are two units, each 53 centimeters (21 inches) square and 3.2 meters (10.5 feet) high.

Location: The stacks are located on the roof of the 276-S Building, over the operating gallery.

Related Sites/ Structures: The stacks are associated with the 276-S building.

Waste Type: Process Effluent

Waste Description: The units received exhaust air from the 276-S Operating Gallery.

This Site Was Consolidated With:

Code: 276-S

Names: 276-S; 276-S Solvent Facility; 276-S Solvent Handling Facility

Code: 296-S-13

Classification: Accepted

Names: 296-S-13; 222-S Stack

Reclassification: None

Type: Stack

Start Date: 1/1/1951

Status: Inactive

End Date: 1/1/1978

Description: The stack originates on the second floor of 222-S and is approximately 2 meters (7 feet) in diameter by 16 meters (52 feet) tall.

Location: The stack is located in the southeast corner of the 222-S building roof.

Waste Type: Process Effluent

Waste Description:

Code: 296-S-16

Classification: Accepted

Names: 296-S-16; 219-S Stack

Reclassification: None

Type: Stack

Start Date: 1/1/1951

Status: Active

End Date:

Description: The stack is approximately 10 centimeters (4 inches) in diameter by 2.7 meters (7 feet) high.

Location: This stack is located on the west side of the 219-S Waste Handling Facility.

Process Description: Air is exhausted from the 219-S waste tanks through a de-mister (TK-105) and a single stage of High-Efficiency Particulate Air (HEPA) filtration prior to discharge through the stack to the atmosphere.

Waste Type: Process Effluent

Waste Description:

Code: 296-S-21 **Classification:** Accepted

Names: 296-S-21; 222-S Stack **Reclassification:** None

Type: Stack **Start Date:** 1/1/1978

Status: Active **End Date:**

Description: The stack is approximately 2 meters (6.5 feet) in diameter by 11.6 meters (38 feet) tall.

Location: The site is located on the southeast corner of the 222-S Laboratory roof.

Process Description: Air is exhausted from the 222-S Laboratory rooms, hoods, gloveboxes, and hot cells through the 222-SB or 222-SE Filter Buildings prior to discharge through the stack to the atmosphere.

Waste Type: Process Effluent

Waste Description:

Code: 2711-S **Classification:** Accepted

Names: 2711-S; 2711-S Stack Monitoring Building **Reclassification:** Rejected (6/25/2014)

Type: Process Unit/Plant **Start Date:** 1/1/1959

Status: Inactive **End Date:**

Description: The 2711-S Building is an isolated, inactive wooden structure. The structure is old and of questionable integrity.

Location: The building is adjacent to the 291-S Air Sampler and the 291-S-1 Stack.

Related Sites/Structures: The structures associated with this unit include the 291-S-1 Stack, the Gas Monitoring Building, and the 202-S Ventilation System.

Process Description: The building is currently used for equipment and lead shielding storage. The building contains a motor, pump, and instrumentation for the 291-S-1 Stack Sampling Building, and supports stack monitoring activities.

Waste Type: Equipment

Waste Description: The building may store lead shielding. According to WHC-SP-0331, Revision 1, this lead was scheduled for removal.

Waste Type: Equipment

Waste Description: The building stores office furniture and performance monitoring equipment which may be radiologically contaminated.

Code: 2718-S **Classification:** Accepted
Names: 2718-S; 2718-S Filter Monitoring Building; 2718-S Sand Filter Monitor; 2718-S Sand Filter Sampler **Reclassification:** Rejected (6/25/2014)
Type: Process Unit/Plant **Start Date:** 1/1/1952
Status: Active **End Date:**

Description: The 2718-S Building is an active wooden building in fair to poor condition. Portions of the building are of questionable integrity.

Location: The facility is located at the southwestern corner of the 291-S Sand Filter, east of the 202-S Building.

Related Sites/Structures: Structures associated with the building include the 291-S Sand Filter, the 202-S Ventilation System, and the rest of the 291-S Exhaust System.

Process Description: The building is currently used for equipment and lead storage. Previously, the building was used for storage and ventilation system (sand filter) performance monitoring.

Waste Type: Equipment

Waste Description: The building may store lead shielding. According to WHC-SP-0331, Revision 1, this lead was scheduled for removal.

Waste Type: Equipment

Waste Description: The building stores office furniture and performance monitoring equipment which may be radiologically contaminated.

Code: 2727-S **Classification:** Accepted
Names: 2727-S; 2727-S Nonradioactive Dangerous Waste Storage Facility; 2727-S NRDWS Facility **Reclassification:** Closed Out (6/27/1995)
Type: Storage **Start Date:** 1/1/1983
Status: Inactive **End Date:** 1/1/1995

Description: The 2727-S Nonradioactive Dangerous Waste Storage Facility (TSD unit) provided container storage for nonradioactive dangerous and extremely hazardous wastes generated in research and development laboratories, process operations, and maintenance and transportation functions through the Hanford Site. All waste containers have been removed from the facility and sent to an offsite RCRA Treatment, Storage, and/or Disposal (TSD) site. The metal building and its surrounding concrete pad have been demolished and removed in 1992. Some piles of dirt and asphalt rubble that appear to be left over from cleanup operations remain. The RCRA TSD permit was Closed Out in 1995.

Location: The 2727-S facility is located in the southeast portion of the 200 West Area, northeast of 202-S, south of U-Plant and west of Beloit Avenue.

Process Description: The facility stored waste from March 14, 1983 to December 30, 1986, but was considered an active waste site until the Treatment, Storage, and/or Disposal (TSD) unit was officially closed in 1995.

Waste Type:	Chemicals
Waste Description:	The unit was used for storage of nonradioactive dangerous and extremely hazardous wastes generated on the Hanford Site. The wastes consisted of listed wastes, wastes from nonspecific sources, characteristic wastes, and state-only wastes.
Waste Type:	Demolition and Inert Waste
Waste Description:	Piles of dirt and asphalt rubble that appear to be left over from cleanup operations still remain at the site.
Closure Info:	Final: In order to minimize closure costs related extensive sampling, it was decided to dispose of the structures and the first 15 centimeters (6 inches) of soil immediately beneath the structures as WT02, Washington State dangerous waste. Closure verification sampling consisted of sampling substructure soils that would remain after demolition and after the planned soil removal. Sampling was performed prior to site demolition to prevent disturbing the underlying soil. Samples B07531 through B07562 were taken in support of closure activities. A sketch showing sampling locations and tables showing sample results are available in WHC-SD-EN-TI-242, Rev. 0B.
	Demolition of the metal building and concrete storage pad began immediately upon the completion of sampling. The bulk of the demolition waste was taken to an offsite RCRA landfill in September 1992.
	The RCRA TSD was closed in 1995.

Code:	233-SA	Classification:	Not Accepted
Names:	233-SA; 233-SA Exhaust Filter Building	Reclassification	None
Type:	Process Unit/Plant	Start Date:	1/1/1967
Status:	Inactive	End Date:	
Description:	The above ground 233-S and 233-SA building structured were demolished in 2003 and 2004. A concrete cap was placed over the foundations. The area was then covered with gravel. A locked chain link fence surrounds the area. The fenced area is posted with Underground Radioactive Material Area signs.		
Location:	The 233-SA Building was located at the northwest corner of 233-S.		
Related Sites/Structures:	Structures associated with this system include the exhaust system, the 233 Building and 200-W-253.		
Process Description:	The building handled the ventilation for the 233-S Facility. It was a one-story reinforced concrete structure. The building housed two banks of double high-efficiency particulate air (HEPA) filters. Each filter bank has its own exhaust fan, stack, and monitoring instrumentation.		
Waste Type:	Chemicals		
Waste Description:	The system contained process equipment contaminated with plutonium and americium derived from 233-S Building operations.		

Code:	2904-SA	Classification:	Accepted
Names:	2904-SA; 2904-SA Cooling Water Sampler Building; 2904-SA Sample Building	Reclassification	Rejected (7/10/2014)
Type:	Process Unit/Plant	Start Date:	1/1/1956

Status: Inactive **End Date:** 1/1/1976

Description: The waste site has been reclassified to Rejected. TPA-MP-14, Rev. 2, Section 2.0 states that WIDS does not document buildings or facilities that do not contain TSD units. It further states that, after buildings are demolished, the footprint will be evaluated for potential soil contamination. If present, the soil contamination will be added to WIDS as a Discovery Site.

2904-SA Sample Building is a prefabricated metal structure resting on a concrete foundation. It is located over the southern portion of the 2904-S-170 Control Structure. Process equipment within the building includes a pump, a stainless steel tank (below grade), and a sample riser that extends through the floor of the building. The exterior of the building is posted with Contamination Area and Danger-Restricted Access signs.

Location: The building is located southwest of the 202-S canyon facility, near the southwest corner of the 211-S tank farm.

Related Sites/ Structures: The sample building is associated with the 2904-S-170 Weir and the process line connected to the weir.

Process Description: The sample shack was built to provide sampling of process waste from the REDOX facility prior to being routed through the 2904-S-170 Weir to liquid waste disposal sites. The building extends 0.97 meters (3 foot 2 inches) over the south end of the 2904-S-170 Weir.

Waste Type: Process Effluent

Waste Description: This unit contains trace amounts of low-level radioactive surface contamination derived from the process effluents sampled in this building.

Code: 222-SD **Classification:** Accepted

Names: 222-SD; 222 SD; 222-S DMWSA; 222-S TSD **Reclassification:** None
Dangerous and Mixed Waste Storage Area

Type: Storage **Start Date:** 6/1/1979

Status: Active **End Date:**

Description: The 222-S Dangerous Waste and Mixed Waste Storage Area (DMWSA) is a permitted treatment, Storage, and Disposal (TSD) area. It consists of two storage buildings (HS-0082 and HS-0083). The storage buildings are self-contained units with fire suppression and air conditioning, and are equipped with secondary containment. The site also includes portions of the concrete pad, which was previously used for the conex boxes in the DMWSA. The units and pad will be removed at closure under the Part B permit.

Location: The unit is located adjacent to the north of the 222-S Laboratory.

Related Sites/ Structures: Structures associated with this unit include the waste generating facilities in the 222-S Laboratory complex.

Process Description: The unit provides temporary storage for liquid and solid waste generated by the 222-S Laboratory complex. This waste includes dangerous and mixed waste.

Waste Type: Chemicals

Waste Description: Wastes generated from 222-S Analytical and 222-SA Standards Laboratories are stored in the unit. This consists of dangerous and mixed waste.

Code: 207-SL **Classification:** Accepted

Names: 207-SL; 207-SL Retention Basin; 222-S Retention Basin; REDOX Lab Retention Basin **Reclassification** None

Type: Retention Basin **Start Date:** 1/1/1952

Status: Active **End Date:**

Description: The site consists of a large below ground basin that is divided into two 94,625 liter (25,000 gallon) holding basins. The below ground basins are constructed of reinforced concrete walls 30 to 41 centimeters (12 to 16 inches) thick, and the floor is 38 centimeters (15 inches) thick. The unit also consists of three above ground 75,700 liter (20,000 gallon) holding tanks, added in 1994 to support the TEDF system.

Location: The site is located east of the 222-S Laboratory Buildings and west of Beloit Avenue.

Related Sites/ Structures: The basin is associated with the 216-S-19 Pond, the 216-S-26 crib and the TEDF system.

Process Description: The retention basin received low-level radioactive waste from the 222-S laboratory ventilation cooling water, laboratory hoods and sinks. Until 1984, the basin effluent was discharged to the 216-S-19 Pond. From 1984 to 1995 the effluent was discharged to the 216-S-26 crib. After 1995, non-radioactive, non-hazardous liquid effluents from the 222-S Laboratory, the 222-SA Laboratory, the 219-S Operating Gallery sump, and the package boiler unit, flow into the below ground basins for retention prior to transfer to the Treated Effluent Disposal Facility (TEDF). The effluents can be transferred to and from the below ground basins to the above ground holding tanks to provide additional extended storage before transfer.

Waste Type: Process Effluent

Waste Description: From 2/52 until 12/54, the site received low-level waste, including ventilation cooling water and miscellaneous wastes from laboratory hoods and sinks in the 222-S Laboratory. These were then discharged to the 216-S-19 Pond. From 12/54 to 10/55, the site was inactive (radioactivity levels of waste exceeded set limits). After 10/55, the site received nondangerous/nonradioactive waste. This unit discharged to the 216-S-19 Pond until 11/94, then was routed to the 216-S-26 Crib until 7/94, and since 7/94 discharges to the 200 Area TEDF.

Code: 241-SY-A **Classification:** Accepted

Names: 241-SY-A; 241-SY-A Diversion Box; 241-SY-A Valve Pit **Reclassification** None

Type: Valve Pit **Start Date:** 1/1/1977

Status: Active **End Date:**

Description: The 241-SY-A Valve Pit is fabricated from reinforced concrete. All concrete and ferrous materials are treated with a protective coating. This unit has two cover blocks with valve handles extending through penetrations in the cover blocks.

Location: This unit is located inside the 241-SY Tank Farm south of and between Tanks 241-SY-101 and 241-SY-102.

Related Sites/ Structures: The 241-SY Tank Farm is associated with this unit. Additional facilities associated with the 241-SY-A Valve Pit include the 244-S, 242-S, and 244-U Facilities.

Process Description: This unit is used to route waste solutions to and from the 241-SY Tank Farm.

Waste Type: Process Effluent

Waste Description: The unit transports waste solutions from processing and decontamination operations. Quantities are variable according to specific plant operations. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Code: 241-SY-B **Classification:** Accepted
Names: 241-SY-B; 241-SY-B Diversion Box; 241-SY-B Valve Pit **Reclassification:** None
Type: Valve Pit **Start Date:** 1/1/1977
Status: Active **End Date:**

Description: The 241-SY-B Valve Pit is fabricated from reinforced concrete. All concrete and ferrous materials are treated with a protective coating. This unit has two cover blocks with valve handles extending through penetrations in the cover blocks.

Location: This unit is located inside the 241-SY Tank Farm south of and between Tanks 241-SY-101 and 241-SY-102.

Related Sites/Structures: The 241-SY Tank Farm is associated with this unit. Additional facilities associated with the 241-SY-B Valve Pit include the 244-S, 242-S, and 244-U Facilities.

Process Description: This unit is used to route waste solutions to and from the 241-SY Tank Farm.

Waste Type: Process Effluent

Waste Description: The unit transports waste solutions from processing and decontamination operations. Quantities are variable according to specific plant operations. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Code: 241-SY-101 **Classification:** Accepted
Names: 241-SY-101; 241-SY-TK-101 **Reclassification:** None
Type: Double-Shell Tank **Start Date:** 1/1/1977
Status: Active **End Date:**

Description: This unit is fabricated as three concentric tanks. The primary tank and secondary tank are made of carbon steel with the secondary tank being larger in diameter than the primary tank. The space between the carbon steel tanks is referred to as the annulus. The third tank is a concrete shell that encloses both the primary and secondary tanks for additional containment, radiation shielding, and structural support. The 241-SY-101 Double Shell Tank is underground to provide shielding from radiation.

Location: The 241-SY-101 Double Shell Tank is located southeast of the 242-S Evaporator and within the 241-SY Tank Farm.

Related Sites/Structures: Structures associated with tank 241-SY-101 include the ventilation system, cover blocks on the access pits, and risers.

Process Description: This unit is used to store Tank Farms processing and operational waste.

Waste Type: Storage Tank

Waste Description: Waste transferred to this unit includes double-shell slurry, and radioactive mixed waste from tanks 241-SY-102, 241-SX-106, and 241-U-111.

Code: 241-SY-102 **Classification:** Accepted
Names: 241-SY-102; 241-SY-TK-102 **Reclassification:** None
Type: Double-Shell Tank **Start Date:** 1/1/1977
Status: Active **End Date:**

Description: This unit is fabricated as three concentric tanks. The primary tank and secondary tank are made of carbon steel with the secondary tank being larger in diameter than the primary tank. The space between the carbon steel tanks is referred to as the annulus. The third tank is a concrete shell that encloses both the primary and secondary tanks for additional containment, radiation shielding, and structural support. The 241-SY-102 Double Shell Tank is underground to provide shielding from radiation.

Location: The 241-SY-102 Double Shell Tank is located southeast of the 242-S Evaporator and within the 241-SY Tank Farm.

Related Sites/ Structures: Structures associated with tank 241-SY-102 include the ventilation system, cover blocks on the access pits, and risers.

Process Description: This unit is used to store tank farms processing and operational waste.

Waste Type: Storage Tank

Waste Description: The unit received supernatant containing partial neutralization feed, double-shell slurry feed, double-shell slurry, and noncomplexed wastes from 241-S, -SX, -TX, and -U Tank Farms. This tank is primarily used as an evaporator feed tank.

Code: 241-SY-103 **Classification:** Accepted
Names: 241-SY-103; 241-SY-TK-103 **Reclassification:** None
Type: Double-Shell Tank **Start Date:** 1/1/1977
Status: Active **End Date:**

Description: This unit is fabricated as three concentric tanks. The primary tank and secondary tank are made of carbon steel with the secondary tank being larger in diameter than the primary tank. The space between the carbon steel tanks is referred to as the annulus. The third tank is a concrete shell that encloses both the primary and secondary tanks for additional containment, radiation shielding, and structural support. The 241-SY-103 Double Shell Tank is underground to provide shielding from radiation.

Location: The 241-SY-103 Double Shell Tank is located southeast of the 242-S Evaporator and within the 241-SY Tank Farm.

Related Sites/ Structures: Structures associated with tank 241-SY-103 include the ventilation system, cover blocks on the access pits, and risers.

Process Description: This unit stores waste from the 241-S and -SY Tank Farms and from the 242-A Evaporator.

Waste Type: Storage Tank

Waste Description: The unit received supernatant containing complexed waste and double-shell slurry from 241-S and -SY tanks from the 242-A Evaporator.

Code: 221-T CSTF **Classification:** Accepted
Names: 221-T CSTF; 221-T Head End; T Plant Laboratory; 221-T Containment System Test Facility **Reclassification:** Closed Out (2/22/1999)
Type: Laboratory **Start Date:** 1/1/1964
Status: Inactive **End Date:**

Description: The 221-T CSTF consisted of the head end (Section 1) of the 221-T Canyon. In 1964, a sheet metal wall was constructed to separate Section 1 from the rest of the canyon. The head end area consists of one large process cell, a control room, laboratories, a shop, a change room, and a high bay near the cell.

Location: The 221-T CSTF is located at Section 1 of the 221-T Building.

Related Sites/Structures: Structures associated with the 221-T CSTF included the containment vessel, tanks, process equipment, laboratories, the 221-T Canyon, the 221-T Canyon and ventilation systems.

Process Description: Between 1964 and 1990, the 221-T Building head-end housed a series of testing programs. From 1964 to 1969 Pacific Northwest Laboratories used the facility to perform experiments with radioactive cobalt, cesium, and iodine. From 1976 to 1985, Westinghouse Hanford Company used the 221-T CSTF to perform liquid metal reactor safety tests using nonradioactive sodium, lithium, and sodium iodide. From 1985 to 1990 the unit was part of the light water reactor tests which were conducted with nonradioactive cesium, manganese, zinc, lithium sulfate, iodine, and hydrogen iodide. The unit was to be used as a research laboratory intended for use as an alkali metal waste treatment unit. It was anticipated alkali operations were to begin in 1977. The unit was also intended to treat dangerous alkali metal waste by heating the waste in a treatment tank equipped with an offgas system.

Waste Type: Chemicals

Waste Description: Wastes generated at the laboratory were intended to include alkali metal hydroxide, oxides, and carbonates. The maximum process design capacity for tank treatment was intended to be 100 liters (26.4 gallons) per day. The 221-T never managed dangerous waste. Previous use of the facility included experiments with radiological constituents. Residual contamination may be present.

Code: 221-T-5-6 **Classification:** Accepted
Names: 221-T-5-6; 221-T-TK-5-6; T Plant Complex; Tank 5-6 221-T System **Reclassification:** None
Type: Storage Tank **Start Date:** 1/1/1944
Status: Active **End Date:**

Description: Tank 221-T-5-6 is a type 347, stainless steel tank with piping connecting the unit to other tanks in the 221-T tank system. The tank is cylindrical in shape.

Location: The tank is located in cell 5L, in the northern third of the 221-T canyon.

Related Sites/Structures: Structures associated with tank 221-T-5-6 include transfer lines, cell 5L equipment, and the other tanks and sumps in the 221-T tank system.

Process Description: Tank 221-T-5-6 provides additional storage for tank 221-T-5-9. Liquid wastes are transferred to the tank for temporary holding from 221-T-5-9. The liquid wastes are eventually transferred back to 221-T-5-9 and subsequently to 221-T-15-1.

Waste Type: Process Effluent

Waste Description: The unit receives liquid mixed waste from T Plant (221-T, 2706-T) decontamination operations.

Code: 221-T-5-7 **Classification:** Accepted

Names: 221-T-5-7; 221-T-TK-5-7; T Plant Complex; Tank 5-7 221-T System **Reclassification:** None

Type: Storage Tank **Start Date:** 1/1/1944

Status: Active **End Date:**

Description: Tank 221-T-5-7 is a type 347 stainless steel tank with piping connecting the unit to other tanks in the 221-T tank system. The tank is rectangular with a flat bottom.

Location: The tank is located in cell 5R, in the northern third of the 221-T canyon.

Related Sites/Structures: Structures associated with tank 221-T-5-7 include transfer lines, cell 5R equipment, and the other tanks and sumps in the 221-T tank system.

Process Description: Tank 221-T-5-7 is the receiving point for liquid waste collected in the 610 millimeter (24 inch) liquid collection line which extends the length of the canyon building and receives drainage from all cells (except 5R) and the railroad tunnel. The tank also receives waste from the 211-T collection sump (by way of tank 221-T-6-1 overflow to the cell 6L drain) and drainage from the decontamination pad over cell 15L. Liquid waste are transferred from 221-T-5-7 to 221-T-5-9 via a steam jet. Sump 221-T-5-8 acts as secondary containment for this tank.

Waste Type: Process Effluent

Waste Description: The unit receives liquid mixed waste from T Plant (221-T, 2706-T) decontamination operations.

Code: 221-T-5-9 **Classification:** Accepted

Names: 221-T-5-9; 221-T-TK-5-9; T Plant Complex; Tank 5-9 221-T System **Reclassification:** None

Type: Storage Tank **Start Date:** 1/1/1944

Status: Active **End Date:**

Description: Tank 221-T-5-9 is a type 347 stainless steel tank with piping connecting the unit to other tanks in the 221-T tank system. The tank is cylindrical in shape.

Location: The tank is located in cell 5L, in the northern third of the 221-T canyon.

Related Sites/Structures: Structures associated with tank 221-T-5-9 include transfer lines, cell 5L equipment, and the other tanks and sumps in the 221-T tank system.

Process Description: Tank 221-T-5-9 receives waste from tank 221-T-5-6 and occasionally from tank 221-T-5-7. Liquid waste is transferred from 221-T-5-9 to 221-T-15-1 via steam jet.

Waste Type: Process Effluent

Waste Description: The unit receives liquid mixed waste from T Plant (221-T, 2706-T) decontamination operations.

Code: 221-T-6-1 **Classification:** Accepted

Names: 221-T-6-1; 221-T-TK-6-1; T Plant Complex; Tank 6-1 221-T System **Reclassification:** None

Type: Storage Tank **Start Date:** 1/1/1944

Status: Active **End Date:**

Description: Tank 221-T-6-1 is a type 347, stainless steel tank with piping connecting the unit to other tanks in the 221-T tank system. The tank is over shaped and is partially enclosed.

Location: The tank is located in cell 6L, in the northern third of the 221-T canyon.

Related Sites/Structures: Structures associated with tank 221-T-6-1 include transfer lines, cell 6L equipment, and the other tanks and sumps in the 221-T tank system.

Process Description: Tank 221-T-6-1 receives waste transferred from the 211-T collection sump. The tank overflows into containment sump 6-L (cell 6L) and gravity drains to tank 221-T-5-7 via the 221-T Building's common 610 millimeter (24 inch) liquid collection line.

Waste Type: Process Effluent

Waste Description: The unit receives liquid mixed waste from T Plant (221-T, 2706-T) decontamination operations.

Code: 221-T-11-R **Classification:** Accepted

Names: 221-T-11-R; 221-T-TK-11-R; T Plant Complex; Tank 11-R 221-T System **Reclassification:** None

Type: Storage Tank **Start Date:** 1/1/1944

Status: Active **End Date:**

Description: Tank 221-T-11-R is a type 347 stainless steel tank with piping connecting the unit to other tanks in the 221-T tank system. The tank is oval shaped with an open top and flat bottom.

Location: The tank is located in cell 11R, near the center of the long axis of the 221-T canyon.

Related Sites/Structures: Structures associated with tank 221-T-11-R include transfer lines, cell 11R equipment, and the other tanks and sumps in the 221-T tank system.

Process Description: Tank 221-T-11-R receives waste from decontamination operations over cell 11R. The wastes are transferred from 221-T-11-R to 221-T-15-1 via steam jet.

Waste Type: Process Effluent

Waste Description: The unit receives liquid mixed waste from T Plant decontamination operations.

Code: 221-T-15-1 **Classification:** Accepted

Names: 221-T-15-1; 221-T-TK-15-1; T Plant Complex; Tank 15-1 221-T System **Reclassification:** None

Type: Storage Tank **Start Date:** 1/1/1957

Status: Active **End Date:**

Description: Tank 221-T-15-1 is a type 347 stainless steel tank with piping connecting the unit to other tanks in the 221-T tank system. The tank has an open top, a flat bottom, and is oval in shape.

Location: The unit is located in cell 15R, in the southern third of the 221-T canyon building.

Related Sites/ Structures: Structures associated with Tank 221-T-15-1 include the 241-TX-154 Diversion Box, associated transfer lines, cell 15 equipment, the other 221-T Tanks, and the double-shell tank system.

Process Description: Tank 221-T-15-1 receives wastes transferred from Tanks 221-T-5-9 and 221-T-11-R, and liquid decontamination wastes generated on the cell 15R Decontamination Pad. This tank is the final tank in the 221-T Tank system before the waste is off loaded to railroad tank cars in the 221-T Railroad Tunnel. Nitrate addition or pH adjustment may also take place in this tank.

Waste Type: Process Effluent

Waste Description: The unit receives liquid mixed waste from T Plant (221-T, 2706-T) decontamination operations.

Code: 224-T **Classification:** Accepted

Names: 224-T; 224-T Canyon; Plutonium Concentration Facility **Reclassification:** None

Type: Process Unit/Plant **Start Date:** 1/1/1944

Status: Inactive **End Date:**

Description: Access to the building is restricted. The entrance portion of the building is enclosed in a locked, chain link fence. The east side of the building that coincides with the canyon cells has sealed doors marked A, B, C, D, E, and F. Each door is posted with Fissile Material, High Radiation, High Contamination and Airborne Contamination signs. Adjacent to the doors, Fixed Contamination signs are posted on painted portions of the concrete facility walls. Inside the building, the canyon portion of this building has been sealed off and is not accessible.

Location: This is a three story concrete building located southeast of 221-T and south of 222-T.

Release Description: In 1972, while modifications to the building were being made, plutonium contaminated soil was identified outside the building, presumably associated with a leaking process waste line (UPR-200-W-102).

Related Sites/ Structures: This portion of the 224-T building is associated with the Bismuth-Phosphate plutonium processing of nuclear fuel at 221-T from 1944 to 1956. The pipeline from 224-T to 216-T-3 reverse well is sitecode 200-W-226-PL.

Process Description: The building was originally constructed in 1943 as part of the T Plant bismuth-phosphate fuel processing complex. From 1944 to 1956 it functioned as the Plutonium Concentration Facility, concentrating the liquid output from the plutonium separations plant from 1,249 liters to 30 liters. The concentration took place in six radiologically contaminated process cells (Cells A, B, C, D, E, & F), located in the southeastern 1/3 of the 224-T building. The cells contained various tanks and piping. Cells A, B, D, and E contained a 40 inch centrifuge on a platform. Cell C is a pit that connects to the underground pipe tunnel from Sections 13 & 14 of 221-T. Cell F was "L" shaped and included an office and a glass enclosure where partial finished product was collected for transfer to 231-W. The contaminated process cell equipment was flushed when the process was terminated (1960's). The amount of radiological or regulated material remaining within the process cells and piping is unknown. The plutonium concentration process was identical to the concentration process done at 224-B in 200 East

Area. A thorough radiological characterization was done of the 224-B Hot Cells in 1985. An inventory of radioactive material remaining in the 224-B hot cells, based on average measurements, estimated 1.1 curies of cesium-137, 22 curies of strontium-90, 3.7 curies of cobalt-60, 5 curies of americium-241, 31 curies of plutonium-239 and 2 curies of other plutonium isotopes. This characterization is assumed to be similar to what may remain in the 224-T hot cells. The building was used as a plutonium liquid and scrap plutonium storage facility from 1975 to 1985. In 1985 the building was modified to house the Transuranic Assay Facility (TRUSAF) equipment. The TRUSAF Part A Permit states the contaminated canyon portion was sealed off from the rest of the building in 1975. During the 1960's and 1970's, the 224-T building was used to store solid and liquid plutonium-bearing material. The storage area was located on the second floor, in the pipe gallery. The southwest end of the first floor of 224-T consisted of the former G-Cell (never used) and the F-10 Hood Room. This area and the adjoining office was converted into an auxiliary measurement facility, equipped with instrumentation for measuring quantities of plutonium. There was also an enclosed equipment dismantling area that handled equipment for the recovery of plutonium residues. In 1985, a RCRA compliant storage unit Transuranic Waste Storage and Assay Facility was placed in 224-T and occupies 2/3 of the building and adjacent outdoor areas. This portion of the building is documented in WIDS Site code TRUSAF. This operation is currently on standby.

Waste Type: Sludge

Waste Description: In the 1940's, plutonium solutions were concentrated in the six cells in 224-T. In the 1950's, the tanks were drained and rinsed. In 2001, Non-destructive Assay analysis of nineteen tanks found less than 2 grams of fissile material inside the tanks, except for one that contained 4 grams of fissile material.

Code: 241-T-302	Classification: Accepted
Names: 241-T-302; 241-T-302 Catch Tank	Reclassification: Rejected (9/18/2002)
Type: Catch Tank	Start Date:
Status: Inactive	End Date:

Description: Although this tank has been listed in the Tri Party Agreement (appendix B), it has been verified that this tank does not exist.

Location: It has been verified this catch tank does not exist. Previous documents have described the tank location to be adjacent to the 241-T-152 Diversion Box, inside the 241-T Tank Farm fence. This has proved to be incorrect.

Code: 224-U CNT	Classification: Accepted
Names: 224-U CNT; 224-U Condensate Neutralization Tank; 224-U Process Condensate Neutralization Tank; 224-U-TK-C-5; Process Condensate Elementary Neutralization Unit; Tank TK-C-5	Reclassification: Rejected (11/17/2014)
Type: Neutralization Tank	Start Date: 1/1/1987
Status: Inactive	End Date: 1/1/1989

Description: The unit was part of a four tank system designed, located inside the 224-U building. The tank neutralized UO₃ Plant process condensate prior to disposal in the 216-U-17 Crib. Buildings 224-U, 224-UA and 203-UX were demolished in 2010. The neutralization tank was removed from the 224-U building and disposed in the ERDF landfill. DOE/RL-2011-04 documents the removal action activities.

Location: The tank was located along the north wall of cell C, inside the 224-U Building.

Related Sites/ Structures: Structures related to 224-U CNT include Phosphoric Acid Tank TK-C-8, Potassium Hydroxide Tank TK-X-36, Surge Tank TK-X-37, transfer lines, pumps, valves, instrumentation, and the 216-U-17 Crib. The demolished structure is associated with the 200-W-136 stabilized area.

Process Description: The process condensate stream is currently inactive. The 224-U Condensate Neutralization Tank is presently in a standby mode with the Uranium Trioxide (UO₃) Facility. During active facility operations, a predetermined dose of phosphoric acid was pumped from TK-C-8 to TK-C-5 every time condensate was pumped from TK-X-37 to TK-C-5. The agitator in TK-C-5 worked in conjunction with a recirculating pump loop to agitate the mixture. Potassium hydroxide from TK-X-36 was added to the recirculating loop under pH feedback control. When pH was within the specified limits, the recirculating loop discharged from the system. Process condensate was discharged to Crib 216-U-17 until 1989. Afterwards it was discharged to storage tanks at the Uranium Trioxide (UO₃) Plant.

Waste Type: Process Effluent

Waste Description: Under normal operating conditions, the process condensate is not designated as a dangerous waste. However, there is a potential for residual chemical or radiological contamination to be present in this neutralization system.

Code: 224-U HWSA **Classification:** Accepted

Names: 224-U HWSA; 224-U Hazardous Waste Storage Area **Reclassification:** Rejected (9/6/2000)

Type: Storage Pad (<90 day) **Start Date:** 1/1/1986

Status: Inactive **End Date:** 1/1/1995

Description: The unit consisted of a paved pad surrounded by a paved parking area on the northwest side of the 224-U Building. There is (April 12, 2000) no longer any evidence of the 90 Day Storage Pad in the area.

Location: The site was located on the northwest side of the 224-U Building.

Related Sites/ Structures: Structures associated with this unit included the 224-U Building and any containment units located at the pad.

Process Description: The hazardous waste staging area was used to store (stage) Uranium Trioxide (UO₃) and PUREX Plant related hazardous wastes prior to transport.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: Waste that was stored (staged) here included paints, solvents, and other hazardous wastes generated at the Uranium Trioxide (UO₃) Plant.

Code: 276-U **Classification:** Accepted

Names: 276-U; 276-U Solvent Facility; 276-U Solvent Handling Facility; 276-U Solvent Recovery Facility **Reclassification:** Rejected (6/25/2014)

Type: Process Unit/Plant **Start Date:** 1/1/1952

Status: Inactive **End Date:** 1/1/1957

Description: This is a DUPLICATE entry. 276-U is also documented as a subsite to 221-U; 221-U:3. The

276-U Solvent Recovery Facility is an aboveground concrete basin extending below grade. The unit is physically attached to the southern wall of the 221-U Canyon.

Location: The unit is directly attached to the southern wall of 221-U.

Related Sites/ Structures: Structures associated with the unit include the tanks and vacant tank pads, the 221-U Building, and the numerous access equipment and utilities related to the tanks.

Process Description: The building is currently isolated. Prior to retirement the building was used for the makeup and treatment of the organic solutions used in the 221-U Building.

Waste Type: Chemicals

Waste Description: Radiological contamination (fixed and smearable) is present on the structures and equipment. Residual chemical contamination may also be present.

Code: 296-U-10

Classification: Accepted

Names: 296-U-10; 296-U-10 Stack

Reclassification: Rejected (6/25/2014)

Type: Stack

Start Date:

Status: Inactive

End Date: 1/1/1976

Description: The exhaust stack is on the rooftop of the 271-U Building and is supported by the 221-U Building wall. The stack is constructed of carbon steel. It 0.6 meters (24 inches) in diameter and extends 3 meters (10 feet) above the roof. An electric motor and fan enclosure, associated with the stack, are also mounted on the rooftop, and rest on a 3 meter by 2.4 meter (9 foot 10 inch by 8 foot) metal foundation.

Location: The site is located on the roof of the 271-U Building.

Related Sites/ Structures: An electric motor and fan enclosure, also mounted on the rooftop and resting on a 3-meter (9.8-foot) by 2.4-meter (8-foot) wide metal foundation are associated to the unit.

Waste Type: Process Effluent

Waste Description: The unit consists of carbon steel with trace amounts of surface contamination.

Code: 200-W ADS

Classification: Accepted

Names: 200-W ADS; 200-W Ashpit Demolition Site

Reclassification: Closed Out (10/26/1995)

Type: Experiment/Test Site

Start Date: 1/1/1984

Status: Inactive

End Date: 1/1/1995

Description: The waste site RCRA Treatment, Storage, Disposal unit has been Closed Out. It is no longer marked or posted. Prior to 1995, the site had been marked with a nylon rope and a sign stating RCRA Waste Site - Do Not Disturb.

Location: The site was located inside the 200 West Area, southeast of the 200 West Area Powerhouse, on the east side of Beloit Ave. The activity occurred within the footprint of the 200 West Area Burn Pit. The documented coordinates were verified and place the site inside the open excavation currently known as the 200 West Burn Pit.

Related Sites/ Structures: The site is associated with the original 200-W ADB (200 West Area Ash Disposal Basin) footprint and the 200 West Burn Pit.

Process Description: The site was used for thermal treatment of discarded shock-sensitive or potentially explosive chemical wastes. Only two demolition events occurred at this site, one in November 1984 and the other in June 1986. The discarded chemicals were placed into a 0.3 meter (1 foot) hole. Two gallons of unleaded gasoline was added and the discarded chemicals were detonated in their original containers. The shock wave from the explosion and fire would have caused chemical residue to be dispersed over the area.

Waste Type: Chemicals

Waste Description: 1984 detonations: p-dioxane 3.4 kg (7.5 lb); tetrahydronaphthalene 3.76 kg (8.29 lb); tetrahydrofuran 9.08 kg (20.00 lb); benzene 9.47 kg (20.88 lb); diisopropyl benzene 6.06 kg (13.36 lb); bromobenzene 15.1 kg (33.3 lb); 1,4-dioxane 757 g (1.67 lb); polyethylene glycol monoethyl ether 757 g (1.67 lb); 1,2-bis(2-chlorethoxy)ethane 3.02 kg (6.66 lb); dioxane 567 g (1.25 lb); 2-butoxyethanol 3.02 kg (6.66 lb). 1985 detonations: none. 1986 detonations: tetrahydrofuran 6.1 kg (13.4 lb); triethylborane 500 g (1.1 lb); lithium hydride 230 g (0.51 lb); acrolein 400 g (0.88 lb); hydrazine 1 kg (2.2 lb); aluminum chloride 450 g (1.0 lb); unsymmetrical dimethyl hydrazine 10 g (0.02 lb); p-nitrobenzoyl chloride 100 g (0.22 lb); sodium peroxide 340 g (0.75 lb); benzene/butyl lithium solution 900 g (2.0 lb); hexane/benzene/butyl lithium/tetrahydrofuran 1 kg (2.2 lb); chromium metal powder 454 g (1.0 lb); toluene/ ether/benzene/ethylacetate 4 kg (8.8 lb); heptane/diethyl ether 4 kg (8.8 lb); ethyl ether/allyl magnesium bromide 1 kg (2.2 lb); benzene/ethyl acetate/ tetrahydrofuran/ether/toluene/ hydrogen sulfide/methanol 4 kg (8.8 lb); ethyl ether 29.7 kg (65.5 lb); picric acid 460 g (1.01 lb); isopropyl ether 1 kg (2.2 lb); butoxyethanol 946 g (2.1 lb); butyl cellosolve 89 g (0.2 lb); carbon trichloride 445 g (0.98 lb); butyl ethanol 9.46 kg (20.9 lb); phenylether 235 g (0.52 lb).

Closure Info: Final: The TSD unit was Clean Closed in accordance with the Washington Administrative Code (WAC) closure performance standards. The letter of acceptance from the Department of Ecology was received 10/26/1995. Soil samples were collected and analyzed to show the absence of chemicals in the soil.

Code: 200-W CSLA	Classification: Accepted
Names: 200-W CSLA; Construction Surface Laydown Area; Non-Rad Burial Ground; 200-W Construction Surface Laydown Area	Reclassification: Rejected (1/19/2000)
Type: Dumping Area	Start Date: 1/1/1945
Status: Inactive	End Date: 1/1/1950

Description: The site is an old construction laydown area. The laydown area is not marked. The 216-U-17 Crib is located at the northwest corner of this location. A 1997 site visit also noted the 200-UP-1 Groundwater Pump and Treat facility in the northwest portion of this location. There was evidence of scattered miscellaneous debris on the surface of the vacant area south and east of the 216-U-17 crib. In 1997, construction of the new Cross-Site Transfer Line was occurring nearby.

Location: The site is located near the southeast corner of the 16th street and Beloit Avenue intersection, inside 200 West Area.

Related Sites/ Structures: The area is associated with 200-W-71.

Process Description: A copy of a historical photograph from an unidentified document was found that shows the construction laydown area being actively used. There is a large temporary hut and several smaller temporary structures and material located at the site. It is assumed to have been taken

in the early 1950's, when U Plant was being renovated to begin the Uranium Metal Recovery mission. The U-Plant Technical Baseline Report states the area was a "pit" where trucks were driven to dump material. No drawings have been found that identify a pit at this location, although an open trench is visible on a 1948 aerial photograph, east of where the 216-U-17 crib is currently located. The trench has been given WIDS sitecode 200-W-71. A meeting with HL Maxfield and RP Knight in 1987 prior to the construction of the 216-U-17 Crib confirmed the area had been used as a laydown area to support construction activities at U-Plant. That explained the large amount of surface debris in the area. The debris located over the new crib site was bladed off during construction.

Waste Type: Misc. Trash and Debris

Waste Description: This site was used to dispose of unusable valves, piping, and other plumbing materials. Angle iron, crushed cans and drums, rusty wire and metal frames were noted on the surface in 1997.

Code: 200-W PAP	Classification: Accepted
Names: 200-W PAP; 200-W Powerhouse Ash Pit	Reclassification: Rejected (5/21/2008)
Type: Coal Ash Pit	Start Date: 1/1/1943
Status: Inactive	End Date: 1/1/1995

Description: The pit is a rectangular, open hole, approximately 7.6 meters (25 feet) deep. In February 2000, the site was empty and dry. As of April, 2000, the unit is a deep pit with steep sloped sides. It is surrounded with a light chain and posted with "Danger-Open Pit" signs. A layer of ash remains on the floor of the pit.

Location: The pit is located south of the 284-W Powerhouse, west of Beloit Ave. and north of 19th Street.

Related Sites/ Structures: The pit is associated with the 284-W Powerhouse and the 200-W Ash Disposal Basin.

Process Description: When supporting the powerhouse operation, the pit was filled with an ash slurry that was sluiced through two underground pipes that emerge from the north side of the pit. Periodically, when the pit became too full, ash was dredged from the pit and moved to the Ash Disposal Basin located on the east side of Beloit Ave.

Waste Type: Ash

Waste Description: A waste determination of the Hanford Site 200 Area steam plant ash was performed in the early 1990s. The waste stream was determined to be nondangerous. Samples were analyzed using the TCLP (Toxicity Characteristic Leaching Procedure), and all were below the regulatory limits. Eleven sample results were also reported for pH: the results ranged from 7.66 to 11.91, with an average of 9.27. The second and third highest pH results were 10.09 and 9.94. The rate of ash generation was approximately 8,890 cubic yards per year. The pit held approximately 57,290 cubic yards of ash.

Code: 200-W PP	Classification: Accepted
Names: 200-W PP; 284-W-B; 200 West Powerhouse Ponds; 200-W Powerhouse Pond	Reclassification: Consolidated (4/20/2000)
Type: Pond	Start Date: 1/1/1984
Status: Inactive	End Date: 1/1/1995

Description: The unit consists of two elongated basins. Drawing H-2-94251 identifies the north basin as a settling pond and the south basin as a seepage pond. The sides and bottom are covered with

cobbles. The head wall and the spillway between the basins are made of concrete. The basins were placed on top of the original head end of the 216-U-14 ditch. This site has been consolidated with the 216-U-14 Ditch.

Location: The unit is located inside 200 West Area, west of the 284-W Powerhouse.

Related Sites/ Structures: The basins are associated with pipeline 200-W-102-PL, 216-U-14 ditch, 284-W Powerhouse, 283-W Water Filter Plant, and 282-W Water Reservoir.

Process Description: Prior to the construction of the Powerhouse Pond, the head end of the 216-U-14 Ditch occupied this location. The Powerhouse Pond was constructed over a portion of the 216-U-14 Ditch when the ditch was deactivated and stabilized. The Powerhouse Pond received effluent from the 284-W Powerhouse, the 283-W Water Filter Plant and the 282-W Water Reservoir from August 1984 until June 1995. In June 1995, the 284-W Powerhouse was shut down and the effluent from the filter plant and reservoir was routed to the 200 Area Treated Effluent Disposal Facility.

Waste Type: Water

Waste Description: The unit received wastes from steam production and water treatment activities from the 284-W Powerhouse. The major components of the powerhouse effluent included quench water for the boiler, basin flush water, softener backflush from the filter systems, and boiler blowdown. Approximately 23.8 million liters per month (6.29 million gallons per month) of liquid waste was discharged to this unit.

This Site Was Consolidated With:

Code: 216-U-14

Names: 216-U-14; 216-U-14 Ditch; Laundry Ditch

Code: 200-W-4

Classification: Accepted

Names: 200-W-4; U-Farm Landfill

Reclassification: Rejected (5/13/2008)

Type: Burial Ground

Start Date: 1/1/1992

Status: Inactive

End Date:

Description: The site was a small excavation containing a yellow paint-like substance. The area is not marked and is no longer visible from the surface.

Location: The unit is located outside the south fence of 241-U Tank Farm, near the corner of 16th Street and Camden Avenue.

Waste Type: Chemicals

Waste Description: The unit waste includes lead, chromium and cadmium. It was assumed to be dried, yellow paint.

Code: 200-W-5

Classification: Accepted

Names: 200-W-5; Burial Ground/Burning Pit; U Plant Burning Pit; UPR-200-W-8

Reclassification: Consolidated (5/6/2004)

Type: Burial Ground

Start Date:

Status: Inactive

End Date:

Description: DUPLICATE entry.

Location: The unit is east of 221-U Building.

Waste Type: Misc. Trash and Debris

Waste Description: The waste includes contaminated coveralls and soil.

This Site Was Consolidated With:

Code: UPR-200-W-8

Names: UPR-200-W-8; 200-W-5; Old Burial/Burning Pit; UN-200-W-8; U-Plant Burning Pit/Burial Ground

Code: 200-W-10

Classification: Accepted

Names: 200-W-10; Grout Wall Test; Item 10 (RCRA General Inspection); Lysimeter Test Site near 201-W

Reclassification: Rejected (5/13/2008)

Type: Depression/Pit (nonspecific)

Start Date: 1/1/1976

Status: Inactive

End Date: 1/1/1977

Description: The 1995 inspection team observed a pit covered at grade with wood planking. It was surrounded by orange plastic fencing on steel posts marked with two signs, one Danger Keep Away and the other stating Controlled Area. Adjacent to orange fenced area were 5 centimeters (2 inch) diameter metal pipes, protruding vertically above grade at heights ranging from 0.45 to 1.05 meters (18 inches to 3 1/2 feet). Debris (consisting of wire, metal and wood) was present.

Location: The site is located inside 200 West Area, southeast of 221-U. It is north of 13th Street, approximately 200 feet north of the 201-W building. The site is west of the dirt road.

Waste Type: Chemicals

Waste Description: The grout consisted of 11,578 L (3059 gal) sodium silicate, 2,467 L (652 gal) formamide, and 20.2 kg (44.5 lb) calcium chloride.

Code: 200-W-17

Classification: Accepted

Names: 200-W-17; S Plant Project W-087 Aluminum Silicate Discovery

Reclassification: Rejected (5/6/2004)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The pipe trench where white aluminum silicate was found has been back-filled to grade. A single, unmarked, steel post indicates the location of the excavation. No signs are attached to the post. There is no visual evidence of aluminum silicate on the surface.

Location: The site is located in the 200 West Area, southwest of REDOX. The site is 120 meters (394 feet) north of 10th Street, along the dirt road that runs outside the REDOX exclusion area fence line.

Release Description: On July 17, 1995, while digging a new pipeline (project 200 W-087), a band of white material was found in the trench excavation. A sample was collected and analyzed. The source of the aluminum silicate is likely to be the same as WIDS site 200-W-1 Mud Pit.

Related Sites/Structures: Associated structures include 200-W-1 and the 200 W-087 pipe line project.

Waste Type: Chemical Release

Waste Description: The waste associated with this site was aluminum silicate. The aluminum silicate is probably from drilling mud.

Code: 200-W-18 **Classification:** Accepted
Names: 200-W-18; S Plant Project W-087 Aluminum Oxide Discovery **Reclassification:** Rejected (5/6/2004)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The pipe trench where the aluminum oxide was found has been backfilled with soil. A single, unmarked, steel post marks the location of the excavation. There is no visual evidence of aluminum oxide on the surface.

Location: The site is located west of 202-S (REDOX), on the west side of the dirt road running outside the REDOX exclusion area fence.

Release Description: On July 17, 1995, while digging a new pipe trench for Project 200 W-087, a layer of white material was seen in a pipeline excavation. It was found approximately 0.3 meters (one foot) below ground surface and was approximately 3 inches thick. The source of the aluminum oxide at this site is likely the 200-W-1 Mud Pit.

Related Sites/Structures: The associated structures include 200-W-1 and the 200 W-087 pipe line.

Waste Type: Abandoned Chemicals

Waste Description: The sample results collected from this site showed the material was aluminum oxide and calcium. The aluminum oxide is probably from drilling mud.

Code: 200-W-19 **Classification:** Not Accepted
Names: 200-W-19; Steam Line Asbestos Release **Reclassification:** None
Type: Unplanned Release **Start Date:** 1/1/1995
Status: Inactive **End Date:**

Description: The site is not marked or posted. It is under a lawn between the M0039 building and a sidewalk. The site is where asbestos covering a clean steam line was knocked to the ground and cleaned up by the next day.

Location: The release site is located approximately 37 meters (40 yards) west of the 2704S building.

Release Description: On August 30, 1995, a backhoe driver was driving under an aboveground steam line when his backhoe hydraulic arm struck the steam line. An area approximate 2 to 3 feet (0.6 to 0.9 m) in length, along the 10 inch (25 cm) line, was affected. This allowed a release of approximately 1180 cubic centimeters (72 cubic inches) of asbestos to the ground below.

Waste Type: Asbestos (friable)

Waste Description:

Code: 200-W-20 **Classification:** Accepted
Names: 200-W-20; T Plant Complex **Reclassification:** None

Type: Process Unit/Plant **Start Date:** 1/1/1944

Status: Active **End Date:**

Description: The T Plant Complex is enclosed within a 2.4 meter (8 foot) chain link fence. Facilities within the fence include the 221-T Canyon Building, the 2706-T Decontamination Facility, the 211-T Sump, the 214-T Storage Building, the 277-T Storage Building, the 2715-T Material Storage Building, the 291-T Ventilation Stack Complex and several small support buildings. The T Plant Complex is considered a RCRA Treatment and Storage Unit.

Location: The T Plant Complex is located inside the 200 West Area near the corner of Beloit Ave. and 23rd Street.

Release Description: Over time, several documented unplanned releases have occurred within the area now defined as the T Plant Complex. HAN-62372 DEL documents that a valving error released 2350 gallons of phosphoric acid to the ground in the 211-T area in November 1955.

Process Description: Currently, the T Plant Complex is a treatment and storage unit for dangerous and mixed waste. The primary mission of the facility is to decontaminate equipment and debris. Equipment is often decontaminated and repaired prior to being returned to service on the Hanford site. Additional activities include identification, verification, sampling, treatment and repackaging of dangerous and mixed waste and decontamination technology demonstrations. Within the T Plant complex, dangerous and/or mixed waste decontamination and treatment activities occur in the 221-T canyon, the 221-T railroad tunnel, the 2706-T building and support facilities incorporating various technologies to remove mixed waste contamination. Liquid waste generated from the decontamination process is collected and transferred to the 2706-T tank system or the 221-T tank system. From these tank systems, the waste is transferred to a treatment, storage/disposal unit capable of accepting this waste. Treatment of dry and liquid waste may include sorting, repackaging, neutralization, absorption and compaction. The 221-T Canyon Building was originally constructed in 1944 to separate plutonium from irradiated fuel rods using the bismuth phosphate process. It continued to be used for that purpose until 1956. It is constructed of reinforced concrete divided into twenty sections, three galleries and a railroad access tunnel. In 1957, T Plant became a decontamination facility. Activities include repair of large equipment and decontamination techniques including high pressure washing, vibratory polishing, acid baths and sand blasting. Some failed equipment is being stored on the canyon deck and in the canyon cells. The 2706-T building is constructed of prefabricated steel. It is used to decontaminate equipment and vehicles. The building contains two pits (the railroad pit and the automotive pit) over which the vehicle decontamination is performed. Liquid mixed waste from 2706-T decontamination activities is stored in the railroad pit sump that has a 23,000 liter (6,100 gallon) capacity. The liquid is transferred via underground piping to the 211-T collection sump and the to the 221-T tank system. The liquid is automatically transferred out of the 211-T sump when a designated level is reached. The 214-T Building is constructed of corrugated steel. It is used to store containerized chemicals and dangerous/mixed waste in segregated areas. The floor is sloped to prevent the mixing of incompatible chemicals. The sloped floors direct spills to separate floor sumps.

Waste Type: Process Effluent

Waste Description: The waste consists of dangerous, hazardous and mixed waste from decontamination and treatment activities occurring in the T Plant Complex.

Code: 200-W-23 **Classification:** Not Accepted

Names: 200-W-23; 203-S and 205-S Underground Contaminated Zone **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive**End Date:****Description:** This site has been rejected as a duplicate of 200-W-22 (203-S/204-S/205-S Stabilized Area). Also see WIDS Site 203-S & 205-S for demolished facility information. These structures are contaminated facility components that remain below grade within an Underground Radioactive Material Area.**This Site Was Consolidated With:****Code:** 200-W-22**Names:** 200-W-22; 203-S/204-S/205-S Stabilized Area

Code: 200-W-24**Classification:** Not Accepted**Names:** 200-W-24; 216-S-10 Borrow Pit; S-10 Pond
Borrow Area**Reclassification:** None**Type:** Depression/Pit (nonspecific)**Start Date:** 1/1/1984**Status:** Inactive**End Date:****Description:** The site is an unmarked, large, scraped sandy area near the southwest corner of 200 West Area. Its surface is mostly level with the surrounding area, except for a cut-away hill on the west edge of the borrow pit. The site has mostly revegetated with crested wheatgrass.**Location:** The borrow area is located immediately south of the 200 West Area, just outside of the perimeter fence.**Related Sites/
Structures:** The borrow pit is associated with the 216-S-10 Pond.**Process
Description:** Clean backfill material was taken from this area in 1984 during the 216-S-10 stabilization activities. No waste has been deposited in this area.

Code: 200-W-25**Classification:** Not Accepted**Names:** 200-W-25; 216-S-16 Borrow Pit**Reclassification:** None**Type:** Depression/Pit (nonspecific)**Start Date:** 1/1/1984**Status:** Inactive**End Date:****Description:** The site is a shallow, scraped area that forms a semi-circle around the north and west edges of the stabilized 216-S-16 Pond. The site is mostly revegetated with crested wheatgrass and large patches of native plants.**Location:** The borrow pit is located southwest of 200 West Area, outside the perimeter fence.**Related Sites/
Structures:** This borrow pit is associated with the 216-S-16 Pond.**Process
Description:** Clean backfill material was taken from this area to backfill and stabilize the 216-S-16 Pond. No waste has been placed in this area.

Code: 200-W-26**Classification:** Not Accepted**Names:** 200-W-26; 216-S-17 Borrow Pit**Reclassification:** None**Type:** Depression/Pit (nonspecific)**Start Date:** 1/1/1984

Status: Inactive

End Date:

Description: The site is an unmarked shallow scraped area located south of the stabilized 216-S-17 Pond. It is slowly revegetating.

Location: The borrow pit is located outside the south perimeter fence of the 200 West Area. It is south of the southern boundary of the stabilized 216-S-17 Pond.

Related Sites/ Structures: The borrow pit is associated with the 216-S-17 Pond.

Process Description: Clean backfill material was taken from this area to backfill and stabilize the 216-S-17 Pond. No waste was placed in this area.

Code: 200-W-27

Classification: Not Accepted

Names: 200-W-27; 216-S-19 Borrow Pit

Reclassification: None

Type: Depression/Pit (nonspecific)

Start Date: 1/1/1984

Status: Inactive

End Date:

Description: The site is a shallow, scraped area south of the stabilized 216-S-19 Pond. The site has been revegetated with crested wheatgrass, and now resembles the stabilized pond (the area of the former pond is delineated with concrete posts).

Location: The site is located south of 10th Street, outside the south perimeter fence of the 200 West Area.

Related Sites/ Structures: This borrow pit is associated with the 216-S-19 Pond.

Process Description: Clean backfill material was taken from this site to backfill and stabilize the 216-S-19 Pond. No waste was deposited at this site.

Code: 200-W-28

Classification: Not Accepted

Names: 200-W-28; 216-U-10 Borrow Pit; U Pond Borrow Area

Reclassification: None

Type: Depression/Pit (nonspecific)

Start Date: 1/1/1985

Status: Inactive

End Date:

Description: The 216-U-10 Borrow Pit is a large shallow, scarred sandy area adjacent to the north side of the backfilled 216-U-10 Pond. It is sparsely vegetated with crested wheatgrass.

Location: The borrow area is located south of 16th Street, east of Dayton Avenue and north of the 216-U-10 Pond.

Related Sites/ Structures: This borrow pit provided fill for the 216-U-10 Pond.

Process Description: Backfill material was taken from this area in 1985 for 216-U-10 Pond stabilization activities. No waste has been placed in the borrow area.

Code: 200-W-29

Classification: Not Accepted

Names: 200-W-29; 216-U-11 Borrow Pit

Reclassification: None

Type: Depression/Pit (nonspecific) **Start Date:** 1/1/1985
Status: Inactive **End Date:**

Description: The site is a large shallow, scraped area south of the stabilized 216-U-11 Ditches. The area has very little vegetation.

Location: The site is located south of the 216-U-11 Ditches, outside the west perimeter fence of 200 West Area.

Related Sites/ Structures: The borrow pit is associated with the 216-U-11 Ditch and 216-U-10 Pond.

Process Description: Clean backfill material was taken from this area in 1985 during the stabilization of the 216-U-10 Pond and the 216-U-11 Ditch. No waste has been placed in the borrow pit.

Code: 200-W-30 **Classification:** Not Accepted
Names: 200-W-30; 218-W-1A Borrow Pit **Reclassification:** None
Type: Depression/Pit (nonspecific) **Start Date:** 1/1/1983
Status: Inactive **End Date:**

Description: The site is a shallow, scraped area adjacent to the east side of the area designated as the 218-W-6 Burial Ground. The area has been revegetated with grasses. The borrow pit is not marked or posted.

Location: The site is located northeast of the 218-W-1A Burial Ground and adjacent to the east boundary of the 218-W-6 Burial Ground.

Related Sites/ Structures: The borrow pit is associated with the surface stabilization of the 218-W-1A Burial Ground.

Process Description: Clean backfill material was taken from the 200-W-30 Borrow Pit in 1983 to stabilize the surface of the 218-W-1A Burial Ground. No waste was placed in the borrow pit.

Code: 200-W-31 **Classification:** Not Accepted
Names: 200-W-31; 218-W-2A Borrow Pit **Reclassification:** None
Type: Depression/Pit (nonspecific) **Start Date:** 1/1/1980
Status: Inactive **End Date:**

Description: The area that was used for backfill material for the 218-W-2A stabilization is currently underneath the southern portion of the 218-W-5 Burial Ground. The borrow pit is no longer visible.

Location: The site was located west of Dayton Avenue and north of 23rd Street, west of the 218-W-3 Burial Ground.

Related Sites/ Structures: This borrow pit was associated with the 218-W-2A Burial Ground.

Process Description: Clean backfill material was removed from this borrow pit in 1980 and used to stabilize the surface of the 218-W-2A Burial Ground.

Code: 200-W-32 **Classification:** Not Accepted
Names: 200-W-32; 216-Z-19 Borrow Pit **Reclassification:** None
Type: Depression/Pit (nonspecific) **Start Date:**
Status: Inactive **End Date:**

Description: The soil disturbance is no longer visible.
Location: The borrow pit was located north of 16th Street, west of the 216-Z-20 Crib. The soil was taken from an area in the eastern part of the 218-W-4C Burial Ground. The exact location cannot be defined.
Process Description: Clean backfill material was taken from this area and used to stabilize the surface of the 216-Z-19 Ditch. No waste was placed in the borrow pit.

Code: 200-W-34 **Classification:** Not Accepted
Names: 200-W-34; 2607-WL; 272-WA Septic System **Reclassification:** None
North of 213W; Duplicate of 2607-WL
Type: Septic Tank **Start Date:**
Status: Inactive **End Date:**

Description: This site is a duplicate of 2607-WL, which is also listed in WIDS as servicing the 272-WA Building and being north of that facility.
Related Sites/Structures: The 2607-WL septic system services the 272-WA Building. The 200-W-34 septic system was entered into WIDS, but is a duplicate of 2607-WL septic system.
Waste Type: Sanitary Sewage
Waste Description:

Code: 200-W-35 **Classification:** Accepted
Names: 200-W-35; 200-W-35-A Infiltration Test Site; **Reclassification:** Rejected (5/13/2008)
200-W-35-B Bentonite Slurry Test Site; 200-W-35-C Buried Garbage Can with Lid; Lysimeter Test Site; Various Sites North of 201-W
Type: Dumping Area **Start Date:** 1/1/1970
Status: Inactive **End Date:**

Description: During the late 1970's and early 1980's, the area north of 13th Street and west of Albany Ave. was used for testing various technology development studies. A 1995 Site Investigation visually identified a shallow excavated area, a pit covered with plywood, and a vertically buried garbage can with the lid at ground surface level. The sites are no longer visible because they were backfilled in 1997. They are not marked or posted.
Location: The sites are located inside the 200 West Area, in an empty field north of 13th Street and west of Albany Avenue. Access is via a dirt road north of the 201-W Fence.
Related Sites/Structures: This site is associated with information contained in Subsite section of 200-W-35, 200-W-12 and 200-W-10.

Process Description: During the 1970's, the Atlantic Richfield (ARCO) and Rockwell Research Departments used this area for testing equipment and processes to support the waste management operations. This area was selected for testing because it was adjacent to the REDOX facility, where the Research Department offices were located, and because the area did not contain any contaminated facilities or vadose contamination.

Waste Type: Equipment

Waste Description: No hazardous or radiological material was used in any of the tests.

This Site has the Following SubSites:

Code: 200-W-35:1

Names: 200-W-35:1; 200-W-35-A Infiltration Test Site

Code: 200-W-35:2

Names: 200-W-35:2; 200-W-35-B; Bentonite Slurry Test Site

Code: 200-W-35:3

Names: 200-W-35:3; 200-W-35-C; Buried Garbage Can with Lid

Code: 200-W-35:1

Classification: Accepted

Names: 200-W-35:1; 200-W-35-A Infiltration Test Site

Reclassification: Rejected (5/13/2008)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site is a shallow excavation located east of the dirt road north of 201-W. It is approximately 10 by 20 meters (30 by 60 feet). A site visit in 1995 identified some aluminum pipes laying around the area. W.H. Price states that the site was used as an Infiltration Test Site to determine the infiltration capacity of new cribs prior to their construction.

The SubSite is Part Of:

Code: 200-W-35

Names: 200-W-35; 200-W-35-A Infiltration Test Site; 200-W-35-B Bentonite Slurry Test Site; 200-W-35-C Buried Garbage Can with Lid; Lysimeter Test Site; Various Sites North of 201-W

Code: 200-W-35:2

Classification: Accepted

Names: 200-W-35:2; 200-W-35-B; Bentonite Slurry Test Site

Reclassification: Rejected (5/13/2008)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The Bentonite Slurry Test Site is located on the east side of the dirt road north of 201-W about half way between 201-W and the end of the road. It is a pit covered with a plywood cover and a circular hole cut in the plywood. W.H. Price states the site was used to develop a tool to sample the 361-Z Tank. Three drums were welded together and filled with a thick bentonite slurry and food coloring to simulate the contents of the 361-Z Tank. The test principal investigator (C.T. Webster) stated that no hazardous or radioactive materials were used in the test. This pit was backfilled with clean dirt on June 20, 1997.

The SubSite is Part Of:

Code: 200-W-35
Names: 200-W-35; 200-W-35-A Infiltration Test Site; 200-W-35-B Bentonite Slurry Test Site; 200-W-35-C Buried Garbage Can with Lid; Lysimeter Test Site; Various Sites North of 201-W

Code: 200-W-35:3 **Classification:** Accepted
Names: 200-W-35:3; 200-W-35-C; Buried Garbage Can with Lid **Reclassification** Rejected (5/13/2008)
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The buried garbage can is located east of the dirt road north of 210-W and west of the Bentonite Slurry Test Pit. It was not marked or posted. Conversations with W.H. Price, Ray Giddings and Steve Phillips did not reveal any information about its use. The Garbage Can was backfilled with clean dirt on June 20, 1997.

The SubSite is Part Of:

Code: 200-W-35
Names: 200-W-35; 200-W-35-A Infiltration Test Site; 200-W-35-B Bentonite Slurry Test Site; 200-W-35-C Buried Garbage Can with Lid; Lysimeter Test Site; Various Sites North of 201-W

Code: 200-W-36 **Classification:** Accepted
Names: 200-W-36; Above Ground Storage Tank; EP 211-143; TK-SQ-143 **Reclassification** None
Type: Storage Tank **Start Date:**
Status: Inactive **End Date:** 1/1/1969

Description: The site is a single aboveground, horizontal tank on three concrete saddles. In April 2014, the tank was posted with "Caution - Radioactive Material - Internally Contaminated" signs that are attached to the sides of the tank.

Location: The tank is in the 211-T tank farm area, which is between 221-T and 2706-T.

Related Sites/ Structures: The site is related to 2706-T, 221-T, 211-T Tank Farm.

Process Description: Originally, the tank was a product tank that stored solutions used in reactor fuel dissolving process. After T Plant ceased operation as an active process facility, the tank was used as a storage tank to temporarily hold 2706-T liquid decontamination waste until it could be sampled. The waste was then transferred to tanks in 221-T Building or to another location. The tank has not actively managed wastes since 1969. At that time a pipeline from 211-T Sump to 221-T Building was installed. Ten to eighteen inches of solids remain in the tank.

Waste Type: Chemicals

Waste Description: A video inspection showed no free liquids and about 25.4 to 45.7 centimeters (10 to 18 inches) of solids in the tank bottom. Samples of the solids were taken April 21, 1994 and showed several hazardous constituents (lead and mercury) at concentrations greater than dangerous waste levels. The tank contains low level radioactive material from decontamination activities at 2706-T.

Code: 200-W-37 **Classification:** Accepted

Names: 200-W-37; Buried Tygon Tubing Near 241-S-101 **Reclassification** Consolidated (6/13/2002)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site is not separately marked or posted.

Location: The site is located just west of the 241-S-101 tank, inside 241-S Tank Farm.

Process Description: In Volume 2 of WHC-EP-0912, JD Anderson documented interviews with former Hanford workers. One of these interviews discusses flushing plugged transfer lines with hot water. The former employee states that in order to unplug one line in 241-S Tank Farm, a piece of heavy tygon tubing was attached to the pressure hose to allow the flush water to negotiate the turns of the transfer line.

Waste Type: Equipment

Waste Description: The equipment was radioactive tygon tubing.

This Site Was Consolidated With:

Code: 200-W-96

Names: 200-W-96; Contaminated Soil at 241-S/SX/SY Tank Farm

Code: 200-W-40

Classification: Accepted

Names: 200-W-40; 292-T; Emission Control Lab; Stack Gas Sampling Building

Reclassification Rejected (6/25/2014)

Type: Laboratory

Start Date:

Status: Inactive

End Date:

Description: The waste site is a grey, concrete block building. The back side of the building is surrounded by post and chain labeled "Contamination Area". A sign on building reads "Emission Control Laboratory 292-T". The surrounding area is gravel and cobble.

This waste site is being Reclassified to Rejected because it does not meet the WIDS database scope, as described in Section 2.0 of TPA-MP-14, Rev. 2.

TPA-MP-14, Rev. 2, Section 2.0 states that WIDS does not document buildings or facilities that do not contain TSD units. It further states that, after buildings are demolished, the footprint will be evaluated for potential soil contamination. If present, the soil contamination will be added to WIDS as a Discovery Site.

Location: The building is located in northeast portion of 200 West Area, within T-Plant Complex. It is about south of 291-T stack, north of 222-T building, and east of 221-T building.

Related Sites/Structures: The site is associated with 291-T, 221-T, 216-T-8, 200-W-140-PL pipeline and the 200-W-16 underground tanks.

Process Description: The 292-T building originally housed the 291-T stack gas sampling system and supported the 221-T off gas monitoring operations. When T plant was built it was not known what material would escape during the reprocessing of the irradiated fuel. Accordingly the stack was equipped with state of the art monitoring equipment, including scrubbers containing 5% soda ash solutions that the stack effluent was passed through. The solution was dried using refrigeration, and then counted to determine Xenon-133 activity. Extensive reviews of documentation remaining from T Plant operations has not located any documents that quantify

the amount of material that was placed in the tanks, but very little emphasis was placed on waste management at that time and it is doubtful that any documents were kept. In 1966, a building addition was added to the existing structure to house a fuel element testing facility, operated by Battelle Northwest. During the lab upgrade, the two underground storage tanks were relocated from southeast of the original 292-T building to their present position, southeast of the 292-T building addition. Fuel failure analysis of irradiated fuel rods was conducted in 292-T in the 1960's and early 1970's. Irradiated N Reactor fuel rods were heated in an induction furnace until rupture or failure occurred. After the rupture occurred, the fuel was transported to the 300 area for further analysis. The fragments that remained in the oven were removed, and any material that remained on the oven surface was dissolved with nitric acid. It is doubtful that much if any of the aluminum clad was dissolved, since aluminum will not dissolve in nitric acid without the use of a catalyst. The solution of trace amounts of irradiated fuel and nitric acid was taken to 200 West Area and poured into the 292-T-TK-1 and 2 tanks through the risers. The solution in the tanks was then neutralized with sodium hydroxide. Neutralization caused the dissolved metals to precipitate and deposit in the tank bottoms.

Waste Type: Equipment

Waste Description: Building, equipment, underground lines.

Code: 200-W-41

Classification: Accepted

Names: 200-W-41; Abandoned Drums; Drums Found East of T Plant

Reclassification: Rejected (5/13/2008)

Type: Dumping Area

Start Date:

Status: Inactive

End Date: 1/1/1999

Description: In August 1996, the site was described as a single 190-liter (50-gallon) carbon tetrachloride drum and two 114-liter (30-gallon) Trysben (herbicide) drums. The drums showed no evidence of contaminating the surrounding soil. A hole was observed near the bottom of the carbon tetrachloride drum. A site investigation done in September 1996 found only two drums at this location. The 114-liter (30-gallon) Trysben weed killer drum was in good condition and was completely sealed. The drums were removed in September 1999.

Location: The site was located in 200 West Area approximately 200 to 300 meters (660 to 980 feet) east of T Plant, between Beloit and Albany Avenues and north of 23rd Street.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: The waste consisted of empty drums, removed in 1997. There was no evidence of leakage from the drums, and no stained soil under them.

Code: 200-W-43

Classification: Accepted

Names: 200-W-43; 291-S Stack Sand Filter

Reclassification: None

Type: Sand Filter

Start Date: 1/1/1952

Status: Active

End Date:

Description: The 291-S Stack Sand Filter is a below grade concrete structure containing seven layers of sand and gravel. The walls and roof are 0.3 meters (1 foot) thick. The roof is visible above grade and is covered with tar and gravel. The sand filter is outside dimensions are 26 by 26 meters (85 by 85 feet) with a depth of 4 meters (12.5 feet).

Location: The 291-S Stack Sand Filter is located adjacent to the east end of the 202-S Facility, southwest of the 291-S Stack.

Related Sites/ Structures: Associated structures include the 291-S-1 Stack and the 291-S Fan House.

Process Description: Layers of sand and gravel were used to filter radioactive contaminants out of the ventilation effluent prior to being released through the 291-S Stack.

Waste Type: Soil

Waste Description: Seven layers of sand and gravel filter radioactive contaminants out of the ventilation effluent prior to being released through the 291-S Stack. The sand filter has a 99.8 % efficiency. The sand filter was grossly contaminated with fission products and transuranics (TRU). Some of the short-lived radionuclides have decayed since the shutdown of the REDOX operation.

Code: 200-W-46 **Classification:** Accepted

Names: 200-W-46; 222-S Laboratory Room 4-E 90-Day Waste Accumulation Area; Satellite Accumulation Area **Reclassification:** Rejected (9/14/2000)

Type: Satellite Accumulation Area **Start Date:**

Status: Active **End Date:**

Description: This site is not a 90 Day Storage Area but is a Satellite Accumulation Area for Room 4E of the 222-S Analytical Laboratory.

Location: This SAA is in Room 4E of the 222-S Building.

Related Sites/ Structures: This site is part of the 222-S Analytical Laboratory.

Process Description: Maintenance waste and expired reagents and chemicals are held here.

Waste Type: Chemicals

Waste Description: Maintenance waste and expired reagents/chemicals are held here.

Code: 200-W-47 **Classification:** Accepted

Names: 200-W-47; 211-T Storage Pad 90-Day Waste Accumulation Area **Reclassification:** Rejected (9/14/2000)

Type: Storage Pad (<90 day) **Start Date:**

Status: Inactive **End Date:**

Description: The 90 day storage area was removed when the T Plant Complex became a Treatment, Storage, and Disposal (TSD) facility. With the TSD Permit, mixed waste storage for the T Plant Complex was designated to be "a combination of paved and gravel surfaces and is surrounded by the fencing that encloses the 2706-T Building." An evaluation of the site in April 2000 showed no wastes stored in this area, but signs on the fence indicate that it is occasionally used for waste storage under the TSD Permit.

Location: The waste storage area is on the southwest side of the 2706-T Building.

Related Sites/ Structures: The site is part of the T Plant Complex TSD. Under the permit, mixed waste may be stored in both the 2607-TA Building (the former 200-W-50 site) and the area enclosed by the 2607-T fence (the former 200-W-47).

Process Description: The T Plant Complex Part B Application lists the area surrounded by the fencing around 2607-T as a dangerous waste container storage area.

Code: 200-W-48	Classification: Accepted
Names: 200-W-48; 241-TX 90-Day Waste Accumulation Area	Reclassification: Rejected (9/6/2000)
Type: Storage Pad (<90 day)	Start Date:
Status: Inactive	End Date: 1/1/1993

Description: The 241-TX Tank Farm 90-Day Waste Accumulation Area has been inactive since October 1993, per the 90-day inspection records maintained by Environmental Waste Operations at the 209-E Building. The site was a self-contained conex box with a spill berm.

Location: The 90-day pad was located approximately 23 meters (75 feet) west of the 241-TX Tank Farm in a fenced area.

Code: 200-W-49	Classification: Accepted
Names: 200-W-49; 222-S Laboratory Room 2-D 90-Day Waste Accumulation Area	Reclassification: Rejected (9/14/2000)
Type: Storage Pad (<90 day)	Start Date:
Status: Active	End Date:

Description: The storage pad is located in Room 2D of the 222-S Analytical Laboratory, and holds solid and liquid mixed waste from laboratory sample analysis activities.

Location: The storage pad is in room 2D of the 222-S Laboratory.

Related Sites/ Structures: The storage pad is related to the 222-S Analytical Laboratory.

Process Description: The pad holds solid and liquid mixed waste from laboratory sample analysis activities.

Waste Type: Chemicals

Waste Description: The pad holds solid and liquid mixed waste from laboratory sample analysis.

Code: 200-W-50	Classification: Accepted
Names: 200-W-50; 2706-T 90-Day Waste Accumulation Area	Reclassification: Rejected (9/14/2000)
Type: Storage Pad (<90 day)	Start Date:
Status: Inactive	End Date:

Description: The 90 day storage area was removed when the T Plant Complex became a Treatment, Storage,

and Disposal (TSD) facility. With the TSD Permit, mixed waste storage for the T Plant Complex was designated to be "a combination of paved and gravel surfaces and is surrounded by the fencing that encloses the 2706-T Building." An evaluation of the site in April 2000 showed no wastes stored in this area, but signs on the fence indicate that it is occasionally used for waste storage under the TSD Permit.

Location: The waste storage area is adjacent to the west end of the 2706-T Building.

Related Sites/ Structures: The site is part of the T Plant Complex TSD. Under the permit, mixed waste may be stored in both the 2607-TA Building (the former 200-W-50 site) and the area enclosed by the 2607-T fence (the former 200-W-47).

Process Description: The 2706-T Building is used to decontaminate railroad equipment, buses, trucks, automobiles, road building equipment, and process equipment.

Code: 200-W-55 **Classification:** Accepted

Names: 200-W-55; Dumping Area North of 231-Z **Reclassification:** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The site consists of scattered debris inside the north end of a large depression. The debris consists of concrete rubble, wood, cans, pipes and rusted sheet metal. The site is not marked or radiologically posted.

Location: The site is located approximately 240 meters (800 feet) north of the 231-Z building.

Waste Type: Misc. Trash and Debris

Waste Description: The debris at the site included concrete rubble, wood, cans, pipes and rusted sheet metal.

Code: 200-W-56 **Classification:** Accepted

Names: 200-W-56; Debris North of 221-U **Reclassification:** Rejected (12/21/2004)

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: An area of debris was identified during a 1997 RCRA Permit General Inspection tour. The site consists of a pile of dirt approximately 10 feet in diameter containing wire, fencing material, metal scrap, cable and grounding rods. The site is not marked or radiologically posted.

Location: The site is located approximately 150 yards north of 221-U.

Waste Type: Misc. Trash and Debris

Waste Description: Debris includes wire, fencing material, metal scrap, cable and grounding rods.

Code: 200-W-57 **Classification:** Not Accepted

Names: 200-W-57; Area West of 2714-U Fence; Excess Equipment Laydown Area Identified in RCRA General Inspection #200WFY97 Item #10 **Reclassification:** None

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site had been two excess equipment laydown areas, located outside the fenced 2714-U facility. One area was adjacent to the U Plant Chemical Spur railroad track. The second area was located adjacent to the western edge of the T Hopper storage area fence. A RCRA General Inspection identified the material as an area needing to be addressed. During the RCRA field inspection on October 8, 1997, the site was discussed with Bill Osborne and Dave Baker of ERC. The equipment was in the process of being salvaged and or recycled. The material has now been removed and is now an empty gravel area.

Location: The laydown area was located outside of the fenced T-Hopper Storage Area, on the west side of the 2714-U Building.

Related Sites/ Structures: The site was adjacent to the 2714-U storage facility building (sitecode 200-W-104).

Waste Type: Equipment

Waste Description: The equipment included electric motors, miscellaneous piping, heavy equipment parts, metal screen, wood, fiberglass vessels, an open steel tank, and scaffolding. There does not appear to be material that could be considered a dangerous waste in the area.

Code: 200-W-60

Classification: Accepted

Names: 200-W-60; 284-W Brine Pit; 284-W Salt Dissolving Pit and Brine Pump Pit

Reclassification: Rejected (4/20/2000)

Type: Sump

Start Date: 1/1/1942

Status: Inactive

End Date: 1/1/1995

Description: The brine pit is no longer visible. It was demolished into itself and backfilled with gravel in 1999. It is not marked or posted.

The two salt dissolving pits each had inner dimensions of 4.3 meters (14 feet) long by 2.4 meters (8 feet) wide by 2.8 meters (9.25 feet) tall. They had a design high water line 2.4 meters (7.75 feet) from the pit bottom. An overflow slot connecting the two dissolving pits was located 0.3 meters (1 foot) above the high water line. The bottom of each pit was filled with a 12.7 centimeter (5 inch layer) of 1.3 to 2.6 centimeter (1/2 to 1 inch) gravel topped by a 17.8 centimeter (7 inch) layer of 0.3 to 0.6 centimeter (1/8 to 1/4 inch) gravel. The dissolving pits each had a 2.4 meter (8 foot) by 0.9 meter (3 feet) opening at the top for receiving salt. Each pit has a capacity of 23,600 kilograms (52,000 pounds) of salt. The brine pump pit was located adjacent to the two salt dissolving pits. The pit was 3.3 meters (10.67 feet) long by 2.2 meters (7.33 feet) wide by 2.1 meters (7 feet) deep. It held two pumps and associated piping (all brass) for the brine system. The floor of the pump pit sloped toward a 46 by 46 by 46 centimeter (18 by 18 by 18 inch) sump in a corner.

Location: The brine pit was located southwest of the 284-W Powerhouse.

Related Sites/ Structures: The site is associated with the 284-W Powerhouse.

Process Description: The salt dissolving pits and brine pump pit were part of a single below-grade concrete structure that provided brine for the 284-W Powerhouse. The brine was used to regenerate the ion exchange demineralizers that were part of the powerhouse water treatment system. The brine was created by adding water to the salt in the dissolving pit. As the water passed through the salt, the solution became saturated. The brine passed through the layers of gravel which filtered

out salt crystals and other particles. The filtered brine was then drawn off by a pipe connecting to the adjacent brine pump pit. A float valve was used to maintain the water/brine level.

Waste Type: Demolition and Inert Waste

Waste Description: The concrete structure was cleaned out, demolished, and buried in place.

Code: 200-W-61

Classification: Accepted

Names: 200-W-61; 284 Powerhouse Coal Ramp Washdown Pit; Miscellaneous Stream #471; 200 West Powerhouse Coal Ramp Washdown Pit

Reclassification: Rejected (4/20/2000)

Type: Depression/Pit (nonspecific)

Start Date:

Status: Inactive

End Date: 1/1/1995

Description: The pit is partially filled in with tumbleweeds and surrounded with metal fence posts and a light chain wire. It is adjacent to a concrete pad, which is next to the railroad track and coal off-loading chute.

Location: The washdown pit is west of the 200 West Powerhouse and coal ramp.

Related Sites/Structures: The pit is associated with the 284-W Powerhouse.

Process Description: The powerhouse coal ramp was washed down periodically. The washdown water was collected in three sumps. During the summer months, the sumps were pumped approximately two times per week, discharging the water into the washdown pit. During the winter months, the sumps were pumped two times per day.

Waste Type: Water

Waste Description: The pit received water from the sumps that collected coal ramp washdown water.

Code: 200-W-62

Classification: Accepted

Names: 200-W-62; 200 West Powerhouse Coal Pile

Reclassification: Rejected (6/18/2008)

Type: Depression/Pit (nonspecific)

Start Date:

Status: Inactive

End Date: 1/1/1995

Description: The ground surface is covered with remnants of coal. Very little vegetation is growing, only small tumbleweeds. The north side is bordered by a concrete wall. Near the wall is a wooden structure, about 4 meters (12 feet) square and 15 centimeters (6 inches) high, covering the hole used to feed coal to the conveyor belt.

Location: The pile was located west of the powerhouse and south of the coal ramp conveyor belt.

Related Sites/Structures: The site is associated with the 284-W Powerhouse.

Process Description: Large piles of coal had been stored in this area to fuel the 284-W Powerhouse. The powerhouse was shut down in 1995. Most of the coal pile has been removed.

Waste Type: Demolition and Inert Waste

Waste Description: A waste determination for Anthracite (Anthrafil) was performed in 1994. A waste determination for bituminous coal dust was performed in 1996. Both waste streams were determined to be nondangerous.

Code: 200-W-65 **Classification:** Not Accepted

Names: 200-W-65; Abandoned Water System Pump Vault; Concrete Vault Northwest of WRAP; Water Pumping Station Vault **Reclassification:** None

Type: Control Structure **Start Date:**

Status: Inactive **End Date:**

Description: The structure is in the undeveloped land in the northwest corner of the 200 West Area. It is a concrete box measuring approximately 3 meters (10 feet) by 3 meters (10 feet) with a smaller concrete curbed structure rising from the center. There are two pipe penetrations and a drain in the floor of the box. A steel grate covers the top. There is an electrical conduit penetrating the wall of the structure and a concrete pump pad. It appears to be an old, abandoned water pumping station for irrigation or dust control.

Location: The site is located in the northwest corner of 200 West Area, approximately 0.46 kilometers (0.75 miles) northwest of the WRAP facility. It is adjacent to a gravel road (jeep trail).

Process Description: The structure appears to be part of a Pre-Hanford irrigation system or part of an early Hanford construction dust control system.

Waste Type: Misc. Trash and Debris

Waste Description: Concrete

Code: 200-W-66 **Classification:** Not Accepted

Names: 200-W-66; Oil Spill at JCI Annex Feeding 283-W/262-WC **Reclassification:** None

Type: Unplanned Release **Start Date:** 12/26/1998

Status: Inactive **End Date:** 12/29/1998

Description: The contaminated soil was removed and the site has been backfilled to grade level with crushed gravel on 12/29/98. No visual evidence of diesel stained soil and no diesel fumes were observed a few days later, during an inspection on 1/4/99.

Location: The site is located between the 283W and the 284W buildings, just north of 20th street. The 283BA boiler annex fuel tank is located just north of the site.

Release Description: Diesel fuel is delivered to JCI 200 east and west boiler annexes by RH Smith Distributing. While delivering fuel to the 283W annex a faulty cam-lock on the dispensing hose at the tank trailer caused fuel to spill on the ground. The RH Smith delivery driver initially estimated the spill to be 3-5 gallons. Notification was made to RH Smith's main office as well as JCI's Operations Supervisor, Mr. Tim Cook. With the initial estimate being less than the required reporting quantity of 10 gallons, no further notifications were made. JCI Operations Supervisor and RH Smith management instructed personnel to apply absorbent to collect and dispose of spilled fuel. This initial estimate of the amount of fuel spilled proved misleading due to the snow and ice present on the ground. Over the weekend of 12/26/1998, a warming trend resulted in the snow and ice to dissipate. On Monday 12/28/1998 a JCI Operator identified diesel fuel

still being present. The JCI Operator contacted Mr. Cook who then re-appraised the situation. Through this re-evaluation it was determined that approximately 30 gallons of diesel fuel spilled onto the ground, from the base of the annex fuel tank approximately ten feet southward. The entire area of the spill is located on JCI leased property.

Related Sites/ Structures: The spill is related to the 283W-BA boiler annex fuel tank. The tank is periodically filled via tanker truck.

Waste Type: Soil

Waste Description: The waste is diesel contaminated soil. The type of diesel spilled was 70% Low Sulfur Diesel Dyed number 2 and 30% Low Sulfur Strove Dyed number 1. The contaminated soil was excavated and backfilled with clean fill to grade level by R.H. Smith Distributing. R.H. Smith Distributing has contracted White Shield Environmental of Grandview, WA to remediate the contaminated soil. White Shield Environmental has recommended the Alpha bioremediation process to treat the contaminated soil that was removed on 12/29/98.

Code: 200-W-68 **Classification:** Not Accepted

Names: 200-W-68; Historic Disposal Site; RCRA General Inspection Report 200WFY99 Item #3 **Reclassification:** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The site is a small area, measuring 4.6 by 3 meters (15 by 10 feet), that contains rusted electrical equipment. The material includes conduit, a light reflector, a space heater, a vent pipe, a little broken glass, and some pieces of charcoal. None of the equipment would have held liquids such as cooling oils or PCBs. One rock appears to have been fire cracked, but there is no discoloration of the soil. The vegetation at the site matches the surrounding area.

Location: The site is about 25 meters west of Albany Road and 130 meters north of 13th Avenue, and is visible from the road.

Waste Type: Misc. Trash and Debris

Waste Description: The wastes consist of pieces of rusted electrical equipment, with small amounts of broken glass and charcoal. None of the electrical pieces would have held liquids.

Code: 200-W-69 **Classification:** Accepted

Names: 200-W-69; 222-S Laboratory Complex **Reclassification:** None

Type: Laboratory **Start Date:** 1/1/1951

Status: Active **End Date:**

Description: The 222-S Laboratory Complex is made up of the following components, several of which have separate WIDS entries (such as the components of the Treatment, Storage, and Disposal (TSD) facility):

- The 222-S Analytical Laboratory
- The 222-S Dangerous and Mixed Waste Storage Area (DMWSA), a storage unit
- The 219-S Waste Handling Facility, which contains the 219-S-101, 102, 103, and 104 storage tanks,
- The 222-SA Standards Laboratory,
- The 296-S-21 (active), 219-S-16 (active), 296-S-23 (active), and 296-S-13 (inactive) Stacks.

The 222-S Complex buildings were constructed in 1950 and 1951 to provide analytical chemistry services for the Reduction-Oxidation (REDOX) Plant. Currently, the 222-S Complex supports a large array of facilities and programs on the Hanford Site with analytical chemistry services.

The 222-S Laboratory is a two-story building in the southeast corner of the 200 West Area. The first floor is divided into three general areas. The west end holds the lunchroom, offices, and locker rooms, which are maintained free of radioactive and dangerous materials. The central section contains laboratories and service areas for work with radioactive and/or dangerous materials. Off the north side of the central section, on the outside of the building, is the 222-S Dangerous and Mixed Waste Storage Area. The east end, also called the multi-curie section, contains laboratories, hot cells, and service areas for work with radioactive samples. All first floor sinks, hood drains, drinking water fountains, equipment cooling water, and steam condensate from radioactive areas drain to the 207-SL Retention Basin. The basins are a non-radioactive, non-hazardous facility. Mixed waste effluents drain to the 219-S Waste Handling Facility.

The second floor of the 222-S Laboratory contains the ventilation supply fans, supply and exhaust ductwork, ventilation system operation and control room, and storage areas. All floor drains, steam condensate overflow drains and the demineralized water system drains empty into the 207-SL Retention Basins.

The 222-S basement contains service piping, vacuum pumps, the counting room areas, an instrument maintenance shop, and a scanning electron microscope. Effluents from the cold tunnel sumps are discharged to the 207-SL Retention Basins and effluents from the hot tunnel sumps discharge to the 219-S Waste Handling Facility.

The supply water for the 222-S Laboratory consists of raw and sanitary water and steam. The raw water is primarily used in the first floor fire sprinkler system, and is less than 1 percent of the waste streams that discharge to the 207-SL Retention Basins. Sanitary water is used for all the other fire sprinkler systems, lab sinks, and hot cells. The sanitary water is estimated to contribute about 85 percent of the waste stream to the 207-SL Retention Basins, and steam condensate is the remaining approximately 15 percent.

The 222-S Dangerous and Mixed Waste Storage Area is part of the 222-S Laboratory Complex TSD, number TS-2-I, and WIDS site code 222-SD. It is located on the north side of the 222-S Laboratory building. Also part of the TSD are Room 2B (site 200-W-76), Room 4E, and the 219-S Storage Tanks (WIDS codes 219-S-101, 219-S-102, and 219-S-103, which includes tank 104).

The 219-S Waste Handling Facility, off the northeast side of the 222-S Laboratory Building, receives liquid mixed waste through hot disposal sinks in the 222-S Laboratory. The waste flows from sink and hot cell drains through all-welded, corrosion-resistant piping to corrosion-resistant tanks located in a below-ground concrete vault in the 219-S facility. The underground portions of the piping are double-encased stainless steel with leak detection to ensure containment and notification if a leak should occur. Pipe connections to the tanks are above maximum liquid levels to avoid potential leaks. The area above the vault is covered with a permanent enclosure and the operating gallery, located north of the vault, contains instrumentation and controls. Adjacent to the operating gallery is the sample gallery which contains a hood that is used for sample analysis during waste transfers. Wastes sent to tanks 101 and 104 are transferred to tank 102, which is a transfer point to the appropriate storage tank in the Double-Shell Tank System. After treatment in tank 102, the waste is transferred through a double encased fiberglass line to Tank Farms via the 244-S Double Contained Receiver Tank (DCRT). Overflows from tanks 101 and 102 are collected in sump 7; overflows from tank 104

are collected in sump 9; intrusion liquids in Cell B are collected in sump 6; and leaks in the Operating Gallery are collected in sump 8.

The 222-SA Standards Laboratory is a five-wide trailer southeast of the 222-S Laboratory. The 222-SA Standards Laboratory prepares non-radioactive standards for the 222-S Laboratory and other analytical laboratories and is also used for non-radioactive development work. Packaged waste generated from the 222-SA Standards Laboratory is non-radioactive, non-dangerous waste, and is accumulated in satellite areas before shipment to the Central Waste Complex. Laboratory sink drains in 222-SA are transferred to the 207-SL Retention Basins.

The 296-S-21 and 296-S-16 Stacks handle both radioactive and non-radioactive emissions. The 296-S-21 Stack exhausts emissions from the 222-S Laboratory after passing through HEPA filtration. The 296-S-16 Stack exhausts emissions from tanks 101, 102, and 104 in the 219-S Waste Handling Facility after passing through a de-entrainment filter and HEPA filter. Both the 296-S-21 and 296-S-16 stacks are record sampled for periodic confirmatory measurements. The 296-S-23 stack exhausts emissions from the 219-S Sample Gallery Hood. It is operated intermittently during waste transfers and the periodic confirmatory measurement consists of a bi-annual non-destructive assay (NDA) of the HEPA filter.

Location: The 222-S Laboratory Complex is on the north side of 10th Street, west of Beloit Ave, in the 200 West Area. The laboratory complex is south of REDOX.

Related Sites/ Structures: Associated Structures: WIDS site code 222-SD, the 222-S Laboratory Storage Pad, is currently listed as a separate site in WIDS. However, it is a part of the TSD site as described in the Part B Permit. Site codes 219-S-101, 219-S-102, and 219-S-103 (which includes tank 104), are stainless steel tanks in a below grade concrete vault at the 219-S Waste Handling Facility, and are also part of the 222-S Laboratory TSD. Room 2B of the TSD is WIDS site code 200-W-76. Site code 200-W-49 (222-S Laboratory Room 2-D 90-Day Waste Accumulation Area) is a rejected site in WIDS. Ninety-Day Waste Accumulation Areas are specifically exempt from classification as waste sites in TPA-MP-14. Site code 218-W-7, 222-S Vault, is a carbon steel burial vault southeast of the 222-S Building. It received dry, packaged laboratory and sampler waste from the 222-S Laboratory. Site code UPR-200-W-137 is a duplicate of 218-W-7. Site code 216-S-19, 222-S Lab Swamp, 216-SL-1, REDOX Lab Swamp, was open from 1952 to 1984, and received miscellaneous wastes from laboratory hoods and decontamination sinks in the 222-S Laboratory Building via the 207-SL Retention Basins.

Process Description: The 222-S Laboratory was originally built to support the REDOX plutonium separation process operation in the 202-S facility. After the REDOX process shut down, the laboratory continued to support other Hanford project analyses.

Waste Type: Chemicals

Waste Description: The 219-S Waste Handling Facility receives low-level aqueous mixed waste generated by the 222-S Analytical Laboratory, and is either intermediate-or high-activity waste. The waste is designated as dangerous because of the characteristic of corrosivity. Liquid organic waste is not accepted in the 219-S Waste Handling Facility. Chemicals from the 222-S Analytical Laboratory are outdated or off-specification and are both liquid and solid. Nonradioactive dangerous waste includes chemicals from the 222-SA Standards Laboratory and nonradioactive off-specification chemicals from the 222-S Analytical Laboratory. This waste is regulated as dangerous waste because individual waste chemical characteristics can include: solid or liquid; reactive with water; ignitable; reactive to form toxic gases; oxidizer; cyanide or sulfide bearing; corrosive; and toxic.

Liquid organic waste contains both nonradioactive and radioactive organic components, and results from organic analyses of volatile, semivolatile, pesticide, and polychlorinated biphenyl compounds during daily laboratory operations. Occasional waste includes mixed and nonradioactive dangerous waste generated during sample analysis such as rags, paper towels,

and contaminated gloves; waste oil generated from equipment maintenance; and mercury-contaminated materials such as bulbs and thermometers. Returned samples come from off-site laboratories. The unused portions of analyzed samples are returned to the generator (the Hanford Site).

Code: 200-W-70 **Classification:** Accepted

Names: 200-W-70; 2731 Burning Pit; Old Burn Pit **Reclassification** Rejected (5/31/2001)
Southeast of Z Plant; 200 West Original Burn Pit

Type: Burn Pit **Start Date:** 1/1/1944

Status: Inactive **End Date:** 1/1/1949

Description: The site is no longer visible, marked, or posted. It can be seen in an aerial photo from 1948, and Hanford drawing H-2-10011. Its is just outside the current Z Plant fenced area. The location is a flat, graveled parking area, containing the tile field for septic system 2607-WB. In 2012, a new potential asbestos in soil site (200-W-247) was identified and posted with chain. Part of 200-W-247 is located on the previous burn pit.

Location: The burn pit was located southeast of the 231-Z Facility. It is just outside the Z Plant fenced area, east of 234-5Z. A portion of the 216-Z-1 Ditch is adjacent to this burn pit.

Related Sites/ Structures: In 2012, a Potential Asbestos in soil site was posted near 200-W-70. The new WIDS site is 200-W-247.

Process Description: The open pit was used by the construction forces for burning non-contaminated scrap lumber and miscellaneous debris.

Waste Type: Construction Debris

Waste Description: The pit received miscellaneous debris and scrap lumber during early 200 Area construction projects. In 2004, some transite material was identified. Transite is considered an asbestos-containing material. The asbestos is in a non-friable state.

Code: 200-W-72 **Classification:** Not Accepted

Names: 200-W-72; 200-ZP-1 Pump and Treat Unplanned **Reclassification** None
Release

Type: Unplanned Release **Start Date:** 1/1/2000

Status: Inactive **End Date:**

Description: There is no visual evidence of the release. Most of the water released was contained within the building, but some leaked into the electrical vaults. The release was determined to be below CERCLA Reportable limits.

Location: The 200-ZP-1 Pump and Treat system equipment is located northwest of the 231-Z Building in the 200 West Area.

Release Description: On April 13, 2000, a line break at the 200-ZP-1 Pump and Treat system facility caused approximately 87,400 liters (23,000 gallons) of contaminated water to spill inside the building. Most of the water was contained within the building, but some leaked into the electrical vaults. The water was recovered with pumps and transported to Modu-tanks. The CERCLA Reportable quantity for this contaminant is 10 pounds. Only 3.5 parts per million or 0.7 pounds of carbon tetrachloride was calculated to be in the 23,000 gallons of water. Therefore, this was a non-reportable incident.

Process Description: The 200-ZP-1 Pump and Treat system is used to pump groundwater that is contaminated with carbon tetrachloride and treat it before returning it to the ground.

Waste Type: Water

Waste Description: The waste was groundwater containing a total of 0.7 pounds of carbon tetrachloride.

Code: 200-W-74 **Classification:** Not Accepted

Names: 200-W-74; 90 Day Storage Area East Side of 622 F **Reclassification:** None

Type: Storage Pad (<90 day) **Start Date:** 1/1/2000

Status: Inactive **End Date:** 1/1/2000

Description: This is a duplicate of site 600-267; the site number was used in error. The pad, inside a metal shed, has been closed.

Location: The site was located on the east side of the 622 F Building (Weather Station).

Related Sites/ Structures: Site 600-267 is the correct side code for this closed 90 Day Accumulation Area.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description:

Code: 200-W-76 **Classification:** Accepted

Names: 200-W-76; Room 2B 222-S Laboratory TSD **Reclassification:** None

Type: Storage **Start Date:** 1/1/1951

Status: Active **End Date:**

Description: The north end of Room 2B in the 222-S Laboratory is partitioned off as a Treatment, Storage, and Disposal (TSD) area using a locked accordion style gate to prevent unauthorized access.

Location: The site is located inside the 222-S Laboratory facility.

Related Sites/ Structures: Room 2B is part of the 222-S Laboratory TSD, which also includes the 219-S Tanks, which are WIDS sites 219-S-101, 219-S-102, and 219-S-103 (site 219-S-103 includes both tanks 103 and 104) and the 222-S Dangerous and Mixed Waste Storage Area, which is WIDS site 222-SD.

Process Description: The Room 2B TSD provides container storage of solid and liquid mixed waste until the waste can be transferred to another TSD unit. Hood 16, within Room 2B, is the introduction point for transfer of liquid mixed waste from containers to the 219-S Waste Handling Facility. Mixed waste exceeding personnel protection radiological levels during transfer are introduced into the 219-S Waste Handling Facility via drains in hot cells instead of Hood 16.

Waste Type: Chemicals

Waste Description:

Code: 200-W-91 **Classification:** Accepted

Names: 200-W-91; Underground Radioactive Material Area Adjacent to the North Side of 241-U Tank Farm

Reclassification Consolidated (6/13/2002)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The site is a large, irregular shaped area. The area has been covered with clean gravel and posted with Underground Radioactive Material signs. The 2607-WUT sanitary tile field is located adjacent to the western edge of this stabilized zone. The area was surveyed with GPS in 2009. The size and shape of the posted area is larger than the area reported in 1995. The waste site was consolidated into 200-W-95.

Location: The site is located adjacent to the north fenceline of 241-U Tank Farm, west of Camden Avenue.

Release Description: The routine tank farm perimeter surveys were used to trace the radiological history of the contamination on the northeast corner of 241-U Tank Farm. Specks of contamination were documented on the May 1983 and May 1984 surveys, with contamination levels ranging from 500 to 20,000 counts per minute. In September 1986, the area was surrounded with radiation rope and posted with Surface Contamination Area signs. The Surface Contamination Area is documented on subsequent surveys through November 1994. On the May 1995 survey, the area is documented as an Underground Radioactive Material area.

Related Sites/ Structures: The site is associated with the 241-U Tank Farm and has been Consolidated with the 241-U Tank Farm contaminated soil sitecode 200-W-95.

Waste Type: Soil

Waste Description:

This Site Was Consolidated With:

Code: 200-W-95

Names: 200-W-95; Contaminated Soil at 241-U Tank Farm; Contamination Migration Beyond the 241-U fence

Code: 200-W-101

Classification: Accepted

Names: 200-W-101; Contaminated Material West of 216-S-12 Crib

Reclassification Rejected (7/15/2015)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The waste site was reclassified to Rejected in 2015. It was identified in 2001. It consisted of two large boxes and a rusted metal shaft surrounded with light post and chain, and posted with Contamination Area signs. The metal shaft was approximately 18 meters (60 feet) long and extends beyond (outside) the posted area chain. The debris was removed and disposed to ERDF in July 2011. The previously posted area was surveyed. No contamination was detected and the radiological postings were removed. Only the WIDS sitecode signs remain.

Location: The debris had been located west of Beloit Ave., west of the 216-S-12 Crib.

Waste Type: Equipment

Waste Description: The material inside the posted area consists of two large boxes and a long metal pipe (shaft).

Code: 200-W-103 **Classification:** Not Accepted
Names: 200-W-103; 201-W Concrete Silo **Reclassification:** None
Type: Experiment/Test Site **Start Date:**
Status: Inactive **End Date:**

Description: The structure is a concrete silo. The silo is marked with painted lines, dividing it into rows and sections. The rows are labeled A, B, C, D, and E. The sections are labeled 1 through 10. Electronic sensing devices are embedded into some of the concrete sections. A white, cylindrical liner is standing next to the silo.

Location: The site is located in 200 West Area, on the north side of 13th Street near Albany Ave. It is inside the 201-W facility fence.

Process Description: The silo was constructed as a feasibility test for aboveground, dry waste storage. No waste was ever stored at this site. The test was observing the durability of the concrete silo and the steel liner as it was exposed to the elements over time. The silo has been abandoned. The electronic sensors embedded into the concrete are no longer functioning.

Waste Type: Demolition and Inert Waste

Waste Description: This was a test facility that did not receive any waste.

Code: 200-W-104 **Classification:** Accepted
Names: 200-W-104; 2714-U Building; 2714-U Foundation; UO3 Storage Warehouse **Reclassification:** None
Type: Foundation **Start Date:**
Status: Inactive **End Date:** 1/1/2005

Description: The site was a metal building. The building had been posted with Contamination Area, Radioactive Material Area signs. The 2714-U and 275-UR buildings were demolished in 2005. The 2714-U foundation is posted with Underground Radioactive Material signs. (see sitecode 200-W-87)

Location: The building was located northwest of the 221-U canyon facility.

Process Description: The 2714-U Storage Facility had been used to store material related to the Uranium Trioxide operations occurring in 224-U and some items for the Plutonium Finishing Plant. Before being demolished, the main incoming power lines were disconnected at the building. The doors were locked and bird netting was placed at the entrance's on both sides of the building for pest control.

Waste Type: Soil

Waste Description: After the building was demolished in 2005, the foundation was posted with Underground Radioactive Material signs.

Waste Type: Equipment

Waste Description: The building had been used to store contaminated equipment related to the Uranium Trioxide operation. Two water shield doors (water drained) were also being stored for the Plutonium Finishing Plant facility along with some miscellaneous metal piping.

Code: 200-W-107 **Classification:** Accepted
Names: 200-W-107; 222-U Building Stormwater Runoff; Miscellaneous Stream #685 **Reclassification** Consolidated (7/15/2015)
Type: Injection/Reverse Well **Start Date:**
Status: Inactive **End Date:**

Description: This french drain structure has been consolidated with 200-W-136. It is located within the graveled area and is no longer visible. It is part of the posted Underground Radioactive Material remediation stabilization area that was created when the 222-U building was demolished in 2005 (see sitecode 200-W-136).

The yellow metal cover had a slot on one side and was level with the surrounding ground. In 2003, no aboveground pipes were visible extending from the building to the drain. The drain lid was posted with a "Contamination Area" sign and a label stating "This is Not a Confined Space".

Location: The drain was located approximately eight feet east of the back wall of the 222-U Building, just west of 216-U-4B. It is now within the Underground Radioactive Material gravel area known as 200-W-136. (coordinates using Qmap = N135122/E56612)

Related Sites/ Structures: This site is associated with the 222-U Building and 200-W-136.

Waste Type: Stormwater Runoff

Waste Description: Documentation states that the site received stormwater runoff from the east side or backside of the 222-U Building. During the site walkdown, however, it was unclear how the drain received stormwater because no pipes were observed extending from the building into the drain.

This Site Was Consolidated With:

Code: 200-W-136
Names: 200-W-136; Demolished 224-U, 224-UA, 203-U, 203-UX, 222-U; Posted Underground Radioactive Material Area; Potential Asbestos in Soil

Code: 200-W-108 **Classification:** Accepted
Names: 200-W-108; 222-U Building Stormwater Runoff; Miscellaneous Stream #687 **Reclassification** Consolidated (7/15/2015)
Type: Injection/Reverse Well **Start Date:**
Status: Inactive **End Date:**

Description: This french drain structure has been consolidated with 200-W-136. It is located within the graveled area and is no longer visible. It is part of the posted Underground Radioactive Material remediation stabilization area that was created when the 222-U building was demolished in 2005 (see sitecode 200-W-136). It is part of the posted Underground Radioactive Material remediation stabilization area that was created when the 222-U building was demolished in 2005 (see sitecode 200-W-136). In 2003, the drain had a yellow metal cover with a slot on one side and was level with the surrounding ground. There were no postings on the yellow metal cover and no aboveground pipes were visible extending into the drain. The yellow drain lid was moved to the side, revealing a 0.76 meter (2.5 foot) diameter culvert, approximately 1.2 meters (4 feet) deep. The culvert was dry. No aboveground pipes were visible during the 2003 walkdown that extended to the french drain.

Location: The site is located on the northeast corner (back side) of the 222-U Building. (coordinates per

Qmap= N135141/E567624) It is now within the gravel area known as 200-W-136.

Related Sites/ Structures: The drain is associated with the demolished 222-U building and the 200-W-136 remediation area.

Waste Type: Stormwater Runoff

Waste Description: Documentation states that the site received stormwater runoff from the east side or backside of the 222-U Building. During the 2003 site walkdown, it was unclear how the drain received stormwater because no pipes were observed extending from the building into the drain and the top of the drain was even with the surrounding ground.

This Site Was Consolidated With:

Code: 200-W-136

Names: 200-W-136; Demolished 224-U, 224-UA, 203-U, 203-UX, 222-U; Posted Underground Radioactive Material Area; Potential Asbestos in Soil

Code: 200-W-109

Classification: Accepted

Names: 200-W-109; 222-U Building Stormwater Runoff; Miscellaneous Stream #521

Reclassification: Consolidated (7/15/2015)

Type: Injection/Reverse Well

Start Date:

Status: Inactive

End Date:

Description: This french drain structure has been consolidated with 200-W-136. It is located within the graveled area and is not visible on the surface. It is part of the posted Underground Radioactive Material remediation stabilization area that was created when the 222-U building was demolished in 2005 (see sitecode 200-W-136). It is part of the posted Underground Radioactive Material remediation stabilization area that was created when the 222-U building was demolished in 2005/2006 (see sitecode 200-W-136). In 2003, the structure had a yellow metal cover with a slot on one side and was level with the surrounding ground. There were no postings on the yellow metal cover and no aboveground pipes were visible extending to the drain. When the cover was removed, the drain structure was found to be filled with sand.

Location: The site was located near the center of the east side of the 222-U Building between the 200-W-108 and 200-W-111 french drains (coordinates per Qmap = N135121/E567607). It is now within the gravel area known as 200-W-136.

Related Sites/ Structures: This site is associated with the 222-U Building and the 200-W-136 stabilized area.

Process Description: The drain received rainwater and stormwater from the 222-U building area.

Waste Type: Stormwater Runoff

Waste Description: Documentation states that the site received stormwater runoff from the east side or backside of the 222-U Building. During the site walkdown, however, it was unclear how the drain could have received stormwater because no pipes were observed extending from the building into the drain.

This Site Was Consolidated With:

Code: 200-W-136

Names: 200-W-136; Demolished 224-U, 224-UA, 203-U, 203-UX, 222-U; Posted Underground Radioactive Material Area; Potential Asbestos in Soil

Code: 200-W-111 **Classification:** Accepted
Names: 200-W-111; 222-U Building Stormwater Runoff; Miscellaneous Stream #394 **Reclassification:** Consolidated (7/15/2015)
Type: Injection/Reverse Well **Start Date:**
Status: Inactive **End Date:**

Description: This french drain structure has been consolidated with 200-W-136. It is located within the graveled area and is no longer visible. It is part of the posted Underground Radioactive Material remediation stabilization area that was created when the 222-U building was demolished in 2005 (see sitecode 200-W-136). It is part of the posted Underground Radioactive Material remediation stabilization area that was created when the 222-U building was demolished in 2005 (see sitecode 200-W-136). In 2015, the MSA UIC Master List stated the drain was Permanently Abandoned.

In 2003, the site was a covered french drain. The yellow metal cover had a slot on one side and was level with the surrounding gravel covered ground. It was posted "Not a Confined Space". The cover had been placed over a 0.61 meter (2 feet) diameter vitrified clay pipe drain structure that was 0.91 meter (3 feet) deep. No underground piping was observed in the drain, nor aboveground pipes extending to the drain, however a steel drain pipe was observed extending downward on the 222-U building. The pipe had been cutoff approximately 0.61 meters (2 feet) above the ground. DOE/RL-88-11, Rev.2 states this miscellaneous stream received both stormwater and steam condensate. A steamline is visible in the background of the photograph, but does not connect to the covered drain

Location: The site is located near the southeastern corner of the 222-U Building. (coordinates per Qmap = N135111/E567605) It is now within the "Underground Radioactive Material Area" remediation stabilization gravel area known as 200-W-136.

Related Sites/ Structures: The drain is associated with the 222-U Building and the 200-W-136 Underground Radioactive Material Area.

Waste Type: Stormwater Runoff

Waste Description: Documentation states that the site received stormwater runoff from the east side or backside of the 222-U Building. During the site walkdown, however, it was unclear how the drain received stormwater because no pipes were observed extending from the building into the drain.

This Site Was Consolidated With:

Code: 200-W-136
Names: 200-W-136; Demolished 224-U, 224-UA, 203-U, 203-UX, 222-U; Posted Underground Radioactive Material Area; Potential Asbestos in Soil

Code: 200-W-112 **Classification:** Accepted
Names: 200-W-112; Miscellaneous Stream #52; Steam Condensate **Reclassification:** None
Type: Injection/Reverse Well **Start Date:**
Status: Inactive **End Date:** 1/1/1995

Description: The site was a 0.9 meter (3 foot) diameter, below ground, cement drain structure. An overhead, insulated pipe entered the top of the drain structure. The drain is currently covered with gravel and located within a posted Underground Radioactive Material Area (200-W-136). A 2012 assessment indicates the drain structure has been removed.

Location: The drain is located approximately 1.8 meters (6 feet) south of the southwest corner of the 224-U building.

Related Sites/ Structures: The site is associated with the 224-U facility and 200-W-136.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The drain received non-contaminated steam condensate from the 224-U facility. The steam source has been abandoned.

Code: 200-W-113

Classification: Accepted

Names: 200-W-113; Miscellaneous Stream #54; North Steam Pit

Reclassification: None

Type: Injection/Reverse Well

Start Date:

Status: Inactive

End Date: 1/1/1995

Description: The drain structure was covered with a yellow metal lid. The lid was labeled with "North Steam Pit" and "Confined Space" signs. The site was surrounded with metal posts and chain. The 224-U and 224-UA buildings have been demolished. The area is now covered with gravel. A 2012 assessment indicates the drain structure has been removed.

Location: The drain is located approximately 4.5 meters (15 feet) from the northwest corner of the 224-U building.

Related Sites/ Structures: The site is associated with the 224-U building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The site received non-contaminated steam condensate. The steam source has been eliminated.

Code: 200-W-115

Classification: Accepted

Names: 200-W-115; Miscellaneous Stream #138; Steam Condensate MSS-TRP-003, -063

Reclassification: None

Type: Injection/Reverse Well

Start Date:

Status: Inactive

End Date:

Description: The site is a 5.08 centimeter (2 inch) pipe and three 2.54 centimeter (1 inch) diameter pipes extending into a broken, 1.2 meter (4 foot) diameter cement french drain structure. The pipe is labeled as MSS-003.

Location: The drain is located northeast of the 221-U Building and is northeast of the 241-WR Vault.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion. This was a seasonal discharge.

Waste Type: Steam Condensate

Waste Description: The drain received non-contaminated steam condensate.

Code: 200-W-116 **Classification:** Accepted

Names: 200-W-116; Miscellaneous Stream #139; Steam Condensate MSS-TRP-004 **Reclassification:** None

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:**

Description: The site is a 0.025 meter (one inch) pipe that emptied into a 1.2 meter (4 foot) deteriorated cement drain. Tags on the steamline identified it as Steam Trap 004.

Location: The drain is located adjacent to Beloit Ave. and 16th Street, east of the north end of 221-U.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion. This was a seasonal discharge.

Waste Type: Steam Condensate

Waste Description: The drain received non-contaminated steam condensate.

Description:

Code: 200-W-117 **Classification:** Accepted

Names: 200-W-117; Miscellaneous Stream #140; Steam Condensate MSS-TRP-005 **Reclassification:** None

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:**

Description: The site is a 0.025 meter (one inch) diameter pipe extending diagonally into a 1.2 meter (4 foot) diameter cement french drain structure.

Location: The drain is located adjacent to Beloit Ave. and 16th Street, south of the 291-U Stack.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to

produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion. This was a seasonal discharge.

Waste Type: Steam Condensate

Waste Description: The drain received non-contaminated steam condensate.

Code: 200-W-118

Classification: Accepted

Names: 200-W-118; Miscellaneous Stream #141; Steam Condensate MSS-TRP-006

Reclassification: Rejected (7/15/2015)

Type: Injection/Reverse Well

Start Date:

Status: Inactive

End Date:

Description: The french drain has been reclassified to Rejected. In 2003, a site visit saw a 0.025 meter (one inch) diameter insulated pipe extending from an overground steam line into a 1.22 meter (4 foot) diameter french drain structure. The 224-U and 224-UA buildings were demolished in 2005. The remaining features were incorporated into a large Underground Radioactive Material Area (sitecode 200-W-136). The drain is now located near the edge of the graveled 200-W-136 site.

Location: The site is located inside the northeastern corner of the demolished 224-U facility area. It is north of 16th Street and west of Beloit Ave. It is located within the expanded 200-W-136 waste site.

Related Sites/Structures: See sitecode 200-W-136.

Process Description: Steam was produced at the powerhouse from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion. This was a seasonal discharge.

Waste Type: Steam Condensate

Waste Description: The drain received non-contaminated steam condensate.

Code: 200-W-119

Classification: Accepted

Names: 200-W-119; Miscellaneous Stream #142; Steam Trap 007

Reclassification: None

Type: Injection/Reverse Well

Start Date:

Status: Inactive

End Date: 1/1/1998

Description: The site includes a 0.76 meter (2.5 foot) diameter cement drain structure. The overhead steam line had multiple pipes and flanges extending from the bottom of the steam line. A label was attached to the flange, stating it is Miscellaneous Steam Trap MSS-TRP-007. One section had been cut and hung above a drain structure. Another section of insulate pipe ran northward from

the flange and has a 2.5 centimeter (1 inch) diameter pipe extending to a hole in the ground, approximately 2 feet north of the cement drain structure. The 224-U and 224-UA buildings were demolished in 2010. The area is currently covered with gravel.

Location: The site is located inside the 224-U facility fence, in the southeast corner of the fenced area. It is approximately 1.8 meters (6 feet) north of 16th Street.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The site received non-contaminated steam condensate. The source has been abandoned.

Code: 200-W-120 **Classification:** Accepted

Names: 200-W-120; Miscellaneous Steam Trap 008; Miscellaneous Stream #143 **Reclassification:** None

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:** 1/1/1998

Description: The site is a 1.8 meter (4 foot) diameter, cement drain structure. A 2.5 centimeter (1 inch) pipe extends from the flange of the overhead steam line to the drain structure. The site is labeled with a tag that identifies it as MSS-TRP-008.

Location: The site is a steam trap located outside the 224-U facility fence, on the south side of 16th Street.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The drain received non-contaminated steam condensate.

Description:

Code: 200-W-121 **Classification:** Accepted

Names: 200-W-121; Miscellaneous Steam Trap 009; Miscellaneous Stream #144 **Reclassification:** None

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:**

Description: The site is a 0.025 meter (one inch) diameter pipe extending diagonally into a 0.762 meter (30 inch) diameter cement french drain structure. The drain is filled with rock and dirt. The steam trap is labeled MSS-TRP-009.

Location: The site is located south of 16th Street, southwest of the 221-U building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The drain received non-contaminated steam condensate.

Code: 200-W-122 **Classification:** Accepted

Names: 200-W-122; Miscellaneous Steam Trap 014; Miscellaneous Stream #145 **Reclassification:** None

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:** 1/1/1998

Description: An overhead steam line crosses the railroad track leading to the REDOX facility. It was constructed approximately 20 feet above the track. A scaffold has been constructed at the steam trap location. A tag identifies this location as MSS-TRP-014. A 0,76 meter (2.5 foot) diameter, vitrified clay pipe drain structure is located below the steam line. A 2.54 centimeter (one inch) diameter pipe extends from the overhead steam line to the vitrified clay pipe french drain structure.

Location: The site is located south of 16th Street, southwest of the 221-U building. It is located adjacent to the railroad track that leads to the REDOX facility.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The site received non-contaminated steam condensate.

Code: 200-W-123 **Classification:** Not Accepted

Names: 200-W-123; Gravel Pit 35 **Reclassification:** None

Type: Depression/Pit (nonspecific) **Start Date:**

Status: Active **End Date:**

Description: The site is a large area of shallow excavations.

Location: The site is located south of 23rd Street and east of Dayton Ave. It is west of the 218-W-4A Burial Ground.

Process Description: The site is used to provide clean backfill material for small excavations.

Waste Type: Soil

Waste Description: The site is a source of clean backfill material. No waste is stored or deposited at this site.

Code: 200-W-124

Classification: Not Accepted

Names: 200-W-124; PFP Stormwater Pond; Z-9 Pond

Reclassification: None

Type: Pond

Start Date:

Status: Inactive

End Date:

Description: The pond is no longer visible. The site is not marked or posted.

Location: The pond was located at the end of a corrugated metal pipe, north and east of the 216-Z-9 crib.

Process Description: Overflow effluent from the elevated water tank, inside the Z Plant fence, was connected to a 12 inch corrugated water line. Some stormwater drainage may have also contributed to the effluent. The pond developed at the terminus of the water line during the 1960's. The pond is visible in historical 200 West photographs dated 1963 and 1969. A drawing, dated 1971, states the 12 inch corrugated line is abandoned. The pond dried up after the line was blanked off. The effluent was originally rerouted to the 216-Z-11 ditch and later routed to the 216-Z-21 basin.

Waste Type: Stormwater Runoff

Waste Description: The pond area received stormwater and water tank overflow effluent.

Code: 200-W-133-PL

Classification: Not Accepted

Names: 200-W-133-PL; V682 Spare Line

Reclassification: None

Type: Direct Buried Tank Farm Pipeline

Start Date: 1/1/1944

Status: Inactive

End Date:

Description: The site is a DUPLICATE of lines documented in 200-W-130-PL.

Location: The pipeline is located inside the 241-T tank farm, but extends south of the 241-T fenceline.

Related Sites/ Structures: The site is associated with 241-T-152 diversion box and 200-W-130-PL.

Process Description: The pipeline is considered a spare line. It is an 8.8 centimeter (3.5 inch) diameter, stainless steel pipeline that extends out of the 241-T-152 diversion box and is capped south of 241-T, beyond the tank farm fence.

Code: 200-W-134-PL

Classification: Not Accepted

Names: 200-W-134-PL; V683 Spare Line

Reclassification: None

Type: Direct Buried Tank Farm Pipeline

Start Date: 1/1/1944

Status: Inactive

End Date:

Description: The site is a DUPLICATE of lines documented in 200-W-130-PL.

Location: The pipeline is located inside the 241-T tank farm, but extends south of the 241-T fenceline.

Related Sites/ Structures: The site is associated with 241-T-152 diversion box and 200-W-130-PL.

Process Description: The pipeline is considered a spare line. It is an 8.8 centimeter (3.5 inch) diameter, stainless steel pipeline that extends out of the 241-T-152 diversion box and is capped south of 241-T, beyond the tank farm fence.

Code: 200-W-135-PL	Classification: Not Accepted
Names: 200-W-135-PL; Spare Line; V662	Reclassification: None
Type: Direct Buried Tank Farm Pipeline	Start Date: 1/1/1944
Status: Inactive	End Date:

Description: The site is a DUPLICATE of lines documented in 200-W-130-PL.

Location: The pipeline is located inside and outside the 241-T Tank Farm fence.

Related Sites/ Structures: Associated with 241-T-151 Diversion Box and 200-W-130-PL.

Process Description: Line V662 is a 7.6 centimeter (3 inch diameter), stainless steel spare pipeline. It is connected to the 241-T-151 Diversion Box. It was capped south of the diversion box, outside the tank farm fence.

Code: 200-W-145	Classification: Not Accepted
Names: 200-W-145; Hidden Wells South of U-Plant; U Plant Dry Wells	Reclassification: None
Type: French Drain	Start Date:
Status: Inactive	End Date:

Description: Multiple (more than twenty) concrete dry wells were found in an undeveloped area south of U Plant on the west side of Beloit Ave. The open concrete wells ranged in size from 91.4 centimeters (36 inches) to 106.6 centimeters (42 inches) in diameter. The estimated depths are greater than 1.8 meters (6 feet).

Location: The wells are located south of 16th Street, west of Beloit Ave and southeast of 224-U.

Process Description: A few aerial photographs from the early 1950's indicate a group of temporary construction facilities were located in this area. They apparently were connected to raw water and potable water utilities. They may also have had a buried steam distribution system. Drawings H-2-43235, dated 1951, and H-2-1496, dated 1952 show the plan and profile for the 200 West Area steam distribution system. The drawings indicate a steam connection to temporary construction facilities southeast of U Plant. A 2006 field inspection found one caisson that was open and empty enough to reveal several small diameter pipelines entering the concrete caisson wall approximately 1.2 meters (4 feet) below the ground surface. This supports the concept that they were part of an underground infrastructure system. More open wells were identified in 2010.

Waste Type: Steam Condensate

Waste Description: Drawings H-2-43235, dated 1951, and H-2-1496, dated 1952 show the plan and profile for the 200 West Area steam distribution system. The drawings indicate a steam connection to temporary construction facilities southeast of U Plant.

Code: 200-W-147-PL **Classification:** Accepted

Names: 200-W-147-PL; Pipeline from 207-SL to 216-S-19 Pond **Reclassification** Rejected (10/19/2010)

Type: Radioactive Process Sewer **Start Date:** 1/1/1952

Status: Inactive **End Date:** 1/1/1984

Description: Due to the restructuring of Operable Units, as described in the Tentative Agreement for Central Plateau Cleanup, this pipeline has been split into segments (see 200-W-147-PL-A and 200-W-147-PL-B). The site is an underground 20 centimeter (8 inch) diameter vitrified clay pipe, extending from the 207-SL retention basin to the 216-S-19 pond.

Location: This portion of the pipeline extends from the 207-SL basin to the Outer Area boundary. The majority of the original pipeline site is located south of the 200 West Area fence.

Related Sites/ Structures: The pipeline is associated with the 216-S-19 Pond, 200-W-147-PL-A and 200-W-147-PL-B.

Process Description: The pipeline carried waste from the 222-S and 202-S facilities to the 216-S-19 Pond via the 207-SL Retention Basin.

Code: 200-W-155-PL **Classification:** Accepted

Names: 200-W-155-PL; Pipeline from 2904-S-160 Control Structure to 216-S-16 Ditch **Reclassification** Rejected (10/19/2010)

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: Due to the restructuring of Operable Units, as described in the Tentative Agreement for Central Plateau Cleanup, this pipeline has been split into segments (see 200-W-155-PL-A and 200-W-155-PL-B). The waste site is an underground 61 centimeter (24 inch) diameter vitrified clay pipe. It extends from the 2904-S-160 Control Structure to the head end of the 216-S-16 Ditch.

Location: The pipeline is located outside the 200 West Area perimeter fence, southwest of the 207-S Retention Basin.

Related Sites/ Structures: The site is associated with the REDOX cooling water effluent stream, the 2904-S-160 Control Structure, the 216-S-16 Ditch and Pond and the 216-S-6 crib.

Process Description: In 1954, the original 61 centimeter (24 inch) process sewer line (sitecode 200-W-152-PL) was plugged and the flow to the 216-S-17 Pond was abandoned. The effluent was directed to the 216-S-6 crib and later to the 216-S-16 Pond via the 2904-S-160 Control Structure. Flow could be directed to 216-S-6 crib at Manhole 8 via pipeline 200-W-156-PL.

Code: 200-W-189-PL **Classification:** Accepted

Names: 200-W-189-PL; Lines SNL-5350 and SNL-5351; Transfer Lines from 219-S to 241-SY Tank Farm **Reclassification** None

Type: Direct Buried Tank Farm Pipeline **Start Date:**

Status: Active **End Date:**

Description: The waste site is two underground, 5 centimeter (2 inch) diameter fiberglass pipelines. Each line is double contained inside a 10 centimeter (4 inch) pipe.

Location: The pipeline extends between 219-S, located southeast of REDOX, and the 241-SY Tank Farm.

Related Sites/ Structures: The pipeline is associated with the 219-S building and tanks 241-SY-101 and 241-SY-103 in the 241-SY Tank Farm. It is also associated with 200-W-15.

Code: 200-W-207-PL **Classification:** Not Accepted

Names: 200-W-207-PL; 216-Z-19 and 216-Z-20 Ditches; Z Plant Radioactive Process Sewer to 216-Z-11 **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Active **End Date:**

Description: This pipeline has been split into two separate waste sites (200-W-207-PL-A - Inactive portion and 200-W-207-PL-B - Active portion). The original waste site was multiple branches of underground vitrified clay pipe that connected to manholes that originally discharged to the 216-Z-1, 216-Z-11 and 216-Z-19 ditches and the 216-Z-20 tile field.

Location: The process sewer lines extends south from the 234-5Z building and east to the 216-Z-1, 216-Z-11 and 216-Z-19 ditches. The pipeline was later diverted to the 216-Z-20 tile field.

Related Sites/ Structures: The process sewer lines are associated with the 216-Z-1, 216-Z-11 and 216-Z-19 ditches and the 216-Z-20 tile field.

Process Description: Many of the process sewer branches are active and were connected to the Treated Effluent Disposal Facility (TEDF) system in 1995. (see H-2-140332 and H-2-140336). Parts of the process sewer were lined before connecting to the TEDF system. Some branches of the sewer are not radiologically contaminated, but other portions are known to have carried radioactive waste.

Code: 200-W-207-PL-B **Classification:** Accepted

Names: 200-W-207-PL-B; PFP Process Sewer Segments Connecting to TEDF System **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Active **End Date:**

Description: The waste site is the multiple, active branches of underground vitrified clay pipe that originate at the 235-5Z, 232-Z, 242-Z, 236-Z and 291-Z buildings and the process sewer manholes.

Location: The process sewer extends south and east from the 234-5Z and supporting facilities. The active portion of the process sewer diverts to the Treated Effluent Disposal Facility (TEDF) pipeline near manhole Z8.

Related Sites/ Structures: The active process sewer is associated with the TEDF pipeline (WIDS sitecode 600-291).

Process Description: The process sewer originally fed the 216-Z-1, 216-Z-11 and 216-Z-19 ditches. Later, it fed the 216-Z-20 ditch (see 200-W-207-PL-A). In 1981, the process sewer was reconfigured to accommodate the construction of the 232-Z building. Some of the original sections of process sewer piping were removed during the construction of the 232-Z building.

Many of the process sewer branches are active and were connected to the Treated Effluent Disposal Facility (TEDF) system in 1995. (see H-2-140332 and H-2-140336). Parts of the process sewer were lined before connecting to the TEDF system. Some branches of the sewer

are not radiologically contaminated, but other portions are known to have carried radioactive waste.

The active process sewer was tied into the Treated Effluent Disposal Facility (TEDF) system in 1995 (see WIDS sitecode 600-291-PL) and by-passed the ditches. The effluent was redirected to the TEDF system at manhole Z8.

Code: 200-W-211-PL	Classification: Accepted
Names: 200-W-211-PL; 207-SL Retention Basin Sewer Pipelines; Pipelines from Boiler Annex and Pump Lift Station to 207-SL Basin; Retention Waste Sewer from 219-S and 222-S to 207-SL Basin	Reclassification: None
Type: Radioactive Process Sewer	Start Date:
Status: Active	End Date:

Description: The waste site is four underground effluent pipelines that feed the 207-SL Retention Basin (see subsites). The original feed line from 222-S laboratory to the 207-SL basin was a 20 centimeter (8 inch) vitrified clay pipeline and a 15 centimeter (6 inch) diameter vitrified clay line from 219-S. The VCP lines are encased in poured concrete. The VCP pipelines were "replaced" by inserting a 10 centimeter (4 inch) diameter fiber reinforced plastic pipe inside the original VCP lines. More recently, a 4 centimeter (1.5 inch) diameter carbon steel line from the boiler annex and a 5 centimeter (2 inch) diameter plastic pipe from a pump lift station were added and also feed the 207-SL basin.

Location: The 207-SL basin is located east of the 222-S laboratory. The three effluent lines enter the west side of the 207-SL basin.

Related Sites/ Structures: The pipelines are associated with the 222-S Laboratory, 219-S, the 222-S Boiler Annex and the 222-SA pump lift station.

This Site has the Following SubSites:

Code: 200-W-211-PL:1
Names: 200-W-211-PL:1; 8-Inch VCP and Plastic (Pipe-in-Pipe) Line from 222-S to 207-SL
Code: 200-W-211-PL:2
Names: 200-W-211-PL:2; 6-Inch VCP Line from 219-S to 207-SL Pipeline
Code: 200-W-211-PL:3
Names: 200-W-211-PL:3; 1.5-Inch Carbon Steel Line from 222S Boiler Annex to 207-SL
Code: 200-W-211-PL:4
Names: 200-W-211-PL:4; 2-Inch PVC Pipe from Pump Lift Station to 207-SL

Code: 200-W-211-PL:1	Classification: Accepted
Names: 200-W-211-PL:1; 8-Inch VCP and Plastic (Pipe-in-Pipe) Line from 222-S to 207-SL	Reclassification: None
Type: Radioactive Process Sewer	Start Date:
Status: Active	End Date:

The SubSite is Part Of:

Code: 200-W-211-PL
Names: 200-W-211-PL; 207-SL Retention Basin Sewer Pipelines; Pipelines from Boiler Annex and Pump Lift Station to 207-SL Basin; Retention Waste Sewer from 219-S and 222-S to 207-SL Basin

Code: 200-W-211-PL:2
Classification: Accepted
Names: 200-W-211-PL:2; 6-Inch VCP Line from 219-S to 207-SL Pipeline
Reclassification: None
Type: Radioactive Process Sewer
Start Date:
Status: Active
End Date:

The SubSite is Part Of:

Code: 200-W-211-PL
Names: 200-W-211-PL; 207-SL Retention Basin Sewer Pipelines; Pipelines from Boiler Annex and Pump Lift Station to 207-SL Basin; Retention Waste Sewer from 219-S and 222-S to 207-SL Basin

Code: 200-W-211-PL:3
Classification: Accepted
Names: 200-W-211-PL:3; 1.5-Inch Carbon Steel Line from 222S Boiler Annex to 207-SL
Reclassification: None
Type: Radioactive Process Sewer
Start Date:
Status: Active
End Date:

Description: A 4 centimeter (1.5 inch) diameter carbon steel line from the 222-BA boiler annex to 207-SL was installed and fed into the 207-SL Basin.

The SubSite is Part Of:

Code: 200-W-211-PL
Names: 200-W-211-PL; 207-SL Retention Basin Sewer Pipelines; Pipelines from Boiler Annex and Pump Lift Station to 207-SL Basin; Retention Waste Sewer from 219-S and 222-S to 207-SL Basin

Code: 200-W-211-PL:4
Classification: Accepted
Names: 200-W-211-PL:4; 2-Inch PVC Pipe from Pump Lift Station to 207-SL
Reclassification: None
Type: Radioactive Process Sewer
Start Date:
Status: Active
End Date:

Description: A 5 centimeter (2 inch) diameter plastic pipe is connected to 200-W-147-PL-B. It comes from a pump lift station and also fed the 207-SL basin.

The SubSite is Part Of:

Code: 200-W-211-PL
Names: 200-W-211-PL; 207-SL Retention Basin Sewer Pipelines; Pipelines from Boiler Annex and Pump Lift Station to 207-SL Basin; Retention Waste Sewer from 219-S and 222-S to 207-SL Basin

Code: 200-W-233
Classification: Accepted
Names: 200-W-233; Plutonium Finishing Plant (PFP) Treatment Unit
Reclassification: Closed Out (2/8/2005)

Type: Process Unit/Plant	Start Date: 1/1/1996
Status: Inactive	End Date: 1/1/1996

Description: The Plutonium Finishing Plant (PFP) Treatment Unit (TSD T-2-9) has been Closed Out. It was glovebox HA-20MB, located in room 235B inside the 234-5Z building.

Location: The 234-5Z building is located inside 200 West Area, near the intersection of 19th Street and Camden Ave.

Process Description: Glovebox HA-20MB supported the cementation process. Various forms of mixed waste were treated with the cementation process. Waste was mixed into standard cement material with water to form a slurry. The slurry was placed into 3 liter (0.8 gallon) billet cans and allowed to harden, creating a stable waste form.

Closure Info: Final: The glovebox was verified to be clean and the part A Permit was closed on 2/8/2005.

Code: 200-W-254	Classification: Accepted
------------------------	---------------------------------

Names: 200-W-254; 218-W-5 Trench 31 and Trench 34; Mixed Waste Trenches	Reclassification: None
--	-------------------------------

Type: Burial Ground	Start Date:
----------------------------	--------------------

Status: Active	End Date:
-----------------------	------------------

Description: Trenches 31 and 34 are active, lined trenches with leachate systems. They are designed to receive containerized and bulk mixed waste. The mixed waste trenches are constructed with a polyethylene liner.

Location: Trenches 31 and 34 are located south of the inactive 218-W-5 Burial Ground, near the intersection of 23rd St. and Dayton Ave.

Related Sites/ Structures: The active trenches are associated with the inactive 218-W-5 burial ground.

Process Description: Trenches 31 and 34 are designated as a Radioactive Mixed Waste (RMW) Land Disposal Facility. They are designed to receive containerized and bulk mixed waste.

Code: 213-W	Classification: Accepted
--------------------	---------------------------------

Names: 213-W; 213-W Compactor Facility	Reclassification: Rejected (7/10/2014)
---	---

Type: Process Unit/Plant	Start Date: 1/1/1985
---------------------------------	-----------------------------

Status: Active	End Date:
-----------------------	------------------

Description: The waste site has been reclassified to Rejected. TPA-MP-14, Rev. 2, Section 2.0 states that WIDS does not document buildings or facilities that do not contain TSD units. It further states that, after buildings are demolished, the footprint will be evaluated for potential soil contamination. If present, the soil contamination will be added to WIDS as a Discovery Site.

213-W is a pre-engineered, self-framing structure originally designed as the Dry Waste Compactor Facility. The building contains three rooms: an entry room, a package inspection room, and the computer room. The entry room opens into the compactor room through an airlock. Vehicle doors open from the compactor room to the inspection room, and from the inspection room to the building exterior.

Location: The 213-W Facility is north of the 272-WA Building and west of the 2401-W Building.

Related Sites/ Structures: Structures associated with the facility include the 213-W-1 tank, the container Products Corporation Model B60 compactor, the facility exhaust and HEPA system, sample and monitoring systems, and the other facilities making up the central waste complex.

Process Description: The Waste Compactor system was used to compact uncompressed low-level waste to approximately 10% of its original volume. The waste was compacted directly into steel burial boxes. Beginning in 1985, this process operated sporadically. Compactor operations ceased about 1994. The facility was transferred to 200 West Tank Farms in 1995. The 213-W Building is now used for equipment storage and occasionally to repair contaminated instruments.

Waste Type: Equipment

Waste Description: The unit was used to compact low-level dry waste and occasion repairs of contaminated instruments. Residual contamination on the equipment is expected.

Code: 218-W-4C ANNEX **Classification:** Not Accepted

Names: 218-W-4C ANNEX; Unused Portion of 218-W-4C Burial Ground **Reclassification:** None

Type: Burial Ground **Start Date:**

Status: Inactive **End Date:**

Description: The annex area looks like a barren field. The area designated for additional waste trenches in the western portion of the 218-W-4C Burial ground was never used.

Location: The 218-W-4C annex section is located directly south of the 234-5 building, north of 16th Street.

Related Sites/ Structures: The 218-W-4C Annex is associated with WIDS sitecode 200-W-242, which documents a small amount of debris.

Process Description: The 218-W-4C burial ground and annex were designed to contain up to 65 trenches. The main burial ground was designed to include forty-eight trenches, orientated east to west. The burial ground annex was designed to include seventeen trenches, running north to south. The burial ground annex area has never been used.

Code: 218-W-6 **Classification:** Accepted

Names: 218-W-6; 218-W-6 Burial Ground **Reclassification:** Closed Out (12/8/2011)

Type: Burial Ground **Start Date:**

Status: Inactive **End Date:**

Description: The site had been delineated with light posts and chain. It is marked with signs that say "Danger - Keep Out - Authorized Personnel Only". The area had been designated as a RCRA burial ground, but never used for that purpose. It had been listed on the RCRA Part A Permit for the Low Level Burial Grounds. This waste site was administratively Closed Out in December 2011.

Location: The site is inside 200 West Area. The site extends south from 27th Street to north of the 218-W-1A Burial Ground and east to the 218-W-3AE Burial Ground.

Code: 2607-W2 **Classification:** Accepted

Names: 2607-W2	Reclassification None
Type: Septic Tank	Start Date: 1/1/1980
Status: Inactive	End Date: 1/1/1994

Description: The 2607-W2 Septic Tank is surrounded by posts with no radiation warning signs. This system was taken out of service and formally abandoned in 1994. The drainfield lines have been cut and the septic tank was filled with soil. The drainfield had a capacity of 785 gallons (2,970 liters) per day. A gravity tie-line was installed to connect this small system to a collection that serves 2607-W1.

Location: This unit lies southwest of the main 200 West Area guard gate and southeast of the 2704-W Building.

Related Sites/ Structures: The 2607-W2 Septic Tank was associated with the 2709-W, the 2720-W and the 2701-WA Buildings.

Process Description: The 2607-W2 Septic Tank and associated drain field were designed to accept sanitary sewer effluent from the 2709-W, the 2720-W and the 2701-WA Buildings.

Waste Type: Sanitary Sewage

Waste Description: The 2607-W2 septic system is currently inactive. This site was formally abandoned and filled with soil in 1994. Prior to 1994, this unit received sanitary sewer effluent at an estimated rate of 360 cubic feet (10.2 cubic meters) per day.

Code: 2607-W6	Classification: Accepted
Names: 2607-W6	Reclassification None
Type: Septic Tank	Start Date: 1/1/1951
Status: Active	End Date:

Description: The 2607-W6 system was reconstructed in 1995. The unit has a sign correctly labeling it. A concrete structure with three metal manhole covers lies on the surface. The 2607-W6 Septic Tank is constructed of reinforced concrete and receives sanitary wastewater and sewage.

Location: This unit is southwest of the 222-S Laboratory and southeast of the MO-291. It is south of 10th Street and south of the 200 West Area fence.

Related Sites/ Structures: The 2607-W6 Septic Tank is associated with the 202-S, the 222-S, and the 2704-S Buildings and MO-037, MO-039, MO-028, MO-924, and MO-936.

Process Description: The 2607-W6 Septic Tank and associated drain field are designed to accept sanitary sewer effluent from the connected facilities (222-S, and the 2704-S Buildings and MO-037, MO-039, MO-028, MO-924, and MO-936.). Replacement of the existing system will be required by 2025.

Waste Type: Sanitary Sewage

Waste Description: The current daily flow rate for the 2607-W6 septic system is 9,300 gallons (15,100 liters). This unit received sanitary sewer effluent at an estimated rate of 603 gallons (2,285 liters) per day in 1995. This system received sanitary wastewater and sewage at an estimated rate of 1,230 cubic feet (34.8 cubic meters) per day in 1987.

Code: 2607-W9	Classification: Accepted
Names: 2607-W9; 2707-SX Septic Tank	Reclassification Rejected (7/15/2015)

Type: Septic Tank **Start Date:** 1/1/1950
Status: Inactive **End Date:**

Description: The waste site was reclassified to Rejected in 2015. A gravel surface covers the 2607-W9 Septic Tank and Tile Field. Two posts and a WIDS Sitecode sign mark the location of the tile field. The septic system was abandoned per WAC requirements in 1999.

Location: The septic tank is located northwest of the 2707-SX Change House and east of the 216-S-25 Crib. The exact location of this septic tank is not visible from the surface.

Related Sites/ Structures: The 2607-W9 Septic Tank is associated with the 2707-SX Change House.

Process Description: The 2607-W9 Septic Tank and associated tile field were designed to accept sanitary sewer effluent from the connected facilities. 2707-SX was designated as a Change House, where personnel would remove contaminated protective clothing. More recently, 2707-SX is designated as a Carpenter Shop.

Waste Type: Sanitary Sewage

Waste Description: The current flow rate to the 2607-W9 septic system is unknown. However, this unit received sanitary sewer effluent at an estimated rate of 36 cubic feet (1.02 cubic meters) per day in 1987.

Code: 2607-W10 **Classification:** Accepted

Names: 2607-W10; MO-281 and MO-438; Septic Servicing 278-WA **Reclassification:** None

Type: Septic Tank **Start Date:** 1/1/1993

Status: Active **End Date:**

Location: The 2607-W10 septic system is located west of Dayton Ave. and south of 19th Street.

Process Description: 2607-W10 septic services the 278-WA, MO-281 and MO-438 buildings.

Code: 2607-W11 **Classification:** Accepted

Names: 2607-W11; Septic Servicing MO-720 **Reclassification:** None

Type: Septic Tank **Start Date:** 1/1/1993

Status: Active **End Date:**

Location: The 2607-W11 septic system is located west of Dayton Ave. and south of 19th Street.

Process Description: The 2607-W11 septic system services MO-720.

Code: 2607-W12 **Classification:** Accepted

Names: 2607-W12; Septic Servicing MO-721 and MO-743 **Reclassification:** None

Type: Septic Tank **Start Date:** 1/1/1993

Status: Active **End Date:**

Location: The 2607-W12 septic system is located west of Dayton Ave. and south of 19th Street.

Process Description: The 2607-W12 septic system services MO-721 and MO-743.

Code: 2607-W14 **Classification:** Accepted

Names: 2607-W14; WRAP Facility Septic; 2336 Bldg. Septic **Reclassification:** None

Type: Septic Tank **Start Date:** 1/1/1995

Status: Active **End Date:**

Location: The 2607-W14 septic system is located east of the 2336 building. It is south of 23rd Street and west of Dayton Ave.

Process Description: The septic system services the WRAP facility (2336W). It has a flow capacity of 2530 gallons per day (9614 liters).

Code: 2607-W15 **Classification:** Accepted

Names: 2607-W15; Septic System for 2740W and 2620W **Reclassification:** None

Type: Septic Tank **Start Date:** 1/1/1996

Status: Active **End Date:**

Location: The 2607-W15 septic system is located west of Dayton Ave. and south of 23rd Street. It is west of the WRAP facility and buildings 2620W and 2740W.

Process Description: The septic system services the 2740W and 2620W buildings. It has a drain field capacity of 2700 gallons per day (10,260 liters).

Code: 2607-WA **Classification:** Accepted

Names: 2607-WA **Reclassification:** None

Type: Septic Tank **Start Date:** 1/1/1968

Status: Active **End Date:**

Description: The 2607-WA septic system consists of two separate septic tanks and two separate drain fields. The septic tanks currently receive sanitary wastewater and sewage. This system was upgraded to meet state requirements in 1994.

Location: This unit lies southwest of the nineteenth Street and Camden Avenue intersection and north of the Z Plant trailers MO-011, MO-244, MO-249, and MO-250.

Related Sites/Structures: The 2607-WA septic system is associated with the Hanford Patrol Facility (MO-011 and MO-244) and MO-249 and MO-250.

Process Description: The 2607-WA Septic Tanks and associated drain fields are designed to accept sanitary sewer effluent from the connected facilities.

Waste Type: Sanitary Sewage

Waste Description: The 2607-WA septic system received sanitary sewer effluent from the connected facilities. The estimated rate of waste generation was 205 cubic feet (5.83 cubic meters) per day in 1987.

Code: 2607-WB **Classification:** Accepted
Names: 2607-WB; 2607-WB Septic System **Reclassification:** Closed Out (2/26/2001)
Type: Septic Tank **Start Date:**
Status: Inactive **End Date:** 1/1/1999

Description: The site is a septic system that consists of three inactive septic tanks, one drain field, and the underground lines from connecting the tanks and drain field to the mobile offices they serviced. The septic tank was properly abandoned in 1999.

Location: The septic tanks are south of MO-016 (200 West - Z Plant Area). The drain field is south of MO-939.

Related Sites/ Structures: The septic system serviced mobile offices MO-016, MO-015, MO-017, MO-939, MO-032, MO-031. These trailers are outside of the Z-Plant fence line.

Waste Type: Sanitary Sewage

Waste Description: The system received sanitary waste from mobile offices outside of Z Plant.

Closure Info: Final: The reclassification to Closed Out is documented on form 99-104. The septic system was abandoned per the requirements of Washington Administrative Code 246-272-1851. All septage inside the tanks was removed and the empty tanks were filled to eliminate void spaces. Per an agreement with the Washington Department of Health, the septic system lids were left in place.

Code: 2607-WWA **Classification:** Not Accepted
Names: 2607-WWA; 2607-WWA Septic System **Reclassification:** None
Type: Septic Tank **Start Date:** 1/1/1955
Status: Inactive **End Date:**

Description: This site does not exist as a separate site; it is likely an alias for 2607-WL.

Process Description: Septic Tank and drain fields are designed to accept and treat sanitary sewer effluent from associated structures.

Waste Type: Sanitary Sewage

Waste Description: The 2607-WWA Septic System was reported by Cramer (1987) to have received sanitary sewer effluent at estimated rate of 3.41 cubic meters (120.4 cubic feet) per day. However, this report is likely referring to 2607-WL.

Code: 2727-WA **Classification:** Accepted
Names: 2727-WA; 2727-WA SRE Sodium Storage Building **Reclassification:** Closed Out (2/22/1999)
Type: Storage **Start Date:** 1/1/1977
Status: Inactive **End Date:** 1/1/1999

Description: The 2727-WA building was constructed to store sodium from the Sodium Reactor Experiment (SRE) reactor. It is a prefabricated Butler-type metal building with a concrete floor. All of the SRE sodium storage containers were removed in 1995. The RCRA Part A permit was procedurally Closed in 1999.

Location: The 2727-WA building is located in 200 West area, north of 16th Street and just east of the rail line.

Process Description: The sodium stored in this facility was transferred to the Hanford Site in 1977 after use by Atomics International as primary coolant in their Sodium Reactor Experiment (SRE reactor). The containers of sodium were purged of air and internally blanketed with nitrogen when filled at Atomics International. In February, 1995, the 158 sodium-filled 208-liter (55-gallon) drums were overpacked into 322-liter (85-gallon) drums and transferred to the South Alkali Metal (SAM) Storage Modules in the 200 West Central Waste Complex.

Waste Type: Chemicals

Waste Description: The sodium had been used as primary coolant in an experimental reactor and was slightly contaminated. A regulatory analysis of the sodium concluded that it was not a dangerous or mixed waste. The sodium was held in 158, 208-liter (55-gallon) steel containers.

Closure Info: Final: February, 1995, the 158 sodium-filled 208-liter (55-gallon) drums were overpacked into 322-liter (85-gallon) drums and transferred to the South Alkali Metal (SAM) Storage Modules in the 200 West Central Waste Complex. The RCRA Part A permit was procedurally closed in 1999.

Code: 216-Z-21	Classification: Accepted
Names: 216-Z-21; 216-Z-21 Seepage Basin; PFP Cold Waste Pond	Reclassification: Rejected (7/15/2015)
Type: Pond	Start Date: 1/1/1980
Status: Inactive	End Date: 1/1/1995

Description: In 2015, the site was reclassified to Rejected. In 2005, the site was evaluated and determined to require No Action. It is a large, unlined soil bermed depression. The basin is currently dry and is not radiologically posted.

Location: The site is located east of the Plutonium Finishing Plant, outside the security fence. It is southeast of the 216-Z-9 trench, on the west side of Camden Ave.

Related Sites/Structures: The site is associated with the 234-5 facility.

Process Description: The site is an unlined seepage basin that was constructed to receive PFP non-contact condensate and stormwater run off.

Waste Type: Steam Condensate

Waste Description: The 216-Z-21 basin received effluent from various sources within the Plutonium Finishing Plant, including High Tank overflow, storm drain run off, ventilation steam condensate, dry air compressor cooling water and ventilation air wash spray pans. These sources do not contain any radionuclides, organics or other waste. The storm drains carried some silt and sand.

Closure Info: Interim: The No Action reclassification is documented on form 2005-040. The 216-Z-21 basin received uncontaminated effluent from various sources within PFP, including High Tank overflow, storm drain run off, ventilation steam condensate, dry air compressor cooling water and ventilation air wash spray pans. The storm drains carried some silt and sand. The basin did

not receive any radioactive or hazardous waste.

Code: 232-Z:1 **Classification:** Accepted

Names: 232-Z:1; Building Foundation; 232-Z Facility
Concrete Slab **Reclassification** None

Type: Process Unit/Plant

Start Date:

Status: Inactive

End Date:

Description: The 232-Z above grade structures were demolished to slab on grade in July 2006. All penetrations through the floor slab were plugged with grout or a fire block material (low density silicone elastomer) prior to building demolition. The slab was painted with Polymeric Barrier System fixative, covered with gravel and posted with Underground Radioactive Material signs. Fixed contamination was identified on the sidewalk between 232-Z and 2731-ZA. The sidewalk was sprayed with a vinyl material and painted yellow. A section of asphalt south of 2736-ZC (adjacent to 232-Z) was found to be contaminated. This area was re-surfaced with asphalt. All areas were posted as Underground Radioactive Material Areas (URMA).

The SubSite is Part Of:

Code: 232-Z

Names: 232-Z; 232-Z Building Foundation; 232-Z Incineration Facility; 232-Z Incinerator; 232-Z Waste Incineration Facility

Code: 232-Z:2 **Classification:** Accepted

Names: 232-Z:2; 232-Z Underground Ventilation Duct **Reclassification** None

Type: Process Unit/Plant

Start Date:

Status: Inactive

End Date:

Description: In 2006, the 60 and 91 centimeter (24 and 36 inch) diameter underground ventilation ducting from the 232-Z Building to the 291-Z Building was filled with a controlled density fill (i.e., grout).

The SubSite is Part Of:

Code: 232-Z

Names: 232-Z; 232-Z Building Foundation; 232-Z Incineration Facility; 232-Z Incinerator; 232-Z Waste Incineration Facility

Code: 232-Z:3 **Classification:** Accepted

Names: 232-Z:3; 232-Z Underground Drain Line to 241-Z **Reclassification** None

Type: Process Unit/Plant

Start Date:

Status: Inactive

End Date:

Description: The 7.6 centimeter (3 inch) diameter underground pipeline drained to the 241-Z facility tank D-6. Water that was removed from the buried three inch drain line was sampled. The water was generally measured at less than 10⁻³ Ci/mL alpha (M2300-06-010, 232-Z Building Final Slab-On-Grade Characterization Report).

The SubSite is Part Of:

Code: 232-Z
Names: 232-Z; 232-Z Building Foundation; 232-Z Incineration Facility; 232-Z Incinerator; 232-Z Waste Incineration Facility

Code: 234-5Z HWSA **Classification:** Accepted
Names: 234-5Z HWSA; 234-5Z Hazardous Waste Storage Area **Reclassification** Rejected (9/14/2000)
Type: Storage Pad (<90 day) **Start Date:** 1/1/1985
Status: Active **End Date:**

Description: The unit consists of a portable steel building, similar to a conex box, with no windows and three doors that open to three internal bays. The conex box is located on an asphalt pad.

Location: The unit is located east of 234-5Z, along the inner security fence line, 15 meters (50 feet) east of the northeast corner of the 234-5Z Building (Z Plant).

Related Sites/ Structures: Structures related to this unit include the 234-5Z Facility and other facilities in the Plutonium Finishing Plant Complex that stage waste at the pad.

Process Description: This unit provides a temporary staging area for hazardous wastes generated in the Plutonium Finishing Plant Complex.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: The unit stores containerized hazardous waste. Examples of waste previously stored at the facility include: halogenated solvents, thinners, paints, laboratory and process chemicals, flammable liquids, polychlorinated biphenyls, and refrigerants.

Code: 2607-Z8 **Classification:** Accepted
Names: 2607-Z8 **Reclassification** Rejected (5/31/2001)
Type: Septic Tank **Start Date:**
Status: Inactive **End Date:**

Description: WIDS site 2607-Z8 was described in Hanford Site Waste Management Units Report, May 1987 as a septic tank and associated drain field. However, No drawings have been found that show this septic system. It likely does not exist.

Location: This septic system has been described as being located along the fence southeast of the 234-5Z Building.

Waste Type: Sanitary Sewage

Waste Description: According to the Hanford Site Waste Management Units Report (Cramer, 1987), this unit received sanitary sewer effluent at an estimated rate of 0.75 cubic meters (26 cubic feet) per day in 1987.

Code: 300 IFBD **Classification:** Accepted
Names: 300 IFBD; 300 Area Interim Filter Backwash Disposal **Reclassification** Rejected (1/27/1999)
Type: Depression/Pit (nonspecific) **Start Date:** 1/1/1987
Status: Inactive **End Date:** 1/1/1987

Description: This site was a temporary disposal area for filter backwash from the 300 Area Filter Water Plant. There is a large, depressed area on the east side of the Gravel Pit 6 property that forms a natural basin. There is a moderate amount of rabbit brush and grasses growing on it. There are no definite, visible signs that the area was used for backwash disposal. However, there are some truck tire tracks and evidence of some grayish, silty sand on the surface in some areas of the natural basin.

Location: The disposal area is located inside the Gravel Pit 6 property boundaries, south of the 300 Area Vitrification Test Site and west of the 300 Area. It is on the west side of Route 4 South. The depressed area believed to be the disposal site is on the east side of the property.

Process Description: The area was used to dispose of filter backwash material for four months (January through April) in 1987. Filter backwash effluent was trucked to this area.

Waste Type: Water

Waste Description: The unit received approximately 2,460,000 liters (650,000 gallons) of effluent from backwashing filters at the 300 Area Filter Water Plant (315 Building). The backwash was 90% river water. The sediment in the backwash contained alum which is used as a coagulating agent prior to filtration. Analysis of the backwash has shown it to be nonhazardous.

Code: 300 PHWSA	Classification: Accepted
Names: 300 PHWSA; 300 Area Powerhouse Hazardous Waste Storage Area; 300 Area Powerhouse HWSA	Reclassification: Rejected (1/27/1999)
Type: Satellite Accumulation Area	Start Date: 1/1/1991
Status: Inactive	End Date: 1/1/1995

Description: The site was a hazardous waste storage area used to store nonradioactive solid waste. Currently, the site is an empty chain link fenced area.

Location: The unit is located near the southwest corner of the 384 Building adjacent to roll up door 3.

Related Sites/Structures: The site was associated with the operation of the 384 Powerhouse.

Process Description: The unit was used to stage nonregulated and hazardous material. Some of the material stored here included waste oil, lubricating oil, oil soaked rags and aerosol cans.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: When active, the unit staged nonregulated waste oil and water treatment chemicals. Other small quantities of hazardous waste were also stored.

Code: 300 SE	Classification: Accepted
Names: 300 SE; Solvent Evaporator; 300 Area Solvent Evaporator; 300 ASE	Reclassification: Closed Out (6/27/1995)
Type: Evaporator	Start Date: 1/1/1975
Status: Inactive	End Date: 1/1/1985

Description: The waste site permit has been Closed. It was a RCRA treatment (TSD) unit for radioactively contaminated spent solvents generated in the fuel fabrication process at the 300 Area. The waste solvents were treated by evaporation in a Brooks Load Lugger (i.e., tank, dumpster). The

waste site consisted of a gravel area and a concrete pad.

Location: The site was located on a concrete pad and an adjacent graveled equipment area behind the 333 Building and next to the east end of the 334 Building.

Release Description: Although no formal spill report is known to exist, one spill is known to have occurred when a small hole developed in a fitting of the steam line (BHI-00012). Steam condensate collected in the evaporator until it overflowed. It was likely that the overflow spilled from the cutout side onto the northern edge of the evaporator area. It is estimated that very little, if any, solvent was released during this spill, as the bulk of the solvent being treated had a density greater than water and thus remained inside the evaporator.

Process Description: The 300 ASE was installed in the spring of 1976 and was a treatment tank (evaporator) that received barrels of accumulated solvent waste from degreasing operations associated with the N Reactor fuel manufacturing facility. Degreaser solvent barrels were routinely stored (up to 1 year) within about 6.1 meters (20 feet) of the evaporator until poured into the 300 ASE with the barrel lift/dumper. Small quantities of solvent (from the paint shop) and uranium-ethyl acetate-bromine solutions were poured by hand directly into the evaporator. Typical 300 ASE waste was composed of perchloroethylene, trichloroethylene, chloroform, ethyl acetate/bromine solution, paint shop solvents, and possibly used oil. Small amounts of uranium and alloys of copper, zirconium, and possibly zirconium/beryllium were present in the degreaser solvents as machining particulates. In 1985, the 300 ASE was phased out. The Brooks load lugger was dismantled between 1985 and 1986.

Waste Type: Chemicals

Waste Description: The unit received approximately 2,300 liters per year (600 gallons per year) of solvents and steam condensate. The solvents consisted mainly of spent trichloroethylene, perchloroethylene, 1,1,1-trichloroethane, and an ethyl acetate/bromine solution. Paint shop solvents that were potentially treated include methyl ethyl ketone, methylene chloride, and petroleum naphtha.

Closure Info: Final: The RCRA TSD was closed on 7/31/1995.

The 300 ASE closure area consisted of two sub-areas located at the south side of the 333 East Concrete Pad. One area was a concrete pad that measured about 15.2 meters (50 feet) long on the south portion of the original 333 East Concrete Pad. The second area was an adjacent gravel/soil area along the south edge of the concrete pad that measured approximately 3.1 meters (10 feet) wide by 15.2 meters (50 feet) long.

Soil samples were collected in August 1993 and analyzed, cadmium, copper and lead were found in concentrations above the Hanford Site Background levels. The results for copper in the soil ranged from 26.8 to 109 milligrams per kilogram, well below the Model Toxics Control Act (MTCA) Method B cleanup level of 3,000 milligrams per kilogram. The MTCA Method A cleanup level was used for lead because data for the Method B cleanup level calculation were not available. The soil results for lead ranged from 9.4 to 101 milligrams per kilogram, well below the MTCA Method A cleanup level of 250 milligrams per kilogram. The one cadmium result of 1.0 milligram per kilogram, was below the MTCA Method A cleanup level of 2.0 milligrams per kilogram.

Concrete core samples were collected and analyzed in April 1994.

Code: 300 SSS	Classification: Not Accepted
Names: 300 SSS; 3607; 3707; 300 Area Sanitary Sewer System	Reclassification: None
Type: Sanitary Sewer	Start Date: 1/1/1944

Status: Active**End Date:****Description:** The sewer system is comprised of underground sewer lines inside the 300 Area that connect to the City of Richland sewer system. On October 1, 1996 the 300 Area Sanitary Sewer System began to discharge to the City of Richland's sewage system. The transfer point is at a junction south of 300 Area, on George Washington Way. Various Hanford contractors have been responsible for the operation, maintenance, monitoring and reporting for the portions of the system inside the 300 Area.

Prior to 1996, the sewer was connected to septic tanks and sanitary leaching trenches located northeast of the 300 Area. The 300 Area Sanitary Sewer utilized gravity and pressure collection lines, septic tanks and leaching trenches. The original sewer system was constructed of concrete and clay pipes and was designated as the 3907 system. The system was connected to a tile field that was replaced, in 1951, by a septic tank and two leaching trenches. Additional septic tanks were added in 1975. The 300 Area Sanitary Trenches (WIDS Site 300-52) site includes two septic tanks and unlined trenches that were connected to the 300 Area Sanitary Sewer System. The 300 Area Sanitary Trenches (WIDS Site 300-52) is a "no action" site in the 300-FF-1 Operable Unit.

Location: The system is located underneath the 300 Area. The sewer sampling station is located on the George Washington Way extension, south of the 300 Area. There are two lift stations. One is located northeast of the 337 Building and the other is northeast of the 306-E Building.**Related Sites/
Structures:** Site associated with 300-52 Sanitary Trenches and 300-276.**Process
Description:** The site receives sanitary waste from throughout the 300 Area. The 300 Area Sanitary Sewer utilizes gravity flow and lift stations to send sanitary waste to the City of Richland.**Waste Type:** Sanitary Sewage**Waste
Description:** The sanitary sewer receives sanitary wastes from throughout the 300 Area.

Code: 300-12**Classification:** Not Accepted**Names:** 300-12; 325 Laboratory Diesel Fuel Tank**Reclassification:** None**Type:** Storage Tank**Start Date:****Status:** Inactive**End Date:** 1/1/1992**Description:** The tank had been located at the northwest corner of the 325 Building. It was a single underground diesel fuel storage tank. It was taken out of service and removed (including accessible piping) in October, 1992. Sampling was performed at the time of tank removal. The site currently appears as a paved area between the building and air conditioning equipment. It can be distinguished from surrounding pavement by its newer appearance.**Location:** The tank was located approximately 5 meters (17 feet) west of the northwest corner of the 325 Radiochemistry Laboratory Building.**Related Sites/
Structures:** This unit was associated with the 325 Building.**Process
Description:** The tank was used to store diesel fuel for an emergency generator located beside the 325 building.**Waste Type:** Storage Tank

Waste Description: The tank was used to store diesel fuel for an emergency generator located beside the 325 building. There are no known leaks or spills associated with this tank.

Code: 300-13 **Classification:** Not Accepted

Names: 300-13; 350 Building Release to Sanitary Sewer System **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The site is an unplanned release to the 300 Area Sanitary Sewer System. The site was discovered during routine surveillance and maintenance of the 350 Building Sanitary Sewer Lift Station. The lift station is a below grade sewage pump station accessible through a raised manhole, painted white and located in the grassy strip of land on the west side of the 350 Building between the security fence and the roadway. A gray electrical panel is located adjacent to and on the east side of the manhole. The panel houses the controls for the sewer lift pumps.

Location: The site is located northwest of the 350 Building and just south of the access roadway to the storage yard on the north side of the 350 Building. It can be identified by the electrical panel adjacent to and on the east side of the access cover for the station.

Related Sites/Structures: The site is associated with the 300 Area Sanitary Sewer System, 350 Building, 350A Building, and 350B Building.

Process Description: The lift station is used to pump sanitary wastes into the 300 Area Sanitary Sewer System. Sewage is collected from 350 Building, 350A Building, 350B Building and pumped to a sewer tie-in just north of the lift station.

Waste Type: Sanitary Sewage

Waste Description: The site was sanitary sewage contaminated by latex paint.

Code: 300-14 **Classification:** Accepted

Names: 300-14; 331 Building Animal Waste Tanks Pit **Reclassification:** Rejected (9/22/1998)

Type: Depression/Pit (nonspecific) **Start Date:** 1/1/1974

Status: Inactive **End Date:** 1/1/1977

Description: This site includes the unlined pit east of the building, a backwash storage tank, and six diversion chambers that are located north of the pit. Originally, the animal waste collection tanks were located in a pit just east of the 331-D Animal Waste Treatment Building. The pit is 28.0 meters (92 feet) by 22.3 meters (73 feet) and approximately 7.6 meters (25 feet) deep. The sides of the pit slope about 30 degrees. The tanks have been removed. Eight concrete tank pedestals remain at the bottom of the pit. A stairway leads to the bottom of the pit. A backwash storage tank remains between the 331-D building and the pit. Water was observed at the bottom of the pit. Six diversion chambers for the sewer system are located northwest of the pit.

Location: Using the Cypress Street entrance to the 300 Area, the site is located on the right side of the street within the 331 Complex.

Related Sites/Structures: The site is related to the Animal Waste Sewer and 331-D Complex.

Process Description: The 331-D Animal Waste Treatment Facility consists of a semi-high bay, prefabricated, metal Butler building erected on a concrete slab. It contained a 94,625 liters (25,000 gallon) per day capacity waste treatment plant that operated to chemically treat, mechanically flocculate and settle, and then gravity filter animal wastes. A sludge dryer also was installed to heat and dry 54.4 kilograms (120 pounds) per hour of sewage sludge product from the treatment facility and to produce a 65 to 100% waste material that could be buried in the 100 and 200 Area trenches. The animal waste collection tanks located in a pit just east of the 331-D building were associated with this process. This treatment facility was needed because hog hairs, sawdust, and undigested animal feed frequently plugged the unlined animal waste pit located along the Columbia River.

Waste Type: Animal Waste

Waste Description: Animal waste from the 331 Complex were routed through the animal waste sewer to the 331-D animal waste treatment facility.

Code: 300-17 **Classification:** Not Accepted

Names: 300-17; 331 Building Trench; 331-D Ditch; Outfall A **Reclassification:** None

Type: Ditch **Start Date:**

Status: Active **End Date:**

Description: The site is a ditch that runs from the southeast corner of the 331-D Building to the top of the west bank of the Columbia River. The ditch is fed by an underground pipe which drains stormwater from the roadway between the north side of Building 331-C and the south side of Building 331. The open trench is piped to a culvert passing beneath a gravel roadway and the perimeter fence. The discharge is approximately 46 meters (150 feet) from the river. The bank is moderately sloped with natural vegetation. This outfall results from non-industrial sources. The site has a natural berm at the fence line. No erosion is evident on the sloping bank.

Location: The ditch is located in the 300 Area, in the southeast corner of the 331 Complex, between the 331-D and 331-E Buildings.

Process Description: The site collects sediment and runoff from storage yards and loading docks.

Waste Type: Stormwater Runoff

Waste Description: The waste is stormwater runoff from the roadway between the 331 and 331-C Buildings.

Code: 300-19 **Classification:** Accepted

Names: 300-19; 324 Building Sodium Removal Pilot Plant; 324 Sodium Removal Pilot Plant **Reclassification:** Closed Out (6/9/1997)

Type: Process Unit/Plant **Start Date:** 1/1/1979

Status: Inactive **End Date:** 1/1/1987

Description: The Sodium Removal Pilot Plant consisted of a reaction vessel, a nitrogen gas supply, a steam supply, and equipment for decontamination studies. The reaction vessel was decommissioned and removed in 1991. The RCRA Part A Permit Application was procedurally Closed on June 6, 1997.

Location: The unit was located within room 146 of the 324 Building, Chemical Materials Engineering Laboratory.

Related Sites/ Structures: Structures associated with the unit include the 324 Highbay, the highbay crane, plumbing, and pressure vessels.

Process Description: The unit has been inactive since 1987. From 1983 to 1987 the unit was used to clean and decontaminate test equipment, reactor components, and other sodium contaminated parts. Before 1983 the system was used to treat small amounts of alkali metals for research and development and to perform equipment decontamination.

Waste Type: Chemicals

Waste Description: Decontamination and research and development activities generated liquid effluents that contained radionuclides and sodium hydroxide. The sodium hydroxide was neutralized prior to discharging the solution to a crib.

Closure Info: Final: The RCRA Part A Permit Application was procedurally closed on June 6, 1997. The reclassification was documented on form 98-68.

Code: 300-21	Classification: Not Accepted
Names: 300-21; 333 Building Underground Limestone Tank	Reclassification: None
Type: Neutralization Tank	Start Date:
Status: Inactive	End Date: 1/1/1973

Description: The site was an underground storage tank that held limestone used to neutralize acid wastes. The Waste Acid Treatment System (WATS) Limestone Neutralization Tank leaked in 1973 and was removed.

Location: The tank was located east of the 333 Building and north of the 334 Tank Farm. The 334A Building was built where the tank had been located. The tank was located within the 618-1 Burial Ground (WIDS Site 618-1).

Release Description: The release to the soil is described in the Releases Section. The release site (WIDS Site UPR-300-13) is a separate waste site.

Related Sites/ Structures: The site is associated with the 333 Building process etch facilities and the associated drain lines (WIDS Site 300-219), Tank 4 in the 334 Tank Farm (WIDS Site 334 TFWAST), the 334-A Facility, and the process sewer. The site is also associated with UPR-300-13, a release to the soil of waste etch acid solution.

Process Description: Prior to mid-1971, the majority of the concentrated chemical wastes from the 333 Building chemical tanks were transferred via polyvinyl chloride (PVC) drain lines in the pipe trench to this 14,380 liter (3800 gallon) plastic-lined, steel tank full of limestone. The waste etch acid solutions were sprayed over the top of the limestone and the neutralized acid waste drained from the bottom of the tank into the process sewer. Limestone was added to the top of the tank during the week as needed. The acid-limestone contact time was increased in 1971 by batch transfers to the tank to maintain at least a 12 hour holdup prior to draining to the process sewer. From late 1971 to August 1973, in an effort to further reduce chemical waste disposal within the 300 Area, the underground limestone neutralization tank was converted to a catch tank to collect and pump batches of waste etch acid to Tank 4 in the 334 Tank Farm. Tank 4 (WIDS Site 334 TFWAST), a 22,710 liter (6000 gallon) elevated tank, was used to store the waste acid solution and to transfer batches of the waste acid solutions to a neutralization tank (WIDS Site 313-TK-2) in the 313 Uranium Recovery Room.

The 334-A Facility was built to replace the failed tank. The collection of batches of waste etch acids in the 334-A Facility catch tanks (WIDS Sites 334-A-TK-B and 334-A-TK-C) started in January 1975. The process for neutralization of the waste etch acids in the 333 waste acid neutralization tank continued from January 1975 until the 333 N Fuels Fabrication processes were shutdown in about 1988.

Waste Type: Equipment

Waste Description: The waste was a tank containing limestone used to neutralize acid waste. The tank was removed in 1973.

Code: 300-23

Classification: Accepted

Names: 300-23; 309-1 UST; PRTR Diesel Storage Tank

Reclassification: Closed Out (10/24/1996)

Type: Storage Tank

Start Date: 1/1/1959

Status: Inactive

End Date: 1/1/1969

Description: The waste site is an underground storage tank that has been removed and the trench backfilled. The tank held diesel fuel used to power the Plutonium Recycle Test Reactor (PRTR) emergency generator located inside the 309 Building.

Location: The tank was located approximately 6.1 meters (20 feet) south of the 309 building and next to the main entrance of the 309 building.

Related Sites/ Structures: The associated structure was the Plutonium Recycle Test Reactor (PRTR), 309 Building.

Waste Type: Storage Tank

Waste Description: The waste was the abandoned underground storage tank (UST). Residual diesel fuel and water remained in the tank.

Closure Info: Final: A site assessment was conducted following the guidance from the Washington State Department of Ecology, Guidance for Site Checks and Site Assessments for Underground Storage Tanks. The objective was to determine if a release of diesel fuel had occurred prior to the tank being abandoned. The assessment is described in Site Assessment Report for the 309-1 Underground Storage Tank (UST), correspondence control number 036527. The tank was excavated and examined for potential leaks. No discolored soil was observed. There was no groundwater in the tank excavation. The results of the site assessment indicated that a confirmed release of a regulated substance had not occurred.

Code: 300-25

Classification: Accepted

Names: 300-25; 324 Building; Waste Technology Laboratory

Reclassification: Rejected (7/10/2015)

Type: Laboratory

Start Date: 1/1/1966

Status: Inactive

End Date:

Description: The 324 Building is an abovegrade structure and does not meet the definition of a waste site. The 300-25 site has been reclassified to Rejected. The contaminated soil beneath the building is WIDS sitecode 300-296.

Portions of the Building were covered under a RCRA Closure Plan with on-going closure activities in progress. The RCRA Closure Plan covers the REC portion of the building,

including the hot cells, low level and high level vault tanks, the airlock and pipe trench. See DOE/RL-96-73, Rev. 1 (3-98) for additional details. In July of 1999, the Washington State Department of Ecology identified the following as areas of interest for this facility: - 324 Shielded Material Facility (SMF) South Cell - 324 Shielded Material Facility (SMF) East Cell - B-Cell (Hot Cell) - A-Cell (Hot Cell) - C-Cell (Hot Cell) - D-Cell (Hot Cell) - Hot Cell Airlock (Hot Cell) - High-Level Vault (4 tanks) - Low-Level Vault (4 tanks) - 324 Process Sewer System (WIDS site 300-15) - 324 Retention Process Sewer System (WIDS site 300-214) - EDL-102 (PNNL Vitrification Pilot) - High Bay (2 tanks with heels) - Room 146 (Fume hood - melter) - Room 3B, 3F (Laboratory and Rad Flume Hood), and Storage Vault - Waste Water Diverter System, Catch Tank and Ion Exchange Tank - HNO₃ Bulk Chemical Tank - West Side of Facility. The areas listed above included in the closure plan are: B-Cell (Hot Cell) - A-Cell (Hot Cell) - C-Cell (Hot Cell) - D-Cell (Hot Cell) - Hot Cell Airlock (Hot Cell) - High-Level Vault (4 tanks) - Low-Level Vault (4 tanks).

Location: The 324 building is in the central part of the 300 Area, northeast of the 309 Building and immediately east of the 308 Building.

Release Description: On 11/16/10, a cone penetrometer (an enclosed pipe pushed into the soil by a hydraulic ram) was used to identify the presence of radioactive material in the soil approximately 3.5 feet beneath the 324 Building near the B-cell. A maximum radiation readings of 6,700 R/hr. was identified. The 324 Building is a Nuclear Category 2 facility, currently undergoing deactivation and decommissioning. The 324 Building was constructed in the 1960s to support materials and chemical process research and development activities, and ceased research operations in 1996. The primary operational system remaining in the building is ventilation. In preparation for removal of B-cell, historical research and on-site investigation identified evidence of a potentially breached liner in the sump floor. A leak may have occurred at some point in the operational past of the cell. The 300 Area is posted as an Underground Radioactive Material (URM) Area. This event is being reported as a Management Concern due to the unexpected very high levels of radiation. (See sitecode 300-296)

Related Sites/ Structures: The 324 Building has been isolated from the RLWS by installing a blank in the diverter valve. The pipes going from Tanks 102 and 177 to the 324 RLWS were cut and capped. The main 324 pipe that connected with the 340 Facility pipe has been cut and capped. The 324 building is associated with Unplanned Release 300-296.

Process Description: The 324 Building was designed and constructed to allow for a high degree of versatility in completing complex and varied experimentation on highly radioactive wastes developing approaches for waste treatment and storage activities. The building was designed as a single integrated facility for orderly progression of nonradioactive and radioactive development studies from laboratory or bench-scale to full engineering-scale pilot plant demonstrations. The facility houses radiochemical and radiometallurgical hot cells and laboratories. The facility supported several DOE/RL related initiatives for highly radioactive chemical processing and metallurgical engineering studies. As a result of residues and internal facility spills during the conduct of these activities, the facility contains areas with significant fixed and dispersible mixed waste contamination.

Waste Type: Equipment

Waste Description: Currently, the facility is undergoing deactivation to address radiological and chemical contamination remaining in the facility. The waste is contaminated equipment that is being removed from the facility, packaged, and transported to the 200 Area for burial.

Code: 300-26

Classification: Accepted

Names: 300-26; 384 Powerhouse #6 Fuel Oil Spill; Delivery Truck Spillage on Roads; Powerhouse Fuel Oil Spill

Reclassification Rejected (1/27/1999)

Type: Unplanned Release

Start Date: 1/1/1991

Status: Inactive

End Date: 1/1/1991

Description: The site was an unplanned release. The area of the release was previously used as a coal pile for the 384 Powerhouse. The soil is stained dark from coal dust. There is no visible evidence of the #6 fuel oil spill in the area. On the south side of the site adjacent to Apple Street there is an Underground Radioactive Material sign, and a buried gas pipeline.

Location: The site is located on the east side of the 384 Powerhouse, just south of the 366 Fuel Oil Bunker, at the refueling area.

Release Description: After refueling of the 366 Fuel Oil Bunkers, an offsite vendor's fuel oil truck spilled #6 fuel oil during departure onto the gravel and paved road. The driver stated that he had left a siphon tube valve cracked open which released the fuel oil to the ground. The date of the spill was December 31, 1991.

Related Sites/ Structures: The site is associated with the 384 Powerhouse and 366/366A Fuel Oil Bunkers (WIDS Site 300-6).

Waste Type: Oil

Waste Description: The waste is #6 fuel oil contaminated soil and gravel. The release occurred on December 31, 1991. The occurrence report does not contain an estimate of the volume. There is no information on the extent of the spill. The leak was not discovered until after the truck left the job site.

Code: 300-27

Classification: Accepted

Names: 300-27; Soil Contamination at 329 Biophysics Laboratory

Reclassification: Rejected (2/12/1999)

Type: Unplanned Release

Start Date: 1/1/1991

Status: Inactive

End Date: 1/1/1991

Description: Radioactive contamination was found at the site during a routine survey on August 14, 1991. The site is an area of crushed rock gravel with no vegetation located near the outside wall of the 329 Building. There are no hazard postings at this location. There is no visible evidence of radioactive contamination that was removed from this site. A cement pad with a liquid argon tank has been constructed adjacent to the site.

Location: The contamination was found in soil just west of Door 12 on the northeast section of the 329 Building.

Release Description: During a routine radiation survey outside of the building on August 14, 1991, a Radiation Protection Technologist (RPT) found radioactive contamination levels of approximately 40,000 disintegrations per minute (dpm) beta-gamma in a one square foot area of soil. Pacific Northwest Laboratory (PNL) was unable to identify the source of the contamination. The contamination was not found during a prior survey in 1990. This site was found within several feet of the outer wall of the 329 Biophysics Laboratory. The source of the contamination is unknown.

Waste Type: Soil

Waste Description: The waste was contaminated soil that was later cleaned up.

Code: 300-30

Classification: Accepted

Names: 300-30; 3705 Photography Building

Reclassification Rejected (1/27/1999)

Type: Process Unit/Plant

Start Date: 1/1/1963

Status: Inactive

End Date:

Description: The 3705 Photography Building was demolished in June 2006. The 3705 Building was a rectangular, one-story concrete block building erected on concrete footings and a slab-on-grade concrete floor. A corrugated metal sided mechanical room penthouse had been erected on the building roof. The roof itself was flat and is covered with built-up tar and gravel. The building contained no windows. Interior partitions were either gypsum wall board on stud frames or movable metal. Utilities serving the building included sanitary water and sewer, compressed air, process water, and electricity. The building was connected to the process sewer, but all connections were capped when the building was remodeled, probably between 1988 and 1990. The capped process sewer connection for the silver reclamation process is located behind a sheet rock wall that has been marked with an identification sticker.

Location: The 3705 Photography Building was inside the 300 Area, just north of the Apple Street Gate. It is on the west side of Alaska Street.

Related Sites/ Structures: The site is associated with the 300 Area Sanitary and Process Sewers (WIDS Sites 300 SSS and 300-15) and the 3746-D Silver Reclamation Process Facility (WIDS Site 3746-D SR).

Process Description: From 1963 through the early 1970's, the building was used to process personnel dosimetry badges and meters. Various radioactive sources were kept and used at the facility. In 1968, a 1.96 microcurie americium-241 source was found to be ruptured and the contamination was subsequently cleaned up (See Releases Section). Since the early 1970's, the facility has provided photographic services, including still camera assignments, color slides work, contract printing, and black and white or color enlargements. Within the facility is the silver reclamation unit that is used to treat the spent photoprocessing chemicals to recover silver for recycling. During the silver reclamation process, liquids from film processing are run through a chemical recovery column (CRC) that precipitates out silver. The building use to be connected to the process sewer and the sanitary sewer. All process sewer connections were capped when the building was remodeled, probably between 1988 and 1990. The silver depleted liquid effluent produced from the silver reclamation process is a nonregulated, nonhazardous waste that is no longer discharged to the sanitary sewer. It is collected in 114 liter (30 gallon) drums and then sent offsite for disposal. The silver enriched CRC's are treated as recyclable material and periodically sent to a refiner for processing. Washwater and overflow from the developers is sent to the City of Richland sanitary sewer. Prior to 1998, this waste stream went to the 300 Area Sanitary Sewer Trenches (WIDS Site 300 SSS).

Waste Type: Chemicals

Waste Description: The waste is spent photo processing chemicals. Prior to silver reclamation, the chemicals designate as a hazardous waste. After the silver reclamation, the solutions are nonregulated and nonhazardous. The treated solutions are disposed of offsite. The recovered silver is shipped offsite for recycling. Additional waste is nondangerous/nonhazardous washwater and overflow from the film developers that goes to the City of Richland sanitary sewer system.

Code: 300-35

Classification: Accepted

Names: 300-35; 3706A Fuel Storage Tank

Reclassification Closed Out (2/12/1999)

Type: Storage Tank

Start Date:

Status: Inactive

End Date:

Description: The site is an abandoned underground fuel storage tank that has been reclassified to Closed

Out. The tank was pumped and abandoned in place. A 0.51 meter by 0.51 meter (1.7 feet by 1.7 feet) concrete block and sign, at the tank fill connection location, marked the location of the underground tank. The sign read "EMPTY 300 GALLON UNDERGROUND DIESEL FUEL TANK LOCATED HERE. CONTACT MAINTENANCE Environmental Services South (376-7210) for information".

- Location:** The tank marker is located 1 meter (3.3 feet) from the south wall of the 3706-A Building and 6.1 meters (20 feet) west of the southeast corner of the building.
- Release Description:** A review of the facility operating history did not reveal any reported instances of diesel spills. It is anticipated that the normal trace amounts of diesel near the filler connection may be present.
- Related Sites/ Structures:** The site is associated with the emergency generator.
- Process Description:** The underground diesel fuel storage tank was used to support emergency generator operations for heating, ventilation, and air conditioning (HVAC).
- Waste Type:** Storage Tank
- Waste Description:** The waste is an abandoned underground fuel storage tank that was pumped out and closed in place.
- Closure Info:** Final: The tank was pumped and closed in place. A message on 2/10/1995 from Ted Wooley of the Washington State Department of Ecology says "It appears that the information provided would allow exemption (e.g., abandonment or closure prior to December 22, 1988) under WAC 173-360." A second email on 3/15/1995 says that "After re-evaluating the data, Ecology agrees that the appropriate disposal steps were taken with the waste water collected. Moreover, closure of the tank in place can serve as final closure of the tank."

The reclassification to Closed Out is documented on from 99-03.

-
- | | |
|--|-------------------------------------|
| Code: 300-36 | Classification: Not Accepted |
| Names: 300-36; 384 Powerhouse Oil Release to French Drain | Reclassification: None |
| Type: Unplanned Release | Start Date: 1/1/1995 |
| Status: Inactive | End Date: 1/1/1995 |
- Description:** The site was an unplanned release to a french drain. The french drain received condensate return from the steam heating system that went to the fuel oil bunkers. The french drain is a 0.65 meter (2.13 feet) diameter drain with a rust colored lid. Although gravel around the drain is slightly stained, it is most likely caused from normal steam condensate activity.
- Location:** The oil release was observed in a french drain located north of the 366 Pumphouse, just east of the railroad tracks.
- Release Description:** On August 2, 1995, a french drain north of the 366 Building was observed by operations personnel to be overflowing. When the employee lifted the drain lid, oil was noted floating on top of the water. Since the source of the water in the drain was condensate return from the oil bunker steam heating system, the oil indicated a tube bundle failure. Response included isolating the steam to the underground fuel oil bunkers and removing the oil contaminated rocks and soil. Oil in the french drain was also removed. Clean dirt was used to backfill the area where material was removed.
- Related Sites/ Structures:** The release is associated with the french drain known as WIDS Site 300-122 (Miscellaneous Stream #344) and the 366/366A Fuel Oil Bunkers (WIDS Site 300-6).
-

Process Description: The oil bunkers were heated with steam to keep the oil viscous enough to be pumped.

Code: 300-37 **Classification:** Accepted
Names: 300-37; PCB Leak to Soil Adjacent to 335A **Reclassification:** Rejected (8/15/2013)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: Reclassification form 98-231 documents the reclassification to Closed Out. The reclassification status was changed to Rejected in 2013 because the PCB material had been properly dispositioned under TSCA. The site was a polychlorinated biphenyl (PCB) leak that contaminated the soil. The leak originated from a rectifier located on a concrete pad outside of the 335-A Building. The rectifier was installed in the early 1970's, but was never activated. The tank was drained and the concrete was removed in 1993 and 1994, before the TPA-MP-14 process was established.

Location: The site is located in the 300 Area, in a gravel area on the north side of building 336. The site is located inside a fenced area, with the gate open.

Release Description: The polychlorinated biphenyl (PCB) leakage was first identified in April 1993 by the Electrical Utilities personnel. The leakage was observed at two fittings, one being the lower drain valve located near the edge of the concrete pad. The leaks appeared to be small and old, presumably pre-1987. The leaking fittings were covered over with a dirty grease-like coating. There was no visual evidence of oil on the concrete pad or soil surrounding the pad. In addition, there was no distinctive PCB odor at the leak site. The site was immediately roped off and plans for removal of the PCBs were initiated.

Related Sites/ Structures: The site was associated with a rectifier, which has been removed.

Waste Type: Oil

Waste Description: The waste was soil contaminated with polychlorinated biphenyls.

Closure Info: Final: The rectifier was drained on August 2 and 4, 1993. The fluid contained a PCB level of 680,000 parts per million. The amount of oil in the rectifier at delivery was indicated on the unit at 6,113 liters (1,615 gallons). The amount of fluid removed, approximately 5,867 liters (1,550 gallons), was consistent with the fill data provided on the unit. The 246 liter (65 gallon) differential is typical of the quantity of oil that can not be removed from the rectifier cooling coils. This fluid and the drained rectifier were shipped off site to a licensed PCB disposal facility. After removal of this material, the concrete pad was smeared and PCB contamination of 12,000 parts per million was found in the area below the suspect fittings.

On July 19, 1994 the concrete pad was removed, packaged into drums and shipped off site for disposal as PCB contaminated waste. Crews also removed soil, approximately 2.4 meters by 2.4 meters by 0.3 meters (8 feet by 8 feet by 1 foot) deep, and sampled this soil for PCBs. The soil was also visually inspected during removal. There was no visual evidence of oil in the soil, nor was the distinctive PCB odor present.

The activity occurred in 1993 and 1994, prior to the establishment of the TPA-MP-14 process.

The PCB Case Reviewer for the EPA (Environmental Protection Agency) agreed that appropriate action had taken place, and from a Toxic Substances Control Act (TSCA) standpoint, regulations were met as long as the soil was less than 10 parts per million PCBs at a

depth of 25 centimeters (10 inches) below the surface.

Code: 300-39	Classification: Accepted
Names: 300-39; 309 Building Ex-Vessel Irradiated Fuel Storage Basin; 309 Building Irradiated Fuel Storage Basin; 309 Fuel Storage Basin	Reclassification: Rejected (8/13/2013)
Type: Storage	Start Date: 1/1/1960
Status: Inactive	End Date: 1/1/1974

Description: The fuel storage basin is considered a component of the 309 facility and was Reclassified to Rejected in 2013. The Fuel Storage Basin had been emptied. All fuel handling and storage equipment have been removed. Gates, stoplogs and fixtures have been removed and all that remains are studs where the equipment was located. The basin has been covered with a plywood, sheet metal and metal grating cover supported by channel iron. This cover made it impossible to check the basin overflow drain system to see if they have been plugged. The Fuel Storage Basin is "L" shaped and may be described as having two sections. The largest section is the Fuel Storage Basin which runs north/south and was the first pit built; the pit is 40 feet (12.2 m) long, 20 feet (6.1 m) wide and 34 feet (10.4 m) below grade. The other section is the Loadout Facility which has two sections that run east/west and are smaller than the original basin and were built as the first basin reached capacity; one basin is 7.9 meters (26 feet) long, 1.5 meters (5 feet) wide, and 7.9 meters (26 feet) below grade and the other is 7.3 meters (24 feet) long, 2.4 meters (8 feet) wide, 7.9 meters (26 feet) below grade. The ion vault and the truck bay are located at the east end of the Loadout Facility.

Location: The site is located inside the 309 building, in the east wing and south of the PRTR Reactor Cell. Rooms 404A, 404B, and 405 are located directly above the Fuel Storage Basin.

Related Sites/Structures: The Fuel Transfer Pit and it's associated structures (Hoist Pit, Sluice Gate Operating Stand, and Drain) are located inside the 309 PRTR containment dome. The Ion Vault and Truck Bay are located within the Fuel Storage Basin. Facility drawing H-3-14950 indicates two overflow drain systems, neither of which is believed to be plugged at the basin. One drain system goes into PRTR tank farm tank TW-3. The SP-100 project cut the drain line in the area underneath where the dump heat exchangers were located in the 1986-1988 timeframe. The other drain system goes into the 300 Area process sewer via manholes MH-4 and MH-1A. Lines in MH-1A were plugged in 1996. The drawings also indicate two cells on the eastern-most end of the expansion basin that contained water purification equipment for the basin and a truck lock. The truck lock allowed a truck to back into the basin area for fuel load out. UPR-300-5 is a spill associated with this site.

Process Description: The main air lock from the reactor containment vessel opens into the storage basin area which is the point of connection of the service building and reactor containment vessel. An under water fuel transfer opening between the containment vessel and the storage basin permitted irradiated fuel elements to be moved to the basin for storage or "green fuel" to the reactor for recharging. A fuel element loadout facility adjoins the storage basin area on the east side. It is from this facility that elements were loaded in shielding casks and shipped to the 327 Building or the 200 Area by truck.

Waste Type: Equipment

Waste Description: The waste is radioactively contaminated equipment and structures.

Code: 300-42	Classification: Not Accepted
---------------------	-------------------------------------

Names: 300-42; 306E Fabrication and Testing Laboratory **Reclassification** None

Type: Fabrication Shop **Start Date:**

Status: Inactive **End Date:**

Description: The 306E Development Fabrication Test Lab was demolished in January 2007 (per D4-300-004 Rev. 1). The waste site was the 306E Building. The area around the 306E building is paved and posted as Underground Radioactive Material Area.

The building had been occupied by COGEMA and used for instrument development and Computer Aided Design (CAD) support.

Location: The 306E Building was on the north side of Ginko Street, in the northeast corner of the 300 Area.

Release Description: See WIDS Site 300-256 for a description of releases to the soil beneath the 306E Facility.

Related Sites/Structures: The site is related to the 306W building, 313 Building, 333 building, 300 Area process sewer, 300 Area sanitary sewer, and WIDS Site 300-258, Abandoned Pipe Trench Between 334 Tank Farm and 306E. Contamination beneath this facility is documented as WIDS Site 300-256. Contamination beneath the adjacent 306W Metal Fabrication Development Building is documented as WIDS Site Code 300-33.

Process Description: The original 306 Building was completed in 1956 and named the Fuel Element Pilot Plant. The facility was constructed to support the 313 Building operations. It was expanded in 1960 to contain the co-extrusion fabrication processes for N Reactor fuels fabrication. In 1972, the east half, the new half, was designated as 306E and that portion of the building became the Hanford Engineering Development Laboratory (HEDL) operated by Westinghouse Electric Corporation. The west portion of the building, which is older, was named 306W and was allocated to Pacific Northwest Laboratories (PNL).

Code: 300-47 **Classification:** Not Accepted

Names: 300-47; Residual Hazardous Substances Northwest of 3708 Building **Reclassification** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:** 1/1/1989

Description: During the demolition of the 3708 facility, the 300-47 WIDS site location was removed. No visual evidence was found of potential contamination at the 300-47 site during removal of the 3708 building foundation concrete slab. The site was identified as two locations of potential contamination near the 3708 Building that resulted from tank leakage. The area around the 3708 Building is not currently posted for contamination and there is no evidence of underground tanks. The area is partially paved with asphalt, and otherwise surfaced in crushed gravel. There are no markers where the chemical tank and the oil tank were located.

Location: The site is located in 300 Area just off the northwest corner of the 3708 Building.

Release Description: No releases have been identified.

Related Sites/Structures: The two areas of potential contamination are associated with the 3708 Building.

Process Description: The tanks were chemical holding tanks containing waste from floor, shower, and sink drains in the 3708 Building, and an underground oil storage tank.

Code: 300-55 **Classification:** Accepted
Names: 300-55; 307-D; 309 Rupture Loop Holding Tank; **Reclassification** Rejected (2/24/1999)
 RLT-2; Rupture Loop Hold-Up Tank
Type: Storage Tank **Start Date:** 1/1/1960
Status: Inactive **End Date:**

Description: The tank was an underground storage tank, 12.2 meters (40 feet) in diameter and 3.05 meters (10 feet) tall with a sloping top.

Location: The Rupture Loop Holding Tank was located approximately 61 meters (200 feet) northeast of the 309 Facility and southwest of the 324 building.

Related Sites/ Structures: The site was related to the 309 Building, Rupture Loop Annex (Room 20), valve pit and piping. There were two piping runs that were connected to the tank. For contaminated material, a 7.6 centimeter (3 inch) pipe ran to the 340 Complex, and for uncontaminated material, a pipe ran to the Columbia River (See WIDS Site 300-257).

Process Description: Liquid waste routed to this tank was sampled. If it was contaminated it was sent to the 340 Complex through a 7.6 centimeter (3 inch) underground pipeline. If the waste was not contaminated, it was diverted to the Columbia River via a 1 meter (3 foot) diameter outfall line.

Waste Type: Equipment

Waste Description: The waste was a tank.

Code: 300-56 **Classification:** Accepted
Names: 300-56; 306-E 90-Day Waste Accumulation Area **Reclassification** Rejected (1/27/1999)
Type: Storage Pad (<90 day) **Start Date:**
Status: Inactive **End Date:**

Description: The site is a steel storage container designed to contain hazardous materials or waste. The site was previously used as a 90 day waste storage area. The site is currently in use as a hazardous material storage area. Materials currently stored include laboratory chemicals, a 208 liter (55 gallon) drum for waste oil recycling, and 320 kilograms (700 pounds) of peanut butter (sludge simulant).

Location: The site is located approximately 20 meters (65 feet) north of the northeast corner of the 306E Building in the 300 area.

Release Description: The material was/is contained within a storage cabinet. No information has been provided related to any potential spills at the site.

Related Sites/ Structures: The site stores hazardous materials or waste from the 306E building.

Waste Type: Misc. Trash and Debris

Waste Description: The site received waste from the 306E building.

Code: 300-57 **Classification:** Accepted

Names: 300-57; 335 Building 90-Day Waste Accumulation Area **Reclassification** Rejected (8/15/2013)

Type: Storage Pad (<90 day) **Start Date:** 1/1/1994

Status: Inactive **End Date:** 1/1/1998

Description: The site has been a 90 Day waste accumulation area. It was reclassified to Closed Out in 1999. In 2013, the reclassification was changed to Rejected, based on the definition that 90 Storage Pads are outside the scope of WIDS. It was a small cinder block room addition on the west side of the 335 Building. The exterior door was locked and labeled "90 Day Storage Accumulation" and "Danger".

Location: The site is located in the southeast portion of 300 Area, east of the 324 Building.

Related Sites/ Structures: The site was related to the Fast Flux Test Facility (FFTF).

Waste Type: Equipment

Waste Description: The 90 Day Waste Storage Accumulation Area was used to store sodium contaminated piping and components after dismantling, prior to shipment for disposal.

Closure Info: Final: The facility contact stated that the room was emptied on 9/30/1998. There are no future plans to store waste in this area.

The Reclassification to Closed Out is documented on form 98-174.

Code: 300-58 **Classification:** Accepted

Names: 300-58; 305B Steam Condensate Injection Well; Miscellaneous Stream #449 **Reclassification** Rejected (9/2/1998)

Type: French Drain **Start Date:**

Status: Inactive **End Date:**

Description: The site is a french drain, identified as miscellaneous stream #449, was properly decommissioned in 2007. The unit was a concrete pipe that is flush with the ground surface, and filled with cobbles and sand. No pipes to the drain are visible. The "Inventory of Miscellaneous Streams", Revision 3 says the site is inactive, source abandoned.

The french drain could also drain stormwater from nearby asphalt roads in very heavy rain. The original purpose of the site was likely to have been used for steam condensate. The soil and rocks are rust stained showing evidence of its use as a steam condensate drain. In addition, a steam line is located over the site. Although stormwater may enter the site, it is not necessarily conveyed to it.

Location: The site is located 3.01 meters (10 feet) from the southwest corner of 305B Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

**Waste
Description:**

Code: 300-59	Classification: Accepted
Names: 300-59; 305 Building Steam Condensate; Miscellaneous Stream #417	Reclassification Rejected (12/15/1998)
Type: Injection/Reverse Well	Start Date:
Status: Inactive	End Date: 1/1/1998

Description: The top 1 meter of the drain structure was removed and backfilled in 2006. It was an injection well covered by a 1.29 meter (4.23 foot) metal lid. The lid was labeled "Confined Space." The lid was flush with the ground surface and is surrounded by soil and rocks. According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive, source abandoned.

Location: This site is located between the 305 Building and 305-BA.

**Related Sites/
Structures:** This site is associated with the 305 Building.

**Process
Description:** Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

**Waste
Description:** When the site was active, it received less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

Code: 300-60	Classification: Accepted
Names: 300-60; 303A Building Steam Condensate; F.D. #26; Miscellaneous Stream #339	Reclassification Rejected (2/12/1999)
Type: Injection/Reverse Well	Start Date:
Status: Inactive	End Date:

Description: The drain was decommissioned in 2012. The site was described as an injection well that receives steam condensate. This stream site was on the east side of the 303A Building, near the northeast corner. A condensate return pipe extends from the building at this point. The area next to the building was dug up when an electrical system was installed, which would explain why there is no evidence of the site at this point. The "Inventory of Miscellaneous Streams," Revision 3, describes the site as active. However, the overhead steam line terminates and is capped at the north edge of the 3717B Building. 303A is posted "Radiation Area and Radioactive Material Area" and "Caution, Fissile Materials." The roof of 303A is posted "Contamination Area." 304 is posted "Fixed Contamination Area."

Location: The site is located east of the 303A Building and near the northwest corner.

**Related Sites/
Structures:** The site is associated with the main 300 Area steam line.

Process Description: Steam is produced from sanitary water that has been sent through a water softener system to remove minerals (calcium and magnesium). The treated water is introduced into boilers to produce steam. This steam is superheated before distribution to facilities for heating and process use. Disposal sites receive steam condensate from the steam distribution lines. When used for heating purposes, this is a seasonal discharge. Non-regulated chemicals are added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, the flow was less than 0.038 liters per minute (0.01 gallons per minute).

Code: 300-61

Classification: Accepted

Names: 300-61; 303B Building Steam Condensate; Injection Well #12; Miscellaneous Stream #444

Reclassification: Rejected (1/19/1999)

Type: Injection/Reverse Well

Start Date:

Status: Inactive

End Date:

Description: The drain was decommissioned in 2012. The site had been described as an injection well. No engineered structure was evident at the location described for this site. Two steam lines labeled HPD-TRP-011 and HPD-TRP-12 were found; both are described in the "Inventory of Miscellaneous Streams," Revision 3. These two lines descend from the overhead line and disappear into the ground. A third line from the overhead steam line is found just east of HPD-TRP-011 and -012. This third line is unlabeled and terminates open-ended approximately 10 centimeters (3.9 inches) above the base of the wooden pole that supports it. The ground surface in this area is covered by gravel. According to the "Inventory of Miscellaneous Stream," Revision 3, this site is inactive, source abandoned.

Location: The site is north/northeast of the northeast corner of 303B and northwest of the northwest corner of 3732.

Related Sites/Structures: The site is related to the 300 Area main steam line. The "Inventory of Miscellaneous Streams," Revision 3, relates this discharge to the 303B Building, but that relation appear to be based only on proximity since 303B never received steam.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

Code: 300-62

Classification: Accepted

Names: 300-62; 303C Building - Steam Condensate; Miscellaneous Stream #495

Reclassification: Rejected (9/2/1998)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The drain was decommissioned in 2012. The site was two, 2.5 centimeter (1 inch) metal pipes from steam drain lines entering the ground at the base of the steam support structure. No engineered drain structure was visible. The miscellaneous streams report (Revision 3) says the stream has been eliminated because the source has been shut off. The site received steam condensate from the main header, HRD-TRP-007, -008.

Location: The drain is located in the northeast corner of the fenced area around 303C Building, at the southwest corner of Ginko and Wisconsin streets. The site is 8.3 meters (27 feet) from the north side of the 303C Building, at the base of steam line support poles.

Process Description: The site received steam condensate from steam lines passing by the 303C Building. Steam is produced from sanitary water that has been sent through a water softener system to remove minerals (calcium and magnesium). The treated water is introduced into boilers to produce steam. This steam is superheated before distribution to facilities for heating and process use. Non-regulated chemicals are added to dechlorinate the water, prevent scale, and control erosion.

Waste Type: Steam Condensate

Waste Description:

Code: 300-63 **Classification:** Not Accepted

Names: 300-63; 305B Building Stormwater Runoff; **Reclassification:** None
Miscellaneous Stream #458

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:**

Description: In September 2006, the top three feet of the structure was removed and the drain was backfilled. The site was a 0.6 meter (2 foot) diameter concrete french drain, 0.5 meters (1.5 feet) deep, with a perforated steel plate cover, flush with the alley road. About 0.3 meters (1 foot) from the top was a 6 centimeter (3 inch) diameter drain pipe that goes toward the west. Construction drawings H-3-52655 and H-3-304714 sheet 2 show that the open bottom catch basin/french drain location is connected directly to the (300-15) process sewer pipeline.

Location: The french drain was on the south side of the 305B Building, at the edge of a gravel slope and the paved alley. The site is 6.2 meters (20.5 feet) south-southeast of the corner of 305B and the downspout for the roof stormwater runoff.

Process Description: The site appears to be just stormwater runoff.

Waste Type: Stormwater Runoff

Waste Description:

Code: 300-64 **Classification:** Accepted

Names: 300-64; 303F Building Steam Condensate; **Reclassification:** Rejected (1/19/1999)
Miscellaneous Stream #352

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:**

Description: The drain was decommissioned in 2012.

The site was an HVAC steam condensate return to the WATS Pipe Trench (WIDS Site 300-224). The discharge went into a rectangular concrete base covered by a 0.90 meter (2.95 foot) by 2.45 meter (8.04 foot) metal lid. Some of the concrete base appears to be rusty. The site was also surrounded by concrete. The lid was posted "Confined Space." There were three openings cut in the metal lid to allow pipes to pass through. An approximately 2.5 centimeter (1 inch) diameter metal pipe entered the middle opening. This pipe was labeled "P198" and appears to be electrical in nature. A second approximately 2.5 centimeter (1 inch) diameter metal pipe entered the south opening. There is a label on the wall next to this pipe that reads "NP-303F-01." This second pipe extends approximately 2 meters (6.6 feet) above the lid, makes a 90 degree turn away from 303F and terminates open-ended over one of the steam lines that enters the west wall of 303F. An approximately 10 centimeter (4 inch) diameter steam pipe and an approximately 2.5 centimeter (1 inch) diameter metal pipe enter the north opening. These two pipes extend down from the building's roof. According to John Remaize, the lines from the roof of 303F are HVAC and cooling lines. The lid does not fit tightly; there are openings between the lid and the concrete base. These openings could allow stormwater runoff from the 303F Building to enter. These openings also allow a limited view of the interior of the structure. Although it is difficult to see inside, the floor of the interior appeared to be dry during the October 29, 1998, walkdown. However, there also appeared to be more pipes inside than could be accounted for by those entering through the lid. Drawing H-3-304714, Sheet 2, shows the WATS and U-Bearing Pipe Trench (WIDS Site 300-224) enters/leaves WIDS Site 300-64 and connects to the 313 Building.

The site is on the east end of a row of removable panels labeled "Radioactive Material, Internally Contaminated." 303F is posted "Fixed Contamination Area" and the 303F roof is posted "Contamination Area." According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive, source abandoned.

Location: The site is located on the west side of the 303F Building, just south of the door.

**Related Sites/
Structures:** The site is associated with the 303F Building.

**Process
Description:** Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

**Waste
Description:** The site has been listed as inactive in all earlier versions of the Miscellaneous Streams. Comments in earlier versions indicate the site has not been active for some time. No flow rate or date for eliminating the source has been provided in any version of the Miscellaneous Streams document.

Code: 300-65	Classification: Accepted
Names: 300-65; 303J Building - Steam Condensate Mud Leg (Part of 300 Main Supply); Miscellaneous Stream #266	Reclassification Rejected (9/2/1998)
Type: French Drain	Start Date:
Status: Inactive	End Date:

Description: The french drain has been decommissioned. The site was a 0.35 meter (14 inch) diameter steel pipe in the ground, about 0.8 meters (2.5 feet) deep. The drain had covered with a steel plate with notches and holes for vents and two steam condensate pipes to enter. According to the miscellaneous streams report (Revision 3), the stream has been eliminated because the steam source has been shut off. Signs on the 303J Building say that it is a closed facility, and no material is stored inside.

Location: The french drain was located in the center of the south side of the 303J Building, about 5 centimeters (2 inches) from the wall.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description:

Code: 300-66	Classification: Accepted
Names: 300-66; 303J Building HVAC Condensate; Miscellaneous Stream #267	Reclassification: Rejected (9/2/1998)
Type: Injection/Reverse Well	Start Date:
Status: Inactive	End Date:

Description: The french drain structure was removed with the 300-6 waste site. The site was an open concrete french drain. Two pipes exited from about the ceiling level of the 303J Building and discharge to the drain. The concrete drain was filled with sand and small rocks and it does not appear to have been used recently. The "Inventory of Miscellaneous Streams", Revision 3 lists the site as a steam condensate site. The responsible contractor believes the site to be an HVAC condensate drain (as it was listed in the previous "Inventory of Miscellaneous Streams", Revision 2).

Location: The site is immediately adjacent to the 303J Building, in the center of the north side.

Related Sites/ Structures: The 303J Building has been closed and is vacant.

Process Description: The Heating, Ventilation, and Air Conditioning (HVAC) system generates condensate on the coils from the air. The condensate is collected by the HVAC unit and it is drained to the french drain.

Waste Type: Water

Waste Description:

Code: 300-67	Classification: Accepted
Names: 300-67; Miscellaneous Stream #414; Steam Condensate from 300 Area Main Steam Header	Reclassification: Rejected (12/15/1998)
Type: Injection/Reverse Well	Start Date:

Status: Inactive**End Date:** 1/1/1998

Description: In January 2006, the structure was filled with grout. The site was an injection well that received steam condensate. Two metal lids and the metal lid frame were visible. The lid frame measured 1.90 meters (6.23 feet) by 0.82 meters (2.69 feet) and is flush with the ground surface. The site is just east of an access manhole for the process sewers, which is labeled "Radioactive Material, Internally Contaminated." The "Inventory of Miscellaneous Streams," Revision 2, states when this injection well was in service, it overflowed to the process sewer. The 303B Building was posted "Fissile Materials," "Radiation Area and Radioactive Material Area," and "Fixed Contamination Area." The roof of the 303B Building was also posted "Contamination Area." The 304 Building was posted "Fixed Contamination Area." This site was slightly down slope of the road to the north. There are small openings in the lid where stormwater runoff from the road may be able to enter the injection well. It did not appear as though runoff from the two buildings would be inclined to flow towards the site; the area between the buildings and the site was fairly level. The site was surrounded by gravel. According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive, source abandoned.

Location: The site is located northwest of 303B and northeast of the 304 Building, just south of the overhead steam line.

Related Sites/ Structures: The site is associated with the 300 Area main steam header.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, it received less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

Code: 300-68**Classification:** Accepted

Names: 300-68; 305 Building - Steam Condensate; Miscellaneous Stream #451; Pit U23

Reclassification: Rejected (12/15/1998)**Type:** Injection/Reverse Well**Start Date:****Status:** Inactive**End Date:** 1/1/1998

Description: In September 2006, the top three feet of structure was removed and then backfilled. The site was an injection well. The base of the injection well was constructed of corrugated metal and was covered by a 1.91 meter (6.27 foot) metal lid. The lid is approximately 30 centimeters (11.8 inches) above grade and was labeled "U-23" and "Confined Space." Two pipes enter the lid from the overhead steam lines. One of these pipes was approximately 20 centimeters (7.9 inches) in diameter and the other was approximately 6 centimeters (2.4 inches) in diameter. The site was surrounded by soil and gravel. The "Inventory of Miscellaneous Streams," Revision 3, says the site is inactive, source abandoned.

Location: The site is on the south side of the 305 building. It is just south and east of the entry door; between the entry door and the metal stairwell.

Related Sites/ Structures: The site is associated with the 305 building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, it received less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

Code: 300-69

Classification: Accepted

Names: 300-69; 305 Building Steam Condensate; Miscellaneous Stream #415

Reclassification: Rejected (12/15/1998)

Type: Injection/Reverse Well

Start Date:

Status: Inactive

End Date: 1/1/1998

Description: September 2006 the top three feet of the structure was removed and backfilled. The site was an injection well covered by a 0.74 meter (2.43 foot) metal lid. The lid was flush with the ground surface and is surrounded by metal grating resting on top of the soil and gravel. A small diameter, less than 2.5 centimeters (1 inch), metal pipe elbow extended approximately 20 centimeters (8 inches) from the building approximately 5 centimeters (2 inches) above the ground surface. The other end of the pipe disappeared into the ground. This pipe was in line with the injection well's lid. According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive, source abandoned.

Location: The site was located just north of the northeast corner of the easternmost extent of the 305 Building. It is also just south of the fence surrounding the electrical substation.

Related Sites/ Structures: This site is associated with the 305 Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, it received less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

Code: 300-70

Classification: Accepted

Names: 300-70; 305 Building Steam Condensate; Miscellaneous Stream #416

Reclassification: Rejected (12/15/1998)

Type: Injection/Reverse Well

Start Date:

Status: Inactive

End Date: 1/1/1998

Description: In September 2006, the top three feet of the structure was removed, then backfilled. The site

was an injection well covered by a 0.51 meter (1.67 foot) metal lid. The lid was flush with the ground surface and is surrounded by asphalt. A small diameter, less than 2.5 centimeters (1 inch), metal pipe elbow extended approximately 0.15 meters (0.5 feet) from the building approximately 0.15 meters (0.5 feet) above the ground surface. The other end of the pipe disappeared into the ground. This pipe was in line with the injection well's lid. The area around the lid and between the lid and the building appeared to have been excavated. According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive, source abandoned.

Location: The site is located on the south side of the 305 Building, approximately 6.7 meters (22 feet) west of the roll up door.

**Related Sites/
Structures:** This site is associated with the 305 Building.

**Process
Description:** Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

**Waste
Description:** When the site was active, it received less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

Code: 300-71

Classification: Accepted

Names: 300-71; 306E Building - HVAC Condensate;
Miscellaneous Stream #454

Reclassification Rejected (12/15/1998)

Type: Injection/Reverse Well

Start Date:

Status: Inactive

End Date: 1/1/1998

Description: The drain was decommissioned in 2012. The site is an injection well that used to receive HVAC condensate. The injection well is constructed of concrete pipe and is covered by a 0.54 meter (1.77 foot) round metal lid with handles. The top of the pipe rises approximately 4 centimeters (1.6 inches) above the ground surface. During the December 17, 1998, walkdown, the interior of the well appeared to be damp. This may have been due to condensation since there was condensation on the bottom of the lid. The well appears to be 20 centimeters (0.66 feet) deep with the bottom covered by cobbles. No pipes were visible entering the well. What appeared to be a black widow was living on the bottom side of the lid. The site is hidden behind an old air conditioning unit that is labeled "6" on its north side and SeasonCon on its south side. The site is surrounded by sand which has been discolored by garnet dust. According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive, source abandoned.

Location: The site is located west of the northeast corner of the 306E Building, behind the easternmost air conditioner unit.

**Related Sites/
Structures:** The site is associated with the 306E Building HVAC system.

**Process
Description:** The Heating, Ventilation, and Air Conditioning (HVAC) system generated condensate on the coils from the air. The condensate was collected by the HVAC unit and drained to the french drain.

Waste Type: Water

Waste Description: When the site was active, it received less than 0.038 liters per minute (0.01 gallons per minute) of HVAC condensate only.

Code: 300-72 **Classification:** Not Accepted

Names: 300-72; 308 Building Stormwater Runoff; Miscellaneous Stream #404 **Reclassification:** None

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:**

Description: The waste site was an injection well that was removed during the demolition of the 308 building. The structure was removed during the demolition of the 308 building. Letter: MSA-1400080 (1/27/2014) Contract Deliverable CD1033 Annual Class V Underground Injection Control (UIC) Wells Update for calendar year 2013 states the estimated backfill date of this drain is 2/1/2013. It received stormwater runoff from the surrounding area. The site was covered by a 0.66 meter (2.17 foot) metal lid with perforations. The lid was flush with the surrounding concrete.

During the November 8, 1998, walkdown, water could be seen through the perforations in the lid. It had rained three days prior to the walkdown. Sand has washed down the truck ramp and has partially covered the lid. The "Inventory of Miscellaneous Streams," Revision 3, states "Disposal site within 300 feet of an active/inactive crib, ditch or trench." The site is within 91 meters (300 feet) of 316-3 Trench.

Location: The site was located in the southernmost of two truck ramps at the northeast corner of the 308 Building. It was located in the ramp with a roll-up door labeled "48."

Related Sites/ Structures: The site is associated with the 308 Building.

Waste Type: Stormwater Runoff

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 3, the flow rate is less than 0.01 gallons per minute.

Code: 300-73 **Classification:** Not Accepted

Names: 300-73; 308 Building Stormwater Runoff; Miscellaneous Stream #405 **Reclassification:** None

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:**

Description: The waste site was an injection well that received stormwater runoff from the surrounding area. The structure was removed during the demolition of the 308 building. Letter: MSA-1400080 (1/27/2014) Contract Deliverable CD1033 Annual Class V Underground Injection Control (UIC) Wells Update for calendar year 2013 states the estimated backfill date of this drain is 2/1/2013. The site had been covered by a 0.18 meter (0.59 foot) metal grate.

At the time of the November 8, 1998, walkdown, the site was surrounded by approximately 7 centimeters (2.8 inches) of sand and debris. The drain itself was also filled with sand and debris. It had rained three days prior to the walkdown. According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive, source abandoned. The document also states "Disposal site within 300 feet of an active/inactive crib, ditch or trench." The site is

within 91 meters (300 feet) of 316-3 Trench.

Location: The site was located in the northernmost of two truck ramps at the northeast corner of the 308 Building. The site was in the truck ramp with the roll-up door labeled "46." It was set into a notch in the ramp's concrete.

Related Sites/ Structures: The site is associated with the 308 Building.

Waste Type: Stormwater Runoff

Waste Description: When the site was active, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute) of stormwater only.

Code: 300-74

Classification: Not Accepted

Names: 300-74; 308 Building Stormwater Runoff; Miscellaneous Stream #406

Reclassification: None

Type: Injection/Reverse Well

Start Date:

Status: Inactive

End Date:

Description: The waste site was an injection well that received stormwater runoff. The structure was removed during the demolition of the 308 building. Letter: MSA-1400080 (1/27/2014) Contract Deliverable CD1033 Annual Class V Underground Injection Control (UIC) Wells Update for calendar year 2013 states the estimated backfill date of this drain is 2/1/2013.

It had a concrete base and was covered by a 0.64 meter (2.10 foot) by 0.64 meter (2.10 foot) metal grate. A sign on the grate read "Drains to R.P.S." Sand and gravel covered part of the concrete surrounding the grate.

The top of the concrete was flush with the ground surface on its south and west sides. The north side was approximately 1 to 5 centimeters (0.4 to 2 inches) above the ground surface. The east side of the concrete rose above the asphalt surface of the truck ramp. At the time of the November 8, 1998, walkdown, the site was filled with water and water had pooled in the adjacent truck ramp. It had rained three day's prior to the walkdown. According to the "Inventory of Miscellaneous Streams," Revision 3, the site has been grouted. It is inactive and listed as, "Disposal Site Permanently Abandoned." The document also states "Disposal site within 300 feet of an active/inactive crib, ditch or trench." The site is within 91 meters (300 feet) of 316-3 Trench.

Location: The site was next to a truck ramp on the north side of the 308 Building, near the northwest corner of the building. It was located at the bottom of a short staircase from the truck ramp to the loading dock.

Related Sites/ Structures: The site is associated with the 308 Building. The 308 Building is inactive.

Waste Type: Stormwater Runoff

Waste Description: When the site was active, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute) of stormwater only.

Code: 300-75

Classification: Accepted

Names: 300-75; 309 Building Stormwater Runoff and Chiller Water; Injection Well #20; Miscellaneous

Reclassification: Rejected (1/19/1999)

Stream #445

Type: Injection/Reverse Well**Start Date:****Status:** Inactive**End Date:**

Description: The site is an injection well that received stormwater runoff and water from a chiller. The well is a concrete pipe covered by a 1.11 meter (3.64 foot) diameter metal lid. The top of the pipe is approximately 2.5 centimeters (1 inch) above grade. The lid is labeled "Confined Space." The site is surrounded by yellow safety posts and asphalt. John Remaize stated that the chiller has been removed. According to the "Inventory of Miscellaneous Streams," Revision 3, the drain has been permanently plugged and the stream has been routed to a process sewer. The document lists the site as inactive, "Source Permanently Abandoned."

Location: The site is located west of Door #11, which is the southernmost door on the west side of the south wing of the 309 Building.

Related Sites/ Structures: The site is associated with the 309 Building.

Process Description: The chiller generated condensate on the coils from the air. The condensate was collected by the chiller unit and was drained to the injection well.

Waste Type: Water

Waste Description: The waste was stormwater runoff and chiller water. When the site was active, the flow rate was less than 0.038 liters (0.01 gallons per minute).

Code: 300-76**Classification:** Accepted**Names:** 300-76; 306W Building Steam Condensate; Miscellaneous Stream #418**Reclassification:** Rejected (9/2/1998)**Type:** French Drain**Start Date:****Status:** Inactive**End Date:**

Description: The site is a french drain that is a concrete pipe almost flush with the ground surface. A 2.54 centimeter (1 inch) metal pipe drops from an overhead steam line and drains to the unit. Adjacent steam drain lines may also enter the unit, but any connecting pipes are below the rocks that come to within about 15.2 centimeters (6 inches) of the top of the drain. The drain is covered with a round steel plate with four vent holes and a notch for the metal pipe. The rocks appear to be discolored from rust. The "Inventory of Miscellaneous Streams", Revision 3, says the site is inactive, source abandoned. The site does not appear to be active, but discharge pipe(s) is (are) still present (assuming adjacent pipes also discharge to the unit).

Location: The site is on the west side of the 306W Building, about 5.5 meters (18 feet) west of the west wall and about 21.3 meters (70 feet) north of the southwest corner.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description:

Code: 300-77 **Classification:** Not Accepted

Names: 300-77; 309 Building Stormwater Runoff; Miscellaneous Stream #450 **Reclassification:** None

Type: Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The site is a 10.16 cm (4 in) storm drain that empties into the process sewer 300-15 (H-3-13532).

Location: The site is located at the bottom of the stairwell on the north side of the west wing of the 309 Building. The stairwell is below door #8.

Related Sites/ Structures: The site is associated with the 309 Building.

Waste Type: Stormwater Runoff

Waste Description: When the site was active, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute) of stormwater only.

Code: 300-78 **Classification:** Accepted

Names: 300-78; Miscellaneous Stream #331; 300 Area Main Header Steam Trap (Southwest Corner of 313 Building) **Reclassification:** Rejected (2/12/1999)

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:**

Description: The effluent source to this structure was removed when the 313 building was demolished in 2004. The waste site is a rectangular shaped below grade concrete box that is covered with two steel plates. Seven pipes of various sizes entered the site from the 313 building. Standing water was observed in the bottom of the site. A concrete lined 6.7 meters long by 0.356 meters wide by 0.330 deep (22 feet long by 14 inches wide by 13 inches deep) trench extended from the site to the south. An opening at the south end of the trench was observed and may lead to the process sewer. This trench may be an overflow in the event the concrete box fills with water. Steel grating covers the top of the trench. A concrete pad surrounding the site is painted gray and posted as fixed radiological contamination.

Location: The waste site was located adjacent to the west side of the 313 building near the southwest corner.

Process Description: According to John Remaize (Point of Contact), the site drained HVAC condensate into the process sewer. It is not a french drain as previously suspected. The site is covered with rectangular steel hatch covers and is posted as a confined space.

Steam was produced from sanitary water that has been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites receive steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only ("Inventory of Miscellaneous Streams"). This information differs from that provided by John Remaize (Point of Contact). According to Mr. Remaize the site received HVAC condensate.

Code: 300-79 **Classification:** Not Accepted

Names: 300-79; 313 Building Stormwater Runoff; Miscellaneous Stream #457 **Reclassification:** None

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:**

Description: The 313 building was demolished in 2004. Letter: MSA-1400080 (1/27/1014) Contract Deliverable CD1033 Annual Class V Underground Injection Control (UIC) Wells Update for calendar year 2013 states the estimated backfill date of this drain is 1/31/2013.

The site was a 1.14 meter (44 inch) diameter drywell that received stormwater from six catch basins located to the south and the surrounding 313 Building Parking Lot area. The surrounding area was paved with asphalt and there is no known contamination within the drainage area. The drywell was 1.4 meters (55 inches) deep and is constructed of corrugated steel pipe. Water was observed at the bottom of the site.

Location: The site is located north of the 313 building.

Waste Type: Stormwater Runoff

Waste Description: The "Inventory of Miscellaneous Streams", Revision 3, states that the flow rate is less than 1.9 liters per minute (0.5 gallons per minute) of stormwater runoff only.

Code: 300-81 **Classification:** Accepted

Names: 300-81; 321 Building Steam Condensate; Miscellaneous Stream #370 **Reclassification:** Consolidated (2/12/1999)

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:**

Description: The drain is a 1.03 meter (3.3 foot) diameter concrete structure with a metal cover. The building source pipe is connected to the drain through the cover.

Location: The site is located on the northwest side of the 321 Building adjacent to Door #07.

Release Description: There were no known hazardous or radioactive releases from this steam condensate discharge.

Related Sites/Structures: The site is related to 321 Building. The 321 Building, also known as the Separation Building and Engineering Development Laboratory, provided facilities for hydraulic and mechanical research and development of reactor components. In the past, the building was used as a chemical pilot plant and also did research and development work for the REDOX Plant. A series of cells and tanks ran the entire length of the 321 Building in the south half and at a depth of 3.6 meters (12 feet) below grade. About 37 meters (120 feet) to the south of the building lay 4 underground tanks, each 14.8 meters (48.5 feet) long by 3.1 meters (10 feet) in diameter that were used to hold radioactive wastes. These tanks were located under the 323 Building. The facility is known to have had a number of releases associated with it. WIDS Site UPR-300-4 is an unplanned release associated with the 321 Building that is known to have contaminated the

soil around the facility.

Process Description: Steam is produced from sanitary water that has been sent through a water softener system to remove minerals (calcium and magnesium). The treated water is introduced into boilers to produce steam. This steam is superheated before distribution to facilities for heating and process use. Disposal sites receive steam condensate from the steam distribution lines. When used for heating purposes, this is a seasonal discharge. Non-regulated chemicals are added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

This Site Was Consolidated With:

Code: UPR-300-4

Names: UPR-300-4; Contaminated Soil Beneath the 321 Building; UN-300-4

Code: 300-82

Classification: Accepted

Names: 300-82; 321 Building Steam Condensate; Miscellaneous Stream #371

Reclassification: Consolidated (1/19/1999)

Type: Injection/Reverse Well

Start Date:

Status: Inactive

End Date:

Description: The site is a 1.04 meter (3.3 foot) diameter french drain with a metal cover. The drain is flush with the ground. An overhead steam line runs north to south above the drain. The source piping has been removed. The soil just north of the french drain is discolored with a rusty stain.

Location: The site is located on the west side of the 321 Building, between the 321 Building and the 352-D Building.

Release Description: There were no known hazardous or radioactive releases from this steam condensate discharge.

Related Sites/Structures: The site is related to 321 Building. The 321 Building, also known as the Separation Building and Engineering Development Laboratory, provided facilities for hydraulic and mechanical research and development of reactor components. In the past, the building was used as a chemical pilot plant and also did research and development work for the REDOX Plant. A series of cells and tanks ran the entire length of the 321 Building in the south half and at a depth of 3.6 meters (12 feet) below grade. About 37 meters (120 feet) to the south of the building lay 4 underground tanks, each 14.8 meters (48.5 feet) long by 3.1 meters (10 feet) in diameter that were used to hold radioactive wastes. These tanks were located under the 323 Building. The facility is known to have had a number of releases associated with it. WIDS Site UPR-300-4 is an unplanned release associated with the 321 Building that is known to have contaminated the soil around the facility.

Process Description: Steam is produced from sanitary water that has been sent through a water softener system to remove minerals (calcium and magnesium). The treated water is introduced into boilers to produce steam. This steam is superheated before distribution to facilities for heating and process use. Disposal sites receive steam condensate from the steam distribution lines. When used for heating purposes, this is a seasonal discharge. Non-regulated chemicals are added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute).

This Site Was Consolidated With:

Code: UPR-300-4

Names: UPR-300-4; Contaminated Soil Beneath the 321 Building; UN-300-4

Code: 300-83

Classification: Accepted

Names: 300-83; 321 Building Steam Condensate; Miscellaneous Stream #372

Reclassification: Consolidated (1/19/1999)

Type: Injection/Reverse Well

Start Date:

Status: Inactive

End Date:

Description: The site is a square concrete structure with a metal cover and labeled, F. D. #35. The concrete structure is raised 12.7 centimeters (5 inches) from the surrounding ground level. Inside the cover is a pipe with a 12.7 centimeter (5 inch) diameter screen cover. The inside of the structure is dry and the pipe appears to be inactive. The concrete structure is 3.6 meters (12 feet) west of the stormwater drain (site code 300-92) in front of the roll-up door.

Location: The site is located on the south side of the 321 Building, outside door #12, and at the bottom of the truck ramp. It is located against the building where two walls form a corner.

Release Description: There were no known hazardous or radioactive releases from this steam condensate discharge.

Related Sites/Structures: The site is related to 321 Building. The 321 Building, also known as the Separation Building and Engineering Development Laboratory, provided facilities for hydraulic and mechanical research and development of reactor components. In the past, the building was used as a chemical pilot plant and also did research and development work for the REDOX Plant. A series of cells and tanks ran the entire length of the 321 Building in the south half and at a depth of 3.6 meters (12 feet) below grade. About 37 meters (120 feet) to the south of the building lay 4 underground tanks, each 14.8 meters (48.5 feet) long by 3.1 meters (10 feet) in diameter that were used to hold radioactive wastes. These tanks were located under the 323 Building. The facility is known to have had a number of releases associated with it. WIDS Site UPR-300-4 is an unplanned release associated with the 321 Building that is known to have contaminated the soil around the facility.

Process Description: Steam was produced from sanitary water that has been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites receive steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

This Site Was Consolidated With:

Code: UPR-300-4

Names: UPR-300-4; Contaminated Soil Beneath the 321 Building; UN-300-4

Code: 300-84

Classification: Accepted

Names: 300-84; 321 Building Vent Valve on Water Line; **Reclassification** Consolidated (1/19/1999)
Miscellaneous Stream #348

Type: Valve Pit

Start Date:

Status: Inactive

End Date:

Description: The site is a 2.4 meter (8 foot) diameter, semicircular, steel caisson. It has a hatch opening marked "Confined Space". There are two valves at the bottom. The caisson is 2.2 meters (7.5 feet) deep. The site is marked "W-25" on the side of the caisson. One valve appears to be a main water shut off valve to the 321 building and the other is a drain valve. The 321 Building is unoccupied.

Location: The site is located adjacent to the west wall of the 321 Building.

Release Description: There were no known hazardous or radioactive releases from this water discharge.

Related Sites/ Structures: The site is related to 321 Building. The 321 Building, also known as the Separation Building and Engineering Development Laboratory, provided facilities for hydraulic and mechanical research and development of reactor components. In the past, the building was used as a chemical pilot plant and also did research and development work for the REDOX Plant. A series of cells and tanks ran the entire length of the 321 Building in the south half and at a depth of 3.6 meters (12 feet) below grade. About 37 meters (120 feet) to the south of the building lay 4 underground tanks, each 14.8 meters (48.5 feet) long by 3.1 meters (10 feet) in diameter that were used to hold radioactive wastes. These tanks were located under the 323 Building. The facility is known to have had a number of releases associated with it. WIDS Site UPR-300-4 is an unplanned release associated with the 321 Building that is known to have contaminated the soil around the facility.

Waste Type: Water

Waste Description: When the site was active, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute).

This Site Was Consolidated With:

Code: UPR-300-4

Names: UPR-300-4; Contaminated Soil Beneath the 321 Building; UN-300-4

Code: 300-85

Classification: Accepted

Names: 300-85; 323 Building Steam Valve Pit;
Miscellaneous Stream #453

Reclassification Rejected (9/2/1998)

Type: Valve Pit

Start Date:

Status: Inactive

End Date:

Description: The site is a 150 centimeter (60 inch) diameter vertical steel caisson with a sloping steel lid. An access door is located on the lid. The interior of the caisson contains several pipes and valves. The site appears to be a valve pit. The site is posted as a confined space.

Location: The site is located on the south end of the 323 Building near the southwest corner.

Process Description: Steam is produced from sanitary water that has been sent through a water softener system to remove minerals (calcium and magnesium). The treated water is introduced into boilers to produce steam. This steam is superheated before distribution to facilities for heating and process use. Disposal sites receive steam condensate from the steam distribution lines. When used for heating purposes, this is a seasonal discharge. Non-regulated chemicals are added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Water

**Waste
Description:**

Code: 300-86 **Classification:** Accepted
Names: 300-86; Miscellaneous Stream #524; 300 Area South Parking Lot Stormwater Runoff **Reclassification** Rejected (12/15/1998)
Type: Depression/Pit (nonspecific) **Start Date:**
Status: Active **End Date:**

Description: The site is a basin approximately 2 meters (6.6 feet) deep that collects stormwater from the main 300 area south parking lot. A lawn has been planted within the basin, and two inlet pipes are visible at the northeast corner and the southeast corner of the site.

Location: The site is located in the southwestern portion of the 300 Area, northeast of the Cypress Street Gate and north of the 320 building.

**Related Sites/
Structures:** The site is associated with the 300 Area south parking lot. Drainage from sitecodes 300-103 and 300-104 was diverted to this parking lot drainage system in 2009 (per H-3-315180, sheet 1).

**Process
Description:** The site collects stormwater from the adjacent parking lot and discharges it to ground. The grass serves to filter and biodegrade potential pollutants prior to infiltration to the soil.

Waste Type: Stormwater Runoff

**Waste
Description:** According to the "Inventory of Miscellaneous Streams," Revision 3, the flow is less than 18.75 liters per minute (5 gallons per minute).

Code: 300-87 **Classification:** Not Accepted
Names: 300-87; 309 Building Stormwater Runoff; Miscellaneous Stream #679 **Reclassification** None
Type: Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The site is a 10.16 cm (4 in) storm drain that empties into the radioactive process sewer 300 RLWS (H-3-11204, Sheets 1 and 2).

Location: The site is located at the bottom of the stairwell on the west side of the south wing of the 309 Building. The stairwell is below door #10.

**Related Sites/
Structures:** The site is associated with the 309 Building.

Waste Type: Stormwater Runoff

**Waste
Description:** When the site was active, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute) of stormwater only.

Code: 300-88 **Classification:** Accepted
Names: 300-88; 320 Building Irrigation Line Effluent; **Reclassification** Rejected (9/2/1998)

Miscellaneous Stream #626

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The site was a french drain that is constructed of concrete and covered with a steel lid. It was decommissioned in March 2012.

Location: The site was located in the 300 Area, south of Cypress Street and northwest of the 320 Building.

Process Description: The site received water from the evacuation of irrigation lines when the lines are drained in the fall.

Waste Type: Water

Waste Description: The site receives irrigation water.

Code: 300-89

Classification: Accepted

Names: 300-89; 320 Building Irrigation Line Effluent; Miscellaneous Stream #627

Reclassification: Rejected (9/2/1998)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The site was a french drain that is constructed of concrete and covered with a steel lid. It was decommissioned in March 2012.

Location: The site was located in the 300 Area, south of Cypress Street and north of the 320 Building. WCH corrected the coordinates of 300-89 to be at N115529.7, E593814.2.

Process Description: The site received water from the evacuation of irrigation lines around the 320 Building when the lines are drained in the fall.

Waste Type: Water

Waste Description: The site receives irrigation water.

Code: 300-90

Classification: Accepted

Names: 300-90; 320 Building Irrigation Line Effluent; Miscellaneous Stream #628

Reclassification: Rejected (9/2/1998)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The french drain was constructed of concrete and covered with a steel lid. It was decommissioned in March 2012.

Location: The site was located in the 300 Area, south of Cypress Street, west of Nebraska Street and east of the 320 Building. WCH corrected the coordinates of 300-90, to be at N115517.4, E593858.5.

Process Description: The site received water from irrigation lines when lines are drained in the fall.

Waste Type: Water

Waste Description: The site receives irrigation water.

Code: 300-91 **Classification:** Accepted
Names: 300-91; 320 Building; Miscellaneous Stream #350 **Reclassification:** Rejected (9/2/1998)
Type: French Drain **Start Date:**
Status: Inactive **End Date:**

Description: The french drain is constructed of concrete and covered with a steel lid.

Location: The site is located southwest of the 320 building under a tree.

Process Description: The site received water from irrigation lines when lines are drained in the fall.

Waste Type: Water

Waste Description: The site received irrigation water.

Code: 300-92 **Classification:** Accepted
Names: 300-92; 321 Building Stormwater Runoff; Miscellaneous Stream #680 **Reclassification:** Consolidated (1/19/1999)
Type: Injection/Reverse Well **Start Date:**
Status: Active **End Date:**

Description: The drain was a small, steel grate, measuring 0.38 meters by 0.38 meters (1.25 foot by 1.25 foot). It was removed during remediation of waste site UPR-300-4.

Location: The drain was located on the south side of the 321 Building, at the bottom of a sloping truck ramp, in front of a roll-up door.

Related Sites/ Structures: The site is associated with the 321 Building.

Process Description: The site was designed to receive stormwater runoff from 321 building.

Waste Type: Stormwater Runoff

Waste Description: The "Inventory of Miscellaneous Streams", Revision 3, states that the flow rate is less than 0.038 liters per minute (0.01 gallons per minute) of stormwater runoff only.

This Site Was Consolidated With:

Code: UPR-300-4
Names: UPR-300-4; Contaminated Soil Beneath the 321 Building; UN-300-4

Code: 300-93 **Classification:** Not Accepted
Names: 300-93; 324 Building Stormwater Runoff; Miscellaneous Stream #354 **Reclassification:** None
Type: Injection/Reverse Well **Start Date:**

Status: Inactive**End Date:**

Description: The site consists of the 324 building storm water drainage system as depicted on construction drawings H-3-56533 and H-3-302821. The site includes 3 catch basins and 1 drywell with all connecting piping features and cleanouts. The site includes the below grade pipe segments for collection of the northwest portion of the 324 building down spouts and one irrigation valve box and associated connecting piping to the catch basin. The site does not include the northeast side storm water collection system as depicted on H-3-307101 and described by WIDS site 300-94.

The site is a 0.65 meter by 0.47 meter (2.1 foot by 1.5 foot) grate in the asphalt parking area on the south side of the 324 Building. It is 3 meters (10 feet) south of the lawn.

Location: The drain is located 9 meters (30 feet) south of the 324 Building.

Related Sites/ Structures: The site was associated with the 324 Building.

Waste Type: Stormwater Runoff

Waste Description: When the site was active, the flow rate was less than 0.19 liters per minute (0.05 gallons per minute) of stormwater runoff only.

Code: 300-94**Classification:** Not Accepted

Names: 300-94; 324 Building Stormwater Runoff; Miscellaneous Stream #711; 300-234

Reclassification: None**Type:** French Drain**Start Date:****Status:** Active**End Date:**

Description: The site is a network of a drywell and a catch basin network installed to eliminate flooding on the east side of the 324 building. The drain and the catch basin are subsurface structures and are not visible. A 0.63 by 0.53 meter grate is visible in the gravel near the northeast corner of the 324 Building. The building escort for the 10-26-98 site visit pointed out that there is an identical grate at the southeast corner of the building, with a concrete trough leading to it to help direct water flow. The second grate is approximately 9 meters (30 feet) south of the one on the northeast corner. The two grates are in line with each other, parallel to the east side of the building. A PVC inlet and outlet pipe is visible through the grates. The two grates appear to be connected and are assumed to be stormwater collection points for the drainage system.

Location: The drain is located approximately 21.3 meters (70 feet) north of the northeast corner of the 324 building. A surface grate is located 1.2 meters (4 feet) east of the 324 Building, adjacent to the exhaust ventilation fans.

Waste Type: Stormwater Runoff

Waste Description: The "Inventory of Miscellaneous Streams", Revision 3, states that the flow rate is less than 0.79 liters per minute (0.20 gallons per minute) of stormwater only.

Code: 300-95**Classification:** Accepted

Names: 300-95; 324/336 Buildings Stormwater Runoff and Steam Condensate; Miscellaneous Stream #425

Reclassification: Rejected (1/19/1999)**Type:** French Drain**Start Date:**

Status: Active**End Date:****Description:** The site is a french drain that receives stormwater runoff and steam condensate. All that can be seen of the site is an inset, 1.37 meter (4.49 foot) diameter, thin metal cover or lid. This cover is inset in a round concrete pad and appears to be bolted onto an underlying grate. The site is labeled "Confined Space." The site and concrete pad are higher in elevation than the surrounding gravel. No incoming or nearby pipes were visible during the November 20, 1998, walkdown.**Location:** The site is due north of the west wing of the 337 Building, 24 meters (78.7 feet) southwest of the southwest corner of the 338 Building, 35 meters (114.8 feet) southeast of the southeast corner of the 336 Building and 130 meters (426.5 feet) east/southeast of the 324 Building.**Release Description:** There were no known hazardous or radioactive releases from the steam condensate discharge.**Related Sites/ Structures:** The site is associated with the 324 and 336 Buildings.**Process Description:** Steam is produced from sanitary water that has been sent through a water softener system to remove minerals (calcium and magnesium). The treated water is introduced into boilers to produce steam. This steam is superheated before distribution to facilities for heating and process use. Disposal sites receive steam condensate from the steam distribution lines. When used for heating purposes, this is a seasonal discharge. Non-regulated chemicals are added to dechlorinate the water, prevent scale, and control corrosion.**Waste Type:** Steam Condensate**Waste Description:** According to the "Inventory of Miscellaneous Streams," Revision 3, the flow for stormwater runoff and steam condensate is less than 0.05 gallons per minute.**Waste Type:** Stormwater Runoff**Waste Description:** According to the "Inventory of Miscellaneous Streams," Revision 3, the flow for stormwater runoff and steam condensate is less than 0.05 gallons per minute.

Code: 300-96**Classification:** Accepted**Names:** 300-96; 325 Building Steam Condensate; Miscellaneous Stream #707**Reclassification:** Rejected (9/2/1998)**Type:** Injection/Reverse Well**Start Date:****Status:** Inactive**End Date:****Description:** The site is a 132.1 centimeter (52 inch) diameter french drain constructed of concrete and covered with a steel lid. Letter: MSA-1400080 (1/27/2014) Contract Deliverable CD1033 Annual Class V Underground Injection Control (UIC) Wells Update for calendar year 2013 states the estimated backfill date of this drain is 10/1/2013. A 3.8 centimeter (1.5 inch) diameter pipe extends from the west wall of the 325 building to the french drain. It was a covered dry well that received Steam Condensate from the 325 building.**Location:** The site is located on the west side of the 325 building.**Process Description:** Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added

to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

**Waste
Description:**

Code: 300-97 **Classification:** Not Accepted

Names: 300-97; 325 Building Stormwater Runoff and Fire System Testing Water; Miscellaneous Stream #706 **Reclassification:** None

Type: French Drain **Start Date:**

Status: Active **End Date:**

Description: The site is a drain that is covered by a rusted perforated steel plate, 0.46 meters (1.5 feet) square. The site drains a small asphalt pad and a pipe coming out of bottom of the fire system shed. The drain cover plate appears to be sealed to the asphalt. Therefore, it was not possible to determine the depth of the site.

Location: The site is located on the southeast side of the 325 Building, 3.96 meters (13 feet) from the building, and adjacent to the fire system shed that is attached to the 325 Building.

**Related Sites/
Structures:** Approximately, 12.2 meters (40 feet) south of the drain, a pipe exits out of a concrete wall onto the roadway. Another stormwater drain is at the bottom of the roadway. It was not possible to determine if 300-97 is attached to the pipe.

Waste Type: Stormwater Runoff

**Waste
Description:**

Code: 300-98 **Classification:** Not Accepted

Names: 300-98; 325 Building South Stairwell Drain; Miscellaneous Stream #264; 300-229 **Reclassification:** None

Type: French Drain **Start Date:**

Status: Active **End Date:**

Description: The site is a 12.7 centimeter (5 inch) square floor drain at the bottom of a stairwell that drains stormwater from a leaky roof.

Location: The site is located inside the 325 Building south stairwell.

Waste Type: Stormwater Runoff

**Waste
Description:** The site receives less than 0.038 liters (0.01 gallons) per minute of stormwater runoff.

Code: 300-99 **Classification:** Accepted

Names: 300-99; 325 Building Nitrogen Tank Blowdown Miscellaneous Stream #265; Injection Well #399-3 **Reclassification:** Rejected (9/2/1998)

Type: Injection/Reverse Well**Start Date:****Status:** Inactive**End Date:**

Description: The site is not visible without entering the confined space under the compressed gas storage loading dock. The loading dock has skirting around it, and therefore, the site is not visible. A limited field walkdown was performed for this site. No access could be gained to the site. Although the Inventory of Miscellaneous Streams, Rev 3 lists this site as a steam condensate injection well, it has been determined that it does not meet the definition of an Underground Injection Control well (UIC).

Location: The site is located on the northeast corner of the 325 Building, under an elevated gas storage dock.

Waste Type: Water

Waste Description: The site received condensate blowdown from a liquid nitrogen tank. The tank has been removed.

Code: 300-100**Classification:** Not Accepted**Names:** 300-100; 325 Building Stormwater Runoff; Miscellaneous Stream #408**Reclassification:** None**Type:** French Drain**Start Date:****Status:** Inactive**End Date:**

Description: The site drains stormwater from the chiller pad to the ground. The drain is covered with a 68.6 centimeter by 61 centimeter (27 inch by 24 inch) steel grate. The site is 22.9 centimeters - 25.4 centimeters (9 inches - 10 inches) deep and contains water just below the grating.

Location: The site is located on the east side of the 325 building on the chiller pad.

Waste Type: Stormwater Runoff

Waste Description:

Code: 300-101**Classification:** Accepted**Names:** 300-101; 326 Building Stormwater Runoff and Steam Condensate; Miscellaneous Stream #409**Reclassification:** Rejected (9/2/1998)**Type:** Depression/Pit (nonspecific)**Start Date:****Status:** Active**End Date:**

Description: According to the "Inventory of Miscellaneous Streams", Revision 3, the site is active for stormwater only. The disposal structure is a non-engineered structure.

The site is a roadway drain, with a 0.4 meter by 0.5 meter (1.3 foot by 1.7 foot) rectangular perforated steel cover. The cover is visible, but the structure is full of sand and gravel. The site drains stormwater from a loading dock and a large area of asphalt parking spaces. A steel pipe 3.7 meters (12 feet) away, on the side of the building, appears to be the steam condensate drain. Next to this pipe is a lock box that is marked with a "Radioactively controlled area" sign.

The steam condensate component for this site has been routed to the sanitary sewer.

Location: The site is on the east side of the 326 Building, below the loading dock, 1.3 meters (4.5 feet) from the dock. It is 3.7 meters (12 feet) northeast of the probable steam condensate drain line.

Process Description: Steam is produced from sanitary water that has been sent through a water softener system to remove minerals (calcium and magnesium). The treated water is introduced into boilers to produce steam. This steam is superheated before distribution to facilities for heating and process use. Disposal sites receive steam condensate from the steam distribution lines. When used for heating purposes, this is a seasonal discharge. Non-regulated chemicals are added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Stormwater Runoff

Waste Description: Waste is also reported to be steam condensate. Lock box next to possible steam condensate line is marked with a warning sign: "Radioactively controlled area." The materials loaded at the loading dock are unknown, but no spills or unplanned releases are known.

Code: 300-102

Classification: Accepted

Names: 300-102; 328 Building Steam Condensate; Miscellaneous Stream #353

Reclassification: Rejected (12/15/1998)

Type: Injection/Reverse Well

Start Date:

Status: Inactive

End Date: 1/1/1998

Description: The site is an injection well that received steam condensate. The injection well is a 96 centimeter (38 inch) diameter structure with a heavy metal cover that has four holes in it. It is flush with the gravel surface surrounding it. According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive, source abandoned.

Location: The site is located on the north side of the 328 Building, just east of a roll up door entrance. The site is between a shed and the roll up door.

Related Sites/Structures: The site is associated with the 328 Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, it received less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

Code: 300-103

Classification: Not Accepted

Names: 300-103; 329 Building Stormwater Runoff; Miscellaneous Stream #422

Reclassification: None

Type: Sump

Start Date:

Status: Inactive

End Date:

Description: The site is a storm drain covered with a 63.5 centimeter by 45.7 centimeter (25 inch by 18 inch) steel grating that drains stormwater from the surrounding area. There are no contamination

postings near the site.

Location: The site is located near the southeast corner of the 329 building just off the loading dock.

Related Sites/ Structures: The stormwater run off is now associated with 300-86 drainage system.

Process Description: Additional research found that this location is actually a Catch Basin that was connected to the 300 Area Sanitary Sewer (300 SSS). Construction drawing H-3-304716 note 3C references the catch basin design type. The specifications for the WSDOT M21-01 Standard Plan B-1B Type 1P Parking Lot Catch Basin require that the catch basin be water tight. The stream was later re-routed to the Retention Process Sewer. Per drawing H-3-315180, sheet 1, the storm water was re-routed again in 2009 to the 300 Area South Parking Lot Stormwater Runoff (see sitecode 300-86).

Waste Type: Stormwater Runoff

Waste Description:

Code: 300-104

Classification: Not Accepted

Names: 300-104; 329 Building Stormwater Runoff; Miscellaneous Stream #546

Reclassification: None

Type: Sump

Start Date:

Status: Inactive

End Date:

Description: The site is a storm drain (catch basin) covered with a 63.5 centimeter by 45.7 centimeter (25 inch by 18 inch) steel grating that drains stormwater from the surrounding area. There are no contamination postings near the site.

Location: The site is located on the east side of the 329 building just off the loading dock.

Related Sites/ Structures: The stormwater run off is now associated with 300-86 drainage system.

Process Description: Additional research found that this location is actually a Catch Basin that was connected to the 300 Area Sanitary Sewer (300 SSS). Construction drawing H-3-304716 note 3C references the catch basin design type. The specifications for the WSDOT M21-01 Standard Plan B-1B Type 1P Parking Lot Catch Basin require that the catch basin be water tight. The stream was later re-routed to the Retention Process Sewer. Per drawing H-3-315180, sheet 1, the storm water was re-routed again in 2009 to the 300 Area South Parking Lot Stormwater Runoff (see sitecode 300-86).

Waste Type: Stormwater Runoff

Waste Description:

Code: 300-105

Classification: Accepted

Names: 300-105; 331 Building Steam Condensate; Miscellaneous Stream #513; Pit U1

Reclassification: Rejected (9/2/1998)

Type: French Drain

Start Date:

Status: Active

End Date:

Description: The site is a steam pit. Several shut off valves are visible and a hatch cover provides access to the site. All locks have been removed from the valves.

Location: The site is located 9.1 meters (30 feet) off the northwest corner of the 331 building.

Process Description: Steam is produced from sanitary water that has been sent through a water softener system to remove minerals (calcium and magnesium). The treated water is introduced into boilers to produce steam. This steam is superheated before distribution to facilities for heating and process use. Disposal sites receive steam condensate from the steam distribution lines. When used for heating purposes, this is a seasonal discharge. Non-regulated chemicals are added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description:

Code: 300-106	Classification: Accepted
Names: 300-106; 331 Building Steam Condensate; Miscellaneous Stream #574	Reclassification: Rejected (9/2/1998)
Type: French Drain	Start Date:
Status: Inactive	End Date:

Description: The site is a drain line (not an injection well) that drains stormwater and possibly steam condensate from what appears to be a steam pipe near the drain. The site is not an injection well or a french drain. Water level in the drain was observed just below the top of the grating.

Location: The site is located adjacent to the west side of the 331 building at the low point of the walkway around the building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description:

Waste Type: Stormwater Runoff

Waste Description:

Code: 300-107	Classification: Not Accepted
Names: 300-107; 331 Building Stormwater Runoff; Injection Well #32; Miscellaneous Stream #447	Reclassification: None
Type: French Drain	Start Date:
Status: Active	End Date:

Description: The site is a french drain constructed of concrete and covered with a steel lid. The drain has

two 10.2 centimeter (4 inch) diameter pipes entering the drain at the bottom. Presumably, the site drains stormwater from drains located near two nearby entrances to the 331 building.

Location: The site is located on the west side of the 331 building near the kennels.

Waste Type: Stormwater Runoff

**Waste
Description:**

Code: 300-108 **Classification:** Not Accepted

Names: 300-108; 331 Building Stormwater Runoff; **Reclassification** None
Injection Well #37; Miscellaneous Stream #448

Type: French Drain **Start Date:**

Status: Active **End Date:**

Description: The site is a stormwater french drain that drains the surrounding paved area and roof drains from the 331 building at a low point. There is no known contamination within the drainage area.

Location: The site is located on the west side of the 331 building, and 12.5 meters (41 feet) south of the northwest corner of the building.

Waste Type: Stormwater Runoff

**Waste
Description:**

Code: 300-111 **Classification:** Not Accepted

Names: 300-111; 337 Building Stormwater Runoff; **Reclassification** None
Miscellaneous Stream #516

Type: French Drain **Start Date:**

Status: Inactive **End Date:**

Description: The site is a french drain; a round concrete pipe 0.7 meters (2.25 feet) in diameter, at least 1.2 meters (4 feet) deep. Water covers the bottom, so the total depth was not determined. The site drains stormwater from the asphalt alley way used to access the trash and recycled cardboard pickup containers, and provide pedestrian access to the 337 Building. The miscellaneous streams report says this site is a "non-engineered structure" and "deleted" but it does not appear to be either case.

Location: The site is on the east side of the 337 Building, north of the cafeteria, in an open alley way. The drain is 7 meters (23 feet) from the east door into the 337 Building.

**Process
Description:** The site received only stormwater runoff.

Waste Type: Stormwater Runoff

**Waste
Description:** Site receives only stormwater runoff.

Code: 300-112 **Classification:** Accepted

Names: 300-112; 340 P-3 Pump Pit; Miscellaneous Stream #428; Retention Process Sewer Pump Pit #3 French Drain **Reclassification** Rejected (1/15/1999)

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:** 1/1/1996

Description: The Pump Pit is an engineered structure with an entry hatch labeled "Non-Permit Confined Space". The drain is at the bottom of the pit. It has a perforated, circular cover that measures approximately 0.61 meters (2 feet) in diameter. The pumps and piping have been removed.

Location: The drain is located at the bottom of the Retention Process Sewer Pump Pit (P-3 Pump Pit). The pump pit is located at the southeast corner of the 307 Retention Basins.

Process Description: The drain received leakage and drainage from the pump. The pump was flushed with clean service water during routine freeze protection maintenance.

Waste Type: Water

Waste Description: When the site was active, it received flush water drainage and pump leakage. The source of the water was uncontaminated potable water. The flow rate was less than 0.038 liters (0.01 gallons) per minute.

Code: 300-113 **Classification:** Accepted

Names: 300-113; 340 Building Steam Condensate/ Water Heater Overflow; Miscellaneous Stream #341 **Reclassification** Rejected (1/15/1999)

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:** 1/1/1996

Description: The drain is a 0.46 meter (18 inch) diameter metal pipe that extends slightly above grade. A 1.3 centimeter (0.5 inch) diameter pipe exits the building wall and terminates over the drain. The pipe is connected to a water heater overflow valve, that is inside the 340 Building. Before the steam utility was removed from the building, the drain received steam condensate.

Location: The drain is located at the southwest corner of the 340 Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The site received steam condensate before the steam was shut off in the building. When the site was active (steam condensate), the flow rate was less than 0.038 liters (0.01 gallons) per minute. Currently, the site is set up to receive overflow from the water heater located inside the 340 Building. The flow rate for this activity is unknown. The effluent from the water heater is nondangerous/nonradioactive potable water.

Code: 300-114 **Classification:** Accepted

Names: 300-114; 340A Building Steam Condensate; Miscellaneous Stream #427 **Reclassification** Rejected (1/15/1999)

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:** 1/1/1996

Description: Currently, there are no visual surface features. The drain area was backfilled with clean gravel when the steam system was removed from the building. The gravel over the drain is slightly darker than the other gravel in the area.

Location: The site is located east of the 340A building, adjacent to the chain link fence.

Related Sites/ Structures: The site is associated with the 340A Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, it received less than 0.038 liters (0.01 gallons) per minute of steam condensate.

Code: 300-115 **Classification:** Not Accepted

Names: 300-115; 340B Building Backflow Preventer Emergency Drain; Miscellaneous Stream #426 **Reclassification** None

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:** 1/1/1996

Description: Currently, there are no visible surface features. The drain was covered with clean gravel when the source was abandoned in 1996. The gravel over the drain is slightly darker than the other gravel in the area. At least some component of the structure has been removed. The gravel would not cover the height of the exposed part of the structure. It may be that the lip of the structure was knocked into the drain or the entire drain may have been removed.

Location: The drain is located near the southeast corner of the 340B building.

Related Sites/ Structures: The site was related to the 340B Building and the service water backflow preventer.

Waste Type: Water

Waste Description: The drain would have received nondangerous/nonradioactive (potable) water in the event of a failure of the service water backflow preventer. There has been no known failure of the backflow preventer. Thus, this site would not have received any discharge.

Code: 300-116 **Classification:** Accepted

Names: 300-116; 3506A Building Steam Condensate; Miscellaneous Stream #381 **Reclassification** Rejected (12/15/1998)

Type: French Drain **Start Date:**

Status: Inactive

End Date:

Description: The site was a french drain that is covered by a 0.48 meter (1.57 foot) by 0.48 meter (1.57 foot) square metal lid. It was removed during the demolition of the 3506A and 3506B facilities in December 2012.

Although the Inventory of Miscellaneous Streams, Rev 3 lists this site as a steam condensate injection well, it has been determined that it does not meet the definition of an Underground Injection Control well (UIC).

Location: The site is located approximately 3.5 meters (11.5 feet) east of the north entry door of the 3506A Building.

Related Sites/ Structures: The site is associated with the 3506A Building and steam trap, HPD-TRP-057.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, it received less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

Code: 300-117

Classification: Accepted

Names: 300-117; 3506A Building Steam Condensate; Miscellaneous Stream #382

Reclassification: Rejected (12/15/1998)

Type: French Drain

Start Date:

Status: Inactive

End Date: 1/1/1998

Description: The site was a french drain that is constructed of concrete. It was removed during the demolition of the 3506A and 3506B facilities in December 2012. The area was backfilled in January 2013.

The top of the drain was flush with the ground surface and covered by two metal lids. Both lids were labeled "Confined Space." A metal pipe, 0.1 meters (0.3 feet) in diameter and 0.24 meters (0.79 feet) in length, extended vertically from the west lid. The metal pipe appeared to be a vent. It did not appear to extend into the cavity of the french drain. Two pipes from the overhead steam line entered the ground nearby. The drain was surrounded by gravel and a metal safety barricade. According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive, source abandoned.

Location: The site is just west of the northeast corner of the 3506A Building.

Related Sites/ Structures: The site is associated with the 3506A Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When

used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, it received less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

Code: 300-118

Classification: Accepted

Names: 300-118; 3621D Building Steam Condensate; Miscellaneous Stream #700; Pit U-7

Reclassification: Rejected (12/15/1998)

Type: Valve Pit

Start Date:

Status: Inactive

End Date: 1/1/1998

Description: The site is a valve pit with a dirt floor. Steam condensate was discharged onto the floor of the pit. The pit has a square concrete base. It is at the bottom of a slope so the top of the concrete base ranges from 21 to 35 centimeters (8.3 to 13.8 inches) above the ground surface. The valve pit is covered by an inset, square metal lid that is 0.81 meters (2.66 feet) by 0.81 meters (2.66 feet). The lid is labeled "Confined Space" and "U-7." Three valves are visible nearby (MSS-V-337, MSS-V-030 and HPD-V-3041A). Two pipes approximately 3.5 centimeters (1.4 inches) in diameter extend from the concrete base, one on the south side and one on the west side. These two pipes then make a 90 degree turn and enter the ground. During the site walkdown, a ladder, pipes and valves were visible inside the drain. Condensation was visible on the bottom of the lid and moisture was visible on the pipes and valves inside the pit and closest to the lid. At least three valves and five pipes were observed inside the structure. Also visible was an underground area that opens up to the east of the inlet. According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive, source abandoned.

Location: The site is southwest of the northwest corner of the 3621D Building. It is outside the fence that surrounds the building. The 3621D building is located southeast of the intersection of Locust Street and George Washington Way.

Related Sites/ Structures: The site is related to the 300 Area Condensate Return System.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, it received less than 0.38 liters per minute (0.1 gallons per minute) of steam condensate only.

Code: 300-119

Classification: Accepted

Names: 300-119; 3621D Air/Condensate Blowdown Drain; 3621D HVAC Condensate; Miscellaneous Stream #401

Reclassification: Rejected (12/15/1998)

Type: Injection/Reverse Well

Start Date:

Status: Inactive**End Date:**

Description: The site status was changed to inactive since Miscellaneous Stream #401 was removed in February 2011 when the 3621-D Building was demolished (per CCN 157847). The drain had been an open corrugated metal pipe filled with rocks. The source pipe exited the building wall and with a 90 degree elbow to connect the pipe to the french drain. The building wall and the french drain rocks were stained with rust. The drain structure was removed when the 3621-D building was demolished.

Location: The drain is located adjacent to the east wall of the 3621-D building inside the fenced area. The 3621D building is located southeast of the intersection of Locust Street and the George Washington Way extension.

Related Sites/ Structures: The site is related to 3621D Building.

Waste Type: Water

Waste Description: According to the "Inventory of Miscellaneous Streams", Revision 3, the site has potentially received hydrocarbons. The report documented the flow rate as less than 0.038 liters per minute (0.01 gallons per minute).

Code: 300-120**Classification:** Accepted

Names: 300-120; 3621D Air Driven Starter Motor Discharge Drain; 3621D Building Diesel Generator Cooling System Condensate; Miscellaneous Stream #402

Reclassification Rejected (12/15/1998)**Type:** Injection/Reverse Well**Start Date:****Status:** Inactive**End Date:**

Description: The drain structure was removed when the 3621-D building was demolished. The site was a 0.9 meter (2.9 feet) diameter concrete structure with a metal grate cover. The unit was filled with rocks. Four pipes, one for each air starter motor, exited the west wall of the 3621D building near the foundation. The pipes teed into a larger aboveground line that runs south, parallel to the building wall. The line elbowed to the west and then down where it is attached to the grate. The grate and the rocks were stained with a black, oily substance.

Location: The drain is located approximately 1.2 meters (4 feet) from the west wall of the 3621D building. The 3621D building is located southeast of the intersection of Locust Street and the George Washington Way extension.

Waste Type: Water

Waste Description: The site receives air and small amounts of condensate from the air starter motors in the 3621D Building. The air and condensate may contain small quantities of oil.

Code: 300-122**Classification:** Accepted

Names: 300-122; 366 Building Fuel Oil Bunker Loading Station Steam Condensate; Miscellaneous Stream #344

Reclassification Rejected (12/15/1998)**Type:** French Drain**Start Date:****Status:** Inactive**End Date:** 1/1/1998

Description: The french drain structure was removed with the 300-6 waste site. The site was a french drain that received steam condensate from the 366 Building fuel oil bunker loading station. Only a small portion of the french drain's pipe was exposed. It could not be ascertained whether the pipe was composed of clay or discolored concrete. The drain was covered with a 0.65 meter (2.13 foot) rusted metal cover and the soil and gravel surrounding the site appears to be discolored by rust. The top of the lid is 5 to 8 centimeters (2 to 3.1 inches) above ground surface. There are also granular ash deposits on the ground in the general area east/northeast of the 384 powerhouse. The ground surface surrounding the site is slightly depressed which could allow the pooling of stormwater. The site is less than a meter (3.3 feet) south of a line of posts labeled "Radiologically Controlled Area" that appears to surround the 3715 and 303E buildings. LPD-TRP-053, -057 and -058 are on a concrete pad at the northwest corner of the 366 Building. There is a black, tar-like residue on this pad. According to the "Inventory of Miscellaneous Streams," Revision 3, there was a potential for fuel oil to contaminate the discharge. The document also states the site is inactive, source abandoned.

Location: The site was located southwest of the southwest corner of the 3715 Building and north of the northwest corner of the 366 Building.

Related Sites/ Structures: This site is associated with the 366 Building fuel oil bunker loading station.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 3, the site has the potential to be contaminated with fuel oil. When this site was active, the flow rate was less than 0.38 liters per minute (0.1 gallons per minute).

DynCorp has reviewed the site and stated the following. The dark stains in the photo appear to correlate to coal powder left over from the powerhouse. There were small piles of this material throughout the area. There was a potential for runoff of fuel oil because of the proximity of the fuel bunkers. However, no fuel oil stained soil was observed near the drain and there is no evidence of discharges to this site.

Code: 300-124

Classification: Accepted

Names: 300-124; 366 Building Fuel Oil Bunker Steam Condensate; Miscellaneous Stream #653

Reclassification: Rejected (12/15/1998)

Type: French Drain

Start Date:

Status: Inactive

End Date: 1/1/1998

Description: The french drain structure was removed with the 300-6 waste site. The site was a french drain that received steam condensate from steam lines on top of the 366 Building fuel oil bunker. The french drain's metal cover was the only part of the site that is visible. It was 0.33 meters (1.08 foot) in diameter. The top of the cover was approximately 5 centimeters (2 inches) above the ground surface. There was a slight depression on the southwest side of the site where stormwater could collect. The gravel and soil surrounding the site appeared to be discolored by rust. LPD-TRP-054 is on a concrete pad by the southwest corner of 366 Building. There is a black, tar-like residue on this pad. According to the "Inventory of Miscellaneous Streams,"

Revision 3, there was a potential for fuel oil to contaminate the steam condensate. The document also states the site is inactive, source abandoned.

Location: The site was located off the southwest corner of the 366 Building.

Related Sites/ Structures: The site is associated with the 366 Building fuel oil bunker.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 3, there is a potential for fuel oil to contaminate the steam condensate. When this site was active, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute). DynCorp has reviewed the site and stated the following. The dark stains in the photo appear to correlate to coal powder left over from the powerhouse. There were small piles of this material throughout the area. There was a potential for runoff of fuel oil because of the proximity of the fuel bunkers. However, no fuel oil stained soil was observed near the drain and there is no evidence of discharges to this site.

Code: 300-125

Classification: Accepted

Names: 300-125; 3702 Building Steam Condensate; Miscellaneous Stream #346

Reclassification: Rejected (12/15/1998)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The site was a french drain that collected steam condensate. The previous location for the 3702 Building is currently a cobble-covered field. No evidence of the site remains. According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive.

Location: According to the "Inventory of Miscellaneous Streams," Revision 3, the site was located west of the stairs on the north side of the former 3702 building.

Related Sites/ Structures: The site is associated with the 3702 Building, which has been demolished.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, it received less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

Code: 300-126

Classification: Accepted

Names: 300-126; 3703 Building Steam Condensate;

Reclassification: Rejected (12/15/1998)

Miscellaneous Stream #431

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The site was a french drain that collected steam condensate. The previous location of the 3703 Building is currently a cobble and gravel covered field. No evidence of a french drain was visible during the site walkdown. According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive, source permanently abandoned.

Location: According to the "Inventory of Miscellaneous Streams," Revision 3, the site was located at the south center of the 3703 Building.

Related Sites/ Structures: The site is associated with the 3703 Building, which has been demolished.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, it received less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

Code: 300-127

Classification: Not Accepted

Names: 300-127; 3705 Building Stormwater Runoff; Miscellaneous Stream #410

Reclassification: None

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The waste site is a subsurface 16 ft long, 4 in perforated drain tile structure. The drain structure was removed during the demolition of the 3705 building, but the tile structure remains in place. Drawing research shows the effluent associated with Miscellaneous Stream #410 discharged to the subsurface perforated drain structure. Stormwater collected in the perforated, sloped pipe and discharged to the soil.

Location: The "Inventory of Miscellaneous Streams," Revision 3, states the site is located at the northeast corner of the 3705 Building.

Related Sites/ Structures: The Miscellaneous Stream site is associated with the 3705 Building.

Process Description: Stormwater was discharged from the building down spout to a 4 in cast iron pipe that discharged to the drywell structure. The drywell structure is a subsurface 16 ft long, 4 in perforated drain tile with open joints. The top of the pipe is located 3 feet below grade. The pipe trench is 6 feet wide at the top and tapers to 4 feet wide at a depth of 7 feet. The drywell structure is filled in layers of sand and gravel.

Waste Type: Stormwater Runoff

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 3, the flow rate is less than 0.038 liters per minute (0.01 gallons per minute).

Code: 300-128 **Classification:** Not Accepted
Names: 300-128; 3705 Building Stormwater Runoff; **Reclassification** None
Miscellaneous Stream #411
Type: French Drain **Start Date:**
Status: Inactive **End Date:** 1/1/1997

Description: The waste site is a subsurface 16 ft long, 4 in perforated drain tile structure. The drain structure was removed during the demolition of the 3705 building, but the tile structure remains in place. Drawing research shows the effluent associated with Miscellaneous Stream #411 discharged to the subsurface perforated drain structure. Stormwater collected in the perforated, sloped pipe and discharged to the soil.

Location: The "Inventory of Miscellaneous Streams," Revision 3, states the site was located at the northwest corner of the 3705 Building.

Related Sites/ Structures: The Miscellaneous Stream is associated with the 3705 Building.

Process Description: Stormwater was discharged from the building down spout to a 4 in cast iron pipe that discharged to the drywell structure. The drywell structure is a subsurface 16 ft long, 4 in perforated drain tile with open joints. The top of the pipe is located 3 feet below grade. The pipe trench is 6 feet wide at the top and tapers to 4 feet wide at a depth of 7 feet. The drywell structure is filled is in layers of sand and gravel.

Waste Type: Stormwater Runoff

Waste Description: When the site was active, it received less than 0.038 liters per minute (0.01 gallons per minute) of stormwater runoff.

Code: 300-129 **Classification:** Not Accepted
Names: 300-129; 3705 Building Stormwater Runoff; **Reclassification** None
Miscellaneous Stream #412
Type: French Drain **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is a subsurface 16 ft long, 4 in perforated drain tile structure. The drain structure was removed during the demolition of the 3705 building, but the tile structure remains in place. Drawing research shows the effluent associated with Miscellaneous Stream #412 discharged to the subsurface perforated drain structure. Stormwater collected in the perforated, sloped pipe and discharged to the soil.

Location: The "Inventory of Miscellaneous Streams," Revision 3, states the site is at the southeast corner of the 3705 Building.

Related Sites/ Structures: The Miscellaneous Stream is associated with the 3705 Building.

Process Description: Stormwater was discharged from the building down spout to a 4 in cast iron pipe that discharged to the drywell structure. The drywell structure is a subsurface 16 ft long, 4 in perforated drain tile with open joints. The top of the pipe is located 3 feet below grade. The pipe trench is 6 feet wide at the top and tapers to 4 feet wide at a depth of 7 feet. The drywell structure is filled is in layers of sand and gravel.

Waste Type: Stormwater Runoff

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 3, the flow is less than 0.038 liters per minute (0.01 gallons per minute).

Code: 300-130

Classification: Not Accepted

Names: 300-130; 3705 Building Stormwater Runoff; Miscellaneous Stream #413

Reclassification: None

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The waste site is a subsurface 16 ft long, 4 in perforated drain tile structure. The drain structure was removed during the demolition of the 3705 building, but the tile structure remains in place. Drawing research shows the effluent associated with Miscellaneous Stream #413 discharged to the subsurface perforated drain structure. Stormwater collected in the perforated, sloped pipe and discharged to the soil.

Location: The "Inventory of Miscellaneous Streams," Revision 3, states the site is at the southwest corner of the 3705 Building.

Related Sites/ Structures: The Miscellaneous Stream is associated with the 3705 Building.

Process Description: Stormwater was discharged from the building down spout to a 4 in cast iron pipe that discharged to the drywell structure. The drywell structure is a subsurface 16 ft long, 4 in perforated drain tile with open joints. The top of the pipe is located 3 feet below grade. The pipe trench is 6 feet wide at the top and tapers to 4 feet wide at a depth of 7 feet. The drywell structure is filled in layers of sand and gravel.

Waste Type: Stormwater Runoff

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 3, the flow is less than 0.038 liters per minute (0.01 gallons per minute).

Code: 300-131

Classification: Accepted

Names: 300-131; 3706 Fire Sprinkler System Water; Miscellaneous Stream #515

Reclassification: Consolidated (1/19/1999)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The site is a french drain that is the discharge point for fire sprinkler system water. The drain is a clay pipe with the outer diameter of 0.42 meters (1.38 feet) and is not covered by a lid. The top of the clay pipe is above grade except where moss is encroaching. The pipe appears to be filled with cobbles and rocks to within 0.3 meters (0.98 feet) of its top. The rocks and cobbles inside the drain appear rusty. Above the site are two capped metal ports labeled "Fire Department Connection." Below these ports, two metal pipes extend from the building and terminate with open ends above the drain. One of these pipes is approximately 5 centimeters (2 inches) in diameter and the other is approximately 2 centimeters (0.8 inches) in diameter. During the October 26, 1998, walkdown, an opening in the side of the building for a third pipe was observed; this opening has not been plugged. The site is surrounded by sand, gravel and moss. The south side of the drain abuts the 3706 Building, which is posted "Fixed Contamination Area." The drain is within the footprint of the WIDS site 300-46, which

estimates the extent of extensive uranium, transuranic and chemical contamination of the 3706 Building and the surrounding area. Nineteen recognized miscellaneous stream drains were located within the boundary of the waste site and have been consolidated with 300-46.

Location: The site is located on the north side of the 3706 Building. It is approximately 5.5 meters (18 feet) east of door #06.

Release Description: There were no known hazardous or radioactive releases from this water discharge.

Related Sites/ Structures: The site is associated with the 3706 Building.

Waste Type: Water

Waste Description: The site receives drainage from the fire sprinkler system at a rate of less than 3.8 liters per minute (1 gallon per minute). Fire sprinkler water is exempt from permitting. However, based on past practice activities at the 3706 Building and potential releases to the soil column, the disposal structure and soil should be surveyed to determine if radioactive contamination is present. The disposal structure is immediately adjacent to the 3706 Building.

This Site Was Consolidated With:

Code: 300-46

Names: 300-46; Soil Contamination and French Drains Surrounding 3706 Building

Code: 300-132

Classification: Accepted

Names: 300-132; 3706 Building Steam Condensate; Miscellaneous Stream #368

Reclassification: Consolidated (1/19/1999)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The site has been described as a french drain that received steam condensate. Although the Inventory of Miscellaneous Streams, Rev 3 lists this site as a steam condensate injection well, it has been determined that it does not meet the definition of an Underground Injection Control well (UIC).

During the November 18, 1998, walkdown, there did not appear to be an engineered structure at the site's location. The site appears to be a rock and cobble filled depression next to the 3706 Building. The depression is surrounded by soil-covered asphalt. The rocks and cobbles in the depression as well as the side of the 3706 Building appear to be rust stained. On the south side of Door #02, an approximately 10 centimeter (4 inch) diameter metal pipe exits the east side of the 3706 Building, turns and enters the ground. Forty centimeters (1.3 feet) to the east of this pipe is a concrete structure with a 0.66 meter (2.17 feet) by 0.66 meter (2.17 feet) metal cover. In addition to steam condensate, the site also appears to have received fire sprinkler system water. Four metal pipes terminate over the depression. Three of these four pipes exit the east side of the 3706 Building near a Fire Department Connection. An approximately 2 centimeter (0.8 inch) diameter metal pipe extends from the building 0.95 meters (3.1 feet) above the ground surface; an approximately 6 centimeter (2.4 inch) diameter metal pipe extends from the building 0.90 meters (3 feet) above the ground surface and an approximately 4 centimeter (1.6 inch) metal pipe extends from the building 0.8 meters (2.6 feet) above the ground surface. These three pipes terminate open-ended over the depression. The fourth pipe is approximately 8 centimeters (3.1 inches) in diameter and exits the building 3 to 4 meters (9.8 to 13.1 feet) above the ground surface. It could not be ascertained whether this pipe is still open or whether it had been plugged. There is a U-shaped section of 8 centimeter (3.1 inches) pipe attached to the east wall of the 3706 Building just below the Fire Department Connection; this section of pipe has

open ends. According to John Remaize, the steam and fire water for the building are still active. According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive, source abandoned. The 3706 Building is posted "Fixed Contamination Area." The drain is within the footprint of the WIDS site 300-46, which estimates the extent of extensive uranium, transuranic and chemical contamination of the 3706 Building and the surrounding area. Nineteen recognized miscellaneous stream drains were located within the boundary of the waste site and have been consolidated with 300-46.

Location: The site is on the east side of the 3706 Building, just north of door #02.

Release Description: There were no known hazardous or radioactive releases from this steam condensate discharge.

Related Sites/ Structures: The site is associated with the 3706 Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute).

This Site Was Consolidated With:

Code: 300-46

Names: 300-46; Soil Contamination and French Drains Surrounding 3706 Building

Code: 300-133

Classification: Accepted

Names: 300-133; 3706 Building Steam Condensate; Injection Well #27; Miscellaneous Stream #367

Reclassification: Consolidated (1/19/1999)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The site is a french drain that used to receive steam condensate. Although the Inventory of Miscellaneous Streams, Rev 3 lists this site as a steam condensate injection well, it has been determined that it does not meet the definition of an Underground Injection Control well (UIC).

The drain has a square concrete base with a 0.66 meter (2.17 foot) by 0.66 meter (2.17 foot) metal lid. What appear to be rust stains are on the lid and surrounding concrete. The remains of "FD 27" written in paint can be seen on the side of the building next to the site. There is also writing on the metal lid but it is illegible due to age. Two metal pipes, both approximately 3.5 centimeters (1.4 inches) in diameter, extend from the east side of the 3706 Building and enter the lid. A metal pipe elbow extends from the ground between the site and 3706. This pipe is approximately 5 centimeters (2 inches) in diameter and terminates open ended. A third steam pipe extends from the east side of the 3706 Building approximately 2.5 meters (8.2 feet) north of the site. This pipe terminates approximately 0.5 meters (1.6 feet) above the ground surface and appears to have been plugged. The site is surrounded by concrete and sand. The 3706 Building is posted "Fixed Contamination Area." The drain is within the footprint of the WIDS Site 300-46 which estimates the extent of extensive uranium, transuranic and chemical contamination of the 3706 Building and the surrounding area. According to the "Inventory of

Miscellaneous Streams," Revision 3, the site is inactive, source abandoned. Nineteen recognized miscellaneous stream drains were located within the boundary of the waste site and have been consolidated with 300-46.

Location: Located north of the former Health Service Center on the east side of 3706.

Release Description: There were no known hazardous or radioactive releases from this steam condensate discharge.

Related Sites/ Structures: The site is associated with the 3706 Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

This Site Was Consolidated With:

Code: 300-46

Names: 300-46; Soil Contamination and French Drains Surrounding 3706 Building

Code: 300-134

Classification: Accepted

Names: 300-134; 3706 Building Steam Condensate; Miscellaneous Stream #362

Reclassification: Consolidated (1/19/1999)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The site is a french drain that received steam condensate. The drain has a concrete base and is covered by a 0.66 meter (2.17 foot) by 0.66 meter (2.17 foot) metal lid. The site is surrounded by gravel and weeds. An approximately 2.5 centimeter (1 inch) diameter metal pipe extends from the east wall of the courtyard, makes a 90 degree turn and enters the ground approximately 0.5 meters (1.6 feet) from the site. According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive, source abandoned. The 3706 Building is posted "Fixed Contamination Area." The drain is within the footprint of the WIDS Site 300-46, which estimates the extent of extensive uranium, transuranic and chemical contamination of the 3706 Building and the surrounding area. Nineteen recognized miscellaneous stream drains were located within the boundary of the waste site and have been consolidated with 300-46.

Location: The site is located in the eastern courtyard of the 3706 Building. It is located along the east wall, almost 5 meters (16.4 feet) from the northeast corner.

Release Description: There were no known hazardous or radioactive releases from this steam condensate discharge.

Related Sites/ Structures: The site is associated with the 3706 Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and

process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

This Site Was Consolidated With:

Code: 300-46

Names: 300-46; Soil Contamination and French Drains Surrounding 3706 Building

Code: 300-135

Classification: Accepted

Names: 300-135; 3706 Building Steam Condensate; Miscellaneous Stream #365

Reclassification: Consolidated (1/19/1999)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The site is a french drain that received steam condensate. The drain is a clay pipe that abuts the north wall of the 3706 Building. The top of the clay pipe ranges from 2 to 4 centimeters (0.8 to 1.6 inches) above the ground surface, except on its southwest side where the pipe is broken. Stormwater runoff may be able to enter the drain through this break. The drain is covered by a 0.77 meter (2.53 foot) metal lid with two handles and an opening that could allow condensate pipes to enter. Any lines that may have entered the drain have been removed; no lines were visible during the November 20, 1998, walkdown. However, there are at least three plugged holes visible in the building wall above the site. These holes are 0.75 meters (2.5 feet), 1.52 meters (5 feet) and 1.7 meters (5.6 feet) above the ground surface. The drain is next to an HVAC unit with a label that reads "RM 13 HVAC MAIN DISC." The site is surrounded by sand, gravel and cobbles. Moss is growing along the north wall of the building and between the drain and the building. Standing water was visible inside the drain during the November 20, 1998, walkdown. Approximately 1 meter (3.2 feet) of the drain was visible above the water. No pipes or openings were visible inside the drain. John Remaize believes this stream is actually the site just west of Door #06. According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive, source abandoned. The 3706 Building is posted "Fixed Contamination Area." The drain is within the footprint of the WIDS Site 300-46, which estimates the extent of extensive uranium, transuranic and chemical contamination of the 3706 Building and the surrounding area. Nineteen recognized miscellaneous stream drains were located within the boundary of the waste site and have been consolidated with 300-46.

Location: The site is on the north side of the 3706 Building, east of Door #07 and just west of an HVAC unit.

Release Description: There were no known hazardous or radioactive releases from this steam condensate discharge.

Related Sites/Structures: The site is associated with the 3706 Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute).

This Site Was Consolidated With:

Code: 300-46

Names: 300-46; Soil Contamination and French Drains Surrounding 3706 Building

Code: 300-136

Classification: Accepted

Names: 300-136; 3706 Building Steam Condensate; Miscellaneous Stream #366

Reclassification: Consolidated (1/19/1999)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The site is a french drain that received steam condensate. The drain is a clay pipe with an outer diameter of 0.85 meters (2.79 feet). The drain is covered by a metal lid with some perforations. The site is surrounded by sand and gravel, some of which partially covers the lid. The upper lip of the clay pipe is breaking up. The top of the pipe is flush with the ground surface for approximately half of its circumference; the rest is 1 to 2 centimeters (0.4 - 0.8 inches) above the ground surface. Two roof drains are visible nearby; some stormwater runoff may be able to enter the drain. Two metal pipes extend from the 3706 Building approximately 3 meters (9.8 feet) west of the site and enter the ground. One pipe is approximately 5 centimeters (2 inches) in diameter and the other is approximately 12 centimeters (4.7 inches) in diameter. The "Inventory of Miscellaneous Streams," Revision 3, lists the site as inactive, source abandoned. The 3706 Building is posted "Fixed Contamination Area." The drain is within the footprint of the WIDS Site 300-46, which estimates the extent of extensive uranium, transuranic and chemical contamination of the 3706 Building and the surrounding area. Nineteen recognized miscellaneous stream drains were located within the boundary of the waste site and have been consolidated with 300-46.

Location: The site is approximately 10 meters (32.8 feet) east of the westernmost entrance on the north side of the 3706 Building, and just west of Door #07.

Release Description: There were no known hazardous or radioactive releases from this steam condensate discharge.

Related Sites/Structures: The site is associated with the 3706 Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute).

This Site Was Consolidated With:

Code: 300-46

Names: 300-46; Soil Contamination and French Drains Surrounding 3706 Building

Code: 300-137 **Classification:** Accepted
Names: 300-137; 3706 Building Steam Condensate; Miscellaneous Stream #440 **Reclassification** Consolidated (1/19/1999)
Type: French Drain **Start Date:**
Status: Inactive **End Date:**

Description: Nineteen recognized miscellaneous stream drains were located within the boundary of the 3706 waste site and have been consolidated with 300-46.

The site has been described as a french drain that received steam condensate. During the November 20, 1998, walkdown, an engineered structure could not be discerned. It could not be ascertained whether or not the condensate stream was active or not, but the overhead steam line from 3706-BA, which is on the opposite side of Apple Street, to the 3706 Building did appear to be active - water was dripping from a valve labeled MSS-V-3706. The overhead steam line splits in two outside the 3706 Building. One of the lines enters the north side of the building and the other disappears into the sand. The latter is approximately 9 centimeters (3.6 inches) in diameter. There are pipes extending from the 3706 Building on either side of this site. John Remaize believes this site is actually located just west of the third window west of Door #06. According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive, source abandoned. The 3706 Building is posted "Fixed Contamination Area." The drain is within the footprint of the WIDS Site 300-46, which estimates the extent of extensive uranium, transuranic and chemical contamination of the 3706 Building and the surrounding area.

Location: The site is on the north side of the 3706 Building, just west of Door #06.

Release Description: There were no known hazardous or radioactive releases from this steam condensate discharge.

Related Sites/ Structures: The site is associated with the 3706 Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute).

This Site Was Consolidated With:

Code: 300-46
Names: 300-46; Soil Contamination and French Drains Surrounding 3706 Building

Code: 300-138 **Classification:** Accepted
Names: 300-138; 3706 Building Steam Condensate; Miscellaneous Stream #360 **Reclassification** Consolidated (1/19/1999)
Type: French Drain **Start Date:**
Status: Inactive **End Date:**

Description: The site is a french drain that received steam condensate. Although the Inventory of Miscellaneous Streams, Rev 3 lists this site as a steam condensate injection well, it has been determined that it does not meet the definition of an Underground Injection Control well (UIC).

The drain has a concrete base and is covered by a 0.66 meter (2.17 feet) by 0.66 meter (2.17 feet) metal lid. The site is surrounded by gravel. An approximately 2.5 centimeter (1 inch) diameter metal pipe extends from the north wall of the courtyard, makes a 90 degree turn and enters the ground approximately 0.5 meters (1.6 feet) from the site. This pipe has had a section removed from it. The area between the site and the north wall of the courtyard appears to be discolored by rust. The "Inventory of Miscellaneous Streams," Revision 3, lists the site as inactive, source abandoned. The 3706 Building is posted "Fixed Contamination Area." The drain is within the footprint of the WIDS Site 300-46, which estimates the extent of extensive uranium, transuranic and chemical contamination of the 3706 Building and the surrounding area. Nineteen recognized miscellaneous stream drains were located within the boundary of the waste site and have been consolidated with 300-46.

Location: The site is located in the eastern courtyard of the 3706 Building. It is located along the north wall of the courtyard, approximately 13 meters (42.7 feet) west of the northeast corner.

Release Description: There were no known hazardous or radioactive releases from this steam condensate discharge.

Related Sites/ Structures: The site is associated with the 3706 Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

This Site Was Consolidated With:

Code: 300-46

Names: 300-46; Soil Contamination and French Drains Surrounding 3706 Building

Code: 300-139

Classification: Accepted

Names: 300-139; 3706 Building Steam Condensate; Miscellaneous Stream #357

Reclassification: Consolidated (1/19/1999)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: Nineteen recognized miscellaneous stream drains were located within the boundary of the 3706 waste site and have been consolidated with 300-46. The site is a french drain that received steam condensate. The drain is a clay pipe covered by a 0.77 meter (2.53 foot) diameter metal lid. The lid has perforations in it. The 3706 Building has been demolished. The drain is within the footprint of the WIDS Site 300-46, which estimates the extent of extensive uranium, transuranic and chemical contamination of the 3706 Building and the surrounding area.

Location: The site is located in the middle courtyard of the 3706 Building. It is approximately 3 meters (9.8 feet) from the northeast corner of the courtyard.

Release Description: There were no known hazardous or radioactive releases from this steam condensate discharge.

Related Sites/ Structures: The site is associated with the 3706 Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, the flow rate was less than 0.19 liters per minute (0.05 gallons per minute) of steam condensate only.

This Site Was Consolidated With:

Code: 300-46

Names: 300-46; Soil Contamination and French Drains Surrounding 3706 Building

Code: 300-140

Classification: Accepted

Names: 300-140; 3706 Building Steam Condensate; Miscellaneous Stream #356

Reclassification: Consolidated (1/19/1999)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The site is a french drain that received steam condensate. Although the Inventory of Miscellaneous Streams, Rev 3 lists this site as a steam condensate injection well, it has been determined that it does not meet the definition of an Underground Injection Control well (UIC).

The drain is a concrete structure with the inner dimensions of 0.82 meters (2.69 feet) by 0.60 meters (1.97 feet) and is covered by a metal grate. The drain abuts the north wall of the 3706 Building. A second concrete structure abuts the drain to the north. This second structure is covered by a 0.66 meter (2.17 feet) by 0.66 meter (2.17 feet) metal lid. An approximately 10 centimeter (4 inch) diameter opening is visible on the north side of the drain, almost 0.6 meters (2 feet) from its top. Access to the process sewer is approximately 3.5 meters (11.5 feet) to the northeast of the site. It appears as though the drain received fire sprinkler system water in addition to steam condensate. Four metal pipes terminate open-ended over the drain's grate. An approximately 6 centimeter (2.4 inch) pipe extends from the north side of the 3706 Building 0.95 meters (3.1 feet) above the ground surface; an approximately 4 centimeter (1.6 inch) pipe extends from the building 0.6 meters (2 feet) above the ground surface; an approximately 2 centimeter (0.8 inch) pipe extends from the building 0.52 meters (1.7 feet) above the ground surface, and an approximately 3 centimeter (1.2 inch) pipe extends from the building 0.15 meters (0.5 feet) above the ground surface. All four pipes exit the building near a Fire Department Connection. The pipes entering the drain and the grate covering the drain appear to be discolored by rust. Approximately a meter to the east of the site, what appears to be an approximately 15 centimeter (5.9 inch) diameter steam pipe enters the ground. The lower 1.2 meters (3.9 feet) of this pipe appear to be of newer construction than the upper section; the upper section has rust marks from the wires that encircle it while the lower section doesn't. During the November 18, 1998, walkdown, there was standing water in the drain. The surface of the water was approximately 0.6 meters (2 feet) from the top of the drain. There had not been any rainfall for almost 2 weeks at that time. According to John Remaize, the steam and fire

water for the building are still active. There is a 30 centimeter (11.8 inches) diameter clay pipe 4.3 meters (14.1 feet) east of the site. According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive, source abandoned. The 3706 Building is posted "Fixed Contamination Area." The drain is within the footprint of the WIDS Site 300-46, which estimates the extent of extensive uranium, transuranic and chemical contamination of the 3706 Building and the surrounding area. Nineteen recognized miscellaneous stream drains were located within the boundary of the waste site and have been consolidated with 300-46.

Location: The site is located on the north side of the 3706 Building, near the northeast corner. The site is just east of Door #05.

Release Description: There were no known hazardous or radioactive releases from this steam condensate discharge.

Related Sites/ Structures: The site is associated with the 3706 Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, the flow rate was less than 0.19 liters per minute (0.05 gallons per minute).

This Site Was Consolidated With:

Code: 300-46

Names: 300-46; Soil Contamination and French Drains Surrounding 3706 Building

Code: 300-141

Classification: Accepted

Names: 300-141; 3706 Building Steam Condensate; Injection Well #29; Miscellaneous Stream #439

Reclassification: Consolidated (1/19/1999)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The french drain has been excavated and removed. The waste site was a french drain that received steam condensate. The drain appeared to be a concrete pipe with a 0.91 meter (3 foot) metal lid at grade level; however, the site is well obscured by sand and gravel. During the October 26, 1998, walkdown, the metal lid appeared to be ajar. There are two steam pipes entering the ground approximately 3 meters (9.8 feet) west of the site. One of these pipes is approximately 7 centimeters (2.8 inches) in diameter and the other is approximately 8 centimeters (3.1 inches) in diameter. There is also a metal pipe extending from the south side of the building next to the site. This pipe terminates approximately 1.8 meters (5.9 feet) above the ground surface and has been plugged. This third pipe is approximately 5 centimeters (2 inches) in diameter. The site is surrounded by sand and gravel. The 3706 Building was posted "Fixed Contamination Area." The drain was within the footprint of WIDS Site 300-46, which estimates the extent of extensive uranium, transuranic and chemical contamination of the 3706 Building and the surrounding area. According to the "Inventory of Miscellaneous Streams," Revision 3, the french drain is inactive, source abandoned. Nineteen recognized miscellaneous stream drains were located within the boundary of the waste site and have been consolidated with 300-46.

Location: The site was located on the south side of the 3706 Building, approximately 4.5 meters (14.8 feet) east of Door #01.

Release Description: There were no known hazardous or radioactive releases from this steam condensate discharge.

Related Sites/Structures: The site is associated with the 3706 Building and WIDS sitecode 300-46.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

This Site Was Consolidated With:

Code: 300-46

Names: 300-46; Soil Contamination and French Drains Surrounding 3706 Building

Code: 300-142

Classification: Accepted

Names: 300-142; 3706 Building Steam Condensate; Injection Well #30; Miscellaneous Stream #369

Reclassification: Consolidated (1/19/1999)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The french drain has been excavated and removed. The waste site was a french drain that received steam condensate. The drain was an open clay pipe that abuts the south wall of the 3706 Building and is surrounded by asphalt and sand. The inner diameter of the top 7 centimeters (2.8 inches) of the pipe is 0.55 meter (1.80 feet). Below the top 7 centimeters (2.8 inches), the inner diameter is reduced to 0.44 meters (1.4 feet). The top of the pipe rises approximately 0.35 meters (1.1 feet) above the ground surface. The bottom of the drain is covered by debris. The top of the debris is approximately 0.7 meters (2.3 feet) below the top of the pipe. No pipes are visible entering the drain. However, there are two approximately 2.5 centimeter (1 inch) holes drilled into the side of the pipe. The clay around these holes as well as the interior of the pipe appear to be rust stained. An approximately 3 centimeter (1.2 inches) metal pipe exits the building 0.6 meters (2 feet) above the ground surface, makes a 90 degree turn and enters the ground approximately 0.6 meters (2 feet) east of the drain. Further east, on the opposite side of a wall extension, there is an approximately 5 centimeter (2 inch) metal pipe that exits the building approximately 0.45 meter (1.5 feet) above the ground surface and enters the ground. This second pipe is approximately 1.8 meters (5.9 feet) from the site and approximately 1 meter (3.2 feet) from a second clay pipe. This second clay pipe is approximately 0.75 meters (2.5 feet) in diameter. According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive, source abandoned. The 3706 Building is posted "Fixed Contamination Area." The drain was within the footprint of the WIDS Site 300-46, which estimates the extent of extensive uranium, transuranic and chemical contamination of the 3706 Building and the surrounding area. Nineteen recognized miscellaneous stream drains were located within the boundary of the waste site and have been consolidated with 300-46.

Location: The drain was located on the south side of the 3706 Building near the southwest entrance door.

It is approximately 3.5 meters (11.5 feet) east of Door #11.

Release Description: There were no known hazardous or radioactive releases from this steam condensate discharge.

Related Sites/ Structures: The site is associated with the 3706 Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute).

This Site Was Consolidated With:

Code: 300-46

Names: 300-46; Soil Contamination and French Drains Surrounding 3706 Building

Code: 300-143

Classification: Accepted

Names: 300-143; 3706 Building Steam Condensate; Miscellaneous Stream #361

Reclassification: Consolidated (1/19/1999)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The site is a french drain that receives steam condensate. Although the Inventory of Miscellaneous Streams, Rev 3 lists this site as a steam condensate injection well, it has been determined that it does not meet the definition of an Underground Injection Control well (UIC).

The drain has a concrete base and is covered by a 0.66 meter (2.17 foot) by 0.66 meter (2.17 foot) metal lid. The site is surrounded by gravel and weeds. During the November 11, 1998, walkdown, the lid could not be removed. From the outside, there are no apparent steam lines entering the site. There are pipes extending from the south wall of the courtyard, but none near the drain. The 3706 Building is posted "Fixed Contamination Area." The site falls within WIDS Site 300-46 which estimates the extent of extensive uranium, transuranic and chemical contamination of the 3706 Building and the surrounding area. Nineteen recognized miscellaneous stream drains were located within the boundary of the waste site and have been consolidated with 300-46.

Location: The site is located in the eastern courtyard of the 3706 Building. It is along the south wall of the courtyard, approximately 15.3 meters (50.2 feet) from the southeast corner.

Release Description: There were no known hazardous or radioactive releases from this steam condensate discharge.

Related Sites/ Structures: The site is associated with the 3706 Building.

Process Description: Steam is produced from sanitary water that has been sent through a water softener system to remove minerals (calcium and magnesium). The treated water is introduced into boilers to produce steam. This steam is superheated before distribution to facilities for heating and

process use. Disposal sites receive steam condensate from the steam distribution lines. When used for heating purposes, this is a seasonal discharge. Non-regulated chemicals are added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 3, the flow is less than 0.038 liters per minute (0.01 gallons per minute).

This Site Was Consolidated With:

Code: 300-46

Names: 300-46; Soil Contamination and French Drains Surrounding 3706 Building

Code: 300-144

Classification: Accepted

Names: 300-144; 3706 Building Steam Condensate; Miscellaneous Stream #358

Reclassification: Consolidated (1/19/1999)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The site is a french drain that received steam condensate. The drain is a clay pipe covered by a 0.85 meter (2.79 foot) diameter metal lid. The top of the clay pipe is approximately 0.3 meters (1 foot) above the ground surface. The lid has an opening allowing pipes to enter the drain. An approximately 2.5 centimeter (1 inch) metal pipe and an approximately 1.3 centimeter (0.5 inch) diameter clear, plastic hose enter the drain through this opening. The plastic hose is attached to what appears to be a steam line extending through an old window or other former opening in the west wall of the courtyard. This opening is 2 to 3 meters (6.6 to 9.8 feet) north of the site and is currently boarded up. An approximately 5 centimeter (2 inch) diameter metal pipe exits the west wall of the courtyard, makes a 90 degree turn and enters the ground near the pipe. The clay pipe is broken, making removal of the lid unsafe. During the November 11, 1998, walkdown, the interior appeared dry when viewed through a break in the clay pipe. The site is surrounded by sand. The site falls within WIDS Site 300-46 which estimates the extent of extensive uranium, transuranic and chemical contamination of the 3706 Building and the surrounding area. According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive, source abandoned. Nineteen recognized miscellaneous stream drains were located within the boundary of the waste site and have been consolidated with 300-46.

Location: The site is located in the middle courtyard of the 3706 Building. It is approximately 8.5 meters (27.9 feet) north of the south entrance to the courtyard, abutting the west wall.

Release Description: There were no known hazardous or radioactive releases from this steam condensate discharge.

Related Sites/Structures: The site is associated with the 3706 Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, the flow rate was less than 0.19 liters per minute (0.05 gallons per minute) of steam condensate only.

This Site Was Consolidated With:**Code:** 300-46**Names:** 300-46; Soil Contamination and French Drains Surrounding 3706 Building**Code:** 300-145**Classification:** Accepted**Names:** 300-145; 3706 Building Steam Condensate; Injection Well #25; Miscellaneous Stream #438**Reclassification:** Consolidated (1/19/1999)**Type:** French Drain**Start Date:****Status:** Inactive**End Date:**

Description: The site is a french drain that received steam condensate. The drain is a clay pipe covered by a 0.78 meter (2.56 foot) metal cover. The lid is posted "Confined Space." The lip of the pipe is broken on its northeast side; this could allow stormwater runoff to enter. "FD 25" is written on the wall of the 3706 Building above the site. A metal pipe approximately 2.5 centimeters (1 inch) in diameter extends from the west side of 3706 just south of the site. This pipe exits the building approximately 3 meters (10 feet) above the ground surface and terminates approximately 15 centimeters (5.9 inches) after leaving the building. It was difficult to ascertain whether the pipe was plugged or not. The side of the building below this pipe appears to have rust stains. A second metal pipe approximately 2.5 centimeters (1 inch) in diameter extends from the south side of 3706, just around the corner from the site. This pipe leaves the building approximately 0.9 meters (3 feet) above the ground surface and disappears into the ground. The site is surrounded by soil and gravel. Moss is growing on the south side of the drain. The 3706 Building is posted "Fixed Contamination Area." The site falls within WIDS Site 300-46 which estimates the extent of extensive uranium, transuranic and chemical contamination of the 3706 Building and the surrounding area. According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive, source abandoned. Nineteen drains were consolidated with 300-46.

Location: The site is on the west wall of the 3706 Building, adjacent to the southwest corner.**Release Description:** There were no known hazardous or radioactive releases from this steam condensate discharge.**Related Sites/ Structures:**

The site is associated with the 3706 Building.

Process Description:

Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate**Waste Description:** When the site was active, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.**This Site Was Consolidated With:****Code:** 300-46**Names:** 300-46; Soil Contamination and French Drains Surrounding 3706 Building**Code:** 300-146**Classification:** Accepted

Names: 300-146; 3706 Building Stormwater Runoff; Miscellaneous Stream #364 **Reclassification** Consolidated (1/19/1999)

Type: French Drain **Start Date:**

Status: Inactive **End Date:**

Description: The site is a french drain that received stormwater runoff. Although the Inventory of Miscellaneous Streams, Rev 3 lists this site as a steam condensate injection well, it has been determined that it does not meet the definition of an Underground Injection Control well (UIC).

The drain is made of concrete and is covered by a 0.90 meter (2.95 foot) by 0.45 meter (1.48 foot) metal grate. An approximately 0.3 meter (1 foot) diameter metal pipe enters the east side of the drain. The site is surrounded by gravel and weeds. During the November 11, 1998, walkdown, standing water was visible through the grate; it had rained over the past week. The standing water made it difficult to estimate the depth of the drain, but it appears to be at least 0.9 meters (3 feet) deep. The 3706 Building is posted "Fixed Contamination Area." The site falls within WIDS Site 300-46 which estimates the extent of extensive uranium, transuranic and chemical contamination of the 3706 Building and the surrounding area. Twenty recognized miscellaneous stream drains were located within the boundary of the waste site and have been consolidated with 300-46. Nineteen recognized miscellaneous stream drains were located within the boundary of the waste site and have been consolidated with 300-46.

Location: The site is located in the eastern courtyard of the 3706 Building. It is located approximately 8 meters (26.2 feet) from the western wall, near the center of the courtyard.

Release Description: There were no known hazardous or radioactive releases from this water discharge.

Related Sites/ Structures: The site is associated with the 3706 Building.

Waste Type: Stormwater Runoff

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 3, the flow is less than 0.01 gallons per minute.

This Site Was Consolidated With:

Code: 300-46

Names: 300-46; Soil Contamination and French Drains Surrounding 3706 Building

Code: 300-147 **Classification:** Accepted

Names: 300-147; 3706 Building Stormwater Runoff; Miscellaneous Stream #363 **Reclassification** Consolidated (1/19/1999)

Type: French Drain **Start Date:**

Status: Inactive **End Date:**

Description: The site is a french drain that receives stormwater runoff. Although the Inventory of Miscellaneous Streams, Rev 3 lists this site as a steam condensate injection well, it has been determined that it does not meet the definition of an Underground Injection Control well (UIC).

The drain is made of concrete and is covered by a 0.90 meter (2.95 foot) by 0.45 meter (1.48 foot) metal grate. The drain appears to be approximately 0.9 meters (3 feet) deep. An approximately 0.3 meter (1 foot) diameter metal pipe enters the eastern side of the drain. The site is surrounded by gravel and weeds. During the November 11, 1998, walkdown, the drain appeared to be dry, its bottom covered by debris. The 3706 Building is posted "Fixed

Contamination Area." The site falls within WIDS Site 300-46 which estimates the extent of extensive uranium, transuranic and chemical contamination of the 3706 Building and the surrounding area. Nineteen recognized miscellaneous stream drains were located within the boundary of the waste site and have been consolidated with 300-46.

Location: The site is located in the eastern courtyard of the 3706 Building. It is approximately 8 meters (26.2 feet) from the eastern wall, towards the center of the courtyard.

Release Description: There were no known hazardous or radioactive releases from this water discharge.

Related Sites/ Structures: The site is associated with the 3706 Building.

Waste Type: Stormwater Runoff

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 3, the flow is less than 0.038 liters per minute (0.01 gallons per minute).

This Site Was Consolidated With:

Code: 300-46

Names: 300-46; Soil Contamination and French Drains Surrounding 3706 Building

Code: 300-148

Classification: Accepted

Names: 300-148; 3706 Building Stormwater Runoff; Injection Well #22; Miscellaneous Stream #359

Reclassification: Consolidated (1/19/1999)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The site is described by the "Inventory of Miscellaneous Streams," Revision 3, as a french drain that collects stormwater runoff. The drain is an uncovered concrete pipe with an outer diameter of 0.9 meters (2.95 feet). The top of the pipe is flush with the ground surface on its southeast side while the northwest side is 7 centimeters (2.8 inches) above grade. The pipe appears to be filled with gravel and large rocks to within centimeters of its top. The drain is surrounded by gravel and soil. There is no evidence of a roof drain at this site. A 2.5 centimeter (1 inch) diameter metal pipe exits the west side of the building approximately 1.8 meters (5.9 feet) above the ground surface, makes a 90 degree turn towards the ground and terminates open-ended approximately 0.75 meters (2.5 feet) above the ground. The side of the drain closest to the 3706 Building, the gravel and rock between the building and the drain, as well as the side of the 3706 Building adjacent to the site all appear to be discolored by rust. The 3706 Building is posted "Fixed Contamination Area." The site falls within WIDS Site 300-46 which estimates the extent of extensive uranium, transuranic and chemical contamination of the 3706 Building and the surrounding area. Nineteen recognized miscellaneous stream drains were located within the boundary of the waste site and have been consolidated with 300-46.

Location: The site is located just west of the northwest corner of the 3706 Building.

Release Description: There were no known hazardous or radioactive releases from this water discharge.

Related Sites/ Structures: The site is associated with the 3706 Building.

Waste Type: Stormwater Runoff

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 3, the flow is less than 0.038 liters per minute (0.01 gallons per minute). During the October 26, 1998, walkdown, the site

appeared to be a steam condensate site as opposed to a stormwater site.

This Site Was Consolidated With:

Code: 300-46

Names: 300-46; Soil Contamination and French Drains Surrounding 3706 Building

Code: 300-149

Classification: Accepted

Names: 300-149; 3706A Building Steam Condensate; Injection Well #28; Miscellaneous Stream #432

Reclassification: Consolidated (1/19/1999)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The site is a french drain that received steam condensate. The french drain is a concrete pipe covered with a 0.88 meter (2.89 foot) perforated metal lid. The lid is posted "Confined Space." The top of the pipe is 5 to 9 centimeters (2 to 3.5 inches) above the ground surface. A steam pipe enters the ground approximately 0.4 meters (1.31 feet) south of the site. The pipe is labeled "HPD-TRP-024" and "HPD-TRP-025." A 2.5 centimeter (1 inch) metal pipe is visible under the cover; it extends approximately 20 centimeters (7.9 inches) from the side of the concrete pipe and is in line with the steam pipe. The concrete pipe is 0.98 meters (3.2 feet) in length. The space below the concrete pipe appears to be filled with rocks and cobbles. During the October 27, 1998, walkdown, there was no evidence that the site was in use. The site is surrounded by asphalt, soil and gravel. The 3706A Building is posted "Fixed Contamination Area." The site falls within WIDS Site 300-46 which estimates the extent of extensive uranium, transuranic and chemical contamination of the 3706 Building and the surrounding area. According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive, source abandoned. Nineteen recognized miscellaneous stream drains were located within the boundary of the waste site and have been consolidated with 300-46. This structure was not excavated because it was in close proximity to an active well (well number 399-6-5).

Location: The site is 7.5 meters (24.6 feet) east of the 3706A east entrance door, under the overhead steam line.

Release Description: There were no known hazardous or radioactive releases from this steam condensate discharge.

Related Sites/ Structures: The site is associated with the 300 Area main steam line.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

This Site Was Consolidated With:

Code: 300-46

Names: 300-46; Soil Contamination and French Drains Surrounding 3706 Building

Code: 300-150	Classification: Accepted
Names: 300-150; 3706 Building Steam Condensate; Miscellaneous Stream #430	Reclassification Rejected (12/15/1998)
Type: French Drain	Start Date:
Status: Inactive	End Date:
Description: The site was a french drain that is a clay pipe. Letter: MSA-1400080 (1/27/2014) Contract Deliverable CD1033 Annual Class V Underground Injection Control (UIC) Wells Update for calendar year 2013 states the estimated backfill date of this drain is 1/5/2013. The outer diameter of the pipe is 1.25 meters (4.10 feet). The pipe had been covered by a metal lid which is labeled "Danger - Confined Space." The upper lip of the pipe was breaking up. The top of the pipe is flush with the ground surface for approximately one half of its circumference. The other half is 1 to 2 centimeters (0.4 to 0.8 inches) above the ground. The pipe was surrounded by soil and gravel. A pipe from the overhead steam line enters the ground nearby. This pipe is labeled "HPD-TRP-021." According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive, source abandoned. Because of the broken lip on the pipe, the site may have collected stormwater from the roadway.	
Location: The site is located across Apple Street from the westernmost entrance on the north side of the 3706 Building. It is under the overhead steam lines.	
Release Description: There were no known hazardous or radioactive releases from this steam condensate discharge.	
Related Sites/Structures: The site is associated with the 3706 Building.	
Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.	
Waste Type: Steam Condensate	
Waste Description: When the site was active, it received less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.	

Code: 300-151	Classification: Accepted
Names: 300-151; 3707B Building Steam Condensate; Miscellaneous Stream #327	Reclassification Rejected (12/15/1998)
Type: French Drain	Start Date:
Status: Inactive	End Date:
Description: Letter: MSA-1400080 (1/27/2014) Contract Deliverable CD1033 Annual Class V Underground Injection Control (UIC) Wells Update for calendar year 2013 states the estimated backfill date of this drain is 1/5/2013. The site was a french drain that is a clay pipe 0.86 meters (2.82 feet) in diameter. The pipe was surrounded by asphalt and cobbles. The drain had an inset metal lid. A small diameter (approximately 2.5 centimeters or 1 inch) metal pipe enters the lid through an opening. Water was observed through this opening on a 10/13/98 visit to the site. At the time of the walkdown, the site was surrounded by a metal barricade. The label "HDP-TRP-009" mentioned in the "Inventory of Miscellaneous Streams," Revision 3, was not observed. The	

former location of the 3707B Building is currently home to electrical equipment and a Johnson Controls, Inc., air compressor. The "Inventory of Miscellaneous Streams," Revision 3, states that this site previously received steam condensate from the main steam line at pit U57 (300-152, stream #326), but now receives condensate from a Johnson Controls, Inc. air compressor.

Location: The site is located just north of the previous location of the 3707B Building. It is south of the two entry doors on the south side of the 3708 Building.

Related Sites/ Structures: Previously, the site was associated with the 3707B Building, which has been demolished. The site is currently associated with a Johnson Controls, Inc., air compressor.

Process Description: Steam is produced from sanitary water that has been sent through a water softener system to remove minerals (calcium and magnesium). The treated water is introduced into boilers to produce steam. This steam is superheated before distribution to facilities for heating and process use. Disposal sites receive steam condensate from the steam distribution lines. When used for heating purposes, this is a seasonal discharge. Non-regulated chemicals are added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 3, the flow is less than 0.038 liters per minute (0.01 gallons per minute).

Code: 300-152

Classification: Accepted

Names: 300-152; 3707B Building Steam Condensate; Miscellaneous Stream #326; U57

Reclassification: Rejected (12/15/1998)

Type: French Drain

Start Date:

Status: Inactive

End Date: 1/1/1996

Description: The site is a french drain. The base of this drain is constructed of corrugated metal and is covered by a 1.3 meter (4.27 foot) metal lid. The lid is labeled "Confined Space" and "U-57." The top of the lid ranges from 5 to 15 centimeters (2 to 6 inches) above grade. The site is surrounded by soil and gravel. The former location of the 3707B Building is currently home to electrical equipment and a Johnson Controls, Inc., air compressor. According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive, source abandoned.

Location: The site is located northeast of the previous location of the 3707B Building. It is 10 meters (32.8 feet) from the southeast corner of the 3708 Building, next to the overhead steam lines.

Related Sites/ Structures: The site is associated with the 3707B Building, which has been demolished.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, it received less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

Code: 300-153

Classification: Accepted

Names: 300-153; 3707B Building Steam Condensate; Miscellaneous Stream #328

Reclassification: Rejected (12/15/1998)

Type: French Drain

Start Date:

Status: Inactive

End Date: 1/1/1996

Description: The site is a french drain which received steam condensate. According to the "Inventory of Miscellaneous Streams," Revision 3, the stream status is inactive, source abandoned. The former location of the 3707B Building is currently home to electrical equipment and a Johnson Controls, Inc., air compressor. No evidence of the site was visible during the site walkdown.

Location: The "Inventory of Miscellaneous Streams," Revision 3, describes this site as being at the northwest corner of the 3707B Building.

Related Sites/ Structures: The site is associated with the 3707B Building, which has been demolished.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, it received less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

Code: 300-154

Classification: Accepted

Names: 300-154; 3707B Building Steam Condensate; Miscellaneous Stream #325

Reclassification: Rejected (12/15/1998)

Type: French Drain

Start Date:

Status: Inactive

End Date: 1/1/1998

Description: The site is not an engineered structure. No pipe or lid was evident during the 10/13/98 walkdown. The ground surface is covered with soil and gravel. A pipe descending from the overhead steam line discharged directly onto the ground. At the time of the walkdown, the site was not labeled "HPD-V-015C" as described in the "Inventory of Miscellaneous Streams," Revision 3. However, the site is below a valve labeled "MSS-V-015." A small, shallow natural depression was observed just southwest of the discharge point. Stormwater runoff could collect in this depression. The former location of the 3707B Building is currently home to electrical equipment and a Johnson Controls, Inc., air compressor. The "Inventory of Miscellaneous Streams," Revision 3, says the site is inactive, source abandoned.

Location: The site is located at the northwest corner of the intersection of Apple St. and Wisconsin Street. It is below an overhead steam line.

Related Sites/ Structures: The site is associated with the 3707B Building, which has been demolished.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When

used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, it received less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

Code: 300-155

Classification: Accepted

Names: 300-155; 3707C Building Steam Condensate; Injection Well #24; Miscellaneous Stream #179

Reclassification: Rejected (12/15/1998)

Type: French Drain

Start Date:

Status: Inactive

End Date: 1/1/1996

Description: The site is a french drain that received steam condensate. The former location of the 3707C Building is currently a cobble-covered field. No evidence of the site remains. According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive.

Location: According to the "Inventory of Miscellaneous Streams," Revision 3, the site was located near the center of the south side of the former 3707C building.

Related Sites/ Structures: The site is associated with the 3707C Building, which has been demolished.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, it received less than 0.38 liters per minute (0.1 gallons per minute) of steam condensate only.

Code: 300-156

Classification: Accepted

Names: 300-156; 3707C Building Steam Condensate; Injection Well #23; Miscellaneous Stream #178

Reclassification: Rejected (12/15/1998)

Type: French Drain

Start Date:

Status: Inactive

End Date: 1/1/1996

Description: The site is a french drain covered by a 1.1 meter (3.61 foot) metal lid. The lid is labeled "Confined Space." The drain itself appears to be approximately half the diameter of the lid. Because of the size difference between the lid and the drain, it was difficult to get a good look inside the drain. The upper part of the drain appears to be made of bricks. The site is surrounded by gravel. A manhole labeled "Caution, Radioactive Material, Internally Contaminated" is approximately 2 meters (6.6 feet) to the northwest. This manhole is related to the 300 Area Process Sewer System (WIDS Site 300-15). According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive.

Location: The site is located approximately 4 meters (13 feet) northwest of the northwest corner of the 3706 Building, and approximately 2 meters (6.6 feet) southeast of a manhole labeled

"Radioactive Material, Internally Contaminated."

Related Sites/ Structures: The site is associated with the 3707C Building, which has been demolished.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, it received less than 0.38 liters per minute (0.1 gallons per minute) of steam condensate only.

Code: 300-157 **Classification:** Accepted

Names: 300-157; 3707C Building Steam Condensate; Miscellaneous Stream #337 **Reclassification:** Rejected (12/15/1998)

Type: French Drain **Start Date:**

Status: Inactive **End Date:** 1/1/1996

Description: The site is a french drain that is a clay pipe. The upper lip of the clay pipe is breaking up. The drain is covered by a 0.76 meter (2.49 foot) metal lid. The drain is surrounded by a metal safety barricade and the area around the it is covered with cobbles. According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive.

Location: The site is located approximately 12 meters (39.4 feet) west of the northwest corner of the 3706 Building.

Related Sites/ Structures: The site is associated with the 3707C Building, which has been demolished.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, it received less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

Code: 300-158 **Classification:** Accepted

Names: 300-158; 3707C Building Steam Condensate; F.D. #31; Miscellaneous Stream #336 **Reclassification:** Rejected (12/15/1998)

Type: French Drain **Start Date:**

Status: Inactive **End Date:** 1/1/1996

Description: The site is a french drain that received steam condensate. The former location of the 3707C

Location: Building is currently a cobble-covered field. No evidence of the site remains. According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive. According to the "Inventory of Miscellaneous Streams," Revision 3, the site was located near the southwest corner of the former 3707C building.

Related Sites/ Structures: The site is associated with the 3707C Building, which has been demolished.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, it received less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

Code: 300-159 **Classification:** Accepted

Names: 300-159; 3707C Building Steam Condensate; F.D. #4; Miscellaneous Stream #335 **Reclassification:** Rejected (12/15/1998)

Type: French Drain **Start Date:**

Status: Inactive **End Date:** 1/1/1996

Description: The site is a french drain that received steam condensate. The former location of the 3707C Building is currently a cobble-covered field. There is no evidence of a french drain in the location described for this site. According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive.

Location: According to the "Inventory of Miscellaneous Streams," Revision 3, the site was on the west side of the former 3707C Building.

Related Sites/ Structures: The site is associated with the 3707C Building, that has been demolished.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, it received less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

Code: 300-160 **Classification:** Accepted

Names: 300-160; 3707D Building Steam Condensate; Injection Well #10; Miscellaneous Stream #443 **Reclassification:** Rejected (12/15/1998)

Type: Injection/Reverse Well **Start Date:**

Status: Inactive**End Date:****Description:** The site is a rectangular concrete structure. It is painted yellow and is marked with "Confined Space" signs.**Location:** The site is located 3 meters (10 feet) from the south side of the 3707-D Building.**Waste Type:** Steam Condensate**Waste Description:** The site receives less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate.

Code: 300-161**Classification:** Accepted**Names:** 300-161; 3707D Building Stormwater Runoff; Miscellaneous Stream #441**Reclassification** Rejected (12/15/1998)**Type:** Injection/Reverse Well**Start Date:****Status:** Inactive**End Date:****Description:** The structure has been removed. The site was a 68 centimeter (27 inch) drain with a perforated metal cover, marked with a "Confined Space" sign. It was excavated in July 2010.**Location:** The site was located approximately 4.5 meters (15 feet) from the northwest side of the 3707D Building.**Waste Type:** Stormwater Runoff**Waste Description:** The site receives surface runoff from a paved area adjacent to the 3707D building. According to the "Inventory of Miscellaneous Streams," Revision 3, the flow rate is less than 0.038 liters per minute (0.01 gallons per minute).

Code: 300-162**Classification:** Accepted**Names:** 300-162; 3707D Building Stormwater Runoff; Miscellaneous Stream #442**Reclassification** Rejected (12/15/1998)**Type:** Injection/Reverse Well**Start Date:****Status:** Inactive**End Date:****Description:** The structure was excavated in July 2010 during the remedial actions at the 300-28, 300-43, 300-48, 300-249, and 300-16:3 sites. The site was a 68 centimeter (27 inch) drain with a perforated metal cover.**Location:** The site was located approximately 4.5 meters (15 feet) from the northeast side of the 3707-D Building.**Waste Type:** Stormwater Runoff**Waste Description:** The site receives surface runoff from a paved area adjacent to the 3707D building. According to the "Inventory of Miscellaneous Streams," Revision 3, the flow is less than 0.038 liters per minute (0.01 gallons per minute).

Code: 300-163**Classification:** Accepted**Names:** 300-163; 3708 Building Steam Condensate; Miscellaneous Stream #423**Reclassification** Rejected (9/2/1998)

Type: French Drain**Start Date:****Status:** Inactive**End Date:**

Description: The french drain was removed during the demolition of the 3708 building. Letter: MSA-1400080 (1/27/2014) Contract Deliverable CD1033 Annual Class V Underground Injection Control (UIC) Wells Update for calendar year 2013 states the estimated backfill date of this drain is 1/8/2013. It was a vitrified clay pipe buried vertically. The top was even with the ground surface and was covered with a metal lid. Two lines discharged into the drain.

Location: The site was located on the east side of the 3708 Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The unit received steam condensate from the 3708 building.

Code: 300-164**Classification:** Accepted

Names: 300-164; 3709 Building Steam Condensate; F.D. #3; Miscellaneous Stream #338

Reclassification: Rejected (12/15/1998)**Type:** French Drain**Start Date:****Status:** Inactive**End Date:** 1/1/1998

Description: The waste site was a french drain that was removed during the demolition of the 3709 building. Letter: MSA-1400080 (1/27/2014) Contract Deliverable CD1033 Annual Class V Underground Injection Control (UIC) Wells Update for calendar year 2013 states the estimated backfill date of this drain is 6/1/2012. It was a concrete pipe, covered by a 1.46 meter (4.79 foot) metal lid. The lid was labeled "Confined Space." The lid was not labeled "F.D. #3" as described by the "Inventory of Miscellaneous Streams," Revision 2. The lid was almost flush with the ground surface and is surrounded by asphalt. A metal pipe approximately 4 centimeters (1.6 inches) in diameter extended from the north side of the 3709 building and entered the ground approximately 1 meter (3.5 feet) from the edge of the drain.

Location: The site was located at the northeast corner of the 3709 building.

Related Sites/ Structures: The site is associated with the 3709 building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, it received less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

Code: 300-165 **Classification:** Accepted

Names: 300-165; 3709A Building Condensate; Miscellaneous Stream #347 **Reclassification** Rejected (12/15/1998)

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:** 1/1/1996

Description: The site is an injection well that received air compressor condensate. The site is a 0.5 meter (1.64 foot) diameter concrete structure with a heavy metal cover. There are two holes in the cover. During the 10/9/98 walkdown, there did not appear to be any water in the drain (observed through one of the holes in the cover).

Location: The site is located adjacent to the west wall of the 3709A Fire Station, just north of the southwest corner.

Related Sites/ Structures: The site is associated with the 3709A Building.

Waste Type: Water

Waste Description: The site received air compressor condensate. The "Inventory of Miscellaneous Streams," Revision 1, lists the flow rate as less than 0.038 liters per minute (0.01 gallons per minute). Revisions 2 and 3 of the document list the flow as 0 liters per minute (0 gallons per minute) because the stream was discontinued.

Code: 300-166 **Classification:** Accepted

Names: 300-166; 3709A Building Steam Trap; Miscellaneous Stream #355 **Reclassification** Rejected (12/15/1998)

Type: Injection/Reverse Well **Start Date:**

Status: Active **End Date:**

Description: The site is an injection well that was originally used as a steam trap and later used for stormwater. The top of the drain is flush with the asphalt parking area. The site is covered with a 1.47 meter (4.82 foot) diameter steel lid with four holes in the cover. The lid is labeled "U-40" and "Confined Space."

Location: The site is located in the asphalt parking area on the south side of the 3709A Fire Station. It is near the southwest corner of the building.

Related Sites/ Structures: The site is associated with the 3709A Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Stormwater Runoff

Waste Description: In 2008, the stormwater from the roof of 3709A was rerouted to this drain.

Waste Type: Steam Condensate

Waste Description: When the site was originally used, it received less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

Code: 300-167 **Classification:** Accepted
Names: 300-167; 3711 Building Steam Condensate; Miscellaneous Stream #343 **Reclassification:** Rejected (12/15/1998)
Type: French Drain **Start Date:**
Status: Inactive **End Date:** 1/1/1997

Description: The site was a french drain that received steam condensate. It was removed during the demolition of the 3711 building. A pipe from the overhead steam line entered the ground in the location described for this site. During the 10/14/98 site walkdown, no evidence of a drain was visible. Tags labeling the valves HPD-V-1001, HPD-V-5001, HPD-V-2001, and HPD-V-3001 were observed. There was not a tag for HPD-TRP-001, which was described in the "Inventory of Miscellaneous Streams," Revision 3. The area surrounding the descending steam pipe is covered with soft sand, which is deep in places. The sand could be obscuring evidence of the site.

Location: The site is located on the north side of the 3711 Building.

Related Sites/ Structures: The site is associated with the 3711 Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, it received less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

Code: 300-168 **Classification:** Accepted
Names: 300-168; 3711 Building Steam Condensate; Miscellaneous Stream #433 **Reclassification:** Rejected (12/15/1998)
Type: French Drain **Start Date:**
Status: Inactive **End Date:**

Description: This french drain was removed with the demolition of the 3711 Building in April 2006. The site was a french drain constructed of a concrete pipe. The pipe did not have a lid and appeared to be filled with sand, cobbles and broken bricks. The top of the pipe, which was deteriorating, ranged from 1 centimeter (0.4 inches) to 10 centimeters (4 inches) above grade. Three metal pipes, approximately 2.5 centimeters (1 inch) in diameter extended from the 3711 Building. The open ends of these three pipes were poised over the top of the drain. A "Radioactive Material Area" was located approximately 5 meters (16.4 feet) to the east.

Location: The site is located on the south side of the 3711 Building, just west of the south entry door.

Related Sites/ Structures: The site is associated with the 3711 Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, it received less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

Code: 300-169

Classification: Accepted

Names: 300-169; 3712 Building Steam Condensate; Miscellaneous Stream #351

Reclassification: Rejected (1/19/1999)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: In January 2006, the drain was sealed with grout.

According to the "Inventory of Miscellaneous Streams," Revision 3, the site is a french drain that receives steam condensate at a flow rate of less than 0.38 liters (0.01 gallons) per minute. Based on a site inspection in June of 1997, the drain is composed of a 0.48 meter (1.57 foot) diameter metal culvert that abuts the east side of the 3712 Building. The culvert is uncovered and appears to be rust stained. The culvert appears to be filled with sand or other soil to within 0.50 meters (1.6 feet) of its top. A 3 centimeter (1.2 inch) diameter metal pipe enters the top of the culvert and intersects a horizontal pipe, making a T-intersection. This second pipe is oriented north-south. One end has a valve. The other end makes a 90 degree turn towards the 306 Building. The vertical pipe that enters the top of the culvert rises to just under the roof line of the 3712 Building where it continues north along the east side of the building, turns and travels west. At another T-intersection near the center of the north side, a short pipe extends downward and appears to be capped. The other segment continues in the towards the northwest corner of the building where it drops towards the ground surface. This pipe terminates open-ended 0.20 meters (0.66 feet) above the ground surface.

During a November 1998 site inspection, the source of the steam condensate for this french drain came into question. Tracing out the lines, and verifying with drawing M-3901, Sheet 2, Revision 30, it was determined that the line into the french drain is actually a line from an abandoned helium system that ran between the 306 and 3712 Buildings. This line terminates open-ended. The drawing shows a gate valve to the atmosphere at the culvert on the east side of the building and at the northwest corner of 3712, plus a 2.5 centimeter (1 inch) gate valve near the center of the north side of 3712.

It is believed that this site was mistakenly included in the miscellaneous streams inventory, and that it was in fact a purge point for the helium system.

This site is located within a "Radiologically Controlled Area" posted around the 3712 Building. The 3712 Building is an active uranium metal storage unit, documented as WIDS Site 3712 USSA, and posted as "Caution Fissile Materials" and "Radiation Area and Contamination Area".

Location: The site is located on the east side of the 3712 Building, 16.3 meters (53.5 feet) south of the

northeast corner.

Related Sites/ Structures: The site is associated with the 3712 Building (WIDS Site 3712 USSA).

Process Description: Helium is a light noble gas. Releases of helium to the atmosphere would quickly dissipate with no expected reaction or contamination of the surrounding area.

Waste Type: Water

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 3, the site received steam condensate with a flow rate less than 0.01 gallons per minute. According to technical personnel responsible for the site, this site was mistakenly identified as a miscellaneous stream site.

Waste Type: Chemicals

Waste Description: According to M-3901, sheet 2, revision 30, an abandoned helium line travels through this site, not a steam condensate line.

Code: 300-170

Classification: Accepted

Names: 300-170; 3712 Building Steam Condensate; Miscellaneous Stream #437

Reclassification: Rejected (2/24/1999)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: According to the "Inventory of Miscellaneous Streams," Revision 3, the site was a french drain that received steam condensate. The report identified the location as the north side of the 3712 Building directly next to the building. During the October 27, 1998 walkdown, a concrete pipe with a 1.0 meter (3.3 foot) metal lid was found at the top of a small slope approximately 13 meters (42.7 feet) northwest of the roll up door on the north side of 3712. The metal lid is not labeled. Based on previous experience with the location descriptions and coordinates in the "Inventory of Miscellaneous Streams," this structure seems to fit the description for this stream. The top of the concrete is above grade except where the surrounding cobbles are spilling over and partially covering the lid. Two metal pipes extend horizontally from the north side of 3712 Building 6 to 9 meters (20 to 30 feet) above the ground surface. One of these pipes appears to be capped; the other appears to be open-ended and approximately half the diameter of the capped pipe. Drawing M-3800, sheet 2, revision 20, shows a steam line running from approximately the center of the north side of the 3712 Building north to 3710A, which has since been demolished. A Johnson Controls, Inc., boiler house has been built north of the northeast corner of 3712. During the October 27, 1998, walkdown, the lid could not be lifted in order to verify whether or not this stream is still active. Another walkdown was done on February 17, 1999 for the purpose of lifting the lid on the site and taking a photograph. There are no pipes visible inside the drain. There is no evidence the drain is active. The concrete pipe is filled with large rocks to within a few inches below the metal cover. Nat Harden, DynCorp Electrical System Specialist was visited. He looked through the available service drawings for the location. Nat stated that he was fairly sure that this waste site was the french drain for the steam condensate from the 3710A Building (now demolished). He said that the 3710A Building steam supply was an overhead line that ran from the north side of the 3712 Building. Nat noticed that the steam line is shown as dashed (denoting an underground) line on the as-built drawings whereas it should be shown as an above ground line that has been removed. The waste site is not shown on any of the utility drawings that Nat had.

Location: The site is located approximately 13 meters (42.7 feet) northwest of the roll up door on the north side of 3712, at the top of a small slope. If the 3710A Building was still in place, this french drain would be located west of this Building.

Related Sites/ The site is associated with the 3712 or 3710A Building.

Structures:

Process Description: Steam was produced from sanitary water that has been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites receive steam condensate from the steam distribution lines. When used for heating purposes, it was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 3, the flow was less than 0.038 liters (0.01 gallons) per minute.

Code: 300-171

Classification: Accepted

Names: 300-171; 3713 Building Steam Condensate and Stormwater Runoff; F.D. #7; Miscellaneous Stream #333

Reclassification: Rejected (12/15/1998)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The waste site was a french drain received only stormwater. It was removed and sealed with grout during the demolition of the 3713 building. It was a clay pipe covered by a 0.32 meter (1.05 foot) perforated metal lid. The lid was not labeled F.D. #7 as described in the "Inventory of Miscellaneous Streams," Revision 2. The top of the drain was flush with the ground surface. The drain appeared to be filled with soil to within 30 centimeters (11.8 inches) of the top of the pipe. The site was surrounded by soil and gravel. Soil was subsiding around the drain (see photos). According to the "Inventory of Miscellaneous Streams," Revision 3, the steam source has been shut off.

Location: The site was located at the northwest corner of the 3713 Building.

Related Sites/ The site is associated with the 3713 Building.

Structures:

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Stormwater Runoff

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 3, the flow rate is less than 0.076 liters per minute (0.02 gallons per minute).

Waste Type: Steam Condensate

Waste Description: When the site was active, the flow rate for both steam condensate and stormwater runoff was listed in the "Inventory of Miscellaneous Streams" as less than 0.076 liters per minute (0.02 gallons per minute).

Code: 300-172

Classification: Accepted

Names: 300-172; 3713 Building Steam Condensate; Miscellaneous Stream #435

Reclassification: Rejected (12/15/1998)

Type: Injection/Reverse Well

Start Date:

Status: Inactive

End Date: 1/1/1998

Description: The waste site was an injection well that was grouted in 2006, but not removed during the demolition of the 3713 building. No engineered structure was evident. It was a slightly depressed area, approximately 0.4 meters (1.31 feet) in diameter, filled with cobbles and larger rocks. Stormwater runoff may have collected in this depression. The site was surrounded by soil and gravel. A pipe from the overhead steam line labeled "HPD-TRP-018" entered the ground just north of the site.

Location: The site was 8.9 meters (29.2 feet) southwest of the southwest corner of the 3713 building.

Related Sites/ Structures: The site is associated with the 3713 building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, it received less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

Code: 300-173

Classification: Accepted

Names: 300-173; 3713 Building Steam Condensate; Miscellaneous Stream #512

Reclassification: Rejected (12/15/1998)

Type: French Drain

Start Date:

Status: Inactive

End Date: 1/1/1998

Description: The waste site was an injection well that was grouted in 2006, but not removed during the demolition of the 3713 building. Letter: MSA-1400080 (1/27/2014) Contract Deliverable CD1033 Annual Class V Underground Injection Control (UIC) Wells Update for calendar year 2013 states the estimated backfill date of this drain is 1/8/2013. It was a french drain covered by a 1.14 meter (3.74 foot) metal lid. The lid was flush with the ground surface and was labeled "Confined Space." A pipe extended from an overhead steam line and entered the ground near the lid.

Location: The site was located 12.5 meters (41 feet) southwest of the southwest corner of the 3713 building.

Related Sites/ Structures: The site is associated with the 3713 building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added

to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, it received less than 3.8 liters per minute (1.0 gallon per minute) of steam condensate only.

Code: 300-174

Classification: Accepted

Names: 300-174; 3713 Building Stormwater Runoff and Steam Condensate; Miscellaneous Stream #544

Reclassification: Rejected (12/15/1998)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The waste site was an injection well that was removed during the demolition of the 3713 building. It was sealed with grout in January 2006. It was covered by a 0.94 meter (3.08 foot) metal lid. A small diameter, 2.5 centimeters (1 inch) diameter metal pipe extended from the building to the drain's lid. The pipe extended from the building approximately 1.75 meters (5.7 feet) above the ground surface, then turned 90 degrees and extended within 0.25 meters (9.8 inches) of the ground surface.

Location: The site was located on the east side of the 3713 Building, 8.7 meters (28.5 feet) south of the northeast corner.

Related Sites/ Structures: The site is associated with the 3713 Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 3, the flow rate was less than 3.8 liters per minute (1 gallon per minute).

Waste Type: Stormwater Runoff

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 3, the flow rate is less than 3.8 liters per minute (1 gallon per minute).

Code: 300-176

Classification: Accepted

Names: 300-176; 3715 Building Steam Condensate; Miscellaneous Stream #678

Reclassification: Rejected (12/15/1998)

Type: Valve Pit

Start Date:

Status: Inactive

End Date: 1/1/1998

Description: The drain was decommissioned in 2012. The site was a rectangular valve pit with a dirt floor. Steam condensate was discharged onto the floor of the pit. The top of the concrete base is 5 to 15 centimeters (1.97 to 5.91 inches) above grade. The valve pit is covered by a metal lid 1.30 meters (4.27 feet) by 1.11 meters (3.64 feet). The lid is labeled "Confined Space" and "U-49."

Location: A steam pipe from the overhead line enters the ground just east of the site. The pipe is labeled "HPD-TRP-005." The site is surrounded by sand and asphalt. The site is located between the 3715 Building and the 303E Building, under the overhead steam line.

Related Sites/ Structures: This site is associated with the 3715 Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, it received less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

Code: 300-177 **Classification:** Accepted

Names: 300-177; 3717 Building Steam Condensate; Miscellaneous Stream #330 **Reclassification:** Rejected (12/15/1998)

Type: Injection/Reverse Well **Start Date:**

Status: Inactive **End Date:** 1/1/1998

Description: The site was an injection well that received steam condensate. It was sealed with grout in January 2006. The site was a 90 centimeter (2.95 foot) diameter, concrete structure with a perforated metal cover. It was located adjacent to an overhead steam line, but there was no visible evidence of a steam pipe connecting to this drain. The drain was in a slight depression from the surrounding grade.

Location: The site was located approximately 5 meters (16.5 feet) from the southeast corner of the 3717 Building.

Related Sites/ Structures: The site is associated with the 3717 Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When the site was active, it received less than 0.038 liters per minute (0.01 gallons per minute) of steam condensate only.

Code: 300-178 **Classification:** Accepted

Names: 300-178; 3717 Building Steam Condensate; Miscellaneous Stream #329 **Reclassification:** Rejected (12/15/1998)

Type: French Drain**Start Date:****Status:** Inactive**End Date:****Description:** The site was a french drain constructed of clay pipe. It was sealed with grout in 2006. The top of the clay pipe was 5 centimeters (2 inches) above grade. The drain appeared to have been filled with sand or soil to within 0.35 meters (1.15 feet) of the top of the pipe. The drain was covered by a 0.25 meter (0.82 foot) metal lid with perforations. There was no evidence of use observed during the 10/08/98 walkdown. The site was surrounded by soil and gravel.**Location:** The site was located just east of the south entry door to the 3717 Building.**Related Sites/
Structures:** The site is associated with the 3717 Building.**Process
Description:** Steam is produced from sanitary water that has been sent through a water softener system to remove minerals (calcium and magnesium). The treated water is introduced into boilers to produce steam. This steam is superheated before distribution to facilities for heating and process use. Disposal sites receive steam condensate from the steam distribution lines. When used for heating purposes, this is a seasonal discharge. Non-regulated chemicals are added to dechlorinate the water, prevent scale, and control corrosion.**Waste Type:** Steam Condensate**Waste
Description:** According to the "Inventory of Miscellaneous Streams," Revision 3, the flow rate is less than 0.038 liters per minute (0.01 gallons per minute).

Code: 300-179**Classification:** Accepted**Names:** 300-179; 3717 Building Steam Condensate;
Miscellaneous Stream #324**Reclassification** Rejected (12/15/1998)**Type:** French Drain**Start Date:****Status:** Inactive**End Date:****Description:** The site was a french drain constructed of clay pipe. It was sealed with grout in 2006. The upper lip on half of the pipe was broken, so the 0.39 meter (1.28 foot) metal lid did not seat properly. During the 10/8/98 walkdown, the site was surrounded by a metal safety barricade. During the same walkdown, it was observed that the pipe that descended from the overhead steam line was not labeled. The "Inventory of Miscellaneous Streams," Revision 3, states "HPD-TRP-022" is the steam trap associated with this french drain. The broken lip may allow stormwater runoff to enter this drain. The site is surrounded by soil and gravel.**Location:** The site is located south of the southwest corner of 3717.**Related Sites/
Structures:** The site is associated with the 3717 Building.**Process
Description:** Steam is produced from sanitary water that has been sent through a water softener system to remove minerals (calcium and magnesium). The treated water is introduced into boilers to produce steam. This steam is superheated before distribution to facilities for heating and process use. Disposal sites receive steam condensate from the steam distribution lines. When used for heating purposes, this is a seasonal discharge. Non-regulated chemicals are added to dechlorinate the water, prevent scale, and control corrosion.**Waste Type:** Steam Condensate**Waste
Description:** According to the "Inventory of Miscellaneous Streams," Revision 3, the flow rate is less than 0.038 liters per minute (0.01 gallons per minute).

Code: 300-180 **Classification:** Not Accepted

Names: 300-180; 3717 Building Stormwater Runoff; Miscellaneous Stream #545 **Reclassification:** None

Type: French Drain **Start Date:**

Status: Inactive **End Date:**

Description: The site is a french drain constructed of clay pipe. It was sealed with grout in 2006. It had been covered by a perforated metal lid. The pipe was surrounded by soil, gravel and concrete. The top of the pipe was approximately 1 centimeter (0.4 inches) above the ground surface. The pipe had been filled with soil and cobbles to within approximately 0.4 meters (1.3 feet) of the top of the pipe.

Location: This site is located on the south side of the 3717 Building, approximately halfway between the south entry door and the east end of the building.

Related Sites/ Structures: This site is associated with the 3717 Building.

Waste Type: Stormwater Runoff

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 3, the flow rate is less than 3.8 liters per minute (1.00 gallon per minute).

Code: 300-181 **Classification:** Accepted

Names: 300-181; 3717 Building Steam Condensate; Miscellaneous Stream #180 **Reclassification:** Rejected (12/15/1998)

Type: French Drain **Start Date:**

Status: Inactive **End Date:**

Description: The site is a french drain covered by an eight-sided metal lid. It was sealed with grout in 2006. The diameter of the lid ranged from 0.60 meters (1.97 feet) to 0.66 meters (2.17 feet) and it appeared to have been welded shut on one side. The site is surrounded by asphalt and concrete. A small area of concrete on the west side of the lid appears to have been excavated.

Location: The site is located on the east side of the 3717 Building, just east of the roll up door.

Related Sites/ Structures: The site is associated with the 3717 Building.

Process Description: Steam is produced from sanitary water that has been sent through a water softener system to remove minerals (calcium and magnesium). The treated water is introduced into boilers to produce steam. This steam is superheated before distribution to facilities for heating and process use. Disposal sites receive steam condensate from the steam distribution lines. When used for heating purposes, this is a seasonal discharge. Non-regulated chemicals are added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: According to the "Inventory of Miscellaneous Streams." Revision 3, the flow rate is less than 0.038 liters per minute (0.01 gallons per minute).

Code: 300-182 **Classification:** Accepted
Names: 300-182; 3717B Building Steam Condensate; **Reclassification** Rejected (12/15/1998)
Miscellaneous Stream #323
Type: French Drain **Start Date:**
Status: Inactive **End Date:**

Description: The site was a french drain with a square concrete base. the top of the structure was removed in 2006 and backfilled. The top of the base ranges from approximately 1 centimeter (0.4 inches) to 5 centimeters (2 inches) above grade. The drain was covered by a 0.66 meter (2.17 foot) by 0.66 meter (2.17 foot) square metal lid. The lid had a "Confined Space" label. The site was surrounded by gravel where it did not abut 3717B. Two pipes from the overhead steam line entered through the lid. A row of "Radiologically Controlled Area" signs ran east to west approximately 5 meters (16.4 feet) north of the site. Although the ground between 3717B and 304 was fairly level, there appeared to be enough of a slope to prevent water flowing from the 304 Building towards the site.

Location: The site was adjacent to the north side of the 3717B Building and south of the 304 Building.

Related Sites/ Structures: The site is associated with the 3717B Building.

Process Description: Steam is produced from sanitary water that has been sent through a water softener system to remove minerals (calcium and magnesium). The treated water is introduced into boilers to produce steam. This steam is superheated before distribution to facilities for heating and process use. Disposal sites receive steam condensate from the steam distribution lines. When used for heating purposes, this is a seasonal discharge. Non-regulated chemicals are added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 3, the flow rate is less than 0.038 liters per minute (0.01 gallons per minute).

Code: 300-183 **Classification:** Accepted
Names: 300-183; 3718 Building Steam Condensate; F.D. **Reclassification** Rejected (12/15/1998)
#40; Miscellaneous Stream #340
Type: French Drain **Start Date:**
Status: Inactive **End Date:** 1/1/1998

Description: In April 2009, 300-183 was filled with dirt and the top three feet of the structure was removed to satisfy requirements of WAC 173-218. The site was a french drain that received steam condensate.

Location: The site was located southeast of the southwest corner of the 3718 Building.

Related Sites/ Structures: The site is associated with the 3718 Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 2, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute).

Code: 300-184

Classification: Not Accepted

Names: 300-184; 3718A Building Stormwater Runoff; Miscellaneous Stream #270

Reclassification: None

Type: Product Piping

Start Date:

Status: Inactive

End Date:

Description: Twin 10-centimeter (4-inch) galvanized pipes drain each of two roofs that slope into each other in the center of the building. The pipes are joined about 0.7 meters (2 feet) above the ground in a Y, and empty into a 14-centimeter (6-inch) PVC pipe. This pipe travels just under the ground surface for about 12.2 meters (40 feet) and exits from a railroad tie retaining wall. The stormwater then spills onto the ground between the road and retaining wall. The soils are very sandy and the water probably infiltrates without overland flow. While the miscellaneous streams report (Rev. 3) says that it is an injection well, there is no injection well. The stormwater runoff ultimately empties into a "non-engineered structure" (the bare ground).

Location: The site is located on the north side of the 3718A Building, in the center where the two sections of the building are joined.

Process Description: The wastes are only roof stormwater runoff.

Waste Type: Stormwater Runoff

Waste Description: The waste is stormwater runoff only.

Code: 300-185

Classification: Accepted

Names: 300-185; 3722 Building Steam Condensate; Injection Well #6; Miscellaneous Stream #436

Reclassification: Rejected (12/15/1998)

Type: French Drain

Start Date:

Status: Inactive

End Date: 1/1/1998

Description: The waste site was an injection well that was sealed with grouted in 2006. The structure was not removed during the demolition of the 3722 building. It was a french drain constructed of a 0.74 meters (2.43 feet) in diameter metal pipe. The top of the pipe was uncovered and flush with the ground surface. The pipe appeared to be filled with gravel to within centimeters of the top. Stormwater runoff may have enter this drain from the surrounding area. Two lines from the overhead steam line entered the ground nearby. One line was associated with HPD-TRP-013 and the other was associated with HPD-TRP-014.

Location: The site was located approximately 7 meters (23 feet) from the northwest corner of the 3722 Building.

Related Sites/Structures: The site is associated with the 3722 Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 2, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute).

Code: 300-186

Classification: Accepted

Names: 300-186; 3730 Building Steam Condensate; Miscellaneous Stream #383

Reclassification: Rejected (9/2/1998)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The site is a steel grate 48.3 centimeters (19 inches) square with two pipes emptying into it. The pipes are uninsulated and are 3.2 centimeters (1.25 inches) and 4.4 centimeters (1.75 inches) outside diameter. The grate covers a sump that is approximately 0.76 meters (2.5 feet) deep. The apparent drain is approximately 0.46 meters (1.5 feet) from the bottom and leads back into the building (east). A cast iron elbow, 10.2 centimeters (4 inches) outside diameter, in the bottom of the sump does not appear to relate to the drainage. Note that "Inventory of Miscellaneous Streams", Revision 3 (Final Draft) lists the site "Active". According to the responsible contractor, the document is not correct, as the site is inactive.

Location: The site is near the southwest corner of the 3730 Building, approximately 30.5 centimeters (1 foot) west of the building and 7.2 meters (23.5 feet) north of the southwestern corner.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description:

Code: 300-187

Classification: Accepted

Names: 300-187; 3730 Building Steam Condensate; Miscellaneous Stream #421

Reclassification: Rejected (9/2/1998)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The site is two pipes coming out of ground, with valves near each. The pipes are connected with a tee in the middle leading to a pipe that goes into the 3730 Building. The pipes are covered with asbestos-free insulation. The pipes are approximately 10.2 centimeters (4 inches) in diameter, including the insulation. Note that "Inventory of Miscellaneous Streams", Revision

3 (Final Draft) lists the site "Active". According to the responsible contractor, the document is not correct, as the site is inactive.

Location: The site is located on the north side of the 3730 Building, 3.05 meters (10 feet) west from the northeast corner, and 30.5 centimeters (12 inches) north of the building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description:

Code: 300-188

Classification: Accepted

Names: 300-188; 3730 Building Steam Condensate; Miscellaneous Stream #420

Reclassification: Rejected (9/2/1998)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The site is covered by a rusted steel plate, 0.84 meters (2.75 feet) in diameter, and with a 10.2 centimeter (4 inch) diameter asbestos-free insulated steam pipe running into the northeast part of plate. Four 2.54 centimeter (1 inch) diameter holes are cut into the plate. A label on top of the plate reads "DANGER LIMITED ACCESS/CONFINED SPACE, ENTRY BY PERMIT ONLY."

Location: The site is located on the northwest side of the 3730 Building, 0.76 meters (2.5 feet) west of the building, and 7.47 meters (24.5 feet) south of the northwest corner of the building.

Process Description: Steam is produced from sanitary water that has been sent through a water softener system to remove minerals (calcium and magnesium). The treated water is introduced into boilers to produce steam. This steam is superheated before distribution to facilities for heating and process use. Disposal sites receive steam condensate from the steam distribution lines. When used for heating purposes, this is a seasonal discharge. Non-regulated chemicals are added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description:

Code: 300-189

Classification: Accepted

Names: 300-189; 3731 Building Steam Condensate; Miscellaneous Stream #269

Reclassification: Rejected (9/2/1998)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: A site walkdown done in 1998 originally described a french drain that is a 10 centimeter (4 inch) metal pipe that extended through the asphalt. The pipe was about 0.75 meters (2.5 feet)

deep and extended from the top half of the building, about 0.6 meters (2 feet) south of a swamp cooler. The "Inventory of Miscellaneous Streams", Revision 3, says the stream is active, but in 1998, the building was posted as closed, and the drain was dry at the bottom. Additional research of Miscellaneous Stream #269 (300-189) was conducted in May 2012 in order to plan for removal/closure activities. As the specific drywell location is undetermined, the coordinates have been adjusted to the estimated inlet 300-293:1 pipe location (E594130.9/N116021.4).

Location: The french drain is located in the center of the east wall of the 3731 Building, about 5 centimeters (2 inches) from the wall. As the specific drywell location is undetermined, the coordinates have been adjusted to the estimated inlet 300-293:1 pipe location (E594130.9/N116021.4).

The estimated inlet pipe coordinates correlate with the location of the WIDS site 300-293:1 pipeline segment. The 9.5 meter long pipeline segment is a 4 inch diameter 2 foot below grade steel drain pipe from reference drawing H-3-300042 sheet 7. The correlation between the 300-189 inlet pipe material, size, and location with 300-293:1 drain pipe segment indicates a potential relationship. The mapped drywell location was adjusted to match the terminus end of the 300-293:1 pipe segment.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description:

Code: 300-190 **Classification:** Not Accepted

Names: 300-190; 3731 Building Stormwater Runoff; Miscellaneous Stream #517 **Reclassification:** None

Type: French Drain **Start Date:**

Status: Inactive **End Date:**

Description: A 1998 site walkdown originally described 17.8 centimeter (7 inch) PVC pipe that extended through the asphalt paving against the 3731 Building. The drain receives only stormwater from the roof of the 3731 Building, which was a closed facility. The downspout was almost the same diameter as the french drain, so the depth was not determined. The french drain pipe was cracked. Additional research of Miscellaneous Stream #517 (300-190) was conducted in May 2012 in order to plan for removal/closure activities. No information was discovered pertaining to the exact location or construction of the drywell.

Location: The drain location is in the northeast corner of the 3731 Building, immediately adjacent to the corner. A review of construction drawing H-3-17451 depicts the down spout locations for the 3731 building stormwater run-off which is the source to 300-190. The down spout locations from drawing H-3-17451 match the location depicted in the WIDS database photos for 300-190. As the specific drywell location is undetermined, the coordinates have been adjusted to the estimated downspout location (E594130/N116033.4.). No feature was visible at the previously mapped site.

The estimated inlet pipe coordinates correlate with the location of the WIDS site 300-293:1 pipeline segment. The 9.5 meter long pipeline segment is a 4 inch diameter 2 foot below grade

steel drain pipe from reference drawing H-3-300042 sheet 7. The correlation between the 300-190 inlet pipe material, size, and location with 300-293:1 drain pipe segment indicates a potential relationship. The mapped drywell location was adjusted to match the terminus end of the 300-293:1 pipe segment.

Process The site received only stormwater runoff.

Description:

Waste Type: Stormwater Runoff

Waste

Description:

Code: 300-191

Classification: Not Accepted

Names: 300-191; 3731 Building Stormwater Runoff;
Miscellaneous Stream #518

Reclassification None

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The 1998 site walkdown originally described this site as a 18 centimeter (7 inch) PVC pipe that extended through the asphalt. The drain received only roof stormwater runoff. The 3731 facility is closed. The roof downspout is almost the same diameter as the french drain, so the depth of the drain was not determined. Additional research of Miscellaneous Stream #518 (300-191) was conducted in May 2012 in order to plan for removal/closure activities. No information was discovered pertaining to the exact location or construction of the drywell.

Location: The site is in southeast corner of the 3731 Building, adjacent to the building corner. A review of construction drawing H-3-17451 depicts the down spout locations for the 3731 building stormwater run-off which is the source to 300-191. The down spout locations from drawing H-3-17451 match the location depicted in the WIDS database photos for 300-191. As the specific drywell location is undetermined, the coordinates have been adjusted to the estimated downspout location (E594130.5/N116008.2.). No feature was visible at the previously mapped site.

The estimated inlet pipe coordinates correlate with the location of the WIDS site 300-293:1 pipeline segment. The 9.5 meter long pipeline segment is a 4 inch diameter 2 foot below grade steel drain pipe from reference drawing H-3-300042 sheet 7. The correlation between the 300-191 inlet pipe material, size, and location with 300-293:1 drain pipe segment indicates a potential relationship. The mapped drywell location was adjusted to match the terminus end of the 200-293:1 pipe segment.

Process The site received only stormwater runoff from the roof.

Description:

Waste Type: Stormwater Runoff

Waste

Description:

Code: 300-192

Classification: Accepted

Names: 300-192; 3732 Building Steam Condensate;
Miscellaneous Stream #349

Reclassification Rejected (12/15/1998)

Type: French Drain**Start Date:****Status:** Inactive**End Date:** 1/1/1997

Description: The drain was decommissioned in 2012. The site was a french drain that received steam condensate from a quench tank. The drain appeared to be made of concrete and is covered by a lid. The foundation of the 3732 Building had been posted "Fixed Contamination Area." Details of this drain have been obscured by the paint applied for this posting. The outer perimeter of the drain measures 1.2 meters (3.9 feet) by 1.2 meters (3.9 feet) and rises approximately 10 centimeters (3.9 inches) above grade. The lid measures 0.98 meters (3.22 feet) by 0.98 meters (3.22 feet). Where the edges of the lid are visible, it appears as though it has been sealed by the paint. A sign on the lid has been obscured by paint. The site is surrounded by gravel. While visiting an adjacent site on 11/2/98, it was noticed that the 3732 pad had been surrounded by post and chain since the previous walkdown. The barricade was labeled "Radiological Buffer Area" and "Radiologically Controlled Area."

Location: The site is located at the southwest corner of the 3732 foundation.

Related Sites/ Structures: This site is associated with the 3732 Building. All that remains of the 3732 Building is the foundation (300-245). The site is also associated with the soil contamination under the remaining foundation (300-48).

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When this stream was active, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute).

Code: 300-193**Classification:** Accepted**Names:** 300-193; 3732 Building Steam Condensate; Injection Well #15; Miscellaneous Stream #419**Reclassification:** Rejected (12/15/1998)**Type:** French Drain**Start Date:****Status:** Inactive**End Date:** 1/1/1997

Description: The drain was decommissioned in 2012. The site was a french drain that received steam condensate. The drain was a concrete pipe which rises approximately 5 centimeters (1.97 inches) above grade. The pipe was covered by a 0.98 meter (3.22 foot) metal lid. The foundation of the 3732 Building had been posted "Fixed Contamination Area." The roof of the adjacent 303B Building is posted "Contamination Area." The site is surrounded by gravel.

Location: The site is southwest of the northwest corner of 3732. It is located between the 3732 foundation and the 303B Building.

Related Sites/ Structures: The site is associated with the 3732 Building. All that remains of 3732 is the foundation (300-245). The site is also associated with the soil contamination remaining under the foundation (300-48).

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and

process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When this stream was active, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute).

Code: 300-194

Classification: Accepted

Names: 300-194; 3734 Building Steam Condensate; F.D. #8; Miscellaneous Stream #334

Reclassification: Rejected (12/15/1998)

Type: French Drain

Start Date:

Status: Inactive

End Date: 1/1/1997

Description: The site is a french drain. The site is associated with the 3734 Building, which has been demolished. The 3734 Building's concrete pad is still in place and is surrounded by soil and gravel. There are two small areas of Fixed Contamination adjacent to the pad. No drain was visible during the site walkdown.

Location: According to the "Inventory of Miscellaneous Streams," Revision 3, the site is associated with the 3734 Building. However, the coordinates provided by that document map the site just north of the former 3734A Building. Both buildings have been demolished and no drain was visible during the site walkdown, so it was not possible to ascertain the actual location of this site.

Related Sites/Structures: The site is associated with the 3734 Building, which has been demolished.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When this stream was active, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute).

Code: 300-195

Classification: Accepted

Names: 300-195; 3734A Building Steam Condensate; Miscellaneous Stream #519

Reclassification: Rejected (12/15/1998)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The site is a french drain that received steam condensate. The previous location of the 3734A Building is currently a cobble-covered area on the east side of the 3705 Building. No drain was visible during the site walkdown.

Location: According to the "Inventory of Miscellaneous Streams," Revision 3, the site is on the south side of the 3734A Building.

Related Sites/ Structures: The site is associated with the 3734A Building, which has been demolished.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When this stream was active, the flow rate was less than 3.8 liters per minute (1 gallon per minute).

Code: 300-196

Classification: Accepted

Names: 300-196; 3745 Building Steam Condensate; Miscellaneous Stream #399

Reclassification: Rejected (9/2/1998)

Type: Sump

Start Date:

Status: Inactive

End Date:

Description: The drain was decommissioned in 2012. The site was a condensate sump constructed of concrete, 96.5 centimeters square (38 inches square), with a 66 centimeter (26 inch) diameter access cover.

Location: The site is located 10.7 meters (35 feet) south of the 3745 Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The waste is steam condensate that has a flow rate of less than 0.19 liters (0.05 gallons) per minute.

Code: 300-197

Classification: Accepted

Names: 300-197; 3745 Building Steam Condensate; Injection Well #5; Miscellaneous Stream #398

Reclassification: Rejected (9/2/1998)

Type: Injection/Reverse Well

Start Date:

Status: Inactive

End Date:

Description: Letter: MSA-1400080 (1/27/2014) Contract Deliverable CD1033 Annual Class V Underground Injection Control (UIC) Wells Update for calendar year 2013 states the estimated backfill date of this drain is 4/1/2012. The site was covered with a 147.3 centimeter (58 inch) diameter steel cover. Two pipes exited the 3745 Building and entered the drain. One of the pipes appeared to be condensate from steam and the other pipe is unknown.

Location: The site is located adjacent to the east side of the 3745 Building, just north of the east door.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The waste was steam condensate that had a flow rate of less than 0.19 liters (0.05 gallons) per minute.

Code: 300-198

Classification: Accepted

Names: 300-198; 3745 Building Steam Condensate; Injection Well #1; Miscellaneous Stream #397

Reclassification: Rejected (9/2/1998)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: Letter: MSA-1400080 (1/27/2014) Contract Deliverable CD1033 Annual Class V Underground Injection Control (UIC) Wells Update for calendar year 2013 states the estimated backfill date of this drain is 4/1/2012. The site was a vertical vitrified clay pipe with a steel lid. An eye bolt was fastened to the center of the lid. The cover should be to be removed to confirm the function of the site.

Location: The site is located just off the northeast corner of the 3745 Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: The waste is steam condensate that has a flow rate of 0.19 liters (0.05 gallons) per gallon.

Code: 300-199

Classification: Accepted

Names: 300-199; 3745A Building Steam Condensate; Miscellaneous Stream #380

Reclassification: Rejected (9/2/1998)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The Miscellaneous Stream site is a 0.6 meter by 0.45 meter (2 foot by 1.5 foot) rectangular concrete pit with a perforated steel cover. Although the Inventory of Miscellaneous Streams, Rev 3 lists this site as a steam condensate injection well, it has been determined that it does not meet the definition of an Underground Injection Control well (UIC).

About 15 centimeters (6 inches) from the top, a 10 centimeter (4 inch) pipe enters from the direction of the 3745A Building. The drain is at least 0.6 meters (2 feet) deep, with the bottom 15 centimeters full of water. The site will also act as a storm drain for the surrounding

compacted graveled area and the nearby roof runoff drain spout. The drain was protected by a yellow steel pipe barricade. The "Inventory of Miscellaneous Streams", Revision 3 lists this stream as eliminated. The lines have been capped. The source has been routed to the process sewer. The 3745A building has been demolished. The drain is no longer visible.

Location: The unit is west of the 3745A Building, 3.5 meters (11.5 feet) northwest of the northwest corner and roof downspout.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: Site appears to still receive storm water runoff.

Code: 300-200

Classification: Accepted

Names: 300-200; 3745B Building Steam Condensate; Miscellaneous Stream #379

Reclassification: Rejected (9/2/1998)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The waste site was removed during the demolition of the 3745A and B buildings. It was a square concrete pit, measuring 1.2 meters (4 feet) on a side, covered with a solid steel plate. The site appeared to be about 1 meter (3 feet) deep, with the bottom covered in water. A 10-centimeter (4-inch) iron pipe entered from the south side (from the 3745B Building) and another 10-centimeter (4-inch) pipe was lower, on the west side of the drain, barely extending into the drain. The "Inventory of Miscellaneous Streams", Revision 3 says the stream is eliminated. The pipes were capped. The source was routed to the process sewer. The water in the bottom was probably residual, as there was no air circulation to evaporate the water.

Location: The unit was located on the north side of the 3745B Building, 1.8 meters (6 feet) north of the north wall, and 9 meters (30 feet) west of the northeast corner.

Process Description: The "Inventory of Miscellaneous Streams", Revision 3, lists the site as inactive, source eliminated. The source has been routed to the process sewer. This site received steam condensate only. Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description:

Code: 300-201

Classification: Accepted

Names: 300-201; 3762 Building Steam Condensate;

Reclassification: Rejected (9/2/1998)

Injection Well #42; Miscellaneous Stream #491

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The site is a 1 meter (3 foot) diameter concrete pipe in the gravel roadway. A 5 centimeter (2 inch) steel pipe comes in at the bottom, from the direction of the 3762 Building. The bottom of the drain is 0.5 meters (1.5 feet) deep, and covered with small rocks and sand. The drain is protected by a yellow steel barrier made of pipes, which has been bent by traffic over the years. The drain is covered by a galvanized steel plate with 4 vent holes. The "Inventory of Miscellaneous Streams", Revision 3, says the site is active. However, the 3762 Building is posted as a closed facility, and most (or all) of the old steam lines in the area have been abandoned, so the site may actually be inactive. The site status has been changed to inactive to reflect information provided by the responsible contractor.

Location: The site is located 5.3 meters (17.5 feet) east of the northeast corner of the 3762 Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description:

Code: 300-202

Classification: Accepted

Names: 300-202; 3765 Building HVAC Condensate; Miscellaneous Stream #345

Reclassification: Rejected (12/15/1998)

Type: Injection/Reverse Well

Start Date:

Status: Inactive

End Date: 1/1/1997

Description: The drain is not visible. The 3765 Building has been demolished. A gravel parking lot has been placed on the location where the building once stood.

Location: The site is located in a gravel parking lot, east of the 3763 and 3764 buildings.

Process Description: The Heating, Ventilation, and Air Conditioning (HVAC) system collected condensate from the air on the coils of the unit. The condensate was collected by the HVAC unit and drained to the french drain.

Waste Type: Water

Waste Description: The Inventory of Miscellaneous Streams Report states the drain received HVAC condensate. When this stream was active, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute).

Code: 300-203

Classification: Accepted

Names: 300-203; 377 Building Steam Condensate; Injection Well #36; Miscellaneous Stream #446

Reclassification: Rejected (9/2/1998)

Type: French Drain**Start Date:****Status:** Inactive**End Date:**

Description: The 300-203 steam condensate french drain was removed during the demolition of the 377 building in 2006. The surface of the drain was covered with an iron plate 0.66 meters (2.17 feet) in diameter, exclusive of the frame. The site was located in a graveled lot. The plate was stuck closed from rust and sand wedged between it and its frame. The plate was flush with the ground, but it does not appear that stormwater would drain into it because the ground tilts slightly away from it, and the surrounding ground is not sealed and will let rainwater infiltrate. Site drawings H-3-42084 Sheet 1 and H-3-42085 Sheet 1 show the facility to drain from the valve pit on the east side of the 377 Building, where the steam lines enter. While the "Inventory of Miscellaneous Streams", Revision 3, lists the drain as active, the former facilities manager, Burke Neuman of DynCorp., said that the steam lines have been disconnected and thus the drain is inactive. The facility is closed, and other utilities, such as water and electricity, are also off.

Location: The drain is 10 meters (33 feet) north of the center of the north wall of the 377 Building.

Process Description: Steam is produced from sanitary water that has been sent through a water softener system to remove minerals (calcium and magnesium). The treated water is introduced into boilers to produce steam. This steam is superheated before distribution to facilities for heating and process use. Disposal sites receive steam condensate from the steam distribution lines. When used for heating purposes, this is a seasonal discharge. Non-regulated chemicals are added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description:

Code: 300-204**Classification:** Not Accepted

Names: 300-204; 3790 Building Stormwater Runoff; F.D. #19; Injection Well #19; Miscellaneous Stream #378

Reclassification: None**Type:** French Drain**Start Date:****Status:** Inactive**End Date:**

Description: Demolition of the above and below-grade 3790 structures was completed in April, 2014 (CCN-176194). Rejected storm water Underground Injection Control well Miscellaneous Stream # 378 was decommissioned during demolition of 3790 structures. The site was a french drain constructed of concrete pipe, covered with a 0.77 meter (2.53 foot) steel lid. The lid was posted with a "Confined Space" warning. This french drain was surrounded by asphalt.

Location: The site is located in the 300 Area on the east side of the 3790 Building.

Related Sites/ Structures: This site is associated with the 3790 building.

Process Description: According to the "Inventory of Miscellaneous Streams," Revision 3, the site receives stormwater from the drain at the bottom of the east stairwell and three drains in the 3790 courtyard.

Waste Type: Stormwater Runoff

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 3, the flow rate is less than 0.038 liters per minute (0.01 gallons per minute).

Code: 300-205 **Classification:** Not Accepted

Names: 300-205; 3790 Building Stormwater Runoff; F.D. #18; Injection Well #18; Miscellaneous Stream #377 **Reclassification:** None

Type: French Drain **Start Date:**

Status: Inactive **End Date:**

Description: Demolition of the above and below-grade 3790 structures was completed in April, 2014 (CCN-176194). Rejected storm water Underground Injection Control well Miscellaneous Stream #377 was decommissioned during demolition of 3790 structures. The site was a french drain constructed of concrete pipe and covered with a 1.16 meter (3.80 foot) steel lid. A roof drain pipe was visible near the french drain. The lid was labeled "FD 18" and "Confined Space." This site is surrounded by cobbles.

Location: The site is located on the west side of 3790, just south of the northwest corner of the building.

Related Sites/ Structures: This site is associated with the 3790 building.

Process Description: The site receives stormwater from 3790 building roof drains.

Waste Type: Stormwater Runoff

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 3, flow rate is less than 0.038 liters per minute (0.01 gallons per minute).

Code: 300-206 **Classification:** Not Accepted

Names: 300-206; 3790 Building Stormwater Runoff; Miscellaneous Stream #373 **Reclassification:** None

Type: French Drain **Start Date:**

Status: Inactive **End Date:**

Description: Demolition of the above and below-grade 3790 structures was completed in April, 2014 (CCN-176194). Rejected storm water Underground Injection Control well Miscellaneous Stream #373 was decommissioned during demolition of 3790 structures. The site was a french drain constructed of concrete pipe and covered with a 1.14 meter (3.75 foot) steel lid. The lid was labeled "Confined Space." The site is surrounded by cobbles. A roof drain pipe was visible near the french drain.

Location: The site is located in the 300 Area just north of the southwest corner of the 3790 building.

Related Sites/ Structures: This site is associated with the 3790 building.

Process Description: The site receives stormwater from 3790 building roof drains.

Waste Type: Stormwater Runoff

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 3, the flow rate is less than 0.038 liters per minute (0.01 gallons per minute).

Code: 300-207 **Classification:** Not Accepted

Names: 300-207; 3790 Building Stormwater Runoff; F.D. #16; Injection Well #16; Miscellaneous Stream #375 **Reclassification:** None

Type: French Drain **Start Date:**

Status: Inactive **End Date:**

Description: Demolition of the above and below-grade 3790 structures was completed in April, 2014 (CCN-176194). Rejected storm water Underground Injection Control well Miscellaneous Stream # 375 was decommissioned during demolition of 3790 structures. The site was a french drain constructed of concrete pipe and covered with a 1.15 meter (3.77 foot) steel lid. The lid was labeled "FD 16" and "Confined Space." This french drain was surrounded by cobbles. A roof drain pipe was visible near the french drain. Two metal pipes extending from the side of the building were also observed. A metal pipe approximately 1.83 meters (6 feet) in length runs parallel to the ground surface, approximately 0.3 meters (1 foot) above the surface. This pipe was part of the fire water test system. A small diameter, short, metal pipe elbow also extended from the building at the same level as the fire water test pipe.

Location: The site is located in the 300 Area on the west side of the 3790 building, just north of the main entrance door.

Related Sites/ Structures: This site is associated with the 3790 building.

Process Description: The site receives stormwater from 3790 building roof drains. According to the "Inventory of Miscellaneous Streams," Revision 3, this site also receives drainage from a nearby stairwell.

Waste Type: Stormwater Runoff

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 3, the flow rate is less than 0.038 liters per minute (0.01 gallons per minute).

Code: 300-208 **Classification:** Not Accepted

Names: 300-208; 3790 Building Stormwater Runoff; F.D. #17; Injection Well #17; Miscellaneous Stream #376 **Reclassification:** None

Type: French Drain **Start Date:**

Status: Inactive **End Date:**

Description: Demolition of the above and below-grade 3790 structures was completed in April, 2014 (CCN-176194). Rejected storm water Underground Injection Control well Miscellaneous Stream # 376 was decommissioned during demolition of 3790 structures. The site was a french drain constructed of concrete pipe and covered with a 1.15 meter (3.77 foot) steel lid. The lid was labeled "FD 17" and "Confined Space." A roof drain pipe was visible entering the french drain. This french drain was behind two bushes and is surrounded by cobbles.

Location: The site is located in the 300 Area on the west side of the 3790 building, just south of the main entrance door.

Related Sites/ Structures: This site is associated with the 3790 building.

Process Description: The site receives stormwater from 3790 building roof drains. According to the "Inventory of Miscellaneous Streams," Revision 3, this site also receives drainage from a nearby stairwell.

Waste Type: Stormwater Runoff

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 3, the flow rate is less than 0.038 liters per minute (0.01 gallons per minute).

Code: 300-209 **Classification:** Not Accepted

Names: 300-209; 3790 Building Stormwater Runoff; Miscellaneous Stream #374 **Reclassification:** None

Type: French Drain **Start Date:**

Status: Inactive **End Date:** 1/1/1998

Description: Demolition of the above and below-grade 3790 structures was completed in April, 2014 (CCN-176194). Rejected storm water Underground Injection Control well Miscellaneous Stream # 374 was decommissioned during demolition of 3790 structures. The site was a drain that receives stormwater runoff. It was located at the bottom of a covered stairwell. The drain was covered by a 0.31 meter (1.02 foot) metal grid and was surrounded by concrete.

Location: The site was located at the bottom of the north stairwell for the 3790 Building.

Related Sites/ Structures: This site is associated with the 3790 building.

Waste Type: Stormwater Runoff

Waste Description: The flow rate to the stairwell drain is less than 0.038 liters per minute (0.01 gallons per minute).

Code: 300-210 **Classification:** Not Accepted

Names: 300-210; 3790 Building Stormwater Runoff; Miscellaneous Stream #514 **Reclassification:** None

Type: French Drain **Start Date:**

Status: Inactive **End Date:**

Description: Demolition of the above and below-grade 3790 structures was completed in April, 2014 (CCN-176194). Rejected storm water Underground Injection Control well Miscellaneous Stream # 514 was decommissioned during demolition of 3790 structures. The site was a drain that received stormwater. The site was located at the bottom of a covered stairwell. The drain was covered by a 0.30 meter (0.98 foot) metal grate and is surrounded by concrete.

Location: The site was located on the west side of the 3790 building, at the bottom of the south stairwell.

Related Sites/ Structures: This site is associated with the 3790 building.

Waste Type: Stormwater Runoff

Waste Description: The flow rate to the stairwell drain is less than 0.038 liters per minute (0.01 gallons per minute).

Code: 300-211 **Classification:** Accepted
Names: 300-211; 382 Building Steam Condensate; Miscellaneous Stream #429 **Reclassification:** Rejected (12/15/1998)
Type: French Drain **Start Date:**
Status: Inactive **End Date:**

Description: The drain was decommissioned along with the demolition of the 382 complex in 2012. The site was a french drain that received steam condensate. The drain is a clay pipe with a 1.12 meter (3.67 foot) metal lid. In April 2012, the drain was filled with grout. The top of the clay pipe is visible a few centimeters above grade. The lid had three holes cut into it and is labeled "Confined Space." A metal pipe, approximately 2.5 centimeters (1 inch) in diameter, was labeled "LPD-TRP-016" and entered the drain through one of the holes in the metal cover. During a site walkdown in 1997, steam could be seen rising from the drain and the sound of a liquid being discharged into the drain could be heard.

Location: The site is located at the northwest corner of the north wing of the 382 Building.

Related Sites/ Structures: The site is associated with the 382 Building.

Process Description: Steam is produced from sanitary water that has been sent through a water softener system to remove minerals (calcium and magnesium). The treated water is introduced into boilers to produce steam. This steam is superheated before distribution to facilities for heating and process use. Disposal sites receive steam condensate from the steam distribution lines. When used for heating purposes, this is a seasonal discharge. Non-regulated chemicals are added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: When this site was active, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute).

Code: 300-212 **Classification:** Accepted
Names: 300-212; Miscellaneous Stream #400; MO010 Building Steam Condensate Sump **Reclassification:** Rejected (9/2/1998)
Type: French Drain **Start Date:**
Status: Inactive **End Date:**

Description: The site is a 121.9 centimeter (48 inch) condensate sump, constructed of concrete and covered with a steel plate. There are no postings.

Location: The site is located 7.6 meters (25 feet) south of the 3745 TRL-3 (M0-010) Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Code: 300-213

Classification: Accepted

Names: 300-213; Miscellaneous Stream #332; West High Tank (Water Tower) Overflow and Steam Condensate

Reclassification: Rejected (12/15/1998)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The site is a french drain that received steam condensate and overflow from a water tower. The drain has a square concrete base covered by two metal grates. The concrete base is approximately 1 meter (3.3 feet) deep. At the bottom of this reservoir is an opening approximately 11 centimeters (4.3 inches) in diameter. Inside the reservoir is a square metal plate held at an angle by two metal rods extending through the grates. Without this support, it appears as though the metal sheet would lay flat at the bottom of the reservoir and block the outlet pipe at the bottom. A metal pipe approximately 11 centimeters (4.3 inches) in diameter extends from the top of the water tower to just above the grates. Three pipes enter the northeast side of the reservoir approximately 0.4 meters (1.31 feet) from its top. The pipes terminate open-ended inside the reservoir. The site is surrounded by sand and cobbles.

Location: The site is located next to the southwest leg of the water tower south of the 3711 Building.

Related Sites/Structures: The site is associated with the water tower south of the 3711 Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Water

Waste Description: The site received sanitary water from the water tower.

Waste Type: Steam Condensate

Waste Description: When this site was active, the flow rate was less than 0.038 liters per minute (0.01 gallons per minute).

Code: 300-215

Classification: Accepted

Names: 300-215; 300 Area South

Reclassification: Rejected (1/27/1999)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site is very large and includes many different features. Much of the site is covered with vegetation such as cheatgrass and sagebrush. Two major roads cross the site: George Washington Way Extension and George Washington Way to Stevens Drive. Many old road traces exist and one major gravel road bisects the site. A gravel pit, and construction materials dumping ground are located in the north section of the site, south of the 300 Area fence, and west of the George Washington Way extension. Vestiges of irrigation canals are found throughout the site. Groundwater monitoring wells are found throughout the site. There is also a drywell (purpose unknown) in the area. Recent debris includes windblown garbage and tumbleweeds. Some older material near an irrigation canal may pre-date Hanford (e.g. porcelain china, battery cores, cans, and glass). A large diameter buried water line installed in the early 1990's is present in the southern part of the site. Underground electrical, water, and telephone lines are present on the site.

Location: The location and areal extent of 300-215 encompasses Stevens Drive on the west, Horn Rapids Road on the South, the Columbia River on the east, and the southern 300 Area fence line on the north.

Waste Type: Construction Debris

Waste Description: There is some construction debris in a dumping area. However, there does not appear to be any hazardous waste dumped in the area. Photograph #1 shows some small battery cores. This was a concern to the EPA and asked that they be picked up. As of February 9, 1999, the "Battery Cores" had been picked up and sent to the Centralized Consolidation/Recycling Center.

Code: 300-217

Classification: Not Accepted

Names: 300-217; 300 Area Laydown Yard

Reclassification: None

Type: Storage

Start Date:

Status: Active

End Date:

Description: The area is currently in use as a laydown area for construction materials. Construction materials observed at the site included Conex boxes, steel pipe, ladders, steel, plastic pipe, wood pallets, insulation material, and railroad ties. Several vehicles were also stored at the site. No wood utility poles were observed and no stains were observed on the soil from temporary storage of wood utility poles. Most material is stored off the ground on racks. An electrical structure is located in the northwest part of the site. The numbers on the structure are: C3X483 on the west side, C3X481 on the north side, and C3-24 on the south side. Four access manholes are present south of the structure. Three of the manholes are 1.22 meters (4 feet) in diameter and the fourth is 0.91 meters (3 feet) in diameter. A 1.22-meter (4-foot) square concrete structure with a metal lid is present about 15.24 meters (50 feet) south of the north side fence. Well 399-04-01 is present on the northeast corner of the site. A minor amount of blown-in paper was observed. A large borrow pit is found south of the site.

Location: The site is located in the 300 Area, southwest of the intersection of Cypress and George Washington Way Extension.

Waste Type: Equipment

Waste Description: There is no waste at this site. Waste that had been a concern to Ecology had been removed prior to the time that the site was entered into WIDS.

Code: 300-220

Classification: Not Accepted

Names: 300-220; Gravel Pit #7; Pit 7

Reclassification: None

Type: Depression/Pit (nonspecific)**Start Date:****Status:** Inactive**End Date:****Description:** The site is a manmade depression identified as Gravel Pit #7. The surface consists of sand and gravel with some cobbles, and a light vegetation cover of bunch grass and small sage. Trace fragments of concrete and asphalt can be found along the depression margins. Although it is included in the general radiologically controlled area north of the 300 Area, there are no site specific radiological postings.**Location:** Gravel pit #7 is located north of 300 Area, northeast of the railroad tracks.**Related Sites/** The pit is related to Aluminum Shavings Area (Site Code 300-8).**Structures:**

Code: 300-222**Classification:** Accepted**Names:** 300-222; 384-W Brine Pit; 384-W Salt
Dissolving Pit and Brine Pump Pit**Reclassification** Rejected (3/14/2002)**Type:** Sump**Start Date:** 1/1/1977**Status:** Inactive**End Date:****Description:** The brine pit, a concrete underground storage pit, was cleaned out and filled with sand/gravel in May 1998. At the surface the structure measures 5.18 meters (17 feet) by 3.05 meters (10 feet). It was divided into two sections. The larger section is the salt dissolving pit, also called "brine pit" on drawings. This section held the salt that was dissolved to make the brine. A 3.8 centimeter (1.5 inch) stainless steel sprinkler pipe runs the length of the pit. A 3.8 centimeter (1.5 inch) PVC (polyvinyl chloride) brine return line enters the pit through its south wall. The bottom of the pit was covered with a 15 centimeter (6 inch) layer of gravel topped by a 15 centimeter (6 inch) layer of sand. Three 2.9 meter (9.5 foot) lengths of 10 centimeter (4 inch) transite tile pipe were located within the gravel layer. These three pipes connected through a dividing wall into the adjacent section. An overflow drain is located near the top of the structure. The salt dissolving pit is identifiable at the surface by its red metal cover. The smaller section is the brine pump pit, also called "tank" in drawings. A 5 centimeter (2 inch) PVC line exits the pit through its south wall. The brine pump pit is identifiable at the surface by its gray metal cover.**Location:** The Brine Pit is located approximately 6 meters (20 feet) north of the west end of the 384 Powerhouse.**Process**
Description: The steam system used "soft" water. Water from the Water Filter Plant (315 Building) ran through a water softening process before going to the boilers. The brine was used to regenerate the ion exchange demineralizers in the water softeners. The brine was created by distributing raw water across the surface of the salt using the sprinkler pipe. As the water passed through the salt, the solution became saturated. The brine solution passed through the layers of sand and gravel which filtered out salt crystals and other particles. The filtered brine passed into the tile pipe and was discharged into the pump pit ready for use. Flow through the brine pit was achieved by the addition of new water into the salt dissolving pit and the removal of brine from the pump pit.**Waste Type:** Abandoned Chemicals**Waste**
Description: Before it was cleaned out, the structure contained salt cake and/or brine, both of which may be designated as dangerous waste.

Code: 300-223 **Classification:** Accepted

Names: 300-223; 384 Powerhouse Fuel Oil Day Tanks #1 and #2 **Reclassification:** Closed Out (7/8/2013)

Type: Storage Tank **Start Date:** 1/1/1964

Status: Inactive **End Date:** 1/1/1998

Description: The site has been remediated and Closed Out. The waste site was two, 16,000 gallon carbon steel, underground storage tanks, positioned horizontally, in a north-south direction. The site was backfilled on March 22, 2003 after the Day Tanks and surrounding contaminated soil had been removed.

Location: The centers of the day tanks were located north of the north wall of the 384 Powerhouse. Day Tank #1 was the east tank and Day Tank #2 was the west tank.

Related Sites/Structures: The Day Tanks were associated with the 384 Powerhouse (WIDS Site 300-26, Rejected), the 366/366A Fuel Oil Bunkers (WIDS Site 300-6, Interim Closed Out), UPR-300-7 (Closed Out) and UPR-300-42 (Interim Closed Out).

Process Description: Fuel oil was pumped into the Day Tanks from the larger fuel oil bunkers. A heater in the Day Tanks kept the oil temperature at 120 degrees Fahrenheit. The oil was used to fuel the 384 Powerhouse boilers to create steam.

Waste Type: Oil

Waste Description:

Closure Info: Final: The Remedial Action Report was issued in March 2000. The report describes the actions take to remove the petroleum contaminated soil and the two 16,000 gallon fuel tanks. On March 21, 1998, an offsite vendor removed the fuel from the 384 Fuel Bunker and associated day tanks. Some residual material remained in the tanks. In June of 1999, the tanks were removed, cleaned, and sold as scrap metal. A site assessment showed that diesel range organics and motor oils were found in almost all soil samples, and most were above the Model Toxics Control Act (MTCA) Method A cleanup levels of 200 milligrams per kilogram. Soils adjacent to the fill area of the tanks had the highest petroleum concentrations based on visual observations. No evidence of free product or petroleum saturated soil was found below the tanks. Visual inspection of the tanks indicated they were in good condition with no evidence of deterioration to the point that product would leak from them. The soil removed from the excavation was taken to Gravel Pit 9 for bioremediation (see 600-278). In September 1999, five verification samples were collected from the tank excavation and analyzed. The day tank excavation was backfilled to grade in March 2003.

Approximately 600 cubic meters of contaminated soil was removed from the site and taken to Pit 9 on the Hanford Site for bioremediation (sitecode 600-278). After visual and field screening indicated no contamination above cleanup levels remained in the excavation, five verification composite samples were collected and analyzed to confirm that cleanup levels had been met. One sample was collected from each of the sidewalls at about 1 meter (3 feet) above the base of the excavation and one from the floor of the excavation.

Code: 300-225 **Classification:** Not Accepted

Names: 300-225; 3790 Building Stormwater Runoff; Miscellaneous Stream #767 **Reclassification:** None

Type: French Drain **Start Date:**

Status: Inactive**End Date:**

Description: Demolition of the above and below-grade 3790 structures was completed in April, 2014 (CCN-176194). Rejected storm water Underground Injection Control well Miscellaneous Stream # 367 was decommissioned during demolition of 3790 structures. The site was a drain that received stormwater. It was located at the bottom of a stairwell that is covered with a corrugated metal roof. The drain was covered with a 0.30 meter (1.00 foot) metal grate and is surrounded by concrete.

Location: The site was located on the east side of the 3790 Building at the bottom of the stairwell. The entrance to the stairwell was located on the east side of a fence.

Related Sites/ Structures: This site is associated with the 3790 building.

Waste Type: Stormwater Runoff

Waste Description: This stream discharges to stream #378.

Code: 300-226**Classification:** Accepted

Names: 300-226; 3709A Building Miscellaneous Stream #768; Drip Station U39

Reclassification Rejected (5/26/1999)**Type:** Injection/Reverse Well**Start Date:****Status:** Inactive**End Date:**

Description: The site is covered with a 147-centimeter (58-inch) diameter steel plate. There are four holes in the cover. The drain structure is slightly elevated from the surrounding ground surface. The site is labeled "U-39" and is posted as a "Confined Space."

Location: The site is located off the southeast corner of the 3709A Building.

Related Sites/ Structures: The site was associated with 3709A Building.

Process Description: The site is a drip station for the underground steam line that supplies steam for the 3709A Building. Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 2, the flow was less than 0.038 liters (0.01 gallons) per minute of nondangerous/nonradioactive steam condensate.

Code: 300-227**Classification:** Accepted

Names: 300-227; 3709A Building Miscellaneous Stream #769; Drip Station U38

Reclassification Rejected (5/26/1999)**Type:** Injection/Reverse Well**Start Date:****Status:** Inactive**End Date:**

Description: The site is covered with a 147-centimeter (58-inch) diameter steel plate. There are four holes in the cover. The site is labeled "U-38" and is posted as a "Confined Space." It is flush with the surrounding ground in the lawn at 3709-A.

Location: The site is located off the northeast corner of the 3709A Building.

Process Description: The site is a drip station for the underground steam line that supplies steam for the 3709A Building. Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 2, the flow was less than 0.038 liters (0.01 gallons) per minute of nondangerous/nonradioactive steam condensate.

Code: 300-228

Classification: Accepted

Names: 300-228; Drip Station U28; HPD-TRP-026; Miscellaneous Stream #770; Steam Trap 3G-U28

Reclassification: Rejected (5/26/1999)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The site is a french drain that received steam condensate. The drain is a concrete pipe covered with a 1.47 meter (4.28 foot) diameter perforated metal plate. The lid is labeled "U-28" and is posted "Danger, Limited Access/Confined Space." The top of the pipe appears to be flush with the ground surface. The site is located on a low rise relative to the surrounding area and is surrounded by sand and gravel. According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive, source abandoned.

Location: The site is located west-northwest of the northwest corner of the 3760 Building.

Related Sites/Structures: The site is a drip station for the underground steam line that supplies steam for the 3709A Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 2, the flow was less than 0.038 liters (0.01 gallons) per minute of nondangerous/nonradioactive steam condensate.

Code: 300-230

Classification: Accepted

Names: 300-230; HPD-TRP-29; Miscellaneous Stream #771; Steam Trap 3G-U44; U44

Reclassification: Rejected (5/26/1999)

Type: Valve Pit

Start Date:

Status: Inactive**End Date:**

Description: The site is covered with a 173-centimeter (68-inch) diameter diamond plate steel cover. Although the Inventory of Miscellaneous Streams, Rev 3 lists this site as a steam condensate injection well, it has been determined that it does not meet the definition of an Underground Injection Control well (UIC).

A square access hatch is located in the center of the cover. The below grade section is constructed of concrete with a dirt floor. The interior of the pit contains valves which released steam condensate to the floor. The site is labeled "U-44" and is posted as a "Confined Space."

Location: The site is located near the southeast corner of the 3746 Building.

Process Description: Steam is produced from sanitary water that has been sent through a water softener system to remove minerals (calcium and magnesium). The treated water is introduced into boilers to produce steam. This steam is superheated before distribution to facilities for heating and process use. Disposal sites receive steam condensate from the steam distribution lines. When used for heating purposes, this is a seasonal discharge. Non-regulated chemicals are added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: Steam condensate was discharged to the floor of the pit. According to the "Inventory of Miscellaneous Streams," Revision 2, the flow was less than 0.038 liters (0.01 gallons) per minute of nondangerous/nonradioactive steam condensate.

Code: 300-235**Classification:** Accepted

Names: 300-235; 3713 Building Storm Water Runoff and Steam Condensate; Miscellaneous Stream #766

Reclassification: Rejected (5/26/1999)**Type:** French Drain**Start Date:****Status:** Inactive**End Date:**

Description: The site is a french drain that currently receives only stormwater. The drain is a concrete pipe that is covered by a 0.76 meter (2.49 foot) metal lid with perforations. The top of the pipe is flush with the ground surface and is surrounded by soil and gravel. The drain appears to be filled with soil to within approximately 0.7 meters (2.3 feet) of the top of the pipe. The upper 0.45 meters (1.5 feet) of the concrete pipe appear to be lined with some kind of a metal that is pulling away from the pipe. At least two, possibly three, metal pipes were observed extending into the side of the drain from the west. A small diameter (approximately 2.5 centimeters or 1 inch) pipe enters the side of the drain, makes a 90 degree turn and disappears into the floor of the drain. An approximately 5 centimeter (2 inch) open end pipe extends approximately 5 centimeters (2 inches) from the side of the drain. What appears to be a third pipe is covered with cobwebs that could not safely be removed. There are no pipes descending from the overhead steam line in the vicinity of the site. According to the "Inventory of Miscellaneous Streams," Revision 3, the steam source has been shut off.

Location: The site is located approximately 9 meters (29.5 feet) northeast of the northwest corner of the 3713 Building, under the overhead steam line.

Related Sites/Structures: The site is associated with the 3713 Building.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and

process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 2, the flow was less than 3.8 liters (1.0 gallons) per minute of nonhazardous/nonradioactive steam condensate. The site no longer receives steam condensate.

Waste Type: Stormwater Runoff

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 3, the flow is less than 3.8 liters (1.0 gallons) per minute of stormwater only.

Code: 300-236

Classification: Accepted

Names: 300-236; HPD-TRP-020; Miscellaneous Stream #772; Steam Trap 3G-U45; U-45

Reclassification: Rejected (5/26/1999)

Type: Valve Pit

Start Date:

Status: Inactive

End Date:

Description: The site is a valve pit that received steam condensate. The structure has a square concrete base with a 1.31 meters (4.30 feet) by 1.31 meters (4.30 feet) metal lid. The lid is labeled "U-45" and "Danger, Confined Space." The lid has a hatch that allows access to its interior. The top of the concrete base ranges from approximately 5 to 10 centimeters (2 to 4 inches) above the ground surface. The site is surrounded by sand and some gravel. According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive, source abandoned.

Location: The site is 10 meters (32.8 feet) southwest of the southwest corner of the 3719 Building. It is just east of the Apple Street Gate.

Related Sites/ Structures: The site is related to the 300 Area steam line.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 3, the flow was less than 0.04 liters (0.01 gallons) per minute of nondangerous/nonradioactive steam condensate.

Code: 300-237

Classification: Accepted

Names: 300-237; Miscellaneous Stream #773; Steam Trap HPD-TRP-010

Reclassification: Rejected (5/26/1999)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The drain was decommissioned in 2012. The site was described as a french drain that received

steam condensate. An engineered structure was not evident in the field. A steam pipe runs down from the overhead steam line and terminates open-ended centimeters above the ground surface. The pipe is labeled "HPD-TRP-010." There is some soil discoloration where the pipe terminates above the ground surface that appears to be rust stains. This discoloration is confined to a very small area. There is also some rust discoloration on the concrete base of the pole that supports the steam pipe. The site is surrounded by sand with some gravel. According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive, source abandoned.

Location: The site is located southeast of the southeast corner of the 303C Building, west of 3707D, on the west side of Wisconsin Street.

Related Sites/ Structures: The site is associated with the 300 Area steam line.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 2, the flow was less than 0.04 liters (0.01 gallons) per minute of nondangerous/nonradioactive per minute of steam condensate.

Code: 300-238

Classification: Accepted

Names: 300-238; HPD-TRP-016; Miscellaneous Stream #774; Steam Trap 3G-U24; U-24

Reclassification: Rejected (5/26/1999)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The site is a french drain that received steam condensate from an underground steam line. The drain is a concrete pipe covered by a 1.55 meter (5.09 foot) diameter metal lid. The lid is labeled "U-24" and "Danger, Limited Access/Confined Space." The site is surrounded by sand and gravel. The site or the nearby steam line are not labeled "HPD-TRP-016." According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive, source abandoned.

Location: The site is located west-southwest of the southwest corner of the 305 Building, next to Alaska Street. It is just north of where the overhead steam line goes underground.

Related Sites/ Structures: The site is associated with the 300 Area steam line.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 2, the flow used to be less than 0.04 liters (0.01 gallons) per minute of nondangerous/nonradioactive steam condensate.

Code: 300-239 **Classification:** Accepted

Names: 300-239; HPD-TRP-058; Miscellaneous Stream #775; Steam Trap 3G-U26; U26 **Reclassification** Rejected (5/26/1999)

Type: French Drain **Start Date:**

Status: Inactive **End Date:**

Description: The site is a french drain that received steam condensate. The drain appears to be a rust stained concrete pipe covered by a 0.61 meter (2.0 foot) diameter metal lid. The metal lid has some perforations and is labeled "U-26." The top of the pipe ranges from flush with the ground surface to approximately 2.5 centimeters (1 inch) above grade. The site is surrounded by sand and some asphalt. According to the "Inventory of Miscellaneous Streams," Revision 3, the site is inactive, source abandoned.

Location: The site is located on the south side of the 3762 Building, at the bottom of the access ramp. The "Inventory of Miscellaneous Streams," Revision 3, erroneously locates the stream south of the 3762 Building.

Related Sites/ Structures: The site is associated with an underground steam line.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion.

Waste Type: Steam Condensate

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 2, the flow was less than 0.038 liters (0.01 gallons) per minute of nondangerous/nonradioactive steam condensate.

Code: 300-240 **Classification:** Not Accepted

Names: 300-240; 314 Building Stormwater Drain; Miscellaneous Stream #789 **Reclassification** None

Type: French Drain **Start Date:**

Status: Inactive **End Date:**

Description: The site was a french drain that received stormwater runoff. It was sealed with grout in 2005. The drain appeared to be constructed of concrete and is covered by a 0.64 meter (2.10 foot) metal grate. The grate was stamped "STD 42" and its edge seems to be sealed. The drain appeared to be approximately 30 centimeters (1 foot) deep. The bottom was covered with sand and gravel. An approximately 10 centimeter (4 inch) diameter pipe entered the west side of the drain, makes a 90 degree turn towards the ground surface, and terminates with a screened opening. The top of the drain is flush with the ground surface, which is slightly depressed relative to the surrounding area. It appears as though the drain would collect runoff from the asphalt on the north side of 314 and from the gravel area southeast of 305B. During the December 17, 1998, walkdown, the inside of the drain appeared to be damp. The drain is surrounded by broken concrete, gravel and cobbles. The 314 Building is a closed facility. There is a similar structure west of this site, southeast of the southeast corner of 305B, south of the fenced area.

Construction drawings H-3-52655 and H-3-304714 sheet 2 show that the open bottom catch basin/french drain location is connected directly to the (300-15) process sewer pipeline.

Location: The site is approximately 17 meters west of the northeast corner of the 314 Building, just north of the asphalt.

Related Sites/ Structures: The site is associated with the area on the north side of the 314 Building.

Waste Type: Stormwater Runoff

Waste Description: According to the "Inventory of Miscellaneous Streams," Revision 3, the flow is less than 0.038 liters (0.01 gallons) per minute of stormwater only.

Code: 300-241 **Classification:** Not Accepted

Names: 300-241; 320 Building Irrigation Line Effluent; Miscellaneous Stream #790 **Reclassification:** None

Type: French Drain **Start Date:**

Status: Inactive **End Date:**

Description: The site was a 60 centimeter (2 foot) diameter, sprinkler valve pit. There is a water valve inside. It was decommissioned in March 2012.

Location: The site was located on the southwest side of the 320 Building. WCH corrected the coordinates of 300-241, to be atN115486, E593769.4.

Process Description: The lawn around the 320 Building had underground sprinklers. This water valve operated the system.

Waste Type: Water

Waste Description: This site receives less than 0.038 liters (0.01 gallons) per minute of effluent from irrigation.

Code: 300-242 **Classification:** Not Accepted

Names: 300-242; 325 Building Stormwater Runoff; Miscellaneous Stream #791 **Reclassification:** None

Type: French Drain **Start Date:**

Status: Inactive **End Date:**

Description: The site is a concrete box that received drainage from the 325 Building. The box is a ground level, square, concrete structure with a steel cover. It measures approximately 0.9 meters (3 feet) by 0.9 meters (3 feet) and is approximately 0.6 meters (2 feet) deep. A large diameter carbon steel line coming from the basement of the 325 Building terminates inside the structure.

Location: The site is located approximately 4.5 meters (15 feet) east of the northwest corner of the 325 Building. The site is adjacent to Fire Protection Riser #1.

Waste Type: Stormwater Runoff

Waste Description: According to the Inventory of Miscellaneous Streams, Revision 3, the site receives less than 0.038 liters (0.01 gallons) per minute of stormwater only.

Code: 300-243 **Classification:** Not Accepted
Names: 300-243; 318 Building Stormwater Runoff; **Reclassification** None
Miscellaneous Stream #792
Type: French Drain **Start Date:**
Status: Active **End Date:**

Description: The site is a rectangular grate in the pavement. Water was observed in the bottom of the drain during a site walkdown on December 14, 1998.
Location: The site is located on the north side of the 318 Building in the asphalt driveway.
Related Sites/ Structures: The site is related to the 318 Building.
Process Description: The drain receives stormwater runoff from the 318 Building.
Waste Type: Stormwater Runoff
Waste Description: The site receives less than 0.038 liters (0.01 gallons) per minute of stormwater only.

Code: 300-244 **Classification:** Not Accepted
Names: 300-244; 318 Building Stormwater Runoff; **Reclassification** None
Miscellaneous Stream #793
Type: French Drain **Start Date:**
Status: Active **End Date:**

Description: The site is a horizontal, metal culvert that protrudes from the ground in a gravel depression. The pipe runs under the asphalt driveway, westward toward the 318 Building.
Location: The coordinates and location given in the Inventory of Miscellaneous Streams Report (Rev. 3) indicate this site is located on the east side of the 318 Building, east of the access driveway.
Waste Type: Stormwater Runoff
Waste Description: The site receives less than 0.038 liters (0.01 gallons) per minute of stormwater only.

Code: 300-248 **Classification:** Accepted
Names: 300-248; 340B Steam Condensate Sump Pit **Reclassification** Rejected (5/26/1999)
Type: Sump **Start Date:**
Status: Inactive **End Date:**

Description: The site is a sump that collected condensate from process steam. The visible structure is approximately 1.22 meters (4 feet) in diameter, with an entry hatch. Originally, the sump was open to the ground under the building. Later the bottom was filled with concrete.
Location: The steam condensate sump is located inside the 340B building, near the southeast corner. The sump structure is located in side a radiologically controlled area.

Process Description: Steam was used to decontaminate rail cars at the 340 B building. The steam condensate sump collected condensate from the process steam. The contaminated solution that resulted from steam cleaning the railcars was flushed into a different drain that led to the Process Sewer.

Waste Type: Steam Condensate

Waste Description: Steam was used to decontaminate rail cars at the 340B building. The steam condensate sump collected condensate from the process steam. The contaminated solution that resulted from steam cleaning the railcars was flushed into a different drain that led to the Process Sewer.

Code: 300-249

Classification: Accepted

Names: 300-249; 304 Building; Residual Rad Contamination

Reclassification: Final Closed Out (5/12/2014)

Type: Unplanned Release

Start Date: 1/1/1952

Status: Inactive

End Date: 1/1/1995

Description: The waste site has been remediated and Interim Closed Out. It was the 304 building and its foundation. The waste site was the residual radioactive contamination at the 304 Building that was not part of the Closed Out 304 Concretion Facility RCRA TSD.

Location: The 304 Building was located in the northwestern 300 area on the south side of Ginko Street across from the 303-K, 314, and 313 Buildings.

Release Description: A billet fire in 1977 may have contributed to the spread of contamination within the building. In August 1977, high temperatures inside the 304 Facility (resulting from the failure of the cooling system) caused six concrete billets in 28.4 liter (7.5 gallon) containers to ignite. Uranium oxide and small amounts of zirconium oxide and copper oxides were formed by the burning billets.

Related Sites/Structures: 300-249 is associated with 300-43, Unplanned Release Outside the 304 Building, 304 Concretion Facility (304 CF) and 304 Storage Area (304 SA).

Waste Type: Chemicals

Waste Description: Residual uranium contamination remains in the building from its past use as a concretion facility.

Closure Info: Interim (11/28/2011): The 300-28, 300-43, 300-48, 300-249, and 300-16:3 excavation of building foundations, associated pipelines, and soils began on June 28 and was completed by July 29, 2010. Due to elevated radiologically contaminated soil found north of 303E Building, additional remediation was performed September 30, 2010, targeting specific locations with elevated readings. The excavation of the 300-28, 300-43, 300-48, 300-249, and 300-16:3 waste sites resulted in a total of approximately 2,914 bank cubic meters (BCM) (3,811 bank cubic yards [BCY]) of contaminated soil and debris. All material was direct loaded for disposal at the Environmental Restoration Disposal Facility (ERDF).

Remediation of the 300-28, 300-43, 300-48, 300-249, and 300-16:3 waste site excavations included removal of the 303A, 304, 304A, 303B, 3732, 303C, 3707D, and 303E Buildings concrete slabs. The manholes and intersections of the 300-15 process sewer were excavated and removed from within the excavation boundaries. All the foundation debris such as concrete, metal rebar, miscellaneous piping (steam, water, etc.), and electrical conduit was excavated and removed from the waste sites. No anomalous materials were observed during remedial activities.

Although remediation and verification sampling was performed for the 300-161 waste site, it was then noted that 300-161 waste site was reclassified as a Rejected site and therefore did not require remediation or site closure process. The 300-161 waste site was removed from the

RSVP. The 300-60, 300-61, 300-62, 300-161, 300-162, 300-176, 300-193 and 300-237 Rejected waste sites were located within the 300-28, 300-43, 300-48, 300-249, and 300-16:3 excavation layback.

Final: (Final) No additional remediation was performed at the site.

Code: 300-250	Classification: Not Accepted
Names: 300-250; Valve Pit Southeast of 303A	Reclassification: None
Type: Valve Pit	Start Date:
Status: Active	End Date:

Description: The site is a valve pit for a sanitary water line. The pit has a rectangular concrete base covered by a 1.12 meter (3.67 foot) by 1.42 meter (4.66 foot) metal lid. The top of the concrete ranges from 11 to 20 centimeters (4.3 to 7.9 inches) above the ground surface. The site is surrounded by sand and gravel. The lid is posted "Confined Space." Both "W 26" and "W 16" are written in fading paint on the lid. The overhead steam line terminates and is capped at the north edge of the 3717B Building. The site is just south of the "Radiologically Controlled Area" signs around the 303A, 304 and 303B Buildings.

On December 10, 1998, a DynCorp employee removed the lid of the structure just described, allowing access to its interior. The pit is approximately 0.9 to 1.2 meters (3 to 4 feet) deep and has a gravel-covered bottom. An approximately 5 to 7.6 centimeter (2 to 3 inch) pipe runs across the pit from east to west. Two valves were visible in the pit. There are no drains.

Location: The site is located southeast of the 303A Building and southwest of the 304 Building.

Related Sites/ Structures: The valve pit is associated with the sanitary water distribution system.

Code: 300-261	Classification: Accepted
Names: 300-261; 315 Filter Plant Process Sewer to River	Reclassification: Rejected (5/26/1999)
Type: Process Sewer	Start Date:
Status: Inactive	End Date:

Description: The sewer is constructed of a 0.61 meter (24 inch) vitrified clay pipe from the building to the river bank. A 0.8 meter (30 inch) corrugated steel flume (1/2 pipe) conveys the effluent down the riverbank and into the river. There is an active stormwater drain located on the west side of the road and due east of the outfall flume. This site has been identified as outfall 012 in DOE/EIS-0113.

Location: The 315 Filter Plant Process Sewer pipeline extends south easterly from the southeast corner of the 315 building towards 3906 Lift Station and then bends due east to the Columbia River.

Release Description: The effluent pipe inside the diversion box near the 315 building has been blanked off with plywood and filled in with concrete.

Process Description: The sewer conveyed water from the 315 basin overflow drains and the 315 filter backwash water to the river.

Waste Type: Water

Waste Description: The waste is a process sewer pipeline that received overflow and filter backwash from the 315 Filter Plant. Treatment chemicals included alum (aluminum sulfate), chlorine, and separan (a

polyacrylamide -flocculent). The site no longer receives material from the 315 Filter Plant. It can receive stormwater.

Code: 300-264	Classification: Accepted
Names: 300-264; 327 Building; Demolished 327 Building; Postirradiation Testing Laboratory (PTL)	Reclassification: Rejected (8/13/2013)
Type: Foundation	Start Date: 1/1/1953
Status: Inactive	End Date:

Description: This waste site was evaluated and Interim Closed Out in 2012. It was reclassified to Rejected in 2013 because buildings are outside the scope of WIDS. The waste site originally described the physical structure of the 327 building. The 327 Building demolition occurred from April 2009 through August 2010. The basement remained a posted Radioactive Contamination Area during final remediation and closeout actions. The building and foundation demolition was completed in May 2012. Soil samples were collected and analyzed in June 2012.

The 327 Basement was separated into 3 areas. The north third was used to store supplies, idle equipment, cell plugs, and includes the SERF Cell storage. Legacy wastes (buckets with pieces of Transuranic Waste [TRU]) were staged in this area pending disposal. The middle of the basement housed the hot cell ventilation ductwork, HEPA filters for the hot cells, and the activated charcoal filtration system. The activated charcoal filtration system did not have filters installed because there are no programmatic or regulatory need. An access hatch to a crawl space containing building steam pipes was also in this area. The south third of the basement was separated from the rest of the basement by a wall. It included a cold equipment room, and hot and cold exhaust supply fans for the facility air inlet system supply. It also contained the Retention Process Sewer system diverter, stack monitoring system, stack base plenum and related equipment, vacuum air sampling system and pumps, and steam system components.

Location: The 327 Building was in the central part of the 300 Area, on the southwest corner of the intersection of California Street and Apple Street.

Release Description: Several unplanned releases and occurrences are recorded for the 327 Building. Occurrence reports over the previous decades showed fires and explosions in several of the Cells, contamination found outside of normal containment (to areas within the building, the outside atmosphere, and soils under the building), and the Retention Process Sewer Line improperly connected to the Process Sewer Line.

More recently, the fire suppression sprinkle line broke December 26, 1998. An estimated 57,000 to 76,000 liters (15,000 to 20,000 gallons) of water was released into the basement of the 327 building. A portion of the water collected in the elevator shaft. An estimated 946 liters (250 gallons) leaked into the soils under the building before the rest could be pumped to the 307 Facility. Analysis showed the water to be slightly radioactive.

Related Sites/Structures: The floor drains from the Cells flowed into the 300 Area Radioactive Liquid Waste System (RLWS), which drained to the 340 Waste Handling Complex. A concrete access port to the RLWS valve pit was located in the parking lot on the southeast corner of the 327 building. The 327 RLWS piping is isolated from the 340 Facility by blind flanges (nuclear blank) in the southeast corner of the hot side basement. The building was later connected to the 300 Area Retention Process Sewer (WIDS sitecode 300-214) which drained to the 307 Retention Basins. The building was originally connected to the Retired Radioactive Liquid Waste System (300 Area RRLWS).

Process Description: The Post Irradiation Testing Laboratory (PTL) consisted of specially equipped, shielded, and ventilated Hot Cells and laboratories designed for physical and metallurgical examination and testing of irradiated fuels, concentrated fission products, and irradiated structural materials. The primary task was to determine the nature and causes of dimensional instability in fuel elements and the effects of irradiation stresses on pile materials. This involved destructive testing on extremely high level radioactive materials, including ruptured or failed fuel rods containing plutonium and fresh fission products. The irradiated grinding fines generated by the work were swept up and treated as solid wastes, but powdery dusts were spread into air filters, ducts, and pipes.

Waste Type: Equipment

Waste Description: Waste material was contained in the building ducts, filters, and piping. A 1995 assessment showed most gamma activity was due to Cesium-137, Cesium-134, Europium-154, and Cobalt-60. Approximately 170 grams (maximum) of plutonium was estimated to be in the ducts, piping and other locations in the building, with an additional 314 grams estimated to be in the cells.

Closure Info: Interim (6/13/2012): Demolition of the 327 building and foundation was completed in May 2012. Residual contaminated soil removal was completed in June 2012. Subsequent evaluation of contaminated soil following the removal of the basement confirmed no releases from building operations had occurred. The residual soil contamination was the result of the building demolition activities. The exception is contaminated soil encountered during the removal of the Retired Radioactive Liquid Waste System (RRLWS) and Radioactive Liquid Waste System (RLWS) pipelines in the building layback area. The radiologically contaminated soil at the termination of the RRLWS and RLWS pipelines remains in place and will be addressed with the pipeline removal action.

Radiological surveys using hand held and global positioning radiological survey equipment were performed to identify contamination hot spots.

Code: 300-266

Classification: Accepted

Names: 300-266; Soil Under 3728 Building Drain Pipe

Reclassification: Rejected (3/8/2001)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The 300-266 drain pipe was removed during the demolition of the 3728 building in 2008 (Per CNN 148748). The site was soil below a 5-centimeter (2-inch) black plastic drain pipe on the southwest corner of the 3728 Building. In October, 1999, a white plastic bucket was placed under the drain pipe to catch any water draining out. The soil under the pipe is lightly graveled (as is the larger area around the entire building), with some of the gravel directly under the pipe washed away. The soil is not discolored. No engineered structure was built as an injection well.

Location: The soil is at the southwest corner of the 3728 Building, in the 300 Area.

Related Sites/ Structures: The 3728 Building is the source of the drain pipe.

Process Description: The drain pipe is connected to a sink where containers are filled with de-ionized water. The de-ionized water system is also connected directly to the drain pipe, and contributes water to the pipe when the system undergoes maintenance. The water is site service water with trace amounts of sodium hypochlorite and hydrogen peroxide, used to disinfect the system.

Code: 300-267

Classification: Accepted

Names: 300-267; French Drain on Northeast Corner of 3728 Building; Miscellaneous Stream #829 **Reclassification** Rejected (3/8/2001)

Type: French Drain **Start Date:**

Status: Inactive **End Date:**

Description: The drain structure has been removed and properly backfilled. The site was a concrete slab with a square pit at the end. The pit was 0.6 meters (2 feet) on a side, and filled with small pea gravel. A galvanized, 3.2-centimeter (1.25-inch) pipe came from the 3728 building and entered the pit.

Location: The site was on the northeast corner of the 3728 Building.

Related Sites/ Structures: The HVAC system for the 3728 Building is associated with the french drain. The 3728 Building is the ERC sample shipping facility.

Process Description: The french drain received water from the HVAC system for the 3728 Building.

Code: 300-271 **Classification:** Accepted

Names: 300-271; 324/327 Buildings 90 Day Storage Pad; HS-027 **Reclassification** Rejected (9/14/2000)

Type: Storage Pad (<90 day) **Start Date:** 1/1/1997

Status: Inactive **End Date:** 1/1/2000

Description: The dangerous waste was kept in a conex box commercially manufactured for storing wastes. The box has a spill containment system in that the waste was stored on a grate at the level of the door threshold, and any spills would be contained under the grate so they could not spill out the door. The box is still in place, but is now used to store hazardous material intended for future use, such as roofing material, propylene glycol (trade name Dow Frost), and oils.

Location: This site was north of the 324 facility and west of the 3718E warehouse. It was within the 324 Building fenced and locked compound.

Related Sites/ Structures: This pad was used for hazardous and dangerous wastes from the 324 and 327 Buildings.

Process Description: The logbook for this pad shows only 6 entries for dangerous waste from the start date of October 31, 1997 to July 15, 1999. Materials stored there include absorbed gasoline, oils (possible contaminated with heavy metals), ice melt (sodium chloride), baking soda, toluene, and PCBs.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: Wastes stored at this 90 Day Pad include absorbed gasoline, oils (possibly contaminated with heavy metals), ice melt (sodium chloride), toluene, and PCBs.

Code: 300-272 **Classification:** Accepted

Names: 300-272; Underground Storage Tank Near the 377 Building **Reclassification** Closed Out (11/4/2002)

Type: Storage Tank **Start Date:**

Status: Unknown **End Date:**

Description: The waste site was an underground, gasoline storage tank that was removed in 2002.

Location: The underground storage tank was located within the industrial boundary of the 300 Area southeast of the 377 Building and northwest of the intersection of Alaska Street and Ginko Street.

Process Description: The 11,356 liter (3,000 gallon) tank served as a gasoline fueling station until the 1960's. The dispensing pump was removed prior to 1968 and the tank was removed in 2002.

Waste Type: Oil

Waste Description: Upon initial investigation of the UST site, an odor of fuel oil or diesel was noted when the fill tube extending above the ground surface was opened. Subsequent sampling and analysis of the tank contents in December 2001 indicated the liquid to be water with the impurities listed in the WSCF Analytical Results Report (See Field Work entry).

Closure Info: Final: The Site Assessment Results report states that the liquid removed from the tank consisted of water with impurities. The contents of the tank were sampled on December 17, 2001 and analyzed at the WSCF laboratory (see additional details under the "Field Work" tab). Excavation of the soil surrounding the UST, the pipe connecting the tank to the dispensing pump, and the concrete pad used to support the dispensing pump was completed by January 25, 2002.

A total of 37 samples including QA samples were collected and analyzed for total petroleum hydrocarbons in both the diesel fuel and gasoline ranges. No evidence of leaking or failure of the connecting pipe or the tank was observed.

Code: 300-278	Classification: Accepted
Names: 300-278; 331-C Storage Unit	Reclassification: Closed Out (7/22/2011)
Type: Storage	Start Date: 1/1/2006
Status: Active	End Date:

Description: The waste site is the RCRA TSD, 331-C Storage Unit. It is a one-story metal building with fenced exterior areas constructed in the early 1970s. Upgrades were completed in 2006 to meet requirements for storage of dangerous waste. Dangerous wastes were stored in Room 1 of the 331-C building. The RCRA TSD Dangerous Waste Permit Application Part A Form was Closed on 7/22/2011.

Location: The unit is located within the southern portion of the 300 Area, south of the 331 complex, near the intersection of Docton and Denmark Ave.

Process Description: The unit is used for the collection, consolidation, packaging, storage and preparation for transport and disposal of dangerous waste. Varieties of small volume chemical wastes are generated by PNNL's research laboratory activities under contract to DOE. These wastes are brought to the 331-C Storage Unit and segregated by compatibility for storage in the unit until enough waste is accumulated to fill a labpack or bulking container, usually a 30 to 55 gallon drum. When a sufficient number of shipping containers of waste have accumulated, they are manifested for shipment, generally to permitted off-site recycling, treatment or disposal facilities.

Waste Type: Chemicals

Waste Description: The unit stores waste that may include acid, oxidizers and flammable materials.

Closure Info: Final (7/22/2011): On February 8, 2011, PNNL completed removal of waste stored at the 331-C

Storage Unit. The majority of the waste stored at the 331-C Storage Unit was transferred offsite for treatment and disposal. The 331-C Storage Unit was transferred to Washington Closure Hanford (WCH) contractor (Co-Operator) in February 2011, to undergo closure. No further, waste management activities will be conducted in the facility prior to building removal and closure.

The RCRA TSD Dangerous Waste Permit Application Part A Form was Closed on 7/22/2011.

Code: 300-282	Classification: Accepted
Names: 300-282; Crib Near 3717-B Building	Reclassification: Rejected (6/8/2011)
Type: Crib	Start Date:
Status: Inactive	End Date:
Description: This feature consists of the historical location of temporary experimental autoclaves with a settling tank that was connected to a wooden French drain. (DDTS-Generated-3822).	
Location: The site location is not exactly known, but the information suggests it was near the process and sanitary lines at approximately (E) 593809 and (N) 116037. This is close to the midpoint of the process sewer (300-15) and sanitary sewer lines (300 SSS) that run underneath the footprint of the 3717-B building. There are other lines that run close by and lie within 20 m (65 ft) of the given coordinates and could be the site of the contamination spread (DDTS-Generated-3822).	
Related Sites/ Structures: The 3717-B building was either constructed over the site or close to the site in 1950.	
Process Description: In 1944, temporary experimental autoclaves were installed on this site employing a settling tank connected to a wooden French drain or crib. The existence of the buried drain or crib is not posted or indicated on 300 Area drawings. During excavation for the construction of the 3717-B building during October 23-24, 1950, contamination of up to 50 mrep per hour was found on an upright, protruding timbers and soil. The contaminated timbers were potentially part of the forgotten French drain or crib. The site was subsequently excavated, but it is not known if the site was cleaned to today's standards or if the settling tank was removed (DDTS-Generated-3822). The excavated soil was used to create a mound in the 300 West area (618-13).	

Code: 300-285	Classification: Not Accepted
Names: 300-285; Ten French Drains and Dry Wells in 300 Area; 300 Area Steam Condensate French Drains/Dry Wells	Reclassification: None
Type: French Drain	Start Date:
Status: Inactive	End Date:
Description: This site consists of 10 discrete locations and underlying soil of steam condensate French drains/drywells and their associated below grade piping components. The French drains/drywells were discovered during the Orphan Site Evaluation (OSE) historical review. Each of the facilities that the French drains/drywells are associated with, were identified and process or function of the buildings determined. Details of inlet pipes, and French drain/drywell size and construction details are provided when available. Field verification and photographs of the present site conditions were obtained.	
See detailed descriptions for each drain in site comment.	
Location: The french drains are located throughout the 300 Area. See detailed locations for each drain in	

site comment.

Related Sites/ Structures: The drains are associated with the 301, 314, 315, 331, 335, 382, 3701-A and 3701-L Buildings.

Process Description: Steam was produced from sanitary water that had been sent through a water softener system to remove minerals (calcium and magnesium). The treated water was introduced into boilers to produce steam. This steam was superheated before distribution to facilities for heating and process use. Disposal sites received steam condensate from the steam distribution lines. When used for heating purposes, this was a seasonal discharge. Non-regulated chemicals were added to dechlorinate the water, prevent scale, and control corrosion. One drywell drained the stairwell landing of the first floor of the 314 building of rainwater.

Code: 303-K CWS	Classification: Accepted
Names: 303-K CWS; 303-K Contaminated Waste Storage	Reclassification: Closed Out (8/5/2002)
Type: Storage	Start Date: 1/1/1943
Status: Inactive	End Date: 1/1/2002

Description: The waste site was the form TSD storage area inside 303-K. The building was demolished in 2001. The RCRA TSD was Clean Closed on July 22, 2002.

The 303-K Facility included a former concrete and cinder block building with no windows, outdoor asphalt, concrete, and gravel storage areas, all surrounded by a six foot chain link fence. The building had a cinder block east-west partition wall with a floor trench drain in the north room. The floor trench drain was sealed in 1988.

Location: The unit was located in the 300 Area on Ginko Street between the 313 and 314 Buildings.

Related Sites/ Structures: Structures associated with the 303-K Building include the other 303 Buildings, the 304 Building, the 333 Building, the 334-A Building, the 300 Area Waste Acid Treatment System, the exterior storage areas, and the process sewer system. The contaminated soil under and surrounding the facility was documented as WIDS site 300-251.

Process Description: The main building was constructed in 1943 to store radioactive and mixed waste generated in the 300 Area. From 1943 to 1953, uranium and aluminum canned uranium was stored in the building. In 1953, the building was partitioned, floor trench drains and work benches were installed in the north room. In 1953 and 1978, outdoor storage pads (concrete and asphalt) were constructed to support the decontamination of aluminum reactor spacers until 1971. From 1953 to present, radioactive and mixed waste had been stored outside the building on the concrete, asphalt, and gravel pads. From 1971 to 1977, the north room was used for equipment decontamination and for storage. The interior walls were painted with a lead-based paint in 1977. Between 1977 and the fall of 1982 the unit was used to cure and test concreted billets of uranium chips and fines from the 304 Concretion Facility. Additional outdoor storage pads were installed in 1978 (asphalt) and in 1979 (concrete). From 1982 to 1986 the building continued to be used for equipment decontamination and storage. After 1986, the building was used to store containers of low-level radioactive waste and mixed waste.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: Since 1943, the building had been used to store various amounts of low-level radioactive wastes and mixed waste. Solids were stored outside, while liquids were contained inside the building. The mixed waste stored after January 1986 included:

a. Neutralized solid waste for the unrecoverable uranium stream of the 300 Area Waste Acid Treatment System

- b. Uranium contaminated metallic lead
- c. Salt and sludge containers from beta and quench metal heat treatment furnaces
- d. Uranium contaminated perchloroethylene, chloroform, and ethyl acetate
- e. Beryllium/zircaloy-2 alloy chips and fines generated at the stepcut lathe, before and after concreting at the 304 Concretion Facility
- f. Spent coolant from counterbore lathes in the 333 Building
- g. Waste oil and hydraulic fluids that are known, or strongly suspected, to be contaminated with uranium
- h. Salt crystals (copper fluorozirconate) from the bottom of the waste storage tanks in the 334-A Building
- i. Acids (HNO₃, HF, and H₂SO₄ mixtures) as a solution and sorbed on opal clay.

There were no records of waste spills or leaks at the site.

Note: Waste materials began being generated in 1943 with the construction and startup of this facility.

Closure Info: Final: Physical closure activities for the 303-K CWS were completed July 2002. Closure Certifications were prepared in accordance with the Washington Administrative Code (WAC) 173-303-610 and the approved 303-K Storage Facility Closure Plan, DOE/RL-90-04, Rev. 2A as amended by the Hanford Facility RCRA Permit, Part V, Chapter 14. The certifications attest that 303-K Storage Facility closure activities are complete and were performed in accordance with the approved closure plan. A Professional Engineer certified completion of closure on August 15, 2002. After closure activities were achieved and verified, Ecology-approved clean closure criteria for soils and structures. Ecology formally acknowledged the closure certification for the 303-K Storage Facility by letter, DOE/RL 02-RCA-0424, dated August 5, 2002.

To complete the clean closure and in accordance with the closure plan, the entire 303-K Building was demolished. The rubble and excavated soil were designated and disposed of as low-level waste at the Hanford site Low Level Burial Grounds (LLBGs). After the site inspection, the soils were compacted and the site was backfilled with gravel.

The reclassification to Closed Out is documented on from 2003-031.

Code: 304 CF	Classification: Accepted
Names: 304 CF; 304 Concretion Facility	Reclassification: Closed Out (11/30/1995)
Type: Process Unit/Plant	Start Date: 1/1/1952
Status: Inactive	End Date: 1/1/1995
Description:	The RCRA waste treatment portion of the facility was Closed in 1995. The 304 building and its foundation were remediated in 2010 as a CERCLA remediation (see Sitecode 300-249).
Location:	The unit is located in the northwestern 300 Area on the south side of Ginko Street across from the 303-K, 314, and 313 Buildings.
Release Description:	During concretion operations, the 304 Facility floor was washed down daily with water. Because the steel walls of the main building were not sealed to the concrete wall base until 1989, and there were numerous small holes in the walls, rinse water splashing against the steel walls might have carried contamination out of the building. In addition, there were no berms at the north and south doors to stop washdown water from leaving the building. The north fenced pad does not have a berm to contain spills or precipitation. The north sliding door normally was left open to allow forklift traffic for container transport. A billet fire in 1977 may have contributed to the spread of contamination within the building. In August 1977, high

temperatures inside the 304 Facility (resulting from the failure of the cooling system) caused six concrete billets in 28.4 liter (7.5 gallon) containers to ignite. Uranium oxide and small amounts of zirconium oxide and copper oxide were formed by the burning billets. Cleanup water was drained through the drainage trenches into the process sewer. After the 1977 fire, concrete billets were cured initially in cold water cooling pans before being transported to the 303-K Facility where the final curing process took place.

Related Sites/ Structures: Units associated with this site include 300-249, the 304 Storage Area (304-SA), 300-249, the 300 Area Process Sewer, and internal process equipment.

Process Description: The 304 Concretion Facility consisted of a RCRA container storage area and a RCRA concretion system used to treat mixed waste and recyclable uranium scrap. The 304 Facility was in operation from 1952 to 1988. During this time, the following activities occurred:

- From 1952 to the late 1950's, the building was used as a pilot plant to fabricate aluminum-clad uranium cores by lead-dip canning process.
- From the late 1950's to the mid-1960 's, the building was used as a pilot plant to electroplate uranium with nickel.
- From the mid-1960's to 1971, the building was used to store engineering equipment and product chemicals.
- From 1971 to 1982 recyclable scrap uranium with zircaloy-2 and copper-silicon alloy chips and fines were concreted into billets. Beginning In 1977, the billets were cured in both the 304 Facility and 303-K Radioactive Mixed Waste Storage Facility (303-K Facility) before being shipped to Fernald, Ohio, for uranium recovery.
- From 1972 until 1986, beryllium/zircaloy-2 alloy and zircaloy-2 chips and fines were concreted in containers to reduce their ignitability. These containers were buried in the 200 Areas burial grounds.
- From 1975 to the spring of 1988, depleted uranium alloy chips and fines from Pacific Northwest Laboratory (PNL) were concreted into billets and returned to PNL for subsequent shipment to the 200 Areas burial grounds.
- In the spring of 1994, pyrophoric metal waste from dismantling of the 300 Area fuel processing equipment was concreted in drums to reduce ignitability. These drums were buried in a 200 Area burial ground. This is the final treatment activity planned for the 304 Facility.

Waste treated in the 304 Facility was generated by processes in the 300 Area. The waste sources are summarized as follows:

- Beryllium/zircaloy-2 alloy and zircaloy-2 chips and fines that were stored temporarily at the 303-K Facility were concreted into containers to reduce their ignitability.
- From 1985, spent counterbore lathe coolant (an aqueous synthetic lubricant) from lathes in the 333 Building was stored at the 303-K Facility until it could be used as makeup water in the 304 Facility cement mixer during concretion of chips and fines. The coolant was a nonregulated material. The spent counterbore lathe coolant used for makeup water for concretion in the 304 Facility was Polar chip 350L, which was diluted with water 20 to 1. Besides uranium, copper-silicon alloy, zircaloy-2 alloy, and graphite particulate, the only other potential contaminant in the lathe coolant was AW Hydraulic Oil 32, used in the counterbore lathe.

During concretion operations, the 304 Facility floor was washed down daily with water. Because the steel walls of the main building were not sealed to the concrete wall base until 1989 and there were numerous small holes in the walls, rinse water splashing against the steel walls might have carried contamination out of the building. In addition, there were no berms at the north and south doors to stop washdown water from leaving the building. The north fenced pad does not have a berm to contain spills or precipitation. The washing down of the floor is unlikely to have caused airborne contamination, because damp uranium saw fines and chips are too large and dense for easy air suspension. Uranium has a specific gravity of 18.9 and uranium oxides have a specific gravity of 7.3 to 10.9. Damp saw fines have a tendency to stick together

and about 73 percent of new saw fines are greater than 100 mesh (150 microns). In addition, the cyclone precipitator was in operation at all times when the cement bags were emptied and the concrete mixer was in operation.

During concretion operations, the north sliding door normally was left open to allow forklift traffic for container transport.

A floor drain near the cement mixer discharged to the sump where fines settled out. The sump has a removable screened standpipe about 40.6 centimeters (16 inches) high that overflowed into an underground drain line to the process sewer on the east side of the building. A water line discharged directly into the overflow pipe below the screen and was used in the concretion process. This flowing water (flow rate unknown) helped prevent the P-trap from plugging with concrete, which happened at least twice during the operation of the 304 Facility. No radiation detectors were in the process sewer and no routine sampling of the process sewer from the 304 Building occurred. Sampling was done at the outflow from the combined 300 Area process sewer system.

Once a year during the recyclable uranium concretion operation (1971 to 1982), a 3-day sample of the overflow pipe in the sump was taken to calculate a loss factor to the sewer for uranium chips and fines. The highly variable flow rate was calculated by adding a known dilute concentration of lithium nitrate (0.2 pound per gallon) at a known flow rate to the sump for a known sampling time. The change in lithium concentration and time would give the total volume of solution discharged from the sump.

Until March 1975, all waste liquid chemicals in the fuels operation were discharged to the process sewer. Therefore, during the nickel-plating pilot plant operation (late 1950's to mid-1960's), waste chemicals from this operation in the 304 Facility would have entered the process sewer. Routine discharges of chemicals to the process sewer were terminated after March 1975.

During concretion operations, the water that covered the uranium chips and fines, and 5 percent beryllium/zircaloy-2 chips in the incoming drums, were drained into the process sewer after passing through the sump to settle out entrained solids. The water covering the chips and fines would have contained an unknown amount of cutting fluid from the lathe operations. Four different types of cutting fluids were used.

In the summer of 1988, spent halogenated solvents consisting of perchloroethylene, 1,1,1-trichloroethane, and rinse water used in degreasing tanks in the fuels manufacturing process were stored at the 303-K and then moved to the 304 Facility for repackaging. Included in this repackaging effort was waste from the 300 Area paint and sign shop. Repackaging was accomplished by placement into new containers along with absorbent material. The containers were returned to the 303-K Facility. Handling and storage time for these spent solvents at the 304 Facility was less than 90 days. Ethyl acetate-bromine solutions generated from laboratory analysis work for uranium were occasionally mixed with the degreaser solvents. No spills were reported during this operation.

It is recognized that several factors associated with operations may have resulted in contamination of the 304 Facility. These factors include use of the building to house pilot plants, concretion operations, the occurrence of a billet fire in 1977, repackaging of spent solvents and ethyl acetate-bromine solutions, and storage of spent counterbore lathe coolant inside the building and on the outside storage pad.

One final concretion was run at the 304 Facility during the mid-1990's. This concretion run was used to treat and stabilize pyrophoric material generated during the final disassembly and removal of the fuels processing equipment. Prior to starting the final concretion run, all floor drains were to be plugged to prevent the entry of water. The concretion was done in the

disposal containers to eliminate the need to use the cement mixer.

Waste Type: Chemicals

Waste Description: Radiological contamination (derived from building concretion and plating activities) on surfaces and in building piping may still be present. Hazardous wastes were addressed in the facilities RCRA closure plan. The waste sources are described below. Beryllium/zircaloy-2 alloy and zircaloy-2 chips and fines that were stored temporarily at the 303-K Facility were concreted into containers to reduce their ignitability. From 1985, spent counterbore lathe coolant (an aqueous synthetic lubricant) from lathes in the 333 Building was stored at the 303-K Facility until it could be used as makeup water in the 304 Facility cement mixer during concretion of chips and fines. The coolant was a nonregulated material. The spent counterbore lathe coolant used for makeup water for concretion in the 304 Facility was Polar chip 350L, which was diluted with water 20 to 1. Besides uranium, copper-silicon alloy, zircaloy-2 alloy, and graphite particulates, the only potential contaminant in the lathe coolant was AW Hydraulic Oil 32, used in the counterbore lathe. Once a year during the recyclable uranium concretion operation (1971 to 1982), a 3-day sample of the overflow pipe in the sump was taken to calculate a loss factor to the sewer for uranium chips and fines. The highly variable flow rate was calculated by adding a known dilute concentration of lithium nitrate 0.34 kilograms per liter (0.2 pounds per gallon) at a known flow rate to the sump for a known sampling time. The change in lithium concentration and time would give the total volume of solution discharged from the sump. No routine sampling of the process sewer from the 304 Building occurred. Until March 1975, all waste liquid chemicals in the fuels operation were discharged to the process sewer. Therefore, during the nickel-plating pilot plant operation (late 1950's to mid-1960's), waste chemicals from this operation in the 304 Facility would have entered the process sewer.

During concretion operations, the water that covered the uranium chips and fines, and 5 percent beryllium/zircaloy-2 chips in the incoming drums, were drained into the process sewer after passing through the sump to settle out entrained solids. The water covering the chips and fines would have contained an unknown amount of cutting fluid from the lathe operations. Four different cutting fluids were used. In the summer of 1988, spent halogenated solvents consisting of perchloroethylene, 1,1,1-trichloroethane, and rinse water used in degreasing tanks in the fuels manufacturing process were stored at the 303-K Facility and then moved to the 304 Facility for repackaging. Occasionally, Ethyl acetate-bromine solutions generated from laboratory analysis work for uranium was mixed with degreaser solvents.

The maximum estimated inventory of containerized waste stored at the 304 Facility at any time was 40 containers. This total includes container sizes (not including overpacks) of 55, 30, and 7.5 gallons. Some of these containers contained labpacks, some were partially filled, and some were full. Up to 10 208 liter (55 gallon) containers could be concreted each day. An average of 9071.8 kilograms (20,000 pounds) of dangerous waste was concreted each year. The maximum amount stored inside was 2082 liters (550 gallons).

Closure Info: Final: The Reclassification to Closed Out for the 304 CF TSD unit is documented on Reclassification form 99-094. The Reclassification to Closed Out for the 304 SA TSD unit is documented on Reclassification form 2000-01. Regulator concurrence with supporting documentation eliminated the need for signatures on these forms. The 304 building and its foundation were remediated in 2010 as a CERCLA remediation (see Sitecode 300-249).

The cleanup and closure strategy for the site was to decontaminate the interior of the 304 Building to remove known or suspected contamination, then to sample for the constituents of concern, and then to perform data analysis, with an evaluation to determine the required actions to meet closure criteria. Criteria for the 304 Concretion Facility was that the concentrations of potentially dangerous constituents treated, stored, or used not be present above the regulatory cleanup levels. If the potentially dangerous constituents are above action levels, then the

evaluation was to determine the actions required. The evaluations could consider the type and extent to which the action levels were exceeded, and an assessment of health based risks. Generally, if the decontamination for dangerous constituents was not effective, the appropriate building section, floor, or pad was to be removed and properly disposed of as mixed waste. The radiological contamination at the 304 Concretion Facility was not addressed by the closure plan.

Phase I Decontamination was to vacuum to remove any loose contamination. Areas excluded from decontamination were the change room interior, all exterior surfaces of the 304 Building, and the exterior concrete and asphalt pads. All areas within the facility were vacuumed. No unusual incidents occurred.

Phase II decontamination was to damp wipe decontamination with a detergent solution to remove surface contamination. There were two areas that could not be decontaminated successfully, the sump and the trench. In both areas, the concrete on the sides and floor crumbled as it was wiped. The crumbling of the concrete prevented effective decontamination. There were approximately 75 millimeters (3 inches) of cement dust, sand, and chunks of semi-consolidated cement. The source of the sump material was the past concretion operations that used water to wash metallic fines and lose cement powder into the sump where the fines settled out. Both areas contained sampling points that were used to determine if any of the constituents of concern were present.

The facility connection to the Process Sewer is not part of the TSD (per the Closure plan).

Under Section 8.2 Post Closure Care of the 304 Concretion Facility Closure Plan (DOE/RL-90-03), the document states that the underlying soils and groundwater might have been contaminated by waste generated during past practice operations in the 300 Area. All soil remediation will take place under the CERCLA remedial action process (WIDS Sites 300-43 and 300-249). If the soil within the 304 Facility boundary is found to be contaminated from operations conducted in the 304 Facility, the 304 Facility will not be considered Closed until the remediation under CERCLA is complete.

Code:	304 SA	Classification:	Accepted
Names:	304 SA; 304 Storage Area; 304 Building Storage Area	Reclassification	Closed Out (11/30/1995)
Type:	Storage	Start Date:	1/1/1972
Status:	Inactive	End Date:	1/1/1986
Description:	The 304 building and its foundation were remediated in 2010 as a CERCLA remediation (see Sitecode 300-249). The RCRA storage area portion of the facility was Closed Out in 1995.		
Location:	The unit is located in the northwestern 300 Area on the south side of Ginko Street across from the 303-K, 314, and 313 Buildings. The storage area is located on the north side of the 304 Building.		
Related Sites/ Structures:	The unit is associated with the 304 Concretion Facility (WIDS Site 304 CF, 300-43 and 300-249).		
Process Description:	The storage area was used to store potentially contaminated wastes generated in the fuel fabrication process.		
Waste Type:	Barrels/Drums/Buckets/Cans		
Waste Description:	No wastes are currently stored at the site. The area was previously used to store containers of potentially contaminated waste generated in the fuel fabrication process. The site was RCRA		

clean closed in 1995. Radiological contamination may be present on pad surfaces and in the surrounding soil.

Closure Info: Final: The Reclassification to Closed Out for the 304 CF TSD unit is documented on Reclassification form 99-094. The Reclassification to Closed Out for the 304 SA TSD unit is documented on Reclassification form 2000-01. Regulator concurrence with supporting documentation eliminated the need for signatures on these forms. The 304 building and its foundation were remediated in 2010 as a CERCLA remediation (see Sitecode 300-249).

The cleanup and closure strategy for the site was to decontaminate the interior of the 304 Building to remove known or suspected contamination, then to sample for the constituents of concern, and then to perform data analysis, with an evaluation to determine the required actions to meet closure criteria. Criteria for the 304 Concretion Facility was that the concentrations of potentially dangerous constituents treated, stored, or used not be present above the regulatory cleanup levels. If the potentially dangerous constituents are above action levels, then the evaluation was to determine the actions required. The evaluations could consider the type and extent to which the action levels were exceeded, and an assessment of health based risks. Generally, if the decontamination for dangerous constituents was not effective, the appropriate building section, floor, or pad was to be removed and properly disposed of as mixed waste. The radiological contamination at the 304 Concretion Facility was not addressed by the closure plan.

Phase I Decontamination was to vacuum to remove any loose contamination. Areas excluded from decontamination were the change room interior, all exterior surfaces of the 304 Building, and the exterior concrete and asphalt pads. All areas within the facility were vacuumed. No unusual incidents occurred.

Phase II decontamination was to damp wipe decontamination with a detergent solution to remove surface contamination. There were two areas that could not be decontaminated successfully, the sump and the trench. In both areas, the concrete on the sides and floor crumbled as it was wiped. The crumbling of the concrete prevented effective decontamination. There were approximately 75 millimeters (3 inches) of cement dust, sand, and chunks of semi-consolidated cement. The source of the sump material was the past concretion operations that used water to wash metallic fines and lose cement powder into the sump where the fines settled out. Both areas contained sampling points that were used to determine if any of the constituents of concern were present.

The facility connection to the Process Sewer is not part of the TSD (per the Closure plan).

Under Section 8.2 Post Closure Care of the 304 Concretion Facility Closure Plan (DOE/RL-90-03), the document states that the underlying soils and groundwater might have been contaminated by waste generated during past practice operations in the 300 Area. All soil remediation will take place under the CERCLA remedial action process (WIDS Sites 300-43 and 300-249). If the soil within the 304 Facility boundary is found to be contaminated from operations conducted in the 304 Facility, the 304 Facility will not be considered Closed until the remediation under CERCLA is complete.

Code: 305-B SF	Classification: Accepted
Names: 305-B SF; 305-B Storage Facility	Reclassification: Closed Out (7/8/2013)
Type: Storage	Start Date: 1/1/1978
Status: Inactive	End Date:

Description: The 305-B facility was used to store, segregate, repackage, and sample hazardous and radioactive mixed waste. The 305-B building was demolished in December 2006. The RCRA

TSD permit was Closed in July 2007.

Location: The 305-B building is located in the northwest corner of the 300 Area, on Alaska Street, south of the 305 Building and north of 314. The storage areas were located in the basement and in the high bay area if the building.

Related Sites/ Structures: The building is associated with waste generated from Research and Development operations (Pacific Northwest National Laboratory) PNNL in the 300 Area.

Process Description: The 305-B facility was used to store, segregate, repackage, and sample hazardous and radioactive mixed waste generated by Pacific Northwest National Laboratory (PNNL) Research Laboratories in the 300 Area. Upon receipt at the 305-B Storage Facility, waste was placed in proper storage areas, depending on waste type and quantity. Dangerous waste was stored on the first floor, in the high bay area. Four storage cells were constructed in the high bay to segregate incompatible waste (Acids and Oxidizers, Poisons and CRV's, Caustics and WSDW and Organics). Non-flammable Radioactive Mixed Waste was stored in the basement of the original building. The area is capable of segregating wastes in four 7.6 meter by 7.6 meter (5 foot by 5 foot) stainless steel container pans. Flammable radioactive mixed waste could not be stored in the basement. Flammable material was stored in the east portion of the building in a 2.1 by 2.1 by 2.1 meter (7 foot by 7 foot by 7 foot) flammable liquid storage module. When a sufficient amount of waste has been accumulated, waste is transported to a permitted offsite treatment/disposal facility.

Prior to use as a treatment storage and disposal facility, the unit housed two test reactors that operated from the mid 1950's until 1978.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: The site is currently used to store hazardous and mixed waste.

Waste Type: Chemicals

Waste Description: Chemical and radiological contamination may be present in and around the facility, due to the operation of the Physical Constants Test Reactor and the Thermal Test Reactor that operated in the building prior to 1978. In 1978 the building became a waste assembly area/satellite storage area for the 300 Area Research and Development facilities in the 300 Area. Hazardous and radioactive waste has been stored, repackaged and/or consolidated (mostly in 55 gallon drums) in the 305-B building high bay and basement. The designed storage capacity is 30,000 gallons.

Closure Info: Final: In March 2006, Pacific Northwest Nation Laboratory completed transferring all the waste stored at the 305-B Storage Facility to an offsite TSD facility and to the 331-C storage Unit. The 305-B facility was transferred to the Washington Closure Hanford contractor in June 2006 for Closure and demolition.

The 305-B building was demolished in December 2006.

The Reclassification to Closed for the RCRA TSD is documented on form 2008-051.

Code: 307 RB

Classification: Accepted

Names: 307 RB; 307 Retention Basins

Reclassification Rejected (8/13/2013)

Type: Retention Basin

Start Date: 1/1/1953

Status: Inactive

End Date: 12/1/2011

Description: The 307 Retention Basins were deactivated in December 2011 and were demolished in June 2012. The basin is considered a component of the facility and the reclassification was changed

to Rejected in 2013. The structure consisted of four open, epoxy-coated, concrete basins. Each basin had a 94,500 liter (25,000 gallon) capacity. The Retention Process Sewer (RPS) tied into the basins on the north side, passing through a sample pit northwest of retention basin #1. The 300 Area Process Sewer and the Radioactive Liquid Waste Sewer (RLWS) drained from the south side of the basins.

Location: The 307 Retention Basins were located directly south of the 340 Building and the 340 Vault. The basins were part of the 340 Complex, inside the 340 Complex fence.

Related Sites/ Structures: The 307 basins are associated with UPR-300-1, the 300 Area Process Sewer (WIDS Site 300-15), the Retention Process Sewer (RPS) (WIDS Site 300-214), the Radioactive Liquid Waste Sewer (RLWS) (WIDS Site 300 RLWS), Retired Radioactive Liquid Waste Sewer (RRLWS) (WIDS Site 300 RRLWS), and the 340 Complex (WIDS Site 340 Complex) are all associated with the 307 Retention Basin operations. Generating facilities tied into the RPS include the 324, 325, 326, 327, and 329 Buildings. The 308 Building was isolated from the system in 1996. The 325 Building will be the last facility to be isolated from the RPS.

Process Description: The retention basins were fed by the Retention Process Sewer (RPS) and discharged to the 300 Area Process Sewer. The facilities tied into the RPS, except for the 308 building, were equipped with in-line beta-gamma detectors at diverter stations in the basement of each building. The 308 Building did not have in-line detectors. In 1996, the diverter station in the 326 building was upgraded and took over for both the 326 and 329 buildings. In the event that a detector alarm tripped, all the RPS waste was routed to the Radioactive Liquid Waste Sewer (RLWS) by valves at the diverter station. Waste in the retention basin was then sampled. In the event that sampling detected basin waste above discharge limits, the valves at the retention basins enabled operations personnel to route basin effluent to the RLWS.

After 1995, the retention waste below discharge limits was routed to the 300 Area Treated Effluent Disposal Facility (310 TEDF). From 1975 to 1994, the retention basin discharged to the 316-5 Process Trenches. From 1963 to 1975, it discharged to the process ponds (WIDS Sites 316-1 and 316-2). From 1953 to 1963, retention waste below discharge levels was discharged to the 307 Trenches (316-3).

With the retirement of the RLWS in 1998, waste above the discharge limits is held in the retention basins until it could be transported to the 200 Area double-shell tanks. Prior to 1998, waste above the discharge criteria was discharged to the RLWS and 340 Vault tanks. The waste sent to the 340 Vault tanks was transported by tanker truck or rail to the 200 Area for storage or disposal.

Waste Type: Process Effluent

Waste Description: The Retention Process Sewer line and the 307 Retention Basin systems (the 3707-F control shack, the RPS sample pit, 307 Trench and RLWS diversion control, and other ancillary equipment) were installed to collect "potentially" contaminated liquids from the sinks, drains and sumps of the laboratory facilities. During FY98, 12 million liters (3 million gallons) of liquid was received by the retention basins; none was diverted to the Radioactive Liquid Waste Sewer (RLWS). Liquid effluents that meet process sewer discharge criteria are released to the process sewer. Waste that exceeds discharge limits is held until it can be transported to the 200 Area double-shell tanks. Prior to October 1, 1998, waste above discharge limits was diverted to the 340 facility holding tanks.

Code: 309-TW-1

Classification: Accepted

Names: 309-TW-1; 309 Holdup Tanks; 309-TW Tank #1

Reclassification: Rejected (8/13/2013)

Type: Storage Tank

Start Date: 1/1/1960

Status: Inactive **End Date:** 1/1/1973

Description: Tank 309-TW-1 is the northernmost tank in the 309 Holdup Tank System. It is considered a component of the 309 facility and was reclassified to Rejected in 2013. All three tanks are located in a rectangular, underground concrete vault. A chain-link fence surrounds the site. Pumps, vents, piping, a valve box and the top of the concrete vault are visible above grade. The tanks are empty and the line to the sewer is capped. Residual contamination is present in the tanks and piping.

Location: The tank is located at the north end of a concrete vault northeast of the 309 Building.

Related Sites/ Structures: Structures associated with the tank include the other two holdup tanks, the adjacent valve box, the 309 Building, and the 300 Area radioactive liquid waste sewer. WIDS Site 300-255 (309 Tank Farm Contaminated Soil) addresses the contaminated soil inside the 309 Tank Farm fence.

Process Description: Contaminated liquid waste from the operation of the reactor was pumped to the holdup tanks prior to discharge to the radioactive liquid waste sewer. Contaminated effluent from the 309 Building facility was designed to be directed to the PRTR transfer waste tank farm (also known as TW Tank or Holdup Tank). It was located to the northeast of the 309 Building reactor containment vessel. The tank farm consisted of three underground tanks on a buried concrete pad, an adjacent concrete valve pit, and underground piping. The tanks are commonly known as TW-1, TW-2, and TW-3. During the late 1970's the radioactive liquid waste sewer connections were plugged and the power supply to the holdup tanks was cut.

Waste Type: Process Effluent

Waste Description: The unit received aqueous nonhazardous radioactive wastes from the operation of the Plutonium Recycle Test Reactor. Residual contamination may be present in the empty tanks.

Code: 309-TW-2 **Classification:** Accepted
Names: 309-TW-2; 309 Holdup Tanks; 309-TW Tank #2 **Reclassification:** Rejected (8/13/2013)
Type: Storage Tank **Start Date:** 1/1/1960
Status: Inactive **End Date:** 1/1/1973

Description: Tank 309-TW-2 is the center tank in the 309 Holdup Tank System. It is considered a component of the 309 facility and was reclassified to Rejected in 2013. All three tanks are located in a rectangular, underground concrete vault. A chain-link fence surrounds the vault. Pumps, vents, piping, a valve box and the top of the concrete vault are visible above grade.

The tanks are empty and the line to the sewer is capped. Residual contamination is present in the tanks and piping.

Location: The tank is located at the center of a concrete vault on the north east side of the 309 Building.

Related Sites/ Structures: Structures associated with the tank include the other to holdup tanks, the adjacent valve box, the 309 Building, and the 300 Area radioactive liquid waste sewer. WIDS Site 300-255 (309 Tank Farm Contaminated Soil) addresses the contaminated soil inside the 309 Tank Farm fence.

Process Description: Contaminated liquid waste from the operation of the reactor was pumped to the holdup tanks prior to discharge to the radioactive liquid waste sewer. During the late 1970's the radioactive liquid waste sewer connections were plugged and the power supply to the holdup tanks was cut.

Waste Type: Process Effluent

Waste Description: The unit received aqueous nonhazardous radioactive wastes from the operation of the Plutonium Recycle Test Reactor. Residual contamination may be present in the tanks.

Code: 309-TW-3 **Classification:** Accepted

Names: 309-TW-3; 309 Holdup Tank; 309-TW Tank #3 **Reclassification** Rejected (8/13/2013)

Type: Storage Tank **Start Date:** 1/1/1960

Status: Inactive **End Date:** 1/1/1973

Description: Tank 309-TW-3 is the southernmost tank in the 309 Holdup Tank System. It is considered a component of the 309 facility and was reclassified to Rejected in 2013. All three tanks rest in a rectangular, underground concrete vault. A chain-link fence surrounds the vaults. Pipes and risers are visible above grade. The tanks are empty and the line to the sewer is capped. Residual contamination is present in the tanks and piping.

Location: The tank is located at the south end of a concrete vault on the northeast side of the 309 Building.

Related Sites/ Structures: Structures associated with the tank include the other two holdup tanks, the adjacent valve box, 309 Building, and the 300 Area radioactive liquid waste sewer. WIDS Site 300-255 (309 Tank Farm Contaminated Soil) addresses the contaminated soil inside the 309 Tank Farm fence.

Process Description: Contaminated liquid waste from the operation of the reactor was pumped to the holdup tanks prior to discharge to the radioactive liquid waste sewer. During the late 1970's the radioactive liquid waste sewer connections were plugged and the power supply to the holdup tanks was cut.

Waste Type: Process Effluent

Waste Description: The unit received aqueous nonhazardous radioactive wastes from the operation of the Plutonium Recycle Test Reactor. Residual contamination may be present in the tank.

Code: 309-WS-1 **Classification:** Accepted

Names: 309-WS-1; PRTR Ion Exchange Vault; Reactor Ion Exchange Pit; 309 Plutonium Recycle Test Reactor Ion Exchanger Vault **Reclassification** Rejected (8/13/2013)

Type: Process Unit/Plant **Start Date:** 1/1/1961

Status: Inactive **End Date:** 1/1/1969

Description: The 309-WS-1 Vault is a below grade, reinforced concrete structure containing two levels. It is considered a component of the 309 facility and was reclassified to Rejected in 2013. The vault has connecting piping to the dome. The upper (main vault) level housed the ion exchangers (IX) used for moderator cleaning, while the lower (resin disposal) level was used to store spent columns. The lower vault has been cleaned of debris, decontaminated and coated with a fixative paint. The upper vault was cleaned of debris and swept clean. Access to the upper vault is through shielding blocks and access to the lower vault is through two concrete plugs.

Location: The unit is located on the northeast side of the 309 Building containment dome.

Related Sites/ Structures: The 309 Plutonium Recycle Test Reactor (PRTR) Building is the only structure associated with the vault.

Process Description: Prior to deactivation, the unit was used to remove contaminants from the heavy water and shield cooling systems.

Waste Type: Chemicals

Waste Description: Following deactivation activities, residual radiological contamination and chemical contamination from the ion exchange resin may be present on surfaces in the vault. Contaminants of concern are cesium-137 and strontium-90. The rainwater (in the lower vault)

and ion exchange columns were removed in 1995.

Code: 309-WS-2 **Classification:** Accepted

Names: 309-WS-2; Ion Exchange Vault; PRTR Rupture Loop; RLAIIX; Rupture Loop Annex Ion Exchange Loop Vault; Rupture Loop Ion Exchange Pit **Reclassification** Rejected (8/13/2013)

Type: Process Unit/Plant **Start Date:** 1/1/1960

Status: Inactive **End Date:** 1/1/1969

Description: The 309-WS-2 Ion Exchange Vault (RLAIIX) is an underground, reinforced concrete structure. It is considered a component of the 309 facility and was reclassified to Rejected in 2013. The unit is divided into five stalls. Four stalls held horizontally configured ion exchange columns, while the fifth stall is covered by a steel plate. A drain in the fifth bay discharged to a sump in Room 20 of the 309 Building. A rain cover has been installed over the top of the vault to prevent water from entering the vault.

Location: The unit is located off of the northwest side of the 309 Containment Dome.

Related Sites/Structures: The Fuel Element Rupture Test Facility, the Rupture Loop Annex (also known as Room 20), and the 309 Plutonium Recycle Test Reactor Building are associated with the unit.

Process Description: The ion exchange columns were used to remove contaminants and fission fragments from the light water coolant.

Waste Type: Equipment

Waste Description: Stabilized radiological contamination is present on vault surfaces. Contaminants of concern are transuranics, cesium-137 and cobalt-60. Prior to stabilization, survey reports indicate radiological contamination levels were as high as 70,000 disintegrations per minute per square centimeter beta-gamma and 28,000 disintegrations per minute per square centimeter alpha and with contact dose rates up to 2.5 rem per hour. After cleanout and stabilization, contamination levels were less than 1,000 disintegrations per minute per square centimeter beta-gamma, less than background (3 counts per minute) alpha, and a dose rate of less than 0.5 millirem per hour.

Code: 309-WS-3 **Classification:** Accepted

Names: 309-WS-3; 309 Brine Tank **Reclassification** Rejected (8/13/2013)

Type: Storage Tank **Start Date:** 1/1/1960

Status: Inactive **End Date:** 1/1/1969

Description: The unit has been backfilled, and grass has been planted above the tank. The Brine Tank is a below grade, rectangular concrete structure with two chambers. It is considered a component of the 309 facility and was reclassified to Rejected in 2013. Access/loading ports were installed on the top of the tank. Inside the tank, four perforated transite pipes ran the length of the main chamber. The pipes were suspended in a gravel filter bed and covered by a layer of sand. The second chamber acted as a holding tank.

Location: The unit is located below grade, off the southwest corner of the 309 Building.

Related Sites/Structures: Structures associated with this unit include the brine tanks in the 309 Building basement, the reactor heat exchange systems, and the liquid transfer lines.

Process Description: The unit has been backfilled and is inactive. During use the container held salt that was slurried and pumped through plastic pipes to three brine tanks located in the basement of 309 Building. These tanks supplied process water used to cool several small heat exchangers for the reactor.

Waste Type: Chemicals

Waste Description: The unit stored brine salt to be used by the process water/brine tanks within the basement of the 309 Building.

Code: 311-TK-40

Classification: Accepted

Names: 311-TK-40; 311 Neutralized Waste Tank 1

Reclassification: Closed Out (7/8/2013)

Type: Storage Tank

Start Date: 1/1/1953

Status: Inactive

End Date:

Description: The RCRA TSD was Clean Closed as part of the 300 Area Waste Acid Treatment System (WATS) Partial Closure in December 2001. The 311-TK-40 tank was an isolated, stainless steel cylinder in the horizontal position. The tank was positioned within a concrete containment structure.

Location: The unit lies between the 303-F and 303-G Buildings.

Related Sites/ Structures: Structures associated with the tank include 311-TK-50, the 303-F Building, and the 300 Area WATS.

Process Description: The tank was part of the WATS from 1973 until 1985. It was used for storing neutralized waste prior to disposal. From 1953 to 1973, the system was used to store nitric acid.

Waste Type: Chemicals

Waste Description: The tank is empty and isolated. From 1953 to 1973 the tank held nitric acid. Since 1973 the system has been part of the 300 Area Waste Acid Treatment System. It held liquid mixed waste prior to disposal.

Closure Info: Final: The RCRA TSD has been Clean Closed. The site was covered under a RCRA Part A Permit Application, and a closure plan was filed with Ecology in 1990. A Decontamination and Decommissioning Plan was issued for Phase III closure of the 300 Area Waste Acid Treatment System which includes this tank. Tank 311-TK-40 will remain in place after closure. It has been decontaminated in-place to a 'clean debris surface' standard. The stainless steel jacket and insulation have been removed to allow full inspection. The insulation was sampled based on visual observations (of worst case matrix). Residue samples were collected from the heel in tank TK-40. The sample was determined by TCLP to have less than the regulatory limit (per WAC 173-303-090, Toxicity Characteristic List) for all RCRA metals. A small quantity of liquid was collected from the recirculation line from the bottom of TK-40 to the 303-F Building (even though the tank was dry). The sample of the drained TK-40 liquid was found to be non-corrosive (pH 9.12), but was determined by ICP to contain greater than the regulatory limit for both chromium (8.53 micrograms per milliliter [ug/ml]) and silver (6.41 ug/ml) compared to a designation threshold of 5 ug/ml for each according to WAC 173-303-090, Toxicity Characteristics Limit.

The Reclassification is documented on form 2001-100.

Code: 311-TK-50

Classification: Accepted

Names: 311-TK-50; 311 Neutralization Tank #2; 311 Neutralized Waste Tank 2

Reclassification: Closed Out (7/8/2013)

Type:	Storage Tank	Start Date:	1/1/1985
Status:	Inactive	End Date:	
Description:	The tank was a RCRA TSD that was part of the 300 Area Waste Acid Treatment System (WATS) has been Closed Out. The 311-TK-50 tank was a 18,927 liter (5000 gallon) vertical stainless tank that has been drained, characterized, isolated.		
Location:	The unit is located within a concrete catch basin in the 311 Tank Farm between the 303-F and 303-G Buildings in the north central 300 Area.		
Related Sites/ Structures:	Structures associated with the tank include 311-TK-40, the 303-F Building, the Pipe Trench, the 300 Area Waste Acid Treatment System equipment in the Uranium Recovery Room of the 313 Building, and the 340 Facility.		
Process Description:	Tanks TK-40 and TK-50 were used to store neutralized acid waste from the 300 Area Waste Acid Treatment System (WATS). 311-TK-50 was installed in 1985.		
Waste Type:	Chemicals		
Waste Description:	The unit received waste solutions consisting of neutralized liquid from the nonrecoverable uranium stream and filtrate from processing of the uranium-bearing waste stream. The tank was used to decant liquid waste.		
Closure Info:	Final: The RCRA TSD was Clean Closed under the 300 Area WATS Partial Closure in 2001. It was covered under a RCRA Part A Permit Application. The closure plan was filed with Ecology in 1990. A Decontamination and Decommissioning Plan was issued for Phase III closure of the 300 Area Waste Acid Treatment System which includes this tank. Tank 311-TK-50 will remain in place after closure. It has been decontaminated in-place to a "clean debris surface" standard. The stainless steel jacket and insulation will be removed to allow full inspection. The insulation will be sampled based on visual observations (of worst case matrix). Residue samples from tank TK-50 along with samples of the liquid/sludge drained from the piping and the pumps and filters (which were located in the 303-F Building) were used to characterize the tank TK-50 subsystem. The liquids which contained 8% solids had a pH of 10.4. ICP lab results for both liquids and solids samples reported less the regulatory limit (see WAC 173-303-090, Toxicity Characteristic List) for all RCRA metals. Similarly, the sample of solids was determined by TCLP to have less than the regulatory limit for all RCRA metals. A dried sample of process residue from inside tank TK-50 was analyzed and shown to be non-corrosive, contained no beryllium and included less than the regulatory limit for RCRA metals. A sample of the filter element contained in the upstream in-line filter housing was removed and sent to the lab for analysis. This information will be used to determine disposal or applicable WATS Phase III waste. The constituents contained in the filter element are expected to have been indicative of the materials processed during the final WATS operations, which were all managed in tank TK-50. The sample of the filter element was determined by TCLP to have less than the regulatory limit for all RCRA metals, a pH of 7.42, no detectable beryllium and no detectable PCBs.		

Code:	313 CENTRIFUGE	Classification:	Accepted
Names:	313 CENTRIFUGE; 300 Area WATS; 313 Centrifuge	Reclassification	Closed Out (12/6/2001)
Type:	Process Unit/Plant	Start Date:	1/1/1985
Status:	Inactive	End Date:	1/1/1997
Description:	This site has been Clean Closed under the 300 Area Waste Acid Treatment System (WATS) Partial Closure. The centrifuge was removed in 1997 and disposed of as low level solid waste.		

The 300 Area Waste Acid Treatment System was closed in phases. It was totally closed on 10/30/2005.

Location: The centrifuge was located in the Uranium Recovery Room in the southern end of the 313 Building in the 300 Area.

Related Sites/ Structures: Structures associated with the unit include transfer lines, 313-TK-2, 313-TK-11, the 313 Filter Press, and the other portions of the waste acid treatment system.

Process Description: The centrifuge was installed in 1985 to reduce the solids content of the final neutralized waste prior to trucking out to the 200 Areas for disposal. Neutralized acid waste was pumped from 313-TK-2 through the centrifuge to 313-TK-11 and then via piping in the pipe trench to the waste storage tanks 311-TK-40 and 311-TK-50 in the 311 Tank Farm. The centrifuge solids were drummed and sent to 303-K for storage prior to burial as low-level solid waste. As needed, the stored waste solutions in Tanks 40 and 50 were recycled through in-line filters in the 303-F Building and back via the pipe trench to the Uranium Recovery Room in the 313 Building for additional solids removal. The 313 Centrifuge and the 313 Filter Press were both used during such recycle activities.

Waste Type: Chemicals

Waste Description: The centrifuge treated neutralized nonrecoverable uranium bearing waste slurry by separating the solid and liquid phases.

Closure Info: Final: The waste site RCRA permit has been Clean Closed. The Centrifuge was removed in 1997 in accordance with the Decontamination and Inspection Plan for Phase 1 Closure of the 300 Area Waste Acid Treatment System. Ecology completed an inspection of the site in October 1997 and agreed that removal was done in accordance with this plan.

The reclassification is documented on form 2001-102.

Code: 313 CRO	Classification: Not Accepted
Names: 313 CRO; 313 Building Copper Remelt Operations; 313 Copper Remelt Operations	Reclassification: None
Type: Process Unit/Plant	Start Date: 1/1/1973
Status: Inactive	End Date: 1/1/1988

Description: The 313 Copper Remelting Operation was performed in the southern end of the 313 Building. The 313 Building is a large structure resting on a reinforced concrete slab floor. The walls are concrete block and structural steel framing. The roof is a precast concrete slab covered in tar and gravel. Interior walls are concrete block or concrete brick.

Location: The unit is located in the original (southern) portion of the 313 Building.

Related Sites/ Structures: Structures associated with the unit include furnaces, casting equipment, and machine equipment used in the copper remelting operations.

Process Description: Copper-silicon alloy scrap materials from the fuel fabrication process were collected, melted, cast, and machined for reuse in the N Reactor Fuel Fabrication operations.

Waste Type: Chemicals

Waste Description: Copper-silicon alloy scrap materials from the fuel fabrication process were melted, cast, and machined in preparation for recycling. The unit processed 600 pounds (270 kilograms) per day when in operation.

Code:	313 FP	Classification:	Accepted
Names:	313 FP; 300 Area Waste Acid Treatment System; 313 Filter Press	Reclassification	Closed Out (12/6/2001)
Type:	Process Unit/Plant	Start Date:	1/1/1944
Status:	Inactive	End Date:	1/1/1997
Description:	This site has been Clean Closed under the RCRA TSD 300 Area Waste Acid Treatment System. The 313 Filter Press was removed in 1997 and buried as low level solid waste. The 300 Area Waste Acid Treatment System was closed in phases. It was totally closed on 10/30/2005.		
Location:	The TSD unit was located in the Uranium Recovery Room inside southern portion of the 313 Building.		
Related Sites/ Structures:	Structures associated with the unit include the U-Bearing Acid storage tanks (TK 3 and TK4), the Caustic Feed Tanks (TK5 and TK6), the Neutralization and Precipitation Tank (TK7), the Filter Press Feed Tank (TK8), and the Filtrate Storage Tanks (TK 9 and TK-10) in the Uranium Recovery Room of the 313 Building, the neutralized liquid effluent storage and load-out tank (TK 40) in the 311 Tank Farm, and the 303-K Contaminated Waste Storage Facility. The 300 Area Waste Acid Treatment System Pipe Trench and the Process Sewer supported the operation of the 313 Filter Press. Contaminated soil under this facility is site UPR-300-38.		
Process Description:	The filter press was used to recover uranium from spent nitric acid etching solutions from the uranium fuels manufacturing operations in the 300 Area. The uranium-bearing nitric acid solutions were transferred to two 1700 liter storage tanks (TK-3 and TK-4) in the Uranium Recovery Room in the south end of the 313 Building. The uranium was precipitated during neutralization of the nitric waste acid with caustic in a 1400 liter Tank (TK-7) and then transferred to the filter feed tank (TK 8). The sodium diuranate slurry was pumped through the filter press to remove uranium solids. Prior to October 1972, the filtrate drained to the process sewer. After October 1972, the filtrate was stored in two 2120 liter tanks (TK 9 and TK 10) until pumped from the 313 Building to a 15,100 liter waste storage loadout tank (TK 40) in the 311 Tank Farm via piping in the pipe trench. The filter press was periodically opened to scrape the sodium diuranate solids from the canvas filter cloth on each filter press frame. The solids were put into 114 liter (30 gallon) drums and transferred to the 303-K Building (see 303-K CWSF) for storage pending shipment off-site for uranium recycle.		
Waste Type:	Chemicals		
Waste Description:	The unit treated recoverable and nonrecoverable uranium-bearing waste acid by separating solid and liquid phases. Residual radiological and chemical contamination may be present.		
Closure Info:	Final: This site has been Clean Closed under RCRA. The closure certifications include the Professional Engineer (PE) Partial Closure Certification (Dated June 7, 2001), the U.S. DOE Partial Closure Certification (Dated December 3, 2001), and Ecology's approval of the U.S. DOE's certification for partial clean closure of the 300 Area WATS (Dated December 6, 2001).		

The reclassification is documented on form 2001-103.

In December 1996, a Decontamination and Inspection Plan was issued for Phase 1 closure of the 300 Area Waste Acid Treatment System. The equipment in the Uranium Recovery Room in the 313 Building including the 313 Filter Press was removed and buried as low level solid waste in the 200 Area in 1997. During the Phase 1 work, the contaminated areas of the floors in the Uranium Recovery Room were cleaned by scabbling. A few small floor cracks, some exposed acid brick, and one construction joint connected to the soil beneath the facility were identified prior to performing the decontamination and inspection outlined in the plan for Phase 1 closure activities. Ecology completed an inspection of the cleaned site in October 1997 and agreed that removal was done in accordance with this plan. A RCRA closure plan was issued in

1990 for the 300 Area Waste Acid Treatment System which included the Uranium Recovery Operations in the 313 Building, with revisions in 1996 and 1999.

Code:	313 URO	Classification:	Accepted
Names:	313 URO; Uranium Recovery Operations; 313 Uranium Recovery Operations	Reclassification	Consolidated (8/15/2013)
Type:	Process Unit/Plant	Start Date:	1/1/1954
Status:	Inactive	End Date:	1/1/1997
Description:	The waste site was reclassified to Closed Out on form 99-016 in 1999. The reclassification status was changed to Consolidated with UPR-300-38 in 2013. In 1997, the 313 Uranium Recovery Operation process equipment and piping were removed and the concrete surfaces scabbled and decontaminated. Past practice sub-floor contamination remained to be addressed as well as the potential for some minor RCRA contributions to subfloor contamination. These will be addressed as part of UPR-300-38.		
Location:	The unit is located along the north wall of the Uranium Recovery Room in the south end of the 313 Building.		
Release Description:	See the WIDS site that describes the unplanned releases (WIDS Sitecode UPR-300-38) associated with this area. All of the RCRA/CERCLA releases identified for the soils in this area will be addressed as part of UPR-300-38. Also see WIDS Sitecode UPR-300-44, which involved a leak in a section of the process sewer line that was detected in January 1985. This leak in the process sewer line downstream from the 313 URO could have allowed uranium-bearing waste spills to have reached the ground beneath the process sewer. Also see WIDS Sitecode UPR-300-45, a waste transfer line leak to the pipe trench between the 313 URO and the 303-F Building. Because the pipe trench bottom has holes in it, this site leaked to the soil column.		
Related Sites/ Structures:	Past practice sub-floor contamination remains to be addressed as well as the potential for some minor RCRA contributions to subfloor contamination. These will be addressed as part of UPR-300-38. Facilities associated with the uranium recovery operation include two U-bearing Acid Waste storage tanks located outside the west wall of the 333 Building (flushed and disconnected), U-Bearing Waste Acid Storage tank (333-TK-24) inside the 333 Building (flushed and disconnected), the 311 Tank Farm (sodium hydroxide supply tank and the neutralized acid waste storage tanks TK-40 and TK-50, both flushed and disconnected), the 303-F Building (pumps, in-line filters. Piping removed), and the Pipe Trench that contains piping which connected the 313 URO to the other facilities and processes and to the Process Sewer. Tanks 313-TK-5 and 313-TK-6 contained sodium hydroxide used in the neutralization and precipitation process.		
Process Description:	The 313 Uranium Recovery Operations (URO) processed uranium-bearing acid wastes from the fuel fabrication processes to recover uranium for recycle. U-bearing acid wastes were received from the 313 Fuels Operations until 1971. From 1961 until shutdown in 1987, U-bearing waste acid solutions were transferred from tank TK-24 in the 333 Building to two outside storage tanks on the west side of the 333 Building. The U-bearing waste acid was pumped from the outside storage tanks via the pipe trench to the 313 Building tanks TK-3 and TK-4 in the Uranium Recovery Room. The uranium was recovered by precipitation and filtration. U-bearing acid waste was metered into TK-7 where sodium hydroxide (from Tanks 5 and 6) was added to neutralize the acid and precipitate uranium as sodium diuranate. The basic slurry was collected in tank TK-8 and pumped through a plate and frame filter (see 313 FP) to remove the uranium. The filtrate was collected in tanks TK-9 and TK-10 for storage and pumping to the 311 Tank Farm via the Pipe Trench. Periodically, the uranium solids were scraped off the removable canvas filter cloth into 30-gallon drums. The drums were taken to the 303-K Facility for storage pending off-site shipment for uranium recycle.		

Waste Type: Equipment

Waste Description: The equipment contained uranium-bearing acid wastes from fuel fabrication processes that were used to treat and recover uranium. All contaminated equipment was removed from the facility.

Closure Info: Final: Waste Site Reclassification Form 99-016 states that, in 1997, the 313 Uranium Recovery Operation process equipment and piping were removed and the concrete surfaces scabbled and decontaminated. Past practice sub-floor contamination remains to be addressed as well as the potential for some minor RCRA contributions to subfloor contamination. These will be addressed as part of UPR-300-38.

Tanks TK-5, TK-9, TK-10, and the filter press (WIDS Sitecode 313 FP) are shared equipment with the Waste Acid Treatment System (WATS). This equipment was removed under a Decontamination and Inspection Plan for Phase 1 WATS closure activities. Ecology inspected the 313 WATS area in October 1997 and concurred that the work was completed in accordance with the Phase 1 Plan. All other 313 URO equipment was also removed in 1997.

This Site Was Consolidated With:

Code: UPR-300-38

Names: UPR-300-38; 313 Slab; Demolished 313 Building Foundation; Soil Contamination Beneath the 313 Building

Code: 313-TK-2

Classification: Accepted

Names: 313-TK-2; 300 Area Waste Acid Treatment System; 313 Waste Acid Neutralization Tank

Reclassification: Closed Out (12/6/2001)

Type: Neutralization Tank

Start Date: 1/1/1975

Status: Inactive

End Date: 1/1/1997

Description: This site was Clean Closed under the 300 Area WATS partial closure in 2001. The 313-TK-2 Neutralization Tank was removed in 1997. The tank was part of the 300 Area Waste Acid Treatment System. The vertical, stainless steel, cylindrical tank was located within a bermed area with other uranium recovery and acid treatment equipment.

Location: The tank was installed inside a bermed area near the southwest interior corner of the 313 Building.

Related Sites/Structures: Structures associated with this site include 334-A Building Tank Farm, the 311 Tank Farm, Tanks 311-TK-40 and 311-TK-50, the 313 Uranium Recovery Room, the 313-Centrifuge, the 303-F Facility, and the Pipe Trench (300-224), all of which are components of the 300 Area Waste Acid Treatment System.

Process Description: From 1973 to 1988, Tank 313-TK-2 was used to neutralize chemical waste acid solutions with sodium hydroxide (caustic). The waste acid originated in zircaloy etching tanks in the 333 Building fuels fabrication process which was periodically batched out to spent acid storage tanks in the 334-A Facility. The waste acid was pumped through transfer lines (300-219) in the Pipe Trench (300-224) to Tank 313-TK-2 for neutralization. The neutralized etch waste in 313-TK-2 was pumped in piping via the Pipe Trench to Tank 311-TK-40 in the 311 Tank Farm.

Waste Type: Chemicals

Waste Description: The unit treated uranium-bearing acid waste by neutralization. Prior to removal of the tank, a precipitate cake was present in the bottom of the tank.

Closure Info: Final: Waste Site Reclassification form 2001-104 documents this site has been Clean Closed.

"Partial closure activities for the 300 Area Waste Acid Treatment System (300 Area WATS) are now complete. The attached certification statement was prepared in accordance with WAC 173-303-610 (6) to independently certify that the 300 Area WATS partial closure activities were performed in accordance with the approved 300 Area Waste Acid Treatment System Closure Plan (DOE/RL-90-11, Rev 2, dated May 1999). This closure plan is considered approved by the Washington State Department of Ecology through Ecology acceptance of the plan as complete in a letter dated July 27, 1999 and because the plan underwent public review without comment. ...Partial closure activities included the activities necessary to clean close all 300 Area WATS aboveground structures and components and most soils. Not all soil potentially contaminated by WATS operations could be clean closed at the time of partial closure." The December 3, 2001, DOE Partial Closure Certification noted that "The unclosed locations include two areas of potential soil contamination from 300 Area WATS operations that are defined in the closure plan. These areas will remain unclosed and RCRA regulated until soil disposition in conjunction with the future 300-FF-2 CERCLA OU remedial action that will complete 300 WATS closure."

A RCRA closure plan was issued in 1990 for the 300 Area Waste Acid Treatment System which included the Uranium Recovery Operations in the 313 Building. Revision 1 of the RCRA closure plan was submitted to Ecology in March 1996. Tank 313-TK-2 was removed in 1997 in accordance with the Decontamination and Inspection Plan for Phase 1 closure of the 300 Area Waste Acid Treatment System. Ecology inspected the cleanup site in October 1997 and concurred that the work was done in accordance with the D Phase 1 plan.

Code:	315 RSDF	Classification:	Accepted
Names:	315 RSDF; 315 Retired Sanitary Drain Field	Reclassification	Rejected (1/27/1999)
Type:	Drain/Tile Field	Start Date:	1/1/1950
Status:	Inactive	End Date:	1/1/1978
Description:	The 315 RSDF is an abandoned septic tank and drain field. The location shown by maps and drawings is not marked in the field. The site is covered with a surface of gravel and cobbles and no vegetation. There are manhole covers with protective posts located in close proximity to the abandoned septic tank/drain field.		
Location:	The site is located in the eastern portion of the 300 Area, northeast of the 315 Water Filter Plant.		
Related Sites/ Structures:	The site was associated with the 315 Water Filter Plant Sanitary Sewer.		
Process Description:	The 315 RSDF received sanitary waste that originated in the 315 Water Filter Plant.		
Waste Type:	Sanitary Sewage		
Waste Description:	The unit received unknown amounts of sanitary wastes from the 315 Water Filter Plant. The authors of the 300-FF-2 Operable Unit Technical Baseline Report speculated that water treatment chemicals may have been discharged to the site, but no supporting documentation for this has been found. According to Jim Day, Dyncorp Water Utilities and Support Services, the only chemicals used at the facility were alum (nonhazardous) and chlorine gas.		

Code:	323 TANK 1	Classification:	Accepted
Names:	323 TANK 1; 321 Building Underground Waste Tanks; 321 Tank Farm #3; 323 Tank 1	Reclassification	Rejected (7/15/2013)

Type: Storage Tank**Start Date:** 1/1/1944**Status:** Inactive**End Date:**

Description: The waste site was reclassified to Rejected. The four, underground 323 tanks have been removed. The underlying soils were addressed in the UPR-300-4 closure documentation. The tank was a carbon steel horizontal tank buried with three other identical tanks encased in a large block of concrete. The top of the concrete block was used as the floor for the installation of the 323 Building (lower level) in 1958.

Location: The site was located beneath the 323 Building, in the west central portion of the 300 Area.

Release Description: According to BHI-00012, contamination in the soil surrounding the four tanks is possible. According to WHC-MR-0388, the soil around and beneath the four tanks and the tanks themselves are very contaminated with mixed wastes. Analyses of liquid and sludge samples from Tank 4 in 1987 reported uranium and aluminum in significant quantities. These contaminants would have been introduced during the period the tanks were used to support the 321 Building chemical process development operations prior to 1967. The source of reports that thorium was associated with the waste in the underground waste tanks may have been with reference to the disposal of lab waste solutions from the 3706 Building. In 1944, the "hot" sinks in the 321 Building laboratories were connected to the underground tanks to eliminate sources of fission activity and product contamination of the 300 Area pond. At the same time, it was planned to dispose of active waste from the 3706 laboratories by collecting the wastes in individual containers and emptying them into the "hot" sinks in the 321 Building. Thorium was used during process development tests in the 3706 Building laboratories. According to operating personnel contacted, thorium was not used in the 321 Building process development tests.

Related Sites/ Structures: The tank is associated with three other identical tanks in the same concrete encasement, the 323 Building (formerly the 321-A Building), the 321 Building, and the 3706 Building labs by way of the hot sink drains in the 321 Building labs.

Process Description: The carbon steel tank received neutralized uranium-bearing process waste and/or basic aluminum cladding contaminated waste solutions from the 321 Building, primarily from cold and hot pilot tests for the bismuth phosphate chemical separations process from 1944 to about 1946. Some neutralized uranium-bearing waste solutions were received from the 321 Building Tank Farm during the pilot plant tests for the REDOX process. Lesser quantities of process wastes containing fission products, uranium, plutonium, and laboratory chemicals were routed to the tank from the "hot sinks" in the 321 Building laboratories from 1944 to about 1954 during the development of the Bismuth Phosphate, Redox, Uranium Metal Recovery, PUREX, RECUPLEX, and Thorex processes and from lab scale tests on medical isotope extraction processes. Beginning in late 1944, "hot" wastes from the 3706 Building laboratories were carried to the 321 Building for disposal via the "hot sinks" to prevent contamination of the 300 Area Ponds.

Waste Type: Process Effluent

Waste Description: The tank received neutralized uranium-contaminated water and/or basic aluminum cladding waste solutions from reprocessing research and development activities in the 321 Building and the 3706 Building (via the hot sink drains in the 321 Building laboratories), including those related to bismuth phosphate chemical separations, REDOX, Uranium Metal Recovery, PUREX, RECUPLEX, the Thorex program, and medical isotope extraction. The tank was emptied in 1952 or 1953.

Closure Info: Interim (7/15/2013): The above grade portions of the 323 building were demolished in 2008. Demolition of the below grade structures, including the 323 tanks (1 through 4), was deferred to the adjacent UPR-300-4 remediation. During the site characterization, the four tanks were found to be filled with water. After sampling the water, approximately 100,000 gallons of water was pumped out of the four tanks and taken to the 200 Area Effluent Treatment Facility.

The four 323 tanks and the underground piping connected to the 321 building was remediated in November 2012.

Code:	323 TANK 2	Classification:	Accepted
Names:	323 TANK 2; 321 Building Underground Waste Tanks; 321 Tank Farm #3; 323 Tank 2	Reclassification	Rejected (7/15/2013)
Type:	Storage Tank	Start Date:	1/1/1944
Status:	Inactive	End Date:	
Description:	The waste site was reclassified to Rejected. The four, underground 323 tanks have been removed. The underlying soils were addressed in the UPR-300-4 closure documentation. The tank was a carbon steel horizontal tank buried with three other identical tanks encased in a large block of concrete. The top of the concrete block was used as the floor for the installation of the 323 Building (lower level) in 1958.		
Location:	The site was located below the 323 Building, in the western portion of the 300 Area.		
Release Description:	According to BHI-00012, contamination in the soil surrounding the four tanks is possible. According to WHC-MR-0388, the soil around and beneath the four tanks and the tanks themselves are very contaminated with mixed wastes. The source of reports that thorium was associated with the waste in the underground waste tanks may have been with reference to the disposal of lab waste solutions from the 3706 Building. In 1944, the "hot" sinks in the 321 Building laboratories were connected to the underground tanks to eliminate sources of fission activity and product contamination of the 300 Area pond. At the same time, it was planned to dispose of active waste from the 3706 laboratories by collecting the wastes in individual containers and emptying them into the "hot" sinks in the 321 Building. Thorium was used during process development tests in the 3706 Building laboratories. According to operating personnel contacted, thorium was not used in the 321 Building process development tests.		
Related Sites/ Structures:	The tank is associated with the 323 Building, the 321 Building, and the 3706 Building by way of the 321 Building hot sink drains.		
Process Description:	The carbon steel tank received neutralized uranium-bearing process waste and/or basic aluminum cladding contaminated waste solutions from the 321 Building, primarily from pilot tests for the bismuth phosphate chemical separations process from 1944 to about 1946. Some neutralized uranium-bearing waste solutions were received from the 321 Building Tank Farm during the pilot plant tests for the REDOX process. Lesser quantities of process wastes containing fission products, uranium, plutonium, and laboratory chemicals were routed to the tank from the "hot sinks" in the 321 Building laboratories from 1944 to about 1954 during the development of the Bismuth Phosphate, Redox, Uranium Metal Recovery, PUREX, RECUPLEX, and Thorex processes and from lab scale tests on medical isotope extraction processes. Beginning in late 1944, "hot" wastes from the 3706 Building laboratories were carried to the 321 Building for disposal via the "hot sinks" to prevent contamination of the 300 Area Ponds.		
Waste Type:	Process Effluent		
Waste Description:	The tank received neutralized uranium-contaminated water and/or basic aluminum cladding waste solutions from reprocessing research and development activities in the 321 Building and the 3706 Building (via the hot sink drains in the 321 Building laboratories), including those related to bismuth phosphate chemical separations, REDOX, Uranium Metal Recovery, PUREX, RECUPLEX, the Thorex program, and medical isotope extraction. The tank was emptied in 1952 or 1953.		
Closure Info:	Interim (7/15/2013): The above grade portions of the 323 building were demolished in 2008.		

Demolition of the below grade structures, including the 323 tanks (1 through 4), was deferred to the adjacent UPR-300-4 remediation. During the site characterization, the four tanks were found to be filled with water. After sampling the water, approximately 100,000 gallons of water was pumped out of the four tanks and taken to the 200 Area Effluent Treatment Facility.

The four 323 tanks and the underground piping connected to the 321 building was remediated in November 2012.

Code:	323 TANK 3	Classification:	Accepted
Names:	323 TANK 3; 321 Building Underground Waste Tanks; 321 Tank Farm #3; 323 Tank 3	Reclassification	Rejected (7/15/2013)
Type:	Storage Tank	Start Date:	1/1/1944
Status:	Inactive	End Date:	
Description:	The waste site was reclassified to Rejected. The four, underground 323 tanks have been removed. The underlying soils were addressed in the UPR-300-4 closure documentation. The tank was a carbon steel horizontal tank buried with three other identical tanks encased in a large block of concrete. The top of the concrete block was used as the floor for the installation of the 323 Building (lower level) in 1958.		
Location:	The site was located beneath the 323 Building, in the western portion of the 300 Area.		
Release Description:	According to BHI-00012, contamination in the soil surrounding the four tanks is possible. According to WHC-MR-0388, the soil around and beneath the four tanks and the tanks themselves are very contaminated with mixed wastes. The source of reports that thorium was associated with the waste in the underground waste tanks may have been with reference to the disposal of lab waste solutions from the 3706 Building. In 1944, the "hot" sinks in the 321 Building laboratories were connected to the underground tanks to eliminate sources of fission activity and product contamination of the 300 Area pond. At the same time, it was planned to dispose of active waste from the 3706 laboratories by collecting the wastes in individual containers and emptying them into the "hot" sinks in the 321 Building. Thorium was used during process development tests in the 3706 Building laboratories. According to operating personnel contacted, thorium was not used in the 321 Building process development tests.		
Related Sites/Structures:	The tank is associated with the 323 Building, the 321 Building, and the 3706 Building by way of the 321 Building hot sink drains.		
Process Description:	The carbon steel tank received neutralized uranium-bearing process waste and/or basic aluminum cladding contaminated waste solutions from the 321 Building, primarily from pilot tests for the bismuth phosphate chemical separations process from 1944 to about 1946. Some neutralized uranium-bearing waste solutions were received from the 321 Building Tank Farm during the pilot plant tests for the REDOX process. Lesser quantities of process wastes containing fission products, uranium, plutonium, and laboratory chemicals were routed to the tank from the "hot sinks" in the 321 Building laboratories from 1944 to about 1954 during the development of the Bismuth Phosphate, Redox, Uranium Metal Recovery, PUREX, RECUPLEX, and Thorex processes and from lab scale tests on medical isotope extraction processes. Beginning in late 1944, "hot" wastes from the 3706 Building laboratories were carried to the 321 Building for disposal via the "hot sinks" to prevent contamination of the 300 Area Ponds.		
Waste Type:	Process Effluent		
Waste Description:	The tank received neutralized uranium-contaminated water and/or basic aluminum cladding waste solutions from reprocessing research and development activities in the 321 Building and the 3706 Building (via the hot sink drains in the 321 Building laboratories), including those		

related to bismuth phosphate chemical separations, REDOX, Uranium Metal Recovery, PUREX, RECUPLEX, the Thorex program, and medical isotope extraction. The tank was emptied in 1952 or 1953.

Closure Info: Interim (7/15/2013): The above grade portions of the 323 building were demolished in 2008. Demolition of the below grade structures, including the 323 tanks (1 through 4), was deferred to the adjacent UPR-300-4 remediation. During the site characterization, the four tanks were found to be filled with water. After sampling the water, approximately 100,000 gallons of water was pumped out of the four tanks and taken to the 200 Area Effluent Treatment Facility.

The four 323 tanks and the underground piping connected to the 321 building was remediated in November 2012.

Code:	323 TANK 4	Classification:	Accepted
Names:	323 TANK 4; 321 Building Underground Waste Tanks; 321 Tank Farm #3; 323 Tank 4	Reclassification	Rejected (7/15/2013)
Type:	Storage Tank	Start Date:	1/1/1944
Status:	Inactive	End Date:	1/1/1987

Description: The waste site was reclassified to Rejected. The four, underground 323 tanks have been removed. The underlying soils were addressed in the UPR-300-4 closure documentation. The tank was a carbon steel horizontal tank buried with three other identical tanks encased in a large block of concrete. The top of the concrete block was used as the floor for the installation of the 323 Building (lower level) in 1958.

Location: The underground tank had been located beneath the 323 Building, in the western portion of the 300 Area.

Release Description: According to BHI-00012, contamination in the soil surrounding the four tanks is possible. According to WHC-MR-0388, the soil around and beneath the four tanks and the tanks themselves are very contaminated with mixed wastes.

Related Sites/ Structures: The tank is associated with the 321 Building and the process sewer. It is also associated with the 323 hot cell, the cleanup box and the process water sump.

Process Description: Between 1944 and 1945, the tank received neutralized uranium-bearing wastes from cold and hot bismuth phosphate pilot tests in the 321 building. Between 1945 and 1953, the tank received neutralized uranium-contaminated water and/or basic aluminum cladding waste solutions from reprocessing research and development activities in the 321 Building and the 3706 Building (via the hot sink drains in the 321 Building laboratories), including those related to bismuth phosphate chemical separations, REDOX, Uranium Metal Recovery, PUREX, RECUPLEX, the Thorex program, and medical isotope extraction. Between 1945 and 1953, the tank may have received uranium-contaminated water and acid solutions from reprocessing research and development activities in the 321 Building, including those related to bismuth phosphate chemical separations, REDOX, PUREX, RECUPLEX, the Thorex program, and medical isotope extraction. Between 1968 and 1987, the tank received waste from the 323 Building, including the hot cell drain, the cleanup box drain and overflow from the process water sump. The tank has not received waste since 1987.

Waste Type: Process Effluent

Waste Description: Between 1945 and 1953, the tank received neutralized uranium-contaminated water and/or basic aluminum cladding waste solutions from reprocessing research and development activities in the 321 Building and the 3706 Building (via the hot sink drains in the 321 Building laboratories), including those related to bismuth phosphate chemical separations, REDOX, Uranium Metal Recovery, PUREX, RECUPLEX, the Thorex program, and medical isotope

extraction. The tank was emptied in 1952 or 1953. Between 1968 and 1987, the tank received waste from the 323 Building, including the hot cell drain, the cleanup box drain and overflow from the process water sump. The tank has not received waste since 1987. In 1987, the tank contained liquid and sludge. Significant uranium and aluminum was detected, but no thorium was detected in either the liquid or the sludge. The uranium and aluminum contamination would have entered the tank prior to 1967.

Closure Info: Interim (7/15/2013): The above grade portions of the 323 building were demolished in 2008. Demolition of the below grade structures, including the 323 tanks (1 through 4), was deferred to the adjacent UPR-300-4 remediation. During the site characterization, the four tanks were found to be filled with water. After sampling the water, approximately 100,000 gallons of water was pumped out of the four tanks and taken to the 200 Area Effluent Treatment Facility.

The four 323 tanks and the underground piping connected to the 321 building was remediated in November 2012.

Code:	325 WTF	Classification:	Accepted
Names:	325 WTF; 325 Hazardous Waste Treatment Units; 325 Waste Treatment Facility	Reclassification	None
Type:	Process Unit/Plant	Start Date:	1/1/1953
Status:	Active	End Date:	
Description:	The 325 Waste Treatment Facilities (WTF) is an active TSD unit located inside the 325 building. It consists of two sections. The first section is the shielded analytical laboratory located in Rooms 32, 200, 201, 201A, 202, and 203. The second section includes the hazardous waste treatment units, located in Rooms 520, 527A, and 528.		
Location:	The 325 Waste Treatment Facilities are located in the 325 Building. The shielded analytical laboratory is located on the west side of the 325 Building. The hazardous waste treatment unit is located on the northeast side of the 325 Building.		
Related Sites/ Structures:	Structures associated with this unit include other 325 Laboratories, the 300 Area Process Sewer, 300 Area Radioactive Liquid Waste Sewer, the Physical and Chemical Treatment Test Facilities, the Thermal Treatment Test Facilities, and the Biological Treatment Test Facilities.		
Process Description:	Mixed waste treatment in the shielded analytical laboratory includes the following processes: pH adjustment, ion exchange, evaporation, precipitation and solvent extraction, solids washing, phase separation, and solidification. The shielded analytical laboratory processes are conducted as small, bench-scale operations. Treatment processes conducted in the hazardous waste treatment units include: pH adjustment, ion exchange, carbon absorption, oxidation/reduction, evaporation, precipitation/filtration, phase separation, catalytic destruction, and solidification.		
Waste Type:	Chemicals		
Waste Description:	The waste treatment facilities treated radioactive mixed wastes generated in research and development activities. The 325 Waste Treatment Facility also served to test and evaluate the effectiveness of various waste treatment technologies.		

Code:	331-C HWSA	Classification:	Accepted
Names:	331-C HWSA; 331-C Low Level Radioactive Storage Area; 331-C Hazardous Waste Storage Area	Reclassification	Rejected (9/2/1998)
Type:	Storage Pad (<90 day)	Start Date:	1/1/1972

Status: Inactive**End Date:** 1/1/1996

Description: The former 331-C HWSA is now a steel building and fenced laydown yard that is currently in use as a refrigeration maintenance shop, material storage area, laydown yard and radioactive waste storage area. The 331-C building is divided into three sections. The southern portion of the 331-C building is currently empty. The mid section of the building is in use as a equipment and material storage area. The northern portion of the building is in use as a refrigeration maintenance shop. The maintenance shop contains a satellite accumulation area for the storage of used oil [less than 208 liters (55 gallons)]. On the east side of the building, a radioactive waste storage area was observed under the roofed area. In addition, several 208 liter (55 gallon) drums of propylene glycol was stored under the roofed area. The fenced laydown area contains equipment.

Location: The 331-C HWSA was located approximately 100 meters south of the 331 building inside 331-C, and in the storage yard on the east side of 331-C.

Release Description: No known spills or releases have been reported from this site.

Related Sites/ Structures: The unit was related to the research and development activities in the 331 Complex.

Process Description: The 90-day storage pad was originally set up under RCRA for the management of hazardous waste generated from animal research in the 331 complex. In the late 1960's, 1500 dogs were exposed to either strontium-90 or radium-226. As the dogs died, their bones and tissues were tested for the movement and accumulation of isotopes. All bones and tissues were preserved in ethanol and saved for 30 years.

Waste Type: Animal Waste

Waste Description: The site stored dog bones and tissues contaminated with strontium-90 and cesium-137 stored in 70% ethanol solution, nitric acid, formalin and regulated empty containers. Hardcopy waste disposal records, waste verification, waste inventory, packing slips, characterization summaries, offsite shipment, waste specification, land disposal notification and certification, waste manifest records are available for this site. (See hardcopy WIDS file). It appears that most of the waste disposed of onsite went to 218-W-4C and 218-W-5 Burial Grounds in the 200 West Area.

Waste Type: Misc. Trash and Debris

Waste Description:

Code: 332 SF

Classification: Accepted

Names: 332 SF; 332 Storage Facility; 332 Hazardous Waste Storage Area; 332 Interim Holding Facility; 332 Packaging Test Facility

Reclassification: Closed Out (4/21/1997)

Type: Storage

Start Date: 1/1/1984

Status: Inactive

End Date: 1/1/1997

Description: The 332 Storage Facility was procedurally Closed in 1997. It was constructed as a less than 90 day storage facility. In late 1989 or early 1990, the chemicals stored in the 332 facility were removed. The building was used only for the testing of Department of Transportation (DOT) containers. The procedural TSD closure of the 332 Storage Facility was approved by the Washington State Department of Ecology on April 21, 1997.

Location: The building is located north of the 300 Area Sanitary Trenches (300-52) and east of 618-2.

Waste Type: Chemicals

Waste Description: The facility was used for the temporary storage (<90 day) of flammable and explosive.

Closure Info: Final: Reclassification form 98-062 states "A letter was issued in 1989 requesting the Part A application for the 332 Storage Facility be withdrawn. The procedural closure of the 332 Storage Facility was approved by the Washington State Department of Ecology on April 21, 1997. A letter from the Washington State Department of Ecology, that approves closure of this TSD, is available through the Administrative Record, #0047389. No signature is required for this form."

The certification package submitted in 1989 provided verification of documentation that the operations covered by the existing Part A, Form 3 did not meet the definition of a treatment, storage and/or disposal (TSD) facility as defined in the Resource Conservation and Recovery Act (RCRA) or the State of Washington Dangerous Waste Regulations (WAC). RL has reviewed the records and activities which have occurred in the 332 Storage Facility since 1989 and has found no evidence to conclude, or suggest, that this facility was used in a manner constituting "treatment, storage, and/or disposal" as defined by regulations promulgated under either the WAC, or the RCRA.

Code: 333 ESHTSSA	Classification: Accepted
Names: 333 ESHTSSA; 333 East Side Heat Treat Salt Storage Area	Reclassification: Consolidated (2/12/1999)
Type: Storage	Start Date: 1/1/1964
Status: Inactive	End Date: 1/1/1987

Description: This waste site has been incorporated (consolidated) into the 618-1 Burial Ground waste site. This waste site is also "subsite" 618-1:1. It was Interim Closed Out with the 618-1 Burial Ground.

The 333 ESHTSSA is an inactive storage area. The site included various locations inside the 333 fence where heat-treat salts were stored. It is now an open paved area near the southeast corner of the 333 Building. Several areas of the asphalt pavement have been painted over and posted fixed radiological contamination (WIDS Site UPR-300-17).

Location: The site includes waste stored in the fenced area east of the 333 Building in the northern part of the 300 Area. The heat-treat salts were stored on the paved area near the southeast corner of the building or in the adjacent area located over a portion of the 618-1 Burial Ground.

Related Sites/Structures: The site is associated with operations in the 333 Building. The site is also associated with the 618-1 Burial Ground since it is located adjacent to and possibly over the southwest corner of the Burial Ground.

Process Description: The site was used to store containers of solidified heat-treat salt waste from the fuels fabrication facility.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: This area is no longer used for storing hazardous wastes. In the past, it stored containers of solidified waste heat-treat salts from the Fuels Fabrication Facility. The waste consisted of sodium chloride, potassium chloride, sodium nitrate, and potassium nitrate. Approximately, thirty to fifty 208-liter (55-gallon) drums accumulated each year.

This Site Was Consolidated With:

Code: 618-1
Names: 618-1; Solid Waste Burial Ground No. 1; 300 Area Burial Ground No. 1; 318-1

Code: 333 LHWSA **Classification:** Accepted
Names: 333 LHWSA; 333 Laydown Hazardous Waste Storage Area; 333 Laydown HWSA **Reclassification:** Consolidated (2/12/1999)
Type: Storage Pad (<90 day) **Start Date:** 1/1/1971
Status: Inactive **End Date:**

Description: This waste site has been consolidated into the 618-1 Burial Ground waste site. The 333 LHWSA is a concrete and asphalt pad on the east side of the 333 Building. The unit is within the 333 Building fence, and a second locked fence surrounds the unit. The white conex box in this unit is the location of the present 90-day waste storage area. Currently this conex box is empty. The yellow boxes on the opposite side of the area contain low level radioactive waste.

Location: The unit is located east of the 333 Building, within the fence of the 333 Building. The 333 Building is in the northern part of the 300 Area.

Related Sites/ Structures: The unit is related to the 333 Building Operations. This site is located over the 618-1 Burial Ground.

Process Description: The area inside the fence was originally a material laydown area. Now this area contains wastes that are segregated into a 90-Day Storage Pad for hazardous wastes and a Radioactive Material Area for low level radioactive waste storage.

Waste Type: Misc. Trash and Debris

Waste Description: The fixed contamination area, i.e., concrete and asphalt, that was the result of storing radioactive materials in the past will be addressed as part of 618-1 Burial Ground. The Burial Ground underlies the 333 LHWSA.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: The area typically contains corrosive and toxic metal wastes.

This Site Was Consolidated With:

Code: 618-1
Names: 618-1; Solid Waste Burial Ground No. 1; 300 Area Burial Ground No. 1; 318-1

Code: 333 WSTF **Classification:** Accepted
Names: 333 WSTF; 333 WSWOT; 333 West Side Tank Farm; 333 West Side Uranium Bearing Acid Tanks; 333 West Side Waste Oil Tank **Reclassification:** Final Closed Out (5/12/2014)
Type: Storage Tank **Start Date:** 1/1/1972
Status: Inactive **End Date:**

Description: This site has been remediated and Interim Closed Out. In 2014, the site was reclassified to Final Closed Out. It was an above grade tank farm containing three cylindrical tanks that stand upright within a concrete containment basin. The containment basin was attached to the outside wall of the 333 Building. One of the tanks was labeled "Non Contaminated Waste Oil - Flashpoint 455 degrees F." The two other tanks were labeled "Uranium bearing acid." The concrete containment basin was 6 meters (19.7 feet) by 4.2 meters (13.8 feet) with a depth of

	0.4 meters (1.3 feet). Asphalt pavement surrounded the basin and the west side of the building. On this pavement there is a sign posting fixed radioactive contamination.
Location:	The tank farm was located on the west side of the 333 Building, in the northern part of the 300 Area.
Related Sites/ Structures:	The tanks are associated with operations in the 333 Building.
Process Description:	The 300 Area WATS began partial operations in January 1973 with tank storage and treatment of waste acid and entered full operations in 1975. The primary source of the waste acid was N Reactor fuel fabrication operations that occurred in tanks in the 333 Building from 1961 until 1987. The waste acids from these operations that contained nonrecoverable uranium were treated in the 300 Area WATS. Because this acid waste contained small amounts of uranium, the waste is considered to have been a mixed waste entering the 300 Area WATS. The 300 Area WATS permanently ceased operations in 1995. Partial clean closure activities for this unit began in 1996 and were completed in September 1999. Clean closure activities occurred in three phases, in accordance with the approved clean closure plan and the requirements of Part V, Chapter 20, of the Hanford Facility RCRA Permit. RCRA Clean closure was achieved for all 300 Area WATS locations and components in October 2005.
	The Waste Oil Tank temporarily stored oil from the extrusion press sump prior to shipment off site. When in use the process accumulated between 1892 and 3785 liters per year (500 to 1000 gallons per year). The Uranium Bearing Acid tanks temporarily stored spent acid from the 333 Building uranium acid etch process tanks. The spent acid was pumped from these storage tanks to the Uranium Recovery Operations (WIDS Site 313 URO) process in the 313 Building where the acid was treated for uranium recovery and recycling.
Waste Type:	Oil
Waste Description:	The Waste Oil Tank was used for storage of oil from the extrusion press sump. It was verified that the oil did not contain polychlorinated biphenyls and was not ignitable prior to removal. No known releases have been reported.
Waste Type:	Chemicals
Waste Description:	The Uranium Bearing Acid tanks stored spent acid containing uranium. The uranium was a recoverable asset for recycling.
Closure Info:	Interim (1/9/2012): Note that the portions of the WATS trench that were inside the 333 Building and east of the 333 Building are not part RSVP-2011-106 interim closeout document. The portion of the 300-219 and 300-224 waste sites that were in the 618-1 Burial Ground were clean closed as part of the 300 Area WATS Resource Conservation and Recovery Act of 1976 (RCRA) treatment, storage, and disposal unit (TS-3-1). The portions of the 300-219 and 300-224 waste sites addressed in the RSVP-2011-016 document are the portions of the WATS trench from the 313 Building to the 333 Building.
	Remediation of the 300-219 and 300-224 waste sites was performed from December 14, 2009, through May 23, 2011. The majority of the soil within the waste sites footprints were excavated to a depth of 0.5 to 1.0 meters (1.6 to 3.3 ft) below ground surface (bgs). The soil under the 300-224 loading area was excavated to a depth of over 1.5 meters (4.9 ft) bgs. Remediation of the 333 WSTF waste site was performed on December 14, 2009. The soil within the waste site footprint was excavated to a depth of 1.0 meter (3.3 ft) bgs, resulting in 40 BCM (52 BCY) of soil was being disposed at the ERDF. The resulting 581 bank cubic meters (BCM) (760 bank cubic yards [BCY]) of soil was disposed at the Environmental Restoration Disposal Facility (ERDF).
	Final: The 300-219 waste site consists of the transfer lines inside the 300-224 Waste Acid

Treatment System (WATS) trench. The 300-224 WATS trench ran between the 313 Building, 303-F Building, 311 Tank Farm, 333 Building, 334-A Building, and 334 Tank Farm. The 333 WSTF waste site, located on the west side of the former 333 Building, was an above-grade tank farm with a concrete containment basin. Remediation occurred from 2009 through 2011 with a maximum depth of 4.9 feet. The 300-219, 300-224, and 333 WSTF waste sites were remediated and have been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). Verification sampling results show that the site meets the CULs for direct exposure and groundwater protection and river protection and support an industrial land use scenario. Because the sample results do not meet the CULs for residential land use, the waste sites require institutional controls to maintain industrial land use. In accordance with this evaluation, the verification sampling results support a reclassification of the 300-219, 300-224, and 333 WSTF waste sites to Final Closed Out.

Code:	333-TK-11	Classification:	Accepted
Names:	333-TK-11; 333 Chromium Treatment Tank 2; 333 West Side Storage Tank for Uranium Bearing Acid	Reclassification	Closed Out (7/8/2013)
Type:	Storage Tank	Start Date:	1/1/1961
Status:	Inactive	End Date:	1/1/1998
Description:	The RCRA TSD permit was Closed under the 300 Area Waste Acid Treatment System (WATS) RCRA TSD partial closure. The 333-TK-11 tank was removed in 1998. It was a square uncovered metal tank. The unit was connected to the 300 Area Waste Treatment System by a polyvinyl chloride (PVC) drain line.		
Location:	The tank was located inside the 333 Building, west of the Pipe Trench.		
Related Sites/ Structures:	The unit was related to the 333 fuel fabrication activities and the 300 Area Waste Acid Treatment System.		
Process Description:	From 1983 to 1987, Tank 11 was used to treat waste acid by reducing chromium (VI) to chromium (III). The waste acid was drained to the 334-A Facility Storage Tanks.		
Waste Type:	Chemicals		
Waste Description:	The tank was used to store spent etch acids (nitric and sulfuric acid with uranium in solution). The unit was also used to treat metal-bearing waste acids by reducing chromium (VI) to chromium (III).		
Closure Info:	Final: Waste Site Reclassification Form 2001-105 states "Partial closure activities for the 300 Area Waste Acid Treatment System (300 Area WATS) are now complete. The attached certification statement was prepared in accordance with WAC 173-303-610 (6) to independently certify that the 300 Area WATS partial closure activities were performed in accordance with the approved 300 Area Waste Acid Treatment System Closure Plan (DOE/RL-90-11, Rev 2, dated May 1999). This closure plan is considered approved by the Washington State Department of Ecology through Ecology acceptance of the plan as complete in a letter dated July 27, 1999 and because the plan underwent public review without comment. ...Partial closure activities included the activities necessary to clean close all 300 Area WATS aboveground structures and components and most soils. Not all soil potentially contaminated by WATS operations could be clean closed at the time of partial closure." The December 3, 2001, DOE Partial Closure Certification noted that "The unclosed locations include two areas of potential soil contamination from 300 Area WATS operations that are defined in the closure plan. These areas will remain unclosed and RCRA regulated until soil disposition in conjunction with the future 300-FF-2 CERCLA OU remedial action that will complete 300 WATS closure."		

This RCRA TSD site has been Clean Closed. Tank 333-TK-11 was removed in 1998 pursuant to the Phase II Decontamination and Inspection Plan. Ecology inspected the cleanup site in August 1998. Ecology concurred that the work was done to the plan.

Code:	333-TK-7	Classification:	Accepted
Names:	333-TK-7; 333 Chromium Treatment Tank 1; 333 West Side Storage Tank for Uranium Bearing Acid	Reclassification	Closed Out (7/13/2013)
Type:	Storage Tank	Start Date:	1/1/1961
Status:	Inactive	End Date:	1/1/1998
Description:	The RCRA TSD permit for this site was Clean Closed under the 300 Area WATS partial RCRA TSD closure in 2001. Tank 333-TK-7 had been removed in 1998. Tank 333-TK-7 was a square, uncovered metal tank. The unit was connected to the 300 Area Waste Acid Treatment System by a polyvinyl chloride drain line. The tank was last used in 1987.		
Location:	The tank was removed in 1998; it was located inside the 333 Building, west of the pipe trench.		
Related Sites/ Structures:	The unit was related to tank 311-TK-11, the 333 fuel fabrication facility, the Pipe Trench, the 334-A Building and Tank Farm, and the 300 Area Waste Acid Treatment System (WATS).		
Process Description:	From 1983 to 1987 the tank was used to treat waste acid by reducing chromium (VI) to chromium (III). The waste acid was drained via piping in the Pipe Trench to the tanks 334-TK-B and 334-TK-C in the 334-A tank pit.		
Waste Type:	Chemicals		
Waste Description:	The tank was used to store spent etch acids (nitric and sulfuric acid with uranium in solution). The unit was later used to reduce chromium (VI) to chromium (III) in metal-bearing waste acids.		
Closure Info:	Final: The waste site was clean closed under the 300 Area WATS partial RCRA TSD closure in 2001. The tank was removed pursuant to Phase II of the Decontamination and Inspection Plan. The tank removal site was inspected by Ecology in August, 1998 and written concurrence of the work done was received in September 1998.		

Reclassification form 2001-109 documents "Partial closure activities included the activities necessary to clean close all 300 Area WATS aboveground structures and components and most soils. Not all soil potentially contaminated by WATS operations could be clean closed at the time of partial closure." The December 3, 2001, DOE Partial Closure Certification noted that "The unclosed locations include two areas of potential soil contamination from 300 Area WATS operations that are defined in the closure plan. These areas will remain unclosed and RCRA regulated until soil disposition in conjunction with the future 300-FF-2 CERCLA OU remedial action that will complete 300 WATS closure."

Code:	334 TFWAST	Classification:	Accepted
Names:	334 TFWAST; Tank 4; 334 Tank Farm Waste Acid Storage Tank	Reclassification	Closed Out (12/6/2001)
Type:	Storage Tank	Start Date:	1/1/1971
Status:	Inactive	End Date:	1/1/1988
Description:	This site RCRA TSD was Clean Closed under the 300 Area WATS partial RCRA TSD closure.		

	The tank was taken out of service in 1986 and removed in 1988. The tank was a 27,710 liter (6000 gallon) Koroseal-lined mild steel tank. It was a vertical cylindrical tank installed on the upper level of the 334 Tank Farm structure, about 8 feet (2.4 meters) above ground level.
Location:	The tank was the north elevated tank in the 334 Tank Farm, located on the east side of the 333 Building.
Release Description:	Unusual Occurrence UO-86-01 states: At about 2200 hours on January 2, 1986, acid was found leaking from the waste acid storage tank (#4) located in the 334 Tank Farm. The leak drained to the process sewer which discharged to the 300 Area process trenches. The waste acid was pumped to another tank and at about 0100 hours on January 3, 1986, 60 gallons of 50 percent caustic was added to the process sewer. The pH meter strip chart for the 333 Building waste water indicated that an unusually low pH first occurred at about 1800 hours and by 0200 hours the pH readings in the waste water stream was back to normal. The pH did not get low enough during the event to trip the pH meter alarm. No acid spilled to the ground; it was all contained within the bermed concrete pad beneath the 334 Tank Farm which drained to the process sewer. Inspection of the tank indicated that the waste acid had corroded through the (Koroseal lined, mild steel) tank in several places about 10 percent down from the top of the tank. The operating staff reported that to the best of their knowledge since Tank 4 was placed in service about ten years earlier, it had never been filled the level at which failure occurred until this event.
Related Sites/Structures:	The tank was related to the 334 Tank Farm, the 333 N Fuels zircaloy fuel etching process, the 300 Area Waste Acid Treatment System, and the Process Sewer.
Process Description:	Tank 334 TFWAST (TK-4) in the 334 Tank Farm was first used in 1973 to store the waste acid for the 300 Area Waste Acid Treatment System while waste acid storage tanks TK-B and TK-C were installed in the 334-A Building. After that time, TK-4 was used for emergency storage during periods when the acid neutralization equipment in the 313 Building was not in operation. When tank TK-4 was filled in January 1986, a leak developed near the top of the tank. The tank was drained at that time and removed in 1988.
Waste Type:	Chemicals
Waste Description:	The unit was intermittently used to store waste acids containing nonrecoverable uranium from the fuel fabrication process.
Closure Info:	Final: This site has been Clean Closed under the 300 Area Waste Acid Treatment System (WATS) partial closure. The 334 Tank Farm Waste Acid Storage Tank 4 was removed in 1988. The superstructure which held tank TK-4 will be decontaminated as required during the Phase 3 closure activities for the 300 Area Waste Acid Treatment System. The RCRA Closure Plan for the 300 Area Waste Acid Treatment System was submitted to Ecology in June 1990; Revision 1 of the closure plan was submitted in March 1996, and Revision 2 in July 1999. Reclassification form 2001-106 states: "Partial closure activities for the 300 Area Waste Acid Treatment System (300 Area WATS) are now complete. The attached certification statement was prepared in accordance with WAC 173-303-610 (6) to independently certify that the 300 Area WATS partial closure activities were performed in accordance with the approved 300 Area Waste Acid Treatment System Closure Plan (DOE/RL-90-11, Rev 2, dated May 1999). This closure plan is considered approved by the Washington State Department of Ecology through Ecology acceptance of the plan as complete in a letter dated July 27, 1999 and because the plan underwent public review without comment. ...Partial closure activities included the activities necessary to clean close all 300 Area WATS aboveground structures and components and most soils. Not all soil potentially contaminated by WATS operations could be clean closed at the time of partial closure." The December 3, 2001, DOE Partial Closure Certification noted that "The unclosed locations include two areas of potential soil contamination from 300 Area WATS operations that are defined in the closure plan. These areas will remain unclosed and RCRA regulated until soil disposition in conjunction with the future 300-FF-2 CERCLA OU remedial action that will complete 300 WATS closure."

Code:	334-A-TK-B	Classification:	Accepted
Names:	334-A-TK-B; 334-A Waste Acid Storage Tank 1	Reclassification	Closed Out (12/6/2001)
Type:	Storage Tank	Start Date:	1/1/1975
Status:	Inactive	End Date:	1/1/1998

Description: The RCRA permit for this site was Clean Closed under the 300 Area WATS partial RCRA TSD closure in 2001. The tank was removed in 1998. The horizontal 7570 liter (2000 gallon) tank was a high-density polyethylene tank resting on a steel saddle. The tank was one of three tanks in a 3 meter (10 foot) deep concrete pit below the 334-A Building. A cover has been installed over the pit and the cover sealed.

Location: The unit was located in the 334-A Tank Pit, east of the 333 Building.

Related Sites/ Structures: The unit is associated with the 334-A-TK-C, the 334-A Tank Pit, the 334-A Building, the Pipe Trench, the 333 Building etch tanks, the 300 Area Waste Acid Treatment System (WATS), and 300-21.

Process Description: The tank stored spent etch acid from the 333 Building fuel fabrication process. Spent acid was drained from the 333 Building etch tanks (8 tanks with a total capacity of 7551 liters [1995 gallons]) to Tank 334-A-TK-B via a 10.1 cm (4-inch) diameter PVC line (see 300-219) in the Pipe Trench (see 300-224). The waste acid was stored until treated by the 300 Area Waste Acid Treatment System. The waste acid was pumped via a 5.1 cm. (2-inch) diameter PVC line in the Pipe Trench to the 313-TK-2 neutralization tank in 313 Building. Spills from the tank into the concrete pit were contained and recovered. A spill alarm in the pit alerted operating personnel. No record was found of any contamination released outside the 334-A boundaries.

Waste Type: Chemicals

Waste Description: The unit was removed in 1998. It received waste acids from the fuel fabrication process. The waste contained nonrecoverable uranium, hydrofluoric, nitric, sulfuric, and chromic acids, and various metals.

Closure Info: Final: Form 2001-017 documents the reclassification to Closed Out. This site was clean closed under the 300 Area WATS partial closure. Tank TK-B was removed in 1998 as part of the cleanup activities pursuant to the Decontamination and Inspection Plan issued for Closure Phase 2. The cleaned site was inspected by Ecology on August 25, 1998. Ecology verified that the Phase 2 work was performed in accordance with Ecology's "Clean Closure Guidance Document" method of a clean debris surface and later provided final approval of the Phase 2 closure.

Code:	334-A-TK-C	Classification:	Accepted
Names:	334-A-TK-C; 334-A Waste Acid Storage Tank 2	Reclassification	Closed Out (12/6/2001)
Type:	Storage Tank	Start Date:	1/1/1975
Status:	Inactive	End Date:	1/1/1998

Description: The permit for this site was Clean Closed under the 300 Area WATS partial RCRA TSD closure in 2001. The tank was removed in 1998. The horizontal 7570 liter (2000 gallon) tank was a high-density polyethylene tank resting on a steel saddle. The tank was one of three tanks in a 3 meter (10 foot) deep concrete pit below the 334-A Building. A cover has been installed over the pit and the cover sealed.

Location: The unit was located in the 334-A Tank Pit, east of the 333 Building.

Related Sites/ Structures:	The unit is associated with the 334-A-TK-B, the 334-A Tank Pit, the 334-A Building, the Pipe Trench, the 333 Building etch tanks, and the 300 Area Waste Acid Treatment System.
Process Description:	The tank stored spent etch acid from the 333 Building fuel fabrication process. Spent acid was drained from the 333 Building etch tanks (8 tanks with a total capacity of 7551 liters [1995 gallons]) to Tank 334-A-TK-C via a 10.1 cm (4-inch) diameter PVC line (see 300-219) in the Pipe Trench (see 300-224). The waste acid was stored until treated by the 300 Area Waste Acid Treatment System. The waste acid was pumped via a 5.1 cm. (2-inch) diameter PVC line in the Pipe Trench to the 313-TK-2 neutralization tank in 313 Building. Spills from the tank into the concrete pit were contained and recovered. A spill alarm in the pit alerted operating personnel. No record was found of any contamination released outside the 334-A boundaries.
Waste Type:	Chemicals
Waste Description:	The unit was removed in 1998. It received waste acids from the fuel fabrication process. The waste contained nonrecoverable uranium, hydrofluoric, nitric, sulfuric, and chromic acids in solution bearing metals in solution.
Closure Info:	Final: Form 2001-108 documents the reclassification to Closed Out. Tank TK-C was removed in 1998 as part of the cleanup activities pursuant to the Decontamination and Inspection Plan issued for Closure Phase 2. The cleaned site was inspected by Ecology on August 25, 1998. Ecology verified that the Phase 2 work was performed in accordance with Ecology's "Clean Closure Guidance Document" method of a clean debris surface and provided tentative approval of the Phase 2 closure. The site was clean closed as part of the 300 Area WATS partial closure in December 2001.

Code:	335 & 336 RSDF	Classification:	Accepted
Names:	335 & 336 RSDF; 335 & 336 Retired Sanitary Drain Field	Reclassification	Rejected (2/12/1999)
Type:	Drain/Tile Field	Start Date:	1/1/1973
Status:	Inactive	End Date:	1/1/1978
Description:	The 335 and 336 RSDF is a below grade waste site consisting of a septic tank and drainfield that were abandoned in place in 1978. In 2012, the drain field was filled with grout. The top three feet were removed in conjunction with the demolition of the 335 and 336 buildings.		
Location:	The site is located south of the southwest corner of the 335 Building.		
Related Sites/ Structures:	The site was associated with the 335 and 336 Sanitary Waste Systems. The 335 and 336 Buildings were constructed to house experimental equipment for the study of the properties of sodium and the behavior of mechanical components to be operated in a sodium environment in support of FFTF development (through the late 1970's).		
Process Description:	The unit disposed of sanitary waste generated in the 335 and 336 Buildings.		
Waste Type:	Sanitary Sewage		
Waste Description:	The unit received unknown amounts of sanitary wastes from the 335 and 336 Buildings.		

Code:	340 CHWSA	Classification:	Accepted
Names:	340 CHWSA; 340 Complex Hazardous Waste Storage Area; 340 Complex HWSA	Reclassification	Rejected (1/15/1999)

Type: Storage Pad (<90 day) **Start Date:**

Status: Inactive **End Date:**

Description: According to 340 Complex personnel, hazardous waste was staged for less-than-90-day storage at various locations throughout the 340 Complex yard. This includes a small concrete pad to the northeast of 340B, and the asphalt pad to the west of the 340 Building.

Location: Waste was staged at various locations inside the 340 Complex Yard.

Release Description: Per Bob Haggard, WMH Environmental Compliance Officer, there is no evidence of an actual or potential for a hazardous substance release.

Related Sites/ Structures: This storage area staged wastes related to 340 Complex operations.

Process Description: Hazardous waste was stored for less than 90 days at various areas throughout the 340 Complex yard.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: This area is no longer used to stage hazardous waste.

Code: 350 HWSA **Classification:** Accepted

Names: 350 HWSA; 350-D Hazardous Waste Staging Area; 350 Building Hazardous Waste Storage Area **Reclassification:** Rejected (2/24/1999)

Type: Storage Pad (<90 day) **Start Date:** 1/1/1982

Status: Active **End Date:**

Description: The 350 Hazardous Waste Staging Area is inside the 350-D Building and on an asphalt pad in front of the building.

Location: The staging area is located in the northeast corner of the fenced 350 Compound.

Related Sites/ Structures: The unit is associated with the 350 Plant and Operations Facility.

Process Description: The staging area is used to temporarily store hazardous wastes. Combustible liquids and PCB containing waste are stored inside the building. Used oil is stored in a 300-gallon (1140-liter) tank behind the 350-D Building. Other waste is stored on the pad in front of the building.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: Typically, the area stores corrosive chemicals, used oils and PCB-contaminated oils. Oil containing PCBs from old ballasts is stored inside the 350-D building along with combustible liquids.

Code: 3712 USSA **Classification:** Accepted

Names: 3712 USSA; 3712 Building Uranium Scrap Storage Area; 3712 Fuels Warehouse; 3712 Uranium Scrap Storage Area **Reclassification:** Final Closed Out (5/12/2014)

Type: Storage **Start Date:** 1/1/1961

Status: Inactive **End Date:**

Description: This site has been remediated and Interim Closed Out. In 2014, the site was reclassified to Final Closed Out. The 3712 USSA was a uranium metal storage unit. The building was a steel frame structure with metal siding and a metal roof and a concrete floor and foundation.

Location: The unit was located on the east side of the 313 Building, south of 3720 and west of 306W.

Related Sites/ Structures: The unit is associated with the fuel manufacturing that occurred in the 313 and 333 Buildings.

Process Description: The building had been used to store uranium fuel elements, fuel fabrication components, and uranium scraps from the 313 and 333 fuel fabrication efforts.

Waste Type: Chemicals

Waste Description: The unit is used to store uranium fuel elements, components for fuel fabrication, concrete billets of ignitable uranium chips and fines, and uranium scrap. Contamination resulting from the 1979 and 1985 fires may be present in or on building surfaces.

Closure Info: Interim (8/16/2011): Demolition of the above-grade 3712 Building structure was completed in January 2006 and remedial action of the 3712 USSA waste site, including the 3712 Building slab and foundation, was performed between June 3 and 15, 2010. The waste site was excavated to a depth ranging from approximately 1.0 m (3.3 ft) to 1.5 m (4.9 ft) below ground surface, resulting in approximately 999 bank cubic meters (1,307 bank cubic yards) or 2,167 metric tons (2,388 U.S. tons) of building slab and foundation debris and soil disposed at the Environmental Restoration Disposal Facility (ERDF) in the 200 Area of the Hanford Site. All material was direct loaded from the excavation; therefore, no waste staging piles were created. No overburden soil stockpiles are associated with the waste site. A post-excavation radiological survey for gamma and beta activity was conducted following the completion of remedial action to confirm that waste site excavation was complete. No elevated gamma activity was detected nor was elevated beta activity detected. A post-excavation civil survey for the excavation has been completed.

A geophysical investigation was not conducted at the 3712 USSA waste site because the 3712 Building concrete slab was in place at the start of the remediation activities.

Final (5/12/2014): The 3712 USSA, Uranium Scrap Storage Area waste site was a metal building built in 1961 and used to store uranium fuel elements, fuel fabrication components, and uranium scraps from the 313 Building and 333 Building fuel fabrication efforts. The 3712 Building was a steel frame structure with metal siding and a metal roof. The building had a concrete floor and foundation. Demolition of the above-grade 3712 Building structure was completed in January 2006 and remedial action of the 3712 USSA waste site, including the 3712 Building slab and foundation, was performed in June 2010. The waste site was excavated from 1.0 meter (3.3 ft) to 1.5 meter (4.9 ft) below ground surface. Verification sampling was conducted on January 31, 2011.

The 3712 USSA waste site were remediated and have been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the RDR/RAWP (DOE-RL 2014). Verification sampling results show that the site meets the CUL's for direct exposure and groundwater protection and river protection and support a residential land use scenario. Contamination at the waste site did not extend into the deep zone (below 4.6 m [15 ft]); therefore, institutional controls to prevent uncontrolled drilling or excavation into the deep zone are not required. In accordance with this evaluation, the verification sampling results support a reclassification of the 3712 USSA waste site to Final Closed Out.

Code: 3713 PSHWSA

Classification: Accepted

Names: 3713 PSHWSA; 3713 Paint Shop Hazardous Waste Satellite Area **Reclassification** Rejected (1/27/1999)

Type: Satellite Accumulation Area **Start Date:** 1/1/1984

Status: Inactive **End Date:** 1/1/1987

Description: Until 1987, the site was a hazardous waste satellite accumulation area. Today, the site is a concrete pad surrounded by a fiberglass and wood fence. There is a drain in the center of the pad. Items stored in this area include nonhazardous materials, such as ladders, hoses, and pipe. Currently, the 3713 Building is being used as a carpenter's shop.

Location: The site is outside the southeast door of the 3713 Building.

Related Sites/Structures: The site was associated with the 3713 Paint Shop. The building is now the 3713 Carpentry Shop.

Process Description: The unit was used to temporarily store small quantities of hazardous waste.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: Hazardous wastes have not been accumulated at this facility since the paint shop was moved. The area contained small quantities of miscellaneous waste solutions. The waste was derived from paint shop operations.

Code: 3713 SSHWSA **Classification:** Accepted

Names: 3713 SSHWSA; 3713 Sign Shop Hazardous Waste Satellite Area **Reclassification** Rejected (1/27/1999)

Type: Satellite Accumulation Area **Start Date:** 1/1/1984

Status: Inactive **End Date:** 1/1/1987

Description: Until 1987, the site was a hazardous waste satellite accumulation area. It is no longer in existence. No evidence of the satellite accumulation area is apparent.

Location: The staging area was located outside the north entrance of the 3713 Building.

Related Sites/Structures: The unit was associated with the 3713 Sign shop. The 3713 Building is currently a carpenter's shop.

Process Description: The staging area accumulated small quantities of nonsolvent waste from sign shop operations.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: Hazardous wastes are no longer staged at this facility. The area accumulated miscellaneous small quantities of nonsolvent waste solutions from sign shop operations.

Code: 3718-F BS **Classification:** Accepted

Names: 3718-F BS; 3718-F Burn Shed **Reclassification** Closed Out (8/1/1998)

Type: Process Pit **Start Date:** 1/1/1968

Status: Inactive **End Date:** 1/1/1998

Description: The site was a component of a Treatment, Storage and Disposal unit that has been Clean

Closed. It was a small structure designed to burn waste alkali metals. It was part of the 3718-F Alkali Metal Treatment and Storage Facility TSD Unit. The RCRA TSD has been Closed. The structure has been removed and all that remains is the concrete pad that is shared with other components related to the 3718-F Alkali Metal Treatment and Storage Facility.

The 3718-F Burn Shed was a 3.0-meter by 3.7-meter (10-foot by 12-foot) sheet metal enclosure with a 2.4 meter (8-foot) wide roll-up door. Small stirring ports and windows were placed on the north and west sides. To the east of the burn shed was a fume scrubber through which the gaseous emissions from the burning were processed. The burn shed and fume scrubber were connected by overhead ductwork. The burn shed and fume scrubber were built on a concrete pad. The pad was bermed on the north and south and sloped to the east. A channel on the east side routed any drainage to a floor drain which discharged to the process sewer.

Location: The unit was located in the 300 Area, east of the 324 Building. It shared a common fence with the 3717C, 335, 335A, and 336 Buildings. The burn shed was located on a concrete pad adjacent to the east side of the storage building (3718-F SF).

Related Sites/ Structures: The unit is associated with the adjacent fume scrubber, the storage building (3718-F SF), and the treatment tanks (3718-F TT1 and 3718-F TT2).

Process Description: When the facility was used, alkali metals were placed in burn pans, surrounded by fuel, and ignited with a torch inserted through a stirring port. The molten metals were stirred to allow for complete combustion. A water fog was then applied to the metals, completing the oxidation process. Effluents were neutralized and discharged to the process sewer.

Waste Type: Chemicals

Waste Description: Wastes treated at the unit included: sodium, lithium and sodium-potassium alloys. After burning, the remaining wastes would have consisted of alkali metal oxides and carbonates. Small quantities of reactive laboratory waste may also have been treated. All wastes have been removed.

Closure Info: Final: All structures associated with the 3718-F Alkali Metal Treatment Facility were removed during September 1996 and May 1998. All that remained was the concrete pad.

On February 24, 1998 it was agreed that DOE would perform a voluntary action to remove the drainage sump structure with from which the PCB contaminated sample was taken and to conduct soil sampling in the vicinity of the structure. Initial sampling was performed on March 17, 1998 to determine the levels of PCB's. Cleanup activities occurred between May 1, 1998 and May 6, 1998. During this time, three drain structures were removed. The drain to the process sewer at the northeast corner of the treatment pad was removed and the line connecting to the process sewer was plugged. The two drain sumps for the fume scrubber were removed as a unit because they were connected together with a metal brace. One drain sump was found to be open to soil at the bottom. The two structures were resting on an aluminum plate covered with a white encrustation (later determined to be corroded aluminum). All discolored soil was removed and drummed. Sampling of the drummed soil and the soil beneath the aluminum plate was performed.

The reclassification is documented on forms 98-085, 98-086, 98-087, and 98-088.

Code: 3718-F SF	Classification: Accepted
Names: 3718-F SF; 3718-F Storage Facility; 3718-F Alkali Metal Treatment Facility	Reclassification: Closed Out (8/4/1998)
Type: Storage	Start Date: 1/1/1968
Status: Inactive	End Date: 1/1/1989

Description: The 3718-F Storage Facility was a component of a Treatment, Storage and Disposal unit that has been Clean Closed. It consisted of a single-story building, an adjoining loading pad, and a concrete treatment pad. It was part of the 3718-F Alkali Metal Treatment and Storage Facility TSD Unit. The RCRA TSD has been Closed Out. The storage building has been removed and all that remains is the concrete pad, which it shared with other sites related to the 3718-F Alkali Metal Treatment and Storage Facility.

The 3718-F Storage Facility was designed and constructed in 1968, and redesigned and modified in 1973. The building, which measured 6.1 meters by 14.6 meters (20 feet by 48 feet), was constructed on a concrete pad. The gabled ends, roof, and siding were corrugated steel. The building had electric lights, electric space heaters, and two window air conditioning units. The northern half of the building was used as a storage area and the southern half was used as a work area. A concrete loading pad measuring 3.7 meters by 6.1 meters (12 feet by 20 feet) was located at the south end of the building.

The 15-centimeter (6-inch) thick concrete treatment pad measuring 7.2 meters by 14.6 meters (25 feet by 48 feet) adjoined the east side of the building. A burn shed and fume scrubber (3718-F BS) and two treatment tanks (3718-F TT1 and 3718-F TT2) were located on the pad. The north and south ends of the pad are bermed and the pad slopes to the east. Along the east edge is a 7.6-centimeter (3-inch) wide by 7.6 centimeter (3-inch) deep trench. The trench was connected to a floor drain which discharged to the process sewer system. This design was intended to prevent runoff onto the surrounding soils.

Location: The unit was located in the 300 Area, east of the 324 Building. It shared a common fence with the 3717C, 335, 335A, and 336 Buildings.

Related Sites/ Structures: The unit was associated with a burn shed and fume scrubber (3718-F BS) and two treatment tanks (3718-F TT1 and 3718-F TT2).

Process Description: The 3718-F Storage Facility was used to store high purity alkali metals and alkali metal alloys to be used in laboratories. Before 1985, solutions from the treatment tanks were drained onto the concrete pad through a valve in the bottom of the tanks. The spent reagents would flow across the pad to the trough and from the trough to the 300 Area Process Sewer. Beginning in 1985, all spent alcohol solutions were packaged in approved containers and handled as dangerous waste. The used water continued to be drained to the process sewer until 1987 when the use of the treatment tanks was discontinued.

Waste Type: Chemicals

Waste Description: Hazardous wastes are no longer stored in this facility. The wastes stored at the facility while in use consisted of sodium, lithium, and sodium alloys. Cleaning agents used within the treatment tanks and discharged to the concrete pad included water, methanol, isopropanol, and 2-butoxy ethanol (trade name Dowanol). Reaction products contained within the solutions included alkali oxides, alkali carbonates, and alkoxides (strong organic bases). During cleanup, polychlorinated biphenyl (PCB) Aroclor 1254 contamination from an unknown source was identified in soil samples.

Closure Info: Final: All structures associated with the 3718-F Alkali Metal Treatment Facility were removed during September 1996 and May 1998. All that remained was the concrete pad.

On February 24, 1998 it was agreed that DOE would perform a voluntary action to remove the drainage sump structure with from which the PCB contaminated sample was taken and to conduct soil sampling in the vicinity of the structure. Initial sampling was performed on March 17, 1998 to determine the levels of PCB's. Cleanup activities occurred between May 1, 1998 and May 6, 1998. During this time, three drain structures were removed. The drain to the process sewer at the northeast corner of the treatment pad was removed and the line connecting to the process sewer was plugged. The two drain sumps for the fume scrubber were removed as

a unit because they were connected together with a metal brace. One drain sump was found to be open to soil at the bottom. The two structures were resting on an aluminum plate covered with a white encrustation (later determined to be corroded aluminum). All discolored soil was removed and drummed. Sampling of the drummed soil and the soil beneath the aluminum plate was performed.

The reclassification is documented on forms 98-085, 98-086, 98-087, and 98-088.

Code:	3718-F TT1	Classification:	Accepted
Names:	3718-F TT1; 3718-F Treatment Tank 1	Reclassification	Closed Out (8/4/1998)
Type:	Storage Tank	Start Date:	1/1/1968
Status:	Inactive	End Date:	1/1/1998

Description: The waste site was a component of a Treatment, Storage and Disposal unit that has been Clean Closed. The 3718-F Treatment Tank 1 (3718-F TT1) was a tank used to clean equipment contaminated with alkali metals by reacting the metals with alcohol. It was part of the 3718-F Alkali Metal Treatment and Storage Facility TSD Unit. The RCRA TSD has been Closed Out. The tank has been removed and all that remains is the concrete pad which it shared with other sites related to the 3718-F Alkali Metal Treatment and Storage Facility.

3718-F TT1 was a long, narrow tank constructed of 0.3-centimeter (1/8-inch) stainless steel. The tank had a hinged solid cover and was supported by eight metal legs spaced in pairs at intervals along the its length.

Location: The unit was located in the 300 Area, east of the 324 Building. It shared a common fence with the 3717C, 335, 335A, and 336 Buildings. The tank was located on a concrete pad adjacent to the east side of the storage building.

Related Sites/Structures: Structures associated with the unit include the other treatment tank (3718-F TT2), the burn shed and fume scrubber (3718-F BS), and the storage shed (3718-F SF).

Process Description: Equipment contaminated with alkali metals was cleaned in an alcohol bath in the tank. The alcohol bath was used for confined quantities of sodium because the sodium-alcohol reaction was slower and easier to control. The reaction process took up to several days to complete, depending on the amount of sodium on the component and the presence of tight crevices which would minimize the surface area available for reaction. The reaction of the alkali metals with alcohol produced alkoxides, strong organic bases. Alcohols used in this process included methanol, isopropanol, and 2-butoxy ethanol (trade name Dowanol).

Before 1985, solutions from the treatment tanks were drained onto the concrete pad through a valve in the bottom of the tanks. The spent reagents would flow across the pad to the trough and from the trough to the 300 Area Process Sewer. Beginning in 1985, all spent alcohol solutions were packaged in approved containers and handled as dangerous waste. The used water continued to be drained to the process sewer until 1987 when the use of the treatment tanks was discontinued.

Waste Type: Chemicals

Waste Description: Hazardous wastes are no longer treated in the tank. Wastes treated at the tank included sodium, lithium, and sodium-potassium alloys. Cleaning agents used within the treatment tank included methanol, isopropanol, and 2-butoxy ethanol (trade name Dowanol). The reaction products were alkoxides (strong organic bases).

Closure Info: Final: All structures associated with the 3718-F Alkali Metal Treatment Facility were removed during September 1996 and May 1998. All that remained was the concrete pad.

On February 24, 1998 it was agreed that DOE would perform a voluntary action to remove the drainage sump structure with from which the PCB contaminated sample was taken and to conduct soil sampling in the vicinity of the structure. Initial sampling was performed on March 17, 1998 to determine the levels of PCB's. Cleanup activities occurred between May 1, 1998 and May 6, 1998. During this time, three drain structures were removed. The drain to the process sewer at the northeast corner of the treatment pad was removed and the line connecting to the process sewer was plugged. The two drain sumps for the fume scrubber were removed as a unit because they were connected together with a metal brace. One drain sump was found to be open to soil at the bottom. The two structures were resting on an aluminum plate covered with a white encrustation (later determined to be corroded aluminum). All discolored soil was removed and drummed. Sampling of the drummed soil and the soil beneath the aluminum plate was performed.

The reclassification is documented on forms 98-085, 98-086, 98-087, and 98-088.

Code:	3718-F TT2	Classification:	Accepted
Names:	3718-F TT2; 3718-F Treatment Tank 2	Reclassification	Closed Out (8/4/1998)
Type:	Storage Tank	Start Date:	1/1/1968
Status:	Inactive	End Date:	1/1/1998
Description:	<p>The waste site was a component of a Treatment, Storage and Disposal unit that has been Clean Closed. The 3718-F Treatment Tank 2 (3718-F TT2) was a tank used to clean equipment contaminated with alkali metals by reacting the metals with water. It was part of the 3718-F Alkali Metal Treatment and Storage Facility TSD Unit. The RCRA TSD has been Closed Out. The tank has been removed and all that remains is the concrete pad which it shared with other sites related to the 3718-F Alkali Metal Treatment and Storage Facility.</p> <p>3718-T TT2 was a 430-gallon (1,630-liter) tank constructed of 0.3-centimeter (1/8-inch) stainless steel. The tank was topped by a hinged screen cover.</p>		
Location:	<p>The unit was located in the 300 Area, east of the 324 Building. It shared a common fence with the 3717C, 335, 335A, and 336 Buildings. The tank was located on a concrete pad adjacent to the east side of the storage building.</p>		
Related Sites/ Structures:	<p>Structures associated with the unit include the other treatment tank (3718-F TT1), the burn shed and fume scrubber (3718-F BS), and the storage shed (3718-F SF).</p>		
Process Description:	<p>Equipment contaminated with alkali metals was cleaned in a water bath in the tank. The water was only used for small quantities of unconfined alkali metal because of the violence of the reaction. The reaction produced alkali metal hydroxides. Before 1985, solutions from the treatment tanks were drained onto the concrete pad through a valve in the bottom of the tanks. The spent reagents would flow across the pad to the trough and from the trough to the 300 Area Process Sewer. Beginning in 1985, all spent alcohol solutions were packaged in approved containers and handled as dangerous waste. The used water continued to be drained to the process sewer until 1987 when the use of the treatment tanks was discontinued.</p>		
Waste Type:	Chemicals		
Waste Description:	<p>Hazardous wastes are no longer treated in the tank. Wastes treated at the tank included sodium, lithium, and sodium-potassium alloys. Water was used as the cleaning agent and the reaction products were alkali metal hydroxides.</p>		
Closure Info:	<p>Final: All structures associated with the 3718-F Alkali Metal Treatment Facility were removed during September 1996 and May 1998. All that remained was the concrete pad.</p>		

On February 24, 1998 it was agreed that DOE would perform a voluntary action to remove the drainage sump structure with from which the PCB contaminated sample was taken and to conduct soil sampling in the vicinity of the structure. Initial sampling was performed on March 17, 1998 to determine the levels of PCB's. Cleanup activities occurred between May 1, 1998 and May 6, 1998. During this time, three drain structures were removed. The drain to the process sewer at the northeast corner of the treatment pad was removed and the line connecting to the process sewer was plugged. The two drain sumps for the fume scrubber were removed as a unit because they were connected together with a metal brace. One drain sump was found to be open to soil at the bottom. The two structures were resting on an aluminum plate covered with a white encrustation (later determined to be corroded aluminum). All discolored soil was removed and drummed. Sampling of the drummed soil and the soil beneath the aluminum plate was performed.

The reclassification is documented on forms 98-085, 98-086, 98-087, and 98-088.

Code:	3746-D SR	Classification:	Accepted
Names:	3746-D SR; 3746-D Silver Recovery; 3746-D Silver Recovery Process	Reclassification	Rejected (1/27/1999)
Type:	Process Unit/Plant	Start Date:	1/1/1984
Status:	Inactive	End Date:	1/1/1996
Description:	The 3746-D Silver Recovery unit was removed with the demolition of the 3746D Building in 2006 and disposed of at ERDF. The 3746-D Silver Recovery unit was a piece of equipment located inside the 3746-D Building. The electrolytic portion of the silver recovery unit was present, but the ion exchange columns were not. The recovery unit had been inactive. A large white basin drained into the sanitary sewer system and was the only drain in the building. This drain is not part of the 3746-D Silver Recovery waste site.		
Location:	The unit was located inside the 3746-D Building. The 3746-D Building was on the west side of Alaska Street, next to the 3705 Building.		
Related Sites/ Structures:	The unit is associated with the 3746-D Building, and the Lockheed Martin Services, Inc. photo-processing operations.		
Process Description:	The unit was used to recycle corrosive, silver-bearing photochemical wastes generated by Pacific Northwest National Laboratory Photo Processing Operations. Silver-bearing liquid ran through an electrolytic unit to remove the majority of the silver. The depleted liquid ran through an ion exchange column to remove more silver. From 1984 to 1992, process effluent was discharged to the sanitary sewer. During this time period, the effluent was tested against discharge limits. Until 1992, effluent that was within discharge limits was poured down a sanitary drain. From 1992 through September 1996, effluent was shipped off site. The unit has been inactive since October 1, 1996, when Lockheed Martin Services, Inc., took over photographic operations.		
Waste Type:	Chemicals		
Waste Description:	Corrosive silver containing waste photochemicals used to be processed to reclaim silver. During 1993, 7,721 liters (2,040 gallons) of photochemical waste was processed to recover 209.2 kilograms (1,139.686 troy ounces) of silver.		

Code:	400 FD1A	Classification:	Accepted
Names:	400 FD1A; 4717 Reactor Service Building	Reclassification	Rejected (12/15/1998)

HVAC Condensate; Injection Well #1A;
Miscellaneous Stream #14; 400 Area French
Drain 1A

Type: French Drain **Start Date:** 1/1/1979

Status: Active **End Date:**

Description: The unit is a 1.5 meter (5 foot) long, 1.2 meter (4 foot) diameter concrete or vitrified clay pipe filled with gravel. It is in a vegetation-free, gravel covered field south of the 403 Building and cannot be identified visually. The site is not located in a depression or a contaminated area.

Location: The site is located between the 403 and 4703 Buildings, about 10.1 meters (33 feet) west of waste site, WIDS Site Code 400 FD1B.

Related Sites/ Structures: The site is associated with the 4717 Reactor Service Building.

Process Description: The Heating, Ventilation, and Air Conditioning (HVAC) system collects condensate from the air on the coils of the unit. The condensate is collected by the HVAC unit and drained to the french drain.

Waste Type: Water

Waste Description: Reports conflict about effluents received by the unit which may have received demineralizer backwash; Heating, Ventilation, and Air Conditioning (HVAC) system condensate from the 4717 Facility Reactor Service Building; and/or water and detergents. The flow rate is less than 0.038 liters per minute (0.01 gallons per minute).

Code: 400 FD1B **Classification:** Accepted

Names: 400 FD1B; 4703 Building (FFTF Control Building) HVAC Condensate; Injection Well #1B; Miscellaneous Stream #15; 400 Area French Drain 1B **Reclassification:** Rejected (12/15/1998)

Type: French Drain **Start Date:** 1/1/1979

Status: Active **End Date:**

Description: The unit is a 1.5-meter (5-foot) long, 1.2-meter (4-foot) diameter concrete or polyvinyl chloride (PVC) pipe filled with gravel. It is in a vegetation free, gravel covered field and cannot be identified visually. The site is not located in a depression or contaminated area.

Location: The site is located south of the 403 Building and approximately 10 meters (33 feet) east of WIDS Site 400 FD1A.

Related Sites/ Structures: The site is associated with the 4703 Building (FFTF Control Building).

Process Description: The Heating, Ventilation, and Air Conditioning (HVAC) system collects condensate from the air on the coils of the unit. The condensate is collected by the HVAC unit and drained to the french drain.

Waste Type: Water

Waste Description: Reports conflict about effluents discharged to this unit which may receive sump water; Heating, Ventilation, and Air Conditioning (HVAC) condensate from the 4703 Building; and/or water and detergent solutions. The flow rate as less is less than 0.038 liters per minute (0.01 gallons per minute).

Code: 400 FD2 **Classification:** Accepted

Names: 400 FD2; 4621E Building HVAC Condensate and Stormwater; Injection Well #02; Miscellaneous Stream #16; 400 Area French Drain 2 **Reclassification** Rejected (12/15/1998)

Type: French Drain **Start Date:** 1/1/1979

Status: Active **End Date:**

Description: The unit is a 1.5-meter (5-foot) long, 1.2-meter (4-foot) diameter concrete or polyvinyl chloride (PVC) pipe filled with gravel. The above ground portion is a 0.9 meter (3 foot) long, 15.2 centimeter (6 inch) diameter rusted metal pipe capped with a metal plug and surrounded with landscaping rocks and shrubs. The site is not located in a depression or contaminated area.

Location: The site is located 3.05 meters (10 feet) south of 4710 Building and 6.1 meters (20 feet) east of that building's southwest corner. It is 7.6 centimeters (3 inch) north of a paved sidewalk.

Related Sites/ Structures: The site is associated with the 4621E Building.

Process Description: The site receives both stormwater runoff and Heating, Ventilation, and Air Conditioning (HVAC) condensate. The HVAC system collects condensate from the air on the coils of the unit. The condensate is collected by the HVAC unit drained to the french drain.

Waste Type: Water

Waste Description: Reports conflict about effluents discharged to this unit. It may have received stormwater; and Heating, Ventilation, and Air Conditioning (HVAC) system condensate from the 4621E Auxiliary Equipment Building; and/or water and detergent solutions. The "Inventory of Miscellaneous Streams", Revision 3, lists the sources as stormwater and potable water. This document lists the flow rate as less than 0.038 liters per minute (0.01 gallons per minute).

Code: 400 FD3 **Classification:** Accepted

Names: 400 FD3; 408A East Dump Heat Exchanger Stormwater; Injection Well #03; Miscellaneous Stream #17; 400 Area French Drain 3 **Reclassification** Rejected (12/15/1998)

Type: French Drain **Start Date:** 1/1/1979

Status: Active **End Date:**

Description: The unit is a 1.5-meter (5-feet) long, 1.2-meter (4-foot) diameter concrete or vitrified clay pipe filled with gravel. The above ground portion is two rusty metal pipes. One is 0.61 meters (2 feet) long and 8.9 centimeters (3.5 inches) in diameter. The other is 0.91 meters (3 feet) long and 11.4 centimeters (4.5 inches) in diameter. Each pipe is capped with a metal plug. The unit is surrounded by four 1.2-meter (4-foot) high yellow metal posts and is in a gravel-covered, vegetation-free field.

Location: The site is located 14.6 meters (42 feet) east of the southeast corner of the 408-A East Dump Heat Exchanger (DHX) outside the protected area fence.

Waste Type: Stormwater Runoff

Waste Description: The site receives stormwater from the 408-A Dump Heat Exchanger (DHX). The flow rate is less than 0.038 liters per minute (0.01 gallons per minute).

Code: 400 FD4 **Classification:** Accepted

Names: 400 FD4; 491E Heat Transport Building Stormwater and HVAC Condensate; Miscellaneous Stream #18; 400 Area French Drain 4 **Reclassification** Rejected (12/15/1998)

Type: French Drain **Start Date:** 1/1/1979

Status: Active **End Date:**

Description: The unit is a 1.5-meter (5-foot) long, 1.2-meter (4-foot) diameter concrete or vitrified clay pipe filled with gravel. The above ground portion is a 0.91 meter (3 foot) long, 11.4-centimeter (4.5-inch) diameter, rusted metal pipe protruding from the middle of a gravel-covered field. It is surrounded by four 1.2-meter (4-foot) tall yellow metal posts. Each of the posts has had a 20-centimeter (8-inch) diameter PVC (polyvinyl chloride) pipe measuring 2.0 meters (6 feet 8 inches) in length placed over it. The white PVC pipes have been marked with three horizontal, yellow stripes.

Location: The site is located approximately 44 meters (144.3 feet) southeast of the 491-E building and approximately 19 meters (62.3 feet) north of the 4713A building.

Related Sites/ Structures: The site is related to the 491-E Building.

Process Description: The site receives both stormwater runoff and Heating, Ventilation, and Air Conditioning (HVAC) condensate. The HVAC system collects condensate from the air on the coils of the unit. The condensate is collected by the HVAC unit and drained to the french drain.

Waste Type: Water

Waste Description:

Waste Type: Water

Waste Description: Reports conflict about effluents discharged to this unit. It may receive dilute condensate; floor drain effluent and effluent from the 491-E Heat Transport Building consisting of stormwater from the roof of HTS-E, condensate from the building's Heating, Ventilation, and Air Conditioning (HVAC) system, rheostat water, and non-regulated quantities of sodium carbonate. The "Inventory of Miscellaneous Streams", Revision 3, lists the streams as HVAC condensate and storm water. The flow rate is less than 0.038 liters per minute (less than 0.01 gallons) per minute.

Code: 400 FD5 **Classification:** Accepted

Names: 400 FD5; 408 South Building Stormwater and Condensate; Injection Well #05; Miscellaneous Stream #19; 400 Area French Drain 5 **Reclassification** Rejected (12/15/1998)

Type: French Drain **Start Date:** 1/1/1979

Status: Active **End Date:**

Description: The unit is a 1.2-meter (4-foot) diameter 1.5-meter (5-foot) long concrete or polyvinyl chloride (PVC) pipe filled with gravel and located in a gravel and cobble covered field. The visible portion of the unit is two rusted metal stand pipes. On pipe is 38.1-centimeters (15 inches) tall by 11.4 centimeters (4.5 inches) in diameter and the other is 15.2 centimeters (6 inches) tall by 20.3 centimeters (8 inches) in diameter. Surrounding the unit are two 1.2-meter (4-foot) tall

yellow metal posts. Both stand pipes have a metal cap.

Location: The site is located 39.6 meters (130 feet) south of the 408-C West Dump Heat Exchanger (DHX) and southwest of the Reactor Containment Building. This location is on the west side of the 491W Heat Transport Building.

Related Sites/ Structures: The site is related to the 408 South Building and the 491-W Heat Transport Building.

Process Description: The site receives both stormwater runoff and heat exchanger condensate from the 491W Heat Transport Building. The heat exchanger system collects condensate from the air on the coils of the unit. The condensate is collected by the heat exchanger unit and drained to the french drain.

Waste Type: Water

Waste Description: Reports conflict about effluents discharged to the unit, which may receive stormwater; dump heat exchanger effluent; and rheostat water containing non regulated quantities of sodium carbonate from the 408-B Dump Heat Exchanger (DHX) and the 491-W Heat Transport Building; condensate from building air cooling systems, solutions of water and detergent. The "Inventory of Miscellaneous Streams", Revision 3 lists the streams as heat exchanger condensate and stormwater. This document states that this stream receives the heat exchanger condensate formerly routed to Miscellaneous Stream #20 (WIDS Site Code 400 FD6). The document lists the flow rate as less than 0.08 liters per minute (0.02 gallons per minute).

Code: 400 FD6

Classification: Accepted

Names: 400 FD6; 408C West Dump Heat Exchanger Sump Stormwater; Miscellaneous Stream #20; 400 Area French Drain 6

Reclassification: Rejected (12/15/1998)

Type: French Drain

Start Date: 1/1/1979

Status: Inactive

End Date: 1/1/1995

Description: The site was a 1.2-meter (4-foot) diameter, 1.5-meter (5-foot) long, concrete or vitrified clay pipe, filled with gravel and cobble, and located in a gravel and cobble covered field. The above ground portion had three rusted metal pipes, one 0.9 meters (3 feet) tall, one 0.61 meters (2 feet) tall, and the third 0.3 meters (1 foot) tall. All three had metal caps. The unit was surrounded by four 1.2-meter (4-foot) high yellow metal marker posts.

The location of the site is now under the Sodium Storage Facility (Building 402). The site was abandoned in place. The site is not accessible.

Location: The site is located under the 402 building, 24.4 meters (80 feet) south of the 408C West Dump Heat Exchanger (DHX), 34.4 meters (113 feet) west of the 408B South Dump Heat Exchanger (DHX), and 16.8 meters (55 feet) northwest of 400 Area French Drain 5 (WIDS Site Code 400 FD5).

Related Sites/ Structures: The site was associated with the 408C West Dump Heat Exchanger.

Waste Type: Water

Waste Description: Reports conflict about effluents discharged to this unit. It may have received stormwater from the 408-C West Dump Heat Exchanger (DHX), condensate from building air cooling systems, floor drain effluent, and/or other stormwater. The Inventory of Miscellaneous Streams, Revision 3 lists the flow as less than 0.038 liters (0.01 gallons) per minute.

Code: 400 FD7 **Classification:** Accepted

Names: 400 FD7; 453C Switch Gear Pad Stormwater; 4621W Auxiliary Equipment Building HVAC Condensate and Stormwater; Injection Well #07; Miscellaneous Stream #21; Miscellaneous Stream #27; 400 Area French Drain 7 **Reclassification** Rejected (12/15/1998)

Type: French Drain **Start Date:** 1/1/1979

Status: Active **End Date:**

Description: The unit is a 1.5-meter (5-foot) long, 1.2-meter (4-foot) diameter concrete or polyvinyl chloride (PVC) pipe filled with gravel. Drawing H-4-14647 shows the site to be in the middle of a paved area northwest of the Fast Flux Test Facility (FFTF) Reactor Containment Building, south of some water tanks. The unit has a 15.2 centimeter (6 inch) diameter metal pipe with a metal cap at grade in its center. The french drain is not visible from the surface. It is paved over with asphalt. Drawing H-4-152050 show both the 453-C Building and 4621-W Building connected to it by pipelines.

Location: The site is located 15.2 meters (50 feet) north of the 408C West Dump Heat Exchanger (DHX) and on the west side of the 4621W Auxiliary Equipment Building.

Related Sites/ Structures: The site is related to the 453C Switch Gear Pad and the 4621W Auxiliary Equipment Building.

Waste Type: Water

Waste Description: The site receives potable and stormwater from several sources. It receives stormwater from the 453-C Switch Gear Pad; effluent from the 4621W Auxiliary Equipment Building, that includes condensate from Heating, Ventilation, and Air Conditioning (HVAC) coolers, water from roof and floor drains and stormwater. The flow rate for the streams from the 4621W Building is less than 0.038 liters per minute (0.01 gallons per minute). The flow rate for the stormwater runoff from the 453C Switch Gear Pad is less than 0.038 liters per minute (0.01 gallons per minute).

Code: 400 FD8 **Classification:** Accepted

Names: 400 FD8; 4621W Auxiliary Equipment Building HVAC Condensate; Injection Well #08; Miscellaneous Stream #22; 400 Area French Drain 8 **Reclassification** Rejected (12/3/1998)

Type: French Drain **Start Date:** 1/1/1979

Status: Active **End Date:**

Description: The unit is a 1.2-meter (4-foot) diameter, 1.5-meter (5-foot) long concrete or polyvinyl chloride (PVC) pipe filled with gravel. Drawing H-4-14647 shows the site to be located in an asphalt covered area. The site is capped by a 20.3-centimeter (8-inch) diameter metal stand pipe with a metal lid at grade.

Location: The site is located south of the 484 Building, 7.6 meters (25 feet) east and slightly south of the 482B/T-87 Storage Tank. The site is on the southwest side of the 4621W Building.

Related Sites/ Structures: The site is related to the 4621W Auxiliary Equipment Building.

Process Description: The Heating, Ventilation, and Air Conditioning (HVAC) system collects condensate from the air on the coils of the unit. The condensate is collected by the HVAC unit and drained to the french drain.

Waste Type: Water

Waste Description: The site receives Heating, Ventilation, and Air Conditioning (HVAC) condensate from the 4621W Auxiliary Equipment Building. The flow rate is less than 0.038 liters per minute (0.01 gallons per minute).

Code: 400 FD9

Classification: Accepted

Names: 400 FD9; 481 Pumphouse Sanitary Water and Salt Water; Injection Well #09; Miscellaneous Stream #23; 400 Area French Drain 9

Reclassification: Rejected (12/3/1998)

Type: French Drain

Start Date: 1/1/1979

Status: Active

End Date:

Description: The unit consists of a 1.5-meter (5-foot) long, 1.2-meter (4-foot) diameter concrete or vitrified clay pipe filled with gravel. The above grade structure is a rusted metal stand pipe 12.7 centimeters (5 inches) in diameter and 30.5 centimeters (1 foot) tall. It is located in a vegetation free, gravel covered field, and is surrounded by three 1.2-meter (4-foot) tall yellow steel posts.

Location: The site is located approximately 39.6 meters (130 feet) north of the 408-C West Dump Heat Exchanger (DHX) and southwest of the 482A/T-58 and 482B/T-87 Water Tanks.

Related Sites/ Structures: The site is related to the 481 Pumphouse.

Waste Type: Water

Waste Description: The site receives sanitary water from pump seal leaks, and salt water from water softener back flushing from the 481 Pumphouse. The flow rate is less than 0.038 liters per minute (0.01 gallons per minute).

Code: 400 FD10

Classification: Not Accepted

Names: 400 FD10; 482A Building - T-58 Stormwater; Injection Well #10; Miscellaneous Stream #25; 400 Area French Drain 10

Reclassification: None

Type: French Drain

Start Date: 1/1/1979

Status: Active

End Date:

Description: The site is either a concrete or vitrified clay pipe filled with gravel (H-4-14647). The disposal structure is not visible in the field. The drawing (H-4-14647) states that the drywells shall be located in the field so that they are 12.2 meters (40 feet) minimum from the nearest building line and 3.05 meters (10 feet) minimum from utilities and other structures. The pipe (cast iron soil) invert is to the top of the french drain. Connections (elbows) are made with 45 degree laterals. The top of the french drain is covered by a polyethylene sheet and a 5.1-centimeter (2-inch) thick redwood or cedar wooden cover. The feed pipe is a 10.2 centimeter (4 inch) diameter steel pipe (drain line) with metal grate cover that is flush with the surrounding concrete paved area. The feed pipe drain is located at the base of a set of concrete steps leading to the equipment room for the 482A/T-58 Water Storage Tank. The Water Storage Tank is a concrete structure with a subgrade equipment room and concrete steps leading to the equipment room.

Location: The french drain is located 12.2 meters (40 feet) west and slightly north of the 482A/T-58 Water Storage Tank.

Related Sites/ Structures: The site is associated with the 482A/T-58 Water Storage Tank and the equipment room for this same structure. A similar structure exists for the 482B/T-87 Water Storage Tank. The french drain associated with the 482B/T-87 Water Storage Tank is WIDS Site Code 400 FD10A.

Process Description: The site is used to receive stormwater runoff from the storage tank and the floor drain located at the base of the steps leading to the equipment room.

Waste Type: Stormwater Runoff

Waste Description: The site receives stormwater runoff from the 482A/T-58 Water Storage Tank and Equipment Room Structure. The flow rate is less than 0.038 liters (0.01 gallons) per minute.

Code: 400 FD10A **Classification:** Not Accepted

Names: 400 FD10A; 482A Building -T-87 Stormwater; Injection Well #10A; Miscellaneous Stream #24; 400 Area French Drain 10A **Reclassification:** None

Type: French Drain **Start Date:** 1/1/1979

Status: Active **End Date:**

Description: The site is either a concrete or vitrified clay pipe filled with gravel (H-4-14647). The disposal structure is not visible in the field. The drawing (H-4-14647) states that the drywells shall be located in the field so that they are 12.2 meters (40 feet) minimum from the nearest building line and 3.05 meters (10 feet) minimum from utilities and other structures. The pipe (cast iron soil) invert is to the top of the french drain. Connections (elbows) are made with 45 degree laterals. The top of the french drain is covered by a polyethylene sheet and a 5.1 centimeter (2 inch) thick redwood or cedar wooden cover. The feed pipe is a 10.2 centimeter (4 inch) diameter steel pipe (drain line) with metal grate cover that is flush with the surrounding concrete paved area. The feed pipe drain is located at the base of a set of concrete steps leading to the equipment room for the 482B/T-87 Water Storage Tank. The Water Storage Tank is a concrete structure with a subgrade equipment room and concrete steps leading to the equipment room.

Location: The french drain is located 6.4 meters (21 feet) northwest of the 482B/T-87 Water Storage Tank.

Related Sites/ Structures: The site is associated with the 482B/T-87 Water Storage Tank and the equipment room for this same structure. A similar structure exists for the 482A/T-58 Water Storage Tank. The french drain associated with the 482A/T-58 Water Storage Tank is WIDS Site Code 400 FD10.

Process Description: The site is used to receive stormwater runoff from the storage tank and the floor drain located at the base of the steps leading to the equipment room.

Waste Type: Stormwater Runoff

Waste Description: The site receives stormwater runoff from the 482B/T-87 Water Storage Tank and Equipment Room Structure. The flow rate is less than 0.038 liters (0.01 gallons) per minute.

Code: 400 PPSS **Classification:** Accepted

Names: 400 PPSS; 4608 Percolation Pond; 4608B Control Structure and Process Sewer Sampling Site; 4904 Process Sewer Main; 4904 Process Sewer System; 400 Area Process Pond and Sewer System **Reclassification:** None

Type: Pond**Start Date:** 1/1/1979**Status:** Active**End Date:**

Description: This site is the 400 Area Secondary Cooling Water (400 Area Process Sewer). The unit consists of underground piping, a control structure, and two percolation ponds known as 4608B and 4608C. The control structure, located near the 4607 Sanitary Sewer septic tank, is a corrugated metal building. A 30.5 centimeter (12 inch) main pipeline carries effluent from the 400 Area to the control structure, then northeast to the percolation ponds. Five 15.2 centimeter (6 inch) diameter pipes discharge process water from the four contributing facilities (see Process Description) into the main pipe (two pipes from FMEF, and one pipe each from the other three facilities). The ponds are 30.5 meters (100 feet) long, 15.3 meters or 23 meters (50 feet or 75 feet) wide, and 1.2 meters (4 feet) deep. The process sewer pipeline empties into a diversion box that is built into the wall that separates the two ponds. Each pond is connected to the diversion box by a 35.6 centimeter (14 inch) vitrified clay pipe. The ponds are enclosed by an 2.4 meter (8 foot) chain-link fence that has an unlocked, open gate. Each pond appears as a vegetation covered area that is recessed 1.2 to 1.8 meters (4 to 6 feet). The sampling location for the process sewer is contained in the flow metering hut (4608B) located just north of the northern fence line of the 400 Area. The following is a list of source contributors and their status. Numbering/naming conventions, e.g., FMEF-352, 36B, 4M-92-00240/M are specific to facility locations, systems, and Engineering Change Notice/Work Package within the FFTF Complex. Note that some of the original source contributors have been plugged or bermed to prevent cooling water from entering the process sewer. 15 Floor Drain - FMEF-404 36B system drain plugged. 16 Floor Drain - FMEF-238 36B system drain plugged. 17 Floor Drain - FMEF Routed to 36B system. 18 Floor Drain - FMEF-307 36B system drain plugged. 19 Floor Drain - FMEF Routed to 36B system. 20 Floor Drain - FMEF Routed to 36B system. 21 Floor Drain - FMEF 36B system drain plugged. 22 Floor Drain - FMEF Routed to 36B system. 23 Floor Drain - FMEF 36B system plugged by 4M-92-00240/M. 24 Floor Drain - FMEF-204 36B system plugged by 4M-92-00240/M. 25 Floor Drain - FMEF-206 36B system plugged by 4M-92-00240/M. 26 Floor Drain - FMEF Routed to 36B system. 27 Floor Drain - FMEF Routed to 36B system. 28 Floor Drain - FMEF-300 36B system plugged by 4M-92-00240/M. 29-42 Floor Drain - FMEF-352 36B system plugged by 4M-92-00240/M. 44-47 Floor Drain - FMEF Bermed to prevent spills from discharging to process sewer. 49-51 Floor Drain - FMEF Bermed to prevent spills from discharging to process sewer. 60 Equipment Drain Bermed to prevent spills from discharging to process sewer. 62 Floor Drain 0 MASF-HB Drain has been permanently plugged. 63 Floor Drain - MASF-HB Bermed to prevent spills from discharging to process sewer. 64 Air Compressor Cooling Water - MASF-ER Bermed under 4A-92-00065/W. 65 Equipment Drain - MASF-ER Bermed under 4A-92-00065/W. 66 Floor Drain in 481-A A rubber plug has been installed on the drain cover under 4F-92-00940/W. 67 Sanitary Water Pump Leakage - 481-A Drains service pump seal; 4 inch collars have been installed. 68 Equipment Drain - 481-A Drains service pump seal; 4 inch collars have been installed. 69 Equipment Drain - 481-A Drains service pump seal; 4 inch collars have been installed. 70 Janitor Sink - 481-A Drains service pump seal; 4 inch collars have been installed.

Location: The site is located approximately 610 meters (2000 feet) north, northeast of the 400 Area.

Related Sites/Structures: Primarily, the site is associated with underground piping (known as the 4904 Process Sewer System), 4608-B Control Structure and Process Sewer Sampling Station, and two percolation ponds (4608-B and 4608-C).

Process Description: There are four facilities in the 400 Area that contribute to the 400 Area Secondary Cooling Water (400 Area Process Sewer). Fast Flux Test Facility (FFTF) The FFTF is a sodium-cooled test reactor that was used for nuclear research. The reactor's high neutron flux level and neutron energies allowed accelerated testing of fuels and materials. The reactor operated from 1980 to April 1, 1990, when it was ordered into standby status by the U. S. Department of Energy (DOE). In a December 15, 1993 memorandum, the DOE directed its Richland Operations Office to initiate action to place the FFTF in a radiologically and industrially safe

shutdown condition. The processes that contribute to the 400 Area Process Sewer are the auxiliary system cooling towers and a batch discharge. The cooling towers reduce the heat generated in the equipment supporting the FFTF auxiliary systems. There is no contact between the piping of the cooling towers and any radioactive liquid, waste, or nuclear materials in the reactor. Adjacent to the cooling tower pad is a building containing water treatment equipment, water quality monitoring instrumentation, and process control for blowdown valves associated with the cooling towers. This system is adjacent to the reactor containment and service buildings within the 400 Area Property Protection Area. Fuels And Materials Examination Facility (FMEF) The FMEF was designed and constructed as a secure, multistoried structure with the capability of handling low and high exposure radioactive materials. Because of program and funding changes, most of the specialized equipment was never installed and radioactive material has never been introduced into the FMEF. The FMEF currently is used for administrative offices. The processes that contribute to the 400 Area Process Sewer are the auxiliary systems cooling towers and batch discharges from the 36B system and the 36D system. Originally, the 36D system was intended to contain radioactive waste. However, with the change in mission for the FMEF, this system has not been used for holding radioactive waste. Engineering documents have been formally changed to reflect the correct status of the 36D system. The cooling system at the FMEF is also a non-contact cooling water system similar to the unit for the FFTF. Maintenance and Storage Facility (MASF) The MASF, located in the 400 Area Property Protection Area, consists of a main building and a two story service wing. The purpose of MASF is to provide maintenance, repair, and storage areas for radioactive and/or specialized maintenance equipment used in support of the FFTF or other onsite activities. The contributors to the 400 Area Process Sewer are floor and equipment drains located in the bay area. Batch discharges from the large diameter cleaning vessel (LDCV) and bearing cooling water from mitigation pump test runs also are discharged to the process sewer. 481-A Water Pumphouse The 481-A Water Pumphouse was constructed to provide space for a diesel driven fire pump and two sanitary water pumps. An equipment drain associated with sanitary water pump packing leakage contributes to the 400 Area Secondary Cooling Water. The discharges for each facility are described below. Fast Flux Test Facility (FFTF) The FFTF has one continuous discharge from the cooling towers, which is non-contact cooling water, and one batch discharge, which is condensate from the heating and ventilation (H&V) units. The cooling tower continuous stream is composed of tower sump blowdown (for conductivity control) and sump overflow. The cooling towers provide cooling to the Cooling Water System, which in turn provides cooling to the following various auxiliary systems, incontainment chill water system, excontainment chill water system, radioactive argon processing system and contaminated air processing system, Mobiltherm lite cooling system, and the liquid rheostat cooling system. These auxiliary cooling systems, cool systems that directly support operation of the reactor plant, and the interim decay and storage (IDS) vessel and are explained in greater detail in the following. A portion of the sodium contained in the reactor vessel is routed to a cold trap (CT), through the reactor overflow line (part of the reactor sodium level control system), for removal of impurities. The CT is cooled by a sodium potassium eutectic metal (NaK) system that, in turn, is cooled by an oil system containing Mobiltherm lite oil. The Mobiltherm cooling system is cooled by the Cooling Water System. The Mobiltherm cooling system has been drained of oil and the oil has been removed from the site. Cooling water is blocked from the Mobiltherm/cooling water heat exchanger by closed valves. This portion of the cooling water system is no longer active. The reactor is cooled by three liquid sodium loops with each loop consisting of a primary and a secondary loop. Each primary and secondary loop contains a main circulating pump to provide motive force for the liquid sodium coolant. Each pump has a liquid rheostat in series with the field windings to control the speed of the pump. The liquid rheostat contains sodium carbonate (3,407 liters) in a 2 to 3 percent weight solution. Because of the heat generated in the rheostat, the sodium carbonate solution must be cooled. Cooling water is applied to a liquid rheostat/cooling water heat exchanger (one per rheostat) to remove the heat generated during operation. The rheostats are located in air atmosphere cells in the heat transport buildings of FFTF. The rheostats do not come into contact with any form of radioactive contamination or field. The IDS vessel contains liquid

sodium that is circulated to remove the decay heat from expended fuel elements stored in the vessel. The sodium loop is cooled by the NaK loop, which in turn is cooled by a Mobiltherm cooling system. The Mobiltherm cooling system has been drained of oil and the oil has been removed from the site. Cooling water is blocked from the Mobiltherm/cooling water heat exchanger by closed valves. This portion of the cooling water system is no longer active. The radioactive argon processing system (RAPS) processes radioactive argon used a cover gas for the reactor. The contaminated air processing system (CAPS) processes the inert gas (nitrogen) used in cells that contained primary system sodium. The RAPS and CAPS compressors are cooled by the RAPS and CAPS cooling water system. This system removes the heat of compression and motor heat from the compressors. The RAPS and CAPS cooling water system is cooled by the Cooling Water System through the RAPS and CAPS/cooling water heat exchanger. The RAPS and CAPS cooling water system has been shut down, although the system still contains the ethylene glycol/water solution. The inert cells containing primary sodium coolant are cooled by inert gas blowers. The blowers take a suction on the inert cells and discharge the gas through a heat exchanger and return the gas to the cell. Incontainment chill water cools the inert gas blowers, using an ethylene glycol solution. The chill water is 'chilled' by use of Freon cycle chillers. The chillers are cooled by the cooling water system. The cells outside of containment are cooled by various H&V units. The H&V units are cooled by excontainment chill water using an ethylene glycol solution. The chill water is 'chilled' by use of Freon cycle chillers. The chillers are cooled by the cooling water system. All the cooling water systems (A-G) contain a 40 percent solution of ethylene glycol that is routed to the cooling towers. The cooling towers are galvanized steel, closed-loop evaporation cooling through cooling coils in the cooling towers. Water is sprayed over the coils as air is blown up through the cooling coils to the recirculated ethylene glycol solution. The eight cooling towers each have a sump capacity of 7,570 liters (2,000 gallons). The water in the cooling tower sumps is treated chemically with a biocide (Dearborn 702), a microbicide (sodium hypochlorite), and a scale inhibitor (Dearborn 878). Scale formation is created by the increasing concentration of naturally occurring salts (typically calcium carbonate) resulting from the evaporation process of the cooling towers. The electrical conductivity of the water in the sumps is monitored and when the conductivity approaches 1,200 micromhos, automatic valves open to discharge water. This allows the addition of fresh water to lower the conductivity to approximately 900 micromhos. Fuel and Materials Examination Facility (FMEF) The FMEF has four routine contributors, three discharges from the FMEF cooling towers and one from the pressure relief valve drain to the process water supply system in the mechanical contributors, 36B system and the 36D system. The 36D system originally was intended to contain radioactive waste. However, with the change in mission for the FMEF, this system has not been used for its intended purpose. Waste water from the fire testing system and a lunchroom sink are the only discharges to the 36D system. Both systems contain two 22,712 liter tanks, the 36B system tanks are fiberglass and the 36D system tanks are stainless steel. Both systems have overflow systems and recirculating lines. The 36B system can discharge to either the process sewer or the 36D system. A computer automatically shifts valves to the other tank when one tank is full. At this time, a technician secures a sample from the full tank and the sample is analyzed as required in the sampling and analysis plan. With approval of the analysis results, 12,113 liters (maximum of the pumping system) are discharged to the process sewer. The 36D system operates similar to the 36B system except the contents only can be sent to the liquid waste loadout room. Presently, a fire hose is connected to the line in the liquid waste loadout room and the contents are sent to the barrel washer pad, which is connected to the process sewer. Each system would discharge no more than once every three months. The three cooling towers at the FMEF are identical to the cooling towers located at the FFTF and are operated under the same conditions. The same Dearborn chemicals are added to the water in the FFTF and FMEF cooling towers. Maintenance and Storage Facility (MASF) The MASF has one routine contributor to the process sewer from the process equipment room air compressor. Two infrequent contributors are from the LDCV and bearing cooling water from mitigation pump test runs. These vessels currently are being used for the testing of new pumps. Water is added to the LDCV and discharged from the vessel to control the heat

generated by the pumps. Testing occurs on an irregular basis, but no more frequently than once per month. The discharge to the Process Sewer is monitored for radioactive contamination by an online monitor. Should radiation be detected, a diversion valve opens to discharge the process sewer water into the MASF radioactive waste system. The Process Sewer is protected from cross-contamination by a check valve downstream of the diversion valve and by piping elevation differences. The radioactive liquid waste system is a gravity drain system located about 1.22 meters below the process sewer. 481-A Pumphouse The 481-A Pumphouse has one routine contributor associated with water pump packing leakage from the sanitary water pumps. The other drains have moats around the drains to prevent accidental discharge.

Waste Type: Process Effluent

Waste Description: The process sewer, which empties into the process ponds, is for discharge of water from cooling systems and nonsanitary drains and sumps in the 400 Area facilities, including the Fast Flux Test Facility (FFTF). Water from the FFTF and FMEF cooling towers contains nonregulated quantities of algacides and other treatment chemicals, including a biocide (Dearcide 702), a microbicide (sodium hypochlorite), and a softening agent (Dearborn 878). Chemicals used for secondary cooling water testing (Dearborn Code 550, 562, 595, 899, 904) are also present in unregulated quantities. Effluent flow varies from approximately (10 gallons per minute) in winter months to approximately (50 gallons per minute) in peak summer months. The following waste streams are produced from each of the listed processes. Process Name Waste Stream Name 1. FFTF Cooling Water Cooling Water System 2. FMEF Cooling Water Cooling Water System 3. FFTF Containment H & V Moisture Condensate from Ambient Air 4. FMEF Containment H & V Moisture Condensate from Ambient Air 5. Paint Shop Spray Filter Water from H & V 6. MASF Large Diameter Cleaning Vessel Pump Water for Testing of Mitigation Pump 7. MASF Bearing Cooling Water Bearing Cooling Water from Pump Test Runs 8. FMEF Retention Water System 36B 9. FMEF Waste System 36D Notes: The water used in the cooling towers is recycled through the system 2.5 times or until the conductivity reading has reached 1,200 umhos. The chemical containers for the cooling tower treatment are rinsed out and the rinsate is added to the cooling tower sump. The FFTF and FMEF recycle lubricants offsite. The total water usage at the site is 471,232.5 liters per day (124,500 gallons per day) (average) and 727,477 liters per day (192,200 gallons per day) (maximum). The water source is a Hanford Site well designated as a drinking water well (Well 499-S1-8J).

Code: 400 RFD

Classification: Not Accepted

Names: 400 RFD; 400 Area Retired French Drains

Reclassification: None

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The sites cannot be positively described, although most french drains in the 400 area are 1.5 meter (5 foot) long, 1.2 meter (4 foot) diameter concrete or vitrified clay pipes filled with gravel.

Location: The site(s) are purported to be located in various locations within the 400 area.

Waste Type: Water

Waste Description: The retired french drains received unknown amounts of water used during construction for washing components prior to installation. The combined hazardous chemical inventory for the drains reportedly includes 40 kilograms of sodium dichromate. Based on reviews of available technical information, this information has not been substantiated.

Code: 400 RSP

Classification: Accepted

Names: 400 RSP; 400 Area Retired Sanitary Pond

Reclassification: Rejected (12/15/1998)

Type: Pond	Start Date: 1/1/1972
Status: Inactive	End Date: 1/1/1979

Description: This site was one component of a sanitary sewer system that supported the temporary facilities during construction of the FFTF. The site was a sanitary sewer pond that has been backfilled and is not visible. It currently appears as a vegetation-free, cobble-covered area. Originally, the site was 152 meters (500 feet) long and (152 meters) (500 feet) wide. Three square unlabeled manholes that provided access to the sanitary sewer pipelines (now abandoned in place) are located in the area and each manhole is adjacent to two, 0.9 meter (3 foot) high metal posts.

Location: The site is located west of the 4706 building.

Related Sites/ Structures: The site was related to Portable Sanitary Sewage Treatment Plant (retired) (WIDS Site 400-9), sanitary sewer pipelines that remain in place, and retired septic tanks.

Waste Type: Sanitary Sewage

Waste Description: The unit received 45,420 liters (12,000 gallons) per day of aqueous wastes from a portable sanitary sewage treatment plant that was located several hundred feet away from the pond. Nonhazardous sludges were taken offsite for disposal while the plant and pond were operating.

Code: 400 RST	Classification: Accepted
----------------------	---------------------------------

Names: 400 RST; 400 Area Retired Septic Tanks	Reclassification Rejected (1/27/1999)
--	--

Type: Septic Tank	Start Date: 1/1/1979
--------------------------	-----------------------------

Status: Inactive	End Date: 1/1/1983
-------------------------	---------------------------

Description: Three septic tanks are shown on drawing H-4-152051 and are listed as inactive waste disposal units in the Hanford Site Waste Management Units Report. There are no signs to mark the septic tanks. Surface features in the locations indicated on the drawing include two steel manhole covers near the southeast portion of 4702. One lid was partially covered with gravel. It is bolted down in the center and has perforated holes around its perimeter. The second manhole cover is posted with a "Danger: Limited Access, Confined Space, Class II" sign. On the east side of the center wing of 4702 Building is a 0.6 meter (2 foot) square concrete pad with a white 10 centimeter (4 inch) diameter PVC vent pipe protruding from the center. On the west side of the 4702 Building is a steel manhole that is surrounded by four yellow posts. It is also posted with a Confined Space, Class II sign. South of this manhole (on the west side of 4702 Building) is another 0.6 meter (2 foot) square concrete pad with a white 10 centimeter (4 inch) diameter PVC vent pipe protruding from the center.

Location: The tanks are located on the south and west sides of the 4702 Building. The building is surrounded by vegetation-free, cobbles. Two tanks are on the south side of the building and one is on the west side near the northwest corner of 4702. The first tank is located approximately 40 feet (12.2 m) west of the southeast wing of the 4702 building. The second tank is located approximately 5 feet (1.5 m) east of the building's central wing. The third tank is located approximately 5.5 meters (18 feet) west of 4702 and east of the 4734-D building.

Waste Type: Sanitary Sewage

Waste Description: The units received unknown amounts of sanitary wastes from office buildings.

Code: 400 SBT	Classification: Not Accepted
----------------------	-------------------------------------

Names: 400 SBT; Cooling Tower Overflow Trench; 400	Reclassification None
---	------------------------------

Area Retired Sand Bottom Trench; 400 Area
Sand Bottom Trench

Type: Trench **Start Date:** 1/1/1979

Status: Inactive **End Date:**

Description: A concrete-lined trench 61 meters (200 feet) long, 1 meter (3 feet) wide, and 0.3 meters (1 foot) deep, covered with steel grating. The site collects overflow water from the 483 Cooling Tower pad and directs it to the process sewer. There is no known contamination or postings at the site.

Location: The site is located north of the 483 Cooling Tower concrete pad running in an east to west direction. BHI-00012, Rev. 00, Figure 4-34, 300-FF-2 Operable Unit Technical Baseline report, shows the cooling tower overflow trench approximately 0.9 meters (3 feet) from the building.

Related Sites/ Structures: The site is related to the 483 Cooling Towers and process sewer.

Waste Type: Water

Waste Description: The 400 Area Sand Bottom Trench reportedly received an unknown amount of non-hazardous cooling tower blowdown. Site personnel state that the Cooling Tower Overflow Trench continues to receive non-hazardous blowdown, also known as secondary cooling water. Secondary cooling water contains non-regulated quantities of a biocide, a microbicide, and a softening agent. Chemicals used for secondary cooling water testing are also present in non-regulated quantities.

Code: 400 SS **Classification:** Accepted

Names: 400 SS; 4608 Sanitary Sewer; 4608 SS; 400 Area Sanitary Sewer **Reclassification:** Rejected (1/27/1999)

Type: Septic Tank **Start Date:** 1/1/1983

Status: Inactive **End Date:** 1/1/1998

Description: The unit is a septic tank with a 11,355 liter (3000 gallon) capacity. The surface features of the septic tank were two fiberglass manhole covers. One of the manhole covers was posted with a "Danger: Confined Space" sign. The area is covered by vegetation.

Location: The septic tank is located southwest of FMEF and the MO-353 office trailer, outside the security fence. The site is inside (east end) an area enclosed by a light weight post and chain. The chained area measures 30.5 by 36.6 meters (100 feet by 120 feet).

Related Sites/ Structures: The septic system was associated with Trailers MO-353, MO-378, MO-379, and MO-908.

Process Description: The septic system was installed to service the mobile office trailers located south of FMEF, the Fuels and Materials Examination Facility (FMEF).

Waste Type: Sanitary Sewage

Waste Description: Site personnel report the unit may have received waste from the T-100, T-101, T-102, T-103, T-104, T-105, T-106, T-107, T-108, and T-109 trailers. The tank received 2,839 liters (750 gallons) of sanitary waste each day. Effluent from this septic tank was discharged to the 4608 Sanitary Tile Field.

Closure Info: Final: The reclassification to Rejected is documented on form 98-226. The tank was abandoned in place in June 1998. No samples were taken because the tank serviced only office trailers.

Code: 400 STF **Classification:** Accepted

Names: 400 STF; 4608 Sanitary Tile Field; 4608 STF; 400 Area Sanitary Tile Field **Reclassification** Rejected (1/27/1999)

Type: Drain/Tile Field **Start Date:** 1/1/1983

Status: Inactive **End Date:** 1/1/1998

Description: The sanitary tile field is located within and at the west end of a vegetation-covered area that is bounded by steel posts and barricade chain. The 4608 Sanitary Sewer septic tank (400 SS) is on the east end of the chained area. The chained area is posted with a blue-and-white sign that reads "No Vehicles--Septic Field." The tile field has no surface features.

Location: The tile field is located in the southwest corner of the 400 Area, outside the security fence. It is inside an area bounded by light weight post and chain that measures 30.5 meters (100 feet) by 36.6 meters (120 feet).

Related Sites/ Structures: The tile field is associated with the 400 SS septic tank (WIDS Site 400 SS) and the office trailers MO-353, MO-378, MO-379, and MO-908. The mobile office trailers are now unoccupied.

Waste Type: Sanitary Sewage

Waste Description: The unit received liquid wastes from the 4608 Sanitary Sewer septic tank. Site personnel report the tank and tile field may have received wastes from the T-100, T-101, T-102, T-103, T-104, T-105, T-106, T-107, T-108, and T-109 trailers.

Code: 400-1 **Classification:** Accepted

Names: 400-1; 400-1 Dump Site **Reclassification** Rejected (12/15/1998)

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The site is an area of soil mounds containing waste material. The mounds vary in content from backfill material (soil and rocks) to chunks of concrete, red volcanic landscaping rocks, metal piping, rebar, chunks of asphalt, and signs. The mounds are from 0.6 to 1.5 meters (2 to 5 feet) high. Some are partially covered with natural vegetation. The entire site is raised approximately 1.5 meters (5 feet) above the perimeter road that surrounds the 400 Area.

Location: The site is located near the northeast corner of the 400 Area, outside the perimeter fence. It is approximately 69 meters (228 feet) from the fence corner.

Waste Type: Construction Debris

Waste Description: The site contains piles of soil, concrete and rubble, a small amount of miscellaneous materials such as traffic markers and landscape rocks, and a few pieces of concrete asbestos board. Approximately 6 half 208 liter (half 55 gallon) drums (cut in half) are also present.

Code: 400-2 **Classification:** Not Accepted

Names: 400-2; Concrete Batch Plant **Reclassification** None

Type: Process Unit/Plant **Start Date:** 1/1/1972

Status: Inactive **End Date:**

Description: The site is a vegetation-free, cobble-covered area that is surrounded by a 2.4-meter (8-foot) high chain-link fence. A concrete building foundation is located at the southwest corner of the fenced area, with rebar and wooden supports protruding from its surface. Several material staging areas contained raw materials for the concrete production. They are open ended, concrete walled bins, located near the building foundation. There is a metal lined pit inside the fenced area that has been used to train employees to use fire extinguishing equipment.

Location: The site is located just north of the perimeter road that runs along the 400 Area's north side, and east of several railroad tracks.

Related Sites/ Structures: The site was associated with the construction of the FFTF.

Code: 400-3 **Classification:** Not Accepted

Names: 400-3; Miscellaneous Stream #732; 400 Area Drainage Trench; 400 Area Storm Drain Outfall Trench; 400 DT **Reclassification:** None

Type: Trench **Start Date:**

Status: Active **End Date:**

Description: This trench emerges just north of the perimeter road, at the northeast corner of the 400 Area, and travels north-northeast for approximately 90 meters (300 feet). The sides of the trench are covered with cobblestones, and the bottom is covered with cobblestones and sand. At its starting point near the perimeter road, the trench is 9 meters (30 feet) wide and 6 meters (20 feet) deep. There is no obvious end to the trench, as it narrows down and eventually becomes an area of disturbed vegetation.

Location: The trench is located west of the 400-1 dump site, at the northeast corner of the perimeter of the 400 Area.

Waste Type: Stormwater Runoff

Waste Description: Site personnel report that the unit receives storm runoff from various drains throughout the 400 Area. The Inventory of Miscellaneous Streams Report (DOE/RL-95-82) states this trench receives less than 0.038 liters per minute (0.01 gallons per minute) of stormwater runoff.

Code: 400-4 **Classification:** Accepted

Names: 400-4; Suspected Burial Ground (East of FFTF) **Reclassification:** Rejected (12/3/1998)

Type: Burial Ground **Start Date:**

Status: Inactive **End Date:**

Description: The site visit done in 1994 to support the 300-FF-2 Operable Unit Technical Baseline Report indicated the site appeared to possibly be a closed burial ground that had been covered with soil. Large mounds of soil are located on the north side of a flat area that measures approximately 30 by 15 meters (100 by 50 feet). The soil has been mounded approximately 3 to 6 meters (10 to 20 feet) above the surrounding terrain. Vegetation on the mound is sparse. In 1994, some waste, such as a glove and an electrical cable, were partially visible.

Location: The site is located northeast of the 400 Area.

Waste Type: Misc. Trash and Debris

Waste Description: A small amount of visible surface debris. A glove and an electric cable.

Code: 400-5

Classification: Accepted

Names: 400-5; Septic Tank or Cistern

Reclassification: Closed Out (12/3/1998)

Type: Septic Tank

Start Date:

Status: Inactive

End Date:

Description: Prior to 1998, the waste site was concrete pipe that extended approximately two feet above the ground surface. It was located approximately 6 meters (20 feet) north of a building foundation. The pipe had an inside diameter of 0.6 meters (2 feet) with a wooden cover. The pipe was connected to an underground concrete or concrete-lined circular vault. On September 16, 1998, the site was backfilled with sand slurry and posted with Caution tape.

Location: The site is located north of the perimeter road that runs along the north side of the 400 Area, on the outside of the perimeter fence.

Process Description: The 300-FF-2 Technical Baseline report states the vault may have been a septic tank or cistern used in the 1970's during the construction phase of the 400 Area. The Limited Field Investigation Report indicates the adjacent building foundation may have been a testing laboratory for testing concrete cores. The small structure that is also located in this vicinity is assumed to have been a sample preparation and concrete curing room. Remnants of concrete cores were observed around the building foundation and the cistern. At the time the samples were taken, a hose was inside the tank that may have been used to pump out the contents when the operation was abandoned. The floor of the tank contained sand and animal nesting material.

Closure Info: Final: During the 300-FF-2 Limited Field investigation (1995), the site was sampled and a radiological survey was done. No radiological contamination was identified. No metal concentrations were identified and the gross beta values were at background level. On September 16, 1998 the site was filled with sand slurry to complete the closeout of this site, in compliance with state regulations for abandonment of septic tanks. The reclassification is documented on form 98-092.

Code: 400-6

Classification: Accepted

Names: 400-6; Material Dumping Area (North of FFTF);
Material Dumping Area and Building Foundation

Reclassification: Rejected (12/3/1998)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site consists of a building foundation, sidewalks, and construction and demolition debris. The concrete building found is approximately 23 meters (75 feet) long and 7.6 meters (25 feet) wide. A portion of the building remains standing. That portion is made of painted concrete blocks with a corrugated metal roof. The floor slopes to a centered drain. Lumber at the site indicates that the rest of the building may have been of wood construction.

Location: The site is located north of the perimeter road that runs along the north side of the 400 Area, outside the perimeter fence.

Related Sites/Structures: A cistern or septic tank is located within this area, adjacent to the building foundation. It is listed in the WIDS Database as sitecode 400-5.

Process Description: During the 300-FF-2 Limited Field Investigation (1995), a closer inspection of the area determined the building foundation was a testing laboratory for concrete cores. The small structure is assumed to have been a sample preparation and concrete curing room. There are numerous remnants of concrete cores around the area.

Waste Type: Construction Debris

Waste Description: Debris scattered randomly at the site includes glass, metal, bricks, and wood from the building; wooden pallets; chunks of concrete; metal scraps; concrete core samples; and other construction materials. Surplus concrete and asphalt were also poured in an area at the north end of the site.

Code: 400-7

Classification: Accepted

Names: 400-7; 4607 Sanitary Sewer; 4607 Sanitary Sewer Septic Tank; 4607 SS; 4607 SSST

Reclassification: Rejected (1/27/1999)

Type: Septic Tank

Start Date: 1/1/1978

Status: Inactive

End Date: 1/1/1997

Description: The septic tank was pumped out and filled with soil in February 2014. The unit is surrounded by a 2.4 meter (8 foot) high chain-link fence that is topped with three strands of barbed wire. The gate is unlocked and open. The top of a concrete structure had six metal access hatches. The hatches were marked with "Confined Space" signs. The septic tank inlet was a circular, above grade concrete tank. It was located approximately 3 meters (10 feet) from the south end of the concrete structure, just outside of the fence.

Hanford Drawing, H-4-38162, Civil Drawing Index Plot Plan, shows the various components of the system. They are the 4607 Septic Tank (WIDS Site 400-7), 4607 Leaching Field (WIDS Site 400-12), 4607 Sanitary Sewer Lagoon (WIDS Site 400-11). Note that this drawing shows the percolation ponds that belong to the process sewer system (WIDS Site 400 PPSS).

Location: The septic tank is located north of the 400 Area perimeter road, outside the fence. It is just west of the access road to the 4608-B and C Percolation Ponds.

Related Sites/Structures: The site is associated with underground lines, including the 4903 Sanitary Sewer Main, that runs throughout the 400 Area. The 4607 Sanitary Tile Field (WIDS Site 400-12) and the 4607 Sanitary Sewer Lagoon (WIDS Site 400-11) are also associated with this septic tank.

Waste Type: Sanitary Sewage

Waste Description: Site personnel report that this unit receives all sanitary wastes from 400 Area buildings except the wastes from a few trailers serviced by the 4608 Sanitary Sewer. The tank was designed to handle a flow rate of 230,000 liters per day (60,000 gallons per day). Reported flow rates include 23,000,000 liters per year (6,000,000 gallons per year), 57,000 liters per day (15,000 gallons per day), 42,000 to 49,200 liters per day (11,000 to 13,000 gallons per day) of effluent, and 87,400 liters per day (23,100 gallons per day) of "influent and effluent." From 1978 to 1986, effluent was discharged through an underground 20 centimeter (8 inch) PVC pipe to the 4607 Sanitary Tile Field.

Code: 400-8

Classification: Accepted

Names: 400-8; Construction Material Dumping Area (North of FFTF)

Reclassification: Rejected (12/3/1998)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: Currently, the dumping area appears as a field that is a partially covered with vegetation and strewn with debris. The debris consists primarily of construction and demolition waste. There are no boundaries to clearly define the size of the dumping area.

Location: The site is located north of the perimeter road that runs along the 400 Area's north side. It is northwest of the 405 Reactor building.

Related Sites/ Structures: The site was associated with the construction of the FFTF.

Waste Type: Construction Debris

Waste Description: Material dumped at the site includes tires, concrete rubble, metal fencing, rebar, metal grating, sheet metal, piping, and metal scraps.

Code: 400-9 **Classification:** Accepted

Names: 400-9; 400 Area Retired Portable Sanitary Sewer Treatment Plant; 400 RPSSTP **Reclassification:** Rejected (12/3/1998)

Type: Sanitary Sewer **Start Date:** 1/1/1972

Status: Inactive **End Date:** 1/1/1979

Description: The site was a temporary sanitary sewage treatment plant. There is no visible evidence from the surface of the underground lines that remain in place, the removed treatment plant, or the backfilled pond.

Location: The site is located just east of the 4701-C Guard Station site.

Related Sites/ Structures: 400 Area Retired Sanitary Pond and Underground Lines Associated with the 400 Area Retired Portable Sanitary Sewage Treatment Plant.

Waste Type: Sanitary Sewage

Waste Description: Approximately 45,000 liters per day (12,000 gallons per day) of aqueous effluent from the treatment plant was transferred through underground lines to the pond, which was located just west of the current 4706 Building site. An unknown amount of that effluent leaked from sanitary sewer manholes and the outfall prior to late 1975 or early 1976. Nonhazardous sludges from the treatment plant were hauled offsite for disposal.

Code: 400-10 **Classification:** Not Accepted

Names: 400-10; 453B Switch Gear Pad Stormwater; Injection Well #11; Miscellaneous Stream #26; 400 Area French Drain #11; 400 FD11 **Reclassification:** None

Type: French Drain **Start Date:** 1/1/1979

Status: Active **End Date:**

Description: The site is a french drain. The visible portion is a 38 centimeter (15 inch) tall metal pipe, 10 centimeters (4 inches) in diameter. On two sides are 20.32 centimeter (8 inch) tall metal bars that are connected by a cross member. The drain is surrounded by four 1.2 meter (4 foot) tall yellow steel posts and is in the middle of a gravel covered field. The pipe is capped with a metal plug that has a raised square on top.

Location: The drain is located approximately 52.4 meters (172 feet) south of the 408C West Dump Heat Exchanger (DHX), and (21.3 m) west of the 408B South Dump Heat Exchanger (DHX), and

southeast of WIDS Site 400 FD5. This location is west of the 453B switch gear pad and south of the 402 Building.

Related Sites/ Structures: The site is related to the 453-B Switch Gear Pad.

Waste Type: Stormwater Runoff

Waste Description: The unit receives stormwater from the 453-B Switchgear Pad. The flow rate is less than 0.038 liters per minute (0.01 gallons per minute).

Code: 400-11 **Classification:** Accepted

Names: 400-11; 4607 Sanitary Sewer Lagoon; 4607 SSL; 400 Area Wetlands **Reclassification** Rejected (1/27/1999)

Type: Pond **Start Date:** 1/1/1986

Status: Inactive **End Date:** 1/1/1996

Description: The site is a sanitary sewer lagoon that is currently dry. It has been backfilled and vegetated with grasses. The north and west sides are slightly depressed, but the south and east sides slope upward to the surrounding terrain. The adjacent terrain is covered with sagebrush and tumbleweeds. Signs are still present around the perimeter of the lagoon that state "Treated Sewage". Shortly after the 4607 Sanitary Sewer and the 4607 Sanitary Tile Field began operating in 1978, sanitary effluent began surfacing in the location of the drain field and overflowing into a natural depression nearby. In 1986, the drain field failed completely, causing effluent to overflow through a manhole and enter the depression through a drainage ditch. A valve pit diversion box was subsequently installed to divert the waste stream to the natural depression. It became known as the 4607 Sanitary Sewer Lagoon and the 400 Area Wetlands. The lagoon was deepened, a berm was constructed around it. The existing drainage ditch was backfilled.

Location: The lagoon is located northeast of the 4607 Sanitary Sewer septic tank (400-7) and southwest of the 4608-B and C Percolation Ponds (400 PPSS).

Related Sites/ Structures: The lagoon was associated with the 4607 Sanitary Sewer (WIDS Site 400-7), 4607 Sanitary Tile Field (WIDS Site 400-12), and the 4903 Sanitary Sewer Main.

Waste Type: Sanitary Sewage

Waste Description: From 1986 to 1996, all sanitary effluent from the 4607 Sanitary Sewer has been discharged from the septic tank to the lagoon. Reported flow rates include 23,000,000 liters per year (6,000,000 gallons per year) in 1987, 57,000 liters per day (15,000 gallons per day) in 1989, 42,000 to 49,200 liters per day (11,000 gallons per day to 13,000 gallons per day) in 1992, and 87,400 liters per day (23,100 gallons per day) of influent and effluent in 1993. The theoretical combined evapotranspiration and percolation rate of the pond, based upon the 1993 flow rate is 187 liters per square meter per day (4.6 gallons per square foot per day).

Code: 400-12 **Classification:** Accepted

Names: 400-12; 4607 Sanitary Tile Field; 4607 STF; 4608A Leaching Field; 4608A Sanitary Sewer Leaching Field **Reclassification** Rejected (1/27/1999)

Type: Drain/Tile Field **Start Date:** 1/1/1978

Status: Inactive **End Date:** 1/1/1986

Description: There are no visible surface features to identify this tile field. The tile field consisted of perforated 10 centimeter (4 inch) diameter PVC pipe that discharged sanitary effluent by gravity. The pipe sloped 0.25 meters for every 30.5 meters (3 inches for every 100 feet) of length. The tile field was filled with 0.3 meters (3 feet) of gravel and was covered with "untreated building paper." Approximately 490 meters (1,600 feet) of PVC pipe connected the tile field with the 4607 Sanitary Sewer septic tank. Per Curt Clement, Dyncorp, the drain/tile field was abandoned in-place years ago when it originally failed. The tie-in has been plugged.

Location: The tile field was located north of the 400 area, outside the security fence and west of the fenced 400 Area Process Ponds.

Related Sites/ Structures: The tile field is associated with the 4607 Sanitary Sewer (WIDS Site 400-7), 4607 Sanitary Sewer Lagoon (WIDS Site 400-11), and 4903 Sanitary Sewer Main.

Process Description: Effluent discharged from the septic tank through an underground PVC pipe to the 4607 Sanitary Tile Field. Numerous problems were encountered with the tile field. Septic tank effluent repeatedly surfaced in the area of the tile field and overflowed into a natural depression nearby (site code 400-11). In 1986, the drain field failed completely, causing effluent to overflow through a manhole and enter the depression through a drainage ditch. A valve pit diversion box was installed to permanently divert the waste stream to the depression.

Waste Type: Sanitary Sewage

Waste Description: The 4607 Sanitary Sewer received all sanitary wastes from 400 Area buildings except the wastes from a few trailers serviced by the 4608 Sanitary Sewer. Between 1978 and 1986, the tile field received liquid effluent from the 4607 Sanitary Sewer septic tank. The tank may have received effluent at a rate of 23,000,000 liters per year (6,000,000 gallons per year) in 1987, 57,000 liters per day (15,000 gallons per day) in 1989, 42,000 to 49,200 liters per day (11,000 to 13,000 gallons per day) in 1992, and 87,400 liters per day (23,100 gallons per day) in 1993.

Code: 400-13

Classification: Accepted

Names: 400-13; Waste Dumping Site (East of FFTF)

Reclassification: Rejected (12/15/1998)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site is a dumping area. Debris has been dumped in several areas, scattered over an area occupying approximately 1.2 hectares (3 acres). One of the dumping areas was possibly fenced in the past, since two corners are framed by wooden posts with fallen fence rails and chicken-wire fencing.

Location: The site is located northeast of the 400 Area, on the east side of a dirt access road. The unit is accessible by a dirt road that begins at the northeast end of the Fast Flux Test Facility (FFTF) Visitor Center parking lot.

Related Sites/ Structures: The site is believed to be related to the construction of FFTF.

Waste Type: Misc. Trash and Debris

Waste Description: Tree limbs, bags of leaves, and other debris are scattered in several locations along the east side of the dirt access road. Additional areas further away from the road contain fire bricks, black rubber gloves, metal buckets, rusted tin cans, broken glass jars, electrical wiring, metal mesh screening, caulking guns, wood scraps, large chunks of building concrete, semi-circular wooden wall sections, and other waste materials.

Code: 400-14 **Classification:** Accepted
Names: 400-14; Burn Pit (East of FFTF) **Reclassification** Rejected (12/15/1998)
Type: Burn Pit **Start Date:**
Status: Inactive **End Date:**

Description: The 1994 site visit that supported the 300-FF-2 Technical Baseline Report stated the site was a large burn pit containing some visible, fire-scarred debris at the east end. Blown-in tumbleweeds were piled within the pit and some natural vegetation had begun to grow along the pit's walls. The unit's appearance indicated it has not been used for some time.

Location: The site is located northeast of the 400 Area, outside the facility fence. The pit is east and southeast of a waste dumping area (WIDS Site Code 400-13), and is southeast of a suspected burial ground (WIDS Site Code 400-4). The unit is accessible by a dirt road that begins at the northeast end of the Fast Flux Test Facility Visitor Center parking lot.

Waste Type: Misc. Trash and Debris

Waste Description: Fire-scarred metal mesh screening, rags, wood scraps, and fire bricks are visible within the pit, particularly at its east end.

Code: 400-15 **Classification:** Not Accepted
Names: 400-15; Diesel Fuel Tank Fitting Leak **Reclassification** None
Type: Unplanned Release **Start Date:** 1/1/1986
Status: Inactive **End Date:** 1/1/1994

Description: The site was a petroleum unplanned release, discovered during the removal of two fuel tanks 400-FS-40 and 400-FS-4. One tank held diesel fuel and one tank held unleaded gasoline.

Location: The release site is located in the southwest corner of the 400 Area Fire Station (4704-S) parking lot.

Related Sites/ Structures: The site was related to tanks 400-FS-40 and 400-FS-41 and the 400-39 bioremediation pad.

Process Description: The tanks served as unleaded gasoline and diesel fuel storage tanks for the 400 Area fire station. The tanks, which were installed in 1986, were double-wall fiberglass construction. Each had a capacity of 1,892.5 liters (500 gallons). Prior to excavation of the two tanks, a site check was performed, which did not reveal any evidence of surficial contamination. The general condition of the fueling station was clean and appeared to be well maintained. Excavation for removal of the tanks was initiated on 5/9/1994. Removal of the concrete pad covering the tanks revealed hydrocarbon staining around both pump lines. No staining was evident above the tank structures. Inspection of the tanks after removal indicated that the integrity of both tanks was good. In addition, there was no indication from the tank wall surfaces or the soil directly around the tanks that leakage had occurred. Once the tanks were removed, soil samples were collected for laboratory analysis from the tank excavations, the spoils piles, and the soil around the pump piping. Excavation of the soil was initiated by the subcontractor who was removing the storage tanks. This excavation resulted in the removal of the contaminated soil at the site. The soil contamination found under the tanks and pump island were cleaned up and safely stored for later treatment. Soil samples were obtained and sent for independent laboratory analysis. The completion date for this activity was 5/25/1994. By August 1994, the 15.2 meter (50 foot) long and 9.1 meter (30 foot) wide tanks were removed. The excavation pit had been backfilled nearly to grade with clean soil and covered with gravel. All signs, barricades, and piles of soil had been removed.

Waste Type: Oil

Waste Description: Two empty underground tanks were unearthed and moved from this site on May 10, 1994. One of the tanks had held diesel fuel, and the other had held unleaded gasoline. The soil underneath was discovered to have been contaminated with fuel. Approximately, 400 cubic yards of contaminated soil was excavated and removed to a bioremediation pit. Maximum soil concentrations were 4,500 parts per million (milligrams per kilogram) and 660 parts per million (milligrams per kilogram) for diesel and gasoline respectively. The soil sampling results indicated that at a depth of (30 feet), gasoline concentration was less than 20 parts per million and the diesel concentration was less than 50 parts per million. These limits were below the regulatory limits of WAC 173-340. As a result, the hole was backfilled with clean soil.

Code: 400-16

Classification: Accepted

Names: 400-16; 4831 Flammable Storage Facility; 4831 FSF

Reclassification: Rejected (12/3/1998)

Type: Storage

Start Date:

Status: Inactive

End Date:

Description: The unit is a yellow, corrugated metal building and a fenced concrete pad to the south. The pad is 6.1 meters (20 feet) wide and 15.2 meters (50 feet) long, surrounded by a 1.8 meter (6 foot) high chain-link fence with a locked gate. The building is about 6.1 meters (20 feet) high, 6.1 meters (20 feet) wide, and 15.2 meters (50 feet) long. A walk-in door and a roll-up door, located on the south side of the building, allow access from the building to the fenced area.

Location: The building borders a portion of Texas Street's east end, and is south of the 4831 LHWSA.

Process Description: The building is used to store flammable or combustible products, including lubricants and alcohols.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: In 1994, signs indicated that the fenced area contains nonregulated empty drums, nonregulated waste, and used oil. No hazardous chemicals were stored on the outdoor pad. In 1998, all nonregulated waste containers were removed from the outdoor concrete pad. This pad is no longer used for nonregulated waste or empty containers. The building is used to store flammable or combustible products including lubricants and alcohols. On 9/8/1998, the facility and nonregulated waste storage pad were walked down by Mr. T. A. Dillhoff (FFTF Environmental Compliance Officer). There was some rust staining on the concrete pad, but no evidence of any chemical leakage.

Code: 400-17

Classification: Accepted

Names: 400-17; Buried Construction Waste Area; Buried Construction Waste Area #1

Reclassification: Rejected (12/15/1998)

Type: Burial Ground

Start Date: 1/1/1977

Status: Inactive

End Date: 1/1/1979

Description: The site is a burial ground. The area shown on SK-4-81543 as a construction waste burial ground is partially covered by the 4843 Building and the 4843 Laydown Area. There is no visible evidence of a burial ground at this location. Areas surrounding the 4843 facilities appear as vegetation-free, gravel-covered fields.

Location: The site is located northwest of the 451-B Substation and FMEF. It is partially underneath the 4843 Building and the 4843 Laydown Area.

Related Sites/ Structures: The site is associated with the construction of the Fast Flux Test Facility (FFTF).

Waste Type: Construction Debris

Waste Description: Site employees report that construction wastes were buried in this unit from "about 1977" to "about 1979."

Code: 400-18	Classification: Accepted
Names: 400-18; Buried Construction Waste Area; Buried Construction Waste Area #2	Reclassification: Rejected (12/15/1998)
Type: Burial Ground	Start Date: 1/1/1972
Status: Inactive	End Date: 1/1/1974

Description: The site is a burial ground. The area shown on SK-4-81543 as a construction waste burial ground is partially covered by the 4831 Flammable Storage Facility. There is no visible evidence of a burial ground at this location. The area is now a vegetation-free, gravel-covered field.

Location: The site is located northeast of the 451-B Substations and FMEF. It is partially underneath the 4831 Flammable Storage Facility and the 4831 Laydown Hazardous Waste Storage Area (4831 LHWSA).

Related Sites/ Structures: The site is associated with the construction of the Fast Flux Test Facility (FFTF).

Waste Type: Construction Debris

Waste Description: Site employees report that construction wastes were buried in this unit from "about 1972" to "about 1974."

Code: 400-19	Classification: Accepted
Names: 400-19; 400-30; 440 Building 90-Day Waste Accumulation Area; Hazardous Waste Temporary Storage Facility	Reclassification: Rejected (12/15/1998)
Type: Storage Pad (<90 day)	Start Date: 1/1/1993
Status: Active	End Date:

Description: This facility consists of a tan-painted clearspan steel structure on a concrete pad. The structure's south, west, and north sides consist of steel siding, and its east side consists of 2.4 meter (8 feet) high metal chain-link fencing with two locked gates. It has a weather tight, zinc-coated steel roof with skylights and a full length roof vent. A 13 centimeter (5 inch) high and 15 centimeter (6 inch) wide concrete containment berm runs along the east side of the foundation. The facility's southeast corner is a fenced-off area, designated on drawings as a "Spill Cleanup Equipment Area," that is 3.0 meters (10 feet) long and 2.9 meters (9.67 feet) wide. Its concrete floor is raised about 15 centimeters (6 inches) from the building foundation. A section of this area is used to store clean empty drums for use as waste containers.

Location: The site is located south of the 4713-C Building and within the FFTF protected area fence.

Related Sites/ Structures: This unit replaced the 4831 LHWSA in December 1993.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: The 4831 LHWSA was used to stage oils and other hazardous wastes, including solvents and ethylene glycol. Empty drums that had previously held cooling water treatment chemicals, such as the acutely hazardous Endcor 4690, were also staged at the site. The 440 HWTSE (WIDS Site Code 400-19) replaced the 4831 LHWSA as the 400 Area's less-than-90-day storage area for hazardous wastes. In August 1994, the main portion of the facility contained a white box, labeled "Spill Kit," along with wooden crates and metal cabinets. The "Spill Cleanup Equipment Area" contained several 208 liter (55 gallon) drums.

Code: 400-20 **Classification:** Not Accepted

Names: 400-20; Altitude Valve Pit T-58; Miscellaneous Stream #31 **Reclassification:** None

Type: French Drain **Start Date:**

Status: Active **End Date:**

Description: The site was listed as a french drain located under Altitude Valve Pit T-58. This site is the source location for WIDS Site 400 FD10. Stormwater runs into the drain at the bottom of the stairs and is routed to the french drain, 400 FD10.

Location: The Altitude Valve Pit T-58 is located beneath the 482-A Water Storage Tower.

Related Sites/ Structures: The site is associated with 482-A, Water Storage Tank T-58, and WIDS Site 400 FD10.

Code: 400-21 **Classification:** Not Accepted

Names: 400-21; Altitude Valve Pit T-87; Miscellaneous Stream #32 **Reclassification:** None

Type: French Drain **Start Date:**

Status: Active **End Date:**

Description: The site was listed as a french drain located under Altitude Valve Pit T-58. This site is the source location for WIDS Site 400 FD10A. Stormwater runs into the drain at the bottom of the stairs and is routed to the french drain, 400 FD10A.

Location: The Altitude Valve Pit T-87 is located beneath the 482-B Water Storage Tower.

Related Sites/ Structures: The site is associated with the 482-B Water Storage Tower, Water Storage Tank T-87, and WIDS Site 400 FD10A.

Code: 400-22 **Classification:** Not Accepted

Names: 400-22; Altitude Valve Pit T-330 French Drain; Miscellaneous Stream #30 **Reclassification:** None

Type: French Drain **Start Date:**

Status: Active **End Date:**

Description: The site was listed as a french drain located under Altitude Valve Pit T-330. No french drain exists at this location. The waste stream discharges directly to the process sewer. A drain was visually identified by opening the hatch cover and seeing a drain located in the southeast corner

of the pit. Water was observed on the floor of the pit. The site is located within a confined space preventing further description of the site at the time of the inspection.

Location: The 482-C Water Storage Tower and the T-330 Altitude Valve Pit are located north of the 481-A building and west of the 4713-D building.

Related Sites/ Structures: The site is associated with the 482-C Water Storage Tower and the T-330 Water Storage Tank.

Code: 400-23

Classification: Accepted

Names: 400-23; 480-A Pump House French Drain; Miscellaneous Stream #34; Well Pump P-14 French Drain

Reclassification Rejected (12/3/1998)

Type: French Drain

Start Date:

Status: Active

End Date:

Description: The site is a square opening in the concrete floor of the 480-A Pumphouse. The site receives leakage from the P-14 Pump. An open 10.2 centimeters (4 inch) diameter pipe was observed at the bottom of the site. The site was dry at the time of the inspection.

Location: The 480-A pumphouse is located northeast of the 4713-C building, and northwest of the 437 building. The site is located inside the pumphouse.

Related Sites/ Structures: The site is associated with the 480-A Pumphouse, Well 499-SO-8, Pump P-14 and the Water Storage Tanks (T-330, T-87, and T-58). Pump P-16 is associated with WIDS Site Code 400-25, Pump P-15 is associated with WIDS Site Code 400-24, and Pump P-14 is associated with WIDS Site Code 400-23.

Process Description: The 400 Area receives raw water from groundwater wells. Normally, Well 499-S1-8J is the active well that supplies raw water to the water storage tanks (T-330, T-87, T-58). Pump P-16 is associated with Well 499-S1-8J and by changing the valve positions, water can be pumped to any of the three water storage tanks. Groundwater wells, 499-SO-8 and 499-SO-7, and their associated pumps, P-14 and P-15 respectively, serve as backup water supply to the 400 Area.

Waste Type: Water

Waste Description: The french drain receives pump packing leakage from the P-14 well pump. The normal flow rate is 0.038 liters per minute (0.01 gallons per minute).

Code: 400-24

Classification: Accepted

Names: 400-24; Miscellaneous Stream #35; Well Pump P-15 French Drain

Reclassification Rejected (12/3/1998)

Type: French Drain

Start Date:

Status: Active

End Date:

Description: The site is a rectangular opening in the concrete floor of the 480-B Pumphouse. The site receives leakage from the P-15 Pump. An open 10.2 centimeter (4 inch) diameter pipe was observed at the bottom of the site. The site was dry at the time of the inspection.

Location: The site is located inside the 480-B Pumphouse. The 480-B is located northeast of the 437 Building.

Related Sites/ Structures: The site is associated with the 480-B Pumphouse, Well 499-SO-7, Pump P-15 and the Water Storage Tanks (T-330, T-87, and T-58). Pump P-16 is associated with WIDS Site Code 400-25, Pump P-15 is associated with WIDS Site Code 400-24, and Pump P-14 is associated with WIDS Site Code 400-23.

Process Description: The 400 Area receives raw water from groundwater wells. Normally, Well 499-S1-8J is the active well that supplies raw water to the water storage tanks (T-330, T-87, T-58). Pump P-16 is associated with Well 499-S1-8J and by changing the valve positions, water can be pumped to any of the three water storage tanks. Groundwater wells, 499-SO-8 and 499-SO-7, and their associated pumps, P-14 and P-15 respectively, serve as backup water supply to the 400 Area. Pump P-16 is associated with WIDS Site Code 400-25, Pump P-15 is associated with WIDS Site Code 400-24, and Pump P-14 is associated with WIDS Site Code 400-23.

Waste Type: Water

Waste Description: This french drain receives groundwater well water leakage from pump P-15. The flow rate for this french drain is less than 0.038 liters per minute (0.01 gallons per minute).

Code: 400-25 **Classification:** Accepted

Names: 400-25; Miscellaneous Stream #36; Well Pump P-16 French Drain **Reclassification:** Rejected (12/3/1998)

Type: French Drain **Start Date:**

Status: Active **End Date:**

Description: The site is an active french drain constructed of concrete and covered with a steel lid. There is no known contamination at the site, and there were no postings. The site is actively receiving water. The water level in the french drain was 0.46 meters (1.5 feet) deep at the time of the inspection (10/5/1998).

Location: The french drain is located northwest of the 4713-D building and east of the P-16 Pump House.

Related Sites/ Structures: The site is associated with the 480-D Pumphouse, P-16 Pump, Well 499-S1-8J, and the Water Storage Tanks (T-330, T-87, T-58). Pump P-16 is associated with WIDS Site Code 400-25, Pump P-15 is associated with WIDS Site Code 400-24, and Pump P-14 is associated with WIDS Site Code 400-23.

Process Description: The 400 Area receives raw water from groundwater wells. Normally, Well 499-S1-8J is the active well that supplies raw water to the water storage tanks (T-330, T-87, T-58). Pump P-16 is associated with Well 499-S1-8J and by changing the valve positions, water can be pumped to any of the three water storage tanks. Groundwater wells, 499-SO-8 and 499-SO-7, and their associated pumps, P-14 and P-15 respectively, serve as backup water supply to the 400 Area.

Waste Type: Water

Waste Description: The french drain receives groundwater well pump packing leakage from the P-16 pump. The well is used to supply drinking and process water for the 400 Area. The flow rate is less than 0.038 liters per minute (0.01 gallons per minute).

Code: 400-26 **Classification:** Not Accepted

Names: 400-26; 451-A Substation and B/N Plant French Drain **Reclassification:** None

Type: French Drain **Start Date:** 1/1/1979

Status: Active **End Date:**

Description: This site consists of two drains located in the bottom of Electrical Manhole #1. These drains remove stormwater.

Location: Electrical Manhole #1 is located in the southeast corner of the 451 Substation.

Related Sites/ Structures: The site is associated with the 451-A Substation and 400 Area B/N Plant.

Waste Type: Stormwater Runoff

Waste Description: This unit receives intermittent discharges of stormwater from the 451-A Substation and the 400 Area B/N plant. It has a normal flow rate of zero.

Code: 400-28

Classification: Not Accepted

Names: 400-28; FFTF Dichlorodifluoromethane Releases

Reclassification: None

Type: Unplanned Release

Start Date:

Status: Active

End Date:

Description: The sites are "fugitive airborne emissions" from eight centrifugal chiller units at the Fast Flux Test Facility (FFTF). These units are used to provide cooling for personnel and equipment. Each chiller unit contains up to 3,000 pounds of dichlorodifluoromethane.

Release Description: The refrigerant dichlorodifluoromethane, or R-12, has reportedly been released in airborne emissions from the eight chiller units at the Fast Flux Test Facility (FFTF). Approximately, 1000 pounds of refrigerant are released each year (Dahl -1991). In Fiscal Year 1998, the R-12 refrigerant in all eight chillers was replaced with R-134A, which is nonhazardous and non-ozone depleting.

Waste Type: Chemicals

Waste Description: The waste released was dichlorodifluoromethane, R-12, refrigerant. In Fiscal Year 1998, the R-12 refrigerant was replaced by R-134A. This information was reported by the FFTF Technical Point of Contact.

Code: 400-29

Classification: Not Accepted

Names: 400-29; FFTF PCB Containing Transformers

Reclassification: None

Type: Control Structure

Start Date:

Status: Active

End Date:

Description: The sites are the 19 electrical transformers within the Fast Flux Test Facility (FFTF) complex containing polychlorinated biphenyls (PCBs). All of the transformers are/were located within buildings or on the roof of buildings. Five of the transformers have been removed and disposed of in accordance with Toxic Substances Control Act (TSCA) regulations.

Location: All of the 19 transformers were located within the Fast Flux Test Facility (FFTF) Complex. 14 of the transformers remain in place at the FFTF Complex. 5 of the transformers have been removed.

Release Description: Past releases from the transformers "involved limited seepage from sample ports due to improperly installed fittings" (WHC-EP-0475-1). Additionally, some routine operations result in the release of small amounts of PCBs to the environment. The exact locations of the leakage are unknown, and it is unknown whether or not all 19 transformers were involved. WHC-EP-0475-1 states 0.0 pounds as the quantity of chemical released per year for these 19

transformers. All seepage and drips were cleaned up when discovered.

Waste Type: Oil

Waste Description: The waste is transformers containing polychlorinated biphenyl oils (Type is Askarel).

This Site has the Following SubSites:

Code: 400-29:1

Names: 400-29:1; Transformer X-5

Code: 400-29:2

Names: 400-29:2; Transformer X-6

Code: 400-29:3

Names: 400-29:3; Transformer X-7

Code: 400-29:4

Names: 400-29:4; Transformer X-9

Code: 400-29:5

Names: 400-29:5; Transformer X-10

Code: 400-29:6

Names: 400-29:6; Transformer X-11

Code: 400-29:7

Names: 400-29:7; Transformer X-12

Code: 400-29:8

Names: 400-29:8; Transformer X-13

Code: 400-29:9

Names: 400-29:9; Transformer X-14

Code: 400-29:10

Names: 400-29:10; Transformer X-25

Code: 400-29:11

Names: 400-29:11; Transformer X-26

Code: 400-29:12

Names: 400-29:12; Transformer X-28

Code: 400-29:13

Names: 400-29:13; Transformer X-29

Code: 400-29:14

Names: 400-29:14; Transformer X-30

Code: 400-29:15

Names: 400-29:15; Transformer X-59

Code: 400-29:16

Names: 400-29:16; Transformer X-98

Code: 400-29:17

Names: 400-29:17; Transformer X-100

Code: 400-29:18
Names: 400-29:18; Transformer X-101
Code: 400-29:19
Names: 400-29:19; Transformer X-117

Code: 400-29:1
Classification: Not Accepted
Names: 400-29:1; Transformer X-5
Reclassification: None
Type: Control Structure
Start Date:
Status: Active
End Date:

Description: The transformer is located in Room 308 of the 4621E Building, 550 Level.

The SubSite is Part Of:

Code: 400-29
Names: 400-29; FFTF PCB Containing Transformers

Code: 400-29:2
Classification: Not Accepted
Names: 400-29:2; Transformer X-6
Reclassification: None
Type: Control Structure
Start Date:
Status: Active
End Date:

Description: The transformer is located in Room 367 of the 4621W Building, 550 Level.

The SubSite is Part Of:

Code: 400-29
Names: 400-29; FFTF PCB Containing Transformers

Code: 400-29:3
Classification: Not Accepted
Names: 400-29:3; Transformer X-7
Reclassification: None
Type: Control Structure
Start Date:
Status: Active
End Date:

Description: The transformer is located in Room 331 of the 4621E Building, 580 Level.

The SubSite is Part Of:

Code: 400-29
Names: 400-29; FFTF PCB Containing Transformers

Code: 400-29:4
Classification: Not Accepted
Names: 400-29:4; Transformer X-9
Reclassification: None
Type: Control Structure
Start Date:
Status: Active
End Date:

Description: The transformer was located on the Roof of the 4621W Building, 580 Level. This transformer

has been removed.

The SubSite is Part Of:

Code: 400-29

Names: 400-29; FFTF PCB Containing Transformers

Code: 400-29:5

Classification: Not Accepted

Names: 400-29:5; Transformer X-10

Reclassification: None

Type: Control Structure

Start Date:

Status: Active

End Date:

Description: The transformer was located on the Roof of the 4621W Building, 580 Level. This transformer has been removed.

The SubSite is Part Of:

Code: 400-29

Names: 400-29; FFTF PCB Containing Transformers

Code: 400-29:6

Classification: Not Accepted

Names: 400-29:6; Transformer X-11

Reclassification: None

Type: Control Structure

Start Date:

Status: Active

End Date:

Description: The transformer is located in Room 449 of the 491E Building, 580 Level.

The SubSite is Part Of:

Code: 400-29

Names: 400-29; FFTF PCB Containing Transformers

Code: 400-29:7

Classification: Not Accepted

Names: 400-29:7; Transformer X-12

Reclassification: None

Type: Control Structure

Start Date:

Status: Active

End Date:

Description: The transformer is located in Room 452 of the 491W Building, 580 Level.

The SubSite is Part Of:

Code: 400-29

Names: 400-29; FFTF PCB Containing Transformers

Code: 400-29:8

Classification: Not Accepted

Names: 400-29:8; Transformer X-13

Reclassification: None

Type: Control Structure

Start Date:

Status: Active

End Date:

Description: The transformer is located in Room 457 of the 491W Building, 580 Level.

The SubSite is Part Of:

Code: 400-29

Names: 400-29; FFTF PCB Containing Transformers

Code: 400-29:9

Classification: Not Accepted

Names: 400-29:9; Transformer X-14

Reclassification: None

Type: Control Structure

Start Date:

Status: Active

End Date:

Description: The transformer is located on the Roof of the 4621W Building, 580 Level.

The SubSite is Part Of:

Code: 400-29

Names: 400-29; FFTF PCB Containing Transformers

Code: 400-29:10

Classification: Not Accepted

Names: 400-29:10; Transformer X-25

Reclassification: None

Type: Control Structure

Start Date:

Status: Active

End Date:

Description: The transformer is located on the Roof of the 4621W Building, 580 Level.

The SubSite is Part Of:

Code: 400-29

Names: 400-29; FFTF PCB Containing Transformers

Code: 400-29:11

Classification: Not Accepted

Names: 400-29:11; Transformer X-26

Reclassification: None

Type: Control Structure

Start Date:

Status: Active

End Date:

Description: The transformer is located on the Roof of the 4621W Building, 580 Level.

The SubSite is Part Of:

Code: 400-29

Names: 400-29; FFTF PCB Containing Transformers

Code: 400-29:12

Classification: Not Accepted

Names: 400-29:12; Transformer X-28

Reclassification: None

Type: Control Structure

Start Date:

Status: Active

End Date:

Description: The transformer was located in Room 303 of the 4621E Building, 533 Level. This transformer has been removed.

The SubSite is Part Of:

Code: 400-29

Names: 400-29; FFTF PCB Containing Transformers

Code: 400-29:13

Classification: Not Accepted

Names: 400-29:13; Transformer X-29

Reclassification: None

Type: Control Structure

Start Date:

Status: Active

End Date:

Description: The transformer was located in Room 365 of the 4621W Building, 550 Level. This transformer has been removed.

The SubSite is Part Of:

Code: 400-29

Names: 400-29; FFTF PCB Containing Transformers

Code: 400-29:14

Classification: Not Accepted

Names: 400-29:14; Transformer X-30

Reclassification: None

Type: Control Structure

Start Date:

Status: Active

End Date:

Description: The transformer was located in Room 431 of the 491-W Building, 531 Level. This transformer has been removed.

The SubSite is Part Of:

Code: 400-29

Names: 400-29; FFTF PCB Containing Transformers

Code: 400-29:15

Classification: Not Accepted

Names: 400-29:15; Transformer X-59

Reclassification: None

Type: Control Structure

Start Date:

Status: Active

End Date:

Description: The transformer is located in Room 457 of the 491W Building, 580 Level.

The SubSite is Part Of:

Code: 400-29

Names: 400-29; FFTF PCB Containing Transformers

Code: 400-29:16

Classification: Not Accepted

Names: 400-29:16; Transformer X-98

Reclassification: None

Type: Control Structure

Start Date:

Status: Active

End Date:

Description: The transformer is located in Room 457 of the 491W Building, 550 Level.

The SubSite is Part Of:

Code: 400-29

Names: 400-29; FFTF PCB Containing Transformers

Code: 400-29:17

Classification: Not Accepted

Names: 400-29:17; Transformer X-100

Reclassification: None

Type: Control Structure

Start Date:

Status: Active

End Date:

Description: The transformer is located in Room 308 of the 4621E Building, 550 Level.

The SubSite is Part Of:

Code: 400-29

Names: 400-29; FFTF PCB Containing Transformers

Code: 400-29:18

Classification: Not Accepted

Names: 400-29:18; Transformer X-101

Reclassification: None

Type: Control Structure

Start Date:

Status: Active

End Date:

Description: The transformer is located in Room 367 of the 4621W Building, 550 Level.

The SubSite is Part Of:

Code: 400-29

Names: 400-29; FFTF PCB Containing Transformers

Code: 400-29:19

Classification: Not Accepted

Names: 400-29:19; Transformer X-117

Reclassification: None

Type: Control Structure

Start Date:

Status: Active

End Date:

Description: The transformer is located in Room 452 of the 491E Building, 580 Level.

The SubSite is Part Of:

Code: 400-29

Names: 400-29; FFTF PCB Containing Transformers

Code: 400-31

Classification: Accepted

Names: 400-31; 402 Building; Sodium Storage Facility

Reclassification: Closed Out (9/17/2003)

Type: Storage

Start Date:

Status: Inactive**End Date:**

Description: The site was a RCRA permitted storage unit that was never used. The Sodium Storage Facility (SSF) and Sodium Reaction Facility had been a RCRA TSD. The TSD was administratively closed on 9/17/2003. The facility was designed to receive sodium drained from the Fast Flux Test Facility (FFTF) reactor coolant system. The unit consists of three 303,000 liter (80,000 gallon) tanks and one 197,000 liter (52,000 gallon) tank contained within a concrete structure approximately 27.7 meters (91 feet) long by 27.4 meters (90 feet) by 9.1 meters (30 feet) high. The total process design capacity for the four SSF storage tanks will be 1,105,000 liters (292,000 gallons). A secondary containment sump is capable of containing the contents of two of the 303,000 liter (80,000 gallon) tanks. The Sodium Reaction Facility (SRF) portion was not constructed.

Location: The Sodium Storage Facility was constructed southwest of the FFTF Reactor (405 Building). The building is west of the 408B Building (Main Heat Dump, South) and south of the 408C Building (Main Heat Dump, West). The building was built over of the 400 FD6 waste site.

Related Sites/ Structures: The Sodium Storage facility is related to the Fast Flux Test Facility (FFTF) and will be related to the Sodium Reaction Facility (SRF) was not constructed.

Process Description: The SSF was designed to receive liquid sodium containing trace amounts of potassium through batch transfers from FFTF by way of transfer lines connecting the two facilities. The sodium will be stored in the SSF until transferred to the Sodium Reaction Facility (SRF) for treatment.

Closure Info: Final (9/17/2003): The site was a RCRA permitted storage unit that was never used. A letter was sent by the DOE to Ecology on June 12, 2003 requesting to procedurally close the unit. A letter from Ecology to DOE on September 17, 2003 accepted DOE's request. The letters are sufficient to reclassify this site.

Code: 400-32**Classification:** Accepted**Names:** 400-32; Construction Dry Well; U.G. Drywell - North**Reclassification** Rejected (12/3/1998)**Type:** French Drain**Start Date:****Status:** Inactive**End Date:**

Description: The site is a large gravel filled excavation that is labeled on drawing H-4-152051 as "U.G. Drywell". The drywell is a subsurface structure and is not visible at the surface.

Location: The site is located west of the 483 Building.

Related Sites/ Structures: The site was associated with the construction of the Fast Flux Test Facility (FFTF).

Waste Type: Water

Waste Description: The gravel filled excavation was used to dispose of water that collected in the bottom of the 400 Area foundation excavations during construction.

Code: 400-33**Classification:** Accepted**Names:** 400-33; Construction Dry Well; U.G. Drywell - South**Reclassification** Rejected (12/3/1998)**Type:** French Drain**Start Date:****Status:** Inactive**End Date:**

Description: The site is a large gravel filled excavation that is labeled on drawing H-4-152051 as "U.G. Drywell". The dry well is a subsurface structure and is not visible at the surface.

Location: The site is located west of the 408-C Building.

Related Sites/ Structures: The site is associated with the construction of the Fast Flux Test Facility (FFTF).

Waste Type: Water

Waste Description: The gravel filled excavation was used to dispose of water that collected in the bottom of the 400 Area foundation excavations during construction.

Code: 400-34 **Classification:** Not Accepted

Names: 400-34; Miscellaneous Stream #733; Northwest Surface Water Drainage Ditch **Reclassification:** None

Type: Ditch **Start Date:** 1/1/1982

Status: Inactive **End Date:**

Description: A surface water drainage system made of a series of ditches and culverts is shown on drawing H-4-155518 and on H-4-150029. The ditch is shown to be northwest of the 437 building, measuring approximately 700 feet in length and exiting the northwest corner of the 400 Area. It was determined that this drainage ditch was never constructed.

Location: The ditch was supposed to be located outside of the northwest corner of the 400 Area perimeter fence.

Code: 400-35 **Classification:** Not Accepted

Names: 400-35; Miscellaneous Stream #734; Southwest Surface Water Drainage Ditch **Reclassification:** None

Type: Ditch **Start Date:** 1/1/1982

Status: Active **End Date:**

Description: A surface water drainage system exits the southwest section of the 400 Area. This system collects surface water runoff from the area west of the Reactor Area. The system is a series of underground culverts and exposed, cobble ditches. It measures approximately 9829 feet in length. It exits the southwest corner of the reactor, area near the 4790 Patrol Headquarters building, as an underground pipeline. It turns south for approximately 229 meters (750 feet) along Grant Ave. It exists the security fence and runs along the FMEF parking area. It then turns to the west along Alabama Blvd. until it reaches the desert southwest of 400 Area.

Location: This drainage system is located partly inside and partly outside the southwest section of the 400 Area.

Waste Type: Stormwater Runoff

Waste Description: The unit collects storm water runoff from the west section of the 400 Area Reactor Area.

Code: 400-39 **Classification:** Accepted

Names: 400-39; 400 Area Bioremediation Pad; 400 Area Soil Cell **Reclassification** Rejected (11/22/2004)

Type: Surface Impoundment **Start Date:** 1/1/1994

Status: Inactive **End Date:**

Description: The site is a bermed, mound of soil with a visible plastic liner. It is marked with a sign that says Keep Out - Petroleum Contaminated Soil.

Location: The site is located east of the 4704-S building.

Process Description: Remediation of the soil from the diesel tank leak (see sitecode 400-15) was accomplished using aeration/bioremediation in accordance with the June 21, 1994 letter provided by the State of Washington Department of Ecology (Ecology). The contaminated soil was placed in a plastic lined, bermed bioremediation pit, located 61 meters (200 feet) west of the tank excavation site. Fertilizer, water, and bacteria were added to the soil. More fertilizer and water were added daily, and the soil was tilled under for aeration. The bioremediation process was estimated to take 45 to 90 days.

Waste Type: Oil

Waste Description: The bioremediation pad contains petroleum contaminated soil that was found when the fire station fuel tanks 400-FS-40 and 400-FS-41 were removed (see sitecode 400-15).

Code: 400-40 **Classification:** Accepted

Names: 400-40; 403 Building Fuel Storage Facility (FSF); 4718 ISA; 400 Area Interim Storage Area (ISA); 400 Area Waste Management Unit **Reclassification** None

Type: Storage **Start Date:**

Status: Active **End Date:**

Description: The 400 Area Waste Management Unit is considered an active RCRA TSD unit. It consists of two parts. The Fuel Storage Facility (FSF) is a one level reinforced concrete substructure covered by a steel frame, metal sided high bay building. The 400 Area Interim Storage Area (ISA) is a 156 by 75 meter (513 by 247 foot) fenced area with perimeter lighting.

Location: The two parts of the 400 Area Waste Management Unit are located in the northeast portion of the 400 Area. Both are north and east of the reactor building.

Process Description: The 403 Fuel Storage Facility (FSF) is capable of storing various types of mixed waste, but as of the effective date of the Part A Permit, only two steel boxes containing sodium contaminated Core Component Pots (CPP) are stored in the 403 FSF. The concrete pad in the fenced Interim Storage Area had been used for dry cask storage, but will not necessarily be used for storing additional mixed waste management.

This Site has the Following SubSites:

Code: 400-40:1

Names: 400-40:1; 403 Building Fuel Storage Facility

Code: 400-40:2

Names: 400-40:2; 400 Area Interim Storage Area (ISA)

Code: 400-40:1 **Classification:** Accepted

Names: 400-40:1; 403 Building Fuel Storage Facility **Reclassification** None

Type: Storage **Start Date:**

Status: Active **End Date:**

Description: The Fuel Storage Facility (FSF) is a one level reinforced concrete substructure covered by a steel frame, metal sided high bay building.

The SubSite is Part Of:

Code: 400-40

Names: 400-40; 403 Building Fuel Storage Facility (FSF); 4718 ISA; 400 Area Interim Storage Area (ISA); 400 Area Waste Management Unit

Code: 400-40:2 **Classification:** Accepted

Names: 400-40:2; 400 Area Interim Storage Area (ISA) **Reclassification** None

Type: Storage **Start Date:**

Status: Active **End Date:**

Description: The 400 Area Interim Storage Area (ISA) is a 156 by 75 meter (513 by 247 foot) fenced area with perimeter lighting.

The SubSite is Part Of:

Code: 400-40

Names: 400-40; 403 Building Fuel Storage Facility (FSF); 4718 ISA; 400 Area Interim Storage Area (ISA); 400 Area Waste Management Unit

Code: 403 FD **Classification:** Accepted

Names: 403 FD; 403 French Drain; Discharge Point from the 403 Building; Miscellaneous Stream #37; 400 Area Drain Discharge from 403; 400 Area French Drain Discharge from 403 **Reclassification** Rejected (12/15/1998)

Type: Injection/Reverse Well **Start Date:** 1/1/1979

Status: Active **End Date:**

Description: Previously, this discharge point was mistakenly described as a french drain. A 1996 site visit has confirmed that the discharge point is a pipe exiting the northeast side of the 403 Building. The effluent follows an asphalt trough to a drain in the pavement. The pavement drain is part of the 400 Area Stormwater Collection System (reference H-4-38972 and H-4-158520).

Location: The site is located on the east side of the 403 Building, just south of the northeast corner.

Related Sites/ Structures: The site is related to the 403 Building and the 400 Area

Process Description: Heating, Ventilation, and Air Conditioning (HVAC) condensate and other liquids flow to a sump inside the 403 building. A sump pump pumps the liquid through the pipe that exits the building.

Waste Type: Water

Waste Description: The unit may receive, or may have received air washer blowdown, Heating, Ventilation, and Air Conditioning (HVAC) system condensate, and stormwater from the 403 building, as well as janitorial solutions of water and detergents. The site has been removed from the active list of the "Inventory of Miscellaneous Streams", Revision 3, because the site does not discharge to an engineered disposal unit. The site is part of the 400 Area Stormwater Collection System.

Code: 427 HWSA **Classification:** Accepted
Names: 427 HWSA; 427 Building Fuel Cycle Plant **Reclassification:** Rejected (8/15/2013)
 Hazardous Waste Storage Area; 427 Building
 Fuels and Materials Exam. Facility HWSA
Type: Satellite Accumulation Area **Start Date:** 1/1/1985
Status: Inactive **End Date:**

Description: The site has been a 90 Day waste accumulation area. It was reclassified to Closed Out in 1999. In 2013, the reclassification was changed to Rejected, based on the definition that 90 Storage Pads are outside the scope of WIDS. The Reusable Oil and Empty Drum Storage Area was a concrete pad, approximately 9.1 meters (30 feet) long and 4.6 meters (15 feet) wide, surrounded by a 2.1 meter (7 foot) high chain link fence with a locked gate.

Location: The site was located north of the 427 Building and 4.6 meters (15 feet) inside the Fuels and Materials Examination Facility (FMEF) perimeter fence.

Process Description: The area became operational in 1985 to stage oil and lubricants.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: The FMEF hazardous waste engineer indicates the Reusable Oil and Empty Drum Staging Area is used to stage containers of oils and lubricants, as well as empty drums. One report describes the 427 HWSA as a staging area for oils and lubricants. That description fits the Reusable Oil and Empty Drum Staging Area. However, another report states that the 427 HWSA was used as a staging area for ethylene glycol and ammonium hydroxide.

Closure Info: Final: The Hazardous Waste Storage Pod was Closed Out on Reclassification Form 98-173.

Code: 437 MASF **Classification:** Accepted
Names: 437 MASF; 400 Area Maintenance and Storage **Reclassification:** Closed Out (9/11/2003)
 Facility; 437 Maintenance and Storage Facility
Type: Maintenance Shop **Start Date:** 1/1/1982
Status: Active **End Date:**

Description: The RCRA TSD components associated with the 400 Area Maintenance and Storage Facility have been Closed Out. The 437 MASF never managed dangerous and/or mixed waste. A procedural/administrative closure was pursued for this unit.

MASF consists of a main building and a two-story service wing. It is a large concrete and rust-colored corrugated metal siding building (See photo #2). DOE/RL-88-21 shows the Dangerous Waste Permit Application was Closed on 9/11/2003. The MASF WIDS entry was divided into eight subsites.

The above grade portion of the main building is constructed of structural steel shapes. The first 3.05 meters (10 feet) elevation of the above grade exterior walls is made of 30.5 centimeters (12

inch) thick precast concrete panels containing 10.2 centimeters (4 inches) of sandwiched insulation. The remaining exterior walls above the 3.05 meter (10 foot) elevation are steel panels. Roof construction is a factory Mutual Class 1 rated insulated metal deck. The building substructure, including all the below grade cells, is concrete. The building is designed and constructed to seismic Zone 2 requirements and wind pressure of 25 pounds per square foot. The concrete lower exterior building wall panels were established by designed to maintain external radiation levels less than 0.2 mrem/h in accordance with DOE Standards for Radiation Protection (Chapter XI of DOE Order 5480.1).

The main building is divided equally into high and low bay sections with heights of 32 meters (105 feet) and 14.9 meters (49 feet). The entire area within the facility is serviced by a 60 ton overhead bridge crane with a 10 ton auxiliary hoist. The high bay section is serviced by a 200 ton overhead bridge crane with a 25 ton auxiliary hoist and includes repair/maintenance floor space and six below grade shielded cells for specialized storage, sodium cleaning, and maintenance services. The high bay also includes a Cask Decontamination and Maintenance Facility (CDMF) to clean and reconfigure the T-3 Shipping Casks. The low bay section includes storage, staging floor space, and the Decontamination Areas I and II shielded enclosure for low level decontamination of small tools, components, and miscellaneous equipment. The low bay also includes a Contaminated Equipment Repair Shop (CERS) for repair of decontaminated Interim Examination and Maintenance (IEM) Cell components. A 10 ton monorail hoist in the low bay supports the Decontamination Areas for handling components/equipment transported to and from the Decontamination Areas. A Shielded Cell Transfer Cask (SCTC), the SCTC air bearing carriage assembly, and the associated support structure are used for equipment transfers into and out of Decontamination Areas through the 1.01 meter (40 inch) diameter ceiling port. Crane controls for the 200 ton crane, the 60 ton crane and the 10 ton monorail are from individual manual pendants. Protective interlocks are incorporated into the crane control circuits to prevent interference of the 200 ton, 60 ton crane, or the 10 ton hoist.

The two story service wing is physically separated from the main building by a concrete/concrete block structural wall, fire wall, and shield wall. The process equipment room, process control room, personnel support areas, health physics office, and main lobby are located on the first floor of the service wing. Personnel support areas include the monitoring room, clothing issue, change rooms, and lavatories. Two 18,925 liters (5,000 gallon) stainless steel radioactive waste storage tanks are located in a concrete shielded cell beneath the process equipment room.

The second floor of the service wing includes the mechanical equipment room, office space, and lunch/conference room. The mechanical equipment room contains the heating, ventilating, and air conditioning (HVAC) equipment including the air handling unit, return air fan, return air HEPA filters, and the energy recovery unit. The loadout facility, attached to the west end of the service wing is a concrete shielded enclosure that is physically separated from the service wing by a concrete shield wall. The loadout facility is used for the transfer of radioactive liquid waste from the radioactive waste storage tanks to Hanford Site tank cars for transportation to the site disposal facilities.

Support Services include a railroad spur comes from the FFTF west track and extends through the main building, terminating at the north end of the building. A second railroad spur is provided from the loadout facility to the FFTF main track north of the MASF. Separate water supply lines are installed from the 400 Area water system to the building to provide both fire and sanitary water services. All post indicator valves in the fire water supply piping are supervised circuit valves. A 13.8 kV underground feeder and duct bank is installed from Substation 451-B to the MASF outdoor substation transformer which provides a 480/277-V, 3-phase, 4-W, 60 Hz building electrical service. Low voltage drawout switchgear is used for distribution and control of building power. Each power circuit breaker has a solid state tripping

device for either delayed, instantaneous, or ground fault tripping characteristics. Motor loads are fed from a motor control center. Lighting, receptacles, and other loads are fed from panelboards. The facility is surrounded by a grounding grid. All building steel and equipment are connected to the grid. The instrumentation system uses a separate analog system that ties directly into the FFTF analog ground grid. The MASF has a lightning protection system.

Sanitary water and fire protection water are supplied from separate mains to the building. A reduced pressure backflow preventer assembly is installed between the sanitary water and process water systems to protect the sanitary water supply. The sanitary sewer collects effluent waste from the sanitary fixtures and floor drains in the personnel support areas. The process sewer collects nonradioactive liquid from all areas of the facility. The primary source of nonradioactive water discharged to the process sewer is the sodium removal system.

All contaminated liquid waste in the facility is discharged into radioactive liquid waste tanks. The stored radioactive liquid waste is transferred to a railroad tank car in the loadout facility for disposal.

The Heating, Ventilation and Air Conditioning (HVAC) System supports all areas of the facility. The direction of air flow, pressure differentials and duct arrangement minimize the potential spread of contamination or the accumulation of inert gas, and potentially contaminated areas are maintained negative with respect to the outside atmosphere. The MASF HVAC System consists of a supply air system, a return air system, and an exhaust air system. All recirculated air or exhaust air from the facility passes through a bank of HEPA filters, and the filtered air is isokinetically sampled and continuously monitored for radioactive contamination.

Location: The site is located in the northeast corner of the 400 Area, 152 meters (500 feet) north of the Fast Flux Test Facility (FFTF) complex, and west of the railroad track serving the FFTF Reactor Containment Building.

Process Description: MASF is a multipurpose service center that supports the specialized maintenance and storage requirements of the 400 Area facilities. MASF provides the capability for sodium film removal, decontamination, repair, and storage of nonfuel components and hardware for the Fast Flux Test Facility (FFTF), Fuel Storage Facility and other major 400 Area facilities. Work in the MASF included handling items that are radioactive due to neutron activation and items that are contaminated with pyrophoric sodium metal (liquid). Transuranic materials, in the form of fuel, are not permitted in the building.

Waste Type: Chemicals

Waste Description: The chemicals to be handled in MASF are of a typical industrial nature. These include organic acids for decontamination and caustic solutions and inorganic acids for regenerating demineralizer resins. The chemicals will be handled in fume hoods and areas appropriately vented and exhausted through a scrubber, demister, dryer and HEPA filters. Caustic rinse water from sodium cleaning operations will be present in the sodium cleaning vessels and piping systems.

Waste Type: Process Effluent

Waste Description: This facility is currently being used for the decontamination of radioactive and/or sodium contaminated FFTF equipment, the repair of contaminated manipulators from the FFTF Reactor Containment Building, the staging of large pieces of equipment to be stored, repaired, or tested; and the temporary storage of low level radioactive solid and liquid wastes prior to shipment.

Radioactive liquids are generated in the sodium cleaning vessel operation and Decontamination Areas. All radioactive liquids from the cleaning vessels and Decontamination Areas discharge into the radioactive waste tanks. The radioactive liquid in the tank(s) can be transferred to a liquid waste tank car in the shielded loadout facility for disposal. The capability to transfer

radioactive liquids from the cleaning vessels directly to the tank car is also provided. All liquid can be discharged from the tank car through a filter to remove radioactive particles. To minimize the potential for spillage during loadout, overflow lines are provided from the tank car to the radioactive waste tanks. In the event of spillage, a collection basin in the floor also drains back to the waste tanks. The loadout facility is isolated during filling operations to minimize personnel exposure. Personnel exits are located at the north and south ends of the facility for rapid egress if required. The facility is maintained at a negative pressure with respect to the atmosphere to prohibit any inadvertent release of contaminants to the environs. Components or equipment containing a sodium film or small residual deposits of sodium can be transported to MASF for disposition. All sodium wetted components can be handled in inerted casks or containers and stored in inerted vessels in below grade cells. All sodium wetted components can be cleaned prior to repair/maintenance or other disposition.

This Site has the Following SubSites:

Code: 437 MASF:1

Names: 437 MASF:1; HVAC

Code: 437 MASF:2

Names: 437 MASF:2; Protective Systems

Code: 437 MASF:3

Names: 437 MASF:3; Decontamination Areas

Code: 437 MASF:4

Names: 437 MASF:4; Cells

Code: 437 MASF:5

Names: 437 MASF:5; Cask Decontamination and Maintenance Facility

Code: 437 MASF:6

Names: 437 MASF:6; Contaminated Equipment Repair Shop

Code: 437 MASF:7

Names: 437 MASF:7; Loadout Facility

Code: 437 MASF:8

Names: 437 MASF:8; Process Systems

Code: 437 MASF:1

Classification: Accepted

Names: 437 MASF:1; HVAC

Reclassification Closed Out (9/11/2003)

Type: Maintenance Shop

Start Date:

Status: Active

End Date:

Description: This subsite has been Closed Out. The air handling unit (AH-1) provided ventilation and conditioned air throughout the facility. Makeup supply air was provided from the outside through a supply/exhaust air heat exchanger and dust filters to AH-1. Chilled water cooling coils in AH-1 cooled the makeup/recirculated air, as required by the HVAC temperature control system. Heated air is provided by electric heaters installed in individual area supply ducts. The supply fan air was controlled at a constant discharge pressure. In the event of a building static pressure upset, such as open doors or other disturbing conditions, the static pressure sensor modulated the supply fan variable inlet vanes to maintain a constant static pressure in the discharge plenum.

The return air system normally recirculated air from noncontaminated areas and introduces the air to the supply side of AH-1 after passing through a bank of HEPA filters. The return air was

isokinetically sampled and continuously monitored prior to introduction into AH-1. Depending on temperature control demands or smoke/fire alarm conditions, the recirculated air could also be partially or fully exhausted from the facility. A flow-controlling instrumentation circuit modulates the variable inlet vanes in the return air blower as required to maintain the constant return air flow.

The exhaust air system takes exhaust air from the potentially contaminated areas for discharge to the atmosphere through HEPA filtration systems. Two exhaust air blowers (each 100% capacity) are provided in the exhaust system and operate in a lead/standby mode. The exhaust air is maintained at a constant volume flow rate by an air flow control circuit similar to the return air system. Automatic switchover from operating to idle blower is incorporated into the control system in the event of a blower system malfunction to ensure maintaining required negative pressurization in the facility. The exhaust air from Decontamination Areas I and II, CDMF, and process system contaminated vents are passed through a wet scrubber, demister, and dryer that are located upstream from the HEPA filters. Operation of the scrubber/dryer normally will involve evolutions that may produce sodium aerosols. All exhaust air passes through HEPA filters and is isokinetically sampled and continuously monitored for radioactive contamination prior to discharge from the building. Demisters were also provided on the exhaust air ducts in Decontamination Area I and Cask Decontamination and Maintenance Facility (CDMF).

A chilled water system feeds the cooling coils in AH-1 to remove heat from the supply air. The chilled water system consists of an air cooled water chiller with dual refrigerant circuits (each 50% capacity), dual chilled water circulating pumps (100% capacity) and piping, and controls to maintain air temperatures. The system configuration permits the use of one chilled water pump in the operating mode while the other chilled water pump remains on standby. Automatic switchover from the operating to the idle pump is provided in the event of pump or system malfunction. Suitable interlocks prevent the simultaneous operation of heating and cooling systems.

Self-contained HEPA filters, with prefilters, are installed as close as practical to the source of potential contaminants to minimize contamination of duct work. HEPA filters are tested at HEHF prior to installation, in place prior to system operation, and at least every two years thereafter. The HEPA filters are installed as single units or manifolded in filter banks and can be changed out as individual units without shutting down the HVAC System. Differential pressure gages are installed across HEPA filters to indicate filter loading. High differential pressure alarms are located on the HVAC control panel for all HEPA filters in the facility, except the CDMF filters.

The HVAC air flow control panel and temperature control panel are located in the mechanical equipment room. The HVAC air flow control system can be operated in a manual or automatic mode. The temperature control system operates in the automatic mode. Any off-normal condition will alarm at the HVAC control panel and the process control room panel.

All potentially contaminated areas are maintained at a negative pressure with respect to the environment and with respect to adjacent less contaminated areas to minimize the spread of potential contamination. Low range, high sensitivity differential pressure instrumentation provides indication and annunciation to the HVAC control panel, for those areas where contamination potential is greater. In addition, local alarm and indication are provided for those areas of greatest potential for contamination.

Smoke detectors are installed in the HVAC return and in selected exhaust ducts upstream from HEPA filters, and these initiate an alarm at the fire alarm control panel (FACP) if smoke is detected in the HVAC exhaust or return ducts.

In the event of a smoke/fire alarm, the supply fan automatically shuts down. The return air recirculation damper to AH-I closes, and the return air is exhausted from the building. Both the return and exhaust fans will continue to operate to exhaust smoke from the facility.

An indicated radiation level above a preset limit in the return or exhaust duct isokinetic sampling and radiation monitoring system will initiate a visible and audible alarm in the process control room to alert personnel to the off normal condition. An assessment of the cause of the alert alarm condition will be made to determine the need and nature of the required corrective action. In the event that the indicated radiation levels in either the return or exhaust duct exceeds the preset high-alarm limit, the HVAC system supply, return and exhaust fans and dampers will automatically shut down (regardless of smoke/fire alarm conditions) to preclude any potential release of radioactive contamination to the environment or dispersal of contaminants to other areas of the facility. The isokinetic sampling monitor alarm setpoints are established in accordance with applicable requirements. The isokinetic radiation monitoring panel is located in the mechanical equipment room, adjacent to the HVAC control panels.

The SubSite is Part Of:

Code: 437 MASF

Names: 437 MASF; 400 Area Maintenance and Storage Facility; 437 Maintenance and Storage Facility

Code: 437 MASF:2

Classification: Accepted

Names: 437 MASF:2; Protective Systems

Reclassification Closed Out (9/11/2003)

Type: Maintenance Shop

Start Date:

Status: Active

End Date:

Description: This subsite has been Closed Out. The instrumentation control system (ICS) provided integrated control and instrumentation for the process system. The sodium removal, nitrogen, steam, contaminated waste, process water, process sewer, and demineralized water were subsystems of this system. Selected process system components located in administratively controlled areas were monitored and controlled in the process control room. The process control panel had visible and audible alarm annunciators. The process control operator took corrective action for alarm conditions. For key parameters, backup automatic action is initiated if the operator fails to respond to the alarm condition. Alarm windows are grouped by systems to aid the operator in quickly identifying the problem and facilitating corrective action.

The MASF Fire Protection System is designed in accordance with Fire Zone 3, Type II N requirements of the Uniform Building Code. The repair and storage area is classified as a Group B, Division 4 occupancy and the two-story service wing as a Group B, Division 2 occupancy. The wet pipe sprinkler system and fire detection/alarm system are designed and installed in accordance with National Fire Protection Association (NFPA) requirements, for ordinary hazard, Group 2 occupancy. All equipment and devices have the Factory Mutual Engineering Corporation approval or are listed for the use intended by the Underwriters Laboratory, Inc.

Fire Protection System alarm devices are zoned and arranged to provide a local fire alarm and fire zone identification at the fire alarm control panel (FACP). HVAC duct smoke detectors initiate an alarm at the FACP in the event of smoke detection. All FACP alarms are transmitted directly to the Hanford Site central fire station. The system also detects any trouble condition such as an inoperative alarm circuit, a closed post indicator valve or a normal power failure and transmits a trouble signal to the FACP and the central fire station.

Hose stations are installed in the repair and storage area in accordance with NFPA requirements.

Radiation Monitoring System

A radiation monitoring system provides radiation surveillance throughout the facility and alarms in the event of above normal radiation levels. The radiation monitoring system consists of remote area monitors, continuous air monitors, and fixed room air samplers. All liquid and gaseous effluents are monitored to prevent releases of radioactivity to the environment.

The local area gamma-radiation monitors visibly and audibly alarm locally and process radiation monitors alarm in the process control room in the event that radiation levels exceed pre-established radiation limits.

Hand and shoe counters are installed at all established exits from potentially contaminated areas to control the possible spread of contamination to other building areas.

Oxygen-Deficient Atmosphere

The principal inert gas present in the MASF is nitrogen, although an argon inerted component cask or container may be shipped to MASF providing the possibility that argon gas could also be present in the facility. Oxygen deficiency monitors are located in confined areas such as the mechanical service tunnel, Large Diameter Cleaning Vessel (LDCV) cell, test cell, Decontamination Areas I and II, and all stairwells where an oxygen deficient atmosphere might occur. The monitors provide an audible and visible alarm.

HVAC supply and exhaust ducting is arranged to ensure maximum circulation to prevent the accumulation of nitrogen or argon gas in confined areas.

Breathing Air System Alarms

Visible and audible alarms are provided at each breathing air station to indicate low air pressure and compressor trouble. The process control room has audible and visual alarms for low pressure, high compressor temperature and loss of alarm power.

Door Annunciators

Limit switches are located at all exterior personnel doors, with the exception of the main lobby door and the process equipment room personnel door. The limit switches indicate that a door is opened and that the contamination control boundary may have been compromised. The limit switches initiate a visible and audible alarm in the process control room.

Emergency Lighting

Battery powered emergency lights are strategically located throughout facility and in all stairwells and at exits to permit safe egress from the building in the event of a power failure.

The SubSite is Part Of:

Code: 437 MASF

Names: 437 MASF; 400 Area Maintenance and Storage Facility; 437 Maintenance and Storage Facility

Code: 437 MASF:3

Classification: Accepted

Names: 437 MASF:3; Decontamination Areas

Reclassification Closed Out (9/11/2003)

Type: Maintenance Shop

Start Date:

Status: Active

End Date:

Description: This subsite has been Closed Out. The Decontamination Areas shielded enclosures inside the main building contains two separate shielded areas, Decontamination Area I and Decontamination Area II. Surface contaminated articles such as tools, small valves, and mechanical components were cleaned and packaged for storage, disposal, or repair. A 5 ton monorail is provided for material handling in the Decontamination Areas. Operation of the 5 ton monorail in both Decontamination Areas is by radio control.

Decontamination Area I was used for semi-remote or spray cleaning and hands-on spray cleaning of contaminated equipment using hot or cold water, steam, and suitable detergents. Two shield windows were installed in the Decontamination Area I shield walls. Work stations, which include all penetrations necessary for the semi-remote spray cleaning of equipment, are provided at each window location. Access to Area I is through a 1.01 meter (40 inch) diameter port in the ceiling via the Shielded Cell Transfer Cask (SCTC). A 1 ton jib crane and electric hoist are provided on the west wall of Decontamination Area I to relocate equipment to a position clear of the 1.01 meter (40 inch) ceiling port, allowing "turn key" operation. A door from Area II to Area I allows equipment and personnel access.

Interim Examination and Maintenance (IEM) Cell equipment transferred items to and from Decontamination Area I using the SCTC, the SCTC Air Bearing Carriage Assembly, and the associated support structure located outside and over the Decontamination Area I cell. The SCTC consists of a shielded cask, an 8 ton hoist and cover assembly, a gas system for cask inerting and purging, and a closure valve. The SCTC is lifted by an overhead crane from the Maintenance Equipment Transport System to the Air Bearing Carriage Assembly and then moved via the carriage to a position over the Decontamination Area I 1.01 meter (40 inch) diameter ceiling port. The carriage is a platform with four air cushion pads and a control system for the air pads. To support the carriage and the SCTC, a support structure is provided that contains support beams between the overhead crane access area and the Decontamination Area I ceiling port. Area I shielding limits all adjacent areas to the design radiation level of 0.2 mrem/h for a maximum 10 R/h point source deposited on the surface of equipment. This point source approximates a 1 curie cobalt-60 equivalent activity deposit which is the maximum projected source to be handled in Decontamination Area I.

Decontamination Area II provided the necessary services for hands-on cleaning and maintenance operations of small, mildly contaminated parts. A 1.01 meter (40 inch) diameter ceiling port is provided in the ceiling to permit transfer of contaminated articles from the IEM Cell transfer container into Decontamination Area II. This area included a large ultrasonic cleaner, a sink with fume hood, worktable, safety shower, a solid waste compactor, service sink, and floor space for repair, packaging, and unpackaging components. The ultrasonic cleaning tank, worktable, and solid waste compactor were equipped with fume hoods. Hood exhausts discharged into the Area II HVAC exhaust duct. Large equipment double doors and a personnel airlock are also provided for access into Decontamination Area II. Decontamination Area II could process articles with measurable radiation levels up to 20 mrem/hr at 1 foot from the component. This point source approximates a 2 millicurie cobalt-60 equivalent activity deposit on the surface of equipment. As the above analysis showed that this activity was the maximum projected source to be handled in Decontamination Area II, Area II shielding has been designed to maintain the design radiation levels in adjacent areas below the design radiation level of 0.2 mrem/h while processing components/equipment with the above stated radiation levels.

The SubSite is Part Of:

Code: 437 MASF

Names: 437 MASF; 400 Area Maintenance and Storage Facility; 437 Maintenance and Storage Facility

Code: 437 MASF:4

Classification: Accepted

Names: 437 MASF:4; Cells

Reclassification Closed Out (9/11/2003)

Type: Maintenance Shop

Start Date:

Status: Active

End Date:

Description: This subsite has been Closed Out.

The Below Grade Cells inside the high bay are concrete shielded enclosures, approximately 12.5 meters (41 feet) deep. They included two inert vessel cells, a large diameter cleaning vessel (LDCV) cell, a small diameter cleaning vessel (SDCV) cell, and an air and test cell. Equipment was accessed from above by removing the shielded floor plugs used to cover the cells. The 200 ton and 60 ton crane support these cells. The Below Grade Cell shielding maintained the radiation levels below 0.2 mrem/hr radiation to adjacent areas. An analysis was made of the potential FFTF components that might be handled in MASF. The worst case component allowed to be stored or serviced in each cell was an instrument tree in the inert vessel and LDCV cell, six reflectors in the SDCV cell, and an intermediate heat exchanger in the air and test cell. The instrument tree and reflectors experienced a maximum neutron flux from the FFTF core. The Intermediate Heat Exchanger (IHX) was subjected to the maximum corrosion product deposition from the primary coolant loops of the FFTF. Source strengths for these components were provided in the facility design criteria. The maximum allowable radiation levels from the cells to the adjacent areas are 2 mrem/hr in the mechanical service tunnel and below-grade cells and 0.2 mrem/hr in the stairwell and above-grade high-bay area.

The Inert Vessel Cells are constructed of a carbon steel vessel that provided controlled inert storage atmosphere for large sodium-wetted components prior to sodium film removal and for components that have been cleaned, repaired, and are ready for reuse. The Large Diameter Cleaning Vessel (LDCV) and Small Diameter Cleaning Vessel (SDCV) cells were the cleaning vessels for sodium film removal from sodium-wetted components. The LDCV and SDCV cleaning vessel design pressures are 20 psig. The vessels have been designed and fabricated to the ASME Boiler and Pressure Vessel Code. The LDCV has been hydrotested to 43 psig. The SDCV has been hydrotested to 30 psig.

The Air and Test Cell provided an area for maintenance and storage of large components, such as a primary pump, secondary pump, or an intermediate heat exchanger, after sodium removal.

The Radioactive Waste Tank Cell was a shielded concrete enclosure located beneath the process equipment room. The cell contains two 18,925 liters (5,000 gallons) stainless steel tanks for the storage of radioactive liquid waste. The tanks were tested in accordance with the ASME Boiler and pressure Vessel Code, Section VIII, Division 1. Design pressure of the tanks is 45 psig; hydrostatic test pressure is 67.5 psig. The cell shielding is based on the maximum source strength of the radioactive liquid stored in the tanks and has been designed to maintain the radiation levels in the process equipment room below the design radiation level of 0.2 mrem/hr. The source strength used in the design calculation is provided in the facility design criteria.

The SubSite is Part Of:

Code: 437 MASF

Names: 437 MASF; 400 Area Maintenance and Storage Facility; 437 Maintenance and Storage Facility

Code: 437 MASF:5

Classification: Accepted

Names: 437 MASF:5; Cask Decontamination and Maintenance Facility

Reclassification Closed Out (9/11/2003)

Type: Maintenance Shop

Start Date:

Status: Active**End Date:**

Description: This subsite has been Closed Out. The Cask Decontamination and Maintenance Facility (CDMF) was an unshielded, air atmosphere glovebox located inside the high-bay area. The CDMF operated at a negative pressure with a once-through HEPA filtered air flow. The CDMF provided radiological containment for cleaning operations and inspections under T-3 Cask's license. Both supply and exhaust air was filtered.

Hands-on decontamination was done inside the glovebox enclosure using a water rinse system and special cask unloading, scraping, and inspection tools. The rinse water from the T-3 Cask was filtered in the CDMF adapter before it entered the Contaminated Liquid Waste System. The CDMF was serviced by a small 1/4 ton bridge crane and electric hoist that comply with all requirements for Hanford hoisting and rigging. CDMF was fabricated and helium-leak tested per HWS-12111, Amendment 1. The glovebox was equipped with an alarm for loss of negative pressure and a fire detector.

The SubSite is Part Of:**Code:** 437 MASF**Names:** 437 MASF; 400 Area Maintenance and Storage Facility; 437 Maintenance and Storage Facility**Code:** 437 MASF:6**Classification:** Accepted**Names:** 437 MASF:6; Contaminated Equipment Repair Shop**Reclassification** Closed Out (9/11/2003)**Type:** Maintenance Shop**Start Date:****Status:** Active**End Date:**

Description: This subsite has been Closed Out. The Contaminated Equipment Repair Shop (CERS) provided the necessary services for hands-on repair and maintenance operations of Interim Examination and Maintenance (IEM) Cell components that had been decontaminated. The CERS is located in the low bay area and is operated at a negative pressure. The shop contained work tables and maintenance tools and is equipped with an overhead sprinkler system. The work tables had local HVAC exhaust drops. A 1 ton monorail and electric hoist services the CERS work tables and a 4 ton electric hoist was housed in a penthouse on the roof of the CERS.

The CERS was accessed through two large equipment doors and a personnel airlock. A ceiling equipment access hatch is also provided. A pair of seal tubes over the large double doors were used for manipulator retesting. Electrical penetrations are provided for contaminated IEM Cell TV equipment repair.

The SubSite is Part Of:**Code:** 437 MASF**Names:** 437 MASF; 400 Area Maintenance and Storage Facility; 437 Maintenance and Storage Facility**Code:** 437 MASF:7**Classification:** Accepted**Names:** 437 MASF:7; Loadout Facility**Reclassification** Closed Out (9/11/2003)**Type:** Maintenance Shop**Start Date:****Status:** Active**End Date:**

Description: This subsite has been Closed Out. The loadout facility is a concrete shielded enclosure that

could accommodate the FFTF and Hanford Site tank rail cars for transfer and disposal of the radioactive liquid waste stored in the radioactive storage tanks. The shielding was designed to maintain the design radiation level of 0.1 mrem/h external to the facility and 0.2 mrem/h in the process equipment room. The shielding calculations used the maximum source strength in a 75,700 liters (20,000 gallon) tank car, as defined in the facility design criteria.

The SubSite is Part Of:

Code: 437 MASF

Names: 437 MASF; 400 Area Maintenance and Storage Facility; 437 Maintenance and Storage Facility

Code: 437 MASF:8

Classification: Accepted

Names: 437 MASF:8; Process Systems

Reclassification Closed Out (9/11/2003)

Type: Maintenance Shop

Start Date:

Status: Active

End Date:

Description: This subsite has been Closed Out. The sodium removal system consisted of the large diameter and small diameter cleaning vessels, fluid/gas supply systems, a vacuum pumping system, water recirculation system, gas recirculation system, and drain and vent systems. Because of the piping system design, only one cleaning vessel could be used at any one time.

The cleaning process consisted of recirculating a water vapor/nitrogen mixture (WVN) while venting gas to remove hydrogen. The reaction rate was controlled by monitoring the hydrogen concentration and adjusting the steam concentration as required to maintain the sodium reaction. The WVN process was continued until the moist circulating gas has completely reacted with the sodium film, as indicated by the hydrogen analyzer. The WVN process was then discontinued, and the vessel was slowly filled with hot demineralized water while the N₂ flow continued and the hydrogen gas was monitored. After a suitable recirculation period, the water was drained, followed by additional rinses as required to ensure that all sodium hydroxide had been rinsed from the item, as indicated by the pH meter. A two-stage filter, with a removal efficiency of 98% (for 0.5 millimeter particles) was included in the water recirculation system to remove radioactive particulate contaminants from the circulating water. After completion of the rinse cycle, the article was dried by recirculating warm dry nitrogen through the system. The gas recirculation system included a gas cooler to remove moisture and a gas heater to reheat the gas to system temperature. The vessel could also be partially evacuated to facilitate the removal of moisture from the, component.

Because of the small volume of the SDCV, the gas phase was a single pass through the vessel and through the scrubber/demister, dryer, and HEPA filters to the HVAC exhaust.

A two stage filter in the water recirculation system is installed in a separate shielded enclosure in the LDCV cell. The expected maximum radiator level of the filter is 80 rem/h within the shielded enclosure. The entire filter assembly, including filter housing, is designed for remote disconnection and removal from the system. Filter piping connections are remotely operated, band type connections and valves are provided with reach rods to permit all required filter removal operations external to the shield enclosure. The filter removal from the enclosure will be accomplished using the FFTF solid waste cask (equipped with electrically operated internal grapple). After filter removal, filter replacement is manually accomplished in the shielded enclosure.

Gas Analyzer System

A gas analyzer system is provided to monitor oxygen, hydrogen, and moisture during the

sodium cleaning process.

The gas analyzer monitors the oxygen concentration in the cleaning vessel to ensure an inert atmosphere for sodium-wetted components and detects any air in-leakage to the vessels. The oxygen analyzer is capable of detecting oxygen concentrations of <0.25% to 5% by volume. At a preset high oxygen concentration limit, the flow of steam is automatically cut off, and additional nitrogen is introduced until the oxygen concentration is within specification.

The gas analyzer monitors the hydrogen concentration to control the sodium removal process and to protect against potentially explosive concentrations in the cleaning vessels. The gas analyzer is capable of detecting hydrogen concentrations in the range of <0.25% to 5% by volume. At a preset high hydrogen concentration limit, steam flow automatically stops and full nitrogen flow is initiated.

The gas analyzer monitors the moisture concentration of both the nitrogen/steam injection and the process system nitrogen gas to control reaction rates and to indicate the end point of the drying process. The instrument is capable of detecting and indicating moisture concentrations in the range of 0.5% to 25% by volume. The instrument indication is used to control the nitrogen/steam ratio and to monitor the drying process.

Process Sewer

Nonradioactive process water from the cleaning vessel is pumped directly to the process sewer. The water is monitored for pH and radioactivity in the sodium cleaning system prior to discharge to the process sewer. Additionally, a liquid monitor in the process sewer system continually checks the discharged water for radioactivity. A removable spoolpiece is provided as a cross connect to the contaminated liquid waste system. The spoolpiece is only installed when the discharge water meets the requirements of the concentration guides in DOE Order 5480.1, Chapter XI. In the event that the discharge water does not meet minimum standards for draining to the process sewer, the water will be automatically diverted to the radioactive waste tanks.

Contaminated Liquid Waste System/Contaminated Gas Vent System

All contaminated liquid waste will be discharged directly to the radioactive waste tanks. During discharge of contaminated liquid waste to the radioactive waste tanks, the removable spoolpiece (cross-connect between the process sewer and the contaminated liquid waste system) is removed to prevent potential release of contaminated liquid waste to the process sewer. Pipe connections are blanked off with blind flanges when the spool piece is not installed.

The contaminated liquid waste in the radioactive waste storage tanks is pumped directly to a railroad tank car in the loadout facility for transport to an appropriate disposal area. All major contamination sources are filtered prior to entering the Contaminated Liquid Waste System. The ultrasonic cleaner in Decontamination Area II has a 20 micrometer in line cartridge filter. The floor drains in Decontamination Areas I and II have 50 micrometer cloth bag filters in metal strainer baskets. The adapter drain basket on the Cask Decontamination and Maintenance Facility has a polyester filter pad insert. These filters minimize the contamination buildup in the Contaminated Liquid Waste System drain lines and storage tanks. In addition, the storage tanks can be flushed and recirculated during the loadout operation to minimize radiation buildup in the tank cell.

All contaminated gas is vented through a scrubber/demister/ dryer and HEPA filter system prior to release to the atmosphere.

The SubSite is Part Of:

Code: 437 MASF
Names: 437 MASF; 400 Area Maintenance and Storage Facility; 437 Maintenance and Storage Facility

Code: 4713-B FD **Classification:** Accepted
Names: 4713-B FD; 4713-B French Drain; Miscellaneous Stream #33 **Reclassification:** Rejected (12/3/1998)
Type: French Drain **Start Date:** 1/1/1979
Status: Active **End Date:**

Description: The unit is a pipe that is 1.5 meters (5 feet) long and 61 centimeters (24 inches) in diameter. The pipe is constructed of concrete and is filled with gravel. The pipe is buried vertically, extends above grade 15.2 centimeters (6 inches) and is covered by a metal grating. Three parallel metal pipes emerge horizontally from the east side of the 4713 Building, then bend 90 degrees downward and end approximately 0.3 meters (1 foot) above the metal grating.

Location: The site is located about 1.22 meters (4 feet) east of 4713B.

Related Sites/ Structures: The site is related to the 4713B Protected Area Maintenance Building.

Process Description: The site is associated with waste water discharges (miscellaneous stream #33) from the 4713B Maintenance Building. In 1996, the sink was disabled to prevent discharge of gray water (waste water excluding sewage) to the french drain. Remaining inputs are infrequent discharges from the 4713B fire sprinkler system and eyewash station.

Waste Type: Water

Waste Description: In 1987, the site received approximately 3,785 liters (1,000 gallons) of waste water from lunchroom sinks. In 1988, the french drain received only intermittent discharges and had a normal flow rate of zero. The "Inventory of Miscellaneous Streams", Revision 3, states that the employee sink water and drinking fountain supply have been shut off. The eyewash station is still an active source. Routine maintenance discharges will be covered under ST 4508 (when it is approved by Ecology). The current flow rate (1998) is less than 0.038 liters (0.01 gallons) per minute.

Code: 4713-B HWSA **Classification:** Accepted
Names: 4713-B HWSA; 4713-B Hazardous Waste Storage Area **Reclassification:** Rejected (12/3/1998)
Type: Storage Pad (<90 day) **Start Date:** 1/1/1980
Status: Active **End Date:** 1/1/1993

Description: The site consists of a 6.1 meters (20 foot) long and 6.1 meters (20 foot) wide concrete pad that is used as a satellite accumulation area. Metal cabinets, 208 liter (55 gallon) drums and a wooden storage box were located on the pad in May, 1994.

Location: The site is located on the west side of the 4713-B building mechanical shop on a 6.1 meters by 6.1 meters (20 foot by 20 foot) concrete pad (source: 7/17/1996 Telecon between MS Watson and A Hill - not available).

Related Sites/ Structures: The site is associated with the 4713B Maintenance Building.

Waste Type: Misc. Trash and Debris

Waste Description: The site was used as an accumulation area to store waste in cabinets and drums. The wastes were small quantity items related to FFTF maintenance activities. Wastes included fluorescent bulbs, incandescent bulbs, mercury vapor lamps, hazardous rags, solvents, suspected PCB-containing ballasts and capacitors, non PCB containing ballasts and capacitors, persistent carcinogens, and printed circuit boards, and miscellaneous equipment.

Code: 4713-B LDFD **Classification:** Accepted
Names: 4713-B LDFD; 4713-B Loading Dock French Drain; Miscellaneous Stream #469 **Reclassification:** Rejected (12/3/1998)

Type: French Drain **Start Date:**

Status: Active **End Date:**

Description: The site is a circular metal grate located in an asphalt paved area east of the 4713-B loading dock. The site sits in a small depression. The site appears to be a stormwater access point to the 400 Area surface drainage system. It does not appear to be a ground disposal site.

Location: The site is located about 23 meters (75 feet) east of the 4713-B building.

Waste Type: Stormwater Runoff

Waste Description: The current "Inventory of Miscellaneous Streams", Revision 3 states that the site collects stormwater and discharges it to the 400 Area stormwater collection system. The current flow rate is less than 1.9 liters per minute (0.50 gallons per minute). Earlier documents, Low Volume Effluent Streams report (Milikan 1988) and the Inventory of Miscellaneous Streams Report (WHC 1993 and DOE/RL-95-82), have stated it receives cooling water from welding equipment or sink water. This earlier data may actually refer to WIDS Site 4713-B FD.

Code: 4721 FD **Classification:** Accepted
Names: 4721 FD; 4721 French Drain; Miscellaneous Stream #28; 400 Area French Drain Discharge from 4721 Building **Reclassification:** Rejected (12/3/1998)

Type: French Drain **Start Date:** 1/1/1979

Status: Active **End Date:**

Description: The unit is a 1.2 meter (4 foot) diameter, 1.5 meter (5 foot) long concrete or vitrified clay pipe filled with gravel. The unit is below grade and cannot be identified visually at the location identified in the "Inventory of Miscellaneous Streams".

Location: The site is located west of the 4721 building in a gravel covered area.

Related Sites/Structures: The french drain is connected to the 4721 Building. This facility is also called the FFTF Emergency Generator Facility or Gas Turbine Building.

Waste Type: Water

Waste Description: The unit may have received janitorial solutions of water and detergents. The "Inventory of Miscellaneous Streams", Revision 3, states that the site routes stormwater from floor drains to an injection well on the west side of the building. The flow rate is less than 0.038 liters per minute (0.01 gallons per minute).

Waste Type: Oil

Waste Description: If a spill occurred during generator operations, the unit might have received diesel oil. Because oil had to be pumped up to the generator from the underground storage tank, spills should not have occurred when the system was not operating. There are no known spills.

Code: 4722 PSHWSA **Classification:** Accepted
Names: 4722 PSHWSA; 4722-C Hazardous Waste Storage Area; 4722 Paint Shop Hazardous Waste Storage Area; 4722 Paint Shop HWSA **Reclassification:** Rejected (1/27/1999)
Type: Storage Pad (<90 day) **Start Date:** 1/1/1980
Status: Active **End Date:**

Description: The Hazardous Waste Storage Area is three metal cabinets that are located on a curbed, concrete pad outside the 4722-C Building.

Location: The site is located on the north side of the 4722-C building, adjacent to the northeast corner.

Waste Type: Chemicals

Waste Description: The site is a staging area primarily for paint solvents. Signs indicate that solvent rags, antifreeze, and absorbent materials (for spill cleanup) may also be present.

Code: 4722-B FD **Classification:** Accepted
Names: 4722-B FD; 4722-B French Drain **Reclassification:** Rejected (1/27/1999)
Type: French Drain **Start Date:** 1/1/1979
Status: Inactive **End Date:**

Description: The unit is described in the Hanford Site Waste Management Units Report as 1.22 meter (4 foot) diameter pipe that is 1.52 meters (5 foot) long. It is made of concrete or vitrified clay and filled with gravel. There are no visible surface features.

Location: Coordinates place the drain approximately 9.7 meters (32 feet) north of 4722-B, under the roadway.

Related Sites/ Structures: The site is related to the 4722-B Building.

Waste Type: Sanitary Sewage

Waste Description: In 1987, the drain was described to have received 3,785 liters (1,000 gallons) per year of wastewater from lunchroom sinks in the 4722-B building. More current documents of miscellaneous stream discharges do not include this french drain. 4722-B employees believe the lunch room sink is connected to the sanitary sewer.

Code: 4722-C FD **Classification:** Accepted
Names: 4722-C FD; 4722-C French Drain; French Drain South of 4722-C; Miscellaneous Stream #29 **Reclassification:** Rejected (1/27/1999)
Type: French Drain **Start Date:** 1/1/1979
Status: Inactive **End Date:** 1/1/1985

Description: The Hanford Site Waste Management Units Report (1987) lists the site as a french drain that is

1.22 meter (4 foot) in diameter, concrete or vitrified clay, gravel-filled buried pipe that extends 1.5 meters (5 feet) below grade. Surface features include a 5 centimeter (2 inch) diameter pipe protruding from the south side of the 4722-C Building. The pipe emerges from the wall approximately 0.6 meters (2 feet) above the building foundation and travels west approximately 0.9 meters (3 feet). The pipe turns 90-degrees downward and then turns 90-degrees to the south. The visible piping terminates in the gravel beside the building. No drain structure is visible. Per the Dyncorp Environmental Compliance group, the pipe is connected to a sink. The drainage is planned to be eliminated.

Location: The drain is located approximately 1.2 meters (4 feet) from the south wall of the 4722-C building.

Related Sites/ Structures: The site is associated with the 4722-C Paint Shop.

Process Description: The site receives waste water from a sink inside the 4722-C Facility. A statement provided by Dyncorp on January 21, 1999 says that it is noteworthy that currently there are two sinks in this facility. The sink, located within the area where the painting is done, is connected to the sewer not the drywell.

Waste Type: Steam Condensate

Waste Description: The source of the discharge to the french drain was eliminated by close of business on 1/28/99. The water was disconnected. The information provided in the following paragraph has been provided for historical purposes. The Hanford Site Waste Management Units Report (1987) states the drain received water 7570 liters (2,000 gallons per year) from a sink used to wash latex paint from hands, brushes and rollers. It also states a sample was taken from the unit and found no hazardous constituents. A 1988 report (DOE/RL-88-11, Revision 0) states that the hazardous chemical inventory for this site includes 1,000 kilograms (2,200 pounds) of sodium dichromate (Reference 1). This data is unsubstantiated. In 1995, the Inventory of Miscellaneous Streams Report DOE/RL-95-82, Rev 0, Table 3-1, changed the process description to indicate the waste is condensate that originates from a water heater on the west side of 4722-C. The flow rate is listed as 0.038 liters (0.01 gallons) per minute. A statement provided by Dyncorp on January 21, 1999 says that it is noteworthy that currently there are two sinks in this facility. The sink, located within the area where the painting is done, is connected to the sewer not the drywell. Dyncorp has not been able to find anyone with any knowledge of what went into the drain. The 'Registration of Hanford Site Class V Underground Injection Wells', DOE/RL-88-11 contains no references that could be used to verify the statement related to the amount of sodium dichromate. It is possible this statement is in error. There is at least one other error, as the formula for sodium dichromate (Na₂Cr₂O₇) is not NaCr₂.

Code: 4831 LHWSA	Classification: Accepted
Names: 4831 LHWSA; 4831 Flammable Storage Facility; 4831 Laydown Hazardous Waste Storage Area; 4831 Laydown HWSA	Reclassification: Rejected (8/15/2013)
Type: Storage Pad (<90 day)	Start Date: 1/1/1984
Status: Inactive	End Date: 1/1/1993

Description: The site has been a 90 Day waste accumulation area. It was reclassified to Closed Out in 1999. In 2013, the reclassification was changed to Rejected, based on the definition that 90 Storage Pads are outside the scope of WIDS. It was an empty concrete pad with a metal berm around its edges. The metal berm measures 5 centimeters (2 inches) tall and 5 centimeters (2 inches) wide around the concrete pad. Cylindrical concrete anchors are attached to 1.2 meter (4 feet) high metal posts that have been placed around the edges of the pad. Most of the posts remain upright

and are connected with a metal chain. A small, tan metal shed at the east end of the pad provided supply storage and a sheltered workspace when the storage area was operating. The shed is 4.9 meters (16 feet) long and 3 meters (10 feet) wide and has double sliding doors on its south side.

Location: The site is located at the east end of Texas Street, north of the 427 Building. The concrete pad is approximately 10 meters (30 feet) north of the 4831 Flammable Storage Facility.

Waste Type: Chemicals

Waste Description: The site was used as a staging area for oils and hazardous wastes produced and collected in the 400 Area. Wastes staged at this site in 1987 were primarily oils, solvents, ethylene glycol, and empty drums for cooling water treatment chemicals such as Endcor 4690, which is acutely hazardous. These wastes were stored in containers on the pad.

Closure Info: Final: The Laydown Hazardous Waste Storage Area was Closed Out on Reclassification form 98-100.

This pad was retired in December 1993 and replaced with the new 440 Hazardous Waste Temporary Storage Facility. On September 8, 1998, the FFTF Environmental Compliance Officer reviewed available inspection records for the 4831 90 Day Accumulation Area. The records covered the period from 1991 to 1993. In 1993, the 440 Building 90 Day Accumulation Area was put into operation, and the 4831 Building 90 Day Accumulation Area was no longer used. The inspection records did not identify any history of waste container leakage at the 4831 90 Day Accumulation Area. The FFTF Environmental Compliance Officer performed a walkdown and visual inspection of the 4831 90 Day Accumulation Area. There was no evidence of past leakage at the facility. There was some slight rust staining in areas, but no evidence of hazardous material leakage.

Code: 4843	Classification: Accepted
Names: 4843; 4843 Alkali Metal Storage Facility; 4843 AMSF; 4843 Building; 4843 FFTF Sodium Storage; 4843 Laydown Area Warehouse	Reclassification: Closed Out (12/3/1998)
Type: Storage	Start Date: 1/1/1986
Status: Inactive	End Date: 1/1/1997
Description: The 4843 Alkali Metal Storage Facility was a RCRA TSD unit that has been Closed Out. It was built to store dangerous and mixed alkali metal waste. The site began storing materials on April 10, 1986. All materials were removed from the building (date not known). The structure was radiologically released by the Department of Health on May 9, 1995. A letter from the Department of Ecology to the Department of Energy dated May 28, 1997 formally documents the clean closure of the site in accordance with Washington Administrative Code (WAC) 173-303 as of April 14, 1997.	
A site visit in October 1998 found the site to be unchanged from previous descriptions.	
Location: The 4843 Building is located in the northwest corner of the 400 Area. A large laydown area is located adjacent to and west of the structure.	
Related Sites/Structures: After the RCRA permit was closed, a new WIDS code was created (400-36), at the request of EPA, for its new use as a waste transfer station.	
Waste Type: Barrels/Drums/Buckets/Cans	

Waste Description: The unit was a storage area for dangerous and mixed alkali metal wastes generated by FFTF and various other operations at the Hanford site. Dangerous and mixed alkali metal wastes that have been stored at the facility include mixed sodium waste; materials used to clean up radioactive sodium; non-radioactive sodium waste; waste radioactive sodium metal; and non-waste, non-radioactive sodium metal. Waste containers used at this facility may have included steel 19 liter (5 gallon), 114 liter (30 gallon), and 208 liter (55 gallon) drums or sealed piping and components that have been welded closed.

Closure Info: Final: The site began storing materials on April 10, 1986. All materials were removed from the building (date not known). The structure was radiologically released by the Department of Health on May 9, 1995. A letter from the Department of Ecology to the Department of Energy dated May 28, 1997 formally documents the clean closure of the site in accordance with Washington Administrative Code (WAC) 173-303 as of April 14, 1997 (Administrative Record #0047356).

The letter from the Department of Ecology to the Department of Energy dated May 28, 1997 formally documents the Clean Closure of the RCRA permit.

Code: 600 BPHWSA	Classification: Accepted
Names: 600 BPHWSA; Hazardous Waste Storage Area (607 Batch Plant); 600 Area Batch Plant HWSA	Reclassification: Rejected (9/6/2000)
Type: Storage Pad (<90 day)	Start Date: 1/1/1984
Status: Inactive	End Date:

Description: The accumulation area is reported to be in the area that is fenced with chain link and adjacent to the 607 Building, but the specific location within the fenced area is not known. While the area south of the vacant 607 Building is still fenced and locked (April 2000), the entire fenced area is visible enough to determine that no wastes remain.

Location: This site is located at the abandoned Batch Plant (Building 607) north of Route 3 between 200 East and West Areas.

Process Description: This site was used as a 90 day waste storage area for maintenance and construction waste. Roofing, insulating, and protective coating materials were stored in drums and pails; approximately 760 liters (200 gallons) per year were held here.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: This site stored miscellaneous containerized maintenance and construction waste up to 90 days.

Closure Info: Final: The 90 day storage pad was Reclassified to Rejected on for 200-038. All wastes have been removed; no evidence remains of their presence.

WAC 173-303-630(10) requires that at closure, all dangerous waste and dangerous waste residues be removed from the containment system. However, there are no documentation requirements for this closure, and thus no referenceable records for older pads. For many of these older pads, the exact locations were not recorded and cannot be reliably re-examined at this time. By analysis of the spill response standard operating procedure and interviews with the spill response coordinator, documentation of closure of these 90 Day Storage Areas can be recreated. According to J. Culmer (July 31, 2000), spill response and reporting coordinator, there have been no releases to the environment from 90-Day pads. The HNF-PRO-453 Spill and Release Reporting procedure covers cleaning up releases and entering release sites, where releases cannot be immediately cleaned up due to the location of the release or the decision made to clean up the site at a later date, as part of the Operable Unit. If the release is to be

cleaned up as part of the Operable Unit, then it is required that the release site and material released be added to an existing Operable Unit WIDS site or a new WIDS site created and entered into the data base. Mr. Culmer is not aware of any spills or releases onto 90 Day Storage Pads, that have not been cleaned up immediately, waste managed properly and then disposed of per state and federal requirements. All releases have been handled per the HNF-PRO-453 Spill and Release Reporting procedure. The releases onto 90 Day Storage Pads that had been reported internally to the spill response office were small leaks from containers that had been cleaned up; none of these releases migrated off the pads and into the soil column.

Code: 600 ESHWSA **Classification:** Accepted

Names: 600 ESHWSA; Hazardous Waste Storage Area (Exploratory Shaft); 600 Area Exploratory Shaft Hazardous Waste Storage Area; 600 Area Exploratory Shaft HWSA **Reclassification** Rejected (9/6/2000)

Type: Storage Pad (<90 day) **Start Date:** 1/1/1983

Status: Inactive **End Date:** 1/1/1988

Description: The Hazardous Waste Storage Area has been reclassified to Rejected. The Exploratory Shaft Facility has been decommissioned and reclaimed. All of the waste was removed. No visual evidence of the site remains, but the specific location is not known.

Location: This site is located at the Exploratory Shaft Facility, west of 200 West Area and southeast of the Yakima Barricade, near Army Loop Road.

Related Sites/ Structures: The associated facility is the Exploratory Shaft Site.

Process Description: This site was a storage area for hazardous waste at the Exploratory Shaft Facility.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: Materials located at the site were excess paint, anti-corrosive coatings, fuels, lubricants, and other similar potentially hazardous materials.

Closure Info: Final: On March 23, 1988 all decommissioning and reclamation work was completed at the Exploratory Shaft Facility. All hazardous waste and materials were removed from the site.

The site was Reclassified to Rejected on form 2000-028.

Code: 600 ESST **Classification:** Accepted

Names: 600 ESST; Septic Tank - Exploratory Shaft; 600 Area Exploratory Shaft Septic Tank **Reclassification** Closed Out (5/31/2001)

Type: Septic Tank **Start Date:** 1/1/1981

Status: Inactive **End Date:** 1/1/1988

Description: This was the site of the Exploratory Shaft Facility septic tank. This area has been reclaimed due to project cancellation. The septic tank was properly abandoned per WAC codes. No visual evidence of a septic tank remains.

Location: This site is at the Exploratory Shaft Facility, west of 200 West Area and southeast of the Yakima Barricade, near Army Loop Road.

Related Sites/ Structures: This site has an associated drainfield and distribution box.

Process Description: This site provided sanitary wastewater disposal for the Exploratory Shaft Facility.

Waste Type: Sanitary Sewage

Waste Description: The unit received sanitary wastewater.

Closure Info: Final: The site has been abandoned per WAC code. Decommissioning and reclamation work was completed at the Exploratory Shaft Facility on March 23, 1988. The septic tank was pumped out, the access manhole covers were removed, and it was backfilled with clean sand. The sanitary concrete distribution box was removed and voids were filled. The steel posts and barrier rope around the drain field were removed, and the drain field pit was backfilled.

Code: 600 NSTFST	Classification: Accepted
Names: 600 NSTFST; Near Surface Test Facility; Septic Tank; 600 Area Near Surface Test Facility Septic Tank	Reclassification: Closed Out (5/31/2001)
Type: Septic Tank	Start Date: 1/1/1981
Status: Inactive	End Date: 1/1/1988

Description: The septic tank and associated tile field was pumped and properly abandoned in 1998. The septic tank serviced the Trailer Village that was located at the base of Gable Mountain. Decommissioning and reclamation activities at the Near Surface Test Facility were completed March 23, 1988.

Location: This site is located at the west end of Gable Mountain, at the base of the north side.

Related Sites/ Structures: The tank was associated with the Near Surface Test Facility Trailer Village.

Process Description: This unit provided sanitary disposal for the Near Surface Test Facility Trailer Village.

Waste Type: Sanitary Sewage

Waste Description: The unit received sanitary wastewater.

Closure Info: Final: The septic tank was pumped out and backfilled. Decommissioning and reclamation activities at the Near Surface Test Facility were completed March 23, 1988.

The site was reclassified to Closed Out on form 2001-028.

Code: 600 NSTFUT	Classification: Accepted
Names: 600 NSTFUT; Near Surface Test Facility; Underground Tank; 600 Area Near Surface Test Facility Underground Tank	Reclassification: Closed Out (5/31/2001)
Type: Storage Tank	Start Date: 1/1/1981
Status: Inactive	End Date: 1/1/1988

Description: The waste site has been reclassified to Closed Out. It consisted of two sanitary waste holding tanks. The two sanitary waste holding tanks were removed from the site. The tanks supported the mobile office trailers that were located on the tunnel bench for the Near Surface Test Facility. The tanks each had a 3,785-liter (1,000-gallon) capacity and were emptied every other week. All decommissioning and reclamation work at the Near Surface Test Facility was completed on March 23, 1988.

Location: The tanks were located on the tunnel bench for the Near Surface Test Facility, on the north side of Gable Mountain.

Process Description: The tanks received sanitary waste from mobile office trailers.

Waste Type: Sanitary Sewage

Waste Description: The tanks received sanitary wastewater.

Closure Info: Final: The holding tanks were removed from the site. All decommissioning and reclamation work at the Near Surface Test Facility was completed on March 23, 1988.

The site was Reclassified to Closed out on form 2001-029.

Code: 600-1

Classification: Accepted

Names: 600-1; Westinghouse Debris Pit

Reclassification: Rejected (4/6/1999)

Type: Dumping Area

Start Date: 1/1/1976

Status: Inactive

End Date:

Description: The site is a large depression with sandy soil and sagebrush. Part of the depressions has been backfilled with soil from adjacent areas. Metal and wood scrap can be seen on the surface. Soil subsidences (sink holes) are evident. One faded yellow sign that states "Positively No Dumping" is located on the south side of the site, adjacent to the gravel road. The sign is located in between the 600-1 trench (located on the east side of the depression) and the JA Jones Pit 1 (located on the west side of the depression). Bulldozer scars are evident on the surface.

Location: This site is located on the east side of a large depression that is located north of the 300 Area, east of the point where the railroad tracks cross Route 4 South.

Related Sites/ Structures: The trench is adjacent to and east of the J. A. Jones 1 Dumping Pit.

Process Description: Interviews with two employees indicate that two trenches were co-located in this depression. One trench was dug from east to west. It was located on the west side of the depression and was used by the J.A. Jones Company to dispose of inert waste, paint products and debris (see WIDS Site JA Jones #1). The other trench was dug from north to south, located adjacent to the J.A. Jones pit. It was used by the 300 Area Westinghouse facilities as a disposal site for tumbleweeds that collected on the 300 Area fences. The site may have received miscellaneous wood, pallets and debris from the 300 Area Westinghouse facilities during the late 1970's and early 1980's. A 1994 site visit observed evidence that tumbleweeds had recently been dumped along the southeast edge of the site, indicating the area was still being used for this purpose.

Waste Type: Misc. Trash and Debris

Waste Description: Roofing remnants, plastic bucket with dried paint, rebar, aluminum, bits of concrete, asphalt, wood, and plastic are visible at the site.

Waste Type: Chemicals

Waste Description: October 1994 interviews with Will Kirk and Tony Day, retired Hanford employees, disclosed that aluminum silicon alloy, may have been disposed of at 600-1. Interviewees were unable to positively confirm dumping at this site, but felt a reasonable certainty. Aluminum silicon alloy was used in its molten state as a reactor fuel cladding process dip in the 313 Building and waste aluminum silicon alloy usually had low levels of uranium contamination.

Waste Type: Misc. Trash and Debris

Waste Description: The site was used by the 300 Area Westinghouse facilities. It was used mostly to dispose of the tumbleweeds that accumulated on the 300 Area fences. Some wood, pallets and miscellaneous debris may have also been placed in this trench.

Code: 600-2

Classification: Accepted

Names: 600-2; Army Landfill

Reclassification: Rejected (5/9/2000)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site is an excavated pit in a dune area. The bottom is covered with wind-blown sand, cheatgrass and tumbleweeds. Only a few pieces of wire, rebar, and concrete are visible.

Location: This site is located south of Horn Rapids Road across from the Horn Rapids Landfill. It is on the eastern portion of Siemens Nuclear Power Corporation property, west of Kelly Ave.

Waste Type: Misc. Trash and Debris

Waste Description: Reports indicate some materials may have been of military origin. No hazardous materials were indicated in reports or on walkdowns. Some metal debris and a few chunks of concrete were visible in 1998 and 2000. Some wire was found in an adjoining gully.

Code: 600-4

Classification: Accepted

Names: 600-4; Howitzer Site

Reclassification: Rejected (10/1/1997)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site is a dumping area left from its use as a military encampment. It includes a garbage dump, the remains of old military tent city, gun emplacements, two small water towers, and scattered debris. A portion of a large gravel pit, located approximately 525 meters (1722 feet) south of Route 1 and west of the railroad tracks that are located closest to the entrance to 100-K, was used as the garbage dump. A wooden loading ramp was used to dump the garbage. To the northwest is the remains of the old military tent city. Earth mounds topped with wooden decks surround the site. Presumably these structures are lookout platforms. On the south side of the site, one of the platforms is on top of what appears to be soils removed from the trench that traverses the site. This would indicate that the site was emplaced after the trench was dug and would account for the trench being backfilled at the center of the site. The trench that traverses the site from northwest to southeast may have been the location of a temporary water supply pipeline that ran from the pre-Hanford Allard pumping station to the 200 North Area and the Central Electrical Control Station located in the 200 North Area. The entire length of this trench was traced for the Technical Baseline Document (WHC-SD-EN-TI-239). At least three large wooden bunkers with earthen berms surrounding the sides were also located in the area. The wooden roofs, made up of 20.3 centimeter by 20.3 centimeter (8 inch by 8 inch) beams have

collapsed into the structures. The overall site covers an area of approximately 6.07 hectares to 8.1 hectares (15 to 20 acres).

In 1997, the debris was determined to be non-hazardous and the waste site was reclassified to rejected.

Location: The site is located south of 100-K Area on the south side of Route 1. The access road to the site leaves Route 1 about 0.9 kilometers (0.6 miles) west of the railroad crossing located just west of the entrance to 100-K.

Waste Type: Misc. Trash and Debris

Waste Description: This unit contains various types of solid wastes including old food containers, 18.9 liter (5 gallon) gas and oil cans, empty ammo crates (confirmed to be empty), and two piles of coal approximately 6.1 meters (20 feet) in diameter. In addition to old military containers and ammo boxes, a 18.9 liter (5 gallon) drum with holes in the bottom was found. The drum was partially buried and appeared to be some type of french drain or sanitary sewage facility (latrine).

Code: 600-6	Classification: Accepted
Names: 600-6; Battery B Nike Missile Launch Site; MIL - H-12-L	Reclassification: Rejected (1/30/2003)
Type: Military Compound	Start Date: 1/1/1953
Status: Inactive	End Date: 1/1/1960

Description: The waste site has been evaluated and reclassified to Rejected. It was a military installation that once included two sheds (paint and acid storage), a generator building, an oil tank, an 11,356 liter (3,000 gallon) UST, a 200 meter (650 feet) deep well, and a septic system. In 1990 the site consisted of concrete foundation pads, a backfilled underground storage area, a 3-4 ft deep excavation, and a large soil depression at the northwest corner of the unit. The large soil depression in the northwest corner of the site was suspected to be a disposal area, based on a general disturbance pattern within the nearby soil (Roos 1990). All above-ground structures were sold to Washington State University prior to 1974 and have been removed.

Location: The Unit location is northeast of 100-F Area on the opposite side of the Columbia River (SW 1/4 of NW 1/4 Section 23 T 14N R 27E). The Unit is approximately 1/2 mile east of the intersection to White Bluffs landing.

Related Sites/ Structures: Storage bunker, electrical access port and acid pit, 600-10 Control Area, and 600-17 Antiaircraft gun site.

Waste Type: Demolition and Inert Waste

Waste Description: Only concrete building foundations and a soil depression remain. An Acid pit was sampled but no hazards were identified.

Closure Info: Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-7	Classification: Accepted
Names: 600-7; Concrete/Asbestos Pipe Site; Nike Asbestos Pipe Site	Reclassification: Rejected (1/30/2003)
Type: Dumping Area	Start Date:

Status: Inactive**End Date:****Description:** The waste site has been evaluated and reclassified to Rejected. The unit is a depression that contained miscellaneous construction debris and exposed pieces of concrete/asbestos pipe. Demolition activities at H-12-L (sitecode 600-6) is believed to be the source of the debris at this waste site.**Location:** The site is located northeast of 100-F Area on the opposite side of the Columbia River (SW 1/4 of NW 1/4 Section 23 T 14N R 27E). It is adjacent to the H-12-L Nike Launch site.**Related Sites/ Structures:** The site is associated with demolition at the Nike Missile Launch Site, H-12-L.**Waste Type:** Demolition and Inert Waste**Waste Description:** This unit contains concrete/asbestos pipe, concrete, and miscellaneous construction debris.**Closure Info:** Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-10**Classification:** Accepted**Names:** 600-10; Battery B Nike Missile Control Center; MIL - H-12C**Reclassification** Rejected (1/30/2003)**Type:** Military Compound**Start Date:** 1/1/1953**Status:** Inactive**End Date:** 1/1/1960**Description:** The waste site has been evaluated and reclassified to Rejected. This unit was the control center for the Battery B Nike Missile site. The site was cleaned up as part of the North Slope Expedited Response Action.**Location:** The site is located northeast of 100-F Area, (NW 1/4 Section 24, T 14N R 27E, 1/4 mile east of sections 13,14,23,24) at the road terminus west of PSN 12/14, and about 3 miles east of the White Bluffs landing.**Related Sites/ Structures:** 600-6 MIL-H-12L Battery B Launch Site.**Waste Type:** Demolition and Inert Waste**Waste Description:** Wastes identified at the unit include a 5-gallon can of military lubricant (containing minimal amounts of free product), wire, several paint and lubricant cans, and some re-bar associated with building foundations.**Closure Info:** Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-11**Classification:** Accepted**Names:** 600-11; MIL - H-81R**Reclassification** Rejected (1/30/2003)**Type:** Military Compound**Start Date:** 1/1/1953**Status:** Inactive**End Date:** 1/1/1960

Description: The waste site has been evaluated and reclassified to Rejected. The unit was an abandoned military installation to support the anti-aircraft gun system. The site was cleaned up as part of an expedited response action.

Location: The site is located northwest of 100-B/C Area on the opposite side of the Columbia River (N 1/2 of SW 1/4 Section 28, T 14N R 25E).

Process Description: In 1954, 81-R was situated near PNS 80 to support the Anti-Aircraft gun system. By 1955, 81-R was moved to near 83-C. The nature of the equipment and structures (if any) are unknown.

Waste Type: Demolition and Inert Waste

Waste Description: Wastes identified at the unit are miscellaneous surface debris including batteries, bottles and a buried, open-top 55-gallon drum.

Closure Info: Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-12	Classification: Accepted
Names: 600-12; Battery C Control Center; MIL - H-83C	Reclassification: Rejected (1/30/2003)
Type: Military Compound	Start Date: 1/1/1956
Status: Inactive	End Date: 1/1/1960

Description: The waste site has been evaluated and reclassified to Rejected. This unit is an abandoned control center for the battery C Nike missile site.

Location: The site is located northwest of 100-B/C Area on the opposite side of the Columbia River (SW 1/4 of NW 1/4 Section 28, T 14N R 25), 1/4 mile east of SR 24, the north-south road, near top the of the bluff.

Related Sites/ Structures: PSN 80 (sites 600-75 and 600-13) and 600-11.

Waste Type: Demolition and Inert Waste

Waste Description: The unit waste includes several hundred rounds of spent 30/06 casings, steel links for belt-fed automatic weapons, and several tires.

Closure Info: Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-13	Classification: Accepted
Names: 600-13; Battery "C" Launch Site; MIL - H-83L; PSN 80	Reclassification: Rejected (1/30/2003)
Type: Military Compound	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1974

Description: The waste site has been evaluated and reclassified to Rejected. This unit is an abandoned military installation. Buildings and other above ground structures have been removed. Underground structures have been backfilled.

The Air Defenses of Hanford: Camp Hanford The Forward Positions 1950-1964 descriptive summary (Anonymous 1993) states there were 15 aboveground structures (including barracks, paint, oil, and acid storage), a septic system, and assorted "miscellaneous tanks." The barracks were located about 0.4 kilometers (0.25 miles) away from the launch site. The summary also reported that the site is "destroyed;" the AEC cleanup was from May to July 1974. The ammunition magazines were detonated in June 1974. The adjacent PSN 80 was merged with this site after 1956 (Anonymous 1993).

Location: The site is located northwest of 100-B/C Area on the opposite side of the Columbia River (SW 1/4 Section 16, R 14N R 25E) It is at the end of a paved access road.

Related Sites/ Structures: 600-11, 600-12, 600-75, 600-18 and 600-96

Waste Type: Demolition and Inert Waste

Waste Description: Wastes identified at the unit are miscellaneous disposal area debris, material from 1960's practice maneuvers, and miscellaneous trash scattered over a 50 acre area.

Closure Info: Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-14

Classification: Accepted

Names: 600-14; MIL - PSN 01

Reclassification Rejected (1/30/2003)

Type: Military Compound

Start Date:

Status: Inactive

End Date: 1/1/1960

Description: The waste site has been evaluated and reclassified to Rejected. The unit is an abandoned military tent camp and anti-aircraft battery site. During the April 1999 site visit, no foundations were observed but several regular shaped disturbed areas and chunks of concrete were visible. What appeared to be an abandoned well was found under a removable metal cover. There is an area of erosion or subsidence with exposed concrete along the edges. Circular areas with little or no vegetation were also seen around the site. Mature trees, grasses and 0.6 to 1.2 meter (2 to 4 foot) tall sagebrush cover the site. An underground septic tank and drain field may still exist as there is no record of them being removed. The well that serviced the position was 892 feet deep, and drilled in 1953.

Location: The site is located north of the Columbia River, north of Highway 24, in the Wahluke Slope State Wildlife Recreation Area. It can be accessed via Gate 136. The site is approximately 1 mile north of marker 56 on Highway 24.

Process Description: Original structures at the site included a 20-foot by 34-foot aluminum pre-fab pumphouse with a concrete floor and foundation, a 550-gallon underground storage tank, and septic system. The site also had a direct communications cable connection with Headquarters site H-03-H, which was in the central region of Hanford, south of the 100-N Area. The use permit was terminated by the Atomic Energy Commission on December 21, 1960. After the site ceased to function as an AAA site, a repeater remained operational.

Closure Info: Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-15

Classification: Accepted

underground room. All of the buildings have been removed.

Location: The tent camp PSN 12/14 was located NW 1/4 of NE 1/4, Section 24 T14N R27E, at the end of the road leading east from White Bluffs landing. Only paved and dirt roads remain.

Related Sites/ Structures: Site 600-74 is northeast of this site, and was another dumping area for this tent camp.

Waste Type: Demolition and Inert Waste

Waste Description: The waste at the unit consisted of metal scraps, old paint cans, commissary-type waste (e.g., food cans, condiment containers and beer bottles), washing machine parts, a water tank, a water heater, 1-gallon solvent cans, and artillery shell packing boxes marked 120 M.

Closure Info: Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-18

Classification: Accepted

Names: 600-18; H-82; MIL - PSN 72/82; PSN 72; Tent Camp 515

Reclassification: Rejected (1/30/2003)

Type: Military Compound

Start Date: 1/1/1951

Status: Inactive

End Date: 1/1/1961

Description: The waste site has been evaluated and reclassified to Rejected. The site is an abandoned military tent camp site and anti-aircraft battery. The unit consisted of a few small disposal pits and piles located west of the road and a small firing range located at the northeast corner of the unit. The site also contained a pumphouse and a 500 gallon underground tank. A disposal area was identified with a considerable amount of surface debris; all debris has been removed.

Location: The site is located northwest of 100 B/C on the opposite side of the Columbia River (SW 1/4 Section 31, T 14N R 25E) Parts of it are on both sides of a small highway heading north from Vernita Bridge, around a group of trees at the top of the hill.

Process Description: The gun emplacements and all the facilities except for the septic system and roads were removed during the 1974 cleanup.

Waste Type: Demolition and Inert Waste

Waste Description: The unit contained wood debris, empty 5-gallon and 1-quart oil cans, an empty 5 gallon can of lubricant, artillery packing materials, two partially buried plywood boxes, ash, communications wire, cable, lead and brass. The unit also contained a septic tank.

Closure Info: Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-19

Classification: Accepted

Names: 600-19; Base Camp 410; H-90; MIL - PSN 90

Reclassification: Rejected (1/30/2003)

Type: Military Compound

Start Date:

Status: Inactive

End Date:

Description: The waste site has been evaluated and reclassified to Rejected. This is an abandoned anti-aircraft military installation. Before final cleanup in 1994, structures included a concrete

foundation pad, an abandoned well, cinderblock well pumphouse with a 550 gallon underground tank, a usable well, abandoned well, and a recently used old oil rack and grease pit, wash platform, generator shed, septic system, and support facilities. Other unit features include an old dumping ground (located south of Highway 24), several trash pits, and a 10 feet by 15 feet by 4 feet deep trench.

During the April 1999 visit, several concrete foundations and walkways were observed, as well as a stone wall, earthen mounds and a small cinderblock structure. Mature trees are growing around the abandoned installation.

Location: The site is located north of the Columbia River in the Saddle Mountain National Wildlife Refuge. Most of the site is located north of Highway 24; however, an old dumping ground is described as being located south of the highway.

**Related Sites/
Structures:** Military motor pool

Waste Type: Demolition and Inert Waste

**Waste
Description:** Unit waste consists of small amounts of refuse including tent parts electrical parts, automobile parts, and sand bag material. In addition, a small area of the ground was oil stained near the oil rack.

Closure Info: Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-20

Classification: Accepted

Names: 600-20; 615 Hot Mix Plant for Road Materials;
Tank Cleaning Site

Reclassification Final Closed Out (9/1/2015)

Type: Depression/Pit (nonspecific)

Start Date:

Status: Inactive

End Date:

Description: The waste site was remediated in 2014 and reclassified to Final Closed Out in 2015. It was the remnants of the 615 Hot Mix plant for road surfacing materials. The site was separated into five areas for remediation. Area 1 contained two abandoned asphalt tanks, each with a volume capacity of 45,420 to 52,990 liters (12,000 to 14,000 gallons) along with piping, valves and debris. Area 2 contained a coal pile, Area 3 was a trench that ran down a gentle slope and contained puddled asphalt and debris, Area 4 contained discarded asphalt and miscellaneous debris, Area 5 was a pit that contained drums, pails and discarded asphalt.

A 1999 waste site walkdown identified several valve pits, and a depression which contains discarded asphalt material, several pails and drums. Waste asphalt, dumped in solid and liquid form, was prevalent at the site, along with other construction and equipment debris. In warm weather, the discarded asphalt liquefied and resembled puddles. The asphalt puddle in the depression (trench) south of the tank area was approximately 0.3 meters (1 foot) deep in May and June 1999.

Location: The site was located on the west side of the Hanford Townsite, south of the railroad tracks. The two remaining tanks were considered to be Area 1 and was located 600 meters (1968.6 feet) west of Route 2 North. Area 2 was west of Area 1. Areas 3 and 4 were southwest of Area 1 and Area 5 was located south and east of Area 1.

**Process
Description:** The Hot Mix Plant for the preparation of bituminous road surfacing materials was originally erected for temporary and permanent road construction. This Plant was a "TC" (temporary field

construction) plant that continued to operate after the construction phase. It was located along the south side of a railroad spur and just east of the former Hanford Aggregate Pit. The Plant was rated at 3/4 to 1-1/4 cubic yards per minute and consisted mainly of eight horizontal oil storage tanks; a Barber-Greene, Model #843, Central Mixer for single aggregate, and a Model #833 Single Drum Dryer; and Steam Facilities. At the close of construction, the above facilities were transferred to the Operating Department and assigned permanent building number 615. The horizontal oil storage tanks were arranged in a single row at the foot of the railroad fill to provide a gravity flow for unloading operations. Six of the tanks, measuring 1.5 meters (5 feet) in diameter and 7.3 meters (24 feet) in length, were supported by reinforced concrete cradles. Two of the tanks, measuring 3.0 meters (10 feet) in diameter by 7.3 meters (24 feet) in length, rested on the ground surrounded by an earthen dike. All tanks were provided with wooden frame access platforms and stairways.

Waste Type: Oil

Waste Description: The remaining waste is located in the pit. The floor of the pit is coated with asphalt.

Waste Description:

Closure Info: Final (9/1/2015): Remedial action at the 600-20 waste site was initiated on May 7, 2014, and completed on November 4, 2014. Approximately 10,373 bank cubic meters of contaminated soil and debris were removed and disposed to ERDF. Debris that was removed included the two asphalt tanks, steel, concrete, ash, wood, asphalt, and asbestos material. Approximately 22,600 kg (49,780 lb) of steel sheared from the tanks was recycled. No anomalies were identified during remediation. No overburden material was associated with this subsite.

The excavation proceeded to a maximum depth of 8 meters (26.2 ft) in the area below where the tanks were located. Since all waste was staged within the excavation prior to shipment to ERDF, no waste staging pile areas were used that required verification sampling.

Ash found outside the waste site boundary was determined to not exceed direct exposure cleanup criteria and was left in place as agreed to with the U.S. Environmental Protection Agency (EPA) and the U.S. Department of Energy.

Code: 600-24

Classification: Accepted

Names: 600-24; H-21 Anti-Aircraft Artillery Compound and Dump Site; West P-11

Reclassification: Rejected (10/1/1997)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site shows evidence of several former building foundations and walkways located along both sides of the roadway. A 20 foot wide by 36 foot wide concrete pad exists with concrete cradles for a large (approximately 30 x 8 foot radius) water tank. A well # 64-27, A-5295 BNW, is located in the concrete pad. Metal water pipes are visible at most building sites. Multiple small dumping sites are evident northwest and northeast of the compound, but none could be located that exhibit more than a small scattering of debris. Lesser amounts of debris are located at a site 100 meters southeast of the end of the paved road. An ammunition case is also located here. A coal pile site exists on the east shoulder of the railroad tracks northwest of the compound, and a large pile of military barbed wire fence posts (screw type) is located west of the tracks. The remains of building debris may be found throughout the area, especially in northeast portion of the site.

Location: This unit is northwest of P-11 Unit (sitecode 600-111) at the end of the paved road. Access road intersects Route 2N, 0.6 miles north of mile marker 3.

Related Sites/ Structures: Associated with this unit was a possible containment basin.

Process Description: The site is typical of other Hanford military facilities of the early 1950's.

Waste Type: Misc. Trash and Debris

Waste Description: The waste at this unit includes: foundations, pipes (above and below grade), paint cans, a pile of army fence posts, antifreeze cans and miscellaneous debris.

Code: 600-25

Classification: Accepted

Names: 600-25; Susie Junction

Reclassification: Consolidated (4/12/2004)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site consists of a gravel pit, disposal pit, ash pile and several waste piles at "Susie Junction," where two railroad tracks intersect.

Location: This unit is located north of 200 West Area near Gable Butte. R.R. junction south of Gable Butte.

Waste Type: Misc. Trash and Debris

Waste Description: Wastes identified at the unit include 4-5 drums (one which has leaked oil and one which is labeled "KEROSENE"), rubber boots, canvas gloves, a canvas bag containing laundry, brooms, brushes, chisels mounted on poles hoses, nails, cans, miscellaneous debris and a fluffy white fibrous material.

This Site Was Consolidated With:

Code: 600-38

Names: 600-38; Railroad Siding Susie; Susie Junction; 600-25

Code: 600-26

Classification: Accepted

Names: 600-26; Hanford Townsite Burn Pile

Reclassification: Rejected (10/1/1997)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The Technical Baseline Report states the site consists of a 2.4 meter (8 foot) excavation containing a construction refuse burn pile. However, it also states that the author was unable to locate the site in the field. This site was originally identified as a "mystery site" by Richard Roos. In his field notes, Roos describes the site as "old burn pile, apparently a construction disposal location. Site is graded off, perhaps 8' below original grade." He then goes on to describe various features north of the site, such as 600-20 (The Tank Cleaning Site) and several gravel pits. Under "Unusual or Identifying Features," Roos lists "very large spikes (10" x 1/2"), molten glass and metal, wood ashes. A dump site for concrete building foundation is located behind the soil mound..." The site is described as being east of this soil mound. This soil mound with the concrete chunks on its west side is easy to find and can be seen from Highway 2 North. The mound is found in a large excavated area. The excavation was made into the side of a slope and is not a typical borrow or gravel pit. It increases in depth from east to west. The area east of the soil mound and within the excavated area appears to coincide with Roos' description. However, there appear to have been several areas of burning, not just a single burn

pile. The spikes, molten glass and wood ashes described by Roos were found in this area during the June 1999 visit.

Location: The site is located west of Route 2 North and south of an access road leading to 600-20, the "Tank Cleaning Site." The site is between wells 699-54-18E and 699-54-19 and east of a large soil mound.

Waste Type: Misc. Trash and Debris

Waste Description: Unit wastes include construction debris and possible asbestos and barrels.

Code: 600-27

Classification: Accepted

Names: 600-27; 6-54-18A; 6-54-18B; 6-54-18C; 6-54-18D; A58858; A8855; A8856; A8857; Foundations and Dumping Area; Water Supply Valve Pits; Well 699-50-18C; Well DC-6

Reclassification Rejected (10/6/1997)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site contains wells, valve pits, foundations, and a dumping area. The site has four monitoring wells identified as follows: 6-54-18A, A8855; 6-54-18B, A8856; 6-54-18C, A8857; 6-54-18D, A58858. Note that 6-54-18C is an alias for 699-54-18C. The second identifier beginning with an alpha character is a barcode value located on all wells that are presently used by the samplers during the collection of samples and groundwater elevations.

The well named 699-50-18C, DC-6 does not exist either in the Hanford Environmental Information System (HEIS) database or in historical well documents. Two ex-Basalt Waste Isolation Project (BWIP) personnel were also consulted about this well. Both persons stated that the well does not exist and that the picture shown in the Technical Baseline Report is not an old BWIP well.

The two other sites that were previously identified as "wells" (see photograph in the Technical Baseline Report) are likely to be valve pits for water utilities and are marked with four steel posts surrounding the pits. The easternmost pit has been filled in with soil and a concrete structure can be seen just under the soil. The other pit has a wooden cover and had two water pipes protruding through the cover. One water pipe was approximately 7.6 centimeters (3 inches) in diameter and was open ended. The other pipe was approximately 2.54 centimeters (1 inch) in diameter and had a faucet (garden hose type) attached to the end. In addition, two valve handles also protruded from the wooden cover. Two power poles were observed between the wells and Route 2 North. The power poles appeared to be active and the breaker switches were not locked out.

Evidence of former buildings shows up between the well house and Route 2 North. Building debris includes concrete footings, concrete pads, transite, sewer pipe, electrical wiring and a large diameter clay pipe approximately 0.77 meters (30 inches) in diameter buried vertically from the surface to approximately 2 meters (6.5 feet) below grade. The clay pipe has no incoming/outgoing pipes. The area surrounding the wells show evidence of former roads and walkways that have been overgrown with weeds.

Location: The site is located approximately 0.5 miles west of the old Hanford School, 45.7 meters (150 feet) east of Route 2 North, and on the south side of a dirt road formerly known as Roosevelt Avenue.

Waste Type: Misc. Trash and Debris

Waste Description: The original waste site package identified that chemical analysis of the monitoring well shows volatile organics. No evidence has been found to support this claim. In order to substantiate this information, the HEIS database was searched for groundwater monitoring wells near the area. The following wells were searched for volatile organics: 699-54-18E, 600-54-19, 699-52-18A, 699-52-18B, 699-52-18C, 699-52-19, 699-52-17, 699-54-18A, 699-54-18B, 699-54-18C, 699-54-18D, 699-54-15A. The results are as follows: Well Number 699-54-18D, Sample Number B07Q48, Date 11/24/92, Constituent 67-64-1, Acetone, 190 micrograms per liter; Well Number 699-54-18D, Sample Number B075S7, Date 11/17/92, Constituent 108-88-3, Toluene, 6.1 micrograms per liter; Well Number 699-54-18D, Sample Number B07Q48, Date 11/24/92, Constituent 108-88-3, Toluene, 5.69 micrograms per liter; Well Number 699-54-18D, Sample Number B01NN6, Date 11/24/92, Constituent 108-88-3, Toluene, 5.2 micrograms per liter. HEIS for Well 699-48-18 was searched for volatile organics. The results are for Sample Number H000DQT1, Date 8/25/87, Constituent 75-09-02 methylenechloride, analytical method id = 16, 80 micrograms per liter. A later sample for the same well showed Sample Number B08185, Date 1/28/93, Constituent 75-09-02 methylenechloride, analytical method id = 83, 5 micrograms per liter (below minimum detectable concentration). Other wells had no volatile organics or the results were below minimum detectable concentration. Some asbestos transite is visible in the area.

Code: 600-31

Classification: Accepted

Names: 600-31; 100-F Area Bottle Disposal Site

Reclassification: Rejected (7/29/1997)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site is a sandy area with rabbitbrush growing throughout. It exhibits physical evidence that the dumping of laboratory materials took place. The area also appears to have been disturbed by a blade or bulldozer. During the April 1999 visit, scattered debris was visible, composed primarily of glass with some metal and wood debris. The glass is found in a swath on the west side of a sandy rise. There is a moderate vegetation cover of rabbitbrush and grasses on the sandy rise with less cover on the disturbed ground.

Location: The site is located approximately 91 meters (300 feet) north of the southeast corner of the perimeter road and approximately 9.1 meters (30 feet) east of the perimeter road.

Waste Type: Misc. Trash and Debris

Waste Description: Wastes identified are laboratory-type bottles and bottle caps with the following markings on some of the caps: 1) Sulfuric, 2) Mallinckrodt, 3) Bakers, 4) B & A, 5) Fisher. The markings and colors on the bottles and caps indicate they most likely contained laboratory chemicals (e.g. nitric acid, sulfuric acid, hydrochloric acid, etc).

Code: 600-32

Classification: Accepted

Names: 600-32; N Area Landfill

Reclassification: Rejected (6/30/2004)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: A field walkdown done in August 2000 compared the site to the area mapped in Arcview and found it to be a duplicate of 100-N-39 and 100-N-19 (it is contained within the much larger 100-N-19). The site is a large area covering approximately 13 hectares (32 acres), consisting of an abandoned gravel pit and several other depressions which were used as dumping areas for 100-

N Reactor and the Hanford Generating Plant (HGP). The main gravel pit depression is approximately 6 meters (20 feet) deep and is located southwest of the HGP facility fence. A steel casing, described as a well head, is located near the northern edge of the unit. Large concrete blocks, a burning area, broken glass, a sandblast material pile, and other debris is scattered across the bottom of the site.

Location: The unit is about 300 meters (1000 feet) south of the 100-N Hanford Generating Plant (HGP) and Bonneville Power Administration (BPA) Hanford Substation facility fence.

Related Sites/ Structures: This site is associated with 100-N-19 (it is contained within the larger site 100-N-19), 100-N-39 (it is a duplicate of 100-N-39), and 100-N-18 (a smaller burning/dumping area about 270 meters (900 feet) north, just south of the HGP fenceline.)

Process Description: The site was used as a dumping area for 100-N Area and the Hanford Generating Plant.

Waste Type: Misc. Trash and Debris

Waste Description: Unit waste includes 19-liter (5-gallon) paint cans (one labeled SCC Portland 26 5 65, one labeled USS 5-28/26-65, one labeled ICC=37-76-80 NRC, others are crushed), sheet aluminum, steel pipes, rebar, transite, cans wood, two 208-liter (55-gallon) drums (one labeled Delvac 1330 SAE-30 motor oil), concrete, wire, cable and spools, bottles (soda pop and amber 3.8-liter [1-gallon] jugs), broken fluorescent and incandescent light blubs, tires, grass clippings and miscellaneous construction debris.

The Following Sites Were Consolidated With This Site:

Code: 100-N-39

Names: 100-N-39; Hanford Substation Construction Dump Area; SWMU #11

Code: 600-33

Classification: Accepted

Names: 600-33; 105-C Reactor Test Loop Burial Site

Reclassification: Rejected (12/9/2004)

Type: Burial Ground

Start Date: 1/1/1963

Status: Inactive

End Date: 1/1/1963

Description: The waste site was a temporary burial site for the 105-C Reactor Test Loop.

Location: Five locations were identified as possible locations for the site, including the one listed as 90 to 120 meters (300 to 400 feet) south of the 105-C Reactor Fan Room (E 565368.938, W 143846.781). Trenches, aka potholes, were dug at (1) E 565369, N 143847, (2) E 565369, N 143916, (3) E 565372, N 143916, (4) E 565371, N 143940, (5) E 565855, N 143769.

Process Description: The selected design for the test loop was a tube within a tube (annular design). The outer tube was a 3.8-centimeter (1.5-inch) inside diameter Schedule 160 stainless steel tubing. The inner tube was 2.5-centimeter (1-inch) inside diameter with 0.17-centimeter (0.065-inch) wall thickness within a 12-meter (40-foot) carbon steel shield tube. The test loop was inserted into the south side of the C Reactor core (one of the channels) and was used to test the effects of ionization on various chemicals being considered for reactor process tube scaling and cleaning.

Waste Type: Equipment

Waste Description: The waste consists of a radioactive double-tube test loop, contaminated carbon-steel shielding pipe, and about 305 meters (1,000 feet) of cable used to remove the test loop from the 105-C Reactor. The test loop is approximately 5.5 to 6.1 meters (18 to 20 feet) long and consists of various sizes of stainless steel tubing. The test loop may have dose rates in excess of 100 rads/hour. Potential contaminants include: Co-60, Ni-63.

Code: 600-34 **Classification:** Accepted

Names: 600-34; 100-B Baled Tumbleweed Disposal Site **Reclassification** Rejected (9/9/1997)

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The site is a dumping area used for disposal of miscellaneous waste. The dumping area is within a borrow or gravel pit which is 3.0 to 4.6 meters (10 to 15 feet) deep.

Location: The unit is west of the 181-B intake structure, north of the 90 degree corner where Route 6 changes from north/south to an east/west direction, and east of Pit #24.

Waste Type: Misc. Trash and Debris

Waste Description: The main concentration of waste is located in the eastern section of the pit. However, there is minor surface rubble spread over the pit floor. Visible wastes include wood (timbers and ties), piles of a silt-like material, sheet metal, cardboard, roofing material, concrete, electrical insulators, and a 10 liter (5 gallon) plastic bucket (090-NRC Paragon Molding Co. Melrose Park, Ill.). Pre-Hanford waste is also evident including barbed wire, what appears to be old farm equipment, and remnants of wire wrapped wooden irrigation pipe. Bales of tumbleweeds were located at the site in 1992, but have since been removed.

Code: 600-39 **Classification:** Not Accepted

Names: 600-39; H-50 Gun Site Building Foundations and Ammunition Storage; Military Camp South of 200W **Reclassification** None

Type: Foundation **Start Date:**

Status: Inactive **End Date:** 1/1/1958

Description: The site has concrete building foundations, walkways and footings. The foundations are: #1. Vehicle maintenance with a mechanic's pit: 30 meters by 14 meters (97 feet by 47 feet). While the pit is filled in with tumbleweeds making observation of the floor impossible, it is likely concrete. It is unlikely that oil would have been allowed to drain freely in the pit, since mechanics would have had to work in the oil while servicing the vehicles. #2. Kitchen/mess: 12 meters by 10 meters (40 feet by 32 feet). #3. Toilet/showers: has five visible toilet drains and two floor drains visible, along with a metal box inset in the foundation, presumably with a water valve inside. The foundation is partially covered with sand. #4. Concrete pad: 9 meters by 6 meters (30 feet by 21 feet). #5. Concrete pad: 15 meters by 6 meters (50 feet by 20 feet). Seven circular ammunition storage berms constructed of wood, sandbags, rock and soil measuring approximately 18 meters (60 feet) in diameter are also present. The July 2000 fire did not affect these bunkers. Very little debris is present, just a couple of empty 5-gallon oil cans (no leaks onto soil are evident), and fencing material in two piles (site 600-223).

Location: The unit is located at the southwest quarter of Section 19, Township 12 North, Range 26 East, 3.2 kilometers (2 miles) south of the 200 West Area and 0.4 miles east of the Rattlesnake Barricade on SR 240.

Related Sites/Structures: The septic system associated with this site is 600-224. Site 600-223 is the associated pits containing fencing material.

Process Description: This was the site of a U. S. Army anti-aircraft gun installation. Typically, Camp Hanford's anti-aircraft artillery sites were each roughly 20 acres in size and contained any number of buildings (typically around 20), various utility distribution systems, roads, and sidewalks. Each site consisted of emplacements protected by revetments made of sandbags and wood planking,

wooden structures, prefabricated metal buildings, and, later, permanent, concrete block structures. The prefabricated buildings had aluminum walls and roofs with wooden or concrete floors set on concrete pier blocks and were the most commonly constructed. The permanent structures included barracks, latrines, mess halls, craft shops, pump houses, motor pools, and radar facilities. Each site typically had a small arms range, water storage cistern, sanitary, and sewage disposal facilities. Pathways, sidewalks, roadways, and parking lots connected the structures.

Waste Type: Demolition and Inert Waste

Waste Description: The waste includes concrete walkways, concrete foundations, and ammunition storage berms constructed of wood, sandbags, rock and soil.

Code: 600-41	Classification: Accepted
Names: 600-41; H 70 Anti-Aircraft Artillery (AAA) Site	Reclassification Rejected (4/11/2002)
Type: Military Compound	Start Date: 1/1/1951
Status: Inactive	End Date: 1/1/1963

Description: The waste site has been evaluated and reclassified to Rejected. The items were removed as "landlord items". It is an abandoned Military Installation (H-70) consisting of a few covered foundations and cleared areas. Some man-made mounds were present. There is a paved road and a few trees at the site.

During the April 16 and April 19, 1999 site visits, two earthen mounds were observed as well as the remains of several foundations. The site was overgrown with approximately 0.9 meter (3 foot) tall sagebrush, making it difficult to discern either features or the edges of the site. There were several opens areas covered with cheatgrass. Scattered pieces of metal, concrete, glass and transite were observed. A burn pit/dump had traces of burned wood, glass and transite. A burrow going into the center of the dump also shows buried glass.

Location: The unit is located approximately 4.2 kilometers southwest of the Vernita Bridge rest area. The site is on the west side of Highway 24, behind Gate 122.

Process Description: This camp is the site of an anti-aircraft battery. Structures reported to have been at the site include administration, classroom, supply and day rooms, barracks, and latrine facilities. The electrical power was provided by overhead wires; water supplied by the "McGee Well;" and the camp was serviced by a septic tank and drain field.

Closure Info: Final: Sitecodes 600-41, 600-42 600-43 and 600-45 were grouped onto one Reclassification form in 2002 and their status was changed to Rejected. The sites were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-42	Classification: Accepted
Names: 600-42; H 71 Anti-Aircraft Artillery (AAA) Site	Reclassification Rejected (4/11/2002)
Type: Military Compound	Start Date: 1/1/1951
Status: Inactive	End Date: 1/1/1963

Description: The waste site has been evaluated and reclassified to Rejected. It is an abandoned military installation. The structures have been removed. The site is accessed by a northeast trending primitive road that runs through it. Berms run along the south side of this road and the remains of barbed wire fences were visible on either side. Well 699-68-105 is located near the northern edge of the site. The marker for this well is a good landmark. Most of the evidence of the site is

found on the north side of the road.

During the April 16, 1999 site visit, evidence of a small tile field was found. It appeared as though the septic tank associated with the tile field has been removed or has collapsed. A pit that could have housed a second septic tank was found on the south side of the road that runs through the site. No evidence of a second tile field was found. A concrete walkway and a rock walkway were found. Wood debris, glass and concrete chunks were found, as well as a metal lid stamped "120 MM GUN" and "CONT M79A." An approximately 1.2 meter (4 foot) by 2.4 meter (8 foot) underground bunker was discovered. Its wooden roof is collapsing and presents a physical hazard. The depth of the bunker could not be estimated. Numerous areas with little or no vegetation were also observed around the site. Evidence of an old orchard can be found north of the site. The orchard can be seen in photo # 02646. Within the old orchard is an earthen mound with vegetation growing on its sides but not on its crown.

Location: The site is located approximately 1.6 kilometers southwest of the Vernita Bridge rest area on Highway 24.

Closure Info: Final: Sitecodes 600-41, 600-42 600-43 and 600-45 were grouped onto one Reclassification form in 2002 and their status was changed to Rejected. The sites were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-43

Classification: Accepted

Names: 600-43; McGee Fish Farm

Reclassification Rejected (4/11/2002)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The waste site has been evaluated and reclassified to Rejected. It is an abandoned commercial fish farm. The fish ponds have been backfilled and revegetated. A site visit in 1999 found a moderate amount of miscellaneous debris, wire and automobile parts strewn around the area near where the fish tanks had been located.

Location: The site is located northwest of the Yakima Barricade, west of Highway 24, approximately 45 meters (147.6 feet) north of well 699-53-103.

Related Sites/ Structures: McGee Wellhouse (699-53-103) is associated with the unit.

Process Description: The site was used in the early 1970's as a commercial tropical fish farm. The site was chosen because the well at the McGee Ranch supplied unusually warm water. Ponds were excavated, lined with black plastic and fed with water from PVC piping. It is believed to have operated only one or two years and then was abandoned.

Waste Type: Misc. Trash and Debris

Waste Description: The unit waste includes broken plastic pipe, plastic sheeting, wood, metal, glass debris and an abandoned vehicle.

Closure Info: Final: Sitecodes 600-41, 600-42 600-43 and 600-45 were grouped onto one Reclassification form in 2002 and their status was changed to Rejected. The sites were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-45

Classification: Accepted

Names: 600-45; Transite and Metal Debris Pile

Reclassification Rejected (4/11/2002)

Type: Dumping Area **Start Date:** 1/1/1951
Status: Inactive **End Date:** 1/1/1964

Description: The waste site has been evaluated and reclassified to Rejected. The items were removed as "landlord items". The site is not marked or posted. It consisted of piles of debris scattered on the ground surface. The area was approximately 500 square meters (5,382 square feet) that ended at a cliff.

Location: The site is west of Highway 24 on Umtanum Ridge. It is 1.6 kilometers southeast of the Midway Substation.

Related Sites/Structures: This site was associated with the H-70 Anti-Aircraft Artillery (AAA) Site (WIDS site code 600-41).

Waste Type: Misc. Trash and Debris

Waste Description: The unit waste includes broken transite shingles, pallet banding straps, exhaust stack made from drums, miscellaneous military food cans and a couple of drums that were rolled off the cliff.

Closure Info: Final: Sitecodes 600-41, 600-42 600-43 and 600-45 were grouped onto one Reclassification form in 2002 and their status was changed to Rejected. The sites were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-50 **Classification:** Accepted
Names: 600-50; Hanford Construction Camp Coal Yard **Reclassification** Rejected (10/1/1997)
Type: Depression/Pit (nonspecific) **Start Date:** 1/1/1943
Status: Inactive **End Date:** 1/1/1945

Description: The site is the remnants of the coal pile that supplied coal to the Hanford Construction Camp residents. The "charred black debris" (described in the previous version of the site description) is the 50 year old remnant bottom layer of coal dust from the pile. There are man made mounds on the northeast corner of the site. Previous documentation describes the mounds as thought to contain waste construction materials, such as, wood, bricks, melted plastics and ceramics. However, the man made mounds were created when the surface was bulldozed in preparation for the coal pile. No waste materials are in evidence.

Location: The site is located approximately 200 meters (656 feet) north-northeast of the old Hanford High School and northwest of the pump house. It is on the east side of Avenue A.

Waste Type: Misc. Trash and Debris

Waste Description: The waste is coal dust remaining from the coal that was stored at the site.

Code: 600-53 **Classification:** Not Accepted
Names: 600-53; H-51 Anti-Aircraft Artillery Site **Reclassification** None
 Building Foundations
Type: Foundation **Start Date:**
Status: Inactive **End Date:** 1/1/1958

Description: Six building foundations and concrete pads were observed at this site and are described as follows: #1. 12.5 meters by 10 meters (41 feet by 33 feet), concrete foundation with 4 floor

drains #2. 15.6 meters by 6.1 meters (51 feet by 20 feet), concrete pad with 8 toilet drains and 11 sink/floor drains #3. 6.1 meters by 15.3 meters (20 feet by 50 feet), concrete foundation #4. 6.7 meters by 15.3 meters (22 feet by 50 feet), concrete foundation #5. 5.5 meters by 3.3 meters (18 feet by 11 feet), Concrete pad #6. 7.3 meters by 5.8 meters (24 feet by 19 feet), Concrete pad.

Location: The H-51 Gun Site is on Army Loop Road, southwest of 200 West Area. This site is located in the southeast quarter of Section 15, Township 12 North, Range 25 East.

Related Sites/ Structures: The site's dumping areas are 600-220; 6607-3 is the site septic system.

Process Description: This is the location of a former U. S. Army anti-aircraft gun site. Typically, Camp Hanford's anti-aircraft artillery sites were each roughly 20 acres in size and contained any number of buildings (typically around 20), various utility distribution systems, roads, and sidewalks. Each site consisted of emplacements protected by revetments made of sandbags and wood planking, wooden structures, prefabricated metal buildings, and, later, permanent, concrete block structures. The prefabricated buildings had aluminum walls and roofs with wooden or concrete floors set on concrete pier blocks and were the most commonly constructed. The permanent structures included barracks, latrines, mess halls, craft shops, pump houses, motor pools, and radar facilities. Each site typically had a small arms range, water storage cistern, sanitary, and sewage disposal facilities. Pathways, sidewalks, roadways, and parking lots connected the structures.

Waste Type: Demolition and Inert Waste

Waste Description: Concrete building foundations and concrete pads

Code: 600-55

Classification: Accepted

Names: 600-55; Paved Area and Collapsed Structure

Reclassification: Rejected (10/1/1997)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site is a dumping area that consists of an asphalt paved area which may have been a parking lot, miscellaneous farm debris and a collapsed wooden building. The pre-Hanford farm debris is scattered approximately 135 meters (443 feet) to the east of the paved area. There is also a cellar and an old stove near the collapsed wooden structure.

Location: The asphalt paved area is located to the west of the 100K Area, southeast of the Allard Pumping Station and to the southwest of the 128-K-2 Burn Pit.

Waste Type: Misc. Trash and Debris

Waste Description: The miscellaneous debris at the site consists of asphalt paving, empty paint and paint solvent containers, an empty antifreeze container, a fan belt, wood, and metal.

Code: 600-56

Classification: Accepted

Names: 600-56; Pre-Hanford Farm Site; Undocumented Solid Waste Site

Reclassification: Rejected (9/9/1997)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site is the abandoned waste from what appears to be a pre-MED (Manhattan Engineering District) farm. The site is identifiable by scattered debris, piles of rocks, and an excavated pit.

Location: The site is located southwest of the 128-B-2 Burn Pit and south of well 699-71-77.

Waste Type: Misc. Trash and Debris

Waste Description: Miscellaneous waste at the site included wood, metal buckets, cans, and wire fencing.

Waste Type: Batteries

Waste Description: Several aging dry cell batteries were found at the site. In September 1997, a field visit was performed by B. D. Schilperoort. He examined the batteries and noted that they appeared to have been in a fire. Some material was removed from the inside of a battery surrounding a carbon electrode. A 50/50 test for corrosivity found neutral pH. A lead test swab found no evidence of lead. The conclusion based on the field investigation was that no hazardous constituents remained in the batteries.

Code: 600-61

Classification: Discovery

Names: 600-61; White Bluffs Substation

Reclassification: None

Type: Electrical Substation

Start Date: 1/1/1976

Status: Active

End Date:

Description: The waste site consisted of potential contamination of the soil from the electrical equipment at the substation.

Location: The substation is located northwest of the Hammer Training Facility off of Horn Rapids Road. The site name has nothing to do with the location.

Process Description: The electrical equipment at the substation included transformers, couplings, capacitors, circuit breakers, reclosers, voltage regulators, switches, and cable. Release occurred from storage tank No. 2.

Waste Type: Oil

Waste Description: The White Bluffs Substation used petroleum oil, primarily mineral oil, as insulation in electrical equipment. Insulating oil was a highly refined, 10-weight petroleum oil with approximately 0.1 percent 2,6-di-tertbutyl-paracresol (an antioxidant known as BHT that was also used as a food additive) and varying amounts of polychlorinated biphenyls (PCBs) to increase dielectric strength. The aboveground tanks contained mineral oil which was used as make-up oil for equipment maintenance or cleaning.

Code: 600-62

Classification: Accepted

Names: 600-62; Benton Switch Substation Releases

Reclassification: None

Type: Unplanned Release

Start Date: 1/1/1948

Status: Active

End Date:

Description: The substation is currently active and is enclosed in a locked, chain link fenced area. It began operations on November 11, 1948. The site contains various electrical equipment, circuit breakers, transformers, tanks, and support facilities. The primary environmental concern stems from leaking insulating oil from transformers and circuit breakers. A site visit on November 20, 1998, observed several areas of discolored gravel and stained concrete beneath vessel

valves.

Location: The substation is located northwest of the northernmost tip of Wooded Island, near the river, at the north end of a gravel utility access road. It is east of the Energy Northwest (Washington Public Power Supply System) property.

Release Description: A number of releases have been associated with the facility. (See releases section). The switchyard has had past mineral oil spills and detections of polychlorinated biphenyls (PCBs) in the soil.

Process Description: This substation is part of the Bonneville Power Administration main transmission grid, that conducts electrical power from the Columbia and Snake Rivers dams to five states (Washington, Oregon, Idaho, western Montana, and northern California). The BPA transmission grid is divided into four subareas. The substations on the Hanford Site are within the Snake River subarea. The substations use petroleum oil, primarily mineral oil, as insulation in electrical equipment. This includes transformers, coupling and potential devices, capacitors, circuit breakers, reclosers, voltage regulators, switches, and cable. Insulating oil is a highly refined, 10-weight petroleum oil with approximately 0.1 percent 2,6-di-tertbutyl-paracresol (an antioxidant known as BHT that is also used as a food additive) and varying amounts of polychlorinated biphenyls (PCBs) to increase dielectric strength. All of the substations have above ground tanks of mineral oil, that is used as make-up oil for equipment maintenance of electrical equipment. Solvents are used for cleaning and degreasing operations. Once maintenance is completed, rags soaked in solvent and all personal protective clothing are to be placed in drums for transport to the generator storage area at the H. J. Ashe Substation. All equipment filled with mineral oil is regularly analyzed for PCB concentration. All untested and unmarked equipment is assumed to be PCB contaminated. Electrical equipment fluid is assumed to be PCB, if the manufacturer's manuals or nameplates do not identify the type of dielectric fluid in the equipment, or if the equipment is known to be PCB according to available information.

Waste Type: Oil

Waste Description: The waste is soil potentially contaminated with polychlorinated biphenyls (PCBs) (Aroclors 1254 and 1260), insulating oil (10-weight petroleum oil with 0.1% 2,6-di-tertbutyl-paracresol). Mineral oil containing PCBs and solvents are the hazardous constituents used at the site.

Code: 600-64 **Classification:** Not Accepted

Names: 600-64; Sanitary Waste Tie-Line from the 400 Area to WPPSS; Underground Sanitary Sewer Line from 400 Area to WPPSS **Reclassification:** None

Type: Sanitary Sewer **Start Date:** 1/1/1997

Status: Inactive **End Date:**

Description: The wastewater line was isolated by plugging it with concrete in December 2013. The underground, gravity flow line began at the inlet to the 4607 Sanitary Sewer septic tanks and connected the 400 Area sanitary sewer main (also known as the 4903 Sanitary Sewer Main) with the Washington Public Power Supply (later renamed Energy Northwest) System sewage treatment facility. The sewer line route appeared as a disturbed area covered with sand and little vegetation. Washington Public Power Supply System (later renamed Energy Northwest) signs were posted along the route mark the existence of an underground sewer line.

Location: The sewer line extended eastward from the existing 400 Area Septic Tanks (WIDS Site 400-7) to the existing Washington Public Power Supply System (later renamed Energy Northwest) sewer line. The line crosses under the Route 4 South highway. The tie-in is located approximately 4.8 kilometers (3 miles) northeast of the 400 Area.

Related Sites/ Structures: The site is associated with the 4607 Sanitary Sewer, 4607 Sanitary Tile Field, 4607 Sanitary Sewer Lagoon, and the 4903 Sanitary Sewer Main.

Waste Type: Sanitary Sewage

Waste Description: Site personnel report that a small amount of sanitary wastes was unintentionally discharged into the tie-line (and, thus, the WPPSS sewage treatment facility), prior to reaching agreement with WPPSS in late 1992. The sanitary wastes remained with the underground tie-line and the treatment facility. No wastes were released to the environment. Radiation detection systems in the treatment facility indicated the presence of radioactive cobalt, cesium, and tritium beyond set limits. However, only tritium was confirmed to have been present in the sanitary wastes from the 400 Area. Water from 400 Area wells contains elevated levels of tritium, which may explain the presence of tritium in sanitary wastes.

Code: 600-67	Classification: Accepted
Names: 600-67; Bruggemann's Fruit Storage Warehouse	Reclassification: Rejected (2/6/2001)
Type: Storage	Start Date: 1/1/1922
Status: Inactive	End Date: 1/1/1943

Description: The Bruggemann's Warehouse site is the remaining single story warehouse, associated foundations, piping, and debris surrounding the site. During 1998 and 2000 field visits, an abandoned fuel tank was identified adjacent to the warehouse. The tank has a 0.6 meter (2 foot) filler pipe showing above ground. All other pipes seen in the area could be attributed to the facility water system. The building is considered culturally significant because of its good condition and use of native materials for construction. It is in the process (as of January 2001) for listing on the National Register of Historic Places. The main warehouse construction consists of local cobblestones in a concrete matrix. An extension of similar construction is present on the south end; it is unknown if this is original to the building or a later addition. The long axis of the warehouse runs north-south. The horizontal wood sheathing of the gable roof is still present on the rafters. On the southeast corner, however, the roof has caved in. Small nails in the roof sheathing indicate that shingles were probably present at one time. The roof overhangs the east and west walls. A cobblestone chimney emerges from the crest of the gable near the south end of the roof. On the west elevation, there is a distinct straight line of cobbles running along the length of the wall about 3 feet (0.9 meters) above grade. A wooden door with a wood frame is in the center of the elevation. On the south edge of the doorway is a wooden plank off its hinges that looks like a garage door. The doors are orange with dark brown decorative trim and each bears two wood frame windows. The north half of this wall has a distinctly straight line of cobbles about 2 feet (0.6 meters) above grade, similar to the west and north walls. On the south wall of the warehouse, there is a wood frame doorway just east of center. The cobblestone extension at the south end of the warehouse is missing its roof. Above most of the structure's doors and windows, the cobblestones are arranged to form decorative arches. The east wall appears to be the main entrance. On all four corners of the building and in the center of the east wall, decorative columns taper diagonally from the ground to the top of the wall. There is a wood frame doorway near the south end. A tall wood frame window south of the door, and two similar windows are north of the door. On the west wall is a single window. The north wall of the extension faces the warehouse, and there is approximately 1 meter (3 feet) between the two walls. In the center of the wall is a doorway with a small square window east of it. A large pile of cobbles lies outside the chain link fence south of the extension. Foundations to the east of the warehouse show other facilities related to fruit packing. A possible fruit washing facility shows evidence of two parallel tables with troughs underneath for draining. Also east of the warehouse is a round concrete foundation with heavy steel eyebolts, presumably to support a tank for pressurized water.

Location: The site is located approximately 1.1 kilometers (0.7 miles) east of the Vernita Bridge and State Highway 240. On the Hanford Site, the site may be accessed via Route 6 between miles 6 and 7.

Related Sites/ Structures: Remnants of previous structures at the site include a concrete pad located approximately north of the warehouse, and a concrete walkway that runs from the east side of the warehouse to a rectangular concrete foundation approximately 12 meters (40 feet) by 24 meters (80 feet). East of the foundation is the circular concrete foundation for the water tank, approximately 6 meters (20 feet) in diameter. West of the warehouse is the remnant of a house foundation. The area surrounding the warehouse consists of agricultural debris including vitrified clay piping for irrigation, dead fruit trees, and fencing material.

Process Description: The following comments on life at the site (1937 - 1943) are from a telephone interview with Mary Bruggemann (she was married to Paul Bruggemann). She is now living in Yakima. They grew peaches, cherries, a new orchard of prunes, and a few wine grapes. The site had a river pumphouse for acquiring water for the orchards. Native Americans were hired during harvest time to pick fruit. Fruit was transported by truck and utilized the Hanford Engineering Works (HEW) train when it first came through. They also had a lot of sheep and a few cattle. The Bruggemann's had two employees.

Waste Type: Storage Tank

Waste Description: The underground storage tank was used for storing fuel. Approximately 5 centimeters (1.97 inches) of water and fuel residue remained in the bottom of the tank in February 1998 and September 2000.

Waste Type: Misc. Trash and Debris

Waste Description: Farm debris was observed around the site including fence posts, pipe, food tins, buckets, farm machinery parts, barbed wire, and wire.

Code: 600-69	Classification: Not Accepted
Names: 600-69; Red Stained Soil (Rust)	Reclassification: None
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The site is an area of reddish soil that was discovered while a road grader was scraping an area for installation of a pipeline. As of July 14, 1997, the stain was disappearing. Some pinkish soil is visible on the surface. The area is covered with vegetation, including cheat grass, tumbleweeds, and rabbitbrush.

Location: The site is located west of 200 East. It is 600 meters (1969 feet) west of the 200 East perimeter fence, west of Route 4 South, and northwest of 2704HV.

Code: 600-72	Classification: Accepted
Names: 600-72; H-12R; Wahluke Slope H-12-R Debris Site	Reclassification: Rejected (1/30/2003)
Type: Dumping Area	Start Date:
Status: Inactive	End Date:

Description: The waste site has been evaluated and reclassified to Rejected. The site is an abandoned military radar and dump site that ran east-west and included approximately 5 acres. A gravel

road formed the perimeter of the site.

Location: The site is northeast of 100-F Area on the opposite side of the Columbia River (Section 23, T 14N, R 27E). The site southeast of H-12L.

**Related Sites/
Structures:** PSN-12/14, H-12L

Waste Type: Construction Debris

**Waste
Description:** The primary hazard at this site is construction debris including domestic garbage, wood, oil cans, and 55 gallon drum. Visible debris has been removed.

Closure Info: Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-73

Classification: Accepted

Names: 600-73; Wahluke Slope Igloo Sites

Reclassification Rejected (1/30/2003)

Type: Military Compound

Start Date:

Status: Inactive

End Date:

Description: The waste site has been evaluated and reclassified to Rejected. It is the site of two ammunition storage "igloos." The buildings have been removed and the area has been cleaned up.

Location: On Wahluke Slope, north of the 100 D Area at the upper east and west ends of a "T-shaped" gravel road.

Waste Type: Misc. Trash and Debris

**Waste
Description:** The debris at this site included a stock watering drum, glass bottles, tin cans, barbed wire, and other garbage. The debris has been removed.

Closure Info: Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-74

Classification: Accepted

Names: 600-74; Motor Pool Dump; Wahluke Slope PSN 12/14 Military Construction Dump

Reclassification Rejected (1/30/2003)

Type: Military Compound

Start Date: 1/1/1950

Status: Inactive

End Date: 1/1/1960

Description: The waste site has been evaluated and reclassified to Rejected. This military construction and motor pool dump site is located approximately 2/3 miles north and east of the PSN 12/14 camp location. It is an area of building remains, trash and debris extending in an east-west direction near the border of sections 13 and 24 in Section T14N R27E. Oil cans and automobile parts suggested some of the trash may be from a military motor pool. Construction debris, like boards with nails, is all that remained in 2001.

Location: The site is located 1 kilometer (2/3 mile) north and east of waste site PSN 12/14 (600-17). The site extends from east to west near the borders of sections 13 and 24 in Section T14N R27E.

Related Sites/ Structures: This site is associated with the MIL-PSN 12/14 (600-17) and the MIL-H-12C, Battery B Nike Missile Control Center (600-10) sites. It is suspected that this dump area was used as part of the 600-10 and 600-17 site demolitions.

Waste Type: Construction Debris

Waste Description: Miscellaneous debris and trash from demolished wooden buildings, automobile parts and 1 gallon and 5 gallon oil cans. The automobile parts and cans suggest the trash may have come from a motor pool.

Closure Info: Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-75

Classification: Accepted

Names: 600-75; Wahluke Slope PSN 80 Debris Site

Reclassification Rejected (1/30/2003)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The waste site has been evaluated and reclassified to Rejected. The site is no longer visible. The debris was removed. The site is similar to the H-12R site (600-72) and the "Radar" sites (600-76). It is roughly oval and surrounded by a gravel road. Two locations were identified, with four small concrete pads with imbedded bolts. It is believed that there should be three sets of pads. The site evaluator found only one concrete building foundation and no obvious disposal pits.

Location: The site is located northwest of 100 B Area, on the opposite side of the Columbia River. (14N, 26E, section 16)

Related Sites/ Structures: The site contained a 160-meter (522-foot) well and pumphouse, metal pre-fab buildings, and septic system, with no fuel tanks listed (Anonymous 1993). After 1956 the identity of the site was merged with Nike site H-83L (WIDS site 600-13), the use permit terminated in 1960, and the site later destroyed (Anonymous 1993).

Waste Type: Misc. Trash and Debris

Waste Description: The debris at this site included building materials, insulators, glass bottles, tin cans, cable, and other garbage. Two septic tanks openings were discovered at this site. These tanks were filled with 12.2 cubic meters (16 cubic yards) of concrete. The debris was picked up. An area of petroleum-contaminated soil around a concrete well structure was excavated and five 208 liter (55-gallon) drums of contaminated soil were removed.

Closure Info: Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-76

Classification: Accepted

Names: 600-76; Underground Rooms; Wahluke Slope Radar Site

Reclassification Rejected (1/30/2003)

Type: Military Compound

Start Date:

Status: Inactive

End Date:

Description: The waste site has been evaluated and reclassified to Rejected. The site is roughly oval,

approximately 400 meters (1/4 mile) by 370 meters (400 yards), and surrounded by a gravel.

Location: The site is a radar site with underground rooms on Wahluke Slope, north of the 100H area and just north of Highway 24. It is southeast of PSN 04 (600-15).

Closure Info: Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-77

Classification: Accepted

Names: 600-77; Antiaircraft Gun Shrapnel Sites 1, 2, and 3; Wahluke Slope Shrapnel Sites

Reclassification Rejected (1/30/2003)

Type: Military Compound

Start Date:

Status: Inactive

End Date:

Description: The waste site has been evaluated and reclassified to Rejected. The shrapnel sites are three nearby but separate areas containing shrapnel from antiaircraft gun firing on the North Slope.

Location: There are three shrapnel sites located on the North Slope. Site 1 is east of 100-H area and north of the electrical transmission lines, 1/2 mile north of the White Bluffs boat landing, west of the old highway (Section 22, T 14N, R 27E). Site 2 is located northeast of 100F area, north of the railroad track, south of Highway 24, and northeast of PSN 12/14 (Section 8, T 14N, R 28E). Site 3 is located north of 100-D Area and south of the Igloo Site in the Saddle Mountain National Wildlife Refuge (Section 2, T 14N, R 26E).

Waste Type: Ordnance

Waste Description: Two pieces of aluminum or magnesium shrapnel have been found at Shrapnel Site 2. Two pieces of iron or steel shrapnel have been found at Shrapnel Site 3. At the major shrapnel area, Shrapnel Site 1, it is reported that over 100 lbs (45 kg) of shrapnel has been found. Shrapnel consists of iron fragments and aluminum or magnesium fuze ring pieces.

Closure Info: Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-78

Classification: Accepted

Names: 600-78; Power Pole 12-3 Cistern; 12-3 Cistern

Reclassification Rejected (1/30/2003)

Type: Catch Tank

Start Date:

Status: Inactive

End Date:

Description: The cistern is approximately 1.5 meters (5 feet) in diameter by 2.4 meters (8 feet) deep. Debris was removed and it was filled with gravel.

Location: The site is located east-southeast of the 100F Area, on the opposite side of the Columbia River. It is near power pole 12-3, and close to the point where the electrical transmission lines change direction from northeast to north. (SW 1/4 of NW 1/4 Section 8, T 13N, R 28E)

Waste Type: Demolition and Inert Waste

Waste Description: The homestead cisterns were relatively free of debris, except for wood. The cistern was filled with approximately 10 yards (7.7 m) of pit-run gravel. Nearby debris has been removed.

Closure Info: Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in

2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-79 **Classification:** Accepted
Names: 600-79; Wahluke Slope Clay Pit Cistern **Reclassification** Rejected (1/30/2003)
Type: Catch Tank **Start Date:**
Status: Inactive **End Date:**

Description: The waste site has been evaluated and reclassified to Rejected. The clay pit cistern was a circular, concrete-lined pit approximately 1.7 meters (5 feet 6 inches) deep and 1.5 meters (5 feet) wide that has been backfilled with gravel. It is located near a pit that was used to obtain clay for lining irrigation canals. No obvious disposal pits remain from the homestead.

Location: Northeast of 100H area, on the opposite side of the Columbia River. It is north of Highway 24, south of the Wahluke Branch Canal, and east of the White Bluffs Wasteway. (SE 1/4 of NE 1/4 Section 27, T 15, R 27E)

Waste Type: Demolition and Inert Waste

Waste Description: The debris at this site included glass bottles, tin cans, asbestos pipe, and other garbage.

Closure Info: Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-80 **Classification:** Accepted
Names: 600-80; Wahluke Slope Cow Camp Cistern **Reclassification** Rejected (1/30/2003)
Type: Catch Tank **Start Date:**
Status: Inactive **End Date:**

Description: The waste site has been evaluated and reclassified to Rejected. The cistern was approximately 1.4 meters (4 feet 9 inches) in diameter and has been backfilled with gravel. A depth value was not estimated during original site investigation because the cistern was filled with debris at that time.

Location: Located northeast of the 100H Area, south of the Wahluke Branch Canal and north of Highway 24. (SE 1/4 of NE 1/4 of Section 26, T 15, R 27E)

Waste Type: Demolition and Inert Waste

Waste Description: The debris at this site included glass bottles, tin cans, and other garbage. Several of the empty bottles were from livestock antibiotic and pesticide for delousing cattle.

Closure Info: Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-81 **Classification:** Accepted
Names: 600-81; Wahluke Slope Homestead Cistern **Reclassification** Rejected (1/30/2003)
Type: Settling Tank **Start Date:**

Status: Inactive**End Date:****Description:** The waste site has been evaluated and reclassified to Rejected. The site is a pre-Hanford cistern that measured approximately 1.52 to 1.83 meters (5 to 6 feet) in diameter. It has been backfilled with gravel.**Location:** East-northeast of the 100F area, southeast of the area where the north-south electrical transmission line crosses the east-west electrical transmission line.**Waste Type:** Misc. Trash and Debris**Waste Description:** The debris at the bottom of the cistern appeared to be homestead-associated food containers.**Closure Info:** Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.**Code:** 600-82**Classification:** Accepted**Names:** 600-82; Wahluke Slope Overlook Cistern**Reclassification:** Rejected (1/30/2003)**Type:** Catch Tank**Start Date:****Status:** Inactive**End Date:****Description:** The waste site has been evaluated and reclassified to Rejected. In 1990 there were two unfenced cisterns at this homestead location. One cistern measured 2.5 meters (8 feet) in diameter and 4.3 meters (14 feet) deep, and the other was 1 meter (3.5 feet) across by 1.2 meter**Location:** This site is on Wahluke Slope northeast of the Hanford townsite, southeast of 100F area, and near the bluffs overlooking the Columbia River.**Waste Type:** Demolition and Inert Waste**Waste Description:****Closure Info:** Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.**Code:** 600-83**Classification:** Accepted**Names:** 600-83; Wahluke Slope Stock Tank Cistern**Reclassification:** Rejected (1/30/2003)**Type:** Catch Tank**Start Date:****Status:** Inactive**End Date:****Description:** The waste site has been evaluated and reclassified to Rejected. The stock tank cistern is approximately 3.7 meters (12 feet) by 3.7 meters (12 feet) by 1.2 meters (4 feet) deep with the top of the tank about 0.6 meters (2 feet) above the ground surface. In 1990 there were many metal cans in the area, as well as lumber used for fencing and corrals. No homestead structure was found. A well with an approximate 20 centimeters (8 inches) diameter casing is north of the tank cistern.**Location:** The site is located on the opposite side of the Columbia River, east-northeast of 100-F Area, near the electrical transmission lines. It is on a power line road that ends at the Wahluke Branch Wasteway. A large sand dune is at the east end of the road. The cistern is at the southwest end

of the sand dune. (NW 1/4 of SW 1/4 Section 29, T 14N, R 28E)

Waste Type: Demolition and Inert Waste

**Waste
Description:**

Closure Info: Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-84

Classification: Accepted

Names: 600-84; Wahluke Slope Wagon Road Cistern

Reclassification Rejected (1/30/2003)

Type: Catch Tank

Start Date:

Status: Inactive

End Date:

Description: The waste site has been evaluated and reclassified to Rejected. The cistern is approximately 2.4 meters (8 feet) in diameter by 2.4 meters (8 feet) deep.

Location: The cistern is located on Wahluke Slope, east of the 100F Area and north-northwest of the Hanford townsite on the opposite side of the Columbia River. (NW 1/4 of NE 1/4 Section 6, T 13N, R 28E)

Waste Type: Demolition and Inert Waste

Waste Description: Debris at this site included glass bottles, tin cans, and other garbage.

Closure Info: Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-85

Classification: Accepted

Names: 600-85; Wahluke Slope Stove Cistern

Reclassification Rejected (1/30/2003)

Type: Catch Tank

Start Date:

Status: Inactive

End Date:

Description: The waste site has been evaluated and reclassified to Rejected. This cistern is located on Wahluke Slope, east of 100-F Area, east-southeast of 100-H Area.

Waste Type: Demolition and Inert Waste

**Waste
Description:**

Closure Info: Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-86

Classification: Accepted

Names: 600-86; Wahluke Slope Wasteway Cistern

Reclassification Rejected (1/30/2003)

Type: Catch Tank**Start Date:****Status:** Inactive**End Date:****Description:** The waste site has been evaluated and reclassified to Rejected. The cistern was approximately 2.4 meters (8 feet) in diameter by 0.9 meters (3 feet) deep. The walls were partially collapsed. In 1990, it was reported that the cistern was mostly destroyed and filled in. The cistern has been backfilled with gravel.**Location:** The cistern is located on Wahluke Slope, northeast of 100H Area, near the Wahluke Branch Canal and the White Bluffs Wasteway. (SE 1/4 Section 22, T 15N, R 27E)**Waste Type:** Demolition and Inert Waste**Waste Description:** Debris at this site included glass bottles, tin cans, cable, concrete, and other garbage.**Closure Info:** Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-87**Classification:** Accepted**Names:** 600-87; Wahluke Slope Dune Homestead**Reclassification** Rejected (1/30/2003)**Type:** Dumping Area**Start Date:****Status:** Inactive**End Date:****Description:** The waste site has been evaluated and reclassified to Rejected. The homestead site contained buildings and a domestic trash disposal area.**Location:** It is located on Wahluke Slope, east of 100F Area and northeast of the Hanford Townsite on the opposite side of the Columbia River. The homestead is near a series of sand dunes. (SW 1/3 of NE 1/4 Section 32, Y 14N, R 28E)**Waste Type:** Misc. Trash and Debris**Waste Description:** Debris consisted of domestic trash, parts of a barn or shed, parts of a flour mill, carriage pieces and a harness.**Closure Info:** Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-88**Classification:** Accepted**Names:** 600-88; Wahluke Slope Lonetree Homestead**Reclassification** Rejected (1/30/2003)**Type:** Dumping Area**Start Date:****Status:** Inactive**End Date:****Description:** The waste site has been evaluated and reclassified to Rejected. The site contains a single live cherry tree, several dead trees and some small disposal areas. No above ground structures remain.**Location:** The site is located on Wahluke Slope, east-northeast of the Hanford Townsite and southeast of the 100F Area, on the opposite side of the Columbia River. (SE 1/4 of NW 1/4 Section 20, T 13N, R 28E)

Waste Type: Misc. Trash and Debris

Waste Description: Debris consisted of metal cans and broken glass.

Closure Info: Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-89

Classification: Accepted

Names: 600-89; Wahluke Slope Asphalt Batch Plant

Reclassification Rejected (1/30/2003)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The waste site has been evaluated and reclassified to Rejected. The site is a graveled area about 0.8 hectares (2 acres) in size located on the Wahluke Slope. The site is north-northeast of the 100-D Area and south of Highway 24. It was apparently used as a temporary batch plant for mixing asphalt for paving operations. Two adjacent pits on site were empty. Another 4.6- by 4.6-meters (15- by 15-feet) area was used for disposal of concrete. The original users of the area are unknown.

Location: The site is located on Wahluke Slope, north-northeast of the 100-D Area and south of Highway 24. (NE 1/4 Section 4, T 14N, R 26E)

Waste Type: Demolition and Inert Waste

Waste Description: Debris from this site included asphalt, concrete, sheet metal, and other debris.

Closure Info: Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-90

Classification: Accepted

Names: 600-90; Wahluke Slope Coyote Bait Can/Bait Station

Reclassification Rejected (1/30/2003)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The waste site has been evaluated and reclassified to Rejected. This unit is composed of two separate sites, both on Wahluke Slope. The Coyote Bait Can was located southeast of 100F area and northeast of the Hanford Townsite. A large military ammunition box was partially buried at this site. The lid of the box was marked "BAIT CAN." Evidence in the area suggested that it was once used to store bait for coyote trapping. The Coyote Bait Station was east of the bait can, near the eastern edge of the wildlife area. At this location, over 50 coyote skulls were counted. Large animal bones in the area indicated that a poisoned carcass was most often used for bait. Historical records report that trappers would poison horse carcasses to attract and kill the coyotes for their pelts. Bones at this location were old and may predate government control of the land.

Location: The sites are located southeast of 100-F Area on the opposite side of the Columbia River on Wahluke Slope. (SW 1/4 Section 18, T 13N, R 28E and NE 1/4 Section 17, T 13N, R 28E)

Closure Info: Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-91 **Classification:** Accepted
Names: 600-91; Pit 47; Wahluke Slope Gravel Pit #47 **Reclassification** Rejected (1/30/2003)
Type: Depression/Pit (nonspecific) **Start Date:**
Status: Inactive **End Date:**

Description: The waste site has been evaluated and reclassified to Rejected. The site is made up of two gravel pits. The smaller pit had been used as a disposal area.

Location: The site is located on Wahluke Slope, northeast of 100B Area, 1/4 mile south of Highway 24 at mile marker 47.

Waste Type: Misc. Trash and Debris

Waste Description: The debris at this site included building materials, glass bottles, tin cans, paint cans, cable, concrete, oil cans, and other garbage in the far pit. There was a significant amount of oil contaminated soil.

Closure Info: Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-92 **Classification:** Accepted
Names: 600-92; Borrow Pit #56; Pit 56; Wahluke Slope Gravel Pit #56 **Reclassification** Rejected (1/30/2003)
Type: Depression/Pit (nonspecific) **Start Date:**
Status: Inactive **End Date:**

Description: The waste site has been evaluated and reclassified to Rejected. The site consists of several soil borrow pits.

Location: The site is located on Wahluke Slope, north-northwest of 100D Area and north of Highway 24.

Waste Type: Demolition and Inert Waste

Waste Description: Debris included communications wire, timbers, bottles, cans, barbed wire fencing, and fence posts. Potentially hazardous items identified included one 19 liter (5-gallon) can full of dead beetles (possible herbicide/insecticide) and two 19 liter (5-gallon) oil cans with liquid.

Closure Info: Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-93 **Classification:** Accepted
Names: 600-93; Hanford Firing Range **Reclassification** Rejected (1/30/2003)
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The waste site has been evaluated and reclassified to Rejected. The range was used by the original Hanford Site security force for target practice. A bench has been cut out of the bluff measuring approximately 100 yards long. Some 55 gallon drums were placed at the base of the bluff along the bench to serve as targets. Numerous spent bullets have been found in the target area. A burial trench located west of the firing range contained empty metal ammunition boxes.

Location: The site is located across the Columbia River from the Hanford Townsite. (N 1/2 Section 30, T 13N, R28E)

Closure Info: Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-94

Classification: Accepted

Names: 600-94; Wahluke Schoolhouse

Reclassification Rejected (1/30/2003)

Type: Foundation

Start Date:

Status: Inactive

End Date:

Description: The waste site has been evaluated and reclassified to Rejected. This site is an old schoolhouse located on the Wahluke Slope. Only the concrete front steps remain to this old schoolhouse. The school structure has been removed. The steps were apparently preserved because a USGS survey marker is imbedded in the top step. This site is not at the townsite of Wahluke.

Location: Located north of the 100B Area, near the north shore of the Columbia River.

Closure Info: Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-95

Classification: Accepted

Names: 600-95; Bridge Overlook Site; Wahluke Slope
Bridge Disposal Area

Reclassification Rejected (1/30/2003)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The waste site has been evaluated and reclassified to Rejected. The site consisted of two separate areas, both of which were littered with old lumber and lesser amounts of glass and metallic debris. In 1990, it was reported that the site contained the remains of three or four wood frame structures, with roofing material, window screen, railroad ties, structural lumber, personal items such as toothbrushes and razors, and military oil cans. The debris has been removed.

Location: The unit is at the top of the hill north of Vernita Bridge, northwest of 100-B/C Area.

Related Sites/ PSN-72/82

Structures:

Waste Type: Demolition and Inert Waste

Waste Debris at this site included building materials, wood, glass, wire mesh, and paper products.

Description: Trash includes items that appear to be of military origin such as tooth brushes, razors, bottles, cans and military oil cans.

Closure Info: Final: Thirty five sites on the Wahluke Slope were grouped onto one Reclassification form in 2003 and their status was changed to Rejected. They were cleaned up by DOE as part of a landlord activity, not a CERCLA activity.

Code: 600-96 **Classification:** Not Accepted

Names: 600-96; 618-10 Borrow Pit **Reclassification:** None

Type: Depression/Pit (nonspecific) **Start Date:**

Status: Inactive **End Date:**

Description: The site is sandy and mostly unvegetated. The site has been scraped for material to cover the adjacent burial ground. No waste was observed in the area in 1995, except for a large pile of tumbleweeds that were removed from the fence surrounding the 618-10 Burial Ground.

Location: The site is located west of Route 4 South between milepost 17 and 18. It is adjacent to the southwest corner of the 618-10 Burial Ground.

Related Sites/ Structures: The 618-10 Burial Ground is associated with the unit.

Waste Type: Vegetation

Waste Description: A large pile of tumbleweeds was observed.

Code: 600-97 **Classification:** Not Accepted

Names: 600-97; 618-11 Borrow Pit **Reclassification:** None

Type: Depression/Pit (nonspecific) **Start Date:**

Status: Inactive **End Date:**

Description: The site is located in a slight depression where 0.3 to 0.6 meters (1 to 2 feet) of soil has been removed to cover the 618-11 Burial Ground.

Location: The site is located approximately 1,500 meters (4,920 feet) west, northwest of Washington Public Power Supply System Plant Number 2 and just north of the 618-11 Burial Ground.

Code: 600-118 **Classification:** Accepted

Names: 600-118; Contaminated Soil Northwest of Gable Mountain Pond; Hot Spot Northwest of Gable Mountain Pond **Reclassification:** Consolidated (4/26/2000)

Type: Ditch **Start Date:**

Status: Inactive **End Date:**

Description: This overflow site has been consolidated with its source, the 216-A-25 Gable Mountain Pond. The stabilized site begins northwest of 216-A-25 Pond, and was formerly an overflow trench from 216-A-25 (Gable Mountain Pond) that ran north-south, approximately 0.9 meters (6 feet) deep. The site extends north, under the power lines where the site widens. The trench deepened again north of the power lines, so the site is narrower there, and fades out in a wider, but shallower area at the north end. The area outside the stabilized area is vegetated with sagebrush and cheatgrass. The stabilized area is sparsely vegetated with cheatgrass, crested

wheatgrass, and Sandberg's bluegrass. The area is posted as an "Underground Radioactive Material" area.

Location: The site is located adjacent to (north side) the 216-A-25 (Gable Mountain Pond) stabilized overflow area.

Related Sites/ Structures: This site is an overflow area from 216-A-25 (Gable Mountain Pond), as evidenced by aerial radiation surveys and topographic relief maps showing a naturally downward flow direction toward this overflow area for water in Gable Mountain Pond.

Waste Type: Soil

Waste Description: The waste site was identified in the 1996 Flyover Survey and reported on April 11, 1996.

This Site Was Consolidated With:

Code: 216-A-25

Names: 216-A-25; 216-A-25 Swamp; Gable Mountain Pond; Gable Mountain Swamp; Gable Pond

Code: 600-121

Classification: Accepted

Names: 600-121; Coal Ash Piles; White Bluffs Coal Ash Piles

Reclassification: Rejected (10/6/1997)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site is several small coal ash piles located just east of the Pickling Acid Cribs.

Location: The site is located south of Federal Avenue and west of Route 2 North. The site is just east of the White Bluffs Pickling Acid Cribs (600-106).

Waste Type: Ash

Waste Description: The waste is coal ash that has been placed in piles (discernible units).

Code: 600-122

Classification: Not Accepted

Names: 600-122; White Bluffs Large Fenced Depression

Reclassification: None

Type: Depression/Pit (nonspecific)

Start Date:

Status: Inactive

End Date:

Description: The eastern boundary of the site once was a power distribution line and powerline road. Power poles were removed by cutting them off just above the ground surface. Glass insulator material litters the area. Just west of this powerline is the fencing that surrounds the site. The fence is wood post and wire enclosure that appears to have been installed to keep deer out of the area. The fence is in very poor condition.

Location: The site is located west of Route 2 North and south of Federal Avenue, adjacent to a powerline road. It is southwest of the White Bluffs Pickling Acid Cribs (600-106).

Code: 600-123

Classification: Not Accepted

Names: 600-123; Farm Site; White Bluffs Farm Site

Reclassification: None

Type: Dumping Area**Start Date:****Status:** Inactive**End Date:**

Description: The site was a farm site. One source indicates that it may have been occupied by the army for a period of time indicates the site is littered with waste debris, including battery cores, broken glass, concrete, cans, bottles, wire, machinery parts, and other domestic wastes (Carpenter, 1994). A site visit done on August 16, 1996 did not find any battery cores or evidence of military debris. Two of the building foundations are deep and open to the surface. One of these is filled with concrete rubble, piping and debris. There is one concrete slab that could be a building foundation and one small concrete structure that is approximately 1.2 meters (4 feet) by 0.9 meters (3 feet) and is approximately 0.9 meters (3 feet deep).

Location: The site is located west of Route 2 North and south/southeast of Federal Avenue. It is southwest of the White Bluffs Large Fenced Depression (600-122) and approximately 1700 meters (1.1 miles) southwest of the intersection of Route 2 North and Federal Avenue.

Waste Type: Misc. Trash and Debris

Waste Description: The waste is farm debris, including sheep fencing, irrigation and other farming equipment, scattered household debris, and foundations for buildings. No evidence of army occupation remains. There is no evidence of any hazardous materials, and is a residential, not industrial site.

Code: 600-126**Classification:** Not Accepted**Names:** 600-126; Small Subsidence; White Bluffs Small Subsidence**Reclassification:** None**Type:** Depression/Pit (nonspecific)**Start Date:****Status:** Inactive**End Date:**

Description: The site is a subsurface concrete structure that appears to be about 1.2 meters (4 feet) across. Soil around the structure has subsided into its underground void space. A few feet behind is a vertical pipe that opens into the void beneath the structure.

Location: The site is on a low rise located west of Route 2 North and north of Federal Avenue. It is 650 meters (2133 feet) southwest of the intersection of Federal Avenue and Route 2 North.

Related Sites/ Structures: 600-126, 600-166, 600-165 and 600-170 all appear to be part of a related underground piping system.

Waste Type: Construction Debris

Waste Description: Concrete

Code: 600-130**Classification:** Not Accepted**Names:** 600-130; American Pipe Company Facilities; Stephensen's Cement Pipe Factory**Reclassification:** None**Type:** Fabrication Shop**Start Date:****Status:** Inactive**End Date:**

Description: The site consists of remnants of the following facilities: valve box and 2 inch water line, concrete foundation, warehouse foundation, concrete sump attached to warehouse foundation,

debris pile, foundation, potential smokestack base, and small subsidences that appear to be rotted wooden poles. The area is littered with wood, metal parts, glass, burned building materials, and debris.

Location: The site is located northeast of Route 2 North, northwest of Federal Avenue, and northwest of the White Bluffs townsite. It is approximately 700 meters (2297 feet) north/northwest of the intersection of Route 2 North and Federal Avenue.

Waste Type: Misc. Trash and Debris

Waste Description: The waste is miscellaneous trash and debris consisting of wood, metal parts, glass, burned building materials, and debris.

Code: 600-135

Classification: Accepted

Names: 600-135; Horseshoe Pit; Spare Parts Machine Shop Landfill; White Bluffs Spare Parts Machine Shop Landfill and Pit

Reclassification: Rejected (1/26/1998)

Type: Burial Ground

Start Date:

Status: Inactive

End Date:

Description: This unit includes two potential waste sites. One site is called the Spare Parts Machine Shop Landfill, also known as the horseshoe pit. It was once a borrow pit that was later used as a waste disposal site. The borrow pit was dug in a semicircle to the northeast of nearby warehouses (hence the name horseshoe pit). The site appears to have been backfilled over about one-half to two-thirds of its area. The second site is a pit oriented in the east-west direction located directly west of Spare Parts Machine Shop Landfill. This pit measures about 90 meters (300 feet) long by 40 meters (130 feet) wide. No documentation could be found to indicate the purpose of the pit.

Location: The site is located northeast of Route 2 North, northwest of Federal Avenue and southwest of the export water line road. The site is approximately 700 meters (2297 feet) northeast of the intersection of Route 2 North and Federal Avenue and almost due west of the intersection of Federal Avenue and the export water line road.

Related Sites/Structures: A DuPont drawing indicates that the southwest corner of the site was the location of the MS-9 Warehouses. The same drawing indicates a well in the vicinity of the warehouses.

Waste Type: Asbestos (non-friable)

Waste Description: The entire area was covered with scattered transite siding.

Waste Type: Equipment

Waste Description: Equipment parts and pieces are scattered about the area.

Code: 600-136

Classification: Not Accepted

Names: 600-136; Insulation Warehouses; White Bluffs Insulation Warehouses

Reclassification: None

Type: Storage

Start Date:

Status: Inactive

End Date:

Description: The site is a warehouse area within the White Bluffs townsite. It is covered with cheatgrass with some rabbitbrush and tumbleweed growth. There is very little evidence of the former warehouse buildings except for a few pieces of wood. Pavement from the former Lincoln St. shown in the referenced documents is still visible south of the site and aided identifying the precise location in the field. There was no evidence of asbestos at the site.

Location: The site is located within the old townsite of White Bluffs, north of Federal Avenue and west of Route 2 North. It is approximately 160 meters (525 feet) northwest of the intersection of Route 2 North and Federal Avenue. Source documents show it's location on the north corner of the former Lincoln Street and Railroad Avenue, which remain visible.

Process This warehouse was used for insulation materials.

Description:

Code: 600-138 **Classification:** Not Accepted

Names: 600-138; Fumigation Chamber Building; White Bluffs Fumigation Building **Reclassification** None

Type: Maintenance Shop **Start Date:**

Status: Inactive **End Date:**

Description: The site is the remains of a fumigation building. A field investigation was performed by T. F. Johnson on October 15, 1996. The terrain was flat with gravel surface soil and had cheatgrass and rabbitbrush vegetation. Very little evidence of the fumigation building remained at the site. A few pieces of wood and concrete were observed in the area. A standing wooden post remained near the site which may have been part of the fence surrounding the building.

Location: The site is located approximately 220 meters (722) west of the intersection of Route 2 North and Federal Avenue and approximately 150 meters (492 feet) northwest of the corner of Commercial Avenue and Federal Avenue. The building was located about 37 meters (120 feet) northeast of Commercial Avenue.

Process The building was used primarily to fumigate bedding materials.

Description:

Code: 600-140 **Classification:** Not Accepted

Names: 600-140; Gunny Sacks South of H-70 Antiaircraft Site **Reclassification** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The site is partially buried empty gunny sacks that appear to have been abandoned. The site was found on 01/11/95 during the Riverland field investigation.

Location: The site is located in the northwest portion of the Hanford Site, north of highway SR24, west of highway SR240 and approximately 1.9 kilometers (1.2 miles) west of gate 122 from highway SR240 and approximately 550 feet (170 meters) south southwest of the former antiaircraft site H-70 (Site Code 600-41).

Waste Type: Misc. Trash and Debris

Waste The sacks were constructed of natural fibers.

Description:

Code: 600-141 **Classification:** Not Accepted

Names: 600-141; Barrels South of H-70 Antiaircraft Site **Reclassification:** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The site is two empty containers. One container is an empty 113 liter (30 gallon) drum painted army green and yellow paint. The other container appears to be an empty garbage can. Both containers are partially buried. No labels or markings were visible on the containers that would identify what they were used for.

Location: The site is located in the northwest portion of the Hanford Site, north of highway SR24, west of highway SR240 and approximately 1.9 kilometers (1.2 miles) west of gate 122 from highway SR240 and approximately 240 meters (800 feet) south of the former antiaircraft site H-70 (Site Code 600-41).

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: An empty steel drum and a garbage can were found at the site.

Code: 600-142 **Classification:** Accepted

Names: 600-142; Car Body at McGee Ranch Fish Farm **Reclassification:** Rejected (2/9/1998)

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The site is an abandoned automobile. The car is resting upside down on its roof and has been partially crushed. The engine, transmission, differential, and radiator remain in the car. No battery was found, the radiator appeared empty and no visible leaks of automotive fluids were observed.

Location: The site is located in the northwest portion of the Hanford Site, north of highway SR24, west of highway SR240 and approximately 1.1 kilometers (0.7 miles) west driving from gate 121 on highway SR240. The car is located at the McGee Ranch Fish Farm site, approximately 140 meters (450 feet) north of the McGee Well.

Waste Type: Equipment

Waste Description: The auto body is constructed of sheet metal and a steel frame.

Waste Type: Oil

Waste Description: The engine, transmission, and differential may contain oil or oil residue.

Code: 600-143 **Classification:** Not Accepted

Names: 600-143; Car Body at Ford Well **Reclassification:** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The site is a car body only. The engine, transmission, radiator, and battery have been removed. Several bullet holes were observed in the car body.

Location: The site is located in the northwest portion of the Hanford Site, north of highway SR24 and west of highway SR240. From gate 121 on SR 240 just north of the Yakima Barricade, drive west 0.8 kilometers (0.5 miles) to the T. Turn left and follow the main road south and then west for 3.2 kilometers (2.0 miles) to well site 699-49-111. Turn right, and drive north 1.1 kilometers (0.7 miles) to the site, just past the Ford Well site. The car body located approximately 180 feet (55 meters) north of the Ford Artesian Well.

Waste Type: Equipment

Waste Description: The car body is constructed of sheet metal and a steel frame.

Code: 600-144 **Classification:** Not Accepted

Names: 600-144; Car Body Near Top of Umptanum Ridge **Reclassification:** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The site is a car body only. The engine, transmission, radiator and battery have been removed. Several bullet holes were observed in the car.

Location: The site is located in the northwest portion of the Hanford Site, north of highway SR24 and west of highway SR240 and approximately 2.9 kilometers (1.8 miles) west northwest of gate 122 from highway SR 240 and approximately 0.2 kilometers (1/8 mile) south of the crest of Umptanum Ridge, on the east flank, just west of the road than leads to the ridge crest.

Waste Type: Equipment

Waste Description: The car body is constructed of sheet metal and a steel frame.

Code: 600-147 **Classification:** Not Accepted

Names: 600-147; Wood Shack (Northwest of Gable Mountain) **Reclassification:** None

Type: Office **Start Date:**

Status: Inactive **End Date:**

Description: The site is an old, very weathered, one-room wooden shack with a gable roof, one door, one window per side, and central heater, mounted on two wooden skids. It has at least 12 wells within 50 meters (160 feet), and is probably a well driller's shed, used to shelter the crews and hold equipment when the nearby wells were installed.

Location: The site is located on the north side of Gable Mountain and just north of the dirt road that runs east west along the north side of Gable Mountain. However, the shed is not visible from the road, because of a small rise between the road and shed. The site is best accessed by turning east just north of milepost 2 on Route 4 North. Continue east on the paved road until the road begins to turn up the mountain. At this point, continue straight ahead on the dirt road which continues east along the mountain. The site is located approximately 2.1 miles east from Route 4 North and east of the high voltage power lines that cross the dirt road. Follow a rough road leading north from the east-west road.

Waste Type: Equipment
Waste Description: The site is a small weathered, wooden building.

Code: 600-148 **Classification:** Accepted
Names: 600-148; Environmental Restoration Disposal Facility; ERDF **Reclassification:** None
Type: Landfill (Lined) **Start Date:** 7/1/1996
Status: Active **End Date:**

Description: Designed to be expanded as needed, ERDF comprises a series of cells or disposal areas. Each pair of cells is 70 feet deep, and 500 feet by 1,000 feet at the base, large enough to hold about 2.8 million tons of material. The fourth and largest expansion of ERDF was completed in January 2011. Two "super cells," each the equivalent of a pair of existing cells, were constructed using Recovery Act funds. Additional upgrades included new maintenance facilities, additional dump ramps and additional transfer areas for waste containers, all of which will enhance the safety of increased, daily operations.

With the addition of super cells 9 and 10, ERDF capacity is 16.4 million tons. At the 70-foot-base, ERDF covers the same areas as 52 football fields. To date (2011), nearly 11 million tons of contaminated material has been disposed in the facility. One of the key components of ERDF is the liner that is built into each cell. The liner consists of multiple layers of plastic and other impermeable materials and a system to collect and removed liquids as they drain through the waste materials. ERDF does not accept liquid waste for disposal, but water enters the facility when it rains and snows, and water also is used for dust control during routine operations. The collected water, or leachate, is collected and routed to an onsite treatment facility. After treatment, the liquid is clean enough to be returned to the ground with no harm to the environment.

Location: The Environmental Restoration Disposal Facility (ERDF) is located southeast of the 200 West Area and southwest of the 200 East Area.

Related Sites/Structures: Leachate collected at the landfill is transported to the 200 Area Effluent Treatment Facility, located in the 200 East Area via pipelines 600-399-PL and 600-401-PL.

Process Description: Built in 1996, ERDF accepts low-level radioactive, hazardous, and mixed wastes that are generated during the cleanup activities at the Site. It does not accept any non-Hanford waste. After each load is placed into ERDF, it is compacted. Earth movers equipped with high-tech ground monitoring equipment drive over the waste to eliminate any air pockets or gaps in the landfill. Hollow tubes or pipes are either filled with a cement material or are cut into pieces. This ensures there are no void spaces in the facility, which could result in the landfill sagging or settling, which could cause damage to the permanent cap that ultimately will cover the entire facility when it is no longer needed. In the meantime, a temporary cap is placed over cells as they are filled.

Waste Type: Equipment
Waste Description: The total volume of waste is expected to be less than 2.14E+07 cubic meters (2.8E+07 cubic yards) is expected to consist of approximately 10% to 15% wastewater pipelines, ancillary equipment, and associated soil contamination.

Waste Type: Soil
Waste Description: The total volume of waste is expected to be less than 2.14E+07 cubic meters (2.8E+07 cubic yards) and is expected to consist of approximately 65% to 75% contaminated soil and

demolition debris.

Waste Type: Misc. Trash and Debris

Waste Description: The total volume of waste is expected to be less than 2.14E+07 cubic meters (2.8E+07 cubic yards) and is expected to consist of approximately 15% to 20% burial ground waste.

Code: 600-153

Classification: Not Accepted

Names: 600-153; Dumping Area Between River Mile Markers 29 and 30

Reclassification: None

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site is pre-Hanford debris, such as a metal strong box, car springs, broken dishes, barbed wire, and wood.

Location: The site is located between mile markers 29 and 30 approximately 50 meters (50 yards) from the water or 0.4 kilometers (1/4 mile) south of river mile marker 29 on the west bank of the Columbia River.

Waste Type: Misc. Trash and Debris

Waste Description: Observed debris includes a metal strong box, car springs, culvert, piping, wire, barbed wire, old piping, glass, broken dishes, metal culvert and wood.

Code: 600-154

Classification: Not Accepted

Names: 600-154; RCRA General Inspection HIRIV-FY96 Item #6; Remains of Windmill

Reclassification: None

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site is the remaining parts from an old windmill. The windmill was constructed of sheet metal and steel. An abandoned well was observed approximately 90 meters (295 feet) southwest of the windmill.

Location: The site is located due north of 100-D Area and approximately 50 meters (165 feet) north of the left bank (facing downstream) of the Columbia River. On the USGS Map Coyote Rapids Quadrangle 7.5 minute series, the site is located about 200 meters (656 feet) east of the intersection labeled "Wahluke". If driving to the site, take the only paved road from highway SR24 to the river.

Waste Type: Equipment

Waste Description: The waste is parts from an old windmill which was constructed of sheet metal and steel.

Code: 600-155

Classification: Not Accepted

Names: 600-155; Dumping Area Upstream of River Mile Marker 35 Identified During RCRA General Inspection #HIRIV-FY96 Item #7

Reclassification: None

Type: Dumping Area

Start Date:

Status: Inactive**End Date:**

Description: The site consists of an old rusty machine part with approximate dimensions of 1.8 meters by 1.2 meters by 0.6 meters (6 feet x 4 feet x 2 feet). The part is marked with a small metal tag "USA-HEW 355464/ Property of US Government." The surrounding soil is silty sand and cobbles, with moderate cheatgrass and bunchgrass vegetation. Nearby flood debris consists of tree branches and small logs. There are no other large pieces of metal or construction type material. The surface of the access road is sand and gravel.

During visits to the site on February 1, 1999, and February 3, 1999, other debris was observed. This debris included a chunk of concrete, an old muffler, a piece of metal that looked as though it could have come from the piece of machinery, other metal debris, a tire and wood debris (not flood debris). This miscellaneous debris is primarily south of the piece of machinery and most is within 100 meters (328.1 feet). A field visit on July 19, 1999, verified that the large piece of equipment had been removed. A small piece of metal (approximately 0.46 meters (18 inches) in length) remained half buried in the soil.

Location: The site is approximately 250 meters (810 feet) upstream from mile marker 35 and approximately 80 meters (260 feet) from the river shoreline. The site is visible from the road.

Related Sites/ Structures: The origin of this piece of equipment is unknown.

Process Description: The purpose of this piece of equipment is unknown.

Waste Type: Equipment

Waste Description: The waste is steel scrap. The metal tag contains "USA-HEW-355464". "HEW" stands for Hanford Engineering Works which was the name used during the era of reactor construction. Therefore, the material is not pre-Hanford historic waste.

Code: 600-156**Classification:** Accepted**Names:** 600-156; Construction Debris Dump Site**Reclassification** Rejected (12/7/2005)**Type:** Dumping Area**Start Date:****Status:** Inactive**End Date:**

Description: Scattered fragments of plastic are the only remaining debris at this site, which was formerly used as a construction dump.

Location: This site is on the east side of 200 East Area, east of the southeast corner of the Grout Treatment Facility Landfill (currently the Waste Treatment Plant construction area).

Waste Type: Construction Debris

Waste Description: In 1996, the waste was construction debris consisting of wood, broken concrete and galvanized metal pipe. In April 2002, only scattered fragments of plastic remained.

Code: 600-157**Classification:** Not Accepted**Names:** 600-157; White Bluffs Concrete Foundation Pads**Reclassification** None**Type:** Foundation**Start Date:****Status:** Inactive**End Date:**

Description: The site is described as several concrete foundation pads. Some of these pads have tie-down straps. Apparently these pads were used to support wooden warehouse buildings. The buildings were probably intentionally destroyed by fire, as the ground surface is littered with charred wood, burned electrical equipment (lights, switches, conduit, etc.), and nails.

Location: The site is located north of Federal Avenue and west of Route 2 North. It is approximately 500 meters (1640 feet) west of the intersection of Route 2 North and Federal Ave.

Waste Type: Misc. Trash and Debris

Waste Description: The waste is concrete pads and miscellaneous burned debris (electrical equipment, e.g., lights, switches, conduit, etc. and nails).

Code: 600-158 **Classification:** Not Accepted

Names: 600-158; White Bluffs Ground Storage Tank and Booster Pump Station **Reclassification:** None

Type: Storage Tank **Start Date:**

Status: Inactive **End Date:**

Description: There is an area of reduced vegetation that is a vague circular shape that could where a storage tank once sat. No evidence of a pumping station was found.

Location: The site was located within the White Bluffs Townsite city limits. The ground storage tank and booster pump station were located north of the intersection of Fifth Avenue and Federal Avenue, 475 meters (1558 feet) northeast of the current intersection of Route 2 North and Federal Avenue.

Process Description: The ground storage tank (100,000 gallons) was located adjacent to the booster pump station (16 feet x 20 feet x 10 feet). These facilities were used to handle potable water.

Code: 600-159 **Classification:** Not Accepted

Names: 600-159; White Bluffs Bank Well **Reclassification:** None

Type: Pump Station **Start Date:**

Status: Inactive **End Date:**

Description: The well had been a concrete structure covered with a steel plate and was surrounded by a light-duty steel post and orange barricade material. The well has been backfilled with grout and marked with a metal disk that reads "Well No. A8991, 699-80-39B, Abandoned 9-26-95."

Location: The site is located southeast of the White Bluffs Bank building and east of Route 2 North. It is south of a dirt road that provides access to 100F.

Code: 600-160 **Classification:** Not Accepted

Names: 600-160; White Bluffs Irrigation Debris **Reclassification:** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The site is an area containing concrete irrigation pipe sections. The piping sections are large in diameter and not very long. The site consists of a pipe standing within a large-diameter pipe.

Other debris is scattered across the nearby area.

Location: The site is located west of Route 2 North, south of Federal Avenue, on the west side of a powerline road. It is approximately 975 meters (3199 feet) south of the intersection of Route 2 North and Federal Avenue, west of 600-188, White Bluffs Waste Disposal Trench 2.

Waste Type: Misc. Trash and Debris

Waste Description: The waste is concrete irrigation piping.

Code: 600-161 **Classification:** Not Accepted

Names: 600-161; White Bluffs Plumbing Debris **Reclassification:** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The site consists of two piles of plumbing debris. One pile contains ceramic plumbing fixtures and the other pile contains cast iron plumbing fixtures.

Location: The site is located west of Route 2 North and south of Federal Avenue. It is south of the intersection of Route 2 North and Federal Avenue and east of the White Bluffs Large Fenced Depression (600-122).

Waste Type: Misc. Trash and Debris

Waste Description: The waste is ceramic urinals, sinks, plumbing fixtures and cast iron piping fixtures.

Code: 600-162 **Classification:** Not Accepted

Names: 600-162; White Bluffs Pipe Debris and Bucket of Lead **Reclassification:** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: There had been two debris remnants, one consisting of two 8 inch steel pipe sections embedded in concrete and the second is a bucket of what appeared to be lead. The bucket of lead was removed in 1995.

Location: The site is located west of Route 2 North and south of Federal Avenue. It is 900 meters (2953 feet) south of the intersection of Route 2 North and Federal Avenue on the west side of a powerline road.

Waste Type: Misc. Trash and Debris

Waste Description: The remaining waste is two 8 inch sections of pipe encased in concrete.

Code: 600-163 **Classification:** Not Accepted

Names: 600-163; White Bluffs Pipe Testing Shop **Reclassification:** None

Type: Laboratory **Start Date:**

Status: Inactive**End Date:****Description:** The vague outline of a building footprint was identified at this location.**Location:** The White Bluffs Pipe Testing Shop was located southwest of the intersection of Federal Avenue and Commercial Avenue. It was west of the White Bluffs Main Pipe Fabrication Shop (600-194).**Process Description:** The facility was reportedly used as the quality control test and training facility for welders who worked in the White Bluffs Main Pipe Fabrication Shop.

Code: 600-164**Classification:** Not Accepted**Names:** 600-164; White Bluffs Earth Berm and Trench**Reclassification:** None**Type:** Trench**Start Date:****Status:** Inactive**End Date:****Description:** The earth berm appeared to have been some of the material removed from the trench excavation.**Location:** The site is located east of Route 2 North and north of Federal Avenue. It is approximately 1000 meters (3,281 feet) north/northwest of the intersection of Route 2 North and Federal Avenue and just east of 600-132, White Bluffs Construction Contractor Shop Landfill.

Code: 600-165**Classification:** Not Accepted**Names:** 600-165; White Bluffs Valve Box**Reclassification:** None**Type:** Valve Pit**Start Date:****Status:** Inactive**End Date:****Description:** The site is a subsidence of about one square meter and is lined with concrete, suggesting a valve box or drain system. The subsidence indicates a subsurface structure with a void space that allows overburden to subside into it because of storm runoff. There is a section of power pole laying across the top of the structure.**Location:** The site is located west of Commercial Avenue and northwest of the intersection of Commercial Avenue and Federal Avenue.**Related Sites/ Structures:** 600-126, 600-166, 600-165 and 600-170 all appear to be part of a related underground piping system.

Code: 600-166**Classification:** Not Accepted**Names:** 600-166; White Bluffs Subsidences**Reclassification:** None**Type:** Depression/Pit (nonspecific)**Start Date:****Status:** Inactive**End Date:****Description:** The site is a series of subsidences. A single subsidence measuring approximately four meters (13 feet) in size was originally identified in the White Bluffs Technical Baseline Report. The author of the report suggested that the site may be a subsurface structure with a void space that allowed overburden materials to be washed into it by rain runoff. A RARA Walkdown visit in May 1999 identified three additional, similar subsidences, two of which are in line with the original one. The subsidences found in 1999 measured approximately 1.83 meters (6 feet)

across and 0.9 meters (3 feet) deep.

Location: The site is located west of Commercial Avenue and north of Federal Avenue.

Related Sites/ Structures: 600-126, 600-166, 600-165 and 600-170 all appear to be part of a related underground piping system, such as a sewer system, stormwater collection system or an irrigation system.

Code: 600-167 **Classification:** Not Accepted

Names: 600-167; White Bluffs Cistern **Reclassification:** None

Type: Catch Tank **Start Date:**

Status: Inactive **End Date:**

Description: The site is a large Pre-Manhattan Engineering District concrete cistern. The top of the concrete cistern structure is located slightly below grade level. The hole is almost filled with windblown tumbleweeds. A small portion of the concrete structure was visible on a 1999 site visit.

Location: The site is located west of Route 2 North and south of Federal Avenue. It is northeast of the White Bluffs Loading Docks and Fuel Storage Area (600-127).

Process Description: The cistern was used to store water (not waste water).

Code: 600-168 **Classification:** Not Accepted

Names: 600-168; Buckholdt Ranch Toilet Pits; Herriford Ranch Toilet Pits **Reclassification:** None

Type: Depression/Pit (nonspecific) **Start Date:**

Status: Inactive **End Date:** 1/1/1943

Description: The general area of the ranch is marked by several acres of orchard tree stumps visible from the highway (Route 2 North). The site contains a number of toilet pits (outhouse pits) that remain open. The toilet pits were described as being located between the house foundation and the road to the south. The ground in this area is very uneven and has a rolling surface. During the June 1999 visit, it was observed that much of the southern end of the orchard east of the house foundation has the same undulating ground surface. Several hazards are found near this site, including the house foundation, a wood-lined pit on the north side of the foundation, and the former well or pump house near the south side of the site.

Location: The site is located north of the Hanford townsite and west of Route 2 North. The site is accessed by a dirt road that exits Route 2 North approximately 4.7 kilometers (2.9 miles) north of the intersection of Route 2 and Route 11. It is located north of an east-west dirt road; the travel distance from Route 2 North is approximately 1100 meters (3609 feet, 0.68 miles).

Code: 600-169 **Classification:** Not Accepted

Names: 600-169; Hanford Construction Camp Trenches **Reclassification:** None

Type: Trench **Start Date:**

Status: Inactive **End Date:**

Description: The site is three trenches located south of the Hanford Construction Camp, along the gravel road that is an extension of Avenue A. Each trench runs northwest to southeast and parallels

the road. Spoil piles are pushed to the west side of the trenches. Their purpose is unclear. A 1997 site visit observed a pile of broken concrete between the southern most trench and the adjacent trench.

Location: The site is located southeast of the Hanford Construction Camp. The northernmost trench is 1.5 kilometers (0.9 miles) southeast of the intersection of Avenue A and 9th Street. The trenches range from 77 to 93 meters (253 to 305 feet) southwest of Avenue A.

Code: 600-170 **Classification:** Not Accepted

Names: 600-170; White Bluffs Subsurface Concrete Structure **Reclassification:** None

Type: Sump **Start Date:**

Status: Inactive **End Date:**

Description: The site is a series of subsurface concrete structures. The White Bluffs Technical Baseline Report originally described a single subsurface concrete structure, possibly a sump. A RARA Walkdown visit in May 1999 found four additional similar concrete structures/subsidesences surrounding an old building foot print.

Location: The site is located in the old warehouse area north of Federal Avenue and west of the intersection of Commercial Avenue and Federal Avenue.

Related Sites/ Structures: 600-126, 600-166, 600-165 and 600-170 all appear to be part of a related underground piping system.

Code: 600-171 **Classification:** Not Accepted

Names: 600-171; White Bluffs Townsite **Reclassification:** None

Type: Foundation **Start Date:**

Status: Inactive **End Date:**

Description: The site is the White Bluffs Townsite located in the proximity of the intersection of Route 2 North and Federal Avenue. Most of the buildings have been demolished except for the White Bluffs Bank.

Location: The site is located west of 100F and south of 100H, around the intersection of Route 2 North and Federal Avenue. The site is predominantly east of Route 2 North.

Related Sites/ Structures: See subsite for individual facility descriptions within the Townsite. Three sites, the booster pump station and the ground storage tank (located next to each other at the northeast corner of Fifth Avenue and Federal Avenue), and the sewer junction box (located about 70 meters due north of the Route 2 North and Federal Avenue intersection), are addressed separately (See Sitecode 600-158 and 600-184).

This Site has the Following SubSites:

Code: 600-171:1

Names: 600-171:1; White Bluffs Townsite Wells

Code: 600-171:2

Names: 600-171:2; Site Number 32; White Bluffs Townsite Insulation Warehouse

Code: 600-171:3
Names: 600-171:3; Office Equipment Warehouses; Site Number 33; White Bluffs Townsite

Code: 600-171:4
Names: 600-171:4; Site Number 34; White Bluffs Townsite Elevated Water Storage Tank

Code: 600-171:5
Names: 600-171:5; Site Number 36; White Bluffs Townsite Air and Welding Tool Maintenance Building

Code: 600-171:6
Names: 600-171:6; Site Number 37; White Bluffs Townsite Fire Station

Code: 600-171:7
Names: 600-171:7; Site Number 38; White Bluffs Townsite Service Division Engineer Office

Code: 600-171:8
Names: 600-171:8; Site Number 39; White Bluffs Townsite Government Checkers and Ration Office

Code: 600-171:9
Names: 600-171:9; Site Number 42; White Bluffs Townsite Two Stationary Storage Warehouses

Code: 600-171:10
Names: 600-171:10; Site Number 43; White Bluffs Townsite Fire Inspection Office

Code: 600-171:1	Classification: Not Accepted
Names: 600-171:1; White Bluffs Townsite Wells	Reclassification: None
Type: Injection/Reverse Well	Start Date:
Status: Inactive	End Date:

Description: The subsite is multiple wells in the White Bluffs Townsite area. One well appears to have a sampling well constructed within the remains of the older well. The new well is labeled 699-81-38, A5337, and appears to be in use. The third well appears to have been decommissioned. It has been filled with grout and is marked with a metal disk that reads "Well No. 699-83-36, Abandoned 9-21-95."

Location: The first well is located north of Federal Avenue and west of Third Avenue. The second well was located almost due south of the intersection of Federal Avenue and Railroad Avenue, and north of Commercial Avenue. A third well was located at the northeast end of Federal Avenue. A fourth well was located near the north end of Fifth Avenue by Building 20, MS-9 Warehouse.

Process Description: While the site type for these wells is listed in as "Injection/Reverse Well," they appear to have been constructed as water wells to service the White Bluffs townsite (C-3316).

The SubSite is Part Of:

Code: 600-171
Names: 600-171; White Bluffs Townsite

Code: 600-171:2	Classification: Not Accepted
Names: 600-171:2; Site Number 32; White Bluffs Townsite Insulation Warehouse	Reclassification: None
Type: Foundation	Start Date:
Status: Inactive	End Date:

Description: This is a duplicate entry. This site is the same as 600-136 and should not have been included as a subsite. Only those sites that did not have their own individual sitecodes should have been included in 600-171.

Location: This site was located at the northeast corner of Railroad Avenue and Lincoln Avenue.

The SubSite is Part Of:

Code: 600-171

Names: 600-171; White Bluffs Townsite

Code: 600-171:3

Classification: Not Accepted

Names: 600-171:3; Office Equipment Warehouses; Site Number 33; White Bluffs Townsite

Reclassification: None

Type: Foundation

Start Date:

Status: Inactive

End Date:

Description: All these warehouses were removed decades ago. There were six warehouses. Three of the warehouses were located on the south side of Federal Avenue between First and Second Avenues. Another one was located on the northeast corner of First Avenue and Federal Avenue. One of the warehouses was located on the west side of First Avenue, half way between Federal Avenue and Lincoln Avenue. The sixth was located at the northeast corner of First Avenue and Lincoln Avenue.

Process Description: Plot map C-3316 indicates the warehouses were used for storing office equipment.

The SubSite is Part Of:

Code: 600-171

Names: 600-171; White Bluffs Townsite

Code: 600-171:4

Classification: Not Accepted

Names: 600-171:4; Site Number 34; White Bluffs Townsite Elevated Water Storage Tank

Reclassification: None

Type: Foundation

Start Date:

Status: Inactive

End Date:

Description: This elevated water tank has been removed.

Location: The site was located at the northwest corner of Second Avenue and Lincoln Avenue.

Process Description: The water tank was connected to the White Bluffs water lines (C-3316).

The SubSite is Part Of:

Code: 600-171

Names: 600-171; White Bluffs Townsite

Code: 600-171:5

Classification: Not Accepted

Names: 600-171:5; Site Number 36; White Bluffs Townsite Air and Welding Tool Maintenance

Reclassification: None

Building

Type: Foundation**Start Date:****Status:** Inactive**End Date:****Description:** The building has been removed.**Location:** The site was located on the east side of Railroad Avenue and half way between Federal Avenue and Lincoln Avenue.**The SubSite is Part Of:****Code:** 600-171**Names:** 600-171; White Bluffs Townsite

Code: 600-171:6**Classification:** Not Accepted**Names:** 600-171:6; Site Number 37; White Bluffs
Townsite Fire Station**Reclassification:** None**Type:** Foundation**Start Date:****Status:** Inactive**End Date:****Description:** The building has been removed.**Location:** The site was located at the northwest corner of First Avenue and Federal Avenue.**The SubSite is Part Of:****Code:** 600-171**Names:** 600-171; White Bluffs Townsite

Code: 600-171:7**Classification:** Not Accepted**Names:** 600-171:7; Site Number 38; White Bluffs
Townsite Service Division Engineer Office**Reclassification:** None**Type:** Foundation**Start Date:****Status:** Inactive**End Date:****Description:** The building has been removed.**Location:** The site was located north of Federal Avenue between Second Avenue and Third Avenue.**The SubSite is Part Of:****Code:** 600-171**Names:** 600-171; White Bluffs Townsite

Code: 600-171:8**Classification:** Not Accepted**Names:** 600-171:8; Site Number 39; White Bluffs
Townsite Government Checkers and Ration
Office**Reclassification:** None**Type:** Foundation**Start Date:****Status:** Inactive**End Date:**

Description: The building has been removed.
Location: The site was located just east of the White Bluffs Townsite Service Division Engineer Office, Site Number 38.

The SubSite is Part Of:

Code: 600-171
Names: 600-171; White Bluffs Townsite

Code: 600-171:9
Classification: Not Accepted
Names: 600-171:9; Site Number 42; White Bluffs
Townsite Two Stationary Storage Warehouses
Reclassification: None
Type: Foundation
Start Date:
Status: Inactive
End Date:

Description: The warehouses have been removed.
Location: Both sites were located south of Federal Avenue and East of Railroad Avenue.

The SubSite is Part Of:

Code: 600-171
Names: 600-171; White Bluffs Townsite

Code: 600-171:10
Classification: Not Accepted
Names: 600-171:10; Site Number 43; White Bluffs
Townsite Fire Inspection Office
Reclassification: None
Type: Foundation
Start Date:
Status: Inactive
End Date:

Description: The warehouse has been removed.
Location: The site was located near the southwest corner of Federal Avenue and First Avenue.

The SubSite is Part Of:

Code: 600-171
Names: 600-171; White Bluffs Townsite

Code: 600-172
Classification: Accepted
Names: 600-172; White Bluffs French Drain or Dry Well
Reclassification: Rejected (10/6/1997)
Type: French Drain
Start Date:
Status: Inactive
End Date:

Description: The site is either a french drain or dry well that is a 61 centimeter concrete pipe, that has a steel lid, and appears to be about 1 meter deep. The sides are perforated, indicating that its purpose may have been for storm runoff or steam condensate. There does not appear to be an inlet pipe inside the structure.
Location: The site is on the north side of Federal Avenue and west of Commercial Avenue. It is approximately 470 meters (1542 feet) southwest of the intersection of Commercial and Federal

and approximately 650 meters (2133 feet) southwest of the intersection of Federal and Route 2 North.

Waste Type: Steam Condensate

Waste Description: Possibly, the waste was steam condensate.

Code: 600-173 **Classification:** Accepted
Names: 600-173; White Bluffs Domestic Debris Dump and Building Foundations **Reclassification** Rejected (10/6/1997)
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The site is a domestic type waste dump and pre-Manhattan Engineering District building foundations. The waste dump consists of miscellaneous debris and the building foundations appear to be pre-Manhattan Engineering District. One building appears to have been a garage or farm shop because of the way that the concrete was formed.

Location: The site is located southwest of the intersection of Route 2 North and Federal Avenue. The site is east of the White Bluffs Large Fenced Depression.

Waste Type: Misc. Trash and Debris

Waste Description: The waste consists of miscellaneous debris including domestic bottles, glassware, paint cans, cans, containers of heavy industrial nuts and bolts (greater than 2.5 cm in diameter). Two building foundations are also included as a part of the site.

Code: 600-174 **Classification:** Accepted
Names: 600-174; White Bluffs French Drain **Reclassification** Rejected (10/6/1997)
Type: French Drain **Start Date:**
Status: Inactive **End Date:**

Description: The site is a 61 centimeter vitrified clay pipe french drain. The top is flush with the surface and it is filled with rocks.

Location: The site is located approximately 530 meters (1739 feet) northwest of the intersection of Route 2 North and Federal Avenue.

Waste Type: Steam Condensate

Waste Description: The french drain may have been used to dispose of steam condensate.

Code: 600-175 **Classification:** Accepted
Names: 600-175; Original Priest Rapids Ice House Drain Field **Reclassification** Rejected (10/6/1997)
Type: Drain/Tile Field **Start Date:**
Status: Inactive **End Date:**

Description: The site is three large depressions thought to be the original drain field for waste water generated at the ice house. The site was originally marked by a steel post and wooden rail fence that can still be found around much of the site.

Location: The site is located in the White Bluffs Area, south of the intersection of Route 2 North and Federal Avenue and northeast of the White Bluffs Pickling Acid Cribs (600-106).

Waste Type: Water

Waste Description: The waste was waste water. It is unknown if other wastes were disposed of at the site or if the site was used for other purposes.

Code: 600-177

Classification: Accepted

Names: 600-177; White Bluffs Pipe Bender and Equipment Dumping Area

Reclassification: Rejected (10/6/1997)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site consists of two areas that are within close proximity. The pipe bender is a large heavy-walled pipe, placed vertically in the ground with approximately 1.2 meters (4 feet) of the pipe extending above grade. Several holes of varied sizes have been drilled into the vertical pipe. The holes are the approximate size of varied small diameter pipes. The structure is assumed to have been used to do rough bending of pipe. Adjacent to the pipe bender is a large area of debris that appears to have been a miscellaneous equipment dumping/storage area. Random dumping of small quantities of oils also occurred in the area.

Location: The site is located west of Route 2 North and south of Federal Avenue. It is approximately 810 meters southeast of the intersection of Route 2 North and Federal Avenue and just west of a powerline road.

Waste Type: Oil

Waste Description: The site shows evidence of random oil dumping.

Code: 600-179

Classification: Accepted

Names: 600-179; Priest Rapids Ice House

Reclassification: Rejected (10/6/1997)

Type: Burial Ground

Start Date: 1/1/1943

Status: Inactive

End Date:

Description: The site is the remains of the Priest Rapids Ice House that was demolished in situ in 1975.

Location: The site is located west of Route 2 North, south of Federal Avenue, between Commercial Avenue and the railroad. It is approximately 260 meters (853 feet) south/southeast of the intersection of Route 2 North and Federal Avenue.

Waste Type: Demolition and Inert Waste

Waste Description: The waste consists of the demolished facility buried in place in 1975. Occasionally small pieces of wood and clay can be observed on the surface.

Code: 600-180

Classification: Accepted

Names: 600-180; White Bluffs Suspect Automotive Repair Shop **Reclassification** Rejected (10/6/1997)

Type: Maintenance Shop **Start Date:**

Status: Inactive **End Date:**

Description: The site is described as the debris remaining from what appears to have been an automotive repair shop. Per HNF-57376, the items were removed in 2013 during Miscellaneous Restoration site activities.

Location: The site is located west of Route 2 North and south of Federal Avenue. It is northeast of the White Bluffs Pickling Acid Cribs (600-106).

Waste Type: Chemicals

Waste Description: The waste may have been solvents, grease, antifreeze, oils, gasoline. Concern was expressed by the Environmental Protection Agency (EPA) because of the types of materials usually found at an automotive repair shop. However, there is no evidence of this type of disposal. (Per Discovery Site Evaluation Checklist completed by Steve Weiss 8/6/96). Remaining surface material consists of jack stands, car parts, wooden debris, and other metallic debris. During the May 1999 visit, the following were observed: light fixtures, paint cans, a muffler, lumber, sections of what appears to be stove pipe, a 55 gallon drum marked "Property of Shell Oil," and buckets containing what appeared to be tar. The site's remains didn't suggest an automotive repair shop as much as a supply hut.

Code: 600-183 **Classification:** Accepted

Names: 600-183; White Bluffs Burn Pile and Debris **Reclassification** Rejected (10/6/1997)

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The site is a burn pile and debris dumping area. Within the site is one area consisting of a burn pile of domestic type debris. The other area consists of 5 gallon military type drums.

Location: The site is located west of Route 2 North and south of Federal Avenue. It is approximately 680 meters (2231 feet) south of the intersection of Route 2 North and Federal Avenue.

Waste Type: Misc. Trash and Debris

Waste Description: The waste consists of miscellaneous debris, including domestic type debris and military drums. It is unknown if any hazardous materials remain.

Code: 600-184 **Classification:** Accepted

Names: 600-184; White Bluffs Townsite Septic System **Reclassification** Rejected (10/6/1997)

Type: Septic Tank **Start Date:**

Status: Inactive **End Date:**

Description: The site is a concrete box with a metal lid. It is about 0.61 meters deep (2 feet) and is dry inside.

Location: The sewer junction box is located about 30 meters due north of the intersection of Route 2 North and Federal Avenue. The site is about 50 meters east of Route 2 North and 50 meters north of Federal Avenue.

Process Description: The site is the various components of a septic system serving the central area of the White Bluffs Townsite. In the rehabilitation of existing buildings containing inside toilets and plumbing facilities, whenever possible, connections were made to permanent systems (DuPont, 1945). The White Bluffs Townsite had one septic tank and 300 feet of sewer line. During field surveillance activities, a sewer junction box consisting of a shallow concrete box with a heavy steel cover was located within the confines of the city.

Waste Type: Sanitary Sewage

Waste Description: The waste is sanitary sewage (if the septic tank and/or drainfield could be located).

Code: 600-185	Classification: Accepted
Names: 600-185; Hanford Construction Camp Honey Dump Site	Reclassification: Rejected (10/1/1997)
Type: Trench	Start Date: 1/1/1943
Status: Inactive	End Date: 1/1/1945

Description: The site is described as a dumping and cleaning station for the portable toilets used at the various Hanford construction sites.

Location: The site is located southeast of the Hanford Construction Camp, 280 meters (919 feet) east/southeast of the intersection of Avenue A and 9th Street. It is south of the southernmost sewage treatment plant (600-186).

Waste Type: Sanitary Sewage

Waste Description: The unit received portable toilet cleaning chemicals and human waste.

Code: 600-189	Classification: Accepted
Names: 600-189; White Bluffs Warehouse Facility French Drains; 100-H-23	Reclassification: Rejected (1/26/1998)
Type: French Drain	Start Date:
Status: Inactive	End Date:

Description: The site is three french drains associated with a large warehouse and temporary construction facility. The area near the french drains is littered with debris and patches of gravel. There is no oil-stained soil or other indication of hazardous waste disposal at or near the french drains.

Location: The site is located approximately 1100 meters (3609 feet) northwest of the intersection of Route 2 North and Federal Avenue in a large warehouse-temporary construction facility area.

Release Description: The use of the drains was not reported. Drains were constructed for disposal of liquid wastes and may have been used for wastewater and/or stormwater.

Process Description: No documentation has been found describing the purpose of the drains. French drains were used for disposal of liquid wastes and these may have been used for wastewater and/or stormwater.

Waste Type: Water

Waste Description: The waste may have been wastewater/stormwater.

Waste Type: Asbestos (non-friable)
Waste Description: Transite siding was scattered throughout the area.

Code: 600-192 **Classification:** Not Accepted
Names: 600-192; Hanford Construction Camp Fumigation Chamber **Reclassification:** None
Type: Maintenance Shop **Start Date:**
Status: Inactive **End Date:**

Description: The site is the remains of a fumigation building. During a field investigation by T. F. Johnson on October 24, 1996, there was no evidence of the fumigation chamber at the site except for a few small pieces of concrete. The area was covered with cheatgrass, rabbitbrush, and tumbleweeds. The fumigation chamber (disinfestation building) was a small wooden frame building. It was posted with "Poison Gas, Keep Out" signs and protected by an 2.4 meter (8 foot) barbed-wire security fence.

Location: The site is located between Avenue A and the Columbia River, between the two northernmost sewage treatment plants (600-186). The site may be approached from the north by taking a road southeast from Route 2 North between mileposts 1 and 2. Continue southeast on this road, which parallels the river, for 3.5 kilometers (2.2 miles). A group of trees is located just above the riverbank and north of the site. The site is located approximately 140 meters (459 feet) northeast of the intersection formerly known as Avenue A and 5th Street.

Process Description: A small building adjacent to the fumigation chamber is referred to as the "bedding storage" building, suggesting that the fumigation chamber was used to fumigate bedding.

Code: 600-193 **Classification:** Accepted
Names: 600-193; White Bluffs Gas Station **Reclassification:** Rejected (10/6/1997)
Type: Storage Tank **Start Date:** 1/1/1942
Status: Inactive **End Date:** 1/1/1975

Description: The site is located in a shallow depression with heavy tumbleweed and cheatgrass growth. Prior to November 1997, the depression had been marked with a steel post and chain barrier and posted with two "DANGER KEEP AWAY" signs. The posts and chains were removed on November 19, 1997.

Location: The site is located east of Federal Avenue, south and west of Route 2 North, between the railroad tracks and the old road which was "Railroad Avenue."

Process Description: The site is the location of the White Bluffs Gas Station, that was demolished in 1975 as part of a sitewide clean up project. No documentation can be found to determine if any underground storage tanks were removed. A depressed area, that measured 4.88 X 7.62 meters (16 X 25 feet), was identified in 1989 and surrounded with steel posts and chain. Federal Avenue is located just north of the site of the depression. The west side of the site is bounded by railroad tracks and the east side is bounded by an old road believed to be "Railroad Avenue." The soil in the area is soft and sandy. The existence of the underground storage tanks could not be determined from the initial (1996) field investigation. In addition, it is possible that the tanks, if present, may have been located north of Federal Avenue and east of Railroad Avenue.

Code: 600-194 **Classification:** Accepted

Names: 600-194; Main Pipe Fabrication and Blacksmith Shop; White Bluffs Main Pipe Fabrication Shop **Reclassification** Rejected (10/6/1997)

Type: Fabrication Shop **Start Date:**

Status: Inactive **End Date:**

Description: The site is the remnants of pipe fabrication shop. The building footprint can be discerned by observing the disturbed ground surface and the lack of rabbitbrush as compared to the surrounding terrain. In some areas near the western portion of the site, the concrete floor is visible. The floor appears to be intact, but much of it is covered by soil. Waste materials observed at the site include wood, coal, metal, metal lathe turnings, pipe, nails, brick, and concrete.

Location: The site is located approximately 60 meters (197 feet) southeast of Federal Avenue and about 230 meters (755 feet) southwest of Route 2 North. The site is just west of the old road once known as "Commercial Avenue" and between Federal Avenue and the BPA Powerlines.

Related Sites/ Structures: Liquid wastes from the Main Pipe Fabrication Shop were disposed to the Pickling Acid Crib.

Process Description: The Main Pipe Fabrication Shop was used to prepare piping systems for the reactor areas. The pipe was prepared for welding by grinding, etching with acid (pickling), and then cleaning with solvent materials. This shop was the source of waste discharged to the White Bluffs Pickling Acid Crib (600-106).

Waste Type: Misc. Trash and Debris

Waste Description: The site contains concrete, brick, wood, coal, metal, and small amounts of glass. The Main Pipe Fabrication And Blacksmith Shop used acids and solvents in the pipe fabrication process which may have contaminated the waste materials and soil remaining at the site. Carbon tetrachloride was a common degreasing agent at the time and may be present in the debris.

Code: 600-195 **Classification:** Not Accepted

Names: 600-195; White Bluffs Townsite Electrical Substation **Reclassification** None

Type: Electrical Substation **Start Date:**

Status: Inactive **End Date:**

Description: The site is the location of a demolished substation that serviced the White Bluffs Townsite. The site had two footprints measuring 4.3 meters by 3.8 meters and 1.8 meters by 5.5 meters (14 feet by 11 feet and 6 feet by 18 feet). The footprints of the former substation site are still visible. The soil at the site is sandy. Cheatgrass vegetation growth within the site appears stunted and indicates the size and location of the former site. There is no evidence of oil spills or stains in the soil at this site or the ground surrounding the site.

Location: The site is located on the south corner of the intersection of Federal Avenue and Commercial Avenue. It is approximately 200 meters (656 feet) southwest of the intersection of Route 2 North and Federal Avenue.

Waste Type: Soil

Waste Description: No waste was observed at the site.

Code: 600-196 **Classification:** Not Accepted
Names: 600-196; White Bluffs Farm Dump Site and Partially Backfilled Pit **Reclassification:** None
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The site is areas of random scattered debris and a pit. The debris includes cans, bottles, barbed wire and car parts scattered along the west side of a dirt road. The pit is a fairly large excavation on the east side of the road and shows no evidence of being used as a waste site.

Location: The site is located approximately 1 kilometer (0.62 miles) northeast of the intersection of Route 2 North and Federal Avenue. The site may be approached from a dirt road heading due north from Federal Avenue about 644 meters (2112 feet) northeast from the intersection of Route 2 North and Federal Avenue.

Waste Type: Misc. Trash and Debris

Waste Description: Cans, glass, barbed wire, and auto parts

Code: 600-198 **Classification:** Not Accepted
Names: 600-198; RCRA General Inspection LORIVFY96 Item #2; White Bluffs River Bank Concrete Structure **Reclassification:** None
Type: Foundation **Start Date:**
Status: Inactive **End Date:**

Description: The site is a box shaped concrete structure partially buried in the river bank. The site appears to have slid partially down the bank. The structure is filled with dirt and debris. There is a large quantity of 0.635 centimeter (0.25 inch) nylon tubing hanging around and in the structure. Four steel pipes extend from each corner of the box. An electrical conduit also extends from the box. A square notch was observed on a top corner of the box.

Location: The site is located 500 meters (1641 feet) upstream from the White Bluff's Landing. It is on the east side of the dirt road leading north from the boat landing and is perched on the riverbank above the water.

Waste Type: Construction Debris

Waste Description: Concrete, steel pipe, and nylon tubing.

Code: 600-199 **Classification:** Accepted
Names: 600-199; White Bluffs Ash Covered Concrete Pad **Reclassification:** Rejected (3/11/1998)
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The site is a concrete foundation pad that is completely covered with coal ash. The original purpose of the pad is unknown.

Location: The site is located west of Route 2 North and north of Federal Avenue. It is approximately 675

meters (2215 feet) southwest of the intersection of Route 2 North and Federal Avenue.

Waste Type: Ash

Waste Description: The waste is coal ash which is a state regulated solid waste. The waste has been placed in a waste pile (discernible unit).

Waste Type: Asbestos (non-friable)

Waste Description: Transite siding was scattered throughout the area.

Code: 600-200

Classification: Accepted

Names: 600-200; Priest Rapids Ice House Septic Tank

Reclassification: Rejected (10/6/1997)

Type: Septic Tank

Start Date:

Status: Inactive

End Date:

Description: The site is a large septic tank thought to have been associated with the Priest Rapids Ice House.

Location: The site is located south of Federal Avenue and west of Commercial Avenue. It is approximately 315 meters (1034 feet) south of the intersection of Route 2 North and Federal Avenue. The site is southwest of the Priest Rapids Ice House (600-179).

Waste Type: Sanitary Sewage

Waste Description: The waste is a septic tank, possibly containing human septage. Septage is a state regulated solid waste.

Code: 600-203

Classification: Accepted

Names: 600-203; White Bluffs French Drains

Reclassification: Rejected (10/6/1997)

Type: French Drain

Start Date:

Status: Inactive

End Date:

Description: The White Bluffs Technical Baseline Report states the site is two french drains and what appears to be a valve box. No additional information is known. A RARA Walkdown visit done in May 1999. They found a round clay french drain filled with rock and an additional small subsidence near the valve box. They also noticed a long narrow area of disturbed vegetation that may indicate these structures were part of an old irrigation system. A third item was observed, photographed and mapped as a new component of this site. It was a concrete, square hole that measured approximately 8 by 8 inches.

Location: The site is located north of Federal Avenue and west of Commercial Avenue. It is approximately 360 meters (1181 feet) northwest of the intersection of Commercial and Federal Avenue.

Waste Type: Steam Condensate

Waste Description: The waste may have been steam condensate.

Code: 600-206

Classification: Accepted

Names: 600-206; 101 Building Graphite Dump Site **Reclassification** Rejected (10/1/1997)

Type: Burial Ground **Start Date:** 1/1/1943

Status: Inactive **End Date:** 1/1/1945

Description: The site is a burial ground used for the disposal of scrap graphite and building rubble. The building was plowed into the ground when it was demolished. Remnants of the site remain on the surface. The 101 Building was used during the 1943-1944 construction program for machining graphite for the 100 Areas. It was then declared surplus and partially dismantled. It was reconstructed for machining graphite in 1948.

Location: The dump site appears to be along the southern edge of the 101 Building site, probably along the railroad right-of-way that serviced the building.

Related Sites/ Structures: The 101 Building site was located at the Hanford Construction Camp, north of Roosevelt Avenue and North of the Hanford High School, west of Avenue A, in the "V" formed by Avenue A and the powerlines.

Waste Type: Demolition and Inert Waste

Waste Description: The records appear to indicate that the site received debris from the demolished building. It is unlikely to contain hazardous or radioactive materials. A records review and site inspection reveal no evidence of radioactive or toxic dumping.

Code: 600-207 **Classification:** Accepted

Names: 600-207; Hanford Construction Camp **Reclassification** Rejected (10/6/1997)
Powerhouse Ash Pile

Type: Dumping Area **Start Date:** 1/1/1943

Status: Inactive **End Date:** 1/1/1945

Description: The site is a large coal ash pile. The pile is pear-shaped and oriented north to south with the wider portion to the south. It is covered with cheatgrass and tumbleweeds. A second smaller ash pile exists to the northwest.

Location: The site is located southeast of the Hanford Construction Camp, approximately 1000 meters (3281 feet) inland from the Columbia River. The site is approximately 780 meters (2559 feet) southeast of 10th Street and 740 meters (2428 feet) southwest of Avenue A. The ash pile is located adjacent to the bluff that overlooks the Hanford Construction Camp from the south. The site is accessible from the north by an overgrown gravel road.

Waste Type: Ash

Waste Description: The waste is ash that appears characteristic of powerhouse ash and probably came from coal fired power houses used at the Hanford Construction Camp. The dirt road leading to the main site has been overlaid with ash. The waste has been placed in a discernible unit (pile).

Code: 600-209 **Classification:** Accepted

Names: 600-209; White Bluffs Excess Railroad Tie **Reclassification** Rejected (10/6/1997)
Materials

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The site is several stacks of excess railroad ties. The ground surface at the site appears to have

been graveled, suggesting that the entire area was a warehouse area for industrial type materials. During the May 1999 visit, it was observed that scattered stacks and piles of railroad ties were found in a large undefined area on both sides of a powerline road. Ties were found to the west and south of 600-188.

Location: The single point that is mapped for this site is located west of Route 2 North, south of Federal Avenue, on the west side of a powerline road. It is 1050 meters (3445 feet) south of the intersection of Route 2 North and Federal Avenue.

Waste Type: Oil

Waste Description: The waste is creosote soaked railroad ties and possibly creosote in the soil underneath the railroad ties. The Regulators were concerned about this site for the reasons stated above.

Code: 600-210 **Classification:** Not Accepted

Names: 600-210; 300 Area TEDF Outfall **Reclassification:** None

Type: Outfall **Start Date:** 1/1/1994

Status: Inactive **End Date:**

Description: The outfall pipeline was a 25-centimeter (10-inch) polyvinyl chloride (PVC) pipeline that was routed to the shore of the Columbia River [approximately 600 meters (2000 feet)] from the TEDF. To protect an archaeological site near the river, the pipeline was laid aboveground, until it was close to the shoreline. At this point, the pipe was routed below grade into a gravel-filled, rock-armored trench. At the shoreline the PVC pipe was transitioned to an 20 centimeter (8-inch) ductile iron pipe that transfers the effluent to the mid-channel single-point diffuser. The diffuser lies on the bottom of the river channel, and consisted of an iron pipe routed through a large, rectangular concrete casing. An angled discharge-pipe bolted directly to the concrete block.

Location: The outfall is located directly east of the 300 Area TEDF. The outfall runs from the TEDF to the middle of the near channel of the Columbia River.

Related Sites/Structures: This structure is associated with the 310 Facility aka the 300 Area Treated Effluent Disposal Facility (TEDF) - See WIDS sitecode 600-117.

Process Description: The outfall discharged treated effluent released from the 300 TEDF. The influent to the 300 TEDF was generated by facilities discharging to the 300 Area process sewer. On September 2, 2009, the discharge from the outfall to the Columbia River was permanently terminated.

Waste Type: Process Effluent

Waste Description: The outfall discharges effluent from the 300 Area TEDF to the Columbia River.

Code: 600-211 **Classification:** Accepted

Names: 600-211; 616A; 616-A; SALDS; State Approved Land Disposal Site **Reclassification:** None

Type: Drain/Tile Field **Start Date:** 1/1/1995

Status: Active **End Date:**

Description: The site is surrounded by steel posts/chain and posted as "SALDS Building 616A Disposal Field". The cobble terrain is flat with primarily cheatgrass cover. There are seven 5 inch plastic pipes (monitoring ports) that extend two to three feet above grade and one 30 inch sampling

access manhole that extends one foot above grade. Two feet below grade in the gravel disposal bed are sixty-six perforated 4 inch diameter distribution laterals branching 90 degrees from an 8 inch diameter feed header. A geotextile and PVC membrane cover the disposal field and are one foot below grade.

Location: About 1200 feet north of the 200 West Area exclusion fence, 1700 feet south of Route 11A, 1100 feet east of the 200 West entrance road to gate 609, and 6500 feet west of Route 3.

Related Sites/ Structures: SALDS Disposal Pipeline (600-292-PL), 200 Area Effluent Treatment Facility (2025E), Liquid Effluent Treatment Facility (LERF), 242-A Evaporator, PUREX.

Process Description: The site receives liquid waste that has been treated and verified at the 200 Area Effluent Treatment Facility in 200 East Area. The waste is distributed (below grade) to a gravel bed via perforated pipe. The liquid waste meets delisting requirements of the 216 permit #ST 4500 and is discharged as nondangerous waste; however it may contain tritium.

Waste Type: Process Effluent

Waste Description: Treated and verified liquid waste received from the 200 Area Effluent Treatment Facility (ETF). The waste meets the delisting requirements of the 216 permit ST 4500 and is considered nondangerous; however it may contain tritium.

Code: 600-212 **Classification:** Accepted

Names: 600-212; Relocatable Latrine Facility Holding Tank System **Reclassification:** None

Type: Septic Tank **Start Date:** 1/1/1993

Status: Active **End Date:**

Description: The site is surrounded with fourteen steel posts painted yellow. The top of the tank is visible at grade level and measures 9 feet by 15 feet. Two concrete covers are located on top of the tank, one has a steel access port for pumping. The electrical conduit for transmitting to the alarm system is visible on top of the tank.

Location: The site is located just west of the 200E area, between Route 4 North and the 200E Perimeter Fence. The site is within the trailer village established for the HWVP Project approximately 8 meters west of MO-730.

Related Sites/ Structures: The tank receives waste from MO-730.

Process Description: The HWVP Relocatable Latrine Facility (RLF) Holding Tank System consists of a trailer (MO-730) divided into men's and women's restrooms. Fixtures which drain into the holding tank system include ten toilets, three urinals, six sinks and four self-contained sinks. The latrine trailer is connected to a holding tank via a 4" diameter drain line. The holding tank is a recast concrete vault providing a nominal volume of 5,440 gallons and working volume of 4,500 gallons.

Waste Type: Sanitary Sewage

Waste Description:

Code: 600-213 **Classification:** Accepted

Names: 600-213; Hanford Airport Underground Fuel Storage Tanks **Reclassification:** Rejected (1/31/2010)

Type: Storage Tank**Start Date:****Status:** Inactive**End Date:****Description:** The site consisted of underground fuel storage tanks that were associated with the Hanford Airport. The airstrip runways are still visible. A windsock pole is visible just off the southeast corner of the airstrip intersection. Two field walkdowns in 2007 were performed, no visual evidence of building locations or fuel storage tanks were observed.

A United States Geological Survey (USGS) June 1, 1948 aerial photograph of the area shows a connecting taxi-way between the south end of the north-south runway and the east end of the east-west runway. The photo shows buildings on the southeast side of the taxi-way. The taxi-way has a large north arrow painted on it that is about 61 meters (200 feet) long.

Location: The site is located approximately 2 kilometers (1.2 miles) east of the southeast end of Gable Mountain. The site is best approached from Route 2 North on a dirt road which heads west 0.32 kilometers (0.2 miles) north of milepost 1 on Route 2 North. The site is north of the dirt road and approximately 0.8 kilometers (0.5 miles) west of Route 2 North. A metal pipe sticking out of the ground may mark the site.**Process Description:** The airport consisted of two landing strips, one running almost north and south, and the other east and west. Both strips were 61 meters (200 feet) wide with the north-south strip approximately 1,220 meters (4,000 feet) long and the east-west strip approximately 732 meters (2,400 feet) long. The landing strips were of bituminous stabilized construction, i.e., mixing the surface sand and gravel in place with road oil and rolling to a 15 to 20-centimeter (6 to 8-inch) thick packed surface. Two wood-frame open-type shed hangars and a 5.6 by 12.2-meter (16 by 40-foot) Pacific Hutment were erected east of the air strip intersections. Electrically-driven gasoline pumps, with underground storage tanks, were provided for refueling of Army planes. The airport was totally enclosed by a Type #2, three-strand barbed wire fence. All construction work was performed by Project forces.

Code: 600-214**Classification:** Accepted**Names:** 600-214; 600-PSTF; MODU-Tanks; 600 Area Purgewater Storage and Treatment Facility**Reclassification:** Closed Out (6/27/2011)**Type:** Retention Basin**Start Date:** 1/1/1990**Status:** Inactive**End Date:****Description:** The site was originally occupied by the RCRA TSD Purgewater Storage and Treatment Facility. The TSD was clean closed under RCRA in June 2011. The facility was inside a fenced area that measured 210 by 150 meters (680 by 480 feet). The two original, above ground RCRA storage tanks (Units #1 and #2) were located in the southeast portion of the fenced area. East of the tanks was the truck unloading area. West of the tanks were two leak detection risers. Unit #1 was demolished in May 2011.**Location:** The waste site is located outside the 200 East Area security fence and near the northeast corner of 200 East Area. It is about 400 meters (1,300 feet) north of B-Pond, 750 meters (2,460 feet) east of Canton Avenue, and 300 meters (980 feet) west of the 216-E-28 Contingency Ponds. Tank Unit #1 was south of Unit #2.**Related Sites/ Structures:** Purgewater from Hanford Site wells is transported to the site by tanker truck and unloaded.**Process Description:** Only Unit #1 was operated. Unit #2 never received purgewater. The original Unit 1 modutank provided RCRA, greater than 90-day storage and treatment of purgewater generated from Hanford Site drilling and groundwater monitoring activities. The treatment was solar

evaporation. Subsequent Modular Storage Units (#2 and #3) continue to receive purgewater generated from Hanford Site drilling and groundwater monitoring activities, but under CERCLA authority. Modular Storage Unit #2 was relined and is being used to receive non-RCRA, investigative derived waste (IDW). Modular Storage Unit #3 was constructed and is receiving non-RCRA, investigative derived waste (IDW).

Waste Type: Water

Waste Description: Wastes include: purgewater from Hanford Facility groundwater monitoring wells. Liquid resulting from well sampling, well development, and aquifer testing. Waste may also include nonregulated purgewater from wells. By permit, purgewater may contain radioactive material, carbon tetrachloride, and other non-specific solvents (F001, F002, F003).

Code: 600-215

Classification: Accepted

Names: 600-215; 6265A 90-Day Waste Accumulation Area

Reclassification: Rejected (9/14/2000)

Type: Storage Pad (<90 day)

Start Date:

Status: Active

End Date:

Description: The storage pad is a fenced-in concrete pad covered with an open shed divided into three sections. The fence is on the east and west sides, and connects to the cinder block walls on the north and south sides, which holds up the roof. The fence has six gates, two into each section of the pad. The two northernmost sections of the pad are chained off inside the fence and marked as "Radioactive Materials Area." The floor of the pad is a metal grate that opens to a concrete basin underneath. This basin is about 20 centimeters (8 inches) deep, and is designed to catch any leaks. It does not have any other drain, but appears to be large enough to hold the entire contents of several drums, if they should leak. In April 2000, no water (that may have come from natural spring precipitation) was evident in the basin, but a small amount of vegetation debris had collected in a few spots.

Location: The site is located east of the 200 West Area. It is approximately 100 meters (300 feet) west of the Waste Sampling and Characterization Facility laboratory building.

Related Sites/ Structures: This storage pad is related to the WSCF.

Process Description: This site is used to temporarily store analytical laboratory waste generated at the Waste Sampling and Characterization Facility (WSCF).

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: Analytical laboratory waste is stored at this site.

Code: 600-216

Classification: Not Accepted

Names: 600-216; 600-48; H-61-H Anti-Aircraft Artillery Site Building Foundations

Reclassification: None

Type: Foundation

Start Date:

Status: Inactive

End Date: 1/1/1958

Description: Seven concrete foundations and pads are at this site: #1. A vehicle maintenance shop with a mechanic's trench in the foundation floor and drive-through ability on each end. The

dimensions are 34 meters by 14 meters (111 feet by 45 feet). The mechanic's trench is filled with tumbleweeds, but as a place to work it would also have a concrete floor and not be used to drain oil to the ground. #2. Concrete pad, 9 meters by 9 meters (29 feet by 29 feet). #3. Concrete Pad, 6.4 meters by 12.5 meters (21 feet by 41 feet). #4. Concrete kitchen foundation with floor drains and a grease trap. The dimensions are 10 meters by 12.5 meters (33 feet by 41 feet). #5. Concrete pad, 14.6 meters by 5.5 meters (48 feet by 18 feet). #6. Concrete foundation that appears to have been a toilet and shower facility. The dimensions are 14.6 meters by 6 meters (48 feet by 20 feet). #7 Concrete pad, 4 meters by 2.4 meters (13 feet by 8 feet). A large, approximately 12 by 12 meters (40 by 40 feet) open pit is at the site and fenced; the purpose and age of the pit are unknown. There is no evidence of trash in the bottom. Two old building heaters also remain at the site.

Location: This site is located just southwest of the intersection of Route 11 and Route 6. It is 640 meters (0.4 mile) south of Route 11 and just west of Army Loop Road. The site is in the east half of the northeast quarter of Section 34, Township 13 north, Range 25 east.

Related Sites/ Structures: Septic system 600-217 serviced this site, and dumping area 600-218 received associated trash.

Process Description: Typically, Camp Hanford's anti-aircraft artillery sites were each roughly 20 acres in size and contained any number of buildings (typically around 20), various utility distribution systems, roads, and sidewalks. Each site consisted of emplacements protected by revetments made of sandbags and wood planking, wooden structures, prefabricated metal buildings, and, later, permanent, concrete block structures. The prefabricated buildings had aluminum walls and roofs with wooden or concrete floors set on concrete pier blocks and were the most commonly constructed. The permanent structures included barracks, latrines, mess halls, craft shops, pump houses, motor pools, and radar facilities. Each site typically had a small arms range, water storage cistern, sanitary, and sewage disposal facilities. Pathways, sidewalks, roadways, and parking lots connected the structures.

Waste Type: Demolition and Inert Waste

Waste Description: Concrete foundations and pads from former buildings and structures, some containing floor drains and steel anchors.

Code: 600-217

Classification: Accepted

Names: 600-217; H-61-H Anti-Aircraft Artillery Site Sewer System

Reclassification: Rejected (5/18/2011)

Type: Sanitary Sewer

Start Date:

Status: Inactive

End Date:

Description: The sewer system extended from the kitchen, toilet and shower building and ran into a septic tank on the eastern side of the site. The manholes and septic tank have been filled in with clean sand (September 2001). Twelve toilet drains and five floor drains were observed on the toilet and shower building foundation floor. A sewer manhole is located just NE of the toilet/shower building. The kitchen foundation has four floor drains and a grease trap. A sewer manhole is located NW of the kitchen.

Location: This site is located just southwest of the intersection of Route 11 and Route 6. It is 0.4 miles south of Route 11 and just west of Army Loop Road. The site is in the east half of the northeast quarter of Section 34, Township 13 north, Range 25 east.

Related Sites/ Structures: This sewer system serviced Anti-Aircraft site 600-216.

Waste Type: Sanitary Sewage

**Waste
Description:**

Code: 600-219 **Classification:** Not Accepted

Names: 600-219; H-61-R Radar Site **Reclassification:** None

Type: Foundation **Start Date:**

Status: Inactive **End Date:**

Description: A concrete block remains at the site. The concrete block measures 3.4 meters by 3.4 meters by 1.2 meters (11 feet by 11 feet by 4 feet). Wooden structures that had been on each side of the block were consumed in the July 2000 range fire; only charred wood and burlap from sandbags remain.

Location: The H-61-R Radar site is located approximately 160 meters (0.1 mile) southwest of the northwest corner of the 200 West Perimeter Fence and approximately 960 meters (0.6 miles) south of Route 11 and just west of Army Loop Road.

**Related Sites/
Structures:** Site 600-216, the H-61-H Anti-Aircraft Artillery Site, is associated with this radar installation.

Waste Type: Demolition and Inert Waste

**Waste
Description:** The only material remaining at the site is a large block of concrete and some charred wood and burlap from sandbags.

Code: 600-223 **Classification:** Accepted

Names: 600-223; H-50 Gun Site Pit; Military Camp South of 200W **Reclassification:** Rejected (5/31/2001)

Type: Depression/Pit (nonspecific) **Start Date:**

Status: Inactive **End Date:** 1/1/1958

Description: The site was described in 1987 as a pit that is filled with blown in tumbleweeds. Fence posts and barbed wire are visible on the northwest corner of the pit. A sanitary sewer manhole is located just south of the pit. While the presence of the tumbleweeds made determining if other debris was present impossible when the site was discovered, the July 2000 fire showed that the pit is empty. A plastic orange fence surrounds the pit to warn of falling danger.

Location: The unit is located south of the 200 West Area, 0.6 kilometers (0.4 miles) east of the Rattlesnake Gate and south of Army Loop Road. The pit is located in the southern portion of the H-50 Gun Site just north of the septic tank.

**Related Sites/
Structures:** This pit is associated with site 600-39, the building foundations, and 600-224, the site septic system.

**Process
Description:** The reason for the pit is unknown, and not evident from the surrounding area. There is no evidence of spills or other hazardous material in the pit. The fencing debris at the top end may have been used to mark the site during military operations, but was left when the anti-aircraft site was decommissioned.

Waste Type: Equipment

Waste Description: Steel fence posts and barbed wire.

Waste Type: Vegetation

Waste Description: The pit is filled with blown in tumbleweeds.

Code: 600-224 **Classification:** Accepted
Names: 600-224; H-50 Gun Site Septic System; Military Camp South of 200W **Reclassification:** Closed Out (2/23/2001)
Type: Septic Tank **Start Date:**
Status: Inactive **End Date:**

Description: The septic system was properly abandoned and Closed Out. It was located in the south portion of the H-50 Gun Site. The tanks have been filled with sand and abandoned in place. Signs reading "Abandoned Septic Tank" are posted.

The system included a manhole, two concrete tanks and concrete block house between the tanks. The first tank is below grade, has three manholes, and measures approximately 3.7 meters by 0.8 meters by 1.5 meters (12 feet by 2.6 feet by 5 feet). The second tank is visible above grade, has two manholes, and measures 1.8 meters by 3.3 meters by 2.7 meters (5.8 feet by 10.7 feet by 9 feet). A concrete block house was located between the two tanks. The structure was demolished and the rubble removed.

Location: The unit is located south of the 200 West Area and 0.4 miles east of the Guard House on SR 240. The septic system is located in the southern portion of the H-50 Gun Site. (southwest quarter of Section 19, Township 12 North, Range 26 East)

Waste Type: Demolition and Inert Waste

Waste Description: Debris from a demolished block house was located between the two septic tanks.

Waste Type: Sanitary Sewage

Waste Description:

Closure Info: Final: The septage was removed from both tanks sometime in the past. In July, 2000 the lids were removed from both tanks and the void space in both tanks was filled with a sand slurry. The inert rubble from the block house, which had been left from past demolition activities, was discarded in a landfill.

Code: 600-229 **Classification:** Not Accepted
Names: 600-229; Dumping Area Near White Bluffs Ferry Landing (East Side); RCRA General Inspection 200WFY97 Item #21 Historic Disposal Site **Reclassification:** None
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The site contains several empty rusty 19 liter (5 gallon) steel containers that are partially buried or filled with soil. The site also contains wire, wire rope, and small amounts of sheet metal.

Location: The site is located approximately 250 meters (820 feet) downstream from the old White Bluffs Ferry Landing on the east side of the Columbia River and just above the high water mark. The Bonneville Power Administration cross the river approximately 25 meters (82 feet) south of the site.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: Several empty rusty 19 liter (five gallon) steel containers are at the site. The containers are partially buried.

Waste Type: Misc. Trash and Debris

Waste Description: The site contains a relatively small amount of metal such as wire rope, barbed wire, wire, and sheet metal.

Code: 600-231 **Classification:** Not Accepted

Names: 600-231; RCRA General Inspection 200WFY97 Item #5 Historic Disposal Site **Reclassification:** None

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site contains pre-Hanford debris, including several rusty metal food containers, empty paint cans, buckets, glass, small pieces of concrete, cable, barbed wire, sheet metal, and a rubber tire.

Location: The site is located on the right bank of the Columbia River (facing downstream) between 100B Area and 100K Area, approximately 250 meters west of the old Hanford Irrigation Project Pumhouse and approximately 40 yards from the river.

Waste Type: Misc. Trash and Debris

Waste Description: Small pieces of concrete, a rubber tire and glass.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: The debris is buckets, cans and wire.

Code: 600-234 **Classification:** Not Accepted

Names: 600-234; RCRA General Inspection 200WFY97 Item #11 Historic Disposal Site **Reclassification:** None

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site is pre-Hanford farmstead debris. The site contains miscellaneous materials including cans, bottles, sheet metal, and wire. The site covers an area approximately 45.7 meters (150 feet) square.

Location: The site is located approximately one mile north (upstream) of the White Bluffs Ferry Landing on the east side of an unnamed island on the Columbia River, approximately 27.4 meters (30 yards) from the edge of the water.

Waste Type: Misc. Trash and Debris

Waste Description: The waste is pre-Hanford homestead waste, including metal, glass, and wire.

Code: 600-236	Classification: Accepted
Names: 600-236; Bioremediation Site; Petroleum Contaminated Soil; Soilcell 607 Site	Reclassification: Rejected (11/22/2004)
Type: Surface Impoundment	Start Date: 1/1/1994
Status: Inactive	End Date: 1/1/1995

Description: The site was a treatment facility for petroleum contaminated soil. The site is rectangular shaped with earth berms on all sides. The site is lined with black plastic, soil is spread evenly on top of the black plastic throughout the interior of the site. The site is posted on all sides with signs stating: "WIDS Site 600-236".

Location: The site is located between the 200 East and 200 West areas and is located approximately 300 meters (1000 feet) east-northeast of the 200 Area Fire Station.

Waste Type: Soil

Waste Description: Petroleum contaminated soil.

Code: 600-237	Classification: Not Accepted
Names: 600-237; Gable Pond (216-A-25) North and South Borrow Pits	Reclassification: None
Type: Depression/Pit (nonspecific)	Start Date: 1/1/1984
Status: Inactive	End Date: 1/1/1988

Description: The borrow pits are large, shallow scraped areas along the north and south sides of the stabilized Gable Pond. The stabilized pond surface was vegetated with wheat grass, but the borrow pits are bare.

Location: The sites are located north of 200 East Area, and north of Route 11A, adjacent to the backfilled Gable Pond.

Related Sites/ Structures: This borrow pit provided fill for the stabilization of site 216-A-25, Gable Pond.

Process Description: Gable Mountain Pond was backfilled and stabilized in a phased approach, over a four year time span ranging from 1984 to 1988. Clean backfill material was taken from areas adjacent to the north and south sides of the pond. No waste has been put into the borrow areas. Only clean backfill material was removed.

Code: 600-240	Classification: Accepted
Names: 600-240; 615 Hot Mix Plant Debris; Debris in Pit 17; Hanford Aggregate Pit Debris	Reclassification: Rejected (5/31/2001)
Type: Dumping Area	Start Date:
Status: Inactive	End Date:

Description: The site has been reclassified to Rejected. It is metal and wooden debris scattered within Gravel Pit #17. The debris originated from the 615 Hot Mix Plant (sitecode 600-20) and operation of the gravel pit. Some of the pipes and wood are partially buried in scattered locations. The pile is naturally revegetating to grasses and rabbitbrush. To the east of the pit is an irregularly shaped pile of a mix of asphalt pieces, soil, gravel, and cobble, about 12 meters by 3.5 meters by 1 meter high (40 feet by 12 feet by 3 feet high). Rabbitbrush plants have started to colonize the pile.

Location: This site is west of Route 2 North, on the north side of the Hot Mix Plant location.

Release Description: There is no evidence of hazardous or dangerous wastes at the site.

Related Sites/ Structures: This pit is related to the adjacent Hot Mix Plant (sitecode 600-20), and adjacent to Pit #16 debris, sitecode 600-239.

Waste Type: Misc. Trash and Debris

Waste Description: The waste is metal pipe, coarse mesh screens, wood, sheet metal, concrete, a rubber tire, and a pile of asphalt pieces mixed with soil, gravel, and cobble.

Code: 600-244 **Classification:** Not Accepted

Names: 600-244; Gravel Pit #6; Gravel Pit 6; Pit 6 **Reclassification:** None

Type: Depression/Pit (nonspecific) **Start Date:**

Status: Active **End Date:**

Description: The gravel pit is a source for gravel used for bedding and backfill material. A gravel road leads into a large irregular shaped pit area. The physical boundaries of the site are larger than the area where gravel is currently being excavated. The boundaries of gravel Pit 6 were expanded in 2008 and again in 2013. The four corners of the pit's largest extents are marked with posts (railroad ties installed vertically). Stock piles of gravel and excavation equipment are present, indicating active gravel pit operations. A chain link fenced equipment storage area is located in the northwest corner of the Pit #6 property.

Location: Gravel Pit #6 is located west of 300 Area, on the west side of Highway Route 4S. It is south of the 618-7 burial ground.

Related Sites/ Structures: The Bioremediation Area (WIDS Site 600-243) is located within the boundaries of the Gravel Pit #6 area, and northeast of the current excavation area. WIDS Sites 600-249 is a large spoil pile of dirt, rock, and debris is located in the northwest quadrant of Pit 6. For a short time in 1987, water treatment filter backwash solutions were trucked to this area for disposal (WIDS Site 300 IFBD). WIDS site 300-288:1 (garnet sand) is located inside the 600-249 boundary. WIDS site 300-288:2 (buried debris) is located in the eastern portion of the Pit 6 expansion.

Code: 600-245 **Classification:** Not Accepted

Names: 600-245; Gravel Pit #8; Pit 8 **Reclassification:** None

Type: Depression/Pit (nonspecific) **Start Date:**

Status: Active **End Date:**

Description: The gravel pit is an irregular shaped depression. No waste of any kind was found in the pit.

Location: Gravel Pit #8 is located approximately 3.2 kilometers (2 miles) north of the 300 Area. It is north of where the railroad tracks cross Route 4S and east of Gravel Pit #9.

Code: 600-246 **Classification:** Accepted
Names: 600-246; Gravel Pit #9; Inert/Demolition Waste Landfill; Pit 9 **Reclassification** Rejected (1/27/1999)
Type: Burial Ground **Start Date:**
Status: Active **End Date:**

Description: Gravel Pit #9 is a large depression where gravel is extracted. The gravel pit is also used as an inert landfill for nondangerous/nonradioactive wastes.
Location: Pit #9 is located approximately 1.2 kilometers (2 miles) north of 300 Area, east of Route 4S.
Related Sites/ Structures: WIDS site 600-278, a Bio Remediation pad, was located within the gravel pit.
Waste Type: Demolition and Inert Waste
Waste Description: The waste includes concrete, wood and asphalt. Soil was removed from around the 384 fuel oil day tanks and placed in Pit 9 in 1999. Soil sample results showed a plutonium spike, so the bio-remediation pad was posted as a Soil Contamination Area.

Code: 600-247 **Classification:** Accepted
Names: 600-247; Gravel Pit #10; Inert Landfill; Pit 10 **Reclassification** Rejected (1/27/1999)
Type: Burial Ground **Start Date:**
Status: Inactive **End Date:**

Description: The site is an old gravel pit. Once extraction operations were completed, the site was then used as a solid waste landfill for inert and demolition waste. Gravel Pit #10 has been closed and backfilled to grade. The site perimeter is marked with posts and chain.
Location: Gravel Pit #10 is approximately 1.2 kilometers (2 miles) north of 300 Area on the west side of Route 4S.
Waste Type: Demolition and Inert Waste
Waste Description: The gravel pit is an approved inert landfill. Waste includes wood, concrete and asphalt.

Code: 600-248 **Classification:** Not Accepted
Names: 600-248; Gravel Pit #11; Pit 11 **Reclassification** None
Type: Depression/Pit (nonspecific) **Start Date:**
Status: Active **End Date:**

Description: Gravel Pit #11 is a large, rocky excavated area north of the WYE Barricade. It is actively being used as a source of gravel for backfill.
Location: The site is located north of the WYE Barricade, on Route 2S, near mile marker 6, on the east side of the road.
Related Sites/ Structures: The site is associated with WIDS Site 600-23, Dumping Area Within Gravel Pit #11.

Code: 600-249 **Classification:** Accepted
Names: 600-249; Debris Within Gravel Pit 6 **Reclassification** Rejected (4/6/1999)
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The site is areas of miscellaneous material located within Gravel Pit #6. There were spoil piles of material excavated during the construction of the Environmental Molecular Sciences Laboratory (EMSL) facility that are located in the northwest section of the Gravel Pit #6 property boundaries. Miscellaneous debris can be seen in scattered piles and protruding from the soil.

Location: The debris is located in the northwest quadrant of Gravel Pit #6.

Related Sites/ Structures: The site is associated with Gravel Pit #6 (WIDS Site 600-244), and WIDS Site 300 ASH PITS. It is also associated with 300-288.

Waste Type: Misc. Trash and Debris

Waste Description: The site contains miscellaneous debris and ash pit sludge. Visible debris includes metal pipes, PVC pipes, concrete and tires. (The tires and some other debris were removed in 1999 for proper disposal) Periodically, damp ash was trucked from the 300 Area Ash Pits (WIDS Site 300 ASH PITS) and placed in Pit #6. Eventually, the area reserved for the ash became filled. The area was covered with dirt. This is the same area where a bioremediation pad was located (WIDS Site 600-243).

Code: 600-250 **Classification:** Not Accepted
Names: 600-250; Metal Debris from RCRA General Inspection #LORIVFY97 Item #4 **Reclassification** None
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The site is a recorded cultural resources site, a historic homestead where rusty sheet metal vent ducting and other miscellaneous debris have been abandoned, including: broken bricks and concrete, old lumber, metal cables and wiring. Some of the debris extends on to the top of the bank, including some half-buried, rusty cans.

Location: The site is located approximately 68.8 meters (225 feet) upstream from Columbia River mile marker #26 (Hanford mile marker) and USGS river mile 362. The site is also approximately 36.6 meters (120 feet) from the water's edge (on the date of inspection).

Waste Type: Misc. Trash and Debris

Waste Description: The waste is sheet metal and other debris.

Code: 600-251 **Classification:** Not Accepted
Names: 600-251; Steel Pipe from RCRA General Inspection #LORIVFY97 Item #6 **Reclassification** None
Type: Dumping Area **Start Date:**

Status: Inactive**End Date:**

Description: The site is a near-vertical (tilted at about 20 degrees) steel pipe with the above ground portion of the pipe approximately 1.2 meters (4 feet) in length. The reason the pipe is tilted is not known. The pipe appears to be buried in the ground about 20 feet (6 meters) (John Auten, personal communication, December 19, 2001). The pipe is approximately 0.46 meters (1.5 feet) in diameter and has a 1.3 centimeters (0.5 inches) thick wall. The pipe is rusted and is filled with earth inside the pipe up to the level where it enters the ground. A well identification label is attached to its side (B8542). The pipe is covered with a flat metal lid.

Location: The site is located between Hanford mile markers 26 and 27 (USGS river miles 362 and 361). The site is on the south bank of the Columbia River, approximately 45.7 meters (150 feet) from the water edge (at the time of the inspection).

Waste Type: Misc. Trash and Debris

Waste Description: The waste is a 40 centimeter (16 inch) diameter steel pipe extending from the ground approximately 1.5 meters (5 feet).

Code: 600-252

Classification: Not Accepted

Names: 600-252; Old Tank from RCRA General Inspection #LORIVFY97 Item #8

Reclassification: None

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site is an old, rusty, corrugated steel tank laying on its side. The tank is approximately 2.74 meters (9 feet) long, 0.91 meters (3 feet) in diameter, and has a 25.4 centimeter (10 inch) hole cut in its side near the bottom, and two short schedule 40 pipes on the side at either end (one pipe at each end). This item meets the specific reporting criteria of the inspection as a solid waste disposal site not previously identified for remedial action. During a site inspection on October 8, 1997 the tank was measured to be (8 feet) 2.44 meters long and (3.5 feet) 1.07 meters in diameter with a tape measure.

Location: The site is located on the south bank of the Columbia River at Hanford mile marker 2 (USGS river mile marker 386) and approximately 228.6 meters (750 feet) from the water edge (at the time of the inspection). The site is also located approximately 1.5 kilometers (0.9 miles) west, northwest of 100 B/C Area just north of Route 6. A site warning siren located just north of Route 6 aids in approaching the site. The site is located between the siren and the Columbia River.

Related Sites/ Structures: This tank is part of the old homestead found in the same area.

Process Description: The site was visited on September 26, 2000, with a cultural resource specialist familiar with the history of the farms in this area. The tank was identified as a water tank because of the lack of any oil staining inside of or below the tank, and the cuts for the pipes fit irrigation piping but not typical oil heating or storage systems.

Waste Type: Misc. Trash and Debris

Waste Description:

Code: 600-253

Classification: Not Accepted

Names: 600-253; Gravel Pit #24; Pit 24 **Reclassification** None

Type: Depression/Pit (nonspecific) **Start Date:**

Status: Active **End Date:**

Description: Gravel Pit #24 is a large excavated area that is actively used as a source of gravel and sand material. Because the bottom of the pit reached groundwater, a wetland was deliberately created in 1999 by excavating a little deeper and contouring the bottom to form islands and different depths of water. The pit was expanded to the west in 2000 as a source of additional backfill for remedial actions in the 100 B Area.

Location: The pit is located northwest of 100-B/C Area on the north side of Route 6, near the Columbia River.

Related Sites/ Structures: This gravel pit is being used (from 1998 until end of remediation) for backfill at 100 B/C sites remediated as part of site cleanup. A rejected waste site, 600-34, is east of the gravel pit, just off the northwest corner of the 100 B/C Area. It is the site where baled tumbleweeds were dumped. The tumbleweed bales have been removed.

Code: 600-254 **Classification:** Not Accepted

Names: 600-254; Abandoned 251-W Substation Mineral Oil Underground Pipelines **Reclassification** None

Type: Product Piping **Start Date:** 1/1/1946

Status: Inactive **End Date:**

Description: The Electrical Distribution equipment yard is surrounded by a locked, chain link fence and posted with "Danger" signs. The ground surface is covered with gravel. Part of the pipeline is visible at the surface, and has been painted red.

Location: The 251-W Electrical Substation is located north of Route 11A, and southwest of the 200 North Area 212-P building.

Process Description: Oil Filled Circuit Breakers (OCB's) are used in high voltage areas to extinguish any sparks caused by the triggering of any circuit breaker actions before the sparks can cause damage. The oil in the circuit breakers is usually plain mineral oil. 251-W was built in the 1940's with an underground oil pipeline to fill the circuit breakers. This process ended in the 1960's, and thus the underground oil pipeline system at 251-W has not been used since then. Because PCBs in electrical equipment has been a concern, the potential for these pipelines to be contaminated was evaluated. In the 1970's, manufacturers of new equipment began to use oil that contained polychlorinated biphenyls (PCB's), such as a brand name oil called Askeral. During pumping activities of oil from one circuit breaker to another across the Hanford Site, the equipment became cross contaminated with PCB's. But, because the underground pipelines at 251-W were abandoned in the 1960s, they were not used to carry PCB-containing mineral oil. PCB's became regulated as a hazardous material in 1976. By 1980, the Hanford Electrical Utilities had separate equipment for PCB equipment and non-PCB equipment to stop further cross contamination of equipment and material.

Waste Type: Equipment

Waste Description: In 1996, a section of pipe was removed from the 251-W yard, taken to 212-P, cut up and placed in a barrel. Wipe samples were collected from the outside and inside of the pipe and analyzed at WSCF. All three samples contained less than 1 ppm of PCB and the pipe is considered to be non-PCB material. Since the oil pipeline had been abandoned several years prior to the to the introduction of PCB oil to the Hanford Site, no PCB contaminated oil would have passed through the pipeline.

Code: 600-255 **Classification:** Not Accepted
Names: 600-255; 300 Area Stormwater Percolation Pond **Reclassification:** None
Type: Pond **Start Date:** 1/1/1980
Status: Active **End Date:**

Description: The site is a very large, unlined basin. It has a gravel bottom and cobble covered sloped sides. There are two effluent pipes protruding from the east wall of the basin. Using the contour patterns on Arcview, it was determined the site is approximately 90 meters (295 feet) long and 30 meters (98 feet) wide.

Location: The basin is located west of 300 Area, on the west side of Highway 4S.

Process Description: The stormwater is directed to two collection points inside the 300 Area, located adjacent to the west 300 Area perimeter fence, behind the 3745-B building that has a packed gravel surface. The perimeter fence of the 300 Area is posted with "Underground Radioactive Material" signs. There is no documentation to confirm that contamination exists beneath the gravel surface behind the 3754 Building, but the possibility exists anywhere inside the 300 Area fence. Since no weeds are growing in the gravel, it is possible the gravel is sprayed with herbicide. The water flows through piping, under the highway, to the basin.

Waste Type: Stormwater Runoff

Waste Description: The site receives stormwater runoff from the northwest section of the 300 Area.

Code: 600-256 **Classification:** Accepted
Names: 600-256; Atmospheric Dispersion Modeling Towers; Ethylene Glycol Release **Reclassification:** Rejected (7/28/2008)
Type: Unplanned Release **Start Date:** 1/1/1965
Status: Inactive **End Date:** 1/1/1995

Description: The concrete foundation pads and portions of the tower structures still remain in the field. There is no visual evidence of a spill at this location. The site is not marked or posted.

Location: Eight 61 meter (200 foot) tall towers were located between 200 West Area and 200 East Area, north of Route 3. They are located near semi-circular gravel roads known as the Arc Roads. The tower of concern was the southern most tower, 9 arc's out from the Met station.

Release Description: In 1995, a decision was made to dismantle the towers and ship them off site to another Federal agency. On April 10, 1995, when the contractor attempted to cut the base of the first leg of the first tower, green liquid was noticed draining out of the tower leg. The contractor stopped work and reported the situation. A maximum of 2.7 liters (0.72 gallons) of liquid had been released to the soil. One cubic foot of damp soil was removed from the spill site and six, 10 gram soil samples were collected. Three soil samples found less than detectable levels of ethylene glycol. Two samples contained ethylene glycol levels below quantities of concern. One sample contained 3830 milligrams of ethylene glycol per kilogram of soil. In order to avoid repeat releases during the tower removals, holes were drilled into the legs of the remaining towers. About 57 liters (15 gallons) of liquid was collected from the remaining tower legs. The rest of the towers were removed without incident.

Process Description: Eight, 61 meter (200 foot) tall towers were used by PNNL to collect data during atmospheric dispersion tests. The eight towers were constructed of aluminum with hollow legs.

Atmospheric detection equipment was mounted on the towers.

Waste Type: Chemical Release

Waste Description: While dismantling an atmospheric testing tower, approximately 2.7 liters (0.72 gallons) of ethylene glycol was released to the soil on 4-10-95. The damp contaminated soil was removed and placed in a barrel. Each year approximately 5.5 liters (1.5 gallons) of ethylene glycol needed to be added to the tower legs. During the 30 year use of the eight towers, it is possible that a maximum of 170 liters (45 gallons) of ethylene glycol could have been released over time to the soil near the bases of the eight towers.

Code: 600-258

Classification: Not Accepted

Names: 600-258; Item #1; RCRA General Inspection Summary Sheet HIRIVFY99

Reclassification: None

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site is surface debris from pre-Hanford activities. It is on the riverbank, facing the White Bluffs, and is covered with vegetation matching the surrounding terrain. The debris on the ground is mostly old metal wire used to wrap wooden irrigation pipes. It appears to have been pushed over the edge as a way to clean up the fields. A small concrete structure is at the northern edge of the site. The structure appears to have been filled in with dirt, although the dirt could have been piled on top of the cover, posing a cave-in hazard. The debris is very scattered over the length of the site.

Location: The site is located to the northeast of the road that follows the Columbia River, north of the 100-H Area. While the site cannot be seen from the road, it can be found by looking for the marker post shown in the photos.

Waste Type: Misc. Trash and Debris

Waste Description: The material consists of rusted metal wire used to wrap wooden irrigation pipes, old bedsprings, food cans, a small concrete box (filled in with soil), and a little broken glass.

Code: 600-260

Classification: Accepted

Names: 600-260; Roped Off Area Near Meteorological Tower

Reclassification: Rejected (7/28/2008)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The site's vegetation cover is composed of mature sagebrush and grasses and is fairly complete. T-posts laying on the ground are all that remain of the site originally found in 1999. An attached photograph shows the condition of the site as it looked in 2003.

Location: The site is located in the area between 200 East and 200 West, north of Route 3. It is approximately 415 meters (1362 feet) southeast of the Meteorology Tower and just east of the arc road labeled U4.

Waste Type: Misc. Trash and Debris

Waste Description: After discovering the roped area in 1999, the site was investigated and a radiation survey was done. No radioactive contamination was found. No soil discoloration or items were found to indicate any other waste in the area.

Code: 600-263 **Classification:** Accepted
Names: 600-263; Pile of Cans and White Powder **Reclassification** Rejected (5/31/2001)
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: There are seven cans scattered within a distance of 2 meters (6.6 feet) of each other. The cans are rusty and approximately 20 centimeters (8 inches) long. Most of the cans are broken open, revealing their current contents of calcium carbonate. No vegetation stress was noticed. A few of the cans were intact, but appeared to be empty. Some lettering could be seen on the cans. Some of the cans were marked "RL - HAR, 300 Order, -----MMABLE, Sealed For Use" One intact canister is located approximately 6 meters (20 feet) from the group of ruptured cans. It has lettering that reads "-----RAY, ___HARGE, Y-45-SE-6".

Location: The cans are located in the White Bluffs area. They are northeast of the intersection of Route 2 and Federal Avenue, and northeast of the old White Bluffs Bank building.

Process Description: Conversations between the Hanford Fire Department and the U.S. Army Corp of Engineers determined the cans originally held calcium hydride, which was used to produce hydrogen for weather balloons. In the presence of water calcium hydroxide produced hydrogen and calcium hydroxide; calcium hydroxide exposed to the environment becomes calcium carbonate.

Waste Type: Abandoned Chemicals

Waste Description: The chemical originally in the cans was calcium hydride, with a chemical formula of CaH_2 . Hydrogen and calcium hydroxide are produced when calcium hydride is mixed with water. Calcium hydroxide rapidly decomposes to calcium carbonate in the environment.

Code: 600-264 **Classification:** Accepted
Names: 600-264; Abandoned Oil Drum **Reclassification** Rejected (6/28/2001)
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:** 1/1/1943

Description: When discovered, the 55 gallon drum was laying on its side, surrounded by orchard smudge pots. The drum was inside a recently erected "Caution" tape barrier. No soil discoloration was noted in March 2000, but according to Ron Del Mar, who made the report when the drum was removed (April 18, 2000), there had been past spills to the ground from the drum. A field visit in September 2000 showed a small area of old, hardened oil-soaked ground. This oiled area was removed in June 2001. Two other drums were nearby, one to the south and one to the north. Both of these drums were empty and neither showed discolored soil underneath.

Location: The site is located 1333 meters (0.83 miles) northwest of Gravel Pit 24, west of 100-B Area.

Waste Type: Oil

Waste Description: The oil remaining has hardened on the ground surface.

Code: 600-265 **Classification:** Not Accepted
Names: 600-265; Unidentified Pipes Near the 618-10 Burial Ground **Reclassification** None

Type: Depression/Pit (nonspecific)

Start Date:**Status:** Inactive**End Date:**

Description: The site consists of two, 5 centimeter (2 inch) diameter, stainless steel pipes protruding approximately 10 centimeters (4 inches) above ground. The pipes are approximately 1.5 meters (5 feet) apart. Each stainless steel pipe has a rusted pipe inserted in the center that extends approximately 0.6 meters (2 feet) above ground.

Location: The site is located approximately 15.25 meters (50 feet) west of the 618-10 Burial Ground.

This Site Was Consolidated With:**Code:** 618-10**Names:** 618-10; 300 North Solid Waste Burial Ground; 318-10

Code: 600-266

Classification: Accepted**Names:** 600-266; Trash Dump West of Gate 117A**Reclassification** Rejected (5/31/2001)**Type:** Dumping Area**Start Date:****Status:** Inactive**End Date:**

Description: This site was discovered after the June 2000 fire. Large sagebrush had been concealing the debris. After the fire destroyed the sagebrush, an area of about 20 by 20 meters (65 by 65 feet) containing most of the trash was noted. Other material trailed off to the north. The debris (except for the cable) was removed within a month after the fire exposed it.

Location: The site is about 50 meters (150 feet) northwest of Highway 240, about 300 meters (1,000 feet) west of Gate 117A.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: Metal, glass, cinder blocks, and transite debris had been disposed here, but are now removed.

Code: 600-267

Classification: Not Accepted**Names:** 600-267; Weather Station 90 Day Storage Pad**Reclassification** None**Type:** Storage Pad (<90 day)**Start Date:** 1/1/2000**Status:** Inactive**End Date:** 1/1/2000

Description: When active, the waste at the 90 Day Pad was stored in steel drums inside a locked metal shed on the east side of the 622 F Weather Station building.

Location: The weather station complex is located on Route 6, east of 200 West Area and north of the Waste Sampling Characterization Facility (WSCF). The storage area was located on the east side of the 622-F building.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: The waste was stored in steel drums, inside a metal shed on the east side of the 622 F Weather Station. The pad was closed on August 29, 2000. At closure, all dangerous waste and dangerous waste residues were removed from the containment system. Remaining containers, liners, bases and soil or contaminated residues were decontaminated or removed. No spills occurred at this site. There is no future need for this storage area and the area has been officially closed in compliance with the closure requirements of WAC 173-303-630(10).

Code:	600-268	Classification:	Accepted
Names:	600-268; Pipe Laydown Yard Accumulation Area; 200 East Pipe Yard Drum Accumulation Area	Reclassification	Rejected (5/11/2004)
Type:	Storage Pad (<90 day)	Start Date:	1/1/1995
Status:	Inactive	End Date:	1/1/1998
Description:	The storage area and laydown yard are enclosed by a 2.4 meter (8 foot) chain link fence. The center coordinates for this site as mapped are N138108.06, E575288.25. The 90-Day Storage Pad was located in the northeast corner of the fenced area. In May 2004, the locked chain link fence was empty, except for a single conex box. The sign on the gate says PNNL, Bob Reidel and CAT 2 Non Traceable.		
Location:	The 90-day accumulation area was located inside the 200 East Pipe Laydown Area, north of the 200 East Area 810 gate.		
Process Description:	The area used for 90 Day accumulation area was part of a larger laydown area enclosed by the chain link fence, located in the northeast corner of the pipe yard. It was used to store 17 drums of mixed and radioactive waste from well maintenance activities, generated between 1993 to 1996.		
Waste Type:	Barrels/Drums/Buckets/Cans		
Waste Description:	Seventeen drums of mixed and radioactive waste from 200 West Area well drilling activities (generated between 1993 and 1996) were stored at the site. The groundwater in 200 West Area is contaminated with carbon tetrachloride. The drums contained a mixture of solids, sand and slurry. The drums were designated as F001/carbon tetrachloride. No leaking, damage or evidence of spills was ever recorded at this site. All the drums were removed in May 1998. They were shipped offsite.		

Code:	600-269-PL	Classification:	Accepted
Names:	600-269-PL; Cross Site Transfer Line Replacement; Lines SNL-3150 and 3160; New Cross-Site Transfer Line	Reclassification	None
Type:	Direct Buried Tank Farm Pipeline	Start Date:	1/1/1995
Status:	Active	End Date:	
Description:	The site is an active underground pipeline. It is marked on the surface with Underground Radioactive Material - Pipeline signs. It begins in the 241-SY tank farm and passes through Diversion Box 6241-A, located east of Beloit Ave. in 200 West Area. The line continues to the Vent Station 6241-V, located between 200 East and West areas, and runs northwest of the 241-EW-151 Vent Station. A short portion of the pipeline ties into the former termination point at the 244-A Lift Station. A segment of pipeline was extends to 241-AN Tank Farm.		
Location:	The pipeline extends from 241-SY Tank Farm inside 200 West Area to the 244-A Lift Station in 200 East Area. A large portion of the line is located between the 200 West and 200 East areas, south of Route 3. A segment of pipeline was extended to 241-AN Tank Farm.		
Related Sites/ Structures:	The pipeline is associated with the 244-A lift station, Diversion Box 6241-A and Vent Station 6241-V.		

Process Description: The pipelines were constructed in 1995 to convey tank waste to 200 East Area and will support the tank waste Vitrification project. It includes lines SNL-3150 and SSL-3160.

Waste Type: Process Effluent

Waste Description: The underground encased line transfers tank farm liquid waste between 200 West Area and 200 East Area.

Code: 600-276 **Classification:** Not Accepted

Names: 600-276; Cold Test Facility; GEDF; Hanford Geotechnical Engineering and Development Facility; Little Egypt **Reclassification:** None

Type: Laboratory **Start Date:** 1/1/1982

Status: Inactive **End Date:**

Description: The site is surrounded with light posts and chain. A vehicle gate is posted "Authorized Personnel Only". The site is a large open field with a high mound of soil in the center. Several pipes extend vertically through the surface of the soil in some areas. A small pallet containing damaged bags of bentonite is located in the southeast corner of the area adjacent to some vertical pipes. Two steel hinged plates cover access holes to underground culverts used as monitoring stations for buried waste tests.

Location: The site is located approximately 4 miles northwest of 300 Area, west of Route 4 South.

Related Sites/Structures: This waste site is associated with sitecode 600-367, buried mobile office.

Process Description: The Hanford Geotechnical Engineering and Development Facility became operational in 1982 to test burial ground subsidence control alternatives. The original site consisted of three test areas. Each test area was a cluster of buried simulated waste with a center monitoring caisson. The monitoring caissons were underground rooms constructed of a circular corrugated metal, measuring 3 meters (10 feet) in diameter and 2.5 meters (8.5 feet) deep. The monitoring caissons had a metal roof and a personnel access hatch. Each caisson contained an array of monitoring equipment. Each cluster contained three areas of buried simulated waste. The simulated waste consisted of boxes containing styrofoam and wood chips and stacks of buried 208 liter (55 gallon) drums. Later, the site was used to perform "cold test" demonstrations of geotechnical engineering prototype systems for in situ isolation and stabilization of waste disposal structures. Mock up burial trenches, caissons, vertical pipe units, drain fields, waste transfer lines and cribs were installed in the area for grout treatment and equipment testing purposes. The site contains nine areas containing simulated buried waste. The 1994 Technical Task Plan Proposal states the site also includes four tile fields and two underground storage tanks. However, Steve Phillips stated that no storage tanks or tile fields were ever placed at this site. In 1986, an area containing caissons, designed to represent the types of caissons used for Hanford waste, was installed.

Waste Type: Equipment

Waste Description: Only simulated buried waste was placed into this test site.

Code: 600-283 **Classification:** Not Accepted

Names: 600-283; Suspect Buried Equipment in Gravel Pit **Reclassification:** None

11

 A-81 Water Services Building facilities.

Code: 600-292-PL **Classification:** Accepted
Names: 600-292-PL; SALDS Pipeline; State Approved Land Disposal Site Pipeline **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:** 1/1/1995
Status: Active **End Date:**

Description: The site is an underground, 20 centimeter (8 inch) diameter PVC pipeline that feeds the State Approved Land Disposal Site. The pipeline is approximately 6 miles long.

Location: The pipeline is located north of 200 East Area and 200 West Area. The pipeline originates at the Effluent Treatment Facility, near the northeast corner of 200 East Area. It extends westward to the State Approved Land Disposal site, north of 200 West Area.

Related Sites/ Structures: The pipeline is associated with the Effluent Treatment Facility and the State Approved Land Disposal Site (sitecode 600-211).

Process Description: The SALDS receives liquid waste that has been treated and verified at the 200 Area Effluent Treatment Facility via the 8 inch diameter plastic pipeline. The liquid waste meets delisting requirements of the 216 permit #ST 4500 and is discharged as nondangerous waste; however it may contain tritium.

Waste Type: Process Effluent

Waste Description: Treated and verified liquid waste received from the 200 Area Effluent Treatment Facility (ETF). The waste meets the delisting requirements of the 216 permit ST 4500 and is considered nondangerous; however it may contain tritium.

Code: 600-304 **Classification:** Not Accepted
Names: 600-304; White Bluffs Sanitary Water **Reclassification:** None
Type: Product Piping **Start Date:**
Status: Inactive **End Date:**

Description: This site consists of the White Bluffs sanitary water service piping as shown on construction drawing H-11-3709 and three associated features discovered during the Orphan Site Evaluation (OSE) process.

Location: A network of clean water service pipelines connect facilities as shown in White Bluffs drawing plot plan H-11-3709 and C-3316. A total of 13,870 meters (45,507 feet) of pipeline were plotted with 125 segments represented by 168 vertices locations with attached coordinates.

Process Description: Little is known about the pipeline sizes, depth or construction material.

Code: 600-330 **Classification:** Accepted
Names: 600-330; Division Street Service Station **Reclassification:** Rejected (6/10/2010)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: During the 2010 geophysical investigation it was noted that the site was flat terrain with grasses and occasional rabbit brush. Originally the site was thought to consist of potential underground components of a service station, including storage tanks, associated piping, and contaminated soils.

Location: The site's historical location is on the east side of Division Street, south of Avenue A and west of the administration building (IN-323). Further historical research indicated that the service station maybe located on the east side of Division Street, south of Avenue A and east of the theater building (IN-163 and IN-321). The coordinates for the site are E585804.0, N139435.0.

Process Description: This site was used for the dispensing of petroleum products for automotive use. The specific location of underground storage tanks and associated piping for this site are unknown.

Waste Type: Oil

Waste Description: The waste consists of underground storage tanks, associated piping and underlying soil.

Code: 600-335

Classification: Accepted

Names: 600-335; Service Station and UST

Reclassification: Rejected (6/10/2010)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: During the 2010 geophysical investigation it was noted that the site was flat terrain with grasses and occasional rabbit brush. Originally, the site was thought to consist of potential underground components of a service station, including storage tanks, associated piping, and contaminated soils, that were identified in historical photo # P-8244. The photo also appears to show two gasoline pumps.

Location: The coordinates for the site are E585924.0, N139746. The site is located approx. 54 meters (177 feet) to the SW of the former 145 Building.

Code: 600-336

Classification: Accepted

Names: 600-336; 609-G Septic Tank and Tile Field; 6607-03; 6607-3

Reclassification: Closed Out (11/4/2009)

Type: Septic Tank

Start Date: 1/1/1989

Status: Inactive

End Date: 1/1/1998

Description: The waste site is an underground septic tank and tile field. It was properly abandoned in 1998. A new regional septic system, built in 1997, replaced the need for individual septic tanks.

Location: The septic tank and tile field are located south of Route 3, southwest of the 200 Area Fire Station.

Related Sites/ Structures: The septic system was associated with the 609-G office facility.

Closure Info: Final: The septic tank and tile field were abandoned per WAC codes in 1998.

Code: 600-337

Classification: Accepted

Names: 600-337; 6290 Building Drain Field; 6607-01;

Reclassification: None

6607-1; Rigging Services Facility Septic

Type: Septic Tank **Start Date:** 1/1/2003

Status: Active **End Date:**

Location: This septic system is located outside the west perimeter fence of 200 East Area. It is northeast of the 6290 Rigging Facility.

Process Description: A new tank was installed to meet facility expansion requirements.

Code: 600-396 **Classification:** Accepted

Names: 600-396; 600-396 Debris Pit near Riverland **Reclassification:** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is a soil depression filled with rusted cans and broken bottles.

Location: The pit is located about 100 feet south of Riverland Rd (aka Priest Rapids Rd) and west of Route 24. It is south of WIDS sitecode 600-101. Coordinates for the pit are N143410.28 E558809.12.

Code: 600-399-PL **Classification:** Accepted

Names: 600-399-PL; ERDF Leachate Line; Groundwater Transfer Line; Groundwater Treatment System; Liquid Effluent Treatment Facility Pipeline, LERF Pipeline **Reclassification:** None

Type: Process Sewer **Start Date:**

Status: Active **End Date:**

Description: The waste site is an underground pipeline. It is constructed of six inch diameter polyvinyl chloride (PVC) pipe.

Location: The pipeline extends from the UP1-5 pit (in 200 West Area near 16th Street and Beloit Ave.) to the LERF basins (in 200 East Area, east of Canton Ave.)

Release Description:

Related Sites/ Structures: The pipeline is associated with the ERDF Landfill (sitecode 600-148) and the LERF basins (sitecode 200-E-17). The segment of pipeline from the ERDF pump house to the UP1-5 pump pit is sitecode 600-401-PL. The active Export Water line intersects the 600-284-PL and 600-399-PL pipelines inside 200 East Area, south of the Canister Storage building.

Process Description: The pipeline conveys liquid waste to the Liquid Effluent Retention Facility (LERF). The LERF pipeline has manholes along its route for air vacuum relief valves (AVRV). The AVRV's in these manholes are inspected during ERDF leachate transfers to LERF Basins. The ERDF leachate is a delisted waste at the source (i.e. before entering the transfer line) per the 1999 ERDF CERCLA ROD amendment. Per WCH-182, Rev. 2, leakages are only reportable to EPA if there is difference in the flow totalizers at ERDF and LERF that exceed 5%.

The TEDF pipeline (600-291-PL) and the LERF pipeline (see 600-399-PL) run parallel,

approximately 10 feet apart, for the majority of the length of the pipelines.

The LERF transfer line sends untreated effluent to the Liquid Effluent Retention Facility (basins). Effluent stored in the basins is sent to the Effluent Treatment Facility (ETF).

The pipeline has received waste from a groundwater extraction facility, located southeast of 221-U and also leachate from the Environmental Restoration Disposal Facility (ERDF).

Code: 600-404	Classification: Accepted
Names: 600-404; 506B and 506BA Unconventional Septic System	Reclassification: Closed Out (12/7/2015)
Type: Septic Tank	Start Date:
Status: Inactive	End Date:

Description: The site is a small septic system that supported the 506B and 506BA telephone exchange buildings. Sanitary drain lines from the two buildings discharged into a 55-gallon drum that was filled with rocks. No drain field is present.

Location: The site is located south of Rt 3, west of the 506B building, between 200 East and 200 West.

Process Description: Recent excavations (April 2015) to locate the system found an unconventional system comprised of what appeared to be a buried 55 gallon drum filled with rocks. No conventional septic tank or drain field could be located through extensive excavations. Discharge to the system was ceased and the bathroom facilities will be removed. Water to the facility was shut off with a lock on the valve. The system will be replaced with a portable toilet. Since no drainfield was located, it is assumed that the drum was open at the bottom and the system operated as cesspit.

Waste Type: Sanitary Sewage

Waste Description:

Code: 616	Classification: Accepted
Names: 616; 616 Building Non-Radioactive Dangerous Waste Storage Facility; 616 Nonradioactive Dangerous Waste Storage; 616 NRDWSF	Reclassification: Closed Out (10/24/2001)
Type: Storage	Start Date: 1/1/1986
Status: Inactive	End Date: 1/1/2001

Description: The 616 Nonradioactive Dangerous Waste Storage Facility (NRDWSF) is a Clean Closed Resource Conservation and Recovery Act Treatment, Storage unit (RCRA TSD). The above ground building was partitioned into six areas, referred to as cells, for storage of different types of hazardous waste. The facility also contains an office and a material handling area.

Location: This site is located on the north side of Route 3, between 200 East and 200 West across from the fire station.

Related Sites/ Structures: Drains in the two outdoor loading pads discharged to the 616-WS-1 French Drain. The building is connected to the 6607-5 Septic System.

Process Description: This facility provided container storage for nonradioactive dangerous waste generated in the research and development laboratories, process operations, construction, waste site cleanup/remediation, environmental monitoring, maintenance, and transportation functions throughout the Hanford Facility and approved off site facilities.

The 616 NRDWSF operated as a clean, well maintained, nonradioactive dangerous waste container storage unit. Detailed storage records were maintained. Only containers of the proper type and in good condition were accepted. Storage and loading area containment was designed to preclude spills from reaching soil, and containment surfaces were maintained to ensure integrity. Waste was managed to minimize the potential for spills. The latest operating methods and administrative controls required waste spills to be cleaned up promptly and completely and the waste removal area to be analytically verified.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: No wastes remain in the facility. The facility had provided container storage for nonradioactive dangerous wastes. These wastes consisted of listed wastes, wastes from nonspecific sources, characteristic wastes, and state-only wastes.

Closure Info: Final: Because operating records did not demonstrate that early operations within the 616 facility met spill cleanup requirements, the building was considered potentially contaminated and underwent decontamination. Equipment used for waste handling was removed. The storage cell floors, sumps, trenches, and outdoor loading pads were cleaned using nonregulated detergents. The rinsates were collected, analyzed, designated and disposed of as nondangerous waste. Some minor residual staining/discoloration of coated surfaces remained after decontamination. This was allowed in the closure plan.

Completion of closure plan requirements was certified by a Professional Engineer on 6/13/2001. The RCRA permit Closure Certification was transmitted to the Washington Department of Ecology on 9/5/2001. Ecology accepted the Closure Certification on 10/24/2001.

Sampling of the french drain was required as part of the Closure Plan for the 616 facility. The gravel within the french drain was removed and stored pending sampling results. A single soil sample was taken from the center of the drain. The sample was analyzed for pH, volatile organic compounds, semi-volatile organic compounds, RCRA (Resource Conservation and Recovery Act) metals, PCBs (polychlorinated biphenyls), herbicides, pesticides, phosphorous pesticides, cyanide, total organic halides, anions, phenols, and chrome VI. The sample met closure standards for all constituents.

Code: 618-6

Classification: Accepted

Names: 618-6; Solid Waste Burial Ground #6

Reclassification: Rejected (10/7/1998)

Type: Burial Ground

Start Date: 1/1/1943

Status: Inactive

End Date: 1/1/1944

Description: The 618-6 Burial Ground was originally located in the southeast corner of 300 Area near where the 325 Building is currently located. The waste was exhumed and relocated twice to allow for 300 Area construction expansions. In 1962, the contents were permanently moved to the 618-10 Burial Ground.

Location: This burial ground has been moved twice. The site was first located in the southeast corner of the 300 Area. Then the contents of the site were moved to just south of the 316-1 Process Pond. Finally, the contents were exhumed again and moved to the 618-10 Burial Ground.

Waste Type: Equipment

Waste Description: The unit contained solid uranium waste.

Code: 622-1 **Classification:** Accepted
Names: 622-1; Construction and Demolition Debris **Reclassification:** Rejected (5/31/2001)
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: All material has been removed and the site sampled for radioactivity, asbestos, and organics. The site is no longer marked or posted.

Location: This site is located south of the intersection of Sixteenth Street and Albany Avenue outside the perimeter fence of the 200 West Area.

Waste Type: Asbestos (non-friable)

Waste Description: The site contained transite siding.

Waste Type: Asbestos (friable)

Waste Description: The site contained friable asbestos.

Waste Type: Misc. Trash and Debris

Waste Description: The site contained miscellaneous trash.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: Some 208-liter (55-gallon), 19-liter (5-gallon), and 4-liter (1-gallon) containers were present at the site.

Code: 622-R ST **Classification:** Accepted
Names: 622-R ST; 6607-02; 6607-2; 622-R Atmospheric Physics Laboratory Septic Tank; 622-R Septic Tank **Reclassification:** None
Type: Septic Tank **Start Date:** 1/1/1965
Status: Inactive **End Date:**

Description: This site consists of a septic tank, distribution box, and tile field. The septic tank is available for use as an emergency holding tank. The rest of the system has been abandoned.

Location: This site is located just northwest of the 622-R Atmospheric Physics Laboratory Building. This building is northwest of the 200 West Area between Route 2 and Route 3.

Related Sites/Structures: The associated structure is the 622-R Building.

Process Description: This site provided sanitary sewage disposal for the 622-R Building. A pump station was added in 1997 to reroute raw sewage to Septic System 6607-09. The septic tank was emptied and will remain available as an emergency holding tank in case of pump failure. The effluent has been routed to 6607-9.

Waste Type: Sanitary Sewage
Waste Description: The unit received sanitary wastewater.

Code: 6241-A **Classification:** Accepted
Names: 6241-A; 6241-A Diversion Box **Reclassification:** None
Type: Diversion Box **Start Date:**
Status: Active **End Date:**

Description: 6241-A is a booster station for the new cross site transfer pipeline. The building is a radiological facility.

Location: The site is located southeast of 221-U, east of Beloit Avenue, between 13th and 16th Street.

Related Sites/Structures: The diversion box is associated with the Replacement Cross Site Transfer Line (WIDS sitecode 600-269).

Process Description: The main structure (room 105) is an underground building with the top of the roof approximately 0.75 meters (2.5 feet) above finish grade. This structure houses two booster pumps and is designed for maintenance access on an infrequent basis. It is cast-in-place concrete equipped with a stainless steel floor liner at the base floor level. A steel shield floor is located 1 meter (3.3 feet) above the base floor with the process piping underneath.

Waste Type: Process Effluent

Waste Description: Some residual waste will be found in the dead legs of the piping systems.

Code: 6241-V **Classification:** Accepted
Names: 6241-V; 6241-V Vent Station **Reclassification:** None
Type: Control Structure **Start Date:**
Status: Active **End Date:**

Description: The vent station is a radiologically controlled facility. Contamination is on the surfaces below the deck plates.

Location: The site is located half way between 200 East and 200 West Areas, south of Route 3, south of the 200 Area Fire Station.

Related Sites/Structures: The vent station is associated with the Replacement Cross Site Transfer Line (WIDS sitecode 600-269).

Process Description: The vent station is located at the hydraulic high point of the RCSTS, and the pipeline slopes down continuously from this point to the two ends. The main structure (room 105) is an underground building with the lower half of the building below finish grade. It houses the transfer piping and other items that support operation of the RCSTS and is designed for maintenance access on an infrequent basis. The main structure is cast-in-place concrete equipped with a stainless steel floor liner and a carbon steel shielding floor located above the transfer piping.

Waste Type: Process Effluent

Waste Description: Some residual waste will be found in the dead legs of the piping systems.

Code: 6607-1	Classification: Accepted
Names: 6607-1; H-40 Gun Site Septic Tank	Reclassification: Rejected (9/10/2010)
Type: Septic Tank	Start Date: 1/1/1945
Status: Inactive	End Date: 1/1/1958

Description: This site includes a manhole located near the kitchen/mess hall and toilet/shower foundations and a below ground concrete septic tank with three manholes. The manholes and the septic tank have been backfilled with clean pit run material and are no longer visible, and the ground over the tank is gravel as of June 2001.

Location: This site is located 1.1 kilometers (0.7 miles) southeast of the southeast corner of 200 East Area, on the south side of Route 4 South. Trees viewed from Route 4 South aid in locating the site. The septic tank is located in the eastern portion of the H-40 Gun Site.

Related Sites/ Structures: The site is associated with 600-227 (the H-40 Gun Site Building Foundations kitchen and toilet/shower buildings).

Process Description: This site provided sanitary sewage disposal for a former U. S. Army facility. Typically, Camp Hanford's anti-aircraft artillery sites were each roughly 20 acres in size and contained any number of buildings (typically around 20), various utility distribution systems, roads, and sidewalks. Each site consisted of emplacements protected by revetments made of sandbags and wood planking, wooden structures, prefabricated metal buildings, and, later, permanent, concrete block structures. The prefabricated buildings had aluminum walls and roofs with wooden or concrete floors set on concrete pier blocks and were the most commonly constructed. The permanent structures included barracks, latrines, mess halls, craft shops, pump houses, motor pools, and radar facilities. Each site typically had a small arms range, water storage cistern, sanitary, and sewage disposal facilities. Pathways, sidewalks, roadways, and parking lots connected the structures.

Waste Type: Water

Waste Description: The tank contains water to a depth of 0.9 meters (3 feet).

Waste Type: Sanitary Sewage

Waste Description: The unit received unknown amounts of sanitary sewage.

Code: 6607-2	Classification: Accepted
Names: 6607-2; Gun Site H-42 Septic Tank	Reclassification: Rejected (9/10/2010)
Type: Septic Tank	Start Date: 1/1/1945
Status: Inactive	End Date: 1/1/1955

Description: This site includes a manhole, two septic tanks and connecting tile field. In May 2001, the open holes associated with the septic system were backfilled. The original manhole measured 71 centimeters (28 inches) diameter by 86 centimeters (34 inches) deep, with two inlet pipes, one outlet pipe and is constructed of cement bricks and mortar. The large septic tank is below grade and had three manholes and a concrete box structure visible above grade. The manholes were

covered with concrete covers. The center manhole was broken providing visual access to the interior of the tank, prior to being backfilled. In 1997, the tank contained water. An above ground structure, located at the west end of the tank, appears to have been used as a pumping station to pump liquid to the smaller tank located to the west. The overall site dimensions of the large tank are 21 by 9 meters (70 by 30 feet). The small tank to the west measures 2.2 by 1.7 meters (7.3 by 5.8 feet) and has one covered manhole. The structures had been surrounded by orange plastic fencing, but the fencing was destroyed in the 2000 grass fire. The open features were backfilled in 2001.

Location: The site is located 6.4 kilometers (4 miles) south of 200 East Area, on the south side of Army Loop Road and east of the powerline road to Rattlesnake Mountain.

Related Sites/ Structures: The site received sanitary sewage from the 600-49, H-42 Gun Site Building toilet/shower building and the kitchen/mess hall building.

Process Description: This site provided sanitary sewage disposal for a U.S. Army Facility.

Waste Type: Water

Waste Description: The septic tank contained water at the time of the inspection.

Waste Type: Sanitary Sewage

Waste Description: The unit received unknown amounts of sanitary sewage.

Code: 6607-3

Classification: Accepted

Names: 6607-3; Anti-Aircraft Artillery Site H-51 Septic Tank

Reclassification: Rejected (9/10/2010)

Type: Septic Tank

Start Date: 1/1/1945

Status: Inactive

End Date: 1/1/1955

Description: The septic tank is constructed of concrete, has three open manholes and an above ground square concrete box-like structure located on the east end. This box-like structure may have been used to support a pump for pumping liquid to the drain field. The tank is below grade. The roped off section measures 17 by 4.6 meters (55 by 15 feet) and the tank interior is 3.4 meters (11 feet) deep. The drain field is located east of the septic tank. The septic tank and four manholes are delineated by orange plastic fencing.

Location: This site is located approximately 2.4 kilometers (1.5 miles) southwest of 200 West Area just west of Army Loop Road between Highway 240 and Army Loop Road.

Related Sites/ Structures: The site is associated with the former U.S. Army Anti-Aircraft Gun Site H-51, which is sites 600-53 (the building foundations) and 600-220 (the dumping areas).

Process Description: This site provided sanitary sewage disposal for a U.S. Army Facility.

Waste Type: Sanitary Sewage

Waste Description: The unit received unknown amounts of sanitary sewage.

Code: 6607-4

Classification: Accepted

Names: 6607-4; 6607-4 Septic System; Replacement for 2607-FSN; 609A Building Septic Tank; 6607-04 **Reclassification** None

Type: Septic Tank **Start Date:** 1/1/1989

Status: Active **End Date:**

Description: The septic tanks consist of two concrete tanks placed in series. The design capacity of the tanks was 1800 gallons (6813 liters) with the first tank being 1200 gallons (4542 liters) (minimum) and the second being between 600 and 1000 gallons (2271 liters and 3785 liters).

Location: The septic system is located east of the 609-A Building (200 Area Central Fire Station) and south of Route 3. The septic tanks are approximately 100 feet east of the northeast corner of the 609-A building. The drainfield is located just east of the tanks.

Related Sites/ Structures: The 6607-4 septic system is associated with the 609-A building and the 2607-EP septic system.

Waste Type: Sanitary Sewage

Waste Description: The system receives sanitary sewage from the 609-A building.

Code: 6607-5 **Classification:** Accepted

Names: 6607-5; 616 Building Septic System; 6607-05 **Reclassification** None

Type: Septic Tank **Start Date:** 1/1/1986

Status: Active **End Date:**

Description: The unit consists of a septic tank and a drain field. The septic tank is surrounded by four yellow posts and is covered by gravel. The drain field is surrounded by metal posts and chain. The drain field is not marked by a sign.

Location: The tank is located on the south side of the 616 Building. The drain field extends southwest of the tank.

Related Sites/ Structures: The site is associated with the 616 Nonradioactive Hazardous Waste Storage Facility.

Process Description: The unit provides sanitary sewage disposal for the 616 Building.

Waste Type: Sanitary Sewage

Waste Description: The unit receives sanitary wastes from the 616 Building.

Code: 6607-6 **Classification:** Accepted

Names: 6607-6; 6701 Building Septic Tank and Tile Field; Wye Barricade Septic; 6607-06 Septic System **Reclassification** None

Type: Septic Tank **Start Date:** 1/1/1991

Status: Active **End Date:**

Description: The waste site is an underground septic tank and tile field.

Location: The septic tank is located at the Hanford Wye Barricade. It is located east of the guard shack building.

Code: 6607-7 **Classification:** Accepted

Names: 6607-7; Yakima Barricade Septic System and Permitted Holding Tank; 6607-07 **Reclassification:** None

Type: Septic Tank **Start Date:**

Status: Active **End Date:**

Description: The waste site is an underground septic holding tank.

Location: The holding tank is located north of the Yakima Barricade guard house.

Code: 6607-8 **Classification:** Accepted

Names: 6607-8; 251-W Electrical Substation Septic System; 6607-08 **Reclassification:** None

Type: Septic Tank **Start Date:** 1/1/1946

Status: Active **End Date:**

Description: The waste site is an underground septic tank and tile field.

Location: The 251-W Electrical Substation is located north of Rt 11A, south of 200 North Area. The septic system is south of the 251-W building.

Code: 6607-9 **Classification:** Accepted

Names: 6607-9; Project W-011H; Septic Tank 6607-9 Large On-Site Sewage System; 6607-09 Septic System **Reclassification:** None

Type: Septic Tank **Start Date:**

Status: Active **End Date:**

Description: The site is a septic system and disposal field. The site is bordered with a steel post and chain barricade with signs posted "SEPTIC TANK AND DISPOSAL FIELD." There are five manholes and two concrete boxes with metal hatch covers visible at grade level at the site. There is also an electrical panel with a red warning light on top and a bell on the side.

Location: The site is located east of 200 West Area and immediately west of the perimeter fence that surrounds the Waste Sampling and Characterization Facility.

Related Sites/ Structures: Waste Sampling and Characterization Facility.

Waste Type: Sanitary Sewage

Waste Description: The site receives sanitary sewage from the Waste Sampling and Characterization Facility.

Code: 6607-10 **Classification:** Accepted

Names: 6607-10; Hanford Patrol Training Academy Septic System **Reclassification** None

Type: Septic Tank **Start Date:**

Status: Inactive **End Date:**

Location: The septic tank and tile field are located west of 300 Area, north of Horn Rapids Rd.

Related Sites/ Structures: The septic system is associated with the Patrol Training building (662).

Code: 6607-13 **Classification:** Accepted

Names: 6607-13; Core Area Septic; Project FP-0003 Septic **Reclassification** None

Type: Septic Tank **Start Date:** 1/1/1993

Status: Active **End Date:**

Description: The waste site is an underground septic tank and drain field.

Location: The septic and drain field are located in a fenced area attached to the southwestern boundary of 200 East Area. It is southwest of the 2750E building. 6607-13 is north of 1st Street.

Code: 6607-16 **Classification:** Accepted

Names: 6607-16; ECN-C018H-040; Project C-018H; 6107-16 Septic System **Reclassification** None

Type: Septic Tank **Start Date:** 1/1/1994

Status: Active **End Date:**

Description: The site is visible in three separate locations. Two locations for the tanks and one for the sanitary tile field. All locations are surrounded with steel fence posts and chain. The sanitary tile field is posted with a sign "Sanitary Tile Field." The tanks are not posted as septic tanks however, all access covers are posted as confined spaces. The septic tank south of the 2025E building has two concrete boxes with metal hatch covers, four vertical culverts, and an electrical panel. The tank south of the 2025EA building has five vertical culverts. The sanitary tile field has several iron rods painted yellow with square orange tops and capped PVC pipes protruding vertically from the tile field.

Location: The site is located just northeast of the 200-E area within the Effluent Treatment Facility (ETF). The two septic tanks are located on the south side of the 2025E and 2025EA buildings. The sanitary tile field is located just north of the entrance road to the ETF.

Related Sites/ Structures: 2025E building and 2025EA building.

Waste Type: Sanitary Sewage

Waste Description: The septic system receives sanitary sewage from the 2025E and 2025EA buildings and is designed to receive 5000 gallons per day. The current daily flow is 2725 gallons per day.

Code: 6607-17 **Classification:** Accepted

Names: 6607-17; Conoco Service Station Septic System; 6291 Service Station Building Septic System **Reclassification** None

Type: Septic Tank **Start Date:** 1/1/1995

Status: Active **End Date:**

Description: The waste site is an underground septic tank and drain field.

Location: The 6291 Service Station Building is located west of 200 East Area, near the intersection of Rt 4S and 4th Street. The septic system is located east of the 6291 building.

Process Description: The drain field has a 1365 liter (360 gallon) per day capacity.

Code: 6607-18 **Classification:** Accepted

Names: 6607-18; 609-G and MO292 Septic System **Reclassification** None

Type: Septic Tank **Start Date:** 1/1/1997

Status: Active **End Date:**

Description: The waste site is an underground septic tank.

Location: The septic tank is located south of Route 3, near the 200 Area Fire Station complex. It is located north of the 609-G building.

Related Sites/ Structures: The tank is associated with the 2607-EP septic system.

Process Description: The new 5678 liter (1500 gallon) tank is tied to the 2607-EP septic system, located inside 200 East Area.

Code: 6607-19 **Classification:** Accepted

Names: 6607-19; Emergency Vehicle Operations Facility Mobile Office Septic **Reclassification** None

Type: Septic Tank **Start Date:**

Status: Active **End Date:**

Description: The waste site is an underground septic system that services two mobile office units near the Emergency Vehicle Operations area.

Location: The septic system is located north of Horn Rapids Rd and west of Ila Lane. It is west of the Hazardous Material and Emergency Response (HAMMER) facility.

Code: 700-1 **Classification:** Accepted

Names: 700-1; 747 Building 90-Day Waste Accumulation Area **Reclassification** Rejected (9/14/2000)

Type: Storage Pad (<90 day) **Start Date:**

Status: Inactive **End Date:** 1/1/1995

Description: There is no longer a 90 Day Storage Area at the 747 Building; the part of the 747 Building that

held the 90 Day pad is no longer in use.

Location: The 747 Building is on the corner of Knight Street and Goethals Drive in Richland, west of the Federal Building. The pad was in the now-abandoned (unused) part of the building that is east of the whole body count facility. However, the specific location of the 90 Day Storage Pad within the building is not known.

Related Sites/ Structures: The 747 Building is the whole body count facility operated by PNNL.

Process Description: This pad supported the HEHF Industrial Hygiene Laboratory in the 747 Building.

Code: 1100 HPADS	Classification: Accepted
Names: 1100 HPADS; 1100 Area Hanford Patrol Academy Demolition Site	Reclassification: Closed Out (9/6/1995)
Type: Depression/Pit (nonspecific)	Start Date: 1/1/1984
Status: Inactive	End Date: 1/1/1995

Description: The site consisted of two demolition areas that were used by the Hanford Patrol to detonate discarded explosive chemical products generated on the Hanford Site. These products were either excess material or beyond their designated shelf life. The RCRA TSD permit was closed on 10/26/1995.

The site was a treatment unit for nonradioactive explosive, ignitable, shock-sensitive, and/or reactive discarded chemical products. The discarded chemical products treated at the site all exhibited the dangerous waste characteristics of ignitability and reactivity. Some of the discarded chemical products also exhibited the dangerous waste characteristic of corrosivity and may have had the state-only designations for toxic extremely hazardous waste, toxic dangerous waste, persistent halogenated hydrocarbons, extremely hazardous waste, persistent polycyclic aromatic hydrocarbons, extremely hazardous waste, and/or carcinogenic dangerous waste.

The treatment design capacity of the site was 568 liters (150 gallons) of discarded explosive chemical products per day. The last detonation event at the site took place on October 27, 1991.

Location: The site is located northwest of 1100 Area and west of 300 Area.

Waste Type: Chemicals

Waste Description: The unit was used for the treatment of shock-sensitive or potentially explosive chemical wastes. The following detonations took place: 1984: Ethyl Ether 169 g (0.37 lb), Perchloric Acid 44.3 kg (97.7 lb), Nitric Acid 1.42 kg (3.13 lb); 1985: 2,4,6-Trinitrorescorcinol 25 g (0.06 lb), 2,4-Dinitrorescorcinol 70 g (0.15 lb), 2,4-Dinitrophenol 500 g (1.10 lb), Alpha-Nitrosomethylisobutylketone 174 g (0.38 lb), Trinitrotoluene 100 g (0.22 lb), Tetrahydrofuran 36 kg (79.4 lb), Picryl Chloride 300 g (0.66 lb), Picric Acid 100 g (0.22 g), Perchloric Acid 4.4 kg (9.7 lb), Ethyl Ether 4.7 kg (10.4 lb), Hexadinitrophenylamine 70 g (0.15 lb), Glycol Dimethyl Ether 500 g (1.1 lb), Carbon Trichloride 600 g (1.3 lb), Carbon Disulfide 1,100 g (2.4 lb), Butyl Ethanol 9.5 kg (20.9 lb), Butyl Cellosolve 100 g (0.22 lb), Benzene with N-Butyl Lithium 100 g (0.22 lb); 1986: None; 1987: Ethyl Ether 20 kg (44.1 lb), Picric Acid 200 g (0.44 lb).

Code: 1100-9	Classification: Accepted
---------------------	---------------------------------

Names: 1100-9; 1164 Building 90-Day Waste Accumulation Area **Reclassification** Rejected (9/14/2000)

Type: Storage Pad (<90 day) **Start Date:**

Status: Inactive **End Date:** 1/1/1998

Description: The 90 Day Storage Area was inside the 1164 Building, a small (15 by 11 meters [48 by 36 feet]) steel structure surrounded by gravel and pavement. The Building is closed, and has transferred to the Port of Benton. However, the Port has not started to use it yet.

Location: The 1164 Building is northeast of the 1167A Excess Salvage Office Building. The 1164 Building is also marked as the 2453 Building. The exact location of the pad within the building is not known.

Related Sites/ Structures: The pad held waste paint aerosol cans and associated equipment waste used at the Excess Salvage Yard.

Process Description: The 90 Day Storage Area was used by the Investment Recovery group to process aerosol cans, which were used to identify sensitive equipment for central stores and investment recovery, along with rags, brushes, and other miscellaneous wastes.

Waste Type: Chemicals

Waste Description: The wastes stored here were materials (for example, rags and brushes) and paints left over from marking sensitive equipment.

Code: 1100-12 **Classification:** Accepted

Names: 1100-12; 1100-12 Dumping Areas **Reclassification** Rejected (5/9/2000)

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The site is miscellaneous pre-Hanford debris consisting of old concrete, glass, and metal (e.g., camp stove, food cans, buckets, and wire). The decayed batteries previously reported were not seen on May 4, 2000. Two separate areas of debris were reported in 1996 and 1998, but only one is evident in 2000.

Location: The debris fields are located in the northern portion of the 1100 area and just south of the powerline road that runs east - west. They are east the of ATG facility and 500 meters west of Stevens Drive.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: Buckets and cans were observed at the site.

Waste Type: Batteries

Waste Description: Dry cell batteries were observed at the site in 1996. Vegetation surrounding the batteries was reported to be stressed in 1996, but no sign of the batteries was found in 2000.

Code: 1100-13 **Classification:** Not Accepted

Names: 1100-13; Gravel Pit #1; Pit 1 **Reclassification** None

Type: Depression/Pit (nonspecific) **Start Date:**

Status: Active

End Date:

Description: The site is a pit where sand was excavated to be used for bedding and backfill material. The northern perimeter is marked with post and chain.

Location: Pit #1 is located north of the 1100 Area, north of the 1171 Laydown Yard.

Related Sites/ Structures: UPR-1100-6 is located adjacent to Pit 1.

Code: 1100-14

Classification: Not Accepted

Names: 1100-14; Gravel Pit #2; Pit 2

Reclassification: None

Type: Depression/Pit (nonspecific)

Start Date: 1/1/1954

Status: Inactive

End Date: 1/1/1985

Description: The pit was a source of gravel for backfill material. It also was used as a dumping site for miscellaneous debris, paint and solvents.

Location: The pit is located north of 1100 Area and north of the 1171 Laydown yard.

Related Sites/ Structures: 1100-2 Paint/Solvent dump

Code: 1100-15

Classification: Not Accepted

Names: 1100-15; Gravel Pit #3; Pit 3

Reclassification: None

Type: Depression/Pit (nonspecific)

Start Date: 1/1/1979

Status: Inactive

End Date: 1/1/1985

Description: The site was used as a source of gravel for backfill material. It was also used as a disposal site for construction material (concrete rubble and roofing material). Occasionally antifreeze and degreaser solutions from the 1171 building were disposed into the pit.

Location: The pit is located north of 1100 Area, north of the 1171 Laydown Yard, on the west side of the railroad tracks.

Related Sites/ Structures: The site was associated with 1100-3 Antifreeze, Degreaser Pit.

Code: 1100-18

Classification: Not Accepted

Names: 1100-18; Cistern and Possible Historic Disposal Site Identified During RCRA General Inspection 1100FY98 Item #3

Reclassification: None

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site appears to be a cistern. In the general area of the cistern is a homestead dump site. There appears to have been a well casing inside of the cistern. The casing is plugged approximately 1.5 meters (5 feet) below the ground surface.

The cistern is in the middle of an old concrete pad and is lined with concrete (at least as much as is visible). The area between the sides of the cistern and the metal well casing is filled with large rocks and cobbles. Connected to this concrete pad, there appears to be another concrete-lined, rock-filled hole. The second hole is now very overgrown and is filled with large rocks and cobbles. It appears to have been rectangular and may have had a wooden cover. A snake was living under the remains of this wooden cover. North of the cistern are the remains of a wire mesh fence and an old household dump (cans primarily, some glass and ceramics). Further north, there is a smaller concrete structure. It is square and is now filled with dirt and vegetation. Overall, the site is mostly grass-covered, with some mature sagebrush and tumbleweeds. Debris is concentrated in the household dump, but there is some scattered debris across the site, including the metal frame of a coil mattress. The features mentioned thus far (with the exception of the small concrete structure) are south of an extensive ditch (irrigation). Northeast of the cistern and north of the ditch, a cement pipe was found extending into the ditch. Just north of this feature, some of the cement pipe is exposed. This could be considered a physical hazard. Southeast of the cistern are the remains of an old foundation. The cellar presents a physical hazard. Adjacent to the foundation is a small, thin area of coal, level with the ground surface.

Location: The site is located approximately 274 meters (900 feet) west of Stevens Drive and 91 meters (300 feet) north of the east/west power line and dirt road to the Allied Technical Group (ATG).

Waste Type: Misc. Trash and Debris

Waste Description: The waste consists of a cistern (with an interior well casing), several other concrete structures, a foundation, and miscellaneous debris (cans, glass, ceramics, an old mattress frame).

Code: 1100-20

Classification: Accepted

Names: 1100-20; Hammer 90-Day Storage Pad

Reclassification: Rejected (9/14/2000)

Type: Storage Pad (<90 day)

Start Date:

Status: Inactive

End Date: 1/1/2000

Description: The storage pad was a "clamshell" unit that protected the waste from the elements and served as a secondary containment. The site is now inactive; all regulated waste was removed by February 15, 2000.

Location: The site was located on the northwest side of the Hammer Facility, near the transportation maintenance shop.

Process Description: The pad stored flammable paint waste.

Description:

Waste Type: Chemicals

Waste Description: The pad stored flammable paint waste.

Description:

Code: B PLANT FILTER

Classification: Accepted

Names: B PLANT FILTER; Filter F-34-4; 221-B-TK-34-2 Decant Filter; B Plant Filter

Reclassification: None

Type: Process Unit/Plant

Start Date: 1/1/1945

Status: Inactive

End Date:

Description: The Decant Filter (F-34-4) is a cylindrical unit located inside and above Tank 221-B-34-2. The filter was a part of the neutralized current acid waste treatment mission.

Location: The unit sits within and above the 221-B-34-2 Tank, located in the eastern central portion of Cell 34. Cell 34 is near the west end of the 221-B Building.

Related Sites/ Structures: Structures associated with this unit include Tanks 221-B-34-2 and 221-B-34-1, jumpers, Cell 34, and the other equipment associated with NCAW treatment.

Process Description: The F-34-4 Filter was part of the neutralized current acid waste pretreatment system, but was never used in the process. The sintered metal filter was designed to filter the supernatant stream of transuranic contaminants prior to sending the waste stream to the ion exchange columns.

Waste Type: Chemicals

Waste Description: The unit was never used to process neutralized current acid waste. However, cell and tank contamination from previous operations may have been transferred to the filter.

Code: BTTF	Classification: Accepted
Names: BTTF; Biological Treatment Test Facilities	Reclassification: Closed Out (12/10/1996)
Type: Laboratory	Start Date: 1/1/1988
Status: Inactive	End Date: 1/1/1996

Description: The unit consisted of various laboratories in the 324, 325, and 331 Buildings. The processing equipment covered under this unit included lab, bench, pilot, and full-scale treatment equipment. The RCRA Part A Permit Application for this unit was procedurally closed on December 12, 1996.

Location: The unit was located in various laboratories throughout the 324, 325 and 331 Buildings.

Related Sites/ Structures: Structures related to these treatment facilities included the 300 Area Process Sewer, similar laboratories in the other buildings, and the remaining laboratories in each building.

Process Description: Various technologies were used to treat radioactive mixed waste and hazardous waste via biological treatment research and development processes. These technologies treated radioactive mixed waste and hazardous waste constituents in soil, effluents, and groundwater through the use of microorganisms (naturally present or organisms that were environmentally enhanced) to treat various chemical constituents, such as organics, nitrates, chromium, and cyanide. Biological treatment processes were capable of treating up to a maximum of 151, 400 liters (40,000 gallons).

Waste Type: Chemicals

Waste Description: Wastes treated by the unit included listed waste, waste from non-specific sources, characteristic wastes, and state-only wastes.

Closure Info: Final: The RCRA Part A Permit Application for this unit was closed on December 12, 1996. Therefore, the WIDS site was reclassified to Closed Out.

Code: CWC	Classification: Accepted
Names: CWC; Hanford Central Waste Complex; Radioactive Mixed Waste Storage Facility; RMWSF; 2401W, 2402W, 2402WB, 2402WC, 2402WD, 2402WE, 2402WF, 2402WG, 2402WH, 2402WI, 2402WJ, 2402WK, 2402WL,	Reclassification: None

2403WA, 2403WB, 2403WC, 2403WD,
2404WA, 2404WB, 2404WC

Type: Storage **Start Date:** 1/1/1988

Status: Active **End Date:**

Description: The Central Waste Complex consists of the 2401-W Storage Building, 23 low-flash-point mixed waste storage modules, the twelve 2402-W series storage buildings, a mixed waste storage pad, the 2403-W mixed waste storage buildings, and the waste receiving and staging area. The 2401-W, 2402-W, and 2403-W Storage Buildings are pre-engineered steel structures.

Location: The unit is located west of Dayton Avenue, north of Nineteenth Street and south of the proposed Twenty Second Street.

Related Sites/ Structures: The Central Waste Complex is associated the Waste Receiving and Packaging Facility (WRAP).

Process Description: The unit provides safe storage for mixed waste until burial in disposal units at the Hanford Site, or shipment to a Transuranic Waste Disposal Site.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: The unit receives and stores designated mixed waste.

Code: GTF **Classification:** Accepted

Names: GTF; Grout Treatment Facility **Reclassification:** None

Type: Process Unit/Plant **Start Date:** 1/1/1986

Status: Inactive **End Date:** 1/1/1991

Description: The facility included the Transportable Grout Equipment from the 241-AP-102 tank. The feed line is WIDS sitecode 200-E-308-PL. The fenced area, previously known as the Grout Treatment Facility, has been transitioned to the construction contractor that will build the new Waste Treatment Facility (vitrification plant). The head end of the 216-A-29 ditch was located within this fenced area. The ditch was backfilled and stabilized.

Location: The Grout Treatment Facility was located east of the 241-AP Tank Farm, east of the 200 East Area. It is west of the Grout Treatment Facility Landfill area.

Related Sites/ Structures: The Grout Treatment Facility was associated with the Dry Materials Receiving and Handling Facility, the AP-Tank Farm, the Grout Treatment Facility Landfill (Near Surface Disposal Facility) and the 200-E-308-PL feed line.

Process Description: The technology and process operation of the GTF was demonstrated from August 1988 through July 1989 with the treatment of 3,785,400 liters (1,000,000 gallons) of radioactive, non-dangerous waste. Processing of this waste generated leachate that was a corrosive mixed waste. The leachate was stored at GTF and later transferred back to the Double Shell Tank System.

The Grout Treatment Facility was put on long term standby and the project was later cancelled. The feed transfer system was disconnected from the 241-AP-102 Tank. The High Efficiency Particulate Air filters were removed from the Liquid Collection Tank/Mixer Module (Transportable Grout Equipment) ventilation system. This reduced the level of contamination in the facility. A failed mixer pump in Tank 241-AP-102 was removed in 1995. The Grout Treatment Facility was to be used as an emergency option in the event that tank space is not available to resolve tank safety issues. During operations, the waste was stored in Tank 241-AP-

104 and pumped to the Grout Feed Tank 241-AP-102. The dry materials (from the Dry Materials Receiving and Handling Facility) were trucked to the Transportable Grout Equipment. The Transportable Grout Equipment mixed the dry blend with liquid additives and aqueous waste to form a cementitious slurry. The slurry was pumped to a below grade vault located in the Grout Treatment Facility Landfill, where it hardened. Excess water from the vaults and flush solutions from the Transportable Grout Equipment were pumped to feed Tank 241-AP-102 or other tanks in the tank farms.

Waste Type: Process Effluent

Waste Description: The liquid waste at this facility had low concentrations of radioactive and other hazardous materials. The facility had the capacity to treat 101,000 gallons (382,285 liters) per day.

Code: GTFL	Classification: Accepted
Names: GTFL; PSW Vault; 218-E-16; Grout Treatment Facility Landfill; GTF Vaults	Reclassification: None
Type: Burial Ground	Start Date: 1/1/1986
Status: Inactive	End Date: 1/1/1991

Description: The Grout Treatment Facility Landfill had been located within a fenced area, now designated for construction of the Waste Treatment Plant (vitrification plant). Access is currently controlled by the construction contractor. Five underground vaults were constructed of reinforced concrete with cover blocks to support the Grout Treatment facility. The vault floors are sloped toward a leachate collection trench. The site consists of five rectangular vaults known as 101, 102, 103, 104, and 105.

Location: The Grout Treatment Facility Landfill is located east of the 200 East Area fence. It was located inside the fence that currently surrounds the Waste Treatment Facility construction site. The landfill is east of the area formerly known as the Grout Treatment Facility. The vaults are located in the western portion of the Grout Treatment Facility Landfill.

Related Sites/ Structures: The vaults are associated with the Grout Treatment Facility.

Process Description: The vaults at the Grout Treatment Facility Landfill received liquid grout slurry from the Transportable Grout Equipment. The liquid feed contained low activity (8.4E-5 curies per liter) phosphate-sulfate waste. The grout slurry hardened in the vaults. The excess liquid was pumped back to the feed tank (241-AP-102 or another tank at the tank farms). After the excess water was removed, the void space between the grout surface and vault roof was filled with nonradioactive grout.

Waste Type: Process Effluent

Waste Description: As of 1992, the Grout Treatment Facility Landfill Vaults had a total capacity of approximately 185 acre feet (228,200 cubic meters). The waste feed had low concentrations of radionuclides and hazardous materials.

Code: HWVP	Classification: Accepted
Names: HWVP; Hanford Waste Vitrification Plant (Original Proposed Site)	Reclassification: Closed Out (11/3/1999)
Type: Process Unit/Plant	Start Date:
Status: Inactive	End Date:

Description: This WIDS site is the original facility designed to be a test treatment/support facility. The proposed Vitrification facility was never built. The 2704 HV office building, 2101 HV and the Canister Storage building were constructed. They have supported different projects.

Location: The proposed Vitrification facility was to be located west of the 200 East Area perimeter fence, between Route 4 North and Akron Ave. This facility was never constructed.

Process Description: The Canister Storage building was built to support HWVP but never used for that purpose. It has been used to store material from the 100-K Basins project.

Waste Type: Chemicals

Waste Description: The site was designed to treat 8,000 gallons (30,000 liters) per day of waste, producing 220 pounds (100 kilograms) of glass per hour.

Code: PCTTF **Classification:** Accepted

Names: PCTTF; Physical and Chemical Treatment Test Facilities **Reclassification:** Closed Out (5/13/1996)

Type: Laboratory **Start Date:** 1/1/1979

Status: Inactive **End Date:** 1/1/1995

Description: The unit consisted of the use of the 324 Building Biological Treatment Test Facilities, the 324 Building Radiochemical Hot-Cell Complex, and the 325 Building Shielded Analytical Laboratory to test treatment technologies for radioactive mixed waste and hazardous waste. The processing equipment covered under this unit included lab and bench-scale treatment equipment. The RCRA Part A Permit Application for this unit was procedurally closed on May 13, 1996.

Location: The unit was located in various laboratories in the 324 and 325 Buildings.

Related Sites/Structures: Structures related to these treatment facilities included the 300 Area Process Sewer, and laboratories in the 324 and 325 Buildings.

Process Description: Treatment processes are usually small, bench-scale operations. The processes included pH adjustment, ion exchange for selective removal of contaminants from waste solution, waste concentration by evaporation, waste dissolution such as waste retrieval from storage tanks by pH adjustment or fusion, precipitation/filtration and solvent extraction from solutions, slurries, and sludges, solids washing for separation of contaminants from sludges, catalytic destruction methods, e.g., electrolytic generation of oxidants such as silver, cerium, and other electrochemically enhanced processes for decontaminating metals and oxidizing non-metals, and grouting. Most treatment processes were small, bench-scale operations.

Waste Type: Chemicals

Waste Description: Waste treated by various processes included listed wastes, wastes from non-specific sources, characteristic wastes, and state-only wastes. Petroleum refining wastes were also included. The processes used in this unit included pH adjustment, ion exchange processes, waste concentration, precipitation/filtering, solids washing, catalytic destruction, and grouting.

Closure Info: Final: The RCRA Part A Permit Application for this unit was closed on May 13, 1996. Therefore, the WIDS site was reclassified to Closed Out.

Code: SHLWSTS **Classification:** Accepted

Names: SHLWSTS; Simulated High-Level Waste Slurry Treatment/Storage **Reclassification:** Closed Out (9/6/1995)

Type:	Process Unit/Plant	Start Date:	1/1/1987
Status:	Inactive	End Date:	1/1/1995
Description:	The site has been cleaned and turned over to the Port of Benton. This site was three roped off areas within the fenced-in 1234 Storage Yard. The site consisted of a treatment area, a storage area, and a less than 90 day accumulation area. The RCRA TSD was clean closed September 6, 1995.		
Location:	This site is located within the 1234 Storage Yard which is southwest of the intersection of Stone Street and "W" Avenue. It is south of the 300 Area, east of Stevens Dr.		
Related Sites/ Structures:	The associated structure is the 1234 Storage Yard.		
Process Description:	This site was used to store containerized simulated high-level waste slurry. The slurry was treated at this site in a grout/stabilization process. The slurry treatment program was initiated on September 13, 1988 and ended on October 28, 1988. The treatment process consisted of neutralization and mixing with grout within lined 55-gallon containers. The treatment eliminated the characteristics of ignitability, corrosivity and EP Toxicity. The grouted slurry was stored in drums at the site of treatment until tests (EP Toxicity, Acute Fish and Rat Toxicity) were completed. These tests verified that the treated waste exhibited no dangerous waste characteristics.		
Waste Type:	Chemicals		
Waste Description:	The slurry was dangerous waste containing toxic constituents and dissolved metals. The treated slurry was managed as non-radioactive solid waste.		
Waste Type:	Chemicals		
Waste Description:	The 90-day pad stored waste from various Battelle research activities including the slurry treatment wastes.		

Code:	TFS OF 218-E-4	Classification:	Accepted
Names:	TFS OF 218-E-4; Tile Field South of 218-E-4; 2607-E3 Tile Field	Reclassification	Consolidated (4/12/2004)
Type:	Drain/Tile Field	Start Date:	1/1/1944
Status:	Inactive	End Date:	1/1/1997
Description:	The tile field south of 218-E Burial Ground is comprised of vitrified clay pipe and drain tile. The laterals of the tile field are open jointed and are spaced 7.9 feet (2.4 meters) apart.		
Location:	This tile field is located southwest of the 218-E-4 Burial Ground and north of the 2607-E3 Septic Tank.		
Related Sites/ Structures:	This tile field is associated with the 2607-E3 Septic Tank and received sanitary wastewater and sewage from B-Plant Facilities.		
Process Description:	The tile field was designed to percolate wastewater into the ground without exposing it to the open air. The 2607-E3 Septic Tank was abandoned in place in 1997.		
Waste Type:	Sanitary Sewage		
Waste Description:	The 2607-E3 Septic Tank has received approximately 5.45 cubic meters (3,800 gallons) of sanitary wastewater and sewage per day from the B Plant Aggregate Area Facilities. The waste is discharged to the tile field located north of the 2706-E3 and South of the 218-E-4 Burial		

Ground.

This Site Was Consolidated With:

Code: 2607-E3

Names: 2607-E3; 2607-E3 Septic System; 2607-E3 Septic Tank and Drainfield; TFS of 218-E-4; Tile Field South of 218-E-4

Code: TRUSAF

Classification: Accepted

Names: TRUSAF; 224-T TRUSAF; Transuranic Assay Facility

Reclassification: Closed Out (11/12/2008)

Type: Storage

Start Date: 1/1/1985

Status: Inactive

End Date: 1/1/1997

Description: The TRUSAF TSD was located inside the 224-T building. The building is a RCRA compliant storage unit occupying 2/3 of the 224-T building and adjacent outdoor areas. One third of the building (224-T Canyon) was sealed off in 1975. The storage capacity is 2,000 (55-gallon) drums (110,000 gallons). Access to the building is restricted with a locked, chain link fence. All TRUSAF waste was removed from the 224-T building in August 1997. The TSD was Closed on November 12, 2008.

Location: This is a three story concrete building located southeast of 221-T and south of 222-T.

Related Sites/ Structures: The TRUSAF activities are associated with waste management operations.

Process Description: The building was originally constructed in 1943 as part of the T Plant bismuth-phosphate fuel processing complex. From 1944 to 1956 it functioned as the Plutonium Concentration Facility. Six radiologically contaminated process cells are located in the eastern 1/3 of the building. The cells were sealed off from the rest of the building in 1975. The amount of radiological or regulated material remaining within the process cells is unknown. This section of the building is documented in WIDS Sitecode 224-T. The TRUSAF process included the exterior inspection of waste drums, neutron assay of waste containers to determine the isotope content and an X-ray examination of the waste containers to confirm the absence of prohibited contents (e.g. free liquids). After examination the containers were stored on the second and third floors, in rows (following a pattern marked on the floor) or in storage modules. All TRUSAF waste was removed from the 224-T building in August 1997. The building is on standby. No operations are currently taking place in 224-T except for routine building surveillance.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: The TRUSAF facility operation consisted of a nondestructive analysis of TRU waste. The hazardous waste that may be allowed into this facility could be any of the listed or characteristic wastes as defined by RCRA and Washington Administrative Code 173-303. The waste was generated by DOE processing facilities and will eventually be shipped to the WIPP in New Mexico for disposal. Prior to placing the building on standby, all of the waste was removed from 224-T.

Code: TTF

Classification: Accepted

Names: TTF; Thermal Treatment Test Facilities

Reclassification: Closed Out (5/13/1996)

Type: Laboratory

Start Date: 1/1/1978

Status: Inactive

End Date: 1/1/1996

Description: The process and equipment consisted of various laboratories inside the 324 and 325 Buildings and the in-situ vitrification (ISV) unit, which was a transportable treatment unit. The processing equipment covered under this unit included bench, engineering, pilot, and full-scale treatment equipment. The RCRA Part A Permit Application was administratively closed on May 13, 1996.

Location: The unit was located inside various labs throughout the 324 and 325 Buildings. The in-situ unit was able to be transported across the Hanford Site.

Related Sites/ Structures: Structures related to these treatment facilities included the 300 Area Process Sewer, engineering development laboratory (EDL), EDL high bay and hot cell complex of the 324 Building. Additionally, the in-situ treatment unit had ancillary structures providing power, filtration and control. The 116-B-6A Crib was used for testing as were other laboratories located in the 324, 325 and 331 Buildings.

Process Description: These units treated mixed and hazardous waste with in-situ vitrification or waste vitrification treatment processes. The equipment and processes were used to treat the waste included bench, pilot, engineering, and full-scale treatment equipment.

ISV was a thermal treatment process that converted contaminated soils and sludges into a glass and crystalline product. An electrical current was passed among an array of four electrodes imbedded in the contaminated soil or sludge, melting and glassifying it. The process continued outward and downward until the appropriate vitrification depth was obtained. Radioactive mixed waste and dangerous waste constituents were stabilized in the glass and crystalline product. Organic contaminants were destroyed by pyrolysis, and the pyrolysis products oxidized as they migrated to the surface. PNL operated four treatability testing units (bench, engineering, pilot, and large-scale). The engineering and bench-scale units were located in the 324 Building in the 300 Area. The pilot and large-scale units were transportable within the Hanford Site. The design capacity of the units varied from 18.9 liters (5 gallons) per day (bench-scale) to 64345 liters (17,000 gallons) per day (large-scale).

Waste vitrification prototype equipment was located in the 324 Building. Treatability studies were performed using simulated and actual radioactive mixed waste samples. Radioactive mixed waste was mixed with glass-forming materials and vitrified into a highly durable glass for disposal. The design capacity ranged from 5.7 liters (1.5 gallons) per day (bench-scale) to 113.6 liters (30 gallons) per day (pilot-scale).

In some treatability studies with ISV, vitrified soil was left in place for additional study before either being removed or designated as nonhazardous.

Other thermal treatment processes covered by this permit included plasma arc pyrolysis, in situ heating of soils and sludges for removal of organics, metal melting for volume reduction and immobilization of contaminated metals, gamma induced oxidation of organic chemicals, thermal treatment for the drying and decomposition of liquid slurries, in can melting of soil wastes and liquid slurries, and microwave heating to dry and immobilize liquid and solid wastes.

Waste Type: Chemicals

Waste Description: Wastes treated by these processes included listed wastes, wastes from non-specific sources, characteristic wastes, and state-only wastes. In-situ vitrification is a thermal process that converts contaminated soil and sludges into a glass and crystalline product. Non-volatilized contaminants are immobilized in the glass and crystalline product. Volatilized contaminants are recovered in a filtration system. Other vitrification processes explored in these units included plasma arc pyrolysis, melters, and gamma-induced oxidation.

Closure Info: Final: This RCRA process was Administratively Closed Out with appropriate Part A forms. Therefore, the WIDS site was reclassified to Closed Out.

Code: UPR-100-N-15	Classification: Accepted
Names: UPR-100-N-15; 108-N Neutralization Sump Spill; Acid Spill at 108-N; UN-100-N-15; UN-116-N-15	Reclassification: Rejected (9/11/2000)
Type: Unplanned Release	Start Date: 1/1/1981
Status: Inactive	End Date: 1/1/1981

Description: The release site is concrete structures and a graveled field. There is no evidence of the spill at the site.

Location: The release occurred at the 108-N Sump. The volume of contaminated soil was less than 1.4 cubic meters (50 cubic feet).

Release Description: On March 20, 1981, during the 8-4 shift, while sulfuric acid was being transferred from the 108-N storage tanks to the 163-N day tanks, a leak developed in a connection in the discharge line from the acid transfer pumps. The operator noticed the leak spraying across the interior of the 108-N building, but knowing the piping of the 108-N building to be prone to leaks over the past several years, he continued to fill the 163-N day tanks (10-15 minutes) until the desired level was reached in accordance with procedure. After the tanks were filled, the operator shut the system down and notified his supervisor of the problems. The pressure in the leaking line during the transfer operation resulted in spraying a large portion of the interior of the 108-N building with highly corrosive sulfuric acid. The operator wore adequate protective clothing and received no injuries. The building interior sustained considerable acid damage. After supervision was notified, cleanup of the 108-N building began. The interior of the building was hosed down with water and drained to the 108-N neutralizing sump. When this sump became filled to capacity, it became necessary to transfer the neutralized mixture to another neutralizing pit. During this transfer a "water leak" was observed coming from the ground outside of the 108-N building. Following pH tests, the leak was traced to the discharge line from the 108-N neutralizing sump. During the transfer of the liquid, the outside of the 108-N building became flooded and was roped off. The Environmental Control Subsection was notified of the spill; and upon their recommendation, the surface leakage was neutralized with soda ash. No further actions were deemed necessary at that time. On March 23, 1981, during the 8-4 shift, Rockwell cement finishers reported to an N Plant Maintenance Analyst requesting permission to enter the 108-N building to clean the area around the base of the two acid transfer pumps to prepare the base for a new surfacing. Since no "hands on maintenance of any equipment" was required, the N Plant Maintenance Analyst saw no need for the preparation of a formal work authorization form. The Maintenance Analyst left the cement finishers at the job site and returned to his office. The cement finishers dressed in protective clothing and went about their assigned task. While scraping the surface of loose debris, the Rockwell cement finishers struck and broke off a small drain pipe coming off the suction header of the acid transfer pumps. Residual acid from the previously isolated line sprayed out on the interior of the 108-N building. Both cement finishers, dressed in appropriate protective clothing, were uninjured. Subsequent cleanup operations similar to those performed on 3/20/1981, again forced the usage of the transfer line from the 108-N neutralizing sump. The Environmental Control Subsection was notified prior to the transfer. They advised similar precautions be taken as those on 3/20/1981. Residual liquid on the ground outside of the 108-N was neutralized with soda ash.

Related Sites/ Structures: This release is associated with the 108-N Chemical Unloading Facility.

Waste Type: Chemicals

Waste Description: The release consisted of sulfuric acid.

Code: UPR-100-N-33 **Classification:** Accepted

Names: UPR-100-N-33; 108-N Acid Transfer Spill; UN-100-N-33; UN-116-N-33 **Reclassification:** Rejected (9/11/2000)

Type: Unplanned Release **Start Date:** 11/6/1981

Status: Inactive **End Date:** 11/6/1981

Description: The waste site is an acid release that occurred in a gravel area at the 108-N Chemical Unloading Facility (CUF). There is no visual evidence of the spill at the site.

Location: The release occurred near the acid storage tanks at the 108-N Facility.

Release Description: Approximately 3,800 liters (1,000 gallons) of 97% sulfuric acid was spilled during an acid transfer from a rail car to the sulfuric acid storage tank at 108-N. The release occurred on November 6, 1981 at about 4:30 pm, during shift change.

Related Sites/Structures: This release is related to the 108-N CUF.

Waste Type: Chemicals

Waste Description: The spill consisted of a solution containing 97% sulfuric acid.

Code: UPR-100-N-34 **Classification:** Accepted

Names: UPR-100-N-34; 108-N Tank Transfer; Sulfuric Acid Line Break; UN-100-N-34 **Reclassification:** Rejected (9/11/2000)

Type: Unplanned Release **Start Date:** 1/1/1980

Status: Inactive **End Date:** 1/1/1980

Description: The release occurred in a concrete trench in a graveled lot. There is no evidence of the spill at the site.

Location: The release occurred at the southwest corner of the 120-N-5, 108-N/163-N Transfer Line And Neutralization Pit.

Release Description: Washington Public Power Supply System (WPPSS) supervision called the 105-N Control Room and reported a large cloud of steam in the vicinity of the WPPSS trestle. An investigation revealed liquid spurting several feet into the air from a sulfuric acid and sodium hydroxide line encasement at the encasement sump. The weekly sulfuric acid transfer from 108-N to 163-N was in process. It was subsequently determined that the sulfuric acid had been transferred from the storage tank at 108-N, and none had been received at the 163-N Storage Tank. Approximately 12,870 liters (3,400 gallons) of 94% sulfuric acid was released to the ground. Contamination was limited to the region near the sulfuric acid transfer line in the vicinity of the sump. The release occurred on May 12, 1980. While the CMS reports a spill of 3,800 liters (1,000 gallons), historical records [e.g., Stenner et al. 1988] lists a release of 12,870 liters (3,400 gallons).

Waste Type: Chemicals

Waste Description: The release was a solution containing 94% sulfuric acid.

Code: UPR-100-N-38 **Classification:** Accepted

Names: UPR-100-N-38; 100-N Spring 1983 Caustic; 116-N-2 Facility Liquid Unplanned Release; Truck Spill 116-N-2
Reclassification Rejected (9/11/2000)

Type: Unplanned Release
Start Date: 1/1/1983

Status: Inactive
End Date: 1/1/1983

Description: The site is level and graveled. A pipe is present that carried sodium hydroxide from the tankers to the 1310-N Facility (116-N-2). The site is located in a radiation zone, but the sodium hydroxide should not have been radioactively contaminated. The 116-N-2 Facility complex consists of piping, pumps, a transfer tank (commonly referred to as the silo) and a large, spherical storage tank (commonly referred to as the golf ball). The site was used as a collection tank for N Reactor primary piping decontamination wastes. The 3.4E+06-liter (9.0E+05-gallon) spherical tank is partially buried in the ground. A compacted soil radiation barrier, 7.6 meters (25 feet) high, borders the tank on three sides.

Location: The spill occurred in the 100-N Area, west northwest of 1310-N.

Release Description: In Spring 1983, a tanker truck was offloading caustic sodium hydroxide to the silo (transfer tank) at 1310-N when a fitting came loose, spilling 380 liters (100 gallons) of sodium hydroxide to the soil.

Related Sites/Structures: The 116-N-2 (1310-N Chemical Waste Treatment and Storage Facility) is associated with the site.

Process Description: The sodium hydroxide was used to neutralize the radioactively contaminated and hazardous decontamination solution pumped from the N Reactor to the 116-N-2 (1310-N Facility).

Waste Type: Chemicals

Waste Description: Three hundred eighty liters, (100 gallons) of sodium hydroxide was spilled to the ground during offloading operations in a radiation zone.

Code: UPR-100-N-40
Classification: Not Accepted

Names: UPR-100-N-40; 6/14/86 163-N Cation/Anion Regeneration Waste Spill; Regeneration Waste Transport System Liquid UPR 1 (06/14/86 Cleaned Up); UN-116-N-27
Reclassification None

Type: Unplanned Release
Start Date: 1/1/1986

Status: Inactive
End Date:

Description: The surface of the area is graveled.

Location: The exact location of the leak is unknown, however, it occurred in the section of line that goes southeast from the southeast corner of 183-N.

Release Description: On June 14, 1986, a leak was detected in the waste transport pipe while wastes from the anion and cation regeneration process were being routed to 120-N-2 Surface Impoundment. Once the leak was discovered, regeneration processes were shut down. A sample was collected at the point of leak and found to have a pH of 1.4. It was estimated that 25,000 liters (6,500 gallons) of acidic regeneration waste had leaked to the ground and formed a pond in an area south and east of the 163-N/183-N Buildings. Caustic regeneration waste was pumped through the line and allowed to leak into the acidic pond to neutralize the spilled material. Several hours elapsed until the pH of the spilled material reached 6.9.

Waste Type: Process Effluent

Waste Description: The 120-N-1 and 120-N-2 disposal sites received waste from the 163N Plant, the same waste that was involved in these unplanned releases. The liquid released was regeneration waste from ion exchange columns in the 163-N Facility, consisting of sulfuric acid and sodium hydroxide.

Code: UPR-100-N-41 **Classification:** Not Accepted

Names: UPR-100-N-41; Waste Spill; 163-N Regeneration; Regeneration Waste Transport System Liquid UPR 2 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1986

Status: Inactive **End Date:**

Description: The spill occurred at the 163-N Regeneration Waste Sump near the northwest corner of the 163-N Building and formed a small pond in this area.

Location: The site is a graveled area northeast of the 163-N Building.

Release Description: A spill of acidic wastewater (pH 1.1) from the 163-N Demineralized Water Treatment Plant occurred on June 30, 1986. The spill happened when a temporary 15-centimeter (6-inch) hose became dislodged for approximately 4 minutes during a discharge cycle, spilling approximately 3,800 liters (1000 gallons) of the liquid. The corrective action was to add 82 kilograms (180 pounds) of soda ash to the spill to neutralize the acid. Subsequent pH of the spill was 10.1 standard units. No cleanup action is mentioned in the occurrence report.

Waste Type: Water

Waste Description: The liquid released was regeneration waste consisting of sulfuric acid from ion exchange columns in the 163-H Facility. Soda ash was added to the spill to help neutralize the liquid.

Code: UPR-200-E-4 **Classification:** Accepted

Names: UPR-200-E-4; 241-B-151 Diversion Box Contamination Spread; UN-200-E-4 **Reclassification:** Consolidated (6/13/2002)

Type: Unplanned Release **Start Date:** 1/1/1951

Status: Inactive **End Date:** 1/1/1952

Description: The site is not separately marked or posted.

Location: The release occurred in an area surrounding the 241-B-151 Diversion Box, inside the 241-B Tank Farm fence.

Release Description: The area around the 241-B-151 Diversion Box was contaminated as a result of work activities in the diversion box in the fall of 1951 and again in the summer of 1952.

Related Sites/ Structures: The release is associated with the 241-B-151 Diversion Box.

Waste Type: Process Effluent

Waste Description: The release involved approximately 10 curies of fission products from the 241-B-151 Diversion Box.

This Site Was Consolidated With:

This Site Was Consolidated With:**Code:** 200-E-120**Names:** 200-E-120; Contaminated Soil at 241-B Tank Farm; Contamination Migration Beyond the 241-B fence**Code:** UPR-200-E-13**Classification:** Accepted**Names:** UPR-200-E-13; UPR-200-E-15; Overflow from 216-A-4; UN-200-E-13**Reclassification:** Consolidated (1/25/2000)**Type:** Unplanned Release**Start Date:** 1/1/1958**Status:** Inactive**End Date:****Description:** WIDS site UPR-200-E-13 has been reclassified based on documentation that verified it was a DUPLICATE of UPR-200-E-15. Future updates and closeout information will only be added to UPR-200-E-15. This site will no longer be updated. The unplanned release contaminated both the soil and blacktop areas between the 291-A Turbine House and the 216-A-4 Crib. The release site was not separately marked or posted.**Location:** The release occurred south of PUREX, between the 216-A-4 Crib and the 291-A Turbine House.**Release Description:** In December 1958, the 216-A-4 Crib became plugged during the jetting of the 216-A-2 Catch Tank which resulted in contaminated material backing into the 291-A Turbine House through the floor drains. The floor was contaminated to 20 rads/hour at 25.4 centimeters (10 inches). In addition, an area of ground and blacktop outside the turbine house was contaminated up to 8 rads/hour.**Related Sites/Structures:** The release was associated with 200-E-102, 200-E-103, 216-A-4, 216-A-2 and the 291-A Turbine House.**Waste Type:** Process Effluent**Waste Description:** The 216-A-4 crib plugged during the jetting of the 216-A-2 catch tank. Contaminated liquid backed up into the 291-A Turbine House floor drains. The floor of the Turbine House was contaminated to 20 rads/hour at 25.4 centimeters (10 inches). The liquid effected an area of ground and blacktop outside the turbine house that was contaminated with beta/gamma levels up to 8 rads/hour.**This Site Was Consolidated With:****Code:** 200-E-103**Names:** 200-E-103; PUREX Stabilized Area; Radiologically Controlled Area - South Side of PUREX**Code:** UPR-200-E-14**Classification:** Accepted**Names:** UPR-200-E-14; 216-B-3 Pond Dike Break; UN-200-E-14**Reclassification:** Consolidated (1/19/2000)**Type:** Unplanned Release**Start Date:** 1/1/1958**Status:** Inactive**End Date:** 1/1/1958**Description:** The site is an unplanned release that occurred as a result of a dike break in 216-B-3 Pond. In 1983, the 216-B-3A Pond lobe was built over the top of this release site. There is no visible evidence of this release. It is not physically marked or posted. There is a large percolation trench in the center of the 216-B-3A pond that is posted as a Soil Contamination Area. However, the percolation trench was dug in 1984 and this Unplanned Release occurred in 1958. This site has been consolidated with 216-B-3B RAD.

HW-60807 states that the soil was contaminated at surface and that the soil was removed to a trench along the south boundary of 216-A-4.

**Related Sites/
Structures:** The site is associated with 200-E-102, 200-E-103, the 216-A-4 crib and the 291-A Turbine House.

Waste Type: Process Effluent

**Waste
Description:** The 216-A-4 crib plugged during the jetting of contaminated liquid from the 216-A-2 Catch Tank. When the 216-A-4 crib plugged, the floor drains in the 291-A Turbine House backed up, contaminating the floor with dose rates up to 20 rads/hour at 25.4 centimeters (10 inches). The liquid then flowed out of the turbine house and contaminated surrounding blacktop and soil. Beta/gamma readings on the blacktop and soil read up to 8 rad/hour were measured immediately following the incident.

This Site Was Consolidated With:

Code: 200-E-103

Names: 200-E-103; PUREX Stabilized Area; Radiologically Controlled Area - South Side of PUREX

Code: UPR-200-E-16

Classification: Accepted

Names: UPR-200-E-16; 241-C Overground Transfer Line Leak; UN-200-E-16

Reclassification: Consolidated (6/13/2002)

Type: Unplanned Release

Start Date: 1/1/1959

Status: Inactive

End Date:

Description: Neither the spill or the associated pipe, buried at the conclusion of the transfer, are marked or posted within the Tank Farm.

Location: The release occurred northeast of the 105-C Tank Pit, inside the 241-C Tank Farm.

**Release
Description:** A leak in the overground coating waste transfer line at 241-C tank farm resulted in contamination of the ground to 1.5 rad per hour at a distance of 4.5 meters (15 feet). The line was replaced with a maximum exposure of 4 rad per hour. The release consisted about 50 gallons. It occurred during the transfer of PUREX coating removal waste from tank 241-C-105 to tank 241-C-108. The leak occurred in the vicinity of the pump pit which is located on the north side (12 o'clock position) of the tank.

**Process
Description:** The 241-C-105 to 241-C-108 overground transfer line broke and contaminated the soil northeast of the 241-C-105 tank pit.

Waste Type: Process Effluent

**Waste
Description:** The waste was PUREX coating waste that was released to the ground from a line break in the 241-C-105 to 241-C-108 overground transfer line.

This Site Was Consolidated With:

Code: 200-E-133

Names: 200-E-133; Contaminated Soil at 241-C Tank Farm; Contamination Migration Beyond the fence at C Farm

Code: UPR-200-E-22

Classification: Accepted

Names: UPR-200-E-22; 291-A-1 Stack Fallout Area; UN-200-E-22

Reclassification: Consolidated (7/19/2004)

Type: Unplanned Release

Start Date: 1/1/1959

Status: Inactive**End Date:**

Description: The ground around the PUREX 291-A Stack was contaminated in 1959. The hand drawn sketch included in HW-60807 created an oval shaped extending east from the PUREX stack to near the 216-A-6 Sample Pit structure and south to near the 216-A-21 crib. The release is no longer separately marked or posted.

Location: The release effected a wide area around the PUREX facility.

Release Description: Document HW-60807, written in 1959, states that an area was posted due to mixed fission product fallout from the 291-A Stack. The contamination was not from a single release, but from contamination build up over time. The heaviest concentrations were northwest and southeast of the stack within about 91 meters (300 feet). The area was chained and marked with Radiation Zone signs in 1959. Its boundaries included 202-A on the north and listed other Hanford Plant coordinates. Based on Hanford Plant coordinates in HW-60807, the approximate boundaries of the contaminated area from the stack are 253 meters (830 feet) to the east, 55 meters (180 feet) to the north, 113 meters (370 feet) to the west, and 119 meters (390 feet) to the south. The hand drawn sketch included in this document created an oval shaped extending east from the PUREX stack to near the 216-A-6 Sample Pit structure and south to near the 216-A-21 crib.

Waste Type: Soil

Waste Description: The soil around the 291-A stack was contaminated with fallout of mixed fission products and ruthenium.

This Site Was Consolidated With:

Code: 200-E-103

Names: 200-E-103; PUREX Stabilized Area; Radiologically Controlled Area - South Side of PUREX

Code: UPR-200-E-23

Classification: Accepted

Names: UPR-200-E-23; UPR-200-W-158; Burial Box Collapse at 218-E-10

Reclassification: Consolidated (5/6/2004)

Type: Unplanned Release

Start Date: 1/1/1960

Status: Inactive

End Date: 1/1/1960

Description: The release site is not separately marked or posted from the burial ground radiological postings.

Location: The release occurred at the 218-E-10 Burial ground, located in the northwest portion of 200 East Area. The contamination spread east and southeast up to 4.8 kilometers (3 miles) beyond the 200 East Area fence.

Release Description: On Friday, June 10, 1960, a burial box containing two PUREX tube bundles (F-11, H-4) collapsed during a backfill in 200 East Area. The maximum dose rate on the burial box was 5 rad per hour at 30 meters (100 feet). The box was covered with dirt, but not completely backfilled. Over the weekend, contamination from the broken box became airborne and caused a contamination spread. On Monday, June 13, the burial ground was found generally contaminated with levels ranging from 10 to 60 millirem per hour. Further investigations determined the wind had carried contamination in a southeasterly direction as far as Mile Post 7. (see Occurrence Report 60-1)

Related Sites/Structures: The release is associated with the burial of contaminated PUREX equipment. This release is also associated with UPR-200-E-24.

Process Description: Large boxes of contaminated equipment were routinely transported to solid waste burial grounds on railroad flat cars. The 200 East Area Waste Burial Ground logbook states that two

PUREX concentrator tube bundles, contained in a wooden burial box measuring 6.1 by 3.3 meters (20 by 11 feet), were buried in Trench #1 of 200 East Burial Ground 10, at coordinates N45058/W54765 (Hanford Plant coordinates). The maximum dose rate recorded on the box during burial was 5 rad per hour at a distance of 30 meters (100 feet). The box was covered with dirt, but not completely backfilled on June 10, 1960.

Waste Type: Soil

Waste Description: The contamination originated from PUREX process tube bundles (from F-11 and H-4). Radiological readings ranged from a maximum of 60 millirad/hour beta/gamma at the burial ground to approximately 1,000 counts/minute outside the 200 East Area fence.

This Site Was Consolidated With:

Code: 218-E-10

Names: 218-E-10; Equipment Burial Ground #10; 200 East Industrial Waste No. 10

Code: UPR-200-E-24

Classification: Accepted

Names: UPR-200-E-24; Contamination Plume from the 218-E-10 Burial Ground; UN-200-E-24

Reclassification: Consolidated (5/6/2004)

Type: Unplanned Release

Start Date: 1/1/1960

Status: Inactive

End Date:

Description: The contaminated area is not currently marked or posted.

Location: Contamination spread from the 200 East Burial Ground (218-E-10) to as far as 3 miles (4.83 kilometers) beyond the 200 East Area perimeter fence.

Release Description: On Friday, June 10, 1960, a burial box containing two PUREX process steam tube bundles was placed in the 218-E-10 Burial Ground. It was covered with dirt, but not completely backfilled. Over the weekend, the box collapsed, causing a contamination spread. On Monday, June 13th, the burial ground was found to be contaminated with radiological levels ranging from 10 to 60 millirads/hour. It was also determined that wind had carried the contamination southeast across the 200 East Area to mile post 7 on Highway 4-S. Contamination levels beyond the 200 East area fence were approximately 1000 counts per minute. Two private vehicles were decontaminated that had been located in the PUREX parking lot. The incident was investigated and reported as Radiation Exposure Occurrence Type C, CPD 60-1. The date of the incident is probably June 10, 1960 instead of the June 17, 1960 as reported in PNL-6456. However, it is likely that the distant contamination (identified at mile marker 7 southeast of 200 East Area) was not documented until June 17th.

Related Sites/Structures: This site is associated with UPR-200-E-23.

Process Description: Large boxes of contaminated equipment were routinely transported to solid waste burial grounds on railroad flat cars.

Waste Type: Soil

Waste Description: The release was caused from a burial box containing PUREX tube bundles. The average radiation level on the soil surfaces inside the burial ground fence was 30 millirads/hour at 10.16 centimeters (4 inches). The contamination diminished as it traveled from the burial site. Less than one particle of contamination per 9 square meters (100 square feet) was found outside the 200 East Area perimeter fence.

This Site Was Consolidated With:

Release Description: On September 30, 1960, a recently installed jumper was being tested. A gross leak was observed in the 241-A-151 Diversion Box causing an operator to stop test. However, the E-1 process tank emptied causing a cloud of steam to blow out of the faulty jumper connection, contaminating the area around the diversion box and beyond the PUREX fence. Beta/gamma readings ranged from 1 to 3 rad per hour near the diversion box. Just outside the PUREX exclusion fence, the general contamination decreased to 3,000 counts per minute. Contamination concentrations of approximately 5 particles per 9.3 square meters (100 square feet) were found as far away as the BC Crib Area. Several employees and government vehicles at the job site were contaminated.

Related Sites/ Structures: The release is associated with the 241-A-151 Diversion Box and 200-E-103.

Waste Type: Steam Condensate

Waste Description: A cloud of contaminated steam escaped from a faulty connection inside the diversion box. Beta/gamma contamination (specks) with readings ranging from 1 to 3 millirads per hour were found near the diversion box. The general contamination levels on surfaces further away averaged 3,000 counts per minute. The waste line being tested was used for routing PUREX strontium interim storage to 244-CR vault.

This Site Was Consolidated With:

Code: 200-E-103

Names: 200-E-103; PUREX Stabilized Area; Radiologically Controlled Area - South Side of PUREX

Code: UPR-200-E-27

Classification: Accepted

Names: UPR-200-E-27; 244-CR Contamination Spread; UN-200-E-27

Reclassification: Consolidated (6/13/2002)

Type: Unplanned Release

Start Date: 1/1/1960

Status: Inactive

End Date: 1/1/1960

Description: The release site, within the Tank Farm fenceline, is not specifically marked or posted.

Location: The release originated from the 244-CR Vault and spread eastward, contaminating the inside of the tank farm and also several hundred feet beyond the tank farm perimeter fence.

Release Description: On November 1, 1960, during work in the 244-CR Vault, winds spread contaminated particles eastward. Contamination levels around the vault, inside the fence, ranged between 50 and 100 millirads/hour. Particles reading as high as 40,000 counts per minute were found outside the fence. The original incident report says work was being done in a diversion box when the release occurred. The 241-CR-151 Diversion Box is adjacent to the 244-CR Vault.

Waste Type: Process Effluent

Waste Description: Beta/gamma contamination (specks) with readings of 50 to 100 millirads/hour was found near the vault. Readings of particles on surfaces outside the tank farm fence area were up to 40,000 counts/minute.

This Site Was Consolidated With:

Code: 200-E-133

Names: 200-E-133; Contaminated Soil at 241-C Tank Farm; Contamination Migration Beyond the fence at C Farm

Code: UPR-200-E-30

Classification: Accepted

Names: UPR-200-E-30; Contamination Within 218-E-10; **Reclassification** Consolidated (6/28/2007)
UN-200-E-30

Type: Unplanned Release **Start Date:** 1/1/1961

Status: Inactive **End Date:** 1/1/1961

Description: The burial ground has been surface stabilized. The burial ground is posted as Underground Radioactive Contamination.

Location: The release occurred within Trench 1 of the 218-E-10 burial ground. It is located in the northwest corner of 200-East Area, south of 12th Street.

Release Description: HW-69443 (document dated 5-22-61) states that on April 20, 1961 a wooden burial box, containing 83 highly contaminated process jumpers, collapsed as it was being covered over with soil in the burial trench. Contamination (maximum 500 millirad/hour) was spread over a 400,000 square foot area within the burial ground. The majority of the contamination was confined to the burial ground.

Waste Type: Process Effluent

Waste Description: The release consisted of dried contamination from process jumper with readings up to 500 millirads/hour that were inside a wooden burial box.

This Site Was Consolidated With:

Code: 218-E-10

Names: 218-E-10; Equipment Burial Ground #10; 200 East Industrial Waste No. 10

Code: UPR-200-E-31 **Classification:** Accepted

Names: UPR-200-E-31; 241-A-151 Release; UN-200-E-31 **Reclassification** Consolidated (12/7/2004)

Type: Unplanned Release **Start Date:** 1/1/1961

Status: Inactive **End Date:**

Description: The area south of PUREX, inside the facility fence had been posted as a Contamination Area. In 1999, the large posted Contamination Area, located on the south side of PUREX, was covered with clean backfill and changed to an Underground Radioactive Material Area (200-E-103). The release is not separately marked or posted, but is documented on a sign hung on the PUREX south perimeter fence. It is possible this release contributed to the contamination in the area.

Location: In 1961, the contamination spread from the 241-A-151 Diversion box (located on the south side of 202-A), affected the PUREX exclusion area, areas northeast of PUREX and east of the 200 East Area fence.

Release Description: Several attempts were made to enter the 241-A-151 Diversion Box, (located on the south side of PUREX [202-A]) on October 7, 1961 during the 12 to 8 and the 8 to 4 shifts. Each attempt detected steam coming out of the diversion box when the cover block was being lifted. On those two shifts, the cover block was replaced and the job was canceled. On the 4 to 12 shift no steam was detected. The cover blocks were removed and the work inside the diversion box proceeded. After the work was completed, a radiological survey found 80,000 counts per minute on the blacktop on the north side of 202-A (the opposite side of the building from the diversion box) that triggered a radiological investigation. Smearable contamination of 80 millirem per hour was found on the PUREX roof. Contamination levels in the vicinity of the PUREX facility ranged from 40,000 to 100,000 counts per minute. Further surveys identified more contamination north of PUREX at 275-EA and east of Canton Avenue. Surveys of the

Hanford environment continued through October 20, 1961. Approximately 20 vehicles were found to be contaminated up to 40,000 counts per minute. Some low level contamination (2 particles per 100 square feet) was found as far away as the west bank of the Columbia River.

Related Sites/ Structures: The release is associated with the 241-A-151 Diversion Box and 200-E-103.

Process Description: The 241-A-151 Diversion Box provided routing for high level waste going from 202-A to the 200 East Area Tank Farms. Several leaks in the jumpers caused gross contamination inside the diversion box.

Waste Type: Steam Condensate

Waste Description: Steam rising from the 241-A-151 Diversion Box resulted in a spread of beta/gamma contamination (specks) with readings ranging from 40,000 to 100,000 counts per minute in the vicinity of PUREX. Readings on surfaces outside of the limited area fence decreased to 1,000 counts per minute. The diversion box provided routing for high level waste from the PUREX F and G cells to the tank farms.

This Site Was Consolidated With:

Code: 200-E-103

Names: 200-E-103; PUREX Stabilized Area; Radiologically Controlled Area - South Side of PUREX

Code: UPR-200-E-32	Classification: Accepted
Names: UPR-200-E-32; Coil Leak from 221-B; UN-200-E-32	Reclassification: Consolidated (1/19/2000)
Type: Unplanned Release	Start Date: 1/1/1963
Status: Inactive	End Date: 1/1/1963

Description: The site is an unplanned release that affected the 207-B Basin and the 216-B-2-1 Ditch. The unplanned release is not visually marked or posted. The 207-B Basin is labeled and posted as a Contamination Area. The 216-B-2-1 ditch is marked with AC-540 markers and is included within a larger Underground Radioactive Material area. This site has been consolidated with the 207-B Retention Basin.

Location: The release occurred at B-Plant and affected the 207-B Retention Basin and the 216-B-2-1 Ditch. The basin and the ditch are located inside the 200 East Area, east of Baltimore Ave. and south of 241-B Tank Farm.

Release Description: On November 7, 1963, a coil failed in the 221-B Building (6-1 Rare Earth Storage Tank) and caused a liquid release, contaminating the 207-B Retention Basin and the head end of the 216-B-2-1 Ditch. Document HW-79768 states the general dose rates ranged from 500 millirem per hour to 2 Rad per hour. Tumbleweeds driven into the contaminated ditch by high winds were found to be reading 50 rads per hour. The tumbleweeds were removed and transported to the burial grounds.

Related Sites/ Structures: The release was related to B-Plant (221-B) 6-1 Tank inside 221-B. The pipeline from B Plant to the 207-B Basin is sitecode 200-E-112-PL.

Waste Type: Process Effluent

Waste Description: The B Plant 6-1 Rare Earth Storage Tank coil failed and cause a release to the retention basin and 216-B-1 ditch. A sample of the effluent released to the 207-B Retention Basin was analyzed in 1963. It was primarily Cerium-144 (30 curies) and 0.05 curies of strontium-90. Dose rates up to 500 millirad per hour were documented. Tumbleweeds that had blown into the ditch read up to 50 rad/hr.

This Site Was Consolidated With:**Code:** 207-B**Names:** 207-B; 207-B Retention Basin; B Plant Retention Basin

Code: UPR-200-E-34	Classification: Accepted
Names: UPR-200-E-34; Liquid Release to B-Pond and Gable Pond; UN-200-E-34	Reclassification: Consolidated (1/19/2000)
Type: Unplanned Release	Start Date: 1/1/1964
Status: Inactive	End Date: 1/1/1964

Description: This was a liquid unplanned release to a pond. There is no visual evidence of this release. The release effected the 216-B-3 Pond, 216-A-25 Pond and 216-A-29 Ditch. The 216-B-3 Pond, 216-A-25 Pond, and 216-A-29 Ditch have all been surface stabilized and are posted as Underground Radioactive Material Areas. This site has been consolidated with the 216-B-3 Pond.

Location: The unplanned release was a liquid release from PUREX that terminated in 216-B-3 Pond located east of 200 East area, outside the east perimeter fence and to 216-A-25 (Gable) Pond, located north of 200 East Area via ditches and an underground pipeline.

Release Description: On June 12, 1964, a coil leak in the F-15 Plutonium Uranium Extraction (PUREX) Tank contaminated 216-B-3 (B Pond) and 216-A-25 (Gable Mountain Pond). Approximately one fourth of the release was discharged to 216-B-3 Pond and the remaining three fourths of the contamination was released to 216-A-25 (Gable) Pond.

Related Sites/ Structures: The release is associated with the PUREX facility, 216-A-25, 216-A-29 and 216-B-3.

Waste Type: Process Effluent

Waste Description: The ponds and ditch were contaminated with approximately 10,000 curies of mixed fission products from a coil leak in the PUREX F-15 tank. Water and biota samples found niobium-95, zirconium, yttrium, strontium-89, cerium-144, praseodymium-144, strontium-90 and cesium-137.

This Site Was Consolidated With:**Code:** 216-B-3**Names:** 216-B-3; 216-B-3 Main Pond; 216-B-3 Swamp; B Plant Swamp; B Pond; B Swamp; B-3 Pond; West Side Overflow Pond

Code: UPR-200-E-36	Classification: Accepted
Names: UPR-200-E-36; Contamination Spread North of Semi-Works; Road Contamination North of Semiworks; UN-200-E-36	Reclassification: Consolidated (11/22/2004)
Type: Unplanned Release	Start Date: 1/1/1967
Status: Inactive	End Date:

Description: The release site is no longer marked or posted. The release was described as contamination that spread in a fan-shaped measuring 150 yards (137 meters) wide and 300 yards (275 meters) long. The contamination effected the road and desert land north of the Strontium Semiworks.

Location: The release effected the road and land north of Strontium Semiworks. The road north of the Semiworks facility is 7th Street. The location description is vague.

Release Description: The release occurred on July 24, 1967 during removal of two pumps from A cell at the Strontium Semiworks facility. The contaminated area consisted of a fan-shaped area extending 150 yards (137 meters) wide and 300 yards (275 meters) long north of A cell at Semiworks (201-C). No conclusive cause of the spread is discussed.

Related Sites/ Structures: The stabilized Semiworks area is known as 200-E-41.

Waste Type: Process Effluent

Waste Description: The release contaminated the area with beta/gamma with readings of 30,000 to 80,000 counts per minute from two pumps removed from the Semiworks A cell.

This Site Was Consolidated With:

Code: 200-E-41

Names: 200-E-41; Stabilized Hot Semiworks Area; Strontium Semi-Works Stabilized Area; UN-216-E-38

Code: UPR-200-E-38

Classification: Accepted

Names: UPR-200-E-38; Release from 241-B-152; UN-200-E-38; UN-216-E-4

Reclassification: Consolidated (6/13/2002)

Type: Unplanned Release

Start Date: 1/1/1968

Status: Inactive

End Date: 1/1/1968

Description: 241-B Tank Farm is enclosed with a chain link fence. The release is not separately marked or posted.

Location: The release occurred in the southwest corner of 241-B Tank Farm, adjacent to the 241-B-152 Diversion Box.

Release Description: A line, carrying 221-B cell drain waste, leaked causing a subsidence at the southeast corner of the 241-B-152 Diversion Box. Liquid was observed in the hole. Dose rate levels included 5 rad per hour at a distance of 10 meters (30 feet) and 30 millirem per hour at a distance of 45 meters (150 feet). Contamination spread in a northeast direction from the diversion box. Ground contamination levels ranged from 2,000 to 6,000 counts per minute at a distance of 183 meters (600 feet). Contamination levels decreased to background levels before reaching the 200 East Area perimeter road and fence.

Related Sites/ Structures: The release is associated with the 241-B-152 Diversion Box.

Waste Type: Chemicals

Waste Description: Dose rates ranged from 5 rad per hour to 30 millirem per hour. Ground contamination readings ranged from 2,000 to 6,000 counts per minute. The waste came from the 221-B 9-2 tank and contained ruthenium and cerium.

This Site Was Consolidated With:

Code: 200-E-120

Names: 200-E-120; Contaminated Soil at 241-B Tank Farm; Contamination Migration Beyond the 241-B fence

Code: UPR-200-E-40

Classification: Accepted

Names: UPR-200-E-40; Release from the 216-A-36B Crib Sampler; UN-200-E-40

Reclassification: Consolidated (1/19/2000)

Type: Unplanned Release**Start Date:** 1/1/1968**Status:** Inactive**End Date:****Description:** The site is an unplanned release. The site is not separately marked or posted. It has been consolidated with 200-E-103, because it is located within the boundaries of the larger site. 200-E-103 is a surface stabilized area that is posted Underground Radioactive Material.**Location:** The release occurred on the ground and blacktop area outside the 216-A-36B Crib Sampler Shack (#295-A). The sample shack is located inside the PUREX Exclusion fence, south of 202-A, adjacent to the west side of the PUREX Storage Tunnel.**Release Description:** On August 5, 1968, the valve to the vent line at the 216-A-36B Crib Sampling Shack was inadvertently left open. Liquid was noted spewing from the vent on the 216-A-36B Crib Sample Shack (295-A). The release contaminated approximately 4.65 square meters (50 square feet) of the blacktop outside the shack. The maximum contamination was 150 millirad/hour.**Related Sites/ Structures:** The site is associated with the 216-A-36B Crib, the 295-A Sample Shack, UPR-200-E-39 and the surface stabilized area known as 200-E-103.**Waste Type:** Process Effluent**Waste Description:** The release consisted of contaminated liquid (ammonia scrubber) with maximum beta/gamma readings of 150 millirad/hour.**This Site Was Consolidated With:****Code:** 200-E-103**Names:** 200-E-103; PUREX Stabilized Area; Radiologically Controlled Area - South Side of PUREX

Code: UPR-200-E-41**Classification:** Accepted**Names:** UPR-200-E-41; UPR-200-E-85; UN-200-E-41
Soil Contamination in the Vicinity of R-13
Stairwell (221-B)**Reclassification:** Consolidated (10/6/2005)**Type:** Unplanned Release**Start Date:** 1/1/1972**Status:** Inactive**End Date:****Description:** This is a DUPLICATE of UPR-200-E-85.**Location:** The site is located in the vicinity of the R-13 stairwell on the south side of the 221-B Building.**Release Description:** This site was originally reclassified as Rejected. The reclassification form states that the site was reclassified because it is a duplicate of another site. The reclassification occurred before a Consolidated reclassification status was available. The reclassification status was administratively changed to Consolidated. The reclassification date was not changed. Elevated dose rates were found inside a concrete electrical utility pit during a routine radiation monitoring survey on July 19, 1972. The maximum dose rate levels were up to 12.5 rad per hour, including 1.5 rad per hour of gamma. The release occurred in the ion exchange loading waste export line from tank 18-1 going to 241-BX Tank Farm via the 241-BX-154 diversion box. This waste line is located adjacent to the electrical utility pit. Contaminated waste seeped from the waste line and effected the electric utility pit.**Waste Type:** Process Effluent**Waste Description:** An estimated 30 curies of cesium-137 with readings of 12.5 rad per hour was released to the soil around the pipeline that carried tank 18-1 waste. Half of the cesium released was removed with the soil excavated to expose the line leak.

This Site Was Consolidated With:**Code:** UPR-200-E-85**Names:** UPR-200-E-85; Line Leak at 221-B Stairwell R-13; UN-200-E-41; UN-200-E-85; UN-216-E-13; UPR-200-E-41**Code:** UPR-200-E-47**Classification:** Accepted**Names:** UPR-200-E-47; Contamination Spread from 241-A Tank Farm; UN-200-E-47 **Reclassification** Consolidated (6/13/2002)**Type:** Unplanned Release**Start Date:** 1/1/1974**Status:** Inactive**End Date:****Description:** This tank farm is fenced and radiologically posted. The unplanned release is not separately marked or posted.**Location:** The contamination spread affected the parking lot east of the 702-A Building and ground surfaces inside the 241-A Tank Farm Complex.**Release Description:** Contamination in the form of small white specks was detected in the 241-A Tank Farm on October 14, 1974. The specks covered an area approximately 30 meters (100 feet) by 76 meters (250 feet), extending in a northwesterly direction from the 702-A Vessel Ventilation Building. Contamination levels ranged from 30,000 counts per minute near the building to 1,000 counts per minute at the edge of the spread. It was assumed the material had come from the 702-A stack. The next day, a few specks were noticed in the parking area, east of the 702-A building. The contamination levels ranged from 500 to 2000 counts per minute. It is believed the specks had blown out of the tank farm onto the parking area. The contaminated soil was removed and the area was released for normal service.**Related Sites/ Structures:** The release is associated with the 702-A Vessel Ventilation Building.**Process Description:** Six High Efficiency Particulate Air Filter (HEPA) units were connected in parallel to adequately filter the tank farm exhaust. An inspection of the filters following the incident indicated that the number one filter had failed. It was removed from service for repairs.**Waste Type:** Process Effluent**Waste Description:** Beta/gamma contamination assumed to be particulates from the 702-A stack, with readings of 500 to 20,000 counts per minute, spread across the 241-A Tank Farm.**This Site Was Consolidated With:****Code:** 200-E-131**Names:** 200-E-131; Contaminated Soil Associated with 241-A Tank Farm Complex**Code:** UPR-200-E-48**Classification:** Accepted**Names:** UPR-200-E-48; 241-A-106 Pump Pit Release; UN-200-E-48 **Reclassification** Consolidated (6/13/2002)**Type:** Unplanned Release**Start Date:** 1/1/1974**Status:** Inactive**End Date:****Description:** The release is not separately marked or posted.**Location:** The release affected the inside of the 241-A Tank Farm and the 241-A parking area.

Release Description: During the installation of a new pump at the 241-A-106 pump pit, wind caused contamination to spread, effecting the 241-A Tank Farm, several personnel, five vehicles and the 241-A Tank Farm parking area. Contamination levels ranged from 700 to 2000 counts per minute.

Waste Type: Process Effluent

Waste Description: Wind caused contamination to spread during the installation of a new pump at the 241-A-106 tank. Contamination included beta/gamma readings ranging from 700 to 2,000 counts per minute.

This Site Was Consolidated With:

Code: 200-E-131

Names: 200-E-131; Contaminated Soil Associated with 241-A Tank Farm Complex

Code: UPR-200-E-49 **Classification:** Not Accepted

Names: UPR-200-E-49; Roadway Contamination; UN-200-E-49 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1975

Status: Inactive **End Date:** 1/1/1975

Description: The sites of the release are not currently marked or posted.

Location: The two contaminated areas were on the roadway between the 241-AY Tank Farm and 218-E-12B Burial Ground.

Release Description: On February 7, 1975, a thermocouple well was removed from the 241-A-104 Storage Tank by pulling the well into a plastic tube as it was withdrawn from the tank. The contained well was placed on a flatbed truck for transportation to the burial ground. When leaving the Tank Farm gate, the plastic tube was ripped at the end closest to the front of the truck. At each of two downhill grades on the road, condensate in the plastic tube dripped out of the rip. Because the road was covered by 15 centimeters (6 inches) of snow, the driver thought the drips were probably melting snow. Upon arrival at the burial ground, the driver informed the foreman of the drips. A monitoring survey showed the release of contamination, which was limited to the snow cover and did not reach the roadway. The cleanup was begun that day and finished by noon on February 10, 1975.

Waste Type: Process Effluent

Waste Description: The road was contaminated with beta/gamma with readings of 100,000 counts/minute while transporting a thermocouple from the 241-A-104 tank to the burial ground.

Code: UPR-200-E-51 **Classification:** Accepted

Names: UPR-200-E-51; Liquid Release from Purex to B-Pond; UN-200-E-51 **Reclassification:** Consolidated (1/19/2000)

Type: Unplanned Release **Start Date:** 1/1/1977

Status: Inactive **End Date:**

Description: The site is an unplanned release that discharged to 216-A-29 Ditch, 216-B-3-3 Ditch, and 216-B-3 Pond. There is no visual evidence of this release. It is not separately marked or posted. The 216-B-3 Pond, 216-A-29 Ditch and the 216-B-3-3 Ditch have all been backfilled and surface stabilized. They are posted Underground Radioactive Material areas. This site has been consolidated with the 216-A-29 Ditch.

Location: The incident involved a release to 216-B-3 Pond via the PUREX Building chemical sewer and

the 216-B-3-3 Ditch. All of these waste units are located east of the 200 East Area perimeter fence.

Release Description: On May 15, 1977, a maximum of 15 kilograms (33 pounds) of cadmium as a nitrate solution was released from the PUREX storage tank, TK-324, to the chemical sewer (216-A-29 Ditch), 216-B-3-3 Ditch, and eventually released into the 216-B-3 Pond (B Pond). The incident occurred during an attempted transfer in the PUREX Building from storage tank TK-324 to storage tank TK-F18. A total of 61 drums that had previously contained cadmium nitrate were rinsed out and the solution was put in storage tank TK-324. TK-324 was discharged to the chemical sewer (216-A-29 Ditch). The cadmium nitrate solution was supposed to be transferred to TK-F18 for ultimate disposal to an underground storage tank, however, the Instrument Engineering Flow Diagram was not correct regarding the discharge routing from TK-324.

Related Sites/ Structures: The release is associated with the PUREX facility, 216-B-3, 216-B-3-3 and 216-A-29.

Waste Type: Chemicals

Waste Description: A cadmium nitrate solution containing 15 kilograms (33 pounds) of cadmium was released to the pond and ditch system. Water samples found levels of cadmium to be 5 times the drinking water standard.

This Site Was Consolidated With:

Code: 216-A-29

Names: 216-A-29; 216-A-29 Ditch; A-29 Ditch; Snow's Canyon

Code: UPR-200-E-53

Classification: Accepted

Names: UPR-200-E-53; Contamination at 218-E-1; UN-200-E-53

Reclassification: Consolidated (5/6/2004)

Type: Unplanned Release

Start Date: 1/1/1978

Status: Inactive

End Date:

Description: The burial ground is surrounded with concrete markers and Underground Radioactive Material signs. The release site is not marked or posted.

Location: The release occurred at the south end the 218-E-1 Burial Ground.

Release Description: On October 17, 1978, a contamination spread occurred during backfilling operations when shallow buried contaminated waste in an adjacent trench was uncovered by a bulldozer blade. Numerous spots of radioactive contamination were detected throughout an area of approximately 15.3 meters (50 feet) by 45.8 meters (150 feet) at the south end of the dry waste trench. A spot of contamination measuring up to 150 millirads/hour was also detected on the bulldozer which had been used during backfilling operations at the trench on October 12, 1978.

Waste Type: Soil

Waste Description: Beta/gamma with readings to 150 millirads/hour were detected on the bulldozer blade after working in the 218-E-1 Burial Ground uncovered a portion of the buried waste. Contamination spots were detected in an area at the south end of the waste trench.

This Site Was Consolidated With:

Code: 218-E-1

Names: 218-E-1; 200 East Dry Waste No. 001

Code: UPR-200-E-58 **Classification:** Accepted

Names: UPR-200-E-58; Contaminated Tumbleweeds Found on Dirt Road; UN-200-E-58 **Reclassification:** Rejected (7/28/2008)

Type: Unplanned Release **Start Date:** 1/1/1980

Status: Inactive **End Date:**

Description: The release location is not currently marked or posted. The contaminated tumbleweeds were removed in 1980.

Location: A dirt roadway leading from 241-BX Tank Farm to the Dry Waste Burial Ground was contaminated. The location description is vague, but indicates the dirt road leading from the 241-BX tank farm to the 218-E-10 Burial Ground.

Release Description: On March 4, 1980, the Radiation Monitoring group, using a truck mounted road monitor, detected a high background on the dirt road to the Dry Waste Burial Ground from the 241-BX Tank Farm. A follow-up survey revealed bits and pieces of a crushed tumbleweed spread over about 22.9 meters (75 feet) of roadway. The maximum beta/gamma radiation was 100,000 counts per minute. No other contaminated weeds were found.

Waste Type: Vegetation

Waste Description: The maximum beta/gamma with reading on the tumbleweed fragments was 100,000 counts per minute.

Code: UPR-200-E-59 **Classification:** Accepted

Names: UPR-200-E-59; Contaminated Bird Nests and Mud at 216-A-40 and 244-AR Vault; UN-200-E-59 **Reclassification:** Rejected (4/12/2004)

Type: Unplanned Release **Start Date:** 1/1/1979

Status: Inactive **End Date:**

Description: The 216-A-40 Retention Basin was backfilled and stabilized in 1994. It is surrounded with cement posts and Underground Radioactive Material signs. The contaminated mud nests were removed from the 244-AR Vault building.

Location: Contaminated mud was found in swallow nests at 244-AR Vault and contaminated tumbleweeds and mud were found outside the 216-A-40 Retention Basin bladder. The contamination source was determined to be the 216-A-40 Basin.

Release Description: On May 23, 1979, swallow nests, made of contaminated mud, were found attached to the outside of the 244-AR Vault building. It was determined that mud from the 216-A-40 retention basin was being used by the birds to the build nests at the 244-AR Vault. Contaminated tumbleweeds and mud, with radiological readings up to 20,000 counts per minute, were found outside the containment bladder of the 216-A-40 retention basin. The cause of the contaminated mud was found to be water, from holes in the upper surface of the bladders, combined with dust blown into the basin that created mud. The holes were probably caused by environmental stresses, i.e. winter freeze.

Related Sites/ Structures: The release is associated with the 216-A-40 Retention Basin and 244-AR Vault.

Process Description: The 216-A-40 Retention Basin was constructed with two 108,310-gallon rubber bladder type bags. They were used to contain contaminated cooling water and steam condensate from 244-AR Vault.

Waste Type: Soil

Waste Description: Contaminated mud containing cesium-137 and cobalt-60 with readings of 10,000 to 20,000 counts/minute was found on the outside of the 244-AR building and in the 216-A-40 basin. Mud collected from the top of the bladder contained 120 picocuries/gram of cesium-137 and 116 picocuries/gram of cobalt-60.

Code: UPR-200-E-60 **Classification:** Not Accepted

Names: UPR-200-E-60; Radioactively Contaminated Dirt Spill; UN-200-E-60; UN-216-E-60 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1981

Status: Inactive **End Date:** 1/1/1981

Description: The 1981 release site was cleaned up immediately, and thus is not marked or posted. It is a paved roadway.

Location: The release occurred north of PUREX. An area of blacktop roadway near Building 275-EA was contaminated.

Release Description: The release occurred on June 3, 1981. The J. A. Jones Construction Company was excavating dirt from a crib near the 203-A Building. The excavated dirt was loaded into a truck for transport to the burial ground. The dirt was kept damp prior to loading to minimize dust and sheet plastic was used over the top of the truck bed load during transport. While transporting the load to the burial ground, the vehicle hit a bump and dirt spilled from the truck bed to the blacktop roadway near 275-EA. The driver stopped the vehicle, and Tank Farm Radiation Monitoring was contacted. A trail of dirt 0.3 to 0.6 meters (1 to 2 feet) wide and 12.2 meters (40 feet) long was noted on the roadway. General beta-gamma levels of 200 to 500 counts per minute (with one pebble to 3,000 counts per minute) were detected.

Waste Type: Soil

Waste Description: Radioactive contaminated soil, with beta/gamma readings from 200 to 500 counts per minute (with one pebble to 3,000 counts per minute), was spilled on the roadway while in route to the burial ground. The contaminated soil was removed from a crib near 203-A.

Code: UPR-200-E-61 **Classification:** Not Accepted

Names: UPR-200-E-61; Radioactive Contamination from Railroad Burial Cars; UN-200-E-61; UN-216-E-61 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1981

Status: Inactive **End Date:** 1/1/1981

Description: The site is located at the railroad right-of-way within the area mapped as the Industrial Burial Grounds (218-E-10). The site is an area of contamination found after a concrete burial box was off-loaded from railroad cars to the 200 East burial grounds. The box had left B-Plant with unacceptable levels of contamination that were not found until after the box had been off-loaded. Both the railroad car and the offloading ramp showed smearable contamination. The UPR was decontaminated within a few days after it was discovered.

Location: The release occurred in the railroad right of way at the burial ground unloading ramp in the 218-E-10 Burial Ground area.

Names: UPR-200-E-70; UPR-216-E-70; Radioactive Contamination from Jumper Removal; UN-200-E-70

Reclassification: None

Type: Unplanned Release

Start Date: 1/1/1984

Status: Inactive

End Date: 1/1/1984

Description: Although several areas adjacent to the 244-A Lift Station are radiologically posted (and are contained within WIDS site code 244-A LS), the area contaminated by this event is not marked or posted since it was decontaminated the next day.

Location: The 244-A Lift Station is located south of 7th Street and west of Buffalo Ave.

Release Description: The contamination spread during a jumper removal at the lift station. The contamination on the ground and equipment consisted of beta/gamma with readings ranging from 1,000 to 50,000 counts per minute. An isolated area had contamination readings of 100,000 counts per minute.

Related Sites/Structures: The release is associated with the 244-A Lift Station (WIDS code 244-A LS).

Waste Type: Process Effluent

Waste Description: The contamination consisted of beta/gamma particulates with readings ranging from 1,000 to 50,000 counts per minute. An isolated area around the lift station had contamination readings of 100,000 counts per minute.

Code: UPR-200-E-73

Classification: Accepted

Names: UPR-200-E-73; 241-B-151 Diversion Box Contamination; UN-200-E-73; UN-216-E-1

Reclassification: Consolidated (6/13/2002)

Type: Unplanned Release

Start Date: 1/1/1951

Status: Inactive

End Date: 1/1/1952

Description: The site is not separately marked or posted.

Location: The release site is located near the 241-B-151 Diversion Box, inside the 241-B Tank Farm. The diversion box is in the southwest corner of the 241-B Tank Farm.

Release Description: The soil around the 241-B-151 Diversion Box was contaminated as a result of work activities in the diversion box in the fall of 1951 and again in the summer of 1952.

Related Sites/Structures: The release is associated with the 241-B-151 Diversion Box.

Waste Type: Process Effluent

Waste Description: Approximately 10 curies of contamination was released from the 241-B-151 Diversion Box.

This Site Was Consolidated With:

Code: 200-E-120

Names: 200-E-120; Contaminated Soil at 241-B Tank Farm; Contamination Migration Beyond the 241-B fence

Code: UPR-200-E-74

Classification: Accepted

Names: UPR-200-E-74; 241-B-152 Diversion Box

Reclassification: Consolidated (6/13/2002)

Status: Inactive **End Date:** 1/1/1968

Description: The site, inside the 241-B Tank Farm, is not separately marked or posted. It is a duplicate of UPR-200-E-38.

Location: The release caused the ground to cave in near the southwest corner of the 241-B-152 Diversion Box, inside the 241-B Tank Farm.

Release Description: On January 4, 1968, a soil cave-in was noticed near the southwest corner of the 241-B-152 Diversion Box. High background readings indicated the pipeline that connected the 9-2 tank in the 221-B Plant to the 241-B-110 tank had ruptured.

Related Sites/Structures: The release is associated with the 241-B-152 Diversion Box.

Waste Type: Process Effluent

Waste Description: The release consisted of solution from the 9-2 Tank in B Plant containing cerium-144 with 4,780 curies, ruthenium-106 with 340 curies, and zirconium-niobium 95 with 850 curies. This is a fission product disposal site, high in salt and is neutral to basic pH waste.

This Site Was Consolidated With:

Code: 200-E-120

Names: 200-E-120; Contaminated Soil at 241-B Tank Farm; Contamination Migration Beyond the 241-B fence

Code: UPR-200-E-81 **Classification:** Accepted

Names: UPR-200-E-81; 241-CR-151 Line Break; UN-200-E-81; UN-216-E-9 **Reclassification:** Consolidated (6/13/2002)

Type: Unplanned Release **Start Date:** 1/1/1969

Status: Inactive **End Date:** 1/1/1969

Description: The release, inside the tank farm fenceline, is not separately marked or posted.

Location: UPR-200-E-81 occurred in the waste transfer line near the 241-CR-151 Diversion Box, inside the 241-C Tank Farm.

Release Description: On October 15, 1969, a puddle of contaminated liquid, measuring approximately 1.8 meters by 12.2 meters (6 feet by 40 feet), was discovered a few feet west of the 241-CR-151 Diversion Box. The source was determined to be a leak in an underground transfer line from the PUREX facility (F-18 cell drainage line) to the 241-C-102 Waste Storage Tank, via the 241-CR-151 Diversion Box. When the leak was stopped, most of the liquid seeped into the soil. The contaminated area was covered with about 0.5 meters (18 inches) of backfill and clean gravel. A maximum dose rate of 5 rad per hour at distance of 6.1 meters (20 feet) was recorded.

Related Sites/Structures: UPR-200-E-81 is associated with the 241-CR-151 Diversion Box, the 241-C-102 Tank, and the PUREX 202-A Building.

Process Description: The original transfer line had a carbon steel segment between the 241-CR-151 diversion box and 241-C-102. The leak occurred at the welded connection between the carbon steel portion of the line and the stainless steel portion of the pipeline. The transfer line is now all stainless steel.

Waste Type: Process Effluent

Waste Description: Approximately 136,800 liters (36,000 gallons) of PUREX coating waste was released to the soil. The release included strontium-90 (360 curies), cesium-137 (720 curies), cerium-144 (360 curies), zirconium-95/niobium (1,080 curies), and ruthenium-103 (1,080 curies) at the time of

release.

This Site Was Consolidated With:

Code: 200-E-133

Names: 200-E-133; Contaminated Soil at 241-C Tank Farm; Contamination Migration Beyond the fence at C Farm

Code: UPR-200-E-82

Classification: Accepted

Names: UPR-200-E-82; V122; 241-C-152 Line Break; B Plant Ion Exchange Feed Line Leak; UN-200-E-82; UN-216-E-10

Reclassification: Consolidated (6/13/2002)

Type: Unplanned Release

Start Date: 12/19/1969

Status: Inactive

End Date: 12/19/1969

Description: A large mound of shotcrete is currently on top of the area where the leak surfaced, inside the tank farm fence.

Location: UPR-200-E-82 occurred at the 241-C-152 Diversion Box (inside the tank farm) and flowed to the northeast, downgrade, until it pooled into an area outside the 241-C Tank Farm fence.

Release Description: On December 19, 1969, an underground waste line (V122) leak was discovered near the 241-C-152 Diversion Box. The source was determined to be the feed line (V122) that ran from 241-C-105 tank to the 221-B Building. Approximately 3800 liters (1000 gallons) of the total liquid released collected on the surface and was visually noticed by a Radiation Monitor. The liquid traveled downgrade, in a northeast direction, until it pooled into an area measuring approximately 0.46 square meter (5 square feet), outside the tank farm fence. The precise location of this area is not provided in the references.

Related Sites/Structures: UPR-200-E-82 was associated with the 241-C-152 Diversion Box, the 241-C-105 Tank, 200-E-116-PL and the 221-B Canyon Building.

Process Description: The feed for the B Plant cesium ion exchange process was pumped from the 241-C-105 (lag storage) tank through an underground pipeline and several diversion boxes, to the 221-B building.

Waste Type: Process Effluent

Waste Description: The waste line leak consisted of B Plant Ion Exchange waste containing cesium-134 (100 curies), cesium-137 (11,300 curies), cerium-144 (260 curies), ruthenium-106 (130 curies) and zirconium-95/niobium (260 curies) at the time of release.

This Site Was Consolidated With:

Code: 200-E-133

Names: 200-E-133; Contaminated Soil at 241-C Tank Farm; Contamination Migration Beyond the fence at C Farm

Code: UPR-200-E-86

Classification: Accepted

Names: UPR-200-E-86; 241-C Tank Farm Line (V812) Break Southwest Corner; UN-200-E-86; UN-216-E-14

Reclassification: Consolidated (7/13/2005)

Type: Unplanned Release

Start Date: 1/1/1971

Status: Inactive

End Date: 1/1/1971

Code: UPR-200-E-92 **Classification:** Accepted

Names: UPR-200-E-92; 216-E-20; Ground Contamination Outside 200 East Fence; UN-200-E-92; UN-216-20; UN-216-E-20; UN-216-E-92 **Reclassification** Consolidated (4/12/2004)

Type: Unplanned Release **Start Date:** 1/1/1980

Status: Inactive **End Date:** 1/1/1981

Description: This site was released from radiation zone status after the contaminated soil was removed in 1981. It is no longer marked or posted.

Location: UPR-200-E-92 had been located along the exterior of the eastern 200 East Area perimeter fence.

Release Description: UPR-200-E-92 was the result of contaminated Russian thistle being blown from some of the 200 East Area waste sites and lodging against the east perimeter fence. The thistles decomposed and released radioactive strontium and cesium into the blown sand along the bottom of the fence.

Related Sites/Structures: The contaminated soil from UPR-200-E-92 was excavated and placed in UPR-200-E-56, which was the site of a leak from the 216-A-24 Retention Basin. WIDS site 200-E-109 addresses the reoccurring contamination of the 200 East Area perimeter fence due to contaminated tumbleweeds accumulating along the fence line.

Waste Type: Vegetation

Waste Description: Small amounts of strontium and cesium were deposited into the sand from contaminated Russian thistle fragments.

This Site Was Consolidated With:

Code: 200-E-109

Names: 200-E-109; Contaminated Tumbleweed Accumulation; Contamination Spread in Northeast Corner of 200 East Area

Code: UPR-200-E-93 **Classification:** Accepted

Names: UPR-200-E-93; UN-216-E-21 Ground Contamination Along 200 East Area fence **Reclassification** Consolidated (4/12/2004)

Type: Unplanned Release **Start Date:** 1/1/1980

Status: Inactive **End Date:** 1/1/1981

Description: This unplanned release is no longer marked or posted.

Location: UPR-200-E-93 was located along the interior of the eastern 200 East Area perimeter fence, extending from the 207-A Retention Basin to the northeast corner of the 200 East Area.

Release Description: UPR-200-E-93 is the result of contaminated Russian thistle being blown from some of the 200 East Area waste sites and lodging against the east perimeter fence. Over a number of years, the thistles decomposed and formed a layer of radioactivity under the sand along the fence.

Related Sites/Structures: The contaminated soil from UPR-200-E-93 was excavated and placed in UPR-200-E-56, which was the site of a leak from the 216-A-24 Retention Basin. WIDS site 200-E-109 addresses the reoccurring contamination of the 200 East Area perimeter fence due to contaminated tumbleweeds accumulating along the fence line.

Process Description: Contamination areas are often identified that are attributed to the accumulation of blowing contaminated tumbleweeds and tumbleweed fragments.

Waste Type: Vegetation

Waste Description: Small amounts of contamination were deposited into the sand from the contaminated Russian thistle that collected and then decomposed along the fence line.

This Site Was Consolidated With:

Code: 200-E-109

Names: 200-E-109; Contaminated Tumbleweed Accumulation; Contamination Spread in Northeast Corner of 200 East Area

Code: UPR-200-E-94

Classification: Accepted

Names: UPR-200-E-94; Vehicle Decontamination Area; UN-200-E-94; UN-216-E-22

Reclassification: Rejected (2/10/2000)

Type: Unplanned Release

Start Date: 1/1/1979

Status: Inactive

End Date: 1/1/1979

Description: The site was a large gravel pit that was sometimes used to decontaminate equipment. The gravel pit had been posted with Surface Contamination Area (SCA) signs. The radiological posting was removed from the gravel pit in 1984. The gravel pit was obliterated by heavy construction equipment in the area during the stabilization of the 216-B-3-1 and 216-B-3-2 ditches. The gravel pit is no longer visible or marked.

Location: The site was located inside a gravel pit located north of the 216-B-3-1 Ditch. The 216-B-3-1 Ditch is located east of the 200 East Area perimeter fence.

Release Description: In June 1979, the Radiation Monitoring Department was informed that moisture was being encountered in the excavation east of the 200 East Area perimeter fence adjacent to the 216-A-24 Crib, where fill dirt was being obtained for the construction of the 241-AN Tank Farm (see Site Code UPR-200-E-56). Follow-up surveys revealed a maximum of 8,000 counts per minute beta/gamma contamination in the moisture, on the earth moving equipment and in the newly hauled-in soil around the new 241-AN Tank Farm. The contaminated equipment was taken to the large gravel pit north of the 216-B-3 Ditch Diverter Station, where it was decontaminated. The designation of the gravel pit as UPR-200-E-94 (alias UN-216-E-22) is the result of the contamination residue on the bottom of the gravel pit, with beta/gamma activity reading 300 counts per minute.

Related Sites/Structures: The site is associated with UPR-200-E-56, 216-B-3-1 and 216-B-3-2.

Process Description: In 1970, the gravel pit was posted as a Radiation Zone and used to park regulated (contaminated) equipment during the decontamination of the 216-B-3-2 Ditch. It was used again in 1979 to decontaminate earth moving equipment that became contaminated by digging too close to the 216-A-24 Crib (see UPR-200-E-56). The gravel pit remained posted as a radiological area until 1984.

Waste Type: Soil

Waste Description: An earth moving vehicle was found to be contaminated with a maximum of 8000 counts per minute. Equipment decontamination efforts done in the gravel pit left a 300 counts per minute residue on the bottom of the pit. The waste was unknown beta and gamma contamination.

Code: UPR-200-E-97

Classification: Accepted

Names: UPR-200-E-97; Contamination Near PUREX Railroad Tunnel; Ground Contamination Around

Reclassification: Consolidated (7/19/2004)

Cribs South of PUREX; UN-200-E-97; UN-216-E-25

Type: Unplanned Release

Start Date: 1/1/1980

Status: Inactive

End Date:

Description: The site is not separately marked or posted. It had been located near the 216-A-21 crib, inside the stabilized area now known as 200-E-103. The area was surface stabilized in 1999.

Location: The site is located south of the 202-A Building near the railroad tunnel. A map attachment to RHO-CD-1048 indicates it was adjacent to the west side of tunnel 218-E-14.

Release Description: Ground contamination from an unknown source was detected around the cribs south of PUREX, west of the railroad tunnel (218-E-14).

Related Sites/ Structures: The release site is associated with the 200-E-103 stabilized area.

Waste Type: Soil

Waste Description: Surface soil contamination was identified from an unknown source.

This Site Was Consolidated With:

Code: 200-E-103

Names: 200-E-103; PUREX Stabilized Area; Radiologically Controlled Area - South Side of PUREX

Code: UPR-200-E-105

Classification: Accepted

Names: UPR-200-E-105; Liquid Release in the 241-BY Tank Farm; UN-200-E-105

Reclassification Consolidated (6/13/2002)

Type: Unplanned Release

Start Date: 1/1/1952

Status: Inactive

End Date:

Description: The release site is located within the 241-BY tank farm fence. It is not separately marked or posted.

Location: The contaminated liquid discharge occurred at the manifold header at the 241-BY-107 Tank, inside the 241-BY Tank Farm.

Release Description: On December 16 and 17, 1952, first cycle waste leaked from the manifold header at the 241-BY-107 Tank in the 241-BY Tank Farm onto the ground surface. A mechanic forgot to replace and tighten the bolts on the manifold header after breaking one of the bolts at the flange connection to the manifold header while removing a waste pump. On December 16, 1952, at 2:55 PM liquid waste started being pumped from the 241-BX-107 Tank to the 241-BY-107 Tank. A pool of contaminated liquid next to 241-BY-107 was discovered by a chemical trainee on December 17, 1952, just after midnight, when he went to the wrong tank by mistake. He took a dose reading, which was well up on the third scale of the CP meter, and immediately left the area. The pumping at the 241-BX-107 Tank was stopped when they realized where the liquid was coming from. About 87,055 liters (23,000 gallons) of first cycle waste was discharged onto the ground surface in a low, well confined area, measuring about 27.9 square meters (300 square feet).

Waste Type: Process Effluent

Waste Description: The release consisted of first-cycle waste. The exposure rate to the chemical operator trainee was 7.5 rad per hour about 0.91 meters (3 feet) from the liquid. Estimated dose to the individual was 60 millirems. Radiation surveys revealed a maximum dose rate of 150 rad per

hour at 5.08 centimeters (2 inches) from the surface of the release.

This Site Was Consolidated With:

Code: 200-E-132

Names: 200-E-132; 241-BX/BY Tank Farm Contaminated Soil; Contamination Migration Beyond the 241-BX/BY fence

Code: UPR-200-E-106

Classification: Accepted

Names: UPR-200-E-106; Contamination at a Burning Ground; UN-200-E-106

Reclassification: Consolidated (5/6/2004)

Type: Unplanned Release

Start Date: 1/1/1946

Status: Inactive

End Date: 1/1/1946

Description: UPR-200-E-106 is an unplanned release that occurred in a burning ground in the 200 East Area. There is no visual evidence of contaminated material remaining in the 200-E Burn Pit. This Unplanned Release is not marked or posted.

Location: The location information contained in the 1946 Occurrence Report is vague. The authors of the PUREX Plant Aggregate Area Management Study Technical Baseline Report (BHI-00178) have assumed that this incident occurred within the 200-E Burning Pit.

Release Description: On September 5, 1946 contaminated towels showing radiation levels as high as 2.4 rads/hour (originally measured as 2.5 reps/hour) were found in one of the "burning grounds". The towels were traceable to the Control Laboratory since they were contained with waste from that location. The acronym rep stands for Roentgen Equivalent Physical with one rep equaling 95 ergs/gram (0.0095 joules/kilogram). One rep is roughly equivalent to 1 rad.

Waste Type: Chemicals

Waste Description: The waste consisted of radiologically contaminated towels.

This Site Was Consolidated With:

Code: 200-E BP

Names: 200-E BP; 200-E Burning Pit; 200 East Burn Pit

Code: UPR-200-E-107

Classification: Accepted

Names: UPR-200-E-107; Contamination Spread in 241-C Tank Farm; UN-200-E-107

Reclassification: Consolidated (6/13/2002)

Type: Unplanned Release

Start Date: 1/1/1952

Status: Inactive

End Date: 1/1/1952

Description: The site is not separately marked or posted from the rest of the tank farm postings.

Location: UPR-200-E-107 occurred within the 241-C Tank Farm.

Release Description: On November 26, 1952, process waste was being directed to the first tank in a three tank cascade series. The waste failed to cascade to the second tank, indicating the overflow line was plugged. Since there was an urgent need to discharge the waste to these tanks, an overground transfer was attempted. The foreman wanted to check the pump operation. He believed the pump was not yet submerged into the waste and opened the air valve. Since the pump leg was already in the liquid, it discharged waste with sufficient force to be propelled 6 meters (20 feet) away. Approximately 19 liters (5 gallons) of waste was discharged to the ground with a dose

rate of 4 rad per hour.

Related Sites/ Structures: UPR-200-E-107 is associated with the 241-C-110 Tank in the 241-C Tank Farm.

Waste Type: Process Effluent

Waste Description: The waste was tributyl phosphate (TBP) from the 221-U uranium recovery process. Approximately 18.9 liters (5 gallons) of contaminated liquid was discharged to the ground before the pump could be shut off. The maximum dose rate was 4.2 rad per hour at the surface, including 200 millirem per hour at a distance of 2 inches.

This Site Was Consolidated With:

Code: 200-E-133

Names: 200-E-133; Contaminated Soil at 241-C Tank Farm; Contamination Migration Beyond the fence at C Farm

Code: UPR-200-E-108

Classification: Accepted

Names: UPR-200-E-108; 241-B-102 Tank Release; UN-200-E-108

Reclassification: Consolidated (6/13/2002)

Type: Unplanned Release

Start Date: 1/1/1953

Status: Inactive

End Date: 1/1/1953

Description: The release is not separately marked or posted from the rest of the tank farm.

Location: Contamination spread in and around the 241-B-102 heel jet pit inside the 241-B Tank Farm. The tank is located in the eastern portion of the 241-B Tank Farm.

Release Description: On April 14, 1953, a high level contamination spread was caused when supernatant pumped from 241-B-102 to 241-B-101 spilled to the ground inside the tank farm because a blank was not installed on the heel jet discharge line. The heel jet pit is located near the surface in the center of the tank. Personnel contamination of 4,000 counts per minute on a shoe led to the discovery of the incident. Ground contamination up to 10 rad per hour was identified 3.05 meters (10 feet) from the pit. No significant exposures were known to have occurred. The incident was investigated by the Manufacturing Department as Incident #64, and published as HW-27914. The same incident (same date, location, and circumstances) was later documented by the Radiological Sciences Department on November 5, 1953, as Incident #279 in HW-29957.

Waste Type: Process Effluent

Waste Description: Metal waste supernatant from 241-B-102 was released to the ground. Visible evidence of ground contamination was noted with dose rates up to 10 rad per hour on the surface.

This Site Was Consolidated With:

Code: 200-E-120

Names: 200-E-120; Contaminated Soil at 241-B Tank Farm; Contamination Migration Beyond the 241-B fence

Code: UPR-200-E-109

Classification: Accepted

Names: UPR-200-E-109; Release from 241-B-104; UN-200-E-109

Reclassification: Consolidated (6/13/2002)

Type: Unplanned Release

Start Date: 1/1/1953

Status: Inactive

End Date:

Description: The site is not separately marked or posted from the rest of the tank farm.

Location: The release occurred inside the 241-B Tank Farm near the north side of tank 241-B-104.

Release Description: On November 11, 1953, tributyl phosphate (TBP) waste liquid contaminated the ground around the 241-B-104 Tank due to a blocked riser. The incident was created by a pump float jammed in the riser. About noon on November 10, 1953, operations and maintenance personnel were attempting a routine placement of a portable pump within a 30.48 pump float became jammed about 3.35 meters (11 feet) below the flange and broke loose from the pump. Pending salvage of the float, the concrete riser plug was replaced. Shortly after this happened, a routine transfer of 15140 liters (4000 gallons) of TBP waste, followed by a 757 liter (200 gallon) hot water flush, was made into the 241-B-104 Tank without apparent incident. About 12 hours later another 15140 liter (4000 gallon) waste transfer was made, followed by a steam sparge for 10 to 20 minutes. After the steam sparge, a process operator entered the tank farm to determine if the transfer was complete. An area of approximately 27.9 square meters (300 square feet) surrounding the jammed riser was visibly discolored, with exposure rates of 18 rad per hour at a distance of 15.24 centimeters (6 inches) and 100 millirads per hour at a distance of 9.1 meters (30 feet). Approximately 567.75 liters (150 gallons) of concentrated waste is estimated to have spread onto the ground. It is assumed that the float partially obstructed the waste flow. When steam pressure was applied, the waste was forced up the riser around the gasketed plug and onto the ground.

Waste Type: Process Effluent

Waste Description: 567.75 liters (150 gallons) of tributyl phosphate waste contaminated the ground at the 241-B-104 Tank. The exposure rate was 18 rad per hour at a distance of 15.24 centimeters (6 inches).

This Site Was Consolidated With:

Code: 200-E-120

Names: 200-E-120; Contaminated Soil at 241-B Tank Farm; Contamination Migration Beyond the 241-B fence

Code: UPR-200-E-110	Classification: Accepted
Names: UPR-200-E-110; 241-BY Valve Pit Release; UN-200-E-110	Reclassification: Consolidated (6/13/2002)
Type: Unplanned Release	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1955

Description: The release occurred in the 241-BY Tank Farm. A crescent shaped area around a valve pit was contaminated. The area is not separately marked or posted.

Location: UPR-200-E-110 occurred around the 241-BY-112 Valve Pit, inside the 241-BY Tank Farm.

Release Description: UPR-200-E-110 occurred when liquid contaminant spread through the soil from the 112-BY Valve Pit. Several employees were potentially over-exposed as a result of the release at the 241-BY Tank Farm. A crescent shaped area around the 112-BY Pit was contaminated. A fire hose and two worker's gloves were also contaminated.

Related Sites/Structures: UPR-200-E-110 was associated with the 241-BY-112 Tank, the 241-BY-112 Valve Pit and the 241-BY Tank Farm.

Waste Type: Process Effluent

Waste Description: The release consisted of first cycle waste from the 241-BY-112 Tank. UPR-200-E-110 covered approximately 700 cubic meters (25,000 square feet) of ground around the 112-BY Valve Pit. Contamination levels up to 22 rad per hour were recorded.

This Site Was Consolidated With:**Code:** 200-E-132**Names:** 200-E-132; 241-BX/BY Tank Farm Contaminated Soil; Contamination Migration Beyond the 241-BX/BY fence**Code:** UPR-200-E-114**Classification:** Accepted**Names:** UPR-200-E-114; 202-A Valve Pit; UN-200-E-114 **Reclassification** Rejected (4/20/2000)**Type:** Unplanned Release**Start Date:** 1/1/1974**Status:** Inactive**End Date:** 1/1/1974**Description:** The documented release describes a personnel contamination. The location where the employee became contaminated was not identified beyond "a valve pit outside 202-A."**Location:** The event occurred in an unidentified valve pit outside the 202-A Building.**Release Description:** An employee had been working in an area where contamination was found. Smearable contamination of 8,000 counts per minute beta-gamma and 1,000 disintegrations per minute of alpha were recorded on the employee. The telephone report documents that an americium lung count was also done on the employee. The results of the lung count reported less than 0.16 nanocuries of americium-241.**Waste Type:** Process Effluent**Waste Description:** Readings of 8,000 counts/minute beta and 1,000 counts/minute alpha were detected on an employee. Americium was detected in a lung count.**Code:** UPR-200-E-115**Classification:** Accepted**Names:** UPR-200-E-115; Contamination Spread Inside 241-AX; UN-200-E-115 **Reclassification** Consolidated (6/13/2002)**Type:** Unplanned Release**Start Date:** 1/1/1974**Status:** Inactive**End Date:** 1/1/1974**Description:** UPR-200-E-115 was liquid release to the soil around the 241-AX-103 Pump Pit inside the tank farm. The site is not separately marked or posted.**Location:** The release occurred on the ground adjacent to the 241-AX-103 Pump Pit, inside the 241-AX Tank Farm fence.**Release Description:** During bleeding of air from a line, air flowed up (instead of down) causing contaminated liquid to spray onto two employees and the ground adjacent to the 241-AX-103 Pump Pit. The employees were wearing coveralls and assault masks. The 241-AX-103 pump pit was contaminated with levels up to 5 rad per hour. The ground around the pump pit had maximum contamination levels of 2 rad per hour.**Related Sites/Structures:** UPR-200-E-115 was associated with the 241-AX-103 Pump Pit and the 241-AX Tank Farm.**Waste Type:** Process Effluent**Waste Description:** Contaminated liquid from the 241-AX-103 pump pit effected the ground adjacent to the pump pit. Dose rates up to 2,000 millirad per hour were detected.**This Site Was Consolidated With:**

Code: 200-E-131
Names: 200-E-131; Contaminated Soil Associated with 241-A Tank Farm Complex

Code: UPR-200-E-116 **Classification:** Accepted
Names: UPR-200-E-116; 241-BY-112 Flush Release; **Reclassification** Consolidated (6/13/2002)
 UN-200-E-116
Type: Unplanned Release **Start Date:** 1/1/1972
Status: Inactive **End Date:** 1/1/1972

Description: The site is not separately marked or posted.

Location: The release occurred inside the 241-BY Tank Farm, effecting the area surrounding the 241-BY-112 pump pit.

Release Description: On November 20, 1972, while backflushing a pump in the 241-BY-112 tank, an employee and his surroundings were sprayed with caustic, contaminated flush water due to a gasket failure. Maximum contamination on the operators outer coveralls was 12 rad per hour at a distance of one inch. Contamination levels around the pit varied from 1 to 3 rad per hour a distance of six inches. The area around the pit was covered with dirt.

Waste Type: Process Effluent

Waste Description: An unknown amount of caustic flush water containing cesium-137, yttrium-90, and strontium-89/90 was released with dose rates up to 3 rad per hour at 15 centimeters (6 inches).

This Site Was Consolidated With:

Code: 200-E-132
Names: 200-E-132; 241-BX/BY Tank Farm Contaminated Soil; Contamination Migration Beyond the 241-BX/BY fence

Code: UPR-200-E-117 **Classification:** Accepted
Names: UPR-200-E-117; Contaminated Liquid Spill; UN- **Reclassification** Consolidated (11/22/2004)
 200-E-117
Type: Unplanned Release **Start Date:** 1/1/1972
Status: Inactive **End Date:**

Description: The release was identified above an encased waste line on the south of PUREX and west of the railroad tunnel. The release site is no longer marked or posted. The release site is within a larger area that was surface stabilized in 1999, known as 200-E-103.

Location: The spill occurred on the south side of 202-A, west of the railroad tunnel.

Release Description: During the excavation of an encased waste line on April 20, 1972, employees encountered liquid spurting up out of ground in the hole they had dug. The excavation was within a few inches of the top of the encasement. Personnel were evacuated from the caisson in which they were working.

Related Sites/ Structures: The site is associated with the 241-A-151 Diversion Box and 200-E-103.

Process Description: Underground pipelines V021, V022 and V023 connect the 241-A-151 Diversion Box to the 241-AW Tank Farm.

Waste Type: Process Effluent

Waste Description: Dose rates following the release were 2 rad per hour including 500 millirad per hour at 0.3 meters (1 foot) from the liquid. Mud samples taken at the point where the leak occurred showed primarily cesium and strontium with little evidence of short-lived radionuclides.

This Site Was Consolidated With:

Code: 200-E-103

Names: 200-E-103; PUREX Stabilized Area; Radiologically Controlled Area - South Side of PUREX

Code: UPR-200-E-118 **Classification:** Accepted

Names: UPR-200-E-118; Airborne Release from 241-C-107; UN-200-E-118 **Reclassification:** Consolidated (6/13/2002)

Type: Unplanned Release **Start Date:** 1/1/1957

Status: Inactive **End Date:** 1/1/1957

Description: The release site is not separately marked or posted.

Location: The release occurred inside the 241-C Tank Farm, at the 241-C-107 Tank.

Release Description: On April 20, 1957, an airborne particle release caused contamination to spread inside the 241-C Tank Farm fence and extended 91 meters (300 feet) to the south of the badge house and an additional 270 meters (900 feet) to the north of the badge house. The contamination also spread outside of the fence, affecting the south bank of the parking lot. The highest dose rate at the surface was estimated at 50 millirad per hour, with one particle deposited per square foot.

Related Sites/Structures: UPR-200-E-118 is associated with the 241-C-107 Tank and the 241-C Tank Farm.

Waste Type: Soil

Waste Description: The contaminated particles on the ground surface read up to 3,000 counts per minute.

This Site Was Consolidated With:

Code: 200-E-133

Names: 200-E-133; Contaminated Soil at 241-C Tank Farm; Contamination Migration Beyond the fence at C Farm

Code: UPR-200-E-119 **Classification:** Accepted

Names: UPR-200-E-119; Contamination Spread Inside 241-AX; UN-200-E-119 **Reclassification:** Consolidated (6/13/2002)

Type: Unplanned Release **Start Date:** 1/1/1969

Status: Inactive **End Date:** 1/1/1969

Description: The release occurred on the ground near the 241-AX-104 Tank. It is not separately marked or posted from the rest of the tank farm.

Location: UPR-200E-119 occurred adjacent to the 241-AX-104 Tank, inside the 241-AX Tank Farm fence.

Release Description: An employee mistakenly pulled a contaminated electrode cable out of Tank 241-AX-104 and set it on the ground. He then removed his contaminated gloves and set them on the ground. Contamination was limited to a small area near the 241-AX-104 Tank, the employee, and the change house. Due to the high dose rate on the electrode, the employee received a whole body

and extremity dose.

Related Sites/ Structures: UPR-200-E-119 was associated with the 241-AX-104 Tank and Change House.

Waste Type: Process Effluent

Waste Description: The release consisted of high-level waste from Tank 241-AX-104 dripping onto the soil from a contaminated electrode cable that had been inside the 241-AX-104 tank.

This Site Was Consolidated With:

Code: 200-E-131

Names: 200-E-131; Contaminated Soil Associated with 241-A Tank Farm Complex

Code: UPR-200-E-125

Classification: Accepted

Names: UPR-200-E-125; 241-A-104 Release; UN-200-E-125

Reclassification: Consolidated (6/13/2002)

Type: Unplanned Release

Start Date: 1/1/1975

Status: Inactive

End Date: 1/1/1975

Description: The release is within the 241-A Tank Farm fence. The site is not separately marked or posted.

Location: UPR-200-E-125 occurred in the soil underneath the 241-A-104 Tank, inside the 241-A Tank Farm.

Release Description: Single Shell Tank 241-A-104 was classified a "Confirmed Leaker" on April 8, 1975 due to radiation readings increasing at several locations beneath the tank. Occurrence Report 75-39 was issued to document the event.

Related Sites/ Structures: UPR-200-E-125 was associated with the 241-A-104 Tank and the 241-A Tank Farm.

Waste Type: Process Effluent

Waste Description: Approximately 9463 liter (2500 gallon), containing 18,000 curies of cesium-137 with levels reading to 6,450 counts per minute, was released from the 241-A-104 tank.

This Site Was Consolidated With:

Code: 200-E-131

Names: 200-E-131; Contaminated Soil Associated with 241-A Tank Farm Complex

Code: UPR-200-E-126

Classification: Accepted

Names: UPR-200-E-126; 241-A-105 Tank Leak; UN-200-E-126

Reclassification: Consolidated (6/13/2002)

Type: Unplanned Release

Start Date: 1/1/1965

Status: Inactive

End Date: 1/1/1965

Description: The unplanned release is not separately marked or posted.

Location: UPR-200-E-126 occurred in the soil beneath the 241-A-105 Tank, inside the 241-A Tank Farm.

Release Description: In January 1965, soon after Tank 241-A-105 was filled, a sudden steam release of severe intensity occurred. An investigation revealed that the bottom liner had bulged significantly, thus creating a void volume of 80,000 gallons (303,000 liters). Approximately 18,900 liters

(5000 gallons) of waste leaked from the deformed tank.

Related Sites/ Structures: UPR-200-E-126 is associated with the 241-A-105 Tank and the soil beneath the tank.

Waste Type: Process Effluent

Waste Description: Approximately 18,900 liters (5000 gallons) of waste leaked from the tank that was deformed after a sudden, volatile release of steam.

This Site Was Consolidated With:

Code: 200-E-131

Names: 200-E-131; Contaminated Soil Associated with 241-A Tank Farm Complex

Code: UPR-200-E-127

Classification: Accepted

Names: UPR-200-E-127; 241-B-107 Leak; UN-200-E-127

Reclassification: Consolidated (6/13/2002)

Type: Unplanned Release

Start Date: 1/1/1968

Status: Inactive

End Date:

Description: The site is underground, under the 241-B-107 Tank.

Location: The release occurred in the soil surrounding and beneath the 241-B-107 Tank inside the 241-B Tank Farm.

Process Description: Cramer (1987) reported that this UPR occurred in 1968 when 30,300 liters (8,000 gallons) of waste containing 2,000 curies of cesium-137 leaked from Tank 241-B-107.

Waste Type: Process Effluent

Waste Description: Approximately 30,300 liters (8,000 gallons) of waste containing 2,000 Curies of cesium-137 leaked from the 241-B-107 Tank.

This Site Was Consolidated With:

Code: 200-E-120

Names: 200-E-120; Contaminated Soil at 241-B Tank Farm; Contamination Migration Beyond the 241-B fence

Code: UPR-200-E-128

Classification: Accepted

Names: UPR-200-E-128; 241-B-110 Leak; UN-200-E-128

Reclassification: Consolidated (6/13/2002)

Type: Unplanned Release

Start Date: 1/1/1968

Status: Inactive

End Date:

Description: The site is a release underneath the 241-B-110 Tank.

Location: The release occurred in the soil surrounding and beneath the 241-B-110 Tank, inside the 241-B Tank Farm. The tank is located in the northern portion of the 241-B Tank Farm.

Process Description: The release occurred in 1969 when 31,500 liters (8,300 gallons) of waste containing 4,300 curies of cesium-137 leaked from Tank 241-B-110.

Waste Type: Process Effluent

Waste Description: 31,500 liters (8,300 gallons) of waste from the 241-B-110 Tank containing 4,300 curies of cesium-137 leaked from the 241-B-110 tank.

This Site Was Consolidated With:

Code: 200-E-120

Names: 200-E-120; Contaminated Soil at 241-B Tank Farm; Contamination Migration Beyond the 241-B fence

Code: UPR-200-E-129

Classification: Accepted

Names: UPR-200-E-129; 241-B-201 Leak; UN-200-E-129

Reclassification: Consolidated (6/13/2002)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: This site is the soil surrounding and beneath the 241-B-201 Tank in the 241-B Tank Farm.

Location: The tank is located on the north side of the 241-B Tank Farm, inside the fence.

Release Description: In 1968, it was reported the tank had lost 4560 liters (1200 gallons) of waste containing 420 curies of cesium-137. Slowly decreasing liquid levels prompted the tank to be categorized as Questionable Integrity in 1971. In June of 1982, tank 241-B-201 was classified as a confirmed leaker. It was documented on Operating Limit Deviation Report 82-04.

Waste Type: Process Effluent

Waste Description: Approximately 4,500 liters (1,200 gallons) of waste containing 420 curies of cesium-137 leaked from the 241-B-201 Tank.

This Site Was Consolidated With:

Code: 200-E-120

Names: 200-E-120; Contaminated Soil at 241-B Tank Farm; Contamination Migration Beyond the 241-B fence

Code: UPR-200-E-130

Classification: Accepted

Names: UPR-200-E-130; 241-B-203 Leak; UN-200-E-130

Reclassification: Consolidated (6/13/2002)

Type: Unplanned Release

Start Date: 1/1/1955

Status: Inactive

End Date: 1/1/1977

Description: The release, under the 241-B-203 Tank, is not separately marked or posted.

Location: This release is the soil surrounding and underneath the 241-B-203 Tank, located inside the 241-B Tank Farm. The tank is in the northwest corner of the 241-B Tank Farm.

Release Description: Between 1951 and 1977, unplanned release (UPR) occurred when about 300 gallons (1,136 L) of lanthanum fluoride escaped from tank 241-B-203 and contaminated the soil surrounding and beneath the tank. The leak was determined by decreasing liquid level measurements.

Waste Type: Process Effluent

Waste Description: Approximately 1,135 liters (300 gallons) of waste containing lanthanum fluoride leaked from the 241-B-203 Tank.

This Site Was Consolidated With:

Code: 200-E-120
Names: 200-E-120; Contaminated Soil at 241-B Tank Farm; Contamination Migration Beyond the 241-B fence

Code: UPR-200-E-131 **Classification:** Accepted
Names: UPR-200-E-131; 241-BX-102 Release; UN-200-E-131 **Reclassification** Consolidated (6/13/2002)
Type: Unplanned Release **Start Date:** 1/1/1971
Status: Inactive **End Date:**

Description: The release is not separately marked or posted.

Location: The release includes the soil around and underneath the 241-BX-102 tank, inside the 241-BX Tank Farm.

Release Description: The tank was determined to be leaking based on liquid level measurements and dry well radiation detection profiles. Over time, approximately 266,000 liters (70,000 gallons) of tank waste leaked into the soil. Nineteen new wells were added in 1970 to determine the extent of the plume. An estimated 930 cubic meters (31,000 cubic feet) of soil were affected by the leak. The plume extends eastward in a 1.8 meters (6 foot) band for approximately 30 meters (100 feet).

Waste Type: Process Effluent

Waste Description: Approximately 266,000 liters (70,000 gallons) of high-level, nonboiling liquid waste from the 241-BX-102 Tank was released. It contained 51,000 curies of cesium-137.

This Site Was Consolidated With:

Code: 200-E-132
Names: 200-E-132; 241-BX/BY Tank Farm Contaminated Soil; Contamination Migration Beyond the 241-BX/BY fence

Code: UPR-200-E-132 **Classification:** Accepted
Names: UPR-200-E-132; 241-BX-102 Tank Leak; UN-200-E-132 **Reclassification** Consolidated (6/13/2002)
Type: Unplanned Release **Start Date:** 1/1/1974
Status: Inactive **End Date:**

Description: The area is not separately marked or posted.

Location: The site is the soil beneath the 241-BX-102 Tank, inside the 241-BX Tank Farm.

Release Description: Waste leaked to the ground from the 241-BX-102 Tank.

Related Sites/ Structures: The release is associated with the 241-BX-102 Tank and UPR-200-E-131.

Waste Type: Process Effluent

Waste Description: 9,500 liters (2,500 gallons) of waste leaked from the 241-BX-102 Tank.

This Site Was Consolidated With:

Code: 200-E-132
Names: 200-E-132; 241-BX/BY Tank Farm Contaminated Soil; Contamination Migration Beyond the 241-BX/BY fence

Code: UPR-200-E-133 **Classification:** Accepted
Names: UPR-200-E-133; 241-BX-108 Leak; UN-200-E-133 **Reclassification:** Consolidated (6/13/2002)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The release is not separately marked or posted.

Location: The release site includes the soil surrounding and underneath the 241-BX-108 Tank, inside the 241-BX Tank Farm.

Release Description: The release occurred over time, from 1949 through 1974.

Waste Type: Process Effluent

Waste Description: 95,000 liters (2,500 gallons) of waste leaked from the 241-BX-108 Tank containing approximately 500 curies of cesium-137.

This Site Was Consolidated With:

Code: 200-E-132
Names: 200-E-132; 241-BX/BY Tank Farm Contaminated Soil; Contamination Migration Beyond the 241-BX/BY fence

Code: UPR-200-E-134 **Classification:** Accepted
Names: UPR-200-E-134; 241-BY-103 Tank Leak; UN-200-E-134 **Reclassification:** Consolidated (6/13/2002)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The release is not separately marked or posted.

Location: The release site includes the soil surrounding and underneath the 241-BY-103 Tank, inside the 241-BY Tank Farm.

Release Description: The release occurred over time. The tank was active from 1954 to 1973.

Waste Type: Process Effluent

Waste Description: The release consisted of approximately 19,000 liters (5,000 gallons) of waste from the 241-BY-103 Tank containing PUREX coating waste, tributyl phosphate process waste, and organic wash waste from the 241-BX, 241-BY, 241-B and 241-C tank farms.

This Site Was Consolidated With:

Code: 200-E-132
Names: 200-E-132; 241-BX/BY Tank Farm Contaminated Soil; Contamination Migration Beyond the 241-BX/BY fence

Code: UPR-200-E-135 **Classification:** Accepted

Names: UPR-200-E-135; 241-BY-108 Tank Leak; UN-200-E-135 **Reclassification** Consolidated (6/13/2002)

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The release is not separately marked or posted.

Location: The release site includes the soil surrounding and underneath the 241-BY-108 Tank, inside the 241-BY Tank Farm.

Release Description: The release from the tank occurred over time. The tank was active from 1955 to 1972.

Related Sites/Structures: The release is associated with the 241-BY-108 tank.

Waste Type: Process Effluent

Waste Description: The release consisted of approximately 19,000 liters (5,000 gallons) of tributyl phosphate waste and evaporator bottoms from 241-BY and 241-C Tank Farms.

This Site Was Consolidated With:

Code: 200-E-132

Names: 200-E-132; 241-BX/BY Tank Farm Contaminated Soil; Contamination Migration Beyond the 241-BX/BY fence

Code: UPR-200-E-136 **Classification:** Accepted

Names: UPR-200-E-136; 241-C-101 Tank Leak; UN-200-E-136 **Reclassification** Consolidated (6/13/2002)

Type: Unplanned Release **Start Date:** 1/1/1946

Status: Inactive **End Date:** 1/1/1970

Description: The release, inside the 241-C Tank Farm under Tank 241-C-101, is not separately marked or posted.

Location: UPR-200-E-136 includes the soil around and underneath the 241-C-101 Tank, inside the 241-C Tank Farm.

Release Description: UPR-200-E-136 occurred over a period of time, due to a liquid level decrease in Tank 241-C-101.

Related Sites/Structures: UPR-200-E-136 was associated with the 241-C-101 Tank and the 241-C Tank Farm.

Waste Type: Process Effluent

Waste Description: It is estimated that between 64,600 and 91,200 liters (17,000 and 24,000 gallons) of waste, containing 2,000 curies of radionuclides, has leaked from the 241-C-101 tank. The tank was active from 1946 through 1970 and received bismuth phosphate metal waste, tributyl phosphate process waste and PUREX coating waste.

This Site Was Consolidated With:

Related Sites/ Structures: UPR-200-E-138 was associated with a manometer sensing line from the 8-1 Tank (inside the 221-B Building), the 216-B-2-2 Ditch, the 216-B-2-3 Ditch and the 216-B-3 Pond. The pipeline associated with this release is sitecode 200-E-188-PL (line 2904-2).

Process Description: After UPR-200-E-138 occurred, the chemical sewer piping from the 221-B Building was flushed to the 216-B-2-2 Ditch (see 200-E-188-PL). Due to the contamination levels from the release, the ditch was then backfilled and a replacement ditch (216-B-2-3) was excavated parallel to and south of the entire length of the old ditch. B Plant effluent was then routed to the new ditch. This pipeline bypasses the 207-B Retention Basin.

Waste Type: Process Effluent

Waste Description: Radioactive liquid was released while attempting to measure the liquid level in the Storage Tank 8-1, located inside the 221-B Building. A breakdown of the radioactive material released indicates 1,495 curies (total beta) was discharged to the ditch including approximately 950 curies of strontium-90, 96 curies of cerium/promethium-144 and 1 curie of cesium-137.

This Site Was Consolidated With:**Code:** 216-B-2-2**Names:** 216-B-2-2; 216-B-2-2W; 216-B-1 Ditch

Code: UPR-200-E-140	Classification: Accepted
Names: UPR-200-E-140; PCB Oil Spill at 211-B Bulk Chemical Storage Area; UN-200-E-140	Reclassification: Rejected (7/28/2008)
Type: Unplanned Release	Start Date: 1/1/1986
Status: Inactive	End Date: 1/1/1986

Description: No warning signs or evidence of the unplanned release were observed during a 1991 site visit. Later, a single post was placed into the ground, with a WIDS Sitecode number sign, to mark the approximate location where the release occurred.**Location:** The 211-B Bulk Storage area is located north of the 221-B building. The spill site is located at the southwest corner of the 211-B Bulk Chemical Storage Area in the 200 East Area.**Release Description:** The Hanford Site Waste Management Units Report (1987) states that UPR-200-E-140 occurred on April 23, 1986. Less than 7.6 liters (2 gallons) of oil containing between 1 to 38 parts per million of polychlorinated biphenyl (PCB) was spilled to the ground at the southwest corner of the 211-B Bulk Storage Area.**Related Sites/ Structures:** UPR-200-E-140 was associated with the 211-B Bulk Chemical Storage Area.**Waste Type:** Chemicals**Waste Description:** The release consisted of oil contaminated with polychlorinated biphenyls (PCBs) at a concentration of 1 to 38 parts per million.

Code: UPR-200-E-141	Classification: Not Accepted
Names: UPR-200-E-141; 2718-E Building Uranyl Nitrate Spill to Ground; UN-200-E-141	Reclassification: None
Type: Unplanned Release	Start Date: 1/1/1984
Status: Inactive	End Date: 1/1/1984

Description: The site is a release of corrosive uranyl nitrate onto asphalt and soil that occurred at the 2718-E Building. The site was located within a fenced area that includes the 209-E facility. The contaminated asphalt and soil were removed until only background levels remained. The site is not currently marked or posted.

Location: The site had been adjacent to the 216-C-7 Crib and the southeast corner of the 2718-E building. It was southwest of the 209-C Building.

Release Description: In September 1984, a 208-liter (55-gallon) container failed due to corrosion, releasing its contents.

Related Sites/ Structures: UPR-200-E-141 was associated with the 2718-E Building.

Waste Type: Chemicals

Waste Description: The release consisted of uranyl nitrate (corrosive), and 84% uranium-235 (source radioactive) from a 207 liter (55 gallon) drum being stored on an asphalt pad.

Code: UPR-200-E-142 **Classification:** Accepted

Names: UPR-200-E-142; 202-A Diesel Fuel Spill; UN-200-E-142 **Reclassification:** Rejected (7/28/2008)

Type: Unplanned Release **Start Date:** 1/1/1986

Status: Inactive **End Date:**

Description: The release site is not physically marked.

Location: The site is located north of the 202-A Building at the 202-A Building diesel fuel tank.

Release Description: The Hanford Site Waste Management Units Report (1987) states that on November 17, 1986, the tank of a diesel-fueled compressor overflowed during filling. The release consisted of 76 liters (20 gallons) of diesel fuel.

Waste Type: Oil

Waste Description: The release consisted of approximately 75.7 liters (20 gallons) of diesel fuel.

Code: UPR-200-W-7 **Classification:** Accepted

Names: UPR-200-W-7; Contamination Spread from the 241-T-151 and 241-T-152 Diversion Boxes; UN-200-W-7 **Reclassification:** Consolidated (6/13/2002)

Type: Unplanned Release **Start Date:** 1/1/1950

Status: Inactive **End Date:**

Description: The release occurred inside the 241-T Tank Farm. The Tank Farm is surrounded with a chain link fence and posted with radiological warning signs. The diversion boxes have been covered with a protective foam layer. The unplanned release is not separately marked or posted.

Location: The 241-T-151 and 152 Diversion Boxes are located in the southeast corner of the 241-T Tank Farm - inside the tank farm fence.

Release Description: Work done in the spring of 1950 at the 241-T-151 and 241-T-152 diversion boxes resulted in contamination spread to the ground around both boxes.

Waste Type: Process Effluent

Waste Description: Dried, loose specks spread from the diversion box and contaminated the surrounding area.

This Site Was Consolidated With:

Code: 200-W-93

Names: 200-W-93; Contaminated Soil at 241-T Tank Farm

Code: UPR-200-W-10	Classification: Accepted
Names: UPR-200-W-10; Contamination Spread at 203-S UNH Tanks; UN-200-W-10	Reclassification: Consolidated (7/19/2004)
Type: Unplanned Release	Start Date: 1/1/1952
Status: Inactive	End Date: 1/1/1952

Description: The site consisted of an area around the 203-S Uranium Nitrate Hexahydrate (UNH) tanks. The 203-S facility area has been decommissioned and surface stabilized (see 200-W-22). It is currently posted with Underground Radioactive Material signs. The release is not separately marked or posted.

Location: The 203-S Uranium Nitrate Hexahydrate (UNH) tanks were located northwest of the 202-S building.

Release Description: In the summer of 1952, the ground around the 203-S Uranium Nitrate Hexahydrate storage tanks were contaminated with uranium. A maximum of 10,000 counts per minute at 25 centimeters (1 inch) was found in this area. The contaminated area was covered with blacktop and surrounded with a wooden rail fence. The fence was posted with Radiation Zone signs in 1952.

Related Sites/Structures: The site is associated with the 203-S tanks and sitecode 200-W-22.

Process Description: The 203-S, 204-S and 205-S Facilities were constructed in the early 1950's as a process unit for the decontamination of uranyl nitrate hexahydrate (UNH) produced by Reduction Oxidation (REDOX) operations. The primary process unit consisted of a column filled with silica gel that removed traces of fission products from the UNH. The silica gel column (SG-1) was located in the underground 205-S vault. The vault also contained a waste neutralization tank. Operations in the vault were accomplished remotely. The 205-S facility was a two story, aboveground, chemical make-up building. It contained two chemical make-up tanks, a UNH sample room and extensive piping connected to the REDOX facility and the underground vault. The 203-S facility was an aboveground UNH storage facility that consisted of two 19,000 liter (5,000 gallon) stainless steel tanks that were set in an open concrete basin. A UNH Unloading Facility was located at the adjacent railroad siding. An aboveground UNH pipeline connected the 203-S, 204-S, 205-S Area to the 224-U (UO₃ Plant). During the REDOX Plant operation, the UNH solution was pumped from REDOX to the 205-S silica gel column for purification. The purified UNH was stored in the 203-S and 204-S tanks and then routed to 224-U for final processing via the above ground pipeline.

Waste Type: Soil

Waste Description: The release was described as uranium contamination of the soil with a maximum reading of 10,000 counts per minute at 25 centimeters (1 inch).

This Site Was Consolidated With:

Code: 200-W-22
Names: 200-W-22; 203-S/204-S/205-S Stabilized Area

Code: UPR-200-W-11 **Classification:** Accepted
Names: UPR-200-W-11; UPR-200-W-16; 218-W-1 **Reclassification:** Consolidated (4/12/2004)
 Burial Ground Fire; UN-200-W-11
Type: Unplanned Release **Start Date:** 1/1/1952
Status: Inactive **End Date:** 1/1/1952

Description: This site was a result of a spontaneous fire in the 218-W-1 Burial Ground. It is also a duplicate of UPR-200-W-16, which was mapped correctly on the 218-W-1 Burial Ground.

Location: The unplanned release occurred in and surrounding one of the trenches located in the 218-W-1 Burial Ground. The trench where the fire occurred runs east and west and was roughly in the center of the burial ground. A fire in the dry waste, spread plutonium contamination to the north and south sides of the trench and outside the burial ground in the vicinity of 231-W (also known as 231-Z). The earliest document (HW-25227) described the release as "in the vicinity of the Z Facility" and also as "the area north of the Isolation Building" (231-W).

Release Description: A fire occurred on July 9, 1952 in the "200 West Burial Ground," causing a spread of plutonium contamination to the north of the Isolation Building. Spotty airborne plutonium contamination from this fire fell out of the smoke in the vicinity of the Z Facility. The fire was probably caused by spontaneous ignition of contaminated waste. A survey of the area found a maximum of 20,000 disintegrations inside the burial ground and 30,000 disintegrations outside the burial ground.

Related Sites/Structures: This fire actually occurred at the 218-W-1 Burial Ground, and not immediately outside the PFP Building, as it was mis-mapped. The correct location (WIDS site UPR-200-W-16) was verified in Selby and Soldat (1958).

Waste Type: Chemicals

Waste Description: Eighteen air samples were collected near the 200 West Area Burial Ground during the fire of July 9. Only one of the samples showed detectable alpha activity, this being 2.6 by 2.6E+12 microcuries/cubic centimeter. A vegetation sample collected near the Meteorology Tower on the following day showed an activity density from alpha emitters of 1.5E+06 microcuries/gram. Resamples collected several days later did not confirm this result.

This Site Was Consolidated With:

Code: 218-W-1
Names: 218-W-1; Solid Waste Burial Ground #1; 200-W Area Dry Waste No. 001

Code: UPR-200-W-12 **Classification:** Accepted
Names: UPR-200-W-12; Ground Contamination Near **Reclassification:** Consolidated (6/13/2002)
 242-T
Type: Unplanned Release **Start Date:** 1/1/1951
Status: Inactive **End Date:** 1/1/1951

Description: The site consists of contaminated soil located on the south side of the 242-T Evaporator Building.

Location: The release occurred south of the 242-T Building, inside the 241-TX Tank Farm fence.

Release Description: While jetting waste concentrate from the evaporator in the spring of 1951, a few gallons of waste was forced up and out of an open (above ground) riser. A maximum dose rate of 2 rad per hour at a distance of 5 centimeters (2 inches) was observed.

Waste Type: Process Effluent

Waste Description: Waste is described as "a few gallons" of concentrate and originated from the 242-T Evaporator. "A maximum dose rate of 2 rads per hour at a distance of 5 centimeters was observed on the contaminated area.

This Site Was Consolidated With:

Code: 200-W-94

Names: 200-W-94; Contaminated Soil at 241-TX/TY Tank Farm

Code: UPR-200-W-13

Classification: Accepted

Names: UPR-200-W-13; Liquid Release from REDOX to 207-S and 216-S-17 Pond; UN-200-W-13

Reclassification: Consolidated (1/25/2000)

Type: Unplanned Release

Start Date: 1/1/1952

Status: Inactive

End Date:

Description: The unplanned release was a liquid contamination release that effected the 207-S Retention Basin and the 216-S-17 Pond (REDOX Swamp). Both the pond and the basin have been surface stabilized and posted as "Underground Radioactive Material". The unplanned release is not separately marked or posted.

Location: The 207-S Retention Basin is located inside the 200 West Area, southwest of 202-S. The 216-S-17 Pond is located southwest of 200 West Area, outside the perimeter fence.

Release Description: In November 1952, a leak in the Oxidizer Vessel (H-4) steam coil at the REDOX Facility caused further gross contamination of the 207-S Retention Basin and the swamp area outside the 200 West Area (216-S-17). Over a three day period following the release, dose rates at the pond inlet increased from 6 millirem per hour to 700 millirem per hour. The REDOX process was shut down at the end of the month to replace the leaking coil.

Related Sites/Structures: The release is associated with the REDOX facility (202-S), the 207-S Retention Basin, and the 216-S-17 Pond.

Process Description: The 216-S-17 Pond was the only pond receiving REDOX process cooling water via the 207-S Retention Basin when the release occurred. The pond was used from 1951 to 1954 and was taken out of service because it exceeded contamination limits.

Waste Type: Steam Condensate

Waste Description: In a three day period, the dose rate 15 centimeters (6 inches) over the inlet water stream to the pond increased from 6 millireps/hour to 700 millireps/hour. The acronym "rep" stands for Roentgen equivalent physical. One rep equals 95 ergs/gram (0.0095 joules/kilogram). One rep is roughly equivalent to 1 rad.

This Site Was Consolidated With:

Code: 207-S

Names: 207-S; 207-S Retention Basin; REDOX Retention Basin

Code: UPR-200-W-15

Classification: Accepted

Names: UPR-200-W-15; Liquid Release from REDOX to

Reclassification: Consolidated (1/25/2000)

207-S and 216-S-17 Pond; UN-200-W-15

Type: Unplanned Release **Start Date:** 1/1/1952

Status: Inactive **End Date:** 1/1/1952

Description: The unplanned release was a contaminated liquid release to the 207-S Retention Basin and the 216-S-17 Pond (REDOX Swamp). Both the pond and the basin are surface stabilized and posted as "Underground Radioactive Material". The release is not separately marked or posted.

Location: The 207-S Retention Basin is located inside the 200 West Area, southwest of 202-S. The 216-S-17 Pond is located southwest of 200 West Area, outside the perimeter fence.

Release Description: In October 1952, a steam coil failure in the REDOX "D-12" Waste Concentrator caused gross contamination of process cooling water, the 207-S Retention Basin, and the swamp area outside of the 200 West Area (216-S-17). Dose rates at the swamp up to 2 Rad per hour were recorded. A dike was constructed to maintain a constant water level.

Related Sites/Structures: The release is associated with the REDOX facility (202-S), the 207-S Retention Basin, and the 216-S-17 Pond.

Process Description: The 216-S-17 Pond was the only pond receiving REDOX process cooling water when the release occurred. The pond was used from 1951 to 1954 and was taken out of service because it exceeded contamination limits.

Waste Type: Steam Condensate

Waste Description: According to the October 1952 monthly report, fission product activity was detected in the 207-S Retention Basin and at the edge of the 216-S-17 Pond. Measurements taken of dry sand at the periphery of the pond were as high as 2200 millireps/hour (CP window open) and 80 millirads/hour (CP window closed).

The acronym "rep" stands for Roentgen equivalent physical. One rep equals 95 ergs/gram (0.0095 joules/kilogram). One rep is roughly equivalent to 1 rad.

This Site Was Consolidated With:

Code: 207-S

Names: 207-S; 207-S Retention Basin; REDOX Retention Basin

Code: UPR-200-W-16 **Classification:** Accepted

Names: UPR-200-W-16; Fire at 218-W-1 Burial Ground **Reclassification:** Consolidated (5/6/2004)

Type: Unplanned Release **Start Date:** 1/1/1952

Status: Inactive **End Date:** 1/1/1952

Description: The Unplanned Release is the result of a 1952 spontaneous fire in the 218-W-1 Burial Ground. Alpha contamination was found outside the boundary of the burial ground.

Location: The unplanned release occurred in and surrounding one of the trenches located in the 218-W-1 Burial Ground. The trench where the fire occurred runs east and west and is roughly in the center of the burial ground. A fire in the dry waste spread plutonium contamination to the north and south sides of the trench and outside the burial ground in the vicinity of 231-W (also known as 231-Z).

Release Description: A fire in the Dry Waste Burial Ground occurred on July 9, 1952, spreading alpha contamination from waste boxes. A survey of the area found a maximum of 20,000 disintegrations inside the burial ground and 30,000 disintegrations outside the burial ground.

Related Sites/ Structures: This fire occurred in the 218-W-1 Burial Ground.

Waste Type: Ash

Waste Description: A fire occurred in the 200 West Area Dry Waste Burial Ground on July 9, 1952. Surveys after the fire did not reveal any contamination spread to personnel or equipment. However, appreciable alpha contamination was found on the ground. The maximum reading was 200,000 disintegrations per minute in the burial ground and 30,000 disintegrations outside the burial ground. The burial trench contained cardboard boxes used to dispose of dry waste such as rags, paper, gloves, etc. Procedures limit the amount of plutonium to 5 grams per box, although most boxes contained less than one gram of plutonium. It was estimated that less than 500 grams of plutonium would have been present in the burial trench at the time of the fire.

This Site Was Consolidated With:

Code: 218-W-1

Names: 218-W-1; Solid Waste Burial Ground #1; 200-W Area Dry Waste No. 001

Code: UPR-200-W-17

Classification: Accepted

Names: UPR-200-W-17; Contamination Spread form 241-TX-106 Pump Removal; UN-200-W-17

Reclassification: Consolidated (6/13/2002)

Type: Unplanned Release

Start Date: 1/1/1952

Status: Inactive

End Date: 1/1/1952

Description: The release occurred inside the tank farm fence. The tank farm is surrounded with a chain link fence and radiological warning signs. The release is not separately marked or posted.

Location: The release occurred inside the 241-TX Tank Farm fence, extending southward from the 241-T-106 Tank to the 244-TXR Vault area and northward from 241-TX-106 to the 241-TX-114 Tank.

Release Description: On September 12, 1952, contamination spread in the 241-TX Tank Farm during the removal of a temporary process waste pump from the 241-TX-106 Tank. Waste was being transferred from 241-TX-106 to 241-TX-114 Tank via an overground line. The contamination on a pump seal was not sufficiently removed or packaged prior to moving the assembly, affecting the ground, personnel, and vehicles at the job site. Adverse wind conditions developed before the contamination could be totally removed or fixed, which caused the contamination spread to enlarge.

Waste Type: Chemicals

Waste Description: Contamination consisted of cerium, cesium, nobelium, ruthenium, strontium, and zirconium. After the wind had subsided, the southern area of the 241-TX tank farm was found to be contaminated generally up to 6,000 c/m with isolated spots up to 50,000c/m. The "major construction zone" immediately south of the 241-TX area had lesser amounts of contamination up to 2000c/m with a maximum of 35,000 c/m detected. Less than 1 g of solvent was dispersed by the wind.

This Site Was Consolidated With:

Code: 200-W-94

Names: 200-W-94; Contaminated Soil at 241-TX/TY Tank Farm

Code: UPR-200-W-18

Classification: Accepted

Names: UPR-200-W-18; Liquid Release to 216-U-9

Reclassification: Consolidated (1/25/2000)

Type: Unplanned Release**Start Date:** 1/1/1953**Status:** Inactive**End Date:**

Description: WIDS site UPR-200-W-18 has been reclassified based on documentation that verified it was a DUPLICATE of UPR-200-W-139. Other documentation verified that WIDS site UPR-200-W-139 was located within the boundary of the larger site of 216-U-9 Ditch and has been consolidated into that site. Future updates and closeout information will only be added to 216-U-9 Ditch. This site will no longer be updated.

Location: The site is located in the 200 West Area.

Release Description: In September 1953, contamination from an unknown source was detected in the 216-U-9 Ditch.

Related Sites/ Structures: The site is associated with the 216-U-9 Ditch.

Waste Type: Soil

Waste Description: The waste was unknown contamination of the 216-U-9 ditch.

This Site Was Consolidated With:

Code: 216-U-9

Names: 216-U-9; U Swamp-S Swamp Ditch; 216-U-6

Code: UPR-200-W-21

Classification: Accepted

Names: UPR-200-W-21; Process Line Cave-in at 241-TX-154 Diversion Box; UN-200-W-21; UN-216-W-36

Reclassification: Consolidated (12/7/2004)

Type: Unplanned Release

Start Date: 1/1/1953

Status: Inactive

End Date: 1/1/1953

Description: The release affected an area between 221-T and 222-T. This area is currently covered with shotcrete and posted with Underground Radioactive Material signs. A single post and sign marks the approximate location where the release occurred.

Location: The release occurred at the 241-TX-154 Diversion Box, located east of 221-T.

Release Description: A cave-in occurred above a process line near the 241-TX-154 Diversion Box causing an area of contamination on both sides of the diversion box, between 221-T and 222-T. The reported dose rate was 25 rad per hour at a distance of eight inches. More than one contamination release occurred at this site (UPR-200-W-38).

Related Sites/ Structures: The release is associated with the 241-TX-154 Diversion Box and UPR-200-W-38.

Waste Type: Process Effluent

Waste Description: The release consisted of T Plant process waste with a maximum dose rate of 25 rad per hour at a distance of 20 centimeters (8 inches).

This Site Was Consolidated With:

Code: UPR-200-W-38

Names: UPR-200-W-38; UPR-200-W-40; 216-T-30; Line Break at 241-TX-302C; UN-200-W-38; UPR-200-W-160

Code: UPR-200-W-24 **Classification:** Accepted
Names: UPR-200-W-24; Release from the 244-UR Vault; **Reclassification** Consolidated (6/13/2002)
 UN-200-W-24
Type: Unplanned Release **Start Date:** 1/1/1953
Status: Inactive **End Date:** 1/1/1953

Description: The release was a fan shaped contamination spread from the 244-UR Vault extending southeast across Camden Avenue and 16th Street. The release occurred in 1953. No visual evidence or posting related specifically to this release currently exists.

Location: The release originated from the 244-UR vault located inside the 241-U Tank Farm fence and extended to the southeast, across Camden Avenue to the 207-U Retention Basin area.

Release Description: On April 30, 1953, a contamination spread was caused by a violent chemical reaction in the 002 Blending Tank of the 244-UR Vault. The incident occurred when metal waste supernate was being pumped from the 241-U-109 Tank into the 002-UR Blending Tank inside the 244-UR Vault. Pressure built up from the waste reacting with acid in the 002 tank and was suddenly relieved through a riser. A geyser of liquid was seen rising 9 meters (30 feet) above the vault cover blocks, persisting for approximately 30 seconds. Five people in the area were found to be contaminated with maximum contamination levels of 4,000 counts per minute. Wind (estimated at 20 miles per hour) blew the contamination in a southeast direction beyond the tank farm fence and across the road (Camden Avenue). Ground surface contamination varied from 35 rad per hour at the point of origin (on the 244-UR cover blocks) inside the tank farm, diminishing to 500 counts per minute 300 meters (1,000 feet) away, outside the tank farm.

Process Description: Uranium metal waste supernate was being pumped from the 109-U tank to the 002-UR blending tank prior to being fed into 221-U for continuation in the Tri butyl Phosphate separations process.

Waste Type: Chemicals

Waste Description: Waste included metal waste supernate combined with nitric acid, with readings varying from 35 rad/hour at the source of the contamination to a few hundred counts per minute at a distance of 305 meters (1,000 feet) from the source.

This Site Was Consolidated With:

Code: 200-W-95
Names: 200-W-95; Contaminated Soil at 241-U Tank Farm; Contamination Migration Beyond the 241-U fence

Code: UPR-200-W-26 **Classification:** Accepted
Names: UPR-200-W-26; Contamination Spread During **Reclassification** Consolidated (5/6/2004)
 Burial Operation
Type: Unplanned Release **Start Date:** 1/1/1953
Status: Inactive **End Date:** 1/1/1953

Description: The release is not marked or posted. All the inactive 200 West Area burial grounds are marked and posted Underground Radioactive Material. Only portions of the railroad tracks are currently posted with radiological signs. No specific location or maps are included in the Radiation Incident Investigation Report to indicate where the contamination was found.

Location: Contamination was identified in the railroad burial ground and along the railroad tracks.

Release Description: On November 27, 1953, a box of used connectors was removed from 221-T and buried in the railroad burial garden. While unloading the box from the flatcar, the box lid was dislodged and contamination was spread to the flatcar and to the surrounding ground. Before the contamination had been removed, a sudden strong wind resulted in additional contamination spread. More contamination was discovered when a comprehensive traverse survey was made of the burial garden and adjacent areas, the T plant railroad spur, and (following discovery of previously unsuspected railroad contamination) the main railroad line between the burial garden and REDOX. The Radiation Incident Investigation report did not include any recommendations for reducing the contamination at the burial ground.

Related Sites/Structures: This release is probably associated with the 218-W-1A Burial Ground, near T Plant.

Waste Type: Chemicals

Waste Description: A comprehensive traverse survey was made of the burial garden and adjacent areas, the T plant railroad spur, and (following discovery of previously unsuspected railroad contamination) the main railroad line between the burial garden and Reduction Oxidation (REDOX). Survey results were as follows: general particulate contamination in and near the burial garden with spots up to 600 mrep/hour (uncorrected for source size) at the surface; numerous spots along the T plant spur of similar levels, with one spot of 15 rep/hour at surface; general particulate contamination in large areas to the southeast and southwest of the burial garden; and numerous spots on both sides of the main railroad line to REDOX having dose rates up to 2 rep/hour (uncorrected for source size) at surface. Highest concentrations of particles (greater than one particle per square yard) were found along the main line west of U plant and west of the powerhouse, and in a large area southwest of the burial garden. Analysis of three spots of contamination, taken from (1) the area southwest of the burial garden, (2) from the T plant spur, and (3) the main line near U plant, revealed the activity to be greater than 95% ruthenium.

This Site Was Consolidated With:

Code: 218-W-1A

Names: 218-W-1A; Equipment Burial Ground #1; 200-W Area Industrial Waste Burial Ground #1

Code: UPR-200-W-27	Classification: Accepted
Names: UPR-200-W-27; Duplicate of UPR-200-W-29; Transfer Line Leak at 23rd and Camden; UN-200-W-27; UN-216-W-5	Reclassification: Consolidated (4/12/2004)
Type: Unplanned Release	Start Date: 1/1/1954
Status: Inactive	End Date:

Description: This is a DUPLICATE of UPR-200-W-29, which occurred on November 15, 1954 at the corner of 23rd and Camden Avenue.

Location: The site is located at the southeast corner of the intersection of Camden Street and 23rd Street.

Release Description: The release was caused by the failure of an un-encased first-cycle waste line from T Plant, which resulted in a cave-in, run-off of solution, and high ground-surface dose rates.

Waste Type: Process Effluent

Waste Description: The release was approximately 3800 liters (1000 gallons) of first-cycle process waste from T Plant. (This is a duplicate of UPR-200-W-29)

This Site Was Consolidated With:

Code: UPR-200-W-29
Names: UPR-200-W-29; 23rd and Camden Line Break; Transfer Line Leak; UN-200-W-27; UN-200-W-29; UN-216-W-5; UPR-200-W-27

Code: UPR-200-W-30
Classification: Accepted
Names: UPR-200-W-30; 216-S-12; UN-200-W-30
Reclassification: Consolidated (1/25/2000)
Type: Trench
Start Date:
Status: Inactive
End Date:

Description: WIDS site UPR-200-W-30, has been reclassified based on documentation that verified it was a DUPLICATE of 216-S-12. Future updates and closeout information will only be added to 216-S-12. This site will no longer be updated. The site was surrounded with a light chain and "Underground Radioactive Material" signs. A concrete marker post was labeled 216-S-12. The surface was sand and gravel with no vents or evidence of subsidence.

Location: The site was located northeast of the 202-S building, north of the 291-S stack.

Release Description: Early in July 1954, the REDOX stack was flushed and approximately 75,700 liters (20,000 gallons) of flush water was drained into a pit 6.1 meters (20 feet) wide, 27.4 meters (90 feet) long and 3 meters (10 feet) deep situated in the northeast corner of the REDOX exclusion area. An estimated five curies of beta particle emitters and two to three curies of gamma particle emitters, predominantly ruthenium and zirconium-niobium, were disposed of here and covered with several feet of clean soil. The approximate plant coordinates are: N34965 and W73384.

Related Sites/Structures: The site was associated with the 291-S Stack and 216-S-12. The excavation was described as a 6.1 meters (20 feet) wide by 27.4 meters (90 feet) long by 3 meters (10 feet) deep pit near the northeast corner of the REDOX stack.

Process Description: The site was a single-use liquid waste disposal pit used for 291-S stack flush water.

Waste Type: Water

Waste Description: The site received 68,100 liters (18,000 gallons) of flush water from the 291-S (REDOX) Stack. The water contained ammonium nitrate (600 kilograms). The material contained an estimated five curies of beta particle emitters and two to three curies of gamma particle emitters that were predominantly ruthenium and zirconium-niobium. Potential contaminants of concern include cobalt-60, cesium-137, strontium-90, plutonium-239/240, and uranium-238.

This Site Was Consolidated With:

Code: 216-S-12
Names: 216-S-12; 291-S Stack Wash Sump; REDOX Stack Flush Trench; UPR-200-W-30

Code: UPR-200-W-34
Classification: Accepted
Names: UPR-200-W-34; Overflow of the 216-S-10 Ditch; UN-200-W-34
Reclassification: Consolidated (1/19/2000)
Type: Unplanned Release
Start Date: 1/1/1955
Status: Inactive
End Date: 1/1/1955

Description: The site is an unplanned release resulting from an overflow of the 216-S-10 Ditch. The site is described as 0.4 hectare (1 acre) large, located between the open 216-S-10 Ditch and the REDOX Chemical Sewer Trenches (aka 216-S-11). The release area is not separately marked or posted. The site has been consolidated with the 216-S-10 Ditch.

Location: The release site was located south of REDOX, outside the 200 West area perimeter fence.

Release Description: During May 1955, overflow from the open ditch (216-S-10 Ditch) to REDOX Chemical Sewer Trenches (216-S-11) contaminated about 0.4 hectares (1 acre) of ground between the open ditch and the east trench. The maximum dose rate detected was 1 rad/hour at the ground surface. (HW-60807 says the overflow occurred in May 1955. RHO-CD-673 quotes the May 1954 Monthly Report for this release)

Related Sites/ Structures: This release is associated with the 216-S-10 Ditch, 216-S-10 Pond and the 216-S-11 Ponds.

Waste Type: Process Effluent

Waste Description: The process that the waste originated from, and the quantity of the overflow was not described in the original reference. The maximum dose rate detected was 1 rad/hour at the ground surface.

This Site Was Consolidated With:

Code: 216-S-10D
Names: 216-S-10D; 216-S-10D Ditch; Chemical Sewer Trench; Open Ditch to the Chemical Sewer Trench; 202 Chemical Sump #1 and Ditch; 216-S-10 Ditch

Code: UPR-200-W-37	Classification: Accepted
Names: UPR-200-W-37; Contaminated Boxes Found in a Burn Pit (Z Plant Burn Pit)	Reclassification: Consolidated (5/6/2004)
Type: Unplanned Release	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1955

Description: The burn pit mentioned in the occurrence report describes the location of the Z Plant burn pit. The burn pit is not marked or posted. It was located in an area that is currently part of the 218-W-4C Burial Ground.

Location: The burning pit was located east of Dayton Avenue, southwest of Z Plant.

Release Description: Page 9 from a letter report titled Summary of CPD and Environmental Activities states that on June 10, 1955 during the 12-8 shift, three boxes containing high-level dry waste that were supposed to be taken to the burial ground, were mistakenly dumped into a pit adjacent to a 200 West Area road (along the west perimeter road). Six hours later, personnel delivering scrap to the construction burning pit saw the boxes marked with radiation symbols. A survey found that one box had broken open. Three cotton swabs and two tissues were found with contamination levels of 100 millirad per hour. The other two boxes were still sealed. The waste cartons were removed and sent to the proper burial trench. The pit was decontaminated before returning to its original use as a burning pit.

Related Sites/ Structures: The unplanned release is associated with the Z Plant Burning Pit and the 218-W-4C Burial Ground.

Process Description: Burning grounds routinely received nonradioactive construction and office waste, chemical solvents, and paint waste to be burned.

Waste Type: Misc. Trash and Debris

Waste Description: Contents from the broken boxes included three cotton swabs and two tissues that were contaminated to a maximum of 100 millirad/hour. The site was cleaned by removing the cartons to the proper burial trench and decontaminating the pit.

This Site Was Consolidated With:

Code: 218-W-4C
Names: 218-W-4C; Dry Waste No. 004C

Code: UPR-200-W-40 **Classification:** Not Accepted

Names: UPR-200-W-40; 216-T-30; Line Break Near 241-TX-154; UN-200-W-40; UPR-200-W-160; UPR-200-W-38 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1955

Status: Inactive **End Date:** 1/1/1955

Description: This site code is recommended for deletion because it is a duplicate of UPR-200-W-38 and UPR-200-W-160. UPR-200-W-38 has been selected to be the 'surviving' site code for this incident.

Location: The spill occurred in 200 West Area, southeast of the 221-T Building between the 241-TX-154 Diversion Box and the 241-TX-302C Catch Tank.

Release Description: On December 30, 1955, highly radioactive waste was spilled on the ground. The release consisted of highly radioactive liquid waste due to failure of an underground line during a waste transfer from the 241-TX-302C Catch Tank. A pool of liquid waste with a high dose rate was identified on the surface near the 241-TX-302 Catch Tank (December 30, 1955). It was estimated that several thousand gallons of "metal" waste and rain water had been released to the ground.

Waste Type: Process Effluent

Waste Description: Several thousand gallons of primarily metal waste and rainwater. RHO-CD-673 estimated 19,000 liters (5026 gallons). Other reference documents estimated 7520 liters (2000 gallons). The waste was high in salt and is neutral to basic. High beta/gamma levels were recorded, up to 100 rads/hour at 0.3 meters (1 foot) above the liquid.

This Site Was Consolidated With:

Code: UPR-200-W-38

Names: UPR-200-W-38; UPR-200-W-40; 216-T-30; Line Break at 241-TX-302C; UN-200-W-38; UPR-200-W-160

Code: UPR-200-W-42 **Classification:** Accepted

Names: UPR-200-W-42; Contamination found at 2706-S; UN-200-W-42 **Reclassification:** Consolidated (7/19/2004)

Type: Unplanned Release **Start Date:** 1/1/1957

Status: Inactive **End Date:**

Description: This site is located within the UPR-200-W-41 surface stabilized area. In 1996, the 2706-S shack was still standing, but the release site was not separately marked or posted. The railroad track adjacent to 202-S had been covered with clean dirt. The section of covered track from the fence to the first gravel road intersection is posted as an Underground Radioactive Material area.

Location: In 1957, contamination was found in and around the railroad shack (2706-S) near the REDOX facility.

Release Description: On February 3, 1957, an unusually high radiation background was noticed by two operators on a routine supply check in the railroad shack (2706-S) north of REDOX. The shack was evacuated and radiation monitoring was immediately called. A follow up survey revealed

contamination on the papered floor to 3,200 millirad/hour. Spotty contamination to 500 millirad/hour was found on the snow outside of the shack by the south exit, near the 202-S Canyon Building, and toward the telephone and railroad tracks. The cause of the contamination is unknown.

Related Sites/ Structures: The site is associated with the REDOX railroad cut and UPR-200-W-41.

Waste Type: Chemicals

Waste Description: The floor of the shack was contaminated with beta/gamma with readings to 500 millirads/hour on the snow outside of the shack and beta/gamma with readings to 3,200 millirads/hour on the papered floor inside the shack.

This Site Was Consolidated With:

Code: UPR-200-W-41

Names: UPR-200-W-41; Railroad Contamination; REDOX Railroad Cut Contamination; UN-200-W-41

Code: UPR-200-W-44

Classification: Accepted

Names: UPR-200-W-44; Railroad Track Contamination; UN-200-W-44

Reclassification: Rejected (5/12/2014)

Type: Unplanned Release

Start Date: 1/1/1957

Status: Inactive

End Date:

Description: The waste site was evaluated and reclassified to Rejected in 2014. In 1954, a burial box in transit to a decontamination facility fell to the ground while the train was in motion and lodged against a steam line support. The exact location is unknown.

Location: The exact location is not known. Contamination occurred along the railroad track between REDOX and either U Plant or T Plant when the box containing failed equipment fell from the train. (Note: HW-53449 says the box was in route to U Plant, but other references state it was in route to T Plant. T Plant and U Plant were both used as equipment decontamination and repair facilities, but U Plant was used more in the 1960's. It is believed that T Plant is the correct destination).

Release Description: On October 24, 1957, a burial box, used to transport failed equipment from REDOX to the T Plant Canyon, was inadvertently pulled from the rail car when one of the box sling cables caught on a railroad tie, or possibly a switch frog. The area was contaminated up to 2 rads/hour. (Note: HW-53449 says the box was in route to U Plant)

Waste Type: Soil

Waste Description: The release site is soil contaminated with beta/gamma with readings maximum readings up to 2 rads/hour.

Code: UPR-200-W-45

Classification: Accepted

Names: UPR-200-W-45; Burial Box Collapse

Reclassification: Rejected (6/18/2008)

Type: Unplanned Release

Start Date: 1/1/1957

Status: Inactive

End Date:

Description: This release is no longer able to be visually identified. The release is not marked or posted. Based on the date of the release and a sketch included in HW-54636, it is assumed to be associated with 218-W-2A Burial Ground.

Release Description: On August 25, 1958, windborne contaminated soil from the 241-SX Tank Farm spread eastward resulting in approximately 2 acres of contaminated ground outside of the tank farm. During the previous week, conditions in 241-SX-114 tank caused the tank to "bump" three times. On the morning of August 25, 241-SX-114 "bumped" again and showed pressure to 71 inches of water. Steam was observed escaping from the risers of all the tanks in the immediate area. Two of the risers in 241-SX-113 tank pump pit were not sealed. The "bumps" in 241-SX-114 forced contaminated vapors out of the 241-SX-113 tank pump pit. Contamination was deposited on the ground around 241-SX-113 and was spread outside the tank farm by the high wind. The contamination inside the tank farm measured approximately 1350 square meters (15,000 square feet) with a maximum dose rate of 5 rads/hour. An area measuring approximately 2 acres east of the tank farm was contaminated, with readings ranging from 40,000 counts per minute to 100 millirads per hour.

Related Sites/ Structures: The release is associated with the 241-SX Tank Farm and UPR-200-W-114.

Waste Type: Process Effluent

Waste Description: The release included contamination specks from 241-SX-114 and 241-SX-113 with beta/gamma readings of 40,000 counts/minute and spots up to 100 millirads/hour.

This Site Was Consolidated With:

Code: 200-W-96

Names: 200-W-96; Contaminated Soil at 241-S/SX/SY Tank Farm

Code: UPR-200-W-52	Classification: Accepted
Names: UPR-200-W-52; Release from 241-S Diversion Box; UN-200-W-52	Reclassification: Consolidated (7/19/2004)
Type: Unplanned Release	Start Date: 1/1/1958
Status: Inactive	End Date: 1/1/1958

Description: The release site is not currently marked or posted. The area where this release had been located in 1958 was surface stabilized in 1992.

Location: A contamination spread caused an oval shaped area of ground that extended southward from the diversion box and included 10th Street and the south end of the 207-S Retention Basin.

Release Description: A contamination spread from the 241-S Diversion Box occurred on September 15, 1958. It contaminated the ground around the diversion box and an oval shaped area from the diversion box extending southward and includes the south end of the 207-S Retention Basin.

Waste Type: Process Effluent

Waste Description: Contaminated particulates from the diversion box contaminated a large area south of the tank farm.

This Site Was Consolidated With:

Code: UPR-200-W-51

Names: UPR-200-W-51; UPR-200-W-52; Release from 241-S Diversion Box; UN-200-W-51

Code: UPR-200-W-53	Classification: Accepted
Names: UPR-200-W-53; Burial Box Collapse	Reclassification: Consolidated (5/6/2004)
Type: Unplanned Release	Start Date: 1/1/1959

Status: Inactive**End Date:****Description:** The release site is not separately marked or posted.**Location:** The major portion of the contamination was spread about 101 hectares (250 acres) extending in an easterly direction from the 218-W-2A Burial Ground to within 275 meters (300 yards) of the east perimeter fence of the 200 West Area. Spotty particulate contamination was also detected outside of the 200 West Area perimeter fence.**Release Description:** On January 8, 1959, a burial box containing REDOX cell jumpers collapsed during backfilling operations at the burial grounds and spread fission product contamination generally eastward covering about 101 hectares (250 acres) in 200 West Area. Ten people received low-level skin and personal clothing contamination and thirteen government-owned vehicles and two railroad diesel engines were also contaminated. One private vehicle was contaminated. Contamination levels ranged from 50 millirads/hour at the burial site to 60,000 counts per minute at T-Plant. Readings up to 400 counts per minute were obtained east of the 200 West Area fence.**Waste Type:** Equipment**Waste Description:** The release contained fission product (ruthenium-106) with beta/gamma readings that ranged from 50 millirads/hour at the burial site to 60,000 counts/minute at T Plant and readings east of the 200 West Area fence at 400 counts/minute.**This Site Was Consolidated With:****Code:** 218-W-2A**Names:** 218-W-2A; Equipment Burial Ground #2; Industrial Waste No. 02A**Code:** UPR-200-W-59**Classification:** Accepted**Names:** UPR-200-W-59; Contaminated Liquid Released to 216-S-16P **Reclassification** Consolidated (1/25/2000)**Type:** Unplanned Release**Start Date:** 1/1/1965**Status:** Inactive**End Date:** 1/1/1965**Description:** The site is a liquid unplanned release to the 216-S-16 Pond (WIDS site code 216-S-16P), and has been consolidated with that pond. The pond has been surface stabilized and posted as an "Underground Radioactive Material" area. The release is not separately marked or posted.**Location:** The 216-S-16 Pond is located southwest of the 200 West area outside the perimeter fence.**Release Description:** On September 26, 1965, a leak occurred in the 2D column feed tank (F-1) cooling coil. Process effluent entered the cooling water from the coil and was transported from REDOX to the 216-S-16 Pond. The maximum dose rate found at the water edge of the #1 pond lobe inlet was 190 millirads/hour. The release was promptly detected by a radiation monitor.**Related Sites/ Structures:** The release is associated with the REDOX facility (202-S) and the 216-S-16 Pond.**Process Description:** Process cooling water and steam condensate was routinely discharged to the 216-S-16 pond from the REDOX facility.**Waste Type:** Process Effluent**Waste Description:** Beta/gamma radiation with a maximum dose rate of 190 millirads/hour was measured at the 216-S16 Pond #1 Pond (lobe) inlet.**This Site Was Consolidated With:**

Code: 216-S-16P

Names: 216-S-16P; REDOX Pond #2; 202-S Swamp #1; 202-S Swamp and Ditch

Code: UPR-200-W-62

Classification: Accepted

Names: UPR-200-W-62; Duplicate of UPR-200-W-97; Line Leak at 23rd and Camden; UN-200-W-62; UN-216-W-5

Reclassification: Consolidated (12/7/2004)

Type: Unplanned Release

Start Date: 1/1/1966

Status: Inactive

End Date:

Description: The area has been stabilized with gravel. It is surrounded with Underground Radioactive Material signs.

Location: The incident occurred at the corner of Camden Avenue and 23rd Street in 200 West Area.

Release Description: On May 4, 1966, contaminated liquid waste leaked from a ruptured transfer line and came to the ground surface during transfer of second-cycle waste (bismuth phosphate) from the 241-T-107 Tank to the 242-T evaporator feed tank. Liquid ran from the site of the leak and spread over an area about 2 yards (1.83 meters) wide and 40 yards (36.58 meters) long. Surface dose rates ranged from 20 to 5000 millirads/hour. The cause of the rupture is listed in the radiation occurrence report as faulty supervisor judgment. The same line that failed in 1954 was mistakenly tested in 1966, causing liquid waste to surface again.

Related Sites/Structures: The site is a duplicate of UPR-200-W-97. The site is associated with UPR-200-W-29 because a repeat release from the same broken transfer line (documented in UPR-200-W-29 in 1954) occurred again in 1966.

Waste Type: Chemicals

Waste Description: Contaminated second-cycle waste consisting of bismuth phosphate, with readings from 20 to 5,000 millirads/hour.

This Site Was Consolidated With:

Code: UPR-200-W-97

Names: UPR-200-W-97; Transfer Line Leak; UN-200-W-97; UN-216-W-5

Code: UPR-200-W-68

Classification: Accepted

Names: UPR-200-W-68; Road Contamination; UN-200-W-68

Reclassification: Rejected (7/28/2008)

Type: Unplanned Release

Start Date: 1/1/1972

Status: Inactive

End Date:

Description: The release is not physically marked or posted.

Location: Contamination was found near the intersection of Dayton Avenue and 13th Street in 200 West Area.

Release Description: On February 8, 1972, beta-gamma contamination was found on the blacktop at the intersection of Dayton Avenue and 13th Street during a routine survey of 200 West Area roadways. Initial surveys revealed two spots on the roadway to a maximum of 4.5 rads/hour at 5.1 centimeters (2 inches). Extensive surveys made on the following shift discovered a stretch of road of about 30.5 meters (100 feet) with spotty contamination of 5,000 to 80,000 counts per minute (exclusive of previously-mentioned spots) on 13th Street and several spots ranging from 5,000 to 20,000 counts per minute on Dayton Avenue. One Hanford Patrol vehicle (HO-1A 2564)

had 10,000 counts per minute in the left rear fender well (which was promptly cleaned). The cause of the contamination was not conclusively determined. The most likely source of the contamination was dripping from an earlier transport of temperature probes from 241-SX Tank Farm to the burial ground.

Waste Type: Chemicals

Waste Description: Beta/gamma contamination with readings from 5,000 to 80,000 counts/minute was found.

Initial surveys revealed two spots to a maximum of 4.5 rads/hour at 5.1 centimeters (2 inches). Assumed to be from tank farm equipment being transported to burial ground.

Code: UPR-200-W-69

Classification: Accepted

Names: UPR-200-W-69; Railroad Contamination; UN-200-W-69

Reclassification: Rejected (5/13/2008)

Type: Unplanned Release

Start Date: 1/1/1973

Status: Inactive

End Date:

Description: The contamination was identified in 1973. The area was bladed and released from Radiation Zone status in 1974. This Unplanned Release is no longer marked or posted.

Location: Contamination was identified north and northeast from the 204-S Unloading Station and between the 204-S railroad spur and the REDOX railroad cut.

Release Description: On March 2, 1973, a contamination status survey starting at the 204-S Unloading Station led to the discovery of a beta-gamma contamination spread north and northeast of the station. Numerous spots of ground contamination of 2,000 to 50,000 counts per minute were noted with infrequent spots of 20 to 100 millirads/hour. A spot measuring 5,000 millirads/hour was discovered near the railroad gate, outside the radiation zone. Inside the zone, the sump pit was found contaminated from 1,000 to 5,000 millirads/hour and the grating from the sump that was stacked nearby measured to 800 millirads/hour. The survey was extended outside the REDOX exclusion fence where several spots of 5,000 to 100,000 counts per minute (20 to 40 millirads/hour uncorrected) were detected between the 204-S railroad spur and the REDOX railroad cut embankment. The suspected cause of the ground contamination was high winds spreading material from a contaminated drain pit.

Related Sites/Structures: The site is associated with 200-W-22.

Waste Type: Chemicals

Waste Description: Beta/gamma contamination with readings from 2,000 to 50,000 counts/minute to 5,000 millirads/hour were measured at the railroad gate and from 5,000 to 100,000 counts/minute were measured outside the REDOX exclusion fence.

Code: UPR-200-W-71

Classification: Accepted

Names: UPR-200-W-71; Contamination Spread from 16th Street to Dayton Ave.; UN-200-W-71

Reclassification: Rejected (7/15/2015)

Type: Unplanned Release

Start Date: 1/1/1974

Status: Inactive

End Date:

Description: The site has been reclassified to Rejected. The event occurred in 1974. The resulting contamination is no longer marked or posted.

Location: Contamination was spread onto the road along the route from the 241-U Tank Farm to the 200

West Burial Ground, effecting 16th Street and Dayton Avenue.

Release Description: On January 24, 1974, contamination spread occurred along the roadways in 200 West Area. ARHCO personnel removed a heel-jet from the 241-U-102 Tank in the 241-U Farm. The jet was taken to the burial ground by truck. After the jet was removed from the truck and placed in the burial trench, the truck was found to be contaminated. A follow-up survey revealed contamination along the route of the truck. At the exit of the 241-U Farm, on 16th Street, spots to 600 millirads/hour were found. Numerous contaminated spots from 20,000 to 100,000 counts per minute were found along 16th Street to the intersection of 16th Street and Dayton Avenue, and on Dayton Ave. to the burial ground. The cause of the contamination spread included inadequate packaging of the failed equipment, inadequate surveillance of the load during transit, and transporting the equipment while it was raining, which made surveillance difficult.

Waste Type: Chemicals

Waste Description: The release dripped residue from a contaminated heel-jet removed from the 241-U-102 Tank. Beta-gamma contamination up to 600 millirads/hour was found on the road.

Code: UPR-200-W-72	Classification: Accepted
Names: UPR-200-W-72; Contamination at 218-W-4A	Reclassification: Consolidated (5/6/2004)
Type: Unplanned Release	Start Date: 1/1/1975
Status: Inactive	End Date:

Description: This release site is not separately marked or posted. The release occurred inside the 218-W-4A Burial Ground.

Location: Contaminated waste was found on the ground surface within the 218-W-4A Burial Ground.

Release Description: On October 21, 1975, contaminated laboratory waste, with gross alpha and mixed fission product contamination, was found to be exposed to the surface. The waste had been buried years ago when depth of burial was only 1.2 meters (4 feet) below grade. It was speculated that this depth requirement was not met. Apparently, some soil erosion occurred which exposed the contaminated waste.

Related Sites/Structures: This release is associated with the 218-W-4A burial ground.

Waste Type: Misc. Trash and Debris

Waste Description: Gross alpha and mixed fission product with beta/gamma readings to 100,000 counts/minute and alpha readings to 70,000 disintegrations/minute were measured at the site.

This Site Was Consolidated With:

Code: 218-W-4A

Names: 218-W-4A; Dry Waste No. 04A

Code: UPR-200-W-74	Classification: Accepted
Names: UPR-200-W-74; Overground Line Leak at 241-Z; UN-200-W-74	Reclassification: Rejected (2/5/2004)
Type: Unplanned Release	Start Date: 1/1/1976
Status: Inactive	End Date: 1/1/1976

Description: The site is a small area where flush solution from decontamination of a cooling waste effluent

header was being pumped. Alpha contamination was found and cleaned up. The area is no longer marked or posted.

Location: The release occurred in an overground line, near the 241-Z-D-8 tank in 241-Z. The area is south of 234-5Z, inside the Z Plant security fence.

Release Description: On May 18, 1976, a small area of ground was contaminated at the surface with alpha activity when an overground polyethylene line leaked at a connection. About 20 square inches (129 centimeters) of ground was contaminated to a maximum of 8,000 disintegrations per minute. Flush solution from decontamination of the Reclamation facility cooling waste effluent header D-3 was being pumped according to Standard Operating Procedure from a tank located in manhole number 4 to tank D-8, 241-Z, through an overground polyethylene pipe. Approximately two minutes after the pumping was initiated a leak was noted at a connection within the greenhouse at manhole number 4. Pumping was immediately stopped and an inspection of the entire pumping route was completed. Solution was noted outside of the protective plastic that was taped around the pipe at a second connection outside of the greenhouse. The solution appeared to be contained by a secondary plastic sheet that the pipe was also wrapped in. During the release survey by Radiation Monitoring following cleanup of this solution, the small area of contaminated ground was found.

Waste Type: Chemicals

Waste Description: Alpha contamination with maximum readings of 8,000 disintegrations/minute.

Code: UPR-200-W-75

Classification: Accepted

Names: UPR-200-W-75; Contamination Spread at 241-Z; UN-200-W-75

Reclassification: Rejected (2/5/2004)

Type: Unplanned Release

Start Date: 1/1/1975

Status: Inactive

End Date:

Description: The site is not marked or posted. The contaminated soil was removed and the site can no longer be located. The release occurred inside a larger area related to a later unplanned release (UPR-200-W-79). At the time of the UPR-200-W-79 release (October 1978), the entire area was again decontaminated.

Location: The release occurred near the 241-Z Facility, south of the 234-5Z building, inside the Z Plant security fence.

Release Description: On January 9, 1975, contaminated equipment inside the 241-Z Area revealed contamination at the D-7 Sample Cabinet. 40,000 d/m alpha was found outside the doors and more than 40,000 d/m was found inside the cabinet. An area of about 70 feet square (21.34 meters square) on the ground and on the black top under the cabinet was found to have contamination levels ranging from 2,000 d/m to 80,000 disintegrations per minute direct with 20,000 d/m smearable.

Related Sites/Structures: This release site is associated with UPR-200-W-79.

Waste Type: Chemicals

Waste Description: Beta/gamma with readings from 2,000 to over 40,000 disintegrations/minute direct and smearable to 20,000 disintegrations/minute.

Code: UPR-200-W-77

Classification: Not Accepted

Names: UPR-200-W-77; Contaminated Coyote Feces;

Reclassification: None

UN-200-W-77

Type: Unplanned Release**Start Date:** 1/1/1978**Status:** Inactive**End Date:****Description:** The site cannot be distinguished in the field; the coyote feces were immediately picked up and no remaining contamination was found at the site.**Location:** The feces were found in the northeast corner of 200 West Area.**Release Description:** On April 4, 1978, contaminated coyote feces were found while soil samples were being collected for the Environmental Surveillance Program. Radioisotopic analyses were performed on samples of the feces. Apparently, the coyotes had eaten mice which had gained entry into medium or high level radioactive waste contamination systems. Many possible source areas exist in 200 West Area.**Waste Type:** Animal Waste**Waste Description:** The waste contained plutonium-239, americium-241, cerium-144, europium-155, and strontium-90 with beta/gamma readings to 40,000 counts/minute and alpha readings to 55,000 counts/minute.**Code:** UPR-200-W-79**Classification:** Accepted**Names:** UPR-200-W-79; Contamination Spread at 241-Z; UN-200-W-79**Reclassification:** Consolidated (5/14/2004)**Type:** Unplanned Release**Start Date:** 1/1/1978**Status:** Inactive**End Date:****Description:** Alpha contamination was spread inside and outside of the 241-Z Sump radiation zone fence. The area was decontaminated and is no longer marked or posted. It occurred in the graveled and concrete area around the 241-Z Building.**Location:** The release occurred at the 241-Z area, south of the 234-5Z building, and inside the 234-5Z exclusion fence.**Release Description:** On October 6, 1978, contamination was detected due to the failure of the pH line at the 241-Z Sump. During replacement of steam valves and lines at the 241-Z Sump D-7 and D-8 sample cabinets, Radiation Monitoring detected alpha contamination in excess of 40,000 disintegrations per minute on an out of service pH control line behind the D-8 sample cabinet. Other locations which were contaminated in excess of 40,000 disintegrations per minute included the concrete pad under the D-7 and D-8 sample cabinets, and the steam line to the sample cabinets. Ground contamination of a five-foot square dirt area under the pH meter lines and another five-foot square dirt area north of the D-7 and D-8 sample cabinets outside of the 241-Z Sump radiation zone fence was detected. Alpha contamination was detected up to 2,000 disintegrations per minute under the pH lines and up to 500 disintegrations per minute outside the fence area. The apparent cause of the contamination was the failure of the pH line due to normal deterioration. The line had not been used or worked on for many years.**Related Sites/ Structures:** The area is associated with UPR-200-W-75.**Waste Type:** Process Effluent**Waste Description:** Alpha contamination with readings from 500 to 2,000 disintegrations per minute was detected behind the 241-Z "D-8" sample cabinet. Alpha contamination in excess of 40,000 disintegrations per minute was detected on the pH line, concrete pad, soil and steam line.

This Site Was Consolidated With:**Code:** 241-Z**Names:** 241-Z; 241-Z Sump; 241-Z Tank Farm; 241-Z Tank Pit; 241-Z Treatment and Storage System; 241-Z Treatment and Storage Tanks; 241-Z-D-4; 241-Z-D-5; 241-Z-D-7; 241-Z-D-8**Code:** UPR-200-W-80**Classification:** Accepted**Names:** UPR-200-W-80; 241-S/SX Contamination Migration; UN-200-W-80**Reclassification:** Consolidated (6/13/2002)**Type:** Unplanned Release**Start Date:** 1/1/1978**Status:** Inactive**End Date:** 1/1/1978**Description:** The 241-S/SX Tank Farms are surrounded with a chain link fence and posted with radiological warning signs. The unplanned release is not separately marked or posted.**Location:** Contamination was found near the 244-S Catch Station construction site and other areas inside the 241-S and 241-SX Tank Farms.**Release Description:** The contamination resulted from windborne contaminated soil and removable surface contamination in the 241-S and 241-SX Tank Farms, possibly from leaking vent lines or an old spill area that was not adequately stabilized.**Related Sites/ Structures:** UPR-200-W-80 was associated with the 244-S Catch Station construction site, the 241-S and the 241-SX Tank Farms.**Waste Type:** Process Effluent**Waste Description:** Laboratory analysis of some of the contamination found contained 1.4 microcuries of strontium-90 and a trace amount of cesium-137 with maximum readings of 60,000 counts per minute.**This Site Was Consolidated With:****Code:** 200-W-96**Names:** 200-W-96; Contaminated Soil at 241-S/SX/SY Tank Farm**Code:** UPR-200-W-81**Classification:** Accepted**Names:** UPR-200-W-81; Contamination Specks in 241-S/SX; UN-200-W-81**Reclassification:** Consolidated (6/13/2002)**Type:** Unplanned Release**Start Date:** 1/1/1979**Status:** Inactive**End Date:** 1/1/1979**Description:** The tank farm is surrounded with a chain link fence and posted with radiological warning signs. The unplanned release is not separately marked or posted.**Location:** The release site was located on the ground between the 241-S Tank Farm and the 241-SX Tank Farms, inside the fence.**Release Description:** A radiation survey of the area on December 22, 1978, revealed contamination in the form of specks reading from 500 to greater than 100,000 counts per minute on the ground between 241-S and 241-SX Tank Farms. The occurrence report was issued in January 1979, citing loose surface contamination as the cause of the contamination migration.**Related Sites/ Structures:** UPR-200-W-81 is associated with the 241-S and 241-SX Tank Farm operations.**Waste Type:** Process Effluent

Waste Description: The release consisted of airborne contamination from surface contaminated tank farm equipment. Contamination readings ranged from 500 to more than 100,000 counts per minute.

This Site Was Consolidated With:

Code: 200-W-96

Names: 200-W-96; Contaminated Soil at 241-S/SX/SY Tank Farm

Code: UPR-200-W-83	Classification: Accepted
Names: UPR-200-W-83; Radioactive Spill Near 204-S Radiation Zone; UN-200-W-83; UN-216-W-82	Reclassification: Consolidated (7/19/2004)
Type: Unplanned Release	Start Date: 1/1/1981
Status: Inactive	End Date: 1/1/1981

Description: The unloading station was decontaminated and decommissioned in December 1983. The area where this release occurred in inside a posted Underground Radioactive Material Area. The release site is co-located with WIDS sitecode 200-W-22.

Location: UPR-200-W-83 occurred on the step-off pad (outside the 204-S radiation area), at the 204-S Railroad Car Unloading Facility, which was located south of the 204-S Foundation and north of the 203-S Basin in the 200 West Area.

Release Description: The release occurred at the 204-S Railroad Car Unloading Facility. The release contaminated the step-off pad outside the 204-S radiation zone at the 204-S Unloading Facility. Improper handling of contaminated trash was the primary cause of the contamination spread. Immediately after the release, the site was secured, stabilized, and decontamination was initiated.

Related Sites/Structures: UPR-200-W-83 was associated with the 204-S Railroad Car Unloading Facility, the 203-S, 204-S, and 205-S facilities and sitecode 200-W-22.

Process Description: Radioactive liquid was transported to the Unloading Station in railroad tank cars.

Waste Type: Chemical Release

Waste Description: The waste had an unknown amount of radioactive contamination.

This Site Was Consolidated With:

Code: 200-W-22

Names: 200-W-22; 203-S/204-S/205-S Stabilized Area

Code: UPR-200-W-84	Classification: Accepted
Names: UPR-200-W-84; Ground Contamination During Burial Operation at 218-W-3A	Reclassification: Consolidated (7/14/2004)
Type: Unplanned Release	Start Date: 1/1/1980
Status: Inactive	End Date: 1/1/1980

Description: The release occurred inside the boundaries of an established burial ground. The release is not separately marked or posted.

Location: The release site occurred at the 218-W-3A Burial Ground, which is located on Dayton Ave., northeast of the 200 West Central Waste Complex.

Release Description: On July 23, 1980, a liquid spill occurred during a pump burial. Liquid from the pump contaminated the truck and the ground around the truck.

Related Sites/Structures: UPR-200-W-84 was associated with the 200 West Area Burial Ground (assumed to be 218-W-3A).

Waste Type: Chemicals

Waste Description: The waste had beta and gamma contamination with readings up to 2,000 millirads/hour.

This Site Was Consolidated With:

Code: 218-W-3A

Names: 218-W-3A; Dry Waste No. 003A

Code: UPR-200-W-85

Classification: Accepted

Names: UPR-200-W-85; Radioactive Spill from Multipurpose Transfer Box; UN-200-W-85; UN-216-W-85

Reclassification: Rejected (7/28/2008)

Type: Unplanned Release

Start Date: 1/1/1982

Status: Inactive

End Date: 1/1/1982

Description: The site where UPR-200-W-85 occurred is a concrete pad west of the 2706-T building. A 1998 site visit found a new equipment decontamination and waste handling building (2706-TA) has been built on this concrete pad. The concrete pad was sealed with an epoxy coating. The building entry is posted as FCA-2706-002. The release site is not marked or posted.

Location: UPR-200-W-85 occurred west of the 2706-T Building, which lies northwest of the 221-T Canyon Building in the 200 West Area.

Release Description: In April 1982, a multi-purpose transfer box was moved from the 221-T railroad cut to the cement pad behind the 2706-T Building. While parked on the pad, liquid was observed dripping from the box. The apparent cause of the leak was a weld failure on the outside sheathing covering the concrete shell. Contamination levels up to 100,000 counts per minute were found on the ground. The contamination was cleaned up at the 2706-T pad area. The railroad track from the 2706-T Building to the 221-T railroad cut was surveyed and no contamination was detected.

Related Sites/Structures: UPR-200-W-85 was associated with a concrete pad behind the 2706-T Building, and the railroad tracks between the 2706-T Building and the 221-T railroad cut.

Waste Type: Process Effluent

Waste Description: The contents of the multi-purpose box is not known. The radiological reading on the spill was 100,000 counts per minute beta/gamma.

Code: UPR-200-W-86

Classification: Accepted

Names: UPR-200-W-86; Contaminated Pigeon Feces at 221-U and 204-S; UN-200-W-86; UN-216-W-86

Reclassification: Rejected (1/3/2008)

Type: Unplanned Release

Start Date: 1/1/1981

Status: Inactive

End Date: 1/1/1981

Description: No physical posting or markers currently identify this unplanned release.

Location: Contamination was found around 221-U Building and the 204-S Waste Unloading Facility.

Release Description: In 1981, contaminated pigeon feces were found at several facilities in 200 West Area. The largest amount of contaminated bird feces, as well as the highest levels of contamination, were found at 221-U and near 204-S. The source of the contamination was determined to be the contaminated water accumulating in the 204-S tank basin. The contamination that prompted this occurrence report (81-72) was found and reported on October 27, 1981.

Related Sites/ Structures: The release is mainly associated with the 204-S facility and 221-U.

Waste Type: Animal Waste

Waste Description: The contamination consisted of pigeon feces containing cesium-134, cesium-137, strontium-90, and ruthenium-106, with readings ranging from 10,000 disintegrations per minute (beta/gamma) to 40 millirad/hour.

Code: UPR-200-W-87	Classification: Accepted
Names: UPR-200-W-87; Radioactive Spill from 219-S Filter Housing; UN-200-W-87; UN-216-W-87	Reclassification: Rejected (7/28/2008)
Type: Unplanned Release	Start Date: 1/1/1982
Status: Inactive	End Date: 1/1/1982

Description: The release site is 2.7 square meters (30 square feet) of ground at the 219-S High Efficiency Particulate Air (HEPA) filter housing. In January 2002, work began on installing a new concrete pad to support a replacement filter housing.

Location: UPR-200-W-87 occurred at the 219-S High Efficiency Particulate Air (HEPA) filter housing, which lies northeast of the 222-S Laboratory in the 200 West Area.

Release Description: Water was being blown from the 219-S High Efficiency filter box up the exhaust stack. The smear of the liquid revealed no contamination. The decision was made to change the High Efficiency filter. The 219-S High Efficiency Particulate Air (HEPA) filter housing was opened for the filter change. As the coverplate bolts were removed, water began to run from the housing. The flow continued until it covered approximately 2.7 square meters (30 square feet). After the water soaked into the ground, 2,000 counts per minute beta gamma was found under the filter box, with 300 counts per minute on the remaining damp soil.

Related Sites/ Structures: UPR-200-W-87 was associated with the 219-S High Efficiency filter housing.

Waste Type: Water

Waste Description: The waste was contaminated water containing beta and gamma contamination with readings from 300 to 2,000 counts per minute.

Code: UPR-200-W-88	Classification: Not Accepted
Names: UPR-200-W-88; Radioactive Spill from Uranyl Nitrate (UNH) Trailer; UN-200-W-88; UN-216-W-88	Reclassification: None
Type: Unplanned Release	Start Date: 1/1/1984
Status: Inactive	End Date: 1/1/1984

Description: This release occurred on a roadway and was cleaned up right away. It was not marked or

Status: Inactive **End Date:** 1/1/1985

Description: Radioactive contamination was immediately removed to background levels. The release was to six personnel moving a box of contaminated pipes and affected an area of ground outside of the 236-Z Building. The area is not marked or posted.

Location: UPR-200-W-90 occurred in an area approximately 1,000 feet (300 meters) outside of the 234-5Z Building and south of the 236-Z Building in the 200 West Area.

Release Description: Six employees and an area of ground were contaminated during the transport and loading of pipe sections into a burial box. Apparently, while lifting the second load into the box, the plastic that covered the pipe was ruptured.

Related Sites/Structures: UPR-200-W-90 was associated with the 234-5Z and the 236-Z Buildings.

Waste Type: Chemicals

Waste Description: The waste contained alpha contamination with readings up to 10,000 disintegrations per minute.

Code: UPR-200-W-91 **Classification:** Accepted

Names: UPR-200-W-91; Radioactive Contamination Near 234-5Z Building; UN-200-W-91; UN-216-W-91 **Reclassification:** Rejected (7/28/2008)

Type: Unplanned Release **Start Date:** 1/1/1985

Status: Inactive **End Date:** 1/1/1985

Description: UPR-200-W-91 contaminated an area of ground on the north side of the 234-5Z Building. The release site was covered with snow and ice, so it was contained with plastic and roped off until it could be decontaminated. The final decontamination record could not be found. It is not currently marked or posted.

Location: UPR-200-W-91 occurred in an area adjacent to the north side of the 234-5Z Building, at Z Plant in the 200 West Area.

Release Description: The release occurred on December 11, 1985. A pallet jack was being used to transport a supposedly empty can from a storage area to the 234-5Z Building. While traveling over the ice and snow, the can overturned and liquid alpha contamination spilled to the ground between the lid and gasket. The area was covered with plastic and decontaminated to 2,000 disintegrations per minute. The total contaminated area was reported as 0.6 meters by 1.8 meters (2 feet by 6 feet).

Related Sites/Structures: UPR-200-W-91 was associated with the 234-5Z Building.

Waste Type: Chemicals

Waste Description: The waste contained alpha contamination with readings up to 20,000 disintegrations per minute.

Code: UPR-200-W-95 **Classification:** Accepted

Names: UPR-200-W-95; 207-S Retention Basin; UN-216-W-2 **Reclassification:** Consolidated (1/25/2000)

Type: Unplanned Release **Start Date:** 1/1/1951

Status: Inactive**End Date:** 1/1/1954

Description: The site is a liquid unplanned release that contaminated the 207-S Retention Basin. The retention basin has been backfilled and surface stabilized. The basin is marked and posted with Underground Radioactive Material signs. The release is not separately marked or posted. The unplanned release has been consolidated with the 207-S site.

Location: The 207-S Retention Basin is located approximately 366 meters (1,200 feet) due west of the 222-S Building in the 200 West Area.

Release Description: Multiple coil leaks in the 202-S Building resulted in contamination of the cooling water discharged to the 207-S Retention Basin. In November 1952, dose rates of 250 milirem per hour were recorded at a distance of 1.5 meters (5 feet) above the basin water. In August 1953, maximum dose rates up to 350 millirem per hour were found over the retention basin outlet header. In September 1953, the dose rate in the basin rose to 2 rad per hour. In 1954, the contaminated concrete basin was filled with soil to prevent the contamination from spreading.

Related Sites/Structures: The site is associated with the 202-S facility and the 207-S Retention Basin.

Process Description: Process cooling water and stem condensate was routinely discharged to the 207-S Retention Basin before being sent to other waste disposal sites.

Waste Type: Process Effluent

Waste Description: The basin has been contaminated with approximately 10 curies of fission products.

This Site Was Consolidated With:

Code: 207-S

Names: 207-S; 207-S Retention Basin; REDOX Retention Basin

Code: UPR-200-W-100

Classification: Accepted

Names: UPR-200-W-100; 105-TX to 118-TX Process Line Leak; UN-200-W-100; UN-216-W-8

Reclassification: Consolidated (6/13/2002)

Type: Unplanned Release

Start Date: 1/1/1954

Status: Inactive

End Date: 1/1/1954

Description: The release occurred inside the 241-TX Tank Farm. The tank farm is surrounded with a chain link fence and has been stabilized with gravel. The release is not separately marked or posted.

Location: The location of this Unplanned Release is difficult to define due to discrepancies in reference documentation. The most reliable reference, ARH-2757, places the release inside the 241-TX Tank Farm fence, east of the 241-TX-105 tank.

Release Description: First cycle waste was discovered leaking from a waste transfer line in November 1954. The maximum dose rate was 4.5 rad per hour at a distance of 1.2 meters (4 feet). The liquid release covered an area of approximately 30 by 38 meters (100 by 125 feet).

Related Sites/Structures: UPR-200-W-100 is associated with the 241-TX-105 and 241-TX-108 tanks and the 241-TX Tank Farm.

Waste Type: Process Effluent

Waste Description: The release consisted of first-cycle, high-salt, neutral to basic waste containing fission products with a maximum dose rate of 4.5 rad per hour at a distance of 1.2 meters (4 feet). The waste contained approximately 10 curies of fission products.

This Site Was Consolidated With:**Code:** 200-W-94**Names:** 200-W-94; Contaminated Soil at 241-TX/TY Tank Farm**Code:** UPR-200-W-104**Classification:** Accepted**Names:** UPR-200-W-104; 216-U-10 Pond Leach Trench;
U Pond Fingers; UN-216-W-14**Reclassification:** Consolidated (1/25/2000)**Type:** Unplanned Release**Start Date:****Status:** Inactive**End Date:****Description:** The site is historically identified as an unplanned release. The site is posted with "Underground Radioactive Material" warning signs. The leach trenches were stabilized along with the 216-U-10 Pond. The AC-540 markers at the ends of the trenches are labeled 216-U-10 and URM. This site has been consolidated with the 216-U-10 Pond.**Location:** The release site runs northwest from the northeast corner of the 216-U-10 Pond.**Related Sites/ Structures:** UPR-200-W-104 was associated with the 216-U-10 Pond.**Process Description:** The trench was dug to provide additional leaching area for 216-U-10 Pond overflow water.**Waste Type:** Process Effluent**Waste Description:** A trench was dug to give additional leaching surface for overflow water from the 216-U-10 Pond. There is low-level, beta/gamma and alpha activity in the bottom of the leach trench. Contaminants of concern include cesium-137, americium-241, cerium-144 and potassium-40.**This Site Was Consolidated With:****Code:** 216-U-10**Names:** 216-U-10; 216-U-10 Pond; 231 Swamp; U Swamp; 216-U-1**Code:** UPR-200-W-105**Classification:** Accepted**Names:** UPR-200-W-105; 216-U-10 Pond Leach Trench;
UN-216-W-15**Reclassification:** Consolidated (1/25/2000)**Type:** Unplanned Release**Start Date:****Status:** Inactive**End Date:****Description:** The site is historically identified as an unplanned release. The site is posted with "Underground Radioactive Material" warning signs. The leach trenches were stabilized along with the 216-U-10 Pond. The AC-540 markers at the ends of the trenches are labeled 216-U-10 and URM. This site has been consolidated with the 216-U-10 Pond.**Location:** The trench runs directly east from the center of the east side of the 216-U-10 Pond.**Related Sites/ Structures:** UPR-200-W-105 was associated with the 216-U-10 Pond.**Process Description:** The trench was dug to provide additional leaching area for 216-U-10 Pond overflow water.**Waste Type:** Process Effluent

Waste Description: A trench was dug to provide additional leaching surface for overflow water from the 216-U-10 Pond. There is low-level, beta/gamma and alpha activity in the bottom of the leach trench. Potential contaminants of concern include cesium-137, strontium-89, strontium-90, potassium-40, and europium-154.

This Site Was Consolidated With:

Code: 216-U-10

Names: 216-U-10; 216-U-10 Pond; 231 Swamp; U Swamp; 216-U-1

Code: UPR-200-W-106 **Classification:** Accepted
Names: UPR-200-W-106; 216-U-10 Pond Leach Trench; **Reclassification** Consolidated (1/25/2000)
 UN-216-W-16
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The site is historically identified as an unplanned release. The release site is posted with "Underground Radioactive Material" warning signs. The leach trenches were stabilized along with the 216-U-10 Pond. The AC-540 markers at the ends of the trenches are labeled 216-U-10 and URM. This site has been consolidated with the 216-U-10 Pond.

Location: The trench runs east from the east side of the 216-U-10 Pond and is south of the UPR-200-W-105 Trench.

Related Sites/ Structures: UPR-200-W-106 was associated with the 216-U-10 Pond.

Process Description: The trench was dug to provide additional leaching area for 216-U-10 Pond overflow water.

Waste Type: Process Effluent

Waste Description: A leach trench was dug to provide additional leaching surface for overflow water from the 216-U-10 Pond. There is low-level, beta/gamma and alpha activity in the ground surface on the bottom of the leach trench. Potential contaminants of concern include cesium-137, strontium-89, strontium-90, and potassium-40.

This Site Was Consolidated With:

Code: 216-U-10

Names: 216-U-10; 216-U-10 Pond; 231 Swamp; U Swamp; 216-U-1

Code: UPR-200-W-107 **Classification:** Accepted
Names: UPR-200-W-107; 216-U-10 Pond Flood Plain; **Reclassification** Consolidated (1/25/2000)
 UN-216-W-17
Type: Unplanned Release **Start Date:** 1/1/1952
Status: Inactive **End Date:** 1/1/1957

Description: The site is historically identified as an unplanned release. The release site is a flood plain that was incorporated into the 216-U-10 Pond stabilization area. The pond is posted with "Underground Radioactive Material" signs. The flood plain cannot be distinguished from the backfilled pond. This site has been consolidated with the 216-U-10 Pond.

Location: The site was located south of the 216-U-10 Pond in the flood plain near the corner of 13th Street and Dayton Ave.

Related Sites/ UPR-200-W-107 was associated with the 216-U-10 Pond.

Structures:

Process Description: The flood plain was a low area that provided additional leaching area for 216-U-10 Pond overflow water.

Waste Type: Process Effluent

Waste Description: The waste water that inundated the site came from the 216-U-10 Pond which received the waste water from the 216-U-14 Ditch, the 216-Z-11 Ditch, and cooling water from the 401-SX Building condensers in the 241-SX Tank Farm. Potential contaminants of concern include cesium-137, strontium-90, and potassium-40.

This Site Was Consolidated With:

Code: 216-U-10

Names: 216-U-10; 216-U-10 Pond; 231 Swamp; U Swamp; 216-U-1

Code: UPR-200-W-123	Classification: Accepted
Names: UPR-200-W-123; 204-S Unloading Facility Frozen Discharge Line; UN-200-W-123	Reclassification: Consolidated (1/19/2005)
Type: Unplanned Release	Start Date: 1/1/1979
Status: Inactive	End Date: 1/1/1979

Description: The 204-S Unloading Station was decontaminated and dismantled in 1983. The entire 204-S/205-S area, including the dismantled railcar Unloading Station, was decommissioned and covered with clean backfill material. This Unplanned Release is not separately marked or posted. The location lies beneath the stabilization cover.

Location: UPR-200-W-123 occurred at the 204-S Unloading Station, which was located south of the 204-S Tank Farm and north of the 203-S Basin, in the 200 West Area.

Release Description: On January 18, 1979, the 204-S Unloading Station received railroad tank car number 18579 from the 300 Area with a total load of 73,050 liters (19,300 gallons) of radioactive liquid waste. Operators connected to the tank car and made three attempts to prime the car. During the third attempt, the pressure relief valve actuated, releasing a small amount of material into the plastic containment and then leaking down the side of the car onto the ground. The apparent cause for the occurrence was a frozen discharge line below the primer tank.

Related Sites/ UPR-200-W-123 is associated with the 204-S Unloading Facility Area and 200-W-22.

Structures:

Waste Type: Chemicals

Waste Description: The release consisted of radioactive liquid waste from the 300 Area.

This Site Was Consolidated With:

Code: 200-W-22

Names: 200-W-22; 203-S/204-S/205-S Stabilized Area

Code: UPR-200-W-125	Classification: Accepted
Names: UPR-200-W-125; 216-U-15; UN-200-W-125; UN-216-W-10	Reclassification: Consolidated (1/25/2000)

Type: Trench **Start Date:** 1/1/1956

Status: Inactive **End Date:**

Description: WIDS site UPR-200-W-125 has been reclassified based on documentation that verified it was a DUPLICATE of 216-U-15. Future updates and closeout information will only be added to 216-U-15. This site will no longer be updated. The site was a one-time use waste disposal unit. A hole was dug in the ground and the material dumped and covered. Contamination was limited to a hole in the ground (which included interface crud, activated charcoal, and diatomaceous earth) near U Plant.

Location: The site is located in the 200 West Area, west of 221-U.

Release Description: The site resulted from a leak in the transfer line from the 200-U Tank (388-U Tank). This statement appeared in the original WIDS files, it is not traceable to a reference.

Related Sites/ Structures: This is a Duplicate record of 216-U-15.

Waste Type: Process Effluent

Waste Description: The waste was 26,500 liters (7000 gallons) of interface crud, activated charcoal, and diatomaceous earth, containing about one curie of fission products.

This Site Was Consolidated With:

Code: 216-U-15

Names: 216-U-15; 388-U Tank Dumping; U-152 Interface Crud Burial; UN-200-W-158; UN-216-W-10; UPR-200-W-125

Code: UPR-200-W-126 **Classification:** Accepted

Names: UPR-200-W-126; Contamination Release Inside 241-TX Tank Farm **Reclassification:** Consolidated (6/13/2002)

Type: Unplanned Release **Start Date:** 1/1/1975

Status: Inactive **End Date:** 1/1/1975

Description: The tank farm that is surrounded by a chain link fence and is posted with radiological warning signs, including Underground Radioactive Material, Radiation Area, Fixed Contamination Area, Radiological Buffer Area and Radioactive Material Area. The release site is not separately marked or posted.

Location: UPR-200-W-126 occurred at the 241-TX-153 Diversion Box, inside the 241-TX Tank Farm, southeast of the 241-TX-101 Tank.

Release Description: While removing old gaskets on an over-ground transfer line from the 241-TX-153 Diversion Box to the 241-TX-101 Tank, a pipe fitter and an operator became contaminated. As the gaskets were being placed into a plastic bag, spotty contamination became airborne. Both employees had approximately 2000 counts per minute on their faces.

Related Sites/ Structures: UPR-200-W-126 is associated with the 241-TX-153 Diversion Box and the 241-TX-101 Tank.

Waste Type: Process Effluent

Waste Description: Spotty contamination became airborne. The employee received contamination levels reading up to 2,000 counts per minute.

This Site Was Consolidated With:

Waste Type: Process Effluent

Waste Description: The release consisted of liquid waste contaminated with fission products.

This Site Was Consolidated With:

Code: 200-W-95

Names: 200-W-95; Contaminated Soil at 241-U Tank Farm; Contamination Migration Beyond the 241-U fence

Code: UPR-200-W-129

Classification: Accepted

Names: UPR-200-W-129; Contamination Release Inside 241-TX Tank Farm

Reclassification: Consolidated (6/13/2002)

Type: Unplanned Release

Start Date: 1/1/1971

Status: Inactive

End Date: 1/1/1971

Description: The personnel contamination incident release occurred inside the fenced 241-TX Tank Farm. The release site is not separately marked or posted.

Location: UPR-200-W-129 occurred at the 241-TX-113 Pump Pit, located inside the 241-TX Tank Farm.

Release Description: While leak testing a new jumper assembly, an employee closed a valve in a pump pit that caused a caustic solution to spray up through the pit cover. The employee's chin and left forearm were contaminated with radiation levels up to 30,000 counts per minute.

Related Sites/Structures: UPR-200-W-129 is associated with the 241-TX Tank Farm and the 241-TX-113 Tank Pump Pit.

Waste Type: Process Effluent

Waste Description: The waste was a caustic radioactive solution. The contamination on the employee had readings up to 30,000 counts per minute.

This Site Was Consolidated With:

Code: 200-W-94

Names: 200-W-94; Contaminated Soil at 241-TX/TY Tank Farm

Code: UPR-200-W-132

Classification: Accepted

Names: UPR-200-W-132; 241-UR-151 Diversion Box Release; UN-200-W-132

Reclassification: Consolidated (6/3/2002)

Type: Unplanned Release

Start Date: 1/1/1956

Status: Inactive

End Date: 1/1/1956

Description: The release occurred inside the fenced 241-U Tank Farm. The area around the 241-UR-151 Diversion Box has been covered with shotcrete. The release is not separately marked or posted.

Location: UPR-200-W-132 occurred inside the 241-U Tank Farm, near the 241-UR-151 Diversion Box and the 254-UR Electrical Substation (adjacent to the 271-U Control Building).

Release Description: An operator working inside the 271-UR Control Building noticed an elevated background reading and an off scale reading on the panel board. He notified his supervisor, shut down operating equipment and evacuated the building. While leaving, he and a co-worker noticed a gurgling sound and observed two pools of liquid forming around the 241-UR-151 Diversion

Box. One pool was approximately 1.8 meters by 6 meters (6 by 20 feet), the other was approximately 4.5 meters by 9 meters (15 by 30 feet). Dose rates taken from 3 meters (10 feet) away from the pools measured up to 10 rad per hour beta/gamma and 500 millirem per hour gamma.

Related Sites/ Structures: UPR-200-W-132 is associated with the 241-UR-151 Diversion Box, the 254-UR Electrical Substation, and the 241-U Tank Farm.

Waste Type: Process Effluent

Waste Description: The waste was feed solution for the tributyl phosphate uranium recovery process.

This Site Was Consolidated With:

Code: 200-W-95

Names: 200-W-95; Contaminated Soil at 241-U Tank Farm; Contamination Migration Beyond the 241-U fence

Code: UPR-200-W-134

Classification: Accepted

Names: UPR-200-W-134; Improper Drum Burial at 218-W-3A

Reclassification: Rejected (6/30/2004)

Type: Unplanned Release

Start Date: 1/1/1975

Status: Inactive

End Date: 1/1/1975

Description: The improper burial of a drum containing transuranic material occurred was at the 218-W-3A Burial Ground. The burial trench has been covered with clean soil. This Unplanned Release site is not separately marked or posted.

Location: UPR-200-W-134 occurred at the 218-W-3A Burial Ground, in the 200 West Area.

Release Description: A waste drum from the 325 building, labeled TRANSURANIC, was improperly buried and documented on Occurrence Report 38-75. It contained 18.6 grams of plutonium, 2466 grams of uranium and a total of 53 grams of fissile material. The handling and storage of this material did not meet applicable standards. The drum was dumped into the burial trench and covered with several other loads of radioactive waste and approximately 2.4 meters (8 feet) of dirt.

Related Sites/ Structures: UPR-200-W-134 was associated with the 218-W-3A Burial Ground.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: The transuranic waste in the drum contained 18.6 grams of plutonium, 2466 grams of uranium and a total of 53 grams (2 ounces) of fissile material.

This Site Was Consolidated With:

Code: 218-W-3A

Names: 218-W-3A; Dry Waste No. 003A

Code: UPR-200-W-137

Classification: Accepted

Names: UPR-200-W-137; 218-W-7; UN-200-W-137

Reclassification: Consolidated (4/12/2004)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: A vent from the vault is visible above the ground surface; the rest of the site is graveled and surrounded by yellow metal poles and a chain to mark the radiation zone.

Location: The site is located in the 200 West Area. It is in a vault east of the 222-S Building.

Process Description: The site received dry, packaged laboratory and sampler wastes from the 222-S Building.

This Site Was Consolidated With:

Code: 218-W-7

Names: 218-W-7; 222-S Vault

Code: UPR-200-W-139	Classification: Accepted
Names: UPR-200-W-139; UPR-200-W-18; Liquid Release to the 216-U-9 Ditch; UN-200-W-139	Reclassification: Consolidated (1/25/2000)
Type: Unplanned Release	Start Date: 1/1/1953
Status: Inactive	End Date: 1/1/1954

Description: WIDS site UPR-200-W-139 was located within the boundary of the larger site of 216-U-9 Ditch and has been consolidated into that site. Future updates and closeout information will only be added to 216-U-9 Ditch. This site will no longer be updated. The site was an unplanned release into the eastern fork of the 216-U-9 Ditch. The eastern fork of the 216-U-9 Ditch was abandoned in 1954. Currently, the eastern fork of the ditch is not marked or posted. It has no chain barricades or radiation warning signs and is partially backfilled. There are no permanent monuments or other identifiers at the site. The head end of the 216-U-9 Ditch, beginning south of 13th Street, is still an open, dry ditch. There is mature sage brush growing on the side slopes of the open ditch.

Location: UPR-200-W-139 occurred within the eastern fork of the 216-U-9 Ditch. The ditch lies southwest of the 241-SX Tank Farm, outside of the 200 West Area perimeter fence.

Release Description: Contamination from an unknown source was detected in the 216-U-9 Ditch in September 1953. In the spring of 1954, the contamination was covered with 0.6 meters (2 feet) of clean soil. It was designated as a radiation zone and posted with Underground Radioactive Material signs. No mention is found in the records regarding the level of contamination.

Related Sites/Structures: UPR-200-W-139 was associated with the 216-U-9 Ditch.

Process Description: The 216-U-9 Ditch received overflow from the 216-U-10 Pond. The release site was within the eastern fork of the 216-U-9 Ditch. The ditch connected the 216-U-10 Pond with the 216-S-17 Pond. The 216-U-9 Ditch was released from radiation zone status in 1969. In 1973, a portion of the 216-U-9 Ditch was reopened and reused to connect the 216-U-10 Pond overflow to the 216-S-16 Pond. The first 152.50 meters (500 feet) of the original 216-U-9 Ditch were reused.

Waste Type: Process Effluent

Waste Description: References state the ditch became contaminated in September of 1953 and was backfilled in spring of 1954. No details of the release are included.

This Site Was Consolidated With:

Code: 216-U-9

Names: 216-U-9; U Swamp-S Swamp Ditch; 216-U-6

Code: UPR-200-W-140	Classification: Accepted
----------------------------	---------------------------------

Names: UPR-200-W-140; 241-SX-107 Leak **Reclassification** Consolidated (6/13/2002)

Type: Unplanned Release **Start Date:** 1/1/1956

Status: Inactive **End Date:** 1/1/1964

Description: The release is the soil beneath the 241-SX-107 Tank. The release is not separately marked or posted.

Location: The release occurred beneath the 241-SX-107 Tank, inside the 241-SX Tank Farm.

Release Description: UPR-200-W-140 occurred over time, as high-level waste leaked into the soil beneath the 241-SX-107 Tank. The waste spread in a geologic strata 17 to 18 meters (55 to 60 feet) below ground surface.

Related Sites/ Structures: UPR-200-W-140 is associated with the 241-SX-107 Tank and the 241-SX Tank Farm.

Waste Type: Process Effluent

Waste Description: The release consisted of REDOX high-level wastes and REDOX coating wastes.

This Site Was Consolidated With:

Code: 200-W-96

Names: 200-W-96; Contaminated Soil at 241-S/SX/SY Tank Farm

Code: UPR-200-W-141 **Classification:** Accepted

Names: UPR-200-W-141; 241-SX-108 Leak **Reclassification** Consolidated (6/13/2002)

Type: Unplanned Release **Start Date:** 1/1/1962

Status: Inactive **End Date:** 1/1/1962

Description: The release is the soil under the 241-SX-108 Tank. The release is not separately marked or posted.

Location: UPR-200-W-141 occurred in the soil underneath and adjacent to the 241-SX-108 Tank, inside the 241-SX Tank Farm.

Release Description: UPR-200-W-141 occurred over time, as REDOX supernatant waste leaked from the 241-SX-108 Tank.

Related Sites/ Structures: UPR-200-W-141 is associated with the 241-SX-108 Tank.

Waste Type: Process Effluent

Waste Description: The release consisted of REDOX waste containing 2,000 curies of cesium-137.

This Site Was Consolidated With:

Code: 200-W-96

Names: 200-W-96; Contaminated Soil at 241-S/SX/SY Tank Farm

Code: UPR-200-W-142 **Classification:** Accepted

Names: UPR-200-W-142; 241-SX-109 Leak **Reclassification** Consolidated (6/13/2002)

Type: Unplanned Release **Start Date:** 1/1/1955

Status: Inactive **End Date:** 1/1/1965

Description: The release is the soil under the 241-SX-109 Tank. The release is not separately marked or posted.

Location: UPR-200-W-142 occurred in the soil beneath the 241-SX-109 Tank, inside the 241-SX Tank Farm.

Release Description: UPR-200-W-142 occurred over time, as approximately 18,900 liters (5,000 gallons) of REDOX process waste leaked from the 241-SX-109 Tank.

Related Sites/ Structures: UPR-200-W-142 was associated with the 241-SX-109 Tank.

Waste Type: Process Effluent

Waste Description: The release consisted of REDOX high-level process waste.

This Site Was Consolidated With:

Code: 200-W-96

Names: 200-W-96; Contaminated Soil at 241-S/SX/SY Tank Farm

Code: UPR-200-W-143 **Classification:** Accepted

Names: UPR-200-W-143; 241-SX-111 Leak **Reclassification** Consolidated (6/13/2002)

Type: Unplanned Release **Start Date:** 1/1/1958

Status: Inactive **End Date:** 1/1/1974

Description: The release site is the soil below the 241-SX-111 Tank. The release is not separately marked or posted.

Location: UPR-200-W-143 occurred in the soil below the 241-SX-111 Tank, inside the 241-SX Tank Farm.

Release Description: UPR-200-W-143 occurred over time as liquid level changes in the 241-SX-111 Tank were noted. Liquid was removed from the tank in 1974.

Related Sites/ Structures: UPR-200-W-143 is associated with the 241-SX-111 Tank.

Waste Type: Process Effluent

Waste Description: The release consisted of REDOX high-level waste supernate and ion exchange waste from 241-SX Tanks.

This Site Was Consolidated With:

Code: 200-W-96

Names: 200-W-96; Contaminated Soil at 241-S/SX/SY Tank Farm

Code: UPR-200-W-144 **Classification:** Accepted

Names: UPR-200-W-144; 241-SX-112 Leak **Reclassification** Consolidated (6/13/2002)

Type: Unplanned Release **Start Date:** 1/1/1959

Status: Inactive **End Date:** 1/1/1969

Description: The release is soil under the 241-SX-112 Tank. The release is not separately marked or posted.

Location: UPR-200-W-144 occurred in the soil underneath and adjacent to the 241-SX-112 Tank, inside the 241-SX Tank Farm.

Release Description: UPR-200-W-144 occurred over time as the 241-SX-112 Tank leaked approximately 114,000 liters (30,000 gallons) of REDOX high-level supernate into the soil.

Related Sites/ Structures: UPR-200-W-144 is associated with the 241-SX-112 Tank.

Waste Type: Process Effluent

Waste Description: The release consisted of REDOX high-level supernate, containing 40,000 curies of cesium-137.

This Site Was Consolidated With:

Code: 200-W-96

Names: 200-W-96; Contaminated Soil at 241-S/SX/SY Tank Farm

Code: UPR-200-W-145

Classification: Accepted

Names: UPR-200-W-145; 241-SX-113 Leak

Reclassification: Consolidated (6/13/2002)

Type: Unplanned Release

Start Date: 1/1/1956

Status: Inactive

End Date: 1/1/1958

Description: The release is the soil under the 241-SX-113 Tank. The release is not separately marked or posted.

Location: UPR-200-W-145 is located in the soil under and adjacent to the 241-SX-113 Tank, inside the 241-SX Tank Farm.

Release Description: The release occurred over time, as 56,800 liters (15,000 gallons) of REDOX high-level liquid process waste leaked from the 241-SX-113 Tank into the soil.

Related Sites/ Structures: UPR-200-W-145 is associated with the 241-SX-113 Tank.

Waste Type: Process Effluent

Waste Description: The waste consisted of REDOX high-level process waste, containing 8,000 curies of cesium-137.

This Site Was Consolidated With:

Code: 200-W-96

Names: 200-W-96; Contaminated Soil at 241-S/SX/SY Tank Farm

Code: UPR-200-W-146

Classification: Accepted

Names: UPR-200-W-146; 241-SX-115 Leak

Reclassification: Consolidated (6/13/2002)

Type: Unplanned Release

Start Date: 1/1/1958

Status: Inactive

End Date: 1/1/1965

Description: The release is the soil under the 241-SX-115 Tank. The release is not separately marked or posted.

Location: UPR-200-W-146 occurred in the soil under and adjacent to the 241-SX-115 Tank, inside the

241-SX Tank Farm.

Release Description: UPR-200-W-146 occurred over time as 189,000 liters (50,000 gallons) of REDOX high-level liquid process waste leaked from the 241-SX-115 Tank into the surrounding soil.

Related Sites/ Structures: UPR-200-W-146 is associated with the 241-SX-115 Tank.

Waste Type: Process Effluent

Waste Description: The release consisted of high-level REDOX process waste, containing 40,000 curies (1.5E15) of cesium-137.

This Site Was Consolidated With:

Code: 200-W-96

Names: 200-W-96; Contaminated Soil at 241-S/SX/SY Tank Farm

Code: UPR-200-W-147

Classification: Accepted

Names: UPR-200-W-147; 241-T-103 Leak

Reclassification: Consolidated (6/13/2002)

Type: Unplanned Release

Start Date: 1/1/1973

Status: Inactive

End Date:

Description: The release is the soil under the 241-T-103 Tank. It is not separately marked or posted.

Location: The release is located southeast of the 241-T-103 Tank, inside the 241-T Tank Farm.

Release Description: In 1973, while monitoring wells were being drilled to assess the 241-T-106 tank leak, contamination was identified between monitoring wells 299-W10-116 and 299-W10-118. This contamination plume was determined to be from the 241-T-103 Tank. Subsequent investigations revealed that the leak resulted from a failed grout seal in a spare entry line to 241-T-103.

Related Sites/ Structures: UPR-200-W-147 is associated with the 241-T-103 Tank.

Waste Type: Process Effluent

Waste Description: In 1973, the release contained 1 microcurie/liter of ruthenium.

This Site Was Consolidated With:

Code: 200-W-93

Names: 200-W-93; Contaminated Soil at 241-T Tank Farm

Code: UPR-200-W-148

Classification: Accepted

Names: UPR-200-W-148; 241-T-106 Leak

Reclassification: Consolidated (6/13/2002)

Type: Unplanned Release

Start Date: 1/1/1973

Status: Inactive

End Date: 1/1/1973

Description: The release is the soil underneath and adjacent to the 241-T-106 Tank. The release is not separately marked or posted.

Location: The release is a contaminated soil plume located adjacent to the 241-T-106 tank, inside the 241-T Tank Farm.

Release Description: The release occurred during a routine tank filling operation. From January 1973 to April 4, 1973, the liquid level in 241-T-106 was stable at 61 centimeters (24 inches). On April 4, 1973, the contents of tank 241-T-107 began being transferred to 241-T-106. Liquid level readings were taken three times per shift during the transfer operations. When the pumping operation stopped on April 24, 1973, the liquid level reading was 445.5 centimeters (175.4 inches). Due to the tank cascading effect, the liquid level continued to rise after the pumping ended, with a maximum liquid level of 466.5 centimeters (183.7 inches) being recorded on April 25, 1973. The first routine, weekly liquid level measurement was taken on May 2, 1973 and recorded a level of 454.4 centimeters (178.9 inches). The liquid level was entered into the logbook. A week later, the routine measurement was recorded in the logbook at 442 centimeters (174 inches). On May 14, 1973 the weekly liquid level of 426.4 centimeters (167.9 inches) was recorded in the logbook. The shift supervisor did not review the logbook but did prepare a Tank Inventory Form and transmit it to the Process Control Group. Because Tank Inventory forms for the previous two weeks were missing, they could only compare the liquid level to the last form transmitted, which was for April 23, 1973 with a liquid level of 389.9 centimeters (153.5 inches), taken during the pumping operations. The missing data caused the diminishing tank levels to go unnoticed. By June 1, 1973, high readings were being identified in dry well 299-W10-51 and the routine weekly liquid level for June 4th was down to 378.9 centimeters (149.2 inches). On June 7, 1973 the tank data was reviewed and determined to be leaking. Emergency plans were made to pump the remaining liquid out of tank 241-T-106.

Related Sites/Structures: UPR-200-W-148 is associated with the 241-T-106 Tank and the 241-T Tank Farm.

Process Description: This release occurred while waste was being transferred from the 241-T-107 tank to 241-T-106 tank (which is the last tank in the T-104, T-105, T-106 cascading tank series). Since 241-T-104 contained a large amount of solid salt cake, the waste was pumped from 241-T-107 to 241-T-105, which overflowed into 241-T-106.

Waste Type: Process Effluent

Waste Description: At the time the release occurred, the tank contained waste with approximately 40,000 curies of cesium-137, 14,000 curies of strontium-90, 4 curies of plutonium, and various fission products.

This Site Was Consolidated With:

Code: 200-W-93

Names: 200-W-93; Contaminated Soil at 241-T Tank Farm

Code: UPR-200-W-149	Classification: Accepted
Names: UPR-200-W-149; 241-TX-107 Leak	Reclassification: Consolidated (6/13/2002)
Type: Unplanned Release	Start Date: 1/1/1977
Status: Inactive	End Date: 1/1/1977

Description: The release is the soil adjacent to the 241-TX-107 Tank. The release is not separately marked or posted.

Location: The release is located in the soil south of the 241-TX-107 Tank, inside the 241-TX-Tank Farm.

Release Description: Elevated radiation readings were recorded in dry wells 51-07-01, 51-03-12, 51-03-11, 51-07-18 and 51-03-01 during 1977 resulting in several Occurrence Reports to be issued. After extensive studies it was concluded that the source of the high-level activity detected in dry well 51-07-18 may have been liquid from the 241-TX-107 Tank.

Related Sites/Structures: UPR-200-W-149 is associated with the 241-TX-107 Tank and Dry Well 51-07-18.

Waste Type: Process Effluent

Waste Description: Assuming the waste came from 241-TX-107, the release would contain bismuth phosphate metal waste, REDOX high-level waste, and evaporator bottoms from the 242-T Evaporator.

This Site Was Consolidated With:

Code: 200-W-94

Names: 200-W-94; Contaminated Soil at 241-TX/TY Tank Farm

Code: UPR-200-W-150

Classification: Accepted

Names: UPR-200-W-150; 241-TY-103 Leak

Reclassification: Consolidated (6/13/2002)

Type: Unplanned Release

Start Date: 1/1/1953

Status: Inactive

End Date: 1/1/1973

Description: The release is the soil adjacent to the 241-TY-103 Tank. The release is not separately marked or posted.

Location: The release is located in the soil under and adjacent to the 241-TY-103 Tank, inside the 241-TY Tank Farm.

Release Description: In 1973, dry wells 52-03-06 and 52-03-03 recorded increases in radiation levels, indicating leakage from the 241-TY-103 Tank or the 241-TY-105 Tank. The exact date the leak began is difficult to determine.

Related Sites/ Structures: UPR-200-W-150 is associated with the 241-TY-103 Tank and the 52-03-06 and 52-03-03 Dry Wells.

Waste Type: Process Effluent

Waste Description: The waste contained in tanks 241-TY-103 and 241-TY-105 included 700 curies of cesium-137 from bismuth phosphate process waste, PUREX organic wash waste, REDOX ion exchange waste, coating waste and evaporator bottoms.

This Site Was Consolidated With:

Code: 200-W-94

Names: 200-W-94; Contaminated Soil at 241-TX/TY Tank Farm

Code: UPR-200-W-151

Classification: Accepted

Names: UPR-200-W-151; 241-TY-104 Leak

Reclassification: Consolidated (6/13/2002)

Type: Unplanned Release

Start Date: 1/1/1953

Status: Inactive

End Date: 1/1/1974

Description: The release site is the soil adjacent to the 241-TY-104 Tank. The release is not separately marked or posted.

Location: UPR-200-W-151 occurred in the soil under the 241-TY-104 Tank, inside the 241-TY Tank Farm.

Release Description: In 1974, the liquid level of the tank decreased more than 0.3 inch (0.77 centimeter), causing the integrity of the 241-TY-104 Tank to be questioned and the tank to become inactive. The leak has occurred over time with routine tank use.

Related Sites/ Structures: UPR-200-W-151 is associated with the 241-TY-104 Tank.

Waste Type: Process Effluent

Waste Description: The tank contained REDOX ion exchange waste, PUREX organic wash waste, bismuth phosphate first-cycle waste, tributyl phosphate waste, and decontamination waste from the 241-TX and the 241-TY Tank Farms.

This Site Was Consolidated With:

Code: 200-W-94

Names: 200-W-94; Contaminated Soil at 241-TX/TY Tank Farm

Code: UPR-200-W-152

Classification: Accepted

Names: UPR-200-W-152; 241-TY-105 Leak

Reclassification: Consolidated (6/13/2002)

Type: Unplanned Release

Start Date: 1/1/1960

Status: Inactive

End Date: 1/1/1960

Description: The release is the soil adjacent to the 241-TY-105 Tank. The release is not separately marked or posted.

Location: UPR-200-W-152 occurred in the soil under the 241-TY-105 Tank, inside the 241-TY Tank Farm.

Release Description: Two dry wells, 52-03-05 and 52-03-06 showed slowing increasing radiological readings in 1974. The activity in these dry wells may be an indication of interstitial liquid seepage from the 241-TY-105 Tank. Occurrence Reports 74-101 and 74-102 were issued in June 1974 to document the findings.

Related Sites/ Structures: UPR-200-W-152 was associated with the 241-TY-105 Tank.

Waste Type: Process Effluent

Waste Description: The release consisted of tributyl phosphate containing 4,000 curies of cesium-137.

This Site Was Consolidated With:

Code: 200-W-94

Names: 200-W-94; Contaminated Soil at 241-TX/TY Tank Farm

Code: UPR-200-W-153

Classification: Accepted

Names: UPR-200-W-153; 241-TY-106 Leak

Reclassification: Consolidated (6/13/2002)

Type: Unplanned Release

Start Date: 1/1/1953

Status: Inactive

End Date: 1/1/1959

Description: The release is not separately marked or posted.

Location: The release is the soil under the 241-TY-106 Tank, inside the 241-TY Tank Farm.

Release Description: Routine surveillance of Dry Well 52-06-05, in 1974, showed a slow increase in radioactivity over a six month span, indicating interstitial liquids were seeping from tanks 241-TY-106 or 241-TY-105. The release occurred over time, from routine tank use. Occurrence Report 74-88 was issued to document the findings.

Related Sites/ Structures: The release is associated with the 241-TY Tank Farm and tank 241-TY-106.

Waste Type: Process Effluent

Waste Description: The release consisted of tributyl phosphate process waste.

This Site Was Consolidated With:

Code: 200-W-94

Names: 200-W-94; Contaminated Soil at 241-TX/TY Tank Farm

Code: UPR-200-W-154

Classification: Accepted

Names: UPR-200-W-154; 241-U-101 Leak

Reclassification: Consolidated (6/13/2002)

Type: Unplanned Release

Start Date: 1/1/1946

Status: Inactive

End Date: 1/1/1959

Description: The release is the soil under and adjacent to the 241-U-101 Tank. The release is not separately marked or posted.

Location: UPR-200-W-154 occurred in the soil adjacent to the 241-U-101 Tank, inside the 241-U Tank Farm.

Release Description: UPR-200-W-154 occurred over time, as approximately 114,000 liters (30,000 gallons) of bismuth phosphate metal waste and supernatant containing high-level waste, leaked from the 241-U-101 Tank, until it was declared to be leaking and removed from service in 1959.

Related Sites/ Structures: UPR-200-W-154 is associated with the 241-U-101 Tank.

Waste Type: Chemicals

Waste Description: The release consisted of bismuth phosphate metal waste and high-level supernatant waste, containing 20,000 curies of cesium-137.

This Site Was Consolidated With:

Code: 200-W-95

Names: 200-W-95; Contaminated Soil at 241-U Tank Farm; Contamination Migration Beyond the 241-U fence

Code: UPR-200-W-155

Classification: Accepted

Names: UPR-200-W-155; 241-U-104 Leak

Reclassification: Consolidated (6/13/2002)

Type: Unplanned Release

Start Date: 1/1/1947

Status: Inactive

End Date: 1/1/1951

Description: The site is the soil under the 241-U-104 Tank. It is not separately marked or posted.

Location: The release site is soil under the 241-U-104 Tank, inside the 241-U Tank Farm.

Release Description: A rupture in the bottom of the tank was first detected in 1956, while attempting to install a heel jet pump. The installation could not be accomplished.

Related Sites/ Structures: UPR-200-W-155 is associated with the 241-U-104 Tank.

Waste Type: Chemicals

Waste Description: From 1947 to 1956, the tank held bismuth phosphate metal waste.

This Site Was Consolidated With:

Code: 200-W-95

Names: 200-W-95; Contaminated Soil at 241-U Tank Farm; Contamination Migration Beyond the 241-U fence

Code: UPR-200-W-156

Classification: Accepted

Names: UPR-200-W-156; 241-U-110 Leak

Reclassification: Consolidated (6/13/2002)

Type: Unplanned Release

Start Date: 1/1/1946

Status: Inactive

End Date: 1/1/1975

Description: The tank farm is surrounded with a chain line fence and posted with radiological warning signs. The release is not separately marked or posted.

Location: The release is the soil adjacent to and underneath the 241-U-110 Tank, inside the 241-U Tank Farm.

Release Description: The tank release occurred over time. In 1975, surveillance of the 241-U-110 Tank indicated a slow drop in the liquid level. Over one month, the liquid level had dropped 0.5 inches (1.3 centimeters).

Related Sites/ Structures: UPR-200-W-156 is associated with Dry Well 60-10-07 and the 241-U-110 Tank.

Waste Type: Process Effluent

Waste Description: The release consisted of bismuth phosphate first-cycle waste and REDOX coating.

This Site Was Consolidated With:

Code: 200-W-95

Names: 200-W-95; Contaminated Soil at 241-U Tank Farm; Contamination Migration Beyond the 241-U fence

Code: UPR-200-W-157

Classification: Accepted

Names: UPR-200-W-157; 241-U-112 Leak

Reclassification: Consolidated (6/13/2002)

Type: Unplanned Release

Start Date: 1/1/1969

Status: Inactive

End Date: 1/1/1969

Description: The 241-U Tank Farm is surrounded by a chain link fence and posted with radiological warning signs. The release is not separately marked or posted.

Location: UPR-200-W-157 is the soil adjacent to and underneath the 241-U-112 Tank, located inside the 241-U Tank Farm.

Release Description: The release occurred over time. Approximately 37,850 liters (10,000 gallons) of waste leaked into the soil from the 241-U-112 Tank.

Related Sites/ Structures: UPR-200-W-157 is associated with the 241-U-112 Tank.

Waste Type: Process Effluent

Waste Description: The release consisted of bismuth phosphate first-cycle waste and recycled waste from 241-U Tanks.

This Site Was Consolidated With:

Code: 200-W-95

Names: 200-W-95; Contaminated Soil at 241-U Tank Farm; Contamination Migration Beyond the 241-U fence

Code: UPR-200-W-159

Classification: Accepted

Names: UPR-200-W-159; Caustic Spill at Plutonium Finishing Plant; UN-200-W-159

Reclassification: Rejected (7/28/2008)

Type: Unplanned Release

Start Date: 1/1/1985

Status: Inactive

End Date: 1/1/1985

Description: The release site was the soil adjacent to the Plutonium Finishing Plant. The soil that was contaminated with sodium hydroxide was disposed of as hazardous waste. The site is not marked or posted.

Location: UPR-200-W-159 occurred in the soil adjacent to the Plutonium Finishing Plant, inside the facility security fence.

Release Description: UPR-200-W-159 occurred when an unknown amount of 50% aqueous sodium hydroxide, a corrosive liquid, was spilled to ground near the Plutonium Finishing Plant.

Related Sites/ Structures: UPR-200-W-159 was associated with the Plutonium Finishing Plant.

Waste Type: Chemicals

Waste Description: The release consisted of an unknown amount of 50% aqueous sodium hydroxide.

Code: UPR-200-W-160

Classification: Not Accepted

Names: UPR-200-W-160; UPR-200-W-38; UPR-200-W-40; 216-T-30; Line Break at 241-TX-302C

Reclassification: None

Type: Unplanned Release

Start Date: 1/1/1955

Status: Inactive

End Date: 1/1/1955

Description: The area around the 241-TX-154 Diversion Box has been stabilized with shotcrete. This UPR is a duplicate of UPR-200-W-40 and UPR-200-W-38. UPR-200-W-38 is the site that will remain.

Location: The release location is the area around the 241-TX-154 Diversion Box and the 241-TX-302 Catch Tank, and between the 221-T Building and the 222-T Building, near section R-11 of 221-T.

Release Description: The release consisted of highly radioactive liquid waste due to failure of an underground line during a waste transfer from the 241-TX-302C Catch Tank. A pool of liquid waste with a high dose rate was identified on the surface near the 241-TX-302 Catch Tank (December 30, 1955). It was estimated that several thousand gallons of "metal" waste and rain water had been released to the ground. The area was backfilled, sprayed with tar, and posted as a radiation zone in 1956. During April and May 1968, the east side of the radiation zone was cut back a distance of 10 ft (3.0 m). Thin concrete cell cover blocks were leaned at a 60-degree angle

against the side of the cut to shield the dose rates to acceptable levels.

Waste Type: Process Effluent

Waste Description: Several thousand gallons of primarily metal waste and rainwater. RHO-CD-673 estimated 19,000 liters (5026 gallons). Other reference documents estimated 7520 liters (2000 gallons). The waste was high in salt and is neutral to basic. Dose rates up to 100 rad per hour were recorded at a distance of 0.3 meters (1 foot) from the release pool.

This Site Was Consolidated With:

Code: UPR-200-W-38

Names: UPR-200-W-38; UPR-200-W-40; 216-T-30; Line Break at 241-TX-302C; UN-200-W-38; UPR-200-W-160

Code: UPR-200-W-163

Classification: Accepted

Names: UPR-200-W-163; Contaminated Vegetation at the 216-U-8 Pipeline (200-W-42-PL); UN-216-W-33

Reclassification: Consolidated (5/14/2004)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The release consisted of radiologically contaminated vegetation growing above the underground pipeline to the 216-U-8 crib (the pipeline is sitecode 200-W-42). The area is currently posted with Underground Radioactive Material signs.

The 200-W-42 pipeline is the source of this unplanned release. The remediation of the pipeline will include the soil above it. This UPR was consolidated into 200-W-42. A large portion of the pipeline and contaminated soil was removed in 2006.

Location: The release site is located in the soil above the pipeline from the 224-U building to the 216-U-8 Crib. Posted Underground Radioactive Material areas are located on the north and south sides of 16th Street. The pipeline is west of Beloit Ave.

Release Description: UPR-200-W-163 occurred over time, as leaking waste from the underground pipeline contaminated the soil. Growing vegetation absorbed some of the radioactive contaminants. Broken pieces of contaminated vegetation scattered in the wind and caused the size of the surface posted contamination area to be increased.

Related Sites/Structures: UPR-200-W-163 is associated with the vitrified clay pipeline (200-W-42-PL) connecting the 216-U-8 Crib to the 224-U Building. The posted area over the pipeline on the north side of 16th Street was stabilized in October 2001.

Process Description: The vitrified clay underground pipeline transferred U Plant waste to the 216-U-8 crib.

Waste Type: Process Effluent

Waste Description: The waste in the pipeline consisted of process condensate from the 224-U Building. The waste was acidic.

This Site Was Consolidated With:

Code: 200-W-42

Names: 200-W-42; 200-W-42-PL; U Plant Radioactive Process Sewer from 221-U to 216-U-8 & 216-U-12 Cribs

Code: UPR-300-7	Classification: Accepted
Names: UPR-300-7; Oil Spill at 384 Building; UN-300-7	Reclassification: Closed Out (8/24/1999)
Type: Unplanned Release	Start Date: 1/1/1972
Status: Inactive	End Date: 1/1/1972

Description: The waste site was an oil release the ground and concrete valve pits around the underground day tanks located behind the 384 Building (300 Area Powerhouse). The area is paved with asphalt. There was no visual evidence of a spill. Most of the spilled oil was contained in the underground, concrete pits that surround the day tanks.

This site was closed out in conjunction with the North Process Pond.

Location: The release occurred on the north side of the 384 Powerhouse, adjacent to the day tanks, but a portion of the spill was sent to the North Process Pond. The day tanks and adjacent oil-contaminated soil have been removed (see site code 300-223).

Release Description: According to the incident report, the release was discovered at 6:45 am on August 7, 1972. There are two 60,560 liter (16,000 gallon), underground day tanks on the north side of the 384 Powerhouse. At the time of the release, one day tank was full and one day tank was empty. The operator was instructed to fill the empty tank, but failed to close the valve on the full tank and open the valve to the empty tank. Approximately 3,220 liters (850 gallons) of #6 fuel oil overflowed from the full day tank when the oil was transferred from the storage bunker. The spilled oil was retained in the concrete valve pits around the day tanks and in the soil between and around these two adjacent tanks. However, approximately 114 liters (30 gallons) of the total oil spilled flowed into the 384 Building drain trench through conduits constructed to carry oil pipes through the building foundation to the trench. This oil mixed with waste water and emptied into a sewer system that terminates in a sump located in the southeast corner of the basement of the 384 Building. A heavy scum of oil was observed on the surface of the sump. A sump pump normally lifted the water from the basement to the process sewer which flows to the north process pond (WIDS Site 316-2). Since the pump suction was at the bottom of the sump, an immediate check was made of the process pond. A significant scum of oil was visible in the fore bay of the first holding section of the pond. An estimated 38 liters (10 gallons) of oil was observed floating on the process pond.

Related Sites/Structures: UPR-300-7 was associated with the day tanks (WIDS Site 300-223) behind the 384 Building, the North Process Pond (WIDS Site 316-2) and WIDS Site 300 ASH PITS.

Waste Type: Oil

Waste Description: The release consisted of approximately 3,220 liters (850 gallons) of #6 fuel oil. An estimated 3,028 liters (800 gallons) were recovered in cleanup operations. Approximately, 114 liters (30 gallons) were conveyed to the powerhouse, of which (20 gallons) went to the ash pits and 38 liters (10 gallons) were observed at the process pond (WIDS Site 316-2). That would leave approximately 38 liters (10 gallons) that may have remained in the soil between the day tanks, the powerhouse facility, piping, the ash pits or process ponds. All values are approximate (as stated in the incident report).

Closure Info: Final (8/24/1999): Remediation activities were initiated in May 1998 and continued into January 1999. On January 25, 1999 a decision was made to suspend excavation activities at the North Process Pond and mobilize work crews to the South Process Pond pending resolution of contractual issues with the remedial action subcontractor. Work crews remobilized to the North Process Pond and completed excavation activities in June 1999.

Based on data collected during the remedial investigation, the pond was divided into the Above Cleanup Level (ACL), Below Cleanup Level (BCL), and Undetermined Contamination Level (UCL) areas prior to excavation. The UCL area included the Scraping Disposal Area (sitecode

618-12). Four UPRs associated with the north pond were also associated with the south pond. UPR-300-34, UPR-300-35, UPR-300-36 and UPR-300-37 were addressed with the South Pond remediation (316-1). UPR-300-7 was closed out with the North Pond (316-2).

Code:	UPR-300-13	Classification:	Accepted
Names:	UPR-300-13; Acid Neutralization Tank Leak East of 333 Building; UN-300-13	Reclassification	Consolidated (2/12/1999)
Type:	Unplanned Release	Start Date:	1/1/1973
Status:	Inactive	End Date:	1/1/1973
Description:	This waste site has been consolidated into the 618-1 Burial Ground waste site. The release site was the soil adjacent to the underground spent acid receiver tank that was located east of the 333 Building and adjacent to the 618-1 Burial Ground. The tank pit depth was 3.05 meters (10 feet) below grade. There is currently no visual evidence of the tank or this release. The 334-A Building was built on top of the area where the tank was removed.		
Location:	UPR-300-13 occurred adjacent to the underground spent acid receiver tank (WIDS Site 300-21) that had been located east of the 333 Building. The underground tank has been removed. The 334-A Building is now located at this location.		
Release Description:	The release occurred on July 31, 1973. A chemical operator noted that the liquid level in the 14,383 liter (3800 gallon) tank was below the normal pump suction level. It was known that the tank had been previously pumped down to the 4,542 liter (1200 gallon) heel on the morning of July 31, 1973. In the afternoon of the same day, 1805.45 liters (477 gallons) of liquid waste from the Zircaloy etching tank was added to the heel. In the afternoon of August 1, 1973, the process engineer investigated the tank plug and valve integrity. He found no problems, so he added water to the tank to recheck the possibility of a leak. In the morning of August 2, 1973 a water level check confirmed that 363.4 liters (96 gallons) of liquid had been lost. The test indicated a hole in the tank wall and that approximately 4,920.5 liters (1300 gallons) of liquid waste had been lost to the ground. Spent acid had leaked to the ground through a hole in a koroseal-lined mild steel receiving tank wall. The extent of contamination is not known. The acid receiving tank was isolated. Samples of the lost liquid (collected prior to the leak) were analyzed to characterize the contents of the spill. The sample results showed that 2015 kilograms (4432 pounds) of nitric acid, 44 kilograms (96 pounds) of fluoride, 217 kilograms (477 pounds) of copper and 1.4 kilograms (3 pounds) equivalent to 0.0005 curies of uranium were lost to the ground. 870 kilograms (1910 pounds) of caustic was added to the leaking tank and allowed to leak into the soil to neutralize the acid that had escaped into the ground. The leak rate of the tank was 582.9 liters (154 gallons) per hour.		
Related Sites/ Structures:	UPR-300-13 was associated with the underground spent acid receiver tank (WIDS Site 300-21), the 333 Building (WIDS Site 300-32), and the 618-1 Burial Ground.		
Process Description:	At the time of this release (1973), waste etch acid from the 333-N Fuel Fabrication process drained to an underground tank filled with limestone. The limestone was used to neutralize the acid. The tank had been in service since the start up of the 333 Building.		
Waste Type:	Process Effluent		
Waste Description:	The waste contained process acid that included 4,432 pounds (2,012 kilograms) of nitrate, 447 pounds (202.9 kilograms) of copper, and 3 pounds (1.4 kilograms) of uranium.		

This Site Was Consolidated With:

Code: 618-1
Names: 618-1; Solid Waste Burial Ground No. 1; 300 Area Burial Ground No. 1; 318-1

Code: UPR-300-14 **Classification:** Accepted

Names: UPR-300-14; Acid Leak at 334 Tank Farm; UN-300-14 **Reclassification:** Consolidated (2/12/1999)

Type: Unplanned Release **Start Date:** 1/1/1975

Status: Inactive **End Date:** 1/1/1975

Description: This waste site has been consolidated into the 618-1 Burial Ground waste site. The release site was a limestone pit designed to neutralize spilled acid before the acid was released to the underlying ground.

Location: UPR-300-14 occurred at the 334 tank farm and traveled through a trench to an open-bottomed limestone pit (See WIDS Site 300-246) located over the 618-1 Burial Ground.

Release Description: On July 18, 1975, a line break in the fill line to Tank No. 32 from the 23,000-liter (6,000 gallon) #3 high tank in the 334 tank farms caused the loss of 4,540 liters (1,200 gallons) of 93% sulfuric acid solution. The solution traveled through a concrete trench to a limestone pit that had been designed to neutralize spilled acid. The limestone pit drained to the soil in the 618-1 Burial Ground.

Related Sites/Structures: The site is associated with the 334 Tank Farm and its sump trench, which is connected to the 333 East Pipe Trench (See WIDS Site 300-224) which drained to the Limestone Neutralization Pit and which in turn drained to the 618-1 Burial Ground.

Process Description: A trench sump was installed below the 334 Tank Farm to collect solutions from chemical spills, including the elevated acid storage tanks, the safety showers, and rainwater, etc. The trench sump drained to an open limestone pit located about 6.1 meters (20 feet) east of the 334 Tank Farm. The limestone pit had an open bottom and drained to the 618-1 Burial Ground soil beneath the pit. The limestone pit was isolated after this unplanned release. The 334 Tank Farm pipe trench and sump were sealed from the drain line to the limestone pit and connected to the process sewer.

Waste Type: Chemicals

Waste Description: The release consisted of 93% sulfuric acid.

This Site Was Consolidated With:

Code: 618-1

Names: 618-1; Solid Waste Burial Ground No. 1; 300 Area Burial Ground No. 1; 318-1

Code: UPR-300-18 **Classification:** Not Accepted

Names: UPR-300-18; Release at 321 Tank Farms; UN-300-18 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1962

Status: Inactive **End Date:** 1/1/1962

Description: On August 27, 1962, an employee was sprayed by a release from a low-level cesium-134 waste line.

Location: UPR-300-18 was located inside one of the 321 Tank Farms.

Release Description: The release occurred on August 27, 1962. In the process of removing a drain plug from a low-level cesium-134 waste line, a pipefitter received general protective clothing contamination up to 10,000 counts per minute (shoes 1,000 counts per minute and coveralls 10,000 counts per minute) when solution unexpectedly squirted out of the drain. The main valve had been turned

off and the solution in the line was purportedly at near static pressure at the time of the release. The pipefitter immediately replaced the plug and prevented further contamination spread. The employee reported that he felt liquid strike his face and mouth. A whole body radiation survey detected contamination to the employee's coveralls and shoes but no skin contamination. A subsequent whole body count proved negative. A follow up inspection by operations personnel revealed that the main valve had failed to seat properly. The fault was corrected and the lines flushed of all foreign solid material. The amount released to the ground was not mentioned in the report.

Related Sites/ Structures: UPR-300-18 was associated with a drain plug from a low-level cesium-134 waste line.

Waste Type: Process Effluent

Waste Description: The Occurrence Report states that the waste line carried low-level cesium-134, but the emitter isotope was cesium-137.

Code: UPR-300-31	Classification: Not Accepted
Names: UPR-300-31; 300-31; UN-300-3	Reclassification: None
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: This site is a duplicate of UPR-300-40 (See Site Comment Section).

Code: UPR-300-43	Classification: Accepted
Names: UPR-300-43; 300 Area Solvent Refined Coal Spill; UN-300-43	Reclassification: Rejected (9/22/1998)
Type: Unplanned Release	Start Date: 1/1/1986
Status: Inactive	End Date: 1/1/1986

Description: The site is an unplanned release to the soil adjacent to the 329 Building. All discolored soil was removed from the site. No occurrence report could be found for this site.

Location: The release occurred in the soil outside the 329 Building in the 300 Area.

Release Description: UPR-300-43 occurred when solvent refined coal was spilled to the ground. The spill was caused by failure of a corroded container.

Related Sites/ Structures: The UPR-300-43 was associated with the 329 Building.

Process Description: During the time of the oil crisis (1980s), the coal liquefaction process was developed to produce an alternative fuel source. Full scale production pilot plants were developed to liquefy coal through fractional distillation. Each of the pilot plants developed their own process for liquefying coal. Solvents were used to liquefy the coal. Pacific Northwest Laboratory's (PNL's) task was to study the effects of fractional distillation on the genotoxic potential of solvent refined coal liquids. PNL received product material from six different source pilot plants. Samples that were taken from the source product were subjected to initial chemical analysis, chemical fractionation, and in vitro bioassay. The references listed describe the tests and the results.

Waste Type: Chemicals

Waste Description: The release consisted of solvent-refined coal (light fraction) that was spilled to the ground.

Code: UPR-300-44 **Classification:** Accepted
Names: UPR-300-44; Uranium Bearing Waste Etch-Acid Spill; 313 Building; UN-300-44 **Reclassification:** Consolidated (2/12/1999)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:** 1/1/1985

Description: The release site was to the soil around a section of process sewer line. The information for this site has been incorporated into WIDS Site UPR-300-38. UPR-300-38 addresses the soil contamination under the 313 Building.

Location: UPR-300-44 occurred in a section of the underground process sewer line from the Uranium Recovery Area in the 313 Building.

Release Description: While a new extrusion press was being installed, a leak was discovered in a section of process sewer line. The leak had resulted in a discharge to the ground. The source of the leaking solution was unknown and it was unknown how long the leak had persisted. Spills in the 313 Uranium Recovery Area could have entered this line, resulting in ground disposal of hazardous substances.

Related Sites/Structures: UPR-300-44 was associated with the 313 Building.

Process Description: The 313 Building process sewer collected chemical waste solutions from throughout the chemical processing areas from the start of operations in the 313 Building. The waste solutions drained to the 300 Area ponds until the 1970s when process effluent improvement projects were begun to replace liquid waste discharges to the soil with collection and treatment processes. (See WIDS Site 313 URO).

Waste Type: Process Effluent

Waste Description: The release consisted of wastewater and possibly uranium-bearing acid (nitric and sulfuric acid with uranium in solution) or waste-etch acid (nitric, hydrofluoric, and chromic acids with uranium, copper, and zirconium metals in solution) to the soil. The spill area was possibly contaminated with byproduct waste material.

This Site Was Consolidated With:

Code: UPR-300-38
Names: UPR-300-38; 313 Slab; Demolished 313 Building Foundation; Soil Contamination Beneath the 313 Building

Code: UPR-400-1 **Classification:** Accepted
Names: UPR-400-1; 400 Area Coolant Spill; UN-400-1 **Reclassification:** Rejected (12/3/1998)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The site was an unplanned release that occurred during the construction of FFTF. This site is located somewhere in a field that is now a vegetation-free, gravel-covered area shaped like a semicircle bordered by an asphalt-covered roadway and parking area. The specific location can not be identified. There is no occurrence report for the site.

Type: Unplanned Release **Start Date:** 1/1/1963

Status: Inactive **End Date:** 1/1/1963

Description: Contamination from this incident was identified in a 1.5 meter (5 foot) radius around the burial receptacle in the 618-10 Burial Ground, an area in front of the burial ground access gate, and a spot in front of the 300 Area Powerhouse. The 618-10 Burial Ground has since been stabilized and revegetated. The burial ground is posted with Underground Radioactive Material signs.

Location: Contamination from UPR-600-2 was limited to an estimated 1.5-meter (5 foot) radius around the burial barrel in the 618-10 Burial Ground, an area in front of the burial ground access gate, and a spot on the road in front of the 300 Area Powerhouse.

Release Description: During a routine "milk can" burial, a contamination spread occurred at the 618-10 Burial Ground. An investigation resulted when the truck driver was found to be contaminated after completing the burial. A radiation survey was conducted from the 327 Building to the 618-10 Burial Ground. A spot of contamination was found in front of the 300 Area Powerhouse. Another area of contamination was found in front of the burial ground access gate. No contamination was found on the highway. A 1.5 meter (5 foot) radius around the burial receptacle was found to be contaminated to 80,000 counts per minute.

Related Sites/Structures: UPR-600-2 was associated with the 618-10 Burial Ground and the 300 Area Powerhouse.

Waste Type: Chemicals

Waste Description: Contamination detected at the time of the release ranged from 60,000 to 80,000 counts per minute around the barrel in the 618-10 Burial Ground, 40,000 counts per minute in front of the 300 Area Powerhouse, and 80,000 counts per minute in front of the burial ground access gate.

This Site Was Consolidated With:

Code: 618-10

Names: 618-10; 300 North Solid Waste Burial Ground; 318-10

Code: UPR-600-3 **Classification:** Accepted

Names: UPR-600-3; Contamination Spread at 618-10 **Reclassification:** Consolidated (2/24/1999)

Type: Unplanned Release **Start Date:** 1/1/1963

Status: Inactive **End Date:** 1/1/1963

Description: The release site was an area of soil around a burial barrel within the 618-10 Burial Ground. The release area was surface stabilized with the rest of the burial ground in 1983. The burial ground is fenced and posed as an Underground Radioactive Material area.

Location: The release site was approximately 56 square meters (600 square feet) of ground within the 618-10 Burial Ground in the 600 Area.

Release Description: On September 4, 1963, an improper container was used to dispose of waste into the 618-10 Burial Ground. The lid of the container came off, causing dust to puff out of the barrel and onto the ground. An area approximately 56 square meters (600 square feet) was contaminated to 400 millirads/hour at 5 centimeters (2 inches). The truck and the driver were also slightly contaminated.

Related Sites/Structures: UPR-600-3 was associated with the 618-10 Burial Ground.

Waste Type: Chemical Release

Waste Description: The waste consisted of radioactive dust that was improperly containerized.

This Site Was Consolidated With:

Code: 618-10

Names: 618-10; 300 North Solid Waste Burial Ground; 318-10

Code: UPR-600-4

Classification: Accepted

Names: UPR-600-4; Contamination Spread at 618-11

Reclassification: Consolidated (2/24/1999)

Type: Unplanned Release

Start Date: 1/1/1964

Status: Inactive

End Date: 1/1/1964

Description: The release consisted of an area of soil contamination in the 618-11 Burial Ground. The release site was surface stabilized along with the rest of the burial ground in 1983.

Location: UPR-600-4 contaminated an estimated 93 square meters (1,000 square feet) in the 618-11 Burial Ground in the 600 Area.

Release Description: A trailer truck hauling two waste casks from the 327 Building attempted to deposit waste into the vertical waste barrels at the 300 Wye Burial Ground. As a waste can was dropped into a burial barrel, a "blowback" of radioactive material occurred, contaminating of four employees, the vehicle and approximately 90 square meters (1000 square feet) of ground in the burial ground. Soil contamination levels averaged 10,000 counts per minute. It was also discovered that three of the waste cans had fallen from the cask and were lodged in the drop chute of the second cask. It was determined that the slide on the bottom of the cask had not been properly secured and the waste had vibrated into the drop chute during transit.

Related Sites/ Structures: UPR-600-4 was associated with the 618-11 Burial Ground.

Waste Type: Chemicals

Waste Description: The release consisted of radioactive waste from the High-Level Radiochemistry Facility. The waste had readings of up to 10,000 counts per minute.

This Site Was Consolidated With:

Code: 618-11

Names: 618-11; Y Burial Ground; 300 Wye Burial Ground; 318-11

Code: UPR-600-5

Classification: Accepted

Names: UPR-600-5; Contamination Spread at 618-11

Reclassification: Consolidated (2/24/1999)

Type: Unplanned Release

Start Date: 1/1/1964

Status: Inactive

End Date: 1/1/1964

Description: The release site was covered with a layer of clean material immediately after the release. The release site consisted of an area of soil in the 618-11 Burial Ground. The 618-11 Burial Ground was surface stabilized in 1983. The burial Ground is fenced and posted as Underground Radioactive Material.

Location: UPR-600-5 contaminated an estimated 167 square meters (1,800 square feet) of ground surface in the 618-11 Burial Ground.

Release Description: On May 18, 1964, a contamination incident occurred while dumping canned waste from the 325 Building from a waste cask at the 300 Wye Burial Ground. The waste truck was positioned over a waste receptacle barrel and the waste chute was opened. Fine white powder was seen drifting out of the chute. After washing down the chute and the plastic chute extension, contamination was detected. Ground contamination was identified measuring approximately 167 square meters (1800 square feet) with contamination levels of 500 counts per minute. An area of 18 square meters (200 square feet) was contaminated with levels ranging from 10,000 to 20,000 counts per minute. Two employees were also found to be contaminated. A layer of ballast (gravel) was placed over the ground contamination and reduced the readings to background levels.

Related Sites/ Structures: UPR-600-5 was associated with the 618-11 Burial Ground.

Waste Type: Chemicals

Waste Description: The release consisted of gross fission products with beta and gamma contamination. The wastes were generated in the Radio Chemistry Building (325 Building) and packaged in cars.

This Site Was Consolidated With:

Code: 618-11

Names: 618-11; Y Burial Ground; 300 Wye Burial Ground; 318-11

Code: UPR-600-6	Classification: Accepted
Names: UPR-600-6; Contamination Spread at 618-11	Reclassification: Consolidated (2/24/1999)
Type: Unplanned Release	Start Date: 1/1/1965
Status: Inactive	End Date: 1/1/1965

Description: The release contaminated an area of soil within the 618-11 Burial Ground. The 618-11 Burial Ground was surface stabilized in 1983. The burial ground is fenced and posted Underground Radioactive Material.

Location: UPR-600-6 contaminated an estimated 130 square meters (1,400 square feet) in the 618-11 Burial Ground in the 600 Area.

Release Description: On February 8, 1965, winds blew waste from a truck, over an employee, and onto the ground, causing spotty contamination at the 618-11 Burial Ground. Winds that day were measured at 51 kilometers per hour (32 miles per hour) with gusts up to 71 kilometers per hour (44 miles per hour).

Related Sites/ Structures: UPR-600-6 was associated with the 618-11 Burial Ground.

Waste Type: Chemicals

Waste Description: The waste consisted of ruthenium-103 and zirconium-niobium-95 with readings from 100 counts per minute to 200 millirads/hour.

This Site Was Consolidated With:

Code: 618-11

Names: 618-11; Y Burial Ground; 300 Wye Burial Ground; 318-11

Code: UPR-600-7	Classification: Accepted
Names: UPR-600-7; Contamination Spread at 618-11	Reclassification: Consolidated (2/24/1999)

Type: Unplanned Release**Start Date:** 1/1/1965**Status:** Inactive**End Date:** 1/1/1965**Description:** The release site was an area of ground in the 618-11 Burial Ground. The 618-11 Burial Ground was surface stabilized in 1983. The burial ground is fenced and posted as Underground Radioactive Material.**Location:** The release occurred in an area of soil in the 618-11 Burial Ground.**Release Description:** During the burial of a wooden box containing a highly contaminated waste filter from the 327 Building, an employee became contaminated. The truck was positioned at the burial trench and the truck bed was tilted. However, the box did not slide off the truck. The employee left the truck cab and noticed clouds of dust emitting out of the box seams, causing spotty contamination in the immediate vicinity and levels of 6,000 counts per minute on the employee.**Related Sites/ Structures:** UPR-600-7 was associated with the 618-11 Burial Ground.**Waste Type:** Chemicals**Waste Description:** The waste was generated at the high-level radiochemistry building (327 Building). The waste consisted of a dust from a highly contaminated filter.**This Site Was Consolidated With:****Code:** 618-11**Names:** 618-11; Y Burial Ground; 300 Wye Burial Ground; 318-11

Code: UPR-600-8**Classification:** Accepted**Names:** UPR-600-8; Contamination Spread at 618-11**Reclassification:** Consolidated (2/24/1999)**Type:** Unplanned Release**Start Date:** 1/1/1967**Status:** Inactive**End Date:** 1/1/1967**Description:** The release contaminated an area of soil in the 618-11 Burial Ground. Following the release, area was covered with a layer of clean gravel. The 618-11 Burial Ground was surface stabilized in 1983. The burial ground is fenced and posted as Underground Radioactive Material.**Location:** UPR-600-8 contaminated soil in the 618-11 Burial Ground.**Release Description:** UPR-600-8 occurred on April 7, 1967 during routine burial operations at the 300 Wye Burial Ground (618-11). Waste from the 327 building was being deposited into a vertical waste receptacle through a chute from a cask. The contamination spread occurred as a result of air backup from the waste barrel or loose contamination blown from the release gate of the cask. At the time of the burial, the operation was being conducted from the upwind side of the cask. At the moment the waste was dropped into the chute, the wind reversed in a strong gust, causing the airborne spread of contaminants. An area of ground approximately 2.7 square meters (30 square feet) was contaminated to a maximum of 100,000 counts per minute. Three employees and the transport truck were also contaminated.**Related Sites/ Structures:** UPR-600-8 was associated with the 618-11 Burial Ground.**Waste Type:** Chemicals**Waste Description:** The waste consisted of, in-part, aluminum rupture cans that had been inspected in the High-Level Radio Chemistry Facility (327 Building). The fact that the airborne contaminant was a

"fairly fresh fission product" indicates that it was picked up by the cans during transfer operations through "A" cell in the 327 Building.

This Site Was Consolidated With:

Code: 618-11

Names: 618-11; Y Burial Ground; 300 Wye Burial Ground; 318-11

Code: UPR-600-9

Classification: Accepted

Names: UPR-600-9; Contamination Spread at 618-11

Reclassification: Consolidated (2/24/1999)

Type: Unplanned Release

Start Date: 1/1/1967

Status: Inactive

End Date: 1/1/1967

Description: The contamination spread was a large fan-shaped area extending in a northeast direction from the burial site. The contamination inside the burial ground was covered with gravel. Contamination outside the fence was turned under and the site was released from radiation zone status. The entire 618-11 Burial Ground was surface stabilized in 1983. An area outside the fence known as the "Wind Row" site was released from radiological control in 1972. The rows of soil are still visible, but the area is not marked or posted.

Location: UPR-600-9 contaminated a fan-shaped area that extended northeast from the dump chute in the 618-11 Burial Ground.

Release Description: On April 14, 1967, during routine burial operations in the 618-11 Burial Ground, a piece of waste became wedged in the truck chute causing an airborne release of contamination.

Related Sites/Structures: UPR-600-9 is associated with the 618-11 Burial Ground and the adjacent "Wind Row" site (600-21 alias UPR-600-22).

Waste Type: Chemicals

Waste Description: The release consisted of airborne contamination from corroded aluminum rupture cans and pieces of an N Reactor safety rod from the 327 Building.

This Site Was Consolidated With:

Code: 618-11

Names: 618-11; Y Burial Ground; 300 Wye Burial Ground; 318-11

Code: UPR-600-10

Classification: Accepted

Names: UPR-600-10; Contamination Spread at 618-11

Reclassification: Consolidated (2/24/1999)

Type: Unplanned Release

Start Date: 1/1/1963

Status: Inactive

End Date: 1/1/1963

Description: The release contaminated an area of soil in the northeast corner of the 618-11 Burial Ground. The 618-11 Burial Ground was surface stabilized in 1983. The burial ground is fenced and posted as Underground Radioactive Contamination.

Location: The release contaminated approximately 36 square meters (400 square feet) of soil around Barrel 327-2 in the 618-11 Burial Ground.

Release Description: On September 30, 1963, a contamination release occurred during a routine, high level waste burial at the 300 Wye (618-11) Burial Ground. A "Milk Pail" container that was externally contaminated with a significant amount of loose, highly radioactive material, was discharged into the 327-2 vertical waste barrel (caisson) causing a contamination spread. Although the

wind was less than 16 kilometers per hour (10 miles per hour), an area of contamination was identified that measured approximately 36 square meters (400 square feet) around the barrel. The cask truck had smearable contamination measuring 180 millirads/hour inside the left rear wheel, 40 millirads/hour on the drop chute and 10 millirads/hour on the top of the cask. The truck was sprayed with a fixing agent and taken to 200 West Area for decontamination. The maximum contamination reading on the ground was 1.4 rads/hour.

Related Sites/ Structures: UPR-600-10 was associated with the 618-11 Burial Ground.

Waste Type: Chemicals

Waste Description: The release consisted of high-level beta and gamma contamination with readings of up to 1.4 rads/hour at 7.6 centimeters (3 inches).

This Site Was Consolidated With:

Code: 618-11

Names: 618-11; Y Burial Ground; 300 Wye Burial Ground; 318-11

Code: UPR-600-17

Classification: Accepted

Names: UPR-600-17; 600 Area Patrol Boat Spill; UN-600-17

Reclassification: Rejected (9/11/2000)

Type: Unplanned Release

Start Date: 1/1/1986

Status: Inactive

End Date: 1/1/1986

Description: The site of the release is a concrete boat ramp and the shoreline, periodically flooded as the Columbia River rises daily and seasonally.

Location: The release occurred at the patrol boat refueling area just south of 100N Area on the Columbia River.

Release Description: Gasoline was spilled inside a patrol boat during refueling operations, and gasoline was discharged from the boat to the shoreline. The release occurred on August 17, 1986.

Waste Type: Oil

Waste Description: The release consisted of 268.4 liters (70.9 gallons) of gasoline.

Code: UPR-600-18

Classification: Accepted

Names: UPR-600-18; Tank Truck Gasoline Spill; UN-600-18

Reclassification: Rejected (10/1/1997)

Type: Unplanned Release

Start Date: 1/1/1987

Status: Inactive

End Date: 1/1/1987

Description: The site is an area where petroleum products leaked to the soil from a fuel delivery truck accident. The release occurred April 16, 1987 9:00 AM and resulted in the spill of CERCLA reportable materials. Appropriate notifications were made to the Department of Energy, Environmental Protection Agency, State of Washington, and Rockwell (maintenance and operations contractor) management.

Location: The site is located 0.8 kilometers (0.5 miles) south of 100 F Area on the 100 F access road.

Release Description: The conditions were dry, clear weather and straight roadway. The pavement and road shoulders were in good repair with the ditch approximately 0.91 meters (3 feet) deep and the inslope and backslope, a three to one slope. The driver of a fuel delivery truck (#68C 4366) (Road, Delivery and Equipment Operation Department) had turned off of Route 2 North onto the 100-F Area access road. Approximately 1.61 kilometers (one mile) north of the turn off his gate keys fell to the floor. He leaned over to pick them up and the vehicle ran off of the paved roadway onto the right side road shoulder. The vehicle then went over the shoulder and part way down the inslope. He tried to steer back onto the roadway and lost control. The vehicle then turned over onto its right side blocking both lanes. The driver exited out of the left side of the vehicle and proceeded on foot to 100-F Area to call for assistance. Hanford Patrol and Fire Department arrived on the scene and isolated the immediate area. The diesel tanks on the vehicle seemed intact and fuel was leaking from one top fill cap. A wrecker, rigging crew and front-end loader were dispatched to assist in uprighting the vehicle. The vehicle and surrounding area were foamed by the Hanford Fire Department. Two Ironworker riggers in full fire fighting clothing attached nylon chokers to the fuel vehicle. The wrecker and front-end loader were positioned and attached to the nylon chokers. The fuel vehicle was uprighted without any further damage or spillage of fuel. The remaining fuel was then pumped into a spare fuel truck. The spill area was washed onto the road shoulder and ditch area by the Hanford Fire Department. The fuel truck was then taken to the 1100 Area and the road was then reopened for traffic.

Waste Type: Oil

Waste Description: The release was a total of 1,354 liters (395 gallons) of fuel consisting of 26 liters (7 gallons) of #2 diesel oil, 434 liters (112 gallons) of unleaded gasoline, 38 liters (10 gallons) of ethylene glycol, and 856 liters (226 gallons) of leaded gasoline.

Code: UPR-600-19

Classification: Accepted

Names: UPR-600-19; Lime Sulfur Barrel

Reclassification: Rejected (10/1/1997)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The site is an unplanned release. An old wooden barrel that pre-dated MED operations deteriorated and collapsed, spilling the contents (about 45 kilograms [100 pounds] of powdery lime sulfur) onto the ground. The site was abandoned when the DeWitt Buckholdt Ranch was taken over by the U.S. Army Corps of Engineers in 1943.

Location: The site is located 402 meters (1320 feet) west of Route 2 North and approximately 183 meters (600 feet) south of mile marker 3 at the old Herriford (Buckholdt Ranch) home site. The lime sulfur was located about 0.91 meters (3 feet) off the access road, approximately in front of the house foundation and southeast of the well house foundation.

Release Description: An old wooden barrel of lime-sulfur fungicide had broken, and its contents had spilled to the ground.

Related Sites/Structures: UPR-600-19 is associated with sitecode 600-331, that is the soil beneath the barrel.

Waste Type: Chemical Release

Waste Description: The waste is lime sulfur powder. According to regulatory support personnel, lime sulfur is not a listed waste. WAC 16-154-100 Materials List for Organic Food Production -- Disease Control Materials and Practices states the following: "Approved materials. The following list of disease control materials and practices are approved for use in organic crop production. Some approved materials have certain restrictions regarding their use. These restrictions are

noted in the list. Lime sulfur: Foliar application as a fungicide only."

Code: WESF **Classification:** Accepted
Names: WESF; 225-B; Waste Encapsulation and Storage Facility **Reclassification:** None
Type: Storage **Start Date:** 1/1/1974
Status: Active **End Date:**

Description: The Waste Encapsulation and Storage Facility is a TSD site within the 225-B Building, which is on the west side of 221-B Building (B Plant).

Location: The building addition is located on the west end of the 221-B canyon building. It was built on top of the 216-B-60 crib.

Related Sites/ Structures: The WESF is within the 225-B Building, which is attached to the west side of the 221-B Building (B Plant).

Process Description: Two areas within WESF are permitted in the Hanford Facility Dangerous Waste Part A Permit Application (Rev. 0, 12/19/97) to store capsules and/or unencapsulated salts. Pool cells number 1 through 8 and 12, located on the west side of the 225-B building, provide underwater storage for radiological protection from cesium-137 and strontium-90 capsules. Process cells A through G, in the south side of the 225-B Building, provide interim dry storage of capsules and/or unencapsulated salts. The maximum process design capacity for miscellaneous storage in pool cells 1 through 8 and 12 is approximately 4,484 liters (1,184.55 gallons) and for process cells A through G is approximately 56 liters (14.79 gallons).

This Site has the Following SubSites:

Code: WESF:1
Names: WESF:1; Waste Encapsulation and Storage Facility Tank 100 System; WESF TK-100 System

Code: WESF:1 **Classification:** Accepted
Names: WESF:1; Waste Encapsulation and Storage Facility Tank 100 System; WESF TK-100 System **Reclassification:** None
Type: Storage **Start Date:**
Status: Active **End Date:**

Description: The TK-100 System was used as a catch tank to transfer low-level radioactive liquid waste from WESF through B-Plant to the Double-Shell Tank System. Closure activities were completed in September 1998 and included sampling and analysis of the piping rinsate, removing the tank to a permitted TSD facility (B Plant Complex), removing any waste residues from the vault, and decontaminating and visually inspecting the vault. Piping (floor drains and sump) rinsate was sampled on July 14 and 15, 1998, and analyzed for 1,1,1-tri-chloroethane. All eight samples (K0N378 through K0N385) had less than detectable levels of 1,1,1-trichloroethane.

The SubSite is Part Of:

Code: WESF
Names: WESF; 225-B; Waste Encapsulation and Storage Facility

Code: WRAP **Classification:** Accepted

Names: WRAP; Waste Receiving and Processing Facility **Reclassification** None

Type: Process Unit/Plant

Start Date:

Status: Active

End Date:

Description: This site is operational. WRAP Module 1 is a large metal frame structure. The module has facilities necessary to handle, treat, and store a wide variety of wastes. Module 2A is planned to be a metal structure designed to receive and ship low-level waste to the enhanced Radioactive and Mixed Waste Storage Facility. Module 2B is still in development.

Location: The WRAP Facility will be located west of Dayton Avenue, north of Twenty-Second Street, and south of Twenty-Third Street.

Related Sites/ Structures: Structures associated with this unit include the Radioactive Mixed Waste Storage Facility, the rest of the Central Waste Complex, and the process equipment that will be located in WRAP.

Process Description: The WRAP Facility is a treatment and storage unit for radioactive and/or mixed waste in containers on the Hanford Facility. The different modules of WRAP are used to receive, certify, repackage, characterize, treat, and store radioactive and/or mixed waste from the Hanford Site.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: The unit consists of a storage and treatment facility for transuranic, low-level, low-level/mixed, and nonradioactive dangerous waste.

Code: Z PLANT BP

Classification: Accepted

Names: Z PLANT BP; Z Plant Burn Pit; Z Plant Burning Pit

Reclassification Consolidated (5/31/2001)

Type: Burn Pit

Start Date: 1/1/1948

Status: Inactive

End Date: 1/1/1960

Description: This unit is a rectangular burning pit trench located within (under) Burial Ground 218-W-4C. Stenner et al. report that the burning pit was exhumed during the excavation of Trench 7 in 218-W-4C. Because the site is entirely contained within the burial ground, and was exhumed during construction of the burial ground, it is proposed for consolidation with site 218-W-4C. Future remedial activities will address both sites together, and the sites are linked under the Regulatory tab page of WIDS.

Location: The unit was located in the 218-W-4C Burial Ground at Trench 7.

Related Sites/ Structures: Structures associated with this unit include Z Plant Laboratories, offices, and the 218-W-4C Burial Ground.

Process Description: The Z Plant Burning Pit was a disposal site for combustible nonradioactive construction, office and non-hazardous laboratory waste, including unnamed chemicals. The burn pit is reported to have received 2,000 cubic meters (70,000 cubic feet) of wastes for burning, including 'less than' 1,000 cubic meters (35,000 cubic feet) of laboratory chemicals.

Waste Type: Ash

Waste Description: The site was used to burn combustible nonradioactive waste and non-hazardous laboratory waste, including unnamed chemicals.

This Site Was Consolidated With:

Code: 218-W-4C

Names: 218-W-4C; Dry Waste No. 004C

TBD

Code: 100-B-34 **Classification:** Accepted

Names: 100-B-34; B/C-Area Pipelines under Active Utilities/Structures **Reclassification:** None

Type: Product Piping **Start Date:**

Status: Inactive **End Date:**

Description: The site consists of multiple segments of underground, miscellaneous pipelines in the 100-B/C Area that required remediation but were deferred due to the presence of active utilities. Three pipeline segments were administratively removed from 100-B-28 (RSVP-2009-057] and 100-C-6:1 (and the former 100-C-6:5). They are included in 100-B-34 so that 100-B-28 and 100-C-6:1 could be reclassified. The following pipeline segments have been included in this waste site:

(1) A section of 7.62 centimeter (3 in) steel, soft water pipeline that was converted for use with sodium dichromate about 1962 (P-5528, P-5649). The pipeline ran between the 184-B Power House and the 183-C Head House. The majority of the pipeline was remediated as 100-B-28. This section could not be removed due to the presence of active export water line. Following discussion with the U.S. Department of Energy, Richland Operations Office (DOE-RL), and U.S. Environmental Protection Agency (EPA), the section was filled with grout to flush residual sodium dichromate liquid out for collection. However, the potential for pipe leakages beneath these sections cannot be addressed while the utilities remain active. Therefore, in agreement with DOE-RL and EPA, the section was administratively removed and reassigned to this site (150166). Another section of the same pipeline was assigned to 100-C-7:1 so that it would be closed during that remedial activity.

(2) Two sections of 1.7 meter (66 in) steel process sewer that carried effluent from the 105-C Reactor to the retention basin (P-5591, M-1904-B Sheets 4 and 9). The majority of the pipelines were remediated as 100-C-6:1. There are sections that could not be removed due to the presence of an overlying active export water line (CVP-2003-00022). These pipe segments were previously known as 100-C-6:5, but are now considered part of 100-B-34.

Location: The pipeline segments are located throughout the 100-B/C Area.

Code: 100-B-35 **Classification:** Accepted

Names: 100-B-35; 151-B Primary Substation and 152-B1 Secondary Electrical Substation **Reclassification:** Interim Closed Out (6/15/2015)

Type: Electrical Substation **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is the electrical substations located in 100-B Area. The site was divided into two subsites. Subsite 1 is the Primary Electrical Substation. It was remediated and Interim Closed Out. Subsite 2 is the Secondary Electrical Substation. Subsite 2 has been reclassified to Interim No Action. Because both subsites have been reclassified, the parent site is being reclassified to Interim Closed Out.

Location: The 151-B Primary Substation was located approximately 350 meters (1150 ft) southwest of the 105-B Reactor Building. The secondary, 152-B1 Substation was located south of the 181-B Building, approximately 820 meters (2,690 ft) northwest of the 105-B Reactor Building.

Process Description: The 151-B Substation served as the primary source of electrical power for all facilities in the 100BC Area. It was first energized in June 1944, and received 230 kV power from the Midway Substation. From the three main transformers in the 151-B Switch Yard, power was transmitted primarily via underground cables to thirteen secondary substations and nine distribution substations located throughout the 100BC Area. One 27.5 KVA transformer, located adjacent to the 151-B Switch House, provided service for the building. Five oil circuit breakers were also in service to support the switch yard operations. In 1952, the substation was expanded to support the new 105-C Reactor facilities, including the construction of an addition to the Switch House as well as additional equipment in the Switch Yard (HW-24800-101). Polychlorinated biphenyl (PCB)-containing oil was transferred, as needed, from a rail tanker on the railroad spur through above ground and underground piping to transformers and oil circuit breakers in the yard. The 152-B1 Substation provided power to the nearby 181-B Building. It had a primary voltage of 13.8 kV and a secondary voltage of 2.3 kV (HAN-10970 Vol. 3, p. 716). Originally there were four 1500 KVA 13800/2300V single phase transformers manufactured by the Kuhlman Electric Company. The substation was constructed in 1944. Two transformers were added in 1952 when the 151-B building was expanded (P-5032).

Closure Info: Interim (6/15/2015): Confirmatory samples were collected for 100-B-35:2 (100-B Secondary Electrical Substation) and was determined to require No Action. 100-B-35:1 is the 151-N Primary Substation. The 100-B-35:1 subsite was identified for remove, treat, and dispose based on the results of confirmatory sampling. A geophysical survey was performed in June 2013 to support excavation of the subsite. Linear anomalies detected with a utility detector were identified as inactive utilities within the 151-B Switch Yard.

The 13.8 kV and 230 kV power lines, switchgear, and cables were previously isolated and/or removed from the 151-B Switch House facility. The 151-B Switch House and the above grade electrical components and concrete pads protruding from the ground surface at the 151-B Switch Yard were removed by the Washington Closure Hanford (WCH) Deactivation, Decontamination, Decommissioning, and Demolition project between October 2013 and March 2014.

WCH recycled 250,608 kg (552,000 lbs) of transformers, transformer bushings, and metal and 3,028 liters (800 gal) of transformer oil. Mission Support Alliance recycled 154,178 kg (339,600 lbs) of metal, beams, components, and wire. The remaining 7,593.4 metric tons (6,890.6 tons) of demolition debris was removed and disposed at the Environmental Restoration Disposal Facility (ERDF).

Remediation of remaining contaminated soil and debris at the 100-B-35:1 subsite was performed by Field Remediation between July 30, 2014, and February 18, 2015. Approximately 42,550 bank cubic meters (55,653 bank cubic yards) of contaminated soil and debris, along with 19,300 bank cubic meters (25,243 bank cubic yards) of padding material that was used to support site remediation processes, were removed and staged for disposal at ERDF. This volume also includes some padding material that was used to support site remediation processes. Excavated materials consisted of concrete, rebar, asbestos, conduit, steel pipe, wire, and stained soil. The depth of the excavation varied between 1 to 6 m (3.3 to 19.7 ft) across the subsite. Significant staining was encountered on the northeast corner of the 100-B-35:1 subsite. To remove the stained soil at this location the excavation was extended into the deep zone (greater than 4.6 meters [15 ft] deep).

Concrete duct banks were encountered in the shallow zone of the 100-B-35:1 excavation. These duct banks contain electrical conduits made of asbestos piping with no other hazardous materials. The field sampling personnel examined the concrete duct banks for staining; no staining on these concrete structures was identified. Per discussion with the EPA, documented in CCN 178739, Concrete Duct at 100-B-35 (Regulatory Agreement), it was agreed that the concrete duct banks could be left in place if the concrete was free of staining.

This Site has the Following SubSites:**Code:** 100-B-35:1**Names:** 100-B-35:1; 151-B Primary Electrical Substation**Code:** 100-B-35:2**Names:** 100-B-35:2; 152-B1; 152-EB1; 100-B Secondary Electrical Substation**Code:** 100-B-35:1**Classification:** Accepted**Names:** 100-B-35:1; 151-B Primary Electrical Substation**Reclassification:** Interim Closed Out (6/15/2015)**Type:** Electrical Substation**Start Date:** 6/1/1944**Status:** Inactive**End Date:** 1/1/1998

Description: The waste site was the 151-B Primary Substation. It has been remediated and Interim Closed Out. It included a wooden fenced, gravel surfaced area as well as a reinforced concrete and concrete block switch house along the north side of the fence. The fenced area contained wooden frame bus structures, two main 15,000 KVA transformers, three oil circuit breakers, and terminal structures. The 151-B Switch House was a one story building, with a sub-level cable pit equipped with a sump pump.

Location: The 151-B Primary Substation was located approximately 210 meters (689 ft) southwest of the 105-B Reactor Building.

Release Description: Oil seepage was recorded from one of the large transformers in 1990, and a 378 liter (100 gal) spill from another transformer was noted in 1992. This may not have been the extent of transformer leaks and spills because such events were not consistently recorded before 1985. A soil sample was collected from the soil around the concrete transformer pad on December 9, 1991. No PCBs were detected in this single sample.

Process Description: The 151-B Substation served as the primary source of electrical power for all facilities in the 100BC Area. It was first energized in June 1944, and received 230 kV power from the Midway Substation.

Closure Info: Interim (6/15/2015): Confirmatory samples were collected for 100-B-35:2 (100-B Secondary Electrical Substation) and was determined to require No Action. 100-B-35:1 is the 151-N Primary Substation. The 100-B-35:1 subsite was identified for remove, treat, and dispose based on the results of confirmatory sampling. A geophysical survey was performed in June 2013 to support excavation of the subsite. Linear anomalies detected with a utility detector were identified as inactive utilities within the 151-B Switch Yard.

The 13.8 kV and 230 kV power lines, switchgear, and cables were previously isolated and/or removed from the 151-B Switch House facility. The 151-B Switch House and the above grade electrical components and concrete pads protruding from the ground surface at the 151-B Switch Yard were removed by the Washington Closure Hanford (WCH) Deactivation, Decontamination, Decommissioning, and Demolition project between October 2013 and March 2014.

WCH recycled 250,608 kg (552,000 lbs) of transformers, transformer bushings, and metal and 3,028 liters (800 gal) of transformer oil. Mission Support Alliance recycled 154,178 kg (339,600 lbs) of metal, beams, components, and wire. The remaining 7,593.4 metric tons (6,890.6 tons) of demolition debris was removed and disposed at the Environmental Restoration Disposal Facility (ERDF).

Remediation of remaining contaminated soil and debris at the 100-B-35:1 subsite was performed by Field Remediation between July 30, 2014, and February 18, 2015. Approximately

42,550 bank cubic meters (55,653 bank cubic yards) of contaminated soil and debris, along with 19,300 bank cubic meters (25,243 bank cubic yards) of padding material that was used to support site remediation processes, were removed and staged for disposal at ERDF. This volume also includes some padding material that was used to support site remediation processes. Excavated materials consisted of concrete, rebar, asbestos, conduit, steel pipe, wire, and stained soil. The depth of the excavation varied between 1 to 6 m (3.3 to 19.7 ft) across the subsite. Significant staining was encountered on the northeast corner of the 100-B-35:1 subsite. To remove the stained soil at this location the excavation was extended into the deep zone (greater than 4.6 meters [15 ft] deep).

Concrete duct banks were encountered in the shallow zone of the 100-B-35:1 excavation. These duct banks contain electrical conduits made of asbestos piping with no other hazardous materials. The field sampling personnel examined the concrete duct banks for staining; no staining on these concrete structures was identified. Per discussion with the EPA, documented in CCN 178739, Concrete Duct at 100-B-35 (Regulatory Agreement), it was agreed that the concrete duct banks could be left in place if the concrete was free of staining.

The SubSite is Part Of:

Code: 100-B-35

Names: 100-B-35; 151-B Primary Substation and 152-B1 Secondary Electrical Substation

Code: 100-B-35:2

Classification: Accepted

Names: 100-B-35:2; 152-B1; 152-EB1; 100-B Secondary Electrical Substation

Reclassification: Interim No Action (6/23/2014)

Type: Electrical Substation

Start Date:

Status: Inactive

End Date:

Description: The waste site has been evaluated and determined to require No Action. The secondary substation consisted of a small fenced area surrounding utility poles and concrete pads that once supported six transformers. In 1952, the 152-B1 Substation was expanded to include two additional 1500 KVA transformers in support of the addition to the 181-B Building and the new 105-C Reactor (P-5032). In 1960, cooling fans were installed on each of the transformers (H-1-12033). The aboveground structures were removed as a Miscellaneous Restoration activity.

Location: The 152-B1 Substation was located south of the 181-B Building and approximately 820 meters (2690 ft) northwest of the 105-B Reactor Building.

Process Description: The 152-B1 Substation was constructed in 1944 and was known as 152-E1B. It provided power to the nearby 181-B Building. It had a primary voltage of 13.8 kV and a secondary voltage of 2.3 kV. Originally, there were four 1500 KVA 13800/2300V single phase transformers manufactured by the Kuhlman Electric Company. Two more were added in 1952. Oil containing polychlorinated biphenyls (PCBs) was transferred, as needed, from oil trucks through over-ground hoses to smaller transformers at the secondary and distribution substations.

Closure Info: Interim (6/23/2014): Confirmatory sampling was performed at the 100-B-35:2 subsite on February 20, 2014, per the Work Instruction for Confirmatory Sampling of the 100-B-35, 151-B Primary Substation and 152-B1 Secondary Substation (WCH 2013b). Confirmatory sampling of the 100-B-35:2 subsite was performed to support evaluation of the site against the RAGs specified in the Remaining Sites ROD (EPA 1999). The analytical results were evaluated against the cleanup criteria specified in the RDR/RAWP (DOE-RL 2009b) to support a No Action or Remedial Action decision.

The SubSite is Part Of:

Code: 100-B-35
Names: 100-B-35; 151-B Primary Substation and 152-B1 Secondary Electrical Substation

Code: 118-B-8 **Classification:** Accepted
Names: 118-B-8; B Reactor; 105-B Reactor Building **Reclassification:** None
Type: Reactor **Start Date:** 1/1/1944
Status: Inactive **End Date:** 1/1/1968

Description: The waste site consists of the 105-B Reactor Building facility, which originally included the inactive plutonium production reactor block with associated shielding and controls, an irradiated fuel storage basin, and contaminated portions of the reactor building. The waste site components were divided into three subsites. Subsite 1 is the reactor building that includes the graphite core, control room and fuel storage basin. The building is currently a museum. Subsite 2 consists of fourteen French drains around the periphery of the 105-B Reactor Building. During two walk downs in September 2004, the suspect French drain locations were recorded using global positioning system (GPS) instrumentation and were photographed. Several indicate connecting piping that was painted pink. Subsite 3 consists of pipeline segments that were deferred from 100-B-21 pipeline waste site. These segments were within the 7.6 meter (25 foot) buffer zone of the reactor building and were identified during removal of effluent pipelines and site characterization in the 100-B/C Area. The pipelines were cut approximately 15.2 meters (50 feet) from the reactor footprint so as not to disturb the 105-B Reactor structure.

Release Description: It is suspected that the irradiated fuel storage basin leaked for a number of years prior to deactivation. The leak rate was small, and the location of the leak was never identified. The soil has not been characterized, but the radionuclide inventory is estimated to be low when compared to the total inventory in the reactor.

Process Description: Water from the Columbia River was extensively treated before passing through the reactor. The water was then circulated in a single pass through the reactor process tubes, cooling tubes imbedded in the thermal shield, and reactor horizontal control rods. After exiting the reactor, the cooling water passed through a retention basin and was then discharged to the river. During reactor operations, fuel cladding failures sometimes occurred while the fuel element were in the process tubes. Over the operational lifetime of the reactor, there were several hundred such cladding failures. When fuel cladding failed, the cooling water in the affected process tubes became highly contaminated and elevated radiation levels were observed in the cooling water exiting the reactor core. This highly contaminated water was diverted to a trench for ground disposal rather than to the Columbia River. During reactor operations and reactor shutdowns, large quantities of decontamination solutions were used routinely to remove radionuclides from reactor equipment and facility surfaces. Decontamination activities took place at the dummy decontamination facility wash pad, which was adjacent to the fuel storage basin. Known decontamination solutions included chromic acid, citric acid, oxalic acid, nitric acid, sulfamic acid, sulfuric acid, and sodium fluoride. Other chemicals, including organic solvents were also used for some decontamination processes. The reactor had many safety and control mechanisms. The function of the horizontal control rods (HCRs) was to control the equilibrium and transient power levels of the reactor during routine operations and to maintain the desired neutron flux distribution. The HCRs were each about 11.0 meters (36 feet) long, with the poison (neutron absorbing) segment being about 8.96 meters (29.4 feet) long. Two of the rods were electrically driven and seven were hydraulically driven. The latter were known as shim rods and were used to achieve ongoing operation control and desired fluctuations. The vertical safety rods (VSRs) were 11.9 meter (39 foot) long, stainless steel sleeves with 0.74 millimeter (3/16 inch) thick boron stainless steel sleeves inside. Each VSR was inserted and withdrawn from the reactor via two separate cables wound around a winch located 12.2 meters (40 feet) above the top of the reactor. In cases of automatic shutdown ("scram") of the reactor, the electromagnetic clutch holding each rod would be deenergized (demagnetized), and the rods

would free fall by gravity into channels penetrating the reactor. A "last ditch" safety system, a boric acid solution, was held in a large pedestal tank at the top of each reactor and connected to each of the 29 VSR channels via 1.27-centimeter (0.5-inch) pipes. The liquid boron system was later replaced by a system that used solid boron steel and carbon steel balls (Ball 3X System). The normal method for reactor refueling was displacement charge-discharge during reactor shutdown. During a refueling operation, the tubes to be discharged had their rear nozzle caps removed. New fuel elements were pushed into the process tube by a charging machine which caused the irradiated fuel elements in the tube to be displaced. The displaced irradiated fuel elements dropped into a water filled discharge chute and slid down into the metal pickup area at the end of the storage basin. The 6.1 meters (20 feet) of water in the chute area provided shielding as the elements accumulated and were sorted into buckets using long, hand-operated tongs. The buckets were then transferred by an overhead monorail system to the storage aisles where they were held for a time to allow the decay of short-lived radionuclides. Following the storage period, the buckets of fuel elements were moved by the overhead monorail system to the transfer area. At the transfer area, the irradiated fuel was loaded into casks, then raised by a crane and placed in special railroad cars for shipment to the chemical reprocessing facilities in the 200 Area.

Waste Type: Equipment

Waste Description: This Reactor building contained an estimated 23,500 curies of radionuclides, 79,800 kilograms (88 tons) of lead, and 227 kilograms (500 pounds) of cadmium.

Waste Type: Asbestos (friable)

Waste Description: The Reactor Building is estimated to contain 85.0 cubic meters (3000 cubic feet) of asbestos.

This Site has the Following SubSites:

Code: 118-B-8:1

Names: 118-B-8:1; 105-B Reactor Building

Code: 118-B-8:2

Names: 118-B-8:2; 105-B French Drains

Code: 118-B-8:3

Names: 118-B-8:3; 105-B Miscellaneous Pipeline Segments

Code: 118-B-8:1

Classification: Accepted

Names: 118-B-8:1; 105-B Reactor Building

Reclassification: None

Type: Reactor

Start Date:

Status: Inactive

End Date:

Description: Subsite 1 is the reactor building that includes the graphite core, control room and fuel storage basin. The 105-B Reactor was transferred from Washington Closure Hanford (WCH) to Fluor Hanford (FH) on 3/16/2009. WCH is still responsible for managing nuclear materials within the transfer pit and reactor core.

Location: The 105-B Reactor is near the center of the 100-B/C Area, and about 0.9 kilometers (0.6 miles) south of the Columbia River.

Process Description: The reactor rests on a 7.0-meter (23-foot) thick concrete foundation topped with cast iron blocks that served as a thermal shield. The building walls consists of reinforced concrete in the lower portions and concrete blocks in the upper portions with thickness varying from 0.9 to 1.5 meters (3 to 5 feet). The roof is composed of precast concrete roof tiles, except for the

discharge area enclosure and inner horizontal rod room where the roof was composed of 1.8-meter (6-foot) thick reinforced concrete.

The reactor core consisted of a graphite "stack" that measured 8.5 meters (28 feet) from front to rear, 11.0 meters (36 feet) from side to side, and 11.0 meters (36 feet) from top to bottom. The stack was pierced front to rear by 2,004 process channels that held the fuel elements. Nine horizontal channels for control rods entered from the left side and 29 vertical channels for safety rods entered from the top. Six test holes labeled A through F, leading from the right, existed for irradiation of experiments, foils, counters, ionization chambers, and special samples. The horizontal control rod (HCR) and vertical safety rod (VSR) channels, as well as the test holes, were lined with a thin sheet of aluminum known as a "thimble".

The graphite core is surrounded by a cast iron thermal shield layer. Cooling for the top, side, and bottom shields were provided by circulating water tubes imbedded in the blocks. The entire reactor block was then enclosed in a welded steel box that functioned to confine the inert gas atmosphere within the reactor. Expansion joints were placed on the corners of the block to allow for thermal expansion and expansion bellows were located at each process tube opening. The bellows served as gas seals as the process tubes expanded and contracted with temperature and with the distortions of the graphite.

The fuel storage basin is located at the rear of the reactor. The concrete basin area served as a collection, storage, and transfer facility for the irradiated fuel elements discharged from the reactor. The water in the basins served both as coolant and as shielding. The basin consisted of a discharge chute and fuel element pickup area, a storage area, a transfer area, and a wash pad area.

Waste Type: Not Specified

Waste Description: This Reactor building contains an estimated 23,500 curies of radionuclides, 79,800 kilograms (88 tons) of lead, and 227 kilograms (500 pounds) of cadmium. The Reactor Building is estimated to contain 85.0 cubic meters (3000 cubic feet) of asbestos.

The SubSite is Part Of:

Code: 118-B-8

Names: 118-B-8; B Reactor; 105-B Reactor Building

Code: 118-B-8:2

Classification: Accepted

Names: 118-B-8:2; 105-B French Drains

Reclassification: None

Type: Reactor

Start Date:

Status: Inactive

End Date:

Description: The subsite consists of fourteen French drains around the periphery of the 105-B Reactor Building. During two walk downs in September 2004, the 14 suspect French drain locations were recorded using global positioning system (GPS) instrumentation and were photographed. Several drains included piping that was painted pink.

Because of variables, each of the suspect drain sites will require further investigation prior to cleanup activities, including removal of covers and visual inspection and sampling of drain fill material and surrounding native soil.

During WCH walkdowns on 9/7/2004 and 9/13/2004 around the periphery of the 105-B Building, fourteen suspect French drain locations were recorded using global positioning system (GPS) instrumentation and were photographed. Most of the suspect drains had

protective covers. No inspection was attempted beneath those covers. Some of the covers had been penetrated by over-ground piping and others had holes that suggested previous discharge points. Other French drains may have received discharges from underground piping.

Location: French Drain #1 is a concrete box with a wooden cover, less than 1 square meter (10.8 square feet) in cross-section. It is located adjacent to the northeast corner of the 105-B Building, under a sign painted on the concrete block wall labeled Drain 1 and has a pink-colored steam condensate line coming out of the wall. It disappears into the soil directly adjacent to the box. It is located at E 565331, N 144524.

French Drain #4 is a concrete box with a wooden cover, less than 1 square meter (10.8 square feet) in cross-section. It is located adjacent to the southeast corner of the 105-B Building, under a sign painted on the concrete block wall labeled Drain 4. The cover is penetrated by a 10 centimeter (4 inch) pipeline that emanates from a larger line. It is located at E565331/N 144502.

French Drain #11 is a confined space about 5 meters (16 feet) from a northeast corner of the 105 B Building, with a red, metal manhole cover. No over-ground lines connect to it. It is located at E565320/N144531.

French Drain #12 is a confined space near a northeast corner of the 105-B Building, with a metal manhole cover penetrated by a 1.3 centimeter (0.5 inch) and a 2.5 centimeter (1 inch) pink-colored pipeline. It is located at E565310/N144533.

French Drain #13 appears to be a clay or concrete pipe adjacent to a northeast corner of the 105 B Building, less than 1 meter (3 feet) in diameter, with only soil visible on its surface. It is penetrated by 10.2 centimeter (4 inch) pipeline. It is located at E565310/N144535.

French Drain #14 is a 1.4 meter (4.6 foot) diameter concrete pipe, 2.5 meters (8 feet) from the northeast corner of the 105-B Building. It appears to have a cover with a lifting ring. No over-ground pipelines connect to it. It is located at E565299/ N144562.

French Drain #15 is a 20 centimeter (8 inch) clay pipe on the northwest corner of the 105 B Building. It is filled with soil with no cover or over-ground lines connecting to it. It is located at E565263/N144545.

French Drain #16 is a 1 meter (3 foot) diameter concrete pipe near the northwest corner of the 105-B Building, with soil visible on its inside. A one 2.5 centimeter (1 inch) pipe is penetrating the top of the drain and a second, capped line terminates just above its surface. It is located at E565262/N144541.

French Drain #18 is a 1 meter (3 foot) diameter confined space along the west wall of the 105 B Building with a metal cover. The cover has a 7.6 centimeter (3 inch) hole in it and a similar-sized pipe terminates near the surface of the cover. It is located at E565252/ N144499.

French Drain #19 is a 1.4 meter (4.6 foot) diameter concrete confined space along the west wall of the 105-B Building. It has a solid, concrete cover with no over-ground lines connecting to it. It is located at E565252/N144491.

French Drain #20 is a 1 meter (3 foot) diameter concrete pipe near the southwest corner of the 105-B Building, and has a metal cover. A 2.5 centimeter (1 inch) pipe penetrates the cover. A similar-sized pipeline (painted pink) terminates just above a second hole in the cover. It is located at E565255/N144473.

French Drain #21 is a 1 meter (3 foot) diameter concrete pipe along the south wall of the 105 B Building just outside a door marked Inner Instrument Room. It has a metal cover and is penetrated by a pink-colored 1.3 centimeter (0.5 inch) pipeline. It is located at

E565284,/N144495.

French Drain #22 is a 1 meter (3 foot) diameter confined space along the south wall of the 105 B Building, and has a metal cover. A pink-colored 2.5 centimeter (1 inch) pipeline penetrates the cover and two other lines enter the soil near the confined space. It is located at E565299/N144492.

French Drain #23 is a white-painted, insulated pipe that directly enters the soil along the south wall of the 105-B Building. It is located at E565308/ N144492.

Process Description: French drains were designed to receive nonradioactive liquids from the 105-B Reactor Building, via over-ground and/or underground piping. The discharges included steam condensate and floor drain wastes. The liquids would percolate through the gravel/soil fill, and out the open end at the bottom of the drain into the native soil. No information could be found to corroborate what liquid waste streams from the building were discharged to each of these suspect drains. Because B Reactor was a first-of-a-kind operation and a national priority, it is prudent to assume that any of these suspect drains could have received unplanned and/or unrecorded releases of both radioactive and nonradioactive CERCLA wastes. It should be noted that the soil associated with some of the French drains at both D Reactor and F Reactor have tested positive for heavy metals and fission products. (See sites 100-F-10, 116-D-6 and 116-F-11.)

Waste Type: Not Specified

Waste Description: The waste are the french drains, piping to the french drains, and potentially contaminated soil associated with the french drains.

The SubSite is Part Of:

Code: 118-B-8

Names: 118-B-8; B Reactor; 105-B Reactor Building

Code: 118-B-8:3

Classification: Accepted

Names: 118-B-8:3; 105-B Miscellaneous Pipeline Segments

Reclassification: None

Type: Reactor

Start Date:

Status: Inactive

End Date:

Description: The subsite consists of pipeline segments (DS-100BC-013, 014, 017, 018, 024, 025, 026, 027, 028, 035, 041 and 043), that were deferred from the 100-B-21 pipeline waste site. The segments were within the 7.6 meter (25 foot) reactor facility buffer zone, and were identified during removal of effluent pipelines and site characterization in the 100-B/C Area. The pipelines were cut approximately 15.2 meters (50 feet) from the reactor footprint so as not to disturb the 105-B Reactor structure. The numbering system for the segments was created and assigned by the contractor (WCH) as they were recorded in the field.

There were two pipelines associated with the 120-B-1 Battery Acid Sump inlet and outlet pipelines that were also left in place. They were cut off and grouted at the edge of the 120-B-1 remediation footprint. These have been assigned to the 118-B-8:3 subsite (per RSVP-2006-057). Other pipelines in this subsite include the southern most part of the 1607-B2 septic system collection lines. They were not remediated with the 1607-B2 site because of their proximity to the reactor facility. They will be addressed with disposition of the 105-B facility (per RSVP-2006-055).

Location: The coordinates were recorded using a Trimble survey grade Global Positioning Satellite (GPS)

instrument, (centimeter accuracy), location coordinates were described in terms of Washington State Plane easting (E), northing (N), and elevation in NAVD88 (meters). For selected sites, Ground-Penetrating Radar (GPR) was also utilized. Dimensions were noted during site characterization. Contaminants of Potential Concern were listed only for segments known to have contaminants. The sample data results have not been loaded into HEIS.

DS-100BC-013 pipeline segment is a 20 centimeters (8 inches) diameter steel line, length unknown. The coordinates at the cut end were E 565322.97, N 144540.94, and elevation 141.71 meters. It was discovered during the excavation of the 16.5 meter (54 inch) cross-tie effluent pipeline. The pipeline segment was shallow and did not appear on project drawings. It has been cut off, the end pinched closed, and the site backfilled. No sampling was conducted.

DS-100BC-014 pipeline segment is a 20 centimeter (8 inch) diameter (estimated), steel line, length unknown. The coordinates at the cut end were E 565337.60, N 144532.97, and elevation 142.22. This pipeline was located approximately 14.5 meters (47.6 feet) east of the DS-100BC-013 segment. It was discovered during the excavation of the effluent pipelines northeast of 105-B. The pipeline was shallow and not apparent on project drawings. It has been cut off, the end pinched closed, and the site backfilled.

DS-100BC-017 pipeline segment is a 20 centimeter (8 inch) diameter (estimated), steel pipeline that entered a junction box, length unknown. The coordinates at the cut end were E 565313.35, N 144550.66, and elevation 141.01 meters. It was pinched closed and backfilled in place. The pipeline was not apparent on project drawings. No sampling was conducted.

DS-100BC-018 pipeline segment is a 30.5 centimeter (12 inch) diameter (estimated) steel pipeline, length unknown. It ran at a diagonal to the former junction box. The coordinates at the exposed ends were (E 565311.85, N 144550.88) and elevation 142.84 meters and E 565317.95, N 144542.72, and elevation 142.98 meters. The pipeline, which was left intact, could not be found on project drawings. No sampling was conducted.

DS-100BC-024 pipeline segment is a large-diameter pipeline (actual diameter and length were unknown). The coordinates at the cut end were E 565320.28, N 144549.81, and elevation 141.25 meters. It has been cut off, covered with plastic and plywood, and backfilled. No sampling was conducted.

DS-100BC-025 pipeline segment is a large-diameter pipeline (actual diameter and length were unknown). The coordinates at the cut end were E 565320.71, N 144545.69, and elevation 138.25. It has been cut off, covered with plastic and plywood, and backfilled. No sampling was conducted.

DS-100BC-026 pipeline segment is a large-diameter pipeline (actual diameter and length were unknown). The coordinates at the capped end of the pipeline were E 565331.46, N 144547.78, and elevation 138.05 meters. The pipeline entered the excavation from the south sidewall and angled northeast toward a large diversion box. The pipeline was found capped with a steel plate. It was not identified on project drawings. No sampling was conducted.

DS-100BC-027 pipeline segment is a concrete pipeline (actual diameter and length were unknown). The coordinates at the end of the segment were E 565341.83, N 144535.68, and elevation 139.28 meters. On 6/16/2003 field screening for radiological control was performed. No analytical samples were collected.

DS-100BC-028 pipeline segment is a vitreous clay pipeline (actual diameter and length were unknown), embedded in concrete in tandem with DS-100BC-027, entering the pipeline excavation south of a junction box. The pipeline coordinates at the end were E 565340.04, N 144536.38, and elevation 139.19 meters. Sections of this pipeline to the south have not been

removed. This pipeline was not identified on project drawings. Fine-grained sediment was observed along the bottom of the pipeline. It was unclear if the material was from processes associated with the pipeline or washed in from dust-suppression efforts during remediation. On 6/16/2003 field screening for radiological control was performed, however, no analytical samples were collected.

DS-100BC-035 pipeline segment is a 137.2 centimeters (54 inches) large-diameter concrete pipeline (length unknown) encased in concrete. The coordinates were E 565306.48, N 144581.69, and elevation 139.80 meters. The structure was capped with plastic and plywood and had a tar/asbestos gasket at the cold joint of the concrete encasement. Contaminants of concern was asbestos. On 3/5/2003, sample J00J04 was collected from the gasket material and sent for asbestos analysis.

DS-100BC-041 pipeline segment is of undetermined diameter [at least 30.5 centimeters (12 inches), actual diameter and length were unknown], just below grade. The coordinates were E 565327.99, N 144535.81, and elevation 142.68 meters. No sampling was conducted. This pipeline was believed to travel in a southwest direction toward a metal plate covered structure on the northeast of the 105-B Reactor Building. The pipeline was not found on project drawings.

DS-100BC-43 consists of a group of pipelines around the south and southwest sides of the 105-B Reactor. The following alpha characters have been added as an indicator for a specific pipeline. The pipeline coordinates were estimated from the center (not accounting for bends) of lines. The diameters of these pipelines were unknown; the lengths were: A - E 565341, N 144510, 58.7 meters (192.6 feet) long; B - E 565335, N 144523, 12.6 meters (41.3 feet) long; C - E 565336, N 144508, 12.7 meters (41.7 feet) long; D - E 565335, N 144504, 10.6 meters (34.8 feet); E - E 565335 N 144492, 12.7 meters (41.6 feet) long; F - E 565335, N 144486, 11.5 meters (37.8 feet); G - E 565313; N 144480, 73 meters (239.5 feet) long. No sampling was conducted.

Waste Type: Not Specified

Waste Description: The waste is mixed (chemically and radiologically) contaminated piping (concrete, steel and vitrified clay) and piping contents (scale and sediment), and contaminated soil.

The SubSite is Part Of:

Code: 118-B-8

Names: 118-B-8; B Reactor; 105-B Reactor Building

Code: 118-C-3

Classification: Accepted

Names: 118-C-3; 105-C Reactor Building

Reclassification: Interim Closed Out (6/9/2015)

Type: Reactor

Start Date: 1/1/1952

Status: Inactive

End Date: 1/1/1969

Description: The waste site is the 105-C reactor building, contaminated soils and french drains. It was divided into three subsites: Subsite 1- the inactive plutonium production 105-C Reactor Core that was reclassified to Rejected. Subsite 2- the 105-C Reactor Building Below-Grade Structures and Underlying Soils was reclassified to Closed Out. Subsite 3 - 105-C French Drains was reclassified to Interim Closed Out. Since all the subsites have been reclassified, the parent site is considered Interim Closed Out.

The 118-C-3 site is an inactive reactor building has been reduced in size and placed in Interim Safe Storage (ISS). The original facility consisted of the reactor block, which included the graphite core, thermal shields, pressure tubes, and the safety and control systems. The irradiated

fuel storage basin was constructed below grade.

Location: The site is located in the 100 B/C Area, south of the 105-B reactor.

Release Description: There may have been some seepage from the fuel storage basins, in which case the soil column under the basins may be contaminated. The soil has not been characterized, but the radionuclide inventory is estimated to be low when compared to the total inventory in the reactor.

Process Description: The facility was a water cooled, graphite moderated nuclear reactor that irradiated uranium fuel rods. The plutonium by-product was extracted from the irradiated rods in the 200 Area Fuel Separations plants. Before the reactor was placed into interim safe storage, the original facility consisted of the reactor block, which included the graphite core, biological and thermal shields, pressure tubes, and the safety and control systems. The irradiated fuel storage basin was constructed below grade. The reactor building was constructed with 0.9 to 1.5-meter (3 to 5-foot) thick concrete walls around the reactor core and corrugated asbestos/cement siding upper walls. The original roof construction was reinforced concrete over the inner rod room and the rear face enclosure and poured insulating concrete over the rest of the building.

Waste Type: Equipment

Waste Description: In 1987, the facility was estimated to contain approximately 25,000 curies of radionuclides, 95,000 kilograms (105 tons) of lead, and 200 cubic meters (7000 cubic feet) of asbestos. During the Interim Safe Storage project, approximately 198 cubic meters (6600 cubic feet) of asbestos was removed along with 500 tons of interior and exterior transite panels. During 1996 through 1998, the total estimated inventory of lead was increased to 203 tons. Seventy tons of lead was removed. Material that was radioactively contaminated was take to the Environmental Restoration Disposal Facility (ERDF).

This Site has the Following SubSites:

Code: 118-C-3:1

Names: 118-C-3:1; 105-C Reactor Core and ISS Project

Code: 118-C-3:2

Names: 118-C-3:2; 105-C Ancillary Support Structures and Underlying Soils; 105-C Reactor Building Below-Grade Structures and Underlying Soils

Code: 118-C-3:3

Names: 118-C-3:3; 105-C French Drains

Code: 118-C-3:1

Classification: Accepted

Names: 118-C-3:1; 105-C Reactor Core and ISS Project

Reclassification: Rejected (6/9/2015)

Type: Reactor

Start Date:

Status: Inactive

End Date:

Description: The subsite is the cocooned reactor core. During 1996 through 1998, the reactor building was placed in Interim Safe Storage (ISS) status. It is an above grade structure and has been reclassified to Rejected because it does not meet the definition of a waste site. The safe storage condition is designed to safely contain the reactor for up to 75 years. The process included removing all portions of the reactor facility outside of the reactor core shield walls and capping the roof with Galvalum steel. Electric and water utilities were isolated.

The safe storage enclosure (SSE) consists of the area within the shield walls, including the reactor block, the front-face of the reactor area, the elevator and the rear-face work area. This part of the reactor building will remain in place to act as temporary storage for the reactor

block. As much as was practical, objects and surface contamination were removed. A new roof was added as part of the Interim Safe Storage (ISS) effort. All doors were permanently sealed, except for one door that remains locked and is welded shut. The only planned entrance to this structure is for surveillance and maintenance activities that occur approximately every 5 years.

Location: The site is located in the 100 B/C Area, south of the 105-B reactor.

Process Description: The facility was a water cooled, graphite moderated nuclear reactor that irradiated uranium fuel rods. Water from the Columbia River was extensively treated before passing through the reactor. Water then circulated in a single pass through the reactor process tubes, cooling tubes imbedded in the thermal shield, and reactor horizontal control rods. After exiting the reactor, contaminated cooling water passed through a retention basin and was then discharged to the river.

The SubSite is Part Of:

Code: 118-C-3

Names: 118-C-3; 105-C Reactor Building

Code: 118-C-3:2

Classification: Accepted

Names: 118-C-3:2; 105-C Ancillary Support Structures and Underlying Soils; 105-C Reactor Building Below-Grade Structures and Underlying Soils

Reclassification: Closed Out (8/7/2000)

Type: Reactor

Start Date:

Status: Inactive

End Date:

Description: The waste site has been remediated and reclassified to Closed Out in August 2000. The remedial action involved the decommissioning and decontamination of associated structures and soils at the 105-C Reactor to the extent required leaving only the reactor core to be placed in Interim Safe Storage status. Remediation included the removal of hazardous and radiologically contaminated material from the fuel storage basin, below grade rooms, tunnels and contaminated soils that were adjacent to the reactor core. Contaminated material was disposed of in the Environmental Restoration Disposal Facility (ERDF). The excavated areas were backfilled to grade with clean material.

Location: The site was located in the 100 B/C Area, south of the 105-B reactor.

Closure Info: Interim (8/7/2000): The remedial action involved the decommissioning and decontamination of associated structures and soils at the 105-C Reactor to the extent required leaving only the reactor core to be placed in Interim Safe Storage status. Remediation included the removal of hazardous and radiologically contaminated material from below grade rooms, tunnels and contaminated soils. Contaminated material was disposed of in the Environmental Restoration Disposal Facility (ERDF). The excavated areas were backfilled to grade with clean material.

General remedial actions in the 105-C Reactor Building included surveys and removal of hazardous chemicals, asbestos, equipment, and radiologically contaminated materials, allowing unrestricted release of the below-grade structures. During Initial characterization, concrete cores were removed from the fuel storage basin floor for radiological and chemical analysis. Core samples were collected from the fuel storage basin structure. It was determined that the upper 4.6 meters (15 feet) of the structure needed to be removed. The lower portion of the walls and the floor were left intact. The lift station walls were demolished and removed. Four areas within the below-grade rooms and tunnels were found to exceed the cleanup levels (as measured by the radiological survey), including portions of tunnel section 5, tunnel sections 7 and 9, a portion of the tunnel section 13 wall, and the battery room floor. Decontamination and removal/disposal activities were selectively performed.

A geoprobe sampling device was used to sample the soil at a variety of depths (up to 3.2 meters [10.5 ft]) beneath the concrete. Additional concrete was removed (the upper 4.6 meters [15 ft]) and the lower portion left in place to meet the shallow and deep zone cleanup criteria, respectively. Verification sampling and radiologically surveying of the concrete (to a depth of 0.6 cm [0.25 in]) was conducted for the other below-grade structures and additional concrete and floor drains were removed to meet the cleanup criteria.

The SubSite is Part Of:

Code: 118-C-3

Names: 118-C-3; 105-C Reactor Building

Code: 118-C-3:3

Classification: Accepted

Names: 118-C-3:3; 105-C French Drains

Reclassification Interim Closed Out (4/24/2006)

Type: Reactor

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. It was a collection of four french drains, roughly located at the four corners of the 105-C Reactor Building (northwest, northeast, southwest, southeast). Each french drain was approximately 40.6 centimeters to 61 centimeters (16 inches to 24 inches) in diameter and had a 3.8 centimeter (1.5 inch) pipeline that ran to the french drain. The site is now a gravel field surrounding the cocooned 105-C reactor core.

Location: The control room drain (northwest) was located at N144055/E565344. The outer rod room drain (northeast) was located at N144055/E565376. The electrical equipment room drain (southwest) was located at N143991/E565333. The decontamination room drain (southeast) was located at N143979/E565390.

Closure Info: Interim (4/24/2006): The area around all four drains was disturbed and/or excavated during 105-C Reactor decommissioning activities. The area around the french drain to the southeast of the reactor was extensively excavated during the remediation of the 100-B/C south effluent pipelines. The entire area was backfilled and smoothed to grade after the various excavations. Prior to confirmatory sampling no visual surface indicators of the french drains remained, but no record of their removal or remediation could be found. To ensure complete cleanup of the Hanford Site a document search was conducted and found evidence of a potential liquid waste site. The french drains were likely condensate drains from the sealed steam heating system that would not have been subject to contamination from within the reactor building. However, the exact history of the drains is unknown, hence the need for the confirmatory sampling.

Excavations at the four french drain locations found three of the four drains partially intact. The fourth drain, #4 to the southeast, was not found in the excavation. It is assumed to have been previously removed. The three french drains found were excavated and sampled just below the bottom of the drain. The southeast location was excavated to 4.6 meters (15 ft) below ground surface and sampled at the bottom of the excavation. This sample design follows an agreement with the U.S. Environmental Protection Agency for sampling an analogous french drain at the 105-F Reactor, which was also removed during decontamination and decommissioning activities.

Per the 105-C Reactor Interim Safe Storage Project Final Report, the walls of the structures within the area described were removed to 4.6 meters (15 feet) below grade. The Cleanup Verification Package for the 105-C Reactor Building Below-Grade Structures and Underlying Soils released the soils under the reactor. The french drains were not included in cleanup activities associated with the Cleanup Verification Package for the 100-B-8:1 and 100-C-6:1

100-B/C South Effluent Pipelines.

The SubSite is Part Of:**Code:** 118-C-3**Names:** 118-C-3; 105-C Reactor Building**Code:** 100-D-64**Classification:** Accepted**Names:** 100-D-64; 105-DR Reactor Exhaust Stack Sampling Building; 119-DR; 119-DR Sample Building**Reclassification** Interim Closed Out (3/4/2004)**Type:** Laboratory**Start Date:****Status:** Inactive**End Date:****Description:** The site has been remediated and Interim Closed Out. The site consisted of a single-story, 33.4 square meter (360 square feet), pre-fabricated metal structure on a concrete slab. It was remediated with a large grouping of other waste sites.**Related Sites/ Structures:** 122-DR-1 the 105-DR Large Sodium Fire Facility and the 116-DR Reactor Exhaust Stack (132-DR-2/122-DR-1:5).**Closure Info:** Interim: Note - The 105-DR reactor operated between 1950 and 1964 for plutonium production. In 1973, the exhaust system portions of the 105-DR reactor were reactivated and re-purposed to support the Large Sodium Fire Facility (LSFF). The LSFF (sitecode 122-DR-1) was a RCRA TSD. Most of the components of the reactor exhaust system have two entries in the WIDS database, one representing the CERCLA (radioactive) contaminants and the other representing the RCRA hazardous chemical contaminants.

The portions of the LSFF TSD that are included in this remedial activity are the 117-DR Exhaust Filter Building (100-D-53/122-DR-1:4), the underground exhaust tunnel (122-DR-1:2), the 119-DR Exhaust sample building (100-D-64), two dry wells (100-D-23 and 100-D-54) and the 116-DR Exhaust Stack (132-DR-2/122-DR-1:5) Four of the seven 122-DR-1 subsites (122-DR-1:1, 122-DR-1:3, 122-DR-1:6 and 122-DR-1:7) were closed out under the 105-DR Large Sodium Fire Facility RCRA Closure Plan (LSFF Closure Plan) are were not discussed in the CVP-2003-00018 Cleanup Verification Package.

The remedial objective for the structures was to remove each structure to a minimum of 0.9 meters (3 feet) below surface grade. In July 2003, remedial/removal action activities removed the 117-DR Exhaust Filter Building (100-D-53/122-DR-1:4), the downstream (post-filter) tunnel and the additional 0.9 meters (3 ft) of the 116-DR Reactor Exhaust Stack (132-DR-2/122-DR-1:5). The aboveground portion of the 132-DR stack had been demolished in 1999.

Large Sodium Fire Facility (LSFF) subsite 122-D-1:2 (underground tunnel between the 105-DR Building) and the 117-DR Exhaust Filter Building were entirely removed. The 315 and 316 exhaust plenums, (aka upper and lower exhaust tunnels) are also associated with the 122-D-1:2 subsite. The upper exhaust tunnel and approximately the top 0.9 meters (3 ft) of the lower exhaust tunnel were removed. The 119-DR Exhaust Stack Sampling Building and two stack sampling building dry wells (100-D-23 and 100-D-64) were also demolished and excavated as part of the remedial/removal action activities in July 2003.

At the completion of the remedial action, the total excavation was approximately 1,010 square meters (10,872 square feet) in area with an approximate depth of 5 meters (16.4 feet). Approximately 14,011 metric tons (15,412 tons) of material from the site were disposed of at the Environmental Restoration Disposal Facility.

Code: 100-D-105	Classification: Accepted
Names: 100-D-105; D/DR-Area Pipelines Discovered During Remediation	Reclassification: Interim No Action (1/21/2014)
Type: Product Piping	Start Date:
Status: Inactive	End Date:

Description: The site has been evaluated and determined to require No Action. It consists of seventeen, unrelated pipeline segments. Fourteen were discovered during 100-D/DR remediation activities and determined to be not associated with an existing waste site. Three segments were determined to be segments of pipelines dispositioned with known waste sites. Some pipeline segments were assigned to this grouping following a spatial analysis of the pipeline geographic information system (GIS) assignments with those contained in regulator approved work instructions and closure documents. Some of the pipeline segments were either not assigned to a waste site or incorrectly assigned to a waste site when compared to the documents.

The following pipeline segments have been included in this waste site:

Segment 1 is a metal pipe that was discovered while excavating the 100-D-31:3 pipelines. The Segment 1 pipeline was located between the 108-D and 1703-D Buildings and extended north to south for a distance of at least 28 meters (92 ft) in two segments. The northern segment was observed in the 100-D-31:3 pipelines excavation and the southern segment of the pipeline was identified using geophysics. The diameter of the pipe was not documented.

Segment 2 is a 20 cm (8-in.) diameter, north to south oriented metal pipe discovered while excavating the 100-D-31:3 pipelines. The Segment 2 pipeline was located between the 1727-D Building and the 187-D1 Emergency Water Tank. The total length of the pipeline was determined to be approximately 95 meters (312 ft). The northernmost 20 meters (66 ft) of pipe was removed during remediation of 100-D-31:3.

Segment 3 is a metal pipe that was discovered while excavating the 100-D-31:3 pipelines. The Segment 3 pipe was located 8 meters (26 ft) south of the 1731-D Building and extended east to west a distance of at least 11 meters (36 ft). The diameter of the pipe was not documented.

Segment 4 is a metal pipe that was discovered while excavating the 100-D-31:3 pipelines. The Segment 4 pipe extended from the north end of the 1731-D Building south for 32 meters (105 ft) before turning west. Segment 4 then extended another 53 meters (174 ft) before turning south again and continuing under the 1726-D Building. The diameter of the pipe was not documented.

Segment 5 is a north-to-south oriented metal pipe that was discovered while excavating the 100-D-31:3 pipelines. The segment 5 pipe also fell within the boundary of the 100-D-56:1 pipeline excavation. The 100-D-56:1 excavation was approximately 1 meter (3 ft) deep in the area of the segment 5 pipeline. Segment 5 was located just east of the 1726-D Building and was adjacent to the segment 4 pipeline at this location. The diameter of the pipe was not documented.

Segment 6 is a 15 cm (6-in.) diameter metal pipe discovered while excavating the 100-D-31:3 pipelines. The Segment 6 pipe was located just west of the 1701-DA Building and extended 14 m (46 ft) to the west, into the 100-D-31:3 excavation.

Segment 7 is an 8 cm (3-in.) diameter pipe discovered while excavating the 100-D-31:1 pipelines. The Segment 7 pipe was located in the 100-D-31:1 excavation approximately 141 meters (463 ft) north of D Avenue. The pipe was oriented east to west and was identified as

miscellaneous pipeline (MP) "MP-1" in the Remaining Sites Verification Package for 100-D-31:1, the 1607-D2 Septic Sewer Pipeline, and 100-D-31:2, the 1700-D Series Buildings Septic Sewer Pipelines.

Segment 8 is a 20 cm (8-in.) diameter pipe discovered while excavating the 100-D-31:2 pipelines. The Segment 8 pipe was located in the 100-D-31:2 excavation, approximately 19 meters (62 ft) east of the 1713-D Building. The Segment 8 pipe was oriented north to south and was identified as "MP-3" in the RSVP for 100-D-31:1 and 100-D-31:2.

Segment 9 is a 15 cm (6 in.) diameter cast iron pipe discovered while excavating the 100-D-31:2 pipelines. The Segment 9 pipe was located in the 100-D-31:2 excavation approximately 6 meters (20 ft) west of the 1713-D Building. The Segment 9 pipe was oriented north to south and was identified as "MP-5" in the RSVP for 100-D-31:1 and 100-D-31:2.

Segment 10 is a 10 cm (4 in.) diameter pipe discovered while excavating the 100-D-31:2 pipelines. The Segment 10 pipe was located in the 100-D-31:2 excavation approximately 10 meters (33 ft) west of the southeast corner of the 1717-D Building. The Segment 10 pipe was oriented north to south and was identified as "MP-8" in the RSVP for 100-D-31:1 and 100-D-31:2.

Segment 11 is a 25 cm (10 in.) diameter steel pipe discovered while excavating the 100-D-31:6 pipelines. The Segment 11 pipe was located in the 100-D-31:6 excavation approximately 72 meters (236 ft) east of the 1901-D Soft Water Tank. The Segment 11 pipeline location is also entirely within the former 100-D-31:7 pipelines excavation boundary in the upper west sidewall area of the excavation. The Segment 11 pipeline was oriented north to south and was identified as "MP-6" in the Remaining Sites Verification Package for the 100-D-31:6, 184-D Powerhouse Sewer Pipelines.

Segment 12 is a 10 cm (4 in.) diameter cast iron pipe discovered while excavating the 100-D-8 Process Sewer Outfall. The Segment 12 pipe was oriented east to west and was estimated to be at least 74 meters (243 ft) long based on ground-penetrating radar geophysics data. The pipe is located approximately 100 meters (328 ft) south of the 1907-DR Outfall Structure.

Segment 13 is a previously unassigned french drain and the associated 3.8 cm (1.5 in.) diameter drain line observed on drawing H-1-9006-DR. These features are associated with the desert cooler and drinking fountain at the 1702-DR Badge House.

Segment 14 is a steel pipe that was discovered while excavating the 100-D-32 waste site. The Segment 14 pipe was uncovered along the southwest corner of the 100-D-32 excavation sidewall at approximately 0.6 meter (2 ft) below grade. Segment 14 is located in the vicinity of a temporary sanitary water line that is part of the 100-D-63 Service Water Pipelines waste site. A linear feature that was observed on the geophysical investigation for 100-D-32 corresponds to the location of Segment 14 and indicated the pipe continued to the west.

Segment 15 is a 30 cm (12 in.) diameter east to west oriented pipe discovered while excavating the 100-D-1 waste site. Due to its location, the Segment 15 pipeline was initially thought to be associated with the 1904-D Spillway (sitecode 100-D-65), but there was not enough information to support that premise.

Segment 16 is a 1.9 cm (0.75 in.) diameter sodium silicate pipeline extending from the sodium silicate storage tank located in the pipe tunnels between 105-D and 190-D to the 30 cm (12 in.) diameter filtered water line to the 187-D1 Emergency Water Tank and the 30-cm (12 in.) diameter filtered water line to the 187-D2 Emergency Water Tank. Both 30 cm (12 in.) filtered water pipes that received the sodium silicate solution are part of the 100-D-63 waste site. Segment 16 pipelines carried sodium silicate only.

Segment 17 is a 1.9 cm (0.75 in.) diameter sodium silicate pipeline extending from the sodium silicate storage tank located in the pipe tunnels between 105-DR and 190-DR to the two 30 cm (12 in.) diameter filtered water lines that lead to either the 187-DR1 or 187-DR Emergency Water Tanks. Both 30 cm (12 in.) filtered water pipes that received the sodium silicate solution are part of the 100-D-63 waste site. Segment 17 pipelines carried sodium silicate only.

Location: The pipeline segments are located throughout the 100-D/DR Area.

Process Description: There is no process history associated with the 100-D-105 waste site.

Closure Info: Interim (1/21/2014): The 100-D-105 waste site consists of 17 unrelated pipeline segments in the 100-D/DR Area. Fourteen segments were discovered during remediation of unrelated waste sites. These 14 pipelines were determined not to be associated with any existing waste site based on spatial analysis of the GIS assignments of these pipelines with those contained in regulator-approved work instructions and closure documents. The pipeline segments were either not assigned to a waste site or were found to be incorrectly assigned to a waste site when compared to the regulator-approved documents.

Pipeline Segments 1 through 12, 14, and 15 were discovered during remediation of unassociated waste sites. The process history of these pipelines is not known. Confirmatory sampling was done at the locations of these segments. The remaining Segments (13, 16, and 17) were previously unassigned pipelines with known process history. Segment 13 is a pipe and french drain associated with a drinking fountain. Segments 16 and 17 transported sodium silicate, which is not a regulated chemical. No confirmatory sampling was required for these three segments.

Confirmatory samples were collected from test pits at the pipe segment locations. The depths ranged from 0.9 meters to 4.6 meters.

Code: 100-D-106	Classification: Accepted
Names: 100-D-106; 1607-D1 Influent Pipelines	Reclassification: Interim Closed Out (1/30/2015)
Type: Sanitary Sewer	Start Date:
Status: Inactive	End Date:

Description: The site has been remediated and Interim Closed Out. It consisted of the sanitary sewer pipelines that connected the service buildings at the 100-D main gate to the 1607-D1 septic tank. It also includes a french drain approximately 21 meters (70 ft) north of the demolished 1709-D building.

Location: The 100-D main gate (1701-D) was located approximately 1 kilometer (0.6 miles) southeast of the 105-D Reactor Building.

Related Sites/Structures: 1701-D Gate House, 1709-D Fire Headquarters, 1720-D Patrol Headquarters and the 1607-D1 septic tank.

Process Description: The site provided sanitary service for patrol and fire personnel located at the entrance to the 100-D/DR Reactor Area.

Closure Info: Interim (1/30/2015): Contamination was discovered in the 1607-D1 septic tank and drain field, which was the basis for remediation of the pipelines. Remedial action at the 100-D-106 waste site was performed from March 31, 2014, until April 2, 2014. Approximately 1,600 bank cubic meters (2,093 bank cubic yards) of excavated materials were removed and staged within the staging pile area (SPA) waiting for disposal at the Environmental Restoration Disposal Facility.

The maximum depth of the pipeline excavation was approximately 1.2 meters (4 ft) below ground surface (bgs). The depth of the remediation where the french drain was taken out was approximately 4.4 meters (10 ft) bgs. Excavated materials consisted of concrete encased 15.2 centimeter (6 in.) diameter vitrified clay pipe, concrete from foundations, asphalt debris from roadways, a french drain, soil, gravel, and approximately 285 linear meters (935 linear feet) of pipe debris. There were no anomalies present and there was no stained soil observed.

Code:	100-D-107	Classification:	Accepted
Names:	100-D-107; Soil beneath the 1713-DA Essential Materials Warehouse	Reclassification	Interim No Action (4/16/2014)
Type:	Unplanned Release	Start Date:	
Status:	Inactive	End Date:	
Description:	The site was evaluated and determined to require No Action. It consisted of the soil beneath and surrounding the demolished 1713-DA Essential Materials Warehouse. It is assumed the building was demolished during the mid-1950's. The 1713-DA Essential Materials Warehouse is analogous in operation to 1713-BA. The sodium dichromate contamination at 1713-BA (100-B-27) was directly related to operations in the 1713-BA Building. It is unknown whether or not there are any releases at 1713-DA from the operations involving sodium dichromate.		
Location:	The 1713-DA building had been located near the intersection of Pump House Loop and Puyallup Street. The site was located 30 meters (98 ft) north of the 126-D-2 Coal Pit.		
Related Sites/ Structures:	The waste site is associated with 100-B-27.		
Process Description:	The 1713-DA Building was used as the main receiving and storage warehouse in support of the initial construction of the 100D Area. After the end of the construction period, the building was kept in use as the Essential Materials Warehouse. During the 1940s and/or 1950s, the building may have been used to store solid sodium dichromate, which was classified as an essential material. Additional items that may have been stored within the building include other dry chemicals used in the 100D Area (e.g. lime, oxalic acid, etc.), spare parts and equipment. Sodium dichromate was used as an additive to the process cooling water for the 105-D and 105-DR Reactors as a corrosion inhibitor.		
Closure Info:	Interim (4/16/2014): Confirmatory sampling was performed on July 17, 18, and 23, 2013 from Test Trenches. Confirmatory sampling results, in conjunction with field instrumentation screening results, indicate that the residual concentrations of COPCs at this site meet the RAGs for direct exposure, groundwater protection, and river protection. In accordance with this evaluation, the confirmatory sampling investigation results support a reclassification of the 100-D-107 waste site to Interim No Action.		

Code:	100-D-108	Classification:	Accepted
Names:	100-D-108; 182-D Remaining Pipeline Stubs	Reclassification	None
Type:	Process Sewer	Start Date:	
Status:	Inactive	End Date:	
Description:	The waste site consists of the stubbed pipeline segments adjacent to the 182-D water reservoir structure that remained after remediation of 100-D-31 pipelines. These segments were left in place to preserve the structural integrity of the active 182-D water reservoir.		

The piping stubs include:

A 15.24 centimeter (6 in) cast iron process sewer that exits the 182-D Inlet House No. 1 and received raw water from the cone valves.

A 15.24 centimeter (6 in) cast iron process sewer that exits the 182-D Inlet House No. 2 and received raw water from the cone valves.

A 20 centimeter (8 in) vitrified clay process sewer that connected the sewers from the two Inlet Houses with a 91.4 centimeter (36 in) process sewer. It exits on the northeast side of the 182-D Reservoir and received raw water from the overflow.

A 106.7 centimeter (42 in) process sewer line that exits the east corner of the building and received raw water from the 182-D Pump House.

A 15 centimeter (6 in) vitrified clay sewer pipe that exits the east side of the 182-D and received sanitary waste from the laboratories in the 182-D Pump House.

Location: The pipeline segments are located adjacent to the north and east sides of the 182-D water reservoir.

Related Sites/ Structures: The stubbed pipelines are associated with the 182-D Reservoir.

Code: 100-D-109	Classification: Accepted
Names: 100-D-109; 183-D Remaining Pipeline Stubs	Reclassification: None
Type: Process Sewer	Start Date:
Status: Inactive	End Date:

Description: The waste site consists of the stubbed pipeline segments adjacent to the 183-D clearwell structure that remained after remediation of 100-D-31 pipelines. These segments were left in place to preserve the structural integrity of the 183-D clearwell bat habitat.

The pipe segments include:

A 20 centimeter (8 in) cast iron sanitary sewer exits the east side of the 183-D building and received sanitary waste from the pump room.

A 106.7 centimeter (42 in) process sewer line that exits the east side of the 183-D building and received filtered water from the 183-D Pump Room.

Location: The pipelines are located adjacent to the north and east sides of the 183-D clearwell structure.

Code: 118-D-6	Classification: Accepted
Names: 118-D-6; 105-D Reactor Building	Reclassification: Interim Closed Out (2/18/2015)
Type: Reactor	Start Date: 1/1/1944
Status: Inactive	End Date: 1/1/1967

Description: 118-D-6 is the 105-D Reactor Building and related support structures. It was divided into four subsites. All of the subsites have been reclassified, so the parent site is considered to be Interim Closed Out. Subsite 1 is the cocooned reactor core, that has been placed in Interim Safe Storage (ISS). It includes the graphite moderator (blocks) stack, biological and thermal shields, pressure

tubes, and the safety and control systems. These were all above grade items and reclassified to Rejected. Subsite 2 is the Ancillary Support Areas, Below-Grade Structures and Underlying Soils the irradiated fuel storage basin. These have been addressed and reclassified to Interim Closed Out. Subsite 3 is the Fuel Storage Basin and Underlying Soils. These items have been addressed and reclassified to Interim Closed Out. Subsite 4 is the 105-D Fuel Storage Basin Side Slope Soils. This slope has been addressed and Interim Closed Out. Following remedial activities, radiological postings were removed per WCH Interoffice Memorandum #179973, dated July 13, 2015.

Location: The 105-D Reactor site is located in the 100-D Area approximately 250 meters (820 feet) north of the 105-DR Reactor.

Release Description: It is suspected that the irradiated fuel storage basin leaked for a number of years prior to deactivation.

Process Description: Between 1942 and 1955, eight water-cooled, graphite-moderated production reactors were constructed along the Columbia River in the 100 Areas of the Hanford Site. The construction of the first three Hanford reactor facilities (B, D, and F Reactors) utilized the same design drawings. The 105-D Reactor facility is located in the 100-D Area of the Hanford Site. Construction of the D Reactor was initiated in November 1943. Initial startup of the reactor was achieved on December 17, 1944. The D Reactor was shut down on June 26, 1967. Since deactivation, the 105-D Reactor has been in a condition of minimum surveillance and maintenance (S&M). Significant deterioration had occurred, particularly in the roof sections over the fan room and work area. Permanent decommissioning alternatives for the Hanford Site production reactors were assessed in the Final Environmental Impact Statement, Decommissioning of the Eight Surplus Production Reactors at the Hanford Site (DOE 1992). A Record of Decision (ROD) was issued by the U.S. Department of Energy (DOE) (58 Federal Register 48509). The ROD alternative selected was to place the reactors into a safe storage condition for up to 75 years. After Interim Safe Storage (ISS), the reactors would be transported in one piece to a specially prepared burial facility in the 200 West Area of the Hanford Site. The original footprint area of the 105-D Reactor Building was approximately 4,994 meters squared (53,750 square feet). The final ground-level footprint area of the safe storage enclosure (SSE) is 999 meters squared (10,750 square feet). The areas of the reactor building that have been removed to ERDF represent 80% of the original footprint of the reactor building.

Waste Type: Equipment

Waste Description: This unit contained an estimated 21,500 curies of radionuclides, 85,000 kilograms (94 tons) of lead, and 2.8 cubic meters (100 cubic feet) of asbestos. The primary source of contamination at the 105-D site was reactor coolant water and water in the FSB (118-D-6:3) that became contaminated through contact with irradiated and ruptured fuel elements and components from the reactor cooling system. The water was believed to have contaminated the concrete surfaces of the FSB. No documentation of basin water leakage into the underlying soils was discovered during the cleanup activities.

This Site has the Following SubSites:

Code: 118-D-6:1

Names: 118-D-6:1; Safe Storage Enclosure (SSE); 105-D Reactor Core and ISS Project

Code: 118-D-6:2

Names: 118-D-6:2; 105-D Ancillary Support Structures and Underlying Soils; 105-D Below-Grade Structures and Underlying Soils

Code: 118-D-6:3

Names: 118-D-6:3; 100-D FSB; 105-D Reactor Fuel Storage Basin and Underlying Soils

Code: 118-D-6:4
Names: 118-D-6:4; 105-D Fuel Storage Basin Side Slope Soils

Code: 118-D-6:1 **Classification:** Accepted
Names: 118-D-6:1; Safe Storage Enclosure (SSE); 105-D Reactor Core and ISS Project **Reclassification** Rejected (2/18/2015)
Type: Reactor **Start Date:**
Status: Inactive **End Date:**

Description: Subsite 1 is the cocooned reactor core, that has been placed in Interim Safe Storage (ISS), also known as safe storage enclosure (SSE). It is an above grade structure and has been reclassified to Rejected because it does not meet the definition of a waste site. It contains the shield walls, the graphite reactor block, the front-face, the elevator, the rear-face work area and miscellaneous areas (rooms 113a, 115a, and 254). This part of the reactor building will remain in place to act as temporary storage for the reactor block. As much as was practical, objects and surface contamination were removed. A new roof was added as part of the Interim Safe Storage (ISS) effort. All doors were permanently sealed except for one door that remains locked and is welded shut. The only planned entrance to this structure is for surveillance and maintenance activities that occur approximately every 5 years. Following remedial activities, radiological postings were removed per WCH Interoffice Memorandum #179973, dated July 13, 2015.

The original footprint area of the 105-D Reactor Building was approximately 4,994 square meters (53,750 square feet). The final ground-level footprint area of the safe storage enclosure (SSE) was reduced to 999 square meters (10,750 square feet). The areas of the reactor building that have been removed to ERDF represent 80% of the original footprint of the reactor building.

Location: The 105-D Reactor site is located in the 100-D Area approximately 250 meters (820 feet) north of the 105-DR Reactor.

The SubSite is Part Of:

Code: 118-D-6
Names: 118-D-6; 105-D Reactor Building

Code: 118-D-6:2 **Classification:** Accepted
Names: 118-D-6:2; 105-D Ancillary Support Structures and Underlying Soils; 105-D Below-Grade Structures and Underlying Soils **Reclassification** Interim Closed Out (7/27/2005)
Type: Reactor **Start Date:**
Status: Inactive **End Date:**

Description: The subsite has been remediated and Interim Closed Out. It is the below grade structures and soil adjacent to the 105-D reactor building. For remediation purposes, the area was divided into several Demolition Zones and the 132-D stack foundation. The Demolition Zones in subsite 118-D-6:2 are:

Demolition zone 1, located on the north side of the original reactor building, consisted of the water tower pedestal, the 103-D Unirradiated Fuel Element Storage Building, miscellaneous storage room 210, and room 215 on the ground level.

Demolition zone 2 was located on the west side of the original reactor building. At ground level this zone consisted of the 230a valve pit, the 310 supply fan room, the 231d tool room, the 231b

laundry storage room, the 230b elevator and the 228a, 228b, 228c, 228d, 229a, and 229b offices.

Demolition zone 3 was located on the south side of the original reactor building. At ground level this zone consisted of the 311, 312, 313, and 314 fan rooms, 315 exhaust plenum, 114a clean storage room, 114b contaminated storage room, 213 stairway/corridor, 233a sample room and miscellaneous rooms 234 and 235.

Demolition zone 5 was located on the north side of the original reactor building. At ground level this zone consisted of the 211, 212, 218, and 219 miscellaneous rooms, the 220 control room, the inner horizontal control rod room, the outer horizontal control rod room and miscellaneous rooms numbered 222, 223, 224, 225, and 227.

Note: Demolition Zone 4, the fuel storage basin, became Subsite 118-D-6:3 and the fuels storage basin side slopes became Subsite 118-D-6:4.

Location: The 105-D Reactor site is located in the 100-D Area approximately 250 meters (820 feet) north of the 105-DR Reactor.

Closure Info: Interim: In 1984 when the reactor shut down, the Fuel Storage Basin (FSB) water level was lowered and the basin was cleaned out. Ruptured fuel elements had caused the shielding water to become highly contaminated. The remaining water was processed and released to 116-D-10 pond. Then an asphalt emulsion was applied to the floors and walls of the basin to fix the loose contamination to the basin structure. The hardware remaining in the basin (perfs, buckets, and sludge) were packaged and disposed of as low-level radioactive waste in the 200 Area burial grounds. The 132-D-4 stack was demolished and remediated to a depth of 0.9 meters (3 ft) below grade in 1999.

Removal and disposal activities at the 105-D site began in January 2000. For remediation purposes, the reactor area was divided into several Demolition Zones, the reactor core and the remaining portion of 132-D stack foundation. These areas were surveyed, and contamination was removed in preparation for clean demolition. With the exception of the Fuel Storage Basin walls and floor below 4.6 meters (15 feet), all structures in this zone were removed due to surface contamination being present. Sampling of underlying soils was not required because structures in this zone were not subjected to standing contaminated water and there was no mechanism for residual surface contamination to penetrate into the concrete and the underlying soil. The above and below grade structures were demolished. The demolition debris sent to ERDF. A section of 100-D-48:4 effluent pipeline remains buried under what was room 210. This section of pipeline will be considered separately from Demolition Zone 1 and deferred to the Remedial Action Project.

All known flammable and hazardous material was removed inside and outside of the Safe Storage Enclosure (SSE), with the exception of non-removable lead, generally in the form of lead-based paint inside the SSE. Concentrations of lead in the lead-based paint were determined to be below regulatory limits. After the hazardous materials were removed, the above and below grade structures at the 105-D site were ready for demolition. The above-grade structures were demolished, the overburden around the foundations was excavated, and the below-grade structures were demolished. During the demolition process, the resulting debris was loaded out and shipped to ERDF for disposal. The 105-D site D&D activities included complete removal of above-grade structures outside of the 105-D Reactor core shield walls. A majority of the below-grade structures outside of the 105-D Reactor core shield walls were completely demolished. A portion of the south wall of the valve pit area (demolished to 0.9 meters [3 ft] below grade) and the entire Fuel Storage Basin floor and a portion of the walls (demolished to 4.6 meters [15 ft] below grade) were left in place based on deep zone cleanup criteria. The overburden piles produced during excavation were found to be contaminated. The overburden was deemed unsuitable for use as backfill of the site and was disposed in ERDF. The site was

backfilled with clean soil/aggregate, using material from Borrow Pit 21 and graded to match the surrounding terrain. The 105-D D&D activities generated approximately 1,585 bulk containers of low-level contaminated material that were shipped to ERDF, accounting for approximately 21,613 metric tons (23,824 tons).

It was determined in the Sampling and Analysis Plan for Interim Closure of the 105-D and 105-H Reactor Below-Grade Structures and Underlying Soils that the 105-D FSB would not be cored to sample the underlying soils because this Fuel Storage Basin was not known to have leaked (the water level variations were consistent with evaporation). Coring would have been very difficult and potentially unsafe. The soils beneath the 100-C and 105-DR FSBs were found to be clean. The 100-D Reactor Site Technical Baseline Report suggests that all of the FSBs had leaked. However, this statement is not supported by the process history of the 105-D FSB. Sampling of the underlying soils at the 105-C and 105-DR FSBs showed that they had not leaked. The FSB concrete floors from all of the previously decommissioned reactors were found to have various types of contamination that penetrated only a maximum of a few millimeters into the concrete. Sampling showed the contamination had not penetrated through the 0.3 to 0.6 meters (1 to 2 feet) of concrete in the FSB floors.

The north decontamination pad, a section of 100-D-48:4 effluent pipeline, and the FSB side-slope soils remained to be addressed, having been deferred to the Remedial Action Project.

The SubSite is Part Of:

Code: 118-D-6

Names: 118-D-6; 105-D Reactor Building

Code: 118-D-6:3

Classification: Accepted

Names: 118-D-6:3; 100-D FSB; 105-D Reactor Fuel Storage Basin and Underlying Soils

Reclassification: Interim Closed Out (7/27/2005)

Type: Reactor

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. It was the 105-D fuel storage basin and the soil beneath the basin. For the purpose of removal, the reactor facility was divided into several Demolition Zones. Subsite 118-D-6:3 consisted of only Demolition Zone 4, that was located on the east side of the original reactor building. At ground level, Zone 4 included of the 400 FSB, the 411 wash pad, the 413, 413a, and 413b transfer bay areas, the 414a valve control room and miscellaneous rooms 414 and 415.

Location: The 105-D Reactor site is located in the 100-D Area approximately 250 meters (820 ft) north of the 105-DR Reactor.

Closure Info: Interim: In 1984 when the reactor shut down, the Fuel Storage Basin (FSB) water level was lowered and the basin was cleaned out. Ruptured fuel elements had caused the shielding water to become highly contaminated. The remaining water was processed and released to 116-D-10 pond. Then an asphalt emulsion was applied to the floors and walls of the basin to fix the loose contamination to the basin structure. The hardware remaining in the basin (perfs, buckets, and sludge) were packaged and disposed of as low-level radioactive waste in the 200 Area burial grounds. The 132-D-4 stack was demolished and remediated to a depth of 0.9 meters (3 ft) below grade in 1999.

Removal and disposal activities at the 105-D site began in January 2000. For remediation purposes, the reactor area was divided into several Demolition Zones, the reactor core and the remaining portion of 132-D stack foundation. These areas were surveyed, and contamination

was removed in preparation for clean demolition. With the exception of the Fuel Storage Basin walls and floor below 4.6 meters (15 feet), all structures in this zone were removed due to surface contamination being present. Sampling of underlying soils was not required because structures in this zone were not subjected to standing contaminated water and there was no mechanism for residual surface contamination to penetrate into the concrete and the underlying soil. The above and below grade structures were demolished. The demolition debris sent to ERDF. A section of 100-D-48:4 effluent pipeline remains buried under what was room 210. This section of pipeline will be considered separately from Demolition Zone 1 and deferred to the Remedial Action Project.

All known flammable and hazardous material was removed inside and outside of the Safe Storage Enclosure (SSE), with the exception of non-removable lead, generally in the form of lead-based paint inside the SSE. Concentrations of lead in the lead-based paint were determined to be below regulatory limits. After the hazardous materials were removed, the above and below grade structures at the 105-D site were ready for demolition. The above-grade structures were demolished, the overburden around the foundations was excavated, and the below-grade structures were demolished. During the demolition process, the resulting debris was loaded out and shipped to ERDF for disposal. The 105-D site D&D activities included complete removal of above-grade structures outside of the 105-D Reactor core shield walls. A majority of the below-grade structures outside of the 105-D Reactor core shield walls were completely demolished. A portion of the south wall of the valve pit area (demolished to 0.9 meters [3 ft] below grade) and the entire Fuel Storage Basin floor and a portion of the walls (demolished to 4.6 meters [15 ft] below grade) were left in place based on deep zone cleanup criteria. The overburden piles produced during excavation were found to be contaminated. The overburden was deemed unsuitable for use as backfill of the site and was disposed in ERDF. The site was backfilled with clean soil/aggregate, using material from Borrow Pit 21 and graded to match the surrounding terrain. The 105-D D&D activities generated approximately 1,585 bulk containers of low-level contaminated material that were shipped to ERDF, accounting for approximately 21,613 metric tons (23,824 tons).

It was determined in the Sampling and Analysis Plan for Interim Closure of the 105-D and 105-H Reactor Below-Grade Structures and Underlying Soils that the 105-D FSB would not be cored to sample the underlying soils because this Fuel Storage Basin was not known to have leaked (the water level variations were consistent with evaporation). Coring would have been very difficult and potentially unsafe. The soils beneath the 100-C and 105-DR FSBs were found to be clean. The 100-D Reactor Site Technical Baseline Report suggests that all of the FSBs had leaked. However, this statement is not supported by the process history of the 105-D FSB. Sampling of the underlying soils at the 105-C and 105-DR FSBs showed that they had not leaked. The FSB concrete floors from all of the previously decommissioned reactors were found to have various types of contamination that penetrated only a maximum of a few millimeters into the concrete. Sampling showed the contamination had not penetrated through the 0.3 to 0.6 meters (1 to 2 feet) of concrete in the FSB floors.

The north decontamination pad, a section of 100-D-48:4 effluent pipeline, and the FSB side-slope soils remained to be addressed, having been deferred to the Remedial Action Project.

The SubSite is Part Of:

Code: 118-D-6

Names: 118-D-6; 105-D Reactor Building

Code: 118-D-6:4

Classification: Accepted

Names: 118-D-6:4; 105-D Fuel Storage Basin Side Slope Soils

Reclassification Interim Closed Out (12/21/2011)

Type: Reactor**Start Date:****Status:** Inactive**End Date:**

Description: This subsite has been remediated and Interim Closed Out. The subsite consisted of the side slope soils associated with the Fuel Storage Basin, a former decontamination pad and one segment of an effluent pipeline. The Fuel Storage Basin (FSB) side slopes were located just outside of the remaining structure of the 105-D FSB, on the east side of the original reactor building. The side slopes could not be completely remediated during the demolition of the Fuel Storage Basin (118-D-6:3). Subsequent characterization identified a contamination plume in the adjacent soil. The decontamination areas consisted of two pads that were located on the north and south sides of the reactor for the purpose of equipment decontamination during D. The two areas were considered together during variance and verification sampling. During field screening and sampling, the area of the north decontamination pad was found to be larger than addressed for the sample design. On the north side of the decontamination pad area, a segment of the 100-D-48:4 effluent pipeline (beneath room 210) could not be removed during the reactor D activities. The contamination from the pipeline was not fully remediated during that remedial action because of interferences with reactor removal activities and the potential to cause structural problems for the foundation of the reactor. Both the remaining effluent pipeline segment and the remaining area for the north decontamination pad were included in the 118-D-6:4 subsite and deferred to the Remedial Action Project for remediation and cleanup verification. Following the remediation activities, the radiological postings were approved to be removed in October 2012.

Location: The 105-D Reactor site is located in the 100-D Area approximately 250 meters (820 ft) north of the 105-DR Reactor. The fuel storage basin was on the east side of the reactor.

Closure Info: Interim (12/21/2011): The Fuel Storage Basin (FSB) side slopes could not be completely remediated during demolition of the 118-D-6:3 FSB. The FSB remediation was halted in 2003 and clean fill was used to stabilize the excavation in support of the 105-D Reactor safe storage enclosure roof installation. It was documented that residual radiological contamination remained below the clean fill. The side slopes were placed in a separate subsite (118-D-6:4) for future remedial action. Part of the northern decontamination pad and the area adjacent to a remaining section of effluent pipeline beneath 105-D Reactor Room 210, that could not be removed during remediation of the 100-D-48 pipelines, were also included in remediation of the 118-D-6:4 subsite. Remediation of the 118-D-6:4 subsite was performed from May 5, 2008 through August 24, 2009. The comparison of the 2008-2009 excavation footprint and the 2003 remediation was performed to confirm that the current activities were comprehensive in removing the volume of clean fill and accessing the remaining contaminated material. All material excavated from the 2008-2009 118-D-6:4 subsite remediation was removed and disposed at ERDF. There was no overburden material associated with the waste site. Borehole sampling was performed within the 118-D-6:4 excavation to support the remedial investigation. Borehole #C7857 was drilled in January 2011 to a depth of approximately 27 meters (90 ft) below ground surface.

Two areas containing suspect anomalous materials were found during remediation: the first anomaly was less than 0.76 cubic meters (1 cubic yard) of red-stained soil in the FSB side slope soils approximately 3 meters (12 feet) below grade. The material appeared to be soil stained from either FSB sediments or an effluent pipeline leak from a north-south pipeline in the area. Effluent pipeline leaks at other 100 Area sites have often exhibited rusty, salmon colored staining on adjacent soils. The anomalous red-stained soil material was disposed at ERDF. The second anomaly was dust suppression and rain water retained within the soil in the residual FSB concrete structure. The material was excavated and disposed at ERDF.

The SubSite is Part Of:

Code: 118-D-6
Names: 118-D-6; 105-D Reactor Building

Code: 118-DR-2	Classification: Accepted
Names: 118-DR-2; 105-DR; 105-DR Reactor Building	Reclassification: Interim Closed Out (2/18/2015)
Type: Reactor	Start Date: 1/1/1950
Status: Inactive	End Date: 1/1/1964

Description: The waste site is the 105-DR Reactor facility. It was divided into two subsites. Both subsites have been reclassified, so the parent site is considered to be Interim Closed Out. Subsite 1 is the cocooned reactor core. It includes the above-grade graphite (block) moderator stack, the biological and thermal shields, the pressure tubes, and the safety and control systems. It was reclassified to Rejected. Subsite 2 is 105-DR Reactor ancillary support areas below-grade structures and underlying soil. It was reclassified to Interim Closed Out.

Location: The site was located at the south end of the 100 D/DR Exclusion Fence.

Release Description: It was suspected that the irradiated fuel storage basin leaked for a number of years prior to deactivation. The leakage rate was minimal, and the location of the leaks were never identified, with the exception of one leak outside of Door 14, that was identified and repaired in 1957.

Process Description: Construction of the 105-DR Reactor began in December 1947 and startup was achieved on October 3, 1950. The facility was a water cooled, graphite moderated nuclear reactor that irradiated uranium fuel rods. The design of the facility was based on the earlier Hanford Site reactors (118-D-6 and 118-F-8). Construction drawings of the older facilities were modified to form the design drawings for the 105-DR Reactor. The 105-DR Reactor was shut down on December 30, 1964. Deactivation of the reactor was completed in early 1971. Between 1972 and 1986, the southwest portion of the 105-DR Reactor building was used as a research laboratory known as the 105-DR Large Sodium Fire Facility (LSFF).

Since deactivation, the 105-DR Reactor has been in a condition of minimum surveillance and maintenance. Significant deterioration had occurred, particularly in the roof sections over the fan room and work area. Permanent decommissioning alternatives for the Hanford Site production reactors were assessed in the Final Environmental Impact Statement, Decommissioning of the Eight Surplus Production Reactors at the Hanford Site (DOE 1992). A Record of Decision (ROD) was issued by the U.S. Department of Energy (DOE) (58 Federal Register 48509). The ROD alternative selected was to place the reactors into a safe storage condition for up to 75 years. After Interim Safe Storage (ISS), the reactors would be transported in one piece to a specially prepared burial facility in the 200 West Area of the Hanford Site.

Waste Type: Equipment

Waste Description: This unit contained radiation levels estimated at 13,500 curies, 85,300 kilograms (94 tons) of lead, 2.8 cubic meters (100 cubic feet) of asbestos, and 230 kilograms (500 pounds) of cadmium.

This Site has the Following SubSites:

Code: 118-DR-2:1
Names: 118-DR-2:1; 105-DR Reactor Core and ISS Project

Code: 118-DR-2:2
Names: 118-DR-2:2; 105-DR Ancillary Support Structures and Underlying Soils; 105-DR Reactor Below-Grade Structures and Soil

Code: 118-DR-2:1	Classification: Accepted
-------------------------	---------------------------------

Names: 118-DR-2:1; 105-DR Reactor Core and ISS Project
Reclassification: Rejected (2/18/2015)

Type: Reactor
Start Date:

Status: Inactive
End Date:

Description: Subsite 1 is the cocooned reactor core. All of the components are above-grade. Therefore the cocooned structure was reclassified to Rejected. It includes the graphite (block) moderator stack, the biological and thermal shields, the pressure tubes, and the safety and control systems. The Interim Safe Storage project at 105-DR Reactor included removing all portions of the reactor facility outside of the reactor block shield walls. The 105-DR ISS Project began January of 1998 and was completed in January 2003. The areas removed included the Fuel Storage Basin (FSB), outer rod room, control room, electrical room, switchgear room, lunch room, office space, fan supply and exhaust rooms, sample rooms, ready room, upper reactor framing and roofing, and other miscellaneous rooms and tunnels. The original footprint area of the reactor building was approximately 4,013 square meters (43,200 square feet). The final footprint area of the safe storage enclosure is 892 square meters (9,600 square feet). The final footprint of the building was reduced by 78% after the safe storage enclosure project was completed.

Location: The 105-DR reactor is located near the south end of the 100 D/DR Exclusion Fence.

The SubSite is Part Of:

Code: 118-DR-2

Names: 118-DR-2; 105-DR; 105-DR Reactor Building

Code: 118-DR-2:2
Classification: Accepted

Names: 118-DR-2:2; 105-DR Ancillary Support Structures and Underlying Soils; 105-DR Reactor Below-Grade Structures and Soil
Reclassification: Interim Closed Out (1/15/2004)

Type: Reactor
Start Date:

Status: Inactive
End Date:

Description: Subsite 2 is 105-DR Reactor below-grade structures and underlying soil. The subsite has been remediated and Interim Closed Out.

For remediation purposes, the waste site was divided into five Zones and three decontamination areas.

Zone 1 consisted of the Fuel Storage Basin (FSB), storage and transfer area, storage area, the transfer bay and the soils underlying the FSB. This zone was located entirely within the deep zone.

Zone 2 consisted of the valve pit that received wastewater from the reactor building and the soil beneath it. Zone 2 was entirely within the deep zone.

Zone 3 consisted of the solids feed area, the north water tunnel, and the trench under the accumulator room. The below-grade rooms, tunnel, and trench had been wetted by isolated spills and standing rainwater that may have acted as a hydraulic driver for potential contamination. Zone 3 was within the shallow zone.

Zone 4 consisted of the gas tunnel, exhaust plenum, gas recirculation tunnel, and the instrument room. These rooms and tunnels had been wetted by isolated spills and standing rainwater,

which may have acted as a hydraulic driver for potential contamination. Zone 4 was entirely within the deep zone.

Zone 5 consisted of the side slope soils around the FSB, the south effluent pipeline, and the soil under the slab. Zone 5 also included a section of a process effluent pipeline located adjacent to the south side of the FSB. This area was included in Zone 5 because of its proximity to the side slopes of the FSB. Zone 5 was within the shallow zone.

The three decontamination areas were located around the reactor for the purpose of equipment decontamination. The northwest decontamination area was approximately 8.0 meters by 8.8 meters (26 feet by 29 feet). The northeast decontamination area was approximately 12 meters by 9.8 meters (39 feet by 32 feet), and the south decontamination area was approximately 16 meters by 17 meters (52 feet by 56 feet).

Location: The 105-DR Reactor is located south of the 105-D Reactor. The decontamination areas were on the northwest, northeast and south sides of the 105-DR structure.

Related Sites/ Structures: This waste site is associated with 100-D-49:4 (North Effluent Pipe Tunnel).

Closure Info: Interim (1/15/2004): The Cleanup verification package CVP-2003-00016 documents completion of removal action for 118-DR-2:2 Below Grade Structures and Underlying soils and the 100-D-49:4 pipeline in support of the 105-DR Reactor Interim Safe Storage Project. The 100-D-49:4 region consisted of the north effluent pipe tunnel, which had been removed. The soil beneath the floor and the side slopes were sampled for cleanup verification purposes. A portion of the 100-D-49:3 pipelines, located adjacent to the 105-D building, were also part of this remedial activity. The remedial activity was divided into five Zones, the north effluent pipeline and three decontamination areas. The three decontamination areas were also part of this remediation.

Removal and disposal activities at the 105-DR site began in September 1998 and concluded through September 2001. Excavation of the site involved removing the overburden materials, building structure, debris, and underlying contaminated soil. The 105-DR D&D activities resulted in removal of above-grade structures and below-grade structures outside of the 105-DR Reactor core shield walls, to 1 meter (3 ft) below surrounding grade, with the exception of the Fuel Storage Basin (FSB). The FSB structure was removed to 4.6 meters (15 ft) below the surrounding grade.

Sample results from the northwest and south decontamination areas resulted in additional excavation of these areas.

An individual calculation of contaminated material removed for cleanup of the pipeline area was not provided in the CVP. A total of approximately 7,220 cubic meters (25,500 cubic feet) of contaminated materials were disposed at the ERDF. The results of this effort indicated that the materials from the site containing COCs at concentrations exceeding RAGs have been excavated and disposed at the ERDF.

The SubSite is Part Of:

Code: 118-DR-2

Names: 118-DR-2; 105-DR; 105-DR Reactor Building

Code: 100-F-52

Classification: Accepted

Names: 100-F-52; 146-FR Radioecology/Aquatic
Biology Laboratory Soil

Reclassification Interim No Action (6/27/2008)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The waste site has been evaluated and determined to require No Action. It consisted of the soil under and around the former 146-FR Radioecology and Aquatic Biology Laboratory. In November 1964 a fire destroyed the roof over the operating ponds. In June 1975 the concrete foundation was removed. After remediation, the site was level to grade with no visual indication of the former facility.

Location: The 146-FR Radioecology and Aquatic Biology Laboratory was located approximately 457 meters (1500 feet) northeast of the 105-F Reactor Building and about 122 meters (400 feet) southwest of the 1904-F Outfall.

Related Sites/ Structures: The facility was associated with the 181-F River Pump House, the 190-F Main Process Pump House and Annex, the 107-F Retention Basin, and the 1904-F Outfall.

Process Description: Process liquids were supplied to the 146-F Fish Laboratory from several sources. Raw water was pumped from the 181-F River Pump House; chemically treated, pre-reactor process water was pumped from the 190-F Main Process Pump House and Annex; and reactor effluent process water was pumped from the 107-F Retention Basin. Aquatic river creatures were exposed to varying amounts of process effluents from 100 F Area operations, and the facility process wastes exited the south end of the building and passed through the 1904-F Outfall to the Columbia River.

Waste Type: Soil

Waste Description: During research of the site history, no reports were found of unplanned discharges to the soil from this building. However, because of the open-pond operations within the building, it is prudent to assume such discharges may have occurred. Confirmatory sampling should be considered. Contaminants of concern/potential concern are based on those for the 1904-F Outfall (116-F-8). Contaminants of concern include cobalt 60, europium 152, europium 154, europium 155, and hexavalent chromium. Contaminants of potential concern include carbon 14, cesium 137, nickel 63, and strontium 90.

Closure Info: Interim: Previous remediation activities for several other waste sites had partially overlapped the 100-F-52 waste site location. A small area along the northern edge of the 146-FR Laboratory footprint was removed along with pipelines associated with the 100-F-33 and 100-F-19 waste sites. Soils that were adjacent to the eastern edge of the 146-FR Laboratory footprint were excavated when pipelines associated with the 1607-F6 waste site were removed. When pipelines associated with the 100-F-19 waste site were removed, the entire southern edge of the 146-FR Laboratory footprint was removed. Excavation associated with the 100-F-26:12 Main Process Sewer Pipeline removed soils underlying the entire southern edge of the 146-FR Laboratory footprint. No indication of the former facility or concrete footprint was found during a March 2007 site visit. The site was partially covered with excavation stockpiles derived from the 100-F-26:12 Main Process Sewer Pipeline excavation. That excavation had removed all of the shallow zone soils from the southern 5 meters (16 feet) of the 146-FR Laboratory footprint.

Geophysical surveys over several sections of the 146-FR Radioecology and Aquatic Biology Laboratory footprint were performed as part of the investigations of adjacent waste sites. In order to get a complete survey for the site, several surveys were merged to get an overall geophysical interpretation map of the 100-F-52 waste site. The resulting survey revealed an area of scattered debris and three pipeline segments. Two of the pipeline segments were just outside of the 146-FR Laboratory footprint and were rejected because they were used for treated water. A third section of pipe, within the footprint of the 146-FR Laboratory, was approximately 22 meters (72 feet) long and 2 meters (3.3 feet) below ground surface. The pipe was included as part of the 100-F-52 waste site. A circular subsurface feature, approximately 12

meters (39 feet) north of the 146-FR Laboratory, can be seen in the geophysical survey interpretation. The location of the circular subsurface feature clearly identified it as the remnants of the circular pond that was closed as part of the 100-F-33 waste site.

Confirmatory sampling was performed on November 28, 2007 and February 20, 2008. A 5 centimeter (2-inch) diameter carbon steel pipe was discovered in each of two trenches, both trenches were sampled and backfilled. On February 20, 2008, the trenches were re-excavated, the pipes breached, revealing scale or sediment in one pipe which was sampled.

Code:	100-F-64	Classification:	Accepted
Names:	100-F-64; Yellow and Red Stained Soil Along Railroad Tracks Near 1713-FA	Reclassification	Interim Closed Out (3/22/2012)
Type:	Unplanned Release	Start Date:	
Status:	Inactive	End Date:	
Description:	The waste site has been remediated. It was red and yellow stained soil straddling railroad tracks containing elevated concentrations of lead.		
Location:	This area was approximately 27 meters (90 feet) east of the 100-F-47 electrical substation waste site boundary and west of the demolished 1713-FA Essential Materials Building.		
Process Description:	This stained soil may have been associated with spills from railroad unloading activities.		
Closure Info:	Interim (3/22/2012): The 100-F-64 stained soil site was discovered during the 100-F Area Orphan Sites walk down on May 4, 2005. A second stained area was subsequently located approximately 5 meters (16 ft) northwest of the original waste site boundary and was included with the remediation of the 100-F-64 waste site.		
	Remediation of the 100-F-64 waste site was performed August 3 through August 22, 2011. Approximately 312 bank cubic meters (408 bank cubic yards) of stained soil were removed from the site and direct-loaded into trucks for disposal at the Environmental Restoration Disposal Facility. The excavation was located in two distinct areas, and all soil was directly loaded out for disposal. The deepest part of the 100-F-64 excavation extended to a depth of approximately 1.5 meters (4.9 ft).		

Code:	100-F-65	Classification:	Accepted
Names:	100-F-65; Green Stained Area Near Tracks Immediately West of 190-F	Reclassification	Interim Closed Out (8/23/2012)
Type:	Unplanned Release	Start Date:	
Status:	Inactive	End Date:	
Description:	The waste site has been remediated and Interim Closed Out. It consisted of green stained soil along the railroad tracks immediately west of the 190-F Building. The site was discovered on March 28, 2011 while remediating 100-F-57.		
Location:	This area is approximately 20 meters (66 feet) west of the northwest corner of the 190-F Building along the railroad tracks.		
Closure Info:	Interim (8/23/2012): A discrepancy between the 100-F-57 sample design and the excavation findings resulted in an evaluation that supported a revised trench location, approximately 9 meters (30 ft) south of the original coordinates. Excavation was done at test trench #2 in		

January 2008. Samples of tar-like material, suspect asbestos found in pipe cradles at test trench #1, scabbled concrete and soil below test trench #2 were collected and analyzed. Based on the confirmatory sampling results, it was determined that remedial action was necessary at this waste site. The excavation exposed concrete slab walls approximately 1 meter (3 ft) apart, with debris filling the area between the walls. The debris was removed to reveal a trench, approximately 1.2 meters (4 ft) below ground surface (bgs), with pipe cradles along the length of the trench. The floor of the pump room was cleared of debris, exposing the pump pads and a grate covering the trench along the north wall. The pump room was examined for the potential location of a sump. It was concluded that no sump was present. Sample material was scabbled from each of the four pieces of concrete brought out of the trench. Soil samples were also collected from below the trench.

The excavation of the 100-F-57 waste site pipe cradles began on October 15, 2010, to collect waste characterization samples. Remediation of the 100-F-57 waste site began on December 6, 2010. On December 9, 2010, during exploration for the 100-F-57 northern pipe cradles, discolored (green-stained) concrete was discovered. The discolored concrete was surveyed using x-ray fluorescence (XRF) and high concentrations of chromium (>900 mg/kg) were detected. The discovery of the high hexavalent chromium concentrations in the in-process soil samples resulted in a design change from the original plan, which had only required remediation of the pipe cradles at the 100-F-57 waste site. October 2011, the project split the site into the 100-F-57:1 and 100-F-57:2 subsites to allow continued remediation of the western portion of the site and to facilitate closure of the eastern portion of the site and the overburden stockpile. The green stain became WIDS site 100-F-65, Green Stained Area Along Railroad Tracks Immediately West of 190-F. It was located approximately 20 meters (66 ft) west of the northwest side of the 190-F Building foundation.

Remediation of 100-F-65 was performed on July 25, 2011. The site was excavated to a depth of 1 meter (3.3 ft) bgs and resulted in approximately 84 BCM (109.9 BCY) of soil being removed and disposed at ERDF.

During the excavation, an underground injection control well was discovered on May 25, 2011 within the 100-F-57:2 subsite (at N147737.93, E580363.59). The underground injection control well was removed and disposed at ERDF. No other anomalies were noted during remediation.

The 100-F-57:2 waste subsite was excavated to groundwater levels in two locations.

Remediation of the 100-F-57:2 waste site was completed on April 9, 2012. The excavation reached a maximum depth of 12.8 meters (42 ft) bgs and resulted in approximately 55,701 BCM (72,854 BCY) of material being removed and disposed at ERDF. The debris included concrete, rebar, steel pipe, transite pipe, miscellaneous steel, wire, steel cable, and non-friable asbestos, unlike the friable asbestos discovered during confirmatory sampling.

Code: 118-F-8	Classification: Accepted
Names: 118-F-8; 105-F Reactor Building	Reclassification: Interim Closed Out (6/9/2015)
Type: Reactor	Start Date: 2/25/1945
Status: Inactive	End Date: 6/25/1965
Description: 118-F-8 is the 105-F Reactor Building, the ancillary support components and the underlying contaminated soils. The waste site has been divided into four subsites. Subsite 1 is the below-grade structures and underlying soils beneath the ancillary structures and has been Interim Closed Out. Subsite 2 is reactor core that has been placed in Interim Safe Storage (ISS) and was reclassified to Rejected. Subsite 3 is the underlying soil beneath the Fuel Storage Basin and had been Interim Closed Out and later Final Closed Out. Subsite 4 is an area of contaminated soil	

west of the boundary of the Fuel Storage Basin excavation (118-F-8:3) that had been Interim Closed Out and later Final Closed Out. Since all the subsites have been reclassified, the parent site is considered Interim Closed Out.

Location: The reactor area is located in the southeastern corner of the 100F Area.

Process Description: Treated cooling water from the Columbia River circulated in a single pass through the reactor process tubes, cooling tubes imbedded in the thermal shield, and reactor horizontal control rods. After exiting the reactor, the cooling water passed through a retention basin and was then discharged to the river. During reactor operations, fuel cladding failures sometimes occurred while the fuel elements were in the process tubes. The first such cladding failure in any reactor occurred at the F Reactor in 1948. When fuel cladding failed, the cooling water in the affected process tubes became highly contaminated and elevated radiation levels were observed in the cooling water exiting the reactor core. This highly contaminated water was diverted to a trench for ground disposal rather than to the Columbia River. During reactor operations and reactor shutdowns, large quantities of decontamination solutions were used routinely to remove radionuclides from reactor equipment and facility surfaces. The reactor facility had many safety and control mechanisms. The function of the horizontal control rods (HCRs) was to control the equilibrium and transient power levels of the reactor during routine operations and to maintain the desired neutron flux distribution. The HCRs were each about 11.0 meters (36 feet) long, with the poison (neutron absorbing) segment being about 8.96 meters (29.4 feet) long. Two of the rods were electrically driven and seven were hydraulically driven. The latter were known as shim rods and were used to achieve ongoing operational control and desired fluctuations. The vertical safety rods (VSRs) were 11.9-meter (39-foot) long, stainless steel sleeves with 0.74-millimeter (3/16-inch) thick boron stainless steel sleeves inside. Each VSR was inserted and withdrawn from the reactor via two separate cables wound around a winch located 12.2 meters (40 feet) above the top of the reactor. In cases of automatic shutdown ("scram") of the reactor, the electromagnetic clutch holding each rod would be deenergized (demagnetized), and the rods would free fall by gravity into channels penetrating the reactor. A "last ditch" safety system, a boric acid solution, was held in a large pedestal tank at the top of each reactor and connected to each of the 29 VSR channels via 1.27-centimeter (0.5-inch) pipes. The liquid boron system was later replaced by a system that used solid boron steel and carbon steel balls (Ball 3X System). The normal method for reactor refueling was displacement charge-discharge during reactor shutdown. During a refueling operation, the tubes to be discharged had their rear nozzle caps removed. New fuel elements were pushed into the process tube by a charging machine which caused the irradiated fuel elements in the tube to be displaced. The displaced irradiated fuel elements dropped into a water filled discharge chute and slid down into the metal pickup area at the end of the storage basin. The 6.1 meters (20 feet) of water in the chute area provided shielding as the elements accumulated and were sorted into buckets using long, hand-operated tongs. Following the storage period to allow radionuclide decay, the fuel elements were placed in special railroad cars for shipment to the chemical reprocessing facilities in the 200 Area.

Waste Type: Asbestos (friable)

Waste Description: The site was estimated to contain less than 2.83 cubic meters (100 cubic feet) of asbestos.

Waste Type: Equipment

Waste Description: Before remediation and ISS the unit contained an estimated 16,000 curies of radionuclides, 85,300 kilograms (94 tons) of lead, and 13.6 kilograms (30 pounds) of cadmium.

This Site has the Following SubSites:

Code: 118-F-8:1

Names: 118-F-8:1; 105-F Ancillary Support Structures and Underlying Soils; 105-F Below-Grade Structures and Underlying Soils

Code: 118-F-8:2

Names: 118-F-8:2; 105-F Reactor Core and ISS Project

Code: 118-F-8:3

Names: 118-F-8:3; 105-F Reactor Fuel Storage Basin Underlying Soils

Code: 118-F-8:4

Names: 118-F-8:4; 105-F Fuel Storage Basin West Side Adjacent and Side Slope Soils

Code: 118-F-8:1

Classification: Accepted

Names: 118-F-8:1; 105-F Ancillary Support Structures and Underlying Soils; 105-F Below-Grade Structures and Underlying Soils

Reclassification: Interim Closed Out (5/6/2004)

Type: Reactor

Start Date:

Status: Inactive

End Date:

Description: 118-F-8:1 subsite has been remediated and Interim Closed Out. It included the reactor ancillary support areas, below-grade structures and underlying soils beneath the support areas. The ancillary support areas consisted of the office areas, the reactor control room, tool storage rooms, restrooms, cooling water influent areas, change rooms, ventilation equipment areas, and electrical systems areas. The remediation area was divided into four zones based on process history and structure depth.

Zone 1 was the underlying soils beneath the Fuel Storage Basin. This zone later was renamed 118-F-8:3 (subsite 3). Subsite 3 was Final Closed Out in 2015.

Zone 2 consisted of the below-grade valve pit, located in the northern portion of the 105-F Reactor Building. It was constructed of poured reinforced concrete with wall thickness ranging from 0.9 to 1.5 meters (3 to 5 ft). The floor of the valve pit was approximately 4.8 meters (15.7 ft) below surrounding grade. During operation of the reactor, pre-reactor cooling water pipelines from the 190 Building entered the 105-F Reactor Building at the valve pit. Additional pipelines carried emergency raw water to the 105-F Reactor Building via the valve pit. Cooling water was distributed to two 91 centimeter (36 in.) diameter pipes that ran to the reactor base for distribution to the reactor block. The valve pit contained the valves and piping necessary to distribute cooling water to the reactor. Interior building floor drains were routed into the valve pit. The valve pit also contained recirculation pumps and components for the solids feed system.

Zone 3 consisted of the shallow (less than 4.6 meter [15 ft] below surface grade) below-grade structures. The Zone 3 structures were the solids feed area, the east water tunnel, the trench under the accumulator room, the gas recirculation tunnel, and the flow laboratory basement. The solids feed area housed a system that was used to inject a slurry of diatomaceous earth into the reactor cooling water to scour the corrosion film from the inner surfaces of the piping, process tubes and fuel elements to reduce friction losses in the system. The solids feed area also contained a sodium dichromate feed tank. The east water tunnel was a pipe tunnel used for piping between the valve pit and the reactor block. The trench under the accumulator room and the flow laboratory basement contained miscellaneous piping.

Zone 4 consisted of the deep (greater than 4.6 meter [15 ft] below surface grade) below grade structures. The Zone 4 structures were the east and west cooling water inlet tunnels, the 315 exhaust plenum, the 316 exhaust plenum, the pipe tunnel, and the southeast tunnel. The east and west inlet water tunnels contained the cooling water pipelines entering into the valve pit. The 315 and 316 exhaust plenums were part of the reactor building exhaust system. The pipe tunnel contained piping for the closed loop reactor block gas system. The southeast tunnel contained

reactor cooling water piping.

Closure Info: Interim: (Interim Closed Out) The remediation area was divided into four zones based on process history and structure depth. The 118-F-8:1 Zone 1 was the underlying soils beneath the Fuel Storage Basin. A portion of Zone 1 was later renamed 118-F-8:3. The 118-F-8:1 was re-defined as the other zones (Zones 2, 3, and 4).

Removal and disposal activities at the 105-F site began in 1999 and concluded in December 2003. Excavation of the site involved removing the building structures, debris, and underlying contaminated soil. The 105-F D&D activities resulted in removal of above and below-grade structures outside of the 105-F Reactor core shield walls to a minimum of 0.9 meters (3 ft) below surrounding grade. Approximately 22,132 metric tons (24,345 tons) of contaminated materials were disposed of at ERDF. The equipment decontamination pads were areas where decontamination of equipment occurred during the removal actions and ISS activities. In 2003, approximately 1 meter (3.3 ft) of contaminated soil from equipment decontamination activities was removed and disposed of at ERDF.

Zone 1 was soil beneath the fuel storage basin (FSB), located on the south side of the 105-F Reactor Building. The FSB held treated water and served as an underwater collection, storage and transfer facility for irradiated fuel elements discharged from the reactor. The FSB was approximately 23.8 by 21.6 by 6.4 meters (78 by 71 by 21 ft) deep. Deactivation of the storage basin occurred in 1970. Deactivation was accomplished by pumping the majority of the water from the basin and filling with sand. The Zone 1 Fuel Storage Basin was excavated and removed in 2003. The south and east portions of the FSB excavation are not included in this activity. They were remediated with the adjacent 100-F-19:2 pipeline excavation. Contaminated soil on the western side of the FSB became subsite 118-F-8:4. Remediation of the 118-F-8:4 soil area was deferred to the Remedial Action Project to be completed at a later date (see CVP-2007-00004).

Zone 2 was the valve pit walls. They were removed to a minimum of 0.9 meters (3 ft) below the surrounding surface grade. Because of elevated levels of hexavalent chromium and polychlorinated biphenyls (PCBs) in the valve pit floor, the concrete floor was removed and disposed of at ERDF. The floor of the Zone 2 valve pit was located 4.8 meters (15.8 ft) below surrounding grade. The soils underlying the former floor were sampled and analyzed for hexavalent chromium and PCBs.

Zone 3 included the shallow zone structures (4.6 meters [15 ft] or less below ground surface). It included the solids feed area, the gas recirculation tunnel, the trench under the accumulator room, the east water tunnel, and the flow laboratory basement. The gas recirculation tunnel was removed so that the underlying pipe tunnel (in Zone 4) could be accessed. All of the other below-grade walls, including ceilings, associated with the Zone 3 structures were removed to a minimum of 0.9 meters (3 ft) below the surrounding grade. Because of elevated levels of hexavalent chromium, the solids feed area concrete floor was removed and disposed of at ERDF. The former floors of the solids feed area and the gas recirculation tunnel were located, at respective depths of 3.4 meters (11 ft) and 4.4 meters (14.5 ft). The floors of the trench under the accumulator room, the east water tunnel, and the flow laboratory are located at the respective depths of 4.4 meters (14.5 ft), 3.8 meters (12.5 ft) and 3 meters (10 ft) below surrounding grade. The soils underlying the former solids feed area floor were sampled and analyzed for hexavalent chromium.

Zone 4 included the deep zone structures. The concrete floors of the Zone 4 structures were within the deep zone (greater than 4.6 meters [15 ft] below ground surface). Zone 4 included the east and west inlet water tunnels, the pipe tunnel, the 315 and 316 exhaust plenums, and the southeast tunnel. All of the concrete ceilings associated with zone 4 structures were removed. All of the Zone 4 walls were removed to a minimum of 0.9 meters (3 ft) below the surrounding

surface grade. None of the Zone 4 concrete floors required removal and were left in place. The floors of the east and west inlet water tunnels, the pipe tunnel, the 315 plenum, the 316 plenum, and the southeast tunnel were located at the respective depths of 4.6 meters (15 ft), 5 meters (16.5 ft), 4.9 meters (16 ft), 5 meters (16.5 ft) and 6.1 meters (20 ft) below surrounding grade.

Because the removal of the 100-F-10 French Drain was inadvertently omitted from the 100-F-19:2 pipeline Closeout Verification Package (CVP-2001-00003) report, the activity was included in the 118-F-8:1 and 118-F-8:3 report (CVP-2003-00017) to document the french drain's reclassification to Interim Closed Out. The 100-F-10 French Drain was completely removed during excavation of the 100-F-19:2 pipelines. The cleanup verification sampling results for the 100-F-10 French Drain were included in the CVP-2001-00003 report. 100-F-10 was Final Closed Out in 2015.

The SubSite is Part Of:

Code: 118-F-8

Names: 118-F-8; 105-F Reactor Building

Code: 118-F-8:2

Classification: Accepted

Names: 118-F-8:2; 105-F Reactor Core and ISS Project

Reclassification Rejected (6/9/2015)

Type: Reactor

Start Date:

Status: Inactive

End Date:

Description: 118-F-8:2 subsite is the 105-F Reactor that has been placed in Interim Safe Storage (ISS). It is an above grade structure and has been reclassified to Rejected because it does not meet the definition of a waste site. The 105-F Reactor was shut down on June 25, 1965. Until the start of the Interim Safe Storage (ISS) Project, the 105-F Reactor had been in a condition of minimum surveillance and maintenance.

Interim Safe Storage (ISS) of the 105-F Reactor included removing all portions of the reactor facility outside of the reactor block shield walls and construction of the safe storage enclosure (SSE), which required the installation of a new roofing system, power and lighting, a remote monitoring system, and ventilation components. The 105-F ISS Project began January of 1998 and was completed in September 2003. The primary objective of the 105-F Reactor ISS Project is to provide storage for up to 75 years with minimal maintenance required. Interim inspection are required only on a 5-year frequency. Access to the 105-F Reactor SSE is through the utility room. During periods of storage, the door to the SSE (located inside the utility room) will be locked and welded shut. The 0.9 to 1.5 meter (3 to 5 ft) thick concrete walls and the welded door provide the security barrier for the facility.

The original footprint area of the reactor building was approximately 4,994 square meters (53,750 sq. ft.). The final footprint area of the safe storage enclosure is 999 square meters (10,750 sq. ft.). Thus, the footprint area of the reactor was reduced by 80%. The footprint area is strictly the at-grade area and does not include the square footage of any above-grade rooms (e.g., sample rooms, ready room, upper electrical room, or exhaust plenums) or below-grade rooms/tunnels. The new steel roof decking was covered with foam and two applications of silicon rubber.

Location: The site is located in the southeastern corner of the 100F Area.

The SubSite is Part Of:

Code: 118-F-8

Names: 118-F-8; 105-F Reactor Building

Code: 118-F-8:3 **Classification:** Accepted
Names: 118-F-8:3; 105-F Reactor Fuel Storage Basin **Reclassification:** Final Closed Out (10/28/2015)
Underlying Soils
Type: Reactor **Start Date:**
Status: Inactive **End Date:**

Description: The subsite has been remediated, Interim Closed Out and later Final Closed Out. The 118-F-8:3 (remediation area Zone 1) was the soil beneath the fuel storage basin (FSB). The soil on the south and east sides of the basin that were adjacent to the pipeline in 100-F-19:2 were addressed with the pipeline remediation (see CVP-2001-00003). Contaminated soil on the west side of the fuel storage base that required additional remediation became subsite 118-F-8:4 and was addressed separately (see CVP-2007-00004).

Location: The fuel storage basin was located on the south side of the 105-F Building.

Related Sites/ Structures: The 118-F-8:3 subsite is associated with additional contaminated soil on the western edge of this excavation, known as subsite 118-F-8:4.

Process Description: The Fuel Storage Basin was the underwater collection, storage, and transfer facility for irradiated fuel elements discharged from the reactor.

Closure Info: Interim: (Interim Closed Out) The remediation area was divided into four zones based on process history and structure depth. The 118-F-8:1 Zone 1 was the underlying soils beneath the Fuel Storage Basin. A portion of Zone 1 was later renamed 118-F-8:3. The 118-F-8:1 was re-defined as the other zones (Zones 2, 3, and 4).

Removal and disposal activities at the 105-F site began in 1999 and concluded in December 2003. Excavation of the site involved removing the building structures, debris, and underlying contaminated soil. The 105-F D&D activities resulted in removal of above and below-grade structures outside of the 105-F Reactor core shield walls to a minimum of 0.9 meters (3 ft) below surrounding grade. Approximately 22,132 metric tons (24,345 tons) of contaminated materials were disposed of at ERDF. The equipment decontamination pads were areas where decontamination of equipment occurred during the removal actions and ISS activities. In 2003, approximately 1 meter (3.3 ft) of contaminated soil from equipment decontamination activities was removed and disposed of at ERDF.

Zone 1 was soil beneath the fuel storage basin (FSB), located on the south side of the 105-F Reactor Building. The FSB held treated water and served as an underwater collection, storage and transfer facility for irradiated fuel elements discharged from the reactor. The FSB was approximately 23.8 by 21.6 by 6.4 meters (78 by 71 by 21 ft) deep. Deactivation of the storage basin occurred in 1970. Deactivation was accomplished by pumping the majority of the water from the basin and filling with sand. The Zone 1 Fuel Storage Basin was excavated and removed in 2003. The south and east portions of the FSB excavation are not included in this activity. They were remediated with the adjacent 100-F-19:2 pipeline excavation. Contaminated soil on the western side of the FSB became subsite 118-F-8:4. Remediation of the 118-F-8:4 soil area was deferred to the Remedial Action Project to be completed at a later date (see CVP-2007-00004).

Zone 2 was the valve pit walls. They were removed to a minimum of 0.9 meters (3 ft) below the surrounding surface grade. Because of elevated levels of hexavalent chromium and polychlorinated biphenyls (PCBs) in the valve pit floor, the concrete floor was removed and disposed of at ERDF. The floor of the Zone 2 valve pit was located 4.8 meters (15.8 ft) below surrounding grade. The soils underlying the former floor were sampled and analyzed for hexavalent chromium and PCBs.

Zone 3 included the shallow zone structures (4.6 meters [15 ft] or less below ground surface). It included the solids feed area, the gas recirculation tunnel, the trench under the accumulator room, the east water tunnel, and the flow laboratory basement. The gas recirculation tunnel was removed so that the underlying pipe tunnel (in Zone 4) could be accessed. All of the other below-grade walls, including ceilings, associated with the Zone 3 structures were removed to a minimum of 0.9 meters (3 ft) below the surrounding grade. Because of elevated levels of hexavalent chromium, the solids feed area concrete floor was removed and disposed of at ERDF. The former floors of the solids feed area and the gas recirculation tunnel were located, at respective depths of 3.4 meters (11 ft) and 4.4 meters (14.5 ft). The floors of the trench under the accumulator room, the east water tunnel, and the flow laboratory are located at the respective depths of 4.4 meters (14.5 ft), 3.8 meters (12.5 ft) and 3 meters (10 ft) below surrounding grade. The soils underlying the former solids feed area floor were sampled and analyzed for hexavalent chromium.

Zone 4 included the deep zone structures. The concrete floors of the Zone 4 structures were within the deep zone (greater than 4.6 meters [15 ft] below ground surface). Zone 4 included the east and west inlet water tunnels, the pipe tunnel, the 315 and 316 exhaust plenums, and the southeast tunnel. All of the concrete ceilings associated with zone 4 structures were removed. All of the Zone 4 walls were removed to a minimum of 0.9 meters (3 ft) below the surrounding surface grade. None of the Zone 4 concrete floors required removal and were left in place. The floors of the east and west inlet water tunnels, the pipe tunnel, the 315 plenum, the 316 plenum, and the southeast tunnel were located at the respective depths of 4.6 meters (15 ft), 5 meters (16.5 ft), 4.9 meters (16 ft), 5 meters (16.5 ft) and 6.1 meters (20 ft) below surrounding grade.

Because the removal of the 100-F-10 French Drain was inadvertently omitted from the 100-F-19:2 pipeline Closeout Verification Package (CVP-2001-00003) report, the activity was included in the 118-F-8:1 and 118-F-8:3 report (CVP-2003-00017) to document the french drain's reclassification to Interim Closed Out. The 100-F-10 French Drain was completely removed during excavation of the 100-F-19:2 pipelines. The cleanup verification sampling results for the 100-F-10 French Drain were included in the CVP-2001-00003 report. 100-F-10 was Final Closed Out in 2015.

Final (10/28/2015): (Final Closed Out) Thirteen 100-F Area waste sites were reclassified to Final Closed out on form 2015-078. They had all previously been classified as Interim Closed Out. The waste sites included on this reclassification form are 100-F-10, 100-F-19 (and subsites 1,2 and 3), 100-F-29, 100-F-34, 116-F-2, 116-F-6, 116-F-9, 116-F-12, subsites 118-F-8:3 and :4, UPR-100-F-1. The Record of Decision (ROD) for the 100-FR-1, 100-FR-2, 100-FR-3, 100-IU-1, 100-IU-2 and 100-IU-6 Operable Units has defined these waste sites as all requiring institutional controls to restrict excavation into the deep zone (greater than 4.6 meters or 15 feet below the ground surface). However, no further remedial actions are required.

Institutional Control Boundaries have been defined to be broadly inclusive of waste site groups. Not all areas within these boundaries contain residual contamination greater than 4.6 meters (15 ft) below ground surface. An image of four Institutional Control Boundaries inside 100F Area was attached to the 2015-078 Reclassification form (and included in the WIDS library).

The SubSite is Part Of:

Code: 118-F-8

Names: 118-F-8; 105-F Reactor Building

Code: 118-F-8:4

Classification: Accepted

Names: 118-F-8:4; 105-F Fuel Storage Basin West Side
Adjacent and Side Slope Soils

Reclassification Final Closed Out (10/28/2015)

Type: Reactor**Start Date:****Status:** Inactive**End Date:**

Description: This subsite has been remediated, Interim Closed Out and later Final Closed Out. It consisted of an area of contaminated soil in the western boundary of the Fuel Storage Basin excavation that required additional remediation. It was identified during the remediation activities at 118-F-8:1 and 118-F-8:3 and remediated in 2007.

Location: This area was located southwest of the 105-F reactor, on the western boundary of the Fuel Storage Basin.

Related Sites/ Structures: This subsite is associated with 118-F-3:3 and pipeline site 100-F-19:2.

Closure Info: Interim (3/4/2008): (Interim Closed Out) Remediation of the subsite 4 began on March 14, 2007, and was completed on June 22, 2007. Remedial action activities involved removing the uncontaminated overburden, the buried contaminated material, and the underlying contaminated soil for disposal. Excavation involved removing the uncontaminated overburden and underlying contaminated soil. Initial verification sampling results showed one area of the overburden stockpiles had elevated carbon-14 levels. Additional soil was removed and disposed. The area was re-sampled on October 22, 2007 and passed cleanup criteria. At the conclusion of remediation activities, deepest part of the excavation was approximately 8 meters (26 ft) below ground surface. No anomalies or stained soil were discovered during remediation.

Approximately 2,950 bank cubic meters (BCM) of overburden was stockpiled. Approximately 1,650 bank cubic meters (BCM) of contaminated soil was disposed at ERDF. The maximum depth of excavation was approximately 8 meters (26 feet) below ground surface.

The 118-F-8:4 subsite has been verified to meet protectiveness standards in accordance with the Action Memorandum. In accordance with this evaluation, the verification sampling and modeling results support a reclassification of the site to Interim Closed Out.

Final (10/28/2015): (Final Closed Out) Thirteen 100-F Area waste sites were reclassified to Final Closed out on form 2015-078. They had all previously been classified as Interim Closed Out. The waste sites included on this reclassification form are 100-F-10, 100-F-19 (and subsites 1,2 and 3), 100-F-29, 100-F-34, 116-F-2, 116-F-6, 116-F-9, 116-F-12, subsites 118-F-8:3 and :4, UPR-100-F-1. The Record of Decision (ROD) for the 100-FR-1, 100-FR-2, 100-FR-3, 100-IU-1, 100-IU-2 and 100-IU-6 Operable Units has defined these waste sites as all requiring institutional controls to restrict excavation into the deep zone (greater than 4.6 meters or 15 feet below the ground surface). However, no further remedial actions are required.

Institutional Control Boundaries have been defined to be broadly inclusive of waste site groups. Not all areas within these boundaries contain residual contamination greater than 4.6 meters (15 ft) below ground surface. An image of four Institutional Control Boundaries inside 100F Area was attached to the 2015-078 Reclassification form (and included in the WIDS library).

The SubSite is Part Of:

Code: 118-F-8**Names:** 118-F-8; 105-F Reactor Building**Code:** 100-H-54**Classification:** Accepted**Names:** 100-H-54; GPERs 100-H Shoreline Survey
Unplanned Release**Reclassification** None

Type: Unplanned Release**Start Date:****Status:** Inactive**End Date:****Description:** The waste site is an area of radiological surface contamination along the Columbia River embankment, southeast of the 107-H Retention Basin. The area was resurveyed and posted as a Surface Contamination Area in May 2012.**Location:** The site is located approximately 150 meters (432 feet) southeast of the 107-H Retention Basin. The site is along the Columbia River embankment. The location with the maximum gamma readings is at coordinates E578294.96,/N152528.72.**Waste Type:** Soil**Waste Description:** The site is an area of elevated radiological activity, generally less than twice background measurements, as shown in the GPERS survey report plot.

Code: 100-H-56**Classification:** Accepted**Names:** 100-H-56; H-Area Miscellaneous Pipelines**Reclassification:** Interim No Action (8/20/2014)**Type:** Product Piping**Start Date:****Status:** Inactive**End Date:****Description:** The waste site was evaluated and determine to require No Action. The site consists of seventeen 100-H Area miscellaneous pipeline segments not associated with an existing waste site. Some segments were discovered during a spatial analysis of the pipeline mapping. Some pipeline segments were either not assigned to waste sites or incorrectly assigned to a waste site. Some pipeline segments were added during field remediation activities. Some segments were removed from this site because they were addressed with other waste sites.

The following pipeline segments were originally included in this waste site:

- (1) The 15.2 cm (6 in) cast iron sanitary sewer services the 181-H building. It carried sanitary waste to the 1607-H4 septic tank and drain field (M-1904-H sht 1, P-1211).
- (2) The 5.08 cm (2 in) steel pipeline carried filtered water from the Brine Pump House to the coal conveyor. The water supply originated from the 184-H Power House and traveled to the Brine Pump House through a 7.62 cm (3 in) steel filtered water line (100-H-51:3) before connecting to the 5.08 cm (2 in) steel filtered water pipeline (P-1418, P-1419).
- (3) The 2.54 cm (1 in) soft water line from the elevated water tower to the 184-H power house (P-1426, P-1216). (Addressed with 100-H-28:3)
- (4) The 10.16 cm (4 in) schedule 40 steel water line supplied filtered water from the elevated water tank 187-H1 to the 119-H Sample Building (H-1-19805, H-1-19812, H-1-19849).
- (5) The 30.48 cm (12 in) filtered water line supplies water from the elevated storage tank 187-H1 to the 105-H Building (H-1-13254).
- (6) The 40.64 cm (16 in) filtered water line supplies water from the elevated storage tank 187-H1 and the 105-H Building (H-1-13254, P-4750, P-1221). Purportedly a 500 parts per million dichromate solution was added to the water left in the pipeline during descaling of the 105 High Tank piping in 1960 (HW-65726 SUPD).
- (7) The 15.2 cm (6 in) vitrified clay pipe sanitary sewer connects the south side of the 105-H building with 100-H-28:4 (H-1-19805). (Addressed with 132-H-3)
- (8) The 15.2 cm (6 in) vitrified clay pipe connects the 110-H building with the sanitary sewer trench (100-H-30) (H-1-19824).
- (9) The 3.8 cm (1.5 in) steel sanitary water pipe connects the 110-H building with the sanitary water supply leading into the east side of the 1608-H building (H-1-19805, H-1-19812, H-1-70246). (Addressed with 132-H-3)

- (10) The 40.6 cm (16 in) steel filtered water line supplies water from the elevated storage tank 187-H2 to the 105-H Building (H-1-13254, P-1220). Approximately 500 parts per million of dichromate solution was added to the water remaining in the pipeline during descaling of the 105 High Tank piping in 1960 (HW-65726 SUPD).
- (11) The 10.16 cm (4 in) sanitary sewer connects the paint shop (1722-H) with 100-H-28:2.
- (12) The 2.54 cm (1 in) pipeline near 100-H-55. It is assumed to be a service water line.
- (13) A concrete encased pipe was discovered running between E577797/N152419 and E577831/N152418. It was discovered during remediation of the 105-H Decontamination Pads (118-H-6:5) in July 2009.
- (14) A 10.16 cm (4 in) thin walled aluminum pipeline set in concrete running east/west near 600-152. It resembles an irrigation pipe.
- (15) Temporary construction sewer line, septic tank and drain field west of 151-H (HW-24800-2, photo 2045).
- (16) A 15.2 cm (6 in) cast iron pipe discovered during excavation of 100-H-4 in January 2010.
- (17) A 1.9 cm (0.75 in) sodium silicate line from the storage tank in the 190-H Building to the 187-H2 Elevated Water Tower (H-1-13254).

NOTE: Two sewer pipelines (7 and 9) were removed with the 132-H-3 waste site. Pipeline 3 was inside the 100-H-28:3 subsite excavation and sampled from the bottom of the 100-H-28:3 excavation. Four sewer lines (1, 8, 11, and 15) will be in a Remove, Treat, Dispose report.

Location:

- (1) End coordinates N153474.45, E577535.22 and N153434.55, E577551.95. The 15-cm (6-in.) cast iron pipeline carried sanitary waste to the 1607-H4 septic tank.
- (2) End coordinates N152944.97, E577455.58 and N152998.08, E577455.58. The 5-cm (2-in.) steel pipeline carried water from the brine pump house to the coal conveyor. The water supply originated from the 184-H Power House and traveled to the brine pump house through the 100-H-53:3 subsite.
- (3) End coordinates N152937.94, E577527.96 and N152972.67, E577525.05. The 2.5-cm (1-in.) steel soft water line runs from the elevated water tower to the 184-H Power House. The 100-H-56 Pipeline # 3 was located inside the 100-H-28:3 subsite excavation. A sample was collected from the bottom of the 100-H-28:3 excavation.
- (4) End coordinates N152553.08, E577687.81 and N152500.00, E577730.23. The 10-cm (4-in.) and 1.9-cm (0.75-in.) steel pipeline carried filtered water from elevated water tank 187-H1 to the 119-H Sample Building.
- (5) End coordinates N152551.11, E577686.91 and N152553.57, E577771.68. The 30-cm (12-in.) pipeline carried filtered water from elevated water tank 187-H1 to the 105-H Sample Building.
- (6) End coordinates N152555.06, E577690.42 and N152558.53, E577766.78. The 40.6-cm (16-in.) pipeline carried filtered water from elevated water tank 187-H1 to the 105-H Sample Building.
- (7) End coordinates N152497.87, E577681.05 and N152506.51, E577753.69. The 15-cm (6-in.) vitrified clay pipeline was within the boundary and taken out with the 132-H-3 waste site.
- (8) End coordinates N152451.66, E577728.13 and N152401.09, E577748.81. The 15-cm (6-in.) vitrified clay pipe connects the 110-H Building with the sanitary sewer trench (100-H-30 waste site).
- (9) End coordinates N152479.46, E577745.75 and N152451.59, E577730.33. The 3.8-cm (1.5-in.) steel sanitary water pipe connected the 110-H Building with the sanitary water supply leading into the east side of the 1608-H Building. This pipe was within the boundary of the 132-H-3 waste site and was taken out with that excavation.

(10) End coordinates N152547.47, E577798.95 and N152550.90, E577841.31. The 40.6-cm. (16-in.) steel pipeline carried filtered water from elevated water tank 187-H2 to the 105-H Building. Allegedly 500 parts per million dichromate solution was added to the water left in the pipeline during descaling of the 105 high tank piping in 1960. After chemically descaling the tanks and the lines in 1960 and 1961, a sodium silicate injection system was added for the high tanks. A sodium silicate tank was installed in the 190-H Building, and silicate was added directly into the fill lines for the 187-H High Tanks.

(11) End coordinates N152655.44, E577974.51 and N152652.88, E577983.39. The 10-cm (4-in.) vitrified clay sanitary sewer line connects the 1722-H Building with the 100-H-28:2 subsite.

(12) End coordinates N153434.19, E576892.43 and N153434.18, E576905.77. The 2.5-cm (1-in.) cast iron service water line is located near the 100-H-55 waste site.

(13) End coordinates N152419.00, E577797.00 and N152418.00, E577831.00. The concrete-encased pipe was found during remediation of the 105-H Decontamination Pads in July 2009.

(14) End coordinates N153591.57, E576881.05 and N153589.19, E576958.70. The 10-cm (4-in.) aluminum resembles an irrigation pipe running east/west near the 600-152 waste site. Thin-walled with concrete set around it.

(15) End coordinates N152509.32, E577553.38 and N152509.34, E577405.98. Temporary construction sewer line, septic tank, and drain field west of the 151-H Building. Sewer line from the 100-H-28:4 subsite.

(16) End coordinates N152604.50, E577975.70 and N152605.50, E578007.30. The 15-cm (6-in.) cast iron pipe was discovered during excavation of the 100-H-4 waste site in January 2010.

(17) End coordinates N152558.86, E577792.40 and N152553.82, E577836.80. The 1.9-cm (0.75-in.) sodium silicate pipe runs from a storage tank in the 190-H Building to the 187-H2 elevated water tower.

Process There is no process history associated with the 100-H-56 waste site.

Description:

Closure Info: Interim (8/20/2014): On June 21, 2013, excavation was started at Test Pit 8 with one sample taken at 4 meters (13 ft) below ground surface (bgs) and one sample taken at 4.6 meters (15 ft) bgs, no pipe was found at this excavation.

On June 28, 2013, Test Pit 1 was excavated to native soil where primary and duplicate samples were taken at a depth of 3 meters (10 ft) bgs. No pipe was found.

On July 1, 2013, Test pit 2 was excavated to a depth of 4.6 meters (15 ft) bgs, and no pipe was visible. A sample was taken at the base of the excavation.

On July 2, 2013 Test Pits 7 and 10 were excavated. A pipe was encountered at 1.1 meter (3.5 ft) bgs in Test Pit 10. A sample was taken below the pipe. No sample was collected from inside the pipe due to the pipe being crimped. Along with the crimped pipe found in the side wall, a 0.76 meters (2.5 ft) section of pipe was found in the excavation. however, according to the logbook, nothing was inside the pipe to be sampled. No staining was encountered.

Test pit 7 was excavated to a depth of 4.6 meters (15 ft) bgs and sampled. No pipe was encountered.

On July 8, 2013, Test Trench 6 was excavated and sampled at a depth of 4.6 meters (15 ft.). No pipe was encountered. Test Pit 9 were excavated to a depth of 1.8 meters (6 ft) bgs. The duct bank runs east/west and is approximately 0.3 meters (1 ft) thick and 0.9 meters (3 ft) wide. The crew and engineer were confident that this resembles previous electrical duct banks encountered at the 100-D, 100-F, and 300 Areas. The amount of concrete used makes it unlikely that there is just a pipe inside. One sample was taken from underneath the electrical duct bank.

On July 16, 2013 test trench 5 that was excavated to a depth of 4.6 meters (15 ft) bgs. No pipe was found. One soil sample was taken at the bottom of the excavation.

On March 5, 2014, two pipes were encountered during excavation of Test Pit 3 (a 2.5 cm (1 in.) diameter pipe running east-west about 0.6 meters (2 ft) bgs and a 5 cm (2 in.) pipe running north-south about 1.2 or 1.5 meters (4 or 5 ft) bgs. Both pipes were open and empty. A sample from underneath the pipes at about 1.5 meters (5 ft) bgs was taken.

On March 5, 2014, Test Pit 4 was excavated. A 5 cm (2 in.) diameter pipe at 1.2 meters (4 ft) bgs was encountered. This pipe was wrapped in thermal system insulation asbestos material and had been disturbed by the excavator during the excavation. The area was stabilized, properly posted, and the excavator was properly decontaminated. It was determined that the pipe was a steam line and therefore nonhazardous. The steam line was left in place.

On March 31, 2014, in a continuing effort to find the pipe and/or collect a soil sample from the pipes location a sample was taken approximately 3 meters (10 ft) bgs at the 100-H-28:3 excavation. This sample took the place of the original TP-4 sample and is located where pipeline 3 would have entered the 100-H-28:3 pipeline. The soft water pipeline was never found.

Code: 100-H-59	Classification: Accepted
Names: 100-H-59; Soil Contamination and Debris Piles near 100-H Area Railroad Track; 100-H Area Railroad Track Soil Contamination Area	Reclassification: Interim Closed Out (11/9/2015)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The site consisted of contaminated soil discovered during the removal of the rail at the 100-H project. Some soil contaminated areas and piles of debris remained after the railroad track removal project was completed. The site was split into two subsites that represent the soil contamination and the piles of debris. Subsite 1 and Subsite 2 have both been remediated and reclassified to Interim Closed Out. The Parent site is also considered to be Interim Closed Out.

Location: This site is along a railroad bed in the 100-H Area south and west of the 105-H Reactor.

Process Description: There is no process history associated with the 100-H-59 waste site.

This Site has the Following SubSites:

Code: 100-H-59:1
Names: 100-H-59:1; 100-H Area Railroad Track Soil Contamination

Code: 100-H-59:2
Names: 100-H-59:2; Debris Piles near 100-H-Rail Road Tracks

anomaly was staged in a small anomaly staging area adjacent to the northern edge of the excavation prior to being sampled for disposal. The liquid was sampled on May 12, 2015, and the glass bottle was disposed at the ERDF. No liquid remained in the bottle following sample collection.

The soil and debris were direct loaded for disposal at ERDF. No waste staging pile was generated. No overburden material was salvaged for use as clean backfill. Several in-process soil samples were collected during the remediation. A post-excavation civil survey was performed at the 100-H-59:2 subsite following remediation.

The SubSite is Part Of:

Code: 100-H-59

Names: 100-H-59; Soil Contamination and Debris Piles near 100-H Area Railroad Track; 100-H Area Railroad Track Soil Contamination Area

Code: 100-H-60

Classification: Accepted (Proposed)

Names: 100-H-60; 184-H Demolition Legacy Asbestos Site

Reclassification: None

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The waste site is a large area of legacy Cement Asbestos Board (CAB) that has been widely dispersed due to the previous demolition of the 184H Powerhouse. The area was identified in May 2013 and was estimated to cover approximately 5 acres. The area had been surrounded with road barricades. Signs were ordered and planned to be installed when they are received. Additional fragments were identified in 2015 and the posted area was enlarged.

Location: The waste site is located in the 100-H Area. It is north of the 1713H warehouse and northwest of the 105H reactor.

Code: 118-H-6

Classification: Accepted

Names: 118-H-6; 105-H Reactor Building

Reclassification: Interim Closed Out (2/18/2015)

Type: Reactor

Start Date: 1/1/1949

Status: Inactive

End Date: 1/1/1965

Description: The waste site is the 105-H Reactor site that was divided into six subsites. All of the subsites have been reclassified. Therefore the parent site is considered to be Interim Closed Out. Subsite 1 is the cocooned 105-H Reactor Core and Interim Safe Storage (ISS) Project. It represents the above-grade structure and has been reclassified to Rejected. Subsite 2 is the 105-H Ancillary Support Areas, Below-Grade Structures and Underlying Soils and has been reclassified to Interim Closed Out. Subsite 3 is the 105-H Reactor Fuel Storage Basin and Underlying Soils and has been reclassified to Interim Closed Out. Subsite 4 is the 105-H Fuel Storage Basin Shallow Zone Side Slope Soils and has been reclassified to Interim Closed Out. Subsite 5 is the 105-H Decontamination Pads and has been reclassified to Interim Closed Out. Subsite 6 is the Deep Zone Side Slopes and has been reclassified to Interim Closed Out.

The reactor area was divided into five Demolition Zones. Demolition Zone 1 was on the west side of the reactor building. It included the 316 gas plenum, drying rooms, filter rooms and exhaust fans. Demolition Zone 2 was on the south side of the reactor building. It included the fuel storage basin, the was pad and transfer bay areas. Demolition Zone 3 was on the northeast

corner of the reactor building. It included the control room, the instrument repair room and the lunch room, offices and corridors. Demolition Zone 4 was on the southeast corner of the reactor building. It included the outer rod room, corridor #3 and storage rooms. The battery room and electrical room were below grade. It also included a concrete ramp. Demolition Zone 5 was on the north and west sides of the reactor building. It included several equipment rooms and storage rooms along with the influent cooling water tunnels.

Location: The 105-H Reactor was located in the 100-H Area of the Hanford Site in southeastern Washington State.

Release Description: It was suspected that the irradiated fuel storage basin leaked for a number of years prior to deactivation. The leak rate was small, and the location of the leak was never identified.

Process Description: The 105-H Reactor was one of eight single-pass plutonium production reactors built along the Columbia River. Construction of the 105-H Reactor began in March 1948 with operations commencing on October 29, 1949. The 105-H Reactor was shut down in April 1965. During the shutdown activities it was determined that the FSB had leaked. A Record of Decision (ROD) was issued by the U.S. Department of Energy (DOE) (58 Federal Register 48509). The ROD alternative selected was to place the reactors into a safe storage condition for up to 75 years. After Interim Safe Storage (ISS), the reactors would be transported in one piece to a specially prepared burial facility in the 200 West Area of the Hanford Site.

Miscellaneous process equipment and sludge was left in the basin, and the sludge was stabilized in place in 1970 with approximately 6 meters (20 feet) of soil backfill. In the years following deactivation, several other significant cleanup efforts were completed at the 105-H Reactor complex. These included the 1983 demolition of the 116-H reactor exhaust stack and above-grade exhaust ducting and the 1984 demolition of the 117-H exhaust air filter building.

Waste Type: Equipment

Waste Description: The primary source of contamination at the site was reactor coolant water and water in the Fuel Storage Basin that became contaminated through contact with irradiated and ruptured fuel elements and components from the reactor cooling system. In 1987 the basin contained an estimated 15,000 curies of radionuclides, 102,000 kilograms (112 tons) of lead, less than 2.8 cubic meters (100 cubic feet) of asbestos, and 9 kilograms (20 pounds) of cadmium.

This Site has the Following SubSites:

Code: 118-H-6:1

Names: 118-H-6:1; 105-H Reactor Core and ISS Project

Code: 118-H-6:2

Names: 118-H-6:2; 105-H Ancillary Support Structures and Underlying Soils; 105-H Below-Grade Structures and Underlying Soils

Code: 118-H-6:3

Names: 118-H-6:3; 105-H Reactor Fuel Storage Basin and Underlying Soils

Code: 118-H-6:4

Names: 118-H-6:4; 105-H Fuel Storage Basin Shallow Zone Side Slope Soils

Code: 118-H-6:5

Names: 118-H-6:5; 105-H Decontamination Pads

Code: 118-H-6:6

Names: 118-H-6:6; 105-H Deep Zone Side Slope Soils

Code: 118-H-6:1

Classification: Accepted

Names: 118-H-6:1; 105-H Reactor Core and ISS Project **Reclassification** Rejected (2/18/2015)

Type: Reactor **Start Date:**

Status: Inactive **End Date:**

Description: Subsite 1 has been evaluated and reclassified to Rejected. It is the above-grade, cocooned 105-H Reactor core. The Interim Safe Storage (ISS) project began in 2000 and continued to 2005. The project included characterization, engineering, removal of hazardous and radiologically contaminated materials, equipment removal, decontamination, demolition of the structure, and restoration of the site. The ISS activities included construction of the safe storage enclosure (SSE), which required the installation of a new roofing system, power and lighting, a remote monitoring system, and ventilation components. The original footprint area of the 105-H Reactor Building was approximately 6,934 square meters (74,640 square feet). The final ground-level footprint area of the safe storage enclosure (SSE) is 1,387 square meters (14,928 square feet). The exterior contaminated areas of the reactor building that have been removed and disposed in ERDF represent 80% of the original footprint of the reactor building.

As much as was practical, all objects and surface contamination were removed during the decommissioning activities. A new roof was added as part of the ISS effort. All doors were permanently sealed except for one door that remains locked and is welded shut. The only planned entrance to this structure is for surveillance and maintenance activities that will occur approximately every 5 years. The below-grade portions of the facility, outside the Safe Storage Enclosure have been removed, and all below-grade areas backfilled to eliminate future subsidence.

Location: The cocooned 105-H Reactor structure is located in the 100-H Area.

The SubSite is Part Of:

Code: 118-H-6

Names: 118-H-6; 105-H Reactor Building

Code: 118-H-6:2

Classification: Accepted

Names: 118-H-6:2; 105-H Ancillary Support Structures and Underlying Soils; 105-H Below-Grade Structures and Underlying Soils

Reclassification Interim Closed Out (6/22/2006)

Type: Reactor

Start Date:

Status: Inactive

End Date:

Description: The 118-H-6:2 Has been remediated and Interim Closed Out. It consisted of the 105-H Reactor ancillary support areas, below-grade structures, and underlying soils. During remediation, this subsite included Demolition Zones 1, 3, 4 and 5 located on the west, south, northeast and southeast portions of the ancillary reactor structures. The remediation area also included the 100-H-9, 100-H-10, 100-H-13 french drains.

Closure Info: Interim: Removal and disposal activities at the 105-H site (118-H-6:2, 118-H-6:3, 118-H-6:6 subsites) were completed in 2004. D&D activities, in preparation for the construction of the 105-H Reactor SSE, also resulted in the removal of 100-H-9, 100-H-10, 100-H-11, 100-H-12, 100-H-13, 100-H-14 french drains and the 100-H-31 electrical transformer soil. All materials from the 105-H Reactor ISS Project were demolished and disposed at ERDF. The overburden piles produced during excavation were found to be contaminated. The overburden was deemed unsuitable for use as backfill of the site and was removed to ERDF.

The site was backfilled with clean soil aggregate from the 100-D Area Borrow Pit 21 and

graded to match the surrounding terrain. This 105-H D&D activity generated approximately 4,863 bulk containers of low-level contaminated material that were shipped to ERDF, accounting for approximately 73,966 metric tons (81,365 tons).

Per the Sampling and Analysis Plan, the 105 H Reactor ancillary support areas and below-grade structures (118-H-6:2) did not require sampling and analysis because the structures were removed in their entirety and then disposed at the Environmental Restoration Disposal Facility (ERDF). During the D&D activities, an additional evaluation was required to determine if the soils under the Fuel Storage Basin (FSB) floor (118-H-6:3) had achieved the RAGs. The evaluation of the FSB soils and deep zone side-slope soils (118-H-6:6) also evaluated the soils under the 100-H-11, 100-H-12, and 100-H-14 waste sites. Radiological surveys and verification sampling analysis were performed on the FSB underlying soils and deep zone side-slope soils. The data was used with the RESRAD computer model to verify that cleanup criteria were satisfied. Localized contamination was removed in preparation for clean demolition, and a fixative was applied as required. With one exception, no below-grade structures remaining. The exception is a portion of the FSB floor, at its northern end between the two access labyrinths to the D elevator. It was not removed with this activity.

Verification soil samples were collected from soils under the FSB floor. All demolition debris from excavations associated with the activity was sent to ERDF. Final cleanup verification samples for the FSB underlying soils and deep zone side-slope soils were collected following evaluation of field screening for radiological contaminants using global positioning environmental radiological surveyor (GPERS) and laser-assisted ranging and data system (LARADS) surveys. This field screening was performed in order to obtain an initial assessment of attainment of radiological cleanup levels

The remaining soils at the 105-H Reactor site were either been deferred to the Field Remediation Closure Project or have been shown to meet the applicable RAGs through verification sampling, analysis, and RESRAD modeling. All excavated materials generated during the D activities were disposed at ERDF, and the area was backfilled to grade with clean backfill. These results also indicate that residual concentrations in the shallow zone will support future land uses that can be represented (or bounded) by a rural-residential scenario and that residual concentrations throughout the site pose no threat to groundwater or the Columbia River.

The three decontamination pads (118-H-6:5) and the Fuel Storage Basin shallow side-slope soils (118-H-6:4) were deferred to the Field Remediation Closure Project and remediated at a later date.

The SubSite is Part Of:

Code: 118-H-6

Names: 118-H-6; 105-H Reactor Building

Code: 118-H-6:3

Classification: Accepted

Names: 118-H-6:3; 105-H Reactor Fuel Storage Basin and Underlying Soils

Reclassification Interim Closed Out (6/22/2006)

Type: Reactor

Start Date:

Status: Inactive

End Date:

Description: The site has been remediated and Interim Closed Out. The 118-H-6:3 subsite was the soil beneath the 105-H Reactor Fuel Storage Basin and included the 100-H-11 french drain and the 100-H-14 soil contamination area.

During remediation, this subsite was known as Demolition Zone 2. This zone consisted of the

control room, the instrument repair room, the lunch room, several offices, and several corridors. The only below-grade structure in this zone was the 106 corridor. The local contamination was removed and a fixative was applied as required. All structures in this demolition zone were removed due to surface contamination being present. Per the 105-H Reactor Sample Analysis Plan, sampling of underlying soils was not required because structures in this demolition zone were not subjected to standing contaminated water. There was no mechanism for residual surface contamination to penetrate into the concrete and the underlying soil.

Location: Demolition Zone 2 was on the northeast corner of the original reactor building.

Closure Info: Interim: Removal and disposal activities at the 105-H site (118-H-6:2, 118-H-6:3, 118-H-6:6 subsites) were completed in 2004. D&D activities, in preparation for the construction of the 105-H Reactor SSE, also resulted in the removal of 100-H-9, 100-H-10, 100-H-11, 100-H-12, 100-H-13, 100-H-14 french drains and the 100-H-31 electrical transformer soil. All materials from the 105-H Reactor ISS Project were demolished and disposed at ERDF. The overburden piles produced during excavation were found to be contaminated. The overburden was deemed unsuitable for use as backfill of the site and was removed to ERDF.

The site was backfilled with clean soil aggregate from the 100-D Area Borrow Pit 21 and graded to match the surrounding terrain. This 105-H D&D activity generated approximately 4,863 bulk containers of low-level contaminated material that were shipped to ERDF, accounting for approximately 73,966 metric tons (81,365 tons).

Per the Sampling and Analysis Plan, the 105 H Reactor ancillary support areas and below-grade structures (118-H-6:2) did not require sampling and analysis because the structures were removed in their entirety and then disposed at the Environmental Restoration Disposal Facility (ERDF). During the D&D activities, an additional evaluation was required to determine if the soils under the Fuel Storage Basin (FSB) floor (118-H-6:3) had achieved the RAGs. The evaluation of the FSB soils and deep zone side-slope soils (118-H-6:6) also evaluated the soils under the 100-H-11, 100-H-12, and 100-H-14 waste sites. Radiological surveys and verification sampling analysis were performed on the FSB underlying soils and deep zone side-slope soils. The data was used with the RESRAD computer model to verify that cleanup criteria were satisfied. Localized contamination was removed in preparation for clean demolition, and a fixative was applied as required. With one exception, no below-grade structures remaining. The exception is a portion of the FSB floor, at its northern end between the two access labyrinths to the D elevator. It was not removed with this activity.

Verification soil samples were collected from soils under the FSB floor. All demolition debris from excavations associated with the activity was sent to ERDF. Final cleanup verification samples for the FSB underlying soils and deep zone side-slope soils were collected following evaluation of field screening for radiological contaminants using global positioning environmental radiological surveyor (GPERS) and laser-assisted ranging and data system (LARADS) surveys. This field screening was performed in order to obtain an initial assessment of attainment of radiological cleanup levels

The remaining soils at the 105-H Reactor site were either been deferred to the Field Remediation Closure Project or have been shown to meet the applicable RAGs through verification sampling, analysis, and RESRAD modeling. All excavated materials generated during the D activities were disposed at ERDF, and the area was backfilled to grade with clean backfill. These results also indicate that residual concentrations in the shallow zone will support future land uses that can be represented (or bounded) by a rural-residential scenario and that residual concentrations throughout the site pose no threat to groundwater or the Columbia River.

The three decontamination pads (118-H-6:5) and the Fuel Storage Basin shallow side-slope soils (118-H-6:4) were deferred to the Field Remediation Closure Project and remediated at a

later date.

The SubSite is Part Of:

Code: 118-H-6

Names: 118-H-6; 105-H Reactor Building

Code: 118-H-6:4

Classification: Accepted

Names: 118-H-6:4; 105-H Fuel Storage Basin Shallow Zone Side Slope Soils

Reclassification Interim Closed Out (11/10/2010)

Type: Reactor

Start Date:

Status: Inactive

End Date:

Description: The waste site has been remediated and Interim Closed Out. It encompassed the 118-H-6:4, 105-H Fuel Storage Basin Shallow Zone Side Slope Soils. Based on the results of the applicable cleanup verification package (CVP) document, authorization was given to remove the Soil Contamination Area and Underground Radioactive Material Area postings from this waste site.

Location: The 118-H-6:4 waste site was located on the south side of the 105-H Reactor Building.

Related Sites/ Structures: This subsite is associated with the 100-H-37 contamination migration waste site.

Closure Info: Interim: In April 2004, the 118-H-6:4 Fuel Storage Basin (FSB) Shallow Zone Soil subsite was deferred to the Remedial Action Program to support the safe storage enclosure (SSE) replacement of the 105-H Building roof structure. Backfill and stabilization of the FSB excavation was required to accommodate the roof replacement. In March 2009, further remediation was performed at the 118-H-6:4 waste site resulting in newly exposed shallow zone side-slope soils requiring verification sampling. The side-slope soils in the 105-H FSB shallow zone were located from grade level to 4.6 meters (15 ft) below grade level. Remedial actions occurred in two stages. The first stage was conducted in 2004 during the D&D of the 105-H Reactor ancillary facilities and the FSB. In March 2004, verification samples indicated that radiological cleanup criteria had not been met in the FSB side-slope shallow zone. Further remediation was deferred to the Remedial Action Program to allow backfill and stabilization of the FSB excavation prior to the construction of the Safe Storage Enclosure for the reactor core. Excavation of subsite 4 was resumed on March 17, 2009 and continued through June 29, 2009. Approximately 4,096 bank cubic meters (BCM) (5,358 bank cubic yards [BCY]) of clean overburden material were removed and stockpiled to allow access the original (2004) excavation side-slope soil. Approximately 2,682 BCM (3,508 BCY) of contaminated shallow zone side-slope soil was excavated and direct loaded for disposal at the ERDF. No debris or anomalous material was found during the 2009 excavation.

The SubSite is Part Of:

Code: 118-H-6

Names: 118-H-6; 105-H Reactor Building

Code: 118-H-6:5

Classification: Accepted

Names: 118-H-6:5; 105-H Decontamination Pads

Reclassification Interim Closed Out (10/18/2011)

Type: Reactor

Start Date:

Status: Inactive

End Date:

Description: The waste site has been remediated and Interim Closed Out. It consisted of three, irregularly

shaped, decontamination (decon) pads that were created by the Environmental Restoration Contractor Decommissioning and Demolition Project during remedial activities. The decon pads consisted of compact level gravel areas where cranes and heavy equipment were staged to support the movement and decontamination of parts and equipment in support of the 105-H Reactor interim safe storage activities. Based on the results of the applicable cleanup verification package (CVP or RSVP) documents, authorization was given to remove the Soil Contamination Area and Underground Radioactive Material Area postings from this waste site.

Location: The decon pads were arranged in an arc on the south-southeast side of the 105-H SSE.

Closure Info: Interim (10/18/2011): Remediation of the 118-H-6:5 waste subsite was performed from April 30 through September 30, 2009. Most of the soil was removed and disposed at the ERDF. The original size of each decon pad was slightly smaller than the area excavated. The excavation depth for each pad was approximately 1.0 to 2.0 meters (3.3 to 6.6 ft). Twelve samples were collected from each of the three pads. In March 2009, oily soil was excavated from the surface of the decon pads and the area between and around the decon pads, and stockpiled separately on the decon pad for waste characterization and removal. Following the main excavation, from July 15 through September 30, 2009, focused stained soil excavations occurred to a depth of 3.0 to 4.0 meters (9.8 to 13.1 ft) in the center decon pad.

Following sample analysis of the original excavation, it was determined that additional remediation was needed because three sample locations exceeded direct exposure cleanup criteria. On October 11, 2010 approximately 0.5 meters (2 ft) of soil was removed from a 3 meters (10 ft) diameter area at the west decon pad, WDP-12 sample location.

A portion of the west decon pad was excavated on November 16, 2009 to perform confirmatory sampling for the 100-H-39 (Rejected waste site). Two focused samples were collected from a test pit. The excavated soil was placed back into the test pit, and the area was leveled to match the grade of the remediated 118-H-6:5 west decon pad excavation.

The SubSite is Part Of:

Code: 118-H-6

Names: 118-H-6; 105-H Reactor Building

Code: 118-H-6:6

Classification: Accepted

Names: 118-H-6:6; 105-H Deep Zone Side Slope Soils

Reclassification: Interim Closed Out (6/22/2006)

Type: Reactor

Start Date:

Status: Inactive

End Date:

Description: The 118-H-6:6 has been remediated and Interim Closed Out. It site consisted of the fuel storage basin deep zone side-slope soils.

Closure Info: Interim: Removal and disposal activities at the 105-H site (118-H-6:2, 118-H-6:3, 118-H-6:6 subsites) were completed in 2004. D&D activities, in preparation for the construction of the 105-H Reactor SSE, also resulted in the removal of 100-H-9, 100-H-10, 100-H-11, 100-H-12, 100-H-13, 100-H-14 french drains and the 100-H-31 electrical transformer soil. All materials from the 105-H Reactor ISS Project were demolished and disposed at ERDF. The overburden piles produced during excavation were found to be contaminated. The overburden was deemed unsuitable for use as backfill of the site and was removed to ERDF.

The site was backfilled with clean soil aggregate from the 100-D Area Borrow Pit 21 and graded to match the surrounding terrain. This 105-H D&D activity generated approximately 4,863 bulk containers of low-level contaminated material that were shipped to

ERDF, accounting for approximately 73,966 metric tons (81,365 tons).

Per the Sampling and Analysis Plan, the 105 H Reactor ancillary support areas and below-grade structures (118-H-6:2) did not require sampling and analysis because the structures were removed in their entirety and then disposed at the Environmental Restoration Disposal Facility (ERDF). During the D&D activities, an additional evaluation was required to determine if the soils under the Fuel Storage Basin (FSB) floor (118-H-6:3) had achieved the RAGs. The evaluation of the FSB soils and deep zone side-slope soils (118-H-6:6) also evaluated the soils under the 100-H-11, 100-H-12, and 100-H-14 waste sites. Radiological surveys and verification sampling analysis were performed on the FSB underlying soils and deep zone side-slope soils. The data was used with the RESRAD computer model to verify that cleanup criteria were satisfied. Localized contamination was removed in preparation for clean demolition, and a fixative was applied as required. With one exception, no below-grade structures remaining. The exception is a portion of the FSB floor, at its northern end between the two access labyrinths to the D elevator. It was not removed with this activity.

Verification soil samples were collected from soils under the FSB floor. All demolition debris from excavations associated with the activity was sent to ERDF. Final cleanup verification samples for the FSB underlying soils and deep zone side-slope soils were collected following evaluation of field screening for radiological contaminants using global positioning environmental radiological surveyor (GPERS) and laser-assisted ranging and data system (LARADS) surveys. This field screening was performed in order to obtain an initial assessment of attainment of radiological cleanup levels

The remaining soils at the 105-H Reactor site were either been deferred to the Field Remediation Closure Project or have been shown to meet the applicable RAGs through verification sampling, analysis, and RESRAD modeling. All excavated materials generated during the D activities were disposed at ERDF, and the area was backfilled to grade with clean backfill. These results also indicate that residual concentrations in the shallow zone will support future land uses that can be represented (or bounded) by a rural-residential scenario and that residual concentrations throughout the site pose no threat to groundwater or the Columbia River.

The three decontamination pads (118-H-6:5) and the Fuel Storage Basin shallow side-slope soils (118-H-6:4) were deferred to the Field Remediation Closure Project and remediated at a later date.

The SubSite is Part Of:

Code: 118-H-6

Names: 118-H-6; 105-H Reactor Building

Code: 100-K-84

Classification: Accepted

Names: 100-K-84; Red Soil Found Southwest of 118-K-1

Reclassification Interim Closed Out (12/5/2013)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The site has been remediated and Interim Closed Out. It consisted five small areas of red stained soil. Some of the material appeared crushed while other pieces looked like "slag". Similar piles of material have been found south of the 200 West Area, 100-B Area, and Riverland (McGee Ranch) Area.

Location: The site was located near the 118-K-1 Burial Ground. Three of the small areas were located in the gravel road that runs just southwest of the 118-K-1 Burial Ground. A fourth area is located on the berm between the gravel road and 126-K-1 Gravel Pit. The fifth area is located 154

meters (505 ft) northeast of 126-K-1.

The center coordinates of the five areas are:

E569632.1 N146821.3
 E569555.7 N146785.5
 E569539.4 N146760.7
 E569533.9 N146733.1
 E569721.1 N147078.5.

Process Description: Crushed iron ore was a component of the concrete used in reactor and other facility construction, as it provided additional shielding. The material is highly magnetic. One sample result indicates 74,400 mg/kg iron, while the other sample indicates 103,000 mg/kg iron.

Waste Type: Soil

Waste Description: The waste is areas of red stained soil. X-ray diffraction (XRF) was performed immediately upon identification of the site. The XRF results indicated the presence of arsenic and lead. Later, the site was sampled for inorganics at Lionville. The sample numbers are J15DV5 and J15DV6. Sample number J15DV5 indicated 62.9 mg/kg arsenic and sample number J15DV6 indicated 116 mg/kg arsenic. Lead was not indicated as a contaminant in these two samples. Eberline performed a gamma scan for selected radionuclides. All results were below cleanup limits. The site contaminant of potential concern (COPC) is arsenic.

Closure Info: Interim (12/5/2013): Waste sites 100-K-84, 100-K-86, 100-K-87, 100-K-91, 100-K-92, 100-K-95 were evaluated and reclassified as a group in the same RSVP document.

Remediation of the waste sites began in November 2012 and was concluded in June 2013. Due to elevated residual concentrations of contaminants after the initial remediation(s), additional remediation was required for the 100-K-84, 100-K-87, and 100-K-95 waste sites. All materials removed from the excavations were disposed at the Environmental Restoration Disposal Facility (ERDF) via direct load out. No staging pile areas were associated with the waste sites.

The excavation at the 100-K-84 waste site began on November 5, 2012, and concluded on March 14, 2013. Approximately 2,695 bank cubic meters (BCM) (3,525 bank cubic yards [BCY]) of soil and rock were removed and disposed at ERDF. The maximum depth of the excavation was approximately 0.91 meters (3 ft) bgs.

The excavation at the 100-K-86 waste site began on November 13, 2012, and concluded on January 22, 2013. Approximately 342 BCM (447 BCY) of debris, soil, and rock were removed and disposed at ERDF. The maximum depth of the excavation was approximately 1.5 meters (5 ft) bgs.

The excavation at the 100-K-87 waste site began on February 26, 2013, and concluded on April 3, 2013. Approximately 72 BCM (94 BCY) of debris, soil, and rock were removed and disposed at ERDF. The maximum depth of the excavation was approximately 0.91 meters (3 ft) bgs.

The excavation at the 100-K-91 waste site was conducted on November 28, 2012. Approximately 0.2 BCM (0.26 BCY) of suspect asbestos, soil, and rock were removed and disposed at ERDF. The maximum depth of the excavation was approximately 1.2 meters (4 ft) bgs.

The excavation at the 100-K-92 waste site began on November 13, 2012, and concluded on December 13, 2012. Approximately 32 BCM (42 BCY) of debris, soil, and rock were removed and disposed at ERDF. The maximum depth of the excavation was approximately 0.6 meters (2

ft) bgs.

The excavation at the 100-K-95 waste site began on January 8, 2013, and concluded on June 24, 2013. Approximately, 4,272 BCM (5,588 BCY) of soil and rock were removed and disposed at ERDF. The maximum depth of the excavation at the 100-K-95 waste site was approximately 1.5 meters (5 ft) bgs.

Code:	100-K-96	Classification:	Accepted
Names:	100-K-96; 100KE River Effluent Pipeline; 100KE River Line; River Line (East) from 116-K-3 Outfall	Reclassification	None
Type:	Radioactive Process Sewer	Start Date:	
Status:	Inactive	End Date:	4/14/2011
Description:	100-K-96 is a 213 centimeters (84 inches) diameter, carbon steel river effluent pipelines that extends from the face of 116-K-3 outfall structure to the Columbia River. The 100-K-80 pipeline runs parallel to 100-K-96. The pipelines are approximately 122 centimeters (48 inches) apart. In January 2012, the river effluent pipeline designations were split. The portion of the 100-K-96 pipeline that extends into the river was given a new WIDS sitecode (100-K-114).		
Location:	The 100-K-96 river pipeline is located on the Columbia River shore, adjacent to the 100K Area. It is east of the adjacent, inactive 100-K-80 pipeline.		
Related Sites/Structures:	The pipeline site is associated with the 116-K-3 Outfall Structure, the 100-K-83 Spillway, the 100-K-47 process sewer, 100-K-56 process effluent lines, the 100-K-55 process effluent lines, the 100-K-60 process sewer, the 116-KW-3 Retention Basins, the 100-K-80 river pipelines, and the 100-K-114 pipeline segment.		
Process Description:	105-KE reactor cooling water was collected and temporarily stored in the 107-KE Retention Basins. The cooling water was discharged to the river, bypassing (underneath) the 116-K-3 outfall structure, through the 100-K-96 river pipeline. Process sewer waste, from both 100-KE and 100-KW facilities, entered the outfall structure and dropped into the 100-KE river pipeline through large-diameter, vertical standpipes welded onto the river pipelines.		
	Retention basins lines (100-K-55 and 100-K-56) did not discharge through the outfall structure, but passed under it. They are continuous lines from each reactor that become the river effluent pipelines downstream of the outfall structure. The pipelines discharge into a recessed, sloped riprap river bed structure, measuring 9 meters (30 feet) wide by 12 meters (40 feet) long and 1 meter (3 feet) thick. The total drop from the face of the outfall structure to the discharge end of the pipelines is 18 meters (60 feet).		
	In 1955, the lines began to float and break. Both lines were damaged. To remedy the problem, a 2 to 3 meter (6 to 10 feet) thick riprap jetty was placed over the lines from the shoreline to a point approximately 320 meters (1050 feet) from the face of the outfall structure.		
Waste Type:	Process Effluent		
Waste Description:	The waste includes the pipeline and the contaminated scale contained within it. The effluent included both reactor cooling water and process sewer waste. The Contaminants of Potential Concern are based on the 116-K-3 outfall, and include Co-60, Cs-137, Eu-152, Eu-154, Pu-239/240, and Sr-90.		

Code:	100-K-110	Classification:	Accepted
--------------	-----------	------------------------	----------

Names: 100-K-110; 183KW; 183-KW; Soil Beneath 183.2-KW Flocculation and Sedimentation Basins; the 183.3-KW Sand Filter Basins

Reclassification None

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The site consists of the soil beneath the removed structures of the 183.2-KW Sedimentation Basins and 183.3 KW Sand Filter Basins. The site was added to WIDS in 2011 as a result of sampling the soil under the 183.2-KW Flocculation and Sedimentation Basins, the 183.3-KW Sand Filter Basin, and the 183.7-KW Pipe Tunnel structures after the demolition activities.

Location: The site is located south of the 105-KW Reactor.

Code: 100-K-111

Classification: Accepted

Names: 100-K-111; Effluent Seepage Area from 116-K-2

Reclassification None

Type: Contamination Migration

Start Date:

Status: Inactive

End Date:

Description: The site is an area along the Columbia River shoreline appears to have been impacted by effluent from the 116-K-2 trench. This suspicion is evidenced by surface features visible in historical photograph (37465-10CN taken in 1964).

Location: The site is 363 meters (1,191 ft) northeast of 116-KE-4 (107-KE Retention Basins).

Release

Description:

Related Sites/ Structures: The surface liquids are northwest of the mile long trench (116-K-2). This trench was associated with 116-KE-4 and 116-KW-3 Retention Basins via the 100-K-55 and 100-K-56 pipelines.

Process Description: The 116-K-2 trench received contaminated effluent from floor drains and the fuel storage basin overflows in the 105-KE and 105-KW Reactors, as well as emergency discharges from the 107-KE and 107-KW Retention Basins. Until 105-KE and 105-KW shut down around February 1, 1970, an undetermined amount of Retention Basin effluent (believed to be up to 37,854 LPM (10,000 GPM)) leaked through 107 cm (42 inch) butterfly valves in the tank bottoms. Other periodic flows included low volume, neutralized, dummy decontamination waste, process-cooling water during charge/discharge; occasional special disposals; and an occasional tank of process cooling water that was collected after a fuel cladding failure. In 1978, the radioactive inventory of the trench was calculated at 2,100 curies (UNI-946).

Prior to 1977, surface contamination extended several hundred feet along the river side of the unit. This surface contamination was covered with up to 1.2 meters (4 ft) feet of soil and gravel during the summer of 1977, and posted with AC-5-40 concrete markers (DC-0023). The concrete post locations have been surveyed. The entire site was posted as underground radioactive material.

The 100K Area geology and hydrology were such that liquid discharges to the soil within the operating area routinely bled out the shore line as it sloped to the river. Also within this area is the leach trench that was installed to drain the cobble filled trench from waste site 116-K-1 to the river (DOE/RL-94-61).

In September 1996 contaminated soil was removed from the site. In 1997, a single test pit was excavated on the south side of 116-K-2 (approximate coordinates were N147260/E569400).

Radiological surveys of the soil did not identify any contamination.

Code: 100-K-112 **Classification:** Accepted
Names: 100-K-112; Surface Contamination from Waste Storage Operations **Reclassification** Rejected (12/6/2012)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The waste site has been evaluated and reclassified to Rejected. It had been a posted Contamination Area remaining after waste stored in this area was removed. The storage area had been approximately 12. by 6.7 meters (41 by 22 feet). Nothing was being stored within the boundaries of the storage area in 2007, when the contamination was identified. Six to twelve inches of soil was removed from inside the smaller Contamination Area in December 2011. The excavated area was also filled to grade with clean material and the posting was changed back to the 100-K Operational Area Underground Radioactive Material Area status.

Location: The waste site is located north of 105-KW, adjacent to the 100-K Area perimeter fence. It is north of Wakefield Loop.

Code: 100-K-113 **Classification:** Accepted
Names: 100-K-113; 100KW Columbia River Effluent Pipeline; Portion of Effluent Piping Extending Beyond River Shore **Reclassification** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: 100-K-113 is a 213 centimeters (84 inches) diameter, carbon steel river effluent pipelines that extends beyond the river shoreline, into the Columbia River. The 100-K-113 pipeline runs parallel to 100-K-114. The pipelines are approximately 122 centimeters (48 inches) apart. In January 2012, the river effluent pipeline designations were split. The portion of the 100-K-80 pipeline that extends into the river was given a new WIDS sitecode (100-K-113).

Both the 100-K-113 and 100-K-114 pipelines are exposed along most of the run, protruding 0.3 to 0.9 meters (1 to 3 feet) above the riverbed. They were originally covered by a minimum of 0.6 meter (2 feet) of soil over their entire length.

Location: The 100-K-113 river pipeline site is located in the Columbia River, adjacent to the 100K Area. It is west of the adjacent 100-K-114 pipeline.

Related Sites/ Structures: This portion of pipeline is the in-river extension associated with the 100-K-80 pipeline.

Waste Type: Process Effluent

Waste Description: The Contaminants of Potential Concern are based on the 116-K-3 outfall, and include Co-60, Cs-137, Eu-152, Eu-154, Pu-239/240, and Sr-90.

Code: 100-K-114 **Classification:** Accepted
Names: 100-K-114; 100KE Columbia River Effluent Pipeline; Portion of Effluent Piping Extending **Reclassification** None

Beyond River Shore

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: 100-K-114 is a 213 centimeters (84 inches) diameter, carbon steel river effluent pipelines that extends beyond the river shoreline, into the Columbia River. The 100-K-114 pipeline runs parallel to 100-K-113. The pipelines are approximately 122 centimeters (48 inches) apart. In January 2012, the river effluent pipeline designations were split. The portion of the 100-K-96 pipeline that extends into the river was given a new WIDS sitecode (100-K-114).

Both the 100-K-113 and 100-K-114 pipelines are exposed along most of the run, protruding 0.3 to 0.9 meters (1 to 3 feet) above the riverbed. They were originally covered by a minimum of 0.6 meter (2 feet) of soil over their entire length.

Location: The 100-K-114 river pipeline site is located in the Columbia River, adjacent to the 100K Area. It is east of the adjacent 100-K-113 pipeline.

Related Sites/ Structures: This portion of pipeline is the in-river extension associated with the 100-K-96 pipeline.

Waste Type: Process Effluent

Waste Description: The Contaminants of Potential Concern are based on the 116-K-3 outfall, and include Co-60, Cs-137, Eu-152, Eu-154, Pu-239/240, and Sr-90.

Code: 100-K-115

Classification: Accepted

Names: 100-K-115; 1717-K Potential Asbestos in Soil

Reclassification: None

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The waste site is the potential asbestos containing material (ACM) left in place following the demolition of the 1717K building. 1717K was demolished in August 2011. The gravel covered area encompasses the footprint of the demolished structure. It is surrounded with concrete barriers and rope. Signs have been posted that say "Caution: Potential Asbestos Hazard; Transite in the Soil; No ground-intrusive or heavy equipment activities in this area unless specifically authorized by controlling project OS&H", due to a potential for encountering asbestos material remaining after the demolition of the structure. Determination of ACM left in place and abated during demolition is based on a Quality Assurance review of project documentation and interviews with activity personnel.

Location: The demolished building site is located near the corner of K Ave. and Wagner St.

Code: 100-K-116

Classification: Accepted

Names: 100-K-116; 1720-K Potential Asbestos in Soil

Reclassification: None

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The waste site is the potential asbestos containing material (ACM) left in place following the demolition of the 1720K building. 1720K was demolished in August 2011. The gravel covered area encompasses the footprint of the demolished structure. It is surrounded with concrete

barriers and rope. Signs have been posted that say "Caution: Potential Asbestos Hazard; Transite in the Soil; No ground-intrusive or heavy equipment activities in this area unless specifically authorized by controlling project OS&H", due to a potential for encountering asbestos material remaining after the demolition of the structure. Determination of ACM left in place and abated during demolition is based on a Quality Assurance review of project documentation and interviews with activity personnel.

Location: The demolished building site is located near the corner of K Ave. and Willard St., near the main entrance to 100-K.

Code: 100-K-117 **Classification:** Discovery

Names: 100-K-117; 183-KW Chlorine Vault Building Foundation Soil Footprint **Reclassification:** None

Type: Foundation **Start Date:**

Status: Inactive **End Date:**

Description: The waste site was added to address potential selenium contaminated soil beneath the demolished 183-KW building.

Location: The 183 KW Chlorine Vault was located west of the 183.1 KW Headhouse.

Code: 100-K-118 **Classification:** Accepted

Names: 100-K-118; 183.1-KW; 183.1KW Headhouse Building Foundation; Potential Asbestos in Soil **Reclassification:** None

Type: Foundation **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is the location of the demolished 183.1 KW Headhouse. Excavation has been backfilled with dirt and gravel. The area posted is much larger than the building foot print. It is posted as Danger Demolition Area.

Location: The 183.1KW head house was located south of the 183.2KW sedimentation basins.

Code: 100-K-119 **Classification:** Accepted

Names: 100-K-119; 182-K; 182K Potential Asbestos Hazard in Soil **Reclassification:** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is the backfilled excavation site of the demolished 182-K water reservoir and pump house. The area is currently not posted. Backfilled with lay-back material and a dirt and gravel cap.

Code: 100-K-120 **Classification:** Accepted

Names: 100-K-120; 110-KW; 110KW Potential Asbestos in Soil **Reclassification:** None

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The waste site is the location of the demolished 110KW building. The site is surrounded with yellow rope. It is posted with Danger Fall hazards, Danger Demolition Area and Danger Asbestos signs. The area posted is much smaller than the actual building foot print. It is attached to 115-KW that is still standing.

Code: 100-K-121

Classification: Accepted

Names: 100-K-121; 115-KE; 115KE Potential Asbestos in Soil

Reclassification: None

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The waste site is the potential asbestos left in place following the demolition of the 115-KE building. The 115-KE footprint is located inside the large, deep carbon-14 contamination plume excavation known as the AH area. Determination of ACM left in place and abated during demolition is based on a Quality Assurance review of project documentation and interviews with activity personnel.

The 115-KE building was demolished in March 2011.

Location: The 115-KE building had been located near the southeast corner of the 105-KE Reactor building.

Code: 100-K-122

Classification: Accepted

Names: 100-K-122; 1706-KE; 1706KE Potential Asbestos in Soil

Reclassification: None

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The waste site is the potential asbestos left in place following the demolition of the 1706-KE building. The 1706-KE footprint is located inside the large, deep remediation excavation known as the AG area. Cesium and strontium contamination with levels above regulatory concern were found in the AG area deep zone. Determination of ACM left in place and abated during demolition is based on a Quality Assurance review of project documentation and interviews with activity personnel.

The 1706-KE building was demolished in September 2009.

Location: The 1706-KE building had been located near the southwest corner of the 105-KE Reactor building.

Code: 100-K-123

Classification: Accepted

Names: 100-K-123; 183.1-KE; 183.1KE Potential Asbestos in Soil

Reclassification: None

Type: Dumping Area

Start Date:

Status: Inactive**End Date:**

Description: The waste site is potential asbestos left in place following the demolition of the 183.1-KE head house facility structure. The head house was demolished in September 2011. The head house had been located with the existing large, open excavation. The open excavation is posted as Danger Fall hazards, Danger Demolition Area and Danger Asbestos. The area posted is much larger than the building foot print. Determination of asbestos containing material (ACM) left in place and abated during demolition is based on a Quality Assurance review of project documentation and interviews with activity personnel.

Location: The 183.1KE head house was located south of the 183.2KE sedimentation basins.

Code: 100-K-124**Classification:** Accepted

Names: 100-K-124; 183.5-KE; 183.5KE Potential
Asbestos in Soil

Reclassification: None**Type:** Dumping Area**Start Date:****Status:** Inactive**End Date:**

Description: The waste site is the potential asbestos left in place following the demolition of the 183.5-KE Lime Feeder structure. 183.5KE was a small structure located on the roof of the 183.4KE clearwell reservoir and was demolished in April 2011. The roof of the clearwell was demolished in September 2011. The area where the structure had been located is currently a large open excavation. The area is posted as Danger Fall hazards, Danger Demolition Area and Danger Asbestos. The area posted is much larger than the building foot print. Determination of ACM left in place and abated during demolition is based on a Quality Assurance review of project documentation and interviews with activity personnel.

Location: The 183.5-KE structure was located on the southwest corner of the roof of the 183.4-KE Clearwell structure.

Process Description: The building was the Lime Feeder structure associated with the 183.4KE Clearwell.

Code: 100-K-125**Classification:** Accepted

Names: 100-K-125; 183.6-KE; 183.6KE Potential
Asbestos in Soil

Reclassification: None**Type:** Dumping Area**Start Date:****Status:** Inactive**End Date:**

Description: The waste site is the potential asbestos left in place following the demolition of the 183.6-KE Lime Feeder structure. 183.6KE was a small structure located on the roof of the 183.4KE clearwell reservoir and was demolished in April 2011. The roof of the clearwell was demolished in September 2011. The area where the structure had been located is currently a large open excavation. The area is posted as Danger Fall hazards, Danger Demolition Area and Danger Asbestos. The area posted is much larger than the building foot print. Determination of ACM left in place and abated during demolition is based on a Quality Assurance review of project documentation and interviews with activity personnel.

Location: The 183.6-KE structure was located on the southeast corner of the roof of the 183.4-KE Clearwell structure.

Process The building was the Lime Feeder structure associated with the 183.4 Clearwell.

Description:

Code: 100-K-126

Classification: Accepted**Names:** 100-K-126; 183.5-KW; 183.5KW Potential
Asbestos in Soil**Reclassification** None**Type:** Dumping Area**Start Date:****Status:** Inactive**End Date:**

Description: The waste site is the potential asbestos left in place following the demolition of the 183.5-KW Lime Feeder structure. 183.5KW was a small structure located on the roof of the 183.4KW clearwell reservoir and was demolished in May 2010. The roof of the clearwell was demolished in September 2011. The area where the structure had been located is currently a large open excavation. The area is posted as Danger Fall hazards, Danger Demolition Area and Danger Asbestos. The area posted is much larger than the building foot print. Determination of ACM left in place and abated during demolition is based on a Quality Assurance review of project documentation and interviews with activity personnel.

Location: The 183.5-KW structure was located on the southwest corner of the roof of the 183.4-KW Clearwell structure.

Process The building was the Lime Feeder structure associated with the 183.4KW Clearwell.

Description:

Code: 100-K-127

Classification: Accepted**Names:** 100-K-127; 183.6-KW; 183.6KW Potential
Asbestos in Soil**Reclassification** None**Type:** Dumping Area**Start Date:****Status:** Inactive**End Date:**

Description: The waste site is the potential asbestos left in place following the demolition of the 183.6-KW Lime Feeder structure. 183.6KW was a small structure located on the roof of the 183.4KW clearwell reservoir and was demolished in April 2010. The roof of the clearwell was demolished in September 2011. The area where the structure had been located is currently a large open excavation. The area is posted as Danger Fall hazards, Danger Demolition Area and Danger Asbestos. The area posted is much larger than the building foot print. A small area, adjacent to where 183.6 KW was demolished, is roped off and posted "Caution Potential Asbestos Hazard in Soil". Orange stakes document sample locations. It is above the open excavation.

Determination of ACM left in place and abated during demolition is based on a Quality Assurance review of project documentation and interviews with activity personnel.

Location: The 183.6-KW structure was located on the southeast corner of the roof of the 183.4-KW Clearwell structure.

Process The building was the Lime Feeder structure associated with the 183.4KW Clearwell.

Description:

Code: 100-K-128

Classification: Accepted

Names: 100-K-128; 190-KE; 190KE Potential Asbestos in Soil **Reclassification** None
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is the potential asbestos containing material (ACM) left in place following the demolition of the 190-KE Pump House. The pump house was demolished in September 2011. The area is a large open excavation posted as Danger Fall hazards, Danger Demolition Area and Danger Asbestos. The area posted is much larger than the building foot print. The 190-KE basement floor and tunnel were left intact. The open 190-KE excavation is adjacent to the demolished 183.4KE clearwell excavation. Determination of ACM left in place and abated during demolition is based on a Quality Assurance review of project documentation and interviews with activity personnel.

Location: The 190-KE pump hose was located on the north side of the 183.4-KE clearwell reservoir. It was attached to the south side of the 165-KE Power Control building.

Code: 100-K-129 **Classification:** Accepted
Names: 100-K-129; 190-KW; 190KW Potential Asbestos in Soil **Reclassification** None
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is the potential asbestos containing material (ACM) left in place following the demolition of the 190-KW Pump House. The pump house was demolished in December 2011. The area is a large open excavation posted as Danger Fall hazards, Danger Demolition Area and Danger Asbestos. The area posted is much larger than the building foot print. The 190-KW basement floor and tunnel were left intact. The open 190-KW excavation is adjacent to the demolished 183.4KW clearwell excavation. Determination of ACM left in place and abated during demolition is based on a Quality Assurance review of project documentation and interviews with activity personnel.

Location: The 190-KW pump hose was located on the north side of the 183.4-KW clearwell reservoir. It was attached to the south side of the 165-KW Power Control building.

Code: 100-K-130 **Classification:** Accepted
Names: 100-K-130; 181KE; 181-KE Pump House Potential Asbestos in Soil **Reclassification** None
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is the potential asbestos containing material (ACM) left in place following the demolition of the 181-KE Pump House. The pump house was demolished in September 2011. Determination of ACM left in place and abated during demolition is based on a Quality Assurance review of project documentation and interviews with activity personnel.

Location: The 181-KE pump house had been located at the river shore, north of the 107KE and 107KW retention basins.

Code: 100-K-131 **Classification:** Accepted
Names: 100-K-131; 1908KE; 1908-KE Water Monitoring Station Potential Asbestos in Soil **Reclassification:** None
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is the potential asbestos containing material (ACM) left in place following the demolition of the 1908-KE water monitoring station building. The structure was demolished in January 2011. Determination of ACM left in place and abated during demolition is based on a Quality Assurance review of project documentation and interviews with activity personnel.

Location: The 1908-KE water monitoring station had been located south of Winlock Street, west of the 107KE basins.

Code: 100-K-132 **Classification:** Accepted
Names: 100-K-132; Deep Vadose Zone Contamination Below 118-K-1 Burial Ground **Reclassification:** None
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is an area of deep vadose zone soil contamination beneath the southern portion of the remediated 118-K-1 Burial Ground. Remedial actions at the 118-K-1 Burial Ground first occurred between May 30, 2006 and July 2008. It was then placed in a safe shutdown with stabilization of the remaining trenches, pits, and silos. The remedial activities resumed in October 2009 and concluded on March 29, 2012. The contamination is associated with the former Trenches O and N, and the southern portion of Trench K.

Location: The site is located approximately 240 meters northeast of the 105-KE Reactor Building, outside the perimeter fence, beneath the 118-K-1 waste site. The area is located at the southern end of the former burial ground.

Related Sites/ Structures: The site is associated with 118-K-1 burial ground.

Process Description: The 118-K-1 Burial Ground received solid waste from both the 100-K and 100-N Areas. Waste was disposed in numerous unlined trenches and in-ground silos.

Code: 118-KE-1 **Classification:** Accepted
Names: 118-KE-1; 105-KE Reactor Building **Reclassification:** Rejected (6/8/2015)
Type: Reactor **Start Date:** 1/1/1955
Status: Inactive **End Date:** 1/1/1971

Description: The waste site consists of the reactor block, which includes the graphite moderator stack, biological and thermal shields, pressure tubes, and the safety and control systems. It is an above grade structure and has been reclassified to Rejected because it does not meet the definition of a waste site. The site also includes contaminated portions of the reactor building and remnant contaminated pipelines connected to the buildings that were not removed through other remedial actions. The fuel storage basin is a separate site (see sitecode 100-K-42).

Location: The unit is located at the east end of the 105-KE/KW exclusion area fence.

Related Sites/ Structures: The 105-KE Fuel Storage Basin is a separate waste site because of past leakage. The basin is sitecode 100-K-42.

Waste Type: Equipment

Waste Description: The unit contains an estimated 58,000 curies of radionuclides, 151,000 kilograms (167 tons) of lead, and 708 cubic meters (25,000 cubic feet) of asbestos.

Code: 118-KW-1

Classification: Accepted

Names: 118-KW-1; 105-KW Reactor Building

Reclassification: Rejected (6/8/2015)

Type: Reactor

Start Date: 1/1/1955

Status: Inactive

End Date: 1/1/1970

Description: The waste site consists of the reactor block, which includes the graphite moderator stack, biological and thermal shields, pressure tubes, and the safety and control systems. It is an above grade structure and has been reclassified to Rejected because it does not meet the definition of a waste site. It also includes contaminated portions of the reactor building and remnant contaminated pipelines connected to the buildings not removed through other remedial actions. The fuel storage basin is sitecode 100-K-43.

Location: The site is located at the west end of the 105-KE/105-KW exclusion area fence.

Release Description: The analogues site at 105-KE contained Cobalt-60, Strontium-90, Cesium-137 and small amounts of plutonium were noted in the soil beneath the 105- K East basin.

Related Sites/ Structures: The 105-KW Fuel Storage Basin is a separate site because of past leakage. The fuel storage basin is sitecode 100-K-43. The basin leakage and contaminated soil is sitecode 100-K-82.

Waste Type: Equipment

Waste Description: This unit contains an estimated 51,000 curies of radionuclides, 1.41E+05 kilograms (155 tons) of lead, and 708 cubic meters (25,000 cubic feet) of asbestos.

Code: 100-N-66

Classification: Accepted

Names: 100-N-66; 105-N/109-N Reactor Building Complex

Reclassification: None

Type: Reactor

Start Date: 1/1/1963

Status: Inactive

End Date: 1/1/1987

Description: The waste site is the 105-N Reactor Building and the 109-N Heat Exchange Building, which shared a common wall. The demolition of the ancillary portions of the 109-N and 105-N buildings began in the spring of 2007 and continued through September 2012. The objective of the demolition activities was to make necessary modifications to the structures to construct the Interim Safe Storage (ISS) Safe Storage Enclosure (SSE) for the 105-N reactor core. The removal of above and below grade structures, up to the SSE boundary, was completed in November 2011. More than one hundred thousand tons of material was shipped to the ERDF facility. A steel roof was placed on the remaining, reactor core enclosure. Excavation areas were radiologically surveyed and backfilled.

In late August 2009, as below-grade demolition was nearing completion, a visual inspection of the excavation identified that cold joint material had fallen to ground from the outside walls of the Safe Storage Enclosure (SSE). The black material was sampled and the analysis indicated

the mastic portion contained between 20% and 30% asbestos.

The 2013 Facility Status Change Form for the 105-N/109-N Buildings (D4-100N-0046) document discusses several items identified where contamination and asbestos was found outside the south and east sides of 105-N/109-N that was left in place. Items left in place include: Mastic containing asbestos stuck to the outside of the 109-N Building's southern and eastern below-grade Safe Storage Enclosure walls; Two areas where short sections of contaminated pipe remain embedded in a below-grade outer foundation on the east side of the 109-N Building; Radiological contamination fixed to the outer Safe Storage Enclosure wall below grade on the east side of the 105-N Building; Radiological contamination in soil underneath the former 105-N Zone 1 Supply Plenum; An anomaly left in the soil below grade on the west side of the 105-N Building.; Radiological contamination fixed to below grade structures on the west side of the 105-N Building and Radiological contamination left in the soil below portions of the 105-N Building.

Shutdown of the N Reactor was ordered in October 1991. N-Reactor Deactivation activities occurred from 1995 through 1998. Operational systems were isolated and hazardous and radiological wastes were removed from 83 facilities at the N Reactor Complex. Over 80,000 cubic feet of solid wastes and 1.7 million gallons of liquid waste were removed during that activity. The 105-N Fuel Storage Basin was cleaned and stabilized. Empty fuel canisters were retrieved and removed. High pressure washing of the basin was required to reduce dose rates and contain airborne contamination hazards. Basin sediments were characterized and removed to the ERDF facility. The fuel storage basin water was removed and transferred to the 200 Area Effluent Treatment Facility and Liquid Effluent Retention Facility.

Final decommissioning and decontamination of the ancillary facilities began in 2007 and was nearly complete in 2008 when demolition activities commenced to remove the southern and eastern portions of the 109-N Building outside the steam generator cells. The removal of these areas, and the areas outside of shield walls surrounding the reactor proceeded in a general counterclockwise pattern around 105-N/109-N until September 2012. Twenty-three WIDS waste sites were within or adjacent to the facility footprint. Nine were completely removed and fourteen were partially removed. The demolition at 105-N/109-N included removing and properly disposing flammable and hazardous material (e.g., oils, grease, asbestos-containing material, mercury, lead and polychlorinated biphenyls [PCBs]). During demolition activities, the construction of a Safe Storage Enclosure roof was coordinated. Excavations left from demolition activities were visually inspected for stains and anomalies and surveyed for radiological contamination prior to backfill. Above and below-grade penetrations into the Safe Storage Enclosure were sealed to prevent animal and insect intrusion, and water in-leakage. Most of the material used to backfill was obtained from the nearby 100-N borrow pit.

On September 19, 2012, a concrete wall (pour back) that had been constructed over the former Fuel Storage Basin's fast cart tunnel was sealed. Sealing this pour back signified completion of the SSE and the Tri-Party Agreement (TPA) Milestone M-093-020.

The 105-NA and 1722-N buildings were demolished in August 2010. A portion of 100-N-66 (105-N) was removed by this activity. Following demolition and removal 105-NA and 1722-N, considerable cleanup of the 105-N Reactor building occurred within, and around the footprints of these buildings. The subsequent excavation removed much, if not all, of the radiological contamination directly associated with them. However there is a potential for the soil beneath them to be contaminated. Therefore, the footprints of the 105-NA and 1722-N buildings will be considered part of 100-N-66.

The above-grade and below-grade portions of the 105-NE Fission Products Trap were demolished and excavated between November 2011 and April 2012. Residual radiological contamination was detected during post-demolition GPERS surveys performed at the footprint

of the 105-NE Fission Products Trap. This contamination was deferred to the 100-N-66 site.

Demolition of the 117N Exhaust Air Filter House and the 117-NVH Valve Control House was completed in 2011. The southern-most portion of the 117N facility consists of the tunnels between 117N and the 105N/109N facilities. The southern portions include the footprint beneath the former tunnels between 117N facility and 105N/109N facilities were greater than 1.5 X background. The contamination that remains in the footprint of these tunnels will be addressed as part of 100-N-66. The 117N building and the northern portion of the tunnel footprint were not radiologically contaminated and do not require further dispositioning. These portions were not deferred to 100-N-66.

Location: The 105-N and 109-N buildings are located in the center of the 100-N Area of the Hanford Site.

Related Sites/ Structures: Structures associated with the 105-N Reactor Building are the 1312-N liquid retention facility, 1734-N Building, the 117-N Filter Building and a stack used for discharge of reactor ventilation air, chemical waste storage tank for decontamination solutions and the 1301-N and 1325-N cribs and tile fields. Structures associated with the 109-N Building are the dump tank for emergency discharge of primary coolant located on the west side of the building, sealwell and outfall system to return condenser cooling and condensate water to the Columbia River. UPR-100-N-35 has been consolidated with Reactor facility (100-N-66).

Process Description: The 105-N Reactor is a graphite-moderated, light-water cooled, horizontal-pressure-tube nuclear reactor. The reactor piping was designed for 13,000 kilopascals (1,825 pounds per square inch) and 320 degrees Celsius (600 degrees Fahrenheit) maximum operating conditions. Normal operating parameters were 11,000 kilopascals (1,600 pounds per square inch) and approximately 290 degrees Celsius (550 degrees Fahrenheit). The reactor coolant circulating pumps are single-stage, horizontal, centrifugal pumps with high pressure water injection seals to prevent reactor coolant loss. As in the other reactor buildings a zoned ventilation system is provided so that air flow is maintained in the direction of areas having the greatest potential risk of contamination. The control room has its own refrigerated air conditioning system. The 105-N Reactor Building is 137.77 meters (452 feet) by 78.94 meters (259 feet) with a stepped roof to 21.34 meters (70 feet). Additionally, a 55.78 meters (183 feet) by 21.34 meters (70 feet) basin and transfer area extend west at the southwest corner. The breakdown of the facility is 29 offices: 467.29 square meters (5,030 square feet); 4 shops: 1,009.82 square meters (10,870 square feet); storage: 295.42 square meters (3,180 square feet); common: 467.29 square meters (5,030 square feet); process, operating and fuel storage: 13,006 square meters (1.4E+05 square feet).

The 109-N Building contained a large pipe gallery on the north side which receives the primary reactor coolant system piping from the reactor for distribution into five separate cells each housing two large heat exchangers, a primary circulating pump and associated piping. A sixth cell contained a heat exchanger system for the moderator cooling system. The pipe gallery and steam generator cells were located in a reinforced concrete enclosure which defined a confinement zone. Located outside of the confinement zone were the pump drive systems, dump condensers for disposal of export steam, condensate return pumps, other auxiliary equipment, a small chemical laboratory, and water sampling and monitoring facilities. A Service Bay had facilities for decontaminating the primary coolant system and contains the heating and ventilation equipment, shop areas, office and common space. The 109-N Building was 62.79 meters (206 feet) by 116.74 meters (383 feet) by 11.89 meters (39 feet) high. The facility included 3 offices: 75.25 square meters (810 square feet); 2 shops: 197.88 square meters (2,130 square feet); common: 111.48 square meters (1,200 square feet); processing area: 11,148 square meters (1.23E+05 square feet).

For special nuclear material production (no steam generation to the Hanford Generating Plant [HGP]), steam from the secondary side of ten steam generators was routed through 16 river water-cooled dump condensers. Condensate from the dump condensers was routed back to

steam generators for regeneration. For dual-purpose operation, byproduct steam from the steam generators was supplied to the HGP to produce 860 megawatts (electrical). For either single- or dual-purpose operation, there were 12 steam generators. Ten of the steam generators were used during five-cell operation and eight for four-cell operation. During dual-purpose operation, most of the steam produced was available for use by HGP to generate electricity, with some reserved to power the reactor coolant system pump drive turbines and the in-plant turbine generator.

The N Reactor used a confinement system based on the concept to release the initial burst of steam resulting from a postulated reactor coolant pipe break. When the confinement pressure subsided, the steam vents were closed and ventilation valves opened. The ventilated steam was filtered through charcoal and high efficiency filters to prevent any release of fission products from fuel failure. The 1312-N Liquid Effluent Retention Facility (LERF) was constructed as part of the safety enhancement program initiated in 1987. This facility served as a backup to the existing containment system and was designed to receive primary cooling water in the event of an emergency, such as fuel failure. The LERF facility consists of a high-density polyethylene bladder contained within a lined berm impoundment. The LERF was never used. The portion of the reactor coolant system within the N Reactor building consists of 16 parallel lines that conducted cooling water from an inlet water manifold in the 109-N Heat Exchanger Building to the reactor. Each of these 16 lines terminates in a vertical header to which is attached 54 to 66 individual pressure tube header-to-inlet nozzle connectors. Similar outlet risers and parallel lines conducted the coolant from the pressure tube outlet nozzle-to-header connectors to an outlet water manifold. In the 109-N Heat Exchanger Building, which is immediately adjacent to the N Reactor building, the reactor coolant system consisted of six cells in parallel, each containing two steam generators (in parallel), a circulating pump and associated valves and instrumentation. Piping and steam generators in each of the six cells could be isolated from the main header piping by means of isolation valves.

Reactor coolant pressure and temperature were controlled to prevent boiling at any point in the system. A surge vessel (pressurizer) controlled system pressure and volume surges resulting from normal coolant density changes during reactor transient heat output conditions. The pressurizer consists of a cylindrical pressure vessel with a useful volume of about 34 cubic meters (1,200 cubic feet) and was connected directly to the reactor outlet piping. Two electric immersion heater systems maintained the pressurizer at saturation temperature and pressure retaining approximately 40% useful surge volume during normal operations. During outsurges of water from the pressurizer, the drop in pressure was compensated for by flashing steam from the saturated water. Increases in system pressure were limited by injecting a water spray into the steam space to condense some of the steam. This spray was reactor coolant fed from either reactor inlet water or from the high pressure injection pumps.

The secondary steam system for the N Reactor removed the reactor heat from the reactor coolant system by boiling secondary water in the shell side of the steam generator. During operation solely for the production of special nuclear material the major fraction of this steam was routed to 16 dump condensers which were arranged in parallel and cooled by untreated Columbia River water. These condensers operated at a pressure near that of the steam generators and eliminated the need for steam pressure reducing stations. Condensate was pumped from the dump condensers back to the steam generators for recycling. To achieve maximum single purpose productions operation, the steam temperature and pressures were maintained as low as practicable. A portion of the steam generated was utilized by the coolant pump drive turbines and by the turbine generator for local station service. During dual purpose operation, the major fraction of steam generated was routed to the HGP. A portion of the steam generated was used to drive the reactor coolant pumps, the onsite turbine generator and to keep the dump condensers warm so they were ready to accept full steam load in the event of an HGP turbine generator shutdown. Strained untreated water from the Columbia River was supplied as coolant to the dump condensers as well as the reactor coolant pump drive turbine surface

condensers and the local turbine generator condensers. This condenser cooling water was then returned to the river.

The fuel used for operation of the N Reactor was slightly enriched uranium-235 (0.94% to 1.25%), clad with a zirconium alloy. At shutdown, a concentric tube-in-tube fuel design was in use. In the past, other materials have been used as a target in connection with an enriched uranium driver fuel element to produce useable isotopes such as tritium and plutonium-238. The fuel cladding is zircaloy-2 metallurgically bonded to the uranium by a co-extrusion process. The fuel elements used in N Reactor were manufactured by United Nuclear Corporation and ranged from 38 to 66 centimeters (15 to 26 inches) in length.

Waste Type: Equipment

Waste Description: The waste is the 105-N/109-N Building complex, including the reactor core. The 105-N and 109-N Building complex is radioactively contaminated or potentially contaminated within all confinement zones, irradiated fuel storage areas, primary and secondary coolant piping systems, and confinement ventilation systems. During demolition approximately 82,107 square feet of asbestos containing material was removed. Thirty two tons of lead was treated and disposed in ERDF along with numerous mercury containing switches, manometers and instruments.

Code: 100-N-79

Classification: Accepted

Names: 100-N-79; 1908 N Outfall Structure; 1908-N Spillway; 100-N-77:1 Flume

Reclassification: Interim Closed Out (2/12/2014)

Type: Outfall

Start Date:

Status: Inactive

End Date:

Description: The waste site has been remediated and Interim Closed Out. It consisted of a reinforced concrete spillway (also referred to as an emergency outfall). The spillway extended from the former 1908-N outfall under a service road, dropping approximately 14.6 meters (48 ft) before discharging at the river shore approximately 112 meters (367 ft) from the outfall. The portion of the spillway that passed below the service road was a four-sided closed concrete plume. Below the service road, the spillway was a 3.7 meters (12 ft) wide concrete flume with 0.3 meters (1 ft) thick walls and floor and wall height that varied from 1.5 meters (5 ft) to 2.1 meters (7 ft).

Location: The site was located west of the 109-N Building and the 1300-N Emergency Dump Basin, and south of the 1301-N Emergency Dump tank, on a steep bank which led to the river.

Related Sites/Structures: The site is associated with 100-N-77 (100-N River Effluent Pipeline), 100-N-57 (Emergency Dump Tank) and the 1908-N Outfall Structure.

Process Description: The spillway was an emergency discharge point for the 1908-N Outfall structure. It was planned to be used only if the 100-N-77 river effluent pipelines were blocked, damaged, or undergoing maintenance. There is no corroborated physical or historical evidence that the spillway was ever used. The spillway served as an alternate discharge point for the 1908-N outfall, receiving raw river water used to cool the secondary coolant loop for the 105-N Reactor.

Waste Type: Construction Debris

Waste Description: There is anecdotal evidence that the spillway was never intended or expected to be used, as it was never permitted. An unknown level of radioactive contamination exists within the structure because the discharge lines were associated with the reactor's secondary steam system.

Closure Info: Interim (2/12/2013): The upper portion of the 100-N-79 spillway was removed during remediation of the 100-N-57 (Emergency Dump Tank) waste site in 2011. The 1908-N Outfall structure was removed in 2012. Remediation of the remaining portion of the spillway was

initiated on March 4, 2013, and was completed on August 29, 2013. Approximately 1,265 bulk cubic meters of material was removed and direct loaded for disposal at the Environmental Restoration Disposal Facility (ERDF). The portion of the concrete spillway remaining below the OHWM was left in place and a sample of the concrete exposed just above the water at the OHWM was collected for informational purposes. No radiological contamination was reported.

Because the 100-N-79 spillway extended into the Columbia River, the ordinary high water mark (OHWM), at an elevation of 120.4 meters (395 ft) above mean sea level (amsl), was used to determine the lower extent of remediation of the waste site.

Following remediation, the radiological postings were removed - per WCH Internal Memos (CCN 176583 and 175935).

Code:	100-N-104	Classification:	Accepted
Names:	100-N-104; Raw Water Overflow Spillway	Reclassification	Interim Closed Out (9/9/2014)
Type:	Outfall	Start Date:	
Status:	Inactive	End Date:	
Description:	The site has been remediated and Interim Closed Out. It was a raw water overflow spillway made up of a concrete chute and stilling basin. A 36 inch raw water return line (100-N-61) emptied into this site. Twenty feet of the concrete spillway was removed when the south river road was constructed.		
Location:	The 100-N-104 spillway was located 119 meters (390 ft) downstream of the Hanford Generating Plant River Pumphouse (181-NE) at coordinates E570939.9 N149367.9.		
Related Sites/ Structures:	1900-N Water Supply Tanks and 182-N High-Lift Pump House.		
Process Description:	<p>The system was designed to collect in a 91 cm (36 in) line (100-N-61:1), the overflow and drainage from four water storage tanks and dispose the waste water to the river. The four, above ground water storage tanks (1900-N) were an stored tank heat removal process water. An emergency raw water storage tank, a filtered water storage tank and a demineralized water storage tank were also part of this system. The system is comprised of an overflow and a drain piping from each of the water storage tanks, and a 30.5 cm (12 in) raw water return line (100-N-61) from the 182-N Building. The effluent from the 91 cm (36 in) line spills into a sloped concrete chute, into the stilling basin and thence to the river (HW-69000 Volume II, Page 8.2.6-2). The afterheat removal system storage tank was designed as a reservoir of demineralized water for makeup to the secondary loop for normal operation and for flooding of the secondary loop in the water-to-water operation. It also served as storage for water spilled for level control of the secondary loop, water not needed in the secondary loop after the water-to-water operation, and condensate returns from various plant heaters (HW-69000 Volume II, Page 3.1.3-2).</p> <p>The emergency raw water storage tank was designed as a reservoir of tempered raw water for reactor emergency once-through cooling (HW-69000 Volume II, Page 1.2.3-2). The a filtered water storage tank was designed for storage of filtered water pumped to it from the 183-N Building (HW -69000 Volume II, Page 2.1.5-2). The demineralized water storage tank was designed as a reservoir of effluent water from the demineralizer plant, and as the normal supply to the high and low pressure injection pumps. It was served as an emergency supply to the pumps of the afterheat removal fill system, the fog spray and fire protection pumping systems, the high lift emergency raw water pumping system, and the emergency raw water storage tank (HW-69000 Volume II, Page 3.1.1-2).</p>		

Closure Info: Interim (9/9/2014): Remedial action at the 100-N-104 waste site was conducted from March 10 through 12, 2014. The waste from the site included residual concrete, soil, rebar, and steel plating. Approximately 445 bank cubic meters (BCM) (582 bank cubic yards [BCY]) of waste was removed and directly loaded for disposal at the Environmental Restoration Disposal Facility. Of the waste volume, approximately 100 BCM (131 BCY) was nonsoil (e.g., concrete, rebar, and steel plating). The excavation extended to approximately 2.0 meters (6.5 ft) below ground surface. No anomalies were discovered during remediation.

The lower section of the spillway (downslope from the river road) is below the ordinary high water mark (OHWM). Per agreement with Ecology, the section of the spillway that is below the OHWM was left in place.

Code: 100-N-105	Classification: Not Accepted
Names: 100-N-105; Contaminated Soil beneath 1900-N Supply Tanks; Paint Chips near 1900-N	Reclassification: None
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The site consists of the concrete foundations beneath the former 1900-N water supply tanks (four large steel tanks and silo) and surrounding contaminated soils. Demolition of the above-grade portions of the 1900-N facility occurred in 2005. The soils beneath the tanks were described as having been stained with oil. However, it was paint flakes that fell from the tanks during demolition that are the primary concern at this site. The paint on at least one of the tanks had elevated lead concentrations.

Location: The tanks were located on the south side of 182-N High-Life Pump House.

Code: 100-N-106	Classification: Accepted
Names: 100-N-106; Shallow Petroleum-Only Releases at 100-N; SPOR Releases	Reclassification: None
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The site consists of multiple SPOR [Shallow Petroleum-Only Releases] areas of subsurface oil contaminated soil in the 100-N Area. 100-N-106 addresses unanticipated discoveries of shallow petroleum contamination at 100-N. The initial list of identified SPOR areas are associated with remedial activities at waste sites includes 100-N-25, 100-N-61:1, 100-N-61:2, 100-N-62, 100-N-63:2, 100-N-64:1, 100-N-64:2, 116-N-2, 120-N-3, UPR-100-N-14. Soil stains and/or elevated TPH or petroleum-derived Poly-aromatic Hydrocarbons (PAH) concentrations were identified during remedial activities, but petroleum contamination was not listed as a constituent of concern (COC) or a constituent of potential concern (COPC) for these waste sites. It was anticipated that additional discoveries of petroleum contamination could be added to this waste site as remediation projects in the 100-N Area continued.

Location: The waste site (SPOR areas) are at locations multiple throughout the 100-N Area.

Related Sites/Structures: The oil contaminated soil areas are associated with remedial activities at waste sites 100-N-25, 100-N-61:1, 100-N-61:2, 100-N-62, 100-N-63:2, 100-N-64:1, 100-N-64:2, 116-N-2, 120-N-3, 100-N-84:2, UPR-100-N-14 and UPR-100-N-17.

Process Description: Elevated TPH or petroleum-derived PAH concentrations were identified during remedial activities, but petroleum contamination was not listed as a constituent of concern (COC) or a constituent of potential concern (COPC) for these waste sites. The source and occurrence of the releases is unknown.

Code: 100-N-107 **Classification:** Accepted

Names: 100-N-107; Bioventing Well Islands; Soil Contamination Adjacent to Bioventing Wells **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The site is two separate but proximal areas of radiologically contaminated soils adjacent to bioventing wells. One area surrounds Wells 199-N-166, 199-N-167, 199-N-168, and 199-N-169. The second area is located adjacent to Well 199-N-172.

100-N-84:10 (Miscellaneous pipelines associated with the Bioventing wells) became part of 100-N-107 by being reclassified to Consolidated.

Location: This site is located approximately 200 meters north-northeast of the 105-N Reactor Safe Storage Enclosure.

Code: 100-N-108 **Classification:** Discovery

Names: 100-N-108; 100-N Shoreline **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Code: 244-A CT **Classification:** Accepted

Names: 244-A CT; 244-A DCRT; 244-A Receiver Tank; 244-A RT; 244-A-TK/SMP; 244-A Catch Tank **Reclassification:** None

Type: Catch Tank **Start Date:** 1/1/1975

Status: Inactive **End Date:** 1/1/2005

Description: The unit is an underground structure constructed of carbon steel. It sits vertically inside a reinforced concrete, steel-lined vault. Above the tank is the lift station (sitecode 244-A LS).

Location: This site is located west of the 241-AZ Tank Farm and south of the 241-C Tank Farm. It is inside the 244-A Lift Station fence.

Related Sites/Structures: Structures associated with the 241-A CT are the 244-A Lift Station, 241-ER-153 diversion box and the 241-A valve pits. See Sitecode 244-A LS.

Process Description: The 244-A RT is located at the 244-A Lift Station (244-A LS) and provided lag storage for waste transferred from the 241-ER-153 diversion box to the 241-A valve pits.

Waste Type: Chemicals

Waste Description: The 244-A Catch Tank/Double-Containment Receiver Tank is located at the 244-A lift station and provides lag storage for waste transferred from the 241-ER-153 diversion box to the 241-A

valve pits. Waste routed through the lift station includes 200 West Area waste; 241-B, 241-BX, 241-BY, and 241-C Single-Shell Tank waste; and waste transferred from B Plant. Waste transferred out of the 244-A lift station can be routed to any of the 200 East Area Double-Shell Tanks. This tank did not receive saltwell pumping like other DCRT's.

Code: 244-A LS	Classification: Accepted
Names: 244-A LS; 244-AR Lift Station; 244-AR LS; SN-232, SN-233 and SN-234; 244-A Lift Station	Reclassification: None
Type: Control Structure	Start Date: 1/1/1975
Status: Inactive	End Date: 1/1/2005

Description: The lift station is surrounded with a chain link fence. The surface is covered with gravel. The lift station consists of an underground concrete structure containing a filter pit, pump pit, and vault in which the catch tank (244-A DCRT) is installed. This site includes the exhaust fan and stack, instrument enclosure, caisson, flush pit, service pit, and vacuum pump pad. The structure is posted with multiple radiological postings, including Radiation Area, Underground Radioactive Material Area, Radioactive Material Area and Contamination Area.

Location: This site is located south of 7th Street, west of the 241-AZ Tank Farm and south of the 241-C Tank Farm.

Related Sites/ Structures: The 244-A LS is associated with the 241-ER-153 diversion box, the 244-A DCRT, lines SN-232, SN-233, SN-234 and the 241-A valve pits. Per drawing H-2-38203, structures related to the 244-A Lift Station also include the exhaust fan and stack, instrument enclosure, caisson, flush pit, service pit, vacuum pump pad and transfer piping. The lift station is also associated with UPR-200-E-70, UPR-200-E-100, UPR-200-E-143, 200-E-144-PL, 200-E-145-PL, 200-E-147-PL and 200-E-167-PL.

Process Description: The 244-A LS provides lag storage for waste transferred from the 241-ER-153 diversion box, via lines SN-232, SN-233 and SN-234. The waste was then sent to the 241-A valve pit.

Waste Type: Process Effluent

Waste Description: The 244-A Double-Containment Receiver Tank is located at the 244-A Lift Station and provides lag storage for waste transferred from the 241-ER-153 diversion box to the 241-A valve pits. Waste routed through the lift station includes 200 West Area waste; 241-B, 241-BX, 241-BY, and 241-C Single-Shell Tank waste; and waste transferred from B Plant. Waste transferred out of the 244-A lift station can be routed to any of the 200 East Area Double-Shell Tanks.

This Site has the Following SubSites:

Code: 244-A LS:1
Names: 244-A LS:1; Lift Station
Code: 244-A LS:2
Names: 244-A LS:2; Transfer Piping

Code: 244-A LS:1	Classification: Accepted
Names: 244-A LS:1; Lift Station	Reclassification: None
Type: Control Structure	Start Date:
Status: Inactive	End Date:

Description: Subsite 1 is the Lift Station that includes the 244-A receiver tank and the pump pit.

The SubSite is Part Of:

Code: 244-A LS

Names: 244-A LS; 244-AR Lift Station; 244-AR LS; SN-232, SN-233 and SN-234; 244-A Lift Station

Code: 244-A LS:2

Classification: Accepted

Names: 244-A LS:2; Transfer Piping

Reclassification: None

Type: Control Structure

Start Date:

Status: Inactive

End Date:

Description: Subsite 2 is the transfer piping between the 241-ER-153 Diversion Box and the 244-A Lift Station (lines SN-232, SN-233 and SN-234). The total length of the pipeline segments is 55 meters, calculated with the Geospatial data in ArcGIS.

The SubSite is Part Of:

Code: 244-A LS

Names: 244-A LS; 244-AR Lift Station; 244-AR LS; SN-232, SN-233 and SN-234; 244-A Lift Station

Code: 241-AR-151

Classification: Accepted

Names: 241-AR-151; 241-AR-151 Diversion Box

Reclassification: None

Type: Diversion Box

Start Date: 1/1/1976

Status: Inactive

End Date: 6/1/2005

Description: The 241-AR-151 diversion box is a reinforced concrete structure. The walls and floor of the diversion box are lined with 11-gage stainless steel. The box drains to the 244-AR Vault and is equipped with a leak detector that alarms inside 242-A evaporator building. The structure is covered with a weather protective cover.

Location: The diversion box is located north of the 244-AR Vault facility, east of 291-AR. It is on the west side of Buffalo Ave.

Related Sites/ Structures: This unit is associated with 241-AY and -AZ tank farms and the 244-AR Vault. A pipeline associated with this diversion box is 200-E-206-PL. The drain line is V717.

Process Description: The unit is utilized for the transfer of liquid mixed waste generated at PUREX to the AY and AZ Tank Farms. The 241-AR-151 was one of two diversion boxes used to transfer high level waste generated at PUREX to aging waste tanks in the 241-AY and 241-AZ Tank Farms. The diversion box is constructed of steel reinforced concrete. The walls and floor of the diversion box are lined with 11-gage stainless steel. The diversion box drains to the 244-AR Vault and is equipped with a leak detector that alarms in the 242-A Evaporator building. The diversion box was constructed in 1976 and was in service through approximately mid-2003, when 6 connecting pipelines were flushed, isolated and process blanks installed. The 241-AR-151 Diversion Box was weather sealed in September 2003. The diversion box was officially removed from service in June 2005 per Milestone Report M-48-07.

Waste Type: Process Effluent

Waste Description: The diversion box is used to transfer waste from the 241-AY and 241-AZ Tank Farms. This waste includes aging waste, high-level B Plant waste, B Plant cesium feed waste, non-complexed, concentrated complexed and cesium and strontium recovery waste.

Code: 244-AR VAULT	Classification: Accepted
Names: 244-AR VAULT; 244-AR Vault	Reclassification: None
Type: Receiving Vault	Start Date: 1/1/1966
Status: Inactive	End Date: 1/1/1978

Description: The 244-AR Vault facilities include a canyon building, a service building, two (filter building) concrete housings, and a change room. The canyon building is a reinforced concrete, two level, multi-cell structure. The lower level process cells contain four tanks, a failed equipment cell and associated piping and equipment. The upper portion of the vault and the lower cells are separated by cover blocks with recessed lifting bails. The facility is posted with multiple radiological postings on the exterior of the building doors. They include Internally Contaminated Systems, Radiation Area, Underground Radioactive Material Area, Radiological Buffer Area, Radioactive Material Area, Contamination Area, High Contamination Area, and Fixed Contamination Area.

Location: The building is located west of the 241-A Tank Farm, at the corner of 4th Street and Buffalo Ave.

Related Sites/ Structures: The facility includes a crane, control room, two ventilation systems, a sluicing system (no longer in use), and a solution piping system.

Process Description: The unit received waste sluiced from the 241-A and -AX Tank Farms. Processing took place, then the waste was shipped to B Plant. The facility was the focal point for reprocessing and routing of PUREX-generated waste between tank farms and B Plant (via 244-CR vault) in the late 1960's and between the tank farms and the Waste Encapsulation Storage Facility in the late 1970's. In 1984, a decision was made to upgrade the 244-AR vault for use as a waste transfer facility. The extensive upgrading effort provided improved features for the safe and efficient transferring of PUREX-generated waste between the tank farms and B Plant. The waste consisted of cladding removal waste enroute to B Plant and transuranic waste from B Plant/Waste Encapsulation Storage Facility to the tank farms. (reference ARH-374)

Waste Type: Storage Tank

Waste Description: The 244-AR Vault was originally used to process radioactive waste that was being removed ("sluiced") from storage tanks. The waste was eventually transferred to the B Plant for removal of cesium and strontium. All of the liquid waste in the facility was transferred to 241-AY-102 in 2003. The vault was interim stabilized in 2003. There is an estimated 660 gallons of sludge and up to 194 gallons of liquid in the tank (RPP-12051, 244-AR Vault Interim Stabilization Completion Report, Page 3-2) Tank-001 cell 1. The tank is thought to be dry, but there may be up to 2 gallons of waste in the sump (RPP-12051). In Tank-002 Cell 2, there is an estimated 2080 gallons of sludge and up to 194 gallons of liquid in the tank (RPP-12051 page 3-3). The cell is thought to be dry, but there may be up to 2 gallons of waste in the sump (RPP-12051).

Code: 241-AX-151	Classification: Accepted
Names: 241-AX-151; 241-AX-151 Diversion Box; 241-AX-151 Diverter Station	Reclassification: None
Type: Diversion Box	Start Date: 1/1/1962
Status: Inactive	End Date: 1/1/1985

Description: The unit is an underground reinforced concrete structure. There are four diverter tanks (tanks 241-AX-151-D, E, F and G; see "Subsite" sections) in individual cells and a catch tank (241-AX-151CT) in a pump pit. Each cell has a stainless steel liner on the floor that extends

approximately one foot (.31 meters) up the wall. The cells and pump pit drain into the catch tank below. The structure is surrounded with posts and chain. It is posted with radiological and IMUST signs.

Location: The 241-AX-151 Diversion Box is located near the corner of 4th Street and Buffalo Ave., south of the 244-AR Vault facility.

Related Sites/ Structures: The unit routed waste from the 202-A Plant to the 244-AR Vault and to the 241-AY and 241-AZ Tank Farms. Pipelines associated with this diversion box include 200-E-143-PL, 200-E-144-PL, 200-E-146-PL, 200-E-227-PL.

Waste Type: Process Effluent

Waste Description: The unit received wastes from 202-A PUREX Plant. Waste transferred also includes PUREX acid waste and B Plant neutralized high-level waste. On August 2, 2006 a video inspection was performed. Based on the zip cord readings made in August 2, 2006, the liquid volume in the tank is estimated to be approximately 2838 gallons. This includes approximately 46 gallons in the sump. (per RPP-RPT-31102)

Waste Type: Equipment

Waste Description: It is estimated that approximately 50 pounds (23 kilograms) of lead is stored in each diversion box.

Code: 241-AZ-301

Classification: Accepted

Names: 241-AZ-301; Condensate Receiver Tank

Reclassification: None

Type: Receiver Tank

Start Date: 1/1/2005

Status: Active

End Date:

Description: The site is a below ground, carbon steel tank with an above ground domed access structure. It is posted with Radiation Area and Contamination Area signs.

Location: The site is located west of the 241-AZ Tank Farm fence, adjacent to the 241-AZ-702 Ventilation Building.

Related Sites/ Structures: The site is associated with the 241-AZ-702 Aging Waste ventilation system.

Process Description: The 241-AZ-301 receiver vessel was built to replace the 241-AZ-151 catch tank. The vessel receives condensate from the 241-AZ-702 Aging Waste ventilation system, which is the primary filter building for the 241-AY and 241-AZ tank farms.

Waste Type: Sludge

Waste Description: In 2013 a waste characterization determined the waste was non dangerous.

Code: 201-C

Classification: Accepted

Names: 201-C; 201-C Process Building

Reclassification: None

Type: Process Unit/Plant

Start Date: 1/1/1949

Status: Inactive

End Date: 1/1/1967

Description: Demolition activities removed the aboveground features of 201-C from 1983 through 1986. The below grade features and remains of the 201-C facility was entombed in concrete and has

been covered with ash material. It is posted with Underground Radioactive Material signs. The current configuration of the building includes the lower 3 meters (10 feet) of the building filled with grout and partially covered with 3 meters (10 feet) of ash. The 201-C Process Building consisted of three integrated cells, seven process galleries, an exhaust system, a hot shop, and an air treatment room. Two additional cells were connected to the east side of the building. The process cells are primarily constructed of reinforced concrete.

Location: The building is located east of the 209-E Critical Mass Laboratory. It is currently located inside an area that has been surface stabilized with flyash and is posted with Underground Radioactive Material signs (see sitecode 200-E-41).

Related Sites/ Structures: The structures associated with this building include process cells, equipment, piping, and ancillary structures. It is associated with the 216-C-1, 216-C-3, 216-C-4 and 216-C-5 cribs, 216-C-9 excavation and the 200-E-41 stabilized area.

Process Description: The 201-C Processing Building was the main processing facility for the Hot Semiworks Area. It was originally built in 1949 as a pilot plant for the Reduction Oxidation (REDOX) process. In 1954, the building was used as a pilot plant for the Plutonium Uranium Extraction (PUREX) process. The plant was converted to recover strontium from process wastes in 1961.

Waste Type: Chemicals

Waste Description: There is residual chemical and radiological contamination present in the structure. According to DOE/RL-92-18 Revision 0, the radiological inventory is estimated to include: 68.3 curies of plutonium, 9,000 curies of strontium, and 0.2 curies of americium. Chemical wastes in the structure include solvents, acids and other process chemicals.

Waste Type: Equipment

Waste Description: The building was entombed in concrete in 1986. The building remnants contain radioactive and chemically contaminated structures, piping, and equipment. There is also a large quantity of lead shielding associated with the hot cells. All shielding was left in place. The entombed building inventory was estimated in 1989 to contain 4.9 curies of plutonium 239, 3.7 curies of plutonium 238, 0.2 curies of Americium 241, 9000 curies of strontium 90 and 2.5 tons of lead.

Code: 291-C	Classification: Accepted
Names: 291-C; 291-C Fan and Filter Building; 291-C Filter/Fan House; 201-C Air Tunnel	Reclassification: None
Type: Process Unit/Plant	Start Date: 1/1/1949
Status: Inactive	End Date: 1/1/1987

Description: This building was demolished prior to the 291-C-1 Stack demolition in 1988. The unit consisted of an air tunnel from the 201-C Cells, fiber glass filters, high-efficiency particulate air (HEPA) filters, and the Fan House. The Fan House and HEPA Filter 2 were located above ground. HEPA Filter 1 and the concrete air tunnel were constructed below grade. The air tunnel connected the 201-C Building with the 291-C-1 Stack. The first 31 meters (100 feet) of the tunnel are 6 meters (20 feet) below grade. The second 31 meters (100 feet) of the tunnel are 1.5 meters (5 feet) below grade. There were forty removable aluminum cartridge glass fiber filters and an array of HEPA filters. The fan house building was a wood frame structure on a concrete slab. It contained two electric fans and one steam turbine fan.

Location: The 291-C Fan House building was located east of the 291-C Stack base, south of 7th Street.

Related Sites/ Structures: The building was associated with the 291-C Exhaust Stack. Also see pipeline sitecodes 200-E-251-PL and 200-E-252-PL that drained these structures to the 216-C-2 reverse well.

Process Description: The structure provided exhaust air ventilation for the operating cells and process vessel vents of the 201-C Facility.

Waste Type: Equipment

Waste Description:

Waste Type: Equipment

Waste Description:

Code: 200-E-27 **Classification:** Accepted

Names: 200-E-27; 242-AC; 242AC Pipefitter Shop Lead Cutting Area **Reclassification:** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The 242AC Pipefitter Shop had a lead cutting area and an area used to store lead sheets and pipe for use on various construction projects. The area is no longer used for lead cutting, but is used by the shop as an equipment and material storage area. The lead cutting area has sandy soil and contains pieces of lead. The area surrounding the lead cutting area is covered with crushed rock. Tank farm equipment, lead material covers, and a heavy duty table are currently stored in the lead cutting area. The entire 242AC Pipefitter Shop area is surrounded by a chain-link fence.

Location: The site is located at the corner of 4th Street and Buffalo Avenue. The Lead Cutting Area is on the east side of the 242 AC pipefitter shop.

Release Description: Lead was cut at the facility using piano wire, a cutting torch, and a skil saw with the blade turned backwards. The skil saw created the small lead particles.

Related Sites/Structures: The site is associated with the 242-AC Pipefitter Shop.

Waste Type: Soil

Waste Description: Soil at the site is contaminated with lead.

Code: 200-E-30 **Classification:** Accepted

Names: 200-E-30; 221-B Stack Sand Filter; 291-B Sand Filter **Reclassification:** None

Type: Sand Filter **Start Date:** 1/1/1948

Status: Inactive **End Date:** 1/1/1997

Description: It consists of a reinforced concrete structure filled with sand and gravel and a roof of pre cast concrete slabs supported by the walls and concrete beams. The unit is partially below grade. The unit measures 33.5 meters (110 feet) by 15.25 meters (50 feet) by 4.8 meters (16 feet) high. It is posted with appropriate radiological signs.

Location: The sand filter is located southeast of the 221-B canyon building, adjacent to the 291-B Stack.

Related Sites/ Structures: The sand filter is associated with the 291-B Stack and a french drain located east of the sand filter (200-E-55). The pipeline from the sand filter to the french drain is sitecode 200-E-214-PL.

Process Description: The sand filter was used to filter the 291-B stack air. The sand filter is a partially buried concrete structure measuring 33.5 X 15.25 X 4.8 meters (110 X 50 X 16 feet). The 1987 Hanford Site Waste Management Units Report site description states "This site consists of sixty french drains, each measuring 6 inches in diameter, 3 foot 5 inches long, filled with coarse gravel, placed 13 feet 7 inches below the top of the structure. There is a concrete structure 100 X 48 X 14 feet 7 inches high which contains concrete blocks arranged in rows to form lateral ducts, with drains spaced throughout, every 10 feet lengthwise - 8 feet widthwise, all covered with 9 feet of sand and gravel, then covered with concrete slabs. There is a 1 foot layer of gravel on the entire bottom, with a layer of sisalkraft paper underneath which surrounds the drains throughout the structure." The 200 Area Waste Site Handbook (RHO-CD-673) describes the facility (sand filter) as "Sixty, 6 inch diameter vitrified soil pipes inside an area measuring 100 X 48 feet. The 291-B sand filter inlet trenches drain to a french drain pipe extending into the ground at the north corner of the sand filter. Any moisture condensed from the canyon air on the filter bed will escape to the ground at this location. The amount and activity are both very low."

Waste Type: Soil

Waste Description: The B Plant canyon ventilation passed through the sand filter from 1948-1952, during the bismuth phosphate fuel processing activities. It was active again periodically through the years as an emergency back up for the HEPA Filters. It is currently in a standby mode. In 1994, a the radionuclide inventory was estimated to be 3000 ci of Strontium-90 and 2000 ci of Cesium-137.

Code: 200-E-41 **Classification:** Accepted

Names: 200-E-41; Stabilized Hot Semiworks Area; Strontium Semi-Works Stabilized Area; UN-216-E-38 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1949

Status: Inactive **End Date:** 1/1/1992

Description: This site is a large area posted with chain and Underground Radioactive Material signs. An area within the posted boundaries has been covered with fly ash. The ash-covered area encompasses the decommissioned 201-C Building, the 291-C Stack Burial Trench and the 216-C-2 French Drain. Waste sites and facilities buried beneath the ash are not individually distinguishable.

Location: The site is located in 200 East Area, south of 7th Street. It is east of the 209-E security fence.

Release Description: Two waste line leaks have been documented in WIDS files 200-E-56 and 200-E-57.

Related Sites/ Structures: The area is associated with the 201-C building, 241-CX-70, 241-CX-71, 241-CX-72, 241-C-154, 216-C-2 and WIDS site codes 200-E-56 and 200-E-57.

Process Description: The 201-C Processing Building was the main processing facility for the Hot Semiworks Area. It was originally built in 1949 as a pilot plant for the Reduction Oxidation (REDOX) process. In 1954, the building was used as a pilot plant for the Plutonium Uranium Extraction (PUREX) process. The plant was converted to recover strontium from process wastes in 1961.

Waste Type: Soil

Waste Description: The area covered with clean backfill contained residual contamination from the operation of the Hot Semiworks facility.

Code: 200-E-44 **Classification:** Accepted

Names: 200-E-44; PUREX Railroad Cut **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The Railroad Cut is approximately 240 meters (800 feet) of track extending from the tunnel door northward to the isolation area gate. Two large berms of soil were placed along both sides of the track within the fenced portion of the spur to provide radiation shielding. A turnout siding (Donkey Track) is also located within the fenced Railroad Cut. The railroad cut is posted as a Contamination Area.

Location: The PUREX Railroad Cut is located on the northeast corner of the 202-A building. A railroad spur extends from the PUREX main lead to the tunnel entrance door.

Related Sites/ Structures: The site is associated with UPR-200-E-10, UPR-200-E-11, UPR-200-E-12, UPR-200-E-20 and UPR-200-E-33.

Process Description: The railroad cut provides access to the PUREX tunnel and also to the burial tunnels south of the PUREX facility (218-E-14 and 218-E-15).

Waste Type: Soil

Waste Description: The contamination in the soil and gravel in the railroad cut is from many years of contaminated equipment and waste being transported on rail cars into and out of the PUREX facility.

Code: 200-E-102 **Classification:** Accepted

Names: 200-E-102; Contaminated Soil Trench **Reclassification:** None

Type: Trench **Start Date:** 1/1/1958

Status: Inactive **End Date:** 1/1/1958

Description: The trench is inside the surface stabilized Underground Radioactive Material area south of PUREX that is known as WIDS Sitecode 200-E-103. The trench is not separately marked or posted.

Location: The site is located 20.7 meters (68 feet) south of the south boundary of 216-A-4 Crib. It is currently covered with clean gravel and cannot be visually identified.

Related Sites/ Structures: The site is related to UPR-200-E-15, 216-A-4 Crib, 291-A Turbine House and 200-E-103.

Process Description: The trench was used to bury contaminated soil from an unplanned release (WIDS Site UPR-200-E-15). When the 216-A-4 Crib plugged in 1958, it caused the ground between the 216-A-4 crib and the 291-A Turbine House to flood. The contaminated soil was scraped up and placed into a slit trench near the south end of the crib. The trench was covered with 0.3 meters (one foot) of clean dirt.

Waste Type: Soil

Waste Description: The waste is contaminated soil caused by the plugging of the 216-A-4 Crib. It resulted in a flood of contaminated water in the 291-A Turbine House floor drains. The turbine house floor

was contaminated to 20 rads/hour at 25.4 centimeters (10 inches). An area of ground and blacktop outside the turbine house was contaminated up to 8 rads/hour. The 216-A-4 Crib received waste solution from the 216-A-2 Waste Collection Tank, the U-3 and U-4 Laboratory Waste Receiver Tanks (located in the acid storage vault), the dissolver off-gas scrubbers and the 241-A-151 Diversion Box Catch Tank. 216-A-4 Crib was intended to receive a maximum of [284 liters (75 gallons) per minute] low level radioactive liquid waste.

Code: 200-E-111-PL **Classification:** Accepted

Names: 200-E-111-PL; 3-38 Encasement; Encased Pipeline from 241-ER-151 Diversion Box and 221-B to 241-C Tank Farm and 244-AR Vault; Lines V108/V837/8618/8653/8901PAS, 809, 818, V836 and V834 **Reclassification:** None

Type: Encased Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: The site is an underground piping encasement that contains three 7.5 centimeter (3 inch) diameter stainless steel waste transfer pipelines connecting 241-ER-151 and B Plant to 241-C and 244-AR Vault. Lines V108, 8618, 8653 run from the 241-ER-151 diversion box through a "Y," which branches to the 241-C Tank Farm and the 244-AR Vault. The section from the "Y" junction to 241-C farm contain lines V108, 8618 and 8653. The section from the "Y" junction to the 244-AR Vault contains two 7.5 centimeter (3 inch) pipelines numbered 809 and 818. There is a posted Contamination Area on top of the line at the Y Junction where the line branches to the 241-C Tank Farm and the 244-AR Vault.

Line V837 extends south from 221-B to join the encasement. Line V837 ties into line V108 inside the encasement.

Line 8653 was replaced with V836. Line 8653 line separated when the cone expansion was added to 200-E-111-PL. Line V836 extended from the 8653 stub to 241-ER-151. V836 is a direct buried (M9) stainless steel line that runs parallel to (but outside) the encased lines.

Line V834 (from B-Plant) connected within the cone expansion to the remaining line 8653 to the Y division. (See drawings H-2-34179 and H-2-43043).

The entire length of the pipeline is marked with steel fence posts and posted as an Underground Radioactive Materials area. The ground surface above the pipeline is bare in spots, other sections are vegetated with crested wheatgrass, tumbleweeds, and native grass species.

Location: The encased pipeline runs eastward from the 241-ER-151 Diversion Box, south of 7th Street, and branches off in two directions (forming a Y) at a point southeast of the 216-C-10 Crib. From the Y, it branches to the 241-CR-151 Diversion Box inside 241-C Tank Farm and to the 244-AR Vault.

Related Sites/ Structures: The waste transfer encasement is connected to the 241-ER-151 Diversion Box, 241-ER-152 Diversion Box, 241-CR-151, 241-C Tank Farm and the 244-AR Vault.

Process Description: The underground, encased pipeline was used to transfer waste from 241-ER-151 and B Plant to the 241-C Tank Farm and the 244-AR Vault.

Line V837 is a single direct buried line that terminates at the 200-E-111 PL encasement. Line V837 ties into line V108 in the encasement.

Waste Type: Process Effluent

Waste Description: The pipeline transported liquid effluent from the 241-ER-151 Diversion Box to the tank farms. Some adjacent soil has been contaminated from pipeline leaks.

Code: 200-E-112-PL **Classification:** Accepted

Names: 200-E-112-PL; 24-Inch VP Line; 2904-E-1; B Plant Process Sewer; Pipeline from B Plant to 207-B Retention Basin **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The site is the 61 centimeter (24 inch) diameter, underground process sewer from B-Plant to the 207-B Retention Basin. The pipeline is also known as 2904-E-1. The pipelines are marked above ground with steel posts and marked as "Underground Radioactive Material/Pipeline". Access manholes are located at intervals along the length of pipelines. Vegetation over the pipelines consists of grass and tumbleweeds, with several areas of bare soil.

Location: The waste site is an underground vitrified clay pipelines connect B Plant and the 207-B Retention Basin. It extends eastward from the southeast corner of B-Plant, then turns northward, connecting to the west side of the 207-B Retention Basin.

Release Description: UPR-200-E-32 is associated with this pipeline.

Related Sites/ Structures: The process sewers are associated with 221-B (B Plant) and the 207-B Retention Basin.

Process Description: B-Plant routinely discharged process effluent, containing small amounts of radioactivity, to the 207-B Retention Basin via an underground process sewer pipeline. The 2904-E-1 sewer line extends eastward from the south side of 221-B and turns north to connect to the west side of the 207-B Retention Basin. On several occasions large, unplanned amounts of radioactive material were released to the underground sewer lines. The process sewers are 0.6 meters (24 inches) in diameter clay pipelines that include a cast iron pipe from the 221-B building to the first manhole of the process sewer. The remainder of the sewer pipelines are constructed of vitrified pipe.

Waste Type: Process Effluent

Waste Description: The process sewer pipelines transferred liquid process effluent and cooling water to the retention basin and the 216-B-2 ditches. The radioactivity levels were normally low and the water was discharged from the retention basin to ditches that connected to the 216-B-3 Pond. However, in 1963 and 1970, Unplanned Releases UPR-200-E-32 and UPR-200-E-138 released significant amounts of cerium-144 and strontium-90 to the process sewer pipelines.

This Site has the Following SubSites:

Code: 200-E-112-PL:1

Names: 200-E-112-PL:1; North/South 24-Inch VCP Pipeline to 207-B

Code: 200-E-112-PL:2

Names: 200-E-112-PL:2; East/West 24-Inch Cast Iron Pipeline from B Plant Facilities Connecting to the North/South 24-Inch VCP Pipeline

Code: 200-E-112-PL:3

Names: 200-E-112-PL:3; 10-Inch Cast Iron Pipeline from 224-B Connecting to the East/West 24-Inch Cast Iron Pipeline

Code: 200-E-112-PL:4
Names: 200-E-112-PL:4; 2-Inch Cast Iron Pipe from 212-B to East/West 24-Inch Cast Iron Pipeline

Code: 200-E-112-PL:1 **Classification:** Accepted
Names: 200-E-112-PL:1; North/South 24-Inch VCP Pipeline to 207-B **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

The SubSite is Part Of:

Code: 200-E-112-PL
Names: 200-E-112-PL; 24-Inch VP Line; 2904-E-1; B Plant Process Sewer; Pipeline from B Plant to 207-B Retention Basin

Code: 200-E-112-PL:2 **Classification:** Accepted
Names: 200-E-112-PL:2; East/West 24-Inch Cast Iron Pipeline from B Plant Facilities Connecting to the North/South 24-Inch VCP Pipeline **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

The SubSite is Part Of:

Code: 200-E-112-PL
Names: 200-E-112-PL; 24-Inch VP Line; 2904-E-1; B Plant Process Sewer; Pipeline from B Plant to 207-B Retention Basin

Code: 200-E-112-PL:3 **Classification:** Accepted
Names: 200-E-112-PL:3; 10-Inch Cast Iron Pipeline from 224-B Connecting to the East/West 24-Inch Cast Iron Pipeline **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: A 10 inch pipeline exits the south side of 224-B to connect to the B Plant Process Sewer. A 4 inch line exits the north side of 224-B and also connects to the process sewer.

The SubSite is Part Of:

Code: 200-E-112-PL
Names: 200-E-112-PL; 24-Inch VP Line; 2904-E-1; B Plant Process Sewer; Pipeline from B Plant to 207-B Retention Basin

Code: 200-E-112-PL:4 **Classification:** Accepted
Names: 200-E-112-PL:4; 2-Inch Cast Iron Pipe from 212-B to East/West 24-Inch Cast Iron Pipeline **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**

Status: Inactive**End Date:****The SubSite is Part Of:****Code:** 200-E-112-PL**Names:** 200-E-112-PL; 24-Inch VP Line; 2904-E-1; B Plant Process Sewer; Pipeline from B Plant to 207-B Retention Basin**Code:** 200-E-113-PL**Classification:** Accepted**Names:** 200-E-113-PL; 216-A-42C Valve Box; Line 8824; Pipeline from PUREX to 216-A-6 and 216-A-30 Crib**Reclassification:** None**Type:** Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** The site is an underground 41 centimeter (16 inch) diameter carbon steel pipeline that extends from the PUREX Plant to a distribution box located on the west side of the 216-A-6 Crib and continues eastward to the 216-A-30 Crib. The pipeline is marked with steel fence posts, posted as "Underground Radioactive Material" (URM) and "Pipeline" over its entire length. The 216-A-42C Valve Box is located on the pipeline, inside a domed cover. It is surrounded by a broken, wood fence. A small area just west of the 216-A-42C Valve Box has been stabilized with cobbles and separately posted as URM. Most of the pipeline is free of vegetation except for tumbleweeds near the 216-A-30 Crib.**Location:** The site extends in an easterly direction from the southeast end of the PUREX plant to the 216-A-6 and 216-A-30 Crib.**Related Sites/ Structures:** The pipeline is associated with the PUREX facility, the 216-A-6 Crib, the 216-A-42 Retention Basin, 220A Sample Pit, UPR-200-E-19 and the 216-A-42C Valve Box.**Process Description:** The pipeline transported steam condensate waste from the PUREX facility to the 216-A-30 Crib via Distribution Box 1. The effluent from this line had the capability of being sent to the 216-A-6 Crib or the 216-A-30 Crib. From 1961 to 1966 the 216-A-6 and 216-A-30 Crib operated in parallel. After the 216-A-6 Crib was abandoned in 1970, all the effluent in this pipeline was diverted to the 216-A-30 Crib. The distribution box was filled with concrete in 1995.

The effluent was monitored for radionuclides with an in-line monitoring system. If concentrations exceeded the discharge limits, an alarm was sounded in the dispatcher's office, a verification sample was collected, and the stream automatically diverted to the 216-A-42 Retention Basin.

Waste Type: Process Effluent**Waste Description:** The waste is the pipeline and adjacent soil contaminated from pipeline leaks.**Code:** 200-E-116-PL**Classification:** Accepted**Names:** 200-E-116-PL; Direct Buried Pipelines V111/V210/V130, 8902; Pipelines from 241-B-154 Diversion Box to 241-C-151 and 241-C-152 Diversion Boxes**Reclassification:** None**Type:** Direct Buried Tank Farm Pipeline**Start Date:**

Status: Inactive

End Date:

Description: 200-E-116-PL waste site consists of two inactive, parallel direct buried lines (V130 and 8902) that run eastward from the 241-B-154 Diversion Box to the 241-C-151 and 241-C-152 Diversion Boxes in the 241-C Tank Farm (drawing H-2-432). In 1962, Line V212 plugged 16 feet from where it exited the 241-B-154 Diversion Box. It was cut and capped. Line 8902 was rerouted and attached to where V212 had been cut. the site includes a segment of line 8902 that exits the 200-E-198-PL and continues to 241-C tank farm (H-2-939). The waste site also includes a drain line that connects to the 241-B-302 Diversion Box.

Vegetation over the pipeline has been crushed due to vehicle traffic. An area located just north of the 241-B-154 Diversion Box was posted as a High Contamination Area in September 2000, but was covered with a bio-barrier and gravel in February 2001. It is now a rectangular posted URM area over a portion of the pipeline. Another area of contamination was found on this pipeline in June 2001. This area was covered with gravel and posted as a URM in August 2001.

Location: The site is located north of and runs parallel to 7th Street, between B Plant and the 241-C Tank Farm in 200 East Area.

Release Description: The Dyncorp Integrated Soil, Vegetation and Animal Control group submitted a posted High Contamination Area site to WIDS as a Discovery Site. They have determined that the area was posted due to growing, contaminated vegetation on the underground pipeline. The contaminated rabbitbrush was surrounded with High Contamination postings. In September 2000, contamination levels inside the posted area ranged from 1200 to 50,000 counts per minute. This area was later covered with a biobarrier and gravel. In June 2001, another area of growing contaminated vegetation was found adjacent to the area recently stabilized. Contamination levels on the vegetation ranged from 1000 to 50,000 counts per minute.

Related Sites/ Structures: The waste site is associated with 200-E-198-PL, 241-B-154 Diversion Box, 241-B-302 catch tank, 241-C-151 Diversion Box, 241-C-152 Diversion Box, and 241-C Tank Farm. UPR-200-E-82 is also associated with this transfer line.

Process Description: The pipelines transported radioactive mixed waste solutions originating from B Plant to the 241-C Tank Farm. This is a direct buried pipeline, not encased in concrete.

Waste Type: Process Effluent

Waste Description: The pipeline transported process effluent from B Plant. Some adjacent soil has been contaminated from pipeline leaks.

Code: 200-E-118

Classification: Accepted

Names: 200-E-118; 216A271 Shack; 216-B-3 Diverter Station; Diverter Station #3; Main Diverter Structure #3

Reclassification: None

Type: Control Structure

Start Date:

Status: Inactive

End Date: 1/1/1994

Description: The site is a small building (shack) that is labeled Main Diverter Structure #3. Inside the shack, the floor is made of metal grating. Below grade pipes and valves are visible through the grate. A section of the floor is open to the pipes below, and has a radiation rope across the opening. The rope had been posted with an old Surface Contamination Area sign. There had been a posted Contamination Area around a portion of the outside of the shack. In April 2007, the contamination was backfilled with clean dirt and the area posting was changed to Underground Radioactive Material. Just outside of the posted Contamination Area is a valve, labeled 216-B-3-3 Diverter Valve. Two concrete manholes are present, one on each side of the diverter valve.

Location: The site is located east of the 200 East Area fence, near the head end of the 216-B-3-3 Ditch.

Related Sites/ Structures: The site is associated with the underground pipelines to 216-B-3 ponds and 216-A-25 pond (see sitecodes 200-E-126-PL and 200-E-127-PL).

Process Description: Water from B Plant and PUREX could be diverted to the 216-B-3 Pond lobes or to Gable Mountain Pond (216-A-25) via valves in the diverter station. Gable Pond became inactive in 1984 and was backfilled. The 216-B-3-3 Ditch was active until 1994.

Waste Type: Equipment

Waste Description: The site is an abandoned shed posted with Contamination Area signs.

Code: 200-E-126-PL-B **Classification:** Accepted

Names: 200-E-126-PL-B; Segments of 200-E-126-PL Pipeline Located in the Inner Area **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: Due to the restructuring of Operable Units, as described in the Agreement for Central Plateau Cleanup, the original pipeline site has been split into segments. 200-E-126-PL-B is the segments of 200-E-126-PL piping located in the Inner Area. The segments of pipelines associated with 200-E-126-B include a twenty two inch diameter poly pipe extending from 207-B to Diverter Station 2, a twenty one inch diameter vitrified clay pipe extending from Diverter Station 2 to the Head End of 216-B-3 Ditches and a twenty four inch corrugated metal pipe extending from Diverter Station #2 to Diverter Station #3.

Location: The pipeline segments in this waste site are located inside 200 East Area, west of the Inner/Outer Area boundary. The waste site begins at the 207-B retention basin and terminates at the Inner/Outer Area boundary.

Related Sites/ Structures: This portion of pipeline is associated with the 207-B Retention Basin and Diverter Station #2.

Process Description: The pipeline conveyed B Plant effluent to the 216-B-3 Pond and Ditch system. B Plant cooling water effluent was originally routed through the 207-B Retention Basin to the 216-B-2-1, 216-B-2-2 and 216-B-2-3 ditches. In 1987, the 216-B-2-3 ditch was closed and was replaced by this, 22 inch diameter plastic underground pipeline. It extended from the 207-B basin to Diverter Station #2. By 1994, all of the open ditches (216-B-2-1, 216-B-2-2, 216-B-2-3, 216-B-3-1, 216-B-3-2 and 216-B-3-3) had been backfilled and surface stabilized. After 1994, all the effluent was conveyed to the 216-B-3A and 216-B-3C pond lobes only through underground pipelines. In 1995 the ponds were closed. The remaining effluent was transferred the Treated Effluent Disposal Facility (TEDF). Parts of the pipelines east of 200 East Area, that had fed the ponds, were re-used to feed the TEDF disposal basin. The TEDF portion begins at Manhole #8 and extends to Pump Station #3. In the event of a failure at Pump Station #3, the effluent can be routed to 216-B-3C (C lobe). The section that connects the southeast corner of 216-B-3A to the northwest corner of 216-B-3C is constructed of 76 centimeter (30 inch) corrugated metal pipe.

Code: 200-E-127-PL-B **Classification:** Accepted

Names: 200-E-127-PL-B; Segments of Gable Mountain Pond Pipeline Located in the Inner Area **Reclassification:** None

Type: Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** Due to the restructuring of Operable Units, as described in the Agreement for Central Plateau Cleanup, the original pipeline site has been split into segments. 200-E-127-PL-B is the segments of pipeline located in the Inner Area. The majority of this pipeline is 36 inch corrugated metal pipe.

When the 241-AP Tank Farm was constructed, a portion of this pipe was re-routed to the east of the new tank farm. The original pipe that was within the boundary of the 241-AP tank farm property was removed during the tank farm construction.

Location: 200-E-127-PL-B is the segments of pipe located in the Inner Area. It extends from the 241-A-201 Pump Pit, located east of the PUREX facility to the 207-A Retention Basins, located east of Canton Ave., east of the 242-A Evaporator building. A segment of 21 inch corrugated steel pipe extends from 241-A-401 and connected to the 36 inch 200-E-127-PL-B.**Process Description:** The pipeline conveyed PUREX and B Plant effluent to the (216-A-25) Gable Pond or the (216-B-3) B Pond system. A segment of 21 inch corrugated steel pipe extends from 241-A-401 and connected to the 36 inch 200-E-127-PL-B. The effluent stream was directed to the preferred pond via Diverter Station #3. The pipeline south of Diverter Station #3 is constructed of 91 centimeter (36 inch) diameter corrugated metal. The portion of the pipeline between the 241-A-201 cooling water storage tanks and the 216-A-42 basin (30 inch VCP) was taken out of service in June 1992.

Code: 200-E-135**Classification:** Accepted**Names:** 200-E-135; Contamination Area South of 241-C Tank Farm**Reclassification:** None**Type:** Unplanned Release**Start Date:****Status:** Inactive**End Date:****Description:** The site is surrounded with steel posts and chain with Underground Radioactive Material signs attached to the chain. It has been covered with clean gravel. An abandoned, above ground steam pipe is located inside the posted area. Underground pipelines 200-E-148-PL, 200-E-150-PL and 200-E-153-PL cross beneath this area of growing, contaminated vegetation.**Location:** The site is located south of 7th Street and southwest of the 241-C Tank Farm.**Release Description:** In September 2000, three growing, contaminated tumbleweeds were found inside the posted area. The maxim contamination level was 1000 counts per minute above background.**Related Sites/Structures:** Underground pipelines 200-E-148-PL, 200-E-150-PL and 200-E-153-PL cross beneath this area of growing, contaminated vegetation.

Code: 200-E-141**Classification:** Accepted**Names:** 200-E-141; 2715EC Paint Shop French Drain; Miscellaneous Stream #223**Reclassification:** None**Type:** French Drain**Start Date:****Status:** Inactive**End Date:****Description:** The site consists of a french drain behind the 2715EC paint shop.

Location: The drain is 3.05 meters (10 feet) west and 7.62 meters (25 feet) north of the northeast corner of the 2715EC paint shop.

**Related Sites/
Structures:** The drain is associated with the 2715EC Paint Shop.

**Process
Description:** The french drain received effluent from a sink located inside the paint shop. The sink was used to wash latex paint brushes. In 1995, the sink effluent was connected to the sanitary sewer. In March 2007, Curt Clement verified the sink water did not discharge to the french drain.

Code: 200-E-142 **Classification:** Accepted

Names: 200-E-142; Paint Brush Cleaning Station **Reclassification:** None

Type: Depression/Pit (nonspecific) **Start Date:**

Status: Inactive **End Date:**

Description: The site consists of soil cover with gravel and scattered vegetation. There is no visual evidence of the chemicals disposed here. It is possible the site extends northward, beyond the steamline.

Location: The contaminated soil is located north of the 2241-B building foundation (demolished), between the concrete pad and the steam line. The area is south of the 224-B Building.

**Related Sites/
Structures:** The cleaning station is associated with 2241-B Building (demolished structure).

**Process
Description:** The 2241-B building had a concrete pad that included an old paint brush cleaning station. The painters had a three-brush cleaning station on a cement pad on the north side of the building. An open top drum was used to soak paint buckets. The excess liquid drained off of the concrete pad and out of the drum onto the soil.

Waste Type: Chemical Release

**Waste
Description:** The waste includes chemicals used to clean paint brushes and buckets.

Code: 200-E-143-PL **Classification:** Accepted

Names: 200-E-143-PL; Encased Transfer Line from 241-AX-151 Diversion Box to 241-A Tank Farms and 244-CR Vault in 241-C Tank Farm; Tank Farm Transfer Lines 4101, 4102, 4103, 4104, 4105, 4106, 4107/V033, 4017, 4018, 4021, 4022 and 8656 **Reclassification:** None

Type: Encased Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground concrete encased transfer line associated with twelve ten, 10 centimeter (4 inch) diameter, stainless steel pipes. Groups of lines divert from the encasement at various points along the route to 244-CR Vault. Lines 4101, 4102 and 4103 divert into the south end of 241-A Tank Farm to feed tanks 241-A-101, 241-A-102 and 241-A-103. Lines 4104, 4105, 4106, 4017 and 4018 divert from the encasement at the north end of 241-A Tank farm to feed tanks 241-A-104, 241-A-105, 241-A-106 and 241-AX-152 Diversion Box. Line 4107 diverts out of the encasement to 241-A-152 Diversion box. Line 8656 continues north to the 244-CR Vault, inside 241-C Tank Farm. Lines 4021 and 4022 are 3 inch diameter "return

lines". These line begin at 241-AX-152 and end at 241-AX-151.

Location: The concrete encased transfer line extends from the 241-AX-151 Diverter Station, near the corner of Route 4 and Buffalo Ave. to 244-CR Vault, inside 241-C Tank Farm.

Related Sites/ Structures: The concrete encasement is associated with 241-AX-151, 241-A Tank Farm and 241-C Tank Farm.

Process Description: The system used gravity flow to deliver the waste from the 241-AX-151 Diverter Station to the 244-CR VAULT or the A and AX Tank Farms. Return lines were pressurized. The waste line encasements drained at the low end to the diverter station or tank.

Code: 200-E-144-PL **Classification:** Accepted

Names: 200-E-144-PL; Encased Transfer Line from 241-CR-152 and 241-CR-153 to 241-AX-151; Lines 4006 and 4007 from 244-AR Vault to 241-AX-151; Tank Farm Transfer Line 4012; Transfer Line 4013 (A-4013) **Reclassification:** None

Type: Encased Tank Farm Pipeline

Start Date:

Status: Inactive

End Date:

Description: The transfer line is radiologically posted as an Underground Radioactive Material Area. Two, stainless steel pipelines are inside the pipe trench. Lines 4012 and 4013 (A-4013) originate inside the 241-C Farm at the 241-CR-152 and 241-CR-153 Diversion Boxes and terminate at the 241-AX-151 Diverter Station. Both lines are 7.6 centimeter (3 inch) in diameter pipes.

Location: The pipeline extends from 241-C tank farm to 241-AX-151 diversion box, located south of 204 AR, near the corner of 4th Street and Buffalo Ave at the 244-AR Vault facility.

Related Sites/ Structures: 200-E-144-PL is associated with 200-E-145-PL and 200-E-147-PL. Line A-4013 is a DUPLICATE entry in sitecode 200-E-146-PL. It is the same line as line 4103 that is described in sitecode 200-E-144-PL.

Code: 200-E-145-PL **Classification:** Accepted

Names: 200-E-145-PL; Interplant Transfer Line; Tank Farm Transfer Line V228; Transfer Pipeline from 241-ER-151 to 241-CR-153 **Reclassification:** None

Type: Encased Tank Farm Pipeline

Start Date: 1/1/1973

Status: Inactive

End Date: 1/1/1980

Description: The waste site is the PUREX Supernate line (V228). The underground trench that contains lines V228 and PAS-244 is radiologically posted as an Underground Radioactive Material Area. The trench contains two, 3 inch diameter stainless steel pipes.

Location: Line V228 originates in 241-C Farm at the 241-CR-153 Diversion Box, passes through the 241-ER-153 Diversion Box south of 241-C Farm. It continues to the 241-ER-151 Diversion Box. Line PAS-244 is located in the same trench as V228. Line 244 originates at B Plant, and is connected to both 241-ER-151 and 241-ER-152 Diversion Boxes. Both V228 and PAS-244 lines continue into 241-C tank farm at the 241-CR-153 diversion box.

Related Sites/ Structures: The pipeline is associated with diversion boxes 241-ER-151, 241-ER-153, 241-CR-153 and pipeline sitecodes 200-E-144-PL and 200-E-147-PL.

Process Description: The stainless steel pipelines, V228 (PUREX Supernate (PSN) and PAS-244 (PUREX Acid Sludge), are inside located inside the same concrete pipe trench (see 200-E-147-PL). The 241-ER-151 Diversion Box is on the west end of the pipeline. 241-ER-153 Diversion Box is located on the east side of the pipeline. These pipelines make up the Interplant Transfer Line System. From the 244-A Lift Station to 241-C tank farm, lines V228 and PAS-244 join lines 4012 and 4013 inside the same encasement. (see 200-E-144-PL).

Waste Type: Process Effluent

Waste Description: Line V228 transported Purex Supernate (PSN). The supernate contained three curies per gallon of cesium-137, one curie per gallon of strontium 89 and 90 and one curie per gallon of cerium.

Code: 200-E-147-PL **Classification:** Accepted

Names: 200-E-147-PL; Interplant Transfer Line; Tank Farm Transfer Line PAS-244; Transfer Line from 244-CR-TK-003 to 241-ER-153 **Reclassification:** None

Type: Encased Tank Farm Pipeline **Start Date:** 1/1/1973

Status: Inactive **End Date:** 1/1/1978

Description: The waste site is the PUREX Acid Sludge line (PAS-244). It is located inside the encased Interplant Transfer pipe trench that also contains line V228 (per drawing H-2-44501, sheet 92). The pipeline is radiologically posted as an Underground Radioactive Material Area.

Location: Line PAS-244 originates inside 241-C Tank Farm, at the 244-CR Vault (244-CR-TK-003), and enters the 241-ER-153 Diversion Box south of 241-C Farm. Line 244 is located in the same trench as V228 from 241-ER-152 to 241-ER-153. Both lines continue into 241-C tank farm at the 241-CR-153 diversion box. PAS-244 enters 241-ER-152 Diversion Box and terminates at 221-B (B Plant).

Release

Description:

Related Sites/Structures: The pipeline is associated with 200-E-144-PL, 200-E-145-PL, 241-ER-152 and 241-ER-153.

Process Description: The stainless steel pipelines, V-228 and PAS-244, are inside the same concrete pipe trench (see 200-E-145-PL). The 241-ER-152 Diversion Box is located on the west side of the pipeline. The 241-ER-153 Diversion Box is located on the east side of the pipeline. These pipelines and two diversion boxes make up the Interplant Transfer Line System. From the 244-A Lift Station to 241-C tank farm, lines V228 and PAS-244 join lines 4012 and 4013 inside a common encasement (see 200-E-144-PL).

Waste Type: Process Effluent

Waste Description: Line 224 transported Purex Acid Sludge (PAS). It contained one curie per gallon of cesium-137, twenty curies per gallon of strontium 89 and 90 and one curie per gallon of cerium.

Code: 200-E-148-PL **Classification:** Accepted

Names: 200-E-148-PL; Direct Buried Transfer Line from 241-C-151 to 241-A-01A; Tank Farm Transfer Line V109 **Reclassification:** None

Type: Direct Buried Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: Transfer Line V109 is a 5 centimeter (2 inch) diameter, direct buried line, that is radiologically posted as an Underground Radioactive Material Area.

Location: Line V109 originates inside the 241-C Farm at the 241-C-151 Diversion Box and terminates at 241-A-01A Pump Pit inside 241-A Farm.

Related Sites/ Structures: This pipeline passes beneath the Contamination Area known as 200-E-135. Growing contaminated vegetation was found in this area in 2000.

Process Description: The 200-E-148-PL pipeline was constructed in 1963 to transfer PUREX Supernate and PUREX Sludge Supernate from tank 241-A-101 (WMA-A) to diversion box 241-C-151 (WMA-C).

Code: 200-E-149-PL **Classification:** Accepted

Names: 200-E-149-PL; Direct Buried Transfer Line from 241-C-252 to 201-C Hot Semi Works; Tank Farm Pipeline; Tank Farm Transfer Line V175 **Reclassification:** None

Type: Direct Buried Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: Tank Farm Transfer Line V175 is a 2 inch diameter, direct buried, stainless steel Tank Farm process waste pipe. The site is radiologically posted as an Underground Radioactive Material Area.

Location: Line V175 originates inside 241-C Farm at the 241-C-252 Diversion Box and terminates at the 241-C-201-C Diversion Box in the 201-C Hot Semi Works complex.

Release Description: WIDS sitecode 200-E-56 says HW-52860 states that teflon flange gaskets on the stainless steel underground waste line from 201-C to 241-C Tank Farm developed leaks. The leaks caused the underground area next to the east side of the 201-C Building and an underground area near the east facility fence to become contaminated. Radiation readings in 1957 were greater than 100 rad per hour at a depth of 3.66 meters (12 feet) adjacent to the 201-C Building and near the fence. The underground waste line was abandoned and bypass sections installed. New sections of pipeline were installed south of the leaking sections.

Related Sites/ Structures: This pipeline is associated with 201-C and WIDS sitecode 200-E-56 soil contamination event.

Process Description: 200-E-149-PL consists of a single line, V175, which runs between the 201-C Hot Semi Works Valve Box and the 241-C-252 Diversion Box at the 241-C Tank Farm. V175 was constructed in 1957, and was used for the transport of PUREX process wastes in support of the PUREX pilot plant at Hot Semi-works.

Leaks in the line were identified in 1957. The lines were subsequently addressed by cutting and abandoning the leaking pipe sections and installing bypass lines to the south. These bypass lines were installed in 1957. The abandoned lines adjacent to the Hot Semiworks building were also blanked. From 1961-1967, line V175 was used to transport C-Tank Farm wastes to Hot Semi-works for the recovery of Strontium.

Code: 200-E-150-PL **Classification:** Accepted

Names: 200-E-150-PL; Direct Buried Transfer Line from 244-CR-TK-003 to 201-C Hot Semi Works Valve Box; Tank Farm Pipeline; Tank Farm Transfer Line 8900 **Reclassification:** None

Type: Direct Buried Tank Farm Pipeline

Start Date:

Status: Inactive

End Date:

Description: Tank Farm Transfer Line 8900 is a direct buried Tank Farm process waste pipe. The site is radiologically posted as an Underground Radioactive Material Area.

Location: Line 8900 originates at the 201-C Valve Box in the 201-C Hot Semi Works complex and terminates inside 241-C Farm at 244-CR-TK-003 in 244-CR Vault.

Related Sites/ Structures: This pipeline passes beneath the Contamination Area known as 200-E-135. Growing contaminated vegetation was found in this area in 2000.

Code: 200-E-151-PL

Classification: Accepted

Names: 200-E-151-PL; Direct Buried Transfer Line from 241-C-104 to 241-A-152; Tank Farm Pipeline; Tank Farm Transfer Line V050

Reclassification: None

Type: Direct Buried Tank Farm Pipeline

Start Date:

Status: Inactive

End Date:

Description: Tank Farm Transfer Line V050 is a 3 inch diameter, schedule 40 steel, process waste pipe. Approximately 48 meters (160 feet) of the line is located inside the tank farm and encased in concrete. The remaining 1700 feet of pipeline direct buried. The site is radiologically posted as an Underground Radioactive Material Area.

Location: Line V050 originates inside 241-C Tank Farm at the 241-C-104 tank and terminates at the 241-A-152 Diversion Box, inside 241-A Tank Farm.

Related Sites/ Structures: The line is associated with 241-C-104, 241-A-152 and pipeline sitecode 200-E-152-PL.

Process Description: The 200-E-151-PL waste site consists of a single waste transfer pipeline that carried PUREX Coating Waste and PUREX Organic Wash Waste between the 241-A and 241-C Tank Farms. The pipeline was constructed in 1951 and placed into service in 1953. A segment from the main line to the 241-CR-151 diversion box (within Tank Farm C) was abandoned in place and capped in 1966. A new segment within 241-C Tank Farm was re-routed directly to the 241-C-104 Tank. PUREX Coating Waste resulted from the de-cladding of aluminum that encased spent nuclear fuel.

The pipeline was taken out of service in approximately 1985, when Tank Farm transfers were completed and isolation of the 241-A-152 diversion box was performed by plugging all the lines in the diversion box. No releases or losses of transfer fluids associated with this line have been identified.

Code: 200-E-152-PL

Classification: Accepted

Names: 200-E-152-PL; Direct Buried Transfer Line from 241-C-104 to 241-A-152; Tank Farm Pipeline; Tank Farm Transfer Line V051

Reclassification: None

Type: Direct Buried Tank Farm Pipeline

Start Date:

Status: Inactive

End Date:

Description: Tank Farm Transfer Line V051 is a 3 inch diameter, schedule 40 steel, Tank Farm process

waste pipe. Most of the line (approximately 1700 ft) is direct buried. Forty eight meters (160 feet) is encased in concrete. The site is radiologically posted as an Underground Radioactive Material Area.

Location: Line V051 originates inside 241-C Tank Farm at the 241-C-104 tank and terminates at the 241-A-152 Diversion Box inside 241-A Tank Farm.

Related Sites/ Structures: The line is associated with 241-C-104, 241-A-152 and pipeline sitecode 200-E-151-PL.

Process Description: The 200-E-152-PL waste site consists of a single waste transfer pipeline that carried PUREX Coating Waste and PUREX Organic Wash Waste between the 241-A and 241-C Tank Farms. The pipeline was constructed in 1951 and placed into service in 1953. This pipeline was taken out of service in approximately 1985 when Tank Farm transfers were completed and isolation of the 241-A-152 diversion box was performed. Isolation of the 241-A-152 diversion box included the installation of isolation plugs in all the lines originating within the diversion box. No releases or losses of transfer fluids associated with this line have been identified.

Code: 200-E-153-PL **Classification:** Accepted

Names: 200-E-153-PL; Direct Buried Transfer Line from 241-C-151 to 244-AR-TK-002; Tank Farm Pipeline; Tank Farm Transfer Line V108/812 **Reclassification:** None

Type: Direct Buried Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: Tank Farm Transfer Line V108/812 are 3 inch diameter, direct buried, Tank Farm process waste pipes. Line V108 is a stainless steel pipe. Line 812 is a carbon steel pipe. The site is radiologically posted as an Underground Radioactive Material Area.

Location: Line V108/812 originates inside 241-C Tank Farm at the 241-C-151 Diversion Box and terminates at 244-AR-TK-002 in 244-AR Vault.

Release Description: UPR-200-E-86 states that routine line (leak detection) monitoring equipment detected a leak in the vicinity of transfer line number 812. The line was being used to transfer process waste (containing approximately 25,000 curies of cesium-137) from the 244-AR Vault to the 241-C Tank Farm. The leak was identified on February 25, 1971. Eight test wells were drilled to determine the extent of the subsurface contamination. Wells 4, 5 and 8 found subsurface contaminated soil. Well number 4 found a maximum contamination of 5 rad per hour at the 3 foot and 6 foot levels. No contamination was found below the 20 foot level.

Related Sites/ Structures: Line 812 is associated with UPR-200-E-86. It is a line leak that occurred in 1971. A posted Underground Radioactive Material Area, covered with shotcrete, remains. This pipeline also passes beneath the Contamination Area known as 200-E-135, south of 7th Street. Growing contaminated vegetation was found in this area in 2000.

Code: 200-E-154-PL **Classification:** Accepted

Names: 200-E-154-PL; Direct Buried Transfer Line from 241-C-151 to 241-AX-01A; Tank Farm Pipeline; Tank Farm Transfer Line V113 **Reclassification:** None

Type: Direct Buried Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: Tank Farm Transfer Line V113 is a 3 inch diameter, direct buried Tank Farm process waste pipe. The site is radiologically posted as an Underground Radioactive Material Area.

Location: Line V113 originates inside 241-C Tank Farm at the 241-C-151 Diversion Box and terminates at 241-AX-01A Pump Pit inside 241-A Tank farm.

Process Description: The 200-E-154-PL waste site consists of a single pipe run (i.e., V113) used to transfer waste between the 241-AX-101 tank and the 241-C-151 diversion box. The pipe exiting the 241-C-151 diversion box is a 3" stainless steel pipe which runs for 36 ft and then converts to a 3" carbon steel pipe running the remaining distance for a total pipe length of 1,983.6 ft. The pipe is direct buried except for the carbon steel elbows which are encased (the elbows in 3" stainless steel section are direct buried). The pipeline was constructed in 1963 and operational until January 1975 when it failed a pressure test and was abandoned. The pipeline was constructed to transport wastes to and from the AX tanks.

Code: 200-E-155-PL	Classification: Accepted
Names: 200-E-155-PL; Pipeline from 241-C Fence to Radioactive Process Sewer Line 2904-CR-1	Reclassification: None
Type: Radioactive Process Sewer	Start Date:
Status: Inactive	End Date:

Description: The site is an underground, 5 centimeter (2 inch) diameter, carbon steel pipeline.

Location: The pipeline originates at the 241-C-03A Pump Pit inside the 241-C tank farm and connects to the 30 inch corrugated metal pipe (200-E-237-PL) outside the northeast corner of the 241-C tank farm.

Related Sites/ Structures: The pipeline is associated with the 241-C-03A pump pit and the 200-E-237-PL pipeline.

Process Description: 241-C farm condensate was transported to the disposal pond system through this pipeline, that connected to the 30 inch corrugated metal pipe (sitecode 200-E-237-PL).

Code: 200-E-156-PL	Classification: Accepted
Names: 200-E-156-PL; 216-C-1 Pipelines; Pipelines from 201-C to 216-C-1	Reclassification: None
Type: Radioactive Process Sewer	Start Date:
Status: Inactive	End Date:

Description: The site is the underground pipeline that fed the 216-C-1 crib. The eastern portion of the pipeline is a 5 centimeter (2 inch) diameter stainless steel pipe. It connects to a 10 centimeter (4 inch) diameter stainless steel pipe as it enters the crib. It is not separately marked or posted. The pipeline is under the 200-E-41 stabilization cover material.

Location: The pipeline is located inside 200 East Area, south of 7th Street, within the Hot Semiworks stabilized area (sitecode 200-E-41).

Related Sites/ Structures: The pipeline is associated with the demolished 201-C facility, the 216-C-1 crib and the 200-E-41 stabilized area.

Process Description: The original crib line is a 10 centimeter (4 inch) diameter stainless steel line extending from the south wall of 201-C to the 216-C-1 crib. In 1954, the 201-C waste was rerouted through a 5 centimeter (2 inch) diameter stainless steel line extending out of the southeast corner of 201-C.

The 5 centimeter (2 inch) diameter stainless steel replacement line ties into the original 10 centimeter (4 inch) diameter line north of the 216-C-1 crib. The original 10 centimeter (4 inch) diameter line was re-routed to the 216-C-9 Pond.

Code: 200-E-157-PL **Classification:** Accepted
Names: 200-E-157-PL; 216-C-10 Pipeline; Pipeline from 201-C to 216-C-10 Crib **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The site is two underground, 5 centimeter (2 inch) diameter stainless steel pipelines that fed the 216-C-10 crib. The original pipeline extended from 201-C to 216-C-10. A second pipeline, from 241-CX vault, tied into the original 216-C-10 crib line after the 216-C-6 crib was deactivated.

Location: The 216-C-10 crib is located east of the Hot Semiworks stabilized area (sitecode 200-E-41). The crib pipeline extends from the demolished 201-C facility, located with the 200-E-41 area, to the 216-C-10 crib.

Related Sites/ Structures: The site is associated with 200-E-41, the 216-C-10 crib and the 200-E-171-PL pipeline.

Process Description: The 216-C-10 crib received process condensate and liquid waste from the 201-C Building via this pipeline. A gate valve is located at approximately the mid point of the line, between 201-C and 216-C-10. The line was blanked where it tied into the 216-C-6 crib line (see sitecode 200-E-171-PL).

This Site has the Following SubSites:

Code: 200-E-157-PL:1
Names: 200-E-157-PL:1; Pipeline from 201-C to 216-C-10 Crib
Code: 200-E-157-PL:2
Names: 200-E-157-PL:2; Pipeline from 241-CX Vault to 216-C-10 Crib Line

Code: 200-E-157-PL:1 **Classification:** Accepted
Names: 200-E-157-PL:1; Pipeline from 201-C to 216-C-10 Crib **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

The SubSite is Part Of:

Code: 200-E-157-PL
Names: 200-E-157-PL; 216-C-10 Pipeline; Pipeline from 201-C to 216-C-10 Crib

Code: 200-E-157-PL:2 **Classification:** Accepted
Names: 200-E-157-PL:2; Pipeline from 241-CX Vault to 216-C-10 Crib Line **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**

Status: Inactive

End Date:

The SubSite is Part Of:

Code: 200-E-157-PL

Names: 200-E-157-PL; 216-C-10 Pipeline; Pipeline from 201-C to 216-C-10 Crib

Code: 200-E-158-PL

Classification: Accepted

Names: 200-E-158-PL; 216-A-1 Pipeline; Pipeline from Sample Pit #3 to 216-A-1 Crib

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The site is an underground pipeline. It is not separately marked or posted on the surface.

Location: Sample Pit #3 and the 216-A-1 crib and associated pipeline are located east of the 241-A tank farm, on the east side of Canton Ave., outside the tank farm fence.

Related Sites/ Structures: The pipeline is associated with the 216-A-1 crib and Sample Pit #3.

Process Description: The pipeline is constructed of six inch diameter, extra strong, vitrified clay.

Code: 200-E-159-PL

Classification: Accepted

Names: 200-E-159-PL; Pipeline from 203-A to 216-A-22; Pipeline from 203-A to 216-A-28 Crib; Pipeline from UNH Truck Apron to 216-A-22

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is a series of underground pipelines from the 203-A facility to the 216-A-22 and 216-A-28 cribs and drainage from the UNH Truck Apron. The pipeline is a 10 centimeter (4-inch) stainless steel 304 perforated pipe. It is 1.2 meters (4 feet) below grade.

Location: The pipeline and crib are located north of PUREX, and north of the 203-A tank storage area.

Related Sites/ Structures: The pipelines are associated with 216-A-22, the UNH Truck Apron sump and 216-A-28.

Process Description: The 203-A tank farm was used for storage and shipping of uranyl nitrate hexahydrate (UNH) product and concentration of UNH waste. It consisted of 460,000 liter (100,000 gallon) stainless steel tanks for UNH storage and three smaller nitric acid tanks. The 216-A-22 crib received liquid waste from the 203-A sumps and heating coil condensate from the uranyl nitrate tanks and the truck apron. The effluent was routed to the 216-A-28 crib in 1958. The effluent piping to 216-A-28 was blanked off in November 1976 when the flow rate exceeded the infiltration capacity of the 216-A-28 crib.

This Site has the Following SubSites:

Code: 200-E-159-PL:1

Names: 200-E-159-PL:1; Pipeline from 203-A to 216-A-22

Code: 200-E-159-PL:2
Names: 200-E-159-PL:2; Pipeline from UNH Truck Apron to 216-A-22
Code: 200-E-159-PL:3
Names: 200-E-159-PL:3; Pipeline from 203-A to 216-A-28 Crib

Code: 200-E-159-PL:1 **Classification:** Accepted
Names: 200-E-159-PL:1; Pipeline from 203-A to 216-A-22 **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The pipeline is a 10 centimeter (4 inch) diameter U3-CD pipe.
Location: 200-E-159-PL:1 is the line from 203-A to 216-A-22.

The SubSite is Part Of:

Code: 200-E-159-PL
Names: 200-E-159-PL; Pipeline from 203-A to 216-A-22; Pipeline from 203-A to 216-A-28 Crib; Pipeline from UNH Truck Apron to 216-A-22

Code: 200-E-159-PL:2 **Classification:** Accepted
Names: 200-E-159-PL:2; Pipeline from UNH Truck Apron to 216-A-22 **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The pipeline is a 10 centimeter (4 inch) diameter U3-DC pipe.
Location: 200-E-159-PL:2 is the drain line from the truck apron to 216-A-22.

The SubSite is Part Of:

Code: 200-E-159-PL
Names: 200-E-159-PL; Pipeline from 203-A to 216-A-22; Pipeline from 203-A to 216-A-28 Crib; Pipeline from UNH Truck Apron to 216-A-22

Code: 200-E-159-PL:3 **Classification:** Accepted
Names: 200-E-159-PL:3; Pipeline from 203-A to 216-A-28 Crib **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The pipeline is constructed of 10 centimeter (4 inch) diameter stainless steel tubing.
Location: 200-E-159-PL:3 is the underground line from the 216-A-22 pipeline (subsite 1) to the 216-A-28 crib.

The SubSite is Part Of:

Code: 200-E-159-PL
Names: 200-E-159-PL; Pipeline from 203-A to 216-A-22; Pipeline from 203-A to 216-A-28 Crib; Pipeline from UNH Truck Apron to 216-A-22

Code: 200-E-160-PL **Classification:** Accepted
Names: 200-E-160-PL; Pipeline from 270-E-1 to 216-B-12 Crib; V219 **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is an underground pipeline. The segment from pipeline from the 270-E-1 neutralization tank to the 216-B-12 crib is 15 centimeter (6 inch diameter) vitrified clay pipe. The segment from the 241-ER-151 diversion box to the 270-E-1 neutralization tank is a 3 inch stainless steel line. A portion of the line is encased in concrete.

Location: The pipeline is located west of 221-B, north of 7th Street.

Related Sites/ Structures: The site is associated with the 241-ER-151 Diversion Box, 216-B-12 crib and 270-E-1.

Process Description: A (3 inch) stainless steel line (V219) diverts from a multi-line encasement (200-E-217-PL) to the 270-E-1 Neutralization Tank. A 15.2 centimeter (6 inch) stainless steel pipeline exits the 270-E-1 tank and connects to a 15.2 centimeter vitrified clay pipe, that goes to the 216-B-12 crib. The pipeline carried waste from 221-U, via the cross site transfer line and 241-ER-151 diversion box, to the 216-B-12 crib. When the 200-E-162-PL pipeline was constructed, the 200-E-160-PL pipeline severed. Effluent was routed to 200-E-162-PL, north of the inactive neutralization tank. The modified pipeline (200-E-162-PL) carried B Plant process condensate to the 216-B-12 crib. The 270-E-1 neutralization tank was decommissioned in 1967. The 200-E-160-PL pipeline was drained and capped with a flange in 1973.

Code: 200-E-161-PL **Classification:** Accepted
Names: 200-E-161-PL; Pipeline from 221-BB to 216-B-55 Crib; V841 **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:** 1/1/1967
Status: Inactive **End Date:** 1/1/1976

Description: The waste site is an underground, 15 centimeter (6 inch) diameter, carbon steel pipeline that fed the 216-B-55 crib. This line was later cut and capped and replaced with a 20 centimeter (8 inch diameter) carbon steel pipeline.

Location: The pipeline originates south of B Plant, at 221-BB. It runs westward to the 216-B-55 Crib.

Process Description: The 200-E-161-PL Waste Site was a pipeline that transferred process condensate from the 221-B Building to the 216-B-55 Crib. The pipeline line was originally constructed in 1967. In 1972 this line leaked and caused two Unplanned Releases (UPR-200-E-103 on 3/8/72 and UPR-200-E-44 on 8/16/72). The original (1967) line was cut, capped and abandoned in place. In 1973, a new 8" replacement pipeline was installed south of the original line. In 1976, the replacement pipeline was modified to flow through the 216-B-64 Diversion Pit to an additional pipeline (200-E-163-PL). It was designed to transfer fluids between the 216-B-64 Diversion Pit and the 216-B-64 Retention Basin, but it was never used. The 8" 200-E-163-PL line was cut, capped and abandoned in 1996.

Code: 200-E-162-PL **Classification:** Accepted

Names: 200-E-162-PL; Lateral Line to 216-B-12 Crib #2; Pipeline from 221-BB to 216-B-62 Crib; V842 **Reclassification** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is a 10 centimeter (4 inch), Fiberglass Reinforced Epoxy, underground pipeline that originates in the 221-BB Sample Pit. The site includes the main pipeline to the 216-B-62 crib and a lateral line to 216-B-12, crib number 2 (see subsite 2).

Location: The pipeline originates on the south side of B Plant at the 221-BB Sample Pit. It extends northwest of the 221-B building to the 216-B-62 crib.

Related Sites/ Structures: The pipeline is associated with 216-B-62 crib and 216-B-12 crib.

Process Description: The pipeline carried B Plant process condensate waste from B Plant to crib #2 of 216-B-12 and the 216-B-62 crib.

200-E-162-PL was constructed in 1966 to transport B Plant process condensate waste from 212-B, via 212-BB, to the 216-B-12 Crib. A lateral (side branch) pipe extended into the 216-B-12 Crib (crib 2). In 1969, a new section of pipeline was extended to connect to the newly constructed 216-B-62 Crib. The 216-B-62 crib placed on standby. The 216-B-62 crib was activated in 1973, due to a collapse at the 216-B-12 crib. The 216-B-62 crib replaced the 216-B-12 crib.

This Site has the Following SubSites:

Code: 200-E-162-PL:1

Names: 200-E-162-PL:1; Pipeline from 221-B to 216-B-62 Crib

Code: 200-E-162-PL:2

Names: 200-E-162-PL:2; Lateral Pipe to Crib #2 of 216-B-12

Code: 200-E-162-PL:1 **Classification:** Accepted

Names: 200-E-162-PL:1; Pipeline from 221-B to 216-B-62 Crib **Reclassification** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The pipeline is an underground, 10 centimeter (4 inch) diameter, Fiberglass Reinforced Epoxy pipe.

Location: The pipeline originates on the south side of B Plant at the 221-BB Sample Pit. It extends northwest of the 221-B building to the 216-B-62 crib.

The SubSite is Part Of:

Code: 200-E-162-PL

Names: 200-E-162-PL; Lateral Line to 216-B-12 Crib #2; Pipeline from 221-BB to 216-B-62 Crib; V842

Code: 200-E-162-PL:2 **Classification:** Accepted

Names: 200-E-162-PL:2; Lateral Pipe to Crib #2 of 216- **Reclassification** None

B-12

Type: Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:**

Description: Subsite 2 is an underground, 10 centimeter (4 inch) diameter, Fiberglass Reinforced Epoxy pipe. It tees off 200-E-162-PL:1 (216-B-62 main line) to feed the center crib (crib #2) at 216-B-12.

Process Description: The pipeline carried B Plant Process Condensate waste to the 216-B-12 crib. The 216-B-62 crib and 200-E-162-PL pipeline were constructed in 1966. The pipeline and side branch fed the 216-B-12 crib until 1973. In 1973, the 216-B-12 crib was deactivated and replaced with the 216-B-62 crib. The side branch was cut and abandoned in place at that time.

The SubSite is Part Of:**Code:** 200-E-162-PL**Names:** 200-E-162-PL; Lateral Line to 216-B-12 Crib #2; Pipeline from 221-BB to 216-B-62 Crib; V842**Code:** 200-E-164-PL**Classification:** Accepted**Names:** 200-E-164-PL; Pipeline Between the 216-A-8 Control Structure and the 216-A-508 Control Structure; Pipeline to 216-A-8 Crib**Reclassification:** None**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:**

Description: The site is a 41 centimeter (16 inch) diameter, schedule 20 steel pipeline.

Location: The pipeline runs eastward, from the 216-A-8 Control Structure (adjacent to 241-A Tank Farm) to the 216-A-508 Control Structure at the north end of the 216-A-8 crib. The crib is located east of the 200 East Area fence.

Related Sites/ Structures: The pipeline is associated with the 216-A-8 Control Structure, the 216-A-508 Control Structure and the 216-A-8 crib.

Code: 200-E-165-PL**Classification:** Accepted**Names:** 200-E-165-PL; Pipeline from 216-A-508 Control Structure and 216-A-8 Crib to 216-A-24 Crib**Reclassification:** None**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:**

Description: The site is a 41 centimeter (16 inch) carbon steel pipeline. The pipeline connects the 216-A-508 Control Structure to the 216-A-524 Control Structure. A 5 centimeter (2 inch) diameter Bypass line extends from the 216-A-524 Control Structure to the third lobe of the crib structure (see subsites).

Location: The pipeline is located east of the 200 East Area fence. It runs north from the 216-A-508 Control Structure to the 216-A-524 Control Structure located on the west end of the 216-A-24 crib.

This Site has the Following SubSites:

Code: 200-E-165-PL:1
Names: 200-E-165-PL:1; Main Pipeline Between 216-A-508 Control Structure and 216-A-524 Control Structure

Code: 200-E-165-PL:2
Names: 200-E-165-PL:2; Bypass Line

Code: 200-E-165-PL:1 **Classification:** Accepted

Names: 200-E-165-PL:1; Main Pipeline Between 216-A-508 Control Structure and 216-A-524 Control Structure **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The main pipeline is a (16 inch) diameter carbon steel line.

The SubSite is Part Of:

Code: 200-E-165-PL

Names: 200-E-165-PL; Pipeline from 216-A-508 Control Structure and 216-A-8 Crib to 216-A-24 Crib

Code: 200-E-165-PL:2 **Classification:** Accepted

Names: 200-E-165-PL:2; Bypass Line **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: A 5 centimeter (2 inch) diameter bypass line extends along the north side of the 216-A-24 crib, from the 216-A-524 Control Structure to the third lobe of the crib.

The SubSite is Part Of:

Code: 200-E-165-PL

Names: 200-E-165-PL; Pipeline from 216-A-508 Control Structure and 216-A-8 Crib to 216-A-24 Crib

Code: 200-E-166-PL **Classification:** Accepted

Names: 200-E-166-PL; Pipeline from 241-A Tank Farm to 216-A-34 Ditch **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The site is an underground, 38 centimeter (15 inch) diameter, vitrified clay pipe.

Location: The pipeline extends eastward from the 241-A tank farm, beyond the 200 East Area fence, to the head end of 216-A-34.

Release Description: UPR-200-E-145 states - In 1993, while excavating for the installation of a new pipeline (Project W-049H) and exposing existing utility lines, contaminated soil with a radiological reading of 300,000 disintegrations/minute beta-gamma was detected at a depth of 0.8 meter (2.5 feet). The contamination was found above an existing 38 centimeter (15 inch) vitrified clay pipe, which was suspected to be the source. Sample analysis of the green colored soil indicated it was uranium oxide.

Related Sites/ Structures: The site is associated with the 216-A-8 Sample Pit (control structure) and the 216-A-34 ditch. UPR-200-E-145 found contamination associated with this pipeline.

Process Description: The 216-A-34 ditch received cooling water from the contact condenser in the 241-A-431 building via a VCP pipeline.

Code: 200-E-167-PL **Classification:** Accepted

Names: 200-E-167-PL; Lines SN-215 and SN-216; Underground Pipelines from 244-A Lift Station to 241-A-A and 241-A-B Valve Pits **Reclassification:** None

Type: Encased Tank Farm Pipeline

Start Date:

Status: Inactive

End Date:

Description: The waste site is two underground, carbon steel pipelines.

Location: The pipeline is located south of 7th Street and west of Buffalo Ave., inside 200 East Area.

Related Sites/ Structures: The pipelines are associated with the 244-A Lift Station and the 241-A Tank Farm.

Process Description: Lines SN-215 and SN-216 are in the same trench that connects 244-A Lift Station with the 241-A-A and 241-A-B Valve Pits. They are double contained (pipe-in-pipe), carbon steel lines that are surrounded by a minimum of 7.6 centimeters (3 inches) of polyurethane insulation. The interior pipe is 7.6 centimeter (3 inch diameter) schedule 40 pipe. The outer pipe is 15.2 centimeter (6 inch diameter) schedule 40 pipe.

Code: 200-E-168-PL **Classification:** Accepted

Names: 200-E-168-PL; Underground Pipeline from 203-A to 216-A-3 **Reclassification:** None

Type: Radioactive Process Sewer

Start Date: 1/1/1956

Status: Inactive

End Date: 1/1/1967

Description: The waste site an underground, 10 centimeter (4-inch) Schedule 10 perforated 304 stainless steel pipe placed horizontally 2.4 meters (8 feet) below grade. Two 6.1 meter (20 foot) lengths of this pipe placed perpendicularly to the first pipe, forming an H pattern inside the crib.

Location: The pipeline is located north of 202-A (PUREX) and south of the 275-EA building.

Related Sites/ Structures: The pipeline is associated with 216-A-3 crib.

Process Description: From 1956 to 1967, the site received silica-gel regeneration waste and pump house drainage from 203-A and drainage from the UNH storage pit. The silica gel discharge was discontinued in 1967.

Code: 200-E-169-PL **Classification:** Accepted

Names: 200-E-169-PL; Pipeline from 201-C and 215-C to the 216-C-3 Crib **Reclassification:** None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is an underground vitrified clay pipeline that fed the 216-C-3 crib. The diameter of the vitrified clay pipe varied from 10 centimeters (4 inch) to 15 centimeters (6 inch).

Location: The pipeline extends from the 215-C building and the 201-C (demolished) building to the 216-C-3 crib. The majority of the pipeline is located west of the 201-C building.

Related Sites/ Structures: The site is associated with the 216-C-3 crib and pipeline 200-E-255-PL.

Code: 200-E-170-PL

Classification: Accepted

Names: 200-E-170-PL; Pipeline from 276-C to 216-C-4 Crib

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is an underground 5 centimeter (2 inch) diameter, stainless steel pipeline from 276-C to the 216-C-4 crib. Also included is a 2.5 centimeter (1 inch) diameter stainless steel line from 201-C to 276-C.

Location: The pipeline runs southwest of the 276-C building, west of the demolished 201-C facility.

Related Sites/ Structures: The site is associated with the 216-C-4 crib.

Process Description: The crib received waste from the 276-C Solvent Handling building.

Code: 200-E-171-PL

Classification: Accepted

Names: 200-E-171-PL; Pipeline from 201-C and 241-CX Vault to the 216-C-6 Crib

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is an underground 5 centimeter (2 inch) diameter carbon steel pipeline.

Location: The pipeline is located south of 7th Street, and west of the 216-C-10 crib.

Related Sites/ Structures: The pipeline is associated with the 216-C-6 crib, the 241-CX vault and the 200-E-157-PL pipeline.

Process Description: The 216-C-6 crib received radioactive REDOX and PUREX type process condensate from 201-C and 241-CX vault floor drainage via this pipeline. When the 216-C-6 crib was discontinued, the effluent was diverted to the 216-C-10 crib via pipeline 200-E-157-PL.

Code: 200-E-172-PL

Classification: Accepted

Names: 200-E-172-PL; Pipeline from 209-E to the 216-C-7 Crib

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive**End Date:****Description:** The site is an underground 5 centimeter (2 inch) stainless steel pipeline.**Location:** The pipeline is located south of the 209-E building.**Related Sites/
Structures:** The pipeline is associated with the 216-C-7 crib.**Process
Description:** The 209-E building was designed to perform critical mass experiments using plutonium nitrate solutions and enriched uranium. At the completion of an experiment, the waste in the Neutron Reflector Tanks was discharged to a 222 liter (60 gallon) buried waste tank outside the building (Critical Mass Laboratory Valve Pit and Hold Up Tank [209-E-TK-111]). After sampling, the tank contents that were below levels of concern were discharged to the 216-C-7 crib.

Code: 200-E-173-PL**Classification:** Accepted**Names:** 200-E-173-PL; Pipeline from 241-CX-71 to 216-C-5 Crib**Reclassification** None**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** The site is an underground 5 centimeter (2 inch) diameter, carbon steel pipeline.**Location:** The pipeline is located south of the demolished 201-C facility. It curves around the 216-C-1 crib area.**Process
Description:** The pipeline carried High Salt Waste that had passed through the 241-CX-71 neutralization tank to the 216-C-5 crib.

Code: 200-E-174-PL**Classification:** Accepted**Names:** 200-E-174-PL; 216-B-10 (A&B) Pipeline; Pipeline from 221-BC and 222-B to 216-B-10 A&B Cribs**Reclassification** None**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** The waste site is an underground, 9 centimeter (3.5 inch) diameter, stainless steel pipeline. The pipeline extends north and south from the 221-BC building and east to west from the 222-B building to connect to the 216-B-10 A&B cribs.**Location:** The pipeline is located south of the 221-B building.**Related Sites/
Structures:** The pipeline is associated with the 216-B-10 A & B cribs, 200-E-179 catch tank, the 222-B laboratory and the 221-BC building.**Process
Description:** In 1949, the pipeline began to carry waste from the 222-B laboratory sink and sample slurper to the 216-B-10A and 10B cribs. In 1969, flow to the 216-B-10A crib was terminated. The pipeline was rerouted to feed only the 216-B-10B crib (see subsite 3). An in-line catch tank was added to the pipeline (see sitecode 200-E-179). The pipeline was extended northward to provide drainage from the 221-BC building. The pipeline and catch tank were abandoned in 1974.**This Site has the Following SubSites:**

Code: 200-E-174-PL:1
Names: 200-E-174-PL:1; East/West Pipeline from 222-B

Code: 200-E-174-PL:2
Names: 200-E-174-PL:2; North/South Pipeline from 221-BD to 216-B-10 A&B Cribs

Code: 200-E-174-PL:3
Names: 200-E-174-PL:3; Diagonal Pipe from 200-E-179 In-Line Catch Tank to 216-B-10B Crib

Code: 200-E-174-PL:4
Names: 200-E-174-PL:4; Pipeline Connecting 216-B-10A to 216-B-10B

Code: 200-E-174-PL:1 **Classification:** Accepted
Names: 200-E-174-PL:1; East/West Pipeline from 222-B **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

The SubSite is Part Of:

Code: 200-E-174-PL
Names: 200-E-174-PL; 216-B-10 (A&B) Pipeline; Pipeline from 221-BC and 222-B to 216-B-10 A&B Cribs

Code: 200-E-174-PL:2 **Classification:** Accepted
Names: 200-E-174-PL:2; North/South Pipeline from 221-BD to 216-B-10 A&B Cribs **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

The SubSite is Part Of:

Code: 200-E-174-PL
Names: 200-E-174-PL; 216-B-10 (A&B) Pipeline; Pipeline from 221-BC and 222-B to 216-B-10 A&B Cribs

Code: 200-E-174-PL:3 **Classification:** Accepted
Names: 200-E-174-PL:3; Diagonal Pipe from 200-E-179 In-Line Catch Tank to 216-B-10B Crib **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: Pipe installed to redirect flow to only the 216-B-10B crib after 216-B-10A was terminated.

The SubSite is Part Of:

Code: 200-E-174-PL
Names: 200-E-174-PL; 216-B-10 (A&B) Pipeline; Pipeline from 221-BC and 222-B to 216-B-10 A&B Cribs

Code: 200-E-174-PL:4 **Classification:** Accepted
Names: 200-E-174-PL:4; Pipeline Connecting 216-B-10A to 216-B-10B **Reclassification:** None

Type: Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****The SubSite is Part Of:****Code:** 200-E-174-PL**Names:** 200-E-174-PL; 216-B-10 (A&B) Pipeline; Pipeline from 221-BC and 222-B to 216-B-10 A&B Cribs

Code: 200-E-175-PL**Classification:** Accepted**Names:** 200-E-175-PL; Pipeline from 292-B to 216-B-10 A&B**Reclassification:** None**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** The waste site is an underground, 9 centimeter (3.5 inch) diameter, stainless steel tubing pipeline.**Location:** The pipeline is located southeast of the 221-B building. It runs diagonally from the 292-B building to the 216-B-10 A crib.**Related Sites/ Structures:** The pipeline is associated with the 216-B-10A crib.**Process Description:** The pipeline carried floor drainage waste from the 292-B building to the 216-B-10 A crib.

Code: 200-E-176-PL-A**Classification:** Accepted**Names:** 200-E-176-PL-A; Pipeline from 242-B to 216-B-11-A&B, Portion of pipeline outside the 241-B fence**Reclassification:** None**Type:** Direct Buried Tank Farm Pipeline**Start Date:****Status:** Inactive**End Date:****Description:** The waste site is an underground, 7.6 centimeter (3 inch) diameter, carbon steel pipeline.**Location:** The pipeline extends northward from the 242-B Evaporator building to the 216-B-11 A cribs, crossing through the 241-B tank farm. This waste site is two segments of pipeline (north portion and south portion) that are outside the 241-B tank farm fence. The north portion of this pipeline extends from the north 241-B fence to the 216-B-11A & B reverse wells. The south portion extends from the 242-B building to the tank farm fence.

Code: 200-E-176-PL-B**Classification:** Accepted**Names:** 200-E-176-PL-B; Pipeline from 242-B to 216-B-11-A&B, Portion of pipeline inside the 241-B fence**Reclassification:** None**Type:** Direct Buried Tank Farm Pipeline**Start Date:****Status:** Inactive**End Date:****Description:** The waste site is an underground, 7.6 centimeter (3 inch) diameter, carbon steel pipeline. The

majority of the pipeline is located inside the 241-B tank farm.

Location: The pipeline extends northward from the 242-B Evaporator building to the 216-B-11 A cribs, crossing through the 241-B tank farm. This waste site represents the portion of the pipeline that is located inside the 241-B tank farm fence.

Code: 200-E-177-PL **Classification:** Accepted

Names: 200-E-177-PL; Pipeline Rerouting Waste from 216-B-8 Crib Pipeline to 216-B-11A&B Reverse Wells **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 7.6 centimeter (3 inch) diameter carbon steel pipeline.

Location: The pipeline extends eastward from the 216-B-8 pipeline (200-E-178-PL), north of the 241-B Tank Farm, to 216-B-11A.

Related Sites/Structures: The pipeline is associated with the 216-B-11 A&B cribs and the pipeline that fed the 216-B-8 crib (200-E-178-PL).

Process Description: This pipeline was installed to reroute the 216-B-8 crib waste to the 216-B-11 A&B cribs.

Code: 200-E-178-PL **Classification:** Accepted

Names: 200-E-178-PL; Pipeline from Tank 241-B-110 to 216-B-8 Crib and Tile Field **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground 7.6 centimeter (3 inch) carbon steel pipe encased inside a 15 centimeter (6 inch) pipe.

Location: The pipeline extends northward from the 241-B-110 tank, along the east side of the 241-B tank Farm. Most of this pipeline is located inside the 241-B Tank Farm fence.

Related Sites/Structures: The pipeline is associated with the B Tank Farm, 216-B-8 crib and 200-E-177-PL (rerouted waste from 216-B-8 to 216-B-11A).

Code: 200-E-179 **Classification:** Accepted

Names: 200-E-179; Catch Tank in 216-B-10 A&B Pipeline (See Sitecode 200-E-174-PL); R-13 Catch Tank **Reclassification:** None

Type: Catch Tank **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, metal tank attached to the 216-B-10B crib pipeline (see 200-E-174-PL). Two metal risers and a valve handle are visible at the surface. Four posts and a metal chain surround the surface features.

Location: The catch tank is located approximately 20 feet north of the 216-B-10 A crib, on the crib pipeline.

Related Sites/ Structures: The catch tank is associated with the 216-B-10B crib and the 200-E-174-PL pipeline.

Code: 200-E-180-PL **Classification:** Accepted

Names: 200-E-180-PL; Pipeline from 241-BY ITS2 to 216-B-57 Crib **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground 10 centimeter (4 inch) diameter carbon steel pipeline.

Location: The pipeline extends westward from the northwest corner of the 241-BY tank farm to the 216-B-57 crib.

Related Sites/ Structures: The pipeline is associated with the 241-BY ITS2 structure and the 216-B-57 crib.

Code: 200-E-182-PL **Classification:** Accepted

Names: 200-E-182-PL; Pipeline from 241-A-152 Diversion Box to 216-A-7 Crib **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The site is an underground, 15 centimeter (6 inch) diameter, vitrified clay pipe. An underground radiological material area (URMA), surrounded with cement marker posts, is located above a portion of this pipeline (see 200-E-306).

Location: The pipeline extends eastward from the 241-A-302B Catch Tank, under Canton Ave., to the 216-A-7 crib. A portion of the pipeline is inside the 241-A Tank Farm.

Related Sites/ Structures: The pipeline is associated with the 241-A-152 Diversion Box, the 241-A-302B Catch Tank and the 216-A-7 crib. A radiological area, surrounded with cement marker posts, is located above a portion of this pipeline. See sitecode 200-E-306. It is possible it could be related to the pipeline.

Code: 200-E-183-PL **Classification:** Accepted

Names: 200-E-183-PL; Lines V010 and V011; Pipelines from 241-A-151 Diversion Box to 216-A-2 **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site consists of two, stainless steel pipelines, direct buried in the same soil trench. V010 and V011 are 7.6 centimeter (3 inch) stainless steel pipes. Lines V014 and V016 are buried adjacent to lines V010 and V011 (see sitecode 200-E-185-PL).

Location: The pipelines are located south of PUREX. They extend southward from the 241-A-151 Diversion Box to the 216-A-2 and 216-A-4 Cribs.

Related Sites/ Structures: The lines are associated with the 241-A-151 Diversion Box, 216-A-2 crib, 216-A-4 crib, 200-E-184-PL, 200-E-185-PL and 200-E-196-PL.

Process Description: Lines V010, V011, V014 and V016 extend from the 241-A-151 diversion box in the same soil trench. At a point just north of the 216-A-4 crib, the lines separate. Lines V010 and V011 split off and tie into the 216-A-2 crib structure. Lines V014 and V016 tie into the 216-A-4 crib structure.

Code: 200-E-184-PL **Classification:** Accepted

Names: 200-E-184-PL; Lines V010 and V011; Pipeline from 241-A-151 Diversion Box to 216-A-2 Crib **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is two parallel, 10 centimeter (4 inch) diameter, vitrified clay pipes that fed the 216-A-2 crib. The two lines are direct buried in the same soil trench.

Location: The pipelines are located south of the 202-A facility and west of the 216-A-4 crib.

Related Sites/ Structures: The pipelines are associated with the 241-A-151 Diversion Box, 200-E-183-PL, 200-E-186-PL and the 216-A-2 crib.

Process Description: Waste lines V010 and V011 originated at the 241-A-151 Diversion Box (see sitecode 200-E-183-PL). They are direct buried in the same soil trench with lines V014, V016 and T167. At a point just north of the 216-A-4 crib, the lines separate. Three lines (V014, V016 and T167) tie into the 216-A-4 crib structure. Lines V010 and V011 split off and tie into the 216-A-2 crib structure. The line numbers V010 and V011 indicate the specific waste stream. When the 216-A-2 crib was abandoned, the pipelines were cut. The effluent was redirected to the 216-A-31 crib by extending lines V010 and V011 (see sitecode 200-E-186-PL).

Code: 200-E-185-PL **Classification:** Accepted

Names: 200-E-185-PL; Lines V014 and V016; Pipeline from 241-A-151 Diversion Box to 216-A-4 Crib **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site consists of two, stainless steel pipelines, direct buried in the same soil trench. Lines V014 and V016 are 7.6 centimeter (3 inch) stainless steel pipes. Lines V010 and V011 are buried adjacent to lines V014 and V016 in the same soil trench (see sitecode 200-E-183-PL). Lines V014 and V016 connect into the 216-A-4 crib structure using a Double Y Connection to connect into the vitrified clay crib distribution pipes. Line T167 enters the soil trench just north of the 216-A-4 crib (see sitecode 200-E-196-PL).

Location: The 216-A-4 crib lines are located south of 202-A. They enter the north side of the crib structure.

Related Sites/ Structures: The pipelines are associated with the 241-A-151 Diversion Box, 216-A-TK-2, 200-E-183-PL, 200-E-196-PL and the 216-A-4 crib.

Process Description: The line numbers indicate a specific waste stream. Waste lines V014, V016 originate at the 241-A-151 Diversion Box. They are direct buried in the same soil trench with lines V010, V011. At a point just north of the 216-A-4 crib, the lines separate. Near the north side of the 216-A-4 crib, line T022 from the 291-A Control House, enters the pipe trench and ties into line

T167, becoming part of line T167 (see sitecode 200-E-196-PL). Line T167 is connected to the 216-A Sample Pit. These three lines (V014, V016 and T167) tie into the 216-A-4 crib structure. Lines V010 and V011 split off and tie into the 216-A-2 crib structure. Line V014 was later rerouted to 216-A-TK-2 and blanked off.

Code: 200-E-186-PL **Classification:** Accepted

Names: 200-E-186-PL; Lines V010 and V011; Pipeline from 241-A-151 Diversion Box to 216-A-31 crib **Reclassification** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is two underground, 7.6 centimeter (3 inch) diameter, stainless steel pipes that are buried in the same soil trench.

Location: The pipelines are located south of 202-A. The 216-A-31 crib pipelines originate at a point where the 216-A-2 crib lines were abandoned.

Related Sites/ Structures: The site is associated with the 216-A-31 crib and pipeline 200-E-184-PL.

Process Description: When discharge to the 216-A-2 crib was discontinued, flow was diverted to the 216-A-31 crib through two stainless steel pipelines. The line numbers V010 and V011 indicate the waste stream was diverted from 216-A-2 to 216-A-31.

Code: 200-E-187-PL **Classification:** Accepted

Names: 200-E-187-PL; Chemical Sewer from 202-A to 216-A-29 Ditch; Lines 8819, 5802 and 5701; PUREX Chemical Sewer (CSL) **Reclassification** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground chemical sewer pipeline. The pipeline begins as a 30 centimeter (12 inch) diameter vitrified clay line but increases to a 38 centimeter (15 inch) diameter vitrified clay line about midway before reaching the 216-A-29 ditch. The original chemical sewer line connected to a 183 centimeter (36 inch) diameter corrugated metal pipe prior to entering the 216-A-29 ditch head wall. Eight manholes and the 216-A-42E control structure are located along the pipeline. A section of this sewer near 216-A-42 basin is constructed of polyethylene plastic.

Location: The chemical sewer line extends from the north side of the 202-A facility and runs eastward to the head end of the 216-A-29 ditch.

Related Sites/ Structures: The waste site is associated with the PUREX facility and the 216-A-29 ditch.

Process Description: The pipeline carried PUREX chemical sewer waste to the 216-A-29 ditch. The 241-A Tank Farm was constructed during 1984 and 1985. The head end of the 216-A-29 ditch was relocated and a portion of the chemical sewer was re-routed north of the new tank farm on the north side of 4th Street. A short piece of the original 183 centimeter (36 inch) diameter corrugated metal pipe remains near the north side of the 272-AW building.

Code: 200-E-188-PL	Classification: Accepted
Names: 200-E-188-PL; 2904-E-2; B Plant Chemical Sewer Line; BCE; 15-Inch VP Line	Reclassification: None
Type: Radioactive Process Sewer	Start Date:
Status: Inactive	End Date:

Description: The site is the underground 38 centimeter (15 inch) diameter vitrified clay pipe and a section of 40 centimeter (16 inch) diameter steel piping, from B-Plant to the valve box east of the 207-B Retention Basin. The pipeline is also known as 2904-E-2 and the B Plant Chemical Sewer. The pipelines are marked above ground with steel posts and "Underground Radioactive Material/Pipeline" signs. Access manholes are located at intervals along the length of pipelines. Vegetation over the pipelines consists of grass and tumbleweeds, with several areas of bare soil.

Location: The 2904-E-2 chemical sewer line runs from the north side of 221-B to the east side of the 207-B Retention Basin. The 2904-E-2 pipeline bypasses the retention basin to discharge directly into the 216-B-2 ditches.

Release Description: UPR-200-E-138 is associated with the B Plant chemical sewer pipeline. On March 22, 1970, a leaking manometer sensing line from the 8-1 Tank inside the 221-B Building was flushed down a floor drain connected to a chemical sewer that contaminated the 216-B-2-2 Ditch and the 216-B-3 Pond. The pipeline bypasses the 207-B Retention Basin so the retention basin was not contaminated as a result of this release, but the release did contaminate the 216-B-2-2 ditch. On March 23, 1970 at 6:00 am, a dose rate of 5 R/hr was noted at check point number one of the 216-B-2-2 Ditch.

Related Sites/Structures: The pipeline is associated with 221-B, 225-B, 211-B, 212-B, 276-B, 224-B, 222-B, the 216-B-2 ditches, 216-B-63 ditch, 200-E-191-PL, 200-E-204-PL, 200-E-205-PL.

Process Description: The 200-E-188-PL (2904-E-2) pipeline bypassed the retention basin to discharge directly into the 216-B-2 ditches. H-2-35495 shows the chemical sewer pipe being cut and plugged south of the valve pit in 1970. Two new 40 centimeter (16 inch) diameter steel pipes (see sitecode 200-E-205-PL) were installed to route effluent to the 216-B-2-3 ditch (see 200-E-205-PL). The piping and valve configuration allowed flow to be diverted to the 216-B-63 ditch (See 200-E-191-PL) or the 216-B-2-3 ditch.

Code: 200-E-189	Classification: Accepted
Names: 200-E-189; 216-A-TK-1 Carbonate Neutralization Tank	Reclassification: None
Type: Neutralization Tank	Start Date: 1/1/1955
Status: Inactive	End Date: 1/1/1991

Description: The waste site is an underground neutralization tank.

Location: The tank is located south of PUREX, south of the 291-A stack. It is inside the Underground Radioactive Material Area known as 200-E-103.

Related Sites/Structures: The tank is associated with the 291-A stack and 200-E-190 (the 216-A-TK-2 catch tank) and pipeline 200-E-196-PL.

Process Description: The tank held calcium carbonate that changed the pH of the 291-A stack condensate waste via line T021. It flowed into 216-A-TK-2 (sitecode 200-E-190) via line T162 and eventually released to cribs via line T167.

Code: 200-E-190 **Classification:** Accepted
Names: 200-E-190; 216-A-TK-2 Catch Tank **Reclassification:** None
Type: Catch Tank **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is an underground catch tank.
Location: The catch tank is located south of PUREX and west of the 216-A Sample Pit.

**Release
Description:**

Related Sites/ Structures: Line V014 is described in sitecode 200-E-185-PL. Line T167 is described in 200-E-196-PL.

Process Description: Multiple waste lines from the 216-A Sample Pit fed the catch tank. Waste was jetted from the catch tank to the 216-A-21 crib.

Code: 200-E-191-PL **Classification:** Accepted
Names: 200-E-191-PL; 216-B-63 Pipeline; Pipeline from 207-B Valve Pit to 216-B-63 Ditch **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is an underground, 38 centimeter (15 inch) diameter, vitrified clay pipeline. The vitrified clay pipeline is connected to the valve pit on the east side of the 207-B Retention basin by a short piece of 41 centimeter (16 inch) diameter carbon steel pipe.

Location: The pipeline is located northeast of the 207-B Retention Basin.

Related Sites/ Structures: The pipeline is associated with the 216-B-63 ditch and the 207-B Retention Basin.

Process Description: The pipeline fed the 216-B-63 ditch.

Code: 200-E-192-PL **Classification:** Accepted
Names: 200-E-192-PL; 216-A-10 Pipelines; Lines from Sample Pit 4 to 216-A-10 Crib **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:** 1/1/1956
Status: Inactive **End Date:** 1/1/1987

Description: The original pipeline to 216-A-10 crib is an underground, 20 centimeter (8 inch) diameter, vitrified clay pipe. The original pipe connected to the center crib distribution line. The 216-A-10 replacement pipeline is an underground, 20 centimeter (8 inch) diameter stainless steel pipeline. The replacement pipeline connected to a new distribution pipe, east of the original distribution pipe.

Location: The pipelines to the 216-A-10 crib are located south of PUREX, southwest of 216-A-5.

Related Sites/ Structures: The pipeline is associated with the 216-A-10 crib and Sample Pit number 4.

Process Description: The pipeline carried acidic PUREX process distillate and condensate waste to the 216-A-10 crib.

This Site has the Following SubSites:

Code: 200-E-192-PL:1

Names: 200-E-192-PL:1; Original Vitrified Clay Crib Pipeline

Code: 200-E-192-PL:2

Names: 200-E-192-PL:2; 216-A-10 Replacement Pipeline

Code: 200-E-192-PL:1 **Classification:** Accepted

Names: 200-E-192-PL:1; Original Vitrified Clay Crib Pipeline **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The original crib pipeline is a 20 centimeter (8 inch) vitrified clay pipeline.

The SubSite is Part Of:

Code: 200-E-192-PL

Names: 200-E-192-PL; 216-A-10 Pipelines; Lines from Sample Pit 4 to 216-A-10 Crib

Code: 200-E-192-PL:2 **Classification:** Accepted

Names: 200-E-192-PL:2; 216-A-10 Replacement Pipeline **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The replacement pipeline is constructed of 20 centimeter (8 inch) diameter stainless steel.

The SubSite is Part Of:

Code: 200-E-192-PL

Names: 200-E-192-PL; 216-A-10 Pipelines; Lines from Sample Pit 4 to 216-A-10 Crib

Code: 200-E-193-PL **Classification:** Accepted

Names: 200-E-193-PL; Line X015; Pipeline from 202-A and 293-A to 216-A-21 Crib **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 15 centimeter (6 inch) diameter, vitrified clay pipeline. It extends from the 293-A building to the 216-A-21 crib.

Location: The pipeline is located south of PUREX and east of the 216-A-4 crib.

Related Sites/ Structures: The VCP pipeline is associated with the 216-A-21 crib, 200-E-196-PL, 200-E-253-PL and the 293-A building.

Process Description: The 216-A-21 crib received sump waste from 293-A Building, laboratory cell drainage from the 202-A Building, and the 291-A-1 Stack drainage via this pipeline. The VCP line was later replaced with a stainless steel line (see sitecode 200-E-196-PL).

Code: 200-E-194-PL **Classification:** Accepted

Names: 200-E-194-PL; Pipeline from 202-A to 216-A-32 Crib **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 15 centimeter (6 inch) diameter, vitrified clay pipeline that fed the 216-A-32 crib.

Location: The 216-A-32 crib and pipeline are located northeast of 202-A and west of the 2607-EE septic tank and tile field.

Related Sites/ Structures: The pipeline is associated with the 202-A canyon and the 216-A-32 crib.

Process Description: The 216-A-32 crib received the 202-A canyon crane maintenance facility floor, sink, and shower drainage via this pipeline.

Code: 200-E-195-PL **Classification:** Accepted

Names: 200-E-195-PL; Line V204; Pipeline from 241-B-154 Diversion Box to 241-B-361 Settling Tank and 216-B-9 Crib **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The site is an underground, 9 centimeter (3.5 inch) diameter, stainless steel pipeline to the 241-B-361 Settling Tank that was later extended to the 216-B-9 crib. Line V204 begins at the 241-B-154 Diversion Box. Line 204 is in the same soil trench as several other tank farm lines (see sitecode 200-E-199-PL), but diverted to the 241-B-361 Settling Tank and later routed to the 216-B-9 crib.

Location: The pipeline is located northeast of 221-B, north of the 216-B-5 Reverse Well.

Release Description: UPR-200-E-7 states that a process waste line leak from 221-B caused the ground to cave-in near the 361-B crib (216-B-9). Approximately 5000 gallons of liquid was lost to the ground over an area approximately 30 square feet. The maximum dose rate was 1.7 rads/hour. The contamination was covered in 1954 and delineated with a chain. It was posted as Underground Contamination. This release is known as UPR-200-E-7.

Related Sites/ Structures: The pipeline is associated with 221-B, the 216-B-9 crib, 241-B-361 and pipeline 200-E-199-PL.

Process Description: The 216-B-9 Crib and Tile Field were built in 1947 to replace the 241-B-361 Settling Tank and the 216-B-5 Reverse well. Line V204 was cut and rerouted to the 216-B-9 crib.

This Site has the Following SubSites:

Code: 200-E-195-PL:1
Names: 200-E-195-PL:1; Original V204 3-Inch Stainless Steel Line to the 241-B-361 Settling Tank

Code: 200-E-195-PL:2
Names: 200-E-195-PL:2; Rerouted V204 3-Inch Stainless Steel Line to 216-B-9 Crib

Code: 200-E-195-PL:1 **Classification:** Accepted

Names: 200-E-195-PL:1; Original V204 3-Inch Stainless Steel Line to the 241-B-361 Settling Tank **Reclassification** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: Line 204 diverts out of the tank farm encasement (200-E-199-PL) to connect to the 241-B-361 settling tank.

The SubSite is Part Of:

Code: 200-E-195-PL

Names: 200-E-195-PL; Line V204; Pipeline from 241-B-154 Diversion Box to 241-B-361 Settling Tank and 216-B-9 Crib

Code: 200-E-195-PL:2 **Classification:** Accepted

Names: 200-E-195-PL:2; Rerouted V204 3-Inch Stainless Steel Line to 216-B-9 Crib **Reclassification** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

The SubSite is Part Of:

Code: 200-E-195-PL

Names: 200-E-195-PL; Line V204; Pipeline from 241-B-154 Diversion Box to 241-B-361 Settling Tank and 216-B-9 Crib

Code: 200-E-196-PL **Classification:** Accepted

Names: 200-E-196-PL; 216-A-21 and 216-A-27 Cribs; Lines T167 and T022; Stainless Steel Line to 216-A-4 **Reclassification** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground stainless steel pipeline that fed the 216-A-4, 216-A-21 and 216-A-27 cribs. Portions of the line range in diameter from 5 centimeters (2 inch) to 7.6 centimeter (3 inch) diameter and 10 centimeter (4 inch). diameter.

Location: The pipeline is located south of 202-A. It originates at the 216-A-4 Sample Pit. The line originally fed the 216-A-4 crib, but later was extended further south (twice) to feed the 216-A-21 and 216-A-27 cribs.

Related Sites/ Structures: The pipeline is associated with the 216-A-4 Sample Pit, 216-A-TK-2, the 291-A Control House, 216-A-4 crib, 216-A-21 crib, 216-A-27 crib, 216-A-26 crib and pipeline sites 200-E-

183-PL, 200-E-185-PL, 200-E-253-PL and 200-E-270-PL.

Process Description: Line numbers indicate a specific waste stream. The T167 pipeline originally fed the 216-A-4 crib from the 216-A-4 sample building. Line T022 from the 291-A Fan Control House tied into T167 just north of the 216-A-4 crib. These lines are buried in the same soil trench as the lines described in 200-E-183-PL (V010, V011, V014 and V016). When the 216-A-4 crib was deactivated, line T167 was rerouted to the 216-A-21 crib. When the 216-A-21 crib was deactivated, line T167 was rerouted to feed the 216-A-27 crib. A branch of this pipeline tied to the 216-A-36 crib pipeline (see sitecode 200-E-253-PL).

Code: 200-E-198-PL **Classification:** Accepted

Names: 200-E-198-PL; Encased Tank Farm Pipeline from 241-BX-154 Diversion to 241-BX-155 Diversion Box; Lines 8902, V282, V283, V284 and V285 **Reclassification:** None

Type: Encased Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground concrete transfer line encasement. Lines V282, V283, V284 and V285 are 9 centimeter (3.5 inch) diameter stainless steel lines. Line V285 diverts from the encasement and connects to transfer line 200-E-199-PL. Line 8902 diverts from the encasement and connects to 200-E-116-PL (H-2-44501, sht 86).

Location: The encased transfer line extends between 241-BX-154 Diversion Box, on the south side of 221-B to the 241-BX-155 Diversion Box located northeast of 221-B. The majority of this encased line is located on the west side of Baltimore Ave.

Related Sites/ Structures: The waste lines are associated with B Plant processes, the 241-BX-154 Diversion Box and the 241-BX-155 Diversion Box.

Code: 200-E-199-PL **Classification:** Accepted

Names: 200-E-199-PL; Lines V204, V206, V208, V209, V211, V213, V215, and V285; Tank Farm Lines from 241-B-154 Diversion Box to 241-B Tank Farm **Reclassification:** None

Type: Direct Buried Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is a group of underground stainless steel transfer lines buried in a common soil trench. All of the pipelines are 9 centimeter (3.5 inch) diameter stainless steel lines. Line V285 diverts from 200-E-198-PL to become part of 200-E-199-PL. V285 also includes a 2 inch drain line from the encasement that connects to the 241-B-302 Catch Tank (H-2-44501, sht 96).

Location: The transfer line extends between the 241-B-154 Diversion Box, located at the corner of 7th Street and Baltimore Ave. and the 241-B Tank Farm. This transfer line is located on the east side of Baltimore Ave.

Release Description: The exact location of the UPR-200-E-7 cave-in on the process line can not be determined from the available documentation. HW-60807 states that in 1954 a cave in occurred near the 361-B crib (alias 216-B-9 crib). The hand drawn sketch in HW-60807 shows the Unplanned Release location as being south and slightly west of the 361-B Reverse Well (216-B-5), approximately where the 241-B-361 tank is located. This location is approximately 125 meters (400 feet) southwest of the south edge of the posted 216-B-9 crib. It is near where pipelines 200-E-199-

PL and 200-E-195-PL connect.

Related Sites/ Structures: The waste site is associated with the 241-B-151, 241-B-152, 241-B-154 Diversion Boxes, UPR-200-E-7 and pipelines 200-E-195-PL, 200-E-198-PL, 200-E-199-PL and 200-E-277-PL.

Process Description: Lines V208, V209 and V211 extend between 241-B-154 Diversion Box and 241-B-152 Diversion Box (inside 241-B Tank Farm). Lines V213 and V215 extend between 241-B-154 Diversion Box and 241-B-151 Diversion Box (inside the 241-B Tank Farm). Line V285 enters the 200-E-199-PL encasement north of 241-B-154 Diversion Box from the encasement described in 200-E-198-PL. Line V204 diverted to the 241-B-361 Settling tank and was later extended to the 216-B-9 crib (see sitecode 200-E-195-PL).

Code: 200-E-201-PL **Classification:** Accepted

Names: 200-E-201-PL; Lines V315 and V319; Transfer Lines from 241-BX-155 to Diversion Boxes in 241-B Tank Farm **Reclassification:** None

Type: Direct Buried Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is two underground, 9 centimeter (3.5 inch) diameter stainless steel pipelines buried in the same soil trench. Lines V315 and V319 extend from the 241-BX-155 Diversion Box and extend to the 241-B-151 and 241-B-152 Diversion Boxes located inside 241-B Tank Farm. For approximately 250 feet beyond the 241-B-155 Diversion box, there are five lines in the same soil trench. Lines V315 and V319 divert eastward, north of the 241-BX-155 Diversion Box to connect to the 241-B Tank Farm (see sitecode 200-E-202-PL).

Location: The transfer lines extend between the 241-BX-155 Diversion Box, on the west side of Baltimore Ave. and connect into the 241-B-151 and 241-B-152 Diversion Boxes located inside 241-B Tank Farm on the east side of Baltimore Ave.

Related Sites/ Structures: The transfer lines are associated with B Plant processes, Diversion Boxes 241-BX-155, 241-B-151 and 241-B-152 and pipeline 200-E-202-PL.

Code: 200-E-202-PL **Classification:** Accepted

Names: 200-E-202-PL; Lines V316, V317, V318; Transfer Lines from 241-BX-155 Diversion Box to 241-BX-153 Diversion Box **Reclassification:** None

Type: Direct Buried Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is three underground, 9 centimeter (3.5 inch) diameter stainless steel pipelines buried in the same soil trench. Lines V316, V317 and V318 exit the 241-BX-155 Diversion Box and extend to the 241-BX-153 Diversion Box inside 241-BX Tank Farm. For approximately 250 feet beyond the 241-B-155 Diversion box, there are five lines in the same soil trench. Lines V315 and V319 divert eastward, north of the 241-BX-155 Diversion Box to connect to the 241-B Tank Farm (see sitecode 200-E-201-PL).

Location: The transfer lines extend from 241-BX-155 Diversion Box to 241-BX-153 Diversion Box in the 241-BX Tank Farm. These lines are on the west side of Baltimore Ave.

Related Sites/ Structures: The transfer lines are associated with B Plant process, 241-BX-155 and 241-BX-153 Diversion Boxes and pipeline sitecode 200-E-201-PL.

Code: 200-E-203-PL **Classification:** Accepted

Names: 200-E-203-PL; Line V7507/9712; Pipeline from 241-BYR-154 Diversion Box to 216-B-2-2 Ditch **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 15 centimeter (6 inch) diameter carbon steel pipe that fed the 216-B-2-2 ditch from diversion box 241-BY-154, located inside 241-BY Tank Farm.

Location: The pipeline extends eastward from the 241-BY-154 Diversion Box, located inside the 241-BY Tank Farm. It crosses under Baltimore Ave. and connects with the head end of the 216-B-2-2 ditch.

Related Sites/ Structures: The site is associated with 241-BY-154, 216-B-2-2 and pipeline site 200-E-204-PL.

Code: 200-E-204-PL **Classification:** Accepted

Names: 200-E-204-PL; Pipeline to 216-B-2-1 and 216-B-2-2 Ditches **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 76 centimeter (30 inch) diameter vitrified clay pipeline that extends from the valve pit east of 207-B Retention Basin to the head end of the 216-B-2-1 and 216-B-2-2 ditches. The site also includes a short section of 61 centimeter (24 inch) diameter clay pipe from the east retention basin outlet to the valve box.

Location: The pipeline is located northeast of the 207-B Retention Basin.

Release Description: UPR-200-E-32: On November 7, 1963, a coil leak developed in the 221-B Building 6-1 Tank (utilized for storing the cerium-rare earth fraction of the fission product stream) which resulted in gross contamination of the 207-B Water Retention Basin and the head end of this unit. After damming off the site approximately 705 meters (1,000 feet) downstream from the head end discharge pipe, the contaminated basin water was flushed into the unit. General dose rates were 500 mr/hr. Tumbleweed that had blown into the 216-B-2-1 ditch were found to be reading 50 R/hr. UPR-200-E-138: In March 1970, approximately 1000 curies of strontium-90 was released to the 216-B-2-2 ditch via the Chemical Sewer.

Related Sites/ Structures: The pipeline is associated with the 207-B Retention Basin and the 216-B-2-1 and 216-B-2 ditches.

This Site has the Following SubSites:

Code: 200-E-204-PL:1

Names: 200-E-204-PL:1; 24-Inch Diameter Pipe

Code: 200-E-204-PL:2

Names: 200-E-204-PL:2; 30-Inch Diameter Pipe

Code: 200-E-204-PL:1 **Classification:** Accepted

Names: 200-E-204-PL:1; 24-Inch Diameter Pipe **Reclassification:** None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This subsite is a short section of 61 centimeter (24 inch) diameter vitrified clay pipe from the retention basin outlet to the valve box.

The SubSite is Part Of:

Code: 200-E-204-PL

Names: 200-E-204-PL; Pipeline to 216-B-2-1 and 216-B-2-2 Ditches

Code: 200-E-204-PL:2

Classification: Accepted

Names: 200-E-204-PL:2; 30-Inch Diameter Pipe

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This subsite is the 76 centimeter (30 inch) diameter clay pipe from the valve box to the 216-B-2-1 and 216-B-2-2 ditches.

The SubSite is Part Of:

Code: 200-E-204-PL

Names: 200-E-204-PL; Pipeline to 216-B-2-1 and 216-B-2-2 Ditches

Code: 200-E-205-PL

Classification: Accepted

Names: 200-E-205-PL; 216-B-2-3 Ditch Pipelines

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is two underground pipes that fed the 216-B-2-3 Ditch. One pipe is a 41 centimeter (16 inch) diameter carbon steel line from the 207-B Retention Basin to the head end of the 216-B-2-3 Ditch. The other is a 38 centimeter (15 inch) diameter vitrified clay line from the B Plant Process Sewer line (see sitecode 200-E-188-PL) to the 216-B-2-3 ditch.

Location: The pipelines are located east of the 207-B Retention Basin.

Related Sites/ Structures: The pipelines are associated with the 207-B Retention Basin, the B Plant Process Sewer and the 216-B-2-3 ditch.

This Site has the Following SubSites:

Code: 200-E-205-PL:1

Names: 200-E-205-PL:1; 16-Inch Diameter Carbon Steel Pipeline from 207-B to 216-B-2-3 Ditch

Code: 200-E-205-PL:2

Names: 200-E-205-PL:2; 15-Inch Diameter Vitrified Clay Pipe from the Process Sewer to the 216-B-2-3 Ditch

Code: 200-E-205-PL:1

Classification: Accepted

Names: 200-E-205-PL:1; 16-Inch Diameter Carbon Steel Pipeline from 207-B to 216-B-2-3 Ditch

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive**End Date:****Description:** Carbon Steel pipe.**The SubSite is Part Of:****Code:** 200-E-205-PL**Names:** 200-E-205-PL; 216-B-2-3 Ditch Pipelines

Code: 200-E-205-PL:2**Classification:** Accepted**Names:** 200-E-205-PL:2; 15-Inch Diameter Vitrified Clay Pipe from the Process Sewer to the 216-B-2-3 Ditch**Reclassification:** None**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** VCP Pipe**The SubSite is Part Of:****Code:** 200-E-205-PL**Names:** 200-E-205-PL; 216-B-2-3 Ditch Pipelines

Code: 200-E-206-PL**Classification:** Accepted**Names:** 200-E-206-PL; Double Pipes from 244-AR Vault to 241-AR-151 Diversion Box; Lines V716, V717 and V718/817**Reclassification:** None**Type:** Direct Buried Tank Farm Pipeline**Start Date:****Status:** Inactive**End Date:****Description:** The waste site is three underground, 7.6 centimeter (3 inch) diameter, stainless steel pipes buried in the same soil trench extending from the north wall of the 244-AR Vault building to the 241-AR-151 Diversion Box. Each pipe (3 inch) is separately double contained within a larger diameter (6 inch) pipe.**Location:** The diversion box is located north of the 244-AR Vault facility, east of the 291-AR ventilation system. The pipes extend eastward along the north wall of the 244-AR building.**Related Sites/ Structures:** The pipeline is associated with the 241-AR-151 Diversion Box and the 244-AR Vault facility.**Process Description:** Two of the pipes originate in cell 3 of the 244-AR vault.

Code: 200-E-207-PL**Classification:** Accepted**Names:** 200-E-207-PL; Encased Transfer Line from 241-A-151 Diversion Box to 241-A-152 Diversion Box; Lines V004, V005, V006, V007 and V008**Reclassification:** None**Type:** Encased Tank Farm Pipeline**Start Date:****Status:** Inactive**End Date:**

Description: The waste site is an underground concrete encasement containing five stainless steel pipelines. Each of the five pipelines is a 9 centimeter (3.5 inch) diameter stainless steel line.

Location: The concrete encasement originates at the 241-A-151 Diversion Box, on the south side of the PUREX building. It runs eastward and turns north to connect with the 241-A-152 Diversion Box, located inside the 241-A Tank Farm. The line crosses under both Canton Ave. and 4th Street.

Release Description: UPR-200-E-67 states that a release occurred on May 7, 1984. An old, contaminated pipe encasement, located under 4th Street north of the 272-AW parking lot, was encountered during the excavation. Contamination levels ranged from 1 to 1.5 milirad per hour.

Related Sites/ Structures: The pipelines are associated with the 241-A-151 and 241-A-152 Diversion Boxes.

Code: 200-E-209-PL **Classification:** Accepted

Names: 200-E-209-PL; Pipeline from 272-BB to 200-E-25 Dry Well **Reclassification:** None

Type: Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 5 centimeter (2 inch) diameter, carbon steel pipeline.

Location: The pipeline is located north of B Plant. It extends northward from the 272-BB building to the 200-E-25 french drain.

Related Sites/ Structures: The pipeline is associated with the 200-E-25 french drain.

Code: 200-E-213-PL **Classification:** Accepted

Names: 200-E-213-PL; Lines V200, V329, V330, V331, V332, V333, and V334; Transfer Lines from 221-B to 241-B-154 Diversion Box **Reclassification:** None

Type: Direct Buried Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is seven underground stainless steel pipelines buried in the same soil trench. All of the lines are 9 centimeter (3.5 inch) diameter pipes.

Location: The transfer lines originate in various cells inside 221-B. They meet south of 221-B and run east to the 241-B-154 Diversion Box. They cross under Baltimore Ave.

Related Sites/ Structures: The lines are associated with 221-B and 241-B-154 Diversion Box.

Process Description: These transfer lines originate inside 221-B. They are not encased in concrete and do not connect to the 241-BX-154 Diversion Box. They were part of the original 1945 B Plant construction.

Code: 200-E-214-PL **Classification:** Accepted

Names: 200-E-214-PL; Pipeline from 291-B Sand Filter **Reclassification:** None

to the 200-E-55 French Drain

Type: Radioactive Process Sewer **Start Date:** 1/1/1945
Status: Inactive **End Date:** 1/1/1997

Description: The waste site is an underground, 15 centimeter (6 inch) diameter, stainless steel pipe.

Location: The pipe to the 200-E-55 french drain is located on the east side of the 291-B Sand Filter structure, southeast of B Plant.

Related Sites/ Structures: The site is associated with the B Plant Sand Filter (sitecode 200-E-30) and the 200-E-55 French Drain.

Process Description: The 200-E-55 french drain received condensate from the B-Plant canyon sand filter and rain water that leaked through the sand filter roof through this pipe.

Code: 200-E-215-PL **Classification:** Accepted

Names: 200-E-215-PL; Line V229; Transfer Line **Reclassification:** None
Between 241-ER-151 Diversion Box and 241-ER-152 Diversion Box

Type: Direct Buried Tank Farm Pipeline **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is a direct buried underground, 7.6 centimeter (3 inch) diameter stainless steel pipe inside a 15 centimeter (6 inch) carbon steel pipe.

Location: The transfer line is located southwest of B Plant. It runs between 241-ER-151 and 241-ER-152 Diversion Boxes. The line crosses under Atlanta Ave.

Related Sites/ Structures: The line is associated with 241-ER-151, 241-ER-152 and 200-E-147-PL.

Code: 200-E-217-PL **Classification:** Accepted

Names: 200-E-217-PL; Encased Transfer Line from 241-ER-151 Diversion Box to 241-BX Tank Farm; **Reclassification:** None
Lines 9808, 9653, 9719 and V225

Type: Encased Tank Farm Pipeline **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is four underground stainless steel lines inside a concrete encasement. Each line is 9 centimeters (3.5 inches) in diameter. Line V225 diverts out of the encasement and extends to 241-B Tank Farm.

Location: The encased transfer line extends north from the 241-ER-151 Diversion box and angles northeast to connect with the 241-BX tank Farm. Line V225 diverts out of the encasement adjacent to the north side of the 218-E-2 Burial ground. It extends eastward to the 241-B Tank Farm.

Related Sites/ Structures: The line is associated with the 241-ER-151 Diversion Box and the 241-B and 241-BX Tank Farms. The pipeline crosses through the 218-E-5A Burial Ground.

This Site has the Following SubSites:

Code: 200-E-217-PL:1
Names: 200-E-217-PL:1; Four Lines Encased in Concrete; Lines 9808, 9653, 9719, and V225
Code: 200-E-217-PL:2
Names: 200-E-217-PL:2; Line V225 that Diverts from the Concrete Encasement

Code: 200-E-217-PL:1 **Classification:** Accepted
Names: 200-E-217-PL:1; Four Lines Encased in Concrete; Lines 9808, 9653, 9719, and V225 **Reclassification** None
Type: Encased Tank Farm Pipeline **Start Date:**
Status: Inactive **End Date:**

Description: Subsite one is the four lines, encased in concrete, that connects to 241-BX Tank Farm.

The SubSite is Part Of:

Code: 200-E-217-PL
Names: 200-E-217-PL; Encased Transfer Line from 241-ER-151 Diversion Box to 241-BX Tank Farm; Lines 9808, 9653, 9719 and V225

Code: 200-E-217-PL:2 **Classification:** Accepted
Names: 200-E-217-PL:2; Line V225 that Diverts from the Concrete Encasement **Reclassification** None
Type: Encased Tank Farm Pipeline **Start Date:**
Status: Inactive **End Date:**

Description: Subsite 2 is Line V225 that diverts from the concrete encasement. It extends from the encasement to 241-B Tank farm in a direct buried soil trench.

The SubSite is Part Of:

Code: 200-E-217-PL
Names: 200-E-217-PL; Encased Transfer Line from 241-ER-151 Diversion Box to 241-BX Tank Farm; Lines 9808, 9653, 9719 and V225

Code: 200-E-218-PL **Classification:** Accepted
Names: 200-E-218-PL; Lines V021; Transfer Lines Between 241-A-151 Diversion Box and 241-AW Tank Farm; V022; V023 **Reclassification** None
Type: Direct Buried Tank Farm Pipeline **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is three, 7.6 centimeter (3 inch) diameter, stainless steel pipes buried in the same soil trench. Each pipe is double contained inside a 15 centimeter (6 inch) steel pipe.

Location: The lines are located on the south and northeast sides of the PUREX facility. The lines go east out of the 241-A-151 Diversion Box, along the south wall of 202-A. The lines turn north and continue to the west side of the 241-AW tank farm. The lines connect to the 241-AW-A and 241-AW-B valve pits, inside the 241-AW tank farm.

Related Sites/ Structures: The lines are associated with the 241-A-151 diversion box and the 241-AW A and B valve pits.

Code: 200-E-219-PL **Classification:** Accepted

Names: 200-E-219-PL; BY Crib Distribution Pipelines; Pipelines from 216-BY-201 Flush Tank to 216-B-43, 216-B-44, 216-B-45, 216-B-46, 216-B-47, 216-B-48, 216-B-49, and 216-B-50 Cribs **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 35.5 centimeter (14 inch) diameter, carbon steel distribution line that fed the eight BY cribs. A 5 centimeter (2 inch) diameter carbon steel by-pass drain line is located at 216-B-50 crib.

Location: The eight BY cribs are located north of the 216-BY tank farm. The pipes that fed the cribs originate on the north side of the 216-BY-201 siphon tank.

Related Sites/ Structures: The lines are associated with the 216-BY-201 Siphon Tank, 216-B-43, 216-B-44, 216-B-45, 216-B-46, 216-B-47, 216-B-48, 216-B-49 and 216-B-50 cribs.

Process Description: The pipeline distributed uranium recovery waste from the 241-BY tank farm to the 241-BY cribs.

This Site has the Following SubSites:

Code: 200-E-219-PL:1

Names: 200-E-219-PL:1; BY Cribs Distribution Line

Code: 200-E-219-PL:2

Names: 200-E-219-PL:2; 216-B-50 By-Pass Drain Line

Code: 200-E-219-PL:1 **Classification:** Accepted

Names: 200-E-219-PL:1; BY Cribs Distribution Line **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: Subsite 1 is the 35.5 centimeter (14 inch) diameter carbon steel distribution line that fed the eight BY cribs.

The SubSite is Part Of:

Code: 200-E-219-PL

Names: 200-E-219-PL; BY Crib Distribution Pipelines; Pipelines from 216-BY-201 Flush Tank to 216-B-43, 216-B-44, 216-B-45, 216-B-46, 216-B-47, 216-B-48, 216-B-49, and 216-B-50 Cribs

Code: 200-E-219-PL:2 **Classification:** Accepted

Names: 200-E-219-PL:2; 216-B-50 By-Pass Drain Line **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: Subsite 2 is the 5 centimeter (2 inch) diameter carbon steel by-pass drain line located at the 216-B-50 crib.

The SubSite is Part Of:

Code: 200-E-219-PL

Names: 200-E-219-PL; BY Crib Distribution Pipelines; Pipelines from 216-BY-201 Flush Tank to 216-B-43, 216-B-44, 216-B-45, 216-B-46, 216-B-47, 216-B-48, 216-B-49, and 216-B-50 Cribs

Code: 200-E-220-PL

Classification: Accepted

Names: 200-E-220-PL; Pipeline from 241-BY Tank Farm to 216-BY-201 Flush Tank and Monitoring Pit

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is an underground, 5 centimeter (2 inch) diameter, carbon steel pipeline and a concrete monitoring pit. The pipeline runs through the monitoring pit before connecting to the 216-BY-201 flush tank.

Location: The pipeline extends from inside 241-BY Tank Farm, north of 241-BY-101, to the 216-BY-201 Flush Tank. It crosses under the tank farm gravel access road diagonally and enters the flush tank at the southeast corner of the tank. The monitoring pit is located approximately 1.5 meters (5 feet) southeast of the flush tank.

Related Sites/ Structures: The pipeline is associated with the 241-BY tank farm and the 216-BY-201 flush tank.

This Site has the Following SubSites:

Code: 200-E-220-PL:1

Names: 200-E-220-PL:1; Flush Pit Drain Line

Code: 200-E-220-PL:2

Names: 200-E-220-PL:2; Concrete Monitoring Pit Structure

Code: 200-E-220-PL:1

Classification: Accepted

Names: 200-E-220-PL:1; Flush Pit Drain Line

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: Subsite 1 is the 2 inch drain line from the tank farm to the flush pit.

The SubSite is Part Of:

Code: 200-E-220-PL

Names: 200-E-220-PL; Pipeline from 241-BY Tank Farm to 216-BY-201 Flush Tank and Monitoring Pit

Code: 200-E-220-PL:2

Classification: Accepted

Names: 200-E-220-PL:2; Concrete Monitoring Pit Structure

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive**End Date:****Description:** Subsite 2 is the 1.8 meter (6 foot) diameter concrete monitoring pit that the pipeline runs through.**The SubSite is Part Of:****Code:** 200-E-220-PL**Names:** 200-E-220-PL; Pipeline from 241-BY Tank Farm to 216-BY-201 Flush Tank and Monitoring Pit

Code: 200-E-221-PL**Classification:** Accepted**Names:** 200-E-221-PL; BC Crib Pipeline Drain Lines; Pipelines to 216-B-51 French Drain**Reclassification:** None**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** The waste site is two underground, 2.5 centimeter (1 inch) diameter, carbon steel drain lines.**Location:** The drain lines from 200-E-114-PL to the 216-B-51 French Drain is located south of 12th Street and east of Baltimore Ave.**Related Sites/ Structures:** The pipeline is associated with the 200-E-114-PL pipeline to the BC cribs and the 216-B-51 french drain.**Process Description:** The pipelines carried flush drainage from the BC pipeline (200-E-114-PL) to the 216-B-51 french drain.

Code: 200-E-222-PL**Classification:** Accepted**Names:** 200-E-222-PL; Distribution Pipelines from 216-BC-201 Siphon Tank to BC Cribs**Reclassification:** None**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** The waste site is an underground, 35.5 centimeter (14 inch) diameter, carbon steel distribution line that fed the six BC cribs. A 5 centimeter (2 inch) diameter carbon steel by-pass drain line is located at 216-B-18 crib.**Location:** The pipelines are located south of Route 4A. The lines extend from the 216-BC-201 Siphon Tank to the six BC cribs.**Related Sites/ Structures:** The lines are associated with the 216-BC-201 Siphon Tank, 216-B-14, 216-B-15, 216-B-16, 216-B-17, 216-B-18, 216-B-19 cribs.**This Site has the Following SubSites:****Code:** 200-E-222-PL:1**Names:** 200-E-222-PL:1; BC Cribs Distribution Line**Code:** 200-E-222-PL:2**Names:** 200-E-222-PL:2; 216-B-18 By Pass Drain Line

Code: 200-E-222-PL:1**Classification:** Accepted

Names: 200-E-222-PL:1; BC Cribs Distribution Line **Reclassification** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: Subsite 1 is the 35.5 centimeter (14 inch) diameter carbon steel distribution line that fed the six BC cribs.

The SubSite is Part Of:

Code: 200-E-222-PL

Names: 200-E-222-PL; Distribution Pipelines from 216-BC-201 Siphon Tank to BC Cribs

Code: 200-E-222-PL:2 **Classification:** Accepted

Names: 200-E-222-PL:2; 216-B-18 By Pass Drain Line **Reclassification** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: Subsite 2 is the 5 centimeter (2 inch) diameter carbon steel by-pass drain line located at the 216-B-18 crib.

The SubSite is Part Of:

Code: 200-E-222-PL

Names: 200-E-222-PL; Distribution Pipelines from 216-BC-201 Siphon Tank to BC Cribs

Code: 200-E-223 **Classification:** Accepted

Names: 200-E-223; BC Pipeline Valve Pit; 200-E-114-PL Valve Pit **Reclassification** None

Type: Valve Pit **Start Date:** 1/1/1955

Status: Inactive **End Date:**

Description: The waste site is a concrete valve pit associated with the 200-E-114-PL pipeline. In 2001 it was surrounded with posts and chain and posted with radiological warning signs. In 2010, it was sealed and surface stabilized. It was reposted with Underground Radioactive Material Area signs.

Location: The valve pit is located north of 7th Street and east of the 216-B-59 basin.

Related Sites/ Structures: The valve pit is associated with the 200-E-114-PL pipeline.

Process Description: The valve pit regulated flow of the Uranium Recovery Process waste being transferred to the BC Cribs and Trenches. The valve pit contains six iron gate valves. The entire scavenging mission necessitated the construction of the transfer system using pipelines 2805-E1, 2805-E2, 2805-E3 and 2805-E4 (sitecode 200-E-114-PL). The entire system can be traced on the series of H-2-2900 thru 2909. The valve box allowed waste to move north to the BY cribs or south to the BC cribs.

Approximately 31 million gallons of supernate was discharged through the pipelines within this valve pit between 1956 and 1958. There is no record of releases at the valve pit or modifications to the valve pit in the historical record.

Code: 200-E-224-PL **Classification:** Accepted

Names: 200-E-224-PL; Line V027; Pipeline from 241-A-151 Diversion Box Drain Line to 241-A-302A Catch Tank **Reclassification:** None

Type: Encased Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 9 centimeter (3.5 inch) diameter, stainless steel drain line that is encased in concrete.

Location: The 241-A-151 diversion box and 241-A-302A catch tank are located on the south side of the PUREX facility. The drain line extends between the two structures.

Related Sites/ Structures: The drain line is associated with the 241-A-151 Diversion Box and the 241-A-302A catch tank.

Code: 200-E-225-PL **Classification:** Accepted

Names: 200-E-225-PL; Line V720; Transfer Line from 241-AR-151 Diversion Box to 241-AY-102 Tank **Reclassification:** None

Type: Direct Buried Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 7.6 centimeter (3 inch) diameter stainless steel pipe encased within a 15 centimeter (6 inch) diameter pipe.

Location: The line extends from the 241-AR-151 Diversion Box, north of the 244-AR Vault facility to the 241-AY-102 tank. It crosses under Buffalo Ave.

Related Sites/ Structures: The pipeline is associated with the 241-AR-151 diversion box and the 241-AY-102 tank.

Code: 200-E-226-PL **Classification:** Accepted

Names: 200-E-226-PL; Promethium Transfer Line; Transfer Line from 221-B to 241-C-154; V743 **Reclassification:** None

Type: Direct Buried Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 5 centimeter (2 inch) diameter stainless steel (promethium) transfer line.

Location: The pipeline extends from the south side of 221-B (Cell 8) to the Hot Semiworks 241-C-154 Diversion Box. The line crosses under Baltimore Ave. and turns south crossing under 7th Street. The line runs eastward paralleling the 200-E-111-PL pipeline, just north of 200-E-111-PL. The line crosses through the 209-E fence and terminates at the 241-C-154 Diversion Box.

Related Sites/ Structures: The pipeline is associated with B Plant operations, Hot Semi Works operations and 241-C-154 Diversion Box.

Process Description: The pipeline transferred radioactive promethium solutions from 221-B to 201-C.

Code: 200-E-227-PL **Classification:** Accepted

Names: 200-E-227-PL; Lines 4005/810, 4015/814 and 4019/817; Transfer Lines Between 244-AR Vault Facility and 241-AX-151 Diversion Box **Reclassification** None

Type: Encased Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground concrete encasement that contains two 7.6 centimeter (3 inch) diameter stainless steel pipes and one 10 centimeter (4 inch) diameter stainless steel pipe.

Location: The transfer lines extend southward from 244-AR Vault to 241-AX-151 Diversion Box, west of Buffalo Ave.

Related Sites/ Structures: The pipelines are associated with the 244-AR Vault and the 241-AX-151 Diversion Box.

Code: 200-E-228-PL **Classification:** Accepted

Names: 200-E-228-PL; Drain Lines from 241-ER-151 Diversion Box to 241-ER-311 and 241-ER-311A Catch Tanks; Lines V224, V226 and V226-1 **Reclassification** None

Type: Direct Buried Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is three underground drain lines that connect the 241-ER-151 Diversion Box to the 241-ER-311 and 241-ER-311A Catch Tanks. Line V224 is a 7.6 centimeter (3 inch) diameter stainless steel line. Lines V226 and V226-1 are 10 centimeter (4 inch) diameter stainless steel lines.

Location: The pipelines are located southwest of B Plant, west of Atlanta Ave., inside the 241-ER-151 Diversion Box chain link fence.

Related Sites/ Structures: The lines are associated with the 241-ER-151 Diversion Box, 241-ER-311 and 241-ER-311A Catch Tanks.

This Site has the Following SubSites:

Code: 200-E-228-PL:1

Names: 200-E-228-PL:1; Line V224

Code: 200-E-228-PL:2

Names: 200-E-228-PL:2; Line V226

Code: 200-E-228-PL:3

Names: 200-E-228-PL:3; Line V226-1

Code: 200-E-228-PL:1 **Classification:** Accepted

Names: 200-E-228-PL:1; Line V224 **Reclassification** None

Type: Direct Buried Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: Subsite 1 is line V224 that extends from the west end of the 241-ER-151 diversion box to the west end of the 241-ER-311 catch tank. The 7.6 centimeter (3inch) line is reduced to a 5 centimeter (2 inch) diameter line where it was extended from the original catch tank to the replacement catch tank.

The SubSite is Part Of:

Code: 200-E-228-PL

Names: 200-E-228-PL; Drain Lines from 241-ER-151 Diversion Box to 241-ER-311 and 241-ER-311A Catch Tanks; Lines V224, V226 and V226-1

Code: 200-E-228-PL:2

Classification: Accepted

Names: 200-E-228-PL:2; Line V226

Reclassification: None

Type: Direct Buried Tank Farm Pipeline

Start Date:

Status: Inactive

End Date:

Description: Subsite 2 is line V226 that extends from the 241-ER-151 Diversion Box to a point east of the center of the 241-ER-311A and 241-ER-311 Catch Tanks.

The SubSite is Part Of:

Code: 200-E-228-PL

Names: 200-E-228-PL; Drain Lines from 241-ER-151 Diversion Box to 241-ER-311 and 241-ER-311A Catch Tanks; Lines V224, V226 and V226-1

Code: 200-E-228-PL:3

Classification: Accepted

Names: 200-E-228-PL:3; Line V226-1

Reclassification: None

Type: Direct Buried Tank Farm Pipeline

Start Date:

Status: Inactive

End Date:

Description: Subsite 3 is line V226-1 that extends from the 241-ER-151 Diversion Box to a point west of the center of the 241-ER-311A and 241-ER-311 Catch Tanks.

The SubSite is Part Of:

Code: 200-E-228-PL

Names: 200-E-228-PL; Drain Lines from 241-ER-151 Diversion Box to 241-ER-311 and 241-ER-311A Catch Tanks; Lines V224, V226 and V226-1

Code: 200-E-229-PL

Classification: Accepted

Names: 200-E-229-PL; Line SN-650; Transfer Line Between tank 241-AP-102 and 241-A-B Valve Pit

Reclassification: None

Type: Direct Buried Tank Farm Pipeline

Start Date:

Status: Inactive

End Date:

Description: The waste site is an underground, 7.6 centimeter (3 inch) diameter stainless steel line that is double encased within a 15 centimeter (6 inch) diameter pipe.

Location: The line extends north out of the 241-AP Tank Farm. It crosses under 4th Street and travels east on the north side of 4th Street. The line turns north on the west side of the 242-A Evaporator. The line terminates at the 241-A-B Valve Pit, inside the 241-A Tank Farm.

Related Sites/ Structures: The pipeline is associated with the 241-AP-102 tank and the 241-A-B valve pit.

Code: 200-E-230-PL **Classification:** Accepted
Names: 200-E-230-PL; Pipeline from 292-B to 216-B-4 Reverse Well **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is an underground, 15 centimeter (6 inch) diameter, vitrified clay pipe that fed the 216-B-4 Reverse well.

Location: The pipeline is located southeast of B Plant, extending north from the 292-B building.

Related Sites/ Structures: The pipeline is associated with the 292-B building and the 216-B-4 well.

Process Description: The pipeline transferred floor drainage from 292-B to 216-B-4.

Code: 200-E-231-PL **Classification:** Accepted
Names: 200-E-231-PL; Pipeline from 202-A to 216-A-45 crib **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is an underground, 20 centimeter (8 inch) diameter fiberglass pipeline that fed the 216-A-45 crib.

Location: The pipeline is located south of the PUREX security fence and south of the 216-A-10 crib.

Related Sites/ Structures: The pipeline is associated with the 216-A-45 crib and the 216-A-10 pipeline (200-E-192-PL).

Process Description: The 216-A-45 crib was built to replace the 216-A-10 crib.

Code: 200-E-232-PL **Classification:** Accepted
Names: 200-E-232-PL; Pipeline from 207-A Basins to 216-A-30 and 216-A-37-1 Cribs **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is an underground, 10 centimeter (4 inch) diameter, cast iron pipeline that fed the 216-A-37-1 crib through a distribution box. A 20 centimeter (8 inch) cement pipe extends from the 216-A-37-1 crib distribution box to the 216-A-30 crib distribution box. (see subsite 2).

Location: The pipeline is located northeast of the PUREX facility. It extends from the 207-A Basins to the 216-A-37-1 distribution box.

Related Sites/ Structures: The pipeline is associated with the 216-A-37-1 and 216-A-30 crib distribution boxes.

This Site has the Following SubSites:

Code: 200-E-232-PL:1

Names: 200-E-232-PL:1; Cast Iron Pipeline from 207-A to 216-A-37-1 Distribution Box

Code: 200-E-232-PL:2

Names: 200-E-232-PL:2; Pipeline from 216-A-37-1 Distribution Box to 216-A-30 Crib

Code: 200-E-232-PL:1

Classification: Accepted

Names: 200-E-232-PL:1; Cast Iron Pipeline from 207-A to 216-A-37-1 Distribution Box

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

The SubSite is Part Of:

Code: 200-E-232-PL

Names: 200-E-232-PL; Pipeline from 207-A Basins to 216-A-30 and 216-A-37-1 Cribs

Code: 200-E-232-PL:2

Classification: Accepted

Names: 200-E-232-PL:2; Pipeline from 216-A-37-1 Distribution Box to 216-A-30 Crib

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This is a 20 centimeter (8 inch) diameter cement pipe.

The SubSite is Part Of:

Code: 200-E-232-PL

Names: 200-E-232-PL; Pipeline from 207-A Basins to 216-A-30 and 216-A-37-1 Cribs

Code: 200-E-233-PL

Classification: Accepted

Names: 200-E-233-PL; Pipeline from 216-A-30 Crib Distribution Box to the 216-A-37-2 Crib Distribution Box

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is an underground, 20 centimeter (8 inch) diameter cast iron pipeline that connected the 216-A-30 crib to the 216-A-37-2 crib distribution box.

Location: The pipeline is located east of the 200 East Area fence, southeast of the PUREX facility.

Related Sites/ Structures: The pipeline is associated with the 216-A-30 and 216-A-37-2 cribs.

Code: 200-E-234-PL **Classification:** Accepted
Names: 200-E-234-PL; Lines 300, 501, 505, and 557; Pipelines from 242-A Evaporator Building to the 207-A Basins **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is three underground, 10 centimeter (4 inch) diameter, carbon steel pipelines buried together in the same soil trench. They terminate at the 207-A pump pit. A fourth line (505) is a spare line that is stubbed off west of the 207-A basins (see subsite 2).

Location: The pipelines extend eastward from the 242-A Evaporator Building to the 207-A Pump Pit. They are located north of 4th Street and cross under Canton Ave.

Related Sites/ Structures: The pipelines are associated with the 242-A Evaporator building and the 207-A North and South Basins.

Process Description: The lines transported secondary waste from the 242-A Evaporator to the 207-A Basins.

This Site has the Following SubSites:

Code: 200-E-234-PL:1
Names: 200-E-234-PL:1; Lines 300, 501, and 557 (alias DR-300)
Code: 200-E-234-PL:2
Names: 200-E-234-PL:2; Line 505 (Stub)

Code: 200-E-234-PL:1 **Classification:** Accepted
Names: 200-E-234-PL:1; Lines 300, 501, and 557 (alias DR-300) **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The subsite is three, 10 centimeter (4 inch) diameter, carbon steel pipelines buried together in the same soil trench, terminating at the 207-A pump pit.

Process Description: Line 300 (alias DR-300) is the effluent return line. It connects to tank 241-A-350, inside the 241-A Tank Farm.

The SubSite is Part Of:

Code: 200-E-234-PL
Names: 200-E-234-PL; Lines 300, 501, 505, and 557; Pipelines from 242-A Evaporator Building to the 207-A Basins

Code: 200-E-234-PL:2 **Classification:** Accepted
Names: 200-E-234-PL:2; Line 505 (Stub) **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The subsite is a 10 centimeter (4 inch) diameter carbon steel spare pipeline. It is stubbed off

west of the 207-A Retention Basins at the pump pit.

The SubSite is Part Of:

Code: 200-E-234-PL

Names: 200-E-234-PL; Lines 300, 501, 505, and 557; Pipelines from 242-A Evaporator Building to the 207-A Basins

Code: 200-E-237-PL

Classification: Accepted (Proposed)

Names: 200-E-237-PL; 2904-E-24; Line 2904-E-1; Pipeline to 200 East Powerhouse Ditch and Pipeline from Powerhouse Ditch to 216-B-3 Ditches

Reclassification: None

Type: Process Sewer

Start Date:

Status: Active

End Date:

Description: The waste site is the 106 centimeter (42 inch) diameter reinforced concrete pipe and vitrified clay pipe that feeds the powerhouse ditch and the 76 centimeter (30 inch) diameter corrugated metal pipe that drained the powerhouse ditch to the B Pond system. The piping was later reused to feed the TEDF system. The mapped detail of this piping system includes the feeder pipes from the 284-E Powerhouse and the 282-E water reservoir. The 284-E Powerhouse has been demolished.

The waste site was divided into two subsites; the concrete pipe at the head end of the powerhouse ditch and the corrugated metal pipe at the distal end of the powerhouse ditch that connected to the 216-B-3 ditch.

Location: The pipeline is located north of 4th Street and south of 7th Street, east of Baltimore Ave. in 200 East Area.

Related Sites/ Structures: The pipeline is associated with the 200-E Power House ditch, 200-E-155-PL and the TEDF system pipeline (600-291-PL).

Process Description: Drainage from the 282-E reservoir and the 284-E Powerhouse (now demolished) has been sent to the 200-E Powerhouse Ditch via the reinforced concrete portion of this pipeline. The powerhouse ditch is unlined and allows the effluent to percolate into the soil of the ditch. The ditch drainage was conveyed to the 216-B-3 ditches and ponds via the corrugated metal pipe at the distal of the powerhouse ditch.

A small diameter pipeline from 241-C tank farm joined the corrugated metal pipe (see 200-E-155-PL). 200-E-155-PL has now been isolated at the 241-C-03A pump pit. Later this effluent was diverted to the TEDF system by reusing the existing powerhouse ditch and piping.

In 2010, discharge from 282E, 282EC and 283E continued to use this pipeline for relatively small amounts of discharge.

This Site has the Following SubSites:

Code: 200-E-237-PL:1

Names: 200-E-237-PL:1; Ditch Feed Pipe

Code: 200-E-237-PL:2

Names: 200-E-237-PL:2; Ditch Drain Line

Code: 200-E-237-PL:1

Classification: Accepted (Proposed)

Description: The waste site is an underground, 20 centimeter (8 inch) diameter, stainless steel pipeline that fed the 216-A-5 crib.

Location: The pipeline to the 216-A-5 crib is located south of the PUREX facility. It extends south from the 216-A-5 Sample Pit #4.

Related Sites/ Structures: The pipeline is associated with Sample Pit #4 and the 216-A-5 crib.

Code: 200-E-240-PL **Classification:** Accepted

Names: 200-E-240-PL; Pipeline from Valve Pit West of Sample Pit 4 to the 216-A-38-1 Crib **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 20 centimeter (8 inch) diameter, stainless steel pipeline that fed the 216-A-38-1 crib.

Location: The pipeline to the 216-A-38-1 crib is located south of the PUREX facility. It extends west and southwest of the 216-A-5 Sample Pit #4.

Related Sites/ Structures: The pipeline is associated with the 216-A-38-1 crib.

Code: 200-E-241-PL **Classification:** Accepted

Names: 200-E-241-PL; Lines 7717 and 7718; Pipeline from 200-E-58 Neutralization Tank to the 216-A-5 Sample Pit #4 **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is several 20 centimeter (8 inch) diameter stainless steel pipelines that carried waste from PUREX to the neutralization tank (sitecode 200-E-58). The neutralized waste continued to the 216-A-5 Sample Pit #4. The pipeline was divided into three subsites. A by pass line around the #4 sampler pit was added later (see Subsite 2).

Location: The pipeline is located south of PUREX and north of the 216-A-5 Crib.

Related Sites/ Structures: The pipeline is associated with the 200-E-58 Neutralization Tank, and Sample Pit #4.

This Site has the Following SubSites:

Code: 200-E-241-PL:1

Names: 200-E-241-PL:1; Pipeline Between 200-E-58 (Neutralization Tank) and Sample Pit #4

Code: 200-E-241-PL:2

Names: 200-E-241-PL:2; Bypass Piping Around Sampler

Code: 200-E-241-PL:3

Names: 200-E-241-PL:3; Lines 7717 and 7718 from 202-A to 200-E-58 (Neutralization Tank)

Code: 200-E-241-PL:1 **Classification:** Accepted
Names: 200-E-241-PL:1; Pipeline Between 200-E-58 (Neutralization Tank) and Sample Pit #4 **Reclassification** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: Subsite 1 is the 8 inch diameter, schedule 40 stainless steel piping between the 200-E-58 neutralization tank and the Sampler Pit #4.

The SubSite is Part Of:

Code: 200-E-241-PL
Names: 200-E-241-PL; Lines 7717 and 7718; Pipeline from 200-E-58 Neutralization Tank to the 216-A-5 Sample Pit #4

Code: 200-E-241-PL:2 **Classification:** Accepted
Names: 200-E-241-PL:2; Bypass Piping Around Sampler **Reclassification** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The subsite 2 is the 8 inch diameter, schedule 40 bypass pipeline around the proportional sample pit number 4.

The SubSite is Part Of:

Code: 200-E-241-PL
Names: 200-E-241-PL; Lines 7717 and 7718; Pipeline from 200-E-58 Neutralization Tank to the 216-A-5 Sample Pit #4

Code: 200-E-241-PL:3 **Classification:** Accepted
Names: 200-E-241-PL:3; Lines 7717 and 7718 from 202-A to 200-E-58 (Neutralization Tank) **Reclassification** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: Subsite 3 is two pipelines (lines 7717 and 7718) that extend from the PUREX building to the 200-E-58 Neutralization Pit. Each is an 8 inch diameter stainless steel line that fed the neutralization tank.

The SubSite is Part Of:

Code: 200-E-241-PL
Names: 200-E-241-PL; Lines 7717 and 7718; Pipeline from 200-E-58 Neutralization Tank to the 216-A-5 Sample Pit #4

Code: 200-E-242-PL **Classification:** Accepted
Names: 200-E-242-PL; Pipeline from 216-A-5 Sample Pit #4 to 216-A-15 French Drain **Reclassification** None
Type: Radioactive Process Sewer **Start Date:**

Status: Inactive

End Date:

Description: The waste site is an underground, 10 centimeter (4 inch) diameter, stainless steel pipeline that fed the 216-A-15 French Drain.

Location: The pipeline is located south of PUREX and east of the 216-A-5 Sample Pit #4.

Related Sites/ Structures: The pipeline is associated with Sample Pit #4 and the 216-A-15 French Drain.

Code: 200-E-243-PL

Classification: Accepted

Names: 200-E-243-PL; Pipeline from 291-B-1 Stack to the 216-B-13 French Drain

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is an underground, 7.6 centimeter (3 inch) diameter stainless steel pipeline that fed the 216-B-13 french drain.

Location: The pipeline is located south of the 221-B facility and north of the 291-B stack.

Related Sites/ Structures: The pipeline is associated with the 291-B stack and the 216-B-13 french drain.

Code: 200-E-244-PL

Classification: Accepted

Names: 200-E-244-PL; Pipeline from 201-C Valve Pit to 241-CX-70

Reclassification: None

Type: Encased Transfer Piping

Start Date:

Status: Inactive

End Date:

Description: The waste site is an underground, 5 centimeter diameter (2 inch) stainless steel pipeline that fed the 241-CX-70 tank. A portion of the pipeline, near the 201-C building, is inside a 46 centimeter (18 inch) diameter corrugated pipe encasement. The pipeline to the 241-CX-72 tank (sitecode 200-E-246-PL), is buried along side of the pipeline to 241-CX-70 tank.

Location: The pipeline is located southeast of the 201-C building. It extends to the 241-CX-70 tank.

Related Sites/ Structures: The pipeline is associated with 200-E-41 Stabilized Area, 200-E-246-PL, the Hot Semiworks Valve Pit (HSVP) and the 241-CX-70 tank.

Code: 200-E-245-PL

Classification: Accepted

Names: 200-E-245-PL; Pipeline from 201-C Hot Shop to 241-CX-71

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is an underground, 5 centimeter (2 inch) diameter stainless steel pipeline that fed the 241-CX-71 tank.

Location: The pipeline is located south of the 201-C building.

Related Sites/ Structures: The pipeline is associated with the 201-C facility and the 241-CX-71 tank.

Code: 200-E-246-PL **Classification:** Accepted
Names: 200-E-246-PL; Pipeline from 201-C Valve Pit to 241-CX-72 **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is an underground, 5 centimeter diameter (2 inch) stainless steel pipeline that fed the 241-CX-72 tank. A portion of the pipeline, near the 201-C building, is inside a 46 centimeter (18 inch) diameter corrugated pipe encasement. The pipeline to the 241-CX-70 tank (sitecode 200-E-244-PL), is buried along side of the pipeline to 241-CX-72 tank.

Location: The pipeline is located southeast of the 201-C building. It extends to the 241-CX-72 tank.

Related Sites/ Structures: The pipeline is associated with 200-E-41 Stabilized Area, 200-E-244-PL, the Hot Semiworks Valve Pit (HSVP) and the 241-CX-72 tank.

Code: 200-E-247-PL **Classification:** Accepted
Names: 200-E-247-PL; Pipelines from 209-E to the 209-E-WS-2 French Drain **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is two underground pipelines from the 209-E facility that fed the 209-E-WS-2 french drain. One line is constructed of 2.5 centimeter (1 inch) diameter carbon steel. The other is constructed of 5 centimeter (2 inch) diameter stainless steel.

Location: The pipelines are located on the east side of the 209-E building.

Related Sites/ Structures: The pipelines are associated with the 209-E laboratory building and the 209-E-WS-2 french drain.

This Site has the Following SubSites:

Code: 200-E-247-PL:1
Names: 200-E-247-PL:1; 1-Inch Carbon Steel Pipeline
Code: 200-E-247-PL:2
Names: 200-E-247-PL:2; 2-Inch Stainless Steel Pipeline

Code: 200-E-247-PL:1 **Classification:** Accepted
Names: 200-E-247-PL:1; 1-Inch Carbon Steel Pipeline **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

The SubSite is Part Of:

Code: 200-E-247-PL
Names: 200-E-247-PL; Pipelines from 209-E to the 209-E-WS-2 French Drain

Code: 200-E-247-PL:2 **Classification:** Accepted
Names: 200-E-247-PL:2; 2-Inch Stainless Steel Pipeline **Reclassification** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

The SubSite is Part Of:

Code: 200-E-247-PL
Names: 200-E-247-PL; Pipelines from 209-E to the 209-E-WS-2 French Drain

Code: 200-E-248-PL **Classification:** Accepted
Names: 200-E-248-PL; Pipelines form 209-E to the 209-E-WS-3 Valve Pit **Reclassification** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is two underground, 5 centimeter (2 inch) diameter stainless steel pipelines connecting the laboratory building to the valve pit structure.

Location: The pipelines extend south from the 209-E building to the 209-E-WS-3 valve pit.

Related Sites/ Structures: The pipelines are associated with the 209-E laboratory building and the 209-E-WS-3 valve pit.

This Site has the Following SubSites:

Code: 200-E-248-PL:1
Names: 200-E-248-PL:1; Western Line from 209-E to Valve Pit

Code: 200-E-248-PL:2
Names: 200-E-248-PL:2; Eastern Line from 209-E to Valve Pit

Code: 200-E-248-PL:1 **Classification:** Accepted
Names: 200-E-248-PL:1; Western Line from 209-E to Valve Pit **Reclassification** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

The SubSite is Part Of:

Code: 200-E-248-PL
Names: 200-E-248-PL; Pipelines form 209-E to the 209-E-WS-3 Valve Pit

Code: 200-E-248-PL:2 **Classification:** Accepted
Names: 200-E-248-PL:2; Eastern Line from 209-E to Valve Pit **Reclassification** None

Status: Inactive

End Date:

Description: The drain line from the valve box is a 1.9 centimeter (0.75 inch) diameter carbon steel line.

The SubSite is Part Of:

Code: 200-E-249-PL

Names: 200-E-249-PL; Pipelines from 209-E to 200-E-4 French Drain

Code: 200-E-250-PL

Classification: Accepted

Names: 200-E-250-PL; Pipeline from 2704-C to 2704-C-WS-1 Quench Tank

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is an underground, 2.5 centimeter (1 inch) diameter carbon steel line that extended from the south side of the 2704-C building to the 2704-C quench tank.

Location: The pipeline is located south of 7th Street, within the 200-E-41 Stabilized Area.

Related Sites/ Structures: The pipeline is associated with the demolished 2704-C building and the 2704-C-WS-1 quench tank.

Code: 200-E-251-PL

Classification: Accepted

Names: 200-E-251-PL; Pipeline from 291-C Stack to 216-C-2 Reverse Well

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is an underground, 10 centimeter (4 inch) diameter carbon steel pipeline that connected the 291-C stack to the 216-C-2 reverse well.

Location: The pipeline is located south of 7th Street, in the Hot Semiworks Stabilized Area (see 200-E-41).

Related Sites/ Structures: The pipeline is associated with the 291-C stack, the 216-C-2 reverse well and the 200-E-41 stabilized area.

Code: 200-E-252-PL

Classification: Accepted

Names: 200-E-252-PL; Pipeline from 291-C Air Filter Building to 216-C-2 Reverse Well

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is an underground, 5 centimeter (2 inch) diameter cast iron pipeline from the 291-C Air Filter building to the 216-C-2 reverse well. Part of this line lies beneath the 200-E-251-PL pipeline.

Location: The pipeline is located south of 7th Street in the 200-E-41 Stabilized Area.

Related Sites/ Structures: The pipeline is associated with the 291-C filter building, the 216-C-2 stack and the 200-E-41 Stabilized Area.

Code: 200-E-253-PL **Classification:** Accepted

Names: 200-E-253-PL; Pipeline from 202-A to 216-A-36A and 216-A-36B Cribs **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 15 centimeter (6 inch) diameter stainless steel pipeline that connected the ASD Valve Pit and 295-A Sample Pit with the 216-A-36A and 216-A-36B cribs. When the 216-A-36A crib was extended to create the 216-A-36B crib, the distribution pipe was lengthened by inserting a 12 centimeter (5 inch) diameter pipe through the original 15 centimeter (6 inch) diameter crib pipe.

Location: The pipeline is located south of the PUREX facility.

Release Description: UPR-200-E-39 is described as a release that occurred on February 6, 1968. Pressurized ammonia scrubber liquid was found to be spewing from the vent filter at the 216-A-36B Crib Sampling Shack (295-A). The contaminated ammonia scrubber water erupted through the vent and filter and onto the ground around the outside of the sample shack. Approximately 60.4 square meters (650 square feet) of ground and blacktop was affected. Contamination levels ranged from 20 to 450 millirad/hour. The cause was determined to be that the export pressure was too high, resulting in back-pressure through the vent.

Related Sites/ Structures: The pipeline is associated with the 295-A Sample Building and the 216-A-36A and 216-A-36B cribs.

Process Description: The 216-A-36A portion of the crib was terminated in March 1966. The existing pipeline was extended to the 216-A-36B portion of the crib by inserting a 12 centimeter (5 inch) diameter pipe inside the existing 15 centimeter (6 inch) diameter distribution pipe. A 29 meter (95 foot) concrete dam was placed between the 216-A-36A and 216-A-36B crib sections.

Code: 200-E-254-PL **Classification:** Accepted

Names: 200-E-254-PL; Pipeline from 209-E to 216-C-9 Pond **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 10 centimeter (4 inch) diameter pipeline that fed the 216-C-9 Pond. Part of the line is constructed of vitrified clay and part is cast iron.

Location: The pipeline runs north and south, between the 209-E building and the 216-C-9 Pond site. The pipeline crosses under 7th Street.

Related Sites/ Structures: The pipeline is associated with the 209-E Criticality Lab facility and the 216-C-9 Pond.

Code: 200-E-255-PL **Classification:** Accepted

Names: 200-E-255-PL; Pipeline Connecting 216-C-9 **Reclassification:** None

Pond to Pipeline 200-E-169-PL

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is an underground, 15 centimeter (6 inch) diameter vitrified clay pipe that fed the 216-C-9 Pond.

Location: The pipeline is located north of the 276-C building. It runs north and south and runs under 7th Street.

Related Sites/ Structures: This line is associated with the 216-C-9 Pond and the 200-E-169-PL pipeline.

Code: 200-E-256-PL

Classification: Accepted

Names: 200-E-256-PL; Pipelines from 201-C (South Side) to 216-C-9 Pond

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site majority of the waste site is an underground, 15 centimeter (6 inch) diameter vitrified clay pipe from the demolished 201-C building to the 216-C-9 Pond. Two 10 centimeter (4 inch) diameter saran lined steel pipes extend from the south side of 201-C and connect to the 15 centimeter VCP line. A drain line from the 241-CX-71 vault ties into this line with a "Y" connection.

Location: The pipeline(s) extend south from the demolished 201-C building. The line extends east and north to discharge into the 216-C-9 Pond. The pipeline crosses under 7th Street.

Related Sites/ Structures: The pipeline is associated with 201-C and 216-C-9 Pond.

Code: 200-E-257-PL

Classification: Accepted

Names: 200-E-257-PL; Pipeline from 201-C (East Side) to 216-C-9 Pond

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is an underground, 7.6 centimeter (3 inch) diameter stainless steel pipeline that fed the 216-C-9 Pond.

Location: The pipeline is located northeast of the demolished 201-C building. It runs north and south and runs under 7th Street.

Related Sites/ Structures: The pipeline is associated with 201-C and 216-C-9 Pond.

Code: 200-E-258-PL

Classification: Accepted

Names: 200-E-258-PL; 216-C-9 Pond Lobe Distribution Piping

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is an underground carbon steel pipeline that diverted effluent to the various sections of the 216-C-9 Pond. The majority of the piping system is constructed of 15 centimeter (6 inch) diameter carbon steel pipe.

Location: The pipeline runs east and west along the north side of 7th Street. Four distribution lines extend to various lobes of the 216-C-9 Pond.

**Related Sites/
Structures:** The pipelines are associated with the 216-C-9 Pond.

**Process
Description:** The 216-C-9 Pond (old 221-C facility excavation) was divided into sections with dikes. Piping was arranged to provide three discharge points, one to each section.

Code: 200-E-259-PL

Classification: Accepted

Names: 200-E-259-PL; Pipeline from 291-C Fan House to 216-C-9 Pond

Reclassification None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is an underground, 5 centimeter (2 inch) diameter carbon steel pipeline that fed the 216-C-9 Pond.

Location: The pipeline is located northeast of the demolished 201-C building. It extended north from the demolished 291-C Fan House to the 216-C-9 Pond. The pipeline crosses under 7th Street.

**Related Sites/
Structures:** The pipeline is associated with the 291-C stack operation and the 216-C-9 Pond.

Code: 200-E-260-PL

Classification: Accepted

Names: 200-E-260-PL; Line 8824A; Steam Condensate By-Pass Line from PUREX to 216-A-30

Reclassification None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is an underground, 20 centimeter (8 inch) diameter carbon steel pipeline from PUREX to the 216-A-30 crib.

Location: The pipeline extends east from the PUREX facility, beyond the 200 East Area fence and terminates at the head end of the 216-A-30 crib.

**Related Sites/
Structures:** The pipeline is associated with PUREX and the 216-A-30 crib.

**Process
Description:** The pipeline was used as a steam condensate bypass line.

Code: 200-E-261-PL

Classification: Accepted

Names: 200-E-261-PL; Effluent Recycle Line from 216-A-42 Basin to PUREX **Reclassification** None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is an underground, 10 centimeter (4 inch) diameter cast iron pipeline. The pipeline returned contaminated effluent from the 216-A-42 Basin back to the PUREX facility.

Location: The pipeline extends from the 216-A-42 basin, located south of 241-AP Tank Farm, to the 202-A (PUREX) facility.

Related Sites/ Structures: The pipeline is associated with the 216-A-42 Basin and the 216-A-42A Pump Station.

Code: 200-E-262-PL

Classification: Accepted

Names: 200-E-262-PL; 216-A-42A Pump Station; 216-A-42B Valve Box and 216-A-42C Diversion Box; Pipelines Associated with 216-A-42 Basin **Reclassification** None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is an underground, 10 centimeter (4 inch) diameter cast iron pipeline that transferred effluent out of the 216-A-42 Retention Basin.

Location: The 216-A-42 Basin is located south of the 241-AP Tank Farm. The pipelines and 216-A-42A Pump Station are on the west side of the 216-A-42 Basin.

Related Sites/ Structures: The pipelines are associated with the 216-A-42 retention basin, the 216-A-42A pump station, the 216-A-42B valve box and the 216-A-42C diverter station.

Process Description: The 216-A-42 Retention Basin was built to hold cooling water or steam condensate that was contaminated above standard release limits and prevent its disposal to the Gable and B Pond systems. After the retained effluent contents were analyzed, a built-in recovery system provided the capability of pumping solutions back into the PUREX facility for reprocessing (see sitecode 200-E-261-PL) or to cribs for disposal.

Code: 200-E-263-PL

Classification: Accepted

Names: 200-E-263-PL; 216-A-42 Basin Pipeline to 216-A-42C Diversion Box **Reclassification** None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is an underground, 20 centimeter (8 inch) diameter cast iron pipeline that connected the 216-A-42 Retention Basin to the 216-A-42C Diversion Box.

Location: The pipeline is located southeast of the 241-AP Tank Farm. The pipeline extends from the south end of the 216-A-42 Basin to the 216-A-42C Diversion Box.

Related Sites/ Structures: The pipeline is associated with the 216-A-42 basin, the 216-A-42C diversion box and the 200-E-113-PL pipeline.

Code: 200-E-264-PL **Classification:** Accepted

Names: 200-E-264-PL; Pipeline from 242-B Evaporator Building to 207-B Retention Basin **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 10 centimeter (4 inch) diameter cast iron pipeline that connected the 242-B Evaporator building to the 207-B Retention Basin.

Location: The pipeline is located east of Baltimore Ave. It extends south from the 242-B Evaporator building to the 207-B retention basin.

Release Description: UPR-200-E-79 describes a release that occurred in June 1953. Five leaks were discovered in the waste line that runs from 242-B to 207-B. Contamination levels up to 2,500 counts per minute were measured at the points of emission of water from the ground.

Related Sites/ Structures: The pipeline is associated with 242-B Evaporator, 207-B Retention Basin and UPR-200-E-79.

Code: 200-E-265-PL **Classification:** Accepted

Names: 200-E-265-PL; 241-BY and 241-BX Tank Farm Cooling Water Pipeline to 207-B Retention Basin **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 10 centimeter (4 inch) diameter carbon steel pipeline that transferred In-Tank Solidification process cooling water to the 207-B Retention Basin. A new pipeline segment was added that by passed the retention basin and connected to the B Ditches.

Location: Portions of the pipeline are located inside the 241-B, BX and BY tank farms. It crosses under Baltimore Ave. One segment of the pipeline connects with the west side of the 207-B Retention Basin and one segment connects with the east side of the 207-B Retention Basin.

Related Sites/ Structures: The pipeline is associated with the ITS process in 241-BY Tank Farm, the In Tank Solidification Systems (ITS 1 and ITS 2) and the 207-B Retention Basin.

Process Description: The pipeline carried cooling water from the In-Tank Solidification (ITS) process to the 207-B retention basin.

This Site has the Following SubSites:

Code: 200-E-265-PL:1

Names: 200-E-265-PL:1; Original Pipeline from 241-BY Tank Farm to the West Side of 207-B Retention Basin

Code: 200-E-265-PL:2

Names: 200-E-265-PL:2; Relocated Section of 4-Inch Pipe Inside a 6-Inch Pipe Created to Bypass a Broken Section of Pipeline

Code: 200-E-265-PL:3

Names: 200-E-265-PL:3; 4-Inch Retention Basin Bypass Line (to B Ditches)

Code: 200-E-265-PL:1 **Classification:** Accepted

Names: 200-E-265-PL:1; Original Pipeline from 241-BY Tank Farm to the West Side of 207-B Retention Basin

Reclassification None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

The SubSite is Part Of:

Code: 200-E-265-PL

Names: 200-E-265-PL; 241-BY and 241-BX Tank Farm Cooling Water Pipeline to 207-B Retention Basin

Code: 200-E-265-PL:2

Classification: Accepted

Names: 200-E-265-PL:2; Relocated Section of 4-Inch Pipe Inside a 6-Inch Pipe Created to Bypass a Broken Section of Pipeline

Reclassification None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

The SubSite is Part Of:

Code: 200-E-265-PL

Names: 200-E-265-PL; 241-BY and 241-BX Tank Farm Cooling Water Pipeline to 207-B Retention Basin

Code: 200-E-265-PL:3

Classification: Accepted

Names: 200-E-265-PL:3; 4-Inch Retention Basin Bypass Line (to B Ditches)

Reclassification None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

The SubSite is Part Of:

Code: 200-E-265-PL

Names: 200-E-265-PL; 241-BY and 241-BX Tank Farm Cooling Water Pipeline to 207-B Retention Basin

Code: 200-E-266-PL

Classification: Accepted

Names: 200-E-266-PL; Pipeline from PUREX Trap Pit #1 to 216-A-11 French Drain

Reclassification None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is an underground, 10 centimeter (4 inch) diameter carbon steel pipeline that connected the PUREX Trap Pit #1 to 216-A-11 French Drain.

Location: The pipeline extends south from PUREX Trap Pit #1. It is near the southeast corner of the 202-A building.

Related Sites/ Structures: The pipeline is associated with 216-A-11 french drain.

Code: 200-E-267-PL **Classification:** Accepted
Names: 200-E-267-PL; Pipeline from PUREX Trap Pit #3 to 216-A-12 French Drain **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is an underground, 10 centimeter (4 inch) diameter carbon steel pipeline that connected the PUREX Trap Pit #3 to 216-A-12 French Drain.
Location: The pipeline extends south from Trap Pit #3. It is located near the center of the south side of the 202-A building.
Related Sites/ Structures: The pipeline is associated with 216-A-12 french drain.

Code: 200-E-268-PL **Classification:** Accepted
Names: 200-E-268-PL; Line T073; Pipeline from PUREX Vacuum Cleaner Filter Box to 216-A-14 French Drain **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is an underground, 6 centimeter (1.5 inch) diameter carbon steel pipeline that connected the PUREX Vacuum Cleaning Filter Box to 216-A-14 French Drain.
Location: The pipeline is located south of 202-A and northwest of 291-AE.
Related Sites/ Structures: The pipeline is associated with 216-A-14 french drain.

Code: 200-E-269-PL **Classification:** Accepted
Names: 200-E-269-PL; Pipeline from 291-A Fan Building to 216-A-33 French Drain **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is an underground, 5 centimeter (2 inch) diameter stainless steel pipeline that connected the 291-A Stack Fan House to the 216-A-33 French Drain.
Location: The pipeline is located southeast of the 291-A Fan House. Part of the pipeline is underneath the 291-AE building.
Related Sites/ Structures: The pipeline is associated with 216-A-33 french drain.

Code: 200-E-270-PL **Classification:** Accepted
Names: 200-E-270-PL; Line T022; Pipeline from 291-A Fan Control House to 216-A-26 and 216-A-26A **Reclassification:** None

French Drains

Type: Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** The waste site is an underground, 10 centimeter (4 inch) diameter stainless steel pipeline that fed the 216-A-26 and 216-A-26A French Drains.**Location:** The pipeline is located south of the 202-A building, southwest of the 291-A stack.**Related Sites/ Structures:** The pipeline is associated with 216-A-26 and 216-A-26A french drains and 200-E-196-PL.**Process Description:** The effluent source to the 216-A-26 and 216-A-26A french drains was two floor drains located inside the 291-A Fan Control Building and the 291-A Fan Plenum. This effluent was originally discharged to 216-A-4 crib, but was rerouted to the french drains. The floor drains were plugged by filling with epoxy during the Purex deactivation. A new pipeline, from the 291-A Fan House to the french drains was installed.**Code:** 200-E-271-PL**Classification:** Accepted**Names:** 200-E-271-PL; Line 8823; PUREX Cooling Water Header Pipeline**Reclassification:** None**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** The waste site is an underground pipeline that transferred PUREX cooling water waste to the pond and ditch system. The carbon steel pipeline has several diameters that increase from 40 centimeters (16 inch) to 76 centimeters (30 inch).**Location:** The Cooling Water Header extends along the south side of the PUREX facility. It extends east behind Railroad Tunnel #1. A portion of the pipeline is located under Railroad Tunnel #2. The pipeline terminates at the pump pit south of 241-A-201.**Related Sites/ Structures:** The waste site is associated with feeding the Gable and B pond and ditch systems.**Code:** 200-E-272-PL**Classification:** Accepted**Names:** 200-E-272-PL; Pipeline from 202-A to 216-A-35 French Drain**Reclassification:** None**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** The waste site is an underground, 7.6 centimeter (3 inch) diameter carbon steel pipeline that fed the 216-A-35 french drain.**Location:** The pipeline is located near the southwest corner of the 202-A building. It extends to the 216-A-35 French Drain.**Related Sites/ Structures:** The pipeline is associated with PUREX and the 216-A-35 french drain.

Code: 200-E-273-PL **Classification:** Accepted
Names: 200-E-273-PL; Pipeline from 202-A Cooling Water Header to 216-A-13 French Drain **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is an underground, 7.6 centimeter (3 inch) diameter carbon steel pipeline that fed the 216-A-13 french drain.

Location: The pipeline is located near the southwest corner of the 202-A building.

Related Sites/ Structures: The pipeline is associated with the 216-A-13 french drain and the PUREX Cooling Water Header pipeline (200-E-271-PL).

This Site has the Following SubSites:

Code: 200-E-273-PL:1
Names: 200-E-273-PL:1; Original 3-Inch Diameter CS Pipeline from PUREX to the Cooling Water Header Pipe (200-E-271-PL)
Code: 200-E-273-PL:2
Names: 200-E-273-PL:2; 3-Inch Re-Routed Line to 216-A-13 French Drain

Code: 200-E-273-PL:1 **Classification:** Accepted
Names: 200-E-273-PL:1; Original 3-Inch Diameter CS Pipeline from PUREX to the Cooling Water Header Pipe (200-E-271-PL) **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

The SubSite is Part Of:

Code: 200-E-273-PL
Names: 200-E-273-PL; Pipeline from 202-A Cooling Water Header to 216-A-13 French Drain

Code: 200-E-273-PL:2 **Classification:** Accepted
Names: 200-E-273-PL:2; 3-Inch Re-Routed Line to 216-A-13 French Drain **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

The SubSite is Part Of:

Code: 200-E-273-PL
Names: 200-E-273-PL; Pipeline from 202-A Cooling Water Header to 216-A-13 French Drain

Code: 200-E-274-PL **Classification:** Accepted
Names: 200-E-274-PL; Line 323; Pipeline from 216-A-40 Basin to 244-A Lift Station **Reclassification:** None

Type: Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** The waste site is an underground, 7.6 centimeter (3 inch) diameter carbon steel pipeline that connected the 216-A-40 basin to the 244-A Lift Station.**Location:** The pipeline is located south of 7th Street and west of Buffalo Ave. It is south and east of the 244-A Lift Station.**Related Sites/ Structures:** The pipeline is associated with the 216-A-40 basin, pump pit and the 244-A Lift Station.**Process Description:** The 216-A-40 Basin was built to retain diverted contaminated water from 244-AR Vault. The basin was originally an open, rubber lined trench that was divided into 3 sections. A 0.3 meter (12 inch) diameter schedule 40 distribution pipe ran horizontally through the south end of the unit, 3.7 meters (12 feet) below grade. Collapsible rubber bladders (200,00 gallon capacity) were utilized to contain the contaminated cooling water and steam condensate. Contaminated cooling water and steam condensate from the 244-AR Vault were diverted to the 216-A-40 Retention Basin when the effluent was above standard release limits for the water to be sent to the 216-B-3 or 216-A-25 Ponds. The retention basin bladders failed in 1979 and the unit was removed from service. Although it was not being used, it remained an open basin until 1994. Contamination from inside the open basin affected the surrounding area via wind and animal related contamination migration.

200-E-274-PL (Line 323) was constructed when the 216-A-40 Retention Basin ended its operations in 1979. 200-E-274-PL (Line 323) was the primary line used to transfer waste from the pump pit to the 244-A Lift Station catch tank. During this construction the 200-E-274-PL was connected to the 244-A Lift Station catch tank using a jumper assembly connected to a valve extension.

The diverter was a two-compartment concrete structure with a motor driven diverter valve. Each bladder was equipped with a concrete sump and a 3 inch pipeline connected to the pump caisson (lines 321, 322 and 324). The pump caisson was connected to a pipeline (line 323 aka 200-E-274-PL) that routed contaminated water into the tank farm system, via the 244-A lift station.

In order to control the contamination migration from the basin, the 216-A-40 Retention Basin was stabilized in 1994. The retention basin pump, the diversion valve motor and other control devices were removed during the stabilization activities, but the pump pit and diversion box structures were left in place.

Code: 200-E-275-PL**Classification:** Accepted**Names:** 200-E-275-PL; 244-AR Cooling Water Pipeline to 216-A-40 Basin; Line 815**Reclassification:** None**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** The waste site is an underground, 30 centimeter (12 inch) diameter concrete cooling water pipeline that fed the 216-A-40 basin. The pipeline is associated with the 216-A-40 basin and the 244-AR Vault.**Location:** The pipeline is located south of 7th Street and west of Buffalo Ave. It runs along the east side of the 216-A-40 Retention Basin.

Related Sites/ Structures: The pipeline is associated with the 216-A-40 basin, the diverter box and the 244-AR Vault.

Code: 200-E-276-PL **Classification:** Accepted

Names: 200-E-276-PL; Pipeline from 296-A-13 Stack to 216-A-41 Crib **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 10 centimeter (4 inch) diameter vitrified clay pipeline that connected the 296-A-13 stack to the 216-A-41 crib.

Location: The pipeline is located west of Buffalo Ave. and north of the 244-AR Vault.

Related Sites/ Structures: The pipeline is associated with the 216-A-41 crib.

Process Description: The pipeline carried stack drainage to the 216-A-41 crib.

Code: 200-E-277-PL **Classification:** Accepted

Names: 200-E-277-PL; Pipelines from 221-B and 221-BA to 216-B-59 and 216-B-59B Basins **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground pipeline that connected 221-B to the 216-B-59 Retention Basin. The majority of the pipeline is constructed of varied diameters of carbon steel pipe. The section of pipe that extends from the 221-BA sampling building to the head end of the basin is constructed of 38 centimeter (15 inch) diameter vitrified clay pipe. The by-pass line that connects to the center of the basin is constructed and the pipeline re-routing basin effluent to 241-B Tank farm are constructed of 5 centimeter (2 inch) diameter carbon steel. (see subsites)

Location: The pipeline extends from the south side of 221-B to 216-B-59 Retention Basin. It crosses under Baltimore Ave.

Related Sites/ Structures: The pipeline is associated with B Plant operations and the 216-B-59 Retention Basin and pipeline 200-E-199-PL.

Process Description: In 1978, a new pipeline was added that connected the 216-B-59B basin to pipeline 200-E-199-PL, allowing effluent to be directed into the tank farm system.

This Site has the Following SubSites:

Code: 200-E-277-PL:1

Names: 200-E-277-PL:1; Carbon Steel Portion of Pipeline South of 221-B

Code: 200-E-277-PL:2

Names: 200-E-277-PL:2; 15-Inch VCP Portion of Pipeline

Code: 200-E-277-PL:3
Names: 200-E-277-PL:3; 2-Inch Carbon Steel Bypass Line from a Pump at the Center Section of the Basin and Two 3-Inch CS Lines from the Basin to the Pump
Code: 200-E-277-PL:4
Names: 200-E-277-PL:4; 2-Inch Carbon Steel Line Re-Routing 216-B-59 Basin Effluent to the 200-E-199-PL Encased Tank Farm Line

Code: 200-E-277-PL:1 **Classification:** Accepted
Names: 200-E-277-PL:1; Carbon Steel Portion of Pipeline South of 221-B **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

The SubSite is Part Of:

Code: 200-E-277-PL
Names: 200-E-277-PL; Pipelines from 221-B and 221-BA to 216-B-59 and 216-B-59B Basins

Code: 200-E-277-PL:2 **Classification:** Accepted
Names: 200-E-277-PL:2; 15-Inch VCP Portion of Pipeline **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

The SubSite is Part Of:

Code: 200-E-277-PL
Names: 200-E-277-PL; Pipelines from 221-B and 221-BA to 216-B-59 and 216-B-59B Basins

Code: 200-E-277-PL:3 **Classification:** Accepted
Names: 200-E-277-PL:3; 2-Inch Carbon Steel Bypass Line from a Pump at the Center Section of the Basin and Two 3-Inch CS Lines from the Basin to the Pump **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: Located inside the basin structure.

The SubSite is Part Of:

Code: 200-E-277-PL
Names: 200-E-277-PL; Pipelines from 221-B and 221-BA to 216-B-59 and 216-B-59B Basins

Code: 200-E-277-PL:4 **Classification:** Accepted
Names: 200-E-277-PL:4; 2-Inch Carbon Steel Line Re-Routing 216-B-59 Basin Effluent to the 200-E-199-PL Encased Tank Farm Line **Reclassification:** None

the west by railroad tracks, and on the south by 4th Street. The northern edge of the parking lot is approximately 160 meters (525 feet) north of 4th street (estimated using aerial photography in QMAP). The entire area surrounding the 2711E facility was mapped as 200-E-280 because of the large area used to park vehicles.

Waste Type: Oil

Waste Description: Areas of oil-stained soil are scattered throughout the parking lot.

Code: 200-E-281-PL **Classification:** Accepted

Names: 200-E-281-PL; Line V306; Pipeline from 241-B Tank Farm to 216-B-7A and 216-B-7B Cribs **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 7.6 centimeter (3 inch) diameter stainless steel pipeline that connects the 241-B-202 and 241-B-202 tanks to the 216-B-7A and 216-B-7B cribs.

Location: The pipeline is located north of the 241-B Tank Farm.

Related Sites/Structures: The pipeline is associated with the 241-B-201 and 241-B-202 tanks and the 216-B-7A and B cribs.

Code: 200-E-282-PL **Classification:** Accepted

Names: 200-E-282-PL; Lines 4001, 4002, 4003 and 4004; Lines 4023 and 4028 connecting to encasement; Process Waste Lines from 202-A to 241-AX-151 Diversion Box **Reclassification:** None

Type: Encased Tank Farm Pipeline **Start Date:** 1/1/1965

Status: Inactive **End Date:** 1/1/1974

Description: The concrete encased pipeline contains four, 7.6 centimeter (3 inch) diameter stainless steel pipelines. Line 4023 extends from the west end of 202-A and ties into line 4004 inside the encasement. Line 4028 extends from the south wall of 202-A and ties into line 4002 inside the encasement.

Location: The pipeline encasement originates on the south side of the PUREX facility. It extends westward beyond the facility footprint and turns north in between the double security fences on the west side of PUREX. The pipeline continues under 4th Street and angles east until it terminates at the 241-AX-151 Diversion Box, south of 244-AR Vault.

Process Description: The 200-E-282-PL waste site pipelines and encasement was constructed in 1965 as part of an improved Purex Essential Waste Routing System. This waste site consists of five pipelines that were utilized to transport approximately 15 billion gallons of PUREX self-boiling waste from the 202-A Plant to the 241-AX-151 Diversion Box. The pipelines were flushed with water after each waste transfer as was the established practice at the time. The final transfer of waste through the pipelines was in 1974.

Code: 200-E-283-PL **Classification:** Accepted

Names: 200-E-283-PL; Line 395; Pipeline from 242-A Bldg to 600-291-PL (TEDF Line) **Reclassification** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground 15 centimeter (6 inch) diameter carbon steel pipeline that connects 242-A to the 600-291-PL TEDF pipeline.

Location: The pipeline is located on the east side of the 242-A Evaporator Building.

Related Sites/Structures: The pipeline is associated with the 200-E-127-PL and 600-291-PL pipelines and the 242-A Evaporator building.

Process Description: Prior to the construction of the LERF and TEDF systems, the pipeline originally transferred waste from 242-A Evaporator to the Gable and B Ponds via pipeline 200-E-127-PL. Later, this effluent was transferred to the TEDF system via the 600-291-PL pipeline. The portion of the 200-E-127-PL pipeline where 200-E-283-PL connects was re-used to feed the TEDF system. The sitecode for this section of pipeline was changed to 600-291-PL.

Code: 200-E-284 **Classification:** Accepted

Names: 200-E-284; Septic Tank East of 241-BY-102 **Reclassification** None

Type: Septic Tank **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground septic tank.

Location: The septic tank is located east of 241-BY Tank Farm, on the west side of Baltimore Ave. It is outside the tank farm fence.

Process Description: The septic tank serviced the In Tank Solidification (ITS) #1 Compressor House. The Compressor House was located inside the tank farm fence.

Code: 200-E-285 **Classification:** Accepted

Names: 200-E-285; 216-A-8 Control Structure; 216-A-8 Sample Pit; Sample Pit #2 **Reclassification** None

Type: Control Structure **Start Date:**

Status: Inactive **End Date:**

Description: The sampler pit is a concrete structure with three valves, two vent stacks and one curved, metal bonnet extending from the structure. The structure is surrounded with post and chain with Underground Radioactive Material and Contamination Area signs. The area around the structure is gravel and asphalt.

Location: The sample pit is located on the east side of 241-A tank farm, outside the tank farm fence.

Release Description: In 1959, contaminated moisture dripping from a vent pipe bonnet at the 216-A-8 Proportional Sample Pit contaminated the ground around the cement pad. (see UPR-200-E-18)

Related Sites/Structures: The sample pit is associated with the 216-A-8 crib, 216-A-34, 241-A Tank farm, 200-E-164-PL, 200-E-166-PL and UPR-200-E-18.

Code: 200-E-287 **Classification:** Accepted
Names: 200-E-287; Posted Contamination Areas on Pipe Berm east of 241-A, AN, AX, AY and AZ Tank Farms **Reclassification:** None
Type: Contamination Migration **Start Date:**
Status: Unknown **End Date:**

Description: The waste site is a long, posted Soil Contamination Area located on the both sides of the gravel covered berm.

Location: The berm is located east of the 241-A Tank Farm Complex. It extends southeast from 241-AN Farm, crosses Canton Ave. and continues beyond the 200 East perimeter fence to the Verification Plant that is currently under construction.

Code: 200-E-288-PL **Classification:** Accepted
Names: 200-E-288-PL; PC-5000; Pipeline from 242-A Evaporator to Liquid Effluent Retention Facility **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Active **End Date:**

Description: The waste site is an underground, fiberglass reinforced epoxy pipeline. It is a 7.6 centimeter (3 inch) pipe inside a 15.2 (6 inch) pipe.

Location: The pipeline extends from the north side of the 242-A Evaporator building to the Liquid Effluent Retention Facility fence.

Process Description: The PC-5000 pipeline carries process condensate waste from the 242-A Evaporator to the Liquid Effluent Retention Facility (LERF) basin 242AL-43. If radiation level exceed established limits, an alarm is received and interlocks divert the stream back to the condensate collection tank and the pump is shut off. This ensures that excessive radionuclides are not accidentally transferred to LERF. Electronic leak detectors and swab risers are provided at 305 meter (1000 foot) intervals along the pipeline.

Waste Type: Steam Condensate

Waste Description: Process condensate from the 242-A Evaporator is a mixed waste stream. It is a dilute aqueous solution containing ammonia, volatile organics and trace quantities of radionuclide and inorganic constituents.

Code: 200-E-289-PL **Classification:** Accepted
Names: 200-E-289-PL; Lines 637, SN-700 and SN-701; Pipelines between AP-02D Pit and WTP **Reclassification:** None
Type: Direct Buried Tank Farm Pipeline **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is three underground, stainless steel pipes (each encased in a carbon steel pipe). Each line (637, SN-700 and SN-701) is a 7.6 centimeter (3 inch) pipe inside a 15.2 (6 inch) pipe. These pipelines have not been activated. They are currently capped outside the 241-AP Tank Farm. They will retain the inactive status until lines is connected to the Waste Treatment Plant (WTP) that is currently under construction.

Location: The pipelines extend from the east side of the 241-AP Tank Farm towards the Waste Treatment Plant (WTP).

Related Sites/ Structures: The lines are associated with the 241-AP 02D pump pit and the WTP (future).

Process Description: These pipelines are currently capped outside the 241-AP Tank Farm. They will retain the inactive status until lines is connected to the Waste Treatment Plant (WTP) that is currently under construction. Line SN-700 and SN-701 extend from the 241-AP-02D pump pit and currently terminate near the west side of the WTP. Pipeline SN-637 extends from the east side of the 241-AZ Tank Farm and terminates near the west side of the WTP. These lines will later be tied into piping that connects to the WTP and will be utilized to support supplying waste to and receiving waste from the WTP.

Waste Type: Process Effluent

Waste Description: In the future, the waste transferred through the pipelines will be Waste Treatment Plant feed and return effluent.

Code: 200-E-290-PL **Classification:** Accepted

Names: 200-E-290-PL; Pipeline from 271-CR to 216-C-8 French Drain **Reclassification:** None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is a 4 inch diameter Vitrified Clay Pipe that extends from the 271-CR building to the 216-C-8 french drain. The 216-C-8 french drain is also known as the 271-CR crib.

Location: The pipeline is located north of 7th Street. A portion of the pipeline is inside the 241-C tank farm fence. It extends eastward, beyond the 241-C tank farm fence to the 216-C-8 french drain.

Code: 200-E-291-PL **Classification:** Accepted

Names: 200-E-291-PL; Pipeline from 241-C-106 to 241-AY-102, SN-200, SL-100, 241-C-106 Sluice Line **Reclassification:** None

Type: Direct Buried Tank Farm Pipeline

Start Date:

Status: Inactive

End Date:

Description: The waste site is two 4 inch diameter stainless steel pipelines buried in the same soil trench. Each stainless steel line is encased within a 6 inch diameter carbon steel pipe.

Location: The pipelines extend from the 241-C tank farm to the 241-AY tank farm, on the east side of Buffalo Ave.

Process Description: Line SN-200 extends from 241-C-106-06C Sluice Pit to the 241-AY-102-02E Sluice Pit. The pump was electrically isolated, but remains in place.

Line SL-100 extends from the 241-C-106-A pump pit to the 241-AY-102-02A pump pit. SL-100 was isolated at 241-C-106.

Code: 200-E-292 **Classification:** Accepted

Names: 200-E-292; Area of Debris and Subsurface Anomalies on Unused Portion of 218-E-10 (aka 200-E-20) **Reclassification** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an area of interest (on 200-E-20) determined with Ground Penetrating Radar.

Location: The debris area is located in the northern portion of WIDS sitecode 200-E-20. The area is approximately 39.6 X 10 meters (130 by 30 feet).

Related Sites/ Structures: The area is associated with 200-E-20.

Code: 200-E-293 **Classification:** Accepted

Names: 200-E-293; 2718-E Contaminated Concrete Slab; 2718-E Foundation **Reclassification** None

Type: Foundation **Start Date:**

Status: Inactive **End Date:**

Description: The surface stabilized slab is associated with building 2718E, in 200 East Area. The metal building atop slab was demolished in November 2011 and the slab was left in place. The slab had a spot of radiological contamination. The contamination on the slab was covered with plastic, plywood and soil and posted as an Underground Radioactive Material Area. The cap covering the 209-E demolished building was expanded and now covers the 2718-E slab as well.

Amended water was sprayed during the 209E building demolition activities. Post-demolition, three to six inches of surface material was removed from all areas affected by the amended water and prior to applying a gravel cap. The final gravel cap was expanded to cover all affected areas. The posted URMA was expanded to include the entire gravel cap. The gravel cap now covers several WIDS sites. The additional WIDS sites under the 209E gravel cap are 200-E-4, 200-E-35, 209-E-WS-1, 209-E-WS-2, 2718-E-WS-1 and 200-E-293 (2718E footprint). The 209-E-WS-3 (Tank 111), adjacent to the south side of the foundation, is within the URMA but was not covered or backfilled.

Location: The waste site is inside the 209-E complex. It is located where the 2718-E building once stood.

Code: 200-E-294 **Classification:** Accepted

Names: 200-E-294; 209-E Slab; Demolished 209-E Critical Mass Laboratory Building Foundation; Potential Asbestos in Soil **Reclassification** None

Type: Foundation **Start Date:**

Status: Inactive **End Date:**

Description: The 209-E building was demolished in December 2011. This waste site is the remaining concrete slab and any contaminated soil or piping beneath the slab under the demolished 209-E Critical Mass Laboratory building. The concrete slab was covered with gravel and posted with Underground Radioactive Material signs. The 209-E-WS-3 (Tank 111), adjacent to the south side of the foundation, was not covered or backfilled. Determination of potential asbestos containing material (ACM) left in place and abated during demolition is based on a Quality

Assurance review of project documentation and interviews with activity personnel.

Amended water was sprayed during the 209E building demolition activities. Post-demolition, three to six inches of surface material was removed from all areas affected by the amended water and prior to applying a gravel cap. The final gravel cap was expanded to cover all affected areas. The posted URMA was expanded to include the entire gravel cap. The gravel cap now covers several WIDS sites. The additional WIDS sites under the 209E gravel cap are 200-E-4, 200-E-35, 209-E-WS-1, 209-E-WS-2, 2718-E-WS-1 and 200-E-293 (2718E footprint). The 209-E-WS-3 (Tank 111), adjacent to the south side of the foundation, is within the URMA but was not covered or backfilled.

Location: The building foundation is located inside 200 East Area, south of 7th Street and east of Baltimore Ave.

Code: 200-E-295 **Classification:** Accepted

Names: 200-E-295; 272E Potential Asbestos Hazard Site **Reclassification:** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is the gravel capped area where the 272E building had been located. The 272E building was demolished in 2010. It is surrounded with posts and chain. The signs on the chain state "Caution: Potential Asbestos Hazard; Transite in the Soil; No ground-intrusive or heavy equipment activities in this area unless specifically authorized by controlling project OS&H" with a Contact phone number and required Protective Clothing listed. Determination of ACM left in place and abated during demolition is based on a Quality Assurance review of project documentation and interviews with activity personnel.

Location: The site is located west of Baltimore Ave. and south of 4th Street where the 272E shop building had been located.

Code: 200-E-296 **Classification:** Accepted

Names: 200-E-296; 284E Potential Asbestos Hazard Site **Reclassification:** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is the gravel capped area where the 284E building had been located. The 284E building was demolished in 2010. It is surrounded with posts and chain. The signs on the chain state "Caution: Potential Asbestos Hazard; Transite in the Soil; No ground-intrusive or heavy equipment activities in this area unless specifically authorized by controlling project OS and H (Operational Safety and Health)" with a Contact phone number and required Protective Clothing listed. Determination of ACM left in place and abated during demolition is based on a Quality Assurance review of project documentation and interviews with activity personnel.

Location: The site is located east of Baltimore Ave. and south of 4th Street where the demolished 284E powerhouse had been located.

Related Sites/ Structures: The gravel cap is also associated with sitecode 200-E-1.

Code: 200-E-297 **Classification:** Accepted

Names: 200-E-297; Open Pit Containing Potential Asbestos Transite **Reclassification** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is describes as an open pit containing material that resembles fragments of asbestos material and miscellaneous building debris. Signs that state "Caution: Potential Asbestos Hazard; Transite in the Soil; No ground-intrusive or heavy equipment activities in this area unless specifically authorized by controlling project OS & H" with a Contact phone number and required Protective Clothing listed" were placed around the area in June 2012.

Location: The pit is located east of Baltimore Ave. and north of 7th Street.

Code: 200-E-298 **Classification:** Accepted

Names: 200-E-298; 2701M Guard House Potential Asbestos in Soil **Reclassification** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is the location of the demolished 2701M guard shack. It is surrounded with yellow rope and railroad ties. The site was covered with 6 inches of gravel after demolition and posted with "Caution Potential Asbestos Hazard in Soil" signs.

Location: The guard shack had been located in 200 East Area, at the entrance to the 2101-M area.

Code: 200-E-299 **Classification:** Accepted

Names: 200-E-299; 2902E Potential Asbestos in Soil **Reclassification** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is the location of the demolished 2902E water tower. The area is currently not marked or posted.

Location: The 2902E water tower had been located south of 3rd Street, west of Baltimore Ave.

Code: 200-E-300 **Classification:** Accepted

Names: 200-E-300; 275-E Potential Asbestos in Soil **Reclassification** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is the location of the demolished 275-E building. The area is paved with asphalt. A portion of the area is fenced and being used for material storage. It is not posted. Determination of asbestos containing material (ACM) left in place and abated during demolition is based on a Quality Assurance review of project documentation and interviews with activity personnel.

Location: The 275-E building had been located west of Baltimore Ave and north of 3rd Street.

Code: 200-E-301 **Classification:** Accepted
Names: 200-E-301; 2701EC; 2701-EC Guard House **Reclassification** None
Potential Asbestos in Soil
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is the potential asbestos containing material (ACM) left in place following the demolition of the 2701-EC Guard House. The guard house was demolished in March 2011. Determination of ACM left in place and abated during demolition is based on a Quality Assurance review of project documentation and interviews with activity personnel.

Location: The 2701-EC guard house had been located at the 209E facility. It was located on the south side of 7th Street, north of the 209E building.

Code: 200-E-303 **Classification:** Accepted
Names: 200-E-303; PUREX Nitric Acid Line Leak **Reclassification** None
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The site is an area of contaminated soil under a nitric acid line. A Bag/Container was placed around the valve to prevent additional release. The leak has been repaired. The area is surrounded with post and chain and marked with a WIDS Sitecode sign.

Location: The site is located east of the 218-E-14 railroad tunnel. It is adjacent to the elbow where the overhead steam line turns north, approximately 1.5 meters (5 feet) west of the 200-E-70 waste site.

Release Description: A Bag/Container was placed around the valve to prevent additional release. The leak has been repaired.

Code: 200-E-305-PL **Classification:** Accepted (Proposed)
Names: 200-E-305-PL; DR311; Drain Line from 241-ER-152 to 241-ER-311 Catch Tank **Reclassification** None
Type: Direct Buried Tank Farm Pipeline **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is a 3 inch stainless steel drain line inside a 4 inch stainless steel pipe.

Location: The drain line extends from the 241-ER-152 Diversion Box, under Atlanta Ave, to the 241-ER-311 Catch Tank. The length of the drain line is approximately 600 feet.

Related Sites/Structures: The line is associated with the 241-ER-152 diversion Box and the 241-ER-311 catch tank.

Process Description: The DR311 drain line carried excess liquid from the 241-ER-152 diversion Box to the 241-ER-311 catch tank.

Code: 200-E-306 **Classification:** Accepted

Names: 200-E-306; Radiologically Posted Area West of 216-A-7 **Reclassification** None

Type: Contamination Migration **Start Date:**

Status: Not Specified **End Date:**

Description: The waste site is a soil area surrounded by six, yellow cement bollards. It is posted with Underground Radioactive Material Area signs. A portion of pipeline 200-E-182-PL is located beneath this posted area.

Location: The waste site is in 200 East area, on the east side of Canton Ave. It is east of the 241-A tank Farm. The center of the posted area is about 40 feet west of the edge of the 216-A-7 crib. The coordinates for the four corners are:

E575493/N136049

E575493/N136032

E575482/N136049

E575482/N136032

Related Sites/ Structures: A portion of pipeline 200-E-182-PL is located beneath this posted area.

Code: 200-E-307 **Classification:** Discovery

Names: 200-E-307; Stabilized Radiological Area Related to Contaminated Rabbit Feces at 242-A Building **Reclassification** None

Type: Contamination Migration **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is a gravel area adjacent to the east side of the 242-A building that is posted with concrete bollards and Underground Radioactive Material signs.

Location: The waste site is directly adjacent to the east wall of the 242-A Evaporator building (and 242-AB addition). It is on the west side of Canton Ave.

Release Description: In August 2015, contaminated rabbit feces were discovered in the lawn on the east side of the 242-A Evaporator building. The area was decontaminated as much as practical and then covered with six inches of gravel.

Code: 200-E-308-PL **Classification:** Discovery

Names: 200-E-308-PL; Grout Facility Feed Line and Excess Water Line; GTF Feed Line; SN-621 **Reclassification** None

Type: Direct Buried Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is two, parallel pipelines buried in the same soil trench. Each pipeline is a 2 inch diameter carbon steel pipe inside a 4 inch diameter carbon steel pipe. One pipe transferred radioactive feed material from tank 241-AP-102 to the Grout Treatment Facility. The other pipe transferred excess water from the Grout Treatment Facility landfill to the 241-AP-102 tank. Line SN-621 is the Grout Facility Feed Line. The pipelines are covered with a soil berm.

Related Sites/ Structures: The pipeline is associated with Grout Treatment Facility and the 241-AP tank farm.

Process Description: The material transferred from tank 241-A-102 via line SN-621 connected to the Grout facility Liquid Collection Tank (LCT). The LCT contained equipment that included grout mixers and pumps. The technology and process operation of the GTF was demonstrated from August 1988 through July 1989 with the treatment of 3,785,400 liters (1,000,000 gallons) of radioactive, non-dangerous waste. Processing of this waste generated leachate that was a corrosive mixed waste. The leachate was stored at GTF and later transferred back to the Double Shell Tank System.

Code: 2607-E13 **Classification:** Accepted

Names: 2607-E13; Septic Holding Tank South of 277-A **Reclassification:** None

Type: Septic Tank **Start Date:**

Status: Active **End Date:**

Location: The septic holding tank is located on the west side of Buffalo Ave., south of the 277-A building.

Related Sites/ Structures: This tank services MO-398, MO-919 and MO-570 in 200 East Area.

Process Description: The drain field failed in 1996 and was abandoned. The septic tank is currently used as a septic holding tank.

Code: 2607-EB **Classification:** Accepted

Names: 2607-EB; 241-BY-254 (ITS #2) Sanitary Septic System **Reclassification:** None

Type: Septic Tank **Start Date:** 1/1/1963

Status: Inactive **End Date:**

Description: In 1991, the system was marked and roped. A site visit in 1997 (from outside the tank farm fence) could not identify the location of the system. The unit includes a drain field.

Location: The septic system is located inside 241-BY, adjacent to the western 241-BY Tank Farm fence, west of 241-BY-112.

Related Sites/ Structures: Adjacent to the septic tank is a drain field composed of vitrified clay pipe, concrete pipe, or drain tile forming the main line and laterals from the tank.

Process Description: The system received sanitary waste from the ITS #2 facility.

Waste Type: Sanitary Sewage

Waste Description: Sanitary wastewater and sewage. Estimated rate of waste generation is 0.02 cu m/d.

Code: 2607-EF **Classification:** Accepted

Names: 2607-EF; Septic Tank West of 241-BX Tank Farm **Reclassification:** None

Type: Septic Tank **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground septic tank.

Location: The septic tank is located on the west side of the 241-BX Tank Farm, outside the fence.

Process Description: The septic tank had serviced the 271 BXR Control House. The Control House building was located inside the tank farm fence.

Code: 2607-ES **Classification:** Accepted

Names: 2607-ES; Septic Tank and Dry Well North of 204-AR **Reclassification:** None

Type: Septic Tank **Start Date:**

Status: Active **End Date:**

Location: The septic tank and dry well are located north of the 204-AR building.

Process Description: The septic tank serviced the 204-AR building. The attached dry well is located north of the septic tank.

Code: 241-ER-153 **Classification:** Accepted

Names: 241-ER-153; 241-ER-153 Diversion Box **Reclassification:** None

Type: Diversion Box **Start Date:** 1/1/1945

Status: Inactive **End Date:**

Description: Most of the diversion box structure is underground. The cover blocks with lifting bails are visible on the surface. The 244-A Lift Station is fenced, marked and radiologically posted.

Location: The 241-ER-153 Diversion Box is located south of Seventh Street, inside the fenced 244-A lift station.

Related Sites/Structures: The 241-ER-153 diversion box is associated with the 244-A Lift Station, 241-C Tank Farm, and the 241-ER-151, and 241-ER-152 Diversion Boxes and pipelines 200-E-145-PL and 200-E-147-PL.

Process Description: Diversion boxes contain jumper piping for routing liquid waste between facilities and the tank farms via underground transfer lines. They are concrete boxes that were designed to contain any waste that leaks from the high-level waste transfer line connections. The diversion boxes generally drain by gravity to nearby catch tanks where any spilled waste is stored. The 241-ER-153 Diversion box is a roughly rectangular reinforced concrete structure. The floors and lower portions of the walls are lined in stainless steel.

Waste Type: Process Effluent

Waste Description: The diversion box distributes waste between facilities and tank farms via underground transfer lines. Transfer lines V228, SN232 and SN233 are connected to 241-ER-153. Quantities are variable according to specific plant operations. This diversion box connects the 241-C Tank Farms to the double-shell tanks, and supports the 241-ER-151 Diversion Box in cross-site waste transfers. It is estimated that approximately 23 kilograms (50 pounds) of lead shielding may be stored in each diversion box.

Code: 241-EW-151 **Classification:** Accepted

Names: 241-EW-151; 241-EW-151 Vent Station; 241- **Reclassification:** None

EW-151 Vent Station Catch Tank; Vent Station;
200 Area East-West Vent Station

Type: Catch Tank **Start Date:** 1/1/1955
Status: Inactive **End Date:** 1/1/2005

Description: The vent station is enclosed in a locked, chain link fence. It consists of an underground concrete structure containing a stainless steel tank in a vault with a jumper pit above the tank. The tank has two vent risers that extend above grade and a riser for the unit's leak detection system. At the bottom of the stairwell access is a floor drain that connects to a nearby french drain. Several hazard and radiological warning signs are posted on the fence. There are also two areas, outside the fence, adjacent to the northeast side of the vent station that are posted with Underground Radioactive Material signs.

Location: The site is located south of Route 3, approximately half way between 200 East and West Areas. It is south of the 609-A Fire Station.

Related Sites/ Structures: This site is part of the cross-site waste transfer system and is associated with UPR-600-20, Diversion Boxes 241-UX-154 (200 West) and 241-ER-151 (200 East). The vent station is associated with the cross-site transfer line that runs between Diversion Boxes 241-UX-154 (200 West) and 241-ER-151 (200 East).

Process Description: The 241-EW-151 Vent Station is located at the high point of the cross site transfer line. The encasement slopes approximately 4 percent on each side of the vent station. The encased underground transfer line piping depth varies from 1.5 meters (5 feet) to 4.5 meters (15 feet). The vent station is designed to contain leaks from transfers and drainage from operations within the transfer system. The piping from the vent station drains to the diversion boxes. The vent station has a jumper pit to facilitate transfer of mixed waste between 200 East and 200 West Areas. The catch tank is part of the 241-EW-151 Vent Station. The catch tank vault used to drain to a nearby french drain, but that line has been isolated. The vent station stairwell floor drain still connects to the french drain. The catch tank has a capacity of 3,030 liters (800 gallons). It is 1.4 meters (4.5 feet) in diameter and 2.1 meters (7 feet) tall. Each of the cross site pipelines has a one inch stainless steel vent line connected to the 800 gallon vent station catch tank. A manually operated valve in each vent line allows for air bleeding, pressure checking and a siphon break on the drain back line. The 241-EW-151 Vent Station drains to a sump with a leak detection alarm that signals in the fire station building.

Waste Type: Process Effluent

Waste Description: The vent station transports waste solutions from processing and decontamination operations via the cross-site waste transfer system.

Code: 200-W-44 **Classification:** Accepted
Names: 200-W-44; 291-U Stack Sand Filter **Reclassification:** None
Type: Sand Filter **Start Date:** 1/1/1948
Status: Inactive **End Date:**

Description: The sand filter is constructed of reinforced concrete that is partially below grade with an asphalt covered, concrete slab roof. The chain link fence was removed in March 2002, when the area was surface stabilized. It is posted as an Underground Radioactive Material area. The sides of the sand filter that extend above grade are covered with gravel. In 20011, the 200-W-136 URMA area was expanded and now includes 200-W-44.

Location: The sand filter is located east of the 221-U Building and northeast of the 291-U Stack.

Related Sites/ Structures: The 291-U-1 Stack, 291-U Fan Control House, a french drain (200-W-234) and 291-U Vessel Vent Pit are associated with the unit.

Process Description: 221-U was built in 1945. Sand Filters were added to T Plant and B Plant in 1948. It is assumed the sand filter at U Plant was constructed in that same time period. From 1945 until 1952, U Plant was only used for training of canyon building workers. In 1952 the facility began the Uranium Metal Recovery process. The exhaust ventilation system was planned to remain in service until the 221-U Building was decommissioned. The U Plant canyon began decommissioning activities in 2005.

Waste Type: Soil

Waste Description: The sand filter contains low-level fission products, but no plutonium.

The Following Sites Were Consolidated With This Site:

Code: 200-W-234

Names: 200-W-234; 291-U Sand Filter French Drain

Code: 200-W-45 **Classification:** Accepted

Names: 200-W-45; 291-T Sand Filter; T Plant Stack Sand Filter **Reclassification:** None

Type: Sand Filter **Start Date:** 1/1/1949

Status: Inactive **End Date:** 1/1/1979

Description: The sand filter is a large, rectangular structure located north of the 291-T stack. It is posted with "Contamination Area" signs. There is one vent pipe, located on the northwest corner of the filter structure, protruding through the top of the sand filter.

Location: The sand filter is located near the northeast corner of 221-T, adjacent to the 291-T stack.

Related Sites/ Structures: The site is associated with the 291-T Stack and the 216-T-29 French Drain.

Process Description: The sand filter was used to filter the 291-T stack air. The sand filter is a partially buried concrete structure measuring 33.5 X 15.25 X 4.8 meters (110 X 50 X 16 feet). The 1987 Hanford Site Waste Management Units Report site description states "This site consists of sixty french drains, each measuring 6 inches in diameter, 3 foot 5 inches long, filled with coarse gravel, placed 13 feet 7 inches below the top of the structure. There is a concrete structure 100 X 48 X 14 feet 7 inches high which contains concrete blocks arranged in rows to form lateral ducts, with drains spaced throughout, every 10 feet lengthwise - 8 feet widthwise, all covered with 9 feet of sand and gravel, then covered with concrete slabs. There is a 1 foot layer of gravel on the entire bottom, with a layer of sisalkraft paper underneath which surrounds the drains throughout the structure." The 200 Area Waste Site Handbook (RHO-CD-673) describes the facility (sand filter) as "Sixty, 6 inch diameter vitrified soil pipes inside an area measuring 100 X 48 feet. The 291-T sand filter inlet trenches drain to a french drain pipe extending into the ground at the north corner of the sand filter. Any moisture condensed from the canyon air on the filter bed will escape to the ground at this location. The amount and activity are both very low."

Waste Type: Soil

Waste Description: Using information found in PNNL document "Radionuclide Releases to the Atmosphere from Hanford Operations, 1944-1972" (PNWD 2222 HEDR), a standard decay equation estimates the curies of radionuclides in the T Plant Sand Filter to be: 29 curies of Strontium-90, 33 curies

of Cesium-137 and 4.1 curies of Plutonium-239 (or 66 grams) as of October 1994.

Code: 200-W-73 **Classification:** Accepted

Names: 200-W-73; Contaminated Debris Near Railroad Track; URMA East of 218-W-2A **Reclassification:** Interim No Action (6/30/2004)

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:** 1/1/2000

Description: The site has been evaluated and determined to require No Action. It is currently an area covered with gravel and posted as an Underground Radioactive Material Area. It originally had been surrounded with light post and chain and posted as a Contamination Area. The contaminated material was removed in June 2000.

Location: The site is located north of 23rd Street, east of the 218-W-2A Burial Ground. It is adjacent to the railroad track.

Release Description: The contaminated material was identified partly inside and partly outside of a previously posted Contamination Area on April 10, 2000. The posted area appeared to be very old and abandoned. The site consisted of contaminated wood and metal debris. The maximum direct contamination found on the metal was 12,000 disintegrations per minute. The area was properly reposted and logged into the Contamination Area logbook.

Waste Type: Misc. Trash and Debris

Waste Description: The waste consists of contaminated wood and metal debris.

Closure Info: Interim: In June 2000, the scrap wood and angle iron were surveyed with field instruments. The metal that exhibited no detectable radiological contamination was recycled. Contaminated iron and scrap wood was processed as Low-level Waste (LLW). After the debris was removed the area was radiologically surveyed. No contamination was identified in the soil or vegetation. Six inches of gravel was spread over the area and the posting was changed from Contamination Area to Underground Radioactive Material. The reclassification to No Action is documented on form 2004-068.

Code: 200-W-78-PL **Classification:** Accepted

Names: 200-W-78-PL; 6025; 7624 and 7630; Lines 6012; Pipeline Between 241-TX/TY and 241-T Tank Farms **Reclassification:** None

Type: Encased Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: The site is an encased underground pipeline that runs between the 241-TXR-151 Diversion Box in the 241-TX Tank Farm and the 241-TR-153 Diversion Box in the 241-T Tank Farm. The encasement contains four lines (6012, 6025, 7624 and 7630). Outside the tank farm fence, the line is marked with Radioactive Pipeline signs.

Location: The underground line is located in 200 West Area between the 241-T and 241-TX/TY Tank Farms, on the west side of Camden Avenue.

Related Sites/Structures: The line is associated with 241-T and 241-TX Tank Farms. UPR-200-W-167 was also located in the vicinity of this pipeline.

Process Description: The lines inside the tank farm fence are direct buried in a soil trench. The portion of the lines that are outside the tank farm fence are encased in cement. Lines 6012, 6025, 7624 and 7630 are inside this pipe trench and encasement. Lines 6025 and 7630 connect 241-TR-153 Diversion Box with 241-TXR-151 Diversion Box. Line 6012 connects the 241-T-101 salt well pump with 244-TX DCRT. Line 7624 connects the 241-T-111 salt well pump with 244-TX DCRT. The lines inside the tank farm are direct buried, stainless steel lines.

Waste Type: Process Effluent

Waste Description: The pipeline transported liquid process effluent between the 241-T and 241-TX/TY tank farms. The contaminated soil and vegetation found above the transfer line was the result of biological intrusion into underground tank farm transfer lines.

Code: 200-W-79-PL **Classification:** Accepted

Names: 200-W-79-PL; Line V663; Pipeline from 241-T-151 Diversion Box to 216-T-36 Crib **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:** 1/1/1967

Status: Inactive **End Date:**

Description: The site is a 10 centimeter (4 inch) diameter, vitrified clay underground pipeline that fed the 216-T-36 Crib. There were three separately posted Contamination Areas located on top of this pipeline, west of the 216-T-36 Crib. In November 2000, the Contamination Areas were stabilized and reposted as Underground Radioactive Material areas.

Location: The pipeline is located south of 23rd Street and west of Camden Avenue.

Related Sites/Structures: The site is associated with the 216-T-36 Crib, 241-T-151 Diversion Box and 200-W-130-PL.

Process Description: The 10 centimeter (4 inch) vitrified clay crib line is connected to the stainless steel "spare line V663" (see 200-W-130-PL). The spare line was activated in 1967 to feed the 216-T-36 crib. This pipeline carried waste that originated at both T-Plant and U-Plant via the 241-T-151 diversion box. The diversion box is located inside the 241-T tank farm.

Waste Type: Soil

Waste Description: The waste is the vitrified clay pipeline and contaminated soil from apparent pipeline leaks. Contaminated vegetation has been identified growing on this pipeline.

Code: 200-W-88-PL **Classification:** Accepted

Names: 200-W-88-PL; 221-T Process Sewer; 24 Inch Process Sewer; T Plant Process Sewer Pipeline; 200-W-88 **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:** 1/1/1944

Status: Inactive **End Date:** 1/1/1995

Description: The main waste site is a vitrified clay process sewer pipeline connecting T Plant buildings to the 207-T Retention Basin. The main line is a 61 centimeter (24 inch) diameter, underground vitrified clay pipeline extending from 221-T and 224-T to the 207-T Retention Basin. Feed lines from various support facilities are listed as subsites. There are multiple 1.2 meter (4 foot) diameter, yellow concrete manholes visible at intervals along the sewer line. This site also includes a radiologically posted area around one of the manholes located northwest of 216-T-6 crib. (see subsites)

Location: The Process Sewer pipeline runs west from 221-T to the 207-T Retention Basin on the north side of 23rd Street.

Related Sites/ Structures: The pipelines are associated with 221-T, 224-T, 2706-T and 207-T.

Process Description: The Process Sewer lines transferred process cooling water, air conditioning condensate and floor drain waste from 221-T, 224-T and 2706-T to the 207-T Retention Basin. The retention basin released effluent to ditch that led to the 216-T-4-1 and 216-T-4-2 Ponds.

Waste Type: Process Effluent

Waste Description: The Process Sewer effluent contained chemicals and low level radiological contaminants from T Plant processes.

This Site has the Following SubSites:

Code: 200-W-88-PL:1

Names: 200-W-88-PL:1; 24-Inch VCP Pipeline from Manhole South of 221-T to 207-T Retention Basin

Code: 200-W-88-PL:2

Names: 200-W-88-PL:2; 6-Inch VCP Line That Runs North to South (West of 221-T)

Code: 200-W-88-PL:3

Names: 200-W-88-PL:3; 24-Inch Cast Iron Pipe Extending the Length of the Rear Side of 221-T and Connecting to the 24-Inch VCP Process Sewer

Code: 200-W-88-PL:4

Names: 200-W-88-PL:4; 10-Inch Cast Iron Pipe from Rear (East Side) of 224-T Connecting to the 24-Inch VCP Process Sewer

Code: 200-W-88-PL:5

Names: 200-W-88-PL:5; 4-Inch Steel Pipe from West Side of 224-T Connecting to the Process Sewer Manhole

Code: 200-W-88-PL:6

Names: 200-W-88-PL:6; 6-Inch Vitrified Clay Line from 2706-T to 200-W-88-PL Process Sewer

Code: 200-W-88-PL:1

Classification: Accepted

Names: 200-W-88-PL:1; 24-Inch VCP Pipeline from Manhole South of 221-T to 207-T Retention Basin

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

The SubSite is Part Of:

Code: 200-W-88-PL

Names: 200-W-88-PL; 221-T Process Sewer; 24 Inch Process Sewer; T Plant Process Sewer Pipeline; 200-W-88

Code: 200-W-88-PL:2

Classification: Accepted

Names: 200-W-88-PL:2; 6-Inch VCP Line That Runs North to South (West of 221-T)

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

The SubSite is Part Of:

Code: 200-W-88-PL

Names: 200-W-88-PL; 221-T Process Sewer; 24 Inch Process Sewer; T Plant Process Sewer Pipeline; 200-W-88

Code: 200-W-88-PL:3

Classification: Accepted

Names: 200-W-88-PL:3; 24-Inch Cast Iron Pipe Extending the Length of the Rear Side of 221-T and Connecting to the 24-Inch VCP Process Sewer

Reclassification None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

The SubSite is Part Of:

Code: 200-W-88-PL

Names: 200-W-88-PL; 221-T Process Sewer; 24 Inch Process Sewer; T Plant Process Sewer Pipeline; 200-W-88

Code: 200-W-88-PL:4

Classification: Accepted

Names: 200-W-88-PL:4; 10-Inch Cast Iron Pipe from Rear (East Side) of 224-T Connecting to the 24-Inch VCP Process Sewer

Reclassification None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

The SubSite is Part Of:

Code: 200-W-88-PL

Names: 200-W-88-PL; 221-T Process Sewer; 24 Inch Process Sewer; T Plant Process Sewer Pipeline; 200-W-88

Code: 200-W-88-PL:5

Classification: Accepted

Names: 200-W-88-PL:5; 4-Inch Steel Pipe from West Side of 224-T Connecting to the Process Sewer Manhole

Reclassification None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

The SubSite is Part Of:

Code: 200-W-88-PL

Names: 200-W-88-PL; 221-T Process Sewer; 24 Inch Process Sewer; T Plant Process Sewer Pipeline; 200-W-88

Code: 200-W-88-PL:6 **Classification:** Accepted
Names: 200-W-88-PL:6; 6-Inch Vitrified Clay Line from 2706-T to 200-W-88-PL Process Sewer **Reclassification** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

The SubSite is Part Of:

Code: 200-W-88-PL
Names: 200-W-88-PL; 221-T Process Sewer; 24 Inch Process Sewer; T Plant Process Sewer Pipeline; 200-W-88

Code: 200-W-97-PL **Classification:** Accepted
Names: 200-W-97-PL; Encased Pipeline from 240-S-151 Diversion Box to 241-S-151 Diversion Box; Lines V508, V509, V512, V513, V514, V515, V516, V517/3603 and V519/1115 **Reclassification** None
Type: Encased Tank Farm Pipeline **Start Date:**
Status: Inactive **End Date:**

Description: The site is an underground, concrete encased pipeline. The surface is marked with Underground Radioactive Material - Pipeline signs. Yellow swab risers are located along the pipeline. One swab riser, near the 204-S facility, has been surrounded with posts and chain and posted with Soil Contamination Area signs.

Location: The pipeline extends northwest from the REDOX facility to the 241- S/SX Tank Farm.

Related Sites/ Structures: The site is associated with 202-S, 203-S, 204-S and 205-S and the 241-S-151 Diversion Box.

Process Description: The encased 7.6 centimeter (3 inch) diameter pipelines transferred waste from the REDOX facility to the 241-S-151 Diversion Box at the 241-S/SX Tank Farm.

Waste Type: Process Effluent

Waste Description: The pipeline transferred REDOX process waste to the 241-S/SX Tank Farm.

Code: 200-W-98-PL **Classification:** Accepted
Names: 200-W-98-PL; Encased Pipeline from 240-S-151 to 241-U-153 Diversion Box; V458, V459, and V460 **Reclassification** None
Type: Encased Tank Farm Pipeline **Start Date:**
Status: Inactive **End Date:**

Description: The site is a cement encased, underground pipeline. The pipeline is marked with Underground Radioactive Material - Pipeline signs.

Location: The pipeline is located south of 16th Street, extending in a southeast direction from the 241-U-153 Diversion Box to 204-S and the REDOX facility.

Related Sites/ Structures: The site is associated with the 204-S Facility and the 241-U-153 Diversion Box. Pipeline 200-W-138-PL exits and connects to 216-S-7 crib.

Process Description: The pipeline transferred waste between the 241-U-153 Diversion Box (located inside the 241-U Tank Farm) and the 204-S facility. There are three, 7.6 centimeter (3 inch diameter) carbon steel lines inside the concrete encasement.

Waste Type: Process Effluent

Waste Description:

Code: 200-W-99-PL **Classification:** Accepted

Names: 200-W-99-PL; Encased Pipeline from 241-U-151 to 241-S-151 Diversion Boxes; Lines V455 and V456 **Reclassification:** None

Type: Encased Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: The site is a cement encased, underground pipeline. The pipeline is marked with Underground Radioactive Material - Pipeline signs.

Location: The pipeline is located south of 16th Street, extending from the 241-U-151 Diversion Box to the 241-S-151 Diversion Box.

Process Description: The pipeline transferred various wastes between the 241-U and 241-S/SX Tank Farms. The lines are contained within a 3-38 encasement, indicating there are three separate lines inside the cement encasement.

Waste Type: Process Effluent

Waste Description:

Code: 200-W-100-PL **Classification:** Accepted

Names: 200-W-100-PL; Encased Pipeline from 241-UX-154 to 241-SX-152 and 241-S-151 Diversion Boxes; Lines V762/4853, V503/4700 and V505/4701 **Reclassification:** None

Type: Encased Tank Farm Pipeline **Start Date:** 1/1/1970

Status: Inactive **End Date:** 1/1/1976

Description: The site is an underground cement encased pipeline. The encasement contains three stainless steel lines. The pipeline encasement is marked with Underground Radioactive Material - Pipeline signs.

Location: The pipeline begins on the east side of the 221-U building at the 241-UX-154 Diversion Box and extends in a southwest direction to terminate at the 241-S-151 Diversion Box, located on the east side of 241-S/SX Tank Farm. An additional line terminates at the 241-SX-152 Diversion Box, also located inside the tank farm fence.

Related Sites/ Structures: 200-W-100-PL ties into 200-W-105-PL south of the 241-UX-154 Diversion Box. A short segment of the 216-U-8 pipeline (sitecode 200-W-42-PL) crosses over 200-W-100-PL at the

point where both pipelines are under 16th Street. This segment of the crib pipeline was given a separate sitecode (200-W-151-PL). It is anticipated that the segment of crib pipeline under 16th Street (200-W-151-PL) will be addressed with the 200-W-100-PL pipeline.

Process Description: The pipelines transferred Redox Supernate waste from the 241-S/SX Tank Farm to the 241-UX-154 diversion box (via a segment within the 200-W-105-PL encasement). The concrete encasement includes three 7.6 centimeter (3 inch) diameter stainless steel lines identified as V762/4853, V503/4700 and V505/4701. The pipelines supported waste evaporation activities from the 242-S Evaporator. The 241-UX-154 diversion box transferred the waste to the 600-284-PL Cross Site Transfer line and the 241-ER-151 Diversion Box.

Waste Type: Process Effluent

Waste Description: The pipeline transferred U Plant canyon waste to the 241-S/SX Tank Farm via the 241-UX-154 diversion box.

Code: 200-W-105-PL **Classification:** Accepted

Names: 200-W-105-PL; Encased Lines V375, V376, V382, 4877, 4851 and 4859/4703, 4878, 4832, 4876, 4897, 4707, 4701, 4700, 4855, 4854 and 4853; Encased Transfer Line between 241-UX-154 Diversion Box and 241-TX-155-Diversion Box and between 241-UX-154 Diversion Box and 241-WR Vault **Reclassification:** None

Type: Encased Tank Farm Pipeline

Start Date:

Status: Inactive

End Date:

Description: The site is an underground pipeline cement encasement. The encasement is marked with Underground Radioactive Material - Pipeline signs.

Location: The pipeline concrete encasement begins at 241-UX-154, on the east side of the 221-U building. It extends east and separates into two segments near the 241-WR Vault. One segment, containing seven lines, extends north and northwest to terminate at the 241-TX-155 Diversion Box.

Related Sites/Structures: The encasement includes tank farm lines V375, V382, 4859/4703, 4878, 4832, 4876, 4897, 4707, 4701, 4702, 4700, 4855, 4854 and 4853. The pipeline is associated with 221-U, 241-UX-154 Diversion Box, 241-WR Vault, 241-TX-155 diversion box.

Process Description: The encased pipeline transferred U Plant canyon waste to the 241-TX Tank Farm via the 241-UX-154 diversion box, the 241-TX-155 diversion box and pipeline 200-W-191-PL. It also supported the Uranium Recovery product and waste transfers via the 241-WR Vault.

The pipeline separates into two segments near the south side of the 241-WR Vault. Five lines from the 241-UX-154 Diversion Box extend beyond the "Y" split to connect to the 241-WR Vault. Beyond the "Y", seven lines (from the upper nozzles of the 241-UX-154 DB) divert to the 241-TX-155 Diversion Box. The line numbers continuing to 241-TX-155 Diversion Box are V375, V376, V382, 4851, 4877 and 4859/4703.

The width of the concrete encasement changes several times to accommodate piping being added and subtracted from the group of pipes. It begins as 300 feet of 9 line (80 inch wide) encasement at the 241-UX-154 Diversion Box. It expands to 200 feet of 12 line (101 inch wide) encasement near the 241-WR Vault. A 7 line (66 inch wide) segment splits near the WR Vault that extends to the 241-TX-155 diversion box.

Beyond the "Y" shaped split, five lines (from the lower nozzles of the 241-UX-154 DB) connect to the 241-WR Vault. Several other Uranium Recovery process lines join the encasement on this side of the split. Some lines feed into the WR vault and others remove product and waste out of the WR Vault. The line numbers that are part of this segment of 200-W-105-PL include 4878, 4832, 4876, 4897, 4702, 4703, 4707, 4701, 4700, 4855, 4854 and 4853. Some of the process lines were installed, but never used. Some lines pass through the 241-UX-154 Diversion box and connect to section 11, 12 and 13 of the 221-U process building. Some lines were rerouted in 1970 to support the Redox Supernate Transfer System (per H-2-35865).

Waste Type: Process Effluent

Waste Description: The pipeline transferred waste to the 241-TX Tank Farm.

Code: 200-W-110 **Classification:** Not Accepted (Proposed)

Names: 200-W-110; Miscellaneous Stream #393 **Reclassification:** None

Type: Injection/Reverse Well **Start Date:**

Status: Unknown **End Date:**

Description: A 2003 field walkdown was unable to locate a drain structure from the description provided in DOE/RL-88-11. In 2005, the 222-U building was demolished and the area was covered with gravel (see 200-W-136).

Location: The drain was on the east side of the 222-U building. The 222-U building has been demolished. Unable to locate in the field.

Process Description: The drain received storm water run off from the 222-U facility.

Code: 200-W-114 **Classification:** Discovery

Names: 200-W-114; Miscellaneous Stream #55 **Reclassification:** None

Type: Injection/Reverse Well **Start Date:**

Status: Unknown **End Date:**

Description: The drain was not visually apparent at the location described in DOE/RL-88-11 as being located on the southeast side of 224-U. The entire south side of 224-U and 224-UA was covered with asphalt. 224-U has been demolished. A 2012 assessment indicates the drain structure has been removed. The remediation area was covered with gravel.

Location: The drain was described in DOE/RL-88-11 as being located in the asphalt area south of 224-U.

Code: 200-W-125-PL **Classification:** Accepted

Names: 200-W-125-PL; 216-Z-1 Ditch Replacement Pipeline **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The site is an underground buried pipeline installed to transfer effluent from 231-Z to the 216-Z-

11, 216-Z-19 and 216-Z-20 Ditches after the 216-Z-1 Ditch was abandoned. Subsite 1 is the pipeline is a 0.46 meter (18 inch) diameter vitrified clay pipe extending from 231-Z to the 216-Z-19 ditch. When 216-Z-11 and 216-Z-19 ditches were discontinued, the effluent was diverted to 216-Z-20 via a 38 centimeter (15 inch) diameter polyvinyl chloride pipe (subsite 2).

Location: The pipeline extends east from the 231-Z building and turns south to connect with the head end of the 216-Z-11 Ditch.

Related Sites/ Structures: The site is associated with 216-Z-1 Ditch, 216-Z-11 Ditch, 216-Z-20 crib and the 231-Z building.

Process Description: The pipeline was installed to transfer effluent from 231-Z to the 216-Z-11, 216-Z-19 and 216-Z-20 Ditches after the 216-Z-1 Ditch was abandoned.

This Site has the Following SubSites:

Code: 200-W-125-PL:1

Names: 200-W-125-PL:1; 18-Inch VCP Pipeline from 231-Z to 216-Z-11 and 216-Z-19 Ditches

Code: 200-W-125-PL:2

Names: 200-W-125-PL:2; 15-Inch PVC Pipe from Manhole to 216-Z-20

Code: 200-W-125-PL:1

Classification: Accepted

Names: 200-W-125-PL:1; 18-Inch VCP Pipeline from 231-Z to 216-Z-11 and 216-Z-19 Ditches

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: Subsite 1 is the vitrified clay pipeline (VCP) that extends from the 231-Z building to the 216-Z-11 and 216-Z-19 ditches.

Location: Subsite 1 is located mostly east of the PFP facility fence.

Process Description: The clay pipeline was installed to transfer effluent from 231-Z to the 216-Z-11 and 216-Z-19

Ditches after the 216-Z-1 Ditch was abandoned.

The SubSite is Part Of:

Code: 200-W-125-PL

Names: 200-W-125-PL; 216-Z-1 Ditch Replacement Pipeline

Code: 200-W-125-PL:2

Classification: Accepted

Names: 200-W-125-PL:2; 15-Inch PVC Pipe from Manhole to 216-Z-20

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: Subsite 2 is the 15 inch diameter, polyvinyl chloride (PVC) pipe that extends from the 200-W-125-PL:1, vitrified clay pipeline to the 216-Z-20 crib.

Location: Subsite 2 is located north of the head end of the 216-Z-20 crib.

The SubSite is Part Of:

Code: 200-W-125-PL
Names: 200-W-125-PL; 216-Z-1 Ditch Replacement Pipeline

Code: 200-W-126 **Classification:** Accepted
Names: 200-W-126; Tank Farm Vertical Storage Units; Vertical Storage Units West of 241-T Tank Farm **Reclassification:** None
Type: Storage **Start Date:**
Status: Inactive **End Date:**

Description: The site consists of six vertical storage units. The units were constructed of steel pipes approximately 0.3 meters (1 foot) in diameter and 2 meters (6 feet) deep. They extend approximately 0.1 meters (4 inches) above the ground surface.

Location: The six storage units are located near the outside of the 241-T Tank Farm fence. They are approximately 10 meters (30 feet) west of the tank farm and north of 23rd Street. They are located within a large Underground Radioactive Material area that includes the 216-T-7 tile field and the 216-T-5 crib.

Related Sites/ Structures: The units are associated with the 241-T Tank Farm.

Process Description: The Vertical Storage Units (VSU) were used to store dry, radiologically contaminated tank farm equipment, like shield plugs and slurry distributor handles or contaminated soil. The units are currently empty and have been capped.

Waste Type: Equipment

Waste Description: The units were used to store radioactively contaminated pieces of equipment like shield plugs and distributor handles.

Code: 200-W-129-PL **Classification:** Accepted
Names: 200-W-129-PL; Encased Pipeline from 241-T-151 and 241-T-152 to 241-TX-155 Diversion Box; Lines V399, V405 and V411 **Reclassification:** None
Type: Encased Tank Farm Pipeline **Start Date:** 1/1/1950
Status: Inactive **End Date:**

Description: The site is an underground cement encasement containing three carbon steel pipelines. The encasement is marked and posted with Underground Radioactive Material and Pipeline signs.

Location: The encased pipeline connects the 241-T-151 and 241-T-152 Diversion Boxes, located inside 241-T Tank Farm to the 241-TX-155 Diversion Box, located south of 23rd Street and north of the Powerhouse Pond.

Related Sites/ Structures: The pipelines are associated with 241-T-151, 241-T-152 and 241-T-155 diversion boxes and UPR-200-W-113.

Process Description: The encasement contains lines V399, V405 and V411. Each pipeline is made of 7.6 centimeter (3 inch) diameter carbon steel. The lines connect 241-T-151 and 241-T-152 with 241-TX-155.

Code: 200-W-130-PL **Classification:** Accepted
Names: 200-W-130-PL; Lines V445, V663, V601 and **Reclassification:** None

V416 and Spare Lines V662, V663, V682 and V683; Pipelines from 241-T-151 and 241-T-152 Diversion Boxes to 241-U-151 Diversion Box

Type: Direct Buried Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: The site is a soil trench that contains multiple stainless steel pipelines exiting the 241-T-151 and 241-T-152 diversion boxes. Each line is 7.6 centimeters (3 inches) in diameter. Three lines (V445, V663, V662) extend south from the 241-T-151 diversion box. Three other lines (V601, V682 V683) extend south from 241-T-152 diversion box. One line from each diversion box (V445 and V601) merge together south of 241-T tank farm, south of 23rd Street and continue to 241-U-152 diversion box. The lines are encased in concrete only where they pass under 23rd Street. Line V663 was activated to feed the 216-T-36 crib and ties into 200-W-79-PL. The remaining lines (V662, V682 and V683) were not activated and are considered Spare lines.

Location: The majority of this pipeline is located east of Camden Ave. It connected the 241-T-151 and 241-T-152 Diversion Boxes, located inside 241-T Tank Farm, to the 241-U-151 Diversion Box, located east of 241-U Tank Farm. Lines V445, V663 and V662 extend from 241-T-151 Diversion Box. Lines V601, V682 and V683 extend from 241-T-152 Diversion Box. The two sets of pipelines join together south of 241-T tank farm, south of 23rd Street.

Release Description: See UPR-200-W-29.

Related Sites/ Structures: The site is associated with, 200-W-79-PL and 200-W-131-PL. Line V601 is associated with UPR-200-W-29.

Process Description: Lines V445, V662 and V663 exit the 241-T-151. Lines V662 and V663 exit 241-T-151 diversion box in the same trench as V445. V662 and V663 were originally spare lines that were cut and capped south of the diversion box, outside the tank farm fence. Line V663 was reactivated in 1967 to connected to the 216-T-36 crib (see sitecode 200-W-79-PL). V445 continues south to 241-U-151. Lines V601, V682 and V683 exit 241-T-152 diversion box. V682 and V683 were spare lines that were cut and capped south of 241-T tank farm, outside the tank farm fence. Line V601 merges with line V445 south of 241-T Tank Farm and shares the same trench until V601 diverts to 241-TX tank farm. Line V416 enters the soil trench from 241-TX tank farm at the point where V601 leaves the trench. South of 241-TX tank farm, line V445 shares the same trench with line V416 until they connect to 241-U-152 diversion box.

Code: 200-W-131-PL **Classification:** Accepted

Names: 200-W-131-PL; Line V601; Spur from 241-T-152 to 241-TX-153 and 241-U-151 **Reclassification:** None

Type: Direct Buried Tank Farm Pipeline **Start Date:** 8/30/1950

Status: Inactive **End Date:**

Description: The waste site is a 7.6 centimeter (3 inch) diameter, stainless steel pipeline in a soil trench that originally transferred waste from 241-T farm to 241-U farm. In 1950, a tee was made to redirect effluent to 241-TX Tank Farm.

Location: The majority of this pipeline is located east of Camden Ave. It connected the 241-T-152 Diversion Box, located inside 241-T Tank Farm, to the 241-U-151 Diversion Box, located east of 241-U Tank Farm. In 1950, a tee was made to redirect effluent to 241-TX Tank Farm.

Related Sites/ Structures: The site is associated with WIDS site 200-W-130-PL, 241-T-152, 241-T Tank Farm, 241-TX Tank Farm, 241-TX-153 and 241-U Tank Farm.

Process Description: Line V601 originally connected 241-T-152 and 241-U-151. Line V601 was cut in 1950 and rerouted to 241-TX Tank Farm with an east/west pipe spur and a tee connection to 241-TX-153 diversion box. The north portion of the pipeline connected 241-T Tank Farm with 241-TX Tank Farm. The southern portion of the pipeline connected 241-U Tank Farm with 241-TX Tank Farm.

Code: 200-W-132-PL **Classification:** Accepted

Names: 200-W-132-PL; Pipelines from 221-T to 241-T-151 and 241-T-152; V653, V654, V667, V668, V669, V706, and V707 **Reclassification:** None

Type: Direct Buried Tank Farm Pipeline **Start Date:** 1/1/1945

Status: Inactive **End Date:**

Description: Seven, 7.6 centimeter (3 inch) diameter, pipelines are contained in the same soil trench. Three lines - V653, V654 and V706 are 7.6 centimeter (3 inch) diameter stainless steel lines. Four lines - V667, V668, V669 and V707 are 7.6 centimeter (3 inch) diameter carbon steel line. The group of pipelines is marked with Underground Radioactive Material and Pipeline signs.

Location: The bundle of pipelines begins at 221-T and terminates at the 241-T-151 Diversion Box in the 241-T Tank Farm.

Process Description: The pipelines transported T Plant waste to the 241-T-151 and 241-T-152 diversion boxes, inside 241-T Tank Farm. Some of the lines are stainless steel and others are carbon steel.

Line V653 is a 3 inch diameter stainless steel line from section 10 of 221-T.

Line V654 is a 3 inch diameter stainless steel line from section 9 of 221-T.

Line V667 is a 3 inch diameter carbon steel line from section 5 of 221-T.

Line V668 is a 3 inch diameter carbon steel line from section 15 of 221-T.

Line V669 is a 3 inch diameter carbon steel line from section 15 of 221-T.

Line V706 is a 3 inch diameter stainless steel line from 224-T. (re-routed from 216-T-3 reverse well in late 1946 - see 200-W-226-PL)

Line V707 is a 3 inch diameter carbon steel line from section 10 of 221-T.

Code: 200-W-136 **Classification:** Accepted

Names: 200-W-136; Demolished 224-U, 224-UA, 203-U, 203-UX, 222-U; Posted Underground Radioactive Material Area; Potential Asbestos in Soil **Reclassification:** None

Type: Post Demolition Remediation Area **Start Date:** 1/1/1947

Status: Inactive **End Date:** 1/1/2005

Description: The waste site was originally an irregular shaped gravel area, posted with Underground Radioactive Material Area (URMA) signs, created after the demolition of the 222-U building. In 2011, the URMA boundary was greatly expanded. It was extended up to the back side of 221-U. The expansion eliminated the need for a separate radiological posting for the UPR-200-W-162 waste site. The posted area also includes the demolished 224-U and 224-UA, 203U, 203UX and the 272-U Hot Shop building footprints. They are beneath the URMA gravel cover. The expanded area also includes 241-UX-154, UPR-200-W-162 and 291-U and the 291-U Sand Filter (sitecode 200-W-44).

The determination of potential asbestos containing material (ACM) left in place and abated during demolition of 224-U, 224-UA and 203-UX is based on a 2013 Quality Assurance review of project documentation and interviews with activity personnel.

Location: The site is located southeast of the 221-U canyon building, north of 16th St and west of Beloit Ave.

Related Sites/ Structures: The large, posted URMA encompasses the demolished 222-U, 224-U, 224-UA, 203-UX and 272-U facility footprints, french drains 200-W-107, 200-W-108, 200-W-109, 200-W-111, 200-W-112, 200-W-113, 200-W-114, and the 216-U-4, 216-U-4A and 216-U-4B reverse wells. The expanded area also includes 241-UX-154, UPR-200-W-162 and 291-U and the Sand Filter (sitecode 200-W-44). It is also associated with UPR-200-W-101, UPR-200-W-138 and UPR-200-W-162.

Process Description: 221-U was built in 1945 as a Bismuth Phosphate Separation Facility. The Bismuth Phosphate process separated only the plutonium from the dissolved irradiated fuel rods. All the uranium and fission products were transferred to the tank farm storage tanks. U Plant was the same design as B Plant and T Plant. This design included installing seven, 3 inch stainless steel (direct buried) lines from 221-U to 241-U-151 diversion Box (see H-2-800 and H-2-804). After the B and T plants began to operate, it was decided that U Plant would not be needed for its original purpose. From 1945 until 1952, it was used as training facility for workers assigned to the B and T Plants. In 1952, the 221-U facility was reconfigured to operate the Uranium Metal Recovery (tributyl phosphate) process. The majority of the original seven transfer lines connected to 241-U-151 were removed, although remnants of the lines may still remain near the diversion box and behind 221-U. The process recovered uranium from the waste stored in the tank farms that had been generated from the bismuth phosphate separation process at B and T Plants. The Uranium Recovery Process operated until 1958.

The 222-U building supported the 221-U canyon as a Sample Preparation Laboratory. The function of the laboratory was to test the 221-U process solutions at various stages to verify the process was working within the process specifications. The aboveground 203-U tanks were associated with the 224-U and 224-UA facility Uranium Tri-Oxide process. The 203 tanks consisted of a concrete enclosure containing two 375,000 liter (100,000 gallon) uranyl nitrate feed tanks.

Code: 200-W-137-PL

Classification: Accepted

Names: 200-W-137-PL; Line V533; Pipeline from 241-S-151 Diversion Box to 216-S-1 & 2 Cribs

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The site is an underground pipeline from the 241-S-151 Diversion box to the 216-S-1 & 2 cribs. The pipeline exits the diversion box in a 3 line concrete encasement. Two spare lines divert to the east and are stubbed. One, double contained (pipe-in pipe), pipeline extends to the crib. It is constructed of a 8.9 centimeter (3.5 inch), outside diameter 40 gauge stainless steel tubing that is encased in a 15.2 centimeter (6 inch) diameter, schedule 40 steel pipe.

Location: The pipeline and cribs are located east of the 241-SX Tank Farm. A concrete encased portion of the pipeline is located inside the tank farm fence. The double contained pipe to the cribs is located outside the tank farm fence.

Related Sites/ Structures: The pipeline is associated with the 241-S-151 Diversion Box and the 216-S-1&2 cribs.

Code: 200-W-138-PL **Classification:** Accepted

Names: 200-W-138-PL; Pipeline from 240-S-151 to 216-S-7 Crib; V547 **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The site is an underground pipeline, extending from an encased pipeline (200-W-98-PL) to the 216-S-7 Crib. It is a 7.6 centimeter (3 inch) diameter, stainless steel pipe that diverted from the 200-W-98-PL encasement.

Location: The 216-S-7 crib and associated pipeline are located northwest of the 202-S building.

Related Sites/ Structures: The pipeline is associated with the 216-S-7 crib, the 240-S-151 diversion box and the encased pipeline 200-W-98-PL.

Process Description: Line V547 extends from the encased pipeline (200-W-98-PL) to 216-S-7.

Code: 200-W-139-PL **Classification:** Accepted

Names: 200-W-139-PL; Pipeline from 200-W-138-PL to 216-S-9 Crib; V547 **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 7.6 centimeter (3 inch), stainless steel pipeline to the 216-S-9 crib. When the 216-S-9 crib was built to replace the 216-S-7 crib, the pipeline (200-W-138-PL) was extended to tie into the 216-S-9 crib. Line V547 emerges from an encased pipeline (200-W-98-PL).

Location: The pipeline is located northwest of the 202-S facility.

Release Description: UPR-200-W-108 occurred on January 8, 1969, during the tie-in that diverted waste to the 216-S-23 crib.

UPR-200-W-109 occurred on January 24, 1969. UPR-200-W-109 states that after repairing the buckled portions of the waste line near the 216-S-9 crib, a pressure test indicated another leak in the line. Additional hydrostatic testing finally forced the water to bubble to the surface. It surfaced inside the radiation zone marking the 218-W-9 burial trench. Dose rates of the liquid were 450 mR/hr, but as the water sank back into the soil, the dose rate dropped to 20 mR/hr. Excavation of the liquid bubble site disclosed a vertical buckle in the pipeline with a sizable break in the line at that point. (RHO-CD-673)

Related Sites/ Structures: The pipeline is associated with UPR-200-W-108, UPR-200-W-109, 216-S-7, 216-S-9 cribs, 216-S-23, 200-W-138-PL, the 200-W-98 encased pipeline and the 240-S-151 diversion box.

Process Description: When the 216-S-9 crib was built to replace the 216-S-7 crib, the extended pipeline was tied into the 216-S-7 pipeline (see 200-W-138-PL). Line V547 emerges from an encased pipeline (200-W-98-PL).

Code: 200-W-140-PL **Classification:** Accepted

Names: 200-W-140-PL; Pipeline from 292-T (200-W-40) to 216-T-8 Crib via 200-W-142-PL **Reclassification:** None

Process Description: 222-T laboratory waste was sent to the 216-T-8 crib via this pipeline. In 1949, the effluent line from 292-T (sitecode 200-W-140-PL) was also connected to this crib pipeline.

Code: 200-W-143-PL **Classification:** Accepted

Names: 200-W-143-PL; Encased Pipeline from 241-TX-154 Diversion Box to 241-TX-152 and 241-TX-155 Diversion Boxes; Lines V383, V384, V385, V387, V388, V391, V392, and V393 **Reclassification:** None

Type: Encased Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, concrete encased pipeline. The pipelines inside the encasement are 9 centimeter (3.5 inch) diameter stainless steel lines. The majority of the encasement contains seven stainless steel pipelines (V383, V384, V385, V387, V388, V391, V392). There is a section of nine stainless steel lines near the 241-TX-154 Diversion Box. This section contains the seven lines (mentioned above) and two, short stub lines - V728 and V729. The section of pipeline near the 241-TX-155 Diversion Box contains ten lines. This section contains the seven main lines (mentioned above), an extra line from the 241-TX-302B catch tank (V393) and two short stub lines (V390 and V386).

Location: The encased pipeline begins at the 241-TX-154 Diversion Box. It runs diagonally south of 23rd Street and terminates at the 241-TX-155 Diversion Box.

Related Sites/ Structures: The site is associated with the 221-T facility operations, the 241-TX-154 diversion box and the 241-TX-152 and 241-TX-155 Diversion Boxes.

Code: 200-W-144 **Classification:** Discovery

Names: 200-W-144; Room 4E 222-S Laboratory TSD **Reclassification:** None

Type: Storage **Start Date:**

Status: Active **End Date:**

Description: The TSD is located inside the 222-S building, in Room 4E.

Code: 200-W-146-PL **Classification:** Accepted

Names: 200-W-146-PL; Pipeline from 293-S to 216-S-22 Crib **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:** 1/1/1957

Status: Inactive **End Date:** 1/1/1967

Description: The pipeline is a 10 centimeter (4 inch) diameter, vitrified clay pipe. The pipeline extends from the 293-S building to the 216-S-22 crib. The piping in the 293-S Building was blanked in 1967.

Location: It is located east of the 202-S (REDOX) building.

Related Sites/ Structures: The pipeline is associated with the 216-S-22 crib.

Process Description: The site provided subsurface liquid disposal for the 293-S Building waste. The crib is a gravel structure with a side slope of 1:1.5. A pipe enters the unit below grade, branches out at right

angles downwards to the bottom, and runs along the bottom for the length of the unit. The section of pipe along the crib bottom has open joints. The rest of structure is filled with backfill.

Code: 200-W-147-PL-B **Classification:** Accepted

Names: 200-W-147-PL-B; Portion of Pipeline in the 200 West Inner Area **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: Due to the restructuring of Operable Units, as described in the Agreement for Central Plateau Cleanup, the original pipeline site (200-W-147-PL) has been split into segments. It was an underground 20 centimeter (8 inch) diameter vitrified clay pipe, extending from the 207-SL retention basin to the 216-S-19 pond. 200-W-147-PL-B is the portion of pipeline that extends from the 207-SL basin to the Outer Area boundary.

Location: This portion of pipeline is located east of the 222-S laboratory facility, inside 200 West Area, in the Inner Area. It extends from the 207-SL basin to the Inner/Outer Area boundary.

Related Sites/ Structures: This portion of pipeline is associated with the 207-SL basin, 216-S-19 Pond, 216-S-26 crib and 200-W-147-PL-A.

Process Description: The pipeline carried waste from the 222-S and 202-S facilities to the 216-S-19 Pond and 216-S-26 crib via the 207-SL Retention Basin.

Code: 200-W-149-PL **Classification:** Accepted

Names: 200-W-149-PL; Pipelines Related to 216-S-20 Crib **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: There are three source facilities that fed the 216-S-20 crib. Each source had separate pipelines to the crib. Two, side by side, 9 centimeter (3.5 inch) diameter stainless steel lines extends from 219-S to the 216-S-20 Crib. One 20 centimeter (8 inch) diameter, carbon steel line extends from the 207-SL Retention Basin valve pit to the 216-S-20 Crib. Another 15 centimeter (6 inch) diameter carbon steel pipeline extends from the truck unloading station to the 216-S-20 crib. (see subsites)

Location: The 216-S-20 crib and associated pipelines are located northeast of the 222-S laboratory and 207-SL Retention Basin.

Related Sites/ Structures: The 216-S-20 crib effluent was associated with the 219-S building, the 207-SL Retention Basin and the lab waste truck unloading station.

Process Description: The 216-S-20 crib received waste from lab hoods and decontamination sinks in the 222-S building via the 219-S Retention Building and the 207-SL Retention Basin. It also received 300 Area laboratory waste via trucks, unloaded into the manhole at the adjacent waste unloading station.

This Site has the Following SubSites:

Code: 200-W-149-PL:1

Names: 200-W-149-PL:1; Two Stainless Steel Lines from 219-S to 216-S-20 Crib

Code: 200-W-149-PL:2
Names: 200-W-149-PL:2; 8-Inch Diameter Carbon Steel Line from 207-SL Retention Basin to 216-S-20 Crib
Code: 200-W-149-PL:3
Names: 200-W-149-PL:3; 8-Inch Diameter Carbon Steel Line from Lab Waste Truck Unloading Station to the 216-S-20 Crib

Code: 200-W-149-PL:1 **Classification:** Accepted
Names: 200-W-149-PL:1; Two Stainless Steel Lines from 219-S to 216-S-20 Crib **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: Two, side by side, 9 centimeter (3.5 inch) diameter stainless steel lines extends from 219-S to the 216-S-20 Crib.

The SubSite is Part Of:

Code: 200-W-149-PL
Names: 200-W-149-PL; Pipelines Related to 216-S-20 Crib

Code: 200-W-149-PL:2 **Classification:** Accepted
Names: 200-W-149-PL:2; 8-Inch Diameter Carbon Steel Line from 207-SL Retention Basin to 216-S-20 Crib **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: One 20 centimeter (8 inch) diameter, carbon steel line extends from the 207-SL Retention Basin valve pit to the 216-S-20 Crib.

The SubSite is Part Of:

Code: 200-W-149-PL
Names: 200-W-149-PL; Pipelines Related to 216-S-20 Crib

Code: 200-W-149-PL:3 **Classification:** Accepted
Names: 200-W-149-PL:3; 8-Inch Diameter Carbon Steel Line from Lab Waste Truck Unloading Station to the 216-S-20 Crib **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: One 15 centimeter (6 inch) diameter carbon steel pipeline extends from the truck unloading station to the 216-S-20 crib.

The SubSite is Part Of:

Code: 200-W-149-PL
Names: 200-W-149-PL; Pipelines Related to 216-S-20 Crib

Code: 200-W-150-PL **Classification:** Accepted

Names: 200-W-150-PL; Pipelines Associated with 216-S-13 Crib **Reclassification** None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is a series of pipelines extending from the 205-S, 204-S, 203-S and 267-S facilities to the 216-S-13 Crib. The waste site has been divided into four subsites.

Location: The 203-S, 204-S, 205-S, 276-S and associated pipelines are located northwest of the 202-S (REDOX) facility.

Related Sites/ Structures: The pipelines are associated with the REDOX process, the 203-S, 204-S, 205-S and 276-S buildings and WIDS site 200-W-22 Stabilized Area.

This Site has the Following SubSites:

Code: 200-W-150-PL:1

Names: 200-W-150-PL:1; Pipeline from 276-S to the 216-S-13 Crib

Code: 200-W-150-PL:2

Names: 200-W-150-PL:2; Pipeline from 203-S Connecting to the 276-S Crib Line

Code: 200-W-150-PL:3

Names: 200-W-150-PL:3; Pipeline from 204-S Connecting to the 203-S Line

Code: 200-W-150-PL:4

Names: 200-W-150-PL:4; Pipeline from the 205-S Vault Connecting to the 204-S Line

Code: 200-W-150-PL:1 **Classification:** Accepted

Names: 200-W-150-PL:1; Pipeline from 276-S to the 216-S-13 Crib **Reclassification** None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The subsite pipeline extends from the 276-S building to the 216-S-13 crib. It is constructed of 15 centimeter (6 inch) diameter vitrified clay pipe, wrapped in concrete.

Location: The 203-S, 204-S, 205-S, 276-S and associated pipelines are located northwest of the 202-S (REDOX) facility.

The SubSite is Part Of:

Code: 200-W-150-PL

Names: 200-W-150-PL; Pipelines Associated with 216-S-13 Crib

Code: 200-W-150-PL:2 **Classification:** Accepted

Names: 200-W-150-PL:2; Pipeline from 203-S Connecting to the 276-S Crib Line **Reclassification** None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The subsite pipeline is constructed of 10 centimeter (4 inch) diameter vitrified clay pipe wrapped in concrete. It extends southward from the 203-S building and connects to the 15 centimeter (6" inch) line going to the 216-S-13 crib. (see subsite 1)

Location: The 203-S, 204-S, 205-S, 276-S and associated pipelines are located northwest of the 202-S (REDOX) facility.

The SubSite is Part Of:**Code:** 200-W-150-PL**Names:** 200-W-150-PL; Pipelines Associated with 216-S-13 Crib

Code: 200-W-150-PL:3 **Classification:** Accepted

Names: 200-W-150-PL:3; Pipeline from 204-S **Reclassification** None
Connecting to the 203-S Line

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The subsite pipeline extends from the 204-S building. It is constructed of 15 centimeter (6 inch) diameter vitrified clay pipe, wrapped in concrete. It connects to the pipeline coming out of 203-S (See subsite 2).

Location: The 203-S, 204-S, 205-S, 276-S and associated pipelines are located northwest of the 202-S (REDOX) facility.

The SubSite is Part Of:**Code:** 200-W-150-PL**Names:** 200-W-150-PL; Pipelines Associated with 216-S-13 Crib

Code: 200-W-150-PL:4 **Classification:** Accepted

Names: 200-W-150-PL:4; Pipeline from the 205-S Vault **Reclassification** None
Connecting to the 204-S Line

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The subsite pipeline is constructed of 10 centimeter (4 inch) diameter vitrified clay pipe wrapped in concrete. It extends southeast from the 205-S building and connects to the 15 centimeter (6" inch) line coming out of the 204-S facility. (see subsite 3).

Location: The 203-S, 204-S, 205-S, 276-S and associated pipelines are located northwest of the 202-S (REDOX) facility.

The SubSite is Part Of:**Code:** 200-W-150-PL**Names:** 200-W-150-PL; Pipelines Associated with 216-S-13 Crib

Code: 200-W-151-PL **Classification:** Accepted

Names: 200-W-151-PL; 200-W-42 Pipe Remaining **Reclassification** None
Under 16th Street

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive**End Date:****Description:** The piece of pipeline remaining under 16th Street is not visible, nor is it marked with a sign.**Location:** The pipe is located southeast of the demolished 224-UA building, beneath the 16th Street asphalt.**Related Sites/
Structures:** The site is associated with the 221-U and 224-U facilities, 270-W tank and the pipeline that fed 216-U-8 and 216-U-12 cribs (see sitecode 200-W-42-PL) and the encased tank farm line 200-W-100-PL.**Process
Description:** WIDS sitecode 200-W-42 (alias 200-W-42-PL) is the underground vitrified clay pipeline transferred process condensate from the 221-U and 224-U Buildings and the 291-U Stack, through the 270-W neutralization tank to the 216-U-8 and 216-U-12 Cribs.**Waste Type:** Process Effluent**Waste
Description:** From 1952 to 1960, the line transferred waste from 221-U, 224-U and 291-U to the 216-U-8 crib. The 216-U-12 crib replaced the 216-U-8 crib in 1960. The pipeline was extended further south to the 216-U-12 location. From April 1960 to May 1967, the pipeline received waste from the 291-U-1 Stack drainage, 241-WR Vault waste, and 224-U process condensate via C-5 Tank. Disposal of contaminated water from 241-WR Vault was accomplished in October 1965 and included 3.14 kilograms (6.9 pounds) of thorium. From May 1967 to September 1972, the site received the above wastes excluding the 241-WR Vault waste and occasional waste via the C-7 Tank in the 244-U Building. From September 1972 to November 1981, the site was taken out of service. After November 1981, the pipeline received process condensate (corrosive: typical pH range is 0.5-1.5) from the 224-U Building. In the past, this facility also received miscellaneous storm drain wastes from 224-U. A Limited Field Investigation was done in 1994 to characterize selected waste sites in the 200-UP-2 Operable Unit. Fourteen surface and subsurface soil samples along with four vegetation samples were collected to characterize the vitrified clay pipeline (VCP) leading to the 216-U-8 Crib. An attempt was made to determine if the contamination had spread laterally from the pipeline by digging holes with an auger rig where subsurface contamination had been identified. An increase in activity was noted at approximately 3 meters (10 feet). At a depth of 3.3 meters (11 feet) the auger was stopped by large cobbles. The samples were analyzed for cesium-137, strontium-90, gross alpha and gross beta. Specific sample data is documented in BHI-00033.**Code:** 200-W-152-PL**Classification:** Accepted**Names:** 200-W-152-PL; Pipeline from 202-S to 2904-S-170 Control Structure and 216-S-17 Pond; REDOX Process Sewer**Reclassification:** None**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** The site is an underground, 61 centimeter (24 inch) diameter vitrified clay pipe that begins at the 202-S (REDOX) building. The pipeline is not visible, but a metal sample shack is located over the western end, above the 2904-S-170 control structure. South of 200 West Area, seven manholes are visible on the surface along the pipeline.**Location:** The pipeline is located west and southwest of the 202-S (REDOX) building.**Related Sites/
Structures:** The pipeline was associated with 202-S (REDOX building), 207-S Retention Basin, 216-S-17 Pond, and 2904-S-170.**Process
Description:** The pipeline carried liquid waste from the REDOX facility to the 2904-S-170 control structure, before it was sent to the liquid waste disposal sites (207-S, 216-S-16, 216-S-17).

Code: 200-W-153-PL **Classification:** Accepted

Names: 200-W-153-PL; Steel Pipeline from 240-S-151 Diversion Box to the 2904-S-172 and 2904-S-171 Control Structures via 200-W-212-PL **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground a 25 centimeter (10 inch) diameter steel pipeline that fed the 2904-S-172 Control Structure and a short 30 centimeter (12 inch) diameter pipeline that exits the south side of the Control Structure and connects to the 61 centimeter VCP line (sitecode 200-W-152-PL). See subsites 1 and 2. Three lines (V550, V544 and V548) exit the encased 200-W-212-PL encasement (connected to 240-S-151 diversion box). The three lines that exit the encasement merge together to form a single line and becomes 200-W-153-PL.

Location: The pipeline begins inside the 200 West Area, at the end of the 200-W-212-PL encasement. The single, direct buried line extends in a southwesterly direction, extending outside the 200 West Perimeter fence and extends to the 2904-S-172 and 241-S-171 Control Structures.

Related Sites/ Structures: The pipeline is associated with 240-S-151, 2904-S-172, 2904-S-171, 216-S-5 and pipeline 200-W-212-PL.

This Site has the Following SubSites:

Code: 200-W-153-PL:1

Names: 200-W-153-PL:1; Pipeline from 240-S-151 to 2904-S-172 via 200-W-212-PL

Code: 200-W-153-PL:2

Names: 200-W-153-PL:2; Pipeline from 2904-S-172 to 216-S-17 Pond

Code: 200-W-153-PL:1 **Classification:** Accepted

Names: 200-W-153-PL:1; Pipeline from 240-S-151 to 2904-S-172 via 200-W-212-PL **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: A 25 centimeter (10 inch) diameter underground steel pipeline from the 240-S-151 Diversion Box to the 2904-S-172 Control Structure and continues to the 2904-S-171 Control Structure.

The SubSite is Part Of:

Code: 200-W-153-PL

Names: 200-W-153-PL; Steel Pipeline from 240-S-151 Diversion Box to the 2904-S-172 and 2904-S-171 Control Structures via 200-W-212-PL

Code: 200-W-153-PL:2 **Classification:** Accepted

Names: 200-W-153-PL:2; Pipeline from 2904-S-172 to 216-S-17 Pond **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: A 30 centimeter (12 inch) diameter steel pipeline that exits the south side of the Control Structure and connects to the 61 centimeter (24 inch) VCP line (sitecode 200-W-152-PL).

Process Description: This segment allowed effluent to be sent to 216-S-17 Pond. 216-S-17 Pond was deactivated in 1954.

The SubSite is Part Of:

Code: 200-W-153-PL

Names: 200-W-153-PL; Steel Pipeline from 240-S-151 Diversion Box to the 2904-S-172 and 2904-S-171 Control Structures via 200-W-212-PL

Code: 200-W-154-PL **Classification:** Accepted

Names: 200-W-154-PL; Pipeline from 200-W-152-PL to 216-S-5 Crib **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground 61 centimeter (24 inch) diameter vitrified clay pipeline that feeds the 216-S-5 crib. The pipeline connects to the 200-W-152-PL.

Location: The pipeline is located outside the 200 West Area perimeter fence, southwest of 207-S.

Related Sites/Structures: The site is associated with the REDOX cooling water effluent stream (202-S Redox Building) and the 200-W-152-PL pipeline and the 216-S-5 Crib.

Process Description: The 216-S-5 crib was built as a replacement for the grossly contaminated 216-S-17 pond. The 216-S-5 crib received the process vessel cooling water and steam condensate from the 202-S (REDOX) building.

Code: 200-W-155-PL-A **Classification:** Accepted

Names: 200-W-155-PL-A; Portion of 200-W-155-PL Pipeline in the Outer Area **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: Due to the restructuring of Operable Units, as described in the Agreement for Central Plateau Cleanup, the original pipeline site (200-W-155-PL) has been split into segments (200-W-155-PL-A and 200-W-155-PL-B). The original pipeline was an underground 61 centimeter (24 inch) diameter vitrified clay pipe. It extends from the 2904-S-160 Control Structure to the head end of the 216-S-16 Ditch. 200-W-155-PL-A is the portion of the pipeline that is located in the Central Plateau Outer Area.

Location: This portion of pipeline extends from the Inner/Outer Area boundary to the head end of the 216-S-16 Ditch.

Related Sites/Structures: The waste site is associated with the 216-S-16 ditch and the 200-W-155-PL-B pipeline.

Process Description: In 1954, the original 61 centimeter (24 inch) process sewer line (sitecode 200-W-152-PL) was plugged and the flow to the 216-S-17 Pond was abandoned. The effluent was directed to the 216-S-6 crib and later to the 216-S-16 Pond via the 2904-S-160 Control Structure. Flow could be directed to 216-S-6 crib at Manhole 8 via pipeline 200-W-156-PL or to the 216-S-16 Ditch

and Pond via pipeline 200-W-155-PL-A and B.

Code: 200-W-155-PL-B **Classification:** Accepted

Names: 200-W-155-PL-B; Portion of Pipeline 200-W-155-PL that is located in the Central Plateau Inner Area **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: Due to the restructuring of Operable Units, as described in the Agreement for Central Plateau Cleanup, the original pipeline site (200-W-155-PL) has been split into segments. It extends from the 2904-S-160 Control Structure to the Inner/Outer Area boundary. 200-W-155-PL-B is the portion of the pipeline that is located in the Central Plateau Inner Area. The original pipeline was an underground 61 centimeter (24 inch) diameter vitrified clay pipe.

Location: 200-W-155-PL-B is the portion of pipeline that extends from the 2904-S-160 Control Structure to the Inner/Outer Area boundary.

Related Sites/ Structures: The waste site is associated with the 2904-S-160 control Structure and the 200-W-155-PL-A pipeline.

Process Description: In 1954, the original 61 centimeter (24 inch) process sewer line (sitecode 200-W-152-PL) was plugged and the flow to the 216-S-17 Pond was abandoned. The effluent was directed to the 216-S-6 crib and later to the 216-S-16 Pond via the 2904-S-160 Control Structure. Flow could be directed to 216-S-6 crib at Manhole 8 via pipeline 200-W-156-PL or to the 216-S-16 Ditch and Pond via pipeline 200-W-155-PL-A and B.

Code: 200-W-156-PL **Classification:** Accepted

Names: 200-W-156-PL; 216-S-6 Crib Pipeline; Pipeline from 200-W-155-PL to the 2904-S-171 Control Structure **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground 46 centimeter (18 inch) diameter vitrified clay pipeline extending from Manhole 8 on the 200-W-155-PL pipeline to the 2904-S-171 Control Structure and the 216-S-6 crib.

Location: The pipeline is located outside the 200-West Area fence, southwest of the 202-S (REDOX) building.

Related Sites/ Structures: The pipeline is associated with 200-W-155-PL, 200-W-153-PL, 2904-S-171 Control Structure and the 216-S-6 crib.

Process Description: This 216-S-6 crib operated from November 1954 to July 1972. The crib was constructed as part of the Segregation Project. REDOX effluent with a high potential for contamination was diverted to the 216-S-6 Crib. Effluent with a low potential for contamination was sent to the 216-S-5 Crib.

Code: 200-W-157-PL **Classification:** Accepted

Names: 200-W-157-PL; Pipeline from 202-S to 200-W-152-PL and 216-S-10 Ditch; Pipeline from 205-S to REDOX Chemical Sewer; REDOX Chemical Sewer

Reclassification None

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The site is a system of underground vitrified clay pipeline with diameters of 20 centimeters (8 inch) and 30 centimeters (12 inch). A 10 centimeter (4 inch) diameter vitrified clay pipe extends from the 205-S building to the main chemical sewer line.

Location: The pipeline attaches to manholes located on the north side of 202-S, the south side of 271-S, the south side of 211-S and south of the 205-S building. The chemical sewer extends beyond the 200 West Area fence, southwest of 202-S.

Related Sites/ Structures: The waste site is associated with the 216-S-10 ditch and pond and the REDOX process sewer (sitecode 200-W-152-PL).

Process Description: The REDOX chemical sewer connected to manhole number 3, southwest of 202-S. It connected to the 216-S-10 ditch at Manhole number 2. A segment of the chemical sewer continued to Manhole number 1, where it tied into the distal end of the Process Sewer line (sitecode 200-W-157-PL).

This Site has the Following SubSites:

Code: 200-W-157-PL:1

Names: 200-W-157-PL:1; REDOX Chemical Sewer Line from 202-S to REDOX Process Sewer (Sitecode 200-W-152-PL)

Code: 200-W-157-PL:2

Names: 200-W-157-PL:2; 10-Centimeter (4-Inch) VCP Chemical Sewer Line from 205-S

Code: 200-W-157-PL:1

Classification: Accepted

Names: 200-W-157-PL:1; REDOX Chemical Sewer Line from 202-S to REDOX Process Sewer (Sitecode 200-W-152-PL)

Reclassification None

Type: Process Sewer

Start Date:

Status: Inactive

End Date:

Description: Subsite 2 is the main system of underground vitrified clay pipeline with diameters of 20 centimeters (8 inch) and 30 centimeters (12 inch).

The SubSite is Part Of:

Code: 200-W-157-PL

Names: 200-W-157-PL; Pipeline from 202-S to 200-W-152-PL and 216-S-10 Ditch; Pipeline from 205-S to REDOX Chemical Sewer; REDOX Chemical Sewer

Code: 200-W-157-PL:2

Classification: Accepted

Names: 200-W-157-PL:2; 10-Centimeter (4-Inch) VCP Chemical Sewer Line from 205-S

Reclassification None

Type: Process Sewer

Start Date:

Status: Inactive**End Date:****Description:** A 10 centimeter (4 inch) diameter vitrified clay pipe extends from the 205-S building to the main chemical sewer line.**The SubSite is Part Of:****Code:** 200-W-157-PL**Names:** 200-W-157-PL; Pipeline from 202-S to 200-W-152-PL and 216-S-10 Ditch; Pipeline from 205-S to REDOX Chemical Sewer; REDOX Chemical Sewer**Code:** 200-W-158-PL**Classification:** Accepted**Names:** 200-W-158-PL; Pipeline from 293-S to 200-W-152-PL**Reclassification:** None**Type:** Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** The waste site is an underground 20 centimeter (8 inch diameter) vitrified clay pipeline from the 293-S building to the 200-W-152-PL pipeline. It connects to the REDOX Process Sewer (200-W-152-PL) on the south side of 202-S at Manhole number 4.**Location:** The pipeline is located east and south of 202-S.**Related Sites/ Structures:** The pipeline is associated with the 293-S building and the REDOX Process Sewer (sitecode 200-W-152-PL).**Code:** 200-W-159-PL**Classification:** Accepted**Names:** 200-W-159-PL; Cooling Water Lines from 241-SX-401 and 241-SX-402 to 216-U-10 Pond**Reclassification:** None**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** The waste site is two 20 centimeter (8 inch) diameter, underground carbon steel pipelines that carried cooling water from the 241-SX-401 and 241-SX-402 Condenser Shielding buildings to the 216-U-10 Pond.**Location:** The pipelines begin inside the 241-SX tank farm at the 241-SX-401 and 241-SX-402 buildings. They cross Cooper Ave. and run west, north of the 216-S-21 crib.**Related Sites/ Structures:** The site is associated with 241-SX-401, 241-SX-402 and 216-U-10 Pond.**Code:** 200-W-160-PL**Classification:** Accepted**Names:** 200-W-160-PL; Pipeline from 241-SX-401 and 241-SX-402 to 216-S-21 Crib**Reclassification:** None**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** The site is an underground, 20 centimeter (8 inch) diameter, carbon steel pipeline.

Location: The pipeline begins inside the 241-SX tank farm at the 241-SX-401 and 241-SX-402 buildings. It crosses Cooper Ave and terminates at the 216-S-21 crib.

Related Sites/ Structures: The pipeline is associated with the 241-SX-401 and 241-SX-402 buildings and the 216-S-21 crib.

Process Description: The pipeline carried condensate from the 241-SX-401 and 241-SX-402 Condensate Shielding buildings to the 216-S-21 crib.

Code: 200-W-161-PL **Classification:** Accepted

Names: 200-W-161-PL; Line 557; Pipeline from 242-S to 216-S-25 Crib **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 10 centimeter (4 inch) diameter, carbon steel pipeline.

Location: The pipeline extends south of the 242-S Evaporator. It crosses under Cooper Ave. and terminates at the 216-S-25 crib. The 216-S-25 crib is located west of the 200 West Area perimeter fence.

Related Sites/ Structures: The pipeline is associated with the 242-S Evaporator and the 216-S-25 crib.

Process Description: The pipeline carried process steam condensate from the 242-S Evaporator to the 216-S-25 crib.

Code: 200-W-162-PL **Classification:** Accepted

Names: 200-W-162-PL; Pipeline from 241-SX-701 to 216-SX-2 Crib **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The site is an underground, 15 centimeter (6 inch) diameter, vitrified clay pipe.

Location: The pipeline is located south of the 241-S Evaporator building. It extends from the south side of the 241-SX-701 building to the 216-SX-2 crib. The pipeline, building and crib are located west of the 241-SX Tank Farm fence.

Related Sites/ Structures: The pipeline is associated with the 241-SX-701 building and the 216-SX-2 crib.

Code: 200-W-163-PL **Classification:** Accepted

Names: 200-W-163-PL; T Plant Process Sewer; 18-Inch 221-T Process Sewer Pipeline **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 46 centimeter (18 inch) diameter vitrified clay pipeline.

Several manholes are visible at the surface. Feed lines are divided into three subsites.

Location: The pipeline extends westward from T Plant and connects to the pipeline that fed the 216-T-4 ditch (see sitecode 200-W-164-PL).

Related Sites/ Structures: The pipeline is associated with 200-W-9, 221-T, 224-T and the 216-T-4 ditch.

This Site has the Following SubSites:

Code: 200-W-163-PL:1

Names: 200-W-163-PL:1; 18-Inch and 12-Inch Vitrified Clay Pipeline from 221-T to 216-T-4 Ditch

Code: 200-W-163-PL:2

Names: 200-W-163-PL:2; 8-Inch Carbon Steel Line from 271-T to Main 18-Inch VCP Process Sewer Pipeline

Code: 200-W-163-PL:3

Names: 200-W-163-PL:3; 222-T and 224-T Connecting to Main 18-Inch VCP Process Sewer Line; Carbon Steel Pipeline from 291-T

Code: 200-W-163-PL:1

Classification: Accepted

Names: 200-W-163-PL:1; 18-Inch and 12-Inch Vitrified Clay Pipeline from 221-T to 216-T-4 Ditch

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The pipeline is constructed of 18 inch VCP from the manhole westward to the 216-T-4 ditch. The pipeline is constructed of 12 inch VCP along the edge of 221-T.

The SubSite is Part Of:

Code: 200-W-163-PL

Names: 200-W-163-PL; T Plant Process Sewer; 18-Inch 221-T Process Sewer Pipeline

Code: 200-W-163-PL:2

Classification: Accepted

Names: 200-W-163-PL:2; 8-Inch Carbon Steel Line from 271-T to Main 18-Inch VCP Process Sewer Pipeline

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

The SubSite is Part Of:

Code: 200-W-163-PL

Names: 200-W-163-PL; T Plant Process Sewer; 18-Inch 221-T Process Sewer Pipeline

Code: 200-W-163-PL:3

Classification: Accepted

Names: 200-W-163-PL:3; 222-T and 224-T Connecting to Main 18-Inch VCP Process Sewer Line; Carbon Steel Pipeline from 291-T

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive**End Date:****The SubSite is Part Of:****Code:** 200-W-163-PL**Names:** 200-W-163-PL; T Plant Process Sewer; 18-Inch 221-T Process Sewer Pipeline

Code: 200-W-164-PL**Classification:** Accepted**Names:** 200-W-164-PL; Pipeline from 207-T Retention Basin to the 216-T-4 Ditch**Reclassification:** None**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** The waste site is an underground 61 centimeter (24 inch) diameter vitrified clay pipe.**Location:** The pipeline extends from the west side of the 207-T Retention Basin, diagonally northwest, to the 216-T-4 ditch.**Related Sites/ Structures:** The site is associated with the 207-T Retention Basin, the 216-T-4-1 and 216-T-4-2 ditches and the 45 centimeter (18 inch) pipeline from T Plant (see sitecode 200-W-163-PL).

Code: 200-W-165-PL**Classification:** Accepted**Names:** 200-W-165-PL; Pipeline from Tank 241-TX-112 to 207-T Retention Basin**Reclassification:** None**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** The waste site is an underground 15 centimeter (6 inch) diameter pipe.**Location:** The pipeline extends from the 241-TX-112 tank, inside the 241-TX tank farm to the 207-T Retention basin. The retention basin is located west of 221-T, on the north side of 23rd Street. This pipeline extends south from the 207-T basin. It crosses under Camden Ave. near the 242-T building.

Code: 200-W-166-PL**Classification:** Accepted**Names:** 200-W-166-PL; Pipeline from 242-T Evaporator Building to the 207-T Retention Basin**Reclassification:** None**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** The waste site is an underground 10 centimeter (4 inch) diameter cast iron pipeline. The pipeline is marked with signs. A surface stabilized area, posted as Underground Radioactive Material Area, is located above this pipeline.**Location:** The pipeline is located south of 23rd Street. The line crosses under Camden Ave. Portions of it are on both sides of Camden Ave. The pipeline connected the 242-T Evaporator building with the 207-T Retention basin.**Related Sites/ Structures:** The pipeline is associated with the 242-T Evaporator, the 207-T basin and UPR-200-W-14.

Process Description: The pipeline carried cooling water from the 242-T Evaporator to the 207-T Retention Basin.

Code: 200-W-167-PL **Classification:** Accepted

Names: 200-W-167-PL; Pipeline from 242-T Evaporator to 207-T Retention Basin **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground 10 centimeter (4 inch) diameter carbon steel pipeline. A radiologically posted area is located above this pipeline.

Location: The pipeline is located south of 23rd Street. Portions of it are on both sides of Camden Ave. The pipeline connected the 242-T Evaporator building with the 207-T Retention basin.

Related Sites/Structures: The pipeline is associated with 207-T, 242-T and 200-W-175-PL.

Process Description: The pipeline carried cooling water from the 242-T building to the 207-T Retention Basin.

Code: 200-W-168-PL **Classification:** Accepted

Names: 200-W-168-PL; Pipelines from 241-U-110 Tank to 216-U-3 Crib and 216-U-14 Ditch **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is two parallel underground, 5 centimeter (2 inch) diameter carbon steel pipelines buried in the same soil trench. Both lines originate at the 241-U-110 tank. One line extends to the 216-U-3 crib. The other line diverts to the 216-U-14 ditch.

Location: The pipeline is located east of the corner of 16th Street and Cooper Ave. The pipeline extends southward from the 241-U-110 tank, inside the 241-U Tank Farm, to the 216-U-3 crib. The 216-U-3 crib is located south of the 241-U tank farm. The pipeline crosses under 16th Street.

Related Sites/Structures: The pipeline is associated with the 241-U-110 tank and the 216-U-3 crib.

This Site has the Following SubSites:

Code: 200-W-168-PL:1

Names: 200-W-168-PL:1; Pipeline from 241-U-110 to 216-U-3 Crib

Code: 200-W-168-PL:2

Names: 200-W-168-PL:2; Pipeline from 241-U-110 to the 216-U-14 Ditch

Code: 200-W-168-PL:1 **Classification:** Accepted

Names: 200-W-168-PL:1; Pipeline from 241-U-110 to 216-U-3 Crib **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive

End Date:

The SubSite is Part Of:

Code: 200-W-168-PL

Names: 200-W-168-PL; Pipelines from 241-U-110 Tank to 216-U-3 Crib and 216-U-14 Ditch

Code: 200-W-168-PL:2

Classification: Accepted

Names: 200-W-168-PL:2; Pipeline from 241-U-110 to the 216-U-14 Ditch

Reclassification None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

The SubSite is Part Of:

Code: 200-W-168-PL

Names: 200-W-168-PL; Pipelines from 241-U-110 Tank to 216-U-3 Crib and 216-U-14 Ditch

Code: 200-W-169-PL

Classification: Accepted

Names: 200-W-169-PL; Pipeline Between 216-U-10 Pond and 216-U-11 Overflow

Reclassification None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is an underground, 46 centimeter (18 inch) diameter, corrugated metal pipe.

Location: The pipeline is located southwest of the corner of 16th Street and Dayton Ave. It extends westward from the northwest corner of the 216-U-10 pond to the 216-U-11 trench. The pipeline crosses under Dayton Ave.

Related Sites/ Structures: The pipeline is associated with the 216-U-11 trench and the 216-U-10 Pond.

Process Description: The pipeline transferred 216-U-10 Pond water to the 216-U-11 trench.

Code: 200-W-170-PL

Classification: Accepted

Names: 200-W-170-PL; 216-U-16 Crib Pipeline

Reclassification None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is an underground, 30.5 centimeter (12 inch) diameter, polyvinyl chloride pipeline.

Location: The pipeline is located south of 16th Street. The reinforced plastic pipe attaches to the U Plant Process Sewer (sitecode 200-W-84-PL).

Related Sites/ Structures: The pipeline is associated with the U Plant Process Sewer (200-W-84-PL) and the 216-U-16 crib.

Code: 200-W-171 **Classification:** Accepted

Names: 200-W-171; 200-W-219-PL Line Leak; Leak from 234-5Z Pipe Trench to 241-Z Tank D-6 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1969

Status: Inactive **End Date:**

Description: The waste site is a release that occurred within the concrete pipe trench. The concrete pipe trench is a subsurface feature extending from 234-5Z to 241-Z (see sitecode 200-W-219-PL).

Location: The release occurred in the pipe trench located south of 234-5Z that extended to the 241-Z tank enclosure.

Release Description: ARH-1048 states that on 2/18/69, approximately 114,000 liters (30,000 gallons) was sent to the 241-Z D-6 tank but it never got to the tank. To help find the cause of the unaccounted waste, water from 880 room 19 (button line) and the incinerator was sent to the D-6 tank. Only the water from the incinerator reached the D-6 tank, indicating a leak in the common waste line from 880 and the button line. Further checks showed that the concrete trench was cracked and the sump pipe was broken near the north side of the road.

Related Sites/ Structures: The release is associated with pipeline 200-W-219-PL.

Waste Type: Water

Waste Description: Based on available plant records, leakage into the pipe trench ranged from 11,400 liters (3,000 gallons) to 114,000 liters (30,000 gallons) containing between 3 and 30 grams of plutonium.

Code: 200-W-172 **Classification:** Accepted

Names: 200-W-172; Liquid Leaking from Drain Laterals Below 234-5Z Floor Slab **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is a series of underground pipes. Secondary drain laterals conveyed liquid from various points inside and beneath the 234-5Z building to the main drain lines in the subsurface pipe tunnels. Visual observations in the pipe tunnels revealed little evidence of substantial leakage.

Location: The release location is the soil underneath the 234-5Z building.

Related Sites/ Structures: The release is associated with the Plutonium Finishing Plant processes.

Process Description: Fifty-two side lateral pipes conveyed process liquids into the main 234-5Z tunnel drain lines. Approximately fifteen lateral lines appear to have possibly leaked.

Waste Type: Process Effluent

Waste Description: Small pipe leaks in the tunnels over time may have accumulated a quantity of less than 3 grams of plutonium.

Code: 200-W-173-PL **Classification:** Accepted

Names: 200-W-173-PL; 216-T-33 Crib Pipeline; Pipeline **Reclassification:** None

from 2706-T to 216-T-33 Crib

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The majority of the waste site is an underground, 20 centimeter (8 inch) diameter, vitrified clay pipeline that fed the 216-T-33 crib. A portion of the pipeline from 2706-T to the weir pit is an underground 15 centimeter (6 inch diameter) vitrified clay pipe.

Location: The pipeline is located west of 221-T and south of 2706-T.

Process Description: The 2706-T facility decontaminated vehicles, rail cars and large pieces of equipment. Water containing chemicals and radionuclide contamination went down the facility drains.

Code: 200-W-174-PL

Classification: Accepted

Names: 200-W-174-PL; 216-Z-1A Modified Pipeline; Lines 1035 and 1036; Pipelines from 234-5Z to 216-Z-1A and 216-Z-18 Crib

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is two parallel underground, 5 centimeter (2 inch) diameter stainless steel lines that diverted from a concrete encasement to feed 216-Z-1A and the 216-Z-18 crib. This pipeline bypassed the 241-Z-361 settling tank. The line numbers are 1035 and 1036.

Location: The pipeline extends south from the 234-5Z facility to the 216-Z-1A tile field. Part of the pipeline is located inside the PFP security fence and part is located outside the security fence.

Release Description: In 1971, the 216-Z-18 Crib line broke near the southwest corner of the 236-Z Building. An excavation of the area uncovered gross alpha contamination in the soil. See UPR-200-W-103

Related Sites/Structures: The waste lines are associated with 234-5Z and 216-Z-1A, 216-Z-18 and UPR-200-W-103.

Process Description: Lines 1035 and 1036 divert out of a concrete encasement that connected 242-Z with 234-5Z.

Description: Lines 1035 and 1036 bypass the 216-Z-1, 216-Z-2 and 216-Z-3 cribs and route the waste directly into the 216-Z-1A tile field (see subsite 1). Later the effluent was directed to the 216-Z-18 crib (see subsite 2).

This Site has the Following SubSites:

Code: 200-W-174-PL:1

Names: 200-W-174-PL:1; Parallel Pipelines from 242-Z/234-5Z to 216-Z-1A

Code: 200-W-174-PL:2

Names: 200-W-174-PL:2; Re-Routed Pipeline to 216-Z-18 Crib

Code: 200-W-174-PL:1

Classification: Accepted

Names: 200-W-174-PL:1; Parallel Pipelines from 242-Z/234-5Z to 216-Z-1A

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: two 2 inch diameter stainless steel lines (1035 and 1036) divert out of concrete encasement.

The SubSite is Part Of:**Code:** 200-W-174-PL**Names:** 200-W-174-PL; 216-Z-1A Modified Pipeline; Lines 1035 and 1036; Pipelines from 234-5Z to 216-Z-1A and 216-Z-18 Crib**Code:** 200-W-174-PL:2**Classification:** Accepted**Names:** 200-W-174-PL:2; Re-Routed Pipeline to 216-Z-18 Crib**Reclassification:** None**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** 3 inch diameter stainless steel**The SubSite is Part Of:****Code:** 200-W-174-PL**Names:** 200-W-174-PL; 216-Z-1A Modified Pipeline; Lines 1035 and 1036; Pipelines from 234-5Z to 216-Z-1A and 216-Z-18 Crib**Code:** 200-W-175-PL**Classification:** Accepted**Names:** 200-W-175-PL; Line V681; Pipeline to Route Waste from 241-T-112 to 216-TY-201 Flush Tank and 216-T-26, 216-T-27 and 216-T-28 Cribs**Reclassification:** None**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** The site is an underground carbon steel pipeline extending from the 241-T-112 tank to the 216-TY-201 Flush Tank. Pipeline diameters vary from 7.6 centimeters (3 inches) and 8.9 centimeter (3.5 inch) diameter to 10 centimeters (4 inches). A fairly large, radiologically posted area is located above the pipeline, at the portion of the line that diverted to 241-T tank farm.**Location:** The pipeline extends southeast out of the 241-T Tank Farm. Most of the pipeline is located south of 23rd Street. The line crosses under Camden Ave. Part of the line is located on the east side of Camden Ave. and part is on the west side of Camden Ave. A portion of the pipeline is inside the 241-T tank farm.**Related Sites/ Structures:** The site is associated with the 241-T-112 tank, the 216-TY-201 Flush Tank and pipeline 200-W-167-PL.**Process Description:** The waste to 216-T-26 originally came from the 241-TY tank farm. In 1956, the pipeline from 241-TY tank farm to the 216-T-26 crib was isolated by installing a blank flange in the pipe between the east perimeter fence of the 241-TY Tank Farm and Camden Ave. A portion of an existing pipeline (see 200-W-167-PL) was re-used to create a new pipeline that routed waste from 241-T-112 tank (inside 241-T tank farm) to the 216-T-201 flush tank and the 216-T-26 crib. The 8.9 centimeter (3.5 inch) diameter pipe changes to a 7.6 centimeter (3 inch) diameter pipe where the pipeline turns eastward to connect with the 241-T-201 Flush Tank.**Code:** 200-W-176-PL**Classification:** Accepted**Names:** 200-W-176-PL; Encased Transfer Lines Between **Reclassification:** None

241-TX-153 Diversion Box and 241-TX-155
Diversion Box; Lines V396, V397, V401, V403,
V407, V409, and V413

Type: Encased Tank Farm Pipeline

Start Date:

Status: Inactive

End Date:

Description: The waste site is an underground concrete transfer line encasement. All of the lines inside the encasement are 9 centimeter (3.5 inch) diameter stainless steel lines.

Location: The concrete encasement extends eastward from 241-TX tank farm to the 241-TX-155 Diversion Box, located east of Camden Ave.

Related Sites/ Structures: The waste site is associated with the 241-TX-153 Diversion Box and the 241-TX-155 Diversion Box.

Code: 200-W-177-PL

Classification: Accepted

Names: 200-W-177-PL; Direct Buried Tank Farm Lines
Between 241-TXR-151 and 241-TX-155
Diversion Boxes; Lines V7616 and V7653

Reclassification: None

Type: Direct Buried Tank Farm Pipeline

Start Date:

Status: Inactive

End Date:

Description: The waste site is two, 9 centimeter (3.5 inch) stainless steel lines buried in a common soil trench. Line V7616 extends between the 241-TXR-151 Diversion Box (inside the 241-TX tank farm) to the 241-TX-155 Diversion Box (outside the tank farm). Line V7653 extends from the 244 TXR Vault (inside the 241-TX tank farm) to the 241-TX-155 Diversion Box (outside the tank farm).

Location: The pipelines extend eastward from the 241-TX tank farm to the 241-TX-155 Diversion Box, located east of Camden Ave.

Related Sites/ Structures: The pipelines are associated with the 241-TXR-151 Diversion Box, the 241-TXR Vault and the 241-TX-155 Diversion Box.

Code: 200-W-178-PL

Classification: Accepted

Names: 200-W-178-PL; Lines HSW-202 and HSW-203;
Pipeline from 241-Z to 244-TX DCRT

Reclassification: None

Type: Direct Buried Tank Farm Pipeline

Start Date:

Status: Inactive

End Date:

Description: The waste site is two, underground, 5 centimeter (2 inch) stainless steel pipelines buried in the same soil trench. The stainless steel lines are wrapped in foam insulation.

Location: The pipeline is located west of Camden Ave. The pipeline exits the east side of the Plutonium Finishing Plant security fence and runs north to enter the west side of the 241-TX Tank Farm.

Related Sites/ Structures: The pipeline is associated with the 241-Z tank farm and the 244-TX DCRT in the 241-TX tank farm.

Process Description: The pipeline transported waste from tank D-5, in 241-Z tank farm to the 244-TX Double Contained Receiver Tank (DCRT) in the 241-TX tank farm.

Code: 200-W-179-PL **Classification:** Accepted

Names: 200-W-179-PL; Lines SL100, SL101, SN216/281 and DR327; Pipelines Between 241-S-152 Diversion Box and 241-U Tank Farm **Reclassification:** None

Type: Direct Buried Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is four carbon steel lines buried in the same soil trench. Two lines (SL100 and SL101) are 5 centimeter diameter pipes double contained inside 10 centimeter (4 inch) diameter pipes. Two lines (SN216/281 and DR327) are 7.6 centimeter (3 inch) diameter pipes double contained within 15 centimeter (6 inch) diameter pipes.

Location: The pipelines extend north from 241-S Tank farm to 241-U tank farm, along the east side of Cooper Ave.

Release Description: In 1980, unplanned release number UPR-200-W-115 was assigned to the surface soil contamination along this pipeline.

Code: 200-W-180-PL **Classification:** Accepted

Names: 200-W-180-PL; Pipelines from 221-T and 277-T Bldgs to 216-T-1 Ditch **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 20 centimeter (8 inch) diameter, vitrified clay pipe that fed the 216-T-1 ditch. The vitrified clay pipes extending out of the 221-T building are smaller diameter (10 centimeter [4 inch] and 15 centimeter [6 inch]). A 10 centimeter (4 inch) diameter cast iron pipe from the 277-T building connects to the main vitrified clay line (see subsite).

Location: The pipeline to the 216-T-1 ditch extends north from the northwest corner of the 221-T facility.

Related Sites/ Structures: The pipeline is associated with the 221-T and 277-T buildings and the 216-T-1 ditch.

This Site has the Following SubSites:

Code: 200-W-180-PL:1

Names: 200-W-180-PL:1; VCP Pipeline

Code: 200-W-180-PL:2

Names: 200-W-180-PL:2; Cast Iron Pipe

Code: 200-W-180-PL:1 **Classification:** Accepted

Names: 200-W-180-PL:1; VCP Pipeline **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: Subsite 1 is the main 8 inch VCP pipeline that fed the 216-T-1 ditch and the two smaller diameter VCP pipes (6 inch and 4 inch) that exit the 221-T building.

The SubSite is Part Of:

Code: 200-W-180-PL

Names: 200-W-180-PL; Pipelines from 221-T and 277-T Bldgs to 216-T-1 Ditch

Code: 200-W-180-PL:2

Classification: Accepted

Names: 200-W-180-PL:2; Cast Iron Pipe

Reclassification None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: Subsite 2 is the 4 inch diameter cast iron pipe from 277-T to the main VCP ditch pipeline.

The SubSite is Part Of:

Code: 200-W-180-PL

Names: 200-W-180-PL; Pipelines from 221-T and 277-T Bldgs to 216-T-1 Ditch

Code: 200-W-181-PL

Classification: Accepted

Names: 200-W-181-PL; Lines V426, V427 and V428/V461; Transfer Lines Between 241-U-152 and 241-U-153 Diversion Boxes

Reclassification None

Type: Direct Buried Tank Farm Pipeline

Start Date:

Status: Inactive

End Date:

Description: The waste site is three, 9 centimeter (3.5 inch) diameter, stainless steel lines buried in the same soil trench.

Location: The lines are located west of U Plant at the intersection of 16th Street and Camden Ave. The lines extend from 241-U-152 Diversion Box, located outside the tank farm, to 241-U-153 Diversion Box, located inside the 241-U tank farm fence. The lines cross under Camden Ave.

Related Sites/ Structures: The lines are associated with 241-U-152 and 241-U-153 diversion boxes.

Code: 200-W-182-PL

Classification: Accepted

Names: 200-W-182-PL; Encased Transfer Lines Between 241-U-152 Diversion Box and 241-TX-152 and 241-TX-155 Diversion Boxes; Lines V398, V404 and V410

Reclassification None

Type: Encased Tank Farm Pipeline

Start Date:

Status: Inactive

End Date:

Description: The waste site is three underground, 7.6 centimeter (3 inch) diameter, stainless steel lines in the same concrete encasement.

Location: The lines are located on the east side of Camden Ave., west of the 216-U-14 ditch. They extend between the 241-U-152 Diversion Box and the 241-TX-152 and 241-TX-155 Diversion Boxes.

Related Sites/ Structures: The lines are associated with 241-U-152, 241-TX-152 and 241-TX-155 diversion boxes.

Code: 200-W-183-PL **Classification:** Accepted

Names: 200-W-183-PL; Lines V422/V452 and V421/V453; Transfer Lines Between 241-U-151 and 241-U-152 Diversion Boxes **Reclassification:** None

Type: Direct Buried Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is two, 7.6 centimeter (3 inch) diameter, carbon steel lines buried in the same soil trench. Each line is double contained inside a 15 centimeter (6 inch) diameter pipe.

Location: The lines are located near the intersection of 16th Street and Camden Ave. They extend between the 241-U-151 and 241-U-152 diversion boxes.

Related Sites/ Structures: The lines are associated with the 241-U-151 and 241-U-152 Diversion Boxes.

Code: 200-W-184-PL **Classification:** Accepted

Names: 200-W-184-PL; Drain Lines from 241-U-151, 241-U-152 and 241-U-153 Diversion Boxes to 241-U-301 Catch Tank; Line V478 **Reclassification:** None

Type: Direct Buried Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 15.2 centimeter (6 inch) diameter, carbon steel pipeline that connects the 241-U-151, 241-U-152 and 241-U-153 Diversion Boxes to the 241-U-301 Catch Tank. Individual 10 centimeter (4 inch) diameter drain lines from the three diversion boxes connect to the same 10 centimeter (4 inch) diameter pipeline to the catch tank.

Location: The pipeline is near the corner of 16th Street and Camden Ave. It crosses under Camden Ave. Approximately one third of the drain line is located outside of the 241-U Tank Farm, east of the tank farm fence. Approximately two thirds of the pipeline is located inside the 241-U Tank Farm fence. The catch tank is located inside the tank farm fence. Diversion Boxes 241-U-151 and 241-U-152 are located outside the tank farm fence. 241-U-153 is located inside the tank farm fence.

Related Sites/ Structures: The pipeline is associated with the 241-U-151, 241-U-152 and 241-U-153 Diversion Boxes and the 241-U-301 Catch Tank.

Process Description: The pipeline provided diversion box drainage to the 241-U-301 catch tank.

Code: 200-W-185-PL **Classification:** Accepted

Names: 200-W-185-PL; Lines V450 and V451; Transfer Lines Between 241-U-151 and 241-U-153 Diversion Boxes **Reclassification:** None

Type: Direct Buried Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is two underground, 9 centimeter (3.5 inch) diameter, stainless steel lines buried in the same soil trench.

Location: The lines are located near the corner of 16th Street and Camden Ave. The lines cross under Camden Ave. A portion of these lines is located inside the 241-U Tank Farm.

Related Sites/ Structures: The lines are associated with the 241-U-151 and 241-U-153 diversion boxes.

Process Description: The lines transferred waste from the 241-U-151 diversion box and to the 241-U-153 Diversion Box.

Code: 200-W-186-PL **Classification:** Accepted

Names: 200-W-186-PL; Lines 1006 and 1045; Transfer Lines from 240-S-152 Diversion Box to 204-S and 205-S **Reclassification:** None

Type: Encased Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground concrete encasement that contains two 9 centimeter (3.5 inch) diameter stainless steel pipelines.

Location: The pipelines originate north of the REDOX, at the 240-S-152 Diversion Box. The extend eastward and connected to the 204-S and 205-S facilities.

Related Sites/ Structures: The pipelines are associated with 240-S-152 Diversion Box and the 204-S and 205-S facilities.

Process Description: The pipeline transferred waste from the 240-S-152 Diversion Box to the 205-S process cell. Line 1045 was rerouted to connect directly to the 204-S facility.

Code: 200-W-187-PL **Classification:** Accepted

Names: 200-W-187-PL; Lines V552, V553 and V555; Transfer Lines Between 240-S-151 and 240-S-152 Diversion Boxes **Reclassification:** None

Type: Encased Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is a concrete encasement containing three 9 centimeter (3.5 inch) diameter stainless steel pipelines.

Location: The pipelines are located north of the 202-S building, connecting the 240-S-151 diversion box to the 240-S-152 diversion box.

Related Sites/ Structures: The pipelines are associated with the 240-S-151 and 240-S-152 diversion boxes.

Code: 200-W-188-PL **Classification:** Accepted (Proposed)

Names: 200-W-188-PL; Waste Distribution Line from 216-TY-201 Flush Tank to 216-T-26, 216-T-27 and 216-T-28 Cribs and Truck Unloading Station **Reclassification:** None

Line

Type: Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** The waste site is the underground, 35.5 centimeter (14 inch) diameter, carbon steel waste distribution line from the flush tank to the cribs. A 15 centimeter (6 inch) diameter poly vinyl chloride pipeline extends from the truck unloading station (see sitecode 200-W-82), east of the cribs, to the main crib distribution line.**Location:** The lines are located east of Camden Ave. They extend south from the 216-TY-201 flush tank to feed the 216-T-26, 216-T-27 and 216-T-28 cribs.**Related Sites/ Structures:** The pipeline is associated with the 216-TY-201 flush tank and the 216-T-26, 216-T-26 and 216-T-28 cribs.**This Site has the Following SubSites:****Code:** 200-W-188-PL:1**Names:** 200-W-188-PL:1; Main Distribution Line**Code:** 200-W-188-PL:2**Names:** 200-W-188-PL:2; Truck Unloading Station Pipeline

Code: 200-W-188-PL:1**Classification:** Accepted (Proposed)**Names:** 200-W-188-PL:1; Main Distribution Line**Reclassification:** None**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** Subsite 1 is the 35 centimeter (14 inch) diameter carbon steel distribution line between the flush tank and the cribs.**The SubSite is Part Of:****Code:** 200-W-188-PL**Names:** 200-W-188-PL; Waste Distribution Line from 216-TY-201 Flush Tank to 216-T-26, 216-T-27 and 216-T-28 Cribs and Truck Unloading Station Line

Code: 200-W-188-PL:2**Classification:** Accepted (Proposed)**Names:** 200-W-188-PL:2; Truck Unloading Station Pipeline**Reclassification:** None**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** Subsite 2 is the 15 centimeter (6 inch) PVC line between the Truck Unloading Station and the crib distribution line.**The SubSite is Part Of:****Code:** 200-W-188-PL**Names:** 200-W-188-PL; Waste Distribution Line from 216-TY-201 Flush Tank to 216-T-26, 216-T-27 and 216-T-28 Cribs and Truck Unloading Station Line

Code: 200-W-190-PL **Classification:** Accepted

Names: 200-W-190-PL; Discharge Line from 240-S-151 Diversion Box to 240-S-302 Catch Tank; Line V554 **Reclassification:** None

Type: Direct Buried Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 7.6 centimeter diameter (3 inch), stainless steel line connecting the 240-S-151 Diversion Box to the 240-S-302 Catch Tank.

Location: The discharge line is located north of the 202-S facility, extending eastward from the 240-S-151 Diversion Box to the 240-S-302 Catch Tank.

Related Sites/ Structures: The line is associated with the 240-S-151 Diversion Box and the 240-S-302 Catch Tank.

Process Description: This is a steam jet discharge line extending out of a concrete encasement. The majority of the line is direct buried.

Code: 200-W-191-PL **Classification:** Accepted

Names: 200-W-191-PL; Encased Transfer Line Between 241-TX-155 and 241-TY-153 Diversion Boxes; Lines V402, V406, V408 and V412 **Reclassification:** None

Type: Encased Tank Farm Pipeline **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is a concrete encasement that contains three 7.6 centimeter (3 inch) diameter stainless steel lines and one 7.6 centimeter (3 inch) diameter carbon steel line.

Location: The transfer line is located southwest of T Plant. It extends from 241-TX-155 Diversion Box to the 241-TY-153 Diversion Box. The line crosses under Camden Ave.

Release Description: See UPR-200-W-135

Related Sites/ Structures: The lines are associated with the 241-TX-155 and 241-TY-153 Diversion Boxes and pipeline 200-W-105-PL from U Plant. This line is also associated with UPR-200-W-135.

Code: 200-W-192-PL **Classification:** Accepted

Names: 200-W-192-PL; Pipeline from 221-U, 222-U and 224-U to the 207-U Retention Basin; U Plant Process Sewer **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The majority of the waste site is an underground, 61 centimeter (24 inch) diameter, vitrified clay pipe that carried waste from U Plant operations to the 207-U Retention Basin. A 61 centimeter (24 inch) cast iron line from 221-U, two 25 centimeter (10 inch) cast iron lines and a 10 centimeter (4 inch) diameter steel line from 224-U feed the main VCP process sewer.

Location: The pipeline is located west of U Plant and north of 16th Street.

Release Description: Occurrence Report 86-46 states that on August 6, 1986, 2365 liters (625 gallons) of recovered nitric acid, containing 39 kilograms (86 pounds) of uranium was discharged through the chemical sewer that connected to the 207-U retention Basin. In 1986, 224-U was operational. Prior to the discovery of the release, the outlet valves on the retention basin were open to the 216-U-14 Ditch. The acid released to the ditch was greatly diluted with the 300 gallon per minute flow of cooling water from the 224-U facility being processed through the chemical sewer system. The Hanford Site Waste Management Units Report (1987) reported different release values. It states that approximately 3,000 liters (796 gallons) of 50% reprocessed nitric acid was released to the basin and subsequently to 216-U-14 Ditch. The total release to the environment consisted of approximately 102,000 kilograms (225,000 pounds) of corrosive solution (pH less than 2.0) and 45.4 kilograms (100 pounds) of uranium.

Related Sites/ Structures: The pipeline is associated with the U Plant facilities and the 207-U Basin.

Process Description: The 207-U basin received process sewer waste from the 221-U Building and the 224-U Building through this pipeline.

This Site has the Following SubSites:

Code: 200-W-192-PL:1

Names: 200-W-192-PL:1; 24-Inch VCP Process Sewer Pipeline

Code: 200-W-192-PL:2

Names: 200-W-192-PL:2; Two 10-Inch Cast Iron Lines from 224-U to the U Plant Process Sewer

Code: 200-W-192-PL:3

Names: 200-W-192-PL:3; 4-Inch Schedule 40 Steel Pipeline from 224-U to U Plant Process Sewer

Code: 200-W-192-PL:4

Names: 200-W-192-PL:4; 24-Inch Cast Iron Pipeline from 221-U to U Plant Process Sewer

Code: 200-W-192-PL:1

Classification: Accepted

Names: 200-W-192-PL:1; 24-Inch VCP Process Sewer Pipeline

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: This subsite is the main, 24 inch vitrified clay process sewer piping.

Release Description: Occurrence Report 86-46 states that on August 6, 1986, 2365 liters (625 gallons) of recovered nitric acid, containing 39 kilograms (86 pounds) of uranium was discharged through the chemical sewer that connected to the 207-U retention Basin. In 1986, 224-U was operational. Prior to the discovery of the release, the outlet valves on the retention basin were open to the 216-U-14 Ditch. The acid released to the ditch was greatly diluted with the 300 gallon per minute flow of cooling water from the 224-U facility being processed through the chemical sewer system. The Hanford Site Waste Management Units Report (1987) reported different release values. It states that approximately 3,000 liters (796 gallons) of 50% reprocessed nitric acid was released to the basin and subsequently to 216-U-14 Ditch. The total release to the environment consisted of approximately 102,000 kilograms (225,000 pounds) of corrosive solution (pH less than 2.0) and 45.4 kilograms (100 pounds) of uranium.

The SubSite is Part Of:

Code: 200-W-192-PL
Names: 200-W-192-PL; Pipeline from 221-U, 222-U and 224-U to the 207-U Retention Basin; U Plant Process Sewer

Code: 200-W-192-PL:2 **Classification:** Accepted
Names: 200-W-192-PL:2; Two 10-Inch Cast Iron Lines **Reclassification** None
from 224-U to the U Plant Process Sewer
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: This subsite is two, cast iron pipelines that connect 224-U to the main process sewer.

The SubSite is Part Of:

Code: 200-W-192-PL
Names: 200-W-192-PL; Pipeline from 221-U, 222-U and 224-U to the 207-U Retention Basin; U Plant Process Sewer

Code: 200-W-192-PL:3 **Classification:** Accepted
Names: 200-W-192-PL:3; 4-Inch Schedule 40 Steel **Reclassification** None
Pipeline from 224-U to U Plant Process Sewer
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: This subsite is the 10 centimeter (4 inch) diameter, steel pipeline that connects 224-U to the process sewer.

The SubSite is Part Of:

Code: 200-W-192-PL
Names: 200-W-192-PL; Pipeline from 221-U, 222-U and 224-U to the 207-U Retention Basin; U Plant Process Sewer

Code: 200-W-192-PL:4 **Classification:** Accepted
Names: 200-W-192-PL:4; 24-Inch Cast Iron Pipeline **Reclassification** None
from 221-U to U Plant Process Sewer
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: This subsite is the 24 inch cast iron pipeline that extends along (and adjacent to) the back side to 221-U and connects the corresponding cells in the canyon building to the process sewer.

The SubSite is Part Of:

Code: 200-W-192-PL
Names: 200-W-192-PL; Pipeline from 221-U, 222-U and 224-U to the 207-U Retention Basin; U Plant Process Sewer

Code: 200-W-193-PL **Classification:** Accepted

Names: 200-W-193-PL; Pipeline from 224-U to 241-U-361 Settling Tank **Reclassification** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 9 centimeter (3.5 inch) diameter, stainless steel pipeline that fed the 241-U-361 Settling Tank.

Location: The majority of the pipeline is located southwest of the 221-U facility, north of 16th Street. It connected to the above grade 224-U CNT (condensate neutralization tank) per DOE/RL-2011-04.

Related Sites/ Structures: The pipeline is associated with 221-U, 224-U, 241-U-361 and 216-U-1 and 2 cribs.

Process Description: 200-W-193-PL transported cell drainage from the 5-6 tank in 221-U from 1952 through 1957 to the 216-U-1&2 Cribs via the 241-U-361 settling tank. It transported 224-U facility and equipment decontamination waste and reclamation waste from the 221-U canyon via the 241-U-361 tank from 1957 through 1967.

Code: 200-W-194-PL **Classification:** Accepted

Names: 200-W-194-PL; Pipeline from 241-U-361 Settling Tank to 216-U-1 and 216-U-2 Cribs **Reclassification** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 9 centimeter (3.5 inch) diameter, stainless steel pipeline from the 241-U-361 Settling Tank to the 216-U-1 and 216-U-2 cribs.

Location: The pipeline is located south west of 221-U and north of 16th Street.

Related Sites/ Structures: The site is associated with 224-U, 221-U and 241-U-361.

Code: 200-W-195-PL **Classification:** Accepted

Names: 200-W-195-PL; Pipeline from 224-U to 216-U-17 Crib **Reclassification** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 15 centimeter (6 inch diameter), polyethylene pipeline that fed the 216-U-17 crib. The underground pipeline was fed by an aboveground (overhead) line connected to the 224-U building.

Location: The pipeline is located east of U Plant. Most of it is north of 16th Street. It crosses under Beloit Ave.

Related Sites/ Structures: The pipeline is associated with 224-U and the 216-U-17 crib.

Code: 200-W-196-PL **Classification:** Accepted

Names: 200-W-196-PL; Pipelines from Railcar Unloading Stations to 216-T-34 Crib **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is two parallel underground pipelines that extend from railcar Unloading Stations 1 and 2 to the 216-T-34 crib. The two lines are buried in the same soil trench. One of the pipelines is constructed of 20 centimeter (8 inch) diameter vitrified clay. The other pipeline is constructed of 15 centimeter (6 inch) diameter polyvinyl chloride. The railcar unloading stations are WIDS sitecode 200-W-21.

Location: The pipelines are located west of T Plant, near the railroad tracks that led into the T Plant area. Railcar Unloading Stations 1 and 2 (see sitecode 200-W-21) were located on the railroad tracks. The pipelines extend from the unloading stations to the crib.

Related Sites/ Structures: The pipelines are associated with sitecodes 200-W-21 and 216-T-34 and 216-T-35 cribs.

Process Description: The railcar unloading stations were used to unload 300 Area liquid laboratory waste sent in railroad tanker cars from the 340 Facility. The waste was pumped into the adjacent 216-T-34 and 216-T-35 Cribs.

Code: 200-W-197-PL **Classification:** Accepted

Names: 200-W-197-PL; Pipelines from Railcar Unloading Stations to 216-T-35 Crib **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is two parallel underground polyvinyl chloride pipelines that extend from the 216-T-34 crib pipeline to the 216-T-35 crib. The two lines are buried in the same soil trench. One of the pipelines is constructed of 20 centimeter (8 inch) diameter polyvinyl chloride. The other pipeline is constructed of 15 centimeter (6 inch) diameter polyvinyl chloride.

Location: The pipelines are located west of T Plant, near the railroad tracks that led into the T Plant area. Railcar Unloading Stations 1 and 2 (see sitecode 200-W-21) were located on the railroad tracks. The pipelines extend west from the 216-T-34 crib feed lines (see 200-W-196-PL).

Related Sites/ Structures: The pipelines are associated with the 216-T-34 crib pipeline (sitecode 200-W-196-PL) and the 216-T-35 crib.

Process Description: The railcar unloading stations were used to unload 300 Area liquid laboratory waste sent in railroad tanker cars from the 340 Facility. The waste was pumped into the adjacent 216-T-34 and 216-T-35 Cribs.

Code: 200-W-198-PL **Classification:** Accepted

Names: 200-W-198-PL; Pipelines from Truck Unloading Station to 216-T-34 and 216-T-35 Cribs **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 15 centimeter (6 inch diameter), polyvinyl chloride pipeline from the truck unloading station to the lines that fed the 216-T-34 and 216-T-35 cribs.

Location: The pipeline is located near the northwest corner of the 216-T-34 crib.

Related Sites/ Structures: The pipeline is associated with the Truck Unloading Station near 216-T-34 crib and the 200-W-197-PL pipeline.

Process Description: Tank trucks of waste emptied into the truck unloading station that fed the 216-T-34 and 216-T-35 cribs.

Code: 200-W-199-PL **Classification:** Accepted

Names: 200-W-199-PL; Pipelines from Building 231-Z to 231-W-151 Vault **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is three underground, 7.6 centimeter (3 inch) diameter, stainless steel pipelines that fed the 231-W-151 vault. The three lines are direct buried in the same soil trench.

Location: The waste site is located east of the 231-Z building.

Related Sites/ Structures: The pipelines are associated with the 231-Z facility, the 231-W-151 vault and 200-W-200-PL.

Code: 200-W-200-PL **Classification:** Accepted

Names: 200-W-200-PL; Pipeline from 231-Z to 216-Z-16 Crib **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, polyvinyl chloride pipeline that transferred waste from the 231-Z building to the 216-Z-16 crib. The majority of the pipeline is 10 centimeters (4 inches) in diameter PVC. A short length of pipe is 7.6 centimeters (3 inches) in diameter.

Location: The pipeline extends north and west of the 231-Z building.

Related Sites/ Structures: The pipeline is associated with the 231-Z building, 200-W-199-PL and the 216-Z-16 crib.

Code: 200-W-201-PL **Classification:** Accepted

Names: 200-W-201-PL; Pipeline from 231-Z to 216-Z-17 Crib **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 7.6 centimeter (3 inch) diameter carbon steel pipeline that fed the 216-Z-17 crib. This pipeline tees off of pipeline 200-W-199-PL.

Location: The pipeline is located east of the 231-Z building.

Related Sites/ Structures: The pipeline is associated with the 231-Z building, pipeline 200-W-199-PL and 216-Z-17 crib.

Code: 200-W-202-PL **Classification:** Accepted

Names: 200-W-202-PL; Pipeline from 231-W-151 to 216-Z-5 Crib **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is the underground pipeline from 231-W-151 to 216-Z-5 Crib. Subsite 1 is the 7.6 centimeter (3 inch) diameter stainless steel pipeline from the 231-W-151 vault to the 216-Z-5 cribs. Subsite 2 is an extra overflow line was added that connected to the 216-Z-10 pipeline (200-W-204-PL).

Location: The pipeline is located northeast of the 231-Z building.

Related Sites/ Structures: The pipeline is associated with the 231-W-151 vault, the 216-Z-5 crib and the pipeline to 216-Z-10 (sitecode 200-W-204-PL).

This Site has the Following SubSites:

Code: 200-W-202-PL:1

Names: 200-W-202-PL:1; Pipeline from 231-W-151 to 216-Z-5 Cribs

Code: 200-W-202-PL:2

Names: 200-W-202-PL:2; Overflow Piping That Connects to 216-Z-10 Pipeline

Code: 200-W-202-PL:1 **Classification:** Accepted

Names: 200-W-202-PL:1; Pipeline from 231-W-151 to 216-Z-5 Cribs **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: Subsite 1 is the 7.6 centimeter (3 inch) diameter stainless steel pipeline from the 231-W-151 vault to the 216-Z-5 cribs.

The SubSite is Part Of:

Code: 200-W-202-PL

Names: 200-W-202-PL; Pipeline from 231-W-151 to 216-Z-5 Crib

Code: 200-W-202-PL:2 **Classification:** Accepted

Names: 200-W-202-PL:2; Overflow Piping That Connects to 216-Z-10 Pipeline **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: Subsite 2 is an extra overflow line was added that connected to the 216-Z-10 pipeline (200-W-204-PL).

The SubSite is Part Of:**Code:** 200-W-202-PL**Names:** 200-W-202-PL; Pipeline from 231-W-151 to 216-Z-5 Crib**Code:** 200-W-203-PL**Classification:** Accepted**Names:** 200-W-203-PL; Pipeline from 231-W-151 Vault to 216-Z-7 Crib**Reclassification:** None**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** The waste site is an underground, 7.6 centimeter (3 inch) diameter pipeline connecting the 231-W-151 vault to the 216-Z-7 crib.**Location:** The pipeline is located northeast of the 231-Z building.**Related Sites/ Structures:** The pipeline is associated with the 231-W-151 vault and the 216-Z-7 crib.**Code:** 200-W-204-PL**Classification:** Accepted**Names:** 200-W-204-PL; Pipeline from 231-W-151 Vault to 216-Z-10 Reverse Well**Reclassification:** None**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** The waste site is an underground, 7.6 centimeter (3 inch) diameter stainless steel line connecting the 231-W-151 vault to the 216-Z-10 reverse well.**Location:** The pipeline is located east of the 231-W-151 vault. It extends eastward from the vault to the 216-Z-10 reverse well.**Related Sites/ Structures:** The pipeline is associated with the 231-W-151 vault and the 216-Z-10 reverse well.**Code:** 200-W-205-PL**Classification:** Accepted**Names:** 200-W-205-PL; Pipelines from 235-5Z to 241-Z-8 Silica Storage Tank and 216-Z-8 French Drain**Reclassification:** None**Type:** Radioactive Process Sewer**Start Date:** 1/1/1955**Status:** Inactive**End Date:** 1/1/1962**Description:** The waste site is two underground, 3.8 centimeter (1.5 inch) diameter stainless steel pipes that connected the 234-5Z building with the 241-Z-8 settling tank and one 10 centimeter (4 inch) diameter carbon steel line extending from 241-Z-8 to the 216-Z-8 french drain.**Location:** The pipeline is located east of the Plutonium Finishing Plant main building. It extends beyond the double security fence.**Related Sites/ Structures:** The pipeline is associated with the 241-Z-8 tank, the 216-Z-8 french drain and also 200-W-206-PL (the pipeline to 216-Z-9).**This Site has the Following SubSites:**

Code: 200-W-205-PL:1
Names: 200-W-205-PL:1; Stainless Steel Pipeline from 234-5Z to the 241-Z-8 Silica Storage Tank
Code: 200-W-205-PL:2
Names: 200-W-205-PL:2; Carbon Steel Pipeline from 241-Z-8 Tank to 216-Z-8 French Drain

Code: 200-W-205-PL:1 **Classification:** Accepted
Names: 200-W-205-PL:1; Stainless Steel Pipeline from 234-5Z to the 241-Z-8 Silica Storage Tank **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The two stainless steel lines that fed the 241-Z-8 settling tank and the two stainless steel lines that fed 216-Z-9 crib were buried in the same soil trench for approximately 200 feet. The two lines to the 241-Z-8 settling tank diverge out of the soil trench and the two other lines continue to the 216-Z-9 crib.

The SubSite is Part Of:

Code: 200-W-205-PL
Names: 200-W-205-PL; Pipelines from 235-5Z to 241-Z-8 Silica Storage Tank and 216-Z-8 French Drain

Code: 200-W-205-PL:2 **Classification:** Accepted
Names: 200-W-205-PL:2; Carbon Steel Pipeline from 241-Z-8 Tank to 216-Z-8 French Drain **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The two stainless steel lines that fed the 241-Z-8 settling tank and the two stainless steel lines that fed 216-Z-9 crib were buried in the same soil trench for approximately 200 feet. The two lines to the 241-Z-8 settling tank diverge out of the soil trench and the two other lines continue to the 216-Z-9 crib.

The SubSite is Part Of:

Code: 200-W-205-PL
Names: 200-W-205-PL; Pipelines from 235-5Z to 241-Z-8 Silica Storage Tank and 216-Z-8 French Drain

Code: 200-W-206-PL **Classification:** Accepted
Names: 200-W-206-PL; Pipelines from 234-5Z to 216-Z-9 Crib **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is two underground, 3.8 centimeter (1.5 inch) diameter stainless steel pipes that connected the 234-5Z building with the 216-Z-9 crib.

Location: The pipeline is located east of the Plutonium Finishing Plant main building. It extends beyond the double security fence.

Related Sites/ Structures: The waste site is associated with the 216-Z-9 crib and also the 200-W-205-PL pipeline (the pipeline to the 241-Z-8 tank).

Code: 200-W-207-PL:1 **Classification:** Not Accepted
Names: 200-W-207-PL:1; Process Sewer Main Pipeline **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Not Specified **End Date:**

Description: This section of pipeline originally extended from the northwest corner of 2736-ZB to the "Z" ditches. It includes manholes Z1, Z2 and Z7.

This section of pipe is considered Active and now part of 200-W-207-PL-B.

The SubSite is Part Of:

Code: 200-W-207-PL
Names: 200-W-207-PL; 216-Z-19 and 216-Z-20 Ditches; Z Plant Radioactive Process Sewer to 216-Z-11

Code: 200-W-207-PL:2 **Classification:** Not Accepted
Names: 200-W-207-PL:2; Process Sewer Branch from 236-Z to Manhole 7 **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Not Specified **End Date:**

Description: This portion of pipe is considered Active and part of 200-W-207-PL-B.

The SubSite is Part Of:

Code: 200-W-207-PL
Names: 200-W-207-PL; 216-Z-19 and 216-Z-20 Ditches; Z Plant Radioactive Process Sewer to 216-Z-11

Code: 200-W-207-PL:3 **Classification:** Not Accepted
Names: 200-W-207-PL:3; Acid Waste Line to Manhole 3 **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Not Specified **End Date:**

Description: This section of pipeline extends from the southeast corner of 234-5Z to manhole Z3 connecting to 291-Z. This segment of pipe is considered active and part of 200-W-207-PL-B.

The SubSite is Part Of:

Code: 200-W-207-PL
Names: 200-W-207-PL; 216-Z-19 and 216-Z-20 Ditches; Z Plant Radioactive Process Sewer to 216-Z-11

Code: 200-W-207-PL-A **Classification:** Accepted
Names: 200-W-207-PL-A; Segment of PFP Process Sewer from manhole Z8 to Z Ditches **Reclassification:** None

Type: Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** The waste site is the inactive, underground vitrified clay pipe that connected to manhole number 8 to the 216-Z-1, 216-Z-11 and 216-Z-19 ditches and the 216-Z-20 tile field.**Location:** The process sewer lines extend south from the 234-5Z building and east to the 216-Z-1, 216-Z-11 and 216-Z-19 ditches. The pipeline was later diverted to the 216-Z-20 tile field.

Code: 200-W-208-PL**Classification:** Accepted**Names:** 200-W-208-PL; Pipeline from Diversion Boxes 200-W-58 and 200-W-59 to 216-Z-12 Crib**Reclassification:** None**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** The waste site is an underground, 15 centimeter (6 inch) diameter stainless steel line that fed the 216-Z-12 crib through the 200-W-59 diversion box. It extends from the 200-W-58 diversion box. The pipeline was divided into three subsites. Originally, a 12 inch diameter vitrified clay pipeline extended from the diversion box to the head end of the crib structure (subsite 2). A 6 inch stainless steel bypass line was later installed that entered the crib, south of the head end (subsite 3).**Location:** The pipeline is located south of the PFP facility. Most of it is located between the two security fences. It extends west from diversion box number 1 (200-W-58) to diversion box number 2 (200-W-59) and then drops south to the 216-Z-12 crib.**Release Description:** The pipe connecting the 200-W-59 diversion box to the 216-Z-12 perforated crib distributor pipe (200-W-208-PL) leaked and caused a thin layer of plutonium contamination between the crib and the diversion box. Four shallow wells were drilled in 1976 to evaluate the leak. Levels of plutonium activity detected were comparable to those found in the 216-Z-12 crib. (see RHO-ST-44 and SGW-39648)**Related Sites/ Structures:** The pipeline is associated with the 241-Z facility, 200-W-58, 200-W-59 and the 216-Z-12 crib.**This Site has the Following SubSites:****Code:** 200-W-208-PL:1**Names:** 200-W-208-PL:1; 6-Inch Line from 200-W-58 Diversion Box to 200-W-59 Diversion Box**Code:** 200-W-208-PL:2**Names:** 200-W-208-PL:2; 12-Inch VCP Line from 200-W-59 Diversion Box to the 216-Z-12 Crib Structure**Code:** 200-W-208-PL:3**Names:** 200-W-208-PL:3; 6-Inch SST Bypass Pipeline from 200-W-59 Diversion Box to the Center of 216-Z-12 Crib

Code: 200-W-208-PL:1**Classification:** Accepted**Names:** 200-W-208-PL:1; 6-Inch Line from 200-W-58 Diversion Box to 200-W-59 Diversion Box**Reclassification:** None**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:**

Description: Subsite 1 is the pipe segment extending (east to west) from the 200-W-58 diversion box to the 200-W-59 diversion box. It is a 6 inch diameter, stainless steel pipe. The segment is approximately 180 meters (592 feet) long.

Location: The subsite segment is located inside the southern portion of the PFP facility and between the two security fences.

The SubSite is Part Of:

Code: 200-W-208-PL

Names: 200-W-208-PL; Pipeline from Diversion Boxes 200-W-58 and 200-W-59 to 216-Z-12 Crib

Code: 200-W-208-PL:2

Classification: Accepted

Names: 200-W-208-PL:2; 12-Inch VCP Line from 200-W-59 Diversion Box to the 216-Z-12 Crib Structure

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: Subsite 2 is the original 12 inch diameter VCP pipe, extending from the 200-W-59 diversion box to the 216-Z-12 crib. The pipe segment is 22 meter (75 foot long).

Location: The segment extends from the inside to the outside of the PFP fence. It enters the north end of the 216-Z-12 crib at the center of the crib structure.

The SubSite is Part Of:

Code: 200-W-208-PL

Names: 200-W-208-PL; Pipeline from Diversion Boxes 200-W-58 and 200-W-59 to 216-Z-12 Crib

Code: 200-W-208-PL:3

Classification: Accepted

Names: 200-W-208-PL:3; 6-Inch SST Bypass Pipeline from 200-W-59 Diversion Box to the Center of 216-Z-12 Crib

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: Subsite 3 is the six inch diameter stainless steel bypass pipeline that was installed in 1968 to replace the original vitrified clay pipe crib line. It was installed west of the center of the 216-Z-12 crib. The pipe segments equal approximately 76 meter (250 feet) in length.

Location: The bypass pipeline runs along the west side of the 216-Z-12 crib to the approximate middle of the crib structure. It turns east and extends to the center of the crib structure.

The SubSite is Part Of:

Code: 200-W-208-PL

Names: 200-W-208-PL; Pipeline from Diversion Boxes 200-W-58 and 200-W-59 to 216-Z-12 Crib

Code: 200-W-209-PL

Classification: Accepted

Names: 200-W-209-PL; 207-Z Pipelines

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is three underground pipelines associated with the 207-Z Retention Basin. One 20 centimeter (8 inch) diameter carbon steel pipe extends from 234-5Z to the Retention Basin. One 15 centimeter (6 inch) diameter carbon steel pipe extends from the retention basin to the 241-Z-361 settling tank. One 15 centimeter (6 inch) diameter pipe extends from the 207-Z retention basin to Manhole #7 and flows into the process sewer (200-W-207-PL).

Location: The 207-Z Retention Basin is located southeast of the 234-5Z building and east of the 241-Z facility.

Related Sites/ Structures: The pipelines are associated with 241-Z-361, 234-5Z building and 200-W-207-PL.

This Site has the Following SubSites:

Code: 200-W-209-PL:1

Names: 200-W-209-PL:1; 8-Inch Steel Line from 234-5Z to 207-Z

Code: 200-W-209-PL:2

Names: 200-W-209-PL:2; 6-Inch Steel Line from 207-Z to 241-Z-361

Code: 200-W-209-PL:3

Names: 200-W-209-PL:3; 6-Inch Line from 207-Z to Manhole #7

Code: 200-W-209-PL:1

Classification: Accepted

Names: 200-W-209-PL:1; 8-Inch Steel Line from 234-5Z to 207-Z

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

The SubSite is Part Of:

Code: 200-W-209-PL

Names: 200-W-209-PL; 207-Z Pipelines

Code: 200-W-209-PL:2

Classification: Accepted

Names: 200-W-209-PL:2; 6-Inch Steel Line from 207-Z to 241-Z-361

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

The SubSite is Part Of:

Code: 200-W-209-PL

Names: 200-W-209-PL; 207-Z Pipelines

Code: 200-W-209-PL:3

Classification: Accepted

Names: 200-W-209-PL:3; 6-Inch Line from 207-Z to Manhole #7

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

The SubSite is Part Of:

Code: 200-W-209-PL

Names: 200-W-209-PL; 207-Z Pipelines

Code: 200-W-210-PL

Classification: Accepted

Names: 200-W-210-PL; Pipeline from 241-Z-361 Settling Tank to 216-Z-1, 216-Z-2 and 216-Z-3 Cribs and 216-Z-1A Tile Field

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is an underground, 20 centimeter (8 inch) diameter stainless steel pipeline extending from the 241-Z-361 settling tank to the 216-Z-1, 216-Z-2 and 216-Z-1A. A 20 centimeter (8 inch) diameter vitrified clay pipe feed line branches off to the 216-Z-3 crib. Another 20 centimeter (8 inch) diameter vitrified clay pipe is a crib overflow line from 216-Z-3 crib to 216-Z-1A (see subsites).

Location: The pipelines are located south of the 234-5Z facility. The majority of the lines are located south of the PFP security fence.

Related Sites/ Structures: The pipeline is associated with the 241-Z-361 settling tank, the 216-Z-1, 216-Z-2 and 216-Z-3 cribs and the 200-W-58 diversion box (diversion box #1). 200-W-174-PL tees off this pipeline.

This Site has the Following SubSites:

Code: 200-W-210-PL:1

Names: 200-W-210-PL:1; 216-Z-2 and 216-Z-1A; Stainless Steel Pipeline from 241-Z-361 (Through 200-W-58 Diversion Box) to 216-Z-1

Code: 200-W-210-PL:2

Names: 200-W-210-PL:2; 8-Inch VCP Pipe to 216-Z-3 Crib

Code: 200-W-210-PL:3

Names: 200-W-210-PL:3; 8-Inch VCP Overflow Pipe (to 216-Z-1A)

Code: 200-W-210-PL:1

Classification: Accepted

Names: 200-W-210-PL:1; 216-Z-2 and 216-Z-1A; Stainless Steel Pipeline from 241-Z-361 (Through 200-W-58 Diversion Box) to 216-Z-1

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

The SubSite is Part Of:

Code: 200-W-210-PL

Names: 200-W-210-PL; Pipeline from 241-Z-361 Settling Tank to 216-Z-1, 216-Z-2 and 216-Z-3 Cribs and 216-Z-1A Tile Field

Code: 200-W-210-PL:2

Classification: Accepted

Names: 200-W-210-PL:2; 8-Inch VCP Pipe to 216-Z-3 Crib
Reclassification: None

Type: Radioactive Process Sewer
Start Date:

Status: Inactive
End Date:

The SubSite is Part Of:

Code: 200-W-210-PL
Names: 200-W-210-PL; Pipeline from 241-Z-361 Settling Tank to 216-Z-1, 216-Z-2 and 216-Z-3 Cribs and 216-Z-1A Tile Field

Code: 200-W-210-PL:3
Classification: Accepted

Names: 200-W-210-PL:3; 8-Inch VCP Overflow Pipe (to 216-Z-1A)
Reclassification: None

Type: Radioactive Process Sewer
Start Date:

Status: Inactive
End Date:

The SubSite is Part Of:

Code: 200-W-210-PL
Names: 200-W-210-PL; Pipeline from 241-Z-361 Settling Tank to 216-Z-1, 216-Z-2 and 216-Z-3 Cribs and 216-Z-1A Tile Field

Code: 200-W-212-PL
Classification: Accepted

Names: 200-W-212-PL; Encased Transfer Line from 240-S-151 Diversion Box to Pipeline 200-W-153-PL; Lines V550, V551, V544, V546, V548 and V549
Reclassification: None

Type: Encased Tank Farm Pipeline
Start Date:

Status: Inactive
End Date:

Description: The waste site is a six line, concrete encasement from the 240-S-151 Diversion Box. Three lines (V546, V549, V551) are stubbed off and were never used. The other three lines (V544, V548 and V550) connect to a reducer, where the three lines become one line. The three lines carried REDOX steam condensate waste. They exit the encasement and feed into 200-W-153-PL.

Location: The pipeline is located northwest of 202-S. It extends west from the 240-S-151 Diversion Box.

Related Sites/ Structures: The pipeline is associated with the 240-S-151 Diversion Box, 2904-S-171, 216-S-6, 216-S-17 and pipeline 200-W-153-PL.

Process Description: Lines V546, V549 and V551 were stubbed off and never used. Lines V544, V548 and V550 transferred REDOX steam condensate waste. They tied into a 10 inch line that sent waste to 216-S-6 Crib.

Code: 200-W-213-PL
Classification: Accepted

Names: 200-W-213-PL; Lines V795, V606 and V605; Pipelines from 241-TX-153 Diversion Box and 241-TX-302A to 216-T-19 Crib
Reclassification: None

Type: Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** The waste site is two underground stainless steel pipelines inside a concrete encasement. The lines transferred waste from the 241-TX-153 Diversion Box and the 241-TX-302A Catch Tank to the 216-T-19 crib.**Location:** The pipeline is located west of Camden Ave. It extends south from inside the 241-TX tank farm at the 241-TX-153 Diversion box to the 216-T-19 crib.**Related Sites/ Structures:** The pipeline is associated with the 241-TX-153 Diversion Box, the 241-TX-302A catch tank and the 216-T-19 crib.**This Site has the Following SubSites:****Code:** 200-W-213-PL:1**Names:** 200-W-213-PL:1; Two 3.5-Inch Diameter Stainless Steel Lines Encased in Concrete from 241-TX-153 DB and 241-TX-302A to 216-T-19 Crib**Code:** 200-W-213-PL:2**Names:** 200-W-213-PL:2; 8-Inch Diameter Stainless Steel Bypass Line Around Original Crib Structure**Code:** 200-W-213-PL:1**Classification:** Accepted**Names:** 200-W-213-PL:1; Two 3.5-Inch Diameter Stainless Steel Lines Encased in Concrete from 241-TX-153 DB and 241-TX-302A to 216-T-19 Crib**Reclassification:** None**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** Line V795 extends from the 241-TX-153 Diversion Box to the 216-T-19 crib. Line V605 extends from the 241-TX-302A Catch Tank to the 216-T-19 crib. Both lines (V605 and V795) are inside the same concrete encasement.**The SubSite is Part Of:****Code:** 200-W-213-PL**Names:** 200-W-213-PL; Lines V795, V606 and V605; Pipelines from 241-TX-153 Diversion Box and 241-TX-302A to 216-T-19 Crib**Code:** 200-W-213-PL:2**Classification:** Accepted**Names:** 200-W-213-PL:2; 8-Inch Diameter Stainless Steel Bypass Line Around Original Crib Structure**Reclassification:** None**Type:** Radioactive Process Sewer**Start Date:****Status:** Inactive**End Date:****Description:** This portion of the pipeline is the bypass line around the original crib structure.**The SubSite is Part Of:**

Code: 200-W-213-PL
Names: 200-W-213-PL; Lines V795, V606 and V605; Pipelines from 241-TX-153 Diversion Box and 241-TX-302A to 216-T-19 Crib

Code: 200-W-214-PL **Classification:** Accepted

Names: 200-W-214-PL; Pipeline from 291-Z to 216-Z-13 French Drain **Reclassification** None

Type: Radioactive Process Sewer **Start Date:**

Status: Active **End Date:**

Description: The waste site is two separate underground, 7.6 and 10 centimeter (3 inch and 4 inch) diameter pipelines from the 291-Z building to the 216-Z-13 French Drain.

Location: The pipelines are located inside the PFP security fence. It is adjacent to the east side of the 291-Z building.

Related Sites/ Structures: The pipeline is associated with the 216-Z-13 French Drain.

Code: 200-W-215-PL **Classification:** Accepted (Proposed)

Names: 200-W-215-PL; Pipeline from 291-Z to 216-Z-14 French Drain **Reclassification** None

Type: Radioactive Process Sewer **Start Date:**

Status: Active **End Date:**

Description: The waste site is an underground, 10 centimeter (4 inch) diameter pipeline from the 291-Z building to the 216-Z-14 French Drain.

Location: The pipeline is located inside the PFP security fence. It is adjacent to the west side of the 291-Z building.

Related Sites/ Structures: The pipeline is associated with the 216-Z-14 French Drain and the 291-Z building.

Process Description: The lower french drain receives steam condensate from the turbine of the ET-9 exhaust fan and 291-Z floor drainage.

Code: 200-W-216-PL **Classification:** Accepted

Names: 200-W-216-PL; Pipelines from 291-Z to 216-Z-15 French Drain **Reclassification** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 10 centimeter (4 inch) diameter pipeline from the 291-Z building to the 216-Z-15 French Drain.

Location: The pipeline is located inside the PFP security fence. It is adjacent to the north side of the 291-Z building.

Related Sites/ Structures: The pipeline is associated with the 216-Z-15 French Drain.

Code: 200-W-217-PL **Classification:** Accepted (Proposed)
Names: 200-W-217-PL; Pipeline from the Counting Box to 216-U-7 French Drain **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is an underground, 7.6 centimeter (3 inch) diameter steel pipe that transferred waste from the Counting Box structure to the 216-U-7 French Drain.
Location: The pipeline is located on the southeast side of the 221-U Building near Section 6. It is northwest of the 241-UX-154 Diversion Box.

Related Sites/ Structures: The pipeline is associated with the 216-U-7 French Drain.

Code: 200-W-218-PL **Classification:** Accepted
Names: 200-W-218-PL; Pipeline from 216-U-10 Pond to 216-U-9 Ditch **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is an underground, 0.8 meter (30 inch) corrugated metal pipe that transferred waste from the 216-U-10 pond to the 216-U-9 ditch.
Location: The pipeline extends from the southwest corner of 216-U-10 pond. It crosses under 13th Street.

Related Sites/ Structures: The pipeline is associated with the 216-U-10 Pond and the 216-U-9 ditch.

Code: 200-W-219-PL **Classification:** Accepted
Names: 200-W-219-PL; 241-Z Primary Pipe Trench; Pipe Tunnel 3; Pipelines from 235-Z to the North Side of 241-Z **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is six underground stainless steel pipes inside a concrete encasement that transferred waste from 234-5Z to the 241-Z tanks. The pipe diameters range from 7.6 centimeters (3 inch) to 20 centimeters (8 inch).
Location: The pipelines inside an encasement, known as a pipe tunnel, that extends from the south wall of 234-5Z to the north side of 241-Z. They are located inside the PFP security fence.
Release Description: Between 11,400 liters (3,000 gallons) and 114,000 liters (30,000 gallons) of waste is estimated to have leaked into the concrete pipe trench and effected the soil below the trench. See sitecode 200-W-171.

Related Sites/ Structures: The pipeline is associated with the 241-Z tanks and Unplanned Release sitecode 200-W-171.

Code: 200-W-220-PL **Classification:** Accepted

Names: 200-W-220-PL; Pipeline from 241-Z to 241-Z-361 Settling Tank **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 15 centimeter (6 inch) diameter stainless steel pipe that transferred waste from the 241-Z tanks to the 241-Z-361 settling tank.

Location: The pipeline is located inside the PFP security fence. It extends from the south wall of the 241-Z tank pit to the 241-Z-361 Settling Tank.

Related Sites/ Structures: The pipeline is associated with the 241-Z Tank Pit and the 241-Z-361 settling tank.

Code: 200-W-221-PL **Classification:** Accepted

Names: 200-W-221-PL; Pipeline from 2724W to Laundry Waste Crib (216-W-LWC) **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 20 centimeter (8 inch) diameter vitrified clay pipe that fed the Laundry Waste Crib (216-W-LWC). It also include the drain line from the Mask Cleaning Station (MO-412).

Location: The pipeline is located south of 20th Street and east of Beloit Ave.

Related Sites/ Structures: The pipeline is associated with 216-W-LWC (Laundry Waste Crib) and pipeline 200-W-102-PL.

Process Description: Pipeline 200-W-102-PL carried laundry waste to the 216-U-14 ditch. When the laundry effluent was diverted to the 216-W-LWC Crib in 1981, the 200-W-102-PL pipeline was plugged west of the manhole located north of the 2723-W building. The portion of the pipeline that was reused to transfer mask cleaning effluent from 2723-W and laundry waste from 2724-W to the 216-W-LWC (Laundry Waste Crib) became part of sitecode 200-W-221-PL.

Code: 200-W-222-PL **Classification:** Accepted

Names: 200-W-222-PL; 207-U Retention Basin Outlet Pipeline to the 216-U-14 Ditch **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 0.61 meter (2 foot) diameter vitrified clay pipe. The pipe carried effluent out of the 207-U Retention Basin to the 216-U-14 Ditch.

Location: The pipeline is located north of 16th Street and east of Camden Ave. It extends from the west

side of the 207-U Retention Basin.

Related Sites/ Structures: The pipe is associated with 207-U and 216-U-14 ditch.

Code: 200-W-223-PL **Classification:** Accepted
Names: 200-W-223-PL; Pipeline from 242-S Evaporator to 216-U-14 Ditch **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is an underground, 0.61 meter (2 foot) diameter corrugated metal pipe that transferred effluent from the 242-S Evaporator building to the 216-U-14 ditch.
Location: The pipeline is located on the west side of Cooper Ave. It extends north from the 242-S Evaporator to the 216-U-14 ditch. It crosses under Cooper Ave.

Related Sites/ Structures: The pipeline is associated with the 216-U-14 ditch.

Code: 200-W-224-PL **Classification:** Accepted
Names: 200-W-224-PL; Pipeline from 234-5Z and 236-Z to West Side of 241-Z **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is four underground, 5 or 7.6 centimeter diameter (2 inch or 3 inch) stainless steel pipelines buried in the same soil trench. Each stainless steel line is encased inside a 15 centimeter (6 inch) diameter pipe. The piping is inside a 10 inch diameter galvanized steel duct that is coated with polyurethane. The waste site was divided into two subsites.
Location: The pipeline is located inside the Plutonium Finishing Plant security fence. It extends south from 234-5Z and connects to the west side of 241-Z.

Related Sites/ Structures: The pipeline is associated with 234-5Z, 236-Z, and 241-Z.

This Site has the Following SubSites:

Code: 200-W-224-PL:1
Names: 200-W-224-PL:1; Pipeline from 234-5Z to West Side of 241-Z
Code: 200-W-224-PL:2
Names: 200-W-224-PL:2; Pipeline from 236-Z Connecting to Pipeline from 234-5Z to West Side of 241-Z

Code: 200-W-224-PL:1 **Classification:** Accepted
Names: 200-W-224-PL:1; Pipeline from 234-5Z to West Side of 241-Z **Reclassification:** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

Description: Subsite 1i is the portion of piping extending from 234-5Z to West Side of 241-Z.

The SubSite is Part Of:

Code: 200-W-224-PL

Names: 200-W-224-PL; Pipeline from 234-5Z and 236-Z to West Side of 241-Z

Code: 200-W-224-PL:2

Classification: Accepted

Names: 200-W-224-PL:2; Pipeline from 236-Z
Connecting to Pipeline from 234-5Z to West Side
of 241-Z

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: Subsite 2 is the portion of piping from 236-Z connecting to Pipeline from 234-5Z to West Side of 241-Z.

The SubSite is Part Of:

Code: 200-W-224-PL

Names: 200-W-224-PL; Pipeline from 234-5Z and 236-Z to West Side of 241-Z

Code: 200-W-225-PL

Classification: Accepted

Names: 200-W-225-PL; PFP Six Inch Condensate Line
Connecting to Process Sewer

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site begins as an underground, 15 centimeter (6 inch diameter) carbon steel condensate pipeline that connected 234-5Z with the Z Plant Process Sewer (see sitecode 200-W-207-PL). Other portions of the pipe are constructed of transite and corrugated metal.

Location: The pipeline is located inside the Plutonium Finishing Plant security fence. It extends from the southwest corner of 234-5Z to southeast of 232-Z.

Related Sites/ Structures: The pipeline is associated with 234-5Z and the 200-W-207-PL process sewer.

Process Description: A portion of this pipeline was removed during the construction of the 232-Z building (around 1960). The pipeline was redesigned to direct the flow around the 232-Z building.

Code: 200-W-226-PL

Classification: Accepted

Names: 200-W-226-PL; Lines V326, V671 and V706;
Pipeline from 224-T (Plutonium Concentration
Facility) to 241-T-361 Settling Tank and 216-T-3
Reverse Well

Reclassification: None

Type: Radioactive Process Sewer

Start Date:

Status: Inactive

End Date:

Description: The waste site is an underground, 7.6 centimeter (3 inch) diameter stainless steel pipeline that

carried waste from the 224-T Plutonium Concentration Facility to the 216-T-361 Settling Tank and the 216-T-3 Reverse Well.

Location: The pipeline is located north of 23rd Street. It extends from the east side of 224-T to the 216-T-3 Reverse Well.

Release Description: UPR-200-W-102 may be associated with this pipeline.

Related Sites/ Structures: The pipeline is associated with 216-T-3 reverse well and 241-T-361 settling tank, pipeline 200-W-132-PL, and UPR-200-W-102.

Code: 200-W-227-PL **Classification:** Accepted

Names: 200-W-227-PL; Pipeline from 221-T Separations Facility to 216-T-6 Crib **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 7.6 centimeter (3 inch) diameter stainless steel pipeline that fed the 216-T-6 cribs.

Location: The pipeline is located on the north side of 23rd Street. It extends from the east side of 221-T, turns south and then runs west to the 216-T-6 cribs.

Related Sites/ Structures: The pipeline is associated with the 216-T-6 cribs.

Code: 200-W-228-PL **Classification:** Accepted

Names: 200-W-228-PL; 3-Inch Contaminated Waste Line; Pipeline from 232-Z to 241-Z **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 7.6 centimeter (3 inch) diameter pipeline from 232-Z to 241-Z. It is labeled on drawings as "contaminated waste line".

Location: The pipeline is located inside the Plutonium Finishing Plant security fence, south of 234-5Z. It extends from 232-Z to the west side of 241-Z.

Related Sites/ Structures: The pipeline is associated with 241-Z.

Code: 200-W-229-PL **Classification:** Accepted

Names: 200-W-229-PL; Pipeline from 2736-ZB to 241-Z **Reclassification:** None

Type: Radioactive Process Sewer **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is an underground, 7.6 centimeter (3 inch) diameter carbon steel pipeline extending from the southeast corner of 2736-ZB to the west side of 241-Z.

Location: The pipeline is located inside the Plutonium Finishing Plant security fence, south of 234-5Z. It

extends from 232-Z to the west side of 241-Z.

Related Sites/ Structures: The pipeline is associated with 241-Z.

Code: 200-W-230-PL	Classification: Accepted
Names: 200-W-230-PL; Pipeline from Railroad Unloading Station to 276-S-141 and 276-S-142 Hexone Tanks	Reclassification: None
Type: Radioactive Process Sewer	Start Date:
Status: Inactive	End Date:

Description: The waste site is a series of underground carbon steel pipelines associated with the 276-S-141 and 276-S-142 hexone tanks. A 6 centimeter (2.5 inch) diameter carbon steel line extended from the railroad track to the tanks. A 6 centimeter (2.5 inch) diameter outlet line and a 5 centimeter (2 inch) diameter inlet line is associated with each tank.

Location: The pipeline is located northwest of the 202-S canyon building.

Related Sites/ Structures: The pipeline is associated with the 276-S-141 and 276-S-142 hexone tanks.

Process Description: The tanks stored various liquid mixed wastes until 1992, when most of the waste was transferred to tank cars for off-site incineration. From 1951 to 1967 the tank was used to store reagent-grade hexone for makeup as a solvent at REDOX. The hexone was delivered to REDOX in rail cars that were unloaded into the 276-S-141 and 241-S-142 tanks via underground lines at the railcar unloading station.

This Site has the Following SubSites:

Code: 200-W-230-PL:1
Names: 200-W-230-PL:1; 2.5-Inch Carbon Steel Line from Railroad Track "Car Spot" to the 276-S-141 and 276-S-142 Tanks

Code: 200-W-230-PL:2
Names: 200-W-230-PL:2; 2.5-Inch Outlet Line and 2-Inch Inlet Line Associated with 276-S-141

Code: 200-W-230-PL:3
Names: 200-W-230-PL:3; 2.5-Inch Outlet Line and 2-Inch Inlet Line Associated with 276-S-142

Code: 200-W-230-PL:1	Classification: Accepted
Names: 200-W-230-PL:1; 2.5-Inch Carbon Steel Line from Railroad Track "Car Spot" to the 276-S-141 and 276-S-142 Tanks	Reclassification: None
Type: Radioactive Process Sewer	Start Date:
Status: Inactive	End Date:

The SubSite is Part Of:

Code: 200-W-230-PL
Names: 200-W-230-PL; Pipeline from Railroad Unloading Station to 276-S-141 and 276-S-142 Hexone Tanks

Code: 200-W-230-PL:2 **Classification:** Accepted
Names: 200-W-230-PL:2; 2.5-Inch Outlet Line and 2-Inch Inlet Line Associated with 276-S-141 **Reclassification** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

The SubSite is Part Of:

Code: 200-W-230-PL
Names: 200-W-230-PL; Pipeline from Railroad Unloading Station to 276-S-141 and 276-S-142 Hexone Tanks

Code: 200-W-230-PL:3 **Classification:** Accepted
Names: 200-W-230-PL:3; 2.5-Inch Outlet Line and 2-Inch Inlet Line Associated with 276-S-142 **Reclassification** None
Type: Radioactive Process Sewer **Start Date:**
Status: Inactive **End Date:**

The SubSite is Part Of:

Code: 200-W-230-PL
Names: 200-W-230-PL; Pipeline from Railroad Unloading Station to 276-S-141 and 276-S-142 Hexone Tanks

Code: 200-W-232 **Classification:** Accepted
Names: 200-W-232; 2607-WT Replacement Septic Tank and Dry Well **Reclassification** None
Type: Septic Tank **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is an underground septic tank and associated dry well. It is surrounded with post and chain and a sign that reads "MISF". The acronym stands for Miscellaneous Inactive Storage Facility.

Location: The septic tank and dry well are located northeast of the 242-T Evaporator building near an entrance gate to the 241-TY Tank Farm. The septic system is located outside the tank farm fence.

Process Description: The 2607-WT septic system is located inside the tank farm fence,. It was abandoned. The new system was placed outside the tank farm fence. It consists of a septic tank and a dry well. It serviced the 242-T Evaporator building.

Code: 200-W-234 **Classification:** Accepted
Names: 200-W-234; 291-U Sand Filter French Drain **Reclassification** Consolidated (7/15/2015)
Type: French Drain **Start Date:**
Status: Inactive **End Date:**

Description: The french drain is a vertical concrete pipe filled with gravel.

Location: The french drain is located adjacent to the southwest corner of the 291-U sand filter structure.

(coordinates per Qmap = N135206/E567667)

Related Sites/ Structures: This drain is associated with the 291-U Sand Filter (WIDS sitecode 200-W-44).

Process Description: The french drain received condensate drainage from the 291-U sand filter.

This Site Was Consolidated With:

Code: 200-W-44

Names: 200-W-44; 291-U Stack Sand Filter

Code: 200-W-235-PL **Classification:** Accepted

Names: 200-W-235-PL; Pipeline from 241-SX-701 Building to S Pit; 200-W-162-PL Replacement Pipeline **Reclassification:** None

Type: Process Sewer **Start Date:** 1/1/1965

Status: Inactive **End Date:**

Description: There is no visual evidence of the pipeline on the surface. It is a 7.6 centimeter (3 inch) diameter, stainless steel pipe.

Location: The pipeline is located east of the 241-S Tank Farm perimeter fence.

Related Sites/ Structures: The pipeline is associated with the 241-SX-701 building, the 200-W-236 pit and the 200-W-162-PL pipeline.

Process Description: The pipeline carried effluent from the 241-SX-701 Compressor House to a pit located south of 241-S Tank Farm. The pit is WIDS sitecode 200-W-236.

Code: 200-W-236 **Classification:** Accepted

Names: 200-W-236; Pit South of 241-SX Tank Farm **Reclassification:** None

Type: Depression/Pit (nonspecific) **Start Date:**

Status: Inactive **End Date:**

Description: The pit is a large, irregular shaped depression.

Location: The pit is located south of the 241-SX tank farm, east of Cooper Ave.

Related Sites/ Structures: The pit is associated with the 200-W-235-PL pipeline.

Process Description: Drawing H-2-33593 shows a 3 inch steel line extending from the 241-SX-701 Compressor House to the pit. A note on the drawing says "Discharge to existing pit". This pipeline replaced the pipeline that had sent compressor house effluent to the 241-SX-2 crib (see 200-W-162-PL).

Code: 200-W-237 **Classification:** Accepted

Names: 200-W-237; Effluent Pond South of T Plant **Reclassification:** None

Type: Pond **Start Date:**

Status: Inactive**End Date:**

Description: The waste site is square, open excavation was visually apparent in January 2011. It is surrounded by several orange stakes. The top of the square excavation is estimated to be approximately 15 by 15 meters (50 by 50 feet) and 1.2 meters (four feet) deep. A grey polyvinyl chloride pipe is visible extending into the excavation in the northeast corner of the hole.

Location: The square excavation is located about 6 meters (20 feet) south of 23rd Street, near Beloit Ave. in 200 West Area.

Related Sites/ Structures: The excavation is fed by a 4 inch PVC pipeline that originates at the 224-T building.

Process Description: The excavation is labeled "Pond" on H-2-44511, sheet 132. However, the excavation was never assigned a Hanford liquid waste site number. Cribs, ponds and ditches in the 200 Areas were usually assigned a number that began with 216, indicating it was a liquid waste site in the 200 Area (116 indicates a liquid waste site in 100 Areas and 316 indicates a liquid waste site in 300 Area). Since it was not assigned a number, it is possible it was built but never put into service. H-2-44511, sheet 132 says the drain line has been plugged and abandoned.

Code: 200-W-238**Classification:** Accepted**Names:** 200-W-238; Large Diameter French Drain North of 241-U**Reclassification:** None**Type:** French Drain**Start Date:****Status:** Inactive**End Date:**

Description: The french drain is surrounded with chain and a sign that reads "MISF Area, No Vehicles or Storage, Contact Shift Office prior to Entry". The blue building in the background (inside the tank farm fence) is the 241-U-271 Control House. MISF means Miscellaneous Isolated Storage Facility.

Location: The large diameter french drain is located in 200 West Area, on the west side of Camden Ave., adjacent to the north side of the 241-U Tank Farm fence.

Process Description: Drawings H-2-40093 and H-2-40241 show this french drain is connected to the 241-U-271 Control House mechanical equipment room via a 15 centimeter (6 inch) diameter vitrified clay pipeline encased in concrete.

Code: 200-W-239**Classification:** Accepted**Names:** 200-W-239; 211-U and 211-UA Potential Asbestos in Soil; Post Remediation URMA**Reclassification:** None**Type:** Unplanned Release**Start Date:****Status:** Inactive**End Date:**

Description: The waste site was originally an irregularly shaped, posted Underground Radioactive Material Area (URMA) that was defined after the 211-A and 211-UA tank farms were demolished in 2009. Following demolition, three to six inches of surface material was removed prior to applying a gravel cap. Determination of potential asbestos containing material (ACM) left in place and abated during demolition is based on a Quality Assurance review of project documentation and interviews with activity personnel.

Location: The area is located on the northwest side of 221-U. It is west of Beloit Ave. and north of 16th

Street.

Related Sites/ Structures: The demolished tank farm and resulting URMA are associated with 221-U, 221-U:1 and 221-U:2.

Process Description: The aboveground features of the 211-U Tank Farm were removed in 2009. It was a bulk liquid storage area, consisting of nine aboveground storage tanks. The tanks are located on the west side of the 221-U building. Six tanks are horizontal tanks, 2.7 meter diameter, 11 meters long (9 foot diameter, 36 feet long). Three of the horizontal tanks were sodium hydroxide storage tanks, one was a demineralized water storage tank and two were considered spare tanks. Three tanks are vertical tanks, 3 meter diameter, 4.2 meters high (10 foot diameter, 14 feet high). One was a demineralized water storage tank and two were chemical make-up tanks. The bulk liquid was transferred to the 211-U tanks from rail cars or trucks.

The aboveground features of the 211-UA (alias 211-AU) Tank Farm were removed in 2009. It consisted of sixteen aboveground storage tanks. Thirteen tanks had a capacity of 380,000 liters (100,000 gallons) each. The tanks were located on the west side of the 221-U building. Nine of these tanks were nitric acid storage tanks and four were sodium hydroxide storage tanks. Three smaller tanks 2.7 meters in diameter and 2.7 meters tall (9 feet diameter, 9 feet tall) were nitric acid sample tanks. The bulk liquid was transported to the tanks in railcars or trucks.

Code: 200-W-240	Classification: Accepted
Names: 200-W-240; Contaminated Rabbit Feces Area South and West of 272S	Reclassification: None
Type: Contamination Migration	Start Date:
Status: Not Specified	End Date:
Description: The waste site is a large area posted with Contamination Area signs. Contaminated rabbit feces have been found in this area for many years.	
Location: The waste site is located on the south and west sides of the 272-S building, on the west side of Cooper Ave. in 200 West Area.	

Code: 200-W-241	Classification: Accepted
Names: 200-W-241; Contaminated Tumbleweed Fragment Areas West of Cooper Ave.	Reclassification: None
Type: Contamination Migration	Start Date:
Status: Not Specified	End Date:
Description: The waste site is multiple posted Contamination Areas. The areas contain contaminated tumbleweeds and contaminated tumbleweed fragments. One area surrounds several conex boxes and one is located on the north side of the MO-027 trailer. A large posted contamination area extends northward from the MO-633 trailer, into the vacant property. Tumbleweeds are visible beneath the MO-633 trailer.	
Location: The areas are located on the west side of Cooper Ave., west of the 242-S Evaporator building.	

Code: 200-W-242	Classification: Accepted
Names: 200-W-242; Area of Debris and Subsurface	Reclassification: None

Anomalies on Unused Portion of 218-W-4C
Annex site

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The waste site is an area of partially buried and surface debris. A large lag bolt and a crushed 8 inch diameter pipe were identified.

Location: The debris area is located west of Dayton Ave and north of 16th Street. It is located in northern part of the unused portion of the 218-W-4C Burial ground, known as the 218-W-4C Annex.

Related Sites/ Structures: This area is associated with the unused portion of the 218-W-4C Burial ground, known as the 218-W-4C Annex.

Code: 200-W-243

Classification: Accepted

Names: 200-W-243; Lead Slag near 2727-WA Sodium Storage Building

Reclassification: None

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The waste site is scattered fragments of lead slag in gravel and soil. The area has been estimated to be 200 feet long by 100 feet wide.

Location: The lead slag area is along an unnamed gravel access road, north of 16th Street, north of the 2727-WA building. It is near a railroad track.

Process Description: The small pieces of lead may be "drips" of lead from old welding operations that were done many years ago, perhaps in the late 1940's or 1950's. A discarded welding rod was found in this area.

Code: 200-W-245

Classification: Accepted

Names: 200-W-245; 284W and 2710W Potential Asbestos Hazard Site

Reclassification: None

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The waste site is the location where the 284W Powerhouse and 2710W Coal Shed were demolished. It is a gravel area, partially capped. The area is surrounded with posts, cement blocks and rope. Signs on the rope state "Caution: Potential Asbestos Hazard; Transite in the Soil; No ground-intrusive or heavy equipment activities in this area unless specifically authorized by controlling project OS", with a Contact phone number and required Protective Clothing listed. The gravel cap extended in September 2012 and now includes the 2710W coal shed footprint. Determination of asbestos containing material (ACM) left in place and abated during demolition is based on a Quality Assurance review of project documentation and interviews with activity personnel.

Location: The site is located west of Beloit Ave. and south of 20th Street, where the 284W powerhouse and 2710W Coal Shed had been located.

Code: 200-W-246 **Classification:** Accepted

Names: 200-W-246; Buildings 2707W, 2723W, 277W and 272W; Industrial Seven Area Potential Asbestos Hazard Site **Reclassification** None

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The 200 West Area shop structures were demolished in 2009. The waste site is a gravel capped area surrounded with concrete blocks, posts and chain. Signs on the chain state "Caution: Potential Asbestos Hazard; Transite in the Soil; No ground-intrusive or heavy equipment activities in this area unless specifically authorized by controlling project OS&H" with a Contact phone number and required Protective Clothing listed.

Although the area is referred to as Industrial Seven, only six buildings are covered by the gravel cap. The six demolished buildings covered by the gravel cap are: 272W, 277W, 2723W, 2728W, 2720W and 274W. Buildings 2707W, 2723W, 277W and 272W were determined to potentially have asbestos containing material left in place. Determination of ACM left in place and abated during demolition is based on a Quality Assurance review of project documentation and interviews with activity personnel.

Location: The site is located east of Beloit Ave. and north of 20th Street where the 200 West Area shop buildings had been located.

Code: 200-W-247 **Classification:** Accepted

Names: 200-W-247; PFP Potential Asbestos Hazard Sites **Reclassification** None

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The waste site is three gravel areas surrounded with posts and chain. Signs on the chain state "Caution: Potential Asbestos Hazard; Transite in the Soil; No ground-intrusive or heavy equipment activities in this area unless specifically authorized by controlling project OS&H". Although the areas are gravel, no additional gravel cap has been placed on these sites. Three In-Use groundwater wells along with aboveground pump and treat piping and electric cables are located inside the large posted area north of 216-Z-9 crib. Another large posted area is east of MO273 and encompasses the 216-Z-8 tank and french drain. A smaller, triangle shaped posted area is south of MO273.

Location: There are three posted areas. One is located on the east side of the 200-W-70 Burn Pit waste site, adjacent to the west side of the MO273 trailer. One is located near the southeast corner of the MO273 office trailer. One is north of the 216-Z-9 crib. They are all west of Camden Ave. and south of 19th Street.

Related Sites/ Structures: The potential asbestos may be associated with the old PFP burn pit, sitecode 200-W-70. MO273 is situated on top of where the old burn pit was located. The posted area for 200-W-247 encompasses the north side of the MO273 trailer.

Code: 200-W-249 **Classification:** Accepted

Names: 200-W-249; 2736-ZB and 2736-ZC Concrete Slabs **Reclassification** None

Type: Foundation

Start Date:

Status: Inactive**End Date:****Description:** The waste site is the concrete building foundations that remain after demolition of the 2736-ZB and adjacent 2736-ZC buildings.

The 2736-Z complex included buildings 2721-Z, 2731-ZA, 2736, 2736-ZA, 2736-ZB and 2736-ZC. Post demolition radiological surveys identified contamination on the 2736-ZB and 2736-ZC concrete floor slabs. The spots of contamination were fixed to the concrete with paint. The painted spots were covered with metal plates and a silicone sealant (RTV). The slabs were covered with approximately 6 inches of gravel. The area is posted as underground radioactive material area (URMA). This WIDS site consists of the two, adjacent concrete slabs where contamination was found. The posted URMA extends beyond the contaminated concrete slabs as a precaution only. The URMA extension is not considered part of the this WIDS site.

Location: The 2736-Z Complex was located southwest of the 234-5Z building (Plutonium Finishing Plant) in the 200 West Area.

Code: 200-W-250**Classification:** Accepted**Names:** 200-W-250; 2704W Potential Asbestos in Soil**Reclassification:** None**Type:** Dumping Area**Start Date:****Status:** Inactive**End Date:****Description:** The waste site is the location of the demolished 2704W building. It is currently not marked or posted. It was gravel capped after demolition and several ARRA trailers set here temporarily.**Location:** The 2704W building had been located south of 20th Street and east of Baltimore Ave. It was south of the gravel area known as Industrial Seven area (sitecode 200-W-246).

Code: 200-W-251**Classification:** Accepted**Names:** 200-W-251; 2722W Potential Asbestos in Soil**Reclassification:** None**Type:** Dumping Area**Start Date:****Status:** Inactive**End Date:****Description:** The waste site is the former location of the demolished 2722W welding lab building. It is currently a cement slab that is not marked or posted. The area is currently being used for parking vehicles.**Location:** The 2722W building had been located east of Beloit Ave, north of 21st Street.

Code: 200-W-252**Classification:** Accepted**Names:** 200-W-252; X8 Railcar Shed Potential Asbestos in Soil**Reclassification:** None**Type:** Dumping Area**Start Date:****Status:** Inactive**End Date:****Description:** The waste site is the location of the demolished railcar shed known as X8. It is currently not marked or posted.**Location:** The X8 shed was located next to rail line switch gear, southwest of MO-278. It is northwest of

the intersection of 20th Street and Beloit Ave.

Code: 200-W-253 **Classification:** Accepted

Names: 200-W-253; 233-S and 233-SA Contaminated Soil Footprint **Reclassification:** None

Type: Post Demolition Remediation Area **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is the footprint of the demolished 233-S and 233-SA buildings. The building footprints were covered with concrete and two feet of gravel. They form a single, "L-Shaped" polygon. Contaminated soil, piping and ducting remain beneath the concrete and gravel cap. The footprint is located inside a locked, chain link fence. The chain link fence is posted with Underground Radioactive Material signs.

Location: The waste site is located on the north side of the 202-S canyon facility.

Process Description: Between 1963 and 1967 the 233-S facility was used to concentrate neptunium and plutonium nitrate solutions from REDOX. Prior to 1963 the 233-S facility provided final purification and concentration of plutonium solutions using ion exchange technologies. The 233-SA building housed two banks of double high-efficiency particulate air (HEPA) filters. Each filter bank had its own exhaust fan, stack, and monitoring instrumentation.

Code: 200-W-255 **Classification:** Discovery

Names: 200-W-255; PFP Remediation Area **Reclassification:** None

Type: Post Demolition Remediation Area **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is the area designated to be the post demolition remediation area following the D&D activities at the Plutonium Finishing Plant (PFP). The PFP structures will be removed to "slab on grade" status. The post demolition remediation area will address any remaining subsurface structures, pipelines and contaminated soil. The waste site boundaries are based on the original, outer fence that surrounded the facility when it was active.

Location: The Plutonium Finishing Plant (PFP) is located inside 200 West Area, west of Canton Ave and south of 19th St.

Related Sites/Structures: Multiple WIDS sites, including pipelines, are located within this remediation boundary. Many buildings are within this boundary that are planned to be demolished.

The 200-W-249 waste site was created for the concrete building foundations that remain after demolition of the 2736-ZB and adjacent 2736-ZC buildings.

The 200-W-171 waste site is a release that occurred within the concrete pipe trench. The concrete pipe trench is a subsurface feature extending from 234-5Z to 241-Z (see sitecode 200-W-219-PL).

The 200-W-172 waste site is a series of underground pipes suspected to have leaked. Secondary drain laterals conveyed liquid from various points inside and beneath the 234-5Z building to the main drain lines in the subsurface pipe tunnels. Visual observations in the pipe tunnels revealed little evidence of substantial leakage.

Code: 213-W-1 **Classification:** Accepted
Names: 213-W-1; 213-W-TK-1; 213-W Compactor Facility Retention Tank **Reclassification:** None
Type: Storage Tank **Start Date:** 1/1/1985
Status: Inactive **End Date:** 1/1/1995

Description: The 213-W-TK-1 Retention Tank is a below grade steel tank. It was plumbed to the 213-W HVAC System, the 272-WA Service Garages, and the 213-W Compactor Room.

Location: This tank is located east of the 213-W Compactor Facility, and north of the 272-WA Building.

Related Sites/Structures: Structures associated with the tank include effluent drain lines, floor drains in the 272-WA Service Garages, the 213-W compactor room, and drains at the high-efficiency particulate air filter system.

Process Description: The unit collected drainage from floor drains in the 213-W Compactor Room, and the 272-WA Service Garage. The tank also received heating ventilation and air conditioning condensate. Water was released from the tank if no radionuclides were found during analysis.

Waste Type: Water

Waste Description: The unit was used to collect drainage water from 272-WA service garages, drainage from the compactor room floor, and condensate from the high-efficiency particulate air filter system. The unit had the possibility of containing radioactive wastes in the event that they were introduced into the process. The water was analyzed periodically for radioactive materials. After analysis, the water was released if no radioactive materials were present. The IMUST Checklist and Photo report, issued in April 1998, states the tank contains non-radioactive water.

Code: 2607-W13 **Classification:** Discovery
Names: 2607-W13; Construction Trailers Septic; JA Jones/Kaiser Constriction Trailers Septic **Reclassification:** None
Type: Septic Tank **Start Date:**
Status: Inactive **End Date:**

Description: There is no visual evidence of a septic tank. The tank was listed in the 2007 Hanford Site Sanitary Liquid Waste and Sanitary Solid Waste Master Plan.

Location: The septic tank is supposed to be located north of 19th Street and west of Beloit Ave, in the Construction Trailer area.

Process Description: There is very little information documented for this septic system.

Code: 2607-W16 **Classification:** Accepted
Names: 2607-W16; Large Onsite Sewer System (LOSS); 200 West Area Regional Wastewater System **Reclassification:** None
Type: Septic Tank **Start Date:** 1/1/2003
Status: Active **End Date:**

Description: The waste site is an active septic system. The septic tile field is marked and posted.

Location: The septic system is located east of Bridgeport Ave. and north of 20th Street. It is northwest of the 284-W Powerhouse.

Related Sites/ Structures: This septic system is associated with 2607-Z1 and 2607-W1.

Process Description: The 2607-W16 sanitary septic system was installed to receive the waste volume that was overwhelming the 2607-W1 system. The entire Plutonium Finishing Plant (PFP) sanitary waste volume was redirected to the 2607-W16 sanitary system. An average flow of 6845 gallons per day is sent to the 2607-W16 septic system.

Waste Type: Sanitary Sewage

Waste Description: The entire Plutonium Finishing Plant (PFP) sanitary waste volume was redirected to the 2607-W16 sanitary system. An average flow of 6845 gallons per day is sent to the 2607-W16 septic system.

Code: 2607-WUT **Classification:** Accepted

Names: 2607-WUT; 2607-WUT Septic Tank and Tile Field **Reclassification:** None

Type: Septic Tank **Start Date:** 1/1/1951

Status: Inactive **End Date:**

Description: The 2607-WUT Septic Tank is constructed of steel and includes a drain field. It is surrounded with an "L" shaped chained area and signs that read Sanitary Tile Field. There is a depressed area on the east end, inside the chain, that indicates a cave-in has occurred over the tile field. There is also a corrugated metal caisson, posted with a Confined Space sign, in the northwest corner of the chained tile field.

Location: This unit is located north of the 241-U Tank Farm.

Related Sites/ Structures: The 2607-WUT Septic Tank is associated with the 241-U-271 Control House.

Process Description: The 2607-WUT Septic Tank and drain field were designed to accept sanitary sewer effluent from the associated structures. H-2-40241 states that it is fed by a 15.2 centimeter (6 inch) vitrified clay pipe that is encased in concrete.

Waste Type: Sanitary Sewage

Waste Description: The current flow rates for the 2607-WUT septic system are unknown. This system received sanitary sewer effluent at an estimated rate of 36 cubic feet (1.02 cubic meters) per day in 1987.

Code: 232-Z **Classification:** Accepted

Names: 232-Z; 232-Z Building Foundation; 232-Z Incineration Facility; 232-Z Incinerator; 232-Z Waste Incineration Facility **Reclassification:** None

Type: Process Unit/Plant **Start Date:** 1/1/1959

Status: Inactive **End Date:** 1/1/1976

Description: The 232-Z above grade structures were demolished to slab on grade in July 2006. All penetrations through the floor slab were plugged with grout or a fire block material (low density silicone elastomer) prior to building demolition. After building demolition, the floor slab was

painted with Polymeric Barrier System (PBS) fixative and then covered with a minimum of 6 inches of gravel. The gravel covered slab is posted with Underground Radioactive Material signs. Fixed contamination was identified on the sidewalk between 232-Z and 2731-ZA. The sidewalk was sprayed with a vinyl material and painted yellow. A section of asphalt south of 2736-ZC (adjacent to 232-Z) was found to be contaminated. This area was re-surfaced with asphalt. All areas were posted as Underground Radioactive Material Areas (URMA).

The underground ventilation ducting from the 232-Z Building to the 291-Z Building was filled with a controlled density fill (i.e., grout). The 232-Z incinerator building had been a concrete block structure with a slightly sloped roof. The building was divided into areas devoted to processing, storage, change rooms, chemical preparation, ventilation, and utility distribution. The building had two stories at the north end and a single story over the remaining portions.

Location: The building was located adjacent to the south side of 2736-ZB.

Related Sites/ Structures: Structures associated with the facility include internal glove boxes, incinerators, and leaching equipment. The building is related to other plutonium recovery and processing facilities at Z Plant.

Process Description: The 232-Z Facility was built to remove plutonium from contaminated solid wastes by incineration and leaching in preparation for plutonium recovery.

Waste Type: Chemicals

Waste Description: There is stabilized contamination on the building surfaces, including low levels of alpha contamination.

Code: 300-231

Classification: Accepted

Names: 300-231; Substation C3-S15; Vitrification Test Site Transformer Pad

Reclassification: Consolidated (8/15/2013)

Type: Electrical Substation

Start Date: 1/1/1983

Status: Inactive

End Date: 1/1/1999

Description: The site concerns have been addressed and the waste site reclassified to Closed Out in 1999 and changed to Consolidated in 2013. It was consolidated with the 300 VTS waste site. It was considered Final Closed Out in 2014. It was a transformer station connected to a 13.8 KVA overhead powerline. The transformers have been removed. The transformers were used to provide electricity for in-situ vitrification tests at the 300 Vitrification Test Site (300 VTS), a separate WIDS site.

The transformers were located on a concrete pad and enclosed by a chain link fence. The transformers were numbered as follows: transformer #C4804P, serial #81439, property #F176743; transformer #C4805P, serial #81441, property #176744; transformer #C4648P, serial #80097, property #176745. The transformers were single phase 200 KVA. The primary voltage for each of the transformers was 14400 and secondary voltage was 240/480. Each transformer weighed 544 kilograms (1200 pounds). Electric fluid capacity was 492.1 liters (130 gallons) and the fluid type was mineral oil.

Location: The transformer pad is located in the southeast corner of the 300 Vitrification Test Site, west of Route Four South, across from the 300 Area.

Release Description: The operating records for the transformers document releases of transformer oil to the exteriors of the units (see Site Comment). The records do not document any releases to the transformer pad or the surrounding soil.

Related Sites/ Structures: The transformer pad was related to the 300 Vitrification Test Site (300 VTS) and the associated Thermal Treatment and Test Facilities (TTTF).

Process Description: In-situ vitrification (ISV) was a thermal treatment process that converted contaminated soils and sludges into a glass and crystalline product. An electrical current was passed among an array of four electrodes imbedded in the contaminated soil or sludge, melting and glassifying it.

Waste Type: Transformer

Waste Description: The transformers have been removed (5/13/1999). The concrete pad and the surrounding soils are clean. The only remaining waste is the abandoned concrete pad and fence. Historical data showed that all three transformers were sampled for polychlorinated biphenyls (PCBs) on 8/18/86. Analysis on C4804P indicated 98 parts per million of PCB. Analysis on C4805P indicated 90 parts per million of PCB. Analysis on C4648P indicated 92 parts per million of PCB.

Closure Info: Final: As of 5/13/1999, the transformers had been disconnected and removed from the site. The enclosure associated with the transformers is empty, and the concrete pad is clean. Maintenance records indicate any leaks were cleaned up before they reached the pad or the soil. The reclassification is documented on form 99-038.

This Site Was Consolidated With:

Code: 300 VTS

Names: 300 VTS; In-Situ Vitrification (ISV) Test Site; 300 Area Vitrification Test Site

Code: 300-277

Classification: Accepted

Names: 300-277; 300 Area Queue Contamination

Reclassification: None

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Code: 300-279

Classification: Accepted

Names: 300-279; 3716 Automotive Repair Building Fuel Tanks

Reclassification: Final No Action (5/12/2014)

Type: Storage Tank

Start Date:

Status: Inactive

End Date:

Description: The waste site has been evaluated and determined to require No Action. In 2014, the site was reclassified to Final No Action. It consisted of the historical location of underground diesel and gasoline storage tanks that were located to the north of the original 313 Bldg. (M-2885 sheet 1 rev 0), and east of the original 3716 Automotive Repair Bldg. location. The northern expansion of the 313 Bldg. was over this area where the tanks were located.

Location: It is located north of Ginko Street, east of the 303K, 305, and 314 Buildings, and west of the 3712 and 3720 Buildings. The 313 Building is located at the north end of the main 300 Area (within the security fence). The 300-279 waste site is located at Washington State Plane coordinates N 116198.8, E 593873.4. The 313 Building footprint encompasses a large portion of the 300-279 waste site location.

300-279 was located within WIDS site UPR-300-38 boundary, which is contaminated soil beneath the 313 Building. The contamination resulted from multiple unplanned release events. With the exception of the fuel tanks, the soil contamination is beneath the southern half of the 313 Building. The fuel contamination, if any, would lie in the northern expansion on the eastern

side of the building. Remediation of the UPR-300-38 waste site was performed from January 10, 2010, through June 2, 2011.

Related Sites/ Structures: The site is associated with the 313 Building and UPR-300-38.

Process Description: Concurrently with the construction of the 313 Building in the 1940's, a fuel station built to the north of the 313 Building (M-2885 sheet 1 rev 0). The fuel station was used to dispense both gasoline and diesel fuels to power machinery and vehicles used for construction (19450108 98026_ [N1619631] and 19450108 P8027_ [N1619634]). The fuel pumps were on a concrete island and were associated with two underground tanks. This fuel station was used until 1947. Volume 22 of HAN-27990 page 27: states "Removed 1947, one gas pump now located at 301 Bldg., one underground tank located at 301 Bldg. Disposition of one gas pump and one underground tank not known." Based on this information, one pump and one tank were removed and were relocated to the 301 Building. It was not known if the second tank was removed or not, or if there were any spills or leaks at the site. This work was performed in 1947 prior to the 1950's, when the 313 Building was expanded in the northward direction over the site of the two tanks.

WIDS site UPR-300-38 is at the former site of the 313 building. The site 300-279 concerns soil contamination still under the building foundation. The 313 building was demolished in 2005. The foundation slab was left in-place with a layer of clean gravel placed over it (BHI-01781). Remediation of the UPR-300-38 waste site was performed from January 10, 2010, through June 2, 2011.

Closure Info: Interim (7/16/2012): Confirmatory samples were collected from two trenches. They were excavated across the location of the suspected fuel tanks on April 4, 2012. Four grab samples per trench were taken along the base of each trench at 3.3 meters (10 ft) below ground surface (bgs). These locations correspond to the areas beneath the suspected fuel tanks. Due to field conditions, the northern section of trench number 2 was moved slightly westward compared to the design in the confirmatory work instruction. This was performed in order to avoid a concrete wall with rebar, which posed a safety concern. No additional debris was observed during sampling, and no sign of soil staining was noted. No asbestos-containing material was identified during field activities and, therefore, asbestos analysis was not performed.

The evaluation of sampling results indicated that environmental contamination warranting remediation was not present at this waste site. Based on confirmatory sampling at the 300-279 waste site, remedial action was determined to be unnecessary, and the confirmatory sampling data have been used to support reclassification of this waste site to Interim No Action.

Final (5/12/2014): The 300-279, 3716 Automotive Repair Building Fuel Tanks waste site is part of the 300-FF-2 Operable Unit. This waste site consists of the historical location of underground diesel and gasoline storage tanks that were located to the north of the original 313 Building and east of the original 3716 Automotive Repair Building. Confirmatory sampling of the 300-279 waste site was performed on April 4, 2011.

The 300-279 waste site has been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the RDR/RAWP (DOE-RL 2014). Evaluation of previous confirmatory sampling results show that the concentrations of COC's meet the CUL's for direct exposure and groundwater protection and river protection and support a residential land use scenario. Institutional controls to prevent uncontrolled drilling or excavation into the deep zone are not required. In accordance with this evaluation, the confirmatory sampling results support a reclassification of the 300-279 waste site to Final No Action.

Code: 300-280

Classification: Accepted

Names: 300-280; Construction Debris Disposal Pit West of George Washington Way Extension **Reclassification** Final Closed Out (7/9/2015)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site was remediated and reclassified to Final Closed Out. It consisted of a construction debris disposal pit. It was a rectangular 13 meters by 38 meters (42 ft by 124 ft) pit, aligned northwest to southeast, with a 6 meters (20 ft) wide gravel road ramping into the northwest end of the pit (M-3904, sheet 16, rev 1).

Location: The disposal pit was located on the west side of the George Washington Extension about 55 meters (180 ft) south of the intersection with Cypress Street. It is immediately east of the 300-217 laydown yard.

Related Sites/ Structures: Construction debris was associated with the construction of the 309 Building.

Process Description: The disposal pit appears to have been used for construction debris during the construction of the 309 Facility in the late 1950's (photo 16998-3).

An interpreted area of buried debris is supported by all the geophysical data sets. The area correlates well with a construction pit shown on drawing. M-3904 Sht. 16 Rev 1. The trench strikes NW-SE and is about 18 meters wide and 35 meters long and is roughly centered at N115476/E594298. There is about 0.4 meters of overburden above the debris. Several utilities were detected and noted on the interpretation map. Some of the linears/utilities closely border the trench boundaries and should be more thoroughly defined before excavating in this area.

Closure Info: Final (7/9/2015): A trench was excavated at the 300-280 waste site as part of the confirmatory sampling effort in May 2012. Debris and potentially hazardous materials consistent with a construction debris disposal pit were observed. The materials included pipe segments, bricks, wire, dried paint, suspect asbestos, and oily soil. The confirmatory sampling efforts were suspended based on the observations in the field, and samples representative of the suspect hazardous material and underlying soil were collected to support the characterization of the site. Sample results exceeded direct exposure CULs for total petroleum hydrocarbons (TPH) and polycyclic aromatic hydrocarbons (PAH). Polychlorinated biphenyls (PCBs) analyses exceeded groundwater/river protection cleanup levels.

Remedial action at the 300-280 waste site began on February 2 and continued through February 19, 2015. The remediation extended to a maximum depth of 6 meters (19.7 ft) below ground surface resulting in 9,348 bank cubic meters (12,227 bank cubic yards) of contaminated soil and debris being removed and disposed at ERDF. The debris consisted of concrete, metal, wood, and other construction debris. No suspect asbestos containing material was observed during remediation.

Code: 300-281

Classification: Accepted

Names: 300-281; Septic Tank Near 325 Building

Reclassification Final No Action (5/12/2014)

Type: Septic Tank

Start Date:

Status: Inactive

End Date:

Description: The waste site has been evaluated and determined to require No Action. In 2014, the site was reclassified to Final No Action. It is the suspected site of a septic tank as shown on a drawing for the Material Transfer Station building (H-3-45154). A drawing note says "Remove existing septic tank". However, the entire drawing was placed on hold for future construction and it is

unclear if the septic tank was ever removed. The Material Transfer Station facility was never built.

Location: The septic is located about 72 meters (236 feet) north of the 3790 building between the north end of the parking lot and the security fence surrounding the 325 building.

Process Description: The source of sanitary waste going to the septic tank has not been determined. However, aerial photographs (16998-1 & 18601-3) taken during the construction of the 309 Facility show a temporary construction building located at the approximate location of the septic tank. This temporary building may have discharged sanitary water to the septic tank. The only drawing (H-3-45154) showing the tank has a sanitary sewer line running north about 8 meters where it tees and then runs east-west where the lines end at sewer clean-outs.

A geophysical investigation (GI 0596714) was performed in the area of the suspected septic tank. The results were inconclusive. A field walkdown identified a pipe extending 1 meter (3 feet) out of the ground as a suspected septic clean-out. The pipe was a capped 2 inch diameter steel pipe that was painted yellow. It may be a location marker (see logbook EL-1616-02 and photograph number DSC02267).

Closure Info: Interim (7/5/2012): The 300-281 waste site was originally suspected to have an underground septic tank located about 72 meters (236 ft) north of the 3790 Building between the north end of the parking lot and the security fence surrounding the 325 Building. The suspected septic tank is shown on drawing H-3-45154 with a notation stating "Remove existing septic tank". However, the entire drawing was placed on hold for future construction of the Material Transfer Station facility. The facility was never constructed. It was unclear if the septic tank ever existed or was removed. Other documentation showed the septic system was to be built as part of the 300 area security upgrade project (V-711). The only reason to have installed a septic tank was to get around the new security systems that were to be installed in this area. Drawing M-3904 sheet 4 and H-3-23705 sheets 2 and 3 indicate a gap in coverage of the sewer system in the location of the planned in this area. Other buildings in the 300 area that were constructed at the time of the V-711 project are hooked up to the SNS system.

A geophysical investigation and confirmatory sampling activities confirmed that there was no septic tank at this location. Two test pits were hand excavated to an approximate depth of 1 meter (3 ft). An intact septic pipeline system was found. However, no septic tank was found nor was there any evidence of one having been there in the past. No radiological or volatile organic constituents were detected with field instruments. No stained soils or anomalous materials were observed. Based on this information, it was concluded that the 300-281 waste site would be reclassification to No Action on form 2012-035.

Final (5/12/2014): A geophysical investigation and confirmatory sampling activities confirmed that there was no septic tank at this location. A test pit was hand excavated to an approximate depth of 1 meters (3 ft) below ground surface where an intact septic pipeline system was found. However, a septic tank was not found and there was no evidence that one had previously existed.

The 300-281 waste site has been evaluated in accordance with the Record of Decision for 300-FF-2 and 300-FF-5, and Record of Decision Amendment for 300-FF-1 (EPA 2013) and the Remedial Design Report/Remedial Action Work Plan for 300-FF-2 Soils (300 Area RDR/RAWP) (DOE-RL 2014). The test pit excavations during previous sampling showed an intact septic pipeline system with no indication that a septic tank had ever existed at this site. These findings support a residential land use scenario for the waste site. The 300-281 waste site did not extend into the deep zone; therefore, institutional controls to prevent uncontrolled drilling or excavation into the deep zone of the site are not required. In accordance with this evaluation, the previous sampling observations support a reclassification of the 300-281 waste site to Final No Action.

Code: 300-284 **Classification:** Accepted
Names: 300-284; Sand Blasting Area Near 3221 Building **Reclassification** Final Closed Out (12/16/2014)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The waste was remediated and reclassified to Final Closed Out. It was the historical location of the sand blasting area associated with the former 3221 building location. The 3221 Building was constructed in 1974 to support sandblasting operations in the 300 Area.

Location: The central point of the sand blasting site lies at approximately (E) 594109.22, (N) 116125.96, which is a fenced area on the south side of the 3221 building.

Process Description: The site and associated 3221 building was used for the sand blasting of various items preparatory to these items being painted (DOE/RL-2004-77 Rev.1, Draft A).

Garnet grit was commonly used in grit-blasting operations to clean rust, paint, or contamination from the surface of metal components in preparation for recoating or painting. The garnet material is not a hazardous substance, but constituents of paint or other contaminants from the blasted surfaces are likely to be contained in spent garnet material.

Closure Info: Final (12/16/2014): Remedial action activities at the 300-284 waste site were performed on August 17, 2012. The excavation reached to a maximum depth of approximately 0.9 meters (3.0 ft). Approximately 424 bank cubic meters (555 bank cubic yards) of soils mixed with garnet sand were removed from the waste site excavation and direct loaded for disposal at ERDF. No anomalous materials or stained soils were observed during remedial activities. There is no waste staging pile area footprint or overburden soil stockpile associated with the remediation of this waste site.

Following remediation of the 300-284 waste site, the 340 Complex, located to the south of the 300-284 waste site, was undergoing excavation expansion and construction of a new ramp. The construction of the 340 Complex ramp resulted in the temporary backfill of the 300-284 excavation with road base gravel. This delayed the verification sampling of 300-284. Verification sampling at 300-284 waste site was performed between June 25 and June 30, 2014. The road base gravel was removed to allow access to 300-284 for verification sampling. The road gravel material was distinctly different (i.e., size, nature, color) from the native soils occurring at the 300-284 waste site. Therefore, it was readily distinguishable from the native soils. Twelve samples were collected and analyzed.

Code: 300-283 **Classification:** Accepted
Names: 300-283; Contaminated Light Water Disposal Site #2; Potential Trench Location #2 **Reclassification** Final No Action (5/12/2014)
Type: Trench **Start Date:**
Status: Inactive **End Date:**

Description: The waste site has been evaluated and determined to require No Action. In 2014, the site was reclassified to Final No Action. It was an intentional release of contaminated water to soil in 1965. The area has been covered and used as an entry road and parking lot for 300 Area remediation activities.

Location: The exact location of the waste site is questionable. It is described as being located east of the 309 Building parking lot. The 300-283 potential site location is approximately 155 meters (508

ft) southeast of the 309 building, 157 meters (515 ft) south of the 324 building and 47 meters (154 ft) north of Cypress Street. An alternate location is described in sitecode 300-2. Drawing H-3-11002 gives the corner coordinates for the disposal area as a location 91 meters (300 ft) east of the original location described for 300-2.

Related Sites/ Structures: This site is associated with 300-2, another potential location of the liquid disposal trench. 300-2 was evaluated and reclassified to No action in 2013.

Process Description: On September 29, 1965, a major contamination event occurred at the 309 building, Plutonium Recycle Test Reactor (PRTR). A fuel element was heated until molten and a process tube burst. The event grossly contaminated the PRTR's heavy water moderator with fission products and with light water from the coolant. Most of the primary coolant and make-up coolant water was disposed via the 340 Building. Secondary coolant and other normally contamination-free streams were routed directly to the Columbia River. When contamination was detected in this stream, the water was pumped to the ground. About 189,250 liters (50,000 gallons) of liquid waste were disposed to the ground (WHC-MR-0388).

Subsequent investigation reported in the Final Investigative Report of Fuel Element Rupture Test Facility Incident, September 29, 1965 (BNW 1965) determined that contamination of the secondary coolant was caused by neutron activation of the secondary coolant water during the fuel element rupture. At no time did release of reactor material (transuranics or fission products) to the secondary coolant occur. The liquid disposed to the ground would have contained short-lived radionuclides of cerium, iodine, and noble gases and no transuranic material or fission products that would have decayed to be undetectable in the 46 years from 1965 to 2011.

Closure Info: Interim (7/16/2012): The Final Investigative Report of Fuel Element Rupture Test Facility Incident, September 29, 1965 (BNW 1965) determined that contamination of the secondary coolant was caused by neutron activation of the secondary coolant water during the fuel element rupture. At no time did release of reactor material (transuranics or fission products) to the secondary coolant occur. The liquid disposed to the ground would have contained short-lived radionuclides of cerium, iodine, and noble gases and no transuranic material or fission products that would have decayed to be undetectable in the 46 years from 1965 to 2011.

Confirmatory sampling for the 300-283 waste site was conducted on April 26, 2012. One test pit was excavated. One focused sample and duplicate was taken at the bottom of the test pit at approximately 3.5 meters (10.5 ft) below ground surface. No additional debris was observed during sampling and no sign of soil staining was noted. No asbestos-containing material was identified during field activities, and therefore asbestos analysis was not performed. Samples were collected to support a determination that residual contaminant concentrations at this site meet the cleanup criteria specified in the RDR/RAWP (DOE/RL 2009) and the 300-FF-2 ROD (EPA 2001). The confirmatory sampling results support a reclassification of the 300-283 waste site to Interim No Action.

Final (5/12/2014): The 300-283, Contaminated Light Water Disposal Site #2 waste site was a suspected liquid disposal area associated with the September 29, 1965, contamination event that occurred at the 309 Building, Plutonium Recycle Test Reactor (PRTR). Confirmatory samples were collected on April 26, 2012 at a depth of 3.5 meters (11.5 ft) below ground surface.

The 300-283 waste site has been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the 300 Area RDR/RAWP (DOE-RL 2014). Evaluation of previous sampling results show that the concentrations of COC's meet the CUL's for direct exposure and groundwater protection and river protection and support a residential land use scenario. Institutional controls to prevent uncontrolled drilling or excavation into the deep zone are not required. In accordance with this evaluation, the confirmatory sampling results support a reclassification of the 300-283 waste site to Final No Action.

Code: 300-286 **Classification:** Accepted
Names: 300-286; Three 300 Area Potentially Contaminated French Drain/Drywells **Reclassification:** Final Closed Out (5/12/2014)
Type: French Drain **Start Date:**
Status: Inactive **End Date:**

Description: This site has been evaluated and determined to require No Action. In 2014, the site was reclassified to Final Closed Out. It consists of three individual french drain and drywell locations that were identified during the orphan sites evaluation process. It includes the underlying soil, and the associated below grade piping components. Each of the facilities that the French drains and drywells are associated with, were identified and process or function of the facilities determined. They are near the 309 Building exhaust filter pit, 3790 Badge House, and 3701-N Guardhouse.

Drain number 1 (FD-1) (Orphan site feature 300-FF2-019) is a 61 cm (24 in) diameter drywell constructed in accordance with Hanford standard AC-4-30 (H-3-14950 & H-3-14947). The drain received liquids from two 0.3 meter x 0.3 meter x 0.3 meter (1 ft x 1 ft x 1 ft) sumps located in the 309 Building exhaust filter pit. A 2.5 cm (1 in) schedule 40 steel drain line from each sump joined a (2 in) schedule 40 steel line that drained to the French drain. There is a locked metal cover over the drywell.

Drain number 2 (FD-28) is a stormwater catch basin and 4-inch slotted drain pipe (corrugated polyethylene with a smooth interior). It is not visible in the field.

Drain number 3 (FD-33) is a french drain with a 15.2-cm (6-inch) pipe that empties into it. The pipe was traced 11 meters due west using geophysics. The traced end of the pipe is 3 meters (10 feet) east of FD-21 (NFE), which was associated with the 3701-N guardhouse. Letter: MSA-1400080 (1/27/2014) Contract Deliverable CD1033 Annual Class V Underground Injection Control (UIC) Wells Update for calendar year 2013 states the estimated backfill date of this drain is 4/1/2012.

Location: Drain number 1 is located about 3.6 meters (12 feet) east of the 309 Building exhaust filter pit.

Drain number 2 is located on the east side of the 3790 Badge House.

Drain number 3 is located about 11 meters east-northeast of the 3701-N Guardhouse.

Process Description: There is a slight potential for contamination being present in drain number 1, as the 309 Building exhaust filter pit is associated the 309 building exhaust stack.

Drain number 2 received stormwater on the east side of the 3790 Badgehuse.

The source for water to drain number 3 is unknown, but thought to be from the 3701-N Guardhouse.

Closure Info: Interim (7/16/2012): Confirmatory sampling for the 300-286 waste site was conducted on April 4, 2012. After the work instruction was issued, it was determined that Drain #1 would be removed during the 309 Building demolition. Therefore, confirmatory sampling at the Drain #1 location was not required.

The stormwater catch basin that comprises the Drain #2 location was adjacent to a light pole. A test pit excavation for sampling was not possible. Therefore, an evaluation of confirmatory sampling data for stormwater drains similar to Drain #2 (100-H-51:4 and 100-F-50) was conducted. Based on the confirmatory sample results from waste sites similar to the 300-286

Drain #2, the drain was not believed to pose a significant risk for direct exposure, groundwater protection, or river protection.

Confirmatory sampling was performed at Drain 3. The analytical results indicate that the residual concentrations of COPCs at this site meet the remedial action objectives for direct exposure, groundwater protection, and river protection. In accordance with this evaluation, the confirmatory sampling and modeling results support a reclassification of the 300-286 waste site to No Action.

Final (5/12/2014): The 300-286, Three 300 Area Potentially Contaminated French Drain/Drywells waste site included three individual french drain and drywell locations, the underlying soil, and the associated below-grade piping components. The french drain and drywell locations were located near the 309 Building exhaust filter pit, 3790 Badge House, and 3701-N Guardhouse. The confirmatory sampling instructions directed sampling at each of the three french drains. After the work instruction was issued, it was determined that Drain #1 (near the 309 Building) would be removed during the 309 Building demolition; therefore, confirmatory sampling at the Drain #1 location was not required.

The stormwater catch basin that comprises the Drain #2 location (near the 3790 Badge House) was adjacent to a light pole, and test pit excavation and sampling was not possible. Therefore, an evaluation of confirmatory sampling data for stormwater drains similar to Drain #2 was conducted. The evaluation concluded that the drain did not pose a significant risk for direct exposure, groundwater protection, or river protection. Confirmatory sampling at Drain #3 (near the 3701-N Guardhouse) was conducted on April 4, 2012. The test pit at Drain # 3 was sampled at a maximum depth of 0.6 meters (2 ft) below ground surface.

The 300-286 waste site has been evaluated in accordance with the 300 Area Final Action ROD (EPA 2013) and the RDR/RAWP (DOE-RL 2014). Evaluation of previous sampling results and evaluations of similar waste sites show that the concentrations of COC's meet the CUL's for direct exposure and groundwater protection and river protection and support an industrial land use scenario. Because the sample results do not meet the CULs for residential land use, the waste site requires institutional controls to maintain industrial land use. In accordance with this evaluation, the previous sampling results support a reclassification of the 300-286 waste site to Final Closed Out.

Code: 300-287	Classification: Accepted
Names: 300-287; Transite Debris west of Route 4 South	Reclassification: Final Closed Out (11/19/2014)
Type: Dumping Area	Start Date:
Status: Inactive	End Date:
Description:	The waste site consisted of broken corrugated transite in a pile measuring approximately 1.5 meters (5 ft) by 0.5 meters (1.6 ft). It was consistent with asbestos-containing material (ACM).
Location:	This feature is located approximately 28 meters west of Route 4 South at coordinates N116083 E593545.
Process Description:	This feature was discovered during the Orphan Site Evaluation field walkdowns of the 300-FF-2 area on June 24, 2009.
Closure Info:	Final (11/19/2014): Remediation of the material occurred on October 10, 2014. The four pipes were removed and disposed at ERDF. The only contaminant was asbestos-containing material (ACM). After removal, the area was visually inspected by a certified asbestos competent person. The results of the visual inspection demonstrated that no asbestos contaminants

remained at the site.

Code: 300-288 **Classification:** Accepted

Names: 300-288; Disposal Sites Within Gravel Pit 6 **Reclassification** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The site is comprised of solid waste deposited inside the large irregular shaped gravel pit (600-244). It is divided into two subsites; 300-288:1 Piles of Garnet Sand/Soil Mixture Within Gravel Pit 6 and 300-288:2 Undocumented disposal site within Gravel Pit 6. Subsite 1 was Reclassified to Final No Action in December 2014.

Location: This site is located west of 300 Area, on the west side of Highway Route 4S. Subsite 1 is located within 600-249 (debris and spoil piles in Gravel Pit 6). Subsite 2 is located within the 600-244 (Gravel Pit 6) expansion area.

Related Sites/ Structures: The site is associated with 600-244 (Gravel Pit 6) and 600-249 (Debris Within Gravel Pit 6).

Process Description: The borrow pits are used as a source of sand and gravel. The materials were excavated using heavy equipment and transported off site in dump trucks. At Hanford, it was common practice (prior to the environmental laws enacted in the 1970's) to use borrow pits for disposal of non-radioactive solid waste. The disposal activities were rarely documented. It appears from historical aerial photography that this area was being used as early as 1944.

This Site has the Following SubSites:

Code: 300-288:1

Names: 300-288:1; Piles of Garnet Sand/Soil Mixture Within Gravel Pit 6

Code: 300-288:2

Names: 300-288:2; Undocumented Disposal Site within Gravel Pit 6

Code: 300-288:1 **Classification:** Accepted

Names: 300-288:1; Piles of Garnet Sand/Soil Mixture Within Gravel Pit 6 **Reclassification** Final No Action (12/15/2014)

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The subsite has been evaluated and determined to require No Action. It consists of two piles of garnet sand within a 5 meters (16.4 ft) diameter area. The total volume is approximately 15 cubic meters (20 cubic yards). Each pile is estimated to contain 5% garnet sand and 95% soil.

Location: Gravel Pit 6 is located west of 300 Area, on the west side of Highway Route 4S. The garnet sand is located inside (Rejected) 600-249, Debris Within Gravel Pit 6 waste site boundary. Gravel Pit 6 is located west of the 300 Area.

Process Description: Garnet grit was commonly used in grit-blasting operations to clean rust, paint, or contamination from the surface of metal components. The garnet material is not a hazardous substance, but there is potential for contamination from the surface material that was removed by grit blasting.

Closure Info: Final (12/15/2015): The total volume of the two piles is approximately 15 cubic meters (20 cubic yards). Each pile is estimated to be 5% garnet sand and 95% soil. An in-process

composite sample (J1TWJ3) consisting of 30 aliquots of garnet sand material was collected on June 24, 2014. The sample was collected to support a determination that residual contaminant concentrations at this site meet the cleanup levels specified in the 300 Area Final ROD (EPA 2013).

The SubSite is Part Of:

Code: 300-288

Names: 300-288; Disposal Sites Within Gravel Pit 6

Code: 300-288:2

Classification: Accepted

Names: 300-288:2; Undocumented Disposal Site within Gravel Pit 6

Reclassification: None

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The subsite includes the debris that resembles raw stock and machined graphite found within the Gravel Pit 6 expansion area boundaries.

Location: Gravel Pit 6 is located west of 300 Area, on the west side of Highway Route 4S. Subsite 2 is located within the 600-244 (Gravel Pit 6) expansion area.

Process Description: The borrow pits are used as a source of sand and gravel. The materials were excavated using heavy equipment and transported off site in dump trucks. At Hanford, it was common practice (prior to the environmental laws enacted in the 1970's) to use borrow pits for disposal of non-radioactive solid waste. The disposal activities were rarely documented. It appears from historical aerial photography that this area was being used as early as 1944.

The SubSite is Part Of:

Code: 300-288

Names: 300-288; Disposal Sites Within Gravel Pit 6

Code: 300-289

Classification: Accepted

Names: 300-289; Stained Soil Area North of 300 Area

Reclassification: Final Closed Out (5/13/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The waste site was remediated in December 2014 and reclassified to Final Closed Out. The site consisted of bare ground, with crusting and two drum bung plugs. It was an area approximately 5 meters (16.4 ft) in diameter.

Location: The site was located 15 meters west of a maintained power line road, north of 300 Area.

Process Description: There is no process history associated with this waste site.

Closure Info: Final (5/13/2015): A walkdown of the 300-289 waste site was conducted on April 13, 2011, to assess existing conditions for confirmatory sampling activities. A ditch was observed in the southern portion of the site ending at the bare ground area. A geophysical survey was performed at the 300-289 waste site in October 2011 to support the confirmatory sampling activities. The results of the GPR survey indicated the presence of a small pocket of shallow anomalies in the vicinity of the surface stain. Remedial action was determined to be necessary because confirmatory sampling of the soil detected hexavalent chromium and polychlorinated

biphenyls at concentrations exceeding direct exposure cleanup levels.

Remediation of the 300-289 waste site was conducted December 8 through 11, 2014. The remediation extended to an approximate maximum depth of 5.5 meters (18 ft) below ground surface, resulting in approximately 1,728 bank cubic meters (2,260 bank cubic yards) of soil being removed for disposal at ERDF. All material was direct loaded from the excavation; therefore, no waste staging pile area was generated.

Code:	300-290	Classification:	Accepted
Names:	300-290; Radiological Debris Area East of Horn Rapids Disposal Landfill	Reclassification	Final No Action (1/23/2015)
Type:	Dumping Area	Start Date:	
Status:	Inactive	End Date:	
Description:	The waste site was evaluated and determined to require No Action. 300-290 had been a posted Radiological Materials Area (RMA) measuring approximately 64 square meters. The material in the posted area consisted of rusted metal automotive parts, scraps of crumpled sheet metal, electrical wire debris and engine gaskets. Some light ballasts were removed to a PCB storage area. The posting was later changed to Underground Radioactive Material (URMA). The radiological postings were removed in 2015.		
Location:	This site is located approximately 32 meters NNE of the NE boundary of WIDS site HRD (Horn Rapids Disposal) at coordinates E592787 N114636.		
Related Sites/ Structures:	WIDS sitecode HRD (Horn Rapids Disposal).		
Process Description:	The debris in this feature is consistent with the debris that was deposited in the Horn Rapids Landfill, which operated as an uncontrolled landfill from the late 1940's to the 1970's. The landfill is currently inactive, and was remediated in accordance with EPA/ROD/R10-93/063, Hanford 1100-Area (USDOE). The landfill has been taken off the National Priorities List, and it was capped and put under institutional controls (DOE/RL-2008-68).		
Closure Info:	Final (1/23/2015): The waste site consists of debris, mostly rusted metal automotive parts, scraps of crumpled sheet metal, electrical wire debris, engine gaskets and light ballasts. The ballasts were managed as PCB items and were moved to a storage location in the 400 Area. During a routine surveillance on May 22, 2014, radiological surveys and smears were taken of the waste site debris (automotive parts and sheet metal) and soils. No radiological activity above background or removable contamination above the instrument detection limit was observed as documented in Radiological Survey Record RSR-300PS-14-1680. An in-process composite soil sample was collected from across the waste site on September 25, 2014. Additionally, two test pits were hand excavated to a depth of 2 feet under the surface debris to determine if additional debris was present below the ground surface. No debris or stained soil was observed below the surface. No additional was found. Another site walkdown was conducted on December 2, 2014.		

Code:	300-291	Classification:	Accepted
Names:	300-291; Garnet Sand West of 350-A Paint Shop	Reclassification	Final No Action (12/15/2014)
Type:	Dumping Area	Start Date:	
Status:	Inactive	End Date:	
Description:	The waste site was evaluated and determined to require No Action. It consists of garnet sand on		

a gravel road bed.

Location: This feature was located 60 meters west of the 350A paint shop.

Related Sites/ Structures: This area likely supported the 350A paint shop.

Process Description: Garnet sand was commonly used in grit-blasting operations to clean rust, paint, or contamination from the surface of metal components. The garnet sand material is not a hazardous substance, but there is potential for contamination from the surface material that was removed by grit blasting. Based on the location of the garnet sand being in close proximity to the 350A Paint Shop, it is likely the garnet sand was used to sandblast painted surfaces.

Closure Info: Final (12/15/2015): The garnet sand is no longer visible along the gravel/dirt roadway due to the installation of the pipeline; however, a small amount is present on a berm located on the north side of the roadway. A discrete grab in-process sample (J1TWJ8) consisting of garnet sand material and soil was collected from the berm area on June 24, 2014. The sample was collected to support a determination that residual contaminant concentrations at this site meet the cleanup levels specified in the 300 Area Final ROD (EPA 2013).

Code: 300-292

Classification: Accepted

Names: 300-292; 315 Water Filter Plant Waste Pipeline Segments

Reclassification: Rejected (5/17/2012)

Type: Product Piping

Start Date:

Status: Inactive

End Date:

Description: This waste site has been evaluated and determined to be nonhazardous. It has been Reclassified to Rejected. The reclassification to Rejected is based on the evaluation and determination that coal ash and filter backwash waste solutions are nonhazardous waste and that the associated waste sites were previously designated as either No Action or Rejected.

This site includes ten (10) abandoned nonhazardous waste pipeline segments associated with the process sewers from the 315 Water Filter Plant (filter backwash) in the 300 Area. The site consists of abandoned pipeline segments and associated features (manholes, junction boxes, sumps, etc.) that transported filter backwash waste solutions from the 315 Water Filter Plant. These waste solutions were routed to Filter Backwash Ponds (e.g. 300 RFBP, 300 FBP:1, 300 FBP:2). The site includes pipeline segments identified during the 300-FF-1 Orphan Site Evaluation for disposition with the 300-FF-2 Operable Unit evaluations and additional undocumented pipeline segments, manholes, sumps and diversion boxes discovered during the 300-FF-2 Orphan Site Evaluation (OSE). The OSE reference number for these segments is 300FF2-266.

The original 315 Water Filter Plant process sewer ran east from the 315 Building process sewer sump (315-22) to an outfall into the Columbia River. In 1975, the 315 process sewer pipeline to the river outfall was isolated and sealed at a diversion box (315-23) installed to redirect the 315 Building process sewer flow north to discharge into on-site sedimentation ponds (see attached map and tables). The east branch of the 315 Water Filter Plant process sewer from the diversion box (315-23) was accepted as WIDS Waste Site 300-261; it was later closed out ("rejected") with Waste Site Reclassification Form 99-044.

The most recent waste site associated with these pipeline segments was the lined 300 FBP:2 Filter Backwash Pond (aka 315-C Sedimentation Pond) that was shutdown in 1998 (2000-116). During the last period of operation, any filter backwash waste solutions were to be settled in the pond and the pond overflow was to drain into a lift station for discharge to the 300 Area

Process Sewer (300-15).

Location: These 315 Water Filter Plant filter backwash waste lines are located inside the 300 Area, northeast of the 324 building.

Related Sites/ Structures: The pipelines included in this site are associated with the 315 Water Filter Plant, and the aqueous waste disposal facilities for these facilities including the 315-C Sedimentation Pond (aka 300 FBP:2), the 315-C Lift Station, the 315-D Lift Station, and associated manholes, sumps, valve pits, and diversion boxes. The site is associated with the 300 Area process sewer (300-15). The 315 Water Filter Plant backwash sewer pipelines were transitioned for disposition with the 300-FF-2 Operable Unit Orphan Site Evaluation (WCH CCN 120421).

Process Description: The process waste solutions for this site included nonhazardous solids suspended in water filter backwash waste solutions from the 315 Water Filter Plant that were routed north to the 315-C Sedimentation Pond (300 FBP:2) where the filter backwash sediments settled.

Coal ash and filter backwash waste solutions were determined to be nonhazardous materials and the associated waste sites (pipelines, ditches, and ponds) were designated as either "No Action" or "Rejected" waste sites (DOE/RL-1994-49, DOE/RL-2004-74). These designations were confirmed during the Orphan Sites Evaluation for the 300-FF-1 Operable Unit completed in 2005 (120421).

Plans for the disposal of the settled filter backwash waste solutions in 300 FBP:2 progressed from 1990 to 1997 that involved: (1) a replacement river outfall pipeline (Segment 7) that was installed (1993) but not used, abandoned, and partially removed (1996), (2) a recycle line to the 315 Water Filter Plant for a 10% recycle process that was installed (1996) but not used and abandoned in place, and (3) pumps and piping installed in 1997 to transfer the waste water to the 300 Area process sewer (300-15) at a manhole (PS-47) near the 340 Facility west of the 315-C Sedimentation Pond. The latter included the reuse of some of the 300-295 pipeline segments.

Closure Info: Interim (5/17/2012): None - The reclassification to Rejected is based on the evaluation and determination that coal ash and filter backwash waste solutions are nonhazardous waste and that the associated waste sites were previously designated as either No Action or Rejected.

Code: 300-293

Classification: Accepted

Names: 300-293; 300 Area Miscellaneous Pipelines

Reclassification: Final No Action (5/12/2014)

Type: Product Piping

Start Date:

Status: Inactive

End Date:

Description: The waste site has been evaluated and reclassified to No Action. In 2014, both subsites were reclassified to Final No Action so the parent site is also Final No Action. The site consists of miscellaneous piping in the 300 Area. The site was divided into two subsites: 300-293:1, 300 Area Miscellaneous Pipelines - less than 2.5 ft bgs and 300-293:2, 300 Area Miscellaneous Pipelines - greater than or equal to 2.5 ft bgs. Both subsites were reclassified to No Action, so the parent site is also considered No Action.

Location: The miscellaneous pipelines are located throughout the 300-FF-2 operable unit. The individual underground lines are mapped in the WCH Geographic Information System (GIS) database.

Closure Info: Final (5/12/2014): The 300-293:1, 300 Area Miscellaneous Pipelines Less Than 2.5 feet bgs waste subsite consists of 107 underground utility lines which are known to not be associated with hazardous waste because of their shallow depth. Pipelines with a depth of less than 0.76 meters (2.5 ft) bgs were determined not to have been associated with liquid waste processes or facilities that may have contained hazardous materials.

The 300-293:2, 300 Area Miscellaneous Pipelines Greater Than or Equal to 2.5 feet bgs waste site, located in the 300-FF-2 Operable Unit, consisted of 171 segments of underground utility lines in the 300 Area. These lines were identified on duct bank plans used for electrical upgrades in the early 1990s, unidentified underground utilities from historic drawings, or objects found on subsurface scans. Some of these segments were previously removed by building demolitions or other waste site excavations. Those segments not previously known to have been removed were the target of previous investigation and sampling.

The 300-293:1 and 300-293:2 waste subsites have been evaluated in accordance with the Record of Decision for 300-FF-2 and 300-FF-5, and Record of Decision Amendment for 300-FF-1 (EPA 2013) and the Remedial Design Report/Remedial Action Work Plan for 300-FF-2 Soils (DOE-RL 2014). A review of the available information associated with the 300-293:1 subsite indicates that the pipelines would have contained telecommunications, electrical ductwork, and compress gas lines. Because all of the lines that are less than 0.76 meters (2.5 ft) in depth, process knowledge indicates that the lines would not have contained liquid wastes or hazardous materials. These findings support a residential land use scenario for the waste site. The 300-293:1 nor 300-293:2 extended into the deep zone. Therefore, institutional controls to prevent uncontrolled drilling or excavation into the deep zone are not required. In accordance with this evaluation, the results support a reclassification of the 300-293:1 and 300-293:2 subsites to Final No Action.

This Site has the Following SubSites:

Code: 300-293:1

Names: 300-293:1; 300 Area Miscellaneous Pipelines - Less Than 2.5 Feet Below Ground Surface

Code: 300-293:2

Names: 300-293:2; 300 Area Miscellaneous Pipelines - Greater Than or Equal to 2.5 Feet Below Ground Surface

Code: 300-293:1

Classification: Accepted

Names: 300-293:1; 300 Area Miscellaneous Pipelines - Less Than 2.5 Feet Below Ground Surface

Reclassification: Final No Action (5/12/2014)

Type: Product Piping

Start Date:

Status: Inactive

End Date:

Description: The subsite was evaluated and determined to require No Action. In 2014, the site was reclassified to Final No Action. It consists of 107 underground utility lines (UGL) in the 300 Area that have been identified as being between 1 and 2.5 feet below the ground surface (bgs). Table 1 of the Waste Site Reclassification form lists each of the segments.

Location: The miscellaneous pipelines are located throughout the 300-FF-2 operable unit. The individual UGLs are mapped in the WCH Geographic Information System (GIS) database. The subsite consists of 107 underground utility lines which are known to not be associated with hazardous waste because of their shallow depth. Pipelines with a depth of less than 0.762 m (2.5 ft) bgs are determined not to have been associated with liquid waste processes or facilities that may have contained hazardous materials.

Process Description: The underground lines in this subsite are expected to associated with telecommunications, electrical ductwork, and compressed gas.

Closure Info: Interim: No remediation was performed. The subsite was reclassified based on process knowledge.

Final (5/12/2014): The 300-293:1, 300 Area Miscellaneous Pipelines Less Than 2.5 feet bgs

waste subsite consists of 107 underground utility lines which are known to not be associated with hazardous waste because of their shallow depth. Pipelines with a depth of less than 0.76 meters (2.5 ft) bgs were determined not to have been associated with liquid waste processes or facilities that may have contained hazardous materials.

The 300-293:2, 300 Area Miscellaneous Pipelines Greater Than or Equal to 2.5 feet bgs waste site, located in the 300-FF-2 Operable Unit, consisted of 171 segments of underground utility lines in the 300 Area. These lines were identified on duct bank plans used for electrical upgrades in the early 1990s, unidentified underground utilities from historic drawings, or objects found on subsurface scans. Some of these segments were previously removed by building demolitions or other waste site excavations. Those segments not previously known to have been removed were the target of previous investigation and sampling.

The 300-293:1 and 300-293:2 waste subsites have been evaluated in accordance with the Record of Decision for 300-FF-2 and 300-FF-5, and Record of Decision Amendment for 300-FF-1 (EPA 2013) and the Remedial Design Report/Remedial Action Work Plan for 300-FF-2 Soils (DOE-RL 2014). A review of the available information associated with the 300-293:1 subsite indicates that the pipelines would have contained telecommunications, electrical ductwork, and compress gas lines. Because all of the lines that are less than 0.76 meters (2.5 ft) in depth, process knowledge indicates that the lines would not have contained liquid wastes or hazardous materials. These findings support a residential land use scenario for the waste site. The 300-293:1 nor 300-293:2 extended into the deep zone. Therefore, institutional controls to prevent uncontrolled drilling or excavation into the deep zone are not required. In accordance with this evaluation, the results support a reclassification of the 300-293:1 and 300-293:2 subsites to Final No Action.

The SubSite is Part Of:

Code: 300-293

Names: 300-293; 300 Area Miscellaneous Pipelines

Code: 300-293:2

Classification: Accepted

Names: 300-293:2; 300 Area Miscellaneous Pipelines - Greater Than or Equal to 2.5 Feet Below Ground Surface

Reclassification: Final No Action (5/12/2014)

Type: Product Piping

Start Date:

Status: Inactive

End Date:

Description: The subsite has been evaluated and determined to require No Action. In 2014, the site was reclassified to Final No Action. It consists of the underground utility lines (UGL) in the 300 Area that have been identified as being greater than 2.5 feet below the ground surface (bgs). The UGLs without an approximate depth were also assigned to this subsite.

Location: The miscellaneous pipelines are located throughout the 300-FF-2 operable unit. The individual UGLs are mapped in the WCH Geographic Information System (GIS) database and provided to the MSA Central Mapping group.

Closure Info: Interim (7/5/2012): Some of the utility line segments were previously removed by building demolitions or other waste site excavations. Segments that were not previously known to be removed or investigated at the time of the confirmatory work instruction document approval were the target of confirmatory investigation. Confirmatory investigation was performed with field instrumentation. Screening results and observations indicate that the residual concentrations of COPCs at this site meet the RAGs for direct exposure, groundwater protection, and river protection. Only nine utility segments remained for evaluation.

The use of a vacuum truck excavator (Guzzler) was necessary to mitigate potential for affecting adjacent utilities at the 300-293:2 sampling locations. The vacuum truck contains all soil removed from a location and allows excavation to occur with less impact to adjacent utilities. Because this vacuum truck is regulated under for transport of radiological material, the soil from the confirmatory test pit and trench locations was staged in radiological buffer areas (RBAs) adjacent to each test pit/trench location. The soil was sent to the Environmental Restoration Disposal Facility (ERDF). Clean backfill was used to fill the test pits/trenches.

Test Trench 1 was excavated using the vacuum-truck Guzzler and hand digging on April 11 and 12, 2012. The three target utility segments were expected to be at a maximum of 1.5 meters (5 ft) below ground surface (bgs). The trench was excavated deeper than the 1.5 meters (5 ft) requirement, but the target segments were not found. One informational soil sample was collected from Test Trench 1. The utility segments targeted by Test Trench 2 were electrical duct banking and will be investigated during remediation of the waste sites adjacent to the 384 Building.

Test Pit 5 was excavated using the Guzzler on April 18, 2012. The excavation extended to the target depth of approximately 1.4 meters (4.5 ft) bgs, but no target utility segment was found. Test Pit 8 was excavated by hand digging (due to shallow depth) on April 18, 2012. The test pit was extended to 0.9 meters (3 ft) bgs in search of the target segment. There were small bits of single-strand copper wire, but no other indication of debris or the target segment. Radiological screening and organic vapor monitoring indicated background levels, therefore, no samples were collected. Test Pit 10 was excavated using the Guzzler on April 16, 2012. The test pit location was excavated to 1.2 meters (4 ft) bgs. The target segments were not found, so the test pit was expanded to the north. An adjacent north-south trending UGL was identified but it was not the target segment. Radiological screening and organic vapor monitoring indicated background levels, therefore, no samples were collected. Test Pit 21 was excavated using the Guzzler on April 16 and 17, 2012. The test pit uncovered a 7.6 cm (3-in.) rusty pipe at approximately 0.9 meters (3 ft) bgs. While the angle of the pipe matched that of the target segment, the diameter did not, and no additional investigation of this pipe occurred. Radiological screening and organic vapor monitoring indicated background levels, therefore, no samples were collected. Test Pit 21 was excavated using the Guzzler on April 16 and 17, 2012. The test pit uncovered a 7.6 cm (3-in.) rusty pipe at approximately 0.9 meters (3 ft) bgs. While the angle of the pipe matched that of the target segment, the diameter did not, and no additional investigation of this pipe occurred. Radiological screening and organic vapor monitoring indicated background levels, therefore, no samples were collected. Test Pit 24 was excavated using the Guzzler on April 19, 2012. Hard packed gravels and very minimal fines were found starting at approximately 1.1 meter (3.5 ft) bgs, resembling coarse fill. There was no indication of the target segment. Radiological screening and organic vapor monitoring indicated background levels, therefore, no samples were collected. Test Pit 38 was excavated using the Guzzler on April 19, 2012. Concrete was found at approximately 0.8 m (2.5 ft) bgs and was determined to be encasement over a duct bank. Radiological screening and organic vapor monitoring indicated background levels, therefore, no samples were collected.

Test Pit 28 contained live underground copper cable and/or polyline conduit within 1.5 meters (5 ft) of the utility segment. Therefore, the Test Pit 28 excavation in this location was deemed to be unsafe and was not dug. Test Pit 35 addressed a utility segment that had live underground power running perpendicular to the segment. This investigation in this location was also considered unsafe and was not dug.

The 300-293:2 subsite has been evaluated in accordance with the 300-FF-2 ROD (EPA 2001) and the RDR/RAWP (DOE-RL 2009). Confirmatory investigation was performed, and the field instrumentation screening results and observations indicate that the residual concentrations of COPCs at this site meet the RAGs for direct exposure, groundwater protection, and river

protection. In accordance with this evaluation, the confirmatory investigation results support a reclassification of the 300-293:2 subsite to No Action.

Final (5/12/2014): The 300-293:1, 300 Area Miscellaneous Pipelines Less Than 2.5 feet bgs waste subsite consists of 107 underground utility lines which are known to not be associated with hazardous waste because of their shallow depth. Pipelines with a depth of less than 0.76 meters (2.5 ft) bgs were determined not to have been associated with liquid waste processes or facilities that may have contained hazardous materials.

The 300-293:2, 300 Area Miscellaneous Pipelines Greater Than or Equal to 2.5 feet bgs waste site, located in the 300-FF-2 Operable Unit, consisted of 171 segments of underground utility lines in the 300 Area. These lines were identified on duct bank plans used for electrical upgrades in the early 1990s, unidentified underground utilities from historic drawings, or objects found on subsurface scans. Some of these segments were previously removed by building demolitions or other waste site excavations. Those segments not previously known to have been removed were the target of previous investigation and sampling.

The 300-293:1 and 300-293:2 waste subsites have been evaluated in accordance with the Record of Decision for 300-FF-2 and 300-FF-5, and Record of Decision Amendment for 300-FF-1 (EPA 2013) and the Remedial Design Report/Remedial Action Work Plan for 300-FF-2 Soils (DOE-RL 2014). A review of the available information associated with the 300-293:1 subsite indicates that the pipelines would have contained telecommunications, electrical ductwork, and compress gas lines. Because all of the lines that are less than 0.76 meters (2.5 ft) in depth, process knowledge indicates that the lines would not have contained liquid wastes or hazardous materials. These findings support a residential land use scenario for the waste site. The 300-293:1 nor 300-293:2 extended into the deep zone. Therefore, institutional controls to prevent uncontrolled drilling or excavation into the deep zone are not required. In accordance with this evaluation, the results support a reclassification of the 300-293:1 and 300-293:2 subsites to Final No Action.

The SubSite is Part Of:

Code: 300-293

Names: 300-293; 300 Area Miscellaneous Pipelines

Code: 300-294

Classification: Accepted

Names: 300-294; Garnet Sand East of 350 Building

Reclassification: Final No Action (1/6/2015)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The waste site was evaluated and determined to require No Action. This feature consists of garnet sand on a gravel road bed and adjacent field. The area measured approximately 60 by 24 meters (197 by 79 ft).

Location: The waste site is located approximately 5 meters east of the demolished 350 building.

Related Sites/Structures: The 350 Complex served as the central craft shop for the 300 area, with offices for supervisory and support personnel. The main 350 building contained shop areas for plastics, carpentry, electrical/instrument, machine, welding, grinding, and pipefitting/millwright work. As of 1984, approximately 70 personnel worked either in or out of the facility providing service and craft functions. The 350-A building provided space for spray-painting and sandblasting. The 350-B building was used to store miscellaneous equipment and supplies. The 350-C building functioned as a storage building for lumber used by the various shops. The 350-D building served as a storage location for hazardous chemicals, primarily oil (350, RCC SIS Report).

Process Description: Garnet sand was commonly used in grit-blasting operations to clean rust, paint, or contamination from the surface of metal components. The garnet sand material is not a hazardous substance, but there is potential for contamination from the surface material that was removed by grit blasting. Based on the location of the garnet sand being in close proximity to the 350-A Building, it is likely the garnet sand was used to sandblast painted surfaces.

Closure Info: Final (1/6/2015): No remediation was required.

Code: 300-295	Classification: Accepted
Names: 300-295; 384 Powerhouse Coal Ash Waste Pipeline Segments	Reclassification: Rejected (5/17/2012)
Type: Product Piping	Start Date:
Status: Inactive	End Date:

Description: This waste site has been evaluated and determined to be nonhazardous. It has been Reclassified to Rejected. The reclassification to Rejected is based on the evaluation and determination that coal ash solutions are nonhazardous waste and that the associated waste sites were previously designated as either No Action or Rejected.

This site includes four (4) abandoned nonhazardous waste pipeline segments and associated features (diversion valve box, manholes, etc.) that serviced the 384 Power House coal ash waste disposal by sluicing to the 300 Ash Pits and/or to the 315-C Sedimentation Pond. The site includes pipeline segments identified during the 300-FF-1 Orphan Site Evaluation for disposition with the 300-FF-2 Operable Unit evaluations and additional undocumented pipeline segments discovered during the 300-FF-2 Orphan Site Evaluation (OSE).

The coal ash waste site (300 Ash Pit) associated with these pipeline segments was reclassified to a status of "No Action" based on the past practice knowledge (DOE/RL-94-49) that the waste streams were nonhazardous and based on post-remediation characterization results for the 300-FF-1 Operable Unit waste sites (CVP 2003-02, DOE/RL-2004-74).

The most recent waste site associated with these pipeline segments was the lined 300 FBP:2 Filter Backwash Pond (aka 315-C Sedimentation Pond) that was shutdown in 1998. No coal ash slurries were routed to the 315 C Filter Backwash Sedimentation Pond (300 FBP:2) via Segment 14, the most recent coal ash sluicing pipeline (see Site Comments). This site is listed as 300FF2-269 in the Orphan Sites Evaluation Report (OSR-2010-0002).

Location: The 384 Power House coal ash waste lines within the 300 Area were mapped in the WCH Geographic Information System (GIS) database.

Related Sites/Structures: The pipelines were identified in the WIDS as part of the 300 Area Process Sewer waste site, 300-15. They were associated with the 384 Power House, the 300 Ash Pits, and the 315 Sedimentation Pond; these pipelines were not connected to the 300-15 waste site piping.

Process Description: Water was used to slurry coal ash from the 384 Power House coal ash (aka fly ash) filters to the 300 Ash Pits via a 10 cm (8 in) diameter pipeline to one of the two 300 Ash Pits. The initial coal ash sluicing pipeline (Segment 10) discharged into an open ditch (Segment 11) that drained into the 300 Ash Pits. The subsequent replacement coal ash pipelines (Segments 12 and 13) discharged alternately into one of the two 300 Ash Pits. The 300 Ash Pits were used alternately to allow the water to drain and the accumulations of coal ash to dry before being excavated and disposed as a solid waste. The coal ash slurries were routed to the 300 Ash Pits until about 1995. In 1995, the 384 coal ash sluicing pipeline was extended (segment 14 part of WIDS site 300-292) to the 315-C Sedimentation Pond.

(300 FBP:2) to support plans to discontinue use of the 300 Ash Pits (H-3-49874). However, before the extended coal ash sluicing line (H-3-49874) was put into service, the coal-fired boilers at the 384 Power House were shut down to reduce stack emissions. No coal ash slurries were routed to the 315-C Filter Backwash Sedimentation Pond (300 FBP:2). However, while Segment 14 was not used for coal ash sluicing, it was used to transfer filter backwash waste solution from the 315-C Sedimentation Pond to the 300 Area Process Sewer (see 315 Miscellaneous Waste Pipelines, 300-292).

Coal ash was determined to be a nonhazardous material and the associated waste sites (pipelines and ditch) were designated as "No Action" waste sites (DOE/RL-1994-49, DOE/RL-2004-74). This designation was confirmed during the Orphan Sites Evaluation for the 300-FF-1 Operable Unit completed in 2005 (120421).

Waste Type: Process Effluent

Waste Description: Coal ash waste solutions were determined to be nonhazardous materials and the associated waste sites (pipelines and ditch) were designated as "No Action" waste sites (DOE/RL-94-49, DOE/RL-2004-74). These designations were confirmed during the Orphan Sites Evaluation for the 300-FF-1 Operable Unit completed in 2005 (120421).

Closure Info: Interim (5/17/2012): None - The reclassification to Rejected is based on the evaluation and determination that coal ash solutions are nonhazardous waste and that the associated waste sites were previously designated as either No Action or Rejected.

Code: 300-296

Classification: Accepted

Names: 300-296; Soil Contamination Under the 324 Building B-Cell

Reclassification: None

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The site consists of high dose rate contaminated soil beneath the B-Cell of the 324 Building. The lateral and vertical extent of contamination is unknown. The B-Cell was 7.6 meters (25 ft) x 6.7 meters (22 ft) x 9.3 meters (30.5 ft) high. The floor and walls (up to 8.2 meters [27 ft] high) were lined with stainless steel (H-3-20195, H-3-20213, H-3-20214 and H-3-20273). The floor sloped to a trench that ran the length of the east side of the cell. The trench emptied into a sump located in the northeast corner of B-Cell (H-3-20195).

Location: The site is located beneath the B-Cell in the north central portion of the 324 Building.

Release Description: On 11/16/10, a cone penetrometer (an enclosed pipe pushed into the soil by a hydraulic ram) was used to identify the presence of radioactive material in the soil approximately 3.5 feet beneath the 324 Building near the B-cell. A maximum radiation readings of 6,700 R/hr. was identified. The 324 Building is a Nuclear Category 2 facility, currently undergoing deactivation and decommissioning. The 324 Building was constructed in the 1960s to support materials and chemical process research and development activities, and ceased research operations in 1996. The primary operational system remaining in the building is ventilation. In preparation for removal of B-cell, historical research and on-site investigation identified evidence of a potentially breached liner in the sump floor. A leak may have occurred at some point in the operational past of the cell. The 300 Area is posted as an Underground Radioactive Material (URM) Area. This event is being reported as a Management Concern due to the unexpected very high levels of radiation.

Related Sites/Structures: The site is associated with the Radiochemical Engineering Cells (REC) area located in the north portion of the 324 Building.

Process Description: The 324 Building was constructed between 1964 and 1966 to demonstrate pilot scale processes for converting high level solvent extraction separations plant wastes to solids (HW-74703). The building was divided into five functional areas (BNWL-CC-2028): Radiochemical Engineering Cells (REC), Shielded Materials Facility, Sodium Studies Facility, Engineering Development Laboratory and the Engineering Development Laboratory.

The 300-296 waste site is related to the REC functional area. The REC area is located in the north portion of the 324 Building and consisted of four hot-cells (A, B, C, and D) located around a central airlock. The cells and airlock were joined forming a "T"-shaped structure. The airlock was used primarily as a transition zone for maintenance, decontamination, and transfer of material and equipment into and out of adjoining hot cells (PNL-10890).

The REC area was used for process and equipment development studies using materials with mega curie radioactive levels. All work was accomplished with remote manipulations from the service gallery (BNWL-CC-2028). Major research and development programs undertaken in the REC have included the Waste Solidification Engineering Prototypes (WSEP) Program, the Fabrication of Cesium and Strontium Heat and Radiation Sources Program (Federal Republic of Germany [FRG]), the Nuclear Waste Vitrification Program (NWVP), the Zeolite Vitrification Demonstration Program (ZVDP), and the Nuclear Waste Treatment Program's (NWTP) Pilot Scale Radioactive Liquid-Fed Ceramic Melter (RLFCM) Testing Task (PNL-10890). The REC operations were concluded in 1996.

Waste Type: Soil

Waste Description: The soil is contaminated with radionuclides which are presumed to have originated from a release of concentrated strontium and cesium solution in about 1986. COPCs Cs-137 and Sr-90.

Code: 400-36	Classification: Accepted
Names: 400-36; 4843 Building Temporary Transfer Station; 4843 Waste Inspection Facility; Sanitary Waste Check Station	Reclassification: Rejected (8/15/2013)
Type: Storage	Start Date: 1/1/1998
Status: Inactive	End Date: 1/1/2002

Description: In 2013, the reclassification was changed to Rejected. When the 4843 building TSD was Closed Out in 1997, WIDS site code 400-36 was created, at the request of EPA, to track the building's use as a waste transfer station. Building 4843 was reassigned from Fast Flux Test Facility (FFTF) Project to DynCorp Tri-Cities Services, Inc. (DYN), Transportation Operations for use as a temporary transfer station. Upon completion of Dyncorp's contract in October of 2001, the transfer station was operated by Fluor Hanford, Inc., Hanford Site Operations. The transfer station operations have ceased. The last load of garbage delivered to the building was on July 31, 2002. Subsequent to cessation of operations, the floor area was surveyed. Direct and removable contamination surveys verified no source term material is present above background levels. The Washington Department of Health approved closure of the facility as an emission unit on October 15, 2002.

Location: The 4843 Building is located in the northwest corner of the 400 Area. A large laydown area is located adjacent to and west of the structure.

Related Sites/Structures: This building was previously known in WIDS as sitecode 4843; 4843 Building, 4843 Alkali Metal Storage Facility, a RCRA Treatment, Storage, and Disposal Facility. When this site was Closed Out under RCRA in 1997, WIDS site code 400-36 was created at the request of EPA to track the building's use as a waste transfer station.

Process Description: The building was used as a transfer station to check Hanford garbage (sanitary waste) for radiological or hazardous contaminants prior to transporting the garbage to the Richland Landfill for final disposal.

Waste Type: Misc. Trash and Debris

Waste Description: The building was used as a transfer station to check Hanford garbage (sanitary waste) for radiological or hazardous contaminants prior to transporting the garbage to the Richland Landfill for final disposal.

Closure Info: Final: The transfer station operations have ceased. The last load of garbage delivered to the building was on July 31, 2002. Subsequent to cessation of operations, the floor area was surveyed. Direct and removable contamination surveys verified no source term material is present above background levels.

The reclassification to No Action is documented on form 2004-102.

The reclassification to Rejected is documented on form 2013-107.

Code: 400-41 **Classification:** Accepted

Names: 400-41; 4723 Flammable Liquid Storage Building Soil Stains; 400 Area Flammable Liquid Storage Area Soil Stains **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The 4723 Building has been demolished. Asphalt currently covers the area where the spills occurred. In April 2010, no visual evidence of the 4723 building or the storage areas could be found.

Location: The soil stains are located between the FMEF perimeter fence and the FFTF exclusion area fence.

Process Description: In 1979 and 1980, the 4723 building stored flammable liquids. Historical photographs show a bermed area outside the building and many containers being stored outside the building. The 4843 Alkali Metal Storage Facility was built and actively began to store dangerous and mixed alkali metal waste in 1986. This building replaced the 4723 building.

Code: 400-42 **Classification:** Accepted

Names: 400-42; Demolished 4722-A Building Slab; Legacy Asbestos Site **Reclassification:** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The waste site is the concrete slab remaining after the demolition of the 4722-A building. There is visible evidence of scattered Cement Asbestos Board (CAB) on the surface of the concrete slab and in the gravel surrounding the slab. It is currently surrounded with T Posts and red boundary tape. It is posted with Danger - Asbestos, Authorized Personnel Only signs.

Location: The 4722-A Building was located west of the 4760 building. It is approximately 195 meters (640 ft) southwest of the 405 Reactor Containment Building.

Related Sites/ Structures: The 4722-A building was associated with fuel tank 400-38.

Process Description: The 4722-A Building was used to provide space for fabricating and assembling piping and mechanical parts in support of construction at the FFTF site through 1984. It contained space for pipe fabrication and modification, instrument fabrication, storage, and offices.

Code: 600-58 **Classification:** Accepted

Names: 600-58; BPA SWMU #13; H.J. Ashe Substation **Reclassification:** None
Oil/Water Separator & Drywells

Type: French Drain **Start Date:** 1/1/1988

Status: Inactive **End Date:**

Description: The oil/water separator is located south of the fuel island and south of the maintenance headquarters building. The oil/water separator receives drainage from eight floor drains in the maintenance headquarters building shop and two drains located on either side of the fuel island. The oil/water separator is designed to remove petroleum, oil, and lubricants from incoming water. It has a 454 liter (120 gallon) capacity. Drainage from the separator as well as drainage from two catch basins south of the maintenance headquarters building, flow into the dry well south of the maintenance building. The oil-water separator is precast concrete with a bottom elevation of about 4.6 meters (15 feet) below the surface. A site visit on November 20, 1998 found the oil-water separator to be active. It contained water with a small amount of oil sheen floating on the surface. In 2012, the three drywells had been removed and covered with asphalt.

Location: The Ashe Substation is located 0.5 miles northwest of and adjacent to the Energy Northwest property (formerly known as the Washington Public Power Supply System).

Related Sites/ Structures: The site is associated with the H.J. Ashe Substation (Sitecode 600-60).

Process Description: This substation is part of the Bonneville Power Administration main transmission grid, that conducts electrical power from the Columbia and Snake Rivers dams to five states (Washington, Oregon, Idaho, western Montana, and northern California). The BPA transmission grid is divided into four subareas. The substations on the Hanford Site are within the Snake River subarea. The substations use petroleum oil, primarily mineral oil, as insulation in electrical equipment. This includes transformers, coupling and potential devices, capacitors, circuit breakers, reclosers, voltage regulators, switches, and cable. Insulating oil is a highly refined, 10-weight petroleum oil with approximately 0.1 percent 2,6-di-tertbutyl-paracresol (an antioxidant known as BHT that is also used as a food additive) and varying amounts of polychlorinated biphenyls (PCBs) to increase dielectric strength. All of the substations have above ground tanks of mineral oil, that is used as make-up oil for equipment maintenance of electrical equipment. Solvents are used for cleaning and degreasing operations. Once maintenance is completed, rags soaked in solvent and all personal protective clothing are to be placed in drums for transport to the generator storage area at the H. J. Ashe Substation. All equipment filled with mineral oil is regularly analyzed for PCB concentration. All untested and unmarked equipment is assumed to be PCB contaminated. Electrical equipment fluid is assumed to be PCB, if the manufacturer's manuals or nameplates do not identify the type of dielectric fluid in the equipment, or if the equipment is known to be PCB according to available information. Drainage from the oil-water separator located adjacent to the fuel island, and stormwater runoff intercepted by two catch basins located south of the maintenance building flow into a drywell located 76 meters (250 feet) south of the maintenance headquarters building. Two other drywells receive stormwater runoff from the blacktop paved areas of the Ashe Substation facility.

Waste Type: Water

Waste Description: The drywells received drainage from the oil/water separator. It is likely that water contained some petroleum products.

Waste Type: Oil

Waste Description: The oil/water separator has received petroleum, oil and lubricants.

Code: 600-59

Classification: Accepted

Names: 600-59; BPA SWMU #12; Generator Storage Area Sump; H.J. Ashe Substation Storage Area

Reclassification: None

Type: Storage

Start Date: 1/1/1976

Status: Active

End Date:

Description: The storage facility is southwest of the maintenance headquarters building. The 6.1 meter (20 foot) by 4.6 meter (15 foot) generator storage area inside the Hazardous Waste Storage portion of the building has a double floor. The top flooring consists of a metal grate. The sub-floor is concrete with no outlet, that acts as a containment basin to catch any spill or release that might occur. The concrete sub-floor is sloped. The low end is considered to be a sump. The sump has no outlet. The building is actively being used by the Bonneville Power Administration (BPA) for storage of waste drums.

Location: The substation is located 0.5 miles northwest of and adjacent to the Energy Northwest property (formerly known as the Washington Public Power Supply System).

Related Sites/Structures: The site is related to the H. J. Ashe Substation, maintenance headquarters, gas pumps, control house, and switch yards. (See WIDS Sites 600-60 and 600-58).

Process Description: If a spill occurred, it would collect in the low end of the sloped sub-floor. It would be soaked up and disposed of properly.

Waste Type: Chemicals

Waste Description: Annual hazardous waste reports indicate that the following wastes are generated at the Ashe Substation, 1,1,1-Trichloroethane mixture, 1,1,1-Trichloroethane-contaminated soils, acetone waste mixture, spent photographic fluids, fixer, and developer, battery acid and fluid mixture, ferric chloride etching solution waste, methanol waste mixture (Karl Fisher reagent), pentachlorophenol and sodium pentachlorophenol, solvent compound-thinner waste, toluene-isopropanol with potassium hydroxide (titrating solution). All waste is taken to the generator storage area (SWMU #12). This unit is part of the Flammable, Herbicide, and Toxic Waste Storage Facility Building located southwest of the maintenance headquarters building. Hazardous wastes from maintenance activities at other substations are collected at this location.

Code: 600-60

Classification: Accepted

Names: 600-60; H.J. Ashe Substation Switchyard Facility

Reclassification: None

Type: Electrical Substation

Start Date: 1/1/1976

Status: Active

End Date:

Description: The H.J. Ashe Substation is an active, operating electrical switchyard facility. The H.J. Ashe Substation consists of two large structures, a control house and a maintenance building, and yard areas with smaller buildings used for dry chemical storage and a vehicle fuel station with

two underground gasoline tanks. The substation was first energized on December 3, 1976. Structures and equipment include an oil-filled circuit breaker (28,766 liters [7,600 gallons]), two underground gasoline tanks (15,140 liters [4,000 gallons] each), four mineral oil storage tanks (18,925 liters [5,000 gallons]), hazardous waste, flammable materials, and herbicide storage building (455 kilograms [1,000 pounds]).

Location: The substation is located 0.5 miles northwest of and adjacent to the Energy Northwest property (formerly known as the Washington Public Power Supply System).

Release Description: Six insulating oil leaks were identified in the switch yard at Reactor #1 on 9-13-90 (C-phase), at CT4885 on 9-13-90 (B-phase), at Reactor #1 on 10-2-90 (I-428), PCB 0-1026 on 4-26-91 and at Reactor #2 on 11-20-90 and 2-20-91 (I-429). There no further documentation on these releases. No cleanup actions were listed. Note that sampling was performed at these areas.

Related Sites/ Structures: There are two Solid Waste Management Units (SWMU) identified at the H. J. Ashe Substation. These are SWMU #12 (sitecode 600-59) - Hazardous and Flammable Storage Area, and SWMU #13 (Sitecode 600-58) Oil and Water Separator.

Process Description: The switching substation was built to supply electrical power produced by the Hanford Generating Plant to the Supply System's main electrical grid.

Waste Type: Chemicals

Waste Description: Annual hazardous waste reports indicate that the following wastes are generated at the Ashe Substation, 1,1,1-Trichloroethane mixture, 1,1,1-Trichloroethane-contaminated soils, acetone waste mixture, spent photographic fluids, fixer, and developer, battery acid and fluid mixture, ferric chloride etching solution waste, methanol waste mixture (Karl Fisher reagent), pentachlorophenol and sodium pentachlorophenol, solvent compound-thinner waste, toluene-isopropanol with potassium hydroxide (titrating solution). Polychlorinated biphenyls (PCBs) are also a potential contaminant of concern at this site because of the releases of insulating oil (See Releases Section).

Code: 600-117	Classification: Accepted
Names: 600-117; 300 Area Treated Effluent Disposal Facility (TEDF); 310 Building	Reclassification: Rejected (8/13/2013)
Type: Process Unit/Plant	Start Date: 1/1/1994
Status: Inactive	End Date: 1/1/2010

Description: The waste site evaluated Interim Closed Out in 2012. TPA-MP-14, Rev 2 states that buildings/facilities which do not contain a TSD unit shall not be documented in WIDS. This facility contained no TSD units and does not meet the TPA-MP-14 criteria. Therefore, the 600-117 waste site was reclassified as Rejected in 2013. The original definition of the waste site included the main treatment building (310 Building), three modular/mobile offices (MO443, MO744, MO745), two exterior Diversion Tanks, one exterior Equalization Tank, two exterior Clarifier Tanks, two drum storage areas and one chemical storage area. All the components are surrounded by a chain link fence. In May 2013, the waste site was redefined. The remaining portions of the original facility were reconfigured to accept process sewer effluent from the 325 laboratory operations. These active components became part of the 600-352-PL waste site.

The facility was deactivated in 2010. The 310 main treatment building (310 building) and two clarifier tanks (310-T-7A and B) were demolished in 2012. The chemical storage area, one drum storage area, MO-443 and MO-744 were removed. The primary effluent concrete sump, located approximately 12 feet below grade, was cleaned of debris and surveyed following demolition. The sump was found to be free of contamination and left in place.

Location: The facility address is 780 Uranium St. It is located 1.1 kilometers (0.7 miles) north of 300

Area on the east side of Route 4S and about 0.5 kilometers (0.3 miles) west of the Columbia River.

When this site was originally added to WIDS, it was considered to be located in the 600 Area. The site became part of the 300 Area because of a change to the 300 Area Boundary definition.

Related Sites/ Structures: Facilities associated with 310 Facility TEDF (600-117) operations originally included the 342 Sump and Control Building, the 182-centimeter (72-inch) diversion manhole in the 300 Area, the transfer piping between the 342 sump and the TEDF (see sitecode 600-352-PL), generating facilities that are connected to the 300 Area process sewer, and the TEDF outfall and transfer pipeline (WIDS Site 600-210). These items were transitioned to the 300-15:1 subsite.

Process Description: The facility treated and disposed of non-hazardous/non-radioactive process sewer effluent from the 300 Area. Treatment included chemical precipitation, selective ion exchange, and UV/peroxide oxidation to destroy organics and cyanide. Pipeline 600-352-PL fed effluent to the facility. After treatment, the effluent was originally disposed of at a submerged, single-port outfall in the Columbia River (Site sitecode 600-210). After 2009, the effluent was returned to the Combined Sewer System via pipeline 300-15. Chemicals used to treat the process sewer discharge included hydrogen peroxide, sodium hydroxide, sulfuric acid, ferric chloride, and ion exchange resins.

The 310 building treated waste water of heavy metals, mercury, organics, and cyanide. After receiving the waste water from the 342 Waste Collection Sump/Lift Station, it was processed at 300 GPM sequentially through an iron co-precipitation system to remove heavy metals, an ion-exchange system to remove mercury, and a hydrogen peroxide/ultraviolet radiation system to destroy organics and cyanide. The primary process chemicals, stored in tanks just outside the east wall, included ferric chloride (6,000 gal. tank), sodium hydroxide (6,000 gal. tank), sulfuric acid (4,000 gal. tank), and hydrogen peroxide (1,000 gal. tank). The two clarifier tanks (T-7A and T-7B) were a part of the iron co-precipitation process. Following the addition of chemicals and a flocculant, the waste water was gravity-fed to the clarifiers where solids precipitated. Clarified waste water overflowed the tanks for further processing, and the solids were pumped to a filter press for dewatering and eventual disposal.

Waste Type: Process Effluent

Waste Description: The 300 Area process sewer discharges via the 342 TEDF Sump to the 310 facility (300 Area TEDF). The wastes discharged to the process sewer is composed of metals, organics, and cyanide. The maximum flow rate the facility is design to accommodate is 1,200 liters per minute (300 gallons per minute). The expected flow rate is approximately 600 liters per minute (150 gallons per minute).

Closure Info: Interim (12/6/2012): The above-grade demolition of the 310 TEDF was completed in October 2012. the below-grade demolition was completed in December 2012. The primary effluent concrete sump, located approximately 12 feet below grade, was cleaned of debris and surveyed following demolition. The sump was found to be free of contamination and left in place. In addition, a small portion of the 310 slab and clarifier tanks on the west side of the facility were left in place because of active utilities that remain in the area. The demolished area was backfilled to grade with clean fill and topped with washed round rock. The building debris from demolition was removed and disposed of at the Environmental Restoration Disposal Facility (ERDF).

Prior to facility demolition, hazardous material such as batteries, Freon, oil, light ballasts, and miscellaneous construction materials. In addition, anthracite filter beds, sulfuric acid, ferric chloride, and sodium hydroxide heels remaining in chemical feed tanks were removed. No asbestos containing materials (ACM) were found in the building during inspection. Beryllium and radiological surveys were also conducted. No contamination was identified. No anomalies or soil staining was observed.

The balance of the facility components that remained operational and were left in place and consolidated with the pipeline site (see sitecode 600-352-PL and 300-15).

Code: 600-187 **Classification:** Accepted
Names: 600-187; West Lake Honey Dump Station **Reclassification:** None
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The site is located in a depression and appears to have been under water as part of West Lake when it was larger. Vegetation in the area is thick and short except for the lowest areas where the soil is very silty and shows desiccation cracks on the surface. There was no visual evidence of sewage waste in the area.

Location: The site is located south of the western portion of Gable Mountain, at the north end of West Lake (216-N-8). The site is 0.9 kilometers (0.6 miles) east of Route 4 North. A well traveled dirt road leads to West Lake from Route 4 North, about 0.8 kilometers (0.5 miles) past milepost 1.

Related Sites/ Structures: The water level in West Lake was affected by the water level in Gable Mountain Pond.

Code: 600-235 **Classification:** Accepted
Names: 600-235; Buried Lead Sheathed Telephone Cables **Reclassification:** Interim No Action (3/9/2005)
Type: Dumping Area **Start Date:** 1/1/1943
Status: Inactive **End Date:**

Description: The waste site has been evaluated and determined to require No Action. This site includes buried, inactive lead-sheathed telephone cable that was abandoned in place when the Integrated Voice Data Telephone System (IVDTS) was installed in 1988 by U. S. West. This system installed new telephone equipment in most buildings and installed new telephone switching facilities. In some cases the IVDTS reused portions of the old lead sheathed cables. The lead-sheathed cables were buried at a depth of 61 to 91 centimeters (24 to 36 inches). Approximately 483 kilometers (300 miles) of telephone cable was used at Hanford. Approximately fifty percent was buried and the remainder was over head lines. It is estimated that 204 kilometers (127 miles) of cable is buried at Hanford. The cables contain lead and will be required to be handled as dangerous waste if removed as part of an excavation or construction activity.

Location: The buried cables are located throughout the Hanford site.

Process Description: Beginning in the 1940's, the US Army began installing communication systems across the Hanford project property. The switching centers were originally tied together with lead sheathed cables. As communication systems have evolved over the years, many of the old switching centers were removed. In some cases, the old lines were reused, but in many cases the lead sheathed cables were abandoned in place. Lead-sheathed aerial cable lines ran from the 702-Central Telephone Exchange Building at Richland to switchboards housed in the 1720 Patrol Headquarters in the 100 B, D and F Areas and to the 704 Supervisor's Office Buildings in the 200 East and West Areas, and Building 3706 in the 300 Area, with interconnecting trunk lines between the 100 and 200 Process Areas. Details of the cable sizes have been documented in previous reports. No information has been located indicating underground telephone cables on the North Slope.

Waste Type: Equipment

Waste Description: The lead in the cable is considered hazardous but not the cable itself.

Closure Info: Interim: Approximately 204 kilometers (127 miles) of buried, lead-sheathed telecommunications cable has been left in place at the Hanford Site. Of concern is the disposition of this cable (Waste Information Data System [WIDS] site 600-235, Lead Sheathed Telephone Cables), and whether the lead present in the buried cable poses a risk to human health or the environment if left in place.

On September 15, 2003, representatives of the U.S. Department of Energy, Richland Operations Office (RL), the U.S. Environmental Protection Agency (EPA), and the Environmental Restoration Contractor (ERC) performed a field inspection at several buried lead-sheathed cable locations. Six candidate sites representing a variety of environmental conditions were selected for sampling to determine if releases of lead to the soil surrounding the lead-sheathed cable have occurred at levels that pose a risk to human health or the environment.

Code: 600-257

Classification: Accepted

Names: 600-257; 213-J Magazine Waste Storage Cavern; 213-J Vault; 213-J&K Storage Facility

Reclassification: Interim Closed Out (7/19/2011)

Type: Storage

Start Date: 1/1/1944

Status: Inactive

End Date:

Description: Sitecode 600-257, refers to the 213-J Vault. The 213-K Vault is described in sitecode 600-108. Both vaults have been remediated and Interim Closed Out.

The 213 facility (213-J and 213-K) was constructed into the south side of the base of Gable Mountain. The vaults are two parallel reinforced concrete, earth covered storage facilities. The south end of each vault forms a continuous reinforced concrete wing-shaped retaining wall with an attached reinforced concrete loading platform. The distance between the two vaults is 13.6 meters (44.5 feet). Each vault contains three rooms: magazine, vestibule, and instrument room. There are two outside, steel-hinged doors opening onto the loading platform. An inner steel vault door separates the vestibule from the magazine. The 213-J Vault is the western vault (600-257). The 213-K Vault (site 600-108) is the eastern vault and is not part of site 600-257.

Location: The unit is located north of Route 11A, east of Gable Mountain Pond.

Related Sites/ Structures: The site is associated with 600-107 (cribs) and 600-108 (213-K Vault).

Process Description: The vaults were originally built in 1944 to store containers of processed plutonium product. They were used only briefly for that purpose (1944-1947). The 213-J was more recently used by Pacific Northwest National Laboratory for storing uncontaminated soil samples from around the world for use in fallout studies by the Environmental Sciences Department. The samples were removed from the vault in March 2002 and remained empty until they were remediated.

Waste Type: Equipment

Waste Description: The vaults were constructed for storage of Hanford plutonium and were used only briefly for that purpose. No smearable radioactivity or radiation above background was detected inside the 213-J Vault in 1981. 213-J was used by Pacific Northwest National Laboratory (PNNL) to store uncontaminated soil samples collected from around the world from a fallout study. In March 2002, PNNL removed the soil samples from the 213-J Vault. The vault is now empty.

Closure Info: Interim: The vaults were used for storage of processed plutonium from 1944 to 1947, and were surrounded by a barbed wire fence and guard tower, both of which are no longer present. Processed plutonium product and waste were sent to the vaults in boxes. The 213-K Vault had also been used to store drums containing equipment that had been contaminated with radioactive sodium. All contaminated materials have been removed from the 213-K Vault, and it was empty prior to the initiation of remedial activities. The 213-J Vault was used in more recent years to store uncontaminated soil samples for use in fallout studies. These soil samples were removed from the vault in March 2002 in the process of emptying the vault. A waste site walkdown was performed on January 9, 2001, to verify that nothing was stored inside the 213-K Vault. The vault was empty and no radiological postings were found. An additional site walkdown was performed on May 1, 2003, at which time the fan room between the two vaults was assessed. Transite and other potential asbestos containing materials were used in construction of the fan room and in the construction of a fire-safe door in the interior of the vaults. The wood of the fan room building roof was found to be rotting and caving in. A 189-L (50-gal) condensate collection tank was found inside the fan room that may have been connected to the outside condensate piping seen on geophysical surveys of the area. No radiological readings were found in the floor drain or elsewhere in the fan room building.

The 600-108 and 600-257 waste sites were remediated together and documented in the RSVP-2011-051. The vaults were split into two sitecodes in June 1999 to accommodate multiple contractor responsibilities.

Remedial action at the sites began on November 8, 2010, and was completed on January 20, 2011. A small oil spill near the vault entrance was assessed. Concrete and other debris were stockpiled prior to removal from the 600-108 excavation for shipment and disposal to the Environmental Restoration Disposal Facility. The overburden soils that surrounded the vaults were stockpiled adjacent to the waste site and will be used to re-contour Gable Mountain to its pre-Hanford conditions. The foundation of the vaults was removed entirely, to a depth of approximately 1 to 2 meters (3 to 6 ft) at the base.

On December 9, 2010, an oil reservoir was found in the fan room at the 600-108 waste site, and a small amount of oil was released to the ground just south of the vault entrance. Most of this oil spilled onto a concrete slab that was subsequently removed; however, a small amount may have leaked under the wall into the area where the vaults were located. In-process samples were collected from this oil spill. The spilled oil was staged on Griflon to the south of the excavated area.

Code: 600-261	Classification: Not Accepted (Proposed)
Names: 600-261; 601 Structures; Standard Gauge Railroad Track	Reclassification: None
Type: Foundation	Start Date: 1/1/1943
Status: Inactive	End Date: 1/1/1998

Description: The site consists of the railroad track system on the Hanford site (beginning at Horn Rapids road and proceeding North). The section from Horn Rapids Road to Energy Northwest is still active. The rest is inactive. This site does not include any radioactive unplanned releases that may have effected portions of the track during Hanford operations. The documented radioactive releases are separate WIDS entries. In 2015, Washington Closure Hanford issued a report related to the removal of sections of abandoned rail systems in the 100, 300 and 600 Areas (See MRD-2014-0004). Approximately 42 kilometers (26 mi) of abandoned railroad rail, more than 50 railroad switches, over 40,000 ties, and miscellaneous signs and hardware were removed between September 2010 and February 2011 by a specialty subcontractor and reused or disposed at ERDF. Between March 2011 and November 2014, additional abandoned railroad

	rails, ties, and hardware were removed by WCH remediation subcontractors or WCH crews.
Location:	The Hanford railroad track system extends from the north side of the Horn Rapids road right-of-way to each operating area of the site, and includes railroad spurs, sidings and junctions.
Related Sites/ Structures:	Movement of contaminated material into and out of the canyon facilities in 200 East and 200 West areas on rail cars resulted in several documented Unplanned Releases located on various rail spurs. The documented UPRs associated with railroad tracks include: 300-8, 200-W-21, 200-W-87, 200-E-44, UPR-200-E-10, UPR-200-E-11, UPR-200-E-12, UPR-200-E-101, UPR-200-E-20, UPR-200-E-20, UPR-200-E-33, UPR-200-E-61, UPR-200-E-69, UPR-200-E-88, UPR-200-E-112, UPR-200-W-3, UPR-200-W-4, UPR-200-W-41, UPR-200-W-44, UPR-200-W-46, UPR-200-W-48, UPR-200-W-58, UPR-200-W-60, UPR-200-W-65, UPR-200-W-69, UPR-200-W-73, and UPR-200-W-117.
Process Description:	The railroad was used to move supplies, equipment and reactor fuel around the Hanford site. Coal was delivered to the coal fired steam generating plants by rail car. Large pieces of equipment (pumps and centrifuges) needed to operate the canyon separations facilities and tank farm activities were transported on rail cars. Large burial containers of contaminated waste were removed from the canyon buildings, placed on flat bed rail cars and transported to specific burial trenches with railroad access. Oversight of the railroad between Horn Rapids Road and the Energy Northwest switch (except for the 300 lead) is the responsibility of the Port of Benton (POB), under DOE-RL ownership. Fluor Hanford retains oversight of the other sections of the railroad not included as part of facilities (Tank Farms, PUREX, PFP, N Reactor, etc.). This includes all mainline, spurs, and track within the 200 Areas and the 300 Area that are outside plant or project boundaries.

Code:	600-270	Classification:	Accepted
Names:	600-270; Horseshoe Landfill; Nike Missile Base	Reclassification	Deleted From NPL (12/5/2005)
Type:	Dumping Area	Start Date:	1/1/1950
Status:	Inactive	End Date:	1/1/1970
Description:	The site is a former historical landfill that was deleted from the NPL in 1996. The site was part of a former Nike missile base consisting of structures which supported missile launch, control, and maintenance functions, living quarters for base personnel, and storage buildings for hazardous substances use in the maintenance of the facilities and missile operations. Post Closure sampling for pesticide contamination occurred between 1998 and 2003. Soil remediation was done between May and August 2005.		
Location:	The site was located on the Fitzner-Eberhardt Arid Lands Ecology Reserve, a.k.a., Arid Lands Ecology (ALE) Reserve. Further the site was located on the northeastern slope of Rattlesnake Mountain about 8 kilometers (5.0 miles) west of the intersection of Highways 240 and 225.		
Related Sites/ Structures:	WIDS Sites 600-116, 600-270, and 600-271 are all related to Nike missile base operations on the Fitzner-Eberhardt Arid Lands Ecology Reserve.		
Process Description:	During the base's operation, missile maintenance included the use of solvents, fuels, acids, hydraulic fluid, and paints. All wastes generated during operations were disposed of in onsite landfills, or dumped nearby offsite.		
Waste Type:	Demolition and Inert Waste		
Waste Description:	The majority of the waste consisted of non-hazardous construction and demolition waste, scrap metal and lumber, empty bottles, cans and drums. A summary of the waste found in each of the 6 anomalous areas is described below.		

Horseshoe Landfill/A-1 - boulders were encountered at 1.2 meters (4 feet) below ground surface, otherwise there was no evidence of any buried wastes or disturbed soil.

Horseshoe Landfill/A-2 - no evidence of any buried waste or disturbed soil was found.

Horseshoe Landfill/A-3 - abundant surface metal debris, barb wire, miscellaneous scrap metal, miscellaneous building materials; no evidence of any buried wastes or disturbed soil.

Horseshoe Landfill/A-4 - bottles, rusted metal debris, car parts, car chassis, car engine with oil pan missing, 7-208 liter (7-55 gallon) drums ripped open and partially collapsed (empty) were found.

Horseshoe Landfill/A-5 - bottles, pieces of rusted metal, a few animal bones were found.

Horseshoe Landfill/A-6 - no evidence of buried wastes or disturbed soil in three excavations on the west side of A-6 except for copper grounding wire found about 15 centimeters (6 inches) below ground surface. Sheet metal scrap, fence post, wood debris, 0.61 meter (2 foot) diameter washing machine washtub, abundant 2.54 centimeter (1 inch) diameter cable, cement blocks, bottles, metal scrap, 3 ripped and partially collapsed 208 liter (55 gallon) drums, car engine with oil pan missing, wire, some plastic/metal parts, 4-25.4 centimeter (4 10-inch) battery-type containers with screens.

Waste Type: Chemicals

Waste Description: Suspected wastes included solvents, fuels, acids, hydraulic fluid, and paints. Contaminants sampled for were barium, chromium, lead, acetone, bis (2-ethylhexyl) phthalate, butylbenzylphthalate, diethylphthalate, di-n-butylphthalate, phenol, chlordane, DDT, DDE, DDD, Endosulfan B, Endrin, Methoxychlor, gasoline, diesel, heavy oils, diesel. Based on the results from soil excavated at A-6, the original 16 contaminants (draft ROD) were expanded to include DDT, DDE, and DDD.

Closure Info: Final (12/5/2005): Based on findings from similar landfills on the North Slope of the Hanford Site, EPA and Ecology required that limited characterization of the Horseshoe Landfill be carried out. Between July 5 and 12, 1994, Golder Associates (under contract to the USACE) conducted electromagnetic (EM) profiling, magnetics (MAG), and ground-penetrating radar (GPR) surveys at the Horseshoe Landfill. The survey covered an area approximately 152 meters (500 feet) by 183 meters (600 feet). Anomalous EM zones were categorized as low to high depending on the deviation from background levels. Anomalous zones were identified as A-1 through A-6. Full excavation of each anomaly was only required when field screening indicated the possible presence of contaminants. In order to excavate for the presence or absence of hazardous material, each geophysical anomaly was excavated in longitudinal trenches, measuring 0.5 to 3 meters (5 to 10 feet) wide and 1 to 2 meters (3 to 7 feet) deep. Trenching activities for each disposal cell consisted of excavating, inventorying, and segregating any potentially hazardous materials.

Remediation began on May 17, 2005 and continued to August 24, 2005. Soil was excavated to a depth of 1.2 meters (4 feet) in the southern portion of the landfill. Approximately 4,935 BCM of soil was removed for disposal at the Environmental Restoration Disposal Facility. A combination of statistical sampling and judgmental sampling to verify the completeness of remediation was performed, and analytical results were shown to meet the cleanup objectives for direct exposure (1 mg/kg DDT) and ecological protection (0.75 mg/kg total DDT/DDE/DDD). In accordance with this evaluation, the verification sampling results support that the remediation of the DDT contaminated soil has been acceptably performed as provided in EPA.

Excavated materials were screened visually and by field instruments. Field test kits were onsite

and used for field screening when the presence of contaminated materials was suspected. Depending on the suspected presence of contaminated materials, soil samples were collected for offsite analysis. Contaminated materials found during the excavation and/or by screening methods were inventoried and segregated (by shovel or trackhoe). Large volumes of contaminated materials encountered during excavation were stockpiled near the excavation site on 6-mil visqueen and covered with hay-bale tarps.

Approximately 1911.5 cubic meters (2,500 cubic yards) of soil contaminated with the pesticide DDT and its breakdown products were discovered. These soils were shipped to the Chemical Waste Management hazardous waste landfill in Arlington, Oregon. No other contaminants were detected above regulatory cleanup levels.

Following cleanup actions, excavations were backfilled, compacted using nonhazardous materials and clean fill, and graded to original conditions.

Code: 600-271	Classification: Accepted
Names: 600-271; Nike Missile Base Landfill	Reclassification: Deleted From NPL (9/30/1996)
Type: Dumping Area	Start Date: 1/1/1950
Status: Inactive	End Date: 1/1/1970

Description: The site was remediated and Deleted from the NPL. It was a former landfill at the Nike missile base. The base consisted of structures which supported missile launch, control, and maintenance functions, living quarters for base personnel, and storage buildings for hazardous substances use in the maintenance of the facilities and missile operations.

Location: The site was located on the Fitzner-Eberhardt Arid Lands Ecology Reserve, a.k.a., Arid Lands Ecology (ALE) Reserve. Further the site was located on the northeastern slope of Rattlesnake Mountain about 8 kilometers (5.0 miles) west of the intersection of Highways 240 and 225. This site is about 305 meters (1,000 feet) south of the Horseshoe Landfill Site (600-270).

Related Sites/ Structures: The site is related to other structures that were a part of the Nike Missile Base. See WIDS site 600-116 for an overall description of other structures.

Process Description: During the base's operation, missile maintenance included the use of solvents, fuels, acids, hydraulic fluid, and paints. All wastes generated during operations were disposed of in onsite landfills, or dumped nearby offsite.

Waste Type: Demolition and Inert Waste

Waste Description: The majority of the waste consisted of non-hazardous construction and demolition waste, scrap metal, lumber, empty bottles, and cans. Nike Missile Base Landfill/A1 - concrete blocks, bottles, wood, and metal debris. Nike Missile Base Landfill/A2 - surface debris; long metal U-bolts, sheet metal scrap, miscellaneous scrap metal. There was no evidence of any buried waste or disturbed soil. Nike Missile Base Landfill/A3 - There was no evidence of any buried waste or disturbed soil.

Closure Info: Final: Based on findings from similar landfills on the North Slope of the Hanford Site, EPA and Ecology required a limited characterization of the Nike Missile Base be carried out.

A previous investigation occurred between July 5 and 12, 1994, by Golder Associates. They conducted electromagnetic (EM), magnetic (MAG), and ground-penetrating radar (GPR) surveys at the Nike Missile Base Landfill. Over an area of approximately 152 meters (500 feet) by 137 meters (450 feet), 9 separate Electromagnetic anomalies (EM) areas were identified. Anomalous EM zones were categorized as low to high. A total of three anomalies were excavated (8/17/1994 - 8/18/1994) at the Nike Missile Base Landfill. Anomalies removed

included two high EM anomalies and one moderate EM anomaly. Anomalous zones were identified as A-1 through A-3. Full excavation of each anomaly was only required when field screening indicated the possible presence of contaminants. In order to excavate for the presence or absence of hazardous material, each anomaly was excavated in trenches measuring 1.5 to 3 meters (5 to 10 feet) wide and 1 to 2 meters (3 to 7 feet) deep. Trenching activities for each disposal cell consisted of excavating, inventorying, and segregating any potentially hazardous materials. Excavated materials were screened visually and by field instruments. Field test kits were onsite and used for field screening when the presence of contaminated materials was suspected. Depending on the suspected presence of contaminated materials, soil samples were collected for offsite analysis. Contaminated materials found during the excavation and/or by screening methods were inventoried and segregated (by shovel or trackhoe). Contaminated materials encountered during excavation were stockpiled near the excavation site on 6-mil plastic and covered with hay bale tarps. Following cleanup actions, excavations were backfilled with nonhazardous materials and clean fill, and graded to original conditions.

Code:	600-272	Classification:	Accepted
Names:	600-272; Petroleum-Contaminated Borehole; Well 699-43-2	Reclassification	None
Type:	Unplanned Release	Start Date:	
Status:	Inactive	End Date:	
Description:	The site is hydrocarbon contamination in well 699-43-2. Well 699-43-2 is a 16.8-centimeter (6-5/8-inch) diameter well with a 10-centimeter (4-inch) PVC liner. Limited information is available about well construction. This well is believed to have been drilled to a depth of 120 meters (390 feet) in 1980 to support geologic studies for reactor citing. The well is currently 103.4 meters (339 feet) deep. The depth to water is 9 meters (26 feet) below land surface. It is believed that the well is not screened to groundwater and is open at the bottom.		
Location:	The well is located in a remote part of the 600 area, approximately 1.5 miles south of the former Hanford townsite, and approximately 300 meters (1000 feet) from the nearest vehicle access. Well 699-43-2 is approximately 600 meters (2000 feet) from the Columbia River.		
Release Description:	While the source of hydrocarbons in well 699-43-2 is unknown, the lack of vehicle tracks adjacent to the well, and the determination that the hydrocarbons were diesel fuel or kerosene derived suggests that contamination may have occurred during drilling.		
Waste Type:	Oil		
Waste Description:	The waste is an oil/water matrix. A sample of the water in the well showed 4.5 milligrams/liter (mg/L) of total petroleum hydrocarbons, 12.3 mg/L of oil and grease, and about 360 mg/L (36,000 micrograms per liter) of unknown alkanes. The likely source is diesel fuels or kerosene type materials. The liquid waste matrix will designate as D001 due to its low flash point.		

Code:	600-273	Classification:	Not Accepted (Proposed)
Names:	600-273; Pile of Red Material at Riverland	Reclassification	None
Type:	Dumping Area	Start Date:	
Status:	Inactive	End Date:	
Description:	The site is a pile of red material about 1.4 meters (4.5 feet) high, 9 meters (30 feet) long, and 5 meters (15 feet) wide. The volume calculated by GPS is 113 cubic meters. The site is near the end of a long berm headed west from the old railroad maintenance yard at Riverlands. Patches of similar colored soil can be seen throughout the area. No vegetation is growing in the upper		

half of the pile, but cheatgrass and other weeds have established at the bottom, presumably where their roots can reach soil. A magnet will pick up some of the fine particles in the pile, suggesting that the material is a crushed iron ore.

Location: The site is at the far west end of the railroad maintenance facility, about 1.6 kilometers (1 mile) from Highway 24, and 150 meters (500 feet) north of the road to the Midway Substation. It is visible from the Midway Substation road.

Related Sites/ Structures: This site is at the far west end of 600-101, the Riverland Rail Yard Maintenance Facility.

Waste Type: Soil

Waste Description: The pile appears to be a pile of iron ore dumped from a hopper car so the car could be worked on at the maintenance facility. Iron ore was used in making the concrete for reactors since it provided additional shielding. A similar mound of material was found at the 100 B/C Area. Samples were taken of that mound. The material at 100 B/C contained 48% iron, 1.5% chromium, and 0.2% aluminum.

Code: 600-278

Classification: Accepted

Names: 600-278; Bioremediation Pad Within Gravel Pit 9; Oil Contaminated Soil

Reclassification: Closed Out (5/4/2004)

Type: Surface Impoundment

Start Date: 1/1/1999

Status: Inactive

End Date:

Description: The waste site is bioremediation area located in the eastern section of Gravel Pit #9. It has been evaluated and Closed Out.

Location: Pit #9 is located approximately 1.2 kilometers (2 miles) north of 300 Area, east of Route 4S.

Related Sites/ Structures: The site is associated with the 384 Day Tanks (300-223) and Gravel Pit #9 (600-246).

Process Description: In 1999, the petroleum contaminated soil was removed from around the 384 fuel oil day tanks and spread onto the ground inside Pit 9 to facilitate bioremediation of petroleum contained in the soil. In 2000, the bioremediation area had been posted as an Underground Radioactive Material Area and later a Soil Contamination Area. The posting was the result of the fact that the 300 Area is posted as an Underground Radioactive Material Area, so the removed soil was potentially contaminated. In June 2003, it was determined the radiological postings were not appropriate and were removed.

Waste Type: Oil

Waste Description: The soil on the bio remediation pad was originally contaminated with petroleum (fuel oil #6 and diesel oil #2) from the excavation of the 384 Day Tanks (sitecode 300-223).

Closure Info: Final: Soil samples were collected in September 2003 and analyzed for petroleum hydrocarbons to check the progress of the bioremediation. Results indicated the levels were below chapter 173-340 of the Washington Administrative Code (WAC) limits. The results were sent to Ecology by DOE/RL in a letter entitled "Completion of Corrective Action for Petroleum Contaminated Soil Associated with the 384 Powerhouse Day Tanks," dated March 1, 2004. Once Ecology confirms that the soil meets cleanup standards, the soil will be used for cover at the inert waste landfill located at Pit 9.

Code: 600-284-PL

Classification: Accepted

Names:	600-284-PL; Cross Site Transfer Pipeline; Lines V360, V361, V362, V363, V364 and V366; Old Cross Site Transfer Line; Original Cross Site Transfer Pipeline; Piping Associated with UPR-600-20, Cross Site Transfer Line	Reclassification	None
Type:	Encased Tank Farm Pipeline	Start Date:	1/1/1952
Status:	Inactive	End Date:	1/1/1995
Description:	The waste site is the underground pipeline that is located beneath the surface stabilized UPR-600-20 soil contamination site. It is posted with Underground Radioactive Material signs.		
Location:	The encased pipeline runs from 241-UX-154 Diversion Box, adjacent to 221-U inside 200 West Area, to the 241-ER-151 Diversion Box inside 200 East Area.		
Release Description:	The surface of the buried waste transfer line became contaminated through biological transport of radioactive materials that leaked in the pipeline encasement and windblown particulates from the vent station. In March 1988, while conducting a radiological survey of the 241-EW-151 Vent Station (located approximately mid way between 200 East and 200 West Areas on the transfer line) contamination was identified approximately 100 meters (300 feet) outside the established radiation zone boundaries of the vent station, above the transfer line. The Mobile Surface Contamination Monitor (MSCM) tractor was used to survey the entire surface of the pipeline. Numerous spots of contamination were identified at various locations along the entire length of the transfer line. Contamination levels ranged from a few hundred counts per minute to 750 millirem per hour. To characterize the integrity of the pipeline, eight boreholes were drilled with an auger at four locations along the transfer line. Although no contamination was found to have leaked below the pipeline encasement, contamination was found in sagebrush growing next to the encasement. This indicated that the roots of the sagebrush had penetrated the encasement. The contamination was given an Unplanned Release number UPR-600-20 in 1989.		
Related Sites/ Structures:	The pipeline is associated with the 241-UX-154 Diversion Box, the 241-ER-151 Diversion Box, 241-EW-151 Vent Station and UPR-600-20. The active Export Water line intersects the 600-284-PL pipeline inside 200 East Area, south of the Canister Storage building. The new Cross Site Transfer line (600-269-PL) intersects the old cross site line at one location, south of the Canister Storage Bldg. The LERF and TEDF lines (600-291-PL and 600-399-PL) also intersect the old cross site line at one location, south of the Canister Storage Bldg.		
Process Description:	The cross site transfer line was originally constructed in 1952 to support the Uranium Metal Recovery operations. Various process and tank farm waste has been transported between 200 East and 200 West areas through this underground concrete encased group of pipelines. The cross site transfer line consists of six stainless steel pipelines (V360, V361, V362, V363, V364, V366) inside a concrete encasement. The encasement type is known as 6-59, indicating there are six lines inside a 59 inch wide encasement. The concrete encased stainless steel pipelines are buried at depths that range from 1.5 to 4.5 meters (5 to 15 feet). Fifty eight encasement test risers (swab risers) were spaced regularly along the pipeline that provided access to the encasement void space. This cross site line was replaced with a new pipeline in 1995 (see 600-269-PL).		

Code:	600-288	Classification:	Accepted
Names:	600-288; Soil Corrosion Test Site	Reclassification	None
Type:	Experiment/Test Site	Start Date:	1/1/1993
Status:	Inactive	End Date:	

Description: The waste site is approximately a 4.5 meter (15 foot) diameter circle. The area contains five, 15 centimeter (6 inch) diameter, polyvinyl chloride shafts, one 7.6 centimeter (3 inch) diameter PVC soil moisture access port and one 5 centimeter (2 inch) diameter PVC instrument access shaft. The shafts are set in the ground to a depth of approximately 9 meters (30 feet). Only a few inches of each PVC pipe casing is visible above the ground surface.

Location: The test site is located east of Route 3, northeast of 200 West Area. It is north of the Meteorology Station (622-R) and the south of an abandoned airstrip.

Process Description: The site was used to test the pieces of painted low carbon steel and galvanized drums to assess the effect of corrosion when the material was buried in Hanford soil.

Code: 600-289	Classification: Accepted
Names: 600-289; Dumping Area Near Shooting Range	Reclassification: None
Type: Dumping Area	Start Date:
Status: Inactive	End Date:

Description: The site consists of an area containing various scattered empty containers. Some containers have labels indicating potential hazardous contents. There is an area of potential asbestos containing material.

Location: The site is located northwest the HAMMER facility and of the Patrol Training Academy building 664. It is north of Shooting Range #1. It was originally described as being northwest MO222, MO302, and 661A, but the trailers are in the process of being removed. The debris is about 1000 to 1500 feet west of 663. You are required to check in at the 664 Patrol administration building to gain access to the area. It is located on property designated as belonging to the Hanford Patrol Training Academy.

Waste Type: Barrels/Drums/Buckets/Cans

Waste Description: There are several groups of empty drums and oil cans. One 55-gallon drum is marked "INSECTICIDE AIRPLANE SPRAY 20% D.D.T."

Code: 600-338	Classification: Discovery
Names: 600-338; Diesel Spill near 623A Bldg on Rattlesnake Mountain	Reclassification: None
Type: Unplanned Release	Start Date: 1/1/2008
Status: Inactive	End Date: 1/1/2008

Description: The site consisted of a diesel fuel leak near the northwest corner of Building 623A, located on Rattlesnake Mountain. The leaking fitting on a diesel fuel return line from an emergency power generator was discovered on September 11, 2008. It was repaired September 12, 2008. The leak resulted in an affected surface area of approximately 0.61 meters to 0.91 meters (2-3 feet) wide by 1.52 meters to 1.83 meters (5-6 feet) long. Soil remediation began on September 18, 2008. The release area is not marked or posted in the field. It is mapped in the GIS system as a data point. The 623A building was demolished in October 2010.

Location: The release was located between a diesel tank and the building, near the northwest corner of Building 623A (Plant Radio Relay Bldg on top of Rattlesnake Mountain).

Release Description: During a routine visit of the 623A building on September 11, 2008, an area of discolored soil was discovered on the west side of the building. Further investigation noted that fittings from the emergency back-up generator near the building had leaked approximately 20 gallons of fuel

onto the ground. The leak was in a previously disturbed area. Proper notifications were made and the leaking fittings were repaired on September 12, 2008. Soil excavation was conducted between September 18, 2008 and October 28, 2008. Samples were collected on October 8, October 28, 2008 and November 25, 2008.

**Related Sites/
Structures:** The spill was associated with the 623A building.

Waste Type: Oil

**Waste
Description:** Diesel fuel oil (number 2) released to the ground via a leaking pipe fitting.

Closure Info: Interim: Excavation of the diesel contaminated soil began on September 18, 2008. Characterization samples were collected as composites from the bottom of the excavation, as well as from the front, left, and right faces of the excavation, as you face the building (COC 100808). Waste characterization sampling and analysis was conducted using EPA SW-846 Method 8260 for volatile organic contaminants by gas chromatography and mass spectrometry.

During a routine visit of the 623A building on September 11, 2008, an area of discolored soil was discovered on the west side of the building. Further investigation noted that fittings from the emergency back-up generator near the building had leaked approximately 20 gallons of fuel onto the ground. The leak was in a previously disturbed area. Proper notifications were made and the leaking fittings were repaired on September 12, 2008. Soil excavation was conducted between September 18, 2008 and October 28, 2008. Samples were collected on October 8, October 28, 2008 and November 25, 2008.

A follow up excavation was done on October 8, 2008. Cleanup verification analysis was conducted using the NWTPH-DX method for diesel range organics in soil and water. The NWTPH-DX method adapts the Oregon Department of Environmental Quality TPH-D method; the Ecology WTPH-D method; and EPA SW-846 Methods 3510, 3540/3550, and 8000 for the qualitative and quantitative analysis of semi-volatile petroleum products using methylene chloride extraction followed by GC/Flame Ionization Detector (FID) analyses. All sample analyses were performed at WSCF. Clean-up verification sample results for the three "face" samples were all below the action level of 2000 mg/kg (130, 180, and 300 mg/kg TPH Diesel for the front, left, and right samples respectively). The sample taken at the bottom of the excavation had a result of 7100 mg/kg TPH Diesel and exceeded the initial action level. Therefore, additional excavation and verification sampling was planned. Based on the October 8, 2008 sample analysis results, Fluor Hanford concluded that the lateral extent of contamination had been bounded by the excavation.

An October 28, 2008 clean-up verification sample, taken from the bottom of the excavation, had a result of 8500 mg/kg TPH Diesel and also exceeded the initial action level. Therefore, additional excavation and verification sampling was planned prior to backfill. Samples were collected from locations where the highest concentrations were most likely to be found based on visual staining. This approach yielded information needed to reach conclusions about the vertical and lateral extent of contamination.

Based on the 11/25/08 sample analysis results, residual concentration of TPH at the spill site were less than 2000 ppm. Although subsurface detectable levels of contamination remain at the site, the residues do not pose a threat to ecological/terrestrial receptors. Moreover, natural attenuation and biodegradation processes have already been observed and will further decrease the potential for ecological/terrestrial receptor uptake/exposure. The cleanup verification samples have indicated that soil concentrations of toxic or carcinogenic constituents were either non-detectable or were below levels typically used by Ecology to ensure protection of human health and the environment.

Code: 600-349 **Classification:** Accepted

Names: 600-349; Unexploded Ordnance (UXO) outside of 600-149 **Reclassification:** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: This site consists of potential Unexploded Ordnance (UXO) in an area bounded by the entire perimeter of the 600-149 waste site and extends from the perimeter to as far as a fired rifle grenade could travel. The area with the highest potential to contain munitions and explosives of concern includes a portion of Gable Mountain south of Prid Canal.

Location: The waste site is located on the west side of the 600-149 waste site boundary.

Related Sites/ Structures: 600-349 is associated with sitecode 600-149, Small Arms Range, Rifle and Pistol Range.

Code: 600-350 **Classification:** Accepted

Names: 600-350; PNL Water Catchment Experiment **Reclassification:** Interim Closed Out (9/14/2011)

Type: Experiment/Test Site **Start Date:**

Status: Inactive **End Date:**

Description: This site has been remediated and Interim Closed Out. It consisted of two separate fenced areas containing linear soil mounds.

Location: This feature is located approximately 700 meters northwest of the Hanford town site's former high school and 122 meters east of route 2N.

Process Description: The Pacific Northwest Laboratory (PNL) constructed this site to perform rain harvesting experiments. The experiments were done to study the use of water harvesting (the collection and use of rainfall runoff) to restore the vegetative productivity of strip mined lands in arid regions. The study tested the technical and economic feasibility of using partially leveled spoil banks at strip mines as catchment areas to collect and direct runoff to the top soiled valley floor where crops were cultivated. The study was performed from 1976 through 1981 (PNL-4538). The site was modified with a small drag line to resemble the smoothed spoil banks of a coal mine; cobble alluvium of the Columbia River served as spoil. Seven areas were prepared, three with valleys that ran north to south, and three with valleys that ran east to west; one area was prepared without adjacent slopes to simulate leveled spoil banks. The north-south valleys were protected from the strongest winds in the region, while the east-west valleys were parallel with the strongest winds. The valleys were each 90 m (300 ft) long by 18 m (60 ft) wide at the top of the catchment areas ("spoil banks") and 4 m (13 ft) wide at the surface of the topsoil, with a 33° angle of repose for each slope. The runoff efficiency of the surface was evaluated by applying a pore filling or waterproofing substance to the surface of the spoil banks. Three materials (rubber sheeting, paraffin and asphalt-rubber) were used for slope treatments. The rubber sheeting was 1.59 mm (1/16 in.) thick EPDM (butyl rubber) installed in September 1976 in one NS valley. Paraffin (approximate melting point 53°C) was melted and sprayed at the rate of approximately 1 kg/m² on the cobbled catchment area of a NS valley in May of 1977 and on the smooth catchment area in an EW valley in September 1977. Asphalt-rubber, a mixture of ground rubber and asphalt, is used as a crack sealer on roadways and as a liner for reservoirs. This treatment was applied to catchment areas of an EW valley in September of 1977 at the rate of 4 to 8 l/m². Catchment (slope) treatments at Hanford included: Flat Control - NS oriented area with no adjacent slopes or catchment areas Rubber sheeting - NS valley with rubber

sheeting on catchment area Asphalt-rubber - EW valley with asphalt-rubber on catchment area Paraffin NS - NS valley with paraffin on catchment area Paraffin EW - EW valley with paraffin on catchment area Bare surface NS - NS valley with no treatment on catchment area Bare surface EW - EW valley with no treatment on catchment area.

Closure Info: Interim (9/14/2011): Remedial action at the 600-350 waste site took place from March 14 to April 4, 2011, and consisted of removing the asphalt coating from the "V"-shaped area between and on the sides of the mounds. The asphalt debris was directly loaded into containers for disposal at the Environmental Restoration Disposal Facility.

Based on observations during a March 2010 walkdown to support remedial action, it was determined that the asphalt material should be removed and the mounds flattened for aesthetic purposes.

Code: 600-351	Classification: Accepted
Names: 600-351; Stained areas outside of 100-F Area	Reclassification: Interim Closed Out (1/10/2012)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: This site has been remediated. The site contained two stained soil areas. The northern area consisted of stained, crusted soil and no vegetation, measuring 4 meters (13.2 feet) in diameter. The southern area consisted petroleum based material released to the ground. The soil was crusted with no vegetation. It measuring 2 meters (6.6 feet) in diameter. Empty oil cans were scattered around the area.

Location: The areas were located approximately 76 meters (250 feet) south of F Ave. (north). The northern area was located at Easting: 579790.07 Northing: 146715.53. The southern area was located at Easting: 579789.44 Northing: 146706.44.

Closure Info: Interim (1/10/2012): Initial remedial action at the 600-351, waste site began and was completed on March 10, 2011. Following initial remediation, verification sampling performed on June 6, 2011, found a sample result that exceeded the direct exposure RAG for total petroleum hydrocarbons (TPH), diesel range at 210 mg/kg. The recommended path forward was to remediate the south excavation further, and re-sample the south excavation. Additional remediation was performed on July 12, 2011, and August 4, 2011. A second round of additional remediation and re-sampling of the north portion of the north excavation was performed on August 4, 2011.

Code: 600-352-PL	Classification: Accepted
Names: 600-352-PL; Pipeline from 342 Sump to 310 Facility; 300 Area Retention/Transfer System (RTS) and Pipeline	Reclassification: Consolidated (9/25/2013)
Type: Process Sewer	Start Date: 1/1/1994
Status: Inactive	End Date: 1/1/2012

Description: In September 2013, the 600-352-PL pipeline was Consolidated with the 300-15 Process Sewer waste site and was considered part of the 300-15:2 subsite (per form 2013-118). The waste site is the underground, 25 centimeter (10 inch) diameter high density polyethylene pipeline extending from the 342 sump and the 310 facility Retention/Transfer System (RTS) (see sitecode 600-117). In April 2015 it was moved to 300-15:5.

In May 2013, the 600-117 (310 Facility) waste site was redefined. Portions of the 310 facility were demolished and Interim Closed Out. The remaining, active portions of the original facility were reconfigured to accept process sewer effluent from the 325 laboratory operations. These active components became part of the 600-352-PL waste site. The active components include MO-745, one drum storage area, two diversion tanks and one equalization tank. The second drum storage area was converted to a truck unloading station. All of these components became part of 300-15 (per form 2013-118 Rev. 1).

Location: The majority of the pipeline is located north of the 300 Area. It begins at the 342 waste collection sump and extends northward to the 310 Retention Storage (RTS) facility. It follows the abandoned rail spur and then parallels Stevens Drive.

Related Sites/ Structures: The pipeline is associated with the 342 waste Collection Sump, the remaining active components of the 310 Facility, 300-15 process sewer and 600-117.

Process Description: The 300 Area Retention/Transfer System is a batch release operation. 300 Area effluent is pumped into the 300 Area Retention/Transfer System (RTS) via this pipeline and the 342 waste collection sump. The pipeline terminates at the 310 valve vault. The water is temporarily stored in one of three retention tanks located in the 310 facility complex. After being analyzed, the effluent below regulatory limits was originally returned to the 300 Area Process Sewer pipeline (see sitecode 300-15). Since becoming active in 1994, most of the facilities in the 300 Area have been demolished. In 2012, the 310 facility was reconfigured to accept process sewer effluent from the only the 325 laboratory operations. After 2012, the effluent below regulatory limits was originally returned to the Combined Sewer System (that is connected to the City of Richland Sewer). Any waste water that exceeds acceptable levels of contaminants is trucked to the 200 Area Effluent Treatment Facility (ETF) for processing.

This Site Was Consolidated With:

Code: 300-15

Names: 300-15; 300 Area Process Sewer System

Code: 600-353

Classification: Accepted

Names: 600-353; Non-Operational Property Evaluation Zone 1, Areas of Distressed Vegetation and Oil Filter Debris

Reclassification: None

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: During a Non-Operational Property Evaluation walkdown, an area of concern was located south of Route 11A. One location containing deteriorating crushed oil filters was identified. Another location, west of the oil filters was found to be devoid of vegetation. Each location measured approximately 25 square feet.

Location: The area of concern is located northwest of 200 West Area, south of Route 11A. It is east of the intersection of Route 11A and Route 6.

Code: 600-354

Classification: Accepted

Names: 600-354; Non-Operational Property Evaluation Zone 1, Debris Field West of Army Loop Road

Reclassification: None

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The 600-354 debris field, located west of Army Loop Road, includes multiple miscellaneous debris items scattered across an area roughly 800 meters long and 500 meters wide. Items identified during Non-Operational Property Evaluation walkdowns include rusty cans, buckets, metal debris, tar, transite and areas of disturbed vegetation. Several large mounds of dirt were noted, but their function is unclear. There is evidence of a trench containing visible surface debris with the potential of containing subsurface debris. A previously identified concrete bottom pit is include in this waste site.

Location: The items associated with 600-354 are located south of the intersection of Route 11A and Route 6, on the west side of Army Loop Road. The area is northwest of 200 West Area.

Code: 600-355 **Classification:** Accepted

Names: 600-355; Non-Operational Property Evaluation Zone 1, Ridgeline West of Army Loop Road **Reclassification:** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The elevated area is known as a mound or a ridgeline. Miscellaneous debris is visible at several locations along the ridgeline. Visible debris includes paint cans, tar, transite and hydraulic fuel cans.

Location: The waste site is located south of Route 11A and west of Army Loop Road.

Code: 600-356 **Classification:** Accepted

Names: 600-356; Non-Operational Area Zone 2; Tar Deposit West of Susie Junction **Reclassification:** Final Closed Out (10/28/2015)

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The waste site has been remediated, Interim Closed Out and later Final Closed Out. It contained two areas of pebbles and rocks with visible concentrations of dark, tar material. One area was originally described as a large tar deposit measuring approximately 18 meters by 11 meters. A smaller area of tar, measuring approximately 0.3 meters by 1 meter, was located southeast of the large area. Eventually the total affected area was defined as 1624 square meters (17,481 sq. ft.).

Location: The areas were located west of the railroad junction known as Susie Junction. The center point coordinates of the large area are N140640.7 E566609.9.

Closure Info: Interim (5/20/2014): (Interim Closed Out) Remediation of the 600-356 waste site was performed between July 9 and December 12, 2013. Approximately 3,600 bank cubic meters (4,709 cubic yards) of rock, gravel, and dirt were removed from the 600-356 waste site and disposed at the Environmental Restoration Disposal Facility. The maximum depth of the excavation was approximately 3.6 meters (12.0 ft). No anomalies were encountered during remediation.

Final (10/28/2015): (Final Closed Out) Based upon evaluation of the previous reclassification data against the 100-F/IU Area ROD cleanup levels, no further RTD is required for any of the 26 waste sites (Listed below).

600-279, Vegetation-Free Area Between White Bluffs and 100-F

600-293, White Bluffs Service Station #1
 600-294, White Bluffs Service Station #2
 600-298, Stained Soil and Surface Debris
 600-299, Surface Debris/Batteries
 600-300, Miscellaneous Surface Debris
 600-301, White Bluffs Sanitary Sewer Pipelines
 600-303, Vertical Pipes
 600-316, Dry Cell Batteries
 600-318, Wet Cell Batteries
 600-320, Oil Stains
 600-321, Suspect ACM Sites
 600-328, Lead Slag
 600-356, Tar Deposit West of Susie Junction
 600-368, Segment 4 Stained Soil #1
 600-369, Segment 4 Bare Ground and Crusted Soil Areas
 600-370, Segment 4 Debris Area #1
 600-371, Segment 4 Chalky Material Area
 600-372, Segment 4 Oil Stain and Filter Area #1
 600-373, Segment 4 Bare Ground and White Stain Area
 600-374, Segment 4 Drum Remnant Area
 600-375, Segment 4 Dry Cell Battery Debris Area #1
 600-376, Segment 4 Stained Soil Area #2
 600-377, Segment 4 Oil Stain and Filter Area #2
 600-378, 506 Telephone Exchange Emergency Generator Building Underground Fuel Storage tank
 600-379, Segment 4 Burn Area #1.

The Reclassification to Final Closed Out applies to all subsites associated with the waste sites listed above.

Code: 600-357 **Classification:** Not Accepted
Names: 600-357; Geophysical Testing Pit #2 near 618-10 **Reclassification:** None
Type: Experiment/Test Site **Start Date:**
Status: Inactive **End Date:**

Description: PNNL constructed a geophysical test bed near 618-10 in 1981. The test bed was constructed by excavating the ground to form a depression approximately 61 m (200 ft) long by 15 m (50 ft) wide. The depression was filled to grade with the excavated soils after the targets were buried in the test bed. The surface remained indistinguishable from the surrounding terrain except for the lack of vegetation.

Location: The test bed is approximately 200 meters northeast of the 618-10 burial ground.

Process Description: Forty-four targets were buried at the PNNL Test Bed. They included steel and plastic pipes (with varying diameters and wall thicknesses), empty 55 gallon drums, finned objects, projectiles of various dimensions, aluminum boxes, aluminum cylinders, spheres (Styrofoam and aluminum), a wood box, a steel box, a brass rod and a conductivity probe. Geophysical testing using various instrumentation was performed at the test bed between 1981 and 1984.

Code: 600-358 **Classification:** Accepted
Names: 600-358; Scattered Waste Areas in the Vicinity of the Gable Mountain Firing Range **Reclassification:** Final Closed Out (9/1/2015)

Type: Dumping Area**Start Date:****Status:** Inactive**End Date:**

Description: The site was remediated and reclassified to Final Closed Out. It consisted of scattered debris identified during the unexploded ordinance (UXO) characterization and the remediation of the 600-149:1 waste site. The debris included pieces of munitions and ordinances, tear gas containers, glass bottles, a lead battery, a lead chunk, a burn area, a suspect drum. A 380 meter (1250 ft) long asbestos pipe and piles of asbestos pipe that had been previously removed were also identified. In October 2011, the asbestos pipeline and staging pile areas were determined to be Miscellaneous Restoration items.

Location: The site was located north of the east end of Gable Mountain near the Rifle and Pistol Range.

Related Sites/ Structures: The site is associated with the 661 Rifle and Pistol Range and waste site 600-149.

Closure Info: Final (9/1/2015): Remedial action at the 600-358 waste site began on July 14, 2014, with removal of soil and debris from the burn pit area. On July 29, 2014, a drum was removed from an area approximately 275 meters (902 ft) south of the burn pit area. Following remediation, a composite soil sample was collected from the drum area excavation to determine if residual contamination remained after the drum and underlying soil were removed. Only trace analyses of herbicide were found. Remediation continued at the burn pit area with excavation and sorting/screening of soil and debris. Once the material was screened to remove potential munitions and explosives of concern (MEC), the waste soil and debris were stockpiled alongside the excavation awaiting loadout and disposal at the Environmental Restoration Disposal Facility (ERDF). The 600-358 waste site remediation depth ranges from 2 to 3 meters (6.6 to 9.8 ft) below ground surface, resulting in approximately 2,300 bank cubic meters (3,008 bank cubic yards) of soil and debris being removed and disposed at ERDF. The remediation and final loadout of waste material was completed on March 17, 2015.

Debris encountered during remediation at the 600-358 waste site included glass, wood, steel, animal bones, asbestos, MEC items, unspent bullets, spent bullet casings, metal badges, bottles, plates, and silverware. Several anomalous items were encountered during remediation and included multiple tear gas vials and glass bottles. One tear gas vial ruptured releasing its contents to the soil where it was staged. An in-process soil sample was collected on August 14, 2014, of the stained soil from below where the vial was located when it ruptured. The soil was removed and disposed at ERDF. All remaining tear gas vials that were found during remediation were broken and mixed with soil for disposal. The glass bottles were inspected and two were found to contain liquid.

Twenty-five pieces of MEC and approximately 22.7 kg (50 lb) of energetic material were also removed from the 600-358 waste site. All items were removed from the site by the Yakima Firing Range 53rd EOD unit for offsite detonation.

Code: 600-359**Classification:** Accepted**Names:** 600-359; Non-Operational Property Evaluation
Zone 2, Location 1 Debris and Distressed
Vegetation**Reclassification:** None**Type:** Dumping Area**Start Date:****Status:** Inactive**End Date:**

Description: During a Non-operation Property Evaluation walkdown, several rubber shoe covers were identified laying on the ground surface, adjacent to a railroad track. Some evidence of

mechanical disturbance was also noted near the shoe covers. A devegetated area, measuring approximately 200 feet by 100 feet, was found. Stained soil, measuring approximately 10 feet by 10 feet, was identified near the railroad switch box.

Location: The area is located approximately 700 meters north of Route 11A and approximately 3000 meters west of Route 4N.

Process Description: Rubber shoe covers have a potential of being contaminated.

Code: 600-360	Classification: Accepted
Names: 600-360; Non-Operational Property Evaluation Zone 2, Location 2 Debris Sites	Reclassification: None
Type: Dumping Area	Start Date:
Status: Inactive	End Date:

Description: During field walkdowns several areas of debris were identified. Debris included cans, drums, wood and a 35 gallon cylinder tank. Some areas of devegetation were also noted.

Location: The area is approximately 1000 meters west of the intersection of Route 11A and Route 4 North. The majority of the area is on the north side of Route 11A, but a portion extends to the south side of Route 11A.

Code: 600-361	Classification: Accepted
Names: 600-361; Non-Operational Property Evaluation Zone 2, Location 3 Debris	Reclassification: None
Type: Dumping Area	Start Date:
Status: Inactive	End Date:

Description: During a site walkdown, a considerable amount of debris was identified. The debris included rubber shoe covers, wood, metal cans, drums aerosol cans, oil filters and electrical parts. A mound of asphalt, measuring approximately 300 feet by 150 feet was also noted. A 30 foot diameter area contained stained soil and stressed vegetation.

Location: The area is located about 500 meters north of the intersection of Route 11A and Route 4N. The majority of the area is located on the west side of Route 4N, but a portion is located on the east side of Route 4N.

Code: 600-362	Classification: Accepted
Names: 600-362; Non-Operational Property Evaluation Zone 2, Location 4 Debris and Anomalies	Reclassification: None
Type: Dumping Area	Start Date:
Status: Inactive	End Date:

Description: Nine items were identified on the east side of Route 4N, near waste site 600-282. A tar area was estimated to cover approximately 0.01 acres of ground. An irregularly shaped area of distressed vegetation and the remains of a wooden building covered an area measuring approximately 0.06 acres. A small area of stressed vegetation and two oil filters were noted. A depression resembling a trench was identified. The vegetation within the trench was different than the

surrounding vegetation. The trench measures approximately 0.04 acres. An area of stressed vegetation, measuring approximately 10 by 10 feet, was noted. An area encompassing approximately 1.5 acres was identified that appeared to have been mechanically disturbed. It contained mounds of soil, distressed vegetation and a pit containing a trash can and tumbleweeds. Another mechanically disturbed area was identified near waste site 600-40. It includes a mound that resembles a loading ramp. A pit was found southwest of the 600-40 site. The pit measured approximately 16.8 meters (55 feet) by 12.2 meters (40 feet). The pit contains aged lumber and a tar-like substance.

Location: The majority of the area is located on the east side of Route 4N. A portion of the area is located on the west side of Route 4N. It is approximately 2500 meters north of the intersection of Route 4 N and Route 11A.

Code: 600-363 **Classification:** Accepted

Names: 600-363; Non-Operational Property Evaluation Zone 2, Location 5 Debris; Walkdown Area 7 **Reclassification:** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: An area measuring approximately 30 by 30 feet was identified that contains a significant amount of surface debris. The debris includes lumber, roofing material transite, solidified tar and asphalt.

Location: The area is located approximately 1400 meters north of Route 11A and 2000 meters west of Route 2N.

Code: 600-364 **Classification:** Accepted

Names: 600-364; Non-Operational Property Evaluation Zone 2, Location 6, Electrical Parts Debris, Area 24 **Reclassification:** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The site encompasses approximately 15 acres. The majority of the debris is related to discarded electrical parts, such as fuses, light bulb tips and foam insulation.

Location: The site is located approximately 1.8 miles east of the intersection of Route 2N and Route 11A and approximately 800 meters south of Route 11A.

Code: 600-365 **Classification:** Accepted

Names: 600-365; Non-Operational Area Zone 2 Debris Landfill adjacent to 600-228, H-40 Anti-Aircraft Gun Site debris **Reclassification:** None

Type: Dumping Area **Start Date:**

Status: Inactive **End Date:**

Description: The waste site appears to be a small landfill or dumping area. Old glass bottles and cans were visible.

Location: This site is located southeast of the 200 East Area, on the south side of Route 4 South. The dumping area is located southeast of the H-40 Anti-Aircraft Gun Site.

Related Sites/ Structures: The debris is associated with the H-40 Anti-Aircraft Gun Site.

Code: 600-366 **Classification:** Not Accepted

Names: 600-366; PNNL Geophysical Test Site West of 300 Area **Reclassification:** None

Type: Experiment/Test Site **Start Date:**

Status: Inactive **End Date:**

Description: This feature consists of a subsurface feature containing nine buried inert objects ranging from near surface to 4.2 meters below ground surface and two acoustic boreholes.

Location: The waste site is located approximately 873 meters west of 300 Area (Rt 4S and Cypress Ave) on the west side of Stevens Drive. It is near the 600-22 UFO Landing Site area.

Process Description: The site was used to test metal detectors on a variety of metal targets with a wide range of shapes and sizes.

Code: 600-367 **Classification:** Accepted

Names: 600-367; Burial Pit near the Geotechnical Engineering and Development Facility (Little Egypt) **Reclassification:** Final Closed Out (8/28/2015)

Type: Burial Ground **Start Date:**

Status: Inactive **End Date:**

Description: The site was remediated and reclassified to Final Closed Out. It was a pit where a trailer and some equipment was buried. The trailer and equipment had burned during a wildfire. The fire occurred during the 1980's. The material was buried one to two meters below the ground surface.

Location: The pit was located approximately 100 meters (328 feet) north of the Hanford Geotechnical Engineering and Development Cold Test Facility (aka Little Egypt), near the test facility access road.

Related Sites/ Structures: The waste site is associated with 600-276 (the Geotechnical Engineering and Development Facility).

Process Description: The pit was excavated to bury the remains of the equipment and trailer that were destroyed during a Hanford Site range fire in the 1980's. The equipment and temporary trailer were being used in support of the Geotechnical Engineering and Development Facility (sitecode 600-276), that became operational in 1982 to support the development of technology for disposal of low-level radioactive wastes. The site use was to test burial ground subsidence control alternatives, including cold test demonstrations of geotechnical engineering prototype systems for in-situ isolation and stabilization of waste disposal structures.

Closure Info: Final (8/28/2015): A geophysical survey was performed at the 600-367 waste site location in February 2011. Remedial action at the 600-367 waste site began on January 23 and continued through February 2, 2015. The remediation extended to an estimated maximum depth of 2.6 meters (8.5 ft) below ground surface resulting in 810 bank cubic meters (1,059 bank cubic

yards) of contaminated soil and debris being removed and disposed at ERDF. The debris consisted of a metal trailer frame, plastic, fiberglass insulation, three empty drums, and an empty 19 liter (5-gal) bucket. An empty compressed gas cylinder was recycled. One anomaly, a blue granular material, was found during remediation. It was sampled on February 20, 2015 and found copper and lead that exceeded direct exposure cleanup levels.

All waste material was direct loaded from the excavation into ERDF cans for disposal. No waste staging pile area was created. No overburden material was salvaged.

Code:	600-368	Classification:	Accepted
Names:	600-368; Segment 4 Stained Soil #1	Reclassification	Final Closed Out (10/28/2015)
Type:	Unplanned Release	Start Date:	
Status:	Inactive	End Date:	
Description:	The site has been remediated, Interim Closed Out and later Final Closed Out. It consisted of a 15 square meter (157 square feet) area covered with green granules.		
Location:	The site was located 20 meters (66 ft) north of Route 1 and 440 meters (1,444 ft) west of Route 2 North at E579763.92/N145328.32. The feature was approximately 130 meters (427 ft) west of the Leazer rail spur.		
Process Description:	In 1944, temporary construction buildings were housed in this area. The area included several warehouses, the crane operators' loft, the riggers' loft and an ice house storage pit (C-3316, HAN-10970 Volume 2, pp. 347, 492 and 520). The Leazer Rail Spur was also known as the Pierce Siding (H-7-618). The Salvage/Scrap Yard (also described as being at Leazer Spur) was a kilometer south of the warehouses and operated as late as December 1948 (HW-12086, p. 192). It is not known what if any relationship existed between the two complexes.		
Closure Info:	Interim (12/18/2013): (Interim Closed Out) Remediation of the 600-368 waste site occurred on March 28, 2013, and resulted in approximately 54 bank cubic meters (71 bank cubic yards) of soil and debris being removed for disposal at the Environmental Restoration Disposal Facility (ERDF). Remediation of the 600-369 waste site (including eight subsites) was performed from March 28 through May 6, 2013. Approximately 3,969 bank cubic meters (5,191 bank cubic yards) of excavated materials from the 600-369 waste site were removed and direct loaded for disposal at ERDF. The approximate depth of the 600-368 and 600-369 excavations is 0.5 to 1 meters (1.5 to 3.3 ft) below ground surface. All material removed from the 600-368 and 600-369 (and subsites) was direct loaded for disposal at ERDF. No soil staging pile areas or overburden areas were utilized.		
	Tree stumps and other farmstead debris indicated that the 600-369:4 had been located within a former farmstead orchard area.		
	Final (10/28/2015): (Final Closed Out) Based upon evaluation of the previous reclassification data against the 100-F/IU Area ROD cleanup levels, no further RTD is required for any of the 26 waste sites (Listed below).		
	600-279, Vegetation-Free Area Between White Bluffs and 100-F		
	600-293, White Bluffs Service Station #1		
	600-294, White Bluffs Service Station #2		
	600-298, Stained Soil and Surface Debris		
	600-299, Surface Debris/Batteries		
	600-300, Miscellaneous Surface Debris		
	600-301, White Bluffs Sanitary Sewer Pipelines		
	600-303, Vertical Pipes		

600-316, Dry Cell Batteries
600-318, Wet Cell Batteries
600-320, Oil Stains
600-321, Suspect ACM Sites
600-328, Lead Slag
600-356, Tar Deposit West of Susie Junction
600-368, Segment 4 Stained Soil #1
600-369, Segment 4 Bare Ground and Crusted Soil Areas
600-370, Segment 4 Debris Area #1
600-371, Segment 4 Chalky Material Area
600-372, Segment 4 Oil Stain and Filter Area #1
600-373, Segment 4 Bare Ground and White Stain Area
600-374, Segment 4 Drum Remnant Area
600-375, Segment 4 Dry Cell Battery Debris Area #1
600-376, Segment 4 Stained Soil Area #2
600-377, Segment 4 Oil Stain and Filter Area #2
600-378, 506 Telephone Exchange Emergency Generator Building Underground Fuel Storage tank
600-379, Segment 4 Burn Area #1.

The Reclassification to Final Closed Out applies to all subsites associated with the waste sites listed above.

Code: 600-369	Classification: Accepted
Names: 600-369; Segment 4 Bare Ground and Crusted Soil Areas	Reclassification: Final Closed Out (10/28/2015)
Type: Dumping Area	Start Date:
Status: Inactive	End Date:

Description: The parent site and all eight subsites have been remediated, Interim Closed Out and later Final Closed Out. It consisted of eight areas near the Leazer Spur that were devoid of vegetation. The site was divided into eight subsites as follows:

600-369:1, Segment 4 Bare Ground and Crusted Soil Area 1
600-369:2, Segment 4 Bare Ground and Crusted Soil Area 2
600-369:3, Segment 4 Bare Ground and Crusted Soil Area 3
600-369:4, Segment 4 Bare Ground and Crusted Soil Area 4
600-369:5, Segment 4 Bare Ground and Crusted Soil Area 5
600-369:6, Segment 4 Bare Ground and Crusted Soil Area 6
600-369:7, Segment 4 Bare Ground and Crusted Soil Area 7
600-369:8, Segment 4 Bare Ground and Crusted Soil Area 8

Location: The 600-369 site was located on both sides of Route 1, west of Route 2 North.

600-369:1, Segment 4 Bare Ground and Crusted Soil Area 1 was located at E579937.3, N145487.63
600-369:2, Segment 4 Bare Ground and Crusted Soil Area 2 was located at E579803.50, N145380.74
600-369:3, Segment 4 Bare Ground and Crusted Soil Area 3 was located at E579812.38, N145204.89
600-369:4, Segment 4 Bare Ground and Crusted Soil Area 4 was located at E579736.30, N145178.74
600-369:5, Segment 4 Bare Ground and Crusted Soil Area 5 was located at E579952.40,

N145351.86
 600-369:6, Segment 4 Bare Ground and Crusted Soil Area 6 was located at E579633.55,
 N145336.17
 600-369:7, Segment 4 Bare Ground and Crusted Soil Area 7 was located at E579895.23,
 N145368.72
 600-369:8, Segment 4 Bare Ground and Crusted Soil Area 8 was located at E579698.99,
 N145413.13

Process Description: In 1944, temporary construction buildings were located in this area. The buildings included various warehouses, the crane operators' loft, the riggers' loft and an ice house storage pit (C-3316, HAN-10970 Volume 2, pp. 347, 492 and 520). The Leazer Rail Spur was also known as the Pierce Siding (H-7-618). The Salvage/Scrap Yard (also described as being at Leazer Spur) was a kilometer south of the warehouses and operated as late as December 1948 (HW-12086, p. 192). It is not known what if any relationship existed between the two complexes.

Closure Info: Interim (12/18/2013): (Interim Closed Out) Remediation of the 600-368 waste site occurred on March 28, 2013, and resulted in approximately 54 bank cubic meters (71 bank cubic yards) of soil and debris being removed for disposal at the Environmental Restoration Disposal Facility (ERDF). Remediation of the 600-369 waste site (including eight subsites) was performed from March 28 through May 6, 2013. Approximately 3,969 bank cubic meters (5,191 bank cubic yards) of excavated materials from the 600-369 waste site were removed and direct loaded for disposal at ERDF. The approximate depth of the 600-368 and 600-369 excavations is 0.5 to 1 meters (1.5 to 3.3 ft) below ground surface. All material removed from the 600-368 and 600-369 (and subsites) was direct loaded for disposal at ERDF. No soil staging pile areas or overburden areas were utilized.

Tree stumps and other farmstead debris indicated that the 600-369:4 had been located within a former farmstead orchard area.

Final (10/28/2015): (Final Closed Out) Based upon evaluation of the previous reclassification data against the 100-F/IU Area ROD cleanup levels, no further RTD is required for any of the 26 waste sites (Listed below).

600-279, Vegetation-Free Area Between White Bluffs and 100-F
 600-293, White Bluffs Service Station #1
 600-294, White Bluffs Service Station #2
 600-298, Stained Soil and Surface Debris
 600-299, Surface Debris/Batteries
 600-300, Miscellaneous Surface Debris
 600-301, White Bluffs Sanitary Sewer Pipelines
 600-303, Vertical Pipes
 600-316, Dry Cell Batteries
 600-318, Wet Cell Batteries
 600-320, Oil Stains
 600-321, Suspect ACM Sites
 600-328, Lead Slag
 600-356, Tar Deposit West of Susie Junction
 600-368, Segment 4 Stained Soil #1
 600-369, Segment 4 Bare Ground and Crusted Soil Areas
 600-370, Segment 4 Debris Area #1
 600-371, Segment 4 Chalky Material Area
 600-372, Segment 4 Oil Stain and Filter Area #1
 600-373, Segment 4 Bare Ground and White Stain Area
 600-374, Segment 4 Drum Remnant Area
 600-375, Segment 4 Dry Cell Battery Debris Area #1

600-376, Segment 4 Stained Soil Area #2
600-377, Segment 4 Oil Stain and Filter Area #2
600-378, 506 Telephone Exchange Emergency Generator Building Underground Fuel Storage tank
600-379, Segment 4 Burn Area #1.

The Reclassification to Final Closed Out applies to all subsites associated with the waste sites listed above.

This Site has the Following SubSites:

Code: 600-369:1
Names: 600-369:1; Segment 4 Bare Ground and Crusted Soil Area 1

Code: 600-369:2
Names: 600-369:2; Segment 4 Bare Ground and Crusted Soil Area 2

Code: 600-369:3
Names: 600-369:3; Segment 4 Bare Ground and Crusted Soil Area 3

Code: 600-369:4
Names: 600-369:4; Segment 4 Bare Ground and Crusted Soil Area 4

Code: 600-369:5
Names: 600-369:5; Segment 4 Bare Ground and Crusted Soil Area 5

Code: 600-369:6
Names: 600-369:6; Segment 4 Bare Ground and Crusted Soil Area 6

Code: 600-369:7
Names: 600-369:7; Segment 4 Bare Ground and Crusted Soil Area 7

Code: 600-369:8
Names: 600-369:8; Segment 4 Bare Ground and Crusted Soil Area 8

Code: 600-369:1 **Classification:** Accepted
Names: 600-369:1; Segment 4 Bare Ground and Crusted Soil Area 1 **Reclassification** Final Closed Out (10/28/2015)
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The subsite consisted of a 6 meter (20 ft) diameter area burn pit.

Location: The site is located 190 meters (623 ft) north of Route 1 and 147 m (482 ft) west of Route 2 North.

The SubSite is Part Of:

Code: 600-369
Names: 600-369; Segment 4 Bare Ground and Crusted Soil Areas

Code: 600-369:2 **Classification:** Accepted
Names: 600-369:2; Segment 4 Bare Ground and Crusted Soil Area 2 **Reclassification** Final Closed Out (10/28/2015)
Type: Dumping Area **Start Date:**

Status: Inactive

End Date:

Description: The subsite consisted of a 3 meter (10 ft) diameter area devoid of vegetation.

Location: The site was located 87 meters (285 ft) north of Route 1 and 360 m (1181 ft) west of Route 2 North.

The SubSite is Part Of:

Code: 600-369

Names: 600-369; Segment 4 Bare Ground and Crusted Soil Areas

Code: 600-369:3

Classification: Accepted

Names: 600-369:3; Segment 4 Bare Ground and Crusted Soil Area 3

Reclassification Final Closed Out (10/28/2015)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The subsite consisted of a large area with multiple spots of stressed vegetation and bare earth.

Location: The site was located 89 meters (292 ft) south of Route 1 and 505 m (1657 ft) west of Route 2 North.

The SubSite is Part Of:

Code: 600-369

Names: 600-369; Segment 4 Bare Ground and Crusted Soil Areas

Code: 600-369:4

Classification: Accepted

Names: 600-369:4; Segment 4 Bare Ground and Crusted Soil Area 4

Reclassification Final Closed Out (10/28/2015)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The subsite consisted of a 14 meter (46 ft) area with multiple spots of bare ground. It was also within a pre-Hanford farmstead area.

Location: The site was located 107 meters (351 ft) south of Route 1 and 607 meters (1992 ft) west of Route 2 North.

The SubSite is Part Of:

Code: 600-369

Names: 600-369; Segment 4 Bare Ground and Crusted Soil Areas

Code: 600-369:5

Classification: Accepted

Names: 600-369:5; Segment 4 Bare Ground and Crusted Soil Area 5

Reclassification Final Closed Out (10/28/2015)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The subsites consisted of a 50 meter (164 ft) diameter area with multiple spots of bare ground.

Location: The site was located 52 meters (171 ft) north of Route 1 and 241 meters (791 ft) west of Route 2 North.

The SubSite is Part Of:

Code: 600-369

Names: 600-369; Segment 4 Bare Ground and Crusted Soil Areas

Code: 600-369:6

Classification: Accepted

Names: 600-369:6; Segment 4 Bare Ground and Crusted Soil Area 6

Reclassification: Final Closed Out (10/28/2015)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The subsite consisted of a 11 meter (36 ft) area of crusted soil with no vegetation visible.

Location: The site was located 44 meters (144 ft) north of Route 1 and 567 meters (1860 ft) west of Route 2 North.

The SubSite is Part Of:

Code: 600-369

Names: 600-369; Segment 4 Bare Ground and Crusted Soil Areas

Code: 600-369:7

Classification: Accepted

Names: 600-369:7; Segment 4 Bare Ground and Crusted Soil Area 7

Reclassification: Final Closed Out (10/28/2015)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The subsite consisted of a 2 meter (7 ft) diameter area of red crusted soil devoid of vegetation.

Location: The site was located 73 meters (240 ft) north of Route 1 and 277 meters (909 ft) west of Route 2 North.

The SubSite is Part Of:

Code: 600-369

Names: 600-369; Segment 4 Bare Ground and Crusted Soil Areas

Code: 600-369:8

Classification: Accepted

Names: 600-369:8; Segment 4 Bare Ground and Crusted Soil Area 8

Reclassification: Final Closed Out (10/28/2015)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The subsite consisted of a 10 meter (33 ft) diameter area of stressed vegetation and 6 drum lids.

Location: The site is located 118 meters (387 ft) north of Route 1 and 440 meters (1444 ft) west of Route 2 North.

Process There is no process history associated with this subsite.
Description:

The SubSite is Part Of:

Code: 600-369
Names: 600-369; Segment 4 Bare Ground and Crusted Soil Areas

Code: 600-370 **Classification:** Accepted
Names: 600-370; Segment 4 Debris Area #1 **Reclassification** Final Closed Out (10/28/2015)
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: This site has been remediated, Interim Closed Out and later Final Closed Out. It consisted of a large disturbed area with surface debris consisting of multiple burn sites with burn remnants, transite, insulators, wood and concrete.

Location: The site was located 237 meters (778 ft) south of Route 1 and 2.7 km (1.7 miles) west of Route 2 North, at coordinates E577743.13 N145009.07.

Closure Info: Interim (12/18/2013): (Interim Closed Out) Remediation of the 600-370 waste site was performed from May 8 through July 9, 2013. One anomaly was discovered and staged outside of the excavation area. Investigation of the anomaly with the subsequent removal and disposal of the waste site underlying soil was performed on September 9, 2013. Approximately 4,853 bank cubic meters (6,347 bank cubic yards) of material was excavated, removed and direct loaded for disposal at the Environmental Restoration Disposal Facility (ERDF). The 600-370 waste site excavation area is approximately 7,369 square meters (79,319 sq. ft), with the approximate excavation depth of 0.3 to 1.5 meters (1 to 5 ft) below ground surface. No soil staging pile area or overburden areas were utilized.

During the 600-370 waste site excavation, an anomaly was discovered at WSP coordinates N145012.2/E577720.4. It was staged outside of the excavated area for further investigation. The anomaly consisted of a 5 centimeter (2 in.) diameter by 46 centimeter (18 in.) long steel pipe (Schedule 40) with caps on both ends and mounting brackets. The pipe appeared to be sealed with no other fittings or openings. During the anomaly investigation, the anomaly was remotely sheared and found to be empty. The anomaly was disposed at ERDF with an additional 0.3 meter (1 ft) of underlying soil from the anomaly staging location.

Final (10/28/2015): (Final Closed Out) Based upon evaluation of the previous reclassification data against the 100-F/IU Area ROD cleanup levels, no further RTD is required for any of the 26 waste sites (Listed below).

600-279, Vegetation-Free Area Between White Bluffs and 100-F
600-293, White Bluffs Service Station #1
600-294, White Bluffs Service Station #2
600-298, Stained Soil and Surface Debris
600-299, Surface Debris/Batteries
600-300, Miscellaneous Surface Debris
600-301, White Bluffs Sanitary Sewer Pipelines
600-303, Vertical Pipes
600-316, Dry Cell Batteries
600-318, Wet Cell Batteries
600-320, Oil Stains

600-321, Suspect ACM Sites
600-328, Lead Slag
600-356, Tar Deposit West of Susie Junction
600-368, Segment 4 Stained Soil #1
600-369, Segment 4 Bare Ground and Crusted Soil Areas
600-370, Segment 4 Debris Area #1
600-371, Segment 4 Chalky Material Area
600-372, Segment 4 Oil Stain and Filter Area #1
600-373, Segment 4 Bare Ground and White Stain Area
600-374, Segment 4 Drum Remnant Area
600-375, Segment 4 Dry Cell Battery Debris Area #1
600-376, Segment 4 Stained Soil Area #2
600-377, Segment 4 Oil Stain and Filter Area #2
600-378, 506 Telephone Exchange Emergency Generator Building Underground Fuel Storage tank
600-379, Segment 4 Burn Area #1.

The Reclassification to Final Closed Out applies to all subsites associated with the waste sites listed above.

Code: 600-371	Classification: Accepted
Names: 600-371; Segment 4 Chalky Material Area	Reclassification: Final Closed Out (10/28/2015)
Type: Dumping Area	Start Date:
Status: Inactive	End Date:

Description: This site has been remediated, Interim Closed Out and later Final Closed Out. It consisted of multiple locations within a 4.6 meter (15 ft.) diameter area of a white chalky substance that resembled either grout or bentonite.

Location: The site was located 1.4 km (0.9 miles) east of H Avenue and 240 meters (787 feet) west of the Columbia River, at coordinates E579060.73 N150280.

Process Description: There is no process history associated with the 600-371 waste site.

Closure Info: Interim (12/18/2013): (Interim Closed Out) Remediation of the 600-371 waste site occurred on July 17 and 18, 2013, and resulted in approximately 97.5 bank cubic meters (127.5 bank cubic yards) of soil and debris being removed for disposal at the Environmental Restoration Disposal Facility. Waste materials included white chalky substance from the surface of the waste site and the underlying soil. All waste site materials were direct loaded, and no soil staging pile area or overburden areas were utilized. The waste site was excavated to an approximate depth of 0.6 meters (2 ft).

Final (10/28/2015): (Final Closed Out) Based upon evaluation of the previous reclassification data against the 100-F/IU Area ROD cleanup levels, no further RTD is required for any of the 26 waste sites (Listed below).

600-279, Vegetation-Free Area Between White Bluffs and 100-F
600-293, White Bluffs Service Station #1
600-294, White Bluffs Service Station #2
600-298, Stained Soil and Surface Debris
600-299, Surface Debris/Batteries
600-300, Miscellaneous Surface Debris

600-301, White Bluffs Sanitary Sewer Pipelines
 600-303, Vertical Pipes
 600-316, Dry Cell Batteries
 600-318, Wet Cell Batteries
 600-320, Oil Stains
 600-321, Suspect ACM Sites
 600-328, Lead Slag
 600-356, Tar Deposit West of Susie Junction
 600-368, Segment 4 Stained Soil #1
 600-369, Segment 4 Bare Ground and Crusted Soil Areas
 600-370, Segment 4 Debris Area #1
 600-371, Segment 4 Chalky Material Area
 600-372, Segment 4 Oil Stain and Filter Area #1
 600-373, Segment 4 Bare Ground and White Stain Area
 600-374, Segment 4 Drum Remnant Area
 600-375, Segment 4 Dry Cell Battery Debris Area #1
 600-376, Segment 4 Stained Soil Area #2
 600-377, Segment 4 Oil Stain and Filter Area #2
 600-378, 506 Telephone Exchange Emergency Generator Building Underground Fuel Storage tank
 600-379, Segment 4 Burn Area #1.

The Reclassification to Final Closed Out applies to all subsites associated with the waste sites listed above.

Code: 600-372	Classification: Accepted
Names: 600-372; Segment 4 Oil Stains and Filter Areas	Reclassification: Final Closed Out (10/28/2015)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:
Description:	The 600-372 waste site and its subsites have been remediated, Interim Closed Out and later Final Closed Out. It consisted of two areas that have a discarded oil filter and are devoid of vegetation. The site had been divided into two subsites, 600-372:1, Segment 4 Oil Stain and Filter Area #1a, and 600-372:2, Segment 4 Oil Stain and Filter Area #1b. The parent and subsites were reclassified together on the same forms.
Location:	The site was located northeast of the intersection of Route 2N and H Avenue. 600-372:1, E578666.74, N150323.91 600-372:2, E578082.80, N578082.80
Process Description:	There is no process history associated with the 600-372 waste site.
Closure Info:	Interim (12/18/2013): (Interim Closed Out) Remediation of the 600-372 waste site occurred on July 18 and September 10 and 11, 2013 resulting in approximately 26 bank cubic meters (34 bank cubic yards) of soil and debris being removed for disposal at the Environmental Restoration Disposal Facility (ERDF). Waste materials included oil filters and the underlying stained soil. All waste site materials were direct loaded, and no soil staging pile area or overburden areas were utilized. The waste site was excavated to an approximate depth of 0.6 meters (2 ft). Final (10/28/2015): (Final Closed Out) Based upon evaluation of the previous reclassification data against the 100-F/IU Area ROD cleanup levels, no further RTD is required for any of the

26 waste sites (Listed below).

600-279, Vegetation-Free Area Between White Bluffs and 100-F
 600-293, White Bluffs Service Station #1
 600-294, White Bluffs Service Station #2
 600-298, Stained Soil and Surface Debris
 600-299, Surface Debris/Batteries
 600-300, Miscellaneous Surface Debris
 600-301, White Bluffs Sanitary Sewer Pipelines
 600-303, Vertical Pipes
 600-316, Dry Cell Batteries
 600-318, Wet Cell Batteries
 600-320, Oil Stains
 600-321, Suspect ACM Sites
 600-328, Lead Slag
 600-356, Tar Deposit West of Susie Junction
 600-368, Segment 4 Stained Soil #1
 600-369, Segment 4 Bare Ground and Crusted Soil Areas
 600-370, Segment 4 Debris Area #1
 600-371, Segment 4 Chalky Material Area
 600-372, Segment 4 Oil Stain and Filter Area #1
 600-373, Segment 4 Bare Ground and White Stain Area
 600-374, Segment 4 Drum Remnant Area
 600-375, Segment 4 Dry Cell Battery Debris Area #1
 600-376, Segment 4 Stained Soil Area #2
 600-377, Segment 4 Oil Stain and Filter Area #2
 600-378, 506 Telephone Exchange Emergency Generator Building Underground Fuel Storage tank
 600-379, Segment 4 Burn Area #1.

The Reclassification to Final Closed Out applies to all subsites associated with the waste sites listed above.

This Site has the Following SubSites:

Code: 600-372:1

Names: 600-372:1; Segment 4 Oil Stain and Filter Area #1a

Code: 600-372:2

Names: 600-372:2; Segment 4 Oil Stain and Filter Area #1b

Code: 600-372:1

Classification: Accepted

Names: 600-372:1; Segment 4 Oil Stain and Filter Area #1a

Reclassification: Final Closed Out (10/28/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The subsite consisted of a 3 sq. meter. (4 sq. yd) area of discarded oil filter. It was devoid of vegetation.

Location: The site was located 3 km (1.8 miles) north of Route 2N and 1 km (0.6 miles) east of H Avenue at coordinates E578666.74, N150323.91.

Process Description: There is no process history associated with this subsite.

Closure Info: Interim (12/18/2013): (Interim Closed Out) Remediation of the 600-372 waste site occurred on July 18 and September 10 and 11, 2013 resulting in approximately 26 bank cubic meters (34 bank cubic yards) of soil and debris being removed for disposal at the Environmental Restoration Disposal Facility (ERDF). Waste materials included oil filters and the underlying stained soil. All waste site materials were direct loaded, and no soil staging pile area or overburden areas were utilized. The waste site was excavated to an approximate depth of 0.6 meters (2 ft).

The SubSite is Part Of:

Code: 600-372

Names: 600-372; Segment 4 Oil Stains and Filter Areas

Code: 600-372:2

Classification: Accepted

Names: 600-372:2; Segment 4 Oil Stain and Filter Area #1b

Reclassification Final Closed Out (10/28/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: Subsite 2 consisted of a 13 sq. meter. (15 sq. yd) area of discarded oil filter that was devoid of vegetation.

Location: The site was located 2.2 km (1.4 miles) north of Route 2N and 0.4 km (0.26 miles) east of H Avenue at coordinates E578082.80, N578082.80.

Process There is no process history associated with this subsite.

Description:

Closure Info: Interim (12/18/2013): (Interim Closed Out) Remediation of the 600-372 waste site occurred on July 18 and September 10 and 11, 2013 resulting in approximately 26 bank cubic meters (34 bank cubic yards) of soil and debris being removed for disposal at the Environmental Restoration Disposal Facility (ERDF). Waste materials included oil filters and the underlying stained soil. All waste site materials were direct loaded, and no soil staging pile area or overburden areas were utilized. The waste site was excavated to an approximate depth of 0.6 meters (2 ft).

The SubSite is Part Of:

Code: 600-372

Names: 600-372; Segment 4 Oil Stains and Filter Areas

Code: 600-373

Classification: Accepted

Names: 600-373; Segment 4 Bare Ground and White Stain Area

Reclassification Final Closed Out (10/28/2015)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: This site has been remediated, Interim Closed Out and later Final Closed Out. It consisted of a 28 square meter (303 square feet) area devoid of vegetation and covered by a white stain and crusted soil/glass debris.

Location: The site was located 2.8 km (1.7 miles) north of Route 2 N and 0.76 km (0.47 miles) east of H Avenue, at E578471.14, N150388.87.

Process There is no process history associated with the 600-373 waste site.

Description:

Closure Info: Interim (1/16/2014): (Interim Closed Out) Remediation of the 600-373 waste site occurred on July 18 and September 9 and 10, 2013, and resulted in approximately 41.3 bank cubic meters (BCM) (54.0 bank cubic yards [BCY]) of soil and debris being removed for disposal at the Environmental Restoration Disposal Facility (ERDF). The approximate depth of the 600-373 excavation is 0.3 to 0.9 meter (1 to 3 ft) below ground surface (bgs).

Remediation of the 600-374 waste site was performed on September 18, 2013, and resulted in approximately 7.5 BCM (9.8 BCY) of soil and debris being removed for disposal at ERDF. The approximate depth of the 600-374 excavation is 0.3 to 0.5 meter (1 to 1.5 ft) bgs. All material removed from the waste sites was direct loaded for disposal at ERDF and no soil staging pile areas or overburden areas were utilized.

The 600-373 waste site is within a known orchard area where historical orchard lead-arsenate applications had occurred. In accordance with the Tri-Party Agreement Change Notice TPA-CN-401 (DOE-RL 2010), dated December 6, 2010, lead and arsenic are conditionally excluded as COPCs for sites demonstrated to have been located within orchard areas.

Final (10/28/2015): (Final Closed Out) Based upon evaluation of the previous reclassification data against the 100-F/IU Area ROD cleanup levels, no further RTD is required for any of the 26 waste sites (Listed below).

600-279, Vegetation-Free Area Between White Bluffs and 100-F
 600-293, White Bluffs Service Station #1
 600-294, White Bluffs Service Station #2
 600-298, Stained Soil and Surface Debris
 600-299, Surface Debris/Batteries
 600-300, Miscellaneous Surface Debris
 600-301, White Bluffs Sanitary Sewer Pipelines
 600-303, Vertical Pipes
 600-316, Dry Cell Batteries
 600-318, Wet Cell Batteries
 600-320, Oil Stains
 600-321, Suspect ACM Sites
 600-328, Lead Slag
 600-356, Tar Deposit West of Susie Junction
 600-368, Segment 4 Stained Soil #1
 600-369, Segment 4 Bare Ground and Crusted Soil Areas
 600-370, Segment 4 Debris Area #1
 600-371, Segment 4 Chalky Material Area
 600-372, Segment 4 Oil Stain and Filter Area #1
 600-373, Segment 4 Bare Ground and White Stain Area
 600-374, Segment 4 Drum Remnant Area
 600-375, Segment 4 Dry Cell Battery Debris Area #1
 600-376, Segment 4 Stained Soil Area #2
 600-377, Segment 4 Oil Stain and Filter Area #2
 600-378, 506 Telephone Exchange Emergency Generator Building Underground Fuel Storage tank
 600-379, Segment 4 Burn Area #1.

The Reclassification to Final Closed Out applies to all subsites associated with the waste sites listed above.

Code: 600-374 **Classification:** Accepted
Names: 600-374; Segment 4 Drum Remnant Area **Reclassification:** Final Closed Out (10/28/2015)
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: This site has been remediated, Interim Closed Out, and later Final Closed Out. It consisted of an empty 55 gallon drum (crushed) surrounded by a small area devoid of vegetation.

Location: The site was located approximately 1.6 km (1 mile) northwest of the intersection of Route 2 North and H Avenue. The drum is located at coordinates E576207.11 N150290.57.

Process Description: There is no process history associated with the 600-374 waste site.

Closure Info: Interim (1/16/2014): (Interim Closed Out) Remediation of the 600-373 waste site occurred on July 18 and September 9 and 10, 2013, and resulted in approximately 41.3 bank cubic meters (BCM) (54.0 bank cubic yards [BCY]) of soil and debris being removed for disposal at the Environmental Restoration Disposal Facility (ERDF). The approximate depth of the 600-373 excavation is 0.3 to 0.9 meter (1 to 3 ft) below ground surface (bgs).

Remediation of the 600-374 waste site was performed on September 18, 2013, and resulted in approximately 7.5 BCM (9.8 BCY) of soil and debris being removed for disposal at ERDF. The approximate depth of the 600-374 excavation is 0.3 to 0.5 meter (1 to 1.5 ft) bgs. All material removed from the waste sites was direct loaded for disposal at ERDF and no soil staging pile areas or overburden areas were utilized.

The 600-373 waste site is within a known orchard area where historical orchard lead-arsenate applications had occurred. In accordance with the Tri-Party Agreement Change Notice TPA-CN-401 (DOE-RL 2010), dated December 6, 2010, lead and arsenic are conditionally excluded as COPCs for sites demonstrated to have been located within orchard areas.

Final (10/28/2015): (Final Closed Out) Based upon evaluation of the previous reclassification data against the 100-F/IU Area ROD cleanup levels, no further RTD is required for any of the 26 waste sites (Listed below).

600-279, Vegetation-Free Area Between White Bluffs and 100-F
600-293, White Bluffs Service Station #1
600-294, White Bluffs Service Station #2
600-298, Stained Soil and Surface Debris
600-299, Surface Debris/Batteries
600-300, Miscellaneous Surface Debris
600-301, White Bluffs Sanitary Sewer Pipelines
600-303, Vertical Pipes
600-316, Dry Cell Batteries
600-318, Wet Cell Batteries
600-320, Oil Stains
600-321, Suspect ACM Sites
600-328, Lead Slag
600-356, Tar Deposit West of Susie Junction
600-368, Segment 4 Stained Soil #1
600-369, Segment 4 Bare Ground and Crusted Soil Areas
600-370, Segment 4 Debris Area #1
600-371, Segment 4 Chalky Material Area
600-372, Segment 4 Oil Stain and Filter Area #1

600-373, Segment 4 Bare Ground and White Stain Area
 600-374, Segment 4 Drum Remnant Area
 600-375, Segment 4 Dry Cell Battery Debris Area #1
 600-376, Segment 4 Stained Soil Area #2
 600-377, Segment 4 Oil Stain and Filter Area #2
 600-378, 506 Telephone Exchange Emergency Generator Building Underground Fuel Storage tank
 600-379, Segment 4 Burn Area #1.

The Reclassification to Final Closed Out applies to all subsites associated with the waste sites listed above.

Code: 600-375	Classification: Accepted
Names: 600-375; Segment 4 Dry Cell Battery Debris Area #1	Reclassification: Final Closed Out (10/28/2015)
Type: Dumping Area	Start Date:
Status: Inactive	End Date:

Description: The 600-375 parent site and subsites have been sampled, Interim Closed Out and later Final Closed Out. The five subsites were evaluated and reclassified to Interim Closed Out on the same reclassification form (form # 2013-092).

The site was originally divided into five subsites as follows:

600-375:1, Segment 4 Dry Cell Battery Debris Area #1a
 600-375:2, Segment 4 Dry Cell Battery Debris Area #1b
 600-375:3, Segment 4 Dry Cell Battery Debris Area #1c
 600-375:4, Segment 4 Dry Cell Battery Debris Area #1d
 600-375:5, Segment 4 Dry Cell Battery Debris Area #1e

Location: The areas were located in Segment 4 west and north of the Central Shops Area (White Bluffs Community). The center point coordinates are:

600-375:1, Segment 4 Dry Cell Battery Debris Area #1a, E577208.71/N150162.85
 600-375:2, Segment 4 Dry Cell Battery Debris Area #1b, E576718.36/N148913.05
 600-375:3, Segment 4 Dry Cell Battery Debris Area #1c, E576955.64/N147365.45
 600-375:4, Segment 4 Dry Cell Battery Debris Area #1d, E576263.76/N147106.86
 600-375:5, Segment 4 Dry Cell Battery Debris Area #1e, E576156.50/N148489.60

Process Description: There is no process history associated with the 600-375 waste site.

Closure Info: Interim (4/17/2014): (Interim Closed Out) The five locations consisting, of dry cell battery debris and stained soil, were evaluated and reclassified on the same reclassification form (form # 2013-092). The 600-375 waste site was recommended for remediation without confirmatory sampling based on the visual observed presence of stained soil and battery debris.

Remediation of the 600-375 waste site was performed from August 8 through October 29, 2013. Approximately 125 bank cubic meters (163 bank cubic yards) of excavated materials from the 600-375 waste site were removed and direct loaded for disposal at the Environmental Restoration Disposal Facility. The approximate depths of the excavations range from 0.3 meters (1.0 ft) to 0.7 meters (2.3 ft) below ground surface. No waste staging pile area or overburden soil stockpiles are associated with the 600-375 waste site. With the exception of the 600-375:1

subsite, a walk around boundary survey was conducted at the 600-375 subsites following the site remediation activities. Because the size of the 600-375:1 site after remediation was small, no walk around boundary survey was conducted.

Final (10/28/2015): (Final Closed Out) Based upon evaluation of the previous reclassification data against the 100-F/IU Area ROD cleanup levels, no further RTD is required for any of the 26 waste sites (Listed below).

600-279, Vegetation-Free Area Between White Bluffs and 100-F
 600-293, White Bluffs Service Station #1
 600-294, White Bluffs Service Station #2
 600-298, Stained Soil and Surface Debris
 600-299, Surface Debris/Batteries
 600-300, Miscellaneous Surface Debris
 600-301, White Bluffs Sanitary Sewer Pipelines
 600-303, Vertical Pipes
 600-316, Dry Cell Batteries
 600-318, Wet Cell Batteries
 600-320, Oil Stains
 600-321, Suspect ACM Sites
 600-328, Lead Slag
 600-356, Tar Deposit West of Susie Junction
 600-368, Segment 4 Stained Soil #1
 600-369, Segment 4 Bare Ground and Crusted Soil Areas
 600-370, Segment 4 Debris Area #1
 600-371, Segment 4 Chalky Material Area
 600-372, Segment 4 Oil Stain and Filter Area #1
 600-373, Segment 4 Bare Ground and White Stain Area
 600-374, Segment 4 Drum Remnant Area
 600-375, Segment 4 Dry Cell Battery Debris Area #1
 600-376, Segment 4 Stained Soil Area #2
 600-377, Segment 4 Oil Stain and Filter Area #2
 600-378, 506 Telephone Exchange Emergency Generator Building Underground Fuel Storage tank
 600-379, Segment 4 Burn Area #1.

The Reclassification to Final Closed Out applies to all subsites associated with the waste sites listed above.

This Site has the Following SubSites:

Code: 600-375:1
Names: 600-375:1; Segment 4 Dry Cell Battery Debris Area #1a

Code: 600-375:2
Names: 600-375:2; Segment 4 Dry Cell Battery Debris Area #1b

Code: 600-375:3
Names: 600-375:3; Segment 4 Dry Cell Battery Debris Area #1c

Code: 600-375:4
Names: 600-375:4; Segment 4 Dry Cell Battery Debris Area #1d

Code: 600-375:5
Names: 600-375:5; Segment 4 Dry Cell Battery Debris Area #1e

Code: 600-375:1 **Classification:** Accepted
Names: 600-375:1; Segment 4 Dry Cell Battery Debris Area #1a **Reclassification** Final Closed Out (10/28/2015)
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: This subsite consisted of debris from four dry cell batteries in a 3 square meter (33 square feet) area.

Location: The site was located 1.4 km (0.85 miles) north of Route 2 North and 460 m (0.3 miles) west of H Avenue at coordinates E577208.71 N150162.85.

Process Description: There is no process history associated with this subsite.

Closure Info: Interim (4/17/2014): (Interim Closed Out) The five locations consisting, of dry cell battery debris and stained soil, were evaluated and reclassified on the same reclassification form (form # 2013-092). The 600-375 waste site was recommended for remediation without confirmatory sampling based on the visual observed presence of stained soil and battery debris.

Remediation of the 600-375 waste site was performed from August 8 through October 29, 2013. Approximately 125 bank cubic meters (163 bank cubic yards) of excavated materials from the 600-375 waste site were removed and direct loaded for disposal at the Environmental Restoration Disposal Facility. The approximate depths of the excavations range from 0.3 meters (1.0 ft) to 0.7 meters (2.3 ft) below ground surface. No waste staging pile area or overburden soil stockpiles are associated with the 600-375 waste site. With the exception of the 600-375:1 subsite, a walk around boundary survey was conducted at the 600-375 subsites following the site remediation activities. Because the size of the 600-375:1 site after remediation was small, no walk around boundary survey was conducted.

The SubSite is Part Of:

Code: 600-375
Names: 600-375; Segment 4 Dry Cell Battery Debris Area #1

Code: 600-375:2 **Classification:** Accepted
Names: 600-375:2; Segment 4 Dry Cell Battery Debris Area #1b **Reclassification** Final Closed Out (10/28/2015)
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: This subsite consisted of a 1 meter (3 foot) diameter stained area from dry cell batteries.

Location: The site was located 119 m (390 feet) south of Route 2 North and 1.3 km (0.8 miles) west of H Avenue at coordinates E576718.36 N148913.05.

Process Description: There is no process history associated with this subsite.

Closure Info: Interim (4/17/2014): (Interim Closed Out) The five locations consisting, of dry cell battery debris and stained soil, were evaluated and reclassified on the same reclassification form (form # 2013-092). The 600-375 waste site was recommended for remediation without confirmatory sampling based on the visual observed presence of stained soil and battery debris.

Remediation of the 600-375 waste site was performed from August 8 through October 29, 2013. Approximately 125 bank cubic meters (163 bank cubic yards) of excavated materials from the 600-375 waste site were removed and direct loaded for disposal at the Environmental Restoration Disposal Facility. The approximate depths of the excavations range from 0.3 meters (1.0 ft) to 0.7 meters (2.3 ft) below ground surface. No waste staging pile area or overburden soil stockpiles are associated with the 600-375 waste site. With the exception of the 600-375:1 subsite, a walk around boundary survey was conducted at the 600-375 subsites following the site remediation activities. Because the size of the 600-375:1 site after remediation was small, no walk around boundary survey was conducted.

The SubSite is Part Of:

Code: 600-375

Names: 600-375; Segment 4 Dry Cell Battery Debris Area #1

Code: 600-375:3

Classification: Accepted

Names: 600-375:3; Segment 4 Dry Cell Battery Debris Area #1c

Reclassification Final Closed Out (10/28/2015)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: This subsite consisted of a 390 square meter (0.1 acre) area that has scattered battery debris and stained soils within a pre-Hanford homestead.

Location: The site was located 2.1 km (1.3 miles) north of Route 1 and 1.8 km (1.1 miles) west of Route 2 North at coordinates E576955.64 N147365.45.

Process There is no process history associated with this subsite.

Description:

Closure Info: Interim (4/17/2014): (Interim Closed Out) The five locations consisting, of dry cell battery debris and stained soil, were evaluated and reclassified on the same reclassification form (form # 2013-092). The 600-375 waste site was recommended for remediation without confirmatory sampling based on the visual observed presence of stained soil and battery debris.

Remediation of the 600-375 waste site was performed from August 8 through October 29, 2013. Approximately 125 bank cubic meters (163 bank cubic yards) of excavated materials from the 600-375 waste site were removed and direct loaded for disposal at the Environmental Restoration Disposal Facility. The approximate depths of the excavations range from 0.3 meters (1.0 ft) to 0.7 meters (2.3 ft) below ground surface. No waste staging pile area or overburden soil stockpiles are associated with the 600-375 waste site. With the exception of the 600-375:1 subsite, a walk around boundary survey was conducted at the 600-375 subsites following the site remediation activities. Because the size of the 600-375:1 site after remediation was small, no walk around boundary survey was conducted.

The SubSite is Part Of:

Code: 600-375

Names: 600-375; Segment 4 Dry Cell Battery Debris Area #1

Code: 600-375:4

Classification: Accepted

Names: 600-375:4; Segment 4 Dry Cell Battery Debris Area #1d

Reclassification Final Closed Out (10/28/2015)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: This subsite consisted of debris from dry cell batteries in two locations with stained soils.

Location: The site was located 1.9 km (1.2 miles) north of Route 1 and 2.7 km (1.7 miles) west of Route 2 North at coordinates E576263.76 N147106.86.

Process Description: There is no process history associated with this subsite.

Closure Info: Interim (4/17/2014): (Interim Closed Out) The five locations consisting, of dry cell battery debris and stained soil, were evaluated and reclassified on the same reclassification form (form # 2013-092). The 600-375 waste site was recommended for remediation without confirmatory sampling based on the visual observed presence of stained soil and battery debris.

Remediation of the 600-375 waste site was performed from August 8 through October 29, 2013. Approximately 125 bank cubic meters (163 bank cubic yards) of excavated materials from the 600-375 waste site were removed and direct loaded for disposal at the Environmental Restoration Disposal Facility. The approximate depths of the excavations range from 0.3 meters (1.0 ft) to 0.7 meters (2.3 ft) below ground surface. No waste staging pile area or overburden soil stockpiles are associated with the 600-375 waste site. With the exception of the 600-375:1 subsite, a walk around boundary survey was conducted at the 600-375 subsites following the site remediation activities. Because the size of the 600-375:1 site after remediation was small, no walk around boundary survey was conducted.

The SubSite is Part Of:

Code: 600-375

Names: 600-375; Segment 4 Dry Cell Battery Debris Area #1

Code: 600-375:5

Classification: Accepted

Names: 600-375:5; Segment 4 Dry Cell Battery Debris Area #1e

Reclassification: Final Closed Out (10/28/2015)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: This subsite consisted of small area with battery debris and stained soil.

Location: The site was located 3.2 kilometers (2.0 miles) north of Route 1 and 1.3 km (0.8 miles) west of Route 2 North at coordinates E576156.50 N148489.60.

Process Description: There is no process history associated with this subsite.

Closure Info: Interim (4/17/2014): (Interim Closed Out) The five locations consisting, of dry cell battery debris and stained soil, were evaluated and reclassified on the same reclassification form (form # 2013-092). The 600-375 waste site was recommended for remediation without confirmatory sampling based on the visual observed presence of stained soil and battery debris.

Remediation of the 600-375 waste site was performed from August 8 through October 29, 2013. Approximately 125 bank cubic meters (163 bank cubic yards) of excavated materials from the 600-375 waste site were removed and direct loaded for disposal at the Environmental Restoration Disposal Facility. The approximate depths of the excavations range from 0.3 meters (1.0 ft) to 0.7 meters (2.3 ft) below ground surface. No waste staging pile area or overburden soil stockpiles are associated with the 600-375 waste site. With the exception of the 600-375:1

subsite, a walk around boundary survey was conducted at the 600-375 subsites following the site remediation activities. Because the size of the 600-375:1 site after remediation was small, no walk around boundary survey was conducted.

The SubSite is Part Of:

Code: 600-375

Names: 600-375; Segment 4 Dry Cell Battery Debris Area #1

Code: 600-376

Classification: Accepted

Names: 600-376; Segment 4 Stained Soil Area #2

Reclassification: Final Closed Out (10/28/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The parent site and subsites have been remediated, Interim Closed Out and later Final Closed Out. It consisted of two stained soil areas and two patches of bare ground with a black material covering the ground. A glass jar (probable food container) with unknown material, and dried yellow material was also present. The site had been divided into two subsites -600-376:1, Segment 4 Stained Soil Area #2a and 600-376:2, Segment 4 Stained Soil Area #2b. Both subsites were Interim Closed Out on Waste Site Reclassification Form 2013-093.

Location: The subsites were located NNW of the intersection of Route 2N and H Avenue.

600-376:1, E575916.56, N150178.99

600-376:2, E576272.73, N149545.31

Process Description: There is no process history associated with the 600-376 waste site.

Closure Info: Interim (1/16/2014): (Interim Closed Out) Waste site characterization samples were collected at the 600-376 subsites in January 2013. Based on observations during the field walkdowns to support remedial action, it was determined that the 600-376 subsites required remediation. Remediation of the two 600-376 subsites occurred between September 16 and 23, 2013. The final excavation depth for the 600-376:1 subsite was 0.6 meters (2.0 ft). The final excavation depth for the 600-376:2 subsite was 1 meter (3.3 ft). A total of approximately 101 bank cubic meters (132 bank cubic yards) of material was removed and disposed to the Environmental Restoration Disposal Facility (ERDF). Removal of stained soil from the 600-376:1 subsite and of surface debris and waste material from the 600-376:2 subsite required excavations beyond the originally mapped WIDS site boundaries.

Final (10/28/2015): (Final Closed Out) Based upon evaluation of the previous reclassification data against the 100-F/IU Area ROD cleanup levels, no further RTD is required for any of the 26 waste sites (Listed below).

600-279, Vegetation-Free Area Between White Bluffs and 100-F

600-293, White Bluffs Service Station #1

600-294, White Bluffs Service Station #2

600-298, Stained Soil and Surface Debris

600-299, Surface Debris/Batteries

600-300, Miscellaneous Surface Debris

600-301, White Bluffs Sanitary Sewer Pipelines

600-303, Vertical Pipes

600-316, Dry Cell Batteries

600-318, Wet Cell Batteries

600-320, Oil Stains
 600-321, Suspect ACM Sites
 600-328, Lead Slag
 600-356, Tar Deposit West of Susie Junction
 600-368, Segment 4 Stained Soil #1
 600-369, Segment 4 Bare Ground and Crusted Soil Areas
 600-370, Segment 4 Debris Area #1
 600-371, Segment 4 Chalky Material Area
 600-372, Segment 4 Oil Stain and Filter Area #1
 600-373, Segment 4 Bare Ground and White Stain Area
 600-374, Segment 4 Drum Remnant Area
 600-375, Segment 4 Dry Cell Battery Debris Area #1
 600-376, Segment 4 Stained Soil Area #2
 600-377, Segment 4 Oil Stain and Filter Area #2
 600-378, 506 Telephone Exchange Emergency Generator Building Underground Fuel Storage tank
 600-379, Segment 4 Burn Area #1.

The Reclassification to Final Closed Out applies to all subsites associated with the waste sites listed above.

This Site has the Following SubSites:

Code: 600-376:1

Names: 600-376:1; Segment 4 Stained Soil Area #2a

Code: 600-376:2

Names: 600-376:2; Segment 4 Stained Soil Area #2b

Code: 600-376:1

Classification: Accepted

Names: 600-376:1; Segment 4 Stained Soil Area #2a

Reclassification: Final Closed Out (10/28/2015)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The subsite consisted of two stained soil areas adjacent to the railroad tracks leading to the 100-H Area.

Location: The site was located 200 meters (653 ft) north of Route 2 North and 1.75 km (1.1 miles) west of H Avenue at coordinates E575916.56 N150178.99.

Process Description: There is no process history associated with this subsite.

Closure Info: Interim (1/16/2014): (Interim Closed Out) Waste site characterization samples were collected at the 600-376 subsites in January 2013. Based on observations during the field walkdowns to support remedial action, it was determined that the 600-376 subsites required remediation. Remediation of the two 600-376 subsites occurred between September 16 and 23, 2013. The final excavation depth for the 600-376:1 subsite was 0.6 meters (2.0 ft). The final excavation depth for the 600-376:2 subsite was 1 meter (3.3 ft). A total of approximately 101 bank cubic meters (132 bank cubic yards) of material was removed and disposed to the Environmental Restoration Disposal Facility (ERDF). Removal of stained soil from the 600-376:1 subsite and of surface debris and waste material from the 600-376:2 subsite required excavations beyond the originally mapped WIDS site boundaries.

The SubSite is Part Of:

Code: 600-376
Names: 600-376; Segment 4 Stained Soil Area #2

Code: 600-376:2 **Classification:** Accepted
Names: 600-376:2; Segment 4 Stained Soil Area #2b **Reclassification** Final Closed Out (10/28/2015)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The subsite consisted of two patches of bare ground covered with debris including black material, a glass jar (probable food container) with unknown material, and dried yellow material.

Location: The site was located 4.3 km (2.7 miles) north of Route 1 and 122 m (400 feet) west of Route 2 North at coordinates E576272.73 N149545.31.

Process There is no process history associated with this subsite.

Description:

Closure Info: Interim (1/16/2014): (Interim Closed Out) Waste site characterization samples were collected at the 600-376 subsites in January 2013. Based on observations during the field walkdowns to support remedial action, it was determined that the 600-376 subsites required remediation. Remediation of the two 600-376 subsites occurred between September 16 and 23, 2013. The final excavation depth for the 600-376:1 subsite was 0.6 meters (2.0 ft). The final excavation depth for the 600-376:2 subsite was 1 meter (3.3 ft). A total of approximately 101 bank cubic meters (132 bank cubic yards) of material was removed and disposed to the Environmental Restoration Disposal Facility (ERDF). Removal of stained soil from the 600-376:1 subsite and of surface debris and waste material from the 600-376:2 subsite required excavations beyond the originally mapped WIDS site boundaries.

The SubSite is Part Of:

Code: 600-376
Names: 600-376; Segment 4 Stained Soil Area #2

Code: 600-377 **Classification:** Accepted
Names: 600-377; Segment 4 Oil Stain and Filter Area #2 **Reclassification** Final Closed Out (10/28/2015)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The site was remediated, Interim Closed Out and later Final Closed Out. It consisted of a 3 square meter (32 square feet) area devoid of vegetation and containing multiple oil filters, burned debris and stained soil.

Location: The site was located 3 kilometers (1.9 miles) south of Route 1 and 97 meters (318 ft) east of Route 4 North. The area was located between Route 4N and the west end of Gable Mountain.

Process There is no process history associated with the 600-377 waste site.

Description:

Closure Info: Interim (5/13/2014): (Interim Closed Out) Remediation of the 600-377 waste site was performed on December 16, 2013. No anomalies were discovered during excavation. A total of approximately 2.64 bank cubic meters (3.45 bank cubic yards) of material was removed and direct loaded for disposal at the Environmental Restoration Disposal Facility. No overburden soil was stockpiled to be used as backfill. The 600-377 waste site excavation area is

approximately 8 square meters (86 sq ft), with the approximate depth of 0.30 meter (1 ft) below ground surface. All excavated materials were direct loaded, and no soil staging pile area or overburden areas were utilized.

Final (10/28/2015): (Final Closed Out) Based upon evaluation of the previous reclassification data against the 100-F/IU Area ROD cleanup levels, no further RTD is required for any of the 26 waste sites (Listed below).

600-279, Vegetation-Free Area Between White Bluffs and 100-F
 600-293, White Bluffs Service Station #1
 600-294, White Bluffs Service Station #2
 600-298, Stained Soil and Surface Debris
 600-299, Surface Debris/Batteries
 600-300, Miscellaneous Surface Debris
 600-301, White Bluffs Sanitary Sewer Pipelines
 600-303, Vertical Pipes
 600-316, Dry Cell Batteries
 600-318, Wet Cell Batteries
 600-320, Oil Stains
 600-321, Suspect ACM Sites
 600-328, Lead Slag
 600-356, Tar Deposit West of Susie Junction
 600-368, Segment 4 Stained Soil #1
 600-369, Segment 4 Bare Ground and Crusted Soil Areas
 600-370, Segment 4 Debris Area #1
 600-371, Segment 4 Chalky Material Area
 600-372, Segment 4 Oil Stain and Filter Area #1
 600-373, Segment 4 Bare Ground and White Stain Area
 600-374, Segment 4 Drum Remnant Area
 600-375, Segment 4 Dry Cell Battery Debris Area #1
 600-376, Segment 4 Stained Soil Area #2
 600-377, Segment 4 Oil Stain and Filter Area #2
 600-378, 506 Telephone Exchange Emergency Generator Building Underground Fuel Storage tank
 600-379, Segment 4 Burn Area #1.

The Reclassification to Final Closed Out applies to all subsites associated with the waste sites listed above.

Code: 600-378	Classification: Accepted
Names: 600-378; 506 Telephone Exchange Emergency Generator Building Underground Fuel Storage Tank	Reclassification: Final Closed Out (10/28/2015)
Type: Storage Tank	Start Date:
Status: Inactive	End Date:
Description: The waste site has been remediated, Interim Closed Out and later Final Closed Out. It was a 379 liter (100 gal) underground storage tank used to store fuel for the 506 Telephone Exchange emergency generator building (also known as the 508 bldg).	
Location: The 506, 507 and 508 buildings were located on the south side of Route 11A. A ground penetrating radar scan found a feature resembling a fuel tank at coordinates E581237.93 N138768.82. The fuel tank was located on the west side of the 508 building.	

Process Description: The 506 B-Y Telephone Exchange was constructed in 1945. It handled the call switching between the inner and outer areas. It also housed the 50 line Hanford exchange and served as the primary base of operations for telephone maintenance personnel in support of the 100 and 200 Areas (GEH-26434-400). The 508 Building provided emergency power to support the 506 B-Y Telephone Exchange Building in the event of a power outage. The adjacent 507 building was used for storage, minor equipment repair and maintenance tasks.

Closure Info: Interim (7/28/2014): (Interim Closed Out) Remediation of the 600-378 waste site began on December 18, 2013. The 379 liter (100 gal) underground fuel tank was discovered 0.46 meters (1.5 ft) below ground surface. The tank was completely empty and positioned sideways as shown on drawing H-5-548. Remediation continued on January 8, 2014, to remove and dispose the underground fuel tank and underlying soil. While removing the fuel tank, it was noted that the valve attached to the tank was broken off. After removing the tank from the excavation and loading it for disposal a dark black stain was observed below the tank. It was determined that the black staining under the fuel tank was the result of the dust-suppression water applied to the inside of the tank. Two pipeline segments that connected to the fuel tank were also removed for disposal.

A 0.6 meter (2 ft) long, 2 inch diameter galvanized steel (Schedule 40) pipeline was observed buried beside the fuel tank. It was a fill pipe that connected to the top of the fuel tank. A copper 3/8 inch diameter pipeline that trended east and connected to the generator structure was also found within the excavation. Concrete debris was uncovered on the east side of the excavation, consistent with the location of the 508 Emergency Generator Building. Some burned debris including burned wood debris was found at 0.9 meters (3 ft) below ground surface, on the northwest side of the excavation. The burned material was only partially removed because it is not associated with the 600-378 fuel tank.

Verification sampling performed on February 25, 2014, indicated that benzo(a)pyrene was above the direct exposure cleanup criteria at sample location FS-3. Additional remediation was performed on April 30, 2014, to remove contaminated material from the excavation. The entire 600-378 excavation was re-excavated. Remediation of the 600-378 waste site resulted in a total excavation of approximately 43.5 BCM (56.8 BCY) of contaminated soil and debris that was direct loaded for disposal at ERDF. No overburden soil was stockpiled to be used as backfill.

Final (10/28/2015): (Final Closed Out) Based upon evaluation of the previous reclassification data against the 100-F/IU Area ROD cleanup levels, no further RTD is required for any of the 26 waste sites (Listed below).

600-279, Vegetation-Free Area Between White Bluffs and 100-F
 600-293, White Bluffs Service Station #1
 600-294, White Bluffs Service Station #2
 600-298, Stained Soil and Surface Debris
 600-299, Surface Debris/Batteries
 600-300, Miscellaneous Surface Debris
 600-301, White Bluffs Sanitary Sewer Pipelines
 600-303, Vertical Pipes
 600-316, Dry Cell Batteries
 600-318, Wet Cell Batteries
 600-320, Oil Stains
 600-321, Suspect ACM Sites
 600-328, Lead Slag
 600-356, Tar Deposit West of Susie Junction
 600-368, Segment 4 Stained Soil #1
 600-369, Segment 4 Bare Ground and Crusted Soil Areas
 600-370, Segment 4 Debris Area #1

600-371, Segment 4 Chalky Material Area
 600-372, Segment 4 Oil Stain and Filter Area #1
 600-373, Segment 4 Bare Ground and White Stain Area
 600-374, Segment 4 Drum Remnant Area
 600-375, Segment 4 Dry Cell Battery Debris Area #1
 600-376, Segment 4 Stained Soil Area #2
 600-377, Segment 4 Oil Stain and Filter Area #2
 600-378, 506 Telephone Exchange Emergency Generator Building Underground Fuel Storage tank
 600-379, Segment 4 Burn Area #1.

The Reclassification to Final Closed Out applies to all subsites associated with the waste sites listed above.

Code: 600-379	Classification: Accepted
Names: 600-379; Segment 4 Burn Area #1	Reclassification: Final Closed Out (10/28/2015)
Type: Dumping Area	Start Date:
Status: Inactive	End Date:

Description: The site was remediated, Interim Closed Out and later Final Closed Out. It consisted of a burn area with visible remnants.

Location: The site was located 1.2 Kilometers (0.75 miles) north of Route 11 and 5.7 Kilometers (3.5 miles) west of Route 2 North. It was also located 648 meters (2,126 ft) southwest of the 213-J & K Storage Facility.

Process Description: There is no process history associated with the 600-379 waste site.

Closure Info: Interim (5/7/2014): (Interim Closed Out) The 600-379 waste site was recommended for remediation without confirmatory sampling due to possible contamination based upon extensive debris and evidence of burning.

Remediation of the 600-379 waste site was performed from December 18, 2013, through January 8, 2014. No anomalies were encountered during the remediation. The excavation in the remediated area was approximately 70 square meters (768 sq. ft.) and 0.6 meters (2 ft) below ground surface. A total of approximately 43 bank cubic meters (56 bank cubic yards) of material was removed and direct loaded for disposal at the Environmental Restoration Disposal Facility. No waste staging pile area or overburden soil stockpiles are associated with the 600-379 waste site. A walk around boundary survey was conducted at the 600-379 waste site following site remediation.

Final (10/28/2015): (Final Closed Out) Based upon evaluation of the previous reclassification data against the 100-F/IU Area ROD cleanup levels, no further RTD is required for any of the 26 waste sites (Listed below).

600-279, Vegetation-Free Area Between White Bluffs and 100-F
 600-293, White Bluffs Service Station #1
 600-294, White Bluffs Service Station #2
 600-298, Stained Soil and Surface Debris
 600-299, Surface Debris/Batteries
 600-300, Miscellaneous Surface Debris
 600-301, White Bluffs Sanitary Sewer Pipelines

600-303, Vertical Pipes
 600-316, Dry Cell Batteries
 600-318, Wet Cell Batteries
 600-320, Oil Stains
 600-321, Suspect ACM Sites
 600-328, Lead Slag
 600-356, Tar Deposit West of Susie Junction
 600-368, Segment 4 Stained Soil #1
 600-369, Segment 4 Bare Ground and Crusted Soil Areas
 600-370, Segment 4 Debris Area #1
 600-371, Segment 4 Chalky Material Area
 600-372, Segment 4 Oil Stain and Filter Area #1
 600-373, Segment 4 Bare Ground and White Stain Area
 600-374, Segment 4 Drum Remnant Area
 600-375, Segment 4 Dry Cell Battery Debris Area #1
 600-376, Segment 4 Stained Soil Area #2
 600-377, Segment 4 Oil Stain and Filter Area #2
 600-378, 506 Telephone Exchange Emergency Generator Building Underground Fuel Storage tank
 600-379, Segment 4 Burn Area #1.

The Reclassification to Final Closed Out applies to all subsites associated with the waste sites listed above.

Code: 600-380	Classification: Accepted
Names: 600-380; Segment 4 Unknown Cylinder	Reclassification: Interim Closed Out (2/25/2014)
Type: Dumping Area	Start Date:
Status: Inactive	End Date:

Description: The waste site has been remediated and Interim Closed Out. It consisted of a cylinder with unknown contents, located 20 meters (64 ft) from a maintained gravel road.

Location: This site is located approximately 0.96 km (0.60 miles) west of the intersection of H Avenue and the 100-H perimeter road at coordinates E576701.265 N151747.148.

Process Description: There is no process history associated with the 600-380 waste site.

Closure Info: Interim (2/25/2014): On October 7, 2013, field investigation of the cylinder was conducted. Significant corrosion of the cylinder's exterior indicated that the cylinder had been abandoned for many years. Markings on the cylinder indicated that it formerly contained hydrogen sulfide gas and the cylinder manufacture date was July 1924. The latest legible hydrostatic test date marked on the cylinder was August 1945, but partial markings of a test date in 1950 were also present. Further field investigation on October 10, 2013, determined that the cylinder valve was open and the cylinder was empty. The cylinder was removed for disposal at the ERDF on October 24, 2013.

The 600-380 cylinder was a surface feature that did not require subsurface remedial action. Assuming hydrostatic testing occurred in 1950, the cylinder would have been out of service by 1955 as the testing is required every five years. The only contaminant of potential concern for the site would be sulfate. However, given the cylinder would have been out of service by 1955 and was found open and empty during field investigation, it is highly unlikely than any sulfate contamination would be present on the surface soil. Therefore, it is proposed the 600-380 waste

site be reclassified to Interim Closed Out without verification sampling based on removal and disposal of the cylinder.

Code: 600-381 **Classification:** Accepted
Names: 600-381; Segment 4 Underground Structure with **Reclassification** Interim No Action (12/3/2013)
 Wooden Air Vents Feature
Type: Depression/Pit (nonspecific) **Start Date:**
Status: Inactive **End Date:**

Description: The waste site has been evaluated and determined to require No Action. It consists of two wooden air vents covered with screening protruding from the ground. This feature is a discovery site because of the possibility of a void under ground space of unknown size.

Location: The site is located 0.8 kilometers (0.5 miles) south of the Columbia River and 1.3 km (0.8 miles) west of Hadley Loop (H-Area perimeter road) at coordinates E575918.008 N153563.985.

Process Description: There is no process history associated with the 600-381 waste site. The waste site was within 100 meters (328 ft) of a known pre-Hanford farm.

Closure Info: Interim (12/3/2013): A geophysical survey, done in October 2011, did not indicate any void space. An anomaly was detected 2 meters (6 feet) south of the air vents.

Test Pit 1 was excavated in June 2013. Wood and cobbles were noted. A pipeline was found 0.6 meters (2 ft) below the surface. Test Pit 2 was placed where the GPR scan identified the anomaly. Nothing, other than the pipeline, was found in Test Pit 2. The pipeline was metal and approximately 1.5 meters (5 feet) long. Samples were collected from the test pits. The pipe and cobbles were returned to the excavation and the two test pits were backfilled to grade.

Code: 600-382 **Classification:** Accepted
Names: 600-382; Segment 4 Oil Stains and Filter Area #3 **Reclassification** Interim Closed Out (8/20/2014)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The waste site, including all of the subsites, was remediated and Interim Closed Out. The 600-382 waste site consisted of five locations of discarded oil filters and ground staining devoid of vegetation. The site had been divided into five subsites. The parent site and all of the subsites were reclassified in a single document and a single Reclassification form (2014-026).

The subsites were 600-382:1, Segment 4 Oil Stain and Filter Area #3a, 600-382:2, Segment 4 Oil Stain and Filter Area #3b, 600-382:3, Segment 4 Oil Stain and Filter Area #3c, 600-382:4, Segment 4 Oil Stain and Filter Area #3d, 600-382:5, Segment 4 Oil Stain and Filter Area #3e.

Location: The subsites were located between the 100-D Area and the railroad tracks that lead to the 100-H Area.

600-382:1, E576315.892, N150679.753
 600-382:2, E576286.206, N150613.712
 600-382:3, E575923.366, N150876.064
 600-382:4, E576231.571, N151788.478
 600-382:5, E574850.417, N150781.277

Process There is no process history associated with the 600-382 waste site.

Description:

Closure Info: Interim (8/20/2014): Remediation of the 600-382 waste site (and all subsites) was performed from October 29, 2013, through March 10, 2014. No anomalies were encountered during the remediation. Approximately 85 bank cubic meters (111 bank cubic yards) of excavated materials from the 600-382 waste site were removed and direct loaded for disposal at the Environmental Restoration Disposal Facility. The approximate depths of the excavations ranged from 0.3 meters (1.0 ft) to 1.0 meters (3.3 ft) below ground surface. No waste staging pile area or overburden soil stockpiles are associated with the 600-382 waste site. Walk around boundary surveys were conducted at each of the 600-382 subsites following their remediation.

This Site has the Following SubSites:

Code: 600-382:1

Names: 600-382:1; Segment 4 Oil Stain and Filter Area #3a

Code: 600-382:2

Names: 600-382:2; Segment 4 Oil Stain and Filter Area #3b

Code: 600-382:3

Names: 600-382:3; Segment 4 Oil Stain and Filter Area #3c

Code: 600-382:4

Names: 600-382:4; Segment 4 Oil Stain and Filter Area #3d

Code: 600-382:5

Names: 600-382:5; Segment 4 Oil Stain and Filter Area #3e

Code: 600-382:1

Classification: Accepted

Names: 600-382:1; Segment 4 Oil Stain and Filter Area #3a

Reclassification Interim Closed Out (8/20/2014)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. The parent site and all of the subsites were reclassified in a single document and a single Reclassification form (2014-026). This subsite consisted of two oil filters surrounded by soil devoid of vegetation.

Location: The site is located 1.0 km (0.6 miles) north of Route 2 North and 1.4 km (0.8 miles) west of H Avenue at coordinates E576315.892 N150679.753.

Process There is no process history associated with this subsite.

Description:

Closure Info: Interim (8/20/2014): Remediation of the 600-382 waste site (and all subsites) was performed from October 29, 2013, through March 10, 2014. No anomalies were encountered during the remediation. Approximately 85 bank cubic meters (111 bank cubic yards) of excavated materials from the 600-382 waste site were removed and direct loaded for disposal at the Environmental Restoration Disposal Facility. The approximate depths of the excavations ranged from 0.3 meters (1.0 ft) to 1.0 meters (3.3 ft) below ground surface. No waste staging pile area or overburden soil stockpiles are associated with the 600-382 waste site. Walk around boundary surveys were conducted at each of the 600-382 subsites following their remediation.

The SubSite is Part Of:

Code: 600-382
Names: 600-382; Segment 4 Oil Stains and Filter Area #3

Code: 600-382:2 **Classification:** Accepted
Names: 600-382:2; Segment 4 Oil Stain and Filter Area #3b **Reclassification:** Interim Closed Out (8/20/2014)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The subsite has been remediated and Interim Closed Out. The parent site and all of the subsites were reclassified in a single document and a single Reclassification form (2014-026). This subsite consisted of three oil filters and a small area of soil devoid of vegetation.

Location: The site is located 960 m (0.6 miles) north of Route 2 North and 1.4 km (0.8 miles) west of H Avenue at coordinates E576286.206 N150613.712.

Process Description: There is no process history associated with this subsite.

Closure Info: Interim (8/20/2014): Remediation of the 600-382 waste site (and all subsites) was performed from October 29, 2013, through March 10, 2014. No anomalies were encountered during the remediation. Approximately 85 bank cubic meters (111 bank cubic yards) of excavated materials from the 600-382 waste site were removed and direct loaded for disposal at the Environmental Restoration Disposal Facility. The approximate depths of the excavations ranged from 0.3 meters (1.0 ft) to 1.0 meters (3.3 ft) below ground surface. No waste staging pile area or overburden soil stockpiles are associated with the 600-382 waste site. Walk around boundary surveys were conducted at each of the 600-382 subsites following their remediation.

The SubSite is Part Of:

Code: 600-382
Names: 600-382; Segment 4 Oil Stains and Filter Area #3

Code: 600-382:3 **Classification:** Accepted
Names: 600-382:3; Segment 4 Oil Stain and Filter Area #3c **Reclassification:** Interim Closed Out (8/20/2014)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The subsite has been remediated and Interim Closed Out. The parent site and all of the subsites were reclassified in a single document and a single Reclassification form (2014-026). This subsite consisted of one oil filter surrounded by soil devoid of vegetation.

Location: The site is located 890 m (0.6 miles) north of Route 2 North and 1.7 km (1 mile) west of H Avenue at coordinates E575923.366 N150876.064.

Process Description: There is no process history associated with this subsite.

Closure Info: Interim (8/20/2014): Remediation of the 600-382 waste site (and all subsites) was performed from October 29, 2013, through March 10, 2014. No anomalies were encountered during the remediation. Approximately 85 bank cubic meters (111 bank cubic yards) of excavated materials from the 600-382 waste site were removed and direct loaded for disposal at the

Environmental Restoration Disposal Facility. The approximate depths of the excavations ranged from 0.3 meters (1.0 ft) to 1.0 meters (3.3 ft) below ground surface. No waste staging pile area or overburden soil stockpiles are associated with the 600-382 waste site. Walk around boundary surveys were conducted at each of the 600-382 subsites following their remediation.

The SubSite is Part Of:

Code: 600-382

Names: 600-382; Segment 4 Oil Stains and Filter Area #3

Code: 600-382:4

Classification: Accepted

Names: 600-382:4; Segment 4 Oil Stain and Filter Area #3d

Reclassification Interim Closed Out (8/20/2014)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. The parent site and all of the subsites were reclassified in a single document and a single Reclassification form (2014-026). This subsite consisted of a 3 square meter (32 square feet) area devoid of vegetation containing discarded oil filters.

Location: The site is located 2.1 km (1.3 miles) north of Route 2 North and 1.4 km (0.8 miles) west of H-area perimeter road at coordinates E576231.571 N151788.478.

Process There is no process history associated with this subsite.

Description:

Closure Info: Interim (8/20/2014): Remediation of the 600-382 waste site (and all subsites) was performed from October 29, 2013, through March 10, 2014. No anomalies were encountered during the remediation. Approximately 85 bank cubic meters (111 bank cubic yards) of excavated materials from the 600-382 waste site were removed and direct loaded for disposal at the Environmental Restoration Disposal Facility. The approximate depths of the excavations ranged from 0.3 meters (1.0 ft) to 1.0 meters (3.3 ft) below ground surface. No waste staging pile area or overburden soil stockpiles are associated with the 600-382 waste site. Walk around boundary surveys were conducted at each of the 600-382 subsites following their remediation.

The SubSite is Part Of:

Code: 600-382

Names: 600-382; Segment 4 Oil Stains and Filter Area #3

Code: 600-382:5

Classification: Accepted

Names: 600-382:5; Segment 4 Oil Stain and Filter Area #3e

Reclassification Interim Closed Out (8/20/2014)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. The parent site and all of the subsites were reclassified in a single document and a single Reclassification form (2014-026). This subsite consisted of three oil filters surrounded by soil devoid of vegetation.

Location: The site is located 376 m (0.2 miles) north of Route 2 North and 2.8 km (1.7 miles) west of H Avenue at coordinates E574850.417 N150781.277.

Process There is no process history associated with this subsite.
Description:

Closure Info: Interim (8/20/2014): Remediation of the 600-382 waste site (and all subsites) was performed from October 29, 2013, through March 10, 2014. No anomalies were encountered during the remediation. Approximately 85 bank cubic meters (111 bank cubic yards) of excavated materials from the 600-382 waste site were removed and direct loaded for disposal at the Environmental Restoration Disposal Facility. The approximate depths of the excavations ranged from 0.3 meters (1.0 ft) to 1.0 meters (3.3 ft) below ground surface. No waste staging pile area or overburden soil stockpiles are associated with the 600-382 waste site. Walk around boundary surveys were conducted at each of the 600-382 subsites following their remediation.

The SubSite is Part Of:

Code: 600-382

Names: 600-382; Segment 4 Oil Stains and Filter Area #3

Code: 600-383

Classification: Accepted

Names: 600-383; Segment 4 Battery Remnant Areas #2

Reclassification Interim Closed Out (7/8/2014)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The 600-383 waste site, including all of the subsites, was remediated and Interim Closed Out. All subsites were addressed in the same Remaining Sites Verification Package and Waste Site Reclassification Form (2014-023). The waste site consisted of ten locations that contained remnants of batteries.

The site was divided into ten subsites as follows:

- 600-383:1, Segment 4 Battery Remnant Area #2a; Consisted of a 4 meter (13 ft) diameter area of discarded dry cell battery remnants on bare ground.
- 600-383:2, Segment 4 Battery Remnant Area #2b; Consisted of multiple dry cell batteries in an approximate 3 meter (10 ft) diameter area of bare ground.
- 600-383:3, Segment 4 Battery Remnant Area #2c; Consisted of multiple dry cell batteries in an approximate 1 meter (3 ft) diameter area of bare ground.
- 600-383:4, Segment 4 Battery Remnant Area #2d; Consisted of a dry cell battery pack in an approximate 1 meter (3 ft) diameter area of bare ground.
- 600-383:5, Segment 4 Battery Remnant Area #2e; Consisted of two areas approximately 1 meter (3 ft) diameter each of discarded dry cell batteries. The areas are devoid of vegetation.
- 600-383:6, Segment 4 Battery Remnant Area #2f; Consisted of a 1 meter (3 ft) diameter area of multiple discarded dry cell batteries on bare ground.
- 600-383:7, Segment 4 Battery Remnant Area #2g; Consisted of wet cell car battery remnants located approximately 1 meter (3 ft) from a dirt road.
- 600-383:8, Segment 4 Battery Remnant Area #2h; Consisted of six dry cell battery remnants in an approximate 6 meter (20 ft) diameter area. No staining was visible.
- 600-383:9, Segment 4 Battery Remnant Area #2i; Consisted of six dry cell battery remnants in an approximate 6 meter (20 ft) diameter area. No staining was visible.
- 600-383:10, Segment 4 Battery Remnant Area #2j; Consisted of a 2 meter (7 ft) diameter area of debris from multiple dry cell batteries on bare ground.

Location: The subsites were located between the 100-D Area and the railroad tracks that lead to the 100-H Area.

600-382:1, E576315.892, N150679.753

600-382:2, E576286.206, N150613.712
 600-382:3, E575923.366, N150876.064
 600-382:4, E576231.571, N151788.478
 600-382:5, E574850.417, N150781.277

Process There is no process history associated with the 600-383 waste site.

Description:

Closure Info: Interim (7/8/2014): All subsites were addressed in the same Remaining Sites Verification Package and Waste Site Reclassification Form (2014-023).

The 600-383 waste site was recommended for remediation without confirmatory sampling based on the observed presence of battery debris. Waste characterization samples were collected from each of the 600-383 subsites prior to the start of remediation. Remediation of the 600-383 waste site was performed from September 25 through November 13, 2013. Approximately 55 bank cubic meters (72 bank cubic yards) of excavated materials from the 600-383 waste site were removed and direct loaded for disposal at the Environmental Restoration Disposal Facility. The approximate depths of the excavations range from less than 0.3 to 0.46 meters (1.0 to 1.5 ft) below ground surface.

This Site has the Following SubSites:

- Code:** 600-383:1
- Names:** 600-383:1; Segment 4 Battery Remnant Area #2a
- Code:** 600-383:2
- Names:** 600-383:2; Segment 4 Battery Remnant Area #2b
- Code:** 600-383:3
- Names:** 600-383:3; Segment 4 Battery Remnant Area #2c
- Code:** 600-383:4
- Names:** 600-383:4; Segment 4 Battery Remnant Area #2d
- Code:** 600-383:5
- Names:** 600-383:5; Segment 4 Battery Remnant Area #2e
- Code:** 600-383:6
- Names:** 600-383:6; Segment 4 Battery Remnant Area #2f
- Code:** 600-383:7
- Names:** 600-383:7; Segment 4 Battery Remnant Area #2g
- Code:** 600-383:8
- Names:** 600-383:8; Segment 4 Battery Remnant Area #2h
- Code:** 600-383:9
- Names:** 600-383:9; Segment 4 Battery Remnant Area #2i
- Code:** 600-383:10
- Names:** 600-383:10; Segment 4 Battery Remnant Area #2j

Code: 600-383:1	Classification: Accepted
Names: 600-383:1; Segment 4 Battery Remnant Area #2a	Reclassification Interim Closed Out (7/8/2014)
Type: Dumping Area	Start Date:
Status: Inactive	End Date:

Description: This subsite consists of a 4 meter (13 feet) diameter area of discarded batteries.

Location: The site is located 1.9 km (1.2 miles) north of Route 2 North and 1.2 kilometers (0.75 miles) west of H Avenue at coordinates E576455.35 N151417.875.

Process Description: There is no process history associated with this subsite.

Closure Info: Interim (7/8/2014): All subsites were addressed in the same Remaining Sites Verification Package and Waste Site Reclassification Form (2014-023).

The 600-383 waste site was recommended for remediation without confirmatory sampling based on the observed presence of battery debris. Waste characterization samples were collected from each of the 600-383 subsites prior to the start of remediation. Remediation of the 600-383 waste site was performed from September 25 through November 13, 2013. Approximately 55 bank cubic meters (72 bank cubic yards) of excavated materials from the 600-383 waste site were removed and direct loaded for disposal at the Environmental Restoration Disposal Facility. The approximate depths of the excavations range from less than 0.3 to 0.46 meters (1.0 to 1.5 ft) below ground surface.

The SubSite is Part Of:

Code: 600-383

Names: 600-383; Segment 4 Battery Remnant Areas #2

Code: 600-383:2

Classification: Accepted

Names: 600-383:2; Segment 4 Battery Remnant Area #2b

Reclassification: Interim Closed Out (7/8/2014)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: This subsite consists of twelve discarded dry cell batteries.

Location: The site is located 1.2 km (0.75 miles) north of Route 2 North and 2.4 km (1.5 miles) west of H Avenue at coordinates E575303.197 N151382.354.

Process Description: There is no process history associated with this subsite.

Closure Info: Interim (7/8/2014): All subsites were addressed in the same Remaining Sites Verification Package and Waste Site Reclassification Form (2014-023).

The 600-383 waste site was recommended for remediation without confirmatory sampling based on the observed presence of battery debris. Waste characterization samples were collected from each of the 600-383 subsites prior to the start of remediation. Remediation of the 600-383 waste site was performed from September 25 through November 13, 2013. Approximately 55 bank cubic meters (72 bank cubic yards) of excavated materials from the 600-383 waste site were removed and direct loaded for disposal at the Environmental Restoration Disposal Facility. The approximate depths of the excavations range from less than 0.3 to 0.46 meters (1.0 to 1.5 ft) below ground surface.

The SubSite is Part Of:

Code: 600-383

Names: 600-383; Segment 4 Battery Remnant Areas #2

Code: 600-383:3

Classification: Accepted

Names: 600-383:3; Segment 4 Battery Remnant Area #2c **Reclassification** Interim Closed Out (7/8/2014)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: This subsite consists of a twenty-two discarded dry cell batteries.

Location: The site is located 1.0 km (0.6 miles) north of Route 2 North and 1.5 km (0.9 miles) west of H Avenue at coordinates E576163.427 N150781.104.

Process There is no process history associated with this subsite.

Description:

Closure Info: Interim (7/8/2014): All subsites were addressed in the same Remaining Sites Verification Package and Waste Site Reclassification Form (2014-023).

The 600-383 waste site was recommended for remediation without confirmatory sampling based on the observed presence of battery debris. Waste characterization samples were collected from each of the 600-383 subsites prior to the start of remediation. Remediation of the 600-383 waste site was performed from September 25 through November 13, 2013. Approximately 55 bank cubic meters (72 bank cubic yards) of excavated materials from the 600-383 waste site were removed and direct loaded for disposal at the Environmental Restoration Disposal Facility. The approximate depths of the excavations range from less than 0.3 to 0.46 meters (1.0 to 1.5 ft) below ground surface.

The SubSite is Part Of:

Code: 600-383

Names: 600-383; Segment 4 Battery Remnant Areas #2

Code: 600-383:4

Classification: Accepted

Names: 600-383:4; Segment 4 Battery Remnant Area #2d **Reclassification** Interim Closed Out (7/8/2014)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: This subsite consists of a dry cell battery pack.

Location: The site is located 1.0 km (0.6 miles) north of Route 2 North and 1.6 km (1.0 miles) west of H Avenue at coordinates E576116.577 N150791.637.

Process There is no process history associated with this subsite.

Description:

Closure Info: Interim (7/8/2014): All subsites were addressed in the same Remaining Sites Verification Package and Waste Site Reclassification Form (2014-023).

The 600-383 waste site was recommended for remediation without confirmatory sampling based on the observed presence of battery debris. Waste characterization samples were collected from each of the 600-383 subsites prior to the start of remediation. Remediation of the 600-383 waste site was performed from September 25 through November 13, 2013. Approximately 55 bank cubic meters (72 bank cubic yards) of excavated materials from the 600-383 waste site were removed and direct loaded for disposal at the Environmental Restoration Disposal Facility. The approximate depths of the excavations range from less than 0.3 to 0.46 meters (1.0 to 1.5 ft) below ground surface.

The SubSite is Part Of:**Code:** 600-383**Names:** 600-383; Segment 4 Battery Remnant Areas #2**Code:** 600-383:5**Classification:** Accepted**Names:** 600-383:5; Segment 4 Battery Remnant Area #2e **Reclassification** Interim Closed Out (7/8/2014)**Type:** Dumping Area**Start Date:****Status:** Inactive**End Date:****Description:** This subsite consists of two areas of discarded dry cell batteries that are devoid of vegetation.**Location:** The site is located 2.0 km (1.2 miles) south of the Columbia River and 0.5 km (0.3 miles) east of the 100-D perimeter road at coordinates E575068.449 N152464.615.**Process** There is no process history associated with this subsite.**Description:****Closure Info:** Interim (7/8/2014): All subsites were addressed in the same Remaining Sites Verification Package and Waste Site Reclassification Form (2014-023).

The 600-383 waste site was recommended for remediation without confirmatory sampling based on the observed presence of battery debris. Waste characterization samples were collected from each of the 600-383 subsites prior to the start of remediation. Remediation of the 600-383 waste site was performed from September 25 through November 13, 2013.

Approximately 55 bank cubic meters (72 bank cubic yards) of excavated materials from the 600-383 waste site were removed and direct loaded for disposal at the Environmental Restoration Disposal Facility. The approximate depths of the excavations range from less than 0.3 to 0.46 meters (1.0 to 1.5 ft) below ground surface.

The SubSite is Part Of:**Code:** 600-383**Names:** 600-383; Segment 4 Battery Remnant Areas #2**Code:** 600-383:6**Classification:** Accepted**Names:** 600-383:6; Segment 4 Battery Remnant Area #2f **Reclassification** Interim Closed Out (7/8/2014)**Type:** Dumping Area**Start Date:****Status:** Inactive**End Date:****Description:** This subsite consists of a 1 meter (3 feet) diameter area of discarded dry cell batteries.**Location:** The site is located 2.4 km (1.5 miles) south of the Columbia River and 0.7 km (0.5 miles) east of the 100-D perimeter road at coordinates E575298.778 N152062.235.**Process** There is no process history associated with this subsite.**Description:****Closure Info:** Interim (7/8/2014): All subsites were addressed in the same Remaining Sites Verification Package and Waste Site Reclassification Form (2014-023).

The 600-383 waste site was recommended for remediation without confirmatory sampling based on the observed presence of battery debris. Waste characterization samples were collected from each of the 600-383 subsites prior to the start of remediation. Remediation of the

600-383 waste site was performed from September 25 through November 13, 2013. Approximately 55 bank cubic meters (72 bank cubic yards) of excavated materials from the 600-383 waste site were removed and direct loaded for disposal at the Environmental Restoration Disposal Facility. The approximate depths of the excavations range from less than 0.3 to 0.46 meters (1.0 to 1.5 ft) below ground surface.

The SubSite is Part Of:

Code: 600-383

Names: 600-383; Segment 4 Battery Remnant Areas #2

Code: 600-383:7

Classification: Accepted

Names: 600-383:7; Segment 4 Battery Remnant Area #2g **Reclassification** Interim Closed Out (7/8/2014)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: This subsite consists of a wet cell car battery.

Location: The site is located 1.9 km (1.2 miles) south of the Columbia River and 1.6 km (1.0 miles) west of the H-Area perimeter road at coordinates E575619.302 N152555.295.

Process Description: There is no process history associated with this subsite.

Closure Info: Interim (7/8/2014): All subsites were addressed in the same Remaining Sites Verification Package and Waste Site Reclassification Form (2014-023).

The 600-383 waste site was recommended for remediation without confirmatory sampling based on the observed presence of battery debris. Waste characterization samples were collected from each of the 600-383 subsites prior to the start of remediation. Remediation of the 600-383 waste site was performed from September 25 through November 13, 2013. Approximately 55 bank cubic meters (72 bank cubic yards) of excavated materials from the 600-383 waste site were removed and direct loaded for disposal at the Environmental Restoration Disposal Facility. The approximate depths of the excavations range from less than 0.3 to 0.46 meters (1.0 to 1.5 ft) below ground surface.

The SubSite is Part Of:

Code: 600-383

Names: 600-383; Segment 4 Battery Remnant Areas #2

Code: 600-383:8

Classification: Accepted

Names: 600-383:8; Segment 4 Battery Remnant Area #2h **Reclassification** Interim Closed Out (7/8/2014)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: This subsite consists of six dry cell batteries.

Location: The site is located 1.0 km (0.6 miles) south of the Columbia River and 0.9 km (0.5 miles) west of the H-Area perimeter road at coordinates E576348.312 N153213.341.

Process Description: There is no process history associated with this subsite.

Description:

Closure Info: Interim (7/8/2014): All subsites were addressed in the same Remaining Sites Verification Package and Waste Site Reclassification Form (2014-023).

The 600-383 waste site was recommended for remediation without confirmatory sampling based on the observed presence of battery debris. Waste characterization samples were collected from each of the 600-383 subsites prior to the start of remediation. Remediation of the 600-383 waste site was performed from September 25 through November 13, 2013. Approximately 55 bank cubic meters (72 bank cubic yards) of excavated materials from the 600-383 waste site were removed and direct loaded for disposal at the Environmental Restoration Disposal Facility. The approximate depths of the excavations range from less than 0.3 to 0.46 meters (1.0 to 1.5 ft) below ground surface.

The SubSite is Part Of:

Code: 600-383

Names: 600-383; Segment 4 Battery Remnant Areas #2

Code: 600-383:9

Classification: Accepted

Names: 600-383:9; Segment 4 Battery Remnant Area #2i **Reclassification** Interim Closed Out (7/8/2014)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: This subsite consists of a 5 meter (16 feet) diameter area of discarded dry cell batteries.

Location: The site is located 1.1 km (0.7 miles) south of the Columbia River and 1.6 km (1.0 miles) west of the H-Area perimeter road at coordinates E575624.336 N153303.821.

Process There is no process history associated with this subsite.

Description:

Closure Info: Interim (7/8/2014): All subsites were addressed in the same Remaining Sites Verification Package and Waste Site Reclassification Form (2014-023).

The 600-383 waste site was recommended for remediation without confirmatory sampling based on the observed presence of battery debris. Waste characterization samples were collected from each of the 600-383 subsites prior to the start of remediation. Remediation of the 600-383 waste site was performed from September 25 through November 13, 2013. Approximately 55 bank cubic meters (72 bank cubic yards) of excavated materials from the 600-383 waste site were removed and direct loaded for disposal at the Environmental Restoration Disposal Facility. The approximate depths of the excavations range from less than 0.3 to 0.46 meters (1.0 to 1.5 ft) below ground surface.

The SubSite is Part Of:

Code: 600-383

Names: 600-383; Segment 4 Battery Remnant Areas #2

Code: 600-383:10

Classification: Accepted

Names: 600-383:10; Segment 4 Battery Remnant Area #2j **Reclassification** Interim Closed Out (7/8/2014)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: This subsite consists of a 2 meters (7 feet) diameter area of discarded batteries.

Location: The site is located 1.5 km (0.9 miles) south of the Columbia River 2.0 km (1.2 miles) west of H Avenue at coordinates E575222.383 N152913.096.

Process Description: There is no process history associated with this subsite.

Closure Info: Interim (7/8/2014): All subsites were addressed in the same Remaining Sites Verification Package and Waste Site Reclassification Form (2014-023).

The 600-383 waste site was recommended for remediation without confirmatory sampling based on the observed presence of battery debris. Waste characterization samples were collected from each of the 600-383 subsites prior to the start of remediation. Remediation of the 600-383 waste site was performed from September 25 through November 13, 2013. Approximately 55 bank cubic meters (72 bank cubic yards) of excavated materials from the 600-383 waste site were removed and direct loaded for disposal at the Environmental Restoration Disposal Facility. The approximate depths of the excavations range from less than 0.3 to 0.46 meters (1.0 to 1.5 ft) below ground surface.

The SubSite is Part Of:

Code: 600-383

Names: 600-383; Segment 4 Battery Remnant Areas #2

Code: 600-384

Classification: Accepted

Names: 600-384; Segment 4 Stained Soil Area #3

Reclassification: Interim Closed Out (8/13/2014)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The waste site was a grouping of five stained soil areas of either yellow powder, tar, or crusted soils. The site had been divided into five subsites. All five subsites have been remediated and Interim Closed Out on the same reclassification form (2014-008). The parent site is also considered Interim Closed Out.

600-384:1, Segment 4 Stained Soil Area #3a
 600-384:2, Segment 4 Stained Soil Area #3b
 600-384:3, Segment 4 Stained Soil Area #3c
 600-384:4, Segment 4 Stained Soil Area #3d
 600-384:5, Segment 4 Stained Soil Area #3e

Location: The subsites were located north of the railroad tracks in Segment 4 between the 100-D/DR and 100-H Areas.

600-384:1, E575505.736 N151010.616
 600-384:2, E575481.948 N151135.371
 600-384:3, E575312.274 N152256.576
 600-384:4, E575508.771 N152209.015
 600-384:5, E575684.069 N151248.983

Process Description: There is no process history associated with the 600-384 waste site.

Closure Info: Interim (8/13/2014): Remediation of the 600-384:1, 600-384:2 and 600-384:5 subsites was performed on November 4 and 5, 2013. Remediation of the 600-384:3 and 600-384:4 subsites was performed on November 25, 2013. Remediation of the total 600-384 waste site resulted in approximately 92 bank cubic meters (BCM) (120 bank cubic yards [BCY]) of soil and debris

being removed for disposal at the Environmental Restoration Disposal Facility (ERDF). Additional remediation was performed at the 600-384:3, 600-384:4, and 600-384:5 subsite locations on March 3 through 5, 2014. Additional soil was removed across the entire base of each subsite excavation. Further remediation performed at these three subsites resulted in an additional soil removal of 233 BCM (305 BCY). The final remediation resulted in a total of approximately 325 BCM (425 BCY) of contaminated material being removed and disposed at ERDF. All material removed from the waste sites was direct loaded for disposal at ERDF, and no soil staging pile areas or overburden areas were utilized.

The dimensions of the remediation areas are:

600-384:1 = 7 by 7 meters, 1.5 meters deep
 600-384:2 = 16 by 9 meters, 1.2 meters deep
 600-384:3 = 14 by 8 meters, 1 meter deep
 600-384:4 = 14 by 13 meters, 1.3 meters deep
 600-384:5 = 10 by 7 meters, 0.9 meter deep

This Site has the Following SubSites:

Code: 600-384:1
Names: 600-384:1; Segment 4 Stained Soil Area #3a
Code: 600-384:2
Names: 600-384:2; Segment 4 Stained Soil Area #3b
Code: 600-384:3
Names: 600-384:3; Segment 4 Stained Soil Area #3c
Code: 600-384:4
Names: 600-384:4; Segment 4 Stained Soil Area #3d
Code: 600-384:5
Names: 600-384:5; Segment 4 Stained Soil Area #3e

Code: 600-384:1	Classification: Accepted
Names: 600-384:1; Segment 4 Stained Soil Area #3a	Reclassification Interim Closed Out (8/13/2014)
Type: Unplanned Release	Start Date:
Status: Inactive	End Date:

Description: The subsite has been remediated and Interim Closed Out. It consisted of a 4 meter (13 ft) diameter area of yellow and white powder.

Location: The site was located 0.86 km (0.5 miles) north of Route 2 N and 2.2 km (1.4 miles) west of H Avenue at coordinates E575505.736 N151010.616.

Process Description: There is no process history associated with this subsite.

Closure Info: Interim (8/13/2014): Remediation of the 600-384:1, 600-384:2 and 600-384:5 subsites was performed on November 4 and 5, 2013. Remediation of the 600-384:3 and 600-384:4 subsites was performed on November 25, 2013. Remediation of the total 600-384 waste site resulted in approximately 92 bank cubic meters (BCM) (120 bank cubic yards [BCY]) of soil and debris being removed for disposal at the Environmental Restoration Disposal Facility (ERDF). Additional remediation was performed at the 600-384:3, 600-384:4, and 600-384:5 subsite locations on March 3 through 5, 2014. Additional soil was removed across the entire base of each subsite excavation. Further remediation performed at these three subsites resulted in an

additional soil removal of 233 BCM (305 BCY). The final remediation resulted in a total of approximately 325 BCM (425 BCY) of contaminated material being removed and disposed at ERDF. All material removed from the waste sites was direct loaded for disposal at ERDF, and no soil staging pile areas or overburden areas were utilized.

The dimensions of the remediation areas are:

600-384:1 = 7 by 7 meters, 1.5 meters deep
 600-384:2 = 16 by 9 meters, 1.2 meters deep
 600-384:3 = 14 by 8 meters, 1 meter deep
 600-384:4 = 14 by 13 meters, 1.3 meters deep
 600-384:5 = 10 by 7 meters, 0.9 meter deep

The SubSite is Part Of:

Code: 600-384

Names: 600-384; Segment 4 Stained Soil Area #3

Code: 600-384:2

Classification: Accepted

Names: 600-384:2; Segment 4 Stained Soil Area #3b

Reclassification: Interim Closed Out (8/13/2014)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. It consisted of a 15 meter (49 ft) diameter area of yellow and white powder.

Location: The site was located 1.0 km (0.6 miles) north of Route 2 N and 2.2 km (1.4 miles) west of H Avenue at coordinates E575481.948 N151135.371.

Process Description: There is no process history associated with this subsite.

Closure Info: Interim (8/13/2014): Remediation of the 600-384:1, 600-384:2 and 600-384:5 subsites was performed on November 4 and 5, 2013. Remediation of the 600-384:3 and 600-384:4 subsites was performed on November 25, 2013. Remediation of the total 600-384 waste site resulted in approximately 92 bank cubic meters (BCM) (120 bank cubic yards [BCY]) of soil and debris being removed for disposal at the Environmental Restoration Disposal Facility (ERDF). Additional remediation was performed at the 600-384:3, 600-384:4, and 600-384:5 subsite locations on March 3 through 5, 2014. Additional soil was removed across the entire base of each subsite excavation. Further remediation performed at these three subsites resulted in an additional soil removal of 233 BCM (305 BCY). The final remediation resulted in a total of approximately 325 BCM (425 BCY) of contaminated material being removed and disposed at ERDF. All material removed from the waste sites was direct loaded for disposal at ERDF, and no soil staging pile areas or overburden areas were utilized.

The dimensions of the remediation areas are:

600-384:1 = 7 by 7 meters, 1.5 meters deep
 600-384:2 = 16 by 9 meters, 1.2 meters deep
 600-384:3 = 14 by 8 meters, 1 meter deep
 600-384:4 = 14 by 13 meters, 1.3 meters deep
 600-384:5 = 10 by 7 meters, 0.9 meter deep

The SubSite is Part Of:

Code: 600-384
Names: 600-384; Segment 4 Stained Soil Area #3

Code: 600-384:3 **Classification:** Accepted
Names: 600-384:3; Segment 4 Stained Soil Area #3c **Reclassification** Interim Closed Out (8/13/2014)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The subsite has been remediated and Interim Closed Out. It consisted of two, adjacent locations that had stained soil.

Location: The site was located 2.0 km (1.2 miles) north of Route 2 N and 1.9 km (1.2 miles) west of H Avenue at coordinates E575312.274 N152256.576.

Process Description: There is no process history associated with this subsite.

Closure Info: Interim (8/13/2014): Remediation of the 600-384:1, 600-384:2 and 600-384:5 subsites was performed on November 4 and 5, 2013. Remediation of the 600-384:3 and 600-384:4 subsites was performed on November 25, 2013. Remediation of the total 600-384 waste site resulted in approximately 92 bank cubic meters (BCM) (120 bank cubic yards [BCY]) of soil and debris being removed for disposal at the Environmental Restoration Disposal Facility (ERDF). Additional remediation was performed at the 600-384:3, 600-384:4, and 600-384:5 subsite locations on March 3 through 5, 2014. Additional soil was removed across the entire base of each subsite excavation. Further remediation performed at these three subsites resulted in an additional soil removal of 233 BCM (305 BCY). The final remediation resulted in a total of approximately 325 BCM (425 BCY) of contaminated material being removed and disposed at ERDF. All material removed from the waste sites was direct loaded for disposal at ERDF, and no soil staging pile areas or overburden areas were utilized.

The dimensions of the remediation areas are:

600-384:1 = 7 by 7 meters, 1.5 meters deep
 600-384:2 = 16 by 9 meters, 1.2 meters deep
 600-384:3 = 14 by 8 meters, 1 meter deep
 600-384:4 = 14 by 13 meters, 1.3 meters deep
 600-384:5 = 10 by 7 meters, 0.9 meter deep

The SubSite is Part Of:

Code: 600-384
Names: 600-384; Segment 4 Stained Soil Area #3

Code: 600-384:4 **Classification:** Accepted
Names: 600-384:4; Segment 4 Stained Soil Area #3d **Reclassification** Interim Closed Out (8/13/2014)
Type: Unplanned Release **Start Date:**
Status: Inactive **End Date:**

Description: The subsite has been remediated and Interim Closed Out. It consisted of a 4 meter (13 ft) diameter area of stained soil.

Location: The site was located 2.1 km (1.3 miles) north of Route 2 N and 1.7 km (1.1 miles) west of the H-Area perimeter road at coordinates E575508.771 N152209.015.

Process There is no process history associated with this subsite.

Description:

Closure Info: Interim (8/13/2014): Remediation of the 600-384:1, 600-384:2 and 600-384:5 subsites was performed on November 4 and 5, 2013. Remediation of the 600-384:3 and 600-384:4 subsites was performed on November 25, 2013. Remediation of the total 600-384 waste site resulted in approximately 92 bank cubic meters (BCM) (120 bank cubic yards [BCY]) of soil and debris being removed for disposal at the Environmental Restoration Disposal Facility (ERDF). Additional remediation was performed at the 600-384:3, 600-384:4, and 600-384:5 subsite locations on March 3 through 5, 2014. Additional soil was removed across the entire base of each subsite excavation. Further remediation performed at these three subsites resulted in an additional soil removal of 233 BCM (305 BCY). The final remediation resulted in a total of approximately 325 BCM (425 BCY) of contaminated material being removed and disposed at ERDF. All material removed from the waste sites was direct loaded for disposal at ERDF, and no soil staging pile areas or overburden areas were utilized.

The dimensions of the remediation areas are:

600-384:1 = 7 by 7 meters, 1.5 meters deep

600-384:2 = 16 by 9 meters, 1.2 meters deep

600-384:3 = 14 by 8 meters, 1 meter deep

600-384:4 = 14 by 13 meters, 1.3 meters deep

600-384:5 = 10 by 7 meters, 0.9 meter deep

The SubSite is Part Of:

Code: 600-384

Names: 600-384; Segment 4 Stained Soil Area #3

Code: 600-384:5

Classification: Accepted

Names: 600-384:5; Segment 4 Stained Soil Area #3e

Reclassification Interim Closed Out (8/13/2014)

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The subsite has been remediated and Interim Closed Out. It consisted of a 1.5 meter (5 ft) diameter area of stained soil.

Location: The site was located 1.1 km (0.7 miles) north of Route 2 N and 2 km (1.2 miles) west of H Avenue at coordinates E575684.069 N151248.983.

Process There is no process history associated with this subsite.

Description:

Closure Info: Interim (8/13/2014): Remediation of the 600-384:1, 600-384:2 and 600-384:5 subsites was performed on November 4 and 5, 2013. Remediation of the 600-384:3 and 600-384:4 subsites was performed on November 25, 2013. Remediation of the total 600-384 waste site resulted in approximately 92 bank cubic meters (BCM) (120 bank cubic yards [BCY]) of soil and debris being removed for disposal at the Environmental Restoration Disposal Facility (ERDF). Additional remediation was performed at the 600-384:3, 600-384:4, and 600-384:5 subsite locations on March 3 through 5, 2014. Additional soil was removed across the entire base of each subsite excavation. Further remediation performed at these three subsites resulted in an additional soil removal of 233 BCM (305 BCY). The final remediation resulted in a total of approximately 325 BCM (425 BCY) of contaminated material being removed and disposed at ERDF. All material removed from the waste sites was direct loaded for disposal at ERDF, and

no soil staging pile areas or overburden areas were utilized.

The dimensions of the remediation areas are:

600-384:1 = 7 by 7 meters, 1.5 meters deep

600-384:2 = 16 by 9 meters, 1.2 meters deep

600-384:3 = 14 by 8 meters, 1 meter deep

600-384:4 = 14 by 13 meters, 1.3 meters deep

600-384:5 = 10 by 7 meters, 0.9 meter deep

The SubSite is Part Of:

Code: 600-384

Names: 600-384; Segment 4 Stained Soil Area #3

Code: 600-385

Classification: Accepted

Names: 600-385; Segment 4 Transite, Concrete, and Metal Debris Area

Reclassification: None

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The site consists of a 5334 square meters (1.3 acres) area with scattered transite, concrete, and metal debris.

Location: This site is located approximately 1.2 kilometers northwest of the northwest corner 100H perimeter road along the Columbia River. E576211.402 N154182.005

Process Description: There is no process history associated with the 600-385 waste site.

Code: 600-386

Classification: Accepted

Names: 600-386; Segment 5 Battery Remnant Area #1

Reclassification: Interim Closed Out (8/23/2012)

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The waste site has been remediated and Interim Closed Out. It consisted of wet cell battery remnants partially buried and some potential related staining visible.

Location: The site was located approximately 835 meters NNW of the 310 building (TEDF) and 13 meters west of Route 4S. The coordinates for the battery site are E593533.2002, N118226.1146, northwest of the 310 (TEDF) building.

Closure Info: Interim (8/23/2012): Remedial action at the 600-386 waste site was conducted on May 30, 2012. Approximately 0.5 bank cubic meters (0.6 bank cubic yards) of soil and debris (battery remnant) was removed and disposed at the Environmental Restoration Disposal Facility. The removal of the battery and soil resulted in a hole approximately 0.7 meters (2.3 ft) deep. There are no overburden soil stockpiles or waste staging pile areas associated with this waste site. No anomalies were encountered during remediation activities.

Code: 600-387

Classification: Accepted

Names: 600-387; 212-R Railspur Legacy Contamination

Reclassification: None

Type: Unplanned Release

Start Date:

Status: Inactive

End Date:

Description: The waste site is two areas of superficial and subsurface radiological contaminated areas identified following the removal of 16 Railcars that had been located at 200 North Area. Contamination was found on the gravel bed under the railroad ties and was unrelated to the actual Decommissioning (D4) Project Activities of the removal of the 16 railcars.

Location: One radiologically contaminated area is on the north side of Deer St. and the other is on the south side of Deer St (aka Railroad Street).

Code: 600-388

Classification: Accepted

Names: 600-388; Non-Operational Property Evaluation
Zone 4, Debris Field South of Army Loop Road

Reclassification: None

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The waste site is surface debris found during the Zone 4 Non Operational Area walkdowns. There is evidence of mechanical ground disturbance, stressed vegetation and indications of potentially buried material.

Location: The area is located south of Army Loop Road, near Beloit Ave. and the Rattlesnake Gate.

Code: 600-389

Classification: Accepted

Names: 600-389; Non-Operational Property Evaluation
Zone 4, Surface Debris near 600-49

Reclassification: None

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The waste site is an area of surface debris identified during the Zone 4 Non-Operational Area walkdowns. The debris includes batteries, paint, metal objects and an oil filter.

Location: The waste site is located south of Army Loop road near waste site 600-49.

Code: 600-390

Classification: Accepted

Names: 600-390; Non-Operational Property Evaluation
Zone 3, Area of Dried Surface Material

Reclassification: None

Type: Depression/Pit (nonspecific)

Start Date:

Status: Inactive

End Date:

Description: During the Non-Operational Area site walkdown of Zone 3, a surface deposit of dried material was identified. The deposit resembles dried resin.

Location: The area is located on the north side of Route 4 South, west of Route 2 South. It is north of the Old Central Landfill waste site.

Code: 600-391

Classification: Accepted

Names: 600-391; Dumping Area Southeast of H-40 Gun Site **Reclassification** None

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: During the Zone 8 ground-truth interpretation of LIDAR data, an area of potential contamination was identified. The Non-Operational Property Evaluation walkdown found a significant mechanically disturbed area containing partially buried debris.

Location: The area is located south east of the H-40 Gun Site, south of Route 4 South.

Related Sites/ Structures: The debris area is associated with WIDS site 600-228.

Code: 600-392

Classification: Accepted

Names: 600-392; Debris and Radiological Signs West of 212-N

Reclassification None

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The waste site is a group of discarded rusty cans, barrels and old metal signs. Some of the signs have words that indicate they were related to safety and radiological control.

Location: The dumping area is located west of the demolished 212-N facility. The center point coordinates are N140230, E569763.

Code: 600-393

Classification: Accepted

Names: 600-393; Potential Battery Components Debris Area

Reclassification None

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The waste site is a debris area that contains potential battery components. The discarded material resembles battery pads. The area measures approximately 20 by 20 feet.

Location: The material is located north of Horn Rapids Road, east of the Hammer facility at coordinates E591582 N114082.

Code: 600-394

Classification: Accepted

Names: 600-394; Debris and Glass Jars near OCSA

Reclassification None

Type: Dumping Area

Start Date:

Status: Inactive

End Date:

Description: The waste site is an area of debris that includes degrading battery components and unbroken glass jars containing an unknown substance.

Location: The waste site is located south of Rt. 11A, near the northern boundary of the OCSA waste site at coordinates E570316.8 N138606.62.

Code: 600-395 **Classification:** Accepted
Names: 600-395; Bomb Fragments and DDT Canisters **Reclassification:** None
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is a few, crushed canisters with printed labels indicating they contained 20% DDT. The canisters are approximately fifteen feet from a visible crater. Multiple bomb fragments are visible on the surface. The bomb fragments are believed to be "dummy bombs" used for target practice. No distressed vegetation was noted.

Location: The debris is located in the Hanford Patrol Training facility, west of 300 Area. The debris is located at coordinates N115619.6/E590374.7.

Code: 600-397 **Classification:** Discovery
Names: 600-397; Transite Asbestos East of Vernita Bridge **Reclassification:** None
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is a deteriorating concrete slab with pieces of transite siding on the ground around the slab.

Location: The site is approximately 295 meters (973 ft) east of the Vernita Bridge by the old Vernita Ferry Landing Road. The site is at Washington State Plan (WSP) coordinates E559145 N145628 (Long: -119.72743; Lat: 46.64092).

Code: 600-398 **Classification:** Accepted
Names: 600-398; Debris South of Waste Treatment Plant **Reclassification:** None
Type: Dumping Area **Start Date:**
Status: Inactive **End Date:**

Description: The waste site is an area of scattered debris that includes batteries, bottles and old electronic vacuum tubes. There is evidence of burning. Some of the battery casings appear to have been burned, exposing the cores.

Location: The debris area is located south of the Waste Treatment Plant and north of Route 4S. The center coordinates are Washington State Plate (WSP) N134970 E576735.

Code: 600-400 **Classification:** Accepted
Names: 600-400; Debris near Pit 14b **Reclassification:** None
Type: Dumping Area **Start Date:**
Status: Unknown **End Date:**

Description: The waste site is mostly old lumber debris with some white plaster-like material present. The debris covers an area of approximately 80 square feet.

Location: The debris is on the southwestern edge of Pit 14B, north of Route 11A and north of 200 East

Area. The pit is centered at N138800/E573768.

Code: 600-401-PL **Classification:** Discovery

Names: 600-401-PL; ERDF Leachate Pipeline **Reclassification:** None

Type: Process Sewer **Start Date:**

Status: Unknown **End Date:**

Description: The waste site is an underground pipeline. It is constructed of six inch diameter polyvinyl chloride (PVC) pipe.

Location: The pipeline extends from the 6618C Pump House, inside the ERDF facility fence, to the UP1-5 pit located inside 200 West Area near the corner of Beloit Ave. and 16th Street.

Process Description: The pipeline carries Environmental Restoration Disposal Facility (ERDF) leachate and ties into the LERF/ETF pipeline (600-399-PL) to be stored in the LERF basins. The LERF basins are located in 200 East Area.

Code: 600-402 **Classification:** Accepted

Names: 600-402; Light Ballasts Dump Site **Reclassification:** None

Type: Dumping Area **Start Date:**

Status: Unknown **End Date:**

Description: The waste site is an area of broken fluorescent bulbs scattered between sagebrush. The area was discovered by Hanford Patrol as they were driving the perimeter road. The broken glass was reflecting sunlight. The area reported to the MSA 600 Area Landlord.

Location: The waste site is located south of 100 B Area at coordinates N143489/E565288. It is south of Milepost 10 on Route 1.

Code: 600-403 **Classification:** Accepted

Names: 600-403; Thorium Contamination Found Near 618-13 **Reclassification:** None

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:**

Description: The site is a posted radiation zone that measures approximately 15 feet by 15 feet.

Location: The site is located just west of Rt 4 South, adjacent to the road that loops around the 618-13 waste site at coordinates N116259/E592843 (N46 22.376/W 119 17.589).

Code: 1100-19 **Classification:** Accepted

Names: 1100-19; Tar Flow and Stained Sands Areas **Reclassification:** Deleted From NPL (9/30/1996)

Type: Unplanned Release **Start Date:**

Status: Inactive **End Date:** 1/1/1995

Description: This site has been remediated based on the 100 Area Record of Decision. Prior to remediation,

the Tar Flow site contained soft, tar like material on the surface. The material appeared to have flowed approximately 45.75 meters (150 feet) to the northeast into a drainage ditch. The Stained Sand Area was located on the east slope of a sand dune. The area had vegetation and the sand appeared to be stained. After remediation, both sites were regraded to a smooth, uniform surface.

Location: The Tar Flow and Stained Sand sites were located northwest of the 1171 building. The Tar Flow area was located 320 meters (1,050 feet) north of the northwest corner of the 1171 building. The Stained Sand site was located approximately 271 meters (888 feet) north of the northwest corner of the 1171 building.

Waste Type: Soil

Waste Description: The waste consisted of petroleum contaminated soil.

Closure Info: Final: The contaminated soil was removed by the US Army Corp of Engineers on June 26, 1995. 1,600 cubic yards of contaminated soil was excavated and stockpiled. Confirmatory samples indicated the remediation had met the clean-up levels established in the Record of Decision. The contaminates soil was disposed of at the Columbia Ridge Disposal Facility in September 1995.

(The remediation occurred prior to the development of the TPA-MP-14 process)

Code: UPR-200-E-18 **Classification:** Accepted

Names: UPR-200-E-18; Contamination Release at the 216-A-8 Sampler Pit; UN-200-E-18 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1959

Status: Inactive **End Date:**

Description: The sampler pit is a concrete structure with three valves, two vent stacks and one curved bonnet extending from the structure. The structure is surrounded with post and chain with Underground Radioactive Material and Contamination Area signs. The area around the structure is gravel and asphalt.

Location: The release site is approximately 30 meters (100 feet) east of the 241-A-271 Building, at the 216-A-8 proportional sample pit. It is east of 241-A Tank Farm and west of Canton Ave.

Release Description: Contaminated moisture dripping from a vent pipe bonnet at the 216-A-8 Proportional Sample Pit contaminated the ground around the cement pad.

Related Sites/ Structures: The release is associated with the 216-A-8 Proportional Sampler Pit (sitecode 200-E-285).

Waste Type: Process Effluent

Waste Description: Low-level fission products dripped onto the ground from the vent pipe bonnet.

Code: UPR-200-E-79 **Classification:** Accepted

Names: UPR-200-E-79; 200-E-264-PL Line Break; 242-B to 207-B Line Break; UN-200-E-79; UN-216-E-7 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1953

Status: Inactive**End Date:****Description:** The area where the release occurred is delineated by light duty posts and chain measuring approximately 7.6 meters (25 feet) wide and 61 meters (200 feet) long. It is posted with Underground Radioactive Material signs.**Location:** The site is located between the 242-B Evaporator and the 207-B Retention Basin, south of 241-B Tank Farm.**Release Description:** In June 1953, five leaks were discovered in the waste line that runs from 242-B to 207-B. Contamination levels up to 2,500 counts per minute were measured at the points of emission of water from the ground.**Related Sites/ Structures:** The site is associated with the 242-B Evaporator and the 207-B basin. The release occurred in the pipeline assigned sitecode 200-E-264-PL.**Process Description:** The release consisted of a 10 centimeter (4 inch) diameter, cast iron underground pipeline that was found to be leaking in 1953.**Waste Type:** Process Effluent**Waste Description:** The release consisted of approximately of 10 curies Mixed Fission Products (MFP) from the pipeline.**Code:** UPR-200-E-99**Classification:** Accepted**Names:** UPR-200-E-99; Contamination Adjacent to 244-CR Vault; UN-200-E-99; UN-216-E-27**Reclassification:** None**Type:** Unplanned Release**Start Date:** 1/1/1980**Status:** Inactive**End Date:** 1/1/1980**Description:** The previously posted Surface Contamination Area was released from radiation zone status in March 1981. A WIDS single sign had been placed at the approximate center location of the release. This sign was removed in 2010 when support trailers were placed in the area. Other areas with radiological postings are currently visible in this area.**Location:** The release was a posted Surface Contamination Area located south of 7th Street, directly south of the 244-CR Vault.**Release Description:** The ground surface surrounding the 244-CR Vault became contaminated during the numerous piping changes and activities associated with the vault.**Related Sites/ Structures:** UPR-200-E-99 is associated with the 244-CR Vault and the 241-C Tank Farm.**Process Description:** The area south of 7th Street and west of Buffalo Ave. has had numerous areas of radiological postings over the years due to contamination migration from the 241-C Tank Farm and the 244-A Lift Station.**Waste Type:** Soil**Waste Description:** The release was associated with the migration of contaminated particulates from the 244-CR Vault onto the surrounding ground surface. The 244-CR Vault was used in the transfer of process waste between facilities.**Code:** UPR-200-E-100**Classification:** Accepted**Names:** UPR-200-E-100; Radioactive Contamination**Reclassification:** None

Near 244-A Lift Station; UN-200-E-100; UN-216-E-100; UN-216-E-29

Type: Unplanned Release **Start Date:** 1/1/1985
Status: Inactive **End Date:**

Description: Various radiological postings exist in this vicinity that are associated with the 244-A Lift Station and 241-C Tank Farm contamination migration. A WIDS sign has been placed at the approximate location of the release. Routine radiological surveys of the 244-A Lift Station Area have changed the size and the shape of the posted areas as new contamination specks are identified and remediation attempts occur.

Location: UPR-200-E-100 consisted of radioactive rodent feces and contamination specks located south Seventh Street and west of Buffalo Street, adjacent to the 244-A Lift Station. Due to rodent movement and some contamination migration from wind, the size and the shape of the contaminated area was redefined several times.

Release Description: The release area was determined to be due to windblown particulates and biological transport (rodent feces) from the tank farms and the 244-A Lift Station. Another source of the contamination may be an underground pipeline leak near the 244-A lift station. A waste site number (UN-216-E-29) was assigned to this area on August 18, 1985.

Related Sites/Structures: UPR-200-E-100 is associated with the 244-A Lift Station, the 241-C Tank Farm, UPR-200-E-143, UPR-200-E-56 and the 216-A-40 Retention Basin.

Waste Type: Animal Waste

Waste Description: The contamination was due to windblown particulates and biological transport (rodent feces) from the 200 East Area tank farms and the 244-A Lift Station.

Code: UPR-200-W-20 **Classification:** Accepted

Names: UPR-200-W-20; Spread of Contamination from a Diversion Box; UN-200-W-20 **Reclassification:** None

Type: Unplanned Release **Start Date:** 1/1/1953

Status: Inactive **End Date:**

Description: There is a discrepancy in the reference documentation of where the release occurred. The 240-S-151 Diversion Box is located north of the 202-S Building (REDOX). The 241-S-151 Diversion Box is located in the southeast portion of 241-S Tank Farm. The identification number for the diversion box associated with the event is different in some documents.

Location: Due to discrepancies in reference documentation, it is not possible to be certain where this release occurred.

Release Description: In January and February 1953 work being done inside a diversion box resulted in extensive spread of contamination to the ground. An area of about 93 square meters (1000 square feet) around the diversion box was covered with six inches of clean gravel. This area was roped off and posted with radiation zone signs in 1953.

Related Sites/Structures: May be a Duplicate entry - see UPR-200-W-82.

Process Description: The 241-S-151 Diversion Box was used to redirect waste solutions from processing and decontamination operations. Waste quantities were variable depending on the specific plant operations. Leak detection and air monitoring are performed continuously with the 241-S Tank Farm. The unit interconnects the 240-S-151, 241-SX-151, and the 241-S Tank Farm.

Waste Type: Process Effluent

Waste Description: Specks from the open diversion box caused an area around the diversion box to be contaminated.